

Facility Condition Assessment Summary Report

This report provides a summary of the Facility Condition Index (FCI) value of a school facility and select major building systems. The FCI calculation represents the cost of needed repairs divided by the replacement value. The FCI is a numerical value of condition and helps to identify the need for renewal or replacement of specific parts of the facility. The FCI is particularly useful when comparing similar facilities within the same portfolio.

Barton School

Governance	DISTRICT	Report Type	Elementary
Address	4600 Rosehill St. Philadelphia, Pa 19120	Enrollment	752
Phone/Fax	215-456-3007 / 215-456-5578	Grade Range	'00-02'
Website	Www.Philasd.Org/Schools/Barton	Admissions Category	Neighborhood
		Turnaround Model	N/A

Building/System FCI Tiers

Facility Condition Index (FCI) = $\frac{\text{Cost of Assessed Deficiencies}}{\text{Replacement Value}}$				
< 15%	15 to 25%	25 to 45%	45 to 60%	> 60%
Buildings				
Minimal Current Capital Funding Required	Refurbish Systems in building	Replace Systems in building.	Building should be considered for major renovation.	Building should be considered for closing/replacement.
Systems				
Perform routine maintenance on system	System requires minor repairs	System should be studied to determine repair vs. replacement.	System is nearing end of its life expectancy and should be considered for replacement	System should be replaced as part of the Capital Program

Building and Grounds

	FCI	Repair Costs	Replacement Cost
Overall	47.43%	\$18,293,137	\$38,565,343
Building	49.35 %	\$17,844,364	\$36,159,365
Grounds	18.65 %	\$448,773	\$2,405,978

Major Building Systems

Building System	System FCI	Repair Costs	Replacement Cost
Roof (Shows physical condition of roof)	92.64 %	\$832,627	\$898,796
Exterior Walls (Shows condition of the structural condition of the exterior facade)	12.23 %	\$325,990	\$2,664,902
Windows (Shows functionality of exterior windows)	144.28 %	\$1,876,062	\$1,300,322
Exterior Doors (Shows condition of exterior doors)	66.74 %	\$69,873	\$104,690
Interior Doors (Classroom doors)	372.74 %	\$944,617	\$253,422
Interior Walls (Paint and Finishes)	15.47 %	\$187,759	\$1,213,682
Plumbing Fixtures	17.68 %	\$172,622	\$976,144
Boilers	97.32 %	\$1,311,841	\$1,347,974
Chillers/Cooling Towers	67.94 %	\$1,200,804	\$1,767,456
Radiators/Unit Ventilators/HVAC	170.17 %	\$5,281,958	\$3,103,878
Heating/Cooling Controls	132.68 %	\$1,293,203	\$974,700
Electrical Service and Distribution	63.11 %	\$441,956	\$700,340
Lighting	02.84 %	\$70,998	\$2,503,896
Communications and Security (Cameras, Pa System and Fire Alarm)	46.17 %	\$433,023	\$937,878

Please note that some FCIs may be over 100% because there are times when replacing a building system requires that other building systems be upgraded to complete the installation. A FCI of 0.0% represents that there are no current deficiencies with the associated system.

School District of Philadelphia
S720001; Barton
Final
Site Assessment Report

January 31, 2017



Table of Contents

Site Executive Summary	4
Site Condition Summary	11
<u>B720001:Barton</u>	13
Executive Summary	13
Condition Summary	14
Condition Detail	15
System Listing	16
System Notes	18
Renewal Schedule	19
Forecasted Sustainment Requirement	22
Condition Index Forecast by Investment Scenario	23
Deficiency Summary By System	24
Deficiency Summary By Priority	25
Deficiency By Priority Investment	26
Deficiency Summary By Category	27
Deficiency Details By Priority	28
Equipment Inventory Detail	54
<u>G720001:Grounds</u>	55
Executive Summary	55
Condition Summary	56
Condition Detail	57
System Listing	58
System Notes	59
Renewal Schedule	60
Forecasted Sustainment Requirement	61
Condition Index Forecast by Investment Scenario	62
Deficiency Summary By System	63
Deficiency Summary By Priority	64
Deficiency By Priority Investment	65

Site Assessment Report

Deficiency Summary By Category	66
Deficiency Details By Priority	67
Equipment Inventory Detail	70
Glossary	71

Site Executive Summary

The organization of this report, as displayed in the Table of Contents, follows the structure of the associated eCOMET database. The overall node for each school campus begins with the letter "S", which indicates the "Site" label. Each Site is comprised of separate "Building" and "Grounds" nodes; their asset names begin with the letters "B" and "G" respectively. Information rolls up to the Site node from the Building and Grounds nodes. This Site report combines facility information with subsections for the Buildings And Grounds nodes.

The basis for the evaluation of condition is the functional systems and elements of a building and grounds organized according to the UNIFORMAT II Elemental Classification. The grouping of these systems and elements and applying a current replacement value to them develops a representative building cost model. Cost Models are typically developed for similar building types and functions. Evaluation of systems and their elements takes into account their current replacement values, life cycles, installation dates and next renewal dates. Systems and their elements that are within their useful lives are further evaluated to identify current deficient conditions that may have a significant impact on a system's or element's remaining service life, and to determine if they are beyond their predicted expected life. The system's or element's current replacement value is based on RS Means Commercial Cost Data.

Following are the cost model's system details for this facility. The Replacement Value is the amount needed to replace the property of the same present value. The Current Repair Amount, also known as Condition Needs, represents the budgeted contractor installed costs plus owner's soft costs for the repair, replacement or renewal for a component or system level deficiency. It excludes contributing costs for other components or systems that might also be associated with the corrective actions due to packaging the work. Facility Condition Index (FCI) is an industry-standard measurement calculated as the ratio of the repair costs to correct a facility's deficiencies to the facility's Current Replacement Value. Condition Index (CI) for a system is calculated as the sum of the deficiencies divided by the sum of a system's Replacement Value (both values include soft-cost) expressed as a percentage ranging from 0% 100%.

Gross Area (SF):	72,200
Year Built:	1925
Last Renovation:	
Replacement Value:	\$38,565,343
Repair Cost:	\$18,293,136.88
Total FCI:	47.43 %
Total RSLI:	64.91 %



Description:

Facility Condition Assessment
July 2015

School District of Philadelphia
Clara Barton Elementary School
4600 Rosehill Street
Philadelphia, PA 19120

72,200sf / 850 students / LN 07

General

Clara Barton School is located at 4600 Rosehill Street. The main entrance faces Rosehill Street. The main building ("Element 1") was constructed in 1925, has 72,200 square feet, and is 3 stories tall. There is a full basement. An addition, called "Element 2" was constructed before 1950. The Clara Barton School can be found on the National Historical Register, number 88002242 with the address of 300 E. Wyoming Avenue. John Greenwood, the Building Engineer accompanied the FCA team during the inspection. The inspection team met with the Principal Bowen at the time of the assessment visit. She indicated that critical items in need of improvement were leaks that come through the walls when it rains (possibly due to roofing problems or cracks over windows),

and control of the heat system throughout the building (third floor is cold, first floor is hot).

Architectural/Structural

Foundations appear to be constructed of concrete, stone, and brick. Joints are in good condition with no major settlement cracks observed. Extensive peeling paint was observed on basement walls and ceilings, mainly due to high room moisture related to excessive steam released by the boilers and a lack of general maintenance of the space. Peeling paint was also observed on ductwork and other metal equipment. These areas should be tested for lead content before scraping, sanding and repainting; if lead is found in paint, proper hazardous material removal techniques must be followed. Footings were not seen and their construction type or condition could not be ascertained. There is evidence of rusting on the steel lintels above most basement windows with some localized joint cracking extending beyond the lintels which can be seen from inside the basement and outside the building. Water entering through these cracks in the exterior is one of the probable sources of the standing water in the basement. Another source is gaps and holes around a grade-level trap door to the basement.

Floor slabs in the basement are in good condition although covered with dirt and in need of stripping, cleaning and repainting. Upper floor slabs are also constructed of cast-in-place concrete with cast-in-place concrete beams. Cracking and spalling of the concrete structure was not observed anywhere in the main structure.

Roof construction over the main building is reinforced concrete beams and deck, bearing on masonry walls. The superstructure is constructed of reinforced concrete columns, beams, and floor slabs. The main building roof deck is flat with minimum overall slope; areas around roof drains are depressed for drainage. Roof access is via a door out of a masonry penthouse; a steep, narrow, dark stairway with very low headroom up from a 3rd floor stairway landing provides access to the roof penthouse. The roof over the auditorium is constructed of heavy timber trusses with wood decking. All appeared to be in good condition as observed in the attic space.

Exterior walls are generally in good condition, however there are lintels above most basement windows, some upper windows, and some doors which are rusted with brick joint cracks extending from the lintels into the brick joints in the walls. On the roof, there are gaps along the caulk joint where the reglets meet parapet walls which could be sources for water to enter the wall, forming leaks inside. A more detailed inspection of masonry is required to repair all failing joints and ensure a watertight envelope. Brick is stained with dirt and mildew and should be cleaned.

Exterior windows were replaced in the 1990's with bronze anodized aluminum frame operable single hung units with single thickness clear plexiglass acrylic vision panel glazing. Windows are in poor condition with oxidized frames and severely scratched single-pane plexiglass vision panels. Operable units are difficult to operate up and down or do not stay open due to broken internal counterbalance weights, accidentally slamming closed in some cases – a potential safety hazard. Single pane plexiglass units do not meet today's energy code requirements and are large sources of heat loss. All wood trim around windows needs refinishing. Replacement of all windows is recommended.

Exterior doors are painted steel framed flush hollow metal units with steel frames. The main entrance and secondary main entrance on Rosehill Street have decorative Romanesque-style tile arches around door openings. They can be cleaned to highlight their style and artistic technique. Some doors have small glazing vision panels. Doors are in generally poor condition, have broken or non-functioning panic hardware, rusted dented panels and frames, and are not ADA compliant. There are no handicap entrances, no accessible ramps and no elevators. All exterior steel doors and hardware systems need to be replaced.

Roof coverings on the main building flat roof consist of a ceramic granule impregnated, fully adhered rolled asphalt sheet system with asphalt flashing up onto rooftop ventilation ductwork, vents, and asphalt-backed metal flashing on masonry parapets with reglets and counterflashing. The roof membrane is in poor condition with dried cracked asphalt seen along membrane joints. The membrane, flashing, and counterflashing embedded in brickwork covering the top of the flashing is weathered and is probably past its normal service life of 20 years. Masonry flashing at the base of rooftop structures and parapets has been repaired with excessive amounts of caulking now weathered, cracking, and the potential sources of future leaks. The top of the brick parapet wall has stone coping with joints that have been caulked; they appear to be in good condition. Roof openings include toilet room vents, ventilation ductwork, and roof drains. Flashing of the penetrations appears to be in poor condition and past its normal service life, although no leaks were reported. Joint cracks in the penthouse and chimney structures have been repointed; other areas are developing cracks and may be the source of water infiltration. There have been a few leaks reported in the interior of exterior walls below but after recent repairs, there are none have been reported by engineering. The auditorium is covered with lightweight "residential-type, 3-tab" asphalt roofing shingles sloping to pitched metal troughs on the two low sides of the roof. There is evidence of leaks on the backstage auditorium wall which might be originating from the metal drain trough. Troughs have been recently recaulked and this could still be a source of the leaks. This roof system is thin and appears to be at the end of its 20 year normal service life.

Site Assessment Report - S720001;Barton

Partitions in basements are brick or concrete masonry units. The upper 2 floors of the original building ("Element 1") are thought to be constructed of wood and plaster on wood lath partitions. There are wood framed clerestory glass panels located in walls over classroom doors and between classroom storage areas and the corridors. These panels are in generally good condition being above the reach of anyone, but the glass is not wired or fire rated and should be replaced. Between some classrooms in "Element 1" are manually operated full height wood folding partitions. Most are not easy to operate and some are not moveable; in general they are not required and might not be stable if moved. In one case, however, a multi-purpose room was created by opening one of the old moveable walls, creating a large space used for evening events and meetings. Now that it is open, this wall is not re-closed. Walls between classrooms and corridors of "Element 2" are concrete masonry units (concrete block) and are generally crack free.

Interior doors are either the original wood and plate glass (not fire rated or wired) raised panel doors with original hardware or replacement wood doors with narrow wired glass vision panels and replacement hardware at least 20 years of age. Most wood doors regardless of age or type are damaged, have broken glass and broken hardware. Classroom doors do not have security locking feature from inside classrooms. Some interior basement doors are hollow metal in hollow metal frames and some are the original wood doors with wired glass. Most of the steel doors are rusted where coming in contact with floors. Upper level stairway doors are steel with 6 large divided lites with divided lite sidelites and transoms. This system does not have a UL label and does not appear to be fire rated, as required for stairway doors and partitions. Stairway doors do not positively latch as required of fire rated doors. Doors are generally in poor condition throughout the building, are not ADA compliant, do not have ADA or proper locking hardware, and are not fire rated where required. All doors and hardware in the building need to be replaced.

Interior fittings/hardware include black slate chalkboards with oak chalk trays or bulletin boards integral to the original dark oak folding wall partitions built into the folding panels. In some classrooms, the panels are not supported adequately at tops and bottoms and could fall off the track. These units are no longer opened as they are heavy and most hinges and bearings are not operable. Wall panels need to be replaced with sturdier, safer, fixed partitions. Toilet room partitions are either the original floor mounted marble toilet partitions or solid plastic replacement partitions. Many do not have doors. The usual sets of toilet room accessories (toilet paper dispensers, soap, paper towel or dryers, grab bars, door latches) are missing. Most toilet rooms are not clean and have years of built up dirt, however one toilet room has been refinished with new ceramic mosaic tile floors, tile walls, and toilet room accessories. New toilet partitions and accessories are required in all un-renovated toilet rooms.

Stair construction in the original building consists of concrete treads with cast-in steel tread plates, concrete risers, and concrete stringers with wood handrails (29" high), guards (36" high), and steel balusters with 3" spacing. Since handrail and guard heights are not in compliance with today's codes, new handrail and guard systems are required. Element 2 has no stairways which creates a dead end corridor code violation on the second and third floors. Exceeding travel distances is a serious fire hazard which needs to be addressed – a new fire stair is required for Element 2.

Wall finishes in the old building are plaster which is cracked with surface crazing in a number of classroom and corridor locations. There is usually damage in classrooms at doorways and corners. Moveable partitions between some classrooms are dark stained oak. Blackboards are embedded into wood panels but are no longer used. Wood panels are covered with staples and small gouges. Interior partitions in "Element 2" consist of glazed block wainscot in corridors with painted block above and painted block in classrooms, all in need of repainting. Corridors in the original building and Element 2 are plaster with some wood trim, both are generally in good condition with isolated cracks or damages requiring repair. Toilet rooms painted plaster walls and marble wainscots. The auditorium has a paneled wood wainscot that is in need of repair and refinishing. The queuing area outside the auditorium has plaster walls and columns with decorative plaster capitals on square columns. Some walls look like limestone blocks and are painted. These historical elements can be revitalized with some repair and new paint, creating an elegant entrance to the auditorium.

Floor finishes in the original building consist of mostly dark stained oak floors in classrooms and the auditorium. Most are in good enough condition to be stripped, sanded, and refinished. There are some classrooms and other rooms such as the main office, faculty lounge, and gymnasium (also serving as the cafeteria) finished with 12"x12" vinyl composition tile (VCT) over the old wood floors. Two small storage rooms in "Element 2" have 9"x9" tile floors that appear to be vinyl asbestos tiles (VAT). All wood floors need to be stripped and refinished to remove years of wax and dirt buildup; few need to be removed and replaced due to excessive warpage of the boards. All 12"x12" VCT floors need to be removed and replaced. Nine by nine inch tile floors may have asbestos and need to be addressed as possible asbestos containing materials. They should be removed using proper asbestos abatement procedures if they are found to contain asbestos. Corridor floors are finished with 4'x4' (nominal size) concrete tiles which appear to be a monolithic system and highly durable. Edges along the walls form a coved base and are painted. These slabs have not been stripped and cleaned for years and have dirt sealed into the surface and corners, causing their color to be very dark and dingy. There is an especially large build-up of dirt at all corners. Stairs walking surfaces are finished in exposed concrete that has years of dirt ground into the surfaces. These floor finishes should be stripped, cleaned and resealed.

Ceiling finishes in corridors are 2x4 suspended acoustical ceiling tile system with recessed 2x4 fluorescent lighting fixtures. Ceilings in classrooms are 2x4 suspended acoustical ceiling tile system with surface mounted 1x4 fluorescent lighting fixtures. These ceilings are old and dirty, lighting fixtures are yellowed, and the entire system needs to be replaced.

There is no elevator in the school.

Furnishings include the original folding wood seating in the auditorium is still in use; however many seats need to be repaired to operate properly and many are scratched. With the unavailability of parts for repair and the worn condition of the seating, full replacement is required. Wood wainscot in the auditorium is generally in good condition and can be repaired and refinished. Casework in classrooms and the office is damaged, worn, and needs replacement. Few classrooms have smartboards.

Grounds

Paving and parking is constructed of asphalt and in need of repaving. Asphalt areas serve as parking and playground areas, separated by fences. Stairways into the building are limestone blocks (tread/riser) with grouted joints between blocks; all stairs need regrouting. Parking and play area striping is worn and almost invisible. Clear separation of play area and parking is not evident. The number of required parking spaces for school staff is unknown.

Fencing is chain-link system generally in good condition. There are some damaged and bent fence panels in need of replacement in the area of Element 2. Steel pipe handrails to rear parking and playground area and up front stairs are not in compliance with stair and handrail requirements of today's building code. New handrails and guards to entrances and play areas are required for safety and code compliance.

Landscaping is in need of trimming and maintenance.

There is an ADA ramp into the auditorium, but not the main entrance area.

Mechanical

Plumbing Fixtures – It appears that all of the bathrooms, including plumbing fixtures, were remodeled within the past 10. Fixtures in the restrooms on each floor consist of wall mounted water closets, wall hung urinals and lavatories with wheel handle faucets. The plumbing fixtures appear to be in satisfactory condition and should not need replacement within the next 10 years.

Drinking fountains in the corridors and outside the restrooms are wall hung with integral refrigerated coolers. Most appear to be beyond their service life. Replacement of all drinking fountains is recommended.

Janitor closets are available throughout the building and appear to have been updated at the time of the bathroom renovations. The Cafeteria has one two-compartment stainless steel sink with sanitizing basin and lever operated faucets. Janitor closets and kitchen plumbing fixtures appear to be in satisfactory condition and should not need replacement within the next 10 years.

Domestic Water Distribution - Domestic water distribution piping is soldered copper. Water service enters the building in the basement, with backflow preventers and the water meter on the main line after entering the building. There is a domestic water pressure pump skid with duplex pumps after the backflow preventers to increase the water pressure supplied to the building. The distribution piping appears to be in satisfactory condition and should not need service or replacement within the next 10 years.

One natural gas fired A.O. Smith vertical water heater tank is installed in the basement with appropriate piping, controls, and venting. The water heater appears to be in satisfactory condition and should not need replacement within the next 10 years.

Sanitary Waste - The sanitary waste piping systems are constructed of threaded cast iron. The small sewer ejector pit with one pump is located in the basement. The entire sanitary system appears to be comprised of the original installed equipment and is well beyond its serviceable life. Inspection of the entire sanitary system throughout the main building is recommended and full replacement will probably be required.

Rain Water Drainage - The rain water drains from the roof are routed through vertical piping located in mechanical chases in the building. There are no roof overflow drains. The District should consider adding overflow scuppers to prevent roof flooding.

Energy Supply - Duplex fuel oil supply pumps provide the required fuel to the boilers when operating on fuel oil. The concrete fuel tank is located in the basement adjacent to the fuel oil pumps. The pumps appear to be beyond their serviceable life and should be replaced. Inspection of the concrete fuel tank is required. Additional boiler room ventilation and a fire suppression/fire alarm system located in the fuel storage area are required.

Heat Generating Systems - Steam is generated in the main building by two Weil McLain 94 series oil fired boilers installed in 1972.

Site Assessment Report - S720001;Barton

The boilers have Webster oil burners. The boilers and burners appear to be at the end of their serviceable life and should be replaced within the next 5 years.

Distribution Systems - Boiler feed water is treated with a combination of chemicals, controlled with a Master water treatment controller. This system has a condensate receiver with duplex pumps feeding a boiler feedwater tank, which also has duplex pumps. The condensate receiver package and the boiler feedwater package appear to be approximately 10 years old and should not need replacement for the next 10 years. The steam traps are failing throughout the building. The building engineer indicated that there is a constant stream of flash steam coming out of the boiler feed tank into the basement area and there poor steam distribution to "Element 2" (the "new" wing of the building) resulting in insufficient heat in Element 2. The steam and condensate return lines are only occasionally insulated and are beyond their serviceable life, requiring replacement.

Ventilation and additional heating for the main building was provided by a house fan in the basement, but this fan is no longer operational. Air had been pushed into most rooms of the building through ducts built into the walls. Air was exhausted from the rooms by separate ducts also built into the walls; the air traveled up through ducts in attic space out of the building through roof mounted vents. Presently, the only fresh air that the building receives is through the windows when opened. This is not an acceptable or code compliant condition for a public building – a fresh air delivery system is required. The bathrooms throughout the building have functional exhaust fans.

Terminal & Package Units – Most of the rooms in the building have window air conditioning units and most of the units are in operation (approximately 40 units total). Four rooms have unit ventilators which are not operational while the other rooms have radiators to generate heat. The majority of the radiators appear to be the originally installed equipment. There is a Mitsubishi ductless mini-split system serving the server room. This unit could not be inspected.

Controls & Instrumentation - There are some pneumatic thermostats on the walls that are not in service. The pneumatic control valves on the radiators are not in service. Most of the heating radiators are operating at 100% flow when the steam is on. This results in an "on-off" control for the whole building; when the boilers are on, the whole building has heat and when the boilers are off, the whole building is without heat. This creates a generally uncomfortable environment in the building. A new DDC system should be added to the main building for better heat control.

Sprinklers - There are no sprinklers in the main building. A new sprinkler system should be installed

Electrical

Site Electrical Service - The original electrical service is from Medium voltage overhead lines on wooden poles along Wyoming St. A utility power transformer is stepping down the voltage from existing medium Voltage to 120/208V, 3Ph 4 wire. That transformer is located in a concrete pit in front of the school on Rose hill Street. The main Breaker and utility metering are located in a closet at multipurpose room. There is one 1600 A distribution switchboard is located in boiler room.

Distribution System and Raceway System- The above mentioned distribution switchboard feeds all lighting and power panel boards throughout the building. An old 75KVA converter transformer convert the existing voltage to 2-240V 4wire for feeding the existing heat pumps. Each floor contains four lighting/power panel boards and two others for feeding the AC units. These panel boards and associated wiring are in good conditions.

Receptacles- Classrooms are typically supplied with duplex or quad receptacles spaced along all walls. Receptacle count for classrooms is adequate.

Lighting- The majority of lighting fixture in the building is 2x4 lay in grid or 1X4 surface mounted fluorescent lighting fixtures with T8 lamps and are in a good condition, however some repairs are needed.

Fire Alarm System- Building is equipped with 120V manual fire alarm system made by Couch Company. The company has been closed in 1985 and spare part is not found in the market since 2003. The existing system does not meet current fire alarm codes and shall be replaced.

Telephone / LAN- The telephone/LAN equipment/devices are located in second floor. Computer room and some classrooms and offices are provided with data outlets. Overall telephone and Local Area network system is adequate.

Public address/ Music- There is no separate PA system in the school. School uses the telephone systems for public announcement. This system is working adequately.

Site Assessment Report - S720001;Barton

Intercom System and paging- present paging system in school is completely functional. The paging system is one way communication from office to classrooms. Two way communications is obtained through wall mounted phones in the classrooms and other areas.

Clock and program system- The clock and program system is not working properly.

Television System- There is no television distribution system is provided in the school.

Security System- Access control, Video surveillance- The present security intrusion alarm and video surveillance system is adequate.

Emergency power systems- There is no generator and transfer switch in the school.

UPS- An adequate UPS provided for the local area network system.

Elevator- There is no elevator in the school.

Emergency Lighting System / Exit Lighting- No emergency lighting provided in the school. This is a safety issue and code violation.

Lightning Protection System- The present Lightning Protection System is adequate. It is accomplished with air terminal mounted on the chimney; however, some repairs are needed. A study needs to be conducted to verify the air terminals provide the proper coverage.

Grounding- The present grounding system is good.

Elevator- There is no elevator in the school.

Site Lighting - The present Site Lighting System is adequate. Some lighting fixtures need to be repair.

Site Video Surveillance – The exterior building is monitored by an adequate video surveillance system.

Site Paging - The present Site Paging System is adequate.

RECOMMENDATIONS

Architectural

- Strip and repaint concrete foundation (basement) walls in mechanical rooms
- Strip and repaint basement ceilings in mechanical rooms
- Clean and repaint basement floor in mechanical rooms
- Clean and reseal concrete floors in hallways and stairways
- Remove and replace all lintels and cracked masonry at basement windows and grade exit doorways
- Inspect and repair cracked masonry joints on rooftop structures
- Replace all exterior windows with insulated single hung units
- Powerwash front and sides of building
- Replace all exterior doors with ADA and code compliant exit hardware
- Remove and replace existing flat roof and insulation; 5 levels
- Remove and replace existing sloped asphalt shingle roof
- Remove non-rated glass panels between classrooms and corridors; fill with fire rated gyp bd sys.
- Remove and replace all wood interior doors and frames in classrooms and offices, etc. with fire rated doors.
- Refinish all doors in interior of classrooms.
- Provide security hardware for classrooms and offices, locking from inside classroom.
- Provide ADA compliant level locksets or latchsets on all other replace doors
- Remove and replace all basement steel doors, frames, and hardware in mechanical rooms and stairways
- Remove folding wood partitions; replace with gypsum board and metal stud walls
- Provide toilet room accessories and partitions
- Repair and repaint interior plaster walls where damaged
- Provide new emergency exit stair for Element 2 from floors 3 and 2, exiting to grade.
- Remove and replace stairway handrails and guards with code compliant systems.
- Regrout all joints between limestone block tread/risers at exterior stairs
- Strip, sand, repair and refinish all wood floors in classrooms and auditorium

Site Assessment Report - S720001;Barton

- Remove and replace all 12"x12" VCT floors in classrooms and gym
- Replace VAT floors using proper asbestos abatement procedures if determined asbestos is present
- Repaint all plaster ceilings in occupied spaces in the building
- Remove and replace folding wood auditorium chair with new chairs
- Add elevator to serve 4 floors (basement - 3rd floors)

Grounds

- Repave concrete playground panels and entrance area concrete
- Replace damaged areas of wrought iron fencing
- Repave asphalt parking & student staging/play area – only area utilized by staff
- Provide ADA accessible ramp into main entrance area / main floor of building.

Mechanical

- Replace of all drinking fountains in the Main building
- Inspect sanitary system throughout the main building.
- Replace duplex fuel oil pumps and skid
- Perform an inspection of the concrete fuel tank
- Install the required ventilation and fire suppression/alarm in the fuel storage area
- The boilers appear to be at the end of their serviceable life and should be replaced within the next 5 years
- Install a new DDC system for heat control
- Install a new sprinkler system
- Add overflow scuppers to roof parapet.
- Remove existing steam boilers and steam distribution system. Install hot water boilers and hot water distribution system.
- Install chiller and chilled water distribution system
- Install unit ventilators in all classrooms and the IMC
- Install AHU to condition the cafeteria
- Install AHU to condition the gymnasium
- Install AHU to condition the auditorium

Electrical

- Replace existing fire alarm system with a new automatic Fire Alarm System including control panel, initiated devices in corridors, air ducts, electrical and LAN rooms, library, and computer rooms. Provide notification devices in class rooms, offices, auditorium, corridors, other area recommended by codes.
- Install a new emergency power system including 100KW diesel generator and respective transfer switch.
- Provide emergency power to sufficient number of lighting fixtures in corridors, hallways, stairways and other egress ways to get minimum 1fc at egress ways per code.

Attributes:

General Attributes:

Active:	Open	Bldg Lot Tm:	Lot 1 / Tm 2
Status:	Accepted by SDP	Team:	Tm 2
Site ID:	S720001		

Site Condition Summary

The Table below shows the CI and FCI for each major system shown at the UNIFORMAT classification Level II. Note that Systems with lower FCIs require less investment than systems with higher FCIs.

Current Investment Requirement and Condition by Uniformat Classification

UNIFORMAT Classification	RSLI%	FCI %	Current Repair
A10 - Foundations	52.00 %	0.00 %	\$0.00
A20 - Basement Construction	52.00 %	0.00 %	\$0.00
B10 - Superstructure	52.00 %	0.00 %	\$0.00
B20 - Exterior Enclosure	71.92 %	55.82 %	\$2,271,925.04
B30 - Roofing	109.48 %	92.64 %	\$832,627.47
C10 - Interior Construction	45.22 %	61.72 %	\$1,093,482.67
C20 - Stairs	52.00 %	213.34 %	\$217,184.09
C30 - Interior Finishes	91.19 %	19.04 %	\$709,063.80
D10 - Conveying	77.14 %	260.79 %	\$670,322.07
D20 - Plumbing	104.44 %	36.05 %	\$531,566.15
D30 - HVAC	72.83 %	113.15 %	\$9,087,805.10
D40 - Fire Protection	105.71 %	177.00 %	\$1,029,992.15
D50 - Electrical	59.65 %	28.75 %	\$1,220,013.95
E10 - Equipment	14.29 %	0.00 %	\$0.00
E20 - Furnishings	12.50 %	117.29 %	\$180,381.10
G20 - Site Improvements	39.69 %	23.83 %	\$448,773.29
G40 - Site Electrical Utilities	30.59 %	0.00 %	\$0.00
Totals:	64.91 %	47.43 %	\$18,293,136.88

Condition Deficiency Priority

Facility Name	Gross Area (S.F.)	FCI %	1 - Response Time (< 2 yr)	2 - Response Time (2-3 yrs)	3 - Response Time (3-4 yrs)	4 - Response Time (4-5 yrs)	5 - Response Time (> 5 yrs)
B720001;Barton	72,200	49.35	\$1,437,198.04	\$6,619,585.78	\$4,305,491.50	\$614,007.22	\$4,868,081.05
G720001;Grounds	120,200	18.65	\$0.00	\$128,012.04	\$152,382.57	\$168,378.68	\$0.00
Total:		47.43	\$1,437,198.04	\$6,747,597.82	\$4,457,874.07	\$782,385.90	\$4,868,081.05

Deficiencies By Priority



- 1 - Response Time (< 2 yr) - \$1,437,198.04
- 2 - Response Time (2-3 yrs) - \$6,747,597.82
- 3 - Response Time (3-4 yrs) - \$4,457,874.07
- 4 - Response Time (4-5 yrs) - \$782,385.90
- 5 - Response Time (> 5 yrs) - \$4,868,081.05

Budget Estimate Total: \$18,293,136.88

Executive Summary

Building condition is evaluated based on the functional systems and elements of a building and organized according to the UNIFORMAT II Elemental Classification. The grouping of these systems and elements and applying a current replacement value to them develops a representative building cost model. Cost Models are developed for similar building types and functions. Systems and their elements are evaluated based on their current replacement values, life cycles, installation dates and next renewal dates. Systems and their elements that are within their useful lives are further evaluated to identify current deficient conditions that may have a significant impact on a system's or element's remaining service life, and to determine if they are beyond their predicted expected life. The system's or element's current replacement value is based on RS Means Commercial Cost Data.

Following are the cost model's system details for this facility. The Replacement Value is the amount needed to replace the property of the same present value. The Current Repair Amount, also known as Condition Needs, represents the budgeted contractor installed costs plus owner's soft costs for the repair, replacement or renewal for a component or system level deficiency. It excludes contributing costs for other components or systems that might also be associated with the corrective actions due to packaging the work. Facility Condition Index (FCI) FCI is an industry-standard measurement of facility condition calculated as the ratio of the costs to correct a facility's deficiencies to the facility's Current Replacement Value. It ranges from 0% (new) to 100% (very poor). Condition Index (CI) is calculated as the sum of a renewable system's Remaining Service Life (RSL) divided by the sum of a system's Replacement Value (both values exclude soft-cost to simplify calculation updates) expressed as a percentage ranging from 100% (new) to 0% (expired).

Function:	Elementary School
Gross Area (SF):	72,200
Year Built:	1925
Last Renovation:	
Replacement Value:	\$36,159,365
Repair Cost:	\$17,844,363.59
Total FCI:	49.35 %
Total RSLI:	66.71 %



Description:

Attributes:

General Attributes:

Active:	Open	Bldg ID:	B720001
Sewage Ejector:	No	Status:	Accepted by SDP
Site ID:	S720001		

Condition Summary

The Table below shows the CI and FCI for each major building system shown at the UNIFORMAT classification Level II. Note that Systems with lower FCIs require less investment than systems with higher FCIs.

UNIFORMAT Classification	RSLI %	FCI %	Current Repair Cost
A10 - Foundations	52.00 %	0.00 %	\$0.00
A20 - Basement Construction	52.00 %	0.00 %	\$0.00
B10 - Superstructure	52.00 %	0.00 %	\$0.00
B20 - Exterior Enclosure	71.92 %	55.82 %	\$2,271,925.04
B30 - Roofing	109.48 %	92.64 %	\$832,627.47
C10 - Interior Construction	45.22 %	61.72 %	\$1,093,482.67
C20 - Stairs	52.00 %	213.34 %	\$217,184.09
C30 - Interior Finishes	91.19 %	19.04 %	\$709,063.80
D10 - Conveying	77.14 %	260.79 %	\$670,322.07
D20 - Plumbing	104.44 %	36.05 %	\$531,566.15
D30 - HVAC	72.83 %	113.15 %	\$9,087,805.10
D40 - Fire Protection	105.71 %	177.00 %	\$1,029,992.15
D50 - Electrical	59.65 %	28.75 %	\$1,220,013.95
E10 - Equipment	14.29 %	0.00 %	\$0.00
E20 - Furnishings	12.50 %	117.29 %	\$180,381.10
Totals:	66.71 %	49.35 %	\$17,844,363.59

Condition Detail

This section of the report contains results of the Facility Condition Assessment. The building is separated into system components based on UNIFORMAT II classification. The columns in the System Listing table below represent the following:

1. System Code: A code that identifies the system.
2. System Description: A brief description of a system present in the building.
3. Unit Price \$: The unit price of the system.
4. UoM: The unit of measure for of the system.
5. Qty: The quantity for the system
6. Life: anticipated service life for the system based on Building Owners and Managers Association (BOMA) recommendations.
7. Year Installed: The date of system installation.
8. Calc Next Renewal Year: The date of system expiration based on the life, NR stands for non renewable.
9. Next Renewal Year: The suggested system expiration date by the assessor based on visual inspection.
10. CI: The Condition Index of the system.
11. FCI: The Facility Condition Index of the system.
12. RSL: Remaining Service Life.
13. eCR: eCOMET Condition Rating (not used).
14. Deficiency \$: The financial investment to repair/replace system.

System Listing

The System Listing table below lists each of the systems organized by their UNIFORMAT II classification. The assessment team was tasked with recording the most recent replacement year of each system, determining the remaining service life based on the theoretical life, and evaluating the condition to confirm the forecast next replacement year. The system listing is the basis for all data contained in the Building Assessment Report.

Additionally, a condition rating (eCR) based on the following guidelines is provided as observed at the time of the assessment.

- Excellent (E) - No noticeable distress or damage. The entire system is free from observable defect.
- Very Good (VG) - Overall no serviceability reduction for the entire system. No degradation of critical components and minor distress and defect noticeable for some but not non critical components within the system.
- Good (G) - Slight or no serviceability reduction for the entire system. There may be noticeable defects for some non critical components and slight noticeable degradation of the critical components.
- Fair (F) - Overall serviceability is degraded but adequate. There may be moderate deterioration for very few of the critical components and few of the non critical components may have severe degradation.
- Marginal (MA) - Overall serviceability and reliability loss. Most if not all of the non critical components suffer from severe degradation and a few of the critical component may have severe degradation.
- Moderate (MO) - Overall a significant serviceability loss. Most if not all the components have severe degradation with the reminder of the component showing visible distress.
- Very Poor (VP) - Overall the system is barely functional. All of the components are severely degraded.
- Non-Functional (NF) - Overall the system does not function with all the components having no serviceability and suffer from severe degradation.

System Code	System Description	Unit Price \$	UoM	Qty	Life	Year Installed	Calc Next Renewal Year	Next Renewal Year	RSLI%	FCI%	RSL	eCR	Deficiency \$	Replacement Value \$
A1010	Standard Foundations	\$18.40	S.F.	72,200	100	1925	2025	2067	52.00 %	0.00 %	52			\$1,328,480
A1030	Slab on Grade	\$7.73	S.F.	72,200	100	1925	2025	2067	52.00 %	0.00 %	52			\$558,106
A2010	Basement Excavation	\$6.55	S.F.	72,200	100	1925	2025	2067	52.00 %	0.00 %	52			\$472,910
A2020	Basement Walls	\$12.70	S.F.	72,200	100	1925	2025	2067	52.00 %	0.00 %	52			\$916,940
B1010	Floor Construction	\$75.10	S.F.	72,200	100	1925	2025	2067	52.00 %	0.00 %	52			\$5,422,220
B1020	Roof Construction	\$13.88	S.F.	72,200	100	1925	2025	2067	52.00 %	0.00 %	52			\$1,002,136
B2010	Exterior Walls	\$36.91	S.F.	72,200	100	1925	2025	2067	52.00 %	12.23 %	52		\$325,990.41	\$2,664,902
B2020	Exterior Windows	\$18.01	S.F.	72,200	40	1980	2020	2057	105.00 %	144.28 %	42		\$1,876,061.84	\$1,300,322
B2030	Exterior Doors	\$1.45	S.F.	72,200	25	1980	2005	2057	168.00 %	66.74 %	42		\$69,872.79	\$104,690
B3010105	Built-Up	\$37.76	S.F.	17,534	20	1990	2010	2037	110.00 %	94.67 %	22		\$626,817.22	\$662,084
B3010120	Single Ply Membrane	\$38.73	S.F.		20				0.00 %	0.00 %				\$0
B3010130	Preformed Metal Roofing	\$54.22	S.F.		30				0.00 %	0.00 %				\$0
B3010140	Shingle & Tile	\$38.73	S.F.	6,000	25	1985	2010	2042	108.00 %	88.57 %	27		\$205,810.25	\$232,380
B3020	Roof Openings	\$0.06	S.F.	72,200	20	1925	1945	2037	110.00 %	0.00 %	22			\$4,332
C1010	Partitions	\$17.91	S.F.	72,200	100	1925	2025	2067	52.00 %	9.92 %	52		\$128,334.08	\$1,293,102
C1020	Interior Doors	\$3.51	S.F.	72,200	40	1925	1965	2030	37.50 %	372.74 %	15		\$944,617.35	\$253,422
C1030	Fittings	\$3.12	S.F.	72,200	40	1925	1965	2021	15.00 %	9.11 %	6		\$20,531.24	\$225,264
C2010	Stair Construction	\$1.41	S.F.	72,200	100	1925	2025	2067	52.00 %	213.34 %	52		\$217,184.09	\$101,802

Site Assessment Report - B720001;Barton

System Code	System Description	Unit Price \$	UoM	Qty	Life	Year Installed	Calc Next Renewal Year	Next Renewal Year	RSLI%	FCI%	RSL	eCR	Deficiency \$	Replacement Value \$
C3010230	Paint & Covering	\$15.98	S.F.	72,200	10	1925	1935	2027	120.00 %	16.27 %	12		\$187,759.17	\$1,153,756
C3010231	Vinyl Wall Covering	\$0.00	S.F.		15				0.00 %	0.00 %				\$0
C3010232	Wall Tile	\$0.83	S.F.	72,200	30	1925	1955	2047	106.67 %	0.00 %	32			\$59,926
C3020411	Carpet	\$7.30	S.F.	0	10				0.00 %	0.00 %				\$0
C3020412	Terrazzo & Tile	\$75.52	S.F.	0	50				0.00 %	0.00 %				\$0
C3020413	Vinyl Flooring	\$9.68	S.F.	18,100	20	1995	2015	2037	110.00 %	57.97 %	22		\$101,565.55	\$175,208
C3020414	Wood Flooring	\$22.27	S.F.	36,100	25	1925	1950	2037	88.00 %	38.84 %	22		\$312,241.26	\$803,947
C3020415	Concrete Floor Finishes	\$0.97	S.F.	18,000	50	1925	1975	2067	104.00 %	396.34 %	52		\$69,201.60	\$17,460
C3030	Ceiling Finishes	\$20.97	S.F.	72,200	25	1925	1950	2032	68.00 %	2.53 %	17		\$38,296.22	\$1,514,034
D1010	Elevators and Lifts	\$3.56	S.F.	72,200	35			2042	77.14 %	260.79 %	27		\$670,322.07	\$257,032
D2010	Plumbing Fixtures	\$13.52	S.F.	72,200	35	1925	1960	2052	105.71 %	17.68 %	37		\$172,621.86	\$976,144
D2020	Domestic Water Distribution	\$1.68	S.F.	72,200	25	1925	1950	2042	108.00 %	0.00 %	27			\$121,296
D2030	Sanitary Waste	\$2.90	S.F.	72,200	25	1925	1950	2042	108.00 %	146.43 %	27		\$306,604.96	\$209,380
D2040	Rain Water Drainage	\$2.32	S.F.	72,200	30	1925	1955	2042	90.00 %	31.25 %	27		\$52,339.33	\$167,504
D3020	Heat Generating Systems	\$18.67	S.F.	72,200	35	1972	2007	2052	105.71 %	97.32 %	37		\$1,311,840.72	\$1,347,974
D3030	Cooling Generating Systems	\$24.48	S.F.	72,200	30				0.00 %	67.94 %			\$1,200,803.61	\$1,767,456
D3040	Distribution Systems	\$42.99	S.F.	72,200	25	1925	1950	2042	108.00 %	170.17 %	27		\$5,281,957.86	\$3,103,878
D3050	Terminal & Package Units	\$11.60	S.F.	72,200	20				0.00 %	0.00 %				\$837,520
D3060	Controls & Instrumentation	\$13.50	S.F.	72,200	20	1970	1990	2037	110.00 %	132.68 %	22		\$1,293,202.91	\$974,700
D4010	Sprinklers	\$7.05	S.F.	72,200	35			2052	105.71 %	202.35 %	37		\$1,029,992.15	\$509,010
D4020	Standpipes	\$1.01	S.F.	72,200	35			2052	105.71 %	0.00 %	37			\$72,922
D5010	Electrical Service/Distribution	\$9.70	S.F.	72,200	30	1995	2025	2025	33.33 %	63.11 %	10		\$441,955.99	\$700,340
D5020	Lighting and Branch Wiring	\$34.68	S.F.	72,200	20	2003	2023	2023	40.00 %	2.84 %	8		\$70,997.90	\$2,503,896
D5030	Communications and Security	\$12.99	S.F.	72,200	15	2004	2019	2034	126.67 %	46.17 %	19		\$433,023.03	\$937,878
D5090	Other Electrical Systems	\$1.41	S.F.	72,200	30	1925	1955	2047	106.67 %	269.19 %	32		\$274,037.03	\$101,802
E1020	Institutional Equipment	\$4.82	S.F.	72,200	35	1925	1960	2020	14.29 %	0.00 %	5			\$348,004
E1090	Other Equipment	\$11.10	S.F.	72,200	35	1925	1960	2020	14.29 %	0.00 %	5			\$801,420
E2010	Fixed Furnishings	\$2.13	S.F.	72,200	40	1925	1965	2020	12.50 %	117.29 %	5		\$180,381.10	\$153,786
Total									66.71 %	49.35 %			\$17,844,363.59	\$36,159,365

System Notes

The facility description in the site executive summary contains an overview of each system. The notes listed below provide additional information on select systems found within the facility.

System: B3010105 - Built-Up		This system contains no images
Note: built-up roof 75%		
System: B3010140 - Shingle & Tile		This system contains no images
Note: asphalt shingle roof 25%		
System: C1010 - Partitions		This system contains no images
Note: glazed block / brick 6%		
painted plaster on lath on wood studs 93%		
wood 1%		
System: C3010 - Wall Finishes		This system contains no images
Note: painted wall finish 95%		
ceramic tile finish 5%		
System: C3020 - Floor Finishes		This system contains no images
Note: vinyl tile (VCT) 25%		
Wood floor stained and clearcoated 50%		
concrete 25%		
System: C3030 - Ceiling Finishes		This system contains no images
Note: 2x4 acoustical ceilings 75%		
painted concrete or plaster 25%		

Renewal Schedule

eCOMET forecasts future Capital Renewal funding needed to address expiring systems based on the Next Renewal year found in the Cost Models. A 3% annual inflation factor is applied to the costs for systems expiring in future years. The table below reflects recommended Capital Renewal funding needs over the next 10 years. Note: Cells with a zero value indicate systems for which renewal is not scheduled in that year.

Inflation Rate: 3%

System	Current Deficiencies	2016	2017	2018	2019	2020	2021	2022	2023	2024	2025	Total
Total:	\$17,844,364	\$0	\$0	\$0	\$0	\$1,661,855	\$295,874	\$0	\$3,489,047	\$0	\$1,035,318	\$24,326,458
* A - Substructure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
A10 - Foundations	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
A1010 - Standard Foundations	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
A1030 - Slab on Grade	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
A20 - Basement Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
A2010 - Basement Excavation	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
A2020 - Basement Walls	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B - Shell	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B10 - Superstructure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B1010 - Floor Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B1020 - Roof Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B20 - Exterior Enclosure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B2010 - Exterior Walls	\$325,990	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$325,990
B2020 - Exterior Windows	\$1,876,062	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$1,876,062
B2030 - Exterior Doors	\$69,873	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$69,873
B30 - Roofing	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3010 - Roof Coverings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3010105 - Built-Up	\$626,817	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$626,817
B3010120 - Single Ply Membrane	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3010130 - Preformed Metal Roofing	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3010140 - Shingle & Tile	\$205,810	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$205,810
B3020 - Roof Openings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C - Interiors	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C10 - Interior Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C1010 - Partitions	\$128,334	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$128,334

Site Assessment Report - B720001;Barton

C1020 - Interior Doors	\$944,617	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$944,617
C1030 - Fittings	\$20,531	\$0	\$0	\$0	\$0	\$0	\$295,874	\$0	\$0	\$0	\$0	\$0	\$316,405
C20 - Stairs	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C2010 - Stair Construction	\$217,184	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$217,184
C30 - Interior Finishes	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C3010 - Wall Finishes	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C3010230 - Paint & Covering	\$187,759	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$187,759
C3010231 - Vinyl Wall Covering	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C3010232 - Wall Tile	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C3020 - Floor Finishes	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C3020411 - Carpet	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C3020412 - Terrazzo & Tile	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C3020413 - Vinyl Flooring	\$101,566	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$101,566
C3020414 - Wood Flooring	\$312,241	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$312,241
C3020415 - Concrete Floor Finishes	\$69,202	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$69,202
C3030 - Ceiling Finishes	\$38,296	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$38,296
D - Services	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D10 - Conveying	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D1010 - Elevators and Lifts	\$670,322	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$670,322
D20 - Plumbing	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D2010 - Plumbing Fixtures	\$172,622	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$172,622
D2020 - Domestic Water Distribution	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D2030 - Sanitary Waste	\$306,605	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$306,605
D2040 - Rain Water Drainage	\$52,339	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$52,339
D30 - HVAC	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D3020 - Heat Generating Systems	\$1,311,841	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$1,311,841
D3030 - Cooling Generating Systems	\$1,200,804	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$1,200,804
D3040 - Distribution Systems	\$5,281,958	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$5,281,958
D3050 - Terminal & Package Units	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D3060 - Controls & Instrumentation	\$1,293,203	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$1,293,203
D40 - Fire Protection	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D4010 - Sprinklers	\$1,029,992	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$1,029,992
D4020 - Standpipes	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0


Site Assessment Report - B720001;Barton

D50 - Electrical	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5010 - Electrical Service/Distribution	\$441,956	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$1,035,318	\$1,477,274
D5020 - Lighting and Branch Wiring	\$70,998	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$3,489,047	\$0	\$0	\$3,560,045
D5030 - Communications and Security	\$433,023	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$433,023
D5090 - Other Electrical Systems	\$274,037	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$274,037
E - Equipment & Furnishings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E10 - Equipment	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E1020 - Institutional Equipment	\$0	\$0	\$0	\$0	\$0	\$0	\$443,775	\$0	\$0	\$0	\$0	\$0	\$443,775
E1090 - Other Equipment	\$0	\$0	\$0	\$0	\$0	\$0	\$1,021,972	\$0	\$0	\$0	\$0	\$0	\$1,021,972
E20 - Furnishings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E2010 - Fixed Furnishings	\$180,381	\$0	\$0	\$0	\$0	\$0	\$196,109	\$0	\$0	\$0	\$0	\$0	\$376,490

* Indicates non-renewable system

Forecasted Sustainment Requirement

The following chart shows the current building deficiencies and forecasting sustainment requirements over the next ten years.




10 Year FCI Forecast by Investment Scenario

The chart below illustrates the effect of various investment levels on the building FCI for the next 10 years. The levels of investment shown below include:

- Current FCI: a variable investment amount based on renewing expired systems to maintain the current FCI for the building
- 2% Investment: an annual investment of 2% of the replacement value of the building, escalated for inflation
- 4% Investment: an annual investment of 4% of the replacement value of the building, escalated for inflation


Facility Investment vs. FCI Forecast



Year	Investment Amount Current FCI - 49.35%	2% Investment		4% Investment	
		Amount	FCI	Amount	FCI
2016	\$0	\$744,883.00	47.35 %	\$1,489,766.00	45.35 %
2017	\$12,863,233	\$767,229.00	78.88 %	\$1,534,459.00	74.88 %
2018	\$0	\$790,246.00	76.88 %	\$1,580,493.00	70.88 %
2019	\$1,161,149	\$813,954.00	77.73 %	\$1,627,907.00	69.73 %
2020	\$1,661,855	\$838,372.00	79.70 %	\$1,676,745.00	69.70 %
2021	\$295,874	\$863,523.00	78.38 %	\$1,727,047.00	66.38 %
2022	\$0	\$889,429.00	76.38 %	\$1,778,858.00	62.38 %
2023	\$3,489,047	\$916,112.00	82.00 %	\$1,832,224.00	66.00 %
2024	\$0	\$943,595.00	80.00 %	\$1,887,191.00	62.00 %
2025	\$1,035,318	\$971,903.00	80.13 %	\$1,943,807.00	60.13 %
Total:	\$20,506,477	\$8,539,246.00		\$17,078,497.00	

Deficiency Summary by System


Current deficiencies included assemblies that have reached or exceeded their design life or components of the assemblies that are in need of repair. Assemblies that have reached their design life are identified as current deficiencies and assigned the distress 'Beyond Useful Life'. The following chart lists all current deficiencies associated with this facility.



Budget Estimate Total: \$17,844,363.59

Deficiency Summary by Priority

The following chart shows the total repair costs broken down by priority. Assessors assigned deficiencies within eCOMET to one of the following priority categories:



Budget Estimate Total: \$17,844,363.59


Deficiency By Priority Investment Table

The table below shows the current investment cost grouped by deficiency priority and building system.

System Code	System Description	1 - Response Time (< 2 yr)	2 - Response Time (2-3 yrs)	3 - Response Time (3-4 yrs)	4 - Response Time (4-5 yrs)	5 - Response Time (> 5 yrs)	Total
B2010	Exterior Walls	\$0.00	\$191,210.01	\$0.00	\$134,780.40	\$0.00	\$325,990.41
B2020	Exterior Windows	\$0.00	\$0.00	\$1,876,061.84	\$0.00	\$0.00	\$1,876,061.84
B2030	Exterior Doors	\$0.00	\$69,872.79	\$0.00	\$0.00	\$0.00	\$69,872.79
B3010105	Built-Up	\$0.00	\$626,817.22	\$0.00	\$0.00	\$0.00	\$626,817.22
B3010140	Shingle & Tile	\$0.00	\$205,810.25	\$0.00	\$0.00	\$0.00	\$205,810.25
C1010	Partitions	\$0.00	\$0.00	\$128,334.08	\$0.00	\$0.00	\$128,334.08
C1020	Interior Doors	\$0.00	\$944,617.35	\$0.00	\$0.00	\$0.00	\$944,617.35
C1030	Fittings	\$0.00	\$0.00	\$20,531.24	\$0.00	\$0.00	\$20,531.24
C2010	Stair Construction	\$217,184.09	\$0.00	\$0.00	\$0.00	\$0.00	\$217,184.09
C3010230	Paint & Covering	\$0.00	\$187,759.17	\$0.00	\$0.00	\$0.00	\$187,759.17
C3020413	Vinyl Flooring	\$0.00	\$7,583.33	\$0.00	\$0.00	\$93,982.22	\$101,565.55
C3020414	Wood Flooring	\$0.00	\$0.00	\$312,241.26	\$0.00	\$0.00	\$312,241.26
C3020415	Concrete Floor Finishes	\$0.00	\$0.00	\$69,201.60	\$0.00	\$0.00	\$69,201.60
C3030	Ceiling Finishes	\$0.00	\$0.00	\$38,296.22	\$0.00	\$0.00	\$38,296.22
D1010	Elevators and Lifts	\$0.00	\$670,322.07	\$0.00	\$0.00	\$0.00	\$670,322.07
D2010	Plumbing Fixtures	\$0.00	\$0.00	\$0.00	\$172,621.86	\$0.00	\$172,621.86
D2030	Sanitary Waste	\$0.00	\$0.00	\$0.00	\$306,604.96	\$0.00	\$306,604.96
D2040	Rain Water Drainage	\$0.00	\$52,339.33	\$0.00	\$0.00	\$0.00	\$52,339.33
D3020	Heat Generating Systems	\$0.00	\$0.00	\$0.00	\$0.00	\$1,311,840.72	\$1,311,840.72
D3030	Cooling Generating Systems	\$0.00	\$0.00	\$0.00	\$0.00	\$1,200,803.61	\$1,200,803.61
D3040	Distribution Systems	\$0.00	\$3,482,873.16	\$567,622.35	\$0.00	\$1,231,462.35	\$5,281,957.86
D3060	Controls & Instrumentation	\$0.00	\$0.00	\$1,293,202.91	\$0.00	\$0.00	\$1,293,202.91
D4010	Sprinklers	\$0.00	\$0.00	\$0.00	\$0.00	\$1,029,992.15	\$1,029,992.15
D5010	Electrical Service/Distribution	\$441,955.99	\$0.00	\$0.00	\$0.00	\$0.00	\$441,955.99
D5020	Lighting and Branch Wiring	\$70,997.90	\$0.00	\$0.00	\$0.00	\$0.00	\$70,997.90
D5030	Communications and Security	\$433,023.03	\$0.00	\$0.00	\$0.00	\$0.00	\$433,023.03
D5090	Other Electrical Systems	\$274,037.03	\$0.00	\$0.00	\$0.00	\$0.00	\$274,037.03
E2010	Fixed Furnishings	\$0.00	\$180,381.10	\$0.00	\$0.00	\$0.00	\$180,381.10
	Total:	\$1,437,198.04	\$6,619,585.78	\$4,305,491.50	\$614,007.22	\$4,868,081.05	\$17,844,363.59

Deficiency Summary by Category

The following chart shows the total repair costs broken down by deficiency categories. Assessors assigned deficiencies to one of the following categories:



Deficiency Details by Priority

The deficiency detail notes listed below provide additional information on identified deficiencies found within the facility.

Priority 1 - Response Time (< 2 yr):

System: C2010 - Stair Construction



Location: stairways

Distress: Building / MEP Codes

Category: 2 - Code Compliance

Priority: 1 - Response Time (< 2 yr)

Correction: Replace inadequate or install proper stair railing - select appropriate material

Qty: 350.00

Unit of Measure: L.F.


Estimate: \$163,831.77

Assessor Name: System

Date Created: 07/30/2015

Notes: Remove and replace stairway handrails and guards with code compliant systems wall mounted pipe rails and center mounted rails with balustrades

System: C2010 - Stair Construction



Location: corridor

Distress: Building / MEP Codes

Category: 2 - Code Compliance

Priority: 1 - Response Time (< 2 yr)

Correction: Repair exterior stairs

Qty: 80.00

Unit of Measure: Riser

Estimate: \$32,832.20

Assessor Name: System

Date Created: 07/30/2015

Notes: Provide new emergency exit stair for Element 2 from floors 3 and 2, exiting to grade.

System: C2010 - Stair Construction



Location: exterior stairs
Distress: Failing
Category: 3 - Operations / Maint.
Priority: 1 - Response Time (< 2 yr)
Correction: Repair exterior stairs
Qty: 50.00
Unit of Measure: Riser
Estimate: \$20,520.12
Assessor Name: System
Date Created: 07/30/2015

Notes: RegROUT all joints between limestone block tread/risers at exterior stairs

System: D5010 - Electrical Service/Distribution



Location: Boiler Room
Distress: Inadequate
Category: 4 - Capital Improvement
Priority: 1 - Response Time (< 2 yr)
Correction: Add service entrance switchboard
Qty: 1.00
Unit of Measure: Ea.
Estimate: \$441,955.99
Assessor Name: System
Date Created: 09/17/2015

Notes: Upgrade the existing electrical service with a new 2000A service. Provide connection between existing switchboard with the new service switchboard.

System: D5020 - Lighting and Branch Wiring



Location: corridors and exitways
Distress: Building / MEP Codes
Category: 2 - Code Compliance
Priority: 1 - Response Time (< 2 yr)
Correction: Add wiring device
Qty: 1.00
Unit of Measure: Ea.
Estimate: \$59,888.97
Assessor Name: System
Date Created: 07/29/2015

Notes: Provide emergency power to sufficient number of lighting fixtures in corridors, hallways, stairways and other egress ways to get minimum 1fc at egress ways per code.

System: D5020 - Lighting and Branch Wiring



Location: Exterior Building
Distress: Damaged
Category: 3 - Operations / Maint.
Priority: 1 - Response Time (< 2 yr)
Correction: Replace lighting fixtures
Qty: 1.00
Unit of Measure: Ea.
Estimate: \$11,108.93
Assessor Name: System
Date Created: 08/05/2015

Notes: Replace existing lighting fixtures that are not functioning. Estimated 30each

System: D5030 - Communications and Security



Location: Entire Building
Distress: Beyond Service Life
Category: 3 - Operations / Maint.
Priority: 1 - Response Time (< 2 yr)
Correction: Replace fire alarm system
Qty: 1.00
Unit of Measure: S.F.
Estimate: \$433,023.03
Assessor Name: System
Date Created: 07/29/2015

Notes: Replace existing fire alarm system with a new automatic Fire Alarm System including control panel, initiated devices in corridors, air ducts, electrical and LAN rooms, library, and computer rooms. Provide notification devices in class rooms, offices, auditorium, corridors, other area recommended by codes.

System: D5090 - Other Electrical Systems

This deficiency has no image.

Location: Boiler Room
Distress: Beyond Service Life
Category: 3 - Operations / Maint.
Priority: 1 - Response Time (< 2 yr)
Correction: Add Standby Generator System
Qty: 1.00
Unit of Measure: Ea.
Estimate: \$245,510.84
Assessor Name: System
Date Created: 07/29/2015

Notes: Install a new emergency power system including 100KW diesel generator and respective transfer switch.

System: D5090 - Other Electrical Systems



Location: Roof

Distress: Life Safety / NFPA / PFD

Category: 1 - Health & Safety

Priority: 1 - Response Time (< 2 yr)

Correction: Repair Lightning Protection System

Qty: 1.00

Unit of Measure: Job

Estimate: \$28,526.19

Assessor Name: System

Date Created: 08/05/2015

Notes: Provide lightning protection studies to ascertain adequacy of existing systems.

Priority 2 - Response Time (2-3 yrs):

System: B2010 - Exterior Walls



Location: exterior walls

Distress: Failing

Category: 3 - Operations / Maint.

Priority: 2 - Response Time (2-3 yrs)

Correction: Remove and replacing failing steel lintels in brick wall construction

Qty: 400.00

Unit of Measure: L.F.

Estimate: \$191,210.01

Assessor Name: System

Date Created: 07/30/2015

Notes: Remove and replace all lintels at basement windows and grade exit doorways

System: B2030 - Exterior Doors



Location: exterior doors

Distress: Damaged

Category: 3 - Operations / Maint.

Priority: 2 - Response Time (2-3 yrs)

Correction: Replace hardware with compliant hardware, paint and weatherstrip - per leaf

Qty: 20.00

Unit of Measure: Ea.

Estimate: \$69,872.79

Assessor Name: System

Date Created: 07/30/2015

Notes: Replace all non-operational exterior door hardware with ADA and code compliant exit hardware

System: B3010105 - Built-Up



Location: roof
Distress: Beyond Service Life
Category: 3 - Operations / Maint.
Priority: 2 - Response Time (2-3 yrs)
Correction: Remove and Replace Built Up Roof
Qty: 18,500.00
Unit of Measure: S.F.
Estimate: \$626,817.22
Assessor Name: System
Date Created: 07/30/2015

Notes: Remove and replace existing flat roof and insulation;

System: B3010140 - Shingle & Tile



Location: asphalt roof (auditorium)
Distress: Beyond Service Life
Category: 3 - Operations / Maint.
Priority: 2 - Response Time (2-3 yrs)
Correction: Remove and replace asphalt shingle roof - partial area
Qty: 6,000.00
Unit of Measure: S.F.
Estimate: \$205,810.25
Assessor Name: System
Date Created: 07/30/2015

Notes: Remove and replace existing sloped asphalt shingle roof on auditorium

System: C1020 - Interior Doors



Location: interior doors
Distress: Building / MEP Codes
Category: 2 - Code Compliance
Priority: 2 - Response Time (2-3 yrs)
Correction: Remove and replace interior doors - wood doors with wood frame - per leaf
Qty: 100.00
Unit of Measure: Ea.
Estimate: \$465,433.90
Assessor Name: System
Date Created: 07/30/2015

Notes: Remove and replace all wood interior doors and frames in classrooms, etc. with code compliant fire rated doors (100)

System: C1020 - Interior Doors



Location: interior rooms
Distress: Damaged
Category: 3 - Operations / Maint.
Priority: 2 - Response Time (2-3 yrs)
Correction: Remove and replace hollow metal frames and doors
Qty: 60.00
Unit of Measure: Ea.
Estimate: \$304,679.23
Assessor Name: System
Date Created: 07/30/2015

Notes: Remove and replace all steel doors, frames, and hardware in mechanical rooms, basement, and stairways

System: C1020 - Interior Doors



Location: interior of rooms

Distress: Beyond Service Life

Category: 3 - Operations / Maint.

Priority: 2 - Response Time (2-3 yrs)

Correction: Refinish interior doors

Qty: 100.00

Unit of Measure: Ea.

Estimate: \$82,818.30

Assessor Name: System

Date Created: 12/14/2015

Notes: Refinish all wood interior doors and frames in closets and interior of rooms (100)

System: C1020 - Interior Doors



Location: interior doors

Distress: Building / MEP Codes

Category: 2 - Code Compliance

Priority: 2 - Response Time (2-3 yrs)

Correction: Replace door knobs with compliant lever type

Qty: 140.00

Unit of Measure: Ea.

Estimate: \$77,919.73

Assessor Name: System

Date Created: 07/30/2015

Notes: Provide ADA compliant level locksets or latchsets on all other replace doors

System: C1020 - Interior Doors



Location: classroom and office doors

Distress: Life Safety / NFPA / PFD

Category: 1 - Health & Safety

Priority: 2 - Response Time (2-3 yrs)

Correction: Provide security hardware for classroom and office doors

Qty: 60.00

Unit of Measure: Ea.


Estimate: \$13,766.19

Assessor Name: System

Date Created: 07/30/2015

Notes: Provide security hardware for classrooms and offices, locking from inside classroom.

System: C3010230 - Paint & Covering



Location: interior walls

Distress: Appearance

Category: 3 - Operations / Maint.

Priority: 2 - Response Time (2-3 yrs)

Correction: Repair and repaint all interior walls - SF of wall surface

Qty: 20,000.00

Unit of Measure: S.F.

Estimate: \$102,169.74

Assessor Name: System

Date Created: 07/30/2015

Notes: Repair and repaint interior plaster walls where damaged

System: C3010230 - Paint & Covering



Location: boiler and mechanical rooms

Distress: Appearance

Category: 3 - Operations / Maint.

Priority: 2 - Response Time (2-3 yrs)

Correction: Repair substrate and repaint interior concrete or CMU walls - SF of wall surface

Qty: 12,000.00

Unit of Measure: S.F.

Estimate: \$60,046.99

Assessor Name: System

Date Created: 07/30/2015

Notes: Strip and repaint concrete foundation (basement) walls in mechanical rooms

System: C3010230 - Paint & Covering



Location: ceilings

Distress: Appearance

Category: 3 - Operations / Maint.

Priority: 2 - Response Time (2-3 yrs)

Correction: Repair and repaint all interior walls - SF of wall surface

Qty: 5,000.00

Unit of Measure: S.F.

Estimate: \$25,542.44

Assessor Name: System

Date Created: 07/30/2015

Notes: Repaint plaster ceilings where damaged in the building

System: C3020413 - Vinyl Flooring



Location: offices

Distress: Life Safety / NFPA / PFD

Category: 1 - Health & Safety

Priority: 2 - Response Time (2-3 yrs)

Correction: Remove VAT and replace with VCT - SF of area

Qty: 500.00

Unit of Measure: S.F.

Estimate: \$7,583.33

Assessor Name: System

Date Created: 07/30/2015

Notes: Replace VAT floors using proper asbestos abatement procedures if determined asbestos is present

System: D1010 - Elevators and Lifts

This deficiency has no image.

Location: to be determined

Distress: Building / MEP Codes

Category: 2 - Code Compliance

Priority: 2 - Response Time (2-3 yrs)

Correction: Add interior elevator - 4 floors - adjust the electrical run lengths to hook up the elevator

Qty: 1.00

Unit of Measure: Ea.

Estimate: \$670,322.07

Assessor Name: System

Date Created: 08/07/2015

Notes: add elevator to serve 4 floors (basement - 3rd floors)

System: D2040 - Rain Water Drainage



Location: roof
Distress: Building / MEP Codes
Category: 2 - Code Compliance
Priority: 2 - Response Time (2-3 yrs)
Correction: Create new overflow scupper through a parapet with up to 100' downspout
Qty: 5.00
Unit of Measure: Ea.
Estimate: \$52,339.33
Assessor Name: System
Date Created: 10/23/2015

Notes: Add overflow scuppers to roof.

System: D3040 - Distribution Systems



Location: classrooms
Distress: Inadequate
Category: 4 - Capital Improvement
Priority: 2 - Response Time (2-3 yrs)
Correction: Replace the existing unit ventilators with new units designed to provide adequate ventilation per ASHRAE Std 62 - insert the SF of bldg. in the qty.
Qty: 72,200.00
Unit of Measure: S.F.
Estimate: \$3,482,873.16
Assessor Name: System
Date Created: 08/04/2015

Notes: Install unit ventilators in all classrooms and IMC

System: E2010 - Fixed Furnishings



Location: auditorium

Distress: Beyond Service Life

Category: 3 - Operations / Maint.

Priority: 2 - Response Time (2-3 yrs)

Correction: Replace auditorium seating - add tablet arms if required. Veneer seating is an option.

Qty: 200.00

Unit of Measure: Ea.

Estimate: \$180,381.10

Assessor Name: System

Date Created: 07/30/2015

Notes: Repair and replace (if necessary) folding wood auditorium chair with new chairs

Priority 3 - Response Time (3-4 yrs):

System: B2020 - Exterior Windows



Location: exterior walls

Distress: Beyond Service Life

Category: 3 - Operations / Maint.

Priority: 3 - Response Time (3-4 yrs)

Correction: Remove and replace aluminum windows - pick the appropriate size and style and insert the number of units

Qty: 300.00

Unit of Measure: Ea.

Estimate: \$1,876,061.84

Assessor Name: System

Date Created: 07/30/2015

Notes: Replace all exterior windows with insulated single hung units

System: C1010 - Partitions



Location: classrooms

Distress: Beyond Service Life

Category: 3 - Operations / Maint.

Priority: 3 - Response Time (3-4 yrs)

Correction: Remove folding wood partitions; replace with metal studs and gypsum board painted

Qty: 5,400.00

Unit of Measure: S.F.

Estimate: \$120,309.28

Assessor Name: System

Date Created: 07/30/2015

Notes: Remove folding wood partitions; replace with gypsum board and metal stud walls

System: C1010 - Partitions



Location: corridors

Distress: Life Safety / NFPA / PFD

Category: 1 - Health & Safety

Priority: 3 - Response Time (3-4 yrs)

Correction: Remove non-rated interior glass panels and replace with studs, gypsum board, paint (E) wall

Qty: 300.00

Unit of Measure: S.F.

Estimate: \$8,024.80

Assessor Name: System

Date Created: 07/30/2015

Notes: Remove non-rated glass panels between classrooms and corridors; fill with fire rated gyp bd sys.

System: C1030 - Fittings



Location: toilet rooms

Distress: Beyond Service Life

Category: 3 - Operations / Maint.

Priority: 3 - Response Time (3-4 yrs)

Correction: Remove and replace toilet partitions

Qty: 8.00

Unit of Measure: Ea.

Estimate: \$20,531.24

Assessor Name: System

Date Created: 07/30/2015

Notes: Provide toilet room accessories and partitions (old bathrooms not yet renovated)

System: C3020414 - Wood Flooring



Location: classrooms, auditoriums

Distress: Appearance

Category: 3 - Operations / Maint.

Priority: 3 - Response Time (3-4 yrs)

Correction: Refinish wood floors

Qty: 29,000.00

Unit of Measure: S.F.

Estimate: \$312,241.26

Assessor Name: System

Date Created: 07/30/2015

Notes: Strip, sand, repair and refinish all wood floors in classrooms and auditorium

System: C3020415 - Concrete Floor Finishes



Location: interiors - corridors

Distress: Appearance

Category: 3 - Operations / Maint.

Priority: 3 - Response Time (3-4 yrs)

Correction: Clean and reseal concrete floors

Qty: 10,000.00

Unit of Measure: S.F.

Estimate: \$38,445.33

Assessor Name: System

Date Created: 07/30/2015

Notes: Clean and reseal concrete floors in hallways and stairways

System: C3020415 - Concrete Floor Finishes



Location: boiler room floor

Distress: Appearance

Category: 3 - Operations / Maint.

Priority: 3 - Response Time (3-4 yrs)

Correction: Clean and reseal concrete floors

Qty: 8,000.00

Unit of Measure: S.F.

Estimate: \$30,756.27

Assessor Name: System

Date Created: 07/30/2015

Notes: Clean and repaint basement floor in mechanical rooms

System: C3030 - Ceiling Finishes



Location: boiler room

Distress: Appearance

Category: 3 - Operations / Maint.

Priority: 3 - Response Time (3-4 yrs)

Correction: Re-paint ceilings - SF of ceilings

Qty: 8,000.00

Unit of Measure: S.F.

Estimate: \$38,296.22

Assessor Name: System

Date Created: 07/30/2015

Notes: Strip and repaint basement ceilings in mechanical rooms

System: D3040 - Distribution Systems



Location: Throughout Building
Distress: Beyond Service Life
Category: 3 - Operations / Maint.
Priority: 3 - Response Time (3-4 yrs)
Correction: Perform testing to identify and replace damaged steam and condensate piping.
Qty: 60,000.00
Unit of Measure: S.F.
Estimate: \$567,622.35
Assessor Name: System
Date Created: 08/04/2015

Notes: Hire a qualified contractor to inspect the steam and condensate piping to identify and replace damaged section and to determine the extent of potential failures.

System: D3060 - Controls & Instrumentation



Location: entire building
Distress: Obsolete
Category: 3 - Operations / Maint.
Priority: 3 - Response Time (3-4 yrs)
Correction: Replace pneumatic controls with DDC (150KSF)
Qty: 72,200.00
Unit of Measure: S.F.
Estimate: \$1,293,202.91
Assessor Name: System
Date Created: 08/04/2015

Notes: Install a new DDC system to the main building

Priority 4 - Response Time (4-5 yrs):

System: B2010 - Exterior Walls



Location: exterior walls

Distress: Appearance

Category: 3 - Operations / Maint.

Priority: 4 - Response Time (4-5 yrs)

Correction: Remove graffiti - power wash and paint

Qty: 20,000.00

Unit of Measure: S.F.

Estimate: \$134,780.40

Assessor Name: System

Date Created: 07/30/2015

Notes: Powerwash front and sides of building

System: D2010 - Plumbing Fixtures



Location: corridors

Distress: Beyond Service Life

Category: 3 - Operations / Maint.

Priority: 4 - Response Time (4-5 yrs)

Correction: Remove and replace water fountains to meet ADA - includes high and low fountains and new recessed alcove

Qty: 11.00

Unit of Measure: Ea.

Estimate: \$172,621.86

Assessor Name: System

Date Created: 08/04/2015

Notes: Replace of all drinking fountains in the Main building

System: D2030 - Sanitary Waste

This deficiency has no image.

Location: entire building

Distress: Beyond Service Life

Category: 3 - Operations / Maint.

Priority: 4 - Response Time (4-5 yrs)

Correction: Inspect sanitary waste piping and replace damaged sections. (+100KSF)

Qty: 72,200.00

Unit of Measure: S.F.

Estimate: \$306,604.96

Assessor Name: System

Date Created: 08/04/2015

Notes: Inspect sanitary system throughout the main building

Priority 5 - Response Time (> 5 yrs):

System: C3020413 - Vinyl Flooring



Location: gymnasium, classrooms

Distress: Beyond Service Life

Category: 3 - Operations / Maint.

Priority: 5 - Response Time (> 5 yrs)

Correction: Remove VAT and replace with VCT - SF of area

Qty: 11,000.00

Unit of Measure: S.F.

Estimate: \$93,982.22

Assessor Name: System

Date Created: 07/30/2015

Notes: Remove and replace all 12"x12" VCT floors in classrooms and gym

System: D3020 - Heat Generating Systems



Location: boiler room

Distress: Beyond Service Life

Category: 3 - Operations / Maint.

Priority: 5 - Response Time (> 5 yrs)

Correction: Replace boiler, cast iron sectional (150 HP)

Qty: 2.00

Unit of Measure: Ea.

Estimate: \$1,050,121.66

Assessor Name: System

Date Created: 08/04/2015

Notes: The steam boilers appear to be at the end of their serviceable life and should be replaced within the next 5 years with hot water boilers..

System: D3020 - Heat Generating Systems



Location: outside building, location to be determined

Distress: Life Safety / NFPA / PFD

Category: 1 - Health & Safety

Priority: 5 - Response Time (> 5 yrs)

Correction: Provide fuel oil tank, above ground concrete encased (8,000 gal)

Qty: 1.00

Unit of Measure: Ea.

Estimate: \$235,040.98

Assessor Name: System

Date Created: 08/04/2015

Notes: Replace concrete fuel tank

System: D3020 - Heat Generating Systems



Location: boiler room

Distress: Beyond Service Life

Category: 3 - Operations / Maint.

Priority: 5 - Response Time (> 5 yrs)

Correction: Replace fuel oil pumps

Qty: 1.00

Unit of Measure: Ea.

Estimate: \$26,678.08

Assessor Name: System

Date Created: 08/04/2015

Notes: Replace duplex fuel oil pumps and skid

System: D3030 - Cooling Generating Systems



Location: entire building
Distress: Inadequate
Category: 4 - Capital Improvement
Priority: 5 - Response Time (> 5 yrs)
Correction: Install chilled water system with distribution piping and pumps. (+150KSF)
Qty: 72,200.00
Unit of Measure: S.F.
Estimate: \$1,200,803.61
Assessor Name: System
Date Created: 08/04/2015

Notes: Install chiller and chilled water distribution system

System: D3040 - Distribution Systems



Location: auditorium
Distress: Inadequate
Category: 4 - Capital Improvement
Priority: 5 - Response Time (> 5 yrs)
Correction: Install HVAC unit for Auditorium (200 seat).
Qty: 400.00
Unit of Measure: Seat
Estimate: \$570,170.82
Assessor Name: System
Date Created: 08/04/2015

Notes: Install AHU to condition the auditorium

System: D3040 - Distribution Systems



Location: cafeteria

Distress: Inadequate

Category: 4 - Capital Improvement

Priority: 5 - Response Time (> 5 yrs)

Correction: Install HVAC unit for Cafeteria (850 students).

Qty: 755.00

Unit of Measure: Pr.

Estimate: \$352,990.49

Assessor Name: System

Date Created: 08/04/2015

Notes: Install AHU to condition the cafeteria

System: D3040 - Distribution Systems



Location: gym

Distress: Inadequate

Category: 4 - Capital Improvement

Priority: 5 - Response Time (> 5 yrs)

Correction: Install HVAC unit for Gymnasium (single station).

Qty: 6,000.00

Unit of Measure: Ea.

Estimate: \$308,301.04

Assessor Name: System

Date Created: 08/04/2015

Notes: Install AHU to condition the gymnasium

System: D4010 - Sprinklers



Location: entire building

Distress: Life Safety / NFPA / PFD

Category: 1 - Health & Safety

Priority: 5 - Response Time (> 5 yrs)

Correction: Install a fire protection sprinkler system

Qty: 72,000.00

Unit of Measure: S.F.

Estimate: \$1,029,992.15

Assessor Name: System

Date Created: 08/04/2015

Notes: Install a new sprinkler system

Equipment Inventory

The following table represents the inventory details of the inventory found in the building, which fall under the following subsystems:


Subsystem	Inventory	Qty	UoM	Location	Manufacturer	Model Number	Serial Number	Barcode	Life	Install Date	Next Renewal	Raw Cost	Inventory Cost
D3020 Heat Generating Systems	Boiler, gas/oil combination, cast iron, steam, gross output, 5230 MBH, includes burners, controls and insulated jacket, packaged	1.00	Ea.	boiler room	Weil McLain	94	107089B		35	1972	2007	\$122,870.00	\$135,157.00
D3020 Heat Generating Systems	Boiler, gas/oil combination, cast iron, steam, gross output, 5230 MBH, includes burners, controls and insulated jacket, packaged	1.00	Ea.	boiler room	Weil McLain	94	107090B		35	1972	2007	\$122,870.00	\$135,157.00
D5010 Electrical Service/Distribution	Switchgear installation, incl switchboard, panels & circuit breaker, 120/208 V, 1600 A	1.00	Ea.	service entrance in electrical closet at multipurpose room and distribution switchboard in boiler room					20	1995	2020	\$40,458.15	\$44,503.97
Total:												\$314,817.97	

Executive Summary

Building condition is evaluated based on the functional systems and elements of a building and organized according to the UNIFORMAT II Elemental Classification. The grouping of these systems and elements and applying a current replacement value to them develops a representative building cost model. Cost Models are developed for similar building types and functions. Systems and their elements are evaluated based on their current replacement values, life cycles, installation dates and next renewal dates. Systems and their elements that are within their useful lives are further evaluated to identify current deficient conditions that may have a significant impact on a system's or element's remaining service life, and to determine if they are beyond their predicted expected life. The system's or element's current replacement value is based on RS Means Commercial Cost Data.

Following are the cost model's system details for this facility. The Replacement Value is the amount needed to replace the property of the same present value. The Current Repair Amount, also known as Condition Needs, represents the budgeted contractor installed costs plus owner's soft costs for the repair, replacement or renewal for a component or system level deficiency. It excludes contributing costs for other components or systems that might also be associated with the corrective actions due to packaging the work. Facility Condition Index (FCI) FCI is an industry-standard measurement of facility condition calculated as the ratio of the costs to correct a facility's deficiencies to the facility's Current Replacement Value. It ranges from 0% (new) to 100% (very poor). Condition Index (CI) is calculated as the sum of a renewable system's Remaining Service Life (RSL) divided by the sum of a system's Replacement Value (both values exclude soft-cost to simplify calculation updates) expressed as a percentage ranging from 100% (new) to 0% (expired).

Function:	
Gross Area (SF):	120,200
Year Built:	1925
Last Renovation:	
Replacement Value:	\$2,405,978
Repair Cost:	\$448,773.29
Total FCI:	18.65 %
Total RSLI:	37.71 %



Description:

Attributes:

General Attributes:

Bldg ID:	S720001	Site ID:	S720001
----------	---------	----------	---------

Condition Summary

The Table below shows the CI and FCI for each major building system shown at the UNIFORMAT classification Level II. Note that Systems with lower FCIs require less investment than systems with higher FCIs.

UNIFORMAT Classification	RSLI %	FCI %	Current Repair Cost
G20 - Site Improvements	39.69 %	23.83 %	\$448,773.29
G40 - Site Electrical Utilities	30.59 %	0.00 %	\$0.00
Totals:	37.71 %	18.65 %	\$448,773.29

Condition Detail

This section of the report contains results of the Facility Condition Assessment. The building is separated into system components based on UNIFORMAT II classification. The columns in the System Listing table below represent the following:

1. System Code: A code that identifies the system.
2. System Description: A brief description of a system present in the building.
3. Unit Price \$: The unit price of the system.
4. UoM: The unit of measure for of the system.
5. Qty: The quantity for the system
6. Life: anticipated service life for the system based on Building Owners and Managers Association (BOMA) recommendations.
7. Year Installed: The date of system installation.
8. Calc Next Renewal Year: The date of system expiration based on the life, NR stands for non renewable.
9. Next Renewal Year: The suggested system expiration date by the assessor based on visual inspection.
10. CI: The Condition Index of the system.
11. FCI: The Facility Condition Index of the system.
12. RSL: Remaining Service Life.
13. eCR: eCOMET Condition Rating (not used).
14. Deficiency \$: The financial investment to repair/replace system.

System Listing

The System Listing table below lists each of the systems organized by their UNIFORMAT II classification. The assessment team was tasked with recording the most recent replacement year of each system, determining the remaining service life based on the theoretical life, and evaluating the condition to confirm the forecast next replacement year. The system listing is the basis for all data contained in the Building Assessment Report.

Additionally, a condition rating (eCR) based on the following guidelines is provided as observed at the time of the assessment.

- Excellent (E) - No noticeable distress or damage. The entire system is free from observable defect.
- Very Good (VG) - Overall no serviceability reduction for the entire system. No degradation of critical components and minor distress and defect noticeable for some but not non critical components within the system.
- Good (G) - Slight or no serviceability reduction for the entire system. There may be noticeable defects for some non critical components and slight noticeable degradation of the critical components.
- Fair (F) - Overall serviceability is degraded but adequate. There may be moderate deterioration for very few of the critical components and few of the non critical components may have severe degradation.
- Marginal (MA) - Overall serviceability and reliability loss. Most if not all of the non critical components suffer from severe degradation and a few of the critical component may have severe degradation.
- Moderate (MO) - Overall a significant serviceability loss. Most if not all the components have severe degradation with the reminder of the component showing visible distress.
- Very Poor (VP) - Overall the system is barely functional. All of the components are severely degraded.
- Non-Functional (NF) - Overall the system does not function with all the components having no serviceability and suffer from severe degradation.

System Code	System Description	Unit Price \$	UoM	Qty	Life	Year Installed	Calc Next Renewal Year	Next Renewal Year	RSLI%	FCI%	RSL	eCR	Deficiency \$	Replacement Value \$
G2010	Roadways	\$11.52	S.F.	0	30	1980	2010	2027	40.00 %	0.00 %	12			\$0
G2020	Parking Lots	\$7.65	S.F.	20,000	30	1980	2010	2020	16.67 %	99.60 %	5		\$152,382.57	\$153,000
G2030	Pedestrian Paving	\$11.52	S.F.	102,000	40	1980	2020	2027	30.00 %	10.89 %	12		\$128,012.04	\$1,175,040
G2040	Site Development	\$4.36	S.F.	120,200	25	1980	2005	2027	48.00 %	32.13 %	12		\$168,378.68	\$524,072
G2050	Landscaping & Irrigation	\$3.78	S.F.	8,200	15	1980	1995	2072	380.00 %	0.00 %	57			\$30,996
G4020	Site Lighting	\$3.58	S.F.	120,200	30	1980	2010	2024	30.00 %	0.00 %	9			\$430,316
G4030	Site Communications & Security	\$0.77	S.F.	120,200	30	1980	2010	2025	33.33 %	0.00 %	10			\$92,554
Total									37.71 %	18.65 %			\$448,773.29	\$2,405,978

System Notes

The facility description in the site executive summary contains an overview of each system. The notes listed below provide additional information on select systems found within the facility.

No data found for this asset

Renewal Schedule

eCOMET forecasts future Capital Renewal funding needed to address expiring systems based on the Next Renewal year found in the Cost Models. A 3% annual inflation factor is applied to the costs for systems expiring in future years. The table below reflects recommended Capital Renewal funding needs over the next 10 years. Note: Cells with a zero value indicate systems for which renewal is not scheduled in that year.


Inflation Rate: 3%

System	Current Deficiencies	2016	2017	2018	2019	2020	2021	2022	2023	2024	2025	Total
Total:	\$448,773	\$0	\$0	\$0	\$0	\$195,106	\$0	\$0	\$0	\$617,612	\$136,823	\$1,398,314
G - Building Sitework	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G20 - Site Improvements	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G2010 - Roadways	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G2020 - Parking Lots	\$152,383	\$0	\$0	\$0	\$0	\$195,106	\$0	\$0	\$0	\$0	\$0	\$347,488
G2030 - Pedestrian Paving	\$128,012	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$128,012
G2040 - Site Development	\$168,379	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$168,379
G2050 - Landscaping & Irrigation	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G40 - Site Electrical Utilities	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G4020 - Site Lighting	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$617,612	\$0	\$617,612
G4030 - Site Communications & Security	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$136,823	\$136,823

* Indicates non-renewable system

Forecasted Sustainment Requirement

The following chart shows the current building deficiencies and forecasting sustainment requirements over the next ten years.




10 Year FCI Forecast by Investment Scenario

The chart below illustrates the effect of various investment levels on the building FCI for the next 10 years. The levels of investment shown below include:

- Current FCI: a variable investment amount based on renewing expired systems to maintain the current FCI for the building
- 2% Investment: an annual investment of 2% of the replacement value of the building, escalated for inflation
- 4% Investment: an annual investment of 4% of the replacement value of the building, escalated for inflation


Facility Investment vs. FCI Forecast



Year	Investment Amount Current FCI - 18.65%	2% Investment		4% Investment	
		Amount	FCI	Amount	FCI
2016	\$0	\$49,563.00	16.65 %	\$99,126.00	14.65 %
2017	\$0	\$51,050.00	14.65 %	\$102,100.00	10.65 %
2018	\$0	\$52,582.00	12.65 %	\$105,163.00	6.65 %
2019	\$0	\$54,159.00	10.65 %	\$108,318.00	2.65 %
2020	\$195,106	\$55,784.00	15.65 %	\$111,568.00	5.65 %
2021	\$0	\$57,457.00	13.65 %	\$114,915.00	1.65 %
2022	\$0	\$59,181.00	11.65 %	\$118,362.00	-2.35 %
2023	\$0	\$60,956.00	9.65 %	\$121,913.00	-6.35 %
2024	\$617,612	\$62,785.00	27.32 %	\$125,570.00	9.32 %
2025	\$136,823	\$64,669.00	29.55 %	\$129,337.00	9.55 %
Total:	\$949,540	\$568,186.00		\$1,136,372.00	


Deficiency Summary by System

Current deficiencies included assemblies that have reached or exceeded their design life or components of the assemblies that are in need of repair. Assemblies that have reached their design life are identified as current deficiencies and assigned the distress 'Beyond Useful Life'. The following chart lists all current deficiencies associated with this facility.



Deficiency Summary by Priority

The following chart shows the total repair costs broken down by priority. Assessors assigned deficiencies within eCOMET to one of the following priority categories:



Budget Estimate Total: \$448,773.29


Deficiency By Priority Investment Table

The table below shows the current investment cost grouped by deficiency priority and building system.

System Code	System Description	1 - Response Time (< 2 yr)	2 - Response Time (2-3 yrs)	3 - Response Time (3-4 yrs)	4 - Response Time (4-5 yrs)	5 - Response Time (> 5 yrs)	Total
G2020	Parking Lots	\$0.00	\$0.00	\$152,382.57	\$0.00	\$0.00	\$152,382.57
G2030	Pedestrian Paving	\$0.00	\$128,012.04	\$0.00	\$0.00	\$0.00	\$128,012.04
G2040	Site Development	\$0.00	\$0.00	\$0.00	\$168,378.68	\$0.00	\$168,378.68
	Total:	\$0.00	\$128,012.04	\$152,382.57	\$168,378.68	\$0.00	\$448,773.29

Deficiency Summary by Category

The following chart shows the total repair costs broken down by deficiency categories. Assessors assigned deficiencies to one of the following categories:



Budget Estimate Total: \$448,773.29

Deficiency Details by Priority

The deficiency detail notes listed below provide additional information on identified deficiencies found within the facility.

Priority 2 - Response Time (2-3 yrs):

System: G2030 - Pedestrian Paving

This deficiency has no image.

Location: exterior - location to be determined

Distress: Building / MEP Codes

Category: 2 - Code Compliance

Priority: 2 - Response Time (2-3 yrs)

Correction: Install an exterior ADA ramp - based on 5' wide by the linear foot - up to 84" rise - per LF of ramp - figure 1 LF of ramp per inch of rise

Qty: 48.00

Unit of Measure: L.F.

Estimate: \$113,629.19

Assessor Name: Craig Anding

Date Created: 08/07/2015

Notes: add handicap accessible ramp into building

System: G2030 - Pedestrian Paving



Location: concrete play area

Distress: Failing

Category: 3 - Operations / Maint.

Priority: 2 - Response Time (2-3 yrs)

Correction: Remove and replace concrete sidewalk or concrete paving - 4" concrete thickness

Qty: 1,000.00

Unit of Measure: S.F.

Estimate: \$14,382.85

Assessor Name: Craig Anding

Date Created: 07/30/2015

Notes: Repave concrete panels in playground area and entrance area

Priority 3 - Response Time (3-4 yrs):

System: G2020 - Parking Lots



Location: parking lot

Distress: Beyond Service Life

Category: 3 - Operations / Maint.

Priority: 3 - Response Time (3-4 yrs)

Correction: Resurface parking lot - grind and resurface including striping

Qty: 40,000.00

Unit of Measure: S.F.

Estimate: \$152,382.57

Assessor Name: Craig Anding

Date Created: 07/30/2015

Notes: Repave asphalt parking student staging/play area – only area utilized by staff

Priority 4 - Response Time (4-5 yrs):

System: G2040 - Site Development



Location: edge of property

Distress: Beyond Service Life

Category: 3 - Operations / Maint.

Priority: 4 - Response Time (4-5 yrs)

Correction: Remove and replace metal picket fence - input number of gates

Qty: 1,000.00

Unit of Measure: L.F.

Estimate: \$168,378.68

Assessor Name: Craig Anding

Date Created: 07/30/2015

Notes: Replace damaged areas of wrought iron fencing

Equipment Inventory

The following table represents the inventory details of the inventory found in the building, which fall under the following subsystems:

No data found for this asset

Glossary

ABMA	American Boiler Manufacturers Association http://www.abma.com/
ACEEE	American Council for an Energy-Efficient Economy
ACGIH	American Council of Governmental and Industrial Hygienists
AEE	Association of Energy Engineers
AFD	Adjustable Frequency Drive
AFTC	After Tax Cash Flow
AGA	American Gas Association
AHU	Air Handling Unit
Amp	Ampere
ANSI	American National Standards Institute
ARI	Air Conditioning and Refrigeration Institute
ASD	Adjustable Speed Drive
ASHRAE	American Society of Heating Refrigerating and Air-Conditioning Engineers Inc.
ASME	American Society of Mechanical Engineers
Assessment	Visual survey of a facility to determine its condition. It involves looking at the age of systems reviewing information from local sources and visual evidence of potential problems to assign a condition rating. It does not include destructive testing of materials or testing of systems or equipment for functionality.
ATS	After Tax Savings
AW	Annual worth
BACNET	Building Automation Control Network
BAS	Building Automation System
BCR	Benefit Cost Ratio
BEP	Business Energy Professional (AEE)
BF	Ballast Factor
BHP	Boiler Horsepower (boilers)
BHP	Brake Horsepower (motors)
BLCC	Building Life Cycle Cost analysis program (FEMP)
BOCA	Building Officials and Code Administrators
BTCF	Before Tax Cash Flow

Site Assessment Report - S720001;Barton

BTS	Before Tax Savings
Btu	British thermal unit
Building Addition	An area space or component of a building added to a building after the original building's year built date.
CAA	Clean Air Act
CAAA-90	Clean Air Act Amendments of 1990
CABO	Council of American Building Officials
CAC	Conventional Air Conditioning
CADDET	Center for the Analysis and Dissemination of Demonstrated Energy Technologies
Calculated Next Renewal	The year a system or element would be expected to expire based solely on the date it was installed and the expected useful lifetime for that kind of system.
Capital Renewal	Capital renewal is condition work (excluding suitability and energy audit work) that includes the replacement of building systems or elements (as they become obsolete or beyond their useful life) not normally included in an annual operating budget. Calculated next renewal The year a system or element would be expected to expire based solely on the date it was installed and the expected useful lifetime for that kind of system. Next renewal The assessor adjusted expected useful life of a system or element based on on-site inspection.
CDD	Cooling Degree Days
CDGP	Certified Distributed Generation Professional
CEC	California Energy Commission
CEM	Certified Energy Manager
CEP	Certified Energy Procurement Professional
CFC	Chlorofluorocarbon
CFD	Cash Flow Diagram
CFL	Compact Fluorescent Light
CFM cfm	Cubic Feet per Minute
CHP	Combined Heat and Power (a.k.a. cogeneration)
CHW	Chilled Water
Condition	Condition refers to the state of physical fitness or readiness of a facility system or system element for its intended use.
COP	Coefficient of Performance
Cp	Heat Capacity of Material
CPUC	California Public Utility Commission
CRI	Color Rendering Index
CRT	Cathode Ray Tube VDT HMI

Site Assessment Report - S720001;Barton

CTC	Competitive Transition Charge
Cu	Coefficient of Utilization
Current Replacement Value (CRV)	CRV represents the hypothetical total cost of rebuilding or replacing an existing facility in current dollars to its optimal condition (excluding auxiliary facilities) under current codes and construction standards.
Cv	Value Coefficient
CWS	Chilled Water System
D d	Distance (usually feet)
DB	Dry Bulb
DCV	Demand Control Ventilation
DD	Degree Day
DDB	Double Declining Balance
DDC	Direct Digital Controls
Deferred maintenance	Deferred maintenance is condition work (excluding suitability and energy audit needs) deferred on a planned or unplanned basis to a future budget cycle or postponed until funds are available.
Deficiency	A deficiency is a repair item that is damaged missing inadequate or insufficient for an intended purpose.
Delta	Difference
Delta P	Pressure Difference
Delta T	Temperature Difference
DG	Distributed Generation
DOE	Department of Energy
DP	Dew Point
DR	Demand Response
DX	Direct Expansion Air Conditioner
EA	Energy Audit
EBITDA	Earnings before Interest Taxes Depreciation and Amortization
ECI	Energy Cost Index
ECM	Energy Conservation Measure
ECO	Energy Conservation Opportunity
ECPA	Energy Conservation and Production Act
ECR	Energy Conservation Recommendation
ECS	Energy Control System

Site Assessment Report - S720001;Barton

EER	Energy Efficiency Ratio
EERE	Energy Efficiency and Renewable Energy division of US DOE
EIA	Energy Information Agency
EIS	Energy Information System
EMCS	Energy Management Computer System
EMO	Energy Management Opportunity
EMP	Energy Management Project
EMR	Energy Management Recommendation
EMS	Energy Management System
Energy Utilization Index (EUI)	EUI is the measure of total energy consumed in the cooling or heating of a building in a period expressed as British thermal unit (BTU) per (cooled or heated) gross square foot.
EO	Executive Order
EPA	Environmental Protection Agency
EPACT	Energy Policy Act of 1992
EPCA	Energy Production and Conservation Act of 1975
EPRI	Electric Power Research Institute
EREN	Efficiency and Renewable Energy (Division of USDOE)
ERV	Energy Recovery Ventilator
ESCO	Energy Service Company
ESPC	Energy Savings Performance Contract
EUI	Energy Use Index
EWG	Exempt Wholesale Generators
Extended Facility Condition Index (EFCI)	EFCI is calculated as the condition needs for the current year plus facility system renewal needs going out to a set time in the future divided by Current Replacement Value.
f	Frequency
F	Fahrenheit
Facility	A facility refers to site(s) building(s) or building addition(s) or combinations thereof that provide a particular service.
Facility Condition Assessment (FCA)	FCA is a process for evaluating the condition of buildings and facilities for programming and budgetary purposes through an on site inspection and evaluation process.
Facility Condition Index (FCI)	FCI is an industry-standard measurement of a facility's condition that is the ratio of the cost to correct a facility's deficiencies to the Current Replacement Value of the facilities. The higher the FCI the poorer the condition of a facility. After an FCI is established for all buildings within a portfolio a building's condition can be ranked relative to other buildings. The FCI may also represent the condition of a portfolio based on the cumulative FCIs of the portfolio's facilities.

Site Assessment Report - S720001;Barton

FC	Footcandle
FCA	Fuel Cost Adjustment
FEMIA	Federal Energy Management Improvement Act of 1988
FEMP	Federal Energy Management Program
FERC	Federal Energy Regulatory Commission
FESR	Fuel Energy Savings Ratio
FLA	Full Load Amps
FLF	Facility Load Factor (usually monthly)
FLRPM	Full Load Revolutions per Minute
FMS	Facility Management System
FPM fpm	Feet per Minute (velocity)
FSEC	Florida Solar Energy Center
Ft	Foot
GPM gpm	Gallons per Minute
GRI	Gas Research Institute
Gross Square Feet (GSF)	The size of the enclosed floor space of a building in square feet measured to the outside face of the enclosing wall.
GUI	Graphical User Interface
H h	Enthalpy Btu/lb
HCFC	Hydrochlorofluorocarbons
HDD	Heating Degree days
HFC	Hydrofluorocarbons
HHV	Higher Heating Value
HID	High Intensity Discharge (lamp)
HMI	Human Machine Interface
HMMI	Human Man Machine Interface
HO	High Output (lamp)
HP Hp hp	Horsepower
HPS	High Pressure Sodium (lamp)
HR	Humidity Ratio
Hr hr	Hour

Site Assessment Report - S720001;Barton

HRU	Heat Recovery Unit
HVAC	Heating Ventilation and Air-Conditioning
Hz	Hertz
I	Intensity (lumen output of lamp)
I i	Interest rate or Discount rate
IAQ	Indoor Air Quality
ICA	International Cogeneration Alliance
ICBO	International Conference of Buildings Officials
ICC	International Code Council
ICP	Institutional Conservation Program
IECC	International Energy Conservation Code
IEEE	Institute of Electrical and Electronic Engineers
IESNA	Illuminating Engineering Society of North America
Install year	The year a building or system was built or the most recent major renovation date (where a minimum of 70 of the system's Current Replacement Value (CRV) was replaced).
IRP	Integrated Resource Planning
IRR	Internal Rate of Return
ISO	Independent System Operator
ITA	Independent Tariff Administrator
k	Kilo multiple of thousands in SI system
K	Kelvins (color temperature of lamp)
K k	Thermal Conductivity of Material
KVA	Kilovolt Ampere
KVAR	Kilovolt Ampere Reactive
kW	kiloWatt
kWh	kiloWatt hour
L	Length (usually feet)
LCC	Life Cycle Costing
LDC	Local Distribution Company
LEED	Leadership in Energy and Environmental Design
LEED EB	LEED for Existing Buildings

Site Assessment Report - S720001;Barton

LEED NC	LEED for new construction
LF	Load Factor
LHV	Lower Heating Value
Life cycle	The period of time that a building or site system or element can be expected to adequately serve its intended function.
LPS	Low Pressure Sodium (lamp)
Lu	Lumen Output of a Lamp or Fixture
M	Mega multiple of millions in SI system
M&V	Measurement and Verification
MACRS	Modified Accelerated Cost Recovery System
MARR	Minimum Attractive Rate of Return
Mbtu	Thousand Btu
MCF	Thousand Cubic Feet (usually of gas)
MEC	Model Energy Code
Mm	Multiple of Thousands in I/P System
MMBtu	Million Btu
MMCS	Maintenance Management Computer System
MMI	Man Machine Interface
MMS	Maintenance Management System
MSE 2000	Management System for Energy 2000 (ANSI Georgia Tech Univ)
MW	MegaWatt
MWH MWh	MegaWatt hour
NAAQS	National Ambient Air Quality Standards
NAESCO	National Association of Energy Service Companies
NAIMA	North American Insulation Manufacturers Association
NEA	National Energy Act of 1978
NECPA	National Energy Conservation Policy Act
NEMA	National Electrical Manufacturer's Association
NERC	North American Electric Reliability Council
Next Renewal	The Next Renewal date is an override of the 'Calculated Next Renewal' date and is based upon the assessor's visual inspection.

Site Assessment Report - S720001;Barton

NFPA	National Fire Protection Association
NGPA	National Gas Policy Act of 1978
NLRPM	No Load Revolutions per Minute (speed)
Nn	Equipment or Project lifetime in economic analysis
NOPR	Notice of Proposed Rule Making from FERC
NOx	Nitrogen Oxide Compounds
NPV	Net present value in economic analysis
NREL	National Renewable Energy Laboratory
NUG	Non-Utility Generator
O&M	Operation and Maintenance
OA	Outside Air
ODP	Ozone Depletion Potential
OPAC	Off-Peak Air Conditioning
P	Present value in economic analysis
PBR	Performance Based Rates
PEA	Preliminary Energy Audit
PF	Power Factor
PID	Proportional plus integral plus derivative (control system)
PM	Portfolio Manager in Energy Star rating system
PM	Preventive Maintenance
PoolCo	Power Pool Company or Organization
POU	Point of Use
PQ	Power Quality
PSC	Public Service Commission
PSIA psia	Pounds per square inch absolute (pressure)
PSIG psig	Pounds per square inch gauge (pressure)
PUC	Public Utility Commission
PUHCA	Public Utilities Holding Company Act of 1935
PURPA	Public Utilities Regulatory Policies of 1978
PV	Photovoltaic system

Site Assessment Report - S720001;Barton

PV	Present Value
PW	Present Worth
PX	Power Exchange
q	Rate of heat flow in Btu per hour
Q	Heat load due to conduction using degree days
QF	Qualifying Facility
R	Electrical resistance
R	Thermal Resistance
RC	Remote controller
RCR	Room Cavity Ratio
RCRA	Resource Conservation and Recovery Act
Remaining Service Life (RSL)	RSL is the number of years service remaining for a system or equipment item. It is automatically calculated based on the difference between the current year and the 'Calculated Next Renewal' date or the 'Next Renewal' date whichever one is the later date.
Remaining Service Life Index (RSLI)	RSLI is defined as a percentage ratio of the remaining service life of a system. It usually ranges from 0 to 100
REMR	Repair Evaluation Maintenance Rehabilitation (REMR) is a scale used to objectively rank systems based on their condition
Renewal Schedule	A timeline that provides the items that need repair the year in which the repair is needed and the estimated price of the renewal.
RH	Relative Humidity
RLA	Running Load Amps
RMS	Root Mean Square
RO	Reverse Osmosis
ROI	Return on Investment
RPM	Revolutions Per Minute
RTG	Regional Transmission Group
RTO	Regional Transmission Organization
RTP	Real Time Pricing
SBCCI	Southern Building Code Congress International
SC	Scheduling Coordinator
SC	Shading Coefficient
SCADA	Supervisory Control and Data Acquisition Systems

Site Assessment Report - S720001;Barton

SEER	Seasonal Energy Efficiency Ratio
SHR	Sensible Heat Ratio
Site	The grounds and utilities roadways landscaping fencing and other typical land improvements needed to support the facility.
Soft Cost	An expense item that is not considered direct construction cost. Soft cost includes architectural engineering financing legal fees and other pre-and-post construction expenses.
SOx	Sulfur Oxide Compounds
SP	Static Pressure
SP SPB	Simple Payback
SPP	Simple Payback Period
SPP	Small Power Producers
STR	Stack Temperature Rise
SV	Specific Volume
System	System refers to building and related site work elements as described by ASTM Uniformat II Classification for Building Elements (E1557-97) a format for classifying major facility elements common to most buildings. Elements usually perform a given function regardless of the design specification construction method or materials used. See also Uniformat II.
T	Temperature
T	Tubular (lamps)
TAA	Technical Assistance Audit
TCP/IP	Transmission Control Protocol/Internet Protocol
TES	Thermal Energy Storage
THD	Total Harmonic Distortion
TOD	Time of Day
TOU	Time of Use
TQM	Total Quality Management
TransCo	Transmission Company
U	Thermal Conductance
UDC	Utility Distribution Company
UL	Underwriters Laboratories
UNIFORMAT II	The ASTM UNIFORMAT II Classification for Building Elements (E1557-97) a format for classifying major facility components common to most buildings.
USGBC	US Green Building Council
v	Specific Volume

Site Assessment Report - S720001;Barton

V	Volts Voltage
V	Volume
VAV	Variable Air Volume
VDT	Video Display Terminal
VFD	Variable Frequency Drive
VHO	Very High Output
VSD	Variable Speed Drive
W	Watts
W	Width
WB	Wet bulb
WH Wh	Watt Hours
Year built	The year that a building or addition was originally built based on substantial completion or occupancy.
Z	Electrical Impedance