

## Facility Condition Assessment Summary Report

This report provides a summary of the Facility Condition Index (FCI) value of a school facility and select major building systems. The FCI calculation represents the cost of needed repairs divided by the replacement value. The FCI is a numerical value of condition and helps to identify the need for renewal or replacement of specific parts of the facility. The FCI is particularly useful when comparing similar facilities within the same portfolio.

### Childs (Barratt) School

Governance	DISTRICT	Report Type	Elementarymiddle
Address	1599 Wharton St. Philadelphia, Pa 19146	Enrollment	559
Phone/Fax	215-952-6213 / 215-952-6443	Grade Range	'00-08'
Website	Www.Philasd.Org/Schools/Childs	Admissions Category	Neighborhood
		Turnaround Model	N/A

### Building/System FCI Tiers

Facility Condition Index (FCI) = $\frac{\text{Cost of Assessed Deficiencies}}{\text{Replacement Value}}$				
< 15%	15 to 25%	25 to 45%	45 to 60%	> 60%
Buildings				
Minimal Current Capital Funding Required	Refurbish Systems in building	Replace Systems in building.	Building should be considered for major renovation.	Building should be considered for closing/replacement.
Systems				
Perform routine maintenance on system	System requires minor repairs	System should be studied to determine repair vs. replacement.	System is nearing end of its life expectancy and should be considered for replacement	System should be replaced as part of the Capital Program

### Building and Grounds

	FCI	Repair Costs	Replacement Cost
<b>Overall</b>	<b>23.31%</b>	<b>\$18,626,228</b>	<b>\$79,890,392</b>
Building	22.98 %	\$18,204,240	\$79,230,602
Grounds	63.96 %	\$421,988	\$659,790

### Major Building Systems

Building System	System FCI	Repair Costs	Replacement Cost
<b>Roof</b> (Shows physical condition of roof)	16.70 %	\$321,599	\$1,926,270
<b>Exterior Walls</b> (Shows condition of the structural condition of the exterior facade)	00.00 %	\$0	\$6,728,140
<b>Windows</b> (Shows functionality of exterior windows)	53.75 %	\$1,766,150	\$3,285,680
<b>Exterior Doors</b> (Shows condition of exterior doors)	00.00 %	\$0	\$223,780
<b>Interior Doors</b> (Classroom doors)	00.00 %	\$0	\$550,740
<b>Interior Walls</b> (Paint and Finishes)	06.90 %	\$171,342	\$2,483,020
<b>Plumbing Fixtures</b>	04.22 %	\$86,336	\$2,044,840
<b>Boilers</b>	00.00 %	\$0	\$2,823,380
<b>Chillers/Cooling Towers</b>	60.19 %	\$2,228,631	\$3,702,420
<b>Radiators/Unit Ventilators/HVAC</b>	94.87 %	\$6,169,698	\$6,503,020
<b>Heating/Cooling Controls</b>	117.53 %	\$2,400,128	\$2,042,160
<b>Electrical Service and Distribution</b>	33.72 %	\$544,465	\$1,614,700
<b>Lighting</b>	01.19 %	\$68,630	\$5,771,380
<b>Communications and Security</b> (Cameras, Pa System and Fire Alarm)	06.49 %	\$140,280	\$2,161,420

Please note that some FCIs may be over 100% because there are times when replacing a building system requires that other building systems be upgraded to complete the installation. A FCI of 0.0% represents that there are no current deficiencies with the associated system.

School District of Philadelphia  
**S211001;Barratt**  
Final  
**Site Assessment Report**  
January 30, 2017



## Table of Contents

Site Executive Summary	4
Site Condition Summary	10
<b><u>B211001:Barratt</u></b>	12
Executive Summary	12
Condition Summary	13
Condition Detail	14
System Listing	15
System Notes	17
Renewal Schedule	18
Forecasted Sustainment Requirement	21
Condition Index Forecast by Investment Scenario	22
Deficiency Summary By System	23
Deficiency Summary By Priority	24
Deficiency By Priority Investment	25
Deficiency Summary By Category	26
Deficiency Details By Priority	27
Equipment Inventory Detail	42
<b><u>G211001:Grounds</u></b>	43
Executive Summary	43
Condition Summary	44
Condition Detail	45
System Listing	46
System Notes	47
Renewal Schedule	48
Forecasted Sustainment Requirement	49
Condition Index Forecast by Investment Scenario	50
Deficiency Summary By System	51
Deficiency Summary By Priority	52
Deficiency By Priority Investment	53

## Site Assessment Report

---

Deficiency Summary By Category	54
Deficiency Details By Priority	55
Equipment Inventory Detail	57
Glossary	58


## Site Executive Summary

The organization of this report, as displayed in the Table of Contents, follows the structure of the associated eCOMET database. The overall node for each school campus begins with the letter "S", which indicates the "Site" label. Each Site is comprised of separate "Building" and "Grounds" nodes; their asset names begin with the letters "B" and "G" respectively. Information rolls up to the Site node from the Building and Grounds nodes. This Site report combines facility information with subsections for the Buildings And Grounds nodes.

The basis for the evaluation of condition is the functional systems and elements of a building and grounds organized according to the UNIFORMAT II Elemental Classification. The grouping of these systems and elements and applying a current replacement value to them develops a representative building cost model. Cost Models are typically developed for similar building types and functions. Evaluation of systems and their elements takes into account their current replacement values, life cycles, installation dates and next renewal dates. Systems and their elements that are within their useful lives are further evaluated to identify current deficient conditions that may have a significant impact on a system's or element's remaining service life, and to determine if they are beyond their predicted expected life. The system's or element's current replacement value is based on RS Means Commercial Cost Data.

Following are the cost model's system details for this facility. The Replacement Value is the amount needed to replace the property of the same present value. The Current Repair Amount, also known as Condition Needs, represents the budgeted contractor installed costs plus owner's soft costs for the repair, replacement or renewal for a component or system level deficiency. It excludes contributing costs for other components or systems that might also be associated with the corrective actions due to packaging the work. Facility Condition Index (FCI) is an industry-standard measurement calculated as the ratio of the repair costs to correct a facility's deficiencies to the facility's Current Replacement Value. Condition Index (CI) for a system is calculated as the sum of the deficiencies divided by the sum of a system's Replacement Value (both values include soft-cost) expressed as a percentage ranging from 0% 100%.

Gross Area (SF):	134,000
Year Built:	1908
Last Renovation:	1926
Replacement Value:	\$79,890,392
Repair Cost:	\$18,626,227.61
Total FCI:	23.31 %
Total RSLI:	49.49 %



### Description:

Facility Assessment  
July 20th, 2015

School District of Philadelphia  
Barratt Middle School  
1599 Wharton Street  
Philadelphia, PA 19146

134,000 SF / 1,176 Students / LN 01

### GENERAL

Mr. Dave Loftus, Facility Area Coordinator, provided input to the Parsons Assessment Team on planned renovation/addition projects. Mr. Russel Amodei, Building Engineer accompanied us on our tour of the school and provided us with detailed information on the building systems and maintenance history.

The 5 story, 134,000 square foot building was originally constructed in 1908 with a large addition built in 1926. The



building has a multi-level basement and sub-basement.

### STRUCTURAL / EXTERIOR CLOSURE

The main building rests on concrete foundations and bearing walls that are showing slight signs of settlement damage with cracked concrete and exposed steel reinforcement. The main structure consists typically of cast-in-place concrete columns, beams and concrete, and one way ribbed slab in basement. The main roof structure consists of concrete one-way slab supported by main structural frame. Main roofing is built up application in fair condition with lightweight concrete on rooftop play yard area. Roofing on gyms are metal roofing on steel truss in fair condition and in need of repair or replacement. The building envelope is masonry with face brick. Elevations are enhanced minimally with stonework around entrances. In general, masonry is in good condition. All elevations are face brick. The original windows were replaced in early 1990s with extruded aluminum, double hung windows, Lexan Plexiglas with insect/security screens. All windows are generally in poor condition with heavy hazing. Exterior doors are hollow metal in good condition. Public access doors and service doors have concrete stoops and stairs. The building is accessible per ADA requirements.

Main building partition wall types include plastered ceramic hollow blocks. Interior doors are generally hollow metal frames with solid core wood doors with lites in good condition with lever type handles. Doors leading to exit stairways are hollow metal doors and frames in good condition. Fittings include: toilet accessories in good condition; composite plastic toilet partitions, in good condition and meeting ADA requirements; fixed metal wall lockers in corridors in good condition; and handrails and ornamental metals, in fair condition. Interior identifying signage is typically directly painted on wall or door surfaces in good condition. Main stair construction is concrete in good condition with tile risers on front entryway stairs. Utility stairs are metal in good condition. Stair railings are wall mounted metal railing in good condition.

Interior wall finishes include: painted plaster or brick with marble wainscot in stairways, corridors, and toilets and glazed brick tile wainscot in cafeteria, kitchen, gyms and basement classrooms; and wood panel wainscot in auditorium and balcony. Generally, paint is in good condition with some plaster deterioration in north side classrooms in need of repair. Marble, glazed brick, and wood panel wainscot is all in good condition. Flooring includes: patterned and bare concrete in corridors, stairways, toilets, and basement service areas in good condition with a few hollow and damaged areas; hardwood in most classrooms, auditorium, stage, and balcony in good condition; vinyl tile in some classrooms, cafeteria and office areas in good condition; tile in front entryway, main office hallway, and kitchen in very good condition; and rubber protection coated concrete in both gyms in good condition. Wood base in classrooms are typically in fair condition. Ceilings are suspended acoustic tile in classrooms, corridors, cafeteria, and offices in good condition with some damaged tiles; painted plaster and structural concrete in toilets, stairways, kitchen, auditorium and entryway generally in good condition with some repairs needed; and painted steel structure in gyms in fair condition with attached acoustic panels that are beyond service life.

The building has one elevator serving 4 stories and is ADA compliant.

Commercial and institutional equipment includes: stage equipment, generally in fair condition. Other equipment includes unused food preparation equipment and food service equipment (heat and serve only) in good condition.

Fixed furnishings include: fixed casework in classrooms, corridors and library, generally in fair to good condition; window shades/blinds, generally in fair condition; fixed cafeteria seating and tables in good condition; and fixed auditorium seating is original, generally in fair condition with some damaged and missing seats.

### MECHANICAL SYSTEMS

Building plumbing fixtures are a mixture of original and replacement. Restroom fixtures on each floor consist of wall hung water closets, urinals and lavatories. A few fixtures are out of order and need repair along with the third floor boy's toilet room. The fixtures should provide reliable service for the next 5-10 years.

Life skills classroom has stainless steel, single basin, rim mounted kitchen sinks with single lever control, mixing faucets. This room also has new washing machine hot and cold supply lines and drain connections, but there is no washing machine. The school cafeteria kitchen has a stainless steel, three basin, commercial, dish washing sink with chemical sanitization system, and also a lavatory. Kitchen sinks are in good condition and should be serviceable for 10-15 years.

## Site Assessment Report - S211001;Barratt

---

Fourth floor science room has a laboratory sink in fair condition with new supply piping and faucets. It is within its service life and will not need replacement before 10 years.

A service sink is available in the corridor on each floor for use by the janitorial staff. These are enamel on cast iron, floor standing, single basin sinks typical of 1920s construction. They have replacement faucets without vacuum breakers. They all appear in good condition with no signs of leakage and should last another 5-10 years without replacement.

Drinking fountains in the corridors are mostly wall hung, accessible, with integral refrigerated coolers. They are within their service life and will remain serviceable for 5-10 years. There still remain non-accessible fountains on the ground floor that should be replaced due to age.

A 3" city water service enters the building on the sub-basement level near the boiler room. The water meter and bypass line need double backflow prevention valves. There is a duplex booster pump with expansion tank. The domestic hot and cold water distribution piping is copper piping and soldered connections. The maintenance staff reports no significant problems with domestic piping and the supply is adequate to the fixtures. However, most domestic water piping is well beyond its service life and should be replaced to eliminate joints made with lead solder.

A 75 gallon vertical tank type, gas-fired water heater installed in 2012 supplies hot water for domestic use. The water heater is within its service life and should provide reliable service for the next 15-20 years. There is a circulation pump which was running at the time of inspection. The constant draft damper on the heater exhaust ducting has rusted through and fallen off. It should be replaced.

The sanitary sewer piping is threaded galvanized steel pipe. There is no sewage ejector. The housekeeping staff report problems with the sanitary waste piping systems backing up into lower level sinks during heavy rains.

Rain water drain pipes are threaded galvanized steel. These pipes are likely original to the building and apparently connect to the sanitary waste piping at some point based on statements from housekeeping workers. The combined system is likely running slowly due to chronic rust and debris clogging the inside of the piping. The district should hire a qualified contractor to examine the rain water discharge piping using video cameras to locate and replace any damaged piping and to further quantify the extent of potential failures. The roof does not have overflow drains.

The building is heated by a combination of steam radiators throughout the building and forced air heat to class rooms, gyms, auditorium, etc.

Steam is supplied by 3 Smith, model 4500A-22, cast iron, 5,994 MBH capacity boilers fired by Power Flame burners on gas or fuel oil. They were installed in 2001, are all operational, and will not need replacement for 20 years. Combustion air makeup is supplied by louvers equipped with automatic control. Condensate collects in a sump and pumps transfer it to the feed water storage tank with one feed water pump for each boiler and a fourth spare pump. The building engineer stated these were rebuilt within the past 12 months. There is a chemical treatment system for makeup water. The oil supply is stored in a 5,000 gallon storage tank installed in 2005. Two pumps located in the boiler room circulate oil through the system and were running at the time of inspection. The gas service enters the building in the boiler room and includes a booster. No problems were reported with steam traps.

The building does not have any central cooling systems. A 335 ton total capacity cooling system should be installed to provide cooling to the entire building and replace approximately 30 aged, inefficient window unit air conditioners.

Steam and condensate piping is steel with welded and threaded fittings. Steam mains from the basement level run up through the building to the terminal units and air handlers on all floors. They appear to be original to the building. The steam and condensate piping should be replaced due to age and visible rust.

Forced air is supplied to multiple parts of the building from 5 air handlers in the basement and sub-basement. These are original to the building. They included primary and secondary steam heat sections with air washers in between. Steam coils and fans are functional, but none of the air washers are operable. The engineer stated the steam coils work well and started one fan during the inspection. The fan started quickly and easily and it ran smoothly and quietly. Outside air intake and attic plenum return air are controlled independently by adjustable dampers at air handler inlets. Heated air is delivered through un-insulated sheet metal ducts to built-in structural clay tile ducts and various plenums and then to

class rooms and other large spaces. Room discharge air is conducted through similar ducts and plenums to the attic where it either returns to the air handlers or is discharged through multiple gravity vent hoods on the roof. These air handlers are obsolete, existing steam coils and fans are inefficient, they lack cooling and humidity control, and they should be replaced with new equipment. Un-insulated metal duct with manual controls should be replaced with insulated ducts and automatic digital controls.

Cast iron radiators supply heat for the entire building. They are original to the building and have pneumatic controlled steam valves. The radiators are well beyond their service life and should be replaced with finned tube unit heaters with electronic controls.

The kitchen has a gas burning stove with exhaust hood and fire extinguishing system. This system appears functional and will not need replacement within 10 years.

The original pneumatic systems have mostly failed according to the building engineer. Pneumatic room thermostats control steam flow valves on the radiators. Central duct dampers are manually adjustable only. The pneumatic systems are beyond their service life. These controls should be converted to DDC and automatically controllable dampers installed when metal ducts are replaced. A new building automation system (BAS) with modern DDC modules and communications network should be installed to serve the HVAC systems in this building to improve reliability and energy efficiency. An interface should be provided with the preferred system in use throughout the District.

The school building has stand pipes but it is not covered by an automatic sprinkler system. The stand pipes are of unknown age, but appear to be in good condition and should be inspected annually. A sprinkler system should be installed to improve life safety. An outdoor, engine driven, packaged fire pump should be installed if required based on the available city water.

### ELECTRICAL SYSTEMS

An underground lateral service from an overhead line on Latona Street to an indoor unit substation serves this building. The unit substation is composed of Penn Panel, 15KV, 600A Medium Voltage load interrupter switch, Olsun, dry type 750/1000KVA, 13.2KV- 120/208V step down transformer and General Electric 3000A, 120/208V distribution section. The unit substation is located in the basement electrical room. The unit substation was installed around 2001 and is expected to provide 26 more years of useful life. Since the HVAC electrical load will exceed the capacity of the existing electrical service. Provide a 1000KVA, 13.2KV- 480/277, indoor unit substation

The electrical distribution is obtained using 120/208V panel-boards located at each floor. Panel-boards are manufactured by Penn Panel and were installed in 2001 and are expected to provide 26 more years of useful life. Raceways are concealed in ceiling or wall spaces. There is a 150KVA phase converter to serve the three elevators.

Approximate 80% of the classrooms are provided with adequate quantity of receptacles. Provide approximate 12 classrooms with the teacher's whiteboard wall and the opposite of it with double compartment surface raceways, the other two walls with minimum two duplex outlets each, when feasible.

Most of the classrooms, offices are illuminated with surface mounted fluorescent fixtures, the corridors are illuminated with recessed mounted fluorescent fixtures. Fluorescent fixtures are provided with T-8 lamps. Fixtures are part of the 2001 project.

The fire alarm system is part of the 2001 project. The fire alarm control panel is manufactured by Simplex. The fire alarm system is composed of pull station at exit doors, and audio/visual devices at corridors, gymnasium and auditorium. Provide fire alarm audio/visual devices in each classroom

The present telephone system is adequate.

An independent and separate PA system does not exist. School uses the telephone systems for public announcement. This system is working adequately for most part.

The school is provided with battery operated, wireless, central clock system. The present bell system is working.



## Site Assessment Report - S211001;Barratt

---

There is not television system.

The security system consists of motion detectors at the first floor and principal's office. CCTV cameras are located at each corridor entrance.

The emergency power system consists of natural gas generator, manufactured by Onan rated 42KW 120/208V. The present emergency power system serves the corridor, exit signs, elevator cab lights, stair ways, fire tower, boiler and fire alarm panel and generator battery charger. Natural gas generator is part of the 2001 project and it is expected to provide 6 more years of useful service life. Generator does not have capacity to carry the elevator motors. Provide an outdoor diesel powered 150KW generator.

There is adequate UPS in the IT room.

The emergency lighting is obtained with dedicated fixtures connected to the emergency generator. Exit signs are located at each exit door and corridors and are connected to the school emergency system.

Lightning Protection System is accomplished with air terminals mounted on the chimney.

At the roof level repair/splice down conductor to maintain the electrical/mechanical continuity of the down conductor. A study should be conducted to determine if the air terminals provide the proper coverage.

The school has a three traction power elevators rated 25HP at 240V. Elevator controller and elevator motors are approximately 10 years old. They are expected to provide 10 more years of useful service life.

The school theatrical lighting and dimming control system is old and obsolete. Provide theatrical lighting and dimming control system.

The auditorium sound system is obtained with portable equipment. Provide a permanent sound system.

### GROUNDS SYSTEMS

The site surrounds the building on all four sides which is set back from the street. Yard area on west side is asphalt paving in good condition with some cracks and indications of a storm water drainage problem on the east edge. Parking for staff vehicles is on south side and accessible from Wharton St. Chain link fence surrounding and separating yard and parking area is in good condition. Landscaping covers about 5% of the site and is new and in good condition.

Accessibility: the building does have an accessible entrance, and accessible routes. Some toilets are equipped with accessible fixtures, partitions and accessories, such as grab bars and accessible partitions. Most doors in the building have ADA required door handles.

The school perimeter and parking lot is illuminated via wall mounted lighting fixtures. However there is not enough lighting. Provide 12 pole mounted lighting fixtures for security.

There are not CCTV cameras around the building perimeter. Provide a site video surveillance system.

Site Paging-There are wall mounted loud speaker facing the parking lot/playground area

### RECOMMENDATIONS

- Repair damaged structural columns and foundation walls in basement
- Repair or replace metal roofing on gym areas – damaged and leaking
- Replace Plexiglas windows – hazed
- Repair and repaint interior plaster walls on north side - water damaged
- Replace acoustic ceiling tiles – discolored/damaged/missing (5% of suspended ceiling area)
- Replace acoustic panels in gyms – beyond service life
- Replace auditorium seats – beyond service life and failing
- Address storm water drainage issue on east side of play yard

## Site Assessment Report - S211001;Barratt

---

- Repair out of service toilet room on 3<sup>rd</sup> floor and other inoperative plumbing fixtures throughout the building.
- Replace the aged drinking fountains in the basement with accessible models.
- Install backflow prevention valves on water meter and bypass lines.
- Repair constant draft damper on water heater exhaust duct.
- Replace the original copper domestic water piping to eliminate joints made with lead solder.
- Hire a qualified contractor to perform a detailed examination of the sanitary waste and rain water drainage piping using visual inspection and video cameras to determine cause of back-ups during heavy rains and replace any damaged or failing piping.
- Replace steam and condensate piping due to age and rust.
- Install 335 ton total capacity cooling system to replace aged and inefficient window unit air conditioners.
- Replace 5 existing obsolete air handlers including heating, cooling, humidification, and dehumidification.
- Replace the existing radiators with finned coil units.
- Replace the pneumatic controls for the HVAC systems with modern DDC modules, valves, and actuators to improve reliability and energy efficiency. Provide a new building automation system (BAS) with communication interface to the preferred system in use throughout the District.
- Install a fire protection sprinkler system with quick response type heads to reduce insurance costs by providing protection for the property. A packaged, outdoor, engine driven fire pump may be required depending on the available city water pressure.
- Provide 1000KVA 13.2KV-480/277V, indoor unit substation
- Provide (2) 25FT of surface raceways with receptacles at 24" on center and two-duplex wall mount receptacles. Approximate 12 classrooms
- Provide fire alarm audio/visual devices in each classroom. Approximate 60
- Generator does not have capacity to carry the elevator motors. Provide an outdoor diesel powered 150KW generator.
- Prepare a study to determine if the air terminals provide the proper coverage.
- Provide a state of the art theatrical lighting and dimming control system.
- Provide a permanent, state of the art auditorium sound system.
- Provide 12 pole-mounted lighting fixtures for security.
- Provide a site video surveillance system. Approximate 8 cameras

### Attributes:

#### General Attributes:

Active:	Open	Bldg Lot Tm:	Lot 1 / Tm 3
Status:	Accepted by SDP	Team:	Tm 3
Site ID:	S211001		

## Site Condition Summary

The Table below shows the CI and FCI for each major system shown at the UNIFORMAT classification Level II. Note that Systems with lower FCIs require less investment than systems with higher FCIs.


### Current Investment Requirement and Condition by Uniformat Classification

UNIFORMAT Classification	RSLI%	FCI %	Current Repair
A10 - Foundations	21.00 %	0.00 %	\$0.00
A20 - Basement Construction	21.00 %	0.30 %	\$6,831.97
B10 - Superstructure	21.00 %	0.00 %	\$0.00
B20 - Exterior Enclosure	27.51 %	17.25 %	\$1,766,150.43
B30 - Roofing	41.55 %	16.70 %	\$321,598.95
C10 - Interior Construction	32.21 %	0.00 %	\$0.00
C20 - Stairs	21.00 %	0.00 %	\$0.00
C30 - Interior Finishes	44.70 %	2.34 %	\$192,172.06
D10 - Conveying	31.43 %	0.00 %	\$0.00
D20 - Plumbing	48.31 %	40.28 %	\$1,220,811.51
D30 - HVAC	100.10 %	64.18 %	\$10,798,456.50
D40 - Fire Protection	96.03 %	157.55 %	\$1,916,928.39
D50 - Electrical	54.11 %	9.88 %	\$966,170.63
E10 - Equipment	49.37 %	13.47 %	\$293,594.70
E20 - Furnishings	40.00 %	248.13 %	\$721,524.41
G20 - Site Improvements	58.19 %	0.00 %	\$0.00
G40 - Site Electrical Utilities	106.67 %	222.80 %	\$421,988.06
<b>Totals:</b>	<b>49.49 %</b>	<b>23.31 %</b>	<b>\$18,626,227.61</b>

### Condition Deficiency Priority

Facility Name	Gross Area (S.F.)	FCI %	1 - Response Time (< 2 yr)	2 - Response Time (2-3 yrs)	3 - Response Time (3-4 yrs)	4 - Response Time (4-5 yrs)	5 - Response Time (> 5 yrs)
B211001;Barratt	134,000	22.98	\$80,900.55	\$1,602,194.82	\$3,634,518.53	\$6,945,970.32	\$5,940,655.33
G211001;Grounds	32,600	63.96	\$329,883.16	\$92,104.90	\$0.00	\$0.00	\$0.00
<b>Total:</b>		<b>23.31</b>	<b>\$410,783.71</b>	<b>\$1,694,299.72</b>	<b>\$3,634,518.53</b>	<b>\$6,945,970.32</b>	<b>\$5,940,655.33</b>

### Deficiencies By Priority



## Executive Summary

Building condition is evaluated based on the functional systems and elements of a building and organized according to the UNIFORMAT II Elemental Classification. The grouping of these systems and elements and applying a current replacement value to them develops a representative building cost model. Cost Models are developed for similar building types and functions. Systems and their elements are evaluated based on their current replacement values, life cycles, installation dates and next renewal dates. Systems and their elements that are within their useful lives are further evaluated to identify current deficient conditions that may have a significant impact on a system's or element's remaining service life, and to determine if they are beyond their predicted expected life. The system's or element's current replacement value is based on RS Means Commercial Cost Data.

Following are the cost model's system details for this facility. The Replacement Value is the amount needed to replace the property of the same present value. The Current Repair Amount, also known as Condition Needs, represents the budgeted contractor installed costs plus owner's soft costs for the repair, replacement or renewal for a component or system level deficiency. It excludes contributing costs for other components or systems that might also be associated with the corrective actions due to packaging the work. Facility Condition Index (FCI) FCI is an industry-standard measurement of facility condition calculated as the ratio of the costs to correct a facility's deficiencies to the facility's Current Replacement Value. It ranges from 0% (new) to 100% (very poor). Condition Index (CI) is calculated as the sum of a renewable system's Remaining Service Life (RSL) divided by the sum of a system's Replacement Value (both values exclude soft-cost to simplify calculation updates) expressed as a percentage ranging from 100% (new) to 0% (expired).

Function:	Middle School
Gross Area (SF):	134,000
Year Built:	1908
Last Renovation:	1926
Replacement Value:	\$79,230,602
Repair Cost:	\$18,204,239.55
Total FCI:	22.98 %
Total RSLI:	49.31 %

### Description:

### Attributes:

#### General Attributes:

Active:	Open	Bldg ID:	B211001
Sewage Ejector:	No	Status:	Accepted by SDP
Site ID:	S211001		



## Condition Summary

The Table below shows the CI and FCI for each major building system shown at the UNIFORMAT classification Level II. Note that Systems with lower FCIs require less investment than systems with higher FCIs.

UNIFORMAT Classification	RSI %	FCI %	Current Repair Cost
A10 - Foundations	21.00 %	0.00 %	\$0.00
A20 - Basement Construction	21.00 %	0.30 %	\$6,831.97
B10 - Superstructure	21.00 %	0.00 %	\$0.00
B20 - Exterior Enclosure	27.51 %	17.25 %	\$1,766,150.43
B30 - Roofing	41.55 %	16.70 %	\$321,598.95
C10 - Interior Construction	32.21 %	0.00 %	\$0.00
C20 - Stairs	21.00 %	0.00 %	\$0.00
C30 - Interior Finishes	44.70 %	2.34 %	\$192,172.06
D10 - Conveying	31.43 %	0.00 %	\$0.00
D20 - Plumbing	48.31 %	40.28 %	\$1,220,811.51
D30 - HVAC	100.10 %	64.18 %	\$10,798,456.50
D40 - Fire Protection	96.03 %	157.55 %	\$1,916,928.39
D50 - Electrical	54.11 %	9.88 %	\$966,170.63
E10 - Equipment	49.37 %	13.47 %	\$293,594.70
E20 - Furnishings	40.00 %	248.13 %	\$721,524.41
<b>Totals:</b>	<b>49.31 %</b>	<b>22.98 %</b>	<b>\$18,204,239.55</b>

## Condition Detail

This section of the report contains results of the Facility Condition Assessment. The building is separated into system components based on UNIFORMAT II classification. The columns in the System Listing table below represent the following:

1. System Code: A code that identifies the system.
2. System Description: A brief description of a system present in the building.
3. Unit Price \$: The unit price of the system.
4. UoM: The unit of measure for of the system.
5. Qty: The quantity for the system
6. Life: anticipated service life for the system based on Building Owners and Managers Association (BOMA) recommendations.
7. Year Installed: The date of system installation.
8. Calc Next Renewal Year: The date of system expiration based on the life, NR stands for non renewable.
9. Next Renewal Year: The suggested system expiration date by the assessor based on visual inspection.
10. CI: The Condition Index of the system.
11. FCI: The Facility Condition Index of the system.
12. RSL: Remaining Service Life.
13. eCR: eCOMET Condition Rating (not used).
14. Deficiency \$: The financial investment to repair/replace system.

## System Listing

The System Listing table below lists each of the systems organized by their UNIFORMAT II classification. The assessment team was tasked with recording the most recent replacement year of each system, determining the remaining service life based on the theoretical life, and evaluating the condition to confirm the forecast next replacement year. The system listing is the basis for all data contained in the Building Assessment Report.

Additionally, a condition rating (eCR) based on the following guidelines is provided as observed at the time of the assessment.

- Excellent (E) - No noticeable distress or damage. The entire system is free from observable defect.
- Very Good (VG) - Overall no serviceability reduction for the entire system. No degradation of critical components and minor distress and defect noticeable for some but not non critical components within the system.
- Good (G) - Slight or no serviceability reduction for the entire system. There may be noticeable defects for some non critical components and slight noticeable degradation of the critical components.
- Fair (F) - Overall serviceability is degraded but adequate. There may be moderate deterioration for very few of the critical components and few of the non critical components may have severe degradation.
- Marginal (MA) - Overall serviceability and reliability loss. Most if not all of the non critical components suffer from severe degradation and a few of the critical component may have severe degradation.
- Moderate (MO) - Overall a significant serviceability loss. Most if not all the components have severe degradation with the reminder of the component showing visible distress.
- Very Poor (VP) - Overall the system is barely functional. All of the components are severely degraded.
- Non-Functional (NF) - Overall the system does not function with all the components having no serviceability and suffer from severe degradation.

System Code	System Description	Unit Price \$	UoM	Qty	Life	Year Installed	Calc Next Renewal Year	Next Renewal Year	RSLI%	FCI%	RSL	eCR	Deficiency \$	Replacement Value \$
A1010	Standard Foundations	\$27.05	S.F.	134,000	100	1926	2026	2036	21.00 %	0.00 %	21			\$3,624,700
A1030	Slab on Grade	\$6.04	S.F.	134,000	100	1926	2026	2036	21.00 %	0.00 %	21			\$809,360
A2010	Basement Excavation	\$5.09	S.F.	134,000	100	1926	2026	2036	21.00 %	0.00 %	21			\$682,060
A2020	Basement Walls	\$11.74	S.F.	134,000	100	1926	2026	2036	21.00 %	0.43 %	21		\$6,831.97	\$1,573,160
B1010	Floor Construction	\$98.06	S.F.	134,000	100	1926	2026	2036	21.00 %	0.00 %	21			\$13,140,040
B1020	Roof Construction	\$10.55	S.F.	134,000	100	1926	2026	2036	21.00 %	0.00 %	21			\$1,413,700
B2010	Exterior Walls	\$50.21	S.F.	134,000	100	1926	2026	2036	21.00 %	0.00 %	21			\$6,728,140
B2020	Exterior Windows	\$24.52	S.F.	134,000	40	1991	2031		40.00 %	53.75 %	16		\$1,766,150.43	\$3,285,680
B2030	Exterior Doors	\$1.67	S.F.	134,000	25	2000	2025		40.00 %	0.00 %	10			\$223,780
B3010105	Built-Up	\$43.61	S.F.	35,092	20	2000	2020		25.00 %	0.00 %	5			\$1,530,362
B3010130	Preformed Metal Roofing	\$62.63	S.F.	6,193	30	1980	2010	2047	106.67 %	82.91 %	32		\$321,598.95	\$387,868
B3020	Roof Openings	\$0.06	S.F.	134,000	30	2000	2030		50.00 %	0.00 %	15			\$8,040
C1010	Partitions	\$20.95	S.F.	134,000	100	1926	2026	2036	21.00 %	0.00 %	21			\$2,807,300
C1020	Interior Doors	\$4.11	S.F.	134,000	40	2000	2040		62.50 %	0.00 %	25			\$550,740
C1030	Fittings	\$3.64	S.F.	134,000	40	2000	2040		62.50 %	0.00 %	25			\$487,760
C2010	Stair Construction	\$1.63	S.F.	134,000	100	1926	2026	2036	21.00 %	0.00 %	21			\$218,420
C3010230	Paint & Covering	\$16.67	S.F.	134,000	10	2010	2020		50.00 %	7.67 %	5		\$171,341.52	\$2,233,780
C3010232	Wall Tile	\$1.86	S.F.	134,000	30	2000	2030		50.00 %	0.00 %	15			\$249,240

# Site Assessment Report - B211001;Barratt

System Code	System Description	Unit Price \$	UoM	Qty	Life	Year Installed	Calc Next Renewal Year	Next Renewal Year	RSLI%	FCI%	RSL	eCR	Deficiency \$	Replacement Value \$
C3020412	Terrazzo & Tile	\$88.36	S.F.	6,700	50	2000	2050		70.00 %	0.00 %	35			\$592,012
C3020413	Vinyl Flooring	\$11.33	S.F.	20,100	20	2000	2020		25.00 %	0.00 %	5			\$227,733
C3020414	Wood Flooring	\$26.07	S.F.	60,300	25	2000	2025		40.00 %	0.00 %	10			\$1,572,021
C3020415	Concrete Floor Finishes	\$1.14	S.F.	46,900	50	1980	2030		30.00 %	0.00 %	15			\$53,466
C3030	Ceiling Finishes	\$24.54	S.F.	134,000	25	2000	2025		40.00 %	0.63 %	10		\$20,830.54	\$3,288,360
D1010	Elevators and Lifts	\$1.61	S.F.	134,000	35	1991	2026		31.43 %	0.00 %	11			\$215,740
D2010	Plumbing Fixtures	\$15.26	S.F.	134,000	35	1927	1962	2022	20.00 %	4.22 %	7		\$86,336.34	\$2,044,840
D2020	Domestic Water Distribution	\$1.90	S.F.	134,000	25	1927	1952	2042	108.00 %	222.09 %	27		\$565,429.71	\$254,600
D2030	Sanitary Waste	\$2.85	S.F.	134,000	30	1927	1957	2047	106.67 %	149.00 %	32		\$569,045.46	\$381,900
D2040	Rain Water Drainage	\$2.61	S.F.	134,000	30	1927	1957	2047	106.67 %	0.00 %	32			\$349,740
D3020	Heat Generating Systems	\$21.07	S.F.	134,000	35	2001	2036		60.00 %	0.00 %	21			\$2,823,380
D3030	Cooling Generating Systems	\$27.63	S.F.	134,000	30			2047	106.67 %	60.19 %	32		\$2,228,630.61	\$3,702,420
D3040	Distribution Systems	\$48.53	S.F.	134,000	25	1927	1952	2042	108.00 %	94.87 %	27		\$6,169,698.30	\$6,503,020
D3050	Terminal & Package Units	\$13.09	S.F.	134,000	20	1927	1947	2037	110.00 %	0.00 %	22			\$1,754,060
D3060	Controls & Instrumentation	\$15.24	S.F.	134,000	20	1960	1980	2037	110.00 %	117.53 %	22		\$2,400,127.59	\$2,042,160
D4010	Sprinklers	\$7.94	S.F.	134,000	35			2052	105.71 %	180.17 %	37		\$1,916,928.39	\$1,063,960
D4020	Standpipes	\$1.14	S.F.	134,000	35	1927	1962	2025	28.57 %	0.00 %	10			\$152,760
D5010	Electrical Service/Distribution	\$12.05	S.F.	134,000	30	2001	2031		53.33 %	33.72 %	16		\$544,464.69	\$1,614,700
D5020	Lighting and Branch Wiring	\$43.07	S.F.	134,000	20	2001	2021		30.00 %	1.19 %	6		\$68,630.18	\$5,771,380
D5030	Communications and Security	\$16.13	S.F.	134,000	15	1927	1942	2032	113.33 %	6.49 %	17		\$140,279.57	\$2,161,420
D5090	Other Electrical Systems	\$1.76	S.F.	134,000	30	1927	1957	2047	106.67 %	90.23 %	32		\$212,796.19	\$235,840
E1020	Institutional Equipment	\$4.92	S.F.	134,000	35	1991	2026		31.43 %	44.53 %	11		\$293,594.70	\$659,280
E1090	Other Equipment	\$11.35	S.F.	134,000	35	2000	2035		57.14 %	0.00 %	20			\$1,520,900
E2010	Fixed Furnishings	\$2.17	S.F.	134,000	40	1991	2031		40.00 %	248.13 %	16		\$721,524.41	\$290,780
<b>Total</b>									<b>49.31 %</b>	<b>22.98 %</b>			<b>\$18,204,239.55</b>	<b>\$79,230,602</b>

## System Notes

The facility description in the site executive summary contains an overview of each system. The notes listed below provide additional information on select systems found within the facility.

<b>System:</b>	C3010 - Wall Finishes	This system contains no images
<b>Note:</b>	90% Paint & Cover 10% Wall Tile (glazed block)	
<b>System:</b>	C3020 - Floor Finishes	This system contains no images
<b>Note:</b>	5% - Terrazzo & Tile 15% - Vinyl Flooring 45% - Wood Flooring 35% - Concrete Floor Cover	
<b>System:</b>	D5010 - Electrical Service/Distribution	This system contains no images
<b>Note:</b>	1-150KVA 208V to 240V phase converter to feed the existing elevator motors.	



## Renewal Schedule

eCOMET forecasts future Capital Renewal funding needed to address expiring systems based on the Next Renewal year found in the Cost Models. A 3% annual inflation factor is applied to the costs for systems expiring in future years. The table below reflects recommended Capital Renewal funding needs over the next 10 years. Note: Cells with a zero value indicate systems for which renewal is not scheduled in that year.

*Inflation Rate: 3%*

System	Current Deficiencies	2016	2017	2018	2019	2020	2021	2022	2023	2024	2025	Total
<b>Total:</b>	<b>\$18,204,240</b>	<b>\$0</b>	<b>\$0</b>	<b>\$0</b>	<b>\$0</b>	<b>\$5,090,444</b>	<b>\$7,580,462</b>	<b>\$2,766,385</b>	<b>\$0</b>	<b>\$0</b>	<b>\$7,741,782</b>	<b>\$41,383,313</b>
<b>* A - Substructure</b>	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
<b>* A10 - Foundations</b>	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
A1010 - Standard Foundations	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
A1030 - Slab on Grade	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
<b>* A20 - Basement Construction</b>	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
A2010 - Basement Excavation	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
A2020 - Basement Walls	\$6,832	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$6,832
<b>B - Shell</b>	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
<b>B10 - Superstructure</b>	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B1010 - Floor Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B1020 - Roof Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
<b>B20 - Exterior Enclosure</b>	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B2010 - Exterior Walls	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B2020 - Exterior Windows	\$1,766,150	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$1,766,150
B2030 - Exterior Doors	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$330,816	\$330,816
<b>B30 - Roofing</b>	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3010 - Roof Coverings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3010105 - Built-Up	\$0	\$0	\$0	\$0	\$0	\$1,951,520	\$0	\$0	\$0	\$0	\$0	\$1,951,520
B3010130 - Preformed Metal Roofing	\$321,599	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$321,599
B3020 - Roof Openings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
<b>C - Interiors</b>	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
<b>C10 - Interior Construction</b>	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C1010 - Partitions	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C1020 - Interior Doors	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C1030 - Fittings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0

# Site Assessment Report - B211001;Barratt

C20 - Stairs	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C2010 - Stair Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C30 - Interior Finishes	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C3010 - Wall Finishes	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C3010230 - Paint & Covering	\$171,342	\$0	\$0	\$0	\$0	\$2,848,520	\$0	\$0	\$0	\$0	\$0	\$3,019,861
C3010232 - Wall Tile	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C3020 - Floor Finishes	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C3020412 - Terrazzo & Tile	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C3020413 - Vinyl Flooring	\$0	\$0	\$0	\$0	\$0	\$290,405	\$0	\$0	\$0	\$0	\$0	\$290,405
C3020414 - Wood Flooring	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$2,323,931	\$2,323,931
C3020415 - Concrete Floor Finishes	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C3030 - Ceiling Finishes	\$20,831	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$4,861,209	\$4,882,039
D - Services	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D10 - Conveying	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D1010 - Elevators and Lifts	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D20 - Plumbing	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D2010 - Plumbing Fixtures	\$86,336	\$0	\$0	\$0	\$0	\$0	\$0	\$2,766,385	\$0	\$0	\$0	\$2,852,721
D2020 - Domestic Water Distribution	\$565,430	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$565,430
D2030 - Sanitary Waste	\$569,045	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$569,045
D2040 - Rain Water Drainage	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D30 - HVAC	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D3020 - Heat Generating Systems	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D3030 - Cooling Generating Systems	\$2,228,631	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$2,228,631
D3040 - Distribution Systems	\$6,169,698	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$6,169,698
D3050 - Terminal & Package Units	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D3060 - Controls & Instrumentation	\$2,400,128	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$2,400,128
D40 - Fire Protection	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D4010 - Sprinklers	\$1,916,928	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$1,916,928
D4020 - Standpipes	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$225,826	\$225,826
D50 - Electrical	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5010 - Electrical Service/Distribution	\$544,465	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$544,465
D5020 - Lighting and Branch Wiring	\$68,630	\$0	\$0	\$0	\$0	\$0	\$7,580,462	\$0	\$0	\$0	\$0	\$7,649,093
D5030 - Communications and Security	\$140,280	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$140,280


## Site Assessment Report - B211001;Barratt

D5090 - Other Electrical Systems	\$212,796	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$212,796
E - Equipment & Furnishings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E10 - Equipment	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E1020 - Institutional Equipment	\$293,595	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$293,595
E1090 - Other Equipment	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E20 - Furnishings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E2010 - Fixed Furnishings	\$721,524	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$721,524

\* Indicates non-renewable system

Forecasted Sustainment Requirement

The following chart shows the current building deficiencies and forecasting sustainment requirements over the next ten years.




## 10 Year FCI Forecast by Investment Scenario

The chart below illustrates the effect of various investment levels on the building FCI for the next 10 years. The levels of investment shown below include:

- Current FCI: a variable investment amount based on renewing expired systems to maintain the current FCI for the building
- 2% Investment: an annual investment of 2% of the replacement value of the building, escalated for inflation
- 4% Investment: an annual investment of 4% of the replacement value of the building, escalated for inflation

**Facility Investment vs. FCI Forecast**




Year	Investment Amount Current FCI - 22.98%	2% Investment		4% Investment	
		Amount	FCI	Amount	FCI
2016	\$0	\$1,632,150.00	20.98 %	\$3,264,301.00	18.98 %
2017	\$21,982,576	\$1,681,115.00	45.13 %	\$3,362,230.00	41.13 %
2018	\$0	\$1,731,548.00	43.13 %	\$3,463,097.00	37.13 %
2019	\$0	\$1,783,495.00	41.13 %	\$3,566,990.00	33.13 %
2020	\$5,090,444	\$1,837,000.00	44.67 %	\$3,673,999.00	34.67 %
2021	\$7,580,462	\$1,892,110.00	50.68 %	\$3,784,219.00	38.68 %
2022	\$2,766,385	\$1,948,873.00	51.52 %	\$3,897,746.00	37.52 %
2023	\$0	\$2,007,339.00	49.52 %	\$4,014,678.00	33.52 %
2024	\$0	\$2,067,559.00	47.52 %	\$4,135,119.00	29.52 %
2025	\$7,741,782	\$2,129,586.00	52.79 %	\$4,259,172.00	32.79 %
<b>Total:</b>	<b>\$45,161,650</b>	<b>\$18,710,775.00</b>		<b>\$37,421,551.00</b>	



## Deficiency Summary by System


Current deficiencies included assemblies that have reached or exceeded their design life or components of the assemblies that are in need of repair. Assemblies that have reached their design life are identified as current deficiencies and assigned the distress 'Beyond Useful Life'. The following chart lists all current deficiencies associated with this facility.



**Budget Estimate Total: \$18,204,239.55**

## Deficiency Summary by Priority

The following chart shows the total repair costs broken down by priority. Assessors assigned deficiencies within eCOMET to one of the following priority categories:



**Budget Estimate Total: \$18,204,239.55**


## Deficiency By Priority Investment Table

The table below shows the current investment cost grouped by deficiency priority and building system.

System Code	System Description	1 - Response Time (< 2 yr)	2 - Response Time (2-3 yrs)	3 - Response Time (3-4 yrs)	4 - Response Time (4-5 yrs)	5 - Response Time (> 5 yrs)	Total
A2020	Basement Walls	\$0.00	\$0.00	\$6,831.97	\$0.00	\$0.00	\$6,831.97
B2020	Exterior Windows	\$0.00	\$0.00	\$0.00	\$1,766,150.43	\$0.00	\$1,766,150.43
B3010130	Preformed Metal Roofing	\$0.00	\$321,598.95	\$0.00	\$0.00	\$0.00	\$321,598.95
C3010230	Paint & Covering	\$0.00	\$0.00	\$171,341.52	\$0.00	\$0.00	\$171,341.52
C3030	Ceiling Finishes	\$0.00	\$20,830.54	\$0.00	\$0.00	\$0.00	\$20,830.54
D2010	Plumbing Fixtures	\$71,177.96	\$0.00	\$15,158.38	\$0.00	\$0.00	\$86,336.34
D2020	Domestic Water Distribution	\$9,722.59	\$0.00	\$0.00	\$0.00	\$555,707.12	\$565,429.71
D2030	Sanitary Waste	\$0.00	\$0.00	\$569,045.46	\$0.00	\$0.00	\$569,045.46
D3030	Cooling Generating Systems	\$0.00	\$0.00	\$0.00	\$0.00	\$2,228,630.61	\$2,228,630.61
D3040	Distribution Systems	\$0.00	\$0.00	\$2,872,141.20	\$141,239.50	\$3,156,317.60	\$6,169,698.30
D3060	Controls & Instrumentation	\$0.00	\$0.00	\$0.00	\$2,400,127.59	\$0.00	\$2,400,127.59
D4010	Sprinklers	\$0.00	\$0.00	\$0.00	\$1,916,928.39	\$0.00	\$1,916,928.39
D5010	Electrical Service/Distribution	\$0.00	\$544,464.69	\$0.00	\$0.00	\$0.00	\$544,464.69
D5020	Lighting and Branch Wiring	\$0.00	\$68,630.18	\$0.00	\$0.00	\$0.00	\$68,630.18
D5030	Communications and Security	\$0.00	\$140,279.57	\$0.00	\$0.00	\$0.00	\$140,279.57
D5090	Other Electrical Systems	\$0.00	\$212,796.19	\$0.00	\$0.00	\$0.00	\$212,796.19
E1020	Institutional Equipment	\$0.00	\$293,594.70	\$0.00	\$0.00	\$0.00	\$293,594.70
E2010	Fixed Furnishings	\$0.00	\$0.00	\$0.00	\$721,524.41	\$0.00	\$721,524.41
	<b>Total:</b>	\$80,900.55	\$1,602,194.82	\$3,634,518.53	\$6,945,970.32	\$5,940,655.33	\$18,204,239.55

## Deficiency Summary by Category

The following chart shows the total repair costs broken down by deficiency categories. Assessors assigned deficiencies to one of the following categories:




## Deficiency Details by Priority

The deficiency detail notes listed below provide additional information on identified deficiencies found within the facility.

### Priority 1 - Response Time (< 2 yr):

#### System: D2010 - Plumbing Fixtures



**Location:** Toilet rooms

**Distress:** Failing

**Category:** 3 - Operations / Maint.

**Priority:** 1 - Response Time (< 2 yr)

**Correction:** Remove and replace or replace water closet - quantify additional units

**Qty:** 10.00

**Unit of Measure:** Ea.

**Estimate:** \$71,177.96

**Assessor Name:** System

**Date Created:** 08/12/2015

**Notes:** Repair out of service toilet room on 3th floor and other inoperative plumbing fixtures throughout the building.

---

#### System: D2020 - Domestic Water Distribution

This deficiency has no image.

**Location:** Sub-basement

**Distress:** Building / MEP Codes

**Category:** 2 - Code Compliance

**Priority:** 1 - Response Time (< 2 yr)

**Correction:** Replace valves

**Qty:** 2.00

**Unit of Measure:** Ea.

**Estimate:** \$9,296.46

**Assessor Name:** System

**Date Created:** 08/12/2015

**Notes:** Install double back flow preventers on water meter and bypass lines.

---



**System: D2020 - Domestic Water Distribution**



**Location:** Boiler room

**Distress:** Damaged

**Category:** 3 - Operations / Maint.

**Priority:** 1 - Response Time (< 2 yr)

**Correction:** Repair water heater (enter estimate)

**Qty:** 1.00

**Unit of Measure:** Ea.

**Estimate:** \$426.13

**Assessor Name:** System

**Date Created:** 08/12/2015

**Notes:** Repair constant draft damper on water heater exhaust duct.

---

**Priority 2 - Response Time (2-3 yrs):**

**System: B3010130 - Preformed Metal Roofing**



**Location:** Gym roof

**Distress:** Failing

**Category:** 3 - Operations / Maint.

**Priority:** 2 - Response Time (2-3 yrs)

**Correction:** Remove and replace preformed metal roofing

**Qty:** 6,200.00

**Unit of Measure:** S.F.

**Estimate:** \$321,598.95

**Assessor Name:** System

**Date Created:** 08/31/2015

**Notes:** Repair or replace metal roofing on gym areas – damaged and leaking

---

**System: C3030 - Ceiling Finishes**



**Location:** Ceiling

**Distress:** Damaged

**Category:** 3 - Operations / Maint.

**Priority:** 2 - Response Time (2-3 yrs)

**Correction:** Remove and replace ceiling tiles only in suspended ceiling - pick the proper material

**Qty:** 2,700.00

**Unit of Measure:** S.F.

**Estimate:** \$20,830.54

**Assessor Name:** System

**Date Created:** 08/31/2015

**Notes:** Replace acoustic ceiling tiles – discolored/damaged/missing (5% of suspended ceiling area)

---

**System: D5010 - Electrical Service/Distribution**



**Location:** Basement- electrical room

**Distress:** Inadequate

**Category:** 4 - Capital Improvement

**Priority:** 2 - Response Time (2-3 yrs)

**Correction:** Add Electrical Switchgear and Distribution System

**Qty:** 1.00

**Unit of Measure:** Ea.

**Estimate:** \$544,464.69


**Assessor Name:** System

**Date Created:** 09/08/2015

**Notes:** Provide 1000KVA 13.2KV-480/277V, indoor unit substation

---

**System: D5020 - Lighting and Branch Wiring**



**Location:** Classrooms

**Distress:** Inadequate

**Category:** 4 - Capital Improvement

**Priority:** 2 - Response Time (2-3 yrs)

**Correction:** Add wiring device

**Qty:** 12.00

**Unit of Measure:** Ea.

**Estimate:** \$68,630.18

**Assessor Name:** System

**Date Created:** 08/07/2015

**Notes:** Provide (2)25FT of surface raceways with 24" receptacles on center and two-duplex wall mount receptacles. Approximate 12 classrooms

---

**System: D5030 - Communications and Security**



**Location:** Entire Building

**Distress:** Life Safety / NFPA / PFD

**Category:** 1 - Health & Safety

**Priority:** 2 - Response Time (2-3 yrs)

**Correction:** Add fire alarm device

**Qty:** 60.00

**Unit of Measure:** Ea.

**Estimate:** \$104,889.94

**Assessor Name:** System

**Date Created:** 08/07/2015

**Notes:** Provide fire alarm audio/visual devices in each classroom. Approximate 60

---

**System: D5030 - Communications and Security**



**Location:** Auditorium

**Distress:** Inadequate

**Category:** 4 - Capital Improvement

**Priority:** 2 - Response Time (2-3 yrs)

**Correction:** Add/Replace Sound System

**Qty:** 1.00

**Unit of Measure:** LS

**Estimate:** \$35,389.63

**Assessor Name:** System

**Date Created:** 08/07/2015

**Notes:** Provide a permanent, state of the art auditorium sound system.

---

**System: D5090 - Other Electrical Systems**



**Location:** Outdoor

**Distress:** Inadequate

**Category:** 4 - Capital Improvement

**Priority:** 2 - Response Time (2-3 yrs)

**Correction:** Replace standby generator system

**Qty:** 1.00

**Unit of Measure:** Ea.

**Estimate:** \$188,546.37

**Assessor Name:** System

**Date Created:** 08/07/2015

**Notes:** Generator does not have capacity to carry the elevator motors. Provide an outdoor diesel powered 150KW generator.

---

**System: D5090 - Other Electrical Systems**



**Location:** Roof

**Distress:** Building / MEP Codes

**Category:** 2 - Code Compliance

**Priority:** 2 - Response Time (2-3 yrs)

**Correction:** Repair Lightning Protection System

**Qty:** 1.00

**Unit of Measure:** Job

**Estimate:** \$24,249.82

**Assessor Name:** System

**Date Created:** 08/07/2015

**Notes:** Prepare a study to determine if the air terminals provide the proper coverage

---

**System: E1020 - Institutional Equipment**



**Location:** Auditorium

**Distress:** Beyond Service Life

**Category:** 3 - Operations / Maint.

**Priority:** 2 - Response Time (2-3 yrs)

**Correction:** Add/Replace Stage Theatrical Lighting System

**Qty:** 1.00

**Unit of Measure:** Ea.

**Estimate:** \$293,594.70

**Assessor Name:** System

**Date Created:** 08/07/2015

**Notes:** Provide a state of the art theatrical lighting and dimming control system

---

**Priority 3 - Response Time (3-4 yrs):**

**System: A2020 - Basement Walls**



**Location:** Basement

**Distress:** Damaged

**Category:** 3 - Operations / Maint.

**Priority:** 3 - Response Time (3-4 yrs)

**Correction:** Repair spalled concrete - pick the appropriate repair and insert the SF of wall area

**Qty:** 50.00

**Unit of Measure:** S.F.

**Estimate:** \$6,831.97

**Assessor Name:** System

**Date Created:** 08/31/2015

**Notes:** Repair damaged structural columns and foundation walls in basement

---

**System: C3010230 - Paint & Covering**



**Location:** North side classrooms

**Distress:** Damaged

**Category:** 3 - Operations / Maint.

**Priority:** 3 - Response Time (3-4 yrs)

**Correction:** Repair substrate and repaint interior walls - SF of wall surface

**Qty:** 20,000.00

**Unit of Measure:** S.F.

**Estimate:** \$171,341.52

**Assessor Name:** System

**Date Created:** 08/31/2015

**Notes:** Repair and repaint interior plaster walls on north side – water damaged

---



**System: D2010 - Plumbing Fixtures**



**Location:** Basement

**Distress:** Accessibility

**Category:** 2 - Code Compliance

**Priority:** 3 - Response Time (3-4 yrs)

**Correction:** Remove and Replace Water Fountains - without ADA new recessed alcove

**Qty:** 2.00

**Unit of Measure:** Ea.

**Estimate:** \$15,158.38

**Assessor Name:** System

**Date Created:** 08/12/2015

**Notes:** Replace the aged drinking fountains in the basement with accessible models.

---

**System: D2030 - Sanitary Waste**



**Location:** Entire building.

**Distress:** Failing

**Category:** 3 - Operations / Maint.

**Priority:** 3 - Response Time (3-4 yrs)

**Correction:** Inspect sanitary waste piping and replace damaged sections. (+100KSF)

**Qty:** 134,000.00

**Unit of Measure:** S.F.

**Estimate:** \$569,045.46

**Assessor Name:** System

**Date Created:** 08/12/2015

**Notes:** Hire a qualified contractor to perform a detailed examination of the sanitary waste and rain water drainage piping using visual inspection and video cameras to determine cause of back-ups during heavy rains and replace any damaged or failing piping.

---



**System: D3040 - Distribution Systems**



**Location:** Fan rooms

**Distress:** Beyond Service Life

**Category:** 3 - Operations / Maint.

**Priority:** 3 - Response Time (3-4 yrs)

**Correction:** Install / replace HVAC unit for Auditorium (800 seat).

**Qty:** 800.00

**Unit of Measure:** Seat

**Estimate:** \$1,604,451.39

**Assessor Name:** System

**Date Created:** 01/21/2016

**Notes:** Replace the HVAC system serving the auditorium.

---

**System: D3040 - Distribution Systems**



**Location:** Entire building

**Distress:** Beyond Service Life

**Category:** 3 - Operations / Maint.

**Priority:** 3 - Response Time (3-4 yrs)

**Correction:** Perform testing to identify and replace damaged steam and condensate piping.

**Qty:** 134,000.00

**Unit of Measure:** S.F.

**Estimate:** \$1,267,689.81

**Assessor Name:** System

**Date Created:** 08/13/2015

**Notes:** Replace steam and condensate piping due to age and rust.

---

**Priority 4 - Response Time (4-5 yrs):**

**System: B2020 - Exterior Windows**



**Location:** Gym

**Distress:** Energy Efficiency

**Category:** 4 - Capital Improvement

**Priority:** 4 - Response Time (4-5 yrs)

**Correction:** Remove and replace double slider windows

**Qty:** 350.00

**Unit of Measure:** Ea.

**Estimate:** \$1,766,150.43

**Assessor Name:** System

**Date Created:** 08/31/2015

**Notes:** Replace Plexiglas windows – hazed

---

**System: D3040 - Distribution Systems**



**Location:** Entire building

**Distress:** Failing

**Category:** 3 - Operations / Maint.

**Priority:** 4 - Response Time (4-5 yrs)

**Correction:** Replace finned tube radiation terminals (per 100 LF)

**Qty:** 350.00

**Unit of Measure:** L.F.


**Estimate:** \$141,239.50

**Assessor Name:** System

**Date Created:** 08/13/2015

**Notes:** Replace the existing radiators with finned coil units.

**System: D3060 - Controls & Instrumentation**



**Location:** Entire building

**Distress:** Energy Efficiency

**Category:** 4 - Capital Improvement

**Priority:** 4 - Response Time (4-5 yrs)

**Correction:** Replace pneumatic controls with DDC (150KSF)

**Qty:** 134,000.00

**Unit of Measure:** S.F.

**Estimate:** \$2,400,127.59

**Assessor Name:** System

**Date Created:** 08/13/2015

**Notes:** Replace the pneumatic controls for the HVAC systems with modern DDC modules, valves, and actuators to improve reliability and energy efficiency. Provide a new building automation system (BAS) with communication interface to the preferred system in use throughout the District.

---

**System: D4010 - Sprinklers**

This deficiency has no image.

**Location:** Entire building

**Distress:** Life Safety / NFPA / PFD

**Category:** 1 - Health & Safety

**Priority:** 4 - Response Time (4-5 yrs)

**Correction:** Install a fire protection sprinkler system

**Qty:** 134,000.00

**Unit of Measure:** S.F.

**Estimate:** \$1,916,928.39

**Assessor Name:** System

**Date Created:** 08/13/2015

**Notes:** Install a fire protection sprinkler system with quick response type heads to reduce insurance costs by providing protection for the property. A packaged, outdoor, engine driven fire pump may be required depending on the available city water pressure.

---

**System: E2010 - Fixed Furnishings**



**Location:** Auditorium

**Distress:** Damaged

**Category:** 3 - Operations / Maint.

**Priority:** 4 - Response Time (4-5 yrs)

**Correction:** Replace auditorium seating - add tablet arms if required. Veneer seating is an option.

**Qty:** 800.00

**Unit of Measure:** Ea.

**Estimate:** \$721,524.41

**Assessor Name:** System

**Date Created:** 08/31/2015

**Notes:** Replace auditorium seats – beyond service life and failing

---

**Priority 5 - Response Time (> 5 yrs):**

**System: D2020 - Domestic Water Distribution**



**Location:** Entire building

**Distress:** Beyond Service Life

**Category:** 3 - Operations / Maint.

**Priority:** 5 - Response Time (> 5 yrs)

**Correction:** Replace domestic water piping (150 KSF)

**Qty:** 134,000.00

**Unit of Measure:** S.F.

**Estimate:** \$555,707.12

**Assessor Name:** System

**Date Created:** 08/12/2015

**Notes:** Replace the original copper domestic water piping to eliminate joints made with lead solder.

---

**System: D3030 - Cooling Generating Systems**



**Location:** Entire building.

**Distress:** Inadequate

**Category:** 4 - Capital Improvement

**Priority:** 5 - Response Time (> 5 yrs)

**Correction:** Install chilled water system with distribution piping and pumps. (+150KSF)

**Qty:** 134,000.00

**Unit of Measure:** S.F.

**Estimate:** \$2,228,630.61

**Assessor Name:** System

**Date Created:** 08/13/2015

**Notes:** Install 335 ton total capacity cooling system to replace aged and inefficient window unit air conditioners.

---

**System: D3040 - Distribution Systems**



**Location:** classrooms

**Distress:** Building / MEP Codes

**Category:** 2 - Code Compliance

**Priority:** 5 - Response Time (> 5 yrs)

**Correction:** Provide classroom FC units and dedicated OA ventilation system. (20 clsrms)

**Qty:** 38.00

**Unit of Measure:** Room

**Estimate:** \$3,156,317.60

**Assessor Name:** System

**Date Created:** 08/13/2015

**Notes:** Replace the original HVAC system serving the classrooms with new fan coil units and dedicated OA systems.

---

## Equipment Inventory

The following table represents the inventory details of the inventory found in the building, which fall under the following subsystems:

Subsystem	Inventory	Qty	UoM	Location	Manufacturer	Model Number	Serial Number	Barcode	Life	Install Date	Next Renewal	Raw Cost	Inventory Cost
D2020 Domestic Water Distribution	Pump, pressure booster system, variable speed, base, controls, starter, duplex, 100' head, 400 GPM, 7-1/2 H.P., 4" discharge	1.00	Ea.	Sub-basement					25	2012	2037	\$51,870.00	\$57,057.00
D3020 Heat Generating Systems	Boiler, gas/oil combination, cast iron, steam, gross output, 6100 MBH, includes burners, controls and insulated jacket, packaged	3.00	Ea.	Boiler room					35	2001	2036	\$140,742.00	\$464,448.60
D3040 Distribution Systems	AHU, field fabricated, built up, cool/heat coils, filters, constant volume, 40,000 CFM	5.00	Ea.	Basement mechanical rooms					25	1927	2042	\$151,511.80	\$833,314.90
D5010 Electrical Service/Distribution	Load interrupter switch, 2 position, 300 kVA & below, 13.8 kV, 600 amp w/CLF fuses, NEMA 1	1.00	Ea.	electrical room	Penn Panel	PPB-3	010143		30	2001	2031	\$42,600.60	\$46,860.66
D5010 Electrical Service/Distribution	Switchboards, no main disconnect, 4 wire, 120/208 V, 3000 amp, incl CT compartment, excl CT's or PT's	1.00	Ea.	basement electrical room	General Electric	Switchboard	6950246D03		30	2001	2031	\$12,792.60	\$14,071.86
D5010 Electrical Service/Distribution	Switchgear installation, incl switchboard, panels & circuit breaker, 120/208 V, 800 A	1.00	Ea.	basement electrical room	General Electric	Spectra Series	178PP63692		20	2001	2021	\$21,766.05	\$23,942.66
D5010 Electrical Service/Distribution	Transformer, liquid-filled, 5 kV or 15 kV primary, 277/480 V secondary, 3 phase, 1000 kVA, pad mounted	1.00	Ea.	basement electrical room	Olsun Electris corporation	dry type transformer class AA	31450-CR 111169		30	2001	2031	\$50,425.20	\$55,467.72
												<b>Total:</b>	<b>\$1,495,163.40</b>



## Executive Summary

Building condition is evaluated based on the functional systems and elements of a building and organized according to the UNIFORMAT II Elemental Classification. The grouping of these systems and elements and applying a current replacement value to them develops a representative building cost model. Cost Models are developed for similar building types and functions. Systems and their elements are evaluated based on their current replacement values, life cycles, installation dates and next renewal dates. Systems and their elements that are within their useful lives are further evaluated to identify current deficient conditions that may have a significant impact on a system's or element's remaining service life, and to determine if they are beyond their predicted expected life. The system's or element's current replacement value is based on RS Means Commercial Cost Data.

Following are the cost model's system details for this facility. The Replacement Value is the amount needed to replace the property of the same present value. The Current Repair Amount, also known as Condition Needs, represents the budgeted contractor installed costs plus owner's soft costs for the repair, replacement or renewal for a component or system level deficiency. It excludes contributing costs for other components or systems that might also be associated with the corrective actions due to packaging the work. Facility Condition Index (FCI) FCI is an industry-standard measurement of facility condition calculated as the ratio of the costs to correct a facility's deficiencies to the facility's Current Replacement Value. It ranges from 0% (new) to 100% (very poor). Condition Index (CI) is calculated as the sum of a renewable system's Remaining Service Life (RSL) divided by the sum of a system's Replacement Value (both values exclude soft-cost to simplify calculation updates) expressed as a percentage ranging from 100% (new) to 0% (expired).

Function:

Gross Area (SF): 32,600

Year Built: 1926

Last Renovation:

Replacement Value: \$659,790

Repair Cost: \$421,988.06

Total FCI: 63.96 %

Total RSLI: 72.10 %



### Description:

### Attributes:

#### General Attributes:

Bldg ID:	S211001	Site ID:	S211001
----------	---------	----------	---------



## Condition Summary

The Table below shows the CI and FCI for each major building system shown at the UNIFORMAT classification Level II. Note that Systems with lower FCIs require less investment than systems with higher FCIs.

UNIFORMAT Classification	RSLI %	FCI %	Current Repair Cost
G20 - Site Improvements	58.19 %	0.00 %	\$0.00
G40 - Site Electrical Utilities	106.67 %	222.80 %	\$421,988.06
<b>Totals:</b>	<b>72.10 %</b>	<b>63.96 %</b>	<b>\$421,988.06</b>

### Condition Detail

This section of the report contains results of the Facility Condition Assessment. The building is separated into system components based on UNIFORMAT II classification. The columns in the System Listing table below represent the following:

1. System Code: A code that identifies the system.
2. System Description: A brief description of a system present in the building.
3. Unit Price \$: The unit price of the system.
4. UoM: The unit of measure for of the system.
5. Qty: The quantity for the system
6. Life: anticipated service life for thesystem based on Building Owners and Managers Association (BOMA) recommendations.
7. Year Installed: The date of system installation.
8. Calc Next Renewal Year: The date of system expiration based on the life, NR stands for non renewable.
9. Next Renewal Year: The suggested system expiration date by the assessor based on visual inspection.
10. CI: The Condition Index of the system.
11. FCI: The Facility Condition Index of the system.
12. RSL: Remaining Service Life.
13. eCR: eCOMET Condition Rating (not used).
14. Deficiency \$: The financial investment to repair/replace system.

## System Listing

The System Listing table below lists each of the systems organized by their UNIFORMAT II classification. The assessment team was tasked with recording the most recent replacement year of each system, determining the remaining service life based on the theoretical life, and evaluating the condition to confirm the forecast next replacement year. The system listing is the basis for all data contained in the Building Assessment Report.

Additionally, a condition rating (eCR) based on the following guidelines is provided as observed at the time of the assessment.

- Excellent (E) - No noticeable distress or damage. The entire system is free from observable defect.
- Very Good (VG) - Overall no serviceability reduction for the entire system. No degradation of critical components and minor distress and defect noticeable for some but not non critical components within the system.
- Good (G) - Slight or no serviceability reduction for the entire system. There may be noticeable defects for some non critical components and slight noticeable degradation of the critical components.
- Fair (F) - Overall serviceability is degraded but adequate. There may be moderate deterioration for very few of the critical components and few of the non critical components may have severe degradation.
- Marginal (MA) - Overall serviceability and reliability loss. Most if not all of the non critical components suffer from severe degradation and a few of the critical component may have severe degradation.
- Moderate (MO) - Overall a significant serviceability loss. Most if not all the components have severe degradation with the reminder of the component showing visible distress.
- Very Poor (VP) - Overall the system is barely functional. All of the components are severely degraded.
- Non-Functional (NF) - Overall the system does not function with all the components having no serviceability and suffer from severe degradation.

System Code	System Description	Unit Price \$	UoM	Qty	Life	Year Installed	Calc Next Renewal Year	Next Renewal Year	RSLI%	FCI%	RSL	eCR	Deficiency \$	Replacement Value \$
G2020	Parking Lots	\$8.50	S.F.	11,200	30	2000	2030		50.00 %	0.00 %	15			\$95,200
G2030	Pedestrian Paving	\$12.30	S.F.	17,600	40	2000	2040		62.50 %	0.00 %	25			\$216,480
G2040	Site Development	\$4.36	S.F.	32,600	25	2005	2030		60.00 %	0.00 %	15			\$142,136
G2050	Landscaping & Irrigation	\$4.36	S.F.	3,800	15	2005	2020		33.33 %	0.00 %	5			\$16,568
G4020	Site Lighting	\$4.84	S.F.	32,600	30			2047	106.67 %	209.07 %	32		\$329,883.16	\$157,784
G4030	Site Communications & Security	\$0.97	S.F.	32,600	30			2047	106.67 %	291.27 %	32		\$92,104.90	\$31,622
<b>Total</b>									<b>72.10 %</b>	<b>63.96 %</b>			<b>\$421,988.06</b>	<b>\$659,790</b>

## System Notes

The facility description in the site executive summary contains an overview of each system. The notes listed below provide additional information on select systems found within the facility.

No data found for this asset

## Renewal Schedule

eCOMET forecasts future Capital Renewal funding needed to address expiring systems based on the Next Renewal year found in the Cost Models. A 3% annual inflation factor is applied to the costs for systems expiring in future years. The table below reflects recommended Capital Renewal funding needs over the next 10 years. Note: Cells with a zero value indicate systems for which renewal is not scheduled in that year.


*Inflation Rate: 3%*

System	Current Deficiencies	2016	2017	2018	2019	2020	2021	2022	2023	2024	2025	Total
<b>Total:</b>	<b>\$421,988</b>	<b>\$0</b>	<b>\$0</b>	<b>\$0</b>	<b>\$0</b>	<b>\$21,128</b>	<b>\$0</b>	<b>\$0</b>	<b>\$0</b>	<b>\$0</b>	<b>\$0</b>	<b>\$443,116</b>
G - Building Sitework	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G20 - Site Improvements	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G2020 - Parking Lots	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G2030 - Pedestrian Paving	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G2040 - Site Development	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G2050 - Landscaping & Irrigation	\$0	\$0	\$0	\$0	\$0	\$21,128	\$0	\$0	\$0	\$0	\$0	\$21,128
G40 - Site Electrical Utilities	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G4020 - Site Lighting	\$329,883	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$329,883
G4030 - Site Communications & Security	\$92,105	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$92,105

*\* Indicates non-renewable system*

Forecasted Sustainment Requirement

The following chart shows the current building deficiencies and forecasting sustainment requirements over the next ten years.




## 10 Year FCI Forecast by Investment Scenario

The chart below illustrates the effect of various investment levels on the building FCI for the next 10 years. The levels of investment shown below include:

- Current FCI: a variable investment amount based on renewing expired systems to maintain the current FCI for the building
- 2% Investment: an annual investment of 2% of the replacement value of the building, escalated for inflation
- 4% Investment: an annual investment of 4% of the replacement value of the building, escalated for inflation


**Facility Investment vs. FCI Forecast**



Year	Investment Amount Current FCI - 63.96%	2% Investment		4% Investment	
		Amount	FCI	Amount	FCI
2016	\$0	\$13,592.00	61.96 %	\$27,183.00	59.96 %
2017	\$221,034	\$13,999.00	91.54 %	\$27,999.00	87.54 %
2018	\$0	\$14,419.00	89.54 %	\$28,839.00	83.54 %
2019	\$0	\$14,852.00	87.54 %	\$29,704.00	79.54 %
2020	\$21,128	\$15,298.00	88.30 %	\$30,595.00	78.30 %
2021	\$0	\$15,756.00	86.30 %	\$31,513.00	74.30 %
2022	\$0	\$16,229.00	84.30 %	\$32,458.00	70.30 %
2023	\$0	\$16,716.00	82.30 %	\$33,432.00	66.30 %
2024	\$0	\$17,218.00	80.30 %	\$34,435.00	62.30 %
2025	\$0	\$17,734.00	78.30 %	\$35,468.00	58.30 %
<b>Total:</b>	<b>\$242,162</b>	<b>\$155,813.00</b>		<b>\$311,626.00</b>	

## Deficiency Summary by System

Current deficiencies included assemblies that have reached or exceeded their design life or components of the assemblies that are in need of repair. Assemblies that have reached their design life are identified as current deficiencies and assigned the distress 'Beyond Useful Life'. The following chart lists all current deficiencies associated with this facility.




**Budget Estimate Total: \$421,988.06**



## Deficiency Summary by Priority

The following chart shows the total repair costs broken down by priority. Assessors assigned deficiencies within eCOMET to one of the following priority categories:



**Budget Estimate Total: \$421,988.06**


## Deficiency By Priority Investment Table

The table below shows the current investment cost grouped by deficiency priority and building system.

System Code	System Description	1 - Response Time (< 2 yr)	2 - Response Time (2-3 yrs)	3 - Response Time (3-4 yrs)	4 - Response Time (4-5 yrs)	5 - Response Time (> 5 yrs)	Total
G4020	Site Lighting	\$329,883.16	\$0.00	\$0.00	\$0.00	\$0.00	\$329,883.16
G4030	Site Communications & Security	\$0.00	\$92,104.90	\$0.00	\$0.00	\$0.00	\$92,104.90
	<b>Total:</b>	\$329,883.16	\$92,104.90	\$0.00	\$0.00	\$0.00	\$421,988.06

## Deficiency Summary by Category

The following chart shows the total repair costs broken down by deficiency categories. Assessors assigned deficiencies to one of the following categories:



## Deficiency Details by Priority

The deficiency detail notes listed below provide additional information on identified deficiencies found within the facility.

### Priority 1 - Response Time (< 2 yr):

#### **System: G4020 - Site Lighting**



**Location:** Grounds

**Distress:** Security Issue

**Category:** 1 - Health & Safety

**Priority:** 1 - Response Time (< 2 yr)

**Correction:** Add Site Lighting - pole mounted - select the proper light and pole

**Qty:** 12.00

**Unit of Measure:** Ea.

**Estimate:** \$329,883.16

**Assessor Name:** Craig Anding

**Date Created:** 08/07/2015

**Notes:** Provide 12 pole mounted lighting fixtures for security.

---

**Priority 2 - Response Time (2-3 yrs):**

**System: G4030 - Site Communications & Security**



**Location:** Bkuilding Exterior

**Distress:** Security Issue

**Category:** 1 - Health & Safety

**Priority:** 2 - Response Time (2-3 yrs)

**Correction:** Add Video Surveillance System

**Qty:** 8.00

**Unit of Measure:** Ea.

**Estimate:** \$92,104.90

**Assessor Name:** Craig Anding

**Date Created:** 08/07/2015

**Notes:** Provide a site video surveillance system. Approximate 8 cameras

---

## Equipment Inventory

The following table represents the inventory details of the inventory found in the building, which fall under the following subsystems:

No data found for this asset

## Glossary

ABMA	American Boiler Manufacturers Association <a href="http://www.abma.com/">http://www.abma.com/</a>
ACEEE	American Council for an Energy-Efficient Economy
ACGIH	American Council of Governmental and Industrial Hygienists
AEE	Association of Energy Engineers
AFD	Adjustable Frequency Drive
AFTC	After Tax Cash Flow
AGA	American Gas Association
AHU	Air Handling Unit
Amp	Ampere
ANSI	American National Standards Institute
ARI	Air Conditioning and Refrigeration Institute
ASD	Adjustable Speed Drive
ASHRAE	American Society of Heating Refrigerating and Air-Conditioning Engineers Inc.
ASME	American Society of Mechanical Engineers
Assessment	Visual survey of a facility to determine its condition. It involves looking at the age of systems reviewing information from local sources and visual evidence of potential problems to assign a condition rating. It does not include destructive testing of materials or testing of systems or equipment for functionality.
ATS	After Tax Savings
AW	Annual worth
BACNET	Building Automation Control Network
BAS	Building Automation System
BCR	Benefit Cost Ratio
BEP	Business Energy Professional (AEE)
BF	Ballast Factor
BHP	Boiler Horsepower (boilers)
BHP	Brake Horsepower (motors)
BLCC	Building Life Cycle Cost analysis program (FEMP)
BOCA	Building Officials and Code Administrators
BTCF	Before Tax Cash Flow

## Site Assessment Report - S211001;Barratt

---

BTS	Before Tax Savings
Btu	British thermal unit
Building Addition	An area space or component of a building added to a building after the original building's year built date.
CAA	Clean Air Act
CAAA-90	Clean Air Act Amendments of 1990
CABO	Council of American Building Officials
CAC	Conventional Air Conditioning
CADDET	Center for the Analysis and Dissemination of Demonstrated Energy Technologies
Calculated Next Renewal	The year a system or element would be expected to expire based solely on the date it was installed and the expected useful lifetime for that kind of system.
Capital Renewal	Capital renewal is condition work (excluding suitability and energy audit work) that includes the replacement of building systems or elements (as they become obsolete or beyond their useful life) not normally included in an annual operating budget. Calculated next renewal The year a system or element would be expected to expire based solely on the date it was installed and the expected useful lifetime for that kind of system. Next renewal The assessor adjusted expected useful life of a system or element based on on-site inspection.
CDD	Cooling Degree Days
CDGP	Certified Distributed Generation Professional
CEC	California Energy Commission
CEM	Certified Energy Manager
CEP	Certified Energy Procurement Professional
CFC	Chlorofluorocarbon
CFD	Cash Flow Diagram
CFL	Compact Fluorescent Light
CFM cfm	Cubic Feet per Minute
CHP	Combined Heat and Power (a.k.a. cogeneration)
CHW	Chilled Water
Condition	Condition refers to the state of physical fitness or readiness of a facility system or system element for its intended use.
COP	Coefficient of Performance
Cp	Heat Capacity of Material
CPUC	California Public Utility Commission
CRI	Color Rendering Index
CRT	Cathode Ray Tube VDT HMI



## Site Assessment Report - S211001;Barratt

---

CTC	Competitive Transition Charge
Cu	Coefficient of Utilization
Current Replacement Value (CRV)	CRV represents the hypothetical total cost of rebuilding or replacing an existing facility in current dollars to its optimal condition (excluding auxiliary facilities) under current codes and construction standards.
Cv	Value Coefficient
CWS	Chilled Water System
D d	Distance (usually feet)
DB	Dry Bulb
DCV	Demand Control Ventilation
DD	Degree Day
DDB	Double Declining Balance
DDC	Direct Digital Controls
Deferred maintenance	Deferred maintenance is condition work (excluding suitability and energy audit needs) deferred on a planned or unplanned basis to a future budget cycle or postponed until funds are available.
Deficiency	A deficiency is a repair item that is damaged missing inadequate or insufficient for an intended purpose.
Delta	Difference
Delta P	Pressure Difference
Delta T	Temperature Difference
DG	Distributed Generation
DOE	Department of Energy
DP	Dew Point
DR	Demand Response
DX	Direct Expansion Air Conditioner
EA	Energy Audit
EBITDA	Earnings before Interest Taxes Depreciation and Amortization
ECI	Energy Cost Index
ECM	Energy Conservation Measure
ECO	Energy Conservation Opportunity
ECPA	Energy Conservation and Production Act
ECR	Energy Conservation Recommendation
ECS	Energy Control System

## Site Assessment Report - S211001;Barratt

---

EER	Energy Efficiency Ratio
EERE	Energy Efficiency and Renewable Energy division of US DOE
EIA	Energy Information Agency
EIS	Energy Information System
EMCS	Energy Management Computer System
EMO	Energy Management Opportunity
EMP	Energy Management Project
EMR	Energy Management Recommendation
EMS	Energy Management System
Energy Utilization Index (EUI)	EUI is the measure of total energy consumed in the cooling or heating of a building in a period expressed as British thermal unit (BTU) per (cooled or heated) gross square foot.
EO	Executive Order
EPA	Environmental Protection Agency
EPACT	Energy Policy Act of 1992
EPCA	Energy Production and Conservation Act of 1975
EPRI	Electric Power Research Institute
EREN	Efficiency and Renewable Energy (Division of USDOE)
ERV	Energy Recovery Ventilator
ESCO	Energy Service Company
ESPC	Energy Savings Performance Contract
EUI	Energy Use Index
EWG	Exempt Wholesale Generators
Extended Facility Condition Index (EFCI)	EFCI is calculated as the condition needs for the current year plus facility system renewal needs going out to a set time in the future divided by Current Replacement Value.
f	Frequency
F	Fahrenheit
Facility	A facility refers to site(s) building(s) or building addition(s) or combinations thereof that provide a particular service.
Facility Condition Assessment (FCA)	FCA is a process for evaluating the condition of buildings and facilities for programming and budgetary purposes through an on site inspection and evaluation process.
Facility Condition Index (FCI)	FCI is an industry-standard measurement of a facility's condition that is the ratio of the cost to correct a facility's deficiencies to the Current Replacement Value of the facilities. The higher the FCI the poorer the condition of a facility. After an FCI is established for all buildings within a portfolio a building's condition can be ranked relative to other buildings. The FCI may also represent the condition of a portfolio based on the cumulative FCIs of the portfolio's facilities.

## Site Assessment Report - S211001;Barratt

---

FC	Footcandle
FCA	Fuel Cost Adjustment
FEMIA	Federal Energy Management Improvement Act of 1988
FEMP	Federal Energy Management Program
FERC	Federal Energy Regulatory Commission
FESR	Fuel Energy Savings Ratio
FLA	Full Load Amps
FLF	Facility Load Factor (usually monthly)
FLRPM	Full Load Revolutions per Minute
FMS	Facility Management System
FPM fpm	Feet per Minute (velocity)
FSEC	Florida Solar Energy Center
Ft	Foot
GPM gpm	Gallons per Minute
GRI	Gas Research Institute
Gross Square Feet (GSF)	The size of the enclosed floor space of a building in square feet measured to the outside face of the enclosing wall.
GUI	Graphical User Interface
H h	Enthalpy Btu/lb
HCFC	Hydrochlorofluorocarbons
HDD	Heating Degree days
HFC	Hydrofluorocarbons
HHV	Higher Heating Value
HID	High Intensity Discharge (lamp)
HMI	Human Machine Interface
HMMI	Human Man Machine Interface
HO	High Output (lamp)
HP Hp hp	Horsepower
HPS	High Pressure Sodium (lamp)
HR	Humidity Ratio
Hr hr	Hour

## Site Assessment Report - S211001;Barratt

---

HRU	Heat Recovery Unit
HVAC	Heating Ventilation and Air-Conditioning
Hz	Hertz
I	Intensity (lumen output of lamp)
I i	Interest rate or Discount rate
IAQ	Indoor Air Quality
ICA	International Cogeneration Alliance
ICBO	International Conference of Buildings Officials
ICC	International Code Council
ICP	Institutional Conservation Program
IECC	International Energy Conservation Code
IEEE	Institute of Electrical and Electronic Engineers
IESNA	Illuminating Engineering Society of North America
Install year	The year a building or system was built or the most recent major renovation date (where a minimum of 70 of the system's Current Replacement Value (CRV) was replaced).
IRP	Integrated Resource Planning
IRR	Internal Rate of Return
ISO	Independent System Operator
ITA	Independent Tariff Administrator
k	Kilo multiple of thousands in SI system
K	Kelvins (color temperature of lamp)
K k	Thermal Conductivity of Material
KVA	Kilovolt Ampere
KVAR	Kilovolt Ampere Reactive
kW	kiloWatt
kWh	kiloWatt hour
L	Length (usually feet)
LCC	Life Cycle Costing
LDC	Local Distribution Company
LEED	Leadership in Energy and Environmental Design
LEED EB	LEED for Existing Buildings

## Site Assessment Report - S211001;Barratt

---

LEED NC	LEED for new construction
LF	Load Factor
LHV	Lower Heating Value
Life cycle	The period of time that a building or site system or element can be expected to adequately serve its intended function.
LPS	Low Pressure Sodium (lamp)
Lu	Lumen Output of a Lamp or Fixture
M	Mega multiple of millions in SI system
M&V	Measurement and Verification
MACRS	Modified Accelerated Cost Recovery System
MARR	Minimum Attractive Rate of Return
Mbtu	Thousand Btu
MCF	Thousand Cubic Feet (usually of gas)
MEC	Model Energy Code
Mm	Multiple of Thousands in I/P System
MMBtu	Million Btu
MMCS	Maintenance Management Computer System
MMI	Man Machine Interface
MMS	Maintenance Management System
MSE 2000	Management System for Energy 2000 (ANSI Georgia Tech Univ)
MW	MegaWatt
MWH MWh	MegaWatt hour
NAAQS	National Ambient Air Quality Standards
NAESCO	National Association of Energy Service Companies
NAIMA	North American Insulation Manufacturers Association
NEA	National Energy Act of 1978
NECPA	National Energy Conservation Policy Act
NEMA	National Electrical Manufacturer's Association
NERC	North American Electric Reliability Council
Next Renewal	The Next Renewal date is an override of the 'Calculated Next Renewal' date and is based upon the assessor's visual inspection.

## Site Assessment Report - S211001;Barratt

---

NFPA	National Fire Protection Association
NGPA	National Gas Policy Act of 1978
NLRPM	No Load Revolutions per Minute (speed)
Nn	Equipment or Project lifetime in economic analysis
NOPR	Notice of Proposed Rule Making from FERC
NOx	Nitrogen Oxide Compounds
NPV	Net present value in economic analysis
NREL	National Renewable Energy Laboratory
NUG	Non-Utility Generator
O&M	Operation and Maintenance
OA	Outside Air
ODP	Ozone Depletion Potential
OPAC	Off-Peak Air Conditioning
P	Present value in economic analysis
PBR	Performance Based Rates
PEA	Preliminary Energy Audit
PF	Power Factor
PID	Proportional plus integral plus derivative (control system)
PM	Portfolio Manager in Energy Star rating system
PM	Preventive Maintenance
PoolCo	Power Pool Company or Organization
POU	Point of Use
PQ	Power Quality
PSC	Public Service Commission
PSIA psia	Pounds per square inch absolute (pressure)
PSIG psig	Pounds per square inch gauge (pressure)
PUC	Public Utility Commission
PUHCA	Public Utilities Holding Company Act of 1935
PURPA	Public Utilities Regulatory Policies of 1978
PV	Photovoltaic system

## Site Assessment Report - S211001;Barratt

---

PV	Present Value
PW	Present Worth
PX	Power Exchange
q	Rate of heat flow in Btu per hour
Q	Heat load due to conduction using degree days
QF	Qualifying Facility
R	Electrical resistance
R	Thermal Resistance
RC	Remote controller
RCR	Room Cavity Ratio
RCRA	Resource Conservation and Recovery Act
Remaining Service Life (RSL)	RSL is the number of years service remaining for a system or equipment item. It is automatically calculated based on the difference between the current year and the 'Calculated Next Renewal' date or the 'Next Renewal' date whichever one is the later date.
Remaining Service Life Index (RSLI)	RSLI is defined as a percentage ratio of the remaining service life of a system. It usually ranges from 0 to 100
REMR	Repair Evaluation Maintenance Rehabilitation (REMR) is a scale used to objectively rank systems based on their condition
Renewal Schedule	A timeline that provides the items that need repair the year in which the repair is needed and the estimated price of the renewal.
RH	Relative Humidity
RLA	Running Load Amps
RMS	Root Mean Square
RO	Reverse Osmosis
ROI	Return on Investment
RPM	Revolutions Per Minute
RTG	Regional Transmission Group
RTO	Regional Transmission Organization
RTP	Real Time Pricing
SBCCI	Southern Building Code Congress International
SC	Scheduling Coordinator
SC	Shading Coefficient
SCADA	Supervisory Control and Data Acquisition Systems

## Site Assessment Report - S211001;Barratt

---

SEER	Seasonal Energy Efficiency Ratio
SHR	Sensible Heat Ratio
Site	The grounds and utilities roadways landscaping fencing and other typical land improvements needed to support the facility.
Soft Cost	An expense item that is not considered direct construction cost. Soft cost includes architectural engineering financing legal fees and other pre-and-post construction expenses.
SOx	Sulfur Oxide Compounds
SP	Static Pressure
SP SPB	Simple Payback
SPP	Simple Payback Period
SPP	Small Power Producers
STR	Stack Temperature Rise
SV	Specific Volume
System	System refers to building and related site work elements as described by ASTM Uniformat II Classification for Building Elements (E1557-97) a format for classifying major facility elements common to most buildings. Elements usually perform a given function regardless of the design specification construction method or materials used. See also Uniformat II.
T	Temperature
T	Tubular (lamps)
TAA	Technical Assistance Audit
TCP/IP	Transmission Control Protocol/Internet Protocol
TES	Thermal Energy Storage
THD	Total Harmonic Distortion
TOD	Time of Day
TOU	Time of Use
TQM	Total Quality Management
TransCo	Transmission Company
U	Thermal Conductance
UDC	Utility Distribution Company
UL	Underwriters Laboratories
UNIFORMAT II	The ASTM UNIFORMAT II Classification for Building Elements (E1557-97) a format for classifying major facility components common to most buildings.
USGBC	US Green Building Council
v	Specific Volume



## Site Assessment Report - S211001;Barratt

---

V	Volts Voltage
V	Volume
VAV	Variable Air Volume
VDT	Video Display Terminal
VFD	Variable Frequency Drive
VHO	Very High Output
VSD	Variable Speed Drive
W	Watts
W	Width
WB	Wet bulb
WH Wh	Watt Hours
Year built	The year that a building or addition was originally built based on substantial completion or occupancy.
Z	Electrical Impedance