

Facility Condition Assessment Summary Report

This report provides a summary of the Facility Condition Index (FCI) value of a school facility and select major building systems. The FCI calculation represents the cost of needed repairs divided by the replacement value. The FCI is a numerical value of condition and helps to identify the need for renewal or replacement of specific parts of the facility. The FCI is particularly useful when comparing similar facilities within the same portfolio.

Conwell School

Governance	DISTRICT	Report Type	Middle
Address	1849 E. Clearfield St. Philadelphia, Pa 19134	Enrollment	408
Phone/Fax	215-291-4722 / 215-291-5019	Grade Range	'05-08'
Website	Www.Philasd.Org/Schools/Conwell	Admissions Category	Special Admit
		Turnaround Model	N/A

Building/System FCI Tiers

Facility Condition Index (FCI) = $\frac{\text{Cost of Assessed Deficiencies}}{\text{Replacement Value}}$				
< 15%	15 to 25%	25 to 45%	45 to 60%	> 60%
Buildings				
Minimal Current Capital Funding Required	Refurbish Systems in building	Replace Systems in building.	Building should be considered for major renovation.	Building should be considered for closing/replacement.
Systems				
Perform routine maintenance on system	System requires minor repairs	System should be studied to determine repair vs. replacement.	System is nearing end of its life expectancy and should be considered for replacement	System should be replaced as part of the Capital Program

Building and Grounds

	FCI	Repair Costs	Replacement Cost
Overall	54.20%	\$15,601,608	\$28,785,240
Building	53.26 %	\$15,073,285	\$28,299,720
Grounds	108.82 %	\$528,323	\$485,520

Major Building Systems

Building System	System FCI	Repair Costs	Replacement Cost
Roof (Shows physical condition of roof)	88.64 %	\$623,429	\$703,331
Exterior Walls (Shows condition of the structural condition of the exterior facade)	30.24 %	\$736,200	\$2,434,168
Windows (Shows functionality of exterior windows)	187.43 %	\$2,230,169	\$1,189,840
Exterior Doors (Shows condition of exterior doors)	158.15 %	\$127,502	\$80,620
Interior Doors (Classroom doors)	32.23 %	\$62,892	\$195,156
Interior Walls (Paint and Finishes)	22.87 %	\$213,790	\$934,636
Plumbing Fixtures	08.48 %	\$63,708	\$751,712
Boilers	93.12 %	\$966,605	\$1,038,052
Chillers/Cooling Towers	63.79 %	\$868,291	\$1,361,088
Radiators/Unit Ventilators/HVAC	138.02 %	\$3,298,901	\$2,390,244
Heating/Cooling Controls	158.90 %	\$1,192,734	\$750,600
Electrical Service and Distribution	77.62 %	\$418,636	\$539,320
Lighting	51.94 %	\$1,001,478	\$1,928,208
Communications and Security (Cameras, Pa System and Fire Alarm)	55.64 %	\$401,860	\$722,244

Please note that some FCIs may be over 100% because there are times when replacing a building system requires that other building systems be upgraded to complete the installation. A FCI of 0.0% represents that there are no current deficiencies with the associated system.

Facility Condition Assessment Summary Report

This report provides a summary of the Facility Condition Index (FCI) value of a school facility and select major building systems. The FCI calculation represents the cost of needed repairs divided by the replacement value. The FCI is a numerical value of condition and helps to identify the need for renewal or replacement of specific parts of the facility. The FCI is particularly useful when comparing similar facilities within the same portfolio.

Conwell Annex School

Governance	DISTRICT	Report Type	Middle
Address	3072 Emerald St Philadelphia, Pa 19134	Enrollment	
Phone/Fax	215-291-4722 / 215-291-5019	Grade Range	'05-08'
Website	Www.Philasd.Org/Schools/Conwell	Admissions Category	Special Admit
		Turnaround Model	N/A

Building/System FCI Tiers

Facility Condition Index (FCI) = $\frac{\text{Cost of Assessed Deficiencies}}{\text{Replacement Value}}$				
< 15%	15 to 25%	25 to 45%	45 to 60%	> 60%
Buildings				
Minimal Current Capital Funding Required	Refurbish Systems in building	Replace Systems in building.	Building should be considered for major renovation.	Building should be considered for closing/replacement.
Systems				
Perform routine maintenance on system	System requires minor repairs	System should be studied to determine repair vs. replacement.	System is nearing end of its life expectancy and should be considered for replacement	System should be replaced as part of the Capital Program

Building and Grounds

	FCI	Repair Costs	Replacement Cost
Overall	26.88%	\$9,128,293	\$33,955,766
Building	28.67 %	\$9,089,321	\$31,700,707
Grounds	01.73 %	\$38,973	\$2,255,059

Major Building Systems

Building System	System FCI	Repair Costs	Replacement Cost
Roof (Shows physical condition of roof)	00.00 %	\$0	\$2,046,640
Exterior Walls (Shows condition of the structural condition of the exterior facade)	33.86 %	\$548,921	\$1,621,317
Windows (Shows functionality of exterior windows)	00.00 %	\$0	\$707,833
Exterior Doors (Shows condition of exterior doors)	00.00 %	\$0	\$86,726
Interior Doors (Classroom doors)	08.84 %	\$17,254	\$195,264
Interior Walls (Paint and Finishes)	66.69 %	\$457,482	\$686,022
Plumbing Fixtures	00.92 %	\$15,158	\$1,640,013
Boilers	22.97 %	\$222,666	\$969,570
Chillers/Cooling Towers	36.36 %	\$462,209	\$1,271,295
Radiators/Unit Ventilators/HVAC	97.71 %	\$2,181,497	\$2,232,557
Heating/Cooling Controls	82.62 %	\$579,206	\$701,082
Electrical Service and Distribution	180.63 %	\$909,901	\$503,740
Lighting	50.58 %	\$911,009	\$1,801,002
Communications and Security (Cameras, Pa System and Fire Alarm)	83.55 %	\$563,626	\$674,597

Please note that some FCIs may be over 100% because there are times when replacing a building system requires that other building systems be upgraded to complete the installation. A FCI of 0.0% represents that there are no current deficiencies with the associated system.

School District of Philadelphia
S523001;Conwell
Final
Site Assessment Report
February 2, 2017



Table of Contents

Site Executive Summary	4
Site Condition Summary	11
<u>B523001:Conwell</u>	13
Executive Summary	13
Condition Summary	14
Condition Detail	15
System Listing	16
System Notes	18
Renewal Schedule	19
Forecasted Sustainment Requirement	22
Condition Index Forecast by Investment Scenario	23
Deficiency Summary By System	24
Deficiency Summary By Priority	25
Deficiency By Priority Investment	26
Deficiency Summary By Category	27
Deficiency Details By Priority	28
Equipment Inventory Detail	50
<u>G523001:Grounds</u>	51
Executive Summary	51
Condition Summary	52
Condition Detail	53
System Listing	54
System Notes	55
Renewal Schedule	56
Forecasted Sustainment Requirement	57
Condition Index Forecast by Investment Scenario	58
Deficiency Summary By System	59
Deficiency Summary By Priority	60
Deficiency By Priority Investment	61

Site Assessment Report

Deficiency Summary By Category	62
Deficiency Details By Priority	63
Equipment Inventory Detail	65
Glossary	66

Site Executive Summary

The organization of this report, as displayed in the Table of Contents, follows the structure of the associated eCOMET database. The overall node for each school campus begins with the letter "S", which indicates the "Site" label. Each Site is comprised of separate "Building" and "Grounds" nodes; their asset names begin with the letters "B" and "G" respectively. Information rolls up to the Site node from the Building and Grounds nodes. This Site report combines facility information with subsections for the Buildings And Grounds nodes.

The basis for the evaluation of condition is the functional systems and elements of a building and grounds organized according to the UNIFORMAT II Elemental Classification. The grouping of these systems and elements and applying a current replacement value to them develops a representative building cost model. Cost Models are typically developed for similar building types and functions. Evaluation of systems and their elements takes into account their current replacement values, life cycles, installation dates and next renewal dates. Systems and their elements that are within their useful lives are further evaluated to identify current deficient conditions that may have a significant impact on a system's or element's remaining service life, and to determine if they are beyond their predicted expected life. The system's or element's current replacement value is based on RS Means Commercial Cost Data.

Following are the cost model's system details for this facility. The Replacement Value is the amount needed to replace the property of the same present value. The Current Repair Amount, also known as Condition Needs, represents the budgeted contractor installed costs plus owner's soft costs for the repair, replacement or renewal for a component or system level deficiency. It excludes contributing costs for other components or systems that might also be associated with the corrective actions due to packaging the work. Facility Condition Index (FCI) is an industry-standard measurement calculated as the ratio of the repair costs to correct a facility's deficiencies to the facility's Current Replacement Value. Condition Index (CI) for a system is calculated as the sum of the deficiencies divided by the sum of a system's Replacement Value (both values include soft-cost) expressed as a percentage ranging from 0% 100%.

Gross Area (SF):	55,600
Year Built:	1926
Last Renovation:	
Replacement Value:	\$28,785,240
Repair Cost:	\$15,601,607.85
Total FCI:	54.20 %
Total RSLI:	67.14 %



Description:

Facility assessment, July 2015

School District of Philadelphia

Conwell Middle School

1829 Clearfield Avenue

Philadelphia, PA 19134

55600 SF / 483 Students / LN 05

The Conwell Middle School building is located at 1829 Clearfield Avenue in Philadelphia, PA. The 3 story, 70,230 square foot building was originally constructed in 1926. The building has a basement partially above ground and a penthouse on the roof. Most toilets in the building were renovated in 2000 including accessibility reconfiguration. VCT tile was installed in some classrooms in 2009.

Mr. Scott Ovington, Facility Area Coordinator provided input to the Parsons assessment team on current problems and planned

Site Assessment Report - S523001;Conwell

renovation projects. Mr. Derek Mathews, Building Engineer, accompanied us on our tour of the school and provided us with detailed information on the building systems and recent maintenance history.

STRUCTURAL/ EXTERIOR CLOSURE:

The building typically rests on concrete foundations and bearing walls that are not showing signs of settlement. Foundation walls do not show signs of deterioration or mold presence.

The main structure consists typically of cast-in-place concrete columns, beams and one-way concrete slabs. Long slab spans are supported with steel truss girders. Above ground floor slabs are generally in good condition, however roof slab shows some structural deterioration including spalled concrete and exposed, rusting reinforcement.

The building envelope is typically masonry with face brick with decorative stone quoining at windows and doors perimeter. In general, masonry is in poor condition with deteriorated and missing mortar from joints; the chimney shows cracks below steel banding reinforcing its top portion.

The original building windows were retrofitted in late 1980's or early 1990's with extruded aluminum double hung windows single glazed with acrylic glazing; original wood frames are left in place and deteriorating. All windows are generally in poor condition with some of the windows inoperable; basement windows have security screens in fair to poor condition; windows are unsafe to operate due to possible balancing mechanism failure (one case of serious injury reported). The windows are generally not energy efficient.

Exterior doors and frames are typically hollow metal in poor condition; there is some rusting and peeling paint. Most exterior doors are beyond their service life. Generally, the building is not accessible per ADA requirements due to first floor- grade separation with no ramps or lifts.

Roofing is typically built-up, over 20 years old. All roofing and flashing is typically in poor condition with some deterioration of the built-up system including water ponding and soft spots; leaks have been reported. The original copper counter flashing under stone coping was left in place during original roofing replacement preventing proper flashing installation.

INTERIORS:

Partition wall types include plastered ceramic hollow blocks and painted CMU. Partitions separating stairways from corridors are generally steel framed borrowed light with wire glazing. The interior wall finishes are generally painted plaster or drywall and some painted brick with marble and glazed brick wainscot in basement. Generally, paint is in fair condition with areas of plaster and paint deterioration at windows perimeters and radiators.

Most ceilings are 2x4 suspended acoustical panels and exposed, painted. The suspension system and tile are old and approaching the end of their useful life. Paint and plaster on exposed ceilings is deteriorated.

Flooring in classrooms and auditorium is generally hardwood; and patterned concrete in most corridors and toilets. Most flooring is original and in poor condition. Some areas have VCT or original VAT tile, generally in fair to poor condition.

Interior doors are generally solid core wood doors installed in around 2005 in most classrooms with original wood frames and transoms left in place. Door finishes are typically in good condition. Most doors are fitted with door knobs and are not ADA compliant. The doors leading to exit stairways are steel framed doors with wire glazing, in good condition.

Fittings include original chalk boards, generally in good condition; toilet accessories and toilet partitions, generally in very good condition; handrails and ornamental metals, generally in good condition. Interior identifying signage is typically directly painted on wall or door surfaces generally in poor condition.

Stair construction is generally concrete with cast iron non-slip treads in good condition.

Institutional and Commercial equipment includes: stage equipment, generally in poor condition; A/V equipment in fair condition; gym equipment – basketball backstops, scoreboards, etc.; generally in poor condition. Other equipment includes kitchen equipment, generally in good condition.

Furnishings include fixed casework in classrooms, corridors and library, generally in fair to poor condition; window shades/blinds, generally in poor condition; fixed auditorium seating is original, generally in fair condition with some damaged seats.

Site Assessment Report - S523001;Conwell

CONVEYING SYSTEMS:

The building has no elevators.

PLUMBING:

Plumbing Fixtures - Many of the original plumbing fixtures remain in service. Fixtures in the restrooms on each floor consist of floor mounted flush valve water closets, wall hung urinals and lavatories with wheel handle faucets. Fixtures in the gang bathrooms were replaced in 2000 and are in good condition. However, the older units should be replaced as part of any renovation of the spaces.

Drinking fountains in the corridors and at the restrooms are wall hung with integral refrigerated coolers. They are well beyond their service life, some are broken, and should be replaced; most are NOT accessible type.

A mop basin is available in a janitor closet in the corridor on each floor for use by the janitorial staff.

The Kitchen has one sink; a three compartment stainless steel prep sink with lever operated faucets and integral grease trap. Chemicals are injected manually into the sanitizing basins.

Domestic Water Distribution - A 4" city water service enters the building from E. Clearfield Street near the intersection with Jasper Street. The 2" meter and valves are located in the basement mechanical room. Two reduced pressure backflow preventers are installed. Duplex Armstrong domestic pressure booster pumps are installed. The domestic hot and cold water distribution piping is copper piping and sweat fittings. The maintenance staff reports no significant problems with scale build up in the domestic piping and the supply is adequate to the fixtures.

One State Sandblaster gas fired, 70 gallon, vertical hot water heater with circulating pump supplies hot water for domestic use. The unit is located in the boiler room on the basement level. The hot water heater is equipped with a T&P relief valve. The domestic hot water heater is beyond its service life and should be replaced. A water softener was located in the boiler room.

Sanitary Waste - The storm and sanitary sewer piping is threaded galvanized piping. Some repairs have been made with HDPE piping with no-hub fittings.

A sewage ejector pit located in basement off of the Cafeteria/Gymnasium receives sewage from the basement area. It has a single pump that is beyond its service life and fails frequently according to the Building Engineer. The pump was inaccessible during the site visit, but the smell of sewage in the Cafeteria/Gymnasium was strong. The pump system should be replaced immediately to prevent flooding of the basement and a sanitary hazard where children eat. The pit is not sealed, but should be.

The maintenance staff reported mostly minor problems with the sanitary waste piping systems. The sewer piping has been in service for over 70 years and will require more frequent attention from the maintenance staff as time passes. The District should hire a qualified contractor to examine the sanitary waste piping using video cameras to locate and replace any damaged piping and to further quantify the extent of potential failures.

Rain Water Drainage - Rain water drains from the roof are routed through mechanical chases in the building and appear to be original. Some of the original galvanized piping has been repaired with HDPE piping and no-hub fittings. The drain piping should be inspected by a qualified contractor and repaired as necessary.

MECHANICAL:

Energy Supply - The oil supply is stored in an 8,000 gallon underground storage tank (UST) located in the paved play area behind the school. Duplex pumps located in the basement circulate oil through the system. Oil is used as the only fuel. The supply should be tested for quality on a regular schedule. USTs have an anticipated service life of 20 years.

Heat Generating Systems - Low pressure steam is generated at a maximum of 15 lbs/sq. in., typically 5-7 lbs/sq. in., by two 135HP Weil-McLain 94 cast iron sectional boilers, installation date unknown, but most likely in the 1960s. One boiler

can handle the load in normal winter weather conditions. Each boiler is equipped with a Power Flame burner designed to operate on fuel oil and installed in 2015. Combustion air makeup is supplied by louvers equipped with motorized dampers. Burner controls provide full modulation with electronic ignition and digital flame sensing. Burner oil pumps are loose and not driven by the fan motor. The Building Engineer reports the system does not lose a significant amount of condensate due to failed traps, which is made up with chemically treated city water. Cast iron sectional boilers have an anticipated service life of 35 years or more; as these units have been in service approximately 50 plus years need to be replaced. The boilers are operational but should be replaced in the next 3 years. The condensate receiver is installed in the basement. The boiler feed pump and tank assembly is installed in the boiler room. No serious problems were reported with steam leaking into the system from failed steam traps.

Distribution Systems - Steam piping is black steel (ASTM A53) with welded fittings. The condensate piping is Schedule 80 black steel with threaded fittings. Steam and condensate piping mains from the basement level runs up through the building to the radiators on all three floors. The distribution piping has been in use well beyond its service life and will require more frequent attention from the maintenance staff to address pipe/valve failures as time passes. The District should hire a qualified contractor to examine the steam and condensate piping and perform additional testing to locate and replace any damaged piping and to further quantify the extent of potential failures. The District should budget for replacing this piping over the next 10 years.

Two pipe cast iron radiators provide heating for the majority of classrooms, offices, and hallways. These radiators are well beyond their service life and original to the building. Ventilation for the building is provided by opening windows, which does not meet current codes for outdoor air ventilation. A new heating system should be installed to meet ventilation requirements and achieve more efficient operation. The new units should be designed for quiet operation and equipped with hot water coils, chilled water coils, and integral heat exchangers, where applicable, to introduce outdoor air to the building.

A kitchen hood with integral fire suppression system, operated by a Range Guard control system, is installed above the gas fired cooking equipment. There is no outdoor air make-up system installed. An automatic gas shutoff valve was installed with kitchen hood equipment. The equipment is within its service life.

Two exhaust fans serving the first through third floor restrooms are operational according to the Building Engineer and are located on the roof. The unisex restrooms on the first and second floor are served by an exhaust fan located on the second floor roof. The kitchen has a dedicated exhaust fan located on the second floor roof. These fans are within their service life.

Ventilation should be provided for the Cafeteria/Gymnasium by installing a constant volume air handling unit with distribution ductwork and registers. For the administration offices a fan coil air handling unit should be hung from the structure with outdoor air ducted to the unit from louvers in the window openings. Ventilation should be provided for the Auditorium by installing a constant volume air handling unit with distribution ductwork and registers. These units would be equipped with hot water heating coils and chilled water cooling coils. Steam converters would be installed in the existing boiler room with circulating pumps, distribution piping and controls to provide heating hot water for the new coils.

Terminal & Package Units - Several of the classrooms in the school building have window air conditioning units that have an anticipated service life of only 10 years. Installing a 150 ton air-cooled chiller with pumps located in a mechanical room and chilled water distribution piping could supply more reliable air conditioning for the building with a much longer service life.

A Mitsubishi split system air conditioning system provided cooling to the LAN room located on the second floor. The installation date of this unit is unknown; the anticipated service life of a split system air conditioner is 15 years. The district should budget to replace this unit within the next 7-10 years.

Controls & Instrumentation - The original pneumatic systems still provide basic control functions. Pneumatic room thermostats are intended to control the steam radiator control valves. In reality the radiator control valves are wide open and heating control is achieved via the boilers. Pneumatic control air is supplied from a duplex Honeywell compressor

Site Assessment Report - S523001;Conwell

and air dryer located in the mechanical room. The pneumatic systems are beyond their service life and require too much attention from the maintenance staff. The original control valves and pneumatic actuators are beyond their service life and should be rebuilt or replaced. These controls should be converted to DDC.

A new building automation system (BAS) with modern DDC modules and communications network should be installed to serve the HVAC systems in this building to improve reliability and energy efficiency. An interface should be provided with the preferred system in use throughout the District.

Sprinklers - The school building is NOT covered by an automatic sprinkler system. Installing a sprinkler system with quick response type heads should reduce insurance costs by providing protection for the property investment. A fire pump may be required depending on the available city water pressure.

ELECTRICAL:

Site Electrical Service - The present electrical service is from Medium Voltage overhead lines (13.2KV) on wooden poles along Clear Field St. There is a pole top transformer to step down the voltage to 120V/240V, 2-phase. Overhead lines are brought down on the face of the pole and run underground in conduit into an underground Manhole close to the school entrance. The underground conduit is extended to the building wall and penetrates into the basement in the boiler/electrical room. The main service is metered at 120V/240V. The electrical service entrance room is part of the basement of the building near Clear Field St. The utility main fused disconnect switch and utility metering is in this electrical room. There is much other electrical equipment also housed in the electrical room. These include the 75 KVA dry type phase convertor transformer, main distribution switchboard. There is no emergency generator. The main switchboard is at maximum capacity and has no more room for growth. It has reached the end of service life (50+ years), and Building Engineer complained about lack of capacity.

Distribution System and Raceway System- The distribution system is both 120V single phase and 120V/208V three phase. There are two 120V distribution panels on each floor for lighting and receptacles. These panels are old and have reached the end of service life. The raceways are mainly conduits run above the ceiling.

Receptacles - There is inadequate number of receptacles in classrooms, multi-purpose room, computer room, etc. Two receptacles on each wall of class rooms and other purpose rooms are needed. Also, a wire-mold system with receptacles on every 3' for the computer room is necessary.

Lighting- The building has a mix of T-8 and outdated T-12 lighting with fixtures that are obsolete.

Fire Alarm System – The present Fire Alarm system is adequate and it is only 2 years old.

Telephone/LAN – The present telephone system is adequate.

Public Address/Intercom/Paging – Although the PA system is not working, the school uses the telephone systems for public announcement. This system is working adequately for most part.

Clock and Program System – The present clocks are not functioning properly.

Television System - The present Television system is adequate.

Security System – There is no security system.

Emergency Power System – There is no emergency power system.

Emergency Lighting System / Exit Lighting- The emergency lighting and exit lighting is inadequate throughout each floor and stairways.

Lightning Protection System- There is adequate Lightning Protection System.

Grounding System - The present grounding system is adequate

Site Lighting - The present Site Lighting System is adequate

Site Assessment Report - S523001;Conwell

Site Video Surveillance - The present Site Video Surveillance System is inadequate with no existing cameras.

Site Paging - The present Site Paging System is adequate

GROUND(S) (SITE):

There is no parking lot at the site. Most of the stone stoops and stairs from the sidewalk have deteriorated joints with missing mortar or sealant.

Playground adjacent to the building is in poor condition, paving is cracked and deteriorated; there is no playground equipment. Original perimeter fences are generally in good condition. The landscaping is minimal along West side of the building consisting of grass and shrubs in poor condition.

ACCESSIBILITY:

The building does not have accessible entrance and accessible routes due to grade to first floor separation and absence of elevator. The toilets are equipped with accessible fixtures, partitions and accessories, such as grab bars and accessible partitions. Most of the doors in the building do not have ADA required door handles.

RECOMMENDATIONS:

- Repair deteriorated structural roof slabs at penthouse
- Repair cracks in stone and brick masonry including chimney, tuck-point walls
- Install all new roofing system including insulation; tear-down existing roofing; install flashing, counter flashing and reglets
- Replace all windows
- Replace exterior doors
- Replace all suspended acoustical ceilings
- Repair and repaint exposed ceilings
- Repair (20% area) and repaint all interior walls
- Repair & refinish hardwood flooring
- Replace VAT tile flooring
- Replace VCT tile flooring
- Install new signage throughout
- Install 3000 lb traction elevator serving all floors and basement
- Provide ADA compliant ramp at one entrance (location TBD)
- Provide wheelchair lift at main entrance stair (from stair stoop to first floor)
- Provide ADA compliant hardware on interior doors
- Resurface playground
- Reset stone stoops and stairs at all entrances
- Replace the wall hung drinking fountains and integral refrigerated coolers in the corridors and at the restrooms. These units are beyond their service life and most are NOT accessible type.
- Replace existing vertical gas fired hot water heater with new gas fired hot water heater.
- Replace existing sewage ejector pump system and piping in the basement as it frequently fails and is located next to the Kitchen and Cafeteria.
- Hire a qualified contractor to perform a detailed examination of the sanitary waste piping using visual inspection and video cameras to locate and replace any damaged piping and to further quantify the extent of potential failures.
- Hire a qualified contractor to perform a detailed examination of the rain water drainage piping using visual inspection and video cameras to locate and replace any damaged piping and to further quantify the extent of potential failures.
- Replace the two existing 4,524MBH cast iron boilers, which are beyond their service life, burners, and exhaust ductwork.
- Hire a qualified contractor to examine the steam and condensate piping, in service for over 50 years, and perform additional testing to locate and replace any damaged piping and to further quantify the extent of potential failures.
- Remove the existing cast iron steam radiators and install fan coil units with hot and chilled water coils and a dedicated outdoor air system.
- Remove the window air conditioning units and install a 150 ton air-cooled chiller with chilled water distribution piping and pumps to supply more reliable air conditioning for the building with a much longer service life.
- Provide ventilation for the Cafeteria/Gymnasium by installing a constant volume air handling unit with distribution ductwork and registers.
- Provide ventilation for the administration offices by installing a fan coil air handling unit hung from the structure with outdoor air ducted to the unit from louvers in window openings.
- Provide ventilation for the Auditorium by installing a fan coil air handling unit hung from the structure with outdoor air ducted

Site Assessment Report - S523001;Conwell

to the unit from louvers in window openings.

- Replace the pneumatic controls for the HVAC systems with modern DDC modules, valves and actuators to improve reliability and energy efficiency. Provide a new building automation system (BAS) with communication interface to the preferred system in use throughout the District.
- Install a fire protection sprinkler system with quick response type heads to reduce insurance costs by providing protection for the property. A fire pump may be required depending on the available city water pressure.
- Upgrade the existing electrical service to a new service with a new 1000 KVA dry-type Transformer, 13.2KV to 480V/277V, 3Ph. Install a new 1200A, 480V, 3 Ph. Switchboard. The new Main switchboard shall be sized to handle the existing loads plus any new HVAC loads. Install a new 500 KVA step down transformer from 480V to 120V/208V, and a main 120V/208V Panel Board for all the lighting/receptacle loads.
- Install 8 120V/208V panels to replace the existing panels (two in each floor). Also replace the power feeders, conduit & wire to the four panels from the new 120V/208V three phase main Panel Board.
- Install two receptacles in all of class rooms and other purpose rooms. Add a wire-mold system with receptacles on every 3' for the computer room.
- Install new lighting fixtures for all the class rooms, and other rooms. New fluorescent lighting (T-5) will be adequate; however, using the state-of-the-art LED lighting will improve the energy usage.
- Install a new Automated Fire Alarm System to be located in the new Electrical Room.
- Install a new clock system.
- Install a new emergency power system (100 KVA generator).
- Install new battery packed emergency lights and exit lights in all the hallways, stairways, and in each class room or other purpose rooms.
- Install a new Auditorium stage lighting and new sound system
- Install a new Security system with new cameras

Attributes:

General Attributes:

Active:	Open	Bldg Lot Tm:	Lot 1 / Tm 4
Status:	Accepted by SDP	Team:	Tm 4
Site ID:	S523001		

Site Condition Summary

The Table below shows the CI and FCI for each major system shown at the UNIFORMAT classification Level II. Note that Systems with lower FCIs require less investment than systems with higher FCIs.


Current Investment Requirement and Condition by Uniformat Classification

UNIFORMAT Classification	RSLI%	FCI %	Current Repair
A10 - Foundations	37.00 %	0.00 %	\$0.00
A20 - Basement Construction	37.00 %	0.00 %	\$0.00
B10 - Superstructure	37.00 %	3.06 %	\$162,170.72
B20 - Exterior Enclosure	58.61 %	83.51 %	\$3,093,871.47
B30 - Roofing	99.84 %	88.64 %	\$623,429.01
C10 - Interior Construction	35.11 %	6.85 %	\$93,505.45
C20 - Stairs	37.00 %	0.00 %	\$0.00
C30 - Interior Finishes	55.52 %	37.70 %	\$965,994.74
D10 - Conveying	0.00 %	240.51 %	\$476,062.05
D20 - Plumbing	41.83 %	44.38 %	\$494,445.11
D30 - HVAC	103.36 %	102.29 %	\$6,326,530.08
D40 - Fire Protection	105.71 %	177.49 %	\$795,384.24
D50 - Electrical	110.11 %	62.48 %	\$2,041,891.88
E10 - Equipment	37.14 %	0.00 %	\$0.00
E20 - Furnishings	32.50 %	0.00 %	\$0.00
G20 - Site Improvements	90.45 %	138.62 %	\$528,323.10
G40 - Site Electrical Utilities	38.61 %	0.00 %	\$0.00
Totals:	67.14 %	54.20 %	\$15,601,607.85

Condition Deficiency Priority

Facility Name	Gross Area (S.F.)	FCI %	1 - Response Time (< 2 yr)	2 - Response Time (2-3 yrs)	3 - Response Time (3-4 yrs)	4 - Response Time (4-5 yrs)	5 - Response Time (> 5 yrs)
B523001;Conwell	55,600	53.26	\$1,449,499.20	\$3,768,377.87	\$5,606,675.50	\$986,763.96	\$3,261,968.22
G523001;Grounds	24,000	108.82	\$0.00	\$163,341.94	\$0.00	\$364,981.16	\$0.00
Total:		54.20	\$1,449,499.20	\$3,931,719.81	\$5,606,675.50	\$1,351,745.12	\$3,261,968.22

Deficiencies By Priority



Executive Summary

Building condition is evaluated based on the functional systems and elements of a building and organized according to the UNIFORMAT II Elemental Classification. The grouping of these systems and elements and applying a current replacement value to them develops a representative building cost model. Cost Models are developed for similar building types and functions. Systems and their elements are evaluated based on their current replacement values, life cycles, installation dates and next renewal dates. Systems and their elements that are within their useful lives are further evaluated to identify current deficient conditions that may have a significant impact on a system's or element's remaining service life, and to determine if they are beyond their predicted expected life. The system's or element's current replacement value is based on RS Means Commercial Cost Data.

Following are the cost model's system details for this facility. The Replacement Value is the amount needed to replace the property of the same present value. The Current Repair Amount, also known as Condition Needs, represents the budgeted contractor installed costs plus owner's soft costs for the repair, replacement or renewal for a component or system level deficiency. It excludes contributing costs for other components or systems that might also be associated with the corrective actions due to packaging the work. Facility Condition Index (FCI) FCI is an industry-standard measurement of facility condition calculated as the ratio of the costs to correct a facility's deficiencies to the facility's Current Replacement Value. It ranges from 0% (new) to 100% (very poor). Condition Index (CI) is calculated as the sum of a renewable system's Remaining Service Life (RSL) divided by the sum of a system's Replacement Value (both values exclude soft-cost to simplify calculation updates) expressed as a percentage ranging from 100% (new) to 0% (expired).

Function:	Middle School
Gross Area (SF):	55,600
Year Built:	1926
Last Renovation:	
Replacement Value:	\$28,299,720
Repair Cost:	\$15,073,284.75
Total FCI:	53.26 %
Total RSLI:	66.93 %

Description:

Attributes:

General Attributes:

Active:	Open	Bldg ID:	B523001
Sewage Ejector:	No	Status:	Accepted by SDP
Site ID:	S523001		

Condition Summary

The Table below shows the CI and FCI for each major building system shown at the UNIFORMAT classification Level II. Note that Systems with lower FCIs require less investment than systems with higher FCIs.

UNIFORMAT Classification	RSLI %	FCI %	Current Repair Cost
A10 - Foundations	37.00 %	0.00 %	\$0.00
A20 - Basement Construction	37.00 %	0.00 %	\$0.00
B10 - Superstructure	37.00 %	3.06 %	\$162,170.72
B20 - Exterior Enclosure	58.61 %	83.51 %	\$3,093,871.47
B30 - Roofing	99.84 %	88.64 %	\$623,429.01
C10 - Interior Construction	35.11 %	6.85 %	\$93,505.45
C20 - Stairs	37.00 %	0.00 %	\$0.00
C30 - Interior Finishes	55.52 %	37.70 %	\$965,994.74
D10 - Conveying	0.00 %	240.51 %	\$476,062.05
D20 - Plumbing	41.83 %	44.38 %	\$494,445.11
D30 - HVAC	103.36 %	102.29 %	\$6,326,530.08
D40 - Fire Protection	105.71 %	177.49 %	\$795,384.24
D50 - Electrical	110.11 %	62.48 %	\$2,041,891.88
E10 - Equipment	37.14 %	0.00 %	\$0.00
E20 - Furnishings	32.50 %	0.00 %	\$0.00
Totals:	66.93 %	53.26 %	\$15,073,284.75

Condition Detail

This section of the report contains results of the Facility Condition Assessment. The building is separated into system components based on UNIFORMAT II classification. The columns in the System Listing table below represent the following:

1. System Code: A code that identifies the system.
2. System Description: A brief description of a system present in the building.
3. Unit Price \$: The unit price of the system.
4. UoM: The unit of measure for of the system.
5. Qty: The quantity for the system
6. Life: anticipated service life for thesystem based on Building Owners and Managers Association (BOMA) recommendations.
7. Year Installed: The date of system installation.
8. Calc Next Renewal Year: The date of system expiration based on the life, NR stands for non renewable.
9. Next Renewal Year: The suggested system expiration date by the assessor based on visual inspection.
10. CI: The Condition Index of the system.
11. FCI: The Facility Condition Index of the system.
12. RSL: Remaining Service Life.
13. eCR: eCOMET Condition Rating (not used).
14. Deficiency \$: The financial investment to repair/replace system.

System Listing

The System Listing table below lists each of the systems organized by their UNIFORMAT II classification. The assessment team was tasked with recording the most recent replacement year of each system, determining the remaining service life based on the theoretical life, and evaluating the condition to confirm the forecast next replacement year. The system listing is the basis for all data contained in the Building Assessment Report.

Additionally, a condition rating (eCR) based on the following guidelines is provided as observed at the time of the assessment.

- Excellent (E) - No noticeable distress or damage. The entire system is free from observable defect.
- Very Good (VG) - Overall no serviceability reduction for the entire system. No degradation of critical components and minor distress and defect noticeable for some but not non critical components within the system.
- Good (G) - Slight or no serviceability reduction for the entire system. There may be noticeable defects for some non critical components and slight noticeable degradation of the critical components.
- Fair (F) - Overall serviceability is degraded but adequate. There may be moderate deterioration for very few of the critical components and few of the non critical components may have severe degradation.
- Marginal (MA) - Overall serviceability and reliability loss. Most if not all of the non critical components suffer from severe degradation and a few of the critical component may have severe degradation.
- Moderate (MO) - Overall a significant serviceability loss. Most if not all the components have severe degradation with the reminder of the component showing visible distress.
- Very Poor (VP) - Overall the system is barely functional. All of the components are severely degraded.
- Non-Functional (NF) - Overall the system does not function with all the components having no serviceability and suffer from severe degradation.

System Code	System Description	Unit Price \$	UoM	Qty	Life	Year Installed	Calc Next Renewal Year	Next Renewal Year	RSLI%	FCI%	RSL	eCR	Deficiency \$	Replacement Value \$
A1010	Standard Foundations	\$23.16	S.F.	55,600	100	1926	2026	2052	37.00 %	0.00 %	37			\$1,287,696
A1030	Slab on Grade	\$5.17	S.F.	55,600	100	1926	2026	2052	37.00 %	0.00 %	37			\$287,452
A2010	Basement Excavation	\$4.36	S.F.	55,600	100	1926	2026	2052	37.00 %	0.00 %	37			\$242,416
A2020	Basement Walls	\$10.05	S.F.	55,600	100	1926	2026	2052	37.00 %	0.00 %	37			\$558,780
B1010	Floor Construction	\$85.94	S.F.	55,600	100	1926	2026	2052	37.00 %	3.39 %	37		\$162,170.72	\$4,778,264
B1020	Roof Construction	\$9.26	S.F.	55,600	100	1926	2026	2052	37.00 %	0.00 %	37			\$514,856
B2010	Exterior Walls	\$43.78	S.F.	55,600	100	1926	2026	2052	37.00 %	30.24 %	37		\$736,199.96	\$2,434,168
B2020	Exterior Windows	\$21.40	S.F.	55,600	40	1926	1966	2055	100.00 %	187.43 %	40		\$2,230,169.02	\$1,189,840
B2030	Exterior Doors	\$1.45	S.F.	55,600	25	1926	1951	2040	100.00 %	158.15 %	25		\$127,502.49	\$80,620
B3010105	Built-Up	\$37.76	S.F.	18,538	20	1995	2015	2035	100.00 %	89.06 %	20		\$623,429.01	\$699,995
B3010120	Single Ply Membrane	\$38.73	S.F.		0				0.00 %	0.00 %				\$0
B3010130	Preformed Metal Roofing	\$54.22	S.F.		0				0.00 %	0.00 %				\$0
B3010140	Shingle & Tile	\$38.73	S.F.		0				0.00 %	0.00 %				\$0
B3020	Roof Openings	\$0.06	S.F.	55,600	30	1926	1956	2035	66.67 %	0.00 %	20			\$3,336
C1010	Partitions	\$17.91	S.F.	55,600	100	1926	2026	2052	37.00 %	0.00 %	37			\$995,796
C1020	Interior Doors	\$3.51	S.F.	55,600	40	1926	1966	2027	30.00 %	32.23 %	12		\$62,892.35	\$195,156
C1030	Fittings	\$3.12	S.F.	55,600	40	1926	1966	2027	30.00 %	17.65 %	12		\$30,613.10	\$173,472
C2010	Stair Construction	\$1.41	S.F.	55,600	100	1926	2026	2052	37.00 %	0.00 %	37			\$78,396

Site Assessment Report - B523001;Conwell

System Code	System Description	Unit Price \$	UoM	Qty	Life	Year Installed	Calc Next Renewal Year	Next Renewal Year	RSLI%	FCI%	RSL	eCR	Deficiency \$	Replacement Value \$
C3010230	Paint & Covering	\$13.21	S.F.	55,600	10	1926	1936	2023	80.00 %	29.11 %	8		\$213,789.60	\$734,476
C3010231	Vinyl Wall Covering	\$0.97	S.F.	55,600	15	1926	1941	2028	86.67 %	0.00 %	13			\$53,932
C3010232	Wall Tile	\$2.63	S.F.	55,600	30	1926	1956	2028	43.33 %	0.00 %	13			\$146,228
C3020411	Carpet	\$7.30	S.F.		10				0.00 %	0.00 %				\$0
C3020412	Terrazzo & Tile	\$75.52	S.F.		50				0.00 %	0.00 %				\$0
C3020413	Vinyl Flooring	\$9.68	S.F.	13,900	20	1926	1946	2037	110.00 %	132.11 %	22		\$177,750.75	\$134,552
C3020414	Wood Flooring	\$22.27	S.F.	14,700	25	1926	1951	2027	48.00 %	55.49 %	12		\$181,645.25	\$327,369
C3020415	Concrete Floor Finishes	\$0.97	S.F.		50				0.00 %	0.00 %				\$0
C3030	Ceiling Finishes	\$20.97	S.F.	55,600	25	1926	1951	2024	36.00 %	33.69 %	9		\$392,809.14	\$1,165,932
D1010	Elevators and Lifts	\$3.56	S.F.	55,600	35				0.00 %	240.51 %			\$476,062.05	\$197,936
D2010	Plumbing Fixtures	\$13.52	S.F.	55,600	35	1926	1961	2025	28.57 %	8.48 %	10		\$63,707.91	\$751,712
D2020	Domestic Water Distribution	\$1.68	S.F.	55,600	25	1926	1951	2025	40.00 %	26.20 %	10		\$24,473.55	\$93,408
D2030	Sanitary Waste	\$2.52	S.F.	55,600	30	1926	1956	2047	106.67 %	216.57 %	32		\$303,445.67	\$140,112
D2040	Rain Water Drainage	\$2.32	S.F.	55,600	30	1926	1956	2030	50.00 %	79.71 %	15		\$102,817.98	\$128,992
D3020	Heat Generating Systems	\$18.67	S.F.	55,600	35	1960	1995	2052	105.71 %	93.12 %	37		\$966,604.67	\$1,038,052
D3030	Cooling Generating Systems	\$24.48	S.F.	55,600	28			2045	107.14 %	63.79 %	30		\$868,290.77	\$1,361,088
D3040	Distribution Systems	\$42.99	S.F.	55,600	25	1926	1951	2042	108.00 %	138.02 %	27		\$3,298,900.87	\$2,390,244
D3050	Terminal & Package Units	\$11.60	S.F.	55,600	15	2010	2025		66.67 %	0.00 %	10			\$644,960
D3060	Controls & Instrumentation	\$13.50	S.F.	55,600	20	1926	1946	2037	110.00 %	158.90 %	22		\$1,192,733.77	\$750,600
D4010	Sprinklers	\$7.05	S.F.	55,600	35			2052	105.71 %	202.91 %	37		\$795,384.24	\$391,980
D4020	Standpipes	\$1.01	S.F.	55,600	35			2052	105.71 %	0.00 %	37			\$56,156
D5010	Electrical Service/Distribution	\$9.70	S.F.	55,600	30	1926	1956	2047	106.67 %	77.62 %	32		\$418,636.06	\$539,320
D5020	Lighting and Branch Wiring	\$34.68	S.F.	55,600	20	1926	1946	2037	110.00 %	51.94 %	22		\$1,001,478.40	\$1,928,208
D5030	Communications and Security	\$12.99	S.F.	55,600	15	1926	1941	2032	113.33 %	55.64 %	17		\$401,859.88	\$722,244
D5090	Other Electrical Systems	\$1.41	S.F.	55,600	30	1926	1956	2047	106.67 %	280.52 %	32		\$219,917.54	\$78,396
E1020	Institutional Equipment	\$4.82	S.F.	55,600	35	1926	1961	2028	37.14 %	0.00 %	13			\$267,992
E1090	Other Equipment	\$11.10	S.F.	55,600	35	1926	1961	2028	37.14 %	0.00 %	13			\$617,160
E2010	Fixed Furnishings	\$2.13	S.F.	55,600	40	1926	1966	2028	32.50 %	0.00 %	13			\$118,428
Total									66.93 %	53.26 %			\$15,073,284.75	\$28,299,720

System Notes

The facility description in the site executive summary contains an overview of each system. The notes listed below provide additional information on select systems found within the facility.

System: D5010 - Electrical Service/Distribution

This system contains no images

Note: Two 75 KVA Phase changer transformer (single phase to three phase).

Renewal Schedule

eCOMET forecasts future Capital Renewal funding needed to address expiring systems based on the Next Renewal year found in the Cost Models. A 3% annual inflation factor is applied to the costs for systems expiring in future years. The table below reflects recommended Capital Renewal funding needs over the next 10 years. Note: Cells with a zero value indicate systems for which renewal is not scheduled in that year.

Inflation Rate: 3%

System	Current Deficiencies	2016	2017	2018	2019	2020	2021	2022	2023	2024	2025	Total
Total:	\$15,073,285	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$1,023,454	\$1,673,404	\$2,202,797	\$19,972,940
* A - Substructure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A10 - Foundations	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
A1010 - Standard Foundations	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
A1030 - Slab on Grade	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A20 - Basement Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
A2010 - Basement Excavation	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
A2020 - Basement Walls	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B - Shell	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B10 - Superstructure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B1010 - Floor Construction	\$162,171	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$162,171
B1020 - Roof Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B20 - Exterior Enclosure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B2010 - Exterior Walls	\$736,200	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$736,200
B2020 - Exterior Windows	\$2,230,169	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$2,230,169
B2030 - Exterior Doors	\$127,502	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$127,502
B30 - Roofing	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3010 - Roof Coverings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3010105 - Built-Up	\$623,429	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$623,429
B3010120 - Single Ply Membrane	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3010130 - Preformed Metal Roofing	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3010140 - Shingle & Tile	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3020 - Roof Openings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C - Interiors	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C10 - Interior Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C1010 - Partitions	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0

Site Assessment Report - B523001;Conwell

C1020 - Interior Doors	\$62,892	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$62,892
C1030 - Fittings	\$30,613	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$30,613
C20 - Stairs	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C2010 - Stair Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C30 - Interior Finishes	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C3010 - Wall Finishes	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C3010230 - Paint & Covering	\$213,790	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$1,023,454	\$0	\$0	\$1,237,244
C3010231 - Vinyl Wall Covering	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C3010232 - Wall Tile	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C3020 - Floor Finishes	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C3020411 - Carpet	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C3020412 - Terrazzo & Tile	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C3020413 - Vinyl Flooring	\$177,751	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$177,751
C3020414 - Wood Flooring	\$181,645	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$181,645
C3020415 - Concrete Floor Finishes	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C3030 - Ceiling Finishes	\$392,809	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$1,673,404	\$0	\$2,066,213
D - Services	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D10 - Conveying	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D1010 - Elevators and Lifts	\$476,062	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$476,062
D20 - Plumbing	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D2010 - Plumbing Fixtures	\$63,708	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$1,111,262	\$1,174,970
D2020 - Domestic Water Distribution	\$24,474	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$138,086	\$162,560
D2030 - Sanitary Waste	\$303,446	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$303,446
D2040 - Rain Water Drainage	\$102,818	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$102,818
D30 - HVAC	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D3020 - Heat Generating Systems	\$966,605	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$966,605
D3030 - Cooling Generating Systems	\$868,291	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$868,291
D3040 - Distribution Systems	\$3,298,901	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$3,298,901
D3050 - Terminal & Package Units	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$953,450	\$953,450
D3060 - Controls & Instrumentation	\$1,192,734	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$1,192,734
D40 - Fire Protection	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D4010 - Sprinklers	\$795,384	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$795,384
D4020 - Standpipes	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0


Site Assessment Report - B523001;Conwell

D50 - Electrical	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5010 - Electrical Service/Distribution	\$418,636	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$418,636
D5020 - Lighting and Branch Wiring	\$1,001,478	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$1,001,478
D5030 - Communications and Security	\$401,860	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$401,860
D5090 - Other Electrical Systems	\$219,918	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$219,918
E - Equipment & Furnishings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E10 - Equipment	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E1020 - Institutional Equipment	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E1090 - Other Equipment	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E20 - Furnishings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E2010 - Fixed Furnishings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0

* Indicates non-renewable system

Forecasted Sustainment Requirement

The following chart shows the current building deficiencies and forecasting sustainment requirements over the next ten years.




10 Year FCI Forecast by Investment Scenario

The chart below illustrates the effect of various investment levels on the building FCI for the next 10 years. The levels of investment shown below include:

- Current FCI: a variable investment amount based on renewing expired systems to maintain the current FCI for the building
- 2% Investment: an annual investment of 2% of the replacement value of the building, escalated for inflation
- 4% Investment: an annual investment of 4% of the replacement value of the building, escalated for inflation


Facility Investment vs. FCI Forecast



Year	Investment Amount Current FCI - 53.26%	2% Investment		4% Investment	
		Amount	FCI	Amount	FCI
2016	\$0	\$582,974.00	51.26 %	\$1,165,948.00	49.26 %
2017	\$11,122,525	\$600,463.00	86.31 %	\$1,200,927.00	82.31 %
2018	\$0	\$618,477.00	84.31 %	\$1,236,955.00	78.31 %
2019	\$0	\$637,032.00	82.31 %	\$1,274,063.00	74.31 %
2020	\$0	\$656,143.00	80.31 %	\$1,312,285.00	70.31 %
2021	\$0	\$675,827.00	78.31 %	\$1,351,654.00	66.31 %
2022	\$0	\$696,102.00	76.31 %	\$1,392,203.00	62.31 %
2023	\$1,023,454	\$716,985.00	77.16 %	\$1,433,970.00	61.16 %
2024	\$1,673,404	\$738,494.00	79.70 %	\$1,476,989.00	61.70 %
2025	\$2,202,797	\$760,649.00	83.49 %	\$1,521,298.00	63.49 %
Total:	\$16,022,181	\$6,683,146.00		\$13,366,292.00	

Deficiency Summary by System


Current deficiencies included assemblies that have reached or exceeded their design life or components of the assemblies that are in need of repair. Assemblies that have reached their design life are identified as current deficiencies and assigned the distress 'Beyond Useful Life'. The following chart lists all current deficiencies associated with this facility.



Budget Estimate Total: \$15,073,284.75

Deficiency Summary by Priority

The following chart shows the total repair costs broken down by priority. Assessors assigned deficiencies within eCOMET to one of the following priority categories:



Budget Estimate Total: \$15,073,284.75


Deficiency By Priority Investment Table

The table below shows the current investment cost grouped by deficiency priority and building system.

System Code	System Description	1 - Response Time (< 2 yr)	2 - Response Time (2-3 yrs)	3 - Response Time (3-4 yrs)	4 - Response Time (4-5 yrs)	5 - Response Time (> 5 yrs)	Total
B1010	Floor Construction	\$0.00	\$162,170.72	\$0.00	\$0.00	\$0.00	\$162,170.72
B2010	Exterior Walls	\$0.00	\$0.00	\$736,199.96	\$0.00	\$0.00	\$736,199.96
B2020	Exterior Windows	\$0.00	\$2,230,169.02	\$0.00	\$0.00	\$0.00	\$2,230,169.02
B2030	Exterior Doors	\$0.00	\$0.00	\$0.00	\$127,502.49	\$0.00	\$127,502.49
B3010105	Built-Up	\$623,429.01	\$0.00	\$0.00	\$0.00	\$0.00	\$623,429.01
C1020	Interior Doors	\$0.00	\$0.00	\$62,892.35	\$0.00	\$0.00	\$62,892.35
C1030	Fittings	\$0.00	\$0.00	\$0.00	\$0.00	\$30,613.10	\$30,613.10
C3010230	Paint & Covering	\$0.00	\$0.00	\$0.00	\$213,789.60	\$0.00	\$213,789.60
C3020413	Vinyl Flooring	\$0.00	\$51,566.67	\$0.00	\$0.00	\$126,184.08	\$177,750.75
C3020414	Wood Flooring	\$0.00	\$0.00	\$0.00	\$0.00	\$181,645.25	\$181,645.25
C3030	Ceiling Finishes	\$0.00	\$0.00	\$221,711.72	\$171,097.42	\$0.00	\$392,809.14
D1010	Elevators and Lifts	\$0.00	\$0.00	\$476,062.05	\$0.00	\$0.00	\$476,062.05
D2010	Plumbing Fixtures	\$0.00	\$60,633.52	\$3,074.39	\$0.00	\$0.00	\$63,707.91
D2020	Domestic Water Distribution	\$0.00	\$24,473.55	\$0.00	\$0.00	\$0.00	\$24,473.55
D2030	Sanitary Waste	\$30,685.95	\$272,759.72	\$0.00	\$0.00	\$0.00	\$303,445.67
D2040	Rain Water Drainage	\$0.00	\$0.00	\$102,817.98	\$0.00	\$0.00	\$102,817.98
D3020	Heat Generating Systems	\$0.00	\$966,604.67	\$0.00	\$0.00	\$0.00	\$966,604.67
D3030	Cooling Generating Systems	\$0.00	\$0.00	\$0.00	\$0.00	\$868,290.77	\$868,290.77
D3040	Distribution Systems	\$0.00	\$0.00	\$2,436,399.62	\$0.00	\$862,501.25	\$3,298,900.87
D3060	Controls & Instrumentation	\$0.00	\$0.00	\$0.00	\$0.00	\$1,192,733.77	\$1,192,733.77
D4010	Sprinklers	\$795,384.24	\$0.00	\$0.00	\$0.00	\$0.00	\$795,384.24
D5010	Electrical Service/Distribution	\$0.00	\$0.00	\$216,965.85	\$201,670.21	\$0.00	\$418,636.06
D5020	Lighting and Branch Wiring	\$0.00	\$0.00	\$947,362.91	\$54,115.49	\$0.00	\$1,001,478.40
D5030	Communications and Security	\$0.00	\$0.00	\$183,271.13	\$218,588.75	\$0.00	\$401,859.88
D5090	Other Electrical Systems	\$0.00	\$0.00	\$219,917.54	\$0.00	\$0.00	\$219,917.54
	Total:	\$1,449,499.20	\$3,768,377.87	\$5,606,675.50	\$986,763.96	\$3,261,968.22	\$15,073,284.75

Deficiency Summary by Category

The following chart shows the total repair costs broken down by deficiency categories. Assessors assigned deficiencies to one of the following categories:



Deficiency Details by Priority

The deficiency detail notes listed below provide additional information on identified deficiencies found within the facility.

Priority 1 - Response Time (< 2 yr):

System: B3010105 - Built-Up



Location: Exterior

Distress: Building Envelope Integrity

Category: 3 - Operations / Maint.

Priority: 1 - Response Time (< 2 yr)

Correction: Remove and Replace Built Up Roof

Qty: 18,400.00

Unit of Measure: S.F.

Estimate: \$623,429.01

Assessor Name: System

Date Created: 10/04/2015

Notes: Install all new roofing system including insulation; tear-down existing roofing; install flashing, counter flashing and reglets

System: D2030 - Sanitary Waste



Location: Boiler Room

Distress: Health Hazard / Risk

Category: 1 - Health & Safety

Priority: 1 - Response Time (< 2 yr)

Correction: Replace sanitary sewage ejector pit and pumps. (48" dia.)

Qty: 1.00

Unit of Measure: Ea.

Estimate: \$30,685.95

Assessor Name: System

Date Created: 08/20/2015

Notes: Replace existing sewage ejector pump system and piping in the basement as it frequently fails and is located next to the Kitchen and Cafeteria.

System: D4010 - Sprinklers



Location: Throughout Building

Distress: Life Safety / NFPA / PFD

Category: 1 - Health & Safety

Priority: 1 - Response Time (< 2 yr)

Correction: Install a fire protection sprinkler system

Qty: 55,600.00

Unit of Measure: S.F.

Estimate: \$795,384.24

Assessor Name: System

Date Created: 08/20/2015

Notes: Install a fire protection sprinkler system with quick response type heads to reduce insurance costs by providing protection for the property. A fire pump may be required depending on the available city water pressure.

Priority 2 - Response Time (2-3 yrs):

System: B1010 - Floor Construction



Location: Roof slab

Distress: Damaged

Category: 3 - Operations / Maint.

Priority: 2 - Response Time (2-3 yrs)

Correction: Repair rebar and epoxy grout exposed rebar on the underside of floors and floor beams

Qty: 2,000.00

Unit of Measure: S.F.

Estimate: \$162,170.72

Assessor Name: System

Date Created: 10/04/2015

Notes: Repair deteriorated structural roof slabs at penthouse

System: B2020 - Exterior Windows



Location: Exterior

Distress: Beyond Service Life

Category: 3 - Operations / Maint.

Priority: 2 - Response Time (2-3 yrs)

Correction: Remove and replace aluminum windows - pick the appropriate size and style and insert the number of units

Qty: 332.00

Unit of Measure: Ea.

Estimate: \$2,230,169.02

Assessor Name: System

Date Created: 10/04/2015

Notes: Replace all windows

System: C3020413 - Vinyl Flooring



Location: Interior

Distress: Beyond Service Life

Category: 3 - Operations / Maint.

Priority: 2 - Response Time (2-3 yrs)

Correction: Remove VAT and replace with VCT - SF of area

Qty: 3,400.00

Unit of Measure: S.F.

Estimate: \$51,566.67

Assessor Name: System

Date Created: 10/04/2015

Notes: Replace VAT tile flooring

System: D2010 - Plumbing Fixtures



Location: Corridors

Distress: Beyond Service Life

Category: 3 - Operations / Maint.

Priority: 2 - Response Time (2-3 yrs)

Correction: Remove and Replace Water Fountains - without ADA new recessed alcove

Qty: 8.00

Unit of Measure: Ea.

Estimate: \$60,633.52

Assessor Name: System

Date Created: 08/20/2015

Notes: Replace the wall hung drinking fountains and integral refrigerated coolers in the corridors and at the restrooms. These units are beyond their service life and most are NOT accessible type.

System: D2020 - Domestic Water Distribution



Location: Boiler Room

Distress: Beyond Service Life

Category: 3 - Operations / Maint.

Priority: 2 - Response Time (2-3 yrs)

Correction: Replace instantaneous water heater

Qty: 1.00

Unit of Measure: Ea.

Estimate: \$24,473.55

Assessor Name: System

Date Created: 08/20/2015

Notes: Replace existing vertical gas fired hot water heater with new gas fired hot water heater.

System: D2030 - Sanitary Waste



Location: Throughout Building

Distress: Beyond Service Life

Category: 3 - Operations / Maint.

Priority: 2 - Response Time (2-3 yrs)

Correction: Inspect sanitary waste piping and replace damaged sections. (+50KSF)

Qty: 55,600.00

Unit of Measure: S.F.

Estimate: \$272,759.72

Assessor Name: System

Date Created: 08/20/2015

Notes: Hire a qualified contractor to perform a detailed examination of the sanitary waste piping using visual inspection and video cameras to locate and replace any damaged piping and to further quantify the extent of potential failures.

System: D3020 - Heat Generating Systems



Location: Boiler Room

Distress: Beyond Service Life

Category: 3 - Operations / Maint.

Priority: 2 - Response Time (2-3 yrs)

Correction: Replace boiler, cast iron sectional (150 HP)

Qty: 2.00

Unit of Measure: Ea.

Estimate: \$966,604.67

Assessor Name: System

Date Created: 08/20/2015

Notes: Replace the two existing 4,524MBH cast iron boilers, which are beyond their service life, burners, and exhaust ductwork.

Priority 3 - Response Time (3-4 yrs):

System: B2010 - Exterior Walls



Location: Exterior

Distress: Building Envelope Integrity

Category: 3 - Operations / Maint.

Priority: 3 - Response Time (3-4 yrs)

Correction: Repair cracks in masonry - replace missing mortar and repoint - SF of wall area

Qty: 22,800.00

Unit of Measure: S.F.


Estimate: \$736,199.96

Assessor Name: System

Date Created: 10/04/2015

Notes: Repair cracks in stone and brick masonry including chimney, tuck-point walls

System: C1020 - Interior Doors



Location: Interior

Distress: Accessibility

Category: 2 - Code Compliance

Priority: 3 - Response Time (3-4 yrs)

Correction: Replace door knobs with compliant lever type

Qty: 113.00

Unit of Measure: Ea.

Estimate: \$62,892.35

Assessor Name: System

Date Created: 10/04/2015

Notes: Provide ADA compliant hardware on interior doors

System: C3030 - Ceiling Finishes



Location: Interior

Distress: Beyond Service Life

Category: 3 - Operations / Maint.

Priority: 3 - Response Time (3-4 yrs)

Correction: Remove and replace suspended acoustic ceilings - lighting not included

Qty: 14,700.00

Unit of Measure: S.F.

Estimate: \$221,711.72

Assessor Name: System

Date Created: 10/04/2015

Notes: Replace all suspended acoustical ceilings

System: D1010 - Elevators and Lifts

This deficiency has no image.

Location: Interior

Distress: Accessibility

Category: 2 - Code Compliance

Priority: 3 - Response Time (3-4 yrs)

Correction: Add interior elevator - 4 floors - adjust the electrical run lengths to hook up the elevator

Qty: 1.00

Unit of Measure: Ea.

Estimate: \$392,870.03

Assessor Name: System

Date Created: 10/04/2015

Notes: Install 3000 lb traction elevator serving all floors and basement

System: D1010 - Elevators and Lifts

This deficiency has no image.

Location: Interior

Distress: Accessibility

Category: 2 - Code Compliance

Priority: 3 - Response Time (3-4 yrs)

Correction: Add interior hydraulic elevator - 2 floors - adjust the electrical run lengths to hook up the elevator

Qty: 1.00

Unit of Measure: Ea.

Estimate: \$83,192.02

Assessor Name: System

Date Created: 10/04/2015

Notes: Provide wheelchair lift at main entrance stair (from stair stoop to first floor)

System: D2010 - Plumbing Fixtures



Location: Restrooms

Distress: Accessibility

Category: 2 - Code Compliance

Priority: 3 - Response Time (3-4 yrs)

Correction: Remove and replace or replace lavatory - quantify accessible if required

Qty: 18.00

Unit of Measure: Ea.

Estimate: \$3,074.39

Assessor Name: System

Date Created: 08/20/2015

Notes: Replace the lavatories in the restrooms with new code compliant fixtures.

System: D2040 - Rain Water Drainage



Location: Throughout Building

Distress: Beyond Service Life

Category: 3 - Operations / Maint.

Priority: 3 - Response Time (3-4 yrs)

Correction: Replace roof drains - per drain including piping

Qty: 4.00

Unit of Measure: Ea.

Estimate: \$102,817.98

Assessor Name: System

Date Created: 08/20/2015

Notes: Hire a qualified contractor to perform a detailed examination of the rain water drainage piping using visual inspection and video cameras to locate and replace any damaged piping and to further quantify the extent of potential failures.

System: D3040 - Distribution Systems



Location: Throuout Building

Distress: Building / MEP Codes

Category: 2 - Code Compliance

Priority: 3 - Response Time (3-4 yrs)

Correction: Provide classroom FC units and dedicated OA ventilation system. (20 clsrms)

Qty: 23.00

Unit of Measure: C

Estimate: \$1,910,402.80

Assessor Name: System

Date Created: 08/20/2015

Notes: Remove the existing cast iron steam radiators and install fan coil units with hot and chilled water coils and a dedicated outdoor air system.

System: D3040 - Distribution Systems



Location: Throughout Building

Distress: Beyond Service Life

Category: 3 - Operations / Maint.

Priority: 3 - Response Time (3-4 yrs)

Correction: Perform testing to identify and replace damaged steam and condensate piping.

Qty: 55,600.00

Unit of Measure: S.F.

Estimate: \$525,996.82

Assessor Name: System

Date Created: 08/20/2015

Notes: Hire a qualified contractor to examine the steam and condensate piping, in service for over 50 years, and perform additional testing to locate and replace any damaged piping and to further quantify the extent of potential failures.

System: D5010 - Electrical Service/Distribution



Location: Throughout the building

Distress: Beyond Service Life

Category: 3 - Operations / Maint.

Priority: 3 - Response Time (3-4 yrs)

Correction: Add Panelboard

Qty: 1.00

Unit of Measure: Ea.


Estimate: \$216,965.85

Assessor Name: System

Date Created: 08/11/2015

Notes: . Install 8 120V/208V panels to replace the existing panels (two in each floor). Also replace the power feeders, conduit wire to the four panels from the new 120V/208V three phase main Panel Board.

System: D5020 - Lighting and Branch Wiring



Location: Throughout the building

Distress: Beyond Service Life

Category: 3 - Operations / Maint.

Priority: 3 - Response Time (3-4 yrs)

Correction: Replace Lighting Fixtures (SF)

Qty: 0.00

Unit of Measure: S.F.


Estimate: \$599,885.10

Assessor Name: System

Date Created: 08/11/2015

Notes: Install new lighting fixtures for all the class rooms, and other rooms. New fluorescent lighting (T-5) will be adequate, however, using the state-of-the-art LED lighting will improve the energy usage.

System: D5020 - Lighting and Branch Wiring



Location: Throughout the building

Distress: Beyond Service Life

Category: 3 - Operations / Maint.

Priority: 3 - Response Time (3-4 yrs)

Correction: Replace Wiring Devices (SF) - surface mounted conduit and boxes

Qty: 0.00

Unit of Measure: S.F.

Estimate: \$347,477.81

Assessor Name: System

Date Created: 08/11/2015

Notes: Install min of two receptacles (12' center) on each wall of the classrooms and other purpose rooms. Add a wire-mold system with receptacles on every 3' for the computer room.

System: D5030 - Communications and Security



Location: Throughout the building

Distress: Building / MEP Codes

Category: 2 - Code Compliance

Priority: 3 - Response Time (3-4 yrs)

Correction: Replace fire alarm system

Qty: 1.00

Unit of Measure: S.F.

Estimate: \$183,271.13

Assessor Name: System

Date Created: 08/11/2015

Notes: Install a new Automated Fire Alarm System to be located in the new Electrical Room.

System: D5090 - Other Electrical Systems



Location: Electrical Room (in the basement)

Distress: Building / MEP Codes

Category: 2 - Code Compliance

Priority: 3 - Response Time (3-4 yrs)

Correction: Add Standby Generator System

Qty: 1.00

Unit of Measure: Ea.


Estimate: \$111,405.76

Assessor Name: System

Date Created: 08/11/2015

Notes: Install a new emergency power system (100 KVA generator). The 100 KVA will have adequate capacity for any new loads including a new elevator, etc. Notes: 20% was added to cover the cost of conduit wiring. A typical emergency generator picture is shown since there is no emergency generator presently in the school. in school.

System: D5090 - Other Electrical Systems



Location: Throughout the building

Distress: Life Safety / NFPA / PFD

Category: 1 - Health & Safety

Priority: 3 - Response Time (3-4 yrs)

Correction: Add Emergency/Exit Lighting

Qty: 1.00

Unit of Measure: Ea.

Estimate: \$108,511.78

Assessor Name: System

Date Created: 08/11/2015

Notes: Install new battery packed emergency lights and exit lights in all the hallways, stairways, and in each class room or other purpose rooms.

Priority 4 - Response Time (4-5 yrs):

System: B2030 - Exterior Doors



Location: Exterior

Distress: Beyond Service Life

Category: 3 - Operations / Maint.

Priority: 4 - Response Time (4-5 yrs)

Correction: Remove and replace exterior doors - per leaf

Qty: 14.00

Unit of Measure: Ea.

Estimate: \$127,502.49

Assessor Name: System

Date Created: 10/04/2015

Notes: Replace exterior doors

System: C3010230 - Paint & Covering



Location: Interior

Distress: Beyond Service Life

Category: 3 - Operations / Maint.

Priority: 4 - Response Time (4-5 yrs)

Correction: Repair substrate and repaint interior walls - SF of wall surface

Qty: 40,000.00

Unit of Measure: S.F.

Estimate: \$213,789.60

Assessor Name: System

Date Created: 10/04/2015

Notes: Repair (20% area) and repaint all interior walls

System: C3030 - Ceiling Finishes



Location: Interior

Distress: Damaged

Category: 3 - Operations / Maint.

Priority: 4 - Response Time (4-5 yrs)

Correction: Repair and resurface plaster ceilings - 2 coats plaster

Qty: 29,800.00

Unit of Measure: S.F.

Estimate: \$171,097.42

Assessor Name: System

Date Created: 10/04/2015

Notes: Repair and repaint exposed ceilings

System: D5010 - Electrical Service/Distribution



Location: Electrical room inside the basement

Distress: Beyond Service Life

Category: 3 - Operations / Maint.

Priority: 4 - Response Time (4-5 yrs)

Correction: Add Electrical Switchgear and Distribution System

Qty: 0.00

Unit of Measure: Ea.


Estimate: \$201,670.21

Assessor Name: System

Date Created: 08/10/2015

Notes: Upgrade the existing electrical service to a new service with a new 1000 KVA dry-type Transformer, 13.2KV to 480V/277V, 3Ph. Install a new 1200A, 480V, 3 Ph. Switchboard. The new Main switchboard shall be sized to handle the existing loads plus any new HVAC loads. Install a new 500 KVA step down transformer from 480V to 120V/208V, and a main 120V/208V Panel Board for all the lighting/receptacle loads.

System: D5020 - Lighting and Branch Wiring



Location: In the Auditorium

Distress: Inadequate

Category: 4 - Capital Improvement

Priority: 4 - Response Time (4-5 yrs)

Correction: Add Lighting Fixtures

Qty: 1.00

Unit of Measure: Ea.


Estimate: \$54,115.49

Assessor Name: System

Date Created: 08/11/2015

Notes: Install a new Auditorium stage lighting and new sound system

System: D5030 - Communications and Security



Location: Throughout the building

Distress: Beyond Service Life

Category: 3 - Operations / Maint.

Priority: 4 - Response Time (4-5 yrs)

Correction: Add/Replace Clock System or Components

Qty: 0.00

Unit of Measure: Ea.

Estimate: \$123,816.25

Assessor Name: System

Date Created: 08/11/2015

Notes: Install a new clock system. Note: 10% was added to cover the cost of wiring.

System: D5030 - Communications and Security



Location: Indors/ Outdoors

Distress: Security Issue

Category: 1 - Health & Safety

Priority: 4 - Response Time (4-5 yrs)

Correction: Add/Replace Security System

Qty: 1.00

Unit of Measure: Ea.

Estimate: \$94,772.50


Assessor Name: System

Date Created: 08/11/2015

Notes: Install a new Security system with new cameras.

Priority 5 - Response Time (> 5 yrs):

System: C1030 - Fittings



Location: Interior

Distress: Building / MEP Codes

Category: 2 - Code Compliance

Priority: 5 - Response Time (> 5 yrs)

Correction: Replace missing or damaged signage - insert the number of rooms

Qty: 113.00

Unit of Measure: Ea.

Estimate: \$30,613.10

Assessor Name: System

Date Created: 10/04/2015

Notes: Install new signage throughout to meet requirements

System: C3020413 - Vinyl Flooring



Location: Interior

Distress: Beyond Service Life

Category: 3 - Operations / Maint.

Priority: 5 - Response Time (> 5 yrs)

Correction: Remove and replace VCT

Qty: 10,500.00

Unit of Measure: S.F.

Estimate: \$126,184.08

Assessor Name: System

Date Created: 10/04/2015

Notes: Replace VCT tile flooring

System: C3020414 - Wood Flooring



Location: Interior

Distress: Beyond Service Life

Category: 3 - Operations / Maint.

Priority: 5 - Response Time (> 5 yrs)

Correction: Remove and replace partial area of wood flooring and refinish entire floor - set replacement area

Qty: 14,700.00

Unit of Measure: S.F.

Estimate: \$181,645.25

Assessor Name: System

Date Created: 10/04/2015

Notes: Repair refinish hardwood flooring

System: D3030 - Cooling Generating Systems



Location: Throughout Buildin

Distress: Inadequate

Category: 4 - Capital Improvement

Priority: 5 - Response Time (> 5 yrs)

Correction: Install chilled water system with distribution piping and pumps. (+75KSF)

Qty: 55,600.00

Unit of Measure: S.F.

Estimate: \$868,290.77

Assessor Name: System

Date Created: 08/20/2015

Notes: Remove the window air conditioning units and install a 150 ton air-cooled chiller with chilled water distribution piping and pumps to supply more reliable air conditioning for the building with a much longer service life.

System: D3040 - Distribution Systems



Location: Auditorium

Distress: Building / MEP Codes

Category: 2 - Code Compliance

Priority: 5 - Response Time (> 5 yrs)

Correction: Install HVAC unit for Auditorium (200 seat).

Qty: 300.00

Unit of Measure: Seat

Estimate: \$427,628.15

Assessor Name: System

Date Created: 08/20/2015

Notes: Provide ventilation for the Auditorium by installing a fan coil air handling unit hung from the structure with outdoor air ducted to the unit from louvers in window openings.

System: D3040 - Distribution Systems



Location: Cafeteria/Gymnasium

Distress: Building / MEP Codes

Category: 2 - Code Compliance

Priority: 5 - Response Time (> 5 yrs)

Correction: Install HVAC unit for Cafeteria (850 students).

Qty: 483.00

Unit of Measure: Pr.


Estimate: \$225,819.31

Assessor Name: System

Date Created: 08/20/2015

Notes: Provide ventilation for the Cafeteria/Gymnasium by installing a constant volume air handling unit with distribution ductwork and registers.

System: D3040 - Distribution Systems



Location: Administration

Distress: Building / MEP Codes

Category: 2 - Code Compliance

Priority: 5 - Response Time (> 5 yrs)

Correction: Install HVAC unit for Administration (2000 students).

Qty: 483.00

Unit of Measure: Pr.

Estimate: \$209,053.79

Assessor Name: System

Date Created: 08/20/2015

Notes: Provide ventilation for the administration offices by installing a fan coil air handling unit hung from the structure with outdoor air ducted to the unit from louvers in window openings.

System: D3060 - Controls & Instrumentation



Location: Throughout Building

Distress: Inadequate

Category: 4 - Capital Improvement

Priority: 5 - Response Time (> 5 yrs)

Correction: Replace pneumatic controls with DDC (75KSF)

Qty: 55,600.00

Unit of Measure: S.F.

Estimate: \$1,192,733.77

Assessor Name: System

Date Created: 08/20/2015

Notes: Replace the pneumatic controls for the HVAC systems with modern DDC modules, valves and actuators to improve reliability and energy efficiency. Provide a new building automation system (BAS) with communication interface to the preferred system in use throughout the District.

Equipment Inventory

The following table represents the inventory details of the inventory found in the building, which fall under the following subsystems:

Subsystem	Inventory	Qty	UoM	Location	Manufacturer	Model Number	Serial Number	Barcode	Life	Install Date	Next Renewal	Raw Cost	Inventory Cost
D2020 Domestic Water Distribution	Pump, pressure booster system, 1 HP pump, includes diaphragm tank, control and pressure switch	2.00	Ea.	Boiler Room	Armstrong				25	2010	2035	\$9,262.50	\$20,377.50
D3020 Heat Generating Systems	Boiler, gas/oil combination, cast iron, hot water, gross output, 4672 MBH, includes burners, controls and insulated jacket, packaged	2.00	Ea.	Boiler Room	Weil-McLain	94			35	1960	1995	\$102,205.50	\$224,852.10
D3020 Heat Generating Systems	Boiler, gas/oil combination, cast iron, hot water, gross output, 4672 MBH, includes burners, controls and insulated jacket, packaged	2.00	Ea.	Boiler Room	Weil-McLain	94			35	1960	1995	\$102,205.50	\$224,852.10
D5010 Electrical Service/Distribution	Switchgear installation, incl switchboard, panels & circuit breaker, 120/208 V, 1 phase, 400 A	1.00	Ea.						20	1926	2017	\$13,848.30	\$15,233.13
D5010 Electrical Service/Distribution	Transformers, 4800 volts to 480/277 volts, 500 kVA	1.00	Ea.	electrical room					30	1926	1956	\$65,205.00	\$71,725.50
												Total:	\$557,040.33

Executive Summary

Building condition is evaluated based on the functional systems and elements of a building and organized according to the UNIFORMAT II Elemental Classification. The grouping of these systems and elements and applying a current replacement value to them develops a representative building cost model. Cost Models are developed for similar building types and functions. Systems and their elements are evaluated based on their current replacement values, life cycles, installation dates and next renewal dates. Systems and their elements that are within their useful lives are further evaluated to identify current deficient conditions that may have a significant impact on a system's or element's remaining service life, and to determine if they are beyond their predicted expected life. The system's or element's current replacement value is based on RS Means Commercial Cost Data.

Following are the cost model's system details for this facility. The Replacement Value is the amount needed to replace the property of the same present value. The Current Repair Amount, also known as Condition Needs, represents the budgeted contractor installed costs plus owner's soft costs for the repair, replacement or renewal for a component or system level deficiency. It excludes contributing costs for other components or systems that might also be associated with the corrective actions due to packaging the work. Facility Condition Index (FCI) FCI is an industry-standard measurement of facility condition calculated as the ratio of the costs to correct a facility's deficiencies to the facility's Current Replacement Value. It ranges from 0% (new) to 100% (very poor). Condition Index (CI) is calculated as the sum of a renewable system's Remaining Service Life (RSL) divided by the sum of a system's Replacement Value (both values exclude soft-cost to simplify calculation updates) expressed as a percentage ranging from 100% (new) to 0% (expired).

Function:

Gross Area (SF): 24,000

Year Built: 1926

Last Renovation:

Replacement Value: \$485,520

Repair Cost: \$528,323.10

Total FCI: 108.82 %

Total RSLI: 79.30 %

Description:

Attributes:

General Attributes:

Bldg ID:	S523001	Site ID:	S523001
----------	---------	----------	---------

Condition Summary

The Table below shows the CI and FCI for each major building system shown at the UNIFORMAT classification Level II. Note that Systems with lower FCIs require less investment than systems with higher FCIs.

UNIFORMAT Classification	RSLI %	FCI %	Current Repair Cost
G20 - Site Improvements	90.45 %	138.62 %	\$528,323.10
G40 - Site Electrical Utilities	38.61 %	0.00 %	\$0.00
Totals:	79.30 %	108.82 %	\$528,323.10

Condition Detail

This section of the report contains results of the Facility Condition Assessment. The building is separated into system components based on UNIFORMAT II classification. The columns in the System Listing table below represent the following:

1. System Code: A code that identifies the system.
2. System Description: A brief description of a system present in the building.
3. Unit Price \$: The unit price of the system.
4. UoM: The unit of measure for of the system.
5. Qty: The quantity for the system
6. Life: anticipated service life for thesystem based on Building Owners and Managers Association (BOMA) recommendations.
7. Year Installed: The date of system installation.
8. Calc Next Renewal Year: The date of system expiration based on the life, NR stands for non renewable.
9. Next Renewal Year: The suggested system expiration date by the assessor based on visual inspection.
10. CI: The Condition Index of the system.
11. FCI: The Facility Condition Index of the system.
12. RSL: Remaining Service Life.
13. eCR: eCOMET Condition Rating (not used).
14. Deficiency \$: The financial investment to repair/replace system.

System Listing

The System Listing table below lists each of the systems organized by their UNIFORMAT II classification. The assessment team was tasked with recording the most recent replacement year of each system, determining the remaining service life based on the theoretical life, and evaluating the condition to confirm the forecast next replacement year. The system listing is the basis for all data contained in the Building Assessment Report.

Additionally, a condition rating (eCR) based on the following guidelines is provided as observed at the time of the assessment.

- Excellent (E) - No noticeable distress or damage. The entire system is free from observable defect.
- Very Good (VG) - Overall no serviceability reduction for the entire system. No degradation of critical components and minor distress and defect noticeable for some but not non critical components within the system.
- Good (G) - Slight or no serviceability reduction for the entire system. There may be noticeable defects for some non critical components and slight noticeable degradation of the critical components.
- Fair (F) - Overall serviceability is degraded but adequate. There may be moderate deterioration for very few of the critical components and few of the non critical components may have severe degradation.
- Marginal (MA) - Overall serviceability and reliability loss. Most if not all of the non critical components suffer from severe degradation and a few of the critical component may have severe degradation.
- Moderate (MO) - Overall a significant serviceability loss. Most if not all the components have severe degradation with the reminder of the component showing visible distress.
- Very Poor (VP) - Overall the system is barely functional. All of the components are severely degraded.
- Non-Functional (NF) - Overall the system does not function with all the components having no serviceability and suffer from severe degradation.

System Code	System Description	Unit Price \$	UoM	Qty	Life	Year Installed	Calc Next Renewal Year	Next Renewal Year	RSLI%	FCI%	RSL	eCR	Deficiency \$	Replacement Value \$
G2010	Roadways	\$11.52	S.F.		30				0.00 %	0.00 %				\$0
G2020	Parking Lots	\$7.65	S.F.		30				0.00 %	0.00 %				\$0
G2030	Pedestrian Paving	\$11.52	S.F.	24,000	40	1926	1966	2057	105.00 %	191.09 %	42		\$528,323.10	\$276,480
G2040	Site Development	\$4.36	S.F.	24,000	25	1926	1951	2028	52.00 %	0.00 %	13			\$104,640
G2050	Landscaping & Irrigation	\$3.78	S.F.		15				0.00 %	0.00 %				\$0
G4020	Site Lighting	\$3.58	S.F.	24,000	30	1926	1956	2028	43.33 %	0.00 %	13			\$85,920
G4030	Site Communications & Security	\$0.77	S.F.	24,000	30	1926	1956	2020	16.67 %	0.00 %	5			\$18,480
Total									79.30 %	108.82 %			\$528,323.10	\$485,520

System Notes

The facility description in the site executive summary contains an overview of each system. The notes listed below provide additional information on select systems found within the facility.

No data found for this asset

Renewal Schedule

eCOMET forecasts future Capital Renewal funding needed to address expiring systems based on the Next Renewal year found in the Cost Models. A 3% annual inflation factor is applied to the costs for systems expiring in future years. The table below reflects recommended Capital Renewal funding needs over the next 10 years. Note: Cells with a zero value indicate systems for which renewal is not scheduled in that year.


Inflation Rate: 3%

System	Current Deficiencies	2016	2017	2018	2019	2020	2021	2022	2023	2024	2025	Total
Total:	\$528,323	\$0	\$0	\$0	\$0	\$23,566	\$0	\$0	\$0	\$0	\$0	\$551,889
G - Building Sitework	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G20 - Site Improvements	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G2010 - Roadways	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G2020 - Parking Lots	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G2030 - Pedestrian Paving	\$528,323	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$528,323
G2040 - Site Development	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G2050 - Landscaping & Irrigation	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G40 - Site Electrical Utilities	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G4020 - Site Lighting	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G4030 - Site Communications & Security	\$0	\$0	\$0	\$0	\$0	\$23,566	\$0	\$0	\$0	\$0	\$0	\$23,566

** Indicates non-renewable system*

Forecasted Sustainment Requirement

The following chart shows the current building deficiencies and forecasting sustainment requirements over the next ten years.




10 Year FCI Forecast by Investment Scenario

The chart below illustrates the effect of various investment levels on the building FCI for the next 10 years. The levels of investment shown below include:

- Current FCI: a variable investment amount based on renewing expired systems to maintain the current FCI for the building
- 2% Investment: an annual investment of 2% of the replacement value of the building, escalated for inflation
- 4% Investment: an annual investment of 4% of the replacement value of the building, escalated for inflation


Facility Investment vs. FCI Forecast



Year	Investment Amount Current FCI - 108.82%	2% Investment		4% Investment	
		Amount	FCI	Amount	FCI
2016	\$0	\$10,002.00	106.82 %	\$20,003.00	104.82 %
2017	\$322,649	\$10,302.00	167.46 %	\$20,604.00	163.46 %
2018	\$0	\$10,611.00	165.46 %	\$21,222.00	159.46 %
2019	\$0	\$10,929.00	163.46 %	\$21,858.00	155.46 %
2020	\$23,566	\$11,257.00	165.64 %	\$22,514.00	155.64 %
2021	\$0	\$11,595.00	163.64 %	\$23,189.00	151.64 %
2022	\$0	\$11,943.00	161.64 %	\$23,885.00	147.64 %
2023	\$0	\$12,301.00	159.64 %	\$24,602.00	143.64 %
2024	\$0	\$12,670.00	157.64 %	\$25,340.00	139.64 %
2025	\$0	\$13,050.00	155.64 %	\$26,100.00	135.64 %
Total:	\$346,215	\$114,660.00		\$229,317.00	


Deficiency Summary by System

Current deficiencies included assemblies that have reached or exceeded their design life or components of the assemblies that are in need of repair. Assemblies that have reached their design life are identified as current deficiencies and assigned the distress 'Beyond Useful Life'. The following chart lists all current deficiencies associated with this facility.



Deficiency Summary by Priority

The following chart shows the total repair costs broken down by priority. Assessors assigned deficiencies within eCOMET to one of the following priority categories:



Budget Estimate Total: \$528,323.10


Deficiency By Priority Investment Table

The table below shows the current investment cost grouped by deficiency priority and building system.

System Code	System Description	1 - Response Time (< 2 yr)	2 - Response Time (2-3 yrs)	3 - Response Time (3-4 yrs)	4 - Response Time (4-5 yrs)	5 - Response Time (> 5 yrs)	Total
G2030	Pedestrian Paving	\$0.00	\$163,341.94	\$0.00	\$364,981.16	\$0.00	\$528,323.10
	Total:	\$0.00	\$163,341.94	\$0.00	\$364,981.16	\$0.00	\$528,323.10

Deficiency Summary by Category

The following chart shows the total repair costs broken down by deficiency categories. Assessors assigned deficiencies to one of the following categories:



Deficiency Details by Priority

The deficiency detail notes listed below provide additional information on identified deficiencies found within the facility.

Priority 2 - Response Time (2-3 yrs):

System: G2030 - Pedestrian Paving

This deficiency has no image.

Location: Grounds/ site

Distress: Accessibility

Category: 2 - Code Compliance

Priority: 2 - Response Time (2-3 yrs)

Correction: Install an exterior ADA ramp - based on 5' wide by the linear foot - up to 84" rise - per LF of ramp - figure 1 LF of ramp per inch of rise

Qty: 69.00

Unit of Measure: L.F.

Estimate: \$163,341.94

Assessor Name: Craig Anding

Date Created: 10/04/2015

Notes: Provide ADA compliant ramp at one entrance (location TBD)

Priority 4 - Response Time (4-5 yrs):

System: G2030 - Pedestrian Paving



Location: Grounds/ site

Distress: Maintenance Required

Category: 3 - Operations / Maint.

Priority: 4 - Response Time (4-5 yrs)

Correction: Remove and replace exterior egress stairway - per flight

Qty: 6.00

Unit of Measure: Flight

Estimate: \$203,893.23

Assessor Name: Craig Anding

Date Created: 10/04/2015

Notes: Reset stone stoops and stairs at all entrances

System: G2030 - Pedestrian Paving



Location: Grounds/ site

Distress: Beyond Service Life

Category: 3 - Operations / Maint.

Priority: 4 - Response Time (4-5 yrs)

Correction: Remove and replace concrete sidewalk or concrete paving - 4" concrete thickness

Qty: 11,200.00

Unit of Measure: S.F.

Estimate: \$161,087.93

Assessor Name: Craig Anding

Date Created: 10/04/2015

Notes: Resurface playground

Equipment Inventory

The following table represents the inventory details of the inventory found in the building, which fall under the following subsystems:

No data found for this asset

Glossary

ABMA	American Boiler Manufacturers Association http://www.abma.com/
ACEEE	American Council for an Energy-Efficient Economy
ACGIH	American Council of Governmental and Industrial Hygienists
AEE	Association of Energy Engineers
AFD	Adjustable Frequency Drive
AFTC	After Tax Cash Flow
AGA	American Gas Association
AHU	Air Handling Unit
Amp	Ampere
ANSI	American National Standards Institute
ARI	Air Conditioning and Refrigeration Institute
ASD	Adjustable Speed Drive
ASHRAE	American Society of Heating Refrigerating and Air-Conditioning Engineers Inc.
ASME	American Society of Mechanical Engineers
Assessment	Visual survey of a facility to determine its condition. It involves looking at the age of systems reviewing information from local sources and visual evidence of potential problems to assign a condition rating. It does not include destructive testing of materials or testing of systems or equipment for functionality.
ATS	After Tax Savings
AW	Annual worth
BACNET	Building Automation Control Network
BAS	Building Automation System
BCR	Benefit Cost Ratio
BEP	Business Energy Professional (AEE)
BF	Ballast Factor
BHP	Boiler Horsepower (boilers)
BHP	Brake Horsepower (motors)
BLCC	Building Life Cycle Cost analysis program (FEMP)
BOCA	Building Officials and Code Administrators
BTCF	Before Tax Cash Flow

Site Assessment Report - S523001;Conwell

BTS	Before Tax Savings
Btu	British thermal unit
Building Addition	An area space or component of a building added to a building after the original building's year built date.
CAA	Clean Air Act
CAAA-90	Clean Air Act Amendments of 1990
CABO	Council of American Building Officials
CAC	Conventional Air Conditioning
CADDET	Center for the Analysis and Dissemination of Demonstrated Energy Technologies
Calculated Next Renewal	The year a system or element would be expected to expire based solely on the date it was installed and the expected useful lifetime for that kind of system.
Capital Renewal	Capital renewal is condition work (excluding suitability and energy audit work) that includes the replacement of building systems or elements (as they become obsolete or beyond their useful life) not normally included in an annual operating budget. Calculated next renewal The year a system or element would be expected to expire based solely on the date it was installed and the expected useful lifetime for that kind of system. Next renewal The assessor adjusted expected useful life of a system or element based on on-site inspection.
CDD	Cooling Degree Days
CDGP	Certified Distributed Generation Professional
CEC	California Energy Commission
CEM	Certified Energy Manager
CEP	Certified Energy Procurement Professional
CFC	Chlorofluorocarbon
CFD	Cash Flow Diagram
CFL	Compact Fluorescent Light
CFM cfm	Cubic Feet per Minute
CHP	Combined Heat and Power (a.k.a. cogeneration)
CHW	Chilled Water
Condition	Condition refers to the state of physical fitness or readiness of a facility system or system element for its intended use.
COP	Coefficient of Performance
Cp	Heat Capacity of Material
CPUC	California Public Utility Commission
CRI	Color Rendering Index
CRT	Cathode Ray Tube VDT HMI

Site Assessment Report - S523001;Conwell

CTC	Competitive Transition Charge
Cu	Coefficient of Utilization
Current Replacement Value (CRV)	CRV represents the hypothetical total cost of rebuilding or replacing an existing facility in current dollars to its optimal condition (excluding auxiliary facilities) under current codes and construction standards.
Cv	Value Coefficient
CWS	Chilled Water System
D d	Distance (usually feet)
DB	Dry Bulb
DCV	Demand Control Ventilation
DD	Degree Day
DDB	Double Declining Balance
DDC	Direct Digital Controls
Deferred maintenance	Deferred maintenance is condition work (excluding suitability and energy audit needs) deferred on a planned or unplanned basis to a future budget cycle or postponed until funds are available.
Deficiency	A deficiency is a repair item that is damaged missing inadequate or insufficient for an intended purpose.
Delta	Difference
Delta P	Pressure Difference
Delta T	Temperature Difference
DG	Distributed Generation
DOE	Department of Energy
DP	Dew Point
DR	Demand Response
DX	Direct Expansion Air Conditioner
EA	Energy Audit
EBITDA	Earnings before Interest Taxes Depreciation and Amortization
ECI	Energy Cost Index
ECM	Energy Conservation Measure
ECO	Energy Conservation Opportunity
ECPA	Energy Conservation and Production Act
ECR	Energy Conservation Recommendation
ECS	Energy Control System

Site Assessment Report - S523001;Conwell

EER	Energy Efficiency Ratio
EERE	Energy Efficiency and Renewable Energy division of US DOE
EIA	Energy Information Agency
EIS	Energy Information System
EMCS	Energy Management Computer System
EMO	Energy Management Opportunity
EMP	Energy Management Project
EMR	Energy Management Recommendation
EMS	Energy Management System
Energy Utilization Index (EUI)	EUI is the measure of total energy consumed in the cooling or heating of a building in a period expressed as British thermal unit (BTU) per (cooled or heated) gross square foot.
EO	Executive Order
EPA	Environmental Protection Agency
EPACT	Energy Policy Act of 1992
EPCA	Energy Production and Conservation Act of 1975
EPRI	Electric Power Research Institute
EREN	Efficiency and Renewable Energy (Division of USDOE)
ERV	Energy Recovery Ventilator
ESCO	Energy Service Company
ESPC	Energy Savings Performance Contract
EUI	Energy Use Index
EWG	Exempt Wholesale Generators
Extended Facility Condition Index (EFCI)	EFCI is calculated as the condition needs for the current year plus facility system renewal needs going out to a set time in the future divided by Current Replacement Value.
f	Frequency
F	Fahrenheit
Facility	A facility refers to site(s) building(s) or building addition(s) or combinations thereof that provide a particular service.
Facility Condition Assessment (FCA)	FCA is a process for evaluating the condition of buildings and facilities for programming and budgetary purposes through an on site inspection and evaluation process.
Facility Condition Index (FCI)	FCI is an industry-standard measurement of a facility's condition that is the ratio of the cost to correct a facility's deficiencies to the Current Replacement Value of the facilities. The higher the FCI the poorer the condition of a facility. After an FCI is established for all buildings within a portfolio a building's condition can be ranked relative to other buildings. The FCI may also represent the condition of a portfolio based on the cumulative FCIs of the portfolio's facilities.

Site Assessment Report - S523001;Conwell

FC	Footcandle
FCA	Fuel Cost Adjustment
FEMIA	Federal Energy Management Improvement Act of 1988
FEMP	Federal Energy Management Program
FERC	Federal Energy Regulatory Commission
FESR	Fuel Energy Savings Ratio
FLA	Full Load Amps
FLF	Facility Load Factor (usually monthly)
FLRPM	Full Load Revolutions per Minute
FMS	Facility Management System
FPM fpm	Feet per Minute (velocity)
FSEC	Florida Solar Energy Center
Ft	Foot
GPM gpm	Gallons per Minute
GRI	Gas Research Institute
Gross Square Feet (GSF)	The size of the enclosed floor space of a building in square feet measured to the outside face of the enclosing wall.
GUI	Graphical User Interface
H h	Enthalpy Btu/lb
HCFC	Hydrochlorofluorocarbons
HDD	Heating Degree days
HFC	Hydrofluorocarbons
HHV	Higher Heating Value
HID	High Intensity Discharge (lamp)
HMI	Human Machine Interface
HMMI	Human Man Machine Interface
HO	High Output (lamp)
HP Hp hp	Horsepower
HPS	High Pressure Sodium (lamp)
HR	Humidity Ratio
Hr hr	Hour

Site Assessment Report - S523001;Conwell

HRU	Heat Recovery Unit
HVAC	Heating Ventilation and Air-Conditioning
Hz	Hertz
I	Intensity (lumen output of lamp)
I i	Interest rate or Discount rate
IAQ	Indoor Air Quality
ICA	International Cogeneration Alliance
ICBO	International Conference of Buildings Officials
ICC	International Code Council
ICP	Institutional Conservation Program
IECC	International Energy Conservation Code
IEEE	Institute of Electrical and Electronic Engineers
IESNA	Illuminating Engineering Society of North America
Install year	The year a building or system was built or the most recent major renovation date (where a minimum of 70 of the system's Current Replacement Value (CRV) was replaced).
IRP	Integrated Resource Planning
IRR	Internal Rate of Return
ISO	Independent System Operator
ITA	Independent Tariff Administrator
k	Kilo multiple of thousands in SI system
K	Kelvins (color temperature of lamp)
K k	Thermal Conductivity of Material
KVA	Kilovolt Ampere
KVAR	Kilovolt Ampere Reactive
kW	kiloWatt
kWh	kiloWatt hour
L	Length (usually feet)
LCC	Life Cycle Costing
LDC	Local Distribution Company
LEED	Leadership in Energy and Environmental Design
LEED EB	LEED for Existing Buildings

Site Assessment Report - S523001;Conwell

LEED NC	LEED for new construction
LF	Load Factor
LHV	Lower Heating Value
Life cycle	The period of time that a building or site system or element can be expected to adequately serve its intended function.
LPS	Low Pressure Sodium (lamp)
Lu	Lumen Output of a Lamp or Fixture
M	Mega multiple of millions in SI system
M&V	Measurement and Verification
MACRS	Modified Accelerated Cost Recovery System
MARR	Minimum Attractive Rate of Return
Mbtu	Thousand Btu
MCF	Thousand Cubic Feet (usually of gas)
MEC	Model Energy Code
Mm	Multiple of Thousands in I/P System
MMBtu	Million Btu
MMCS	Maintenance Management Computer System
MMI	Man Machine Interface
MMS	Maintenance Management System
MSE 2000	Management System for Energy 2000 (ANSI Georgia Tech Univ)
MW	MegaWatt
MWH MWh	MegaWatt hour
NAAQS	National Ambient Air Quality Standards
NAESCO	National Association of Energy Service Companies
NAIMA	North American Insulation Manufacturers Association
NEA	National Energy Act of 1978
NECPA	National Energy Conservation Policy Act
NEMA	National Electrical Manufacturer's Association
NERC	North American Electric Reliability Council
Next Renewal	The Next Renewal date is an override of the 'Calculated Next Renewal' date and is based upon the assessor's visual inspection.

Site Assessment Report - S523001;Conwell

NFPA	National Fire Protection Association
NGPA	National Gas Policy Act of 1978
NLRPM	No Load Revolutions per Minute (speed)
Nn	Equipment or Project lifetime in economic analysis
NOPR	Notice of Proposed Rule Making from FERC
NOx	Nitrogen Oxide Compounds
NPV	Net present value in economic analysis
NREL	National Renewable Energy Laboratory
NUG	Non-Utility Generator
O&M	Operation and Maintenance
OA	Outside Air
ODP	Ozone Depletion Potential
OPAC	Off-Peak Air Conditioning
P	Present value in economic analysis
PBR	Performance Based Rates
PEA	Preliminary Energy Audit
PF	Power Factor
PID	Proportional plus integral plus derivative (control system)
PM	Portfolio Manager in Energy Star rating system
PM	Preventive Maintenance
PoolCo	Power Pool Company or Organization
POU	Point of Use
PQ	Power Quality
PSC	Public Service Commission
PSIA psia	Pounds per square inch absolute (pressure)
PSIG psig	Pounds per square inch gauge (pressure)
PUC	Public Utility Commission
PUHCA	Public Utilities Holding Company Act of 1935
PURPA	Public Utilities Regulatory Policies of 1978
PV	Photovoltaic system

Site Assessment Report - S523001;Conwell

PV	Present Value
PW	Present Worth
PX	Power Exchange
q	Rate of heat flow in Btu per hour
Q	Heat load due to conduction using degree days
QF	Qualifying Facility
R	Electrical resistance
R	Thermal Resistance
RC	Remote controller
RCR	Room Cavity Ratio
RCRA	Resource Conservation and Recovery Act
Remaining Service Life (RSL)	RSL is the number of years service remaining for a system or equipment item. It is automatically calculated based on the difference between the current year and the 'Calculated Next Renewal' date or the 'Next Renewal' date whichever one is the later date.
Remaining Service Life Index (RSLI)	RSLI is defined as a percentage ratio of the remaining service life of a system. It usually ranges from 0 to 100
REMR	Repair Evaluation Maintenance Rehabilitation (REMR) is a scale used to objectively rank systems based on their condition
Renewal Schedule	A timeline that provides the items that need repair the year in which the repair is needed and the estimated price of the renewal.
RH	Relative Humidity
RLA	Running Load Amps
RMS	Root Mean Square
RO	Reverse Osmosis
ROI	Return on Investment
RPM	Revolutions Per Minute
RTG	Regional Transmission Group
RTO	Regional Transmission Organization
RTP	Real Time Pricing
SBCCI	Southern Building Code Congress International
SC	Scheduling Coordinator
SC	Shading Coefficient
SCADA	Supervisory Control and Data Acquisition Systems

Site Assessment Report - S523001;Conwell

SEER	Seasonal Energy Efficiency Ratio
SHR	Sensible Heat Ratio
Site	The grounds and utilities roadways landscaping fencing and other typical land improvements needed to support the facility.
Soft Cost	An expense item that is not considered direct construction cost. Soft cost includes architectural engineering financing legal fees and other pre-and-post construction expenses.
SOx	Sulfur Oxide Compounds
SP	Static Pressure
SP SPB	Simple Payback
SPP	Simple Payback Period
SPP	Small Power Producers
STR	Stack Temperature Rise
SV	Specific Volume
System	System refers to building and related site work elements as described by ASTM Uniformat II Classification for Building Elements (E1557-97) a format for classifying major facility elements common to most buildings. Elements usually perform a given function regardless of the design specification construction method or materials used. See also Uniformat II.
T	Temperature
T	Tubular (lamps)
TAA	Technical Assistance Audit
TCP/IP	Transmission Control Protocol/Internet Protocol
TES	Thermal Energy Storage
THD	Total Harmonic Distortion
TOD	Time of Day
TOU	Time of Use
TQM	Total Quality Management
TransCo	Transmission Company
U	Thermal Conductance
UDC	Utility Distribution Company
UL	Underwriters Laboratories
UNIFORMAT II	The ASTM UNIFORMAT II Classification for Building Elements (E1557-97) a format for classifying major facility components common to most buildings.
USGBC	US Green Building Council
v	Specific Volume

Site Assessment Report - S523001;Conwell

V	Volts Voltage
V	Volume
VAV	Variable Air Volume
VDT	Video Display Terminal
VFD	Variable Frequency Drive
VHO	Very High Output
VSD	Variable Speed Drive
W	Watts
W	Width
WB	Wet bulb
WH Wh	Watt Hours
Year built	The year that a building or addition was originally built based on substantial completion or occupancy.
Z	Electrical Impedance

School District of Philadelphia

S523101;Conwell Annex

Final

Site Assessment Report

February 2, 2017



Table of Contents

Site Executive Summary	4
Site Condition Summary	10
<u>B523101:Conwell Annex</u>	12
Executive Summary	12
Condition Summary	13
Condition Detail	14
System Listing	15
System Notes	17
Renewal Schedule	18
Forecasted Sustainment Requirement	21
Condition Index Forecast by Investment Scenario	22
Deficiency Summary By System	23
Deficiency Summary By Priority	24
Deficiency By Priority Investment	25
Deficiency Summary By Category	26
Deficiency Details By Priority	27
Equipment Inventory Detail	43
<u>G523101:Grounds</u>	44
Executive Summary	44
Condition Summary	45
Condition Detail	46
System Listing	47
System Notes	48
Renewal Schedule	49
Forecasted Sustainment Requirement	50
Condition Index Forecast by Investment Scenario	51
Deficiency Summary By System	52
Deficiency Summary By Priority	53
Deficiency By Priority Investment	54

Site Assessment Report

Deficiency Summary By Category	55
Deficiency Details By Priority	56
Equipment Inventory Detail	57
Glossary	58

Site Executive Summary

The organization of this report, as displayed in the Table of Contents, follows the structure of the associated eCOMET database. The overall node for each school campus begins with the letter "S", which indicates the "Site" label. Each Site is comprised of separate "Building" and "Grounds" nodes; their asset names begin with the letters "B" and "G" respectively. Information rolls up to the Site node from the Building and Grounds nodes. This Site report combines facility information with subsections for the Buildings And Grounds nodes.

The basis for the evaluation of condition is the functional systems and elements of a building and grounds organized according to the UNIFORMAT II Elemental Classification. The grouping of these systems and elements and applying a current replacement value to them develops a representative building cost model. Cost Models are typically developed for similar building types and functions. Evaluation of systems and their elements takes into account their current replacement values, life cycles, installation dates and next renewal dates. Systems and their elements that are within their useful lives are further evaluated to identify current deficient conditions that may have a significant impact on a system's or element's remaining service life, and to determine if they are beyond their predicted expected life. The system's or element's current replacement value is based on RS Means Commercial Cost Data.

Following are the cost model's system details for this facility. The Replacement Value is the amount needed to replace the property of the same present value. The Current Repair Amount, also known as Condition Needs, represents the budgeted contractor installed costs plus owner's soft costs for the repair, replacement or renewal for a component or system level deficiency. It excludes contributing costs for other components or systems that might also be associated with the corrective actions due to packaging the work. Facility Condition Index (FCI) is an industry-standard measurement calculated as the ratio of the repair costs to correct a facility's deficiencies to the facility's Current Replacement Value. Condition Index (CI) for a system is calculated as the sum of the deficiencies divided by the sum of a system's Replacement Value (both values include soft-cost) expressed as a percentage ranging from 0% 100%.

Gross Area (SF):	27,000
Year Built:	1903
Last Renovation:	1972
Replacement Value:	\$33,955,766
Repair Cost:	\$9,128,293.22
Total FCI:	26.88 %
Total RSLI:	81.29 %



Description:

Facility Assessment, August, 2015

School District of Philadelphia

Conwell Annex School

3072 Emerald Street

Philadelphia, PA 19134

27000 SF / 420 Students / LN 05

The Conwell Annex school building is located at 3072 Emerald Street in Philadelphia, PA. The 3 story with basement, approximately 27,000 square foot building was originally constructed in 1903. Some interior renovations were done in 1971 and an enclosed external egress stairway was added.

Mr. Scott Ovington, Facility Area Coordinator provided input to the Parsons assessment team on current problems and planned

Site Assessment Report - S523101;Conwell Annex

renovation projects. Ms. Donna Jakimowicz, building engineer, accompanied us on our tour of the school and provided us with as much information as he could on the building systems and recent maintenance history.

STRUCTURAL/ EXTERIOR CLOSURE:

The building typically rests on stone masonry foundations and bearing walls that are not showing signs of settlement or damage, although water penetration in Northwest corner of the boiler room has been reported.

The main structure consists typically of masonry load bearing walls and timber columns supporting heavy timber beams and joists and wood plank sub-floor, generally in good condition. Roof structure consists of sloped heavy timber trusses and purlins supporting wood plank sheathing.

The building envelope is typically face brick with solid brick backup. In general, masonry is in poor condition with mortar missing from joints; moisture penetration through walls is evident and has been reported. Brick pilasters between basement windows supporting timber girders are cracked and crumbling. Brick chimney is also damaged.

The original windows were replaced in early 2000's with extruded aluminum double hung windows single glazed with acrylic glazing; they are not energy efficient. First floor windows are fitted with galvanized steel security screens. All windows and screens are generally in good condition.

The exterior doors are generally in fair condition; no weather-stripping is installed; some doors have vision glazing with security screens.

Roofing is typically shingles roofing installed in approximately 2000 and is in good condition. No leaks have been reported.

Exterior doors and frames are typically hollow metal in fair condition.

INTERIORS:

Partition wall types include plastered ceramic blocks (hollow brick), CMU and drywall. The interior wall finishes are generally painted plaster or drywall. Generally, paint is in fair condition, except toilets and interior faces of exterior walls. Plaster cracking and peeling paint was observed.

Interior doors are generally solid core wood doors, some glazed in good condition, however most doors do not have accessible handles; doors leading to exit stairways are retrofitted with hollow metal doors and frames in good condition.

Stair finishes are generally painted wood with non-slip treads. Added stairway is painted steel with steel non-slip checkered plate treads.

Interior identifying signage is typically directly painted on wall or door surfaces in poor condition.

Most ceilings are exposed, painted plaster and 2x4 suspended acoustical panels; the suspension system and tile are old and approaching the end of their useful life. There is substantial plaster cracking and peeling paint in stairways and boiler room.

Flooring is generally VCT with cove base in good condition (installed approximately in 2000), and original hardwood in fair to poor condition. Toilets have 2x2 ceramic tile flooring in good condition.

Furnishings include fixed casework in classrooms, corridors and library, generally in good condition; window shades/blinds, generally in fair condition.

GROUNDS (SITE):

There is neither parking nor playground at the site.

The landscaping consists of narrow strips of grass along South and West walls in fair condition.

ACCESSIBILITY:

Site Assessment Report - S523101;Conwell Annex

The building does not have accessible entrance, and accessible routes. There is no elevator to reach floors above. Toilets are equipped with accessible fixtures, partitions and accessories, such as grab bars. Most doors in the building do not have ADA required door handles.

PLUMBING:

Plumbing Fixtures - Many of the plumbing fixtures have recently been replaced. Fixtures in the restrooms on each floor consist of wall mounted flush valve water closets, wall hung urinals and lavatories with wheel handle faucets. The building is equipped with handicap accessible stalls on each floor, except the basement. The fixtures are in good condition and should provide reliable service for the next 15-20 years.

Drinking fountains are a mixture of old and new wall hung units with integral refrigerated coolers. Several units are well beyond their service life and should be replaced; some are accessible type.

A mop basin is available in a janitor on the first floor for use by the janitorial staff.

There is no kitchen at Conwell Annex as all meals are served at the main Conwell School building down the block.

Domestic Water Distribution - A 4" city water service enters the building from Emerald Street near the middle of the block. The 3" meter and valves are located in a small room in the basement. A reduced pressure backflow preventer is installed. The domestic hot and cold water distribution piping is copper piping and sweat fittings. The maintenance staff reports no significant problems with scale build up in the domestic piping and the supply is adequate to the fixtures, but the piping is over 40 years old and should be inspected and replaced by a qualified contractor.

One Bradford White gas fired, 75 gallon, vertical hot water heater with circulating pump supplies hot water for domestic use. The unit was installed in 2013 and is located in the boiler room on the basement level. The hot water heater is equipped with a T&P relief valve. The domestic hot water heater is within its service life and should provide reliable service for the next 6-8 years.

Sanitary Waste - The storm and sanitary sewer piping is a mixture of threaded galvanized piping and cast iron with hub and spigot fittings.

The maintenance staff reported no problems with the sanitary waste piping systems. The sewer piping has been in service for over 40 years and will require more frequent attention from the maintenance staff as time passes. The District should hire a qualified contractor to examine the sanitary waste piping using video cameras to locate and replace any damaged piping and to further quantify the extent of potential failures.

A sewage ejector pit located in basement boiler room receives sewage from the basement area. It has a single pump that is beyond its service life. The pump system should be replaced to prevent flooding of the basement. The pit is sealed.

Rain Water Drainage - Rain water drains from the roof and is routed to downspouts on the exterior of the building. Aluminum downspouts have replaced much of the original cast iron piping above ground level, with the aluminum to iron transition taking place about six feet above ground. The original cast iron piping remains for the underground drainage piping. The drain piping should be inspected by a qualified contractor and repaired as necessary.

MECHANICAL:

Energy Supply - A 2" city gas service enters the building from Emerald Street near the middle of the block. The gas meter is 2" and is located in a closet in the basement.

The oil supply is stored in two 275 gallon storage tanks located in the basement. Oil is the only fuel for the burners, which are not served by natural gas.

Heat Generating Systems - Low pressure steam is generated at a maximum of 15 lbs/sq. in., typically 5-7 lbs/sq. in., by one 30HP HB Smith cast iron sectional boiler, original to the building. The one boiler handles the load in all winter weather conditions. The boiler is equipped with an external burner, manufacturer unknown, designed to operate on fuel oil. The burner is well beyond its service life and should be replaced. Burner oil pumps are connected and are driven by the fan motor, which is not allowed by current codes. The Building Engineer reports no major issues with the boiler or burner. Cast iron sectional boilers have an anticipated service life of 35 years or more; as this unit has most likely been in service 45 years it needs to be replaced. The boiler is operational but should be replaced within the next 3 years.

Site Assessment Report - S523101;Conwell Annex

The condensate receiver is installed in the basement boiler room. No problems were reported with steam leaking into the system from failed steam traps. The district should hire a qualified contractor to examine the piping, in service for over 40 years, and perform additional testing to locate and replace any damaged piping and to further quantify the extent of potential failures. A chemical feed tank is installed for the boiler condensate tank.

Distribution Systems - The steam/condensate piping is black steel with threaded fittings in a one pipe system. Steam/condensate piping mains from the basement level run up through the building to the radiators on all three floors. The distribution piping has been in use beyond its service life and will require more frequent attention from the maintenance staff to address pipe/valve failures as time passes. The District should hire a qualified contractor to examine the steam/condensate piping and perform additional testing to locate and replace any damaged piping and to further quantify the extent of potential failures. The District should budget for replacing this piping over the next 10 years.

One pipe cast iron radiators and fin tube radiators provide heating for the majority of classrooms, offices, and hallways. These radiators are well beyond their service life and original to the building. Ventilation for the building is provided by roof mounted fans and opening windows, which does not meet current codes for outdoor air ventilation. A new heating system should be installed to meet ventilation requirements and achieve more efficient operation. The new units should be designed for quiet operation and equipped with hot water coils, chilled water coils, and integral heat exchangers, where applicable, to introduce outdoor air to the building.

Meals are served in the Conwell School two blocks away, therefore there is no kitchen in the building.

Two roof mounted exhaust fans serving the east and west restrooms are operational according to the Building Engineer. These fans are within their service life.

Ventilation should be provided for the administration offices by installing a fan coil air handling unit hung from the structure with outdoor air ducted to the unit from louvers in the window openings. This unit would be equipped with hot water heating coils and chilled water cooling coils. Steam converters would be installed in the existing boiler room with circulating pumps, distribution piping and controls to provide heating hot water for the new coils.

Terminal & Package Units - Several of the classrooms in the school building have window air conditioning units that have an anticipated service life of only 10 years. Installing a 70 ton air-cooled chiller with pumps located in a mechanical room and chilled water distribution piping would supply more reliable air conditioning for the building with a much longer service life.

One unit ventilator, with an associated roof mounted McQuay condenser unit, is located on the third floor. This unit is now defunct, but was used to supply cool air in a space that was used as a computer room in the past.

Controls & Instrumentation - The temperature in the building is controlled by one electric Honeywell thermostat mounted on the wall outside the main office. The thermostat controls heating for the building and works well according to the Building Engineer. This control scheme should be converted to DDC.

A new building automation system (BAS) with modern DDC modules and communications network should be installed to serve the HVAC systems in this building to improve reliability and energy efficiency. An interface should be provided with the preferred system in use throughout the District.

Sprinklers - Only the basement is covered by an automatic sprinkler system, a wet pipe system, the rest of the building is not. A 6" fire line enters the building from Emerald Street. Installing a sprinkler system with quick response type heads throughout the building should reduce insurance costs by providing protection for the property investment. A fire pump may be required depending on the available city water pressure.

ELECTRICAL:

Site electrical service – The primary power is at 13.2KV from the street power pole which feeds a 300KVA pole-top transformer (13.2KV – 120V/240V) and runs overhead to the building and into the electrical room. The electrical service is not functioning adequately and has reached its useful life (built in 1972). The main switchgear is rated at 600 Amp, 120V/240V/480 V, 2 phase, 3W, and is located in main electrical room. The PECO meter (PECO AXR) is also located inside the electrical room. The service entrance and the main building electrical distribution systems are not in good condition, and have reached the end of their service life. Also, the system has no extra capacity for the additional mechanical loads.

Distribution system - The electrical distribution is accomplished with a 120V/240V distribution switchboard, located in the electrical

Site Assessment Report - S523101;Conwell Annex

room, feeding several panels throughout the building. These panels are not in good condition. They have reached the end of their service life.

Receptacles - The receptacles in classrooms, computer rooms, libraries, and other areas are not adequate.

Lighting- Interior building is illuminated by various types of fixtures. They include fluorescent lighting (T-8 lamp) in majority of the areas, including; classrooms, corridor, offices and Kitchen. Surface or pendant mounted industrial fluorescent fixtures are used in mechanical and electrical rooms. Gymnasium is illuminated by metal halide enclosed glass fixtures. The majority of interior lighting fixtures are in a poor condition and have reached the end of their service life.

Fire alarm- The present Fire Alarm system is not automatic/addressable, and is not in compliance with safety code. There are manual pulls stations throughout the building. There is not sufficient number of horn/strobes installed in the classrooms, corridors, offices and other areas in the school.

Telephone/LAN- The school telephone and data systems are new and working adequately. A main distribution frame (MDF) along with a telephone PBX system are providing the communication system function for the building. School is also equipped with Wi-Fi system.

Public address- A separate PA system does not exist. School uses the telephone systems for public announcement. This system is working properly. The present Intercom System is functioning properly. Each class room is provided by with an intercom telephone service. The system permits paging and intercom communication between main office to each classroom, between each classroom to main office, and between classrooms to classrooms.

Clock and Program system - Clock and program systems are not working adequately. Classrooms are provided with 12-inch wall mounted, round clock, however, the clocks are not controlled properly by central master control panel.

Television System- Television system is not provided in the school. Most classes are provided with smart boards having the ability to connect to computer and internet.

Security Systems-access control, video surveillance- The school is not provided with video surveillance system. Cameras are not installed at exit doors, corridors, exterior, and other critical areas. These cameras should be controlled by a Closed Circuit Television system (CCTV).

Emergency Power System - School is not provided with emergency power. There is no generator for emergency lights and other emergency loads.

Emergency lighting system, including exit lighting- there are insufficient emergency lighting fixtures in corridors, library and other exit ways. Exit signs and emergency fixtures are old and beyond their useful life.

Lightning Protection System - There is adequate lightning protection system installed in the school.

Grounding - The present grounding system is adequate.

Site Lighting – There is no site per say at this campus. There is only a narrow strip of grass on the south side of the building. The existing lights on the building exteriors are adequate.

Site Paging – The present site paging is adequate. Sufficient number of speakers are located on the exterior walls.

Auditorium lighting and sound system – No major deficiencies were observed during the assessment.

RECOMMENDATIONS:

- Repair cracks in masonry, replace missing mortar, tuck-point original building – all walls, window pilasters in basement and chimney
- Provide new signage throughout the building
- Refinish hardwood flooring
- Replace all suspended acoustical ceilings
- Repair plaster ceilings (25% area), repaint all ceilings
- Repair and repaint interior walls
- Replace all door hardware for accessibility

Site Assessment Report - S523101;Conwell Annex

- Provide accessible ramp at the main entrance
- Provide elevator serving all floors.
- Replace two (2) wall hung drinking fountains and integral refrigerated coolers in the corridors. These units are beyond their service life and are NOT accessible type.
- Hire a qualified contractor to perform a detailed inspection of the domestic water piping, in use for over 40 years, and replace any damaged piping.
- Replace existing sewage ejector pump system and piping in the basement as it is beyond its service life.
- Hire a qualified contractor to perform a detailed examination of the sanitary waste piping using visual inspection and video cameras to locate and replace any damaged piping and to further quantify the extent of potential failures.
- Hire a qualified contractor to perform a detailed examination of the rain water drainage piping using visual inspection and video cameras to locate and replace any damaged piping and to further quantify the extent of potential failures.
- Replace the one existing 1,005MBH cast iron boiler, which is beyond its service life, burners, and exhaust ductwork.
- Hire a qualified contractor to examine the steam/condensate piping, in service for over 40 years, and perform additional testing to locate and replace any damaged piping and to further quantify the extent of potential failures.
- Remove the existing cast iron steam radiators and fin tube radiators and install fan coil units with hot and chilled water coils and a dedicated outdoor air system.
- Remove the window air conditioning units and install a 70 ton air-cooled chiller with chilled water distribution piping and pumps to supply more reliable air conditioning for the building with a much longer service life.
- Provide ventilation for the administration office by installing a fan coil air handling unit hung from the structure with outdoor air ducted to the unit from louvers in window openings.
- Replace the electric controls for the HVAC systems with modern DDC modules, valves and actuators to improve reliability and energy efficiency. Provide a new building automation system (BAS) with communication interface to the preferred system in use throughout the District.
- Install a fire protection sprinkler system with quick response type heads throughout the building to reduce insurance costs by providing protection for the property. A fire pump may be required depending on the available city water pressure.
- Install a new electrical Service.
- Install new distribution panels.
- Install adequate (two on each wall minimum) surface-mounted receptacles in all classrooms and other areas within the building.
- Install new lighting system for the entire building.
- Install new automated FA system.
- Install new Video Surveillance System with Cameras and CCTV.
- Install new Clock System.
- Install new emergency exit signs & emergency lights.
- Install a new Emergency generator.

Attributes:

General Attributes:

Active:	Open	Bldg Lot Tm:	Lot 2 / Tm 4
Status:	Accepted by SDP	Team:	Tm 4
Site ID:	S523101		

Site Condition Summary

The Table below shows the CI and FCI for each major system shown at the UNIFORMAT classification Level II. Note that Systems with lower FCIs require less investment than systems with higher FCIs.


Current Investment Requirement and Condition by Uniformat Classification

UNIFORMAT Classification	RSLI%	FCI %	Current Repair
A10 - Foundations	57.00 %	0.00 %	\$0.00
A20 - Basement Construction	57.00 %	0.00 %	\$0.00
B10 - Superstructure	57.00 %	0.00 %	\$0.00
B20 - Exterior Enclosure	111.69 %	22.72 %	\$548,921.03
B30 - Roofing	125.00 %	0.00 %	\$0.00
C10 - Interior Construction	93.45 %	2.17 %	\$25,651.94
C20 - Stairs	57.00 %	0.00 %	\$0.00
C30 - Interior Finishes	99.86 %	25.73 %	\$781,392.45
D10 - Conveying	105.71 %	135.02 %	\$670,322.07
D20 - Plumbing	63.01 %	16.91 %	\$357,157.80
D30 - HVAC	97.25 %	59.64 %	\$3,445,577.87
D40 - Fire Protection	105.71 %	82.55 %	\$386,247.07
D50 - Electrical	109.97 %	90.46 %	\$2,874,050.27
E10 - Equipment	37.14 %	0.00 %	\$0.00
E20 - Furnishings	62.50 %	0.00 %	\$0.00
G20 - Site Improvements	0.00 %	2.36 %	\$38,972.72
G40 - Site Electrical Utilities	106.67 %	0.00 %	\$0.00
Totals:	81.29 %	26.88 %	\$9,128,293.22

Condition Deficiency Priority

Facility Name	Gross Area (S.F.)	FCI %	1 - Response Time (< 2 yr)	2 - Response Time (2-3 yrs)	3 - Response Time (3-4 yrs)	4 - Response Time (4-5 yrs)	5 - Response Time (> 5 yrs)
B523101;Conwell Annex	51,392	28.67	\$608,912.99	\$712,062.15	\$3,538,373.76	\$1,134,916.50	\$3,095,055.10
G523101;Grounds	138,100	1.73	\$0.00	\$0.00	\$38,972.72	\$0.00	\$0.00
Total:		26.88	\$608,912.99	\$712,062.15	\$3,577,346.48	\$1,134,916.50	\$3,095,055.10

Deficiencies By Priority



Executive Summary

Building condition is evaluated based on the functional systems and elements of a building and organized according to the UNIFORMAT II Elemental Classification. The grouping of these systems and elements and applying a current replacement value to them develops a representative building cost model. Cost Models are developed for similar building types and functions. Systems and their elements are evaluated based on their current replacement values, life cycles, installation dates and next renewal dates. Systems and their elements that are within their useful lives are further evaluated to identify current deficient conditions that may have a significant impact on a system's or element's remaining service life, and to determine if they are beyond their predicted expected life. The system's or element's current replacement value is based on RS Means Commercial Cost Data.

Following are the cost model's system details for this facility. The Replacement Value is the amount needed to replace the property of the same present value. The Current Repair Amount, also known as Condition Needs, represents the budgeted contractor installed costs plus owner's soft costs for the repair, replacement or renewal for a component or system level deficiency. It excludes contributing costs for other components or systems that might also be associated with the corrective actions due to packaging the work. Facility Condition Index (FCI) FCI is an industry-standard measurement of facility condition calculated as the ratio of the costs to correct a facility's deficiencies to the facility's Current Replacement Value. It ranges from 0% (new) to 100% (very poor). Condition Index (CI) is calculated as the sum of a renewable system's Remaining Service Life (RSL) divided by the sum of a system's Replacement Value (both values exclude soft-cost to simplify calculation updates) expressed as a percentage ranging from 100% (new) to 0% (expired).

Function:

Gross Area (SF): 51,392

Year Built: 1972

Last Renovation:

Replacement Value: \$31,700,707

Repair Cost: \$9,089,320.50

Total FCI: 28.67 %

Total RSLI: 85.05 %

Description:

Attributes:

General Attributes:

Active:	Open	Bldg ID:	B523101
Sewage Ejector:	Yes	Status:	Accepted by SDP
Site ID:	S523101		

Condition Summary

The Table below shows the CI and FCI for each major building system shown at the UNIFORMAT classification Level II. Note that Systems with lower FCIs require less investment than systems with higher FCIs.

UNIFORMAT Classification	RSLI %	FCI %	Current Repair Cost
A10 - Foundations	57.00 %	0.00 %	\$0.00
A20 - Basement Construction	57.00 %	0.00 %	\$0.00
B10 - Superstructure	57.00 %	0.00 %	\$0.00
B20 - Exterior Enclosure	111.69 %	22.72 %	\$548,921.03
B30 - Roofing	125.00 %	0.00 %	\$0.00
C10 - Interior Construction	93.45 %	2.17 %	\$25,651.94
C20 - Stairs	57.00 %	0.00 %	\$0.00
C30 - Interior Finishes	99.86 %	25.73 %	\$781,392.45
D10 - Conveying	105.71 %	135.02 %	\$670,322.07
D20 - Plumbing	63.01 %	16.91 %	\$357,157.80
D30 - HVAC	97.25 %	59.64 %	\$3,445,577.87
D40 - Fire Protection	105.71 %	82.55 %	\$386,247.07
D50 - Electrical	109.97 %	90.46 %	\$2,874,050.27
E10 - Equipment	37.14 %	0.00 %	\$0.00
E20 - Furnishings	62.50 %	0.00 %	\$0.00
Totals:	85.05 %	28.67 %	\$9,089,320.50

Condition Detail

This section of the report contains results of the Facility Condition Assessment. The building is separated into system components based on UNIFORMAT II classification. The columns in the System Listing table below represent the following:

1. System Code: A code that identifies the system.
2. System Description: A brief description of a system present in the building.
3. Unit Price \$: The unit price of the system.
4. UoM: The unit of measure for of the system.
5. Qty: The quantity for the system
6. Life: anticipated service life for thesystem based on Building Owners and Managers Association (BOMA) recommendations.
7. Year Installed: The date of system installation.
8. Calc Next Renewal Year: The date of system expiration based on the life, NR stands for non renewable.
9. Next Renewal Year: The suggested system expiration date by the assessor based on visual inspection.
10. CI: The Condition Index of the system.
11. FCI: The Facility Condition Index of the system.
12. RSL: Remaining Service Life.
13. eCR: eCOMET Condition Rating (not used).
14. Deficiency \$: The financial investment to repair/replace system.

System Listing

The System Listing table below lists each of the systems organized by their UNIFORMAT II classification. The assessment team was tasked with recording the most recent replacement year of each system, determining the remaining service life based on the theoretical life, and evaluating the condition to confirm the forecast next replacement year. The system listing is the basis for all data contained in the Building Assessment Report.

Additionally, a condition rating (eCR) based on the following guidelines is provided as observed at the time of the assessment.

- Excellent (E) - No noticeable distress or damage. The entire system is free from observable defect.
- Very Good (VG) - Overall no serviceability reduction for the entire system. No degradation of critical components and minor distress and defect noticeable for some but not non critical components within the system.
- Good (G) - Slight or no serviceability reduction for the entire system. There may be noticeable defects for some non critical components and slight noticeable degradation of the critical components.
- Fair (F) - Overall serviceability is degraded but adequate. There may be moderate deterioration for very few of the critical components and few of the non critical components may have severe degradation.
- Marginal (MA) - Overall serviceability and reliability loss. Most if not all of the non critical components suffer from severe degradation and a few of the critical component may have severe degradation.
- Moderate (MO) - Overall a significant serviceability loss. Most if not all the components have severe degradation with the reminder of the component showing visible distress.
- Very Poor (VP) - Overall the system is barely functional. All of the components are severely degraded.
- Non-Functional (NF) - Overall the system does not function with all the components having no serviceability and suffer from severe degradation.

System Code	System Description	Unit Price \$	UoM	Qty	Life	Year Installed	Calc Next Renewal Year	Next Renewal Year	RSLI%	FCI%	RSL	eCR	Deficiency \$	Replacement Value \$
A1010	Standard Foundations	\$24.32	S.F.	51,932	100	1972	2072		57.00 %	0.00 %	57			\$1,262,986
A1030	Slab on Grade	\$15.51	S.F.	51,932	100	1972	2072		57.00 %	0.00 %	57			\$805,465
A2010	Basement Excavation	\$13.07	S.F.	51,932	100	1972	2072		57.00 %	0.00 %	57			\$678,751
A2020	Basement Walls	\$23.02	S.F.	51,932	100	1972	2072		57.00 %	0.00 %	57			\$1,195,475
B1010	Floor Construction	\$92.20	S.F.	51,932	100	1972	2072		57.00 %	0.00 %	57			\$4,788,130
B1020	Roof Construction	\$24.11	S.F.	51,932	100	1972	2072		57.00 %	0.00 %	57			\$1,252,081
B2010	Exterior Walls	\$31.22	S.F.	51,932	100	1903	2003	2103	88.00 %	33.86 %	88		\$548,921.03	\$1,621,317
B2020	Exterior Windows	\$13.63	S.F.	51,932	40	2000	2040	2080	162.50 %	0.00 %	65			\$707,833
B2030	Exterior Doors	\$1.67	S.F.	51,932	25	2000	2025	2050	140.00 %	0.00 %	35			\$86,726
B3010105	Built-Up	\$37.76	S.F.		20				0.00 %	0.00 %				\$0
B3010120	Single Ply Membrane	\$38.73	S.F.		20				0.00 %	0.00 %				\$0
B3010130	Preformed Metal Roofing	\$54.22	S.F.		30				0.00 %	0.00 %				\$0
B3010140	Shingle & Tile	\$38.73	S.F.	51,932	20	2000	2020	2040	125.00 %	0.00 %	25			\$2,011,326
B3020	Roof Openings	\$0.68	S.F.	51,932	20	2000	2020	2040	125.00 %	0.00 %	25			\$35,314
C1010	Partitions	\$14.93	S.F.	51,932	100	1972	2072		57.00 %	0.00 %	57			\$775,345
C1020	Interior Doors	\$3.76	S.F.	51,932	40	2000	2040	2080	162.50 %	8.84 %	65		\$17,253.65	\$195,264
C1030	Fittings	\$4.12	S.F.	51,932	40	2000	2040	2080	162.50 %	3.93 %	65		\$8,398.29	\$213,960
C2010	Stair Construction	\$1.28	S.F.	51,932	100	1972	2072		57.00 %	0.00 %	57			\$66,473

Site Assessment Report - B523101;Conwell Annex

System Code	System Description	Unit Price \$	UoM	Qty	Life	Year Installed	Calc Next Renewal Year	Next Renewal Year	RSLI%	FCI%	RSL	eCR	Deficiency \$	Replacement Value \$
C3010230	Paint & Covering	\$13.21	S.F.	51,932	10	2000	2010	2027	120.00 %	66.69 %	12		\$457,481.86	\$686,022
C3010231	Vinyl Wall Covering	\$0.97	S.F.		15				0.00 %	0.00 %				\$0
C3010232	Wall Tile	\$2.63	S.F.		30				0.00 %	0.00 %				\$0
C3020411	Carpet	\$7.30	S.F.		10				0.00 %	0.00 %				\$0
C3020412	Terrazzo & Tile	\$75.52	S.F.	11,632	50	2000	2050		70.00 %	0.00 %	35			\$878,449
C3020413	Vinyl Flooring	\$9.68	S.F.	35,800	20	2000	2020	2037	110.00 %	0.00 %	22			\$346,544
C3020414	Wood Flooring	\$22.27	S.F.	1,500	25	1903	1928	2042	108.00 %	85.86 %	27		\$28,680.34	\$33,405
C3020415	Concrete Floor Finishes	\$0.97	S.F.	3,000	50	1972	2022		14.00 %	0.00 %	7			\$2,910
C3030	Ceiling Finishes	\$20.97	S.F.	51,932	25	1972	1997	2042	108.00 %	27.11 %	27		\$295,230.25	\$1,089,014
D1010	Elevators and Lifts	\$9.66	S.F.	51,392	35			2052	105.71 %	135.02 %	37		\$670,322.07	\$496,447
D2010	Plumbing Fixtures	\$31.58	S.F.	51,932	35	2000	2035		57.14 %	0.92 %	20		\$15,158.38	\$1,640,013
D2020	Domestic Water Distribution	\$2.90	S.F.	51,932	25	1972	1997	2042	108.00 %	90.85 %	27		\$136,818.72	\$150,603
D2030	Sanitary Waste	\$2.90	S.F.	51,932	25	1972	1997	2042	108.00 %	108.33 %	27		\$163,141.12	\$150,603
D2040	Rain Water Drainage	\$3.29	S.F.	51,932	30	1972	2002	2027	40.00 %	24.61 %	12		\$42,039.58	\$170,856
D3020	Heat Generating Systems	\$18.67	S.F.	51,932	35	1972	2007	2047	91.43 %	22.97 %	32		\$222,665.92	\$969,570
D3030	Cooling Generating Systems	\$24.48	S.F.	51,932	20			2037	110.00 %	36.36 %	22		\$462,208.70	\$1,271,295
D3040	Distribution Systems	\$42.99	S.F.	51,932	25	1972	1997	2042	108.00 %	97.71 %	27		\$2,181,496.80	\$2,232,557
D3050	Terminal & Package Units	\$11.60	S.F.	51,932	20	2000	2020		25.00 %	0.00 %	5			\$602,411
D3060	Controls & Instrumentation	\$13.50	S.F.	51,932	20	1972	1992	2037	110.00 %	82.62 %	22		\$579,206.45	\$701,082
D4010	Sprinklers	\$8.02	S.F.	51,932	35			2052	105.71 %	92.74 %	37		\$386,247.07	\$416,495
D4020	Standpipes	\$0.99	S.F.	51,932	35			2052	105.71 %	0.00 %	37			\$51,413
D5010	Electrical Service/Distribution	\$9.70	S.F.	51,932	30	1972	2002	2047	106.67 %	180.63 %	32		\$909,900.70	\$503,740
D5020	Lighting and Branch Wiring	\$34.68	S.F.	51,932	20	1972	1992	2037	110.00 %	50.58 %	22		\$911,009.38	\$1,801,002
D5030	Communications and Security	\$12.99	S.F.	51,932	15	1972	1987	2032	113.33 %	83.55 %	17		\$563,626.42	\$674,597
D5090	Other Electrical Systems	\$3.81	S.F.	51,932	30	1972	2002	2047	106.67 %	247.40 %	32		\$489,513.77	\$197,861
E1020	Institutional Equipment	\$4.82	S.F.	51,932	35	1972	2007	2028	37.14 %	0.00 %	13			\$250,312
E1090	Other Equipment	\$11.10	S.F.	51,932	35	1972	2007	2028	37.14 %	0.00 %	13			\$576,445
E2010	Fixed Furnishings	\$2.13	S.F.	51,932	40	2000	2040		62.50 %	0.00 %	25			\$110,615
Total									85.05 %	28.67 %			\$9,089,320.50	\$31,700,707

System Notes

The facility description in the site executive summary contains an overview of each system. The notes listed below provide additional information on select systems found within the facility.

No data found for this asset

Renewal Schedule

eCOMET forecasts future Capital Renewal funding needed to address expiring systems based on the Next Renewal year found in the Cost Models. A 3% annual inflation factor is applied to the costs for systems expiring in future years. The table below reflects recommended Capital Renewal funding needs over the next 10 years. Note: Cells with a zero value indicate systems for which renewal is not scheduled in that year.

Inflation Rate: 3%

System	Current Deficiencies	2016	2017	2018	2019	2020	2021	2022	2023	2024	2025	Total
Total:	\$9,089,321	\$0	\$0	\$0	\$0	\$768,195	\$0	\$3,937	\$0	\$0	\$0	\$9,861,453
* A - Substructure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A10 - Foundations	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
A1010 - Standard Foundations	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
A1030 - Slab on Grade	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A20 - Basement Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
A2010 - Basement Excavation	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
A2020 - Basement Walls	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B - Shell	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B10 - Superstructure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B1010 - Floor Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B1020 - Roof Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B20 - Exterior Enclosure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B2010 - Exterior Walls	\$548,921	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$548,921
B2020 - Exterior Windows	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B2030 - Exterior Doors	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B30 - Roofing	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3010 - Roof Coverings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3010105 - Built-Up	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3010120 - Single Ply Membrane	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3010130 - Preformed Metal Roofing	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3010140 - Shingle & Tile	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3020 - Roof Openings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C - Interiors	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C10 - Interior Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C1010 - Partitions	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0

Site Assessment Report - B523101;Conwell Annex

C1020 - Interior Doors	\$17,254	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$17,254
C1030 - Fittings	\$8,398	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$8,398
C20 - Stairs	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C2010 - Stair Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C30 - Interior Finishes	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C3010 - Wall Finishes	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C3010230 - Paint & Covering	\$457,482	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$457,482
C3010231 - Vinyl Wall Covering	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C3010232 - Wall Tile	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C3020 - Floor Finishes	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C3020411 - Carpet	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C3020412 - Terrazzo & Tile	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C3020413 - Vinyl Flooring	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C3020414 - Wood Flooring	\$28,680	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$28,680
C3020415 - Concrete Floor Finishes	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$3,937	\$0	\$0	\$0	\$3,937
C3030 - Ceiling Finishes	\$295,230	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$295,230
D - Services	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D10 - Conveying	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D1010 - Elevators and Lifts	\$670,322	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$670,322
D20 - Plumbing	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D2010 - Plumbing Fixtures	\$15,158	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$15,158
D2020 - Domestic Water Distribution	\$136,819	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$136,819
D2030 - Sanitary Waste	\$163,141	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$163,141
D2040 - Rain Water Drainage	\$42,040	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$42,040
D30 - HVAC	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D3020 - Heat Generating Systems	\$222,666	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$222,666
D3030 - Cooling Generating Systems	\$462,209	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$462,209
D3040 - Distribution Systems	\$2,181,497	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$2,181,497
D3050 - Terminal & Package Units	\$0	\$0	\$0	\$0	\$0	\$768,195	\$0	\$0	\$0	\$0	\$0	\$768,195
D3060 - Controls & Instrumentation	\$579,206	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$579,206
D40 - Fire Protection	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D4010 - Sprinklers	\$386,247	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$386,247
D4020 - Standpipes	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0


Site Assessment Report - B523101;Conwell Annex

D50 - Electrical	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5010 - Electrical Service/Distribution	\$909,901	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$909,901
D5020 - Lighting and Branch Wiring	\$911,009	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$911,009
D5030 - Communications and Security	\$563,626	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$563,626
D5090 - Other Electrical Systems	\$489,514	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$489,514
E - Equipment & Furnishings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E10 - Equipment	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E1020 - Institutional Equipment	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E1090 - Other Equipment	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E20 - Furnishings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E2010 - Fixed Furnishings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0

* Indicates non-renewable system

Forecasted Sustainment Requirement

The following chart shows the current building deficiencies and forecasting sustainment requirements over the next ten years.




10 Year FCI Forecast by Investment Scenario

The chart below illustrates the effect of various investment levels on the building FCI for the next 10 years. The levels of investment shown below include:

- Current FCI: a variable investment amount based on renewing expired systems to maintain the current FCI for the building
- 2% Investment: an annual investment of 2% of the replacement value of the building, escalated for inflation
- 4% Investment: an annual investment of 4% of the replacement value of the building, escalated for inflation


Facility Investment vs. FCI Forecast



Year	Investment Amount Current FCI - 28.67%	2% Investment		4% Investment	
		Amount	FCI	Amount	FCI
2016	\$0	\$653,035.00	26.67 %	\$1,306,069.00	24.67 %
2017	\$12,606,615	\$672,626.00	62.16 %	\$1,345,251.00	58.16 %
2018	\$0	\$692,804.00	60.16 %	\$1,385,609.00	54.16 %
2019	\$0	\$713,589.00	58.16 %	\$1,427,177.00	50.16 %
2020	\$3,378,074	\$734,996.00	65.35 %	\$1,469,992.00	55.35 %
2021	\$0	\$757,046.00	63.35 %	\$1,514,092.00	51.35 %
2022	\$3,937	\$779,757.00	61.36 %	\$1,559,515.00	47.36 %
2023	\$0	\$803,150.00	59.36 %	\$1,606,300.00	43.36 %
2024	\$0	\$827,245.00	57.36 %	\$1,654,489.00	39.36 %
2025	\$128,208	\$852,062.00	55.66 %	\$1,704,124.00	35.66 %
Total:	\$16,116,834	\$7,486,310.00		\$14,972,618.00	

Deficiency Summary by System


Current deficiencies included assemblies that have reached or exceeded their design life or components of the assemblies that are in need of repair. Assemblies that have reached their design life are identified as current deficiencies and assigned the distress 'Beyond Useful Life'. The following chart lists all current deficiencies associated with this facility.



Budget Estimate Total: \$9,089,320.50

Deficiency Summary by Priority

The following chart shows the total repair costs broken down by priority. Assessors assigned deficiencies within eCOMET to one of the following priority categories:



Budget Estimate Total: \$9,089,320.50


Deficiency By Priority Investment Table

The table below shows the current investment cost grouped by deficiency priority and building system.

System Code	System Description	1 - Response Time (< 2 yr)	2 - Response Time (2-3 yrs)	3 - Response Time (3-4 yrs)	4 - Response Time (4-5 yrs)	5 - Response Time (> 5 yrs)	Total
B2010	Exterior Walls	\$0.00	\$548,921.03	\$0.00	\$0.00	\$0.00	\$548,921.03
C1020	Interior Doors	\$0.00	\$0.00	\$0.00	\$17,253.65	\$0.00	\$17,253.65
C1030	Fittings	\$0.00	\$0.00	\$0.00	\$0.00	\$8,398.29	\$8,398.29
C3010230	Paint & Covering	\$0.00	\$0.00	\$457,481.86	\$0.00	\$0.00	\$457,481.86
C3020414	Wood Flooring	\$0.00	\$0.00	\$0.00	\$0.00	\$28,680.34	\$28,680.34
C3030	Ceiling Finishes	\$0.00	\$0.00	\$0.00	\$204,735.67	\$90,494.58	\$295,230.25
D1010	Elevators and Lifts	\$0.00	\$0.00	\$670,322.07	\$0.00	\$0.00	\$670,322.07
D2010	Plumbing Fixtures	\$0.00	\$0.00	\$15,158.38	\$0.00	\$0.00	\$15,158.38
D2020	Domestic Water Distribution	\$0.00	\$0.00	\$136,818.72	\$0.00	\$0.00	\$136,818.72
D2030	Sanitary Waste	\$0.00	\$163,141.12	\$0.00	\$0.00	\$0.00	\$163,141.12
D2040	Rain Water Drainage	\$0.00	\$0.00	\$42,039.58	\$0.00	\$0.00	\$42,039.58
D3020	Heat Generating Systems	\$222,665.92	\$0.00	\$0.00	\$0.00	\$0.00	\$222,665.92
D3030	Cooling Generating Systems	\$0.00	\$0.00	\$0.00	\$0.00	\$462,208.70	\$462,208.70
D3040	Distribution Systems	\$0.00	\$0.00	\$255,430.06	\$0.00	\$1,926,066.74	\$2,181,496.80
D3060	Controls & Instrumentation	\$0.00	\$0.00	\$0.00	\$0.00	\$579,206.45	\$579,206.45
D4010	Sprinklers	\$386,247.07	\$0.00	\$0.00	\$0.00	\$0.00	\$386,247.07
D5010	Electrical Service/Distribution	\$0.00	\$0.00	\$194,057.67	\$715,843.03	\$0.00	\$909,900.70
D5020	Lighting and Branch Wiring	\$0.00	\$0.00	\$911,009.38	\$0.00	\$0.00	\$911,009.38
D5030	Communications and Security	\$0.00	\$0.00	\$366,542.27	\$197,084.15	\$0.00	\$563,626.42
D5090	Other Electrical Systems	\$0.00	\$0.00	\$489,513.77	\$0.00	\$0.00	\$489,513.77
Total:		\$608,912.99	\$712,062.15	\$3,538,373.76	\$1,134,916.50	\$3,095,055.10	\$9,089,320.50

Deficiency Summary by Category

The following chart shows the total repair costs broken down by deficiency categories. Assessors assigned deficiencies to one of the following categories:



Deficiency Details by Priority

The deficiency detail notes listed below provide additional information on identified deficiencies found within the facility.

Priority 1 - Response Time (< 2 yr):

System: D3020 - Heat Generating Systems



Location: Boiler room

Distress: Beyond Service Life

Category: 3 - Operations / Maint.

Priority: 1 - Response Time (< 2 yr)

Correction: Replace boiler, cast iron sectional (50 HP)

Qty: 1.00

Unit of Measure: Ea.

Estimate: \$222,665.92

Assessor Name: System

Date Created: 09/08/2015

Notes: Replace the one existing 1,005MBH cast iron boiler, which is beyond its service life, burners, and exhaust ductwork.

System: D4010 - Sprinklers



Location: Throughout building

Distress: Life Safety / NFPA / PFD

Category: 1 - Health & Safety

Priority: 1 - Response Time (< 2 yr)

Correction: Install a fire protection sprinkler system

Qty: 27,000.00

Unit of Measure: S.F.

Estimate: \$386,247.07

Assessor Name: System

Date Created: 09/08/2015

Notes: Install a fire protection sprinkler system with quick response type heads throughout the building to reduce insurance costs by providing protection for the property. A fire pump may be required depending on the available city water pressure.

Priority 2 - Response Time (2-3 yrs):

System: B2010 - Exterior Walls



Location: Exterior

Distress: Building Envelope Integrity

Category: 3 - Operations / Maint.

Priority: 2 - Response Time (2-3 yrs)

Correction: Repair cracks in masonry - replace missing mortar and repoint - SF of wall area

Qty: 17,000.00

Unit of Measure: S.F.

Estimate: \$548,921.03

Assessor Name: System

Date Created: 10/20/2015

Notes: Repair cracks in masonry, replace missing mortar, tuck-point original building – all walls, window pilasters in basement and chimney

System: D2030 - Sanitary Waste



Location: Throughout building

Distress: Beyond Service Life

Category: 3 - Operations / Maint.

Priority: 2 - Response Time (2-3 yrs)

Correction: Inspect sanitary waste piping and replace damaged sections. (+50KSF)

Qty: 27,000.00

Unit of Measure: S.F.

Estimate: \$132,455.17

Assessor Name: System

Date Created: 09/08/2015

Notes: Hire a qualified contractor to perform a detailed examination of the sanitary waste piping using visual inspection and video cameras to locate and replace any damaged piping and to further quantify the extent of potential failures.

System: D2030 - Sanitary Waste



Location: Boiler room

Distress: Beyond Service Life

Category: 3 - Operations / Maint.

Priority: 2 - Response Time (2-3 yrs)

Correction: Replace sanitary sewage ejector pit and pumps.
(48" dia.)

Qty: 1.00

Unit of Measure: Ea.

Estimate: \$30,685.95


Assessor Name: System

Date Created: 09/08/2015

Notes: Replace existing sewage ejector pump system and piping in the basement as it is beyond its service life.

Priority 3 - Response Time (3-4 yrs):

System: C3010230 - Paint & Covering



Location: Interior

Distress: Beyond Service Life

Category: 3 - Operations / Maint.

Priority: 3 - Response Time (3-4 yrs)

Correction: Repair substrate and repaint interior walls - SF of wall surface

Qty: 53,400.00

Unit of Measure: S.F.

Estimate: \$457,481.86

Assessor Name: System

Date Created: 10/20/2015

Notes: Repair and repaint interior walls

System: D1010 - Elevators and Lifts

This deficiency has no image.

Location: Interior

Distress: Accessibility

Category: 2 - Code Compliance

Priority: 3 - Response Time (3-4 yrs)

Correction: Add interior elevator - 4 floors - adjust the electrical run lengths to hook up the elevator

Qty: 1.00

Unit of Measure: Ea.

Estimate: \$670,322.07

Assessor Name: System

Date Created: 10/20/2015

Notes: Provide elevator serving all floors.

System: D2010 - Plumbing Fixtures



Location: Corridors

Distress: Beyond Service Life

Category: 3 - Operations / Maint.

Priority: 3 - Response Time (3-4 yrs)

Correction: Remove and Replace Water Fountains - without ADA new recessed alcove

Qty: 2.00

Unit of Measure: Ea.

Estimate: \$15,158.38

Assessor Name: System

Date Created: 09/08/2015

Notes: Replace two (2) wall hung drinking fountains and integral refrigerated coolers in the corridors. These units are beyond their service life and are NOT accessible type.

System: D2020 - Domestic Water Distribution



Location: Throughout building

Distress: Beyond Service Life

Category: 3 - Operations / Maint.

Priority: 3 - Response Time (3-4 yrs)

Correction: Replace domestic water piping (75 KSF)

Qty: 27,000.00

Unit of Measure: S.F.

Estimate: \$136,818.72

Assessor Name: System

Date Created: 09/09/2015

Notes: Hire a qualified contractor to perform a detailed inspection of the domestic water piping, in use for over 40 years, and replace any damaged piping.

System: D2040 - Rain Water Drainage



Location: Throughout building

Distress: Beyond Service Life

Category: 3 - Operations / Maint.

Priority: 3 - Response Time (3-4 yrs)

Correction: Replace roof drains - per drain including piping

Qty: 2.00

Unit of Measure: Ea.

Estimate: \$42,039.58

Assessor Name: System

Date Created: 09/08/2015

Notes: Hire a qualified contractor to perform a detailed examination of the rain water drainage piping using visual inspection and video cameras to locate and replace any damaged piping and to further quantify the extent of potential failures.

System: D3040 - Distribution Systems



Location: Throughout building

Distress: Beyond Service Life

Category: 3 - Operations / Maint.

Priority: 3 - Response Time (3-4 yrs)

Correction: Perform testing to identify and replace damaged steam and condensate piping.

Qty: 27,000.00

Unit of Measure: S.F.

Estimate: \$255,430.06

Assessor Name: System

Date Created: 09/08/2015

Notes: Hire a qualified contractor to examine the steam/condensate piping, in service for over 40 years, and perform additional testing to locate and replace any damaged piping and to further quantify the extent of potential failures.

System: D5010 - Electrical Service/Distribution



Location: throughout the building

Distress: Beyond Service Life

Category: 3 - Operations / Maint.

Priority: 3 - Response Time (3-4 yrs)

Correction: Add Panelboard

Qty: 1.00

Unit of Measure: Ea.

Estimate: \$194,057.67

Assessor Name: System

Date Created: 10/19/2015

Notes: Install new panelboards.

System: D5020 - Lighting and Branch Wiring



Location: throughout the building

Distress: Beyond Service Life

Category: 3 - Operations / Maint.

Priority: 3 - Response Time (3-4 yrs)

Correction: Replace Lighting Fixtures (SF)

Qty: 0.00

Unit of Measure: S.F.


Estimate: \$596,623.41

Assessor Name: System

Date Created: 10/19/2015

Notes: Install new lighting system for the entire building

System: D5020 - Lighting and Branch Wiring



Location: throughout the building

Distress: Beyond Service Life

Category: 3 - Operations / Maint.

Priority: 3 - Response Time (3-4 yrs)

Correction: Replace Wiring Devices (SF) - surface mounted conduit and boxes

Qty: 0.00

Unit of Measure: S.F.

Estimate: \$314,385.97

Assessor Name: System

Date Created: 10/19/2015

Notes: Install adequate (two on each wall minimum) surface-mounted receptacles in all classrooms and other areas within the building.

System: D5030 - Communications and Security



Location: throughout the building

Distress: Beyond Service Life

Category: 3 - Operations / Maint.

Priority: 3 - Response Time (3-4 yrs)

Correction: Replace fire alarm system

Qty: 1.00

Unit of Measure: S.F.

Estimate: \$366,542.27

Assessor Name: System

Date Created: 10/19/2015

Notes: Install new automated FA system

System: D5090 - Other Electrical Systems



Location: throughout the building

Distress: Life Safety / NFPA / PFD

Category: 1 - Health & Safety

Priority: 3 - Response Time (3-4 yrs)

Correction: Add Emergency/Exit Lighting

Qty: 1.00

Unit of Measure: Ea.

Estimate: \$288,408.75

Assessor Name: System

Date Created: 10/19/2015

Notes: Install new emergency exit signs emergency lights

System: D5090 - Other Electrical Systems

This deficiency has no image.

Location: Electrical room

Distress: Building / MEP Codes

Category: 2 - Code Compliance

Priority: 3 - Response Time (3-4 yrs)

Correction: Add Standby Generator System

Qty: 1.00

Unit of Measure: Ea.

Estimate: \$201,105.02

Assessor Name: System

Date Created: 10/19/2015

Notes: Install a new Emergency generator

Note: A multiplier of 1.4 was used instead of 1.0 to cover the cost of other related work.

No attachment picture, since there is no Emergency generator at this time.

Priority 4 - Response Time (4-5 yrs):

System: C1020 - Interior Doors



Location: Interior

Distress: Accessibility

Category: 2 - Code Compliance

Priority: 4 - Response Time (4-5 yrs)

Correction: Replace door knobs with compliant lever type

Qty: 31.00

Unit of Measure: Ea.

Estimate: \$17,253.65

Assessor Name: System

Date Created: 10/20/2015

Notes: Replace all door hardware for accessibility

System: C3030 - Ceiling Finishes



Location: Interior

Distress: Beyond Service Life

Category: 3 - Operations / Maint.

Priority: 4 - Response Time (4-5 yrs)

Correction: Repair and resurface plaster ceilings - 2 coats plaster

Qty: 15,600.00

Unit of Measure: S.F.

Estimate: \$204,735.67

Assessor Name: System

Date Created: 10/20/2015

Notes: Repair plaster ceilings (25% area), repaint all ceilings

System: D5010 - Electrical Service/Distribution



Location: Electrical Room

Distress: Beyond Service Life

Category: 3 - Operations / Maint.

Priority: 4 - Response Time (4-5 yrs)

Correction: Replace Service Transformer

Qty: 0.00

Unit of Measure: Ea.

Estimate: \$458,555.28

Assessor Name: System

Date Created: 10/19/2015

Notes: Install a new electrical Service. Replace Service Transformer, new 480 V distribution Panel and new MCC

System: D5010 - Electrical Service/Distribution



Location: Throughout the building

Distress: Beyond Service Life

Category: 3 - Operations / Maint.

Priority: 4 - Response Time (4-5 yrs)

Correction: Add Electrical Switchgear and Distribution System

Qty: 0.00

Unit of Measure: Ea.

Estimate: \$257,287.75

Assessor Name: System

Date Created: 10/19/2015

Notes: Install new distribution panels

System: D5030 - Communications and Security



Location: throughout the building

Distress: Beyond Service Life

Category: 3 - Operations / Maint.

Priority: 4 - Response Time (4-5 yrs)

Correction: Add/Replace Clock System or Components

Qty: 0.00

Unit of Measure: Ea.

Estimate: \$146,328.29

Assessor Name: System

Date Created: 10/19/2015

Notes: Install new Clock System

Note: A multiplier of 1.3 was selected instead of 1.0 to cover the cost for other related work.

System: D5030 - Communications and Security



Location: throughout the building

Distress: Security Issue

Category: 1 - Health & Safety

Priority: 4 - Response Time (4-5 yrs)

Correction: Add/Replace Video Surveillance System

Qty: 1.00

Unit of Measure: Ea.

Estimate: \$50,755.86

Assessor Name: System

Date Created: 10/19/2015

Notes: Install new Video Surveillance System with Cameras and CCTV

Priority 5 - Response Time (> 5 yrs):

System: C1030 - Fittings



Location: Interior

Distress: Inadequate

Category: 4 - Capital Improvement

Priority: 5 - Response Time (> 5 yrs)

Correction: Replace missing or damaged signage - insert the number of rooms

Qty: 31.00

Unit of Measure: Ea.

Estimate: \$8,398.29

Assessor Name: System

Date Created: 10/20/2015

Notes: Provide new signage throughout the building

System: C3020414 - Wood Flooring



Location: Interior

Distress: Appearance

Category: 3 - Operations / Maint.

Priority: 5 - Response Time (> 5 yrs)

Correction: Remove and replace partial area of wood flooring and refinish entire floor - set replacement area

Qty: 3,100.00

Unit of Measure: S.F.

Estimate: \$28,680.34

Assessor Name: System

Date Created: 10/20/2015

Notes: Refinish hardwood flooring

System: C3030 - Ceiling Finishes



Location: Interior

Distress: Beyond Service Life

Category: 3 - Operations / Maint.

Priority: 5 - Response Time (> 5 yrs)

Correction: Remove and replace suspended acoustic ceilings - lighting not included

Qty: 6,000.00

Unit of Measure: S.F.

Estimate: \$90,494.58

Assessor Name: System

Date Created: 10/20/2015

Notes: Replace all suspended acoustical ceilings

System: D3030 - Cooling Generating Systems



Location: Throughout building

Distress: Inadequate

Category: 4 - Capital Improvement

Priority: 5 - Response Time (> 5 yrs)

Correction: Install chilled water system with distribution piping and pumps. (+75KSF)

Qty: 27,000.00

Unit of Measure: S.F.

Estimate: \$462,208.70

Assessor Name: System

Date Created: 09/08/2015

Notes: Remove the window air conditioning units and install a 70 ton air-cooled chiller with chilled water distribution piping and pumps to supply more reliable air conditioning for the building with a much longer service life.

System: D3040 - Distribution Systems



Location: Throughout building

Distress: Beyond Service Life

Category: 3 - Operations / Maint.

Priority: 5 - Response Time (> 5 yrs)

Correction: Provide classroom FC units and dedicated OA ventilation system. (20 clsrms)

Qty: 21.00

Unit of Measure: C

Estimate: \$1,744,280.82

Assessor Name: System

Date Created: 09/08/2015

Notes: Remove the existing cast iron steam radiators and fin tube radiators and install fan coil units with hot and chilled water coils and a dedicated outdoor air system.

System: D3040 - Distribution Systems



Location: Throughout building

Distress: Inadequate

Category: 4 - Capital Improvement

Priority: 5 - Response Time (> 5 yrs)

Correction: Install HVAC unit for Administration (2000 students).

Qty: 420.00

Unit of Measure: Pr.

Estimate: \$181,785.92

Assessor Name: System

Date Created: 09/08/2015

Notes: Provide ventilation for the administration office by installing a fan coil air handling unit hung from the structure with outdoor air ducted to the unit from louvers in window openings.

System: D3060 - Controls & Instrumentation



Location: Throughout building

Distress: Energy Efficiency

Category: 4 - Capital Improvement

Priority: 5 - Response Time (> 5 yrs)

Correction: Replace pneumatic controls with DDC (75KSF)

Qty: 27,000.00

Unit of Measure: S.F.

Estimate: \$579,206.45

Assessor Name: System

Date Created: 09/08/2015

Notes: Replace the electric controls for the HVAC systems with modern DDC modules, valves and actuators to improve reliability and energy efficiency. Provide a new building automation system (BAS) with communication interface to the preferred system in use throughout the District.

Equipment Inventory

The following table represents the inventory details of the inventory found in the building, which fall under the following subsystems:

Subsystem	Inventory	Qty	UoM	Location	Manufacturer	Model Number	Serial Number	Barcode	Life	Install Date	Next Renewal	Raw Cost	Inventory Cost
D3020 Heat Generating Systems	Boiler, oil fired, flame retention burner, cast iron, steam, gross output, 1084 MBH, includes standard controls and insulated flush jacket, packaged	1.00	Ea.	Boiler Room	HB Smith	350 Mills			35	1972	2007	\$21,558.10	\$23,713.91
												Total:	\$23,713.91

Executive Summary

Building condition is evaluated based on the functional systems and elements of a building and organized according to the UNIFORMAT II Elemental Classification. The grouping of these systems and elements and applying a current replacement value to them develops a representative building cost model. Cost Models are developed for similar building types and functions. Systems and their elements are evaluated based on their current replacement values, life cycles, installation dates and next renewal dates. Systems and their elements that are within their useful lives are further evaluated to identify current deficient conditions that may have a significant impact on a system's or element's remaining service life, and to determine if they are beyond their predicted expected life. The system's or element's current replacement value is based on RS Means Commercial Cost Data.

Following are the cost model's system details for this facility. The Replacement Value is the amount needed to replace the property of the same present value. The Current Repair Amount, also known as Condition Needs, represents the budgeted contractor installed costs plus owner's soft costs for the repair, replacement or renewal for a component or system level deficiency. It excludes contributing costs for other components or systems that might also be associated with the corrective actions due to packaging the work. Facility Condition Index (FCI) FCI is an industry-standard measurement of facility condition calculated as the ratio of the costs to correct a facility's deficiencies to the facility's Current Replacement Value. It ranges from 0% (new) to 100% (very poor). Condition Index (CI) is calculated as the sum of a renewable system's Remaining Service Life (RSL) divided by the sum of a system's Replacement Value (both values exclude soft-cost to simplify calculation updates) expressed as a percentage ranging from 100% (new) to 0% (expired).

Function:

Gross Area (SF): 138,100

Year Built: 1972

Last Renovation:

Replacement Value: \$2,255,059

Repair Cost: \$38,972.72

Total FCI: 1.73 %

Total RSLI: 28.42 %

Description:

Attributes:

General Attributes:

Bldg ID:	S523101	Site ID:	S523101
----------	---------	----------	---------

Condition Summary

The Table below shows the CI and FCI for each major building system shown at the UNIFORMAT classification Level II. Note that Systems with lower FCIs require less investment than systems with higher FCIs.

UNIFORMAT Classification	RSLI %	FCI %	Current Repair Cost
G20 - Site Improvements	0.00 %	2.36 %	\$38,972.72
G40 - Site Electrical Utilities	106.67 %	0.00 %	\$0.00
Totals:	28.42 %	1.73 %	\$38,972.72

Condition Detail

This section of the report contains results of the Facility Condition Assessment. The building is separated into system components based on UNIFORMAT II classification. The columns in the System Listing table below represent the following:

1. System Code: A code that identifies the system.
2. System Description: A brief description of a system present in the building.
3. Unit Price \$: The unit price of the system.
4. UoM: The unit of measure for of the system.
5. Qty: The quantity for the system
6. Life: anticipated service life for the system based on Building Owners and Managers Association (BOMA) recommendations.
7. Year Installed: The date of system installation.
8. Calc Next Renewal Year: The date of system expiration based on the life, NR stands for non renewable.
9. Next Renewal Year: The suggested system expiration date by the assessor based on visual inspection.
10. CI: The Condition Index of the system.
11. FCI: The Facility Condition Index of the system.
12. RSL: Remaining Service Life.
13. eCR: eCOMET Condition Rating (not used).
14. Deficiency \$: The financial investment to repair/replace system.

System Listing

The System Listing table below lists each of the systems organized by their UNIFORMAT II classification. The assessment team was tasked with recording the most recent replacement year of each system, determining the remaining service life based on the theoretical life, and evaluating the condition to confirm the forecast next replacement year. The system listing is the basis for all data contained in the Building Assessment Report.

Additionally, a condition rating (eCR) based on the following guidelines is provided as observed at the time of the assessment.

- Excellent (E) - No noticeable distress or damage. The entire system is free from observable defect.
- Very Good (VG) - Overall no serviceability reduction for the entire system. No degradation of critical components and minor distress and defect noticeable for some but not non critical components within the system.
- Good (G) - Slight or no serviceability reduction for the entire system. There may be noticeable defects for some non critical components and slight noticeable degradation of the critical components.
- Fair (F) - Overall serviceability is degraded but adequate. There may be moderate deterioration for very few of the critical components and few of the non critical components may have severe degradation.
- Marginal (MA) - Overall serviceability and reliability loss. Most if not all of the non critical components suffer from severe degradation and a few of the critical component may have severe degradation.
- Moderate (MO) - Overall a significant serviceability loss. Most if not all the components have severe degradation with the reminder of the component showing visible distress.
- Very Poor (VP) - Overall the system is barely functional. All of the components are severely degraded.
- Non-Functional (NF) - Overall the system does not function with all the components having no serviceability and suffer from severe degradation.

System Code	System Description	Unit Price \$	UoM	Qty	Life	Year Installed	Calc Next Renewal Year	Next Renewal Year	RSLI%	FCI%	RSL	eCR	Deficiency \$	Replacement Value \$
G2010	Roadways	\$11.52	S.F.		30				0.00 %	0.00 %				\$0
G2020	Parking Lots	\$7.65	S.F.	48,800	30				0.00 %	0.00 %				\$373,320
G2030	Pedestrian Paving	\$11.52	S.F.	44,100	40				0.00 %	7.67 %			\$38,972.72	\$508,032
G2040	Site Development	\$4.36	S.F.	138,100	25				0.00 %	0.00 %				\$602,116
G2050	Landscaping & Irrigation	\$3.78	S.F.	45,200	15				0.00 %	0.00 %				\$170,856
G4020	Site Lighting	\$3.58	S.F.	138,100	30	1972	2002	2047	106.67 %	0.00 %	32			\$494,398
G4030	Site Communications & Security	\$0.77	S.F.	138,100	30	1972	2002	2047	106.67 %	0.00 %	32			\$106,337
Total									28.42 %	1.73 %			\$38,972.72	\$2,255,059

System Notes

The facility description in the site executive summary contains an overview of each system. The notes listed below provide additional information on select systems found within the facility.

No data found for this asset

Renewal Schedule

eCOMET forecasts future Capital Renewal funding needed to address expiring systems based on the Next Renewal year found in the Cost Models. A 3% annual inflation factor is applied to the costs for systems expiring in future years. The table below reflects recommended Capital Renewal funding needs over the next 10 years. Note: Cells with a zero value indicate systems for which renewal is not scheduled in that year.


Inflation Rate: 3%

System	Current Deficiencies	2016	2017	2018	2019	2020	2021	2022	2023	2024	2025	Total
Total:	\$38,973	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$38,973
G - Building Sitework	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G20 - Site Improvements	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G2010 - Roadways	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G2020 - Parking Lots	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G2030 - Pedestrian Paving	\$38,973	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$38,973
G2040 - Site Development	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G2050 - Landscaping & Irrigation	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G40 - Site Electrical Utilities	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G4020 - Site Lighting	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G4030 - Site Communications & Security	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0

** Indicates non-renewable system*

Forecasted Sustainment Requirement

The following chart shows the current building deficiencies and forecasting sustainment requirements over the next ten years.




10 Year FCI Forecast by Investment Scenario

The chart below illustrates the effect of various investment levels on the building FCI for the next 10 years. The levels of investment shown below include:

- Current FCI: a variable investment amount based on renewing expired systems to maintain the current FCI for the building
- 2% Investment: an annual investment of 2% of the replacement value of the building, escalated for inflation
- 4% Investment: an annual investment of 4% of the replacement value of the building, escalated for inflation


Facility Investment vs. FCI Forecast



Year	Investment Amount Current FCI - 1.73%	2% Investment		4% Investment	
		Amount	FCI	Amount	FCI
2016	\$0	\$46,454.00	-0.27 %	\$92,908.00	-2.27 %
2017	\$701,052	\$47,848.00	27.03 %	\$95,696.00	23.03 %
2018	\$0	\$49,283.00	25.03 %	\$98,567.00	19.03 %
2019	\$0	\$50,762.00	23.03 %	\$101,524.00	15.03 %
2020	\$0	\$52,285.00	21.03 %	\$104,569.00	11.03 %
2021	\$0	\$53,853.00	19.03 %	\$107,706.00	7.03 %
2022	\$0	\$55,469.00	17.03 %	\$110,938.00	3.03 %
2023	\$0	\$57,133.00	15.03 %	\$114,266.00	-0.97 %
2024	\$0	\$58,847.00	13.03 %	\$117,694.00	-4.97 %
2025	\$0	\$60,612.00	11.03 %	\$121,224.00	-8.97 %
Total:	\$701,052	\$532,546.00		\$1,065,092.00	


Deficiency Summary by System

Current deficiencies included assemblies that have reached or exceeded their design life or components of the assemblies that are in need of repair. Assemblies that have reached their design life are identified as current deficiencies and assigned the distress 'Beyond Useful Life'. The following chart lists all current deficiencies associated with this facility.



Deficiency Summary by Priority

The following chart shows the total repair costs broken down by priority. Assessors assigned deficiencies within eCOMET to one of the following priority categories:



Budget Estimate Total: \$38,972.72


Deficiency By Priority Investment Table

The table below shows the current investment cost grouped by deficiency priority and building system.

System Code	System Description	1 - Response Time (< 2 yr)	2 - Response Time (2-3 yrs)	3 - Response Time (3-4 yrs)	4 - Response Time (4-5 yrs)	5 - Response Time (> 5 yrs)	Total
G2030	Pedestrian Paving	\$0.00	\$0.00	\$38,972.72	\$0.00	\$0.00	\$38,972.72
	Total:	\$0.00	\$0.00	\$38,972.72	\$0.00	\$0.00	\$38,972.72

Deficiency Summary by Category

The following chart shows the total repair costs broken down by deficiency categories. Assessors assigned deficiencies to one of the following categories:



Deficiency Details by Priority

The deficiency detail notes listed below provide additional information on identified deficiencies found within the facility.

Priority 3 - Response Time (3-4 yrs):

System: G2030 - Pedestrian Paving

This deficiency has no image.

Location: Grounds/ site

Distress: Accessibility

Category: 2 - Code Compliance

Priority: 3 - Response Time (3-4 yrs)

Correction: Install an exterior ADA ramp - based on 5' wide by the linear foot - up to a 48" rise - per LF of ramp - figure 1 LF per inch of rise

Qty: 30.00

Unit of Measure: L.F.

Estimate: \$38,972.72

Assessor Name: Ben Nixon

Date Created: 10/20/2015

Notes: Provide accessible ramp at the main entrance

Equipment Inventory

The following table represents the inventory details of the inventory found in the building, which fall under the following subsystems:

No data found for this asset

Glossary

ABMA	American Boiler Manufacturers Association http://www.abma.com/
ACEEE	American Council for an Energy-Efficient Economy
ACGIH	American Council of Governmental and Industrial Hygienists
AEE	Association of Energy Engineers
AFD	Adjustable Frequency Drive
AFTC	After Tax Cash Flow
AGA	American Gas Association
AHU	Air Handling Unit
Amp	Ampere
ANSI	American National Standards Institute
ARI	Air Conditioning and Refrigeration Institute
ASD	Adjustable Speed Drive
ASHRAE	American Society of Heating Refrigerating and Air-Conditioning Engineers Inc.
ASME	American Society of Mechanical Engineers
Assessment	Visual survey of a facility to determine its condition. It involves looking at the age of systems reviewing information from local sources and visual evidence of potential problems to assign a condition rating. It does not include destructive testing of materials or testing of systems or equipment for functionality.
ATS	After Tax Savings
AW	Annual worth
BACNET	Building Automation Control Network
BAS	Building Automation System
BCR	Benefit Cost Ratio
BEP	Business Energy Professional (AEE)
BF	Ballast Factor
BHP	Boiler Horsepower (boilers)
BHP	Brake Horsepower (motors)
BLCC	Building Life Cycle Cost analysis program (FEMP)
BOCA	Building Officials and Code Administrators
BTCF	Before Tax Cash Flow

Site Assessment Report - S523101;Conwell Annex

BTS	Before Tax Savings
Btu	British thermal unit
Building Addition	An area space or component of a building added to a building after the original building's year built date.
CAA	Clean Air Act
CAAA-90	Clean Air Act Amendments of 1990
CABO	Council of American Building Officials
CAC	Conventional Air Conditioning
CADDET	Center for the Analysis and Dissemination of Demonstrated Energy Technologies
Calculated Next Renewal	The year a system or element would be expected to expire based solely on the date it was installed and the expected useful lifetime for that kind of system.
Capital Renewal	Capital renewal is condition work (excluding suitability and energy audit work) that includes the replacement of building systems or elements (as they become obsolete or beyond their useful life) not normally included in an annual operating budget. Calculated next renewal The year a system or element would be expected to expire based solely on the date it was installed and the expected useful lifetime for that kind of system. Next renewal The assessor adjusted expected useful life of a system or element based on on-site inspection.
CDD	Cooling Degree Days
CDGP	Certified Distributed Generation Professional
CEC	California Energy Commission
CEM	Certified Energy Manager
CEP	Certified Energy Procurement Professional
CFC	Chlorofluorocarbon
CFD	Cash Flow Diagram
CFL	Compact Fluorescent Light
CFM cfm	Cubic Feet per Minute
CHP	Combined Heat and Power (a.k.a. cogeneration)
CHW	Chilled Water
Condition	Condition refers to the state of physical fitness or readiness of a facility system or system element for its intended use.
COP	Coefficient of Performance
Cp	Heat Capacity of Material
CPUC	California Public Utility Commission
CRI	Color Rendering Index
CRT	Cathode Ray Tube VDT HMI

Site Assessment Report - S523101;Conwell Annex

CTC	Competitive Transition Charge
Cu	Coefficient of Utilization
Current Replacement Value (CRV)	CRV represents the hypothetical total cost of rebuilding or replacing an existing facility in current dollars to its optimal condition (excluding auxiliary facilities) under current codes and construction standards.
Cv	Value Coefficient
CWS	Chilled Water System
D d	Distance (usually feet)
DB	Dry Bulb
DCV	Demand Control Ventilation
DD	Degree Day
DDB	Double Declining Balance
DDC	Direct Digital Controls
Deferred maintenance	Deferred maintenance is condition work (excluding suitability and energy audit needs) deferred on a planned or unplanned basis to a future budget cycle or postponed until funds are available.
Deficiency	A deficiency is a repair item that is damaged missing inadequate or insufficient for an intended purpose.
Delta	Difference
Delta P	Pressure Difference
Delta T	Temperature Difference
DG	Distributed Generation
DOE	Department of Energy
DP	Dew Point
DR	Demand Response
DX	Direct Expansion Air Conditioner
EA	Energy Audit
EBITDA	Earnings before Interest Taxes Depreciation and Amortization
ECI	Energy Cost Index
ECM	Energy Conservation Measure
ECO	Energy Conservation Opportunity
ECPA	Energy Conservation and Production Act
ECR	Energy Conservation Recommendation
ECS	Energy Control System

Site Assessment Report - S523101;Conwell Annex

EER	Energy Efficiency Ratio
EERE	Energy Efficiency and Renewable Energy division of US DOE
EIA	Energy Information Agency
EIS	Energy Information System
EMCS	Energy Management Computer System
EMO	Energy Management Opportunity
EMP	Energy Management Project
EMR	Energy Management Recommendation
EMS	Energy Management System
Energy Utilization Index (EUI)	EUI is the measure of total energy consumed in the cooling or heating of a building in a period expressed as British thermal unit (BTU) per (cooled or heated) gross square foot.
EO	Executive Order
EPA	Environmental Protection Agency
EPACT	Energy Policy Act of 1992
EPCA	Energy Production and Conservation Act of 1975
EPRI	Electric Power Research Institute
EREN	Efficiency and Renewable Energy (Division of USDOE)
ERV	Energy Recovery Ventilator
ESCO	Energy Service Company
ESPC	Energy Savings Performance Contract
EUI	Energy Use Index
EWG	Exempt Wholesale Generators
Extended Facility Condition Index (EFCI)	EFCI is calculated as the condition needs for the current year plus facility system renewal needs going out to a set time in the future divided by Current Replacement Value.
f	Frequency
F	Fahrenheit
Facility	A facility refers to site(s) building(s) or building addition(s) or combinations thereof that provide a particular service.
Facility Condition Assessment (FCA)	FCA is a process for evaluating the condition of buildings and facilities for programming and budgetary purposes through an on site inspection and evaluation process.
Facility Condition Index (FCI)	FCI is an industry-standard measurement of a facility's condition that is the ratio of the cost to correct a facility's deficiencies to the Current Replacement Value of the facilities. The higher the FCI the poorer the condition of a facility. After an FCI is established for all buildings within a portfolio a building's condition can be ranked relative to other buildings. The FCI may also represent the condition of a portfolio based on the cumulative FCIs of the portfolio's facilities.

Site Assessment Report - S523101;Conwell Annex

FC	Footcandle
FCA	Fuel Cost Adjustment
FEMIA	Federal Energy Management Improvement Act of 1988
FEMP	Federal Energy Management Program
FERC	Federal Energy Regulatory Commission
FESR	Fuel Energy Savings Ratio
FLA	Full Load Amps
FLF	Facility Load Factor (usually monthly)
FLRPM	Full Load Revolutions per Minute
FMS	Facility Management System
FPM fpm	Feet per Minute (velocity)
FSEC	Florida Solar Energy Center
Ft	Foot
GPM gpm	Gallons per Minute
GRI	Gas Research Institute
Gross Square Feet (GSF)	The size of the enclosed floor space of a building in square feet measured to the outside face of the enclosing wall.
GUI	Graphical User Interface
H h	Enthalpy Btu/lb
HCFC	Hydrochlorofluorocarbons
HDD	Heating Degree days
HFC	Hydrofluorocarbons
HHV	Higher Heating Value
HID	High Intensity Discharge (lamp)
HMI	Human Machine Interface
HMMI	Human Man Machine Interface
HO	High Output (lamp)
HP Hp hp	Horsepower
HPS	High Pressure Sodium (lamp)
HR	Humidity Ratio
Hr hr	Hour

Site Assessment Report - S523101;Conwell Annex

HRU	Heat Recovery Unit
HVAC	Heating Ventilation and Air-Conditioning
Hz	Hertz
I	Intensity (lumen output of lamp)
I i	Interest rate or Discount rate
IAQ	Indoor Air Quality
ICA	International Cogeneration Alliance
ICBO	International Conference of Buildings Officials
ICC	International Code Council
ICP	Institutional Conservation Program
IECC	International Energy Conservation Code
IEEE	Institute of Electrical and Electronic Engineers
IESNA	Illuminating Engineering Society of North America
Install year	The year a building or system was built or the most recent major renovation date (where a minimum of 70 of the system's Current Replacement Value (CRV) was replaced).
IRP	Integrated Resource Planning
IRR	Internal Rate of Return
ISO	Independent System Operator
ITA	Independent Tariff Administrator
k	Kilo multiple of thousands in SI system
K	Kelvins (color temperature of lamp)
K k	Thermal Conductivity of Material
KVA	Kilovolt Ampere
KVAR	Kilovolt Ampere Reactive
kW	kiloWatt
kWh	kiloWatt hour
L	Length (usually feet)
LCC	Life Cycle Costing
LDC	Local Distribution Company
LEED	Leadership in Energy and Environmental Design
LEED EB	LEED for Existing Buildings

Site Assessment Report - S523101;Conwell Annex

LEED NC	LEED for new construction
LF	Load Factor
LHV	Lower Heating Value
Life cycle	The period of time that a building or site system or element can be expected to adequately serve its intended function.
LPS	Low Pressure Sodium (lamp)
Lu	Lumen Output of a Lamp or Fixture
M	Mega multiple of millions in SI system
M&V	Measurement and Verification
MACRS	Modified Accelerated Cost Recovery System
MARR	Minimum Attractive Rate of Return
Mbtu	Thousand Btu
MCF	Thousand Cubic Feet (usually of gas)
MEC	Model Energy Code
Mm	Multiple of Thousands in I/P System
MMBtu	Million Btu
MMCS	Maintenance Management Computer System
MMI	Man Machine Interface
MMS	Maintenance Management System
MSE 2000	Management System for Energy 2000 (ANSI Georgia Tech Univ)
MW	MegaWatt
MWH MWh	MegaWatt hour
NAAQS	National Ambient Air Quality Standards
NAESCO	National Association of Energy Service Companies
NAIMA	North American Insulation Manufacturers Association
NEA	National Energy Act of 1978
NECPA	National Energy Conservation Policy Act
NEMA	National Electrical Manufacturer's Association
NERC	North American Electric Reliability Council
Next Renewal	The Next Renewal date is an override of the 'Calculated Next Renewal' date and is based upon the assessor's visual inspection.

Site Assessment Report - S523101;Conwell Annex

NFPA	National Fire Protection Association
NGPA	National Gas Policy Act of 1978
NLRPM	No Load Revolutions per Minute (speed)
Nn	Equipment or Project lifetime in economic analysis
NOPR	Notice of Proposed Rule Making from FERC
NOx	Nitrogen Oxide Compounds
NPV	Net present value in economic analysis
NREL	National Renewable Energy Laboratory
NUG	Non-Utility Generator
O&M	Operation and Maintenance
OA	Outside Air
ODP	Ozone Depletion Potential
OPAC	Off-Peak Air Conditioning
P	Present value in economic analysis
PBR	Performance Based Rates
PEA	Preliminary Energy Audit
PF	Power Factor
PID	Proportional plus integral plus derivative (control system)
PM	Portfolio Manager in Energy Star rating system
PM	Preventive Maintenance
PoolCo	Power Pool Company or Organization
POU	Point of Use
PQ	Power Quality
PSC	Public Service Commission
PSIA psia	Pounds per square inch absolute (pressure)
PSIG psig	Pounds per square inch gauge (pressure)
PUC	Public Utility Commission
PUHCA	Public Utilities Holding Company Act of 1935
PURPA	Public Utilities Regulatory Policies of 1978
PV	Photovoltaic system

Site Assessment Report - S523101;Conwell Annex

PV	Present Value
PW	Present Worth
PX	Power Exchange
q	Rate of heat flow in Btu per hour
Q	Heat load due to conduction using degree days
QF	Qualifying Facility
R	Electrical resistance
R	Thermal Resistance
RC	Remote controller
RCR	Room Cavity Ratio
RCRA	Resource Conservation and Recovery Act
Remaining Service Life (RSL)	RSL is the number of years service remaining for a system or equipment item. It is automatically calculated based on the difference between the current year and the 'Calculated Next Renewal' date or the 'Next Renewal' date whichever one is the later date.
Remaining Service Life Index (RSLI)	RSLI is defined as a percentage ratio of the remaining service life of a system. It usually ranges from 0 to 100
REMR	Repair Evaluation Maintenance Rehabilitation (REMR) is a scale used to objectively rank systems based on their condition
Renewal Schedule	A timeline that provides the items that need repair the year in which the repair is needed and the estimated price of the renewal.
RH	Relative Humidity
RLA	Running Load Amps
RMS	Root Mean Square
RO	Reverse Osmosis
ROI	Return on Investment
RPM	Revolutions Per Minute
RTG	Regional Transmission Group
RTO	Regional Transmission Organization
RTP	Real Time Pricing
SBCCI	Southern Building Code Congress International
SC	Scheduling Coordinator
SC	Shading Coefficient
SCADA	Supervisory Control and Data Acquisition Systems

Site Assessment Report - S523101;Conwell Annex

SEER	Seasonal Energy Efficiency Ratio
SHR	Sensible Heat Ratio
Site	The grounds and utilities roadways landscaping fencing and other typical land improvements needed to support the facility.
Soft Cost	An expense item that is not considered direct construction cost. Soft cost includes architectural engineering financing legal fees and other pre-and-post construction expenses.
SOx	Sulfur Oxide Compounds
SP	Static Pressure
SP SPB	Simple Payback
SPP	Simple Payback Period
SPP	Small Power Producers
STR	Stack Temperature Rise
SV	Specific Volume
System	System refers to building and related site work elements as described by ASTM Uniformat II Classification for Building Elements (E1557-97) a format for classifying major facility elements common to most buildings. Elements usually perform a given function regardless of the design specification construction method or materials used. See also Uniformat II.
T	Temperature
T	Tubular (lamps)
TAA	Technical Assistance Audit
TCP/IP	Transmission Control Protocol/Internet Protocol
TES	Thermal Energy Storage
THD	Total Harmonic Distortion
TOD	Time of Day
TOU	Time of Use
TQM	Total Quality Management
TransCo	Transmission Company
U	Thermal Conductance
UDC	Utility Distribution Company
UL	Underwriters Laboratories
UNIFORMAT II	The ASTM UNIFORMAT II Classification for Building Elements (E1557-97) a format for classifying major facility components common to most buildings.
USGBC	US Green Building Council
v	Specific Volume

Site Assessment Report - S523101;Conwell Annex

V	Volts Voltage
V	Volume
VAV	Variable Air Volume
VDT	Video Display Terminal
VFD	Variable Frequency Drive
VHO	Very High Output
VSD	Variable Speed Drive
W	Watts
W	Width
WB	Wet bulb
WH Wh	Watt Hours
Year built	The year that a building or addition was originally built based on substantial completion or occupancy.
Z	Electrical Impedance