

## Facility Condition Assessment Summary Report

This report provides a summary of the Facility Condition Index (FCI) value of a school facility and select major building systems. The FCI calculation represents the cost of needed repairs divided by the replacement value. The FCI is a numerical value of condition and helps to identify the need for renewal or replacement of specific parts of the facility. The FCI is particularly useful when comparing similar facilities within the same portfolio.

### Crossan School

Governance	DISTRICT	Report Type	Elementary
Address	7350 Bingham St. Philadelphia, Pa 19111	Enrollment	377
Phone/Fax	215-728-5014 / 215-728-5955	Grade Range	'00-05'
Website	Www.Philasd.Org/Schools/Crossan	Admissions Category	Neighborhood
		Turnaround Model	N/A

### Building/System FCI Tiers

Facility Condition Index (FCI) = $\frac{\text{Cost of Assessed Deficiencies}}{\text{Replacement Value}}$				
< 15%	15 to 25%	25 to 45%	45 to 60%	> 60%
Buildings				
Minimal Current Capital Funding Required	Refurbish Systems in building	Replace Systems in building.	Building should be considered for major renovation.	Building should be considered for closing/replacement.
Systems				
Perform routine maintenance on system	System requires minor repairs	System should be studied to determine repair vs. replacement.	System is nearing end of its life expectancy and should be considered for replacement	System should be replaced as part of the Capital Program

### Building and Grounds

	FCI	Repair Costs	Replacement Cost
<b>Overall</b>	<b>54.81%</b>	<b>\$8,521,476</b>	<b>\$15,546,186</b>
Building	55.55 %	\$8,361,398	\$15,050,924
Grounds	32.32 %	\$160,078	\$495,262

### Major Building Systems

Building System	System FCI	Repair Costs	Replacement Cost
<b>Roof</b> (Shows physical condition of roof)	00.00 %	\$0	\$453,840
<b>Exterior Walls</b> (Shows condition of the structural condition of the exterior facade)	00.36 %	\$4,032	\$1,123,097
<b>Windows</b> (Shows functionality of exterior windows)	175.45 %	\$961,480	\$548,008
<b>Exterior Doors</b> (Shows condition of exterior doors)	245.47 %	\$108,302	\$44,121
<b>Interior Doors</b> (Classroom doors)	231.50 %	\$247,244	\$106,802
<b>Interior Walls</b> (Paint and Finishes)	11.34 %	\$45,593	\$401,954
<b>Plumbing Fixtures</b>	84.59 %	\$348,004	\$411,387
<b>Boilers</b>	22.54 %	\$128,072	\$568,091
<b>Chillers/Cooling Towers</b>	65.60 %	\$488,652	\$744,877
<b>Radiators/Unit Ventilators/HVAC</b>	222.29 %	\$2,907,811	\$1,308,100
<b>Heating/Cooling Controls</b>	158.90 %	\$652,744	\$410,778
<b>Electrical Service and Distribution</b>	174.63 %	\$515,418	\$295,152
<b>Lighting</b>	07.81 %	\$82,394	\$1,055,243
<b>Communications and Security</b> (Cameras, Pa System and Fire Alarm)	83.24 %	\$329,033	\$395,260

Please note that some FCIs may be over 100% because there are times when replacing a building system requires that other building systems be upgraded to complete the installation. A FCI of 0.0% represents that there are no current deficiencies with the associated system.

School District of Philadelphia  
**S823001; Crossan**  
Final  
**Site Assessment Report**

January 31, 2017



## Table of Contents

Site Executive Summary	4
Site Condition Summary	13
<b><u>B823001:Crossan</u></b>	15
Executive Summary	15
Condition Summary	16
Condition Detail	17
System Listing	18
System Notes	20
Renewal Schedule	21
Forecasted Sustainment Requirement	24
Condition Index Forecast by Investment Scenario	25
Deficiency Summary By System	26
Deficiency Summary By Priority	27
Deficiency By Priority Investment	28
Deficiency Summary By Category	29
Deficiency Details By Priority	30
Equipment Inventory Detail	57
<b><u>G823001:Grounds</u></b>	58
Executive Summary	58
Condition Summary	59
Condition Detail	60
System Listing	61
System Notes	62
Renewal Schedule	63
Forecasted Sustainment Requirement	64
Condition Index Forecast by Investment Scenario	65
Deficiency Summary By System	66
Deficiency Summary By Priority	67
Deficiency By Priority Investment	68

## Site Assessment Report

---

Deficiency Summary By Category	69
Deficiency Details By Priority	70
Equipment Inventory Detail	74
Glossary	75

## Site Executive Summary

The organization of this report, as displayed in the Table of Contents, follows the structure of the associated eCOMET database. The overall node for each school campus begins with the letter "S", which indicates the "Site" label. Each Site is comprised of separate "Building" and "Grounds" nodes; their asset names begin with the letters "B" and "G" respectively. Information rolls up to the Site node from the Building and Grounds nodes. This Site report combines facility information with subsections for the Buildings And Grounds nodes.

The basis for the evaluation of condition is the functional systems and elements of a building and grounds organized according to the UNIFORMAT II Elemental Classification. The grouping of these systems and elements and applying a current replacement value to them develops a representative building cost model. Cost Models are typically developed for similar building types and functions. Evaluation of systems and their elements takes into account their current replacement values, life cycles, installation dates and next renewal dates. Systems and their elements that are within their useful lives are further evaluated to identify current deficient conditions that may have a significant impact on a system's or element's remaining service life, and to determine if they are beyond their predicted expected life. The system's or element's current replacement value is based on RS Means Commercial Cost Data.

Following are the cost model's system details for this facility. The Replacement Value is the amount needed to replace the property of the same present value. The Current Repair Amount, also known as Condition Needs, represents the budgeted contractor installed costs plus owner's soft costs for the repair, replacement or renewal for a component or system level deficiency. It excludes contributing costs for other components or systems that might also be associated with the corrective actions due to packaging the work. Facility Condition Index (FCI) is an industry-standard measurement calculated as the ratio of the repair costs to correct a facility's deficiencies to the facility's Current Replacement Value. Condition Index (CI) for a system is calculated as the sum of the deficiencies divided by the sum of a system's Replacement Value (both values include soft-cost) expressed as a percentage ranging from 0% 100%.

Gross Area (SF):	30,428
Year Built:	1924
Last Renovation:	
Replacement Value:	\$15,546,186
Repair Cost:	\$8,521,475.93
Total FCI:	54.81 %
Total RSLI:	62.81 %



### Description:

Facility Condition Assessment  
October 2015

**School District of Philadelphia**  
**Kennedy Crossan Elementary School**  
**7350 Bingham Street**  
**Philadelphia, PA 19111**

30,428 SF / 400 Students / LN 08

### General

Kennedy Crossan Elementary School is located at 7350 Bingham Street. The main entrance faces Bingham Street. The main building was constructed in 1924, has 30,428 square feet, and is 2 stories tall with a full basement. This is a small school with only 13 classrooms, an auditorium, a "gymateria" (gym-cafeteria) and an IMC. The precast concrete "portable building" ("Element 2") constructed in the rear playground around 1967 was not inspected since it is considered "temporary". The Kennedy Crossan School can be found on the National Historical Register, number 88002261 with the address of 7341 Palmetto Street. This building, designed by Irwin Catharine, the Philadelphia Public School Chief Architect during that time and is considered Late Gothic Revival with stone



## Site Assessment Report - S823001;Crossan

---

exterior wall construction and limestone coping, window heads and sills, and grand entrance portico. Paul Devlin, the Building Engineer accompanied the team during the building inspection.

The Inspection team met with Principal Lynn Millard at the time of inspection. She expressed concern over a number of deficiencies such as the lack of toilet facilities for the children on first and second floors (the District should consider converting one set of Faculty toilets on the 1<sup>st</sup> or 2<sup>nd</sup> floor to children's toilets), poor functioning gang toilets on basement floor, clock system that does not function, peeling paint on many walls, and a heating system that does not provide uniform heat (the heat is either all on or all off). She also indicated that a security camera system is required to be able to monitor outside doors and the site.

### Architectural/Structural

Foundations appear to be constructed of concrete exterior walls and brick internal walls. Boiler Room walls are mostly in good condition with one vertical crack observed in a foundation wall and a crack along the intersection of the sloped concrete front stair support slab and the foundation wall; these cracks are less than ¼" thickness and should be structurally repaired to prevent further growth of the cracks. Extensive peeling paint was observed on some of the basement walls, mainly due to high room moisture related to excessive steam released by the boilers, but in general, the boiler room appeared to be well maintained. Other rooms in the basement are the only student toilet rooms in the building and the gymnasium/cafeteria ("gymateria"). Footings were not seen and their construction type or condition could not be ascertained. .

Floor slabs in the boiler room are in good condition although covered with dirt and in need of stripping, cleaning and repainting. Exposed concrete floor slabs in other basement rooms also need stripping and resealing. Upper floor slabs are also constructed of cast-in-place concrete with cast-in-place concrete beams. Cracking and spalling of the above ground concrete structure was not observed anywhere.

Roof construction over the main building is reinforced concrete beams and deck, bearing on masonry walls. The superstructure is constructed of reinforced concrete columns, beams, and floor slabs. The main building roof deck is flat with minimum overall slope; areas around roof drains are depressed for drainage and crickets are located between roof drains to improve flow into the roof drains. Roof access is via a door out of a stone masonry penthouse; a steep, narrow, dark stairway with very low headroom up from a 2<sup>nd</sup> floor stairway landing providing access to the roof through a penthouse. The roof over the auditorium is constructed of concrete beams and decking like the other areas of the building. From the small plank in the dark attic space adjacent to the roof access door, the roof structure appeared to be in good condition.

Exterior walls and are in very good condition. It appears as if there was an extensive stone repointing project completed over the last few years as there were no cracks observed in stone wall joints and many of the upper stone joints appeared to be lighter than the other joints. Even though the chimney was also apparently repointed, some joint cracking is reappearing at the base of the stack and should be repointed before they grow into longer and deeper cracks. There are leaks along the base of the auditorium wall where the recessed walks into the building are located; water is seeping in above the cafeteria windows along the intersection of the stone wall and the concrete walk. Evidence of the water seepage can be seen in the cafeteria over the windows. This are should be sealed to prevent further seepage into the wall below.

Exterior windows were replaced in the 1990's with bronze anodized aluminum frame operable single hung units with single thickness clear plexiglass acrylic vision panel glazing. Windows are in poor condition with oxidized frames and severely scratched single-pane plexiglass vision panels. Operable units are difficult to operate up and down or do not stay open due to broken internal counterbalance weights, accidentally slamming closed in some cases – a potential safety hazard. Single pane plexiglass units do not meet today's energy code requirements and are large sources of heat loss. Basement level windows are at grade when viewed from the outside; galvanized steel security screens attached to basement windows, the lower section of 1<sup>st</sup> floor windows, and the auditorium windows are in good condition.

Exterior doors are painted steel framed flush hollow metal units with steel frames. The main entrance on Bingham Street and other side entrances have decorative limestone headers and jambs framing the doors. The main entrance also has limestone arch work and the name of the school engraved into a stone panel. The limestone has been recently cleaned and stands out in highlighting the style and artistic technique of that era. Doors have small glazing vision panels, protected with steel mesh. Some doors surfaces are in poor condition with worn paint and dented panels and frames, in need of repair. There are no ADA compliant handicap entrances, no accessible ramps and no elevators. A handicap entrance should be provided; the southwest stair into the niche adjacent to the auditorium is an area where a ramp could be constructed.

Roof covering on the main building flat roof is a ceramic granule impregnated, fully adhered rolled asphalt sheet system, installed 3 years ago and in very good condition. Brick rooftop structures and stone parapets are flashed with metal flashing the same granule impregnated membrane. Fan structures lack flashing and are sealed only with caulking and a black sealant applied to the penetration

## Site Assessment Report - S823001;Crossan

---

and the roof membrane. A new off-white factory painted aluminum coping is installed on top of the stone wall and is in good condition. Roof openings include toilet room vents, ventilation ductwork, and roof drains. Flashing of the penetrations appears to be in good condition, although it looks like they have already been repaired at least once. Painted aluminum counter flashing matches the coping and covers the connection of the roof flashing into the brick rooftop structures and parapets. Crickets are used to provide additional slope for water to reach roof drains. A sort of overflow scupper is created by use of "battlements" along the front of the main roof coping, which are decorative gothic revival recesses in the coping that also allow water to flow off the roof if the roof drains were clogged. Good continued maintenance is required to help this new membrane last as long as possible.

Partitions in basements are constructed of brick masonry. The upper 3 floors of the building have plaster on wood lath on masonry partitions. There are wood framed clerestory glass panels located in walls above classroom doors in the corridors. These panels are in generally good condition being above the reach of anyone, but the glass is not wired or fire rated and should be replaced with a fire rated element. Except for areas damaged by leaks and heavy moisture, partitions are in good condition.

Interior doors are original wood and plate glass (not fire rated or wired) raised panel doors with original hardware or replacement hardware at least 20 years of age. Wood doors to the Fire Towers and some basement doors were replaced with plain wood doors with narrow vision panels, which are now all in poor condition. Most original wood doors are damaged, have broken or replacement molding and glass, and old knob-type hardware. Stairways doors are steel and wired glass units which do not latch, are dented and damaged, and are not fire rated. Some interior basement doors are painted wood doors in metal frames. Doors are generally in poor condition throughout the building, are not ADA compliant, do not have ADA or proper locking hardware, and are not fire rated where required. Stairway doors do not positively latch as required of fire rated doors. Classroom doors do not have security locking feature from inside classrooms. All doors and hardware need to be replaced. The only doors that might be salvaged are the auditorium and the lobby doors; being a historical building, it might be worth considering ways to repair and upgrade the glazing and construction of these highly decorative corridor doors.

Interior fittings/hardware include black slate chalkboards with oak frames and cork bulletin board surrounds, still in good condition and used today. Classrooms and the Library have freestanding book cases and low shelving around the other walls... Some classrooms have smartboards which connect to the teacher's laptop computers, used for teaching in lieu of blackboards. Toilet room partitions are new solid plastic replacement partition in the boy's and girl's gang toilets in the basement. They are in good condition. Toilet room accessories (toilet paper dispensers, soap, paper towel or dryers, grab bars, door latches) have been recently replaced and seem to be present and operational.

Stair construction consists of concrete treads with steel nosings, concrete risers, and concrete stringers with wood handrails (29" high), wood guard rails (36" high), and steel balusters with 3" spacing. Since handrail and guard heights are not in compliance with today's codes, new handrail and guard systems are required. Concrete treads, platforms and landings have years of dirt sealed into the surface; they should be stripped and resealed. Some basement stairs are painted which does not necessarily make them look any better, although stripping them at this point is probably not an option; this stairway should be repainted. The front staircase is all marble with steel and wood handrails and is in excellent condition; the center handrail could be the original handrail, but it does not meet today's code for height and extensions at top and bottom. Replacing it should be considered but in light of the possible historical significance, it might be acceptable to leave it in place.

Wall finishes in all 1<sup>st</sup> and 2<sup>nd</sup> floor spaces are plaster which is in good condition. There are areas of water damage on walls in the auditorium backstage area due to past leaks before the roof replacement; it is thought those leaks have been corrected. There are no folding wood partitions in this school. Corridors have 48" high marble panel wainscots that protect the walls from damage and are generally in good condition. Some of the stained oak wood trim in classrooms, halls, offices is damaged and worn requiring filling and but the trim can probably be refinished. Student toilet room ("gang" toilet rooms) located in the basement, have brick walls with a glazed brick wainscot and painted brick above, all in good condition. The auditorium has a dark stained oak paneled wood wainscot that is in need of repair and refinishing. There are some areas of plaster walls in the auditorium back stage that have been damaged from water entering the building through the roof or steel lintels. It is thought that these leaks have been addressed and that the plaster should be repaired. Plaster walls above the wood wainscot in the auditorium are in good condition. The stage area has a simple, subtle, engaged pilaster and beam design around the stage opening, constructed of plaster. The gym/cafeteria ("gymateria") has glazed brick and painted brick walls like the toilet rooms and windows or doors on all walls. The basketball basket was located between two windows which are only partially protected by security screens.

Floor finishes on 1<sup>st</sup> and 2<sup>nd</sup> floors consist of dark stained oak floors in the auditorium and wood floors or VCT (vinyl composition tile) in classrooms. Wood floors are in good enough condition to be stripped, sanded, and refinished with minor plank repairs required in the auditorium. The upper floor classroom with 12"x12" vinyl composition tile (VCT) over the wood and faculty office with VCT are in good condition. The gymnasium which also serves as the cafeteria is finished in VCT. That floor is installed over concrete, is not in good condition, and should be replaced. Stair walking surfaces are finished in exposed concrete that have years of dirt ground into the surfaces; these should be stripped, cleaned and resealed. All corridor floors are finished with 2'x2' (nominal size) concrete tiles

## Site Assessment Report - S823001;Crossan

---

which appear to be a monolithic system and highly durable. Edges along the walls are painted; these corridor floors have recently been stripped and cleaned and look very good; painted coved edges are somewhat worn but are also in good condition. These floors demonstrate the fact that these nearly 100 year old concrete floors are durable and good looking if cleaned and refinished properly. The IMC (Instructional Material Center) is in the basement down 8 steps from the first floor but up from the basement; it is located on its own level in the building. It is finished with carpet which should be replaced.

Ceiling finishes are mostly exposed concrete deck throughout the building with suspended or surface mounted fluorescent lighting fixtures. One classroom has a suspended acoustical tile ceiling with recessed fluorescent lighting fixtures in good condition. The auditorium has a decorative plaster ceiling with suspended chandeliers. The auditorium ceiling has water damage from leaks that (it is said) have been repaired; the ceiling should be repaired and repainted.

Furnishings consist of folding wood seating in the auditorium. Some of the chairs need to be refinished, but in general most seem to be operating properly.

There is no elevator or ADA accessible ramp into this building. With ramp access to a basement door and a first floor door, it may not be necessary to provide an elevator. If access is provided, the location of the Library would still be isolated from access, being on its own level between the basement and the first floor; it will need to have a small "chair lift" or relocated to provide access to all students.

### **Mechanical**

Plumbing Fixtures –The building is equipped with wall hung urinals (flush valve type), wall hung water closets (flush valve type), and wall hung lavatories with wheel handle faucets. Many of the original plumbing fixtures remain in service, however, these fixtures have reached the end of their service life and should be replaced. New fixtures will provide lower water consumption and provide savings on water heating costs. The bathrooms are also equipped with floor drains.

There are a combination of electric water coolers and drinking fountains in the corridors at the restrooms as well as other corridor locations are wall hung fountains. Most fixtures appear to be the original installed equipment. The replacement of all drinking fountains is recommended as the equipment is approximately 92 years old and beyond its service life.

Wall hung service sinks are original and are available throughout the building for use by the janitorial staff. Service sinks are typically located in the corridors near EWCs or drinking fountains. The sinks appear have exceeded their service life, and should be replaced.

Domestic Water Distribution – It appears that the 3" domestic water service piping is mostly soldered copper. Water service enters the building in the basement, with double check backflow preventer (RPZA – reduced pressure zone assembly) and a 2" water meter on the main line upon entering the building. The water meter appears to be new. The piping is copper with soldered joints. The distribution piping appears to be original and is at the end of its service life and is recommended to be inspected and repaired as needed.

There is one natural gas fired vertical tank water heater, Bradford White, 75 gallon, model 75T80B3N, gas input 76,000 btuh at this facility which is located in the boiler mechanical room. The hot water system is equipped with a recirculation pump as well. The water heater appears to be in satisfactory condition and should not need replacement within the next 10 years as it appears to have been installed in 2013. A water softener was located in the boiler room for treating the boiler make up water system. The water softener system appears to be relatively new.

Sanitary Waste - The sanitary waste piping system in the original building is extra heavy cast iron with lead and oakum seals and appears to be the original piping installed in the building. It is therefore recommended to inspect this piping and repair or replace sections as needed. The sanitary system leaves the building by gravity flow.

Rain Water Drainage - The rain water drains from the roof are routed through mechanical chases in the building and connect to the underground site drainage system. There are overflow scuppers for the building. A duplex sump pump is located in the boiler mechanical equipment room.

Energy Supply - Duplex fuel oil supply pumps provide the required fuel to the boilers when operating with fuel oil. The fuel storage tank is located underground in the paved area nearing Palmetto Street. The fuel pumps and controls are original vintage, are beyond their serviceable life and therefore should be replaced. The 6" natural gas service enters the building in the basement and is equipped with a gas booster system. The natural gas main is welded, black steel piping while the branches are threaded, black steel.

Heat Generating Systems – Low pressure steam is generated at 15 lbs./sq. in. or less by two 2,702 MBH Weil McLain 94 series, cast



## Site Assessment Report - S823001;Crossan

---

iron, sectional, model 1394 steam boilers with dual fuel burners. All boilers are equipped with Power Flame dual fuel burners, natural gas and number 2 fuel oil, model CR4-GO-25. The boilers appear to have been installed in the 1990's and based on this would need to be replaced in the next 10 – 15 years. There is draft control on both boiler flues. Combustion air louvers equipped with electric actuators serve the boiler room to provide combustion air for the boiler operation. Burner controls provide full modulation with electronic ignition. Burner oil pumps are driven by independent motors. The gas train serving each boiler appears to have code required venting of the regulators and dual solenoid valves with venting of the chamber between. The oil supply to the burner is equipped with dual solenoid valves and strainer/disposable media filter.

**Distribution Systems** – The building steam distribution piping is black steel with welded fittings. The condensate piping is Schedule 80 black steel with threaded fittings. The piping has been in use beyond its service life and will require more frequent attention from the maintenance staff to address pipe/valve failures as time passes. The District should hire a qualified contractor to examine the distribution piping and perform additional testing to locate and replace any damaged piping and to further quantify the extent of potential failures. The District should budget for replacing this piping over the next 5 years.

The boiler feed water is collected by a boiler feedwater pad mounted system and is treated with a combination of chemicals by a water treatment controller. The condensate is returned directly to the boiler feedwater tank and then pumped back to the boiler. There are no condensate receivers or pumps. The condensate return piping is black steel with threaded joints. The boiler feedwater assembly is equipped with three pumps and a pump control panel. Replace boiler feedwater system. The steam traps are failing throughout the building and have not been replaced for 20 years as per the building engineer. It is recommended that the District conduct a steam trap survey to determine the quantity and condition of all steam traps. The boiler feed tank, pumps and associated components are nearing the end of their service life and should be replaced.

Fresh air is admitted into the building by opening windows. The auditorium is heated by steam radiators with enclosures or guards which are located at the perimeter walls. In addition for the auditorium, ventilation and additional heating for the space was provided by a house fan in the basement which is operational but is not used. The air was pushed through a supply plenum which distributed air through mushroom supply air diffusers below the auditorium seats. The air was exhausted from other ducts built into the walls, up through the attic space, and out through roof mounted vents.

The building uses steam radiators in the classrooms, stair landings, hall, corridors and bathrooms and currently is the sole source of heat for these areas. In some locations steam convectors are utilized. During our survey many of the steam radiators had protective covers, however, there are some steam radiators in service without guards or enclosures, these units should be replaced with finned tube convectors or have guards added to protect students from exposure to the hot surfaces.

The gymnasium/cafeteria is served by horizontally ceiling suspended steam radiators. Ventilation is provided by operable windows. It is recommended to replace these systems with a roof top heating and cooling unit with an overhead supply air distribution system and return air ductwork and low return intake grilles which would be protected from damage.

**Terminal & Package Units** - There are a few which have window air conditioning units but predominantly the building does not have cooling systems. There are roof mounted exhaust fans of which serve the restrooms. Two split system AC cooling only units serve two server rooms in the building. One unit is 1-1/2 tons (condenser model PUY-A18NHA3) while the other is a two ton unit (condenser model PUY-A24NHA3). Both units are manufactured by Mitsubishi.

**Controls & Instrumentation** - The original pneumatic systems still provide basic control functions. Pneumatic room thermostats drive the unit ventilators, the damper actuators and control valves. Wall mounted pneumatic thermostats on the corridor walls control the steam radiators. An air compressor which generates control air for the temperature control system could not be located. The maintenance staff reports temperature control is generally lacking throughout the facility. Potential problems with oil, moisture or dirt in the pneumatic copper tubing can be one source of problems. The small rubber gaskets and tubing connections at control devices can become brittle over time and fail to compound control problems. The pneumatic systems are beyond their service life and require too much attention from the maintenance staff. The original control valves, dampers and pneumatic actuators are over 92 years old and should be replaced. These controls should be converted to DDC.

A new building automation system (BAS) with modern DDC modules and communications network should be installed to serve the HVAC systems in this building to improve reliability and energy efficiency. An interface should be provided with the preferred system in use throughout the District.

**Sprinklers** - The school building is NOT covered by an automatic sprinkler system. Installing a sprinkler system with quick response type heads should reduce insurance costs by providing protection for the property investment. A fire pump may be required depending on the available city water pressure.

### Electrical

Site Electrical Service for the main building is delivered from medium voltage overhead lines on wooden poles located along Bleigh Street. One pole-mounted power transformer with medium voltage primary service (voltage level unknown at this time) and a 120/208VAC secondary transformer at an estimated available power of 112.5KVA are installed for supplying power to facility.

The service entrance to the facility consists of a disconnect switch and utility meter and two main distribution panels (one for lighting and one for power), located in an electrical room in the basement of the building. Distribution panels do not have enough capacity for future loads and should be replaced.

Power distribution is accomplished with several lighting/receptacle and power panels located throughout the building. All panel boards along with the associated wiring have exceeded their useful life and should be replaced. As recommended by Building Owners and Managers Association (BOMA), panel boards shall be replaced with those having more circuit breakers than needed to accommodate additional branch circuits that might be needed in the future.

Classrooms, corridors, offices, and other areas typically have an adequate number of duplex receptacles on each wall. No major deficiencies with respect to receptacle numbers and location were observed.

Approximately 95% of lighting fixtures are fluorescent-type with T8 lamps. In general lighting fixtures are in good working condition with a few fixtures requiring replacement. Incandescent lighting fixtures are used in some areas such as the basement corridors and attic spaces. These fixtures are near the useful life and are no longer commercially available. They should be replaced with fluorescent lighting fixtures. The Auditorium has decorative chandeliers which are in need of repair. Since they are old, vintage fixtures, the recommendation is to replace them with updated lighting fixtures that maintain the vintage look of the old fixtures. The gymnasium has 2x2 surface mounted metal halide fixtures. These fixtures are near end of the useful life and their lighting level does meet IES (Illuminating Engineering Society) minimum requirements; these fixtures should also be replaced.

The Fire Alarm System consists of a 120V manual fire alarm system. The system does not meet current fire alarm codes and should be replaced.

The school telephone and data systems are new and working adequately. A main distribution frame (MDF) along with a telephone PBX system (telephone within an enterprise that switches calls between enterprise users on local lines while allowing all users to share a certain number of external phone lines) serving as the communication system for the building. The school also equipped with Wi-Fi system.

Separate PA system does not exist. The school uses the telephone system for public announcements. This system is working adequately.

Each classroom is provided with telephone intercom service. The system permits paging and intercom communications from the main office to classrooms, classrooms to the main office, and classroom to classroom. Outside line access from a classroom phone through the PBX is blocked. The system interfaces with master clock system for class change signaling utilizing paging speakers. The system also is equipped with a tone generator and has input from program/clock controller.

The existing master clock system consists of a simplex master controller with electric clocks in classrooms and offices. The system is old and has exceeded its useful service life and is not functioning properly thus requiring replacement. The existing bell system is working adequately.

Video surveillance system is not provided in the school. The school has an access control system including door contact and motion security sensors in critical areas. The school desires a complete video surveillance system with cameras located in critical areas, such as exit doors, corridors, and building exterior areas. The cameras should be controlled by a Closed Circuit Television (CCTV) system.

Public address / Music system and a separate PA system does not exist. The school uses the telephone system for public announcements. This system is working adequately.

Intercom and paging systems are completely functional. The paging system is one way communication from office to classrooms. Two way communications are accomplished through wall mounted phones in the classrooms and other areas. The paging speakers are old and shall be replaced.

School is provided with time system controller consisting of combination of clock and speaker installed on the wall in each classrooms and a master time programmer manufactured by "STANDARD" located in the main office. The clocks are not controlled properly with

## Site Assessment Report - S823001;Crossan

---

the central master controller. System is old and has exceeded its useful service life thus requiring replacement. The present bell system is working adequately.

Television system is not provided in the school.

Emergency Power System (backup power generator) is provided in the school. A 10KW, 240/120V, 1PH, 3W, diesel generator including transfer switch, located in the Boiler Room. It feeds emergency lighting and other critical emergency loads. The system is old and has exceeded its useful service life.

Uninterruptible Power System (UPS) is provided for the Local Area Network located in the main IT room.

The emergency power system provides power to emergency lighting fixtures and exit lights in the building. A sufficient number of lighting fixtures in corridors, egress ways and exit signs are fed by emergency back-up power.

Lightning Protection System is adequate. It is accomplished with air terminals mounted on the chimney; however, some repairs are needed. A study is needed to verify that the air terminals provide the proper coverage.

Grounding is present and is adequate.

Elevator is not provided in the school.

Site Lighting System is adequate. There are sufficient numbers of flood lights with photo cells provided around the building. No major deficiencies were observed.

Site Video Surveillance system is not provided in the school.

Site Paging system is provided in the school and working adequately. Existing speakers provide adequate coverage in the playground.

### **Grounds**

Paving in the rear is constructed of asphalt. Approximately one-third of the paved area needs to be repaved; the other area should be crackfilled and sealed to preserve the surface life. This expansive and completely fenced in paved area serves as the playground; faculty parking is not permitted inside and is located along local side streets. Granite block stairways into the rear of the building are in need of regrouting. One of the stair and walkways (the south side of the auditorium) has a gap between the concrete walkway and the exterior auditorium wall which is the probable source of water entering the cafeteria windows below; this gap should be filled with a backer rod and sealant to block the water infiltration. New handrails and guards are required at the two exterior stairs leading away from the auditorium and the basement window well.

Concrete walkway around the side, front and rear of the building are in good condition and appear to have been recently repaired. Some isolated 4'x4' panels are cracked and in need of replacement.

Painted steel fencing is generally in good condition and appears to have been recently installed. There is a gate providing street and pedestrian access, also installed recently with the new fence. However, the steel fence over the area way to the basement needs to be replaced.

### **RECOMMENDATIONS**

#### **Architectural**

- Strip and repaint concrete foundation (basement) walls in mechanical rooms (5,000sf)
- Clean and repaint basement floor in mechanical rooms (5000sf)
- Repair vertical and horizontal cracks in mechanical room foundation, slab above over window, and along edge of front stair support slab (60 ft.)
- Seal gap between walkway into door near auditorium and auditorium exterior walls (40 ft.)
- Replace all exterior windows with insulated single hung units (160)3.5x8
- Replace all exterior doors with ADA and code compliant exit hardware; repaint doors and frames. (14)3x7
- Remove non-rated glass panels between classrooms and corridors; fill with fire rated glazing (15 @ 18sf)
- Remove and replace all wood interior doors, frames and hardware in classrooms with fire rated doors to corridors and non-rated doors to closets, offices, etc. (50)

## Site Assessment Report - S823001;Crossan

---

- Provide security hardware for classrooms and offices, locking from inside classroom. (20)
- Refinish first floor lobby, auditorium, and office doors opening to corridor, replacing glazing with fire rated glazing (12 door panels)
- Provide handicap accessible toilet room accessories and new partitions for 1 toilet room (2<sup>nd</sup> fl.) (2 water closets, 1 lavatory)
- Repair water damage, cracks, and repaint all damaged interior plaster walls and ceilings in auditorium, gymateria and corridors (1,000sf)
- Remove and replace stairway handrails and guards with code compliant systems (2) 3 story;=50x6=300 ft. of handrail+guard
- Regrout cracking joints between limestone block tread/risers at exterior stairs (10 treads)
- Strip, sand, repair and refinish all wood floors in classrooms and in auditorium (14,150sf)
- Refinish wood wainscot in auditorium (600sf)
- Remove and replace all 12"x12" VCT floors in gymateria (3150sf)
- Repair or replace damaged folding wood auditorium chairs (500)
- Replace carpet in IMC and other rooms (800sf)
- Repoint chimney (100sf)

### Mechanical

- Replace all lavatories in the building with lower flow fixtures, as the fixtures are original.
- Replace all water closets in the building with lower flow fixtures, as the fixtures are original.
- Replace all urinals in the building with lower flow fixtures, as the fixtures are original.
- Replace the wall hung drinking fountains and integral refrigerated coolers in the corridors and at the restrooms. These units are well beyond their service life and most are NOT accessible type.
- Replace service sinks (janitor sinks) in the building.
- Hire a qualified contractor to perform a detailed examination of the sanitary waste piping using visual inspection and video cameras to locate and replace any damaged piping and to further quantify the extent of potential failures.
- Replace the gallon underground storage tank (UST) installed before 2000.
- Add automatic sanitizing chemicals to the stainless steel sink in the cafeteria.
- Replace natural gas fired vertical tank water heater.
- Inspect and replace the original as needed the domestic water piping in the building
- Hire a qualified contractor to perform a detailed examination of the sanitary waste piping using visual inspection and video cameras to locate and replace any damaged piping and to further quantify the extent of potential failures.
- Conduct a steam trap survey to identify and replace failed traps passing live steam into the condensate piping system.
- Replace boiler feedwater system.
- Hire a qualified contractor to examine the steam and condensate piping in service for 92 years and perform additional testing to locate and replace any damaged piping and to further quantify the extent of potential failures. The District should budget for replacing this piping over the next 10 years.
- Replace duplex fuel oil pumps.
- Replace the steam convection units and any of the original radiant heating (manifold) terminals fashioned from welded piping still present in the building (or add guards) with finned tube elements to protect students from exposure to the hot surfaces.
- Install unit ventilators throughout the building designed to provide adequate ventilation per ASHRAE Stds 62. The new units shall be equipped with hot water / chilled water coils and integral heat recovery wheels. Install steam converters in the existing boiler room with circulating pumps, distribution piping and controls to provide heating hot water for the new coils.
- Remove the window air conditioning units and install a 250 ton air-cooled chiller on the roof with chilled water distribution piping and pumps located in a mechanical room on the basement level to supply more reliable air conditioning for the building with a much longer service life.
- Provide ventilation, heating and cooling for the gymnasium/cafeteria by installing an air handling unit.
- Provide ventilation for the corridors at four first floor entryways by installing fan coil air handling units hung from the structure with outdoor air ducted to the unit from louvers in the window openings

### Electrical

- Upgrade existing service entrance for adding a new 1200A, 208/120V, 3PH, 4 wire switchboard.
- Replace the entire distribution system with new panel boards and new feeders. Provide an arc flash label on all new panel boards. Estimated, 6 panel boards.
- Replace existing lighting fixtures with new fluorescent fixtures where existing fixtures are not working. Estimated 40 each.
- Replace existing incandescent fixtures in basement and other areas with fluorescent lighting fixtures. Estimated 25 each.
- Replace gymnasium luminaires with high-bay LED fixtures. Estimated 15 each.
- Replace the existing fire alarm system with an automatic fire alarm system including smoke detectors in corridors and other areas recommended by the NEC. Install horn/strobes in classrooms, corridors, offices, toilets, library and other areas as

## Site Assessment Report - S823001;Crossan

---

recommended by electrical codes.

- Provide master clock system including wireless master clock controller and new clocks in classrooms and offices.
- Provide a new video surveillance system including cameras and Closed Circuit Television (CCTV) unit for monitoring the system. Cameras should be installed in the corridors, school entrance doors and on the walls around the building. Provide a monitor in the main office and the building engineer's office.
- Replace existing emergency diesel generator with a new 30KW diesel generator.
- Replace existing exit signs with battery pack types. Estimated 25 each
- Perform lightning protection studies to ascertain that the mechanical equipment on the roof is protected against lightning strikes.
- Provide new stage lighting and lighting controller in the Auditorium.
- Provide new sound system including a freestanding 19" rack located in the backstage area with a mixer, amplifiers, CD player, cassette player, AM-FM radio, graphic or parametric equalizer, and receivers for wireless microphones.

### Grounds

- Repave damaged sections of asphalt playground area (6,000sf)
- Repair concrete walkways (1000sf)
- Crack fill and reseal remaining sections of asphalt playground (9000sf)
- Replace steel fence over basement areaway. (60ft)
- Add handicap ramp to rear door (80ft)

### Attributes:

#### General Attributes:

Active:	Open	Bldg Lot Tm:	Lot 3 / Tm 2
Status:	Accepted by SDP	Team:	Tm 2
Site ID:	S823001		



## Site Condition Summary

The Table below shows the CI and FCI for each major system shown at the UNIFORMAT classification Level II. Note that Systems with lower FCIs require less investment than systems with higher FCIs.

### Current Investment Requirement and Condition by Uniformat Classification

UNIFORMAT Classification	RSLI%	FCI %	Current Repair
A10 - Foundations	35.00 %	0.00 %	\$0.00
A20 - Basement Construction	35.00 %	0.12 %	\$683.20
B10 - Superstructure	35.00 %	0.00 %	\$0.00
B20 - Exterior Enclosure	57.65 %	62.60 %	\$1,073,814.06
B30 - Roofing	85.00 %	0.00 %	\$0.00
C10 - Interior Construction	22.46 %	34.75 %	\$259,462.70
C20 - Stairs	40.00 %	238.52 %	\$102,333.19
C30 - Interior Finishes	53.35 %	18.79 %	\$265,788.22
D10 - Conveying	0.00 %	0.00 %	\$0.00
D20 - Plumbing	99.14 %	110.41 %	\$686,016.11
D30 - HVAC	79.10 %	123.41 %	\$4,177,278.59
D40 - Fire Protection	105.71 %	177.49 %	\$435,284.67
D50 - Electrical	103.81 %	57.71 %	\$1,032,263.16
E10 - Equipment	34.29 %	19.29 %	\$93,445.81
E20 - Furnishings	100.00 %	362.63 %	\$235,028.16
G20 - Site Improvements	89.11 %	43.43 %	\$160,078.06
G40 - Site Electrical Utilities	40.00 %	0.00 %	\$0.00
<b>Totals:</b>	<b>62.81 %</b>	<b>54.81 %</b>	<b>\$8,521,475.93</b>

### Condition Deficiency Priority

Facility Name	Gross Area (S.F.)	FCI %	1 - Response Time (< 2 yr)	2 - Response Time (2-3 yrs)	3 - Response Time (3-4 yrs)	4 - Response Time (4-5 yrs)	5 - Response Time (> 5 yrs)
B823001;Crossan	30,428	55.55	\$2,701,867.01	\$2,937,311.43	\$471,682.50	\$93,445.81	\$2,157,091.12
G823001;Grounds	21,800	32.32	\$103,927.21	\$34,245.53	\$21,905.32	\$0.00	\$0.00
<b>Total:</b>		<b>54.81</b>	<b>\$2,805,794.22</b>	<b>\$2,971,556.96</b>	<b>\$493,587.82</b>	<b>\$93,445.81</b>	<b>\$2,157,091.12</b>

### Deficiencies By Priority



- 1 - Response Time (< 2 yr) - \$2,805,794.22
- 2 - Response Time (2-3 yrs) - \$2,971,556.96
- 3 - Response Time (3-4 yrs) - \$493,587.82
- 4 - Response Time (4-5 yrs) - \$93,445.81
- 5 - Response Time (> 5 yrs) - \$2,157,091.12

**Budget Estimate Total: \$8,521,475.93**

## Executive Summary

Building condition is evaluated based on the functional systems and elements of a building and organized according to the UNIFORMAT II Elemental Classification. The grouping of these systems and elements and applying a current replacement value to them develops a representative building cost model. Cost Models are developed for similar building types and functions. Systems and their elements are evaluated based on their current replacement values, life cycles, installation dates and next renewal dates. Systems and their elements that are within their useful lives are further evaluated to identify current deficient conditions that may have a significant impact on a system's or element's remaining service life, and to determine if they are beyond their predicted expected life. The system's or element's current replacement value is based on RS Means Commercial Cost Data.

Following are the cost model's system details for this facility. The Replacement Value is the amount needed to replace the property of the same present value. The Current Repair Amount, also known as Condition Needs, represents the budgeted contractor installed costs plus owner's soft costs for the repair, replacement or renewal for a component or system level deficiency. It excludes contributing costs for other components or systems that might also be associated with the corrective actions due to packaging the work. Facility Condition Index (FCI) FCI is an industry-standard measurement of facility condition calculated as the ratio of the costs to correct a facility's deficiencies to the facility's Current Replacement Value. It ranges from 0% (new) to 100% (very poor). Condition Index (CI) is calculated as the sum of a renewable system's Remaining Service Life (RSL) divided by the sum of a system's Replacement Value (both values exclude soft-cost to simplify calculation updates) expressed as a percentage ranging from 100% (new) to 0% (expired).

Function:	Elementary School
Gross Area (SF):	30,428
Year Built:	1924
Last Renovation:	
Replacement Value:	\$15,050,924
Repair Cost:	\$8,361,397.87
Total FCI:	55.55 %
Total RSLI:	62.36 %



**Description:**

**Attributes:**

**General Attributes:**

Active:	Open	Bldg ID:	B823001
Sewage Ejector:	No	Status:	Accepted by SDP
Site ID:	S823001		

## Condition Summary

The Table below shows the CI and FCI for each major building system shown at the UNIFORMAT classification Level II. Note that Systems with lower FCIs require less investment than systems with higher FCIs.

UNIFORMAT Classification	RSLI %	FCI %	Current Repair Cost
A10 - Foundations	35.00 %	0.00 %	\$0.00
A20 - Basement Construction	35.00 %	0.12 %	\$683.20
B10 - Superstructure	35.00 %	0.00 %	\$0.00
B20 - Exterior Enclosure	57.65 %	62.60 %	\$1,073,814.06
B30 - Roofing	85.00 %	0.00 %	\$0.00
C10 - Interior Construction	22.46 %	34.75 %	\$259,462.70
C20 - Stairs	40.00 %	238.52 %	\$102,333.19
C30 - Interior Finishes	53.35 %	18.79 %	\$265,788.22
D10 - Conveying	0.00 %	0.00 %	\$0.00
D20 - Plumbing	99.14 %	110.41 %	\$686,016.11
D30 - HVAC	79.10 %	123.41 %	\$4,177,278.59
D40 - Fire Protection	105.71 %	177.49 %	\$435,284.67
D50 - Electrical	103.81 %	57.71 %	\$1,032,263.16
E10 - Equipment	34.29 %	19.29 %	\$93,445.81
E20 - Furnishings	100.00 %	362.63 %	\$235,028.16
<b>Totals:</b>	<b>62.36 %</b>	<b>55.55 %</b>	<b>\$8,361,397.87</b>

## Condition Detail

This section of the report contains results of the Facility Condition Assessment. The building is separated into system components based on UNIFORMAT II classification. The columns in the System Listing table below represent the following:

1. System Code: A code that identifies the system.
2. System Description: A brief description of a system present in the building.
3. Unit Price \$: The unit price of the system.
4. UoM: The unit of measure for of the system.
5. Qty: The quantity for the system
6. Life: anticipated service life for thesystem based on Building Owners and Managers Association (BOMA) recommendations.
7. Year Installed: The date of system installation.
8. Calc Next Renewal Year: The date of system expiration based on the life, NR stands for non renewable.
9. Next Renewal Year: The suggested system expiration date by the assessor based on visual inspection.
10. CI: The Condition Index of the system.
11. FCI: The Facility Condition Index of the system.
12. RSL: Remaining Service Life.
13. eCR: eCOMET Condition Rating (not used).
14. Deficiency \$: The financial investment to repair/replace system.



## System Listing

The System Listing table below lists each of the systems organized by their UNIFORMAT II classification. The assessment team was tasked with recording the most recent replacement year of each system, determining the remaining service life based on the theoretical life, and evaluating the condition to confirm the forecast next replacement year. The system listing is the basis for all data contained in the Building Assessment Report.

Additionally, a condition rating (eCR) based on the following guidelines is provided as observed at the time of the assessment.

- Excellent (E) - No noticeable distress or damage. The entire system is free from observable defect.
- Very Good (VG) - Overall no serviceability reduction for the entire system. No degradation of critical components and minor distress and defect noticeable for some but not non critical components within the system.
- Good (G) - Slight or no serviceability reduction for the entire system. There may be noticeable defects for some non critical components and slight noticeable degradation of the critical components.
- Fair (F) - Overall serviceability is degraded but adequate. There may be moderate deterioration for very few of the critical components and few of the non critical components may have severe degradation.
- Marginal (MA) - Overall serviceability and reliability loss. Most if not all of the non critical components suffer from severe degradation and a few of the critical component may have severe degradation.
- Moderate (MO) - Overall a significant serviceability loss. Most if not all the components have severe degradation with the reminder of the component showing visible distress.
- Very Poor (VP) - Overall the system is barely functional. All of the components are severely degraded.
- Non-Functional (NF) - Overall the system does not function with all the components having no serviceability and suffer from severe degradation.

System Code	System Description	Unit Price \$	UoM	Qty	Life	Year Installed	Calc Next Renewal Year	Next Renewal Year	RSLT%	FCI%	RSL	eCR	Deficiency \$	Replacement Value \$
A1010	Standard Foundations	\$18.40	S.F.	30,428	100	1924	2024	2050	35.00 %	0.00 %	35			\$559,875
A1030	Slab on Grade	\$7.73	S.F.	30,428	100	1924	2024	2050	35.00 %	0.00 %	35			\$235,208
A2010	Basement Excavation	\$6.55	S.F.	30,428	100	1924	2024	2050	35.00 %	0.00 %	35			\$199,303
A2020	Basement Walls	\$12.70	S.F.	30,428	100	1924	2024	2050	35.00 %	0.18 %	35		\$683.20	\$386,436
B1010	Floor Construction	\$75.10	S.F.	30,428	100	1924	2024	2050	35.00 %	0.00 %	35			\$2,285,143
B1020	Roof Construction	\$13.88	S.F.	30,428	100	1924	2024	2050	35.00 %	0.00 %	35			\$422,341
B2010	Exterior Walls	\$36.91	S.F.	30,428	100	1924	2024	2050	35.00 %	0.36 %	35		\$4,031.58	\$1,123,097
B2020	Exterior Windows	\$18.01	S.F.	30,428	40	1924	1964	2055	100.00 %	175.45 %	40		\$961,480.00	\$548,008
B2030	Exterior Doors	\$1.45	S.F.	30,428	25	1924	1949	2042	108.00 %	245.47 %	27		\$108,302.48	\$44,121
B3010105	Built-Up	\$37.76	S.F.	12,000	20	2012	2032		85.00 %	0.00 %	17			\$453,120
B3010120	Single Ply Membrane	\$38.73	S.F.		20				0.00 %	0.00 %				\$0
B3010130	Preformed Metal Roofing	\$54.22	S.F.		30				0.00 %	0.00 %				\$0
B3010140	Shingle & Tile	\$38.73	S.F.		25				0.00 %	0.00 %				\$0
B3020	Roof Openings	\$0.06	S.F.	12,000	20	2012	2032		85.00 %	0.00 %	17			\$720
C1010	Partitions	\$17.91	S.F.	30,428	100	1924	2024		9.00 %	1.33 %	9		\$7,222.31	\$544,965
C1020	Interior Doors	\$3.51	S.F.	30,428	40	1924	1964	2055	100.00 %	231.50 %	40		\$247,243.88	\$106,802
C1030	Fittings	\$3.12	S.F.	30,428	40	1924	1964	2020	12.50 %	5.26 %	5		\$4,996.51	\$94,935
C2010	Stair Construction	\$1.41	S.F.	30,428	100	1924	2024	2055	40.00 %	238.52 %	40		\$102,333.19	\$42,903

Site Assessment Report - B823001;Crossan

System Code	System Description	Unit Price \$	UoM	Qty	Life	Year Installed	Calc Next Renewal Year	Next Renewal Year	RSLI%	FCI%	RSL	eCR	Deficiency \$	Replacement Value \$
C3010230	Paint & Covering	\$13.21	S.F.	30,428	10	1924	1934	2020	50.00 %	11.34 %	5		\$45,592.96	\$401,954
C3010231	Vinyl Wall Covering	\$0.97	S.F.		15				0.00 %	0.00 %				\$0
C3010232	Wall Tile	\$2.63	S.F.		30				0.00 %	0.00 %				\$0
C3020411	Carpet	\$7.30	S.F.	800	10	2015	2025	2028	130.00 %	153.30 %	13		\$8,952.61	\$5,840
C3020412	Terrazzo & Tile	\$75.52	S.F.		50				0.00 %	0.00 %				\$0
C3020413	Vinyl Flooring	\$9.68	S.F.	4,450	20	2015	2035		100.00 %	87.88 %	20		\$37,855.22	\$43,076
C3020414	Wood Flooring	\$22.27	S.F.	14,150	25	1924	1949	2028	52.00 %	50.40 %	13		\$158,812.36	\$315,121
C3020415	Concrete Floor Finishes	\$0.97	S.F.	11,028	50	1924	1974	2050	70.00 %	136.25 %	35		\$14,575.07	\$10,697
C3030	Ceiling Finishes	\$20.97	S.F.	30,428	25	1924	1949	2028	52.00 %	0.00 %	13			\$638,075
D1010	Elevators and Lifts	\$1.53	S.F.		35				0.00 %	0.00 %				\$0
D2010	Plumbing Fixtures	\$13.52	S.F.	30,428	35	1924	1959	2052	105.71 %	84.59 %	37		\$348,004.24	\$411,387
D2020	Domestic Water Distribution	\$1.68	S.F.	30,428	25	1924	1949	2042	108.00 %	408.45 %	27		\$208,796.16	\$51,119
D2030	Sanitary Waste	\$2.90	S.F.	30,428	25	1924	1949	2042	108.00 %	146.44 %	27		\$129,215.71	\$88,241
D2040	Rain Water Drainage	\$2.32	S.F.	30,428	30	1924	1954	2028	43.33 %	0.00 %	13			\$70,593
D3020	Heat Generating Systems	\$18.67	S.F.	30,428	35	1924	1959	2028	37.14 %	22.54 %	13		\$128,072.25	\$568,091
D3030	Cooling Generating Systems	\$24.48	S.F.	30,428	30	1924	1954	2030	50.00 %	65.60 %	15		\$488,651.57	\$744,877
D3040	Distribution Systems	\$42.99	S.F.	30,428	25	1924	1949	2042	108.00 %	222.29 %	27		\$2,907,811.05	\$1,308,100
D3050	Terminal & Package Units	\$11.60	S.F.	30,428	20	1924	1944	2028	65.00 %	0.00 %	13			\$352,965
D3060	Controls & Instrumentation	\$13.50	S.F.	30,428	20	1924	1944	2037	110.00 %	158.90 %	22		\$652,743.72	\$410,778
D4010	Sprinklers	\$7.05	S.F.	30,428	35			2052	105.71 %	202.91 %	37		\$435,284.67	\$214,517
D4020	Standpipes	\$1.01	S.F.	30,428	35			2052	105.71 %	0.00 %	37			\$30,732
D5010	Electrical Service/Distribution	\$9.70	S.F.	30,428	30	1924	1954	2037	73.33 %	174.63 %	22		\$515,417.60	\$295,152
D5020	Lighting and Branch Wiring	\$34.68	S.F.	30,428	20	1924	1944	2037	110.00 %	7.81 %	22		\$82,393.82	\$1,055,243
D5030	Communications and Security	\$12.99	S.F.	30,428	15	1924	1939	2032	113.33 %	83.24 %	17		\$329,033.10	\$395,260
D5090	Other Electrical Systems	\$1.41	S.F.	30,428	30	1924	1954	2037	73.33 %	245.71 %	22		\$105,418.64	\$42,903
E1020	Institutional Equipment	\$4.82	S.F.	30,428	35	1924	1959	2027	34.29 %	63.71 %	12		\$93,445.81	\$146,663
E1090	Other Equipment	\$11.10	S.F.	30,428	35	1924	1959	2027	34.29 %	0.00 %	12			\$337,751
E2010	Fixed Furnishings	\$2.13	S.F.	30,428	40	1924	1964	2055	100.00 %	362.63 %	40		\$235,028.16	\$64,812
<b>Total</b>									<b>62.36 %</b>	<b>55.55 %</b>			<b>\$8,361,397.87</b>	<b>\$15,050,924</b>

## System Notes

The facility description in the site executive summary contains an overview of each system. The notes listed below provide additional information on select systems found within the facility.

---

**System:** C30 - Interior Finishes This system contains no images

**Note:** painted block 80%  
glazed brick 8%  
marble 8%  
wood 1%

---

**System:** C3020 - Floor Finishes This system contains no images

**Note:** Concrete - 11028 36%  
Wood - 14150 47%  
VCT - 4450 14%  
Carpet - 800 3%

---

**System:** C3030 - Ceiling Finishes This system contains no images

**Note:** Plaster - 3150 - 10%  
Acoustical Tile - 800 - 3%  
concrete painted - 26478 - 87%

## Renewal Schedule

eCOMET forecasts future Capital Renewal funding needed to address expiring systems based on the Next Renewal year found in the Cost Models. A 3% annual inflation factor is applied to the costs for systems expiring in future years. The table below reflects recommended Capital Renewal funding needs over the next 10 years. Note: Cells with a zero value indicate systems for which renewal is not scheduled in that year.

*Inflation Rate: 3%*

System	Current Deficiencies	2016	2017	2018	2019	2020	2021	2022	2023	2024	2025	Total
<b>Total:</b>	<b>\$8,361,398</b>	<b>\$0</b>	<b>\$0</b>	<b>\$0</b>	<b>\$0</b>	<b>\$633,634</b>	<b>\$0</b>	<b>\$0</b>	<b>\$0</b>	<b>\$782,162</b>	<b>\$0</b>	<b>\$9,777,194</b>
<b>* A - Substructure</b>	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
<b>A10 - Foundations</b>	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
<b>A1010 - Standard Foundations</b>	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
<b>A1030 - Slab on Grade</b>	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
<b>A20 - Basement Construction</b>	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
<b>A2010 - Basement Excavation</b>	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
<b>A2020 - Basement Walls</b>	\$683	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$683
<b>B - Shell</b>	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
<b>B10 - Superstructure</b>	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
<b>B1010 - Floor Construction</b>	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
<b>B1020 - Roof Construction</b>	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
<b>B20 - Exterior Enclosure</b>	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
<b>B2010 - Exterior Walls</b>	\$4,032	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$4,032
<b>B2020 - Exterior Windows</b>	\$961,480	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$961,480
<b>B2030 - Exterior Doors</b>	\$108,302	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$108,302
<b>B30 - Roofing</b>	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
<b>B3010 - Roof Coverings</b>	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
<b>B3010105 - Built-Up</b>	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
<b>B3010120 - Single Ply Membrane</b>	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
<b>B3010130 - Preformed Metal Roofing</b>	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
<b>B3010140 - Shingle &amp; Tile</b>	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
<b>B3020 - Roof Openings</b>	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
<b>C - Interiors</b>	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
<b>C10 - Interior Construction</b>	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
<b>C1010 - Partitions</b>	\$7,222	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$782,162	\$0	\$789,384

Site Assessment Report - B823001;Crossan

C1020 - Interior Doors	\$247,244	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$247,244
C1030 - Fittings	\$4,997	\$0	\$0	\$0	\$0	\$121,062	\$0	\$0	\$0	\$0	\$0	\$0	\$126,058
C20 - Stairs	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C2010 - Stair Construction	\$102,333	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$102,333
C30 - Interior Finishes	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C3010 - Wall Finishes	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C3010230 - Paint & Covering	\$45,593	\$0	\$0	\$0	\$0	\$512,572	\$0	\$0	\$0	\$0	\$0	\$0	\$558,165
C3010231 - Vinyl Wall Covering	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C3010232 - Wall Tile	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C3020 - Floor Finishes	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C3020411 - Carpet	\$8,953	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$8,953
C3020412 - Terrazzo & Tile	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C3020413 - Vinyl Flooring	\$37,855	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$37,855
C3020414 - Wood Flooring	\$158,812	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$158,812
C3020415 - Concrete Floor Finishes	\$14,575	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$14,575
C3030 - Ceiling Finishes	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D - Services	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D10 - Conveying	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D1010 - Elevators and Lifts	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D20 - Plumbing	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D2010 - Plumbing Fixtures	\$348,004	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$348,004
D2020 - Domestic Water Distribution	\$208,796	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$208,796
D2030 - Sanitary Waste	\$129,216	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$129,216
D2040 - Rain Water Drainage	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D30 - HVAC	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D3020 - Heat Generating Systems	\$128,072	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$128,072
D3030 - Cooling Generating Systems	\$488,652	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$488,652
D3040 - Distribution Systems	\$2,907,811	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$2,907,811
D3050 - Terminal & Package Units	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D3060 - Controls & Instrumentation	\$652,744	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$652,744
D40 - Fire Protection	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D4010 - Sprinklers	\$435,285	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$435,285
D4020 - Standpipes	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0




Site Assessment Report - B823001;Crossan

<b>D50 - Electrical</b>	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
<b>D5010 - Electrical Service/Distribution</b>	\$515,418	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$515,418
<b>D5020 - Lighting and Branch Wiring</b>	\$82,394	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$82,394
<b>D5030 - Communications and Security</b>	\$329,033	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$329,033
<b>D5090 - Other Electrical Systems</b>	\$105,419	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$105,419
<b>E - Equipment &amp; Furnishings</b>	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
<b>E10 - Equipment</b>	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
<b>E1020 - Institutional Equipment</b>	\$93,446	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$93,446
<b>E1090 - Other Equipment</b>	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
<b>E20 - Furnishings</b>	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
<b>E2010 - Fixed Furnishings</b>	\$235,028	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$235,028

\* Indicates non-renewable system

## Forecasted Sustainment Requirement

The following chart shows the current building deficiencies and forecasting sustainment requirements over the next ten years.




## 10 Year FCI Forecast by Investment Scenario

The chart below illustrates the effect of various investment levels on the building FCI for the next 10 years. The levels of investment shown below include:

- Current FCI: a variable investment amount based on renewing expired systems to maintain the current FCI for the building
- 2% Investment: an annual investment of 2% of the replacement value of the building, escalated for inflation
- 4% Investment: an annual investment of 4% of the replacement value of the building, escalated for inflation


**Facility Investment vs. FCI Forecast**



Year	Investment Amount Current FCI - 55.55%	2% Investment		4% Investment	
		Amount	FCI	Amount	FCI
2016	\$0	\$310,049.00	53.55 %	\$620,098.00	51.55 %
2017	\$4,679,044	\$319,351.00	80.86 %	\$638,701.00	76.86 %
2018	\$7,020	\$328,931.00	78.90 %	\$657,862.00	72.90 %
2019	\$0	\$338,799.00	76.90 %	\$677,598.00	68.90 %
2020	\$633,634	\$348,963.00	78.53 %	\$697,926.00	68.53 %
2021	\$0	\$359,432.00	76.53 %	\$718,864.00	64.53 %
2022	\$0	\$370,215.00	74.53 %	\$740,430.00	60.53 %
2023	\$0	\$381,321.00	72.53 %	\$762,642.00	56.53 %
2024	\$782,162	\$392,761.00	74.51 %	\$785,522.00	56.51 %
2025	\$0	\$404,544.00	72.51 %	\$809,087.00	52.51 %
<b>Total:</b>	<b>\$6,101,860</b>	<b>\$3,554,366.00</b>		<b>\$7,108,730.00</b>	

## Deficiency Summary by System


Current deficiencies included assemblies that have reached or exceeded their design life or components of the assemblies that are in need of repair. Assemblies that have reached their design life are identified as current deficiencies and assigned the distress 'Beyond Useful Life'. The following chart lists all current deficiencies associated with this facility.



**Budget Estimate Total: \$8,361,397.87**

## Deficiency Summary by Priority

The following chart shows the total repair costs broken down by priority. Assessors assigned deficiencies within eCOMET to one of the following priority categories:



**Budget Estimate Total: \$8,361,397.87**


## Deficiency By Priority Investment Table

The table below shows the current investment cost grouped by deficiency priority and building system.

System Code	System Description	1 - Response Time (< 2 yr)	2 - Response Time (2-3 yrs)	3 - Response Time (3-4 yrs)	4 - Response Time (4-5 yrs)	5 - Response Time (> 5 yrs)	Total
A2020	Basement Walls	\$0.00	\$683.20	\$0.00	\$0.00	\$0.00	\$683.20
B2010	Exterior Walls	\$802.64	\$3,228.94	\$0.00	\$0.00	\$0.00	\$4,031.58
B2020	Exterior Windows	\$0.00	\$961,480.00	\$0.00	\$0.00	\$0.00	\$961,480.00
B2030	Exterior Doors	\$0.00	\$108,302.48	\$0.00	\$0.00	\$0.00	\$108,302.48
C1010	Partitions	\$0.00	\$7,222.31	\$0.00	\$0.00	\$0.00	\$7,222.31
C1020	Interior Doors	\$0.00	\$247,243.88	\$0.00	\$0.00	\$0.00	\$247,243.88
C1030	Fittings	\$0.00	\$4,996.51	\$0.00	\$0.00	\$0.00	\$4,996.51
C2010	Stair Construction	\$101,137.59	\$1,195.60	\$0.00	\$0.00	\$0.00	\$102,333.19
C3010230	Paint & Covering	\$0.00	\$45,592.96	\$0.00	\$0.00	\$0.00	\$45,592.96
C3020411	Carpet	\$0.00	\$8,952.61	\$0.00	\$0.00	\$0.00	\$8,952.61
C3020413	Vinyl Flooring	\$0.00	\$37,855.22	\$0.00	\$0.00	\$0.00	\$37,855.22
C3020414	Wood Flooring	\$0.00	\$158,812.36	\$0.00	\$0.00	\$0.00	\$158,812.36
C3020415	Concrete Floor Finishes	\$0.00	\$14,575.07	\$0.00	\$0.00	\$0.00	\$14,575.07
D2010	Plumbing Fixtures	\$0.00	\$348,004.24	\$0.00	\$0.00	\$0.00	\$348,004.24
D2020	Domestic Water Distribution	\$0.00	\$0.00	\$54,606.72	\$0.00	\$154,189.44	\$208,796.16
D2030	Sanitary Waste	\$0.00	\$0.00	\$129,215.71	\$0.00	\$0.00	\$129,215.71
D3020	Heat Generating Systems	\$0.00	\$101,394.17	\$0.00	\$0.00	\$26,678.08	\$128,072.25
D3030	Cooling Generating Systems	\$0.00	\$0.00	\$0.00	\$0.00	\$488,651.57	\$488,651.57
D3040	Distribution Systems	\$1,567,663.62	\$0.00	\$287,860.07	\$0.00	\$1,052,287.36	\$2,907,811.05
D3060	Controls & Instrumentation	\$0.00	\$652,743.72	\$0.00	\$0.00	\$0.00	\$652,743.72
D4010	Sprinklers	\$0.00	\$0.00	\$0.00	\$0.00	\$435,284.67	\$435,284.67
D5010	Electrical Service/Distribution	\$515,417.60	\$0.00	\$0.00	\$0.00	\$0.00	\$515,417.60
D5020	Lighting and Branch Wiring	\$82,393.82	\$0.00	\$0.00	\$0.00	\$0.00	\$82,393.82
D5030	Communications and Security	\$329,033.10	\$0.00	\$0.00	\$0.00	\$0.00	\$329,033.10
D5090	Other Electrical Systems	\$105,418.64	\$0.00	\$0.00	\$0.00	\$0.00	\$105,418.64
E1020	Institutional Equipment	\$0.00	\$0.00	\$0.00	\$93,445.81	\$0.00	\$93,445.81
E2010	Fixed Furnishings	\$0.00	\$235,028.16	\$0.00	\$0.00	\$0.00	\$235,028.16
	<b>Total:</b>	\$2,701,867.01	\$2,937,311.43	\$471,682.50	\$93,445.81	\$2,157,091.12	\$8,361,397.87

## Deficiency Summary by Category

The following chart shows the total repair costs broken down by deficiency categories. Assessors assigned deficiencies to one of the following categories:



**Budget Estimate Total: \$8,361,397.87**



## Deficiency Details by Priority

The deficiency detail notes listed below provide additional information on identified deficiencies found within the facility.

### Priority 1 - Response Time (< 2 yr):

#### System: B2010 - Exterior Walls



**Location:** exterior walkway along auditorium

**Distress:** Failing

**Category:** 3 - Operations / Maint.

**Priority:** 1 - Response Time (< 2 yr)

**Correction:** Re-caulk exterior control joints and other caulk joints

**Qty:** 40.00

**Unit of Measure:** L.F.

**Estimate:** \$802.64

**Assessor Name:** System

**Date Created:** 01/04/2016

**Notes:** Seal gap between walkway into door near auditorium and auditorium exterior walls (40 ft)

#### System: C2010 - Stair Construction



**Location:** stairways

**Distress:** Building / MEP Codes

**Category:** 2 - Code Compliance

**Priority:** 1 - Response Time (< 2 yr)

**Correction:** Replace inadequate or install proper stair railing - select appropriate material

**Qty:** 300.00

**Unit of Measure:** L.F.

**Estimate:** \$101,137.59

**Assessor Name:** System

**Date Created:** 01/04/2016

**Notes:** Remove and replace stairway handrails and guards with code compliant systems (2) 3 story;=50x6=300 ft of handrail+guard

**System: D3040 - Distribution Systems**

This deficiency has no image.

**Location:** Throughout the building

**Distress:** Beyond Service Life

**Category:** 3 - Operations / Maint.

**Priority:** 1 - Response Time (< 2 yr)

**Correction:** Replace the existing unit ventilators with new units designed to provide adequate ventilation per ASHRAE Std 62 - insert the SF of bldg. in the qty.

**Qty:** 30,428.00

**Unit of Measure:** S.F.

**Estimate:** \$1,467,825.89

**Assessor Name:** System

**Date Created:** 02/06/2016

**Notes:** Install unit ventilators throughout the building designed to provide adequate ventilation per ASHRAE Std 62. The new units shall be equipped with hot water / chilled water coils and integral heat exchangers.

---

**System: D3040 - Distribution Systems**



**Location:** Throughout the building

**Distress:** Beyond Service Life

**Category:** 3 - Operations / Maint.

**Priority:** 1 - Response Time (< 2 yr)

**Correction:** Conduct a steam trap survey and replace failed units.

**Qty:** 30,428.00

**Unit of Measure:** S.F.

**Estimate:** \$99,837.73

**Assessor Name:** System

**Date Created:** 02/06/2016

**Notes:** Conduct a steam trap survey to identify and replace failed traps passing live steam into the condensate piping system.

---

**System: D5010 - Electrical Service/Distribution**



**Location:** Electrical Room  
**Distress:** Inadequate  
**Category:** 4 - Capital Improvement  
**Priority:** 1 - Response Time (< 2 yr)  
**Correction:** Replace Switchboard  
**Qty:** 1.00

**Unit of Measure:** Ea.  
**Estimate:** \$369,558.37  
**Assessor Name:** System  
**Date Created:** 10/19/2015

**Notes:** Upgrade existing service entrance for adding a new 1200A, 208/120V, 3PH, 4 wire switchboard.

---

**System: D5010 - Electrical Service/Distribution**



**Location:** Entire Building  
**Distress:** Beyond Service Life  
**Category:** 3 - Operations / Maint.  
**Priority:** 1 - Response Time (< 2 yr)  
**Correction:** Replace Electrical Distribution System (U)  
**Qty:** 1.00

**Unit of Measure:** Ea.  
**Estimate:** \$145,859.23  
**Assessor Name:** System  
**Date Created:** 10/19/2015

**Notes:** Replace the entire distribution system with new panel boards and new feeders. Provide arc flash label on the all panel boards. Estimated, 6 panel boards.

---

**System: D5020 - Lighting and Branch Wiring**



**Location:** Entire Building  
**Distress:** Beyond Service Life  
**Category:** 3 - Operations / Maint.  
**Priority:** 1 - Response Time (< 2 yr)  
**Correction:** Replace lighting fixtures  
**Qty:** 1.00  
**Unit of Measure:** Ea.  
**Estimate:** \$62,852.11  
**Assessor Name:** System  
**Date Created:** 10/19/2015

**Notes:** Replace existing lighting fixtures with new fluorescent fixtures where needed. Estimated 40 each. Replace existing incandescent fixtures in basement and other area with fluorescent lighting fixtures. Estimated 25 each. Replace gymnasium illuminates with LED high bay . Estimated 15 each.

---

**System: D5020 - Lighting and Branch Wiring**



**Location:** Entire Building  
**Distress:** Inadequate  
**Category:** 4 - Capital Improvement  
**Priority:** 1 - Response Time (< 2 yr)  
**Correction:** Replace lighting fixtures  
**Qty:** 1.00  
**Unit of Measure:** Ea.  
**Estimate:** \$19,541.71  
**Assessor Name:** System  
**Date Created:** 10/19/2015

**Notes:** Replace existing exit signs with battery pack types. Estimated 25 each

---

**System: D5030 - Communications and Security**



**Location:** Entire Building  
**Distress:** Beyond Service Life  
**Category:** 3 - Operations / Maint.  
**Priority:** 1 - Response Time (< 2 yr)  
**Correction:** Replace fire alarm system  
**Qty:** 1.00  
**Unit of Measure:** S.F.  
**Estimate:** \$170,192.75  
**Assessor Name:** System  
**Date Created:** 10/19/2015

**Notes:** Replace existing fire alarm system with an automatic fire alarm system including smoke detectors in corridors and other recommended areas per NEC. Install horn/strobes in class rooms, corridors, offices, toilets, library and other recommended areas per codes.

---

**System: D5030 - Communications and Security**



**Location:** Entire Building  
**Distress:** Security Issue  
**Category:** 1 - Health & Safety  
**Priority:** 1 - Response Time (< 2 yr)  
**Correction:** Add/Replace Video Surveillance System  
**Qty:** 1.00  
**Unit of Measure:** Ea.  
**Estimate:** \$97,759.65  
**Assessor Name:** System  
**Date Created:** 10/19/2015

**Notes:** Provide an adequate video surveillance system including camera and Closed Circuit Television (CCTV) for monitoring the system. Cameras should install in the corridors, school entrance doors and on the walls around the building. Provide monitor in main office and building engineer office.

---



**System: D5030 - Communications and Security**



**Location:** Auditorium  
**Distress:** Beyond Service Life  
**Category:** 3 - Operations / Maint.  
**Priority:** 1 - Response Time (< 2 yr)  
**Correction:** Add/Replace Sound System  
**Qty:** 1.00  
**Unit of Measure:** LS  
**Estimate:** \$38,400.80  
**Assessor Name:** System  
**Date Created:** 10/19/2015

**Notes:** Provide new sound system including a freestanding 19" rack backstage area with a mixer, amplifiers, CD player, cassette player, AM-FM radio, graphic or parametric equalizer, and receivers.

---

**System: D5030 - Communications and Security**



**Location:** Entire Building  
**Distress:** Inadequate  
**Category:** 4 - Capital Improvement  
**Priority:** 1 - Response Time (< 2 yr)  
**Correction:** Add/Replace Clock System or Components  
**Qty:** 1.00  
**Unit of Measure:** Ea.  
**Estimate:** \$22,679.90  
**Assessor Name:** System  
**Date Created:** 10/19/2015

**Notes:** Provide master clock system including wireless master clock controller and new clock in the classes and offices.

---

**System: D5090 - Other Electrical Systems**



**Location:** Boiler Room  
**Distress:** Beyond Service Life  
**Category:** 3 - Operations / Maint.  
**Priority:** 1 - Response Time (< 2 yr)  
**Correction:** Replace standby generator system  
**Qty:** 1.00  
**Unit of Measure:** Ea.  
**Estimate:** \$77,696.29  
**Assessor Name:** System  
**Date Created:** 10/19/2015

**Notes:** Replace existing emergency diesel generator with new 30KW diesel generator.

---

**System: D5090 - Other Electrical Systems**



**Location:** Roof  
**Distress:** Life Safety / NFPA / PFD  
**Category:** 1 - Health & Safety  
**Priority:** 1 - Response Time (< 2 yr)  
**Correction:** Provide Lightning Protection System  
**Qty:** 1.00  
**Unit of Measure:** LS  
**Estimate:** \$27,722.35  
**Assessor Name:** System  
**Date Created:** 10/19/2015

**Notes:** Perform lightning protection studies to ascertain that the mechanical equipment on the roof are protected against the lightning strokes.

---



**Priority 2 - Response Time (2-3 yrs):**

**System: A2020 - Basement Walls**



**Location:** basement walls

**Distress:** Failing

**Category:** 3 - Operations / Maint.

**Priority:** 2 - Response Time (2-3 yrs)

**Correction:** Repair cracks in foundation walls - pick the appropriate repair and insert the LF

**Qty:** 60.00

**Unit of Measure:** L.F.

**Estimate:** \$683.20

**Assessor Name:** System

**Date Created:** 01/04/2016

**Notes:** Repair vertical and horizontal cracks in mechanical room foundation, slab above over window, and along edge of front stair support slab (60 ft)

---

**System: B2010 - Exterior Walls**



**Location:** chimney

**Distress:** Failing

**Category:** 3 - Operations / Maint.

**Priority:** 2 - Response Time (2-3 yrs)

**Correction:** Repair cracks in masonry - replace missing mortar and repoint - SF of wall area

**Qty:** 100.00

**Unit of Measure:** S.F.

**Estimate:** \$3,228.94

**Assessor Name:** System

**Date Created:** 01/04/2016

**Notes:** Repoint chimney (100sf)

---

**System: B2020 - Exterior Windows**



**Location:** exterior windows

**Distress:** Failing

**Category:** 3 - Operations / Maint.

**Priority:** 2 - Response Time (2-3 yrs)

**Correction:** Remove and replace aluminum windows - pick the appropriate size and style and insert the number of units

**Qty:** 160.00

**Unit of Measure:** Ea.

**Estimate:** \$961,480.00

**Assessor Name:** System

**Date Created:** 01/04/2016

**Notes:** Replace all exterior windows with insulated single hung units (160)3.5x8

---

**System: B2030 - Exterior Doors**



**Location:** exterior doors

**Distress:** Failing

**Category:** 3 - Operations / Maint.

**Priority:** 2 - Response Time (2-3 yrs)

**Correction:** Remove and replace exterior doors - per leaf

**Qty:** 14.00

**Unit of Measure:** Ea.

**Estimate:** \$108,302.48

**Assessor Name:** System

**Date Created:** 01/04/2016

**Notes:** Replace all exterior doors with ADA and code compliant exit hardware; repaint doors and frames.(14)3x7

---

**System: C1010 - Partitions**



**Location:** corridor walls

**Distress:** Building / MEP Codes

**Category:** 2 - Code Compliance

**Priority:** 2 - Response Time (2-3 yrs)

**Correction:** Remove non-rated interior glass panels and replace with studs, gypsum board, paint (E) wall

**Qty:** 270.00

**Unit of Measure:** S.F.

**Estimate:** \$7,222.31

**Assessor Name:** System

**Date Created:** 01/04/2016

**Notes:** Remove non-rated glass panels between classrooms and corridors; fill with fire rated glazing (15 @ 18sf)

---

**System: C1020 - Interior Doors**



**Location:** interior doors

**Distress:** Building / MEP Codes

**Category:** 2 - Code Compliance

**Priority:** 2 - Response Time (2-3 yrs)

**Correction:** Remove and replace interior doors - wood doors with wood frame - per leaf

**Qty:** 50.00

**Unit of Measure:** Ea.

**Estimate:** \$232,716.95

**Assessor Name:** System

**Date Created:** 01/04/2016

**Notes:** Remove and replace all wood interior doors, frames and hardware in classrooms with fire rated doors to corridors and non-rated doors to closets, offices, etc. (50)

---

**System: C1020 - Interior Doors**



**Location:** lobby and auditorium

**Distress:** Appearance

**Category:** 3 - Operations / Maint.

**Priority:** 2 - Response Time (2-3 yrs)

**Correction:** Refinish interior doors

**Qty:** 12.00

**Unit of Measure:** Ea.

**Estimate:** \$9,938.20

**Assessor Name:** System

**Date Created:** 01/04/2016

**Notes:** Refinish first floor lobby, auditorium, and office doors opening to corridor, replacing glazing with fire rated glazing (12 door panels)

---

**System: C1020 - Interior Doors**



**Location:** corridor doors

**Distress:** Security Issue

**Category:** 1 - Health & Safety

**Priority:** 2 - Response Time (2-3 yrs)

**Correction:** Provide security hardware for classroom and office doors

**Qty:** 20.00

**Unit of Measure:** Ea.

**Estimate:** \$4,588.73

**Assessor Name:** System

**Date Created:** 01/04/2016

**Notes:** Provide security hardware for classrooms and offices, locking from inside classroom. (20)

---

**System: C1030 - Fittings**



**Location:** toilet room

**Distress:** Building / MEP Codes

**Category:** 2 - Code Compliance

**Priority:** 2 - Response Time (2-3 yrs)

**Correction:** Remove and replace toilet partitions

**Qty:** 1.00

**Unit of Measure:** Ea.

**Estimate:** \$2,566.40

**Assessor Name:** System

**Date Created:** 01/04/2016

**Notes:** Provide handicap accessible toilet room accessories and new partitions for 1 toilet room (2nd fl) (2 water closets, 1 lavatory)

---

**System: C1030 - Fittings**



**Location:** toilet room

**Distress:** Building / MEP Codes

**Category:** 2 - Code Compliance

**Priority:** 2 - Response Time (2-3 yrs)

**Correction:** Replace toilet accessories - select accessories and quantity

**Qty:** 2.00

**Unit of Measure:** Ea.

**Estimate:** \$2,430.11

**Assessor Name:** System

**Date Created:** 01/04/2016

**Notes:** Provide handicap accessible toilet room accessories and new partitions for 1 toilet room (2nd fl) (2 water closets, 1 lavatory)

---



**System: C2010 - Stair Construction**



**Location:** exterior stairs

**Distress:** Failing

**Category:** 3 - Operations / Maint.

**Priority:** 2 - Response Time (2-3 yrs)

**Correction:** RegROUT joints between stone treads and risers  
- LF of grout

**Qty:** 80.00

**Unit of Measure:** L.F.

**Estimate:** \$1,195.60

**Assessor Name:** System

**Date Created:** 01/04/2016

**Notes:** RegROUT cracking joints between limestone block tread/risers at exterior stairs (10 treads)

---

**System: C3010230 - Paint & Covering**



**Location:** mechanical rooms

**Distress:** Appearance

**Category:** 3 - Operations / Maint.

**Priority:** 2 - Response Time (2-3 yrs)

**Correction:** Repair substrate and repaint interior concrete  
or CMU walls - SF of wall surface

**Qty:** 5,000.00

**Unit of Measure:** S.F.

**Estimate:** \$37,510.01

**Assessor Name:** System

**Date Created:** 01/04/2016

**Notes:** Strip and repaint concrete foundation (basement) walls in mechanical rooms (5,000sf)

---

**System: C3010230 - Paint & Covering**



**Location:** auditorium, gymateria, corridors

**Distress:** Appearance

**Category:** 3 - Operations / Maint.

**Priority:** 2 - Response Time (2-3 yrs)

**Correction:** Repair substrate and repaint interior walls - SF of wall surface

**Qty:** 1,000.00

**Unit of Measure:** S.F.

**Estimate:** \$8,082.95

**Assessor Name:** System

**Date Created:** 01/04/2016

**Notes:** Repair water damage, cracks, and repaint all damaged interior plaster walls and ceilings in auditorium, gymateria and corridors (1,000sf)

---

**System: C3020411 - Carpet**



**Location:** IMC

**Distress:** Failing

**Category:** 3 - Operations / Maint.

**Priority:** 2 - Response Time (2-3 yrs)

**Correction:** Remove and replace carpet

**Qty:** 800.00

**Unit of Measure:** S.F.

**Estimate:** \$8,952.61

**Assessor Name:** System

**Date Created:** 01/04/2016

**Notes:** Replace carpet in IMC and other rooms (800sf)

---



**System: C3020413 - Vinyl Flooring**



**Location:** gymateria  
**Distress:** Failing  
**Category:** 3 - Operations / Maint.  
**Priority:** 2 - Response Time (2-3 yrs)  
**Correction:** Remove and replace VCT  
**Qty:** 3,150.00  
**Unit of Measure:** S.F.  
**Estimate:** \$37,855.22  
**Assessor Name:** System  
**Date Created:** 01/04/2016

**Notes:** Remove and replace all 12"x12" VCT floors in gymateria (3150sf)

---

**System: C3020414 - Wood Flooring**



**Location:** classrooms  
**Distress:** Appearance  
**Category:** 3 - Operations / Maint.  
**Priority:** 2 - Response Time (2-3 yrs)  
**Correction:** Refinish wood floors  
**Qty:** 14,150.00  
**Unit of Measure:** S.F.  
**Estimate:** \$152,352.20  
**Assessor Name:** System  
**Date Created:** 01/04/2016

**Notes:** Strip, sand, repair and refinish all wood floors in classrooms and in auditorium (14,150sf)

---

**System: C3020414 - Wood Flooring**



**Location:** auditorium wainscot on wall

**Distress:** Appearance

**Category:** 3 - Operations / Maint.

**Priority:** 2 - Response Time (2-3 yrs)

**Correction:** Refinish wood floors

**Qty:** 600.00

**Unit of Measure:** S.F.

**Estimate:** \$6,460.16

**Assessor Name:** System

**Date Created:** 01/04/2016

**Notes:** Refinish wood wainscot in auditorium (600sf)

---

**System: C3020415 - Concrete Floor Finishes**



**Location:** mechanical rooms

**Distress:** Appearance

**Category:** 3 - Operations / Maint.

**Priority:** 2 - Response Time (2-3 yrs)

**Correction:** Clean and reseal concrete floors

**Qty:** 5,000.00

**Unit of Measure:** S.F.

**Estimate:** \$14,575.07

**Assessor Name:** System

**Date Created:** 01/04/2016

**Notes:** Clean and repaint basement floor in mechanical rooms (5000sf)

---

**System: D2010 - Plumbing Fixtures**



**Location:** Throughout the building

**Distress:** Beyond Service Life

**Category:** 3 - Operations / Maint.

**Priority:** 2 - Response Time (2-3 yrs)

**Correction:** Remove and replace or replace water closet - quantify additional units

**Qty:** 24.00

**Unit of Measure:** Ea.

**Estimate:** \$179,091.55

**Assessor Name:** System

**Date Created:** 02/06/2016

**Notes:** Replace all water closets in the building with lower flow fixtures, as the fixtures are original

---

**System: D2010 - Plumbing Fixtures**



**Location:** Throughout the building

**Distress:** Beyond Service Life

**Category:** 3 - Operations / Maint.

**Priority:** 2 - Response Time (2-3 yrs)

**Correction:** Remove and replace water fountains to meet ADA - includes high and low fountains and new recessed alcove

**Qty:** 4.00

**Unit of Measure:** Ea.

**Estimate:** \$62,771.59

**Assessor Name:** System

**Date Created:** 02/06/2016

**Notes:** Replace the wall hung drinking fountains and integral refrigerated coolers in the corridors and at the restrooms. These units are well beyond their service life and most are NOT accessible type.

---

**System: D2010 - Plumbing Fixtures**



**Location:** Throughout the building

**Distress:** Beyond Service Life

**Category:** 3 - Operations / Maint.

**Priority:** 2 - Response Time (2-3 yrs)

**Correction:** Remove and replace or replace wall hung urinals

**Qty:** 11.00

**Unit of Measure:** Ea.

**Estimate:** \$40,766.60

**Assessor Name:** System

**Date Created:** 02/06/2016

**Notes:** Replace all urinals in the building with lower flow fixtures, as the fixtures are original.

---

**System: D2010 - Plumbing Fixtures**



**Location:** Throughout the building

**Distress:** Beyond Service Life

**Category:** 3 - Operations / Maint.

**Priority:** 2 - Response Time (2-3 yrs)

**Correction:** Remove and replace or replace lavatory - quantify accessible if required

**Qty:** 10.00

**Unit of Measure:** Ea.

**Estimate:** \$38,110.13

**Assessor Name:** System

**Date Created:** 02/06/2016

**Notes:** Replace all lavatories in the building with lower flow fixtures, as the fixtures are original

---

**System: D2010 - Plumbing Fixtures**



**Location:** Throughout the building

**Distress:** Beyond Service Life

**Category:** 3 - Operations / Maint.

**Priority:** 2 - Response Time (2-3 yrs)

**Correction:** Remove and replace floor janitor or mop sink - insert the quantity

**Qty:** 4.00

**Unit of Measure:** Ea.

**Estimate:** \$27,264.37

**Assessor Name:** System

**Date Created:** 02/06/2016

**Notes:** Replace service sinks (janitor sinks) in the building.

---

**System: D3020 - Heat Generating Systems**



**Location:** Main boiler mechanical equipment room

**Distress:** Beyond Service Life

**Category:** 3 - Operations / Maint.

**Priority:** 2 - Response Time (2-3 yrs)

**Correction:** Replace boiler feed pump (duplex) and surge tank

**Qty:** 1.00

**Unit of Measure:** Ea.

**Estimate:** \$101,394.17

**Assessor Name:** System

**Date Created:** 02/06/2016

**Notes:** Replace boiler feedwater system.

---



**System: D3060 - Controls & Instrumentation**



**Location:** Throughout the building

**Distress:** Beyond Service Life

**Category:** 3 - Operations / Maint.

**Priority:** 2 - Response Time (2-3 yrs)

**Correction:** Replace pneumatic controls with DDC (75KSF)

**Qty:** 30,428.00

**Unit of Measure:** S.F.

**Estimate:** \$652,743.72

**Assessor Name:** System

**Date Created:** 02/06/2016

**Notes:** Replace the pneumatic controls for the HVAC systems with modern DDC modules, valves and actuators to improve reliability and energy efficiency. Provide a new building automation system (BAS) with communication interface to the preferred system in use throughout the District.

---

**System: E2010 - Fixed Furnishings**



**Location:** auditorium

**Distress:** Failing

**Category:** 3 - Operations / Maint.

**Priority:** 2 - Response Time (2-3 yrs)

**Correction:** Replace auditorium seating - add tablet arms if required. Veneer seating is an option.

**Qty:** 500.00

**Unit of Measure:** Ea.

**Estimate:** \$235,028.16

**Assessor Name:** System

**Date Created:** 01/04/2016

**Notes:** Repair or replace damaged folding wood auditorium chairs (500)

---

**Priority 3 - Response Time (3-4 yrs):**

**System: D2020 - Domestic Water Distribution**



**Location:** Main boiler mechanical equipment room

**Distress:** Beyond Service Life

**Category:** 3 - Operations / Maint.

**Priority:** 3 - Response Time (3-4 yrs)

**Correction:** Replace vertical tank type gas-fired water heater (75 gal)

**Qty:** 1.00

**Unit of Measure:** Ea.

**Estimate:** \$54,606.72

**Assessor Name:** System

**Date Created:** 02/06/2016

**Notes:** Replace natural gas fired vertical tank water heater.

---

**System: D2030 - Sanitary Waste**



**Location:** Throughout the building

**Distress:** Beyond Service Life

**Category:** 3 - Operations / Maint.

**Priority:** 3 - Response Time (3-4 yrs)

**Correction:** Inspect sanitary waste piping and replace damaged sections. (+100KSF)

**Qty:** 30,428.00

**Unit of Measure:** S.F.

**Estimate:** \$129,215.71

**Assessor Name:** System

**Date Created:** 02/06/2016

**Notes:** Hire a qualified contractor to perform a detailed examination of the sanitary waste piping using visual inspection and video cameras to locate and replace any damaged piping and to further quantify the extent of potential failures

---



**System: D3040 - Distribution Systems**



**Location:** Throughout the building

**Distress:** Beyond Service Life

**Category:** 3 - Operations / Maint.

**Priority:** 3 - Response Time (3-4 yrs)

**Correction:** Perform testing to identify and replace damaged steam and condensate piping.

**Qty:** 30,428.00

**Unit of Measure:** S.F.

**Estimate:** \$287,860.07

**Assessor Name:** System

**Date Created:** 02/06/2016

**Notes:** Hire a qualified contractor to examine the steam and condensate piping in service for 92 years and perform additional testing to locate and replace any damaged piping and to further quantify the extent of potential failures. The District should budget for replacing this piping over the next 10 years.

---

**Priority 4 - Response Time (4-5 yrs):**

**System: E1020 - Institutional Equipment**



**Location:** auditorium

**Distress:** Inadequate

**Category:** 4 - Capital Improvement

**Priority:** 4 - Response Time (4-5 yrs)

**Correction:** Add/Replace Stage Theatrical Lighting System

**Qty:** 1.00

**Unit of Measure:** Ea.

**Estimate:** \$93,445.81

**Assessor Name:** System

**Date Created:** 10/19/2015

**Notes:** Provide new stage lighting and lighting controller in the Auditorium.

---

**Priority 5 - Response Time (> 5 yrs):**

**System: D2020 - Domestic Water Distribution**



**Location:** Throughout the building

**Distress:** Beyond Service Life

**Category:** 3 - Operations / Maint.

**Priority:** 5 - Response Time (> 5 yrs)

**Correction:** Replace domestic water piping (75 KSF)

**Qty:** 30,428.00

**Unit of Measure:** S.F.

**Estimate:** \$154,189.44

**Assessor Name:** System

**Date Created:** 02/06/2016

**Notes:** Inspect and replace the original as needed the domestic water piping in the building

---

**System: D3020 - Heat Generating Systems**

This deficiency has no image.

**Location:** Main boiler mechanical equipment room

**Distress:** Beyond Service Life

**Category:** 3 - Operations / Maint.

**Priority:** 5 - Response Time (> 5 yrs)

**Correction:** Replace fuel oil pumps

**Qty:** 1.00

**Unit of Measure:** Ea.

**Estimate:** \$26,678.08

**Assessor Name:** System

**Date Created:** 02/06/2016

**Notes:** Replace duplex fuel oil pumps.

---

**System: D3030 - Cooling Generating Systems**



**Location:** Adjacent to building

**Distress:** Inadequate

**Category:** 4 - Capital Improvement

**Priority:** 5 - Response Time (> 5 yrs)

**Correction:** Install chilled water system with distribution piping and pumps. (+75KSF)

**Qty:** 30,428.00

**Unit of Measure:** S.F.

**Estimate:** \$488,651.57


**Assessor Name:** System

**Date Created:** 02/06/2016

**Notes:** Remove the window air conditioning units and install a 250 ton air-cooled chiller on the roof with chilled water distribution piping and pumps located in a mechanical room on the basement level to supply more reliable air conditioning for the building with a much longer service life.

---

**System: D3040 - Distribution Systems**



**Location:** Cafeteria

**Distress:** Beyond Service Life

**Category:** 3 - Operations / Maint.

**Priority:** 5 - Response Time (> 5 yrs)

**Correction:** Install HVAC unit for Cafeteria (850 students).

**Qty:** 850.00

**Unit of Measure:** Student

**Estimate:** \$434,958.00

**Assessor Name:** System

**Date Created:** 02/06/2016

**Notes:** Provide ventilation, heating and cooling for the gymnasium/cafeteria by installing an air handling unit.

---

**System: D3040 - Distribution Systems**



**Location:** Throughout the building

**Distress:** Beyond Service Life

**Category:** 3 - Operations / Maint.

**Priority:** 5 - Response Time (> 5 yrs)

**Correction:** Provide classroom FC units and dedicated OA ventilation system. (20 clsrms)

**Qty:** 4.00

**Unit of Measure:** C

**Estimate:** \$332,243.95

**Assessor Name:** System

**Date Created:** 02/06/2016

**Notes:** Provide ventilation for the corridors at four first floor entryways by installing fan coil air handling units hung from the structure with outdoor air ducted to the unit from louvers in the window openings

---

**System: D3040 - Distribution Systems**



**Location:** Auditorium

**Distress:** Beyond Service Life

**Category:** 3 - Operations / Maint.

**Priority:** 5 - Response Time (> 5 yrs)

**Correction:** Install HVAC unit for Auditorium (200 seat).

**Qty:** 200.00

**Unit of Measure:** Seat

**Estimate:** \$285,085.41

**Assessor Name:** System

**Date Created:** 02/06/2016

**Notes:** Provide ventilation, heating and cooling for the auditorium by installing an air handling unit.

---

**System: D4010 - Sprinklers**



**Location:** Throughout the building

**Distress:** Life Safety / NFPA / PFD

**Category:** 2 - Code Compliance

**Priority:** 5 - Response Time (> 5 yrs)

**Correction:** Install a fire protection sprinkler system

**Qty:** 30,428.00

**Unit of Measure:** S.F.

**Estimate:** \$435,284.67

**Assessor Name:** System

**Date Created:** 02/06/2016

**Notes:** Install a fire protection sprinkler system with quick response type heads to reduce insurance costs by providing protection for the property. A fire pump may be required depending on the available city water pressure. Install a new sprinkler system throughout the building

---

## Equipment Inventory

The following table represents the inventory details of the inventory found in the building, which fall under the following subsystems:

Subsystem	Inventory	Qty	UoM	Location	Manufacturer	Model Number	Serial Number	Barcode	Life	Install Date	Next Renewal	Raw Cost	Inventory Cost
D3020 Heat Generating Systems	Boiler, cast iron, gas & oil, steam, 3270 MBH	2.00	Ea.	Main boiler mechnaical equipment room	Weil McLain	1394			35			\$106,126.00	\$233,477.20
D3020 Heat Generating Systems	Boiler, cast iron, gas & oil, steam, 3270 MBH	2.00	Ea.	Main boiler mechnaical equipment room	Weil McLain	1394			35			\$106,126.00	\$233,477.20
D5010 Electrical Service/Distribution	Switchboards, split bus, 60 - 200 amp	2.00	Ea.	Electrical Room					30	1924	2017	\$428.49	\$942.68
												<b>Total:</b>	<b>\$467,897.08</b>



## Executive Summary

Building condition is evaluated based on the functional systems and elements of a building and organized according to the UNIFORMAT II Elemental Classification. The grouping of these systems and elements and applying a current replacement value to them develops a representative building cost model. Cost Models are developed for similar building types and functions. Systems and their elements are evaluated based on their current replacement values, life cycles, installation dates and next renewal dates. Systems and their elements that are within their useful lives are further evaluated to identify current deficient conditions that may have a significant impact on a system's or element's remaining service life, and to determine if they are beyond their predicted expected life. The system's or element's current replacement value is based on RS Means Commercial Cost Data.

Following are the cost model's system details for this facility. The Replacement Value is the amount needed to replace the property of the same present value. The Current Repair Amount, also known as Condition Needs, represents the budgeted contractor installed costs plus owner's soft costs for the repair, replacement or renewal for a component or system level deficiency. It excludes contributing costs for other components or systems that might also be associated with the corrective actions due to packaging the work. Facility Condition Index (FCI) FCI is an industry-standard measurement of facility condition calculated as the ratio of the costs to correct a facility's deficiencies to the facility's Current Replacement Value. It ranges from 0% (new) to 100% (very poor). Condition Index (CI) is calculated as the sum of a renewable system's Remaining Service Life (RSL) divided by the sum of a system's Replacement Value (both values exclude soft-cost to simplify calculation updates) expressed as a percentage ranging from 100% (new) to 0% (expired).

Function:

Gross Area (SF):	21,800
Year Built:	1924
Last Renovation:	
Replacement Value:	\$495,262
Repair Cost:	\$160,078.06
Total FCI:	32.32 %
Total RSLI:	76.55 %

### Description:

### Attributes:

#### General Attributes:

Bldg ID:	S823001	Site ID:	S823001
----------	---------	----------	---------

## Condition Summary

The Table below shows the CI and FCI for each major building system shown at the UNIFORMAT classification Level II. Note that Systems with lower FCIs require less investment than systems with higher FCIs.

UNIFORMAT Classification	RSLI %	FCI %	Current Repair Cost
G20 - Site Improvements	89.11 %	43.43 %	\$160,078.06
G40 - Site Electrical Utilities	40.00 %	0.00 %	\$0.00
<b>Totals:</b>	<b>76.55 %</b>	<b>32.32 %</b>	<b>\$160,078.06</b>

## Condition Detail

This section of the report contains results of the Facility Condition Assessment. The building is separated into system components based on UNIFORMAT II classification. The columns in the System Listing table below represent the following:

1. System Code: A code that identifies the system.
2. System Description: A brief description of a system present in the building.
3. Unit Price \$: The unit price of the system.
4. UoM: The unit of measure for of the system.
5. Qty: The quantity for the system
6. Life: anticipated service life for the system based on Building Owners and Managers Association (BOMA) recommendations.
7. Year Installed: The date of system installation.
8. Calc Next Renewal Year: The date of system expiration based on the life, NR stands for non renewable.
9. Next Renewal Year: The suggested system expiration date by the assessor based on visual inspection.
10. CI: The Condition Index of the system.
11. FCI: The Facility Condition Index of the system.
12. RSL: Remaining Service Life.
13. eCR: eCOMET Condition Rating (not used).
14. Deficiency \$: The financial investment to repair/replace system.

## System Listing

The System Listing table below lists each of the systems organized by their UNIFORMAT II classification. The assessment team was tasked with recording the most recent replacement year of each system, determining the remaining service life based on the theoretical life, and evaluating the condition to confirm the forecast next replacement year. The system listing is the basis for all data contained in the Building Assessment Report.

Additionally, a condition rating (eCR) based on the following guidelines is provided as observed at the time of the assessment.

- Excellent (E) - No noticeable distress or damage. The entire system is free from observable defect.
- Very Good (VG) - Overall no serviceability reduction for the entire system. No degradation of critical components and minor distress and defect noticeable for some but not non critical components within the system.
- Good (G) - Slight or no serviceability reduction for the entire system. There may be noticeable defects for some non critical components and slight noticeable degradation of the critical components.
- Fair (F) - Overall serviceability is degraded but adequate. There may be moderate deterioration for very few of the critical components and few of the non critical components may have severe degradation.
- Marginal (MA) - Overall serviceability and reliability loss. Most if not all of the non critical components suffer from severe degradation and a few of the critical component may have severe degradation.
- Moderate (MO) - Overall a significant serviceability loss. Most if not all the components have severe degradation with the reminder of the component showing visible distress.
- Very Poor (VP) - Overall the system is barely functional. All of the components are severely degraded.
- Non-Functional (NF) - Overall the system does not function with all the components having no serviceability and suffer from severe degradation.

System Code	System Description	Unit Price \$	UoM	Qty	Life	Year Installed	Calc Next Renewal Year	Next Renewal Year	RSLI%	FCI%	RSL	eCR	Deficiency \$	Replacement Value \$
G2010	Roadways	\$11.52	S.F.		30				0.00 %	0.00 %				\$0
G2020	Parking Lots	\$8.50	S.F.	4,000	30	1924	1954	2047	106.67 %	111.33 %	32		\$37,852.40	\$34,000
G2030	Pedestrian Paving	\$12.30	S.F.	18,200	40	1924	1964	2057	105.00 %	52.85 %	42		\$118,310.06	\$223,860
G2040	Site Development	\$4.36	S.F.	21,800	25	1924	1949	2027	48.00 %	4.12 %	12		\$3,915.60	\$95,048
G2050	Landscaping & Irrigation	\$4.36	S.F.	3,600	15	1924	1939	2026	73.33 %	0.00 %	11			\$15,696
G4020	Site Lighting	\$4.84	S.F.	21,800	30	1924	1954	2027	40.00 %	0.00 %	12			\$105,512
G4030	Site Communications & Security	\$0.97	S.F.	21,800	30	1924	1954	2027	40.00 %	0.00 %	12			\$21,146
<b>Total</b>									<b>76.55 %</b>	<b>32.32 %</b>			<b>\$160,078.06</b>	<b>\$495,262</b>

## System Notes

The facility description in the site executive summary contains an overview of each system. The notes listed below provide additional information on select systems found within the facility.

No data found for this asset

## Renewal Schedule

eCOMET forecasts future Capital Renewal funding needed to address expiring systems based on the Next Renewal year found in the Cost Models. A 3% annual inflation factor is applied to the costs for systems expiring in future years. The table below reflects recommended Capital Renewal funding needs over the next 10 years. Note: Cells with a zero value indicate systems for which renewal is not scheduled in that year.


*Inflation Rate: 3%*

System	Current Deficiencies	2016	2017	2018	2019	2020	2021	2022	2023	2024	2025	Total
<b>Total:</b>	<b>\$160,078</b>	<b>\$0</b>	<b>\$0</b>	<b>\$0</b>	<b>\$0</b>	<b>\$0</b>	<b>\$0</b>	<b>\$0</b>	<b>\$0</b>	<b>\$0</b>	<b>\$0</b>	<b>\$160,078</b>
G - Building Sitework	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G20 - Site Improvements	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G2010 - Roadways	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G2020 - Parking Lots	\$37,852	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$37,852
G2030 - Pedestrian Paving	\$118,310	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$118,310
G2040 - Site Development	\$3,916	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$3,916
G2050 - Landscaping & Irrigation	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G40 - Site Electrical Utilities	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G4020 - Site Lighting	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G4030 - Site Communications & Security	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0

\* Indicates non-renewable system

## Forecasted Sustainment Requirement

The following chart shows the current building deficiencies and forecasting sustainment requirements over the next ten years.






## 10 Year FCI Forecast by Investment Scenario

The chart below illustrates the effect of various investment levels on the building FCI for the next 10 years. The levels of investment shown below include:

- Current FCI: a variable investment amount based on renewing expired systems to maintain the current FCI for the building
- 2% Investment: an annual investment of 2% of the replacement value of the building, escalated for inflation
- 4% Investment: an annual investment of 4% of the replacement value of the building, escalated for inflation


**Facility Investment vs. FCI Forecast**



Year	Investment Amount Current FCI - 32.32%	2% Investment		4% Investment	
		Amount	FCI	Amount	FCI
2016	\$0	\$10,202.00	30.32 %	\$20,405.00	28.32 %
2017	\$300,920	\$10,508.00	85.59 %	\$21,017.00	81.59 %
2018	\$0	\$10,824.00	83.59 %	\$21,647.00	77.59 %
2019	\$0	\$11,148.00	81.59 %	\$22,297.00	73.59 %
2020	\$0	\$11,483.00	79.59 %	\$22,966.00	69.59 %
2021	\$0	\$11,827.00	77.59 %	\$23,655.00	65.59 %
2022	\$0	\$12,182.00	75.59 %	\$24,364.00	61.59 %
2023	\$0	\$12,548.00	73.59 %	\$25,095.00	57.59 %
2024	\$0	\$12,924.00	71.59 %	\$25,848.00	53.59 %
2025	\$0	\$13,312.00	69.59 %	\$26,624.00	49.59 %
<b>Total:</b>	<b>\$300,920</b>	<b>\$116,958.00</b>		<b>\$233,918.00</b>	


## Deficiency Summary by System

Current deficiencies included assemblies that have reached or exceeded their design life or components of the assemblies that are in need of repair. Assemblies that have reached their design life are identified as current deficiencies and assigned the distress 'Beyond Useful Life'. The following chart lists all current deficiencies associated with this facility.



## Deficiency Summary by Priority

The following chart shows the total repair costs broken down by priority. Assessors assigned deficiencies within eCOMET to one of the following priority categories:



**Budget Estimate Total: \$160,078.06**


## Deficiency By Priority Investment Table

The table below shows the current investment cost grouped by deficiency priority and building system.

System Code	System Description	1 - Response Time (< 2 yr)	2 - Response Time (2-3 yrs)	3 - Response Time (3-4 yrs)	4 - Response Time (4-5 yrs)	5 - Response Time (> 5 yrs)	Total
G2020	Parking Lots	\$0.00	\$15,947.08	\$21,905.32	\$0.00	\$0.00	\$37,852.40
G2030	Pedestrian Paving	\$103,927.21	\$14,382.85	\$0.00	\$0.00	\$0.00	\$118,310.06
G2040	Site Development	\$0.00	\$3,915.60	\$0.00	\$0.00	\$0.00	\$3,915.60
<b>Total:</b>		\$103,927.21	\$34,245.53	\$21,905.32	\$0.00	\$0.00	\$160,078.06

## Deficiency Summary by Category

The following chart shows the total repair costs broken down by deficiency categories. Assessors assigned deficiencies to one of the following categories:



## Deficiency Details by Priority

The deficiency detail notes listed below provide additional information on identified deficiencies found within the facility.

### Priority 1 - Response Time (< 2 yr):

#### System: G2030 - Pedestrian Paving



**Location:** rear entrance door

**Distress:** Building / MEP Codes

**Category:** 2 - Code Compliance

**Priority:** 1 - Response Time (< 2 yr)

**Correction:** Install an exterior ADA ramp - based on 5' wide by the linear foot - up to a 48" rise - per LF of ramp - figure 1 LF per inch of rise

**Qty:** 80.00

**Unit of Measure:** L.F.

**Estimate:** \$103,927.21

**Assessor Name:** Craig Anding

**Date Created:** 01/04/2016

**Notes:** Add handicap ramp to rear door (80ft)

---

**Priority 2 - Response Time (2-3 yrs):**

**System: G2020 - Parking Lots**



**Location:** asphalt playground

**Distress:** Failing

**Category:** 3 - Operations / Maint.

**Priority:** 2 - Response Time (2-3 yrs)

**Correction:** Fill pavement cracks and reseal parking lot - including striping - change the LF of crack repair if it is severe

**Qty:** 9,000.00

**Unit of Measure:** S.F.

**Estimate:** \$15,947.08

**Assessor Name:** Craig Anding

**Date Created:** 01/04/2016

**Notes:** Crack fill and reseal remaining sections of asphalt playground (9000sf)

---

**System: G2030 - Pedestrian Paving**



**Location:** concrete walkways

**Distress:** Failing

**Category:** 3 - Operations / Maint.

**Priority:** 2 - Response Time (2-3 yrs)

**Correction:** Remove and replace concrete sidewalk or concrete paving - 4" concrete thickness

**Qty:** 1,000.00

**Unit of Measure:** S.F.

**Estimate:** \$14,382.85

**Assessor Name:** Craig Anding

**Date Created:** 01/04/2016

**Notes:** Repair concrete walkways (1000sf)

---



**System: G2040 - Site Development**



**Location:** areaway fence

**Distress:** Failing

**Category:** 3 - Operations / Maint.

**Priority:** 2 - Response Time (2-3 yrs)

**Correction:** Paint steel picket fence - LF of fence 6' high

**Qty:** 60.00

**Unit of Measure:** L.F.

**Estimate:** \$3,915.60

**Assessor Name:** Craig Anding

**Date Created:** 01/04/2016

**Notes:** Replace steel fence over basement areaway. (60ft)

---

**Priority 3 - Response Time (3-4 yrs):**

**System: G2020 - Parking Lots**



**Location:** asphalt playground

**Distress:** Failing

**Category:** 3 - Operations / Maint.

**Priority:** 3 - Response Time (3-4 yrs)

**Correction:** Resurface parking lot - grind and resurface including striping

**Qty:** 6,000.00

**Unit of Measure:** S.F.

**Estimate:** \$21,905.32

**Assessor Name:** Craig Anding

**Date Created:** 01/04/2016

**Notes:** Repave damaged sections of asphalt playground area (6,000sf)

---

## Equipment Inventory

The following table represents the inventory details of the inventory found in the building, which fall under the following subsystems:

No data found for this asset

## Glossary

ABMA	American Boiler Manufacturers Association <a href="http://www.abma.com/">http://www.abma.com/</a>
ACEEE	American Council for an Energy-Efficient Economy
ACGIH	American Council of Governmental and Industrial Hygienists
AEE	Association of Energy Engineers
AFD	Adjustable Frequency Drive
AFTC	After Tax Cash Flow
AGA	American Gas Association
AHU	Air Handling Unit
Amp	Ampere
ANSI	American National Standards Institute
ARI	Air Conditioning and Refrigeration Institute
ASD	Adjustable Speed Drive
ASHRAE	American Society of Heating Refrigerating and Air-Conditioning Engineers Inc.
ASME	American Society of Mechanical Engineers
Assessment	Visual survey of a facility to determine its condition. It involves looking at the age of systems reviewing information from local sources and visual evidence of potential problems to assign a condition rating. It does not include destructive testing of materials or testing of systems or equipment for functionality.
ATS	After Tax Savings
AW	Annual worth
BACNET	Building Automation Control Network
BAS	Building Automation System
BCR	Benefit Cost Ratio
BEP	Business Energy Professional (AEE)
BF	Ballast Factor
BHP	Boiler Horsepower (boilers)
BHP	Brake Horsepower (motors)
BLCC	Building Life Cycle Cost analysis program (FEMP)
BOCA	Building Officials and Code Administrators
BTCF	Before Tax Cash Flow

## Site Assessment Report - S823001;Crossan

---

BTS	Before Tax Savings
Btu	British thermal unit
Building Addition	An area space or component of a building added to a building after the original building's year built date.
CAA	Clean Air Act
CAAA-90	Clean Air Act Amendments of 1990
CABO	Council of American Building Officials
CAC	Conventional Air Conditioning
CADDET	Center for the Analysis and Dissemination of Demonstrated Energy Technologies
Calculated Next Renewal	The year a system or element would be expected to expire based solely on the date it was installed and the expected useful lifetime for that kind of system.
Capital Renewal	Capital renewal is condition work (excluding suitability and energy audit work) that includes the replacement of building systems or elements (as they become obsolete or beyond their useful life) not normally included in an annual operating budget. Calculated next renewal The year a system or element would be expected to expire based solely on the date it was installed and the expected useful lifetime for that kind of system. Next renewal The assessor adjusted expected useful life of a system or element based on on-site inspection.
CDD	Cooling Degree Days
CDGP	Certified Distributed Generation Professional
CEC	California Energy Commission
CEM	Certified Energy Manager
CEP	Certified Energy Procurement Professional
CFC	Chlorofluorocarbon
CFD	Cash Flow Diagram
CFL	Compact Fluorescent Light
CFM cfm	Cubic Feet per Minute
CHP	Combined Heat and Power (a.k.a. cogeneration)
CHW	Chilled Water
Condition	Condition refers to the state of physical fitness or readiness of a facility system or system element for its intended use.
COP	Coefficient of Performance
Cp	Heat Capacity of Material
CPUC	California Public Utility Commission
CRI	Color Rendering Index
CRT	Cathode Ray Tube VDT HMI

## Site Assessment Report - S823001;Crossan

---

CTC	Competitive Transition Charge
Cu	Coefficient of Utilization
Current Replacement Value (CRV)	CRV represents the hypothetical total cost of rebuilding or replacing an existing facility in current dollars to its optimal condition (excluding auxiliary facilities) under current codes and construction standards.
Cv	Value Coefficient
CWS	Chilled Water System
D d	Distance (usually feet)
DB	Dry Bulb
DCV	Demand Control Ventilation
DD	Degree Day
DDB	Double Declining Balance
DDC	Direct Digital Controls
Deferred maintenance	Deferred maintenance is condition work (excluding suitability and energy audit needs) deferred on a planned or unplanned basis to a future budget cycle or postponed until funds are available.
Deficiency	A deficiency is a repair item that is damaged missing inadequate or insufficient for an intended purpose.
Delta	Difference
Delta P	Pressure Difference
Delta T	Temperature Difference
DG	Distributed Generation
DOE	Department of Energy
DP	Dew Point
DR	Demand Response
DX	Direct Expansion Air Conditioner
EA	Energy Audit
EBITDA	Earnings before Interest Taxes Depreciation and Amortization
ECI	Energy Cost Index
ECM	Energy Conservation Measure
ECO	Energy Conservation Opportunity
ECPA	Energy Conservation and Production Act
ECR	Energy Conservation Recommendation
ECS	Energy Control System

## Site Assessment Report - S823001;Crossan

---

EER	Energy Efficiency Ratio
EERE	Energy Efficiency and Renewable Energy division of US DOE
EIA	Energy Information Agency
EIS	Energy Information System
EMCS	Energy Management Computer System
EMO	Energy Management Opportunity
EMP	Energy Management Project
EMR	Energy Management Recommendation
EMS	Energy Management System
Energy Utilization Index (EUI)	EUI is the measure of total energy consumed in the cooling or heating of a building in a period expressed as British thermal unit (BTU) per (cooled or heated) gross square foot.
EO	Executive Order
EPA	Environmental Protection Agency
EPACT	Energy Policy Act of 1992
EPCA	Energy Production and Conservation Act of 1975
EPRI	Electric Power Research Institute
EREN	Efficiency and Renewable Energy (Division of USDOE)
ERV	Energy Recovery Ventilator
ESCO	Energy Service Company
ESPC	Energy Savings Performance Contract
EUI	Energy Use Index
EWG	Exempt Wholesale Generators
Extended Facility Condition Index (EFCI)	EFCI is calculated as the condition needs for the current year plus facility system renewal needs going out to a set time in the future divided by Current Replacement Value.
f	Frequency
F	Fahrenheit
Facility	A facility refers to site(s) building(s) or building addition(s) or combinations thereof that provide a particular service.
Facility Condition Assessment (FCA)	FCA is a process for evaluating the condition of buildings and facilities for programming and budgetary purposes through an on site inspection and evaluation process.
Facility Condition Index (FCI)	FCI is an industry-standard measurement of a facility's condition that is the ratio of the cost to correct a facility's deficiencies to the Current Replacement Value of the facilities. The higher the FCI the poorer the condition of a facility. After an FCI is established for all buildings within a portfolio a building's condition can be ranked relative to other buildings. The FCI may also represent the condition of a portfolio based on the cumulative FCIs of the portfolio's facilities.



## Site Assessment Report - S823001;Crossan

---

FC	Footcandle
FCA	Fuel Cost Adjustment
FEMIA	Federal Energy Management Improvement Act of 1988
FEMP	Federal Energy Management Program
FERC	Federal Energy Regulatory Commission
FESR	Fuel Energy Savings Ratio
FLA	Full Load Amps
FLF	Facility Load Factor (usually monthly)
FLRPM	Full Load Revolutions per Minute
FMS	Facility Management System
FPM fpm	Feet per Minute (velocity)
FSEC	Florida Solar Energy Center
Ft	Foot
GPM gpm	Gallons per Minute
GRI	Gas Research Institute
Gross Square Feet (GSF)	The size of the enclosed floor space of a building in square feet measured to the outside face of the enclosing wall.
GUI	Graphical User Interface
H h	Enthalpy Btu/lb
HCFC	Hydrochlorofluorocarbons
HDD	Heating Degree days
HFC	Hydrofluorocarbons
HHV	Higher Heating Value
HID	High Intensity Discharge (lamp)
HMI	Human Machine Interface
HMMI	Human Man Machine Interface
HO	High Output (lamp)
HP Hp hp	Horsepower
HPS	High Pressure Sodium (lamp)
HR	Humidity Ratio
Hr hr	Hour

## Site Assessment Report - S823001;Crossan

---

HRU	Heat Recovery Unit
HVAC	Heating Ventilation and Air-Conditioning
Hz	Hertz
I	Intensity (lumen output of lamp)
I i	Interest rate or Discount rate
IAQ	Indoor Air Quality
ICA	International Cogeneration Alliance
ICBO	International Conference of Buildings Officials
ICC	International Code Council
ICP	Institutional Conservation Program
IECC	International Energy Conservation Code
IEEE	Institute of Electrical and Electronic Engineers
IESNA	Illuminating Engineering Society of North America
Install year	The year a building or system was built or the most recent major renovation date (where a minimum of 70 of the system's Current Replacement Value (CRV) was replaced).
IRP	Integrated Resource Planning
IRR	Internal Rate of Return
ISO	Independent System Operator
ITA	Independent Tariff Administrator
k	Kilo multiple of thousands in SI system
K	Kelvins (color temperature of lamp)
K k	Thermal Conductivity of Material
KVA	Kilovolt Ampere
KVAR	Kilovolt Ampere Reactive
kW	kiloWatt
kWh	kiloWatt hour
L	Length (usually feet)
LCC	Life Cycle Costing
LDC	Local Distribution Company
LEED	Leadership in Energy and Environmental Design
LEED EB	LEED for Existing Buildings

## Site Assessment Report - S823001;Crossan

---

LEED NC	LEED for new construction
LF	Load Factor
LHV	Lower Heating Value
Life cycle	The period of time that a building or site system or element can be expected to adequately serve its intended function.
LPS	Low Pressure Sodium (lamp)
Lu	Lumen Output of a Lamp or Fixture
M	Mega multiple of millions in SI system
M&V	Measurement and Verification
MACRS	Modified Accelerated Cost Recovery System
MARR	Minimum Attractive Rate of Return
Mbtu	Thousand Btu
MCF	Thousand Cubic Feet (usually of gas)
MEC	Model Energy Code
Mm	Multiple of Thousands in I/P System
MMBtu	Million Btu
MMCS	Maintenance Management Computer System
MMI	Man Machine Interface
MMS	Maintenance Management System
MSE 2000	Management System for Energy 2000 (ANSI Georgia Tech Univ)
MW	MegaWatt
MWH MWh	MegaWatt hour
NAAQS	National Ambient Air Quality Standards
NAESCO	National Association of Energy Service Companies
NAIMA	North American Insulation Manufacturers Association
NEA	National Energy Act of 1978
NECPA	National Energy Conservation Policy Act
NEMA	National Electrical Manufacturer's Association
NERC	North American Electric Reliability Council
Next Renewal	The Next Renewal date is an override of the 'Calculated Next Renewal' date and is based upon the assessor's visual inspection.

## Site Assessment Report - S823001;Crossan

---

NFPA	National Fire Protection Association
NGPA	National Gas Policy Act of 1978
NLRPM	No Load Revolutions per Minute (speed)
Nn	Equipment or Project lifetime in economic analysis
NOPR	Notice of Proposed Rule Making from FERC
NOx	Nitrogen Oxide Compounds
NPV	Net present value in economic analysis
NREL	National Renewable Energy Laboratory
NUG	Non-Utility Generator
O&M	Operation and Maintenance
OA	Outside Air
ODP	Ozone Depletion Potential
OPAC	Off-Peak Air Conditioning
P	Present value in economic analysis
PBR	Performance Based Rates
PEA	Preliminary Energy Audit
PF	Power Factor
PID	Proportional plus integral plus derivative (control system)
PM	Portfolio Manager in Energy Star rating system
PM	Preventive Maintenance
PoolCo	Power Pool Company or Organization
POU	Point of Use
PQ	Power Quality
PSC	Public Service Commission
PSIA psia	Pounds per square inch absolute (pressure)
PSIG psig	Pounds per square inch gauge (pressure)
PUC	Public Utility Commission
PUHCA	Public Utilities Holding Company Act of 1935
PURPA	Public Utilities Regulatory Policies of 1978
PV	Photovoltaic system

## Site Assessment Report - S823001;Crossan

---

PV	Present Value
PW	Present Worth
PX	Power Exchange
q	Rate of heat flow in Btu per hour
Q	Heat load due to conduction using degree days
QF	Qualifying Facility
R	Electrical resistance
R	Thermal Resistance
RC	Remote controller
RCR	Room Cavity Ratio
RCRA	Resource Conservation and Recovery Act
Remaining Service Life (RSL)	RSL is the number of years service remaining for a system or equipment item. It is automatically calculated based on the difference between the current year and the 'Calculated Next Renewal' date or the 'Next Renewal' date whichever one is the later date.
Remaining Service Life Index (RSLI)	RSLI is defined as a percentage ratio of the remaining service life of a system. It usually ranges from 0 to 100
REMR	Repair Evaluation Maintenance Rehabilitation (REMR) is a scale used to objectively rank systems based on their condition
Renewal Schedule	A timeline that provides the items that need repair the year in which the repair is needed and the estimated price of the renewal.
RH	Relative Humidity
RLA	Running Load Amps
RMS	Root Mean Square
RO	Reverse Osmosis
ROI	Return on Investment
RPM	Revolutions Per Minute
RTG	Regional Transmission Group
RTO	Regional Transmission Organization
RTP	Real Time Pricing
SBCCI	Southern Building Code Congress International
SC	Scheduling Coordinator
SC	Shading Coefficient
SCADA	Supervisory Control and Data Acquisition Systems

## Site Assessment Report - S823001;Crossan

---

SEER	Seasonal Energy Efficiency Ratio
SHR	Sensible Heat Ratio
Site	The grounds and utilities roadways landscaping fencing and other typical land improvements needed to support the facility.
Soft Cost	An expense item that is not considered direct construction cost. Soft cost includes architectural engineering financing legal fees and other pre-and-post construction expenses.
SOx	Sulfur Oxide Compounds
SP	Static Pressure
SP SPB	Simple Payback
SPP	Simple Payback Period
SPP	Small Power Producers
STR	Stack Temperature Rise
SV	Specific Volume
System	System refers to building and related site work elements as described by ASTM Uniformat II Classification for Building Elements (E1557-97) a format for classifying major facility elements common to most buildings. Elements usually perform a given function regardless of the design specification construction method or materials used. See also Uniformat II.
T	Temperature
T	Tubular (lamps)
TAA	Technical Assistance Audit
TCP/IP	Transmission Control Protocol/Internet Protocol
TES	Thermal Energy Storage
THD	Total Harmonic Distortion
TOD	Time of Day
TOU	Time of Use
TQM	Total Quality Management
TransCo	Transmission Company
U	Thermal Conductance
UDC	Utility Distribution Company
UL	Underwriters Laboratories
UNIFORMAT II	The ASTM UNIFORMAT II Classification for Building Elements (E1557-97) a format for classifying major facility components common to most buildings.
USGBC	US Green Building Council
v	Specific Volume

## Site Assessment Report - S823001;Crossan

---

V	Volts Voltage
V	Volume
VAV	Variable Air Volume
VDT	Video Display Terminal
VFD	Variable Frequency Drive
VHO	Very High Output
VSD	Variable Speed Drive
W	Watts
W	Width
WB	Wet bulb
WH Wh	Watt Hours
Year built	The year that a building or addition was originally built based on substantial completion or occupancy.
Z	Electrical Impedance