

Facility Condition Assessment Summary Report

This report provides a summary of the Facility Condition Index (FCI) value of a school facility and select major building systems. The FCI calculation represents the cost of needed repairs divided by the replacement value. The FCI is a numerical value of condition and helps to identify the need for renewal or replacement of specific parts of the facility. The FCI is particularly useful when comparing similar facilities within the same portfolio.

Feltonville Intermediate School

| | | | |
|------------|--------------------------------------------------|---------------------|--------------|
| Governance | DISTRICT | Report Type | Elementary |
| Address | 238 E. Wyoming Ave. Philadelphia, Pa 19120 | Enrollment | 769 |
| Phone/Fax | 215-456-3012 / 215-456-0122 | Grade Range | '03-05' |
| Website | Www.Philasd.Org/Schools/Feltonville-Intermediate | Admissions Category | Neighborhood |
| | | Turnaround Model | N/A |

Building/System FCI Tiers

| Facility Condition Index (FCI) = $\frac{\text{Cost of Assessed Deficiencies}}{\text{Replacement Value}}$ | | | | |
|----------------------------------------------------------------------------------------------------------|-------------------------------|---------------------------------------------------------------|---------------------------------------------------------------------------------------|----------------------------------------------------------|
| < 15% | 15 to 25% | 25 to 45% | 45 to 60% | > 60% |
| Buildings | | | | |
| Minimal Current Capital Funding Required | Refurbish Systems in building | Replace Systems in building. | Building should be considered for major renovation. | Building should be considered for closing/replacement. |
| Systems | | | | |
| Perform routine maintenance on system | System requires minor repairs | System should be studied to determine repair vs. replacement. | System is nearing end of its life expectancy and should be considered for replacement | System should be replaced as part of the Capital Program |

Building and Grounds

| | FCI | Repair Costs | Replacement Cost |
|----------------|---------------|---------------------|---------------------|
| Overall | 40.14% | \$17,133,237 | \$42,683,473 |
| Building | 40.57 % | \$16,925,121 | \$41,721,754 |
| Grounds | 21.64 % | \$208,117 | \$961,719 |

Major Building Systems

| Building System | System FCI | Repair Costs | Replacement Cost |
|--------------------------------------------------------------------------------------------|------------|--------------|------------------|
| Roof (Shows physical condition of roof) | 89.44 % | \$1,412,609 | \$1,579,330 |
| Exterior Walls (Shows condition of the structural condition of the exterior facade) | 09.85 % | \$305,414 | \$3,100,440 |
| Windows (Shows functionality of exterior windows) | 60.40 % | \$913,792 | \$1,512,840 |
| Exterior Doors (Shows condition of exterior doors) | 149.55 % | \$182,146 | \$121,800 |
| Interior Doors (Classroom doors) | 181.73 % | \$535,826 | \$294,840 |
| Interior Walls (Paint and Finishes) | 05.03 % | \$55,819 | \$1,109,640 |
| Plumbing Fixtures | 02.96 % | \$33,660 | \$1,135,680 |
| Boilers | 00.00 % | \$0 | \$1,568,280 |
| Chillers/Cooling Towers | 121.19 % | \$2,492,130 | \$2,056,320 |
| Radiators/Unit Ventilators/HVAC | 164.74 % | \$5,948,957 | \$3,611,160 |
| Heating/Cooling Controls | 00.00 % | \$0 | \$1,134,000 |
| Electrical Service and Distribution | 00.00 % | \$0 | \$814,800 |
| Lighting | 00.00 % | \$0 | \$2,913,120 |
| Communications and Security (Cameras, Pa System and Fire Alarm) | 59.37 % | \$647,863 | \$1,091,160 |

Please note that some FCIs may be over 100% because there are times when replacing a building system requires that other building systems be upgraded to complete the installation. A FCI of 0.0% represents that there are no current deficiencies with the associated system.

School District of Philadelphia

S731001;Feltonville Intermediate

Final
Site Assessment Report

January 31, 2017



PARSONS

Table of Contents

| | |
|-------------------------------------------------|----|
| Site Executive Summary | 4 |
| Site Condition Summary | 12 |
| <u>B731001;Feltonville Intermediate</u> | 14 |
| Executive Summary | 14 |
| Condition Summary | 15 |
| Condition Detail | 16 |
| System Listing | 17 |
| System Notes | 19 |
| Renewal Schedule | 20 |
| Forecasted Sustainment Requirement | 23 |
| Condition Index Forecast by Investment Scenario | 24 |
| Deficiency Summary By System | 25 |
| Deficiency Summary By Priority | 26 |
| Deficiency By Priority Investment | 27 |
| Deficiency Summary By Category | 28 |
| Deficiency Details By Priority | 29 |
| Equipment Inventory Detail | 54 |
| <u>G731001;Grounds</u> | 55 |
| Executive Summary | 55 |
| Condition Summary | 56 |
| Condition Detail | 57 |
| System Listing | 58 |
| System Notes | 59 |
| Renewal Schedule | 60 |
| Forecasted Sustainment Requirement | 61 |
| Condition Index Forecast by Investment Scenario | 62 |
| Deficiency Summary By System | 63 |
| Deficiency Summary By Priority | 64 |
| Deficiency By Priority Investment | 65 |

Site Assessment Report

| | |
|--------------------------------|----|
| Deficiency Summary By Category | 66 |
| Deficiency Details By Priority | 67 |
| Equipment Inventory Detail | 72 |
| Glossary | 73 |

Site Executive Summary

The organization of this report, as displayed in the Table of Contents, follows the structure of the associated eCOMET database. The overall node for each school campus begins with the letter "S", which indicates the "Site" label. Each Site is comprised of separate "Building" and "Grounds" nodes; their asset names begin with the letters "B" and "G" respectively. Information rolls up to the Site node from the Building and Grounds nodes. This Site report combines facility information with subsections for the Buildings And Grounds nodes.

The basis for the evaluation of condition is the functional systems and elements of a building and grounds organized according to the UNIFORMAT II Elemental Classification. The grouping of these systems and elements and applying a current replacement value to them develops a representative building cost model. Cost Models are typically developed for similar building types and functions. Evaluation of systems and their elements takes into account their current replacement values, life cycles, installation dates and next renewal dates. Systems and their elements that are within their useful lives are further evaluated to identify current deficient conditions that may have a significant impact on a system's or element's remaining service life, and to determine if they are beyond their predicted expected life. The system's or element's current replacement value is based on RS Means Commercial Cost Data.

Following are the cost model's system details for this facility. The Replacement Value is the amount needed to replace the property of the same present value. The Current Repair Amount, also known as Condition Needs, represents the budgeted contractor installed costs plus owner's soft costs for the repair, replacement or renewal for a component or system level deficiency. It excludes contributing costs for other components or systems that might also be associated with the corrective actions due to packaging the work. Facility Condition Index (FCI) is an industry-standard measurement calculated as the ratio of the repair costs to correct a facility's deficiencies to the facility's Current Replacement Value. Condition Index (CI) for a system is calculated as the sum of a the deficiencies divided by the sum of a system's Replacement Value (both values include soft-cost) expressed as a percentage ranging from 0% 100%.

| | |
|--------------------|-----------------|
| Gross Area (SF): | 84,000 |
| Year Built: | 1936 |
| Last Renovation: | |
| Replacement Value: | \$42,683,473 |
| Repair Cost: | \$17,133,237.19 |
| Total FCI: | 40.14 % |
| Total RSLI: | 68.36 % |



Description:

Facility Condition Assessment
November 2015

School District of Philadelphia
Feltonville Intermediate School
238 East Wyoming Avenue
Philadelphia, PA 19120

84,000sf / 725 students / LN 07

Feltonville Intermediate School is located at 238 East Wyoming Avenue. The main entrance faces East Wyoming Avenue. This building appears to be constructed over a period of years, because the floor plan of the building is somewhat rambling and the exterior is constructed of different materials which seem to be assembled in ad-hoc ways, although there is no photographic or written proof of this assumption. The oldest available on-line aerial photograph of the site from 1948 shows the structure with all components as they are today. The rambling layout has internal classrooms with no outside windows and long, internal corridors also without any daylight, signs of a building not designed as a school; the layout is not a bright and child-friendly layout. It is thought that after being

Site Assessment Report - S731001; Feltonville Intermediate

converted from a paper mill to a school, the building was used as the Olney High School Annex, then the Central Middle School, before becoming the Feltonville Intermediate School for grades 3, 4, and 5. The total size of the facility is 84,000sf. Duane Dotson, the Assistant Building Engineer, accompanied the team during the building inspection.

At the time of the site visitation, the inspection team met with Principal Donald Anticoli and Marcy, the Director of Education, who expressed the following concerns. Faculty and staff must park on the street because there is no off-street parking for the school. All toilet rooms have leaky plumbing; when it rains, the toilet room drains back-up and cause flooding. Some classrooms have no exterior windows, due to the wide footprint of the converted factory building layout. There is a central airconditioning system, but it is not always working and controls do not function properly. Interior and exterior lighting is inadequate. There are roof leaks and window leaks. There are no outside speakers. There is a rodent problem in the building.

ARCHITECTURAL/STRUCTURAL SYSTEMS

Foundations appear to be constructed of poured concrete and brick. Joints are in good condition with no major settlement cracks observed. Paint on the basement walls and ceilings, is in good condition as it appears to have been recently repainted. Exposed structural steel columns and beams are fireproofed. Footings were not seen and their construction type or condition could not be ascertained.

Floor slabs in the boiler room in the original building basement and the new addition are constructed of concrete which is in good condition although covered with a layer of ground in dirt. Upper floor slabs are concrete on either steel beams with metal deck or concrete beams and a concrete plank structure. There was no observed cracking and spalling of the concrete slabs. .

Roof construction over the is a flat deck; the structural system was exposed only over the gym, where steel beams and columns (encased in block) support an exposed wood deck with wood joists. It is not known what type of structural system is used over other areas of the building. Internal roof drains are used to drain the roof. There are some roof areas which have overflow scuppers cut into the low parapet; these might have been added at some point in the past. Other sections of roof deck are flat with no parapet, allowing water to flow over the edge if roof drains become blocked. Roof construction over the gymnasium. All roof decks are nearly dead-level flat with minimum overall slope. There is one roof penthouse with a door to the roof; access to other roof levels are from windows or grade level portable ladders. One of the low roofs has two air handlers, but neither are in operation. All roof decks have soft spots and flat spots that accumulate water. Perimeter flashing is cracked and leaking and couter flashing is loose in many locations. The entire roof membrane is worn and needs to be replaced

Exterior walls on the new addition are constructed of brick, flat metal panels, painted terra cotta tiles and cement covered columns. Many joints in many areas of the old building brickwork are losing grout, in need of repointing. Some areas have already been repointed as evident from the lighter grout and brick color. Walls around the building up to the top of the first floor have been painted with brown paint (on walls) or white paint on cement pilasters along street; the color is fading and has blotchy-patched areas and needs to be properly reapplied. EIFS (Exterior insulation and finish system, also known as "Dryvit") is used on the walls of a second floor section in the rear. The rear one-story section of the building housing the gymnasium has what appears to be a terra cotta or ceramic tile exterior wall system, painted brown. These blocks have holes in the exterior face. Furthermore, this material appears to be utilized in a single wythe construction without any insulation or other wythe of blocks on the inside the exterior blocks. This creates a very poor and porous wall system providing very little protection from the cold exterior during winter and moisture or water during warmer months. The District should consider adding another skin to the outside of the blocks by utilizing a cost effective solution such as EIFS to provide better weather protection, a layer of insulation on the exterior of the wall, and more interior comfort with better heat retention to that section of the building.

Exterior windows are made of bronze anodized aluminum frames with operable single hung units and single thickness clear plexi glass vision panel glazing. These windows are in poor condition with oxidized frames and severely scratched single-pane plexi glass vision panels. Operable units are difficult to operate up and down, due to broken internal counterbalance weights. Single pane plexiglass units do not meet today's energy code requirements and are large sources of heat loss; they should be replaced. First floor and basement windows in the old building facing the street have external galvanized steel security screens. Some steel lintels in brick walls over these windows are rusted and causing joint damage in need of replacement. First floor windows have heavy duty galvanized steel security screens. Many windows leak with water damage evident on the walls around the windows. Windows are in poor condition and in need of replacement.

Exterior doors providing emergency exit from stairways (with and without narrow vision panels) are flush, painted hollow metal doors with painted steel frames. These steel doors and frames are rusted, damaged, lack weather stripping, have hardware that is old/damaged, and need to be replaced. The gymnasium in the rear of the building has grade-level access from the exterior, but there are stairs in the corridor leading up to the other first floor spaces and stairs leading up from grade to the exit doors in the other first floor areas. The entrance to the main lobby from the street is through a pair of hollow metal doors at the top of an aging and crumbling 12 riser stair. Accessibility can be provided by constructing ramps at a side exit and a ramp or chair lift in the corridor

Site Assessment Report - S731001; Feltonville Intermediate

leading to the gym.

Roof coverings on all roofs consist of a naturally colored (black) fully adhered rolled asphalt sheet system without granules or gravel. Brick wall structures and mechanical equipment are flashed with similar asphaltic membranes with aluminum or copper counterflashing overlapping top edges. The roof membranes on all roofs are aging with many soft and cracked areas; flashing and counterflashing is damaged and worn. Roof leaks throughout the building have been reported and repairs have been attempted. The masonry flashing and counterflashing on many areas of roof over appears bent and losing integrity with the brick. Aluminum coping on all walls appear to be in good condition. In light of the leaks reported and the worn condition of the membrane of the new roof, full replacement is required.

Partitions in classrooms, offices, corridors, cafeteria, multipurpose room, gymnasium, and stairways are constructed of painted concrete block. Toilet rooms also have glazed block, painted brick and painted block; all toilet rooms are old with a mix of old fixtures and finishes. The gymnasium interior partitions are block. All partitions are generally adequate; they have been repainted in the past by maintenance or under other small contracts, but many need to be refreshed with a new coat of paint or patched and repainted.

Interior doors into classrooms, offices, toilet rooms, and the cafeteria are solid core wood with oak veneer and mostly hollow metal frames. Most doors have narrow vertical vision panels. Mechanical room doors, auditorium doors, and stairway doors are hollow metal doors and frames; they are scratched, dented and do not latch closed as required by code and hardware is in poor condition. Doors do not have lever handle hardware and are not ADA compliant. Doors do not have security locks, which allow for locking from inside the room; these are required to meet new school security guidelines. Due to the poor condition and lack of code compliant working hardware, all doors and hardware need to be replaced.

Interior fittings/hardware include white boards, blackboards, and green boards. Some classrooms have working or broken smart boards. Toilet room partitions are mostly plastic (HDPE- high density polyethylene) in fair condition with most of the necessary accessories such as toilet paper dispensers, soap, paper towel or dryers, and grab bars for accessibility in selected toilet rooms. Toilet room partitions are different in different toilet rooms, but at least are somewhat functional and upgrades from the original partitions. There are no toilet rooms that are fully compliant with ADA; grab bars and fixtures should be added to selected toilet rooms to provide accessible rest room facilities.

Stair construction consists of steel pan and riser stair systems with concrete-filled treads. Stairways all have 30" high handrails and 36" high guards at platforms and steel vertical balusters with 3" maximum spacing. All stair railings are painted steel in worn condition. None of the stair railing and guard systems comply with today's codes, which require 36" handrails, 42" guards on open sides of stairs and platforms; baluster spacing is 4", thus existing 3" spaced baluster, where used, comply. Stairway railing and guard systems do not comply with today's codes and need to be upgraded.

Wall finishes in the old building are painted block or painted brick in good condition. This includes classrooms, auditorium, cafeteria, toilet rooms, and stairways. Some walls have been repainted by maintenance or faculty which has improved their appearance.

Floor finishes in corridors, most classrooms, most offices, auditorium, cafeteria, and stairway landings consist of 12"x12" vinyl composition tiles (VCT). This material is has not been adequately maintained and cleaned; many tiles are cracked and broken. Some third floor classrooms and some offices have VAT (vinyl asbestos tile), which needs to be replaced. Toilet rooms have painted concrete floor finishes. The gymnasium has a high-build painted floor system, cracked in a number of locations.

Ceiling finishes in the new addition are mostly 2'x4' suspended acoustical tile ceilings with recessed or pendant mounted fluorescent lighting fixtures, all in good condition. Toilet rooms have plaster or 2x4 ceilings with surface mounted fluorescent lighting. The ceiling of the gymnasium is open with exposed painted steel beams, wood joists and wood roof deck with surface mounted industrial-type fluorescent lighting. Ceilings are worn, discolored, water stained, and need to be replaced.

A four-stop, 3500lb capacity, traction elevator is provided in the building. It appears to have been upgraded to provide audible, visual, and tactile notifications as required by ADA. New controls also appear to have been recently installed in the elevator control room located on the roof.

Fixed furnishings consist of oak and chemical resistant resin countertop laboratory casework in science rooms that are worn, scratched, and need to be replaced. Stainless steel kitchen service counters and equipment are used for food warming and service are still in adequate usable condition. The IMC (library), classrooms, and offices have loose wood, met and plastic laminate bookcases laminate and metal storage casework and storage cabinets are utilized throughout the building. The Multi-Purpose Room has a portable stage and loose, stackable chairs. The cafeteria and auditorium have foldable table/chair units and a portable stage; there is no fixed seating and no fixed stage in this building.

MECHANICAL

Plumbing Fixtures – The building is equipped with wall hung urinals (flush valve type), a combination of floor mount and wall hung water closets (flush valve type), and wall hung lavatories with wheel handle faucets. Many of the original plumbing fixtures remain in service, however, these fixtures have reached the end of their service life and should be replaced. New fixtures will provide lower water consumption and provide savings on water heating costs. The bathrooms are also equipped with floor drains.

Original drinking fountains in the corridors and at the restrooms are wall hung electric water coolers. There is a combination of wall hung and floor set electric water coolers throughout the remainder of the school. Most of the fixtures do not appear to be original, however they do appear to have exceeded their service life so they should be replaced.

Floor set mop sinks are available throughout the building for use by the janitorial staff. Service sinks are typically located in the vicinity of the bathroom groups. Floor set mop sinks appear to have been replaced in the past, however the sinks appear have exceeded their service life, and should be replaced. The Cafeteria's food prep/kitchen is equipped with one, three compartment stainless steel sink with wheel handle operated faucets and its sanitary connection is served by a floor mounted grease trap. The kitchen is also equipped with a hand sink. The triple wash sink (with wheel handles) and hand sink (with lever handles) show signs of normal usage. A grease interceptor could not be located, therefore one should be installed.. Chemicals are injected manually into the sanitizing basin.

Domestic Water Distribution – It appears that the 2" domestic water service piping is mostly soldered copper. Water service enters without a double check backflow preventer (RPZA – reduced pressure zone assembly) but has a 2" water meter on the main line upon entering the building. The water meter appears to be new. There is a dedicated cold water make up with a RPZA BFP for the boiler. The piping is copper with soldered joints. The distribution piping appears to be original and is at the end of its service life and is recommended to be inspected and repaired as needed.

There is one natural gas fired vertical, 100 gallon, tank type water heater, American Standard, Dura Glass model D100-199 AS, at this facility which are located in the boiler mechanical room. The heater is rated for a gas input of 199,000 btuh, the hot water system is equipped with a recirculation pump and expansion tank. The water heater was manufactured in 2010 and appears to be in satisfactory condition and should not need replacement within the next 10 years. A water softener was located in the boiler room for treating the boiler make up water system. The water softener system appears to be relatively new. Domestic water piping should be checked and inspected by a contractor.

Sanitary Waste - The sanitary waste piping system in the original building is extra heavy cast iron with lead and oakum seals and appears to be the original piping installed in the building. It is therefore recommended to inspect this piping and repair or replace sections as needed. The sanitary system leaves the building by gravity.

Rain Water Drainage - The rain water drains from the roof are routed through mechanical chases in the building and connect to the underground site drainage system. The original building roof has a parapet, while the two additions' roofs are downspout and gutters. There are no overflow scuppers or other overflow systems for any of the building's roof systems. There is a sump pump in the main boiler mechanical equipment room.

Energy Supply - Duplex fuel oil supply pumps provide the required fuel to the boilers when operating on fuel oil. The 7,000 gallon fuel storage tank is located underground beneath the concrete pavement toward the rear of the building. The fuel pumps and level monitoring controls have been recently replaced in the past 5 – 7 years and should not need to be replaced for 20 years as long as preventative maintenance is performed as required. The 8" natural gas enters the building in the basement into the main boiler mechanical equipment room and is equipped with a gas booster system. The gas service splits into two branches, a 3" line and a 1-1/2" line, both are metered. The natural gas main is welded, black steel piping while the branches are threaded, black steel.

Heat Generating Systems – Low pressure steam is generated at 15 lbs. /sq. in. or less by two 4,070 MBH (IBR steam) Weil McLain model 94 series 1594 steam boilers with dual fuel burners. Both boilers are equipped with Webster dual fuel burners, natural gas and number 2 fuel oil, model Cyclonetic JB2C-30-VB110-M25-MP-UL-IRI-CSD-1CR5-GO-30. The boilers appear to have been installed in 2010 and should not need to be replaced for 25 – 30 years as long as preventative maintenance is performed as required. There is draft control on both of the boiler flues. Combustion air louvers serve the boiler room to provide combustion air for the boiler operation. Burner controls provide full modulation with electronic ignition and digital flame sensing. Burner oil pumps are driven by independent motors. The gas train serving each boiler appears to have code required venting of the regulators and dual solenoid valves with venting of the chamber between. The oil supply to the burner is equipped with dual solenoid valves and strainer/disposable media filter.

Steam is delivered to a skid mounted packaged shell and tube heat exchanger and pumps, manufactured by Bell & Gossett, which provide heating water to the building's heating water sources. This serves hot water systems in the addition.

Site Assessment Report - S731001; Feltonville Intermediate

Cooling Systems – The building cooling system consist of a Carrier model 30HXC106RZ-661BA, package screw chiller, 104 nominal tons, with R134a as the refrigerant. The chiller is served by two, of which only one is operation, Evapco model LSTA 4-121, forced draft, counter flow cooling tower. Further investigation is recommended of the pairing of the tower and the chiller. The chiller and cooling tower appear to be approximately 10 years in age. The cooling towers are housed inside the mechanical equipment room with the discharge of the tower ducted to the atmosphere. Nameplate data was illegible on the chilled water and condenser water pumps, however the pumps are manufactured by Bell & Gossett and are base mounted end suction centrifugal type.

Distribution Systems – The building steam distribution piping is black steel with welded fittings. The condensate piping is Schedule 80 black steel with threaded fittings. The piping has been in use beyond its service life, with the exception of the piping which was replaced during the 2010 boiler replacement project, and will require more frequent attention from the maintenance staff to address pipe/valve failures as time passes. The District should hire a qualified contractor to examine the distribution piping and perform additional testing to locate and replace any damaged piping and to further quantify the extent of potential failures. This should be performed for the steam and condensate system as well as the heating water supply and return system. The District should budget for replacing this piping over the next 5 years.

The boiler feed water is collected by a boiler feed water pad mounted system, which was installed in 2010, manufactured by Bell & Gossett model 1-50-CHLD-4-0-635, 22 GPM and is treated with a combination of chemicals by a water treatment controller. The condensate return piping is black steel with threaded joints. A duplex condensate receiver system, installed in 2010, returns condensate to the boiler feed water system for water treatment and storage. The boiler feed water assembly is equipped with three pumps and a pump control panel. The steam traps are in good condition throughout the building according to the building engineer. However, it is recommended that the District conduct a steam trap survey to determine the quantity and condition of all steam traps. The boiler feed tank, pumps and associated components are were replaced in 2010 as part of the boiler plant renovation and should not need to be replaced for 25 – 30 years as long as preventative maintenance is performed as required.

Fresh air is admitted into the building through the air handling units and by opening windows for some spaces such as the cafeteria and gymnasium. . The new air handlers should be designed for quiet operation and equipped with steam and chilled water coils. The building uses original York indoor package air handlers and Carrier modular units for the classrooms. The York units of which there are 5 total serve the areas as follows; three units serve the second floor classrooms or which the unit for classroom 201 works, the unit near classroom 206 and by classroom 202A do not work, two units serve the first floor of which one does not work that serves a classroom and the one serving classroom 100 does function. The two Carrier units, which are five years old, one serves portions of the second floor and the other serves the third floor. These units have steam coils and chilled water coils. They are models 39L modular air handlers. A horizontally suspended air handler next to room 114 serve part of the first floor and is equipped with heating and cooling. Steam coils radiators serve the classrooms, cast iron radiators in the hallways, steam radiators serve areas near stairwells and wall or ceiling mount radiators for bathrooms. This equipment currently is the sole source of heat for these areas. During our survey we noted radiators with and without guards or enclosures. Any steam radiators in service without guards or enclosures should be replaced with finned tube convectors to protect students from exposure to the hot surfaces or guards should be added.

The gymnasium is served by horizontally ceiling suspended heating and ventilating units with steam coils and operable windows for ventilation. . The gym lockers are not in use and are being used for storage. It is recommended to replace these systems with a roof top mounted unit with a similar overhead supply air distribution system and return air ductwork and low return intake grilles which would be protected from damage as the existing system is

The multipurpose room is served by steam radiators and an air handling unit capable of providing heating and ventilation via overhead supply ductwork system. It is recommended to replace these systems with an air handling unit with a similar overhead supply air distribution system and return air ductwork and low return intake grilles.

The cafeteria is served three split system Goodman units, each with five tons of cooling capacity. Heat is provided to the cafeteria by vertical suspended unit heaters with steam coils. The convection heaters are part of the original building equipment, have exceeded their life expectancy and should be removed. The split systems which provide cooling should be replaced as well since they use R22 refrigerant. A ducted supply system is recommended to provide better air distribution instead of the current supply plenum with diffusers arrangement. The kitchen is not provided with a hood exhaust system. It is recommended that a hood exhaust system be implemented for any equipment which generates heat. This system should be coupled with a make-up air heating and ventilating supply air system for the kitchen hoods. Proper air flow pressurization and balancing should be performed for the seating area with respect to the kitchen to maintain the kitchen under negative pressurization.

Terminal & Package Units - There are a few which have window air conditioning units however most of the school is served by air handling equipment which is connected to the chilled water system.. There are roof mounted exhaust fans of which serve the restrooms.. The two restroom exhaust fans should be replaced. Entryways are served by convective heaters or fan coil units.

Controls & Instrumentation - The controls are DDC.

Site Assessment Report - S731001;Feltonville Intermediate

Sprinklers - The school building is partially covered by an automatic sprinkler system with the exception of the gymnasium, lunchroom, kitchen and stairwell. Installing a sprinkler system with quick response type heads should reduce insurance costs by providing protection for the property investment. A fire pump may be required depending on the available city water pressure.

ELECTRICAL

Site Electrical Service comes from medium voltage overhead lines on wooden poles along Wyoming Ave. The main service substation located in the Main Electrical Room in ground floor and receives power from an overhead pole via an underground raceway. The service substation is consisting of a 600A, 4160V load interrupter section, a section for current and potential transformers, a section for protection relays, 1000KVA 4160V to 480/277VAC, 3PH, 4 wire power transformer section and a 1600A rated, 480/277V distribution switchboard. Utility meter is installed in a separate enclosure adjacent to the switchgear assembly. 50KVAR capacitor bank is installed for the system power factor correction. There is one step down transformers rated at 225KVA, 480V to 208/120V is provided in same room. This transformer in turn feeds an 800A distribution power panel named MDP-1. Service substation is 21 years old and still is in good condition. It could be in service for 10 more years.

Power distribution is achieved through several lighting/receptacle panels. Panel boards, two or three in each floor, one in the kitchen, two in gymnasium and one in auditorium. Our observation shows that about 90 present the panel boards are exceed their useful life and should be replaced. Our suggestion is to provide also more power panels for future expansion.

Classrooms, corridors, offices, and other areas typically have an adequate number of duplex receptacles on each wall. No major deficiencies with respect to receptacle number and location were observed.

Majority of lighting fixtures have been upgraded last summer. In general interior lighting fixtures are in a good condition and building illumination is sufficient. However some lighting fixtures still need to be repaired to make the system fully operational.

Building is equipped with 120V manual fire alarm system. The system does not meet current fire alarm codes and should be replaced with an automatic fire alarm system.

The school telephone and data systems are new and working adequately. A main distribution frame (MDF) along with a telephone PBX system (telephone within an enterprise that switches calls between enterprise users on local lines while allowing all users to share a certain number of external phone lines) located in IT room servicing the communication system of the building. School also equipped with wifi system.

Separate PA system does not exist. School uses the telephone systems for public announcement. This system is working adequately.

Each classroom is provided by intercom telephone service. The system is permit paging and intercom communication between main office phone to classroom phones, and classroom to main office, classroom to classroom, and to office. Outside line access from a classroom phone through the PBX is blocked. The system is interfaces with master clock system for class change signaling utilizing paging speakers. The system also equipped with a tone generator and input from program/clock controller.

Present clock system is not working. School is provided with time system controller consisting of 12" electric round clock installed on the wall in each classrooms and offices and a master time programmer manufactured by "STANDARD" located in the main office. The clocks are not controlled properly with the central master controller. System is old and has exceeded its useful service life thus requiring replacement. The present bell system is working adequately.

Television System is not provided in the school.

Video surveillance system is not provided in the school. School provided only with access control system such a door contacts on IMC, and main entrance doors and motion security sensors in corridors. The school desires a complete video surveillance system with cameras located in critical areas, such as exit doors, corridors, and building exterior areas. The cameras should be controlled by a Closed Circuit Television (CCTV) system.

Emergency Power System is provided in the school. A 10KW, 240/120V, single phase, 3W is installed in Boiler room for emergency lighting. The system is old and exceeds its useful service life and required to be replaced.

Uninterruptible Power System (UPS) is provided for Local Area Network in the main IT room.

Emergency lighting system, including exit lights are provided in the buildings. Numbers of lighting fixtures in corridors, and egress

Site Assessment Report - S731001; Feltonville Intermediate

ways are fed by backup power generator. Exit signs are also fed by emergency pack up power and 80 percent of them are in good condition.

Lightning Protection System is accomplished with a few air terminals mounted on the chimney on the roof and connected to the ground system. Further study is needed to verify that the air terminals provide the proper coverage.

There is one 12.5HP hydraulic type elevator manufactured by Imperial Electric Company, is in operation at the school. The elevator appears to be working properly.

Sound System in multipurpose room is old and not comply with modern multipurpose/auditorium sound system requirements recommended by ECE40020 (standard for reinforcement system design) and required to be replaced.

Site Lighting is provided in the school; however some lighting fixtures need to be repaired to make the system fully operational as designed.

Site Lighting System is adequate. Numbers of flood lights are provided on exterior walls around the building where required. Minority of the lights need to be repaired for making the system fully operational as designed. Building engineer also indicated that they do not have any major issues with the exterior lighting system.

Exterior building is not monitored by video surveillance camera.

Site Paging System is not provided in the school.

GROUNDS

Paving and parking is constructed of asphalt and is very limited on this site. There is no faculty parking on site and also no handicap parking on site. Driveway access to East Wyoming Avenue allows for delivery, fuel oil, and waste management trucks to enter and leave the site. The asphalt paving and concrete entrance apron is broken up and disintegrating from the heavy truck traffic; the roadway is also settling around the filling ports to the underground fuel oil tanks. The asphalt area to the rear has access to East Courtland Street but is blocked since it is used as the children's playground; this area also needs to be repaved. A low concrete retaining wall with a chain link fence mounted to the top forms the east side of the property, which borders a cemetery on the east. The retaining wall is cracking and spalling and needs to be repaired.

A wrought iron fence lines the East Wyoming Avenue sidewalk and forms the railing to the entry stairway up to the front door. The fence is rusted and needs to be repainted.

There are no handicap accessible ramps into the building, however there is a grade-level entrance into the rear gymnasium door which allows for access into the gym. Since this is quite far from the street entrance, a second ramp should be constructed to provide handicap access into the main building first floor where there is access to the elevator.

RECOMMENDATIONS

- Strip, clean and reseal concrete floors in mechanical rooms, toilet rooms and stairways. (8,400 s.f.)
- Repoint brick on chimney, penthouse and other building walls; repair brick at lintel bearing (700 s.f.)
- Replaster front and side exterior cement pilasters and beams (2,500 s.f.)
- Remove vegetation attached to building; power wash brick on front and front sides (6,000 s.f.)
- Repaint brown on front and east side foundation walls (6000sf)
- Provide new EIFS (exterior insulation and finish system) on three exterior walls on gym (4,000 s.f.)
- Replace all exterior windows with insulated single hung units (200) 3.5x6
- Repaint lintels over windows in brick walls (200 ft)
- Replace exterior hollow metal doors on old building (20 3x7)
- Replace all roofing (41,692sf)
- Replace all interior wood doors, hollow metal frames, and hardware (88 3x7)
- Replace interior hollow metal doors and frames – fire rated (20 3x7)
- Provide security hardware for classrooms and offices, locking from inside classroom (63 each)
- Replace old 2x4 ceilings with new ceiling systems (60,000 s.f.)
- Repair walls damaged by water leaks; repaint walls in old building (10,000 s.f.)
- Replace VCT (40,000 s.f.)
- Replace VAT with VCT (12,600 s.f.)

Site Assessment Report - S731001; Feltonville Intermediate

- Remove existing gym floor finish and provide new gymnasium floor (6,000 s.f.)
- Construct new ramp 50" tall, 50ft long in corridor to gymnasium
- Provide new toilet room partitions where old partitions are damaged (4)
- Provide new ADA toilet room partitions and accessories (4 sets)
- Provide new science lab furniture (100lf)
- Repaint rusted underside of stairway risers/treads (200sf)
- Remove and replace stairway handrails and guards with code compliant systems in stairway 1 - 3 stories = 14 stairway/levels for all stairways x 50ft/floor (2 half runs) = 700ft

MECHANICAL

- Replace all lavatories in the building with lower flow fixtures, as the fixtures are original.
- Replace all water closets in the building with lower flow fixtures, as the fixtures are original.
- Replace all urinals in the building with lower flow fixtures, as the fixtures are original.
- Replace the wall hung drinking fountains and integral refrigerated coolers in the corridors and at the restrooms. These units are well beyond their service life and most are NOT accessible type.
- Replace service sinks (janitor sinks) in the building.
- Hire a qualified contractor to perform a detailed examination of the sanitary waste piping using visual inspection and video cameras to locate and replace any damaged piping and to further quantify the extent of potential failures.
- Add automatic sanitizing chemicals to the stainless steel sink in the cafeteria.
- Inspect and replace the original as needed the domestic water piping in the building

ELECTRICAL

- Provide an adequate video surveillance system including camera and Closed Circuit Television (CCTV) for monitoring the system. Cameras should install in the corridors, school entrance.
- Provide lightning protection studies to ascertain adequacy of existing systems.
- Provide speakers on exterior walls to adequately cover the area. Estimated 5 in total.
- Replace existing emergency generator with a 30KW, 120/208V generator along with respective Automatic Transfer Switch. Replace existing emergency distribution panel board.

GROUNDS

- Repave asphalt driveway/delivery and playground area (22,000sf)
- Repair and repaint chain link fence on retaining wall (200sf)
- Repave broken sidewalk (200sf)
- New concrete apron to street, vehicle rated (100sf)
- Reconstruct entrance stairs (12 risers)
- New handrails for entrance stairs (24ft)
- Repair cracked and spalling retaining wall (150sf)
- Provide new handicap ramp and railing system into east entrance (40ft.)

Attributes:

General Attributes:

| | | | |
|----------|-----------------|--------------|--------------|
| Active: | Open | Bldg Lot Tm: | Lot 4 / Tm 2 |
| Status: | Accepted by SDP | Team: | Tm 2 |
| Site ID: | S731001 | | |

Site Condition Summary

The Table below shows the CI and FCI for each major system shown at the UNIFORMAT classification Level II. Note that Systems with lower FCIs require less investment than systems with higher FCIs.


Current Investment Requirement and Condition by Uniformat Classification

| UNIFORMAT Classification | RSLI% | FCI % | Current Repair |
|---------------------------------|----------------|----------------|------------------------|
| A10 - Foundations | 21.00 % | 0.00 % | \$0.00 |
| A20 - Basement Construction | 21.00 % | 0.00 % | \$0.00 |
| B10 - Superstructure | 21.00 % | 1.34 % | \$100,369.76 |
| B20 - Exterior Enclosure | 49.05 % | 29.60 % | \$1,401,351.71 |
| B30 - Roofing | 110.00 % | 89.44 % | \$1,412,608.80 |
| C10 - Interior Construction | 34.48 % | 26.68 % | \$550,002.95 |
| C20 - Stairs | 21.00 % | 199.25 % | \$235,987.70 |
| C30 - Interior Finishes | 90.43 % | 49.44 % | \$1,791,145.24 |
| D10 - Conveying | 14.29 % | 0.00 % | \$0.00 |
| D20 - Plumbing | 115.84 % | 50.80 % | \$871,400.78 |
| D30 - HVAC | 119.44 % | 90.34 % | \$8,441,087.65 |
| D40 - Fire Protection | 105.71 % | 177.49 % | \$1,201,657.51 |
| D50 - Electrical | 80.03 % | 15.07 % | \$743,873.77 |
| E10 - Equipment | 28.99 % | 13.13 % | \$175,634.74 |
| E20 - Furnishings | 32.50 % | 0.00 % | \$0.00 |
| G20 - Site Improvements | 48.22 % | 30.35 % | \$208,116.58 |
| G40 - Site Electrical Utilities | 46.67 % | 0.00 % | \$0.00 |
| Totals: | 68.36 % | 40.14 % | \$17,133,237.19 |

Condition Deficiency Priority

| Facility Name | Gross Area (S.F.) | FCI % | 1 - Response Time (< 2 yr) | 2 - Response Time (2-3 yrs) | 3 - Response Time (3-4 yrs) | 4 - Response Time (4-5 yrs) | 5 - Response Time (> 5 yrs) |
|----------------------------------|-------------------|--------------|----------------------------|-----------------------------|-----------------------------|-----------------------------|-----------------------------|
| B731001;Feltonville Intermediate | 84,000 | 40.57 | \$2,668,083.52 | \$3,951,794.25 | \$7,425,694.28 | \$432,060.47 | \$2,447,488.09 |
| G731001;Grounds | 47,500 | 21.64 | \$56,580.06 | \$73,006.33 | \$78,530.19 | \$0.00 | \$0.00 |
| Total: | | 40.14 | \$2,724,663.58 | \$4,024,800.58 | \$7,504,224.47 | \$432,060.47 | \$2,447,488.09 |

Deficiencies By Priority



Executive Summary

Building condition is evaluated based on the functional systems and elements of a building and organized according to the UNIFORMAT II Elemental Classification. The grouping of these systems and elements and applying a current replacement value to them develops a representative building cost model. Cost Models are developed for similar building types and functions. Systems and their elements are evaluated based on their current replacement values, life cycles, installation dates and next renewal dates. Systems and their elements that are within their useful lives are further evaluated to identify current deficient conditions that may have a significant impact on a system's or element's remaining service life, and to determine if they are beyond their predicted expected life. The system's or element's current replacement value is based on RS Means Commercial Cost Data.

Following are the cost model's system details for this facility. The Replacement Value is the amount needed to replace the property of the same present value. The Current Repair Amount, also known as Condition Needs, represents the budgeted contractor installed costs plus owner's soft costs for the repair, replacement or renewal for a component or system level deficiency. It excludes contributing costs for other components or systems that might also be associated with the corrective actions due to packaging the work. Facility Condition Index (FCI) FCI is an industry-standard measurement of facility condition calculated as the ratio of the costs to correct a facility's deficiencies to the facility's Current Replacement Value. It ranges from 0% (new) to 100% (very poor). Condition Index (CI) is calculated as the sum of a renewable system's Remaining Service Life (RSL) divided by the sum of a system's Replacement Value (both values exclude soft-cost to simplify calculation updates) expressed as a percentage ranging from 100% (new) to 0% (expired).

| | |
|--------------------|-------------------|
| Function: | Elementary School |
| Gross Area (SF): | 84,000 |
| Year Built: | 1936 |
| Last Renovation: | |
| Replacement Value: | \$41,721,754 |
| Repair Cost: | \$16,925,120.61 |
| Total FCI: | 40.57 % |
| Total RSLI: | 68.84 % |



Description:

Attributes:

General Attributes:

| | | | |
|-----------------|---------|----------|-----------------|
| Active: | Open | Bldg ID: | B731001 |
| Sewage Ejector: | No | Status: | Accepted by SDP |
| Site ID: | S731001 | | |

Condition Summary

The Table below shows the CI and FCI for each major building system shown at the UNIFORMAT classification Level II. Note that Systems with lower FCIs require less investment than systems with higher FCIs.

| UNIFORMAT Classification | RSLI % | FCI % | Current Repair Cost |
|-----------------------------|----------------|----------------|------------------------|
| A10 - Foundations | 21.00 % | 0.00 % | \$0.00 |
| A20 - Basement Construction | 21.00 % | 0.00 % | \$0.00 |
| B10 - Superstructure | 21.00 % | 1.34 % | \$100,369.76 |
| B20 - Exterior Enclosure | 49.05 % | 29.60 % | \$1,401,351.71 |
| B30 - Roofing | 110.00 % | 89.44 % | \$1,412,608.80 |
| C10 - Interior Construction | 34.48 % | 26.68 % | \$550,002.95 |
| C20 - Stairs | 21.00 % | 199.25 % | \$235,987.70 |
| C30 - Interior Finishes | 90.43 % | 49.44 % | \$1,791,145.24 |
| D10 - Conveying | 14.29 % | 0.00 % | \$0.00 |
| D20 - Plumbing | 115.84 % | 50.80 % | \$871,400.78 |
| D30 - HVAC | 119.44 % | 90.34 % | \$8,441,087.65 |
| D40 - Fire Protection | 105.71 % | 177.49 % | \$1,201,657.51 |
| D50 - Electrical | 80.03 % | 15.07 % | \$743,873.77 |
| E10 - Equipment | 28.99 % | 13.13 % | \$175,634.74 |
| E20 - Furnishings | 32.50 % | 0.00 % | \$0.00 |
| Totals: | 68.84 % | 40.57 % | \$16,925,120.61 |

Condition Detail

This section of the report contains results of the Facility Condition Assessment. The building is separated into system components based on UNIFORMAT II classification. The columns in the System Listing table below represent the following:

1. System Code: A code that identifies the system.
2. System Description: A brief description of a system present in the building.
3. Unit Price \$: The unit price of the system.
4. UoM: The unit of measure for of the system.
5. Qty: The quantity for the system
6. Life: anticipated service life for the system based on Building Owners and Managers Association (BOMA) recommendations.
7. Year Installed: The date of system installation.
8. Calc Next Renewal Year: The date of system expiration based on the life, NR stands for non renewable.
9. Next Renewal Year: The suggested system expiration date by the assessor based on visual inspection.
10. CI: The Condition Index of the system.
11. FCI: The Facility Condition Index of the system.
12. RSL: Remaining Service Life.
13. eCR: eCOMET Condition Rating (not used).
14. Deficiency \$: The financial investment to repair/replace system.

System Listing

The System Listing table below lists each of the systems organized by their UNIFORMAT II classification. The assessment team was tasked with recording the most recent replacement year of each system, determining the remaining service life based on the theoretical life, and evaluating the condition to confirm the forecast next replacement year. The system listing is the basis for all data contained in the Building Assessment Report.

Additionally, a condition rating (eCR) based on the following guidelines is provided as observed at the time of the assessment.

- Excellent (E) - No noticeable distress or damage. The entire system is free from observable defect.
- Very Good (VG) - Overall no serviceability reduction for the entire system. No degradation of critical components and minor distress and defect noticeable for some but not non critical components within the system.
- Good (G) - Slight or no serviceability reduction for the entire system. There may be noticeable defects for some non critical components and slight noticeable degradation of the critical components.
- Fair (F) - Overall serviceability is degraded but adequate. There may be moderate deterioration for very few of the critical components and few of the non critical components may have severe degradation.
- Marginal (MA) - Overall serviceability and reliability loss. Most if not all of the non critical components suffer from severe degradation and a few of the critical component may have severe degradation.
- Moderate (MO) - Overall a significant serviceability loss. Most if not all the components have severe degradation with the reminder of the component showing visible distress.
- Very Poor (VP) - Overall the system is barely functional. All of the components are severely degraded.
- Non-Functional (NF) - Overall the system does not function with all the components having no serviceability and suffer from severe degradation.

| System Code | System Description | Unit Price \$ | UoM | Qty | Life | Year Installed | Calc Next Renewal Year | Next Renewal Year | RSLI% | FCI% | RSL | eCR | Deficiency \$ | Replacement Value \$ |
|-------------|-------------------------|---------------|------|--------|------|----------------|------------------------|-------------------|----------|----------|-----|-----|----------------|----------------------|
| A1010 | Standard Foundations | \$18.40 | S.F. | 84,000 | 100 | 1936 | 2036 | | 21.00 % | 0.00 % | 21 | | | \$1,545,600 |
| A1030 | Slab on Grade | \$7.73 | S.F. | 84,000 | 100 | 1936 | 2036 | | 21.00 % | 0.00 % | 21 | | | \$649,320 |
| A2010 | Basement Excavation | \$6.55 | S.F. | 84,000 | 100 | 1936 | 2036 | | 21.00 % | 0.00 % | 21 | | | \$550,200 |
| A2020 | Basement Walls | \$12.70 | S.F. | 84,000 | 100 | 1936 | 2036 | | 21.00 % | 0.00 % | 21 | | | \$1,066,800 |
| B1010 | Floor Construction | \$75.10 | S.F. | 84,000 | 100 | 1936 | 2036 | | 21.00 % | 1.59 % | 21 | | \$100,369.76 | \$6,308,400 |
| B1020 | Roof Construction | \$13.88 | S.F. | 84,000 | 100 | 1936 | 2036 | | 21.00 % | 0.00 % | 21 | | | \$1,165,920 |
| B2010 | Exterior Walls | \$36.91 | S.F. | 84,000 | 100 | 1936 | 2036 | | 21.00 % | 9.85 % | 21 | | \$305,413.54 | \$3,100,440 |
| B2020 | Exterior Windows | \$18.01 | S.F. | 84,000 | 40 | 1936 | 1976 | 2057 | 105.00 % | 60.40 % | 42 | | \$913,791.75 | \$1,512,840 |
| B2030 | Exterior Doors | \$1.45 | S.F. | 84,000 | 25 | 1936 | 1961 | 2032 | 68.00 % | 149.55 % | 17 | | \$182,146.42 | \$121,800 |
| B3010105 | Built-Up | \$37.76 | S.F. | 41,692 | 20 | 1936 | 1956 | 2037 | 110.00 % | 89.73 % | 22 | | \$1,412,608.80 | \$1,574,290 |
| B3010120 | Single Ply Membrane | \$38.73 | S.F. | | 20 | | | | 0.00 % | 0.00 % | | | | \$0 |
| B3010130 | Preformed Metal Roofing | \$54.22 | S.F. | | 30 | | | | 0.00 % | 0.00 % | | | | \$0 |
| B3010140 | Shingle & Tile | \$38.73 | S.F. | | 25 | | | | 0.00 % | 0.00 % | | | | \$0 |
| B3020 | Roof Openings | \$0.06 | S.F. | 84,000 | 20 | 1936 | 1956 | 2037 | 110.00 % | 0.00 % | 22 | | | \$5,040 |
| C1010 | Partitions | \$17.91 | S.F. | 84,000 | 100 | 1936 | 2036 | | 21.00 % | 0.00 % | 21 | | | \$1,504,440 |
| C1020 | Interior Doors | \$3.51 | S.F. | 84,000 | 40 | 1936 | 1976 | 2057 | 105.00 % | 181.73 % | 42 | | \$535,825.91 | \$294,840 |
| C1030 | Fittings | \$3.12 | S.F. | 84,000 | 40 | 1936 | 1976 | 2028 | 32.50 % | 5.41 % | 13 | | \$14,177.04 | \$262,080 |
| C2010 | Stair Construction | \$1.41 | S.F. | 84,000 | 100 | 1936 | 2036 | | 21.00 % | 199.25 % | 21 | | \$235,987.70 | \$118,440 |

Site Assessment Report - B731001;Feltonville Intermediate

| System Code | System Description | Unit Price \$ | UoM | Qty | Life | Year Installed | Calc Next Renewal Year | Next Renewal Year | RSLI% | FCI% | RSL | eCR | Deficiency \$ | Replacement Value \$ | |
|--------------|---------------------------------|---------------|------|--------|------|----------------|------------------------|-------------------|----------|----------------|----------------|-----|----------------|------------------------|---------------------|
| C3010230 | Paint & Covering | \$13.21 | S.F. | 84,000 | 10 | 1936 | 1946 | 2020 | 50.00 % | 5.03 % | 5 | | \$55,819.23 | \$1,109,640 | |
| C3010231 | Vinyl Wall Covering | \$0.97 | S.F. | | 15 | | | | 0.00 % | 0.00 % | | | | \$0 | |
| C3010232 | Wall Tile | \$2.63 | S.F. | | 30 | | | | 0.00 % | 0.00 % | | | | \$0 | |
| C3020411 | Carpet | \$7.30 | S.F. | | 10 | | | | 0.00 % | 0.00 % | | | | \$0 | |
| C3020412 | Terrazzo & Tile | \$75.52 | S.F. | | 50 | | | | 0.00 % | 0.00 % | | | | \$0 | |
| C3020413 | Vinyl Flooring | \$9.68 | S.F. | 75,600 | 20 | 1936 | 1956 | 2037 | 110.00 % | 106.81 % | 22 | | \$781,668.23 | \$731,808 | |
| C3020414 | Wood Flooring | \$22.27 | S.F. | | 25 | | | | 0.00 % | 0.00 % | | | | \$0 | |
| C3020415 | Concrete Floor Finishes | \$2.34 | S.F. | 8,400 | 50 | 1936 | 1986 | 2050 | 70.00 % | 247.82 % | 35 | | \$48,711.96 | \$19,656 | |
| C3030 | Ceiling Finishes | \$20.97 | S.F. | 84,000 | 25 | 1936 | 1961 | 2042 | 108.00 % | 51.37 % | 27 | | \$904,945.82 | \$1,761,480 | |
| D1010 | Elevators and Lifts | \$1.53 | S.F. | 84,000 | 35 | 1936 | 1971 | 2020 | 14.29 % | 0.00 % | 5 | | | \$128,520 | |
| D2010 | Plumbing Fixtures | \$13.52 | S.F. | 84,000 | 35 | 1936 | 1971 | 2055 | 114.29 % | 2.96 % | 40 | | \$33,659.61 | \$1,135,680 | |
| D2020 | Domestic Water Distribution | \$1.68 | S.F. | 84,000 | 25 | 1936 | 1961 | 2045 | 120.00 % | 301.63 % | 30 | | \$425,658.17 | \$141,120 | |
| D2030 | Sanitary Waste | \$2.90 | S.F. | 84,000 | 25 | 1936 | 1961 | 2045 | 120.00 % | 169.16 % | 30 | | \$412,083.00 | \$243,600 | |
| D2040 | Rain Water Drainage | \$2.32 | S.F. | 84,000 | 30 | 1936 | 1966 | 2050 | 116.67 % | 0.00 % | 35 | | | \$194,880 | |
| D3020 | Heat Generating Systems | \$18.67 | S.F. | 84,000 | 35 | 1936 | 1971 | 2055 | 114.29 % | 0.00 % | 40 | | | \$1,568,280 | |
| D3030 | Cooling Generating Systems | \$24.48 | S.F. | 84,000 | 30 | 1936 | 1966 | 2050 | 116.67 % | 121.19 % | 35 | | \$2,492,130.43 | \$2,056,320 | |
| D3040 | Distribution Systems | \$42.99 | S.F. | 84,000 | 25 | 1936 | 1961 | 2045 | 120.00 % | 164.74 % | 30 | | \$5,948,957.22 | \$3,611,160 | |
| D3050 | Terminal & Package Units | \$11.60 | S.F. | 84,000 | 20 | 1936 | 1956 | 2040 | 125.00 % | 0.00 % | 25 | | | \$974,400 | |
| D3060 | Controls & Instrumentation | \$13.50 | S.F. | 84,000 | 20 | 1936 | 1956 | 2040 | 125.00 % | 0.00 % | 25 | | | \$1,134,000 | |
| D4010 | Sprinklers | \$7.05 | S.F. | 84,000 | 35 | | | 2052 | 105.71 % | 202.91 % | 37 | | \$1,201,657.51 | \$592,200 | |
| D4020 | Standpipes | \$1.01 | S.F. | 84,000 | 35 | | | 2052 | 105.71 % | 0.00 % | 37 | | | \$84,840 | |
| D5010 | Electrical Service/Distribution | \$9.70 | S.F. | 84,000 | 30 | 1936 | 1966 | 2025 | 33.33 % | 0.00 % | 10 | | | \$814,800 | |
| D5020 | Lighting and Branch Wiring | \$34.68 | S.F. | 84,000 | 20 | 1936 | 1956 | 2035 | 100.00 % | 0.00 % | 20 | | | \$2,913,120 | |
| D5030 | Communications and Security | \$12.99 | S.F. | 84,000 | 15 | 1936 | 1951 | 2025 | 66.67 % | 59.37 % | 10 | | \$647,863.43 | \$1,091,160 | |
| D5090 | Other Electrical Systems | \$1.41 | S.F. | 84,000 | 30 | 1936 | 1966 | 2025 | 33.33 % | 81.06 % | 10 | | \$96,010.34 | \$118,440 | |
| E1020 | Institutional Equipment | \$4.82 | S.F. | 84,000 | 35 | 1936 | 1971 | 2037 | 62.86 % | 43.38 % | 22 | | \$175,634.74 | \$404,880 | |
| E1090 | Other Equipment | \$11.10 | S.F. | 84,000 | 35 | 1936 | 1971 | 2020 | 14.29 % | 0.00 % | 5 | | | \$932,400 | |
| E2010 | Fixed Furnishings | \$2.13 | S.F. | 84,000 | 40 | 1936 | 1976 | 2028 | 32.50 % | 0.00 % | 13 | | | \$178,920 | |
| Total | | | | | | | | | | 68.84 % | 40.57 % | | | \$16,925,120.61 | \$41,721,754 |

System Notes

The facility description in the site executive summary contains an overview of each system. The notes listed below provide additional information on select systems found within the facility.

| | |
|-----------------------------------------------------------------------------------------------------------------|--------------------------------|
| System: C3010 - Wall Finishes | This system contains no images |
| Note: Painted 95% Glazed brick/block 5% | |
| System: C3020 - Floor Finishes | This system contains no images |
| Note: Concrete – 8,400 10% VCT - 63,000 75% VAT 12,600 15% | |
| System: C3030 - Ceiling Finishes | This system contains no images |
| Note: painted concrete, plaster, or wood deck 8,400 10% acoustical tile 75,600 90% (replace 60,000sf) | |
| System: D5010 - Electrical Service/Distribution | This system contains no images |
| Note: 1-225KVA, 480VAC to 208/120VAC | |

Renewal Schedule

eCOMET forecasts future Capital Renewal funding needed to address expiring systems based on the Next Renewal year found in the Cost Models. A 3% annual inflation factor is applied to the costs for systems expiring in future years. The table below reflects recommended Capital Renewal funding needs over the next 10 years. Note: Cells with a zero value indicate systems for which renewal is not scheduled in that year.

Inflation Rate: 3%

| System | Current Deficiencies | 2016 | 2017 | 2018 | 2019 | 2020 | 2021 | 2022 | 2023 | 2024 | 2025 | Total |
|------------------------------------|----------------------|------|------|------|------|-------------|------|------|------|------|-------------|--------------|
| Total: | \$16,925,121 | \$0 | \$0 | \$0 | \$0 | \$2,767,901 | \$0 | \$0 | \$0 | \$0 | \$2,992,687 | \$22,685,709 |
| * A - Substructure | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| A10 - Foundations | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| A1010 - Standard Foundations | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| A1030 - Slab on Grade | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| A20 - Basement Construction | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| A2010 - Basement Excavation | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| A2020 - Basement Walls | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| B - Shell | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| B10 - Superstructure | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| B1010 - Floor Construction | \$100,370 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$100,370 |
| B1020 - Roof Construction | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| B20 - Exterior Enclosure | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| B2010 - Exterior Walls | \$305,414 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$305,414 |
| B2020 - Exterior Windows | \$913,792 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$913,792 |
| B2030 - Exterior Doors | \$182,146 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$182,146 |
| B30 - Roofing | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| B3010 - Roof Coverings | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| B3010105 - Built-Up | \$1,412,609 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$1,412,609 |
| B3010120 - Single Ply Membrane | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| B3010130 - Preformed Metal Roofing | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| B3010140 - Shingle & Tile | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| B3020 - Roof Openings | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| C - Interiors | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| C10 - Interior Construction | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| C1010 - Partitions | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |

Site Assessment Report - B731001;Feltonville Intermediate

| | | | | | | | | | | | | | | |
|-------------------------------------|-------------|-----|-----|-----|-----|-----|-------------|-----|-----|-----|-----|-----|-----|-------------|
| C1020 - Interior Doors | \$535,826 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$535,826 |
| C1030 - Fittings | \$14,177 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$14,177 |
| C20 - Stairs | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| C2010 - Stair Construction | \$235,988 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$235,988 |
| C30 - Interior Finishes | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| C3010 - Wall Finishes | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| C3010230 - Paint & Covering | \$55,819 | \$0 | \$0 | \$0 | \$0 | \$0 | \$1,415,015 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$1,470,834 |
| C3010231 - Vinyl Wall Covering | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| C3010232 - Wall Tile | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| C3020 - Floor Finishes | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| C3020411 - Carpet | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| C3020412 - Terrazzo & Tile | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| C3020413 - Vinyl Flooring | \$781,668 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$781,668 |
| C3020414 - Wood Flooring | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| C3020415 - Concrete Floor Finishes | \$48,712 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$48,712 |
| C3030 - Ceiling Finishes | \$904,946 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$904,946 |
| D - Services | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| D10 - Conveying | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| D1010 - Elevators and Lifts | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$163,889 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$163,889 |
| D20 - Plumbing | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| D2010 - Plumbing Fixtures | \$33,660 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$33,660 |
| D2020 - Domestic Water Distribution | \$425,658 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$425,658 |
| D2030 - Sanitary Waste | \$412,083 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$412,083 |
| D2040 - Rain Water Drainage | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| D30 - HVAC | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| D3020 - Heat Generating Systems | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| D3030 - Cooling Generating Systems | \$2,492,130 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$2,492,130 |
| D3040 - Distribution Systems | \$5,948,957 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$5,948,957 |
| D3050 - Terminal & Package Units | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| D3060 - Controls & Instrumentation | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| D40 - Fire Protection | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| D4010 - Sprinklers | \$1,201,658 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$1,201,658 |
| D4020 - Standpipes | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |


Site Assessment Report - B731001;Feltonville Intermediate

| | | | | | | | | | | | | | |
|------------------------------------------------|-----------|-----|-----|-----|-----|-------------|-----|-----|-----|-----|-------------|-------------|-------------|
| D50 - Electrical | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| D5010 - Electrical Service/Distribution | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$1,204,525 | \$1,204,525 | \$0 |
| D5020 - Lighting and Branch Wiring | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| D5030 - Communications and Security | \$647,863 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$1,613,071 | \$2,260,934 | \$0 |
| D5090 - Other Electrical Systems | \$96,010 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$175,091 | \$271,101 | \$0 |
| E - Equipment & Furnishings | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| E10 - Equipment | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| E1020 - Institutional Equipment | \$175,635 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$175,635 |
| E1090 - Other Equipment | \$0 | \$0 | \$0 | \$0 | \$0 | \$1,188,998 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$1,188,998 |
| E20 - Furnishings | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| E2010 - Fixed Furnishings | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |

* Indicates non-renewable system

Forecasted Sustainment Requirement


The following chart shows the current building deficiencies and forecasting sustainment requirements over the next ten years.



10 Year FCI Forecast by Investment Scenario

The chart below illustrates the effect of various investment levels on the building FCI for the next 10 years. The levels of investment shown below include:


- Current FCI: a variable investment amount based on renewing expired systems to maintain the current FCI for the building
- 2% Investment: an annual investment of 2% of the replacement value of the building, escalated for inflation
- 4% Investment: an annual investment of 4% of the replacement value of the building, escalated for inflation



| Year | Investment Amount Current FCI - 40.57% | 2% Investment | | 4% Investment | |
|---------------|-------------------------------------------|-----------------------|---------|------------------------|---------|
| | | Amount | FCI | Amount | FCI |
| 2016 | \$0 | \$859,468.00 | 38.57 % | \$1,718,936.00 | 36.57 % |
| 2017 | \$7,652,348 | \$885,252.00 | 53.86 % | \$1,770,504.00 | 49.86 % |
| 2018 | \$0 | \$911,810.00 | 51.86 % | \$1,823,619.00 | 45.86 % |
| 2019 | \$0 | \$939,164.00 | 49.86 % | \$1,878,328.00 | 41.86 % |
| 2020 | \$16,870,916 | \$967,339.00 | 82.74 % | \$1,934,678.00 | 72.74 % |
| 2021 | \$0 | \$996,359.00 | 80.74 % | \$1,992,718.00 | 68.74 % |
| 2022 | \$0 | \$1,026,250.00 | 78.74 % | \$2,052,500.00 | 64.74 % |
| 2023 | \$0 | \$1,057,037.00 | 76.74 % | \$2,114,075.00 | 60.74 % |
| 2024 | \$0 | \$1,088,749.00 | 74.74 % | \$2,177,497.00 | 56.74 % |
| 2025 | \$2,992,687 | \$1,121,411.00 | 78.07 % | \$2,242,822.00 | 58.07 % |
| Total: | \$27,515,950 | \$9,852,839.00 | | \$19,705,677.00 | |

Deficiency Summary by System


Current deficiencies included assemblies that have reached or exceeded their design life or components of the assemblies that are in need of repair. Assemblies that have reached their design life are identified as current deficiencies and assigned the distress 'Beyond Useful Life'. The following chart lists all current deficiencies associated with this facility.



Budget Estimate Total: \$16,925,120.61

Deficiency Summary by Priority

The following chart shows the total repair costs broken down by priority. Assessors assigned deficiencies within eCOMET to one of the following priority categories:



Budget Estimate Total: \$16,925,120.61


Deficiency By Priority Investment Table

The table below shows the current investment cost grouped by deficiency priority and building system.

| System Code | System Description | 1 - Response Time (< 2 yr) | 2 - Response Time (2-3 yrs) | 3 - Response Time (3-4 yrs) | 4 - Response Time (4-5 yrs) | 5 - Response Time (> 5 yrs) | Total |
|-------------|-----------------------------|----------------------------|-----------------------------|-----------------------------|-----------------------------|-----------------------------|------------------------|
| B1010 | Floor Construction | \$0.00 | \$0.00 | \$100,369.76 | \$0.00 | \$0.00 | \$100,369.76 |
| B2010 | Exterior Walls | \$0.00 | \$305,413.54 | \$0.00 | \$0.00 | \$0.00 | \$305,413.54 |
| B2020 | Exterior Windows | \$0.00 | \$913,791.75 | \$0.00 | \$0.00 | \$0.00 | \$913,791.75 |
| B2030 | Exterior Doors | \$0.00 | \$182,146.42 | \$0.00 | \$0.00 | \$0.00 | \$182,146.42 |
| B3010105 | Built-Up | \$1,412,608.80 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$1,412,608.80 |
| C1020 | Interior Doors | \$0.00 | \$535,825.91 | \$0.00 | \$0.00 | \$0.00 | \$535,825.91 |
| C1030 | Fittings | \$0.00 | \$14,177.04 | \$0.00 | \$0.00 | \$0.00 | \$14,177.04 |
| C2010 | Stair Construction | \$235,987.70 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$235,987.70 |
| C3010230 | Paint & Covering | \$0.00 | \$55,819.23 | \$0.00 | \$0.00 | \$0.00 | \$55,819.23 |
| C3020413 | Vinyl Flooring | \$0.00 | \$781,668.23 | \$0.00 | \$0.00 | \$0.00 | \$781,668.23 |
| C3020415 | Concrete Floor Finishes | \$0.00 | \$48,711.96 | \$0.00 | \$0.00 | \$0.00 | \$48,711.96 |
| C3030 | Ceiling Finishes | \$0.00 | \$904,945.82 | \$0.00 | \$0.00 | \$0.00 | \$904,945.82 |
| D2010 | Plumbing Fixtures | \$0.00 | \$33,659.61 | \$0.00 | \$0.00 | \$0.00 | \$33,659.61 |
| D2020 | Domestic Water Distribution | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$425,658.17 | \$425,658.17 |
| D2030 | Sanitary Waste | \$0.00 | \$0.00 | \$412,083.00 | \$0.00 | \$0.00 | \$412,083.00 |
| D3030 | Cooling Generating Systems | \$0.00 | \$0.00 | \$2,060,069.96 | \$432,060.47 | \$0.00 | \$2,492,130.43 |
| D3040 | Distribution Systems | \$275,613.25 | \$0.00 | \$4,853,171.56 | \$0.00 | \$820,172.41 | \$5,948,957.22 |
| D4010 | Sprinklers | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$1,201,657.51 | \$1,201,657.51 |
| D5030 | Communications and Security | \$647,863.43 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$647,863.43 |
| D5090 | Other Electrical Systems | \$96,010.34 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$96,010.34 |
| E1020 | Institutional Equipment | \$0.00 | \$175,634.74 | \$0.00 | \$0.00 | \$0.00 | \$175,634.74 |
| | Total: | \$2,668,083.52 | \$3,951,794.25 | \$7,425,694.28 | \$432,060.47 | \$2,447,488.09 | \$16,925,120.61 |

Deficiency Summary by Category

The following chart shows the total repair costs broken down by deficiency categories. Assessors assigned deficiencies to one of the following categories:



Deficiency Details by Priority

The deficiency detail notes listed below provide additional information on identified deficiencies found within the facility.

Priority 1 - Response Time (< 2 yr):

System: B3010105 - Built-Up



Location: roof

Distress: Failing

Category: 3 - Operations / Maint.

Priority: 1 - Response Time (< 2 yr)

Correction: Remove and Replace Built Up Roof

Qty: 41,692.00

Unit of Measure: S.F.

Estimate: \$1,412,608.80

Assessor Name: Craig Anding

Date Created: 01/19/2016

Notes: Replace all roofing (41,692sf)

System: C2010 - Stair Construction



Location: stairways

Distress: Building / MEP Codes

Category: 2 - Code Compliance

Priority: 1 - Response Time (< 2 yr)

Correction: Replace inadequate or install proper stair railing
- select appropriate material

Qty: 700.00

Unit of Measure: L.F.

Estimate: \$235,987.70

Assessor Name: Craig Anding

Date Created: 01/19/2016

Notes: Remove and replace stairway handrails and guards with code compliant systems in stairway 1 - 3 stories = 14 stairway/levels
for all stairways x 50ft/floor (2 half runs) = 700ft

System: D3040 - Distribution Systems



Location: Throughout the school

Distress: Beyond Service Life

Category: 3 - Operations / Maint.

Priority: 1 - Response Time (< 2 yr)

Correction: Conduct a steam trap survey and replace failed units.

Qty: 84,000.00

Unit of Measure: S.F.

Estimate: \$275,613.25

Assessor Name: Craig Anding

Date Created: 02/09/2016

Notes: Conduct a steam trap survey to identify and replace failed traps passing live steam into the condensate piping system.

System: D5030 - Communications and Security



Location: Entire Building

Distress: Security Issue

Category: 1 - Health & Safety

Priority: 1 - Response Time (< 2 yr)

Correction: Add/Replace Video Surveillance System

Qty: 1.00

Unit of Measure: Ea.

Estimate: \$631,280.12

Assessor Name: Craig Anding

Date Created: 11/24/2015

Notes: Provide an adequate video surveillance system including camera and Closed Circuit Television (CCTV) for monitoring the system. Cameras should install in the corridors, school entrance.

System: D5030 - Communications and Security



Location: Exterior Building

Distress: Inadequate

Category: 4 - Capital Improvement

Priority: 1 - Response Time (< 2 yr)

Correction: Add/Replace Paging System

Qty: 1.00

Unit of Measure: Ea.

Estimate: \$16,583.31

Assessor Name: Craig Anding

Date Created: 11/24/2015

Notes: Provide speakers on exterior walls to adequately cover the area. Estimated 5 in total.

System: D5090 - Other Electrical Systems



Location: Mechanical Room

Distress: Life Safety / NFPA / PFD

Category: 1 - Health & Safety

Priority: 1 - Response Time (< 2 yr)

Correction: Replace standby generator system

Qty: 1.00

Unit of Measure: Ea.

Estimate: \$73,428.23

Assessor Name: Craig Anding

Date Created: 12/24/2015

Notes: Replace existing emergency generator with a 30KW, 120/208V generator along with respective Automatic Transfer Switch. Replace existing emergency distribution panel board.

System: D5090 - Other Electrical Systems



Location: Roof

Distress: Life Safety / NFPA / PFD

Category: 1 - Health & Safety

Priority: 1 - Response Time (< 2 yr)

Correction: Repair Lightning Protection System

Qty: 1.00

Unit of Measure: Job

Estimate: \$22,582.11

Assessor Name: Craig Anding

Date Created: 11/24/2015

Notes: Provide lightning protection studies to ascertain adequacy of existing systems.

Priority 2 - Response Time (2-3 yrs):

System: B2010 - Exterior Walls



Location: exterior gymnasium walls

Distress: Building Envelope Integrity

Category: 3 - Operations / Maint.

Priority: 2 - Response Time (2-3 yrs)

Correction: Remove and replace exterior insulating finish system (EIFS)

Qty: 4,000.00

Unit of Measure: S.F.

Estimate: \$186,341.82

Assessor Name: Craig Anding

Date Created: 01/19/2016

Notes: Provide new EIFS (exterior insulation and finish system) on three exterior walls on gym (4,000sf)

System: B2010 - Exterior Walls



Location: first floor front and east side walls

Distress: Appearance

Category: 3 - Operations / Maint.

Priority: 2 - Response Time (2-3 yrs)

Correction: Repaint exterior walls - CMU

Qty: 6,000.00

Unit of Measure: S.F.

Estimate: \$52,634.07

Assessor Name: Craig Anding

Date Created: 01/19/2016

Notes: Repaint brown foundation up to first floor windows (6000sf)

System: B2010 - Exterior Walls



Location: front and side elevations

Distress: Failing

Category: 3 - Operations / Maint.

Priority: 2 - Response Time (2-3 yrs)

Correction: Exterior plaster or stucco repair and refinishing
- based on SF of wall surface

Qty: 2,500.00

Unit of Measure: S.F.

Estimate: \$35,754.39

Assessor Name: Craig Anding

Date Created: 01/19/2016

Notes: Replaster front and side exterior cement pilasters and beams (2,500sf)

System: B2010 - Exterior Walls



Location: exterior walls, chimney

Distress: Building Envelope Integrity

Category: 3 - Operations / Maint.

Priority: 2 - Response Time (2-3 yrs)

Correction: Repair cracks in masonry - replace missing mortar and repoint - SF of wall area

Qty: 700.00

Unit of Measure: S.F.

Estimate: \$22,602.63

Assessor Name: Craig Anding

Date Created: 01/19/2016

Notes: Repoint brick on chimney, penthouse and other building walls (700sf)

System: B2010 - Exterior Walls



Location: exterior walls front and side brick

Distress: Appearance

Category: 3 - Operations / Maint.

Priority: 2 - Response Time (2-3 yrs)

Correction: Sooty and dirty walls - powerwash

Qty: 6,000.00

Unit of Measure: S.F.

Estimate: \$6,562.41

Assessor Name: Craig Anding

Date Created: 01/19/2016

Notes: Remove vegetation attached to building; powerwash brick on front and front sides (6,000sf)

System: B2010 - Exterior Walls



Location: lintels in brick walls

Distress: Damaged

Category: 3 - Operations / Maint.

Priority: 2 - Response Time (2-3 yrs)

Correction: Prepare and paint exterior steel beams or steel surfaces

Qty: 200.00

Unit of Measure: S.F.

Estimate: \$1,518.22

Assessor Name: Craig Anding

Date Created: 01/19/2016

Notes: Repaint lintels over windows in brick walls (200 sf)

System: B2020 - Exterior Windows



Location: exterior windows

Distress: Failing

Category: 3 - Operations / Maint.

Priority: 2 - Response Time (2-3 yrs)

Correction: Remove and replace aluminum windows - pick the appropriate size and style and insert the number of units

Qty: 200.00

Unit of Measure: Ea.

Estimate: \$913,791.75

Assessor Name: Craig Anding

Date Created: 01/19/2016

Notes: Replace all exterior windows with insulated single hung units (200)3.5x6

System: B2030 - Exterior Doors



Location: exterior doors

Distress: Failing

Category: 3 - Operations / Maint.

Priority: 2 - Response Time (2-3 yrs)

Correction: Remove and replace exterior doors - per leaf

Qty: 20.00

Unit of Measure: Ea.

Estimate: \$182,146.42

Assessor Name: Craig Anding

Date Created: 01/19/2016

Notes: Replace exterior hollow metal doors on old building (20 3x7)

System: C1020 - Interior Doors



Location: interior doors

Distress: Damaged

Category: 3 - Operations / Maint.

Priority: 2 - Response Time (2-3 yrs)

Correction: Remove and replace interior doors - wood doors with hollow metal frames - per leaf

Qty: 88.00

Unit of Measure: Ea.

Estimate: \$419,811.67

Assessor Name: Craig Anding

Date Created: 01/19/2016

Notes: Replace all interior wood doors, hollow metal frames, and hardware (88 3x7)

System: C1020 - Interior Doors



Location: interior doors

Distress: Damaged

Category: 3 - Operations / Maint.

Priority: 2 - Response Time (2-3 yrs)

Correction: Remove and replace hollow metal frames and doors

Qty: 20.00

Unit of Measure: Ea.

Estimate: \$101,559.74

Assessor Name: Craig Anding

Date Created: 01/19/2016

Notes: Replace interior hollow metal doors and frames – fire rated (20 3x7)

System: C1020 - Interior Doors



Location: corridor doors to classrooms and offices

Distress: Security Issue

Category: 1 - Health & Safety

Priority: 2 - Response Time (2-3 yrs)

Correction: Provide security hardware for classroom and office doors

Qty: 63.00

Unit of Measure: Ea.

Estimate: \$14,454.50

Assessor Name: Craig Anding

Date Created: 01/19/2016

Notes: Provide security hardware for classrooms and offices, locking from inside classroom (63 each)

System: C1030 - Fittings



Location: toilet rooms

Distress: Damaged

Category: 3 - Operations / Maint.

Priority: 2 - Response Time (2-3 yrs)

Correction: Remove and replace toilet partitions

Qty: 4.00

Unit of Measure: Ea.

Estimate: \$10,265.62

Assessor Name: Craig Anding

Date Created: 01/19/2016

Notes: Provide new toilet room partitions where old partitions are damaged (4)

System: C1030 - Fittings



Location: toilet rooms

Distress: Accessibility

Category: 2 - Code Compliance

Priority: 2 - Response Time (2-3 yrs)

Correction: Remove and replace damaged toilet partitions - handicap units

Qty: 4.00

Unit of Measure: Ea.

Estimate: \$3,911.42

Assessor Name: Craig Anding

Date Created: 01/19/2016

Notes: Provide new ADA toilet room partitions and accessories (4 sets)

System: C3010230 - Paint & Covering



Location: walls, water damaged

Distress: Appearance

Category: 3 - Operations / Maint.

Priority: 2 - Response Time (2-3 yrs)

Correction: Repair substrate and repaint interior walls - SF of wall surface

Qty: 10,000.00

Unit of Measure: S.F.


Estimate: \$54,105.81

Assessor Name: Craig Anding

Date Created: 01/19/2016

Notes: Repair walls damaged by water leaks; repaint walls in old building (10,000sf)

System: C3010230 - Paint & Covering



Location: stairways

Distress: Failing

Category: 3 - Operations / Maint.

Priority: 2 - Response Time (2-3 yrs)

Correction: Repair substrate and repaint interior walls - SF of wall surface

Qty: 200.00

Unit of Measure: S.F.

Estimate: \$1,713.42

Assessor Name: Craig Anding

Date Created: 01/19/2016

Notes: Repaint rusted underside of stairway risers/treads (200sf)

System: C3020413 - Vinyl Flooring



Location: floors

Distress: Damaged

Category: 3 - Operations / Maint.

Priority: 2 - Response Time (2-3 yrs)

Correction: Remove and replace VCT

Qty: 40,000.00

Unit of Measure: S.F.

Estimate: \$480,701.27

Assessor Name: Craig Anding

Date Created: 01/19/2016

Notes: Replace VCT (40,000sf)

System: C3020413 - Vinyl Flooring



Location: floors - VAT

Distress: Health Hazard / Risk

Category: 1 - Health & Safety

Priority: 2 - Response Time (2-3 yrs)

Correction: Remove VAT and replace with VCT - SF of area

Qty: 12,600.00

Unit of Measure: S.F.

Estimate: \$191,100.02

Assessor Name: Craig Anding

Date Created: 01/19/2016

Notes: Replace VAT with VCT (12,600sf)

System: C3020413 - Vinyl Flooring



Location: gym floor

Distress: Damaged

Category: 3 - Operations / Maint.

Priority: 2 - Response Time (2-3 yrs)

Correction: Remove and replace vinyl sheet flooring

Qty: 6,000.00

Unit of Measure: S.F.

Estimate: \$109,866.94

Assessor Name: Craig Anding

Date Created: 01/19/2016

Notes: Remove existing gym floor finish and provide new gymnasium floor (6,000sf)

System: C3020415 - Concrete Floor Finishes



Location: mech rooms, toilet rooms, stairways

Distress: Appearance

Category: 3 - Operations / Maint.

Priority: 2 - Response Time (2-3 yrs)

Correction: Prepare and repaint concrete floor

Qty: 8,400.00

Unit of Measure: S.F.

Estimate: \$48,711.96

Assessor Name: Craig Anding

Date Created: 01/19/2016

Notes: Strip, clean and reseal/repaint concrete floors in mechanical rooms, toilet rooms and stairways. (8,400sf)

System: C3030 - Ceiling Finishes



Location: ceilings

Distress: Failing

Category: 3 - Operations / Maint.

Priority: 2 - Response Time (2-3 yrs)

Correction: Remove and replace suspended acoustic ceilings - lighting not included

Qty: 60,000.00

Unit of Measure: S.F.

Estimate: \$904,945.82

Assessor Name: Craig Anding

Date Created: 01/19/2016

Notes: Replace old 2x4 ceilings with new ceiling systems (60,000sf)

System: D2010 - Plumbing Fixtures



Location: Throughout the school

Distress: Beyond Service Life

Category: 3 - Operations / Maint.

Priority: 2 - Response Time (2-3 yrs)

Correction: Remove and replace or replace water closet - quantify additional units

Qty: 1.00

Unit of Measure: Ea.

Estimate: \$7,462.15

Assessor Name: Craig Anding

Date Created: 02/09/2016

Notes: Replace all water closets in the building with lower flow fixtures, as the fixtures are original.

System: D2010 - Plumbing Fixtures



Location: Throughout the school

Distress: Beyond Service Life

Category: 3 - Operations / Maint.

Priority: 2 - Response Time (2-3 yrs)

Correction: Remove and replace or replace water closet - quantify additional units

Qty: 1.00

Unit of Measure: Ea.


Estimate: \$7,462.15

Assessor Name: Craig Anding

Date Created: 02/09/2016

Notes: Replace all urinals in the building with lower flow fixtures, as the fixtures are original.

System: D2010 - Plumbing Fixtures



Location: Throughout the school

Distress: Beyond Service Life

Category: 3 - Operations / Maint.

Priority: 2 - Response Time (2-3 yrs)

Correction: Remove and replace or replace water closet - quantify additional units

Qty: 1.00

Unit of Measure: Ea.

Estimate: \$7,462.15

Assessor Name: Craig Anding

Date Created: 02/09/2016

Notes: Replace the wall hung drinking fountains and integral refrigerated coolers in the corridors and at the restrooms. These units are well beyond their service life and most are NOT accessible type.

System: D2010 - Plumbing Fixtures



Location: Throughout the school

Distress: Beyond Service Life

Category: 3 - Operations / Maint.

Priority: 2 - Response Time (2-3 yrs)

Correction: Remove and replace or replace water closet - quantify additional units

Qty: 1.00

Unit of Measure: Ea.

Estimate: \$7,462.15

Assessor Name: Craig Anding

Date Created: 02/09/2016

Notes: Replace service sinks (janitor sinks) in the building

System: D2010 - Plumbing Fixtures



Location: Throughout the school

Distress: Beyond Service Life

Category: 3 - Operations / Maint.

Priority: 2 - Response Time (2-3 yrs)

Correction: Remove and replace or replace lavatory - quantify accessible if required

Qty: 1.00

Unit of Measure: Ea.

Estimate: \$3,811.01

Assessor Name: Craig Anding

Date Created: 02/09/2016

Notes: Replace all lavatories in the building with lower flow fixtures, as the fixtures are original

System: E1020 - Institutional Equipment



Location: science rooms

Distress: Failing

Category: 3 - Operations / Maint.

Priority: 2 - Response Time (2-3 yrs)

Correction: Remove and replace lab base cabinets and countertops - per LF - add sinks in plumbing fixtures if required

Qty: 100.00

Unit of Measure: L.F.

Estimate: \$175,634.74

Assessor Name: Craig Anding

Date Created: 01/19/2016

Notes: Provide new science lab furniture (100lf)

Priority 3 - Response Time (3-4 yrs):

System: B1010 - Floor Construction



Location: ramp in corridor to gym

Distress: Accessibility

Category: 2 - Code Compliance

Priority: 3 - Response Time (3-4 yrs)

Correction: Install interior handicap ramp - per LF 5' wide - insert the LF in the quantity

Qty: 50.00

Unit of Measure: L.F.

Estimate: \$100,369.76

Assessor Name: Craig Anding

Date Created: 01/19/2016

Notes: Construct new ramp 50" tall, 50ft long in corridor to gymnasium

System: D2030 - Sanitary Waste



Location: Throughout the school

Distress: Beyond Service Life

Category: 3 - Operations / Maint.

Priority: 3 - Response Time (3-4 yrs)

Correction: Inspect sanitary waste piping and replace damaged sections. (+50KSF)

Qty: 84,000.00

Unit of Measure: S.F.

Estimate: \$412,083.00

Assessor Name: Craig Anding

Date Created: 02/09/2016

Notes: Hire a qualified contractor to perform a detailed examination of the sanitary waste piping using visual inspection and video cameras to locate and replace any damaged piping and to further quantify the extent of potential failures

System: D3030 - Cooling Generating Systems



Location: Chiller mechanical equipment room

Distress: Beyond Service Life

Category: 3 - Operations / Maint.

Priority: 3 - Response Time (3-4 yrs)

Correction: Replace cooling tower, ID, galv. (250 tons)

Qty: 2.00

Unit of Measure: Ea.

Estimate: \$1,204,670.00

Assessor Name: Craig Anding

Date Created: 02/09/2016

Notes: Replace cooling towers.

System: D3030 - Cooling Generating Systems



Location: Chiller mechanical equipment room

Distress: Beyond Service Life

Category: 3 - Operations / Maint.

Priority: 3 - Response Time (3-4 yrs)

Correction: Replace chiller, water-cooled (500 tons)

Qty: 1.00

Unit of Measure: Ea.

Estimate: \$855,399.96

Assessor Name: Craig Anding

Date Created: 02/09/2016

Notes: Replace chiller.

System: D3040 - Distribution Systems



Location: Throughout the school

Distress: Beyond Service Life

Category: 3 - Operations / Maint.

Priority: 3 - Response Time (3-4 yrs)

Correction: Replace indoor AHU, CV, DT (15T)

Qty: 15.00

Unit of Measure: TonAC

Estimate: \$3,600,167.72

Assessor Name: Craig Anding

Date Created: 02/09/2016

Notes: Replace the existing York air handling units with package indoor units with heating and cooling coils and outside air for ventilation to provide adequate ventilation per ASHRAE Std 62.

System: D3040 - Distribution Systems



Location: Throughout the school

Distress: Beyond Service Life

Category: 3 - Operations / Maint.

Priority: 3 - Response Time (3-4 yrs)

Correction: Perform testing to identify and replace damaged steam and condensate piping.

Qty: 84,000.00

Unit of Measure: S.F.

Estimate: \$794,671.28

Assessor Name: Craig Anding

Date Created: 02/09/2016

Notes: Hire a qualified contractor to examine the steam and condensate piping in service for 80 years and perform additional testing to locate and replace any damaged piping and to further quantify the extent of potential failures. The District should budget for replacing this piping over the next 10 years

System: D3040 - Distribution Systems



Location: Roof

Distress: Beyond Service Life

Category: 3 - Operations / Maint.

Priority: 3 - Response Time (3-4 yrs)

Correction: Replace indoor AHU, CV, DT (15T)

Qty: 15.00

Unit of Measure: TonAC

Estimate: \$281,099.01

Assessor Name: Craig Anding

Date Created: 02/09/2016

Notes: Replace split systems with a supply duct distributed split system air handling system with outside air ventilation for the Cafeteria

System: D3040 - Distribution Systems



Location: Roof

Distress: Beyond Service Life

Category: 3 - Operations / Maint.

Priority: 3 - Response Time (3-4 yrs)

Correction: Replace power roof ventilator (24" dia.)

Qty: 4.00

Unit of Measure: Ea.

Estimate: \$177,233.55

Assessor Name: Craig Anding

Date Created: 02/09/2016

Notes: Replace restroom exhaust fans.

Priority 4 - Response Time (4-5 yrs):

System: D3030 - Cooling Generating Systems



Location: Chiller mechanical equipment room

Distress: Beyond Service Life

Category: 3 - Operations / Maint.

Priority: 4 - Response Time (4-5 yrs)

Correction: Replace base mounted, end suction CHW pump
(5" size, 15 HP, to 1000 GPM)

Qty: 2.00

Unit of Measure: Ea.

Estimate: \$262,097.10

Assessor Name: Craig Anding

Date Created: 02/09/2016

Notes: Replace chilled water pumps.

System: D3030 - Cooling Generating Systems



Location: Chiller mechanical equipment room

Distress: Beyond Service Life

Category: 3 - Operations / Maint.

Priority: 4 - Response Time (4-5 yrs)

Correction: Replace base mounted, end suction CHW pump
(6" size, 25 HP, to 1550 GPM)

Qty: 1.00

Unit of Measure: Ea.

Estimate: \$169,963.37

Assessor Name: Craig Anding

Date Created: 02/09/2016

Notes: Replace condenser water pumps.

Priority 5 - Response Time (> 5 yrs):

System: D2020 - Domestic Water Distribution



Location: Throughout the school

Distress: Beyond Service Life

Category: 3 - Operations / Maint.

Priority: 5 - Response Time (> 5 yrs)

Correction: Replace domestic water piping (75 KSF)

Qty: 84,000.00

Unit of Measure: S.F.

Estimate: \$425,658.17

Assessor Name: Craig Anding

Date Created: 02/09/2016

Notes: Inspect and replace the original as needed the domestic water piping in the building

System: D3040 - Distribution Systems



Location: Roof

Distress: Beyond Service Life

Category: 3 - Operations / Maint.

Priority: 5 - Response Time (> 5 yrs)

Correction: Install HVAC unit for Cafeteria (850 students).

Qty: 850.00

Unit of Measure: Student

Estimate: \$434,958.00

Assessor Name: Craig Anding

Date Created: 02/09/2016

Notes: Provide ventilation, heating and cooling for the Multipurpose Room by installing a packaged roof top unit.

System: D3040 - Distribution Systems



Location: Roof

Distress: Beyond Service Life

Category: 3 - Operations / Maint.

Priority: 5 - Response Time (> 5 yrs)

Correction: Install HVAC unit for Gymnasium (single station).

Qty: 6,000.00

Unit of Measure: S.F.

Estimate: \$344,860.27

Assessor Name: Craig Anding

Date Created: 02/09/2016

Notes: Provide ventilation, heating and cooling for the gymnasium by installing a packaged roof top unit.

System: D3040 - Distribution Systems



Location: Throughout the school

Distress: Beyond Service Life

Category: 3 - Operations / Maint.

Priority: 5 - Response Time (> 5 yrs)

Correction: Replace finned tube radiation terminals (per 100 LF)

Qty: 100.00

Unit of Measure: L.F.

Estimate: \$40,354.14

Assessor Name: Craig Anding

Date Created: 02/09/2016

Notes: Replace the steam convection units and any of the original radiant heating (manifold) terminals fashioned from welded piping still present in the building with finned tube elements to protect students from exposure to the hot surfaces.

System: D4010 - Sprinklers



Location: Throughout the building

Distress: Life Safety / NFPA / PFD

Category: 2 - Code Compliance

Priority: 5 - Response Time (> 5 yrs)

Correction: Install a fire protection sprinkler system

Qty: 84,000.00

Unit of Measure: S.F.

Estimate: \$1,201,657.51

Assessor Name: Craig Anding

Date Created: 02/09/2016

Notes: Install a fire protection sprinkler system for the areas which are currently not protected with quick response type heads to reduce insurance costs by providing protection for the property. A fire pump may be required depending on the available city water pressure.

Equipment Inventory

The following table represents the inventory details of the inventory found in the building, which fall under the following subsystems:

| Subsystem | Inventory | Qty | UoM | Location | Manufacturer | Model Number | Serial Number | Barcode | Life | Install Date | Next Renewal | Raw Cost | Inventory Cost |
|---------------------------------------|-----------------------------------------------------------------------------------------------------------------------|------|-----|---------------------------------------|--------------|------------------|---------------|---------|------|--------------|--------------|---------------|-----------------------|
| D1010 Elevators and Lifts | Hydraulic, passenger elevator, 1500 lb, 2 floors, 100 FPM | 1.00 | Ea. | Building Interior | | | | | 30 | 1936 | 2023 | \$68,985.00 | \$75,883.50 |
| D3020 Heat Generating Systems | Boiler, cast iron, gas, steam, 4720 MBH | 2.00 | Ea. | Main boiler mechnaical equipment room | Weil McLain | | | | 35 | | | \$150,947.30 | \$332,084.06 |
| D3020 Heat Generating Systems | Boiler, cast iron, gas, steam, 4720 MBH | 2.00 | Ea. | Main boiler mechnaical equipment room | Weil McLain | 1594 | | | 35 | | | \$150,947.30 | \$332,084.06 |
| D3030 Cooling Generating Systems | Chiller, reciprocating, air cooled, standard controls, 80 ton | 1.00 | Ea. | Main mechanical room | Carrier | 30HXC106RZ-661BA | | | 30 | | | \$90,207.10 | \$99,227.81 |
| D3030 Cooling Generating Systems | Cooling tower, galvanized steel, packaged unit, draw thru, 110 ton | 2.00 | Ea. | Main mechanical room | Evapco | LSTA 4-121 | | | 30 | | | \$51,369.50 | \$113,012.90 |
| D5010 Electrical Service/Distribution | Load interrupter switch, 2 position, 400 kVA & above w/CLF fuses, 4.8 KV, 600 amp, NEMA 1 | 1.00 | Ea. | Electrical Room | | | | | 30 | 1936 | 2025 | \$38,502.00 | \$42,352.20 |
| D5010 Electrical Service/Distribution | Switchboards, pressure switch, 4 wire, with ground fault, 120/208 V, 1600 amp, incl CT compartment, excl CT's or PT's | 1.00 | Ea. | Electrical Room | | | | | 30 | 1936 | 2025 | \$35,024.40 | \$38,526.84 |
| D5010 Electrical Service/Distribution | Transformer, liquid-filled, 5 kV or 15 kV primary, 277/480 V secondary, 3 phase, 1000 kVA, pad mounted | 1.00 | Ea. | Electrical Room | | | | | 30 | 1936 | 2025 | \$50,425.20 | \$55,467.72 |
| | | | | | | | | | | | | Total: | \$1,088,639.09 |

Executive Summary

Building condition is evaluated based on the functional systems and elements of a building and organized according to the UNIFORMAT II Elemental Classification. The grouping of these systems and elements and applying a current replacement value to them develops a representative building cost model. Cost Models are developed for similar building types and functions. Systems and their elements are evaluated based on their current replacement values, life cycles, installation dates and next renewal dates. Systems and their elements that are within their useful lives are further evaluated to identify current deficient conditions that may have a significant impact on a system's or element's remaining service life, and to determine if they are beyond their predicted expected life. The system's or element's current replacement value is based on RS Means Commercial Cost Data.

Following are the cost model's system details for this facility. The Replacement Value is the amount needed to replace the property of the same present value. The Current Repair Amount, also known as Condition Needs, represents the budgeted contractor installed costs plus owner's soft costs for the repair, replacement or renewal for a component or system level deficiency. It excludes contributing costs for other components or systems that might also be associated with the corrective actions due to packaging the work. Facility Condition Index (FCI) FCI is an industry-standard measurement of facility condition calculated as the ratio of the costs to correct a facility's deficiencies to the facility's Current Replacement Value. It ranges from 0% (new) to 100% (very poor). Condition Index (CI) is calculated as the sum of a renewable system's Remaining Service Life (RSL) divided by the sum of a system's Replacement Value (both values exclude soft-cost to simplify calculation updates) expressed as a percentage ranging from 100% (new) to 0% (expired).

Function:

| | |
|--------------------|--------------|
| Gross Area (SF): | 47,500 |
| Year Built: | 1936 |
| Last Renovation: | |
| Replacement Value: | \$961,719 |
| Repair Cost: | \$208,116.58 |
| Total FCI: | 21.64 % |
| Total RSLI: | 47.77 % |

Description:

Attributes:

General Attributes:

| | | | |
|----------|---------|----------|---------|
| Bldg ID: | S731001 | Site ID: | S731001 |
|----------|---------|----------|---------|

Condition Summary

The Table below shows the CI and FCI for each major building system shown at the UNIFORMAT classification Level II. Note that Systems with lower FCIs require less investment than systems with higher FCIs.

| UNIFORMAT Classification | RSLI % | FCI % | Current Repair Cost |
|---------------------------------|----------------|----------------|---------------------|
| G20 - Site Improvements | 48.22 % | 30.35 % | \$208,116.58 |
| G40 - Site Electrical Utilities | 46.67 % | 0.00 % | \$0.00 |
| Totals: | 47.77 % | 21.64 % | \$208,116.58 |

Condition Detail

This section of the report contains results of the Facility Condition Assessment. The building is separated into system components based on UNIFORMAT II classification. The columns in the System Listing table below represent the following:

1. System Code: A code that identifies the system.
2. System Description: A brief description of a system present in the building.
3. Unit Price \$: The unit price of the system.
4. UoM: The unit of measure for of the system.
5. Qty: The quantity for the system
6. Life: anticipated service life for the system based on Building Owners and Managers Association (BOMA) recommendations.
7. Year Installed: The date of system installation.
8. Calc Next Renewal Year: The date of system expiration based on the life, NR stands for non renewable.
9. Next Renewal Year: The suggested system expiration date by the assessor based on visual inspection.
10. CI: The Condition Index of the system.
11. FCI: The Facility Condition Index of the system.
12. RSL: Remaining Service Life.
13. eCR: eCOMET Condition Rating (not used).
14. Deficiency \$: The financial investment to repair/replace system.

System Listing

The System Listing table below lists each of the systems organized by their UNIFORMAT II classification. The assessment team was tasked with recording the most recent replacement year of each system, determining the remaining service life based on the theoretical life, and evaluating the condition to confirm the forecast next replacement year. The system listing is the basis for all data contained in the Building Assessment Report.

Additionally, a condition rating (eCR) based on the following guidelines is provided as observed at the time of the assessment.

- Excellent (E) - No noticeable distress or damage. The entire system is free from observable defect.
- Very Good (VG) - Overall no serviceability reduction for the entire system. No degradation of critical components and minor distress and defect noticeable for some but not non critical components within the system.
- Good (G) - Slight or no serviceability reduction for the entire system. There may be noticeable defects for some non critical components and slight noticeable degradation of the critical components.
- Fair (F) - Overall serviceability is degraded but adequate. There may be moderate deterioration for very few of the critical components and few of the non critical components may have severe degradation.
- Marginal (MA) - Overall serviceability and reliability loss. Most if not all of the non critical components suffer from severe degradation and a few of the critical component may have severe degradation.
- Moderate (MO) - Overall a significant serviceability loss. Most if not all the components have severe degradation with the remainder of the component showing visible distress.
- Very Poor (VP) - Overall the system is barely functional. All of the components are severely degraded.
- Non-Functional (NF) - Overall the system does not function with all the components having no serviceability and suffer from severe degradation.

| System Code | System Description | Unit Price \$ | UoM | Qty | Life | Year Installed | Calc Next Renewal Year | Next Renewal Year | RSLI% | FCI% | RSL | eCR | Deficiency \$ | Replacement Value \$ | |
|--------------|--------------------------------|---------------|------|--------|------|----------------|------------------------|-------------------|----------|----------------|----------------|-----|---------------|----------------------|------------------|
| G2010 | Roadways | \$11.52 | S.F. | | 30 | | | | 0.00 % | 0.00 % | | | | \$0 | |
| G2020 | Parking Lots | \$8.50 | S.F. | 8,500 | 30 | 1936 | 1966 | 2047 | 106.67 % | 108.69 % | 32 | | \$78,530.19 | \$72,250 | |
| G2030 | Pedestrian Paving | \$12.30 | S.F. | 25,100 | 40 | 1936 | 1976 | 2027 | 30.00 % | 18.61 % | 12 | | \$57,467.52 | \$308,730 | |
| G2040 | Site Development | \$4.36 | S.F. | 47,500 | 25 | 1936 | 1961 | 2025 | 40.00 % | 34.82 % | 10 | | \$72,118.87 | \$207,100 | |
| G2050 | Landscaping & Irrigation | \$4.36 | S.F. | 22,400 | 15 | 1936 | 1951 | 2027 | 80.00 % | 0.00 % | 12 | | | \$97,664 | |
| G4020 | Site Lighting | \$4.84 | S.F. | 47,500 | 30 | 1936 | 1966 | 2029 | 46.67 % | 0.00 % | 14 | | | \$229,900 | |
| G4030 | Site Communications & Security | \$0.97 | S.F. | 47,500 | 30 | 1936 | 1966 | 2029 | 46.67 % | 0.00 % | 14 | | | \$46,075 | |
| Total | | | | | | | | | | 47.77 % | 21.64 % | | | \$208,116.58 | \$961,719 |

System Notes

The facility description in the site executive summary contains an overview of each system. The notes listed below provide additional information on select systems found within the facility.

No data found for this asset

Renewal Schedule

eCOMET forecasts future Capital Renewal funding needed to address expiring systems based on the Next Renewal year found in the Cost Models. A 3% annual inflation factor is applied to the costs for systems expiring in future years. The table below reflects recommended Capital Renewal funding needs over the next 10 years. Note: Cells with a zero value indicate systems for which renewal is not scheduled in that year.


Inflation Rate: 3%

| System | Current Deficiencies | 2016 | 2017 | 2018 | 2019 | 2020 | 2021 | 2022 | 2023 | 2024 | 2025 | Total |
|----------------------------------------|----------------------|------|------|------|------|------|------|------|------|------|-----------|-----------|
| Total: | \$208,117 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$306,158 | \$514,274 |
| G - Building Sitework | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| G20 - Site Improvements | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| G2010 - Roadways | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| G2020 - Parking Lots | \$78,530 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$78,530 |
| G2030 - Pedestrian Paving | \$57,468 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$57,468 |
| G2040 - Site Development | \$72,119 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$306,158 | \$378,276 |
| G2050 - Landscaping & Irrigation | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| G40 - Site Electrical Utilities | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| G4020 - Site Lighting | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| G4030 - Site Communications & Security | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |

* Indicates non-renewable system

Forecasted Sustainment Requirement


The following chart shows the current building deficiencies and forecasting sustainment requirements over the next ten years.



10 Year FCI Forecast by Investment Scenario

The chart below illustrates the effect of various investment levels on the building FCI for the next 10 years. The levels of investment shown below include:


- Current FCI: a variable investment amount based on renewing expired systems to maintain the current FCI for the building
- 2% Investment: an annual investment of 2% of the replacement value of the building, escalated for inflation
- 4% Investment: an annual investment of 4% of the replacement value of the building, escalated for inflation



| Year | Investment Amount Current FCI - 21.64% | 2% Investment | | 4% Investment | |
|---------------|-------------------------------------------|---------------------|---------|---------------------|---------|
| | | Amount | FCI | Amount | FCI |
| 2016 | \$0 | \$19,811.00 | 19.64 % | \$39,623.00 | 17.64 % |
| 2017 | \$84,315 | \$20,406.00 | 25.90 % | \$40,812.00 | 21.90 % |
| 2018 | \$0 | \$21,018.00 | 23.90 % | \$42,036.00 | 17.90 % |
| 2019 | \$0 | \$21,648.00 | 21.90 % | \$43,297.00 | 13.90 % |
| 2020 | \$0 | \$22,298.00 | 19.90 % | \$44,596.00 | 9.90 % |
| 2021 | \$0 | \$22,967.00 | 17.90 % | \$45,934.00 | 5.90 % |
| 2022 | \$0 | \$23,656.00 | 15.90 % | \$47,312.00 | 1.90 % |
| 2023 | \$0 | \$24,366.00 | 13.90 % | \$48,731.00 | -2.10 % |
| 2024 | \$0 | \$25,097.00 | 11.90 % | \$50,193.00 | -6.10 % |
| 2025 | \$306,158 | \$25,849.00 | 33.59 % | \$51,699.00 | 13.59 % |
| Total: | \$390,473 | \$227,116.00 | | \$454,233.00 | |


Deficiency Summary by System

Current deficiencies included assemblies that have reached or exceeded their design life or components of the assemblies that are in need of repair. Assemblies that have reached their design life are identified as current deficiencies and assigned the distress 'Beyond Useful Life'. The following chart lists all current deficiencies associated with this facility.



Deficiency Summary by Priority

The following chart shows the total repair costs broken down by priority. Assessors assigned deficiencies within eCOMET to one of the following priority categories:




Deficiency By Priority Investment Table

The table below shows the current investment cost grouped by deficiency priority and building system.

| System Code | System Description | 1 - Response Time (< 2 yr) | 2 - Response Time (2-3 yrs) | 3 - Response Time (3-4 yrs) | 4 - Response Time (4-5 yrs) | 5 - Response Time (> 5 yrs) | Total |
|-------------|--------------------|----------------------------|-----------------------------|-----------------------------|-----------------------------|-----------------------------|---------------------|
| G2020 | Parking Lots | \$0.00 | \$0.00 | \$78,530.19 | \$0.00 | \$0.00 | \$78,530.19 |
| G2030 | Pedestrian Paving | \$51,963.60 | \$5,503.92 | \$0.00 | \$0.00 | \$0.00 | \$57,467.52 |
| G2040 | Site Development | \$4,616.46 | \$67,502.41 | \$0.00 | \$0.00 | \$0.00 | \$72,118.87 |
| | Total: | \$56,580.06 | \$73,006.33 | \$78,530.19 | \$0.00 | \$0.00 | \$208,116.58 |

Deficiency Summary by Category

The following chart shows the total repair costs broken down by deficiency categories. Assessors assigned deficiencies to one of the following categories:



Deficiency Details by Priority

The deficiency detail notes listed below provide additional information on identified deficiencies found within the facility.

Priority 1 - Response Time (< 2 yr):

System: G2030 - Pedestrian Paving



Location: east driveway, door to corridor/stair

Distress: Accessibility

Category: 2 - Code Compliance

Priority: 1 - Response Time (< 2 yr)

Correction: Install an exterior ADA ramp - based on 5' wide by the linear foot - up to a 48" rise - per LF of ramp - figure 1 LF per inch of rise

Qty: 40.00

Unit of Measure: L.F.

Estimate: \$51,963.60

Assessor Name: Craig Anding

Date Created: 01/19/2016

Notes: Provide new handicap ramp and railing system into east entrance (40 ft.)

System: G2040 - Site Development



Location: main entrance stair on E. Wyoming Ave.

Distress: Failing

Category: 3 - Operations / Maint.

Priority: 1 - Response Time (< 2 yr)

Correction: Replace or install exterior guardrails

Qty: 24.00

Unit of Measure: L.F.

Estimate: \$4,616.46

Assessor Name: Craig Anding

Date Created: 01/19/2016

Notes: New handrails (2) for entrance stairs (24ft)

Priority 2 - Response Time (2-3 yrs):

System: G2030 - Pedestrian Paving



Location: sidewalk

Distress: Damaged

Category: 3 - Operations / Maint.

Priority: 2 - Response Time (2-3 yrs)

Correction: Remove and replace concrete sidewalk or concrete paving - 4" concrete thickness

Qty: 200.00

Unit of Measure: S.F.

Estimate: \$2,876.57

Assessor Name: Craig Anding

Date Created: 01/19/2016

Notes: Repave broken sidewalk (200sf)

System: G2030 - Pedestrian Paving



Location: vehicle apron

Distress: Damaged

Category: 3 - Operations / Maint.

Priority: 2 - Response Time (2-3 yrs)

Correction: Remove and replace concrete paving - pedestrian or parking - 8" concrete thickness

Qty: 100.00

Unit of Measure: S.F.

Estimate: \$2,627.35

Assessor Name: Craig Anding

Date Created: 01/19/2016

Notes: New concrete apron to street, vehicle rated (100sf)

System: G2040 - Site Development



Location: retaining wall along east property line

Distress: Failing

Category: 3 - Operations / Maint.

Priority: 2 - Response Time (2-3 yrs)

Correction: Repair concrete retaining wall in poor condition including rebar doweling - insert the SF of wall area

Qty: 150.00

Unit of Measure: S.F.

Estimate: \$44,490.60

Assessor Name: Craig Anding

Date Created: 01/19/2016

Notes: Repair cracked and spalling retaining wall (150sf)

System: G2040 - Site Development



Location: main entrance stair on E. Wyoming Ave.

Distress: Damaged

Category: 3 - Operations / Maint.

Priority: 2 - Response Time (2-3 yrs)

Correction: Remove and replace on grade concrete steps - based on 6' wide steps and 6 or 12 risers - modify estimate to suit the configuration

Qty: 1.00

Unit of Measure: Flight

Estimate: \$14,040.01

Assessor Name: Craig Anding

Date Created: 01/19/2016

Notes: Reconstruct concrete entrance stairs (12 risers)

System: G2040 - Site Development



Location: site fence

Distress: Appearance

Category: 3 - Operations / Maint.

Priority: 2 - Response Time (2-3 yrs)

Correction: Replace chain link fence - 6' high

Qty: 100.00

Unit of Measure: L.F.

Estimate: \$8,971.80

Assessor Name: Craig Anding

Date Created: 01/19/2016

Notes: Repair and repaint chain link fence on retaining wall (100lf)

Priority 3 - Response Time (3-4 yrs):

System: G2020 - Parking Lots



Location: driveway and playground

Distress: Failing

Category: 3 - Operations / Maint.

Priority: 3 - Response Time (3-4 yrs)

Correction: Resurface parking lot - grind and resurface including striping

Qty: 22,000.00

Unit of Measure: S.F.

Estimate: \$78,530.19

Assessor Name: Craig Anding

Date Created: 01/19/2016

Notes: Repave asphalt driveway/delivery and playground area (22,000sf)

Equipment Inventory

The following table represents the inventory details of the inventory found in the building, which fall under the following subsystems:

No data found for this asset

Glossary

| | |
|------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| ABMA | American Boiler Manufacturers Association http://www.abma.com/ |
| ACEEE | American Council for an Energy-Efficient Economy |
| ACGIH | American Council of Governmental and Industrial Hygienists |
| AEE | Association of Energy Engineers |
| AFD | Adjustable Frequency Drive |
| AFTC | After Tax Cash Flow |
| AGA | American Gas Association |
| AHU | Air Handling Unit |
| Amp | Ampere |
| ANSI | American National Standards Institute |
| ARI | Air Conditioning and Refrigeration Institute |
| ASD | Adjustable Speed Drive |
| ASHRAE | American Society of Heating Refrigerating and Air-Conditioning Engineers Inc. |
| ASME | American Society of Mechanical Engineers |
| Assessment | Visual survey of a facility to determine its condition. It involves looking at the age of systems reviewing information from local sources and visual evidence of potential problems to assign a condition rating. It does not include destructive testing of materials or testing of systems or equipment for functionality. |
| ATS | After Tax Savings |
| AW | Annual worth |
| BACNET | Building Automation Control Network |
| BAS | Building Automation System |
| BCR | Benefit Cost Ratio |
| BEP | Business Energy Professional (AEE) |
| BF | Ballast Factor |
| BHP | Boiler Horsepower (boilers) |
| BHP | Brake Horsepower (motors) |
| BLCC | Building Life Cycle Cost analysis program (FEMP) |
| BOCA | Building Officials and Code Administrators |
| BTCF | Before Tax Cash Flow |

Site Assessment Report - S731001;Feltonville Intermediate

| | |
|-------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| BTS | Before Tax Savings |
| Btu | British thermal unit |
| Building Addition | An area space or component of a building added to a building after the original building's year built date. |
| CAA | Clean Air Act |
| CAAA-90 | Clean Air Act Amendments of 1990 |
| CABO | Council of American Building Officials |
| CAC | Conventional Air Conditioning |
| CADDET | Center for the Analysis and Dissemination of Demonstrated Energy Technologies |
| Calculated Next Renewal | The year a system or element would be expected to expire based solely on the date it was installed and the expected useful lifetime for that kind of system. |
| Capital Renewal | Capital renewal is condition work (excluding suitability and energy audit work) that includes the replacement of building systems or elements (as they become obsolete or beyond their useful life) not normally included in an annual operating budget. Calculated next renewal The year a system or element would be expected to expire based solely on the date it was installed and the expected useful lifetime for that kind of system. Next renewal The assessor adjusted expected useful life of a system or element based on on-site inspection. |
| CDD | Cooling Degree Days |
| CDGP | Certified Distributed Generation Professional |
| CEC | California Energy Commission |
| CEM | Certified Energy Manager |
| CEP | Certified Energy Procurement Professional |
| CFC | Chlorofluorocarbon |
| CFD | Cash Flow Diagram |
| CFL | Compact Fluorescent Light |
| CFM cfm | Cubic Feet per Minute |
| CHP | Combined Heat and Power (a.k.a. cogeneration) |
| CHW | Chilled Water |
| Condition | Condition refers to the state of physical fitness or readiness of a facility system or system element for its intended use. |
| COP | Coefficient of Performance |
| Cp | Heat Capacity of Material |
| CPUC | California Public Utility Commission |
| CRI | Color Rendering Index |
| CRT | Cathode Ray Tube VDT HMI |

Site Assessment Report - S731001;Feltonville Intermediate

| | |
|---------------------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| CTC | Competitive Transition Charge |
| Cu | Coefficient of Utilization |
| Current Replacement Value (CRV) | CRV represents the hypothetical total cost of rebuilding or replacing an existing facility in current dollars to its optimal condition (excluding auxiliary facilities) under current codes and construction standards. |
| Cv | Value Coefficient |
| CWS | Chilled Water System |
| D d | Distance (usually feet) |
| DB | Dry Bulb |
| DCV | Demand Control Ventilation |
| DD | Degree Day |
| DDB | Double Declining Balance |
| DDC | Direct Digital Controls |
| Deferred maintenance | Deferred maintenance is condition work (excluding suitability and energy audit needs) deferred on a planned or unplanned basis to a future budget cycle or postponed until funds are available. |
| Deficiency | A deficiency is a repair item that is damaged missing inadequate or insufficient for an intended purpose. |
| Delta | Difference |
| Delta P | Pressure Difference |
| Delta T | Temperature Difference |
| DG | Distributed Generation |
| DOE | Department of Energy |
| DP | Dew Point |
| DR | Demand Response |
| DX | Direct Expansion Air Conditioner |
| EA | Energy Audit |
| EBITDA | Earnings before Interest Taxes Depreciation and Amortization |
| ECI | Energy Cost Index |
| ECM | Energy Conservation Measure |
| ECO | Energy Conservation Opportunity |
| ECPA | Energy Conservation and Production Act |
| ECR | Energy Conservation Recommendation |
| ECS | Energy Control System |

Site Assessment Report - S731001;Feltonville Intermediate

| | |
|------------------------------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| EER | Energy Efficiency Ratio |
| EERE | Energy Efficiency and Renewable Energy division of US DOE |
| EIA | Energy Information Agency |
| EIS | Energy Information System |
| EMCS | Energy Management Computer System |
| EMO | Energy Management Opportunity |
| EMP | Energy Management Project |
| EMR | Energy Management Recommendation |
| EMS | Energy Management System |
| Energy Utilization Index (EUI) | EUI is the measure of total energy consumed in the cooling or heating of a building in a period expressed as British thermal unit (BTU) per (cooled or heated) gross square foot. |
| EO | Executive Order |
| EPA | Environmental Protection Agency |
| EPACT | Energy Policy Act of 1992 |
| EPCA | Energy Production and Conservation Act of 1975 |
| EPRI | Electric Power Research Institute |
| EREN | Efficiency and Renewable Energy (Division of USDOE) |
| ERV | Energy Recovery Ventilator |
| ESCO | Energy Service Company |
| ESPC | Energy Savings Performance Contract |
| EUI | Energy Use Index |
| EWG | Exempt Wholesale Generators |
| Extended Facility Condition Index (EFCI) | EFCI is calculated as the condition needs for the current year plus facility system renewal needs going out to a set time in the future divided by Current Replacement Value. |
| f | Frequency |
| F | Fahrenheit |
| Facility | A facility refers to site(s) building(s) or building addition(s) or combinations thereof that provide a particular service. |
| Facility Condition Assessment (FCA) | FCA is a process for evaluating the condition of buildings and facilities for programming and budgetary purposes through an on site inspection and evaluation process. |
| Facility Condition Index (FCI) | FCI is an industry-standard measurement of a facility's condition that is the ratio of the cost to correct a facility's deficiencies to the Current Replacement Value of the facilities. The higher the FCI the poorer the condition of a facility. After an FCI is established for all buildings within a portfolio a building's condition can be ranked relative to other buildings. The FCI may also represent the condition of a portfolio based on the cumulative FCIs of the portfolio's facilities. |

Site Assessment Report - S731001;Feltonville Intermediate

| | |
|-------------------------|-----------------------------------------------------------------------------------------------------------------------|
| FC | Footcandle |
| FCA | Fuel Cost Adjustment |
| FEMIA | Federal Energy Management Improvement Act of 1988 |
| FEMP | Federal Energy Management Program |
| FERC | Federal Energy Regulatory Commission |
| FESR | Fuel Energy Savings Ratio |
| FLA | Full Load Amps |
| FLF | Facility Load Factor (usually monthly) |
| FLRPM | Full Load Revolutions per Minute |
| FMS | Facility Management System |
| FPM fpm | Feet per Minute (velocity) |
| FSEC | Florida Solar Energy Center |
| Ft | Foot |
| GPM gpm | Gallons per Minute |
| GRI | Gas Research Institute |
| Gross Square Feet (GSF) | The size of the enclosed floor space of a building in square feet measured to the outside face of the enclosing wall. |
| GUI | Graphical User Interface |
| H h | Enthalpy Btu/lb |
| HCFC | Hydrochlorofluorocarbons |
| HDD | Heating Degree days |
| HFC | Hydrofluorocarbons |
| HHV | Higher Heating Value |
| HID | High Intensity Discharge (lamp) |
| HMI | Human Machine Interface |
| HMMI | Human Man Machine Interface |
| HO | High Output (lamp) |
| HP Hp hp | Horsepower |
| HPS | High Pressure Sodium (lamp) |
| HR | Humidity Ratio |
| Hr hr | Hour |

Site Assessment Report - S731001;Feltonville Intermediate

| | |
|--------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| HRU | Heat Recovery Unit |
| HVAC | Heating Ventilation and Air-Conditioning |
| Hz | Hertz |
| I | Intensity (lumen output of lamp) |
| I i | Interest rate or Discount rate |
| IAQ | Indoor Air Quality |
| ICA | International Cogeneration Alliance |
| ICBO | International Conference of Buildings Officials |
| ICC | International Code Council |
| ICP | Institutional Conservation Program |
| IECC | International Energy Conservation Code |
| IEEE | Institute of Electrical and Electronic Engineers |
| IESNA | Illuminating Engineering Society of North America |
| Install year | The year a building or system was built or the most recent major renovation date (where a minimum of 70% of the system's Current Replacement Value (CRV) was replaced). |
| IRP | Integrated Resource Planning |
| IRR | Internal Rate of Return |
| ISO | Independent System Operator |
| ITA | Independent Tariff Administrator |
| k | Kilo multiple of thousands in SI system |
| K | Kelvins (color temperature of lamp) |
| K k | Thermal Conductivity of Material |
| KVA | Kilovolt Ampere |
| KVAR | Kilovolt Ampere Reactive |
| kW | kiloWatt |
| kWh | kiloWatt hour |
| L | Length (usually feet) |
| LCC | Life Cycle Costing |
| LDC | Local Distribution Company |
| LEED | Leadership in Energy and Environmental Design |
| LEED EB | LEED for Existing Buildings |

Site Assessment Report - S731001;Feltonville Intermediate

| | |
|--------------|--------------------------------------------------------------------------------------------------------------------------------|
| LEED NC | LEED for new construction |
| LF | Load Factor |
| LHV | Lower Heating Value |
| Life cycle | The period of time that a building or site system or element can be expected to adequately serve its intended function. |
| LPS | Low Pressure Sodium (lamp) |
| Lu | Lumen Output of a Lamp or Fixture |
| M | Mega multiple of millions in SI system |
| M&V | Measurement and Verification |
| MACRS | Modified Accelerated Cost Recovery System |
| MARR | Minimum Attractive Rate of Return |
| Mbtu | Thousand Btu |
| MCF | Thousand Cubic Feet (usually of gas) |
| MEC | Model Energy Code |
| Mm | Multiple of Thousands in I/P System |
| MMBtu | Million Btu |
| MMCS | Maintenance Management Computer System |
| MMI | Man Machine Interface |
| MMS | Maintenance Management System |
| MSE 2000 | Management System for Energy 2000 (ANSI Georgia Tech Univ) |
| MW | MegaWatt |
| MWH MWh | MegaWatt hour |
| NAAQS | National Ambient Air Quality Standards |
| NAESCO | National Association of Energy Service Companies |
| NAIMA | North American Insulation Manufacturers Association |
| NEA | National Energy Act of 1978 |
| NECPA | National Energy Conservation Policy Act |
| NEMA | National Electrical Manufacturer's Association |
| NERC | North American Electric Reliability Council |
| Next Renewal | The Next Renewal date is an override of the 'Calculated Next Renewal' date and is based upon the assessor's visual inspection. |

Site Assessment Report - S731001;Feltonville Intermediate

| | |
|-----------|-------------------------------------------------------------|
| NFPA | National Fire Protection Association |
| NGPA | National Gas Policy Act of 1978 |
| NLRPM | No Load Revolutions per Minute (speed) |
| Nn | Equipment or Project lifetime in economic analysis |
| NOPR | Notice of Proposed Rule Making from FERC |
| NOx | Nitrogen Oxide Compounds |
| NPV | Net present value in economic analysis |
| NREL | National Renewable Energy Laboratory |
| NUG | Non-Utility Generator |
| O&M | Operation and Maintenance |
| OA | Outside Air |
| ODP | Ozone Depletion Potential |
| OPAC | Off-Peak Air Conditioning |
| P | Present value in economic analysis |
| PBR | Performance Based Rates |
| PEA | Preliminary Energy Audit |
| PF | Power Factor |
| PID | Proportional plus integral plus derivative (control system) |
| PM | Portfolio Manager in Energy Star rating system |
| PM | Preventive Maintenance |
| PoolCo | Power Pool Company or Organization |
| POU | Point of Use |
| PQ | Power Quality |
| PSC | Public Service Commission |
| PSIA psia | Pounds per square inch absolute (pressure) |
| PSIG psig | Pounds per square inch gauge (pressure) |
| PUC | Public Utility Commission |
| PUHCA | Public Utilities Holding Company Act of 1935 |
| PURPA | Public Utilities Regulatory Policies of 1978 |
| PV | Photovoltaic system |

Site Assessment Report - S731001;Feltonville Intermediate

| | |
|------------------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| PV | Present Value |
| PW | Present Worth |
| PX | Power Exchange |
| q | Rate of heat flow in Btu per hour |
| Q | Heat load due to conduction using degree days |
| QF | Qualifying Facility |
| R | Electrical resistance |
| R | Thermal Resistance |
| RC | Remote controller |
| RCR | Room Cavity Ratio |
| RCRA | Resource Conservation and Recovery Act |
| Remaining Service Life (RSL) | RSL is the number of years service remaining for a system or equipment item. It is automatically calculated based on the difference between the current year and the 'Calculated Next Renewal' date or the 'Next Renewal' date whichever one is the later date. |
| Remaining Service Life Index (RSI) | RSI is defined as a percentage ratio of the remaining service life of a system. It usually ranges from 0 to 100 |
| REMR | Repair Evaluation Maintenance Rehabilitation (REMR) is a scale used to objectively rank systems based on their condition |
| Renewal Schedule | A timeline that provides the items that need repair the year in which the repair is needed and the estimated price of the renewal. |
| RH | Relative Humidity |
| RLA | Running Load Amps |
| RMS | Root Mean Square |
| RO | Reverse Osmosis |
| ROI | Return on Investment |
| RPM | Revolutions Per Minute |
| RTG | Regional Transmission Group |
| RTO | Regional Transmission Organization |
| RTP | Real Time Pricing |
| SBCCI | Southern Building Code Congress International |
| SC | Scheduling Coordinator |
| SC | Shading Coefficient |
| SCADA | Supervisory Control and Data Acquisition Systems |

Site Assessment Report - S731001;Feltonville Intermediate

| | |
|--------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| SEER | Seasonal Energy Efficiency Ratio |
| SHR | Sensible Heat Ratio |
| Site | The grounds and utilities roadways landscaping fencing and other typical land improvements needed to support the facility. |
| Soft Cost | An expense item that is not considered direct construction cost. Soft cost includes architectural engineering financing legal fees and other pre-and-post construction expenses. |
| SOx | Sulfur Oxide Compounds |
| SP | Static Pressure |
| SP SPB | Simple Payback |
| SPP | Simple Payback Period |
| SPP | Small Power Producers |
| STR | Stack Temperature Rise |
| SV | Specific Volume |
| System | System refers to building and related site work elements as described by ASTM Uniformat II Classification for Building Elements (E1557-97) a format for classifying major facility elements common to most buildings. Elements usually perform a given function regardless of the design specification construction method or materials used. See also Uniformat II. |
| T | Temperature |
| T | Tubular (lamps) |
| TAA | Technical Assistance Audit |
| TCP/IP | Transmission Control Protocol/Internet Protocol |
| TES | Thermal Energy Storage |
| THD | Total Harmonic Distortion |
| TOD | Time of Day |
| TOU | Time of Use |
| TQM | Total Quality Management |
| TransCo | Transmission Company |
| U | Thermal Conductance |
| UDC | Utility Distribution Company |
| UL | Underwriters Laboratories |
| UNIFORMAT II | The ASTM UNIFORMAT II Classification for Building Elements (E1557-97) a format for classifying major facility components common to most buildings. |
| USGBC | US Green Building Council |
| v | Specific Volume |

Site Assessment Report - S731001;Feltonville Intermediate

| | |
|------------|---------------------------------------------------------------------------------------------------------|
| V | Volts Voltage |
| V | Volume |
| VAV | Variable Air Volume |
| VDT | Video Display Terminal |
| VFD | Variable Frequency Drive |
| VHO | Very High Output |
| VSD | Variable Speed Drive |
| W | Watts |
| W | Width |
| WB | Wet bulb |
| WH Wh | Watt Hours |
| Year built | The year that a building or addition was originally built based on substantial completion or occupancy. |
| Z | Electrical Impedance |