

Facility Condition Assessment Summary Report

This report provides a summary of the Facility Condition Index (FCI) value of a school facility and select major building systems. The FCI calculation represents the cost of needed repairs divided by the replacement value. The FCI is a numerical value of condition and helps to identify the need for renewal or replacement of specific parts of the facility. The FCI is particularly useful when comparing similar facilities within the same portfolio.

Kelley, W D School

| | | | |
|------------|--|---------------------|------------------|
| Governance | DISTRICT | Report Type | Elementarymiddle |
| Address | 1601 N. 28Th St. Philadelphia, Pa 19121 | Enrollment | 409 |
| Phone/Fax | 215-684-5071 / 215-684-5179 | Grade Range | '00-08' |
| Website | Www.Philasd.Org/Schools/Kelley | Admissions Category | Neighborhood |
| | | Turnaround Model | Turnaround |

Building/System FCI Tiers

| Facility Condition Index (FCI) = $\frac{\text{Cost of Assessed Deficiencies}}{\text{Replacement Value}}$ | | | | |
|--|-------------------------------|---|---|--|
| < 15% | 15 to 25% | 25 to 45% | 45 to 60% | > 60% |
| Buildings | | | | |
| Minimal Current Capital Funding Required | Refurbish Systems in building | Replace Systems in building. | Building should be considered for major renovation. | Building should be considered for closing/replacement. |
| Systems | | | | |
| Perform routine maintenance on system | System requires minor repairs | System should be studied to determine repair vs. replacement. | System is nearing end of its life expectancy and should be considered for replacement | System should be replaced as part of the Capital Program |

Building and Grounds

| | FCI | Repair Costs | Replacement Cost |
|----------------|---------------|---------------------|---------------------|
| Overall | 28.18% | \$12,045,221 | \$42,740,118 |
| Building | 28.64 % | \$11,827,447 | \$41,298,632 |
| Grounds | 15.11 % | \$217,773 | \$1,441,486 |

Major Building Systems

| Building System | System FCI | Repair Costs | Replacement Cost |
|--|------------|--------------|------------------|
| Roof (Shows physical condition of roof) | 00.54 % | \$6,711 | \$1,234,700 |
| Exterior Walls (Shows condition of the structural condition of the exterior facade) | 00.31 % | \$6,935 | \$2,247,840 |
| Windows (Shows functionality of exterior windows) | 00.00 % | \$0 | \$981,360 |
| Exterior Doors (Shows condition of exterior doors) | 00.00 % | \$0 | \$120,240 |
| Interior Doors (Classroom doors) | 17.48 % | \$47,308 | \$270,720 |
| Interior Walls (Paint and Finishes) | 00.00 % | \$0 | \$1,416,240 |
| Plumbing Fixtures | 16.91 % | \$384,422 | \$2,273,760 |
| Boilers | 12.02 % | \$161,581 | \$1,344,240 |
| Chillers/Cooling Towers | 63.72 % | \$1,123,153 | \$1,762,560 |
| Radiators/Unit Ventilators/HVAC | 121.14 % | \$3,749,614 | \$3,095,280 |
| Heating/Cooling Controls | 158.90 % | \$1,544,551 | \$972,000 |
| Electrical Service and Distribution | 115.08 % | \$803,750 | \$698,400 |
| Lighting | 34.04 % | \$850,069 | \$2,496,960 |
| Communications and Security (Cameras, Pa System and Fire Alarm) | 67.61 % | \$632,327 | \$935,280 |

Please note that some FCIs may be over 100% because there are times when replacing a building system requires that other building systems be upgraded to complete the installation. A FCI of 0.0% represents that there are no current deficiencies with the associated system.

School District of Philadelphia

S456001;Kelley, William

Final

Site Assessment Report

January 30, 2017



Table of Contents

| | |
|---|----|
| Site Executive Summary | 4 |
| Site Condition Summary | 11 |
| <u>B456001:Kelley, William</u> | 13 |
| Executive Summary | 13 |
| Condition Summary | 14 |
| Condition Detail | 15 |
| System Listing | 16 |
| System Notes | 18 |
| Renewal Schedule | 19 |
| Forecasted Sustainment Requirement | 22 |
| Condition Index Forecast by Investment Scenario | 23 |
| Deficiency Summary By System | 24 |
| Deficiency Summary By Priority | 25 |
| Deficiency By Priority Investment | 26 |
| Deficiency Summary By Category | 27 |
| Deficiency Details By Priority | 28 |
| Equipment Inventory Detail | 46 |
| <u>G456001:Grounds</u> | 47 |
| Executive Summary | 47 |
| Condition Summary | 48 |
| Condition Detail | 49 |
| System Listing | 50 |
| System Notes | 51 |
| Renewal Schedule | 52 |
| Forecasted Sustainment Requirement | 53 |
| Condition Index Forecast by Investment Scenario | 54 |
| Deficiency Summary By System | 55 |
| Deficiency Summary By Priority | 56 |
| Deficiency By Priority Investment | 57 |

Site Assessment Report

| | |
|--------------------------------|----|
| Deficiency Summary By Category | 58 |
| Deficiency Details By Priority | 59 |
| Equipment Inventory Detail | 61 |
| Glossary | 62 |

Site Executive Summary

The organization of this report, as displayed in the Table of Contents, follows the structure of the associated eCOMET database. The overall node for each school campus begins with the letter "S", which indicates the "Site" label. Each Site is comprised of separate "Building" and "Grounds" nodes; their asset names begin with the letters "B" and "G" respectively. Information rolls up to the Site node from the Building and Grounds nodes. This Site report combines facility information with subsections for the Buildings And Grounds nodes.

The basis for the evaluation of condition is the functional systems and elements of a building and grounds organized according to the UNIFORMAT II Elemental Classification. The grouping of these systems and elements and applying a current replacement value to them develops a representative building cost model. Cost Models are typically developed for similar building types and functions. Evaluation of systems and their elements takes into account their current replacement values, life cycles, installation dates and next renewal dates. Systems and their elements that are within their useful lives are further evaluated to identify current deficient conditions that may have a significant impact on a system's or element's remaining service life, and to determine if they are beyond their predicted expected life. The system's or element's current replacement value is based on RS Means Commercial Cost Data.

Following are the cost model's system details for this facility. The Replacement Value is the amount needed to replace the property of the same present value. The Current Repair Amount, also known as Condition Needs, represents the budgeted contractor installed costs plus owner's soft costs for the repair, replacement or renewal for a component or system level deficiency. It excludes contributing costs for other components or systems that might also be associated with the corrective actions due to packaging the work. Facility Condition Index (FCI) is an industry-standard measurement calculated as the ratio of the repair costs to correct a facility's deficiencies to the facility's Current Replacement Value. Condition Index (CI) for a system is calculated as the sum of a the deficiencies divided by the sum of a system's Replacement Value (both values include soft-cost) expressed as a percentage ranging from 0% 100%.

| | |
|--------------------|-----------------|
| Gross Area (SF): | 72,000 |
| Year Built: | 1965 |
| Last Renovation: | |
| Replacement Value: | \$42,740,118 |
| Repair Cost: | \$12,045,220.66 |
| Total FCI: | 28.18 % |
| Total RSLI: | 68.40 % |



Description:

Facility Assessment, December 2015

School District of Philadelphia

William Kelley Elementary School

1601 N. 28th St.

Philadelphia, PA 19121

72,000 SF / 676 Students / LN 04

The Kelley, W. Elementary school building is located at 1601 N. 28th Street in Philadelphia, PA. The three story with partial basement, approximately 72,000 square foot building was originally constructed in 1965. The basement houses mechanical spaces only.

The Facility Area Coordinator did not accompany the Parsons assessment team to the site and was unable to provide input on current problems and planned renovation projects. Mr. Wayne Fuller, Building Engineer, accompanied us on our tour of the school and provided us with detailed

Site Assessment Report - S456001;Kelley, William

information on the building systems and recent maintenance history.

STRUCTURAL/ EXTERIOR CLOSURE:

The original building typically rests on concrete foundations and concrete bearing walls that are not showing signs of settlement. There are no signs of moisture penetration through basement walls

The main structure consists typically of cast-in-place concrete columns, beams and ribbed concrete slabs (1-way and 2-way). Long spans (gym and auditorium) are supported by concrete encased steel framing. The superstructure is in good condition.

The building envelope is typically face brick masonry with CMU backup with large section of curtain wall windows and translucent panels. In general, masonry is in fair condition. Water penetration through walls has not been reported.

The building windows are extruded aluminum, curtain wall type with base panels that are louvered. All windows are double glazed and generally in fair condition.

The exterior doors are typically hollow metal doors and frames, painted. The doors are generally in fair condition. Roofing system is a built-up system installed approximately in 2000 and in fair condition. No leaks have been reported. No roof access to lower roof over entrance and lobby area. Railing needed due to roof access proximity to roof edge.

INTERIORS:

The building partition wall types include painted CMU and folding wood partitions; operable but not used; generally in good condition. Interior doors are generally solid core wood doors, some glazed, with hollow metal frames and extruded aluminum framed storefront leading from entrance to lobby. Most doors are in fair condition but do not have lever type hardware. The doors leading to exits stairways are hollow metal doors and frames in good condition.

Fittings include toilet accessories and toilet partitions, generally in good condition, installed approximately in 2000, no accessible compartments; chalkboards are mostly original in fair condition. Handrails and ornamental metals are generally in good condition. Built-in cabinets are wood in good condition. Interior identifying signage is typically directly painted on wall or door surfaces generally in poor condition.

The interior wall finishes in the building are generally painted CMU. Main lobby on the ground floor and basement is finished with face brick matching the exterior walls. Interiors were painted in 2005 and are in good condition.

Most ceilings are exposed structural painted concrete with 2x2 suspended acoustical panels installed in corridors, office and auditorium in various conditions. Ceilings in some corridors are damaged and beyond their service life. Ceiling in gymnasium is exposed painted metal structure in good condition.

Flooring is typically a mix of VCT, VAT (mostly in corridors) and painted concrete in toilets, stairways and basement. Most flooring is in fair to good condition.

Stair construction is generally steel with concrete filled steel pan treads cast iron non-slip treads in good condition.

Institutional and Commercial equipment includes: A/V equipment in good condition; gym equipment – basketball backstops in good condition. Other equipment includes kitchen equipment, generally in good condition.

Furnishings include fixed casework in classrooms, and other spaces are generally in good condition; window shades/blinds, generally in good condition; fixed seating in auditorium is in good condition.

CONVEYING SYSTEMS:

The building has 1200 lb traction elevator, original to the building. Cabin size does not conform to ADA requirement and its finishes are old and deteriorating.

MECHANICAL

Plumbing Fixtures

Site Assessment Report - S456001;Kelley, William

Many of the plumbing fixtures were replaced in the 1980s and are approaching the end of their useful service lives. Fixtures in the restrooms on each floor consist of both floor and wall mounted flush valve water closets, wall hung urinals, and lavatories with both lever and wheel handle faucets. The installation date of the plumbing fixtures is unknown, but they are estimated to be over 30 years old. The plumbing fixtures are approaching the end of their service lives and should be replaced in the next 3-5 years.

Drinking fountains in the corridors are a mixture of wall hung units and floor standing units with integral refrigerated coolers. Many are beyond their service life and should be replaced; most are NOT accessible type.

A mop basin is available in a janitor closet in the corridor on each floor for use by the janitorial staff.

The Kitchen, located adjacent to the Gymnasium/Cafeteria, does not have a sink or exhaust hood; only premade meals are served.

Domestic Water Distribution

A 4" city water service enters the building boiler room from North 28th Street. A reduced pressure backflow preventer is located in the basement boiler room on the front side of the building, where the water service enters the building. The domestic hot and cold water distribution piping is copper piping and sweat fittings. The maintenance staff reports no significant problems with scale build up in the domestic piping and the supply is adequate to the fixtures, however the age of the piping is unknown. The domestic water piping should be inspected and replaced as necessary by a qualified contractor.

One (1) Bradford White gas fired, 75 gallon, vertical hot water heater with circulating pump supplies hot water for domestic use. The water heater was installed in 2015. The unit is located in the boiler room on the basement level. The domestic hot water heater is within its service life and should provide reliable service for the next 10-12 years. A water softener is not installed.

Sanitary Waste

The storm and sanitary sewer piping is a mixture of galvanized piping with threaded fittings and cast iron piping with hub and spigot fittings. Several sections of piping have been replaced with cast iron piping with no-hub fittings.

A sewage ejector pit located in the basement boiler room receives sewage from the basement area. The system has been in use for an unknown amount of time and appears to be in good condition. The pit is sealed. Two (2) 1/2HP Gorman Rupp pumps are located outside the pit and appeared to be in good condition.

The maintenance staff reported mostly minor problems with the sanitary waste piping systems. However, the sewer piping has been in service for over 50 years and will require more frequent attention from the maintenance staff as time passes. The District should hire a qualified contractor to examine the sanitary waste piping using video cameras to locate and replace any damaged piping and to further quantify the extent of potential failures.

Rain Water Drainage

The rain water drains from the roof are routed through mechanical chases in the building and appear to be original. The piping is cast iron with hub and spigot fittings and has been in use beyond its service life. The drain piping should be inspected by a qualified contractor and repaired as necessary.

Energy Supply

An 8" city gas service enters the building in the basement boiler room from North 28th Street. The gas meter is 3" and is located in the boiler room. An Eclipse gas booster pump is installed to ensure adequate gas pressure to the boilers.

The reserve oil supply is stored in a 10,000 gallon underground storage tank (UST) located in the paved play area on the East side of the school. Duplex pumps located in the boiler room circulate oil through the system. Oil is used as a backup fuel and the District receives credit from the gas utility as an interruptible service. The storage tank should be inspected on a regular basis. USTs have an anticipated service life of 20 years. The actual condition of the fuel side is unknown.

Heat Generating Systems

Building heating hot water is generated by three (3) 100HP HB Smith model 350A cast iron sectional boilers, installed in 1996. Each boiler is equipped with a Power Flame burner designed to operate on natural gas or fuel oil. Combustion air makeup is supplied by louvers equipped with

Site Assessment Report - S456001;Kelley, William

motorized dampers. Burner oil pumps are loose and not driven by the fan motor. The gas train serving the boilers does appear to have code required venting of the regulators and dual solenoid valves with venting of the chamber between. No major issues with the boilers were reported by the Building Engineer. Cast iron boilers have an anticipated service life of 35 years or more; these units have been in service 20 years. The District should provide reliable service for the next 10 to 15 years.

Distribution Systems

Building heating hot water piping is black steel with threaded fittings, smaller branch piping is copper piping with sweat fittings. Three (3) expansion tanks are installed on the hot water piping, one (1) for each boiler. The heating hot water distribution piping has been in use for an unknown amount of time and will require more frequent attention from the maintenance staff to address pipe/valve failures as time passes. The District should hire a qualified contractor to examine the heating hot water distribution piping and perform additional testing to locate and replace any damaged piping and to further quantify the extent of potential failures.

A two pipe distribution system supplies building heating water to the unit ventilators, fin tube radiators, and heating and ventilation (HV) units. Two (2) 7.5HP base mounted, end suction heating water supply pumps circulate building heating hot water. A small circulating pump serving the HV unit for the Auditorium and Gymnasium/Cafeteria is installed. The pumps are in poor condition, well beyond their service lives, and should be replaced. All piping was covered with insulation.

Unit ventilators and fin tube radiators provide heating for classrooms, offices, and indirectly to the hallways. The unit ventilators and fin tube radiators are original to the building and well beyond their service lives. Outdoor air for the building is supposed to be provided by wall openings in the unit ventilators. The Building Engineer reported that the fin tube radiators heat the building sufficiently and the unit ventilators are only used on very cold days; this does not provide sufficient outdoor air ventilation. The existing unit ventilators should be removed and new units installed with hot and chilled water coils and integral heat exchangers to introduce sufficient outdoor air to the building. Ventilation is provided to the Auditorium and Gymnasium/Cafeteria by one (1) heating and ventilation unit located in the basement boiler room. Ventilation is provided to the administration offices by one (1) heating and ventilation unit located in the basement boiler room. The existing HV units are beyond their service lives and should be replaced. Ventilation should be provided for the Gymnasium/Cafeteria by a fan coil air handling unit hung from the structure with outdoor air ducted to the unit from louvers in the window openings. Similar units should be installed for the administration offices. Ventilation should be provided for the Auditorium by installing a constant volume air handling unit with distribution ductwork and registers. These units would be equipped with hot water heating coils and chilled water cooling coils.

Exhaust for the restrooms, art lab, and science lab is provided by four (4) roof mounted exhaust fans. One (1) exhaust fan serves the girls' restrooms, one (1) serves the boys' restrooms, and the other two (2) serve the science and art labs. The existing roof mounted exhaust fans are operational according to the Building Engineer but are in poor condition and should be replaced. Nine (9) roof mounted power ventilators provide relief air for the corridors, are in poor condition, and should be replaced.

Terminal & Package Units

Several of the classrooms in the school building have window air conditioning units that have an anticipated service life of only 10 years. Installing a 200 ton air-cooled chiller, with pumps located in a mechanical room, and chilled water distribution piping would supply more reliable air conditioning for the building with a much longer service life.

A Mitsubishi split system air conditioning system provides cooling to the LAN room located on the first floor off of the Main Office. The installation date of this unit is unknown; the anticipated service life of a split system air conditioner is 15 years. The district should budget to replace this unit within the next 7-10 years.

A kitchen hood is not installed in this building.

Controls & Instrumentation

The original pneumatic systems still provide basic control functions. Pneumatic room thermostats are intended to control the temperature of each space, most of the thermostats still function. The unit ventilators are controlled at the breaker panel and are either "on" or "off", there is no fan modulation. Pneumatic control air is supplied by one (1) duplex Johnson Controls air compressor and Hankison air dryer located in the boiler room. The pneumatic systems are beyond their service life and require too much attention from the maintenance staff. These controls should be converted to DDC.

A new building automation system (BAS) with modern DDC modules and communications network should be installed to serve the HVAC systems in this building to improve reliability and energy efficiency. An interface should be provided with the preferred system in use throughout the District.

Site Assessment Report - S456001;Kelley, William

Sprinklers

The school building is NOT covered by an automatic sprinkler system. Installing a sprinkler system with quick response type heads should reduce insurance costs by providing protection for the property investment. A fire pump may be required depending on the available city water pressure.

The building is not equipped with fire stand pipe.

ELECTRICAL:

Site electrical service - The primary power is at 2.4KV from the power poles. The primary power is brought into the school underground and to the electrical room, feeding a 500 KVA pad-mounted dry-type transformer. The secondary power feeds an old 1600A, 120V/240V, 2 phase switchboard. The PECO meter (PECO 515 MUC 42216) is also located inside the new electrical room (basement). The switchboard is barely functioning. It was built in 1965 and has reached the end of its useful service life.

Distribution system - The electrical distribution is accomplished by using the main switchboard (located in the electrical room) and feeding several 120V lighting and receptacle panels throughout the building. These panels are old, were installed in 1965, and they have reached the end of their useful service life.

Receptacles - The receptacles in classrooms, computer rooms, libraries, and other areas are not adequate. The walls in classrooms and the computer rooms have insufficient number of receptacles (minimum of 2 on each wall).

Lighting - Interior building is illuminated by various types of fixtures. They include fluorescent lighting (mostly T-12 lamps) in majority of the areas, including; classrooms, corridors, offices, Library, cafeteria, Kitchen, etc. Surface or pendant mounted industrial fluorescent fixtures are used in mechanical and electrical rooms. About 20% of the school lighting has been upgraded, however the majority of the building (80%) lacks adequate illumination level. The majority of interior lighting fixtures (80%) are in poor condition and have reached the end of their useful service life.

Fire alarm - The present Fire Alarm system is old, not automatic/addressable, and is not in compliance with safety codes. There are some manual pulls stations throughout the building. There are also some horn/strobes in the classrooms, corridors, offices and other areas in the school. Overall, the FA system is old and has reached the end of its useful service life.

Telephone/LAN - The school telephone and data systems are working properly. A main distribution frame (MDF) along with a telephone PBX system are providing the communication system function for the building. School is also equipped with Wi-Fi system.

Public address - A separate PA system does not exist. School uses the telephone systems for public announcement. The present System is functioning properly. Each class room is provided with an intercom telephone service. This system allows paging and intercom communication between main office to each classroom, and vice versa between each classroom and main office. Also, the system allows communications between classrooms to other classrooms.

Clock and Program system – There are clocks in each classroom (12-inch round clocks), however, the clocks are not controlled properly by the master clock control.

Television System - Television system is not provided for the school. There are smart boards in most of the classrooms capable of connecting to computers and internet.

Security Systems, access control, and video surveillance - The school has an old video surveillance system. There are cameras are installed at exit doors, corridors, exterior, and other critical areas. However school would like to have new video surveillance system with more cameras to cover critical areas. The new cameras should be controlled by a Closed Circuit Television system (CCTV).

Emergency Power System – There is no emergency generator in this building. School needs an Emergency generator for all the critical loads and elevator loads.

Emergency lighting and exit lights - there are sufficient number of emergency lights/exit lights in the corridors and other exit ways. The exit/emergency lights have recently been upgraded (2006).

Lightning Protection System - There are several lightning protection rods installed on the roof. The rods are connected to the ground by using stranded aluminum cables from the roof top all the way to the ground floor.

Grounding - The present grounding system is adequate. All equipment are properly bonded to the ground.

Site Assessment Report - S456001;Kelley, William

Auditorium – The auditorium general lighting uses decorative light fixtures with adequate lumens. The stage lighting has updated lighting and controller. Also, the auditorium has updated sound system.

Elevators – This school has a fairly new elevator (traction 5 HP).

GROUNDS (SITE):

There is no parking lot at the site; staff parking is located on a separate lot across Marston Street. Play yard in asphalt paving in fair condition with newly added turf area, play structure, and fall protection all in good condition. Perimeter fencing is aluminum fence in good condition. The building is accessible via ramp on northeast side. There is no landscaping on site.

Site Lighting - The school has some exterior lighting. However, a few pole-mounted lights are needed to provide adequate lighting for the grounds security and safety of people at night.

Site Paging – The school has some exterior speakers, however a few additional speakers are needed for proper communication with students playing outside.

ACCESSIBILITY:

Generally, the building has accessible routes per ADA requirements; however, floors other than the ground floor are not accessible due to non-compliant elevator cabin. Toilets are not equipped with accessible fixtures and accessories, such as grab bars, and accessible partitions. Most of the doors in the building do not have ADA required door handles.

RECOMMENDATIONS:

- Install caged ladder to access lower roof over entry/lobby area
- Install safety railing at roof access hatch near roof edge
- Replace interior doors hardware with lever type handles for accessibility
- Replace non-ADA compliant toilet partitions; reconfigure remaining toilet partitions
- Install new signage throughout
- Replace suspended acoustic ceiling system – 25% of suspended ceiling damaged
- Replace existing elevator with an ADA compliant 2500 lb elevator serving all floors
- Replace thirty five (35) water closets, in use beyond their service life, in the restrooms with new code compliant fixtures.
- Replace eighteen (18) urinals, in use beyond their service life, in the restrooms with new low flow fixtures.
- Replace four (4) wall hung drinking fountains and integral refrigerated coolers in the corridors. These units are beyond their service life and most are NOT accessible type.
- Hire a qualified contractor to perform a detailed inspection of the domestic water piping, in use beyond its service life, and replace any damaged piping.
- Hire a qualified contractor to perform a detailed examination of the sanitary waste piping using visual inspection and video cameras to locate and replace any damaged piping and to further quantify the extent of potential failures.
- Hire a qualified contractor to perform a detailed examination of the rain water drainage piping using visual inspection and video cameras to locate and replace any damaged piping and to further quantify the extent of potential failures.
- Hire a qualified contractor to examine the distribution piping, in service for over 50 years, and replace any damaged piping and to further quantify the extent of potential failures.
- Replace two (2) 7.5HP end-suction hot water supply pumps in the boiler room which are beyond their service lives and in poor condition.
- Remove the existing unit ventilators and install units with hot and chilled water coils and integral heat exchangers to introduce outdoor air to the building.
- Remove the existing heating and ventilation unit, which is beyond its service life, and provide ventilation for the Gymnasium/Cafeteria by installing a fan coil air handling unit hung from the structure with outdoor air ducted to the unit from louvers in the window openings.
- Provide ventilation for the Auditorium by installing a fan coil air handling unit installed in the basement boiler room with outdoor air ducted to the unit from existing louvers.
- Remove the existing heating and ventilation unit, which is beyond its service life, and provide ventilation for the administration offices by installing a fan coil air handling unit hung from the structure with outdoor air ducted to the unit from the existing louvers.
- Remove the window air conditioning units and install a 200 ton air-cooled chiller with chilled water distribution piping and pumps located in a mechanical room to supply more reliable air conditioning for the building with a much longer service life.

Site Assessment Report - S456001;Kelley, William

- Replace four (4) roof mounted exhaust fans serving the restrooms, science lab, and art lab which are in poor condition.
- Replace nine (9) roof mounted power ventilators allowing relief air to escape from the building which are in poor condition.
- Replace the existing controls for the HVAC systems with modern DDC modules, valves and actuators to improve reliability and energy efficiency. Provide a new building automation system (BAS) with communication interface to the preferred system in use throughout the District.
- Install a fire protection sprinkler system with quick response type heads to reduce insurance costs by providing protection for the property. A fire pump may be required depending on the available city water pressure.
- Install a new and upgraded electrical service for this school to handle existing loads plus any additional mechanical loads.
- Install new 120V lighting and receptacle panels throughout the building (total of 10)
- Install new lighting system for 80% of the building.
- Install new receptacles for the building
- Install new clock system
- Install new video surveillance system.
- Install new automated/addressable FA system.
- Install a new Emergency generator.
- Install new exit lights and emergency lights.
- Install additional pole-mounted lights for the grounds
- Install additional exterior speakers for the grounds

Attributes:

General Attributes:

| | | | |
|----------|-----------------|--------------|--------------|
| Active: | Open | Bldg Lot Tm: | Lot 5 / Tm 4 |
| Status: | Accepted by SDP | Team: | Tm 4 |
| Site ID: | S456001 | | |

Site Condition Summary

The Table below shows the CI and FCI for each major system shown at the UNIFORMAT classification Level II. Note that Systems with lower FCIs require less investment than systems with higher FCIs.


Current Investment Requirement and Condition by Unifomat Classification

| UNIFORMAT Classification | RSLI% | FCI % | Current Repair |
|---------------------------------|----------------|----------------|------------------------|
| A10 - Foundations | 50.00 % | 0.00 % | \$0.00 |
| A20 - Basement Construction | 50.00 % | 0.00 % | \$0.00 |
| B10 - Superstructure | 50.00 % | 0.00 % | \$0.00 |
| B20 - Exterior Enclosure | 56.97 % | 0.21 % | \$6,934.61 |
| B30 - Roofing | 25.00 % | 0.54 % | \$6,710.94 |
| C10 - Interior Construction | 48.14 % | 5.15 % | \$84,627.08 |
| C20 - Stairs | 50.00 % | 0.00 % | \$0.00 |
| C30 - Interior Finishes | 41.05 % | 1.54 % | \$54,296.75 |
| D10 - Conveying | 25.00 % | 8.08 % | \$39,791.67 |
| D20 - Plumbing | 106.12 % | 48.55 % | \$1,421,764.87 |
| D30 - HVAC | 93.22 % | 82.14 % | \$6,578,899.26 |
| D40 - Fire Protection | 105.71 % | 158.77 % | \$1,029,992.15 |
| D50 - Electrical | 110.11 % | 61.54 % | \$2,604,430.04 |
| E10 - Equipment | 57.14 % | 0.00 % | \$0.00 |
| E20 - Furnishings | 62.50 % | 0.00 % | \$0.00 |
| G20 - Site Improvements | 60.06 % | 0.00 % | \$0.00 |
| G40 - Site Electrical Utilities | 106.67 % | 66.66 % | \$217,773.29 |
| Totals: | 68.40 % | 28.18 % | \$12,045,220.66 |

Condition Deficiency Priority

| Facility Name | Gross Area (S.F.) | FCI % | 1 - Response Time (< 2 yr) | 2 - Response Time (2-3 yrs) | 3 - Response Time (3-4 yrs) | 4 - Response Time (4-5 yrs) | 5 - Response Time (> 5 yrs) |
|-------------------------|-------------------|--------------|----------------------------|-----------------------------|-----------------------------|-----------------------------|-----------------------------|
| B456001;Kelley, William | 72,000 | 28.64 | \$1,036,703.09 | \$683,073.81 | \$5,632,400.25 | \$3,352,116.84 | \$1,123,153.38 |
| G456001;Grounds | 75,100 | 15.11 | \$0.00 | \$0.00 | \$169,818.66 | \$47,954.63 | \$0.00 |
| Total: | | 28.18 | \$1,036,703.09 | \$683,073.81 | \$5,802,218.91 | \$3,400,071.47 | \$1,123,153.38 |

Deficiencies By Priority



Executive Summary

Building condition is evaluated based on the functional systems and elements of a building and organized according to the UNIFORMAT II Elemental Classification. The grouping of these systems and elements and applying a current replacement value to them develops a representative building cost model. Cost Models are developed for similar building types and functions. Systems and their elements are evaluated based on their current replacement values, life cycles, installation dates and next renewal dates. Systems and their elements that are within their useful lives are further evaluated to identify current deficient conditions that may have a significant impact on a system's or element's remaining service life, and to determine if they are beyond their predicted expected life. The system's or element's current replacement value is based on RS Means Commercial Cost Data.

Following are the cost model's system details for this facility. The Replacement Value is the amount needed to replace the property of the same present value. The Current Repair Amount, also known as Condition Needs, represents the budgeted contractor installed costs plus owner's soft costs for the repair, replacement or renewal for a component or system level deficiency. It excludes contributing costs for other components or systems that might also be associated with the corrective actions due to packaging the work. Facility Condition Index (FCI) FCI is an industry-standard measurement of facility condition calculated as the ratio of the costs to correct a facility's deficiencies to the facility's Current Replacement Value. It ranges from 0% (new) to 100% (very poor). Condition Index (CI) is calculated as the sum of a renewable system's Remaining Service Life (RSL) divided by the sum of a system's Replacement Value (both values exclude soft-cost to simplify calculation updates) expressed as a percentage ranging from 100% (new) to 0% (expired).

| | |
|--------------------|-------------------|
| Function: | Elementary School |
| Gross Area (SF): | 72,000 |
| Year Built: | 1965 |
| Last Renovation: | |
| Replacement Value: | \$41,298,632 |
| Repair Cost: | \$11,827,447.37 |
| Total FCI: | 28.64 % |
| Total RSLI: | 68.32 % |



Description:

Attributes:

General Attributes:

| | | | |
|-----------------|---------|----------|-----------------|
| Active: | Open | Bldg ID: | B456001 |
| Sewage Ejector: | Yes | Status: | Accepted by SDP |
| Site ID: | S456001 | | |

Condition Summary

The Table below shows the CI and FCI for each major building system shown at the UNIFORMAT classification Level II. Note that Systems with lower FCIs require less investment than systems with higher FCIs.

| UNIFORMAT Classification | RSLI % | FCI % | Current Repair Cost |
|-----------------------------|----------------|----------------|------------------------|
| A10 - Foundations | 50.00 % | 0.00 % | \$0.00 |
| A20 - Basement Construction | 50.00 % | 0.00 % | \$0.00 |
| B10 - Superstructure | 50.00 % | 0.00 % | \$0.00 |
| B20 - Exterior Enclosure | 56.97 % | 0.21 % | \$6,934.61 |
| B30 - Roofing | 25.00 % | 0.54 % | \$6,710.94 |
| C10 - Interior Construction | 48.14 % | 5.15 % | \$84,627.08 |
| C20 - Stairs | 50.00 % | 0.00 % | \$0.00 |
| C30 - Interior Finishes | 41.05 % | 1.54 % | \$54,296.75 |
| D10 - Conveying | 25.00 % | 8.08 % | \$39,791.67 |
| D20 - Plumbing | 106.12 % | 48.55 % | \$1,421,764.87 |
| D30 - HVAC | 93.22 % | 82.14 % | \$6,578,899.26 |
| D40 - Fire Protection | 105.71 % | 158.77 % | \$1,029,992.15 |
| D50 - Electrical | 110.11 % | 61.54 % | \$2,604,430.04 |
| E10 - Equipment | 57.14 % | 0.00 % | \$0.00 |
| E20 - Furnishings | 62.50 % | 0.00 % | \$0.00 |
| Totals: | 68.32 % | 28.64 % | \$11,827,447.37 |

Condition Detail

This section of the report contains results of the Facility Condition Assessment. The building is separated into system components based on UNIFORMAT II classification. The columns in the System Listing table below represent the following:

1. System Code: A code that identifies the system.
2. System Description: A brief description of a system present in the building.
3. Unit Price \$: The unit price of the system.
4. UoM: The unit of measure for of the system.
5. Qty: The quantity for the system
6. Life: anticipated service life for the system based on Building Owners and Managers Association (BOMA) recommendations.
7. Year Installed: The date of system installation.
8. Calc Next Renewal Year: The date of system expiration based on the life, NR stands for non renewable.
9. Next Renewal Year: The suggested system expiration date by the assessor based on visual inspection.
10. CI: The Condition Index of the system.
11. FCI: The Facility Condition Index of the system.
12. RSL: Remaining Service Life.
13. eCR: eCOMET Condition Rating (not used).
14. Deficiency \$: The financial investment to repair/replace system.

System Listing

The System Listing table below lists each of the systems organized by their UNIFORMAT II classification. The assessment team was tasked with recording the most recent replacement year of each system, determining the remaining service life based on the theoretical life, and evaluating the condition to confirm the forecast next replacement year. The system listing is the basis for all data contained in the Building Assessment Report.

Additionally, a condition rating (eCR) based on the following guidelines is provided as observed at the time of the assessment.

- Excellent (E) - No noticeable distress or damage. The entire system is free from observable defect.
- Very Good (VG) - Overall no serviceability reduction for the entire system. No degradation of critical components and minor distress and defect noticeable for some but not non critical components within the system.
- Good (G) - Slight or no serviceability reduction for the entire system. There may be noticeable defects for some non critical components and slight noticeable degradation of the critical components.
- Fair (F) - Overall serviceability is degraded but adequate. There may be moderate deterioration for very few of the critical components and few of the non critical components may have severe degradation.
- Marginal (MA) - Overall serviceability and reliability loss. Most if not all of the non critical components suffer from severe degradation and a few of the critical component may have severe degradation.
- Moderate (MO) - Overall a significant serviceability loss. Most if not all the components have severe degradation with the reminder of the component showing visible distress.
- Very Poor (VP) - Overall the system is barely functional. All of the components are severely degraded.
- Non-Functional (NF) - Overall the system does not function with all the components having no serviceability and suffer from severe degradation.

| System Code | System Description | Unit Price \$ | UoM | Qty | Life | Year Installed | Calc Next Renewal Year | Next Renewal Year | RSLI% | FCI% | RSL | eCR | Deficiency \$ | Replacement Value \$ |
|-------------|-------------------------|---------------|------|--------|------|----------------|------------------------|-------------------|---------|---------|-----|-----|---------------|----------------------|
| A1010 | Standard Foundations | \$24.32 | S.F. | 72,000 | 100 | 1965 | 2065 | | 50.00 % | 0.00 % | 50 | | | \$1,751,040 |
| A1030 | Slab on Grade | \$15.51 | S.F. | 72,000 | 100 | 1965 | 2065 | | 50.00 % | 0.00 % | 50 | | | \$1,116,720 |
| A2010 | Basement Excavation | \$13.07 | S.F. | 72,000 | 100 | 1965 | 2065 | | 50.00 % | 0.00 % | 50 | | | \$941,040 |
| A2020 | Basement Walls | \$23.02 | S.F. | 72,000 | 100 | 1965 | 2065 | | 50.00 % | 0.00 % | 50 | | | \$1,657,440 |
| B1010 | Floor Construction | \$92.20 | S.F. | 72,000 | 100 | 1965 | 2065 | | 50.00 % | 0.00 % | 50 | | | \$6,638,400 |
| B1020 | Roof Construction | \$24.11 | S.F. | 72,000 | 100 | 1965 | 2065 | | 50.00 % | 0.00 % | 50 | | | \$1,735,920 |
| B2010 | Exterior Walls | \$31.22 | S.F. | 72,000 | 100 | 1965 | 2065 | | 50.00 % | 0.31 % | 50 | | \$6,934.61 | \$2,247,840 |
| B2020 | Exterior Windows | \$13.63 | S.F. | 72,000 | 40 | 2005 | 2045 | | 75.00 % | 0.00 % | 30 | | | \$981,360 |
| B2030 | Exterior Doors | \$1.67 | S.F. | 72,000 | 25 | 2000 | 2025 | | 40.00 % | 0.00 % | 10 | | | \$120,240 |
| B3010105 | Built-Up | \$37.76 | S.F. | 31,402 | 20 | 2000 | 2020 | | 25.00 % | 0.00 % | 5 | | | \$1,185,740 |
| B3010120 | Single Ply Membrane | \$38.73 | S.F. | | 20 | | | | 0.00 % | 0.00 % | | | | \$0 |
| B3010130 | Preformed Metal Roofing | \$54.22 | S.F. | | 30 | | | | 0.00 % | 0.00 % | | | | \$0 |
| B3010140 | Shingle & Tile | \$38.73 | S.F. | | 20 | | | | 0.00 % | 0.00 % | | | | \$0 |
| B3020 | Roof Openings | \$0.68 | S.F. | 72,000 | 20 | 2000 | 2020 | | 25.00 % | 13.71 % | 5 | | \$6,710.94 | \$48,960 |
| C1010 | Partitions | \$14.93 | S.F. | 72,000 | 100 | 1965 | 2065 | | 50.00 % | 0.00 % | 50 | | | \$1,074,960 |
| C1020 | Interior Doors | \$3.76 | S.F. | 72,000 | 40 | 1965 | 2005 | 2025 | 25.00 % | 17.48 % | 10 | | \$47,308.40 | \$270,720 |
| C1030 | Fittings | \$4.12 | S.F. | 72,000 | 40 | 2000 | 2040 | | 62.50 % | 12.58 % | 25 | | \$37,318.68 | \$296,640 |
| C2010 | Stair Construction | \$1.28 | S.F. | 72,000 | 100 | 1965 | 2065 | | 50.00 % | 0.00 % | 50 | | | \$92,160 |

Site Assessment Report - B456001;Kelley, William

| System Code | System Description | Unit Price \$ | UoM | Qty | Life | Year Installed | Calc Next Renewal Year | Next Renewal Year | RSLI% | FCI% | RSL | eCR | Deficiency \$ | Replacement Value \$ |
|--------------|---------------------------------|---------------|------|--------|------|----------------|------------------------|-------------------|----------------|----------------|-----|-----|------------------------|----------------------|
| C3010230 | Paint & Covering | \$19.67 | S.F. | 72,000 | 10 | 2012 | 2022 | | 70.00 % | 0.00 % | 7 | | | \$1,416,240 |
| C3010231 | Vinyl Wall Covering | \$0.00 | S.F. | | 15 | | | | 0.00 % | 0.00 % | | | | \$0 |
| C3010232 | Wall Tile | \$0.00 | S.F. | | 30 | | | | 0.00 % | 0.00 % | | | | \$0 |
| C3020411 | Carpet | \$7.30 | S.F. | | 10 | | | | 0.00 % | 0.00 % | | | | \$0 |
| C3020412 | Terrazzo & Tile | \$75.52 | S.F. | | 50 | | | | 0.00 % | 0.00 % | | | | \$0 |
| C3020413 | Vinyl Flooring | \$9.68 | S.F. | 61,200 | 20 | 2000 | 2020 | | 25.00 % | 0.00 % | 5 | | | \$592,416 |
| C3020414 | Wood Flooring | \$22.27 | S.F. | | 25 | | | | 0.00 % | 0.00 % | | | | \$0 |
| C3020415 | Concrete Floor Finishes | \$0.97 | S.F. | 10,800 | 50 | 2000 | 2050 | | 70.00 % | 0.00 % | 35 | | | \$10,476 |
| C3030 | Ceiling Finishes | \$20.97 | S.F. | 72,000 | 25 | 1995 | 2020 | | 20.00 % | 3.60 % | 5 | | \$54,296.75 | \$1,509,840 |
| D1010 | Elevators and Lifts | \$6.84 | S.F. | 72,000 | 40 | 1985 | 2025 | | 25.00 % | 8.08 % | 10 | | \$39,791.67 | \$492,480 |
| D2010 | Plumbing Fixtures | \$31.58 | S.F. | 72,000 | 35 | 1965 | 2000 | 2052 | 105.71 % | 16.91 % | 37 | | \$384,422.04 | \$2,273,760 |
| D2020 | Domestic Water Distribution | \$2.90 | S.F. | 72,000 | 25 | 1965 | 1990 | 2042 | 108.00 % | 174.74 % | 27 | | \$364,849.90 | \$208,800 |
| D2030 | Sanitary Waste | \$2.90 | S.F. | 72,000 | 25 | 1965 | 1990 | 2042 | 108.00 % | 169.16 % | 27 | | \$353,213.96 | \$208,800 |
| D2040 | Rain Water Drainage | \$3.29 | S.F. | 72,000 | 30 | 1965 | 1995 | 2047 | 106.67 % | 134.79 % | 32 | | \$319,278.97 | \$236,880 |
| D3020 | Heat Generating Systems | \$18.67 | S.F. | 72,000 | 35 | 1996 | 2031 | | 45.71 % | 12.02 % | 16 | | \$161,580.94 | \$1,344,240 |
| D3030 | Cooling Generating Systems | \$24.48 | S.F. | 72,000 | 20 | | | 2037 | 110.00 % | 63.72 % | 22 | | \$1,123,153.38 | \$1,762,560 |
| D3040 | Distribution Systems | \$42.99 | S.F. | 72,000 | 25 | 1965 | 1990 | 2042 | 108.00 % | 121.14 % | 27 | | \$3,749,614.38 | \$3,095,280 |
| D3050 | Terminal & Package Units | \$11.60 | S.F. | 72,000 | 20 | 1965 | 1985 | 2027 | 60.00 % | 0.00 % | 12 | | | \$835,200 |
| D3060 | Controls & Instrumentation | \$13.50 | S.F. | 72,000 | 20 | 1965 | 1985 | 2037 | 110.00 % | 158.90 % | 22 | | \$1,544,550.56 | \$972,000 |
| D4010 | Sprinklers | \$8.02 | S.F. | 72,000 | 35 | | | 2052 | 105.71 % | 178.37 % | 37 | | \$1,029,992.15 | \$577,440 |
| D4020 | Standpipes | \$0.99 | S.F. | 72,000 | 35 | | | 2052 | 105.71 % | 0.00 % | 37 | | | \$71,280 |
| D5010 | Electrical Service/Distribution | \$9.70 | S.F. | 72,000 | 30 | 1965 | 1995 | 2047 | 106.67 % | 115.08 % | 32 | | \$803,749.73 | \$698,400 |
| D5020 | Lighting and Branch Wiring | \$34.68 | S.F. | 72,000 | 20 | 1965 | 1985 | 2037 | 110.00 % | 34.04 % | 22 | | \$850,069.28 | \$2,496,960 |
| D5030 | Communications and Security | \$12.99 | S.F. | 72,000 | 15 | 1965 | 1980 | 2032 | 113.33 % | 67.61 % | 17 | | \$632,327.22 | \$935,280 |
| D5090 | Other Electrical Systems | \$1.41 | S.F. | 72,000 | 30 | 1965 | 1995 | 2047 | 106.67 % | 313.52 % | 32 | | \$318,283.81 | \$101,520 |
| E1020 | Institutional Equipment | \$4.82 | S.F. | 72,000 | 35 | 2000 | 2035 | | 57.14 % | 0.00 % | 20 | | | \$347,040 |
| E1090 | Other Equipment | \$11.10 | S.F. | 72,000 | 35 | 2000 | 2035 | | 57.14 % | 0.00 % | 20 | | | \$799,200 |
| E2010 | Fixed Furnishings | \$2.13 | S.F. | 72,000 | 40 | 2000 | 2040 | | 62.50 % | 0.00 % | 25 | | | \$153,360 |
| Total | | | | | | | | | 68.32 % | 28.64 % | | | \$11,827,447.37 | \$41,298,632 |

System Notes

The facility description in the site executive summary contains an overview of each system. The notes listed below provide additional information on select systems found within the facility.

| | | |
|----------------|-----------------------|--------------------------------|
| System: | C3010 - Wall Finishes | This system contains no images |
| Note: | 100% Paint & Covering | |

| | | |
|----------------|-------------------------------|--------------------------------|
| System: | C3020 - Floor Finishes | This system contains no images |
| Note: | 85% - Vinyl Flooring | |
| | 15% - Concrete Floor Finishes | |

Renewal Schedule

eCOMET forecasts future Capital Renewal funding needed to address expiring systems based on the Next Renewal year found in the Cost Models. A 3% annual inflation factor is applied to the costs for systems expiring in future years. The table below reflects recommended Capital Renewal funding needs over the next 10 years. Note: Cells with a zero value indicate systems for which renewal is not scheduled in that year.

Inflation Rate: 3%

| System | Current Deficiencies | 2016 | 2017 | 2018 | 2019 | 2020 | 2021 | 2022 | 2023 | 2024 | 2025 | Total |
|--------------------------------------|----------------------|------------|------------|------------|------------|--------------------|------------|--------------------|------------|------------|--------------------|---------------------|
| Total: | \$11,827,447 | \$0 | \$0 | \$0 | \$0 | \$4,255,291 | \$0 | \$1,915,976 | \$0 | \$0 | \$1,305,996 | \$19,304,711 |
| * A - Substructure | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| * A10 - Foundations | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| A1010 - Standard Foundations | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| A1030 - Slab on Grade | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| * A20 - Basement Construction | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| A2010 - Basement Excavation | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| A2020 - Basement Walls | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| B - Shell | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| B10 - Superstructure | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| B1010 - Floor Construction | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| B1020 - Roof Construction | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| B20 - Exterior Enclosure | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| B2010 - Exterior Walls | \$6,935 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$6,935 |
| B2020 - Exterior Windows | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| B2030 - Exterior Doors | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$177,752 | \$177,752 |
| B30 - Roofing | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| B3010 - Roof Coverings | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| B3010105 - Built-Up | \$0 | \$0 | \$0 | \$0 | \$0 | \$1,512,056 | \$0 | \$0 | \$0 | \$0 | \$0 | \$1,512,056 |
| B3010120 - Single Ply Membrane | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| B3010130 - Preformed Metal Roofing | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| B3010140 - Shingle & Tile | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| B3020 - Roof Openings | \$6,711 | \$0 | \$0 | \$0 | \$0 | \$62,434 | \$0 | \$0 | \$0 | \$0 | \$0 | \$69,145 |
| C - Interiors | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| C10 - Interior Construction | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| C1010 - Partitions | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |

Site Assessment Report - B456001;Kelley, William

| | | | | | | | | | | | | |
|-------------------------------------|-------------|-----|-----|-----|-----|-------------|-----|-------------|-----|-----|-----------|-------------|
| C1020 - Interior Doors | \$47,308 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$400,208 | \$447,516 |
| C1030 - Fittings | \$37,319 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$37,319 |
| C20 - Stairs | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| C2010 - Stair Construction | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| C30 - Interior Finishes | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| C3010 - Wall Finishes | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| C3010230 - Paint & Covering | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$1,915,976 | \$0 | \$0 | \$0 | \$1,915,976 |
| C3010231 - Vinyl Wall Covering | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| C3010232 - Wall Tile | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| C3020 - Floor Finishes | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| C3020411 - Carpet | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| C3020412 - Terrazzo & Tile | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| C3020413 - Vinyl Flooring | \$0 | \$0 | \$0 | \$0 | \$0 | \$755,450 | \$0 | \$0 | \$0 | \$0 | \$0 | \$755,450 |
| C3020414 - Wood Flooring | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| C3020415 - Concrete Floor Finishes | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| C3030 - Ceiling Finishes | \$54,297 | \$0 | \$0 | \$0 | \$0 | \$1,925,350 | \$0 | \$0 | \$0 | \$0 | \$0 | \$1,979,647 |
| D - Services | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| D10 - Conveying | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| D1010 - Elevators and Lifts | \$39,792 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$728,037 | \$767,829 |
| D20 - Plumbing | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| D2010 - Plumbing Fixtures | \$384,422 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$384,422 |
| D2020 - Domestic Water Distribution | \$364,850 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$364,850 |
| D2030 - Sanitary Waste | \$353,214 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$353,214 |
| D2040 - Rain Water Drainage | \$319,279 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$319,279 |
| D30 - HVAC | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| D3020 - Heat Generating Systems | \$161,581 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$161,581 |
| D3030 - Cooling Generating Systems | \$1,123,153 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$1,123,153 |
| D3040 - Distribution Systems | \$3,749,614 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$3,749,614 |
| D3050 - Terminal & Package Units | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| D3060 - Controls & Instrumentation | \$1,544,551 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$1,544,551 |
| D40 - Fire Protection | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| D4010 - Sprinklers | \$1,029,992 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$1,029,992 |
| D4020 - Standpipes | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |


Site Assessment Report - B456001;Kelley, William

| | | | | | | | | | | | | |
|---|-----------|-----|-----|-----|-----|-----|-----|-----|-----|-----|-----|-----------|
| D50 - Electrical | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| D5010 - Electrical Service/Distribution | \$803,750 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$803,750 |
| D5020 - Lighting and Branch Wiring | \$850,069 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$850,069 |
| D5030 - Communications and Security | \$632,327 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$632,327 |
| D5090 - Other Electrical Systems | \$318,284 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$318,284 |
| E - Equipment & Furnishings | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| E10 - Equipment | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| E1020 - Institutional Equipment | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| E1090 - Other Equipment | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| E20 - Furnishings | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| E2010 - Fixed Furnishings | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |

* Indicates non-renewable system

Forecasted Sustainment Requirement

The following chart shows the current building deficiencies and forecasting sustainment requirements over the next ten years.




10 Year FCI Forecast by Investment Scenario

The chart below illustrates the effect of various investment levels on the building FCI for the next 10 years. The levels of investment shown below include:

- Current FCI: a variable investment amount based on renewing expired systems to maintain the current FCI for the building
- 2% Investment: an annual investment of 2% of the replacement value of the building, escalated for inflation
- 4% Investment: an annual investment of 4% of the replacement value of the building, escalated for inflation


Facility Investment vs. FCI Forecast



| Year | Investment Amount Current FCI - 28.64% | 2% Investment | | 4% Investment | |
|---------------|---|-----------------------|---------|------------------------|---------|
| | | Amount | FCI | Amount | FCI |
| 2016 | \$0 | \$850,752.00 | 26.64 % | \$1,701,504.00 | 24.64 % |
| 2017 | \$15,916,530 | \$876,274.00 | 60.97 % | \$1,752,549.00 | 56.97 % |
| 2018 | \$0 | \$902,563.00 | 58.97 % | \$1,805,125.00 | 52.97 % |
| 2019 | \$0 | \$929,639.00 | 56.97 % | \$1,859,279.00 | 48.97 % |
| 2020 | \$4,255,291 | \$957,529.00 | 63.85 % | \$1,915,057.00 | 53.85 % |
| 2021 | \$0 | \$986,255.00 | 61.85 % | \$1,972,509.00 | 49.85 % |
| 2022 | \$1,915,976 | \$1,015,842.00 | 63.63 % | \$2,031,684.00 | 49.63 % |
| 2023 | \$0 | \$1,046,317.00 | 61.63 % | \$2,092,635.00 | 45.63 % |
| 2024 | \$0 | \$1,077,707.00 | 59.63 % | \$2,155,414.00 | 41.63 % |
| 2025 | \$1,305,996 | \$1,110,038.00 | 59.98 % | \$2,220,076.00 | 39.98 % |
| Total: | \$23,393,793 | \$9,752,916.00 | | \$19,505,832.00 | |

Deficiency Summary by System


Current deficiencies included assemblies that have reached or exceeded their design life or components of the assemblies that are in need of repair. Assemblies that have reached their design life are identified as current deficiencies and assigned the distress 'Beyond Useful Life'. The following chart lists all current deficiencies associated with this facility.



Budget Estimate Total: \$11,827,447.37

Deficiency Summary by Priority

The following chart shows the total repair costs broken down by priority. Assessors assigned deficiencies within eCOMET to one of the following priority categories:



Budget Estimate Total: \$11,827,447.37


Deficiency By Priority Investment Table

The table below shows the current investment cost grouped by deficiency priority and building system.

| System Code | System Description | 1 - Response Time (< 2 yr) | 2 - Response Time (2-3 yrs) | 3 - Response Time (3-4 yrs) | 4 - Response Time (4-5 yrs) | 5 - Response Time (> 5 yrs) | Total |
|-------------|---------------------------------|----------------------------|-----------------------------|-----------------------------|-----------------------------|-----------------------------|-----------------|
| B2010 | Exterior Walls | \$0.00 | \$0.00 | \$6,934.61 | \$0.00 | \$0.00 | \$6,934.61 |
| B3020 | Roof Openings | \$6,710.94 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$6,710.94 |
| C1020 | Interior Doors | \$0.00 | \$0.00 | \$47,308.40 | \$0.00 | \$0.00 | \$47,308.40 |
| C1030 | Fittings | \$0.00 | \$15,645.68 | \$0.00 | \$21,673.00 | \$0.00 | \$37,318.68 |
| C3030 | Ceiling Finishes | \$0.00 | \$54,296.75 | \$0.00 | \$0.00 | \$0.00 | \$54,296.75 |
| D1010 | Elevators and Lifts | \$0.00 | \$39,791.67 | \$0.00 | \$0.00 | \$0.00 | \$39,791.67 |
| D2010 | Plumbing Fixtures | \$0.00 | \$0.00 | \$384,422.04 | \$0.00 | \$0.00 | \$384,422.04 |
| D2020 | Domestic Water Distribution | \$0.00 | \$0.00 | \$0.00 | \$364,849.90 | \$0.00 | \$364,849.90 |
| D2030 | Sanitary Waste | \$0.00 | \$0.00 | \$353,213.96 | \$0.00 | \$0.00 | \$353,213.96 |
| D2040 | Rain Water Drainage | \$0.00 | \$0.00 | \$319,278.97 | \$0.00 | \$0.00 | \$319,278.97 |
| D3020 | Heat Generating Systems | \$0.00 | \$161,580.94 | \$0.00 | \$0.00 | \$0.00 | \$161,580.94 |
| D3030 | Cooling Generating Systems | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$1,123,153.38 | \$1,123,153.38 |
| D3040 | Distribution Systems | \$0.00 | \$0.00 | \$3,040,816.65 | \$708,797.73 | \$0.00 | \$3,749,614.38 |
| D3060 | Controls & Instrumentation | \$0.00 | \$0.00 | \$0.00 | \$1,544,550.56 | \$0.00 | \$1,544,550.56 |
| D4010 | Sprinklers | \$1,029,992.15 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$1,029,992.15 |
| D5010 | Electrical Service/Distribution | \$0.00 | \$411,758.77 | \$0.00 | \$391,990.96 | \$0.00 | \$803,749.73 |
| D5020 | Lighting and Branch Wiring | \$0.00 | \$0.00 | \$850,069.28 | \$0.00 | \$0.00 | \$850,069.28 |
| D5030 | Communications and Security | \$0.00 | \$0.00 | \$312,072.53 | \$320,254.69 | \$0.00 | \$632,327.22 |
| D5090 | Other Electrical Systems | \$0.00 | \$0.00 | \$318,283.81 | \$0.00 | \$0.00 | \$318,283.81 |
| | Total: | \$1,036,703.09 | \$683,073.81 | \$5,632,400.25 | \$3,352,116.84 | \$1,123,153.38 | \$11,827,447.37 |

Deficiency Summary by Category

The following chart shows the total repair costs broken down by deficiency categories. Assessors assigned deficiencies to one of the following categories:



Deficiency Details by Priority

The deficiency detail notes listed below provide additional information on identified deficiencies found within the facility.

Priority 1 - Response Time (< 2 yr):

System: B3020 - Roof Openings



Location: Roof access

Distress: Building / MEP Codes

Category: 2 - Code Compliance

Priority: 1 - Response Time (< 2 yr)

Correction: Install safety guard rails at roof perimeter (OSHA required if roof hatch is 10' from roof edge).

Qty: 10.00

Unit of Measure: L.F.

Estimate: \$6,710.94

Assessor Name: System

Date Created: 02/12/2016

Notes: Install safety railing at roof access hatch near roof edge

System: D4010 - Sprinklers



Location: Throughout building

Distress: Life Safety / NFPA / PFD

Category: 2 - Code Compliance

Priority: 1 - Response Time (< 2 yr)

Correction: Install a fire protection sprinkler system

Qty: 72,000.00

Unit of Measure: S.F.

Estimate: \$1,029,992.15

Assessor Name: System

Date Created: 02/02/2016

Notes: Install a fire protection sprinkler system with quick response type heads to reduce insurance costs by providing protection for the property. A fire pump may be required depending on the available city water pressure.

Priority 2 - Response Time (2-3 yrs):

System: C1030 - Fittings



Location: Toilets

Distress: Accessibility

Category: 2 - Code Compliance

Priority: 2 - Response Time (2-3 yrs)

Correction: Remove and replace damaged toilet partitions - handicap units

Qty: 16.00

Unit of Measure: Ea.

Estimate: \$15,645.68

Assessor Name: System

Date Created: 02/12/2016

Notes: Replace non-ADA compliant toilet partitions; reconfigure remaining toilet partitions

System: C3030 - Ceiling Finishes



Location: B456001;Kelley, William

Distress: Damaged

Category: 3 - Operations / Maint.

Priority: 2 - Response Time (2-3 yrs)

Correction: Remove and replace suspended acoustic ceilings - lighting not included

Qty: 3,600.00

Unit of Measure: S.F.

Estimate: \$54,296.75

Assessor Name: System

Date Created: 02/12/2016

Notes: Replace suspended acoustic ceiling system – 25% of suspended ceiling damaged

System: D1010 - Elevators and Lifts



Location: Elevator

Distress: Accessibility

Category: 2 - Code Compliance

Priority: 2 - Response Time (2-3 yrs)

Correction: Modernize or upgrade the elevator cab or to comply with ADA - exact scope of work estimate not available - total cost is sufficient

Qty: 1.00

Unit of Measure: Ea.

Estimate: \$39,791.67

Assessor Name: System

Date Created: 02/12/2016

Notes: Replace existing elevator with an ADA compliant 2500 lb elevator serving all floors

System: D3020 - Heat Generating Systems



Location: Boiler room

Distress: Beyond Service Life

Category: 3 - Operations / Maint.

Priority: 2 - Response Time (2-3 yrs)

Correction: Replace pump, base-mounted, end suction HHW (4" size, 7-1/2 HP, to 350 GPM)

Qty: 2.00

Unit of Measure: Ea.


Estimate: \$161,580.94

Assessor Name: System

Date Created: 02/02/2016

Notes: Replace two (2) 7.5HP end-suction hot water supply pumps in the boiler room which are beyond their service lives and in poor condition.

System: D5010 - Electrical Service/Distribution



Location: throughout the building

Distress: Beyond Service Life

Category: 3 - Operations / Maint.

Priority: 2 - Response Time (2-3 yrs)

Correction: Remove and Replace Panelboard - 400 amp

Qty: 1.00

Unit of Measure: Ea.

Estimate: \$411,758.77

Assessor Name: System

Date Created: 02/12/2016

Notes: Install new 120V lighting and receptacle panels throughout the building (total of 10)

Priority 3 - Response Time (3-4 yrs):

System: B2010 - Exterior Walls



Location: Lobby roof

Distress: Health Hazard / Risk

Category: 1 - Health & Safety

Priority: 3 - Response Time (3-4 yrs)

Correction: Add fixed ladders to wall

Qty: 25.00

Unit of Measure: V.L.F.

Estimate: \$6,934.61

Assessor Name: System

Date Created: 02/12/2016

Notes: Install caged ladder to access lower roof over entry/lobby area

System: C1020 - Interior Doors



Location: Throughout

Distress: Accessibility

Category: 2 - Code Compliance

Priority: 3 - Response Time (3-4 yrs)

Correction: Replace door knobs with compliant lever type

Qty: 85.00

Unit of Measure: Ea.


Estimate: \$47,308.40

Assessor Name: System

Date Created: 02/12/2016

Notes: Replace interior doors hardware with lever type handles for accessibility

System: D2010 - Plumbing Fixtures



Location: Restrooms

Distress: Beyond Service Life

Category: 3 - Operations / Maint.

Priority: 3 - Response Time (3-4 yrs)

Correction: Remove and replace or replace water closet - quantify additional units

Qty: 35.00

Unit of Measure: Ea.


Estimate: \$261,408.72

Assessor Name: System

Date Created: 02/02/2016

Notes: Replace thirty five (35) water closets, in use beyond their service life, in the restrooms with new code compliant fixtures.

System: D2010 - Plumbing Fixtures



Location: Corridors

Distress: Beyond Service Life

Category: 3 - Operations / Maint.

Priority: 3 - Response Time (3-4 yrs)

Correction: Remove and replace water fountains to meet ADA - includes high and low fountains and new recessed alcove

Qty: 4.00

Unit of Measure: Ea.

Estimate: \$62,771.59

Assessor Name: System

Date Created: 02/02/2016

Notes: Replace four (4) wall hung drinking fountains and integral refrigerated coolers in the corridors. These units are beyond their service life and most are NOT accessible type.

System: D2010 - Plumbing Fixtures



Location: Restrooms

Distress: Beyond Service Life

Category: 3 - Operations / Maint.

Priority: 3 - Response Time (3-4 yrs)

Correction: Remove and replace or replace wall hung urinals

Qty: 18.00

Unit of Measure: Ea.

Estimate: \$60,241.73

Assessor Name: System

Date Created: 02/02/2016

Notes: Replace eighteen (18) urinals, in use beyond their service life, in the restrooms with new low flow fixtures.

System: D2030 - Sanitary Waste



Location: Throughout building

Distress: Beyond Service Life

Category: 3 - Operations / Maint.

Priority: 3 - Response Time (3-4 yrs)

Correction: Inspect sanitary waste piping and replace damaged sections. (+50KSF)

Qty: 72,000.00

Unit of Measure: S.F.

Estimate: \$353,213.96

Assessor Name: System

Date Created: 02/02/2016

Notes: Hire a qualified contractor to perform a detailed examination of the sanitary waste piping using visual inspection and video cameras to locate and replace any damaged piping and to further quantify the extent of potential failures.

System: D2040 - Rain Water Drainage



Location: Throughout building

Distress: Beyond Service Life

Category: 3 - Operations / Maint.

Priority: 3 - Response Time (3-4 yrs)

Correction: Inspect internal rain water drainage piping and replace pipe - based on SF of multi-story building - insert SF of building

Qty: 72,000.00

Unit of Measure: S.F.

Estimate: \$319,278.97

Assessor Name: System

Date Created: 02/02/2016

Notes: Hire a qualified contractor to perform a detailed examination of the rain water drainage piping using visual inspection and video cameras to locate and replace any damaged piping and to further quantify the extent of potential failures.

System: D3040 - Distribution Systems



Location: Classrooms

Distress: Beyond Service Life

Category: 3 - Operations / Maint.

Priority: 3 - Response Time (3-4 yrs)

Correction: Replace classroom unit ventilator (htg/clg coils, 5 tons, 2,000 CFM)

Qty: 34.00

Unit of Measure: Ea.

Estimate: \$1,695,874.87

Assessor Name: System

Date Created: 02/02/2016

Notes: Remove the existing unit ventilators and install units with hot and chilled water coils and integral heat exchangers to introduce outdoor air to the building.

System: D3040 - Distribution Systems



Location: Gymnasium/Cafeteria

Distress: Beyond Service Life

Category: 3 - Operations / Maint.

Priority: 3 - Response Time (3-4 yrs)

Correction: Install HVAC unit for Gymnasium (single station).

Qty: 6,000.00

Unit of Measure: S.F.

Estimate: \$362,060.10

Assessor Name: System

Date Created: 02/02/2016

Notes: Remove the existing heating and ventilation unit, which is beyond its service life, and provide ventilation for the Gymnasium/Cafeteria by installing a fan coil air handling unit hung from the structure with outdoor air ducted to the unit from louvers in the window openings.

System: D3040 - Distribution Systems



Location: Auditorium

Distress: Building / MEP Codes

Category: 2 - Code Compliance

Priority: 3 - Response Time (3-4 yrs)

Correction: Install HVAC unit for Administration (2000 students).

Qty: 676.00

Unit of Measure: Student

Estimate: \$292,588.81

Assessor Name: System

Date Created: 02/02/2016

Notes: Provide ventilation for the Auditorium by installing a fan coil air handling unit installed in the basement boiler room with outdoor air ducted to the unit from existing louvers.

System: D3040 - Distribution Systems



Location: Administration offices

Distress: Beyond Service Life

Category: 3 - Operations / Maint.

Priority: 3 - Response Time (3-4 yrs)

Correction: Install HVAC unit for Administration (2000 students).

Qty: 676.00

Unit of Measure: Student

Estimate: \$292,588.81

Assessor Name: System

Date Created: 02/02/2016

Notes: Remove the existing heating and ventilation unit, which is beyond its service life, and provide ventilation for the administration offices by installing a fan coil air handling unit hung from the structure with outdoor air ducted to the unit from the existing louvers.

System: D3040 - Distribution Systems



Location: Roof

Distress: Beyond Service Life

Category: 3 - Operations / Maint.

Priority: 3 - Response Time (3-4 yrs)

Correction: Replace power roof ventilator (24" dia.)

Qty: 9.00

Unit of Measure: Ea.

Estimate: \$245,355.03

Assessor Name: System

Date Created: 02/02/2016

Notes: Replace nine (9) roof mounted power ventilators allowing relief air to escape from the building which are in poor condition.

System: D3040 - Distribution Systems



Location: Roof

Distress: Beyond Service Life

Category: 3 - Operations / Maint.

Priority: 3 - Response Time (3-4 yrs)

Correction: Replace utility set exhaust fan (5 HP)

Qty: 4.00

Unit of Measure: Ea.


Estimate: \$152,349.03

Assessor Name: System

Date Created: 02/02/2016

Notes: Replace four (4) roof mounted exhaust fans serving the restrooms, science lab, and art lab which are in poor condition.

System: D5020 - Lighting and Branch Wiring



Location: throughout the building

Distress: Beyond Service Life

Category: 3 - Operations / Maint.

Priority: 3 - Response Time (3-4 yrs)

Correction: Replace Lighting Fixtures (SF)

Qty: 0.00

Unit of Measure: S.F.

Estimate: \$517,820.10

Assessor Name: System

Date Created: 02/12/2016

Notes: Install new lighting system for 80% of the building.
74,000 SF x 80% = 59,200 SF

System: D5020 - Lighting and Branch Wiring



Location: throughout the building

Distress: Inadequate

Category: 4 - Capital Improvement

Priority: 3 - Response Time (3-4 yrs)

Correction: Replace Wiring Devices (SF) - surface mounted conduit and boxes

Qty: 0.00

Unit of Measure: S.F.

Estimate: \$332,249.18

Assessor Name: System

Date Created: 02/12/2016

Notes: Install new receptacles for the building (80% of the building)
 $74,000 \times 80\% = 59,200$ SF

System: D5030 - Communications and Security



Location: throughout the building

Distress: Health Hazard / Risk

Category: 1 - Health & Safety

Priority: 3 - Response Time (3-4 yrs)

Correction: Replace fire alarm system

Qty: 1.00

Unit of Measure: S.F.

Estimate: \$312,072.53

Assessor Name: System

Date Created: 02/12/2016

Notes: Install new automated/addressable FA system.

System: D5090 - Other Electrical Systems



Location: throughout the building

Distress: Beyond Service Life

Category: 3 - Operations / Maint.

Priority: 3 - Response Time (3-4 yrs)

Correction: Replace Emergency/Exit Lighting

Qty: 1.00

Unit of Measure: Ea.

Estimate: \$193,493.14

Assessor Name: System

Date Created: 02/12/2016

Notes: Install new exit lights and emergency lights.

System: D5090 - Other Electrical Systems

This deficiency has no image.

Location: electrical room

Distress: Inadequate

Category: 4 - Capital Improvement

Priority: 3 - Response Time (3-4 yrs)

Correction: Add Standby Generator System

Qty: 1.00

Unit of Measure: Ea.

Estimate: \$124,790.67

Assessor Name: System

Date Created: 02/12/2016

Notes: Install a new Emergency generator.

Note: There is no picture attached since school presently does not have an emergency generator.

Priority 4 - Response Time (4-5 yrs):

System: C1030 - Fittings



Location: Throughout

Distress: Inadequate

Category: 4 - Capital Improvement

Priority: 4 - Response Time (4-5 yrs)

Correction: Replace missing or damaged signage - insert the number of rooms

Qty: 80.00

Unit of Measure: Ea.

Estimate: \$21,673.00

Assessor Name: System

Date Created: 02/12/2016

Notes: Install new signage throughout

System: D2020 - Domestic Water Distribution



Location: Throughout building

Distress: Beyond Service Life

Category: 3 - Operations / Maint.

Priority: 4 - Response Time (4-5 yrs)

Correction: Replace domestic water piping (75 KSF)

Qty: 72,000.00

Unit of Measure: S.F.

Estimate: \$364,849.90

Assessor Name: System

Date Created: 02/02/2016

Notes: Hire a qualified contractor to perform a detailed inspection of the domestic water piping, in use beyond its service life, and replace any damaged piping.

System: D3040 - Distribution Systems



Location: Throughout building

Distress: Beyond Service Life

Category: 3 - Operations / Maint.

Priority: 4 - Response Time (4-5 yrs)

Correction: Replace hydronic heating piping (75KSF)

Qty: 72,000.00

Unit of Measure: S.F.

Estimate: \$708,797.73

Assessor Name: System

Date Created: 02/02/2016

Notes: Hire a qualified contractor to examine the distribution piping, in service for over 50 years, and replace any damaged piping and to further quantify the extent of potential failures.

System: D3060 - Controls & Instrumentation



Location: Throughout building

Distress: Beyond Service Life

Category: 3 - Operations / Maint.

Priority: 4 - Response Time (4-5 yrs)

Correction: Replace pneumatic controls with DDC (75KSF)

Qty: 72,000.00

Unit of Measure: S.F.

Estimate: \$1,544,550.56

Assessor Name: System

Date Created: 02/02/2016

Notes: Replace the existing controls for the HVAC systems with modern DDC modules, valves and actuators to improve reliability and energy efficiency. Provide a new building automation system (BAS) with communication interface to the preferred system in use throughout the District.

System: D5010 - Electrical Service/Distribution



Location: electrical room

Distress: Beyond Service Life

Category: 3 - Operations / Maint.

Priority: 4 - Response Time (4-5 yrs)

Correction: Replace Service Transformer, Add Switchboard

Qty: 0.00

Unit of Measure: Ea.


Estimate: \$391,990.96

Assessor Name: System

Date Created: 02/12/2016

Notes: Install a new and upgraded electrical service for this school to handle existing loads plus any additional mechanical loads.

System: D5030 - Communications and Security



Location: throughout the building

Distress: Beyond Service Life

Category: 3 - Operations / Maint.

Priority: 4 - Response Time (4-5 yrs)

Correction: Replace clock/program system

Qty: 0.00

Unit of Measure: Ea.

Estimate: \$238,589.19

Assessor Name: System

Date Created: 02/12/2016

Notes: Install new clock system

System: D5030 - Communications and Security



Location: throughout the building grounds

Distress: Inadequate

Category: 4 - Capital Improvement

Priority: 4 - Response Time (4-5 yrs)

Correction: Add/Replace Video Surveillance System

Qty: 1.00

Unit of Measure: Ea.

Estimate: \$81,665.50

Assessor Name: System

Date Created: 02/12/2016

Notes: Install new video surveillance system inside the building (10) as well as the exterior of the building (6)

Priority 5 - Response Time (> 5 yrs):

System: D3030 - Cooling Generating Systems



Location: Throughout building

Distress: Inadequate

Category: 4 - Capital Improvement

Priority: 5 - Response Time (> 5 yrs)

Correction: Install chilled water system with distribution piping and pumps. (+75KSF)

Qty: 72,000.00

Unit of Measure: S.F.

Estimate: \$1,123,153.38

Assessor Name: System

Date Created: 02/02/2016

Notes: Remove the window air conditioning units and install a 200 ton air-cooled chiller with chilled water distribution piping and pumps located in a mechanical room to supply more reliable air conditioning for the building with a much longer service life.

Equipment Inventory

The following table represents the inventory details of the inventory found in the building, which fall under the following subsystems:

| Subsystem | Inventory | Qty | UoM | Location | Manufacturer | Model Number | Serial Number | Barcode | Life | Install Date | Next Renewal | Raw Cost | Inventory Cost |
|---------------------------------------|--|------|-----|-------------------------|--------------|--------------|---------------|---------|------|--------------|--------------|---------------|---------------------|
| D1010 Elevators and Lifts | Hydraulic, passenger elevator, 2500 lb, 5 floors, 100 FPM | 1.00 | Ea. | building interior | | | | | 30 | 1985 | 2047 | \$142,170.00 | \$156,387.00 |
| D3020 Heat Generating Systems | Boiler, gas/oil combination, cast iron, hot water, gross output, 3210 MBH, includes burners, controls and insulated jacket, packaged | 3.00 | Ea. | Boiler Room | HB Smith | 350A-13 | MA-96-45 | | 35 | 1996 | 2031 | \$75,956.00 | \$250,654.80 |
| D3020 Heat Generating Systems | Boiler, gas/oil combination, cast iron, hot water, gross output, 3210 MBH, includes burners, controls and insulated jacket, packaged | 3.00 | Ea. | Boiler Room | HB Smith | 350A-13 | MA-96-44 | | 35 | 1996 | 2031 | \$75,956.00 | \$250,654.80 |
| D3020 Heat Generating Systems | Boiler, gas/oil combination, cast iron, hot water, gross output, 3210 MBH, includes burners, controls and insulated jacket, packaged | 3.00 | Ea. | Boiler Room | HB Smith | 350A-13 | MA-96-43 | | 35 | 1996 | 2031 | \$75,956.00 | \$250,654.80 |
| D5010 Electrical Service/Distribution | Load interrupter switch, 2 position, 400 kVA & above w/CLF fuses, 4.8 kV, 600 amp, NEMA 1 | 1.00 | Ea. | electrical room | | | | | 30 | 1965 | 1995 | \$38,502.00 | \$42,352.20 |
| D5010 Electrical Service/Distribution | Panelboards, 1 phase 3 wire, main lugs, 120/240 V, 225 amp, 24 circuits, NQOD, incl 20 A 1 pole plug-in breakers | 4.00 | Ea. | throughout the building | | | | | 30 | 1965 | 2047 | \$2,608.20 | \$11,476.08 |
| D5010 Electrical Service/Distribution | Panelboards, 1 phase 3 wire, main lugs, 120/240 V, 225 amp, 24 circuits, NQOD, incl 20 A 1 pole plug-in breakers | 1.00 | Ea. | electrical room | | | | | 30 | 1965 | 1995 | \$2,608.20 | \$2,869.02 |
| | | | | | | | | | | | | Total: | \$965,048.70 |

Executive Summary

Building condition is evaluated based on the functional systems and elements of a building and organized according to the UNIFORMAT II Elemental Classification. The grouping of these systems and elements and applying a current replacement value to them develops a representative building cost model. Cost Models are developed for similar building types and functions. Systems and their elements are evaluated based on their current replacement values, life cycles, installation dates and next renewal dates. Systems and their elements that are within their useful lives are further evaluated to identify current deficient conditions that may have a significant impact on a system's or element's remaining service life, and to determine if they are beyond their predicted expected life. The system's or element's current replacement value is based on RS Means Commercial Cost Data.

Following are the cost model's system details for this facility. The Replacement Value is the amount needed to replace the property of the same present value. The Current Repair Amount, also known as Condition Needs, represents the budgeted contractor installed costs plus owner's soft costs for the repair, replacement or renewal for a component or system level deficiency. It excludes contributing costs for other components or systems that might also be associated with the corrective actions due to packaging the work. Facility Condition Index (FCI) FCI is an industry-standard measurement of facility condition calculated as the ratio of the costs to correct a facility's deficiencies to the facility's Current Replacement Value. It ranges from 0% (new) to 100% (very poor). Condition Index (CI) is calculated as the sum of a renewable system's Remaining Service Life (RSL) divided by the sum of a system's Replacement Value (both values exclude soft-cost to simplify calculation updates) expressed as a percentage ranging from 100% (new) to 0% (expired).

Function:

Gross Area (SF): 75,100

Year Built: 1965


Last Renovation:

Replacement Value: \$1,441,486

Repair Cost: \$217,773.29

Total FCI: 15.11 %

Total RSLI: 70.62 %



Description:

Attributes:

General Attributes:

| | | | |
|----------|---------|----------|---------|
| Bldg ID: | S456001 | Site ID: | S456001 |
|----------|---------|----------|---------|

Condition Summary

The Table below shows the CI and FCI for each major building system shown at the UNIFORMAT classification Level II. Note that Systems with lower FCIs require less investment than systems with higher FCIs.

| UNIFORMAT Classification | RSLI % | FCI % | Current Repair Cost |
|---------------------------------|----------------|----------------|---------------------|
| G20 - Site Improvements | 60.06 % | 0.00 % | \$0.00 |
| G40 - Site Electrical Utilities | 106.67 % | 66.66 % | \$217,773.29 |
| Totals: | 70.62 % | 15.11 % | \$217,773.29 |

Condition Detail

This section of the report contains results of the Facility Condition Assessment. The building is separated into system components based on UNIFORMAT II classification. The columns in the System Listing table below represent the following:

1. System Code: A code that identifies the system.
2. System Description: A brief description of a system present in the building.
3. Unit Price \$: The unit price of the system.
4. UoM: The unit of measure for of the system.
5. Qty: The quantity for the system
6. Life: anticipated service life for the system based on Building Owners and Managers Association (BOMA) recommendations.
7. Year Installed: The date of system installation.
8. Calc Next Renewal Year: The date of system expiration based on the life, NR stands for non renewable.
9. Next Renewal Year: The suggested system expiration date by the assessor based on visual inspection.
10. CI: The Condition Index of the system.
11. FCI: The Facility Condition Index of the system.
12. RSL: Remaining Service Life.
13. eCR: eCOMET Condition Rating (not used).
14. Deficiency \$: The financial investment to repair/replace system.

System Listing

The System Listing table below lists each of the systems organized by their UNIFORMAT II classification. The assessment team was tasked with recording the most recent replacement year of each system, determining the remaining service life based on the theoretical life, and evaluating the condition to confirm the forecast next replacement year. The system listing is the basis for all data contained in the Building Assessment Report.

Additionally, a condition rating (eCR) based on the following guidelines is provided as observed at the time of the assessment.

- Excellent (E) - No noticeable distress or damage. The entire system is free from observable defect.
- Very Good (VG) - Overall no serviceability reduction for the entire system. No degradation of critical components and minor distress and defect noticeable for some but not non critical components within the system.
- Good (G) - Slight or no serviceability reduction for the entire system. There may be noticeable defects for some non critical components and slight noticeable degradation of the critical components.
- Fair (F) - Overall serviceability is degraded but adequate. There may be moderate deterioration for very few of the critical components and few of the non critical components may have severe degradation.
- Marginal (MA) - Overall serviceability and reliability loss. Most if not all of the non critical components suffer from severe degradation and a few of the critical component may have severe degradation.
- Moderate (MO) - Overall a significant serviceability loss. Most if not all the components have severe degradation with the reminder of the component showing visible distress.
- Very Poor (VP) - Overall the system is barely functional. All of the components are severely degraded.
- Non-Functional (NF) - Overall the system does not function with all the components having no serviceability and suffer from severe degradation.

| System Code | System Description | Unit Price \$ | UoM | Qty | Life | Year Installed | Calc Next Renewal Year | Next Renewal Year | RSLI% | FCI% | RSL | eCR | Deficiency \$ | Replacement Value \$ |
|--------------|--------------------------------|---------------|------|--------|------|----------------|------------------------|-------------------|----------------|----------------|-----|-----|---------------------|----------------------|
| G2010 | Roadways | \$11.52 | S.F. | | 30 | | | | 0.00 % | 0.00 % | | | | \$0 |
| G2020 | Parking Lots | \$7.65 | S.F. | 19,300 | 30 | 1995 | 2025 | | 33.33 % | 0.00 % | 10 | | | \$147,645 |
| G2030 | Pedestrian Paving | \$11.52 | S.F. | 55,400 | 40 | 1995 | 2035 | | 50.00 % | 0.00 % | 20 | | | \$638,208 |
| G2040 | Site Development | \$4.36 | S.F. | 75,100 | 25 | 2013 | 2038 | | 92.00 % | 0.00 % | 23 | | | \$327,436 |
| G2050 | Landscaping & Irrigation | \$3.78 | S.F. | 400 | 15 | | | | 0.00 % | 0.00 % | | | | \$1,512 |
| G4020 | Site Lighting | \$3.58 | S.F. | 75,100 | 30 | 1965 | 1995 | 2047 | 106.67 % | 63.16 % | 32 | | \$169,818.66 | \$268,858 |
| G4030 | Site Communications & Security | \$0.77 | S.F. | 75,100 | 30 | 1965 | 1995 | 2047 | 106.67 % | 82.93 % | 32 | | \$47,954.63 | \$57,827 |
| Total | | | | | | | | | 70.62 % | 15.11 % | | | \$217,773.29 | \$1,441,486 |

System Notes

The facility description in the site executive summary contains an overview of each system. The notes listed below provide additional information on select systems found within the facility.

No data found for this asset

Renewal Schedule

eCOMET forecasts future Capital Renewal funding needed to address expiring systems based on the Next Renewal year found in the Cost Models. A 3% annual inflation factor is applied to the costs for systems expiring in future years. The table below reflects recommended Capital Renewal funding needs over the next 10 years. Note: Cells with a zero value indicate systems for which renewal is not scheduled in that year.


Inflation Rate: 3%

| System | Current Deficiencies | 2016 | 2017 | 2018 | 2019 | 2020 | 2021 | 2022 | 2023 | 2024 | 2025 | Total |
|--|----------------------|------------|------------|------------|------------|------------|------------|------------|------------|------------|------------------|------------------|
| Total: | \$217,773 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$218,265 | \$436,039 |
| G - Building Sitework | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| G20 - Site Improvements | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| G2010 - Roadways | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| G2020 - Parking Lots | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$218,265 | \$218,265 |
| G2030 - Pedestrian Paving | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| G2040 - Site Development | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| G2050 - Landscaping & Irrigation | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| G40 - Site Electrical Utilities | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| G4020 - Site Lighting | \$169,819 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$169,819 |
| G4030 - Site Communications & Security | \$47,955 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$47,955 |

** Indicates non-renewable system*

Forecasted Sustainment Requirement

The following chart shows the current building deficiencies and forecasting sustainment requirements over the next ten years.




10 Year FCI Forecast by Investment Scenario

The chart below illustrates the effect of various investment levels on the building FCI for the next 10 years. The levels of investment shown below include:

- Current FCI: a variable investment amount based on renewing expired systems to maintain the current FCI for the building
- 2% Investment: an annual investment of 2% of the replacement value of the building, escalated for inflation
- 4% Investment: an annual investment of 4% of the replacement value of the building, escalated for inflation


Facility Investment vs. FCI Forecast



| Year | Investment Amount Current FCI - 15.11% | 2% Investment | | 4% Investment | |
|---------------|---|---------------------|---------|---------------------|---------|
| | | Amount | FCI | Amount | FCI |
| 2016 | \$0 | \$29,695.00 | 13.11 % | \$59,389.00 | 11.11 % |
| 2017 | \$381,239 | \$30,585.00 | 36.04 % | \$61,171.00 | 32.04 % |
| 2018 | \$0 | \$31,503.00 | 34.04 % | \$63,006.00 | 28.04 % |
| 2019 | \$0 | \$32,448.00 | 32.04 % | \$64,896.00 | 24.04 % |
| 2020 | \$0 | \$33,422.00 | 30.04 % | \$66,843.00 | 20.04 % |
| 2021 | \$0 | \$34,424.00 | 28.04 % | \$68,848.00 | 16.04 % |
| 2022 | \$0 | \$35,457.00 | 26.04 % | \$70,914.00 | 12.04 % |
| 2023 | \$0 | \$36,521.00 | 24.04 % | \$73,041.00 | 8.04 % |
| 2024 | \$0 | \$37,616.00 | 22.04 % | \$75,232.00 | 4.04 % |
| 2025 | \$218,265 | \$38,745.00 | 31.30 % | \$77,489.00 | 11.30 % |
| Total: | \$599,504 | \$340,416.00 | | \$680,829.00 | |

Deficiency Summary by System


Current deficiencies included assemblies that have reached or exceeded their design life or components of the assemblies that are in need of repair. Assemblies that have reached their design life are identified as current deficiencies and assigned the distress 'Beyond Useful Life'. The following chart lists all current deficiencies associated with this facility.



Budget Estimate Total: \$217,773.29

Deficiency Summary by Priority

The following chart shows the total repair costs broken down by priority. Assessors assigned deficiencies within eCOMET to one of the following priority categories:



Budget Estimate Total: \$217,773.29


Deficiency By Priority Investment Table

The table below shows the current investment cost grouped by deficiency priority and building system.

| System Code | System Description | 1 - Response Time (< 2 yr) | 2 - Response Time (2-3 yrs) | 3 - Response Time (3-4 yrs) | 4 - Response Time (4-5 yrs) | 5 - Response Time (> 5 yrs) | Total |
|-------------|--------------------------------|----------------------------|-----------------------------|-----------------------------|-----------------------------|-----------------------------|--------------|
| G4020 | Site Lighting | \$0.00 | \$0.00 | \$169,818.66 | \$0.00 | \$0.00 | \$169,818.66 |
| G4030 | Site Communications & Security | \$0.00 | \$0.00 | \$0.00 | \$47,954.63 | \$0.00 | \$47,954.63 |
| | Total: | \$0.00 | \$0.00 | \$169,818.66 | \$47,954.63 | \$0.00 | \$217,773.29 |

Deficiency Summary by Category

The following chart shows the total repair costs broken down by deficiency categories. Assessors assigned deficiencies to one of the following categories:




Deficiency Details by Priority

The deficiency detail notes listed below provide additional information on identified deficiencies found within the facility.

Priority 3 - Response Time (3-4 yrs):

System: G4020 - Site Lighting



Location: grounds

Distress: Security Issue

Category: 1 - Health & Safety

Priority: 3 - Response Time (3-4 yrs)

Correction: Add Site Lighting - pole mounted - select the proper light and pole

Qty: 1.00

Unit of Measure: Ea.

Estimate: \$169,818.66

Assessor Name: Craig Anding

Date Created: 02/12/2016

Notes: Install additional pole-mounted lights for the grounds

Priority 4 - Response Time (4-5 yrs):

System: G4030 - Site Communications & Security



Location: grounds

Distress: Inadequate

Category: 4 - Capital Improvement

Priority: 4 - Response Time (4-5 yrs)

Correction: Add Site Paging System

Qty: 0.00

Unit of Measure: Ea.

Estimate: \$47,954.63

Assessor Name: Iraj Boroumand

Date Created: 02/12/2016

Notes: Install additional exterior speakers for the grounds

Equipment Inventory

The following table represents the inventory details of the inventory found in the building, which fall under the following subsystems:

No data found for this asset

Glossary

| | |
|------------|---|
| ABMA | American Boiler Manufacturers Association http://www.abma.com/ |
| ACEEE | American Council for an Energy-Efficient Economy |
| ACGIH | American Council of Governmental and Industrial Hygienists |
| AEE | Association of Energy Engineers |
| AFD | Adjustable Frequency Drive |
| AFTC | After Tax Cash Flow |
| AGA | American Gas Association |
| AHU | Air Handling Unit |
| Amp | Ampere |
| ANSI | American National Standards Institute |
| ARI | Air Conditioning and Refrigeration Institute |
| ASD | Adjustable Speed Drive |
| ASHRAE | American Society of Heating Refrigerating and Air-Conditioning Engineers Inc. |
| ASME | American Society of Mechanical Engineers |
| Assessment | Visual survey of a facility to determine its condition. It involves looking at the age of systems reviewing information from local sources and visual evidence of potential problems to assign a condition rating. It does not include destructive testing of materials or testing of systems or equipment for functionality. |
| ATS | After Tax Savings |
| AW | Annual worth |
| BACNET | Building Automation Control Network |
| BAS | Building Automation System |
| BCR | Benefit Cost Ratio |
| BEP | Business Energy Professional (AEE) |
| BF | Ballast Factor |
| BHP | Boiler Horsepower (boilers) |
| BHP | Brake Horsepower (motors) |
| BLCC | Building Life Cycle Cost analysis program (FEMP) |
| BOCA | Building Officials and Code Administrators |
| BTCF | Before Tax Cash Flow |

| | |
|-------------------------|---|
| BTS | Before Tax Savings |
| Btu | British thermal unit |
| Building Addition | An area space or component of a building added to a building after the original building's year built date. |
| CAA | Clean Air Act |
| CAAA-90 | Clean Air Act Amendments of 1990 |
| CABO | Council of American Building Officials |
| CAC | Conventional Air Conditioning |
| CADDET | Center for the Analysis and Dissemination of Demonstrated Energy Technologies |
| Calculated Next Renewal | The year a system or element would be expected to expire based solely on the date it was installed and the expected useful lifetime for that kind of system. |
| Capital Renewal | Capital renewal is condition work (excluding suitability and energy audit work) that includes the replacement of building systems or elements (as they become obsolete or beyond their useful life) not normally included in an annual operating budget. Calculated next renewal The year a system or element would be expected to expire based solely on the date it was installed and the expected useful lifetime for that kind of system. Next renewal The assessor adjusted expected useful life of a system or element based on on-site inspection. |
| CDD | Cooling Degree Days |
| CDGP | Certified Distributed Generation Professional |
| CEC | California Energy Commission |
| CEM | Certified Energy Manager |
| CEP | Certified Energy Procurement Professional |
| CFC | Chlorofluorocarbon |
| CFD | Cash Flow Diagram |
| CFL | Compact Fluorescent Light |
| CFM cfm | Cubic Feet per Minute |
| CHP | Combined Heat and Power (a.k.a. cogeneration) |
| CHW | Chilled Water |
| Condition | Condition refers to the state of physical fitness or readiness of a facility system or system element for its intended use. |
| COP | Coefficient of Performance |
| Cp | Heat Capacity of Material |
| CPUC | California Public Utility Commission |
| CRI | Color Rendering Index |
| CRT | Cathode Ray Tube VDT HMI |

Site Assessment Report - S456001;Kelley, William

| | |
|---------------------------------|---|
| CTC | Competitive Transition Charge |
| Cu | Coefficient of Utilization |
| Current Replacement Value (CRV) | CRV represents the hypothetical total cost of rebuilding or replacing an existing facility in current dollars to its optimal condition (excluding auxiliary facilities) under current codes and construction standards. |
| Cv | Value Coefficient |
| CWS | Chilled Water System |
| D d | Distance (usually feet) |
| DB | Dry Bulb |
| DCV | Demand Control Ventilation |
| DD | Degree Day |
| DDB | Double Declining Balance |
| DDC | Direct Digital Controls |
| Deferred maintenance | Deferred maintenance is condition work (excluding suitability and energy audit needs) deferred on a planned or unplanned basis to a future budget cycle or postponed until funds are available. |
| Deficiency | A deficiency is a repair item that is damaged missing inadequate or insufficient for an intended purpose. |
| Delta | Difference |
| Delta P | Pressure Difference |
| Delta T | Temperature Difference |
| DG | Distributed Generation |
| DOE | Department of Energy |
| DP | Dew Point |
| DR | Demand Response |
| DX | Direct Expansion Air Conditioner |
| EA | Energy Audit |
| EBITDA | Earnings before Interest Taxes Depreciation and Amortization |
| ECI | Energy Cost Index |
| ECM | Energy Conservation Measure |
| ECO | Energy Conservation Opportunity |
| ECPA | Energy Conservation and Production Act |
| ECR | Energy Conservation Recommendation |
| ECS | Energy Control System |

| | |
|--|--|
| EER | Energy Efficiency Ratio |
| EERE | Energy Efficiency and Renewable Energy division of US DOE |
| EIA | Energy Information Agency |
| EIS | Energy Information System |
| EMCS | Energy Management Computer System |
| EMO | Energy Management Opportunity |
| EMP | Energy Management Project |
| EMR | Energy Management Recommendation |
| EMS | Energy Management System |
| Energy Utilization Index (EUI) | EUI is the measure of total energy consumed in the cooling or heating of a building in a period expressed as British thermal unit (BTU) per (cooled or heated) gross square foot. |
| EO | Executive Order |
| EPA | Environmental Protection Agency |
| EPACT | Energy Policy Act of 1992 |
| EPCA | Energy Production and Conservation Act of 1975 |
| EPRI | Electric Power Research Institute |
| EREN | Efficiency and Renewable Energy (Division of USDOE) |
| ERV | Energy Recovery Ventilator |
| ESCO | Energy Service Company |
| ESPC | Energy Savings Performance Contract |
| EUI | Energy Use Index |
| EWG | Exempt Wholesale Generators |
| Extended Facility Condition Index (EFCI) | EFCI is calculated as the condition needs for the current year plus facility system renewal needs going out to a set time in the future divided by Current Replacement Value. |
| f | Frequency |
| F | Fahrenheit |
| Facility | A facility refers to site(s) building(s) or building addition(s) or combinations thereof that provide a particular service. |
| Facility Condition Assessment (FCA) | FCA is a process for evaluating the condition of buildings and facilities for programming and budgetary purposes through an on site inspection and evaluation process. |
| Facility Condition Index (FCI) | FCI is an industry-standard measurement of a facility's condition that is the ratio of the cost to correct a facility's deficiencies to the Current Replacement Value of the facilities. The higher the FCI the poorer the condition of a facility. After an FCI is established for all buildings within a portfolio a building's condition can be ranked relative to other buildings. The FCI may also represent the condition of a portfolio based on the cumulative FCIs of the portfolio's facilities. |

Site Assessment Report - S456001;Kelley, William

| | |
|-------------------------|---|
| FC | Footcandle |
| FCA | Fuel Cost Adjustment |
| FEMIA | Federal Energy Management Improvement Act of 1988 |
| FEMP | Federal Energy Management Program |
| FERC | Federal Energy Regulatory Commission |
| FESR | Fuel Energy Savings Ratio |
| FLA | Full Load Amps |
| FLF | Facility Load Factor (usually monthly) |
| FLRPM | Full Load Revolutions per Minute |
| FMS | Facility Management System |
| FPM fpm | Feet per Minute (velocity) |
| FSEC | Florida Solar Energy Center |
| Ft | Foot |
| GPM gpm | Gallons per Minute |
| GRI | Gas Research Institute |
| Gross Square Feet (GSF) | The size of the enclosed floor space of a building in square feet measured to the outside face of the enclosing wall. |
| GUI | Graphical User Interface |
| H h | Enthalpy Btu/lb |
| HCFC | Hydrochlorofluorocarbons |
| HDD | Heating Degree days |
| HFC | Hydrofluorocarbons |
| HHV | Higher Heating Value |
| HID | High Intensity Discharge (lamp) |
| HMI | Human Machine Interface |
| HMMI | Human Man Machine Interface |
| HO | High Output (lamp) |
| HP Hp hp | Horsepower |
| HPS | High Pressure Sodium (lamp) |
| HR | Humidity Ratio |
| Hr hr | Hour |

| | |
|--------------|--|
| HRU | Heat Recovery Unit |
| HVAC | Heating Ventilation and Air-Conditioning |
| Hz | Hertz |
| I | Intensity (lumen output of lamp) |
| I i | Interest rate or Discount rate |
| IAQ | Indoor Air Quality |
| ICA | International Cogeneration Alliance |
| ICBO | International Conference of Buildings Officials |
| ICC | International Code Council |
| ICP | Institutional Conservation Program |
| IECC | International Energy Conservation Code |
| IEEE | Institute of Electrical and Electronic Engineers |
| IESNA | Illuminating Engineering Society of North America |
| Install year | The year a building or system was built or the most recent major renovation date (where a minimum of 70 of the system's Current Replacement Value (CRV) was replaced). |
| IRP | Integrated Resource Planning |
| IRR | Internal Rate of Return |
| ISO | Independent System Operator |
| ITA | Independent Tariff Administrator |
| k | Kilo multiple of thousands in SI system |
| K | Kelvins (color temperature of lamp) |
| K k | Thermal Conductivity of Material |
| KVA | Kilovolt Ampere |
| KVAR | Kilovolt Ampere Reactive |
| kW | kiloWatt |
| kWh | kiloWatt hour |
| L | Length (usually feet) |
| LCC | Life Cycle Costing |
| LDC | Local Distribution Company |
| LEED | Leadership in Energy and Environmental Design |
| LEED EB | LEED for Existing Buildings |

Site Assessment Report - S456001;Kelley, William

| | |
|--------------|--|
| LEED NC | LEED for new construction |
| LF | Load Factor |
| LHV | Lower Heating Value |
| Life cycle | The period of time that a building or site system or element can be expected to adequately serve its intended function. |
| LPS | Low Pressure Sodium (lamp) |
| Lu | Lumen Output of a Lamp or Fixture |
| M | Mega multiple of millions in SI system |
| M&V | Measurement and Verification |
| MACRS | Modified Accelerated Cost Recovery System |
| MARR | Minimum Attractive Rate of Return |
| Mbtu | Thousand Btu |
| MCF | Thousand Cubic Feet (usually of gas) |
| MEC | Model Energy Code |
| Mm | Multiple of Thousands in I/P System |
| MMBtu | Million Btu |
| MMCS | Maintenance Management Computer System |
| MMI | Man Machine Interface |
| MMS | Maintenance Management System |
| MSE 2000 | Management System for Energy 2000 (ANSI Georgia Tech Univ) |
| MW | MegaWatt |
| MWH MWh | MegaWatt hour |
| NAAQS | National Ambient Air Quality Standards |
| NAESCO | National Association of Energy Service Companies |
| NAIMA | North American Insulation Manufacturers Association |
| NEA | National Energy Act of 1978 |
| NECPA | National Energy Conservation Policy Act |
| NEMA | National Electrical Manufacturer's Association |
| NERC | North American Electric Reliability Council |
| Next Renewal | The Next Renewal date is an override of the 'Calculated Next Renewal' date and is based upon the assessor's visual inspection. |

Site Assessment Report - S456001;Kelley, William

| | |
|-----------|---|
| NFPA | National Fire Protection Association |
| NGPA | National Gas Policy Act of 1978 |
| NLRPM | No Load Revolutions per Minute (speed) |
| Nn | Equipment or Project lifetime in economic analysis |
| NOPR | Notice of Proposed Rule Making from FERC |
| NOx | Nitrogen Oxide Compounds |
| NPV | Net present value in economic analysis |
| NREL | National Renewable Energy Laboratory |
| NUG | Non-Utility Generator |
| O&M | Operation and Maintenance |
| OA | Outside Air |
| ODP | Ozone Depletion Potential |
| OPAC | Off-Peak Air Conditioning |
| P | Present value in economic analysis |
| PBR | Performance Based Rates |
| PEA | Preliminary Energy Audit |
| PF | Power Factor |
| PID | Proportional plus integral plus derivative (control system) |
| PM | Portfolio Manager in Energy Star rating system |
| PM | Preventive Maintenance |
| PoolCo | Power Pool Company or Organization |
| POU | Point of Use |
| PQ | Power Quality |
| PSC | Public Service Commission |
| PSIA psia | Pounds per square inch absolute (pressure) |
| PSIG psig | Pounds per square inch gauge (pressure) |
| PUC | Public Utility Commission |
| PUHCA | Public Utilities Holding Company Act of 1935 |
| PURPA | Public Utilities Regulatory Policies of 1978 |
| PV | Photovoltaic system |

| | |
|-------------------------------------|---|
| PV | Present Value |
| PW | Present Worth |
| PX | Power Exchange |
| q | Rate of heat flow in Btu per hour |
| Q | Heat load due to conduction using degree days |
| QF | Qualifying Facility |
| R | Electrical resistance |
| R | Thermal Resistance |
| RC | Remote controller |
| RCR | Room Cavity Ratio |
| RCRA | Resource Conservation and Recovery Act |
| Remaining Service Life (RSL) | RSL is the number of years service remaining for a system or equipment item. It is automatically calculated based on the difference between the current year and the 'Calculated Next Renewal' date or the 'Next Renewal' date whichever one is the later date. |
| Remaining Service Life Index (RSLI) | RSLI is defined as a percentage ratio of the remaining service life of a system. It usually ranges from 0 to 100 |
| REMR | Repair Evaluation Maintenance Rehabilitation (REMR) is a scale used to objectively rank systems based on their condition |
| Renewal Schedule | A timeline that provides the items that need repair the year in which the repair is needed and the estimated price of the renewal. |
| RH | Relative Humidity |
| RLA | Running Load Amps |
| RMS | Root Mean Square |
| RO | Reverse Osmosis |
| ROI | Return on Investment |
| RPM | Revolutions Per Minute |
| RTG | Regional Transmission Group |
| RTO | Regional Transmission Organization |
| RTP | Real Time Pricing |
| SBCCI | Southern Building Code Congress International |
| SC | Scheduling Coordinator |
| SC | Shading Coefficient |
| SCADA | Supervisory Control and Data Acquisition Systems |

Site Assessment Report - S456001;Kelley, William

| | |
|--------------|--|
| SEER | Seasonal Energy Efficiency Ratio |
| SHR | Sensible Heat Ratio |
| Site | The grounds and utilities roadways landscaping fencing and other typical land improvements needed to support the facility. |
| Soft Cost | An expense item that is not considered direct construction cost. Soft cost includes architectural engineering financing legal fees and other pre-and-post construction expenses. |
| SOx | Sulfur Oxide Compounds |
| SP | Static Pressure |
| SP SPB | Simple Payback |
| SPP | Simple Payback Period |
| SPP | Small Power Producers |
| STR | Stack Temperature Rise |
| SV | Specific Volume |
| System | System refers to building and related site work elements as described by ASTM Unifomat II Classification for Building Elements (E1557-97) a format for classifying major facility elements common to most buildings. Elements usually perform a given function regardless of the design specification construction method or materials used. See also Unifomat II. |
| T | Temperature |
| T | Tubular (lamps) |
| TAA | Technical Assistance Audit |
| TCP/IP | Transmission Control Protocol/Internet Protocol |
| TES | Thermal Energy Storage |
| THD | Total Harmonic Distortion |
| TOD | Time of Day |
| TOU | Time of Use |
| TQM | Total Quality Management |
| TransCo | Transmission Company |
| U | Thermal Conductance |
| UDC | Utility Distribution Company |
| UL | Underwriters Laboratories |
| UNIFORMAT II | The ASTM UNIFORMAT II Classification for Building Elements (E1557-97) a format for classifying major facility components common to most buildings. |
| USGBC | US Green Building Council |
| v | Specific Volume |

Site Assessment Report - S456001;Kelley, William

| | |
|------------|---|
| V | Volts Voltage |
| V | Volume |
| VAV | Variable Air Volume |
| VDT | Video Display Terminal |
| VFD | Variable Frequency Drive |
| VHO | Very High Output |
| VSD | Variable Speed Drive |
| W | Watts |
| W | Width |
| WB | Wet bulb |
| WH Wh | Watt Hours |
| Year built | The year that a building or addition was originally built based on substantial completion or occupancy. |
| Z | Electrical Impedance |