

Facility Condition Assessment Summary Report

This report provides a summary of the Facility Condition Index (FCI) value of a school facility and select major building systems. The FCI calculation represents the cost of needed repairs divided by the replacement value. The FCI is a numerical value of condition and helps to identify the need for renewal or replacement of specific parts of the facility. The FCI is particularly useful when comparing similar facilities within the same portfolio.

McCall School

Governance	DISTRICT	Report Type	Elementarymiddle
Address	325 S. 7Th St. Philadelphia, Pa 19106	Enrollment	716
Phone/Fax	215-351-7350 / 215-351-7349	Grade Range	'00-08'
Website	Www.Philasd.Org/Schools/Mccall	Admissions Category	Neighborhood
		Turnaround Model	N/A

Building/System FCI Tiers

Facility Condition Index (FCI) = $\frac{\text{Cost of Assessed Deficiencies}}{\text{Replacement Value}}$				
< 15%	15 to 25%	25 to 45%	45 to 60%	> 60%
Buildings				
Minimal Current Capital Funding Required	Refurbish Systems in building	Replace Systems in building.	Building should be considered for major renovation.	Building should be considered for closing/replacement.
Systems				
Perform routine maintenance on system	System requires minor repairs	System should be studied to determine repair vs. replacement.	System is nearing end of its life expectancy and should be considered for replacement	System should be replaced as part of the Capital Program

Building and Grounds

	FCI	Repair Costs	Replacement Cost
Overall	56.37%	\$20,000,724	\$35,482,836
Building	56.03 %	\$19,273,275	\$34,396,556
Grounds	66.97 %	\$727,449	\$1,086,280

Major Building Systems

Building System	System FCI	Repair Costs	Replacement Cost
Roof (Shows physical condition of roof)	89.19 %	\$609,876	\$683,765
Exterior Walls (Shows condition of the structural condition of the exterior facade)	42.04 %	\$1,056,310	\$2,512,685
Windows (Shows functionality of exterior windows)	133.99 %	\$1,642,735	\$1,226,049
Exterior Doors (Shows condition of exterior doors)	00.00 %	\$0	\$98,710
Interior Doors (Classroom doors)	18.63 %	\$44,526	\$238,947
Interior Walls (Paint and Finishes)	44.92 %	\$514,025	\$1,144,358
Plumbing Fixtures	21.16 %	\$194,718	\$920,388
Boilers	00.00 %	\$0	\$1,270,979
Chillers/Cooling Towers	58.94 %	\$982,294	\$1,666,500
Radiators/Unit Ventilators/HVAC	118.22 %	\$3,459,752	\$2,926,587
Heating/Cooling Controls	158.90 %	\$1,460,373	\$919,026
Electrical Service and Distribution	189.78 %	\$1,253,170	\$660,337
Lighting	54.78 %	\$1,293,179	\$2,360,876
Communications and Security (Cameras, Pa System and Fire Alarm)	52.94 %	\$468,125	\$884,307

Please note that some FCIs may be over 100% because there are times when replacing a building system requires that other building systems be upgraded to complete the installation. A FCI of 0.0% represents that there are no current deficiencies with the associated system.

School District of Philadelphia

S234001;McCall

Final

Site Assessment Report

January 31, 2017



Table of Contents

Site Executive Summary	4
Site Condition Summary	11
<u>B234001:McCall</u>	13
Executive Summary	13
Condition Summary	14
Condition Detail	15
System Listing	16
System Notes	18
Renewal Schedule	19
Forecasted Sustainment Requirement	22
Condition Index Forecast by Investment Scenario	23
Deficiency Summary By System	24
Deficiency Summary By Priority	25
Deficiency By Priority Investment	26
Deficiency Summary By Category	27
Deficiency Details By Priority	28
Equipment Inventory Detail	48
<u>G234001:Grounds</u>	49
Executive Summary	49
Condition Summary	50
Condition Detail	51
System Listing	52
System Notes	53
Renewal Schedule	54
Forecasted Sustainment Requirement	55
Condition Index Forecast by Investment Scenario	56
Deficiency Summary By System	57
Deficiency Summary By Priority	58
Deficiency By Priority Investment	59

Site Assessment Report

Deficiency Summary By Category	60
Deficiency Details By Priority	61
Equipment Inventory Detail	64
Glossary	65

Site Executive Summary

The organization of this report, as displayed in the Table of Contents, follows the structure of the associated eCOMET database. The overall node for each school campus begins with the letter "S", which indicates the "Site" label. Each Site is comprised of separate "Building" and "Grounds" nodes; their asset names begin with the letters "B" and "G" respectively. Information rolls up to the Site node from the Building and Grounds nodes. This Site report combines facility information with subsections for the Buildings And Grounds nodes.

The basis for the evaluation of condition is the functional systems and elements of a building and grounds organized according to the UNIFORMAT II Elemental Classification. The grouping of these systems and elements and applying a current replacement value to them develops a representative building cost model. Cost Models are typically developed for similar building types and functions. Evaluation of systems and their elements takes into account their current replacement values, life cycles, installation dates and next renewal dates. Systems and their elements that are within their useful lives are further evaluated to identify current deficient conditions that may have a significant impact on a system's or element's remaining service life, and to determine if they are beyond their predicted expected life. The system's or element's current replacement value is based on RS Means Commercial Cost Data.

Following are the cost model's system details for this facility. The Replacement Value is the amount needed to replace the property of the same present value. The Current Repair Amount, also known as Condition Needs, represents the budgeted contractor installed costs plus owner's soft costs for the repair, replacement or renewal for a component or system level deficiency. It excludes contributing costs for other components or systems that might also be associated with the corrective actions due to packaging the work. Facility Condition Index (FCI) is an industry-standard measurement calculated as the ratio of the repair costs to correct a facility's deficiencies to the facility's Current Replacement Value. Condition Index (CI) for a system is calculated as the sum of the deficiencies divided by the sum of a system's Replacement Value (both values include soft-cost) expressed as a percentage ranging from 0% 100%.

Gross Area (SF):	68,076
Year Built:	1909
Last Renovation:	2010
Replacement Value:	\$35,482,836
Repair Cost:	\$20,000,723.75
Total FCI:	56.37 %
Total RSLI:	96.90 %



Description:

Facility assessment, July 2015

School District of Philadelphia

McCall Elementary School

325 S 7th Street

Philadelphia, PA 19106

68,076 SF / 596 Students / LN 03

The McCall Elementary School building is located at 325 S 7th Street in Philadelphia, PA. The 3 story, 68,076 square foot building was originally constructed in 1909. Approximately in 1965 a 1 story addition was constructed in North East corner of the site containing auditorium, gymnasium and support spaces. The original building has a basement partially above ground and a penthouse on the roof. In 2010 the boiler room was renovated including replacement of most of the mechanical equipment.

Site Assessment Report - S234001;McCall

Mr. Derek Parker, Facility Area Coordinator provided input to the Parsons assessment team on current problems and planned renovation projects. Mr. Chris Ragni, Building Engineer, accompanied us on our tour of the school and provided us with detailed information on the building systems and recent maintenance history.

STRUCTURAL/ EXTERIOR CLOSURE:

The building typically rests on concrete foundations and bearing walls that are not showing signs of settlement. Foundation walls do not show signs of deterioration with the exception of small cracks in electrical rooms in South West corner of the basement. The basement slab does not show signs of heaving or cracking. No signs of water penetration through walls have been observed or reported, however, some mildew was observed in basement electrical rooms.

The main structure consists typically of load bearing masonry walls, beams and concrete, ribbed slabs in the original building. Long roof spans in the Auditorium and Gymnasium are supported with steel truss joists resting on masonry bearing walls. Above ground floor slabs are generally in good condition, however, the masonry bearing wall on the North side and North West corner of the original building is cracked along the lintel level of the basement windows. The North West corner, previously stabilized with steel rods and anchor plates, shows masonry cracks and face brick buckling up to the third floor level. It is strongly recommended that a structural analysis is conducted to determine the exact cause of overstress cracking and develop remedial action.

The load bearing masonry structure of the fire escape located in the middle of the South wall is unusable due to severe structural deterioration of walls and stair structure. It has been condemned by the City of Philadelphia in 2006.

The building envelope is typically face brick masonry with decorative stone water table and window sills. In general, masonry is in fair condition with deteriorated and missing mortar from joints (approximately 30%).

The original windows were replaced in 1980's with extruded aluminum double hung windows, single acrylic glazed. Basement windows are fitted with security screens attached to adjacent masonry. All windows and screens are generally in poor condition and beyond their useful life.

Exterior doors and frames are typically hollow metal in fair to good condition.

Roofing is typically built-up. All roofing and flashing is typically in poor condition with deterioration of the built-up system including water ponding and soft spots; several leaks have been reported.

INTERIORS:

Partition wall types include plastered ceramic hollow blocks and painted CMU. Partitions between some classrooms are original, movable partitions in poor condition and inoperable. The interior wall finishes are generally painted plaster or drywall. Corridors in basement are typically painted brick with glazed brick wainscot. Generally, paint is in fair condition with some deterioration in stairways and toilets. Most ceilings are 2x4 suspended acoustical panels and exposed, painted. The suspension system and tile are old and approaching the end of their useful life. Auditorium and Gym has suspended acoustical baffles in good condition. Paint on exposed ceilings is deteriorated. Flooring in classrooms, gym and auditorium is generally hardwood; and patterned concrete in most corridors and toilets. Some toilet walls and floors are finished with ceramic tile. Most flooring is original and in poor condition, often uneven creating possible tripping hazard; cove base is typically in fair condition. Some areas in basement have VCT tile, generally in fair condition. However, tiles in Auditorium and Gymnasium are VAT tiles (containing asbestos), in poor condition. Some tiles are missing creating a possibility of ACM exposure.

Interior doors are generally solid core wood, some glazed in original wood frames installed in late 1990's. Door finishes are typically in good condition. Most doors are fitted with door knobs and are not ADA compliant. The doors leading to exit stairways are hollow metal doors and frames in good condition.

Fittings include original chalk boards, generally in poor condition; toilet accessories in fair condition; toilet partitions, generally in fair condition; handrails and ornamental metals, generally in good condition. Interior identifying signage is typically directly painted on wall or door surfaces generally in fair condition. Some doors have no signage.

Stair construction is generally concrete with cast iron non-slip treads in good condition.

Institutional and Commercial equipment includes: stage equipment, generally in poor condition; A/V equipment in fair condition; gym equipment – basketball backstops, scoreboards, etc.; generally in poor condition. Other equipment includes kitchen equipment, generally in good condition.

Site Assessment Report - S234001;McCall

Furnishings include fixed casework in classrooms, corridors and library, generally in fair to poor condition; window shades/blinds, generally in poor condition; fixed auditorium seating is original, generally in fair condition with some damaged seats.

CONVEYING SYSTEMS:

The building has no original elevators.

PLUMBING:

Plumbing Fixtures - Many of the original plumbing fixtures remain in service. Fixtures in the restrooms on each floor consist of floor and wall mounted flush valve water closets, wall hung urinals, and lavatories with wheel handle faucets. With proper maintenance these fixtures should provide reliable service for the next 5-10 years. However, the older units should be replaced as part of any renovation of the spaces.

Drinking fountains in the corridors and at the restrooms are a mixture of wall hung with integral refrigerated coolers and wall hung porcelain fountains. The porcelain fountains are well beyond their service life and should be replaced; most are NOT accessible type.

A service sink is available in a janitor closet in the corridor on each floor for use by the janitorial staff.

The Gymnasium/Cafeteria has no sink, only premade meals are served.

Domestic Water Distribution - A 4" city water service enters the building from Panama Street. The 4" meter and valves are located in the basement mechanical room on the west side of the building. Two Armstrong domestic water booster pumps, installed in 2001, ensure adequate water pressure for the building. The original domestic hot and cold water distribution piping was replaced with copper piping and sweat fittings. The maintenance staff reports no significant problems with scale build up in the domestic piping and the supply is adequate to the fixtures.

Two Bradford White gas fired vertical hot water heaters, installed in approximately 2010, supply hot water for domestic use. Both units have an 80 gallon capacity and are located in the boiler room on the basement level. The hot water heaters are equipped with a T&P relief valve, and one expansion tank. The domestic hot water heater is within its service life and should provide reliable service for the next 5-7 years. No water softener was seen in the boiler room.

Sanitary Waste - The original storm and sanitary sewer piping is heavy weight cast iron with hub and spigot fittings. Downspouts from the roof run down the interior of the building and connect to the storm sewer system in the basement.

There is no sewage ejector or sump pump in the building.

The maintenance staff reported mostly minor problems with the sanitary waste piping systems. However, the sewer piping has been in service for over 50 years and will require more frequent attention from the maintenance staff as time passes. The District should hire a qualified contractor to examine the sanitary waste piping using video cameras to locate and replace any damaged piping and to further quantify the extent of potential failures.

MECHANICAL:

Energy Supply - A 4" city gas service enters the building from Panama Street. The meter is 4" and located in the in the basement mechanical room. The gas main has a booster pump connected in the mechanical room.

The oil supply is stored in a 12,000 gallon underground storage tank (UST) located in the parking lot adjacent to Panama Street. Duplex pumps located in the basement boiler room circulate oil through the system. Oil is used as the primary fuel for the boilers. It is estimated that the storage tank is beyond its useful life and should be inspected on a regular basis.

Heat Generating Systems - Building heating hot water is generated by two Buderus Logano GE615 boilers with, net IBR rating of 3,463 MBH and installed in approximately 2010. One boiler can handle the load in normal winter weather conditions; two units are required to bring the building up to temperature on very cold days. Each boiler is equipped with a Webster burner designed to operate on natural gas or fuel oil. Burner oil pumps are loose and not driven by the fan motor. The gas train serving the boilers does have code required venting of the regulators and dual solenoid valves with venting of the chamber between. Combustion air makeup is supplied by louvers equipped with motorized dampers. No major issues with the boilers were reported by the Building Engineer. Cast iron sectional boilers have an anticipated service life of 35 years or more; these units have been in service

Site Assessment Report - S234001;McCall

approximately 5 years. The boilers appear to have been maintained well. The District should provide reliable service for the next 25 to 30 years.

The heating hot water system is equipped with two base mounted, end suction 10HP Taco hot water circulating pumps with suction diffusers in the boiler room. An expansion tank and air separator are located in the boiler room. The hot water piping is covered with insulation and appears to be in good condition.

Distribution Systems - Unit ventilators provide heating for the majority of classrooms, offices, and indirectly to the hallways. The unit ventilators are original to the building and well beyond their service life. Outdoor air for the building is provided by wall openings in the unit ventilators, which may not be sufficient to meet current codes for outdoor air ventilation. The existing unit ventilators should be removed and new units installed with hot and chilled water coils and integral heat exchangers to introduce sufficient outdoor air to the building.

The school has mechanical ventilation in each classroom via unit ventilators, roof mounted exhaust fans serving the bathrooms, and air handling units serving the Auditorium and Gymnasium/Cafeteria. For the Gymnasium/Cafeteria a house fan and heating coil from 1969 provides heating and ventilation only. This air handling unit is beyond its service life and should be replaced with a fan coil (heating and cooling) air handling unit with outdoor air ventilation. Currently the Auditorium is provided heating and ventilation only by a house fan and heating coil from 1969. This air handling unit is beyond its service life and should be replaced with a constant volume air handling unit with distribution ductwork and registers. Both AHUs serving the Gymnasium/Cafeteria and Auditorium are located in a mechanical room behind the Auditorium stage. These units would be equipped with hot water heating coils and chilled water cooling coils.

Exhaust for the restrooms is provided by two roof mounted exhaust fans. One exhaust fan serves the girls restrooms, the other serves the boys. An exhaust fan mounted on the roof of the boiler room serves the boiler room. The existing roof mounted exhaust fans serving the restrooms are beyond their service life and should be replaced.

A hot water make up air unit in the basement provides ventilation air for the classrooms on that level, which do not have ventilation air provided by the unit ventilators.

Terminal & Package Units - Several of the classrooms in the school building have window air conditioning units that have an anticipated service life of only 10 years. Installing a 170 ton air-cooled chiller on the roof, with pumps located in the mechanical room, and chilled water distribution piping would supply more reliable air conditioning for the building with a much longer service life.

A Mitsubishi split system air conditioning system provides cooling to the LAN room located on the first floor off of the Main Office. The installation date of this unit is unknown; the anticipated service life of a split system air conditioner is 15 years. The district should budget to replace this unit within the next 7-10 years.

The IMC is served by its own air conditioning system which consists of an indoor unit and remote condensing unit located on the roof above the boiler room. A thermostat in the IMC controls the temperature of the room. The installation date and manufacturer of the unit was not available.

A Modine unit heater provides heating to the boiler room.

Controls & Instrumentation - The original pneumatic systems still provide basic control functions. Pneumatic room thermostats are intended to control the steam radiator control valves. In reality the radiator control valves are wide open and heating control is achieved via the boilers. Pneumatic control air is supplied from a duplex Quincy compressor and air drying system located in the boiler room. The original control valves and pneumatic actuators are beyond their service life and should be rebuilt or replaced. These controls should be converted to DDC.

A new building automation system (BAS) with modern DDC modules and communications network should be installed to serve the HVAC systems in this building to improve reliability and energy efficiency. An interface should be provided with the preferred system in use throughout the District.

Sprinklers - The school building is NOT covered by an automatic sprinkler system. Installing a sprinkler system with quick response type heads should reduce insurance costs by providing protection for the property investment. A fire pump may be required depending on the available city water pressure.

ELECTRICAL:

Site Assessment Report - S234001;McCall

Electrical Service- The electrical service is fed from an underground distribution system along S Seventh St. The service enters the building underground to a 500 kVA, 2400V:208/120V substation. The substation is equipped with a 600A load interrupter switch. After the medium voltage transformer, the substation contains a 208/120V 1600A distribution section. The substation is original to the building, and was manufactured by Westinghouse. The substation is not adequately sized for a building air conditioning system and elevator.

Distribution System and Raceway System- The main distribution panel is rated 1600A, and is attached to the end of the substation. Electrical panels located on each floor are fed from this main distribution panel, and provides power to the receptacles and lighting on each floor.

Receptacles- Classrooms are typically supplied with 2 to 4 duplex receptacles. Two additional receptacle should be added to each wall in these classrooms.

Lighting- Most of the building is outfitted with fluorescent fixtures with T-12 lamps, The auditorium and lobby area contain incandescent par type lamps. The gymnasium has 15 mercury vapor lamps. Classroom are comprised of 1X4 - 2 lamp pendant fixtures. Classroom lighting is typically controlled by inboard/outboard switching. Corridors are illuminated by 1X4-2 lamp pendant mounted fixtures in the older portion of the school, and 2X4 - 4 lamp lay in grid type fixtures in the new section. The administrative areas use 2X4 - 4 lamp lay in grid type fixtures with T8 lamps. Lighting levels in the classroom areas were found to be in the 15-20 fc range which is below the recommended 50 fc. The gym lighting level was found acceptable at 50 fc. Media center and administrative area lighting levels were found to be in the 50 fc range with 4 lamp 2X4 T8 fixtures. Corridor lighting was found to range from 5 to 15 fc. It is recommended to upgrade the remaining lighting throughout the facility.

Fire Alarm System – The school has an older 120V fire alarm system that has pull stations at exits and audible bell arms in the corridors only. A newer Silent Knight system by Honeywell was installed in 2010 for the installation of duct smoke detectors in the heating system.

Telephone/LAN – The present telephone/LAN system is adequate.

Public Address/Intercom/Paging – An independent and separate PA system does not exist. School uses the telephone system for public announcement. Two way communication is not available through the public announcement system. Communication back to the office is through a wall mounted phone located in each classroom. This system is adequate and in working condition. Classrooms and corridors contain ceiling mounted speakers where a drop ceiling exists, and wall mounted speakers otherwise.

Clock and Program System – The present bell system is adequate. There is no clock system for classrooms.

Television System – The facility is equipped with TV coax system, however there presently are no televisions in the classrooms.

Security System – There facility is equipped with door contacts on exterior doors. There are also motion sensors in the first floor corridors.

Emergency Power System – The facility does not have an emergency standby generator.

Emergency Lighting System / Exit Lighting- The emergency lighting is provided by battery packs located in the corridors. Most of these battery packs were in inoperable condition. The exit lighting is are incandescent and are in poor condition.

Lightning Protection System- A lightning protection system is installed on the chimney and is in adequate condition.

Site Lighting - Site lighting is provided by building mounted flood lights installed around the entire perimeter of the school. The site lighting provides an adequate amount of lighting.

Video Surveillance – There is an exterior camera mounted on the northwest corner of the original building to cover the paved play area, and a camera on the south wall to cover that side of the building. There are no cameras along the east side to cover the main entrance or courtyard. There are interior cameras installed in the stairwells.

Site Paging – There are exterior speakers located in the paved play area for site paging. There are no speakers for front entrance and courtyard.

GROUNDS (SITE):

Site Assessment Report - S234001;McCall

There is a parking lot at the North West corner of the site. It is partially fenced with 14 spaces inside and 19 spaces outside, directly accessible from Cypress St. The pavement is in good condition; however, the aisle striping is faded and missing in 80% of area.

Playground pavement adjacent to the building is in poor condition, paving is cracked and uneven. Playground equipment is in good condition, however, resilient rubber tile surrounding it is in poor condition.

Perimeter picket fence separating the playground from the street and parking is generally in good condition; however, a picket fence separating school grounds from the Panama St. is original and in poor condition.

The landscaping is limited to South East corner of the site and is generally well maintained in good condition.

ACCESSIBILITY:

Generally, the building has an accessible route per ADA requirements to the Gym and Auditorium (1965 addition); the original building is not accessible due to level separation between addition and the original building and lack of elevator to basement, second and the third floors. Toilets are not equipped with accessible fixtures, and accessories, such as grab bars, and accessible partitions. Most of the doors in the building have ADA required door handles.

Parking does not have defined accessible stalls and signage.

RECOMMENDATIONS:

- Repair and stabilize cracked exterior bearing walls
- Rebuild fire exit tower
- Install new stairs in fire exit tower
- Conduct mildew remediation in basement
- Install all new roofing system including insulation; tear-down existing roofing; install flashing, counter flashing and reglets
- Replace all windows
- Replace inoperable movable partitions
- Replace all suspended acoustical ceilings
- Repair and repaint exposed ceilings
- Repair and repaint interior walls (40% area)
- Repair & refinish hardwood flooring
- Replace all VAT floor tiles
- Replace carpet in library
- Install new signage throughout the building
- Provide ADA compliant elevator serving basement and all floors (exterior)
- Provide ADA compliant ramp at main entrance
- Provide ADA compliant hardware on interior doors
- Replace original chalk boards
- Reconfigure toilets on each floor for accessibility, provide new toilet partitions
- Provide new toilet accessories including grab bars
- Provide parking striping with (2) accessible spaces and aisles
- Repave playground area. Replace resilient rubber tiles around playground equipment
- Replace picket fence
- Replace the lavatories in the restrooms with new code compliant fixtures.
- Replace the wall hung drinking fountains and integral refrigerated coolers in the corridors and at the restrooms. These units are well beyond their service life.
- Hire a qualified contractor to perform a detailed examination of the sanitary waste piping using visual inspection and video cameras to locate and replace any damaged piping and to further quantify the extent of potential failures.
- Hire a qualified contractor to perform a detailed examination of the rain water drainage piping using visual inspection and video cameras to locate and replace any damaged piping and to further quantify the extent of potential failures.
- Remove the existing unit ventilators and install units with hot and chilled water coils and integral heat exchangers to introduce outdoor air to the building.
- Remove the window air conditioning units and install a 170 ton air-cooled chiller on the roof with chilled water distribution piping and pumps located in the mechanical room to supply more reliable air conditioning for the building with a much longer service life.
- Replace existing exhaust fans on the roof serving the bathrooms and utilize the existing ductwork.
- Provide ventilation for the Gymnasium/Cafeteria by installing a fan coil air handling unit installed in the mechanical room behind the Auditorium stage and utilize the existing outdoor air intake.

Site Assessment Report - S234001;McCall

- Provide ventilation for the Auditorium by installing a fan coil air handling unit in the mechanical room behind the Auditorium stage and utilize the existing outdoor air intake.
- Replace the pneumatic controls for the HVAC systems with modern DDC modules, valves and actuators to improve reliability and energy efficiency. Provide a new building automation system (BAS) with communication interface to the preferred system in use throughout the District.
- Install a fire protection sprinkler system with quick response type heads to reduce insurance costs by providing protection for the property. A fire pump may be required depending on the available city water pressure.
- Install minimum 2 receptacles on each wall of classrooms and other purpose rooms.
- Replace existing T12 fixtures with T8 fixtures and incandescent fixtures with compact fluorescent.
- Install a new addressable fire alarm system and provide audible and/or visual devices in all areas.
- Install a generator sized to operate the elevator and emergency lighting.
- Replace existing substation with new 480/277V sized to provide power for an elevator and air conditioning equipment.
- Replace existing EXIT fixtures with new LED type.
- Provide new emergency lighting throughout the building.
- Add video surveillance to main entrance/courtyard.
- Add site paging to main entrance/courtyard.

Attributes:

General Attributes:

Active:	Open	Bldg Lot Tm:	Lot 1 / Tm 4
Status:	Accepted by SDP	Team:	Tm 4
Site ID:	S234001		

Site Condition Summary

The Table below shows the CI and FCI for each major system shown at the UNIFORMAT classification Level II. Note that Systems with lower FCIs require less investment than systems with higher FCIs.


Current Investment Requirement and Condition by Uniformat Classification

UNIFORMAT Classification	RSLI%	FCI %	Current Repair
A10 - Foundations	95.00 %	0.00 %	\$0.00
A20 - Basement Construction	95.00 %	3.17 %	\$41,509.25
B10 - Superstructure	95.00 %	0.00 %	\$0.00
B20 - Exterior Enclosure	98.53 %	70.33 %	\$2,699,045.07
B30 - Roofing	110.00 %	89.19 %	\$609,876.20
C10 - Interior Construction	97.70 %	31.14 %	\$520,186.50
C20 - Stairs	95.00 %	260.62 %	\$1,859,361.08
C30 - Interior Finishes	79.92 %	44.63 %	\$1,437,853.91
D10 - Conveying	100.00 %	265.62 %	\$1,012,601.25
D20 - Plumbing	49.66 %	59.75 %	\$830,560.11
D30 - HVAC	99.53 %	77.94 %	\$5,902,419.88
D40 - Fire Protection	105.71 %	177.49 %	\$973,857.58
D50 - Electrical	110.11 %	84.62 %	\$3,386,004.16
E10 - Equipment	105.71 %	0.00 %	\$0.00
E20 - Furnishings	105.00 %	0.00 %	\$0.00
G20 - Site Improvements	117.17 %	113.21 %	\$727,448.76
G40 - Site Electrical Utilities	142.18 %	0.00 %	\$0.00
Totals:	96.90 %	56.37 %	\$20,000,723.75

Condition Deficiency Priority

Facility Name	Gross Area (S.F.)	FCI %	1 - Response Time (< 2 yr)	2 - Response Time (2-3 yrs)	3 - Response Time (3-4 yrs)	4 - Response Time (4-5 yrs)	5 - Response Time (> 5 yrs)
B234001;McCall	68,076	56.03	\$3,167,182.42	\$1,611,844.11	\$7,351,582.14	\$3,579,516.71	\$3,563,149.61
G234001;Grounds	102,000	66.97	\$0.00	\$0.00	\$599,801.23	\$6,912.22	\$120,735.31
Total:		56.37	\$3,167,182.42	\$1,611,844.11	\$7,951,383.37	\$3,586,428.93	\$3,683,884.92

Deficiencies By Priority



Executive Summary

Building condition is evaluated based on the functional systems and elements of a building and organized according to the UNIFORMAT II Elemental Classification. The grouping of these systems and elements and applying a current replacement value to them develops a representative building cost model. Cost Models are developed for similar building types and functions. Systems and their elements are evaluated based on their current replacement values, life cycles, installation dates and next renewal dates. Systems and their elements that are within their useful lives are further evaluated to identify current deficient conditions that may have a significant impact on a system's or element's remaining service life, and to determine if they are beyond their predicted expected life. The system's or element's current replacement value is based on RS Means Commercial Cost Data.

Following are the cost model's system details for this facility. The Replacement Value is the amount needed to replace the property of the same present value. The Current Repair Amount, also known as Condition Needs, represents the budgeted contractor installed costs plus owner's soft costs for the repair, replacement or renewal for a component or system level deficiency. It excludes contributing costs for other components or systems that might also be associated with the corrective actions due to packaging the work. Facility Condition Index (FCI) FCI is an industry-standard measurement of facility condition calculated as the ratio of the costs to correct a facility's deficiencies to the facility's Current Replacement Value. It ranges from 0% (new) to 100% (very poor). Condition Index (CI) is calculated as the sum of a renewable system's Remaining Service Life (RSL) divided by the sum of a system's Replacement Value (both values exclude soft-cost to simplify calculation updates) expressed as a percentage ranging from 100% (new) to 0% (expired).

Function:	Elementary School
Gross Area (SF):	68,076
Year Built:	1909
Last Renovation:	
Replacement Value:	\$34,396,556
Repair Cost:	\$19,273,274.99
Total FCI:	56.03 %
Total RSLI:	95.94 %

Description:

Attributes:

General Attributes:

Active:	Open	Bldg ID:	B234001
Sewage Ejector:	No	Status:	Accepted by SDP
Site ID:	S234001		

Condition Summary

The Table below shows the CI and FCI for each major building system shown at the UNIFORMAT classification Level II. Note that Systems with lower FCIs require less investment than systems with higher FCIs.

UNIFORMAT Classification	RSLI %	FCI %	Current Repair Cost
A10 - Foundations	95.00 %	0.00 %	\$0.00
A20 - Basement Construction	95.00 %	3.17 %	\$41,509.25
B10 - Superstructure	95.00 %	0.00 %	\$0.00
B20 - Exterior Enclosure	98.53 %	70.33 %	\$2,699,045.07
B30 - Roofing	110.00 %	89.19 %	\$609,876.20
C10 - Interior Construction	97.70 %	31.14 %	\$520,186.50
C20 - Stairs	95.00 %	260.62 %	\$1,859,361.08
C30 - Interior Finishes	79.92 %	44.63 %	\$1,437,853.91
D10 - Conveying	100.00 %	265.62 %	\$1,012,601.25
D20 - Plumbing	49.66 %	59.75 %	\$830,560.11
D30 - HVAC	99.53 %	77.94 %	\$5,902,419.88
D40 - Fire Protection	105.71 %	177.49 %	\$973,857.58
D50 - Electrical	110.11 %	84.62 %	\$3,386,004.16
E10 - Equipment	105.71 %	0.00 %	\$0.00
E20 - Furnishings	105.00 %	0.00 %	\$0.00
Totals:	95.94 %	56.03 %	\$19,273,274.99

Condition Detail

This section of the report contains results of the Facility Condition Assessment. The building is separated into system components based on UNIFORMAT II classification. The columns in the System Listing table below represent the following:

1. System Code: A code that identifies the system.
2. System Description: A brief description of a system present in the building.
3. Unit Price \$: The unit price of the system.
4. UoM: The unit of measure for of the system.
5. Qty: The quantity for the system
6. Life: anticipated service life for the system based on Building Owners and Managers Association (BOMA) recommendations.
7. Year Installed: The date of system installation.
8. Calc Next Renewal Year: The date of system expiration based on the life, NR stands for non renewable.
9. Next Renewal Year: The suggested system expiration date by the assessor based on visual inspection.
10. CI: The Condition Index of the system.
11. FCI: The Facility Condition Index of the system.
12. RSL: Remaining Service Life.
13. eCR: eCOMET Condition Rating (not used).
14. Deficiency \$: The financial investment to repair/replace system.

System Listing

The System Listing table below lists each of the systems organized by their UNIFORMAT II classification. The assessment team was tasked with recording the most recent replacement year of each system, determining the remaining service life based on the theoretical life, and evaluating the condition to confirm the forecast next replacement year. The system listing is the basis for all data contained in the Building Assessment Report.

Additionally, a condition rating (eCR) based on the following guidelines is provided as observed at the time of the assessment.

- Excellent (E) - No noticeable distress or damage. The entire system is free from observable defect.
- Very Good (VG) - Overall no serviceability reduction for the entire system. No degradation of critical components and minor distress and defect noticeable for some but not non critical components within the system.
- Good (G) - Slight or no serviceability reduction for the entire system. There may be noticeable defects for some non critical components and slight noticeable degradation of the critical components.
- Fair (F) - Overall serviceability is degraded but adequate. There may be moderate deterioration for very few of the critical components and few of the non critical components may have severe degradation.
- Marginal (MA) - Overall serviceability and reliability loss. Most if not all of the non critical components suffer from severe degradation and a few of the critical component may have severe degradation.
- Moderate (MO) - Overall a significant serviceability loss. Most if not all the components have severe degradation with the reminder of the component showing visible distress.
- Very Poor (VP) - Overall the system is barely functional. All of the components are severely degraded.
- Non-Functional (NF) - Overall the system does not function with all the components having no serviceability and suffer from severe degradation.

System Code	System Description	Unit Price \$	UoM	Qty	Life	Year Installed	Calc Next Renewal Year	Next Renewal Year	RSLT%	FCI%	RSL	eCR	Deficiency \$	Replacement Value \$
A1010	Standard Foundations	\$18.40	S.F.	68,076	100	1909	2009	2110	95.00 %	0.00 %	95			\$1,252,598
A1030	Slab on Grade	\$7.73	S.F.	68,076	100	1909	2009	2110	95.00 %	0.00 %	95			\$526,227
A2010	Basement Excavation	\$6.55	S.F.	68,076	100	1909	2009	2110	95.00 %	0.00 %	95			\$445,898
A2020	Basement Walls	\$12.70	S.F.	68,076	100	1909	2009	2110	95.00 %	4.80 %	95		\$41,509.25	\$864,565
B1010	Floor Construction	\$75.10	S.F.	68,076	100	1909	2009	2110	95.00 %	0.00 %	95			\$5,112,508
B1020	Roof Construction	\$13.88	S.F.	68,076	100	1909	2009	2110	95.00 %	0.00 %	95			\$944,895
B2010	Exterior Walls	\$36.91	S.F.	68,076	100	1909	2009	2110	95.00 %	42.04 %	95		\$1,056,310.30	\$2,512,685
B2020	Exterior Windows	\$18.01	S.F.	68,076	40	1980	2020	2057	105.00 %	133.99 %	42		\$1,642,734.77	\$1,226,049
B2030	Exterior Doors	\$1.45	S.F.	68,076	25	1990	2015	2042	108.00 %	0.00 %	27			\$98,710
B3010105	Built-Up	\$37.76	S.F.	18,000	20	1990	2010	2037	110.00 %	89.73 %	22		\$609,876.20	\$679,680
B3010120	Single Ply Membrane	\$38.73	S.F.		20				0.00 %	0.00 %				\$0
B3010130	Preformed Metal Roofing	\$54.22	S.F.		30				0.00 %	0.00 %				\$0
B3010140	Shingle & Tile	\$38.73	S.F.		25				0.00 %	0.00 %				\$0
B3020	Roof Openings	\$0.06	S.F.	68,076	20			2037	110.00 %	0.00 %	22			\$4,085
C1010	Partitions	\$17.91	S.F.	68,076	100	1909	2009	2110	95.00 %	33.69 %	95		\$410,702.60	\$1,219,241
C1020	Interior Doors	\$3.51	S.F.	68,076	40	1998	2038	2057	105.00 %	18.63 %	42		\$44,525.56	\$238,947
C1030	Fittings	\$3.12	S.F.	68,076	40	2000	2040	2057	105.00 %	30.58 %	42		\$64,958.34	\$212,397
C2010	Stair Construction	\$10.48	S.F.	68,076	100	1909	2009	2110	95.00 %	260.62 %	95		\$1,859,361.08	\$713,436

Site Assessment Report - B234001;McCall

System Code	System Description	Unit Price \$	UoM	Qty	Life	Year Installed	Calc Next Renewal Year	Next Renewal Year	RSLI%	FCI%	RSL	eCR	Deficiency \$	Replacement Value \$
C3010230	Paint & Covering	\$13.21	S.F.	68,076	10	2005	2015		0.00 %	57.16 %	0		\$514,024.56	\$899,284
C3010231	Vinyl Wall Covering	\$0.97	S.F.	68,076	15				0.00 %	0.00 %				\$66,034
C3010232	Wall Tile	\$2.63	S.F.	68,076	30				0.00 %	0.00 %				\$179,040
C3020411	Carpet	\$7.30	S.F.	1,650	10	2005	2015		0.00 %	157.94 %	0		\$19,024.31	\$12,045
C3020412	Terrazzo & Tile	\$75.52	S.F.		50				0.00 %	0.00 %				\$0
C3020413	Vinyl Flooring	\$9.68	S.F.	17,150	20	1998	2018	2037	110.00 %	40.20 %	22		\$66,733.34	\$166,012
C3020414	Wood Flooring	\$22.27	S.F.	20,200	25	1909	1934	2042	108.00 %	41.78 %	27		\$187,927.26	\$449,854
C3020415	Concrete Floor Finishes	\$0.97	S.F.	22,400	50	1909	1959	2065	100.00 %	0.00 %	50			\$21,728
C3030	Ceiling Finishes	\$20.97	S.F.	68,076	25	1998	2023	2048	132.00 %	45.54 %	33		\$650,144.44	\$1,427,554
D1010	Elevators and Lifts	\$5.60	S.F.	68,076	35	2015	2050		100.00 %	265.62 %	35		\$1,012,601.25	\$381,226
D2010	Plumbing Fixtures	\$13.52	S.F.	68,076	35	1909	1944	2025	28.57 %	21.16 %	10		\$194,718.10	\$920,388
D2020	Domestic Water Distribution	\$1.68	S.F.	68,076	25	1909	1934	2025	40.00 %	0.00 %	10			\$114,368
D2030	Sanitary Waste	\$2.90	S.F.	68,076	25	1909	1934	2042	108.00 %	169.16 %	27		\$333,963.76	\$197,420
D2040	Rain Water Drainage	\$2.32	S.F.	68,076	30	1909	1939	2047	106.67 %	191.14 %	32		\$301,878.25	\$157,936
D3020	Heat Generating Systems	\$18.67	S.F.	68,076	24	2010	2034		79.17 %	0.00 %	19			\$1,270,979
D3030	Cooling Generating Systems	\$24.48	S.F.	68,076	20			2037	110.00 %	58.94 %	22		\$982,294.47	\$1,666,500
D3040	Distribution Systems	\$42.99	S.F.	68,076	25	1909	1934	2042	108.00 %	118.22 %	27		\$3,459,752.22	\$2,926,587
D3050	Terminal & Package Units	\$11.60	S.F.	68,076	15	2010	2025		66.67 %	0.00 %	10			\$789,682
D3060	Controls & Instrumentation	\$13.50	S.F.	68,076	20	1909	1929	2037	110.00 %	158.90 %	22		\$1,460,373.19	\$919,026
D4010	Sprinklers	\$7.05	S.F.	68,076	35			2052	105.71 %	202.91 %	37		\$973,857.58	\$479,936
D4020	Standpipes	\$1.01	S.F.	68,076	35			2052	105.71 %	0.00 %	37			\$68,757
D5010	Electrical Service/Distribution	\$9.70	S.F.	68,076	30	1909	1939	2047	106.67 %	189.78 %	32		\$1,253,169.53	\$660,337
D5020	Lighting and Branch Wiring	\$34.68	S.F.	68,076	20	1909	1929	2037	110.00 %	54.78 %	22		\$1,293,179.21	\$2,360,876
D5030	Communications and Security	\$12.99	S.F.	68,076	15	1909	1924	2032	113.33 %	52.94 %	17		\$468,125.41	\$884,307
D5090	Other Electrical Systems	\$1.41	S.F.	68,076	30	1909	1939	2047	106.67 %	387.06 %	32		\$371,530.01	\$95,987
E1020	Institutional Equipment	\$4.82	S.F.	68,076	35	1990	2025	2052	105.71 %	0.00 %	37			\$328,126
E1090	Other Equipment	\$11.10	S.F.	68,076	35	1990	2025	2052	105.71 %	0.00 %	37			\$755,644
E2010	Fixed Furnishings	\$2.13	S.F.	68,076	40	1965	2005	2057	105.00 %	0.00 %	42			\$145,002
Total									95.94 %	56.03 %			\$19,273,274.99	\$34,396,556

System Notes

The facility description in the site executive summary contains an overview of each system. The notes listed below provide additional information on select systems found within the facility.

No data found for this asset

Renewal Schedule

eCOMET forecasts future Capital Renewal funding needed to address expiring systems based on the Next Renewal year found in the Cost Models. A 3% annual inflation factor is applied to the costs for systems expiring in future years. The table below reflects recommended Capital Renewal funding needs over the next 10 years. Note: Cells with a zero value indicate systems for which renewal is not scheduled in that year.

Inflation Rate: 3%

System	Current Deficiencies	2016	2017	2018	2019	2020	2021	2022	2023	2024	2025	Total
Total:	\$19,273,275	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$4,044,304	\$23,317,579
* A - Substructure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
A10 - Foundations	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
A1010 - Standard Foundations	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
A1030 - Slab on Grade	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
A20 - Basement Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
A2010 - Basement Excavation	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
A2020 - Basement Walls	\$41,509	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$41,509
B - Shell	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B10 - Superstructure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B1010 - Floor Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B1020 - Roof Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B20 - Exterior Enclosure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B2010 - Exterior Walls	\$1,056,310	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$1,056,310
B2020 - Exterior Windows	\$1,642,735	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$1,642,735
B2030 - Exterior Doors	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B30 - Roofing	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3010 - Roof Coverings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3010105 - Built-Up	\$609,876	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$609,876
B3010120 - Single Ply Membrane	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3010130 - Preformed Metal Roofing	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3010140 - Shingle & Tile	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3020 - Roof Openings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C - Interiors	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C10 - Interior Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C1010 - Partitions	\$410,703	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$410,703

Site Assessment Report - B234001;McCall

C1020 - Interior Doors	\$44,526	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$44,526
C1030 - Fittings	\$64,958	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$64,958
C20 - Stairs	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C2010 - Stair Construction	\$1,859,361	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$1,859,361
C30 - Interior Finishes	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C3010 - Wall Finishes	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C3010230 - Paint & Covering	\$514,025	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$1,329,418	\$1,843,443
C3010231 - Vinyl Wall Covering	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C3010232 - Wall Tile	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C3020 - Floor Finishes	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C3020411 - Carpet	\$19,024	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$17,807	\$36,831
C3020412 - Terrazzo & Tile	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C3020413 - Vinyl Flooring	\$66,733	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$66,733
C3020414 - Wood Flooring	\$187,927	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$187,927
C3020415 - Concrete Floor Finishes	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C3030 - Ceiling Finishes	\$650,144	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$650,144
D - Services	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D10 - Conveying	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D1010 - Elevators and Lifts	\$1,012,601	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$1,012,601
D20 - Plumbing	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D2010 - Plumbing Fixtures	\$194,718	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$1,360,616	\$1,555,334
D2020 - Domestic Water Distribution	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$169,070	\$169,070
D2030 - Sanitary Waste	\$333,964	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$333,964
D2040 - Rain Water Drainage	\$301,878	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$301,878
D30 - HVAC	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D3020 - Heat Generating Systems	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D3030 - Cooling Generating Systems	\$982,294	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$982,294
D3040 - Distribution Systems	\$3,459,752	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$3,459,752
D3050 - Terminal & Package Units	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$1,167,393	\$1,167,393
D3060 - Controls & Instrumentation	\$1,460,373	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$1,460,373
D40 - Fire Protection	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D4010 - Sprinklers	\$973,858	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$973,858
D4020 - Standpipes	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0


Site Assessment Report - B234001;McCall

D50 - Electrical	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5010 - Electrical Service/Distribution	\$1,253,170	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$1,253,170
D5020 - Lighting and Branch Wiring	\$1,293,179	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$1,293,179
D5030 - Communications and Security	\$468,125	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$468,125
D5090 - Other Electrical Systems	\$371,530	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$371,530
E - Equipment & Furnishings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E10 - Equipment	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E1020 - Institutional Equipment	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E1090 - Other Equipment	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E20 - Furnishings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E2010 - Fixed Furnishings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0

* Indicates non-renewable system

Forecasted Sustainment Requirement

The following chart shows the current building deficiencies and forecasting sustainment requirements over the next ten years.




10 Year FCI Forecast by Investment Scenario

The chart below illustrates the effect of various investment levels on the building FCI for the next 10 years. The levels of investment shown below include:

- Current FCI: a variable investment amount based on renewing expired systems to maintain the current FCI for the building
- 2% Investment: an annual investment of 2% of the replacement value of the building, escalated for inflation
- 4% Investment: an annual investment of 4% of the replacement value of the building, escalated for inflation


Facility Investment vs. FCI Forecast



Year	Investment Amount Current FCI - 56.03%	2% Investment		4% Investment	
		Amount	FCI	Amount	FCI
2016	\$0	\$708,569.00	54.03 %	\$1,417,138.00	52.03 %
2017	\$17,180,630	\$729,826.00	99.11 %	\$1,459,652.00	95.11 %
2018	\$0	\$751,721.00	97.11 %	\$1,503,442.00	91.11 %
2019	\$0	\$774,273.00	95.11 %	\$1,548,545.00	87.11 %
2020	\$0	\$797,501.00	93.11 %	\$1,595,001.00	83.11 %
2021	\$0	\$821,426.00	91.11 %	\$1,642,851.00	79.11 %
2022	\$0	\$846,069.00	89.11 %	\$1,692,137.00	75.11 %
2023	\$1,989,220	\$871,451.00	91.68 %	\$1,742,901.00	75.68 %
2024	\$0	\$897,594.00	89.68 %	\$1,795,188.00	71.68 %
2025	\$4,044,304	\$924,522.00	96.43 %	\$1,849,044.00	76.43 %
Total:	\$23,214,155	\$8,122,952.00		\$16,245,899.00	

Deficiency Summary by System


Current deficiencies included assemblies that have reached or exceeded their design life or components of the assemblies that are in need of repair. Assemblies that have reached their design life are identified as current deficiencies and assigned the distress 'Beyond Useful Life'. The following chart lists all current deficiencies associated with this facility.



Budget Estimate Total: \$19,273,274.99

Deficiency Summary by Priority

The following chart shows the total repair costs broken down by priority. Assessors assigned deficiencies within eCOMET to one of the following priority categories:



Budget Estimate Total: \$19,273,274.99


Deficiency By Priority Investment Table

The table below shows the current investment cost grouped by deficiency priority and building system.

System Code	System Description	1 - Response Time (< 2 yr)	2 - Response Time (2-3 yrs)	3 - Response Time (3-4 yrs)	4 - Response Time (4-5 yrs)	5 - Response Time (> 5 yrs)	Total
A2020	Basement Walls	\$0.00	\$41,509.25	\$0.00	\$0.00	\$0.00	\$41,509.25
B2010	Exterior Walls	\$0.00	\$1,056,310.30	\$0.00	\$0.00	\$0.00	\$1,056,310.30
B2020	Exterior Windows	\$0.00	\$0.00	\$0.00	\$1,642,734.77	\$0.00	\$1,642,734.77
B3010105	Built-Up	\$0.00	\$0.00	\$0.00	\$609,876.20	\$0.00	\$609,876.20
C1010	Partitions	\$0.00	\$0.00	\$0.00	\$0.00	\$410,702.60	\$410,702.60
C1020	Interior Doors	\$0.00	\$0.00	\$0.00	\$44,525.56	\$0.00	\$44,525.56
C1030	Fittings	\$0.00	\$0.00	\$0.00	\$64,958.34	\$0.00	\$64,958.34
C2010	Stair Construction	\$1,859,361.08	\$0.00	\$0.00	\$0.00	\$0.00	\$1,859,361.08
C3010230	Paint & Covering	\$0.00	\$514,024.56	\$0.00	\$0.00	\$0.00	\$514,024.56
C3020411	Carpet	\$0.00	\$0.00	\$0.00	\$19,024.31	\$0.00	\$19,024.31
C3020413	Vinyl Flooring	\$0.00	\$0.00	\$66,733.34	\$0.00	\$0.00	\$66,733.34
C3020414	Wood Flooring	\$0.00	\$0.00	\$0.00	\$0.00	\$187,927.26	\$187,927.26
C3030	Ceiling Finishes	\$0.00	\$0.00	\$0.00	\$128,292.35	\$521,852.09	\$650,144.44
D1010	Elevators and Lifts	\$0.00	\$0.00	\$1,012,601.25	\$0.00	\$0.00	\$1,012,601.25
D2010	Plumbing Fixtures	\$0.00	\$0.00	\$194,718.10	\$0.00	\$0.00	\$194,718.10
D2030	Sanitary Waste	\$333,963.76	\$0.00	\$0.00	\$0.00	\$0.00	\$333,963.76
D2040	Rain Water Drainage	\$0.00	\$0.00	\$301,878.25	\$0.00	\$0.00	\$301,878.25
D3030	Cooling Generating Systems	\$0.00	\$0.00	\$0.00	\$0.00	\$982,294.47	\$982,294.47
D3040	Distribution Systems	\$0.00	\$0.00	\$3,459,752.22	\$0.00	\$0.00	\$3,459,752.22
D3060	Controls & Instrumentation	\$0.00	\$0.00	\$0.00	\$0.00	\$1,460,373.19	\$1,460,373.19
D4010	Sprinklers	\$973,857.58	\$0.00	\$0.00	\$0.00	\$0.00	\$973,857.58
D5010	Electrical Service/Distribution	\$0.00	\$0.00	\$358,966.10	\$894,203.43	\$0.00	\$1,253,169.53
D5020	Lighting and Branch Wiring	\$0.00	\$0.00	\$1,293,179.21	\$0.00	\$0.00	\$1,293,179.21
D5030	Communications and Security	\$0.00	\$0.00	\$292,223.66	\$175,901.75	\$0.00	\$468,125.41
D5090	Other Electrical Systems	\$0.00	\$0.00	\$371,530.01	\$0.00	\$0.00	\$371,530.01
	Total:	\$3,167,182.42	\$1,611,844.11	\$7,351,582.14	\$3,579,516.71	\$3,563,149.61	\$19,273,274.99

Deficiency Summary by Category

The following chart shows the total repair costs broken down by deficiency categories. Assessors assigned deficiencies to one of the following categories:



Deficiency Details by Priority

The deficiency detail notes listed below provide additional information on identified deficiencies found within the facility.

Priority 1 - Response Time (< 2 yr):

System: C2010 - Stair Construction



Location: Exterior/ fire tower stair

Distress: Failing

Category: 3 - Operations / Maint.

Priority: 1 - Response Time (< 2 yr)

Correction: Replace enclosed egress masonry stair tower including new stairs - per flight approximately 600 SF footprint and 15' floor to floor

Qty: 8.00

Unit of Measure: Flight


Estimate: \$1,429,158.46

Assessor Name: System

Date Created: 09/17/2015

Notes: Rebuild fire exit tower

System: C2010 - Stair Construction



Location: Exterior/ fire tower stair

Distress: Failing

Category: 3 - Operations / Maint.

Priority: 1 - Response Time (< 2 yr)

Correction: Replace exterior enclosed stair tower egress stairs - per flight of stairs - stairs only

Qty: 8.00

Unit of Measure: Flight

Estimate: \$430,202.62

Assessor Name: System

Date Created: 09/17/2015

Notes: Install new stairs in fire exit tower

System: D2030 - Sanitary Waste



Location: Throughout building

Distress: Health Hazard / Risk

Category: 1 - Health & Safety

Priority: 1 - Response Time (< 2 yr)

Correction: Inspect sanitary waste piping and replace damaged sections. (+50KSF)

Qty: 68,076.00

Unit of Measure: S.F.

Estimate: \$333,963.76

Assessor Name: System

Date Created: 08/06/2015

Notes: Hire a qualified contractor to perform a detailed examination of the sanitary waste piping using visual inspection and video cameras to locate and replace any damaged piping and to further quantify the extent of potential failures.

System: D4010 - Sprinklers



Location: Throughout building

Distress: Life Safety / NFPA / PFD

Category: 1 - Health & Safety

Priority: 1 - Response Time (< 2 yr)

Correction: Install a fire protection sprinkler system

Qty: 68,076.00

Unit of Measure: S.F.

Estimate: \$973,857.58

Assessor Name: System

Date Created: 08/06/2015

Notes: Install a fire protection sprinkler system with quick response type heads to reduce insurance costs by providing protection for the property. A fire pump may be required depending on the available city water pressure.

Priority 2 - Response Time (2-3 yrs):

System: A2020 - Basement Walls



Location: Interior/ basement

Distress: Health Hazard / Risk

Category: 1 - Health & Safety

Priority: 2 - Response Time (2-3 yrs)

Correction: Mold abatement on basement walls - insert proper quantities

Qty: 1,000.00

Unit of Measure: S.F.

Estimate: \$41,509.25

Assessor Name: System

Date Created: 09/17/2015

Notes: Conduct mildew remediation in basement

System: B2010 - Exterior Walls



Location: Exterior

Distress: Damaged

Category: 3 - Operations / Maint.

Priority: 2 - Response Time (2-3 yrs)

Correction: Repair cracks in masonry - replace missing mortar and repoint - SF of wall area

Qty: 30,000.00

Unit of Measure: S.F.


Estimate: \$1,056,310.30

Assessor Name: System

Date Created: 09/17/2015

Notes: Repair and stabilize cracked exterior bearing walls

System: C3010230 - Paint & Covering



Location: Interior

Distress: Beyond Service Life

Category: 3 - Operations / Maint.

Priority: 2 - Response Time (2-3 yrs)

Correction: Repair substrate and repaint interior walls - SF of wall surface

Qty: 60,000.00

Unit of Measure: S.F.

Estimate: \$514,024.56

Assessor Name: System

Date Created: 09/18/2015

Notes: Repair and repaint interior walls (40% area)

Priority 3 - Response Time (3-4 yrs):

System: C3020413 - Vinyl Flooring



Location: interior

Distress: Health Hazard / Risk

Category: 1 - Health & Safety

Priority: 3 - Response Time (3-4 yrs)

Correction: Remove VAT and replace with VCT - SF of area

Qty: 4,400.00

Unit of Measure: S.F.

Estimate: \$66,733.34

Assessor Name: System

Date Created: 09/18/2015

Notes: Replace all VAT floor tiles

System: D1010 - Elevators and Lifts

This deficiency has no image.

Location: Interior

Distress: Accessibility

Category: 2 - Code Compliance

Priority: 3 - Response Time (3-4 yrs)

Correction: Add external 4 stop elevator - adjust the electrical run lengths to hook up the elevator

Qty: 1.00

Unit of Measure: Ea.

Estimate: \$1,012,601.25

Assessor Name: System

Date Created: 09/18/2015

Notes: Provide ADA compliant elevator serving basement and all floors (exterior)

System: D2010 - Plumbing Fixtures



Location: Restrooms

Distress: Beyond Service Life

Category: 3 - Operations / Maint.

Priority: 3 - Response Time (3-4 yrs)

Correction: Remove and replace or replace water closet - quantify additional units

Qty: 20.00

Unit of Measure: Ea.

Estimate: \$149,242.96

Assessor Name: System

Date Created: 08/06/2015

Notes: Replace the water closets in the restrooms with new code compliant fixtures.

System: D2010 - Plumbing Fixtures



Location: Corridors

Distress: Beyond Service Life

Category: 3 - Operations / Maint.

Priority: 3 - Response Time (3-4 yrs)

Correction: Remove and Replace Water Fountains - without ADA new recessed alcove

Qty: 6.00

Unit of Measure: Ea.

Estimate: \$45,475.14

Assessor Name: System

Date Created: 08/06/2015

Notes: Replace the wall hung drinking fountains and integral refrigerated coolers in the corridors and at the restrooms. These units are well beyond their service life.

System: D2040 - Rain Water Drainage



Location: Throughout building

Distress: Beyond Service Life

Category: 3 - Operations / Maint.

Priority: 3 - Response Time (3-4 yrs)

Correction: Inspect internal rain water drainage piping and replace pipe - based on SF of multi-story building - insert SF of building

Qty: 68,076.00

Unit of Measure: S.F.

Estimate: \$301,878.25

Assessor Name: System

Date Created: 11/18/2015

Notes: Hire a qualified contractor to perform a detailed examination of the rain water drainage piping using visual inspection and video cameras to locate and replace any damaged piping and to further quantify the extent of potential failures.

System: D3040 - Distribution Systems



Location: Throughout building

Distress: Beyond Service Life

Category: 3 - Operations / Maint.

Priority: 3 - Response Time (3-4 yrs)

Correction: Replace the existing unit ventilators with new units designed to provide adequate ventilation per ASHRAE Std 62 - insert the SF of bldg. in the qty.

Qty: 68,076.00

Unit of Measure: S.F.

Estimate: \$2,888,337.79

Assessor Name: System

Date Created: 08/06/2015

Notes: Remove the existing unit ventilators and install units with hot and chilled water coils and integral heat exchangers to introduce outdoor air to the building.

System: D3040 - Distribution Systems



Location: Auditorium Mechanical room

Distress: Beyond Service Life

Category: 3 - Operations / Maint.

Priority: 3 - Response Time (3-4 yrs)

Correction: Install HVAC unit for Gymnasium (single station).

Qty: 6,000.00

Unit of Measure: Ea.

Estimate: \$308,301.04

Assessor Name: System

Date Created: 08/06/2015

Notes: Provide ventilation for the Gymnasium/Cafeteria by installing a fan coil air handling unit installed in the mechanical room behind the Auditorium stage and utilize the existing outdoor air intake.

System: D3040 - Distribution Systems



Location: Auditorium Mechanical room

Distress: Beyond Service Life

Category: 3 - Operations / Maint.

Priority: 3 - Response Time (3-4 yrs)

Correction: Install / replace HVAC unit for Auditorium (800 seat).

Qty: 350.00

Unit of Measure: Seat

Estimate: \$195,744.07

Assessor Name: System

Date Created: 08/06/2015

Notes: Provide ventilation for the Auditorium by installing a fan coil air handling unit in the mechanical room behind the Auditorium stage and utilize the existing outdoor air intake.

System: D3040 - Distribution Systems



Location: Roof

Distress: Beyond Service Life

Category: 3 - Operations / Maint.

Priority: 3 - Response Time (3-4 yrs)

Correction: Replace utility set exhaust fan (5 HP)

Qty: 2.00

Unit of Measure: Ea.

Estimate: \$67,369.32

Assessor Name: System

Date Created: 08/06/2015

Notes: Replace existing exhaust fans on the roof serving the bathrooms and utilize the existing ductwork.

System: D5010 - Electrical Service/Distribution



Location: Basement

Distress: Inadequate

Category: 4 - Capital Improvement

Priority: 3 - Response Time (3-4 yrs)

Correction: Replace Substation

Qty: 0.00

Unit of Measure: Ea.

Estimate: \$358,966.10

Assessor Name: System

Date Created: 08/11/2015

Notes: Replace existing substation with new 480/277V sized to provide power for an elevator and air conditioning equipment.

System: D5020 - Lighting and Branch Wiring



Location: Throughout Building

Distress: Inadequate

Category: 4 - Capital Improvement

Priority: 3 - Response Time (3-4 yrs)

Correction: Replace Lighting Fixtures (SF)

Qty: 0.00

Unit of Measure: S.F.

Estimate: \$1,163,061.90

Assessor Name: System

Date Created: 08/11/2015

Notes: Replace existing T12 fixtures with T8 fixtures and incandescent fixtures with compact fluorescent.

System: D5020 - Lighting and Branch Wiring



Location: Throughout Building

Distress: Inadequate

Category: 4 - Capital Improvement

Priority: 3 - Response Time (3-4 yrs)

Correction: Add wiring device

Qty: 1.00

Unit of Measure: Ea.

Estimate: \$130,117.31

Assessor Name: System

Date Created: 08/11/2015

Notes: Install minimum 2 receptacles on each wall of classrooms and other purpose rooms.

System: D5030 - Communications and Security



Location: Throughout Building

Distress: Life Safety / NFPA / PFD

Category: 1 - Health & Safety

Priority: 3 - Response Time (3-4 yrs)

Correction: Replace fire alarm system

Qty: 1.00

Unit of Measure: S.F.

Estimate: \$292,223.66

Assessor Name: System

Date Created: 08/11/2015

Notes: Install a new addressable fire alarm system and provide audible and/or visual devices in all areas.

System: D5090 - Other Electrical Systems

This deficiency has no image.

Location: Basement

Distress: Inadequate

Category: 4 - Capital Improvement

Priority: 3 - Response Time (3-4 yrs)

Correction: Add Standby Generator System

Qty: 1.00

Unit of Measure: Ea.


Estimate: \$144,365.01

Assessor Name: System

Date Created: 08/11/2015

Notes: Install a generator sized to operate the elevator and emergency lighting.

System: D5090 - Other Electrical Systems



Location: Throughout Building

Distress: Health Hazard / Risk

Category: 1 - Health & Safety

Priority: 3 - Response Time (3-4 yrs)

Correction: Replace Emergency/Exit Lighting

Qty: 1.00

Unit of Measure: Ea.


Estimate: \$126,209.45

Assessor Name: System

Date Created: 08/11/2015

Notes: Replace existing EXIT fixtures with new LED type.

System: D5090 - Other Electrical Systems



Location: Throughout Building

Distress: Life Safety / NFPA / PFD

Category: 1 - Health & Safety

Priority: 3 - Response Time (3-4 yrs)

Correction: Replace Emergency/Exit Lighting

Qty: 1.00

Unit of Measure: Ea.

Estimate: \$100,955.55

Assessor Name: System

Date Created: 08/11/2015

Notes: Provide new emergency lighting throughout the building

Priority 4 - Response Time (4-5 yrs):

System: B2020 - Exterior Windows



Location: Exterior

Distress: Beyond Service Life

Category: 3 - Operations / Maint.

Priority: 4 - Response Time (4-5 yrs)

Correction: Remove and replace aluminum windows - pick the appropriate size and style and insert the number of units

Qty: 272.00

Unit of Measure: Ea.

Estimate: \$1,642,734.77

Assessor Name: System

Date Created: 09/17/2015

Notes: Replace all windows

System: B3010105 - Built-Up



Location: Exterior/ roof

Distress: Building Envelope Integrity

Category: 3 - Operations / Maint.

Priority: 4 - Response Time (4-5 yrs)

Correction: Remove and Replace Built Up Roof

Qty: 18,000.00

Unit of Measure: S.F.

Estimate: \$609,876.20

Assessor Name: System

Date Created: 09/17/2015

Notes: Install all new roofing system including insulation; tear-down existing roofing; install flashing, counter flashing and reglets

System: C1020 - Interior Doors



Location: Interior

Distress: Accessibility

Category: 2 - Code Compliance

Priority: 4 - Response Time (4-5 yrs)

Correction: Replace door knobs with compliant lever type

Qty: 80.00

Unit of Measure: Ea.


Estimate: \$44,525.56

Assessor Name: System

Date Created: 09/18/2015

Notes: Provide ADA compliant hardware on interior doors

System: C1030 - Fittings



Location: Interior

Distress: Accessibility

Category: 2 - Code Compliance

Priority: 4 - Response Time (4-5 yrs)

Correction: Remove and replace damaged toilet partitions - handicap units

Qty: 20.00

Unit of Measure: Ea.


Estimate: \$64,958.34

Assessor Name: System

Date Created: 09/18/2015

Notes: Reconfigure toilets on each floor for accessibility, provide new toilet partitions

System: C3020411 - Carpet



Notes: Replace carpet in library

Location: Interior

Distress: Beyond Service Life

Category: 3 - Operations / Maint.

Priority: 4 - Response Time (4-5 yrs)

Correction: Remove and replace carpet

Qty: 1,700.00


Unit of Measure: S.F.

Estimate: \$19,024.31

Assessor Name: System

Date Created: 09/18/2015

System: C3030 - Ceiling Finishes



Notes: Repair and repaint exposed ceilings

Location: Interior

Distress: Beyond Service Life

Category: 3 - Operations / Maint.

Priority: 4 - Response Time (4-5 yrs)

Correction: Re-paint ceilings - SF of ceilings

Qty: 26,800.00

Unit of Measure: S.F.

Estimate: \$128,292.35

Assessor Name: System

Date Created: 09/17/2015

System: D5010 - Electrical Service/Distribution



Location: Electrical Room

Distress: Inadequate

Category: 4 - Capital Improvement

Priority: 4 - Response Time (4-5 yrs)

Correction: Replace Electrical DIstribution System (U1)

Qty: 1.00

Unit of Measure: Ea.

Estimate: \$519,183.07

Assessor Name: System

Date Created: 10/21/2015

Notes: Replace existing substation with new 480/277V sized to provide power for an elevator and air conditioning equipment.

System: D5010 - Electrical Service/Distribution



Location: Electrical Room

Distress: Inadequate

Category: 4 - Capital Improvement

Priority: 4 - Response Time (4-5 yrs)

Correction: Replace Service Transformer

Qty: 0.00

Unit of Measure: Ea.

Estimate: \$375,020.36

Assessor Name: System

Date Created: 10/21/2015

Notes: Replace existing transformer with new 1000 KVA transformer (13.2KV - 480V/277V) sized to provide power for existing loads plus the new air conditioning equipment.

System: D5030 - Communications and Security



Location: interior/exterior and Main Entrance

Distress: Inadequate

Category: 4 - Capital Improvement

Priority: 4 - Response Time (4-5 yrs)

Correction: Add/Replace Video Surveillance System

Qty: 1.00

Unit of Measure: Ea.

Estimate: \$100,799.59

Assessor Name: System

Date Created: 08/11/2015

Notes: Add video surveillance to interior, main entrance/courtyard.

System: D5030 - Communications and Security



Location: Main Entrance/court yard

Distress: Inadequate

Category: 4 - Capital Improvement

Priority: 4 - Response Time (4-5 yrs)

Correction: Add/Replace Paging System

Qty: 1.00

Unit of Measure: Ea.

Estimate: \$75,102.16

Assessor Name: System

Date Created: 08/11/2015

Notes: Add site paging to main entrance and courtyard.

Priority 5 - Response Time (> 5 yrs):

System: C1010 - Partitions



Location: Interior

Distress: Damaged

Category: 3 - Operations / Maint.

Priority: 5 - Response Time (> 5 yrs)

Correction: Folding partition inoperable - remove and replace - select quality

Qty: 1,500.00

Unit of Measure: S.F.

Estimate: \$410,702.60

Assessor Name: System

Date Created: 09/18/2015

Notes: Replace inoperable movable partitions

System: C3020414 - Wood Flooring



Location: Interior

Distress: Beyond Service Life

Category: 3 - Operations / Maint.

Priority: 5 - Response Time (> 5 yrs)

Correction: Remove and replace partial area of wood flooring and refinish entire floor - set replacement area

Qty: 20,200.00

Unit of Measure: S.F.

Estimate: \$187,927.26

Assessor Name: System

Date Created: 09/18/2015

Notes: Repair refinish hardwood flooring

System: C3030 - Ceiling Finishes



Location: Interior

Distress: Beyond Service Life

Category: 3 - Operations / Maint.

Priority: 5 - Response Time (> 5 yrs)

Correction: Remove and replace suspended acoustic ceilings - lighting not included

Qty: 34,600.00

Unit of Measure: S.F.

Estimate: \$521,852.09

Assessor Name: System

Date Created: 09/17/2015

Notes: Replace all suspended acoustical ceilings

System: D3030 - Cooling Generating Systems



Location: Throughout building

Distress: Inadequate

Category: 4 - Capital Improvement

Priority: 5 - Response Time (> 5 yrs)

Correction: Install chilled water system with distribution piping and pumps. (+75KSF)

Qty: 68,076.00

Unit of Measure: S.F.

Estimate: \$982,294.47

Assessor Name: System

Date Created: 08/06/2015

Notes: Remove the window air conditioning units and install a 170 ton air-cooled chiller on the roof with chilled water distribution piping and pumps located in the mechanical room to supply more reliable air conditioning for the building with a much longer service life.

System: D3060 - Controls & Instrumentation



Location: Throughout building

Distress: Inadequate

Category: 4 - Capital Improvement

Priority: 5 - Response Time (> 5 yrs)

Correction: Replace pneumatic controls with DDC (75KSF)

Qty: 68,076.00

Unit of Measure: S.F.

Estimate: \$1,460,373.19

Assessor Name: System

Date Created: 08/06/2015

Notes: Replace the pneumatic controls for the HVAC systems with modern DDC modules, valves and actuators to improve reliability and energy efficiency. Provide a new building automation system (BAS) with communication interface to the preferred system in use throughout the District.

Equipment Inventory

The following table represents the inventory details of the inventory found in the building, which fall under the following subsystems:

Subsystem	Inventory	Qty	UoM	Location	Manufacturer	Model Number	Serial Number	Barcode	Life	Install Date	Next Renewal	Raw Cost	Inventory Cost
D3020 Heat Generating Systems	Boiler, gas/oil combination, cast iron, hot water, gross output, 3796 MBH, includes burners, controls and insulated jacket, packaged	1.00	Ea.	Boiler Room	Buderus	Logano GE615			35	2010	2045	\$84,333.50	\$92,766.85
D3020 Heat Generating Systems	Boiler, gas/oil combination, cast iron, hot water, gross output, 3796 MBH, includes burners, controls and insulated jacket, packaged	1.00	Ea.	Boiler Room	Buderus	Logano GE615			35	2010	2045	\$84,333.50	\$92,766.85
D3020 Heat Generating Systems	Pump, base mounted with motor, end-suction, 4" size, 7-1/2 HP, to 350 GPM	2.00	Ea.	Boiler room	Taco	FI			35	2010	2045	\$27,265.35	\$59,983.77
D3020 Heat Generating Systems	Pump, base mounted with motor, end-suction, 4" size, 7-1/2 HP, to 350 GPM	2.00	Ea.	Boiler room	Taco	FI			35	2010	2045	\$27,265.35	\$59,983.77
D5010 Electrical Service/Distribution	Load interrupter switch, 2 position, 400 kVA & above w/CLF fuses, 4.8 kV, 600 amp, NEMA 1	1.00	Ea.	Electrical Room	Westinghouse				30			\$38,502.00	\$42,352.20
D5010 Electrical Service/Distribution	Switchboards, fused switch, 4 wire, 120/208 V, 1200 amp, incl CT compartment, excl CT's or PT's	1.00	Ea.	Electrical Room	Westinghouse		PHYB-72410		30			\$22,604.40	\$24,864.84
D5010 Electrical Service/Distribution	Transformers, 4800 volts to 480/277 volts, 500 kVA	1.00	Ea.	Electrical Room	Hevi-Duty Electric Co				30			\$65,205.00	\$71,725.50
												Total:	\$444,443.78

Executive Summary

Building condition is evaluated based on the functional systems and elements of a building and organized according to the UNIFORMAT II Elemental Classification. The grouping of these systems and elements and applying a current replacement value to them develops a representative building cost model. Cost Models are developed for similar building types and functions. Systems and their elements are evaluated based on their current replacement values, life cycles, installation dates and next renewal dates. Systems and their elements that are within their useful lives are further evaluated to identify current deficient conditions that may have a significant impact on a system's or element's remaining service life, and to determine if they are beyond their predicted expected life. The system's or element's current replacement value is based on RS Means Commercial Cost Data.

Following are the cost model's system details for this facility. The Replacement Value is the amount needed to replace the property of the same present value. The Current Repair Amount, also known as Condition Needs, represents the budgeted contractor installed costs plus owner's soft costs for the repair, replacement or renewal for a component or system level deficiency. It excludes contributing costs for other components or systems that might also be associated with the corrective actions due to packaging the work. Facility Condition Index (FCI) FCI is an industry-standard measurement of facility condition calculated as the ratio of the costs to correct a facility's deficiencies to the facility's Current Replacement Value. It ranges from 0% (new) to 100% (very poor). Condition Index (CI) is calculated as the sum of a renewable system's Remaining Service Life (RSL) divided by the sum of a system's Replacement Value (both values exclude soft-cost to simplify calculation updates) expressed as a percentage ranging from 100% (new) to 0% (expired).

Function:

Gross Area (SF): 102,000

Year Built: 1909

Last Renovation:

Replacement Value: \$1,086,280

Repair Cost: \$727,448.76

Total FCI: 66.97 %

Total RSLI: 127.39 %

Description:

Attributes:

General Attributes:

Bldg ID:	S234001	Site ID:	S234001
----------	---------	----------	---------

Condition Summary

The Table below shows the CI and FCI for each major building system shown at the UNIFORMAT classification Level II. Note that Systems with lower FCIs require less investment than systems with higher FCIs.

UNIFORMAT Classification	RSLI %	FCI %	Current Repair Cost
G20 - Site Improvements	117.17 %	113.21 %	\$727,448.76
G40 - Site Electrical Utilities	142.18 %	0.00 %	\$0.00
Totals:	127.39 %	66.97 %	\$727,448.76

Condition Detail

This section of the report contains results of the Facility Condition Assessment. The building is separated into system components based on UNIFORMAT II classification. The columns in the System Listing table below represent the following:

1. System Code: A code that identifies the system.
2. System Description: A brief description of a system present in the building.
3. Unit Price \$: The unit price of the system.
4. UoM: The unit of measure for of the system.
5. Qty: The quantity for the system
6. Life: anticipated service life for thesystem based on Building Owners and Managers Association (BOMA) recommendations.
7. Year Installed: The date of system installation.
8. Calc Next Renewal Year: The date of system expiration based on the life, NR stands for non renewable.
9. Next Renewal Year: The suggested system expiration date by the assessor based on visual inspection.
10. CI: The Condition Index of the system.
11. FCI: The Facility Condition Index of the system.
12. RSL: Remaining Service Life.
13. eCR: eCOMET Condition Rating (not used).
14. Deficiency \$: The financial investment to repair/replace system.

System Listing

The System Listing table below lists each of the systems organized by their UNIFORMAT II classification. The assessment team was tasked with recording the most recent replacement year of each system, determining the remaining service life based on the theoretical life, and evaluating the condition to confirm the forecast next replacement year. The system listing is the basis for all data contained in the Building Assessment Report.

Additionally, a condition rating (eCR) based on the following guidelines is provided as observed at the time of the assessment.

- Excellent (E) - No noticeable distress or damage. The entire system is free from observable defect.
- Very Good (VG) - Overall no serviceability reduction for the entire system. No degradation of critical components and minor distress and defect noticeable for some but not non critical components within the system.
- Good (G) - Slight or no serviceability reduction for the entire system. There may be noticeable defects for some non critical components and slight noticeable degradation of the critical components.
- Fair (F) - Overall serviceability is degraded but adequate. There may be moderate deterioration for very few of the critical components and few of the non critical components may have severe degradation.
- Marginal (MA) - Overall serviceability and reliability loss. Most if not all of the non critical components suffer from severe degradation and a few of the critical component may have severe degradation.
- Moderate (MO) - Overall a significant serviceability loss. Most if not all the components have severe degradation with the reminder of the component showing visible distress.
- Very Poor (VP) - Overall the system is barely functional. All of the components are severely degraded.
- Non-Functional (NF) - Overall the system does not function with all the components having no serviceability and suffer from severe degradation.

System Code	System Description	Unit Price \$	UoM	Qty	Life	Year Installed	Calc Next Renewal Year	Next Renewal Year	RSLI%	FCI%	RSL	eCR	Deficiency \$	Replacement Value \$
G2010	Roadways	\$11.52	S.F.		30				0.00 %	0.00 %				\$0
G2020	Parking Lots	\$7.65	S.F.	10,800	30	1995	2025	2055	133.33 %	8.37 %	40		\$6,912.22	\$82,620
G2030	Pedestrian Paving	\$11.52	S.F.	31,000	40	1980	2020	2060	112.50 %	167.96 %	45		\$599,801.23	\$357,120
G2040	Site Development	\$4.36	S.F.	38,200	25	1995	2020	2045	120.00 %	72.49 %	30		\$120,735.31	\$166,552
G2050	Landscaping & Irrigation	\$3.78	S.F.	9,600	15	1995	2010	2032	113.33 %	0.00 %	17			\$36,288
G4020	Site Lighting	\$3.58	S.F.	102,000	30	1995	2025	2055	133.33 %	0.00 %	40			\$365,160
G4030	Site Communications & Security	\$0.77	S.F.	102,000	30	2010	2040	2070	183.33 %	0.00 %	55			\$78,540
Total									127.39 %	66.97 %			\$727,448.76	\$1,086,280

System Notes

The facility description in the site executive summary contains an overview of each system. The notes listed below provide additional information on select systems found within the facility.

No data found for this asset

Renewal Schedule

eCOMET forecasts future Capital Renewal funding needed to address expiring systems based on the Next Renewal year found in the Cost Models. A 3% annual inflation factor is applied to the costs for systems expiring in future years. The table below reflects recommended Capital Renewal funding needs over the next 10 years. Note: Cells with a zero value indicate systems for which renewal is not scheduled in that year.


Inflation Rate: 3%

System	Current Deficiencies	2016	2017	2018	2019	2020	2021	2022	2023	2024	2025	Total
Total:	\$727,449	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$727,449
G - Building Sitework	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G20 - Site Improvements	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G2010 - Roadways	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G2020 - Parking Lots	\$6,912	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$6,912
G2030 - Pedestrian Paving	\$599,801	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$599,801
G2040 - Site Development	\$120,735	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$120,735
G2050 - Landscaping & Irrigation	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G40 - Site Electrical Utilities	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G4020 - Site Lighting	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G4030 - Site Communications & Security	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0

** Indicates non-renewable system*

Forecasted Sustainment Requirement

The following chart shows the current building deficiencies and forecasting sustainment requirements over the next ten years.




10 Year FCI Forecast by Investment Scenario

The chart below illustrates the effect of various investment levels on the building FCI for the next 10 years. The levels of investment shown below include:

- Current FCI: a variable investment amount based on renewing expired systems to maintain the current FCI for the building
- 2% Investment: an annual investment of 2% of the replacement value of the building, escalated for inflation
- 4% Investment: an annual investment of 4% of the replacement value of the building, escalated for inflation


Facility Investment vs. FCI Forecast



Year	Investment Amount Current FCI - 66.97%	2% Investment		4% Investment	
		Amount	FCI	Amount	FCI
2016	\$0	\$22,377.00	64.97 %	\$44,755.00	62.97 %
2017	\$42,348	\$23,049.00	66.64 %	\$46,097.00	62.64 %
2018	\$0	\$23,740.00	64.64 %	\$47,480.00	58.64 %
2019	\$0	\$24,452.00	62.64 %	\$48,905.00	54.64 %
2020	\$667,787	\$25,186.00	113.67 %	\$50,372.00	103.67 %
2021	\$0	\$25,942.00	111.67 %	\$51,883.00	99.67 %
2022	\$0	\$26,720.00	109.67 %	\$53,439.00	95.67 %
2023	\$0	\$27,521.00	107.67 %	\$55,043.00	91.67 %
2024	\$0	\$28,347.00	105.67 %	\$56,694.00	87.67 %
2025	\$661,957	\$29,197.00	149.01 %	\$58,395.00	129.01 %
Total:	\$1,372,092	\$256,531.00		\$513,063.00	


Deficiency Summary by System

Current deficiencies included assemblies that have reached or exceeded their design life or components of the assemblies that are in need of repair. Assemblies that have reached their design life are identified as current deficiencies and assigned the distress 'Beyond Useful Life'. The following chart lists all current deficiencies associated with this facility.



Deficiency Summary by Priority

The following chart shows the total repair costs broken down by priority. Assessors assigned deficiencies within eCOMET to one of the following priority categories:



Budget Estimate Total: \$727,448.76


Deficiency By Priority Investment Table

The table below shows the current investment cost grouped by deficiency priority and building system.

System Code	System Description	1 - Response Time (< 2 yr)	2 - Response Time (2-3 yrs)	3 - Response Time (3-4 yrs)	4 - Response Time (4-5 yrs)	5 - Response Time (> 5 yrs)	Total
G2020	Parking Lots	\$0.00	\$0.00	\$0.00	\$6,912.22	\$0.00	\$6,912.22
G2030	Pedestrian Paving	\$0.00	\$0.00	\$599,801.23	\$0.00	\$0.00	\$599,801.23
G2040	Site Development	\$0.00	\$0.00	\$0.00	\$0.00	\$120,735.31	\$120,735.31
Total:		\$0.00	\$0.00	\$599,801.23	\$6,912.22	\$120,735.31	\$727,448.76

Deficiency Summary by Category

The following chart shows the total repair costs broken down by deficiency categories. Assessors assigned deficiencies to one of the following categories:



Deficiency Details by Priority

The deficiency detail notes listed below provide additional information on identified deficiencies found within the facility.

Priority 3 - Response Time (3-4 yrs):

System: G2030 - Pedestrian Paving



Location: Grounds/ site

Distress: Beyond Service Life

Category: 3 - Operations / Maint.

Priority: 3 - Response Time (3-4 yrs)

Correction: Remove and replace concrete sidewalk or concrete paving - 4" concrete thickness

Qty: 31,000.00

Unit of Measure: S.F.

Estimate: \$493,273.88

Assessor Name: Ben Nixon

Date Created: 09/18/2015

Notes: Repave playground area. Replace resilient rubber tiles around playground equipment

System: G2030 - Pedestrian Paving

This deficiency has no image.

Location: G234001;Grounds

Distress: Accessibility

Category: 2 - Code Compliance

Priority: 3 - Response Time (3-4 yrs)

Correction: Install an exterior ADA ramp - based on 5' wide by the linear foot - up to 84" rise - per LF of ramp - figure 1 LF of ramp per inch of rise

Qty: 45.00

Unit of Measure: L.F.

Estimate: \$106,527.35

Assessor Name: Ben Nixon

Date Created: 09/18/2015

Notes: Provide ADA compliant ramp at main entrance

Priority 4 - Response Time (4-5 yrs):

System: G2020 - Parking Lots



Location: Grounds/ site

Distress: Beyond Service Life

Category: 3 - Operations / Maint.

Priority: 4 - Response Time (4-5 yrs)

Correction: Stripe parking stalls, install parking bumpers, provide handicap symbol and handicap post mounted sign - insert proper quantities in estimate

Qty: 33.00

Unit of Measure: Ea.

Estimate: \$6,912.22

Assessor Name: Ben Nixon

Date Created: 09/18/2015

Notes: Provide parking striping with (2) accessible spaces and aisles

Priority 5 - Response Time (> 5 yrs):

System: G2040 - Site Development



Location: Grounds/ site

Distress: Beyond Service Life

Category: 3 - Operations / Maint.

Priority: 5 - Response Time (> 5 yrs)

Correction: Remove and replace metal picket fence - input number of gates

Qty: 650.00

Unit of Measure: L.F.

Estimate: \$120,735.31

Assessor Name: Tom Moe

Date Created: 09/18/2015

Notes: Replace picket fence

Equipment Inventory

The following table represents the inventory details of the inventory found in the building, which fall under the following subsystems:

Subsystem	Inventory	Qty	UoM	Location	Manufacturer	Model Number	Serial Number	Barcode	Life	Install Date	Next Renewal	Raw Cost	Inventory Cost
G4020 Site Lighting	Metal halide fixture, exterior, wall pack, 250 Watt, incl lamps	8.00	Ea.	Paved Play Area					30	1995	2025	\$589.95	\$5,191.56
G4020 Site Lighting	Metal halide fixture, exterior, wall pack, 250 Watt, incl lamps	1.00	Ea.	Courtyard					30	1995	2025	\$589.95	\$648.95
												Total:	\$5,840.51

Glossary

ABMA	American Boiler Manufacturers Association http://www.abma.com/
ACEEE	American Council for an Energy-Efficient Economy
ACGIH	American Council of Governmental and Industrial Hygienists
AEE	Association of Energy Engineers
AFD	Adjustable Frequency Drive
AFTC	After Tax Cash Flow
AGA	American Gas Association
AHU	Air Handling Unit
Amp	Ampere
ANSI	American National Standards Institute
ARI	Air Conditioning and Refrigeration Institute
ASD	Adjustable Speed Drive
ASHRAE	American Society of Heating Refrigerating and Air-Conditioning Engineers Inc.
ASME	American Society of Mechanical Engineers
Assessment	Visual survey of a facility to determine its condition. It involves looking at the age of systems reviewing information from local sources and visual evidence of potential problems to assign a condition rating. It does not include destructive testing of materials or testing of systems or equipment for functionality.
ATS	After Tax Savings
AW	Annual worth
BACNET	Building Automation Control Network
BAS	Building Automation System
BCR	Benefit Cost Ratio
BEP	Business Energy Professional (AEE)
BF	Ballast Factor
BHP	Boiler Horsepower (boilers)
BHP	Brake Horsepower (motors)
BLCC	Building Life Cycle Cost analysis program (FEMP)
BOCA	Building Officials and Code Administrators
BTCF	Before Tax Cash Flow

Site Assessment Report - S234001;McCall

BTS	Before Tax Savings
Btu	British thermal unit
Building Addition	An area space or component of a building added to a building after the original building's year built date.
CAA	Clean Air Act
CAAA-90	Clean Air Act Amendments of 1990
CABO	Council of American Building Officials
CAC	Conventional Air Conditioning
CADDET	Center for the Analysis and Dissemination of Demonstrated Energy Technologies
Calculated Next Renewal	The year a system or element would be expected to expire based solely on the date it was installed and the expected useful lifetime for that kind of system.
Capital Renewal	Capital renewal is condition work (excluding suitability and energy audit work) that includes the replacement of building systems or elements (as they become obsolete or beyond their useful life) not normally included in an annual operating budget. Calculated next renewal The year a system or element would be expected to expire based solely on the date it was installed and the expected useful lifetime for that kind of system. Next renewal The assessor adjusted expected useful life of a system or element based on on-site inspection.
CDD	Cooling Degree Days
CDGP	Certified Distributed Generation Professional
CEC	California Energy Commission
CEM	Certified Energy Manager
CEP	Certified Energy Procurement Professional
CFC	Chlorofluorocarbon
CFD	Cash Flow Diagram
CFL	Compact Fluorescent Light
CFM cfm	Cubic Feet per Minute
CHP	Combined Heat and Power (a.k.a. cogeneration)
CHW	Chilled Water
Condition	Condition refers to the state of physical fitness or readiness of a facility system or system element for its intended use.
COP	Coefficient of Performance
Cp	Heat Capacity of Material
CPUC	California Public Utility Commission
CRI	Color Rendering Index
CRT	Cathode Ray Tube VDT HMI

Site Assessment Report - S234001;McCall

CTC	Competitive Transition Charge
Cu	Coefficient of Utilization
Current Replacement Value (CRV)	CRV represents the hypothetical total cost of rebuilding or replacing an existing facility in current dollars to its optimal condition (excluding auxiliary facilities) under current codes and construction standards.
Cv	Value Coefficient
CWS	Chilled Water System
D d	Distance (usually feet)
DB	Dry Bulb
DCV	Demand Control Ventilation
DD	Degree Day
DDB	Double Declining Balance
DDC	Direct Digital Controls
Deferred maintenance	Deferred maintenance is condition work (excluding suitability and energy audit needs) deferred on a planned or unplanned basis to a future budget cycle or postponed until funds are available.
Deficiency	A deficiency is a repair item that is damaged missing inadequate or insufficient for an intended purpose.
Delta	Difference
Delta P	Pressure Difference
Delta T	Temperature Difference
DG	Distributed Generation
DOE	Department of Energy
DP	Dew Point
DR	Demand Response
DX	Direct Expansion Air Conditioner
EA	Energy Audit
EBITDA	Earnings before Interest Taxes Depreciation and Amortization
ECI	Energy Cost Index
ECM	Energy Conservation Measure
ECO	Energy Conservation Opportunity
ECPA	Energy Conservation and Production Act
ECR	Energy Conservation Recommendation
ECS	Energy Control System

Site Assessment Report - S234001;McCall

EER	Energy Efficiency Ratio
EERE	Energy Efficiency and Renewable Energy division of US DOE
EIA	Energy Information Agency
EIS	Energy Information System
EMCS	Energy Management Computer System
EMO	Energy Management Opportunity
EMP	Energy Management Project
EMR	Energy Management Recommendation
EMS	Energy Management System
Energy Utilization Index (EUI)	EUI is the measure of total energy consumed in the cooling or heating of a building in a period expressed as British thermal unit (BTU) per (cooled or heated) gross square foot.
EO	Executive Order
EPA	Environmental Protection Agency
EPACT	Energy Policy Act of 1992
EPCA	Energy Production and Conservation Act of 1975
EPRI	Electric Power Research Institute
EREN	Efficiency and Renewable Energy (Division of USDOE)
ERV	Energy Recovery Ventilator
ESCO	Energy Service Company
ESPC	Energy Savings Performance Contract
EUI	Energy Use Index
EWG	Exempt Wholesale Generators
Extended Facility Condition Index (EFCI)	EFCI is calculated as the condition needs for the current year plus facility system renewal needs going out to a set time in the future divided by Current Replacement Value.
f	Frequency
F	Fahrenheit
Facility	A facility refers to site(s) building(s) or building addition(s) or combinations thereof that provide a particular service.
Facility Condition Assessment (FCA)	FCA is a process for evaluating the condition of buildings and facilities for programming and budgetary purposes through an on site inspection and evaluation process.
Facility Condition Index (FCI)	FCI is an industry-standard measurement of a facility's condition that is the ratio of the cost to correct a facility's deficiencies to the Current Replacement Value of the facilities. The higher the FCI the poorer the condition of a facility. After an FCI is established for all buildings within a portfolio a building's condition can be ranked relative to other buildings. The FCI may also represent the condition of a portfolio based on the cumulative FCIs of the portfolio's facilities.

Site Assessment Report - S234001;McCall

FC	Footcandle
FCA	Fuel Cost Adjustment
FEMIA	Federal Energy Management Improvement Act of 1988
FEMP	Federal Energy Management Program
FERC	Federal Energy Regulatory Commission
FESR	Fuel Energy Savings Ratio
FLA	Full Load Amps
FLF	Facility Load Factor (usually monthly)
FLRPM	Full Load Revolutions per Minute
FMS	Facility Management System
FPM fpm	Feet per Minute (velocity)
FSEC	Florida Solar Energy Center
Ft	Foot
GPM gpm	Gallons per Minute
GRI	Gas Research Institute
Gross Square Feet (GSF)	The size of the enclosed floor space of a building in square feet measured to the outside face of the enclosing wall.
GUI	Graphical User Interface
H h	Enthalpy Btu/lb
HCFC	Hydrochlorofluorocarbons
HDD	Heating Degree days
HFC	Hydrofluorocarbons
HHV	Higher Heating Value
HID	High Intensity Discharge (lamp)
HMI	Human Machine Interface
HMMI	Human Man Machine Interface
HO	High Output (lamp)
HP Hp hp	Horsepower
HPS	High Pressure Sodium (lamp)
HR	Humidity Ratio
Hr hr	Hour

Site Assessment Report - S234001;McCall

HRU	Heat Recovery Unit
HVAC	Heating Ventilation and Air-Conditioning
Hz	Hertz
I	Intensity (lumen output of lamp)
I i	Interest rate or Discount rate
IAQ	Indoor Air Quality
ICA	International Cogeneration Alliance
ICBO	International Conference of Buildings Officials
ICC	International Code Council
ICP	Institutional Conservation Program
IECC	International Energy Conservation Code
IEEE	Institute of Electrical and Electronic Engineers
IESNA	Illuminating Engineering Society of North America
Install year	The year a building or system was built or the most recent major renovation date (where a minimum of 70 of the system's Current Replacement Value (CRV) was replaced).
IRP	Integrated Resource Planning
IRR	Internal Rate of Return
ISO	Independent System Operator
ITA	Independent Tariff Administrator
k	Kilo multiple of thousands in SI system
K	Kelvins (color temperature of lamp)
K k	Thermal Conductivity of Material
KVA	Kilovolt Ampere
KVAR	Kilovolt Ampere Reactive
kW	kiloWatt
kWh	kiloWatt hour
L	Length (usually feet)
LCC	Life Cycle Costing
LDC	Local Distribution Company
LEED	Leadership in Energy and Environmental Design
LEED EB	LEED for Existing Buildings

Site Assessment Report - S234001;McCall

LEED NC	LEED for new construction
LF	Load Factor
LHV	Lower Heating Value
Life cycle	The period of time that a building or site system or element can be expected to adequately serve its intended function.
LPS	Low Pressure Sodium (lamp)
Lu	Lumen Output of a Lamp or Fixture
M	Mega multiple of millions in SI system
M&V	Measurement and Verification
MACRS	Modified Accelerated Cost Recovery System
MARR	Minimum Attractive Rate of Return
Mbtu	Thousand Btu
MCF	Thousand Cubic Feet (usually of gas)
MEC	Model Energy Code
Mm	Multiple of Thousands in I/P System
MMBtu	Million Btu
MMCS	Maintenance Management Computer System
MMI	Man Machine Interface
MMS	Maintenance Management System
MSE 2000	Management System for Energy 2000 (ANSI Georgia Tech Univ)
MW	MegaWatt
MWH MWh	MegaWatt hour
NAAQS	National Ambient Air Quality Standards
NAESCO	National Association of Energy Service Companies
NAIMA	North American Insulation Manufacturers Association
NEA	National Energy Act of 1978
NECPA	National Energy Conservation Policy Act
NEMA	National Electrical Manufacturer's Association
NERC	North American Electric Reliability Council
Next Renewal	The Next Renewal date is an override of the 'Calculated Next Renewal' date and is based upon the assessor's visual inspection.

Site Assessment Report - S234001;McCall

NFPA	National Fire Protection Association
NGPA	National Gas Policy Act of 1978
NLRPM	No Load Revolutions per Minute (speed)
Nn	Equipment or Project lifetime in economic analysis
NOPR	Notice of Proposed Rule Making from FERC
NOx	Nitrogen Oxide Compounds
NPV	Net present value in economic analysis
NREL	National Renewable Energy Laboratory
NUG	Non-Utility Generator
O&M	Operation and Maintenance
OA	Outside Air
ODP	Ozone Depletion Potential
OPAC	Off-Peak Air Conditioning
P	Present value in economic analysis
PBR	Performance Based Rates
PEA	Preliminary Energy Audit
PF	Power Factor
PID	Proportional plus integral plus derivative (control system)
PM	Portfolio Manager in Energy Star rating system
PM	Preventive Maintenance
PoolCo	Power Pool Company or Organization
POU	Point of Use
PQ	Power Quality
PSC	Public Service Commission
PSIA psia	Pounds per square inch absolute (pressure)
PSIG psig	Pounds per square inch gauge (pressure)
PUC	Public Utility Commission
PUHCA	Public Utilities Holding Company Act of 1935
PURPA	Public Utilities Regulatory Policies of 1978
PV	Photovoltaic system

PV	Present Value
PW	Present Worth
PX	Power Exchange
q	Rate of heat flow in Btu per hour
Q	Heat load due to conduction using degree days
QF	Qualifying Facility
R	Electrical resistance
R	Thermal Resistance
RC	Remote controller
RCR	Room Cavity Ratio
RCRA	Resource Conservation and Recovery Act
Remaining Service Life (RSL)	RSL is the number of years service remaining for a system or equipment item. It is automatically calculated based on the difference between the current year and the 'Calculated Next Renewal' date or the 'Next Renewal' date whichever one is the later date.
Remaining Service Life Index (RSLI)	RSLI is defined as a percentage ratio of the remaining service life of a system. It usually ranges from 0 to 100
REMR	Repair Evaluation Maintenance Rehabilitation (REMR) is a scale used to objectively rank systems based on their condition
Renewal Schedule	A timeline that provides the items that need repair the year in which the repair is needed and the estimated price of the renewal.
RH	Relative Humidity
RLA	Running Load Amps
RMS	Root Mean Square
RO	Reverse Osmosis
ROI	Return on Investment
RPM	Revolutions Per Minute
RTG	Regional Transmission Group
RTO	Regional Transmission Organization
RTP	Real Time Pricing
SBCCI	Southern Building Code Congress International
SC	Scheduling Coordinator
SC	Shading Coefficient
SCADA	Supervisory Control and Data Acquisition Systems

Site Assessment Report - S234001;McCall

SEER	Seasonal Energy Efficiency Ratio
SHR	Sensible Heat Ratio
Site	The grounds and utilities roadways landscaping fencing and other typical land improvements needed to support the facility.
Soft Cost	An expense item that is not considered direct construction cost. Soft cost includes architectural engineering financing legal fees and other pre-and-post construction expenses.
SOx	Sulfur Oxide Compounds
SP	Static Pressure
SP SPB	Simple Payback
SPP	Simple Payback Period
SPP	Small Power Producers
STR	Stack Temperature Rise
SV	Specific Volume
System	System refers to building and related site work elements as described by ASTM Uniformat II Classification for Building Elements (E1557-97) a format for classifying major facility elements common to most buildings. Elements usually perform a given function regardless of the design specification construction method or materials used. See also Uniformat II.
T	Temperature
T	Tubular (lamps)
TAA	Technical Assistance Audit
TCP/IP	Transmission Control Protocol/Internet Protocol
TES	Thermal Energy Storage
THD	Total Harmonic Distortion
TOD	Time of Day
TOU	Time of Use
TQM	Total Quality Management
TransCo	Transmission Company
U	Thermal Conductance
UDC	Utility Distribution Company
UL	Underwriters Laboratories
UNIFORMAT II	The ASTM UNIFORMAT II Classification for Building Elements (E1557-97) a format for classifying major facility components common to most buildings.
USGBC	US Green Building Council
v	Specific Volume

Site Assessment Report - S234001;McCall

V	Volts Voltage
V	Volume
VAV	Variable Air Volume
VDT	Video Display Terminal
VFD	Variable Frequency Drive
VHO	Very High Output
VSD	Variable Speed Drive
W	Watts
W	Width
WB	Wet bulb
WH Wh	Watt Hours
Year built	The year that a building or addition was originally built based on substantial completion or occupancy.
Z	Electrical Impedance