

Facility Condition Assessment Summary Report

This report provides a summary of the Facility Condition Index (FCI) value of a school facility and select major building systems. The FCI calculation represents the cost of needed repairs divided by the replacement value. The FCI is a numerical value of condition and helps to identify the need for renewal or replacement of specific parts of the facility. The FCI is particularly useful when comparing similar facilities within the same portfolio.

McClure School

Governance	DISTRICT	Report Type	Elementary
Address	600 W. Hunting Park Ave. Philadelphia, Pa 19140	Enrollment	639
Phone/Fax	215-456-3001 / 215-456-5587	Grade Range	'00-05'
Website	Www.Philasd.Org/Schools/Mcclure	Admissions Category	Neighborhood
		Turnaround Model	N/A

Building/System FCI Tiers

Facility Condition Index (FCI) = $\frac{\text{Cost of Assessed Deficiencies}}{\text{Replacement Value}}$				
< 15%	15 to 25%	25 to 45%	45 to 60%	> 60%
Buildings				
Minimal Current Capital Funding Required	Refurbish Systems in building	Replace Systems in building.	Building should be considered for major renovation.	Building should be considered for closing/replacement.
Systems				
Perform routine maintenance on system	System requires minor repairs	System should be studied to determine repair vs. replacement.	System is nearing end of its life expectancy and should be considered for replacement	System should be replaced as part of the Capital Program

Building and Grounds

	FCI	Repair Costs	Replacement Cost
Overall	51.82%	\$17,402,835	\$33,581,965
Building	50.75 %	\$16,705,231	\$32,914,606
Grounds	104.53 %	\$697,604	\$667,359

Major Building Systems

Building System	System FCI	Repair Costs	Replacement Cost
Roof (Shows physical condition of roof)	84.82 %	\$606,488	\$715,004
Exterior Walls (Shows condition of the structural condition of the exterior facade)	00.00 %	\$0	\$1,795,150
Windows (Shows functionality of exterior windows)	215.95 %	\$1,692,439	\$783,725
Exterior Doors (Shows condition of exterior doors)	170.72 %	\$163,932	\$96,025
Interior Doors (Classroom doors)	172.22 %	\$372,347	\$216,200
Interior Walls (Paint and Finishes)	80.59 %	\$778,996	\$966,575
Plumbing Fixtures	00.00 %	\$0	\$1,815,850
Boilers	00.00 %	\$0	\$1,073,525
Chillers/Cooling Towers	65.31 %	\$919,357	\$1,407,600
Radiators/Unit Ventilators/HVAC	152.01 %	\$3,757,521	\$2,471,925
Heating/Cooling Controls	158.90 %	\$1,233,498	\$776,250
Electrical Service and Distribution	146.96 %	\$819,675	\$557,750
Lighting	58.36 %	\$1,163,792	\$1,994,100
Communications and Security (Cameras, Pa System and Fire Alarm)	99.68 %	\$744,554	\$746,925

Please note that some FCIs may be over 100% because there are times when replacing a building system requires that other building systems be upgraded to complete the installation. A FCI of 0.0% represents that there are no current deficiencies with the associated system.

School District of Philadelphia
S738001; McClure
Final
Site Assessment Report

January 30, 2017



Table of Contents

Site Executive Summary	4
Site Condition Summary	12
<u>B738001:McClure</u>	14
Executive Summary	14
Condition Summary	15
Condition Detail	16
System Listing	17
System Notes	19
Renewal Schedule	20
Forecasted Sustainment Requirement	23
Condition Index Forecast by Investment Scenario	24
Deficiency Summary By System	25
Deficiency Summary By Priority	26
Deficiency By Priority Investment	27
Deficiency Summary By Category	28
Deficiency Details By Priority	29
Equipment Inventory Detail	51
<u>G738001:Grounds</u>	52
Executive Summary	52
Condition Summary	53
Condition Detail	54
System Listing	55
System Notes	56
Renewal Schedule	57
Forecasted Sustainment Requirement	58
Condition Index Forecast by Investment Scenario	59
Deficiency Summary By System	60
Deficiency Summary By Priority	61
Deficiency By Priority Investment	62

Site Assessment Report

Deficiency Summary By Category	63
Deficiency Details By Priority	64
Equipment Inventory Detail	68
Glossary	69

Site Executive Summary

The organization of this report, as displayed in the Table of Contents, follows the structure of the associated eCOMET database. The overall node for each school campus begins with the letter "S", which indicates the "Site" label. Each Site is comprised of separate "Building" and "Grounds" nodes; their asset names begin with the letters "B" and "G" respectively. Information rolls up to the Site node from the Building and Grounds nodes. This Site report combines facility information with subsections for the Buildings And Grounds nodes.

The basis for the evaluation of condition is the functional systems and elements of a building and grounds organized according to the UNIFORMAT II Elemental Classification. The grouping of these systems and elements and applying a current replacement value to them develops a representative building cost model. Cost Models are typically developed for similar building types and functions. Evaluation of systems and their elements takes into account their current replacement values, life cycles, installation dates and next renewal dates. Systems and their elements that are within their useful lives are further evaluated to identify current deficient conditions that may have a significant impact on a system's or element's remaining service life, and to determine if they are beyond their predicted expected life. The system's or element's current replacement value is based on RS Means Commercial Cost Data.

Following are the cost model's system details for this facility. The Replacement Value is the amount needed to replace the property of the same present value. The Current Repair Amount, also known as Condition Needs, represents the budgeted contractor installed costs plus owner's soft costs for the repair, replacement or renewal for a component or system level deficiency. It excludes contributing costs for other components or systems that might also be associated with the corrective actions due to packaging the work. Facility Condition Index (FCI) is an industry-standard measurement calculated as the ratio of the repair costs to correct a facility's deficiencies to the facility's Current Replacement Value. Condition Index (CI) for a system is calculated as the sum of the deficiencies divided by the sum of a system's Replacement Value (both values include soft-cost) expressed as a percentage ranging from 0% 100%.

Gross Area (SF):	57,500
Year Built:	1910
Last Renovation:	
Replacement Value:	\$33,581,965
Repair Cost:	\$17,402,834.65
Total FCI:	51.82 %
Total RSLI:	74.43 %



Description:

Facility Assessment
September 2015

School District of Philadelphia
McClure Elementary School
600 W. Hunting Park Avenue
Philadelphia, PA 19140

57,500 SF / 576 Students / LN 05

The McClure Elementary school building is located at 600 W. Hunting Park Ave in Philadelphia, PA. The 3 story with basement, 57,500 square foot building was originally constructed in 1910 with a second element added in 1915. The original building has C-shape footprint. One of the wings on west side was extended approximately in the 1970's with a 1 story prefabricated (portable building) addition. The building has a basement partially above ground and two access penthouses on the roof.

Mr. Scott Ovington, Facility Area Coordinator provided input to the Parsons assessment team on current problems and planned renovation projects. Mr. Les Crawley, building engineer, accompanied us on our tour of the school and provided us with detailed information on the building systems and recent maintenance history. Ms. Sharon Marino, school principal, provided additional information about the building's condition.

ARCHITECTURAL/STRUCTURAL/ EXTERIOR CLOSURE:

The building typically rests on concrete foundations and bearing walls that are not showing signs of settlement. There is no water seepage through basement walls. The mold build-up is not evident in bunkers and other parts of mechanical spaces. The basement slab does not show signs of heaving or cracking, except in room 006 where a portion of the slab appears to be settling and causing partition cracking and door headers out of level.

The main structure consists typically of cast-in-place concrete columns, beams and one-way concrete slabs. Above ground floor slabs are generally in good condition, however floor slabs in fire tower show minor structural deterioration including spalled concrete and exposed, and rusting reinforcement. One of the concrete columns in boiler room is damaged with exposed reinforcing.

The roof structure is typically similar to floor construction.

Prefabricated addition is constructed of precast single-T walls and roof resting on cast in place concrete pier foundations.

The building envelope is typically masonry with face brick with decorative stone friezes below first floor windows on elevations facing streets. In general, masonry is in fair condition. A replacement of window lintels was under way during the site visit.

The original windows were replaced in 1990's with extruded aluminum double hung windows, single, acrylic glazed. Basement windows are fitted with steel bar security screens, damaged and rusting. All windows are generally in good condition; however, they are not energy efficient.

Roofing is typically built-up, over 25 years old. All roofing and flashing is typically in poor condition with severe deterioration of the built-up system including water ponding and soft spots; building engineer reported that several leaks have been repaired.

Exterior doors are typically hollow metal in fair to poor condition; they are beyond their service life. Generally, the building is not accessible per ADA requirements due to first floor-grade separation and elevation difference between floors, with no ramps or lifts.

INTERIORS:

Partition wall types include plastered ceramic hollow blocks and painted CMU. Corridors, basement spaces and fire towers have glazed brick wainscot. Some classrooms are separated with unused sliding partitions. The interior wall finishes are generally painted plaster or CMU and painted brick with some water damage observed. Walls in toilets are covered with ceramic tile installed in late 2000's. Generally, paint is in fair condition with some deterioration in stairways and auditorium. Most ceilings are exposed, plastered and painted. 2x4 suspended acoustical ceilings are installed in two classrooms and are beyond their service life.

Flooring in classrooms is generally hardwood in fair to poor condition; and patterned concrete in most corridors in the original building. Some classrooms and gym have VCT installed in mid 2000's. Floor in toilets is typically ceramic tile installed in late 2000's.

Interior doors are generally rail and stile wood doors with transoms, some glazed, in wood frames and solid core wood in original frames. Doors are typically beyond their service life. Most doors are fitted with door knobs that are not ADA compliant.

Fittings include original chalk boards, generally in poor condition. Toilet partitions and accessories in are in good condition, installed in late 2000's with toilets in basement fitted with accessible partitions; handrails, generally in good condition. Interior identifying signage is typically directly painted on wall or door surfaces generally in poor condition.

Stair construction is generally steel stringers with concrete filled steel pan treads in main stairways and concrete in fire tower.

Furnishings include fixed casework in classrooms, corridors and library, generally in good condition; window shades/blinds, generally in good condition.

CONVEYING SYSTEMS:

The building has no elevators.

PLUMBING:

Plumbing Fixtures - Many of the original plumbing fixtures appear to have been replaced within the last fifteen years. Fixtures in the restrooms on each floor consist of wall mounted push button flush water closets, wall hung urinals, and lavatories with wheel handle faucets. These fixtures should provide reliable service for the next 10-15 years.

Drinking fountains in the corridors consist of handicap accessible wall hung fixtures with integral refrigerated coolers. The fixtures appear to be in good condition and the Building Engineer reported no issues; he did not know when the fixtures were replaced.

A mop basin is available in a janitor closet in the corridor on each floor for use by the janitorial staff.

The Kitchen does not have any plumbing fixtures as only premade meals are served.

Domestic Water Distribution - A 3" city water service enters the building from the paved play area on the South side of the building. The 3" meter and valves are located in a room in the basement adjacent to the Gymnasium. Two reduced pressure backflow preventers are installed in parallel. Duplex base mounted 5HP Armstrong domestic pressure booster pumps are installed on the domestic water line to ensure adequate pressure throughout the system. The original domestic hot and cold water distribution piping was replaced with copper piping and sweat fittings. The maintenance staff reports no significant problems with scale build up in the domestic piping and the supply is adequate to the fixtures, but the piping has been in use for an unknown amount of time and should be inspected and repaired as necessary by a qualified contractor.

One Bradford White gas fired, 48 gallon, vertical hot water heater with circulating pump supplies hot water for domestic use. The unit is located in the boiler room on the basement level and has an installation date of 2000. The hot water heater is equipped with a T&P relief valve. The domestic hot water heater is beyond its service life and should be replaced in the next 1-2 years.

Sanitary Waste - The original sanitary sewer piping is still in use and is a mixture of threaded galvanized piping and cast iron piping with hub and spigot fittings. Some repairs have been made with steel piping and no-hub fittings.

The building does not have a sewage ejector pit.

The maintenance staff reported mostly minor problems with the sanitary waste piping systems. The original sewer piping has been in service for over 100 years and will require more frequent attention from the maintenance staff as time passes. The District should hire a qualified contractor to examine the sanitary waste piping using video cameras to locate and replace any damaged piping and to further quantify the extent of potential failures.

Rain Water Drainage - Rain water drains from the roof are routed through mechanical chases in the building and appear to be original. Sections of the cast iron piping with hub and spigot fittings have been replaced with steel piping and no-hub fittings. The Building Engineer reported that rain leaders leak in several places within the building. The District should hire a qualified contractor to examine the rain water drainage piping using video cameras to locate and replace any damaged piping and to further quantify the extent of potential failures.

MECHANICAL:

Energy Supply - An 8" city gas service enters the building in the basement boiler room from the parking lot on the South side of the building. The gas meter is 6" and a pressure booster pump is installed. Gas is the primary fuel for the boilers.

The reserve oil supply is stored in a 12,000 gallon underground storage tank (UST) located in the paved play area on the South side of the school. Duplex pumps located in the basement boiler room are supposed to circulate oil through the system, but currently the oil tank is empty and gas is the only fuel used for the boilers. It is estimated that the storage tank is beyond its useful life and should be inspected on a regular basis.

Heat Generating Systems - Low pressure steam is generated at a maximum of 15 lbs./sq. in. by three (3) 68HP HB Smith model 350 cast iron sectional boilers, installed in 1992. Two boilers can handle the load in normal winter weather conditions; three units are required on very cold days. Each boiler is equipped with a Power Flame burner designed to operate on natural gas or fuel oil. Combustion air makeup is supplied by louvers equipped with motorized dampers. Induced draft fans with positive draft control are installed on the rear of each boiler. Burner controls provide full modulation with electronic ignition, digital flame sensing and pressure atomization on oil. Burner oil pumps are loose and not driven by the fan motor. The gas train serving the building does appear to have code required venting of the regulators and dual solenoid valves with venting of the chamber between. Condensate makeup water is supplemented with chemically treated city water. Cast iron sectional boilers have an anticipated service life of 35 years or more; these units have been in service approximately 23 years. The boilers appear to have been maintained well. The District should provide reliable service for the next 10 to 15 years.

The condensate receiver and boiler feed tank assembly and four (4) pumps are installed in the boiler room. The feed tank appears to be in good condition but the feed pumps are showing signs of rust damage, two of the pumps should be replaced. The Building Engineer reported that there is no steam in the boiler room when he runs the boilers.

Distribution Systems - Steam piping is black steel with welded fittings. The condensate piping is black steel with threaded fittings. Steam and condensate piping mains from the basement level run up through the building to the radiators on all three floors. The distribution piping has been in use well beyond its service life and will require more frequent attention from the maintenance staff to address pipe/valve failures as time passes. The District should hire a qualified contractor to examine the steam and condensate piping and perform additional testing to locate and replace any damaged piping and to further quantify the extent of potential failures. The District should budget for replacing this piping over the next 10 years.

Two pipe cast iron radiators provide heating for the South side of the building, Element 2. The house fan and cast iron radiators provide heating and ventilation for the North side of the building, Element 1. The radiators and house fan are original to the building and well beyond their service life. Ventilation for the building is provided by opening windows and the house fan when it is in use, which does not meet current codes for outdoor air ventilation. A new heating

system should be installed to meet ventilation requirements and achieve more efficient operation. The new units should be designed for quiet operation and equipped with hot water coils, chilled water coils, and integral heat exchangers, where applicable, to introduce outdoor air to the building.

Mechanical ventilation is provided to the North side of the building by one large paddle wheel house fan located in the basement and original to the building. This fan also provides heating to classrooms and runs off the building steam loop. The fan has been refurbished in the recent past, but the Building Engineer did not know when. The fan is run by a 30HP motor. Roof mounted gravity ventilators used to provide passive ventilation, but the vent stacks have been removed and the roof openings covered. The house fans only run during the heating season, thus the building is without mechanical ventilation much of the year. Unit ventilators should be installed to provide ventilation year round as required by code.

Ventilation for the restrooms is provided by two roof mounted exhaust fans, one (1) on the East side of the building and one (1) on the West side. The fans are operational and look to be within their service life, but the Building Engineer did not know the year they were installed.

Terminal & Package Units - Several of the classrooms in the school building have window conditioning units that have an anticipated service life of only 10 years. Installing a 150 ton air-cooled chiller with pumps located in a mechanical room and chilled water distribution piping would supply more reliable air conditioning for the building with a much longer service life.

A Mitsubishi split system air conditioning system provides cooling to the LAN room located on the first floor off of the nurse's office. The installation date of this unit is unknown; the anticipated service life of a split system air conditioner is 15 years. The district should budget to replace this unit within the next 7-10 years.

Controls & Instrumentation - The original pneumatic systems provide no control functions. Pneumatic room thermostats are intended to control the steam radiator control valves. In reality the radiator control valves are wide open and heating control is achieved via the boilers. Pneumatic control air is supplied from a Champion compressor and Champion air dryer. The pneumatic systems are beyond their service life and require too much attention from the maintenance staff. The original control valves and pneumatic actuators are beyond their service life and should be rebuilt or replaced. These controls should be converted to DDC.

A new building automation system (BAS) with modern DDC modules and communications network should be installed to serve the HVAC systems in this building to improve reliability and energy efficiency. An interface should be provided with the preferred system in use throughout the District.

Sprinklers - The school building is NOT covered by an automatic sprinkler system. Installing a sprinkler system with quick response type heads should reduce insurance costs by providing protection for the property investment. A fire pump may be required depending on the available city water pressure. The building does have standpipe in the stairwells.

ELECTRICAL:

Site electrical service - The primary power is at 13.2KV from the street power pole which goes underground and feeds a transformer (500 KVA, 13.2KV – 120V/208V, 3 Phase). The electrical service is old and has reached the end of its useful service. The main disconnect is rated at 1200A, 120V/208V, 3 phase, and is located in main electrical room. The PECO meter (PECO MU-16455) is also located inside the electrical room. The service entrance and the main building electrical distribution systems are old, in very poor condition. They provide power for lighting and receptacles of the building, and not the HVAC System.

Receptacles - There is not enough receptacles in classrooms, computer rooms, libraries, and other areas. There should

Site Assessment Report - S738001;McClure

be a minimum of two receptacles on each wall of the classrooms, and other areas.

Lighting - Interior building is illuminated by various types of fixtures. They include fluorescent lighting (with T-12 & T-8 lamp) in majority of the areas, including; classrooms, corridor, offices, and the Kitchen. Surface or pendant mounted industrial fluorescent fixtures are used in mechanical and electrical rooms. The Gymnasium also has old HID fixtures. The majority of interior lighting fixtures is in a poor condition and has reached the end of their useful service.

Fire alarm - The present Fire Alarm system is old and is not automatic/addressable, and is not in compliance with safety codes. There are manual pulls stations throughout the building. However, there are insufficient number of horns/strobes installed in the classrooms, corridors, offices and other areas in the school.

Telephone/LAN - The school telephone and data systems are new and working adequately. The main distribution frame (MDF) along with a telephone PBX system are providing the necessary communication function of the building. School is also equipped with Wi-Fi system.

Public Address - Separate PA system does not exist. School uses the telephone systems for public announcement. This system is working adequately. The present Intercom System is functioning fine. Each class room is provided with intercom telephone service. The system permits paging and intercom communication between main office to classrooms, and vice versa (classrooms to main office), and communication between classrooms.

Clock and Program system – Clocks and program systems are old and not working properly. Classrooms are provided with 12-inch wall mounted round clocks that are not controlled properly by central master control panel.

Television System - Television system is not provided in the school. Most classes are equipped with smart boards having the ability to connect to computers and internet.

Security Systems, access control, and video surveillance - The school does not have a video surveillance system. There are no cameras at exit doors, corridors, exterior, and other critical areas. The school principal expressed desire to have a working video surveillance system. The new cameras should be controlled by a Closed Circuit Television system (CCTV).

Emergency Power System - School has an old small emergency generator to feed, emergency lighting and other emergency loads. The Generator has reached the end of its useful service.

Emergency lighting system, including exit lighting - there are insufficient emergency lighting fixtures in corridors and other exit ways. Exit signs and emergency fixtures are old and have reached the end of their useful service.

Lightning Protection System - There is adequate lightning protection system in the school. The roof has lightning rods, and they are connected to the ground properly via stranded aluminum cables.

Grounding - The present grounding system is adequate. All equipment is correctly bonded to the ground.

Site Lighting - The school grounds and building perimeters are not adequately lighted for safety of the people and security of property.

Site Paging - The present Site paging System is not adequate. There is insufficient number of speakers on building's exterior walls.

GROUNDS (SITE):

There is no parking at the site.

Site Assessment Report - S738001;McClure

Playground adjacent to the building is in poor condition, paving is cracked and deteriorated; playground equipment is new, installed in 2014. Perimeter picket fences are generally in good condition, however, some sections are damaged; brick gate pylons are deteriorated. There is no landscaping.

ACCESSIBILITY:

The building does not have accessible entrance, and accessible routes. The toilets are equipped with accessible fixtures, partitions and accessories, such as grab bars and accessible partitions in basement only. None of the doors in the building have ADA required door handles.

RECOMMENDATIONS

- Repair deteriorated slab section in basement (room 006)
- Repair (epoxy patch) damaged concrete column in boiler room
- Repair/patch concrete slabs in fire tower
- Install all new roofing system including insulation within next 4 to 5 years; tear-down existing roofing; install flashing, counter flashing and reglets
- Replace all windows with double insulated units
- Replace all exterior doors
- Replace sliding partitions with drywall partitions
- Repaint all walls
- Repair (15%) & refinish hardwood flooring
- Replace damaged VCT (20%)
- Repair and repaint all ceilings
- Replace ACT ceilings
- Install 4000 lb traction elevator serving all floors and basement
- Provide wheelchair lift at the main entrance
- Provide ADA compliant ramp at one entrance (location TBD)
- Replace interior doors in the building
- Provide ADA compliant hardware on interior doors
- Replace signage throughout
- Provide ADA accessible partitions in toilets (all floors except basement)
- Replace playground paving
- Replace damaged sections of picket fence
- Repair brick gate pylons
- Hire a qualified contractor to perform a detailed inspection of the domestic water piping, in use for an unknown amount of time, and replace any damaged piping.
- Replace the existing vertical gas fired, 48 gallon, domestic hot water heater which is beyond its service life with new gas fired hot water heater.
- Replace the skid mounted duplex 5HP domestic water booster pumps and isolation valves on the incoming domestic water line which show signs of rust damage.
- Hire a qualified contractor to perform a detailed examination of the sanitary waste piping using visual inspection and video cameras to locate and replace any damaged piping and to further quantify the extent of potential failures.
- Hire a qualified contractor to perform a detailed examination of the rain water drainage piping using visual inspection and video cameras to locate and replace any damaged piping and to further quantify the extent of potential failures.
- Replace two (2) of the boiler feed water pumps which are damaged from rust.
- Hire a qualified contractor to examine the steam piping, in service for over 100 years, and perform additional

Site Assessment Report - S738001;McClure

- testing to locate and replace any damaged piping and to further quantify the extent of potential failures.
- Remove the existing cast iron and fin tube steam radiators and install units with hot and chilled water coils and integral heat exchangers to introduce outdoor air to the building.
- Remove the window air conditioning units and install a 150 ton air-cooled chiller with chilled water distribution piping and pumps located in a mechanical room to supply more reliable air conditioning for the building with a much longer service life.
- Provide ventilation for the Cafeteria by installing a constant volume air handling unit with distribution ductwork and registers.
- Provide ventilation for the Gymnasium by installing a fan coil air handling unit hung from the structure with outdoor air ducted to the unit from louvers in the window openings.
- Provide ventilation for the Administration offices by installing a fan coil air handling unit hung from the structure with outdoor air ducted to the unit from louvers in window openings.
- Replace eleven (11) roof mounted gravity ventilators which have been removed from the roof.
- Replace the pneumatic controls for the HVAC systems with modern DDC modules, valves and actuators to improve reliability and energy efficiency. Provide a new building automation system (BAS) with communication interface to the preferred system in use throughout the District.
- Install a fire protection sprinkler system with quick response type heads to reduce insurance costs by providing protection for the property. A fire pump may be required depending on the available city water pressure.
- Install new Site electrical service 1500KVA, 480V, 3 Phase to feed the HVAC, lighting and receptacle loads.
- Install a new 480V, 3 phase switchgear.
- Install a new 120V/208V, 3 phase switchgear.
- Install new 120V panelboards throughout the building for lighting, and receptacles loads.
- Install new receptacles in all classrooms and other areas (minimum two receptacles on each wall).
- Install new a lighting system for the entire building.
- Install new emergency exit signs & emergency lights.
- Install a new automated FA System
- Install a new 100KW Emergency Generator

Attributes:

General Attributes:

Active:	Open	Bldg Lot Tm:	Lot 3 / Tm 4
Status:	Accepted by SDP	Team:	Tm 4
Site ID:	S738001		

Site Condition Summary

The Table below shows the CI and FCI for each major system shown at the UNIFORMAT classification Level II. Note that Systems with lower FCIs require less investment than systems with higher FCIs.

Current Investment Requirement and Condition by Uniformat Classification

UNIFORMAT Classification	RSLI%	FCI %	Current Repair
A10 - Foundations	52.00 %	2.24 %	\$51,343.32
A20 - Basement Construction	52.00 %	0.00 %	\$0.00
B10 - Superstructure	52.00 %	1.03 %	\$68,922.58
B20 - Exterior Enclosure	69.54 %	69.40 %	\$1,856,371.00
B30 - Roofing	103.98 %	84.82 %	\$606,488.00
C10 - Interior Construction	65.79 %	85.66 %	\$1,123,471.67
C20 - Stairs	52.00 %	0.00 %	\$0.00
C30 - Interior Finishes	105.52 %	44.87 %	\$1,390,093.50
D10 - Conveying	105.71 %	344.54 %	\$758,761.42
D20 - Plumbing	68.40 %	39.92 %	\$933,574.37
D30 - HVAC	85.05 %	92.40 %	\$5,910,375.55
D40 - Fire Protection	94.10 %	158.77 %	\$822,561.76
D50 - Electrical	110.01 %	91.55 %	\$3,183,267.88
E10 - Equipment	19.92 %	0.00 %	\$0.00
E20 - Furnishings	0.00 %	0.00 %	\$0.00
G20 - Site Improvements	105.79 %	99.36 %	\$491,650.12
G40 - Site Electrical Utilities	106.67 %	119.35 %	\$205,953.48
Totals:	74.43 %	51.82 %	\$17,402,834.65

Condition Deficiency Priority

Facility Name	Gross Area (S.F.)	FCI %	1 - Response Time (< 2 yr)	2 - Response Time (2-3 yrs)	3 - Response Time (3-4 yrs)	4 - Response Time (4-5 yrs)	5 - Response Time (> 5 yrs)
B738001;McClure	57,500	50.75	\$877,168.48	\$944,848.70	\$3,744,706.53	\$3,266,604.58	\$7,871,902.76
G738001;Grounds	29,700	104.53	\$0.00	\$0.00	\$143,724.13	\$132,139.57	\$421,739.90
Total:		51.82	\$877,168.48	\$944,848.70	\$3,888,430.66	\$3,398,744.15	\$8,293,642.66

Deficiencies By Priority



- 1 - Response Time (< 2 yr) - \$877,168.48
- 2 - Response Time (2-3 yrs) - \$944,848.70
- 3 - Response Time (3-4 yrs) - \$3,888,430.66
- 4 - Response Time (4-5 yrs) - \$3,398,744.15
- 5 - Response Time (> 5 yrs) - \$8,293,642.66

Budget Estimate Total: \$17,402,834.65

Executive Summary

Building condition is evaluated based on the functional systems and elements of a building and organized according to the UNIFORMAT II Elemental Classification. The grouping of these systems and elements and applying a current replacement value to them develops a representative building cost model. Cost Models are developed for similar building types and functions. Systems and their elements are evaluated based on their current replacement values, life cycles, installation dates and next renewal dates. Systems and their elements that are within their useful lives are further evaluated to identify current deficient conditions that may have a significant impact on a system's or element's remaining service life, and to determine if they are beyond their predicted expected life. The system's or element's current replacement value is based on RS Means Commercial Cost Data.

Following are the cost model's system details for this facility. The Replacement Value is the amount needed to replace the property of the same present value. The Current Repair Amount, also known as Condition Needs, represents the budgeted contractor installed costs plus owner's soft costs for the repair, replacement or renewal for a component or system level deficiency. It excludes contributing costs for other components or systems that might also be associated with the corrective actions due to packaging the work. Facility Condition Index (FCI) FCI is an industry-standard measurement of facility condition calculated as the ratio of the costs to correct a facility's deficiencies to the facility's Current Replacement Value. It ranges from 0% (new) to 100% (very poor). Condition Index (CI) is calculated as the sum of a renewable system's Remaining Service Life (RSL) divided by the sum of a system's Replacement Value (both values exclude soft-cost to simplify calculation updates) expressed as a percentage ranging from 100% (new) to 0% (expired).

Function:	Elementary School
Gross Area (SF):	57,500
Year Built:	1910
Last Renovation:	
Replacement Value:	\$32,914,606
Repair Cost:	\$16,705,231.05
Total FCI:	50.75 %
Total RSLI:	73.79 %

Description:

Attributes:

General Attributes:

Active:	Open	Bldg ID:	B738001
Sewage Ejector:	No	Status:	Accepted by SDP
Site ID:	S738001		

Condition Summary

The Table below shows the CI and FCI for each major building system shown at the UNIFORMAT classification Level II. Note that Systems with lower FCIs require less investment than systems with higher FCIs.

UNIFORMAT Classification	RSLI %	FCI %	Current Repair Cost
A10 - Foundations	52.00 %	2.24 %	\$51,343.32
A20 - Basement Construction	52.00 %	0.00 %	\$0.00
B10 - Superstructure	52.00 %	1.03 %	\$68,922.58
B20 - Exterior Enclosure	69.54 %	69.40 %	\$1,856,371.00
B30 - Roofing	103.98 %	84.82 %	\$606,488.00
C10 - Interior Construction	65.79 %	85.66 %	\$1,123,471.67
C20 - Stairs	52.00 %	0.00 %	\$0.00
C30 - Interior Finishes	105.52 %	44.87 %	\$1,390,093.50
D10 - Conveying	105.71 %	344.54 %	\$758,761.42
D20 - Plumbing	68.40 %	39.92 %	\$933,574.37
D30 - HVAC	85.05 %	92.40 %	\$5,910,375.55
D40 - Fire Protection	94.10 %	158.77 %	\$822,561.76
D50 - Electrical	110.01 %	91.55 %	\$3,183,267.88
E10 - Equipment	19.92 %	0.00 %	\$0.00
E20 - Furnishings	0.00 %	0.00 %	\$0.00
Totals:	73.79 %	50.75 %	\$16,705,231.05

Condition Detail

This section of the report contains results of the Facility Condition Assessment. The building is separated into system components based on UNIFORMAT II classification. The columns in the System Listing table below represent the following:

1. System Code: A code that identifies the system.
2. System Description: A brief description of a system present in the building.
3. Unit Price \$: The unit price of the system.
4. UoM: The unit of measure for of the system.
5. Qty: The quantity for the system
6. Life: anticipated service life for the system based on Building Owners and Managers Association (BOMA) recommendations.
7. Year Installed: The date of system installation.
8. Calc Next Renewal Year: The date of system expiration based on the life, NR stands for non renewable.
9. Next Renewal Year: The suggested system expiration date by the assessor based on visual inspection.
10. CI: The Condition Index of the system.
11. FCI: The Facility Condition Index of the system.
12. RSL: Remaining Service Life.
13. eCR: eCOMET Condition Rating (not used).
14. Deficiency \$: The financial investment to repair/replace system.

System Listing

The System Listing table below lists each of the systems organized by their UNIFORMAT II classification. The assessment team was tasked with recording the most recent replacement year of each system, determining the remaining service life based on the theoretical life, and evaluating the condition to confirm the forecast next replacement year. The system listing is the basis for all data contained in the Building Assessment Report.

Additionally, a condition rating (eCR) based on the following guidelines is provided as observed at the time of the assessment.

- Excellent (E) - No noticeable distress or damage. The entire system is free from observable defect.
- Very Good (VG) - Overall no serviceability reduction for the entire system. No degradation of critical components and minor distress and defect noticeable for some but not non critical components within the system.
- Good (G) - Slight or no serviceability reduction for the entire system. There may be noticeable defects for some non critical components and slight noticeable degradation of the critical components.
- Fair (F) - Overall serviceability is degraded but adequate. There may be moderate deterioration for very few of the critical components and few of the non critical components may have severe degradation.
- Marginal (MA) - Overall serviceability and reliability loss. Most if not all of the non critical components suffer from severe degradation and a few of the critical component may have severe degradation.
- Moderate (MO) - Overall a significant serviceability loss. Most if not all the components have severe degradation with the reminder of the component showing visible distress.
- Very Poor (VP) - Overall the system is barely functional. All of the components are severely degraded.
- Non-Functional (NF) - Overall the system does not function with all the components having no serviceability and suffer from severe degradation.

System Code	System Description	Unit Price \$	UoM	Qty	Life	Year Installed	Calc Next Renewal Year	Next Renewal Year	RSLI%	FCI%	RSL	eCR	Deficiency \$	Replacement Value \$
A1010	Standard Foundations	\$24.32	S.F.	57,500	100	1910	2010	2067	52.00 %	0.00 %	52			\$1,398,400
A1030	Slab on Grade	\$15.51	S.F.	57,500	100	1910	2010	2067	52.00 %	5.76 %	52		\$51,343.32	\$891,825
A2010	Basement Excavation	\$13.07	S.F.	57,500	100	1910	2010	2067	52.00 %	0.00 %	52			\$751,525
A2020	Basement Walls	\$23.02	S.F.	57,500	100	1910	2010	2067	52.00 %	0.00 %	52			\$1,323,650
B1010	Floor Construction	\$92.20	S.F.	57,500	100	1910	2010	2067	52.00 %	1.30 %	52		\$68,922.58	\$5,301,500
B1020	Roof Construction	\$24.11	S.F.	57,500	100	1910	2010	2067	52.00 %	0.00 %	52			\$1,386,325
B2010	Exterior Walls	\$31.22	S.F.	57,500	100	1910	2010	2067	52.00 %	0.00 %	52			\$1,795,150
B2020	Exterior Windows	\$13.63	S.F.	57,500	40	1990	2030	2057	105.00 %	215.95 %	42		\$1,692,439.23	\$783,725
B2030	Exterior Doors	\$1.67	S.F.	57,500	25	1990	2015	2042	108.00 %	170.72 %	27		\$163,931.77	\$96,025
B3010105	Built-Up	\$37.76	S.F.	17,900	20	1990	2010	2037	110.00 %	89.73 %	22		\$606,488.00	\$675,904
B3010120	Single Ply Membrane	\$38.73	S.F.		20				0.00 %	0.00 %				\$0
B3010130	Preformed Metal Roofing	\$54.22	S.F.		30				0.00 %	0.00 %				\$0
B3010140	Shingle & Tile	\$38.73	S.F.		20				0.00 %	0.00 %				\$0
B3020	Roof Openings	\$0.68	S.F.	57,500	20				0.00 %	0.00 %				\$39,100
C1010	Partitions	\$14.93	S.F.	57,500	100	1910	2010	2067	52.00 %	79.73 %	52		\$684,504.34	\$858,475
C1020	Interior Doors	\$3.76	S.F.	57,500	40	1910	1950	2057	105.00 %	172.22 %	42		\$372,347.12	\$216,200
C1030	Fittings	\$4.12	S.F.	57,500	40	2007	2047		80.00 %	28.12 %	32		\$66,620.21	\$236,900
C2010	Stair Construction	\$1.28	S.F.	57,500	100	1910	2010	2067	52.00 %	0.00 %	52			\$73,600

Site Assessment Report - B738001;McClure

System Code	System Description	Unit Price \$	UoM	Qty	Life	Year Installed	Calc Next Renewal Year	Next Renewal Year	RSLI%	FCI%	RSL	eCR	Deficiency \$	Replacement Value \$
C3010230	Paint & Covering	\$13.21	S.F.	57,500	10	2005	2015	2027	120.00 %	102.56 %	12		\$778,995.86	\$759,575
C3010231	Vinyl Wall Covering	\$0.97	S.F.	57,500	15				0.00 %	0.00 %				\$55,775
C3010232	Wall Tile	\$2.63	S.F.	57,500	30	2005	2035		66.67 %	0.00 %	20			\$151,225
C3020411	Carpet	\$7.30	S.F.		10				0.00 %	0.00 %				\$0
C3020412	Terrazzo & Tile	\$75.52	S.F.	2,200	50	2005	2055		80.00 %	0.00 %	40			\$166,144
C3020413	Vinyl Flooring	\$9.68	S.F.	8,000	20	2000	2020	2037	110.00 %	49.66 %	22		\$38,456.10	\$77,440
C3020414	Wood Flooring	\$22.27	S.F.	30,400	25	1910	1935	2042	108.00 %	48.56 %	27		\$328,758.83	\$677,008
C3020415	Concrete Floor Finishes	\$0.97	S.F.	5,500	50	1910	1960	2067	104.00 %	0.00 %	52			\$5,335
C3030	Ceiling Finishes	\$20.97	S.F.	57,500	25	1990	2015	2042	108.00 %	20.23 %	27		\$243,882.71	\$1,205,775
D1010	Elevators and Lifts	\$3.83	S.F.	57,500	35			2052	105.71 %	344.54 %	37		\$758,761.42	\$220,225
D2010	Plumbing Fixtures	\$31.58	S.F.	57,500	35	2000	2035		57.14 %	0.00 %	20			\$1,815,850
D2020	Domestic Water Distribution	\$2.90	S.F.	57,500	25	1910	1935	2042	108.00 %	237.79 %	27		\$396,514.04	\$166,750
D2030	Sanitary Waste	\$2.90	S.F.	57,500	25	1910	1935	2042	108.00 %	169.16 %	27		\$282,080.52	\$166,750
D2040	Rain Water Drainage	\$3.29	S.F.	57,500	30	1910	1940	2047	106.67 %	134.79 %	32		\$254,979.81	\$189,175
D3020	Heat Generating Systems	\$18.67	S.F.	57,500	35	1992	2027		34.29 %	0.00 %	12			\$1,073,525
D3030	Cooling Generating Systems	\$24.48	S.F.	57,500	20			2037	110.00 %	65.31 %	22		\$919,356.92	\$1,407,600
D3040	Distribution Systems	\$42.99	S.F.	57,500	25	1910	1935	2042	108.00 %	152.01 %	27		\$3,757,520.90	\$2,471,925
D3050	Terminal & Package Units	\$11.60	S.F.	57,500	20				0.00 %	0.00 %				\$667,000
D3060	Controls & Instrumentation	\$13.50	S.F.	57,500	20	1910	1930	2037	110.00 %	158.90 %	22		\$1,233,497.73	\$776,250
D4010	Sprinklers	\$8.02	S.F.	57,500	35			2052	105.71 %	178.37 %	37		\$822,561.76	\$461,150
D4020	Standpipes	\$0.99	S.F.	57,500	35				0.00 %	0.00 %				\$56,925
D5010	Electrical Service/Distribution	\$9.70	S.F.	57,500	30	1910	1940	2047	106.67 %	146.96 %	32		\$819,674.80	\$557,750
D5020	Lighting and Branch Wiring	\$34.68	S.F.	57,500	20	1910	1930	2037	110.00 %	58.36 %	22		\$1,163,791.96	\$1,994,100
D5030	Communications and Security	\$12.99	S.F.	57,500	15	1910	1925	2032	113.33 %	99.68 %	17		\$744,553.98	\$746,925
D5090	Other Electrical Systems	\$3.10	S.F.	57,500	30	1910	1940	2047	106.67 %	255.40 %	32		\$455,247.14	\$178,250
E1020	Institutional Equipment	\$4.82	S.F.	57,500	35				0.00 %	0.00 %				\$277,150
E1090	Other Equipment	\$11.10	S.F.	57,500	35	1990	2025		28.57 %	0.00 %	10			\$638,250
E2010	Fixed Furnishings	\$2.13	S.F.	57,500	40				0.00 %	0.00 %				\$122,475
Total									73.79 %	50.75 %			\$16,705,231.05	\$32,914,606

System Notes

The facility description in the site executive summary contains an overview of each system. The notes listed below provide additional information on select systems found within the facility.

System: C3010 - Wall Finishes	This system contains no images
Note: Paint 85% Ceramic tile 5% Glazed brick 10%	

System: C3020 - Floor Finishes	This system contains no images
Note: Hardwood 66% VCT 17% Ceramic tile 5% Concrete 12%	

System: C3030 - Ceiling Finishes	This system contains no images
Note: Exposed/plaster, painted 95% ACT 5%	

Renewal Schedule

eCOMET forecasts future Capital Renewal funding needed to address expiring systems based on the Next Renewal year found in the Cost Models. A 3% annual inflation factor is applied to the costs for systems expiring in future years. The table below reflects recommended Capital Renewal funding needs over the next 10 years. Note: Cells with a zero value indicate systems for which renewal is not scheduled in that year.

Inflation Rate: 3%

System	Current Deficiencies	2016	2017	2018	2019	2020	2021	2022	2023	2024	2025	Total
Total:	\$16,705,231	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$943,530	\$17,648,761
* A - Substructure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A10 - Foundations	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
A1010 - Standard Foundations	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
A1030 - Slab on Grade	\$51,343	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$51,343
* A20 - Basement Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
A2010 - Basement Excavation	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
A2020 - Basement Walls	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B - Shell	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B10 - Superstructure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B1010 - Floor Construction	\$68,923	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$68,923
B1020 - Roof Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B20 - Exterior Enclosure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B2010 - Exterior Walls	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B2020 - Exterior Windows	\$1,692,439	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$1,692,439
B2030 - Exterior Doors	\$163,932	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$163,932
B30 - Roofing	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3010 - Roof Coverings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3010105 - Built-Up	\$606,488	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$606,488
B3010120 - Single Ply Membrane	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3010130 - Preformed Metal Roofing	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3010140 - Shingle & Tile	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3020 - Roof Openings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C - Interiors	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C10 - Interior Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C1010 - Partitions	\$684,504	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$684,504

Site Assessment Report - B738001;McClure

C1020 - Interior Doors	\$372,347	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$372,347
C1030 - Fittings	\$66,620	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$66,620
C20 - Stairs	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C2010 - Stair Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C30 - Interior Finishes	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C3010 - Wall Finishes	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C3010230 - Paint & Covering	\$778,996	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$778,996
C3010231 - Vinyl Wall Covering	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C3010232 - Wall Tile	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C3020 - Floor Finishes	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C3020411 - Carpet	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C3020412 - Terrazzo & Tile	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C3020413 - Vinyl Flooring	\$38,456	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$38,456
C3020414 - Wood Flooring	\$328,759	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$328,759
C3020415 - Concrete Floor Finishes	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C3030 - Ceiling Finishes	\$243,883	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$243,883
D - Services	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D10 - Conveying	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D1010 - Elevators and Lifts	\$758,761	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$758,761
D20 - Plumbing	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D2010 - Plumbing Fixtures	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D2020 - Domestic Water Distribution	\$396,514	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$396,514
D2030 - Sanitary Waste	\$282,081	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$282,081
D2040 - Rain Water Drainage	\$254,980	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$254,980
D30 - HVAC	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D3020 - Heat Generating Systems	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D3030 - Cooling Generating Systems	\$919,357	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$919,357
D3040 - Distribution Systems	\$3,757,521	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$3,757,521
D3050 - Terminal & Package Units	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D3060 - Controls & Instrumentation	\$1,233,498	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$1,233,498
D40 - Fire Protection	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D4010 - Sprinklers	\$822,562	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$822,562
D4020 - Standpipes	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0


Site Assessment Report - B738001;McClure

D50 - Electrical	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5010 - Electrical Service/Distribution	\$819,675	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$819,675
D5020 - Lighting and Branch Wiring	\$1,163,792	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$1,163,792
D5030 - Communications and Security	\$744,554	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$744,554
D5090 - Other Electrical Systems	\$455,247	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$455,247
E - Equipment & Furnishings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E10 - Equipment	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E1020 - Institutional Equipment	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E1090 - Other Equipment	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$943,530	\$943,530
E20 - Furnishings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E2010 - Fixed Furnishings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0

* Indicates non-renewable system

Forecasted Sustainment Requirement

The following chart shows the current building deficiencies and forecasting sustainment requirements over the next ten years.




10 Year FCI Forecast by Investment Scenario

The chart below illustrates the effect of various investment levels on the building FCI for the next 10 years. The levels of investment shown below include:

- Current FCI: a variable investment amount based on renewing expired systems to maintain the current FCI for the building
- 2% Investment: an annual investment of 2% of the replacement value of the building, escalated for inflation
- 4% Investment: an annual investment of 4% of the replacement value of the building, escalated for inflation


Facility Investment vs. FCI Forecast



Year	Investment Amount Current FCI - 50.75%	2% Investment		4% Investment	
		Amount	FCI	Amount	FCI
2016	\$0	\$678,041.00	48.75 %	\$1,356,082.00	46.75 %
2017	\$16,143,954	\$698,382.00	92.99 %	\$1,396,764.00	88.99 %
2018	\$0	\$719,334.00	90.99 %	\$1,438,667.00	84.99 %
2019	\$0	\$740,914.00	88.99 %	\$1,481,827.00	80.99 %
2020	\$0	\$763,141.00	86.99 %	\$1,526,282.00	76.99 %
2021	\$0	\$786,035.00	84.99 %	\$1,572,070.00	72.99 %
2022	\$0	\$809,616.00	82.99 %	\$1,619,233.00	68.99 %
2023	\$0	\$833,905.00	80.99 %	\$1,667,810.00	64.99 %
2024	\$0	\$858,922.00	78.99 %	\$1,717,844.00	60.99 %
2025	\$943,530	\$884,690.00	79.12 %	\$1,769,379.00	59.12 %
Total:	\$17,087,484	\$7,772,980.00		\$15,545,958.00	

Deficiency Summary by System


Current deficiencies included assemblies that have reached or exceeded their design life or components of the assemblies that are in need of repair. Assemblies that have reached their design life are identified as current deficiencies and assigned the distress 'Beyond Useful Life'. The following chart lists all current deficiencies associated with this facility.



Budget Estimate Total: \$16,705,231.05

Deficiency Summary by Priority

The following chart shows the total repair costs broken down by priority. Assessors assigned deficiencies within eCOMET to one of the following priority categories:



Budget Estimate Total: \$16,705,231.05


Deficiency By Priority Investment Table

The table below shows the current investment cost grouped by deficiency priority and building system.

System Code	System Description	1 - Response Time (< 2 yr)	2 - Response Time (2-3 yrs)	3 - Response Time (3-4 yrs)	4 - Response Time (4-5 yrs)	5 - Response Time (> 5 yrs)	Total
A1030	Slab on Grade	\$0.00	\$0.00	\$0.00	\$51,343.32	\$0.00	\$51,343.32
B1010	Floor Construction	\$0.00	\$0.00	\$4,054.28	\$64,868.30	\$0.00	\$68,922.58
B2020	Exterior Windows	\$0.00	\$0.00	\$0.00	\$0.00	\$1,692,439.23	\$1,692,439.23
B2030	Exterior Doors	\$0.00	\$0.00	\$0.00	\$163,931.77	\$0.00	\$163,931.77
B3010105	Built-Up	\$0.00	\$606,488.00	\$0.00	\$0.00	\$0.00	\$606,488.00
C1010	Partitions	\$0.00	\$0.00	\$0.00	\$0.00	\$684,504.34	\$684,504.34
C1020	Interior Doors	\$0.00	\$0.00	\$0.00	\$372,347.12	\$0.00	\$372,347.12
C1030	Fittings	\$0.00	\$0.00	\$0.00	\$66,620.21	\$0.00	\$66,620.21
C3010230	Paint & Covering	\$0.00	\$0.00	\$0.00	\$778,995.86	\$0.00	\$778,995.86
C3020413	Vinyl Flooring	\$0.00	\$0.00	\$0.00	\$38,456.10	\$0.00	\$38,456.10
C3020414	Wood Flooring	\$0.00	\$0.00	\$0.00	\$328,758.83	\$0.00	\$328,758.83
C3030	Ceiling Finishes	\$0.00	\$0.00	\$0.00	\$34,689.59	\$209,193.12	\$243,882.71
D1010	Elevators and Lifts	\$0.00	\$0.00	\$758,761.42	\$0.00	\$0.00	\$758,761.42
D2020	Domestic Water Distribution	\$54,606.72	\$50,533.86	\$0.00	\$291,373.46	\$0.00	\$396,514.04
D2030	Sanitary Waste	\$0.00	\$0.00	\$282,080.52	\$0.00	\$0.00	\$282,080.52
D2040	Rain Water Drainage	\$0.00	\$254,979.81	\$0.00	\$0.00	\$0.00	\$254,979.81
D3030	Cooling Generating Systems	\$0.00	\$0.00	\$0.00	\$0.00	\$919,356.92	\$919,356.92
D3040	Distribution Systems	\$0.00	\$32,847.03	\$591,762.45	\$0.00	\$3,132,911.42	\$3,757,520.90
D3060	Controls & Instrumentation	\$0.00	\$0.00	\$0.00	\$0.00	\$1,233,497.73	\$1,233,497.73
D4010	Sprinklers	\$822,561.76	\$0.00	\$0.00	\$0.00	\$0.00	\$822,561.76
D5010	Electrical Service/Distribution	\$0.00	\$0.00	\$0.00	\$819,674.80	\$0.00	\$819,674.80
D5020	Lighting and Branch Wiring	\$0.00	\$0.00	\$1,163,791.96	\$0.00	\$0.00	\$1,163,791.96
D5030	Communications and Security	\$0.00	\$0.00	\$489,008.76	\$255,545.22	\$0.00	\$744,553.98
D5090	Other Electrical Systems	\$0.00	\$0.00	\$455,247.14	\$0.00	\$0.00	\$455,247.14
	Total:	\$877,168.48	\$944,848.70	\$3,744,706.53	\$3,266,604.58	\$7,871,902.76	\$16,705,231.05

Deficiency Summary by Category

The following chart shows the total repair costs broken down by deficiency categories. Assessors assigned deficiencies to one of the following categories:



Deficiency Details by Priority

The deficiency detail notes listed below provide additional information on identified deficiencies found within the facility.

Priority 1 - Response Time (< 2 yr):

System: D2020 - Domestic Water Distribution



Location: Boiler room

Distress: Beyond Service Life

Category: 3 - Operations / Maint.

Priority: 1 - Response Time (< 2 yr)

Correction: Replace vertical tank type gas-fired water heater (75 gal)

Qty: 1.00

Unit of Measure: Ea.

Estimate: \$54,606.72

Assessor Name: System

Date Created: 11/13/2015

Notes: Replace the existing vertical gas fired, 48 gallon, domestic hot water heater which is beyond its service life with a new gas fired hot water heater.

System: D4010 - Sprinklers



Location: Throughout building

Distress: Life Safety / NFPA / PFD

Category: 1 - Health & Safety

Priority: 1 - Response Time (< 2 yr)

Correction: Install a fire protection sprinkler system

Qty: 57,500.00

Unit of Measure: S.F.

Estimate: \$822,561.76

Assessor Name: System

Date Created: 11/13/2015

Notes: Install a fire protection sprinkler system with quick response type heads to reduce insurance costs by providing protection for the property. A fire pump may be required depending on the available city water pressure.

Priority 2 - Response Time (2-3 yrs):

System: B3010105 - Built-Up



Location: Exterior

Distress: Beyond Service Life

Category: 3 - Operations / Maint.

Priority: 2 - Response Time (2-3 yrs)

Correction: Remove and Replace Built Up Roof

Qty: 17,900.00

Unit of Measure: S.F.

Estimate: \$606,488.00

Assessor Name: System

Date Created: 01/07/2016

Notes: Install all new roofing system including insulation within next 4 to 5 years; tear-down existing roofing; install flashing, counter flashing and reglets

System: D2020 - Domestic Water Distribution



Location: Boiler room

Distress: Damaged

Category: 3 - Operations / Maint.

Priority: 2 - Response Time (2-3 yrs)

Correction: Replace duplex domestic booster pump set (5 HP)

Qty: 1.00

Unit of Measure: Ea.

Estimate: \$50,533.86

Assessor Name: System

Date Created: 11/13/2015

Notes: Replace the skid mounted duplex 5HP domestic water booster pumps and isolation valves on the incoming domestic water line which show signs of rust damage.

System: D2040 - Rain Water Drainage



Location: Throughout building

Distress: Damaged

Category: 3 - Operations / Maint.

Priority: 2 - Response Time (2-3 yrs)

Correction: Inspect internal rain water drainage piping and replace pipe - based on SF of multi-story building - insert SF of building

Qty: 57,500.00

Unit of Measure: S.F.

Estimate: \$254,979.81

Assessor Name: System

Date Created: 11/13/2015

Notes: Hire a qualified contractor to perform a detailed examination of the rain water drainage piping using visual inspection and video cameras to locate and replace any damaged piping and to further quantify the extent of potential failures.

System: D3040 - Distribution Systems



Location: Roof

Distress: Damaged

Category: 3 - Operations / Maint.

Priority: 2 - Response Time (2-3 yrs)

Correction: Replace rooftop gravity ventilator units - select the proper type and size

Qty: 11.00

Unit of Measure: Ea.

Estimate: \$32,847.03

Assessor Name: System

Date Created: 11/13/2015

Notes: Replace eleven (11) roof mounted gravity ventilators which have been removed from the roof.

Priority 3 - Response Time (3-4 yrs):

System: B1010 - Floor Construction



Location: Interior/ basement

Distress: Damaged

Category: 3 - Operations / Maint.

Priority: 3 - Response Time (3-4 yrs)

Correction: Repair rebar and epoxy grout exposed rebar on the underside of floors and floor beams

Qty: 50.00

Unit of Measure: S.F.

Estimate: \$4,054.28

Assessor Name: System

Date Created: 01/07/2016

Notes: Repair (epoxy patch) damaged concrete column in boiler room

System: D1010 - Elevators and Lifts

This deficiency has no image.

Location: Interior

Distress: Accessibility

Category: 2 - Code Compliance

Priority: 3 - Response Time (3-4 yrs)

Correction: Add interior elevator - 4 floors - adjust the electrical run lengths to hook up the elevator

Qty: 1.00

Unit of Measure: Ea.

Estimate: \$670,322.07

Assessor Name: System

Date Created: 01/08/2016

Notes: Install 4000 lb traction elevator serving all floors and basement

System: D1010 - Elevators and Lifts

This deficiency has no image.

Location: Interior
Distress: Accessibility
Category: 2 - Code Compliance
Priority: 3 - Response Time (3-4 yrs)
Correction: Add interior hydraulic elevator - 2 floors - adjust the electrical run lengths to hook up the elevator
Qty: 1.00
Unit of Measure: Ea.
Estimate: \$88,439.35
Assessor Name: System
Date Created: 01/08/2016

Notes: Provide wheelchair lift at the main entrance

System: D2030 - Sanitary Waste



Location: Throughout building
Distress: Beyond Service Life
Category: 3 - Operations / Maint.
Priority: 3 - Response Time (3-4 yrs)
Correction: Inspect sanitary waste piping and replace damaged sections. (+50KSF)
Qty: 57,500.00
Unit of Measure: S.F.
Estimate: \$282,080.52
Assessor Name: System
Date Created: 11/13/2015

Notes: Hire a qualified contractor to perform a detailed examination of the sanitary waste piping using visual inspection and video cameras to locate and replace any damaged piping and to further quantify the extent of potential failures.

System: D3040 - Distribution Systems



Location: Throughout building

Distress: Beyond Service Life

Category: 3 - Operations / Maint.

Priority: 3 - Response Time (3-4 yrs)

Correction: Perform testing to identify and replace damaged steam and condensate piping.

Qty: 57,500.00

Unit of Measure: S.F.

Estimate: \$543,971.35

Assessor Name: System

Date Created: 11/13/2015

Notes: Hire a qualified contractor to examine the steam piping, in service for over 100 years, and perform additional testing to locate and replace any damaged piping and to further quantify the extent of potential failures.

System: D3040 - Distribution Systems



Location: Boiler room

Distress: Damaged

Category: 3 - Operations / Maint.

Priority: 3 - Response Time (3-4 yrs)

Correction: Replace Condensate Receiver Pump Set

Qty: 1.00

Unit of Measure: Ea.


Estimate: \$47,791.10

Assessor Name: System

Date Created: 11/13/2015

Notes: Replace two (2) of the boiler feed water pumps which are damaged from rust.

System: D5020 - Lighting and Branch Wiring



Location: throughout the building

Distress: Beyond Service Life

Category: 3 - Operations / Maint.

Priority: 3 - Response Time (3-4 yrs)

Correction: Replace Lighting Fixtures (SF)

Qty: 0.00

Unit of Measure: S.F.

Estimate: \$749,226.04

Assessor Name: System

Date Created: 01/06/2016

Notes: Install new a lighting system for the entire building•

System: D5020 - Lighting and Branch Wiring



Location: throughout the building

Distress: Inadequate

Category: 3 - Operations / Maint.

Priority: 3 - Response Time (3-4 yrs)

Correction: Replace Wiring Devices (SF) - surface mounted conduit and boxes

Qty: 0.00

Unit of Measure: S.F.

Estimate: \$414,565.92

Assessor Name: System

Date Created: 01/06/2016

Notes: Install new receptacles in all classrooms and other areas (minimum two receptacles on each wall).


System: D5030 - Communications and Security



Location: throughout the building
Distress: Health Hazard / Risk
Category: 1 - Health & Safety
Priority: 3 - Response Time (3-4 yrs)
Correction: Replace fire alarm system
Qty: 1.00
Unit of Measure: S.F.
Estimate: \$489,008.76
Assessor Name: System
Date Created: 01/06/2016

Notes: Install a new automated FA System

System: D5090 - Other Electrical Systems



Location: throughout the building
Distress: Beyond Service Life
Category: 3 - Operations / Maint.
Priority: 3 - Response Time (3-4 yrs)
Correction: Add Emergency/Exit Lighting
Qty: 1.00
Unit of Measure: Ea.
Estimate: \$331,983.88
Assessor Name: System
Date Created: 01/06/2016

Notes: Install new emergency exit signs emergency lights.

System: D5090 - Other Electrical Systems



Location: electrical room

Distress: Inadequate

Category: 4 - Capital Improvement

Priority: 3 - Response Time (3-4 yrs)

Correction: Add Standby Generator System

Qty: 1.00

Unit of Measure: Ea.

Estimate: \$123,263.26

Assessor Name: System

Date Created: 01/06/2016

Notes: Install a new 100KW Emergency Generator.

Priority 4 - Response Time (4-5 yrs):

System: A1030 - Slab on Grade



Location: Interior/ basement

Distress: Failing

Category: 3 - Operations / Maint.

Priority: 4 - Response Time (4-5 yrs)

Correction: Remove and replace slab on grade including under slab electrical conduit and in-floor receptacles

Qty: 1,800.00

Unit of Measure: S.F.

Estimate: \$51,343.32

Assessor Name: System

Date Created: 01/07/2016

Notes: Repair deteriorated slab section in basement (room 006)

System: B1010 - Floor Construction



Location: Exterior/ Interior

Distress: Damaged

Category: 3 - Operations / Maint.

Priority: 4 - Response Time (4-5 yrs)

Correction: Repair rebar and epoxy grout exposed rebar on the underside of floors and floor beams

Qty: 800.00

Unit of Measure: S.F.

Estimate: \$64,868.30

Assessor Name: System

Date Created: 01/07/2016

Notes: Repair/patch concrete slabs in fire tower

System: B2030 - Exterior Doors



Location: Exterior

Distress: Beyond Service Life

Category: 3 - Operations / Maint.

Priority: 4 - Response Time (4-5 yrs)

Correction: Remove and replace exterior doors - per leaf

Qty: 18.00

Unit of Measure: Ea.

Estimate: \$163,931.77

Assessor Name: System

Date Created: 01/07/2016

Notes: Replace all exterior doors

System: C1020 - Interior Doors



Location: Interior

Distress: Beyond Service Life

Category: 3 - Operations / Maint.

Priority: 4 - Response Time (4-5 yrs)

Correction: Remove and replace interior doors - wood doors with wood frame - per leaf

Qty: 80.00

Unit of Measure: Ea.

Estimate: \$372,347.12

Assessor Name: System

Date Created: 01/07/2016

Notes: Replace interior doors in the building

System: C1030 - Fittings



Location: Interior

Distress: Beyond Service Life

Category: 3 - Operations / Maint.

Priority: 4 - Response Time (4-5 yrs)

Correction: Replace missing or damaged signage - insert the number of rooms

Qty: 150.00

Unit of Measure: Ea.

Estimate: \$40,636.87

Assessor Name: System

Date Created: 01/07/2016

Notes: Replace signage throughout

System: C1030 - Fittings



Location: Interior

Distress: Building / MEP Codes

Category: 2 - Code Compliance

Priority: 4 - Response Time (4-5 yrs)

Correction: Remove and replace damaged toilet partitions - handicap units

Qty: 8.00

Unit of Measure: Ea.

Estimate: \$25,983.34

Assessor Name: System

Date Created: 01/07/2016

Notes: Provide ADA accessible partitions in toilets (all floors except basement)

System: C3010230 - Paint & Covering



Location: Interior

Distress: Beyond Service Life

Category: 3 - Operations / Maint.

Priority: 4 - Response Time (4-5 yrs)

Correction: Repair and repaint all interior walls - SF of wall surface

Qty: 115,000.00

Unit of Measure: S.F.

Estimate: \$778,995.86

Assessor Name: System

Date Created: 01/07/2016

Notes: Repaint all walls

System: C3020413 - Vinyl Flooring



Location: Interior

Distress: Damaged

Category: 3 - Operations / Maint.

Priority: 4 - Response Time (4-5 yrs)

Correction: Remove and replace VCT

Qty: 3,200.00

Unit of Measure: S.F.

Estimate: \$38,456.10

Assessor Name: System

Date Created: 01/07/2016

Notes: Replace damaged VCT (20%)

System: C3020414 - Wood Flooring



Location: Interior

Distress: Beyond Service Life

Category: 3 - Operations / Maint.

Priority: 4 - Response Time (4-5 yrs)

Correction: Remove and replace partial area of wood flooring and refinish entire floor - set replacement area

Qty: 30,400.00

Unit of Measure: S.F.


Estimate: \$328,758.83

Assessor Name: System

Date Created: 01/07/2016

Notes: Repair (15%) refinish hardwood flooring

System: C3030 - Ceiling Finishes



Location: Interior

Distress: Beyond Service Life

Category: 3 - Operations / Maint.

Priority: 4 - Response Time (4-5 yrs)

Correction: Remove and replace suspended acoustic ceilings - lighting not included

Qty: 2,300.00

Unit of Measure: S.F.

Estimate: \$34,689.59

Assessor Name: System

Date Created: 01/07/2016

Notes: Replace ACT ceilings

System: D2020 - Domestic Water Distribution



Location: Throughout building

Distress: Beyond Service Life

Category: 3 - Operations / Maint.

Priority: 4 - Response Time (4-5 yrs)

Correction: Replace domestic water piping (75 KSF)

Qty: 57,500.00

Unit of Measure: S.F.


Estimate: \$291,373.46

Assessor Name: System

Date Created: 11/13/2015

Notes: Hire a qualified contractor to perform a detailed inspection of the domestic water piping, in use for an unknown amount of time, and replace any damaged piping.

System: D5010 - Electrical Service/Distribution



Location: electrical room

Distress: Beyond Service Life

Category: 3 - Operations / Maint.

Priority: 4 - Response Time (4-5 yrs)

Correction: Replace Service Transformer, Add Switchboard

Qty: 0.00

Unit of Measure: Ea.

Estimate: \$508,786.15

Assessor Name: System

Date Created: 01/05/2016

Notes: Install new Site electrical service 1500KVA, 480V, 3 Phase to feed the HVAC, lighting and receptacle loads.
Install a new 480V, 3 phase switchgear.
Install a new 120V/208V, 3 phase switchgear.

System: D5010 - Electrical Service/Distribution



Location: throughout the building

Distress: Beyond Service Life

Category: 3 - Operations / Maint.

Priority: 4 - Response Time (4-5 yrs)

Correction: Replace Panelboard - 225A

Qty: 0.00

Unit of Measure: Ea.

Estimate: \$310,888.65

Assessor Name: System

Date Created: 01/05/2016

Notes: Install new 120V panel-boards throughout the building for lighting, and receptacles loads.

System: D5030 - Communications and Security



Location: throughout the building

Distress: Beyond Service Life

Category: 3 - Operations / Maint.

Priority: 4 - Response Time (4-5 yrs)

Correction: Add/Replace Clock System or Components

Qty: 0.00

Unit of Measure: Ea.

Estimate: \$157,584.31

Assessor Name: System

Date Created: 01/06/2016

Notes: Install a new Clock System.

Note: A multiplier of 1.4 is used (instead of 1.0) to cover the additional installation costs.

System: D5030 - Communications and Security

This deficiency has no image.

Location: throughout the building

Distress: Health Hazard / Risk

Category: 1 - Health & Safety

Priority: 4 - Response Time (4-5 yrs)

Correction: Add/Replace Video Surveillance System

Qty: 1.00

Unit of Measure: Ea.

Estimate: \$97,960.91

Assessor Name: System

Date Created: 01/06/2016

Notes: Install a new security system with cameras and monitor (CCTV).

Note: There is no picture attached since presently school has no security cameras.

Priority 5 - Response Time (> 5 yrs):

System: B2020 - Exterior Windows



Location: Exterior

Distress: Energy Efficiency

Category: 4 - Capital Improvement

Priority: 5 - Response Time (> 5 yrs)

Correction: Remove and replace aluminum windows - pick the appropriate size and style and insert the number of units

Qty: 250.00

Unit of Measure: Ea.


Estimate: \$1,692,439.23

Assessor Name: System

Date Created: 01/07/2016

Notes: Replace all windows with double insulated units

System: C1010 - Partitions



Location: Interior

Distress: Inadequate

Category: 4 - Capital Improvement

Priority: 5 - Response Time (> 5 yrs)

Correction: Folding partition inoperable - remove and replace - select quality

Qty: 2,500.00

Unit of Measure: S.F.

Estimate: \$684,504.34

Assessor Name: System

Date Created: 01/07/2016

Notes: Replace sliding partitions with drywall partitions

System: C3030 - Ceiling Finishes



Location: Interior

Distress: Beyond Service Life

Category: 3 - Operations / Maint.

Priority: 5 - Response Time (> 5 yrs)

Correction: Re-paint ceilings - SF of ceilings

Qty: 43,700.00

Unit of Measure: S.F.

Estimate: \$209,193.12

Assessor Name: System

Date Created: 01/07/2016

Notes: Repair and repaint all ceilings

System: D3030 - Cooling Generating Systems



Location: Throughout building

Distress: Inadequate

Category: 4 - Capital Improvement

Priority: 5 - Response Time (> 5 yrs)

Correction: Install chilled water system with distribution piping and pumps. (+75KSF)

Qty: 57,500.00

Unit of Measure: S.F.

Estimate: \$919,356.92

Assessor Name: System

Date Created: 11/13/2015

Notes: Remove the window air conditioning units and install a 150 ton air-cooled chiller with chilled water distribution piping and pumps located in a mechanical room to supply more reliable air conditioning for the building with a much longer service life.

System: D3040 - Distribution Systems



Location: Classrooms

Distress: Building / MEP Codes

Category: 2 - Code Compliance

Priority: 5 - Response Time (> 5 yrs)

Correction: Provide classroom FC units and dedicated OA ventilation system. (20 clsrms)

Qty: 29.00

Unit of Measure: C

Estimate: \$2,408,768.64

Assessor Name: System

Date Created: 11/13/2015

Notes: Remove the existing cast iron and fin tube steam radiators and install units with hot and chilled water coils and integral heat exchangers to introduce outdoor air to the building.

System: D3040 - Distribution Systems



Location: Cafeteria

Distress: Building / MEP Codes

Category: 2 - Code Compliance

Priority: 5 - Response Time (> 5 yrs)

Correction: Install HVAC unit for Cafeteria (850 students).

Qty: 576.00

Unit of Measure: Pr.

Estimate: \$269,299.35

Assessor Name: System

Date Created: 11/13/2015

Notes: Provide ventilation for the Cafeteria by installing a constant volume air handling unit with distribution ductwork and registers.

System: D3040 - Distribution Systems

This deficiency has no image.

Location: Administration

Distress: Building / MEP Codes

Category: 2 - Code Compliance

Priority: 5 - Response Time (> 5 yrs)

Correction: Install HVAC unit for Administration (2000 students).

Qty: 576.00

Unit of Measure: Pr.

Estimate: \$249,306.40

Assessor Name: System

Date Created: 11/13/2015

Notes: Provide ventilation for the Administration offices by installing a fan coil air handling unit hung from the structure with outdoor air ducted to the unit from louvers in window openings.

System: D3040 - Distribution Systems



Location: Gymnasium

Distress: Building / MEP Codes

Category: 2 - Code Compliance

Priority: 5 - Response Time (> 5 yrs)

Correction: Install HVAC unit for Gymnasium (single station).

Qty: 4,000.00

Unit of Measure: Ea.

Estimate: \$205,537.03

Assessor Name: System

Date Created: 11/13/2015

Notes: Provide ventilation for the Gymnasium by installing a fan coil air handling unit hung from the structure with outdoor air ducted to the unit from louvers in the window openings.

System: D3060 - Controls & Instrumentation



Location: Throughout building

Distress: Energy Efficiency

Category: 4 - Capital Improvement

Priority: 5 - Response Time (> 5 yrs)

Correction: Replace pneumatic controls with DDC (75KSF)

Qty: 57,500.00

Unit of Measure: S.F.

Estimate: \$1,233,497.73

Assessor Name: System

Date Created: 11/13/2015

Notes: Replace the pneumatic controls for the HVAC systems with modern DDC modules, valves and actuators to improve reliability and energy efficiency. Provide a new building automation system (BAS) with communication interface to the preferred system in use throughout the District.

Equipment Inventory

The following table represents the inventory details of the inventory found in the building, which fall under the following subsystems:

Subsystem	Inventory	Qty	UoM	Location	Manufacturer	Model Number	Serial Number	Barcode	Life	Install Date	Next Renewal	Raw Cost	Inventory Cost
D2020 Domestic Water Distribution	Pump, pressure booster system, 5 HP pump, includes diaphragm tank, control and pressure switch	1.00	Ea.	Basement	Armstrong				25	1995	2020	\$10,972.50	\$12,069.75
D3020 Heat Generating Systems	Boiler, gas fired, natural or propane, cast iron, steam, gross output, 2675 MBH, includes standard controls and insulated jacket, packaged	3.00	Ea.	Boiler Room	HB Smith	Mills 350			35	1992	2027	\$50,376.70	\$166,243.11
D3020 Heat Generating Systems	Boiler, gas fired, natural or propane, cast iron, steam, gross output, 2675 MBH, includes standard controls and insulated jacket, packaged	3.00	Ea.	Boiler Room	HB Smith	Mills 350			35	1992	2027	\$50,376.70	\$166,243.11
D3020 Heat Generating Systems	Boiler, gas fired, natural or propane, cast iron, steam, gross output, 2675 MBH, includes standard controls and insulated jacket, packaged	3.00	Ea.	Boiler Room	HB Smith	Mills 350			35	1992	2027	\$50,376.70	\$166,243.11
D5010 Electrical Service/Distribution	Circuit breaker, 3 pole, 600 volt, 1200 amp, enclosed (NEMA 1)	1.00	Ea.	electrical room					30			\$13,662.00	\$15,028.20
D5010 Electrical Service/Distribution	Panelboards, 3 pole 3 wire, main circuit breaker, 240 V, 225 amp	1.00	Ea.	electrical room					30	1910	2047	\$3,105.00	\$3,415.50
												Total:	\$529,242.78

Executive Summary

Building condition is evaluated based on the functional systems and elements of a building and organized according to the UNIFORMAT II Elemental Classification. The grouping of these systems and elements and applying a current replacement value to them develops a representative building cost model. Cost Models are developed for similar building types and functions. Systems and their elements are evaluated based on their current replacement values, life cycles, installation dates and next renewal dates. Systems and their elements that are within their useful lives are further evaluated to identify current deficient conditions that may have a significant impact on a system's or element's remaining service life, and to determine if they are beyond their predicted expected life. The system's or element's current replacement value is based on RS Means Commercial Cost Data.

Following are the cost model's system details for this facility. The Replacement Value is the amount needed to replace the property of the same present value. The Current Repair Amount, also known as Condition Needs, represents the budgeted contractor installed costs plus owner's soft costs for the repair, replacement or renewal for a component or system level deficiency. It excludes contributing costs for other components or systems that might also be associated with the corrective actions due to packaging the work. Facility Condition Index (FCI) FCI is an industry-standard measurement of facility condition calculated as the ratio of the costs to correct a facility's deficiencies to the facility's Current Replacement Value. It ranges from 0% (new) to 100% (very poor). Condition Index (CI) is calculated as the sum of a renewable system's Remaining Service Life (RSL) divided by the sum of a system's Replacement Value (both values exclude soft-cost to simplify calculation updates) expressed as a percentage ranging from 100% (new) to 0% (expired).

Function:	
Gross Area (SF):	29,700
Year Built:	1910
Last Renovation:	
Replacement Value:	\$667,359
Repair Cost:	\$697,603.60
Total FCI:	104.53 %
Total RSLI:	106.01 %



Description:

Attributes:

General Attributes:

Bldg ID:	S738001	Site ID:	S738001
----------	---------	----------	---------

Condition Summary

The Table below shows the CI and FCI for each major building system shown at the UNIFORMAT classification Level II. Note that Systems with lower FCIs require less investment than systems with higher FCIs.

UNIFORMAT Classification	RSLI %	FCI %	Current Repair Cost
G20 - Site Improvements	105.79 %	99.36 %	\$491,650.12
G40 - Site Electrical Utilities	106.67 %	119.35 %	\$205,953.48
Totals:	106.01 %	104.53 %	\$697,603.60

Condition Detail

This section of the report contains results of the Facility Condition Assessment. The building is separated into system components based on UNIFORMAT II classification. The columns in the System Listing table below represent the following:

1. System Code: A code that identifies the system.
2. System Description: A brief description of a system present in the building.
3. Unit Price \$: The unit price of the system.
4. UoM: The unit of measure for of the system.
5. Qty: The quantity for the system
6. Life: anticipated service life for thesystem based on Building Owners and Managers Association (BOMA) recommendations.
7. Year Installed: The date of system installation.
8. Calc Next Renewal Year: The date of system expiration based on the life, NR stands for non renewable.
9. Next Renewal Year: The suggested system expiration date by the assessor based on visual inspection.
10. CI: The Condition Index of the system.
11. FCI: The Facility Condition Index of the system.
12. RSL: Remaining Service Life.
13. eCR: eCOMET Condition Rating (not used).
14. Deficiency \$: The financial investment to repair/replace system.

System Listing

The System Listing table below lists each of the systems organized by their UNIFORMAT II classification. The assessment team was tasked with recording the most recent replacement year of each system, determining the remaining service life based on the theoretical life, and evaluating the condition to confirm the forecast next replacement year. The system listing is the basis for all data contained in the Building Assessment Report.

Additionally, a condition rating (eCR) based on the following guidelines is provided as observed at the time of the assessment.

- Excellent (E) - No noticeable distress or damage. The entire system is free from observable defect.
- Very Good (VG) - Overall no serviceability reduction for the entire system. No degradation of critical components and minor distress and defect noticeable for some but not non critical components within the system.
- Good (G) - Slight or no serviceability reduction for the entire system. There may be noticeable defects for some non critical components and slight noticeable degradation of the critical components.
- Fair (F) - Overall serviceability is degraded but adequate. There may be moderate deterioration for very few of the critical components and few of the non critical components may have severe degradation.
- Marginal (MA) - Overall serviceability and reliability loss. Most if not all of the non critical components suffer from severe degradation and a few of the critical component may have severe degradation.
- Moderate (MO) - Overall a significant serviceability loss. Most if not all the components have severe degradation with the reminder of the component showing visible distress.
- Very Poor (VP) - Overall the system is barely functional. All of the components are severely degraded.
- Non-Functional (NF) - Overall the system does not function with all the components having no serviceability and suffer from severe degradation.

System Code	System Description	Unit Price \$	UoM	Qty	Life	Year Installed	Calc Next Renewal Year	Next Renewal Year	RSLI%	FCI%	RSL	eCR	Deficiency \$	Replacement Value \$
G2010	Roadways	\$11.52	S.F.		30				0.00 %	0.00 %				\$0
G2020	Parking Lots	\$8.50	S.F.		30				0.00 %	0.00 %				\$0
G2030	Pedestrian Paving	\$12.30	S.F.	29,700	40	1910	1950	2057	105.00 %	123.35 %	42		\$450,609.90	\$365,310
G2040	Site Development	\$4.36	S.F.	29,700	25	1990	2015	2042	108.00 %	31.69 %	27		\$41,040.22	\$129,492
G2050	Landscaping & Irrigation	\$4.36	S.F.		15				0.00 %	0.00 %				\$0
G4020	Site Lighting	\$4.84	S.F.	29,700	30	1910	1940	2047	106.67 %	99.98 %	32		\$143,724.13	\$143,748
G4030	Site Communications & Security	\$0.97	S.F.	29,700	30	1910	1940	2047	106.67 %	216.01 %	32		\$62,229.35	\$28,809
Total									106.01 %	104.53 %			\$697,603.60	\$667,359

System Notes

The facility description in the site executive summary contains an overview of each system. The notes listed below provide additional information on select systems found within the facility.

No data found for this asset

Renewal Schedule

eCOMET forecasts future Capital Renewal funding needed to address expiring systems based on the Next Renewal year found in the Cost Models. A 3% annual inflation factor is applied to the costs for systems expiring in future years. The table below reflects recommended Capital Renewal funding needs over the next 10 years. Note: Cells with a zero value indicate systems for which renewal is not scheduled in that year.


Inflation Rate: 3%

System	Current Deficiencies	2016	2017	2018	2019	2020	2021	2022	2023	2024	2025	Total
Total:	\$697,604	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$697,604
G - Building Sitework	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G20 - Site Improvements	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G2010 - Roadways	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G2020 - Parking Lots	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G2030 - Pedestrian Paving	\$450,610	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$450,610
G2040 - Site Development	\$41,040	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$41,040
G2050 - Landscaping & Irrigation	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G40 - Site Electrical Utilities	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G4020 - Site Lighting	\$143,724	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$143,724
G4030 - Site Communications & Security	\$62,229	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$62,229

* Indicates non-renewable system

Forecasted Sustainment Requirement

The following chart shows the current building deficiencies and forecasting sustainment requirements over the next ten years.




10 Year FCI Forecast by Investment Scenario

The chart below illustrates the effect of various investment levels on the building FCI for the next 10 years. The levels of investment shown below include:

- Current FCI: a variable investment amount based on renewing expired systems to maintain the current FCI for the building
- 2% Investment: an annual investment of 2% of the replacement value of the building, escalated for inflation
- 4% Investment: an annual investment of 4% of the replacement value of the building, escalated for inflation


Facility Investment vs. FCI Forecast



Year	Investment Amount Current FCI - 104.53%	2% Investment		4% Investment	
		Amount	FCI	Amount	FCI
2016	\$0	\$13,748.00	102.53 %	\$27,495.00	100.53 %
2017	\$778,801	\$14,160.00	210.53 %	\$28,320.00	206.53 %
2018	\$0	\$14,585.00	208.53 %	\$29,170.00	202.53 %
2019	\$0	\$15,022.00	206.53 %	\$30,045.00	198.53 %
2020	\$0	\$15,473.00	204.53 %	\$30,946.00	194.53 %
2021	\$0	\$15,937.00	202.53 %	\$31,874.00	190.53 %
2022	\$0	\$16,415.00	200.53 %	\$32,831.00	186.53 %
2023	\$0	\$16,908.00	198.53 %	\$33,816.00	182.53 %
2024	\$0	\$17,415.00	196.53 %	\$34,830.00	178.53 %
2025	\$0	\$17,937.00	194.53 %	\$35,875.00	174.53 %
Total:	\$778,801	\$157,600.00		\$315,202.00	

Deficiency Summary by System


Current deficiencies included assemblies that have reached or exceeded their design life or components of the assemblies that are in need of repair. Assemblies that have reached their design life are identified as current deficiencies and assigned the distress 'Beyond Useful Life'. The following chart lists all current deficiencies associated with this facility.



Budget Estimate Total: \$697,603.60

Deficiency Summary by Priority

The following chart shows the total repair costs broken down by priority. Assessors assigned deficiencies within eCOMET to one of the following priority categories:



Budget Estimate Total: \$697,603.60


Deficiency By Priority Investment Table

The table below shows the current investment cost grouped by deficiency priority and building system.

System Code	System Description	1 - Response Time (< 2 yr)	2 - Response Time (2-3 yrs)	3 - Response Time (3-4 yrs)	4 - Response Time (4-5 yrs)	5 - Response Time (> 5 yrs)	Total
G2030	Pedestrian Paving	\$0.00	\$0.00	\$0.00	\$38,972.72	\$411,637.18	\$450,609.90
G2040	Site Development	\$0.00	\$0.00	\$0.00	\$30,937.50	\$10,102.72	\$41,040.22
G4020	Site Lighting	\$0.00	\$0.00	\$143,724.13	\$0.00	\$0.00	\$143,724.13
G4030	Site Communications & Security	\$0.00	\$0.00	\$0.00	\$62,229.35	\$0.00	\$62,229.35
	Total:	\$0.00	\$0.00	\$143,724.13	\$132,139.57	\$421,739.90	\$697,603.60

Deficiency Summary by Category

The following chart shows the total repair costs broken down by deficiency categories. Assessors assigned deficiencies to one of the following categories:



Deficiency Details by Priority

The deficiency detail notes listed below provide additional information on identified deficiencies found within the facility.

Priority 3 - Response Time (3-4 yrs):

System: G4020 - Site Lighting



Location: Grounds

Distress: Inadequate

Category: 4 - Capital Improvement

Priority: 3 - Response Time (3-4 yrs)

Correction: Add Site Lighting - pole mounted - select the proper light and pole

Qty: 1.00

Unit of Measure: Ea.

Estimate: \$143,724.13

Assessor Name: Wlodek Pieczonka

Date Created: 01/06/2016

Notes: Install new site lighting for safety of the people and security of property.

Priority 4 - Response Time (4-5 yrs):

System: G2030 - Pedestrian Paving

This deficiency has no image.

Location: Grounds

Distress: Accessibility

Category: 2 - Code Compliance

Priority: 4 - Response Time (4-5 yrs)

Correction: Install an exterior ADA ramp - based on 5' wide by the linear foot - up to a 48" rise - per LF of ramp - figure 1 LF per inch of rise

Qty: 30.00

Unit of Measure: L.F.

Estimate: \$38,972.72

Assessor Name: Wlodek Pieczonka

Date Created: 01/08/2016

Notes: Provide ADA compliant ramp at one entrance (location TBD)

System: G2040 - Site Development



Location: Grounds

Distress: Damaged

Category: 3 - Operations / Maint.

Priority: 4 - Response Time (4-5 yrs)

Correction: Repair exterior brick retaining wall - per LF of wall - up to 4' tall

Qty: 60.00

Unit of Measure: L.F.

Estimate: \$30,937.50

Assessor Name: Wlodek Pieczonka

Date Created: 01/08/2016

Notes: Repair brick gate pylons

System: G4030 - Site Communications & Security



Location: Grounds

Distress: Inadequate

Category: 4 - Capital Improvement

Priority: 4 - Response Time (4-5 yrs)

Correction: Add Site Paging System

Qty: 0.00

Unit of Measure: Ea.

Estimate: \$62,229.35

Assessor Name: Wlodek Pieczonka

Date Created: 01/06/2016

Notes: Install new site paging on building exterior walls.

Priority 5 - Response Time (> 5 yrs):

System: G2030 - Pedestrian Paving



Location: Grounds

Distress: Beyond Service Life

Category: 3 - Operations / Maint.

Priority: 5 - Response Time (> 5 yrs)

Correction: Remove and replace concrete sidewalk or concrete paving - 4" concrete thickness

Qty: 28,620.00

Unit of Measure: S.F.

Estimate: \$411,637.18

Assessor Name: Wlodek Pieczonka

Date Created: 01/07/2016

Notes: Replace playground paving

System: G2040 - Site Development



Location: Grounds

Distress: Damaged

Category: 3 - Operations / Maint.

Priority: 5 - Response Time (> 5 yrs)

Correction: Remove and replace metal picket fence - input number of gates

Qty: 60.00

Unit of Measure: L.F.

Estimate: \$10,102.72

Assessor Name: Wlodek Pieczonka

Date Created: 01/08/2016

Notes: Replace damaged sections of picket fence

Equipment Inventory

The following table represents the inventory details of the inventory found in the building, which fall under the following subsystems:

No data found for this asset

Glossary

ABMA	American Boiler Manufacturers Association http://www.abma.com/
ACEEE	American Council for an Energy-Efficient Economy
ACGIH	American Council of Governmental and Industrial Hygienists
AEE	Association of Energy Engineers
AFD	Adjustable Frequency Drive
AFTC	After Tax Cash Flow
AGA	American Gas Association
AHU	Air Handling Unit
Amp	Ampere
ANSI	American National Standards Institute
ARI	Air Conditioning and Refrigeration Institute
ASD	Adjustable Speed Drive
ASHRAE	American Society of Heating Refrigerating and Air-Conditioning Engineers Inc.
ASME	American Society of Mechanical Engineers
Assessment	Visual survey of a facility to determine its condition. It involves looking at the age of systems reviewing information from local sources and visual evidence of potential problems to assign a condition rating. It does not include destructive testing of materials or testing of systems or equipment for functionality.
ATS	After Tax Savings
AW	Annual worth
BACNET	Building Automation Control Network
BAS	Building Automation System
BCR	Benefit Cost Ratio
BEP	Business Energy Professional (AEE)
BF	Ballast Factor
BHP	Boiler Horsepower (boilers)
BHP	Brake Horsepower (motors)
BLCC	Building Life Cycle Cost analysis program (FEMP)
BOCA	Building Officials and Code Administrators
BTCF	Before Tax Cash Flow

Site Assessment Report - S738001;McClure

BTS	Before Tax Savings
Btu	British thermal unit
Building Addition	An area space or component of a building added to a building after the original building's year built date.
CAA	Clean Air Act
CAAA-90	Clean Air Act Amendments of 1990
CABO	Council of American Building Officials
CAC	Conventional Air Conditioning
CADDET	Center for the Analysis and Dissemination of Demonstrated Energy Technologies
Calculated Next Renewal	The year a system or element would be expected to expire based solely on the date it was installed and the expected useful lifetime for that kind of system.
Capital Renewal	Capital renewal is condition work (excluding suitability and energy audit work) that includes the replacement of building systems or elements (as they become obsolete or beyond their useful life) not normally included in an annual operating budget. Calculated next renewal The year a system or element would be expected to expire based solely on the date it was installed and the expected useful lifetime for that kind of system. Next renewal The assessor adjusted expected useful life of a system or element based on on-site inspection.
CDD	Cooling Degree Days
CDGP	Certified Distributed Generation Professional
CEC	California Energy Commission
CEM	Certified Energy Manager
CEP	Certified Energy Procurement Professional
CFC	Chlorofluorocarbon
CFD	Cash Flow Diagram
CFL	Compact Fluorescent Light
CFM cfm	Cubic Feet per Minute
CHP	Combined Heat and Power (a.k.a. cogeneration)
CHW	Chilled Water
Condition	Condition refers to the state of physical fitness or readiness of a facility system or system element for its intended use.
COP	Coefficient of Performance
Cp	Heat Capacity of Material
CPUC	California Public Utility Commission
CRI	Color Rendering Index
CRT	Cathode Ray Tube VDT HMI

Site Assessment Report - S738001;McClure

CTC	Competitive Transition Charge
Cu	Coefficient of Utilization
Current Replacement Value (CRV)	CRV represents the hypothetical total cost of rebuilding or replacing an existing facility in current dollars to its optimal condition (excluding auxiliary facilities) under current codes and construction standards.
Cv	Value Coefficient
CWS	Chilled Water System
D d	Distance (usually feet)
DB	Dry Bulb
DCV	Demand Control Ventilation
DD	Degree Day
DDB	Double Declining Balance
DDC	Direct Digital Controls
Deferred maintenance	Deferred maintenance is condition work (excluding suitability and energy audit needs) deferred on a planned or unplanned basis to a future budget cycle or postponed until funds are available.
Deficiency	A deficiency is a repair item that is damaged missing inadequate or insufficient for an intended purpose.
Delta	Difference
Delta P	Pressure Difference
Delta T	Temperature Difference
DG	Distributed Generation
DOE	Department of Energy
DP	Dew Point
DR	Demand Response
DX	Direct Expansion Air Conditioner
EA	Energy Audit
EBITDA	Earnings before Interest Taxes Depreciation and Amortization
ECI	Energy Cost Index
ECM	Energy Conservation Measure
ECO	Energy Conservation Opportunity
ECPA	Energy Conservation and Production Act
ECR	Energy Conservation Recommendation
ECS	Energy Control System

Site Assessment Report - S738001;McClure

EER	Energy Efficiency Ratio
EERE	Energy Efficiency and Renewable Energy division of US DOE
EIA	Energy Information Agency
EIS	Energy Information System
EMCS	Energy Management Computer System
EMO	Energy Management Opportunity
EMP	Energy Management Project
EMR	Energy Management Recommendation
EMS	Energy Management System
Energy Utilization Index (EUI)	EUI is the measure of total energy consumed in the cooling or heating of a building in a period expressed as British thermal unit (BTU) per (cooled or heated) gross square foot.
EO	Executive Order
EPA	Environmental Protection Agency
EPACT	Energy Policy Act of 1992
EPCA	Energy Production and Conservation Act of 1975
EPRI	Electric Power Research Institute
EREN	Efficiency and Renewable Energy (Division of USDOE)
ERV	Energy Recovery Ventilator
ESCO	Energy Service Company
ESPC	Energy Savings Performance Contract
EUI	Energy Use Index
EWG	Exempt Wholesale Generators
Extended Facility Condition Index (EFCI)	EFCI is calculated as the condition needs for the current year plus facility system renewal needs going out to a set time in the future divided by Current Replacement Value.
f	Frequency
F	Fahrenheit
Facility	A facility refers to site(s) building(s) or building addition(s) or combinations thereof that provide a particular service.
Facility Condition Assessment (FCA)	FCA is a process for evaluating the condition of buildings and facilities for programming and budgetary purposes through an on site inspection and evaluation process.
Facility Condition Index (FCI)	FCI is an industry-standard measurement of a facility's condition that is the ratio of the cost to correct a facility's deficiencies to the Current Replacement Value of the facilities. The higher the FCI the poorer the condition of a facility. After an FCI is established for all buildings within a portfolio a building's condition can be ranked relative to other buildings. The FCI may also represent the condition of a portfolio based on the cumulative FCIs of the portfolio's facilities.

Site Assessment Report - S738001;McClure

FC	Footcandle
FCA	Fuel Cost Adjustment
FEMIA	Federal Energy Management Improvement Act of 1988
FEMP	Federal Energy Management Program
FERC	Federal Energy Regulatory Commission
FESR	Fuel Energy Savings Ratio
FLA	Full Load Amps
FLF	Facility Load Factor (usually monthly)
FLRPM	Full Load Revolutions per Minute
FMS	Facility Management System
FPM fpm	Feet per Minute (velocity)
FSEC	Florida Solar Energy Center
Ft	Foot
GPM gpm	Gallons per Minute
GRI	Gas Research Institute
Gross Square Feet (GSF)	The size of the enclosed floor space of a building in square feet measured to the outside face of the enclosing wall.
GUI	Graphical User Interface
H h	Enthalpy Btu/lb
HCFC	Hydrochlorofluorocarbons
HDD	Heating Degree days
HFC	Hydrofluorocarbons
HHV	Higher Heating Value
HID	High Intensity Discharge (lamp)
HMI	Human Machine Interface
HMMI	Human Man Machine Interface
HO	High Output (lamp)
HP Hp hp	Horsepower
HPS	High Pressure Sodium (lamp)
HR	Humidity Ratio
Hr hr	Hour

Site Assessment Report - S738001;McClure

HRU	Heat Recovery Unit
HVAC	Heating Ventilation and Air-Conditioning
Hz	Hertz
I	Intensity (lumen output of lamp)
I i	Interest rate or Discount rate
IAQ	Indoor Air Quality
ICA	International Cogeneration Alliance
ICBO	International Conference of Buildings Officials
ICC	International Code Council
ICP	Institutional Conservation Program
IECC	International Energy Conservation Code
IEEE	Institute of Electrical and Electronic Engineers
IESNA	Illuminating Engineering Society of North America
Install year	The year a building or system was built or the most recent major renovation date (where a minimum of 70 of the system's Current Replacement Value (CRV) was replaced).
IRP	Integrated Resource Planning
IRR	Internal Rate of Return
ISO	Independent System Operator
ITA	Independent Tariff Administrator
k	Kilo multiple of thousands in SI system
K	Kelvins (color temperature of lamp)
K k	Thermal Conductivity of Material
KVA	Kilovolt Ampere
KVAR	Kilovolt Ampere Reactive
kW	kiloWatt
kWh	kiloWatt hour
L	Length (usually feet)
LCC	Life Cycle Costing
LDC	Local Distribution Company
LEED	Leadership in Energy and Environmental Design
LEED EB	LEED for Existing Buildings

Site Assessment Report - S738001;McClure

LEED NC	LEED for new construction
LF	Load Factor
LHV	Lower Heating Value
Life cycle	The period of time that a building or site system or element can be expected to adequately serve its intended function.
LPS	Low Pressure Sodium (lamp)
Lu	Lumen Output of a Lamp or Fixture
M	Mega multiple of millions in SI system
M&V	Measurement and Verification
MACRS	Modified Accelerated Cost Recovery System
MARR	Minimum Attractive Rate of Return
Mbtu	Thousand Btu
MCF	Thousand Cubic Feet (usually of gas)
MEC	Model Energy Code
Mm	Multiple of Thousands in I/P System
MMBtu	Million Btu
MMCS	Maintenance Management Computer System
MMI	Man Machine Interface
MMS	Maintenance Management System
MSE 2000	Management System for Energy 2000 (ANSI Georgia Tech Univ)
MW	MegaWatt
MWH MWh	MegaWatt hour
NAAQS	National Ambient Air Quality Standards
NAESCO	National Association of Energy Service Companies
NAIMA	North American Insulation Manufacturers Association
NEA	National Energy Act of 1978
NECPA	National Energy Conservation Policy Act
NEMA	National Electrical Manufacturer's Association
NERC	North American Electric Reliability Council
Next Renewal	The Next Renewal date is an override of the 'Calculated Next Renewal' date and is based upon the assessor's visual inspection.

Site Assessment Report - S738001;McClure

NFPA	National Fire Protection Association
NGPA	National Gas Policy Act of 1978
NLRPM	No Load Revolutions per Minute (speed)
Nn	Equipment or Project lifetime in economic analysis
NOPR	Notice of Proposed Rule Making from FERC
NOx	Nitrogen Oxide Compounds
NPV	Net present value in economic analysis
NREL	National Renewable Energy Laboratory
NUG	Non-Utility Generator
O&M	Operation and Maintenance
OA	Outside Air
ODP	Ozone Depletion Potential
OPAC	Off-Peak Air Conditioning
P	Present value in economic analysis
PBR	Performance Based Rates
PEA	Preliminary Energy Audit
PF	Power Factor
PID	Proportional plus integral plus derivative (control system)
PM	Portfolio Manager in Energy Star rating system
PM	Preventive Maintenance
PoolCo	Power Pool Company or Organization
POU	Point of Use
PQ	Power Quality
PSC	Public Service Commission
PSIA psia	Pounds per square inch absolute (pressure)
PSIG psig	Pounds per square inch gauge (pressure)
PUC	Public Utility Commission
PUHCA	Public Utilities Holding Company Act of 1935
PURPA	Public Utilities Regulatory Policies of 1978
PV	Photovoltaic system

Site Assessment Report - S738001;McClure

PV	Present Value
PW	Present Worth
PX	Power Exchange
q	Rate of heat flow in Btu per hour
Q	Heat load due to conduction using degree days
QF	Qualifying Facility
R	Electrical resistance
R	Thermal Resistance
RC	Remote controller
RCR	Room Cavity Ratio
RCRA	Resource Conservation and Recovery Act
Remaining Service Life (RSL)	RSL is the number of years service remaining for a system or equipment item. It is automatically calculated based on the difference between the current year and the 'Calculated Next Renewal' date or the 'Next Renewal' date whichever one is the later date.
Remaining Service Life Index (RSLI)	RSLI is defined as a percentage ratio of the remaining service life of a system. It usually ranges from 0 to 100
REMR	Repair Evaluation Maintenance Rehabilitation (REMR) is a scale used to objectively rank systems based on their condition
Renewal Schedule	A timeline that provides the items that need repair the year in which the repair is needed and the estimated price of the renewal.
RH	Relative Humidity
RLA	Running Load Amps
RMS	Root Mean Square
RO	Reverse Osmosis
ROI	Return on Investment
RPM	Revolutions Per Minute
RTG	Regional Transmission Group
RTO	Regional Transmission Organization
RTP	Real Time Pricing
SBCCI	Southern Building Code Congress International
SC	Scheduling Coordinator
SC	Shading Coefficient
SCADA	Supervisory Control and Data Acquisition Systems

Site Assessment Report - S738001;McClure

SEER	Seasonal Energy Efficiency Ratio
SHR	Sensible Heat Ratio
Site	The grounds and utilities roadways landscaping fencing and other typical land improvements needed to support the facility.
Soft Cost	An expense item that is not considered direct construction cost. Soft cost includes architectural engineering financing legal fees and other pre-and-post construction expenses.
SOx	Sulfur Oxide Compounds
SP	Static Pressure
SP SPB	Simple Payback
SPP	Simple Payback Period
SPP	Small Power Producers
STR	Stack Temperature Rise
SV	Specific Volume
System	System refers to building and related site work elements as described by ASTM Uniformat II Classification for Building Elements (E1557-97) a format for classifying major facility elements common to most buildings. Elements usually perform a given function regardless of the design specification construction method or materials used. See also Uniformat II.
T	Temperature
T	Tubular (lamps)
TAA	Technical Assistance Audit
TCP/IP	Transmission Control Protocol/Internet Protocol
TES	Thermal Energy Storage
THD	Total Harmonic Distortion
TOD	Time of Day
TOU	Time of Use
TQM	Total Quality Management
TransCo	Transmission Company
U	Thermal Conductance
UDC	Utility Distribution Company
UL	Underwriters Laboratories
UNIFORMAT II	The ASTM UNIFORMAT II Classification for Building Elements (E1557-97) a format for classifying major facility components common to most buildings.
USGBC	US Green Building Council
v	Specific Volume

Site Assessment Report - S738001;McClure

V	Volts Voltage
V	Volume
VAV	Variable Air Volume
VDT	Video Display Terminal
VFD	Variable Frequency Drive
VHO	Very High Output
VSD	Variable Speed Drive
W	Watts
W	Width
WB	Wet bulb
WH Wh	Watt Hours
Year built	The year that a building or addition was originally built based on substantial completion or occupancy.
Z	Electrical Impedance