

Facility Condition Assessment Summary Report

This report provides a summary of the Facility Condition Index (FCI) value of a school facility and select major building systems. The FCI calculation represents the cost of needed repairs divided by the replacement value. The FCI is a numerical value of condition and helps to identify the need for renewal or replacement of specific parts of the facility. The FCI is particularly useful when comparing similar facilities within the same portfolio.

Moffet School

| | | | |
|------------|---|---------------------|--------------|
| Governance | DISTRICT | Report Type | Elementary |
| Address | 127 W. Oxford St. Philadelphia, Pa 19122 | Enrollment | 346 |
| Phone/Fax | 215-291-4721 / 215-291-5190 | Grade Range | '00-05' |
| Website | Www.Philasd.Org/Schools/Moffet | Admissions Category | Neighborhood |
| | | Turnaround Model | N/A |

Building/System FCI Tiers

| Facility Condition Index (FCI) = $\frac{\text{Cost of Assessed Deficiencies}}{\text{Replacement Value}}$ | | | | |
|--|-------------------------------|---|---|--|
| < 15% | 15 to 25% | 25 to 45% | 45 to 60% | > 60% |
| Buildings | | | | |
| Minimal Current Capital Funding Required | Refurbish Systems in building | Replace Systems in building. | Building should be considered for major renovation. | Building should be considered for closing/replacement. |
| Systems | | | | |
| Perform routine maintenance on system | System requires minor repairs | System should be studied to determine repair vs. replacement. | System is nearing end of its life expectancy and should be considered for replacement | System should be replaced as part of the Capital Program |

Building and Grounds

| | FCI | Repair Costs | Replacement Cost |
|----------------|---------------|---------------------|---------------------|
| Overall | 47.29% | \$10,264,764 | \$21,707,326 |
| Building | 45.74 % | \$9,312,367 | \$20,360,696 |
| Grounds | 70.72 % | \$952,397 | \$1,346,630 |

Major Building Systems

| Building System | System FCI | Repair Costs | Replacement Cost |
|--|------------|--------------|------------------|
| Roof (Shows physical condition of roof) | 89.52 % | \$938,532 | \$1,048,352 |
| Exterior Walls (Shows condition of the structural condition of the exterior facade) | 00.00 % | \$0 | \$1,476,400 |
| Windows (Shows functionality of exterior windows) | 130.04 % | \$936,839 | \$720,400 |
| Exterior Doors (Shows condition of exterior doors) | 60.24 % | \$34,936 | \$58,000 |
| Interior Doors (Classroom doors) | 09.80 % | \$13,766 | \$140,400 |
| Interior Walls (Paint and Finishes) | 00.00 % | \$0 | \$672,400 |
| Plumbing Fixtures | 11.21 % | \$60,634 | \$540,800 |
| Boilers | 140.62 % | \$1,050,122 | \$746,800 |
| Chillers/Cooling Towers | 69.34 % | \$678,976 | \$979,200 |
| Radiators/Unit Ventilators/HVAC | 152.91 % | \$2,629,506 | \$1,719,600 |
| Heating/Cooling Controls | 158.90 % | \$858,081 | \$540,000 |
| Electrical Service and Distribution | 00.00 % | \$0 | \$388,000 |
| Lighting | 40.94 % | \$567,931 | \$1,387,200 |
| Communications and Security (Cameras, Pa System and Fire Alarm) | 09.62 % | \$49,967 | \$519,600 |

Please note that some FCIs may be over 100% because there are times when replacing a building system requires that other building systems be upgraded to complete the installation. A FCI of 0.0% represents that there are no current deficiencies with the associated system.

School District of Philadelphia
S537001;Moffet
Final
Site Assessment Report

January 31, 2017



Table of Contents

| | |
|---|----|
| Site Executive Summary | 4 |
| Site Condition Summary | 10 |
| <u>B537001:Moffet</u> | 12 |
| Executive Summary | 12 |
| Condition Summary | 13 |
| Condition Detail | 14 |
| System Listing | 15 |
| System Notes | 17 |
| Renewal Schedule | 18 |
| Forecasted Sustainment Requirement | 21 |
| Condition Index Forecast by Investment Scenario | 22 |
| Deficiency Summary By System | 23 |
| Deficiency Summary By Priority | 24 |
| Deficiency By Priority Investment | 25 |
| Deficiency Summary By Category | 26 |
| Deficiency Details By Priority | 27 |
| Equipment Inventory Detail | 41 |
| <u>G537001:Grounds</u> | 42 |
| Executive Summary | 42 |
| Condition Summary | 43 |
| Condition Detail | 44 |
| System Listing | 45 |
| System Notes | 46 |
| Renewal Schedule | 47 |
| Forecasted Sustainment Requirement | 48 |
| Condition Index Forecast by Investment Scenario | 49 |
| Deficiency Summary By System | 50 |
| Deficiency Summary By Priority | 51 |
| Deficiency By Priority Investment | 52 |

Site Assessment Report

| | |
|--------------------------------|----|
| Deficiency Summary By Category | 53 |
| Deficiency Details By Priority | 54 |
| Equipment Inventory Detail | 57 |
| Glossary | 58 |

Site Executive Summary

The organization of this report, as displayed in the Table of Contents, follows the structure of the associated eCOMET database. The overall node for each school campus begins with the letter "S", which indicates the "Site" label. Each Site is comprised of separate "Building" and "Grounds" nodes; their asset names begin with the letters "B" and "G" respectively. Information rolls up to the Site node from the Building and Grounds nodes. This Site report combines facility information with subsections for the Buildings And Grounds nodes.

The basis for the evaluation of condition is the functional systems and elements of a building and grounds organized according to the UNIFORMAT II Elemental Classification. The grouping of these systems and elements and applying a current replacement value to them develops a representative building cost model. Cost Models are typically developed for similar building types and functions. Evaluation of systems and their elements takes into account their current replacement values, life cycles, installation dates and next renewal dates. Systems and their elements that are within their useful lives are further evaluated to identify current deficient conditions that may have a significant impact on a system's or element's remaining service life, and to determine if they are beyond their predicted expected life. The system's or element's current replacement value is based on RS Means Commercial Cost Data.

Following are the cost model's system details for this facility. The Replacement Value is the amount needed to replace the property of the same present value. The Current Repair Amount, also known as Condition Needs, represents the budgeted contractor installed costs plus owner's soft costs for the repair, replacement or renewal for a component or system level deficiency. It excludes contributing costs for other components or systems that might also be associated with the corrective actions due to packaging the work. Facility Condition Index (FCI) is an industry-standard measurement calculated as the ratio of the repair costs to correct a facility's deficiencies to the facility's Current Replacement Value. Condition Index (CI) for a system is calculated as the sum of the deficiencies divided by the sum of a system's Replacement Value (both values include soft-cost) expressed as a percentage ranging from 0% 100%.

| | |
|--------------------|-----------------|
| Gross Area (SF): | 40,000 |
| Year Built: | 1973 |
| Last Renovation: | |
| Replacement Value: | \$21,707,326 |
| Repair Cost: | \$10,264,764.05 |
| Total FCI: | 47.29 % |
| Total RSLI: | 82.13 % |



Description:

Facility Assessment, July 2015

School District of Philadelphia

Moffet School

127 W. Oxford St.

Philadelphia, PA 19122

40,000 SF / 417 Students / LN 03

The Morris Elementary school building is located at 127 W. Oxford St. in Philadelphia, PA. The 2 story with mechanical penthouse, approximately 40,000 square foot building was originally constructed in 1973.

Mr. Derek Parker, Facility Area Coordinator provided input to the Parsons assessment team on current problems and planned renovation projects. Mr. David Stone, building engineer, accompanied us on our tour of the school and provided limited information on

Site Assessment Report - S537001;Moffet

the building systems and recent maintenance history.

STRUCTURAL/ EXTERIOR CLOSURE:

The original building typically rests on concrete foundations and concrete bearing walls that are not showing signs of settlement. There are no signs of moisture penetration through foundation walls

The main structure consists typically of precast concrete columns, beams and double-T precast concrete floors. The roof structure consists of double-T precast slabs supported by precast superstructure. Some minor structural elements are cast-in-place concrete. The superstructure is in good condition.

The building envelope is typically face brick masonry with CMU backup. Precast concrete wall panels are accenting small windows. Mechanical penthouse is clad with prefinished, insulated metal panels with prefinished metal liners. There is no water penetration through walls.

The windows are original extruded aluminum double hung windows double glazed insulated glass and security screens. All windows are generally in good condition with some security screens damaged.

The exterior doors are typically hollow metal doors and frames, painted. The doors are generally in fair condition; no weather-stripping is installed. The loading dock is equipped with overhead roll-up, manually operated doors in fair condition.

Roofing system is a built-up system approximately 15 to 20 years old and in fair condition with external insulating panels above it (outsulation); all roofing and flashing is typically in fair condition with some deterioration of the built-up system and insulation panels; leaks have not been reported.

INTERIORS:

The building partition wall types include painted CMU. Partitions are generally in good condition.

Interior doors are generally solid core wood doors, some glazed, in hollow metal frames. The doors leading to exits and stairway are hollow metal doors and frames with wire glass vision panes, in good condition.

Fittings include toilet accessories and toilet partitions, generally in fair condition, no accessible compartments; chalkboards, in good condition. Handrails are generally in good condition. Built-in cabinets are steel, in good condition. Interior identifying signage is typically directly painted on wall or door surfaces generally in good condition.

The interior wall finishes are mostly painted CMU. Generally, paint is in good condition throughout the building.

Most ceilings in the original building are 2x4 suspended acoustical panels in fair condition. The suspension system and tiles are approaching the end of their useful life. Auditorium is equipped with suspended acoustical baffles in good condition.

Flooring in most spaces is VCT in good condition; and ceramic tile with glazed CMU base in toilets. Most flooring is in fair to good condition. Library and principal's office has carpet in good condition.

Stair construction is generally steel stringers and risers with steel pan concrete treads. Treads are fitted with extruded aluminum non-slip nosings. Stairs are generally in good condition.

Institutional and Commercial equipment includes stage equipment, generally in good condition; A/V equipment in very good condition; gym equipment – basketball backstops, scoreboards, etc.; generally in fair condition. Other equipment includes kitchen equipment, generally in good condition. Vehicular equipment includes loading dock bumpers, severely damaged.

Furnishings include fixed casework in classrooms, corridors and library, generally in fair to good condition; window shades/blinds, generally in good condition; fixed auditorium seating is original, generally in fair condition.

CONVEYING SYSTEMS:

The building has a 2,500 lb hydraulic elevator serving two floors and the penthouse; generally in good condition.

Site Assessment Report - S537001;Moffet

PLUMBING:

Plumbing Fixtures - Many of the original plumbing fixtures remain in service. Fixtures in the restrooms on each floor consist of both floor and wall mounted flush valve water closets, wall hung urinals and lavatories with wheel handle faucets. The units appear to be in good condition and should be provide reliable service for the next 5-10 years.

Drinking fountains in the corridors and at the restrooms consist of wall hung fixtures with integral refrigerated coolers or wall hung porcelain fixtures. Both types are well beyond their service life and should be replaced; most are NOT accessible type.

A service sink is available in a janitor closet in the corridor on each floor for use by the janitorial staff.

Domestic Water Distribution - A 5" city water service enters the building from W. Oxford Street near the intersection with N. Mascher Street. The 4" meter and valves are located in the elevator machine room. The original domestic hot and cold water distribution piping with copper piping and sweat fittings is still in service. The maintenance staff reports no significant problems with scale build up in the domestic piping and the supply is adequate to the fixtures.

Domestic hot water is produced via a steam to water heat exchanger in a vertical hot water storage tank. This system requires at least one boiler to be running for the building to have hot water. The tank and heat exchanger are most likely original to the building and beyond their service life. This system is inefficient, requiring the boilers to be run in the summer when they could be shut down. A new gas fired domestic hot water system with circulating pump should be installed to eliminate dependence on the boiler. A water softener located in the boiler room supplies conditioned water to the boilers.

Sanitary Waste - The original storm and sanitary sewer piping is heavy weight cast iron with hub and spigot fittings. Downspouts from the roof run down the interior of the building and connect to the storm sewer system below the building slab.

A small sewage ejector pit located in the elevator machine room receives water from three floor drains in that area. It has a single pump that has been in use for an unknown amount of time, but may be reaching the end of its service life.

The maintenance staff reported mostly minor problems with the sanitary waste piping systems. However, the sewer piping has been in service for nearly 45 years and will require more frequent attention from the maintenance staff as time passes. The District should hire a qualified contractor to examine the sanitary waste piping using video cameras to locate and replace any damaged piping and to further quantify the extent of potential failures.

Energy Supply - A 3" city gas service enters the building from W. Oxford Street near the intersection with N. Mascher Street. The meter is 2" and located in the in the elevator machine room.

A reserve oil supply is stored in a 12,000 gallon underground storage tank (UST). Oil is used as a backup fuel and the District receives credit from the gas utility as an interruptible service. The current supply has been in storage for some time and should be tested for quality on a regular schedule. USTs have an anticipated service life of 20 years.

MECHANICAL:

Heat Generating Systems - Low pressure steam is generated by two Weil-McLain cast iron sectional boilers original to the building, located in the penthouse boiler room. Each boiler is equipped with what looks like the original burner, designed to operate on natural gas or fuel oil. Combustion air makeup is supplied by louvers equipped with motorized dampers. Burner oil pumps are connected and driven by the fan motor, which is not allowed by current code. The gas train serving the building does not appear to have code required venting of the regulators and dual solenoid valves with venting of the chamber between. The Building Engineer reports the system loses a significant amount of condensate due to failed traps, which is made up with chemically treated city water. Cast iron sectional boilers have an anticipated service life of 35 years or more; these units have been in service approximately 45 years. The boilers appear to have been poorly maintained. The District should replace these boilers within the next 1-3 years.

One condensate receiver is installed in the elevator machine room to return condensate to the boiler room. Another condensate receiver is installed in the boiler room. The boiler feed pump and tank assembly is installed in the boiler room. Live steam passes into the condensate piping system from the failed traps and then vents from the condensate handling equipment when the system is run above 5 lbs/sq. in. The District has not conducted a steam trap survey for this building and traps are not serviced on a regular schedule.

Cooling Generating Systems - Chilled water is generated by one absorption chiller located in the boiler room with heat rejected by one Havens M46-200 galvanized cooling tower located on the roof. The manufacturer and model number were not visible on the chiller.

Site Assessment Report - S537001;Moffet

Absorption chillers have an anticipated service life of 30 years; this unit has been in service approximately 45 years and needs to be replaced. The building engineer reported an air leak in the chiller which requires the continuous running of a vacuum pump to keep the chiller operational. Galvanized cooling tower have an anticipated service life of 18 years; this unit has been in service approximately 45 years. The existing absorption chiller and cooling tower are beyond their service life and should be replaced with a new packaged roof top mounted air cooled chiller fitted with modern controls.

Distribution Systems - Steam piping is black steel (ASTM A53) with welded fittings. The condensate piping is Schedule 80 black steel with threaded fittings. Steam and condensate piping mains are located in the penthouse boiler room. The steam distribution piping is all located in the boiler room and has been in use beyond its service life and will require more frequent attention from the maintenance staff to address pipe/valve failures as time passes. The District should hire a qualified contractor to examine the steam and condensate piping and perform additional testing to locate and replace any damaged piping and to further quantify the extent of potential failures. The District should budget for replacing this piping over the next 10 years.

A two pipe distribution system supplies building heating or cooling water to the unit ventilators and two air handling units (AHU). There are two primary loop water pumps which can serve either the boilers or the chiller depending on valve configuration. There are two secondary loop water pumps which serve the hot/cold water distribution network. Two condenser water pumps serve the cooling tower and absorption chiller. All pumps appear to be original to the building, are beyond the anticipated service life of 25 years, and should be replaced.

Unit ventilators provide heating and cooling for the majority of classrooms, offices, and indirectly to the hallways. The unit ventilators are original to the building and are beyond their service life. Outdoor air for the building is provided by wall openings in the unit ventilators, which may not be sufficient to meet current codes for outdoor air ventilation. The existing unit ventilators should be removed and new units installed.

Two Trane Climate Changer air handling units located in the boiler room and original to the building provide conditioned air to the Auditorium and Gymnasium. The Auditorium AHU provides heating and cooling. The Gymnasium AHU only provides heating. These AHUs are beyond their service life and should be replaced with more efficient modern units. Fraying asbestos insulation covers the piping for the units and should be abated immediately.

Terminal & Package Units - The school has mechanical ventilation via exhaust fans which exhaust air from the plenum above the drop ceiling. Eight (8) exhaust fans are located on the penthouse roof and six (6) fans located on the main roof. No major issues reported with the exhaust fans.

There is one Mitsubishi split system that serves the computer room. This appears to be installed within the last 5 years and should not need replacement within the next 10 years.

Controls & Instrumentation - The original pneumatic systems still provide basic control functions. Pneumatic room thermostats are intended to control the dual system unit ventilator control valves. Several rooms have digital thermostats connected to unit ventilators. In reality the ventilator control valves are wide open and heating and cooling control is achieved via the boilers or chiller. Pneumatic control air is supplied from a duplex Robertshaw compressor and Hankison air dryer located in the boiler room. The maintenance staff reports problems with oil being sprayed into the pneumatic copper tubing. The pneumatic systems are beyond their service life and require too much attention from the maintenance staff. The original control valves and pneumatic actuators are beyond their service life and should be rebuilt or replaced. These controls should be converted to DDC.

A new building automation system (BAS) with modern DDC modules and communications network should be installed to serve the HVAC systems in this building to improve reliability and energy efficiency. An interface should be provided with the preferred system in use throughout the District.

Sprinklers - The school building is NOT covered by an automatic sprinkler system. Installing a sprinkler system with quick response type heads should reduce insurance costs by providing protection for the property investment. A fire pump may be required depending on the available city water pressure.

ELECTRICAL:

Electrical Service- The electrical service is fed from an underground distribution system along W Oxford St. The service enters the building underground then rises up to the penthouse to a 500 kVA, 13200V:480/277V substation. The substation is equipped with a 600A load interrupter switch. After the medium voltage transformer, the substation contains a 480V 800A distribution section, followed by a 480:208/120V 225 kVA step down transformer, then a 208/120V 800A distribution section. The substation is original to the building, and was manufactured by Federal Pacific which no longer exists. The substation should be replaced.

Site Assessment Report - S537001;Moffet

Distribution System and Raceway System - The main distribution panel is rated 1600A, and is attached to the end of the substation. Electrical panels located on each floor are fed from this main distribution panel, and provides power to the receptacles and lighting on each floor. The second and third floor contains a panel to provide power to the unit ventilators located in the classrooms.

Receptacles - Classrooms are typically supplied with 4 duplex receptacles. One additional receptacle should be added to each wall in these classrooms.

Lighting- Most of the building is outfitted with fluorescent fixtures with T-12 lamps, the auditorium contains compact fluorescent screw in type fixtures, while the gymnasium has 15 mercury vapor lamps. Classroom are fitted with either suspended indirect linear fixtures, or 2X4-4 lamp fixtures. Classroom lighting is typically controlled by inboard/outboard switching. Corridors are illuminated by 1X4-2 lamp surface mounted fixtures in some areas, and 2X4-4 lamp lay in fixtures in other areas. The administrative areas use 2X4-4 lamp lay in type fixtures. Lighting levels in the classroom areas were found to be in the 15-20 fc range in the rooms with the indirect lighting. This does not meet IES (Illuminating Engineering Society) recommended levels of 50 fc. The gym lighting level was found acceptable at 50 fc. Media center lighting levels were found to be in the 20-30 fc range, which is below recommended levels. Administrative area lighting is acceptable. Corridor lighting was found acceptable at 15 fc. It is recommended to upgrade the lighting throughout the facility.

Fire Alarm System – The school has a Simplex 4005 fire alarm system. The system consists of pull stations and bells with strobes located in the corridors only. There are no devices in classrooms, gymnasium, or auditorium. Administrative area contains an audible device. It is recommended to upgrade the fire alarm system to provide adequate visual coverage throughout the school.

Telephone/LAN – The present telephone/LAN system is adequate.

Public Address/Intercom/Paging – An independent and separate PA system does not exist. School uses the telephone system for public announcement. Two way communication is not available through the public announcement system. Communication back to the office is through a wall mounted phone located in each classroom. This system is adequate and in working condition. Classrooms and corridors contain ceiling mounted speakers where a drop ceiling exists, and wall mounted speakers otherwise.

Clock and Program System – The present bell system is adequate. There is no clock system for classrooms.

Television System – The facility is equipped with TV coax system, however there presently are no televisions in the classrooms.

Security System – There facility is equipped with door contacts on exterior doors. There are also motion sensors in the first floor corridors.

Emergency Power System – A 30kW natural gas Onan generator is housed in the basement of the school for emergency lighting. The generator is not currently adequate for the facility as it does not provide emergency power to the elevator.

Emergency Lighting System / Exit Lighting - The emergency lighting is provided by select fluorescent fixtures that are connected to the generator. This lighting is not adequate and needs to be upgraded. The exit lighting is adequate.

Lightning Protection System- A lightning protection system does not exist.

Site Lighting - Site lighting is provided by building mounted flood lights installed around the entire perimeter of the school. The site lighting provides an adequate amount of lighting.

Video Surveillance – There are exterior cameras and cameras covering entrances, first floor lobby, and main office.

Site Paging – There are no exterior speakers for site paging.

Elevators – There is one passenger elevator in the facility. The elevator is a hydraulic type with a 2,500 pound capacity. The elevator hydraulic pump is rated 25 hp, 460V. Elevator is not on emergency generator.

GROUNDS (SITE):

There is no parking lot at the site. Playground pavement adjacent to the building is in poor condition, paving is cracked and deteriorated; playground equipment is in fair condition. Perimeter fence separating the playground from the street is partially metal picket fence good condition, and partially chain link fence in, generally in poor condition and rusting. Landscaping is generally in fair condition.

Site Assessment Report - S537001;Moffet

ACCESSIBILITY:

Generally, the building has an accessible route per ADA requirements. However, toilets are not equipped with accessible fixtures, and accessories, such as grab bars, and accessible partitions. None of the doors in the building have ADA required door handles.

RECOMMENDATIONS:

- Install all new roofing system including insulation within next 5 to 10 years; tear-down existing roofing; install flashing, and counter flashing
- Replace all windows within next 5 to 10 years including security screens
- Install weather-stripping on all exterior doors
- Replace interior doors hardware for ADA accessibility
- Reconfigure toilets for accessibility, provide new toilet partitions
- Replace existing carpet
- Replace all suspended acoustical ceilings
- Replace loading dock bumpers
- Resurface playground paving.
- Replace loading dock area pavement (heavy vehicular traffic)
- Replace original chain link fence and security gate
- Replace the wall hung drinking fountains and integral refrigerated coolers in the corridors and at the restrooms. These units are well beyond their service life and most are NOT accessible type.
- Install three new gas fired instant hot water heaters with circulating pump.
- Replace existing sewage ejector pump system and piping in the sub-basement as it is approaching the end of its useful service life.
- Hire a qualified contractor to perform a detailed examination of the sanitary waste piping using visual inspection and video cameras to locate and replace any damaged piping and to further quantify the extent of potential failures.
- Replace the two existing cast iron sectional boilers and burners with new cast iron sectional boilers of similar size, burners, and power ventilators.
- Hire a qualified contractor to examine the steam and condensate piping, in service for nearly 45 years, and perform additional testing to locate and replace any damaged piping and to further quantify the extent of potential failures.
- Replace the existing absorption chiller and cooling tower with a new packaged roof top mounted air cooled chiller fitted with modern controls. All associated piping and pumping systems should also be replaced.
- Replace building water distribution system in the boiler room with new primary and secondary loop pumps, piping, and controls.
- Replace the existing unit ventilators with two pipe units that have integral heat exchangers to introduce outdoor air to the building.
- Replace the two Trane Climate Changer air handling units serving the Auditorium and gymnasium by installing two new air handling units with outdoor air ducted to the units from louvers in the boiler room.
- Replace the pneumatic controls for the HVAC systems with modern DDC modules, valves and actuators to improve reliability and energy efficiency. Provide a new building automation system (BAS) with communication interface to the preferred system in use throughout the District.
- Install a fire protection sprinkler system with quick response type heads to reduce insurance costs by providing protection for the property. A fire pump may be required depending on the available city water pressure
- Install minimum one receptacle on each wall of classrooms and other purpose rooms.
- Replace existing T12 fixtures with T8 fixtures.
- Install a new addressable fire alarm system and provide audible and/or visual devices in all areas.
- Replace existing generator with larger generator sized to operate the elevator.

Attributes:

General Attributes:

| | | | |
|----------|-----------------|--------------|--------------|
| Active: | Open | Bldg Lot Tm: | Lot 1 / Tm 4 |
| Status: | Accepted by SDP | Team: | Tm 4 |
| Site ID: | S537001 | | |

Site Condition Summary

The Table below shows the CI and FCI for each major system shown at the UNIFORMAT classification Level II. Note that Systems with lower FCIs require less investment than systems with higher FCIs.

Current Investment Requirement and Condition by Uniformat Classification

| UNIFORMAT Classification | RSLI% | FCI % | Current Repair |
|---------------------------------|----------------|----------------|------------------------|
| A10 - Foundations | 58.00 % | 0.00 % | \$0.00 |
| A20 - Basement Construction | 58.00 % | 0.00 % | \$0.00 |
| B10 - Superstructure | 58.00 % | 0.00 % | \$0.00 |
| B20 - Exterior Enclosure | 74.30 % | 43.10 % | \$971,775.79 |
| B30 - Roofing | 109.75 % | 89.52 % | \$938,531.72 |
| C10 - Interior Construction | 70.70 % | 6.70 % | \$65,732.86 |
| C20 - Stairs | 58.00 % | 0.00 % | \$0.00 |
| C30 - Interior Finishes | 96.17 % | 23.14 % | \$444,726.37 |
| D10 - Conveying | 105.71 % | 0.00 % | \$0.00 |
| D20 - Plumbing | 45.03 % | 44.19 % | \$360,970.03 |
| D30 - HVAC | 101.17 % | 117.24 % | \$5,216,685.07 |
| D40 - Fire Protection | 96.05 % | 177.49 % | \$572,219.29 |
| D50 - Electrical | 99.79 % | 31.38 % | \$737,915.70 |
| E10 - Equipment | 105.71 % | 0.60 % | \$3,810.26 |
| E20 - Furnishings | 105.00 % | 0.00 % | \$0.00 |
| G20 - Site Improvements | 75.45 % | 90.86 % | \$952,396.96 |
| G40 - Site Electrical Utilities | 55.90 % | 0.00 % | \$0.00 |
| Totals: | 82.13 % | 47.29 % | \$10,264,764.05 |

Condition Deficiency Priority

| Facility Name | Gross Area (S.F.) | FCI % | 1 - Response Time (< 2 yr) | 2 - Response Time (2-3 yrs) | 3 - Response Time (3-4 yrs) | 4 - Response Time (4-5 yrs) | 5 - Response Time (> 5 yrs) |
|-----------------|-------------------|--------------|----------------------------|-----------------------------|-----------------------------|-----------------------------|-----------------------------|
| B537001;Moffet | 40,000 | 45.74 | \$572,219.29 | \$1,732,908.23 | \$2,811,744.94 | \$1,978,266.03 | \$2,217,228.60 |
| G537001;Grounds | 68,600 | 70.72 | \$0.00 | \$0.00 | \$210,463.08 | \$16,798.17 | \$725,135.71 |
| Total: | | 47.29 | \$572,219.29 | \$1,732,908.23 | \$3,022,208.02 | \$1,995,064.20 | \$2,942,364.31 |

Deficiencies By Priority



- 1 - Response Time (< 2 yr) - \$572,219.29
- 2 - Response Time (2-3 yrs) - \$1,732,908.23
- 3 - Response Time (3-4 yrs) - \$3,022,208.02
- 4 - Response Time (4-5 yrs) - \$1,995,064.20
- 5 - Response Time (> 5 yrs) - \$2,942,364.31

Budget Estimate Total: \$10,264,764.05

Executive Summary

Building condition is evaluated based on the functional systems and elements of a building and organized according to the UNIFORMAT II Elemental Classification. The grouping of these systems and elements and applying a current replacement value to them develops a representative building cost model. Cost Models are developed for similar building types and functions. Systems and their elements are evaluated based on their current replacement values, life cycles, installation dates and next renewal dates. Systems and their elements that are within their useful lives are further evaluated to identify current deficient conditions that may have a significant impact on a system's or element's remaining service life, and to determine if they are beyond their predicted expected life. The system's or element's current replacement value is based on RS Means Commercial Cost Data.

Following are the cost model's system details for this facility. The Replacement Value is the amount needed to replace the property of the same present value. The Current Repair Amount, also known as Condition Needs, represents the budgeted contractor installed costs plus owner's soft costs for the repair, replacement or renewal for a component or system level deficiency. It excludes contributing costs for other components or systems that might also be associated with the corrective actions due to packaging the work. Facility Condition Index (FCI) FCI is an industry-standard measurement of facility condition calculated as the ratio of the costs to correct a facility's deficiencies to the facility's Current Replacement Value. It ranges from 0% (new) to 100% (very poor). Condition Index (CI) is calculated as the sum of a renewable system's Remaining Service Life (RSL) divided by the sum of a system's Replacement Value (both values exclude soft-cost to simplify calculation updates) expressed as a percentage ranging from 100% (new) to 0% (expired).

| | |
|--------------------|-------------------|
| Function: | Elementary School |
| Gross Area (SF): | 40,000 |
| Year Built: | 1973 |
| Last Renovation: | |
| Replacement Value: | \$20,360,696 |
| Repair Cost: | \$9,312,367.09 |
| Total FCI: | 45.74 % |
| Total RSLI: | 82.86 % |

Description:

Attributes:

General Attributes:

| | | | |
|-----------------|---------|----------|-----------------|
| Active: | Open | Bldg ID: | B537001 |
| Sewage Ejector: | Yes | Status: | Accepted by SDP |
| Site ID: | S537001 | | |

Condition Summary

The Table below shows the CI and FCI for each major building system shown at the UNIFORMAT classification Level II. Note that Systems with lower FCIs require less investment than systems with higher FCIs.

| UNIFORMAT Classification | RSLI % | FCI % | Current Repair Cost |
|-----------------------------|----------------|----------------|-----------------------|
| A10 - Foundations | 58.00 % | 0.00 % | \$0.00 |
| A20 - Basement Construction | 58.00 % | 0.00 % | \$0.00 |
| B10 - Superstructure | 58.00 % | 0.00 % | \$0.00 |
| B20 - Exterior Enclosure | 74.30 % | 43.10 % | \$971,775.79 |
| B30 - Roofing | 109.75 % | 89.52 % | \$938,531.72 |
| C10 - Interior Construction | 70.70 % | 6.70 % | \$65,732.86 |
| C20 - Stairs | 58.00 % | 0.00 % | \$0.00 |
| C30 - Interior Finishes | 96.17 % | 23.14 % | \$444,726.37 |
| D10 - Conveying | 105.71 % | 0.00 % | \$0.00 |
| D20 - Plumbing | 45.03 % | 44.19 % | \$360,970.03 |
| D30 - HVAC | 101.17 % | 117.24 % | \$5,216,685.07 |
| D40 - Fire Protection | 96.05 % | 177.49 % | \$572,219.29 |
| D50 - Electrical | 99.79 % | 31.38 % | \$737,915.70 |
| E10 - Equipment | 105.71 % | 0.60 % | \$3,810.26 |
| E20 - Furnishings | 105.00 % | 0.00 % | \$0.00 |
| Totals: | 82.86 % | 45.74 % | \$9,312,367.09 |

Condition Detail

This section of the report contains results of the Facility Condition Assessment. The building is separated into system components based on UNIFORMAT II classification. The columns in the System Listing table below represent the following:

1. System Code: A code that identifies the system.
2. System Description: A brief description of a system present in the building.
3. Unit Price \$: The unit price of the system.
4. UoM: The unit of measure for of the system.
5. Qty: The quantity for the system
6. Life: anticipated service life for thesystem based on Building Owners and Managers Association (BOMA) recommendations.
7. Year Installed: The date of system installation.
8. Calc Next Renewal Year: The date of system expiration based on the life, NR stands for non renewable.
9. Next Renewal Year: The suggested system expiration date by the assessor based on visual inspection.
10. CI: The Condition Index of the system.
11. FCI: The Facility Condition Index of the system.
12. RSL: Remaining Service Life.
13. eCR: eCOMET Condition Rating (not used).
14. Deficiency \$: The financial investment to repair/replace system.

System Listing

The System Listing table below lists each of the systems organized by their UNIFORMAT II classification. The assessment team was tasked with recording the most recent replacement year of each system, determining the remaining service life based on the theoretical life, and evaluating the condition to confirm the forecast next replacement year. The system listing is the basis for all data contained in the Building Assessment Report.

Additionally, a condition rating (eCR) based on the following guidelines is provided as observed at the time of the assessment.

- Excellent (E) - No noticeable distress or damage. The entire system is free from observable defect.
- Very Good (VG) - Overall no serviceability reduction for the entire system. No degradation of critical components and minor distress and defect noticeable for some but not non critical components within the system.
- Good (G) - Slight or no serviceability reduction for the entire system. There may be noticeable defects for some non critical components and slight noticeable degradation of the critical components.
- Fair (F) - Overall serviceability is degraded but adequate. There may be moderate deterioration for very few of the critical components and few of the non critical components may have severe degradation.
- Marginal (MA) - Overall serviceability and reliability loss. Most if not all of the non critical components suffer from severe degradation and a few of the critical component may have severe degradation.
- Moderate (MO) - Overall a significant serviceability loss. Most if not all the components have severe degradation with the reminder of the component showing visible distress.
- Very Poor (VP) - Overall the system is barely functional. All of the components are severely degraded.
- Non-Functional (NF) - Overall the system does not function with all the components having no serviceability and suffer from severe degradation.

| System Code | System Description | Unit Price \$ | UoM | Qty | Life | Year Installed | Calc Next Renewal Year | Next Renewal Year | RSLI% | FCI% | RSL | eCR | Deficiency \$ | Replacement Value \$ |
|-------------|-------------------------|---------------|------|--------|------|----------------|------------------------|-------------------|----------|----------|-----|-----|---------------|----------------------|
| A1010 | Standard Foundations | \$18.40 | S.F. | 40,000 | 100 | 1973 | 2073 | | 58.00 % | 0.00 % | 58 | | | \$736,000 |
| A1030 | Slab on Grade | \$7.73 | S.F. | 40,000 | 100 | 1973 | 2073 | | 58.00 % | 0.00 % | 58 | | | \$309,200 |
| A2010 | Basement Excavation | \$6.55 | S.F. | 40,000 | 100 | 1973 | 2073 | | 58.00 % | 0.00 % | 58 | | | \$262,000 |
| A2020 | Basement Walls | \$12.70 | S.F. | 40,000 | 100 | 1973 | 2073 | | 58.00 % | 0.00 % | 58 | | | \$508,000 |
| B1010 | Floor Construction | \$75.10 | S.F. | 40,000 | 100 | 1973 | 2073 | | 58.00 % | 0.00 % | 58 | | | \$3,004,000 |
| B1020 | Roof Construction | \$13.88 | S.F. | 40,000 | 100 | 1973 | 2073 | | 58.00 % | 0.00 % | 58 | | | \$555,200 |
| B2010 | Exterior Walls | \$36.91 | S.F. | 40,000 | 100 | 1973 | 2073 | | 58.00 % | 0.00 % | 58 | | | \$1,476,400 |
| B2020 | Exterior Windows | \$18.01 | S.F. | 40,000 | 40 | 1973 | 2013 | 2057 | 105.00 % | 130.04 % | 42 | | \$936,839.39 | \$720,400 |
| B2030 | Exterior Doors | \$1.45 | S.F. | 40,000 | 25 | 1973 | 1998 | 2042 | 108.00 % | 60.24 % | 27 | | \$34,936.40 | \$58,000 |
| B3010105 | Built-Up | \$37.76 | S.F. | 27,700 | 20 | 1973 | 1993 | 2037 | 110.00 % | 89.73 % | 22 | | \$938,531.72 | \$1,045,952 |
| B3010120 | Single Ply Membrane | \$38.73 | S.F. | | 20 | | | | 0.00 % | 0.00 % | | | | \$0 |
| B3010130 | Preformed Metal Roofing | \$54.22 | S.F. | | 30 | | | | 0.00 % | 0.00 % | | | | \$0 |
| B3010140 | Shingle & Tile | \$38.73 | S.F. | | 25 | | | | 0.00 % | 0.00 % | | | | \$0 |
| B3020 | Roof Openings | \$0.06 | S.F. | 40,000 | 20 | | | | 0.00 % | 0.00 % | | | | \$2,400 |
| C1010 | Partitions | \$17.91 | S.F. | 40,000 | 100 | 1973 | 2073 | | 58.00 % | 0.00 % | 58 | | | \$716,400 |
| C1020 | Interior Doors | \$3.51 | S.F. | 40,000 | 40 | 1973 | 2013 | 2057 | 105.00 % | 9.80 % | 42 | | \$13,766.19 | \$140,400 |
| C1030 | Fittings | \$3.12 | S.F. | 40,000 | 40 | 1973 | 2013 | 2057 | 105.00 % | 41.64 % | 42 | | \$51,966.67 | \$124,800 |
| C2010 | Stair Construction | \$1.41 | S.F. | 40,000 | 100 | 1973 | 2073 | | 58.00 % | 0.00 % | 58 | | | \$56,400 |

Site Assessment Report - B537001;Moffet

| System Code | System Description | Unit Price \$ | UoM | Qty | Life | Year Installed | Calc Next Renewal Year | Next Renewal Year | RSLI% | FCI% | RSL | eCR | Deficiency \$ | Replacement Value \$ |
|--------------|---------------------------------|---------------|------|--------|------|----------------|------------------------|-------------------|----------------|----------------|-----|-----|-----------------------|----------------------|
| C3010230 | Paint & Covering | \$13.21 | S.F. | 40,000 | 10 | 2005 | 2015 | 2027 | 120.00 % | 0.00 % | 12 | | | \$528,400 |
| C3010231 | Vinyl Wall Covering | \$0.97 | S.F. | 40,000 | 15 | | | | 0.00 % | 0.00 % | | | | \$38,800 |
| C3010232 | Wall Tile | \$2.63 | S.F. | 40,000 | 30 | | | | 0.00 % | 0.00 % | | | | \$105,200 |
| C3020411 | Carpet | \$7.30 | S.F. | 2,000 | 10 | 1973 | 1983 | 2027 | 120.00 % | 153.55 % | 12 | | \$22,418.32 | \$14,600 |
| C3020412 | Terrazzo & Tile | \$75.52 | S.F. | 2,000 | 50 | 1973 | 2023 | | 16.00 % | 0.00 % | 8 | | | \$151,040 |
| C3020413 | Vinyl Flooring | \$9.68 | S.F. | 25,000 | 20 | 1973 | 1993 | 2037 | 110.00 % | 0.00 % | 22 | | | \$242,000 |
| C3020414 | Wood Flooring | \$22.27 | S.F. | | 25 | | | | 0.00 % | 0.00 % | | | | \$0 |
| C3020415 | Concrete Floor Finishes | \$0.97 | S.F. | 3,200 | 50 | 1973 | 2023 | | 16.00 % | 0.00 % | 8 | | | \$3,104 |
| C3030 | Ceiling Finishes | \$20.97 | S.F. | 40,000 | 25 | 1973 | 1998 | 2042 | 108.00 % | 50.35 % | 27 | | \$422,308.05 | \$838,800 |
| D1010 | Elevators and Lifts | \$1.53 | S.F. | 40,000 | 35 | 1973 | 2008 | 2052 | 105.71 % | 0.00 % | 37 | | | \$61,200 |
| D2010 | Plumbing Fixtures | \$13.52 | S.F. | 40,000 | 35 | 1973 | 2008 | 2025 | 28.57 % | 11.21 % | 10 | | \$60,633.52 | \$540,800 |
| D2020 | Domestic Water Distribution | \$1.68 | S.F. | 40,000 | 25 | 1973 | 1998 | 2042 | 108.00 % | 109.26 % | 27 | | \$73,420.64 | \$67,200 |
| D2030 | Sanitary Waste | \$2.90 | S.F. | 40,000 | 25 | 1973 | 1998 | 2042 | 108.00 % | 195.62 % | 27 | | \$226,915.87 | \$116,000 |
| D2040 | Rain Water Drainage | \$2.32 | S.F. | 40,000 | 30 | 1973 | 2003 | 2020 | 16.67 % | 0.00 % | 5 | | | \$92,800 |
| D3020 | Heat Generating Systems | \$18.67 | S.F. | 40,000 | 35 | 1973 | 2008 | 2052 | 105.71 % | 140.62 % | 37 | | \$1,050,121.66 | \$746,800 |
| D3030 | Cooling Generating Systems | \$24.48 | S.F. | 40,000 | 30 | 1973 | 2003 | 2047 | 106.67 % | 69.34 % | 32 | | \$678,976.31 | \$979,200 |
| D3040 | Distribution Systems | \$42.99 | S.F. | 40,000 | 25 | 1973 | 1998 | 2042 | 108.00 % | 152.91 % | 27 | | \$2,629,505.94 | \$1,719,600 |
| D3050 | Terminal & Package Units | \$11.60 | S.F. | 40,000 | 15 | 1973 | 1988 | 2022 | 46.67 % | 0.00 % | 7 | | | \$464,000 |
| D3060 | Controls & Instrumentation | \$13.50 | S.F. | 40,000 | 20 | 1973 | 1993 | 2037 | 110.00 % | 158.90 % | 22 | | \$858,081.16 | \$540,000 |
| D4010 | Sprinklers | \$7.05 | S.F. | 40,000 | 35 | 1973 | 2008 | 2052 | 105.71 % | 202.91 % | 37 | | \$572,219.29 | \$282,000 |
| D4020 | Standpipes | \$1.01 | S.F. | 40,000 | 35 | 1973 | 2008 | 2025 | 28.57 % | 0.00 % | 10 | | | \$40,400 |
| D5010 | Electrical Service/Distribution | \$9.70 | S.F. | 40,000 | 30 | 1973 | 2003 | 2047 | 106.67 % | 0.00 % | 32 | | | \$388,000 |
| D5020 | Lighting and Branch Wiring | \$34.68 | S.F. | 40,000 | 20 | 1973 | 1993 | 2037 | 110.00 % | 40.94 % | 22 | | \$567,930.52 | \$1,387,200 |
| D5030 | Communications and Security | \$12.99 | S.F. | 40,000 | 15 | 2010 | 2025 | | 66.67 % | 9.62 % | 10 | | \$49,966.64 | \$519,600 |
| D5090 | Other Electrical Systems | \$1.41 | S.F. | 40,000 | 30 | 1973 | 2003 | 2047 | 106.67 % | 212.80 % | 32 | | \$120,018.54 | \$56,400 |
| E1020 | Institutional Equipment | \$4.82 | S.F. | 40,000 | 35 | 1973 | 2008 | 2052 | 105.71 % | 0.00 % | 37 | | | \$192,800 |
| E1090 | Other Equipment | \$11.10 | S.F. | 40,000 | 35 | 1973 | 2008 | 2052 | 105.71 % | 0.86 % | 37 | | \$3,810.26 | \$444,000 |
| E2010 | Fixed Furnishings | \$2.13 | S.F. | 40,000 | 40 | 1973 | 2013 | 2057 | 105.00 % | 0.00 % | 42 | | | \$85,200 |
| Total | | | | | | | | | 82.86 % | 45.74 % | | | \$9,312,367.09 | \$20,360,696 |

System Notes

The facility description in the site executive summary contains an overview of each system. The notes listed below provide additional information on select systems found within the facility.

System: C3010 - Wall Finishes This system contains no images
Note: Paint 100%

System: C3020 - Floor Finishes This system contains no images
Note: VCT 78%
Carpet 6%
Ceramic tile 6%
Concrete 10%

System: C3030 - Ceiling Finishes This system contains no images
Note: ACT 87%
Exposed, paint 13%

System: D5010 - Electrical Service/Distribution This system contains no images
Note: 1-225 kVA 480:208/120V 3 phase transformer - part of the substation/switchgear line up in the penthouse electrical room

Renewal Schedule

eCOMET forecasts future Capital Renewal funding needed to address expiring systems based on the Next Renewal year found in the Cost Models. A 3% annual inflation factor is applied to the costs for systems expiring in future years. The table below reflects recommended Capital Renewal funding needs over the next 10 years. Note: Cells with a zero value indicate systems for which renewal is not scheduled in that year.

Inflation Rate: 3%

| System | Current Deficiencies | 2016 | 2017 | 2018 | 2019 | 2020 | 2021 | 2022 | 2023 | 2024 | 2025 | Total |
|---|----------------------|------------|------------|------------|------------|------------------|------------|------------------|------------------|------------|--------------------|---------------------|
| Total: | \$9,312,367 | \$0 | \$0 | \$0 | \$0 | \$118,339 | \$0 | \$627,728 | \$214,791 | \$0 | \$1,627,321 | \$11,900,546 |
| * A - Substructure | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| A10 - Foundations | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| A1010 - Standard Foundations | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| A1030 - Slab on Grade | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| A20 - Basement Construction | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| A2010 - Basement Excavation | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| A2020 - Basement Walls | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| B - Shell | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| B10 - Superstructure | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| B1010 - Floor Construction | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| B1020 - Roof Construction | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| B20 - Exterior Enclosure | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| B2010 - Exterior Walls | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| B2020 - Exterior Windows | \$936,839 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$936,839 |
| B2030 - Exterior Doors | \$34,936 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$34,936 |
| B30 - Roofing | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| B3010 - Roof Coverings | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| B3010105 - Built-Up | \$938,532 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$938,532 |
| B3010120 - Single Ply Membrane | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| B3010130 - Preformed Metal Roofing | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| B3010140 - Shingle & Tile | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| B3020 - Roof Openings | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| C - Interiors | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| C10 - Interior Construction | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| C1010 - Partitions | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |

Site Assessment Report - B537001;Moffet

| | | | | | | | | | | | | | |
|-------------------------------------|-------------|-----|-----|-----|-----|-----------|-----|-----------|-----------|-----|-----|-----------|-------------|
| C1020 - Interior Doors | \$13,766 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$13,766 |
| C1030 - Fittings | \$51,967 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$51,967 |
| C20 - Stairs | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| C2010 - Stair Construction | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| C30 - Interior Finishes | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| C3010 - Wall Finishes | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| C3010230 - Paint & Covering | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| C3010231 - Vinyl Wall Covering | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| C3010232 - Wall Tile | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| C3020 - Floor Finishes | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| C3020411 - Carpet | \$22,418 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$22,418 |
| C3020412 - Terrazzo & Tile | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$210,466 | \$0 | \$0 | \$0 | \$210,466 |
| C3020413 - Vinyl Flooring | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| C3020414 - Wood Flooring | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| C3020415 - Concrete Floor Finishes | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$4,325 | \$0 | \$0 | \$0 | \$4,325 |
| C3030 - Ceiling Finishes | \$422,308 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$422,308 |
| D - Services | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| D10 - Conveying | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| D1010 - Elevators and Lifts | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| D20 - Plumbing | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| D2010 - Plumbing Fixtures | \$60,634 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$799,469 | \$860,102 |
| D2020 - Domestic Water Distribution | \$73,421 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$73,421 |
| D2030 - Sanitary Waste | \$226,916 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$226,916 |
| D2040 - Rain Water Drainage | \$0 | \$0 | \$0 | \$0 | \$0 | \$118,339 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$118,339 |
| D30 - HVAC | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| D3020 - Heat Generating Systems | \$1,050,122 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$1,050,122 |
| D3030 - Cooling Generating Systems | \$678,976 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$678,976 |
| D3040 - Distribution Systems | \$2,629,506 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$2,629,506 |
| D3050 - Terminal & Package Units | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$627,728 | \$0 | \$0 | \$0 | \$0 | \$627,728 |
| D3060 - Controls & Instrumentation | \$858,081 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$858,081 |
| D40 - Fire Protection | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| D4010 - Sprinklers | \$572,219 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$572,219 |
| D4020 - Standpipes | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$59,724 | \$59,724 |


Site Assessment Report - B537001;Moffet

| | | | | | | | | | | | | | |
|--|-----------|-----|-----|-----|-----|-----|-----|-----|-----|-----|-----|-----------|-----------|
| D50 - Electrical | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| D5010 - Electrical Service/Distribution | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| D5020 - Lighting and Branch Wiring | \$567,931 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$567,931 |
| D5030 - Communications and Security | \$49,967 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$768,129 | \$818,095 |
| D5090 - Other Electrical Systems | \$120,019 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$120,019 |
| E - Equipment & Furnishings | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| E10 - Equipment | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| E1020 - Institutional Equipment | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| E1090 - Other Equipment | \$3,810 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$3,810 |
| E20 - Furnishings | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| E2010 - Fixed Furnishings | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |

* Indicates non-renewable system

Forecasted Sustainment Requirement

The following chart shows the current building deficiencies and forecasting sustainment requirements over the next ten years.




10 Year FCI Forecast by Investment Scenario

The chart below illustrates the effect of various investment levels on the building FCI for the next 10 years. The levels of investment shown below include:

- Current FCI: a variable investment amount based on renewing expired systems to maintain the current FCI for the building
- 2% Investment: an annual investment of 2% of the replacement value of the building, escalated for inflation
- 4% Investment: an annual investment of 4% of the replacement value of the building, escalated for inflation


Facility Investment vs. FCI Forecast



| Year | Investment Amount Current FCI - 45.74% | 2% Investment | | 4% Investment | |
|---------------|---|-----------------------|---------|-----------------------|---------|
| | | Amount | FCI | Amount | FCI |
| 2016 | \$0 | \$419,430.00 | 43.74 % | \$838,861.00 | 41.74 % |
| 2017 | \$12,578,929 | \$432,013.00 | 99.97 % | \$864,026.00 | 95.97 % |
| 2018 | \$0 | \$444,974.00 | 97.97 % | \$889,947.00 | 91.97 % |
| 2019 | \$0 | \$458,323.00 | 95.97 % | \$916,646.00 | 87.97 % |
| 2020 | \$118,339 | \$472,073.00 | 94.47 % | \$944,145.00 | 84.47 % |
| 2021 | \$0 | \$486,235.00 | 92.47 % | \$972,469.00 | 80.47 % |
| 2022 | \$627,728 | \$500,822.00 | 92.98 % | \$1,001,644.00 | 78.98 % |
| 2023 | \$214,791 | \$515,846.00 | 91.81 % | \$1,031,693.00 | 75.81 % |
| 2024 | \$0 | \$531,322.00 | 89.81 % | \$1,062,644.00 | 71.81 % |
| 2025 | \$1,627,321 | \$547,261.00 | 93.76 % | \$1,094,523.00 | 73.76 % |
| Total: | \$15,167,108 | \$4,808,299.00 | | \$9,616,598.00 | |

Deficiency Summary by System


Current deficiencies included assemblies that have reached or exceeded their design life or components of the assemblies that are in need of repair. Assemblies that have reached their design life are identified as current deficiencies and assigned the distress 'Beyond Useful Life'. The following chart lists all current deficiencies associated with this facility.



Budget Estimate Total: \$9,312,367.09

Deficiency Summary by Priority

The following chart shows the total repair costs broken down by priority. Assessors assigned deficiencies within eCOMET to one of the following priority categories:



Budget Estimate Total: \$9,312,367.09


Deficiency By Priority Investment Table

The table below shows the current investment cost grouped by deficiency priority and building system.

| System Code | System Description | 1 - Response Time (< 2 yr) | 2 - Response Time (2-3 yrs) | 3 - Response Time (3-4 yrs) | 4 - Response Time (4-5 yrs) | 5 - Response Time (> 5 yrs) | Total |
|-------------|-----------------------------|----------------------------|-----------------------------|-----------------------------|-----------------------------|-----------------------------|----------------|
| B2020 | Exterior Windows | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$936,839.39 | \$936,839.39 |
| B2030 | Exterior Doors | \$0.00 | \$0.00 | \$0.00 | \$34,936.40 | \$0.00 | \$34,936.40 |
| B3010105 | Built-Up | \$0.00 | \$0.00 | \$938,531.72 | \$0.00 | \$0.00 | \$938,531.72 |
| C1020 | Interior Doors | \$0.00 | \$0.00 | \$0.00 | \$13,766.19 | \$0.00 | \$13,766.19 |
| C1030 | Fittings | \$0.00 | \$0.00 | \$51,966.67 | \$0.00 | \$0.00 | \$51,966.67 |
| C3020411 | Carpet | \$0.00 | \$0.00 | \$22,418.32 | \$0.00 | \$0.00 | \$22,418.32 |
| C3030 | Ceiling Finishes | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$422,308.05 | \$422,308.05 |
| D2010 | Plumbing Fixtures | \$0.00 | \$0.00 | \$60,633.52 | \$0.00 | \$0.00 | \$60,633.52 |
| D2020 | Domestic Water Distribution | \$0.00 | \$0.00 | \$73,420.64 | \$0.00 | \$0.00 | \$73,420.64 |
| D2030 | Sanitary Waste | \$0.00 | \$0.00 | \$226,915.87 | \$0.00 | \$0.00 | \$226,915.87 |
| D3020 | Heat Generating Systems | \$0.00 | \$1,050,121.66 | \$0.00 | \$0.00 | \$0.00 | \$1,050,121.66 |
| D3030 | Cooling Generating Systems | \$0.00 | \$678,976.31 | \$0.00 | \$0.00 | \$0.00 | \$678,976.31 |
| D3040 | Distribution Systems | \$0.00 | \$0.00 | \$699,942.50 | \$1,929,563.44 | \$0.00 | \$2,629,505.94 |
| D3060 | Controls & Instrumentation | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$858,081.16 | \$858,081.16 |
| D4010 | Sprinklers | \$572,219.29 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$572,219.29 |
| D5020 | Lighting and Branch Wiring | \$0.00 | \$0.00 | \$567,930.52 | \$0.00 | \$0.00 | \$567,930.52 |
| D5030 | Communications and Security | \$0.00 | \$0.00 | \$49,966.64 | \$0.00 | \$0.00 | \$49,966.64 |
| D5090 | Other Electrical Systems | \$0.00 | \$0.00 | \$120,018.54 | \$0.00 | \$0.00 | \$120,018.54 |
| E1090 | Other Equipment | \$0.00 | \$3,810.26 | \$0.00 | \$0.00 | \$0.00 | \$3,810.26 |
| | Total: | \$572,219.29 | \$1,732,908.23 | \$2,811,744.94 | \$1,978,266.03 | \$2,217,228.60 | \$9,312,367.09 |

Deficiency Summary by Category

The following chart shows the total repair costs broken down by deficiency categories. Assessors assigned deficiencies to one of the following categories:



Deficiency Details by Priority

The deficiency detail notes listed below provide additional information on identified deficiencies found within the facility.

Priority 1 - Response Time (< 2 yr):

System: D4010 - Sprinklers



Location: Throughout buliding

Distress: Life Safety / NFPA / PFD

Category: 1 - Health & Safety

Priority: 1 - Response Time (< 2 yr)

Correction: Install a fire protection sprinkler system

Qty: 40,000.00

Unit of Measure: S.F.

Estimate: \$572,219.29

Assessor Name: System

Date Created: 08/03/2015

Notes: Install a fire protection sprinkler system with quick response type heads to reduce insurance costs by providing protection for the property. A fire pump may be required depending on the available city water pressure.

Priority 2 - Response Time (2-3 yrs):

System: D3020 - Heat Generating Systems



Location: Boiler Room

Distress: Beyond Service Life

Category: 3 - Operations / Maint.

Priority: 2 - Response Time (2-3 yrs)

Correction: Replace boiler, cast iron sectional (150 HP)

Qty: 2.00

Unit of Measure: Ea.

Estimate: \$1,050,121.66

Assessor Name: System

Date Created: 08/03/2015

Notes: Replace the two existing cast iron sectional boilers and burners with new cast iron sectional boilers of similar size, burners, and power ventilators.

System: D3030 - Cooling Generating Systems



Location: Boiler room

Distress: Beyond Service Life

Category: 3 - Operations / Maint.

Priority: 2 - Response Time (2-3 yrs)

Correction: Install chilled water system with distribution piping and pumps. (+75KSF)

Qty: 40,000.00

Unit of Measure: S.F.


Estimate: \$678,976.31

Assessor Name: System

Date Created: 08/03/2015

Notes: Replace the existing absorption chiller and cooling tower with a new water cooled chiller and cooling tower fitted with modern controls. All associated piping and pumping systems should also be replaced.

System: E1090 - Other Equipment



Location: Exterior

Distress: Damaged

Category: 3 - Operations / Maint.

Priority: 2 - Response Time (2-3 yrs)

Correction: Loading dock equipment - remove and replace dock leveler - delete the pipe bollards if not needed

Qty: 1.00

Unit of Measure: Ea.

Estimate: \$3,810.26

Assessor Name: System

Date Created: 08/17/2015

Notes: Replace loading dock bumpers

Priority 3 - Response Time (3-4 yrs):

System: B3010105 - Built-Up



Location: Exterior/ Roof

Distress: Beyond Service Life

Category: 3 - Operations / Maint.

Priority: 3 - Response Time (3-4 yrs)

Correction: Remove and Replace Built Up Roof

Qty: 27,700.00

Unit of Measure: S.F.

Estimate: \$938,531.72

Assessor Name: System

Date Created: 08/17/2015

Notes: Install all new roofing system including insulation within next 5 to 10 years; tear-down existing roofing; install flashing, and counter flashing

System: C1030 - Fittings



Location: Interiors

Distress: Accessibility

Category: 2 - Code Compliance

Priority: 3 - Response Time (3-4 yrs)

Correction: Remove and replace damaged toilet partitions - handicap units

Qty: 16.00

Unit of Measure: Ea.

Estimate: \$51,966.67

Assessor Name: System

Date Created: 08/17/2015

Notes: Reconfigure toilets for accessibility, provide new toilet partitions

System: C3020411 - Carpet



Location: Interiors
Distress: Beyond Service Life
Category: 3 - Operations / Maint.
Priority: 3 - Response Time (3-4 yrs)
Correction: Remove and replace carpet
Qty: 2,000.00

Unit of Measure: S.F.
Estimate: \$22,418.32
Assessor Name: System
Date Created: 08/17/2015

Notes: Replace existing carpet

System: D2010 - Plumbing Fixtures



Location: Corridors
Distress: Beyond Service Life
Category: 3 - Operations / Maint.
Priority: 3 - Response Time (3-4 yrs)
Correction: Remove and Replace Water Fountains - without ADA new recessed alcove
Qty: 8.00

Unit of Measure: Ea.
Estimate: \$60,633.52
Assessor Name: System
Date Created: 08/03/2015

Notes: Replace the wall hung drinking fountains and integral refrigerated coolers in the corridors and at the restrooms. These units are well beyond their service life and most are NOT accessible type.

System: D2020 - Domestic Water Distribution



Location: Boiler Room
Distress: Beyond Service Life
Category: 3 - Operations / Maint.
Priority: 3 - Response Time (3-4 yrs)
Correction: Replace instantaneous water heater
Qty: 3.00
Unit of Measure: Ea.
Estimate: \$73,420.64
Assessor Name: System
Date Created: 08/03/2015

Notes: Install three new gas fired instant hot water heaters with circulating pump.

System: D2030 - Sanitary Waste



Location: Throughout building
Distress: Health Hazard / Risk
Category: 1 - Health & Safety
Priority: 3 - Response Time (3-4 yrs)
Correction: Inspect sanitary waste piping and replace damaged sections. (+50KSF)
Qty: 40,000.00
Unit of Measure: S.F.
Estimate: \$196,229.92
Assessor Name: System
Date Created: 08/03/2015

Notes: Hire a qualified contractor to perform a detailed examination of the sanitary waste piping using visual inspection and video cameras to locate and replace any damaged piping and to further quantify the extent of potential failures.

System: D2030 - Sanitary Waste



Location: Elevator machine room

Distress: Beyond Service Life

Category: 3 - Operations / Maint.

Priority: 3 - Response Time (3-4 yrs)

Correction: Replace sanitary sewage ejector pit and pumps. (48" dia.)

Qty: 1.00

Unit of Measure: Ea.

Estimate: \$30,685.95

Assessor Name: System

Date Created: 08/03/2015

Notes: Replace existing sewage ejector pump system and piping in the sub-basement as it is approaching the end of its useful service life.

System: D3040 - Distribution Systems



Location: Boiler room

Distress: Beyond Service Life

Category: 3 - Operations / Maint.

Priority: 3 - Response Time (3-4 yrs)

Correction: Replace HVAC unit for Auditorium (200 seat).

Qty: 200.00

Unit of Measure: Seat

Estimate: \$333,093.30

Assessor Name: System

Date Created: 08/04/2015

Notes: Replace the Trane Climate Changer air handling unit serving the Auditorium by installing a new air handling unit with outdoor air ducted to the unit from louvers in the boiler room.

System: D3040 - Distribution Systems



Location: Boiler room

Distress: Beyond Service Life

Category: 3 - Operations / Maint.

Priority: 3 - Response Time (3-4 yrs)

Correction: Install HVAC unit for Cafeteria (850 students).

Qty: 417.00

Unit of Measure: Pr.

Estimate: \$194,966.18

Assessor Name: System

Date Created: 08/03/2015

Notes: Replace the Trane Climate Changer air handling unit serving the gymnasium by installing a new air handling unit with outdoor air ducted to the unit from louvers in the boiler room.

System: D3040 - Distribution Systems



Location: Boiler Room

Distress: Beyond Service Life

Category: 3 - Operations / Maint.

Priority: 3 - Response Time (3-4 yrs)

Correction: Perform testing to identify and replace damaged steam and condensate piping.

Qty: 40,000.00

Unit of Measure: S.F.

Estimate: \$171,883.02

Assessor Name: System

Date Created: 08/03/2015

Notes: Hire a qualified contractor to examine the steam and condensate piping, in service for nearly 45 years, and perform additional testing to locate and replace any damaged piping and to further quantify the extent of potential failures.

System: D5020 - Lighting and Branch Wiring



Location: Throughout Building
Distress: Energy Efficiency
Category: 4 - Capital Improvement
Priority: 3 - Response Time (3-4 yrs)
Correction: Replace Lighting Fixtures (SF)
Qty: 40,000.00
Unit of Measure: S.F.
Estimate: \$515,883.60
Assessor Name: System
Date Created: 08/05/2015

Notes: Replace existing T12 fixtures with T8 fixtures

System: D5020 - Lighting and Branch Wiring



Location: Throughout Building
Distress: Inadequate
Category: 4 - Capital Improvement
Priority: 3 - Response Time (3-4 yrs)
Correction: Add wiring device
Qty: 1.00
Unit of Measure: Ea.
Estimate: \$52,046.92
Assessor Name: System
Date Created: 08/05/2015

Notes: Install minimum one receptacle on each wall of classrooms and other purpose rooms.

System: D5030 - Communications and Security



Location: Throughout Building
Distress: Life Safety / NFPA / PFD
Category: 1 - Health & Safety
Priority: 3 - Response Time (3-4 yrs)
Correction: Replace fire alarm system
Qty: 1.00
Unit of Measure: S.F.
Estimate: \$49,966.64
Assessor Name: System
Date Created: 08/05/2015

Notes: Install a new addressable fire alarm system and provide audible and/or visual devices in all areas.

System: D5090 - Other Electrical Systems



Location: Penthouse
Distress: Inadequate
Category: 4 - Capital Improvement
Priority: 3 - Response Time (3-4 yrs)
Correction: Replace standby generator system
Qty: 1.00
Unit of Measure: Ea.
Estimate: \$120,018.54
Assessor Name: System
Date Created: 08/05/2015

Notes: Replace existing generator with larger generator sized to operate the elevator.

Priority 4 - Response Time (4-5 yrs):

System: B2030 - Exterior Doors



Location: Exterior

Distress: Building / MEP Codes

Category: 2 - Code Compliance

Priority: 4 - Response Time (4-5 yrs)

Correction: Replace hardware with compliant hardware, paint and weatherstrip - per leaf

Qty: 10.00

Unit of Measure: Ea.

Estimate: \$34,936.40

Assessor Name: System

Date Created: 08/17/2015

Notes: Install ADA compliant hardware and weather-stripping on all exterior doors

System: C1020 - Interior Doors



Location: Interiors

Distress: Accessibility

Category: 2 - Code Compliance

Priority: 4 - Response Time (4-5 yrs)

Correction: Provide security hardware for classroom and office doors

Qty: 60.00

Unit of Measure: Ea.

Estimate: \$13,766.19

Assessor Name: System

Date Created: 08/17/2015

Notes: • Replace interior doors hardware for ADA accessibility

System: D3040 - Distribution Systems



Location: Throughout building

Distress: Beyond Service Life

Category: 3 - Operations / Maint.

Priority: 4 - Response Time (4-5 yrs)

Correction: Replace the existing unit ventilators with new units designed to provide adequate ventilation per ASHRAE Std 62 - insert the SF of bldg. in the qty.

Qty: 40,000.00

Unit of Measure: S.F.

Estimate: \$1,929,563.44

Assessor Name: System

Date Created: 08/03/2015

Notes: Replace the existing unit ventilators with two pipe units that have integral heat exchangers to introduce outdoor air to the building.

Priority 5 - Response Time (> 5 yrs):

System: B2020 - Exterior Windows



Location: Exterior

Distress: Beyond Service Life

Category: 3 - Operations / Maint.

Priority: 5 - Response Time (> 5 yrs)

Correction: Remove and replace aluminum windows - pick the appropriate size and style and insert the number of units

Qty: 80.00

Unit of Measure: Ea.

Estimate: \$553,073.50

Assessor Name: System

Date Created: 08/17/2015

Notes: Replace all windows within next 5 to 10 years including security screens

System: B2020 - Exterior Windows



Location: Exterior

Distress: Damaged

Category: 3 - Operations / Maint.

Priority: 5 - Response Time (> 5 yrs)

Correction: Replace security screens

Qty: 2,500.00

Unit of Measure: S.F.

Estimate: \$383,765.89

Assessor Name: System

Date Created: 08/17/2015

Notes: Replace all windows within next 5 to 10 years including security screens

System: C3030 - Ceiling Finishes



Location: Interiors

Distress: Beyond Service Life

Category: 3 - Operations / Maint.

Priority: 5 - Response Time (> 5 yrs)

Correction: Remove and replace suspended acoustic ceilings - lighting not included

Qty: 28,000.00

Unit of Measure: S.F.

Estimate: \$422,308.05

Assessor Name: System

Date Created: 08/17/2015

Notes: Replace all suspended acoustical ceilings

System: D3060 - Controls & Instrumentation



Location: Throughout building

Distress: Inadequate

Category: 4 - Capital Improvement

Priority: 5 - Response Time (> 5 yrs)

Correction: Replace pneumatic controls with DDC (75KSF)

Qty: 40,000.00

Unit of Measure: S.F.

Estimate: \$858,081.16

Assessor Name: System

Date Created: 08/03/2015

Notes: Replace the pneumatic controls for the HVAC systems with modern DDC modules, valves and actuators to improve reliability and energy efficiency. Provide a new building automation system (BAS) with communication interface to the preferred system in use throughout the District.

Equipment Inventory

The following table represents the inventory details of the inventory found in the building, which fall under the following subsystems:

| Subsystem | Inventory | Qty | UoM | Location | Manufacturer | Model Number | Serial Number | Barcode | Life | Install Date | Next Renewal | Raw Cost | Inventory Cost |
|---------------------------------------|--|------|-----|---------------------------|-----------------|--------------|---------------|---------|------|--------------|--------------|---------------------|----------------|
| D1010 Elevators and Lifts | Hydraulic, passenger elevator, 3000 lb, 2 floors, 100 FPM | 1.00 | Ea. | | | | | | 30 | | | \$73,815.00 | \$81,196.50 |
| D3020 Heat Generating Systems | Boiler, oil fired, flame retention burner, cast iron, steam, gross output, 3820 MBH, includes standard controls and insulated flush jacket, packaged | 2.00 | Ea. | Boiler Room | Weil-McLain | 94 | | | 35 | | | \$67,020.00 | \$147,444.00 |
| D3020 Heat Generating Systems | Boiler, oil fired, flame retention burner, cast iron, steam, gross output, 3820 MBH, includes standard controls and insulated flush jacket, packaged | 2.00 | Ea. | Boiler Room | Weil-McLain | 94 | | | 35 | | | \$67,020.00 | \$147,444.00 |
| D5010 Electrical Service/Distribution | Load interrupter switch, 2 position, 400 kVA & above, 13.8 kV, 600 amp w/CLF fuses, NEMA 1 | 1.00 | Ea. | Penthouse | Federal Pacific | 26510 1595 | | | 30 | | | \$42,849.00 | \$47,133.90 |
| D5010 Electrical Service/Distribution | Switchgear installation, incl switchboard, panels & circuit breaker, 120/208 V, 800 A | 1.00 | Ea. | Penthouse Electrical Room | Federal Pacific | | 22424-01 | | 20 | | | \$21,766.05 | \$23,942.66 |
| D5010 Electrical Service/Distribution | Switchgear installation, incl switchboard, panels & circuit breaker, 277/480 V, 800 A | 1.00 | Ea. | Penthouse Electrical Room | Federal Pacific | | 22424-01 | | 20 | | | \$31,205.25 | \$34,325.78 |
| D5010 Electrical Service/Distribution | Transformers, 13,800 volts to 480/277 volts, 500 kVA | 1.00 | Ea. | Penthouse Electrical Room | Federal Pacific | | 23439-001 | | 30 | | | \$68,931.00 | \$75,824.10 |
| Total: | | | | | | | | | | | | \$557,310.94 | |

Executive Summary

Building condition is evaluated based on the functional systems and elements of a building and organized according to the UNIFORMAT II Elemental Classification. The grouping of these systems and elements and applying a current replacement value to them develops a representative building cost model. Cost Models are developed for similar building types and functions. Systems and their elements are evaluated based on their current replacement values, life cycles, installation dates and next renewal dates. Systems and their elements that are within their useful lives are further evaluated to identify current deficient conditions that may have a significant impact on a system's or element's remaining service life, and to determine if they are beyond their predicted expected life. The system's or element's current replacement value is based on RS Means Commercial Cost Data.

Following are the cost model's system details for this facility. The Replacement Value is the amount needed to replace the property of the same present value. The Current Repair Amount, also known as Condition Needs, represents the budgeted contractor installed costs plus owner's soft costs for the repair, replacement or renewal for a component or system level deficiency. It excludes contributing costs for other components or systems that might also be associated with the corrective actions due to packaging the work. Facility Condition Index (FCI) FCI is an industry-standard measurement of facility condition calculated as the ratio of the costs to correct a facility's deficiencies to the facility's Current Replacement Value. It ranges from 0% (new) to 100% (very poor). Condition Index (CI) is calculated as the sum of a renewable system's Remaining Service Life (RSL) divided by the sum of a system's Replacement Value (both values exclude soft-cost to simplify calculation updates) expressed as a percentage ranging from 100% (new) to 0% (expired).

Function:

Gross Area (SF): 68,600

Year Built: 1973

Last Renovation:

Replacement Value: \$1,346,630

Repair Cost: \$952,396.96

Total FCI: 70.72 %

Total RSLI: 71.12 %

Description:

Attributes:

General Attributes:

| | | | |
|----------|---------|----------|---------|
| Bldg ID: | S537001 | Site ID: | S537001 |
|----------|---------|----------|---------|

Condition Summary

The Table below shows the CI and FCI for each major building system shown at the UNIFORMAT classification Level II. Note that Systems with lower FCIs require less investment than systems with higher FCIs.

| UNIFORMAT Classification | RSLI % | FCI % | Current Repair Cost |
|---------------------------------|----------------|----------------|---------------------|
| G20 - Site Improvements | 75.45 % | 90.86 % | \$952,396.96 |
| G40 - Site Electrical Utilities | 55.90 % | 0.00 % | \$0.00 |
| Totals: | 71.12 % | 70.72 % | \$952,396.96 |

Condition Detail

This section of the report contains results of the Facility Condition Assessment. The building is separated into system components based on UNIFORMAT II classification. The columns in the System Listing table below represent the following:

1. System Code: A code that identifies the system.
2. System Description: A brief description of a system present in the building.
3. Unit Price \$: The unit price of the system.
4. UoM: The unit of measure for of the system.
5. Qty: The quantity for the system
6. Life: anticipated service life for the system based on Building Owners and Managers Association (BOMA) recommendations.
7. Year Installed: The date of system installation.
8. Calc Next Renewal Year: The date of system expiration based on the life, NR stands for non renewable.
9. Next Renewal Year: The suggested system expiration date by the assessor based on visual inspection.
10. CI: The Condition Index of the system.
11. FCI: The Facility Condition Index of the system.
12. RSL: Remaining Service Life.
13. eCR: eCOMET Condition Rating (not used).
14. Deficiency \$: The financial investment to repair/replace system.

System Listing

The System Listing table below lists each of the systems organized by their UNIFORMAT II classification. The assessment team was tasked with recording the most recent replacement year of each system, determining the remaining service life based on the theoretical life, and evaluating the condition to confirm the forecast next replacement year. The system listing is the basis for all data contained in the Building Assessment Report.

Additionally, a condition rating (eCR) based on the following guidelines is provided as observed at the time of the assessment.

- Excellent (E) - No noticeable distress or damage. The entire system is free from observable defect.
- Very Good (VG) - Overall no serviceability reduction for the entire system. No degradation of critical components and minor distress and defect noticeable for some but not non critical components within the system.
- Good (G) - Slight or no serviceability reduction for the entire system. There may be noticeable defects for some non critical components and slight noticeable degradation of the critical components.
- Fair (F) - Overall serviceability is degraded but adequate. There may be moderate deterioration for very few of the critical components and few of the non critical components may have severe degradation.
- Marginal (MA) - Overall serviceability and reliability loss. Most if not all of the non critical components suffer from severe degradation and a few of the critical component may have severe degradation.
- Moderate (MO) - Overall a significant serviceability loss. Most if not all the components have severe degradation with the reminder of the component showing visible distress.
- Very Poor (VP) - Overall the system is barely functional. All of the components are severely degraded.
- Non-Functional (NF) - Overall the system does not function with all the components having no serviceability and suffer from severe degradation.

| System Code | System Description | Unit Price \$ | UoM | Qty | Life | Year Installed | Calc Next Renewal Year | Next Renewal Year | RSLI% | FCI% | RSL | eCR | Deficiency \$ | Replacement Value \$ |
|--------------|--------------------------------|---------------|------|--------|------|----------------|------------------------|-------------------|----------------|----------------|-----|-----|---------------------|----------------------|
| G2010 | Roadways | \$11.52 | S.F. | | 30 | | | | 0.00 % | 0.00 % | | | | \$0 |
| G2020 | Parking Lots | \$7.65 | S.F. | 10,000 | 30 | 1973 | 2003 | 2040 | 83.33 % | 275.12 % | 25 | | \$210,463.08 | \$76,500 |
| G2030 | Pedestrian Paving | \$11.52 | S.F. | 53,400 | 40 | 1973 | 2013 | 2040 | 62.50 % | 116.90 % | 25 | | \$719,142.51 | \$615,168 |
| G2040 | Site Development | \$4.36 | S.F. | 68,600 | 25 | 1990 | 2015 | 2035 | 80.00 % | 7.62 % | 20 | | \$22,791.37 | \$299,096 |
| G2050 | Landscaping & Irrigation | \$3.78 | S.F. | 15,200 | 15 | 1973 | 1988 | 2042 | 180.00 % | 0.00 % | 27 | | | \$57,456 |
| G4020 | Site Lighting | \$3.58 | S.F. | 68,600 | 30 | 2000 | 2030 | | 50.00 % | 0.00 % | 15 | | | \$245,588 |
| G4030 | Site Communications & Security | \$0.77 | S.F. | 68,600 | 30 | 2010 | 2040 | | 83.33 % | 0.00 % | 25 | | | \$52,822 |
| Total | | | | | | | | | 71.12 % | 70.72 % | | | \$952,396.96 | \$1,346,630 |

System Notes

The facility description in the site executive summary contains an overview of each system. The notes listed below provide additional information on select systems found within the facility.

No data found for this asset

Renewal Schedule

eCOMET forecasts future Capital Renewal funding needed to address expiring systems based on the Next Renewal year found in the Cost Models. A 3% annual inflation factor is applied to the costs for systems expiring in future years. The table below reflects recommended Capital Renewal funding needs over the next 10 years. Note: Cells with a zero value indicate systems for which renewal is not scheduled in that year.


Inflation Rate: 3%

| System | Current Deficiencies | 2016 | 2017 | 2018 | 2019 | 2020 | 2021 | 2022 | 2023 | 2024 | 2025 | Total |
|--|----------------------|------------|------------|------------|------------|------------|------------|------------|------------|------------|------------|------------------|
| Total: | \$952,397 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$952,397 |
| G - Building Sitework | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| G20 - Site Improvements | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| G2010 - Roadways | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| G2020 - Parking Lots | \$210,463 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$210,463 |
| G2030 - Pedestrian Paving | \$719,143 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$719,143 |
| G2040 - Site Development | \$22,791 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$22,791 |
| G2050 - Landscaping & Irrigation | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| G40 - Site Electrical Utilities | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| G4020 - Site Lighting | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| G4030 - Site Communications & Security | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |

** Indicates non-renewable system*

Forecasted Sustainment Requirement

The following chart shows the current building deficiencies and forecasting sustainment requirements over the next ten years.




10 Year FCI Forecast by Investment Scenario

The chart below illustrates the effect of various investment levels on the building FCI for the next 10 years. The levels of investment shown below include:

- Current FCI: a variable investment amount based on renewing expired systems to maintain the current FCI for the building
- 2% Investment: an annual investment of 2% of the replacement value of the building, escalated for inflation
- 4% Investment: an annual investment of 4% of the replacement value of the building, escalated for inflation


Facility Investment vs. FCI Forecast



| Year | Investment Amount Current FCI - 70.72% | 2% Investment | | 4% Investment | |
|---------------|---|---------------------|---------|---------------------|---------|
| | | Amount | FCI | Amount | FCI |
| 2016 | \$0 | \$27,741.00 | 68.72 % | \$55,481.00 | 66.72 % |
| 2017 | \$0 | \$28,573.00 | 66.72 % | \$57,146.00 | 62.72 % |
| 2018 | \$0 | \$29,430.00 | 64.72 % | \$58,860.00 | 58.72 % |
| 2019 | \$0 | \$30,313.00 | 62.72 % | \$60,626.00 | 54.72 % |
| 2020 | \$0 | \$31,222.00 | 60.72 % | \$62,445.00 | 50.72 % |
| 2021 | \$0 | \$32,159.00 | 58.72 % | \$64,318.00 | 46.72 % |
| 2022 | \$0 | \$33,124.00 | 56.72 % | \$66,247.00 | 42.72 % |
| 2023 | \$0 | \$34,117.00 | 54.72 % | \$68,235.00 | 38.72 % |
| 2024 | \$0 | \$35,141.00 | 52.72 % | \$70,282.00 | 34.72 % |
| 2025 | \$0 | \$36,195.00 | 50.72 % | \$72,390.00 | 30.72 % |
| Total: | \$0 | \$318,015.00 | | \$636,030.00 | |


Deficiency Summary by System

Current deficiencies included assemblies that have reached or exceeded their design life or components of the assemblies that are in need of repair. Assemblies that have reached their design life are identified as current deficiencies and assigned the distress 'Beyond Useful Life'. The following chart lists all current deficiencies associated with this facility.



Deficiency Summary by Priority

The following chart shows the total repair costs broken down by priority. Assessors assigned deficiencies within eCOMET to one of the following priority categories:



Budget Estimate Total: \$952,396.96


Deficiency By Priority Investment Table

The table below shows the current investment cost grouped by deficiency priority and building system.

| System Code | System Description | 1 - Response Time (< 2 yr) | 2 - Response Time (2-3 yrs) | 3 - Response Time (3-4 yrs) | 4 - Response Time (4-5 yrs) | 5 - Response Time (> 5 yrs) | Total |
|---------------|--------------------|----------------------------|-----------------------------|-----------------------------|-----------------------------|-----------------------------|--------------|
| G2020 | Parking Lots | \$0.00 | \$0.00 | \$210,463.08 | \$0.00 | \$0.00 | \$210,463.08 |
| G2030 | Pedestrian Paving | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$719,142.51 | \$719,142.51 |
| G2040 | Site Development | \$0.00 | \$0.00 | \$0.00 | \$16,798.17 | \$5,993.20 | \$22,791.37 |
| Total: | | \$0.00 | \$0.00 | \$210,463.08 | \$16,798.17 | \$725,135.71 | \$952,396.96 |

Deficiency Summary by Category

The following chart shows the total repair costs broken down by deficiency categories. Assessors assigned deficiencies to one of the following categories:



Deficiency Details by Priority

The deficiency detail notes listed below provide additional information on identified deficiencies found within the facility.

Priority 3 - Response Time (3-4 yrs):

System: G2020 - Parking Lots



Location: Grounds/ Site

Distress: Beyond Service Life

Category: 3 - Operations / Maint.

Priority: 3 - Response Time (3-4 yrs)

Correction: Remove and replace concrete paving

Qty: 10,000.00

Unit of Measure: S.F.

Estimate: \$210,463.08

Assessor Name: Wlodek Pieczonka

Date Created: 08/17/2015

Notes: Replace loading dock area pavement (heavy vehicular traffic)

Priority 4 - Response Time (4-5 yrs):

System: G2040 - Site Development



Location: Grounds/ Site

Distress: Beyond Service Life

Category: 3 - Operations / Maint.

Priority: 4 - Response Time (4-5 yrs)

Correction: Replace chain link fence - 8' high

Qty: 150.00

Unit of Measure: L.F.

Estimate: \$16,798.17

Assessor Name: Wlodek Pieczonka

Date Created: 08/17/2015

Notes: Replace original chain link fence and security gate

Priority 5 - Response Time (> 5 yrs):

System: G2030 - Pedestrian Paving



Location: Grounds/ Site

Distress: Beyond Service Life

Category: 3 - Operations / Maint.

Priority: 5 - Response Time (> 5 yrs)

Correction: Remove and replace concrete sidewalk or concrete paving - 4" concrete thickness

Qty: 50,000.00

Unit of Measure: S.F.

Estimate: \$719,142.51

Assessor Name: Wlodek Pieczonka

Date Created: 08/17/2015

Notes: Resurface playground paving.

System: G2040 - Site Development



Location: Grounds/ Site

Distress: Security Issue

Category: 1 - Health & Safety

Priority: 5 - Response Time (> 5 yrs)

Correction: Remove and replace chain link gate - 8' high

Qty: 1.00

Unit of Measure: Ea.

Estimate: \$5,993.20

Assessor Name: Craig Anding

Date Created: 08/17/2015

Notes: Replace original chain link fence and security gate

Equipment Inventory

The following table represents the inventory details of the inventory found in the building, which fall under the following subsystems:

No data found for this asset

Glossary

| | |
|------------|---|
| ABMA | American Boiler Manufacturers Association http://www.abma.com/ |
| ACEEE | American Council for an Energy-Efficient Economy |
| ACGIH | American Council of Governmental and Industrial Hygienists |
| AEE | Association of Energy Engineers |
| AFD | Adjustable Frequency Drive |
| AFTC | After Tax Cash Flow |
| AGA | American Gas Association |
| AHU | Air Handling Unit |
| Amp | Ampere |
| ANSI | American National Standards Institute |
| ARI | Air Conditioning and Refrigeration Institute |
| ASD | Adjustable Speed Drive |
| ASHRAE | American Society of Heating Refrigerating and Air-Conditioning Engineers Inc. |
| ASME | American Society of Mechanical Engineers |
| Assessment | Visual survey of a facility to determine its condition. It involves looking at the age of systems reviewing information from local sources and visual evidence of potential problems to assign a condition rating. It does not include destructive testing of materials or testing of systems or equipment for functionality. |
| ATS | After Tax Savings |
| AW | Annual worth |
| BACNET | Building Automation Control Network |
| BAS | Building Automation System |
| BCR | Benefit Cost Ratio |
| BEP | Business Energy Professional (AEE) |
| BF | Ballast Factor |
| BHP | Boiler Horsepower (boilers) |
| BHP | Brake Horsepower (motors) |
| BLCC | Building Life Cycle Cost analysis program (FEMP) |
| BOCA | Building Officials and Code Administrators |
| BTCF | Before Tax Cash Flow |

Site Assessment Report - S537001;Moffet

| | |
|-------------------------|---|
| BTS | Before Tax Savings |
| Btu | British thermal unit |
| Building Addition | An area space or component of a building added to a building after the original building's year built date. |
| CAA | Clean Air Act |
| CAAA-90 | Clean Air Act Amendments of 1990 |
| CABO | Council of American Building Officials |
| CAC | Conventional Air Conditioning |
| CADDET | Center for the Analysis and Dissemination of Demonstrated Energy Technologies |
| Calculated Next Renewal | The year a system or element would be expected to expire based solely on the date it was installed and the expected useful lifetime for that kind of system. |
| Capital Renewal | Capital renewal is condition work (excluding suitability and energy audit work) that includes the replacement of building systems or elements (as they become obsolete or beyond their useful life) not normally included in an annual operating budget. Calculated next renewal The year a system or element would be expected to expire based solely on the date it was installed and the expected useful lifetime for that kind of system. Next renewal The assessor adjusted expected useful life of a system or element based on on-site inspection. |
| CDD | Cooling Degree Days |
| CDGP | Certified Distributed Generation Professional |
| CEC | California Energy Commission |
| CEM | Certified Energy Manager |
| CEP | Certified Energy Procurement Professional |
| CFC | Chlorofluorocarbon |
| CFD | Cash Flow Diagram |
| CFL | Compact Fluorescent Light |
| CFM cfm | Cubic Feet per Minute |
| CHP | Combined Heat and Power (a.k.a. cogeneration) |
| CHW | Chilled Water |
| Condition | Condition refers to the state of physical fitness or readiness of a facility system or system element for its intended use. |
| COP | Coefficient of Performance |
| Cp | Heat Capacity of Material |
| CPUC | California Public Utility Commission |
| CRI | Color Rendering Index |
| CRT | Cathode Ray Tube VDT HMI |

Site Assessment Report - S537001;Moffet

| | |
|---------------------------------|---|
| CTC | Competitive Transition Charge |
| Cu | Coefficient of Utilization |
| Current Replacement Value (CRV) | CRV represents the hypothetical total cost of rebuilding or replacing an existing facility in current dollars to its optimal condition (excluding auxiliary facilities) under current codes and construction standards. |
| Cv | Value Coefficient |
| CWS | Chilled Water System |
| D d | Distance (usually feet) |
| DB | Dry Bulb |
| DCV | Demand Control Ventilation |
| DD | Degree Day |
| DDB | Double Declining Balance |
| DDC | Direct Digital Controls |
| Deferred maintenance | Deferred maintenance is condition work (excluding suitability and energy audit needs) deferred on a planned or unplanned basis to a future budget cycle or postponed until funds are available. |
| Deficiency | A deficiency is a repair item that is damaged missing inadequate or insufficient for an intended purpose. |
| Delta | Difference |
| Delta P | Pressure Difference |
| Delta T | Temperature Difference |
| DG | Distributed Generation |
| DOE | Department of Energy |
| DP | Dew Point |
| DR | Demand Response |
| DX | Direct Expansion Air Conditioner |
| EA | Energy Audit |
| EBITDA | Earnings before Interest Taxes Depreciation and Amortization |
| ECI | Energy Cost Index |
| ECM | Energy Conservation Measure |
| ECO | Energy Conservation Opportunity |
| ECPA | Energy Conservation and Production Act |
| ECR | Energy Conservation Recommendation |
| ECS | Energy Control System |

Site Assessment Report - S537001;Moffet

| | |
|--|--|
| EER | Energy Efficiency Ratio |
| EERE | Energy Efficiency and Renewable Energy division of US DOE |
| EIA | Energy Information Agency |
| EIS | Energy Information System |
| EMCS | Energy Management Computer System |
| EMO | Energy Management Opportunity |
| EMP | Energy Management Project |
| EMR | Energy Management Recommendation |
| EMS | Energy Management System |
| Energy Utilization Index (EUI) | EUI is the measure of total energy consumed in the cooling or heating of a building in a period expressed as British thermal unit (BTU) per (cooled or heated) gross square foot. |
| EO | Executive Order |
| EPA | Environmental Protection Agency |
| EPACT | Energy Policy Act of 1992 |
| EPCA | Energy Production and Conservation Act of 1975 |
| EPRI | Electric Power Research Institute |
| EREN | Efficiency and Renewable Energy (Division of USDOE) |
| ERV | Energy Recovery Ventilator |
| ESCO | Energy Service Company |
| ESPC | Energy Savings Performance Contract |
| EUI | Energy Use Index |
| EWG | Exempt Wholesale Generators |
| Extended Facility Condition Index (EFCI) | EFCI is calculated as the condition needs for the current year plus facility system renewal needs going out to a set time in the future divided by Current Replacement Value. |
| f | Frequency |
| F | Fahrenheit |
| Facility | A facility refers to site(s) building(s) or building addition(s) or combinations thereof that provide a particular service. |
| Facility Condition Assessment (FCA) | FCA is a process for evaluating the condition of buildings and facilities for programming and budgetary purposes through an on site inspection and evaluation process. |
| Facility Condition Index (FCI) | FCI is an industry-standard measurement of a facility's condition that is the ratio of the cost to correct a facility's deficiencies to the Current Replacement Value of the facilities. The higher the FCI the poorer the condition of a facility. After an FCI is established for all buildings within a portfolio a building's condition can be ranked relative to other buildings. The FCI may also represent the condition of a portfolio based on the cumulative FCIs of the portfolio's facilities. |

Site Assessment Report - S537001;Moffet

| | |
|-------------------------|---|
| FC | Footcandle |
| FCA | Fuel Cost Adjustment |
| FEMIA | Federal Energy Management Improvement Act of 1988 |
| FEMP | Federal Energy Management Program |
| FERC | Federal Energy Regulatory Commission |
| FESR | Fuel Energy Savings Ratio |
| FLA | Full Load Amps |
| FLF | Facility Load Factor (usually monthly) |
| FLRPM | Full Load Revolutions per Minute |
| FMS | Facility Management System |
| FPM fpm | Feet per Minute (velocity) |
| FSEC | Florida Solar Energy Center |
| Ft | Foot |
| GPM gpm | Gallons per Minute |
| GRI | Gas Research Institute |
| Gross Square Feet (GSF) | The size of the enclosed floor space of a building in square feet measured to the outside face of the enclosing wall. |
| GUI | Graphical User Interface |
| H h | Enthalpy Btu/lb |
| HCFC | Hydrochlorofluorocarbons |
| HDD | Heating Degree days |
| HFC | Hydrofluorocarbons |
| HHV | Higher Heating Value |
| HID | High Intensity Discharge (lamp) |
| HMI | Human Machine Interface |
| HMMI | Human Man Machine Interface |
| HO | High Output (lamp) |
| HP Hp hp | Horsepower |
| HPS | High Pressure Sodium (lamp) |
| HR | Humidity Ratio |
| Hr hr | Hour |

Site Assessment Report - S537001;Moffet

| | |
|--------------|--|
| HRU | Heat Recovery Unit |
| HVAC | Heating Ventilation and Air-Conditioning |
| Hz | Hertz |
| I | Intensity (lumen output of lamp) |
| I i | Interest rate or Discount rate |
| IAQ | Indoor Air Quality |
| ICA | International Cogeneration Alliance |
| ICBO | International Conference of Buildings Officials |
| ICC | International Code Council |
| ICP | Institutional Conservation Program |
| IECC | International Energy Conservation Code |
| IEEE | Institute of Electrical and Electronic Engineers |
| IESNA | Illuminating Engineering Society of North America |
| Install year | The year a building or system was built or the most recent major renovation date (where a minimum of 70 of the system's Current Replacement Value (CRV) was replaced). |
| IRP | Integrated Resource Planning |
| IRR | Internal Rate of Return |
| ISO | Independent System Operator |
| ITA | Independent Tariff Administrator |
| k | Kilo multiple of thousands in SI system |
| K | Kelvins (color temperature of lamp) |
| K k | Thermal Conductivity of Material |
| KVA | Kilovolt Ampere |
| KVAR | Kilovolt Ampere Reactive |
| kW | kiloWatt |
| kWh | kiloWatt hour |
| L | Length (usually feet) |
| LCC | Life Cycle Costing |
| LDC | Local Distribution Company |
| LEED | Leadership in Energy and Environmental Design |
| LEED EB | LEED for Existing Buildings |

Site Assessment Report - S537001;Moffet

| | |
|--------------|--|
| LEED NC | LEED for new construction |
| LF | Load Factor |
| LHV | Lower Heating Value |
| Life cycle | The period of time that a building or site system or element can be expected to adequately serve its intended function. |
| LPS | Low Pressure Sodium (lamp) |
| Lu | Lumen Output of a Lamp or Fixture |
| M | Mega multiple of millions in SI system |
| M&V | Measurement and Verification |
| MACRS | Modified Accelerated Cost Recovery System |
| MARR | Minimum Attractive Rate of Return |
| Mbtu | Thousand Btu |
| MCF | Thousand Cubic Feet (usually of gas) |
| MEC | Model Energy Code |
| Mm | Multiple of Thousands in I/P System |
| MMBtu | Million Btu |
| MMCS | Maintenance Management Computer System |
| MMI | Man Machine Interface |
| MMS | Maintenance Management System |
| MSE 2000 | Management System for Energy 2000 (ANSI Georgia Tech Univ) |
| MW | MegaWatt |
| MWH MWh | MegaWatt hour |
| NAAQS | National Ambient Air Quality Standards |
| NAESCO | National Association of Energy Service Companies |
| NAIMA | North American Insulation Manufacturers Association |
| NEA | National Energy Act of 1978 |
| NECPA | National Energy Conservation Policy Act |
| NEMA | National Electrical Manufacturer's Association |
| NERC | North American Electric Reliability Council |
| Next Renewal | The Next Renewal date is an override of the 'Calculated Next Renewal' date and is based upon the assessor's visual inspection. |

Site Assessment Report - S537001;Moffet

| | |
|-----------|---|
| NFPA | National Fire Protection Association |
| NGPA | National Gas Policy Act of 1978 |
| NLRPM | No Load Revolutions per Minute (speed) |
| Nn | Equipment or Project lifetime in economic analysis |
| NOPR | Notice of Proposed Rule Making from FERC |
| NOx | Nitrogen Oxide Compounds |
| NPV | Net present value in economic analysis |
| NREL | National Renewable Energy Laboratory |
| NUG | Non-Utility Generator |
| O&M | Operation and Maintenance |
| OA | Outside Air |
| ODP | Ozone Depletion Potential |
| OPAC | Off-Peak Air Conditioning |
| P | Present value in economic analysis |
| PBR | Performance Based Rates |
| PEA | Preliminary Energy Audit |
| PF | Power Factor |
| PID | Proportional plus integral plus derivative (control system) |
| PM | Portfolio Manager in Energy Star rating system |
| PM | Preventive Maintenance |
| PoolCo | Power Pool Company or Organization |
| POU | Point of Use |
| PQ | Power Quality |
| PSC | Public Service Commission |
| PSIA psia | Pounds per square inch absolute (pressure) |
| PSIG psig | Pounds per square inch gauge (pressure) |
| PUC | Public Utility Commission |
| PUHCA | Public Utilities Holding Company Act of 1935 |
| PURPA | Public Utilities Regulatory Policies of 1978 |
| PV | Photovoltaic system |

Site Assessment Report - S537001;Moffet

| | |
|-------------------------------------|---|
| PV | Present Value |
| PW | Present Worth |
| PX | Power Exchange |
| q | Rate of heat flow in Btu per hour |
| Q | Heat load due to conduction using degree days |
| QF | Qualifying Facility |
| R | Electrical resistance |
| R | Thermal Resistance |
| RC | Remote controller |
| RCR | Room Cavity Ratio |
| RCRA | Resource Conservation and Recovery Act |
| Remaining Service Life (RSL) | RSL is the number of years service remaining for a system or equipment item. It is automatically calculated based on the difference between the current year and the 'Calculated Next Renewal' date or the 'Next Renewal' date whichever one is the later date. |
| Remaining Service Life Index (RSLI) | RSLI is defined as a percentage ratio of the remaining service life of a system. It usually ranges from 0 to 100 |
| REMR | Repair Evaluation Maintenance Rehabilitation (REMR) is a scale used to objectively rank systems based on their condition |
| Renewal Schedule | A timeline that provides the items that need repair the year in which the repair is needed and the estimated price of the renewal. |
| RH | Relative Humidity |
| RLA | Running Load Amps |
| RMS | Root Mean Square |
| RO | Reverse Osmosis |
| ROI | Return on Investment |
| RPM | Revolutions Per Minute |
| RTG | Regional Transmission Group |
| RTO | Regional Transmission Organization |
| RTP | Real Time Pricing |
| SBCCI | Southern Building Code Congress International |
| SC | Scheduling Coordinator |
| SC | Shading Coefficient |
| SCADA | Supervisory Control and Data Acquisition Systems |

Site Assessment Report - S537001;Moffet

| | |
|--------------|--|
| SEER | Seasonal Energy Efficiency Ratio |
| SHR | Sensible Heat Ratio |
| Site | The grounds and utilities roadways landscaping fencing and other typical land improvements needed to support the facility. |
| Soft Cost | An expense item that is not considered direct construction cost. Soft cost includes architectural engineering financing legal fees and other pre-and-post construction expenses. |
| SOx | Sulfur Oxide Compounds |
| SP | Static Pressure |
| SP SPB | Simple Payback |
| SPP | Simple Payback Period |
| SPP | Small Power Producers |
| STR | Stack Temperature Rise |
| SV | Specific Volume |
| System | System refers to building and related site work elements as described by ASTM Uniformat II Classification for Building Elements (E1557-97) a format for classifying major facility elements common to most buildings. Elements usually perform a given function regardless of the design specification construction method or materials used. See also Uniformat II. |
| T | Temperature |
| T | Tubular (lamps) |
| TAA | Technical Assistance Audit |
| TCP/IP | Transmission Control Protocol/Internet Protocol |
| TES | Thermal Energy Storage |
| THD | Total Harmonic Distortion |
| TOD | Time of Day |
| TOU | Time of Use |
| TQM | Total Quality Management |
| TransCo | Transmission Company |
| U | Thermal Conductance |
| UDC | Utility Distribution Company |
| UL | Underwriters Laboratories |
| UNIFORMAT II | The ASTM UNIFORMAT II Classification for Building Elements (E1557-97) a format for classifying major facility components common to most buildings. |
| USGBC | US Green Building Council |
| v | Specific Volume |

Site Assessment Report - S537001;Moffet

| | |
|------------|---|
| V | Volts Voltage |
| V | Volume |
| VAV | Variable Air Volume |
| VDT | Video Display Terminal |
| VFD | Variable Frequency Drive |
| VHO | Very High Output |
| VSD | Variable Speed Drive |
| W | Watts |
| W | Width |
| WB | Wet bulb |
| WH Wh | Watt Hours |
| Year built | The year that a building or addition was originally built based on substantial completion or occupancy. |
| Z | Electrical Impedance |