

## Facility Condition Assessment Summary Report

This report provides a summary of the Facility Condition Index (FCI) value of a school facility and select major building systems. The FCI calculation represents the cost of needed repairs divided by the replacement value. The FCI is a numerical value of condition and helps to identify the need for renewal or replacement of specific parts of the facility. The FCI is particularly useful when comparing similar facilities within the same portfolio.

### Morris School

|            |  |                     |                  |
|------------|--|---------------------|------------------|
| Governance | DISTRICT                                       | Report Type         | Elementarymiddle |
| Address    | 2600 W. Thompson St.<br>Philadelphia, Pa 19121 | Enrollment          | 289              |
| Phone/Fax  | 215-684-5087 / 215-684-8881                    | Grade Range         | '00-08'          |
| Website    | Www.Philasd.Org/Schools/Morris                 | Admissions Category | Neighborhood     |
|            |  | Turnaround Model    | N/A              |

### Building/System FCI Tiers

| Facility Condition Index (FCI) = $\frac{\text{Cost of Assessed Deficiencies}}{\text{Replacement Value}}$ |                               |   |   |  |
|--|-------------------------------|---|---|--|
| < 15%  | 15 to 25%                     | 25 to 45%   | 45 to 60%   | > 60%  |
| Buildings  |                               |   |   |  |
| Minimal Current Capital Funding Required   | Refurbish Systems in building | Replace Systems in building.                                  | Building should be considered for major renovation.                                   | Building should be considered for closing/replacement.   |
| Systems  |                               |   |   |  |
| Perform routine maintenance on system  | System requires minor repairs | System should be studied to determine repair vs. replacement. | System is nearing end of its life expectancy and should be considered for replacement | System should be replaced as part of the Capital Program |

### Building and Grounds

|                | FCI           | Repair Costs        | Replacement Cost    |
|----------------|---------------|---------------------|---------------------|
| <b>Overall</b> | <b>43.73%</b> | <b>\$17,443,349</b> | <b>\$39,886,142</b> |
| Building       | 43.44 %       | \$17,174,264        | \$39,540,104        |
| Grounds        | 77.76 %       | \$269,085           | \$346,038           |

### Major Building Systems

| Building System  | System FCI | Repair Costs | Replacement Cost |
|--|------------|--------------|------------------|
| <b>Roof</b> (Shows physical condition of roof)   | 89.35 %    | \$1,016,460  | \$1,137,600      |
| <b>Exterior Walls</b> (Shows condition of the structural condition of the exterior facade) | 26.24 %    | \$774,947    | \$2,952,800      |
| <b>Windows</b> (Shows functionality of exterior windows)                                   | 126.97 %   | \$1,829,388  | \$1,440,800      |
| <b>Exterior Doors</b> (Shows condition of exterior doors)                                  | 00.00 %    | \$0          | \$116,000        |
| <b>Interior Doors</b> (Classroom doors)  | 18.83 %    | \$52,874     | \$280,800        |
| <b>Interior Walls</b> (Paint and Finishes)   | 00.00 %    | \$0          | \$1,344,800      |
| <b>Plumbing Fixtures</b>   | 28.34 %    | \$306,507    | \$1,081,600      |
| <b>Boilers</b>   | 00.00 %    | \$0          | \$1,493,600      |
| <b>Chillers/Cooling Towers</b>   | 65.60 %    | \$1,284,765  | \$1,958,400      |
| <b>Radiators/Unit Ventilators/HVAC</b>   | 143.32 %   | \$4,929,100  | \$3,439,200      |
| <b>Heating/Cooling Controls</b>  | 158.90 %   | \$1,716,170  | \$1,080,000      |
| <b>Electrical Service and Distribution</b>   | 34.34 %    | \$266,481    | \$776,000        |
| <b>Lighting</b>  | 39.16 %    | \$1,086,416  | \$2,774,400      |
| <b>Communications and Security</b> (Cameras, Pa System and Fire Alarm)                     | 40.32 %    | \$418,974    | \$1,039,200      |

Please note that some FCIs may be over 100% because there are times when replacing a building system requires that other building systems be upgraded to complete the installation. A FCI of 0.0% represents that there are no current deficiencies with the associated system.


School District of Philadelphia

**S239001;Morris**

Final

**Site Assessment Report**

**January 31, 2017**



## Table of Contents

|   |    |
|---|----|
| Site Executive Summary                          | 4  |
| Site Condition Summary                          | 10 |
| <b><u>B239001:Morris</u></b>                    | 12 |
| Executive Summary                               | 12 |
| Condition Summary                               | 13 |
| Condition Detail                                | 14 |
| System Listing                                  | 15 |
| System Notes                                    | 17 |
| Renewal Schedule                                | 18 |
| Forecasted Sustainment Requirement              | 21 |
| Condition Index Forecast by Investment Scenario | 22 |
| Deficiency Summary By System                    | 23 |
| Deficiency Summary By Priority                  | 24 |
| Deficiency By Priority Investment               | 25 |
| Deficiency Summary By Category                  | 26 |
| Deficiency Details By Priority                  | 27 |
| Equipment Inventory Detail                      | 42 |
| <b><u>G239001:Grounds</u></b>                   | 43 |
| Executive Summary                               | 43 |
| Condition Summary                               | 44 |
| Condition Detail                                | 45 |
| System Listing                                  | 46 |
| System Notes                                    | 47 |
| Renewal Schedule                                | 48 |
| Forecasted Sustainment Requirement              | 49 |
| Condition Index Forecast by Investment Scenario | 50 |
| Deficiency Summary By System                    | 51 |
| Deficiency Summary By Priority                  | 52 |
| Deficiency By Priority Investment               | 53 |

## Site Assessment Report

---

|                                |    |
|--------------------------------|----|
| Deficiency Summary By Category | 54 |
| Deficiency Details By Priority | 55 |
| Equipment Inventory Detail     | 57 |
| Glossary                       | 58 |


## Site Executive Summary

The organization of this report, as displayed in the Table of Contents, follows the structure of the associated eCOMET database. The overall node for each school campus begins with the letter "S", which indicates the "Site" label. Each Site is comprised of separate "Building" and "Grounds" nodes; their asset names begin with the letters "B" and "G" respectively. Information rolls up to the Site node from the Building and Grounds nodes. This Site report combines facility information with subsections for the Buildings And Grounds nodes.

The basis for the evaluation of condition is the functional systems and elements of a building and grounds organized according to the UNIFORMAT II Elemental Classification. The grouping of these systems and elements and applying a current replacement value to them develops a representative building cost model. Cost Models are typically developed for similar building types and functions. Evaluation of systems and their elements takes into account their current replacement values, life cycles, installation dates and next renewal dates. Systems and their elements that are within their useful lives are further evaluated to identify current deficient conditions that may have a significant impact on a system's or element's remaining service life, and to determine if they are beyond their predicted expected life. The system's or element's current replacement value is based on RS Means Commercial Cost Data.

Following are the cost model's system details for this facility. The Replacement Value is the amount needed to replace the property of the same present value. The Current Repair Amount, also known as Condition Needs, represents the budgeted contractor installed costs plus owner's soft costs for the repair, replacement or renewal for a component or system level deficiency. It excludes contributing costs for other components or systems that might also be associated with the corrective actions due to packaging the work. Facility Condition Index (FCI) is an industry-standard measurement calculated as the ratio of the repair costs to correct a facility's deficiencies to the facility's Current Replacement Value. Condition Index (CI) for a system is calculated as the sum of the deficiencies divided by the sum of a system's Replacement Value (both values include soft-cost) expressed as a percentage ranging from 0% 100%.

|                    |                 |
|--------------------|-----------------|
| Gross Area (SF):   | 80,000          |
| Year Built:        | 1966            |
| Last Renovation:   | 2000            |
| Replacement Value: | \$39,886,142    |
| Repair Cost:       | \$17,443,349.28 |
| Total FCI:         | 43.73 %         |
| Total RSLI:        | 81.33 %         |



### Description:

Facility Assessment, July 2015

### School District of Philadelphia

### Morris Elementary School

2600 W Thompson St.

Philadelphia, PA 19121

80,000 SF / 795 Students / LN 03

The Morris Elementary school building is located at 2600 W. Thompson St. in Philadelphia, PA. The 4 story with partial basement, approximately 80,000 square foot building was originally constructed in 1966.

Mr. Derek Parker, Facility Area Coordinator provided input to the Parsons assessment team on current problems and planned renovation projects. Mr. Jason Adams, building engineer, accompanied us on our tour of the school and provided limited information



## Site Assessment Report - S239001;Morris

---

on the building systems and recent maintenance history.

### STRUCTURAL/ EXTERIOR CLOSURE:

The original building typically rests on concrete foundations and concrete bearing walls that are not showing signs of settlement. There are no signs of moisture penetration through basement walls

The main structure consists typically of combination of cast-in-place concrete columns, beams and concrete slabs in the basement; and structural steel framing, columns and bar joists supporting concrete slabs over metal deck. The roof structure consists of bar joists supporting metal deck. The superstructure is in good condition.

The building envelope is typically face brick masonry with CMU backup. It was renovated in 2005. In general, masonry is in fair to good condition with some missing mortar. The columns and girders are clad with cementitious panels to accentuate the structural grid. These panels are sealed to adjacent brick with sealant where mortar was missing; joints at panels' perimeter show substantial deterioration. Water penetration through walls has been reported.

The original building windows were replaced in 2000 with extruded aluminum double hung windows double glazed insulated glass. All windows are generally in poor condition with some of the windows inoperable; first floor windows have security screens in fair condition. The leaks around the windows perimeters have been reported and are evident.

The exterior doors are typically hollow metal doors and frames, painted. The doors are generally in fair condition; no weather-stripping is installed; some doors have vision glazing with security screens.

Roofing system is a built-up system approximately 15 to 20 years old and in fair condition; all roofing and flashing is typically in fair condition with some deterioration of the built-up system; leaks have not been reported.

### INTERIORS:

The building partition wall types include painted CMU; first floor corridors near main entrance are glazed brick. Partitions are generally in good condition.

Interior doors are generally solid core wood doors, some glazed, with hollow metal frames, some doors are missing closers. The doors leading to exit stairways are hollow metal doors and frames in good condition.

Fittings include toilet accessories and toilet partitions, generally in good condition, installed approximately in 2000, no accessible compartments; chalkboards in good condition. Handrails and ornamental metals are generally in good condition. Built-in cabinets are steel in good condition. Interior identifying signage is typically directly painted on wall or door surfaces generally in good condition.

The interior wall finishes in the original building are generally painted CMU. Generally, paint is in good condition throughout the building.

Most ceilings in the original building are 2x4 suspended acoustical panels and 1x1 concealed grid tiles. The suspension system and tile are old and approaching the end of their useful life.

Flooring in classrooms and auditorium is VAT (approximately 70% of floor area); the balance of the floor is VCT in Kindergarten and portion of the Auditorium installed in 2003; and painted concrete in toilets. Most flooring is in fair to good condition, however, the VAT tile flooring will need to be replaced at the end of its useful life; Library and principal's office has carpet in good condition.

Stair construction is generally concrete with cast iron non-slip treads in good condition.

Institutional and Commercial equipment includes: stage equipment, generally in good condition; A/V equipment in very good condition; gym equipment – basketball backstops, scoreboards, etc.; generally in fair condition. Other equipment includes kitchen equipment, generally in good condition.

Furnishings include fixed casework in classrooms, corridors and library, generally in fair to good condition; window shades/blinds, generally in good condition; fixed auditorium seating is original, generally in fair condition.

### CONVEYING SYSTEMS:

## Site Assessment Report - S239001;Morris

---

The building has a 12,000 lb traction elevator serving all floors; generally in good condition. The elevator motor is rated 75 hp, 240V DC. Elevator is not on emergency generator.

### PLUMBING:

Many of the original plumbing fixtures remain in service. Fixtures in the restrooms on each floor consist of wall mounted flush valve water closets, wall hung urinals, and lavatories with wheel handle faucets. With proper maintenance these fixtures should provide reliable service for the next 5-10 years. However, the older units should be replaced as part of any renovation of the spaces.

Drinking fountains in the corridors and at the restrooms are wall hung with integral refrigerated coolers. They are well beyond their service life and should be replaced.

A service sink is available in a janitor closet in the corridor on each floor for use by the janitorial staff.

The Cafeteria, classrooms converted into an eating space, has one sink: a three compartment stainless steel sink with lever operated faucets. There is no grease trap connected to the sink. No chemical dispensers present during the site visit.

A 4" city water service enters the building from N. Taney Street near the intersection with W. Thompson Street. The 4" meter and valves are located in the basement mechanical room on the west side of the building. Two Armstrong domestic water booster pumps, located in the mechanical room, ensure adequate water pressure for the building. The original domestic hot and cold water distribution piping was replaced with copper piping and sweat fittings. The maintenance staff reports no significant problems with scale build up in the domestic piping and the supply is adequate to the fixtures.

A 6" city gas service enters the building from N. Taney Street near the intersection with W. Thompson Street. The meter is 4" and located in the basement mechanical room. The gas main has a booster pump connected in the mechanical room.

One Bradford White gas fired, 75 gallon, vertical hot water heater with recirculating pump, installed in 2012, supplies hot water for domestic use. The unit is located in the boiler room on the basement level. The hot water heater is equipped with a T&P relief valve, and expansion tank. The domestic hot water heater is within its service life and should provide reliable service for the next 5-7 years. No water softener was seen in the boiler room.

The original storm and sanitary sewer piping is heavy weight cast iron with hub and spigot fittings. Downspouts from the roof run down the interior of the building and connect to the storm sewer system in the basement. A 12" sanitary line leaves the south side of the building through the boiler room.

A sewage ejector pit located in basement boiler room receives water from the basement area. It has two pumps that are beyond their service life. According to the Building Engineer one of the pumps was rebuilt in 2014. Both pumps and motors should be replaced. The pit is not sealed, but should be.

The maintenance staff reported mostly minor problems with the sanitary waste piping systems. However, the sewer piping has been in service for nearly 50 years and will require more frequent attention from the maintenance staff as time passes. The District should hire a qualified contractor to examine the sanitary waste piping using video cameras to locate and replace any damaged piping and to further quantify the extent of potential failures.

### MECHANICAL:

Building heating hot water is generated by two Buderus Logano GE615 cast iron sectional boilers with, net IBR rating of 3,463 Mbtu/hr, installed in approximately 2000. The building engineer did not know exact year. One boiler can handle the load in normal winter weather conditions; two units are required to bring the building up to temperature on very cold days. Each boiler is equipped with an Internal Combustion burner designed to operate on natural gas. Combustion air makeup is supplied by louvers equipped with motorized dampers. No major issues with the boilers were reported by the Building Engineer. Cast iron sectional boilers have an anticipated service life of 35 years or more; these units have been in service approximately 15 years. The boilers appear to have been maintained well. The District should provide reliable service for the next 15 to 20 years. The burners should be replaced as they are nearing the end of their service life and newer, more efficient technologies are available.

The heating hot water system is equipped with an expansion tank and air separator located in the boiler room. The hot water piping is covered with insulation and appears to be in good condition.

Unit ventilators provide heating for the majority of classrooms, offices, and indirectly to the hallways. The unit ventilators are original

## Site Assessment Report - S239001;Morris

---

to the building and well beyond their service life. Outdoor air for the building is provided by wall openings in the unit ventilators, which may not be sufficient to meet current codes for outdoor air ventilation. The existing unit ventilators should be removed and new units installed with hot and chilled water coils and integral heat exchangers to introduce sufficient outdoor air to the building.

Several of the classrooms in the school building have window air conditioning units that have an anticipated service life of only 10 years. Installing a 200 ton air-cooled chiller on the roof, with pumps located in the mechanical room, and chilled water distribution piping would supply more reliable air conditioning for the building with a much longer service life.

The school has mechanical ventilation in each classroom via unit ventilators and roof mounted exhaust fans serving the bathrooms. The space currently used as the Cafeteria only has two unit ventilators serving it, which is insufficient to meet the code required ventilation rates. Sufficient ventilation could be provided for the space designated as the Cafeteria by installing a constant volume air handling unit with distribution ductwork and registers. For the gymnasium a house fan and heating coil from the 1960s provide heating only. This could be replaced with a fan coil air handling unit with outdoor air ducted to the unit from louvers in the window openings. Similar ceiling hung units could be installed for the administrative offices. Currently the Auditorium is provided heating only by a house fan and heating coil from the 1960s. Ventilation could be provided for the Auditorium by installing a constant volume air handling unit with distribution ductwork and registers. These units would be equipped with hot water heating coils and chilled water cooling coils.

Exhaust for the restrooms is provided by two roof mounted exhaust fans. The existing roof mounted exhaust fans are beyond their service life and should be replaced.

The original pneumatic systems still provide basic control functions. Pneumatic room thermostats are intended to control the steam radiator control valves. In reality the radiator control valves are wide open and heating control is achieved via the boilers. Pneumatic control air is supplied from two Quincy compressors located in the boiler room. The maintenance staff reports no problems with oil, moisture or dirt in the pneumatic copper tubing. The pneumatic systems are beyond their service life and require too much attention from the maintenance staff. The original control valves and pneumatic actuators are beyond their service life and should be rebuilt or replaced. These controls should be converted to DDC.

A new building automation system (BAS) with modern DDC modules and communications network should be installed to serve the HVAC systems in this building to improve reliability and energy efficiency. An interface should be provided with the preferred system in use throughout the District.

The school building is NOT covered by an automatic sprinkler system. Installing a sprinkler system with quick response type heads should reduce insurance costs by providing protection for the property investment. A fire pump may be required depending on the available city water pressure. The building does have standpipe in the stairwells.

### ELECTRICAL:

Electrical Service- The electrical service is fed from a medium voltage overhead line on wooden poles along W Thompson St. The service enters the building underground to a 500 kVA, 2400V:208/120V substation.

With the addition of air conditioning to the school, the 500 kVA station transformer will not be large enough to carry the new load. A second substation will need to be installed to provide power for the air conditioning. It is recommended that a second feeder from the load side of the medium voltage service disconnect switch be installed to serve a new 2400V:480/277V substation.

Distribution System and Raceway System- The main distribution panel is rated 1600A, and is attached to the end of the substation. Electrical panels located on each floor are fed from this main distribution panel, and provides power to the receptacles and lighting on each floor. The second and third floor contains a panel to provide power to the unit ventilators located in the classrooms.

Receptacles- Classrooms are typically supplied with 4 receptacles. One additional receptacle should be added to each of these classrooms.

Lighting- Most of the building is outfitted with fluorescent fixtures with T-12 lamps, The auditorium contains incandescent lighting and compact fluorescent screw in type. The gymnasium has mercury vapor lamps. For the typical classroom, there is a mix of 2X4 lay in and 1X4 surface mounted, 3 lamp fluorescent lighting. Classroom lighting is typically controlled by inboard/outboard switching. Lighting levels in these areas do not meet IES (Illuminating Engineering Society) recommended levels. Classroom lighting levels were found to be in the range of 35 fc in classrooms (50 fc recommended), and 15 fc in the gym (50 fc recommended). There are some areas where lighting has been updated. Select classrooms and the media center lighting has T-8 lamps and lighting levels are above 50 fc. Lighting upgrade should be completed for the remaining parts of the school.



## Site Assessment Report - S239001;Morris

---

Fire Alarm System – The school has a 120V fire alarm system. The system consists of pull stations and bells located in the corridors only.

Telephone/LAN – The present telephone/LAN system is adequate.

Public Address/Intercom/Paging – An independent and separate PA system does not exist. School uses the telephone system for public announcement. Two way communication is not available through the public announcement system. Communication back to the office is through a wall mounted phone located in each classroom. This system is adequate and in working condition.

Clock and Program System – The present bell system is adequate, but classroom clocks do not function properly.

Television System – The facility is equipped with TV coax system, however there presently are no televisions in the classrooms.

Security System – There facility is equipped with door contacts. These contacts are installed on doors leading to the main corridors on the first floor. This includes doors from the stairwells, as well as first floor classrooms with windows.

Emergency Power System – A 18kW natural gas Katolight generator is housed in the basement of the school for emergency lighting. The generator is not currently adequate for the facility as it does not provide emergency power to the elevator.

Emergency Lighting System / Exit Lighting- The emergency lighting is provided by incandescent lamps connected to the generator. This lighting is not adequate and needs to be upgraded. The exit lighting is outdated incandescent and is not adequate.

Lightning Protection System- A lightning protection system exists on the roof but it does not provide adequate coverage.

Site Lighting - Site lighting is provided by building mounted flood lights installed around the entire perimeter of the school. The site lighting provides an adequate amount of lighting.

Video Surveillance – There are exterior cameras and cameras covering entrances, first floor lobby, and main office.

Site Paging – There are no exterior speakers for site paging.

Elevators – There is one passenger elevator in the facility. The elevator is a traction type with a 12,000 pound capacity. The elevator motor is rated 75 hp, 240V DC. Elevator is not on emergency generator.

### GROUNDS (SITE):

There is no parking lot at the site. Playground pavement adjacent to the building is in poor condition, paving is cracked and deteriorated; there is no playground equipment. Perimeter fence separating the playground from the street is generally in poor condition and rusting. There is no landscaping.

### ACCESSIBILITY:

Generally, the building has an accessible route per ADA requirements. However, toilets are not equipped with accessible fixtures, and accessories, such as grab bars, and accessible partitions. None of the doors in the building have ADA required door handles.

### RECOMMENDATIONS:

- Repair cracks in masonry, replace missing mortar, tuck-point – all walls including panels covering columns and girders
- Install all new roofing system including insulation within next 5 to 10 years; tear-down existing roofing; install flashing, and counter flashing
- Replace all windows within next 4 to 5 years
- Replace interior doors hardware for ADA accessibility
- Replace all VAT flooring including cove base within 10 years
- Replace existing carpet
- Replace all suspended acoustical ceilings
- Resurface playground paving.
- Replace original chain link fence and security gate
- Replace the twist-type handle lavatories in the restrooms with new code compliant fixtures.

## Site Assessment Report - S239001;Morris

---

- Replace existing sewage ejector pump system and piping in the basement as it is beyond its useful service life.
- Replace the wall hung drinking fountains and integral refrigerated coolers in the corridors and at the restrooms. These units are well beyond their service life.
- Hire a qualified contractor to perform a detailed examination of the sanitary waste piping using visual inspection and video cameras to locate and replace any damaged piping and to further quantify the extent of potential failures.
- Remove the existing unit ventilators and install units with hot and chilled water coils and integral heat exchangers to introduce outdoor air to the building.
- Remove the window air conditioning units and install a 200 ton air-cooled chiller on the roof with chilled water distribution piping and pumps located in the mechanical room to supply more reliable air conditioning for the building with a much longer service life.
- Replace existing exhaust fans on the roof serving the bathrooms and utilize the existing ductwork.
- Provide ventilation for the Cafeteria by installing a constant volume air handling unit with distribution ductwork and registers.
- Provide ventilation for the gymnasium by installing a fan coil air handling unit hung from the structure with outdoor air ducted to the unit from louvers in the window openings.
- Provide ventilation for the administrative offices by installing a fan coil air handling unit hung from the structure with outdoor air ducted to the unit from louvers in window openings.
- Provide ventilation for the Auditorium by installing a fan coil air handling unit hung from the structure with outdoor air ducted to the unit from louvers in window openings.
- Replace the pneumatic controls for the HVAC systems with modern DDC modules, valves and actuators to improve reliability and energy efficiency. Provide a new building automation system (BAS) with communication interface to the preferred system in use throughout the District.
- Install a fire protection sprinkler system with quick response type heads to reduce insurance costs by providing protection for the property. A fire pump may be required depending on the available city water pressure.
- Install minimum two receptacles on each wall of class rooms and other purpose rooms.
- Complete lighting upgrade
- Install a new addressable fire alarm system and provide audible and/or visual devices in all areas.
- Provide new emergency lighting.
- Provide new exit lighting.
- Replace existing generator with larger generator sized to operate the elevator.
- Install a second substation to serve new air conditioning equipment.

### Attributes:

#### General Attributes:

|          |                 |              |              |
|----------|-----------------|--------------|--------------|
| Active:  | Open            | Bldg Lot Tm: | Lot 1 / Tm 4 |
| Status:  | Accepted by SDP | Team:        | Tm 4         |
| Site ID: | S239001         |              |              |

## Site Condition Summary

The Table below shows the CI and FCI for each major system shown at the UNIFORMAT classification Level II. Note that Systems with lower FCIs require less investment than systems with higher FCIs.


### Current Investment Requirement and Condition by Uniformat Classification

| UNIFORMAT Classification        | RSLI%          | FCI %          | Current Repair         |
|---------------------------------|----------------|----------------|------------------------|
| A10 - Foundations               | 51.00 %        | 0.00 %         | \$0.00                 |
| A20 - Basement Construction     | 51.00 %        | 0.00 %         | \$0.00                 |
| B10 - Superstructure            | 51.00 %        | 0.00 %         | \$0.00                 |
| B20 - Exterior Enclosure        | 54.39 %        | 57.75 %        | \$2,604,335.64         |
| B30 - Roofing                   | 125.00 %       | 89.35 %        | \$1,016,460.33         |
| C10 - Interior Construction     | 50.53 %        | 2.69 %         | \$52,874.10            |
| C20 - Stairs                    | 51.00 %        | 0.00 %         | \$0.00                 |
| C30 - Interior Finishes         | 127.93 %       | 50.89 %        | \$1,843,246.71         |
| D10 - Conveying                 | 28.57 %        | 0.00 %         | \$0.00                 |
| D20 - Plumbing                  | 52.69 %        | 41.44 %        | \$676,921.74           |
| D30 - HVAC                      | 91.80 %        | 89.11 %        | \$7,930,035.01         |
| D40 - Fire Protection           | 105.71 %       | 177.49 %       | \$1,144,434.28         |
| D50 - Electrical                | 109.31 %       | 40.53 %        | \$1,905,956.54         |
| E10 - Equipment                 | 157.14 %       | 0.00 %         | \$0.00                 |
| E20 - Furnishings               | 137.50 %       | 0.00 %         | \$0.00                 |
| G20 - Site Improvements         | 90.77 %        | 104.88 %       | \$269,084.93           |
| G40 - Site Electrical Utilities | 50.00 %        | 0.00 %         | \$0.00                 |
| <b>Totals:</b>                  | <b>81.33 %</b> | <b>43.73 %</b> | <b>\$17,443,349.28</b> |

### Condition Deficiency Priority

| Facility Name   | Gross Area (S.F.) | FCI %        | 1 - Response Time (< 2 yr) | 2 - Response Time (2-3 yrs) | 3 - Response Time (3-4 yrs) | 4 - Response Time (4-5 yrs) | 5 - Response Time (> 5 yrs) |
|-----------------|-------------------|--------------|----------------------------|-----------------------------|-----------------------------|-----------------------------|-----------------------------|
| B239001;Morris  | 80,000            | 43.44        | \$1,144,434.28             | \$774,947.33                | \$3,945,399.95              | \$4,455,054.03              | \$6,854,428.76              |
| G239001;Grounds | 15,400            | 77.76        | \$0.00                     | \$0.00                      | \$245,173.68                | \$0.00                      | \$23,911.25                 |
| <b>Total:</b>   |                   | <b>43.73</b> | <b>\$1,144,434.28</b>      | <b>\$774,947.33</b>         | <b>\$4,190,573.63</b>       | <b>\$4,455,054.03</b>       | <b>\$6,878,340.01</b>       |

### Deficiencies By Priority



## Executive Summary

Building condition is evaluated based on the functional systems and elements of a building and organized according to the UNIFORMAT II Elemental Classification. The grouping of these systems and elements and applying a current replacement value to them develops a representative building cost model. Cost Models are developed for similar building types and functions. Systems and their elements are evaluated based on their current replacement values, life cycles, installation dates and next renewal dates. Systems and their elements that are within their useful lives are further evaluated to identify current deficient conditions that may have a significant impact on a system's or element's remaining service life, and to determine if they are beyond their predicted expected life. The system's or element's current replacement value is based on RS Means Commercial Cost Data.

Following are the cost model's system details for this facility. The Replacement Value is the amount needed to replace the property of the same present value. The Current Repair Amount, also known as Condition Needs, represents the budgeted contractor installed costs plus owner's soft costs for the repair, replacement or renewal for a component or system level deficiency. It excludes contributing costs for other components or systems that might also be associated with the corrective actions due to packaging the work. Facility Condition Index (FCI) FCI is an industry-standard measurement of facility condition calculated as the ratio of the costs to correct a facility's deficiencies to the facility's Current Replacement Value. It ranges from 0% (new) to 100% (very poor). Condition Index (CI) is calculated as the sum of a renewable system's Remaining Service Life (RSL) divided by the sum of a system's Replacement Value (both values exclude soft-cost to simplify calculation updates) expressed as a percentage ranging from 100% (new) to 0% (expired).

|                    |                   |
|--------------------|-------------------|
| Function:          | Elementary School |
| Gross Area (SF):   | 80,000            |
| Year Built:        | 1966              |
| Last Renovation:   | 2000              |
| Replacement Value: | \$39,540,104      |
| Repair Cost:       | \$17,174,264.35   |
| Total FCI:         | 43.44 %           |
| Total RSLI:        | 81.34 %           |

### Description:

### Attributes:

#### General Attributes:

|                 |         |          |                 |
|-----------------|---------|----------|-----------------|
| Active:         | Open    | Bldg ID: | B239001         |
| Sewage Ejector: | Yes     | Status:  | Accepted by SDP |
| Site ID:        | S239001 |          |                 |



## Condition Summary

The Table below shows the CI and FCI for each major building system shown at the UNIFORMAT classification Level II. Note that Systems with lower FCIs require less investment than systems with higher FCIs.

| UNIFORMAT Classification    | RSI %          | FCI %          | Current Repair Cost    |
|-----------------------------|----------------|----------------|------------------------|
| A10 - Foundations           | 51.00 %        | 0.00 %         | \$0.00                 |
| A20 - Basement Construction | 51.00 %        | 0.00 %         | \$0.00                 |
| B10 - Superstructure        | 51.00 %        | 0.00 %         | \$0.00                 |
| B20 - Exterior Enclosure    | 54.39 %        | 57.75 %        | \$2,604,335.64         |
| B30 - Roofing               | 125.00 %       | 89.35 %        | \$1,016,460.33         |
| C10 - Interior Construction | 50.53 %        | 2.69 %         | \$52,874.10            |
| C20 - Stairs                | 51.00 %        | 0.00 %         | \$0.00                 |
| C30 - Interior Finishes     | 127.93 %       | 50.89 %        | \$1,843,246.71         |
| D10 - Conveying             | 28.57 %        | 0.00 %         | \$0.00                 |
| D20 - Plumbing              | 52.69 %        | 41.44 %        | \$676,921.74           |
| D30 - HVAC                  | 91.80 %        | 89.11 %        | \$7,930,035.01         |
| D40 - Fire Protection       | 105.71 %       | 177.49 %       | \$1,144,434.28         |
| D50 - Electrical            | 109.31 %       | 40.53 %        | \$1,905,956.54         |
| E10 - Equipment             | 157.14 %       | 0.00 %         | \$0.00                 |
| E20 - Furnishings           | 137.50 %       | 0.00 %         | \$0.00                 |
| <b>Totals:</b>              | <b>81.34 %</b> | <b>43.44 %</b> | <b>\$17,174,264.35</b> |

## Condition Detail

This section of the report contains results of the Facility Condition Assessment. The building is separated into system components based on UNIFORMAT II classification. The columns in the System Listing table below represent the following:

1. System Code: A code that identifies the system.
2. System Description: A brief description of a system present in the building.
3. Unit Price \$: The unit price of the system.
4. UoM: The unit of measure for of the system.
5. Qty: The quantity for the system
6. Life: anticipated service life for the system based on Building Owners and Managers Association (BOMA) recommendations.
7. Year Installed: The date of system installation.
8. Calc Next Renewal Year: The date of system expiration based on the life, NR stands for non renewable.
9. Next Renewal Year: The suggested system expiration date by the assessor based on visual inspection.
10. CI: The Condition Index of the system.
11. FCI: The Facility Condition Index of the system.
12. RSL: Remaining Service Life.
13. eCR: eCOMET Condition Rating (not used).
14. Deficiency \$: The financial investment to repair/replace system.

## System Listing

The System Listing table below lists each of the systems organized by their UNIFORMAT II classification. The assessment team was tasked with recording the most recent replacement year of each system, determining the remaining service life based on the theoretical life, and evaluating the condition to confirm the forecast next replacement year. The system listing is the basis for all data contained in the Building Assessment Report.

Additionally, a condition rating (eCR) based on the following guidelines is provided as observed at the time of the assessment.

- Excellent (E) - No noticeable distress or damage. The entire system is free from observable defect.
- Very Good (VG) - Overall no serviceability reduction for the entire system. No degradation of critical components and minor distress and defect noticeable for some but not non critical components within the system.
- Good (G) - Slight or no serviceability reduction for the entire system. There may be noticeable defects for some non critical components and slight noticeable degradation of the critical components.
- Fair (F) - Overall serviceability is degraded but adequate. There may be moderate deterioration for very few of the critical components and few of the non critical components may have severe degradation.
- Marginal (MA) - Overall serviceability and reliability loss. Most if not all of the non critical components suffer from severe degradation and a few of the critical component may have severe degradation.
- Moderate (MO) - Overall a significant serviceability loss. Most if not all the components have severe degradation with the reminder of the component showing visible distress.
- Very Poor (VP) - Overall the system is barely functional. All of the components are severely degraded.
- Non-Functional (NF) - Overall the system does not function with all the components having no serviceability and suffer from severe degradation.

| System Code | System Description      | Unit Price \$ | UoM  | Qty    | Life | Year Installed | Calc Next Renewal Year | Next Renewal Year | RSLT%    | FCI%     | RSL | eCR | Deficiency \$  | Replacement Value \$ |
|-------------|-------------------------|---------------|------|--------|------|----------------|------------------------|-------------------|----------|----------|-----|-----|----------------|----------------------|
| A1010       | Standard Foundations    | \$18.40       | S.F. | 80,000 | 100  | 1966           | 2066                   |                   | 51.00 %  | 0.00 %   | 51  |     |                | \$1,472,000          |
| A1030       | Slab on Grade           | \$7.73        | S.F. | 80,000 | 100  | 1966           | 2066                   |                   | 51.00 %  | 0.00 %   | 51  |     |                | \$618,400            |
| A2010       | Basement Excavation     | \$6.55        | S.F. | 80,000 | 100  | 1966           | 2066                   |                   | 51.00 %  | 0.00 %   | 51  |     |                | \$524,000            |
| A2020       | Basement Walls          | \$12.70       | S.F. | 80,000 | 100  | 1966           | 2066                   |                   | 51.00 %  | 0.00 %   | 51  |     |                | \$1,016,000          |
| B1010       | Floor Construction      | \$75.10       | S.F. | 80,000 | 100  | 1966           | 2066                   |                   | 51.00 %  | 0.00 %   | 51  |     |                | \$6,008,000          |
| B1020       | Roof Construction       | \$13.88       | S.F. | 80,000 | 100  | 1966           | 2066                   |                   | 51.00 %  | 0.00 %   | 51  |     |                | \$1,110,400          |
| B2010       | Exterior Walls          | \$36.91       | S.F. | 80,000 | 100  | 1966           | 2066                   |                   | 51.00 %  | 26.24 %  | 51  |     | \$774,947.33   | \$2,952,800          |
| B2020       | Exterior Windows        | \$18.01       | S.F. | 80,000 | 40   | 2000           | 2040                   |                   | 62.50 %  | 126.97 % | 25  |     | \$1,829,388.31 | \$1,440,800          |
| B2030       | Exterior Doors          | \$1.45        | S.F. | 80,000 | 25   | 2000           | 2025                   |                   | 40.00 %  | 0.00 %   | 10  |     |                | \$116,000            |
| B3010105    | Built-Up                | \$37.76       | S.F. | 30,000 | 20   | 2000           | 2020                   | 2040              | 125.00 % | 89.73 %  | 25  |     | \$1,016,460.33 | \$1,132,800          |
| B3010120    | Single Ply Membrane     | \$38.73       | S.F. |        | 20   | 1966           | 1986                   |                   | 0.00 %   | 0.00 %   | -29 |     |                | \$0                  |
| B3010130    | Preformed Metal Roofing | \$54.22       | S.F. |        | 30   | 1966           | 1996                   |                   | 0.00 %   | 0.00 %   | -19 |     |                | \$0                  |
| B3010140    | Shingle & Tile          | \$38.73       | S.F. |        | 25   | 1966           | 1991                   |                   | 0.00 %   | 0.00 %   | -24 |     |                | \$0                  |
| B3020       | Roof Openings           | \$0.06        | S.F. | 80,000 | 20   | 1966           | 1986                   | 2040              | 125.00 % | 0.00 %   | 25  |     |                | \$4,800              |
| C1010       | Partitions              | \$17.91       | S.F. | 80,000 | 100  | 1966           | 2066                   |                   | 51.00 %  | 0.00 %   | 51  |     |                | \$1,432,800          |
| C1020       | Interior Doors          | \$3.51        | S.F. | 80,000 | 40   | 1990           | 2030                   |                   | 37.50 %  | 18.83 %  | 15  |     | \$52,874.10    | \$280,800            |
| C1030       | Fittings                | \$3.12        | S.F. | 80,000 | 40   | 2000           | 2040                   |                   | 62.50 %  | 0.00 %   | 25  |     |                | \$249,600            |
| C2010       | Stair Construction      | \$1.41        | S.F. | 80,000 | 100  | 1966           | 2066                   |                   | 51.00 %  | 0.00 %   | 51  |     |                | \$112,800            |

# Site Assessment Report - B239001;Morris

| System Code  | System Description              | Unit Price \$ | UoM  | Qty    | Life | Year Installed | Calc Next Renewal Year | Next Renewal Year | RSLI%          | FCI%           | RSL | eCR | Deficiency \$          | Replacement Value \$ |
|--------------|---------------------------------|---------------|------|--------|------|----------------|------------------------|-------------------|----------------|----------------|-----|-----|------------------------|----------------------|
| C3010230     | Paint & Covering                | \$13.21       | S.F. | 80,000 | 10   | 2012           | 2022                   | 2032              | 170.00 %       | 0.00 %         | 17  |     |                        | \$1,056,800          |
| C3010231     | Vinyl Wall Covering             | \$0.97        | S.F. | 80,000 | 15   | 1966           | 1981                   | 2028              | 86.67 %        | 0.00 %         | 13  |     |                        | \$77,600             |
| C3010232     | Wall Tile                       | \$2.63        | S.F. | 80,000 | 30   | 1966           | 1996                   | 2030              | 50.00 %        | 0.00 %         | 15  |     |                        | \$210,400            |
| C3020411     | Carpet                          | \$7.30        | S.F. | 2,800  | 10   | 2000           | 2010                   | 2022              | 70.00 %        | 153.30 %       | 7   |     | \$31,334.14            | \$20,440             |
| C3020412     | Terrazzo & Tile                 | \$75.52       | S.F. |        | 50   |                |                        |                   | 0.00 %         | 0.00 %         |     |     |                        | \$0                  |
| C3020413     | Vinyl Flooring                  | \$9.68        | S.F. | 59,800 | 20   | 1966           | 1986                   | 2037              | 110.00 %       | 156.68 %       | 22  |     | \$906,966.75           | \$578,864            |
| C3020414     | Wood Flooring                   | \$22.27       | S.F. |        | 25   |                |                        |                   | 0.00 %         | 0.00 %         |     |     |                        | \$0                  |
| C3020415     | Concrete Floor Finishes         | \$0.97        | S.F. |        | 50   |                |                        |                   | 0.00 %         | 0.00 %         |     |     |                        | \$0                  |
| C3030        | Ceiling Finishes                | \$20.97       | S.F. | 80,000 | 25   | 1995           | 2020                   | 2045              | 120.00 %       | 53.94 %        | 30  |     | \$904,945.82           | \$1,677,600          |
| D1010        | Elevators and Lifts             | \$1.53        | S.F. | 80,000 | 35   | 1990           | 2025                   |                   | 28.57 %        | 0.00 %         | 10  |     |                        | \$122,400            |
| D2010        | Plumbing Fixtures               | \$13.52       | S.F. | 80,000 | 35   | 1980           | 2015                   | 2028              | 37.14 %        | 28.34 %        | 13  |     | \$306,507.25           | \$1,081,600          |
| D2020        | Domestic Water Distribution     | \$1.68        | S.F. | 80,000 | 25   | 1980           | 2005                   | 2025              | 40.00 %        | 0.00 %         | 10  |     |                        | \$134,400            |
| D2030        | Sanitary Waste                  | \$2.90        | S.F. | 80,000 | 25   | 1966           | 1991                   | 2042              | 108.00 %       | 159.66 %       | 27  |     | \$370,414.49           | \$232,000            |
| D2040        | Rain Water Drainage             | \$2.32        | S.F. | 80,000 | 30   | 1966           | 1996                   | 2040              | 83.33 %        | 0.00 %         | 25  |     |                        | \$185,600            |
| D3020        | Heat Generating Systems         | \$18.67       | S.F. | 80,000 | 35   | 2000           | 2035                   |                   | 57.14 %        | 0.00 %         | 20  |     |                        | \$1,493,600          |
| D3030        | Cooling Generating Systems      | \$24.48       | S.F. | 80,000 | 30   |                |                        | 2047              | 106.67 %       | 65.60 %        | 32  |     | \$1,284,765.21         | \$1,958,400          |
| D3040        | Distribution Systems            | \$42.99       | S.F. | 80,000 | 25   | 1966           | 1991                   | 2042              | 108.00 %       | 143.32 %       | 27  |     | \$4,929,100.01         | \$3,439,200          |
| D3050        | Terminal & Package Units        | \$11.60       | S.F. | 80,000 | 20   | 1966           | 1986                   | 2022              | 35.00 %        | 0.00 %         | 7   |     |                        | \$928,000            |
| D3060        | Controls & Instrumentation      | \$13.50       | S.F. | 80,000 | 20   | 1966           | 1986                   | 2037              | 110.00 %       | 158.90 %       | 22  |     | \$1,716,169.79         | \$1,080,000          |
| D4010        | Sprinklers                      | \$7.05        | S.F. | 80,000 | 35   |                |                        | 2052              | 105.71 %       | 202.91 %       | 37  |     | \$1,144,434.28         | \$564,000            |
| D4020        | Standpipes                      | \$1.01        | S.F. | 80,000 | 35   |                |                        | 2052              | 105.71 %       | 0.00 %         | 37  |     |                        | \$80,800             |
| D5010        | Electrical Service/Distribution | \$9.70        | S.F. | 80,000 | 30   | 1966           | 1996                   | 2047              | 106.67 %       | 34.34 %        | 32  |     | \$266,481.47           | \$776,000            |
| D5020        | Lighting and Branch Wiring      | \$34.68       | S.F. | 80,000 | 20   | 1966           | 1986                   | 2037              | 110.00 %       | 39.16 %        | 22  |     | \$1,086,416.47         | \$2,774,400          |
| D5030        | Communications and Security     | \$12.99       | S.F. | 80,000 | 15   | 1966           | 1981                   | 2032              | 113.33 %       | 40.32 %        | 17  |     | \$418,974.17           | \$1,039,200          |
| D5090        | Other Electrical Systems        | \$1.41        | S.F. | 80,000 | 30   | 1966           | 1996                   | 2037              | 73.33 %        | 118.87 %       | 22  |     | \$134,084.43           | \$112,800            |
| E1020        | Institutional Equipment         | \$4.82        | S.F. | 80,000 | 35   | 2000           | 2035                   | 2070              | 157.14 %       | 0.00 %         | 55  |     |                        | \$385,600            |
| E1090        | Other Equipment                 | \$11.10       | S.F. | 80,000 | 35   | 2000           | 2035                   | 2070              | 157.14 %       | 0.00 %         | 55  |     |                        | \$888,000            |
| E2010        | Fixed Furnishings               | \$2.13        | S.F. | 80,000 | 40   | 1990           | 2030                   | 2070              | 137.50 %       | 0.00 %         | 55  |     |                        | \$170,400            |
| <b>Total</b> |                                 |               |      |        |      |                |                        |                   | <b>81.34 %</b> | <b>43.44 %</b> |     |     | <b>\$17,174,264.35</b> | <b>\$39,540,104</b>  |

## System Notes

The facility description in the site executive summary contains an overview of each system. The notes listed below provide additional information on select systems found within the facility.

---

|                |                       |                                |
|----------------|-----------------------|--------------------------------|
| <b>System:</b> | C3010 - Wall Finishes | This system contains no images |
| <b>Note:</b>   | Painted CMU 100%      |                                |

---

|                |                        |                                |
|----------------|------------------------|--------------------------------|
| <b>System:</b> | C3020 - Floor Finishes | This system contains no images |
| <b>Note:</b>   | VAT tile 70%           |                                |
|                | VCT tile 15%           |                                |
|                | Carpet 4%              |                                |



## Renewal Schedule

eCOMET forecasts future Capital Renewal funding needed to address expiring systems based on the Next Renewal year found in the Cost Models. A 3% annual inflation factor is applied to the costs for systems expiring in future years. The table below reflects recommended Capital Renewal funding needs over the next 10 years. Note: Cells with a zero value indicate systems for which renewal is not scheduled in that year.

*Inflation Rate: 3%*

| System                                    | Current Deficiencies | 2016       | 2017       | 2018       | 2019       | 2020       | 2021       | 2022               | 2023       | 2024       | 2025             | Total               |
|---|----------------------|------------|------------|------------|------------|------------|------------|--------------------|------------|------------|------------------|---------------------|
| <b>Total:</b>                             | <b>\$17,174,264</b>  | <b>\$0</b> | <b>\$0</b> | <b>\$0</b> | <b>\$0</b> | <b>\$0</b> | <b>\$0</b> | <b>\$1,283,108</b> | <b>\$0</b> | <b>\$0</b> | <b>\$551,113</b> | <b>\$19,008,485</b> |
| <b>* A - Substructure</b>                 | \$0                  | \$0        | \$0        | \$0        | \$0        | \$0        | \$0        | \$0                | \$0        | \$0        | \$0              | \$0                 |
| <b>A10 - Foundations</b>                  | \$0                  | \$0        | \$0        | \$0        | \$0        | \$0        | \$0        | \$0                | \$0        | \$0        | \$0              | \$0                 |
| <b>A1010 - Standard Foundations</b>       | \$0                  | \$0        | \$0        | \$0        | \$0        | \$0        | \$0        | \$0                | \$0        | \$0        | \$0              | \$0                 |
| <b>A1030 - Slab on Grade</b>              | \$0                  | \$0        | \$0        | \$0        | \$0        | \$0        | \$0        | \$0                | \$0        | \$0        | \$0              | \$0                 |
| <b>A20 - Basement Construction</b>        | \$0                  | \$0        | \$0        | \$0        | \$0        | \$0        | \$0        | \$0                | \$0        | \$0        | \$0              | \$0                 |
| <b>A2010 - Basement Excavation</b>        | \$0                  | \$0        | \$0        | \$0        | \$0        | \$0        | \$0        | \$0                | \$0        | \$0        | \$0              | \$0                 |
| <b>A2020 - Basement Walls</b>             | \$0                  | \$0        | \$0        | \$0        | \$0        | \$0        | \$0        | \$0                | \$0        | \$0        | \$0              | \$0                 |
| <b>B - Shell</b>                          | \$0                  | \$0        | \$0        | \$0        | \$0        | \$0        | \$0        | \$0                | \$0        | \$0        | \$0              | \$0                 |
| <b>B10 - Superstructure</b>               | \$0                  | \$0        | \$0        | \$0        | \$0        | \$0        | \$0        | \$0                | \$0        | \$0        | \$0              | \$0                 |
| <b>B1010 - Floor Construction</b>         | \$0                  | \$0        | \$0        | \$0        | \$0        | \$0        | \$0        | \$0                | \$0        | \$0        | \$0              | \$0                 |
| <b>B1020 - Roof Construction</b>          | \$0                  | \$0        | \$0        | \$0        | \$0        | \$0        | \$0        | \$0                | \$0        | \$0        | \$0              | \$0                 |
| <b>B20 - Exterior Enclosure</b>           | \$0                  | \$0        | \$0        | \$0        | \$0        | \$0        | \$0        | \$0                | \$0        | \$0        | \$0              | \$0                 |
| <b>B2010 - Exterior Walls</b>             | \$774,947            | \$0        | \$0        | \$0        | \$0        | \$0        | \$0        | \$0                | \$0        | \$0        | \$0              | \$774,947           |
| <b>B2020 - Exterior Windows</b>           | \$1,829,388          | \$0        | \$0        | \$0        | \$0        | \$0        | \$0        | \$0                | \$0        | \$0        | \$0              | \$1,829,388         |
| <b>B2030 - Exterior Doors</b>             | \$0                  | \$0        | \$0        | \$0        | \$0        | \$0        | \$0        | \$0                | \$0        | \$0        | \$171,484        | \$171,484           |
| <b>B30 - Roofing</b>                      | \$0                  | \$0        | \$0        | \$0        | \$0        | \$0        | \$0        | \$0                | \$0        | \$0        | \$0              | \$0                 |
| <b>B3010 - Roof Coverings</b>             | \$0                  | \$0        | \$0        | \$0        | \$0        | \$0        | \$0        | \$0                | \$0        | \$0        | \$0              | \$0                 |
| <b>B3010105 - Built-Up</b>                | \$1,016,460          | \$0        | \$0        | \$0        | \$0        | \$0        | \$0        | \$0                | \$0        | \$0        | \$0              | \$1,016,460         |
| <b>B3010120 - Single Ply Membrane</b>     | \$0                  | \$0        | \$0        | \$0        | \$0        | \$0        | \$0        | \$0                | \$0        | \$0        | \$0              | \$0                 |
| <b>B3010130 - Preformed Metal Roofing</b> | \$0                  | \$0        | \$0        | \$0        | \$0        | \$0        | \$0        | \$0                | \$0        | \$0        | \$0              | \$0                 |
| <b>B3010140 - Shingle &amp; Tile</b>      | \$0                  | \$0        | \$0        | \$0        | \$0        | \$0        | \$0        | \$0                | \$0        | \$0        | \$0              | \$0                 |
| <b>B3020 - Roof Openings</b>              | \$0                  | \$0        | \$0        | \$0        | \$0        | \$0        | \$0        | \$0                | \$0        | \$0        | \$0              | \$0                 |
| <b>C - Interiors</b>                      | \$0                  | \$0        | \$0        | \$0        | \$0        | \$0        | \$0        | \$0                | \$0        | \$0        | \$0              | \$0                 |
| <b>C10 - Interior Construction</b>        | \$0                  | \$0        | \$0        | \$0        | \$0        | \$0        | \$0        | \$0                | \$0        | \$0        | \$0              | \$0                 |
| <b>C1010 - Partitions</b>                 | \$0                  | \$0        | \$0        | \$0        | \$0        | \$0        | \$0        | \$0                | \$0        | \$0        | \$0              | \$0                 |

# Site Assessment Report - B239001;Morris

|                                     |             |     |     |     |     |     |     |             |     |     |           |             |
|-------------------------------------|-------------|-----|-----|-----|-----|-----|-----|-------------|-----|-----|-----------|-------------|
| C1020 - Interior Doors              | \$52,874    | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0         | \$0 | \$0 | \$0       | \$52,874    |
| C1030 - Fittings                    | \$0         | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0         | \$0 | \$0 | \$0       | \$0         |
| C20 - Stairs                        | \$0         | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0         | \$0 | \$0 | \$0       | \$0         |
| C2010 - Stair Construction          | \$0         | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0         | \$0 | \$0 | \$0       | \$0         |
| C30 - Interior Finishes             | \$0         | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0         | \$0 | \$0 | \$0       | \$0         |
| C3010 - Wall Finishes               | \$0         | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0         | \$0 | \$0 | \$0       | \$0         |
| C3010230 - Paint & Covering         | \$0         | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0         | \$0 | \$0 | \$0       | \$0         |
| C3010231 - Vinyl Wall Covering      | \$0         | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0         | \$0 | \$0 | \$0       | \$0         |
| C3010232 - Wall Tile                | \$0         | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0         | \$0 | \$0 | \$0       | \$0         |
| C3020 - Floor Finishes              | \$0         | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0         | \$0 | \$0 | \$0       | \$0         |
| C3020411 - Carpet                   | \$31,334    | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$27,652    | \$0 | \$0 | \$0       | \$58,987    |
| C3020412 - Terrazzo & Tile          | \$0         | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0         | \$0 | \$0 | \$0       | \$0         |
| C3020413 - Vinyl Flooring           | \$906,967   | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0         | \$0 | \$0 | \$0       | \$906,967   |
| C3020414 - Wood Flooring            | \$0         | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0         | \$0 | \$0 | \$0       | \$0         |
| C3020415 - Concrete Floor Finishes  | \$0         | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0         | \$0 | \$0 | \$0       | \$0         |
| C3030 - Ceiling Finishes            | \$904,946   | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0         | \$0 | \$0 | \$0       | \$904,946   |
| D - Services                        | \$0         | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0         | \$0 | \$0 | \$0       | \$0         |
| D10 - Conveying                     | \$0         | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0         | \$0 | \$0 | \$0       | \$0         |
| D1010 - Elevators and Lifts         | \$0         | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0         | \$0 | \$0 | \$180,945 | \$180,945   |
| D20 - Plumbing                      | \$0         | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0         | \$0 | \$0 | \$0       | \$0         |
| D2010 - Plumbing Fixtures           | \$306,507   | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0         | \$0 | \$0 | \$0       | \$306,507   |
| D2020 - Domestic Water Distribution | \$0         | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0         | \$0 | \$0 | \$198,685 | \$198,685   |
| D2030 - Sanitary Waste              | \$370,414   | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0         | \$0 | \$0 | \$0       | \$370,414   |
| D2040 - Rain Water Drainage         | \$0         | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0         | \$0 | \$0 | \$0       | \$0         |
| D30 - HVAC                          | \$0         | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0         | \$0 | \$0 | \$0       | \$0         |
| D3020 - Heat Generating Systems     | \$0         | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0         | \$0 | \$0 | \$0       | \$0         |
| D3030 - Cooling Generating Systems  | \$1,284,765 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0         | \$0 | \$0 | \$0       | \$1,284,765 |
| D3040 - Distribution Systems        | \$4,929,100 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0         | \$0 | \$0 | \$0       | \$4,929,100 |
| D3050 - Terminal & Package Units    | \$0         | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$1,255,455 | \$0 | \$0 | \$0       | \$1,255,455 |
| D3060 - Controls & Instrumentation  | \$1,716,170 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0         | \$0 | \$0 | \$0       | \$1,716,170 |
| D40 - Fire Protection               | \$0         | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0         | \$0 | \$0 | \$0       | \$0         |
| D4010 - Sprinklers                  | \$1,144,434 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0         | \$0 | \$0 | \$0       | \$1,144,434 |
| D4020 - Standpipes                  | \$0         | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0         | \$0 | \$0 | \$0       | \$0         |


## Site Assessment Report - B239001;Morris

|   |             |     |     |     |     |     |     |     |     |     |     |             |
|---|-------------|-----|-----|-----|-----|-----|-----|-----|-----|-----|-----|-------------|
| D50 - Electrical                        | \$0         | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0         |
| D5010 - Electrical Service/Distribution | \$266,481   | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$266,481   |
| D5020 - Lighting and Branch Wiring      | \$1,086,416 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$1,086,416 |
| D5030 - Communications and Security     | \$418,974   | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$418,974   |
| D5090 - Other Electrical Systems        | \$134,084   | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$134,084   |
| E - Equipment & Furnishings             | \$0         | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0         |
| E10 - Equipment                         | \$0         | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0         |
| E1020 - Institutional Equipment         | \$0         | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0         |
| E1090 - Other Equipment                 | \$0         | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0         |
| E20 - Furnishings                       | \$0         | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0         |
| E2010 - Fixed Furnishings               | \$0         | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0         |

\* Indicates non-renewable system

Forecasted Sustainment Requirement

The following chart shows the current building deficiencies and forecasting sustainment requirements over the next ten years.




## 10 Year FCI Forecast by Investment Scenario

The chart below illustrates the effect of various investment levels on the building FCI for the next 10 years. The levels of investment shown below include:

- Current FCI: a variable investment amount based on renewing expired systems to maintain the current FCI for the building
- 2% Investment: an annual investment of 2% of the replacement value of the building, escalated for inflation
- 4% Investment: an annual investment of 4% of the replacement value of the building, escalated for inflation

**Facility Investment vs. FCI Forecast**




| Year          | Investment Amount<br>Current FCI - 43.44% | 2% Investment         |         | 4% Investment          |         |
|---------------|---|-----------------------|---------|------------------------|---------|
|               |   | Amount                | FCI     | Amount                 | FCI     |
| 2016          | \$0                                       | \$814,526.00          | 41.44 % | \$1,629,052.00         | 39.44 % |
| 2017          | \$14,614,057                              | \$838,962.00          | 74.27 % | \$1,677,924.00         | 70.27 % |
| 2018          | \$0                                       | \$864,131.00          | 72.27 % | \$1,728,262.00         | 66.27 % |
| 2019          | \$0                                       | \$890,055.00          | 70.27 % | \$1,780,109.00         | 62.27 % |
| 2020          | \$3,589,947                               | \$916,756.00          | 76.11 % | \$1,833,513.00         | 66.11 % |
| 2021          | \$0                                       | \$944,259.00          | 74.11 % | \$1,888,518.00         | 62.11 % |
| 2022          | \$2,712,811                               | \$972,587.00          | 77.68 % | \$1,945,174.00         | 63.68 % |
| 2023          | \$0                                       | \$1,001,764.00        | 75.68 % | \$2,003,529.00         | 59.68 % |
| 2024          | \$0                                       | \$1,031,817.00        | 73.68 % | \$2,063,635.00         | 55.68 % |
| 2025          | \$551,113                                 | \$1,062,772.00        | 72.72 % | \$2,125,544.00         | 52.72 % |
| <b>Total:</b> | <b>\$21,467,929</b>                       | <b>\$9,337,629.00</b> |         | <b>\$18,675,260.00</b> |         |



## Deficiency Summary by System


Current deficiencies included assemblies that have reached or exceeded their design life or components of the assemblies that are in need of repair. Assemblies that have reached their design life are identified as current deficiencies and assigned the distress 'Beyond Useful Life'. The following chart lists all current deficiencies associated with this facility.



**Budget Estimate Total: \$17,174,264.35**

## Deficiency Summary by Priority

The following chart shows the total repair costs broken down by priority. Assessors assigned deficiencies within eCOMET to one of the following priority categories:



**Budget Estimate Total: \$17,174,264.35**


## Deficiency By Priority Investment Table

The table below shows the current investment cost grouped by deficiency priority and building system.

| System Code | System Description              | 1 - Response Time (< 2 yr) | 2 - Response Time (2-3 yrs) | 3 - Response Time (3-4 yrs) | 4 - Response Time (4-5 yrs) | 5 - Response Time (> 5 yrs) | Total           |
|-------------|---------------------------------|----------------------------|-----------------------------|-----------------------------|-----------------------------|-----------------------------|-----------------|
| B2010       | Exterior Walls                  | \$0.00                     | \$774,947.33                | \$0.00                      | \$0.00                      | \$0.00                      | \$774,947.33    |
| B2020       | Exterior Windows                | \$0.00                     | \$0.00                      | \$1,829,388.31              | \$0.00                      | \$0.00                      | \$1,829,388.31  |
| B3010105    | Built-Up                        | \$0.00                     | \$0.00                      | \$0.00                      | \$0.00                      | \$1,016,460.33              | \$1,016,460.33  |
| C1020       | Interior Doors                  | \$0.00                     | \$0.00                      | \$0.00                      | \$52,874.10                 | \$0.00                      | \$52,874.10     |
| C3020411    | Carpet                          | \$0.00                     | \$0.00                      | \$0.00                      | \$0.00                      | \$31,334.14                 | \$31,334.14     |
| C3020413    | Vinyl Flooring                  | \$0.00                     | \$0.00                      | \$0.00                      | \$0.00                      | \$906,966.75                | \$906,966.75    |
| C3030       | Ceiling Finishes                | \$0.00                     | \$0.00                      | \$0.00                      | \$0.00                      | \$904,945.82                | \$904,945.82    |
| D2010       | Plumbing Fixtures               | \$0.00                     | \$0.00                      | \$60,633.52                 | \$245,873.73                | \$0.00                      | \$306,507.25    |
| D2030       | Sanitary Waste                  | \$0.00                     | \$0.00                      | \$339,728.54                | \$30,685.95                 | \$0.00                      | \$370,414.49    |
| D3030       | Cooling Generating Systems      | \$0.00                     | \$0.00                      | \$0.00                      | \$0.00                      | \$1,284,765.21              | \$1,284,765.21  |
| D3040       | Distribution Systems            | \$0.00                     | \$0.00                      | \$76,174.51                 | \$3,859,138.78              | \$993,786.72                | \$4,929,100.01  |
| D3060       | Controls & Instrumentation      | \$0.00                     | \$0.00                      | \$0.00                      | \$0.00                      | \$1,716,169.79              | \$1,716,169.79  |
| D4010       | Sprinklers                      | \$1,144,434.28             | \$0.00                      | \$0.00                      | \$0.00                      | \$0.00                      | \$1,144,434.28  |
| D5010       | Electrical Service/Distribution | \$0.00                     | \$0.00                      | \$0.00                      | \$266,481.47                | \$0.00                      | \$266,481.47    |
| D5020       | Lighting and Branch Wiring      | \$0.00                     | \$0.00                      | \$1,086,416.47              | \$0.00                      | \$0.00                      | \$1,086,416.47  |
| D5030       | Communications and Security     | \$0.00                     | \$0.00                      | \$418,974.17                | \$0.00                      | \$0.00                      | \$418,974.17    |
| D5090       | Other Electrical Systems        | \$0.00                     | \$0.00                      | \$134,084.43                | \$0.00                      | \$0.00                      | \$134,084.43    |
|             | <b>Total:</b>                   | \$1,144,434.28             | \$774,947.33                | \$3,945,399.95              | \$4,455,054.03              | \$6,854,428.76              | \$17,174,264.35 |

## Deficiency Summary by Category

The following chart shows the total repair costs broken down by deficiency categories. Assessors assigned deficiencies to one of the following categories:



## Deficiency Details by Priority

The deficiency detail notes listed below provide additional information on identified deficiencies found within the facility.

### Priority 1 - Response Time (< 2 yr):

#### System: D4010 - Sprinklers



**Location:** Throughout building

**Distress:** Life Safety / NFPA / PFD

**Category:** 1 - Health & Safety

**Priority:** 1 - Response Time (< 2 yr)

**Correction:** Install a fire protection sprinkler system

**Qty:** 80,000.00

**Unit of Measure:** S.F.

**Estimate:** \$1,144,434.28

**Assessor Name:** System

**Date Created:** 07/28/2015

**Notes:** Install a fire protection sprinkler system with quick response type heads to reduce insurance costs by providing protection for the property. A fire pump may be required depending on the available city water pressure.

---



**Priority 2 - Response Time (2-3 yrs):**

**System: B2010 - Exterior Walls**



**Location:** Exterior

**Distress:** Building Envelope Integrity

**Category:** 3 - Operations / Maint.

**Priority:** 2 - Response Time (2-3 yrs)

**Correction:** Repair cracks in masonry - replace missing mortar and repoint - SF of wall area

**Qty:** 24,000.00

**Unit of Measure:** S.F.

**Estimate:** \$774,947.33

**Assessor Name:** System

**Date Created:** 08/04/2015

**Notes:** Repair cracks in masonry, replace missing mortar, tuck-point – all walls including panels covering columns and girders

---

**Priority 3 - Response Time (3-4 yrs):**

**System: B2020 - Exterior Windows**



**Location:** Exterior

**Distress:** Building Envelope Integrity

**Category:** 3 - Operations / Maint.

**Priority:** 3 - Response Time (3-4 yrs)

**Correction:** Remove and replace aluminum windows - pick the appropriate size and style and insert the number of units

**Qty:** 600.00

**Unit of Measure:** Ea.

**Estimate:** \$1,829,388.31

**Assessor Name:** System

**Date Created:** 08/04/2015

**Notes:** Replace all windows within next 4 to 5 years

---

**System: D2010 - Plumbing Fixtures**



**Location:** Throughout building

**Distress:** Beyond Service Life

**Category:** 3 - Operations / Maint.

**Priority:** 3 - Response Time (3-4 yrs)

**Correction:** Remove and Replace Water Fountains - without ADA new recessed alcove

**Qty:** 8.00

**Unit of Measure:** Ea.

**Estimate:** \$60,633.52

**Assessor Name:** System

**Date Created:** 07/28/2015

**Notes:** Replace the wall hung drinking fountains and integral refrigerated coolers in the corridors and at the restrooms. These units are well beyond their service life.

---

**System: D2030 - Sanitary Waste**



**Location:** Throughout buliding

**Distress:** Beyond Service Life

**Category:** 3 - Operations / Maint.

**Priority:** 3 - Response Time (3-4 yrs)

**Correction:** Inspect sanitary waste piping and replace damaged sections. (+100KSF)

**Qty:** 80,000.00

**Unit of Measure:** S.F.

**Estimate:** \$339,728.54

**Assessor Name:** System

**Date Created:** 07/28/2015

**Notes:** Hire a qualified contractor to perform a detailed examination of the sanitary waste piping using visual inspection and video cameras to locate and replace any damaged piping and to further quantify the extent of potential failures.

---

**System: D3040 - Distribution Systems**



**Location:** Roof

**Distress:** Beyond Service Life

**Category:** 3 - Operations / Maint.

**Priority:** 3 - Response Time (3-4 yrs)

**Correction:** Replace utility set exhaust fan (5 HP)

**Qty:** 2.00

**Unit of Measure:** Ea.

**Estimate:** \$76,174.51

**Assessor Name:** System

**Date Created:** 07/28/2015

**Notes:** Replace existing exhaust fans on the roof serving the bathrooms and utilize the existing ductwork.

---

**System: D5020 - Lighting and Branch Wiring**



**Location:** Throughout Building

**Distress:** Inadequate

**Category:** 4 - Capital Improvement

**Priority:** 3 - Response Time (3-4 yrs)

**Correction:** Replace Lighting Fixtures (SF)

**Qty:** 80,000.00

**Unit of Measure:** S.F.

**Estimate:** \$1,031,767.20

**Assessor Name:** System

**Date Created:** 07/29/2015

**Notes:** Complete lighting upgrade

---

**System: D5020 - Lighting and Branch Wiring**



**Location:** Throughout Building

**Distress:** Inadequate

**Category:** 4 - Capital Improvement

**Priority:** 3 - Response Time (3-4 yrs)

**Correction:** Add wiring device

**Qty:** 1.00

**Unit of Measure:** Ea.

**Estimate:** \$54,649.27

**Assessor Name:** System

**Date Created:** 07/29/2015

**Notes:** Install minimum two receptacles on each wall of class rooms and other purpose rooms.

---

**System: D5030 - Communications and Security**



**Location:** Throughout Building

**Distress:** Life Safety / NFPA / PFD

**Category:** 1 - Health & Safety

**Priority:** 3 - Response Time (3-4 yrs)

**Correction:** Replace fire alarm system

**Qty:** 1.00

**Unit of Measure:** S.F.

**Estimate:** \$418,974.17

**Assessor Name:** System

**Date Created:** 07/29/2015

**Notes:** Install a new addressable fire alarm system and provide audible and/or visual devices in all areas.

---

**System: D5090 - Other Electrical Systems**



**Location:** Basement

**Distress:** Inadequate

**Category:** 4 - Capital Improvement

**Priority:** 3 - Response Time (3-4 yrs)

**Correction:** Replace standby generator system

**Qty:** 1.00

**Unit of Measure:** Ea.

**Estimate:** \$112,888.95

**Assessor Name:** System

**Date Created:** 07/30/2015

**Notes:** Replace existing generator with larger generator sized to operate the elevator.

---

**System: D5090 - Other Electrical Systems**



**Location:** Throughout Building

**Distress:** Inadequate

**Category:** 4 - Capital Improvement

**Priority:** 3 - Response Time (3-4 yrs)

**Correction:** Replace Emergency/Exit Lighting

**Qty:** 1.00

**Unit of Measure:** Ea.

**Estimate:** \$21,195.48

**Assessor Name:** System

**Date Created:** 07/29/2015

**Notes:** Provide new exit lighting

---

**Priority 4 - Response Time (4-5 yrs):**

**System: C1020 - Interior Doors**



**Location:** Interior

**Distress:** Accessibility

**Category:** 2 - Code Compliance

**Priority:** 4 - Response Time (4-5 yrs)

**Correction:** Replace door knobs with compliant lever type

**Qty:** 95.00

**Unit of Measure:** Ea.

**Estimate:** \$52,874.10

**Assessor Name:** System

**Date Created:** 08/04/2015

**Notes:** Replace interior doors hardware for ADA accessibility

---

**System: D2010 - Plumbing Fixtures**



**Location:** Restrooms

**Distress:** Accessibility

**Category:** 2 - Code Compliance

**Priority:** 4 - Response Time (4-5 yrs)

**Correction:** Replace lavatory - with finishes

**Qty:** 30.00

**Unit of Measure:** Ea.

**Estimate:** \$245,873.73

**Assessor Name:** System

**Date Created:** 07/28/2015

**Notes:** Replace the wheel lavatories in the restrooms with new code compliant fixtures.

---



**System: D2030 - Sanitary Waste**



**Location:** Boiler Room

**Distress:** Beyond Service Life

**Category:** 3 - Operations / Maint.

**Priority:** 4 - Response Time (4-5 yrs)

**Correction:** Replace sanitary sewage ejector pit and pumps. (48" dia.)

**Qty:** 1.00

**Unit of Measure:** Ea.

**Estimate:** \$30,685.95

**Assessor Name:** System

**Date Created:** 07/28/2015

**Notes:** Replace existing sewage ejector pump system and piping in the basement as it is beyond its useful service life.

---

**System: D3040 - Distribution Systems**



**Location:** Throughout building

**Distress:** Beyond Service Life

**Category:** 3 - Operations / Maint.

**Priority:** 4 - Response Time (4-5 yrs)

**Correction:** Replace the existing unit ventilators with new units designed to provide adequate ventilation per ASHRAE Std 62 - insert the SF of bldg. in the qty.

**Qty:** 80,000.00

**Unit of Measure:** S.F.

**Estimate:** \$3,859,138.78

**Assessor Name:** System

**Date Created:** 07/28/2015

**Notes:** Remove the existing unit ventilators and install units with hot and chilled water coils and integral heat exchangers to introduce outdoor air to the building.

---



**System: D5010 - Electrical Service/Distribution**



**Location:** Basement

**Distress:** Inadequate

**Category:** 4 - Capital Improvement

**Priority:** 4 - Response Time (4-5 yrs)

**Correction:** Add Electrical Switchgear and Distribution System

**Qty:** 0.00

**Unit of Measure:** Ea.

**Estimate:** \$266,481.47

**Assessor Name:** System

**Date Created:** 07/30/2015

**Notes:** Install a second substation to serve new air conditioning equipment.

---

**Priority 5 - Response Time (> 5 yrs):**

**System: B3010105 - Built-Up**



**Location:** Exterior

**Distress:** Building Envelope Integrity

**Category:** 3 - Operations / Maint.

**Priority:** 5 - Response Time (> 5 yrs)

**Correction:** Remove and Replace Built Up Roof

**Qty:** 30,000.00

**Unit of Measure:** S.F.

**Estimate:** \$1,016,460.33

**Assessor Name:** System

**Date Created:** 08/04/2015

**Notes:** Install all new roofing system including insulation within next 5 to 10 years; tear-down existing roofing; install flashing, and counter flashing

---

**System: C3020411 - Carpet**



**Location:** Interior

**Distress:** Beyond Service Life

**Category:** 3 - Operations / Maint.

**Priority:** 5 - Response Time (> 5 yrs)

**Correction:** Remove and replace carpet

**Qty:** 2,800.00

**Unit of Measure:** S.F.

**Estimate:** \$31,334.14


**Assessor Name:** System

**Date Created:** 08/04/2015

**Notes:** Replace existing carpet

---

**System: C3020413 - Vinyl Flooring**



**Location:** Interior

**Distress:** Beyond Service Life

**Category:** 3 - Operations / Maint.

**Priority:** 5 - Response Time (> 5 yrs)

**Correction:** Remove VAT and replace with VCT - SF of area

**Qty:** 59,800.00

**Unit of Measure:** S.F.

**Estimate:** \$906,966.75

**Assessor Name:** System

**Date Created:** 08/04/2015

**Notes:** Replace all VAT flooring including cove base within 10 years

---

**System: C3030 - Ceiling Finishes**



**Location:** Interior

**Distress:** Beyond Service Life

**Category:** 3 - Operations / Maint.

**Priority:** 5 - Response Time (> 5 yrs)

**Correction:** Remove and replace suspended acoustic ceilings - lighting not included

**Qty:** 60,000.00

**Unit of Measure:** S.F.

**Estimate:** \$904,945.82

**Assessor Name:** System

**Date Created:** 08/04/2015

**Notes:** Replace all suspended acoustical ceilings

---

**System: D3030 - Cooling Generating Systems**



**Location:** Roof

**Distress:** Inadequate

**Category:** 4 - Capital Improvement

**Priority:** 5 - Response Time (> 5 yrs)

**Correction:** Install chilled water system with distribution piping and pumps. (+75KSF)

**Qty:** 80,000.00

**Unit of Measure:** S.F.

**Estimate:** \$1,284,765.21

**Assessor Name:** System

**Date Created:** 07/28/2015

**Notes:** Remove the window air conditioning units and install a 200 ton air-cooled chiller on the roof with chilled water distribution piping and pumps located in the mechanical room to supply more reliable air conditioning for the building with a much longer service life.

---

**System: D3040 - Distribution Systems**



**Location:** Administration

**Distress:** Building / MEP Codes

**Category:** 2 - Code Compliance

**Priority:** 5 - Response Time (> 5 yrs)

**Correction:** Install HVAC unit for Administration (2000 students).

**Qty:** 795.00

**Unit of Measure:** Pr.

**Estimate:** \$330,266.69

**Assessor Name:** System

**Date Created:** 07/28/2015

**Notes:** Provide ventilation for the administrative offices by installing a fan coil air handling unit hung from the structure with outdoor air ducted to the unit from louvers in window openings.

---

**System: D3040 - Distribution Systems**



**Location:** Gymnasium

**Distress:** Building / MEP Codes

**Category:** 2 - Code Compliance

**Priority:** 5 - Response Time (> 5 yrs)

**Correction:** Install HVAC unit for Gymnasium (single station).

**Qty:** 6,000.00

**Unit of Measure:** Ea.

**Estimate:** \$308,301.04

**Assessor Name:** System

**Date Created:** 07/28/2015

**Notes:** Provide ventilation for the gymnasium by installing a fan coil air handling unit hung from the structure with outdoor air ducted to the unit from louvers in the window openings.

---

**System: D3040 - Distribution Systems**



**Location:** Auditorium

**Distress:** Building / MEP Codes

**Category:** 2 - Code Compliance

**Priority:** 5 - Response Time (> 5 yrs)

**Correction:** Install HVAC unit for Auditorium (200 seat).

**Qty:** 200.00

**Unit of Measure:** Seat

**Estimate:** \$285,085.41

**Assessor Name:** System

**Date Created:** 07/29/2015

**Notes:** Provide ventilation for the Auditorium by installing a fan coil air handling unit hung from the structure with outdoor air ducted to the unit from louvers in window openings.

---

**System: D3040 - Distribution Systems**



**Location:** Cafeteria

**Distress:** Building / MEP Codes

**Category:** 2 - Code Compliance

**Priority:** 5 - Response Time (> 5 yrs)

**Correction:** Install HVAC unit for Cafeteria (850 students).

**Qty:** 150.00

**Unit of Measure:** Pr.

**Estimate:** \$70,133.58

**Assessor Name:** System

**Date Created:** 07/28/2015

**Notes:** Provide ventilation for the Cafeteria by installing a constant volume air handling unit with distribution ductwork and registers.

---

**System: D3060 - Controls & Instrumentation**



**Location:** Throughout building

**Distress:** Energy Efficiency

**Category:** 4 - Capital Improvement

**Priority:** 5 - Response Time (> 5 yrs)

**Correction:** Replace pneumatic controls with DDC (75KSF)

**Qty:** 80,000.00

**Unit of Measure:** S.F.

**Estimate:** \$1,716,169.79

**Assessor Name:** System

**Date Created:** 07/28/2015

**Notes:** Replace the pneumatic controls for the HVAC systems with modern DDC modules, valves and actuators to improve reliability and energy efficiency. Provide a new building automation system (BAS) with communication interface to the preferred system in use throughout the District.

---

## Equipment Inventory

The following table represents the inventory details of the inventory found in the building, which fall under the following subsystems:

| Subsystem                             | Inventory  | Qty  | UoM | Location                 | Manufacturer | Model Number | Serial Number         | Barcode | Life | Install Date | Next Renewal | Raw Cost      | Inventory Cost      |
|---------------------------------------|--|------|-----|--------------------------|--------------|--------------|-----------------------|---------|------|--------------|--------------|---------------|---------------------|
| D3020 Heat Generating Systems         | Boiler, gas/oil combination, cast iron, steam, gross output, 4650 MBH, includes burners, controls and insulated jacket, packaged | 2.00 | Ea. | Basement Boiler Room     | Buderus      | GE615/16     |                       |         | 35   | 2000         | 2035         | \$112,258.50  | \$246,968.70        |
| D3020 Heat Generating Systems         | Boiler, gas/oil combination, cast iron, steam, gross output, 4650 MBH, includes burners, controls and insulated jacket, packaged | 2.00 | Ea. | Basement Boiler Room     | Buderus      | GE615/16     | 63130084-00-3000-0031 |         | 35   | 2000         | 2035         | \$112,258.50  | \$246,968.70        |
| D3020 Heat Generating Systems         | Pump, base mounted with motor, end-suction, 3" size, 5 HP, to 225 GPM  | 2.00 | Ea. | Basement Mechanical Room | Armstrong    | 4030         |                       |         | 35   |              |              | \$23,031.60   | \$50,669.52         |
| D3020 Heat Generating Systems         | Pump, base mounted with motor, end-suction, 3" size, 5 HP, to 225 GPM  | 2.00 | Ea. | Basement Mechanical Room | Armstrong    | 4030         | 540920                |         | 35   |              |              | \$23,031.60   | \$50,669.52         |
| D5010 Electrical Service/Distribution | Load interrupter switch, 2 position, 400 kVA & above w/CLF fuses, 4.8 kV, 600 amp, NEMA 1  | 1.00 | Ea. | Basement                 | Eaton        |              |                       |         | 30   |              |              | \$38,502.00   | \$42,352.20         |
| D5010 Electrical Service/Distribution | Switchgear installation, incl switchboard, panels & circuit breaker, 120/208 V, 1600 A   | 1.00 | Ea. | Basement                 | Eaton        |              |                       |         | 20   |              |              | \$40,458.15   | \$44,503.97         |
| D5010 Electrical Service/Distribution | Transformers, 4800 volts to 480/277 volts, 500 kVA   | 1.00 | Ea. | Basement                 | Eaton        |              |                       |         | 30   |              |              | \$65,205.00   | \$71,725.50         |
|                                       |  |      |     |                          |              |              |                       |         |      |              |              | <b>Total:</b> | <b>\$753,858.11</b> |



## Executive Summary

Building condition is evaluated based on the functional systems and elements of a building and organized according to the UNIFORMAT II Elemental Classification. The grouping of these systems and elements and applying a current replacement value to them develops a representative building cost model. Cost Models are developed for similar building types and functions. Systems and their elements are evaluated based on their current replacement values, life cycles, installation dates and next renewal dates. Systems and their elements that are within their useful lives are further evaluated to identify current deficient conditions that may have a significant impact on a system's or element's remaining service life, and to determine if they are beyond their predicted expected life. The system's or element's current replacement value is based on RS Means Commercial Cost Data.

Following are the cost model's system details for this facility. The Replacement Value is the amount needed to replace the property of the same present value. The Current Repair Amount, also known as Condition Needs, represents the budgeted contractor installed costs plus owner's soft costs for the repair, replacement or renewal for a component or system level deficiency. It excludes contributing costs for other components or systems that might also be associated with the corrective actions due to packaging the work. Facility Condition Index (FCI) FCI is an industry-standard measurement of facility condition calculated as the ratio of the costs to correct a facility's deficiencies to the facility's Current Replacement Value. It ranges from 0% (new) to 100% (very poor). Condition Index (CI) is calculated as the sum of a renewable system's Remaining Service Life (RSL) divided by the sum of a system's Replacement Value (both values exclude soft-cost to simplify calculation updates) expressed as a percentage ranging from 100% (new) to 0% (expired).

Function:

Gross Area (SF): 15,400

Year Built: 1966

Last Renovation:

Replacement Value: \$346,038

Repair Cost: \$269,084.93

Total FCI: 77.76 %

Total RSLI: 80.23 %

### Description:

#### Attributes:

##### General Attributes:

|          |         |          |         |
|----------|---------|----------|---------|
| Bldg ID: | S239001 | Site ID: | S239001 |
|----------|---------|----------|---------|



## Condition Summary

The Table below shows the CI and FCI for each major building system shown at the UNIFORMAT classification Level II. Note that Systems with lower FCIs require less investment than systems with higher FCIs.

| UNIFORMAT Classification        | RSLI %         | FCI %          | Current Repair Cost |
|---------------------------------|----------------|----------------|---------------------|
| G20 - Site Improvements         | 90.77 %        | 104.88 %       | \$269,084.93        |
| G40 - Site Electrical Utilities | 50.00 %        | 0.00 %         | \$0.00              |
| <b>Totals:</b>                  | <b>80.23 %</b> | <b>77.76 %</b> | <b>\$269,084.93</b> |

### Condition Detail

This section of the report contains results of the Facility Condition Assessment. The building is separated into system components based on UNIFORMAT II classification. The columns in the System Listing table below represent the following:

1. System Code: A code that identifies the system.
2. System Description: A brief description of a system present in the building.
3. Unit Price \$: The unit price of the system.
4. UoM: The unit of measure for of the system.
5. Qty: The quantity for the system
6. Life: anticipated service life for thesystem based on Building Owners and Managers Association (BOMA) recommendations.
7. Year Installed: The date of system installation.
8. Calc Next Renewal Year: The date of system expiration based on the life, NR stands for non renewable.
9. Next Renewal Year: The suggested system expiration date by the assessor based on visual inspection.
10. CI: The Condition Index of the system.
11. FCI: The Facility Condition Index of the system.
12. RSL: Remaining Service Life.
13. eCR: eCOMET Condition Rating (not used).
14. Deficiency \$: The financial investment to repair/replace system.

## System Listing

The System Listing table below lists each of the systems organized by their UNIFORMAT II classification. The assessment team was tasked with recording the most recent replacement year of each system, determining the remaining service life based on the theoretical life, and evaluating the condition to confirm the forecast next replacement year. The system listing is the basis for all data contained in the Building Assessment Report.

Additionally, a condition rating (eCR) based on the following guidelines is provided as observed at the time of the assessment.

- Excellent (E) - No noticeable distress or damage. The entire system is free from observable defect.
- Very Good (VG) - Overall no serviceability reduction for the entire system. No degradation of critical components and minor distress and defect noticeable for some but not non critical components within the system.
- Good (G) - Slight or no serviceability reduction for the entire system. There may be noticeable defects for some non critical components and slight noticeable degradation of the critical components.
- Fair (F) - Overall serviceability is degraded but adequate. There may be moderate deterioration for very few of the critical components and few of the non critical components may have severe degradation.
- Marginal (MA) - Overall serviceability and reliability loss. Most if not all of the non critical components suffer from severe degradation and a few of the critical component may have severe degradation.
- Moderate (MO) - Overall a significant serviceability loss. Most if not all the components have severe degradation with the reminder of the component showing visible distress.
- Very Poor (VP) - Overall the system is barely functional. All of the components are severely degraded.
- Non-Functional (NF) - Overall the system does not function with all the components having no serviceability and suffer from severe degradation.

| System Code  | System Description             | Unit Price \$ | UoM  | Qty    | Life | Year Installed | Calc Next Renewal Year | Next Renewal Year | RSLI%          | FCI%           | RSL | eCR | Deficiency \$       | Replacement Value \$ |
|--------------|--------------------------------|---------------|------|--------|------|----------------|------------------------|-------------------|----------------|----------------|-----|-----|---------------------|----------------------|
| G2010        | Roadways                       | \$11.52       | S.F. |        | 30   |                |                        |                   | 0.00 %         | 0.00 %         |     |     |                     | \$0                  |
| G2020        | Parking Lots                   | \$8.50        | S.F. |        | 30   |                |                        |                   | 0.00 %         | 0.00 %         |     |     |                     | \$0                  |
| G2030        | Pedestrian Paving              | \$12.30       | S.F. | 15,400 | 40   | 1980           | 2020                   | 2050              | 87.50 %        | 129.43 %       | 35  |     | \$245,173.68        | \$189,420            |
| G2040        | Site Development               | \$4.36        | S.F. | 15,400 | 25   | 1995           | 2020                   | 2040              | 100.00 %       | 35.61 %        | 25  |     | \$23,911.25         | \$67,144             |
| G2050        | Landscaping & Irrigation       | \$4.36        | S.F. |        | 15   |                |                        |                   | 0.00 %         | 0.00 %         |     |     |                     | \$0                  |
| G4020        | Site Lighting                  | \$4.84        | S.F. | 15,400 | 30   | 2000           | 2030                   |                   | 50.00 %        | 0.00 %         | 15  |     |                     | \$74,536             |
| G4030        | Site Communications & Security | \$0.97        | S.F. | 15,400 | 30   | 2000           | 2030                   |                   | 50.00 %        | 0.00 %         | 15  |     |                     | \$14,938             |
| <b>Total</b> |                                |               |      |        |      |                |                        |                   | <b>80.23 %</b> | <b>77.76 %</b> |     |     | <b>\$269,084.93</b> | <b>\$346,038</b>     |

## System Notes

The facility description in the site executive summary contains an overview of each system. The notes listed below provide additional information on select systems found within the facility.

No data found for this asset

## Renewal Schedule

eCOMET forecasts future Capital Renewal funding needed to address expiring systems based on the Next Renewal year found in the Cost Models. A 3% annual inflation factor is applied to the costs for systems expiring in future years. The table below reflects recommended Capital Renewal funding needs over the next 10 years. Note: Cells with a zero value indicate systems for which renewal is not scheduled in that year.


*Inflation Rate: 3%*

| System                                 | Current Deficiencies | 2016       | 2017       | 2018       | 2019       | 2020       | 2021       | 2022       | 2023       | 2024       | 2025       | Total            |
|--|----------------------|------------|------------|------------|------------|------------|------------|------------|------------|------------|------------|------------------|
| <b>Total:</b>                          | <b>\$269,085</b>     | <b>\$0</b> | <b>\$0</b> | <b>\$0</b> | <b>\$0</b> | <b>\$0</b> | <b>\$0</b> | <b>\$0</b> | <b>\$0</b> | <b>\$0</b> | <b>\$0</b> | <b>\$269,085</b> |
| G - Building Sitework                  | \$0                  | \$0        | \$0        | \$0        | \$0        | \$0        | \$0        | \$0        | \$0        | \$0        | \$0        | \$0              |
| G20 - Site Improvements                | \$0                  | \$0        | \$0        | \$0        | \$0        | \$0        | \$0        | \$0        | \$0        | \$0        | \$0        | \$0              |
| G2010 - Roadways                       | \$0                  | \$0        | \$0        | \$0        | \$0        | \$0        | \$0        | \$0        | \$0        | \$0        | \$0        | \$0              |
| G2020 - Parking Lots                   | \$0                  | \$0        | \$0        | \$0        | \$0        | \$0        | \$0        | \$0        | \$0        | \$0        | \$0        | \$0              |
| G2030 - Pedestrian Paving              | \$245,174            | \$0        | \$0        | \$0        | \$0        | \$0        | \$0        | \$0        | \$0        | \$0        | \$0        | \$245,174        |
| G2040 - Site Development               | \$23,911             | \$0        | \$0        | \$0        | \$0        | \$0        | \$0        | \$0        | \$0        | \$0        | \$0        | \$23,911         |
| G2050 - Landscaping & Irrigation       | \$0                  | \$0        | \$0        | \$0        | \$0        | \$0        | \$0        | \$0        | \$0        | \$0        | \$0        | \$0              |
| G40 - Site Electrical Utilities        | \$0                  | \$0        | \$0        | \$0        | \$0        | \$0        | \$0        | \$0        | \$0        | \$0        | \$0        | \$0              |
| G4020 - Site Lighting                  | \$0                  | \$0        | \$0        | \$0        | \$0        | \$0        | \$0        | \$0        | \$0        | \$0        | \$0        | \$0              |
| G4030 - Site Communications & Security | \$0                  | \$0        | \$0        | \$0        | \$0        | \$0        | \$0        | \$0        | \$0        | \$0        | \$0        | \$0              |

*\* Indicates non-renewable system*

Forecasted Sustainment Requirement

The following chart shows the current building deficiencies and forecasting sustainment requirements over the next ten years.




## 10 Year FCI Forecast by Investment Scenario

The chart below illustrates the effect of various investment levels on the building FCI for the next 10 years. The levels of investment shown below include:

- Current FCI: a variable investment amount based on renewing expired systems to maintain the current FCI for the building
- 2% Investment: an annual investment of 2% of the replacement value of the building, escalated for inflation
- 4% Investment: an annual investment of 4% of the replacement value of the building, escalated for inflation


**Facility Investment vs. FCI Forecast**



| Year          | Investment Amount<br>Current FCI - 77.76% | 2% Investment      |         | 4% Investment       |         |
|---------------|---|--------------------|---------|---------------------|---------|
|               |   | Amount             | FCI     | Amount              | FCI     |
| 2016          | \$0                                       | \$7,128.00         | 75.76 % | \$14,257.00         | 73.76 % |
| 2017          | \$0                                       | \$7,342.00         | 73.76 % | \$14,684.00         | 69.76 % |
| 2018          | \$0                                       | \$7,563.00         | 71.76 % | \$15,125.00         | 65.76 % |
| 2019          | \$0                                       | \$7,789.00         | 69.76 % | \$15,579.00         | 61.76 % |
| 2020          | \$0                                       | \$8,023.00         | 67.76 % | \$16,046.00         | 57.76 % |
| 2021          | \$0                                       | \$8,264.00         | 65.76 % | \$16,527.00         | 53.76 % |
| 2022          | \$0                                       | \$8,512.00         | 63.76 % | \$17,023.00         | 49.76 % |
| 2023          | \$0                                       | \$8,767.00         | 61.76 % | \$17,534.00         | 45.76 % |
| 2024          | \$0                                       | \$9,030.00         | 59.76 % | \$18,060.00         | 41.76 % |
| 2025          | \$0                                       | \$9,301.00         | 57.76 % | \$18,602.00         | 37.76 % |
| <b>Total:</b> | <b>\$0</b>                                | <b>\$81,719.00</b> |         | <b>\$163,437.00</b> |         |

## Deficiency Summary by System


Current deficiencies included assemblies that have reached or exceeded their design life or components of the assemblies that are in need of repair. Assemblies that have reached their design life are identified as current deficiencies and assigned the distress 'Beyond Useful Life'. The following chart lists all current deficiencies associated with this facility.





## Deficiency Summary by Priority

The following chart shows the total repair costs broken down by priority. Assessors assigned deficiencies within eCOMET to one of the following priority categories:



**Budget Estimate Total: \$269,084.93**


## Deficiency By Priority Investment Table

The table below shows the current investment cost grouped by deficiency priority and building system.

| System Code | System Description | 1 - Response Time (< 2 yr) | 2 - Response Time (2-3 yrs) | 3 - Response Time (3-4 yrs) | 4 - Response Time (4-5 yrs) | 5 - Response Time (> 5 yrs) | Total        |
|-------------|--------------------|----------------------------|-----------------------------|-----------------------------|-----------------------------|-----------------------------|--------------|
| G2030       | Pedestrian Paving  | \$0.00                     | \$0.00                      | \$245,173.68                | \$0.00                      | \$0.00                      | \$245,173.68 |
| G2040       | Site Development   | \$0.00                     | \$0.00                      | \$0.00                      | \$0.00                      | \$23,911.25                 | \$23,911.25  |
|             | <b>Total:</b>      | \$0.00                     | \$0.00                      | \$245,173.68                | \$0.00                      | \$23,911.25                 | \$269,084.93 |

## Deficiency Summary by Category

The following chart shows the total repair costs broken down by deficiency categories. Assessors assigned deficiencies to one of the following categories:



## Deficiency Details by Priority

The deficiency detail notes listed below provide additional information on identified deficiencies found within the facility.

### Priority 3 - Response Time (3-4 yrs):

#### **System: G2030 - Pedestrian Paving**



**Location:** Grounds

**Distress:** Damaged

**Category:** 3 - Operations / Maint.

**Priority:** 3 - Response Time (3-4 yrs)

**Correction:** Remove and replace concrete sidewalk or concrete paving - 4" concrete thickness

**Qty:** 15,000.00

**Unit of Measure:** S.F.

**Estimate:** \$245,173.68

**Assessor Name:** Craig Anding

**Date Created:** 08/04/2015

**Notes:** Resurface playground paving

**Priority 5 - Response Time (> 5 yrs):**

**System: G2040 - Site Development**



**Location:** Grounds

**Distress:** Security Issue

**Category:** 1 - Health & Safety

**Priority:** 5 - Response Time (> 5 yrs)

**Correction:** Replace chain link fence - 8' high

**Qty:** 160.00

**Unit of Measure:** L.F.

**Estimate:** \$17,918.05

**Assessor Name:** Craig Anding

**Date Created:** 08/04/2015

**Notes:** Replace original chain link fence and security gate

---

**System: G2040 - Site Development**



**Location:** Grounds

**Distress:** Beyond Service Life

**Category:** 3 - Operations / Maint.

**Priority:** 5 - Response Time (> 5 yrs)

**Correction:** Remove and replace chain link gate - 8' high

**Qty:** 1.00

**Unit of Measure:** Ea.

**Estimate:** \$5,993.20

**Assessor Name:** Craig Anding

**Date Created:** 08/04/2015

**Notes:** Replace original chain link security gate

---

## Equipment Inventory

The following table represents the inventory details of the inventory found in the building, which fall under the following subsystems:

No data found for this asset

## Glossary

|            |   |
|------------|---|
| ABMA       | American Boiler Manufacturers Association <a href="http://www.abma.com/">http://www.abma.com/</a>   |
| ACEEE      | American Council for an Energy-Efficient Economy  |
| ACGIH      | American Council of Governmental and Industrial Hygienists  |
| AEE        | Association of Energy Engineers   |
| AFD        | Adjustable Frequency Drive  |
| AFTC       | After Tax Cash Flow   |
| AGA        | American Gas Association  |
| AHU        | Air Handling Unit   |
| Amp        | Ampere  |
| ANSI       | American National Standards Institute   |
| ARI        | Air Conditioning and Refrigeration Institute  |
| ASD        | Adjustable Speed Drive  |
| ASHRAE     | American Society of Heating Refrigerating and Air-Conditioning Engineers Inc.   |
| ASME       | American Society of Mechanical Engineers  |
| Assessment | Visual survey of a facility to determine its condition. It involves looking at the age of systems reviewing information from local sources and visual evidence of potential problems to assign a condition rating. It does not include destructive testing of materials or testing of systems or equipment for functionality. |
| ATS        | After Tax Savings   |
| AW         | Annual worth  |
| BACNET     | Building Automation Control Network   |
| BAS        | Building Automation System  |
| BCR        | Benefit Cost Ratio  |
| BEP        | Business Energy Professional (AEE)  |
| BF         | Ballast Factor  |
| BHP        | Boiler Horsepower (boilers)   |
| BHP        | Brake Horsepower (motors)   |
| BLCC       | Building Life Cycle Cost analysis program (FEMP)  |
| BOCA       | Building Officials and Code Administrators  |
| BTCF       | Before Tax Cash Flow  |

## Site Assessment Report - S239001;Morris

---

|                         |   |
|-------------------------|---|
| BTS                     | Before Tax Savings  |
| Btu                     | British thermal unit  |
| Building Addition       | An area space or component of a building added to a building after the original building's year built date.   |
| CAA                     | Clean Air Act   |
| CAAA-90                 | Clean Air Act Amendments of 1990  |
| CABO                    | Council of American Building Officials  |
| CAC                     | Conventional Air Conditioning   |
| CADDET                  | Center for the Analysis and Dissemination of Demonstrated Energy Technologies   |
| Calculated Next Renewal | The year a system or element would be expected to expire based solely on the date it was installed and the expected useful lifetime for that kind of system.  |
| Capital Renewal         | Capital renewal is condition work (excluding suitability and energy audit work) that includes the replacement of building systems or elements (as they become obsolete or beyond their useful life) not normally included in an annual operating budget. Calculated next renewal The year a system or element would be expected to expire based solely on the date it was installed and the expected useful lifetime for that kind of system. Next renewal The assessor adjusted expected useful life of a system or element based on on-site inspection. |
| CDD                     | Cooling Degree Days   |
| CDGP                    | Certified Distributed Generation Professional   |
| CEC                     | California Energy Commission  |
| CEM                     | Certified Energy Manager  |
| CEP                     | Certified Energy Procurement Professional   |
| CFC                     | Chlorofluorocarbon  |
| CFD                     | Cash Flow Diagram   |
| CFL                     | Compact Fluorescent Light   |
| CFM cfm                 | Cubic Feet per Minute   |
| CHP                     | Combined Heat and Power (a.k.a. cogeneration)   |
| CHW                     | Chilled Water   |
| Condition               | Condition refers to the state of physical fitness or readiness of a facility system or system element for its intended use.   |
| COP                     | Coefficient of Performance  |
| Cp                      | Heat Capacity of Material   |
| CPUC                    | California Public Utility Commission  |
| CRI                     | Color Rendering Index   |
| CRT                     | Cathode Ray Tube VDT HMI  |



## Site Assessment Report - S239001;Morris

---

|                                 |   |
|---------------------------------|---|
| CTC                             | Competitive Transition Charge   |
| Cu                              | Coefficient of Utilization  |
| Current Replacement Value (CRV) | CRV represents the hypothetical total cost of rebuilding or replacing an existing facility in current dollars to its optimal condition (excluding auxiliary facilities) under current codes and construction standards. |
| Cv                              | Value Coefficient   |
| CWS                             | Chilled Water System  |
| D d                             | Distance (usually feet)   |
| DB                              | Dry Bulb  |
| DCV                             | Demand Control Ventilation  |
| DD                              | Degree Day  |
| DDB                             | Double Declining Balance  |
| DDC                             | Direct Digital Controls   |
| Deferred maintenance            | Deferred maintenance is condition work (excluding suitability and energy audit needs) deferred on a planned or unplanned basis to a future budget cycle or postponed until funds are available.                         |
| Deficiency                      | A deficiency is a repair item that is damaged missing inadequate or insufficient for an intended purpose.   |
| Delta                           | Difference  |
| Delta P                         | Pressure Difference   |
| Delta T                         | Temperature Difference  |
| DG                              | Distributed Generation  |
| DOE                             | Department of Energy  |
| DP                              | Dew Point   |
| DR                              | Demand Response   |
| DX                              | Direct Expansion Air Conditioner  |
| EA                              | Energy Audit  |
| EBITDA                          | Earnings before Interest Taxes Depreciation and Amortization  |
| ECI                             | Energy Cost Index   |
| ECM                             | Energy Conservation Measure   |
| ECO                             | Energy Conservation Opportunity   |
| ECPA                            | Energy Conservation and Production Act  |
| ECR                             | Energy Conservation Recommendation  |
| ECS                             | Energy Control System   |

## Site Assessment Report - S239001;Morris

---

|  |  |
|--|--|
| EER                                      | Energy Efficiency Ratio  |
| EERE                                     | Energy Efficiency and Renewable Energy division of US DOE  |
| EIA                                      | Energy Information Agency  |
| EIS                                      | Energy Information System  |
| EMCS                                     | Energy Management Computer System  |
| EMO                                      | Energy Management Opportunity  |
| EMP                                      | Energy Management Project  |
| EMR                                      | Energy Management Recommendation   |
| EMS                                      | Energy Management System   |
| Energy Utilization Index (EUI)           | EUI is the measure of total energy consumed in the cooling or heating of a building in a period expressed as British thermal unit (BTU) per (cooled or heated) gross square foot.  |
| EO                                       | Executive Order  |
| EPA                                      | Environmental Protection Agency  |
| EPACT                                    | Energy Policy Act of 1992  |
| EPCA                                     | Energy Production and Conservation Act of 1975   |
| EPRI                                     | Electric Power Research Institute  |
| EREN                                     | Efficiency and Renewable Energy (Division of USDOE)  |
| ERV                                      | Energy Recovery Ventilator   |
| ESCO                                     | Energy Service Company   |
| ESPC                                     | Energy Savings Performance Contract  |
| EUI                                      | Energy Use Index   |
| EWG                                      | Exempt Wholesale Generators  |
| Extended Facility Condition Index (EFCI) | EFCI is calculated as the condition needs for the current year plus facility system renewal needs going out to a set time in the future divided by Current Replacement Value.  |
| f  | Frequency  |
| F  | Fahrenheit   |
| Facility                                 | A facility refers to site(s) building(s) or building addition(s) or combinations thereof that provide a particular service.  |
| Facility Condition Assessment (FCA)      | FCA is a process for evaluating the condition of buildings and facilities for programming and budgetary purposes through an on site inspection and evaluation process.   |
| Facility Condition Index (FCI)           | FCI is an industry-standard measurement of a facility's condition that is the ratio of the cost to correct a facility's deficiencies to the Current Replacement Value of the facilities. The higher the FCI the poorer the condition of a facility. After an FCI is established for all buildings within a portfolio a building's condition can be ranked relative to other buildings. The FCI may also represent the condition of a portfolio based on the cumulative FCIs of the portfolio's facilities. |

## Site Assessment Report - S239001;Morris

---

|                         |   |
|-------------------------|---|
| FC                      | Footcandle  |
| FCA                     | Fuel Cost Adjustment  |
| FEMIA                   | Federal Energy Management Improvement Act of 1988   |
| FEMP                    | Federal Energy Management Program   |
| FERC                    | Federal Energy Regulatory Commission  |
| FESR                    | Fuel Energy Savings Ratio   |
| FLA                     | Full Load Amps  |
| FLF                     | Facility Load Factor (usually monthly)  |
| FLRPM                   | Full Load Revolutions per Minute  |
| FMS                     | Facility Management System  |
| FPM fpm                 | Feet per Minute (velocity)  |
| FSEC                    | Florida Solar Energy Center   |
| Ft                      | Foot  |
| GPM gpm                 | Gallons per Minute  |
| GRI                     | Gas Research Institute  |
| Gross Square Feet (GSF) | The size of the enclosed floor space of a building in square feet measured to the outside face of the enclosing wall. |
| GUI                     | Graphical User Interface  |
| H h                     | Enthalpy Btu/lb   |
| HCFC                    | Hydrochlorofluorocarbons  |
| HDD                     | Heating Degree days   |
| HFC                     | Hydrofluorocarbons  |
| HHV                     | Higher Heating Value  |
| HID                     | High Intensity Discharge (lamp)   |
| HMI                     | Human Machine Interface   |
| HMMI                    | Human Man Machine Interface   |
| HO                      | High Output (lamp)  |
| HP Hp hp                | Horsepower  |
| HPS                     | High Pressure Sodium (lamp)   |
| HR                      | Humidity Ratio  |
| Hr hr                   | Hour  |

## Site Assessment Report - S239001;Morris

---

|              |  |
|--------------|--|
| HRU          | Heat Recovery Unit   |
| HVAC         | Heating Ventilation and Air-Conditioning   |
| Hz           | Hertz  |
| I            | Intensity (lumen output of lamp)   |
| I i          | Interest rate or Discount rate   |
| IAQ          | Indoor Air Quality   |
| ICA          | International Cogeneration Alliance  |
| ICBO         | International Conference of Buildings Officials  |
| ICC          | International Code Council   |
| ICP          | Institutional Conservation Program   |
| IECC         | International Energy Conservation Code   |
| IEEE         | Institute of Electrical and Electronic Engineers   |
| IESNA        | Illuminating Engineering Society of North America  |
| Install year | The year a building or system was built or the most recent major renovation date (where a minimum of 70 of the system's Current Replacement Value (CRV) was replaced). |
| IRP          | Integrated Resource Planning   |
| IRR          | Internal Rate of Return  |
| ISO          | Independent System Operator  |
| ITA          | Independent Tariff Administrator   |
| k            | Kilo multiple of thousands in SI system  |
| K            | Kelvins (color temperature of lamp)  |
| K k          | Thermal Conductivity of Material   |
| KVA          | Kilovolt Ampere  |
| KVAR         | Kilovolt Ampere Reactive   |
| kW           | kiloWatt   |
| kWh          | kiloWatt hour  |
| L            | Length (usually feet)  |
| LCC          | Life Cycle Costing   |
| LDC          | Local Distribution Company   |
| LEED         | Leadership in Energy and Environmental Design  |
| LEED EB      | LEED for Existing Buildings  |

## Site Assessment Report - S239001;Morris

---

|              |  |
|--------------|--|
| LEED NC      | LEED for new construction  |
| LF           | Load Factor  |
| LHV          | Lower Heating Value  |
| Life cycle   | The period of time that a building or site system or element can be expected to adequately serve its intended function.        |
| LPS          | Low Pressure Sodium (lamp)   |
| Lu           | Lumen Output of a Lamp or Fixture  |
| M            | Mega multiple of millions in SI system   |
| M&V          | Measurement and Verification   |
| MACRS        | Modified Accelerated Cost Recovery System  |
| MARR         | Minimum Attractive Rate of Return  |
| Mbtu         | Thousand Btu   |
| MCF          | Thousand Cubic Feet (usually of gas)   |
| MEC          | Model Energy Code  |
| Mm           | Multiple of Thousands in I/P System  |
| MMBtu        | Million Btu  |
| MMCS         | Maintenance Management Computer System   |
| MMI          | Man Machine Interface  |
| MMS          | Maintenance Management System  |
| MSE 2000     | Management System for Energy 2000 (ANSI Georgia Tech Univ)   |
| MW           | MegaWatt   |
| MWH MWh      | MegaWatt hour  |
| NAAQS        | National Ambient Air Quality Standards   |
| NAESCO       | National Association of Energy Service Companies   |
| NAIMA        | North American Insulation Manufacturers Association  |
| NEA          | National Energy Act of 1978  |
| NECPA        | National Energy Conservation Policy Act  |
| NEMA         | National Electrical Manufacturer's Association   |
| NERC         | North American Electric Reliability Council  |
| Next Renewal | The Next Renewal date is an override of the 'Calculated Next Renewal' date and is based upon the assessor's visual inspection. |

## Site Assessment Report - S239001;Morris

---

|           |   |
|-----------|---|
| NFPA      | National Fire Protection Association                        |
| NGPA      | National Gas Policy Act of 1978                             |
| NLRPM     | No Load Revolutions per Minute (speed)                      |
| Nn        | Equipment or Project lifetime in economic analysis          |
| NOPR      | Notice of Proposed Rule Making from FERC                    |
| NOx       | Nitrogen Oxide Compounds                                    |
| NPV       | Net present value in economic analysis                      |
| NREL      | National Renewable Energy Laboratory                        |
| NUG       | Non-Utility Generator                                       |
| O&M       | Operation and Maintenance                                   |
| OA        | Outside Air   |
| ODP       | Ozone Depletion Potential                                   |
| OPAC      | Off-Peak Air Conditioning                                   |
| P         | Present value in economic analysis                          |
| PBR       | Performance Based Rates                                     |
| PEA       | Preliminary Energy Audit                                    |
| PF        | Power Factor  |
| PID       | Proportional plus integral plus derivative (control system) |
| PM        | Portfolio Manager in Energy Star rating system              |
| PM        | Preventive Maintenance                                      |
| PoolCo    | Power Pool Company or Organization                          |
| POU       | Point of Use  |
| PQ        | Power Quality   |
| PSC       | Public Service Commission                                   |
| PSIA psia | Pounds per square inch absolute (pressure)                  |
| PSIG psig | Pounds per square inch gauge (pressure)                     |
| PUC       | Public Utility Commission                                   |
| PUHCA     | Public Utilities Holding Company Act of 1935                |
| PURPA     | Public Utilities Regulatory Policies of 1978                |
| PV        | Photovoltaic system   |

## Site Assessment Report - S239001;Morris

---

|                                     |   |
|-------------------------------------|---|
| PV                                  | Present Value   |
| PW                                  | Present Worth   |
| PX                                  | Power Exchange  |
| q                                   | Rate of heat flow in Btu per hour   |
| Q                                   | Heat load due to conduction using degree days   |
| QF                                  | Qualifying Facility   |
| R                                   | Electrical resistance   |
| R                                   | Thermal Resistance  |
| RC                                  | Remote controller   |
| RCR                                 | Room Cavity Ratio   |
| RCRA                                | Resource Conservation and Recovery Act  |
| Remaining Service Life (RSL)        | RSL is the number of years service remaining for a system or equipment item. It is automatically calculated based on the difference between the current year and the 'Calculated Next Renewal' date or the 'Next Renewal' date whichever one is the later date. |
| Remaining Service Life Index (RSLI) | RSLI is defined as a percentage ratio of the remaining service life of a system. It usually ranges from 0 to 100  |
| REMR                                | Repair Evaluation Maintenance Rehabilitation (REMR) is a scale used to objectively rank systems based on their condition  |
| Renewal Schedule                    | A timeline that provides the items that need repair the year in which the repair is needed and the estimated price of the renewal.  |
| RH                                  | Relative Humidity   |
| RLA                                 | Running Load Amps   |
| RMS                                 | Root Mean Square  |
| RO                                  | Reverse Osmosis   |
| ROI                                 | Return on Investment  |
| RPM                                 | Revolutions Per Minute  |
| RTG                                 | Regional Transmission Group   |
| RTO                                 | Regional Transmission Organization  |
| RTP                                 | Real Time Pricing   |
| SBCCI                               | Southern Building Code Congress International   |
| SC                                  | Scheduling Coordinator  |
| SC                                  | Shading Coefficient   |
| SCADA                               | Supervisory Control and Data Acquisition Systems  |

## Site Assessment Report - S239001;Morris

---

|              |  |
|--------------|--|
| SEER         | Seasonal Energy Efficiency Ratio   |
| SHR          | Sensible Heat Ratio  |
| Site         | The grounds and utilities roadways landscaping fencing and other typical land improvements needed to support the facility.   |
| Soft Cost    | An expense item that is not considered direct construction cost. Soft cost includes architectural engineering financing legal fees and other pre-and-post construction expenses.   |
| SOx          | Sulfur Oxide Compounds   |
| SP           | Static Pressure  |
| SP SPB       | Simple Payback   |
| SPP          | Simple Payback Period  |
| SPP          | Small Power Producers  |
| STR          | Stack Temperature Rise   |
| SV           | Specific Volume  |
| System       | System refers to building and related site work elements as described by ASTM Uniformat II Classification for Building Elements (E1557-97) a format for classifying major facility elements common to most buildings. Elements usually perform a given function regardless of the design specification construction method or materials used. See also Uniformat II. |
| T            | Temperature  |
| T            | Tubular (lamps)  |
| TAA          | Technical Assistance Audit   |
| TCP/IP       | Transmission Control Protocol/Internet Protocol  |
| TES          | Thermal Energy Storage   |
| THD          | Total Harmonic Distortion  |
| TOD          | Time of Day  |
| TOU          | Time of Use  |
| TQM          | Total Quality Management   |
| TransCo      | Transmission Company   |
| U            | Thermal Conductance  |
| UDC          | Utility Distribution Company   |
| UL           | Underwriters Laboratories  |
| UNIFORMAT II | The ASTM UNIFORMAT II Classification for Building Elements (E1557-97) a format for classifying major facility components common to most buildings.   |
| USGBC        | US Green Building Council  |
| v            | Specific Volume  |



## Site Assessment Report - S239001;Morris

---

|            |   |
|------------|---|
| V          | Volts Voltage   |
| V          | Volume  |
| VAV        | Variable Air Volume   |
| VDT        | Video Display Terminal  |
| VFD        | Variable Frequency Drive  |
| VHO        | Very High Output  |
| VSD        | Variable Speed Drive  |
| W          | Watts   |
| W          | Width   |
| WB         | Wet bulb  |
| WH Wh      | Watt Hours  |
| Year built | The year that a building or addition was originally built based on substantial completion or occupancy. |
| Z          | Electrical Impedance  |