

Facility Condition Assessment Summary Report

This report provides a summary of the Facility Condition Index (FCI) value of a school facility and select major building systems. The FCI calculation represents the cost of needed repairs divided by the replacement value. The FCI is a numerical value of condition and helps to identify the need for renewal or replacement of specific parts of the facility. The FCI is particularly useful when comparing similar facilities within the same portfolio.

Sharswood School

| | | | |
|------------|---|---------------------|------------------|
| Governance | DISTRICT | Report Type | Elementarymiddle |
| Address | 2300 S. 2Nd St. Philadelphia, Pa 19148 | Enrollment | 572 |
| Phone/Fax | 215-952-6212 / 215-952-6405 | Grade Range | '00-08' |
| Website | Www.Philasd.Org/Schools/Sharswood | Admissions Category | Neighborhood |
| | | Turnaround Model | N/A |

Building/System FCI Tiers

| Facility Condition Index (FCI) = $\frac{\text{Cost of Assessed Deficiencies}}{\text{Replacement Value}}$ | | | | |
|--|-------------------------------|---|---|--|
| < 15% | 15 to 25% | 25 to 45% | 45 to 60% | > 60% |
| Buildings | | | | |
| Minimal Current Capital Funding Required | Refurbish Systems in building | Replace Systems in building. | Building should be considered for major renovation. | Building should be considered for closing/replacement. |
| Systems | | | | |
| Perform routine maintenance on system | System requires minor repairs | System should be studied to determine repair vs. replacement. | System is nearing end of its life expectancy and should be considered for replacement | System should be replaced as part of the Capital Program |

Building and Grounds

| | FCI | Repair Costs | Replacement Cost |
|----------------|---------------|---------------------|---------------------|
| Overall | 26.74% | \$10,031,183 | \$37,510,744 |
| Building | 26.97 % | \$9,776,523 | \$36,249,119 |
| Grounds | 20.19 % | \$254,660 | \$1,261,625 |

Major Building Systems

| Building System | System FCI | Repair Costs | Replacement Cost |
|--|------------|--------------|------------------|
| Roof (Shows physical condition of roof) | 89.29 % | \$806,358 | \$903,030 |
| Exterior Walls (Shows condition of the structural condition of the exterior facade) | 00.36 % | \$9,687 | \$2,694,430 |
| Windows (Shows functionality of exterior windows) | 115.14 % | \$1,513,843 | \$1,314,730 |
| Exterior Doors (Shows condition of exterior doors) | 06.60 % | \$6,987 | \$105,850 |
| Interior Doors (Classroom doors) | 13.03 % | \$33,394 | \$256,230 |
| Interior Walls (Paint and Finishes) | 21.09 % | \$243,860 | \$1,156,320 |
| Plumbing Fixtures | 06.14 % | \$60,634 | \$986,960 |
| Boilers | 00.00 % | \$0 | \$1,362,910 |
| Chillers/Cooling Towers | 40.44 % | \$722,673 | \$1,787,040 |
| Radiators/Unit Ventilators/HVAC | 22.82 % | \$716,264 | \$3,138,270 |
| Heating/Cooling Controls | 132.68 % | \$1,307,533 | \$985,500 |
| Electrical Service and Distribution | 122.30 % | \$865,981 | \$708,100 |
| Lighting | 26.67 % | \$675,296 | \$2,531,640 |
| Communications and Security (Cameras, Pa System and Fire Alarm) | 34.60 % | \$328,123 | \$948,270 |

Please note that some FCIs may be over 100% because there are times when replacing a building system requires that other building systems be upgraded to complete the installation. A FCI of 0.0% represents that there are no current deficiencies with the associated system.

School District of Philadelphia
S263001;Sharswood
Final
Site Assessment Report
January 31, 2017



Table of Contents

| | |
|---|----|
| Site Executive Summary | 4 |
| Site Condition Summary | 9 |
| <u>B263001:Sharswood</u> | 11 |
| Executive Summary | 11 |
| Condition Summary | 12 |
| Condition Detail | 13 |
| System Listing | 14 |
| System Notes | 16 |
| Renewal Schedule | 17 |
| Forecasted Sustainment Requirement | 20 |
| Condition Index Forecast by Investment Scenario | 21 |
| Deficiency Summary By System | 22 |
| Deficiency Summary By Priority | 23 |
| Deficiency By Priority Investment | 24 |
| Deficiency Summary By Category | 25 |
| Deficiency Details By Priority | 26 |
| Equipment Inventory Detail | 40 |
| <u>G263001:Grounds</u> | 41 |
| Executive Summary | 41 |
| Condition Summary | 42 |
| Condition Detail | 43 |
| System Listing | 44 |
| System Notes | 45 |
| Renewal Schedule | 46 |
| Forecasted Sustainment Requirement | 47 |
| Condition Index Forecast by Investment Scenario | 48 |
| Deficiency Summary By System | 49 |
| Deficiency Summary By Priority | 50 |
| Deficiency By Priority Investment | 51 |

Site Assessment Report

| | |
|--------------------------------|----|
| Deficiency Summary By Category | 52 |
| Deficiency Details By Priority | 53 |
| Equipment Inventory Detail | 56 |
| Glossary | 57 |

Site Executive Summary

The organization of this report, as displayed in the Table of Contents, follows the structure of the associated eCOMET database. The overall node for each school campus begins with the letter "S", which indicates the "Site" label. Each Site is comprised of separate "Building" and "Grounds" nodes; their asset names begin with the letters "B" and "G" respectively. Information rolls up to the Site node from the Building and Grounds nodes. This Site report combines facility information with subsections for the Buildings And Grounds nodes.

The basis for the evaluation of condition is the functional systems and elements of a building and grounds organized according to the UNIFORMAT II Elemental Classification. The grouping of these systems and elements and applying a current replacement value to them develops a representative building cost model. Cost Models are typically developed for similar building types and functions. Evaluation of systems and their elements takes into account their current replacement values, life cycles, installation dates and next renewal dates. Systems and their elements that are within their useful lives are further evaluated to identify current deficient conditions that may have a significant impact on a system's or element's remaining service life, and to determine if they are beyond their predicted expected life. The system's or element's current replacement value is based on RS Means Commercial Cost Data.

Following are the cost model's system details for this facility. The Replacement Value is the amount needed to replace the property of the same present value. The Current Repair Amount, also known as Condition Needs, represents the budgeted contractor installed costs plus owner's soft costs for the repair, replacement or renewal for a component or system level deficiency. It excludes contributing costs for other components or systems that might also be associated with the corrective actions due to packaging the work. Facility Condition Index (FCI) is an industry-standard measurement calculated as the ratio of the repair costs to correct a facility's deficiencies to the facility's Current Replacement Value. Condition Index (CI) for a system is calculated as the sum of the deficiencies divided by the sum of a system's Replacement Value (both values include soft-cost) expressed as a percentage ranging from 0% 100%.

| | |
|--------------------|-----------------|
| Gross Area (SF): | 80,000 |
| Year Built: | 1906 |
| Last Renovation: | |
| Replacement Value: | \$37,510,744 |
| Repair Cost: | \$10,031,183.03 |
| Total FCI: | 26.74 % |
| Total RSLI: | 60.45 % |



Description:

Facility Assessment

July 21th, 2015

School District of Philadelphia

Sharswood Elementary School

2300 S 2nd Street

Philadelphia, PA 19148

73,000 SF / 596 Students / LN 01

GENERAL

Building Engineer, accompanied us on our tour of the school and provided us with detailed information on the building systems and maintenance

Site Assessment Report - S263001;Sharswood

history.

The 4 story, 73,000 square foot building was originally constructed in 1906. The building has a multi-level basement.

ARCHITECTURAL/STRUCTURAL SYSTEMS

The building rests on concrete foundations and bearing walls that are not showing signs of settlement or damage. The main structure consists typically of cast-in-place concrete columns, beams, and concrete one way ribbed slab. The roof structure consists of concrete one-way slab supported by main structural frame. Roofing is built up application in poor condition, uneven with evidence of ponding and in need of replacement. The building envelope is typically masonry with face brick. Elevations are enhanced minimally with decorative stonework around entrances and windows. In general, masonry is in good condition with some cracks in parapet wall. All elevations are face brick in need of re-pointing. The original windows were replaced in early 1990s with extruded aluminum, double hung windows, Lexan Plexiglas with insect/security screens. All windows are generally in poor condition with heavy hazing. Exterior doors are typically hollow metal in fair condition. Public access doors have granite stoops with granite stairs; service doors have concrete stoops and stairs. Generally, the building is not accessible per ADA requirements due to first floor- grade separation with no ramps or lifts.

Partition wall types include plastered ceramic hollow blocks with some CMU added at a later date. Interior doors are generally wood frame with solid core and wood panel doors with lites and transoms in fair condition. Doors leading to exit stairways are hollow metal doors and frames in good condition. Interior doors do not have lever type handles. Fittings include: toilet accessories in good condition; composite plastic toilet partitions, generally in good condition; handrails and ornamental metals, generally in fair condition. Toilet partitions and accessories are not ADA accessible. Interior identifying signage is typically directly painted on wall or door surfaces generally in poor condition. Stair construction is generally steel and concrete with cast iron treads and nosing in good condition. Stair railings are cast iron balusters with wood handrail in fair condition.

The interior wall finishes include painted plaster, brick, or CMU with glazed brick wainscot in fire towers, basement corridor, and cafeteria in good condition; and tile wainscot in toilets areas in good condition. Generally, paint is in good condition with some deterioration in basement areas and fire towers. Flooring includes: patterned or bare concrete in corridors, stairways, and fire towers in good condition; hardwood in most classrooms, auditorium, and stage in fair condition; vinyl tile in some classrooms, cafeteria, and offices; and ceramic tile in toilets in good condition. Wood base is typically in fair-good condition. Ceiling finishes include: suspended acoustic tile system in some classrooms, IMC, and offices; painted plaster or structural concrete in most classrooms, corridors, toilets, auditorium, cafeteria and basement areas in fair condition with some areas in need or re-painting.

The building has no elevators.

Institutional and Commercial equipment includes: stage equipment, generally in fair condition. Other equipment includes kitchen equipment (heat and serve only), generally in good condition.

Fixed furnishings include: fixed casework in classrooms, corridors and library, generally in fair to good condition; window shades/blinds in fair condition; and fixed auditorium seating in good condition.

MECHANICAL SYSTEMS

Building plumbing fixtures are mostly modern low flow equipment. Restroom fixtures on each floor consist of wall hung urinals and lavatories, and water closets. Sinks have push button momentary action mixing faucets while others have twist knob, momentary action, separate hot and cold faucets. Kindergarten room has child sized, floor mounted water closets. Faucets and flush valves work well. The fixtures should provide reliable service for at least 5 to 10 years.

Third floor science classroom has a stainless steel single basin lab sink with two swan neck faucets. There is a single basin, rim mounted, stainless steel kitchen sink in the second floor teacher lounge which is in good condition. Life skills classroom in the basement is equipped similarly to the lounge. The cafeteria kitchen has a floor standing, stainless steel, 2 basin cook sink, and there is a wall mounted porcelain lavatory in the cafeteria dining room. Janitor closets on each floor have floor mounted polymer service sinks with mixing faucets with vacuum breaker spouts. Sinks will not need replacement in the next 10 years.

Drinking fountains in the corridors, kindergarten room, and teacher lounge are a variety of styles, generally non-accessible. They have exceeded their service life and should be replaced.

Domestic water distribution piping is soldered copper and provides adequate flow for all fixtures. The building does not have a pressure booster pump system. The water heater is a Bradford White, gas fired, 75 gallon vertical tank installed in January 2015. It has a circulation pump controlled by an aquastat. The domestic water distribution should be serviceable until at least 2025.

Site Assessment Report - S263001;Sharswood

Sanitary drain pipes are primarily hub and spigot cast iron with hubless banded connection pipe for repairs in some locations. Due to their age they should be inspected in detail and repaired as needed. There is no sewage ejector.

Roof drain pipes were inaccessible because their pipe chases have been covered over with metal sheeting. They should be inspected and repaired at the time of roof replacement or sanitary drain pipe inspection.

The building was originally constructed with central forced air and steam radiator heating. When the ells were added to the original construction, the system was expanded with additional air handlers in the new construction. Since then, the radiators have been mostly replaced by finned tube steam convectors and the air handlers have fallen into disuse.

Steam for heat is generated by 2 Weil-McLain model 1694, 3,385 MBH (101 HP) net capacity, cast iron boilers with dual fuel Power Flame burners. They were installed in 1991 and have 10 years life remaining. Boiler feed water is supplied by two primary and 1 spare pump located at the feed water tank. There is a water softener for make-up water. Gas service enters the building in the northeast corner along 2nd street. There is a gas booster. Fuel oil is stored in an 8,000 gallon underground tank in the yard. Two oil pumps are located in the basement generator room behind the boiler room. Combustion make-up air enters the building through automatically controlled louvers in the generator room.

The IMC is cooled by a 5 ton direct expansion outside unit located on the southwestern fire tower roof and a fan coil unit located above the drop ceiling. The computer network room is cooled by a Mitsubishi mini-split system. Several classrooms and offices have window unit air conditions.

In total, the building has about 30 tons of cooling presently, which is insufficient. A central cooling system of 150 ton capacity should be installed.

The air handlers in the basement mechanical rooms provided ventilation and heat but are obsolete and currently appear to be unused. The original masonry ducts which connect the air handlers to the classrooms and then to the attic plenum are open in most of the rooms. The existing air handlers should be removed and replaced with modern units including cooling coils and digital controls and the duct work should be renovated to restore classroom ventilation. Steam and condensate pipe is threaded steel estimated installed in 1991 the same time as the boilers, and it should have 6 years useful life remaining.

Classrooms and offices are heated with finned tube steam convectors however radiators remain in the basement level. All units have exceeded their service life, but the convectors are in good condition and can be expected to last another 10 years. The cast iron and steel radiators are estimated to be 80 years old (or older) and should be upgraded to finned tube units.

Pneumatic controls were added to the build some time ago. They include wall mounted thermostats in the classrooms and remote control steam valves on the convectors and radiators. They are past their service life, obsolete, damaged, and most likely inoperable. They should be upgraded to DDC when other HVAC system components replaced.

The school does not have stand pipes or sprinkler system. A sprinkler system should be added including fire pump if needed.

ELECTRICAL SYSTEMS

Most probably a service drop on S. 2nd Street provides the incoming service to this school. The electrical service entrance is located in the basement at the fan room. The fan room houses the utility main disconnect switch, the utility meters 222MU-13460 and PECO 47123576785 and (2) 400A, 120/240V distribution sections. The existing service has no extra capacity for expansion or new Heating, Ventilation, Air Conditioning (HVAC) system. The electrical service entrance should be upgraded. The new service will be 480V/277V, 3 phase power, approximate 1000 Amperes and will be located in the vicinity of the existing electrical service. The new electrical service would feed a 480V Motor Control Center (MCC) and HVAC (Heating, Ventilation and Air Conditioning) equipment and a 480V 3 phase to 120V/208V 3 phase, 300KVA step-down transformer to feed receptacles, lighting fixtures and other smaller loads.

There are 120/240V panel-boards in each floor for lighting and receptacles. These panel-boards and associated wiring have exceeded the end of their useful life and are undersized to absorb additional loads. The entire distribution system needs to be replaced with new 208/120 volt, 3 phase panelboards and new wiring. The raceway is mainly conduits run above the ceiling. There is a 50KVA phase converter from 240V to 120/208V which normally feeds newest mechanical equipment. Panel-board's doors at corridors are not locked and represent a potential hazard for students. As a safety issue all panel-boards at corridor or in areas where students are present must be provided with lockable devices.

There number of receptacles in classrooms varies, approximate 15% of the classrooms have been remodeled and provided with the proper amount of receptacles but 85% of them the quantity of receptacles are inadequate. Teachers use extension cords. Provide approximate 27 classrooms with the teacher's whiteboard wall and the opposite of it with double compartment surface raceways, the other two walls with minimum two duplex outlets each, when feasible.

Site Assessment Report - S263001;Sharswood

The school is illuminated with pendant mounted fluorescent fixtures except some remodeled rooms that are illuminated with recessed mounted fluorescent fixtures. Approximate 85% of the lighting fixtures are provided with T-12 lamps. Provide lighting fixtures with T-8 lamps.

A tap ahead of the main disconnect switch serves the fire alarm control panel (FACP). The Fire Alarm system is manufactured by S.H. COUCH INC. The system is approximately 30 years old. The present Fire Alarm system does not meet current code. Fire alarm system is tested every day in the morning. Provide a new fire alarm system.

The present telephone system is adequate.

An independent and separate PA system does not exist. School uses the telephone systems for public announcement. This system is working adequately for most part. The obsolete, non-functional devices should be removed from all rooms.

The present clocks is old and manufactured by Simplex and does not work. A new clock system should be provided with battery operated and wireless.

There is not television system.

The security system consists of CCTV cameras at first floor and basement and motion sensors at first floor. The location of the video surveillance monitor was not determined.

The emergency power system consists of a gas powered generator, manufactured by Generac rated 15KVA, 120/240V with (3) 70A output circuit breakers. The present emergency power system serves the corridor, exit signs, auditorium, library, gymnasium, stair ways and fire tower. The gas powered generator is approximately 20 years old and has reached its useful service life. Provide an outdoor, diesel powered 75KW generator.

There is adequate UPS in the IT room.

The emergency lighting is obtained with dedicated fixtures connected to the emergency generator. Exit signs are located at each exit door and corridors and are connected to the school emergency system.

The chimney is provided with one air terminal. A study should be conducted to determine if the existing lightning system provide the proper protection to the school building.

The auditorium is not provided with theatrical lighting nor dimming control system. Provide theatrical lighting and dimming control system

The auditorium is provided with local sound system. Provide a more complete sound system

GROUNDS SYSTEMS

The site surrounds the building on all four sides which is set back from the street. Yard area on north, south, and west sides is concrete paving with parking for staff vehicles on south east corner separated by metal fence and accessible via Ritner St. Paving, including driveway and access to entrances is in fair condition with some cracks and spalling developed. Metal fence surrounding most of the site is in good condition with a need for lockable gates for security of the property.

Accessibility: the building does not have accessible entrance, and accessible routes. None of the toilets are equipped with accessible fixtures, partitions and accessories, such as grab bars and accessible partitions. None of the doors in the building have ADA required door handles.

The school perimeter is illuminated from wall mounted fixtures, as a safety issue provide 6 pole mounted lighting fixtures in the parking area and playground.

There are (2) CCTV cameras on the building exterior. Provide additional CCTV cameras to provide complete coverage of the building perimeter.

There are not exterior speakers for site paging. Provide two loud speakers in front of the parking lot and playground.

RECOMMENDATIONS

- [Repair and re-point parapet walls](#)
- Replace Plexiglas windows – hazed
- Replace built-up roofing system – leaking, failing, and beyond service life

Site Assessment Report - S263001;Sharswood

- Provide ADA compliant exterior door hardware at one entrance
- Provide ADA lever handle lock/latchsets on interior doors
- Provide new toilet partitions and toilet accessories including grab bars for accessibility
- Install new ID signage
- Repaint interior walls in basement & fire towers
- Repaint ceilings in basement
- Install elevator for accessibility (location TBD)
- Provide ADA compliant ramp at one entrance (location TBD)

- Replace aged, non-accessible drinking fountains.
- Inspect drainage pipes and repair as needed.
- Install 150 ton central cooling system for entire building.
- Replace obsolete air handlers and radiators with modern equipment including cooling coils and digital controls and renovate ductwork to supply fresh air to classrooms.
- Upgrade obsolete pneumatic control system to digital.
- Install fire sprinkler system including fire pump if needed.
- Provide a new electrical service 480V/277V, 3 phase power, approximate 1000 Amperes and will be located in the vicinity of the existing electrical service.
- Replace the entire distribution system with new panels and new wiring/conduits. Approximate (15) 208/120V
- Provide (2)25FT of surface raceways with 24" receptacles on center and two-duplex wall mount receptacles. Approximate 27 classrooms
- Approximate 90% of the lighting fixtures are provided with T-12 lamps. Provide lighting fixtures with T-8 lamps. Approximate 869 fixtures.
- Replace old fire alarm system with addressable type with audio/visual devices in the entire school. Approximate 100 devices
- Provide a new clock system, wireless battery operated. Approximate 55 clocks
- Provide an outdoor, diesel powered 75KW generator.
- Prepare a study to determine if existing lightning protection system provide the proper coverage to the school building.
- Provide the auditorium with theatrical lighting and dimming control system
- Provide a more complete sound system
- Provide 6 pole mounted lighting fixtures in the parking area and playground.
- Provide additional CCTV cameras to provide complete coverage of the building perimeter. Approximate 4
- Provide two loud speakers in front of the parking lot and playground.

Attributes:

General Attributes:

| | | | |
|----------|-----------------|--------------|--------------|
| Active: | Open | Bldg Lot Tm: | Lot 1 / Tm 3 |
| Status: | Accepted by SDP | Team: | Tm 3 |
| Site ID: | S263001 | | |

Site Condition Summary

The Table below shows the CI and FCI for each major system shown at the UNIFORMAT classification Level II. Note that Systems with lower FCIs require less investment than systems with higher FCIs.

Current Investment Requirement and Condition by Uniformat Classification

| UNIFORMAT Classification | RSLI% | FCI % | Current Repair |
|---------------------------------|----------------|----------------|------------------------|
| A10 - Foundations | 37.00 % | 0.00 % | \$0.00 |
| A20 - Basement Construction | 37.00 % | 0.00 % | \$0.00 |
| B10 - Superstructure | 37.00 % | 0.00 % | \$0.00 |
| B20 - Exterior Enclosure | 38.04 % | 37.19 % | \$1,530,517.35 |
| B30 - Roofing | 110.00 % | 89.29 % | \$806,357.98 |
| C10 - Interior Construction | 36.74 % | 3.09 % | \$55,395.71 |
| C20 - Stairs | 37.00 % | 0.00 % | \$0.00 |
| C30 - Interior Finishes | 50.33 % | 9.57 % | \$331,222.83 |
| D10 - Conveying | 0.00 % | 257.94 % | \$670,322.07 |
| D20 - Plumbing | 33.57 % | 28.09 % | \$418,753.25 |
| D30 - HVAC | 89.05 % | 33.82 % | \$2,746,469.49 |
| D40 - Fire Protection | 92.47 % | 177.49 % | \$1,044,299.01 |
| D50 - Electrical | 110.11 % | 48.53 % | \$2,082,382.43 |
| E10 - Equipment | 48.49 % | 7.81 % | \$90,802.49 |
| E20 - Furnishings | 12.50 % | 0.00 % | \$0.00 |
| G20 - Site Improvements | 50.10 % | 6.38 % | \$59,181.86 |
| G40 - Site Electrical Utilities | 0.00 % | 58.51 % | \$195,478.56 |
| Totals: | 60.45 % | 26.74 % | \$10,031,183.03 |

Condition Deficiency Priority

| Facility Name | Gross Area (S.F.) | FCI % | 1 - Response Time (< 2 yr) | 2 - Response Time (2-3 yrs) | 3 - Response Time (3-4 yrs) | 4 - Response Time (4-5 yrs) | 5 - Response Time (> 5 yrs) |
|-------------------|-------------------|--------------|----------------------------|-----------------------------|-----------------------------|-----------------------------|-----------------------------|
| B263001;Sharswood | 73,000 | 26.97 | \$806,357.98 | \$2,869,959.66 | \$2,721,207.52 | \$2,656,324.74 | \$722,672.71 |
| G263001;Grounds | 57,500 | 20.19 | \$0.00 | \$195,478.56 | \$59,181.86 | \$0.00 | \$0.00 |
| Total: | | 26.74 | \$806,357.98 | \$3,065,438.22 | \$2,780,389.38 | \$2,656,324.74 | \$722,672.71 |

Deficiencies By Priority



- 1 - Response Time (< 2 yr) - \$806,357.98
- 2 - Response Time (2-3 yrs) - \$3,065,438.22
- 3 - Response Time (3-4 yrs) - \$2,780,389.38
- 4 - Response Time (4-5 yrs) - \$2,656,324.74
- 5 - Response Time (> 5 yrs) - \$722,672.71

Budget Estimate Total: \$10,031,183.03

Executive Summary

Building condition is evaluated based on the functional systems and elements of a building and organized according to the UNIFORMAT II Elemental Classification. The grouping of these systems and elements and applying a current replacement value to them develops a representative building cost model. Cost Models are developed for similar building types and functions. Systems and their elements are evaluated based on their current replacement values, life cycles, installation dates and next renewal dates. Systems and their elements that are within their useful lives are further evaluated to identify current deficient conditions that may have a significant impact on a system's or element's remaining service life, and to determine if they are beyond their predicted expected life. The system's or element's current replacement value is based on RS Means Commercial Cost Data.

Following are the cost model's system details for this facility. The Replacement Value is the amount needed to replace the property of the same present value. The Current Repair Amount, also known as Condition Needs, represents the budgeted contractor installed costs plus owner's soft costs for the repair, replacement or renewal for a component or system level deficiency. It excludes contributing costs for other components or systems that might also be associated with the corrective actions due to packaging the work. Facility Condition Index (FCI) FCI is an industry-standard measurement of facility condition calculated as the ratio of the costs to correct a facility's deficiencies to the facility's Current Replacement Value. It ranges from 0% (new) to 100% (very poor). Condition Index (CI) is calculated as the sum of a renewable system's Remaining Service Life (RSL) divided by the sum of a system's Replacement Value (both values exclude soft-cost to simplify calculation updates) expressed as a percentage ranging from 100% (new) to 0% (expired).

| | |
|--------------------|-------------------|
| Function: | Elementary School |
| Gross Area (SF): | 73,000 |
| Year Built: | 1906 |
| Last Renovation: | |
| Replacement Value: | \$36,249,119 |
| Repair Cost: | \$9,776,522.61 |
| Total FCI: | 26.97 % |
| Total RSLI: | 61.27 % |

Description:

Attributes:

General Attributes:

| | | | |
|-----------------|---------|----------|-----------------|
| Active: | Open | Bldg ID: | B263001 |
| Sewage Ejector: | No | Status: | Accepted by SDP |
| Site ID: | S263001 | | |

Condition Summary

The Table below shows the CI and FCI for each major building system shown at the UNIFORMAT classification Level II. Note that Systems with lower FCIs require less investment than systems with higher FCIs.

| UNIFORMAT Classification | RSLI % | FCI % | Current Repair Cost |
|-----------------------------|----------------|----------------|-----------------------|
| A10 - Foundations | 37.00 % | 0.00 % | \$0.00 |
| A20 - Basement Construction | 37.00 % | 0.00 % | \$0.00 |
| B10 - Superstructure | 37.00 % | 0.00 % | \$0.00 |
| B20 - Exterior Enclosure | 38.04 % | 37.19 % | \$1,530,517.35 |
| B30 - Roofing | 110.00 % | 89.29 % | \$806,357.98 |
| C10 - Interior Construction | 36.74 % | 3.09 % | \$55,395.71 |
| C20 - Stairs | 37.00 % | 0.00 % | \$0.00 |
| C30 - Interior Finishes | 50.33 % | 9.57 % | \$331,222.83 |
| D10 - Conveying | 0.00 % | 257.94 % | \$670,322.07 |
| D20 - Plumbing | 33.57 % | 28.09 % | \$418,753.25 |
| D30 - HVAC | 89.05 % | 33.82 % | \$2,746,469.49 |
| D40 - Fire Protection | 92.47 % | 177.49 % | \$1,044,299.01 |
| D50 - Electrical | 110.11 % | 48.53 % | \$2,082,382.43 |
| E10 - Equipment | 48.49 % | 7.81 % | \$90,802.49 |
| E20 - Furnishings | 12.50 % | 0.00 % | \$0.00 |
| Totals: | 61.27 % | 26.97 % | \$9,776,522.61 |

Condition Detail

This section of the report contains results of the Facility Condition Assessment. The building is separated into system components based on UNIFORMAT II classification. The columns in the System Listing table below represent the following:

1. System Code: A code that identifies the system.
2. System Description: A brief description of a system present in the building.
3. Unit Price \$: The unit price of the system.
4. UoM: The unit of measure for of the system.
5. Qty: The quantity for the system
6. Life: anticipated service life for thesystem based on Building Owners and Managers Association (BOMA) recommendations.
7. Year Installed: The date of system installation.
8. Calc Next Renewal Year: The date of system expiration based on the life, NR stands for non renewable.
9. Next Renewal Year: The suggested system expiration date by the assessor based on visual inspection.
10. CI: The Condition Index of the system.
11. FCI: The Facility Condition Index of the system.
12. RSL: Remaining Service Life.
13. eCR: eCOMET Condition Rating (not used).
14. Deficiency \$: The financial investment to repair/replace system.

System Listing

The System Listing table below lists each of the systems organized by their UNIFORMAT II classification. The assessment team was tasked with recording the most recent replacement year of each system, determining the remaining service life based on the theoretical life, and evaluating the condition to confirm the forecast next replacement year. The system listing is the basis for all data contained in the Building Assessment Report.

Additionally, a condition rating (eCR) based on the following guidelines is provided as observed at the time of the assessment.

- Excellent (E) - No noticeable distress or damage. The entire system is free from observable defect.
- Very Good (VG) - Overall no serviceability reduction for the entire system. No degradation of critical components and minor distress and defect noticeable for some but not non critical components within the system.
- Good (G) - Slight or no serviceability reduction for the entire system. There may be noticeable defects for some non critical components and slight noticeable degradation of the critical components.
- Fair (F) - Overall serviceability is degraded but adequate. There may be moderate deterioration for very few of the critical components and few of the non critical components may have severe degradation.
- Marginal (MA) - Overall serviceability and reliability loss. Most if not all of the non critical components suffer from severe degradation and a few of the critical component may have severe degradation.
- Moderate (MO) - Overall a significant serviceability loss. Most if not all the components have severe degradation with the reminder of the component showing visible distress.
- Very Poor (VP) - Overall the system is barely functional. All of the components are severely degraded.
- Non-Functional (NF) - Overall the system does not function with all the components having no serviceability and suffer from severe degradation.

| System Code | System Description | Unit Price \$ | UoM | Qty | Life | Year Installed | Calc Next Renewal Year | Next Renewal Year | RSLI% | FCI% | RSL | eCR | Deficiency \$ | Replacement Value \$ |
|-------------|----------------------|---------------|------|--------|------|----------------|------------------------|-------------------|----------|----------|-----|-----|----------------|----------------------|
| A1010 | Standard Foundations | \$18.40 | S.F. | 73,000 | 100 | 1906 | 2006 | 2052 | 37.00 % | 0.00 % | 37 | | | \$1,343,200 |
| A1030 | Slab on Grade | \$7.73 | S.F. | 73,000 | 100 | 1906 | 2006 | 2052 | 37.00 % | 0.00 % | 37 | | | \$564,290 |
| A2010 | Basement Excavation | \$6.55 | S.F. | 73,000 | 100 | 1906 | 2006 | 2052 | 37.00 % | 0.00 % | 37 | | | \$478,150 |
| A2020 | Basement Walls | \$12.70 | S.F. | 73,000 | 100 | 1906 | 2006 | 2052 | 37.00 % | 0.00 % | 37 | | | \$927,100 |
| B1010 | Floor Construction | \$75.10 | S.F. | 73,000 | 100 | 1906 | 2006 | 2052 | 37.00 % | 0.00 % | 37 | | | \$5,482,300 |
| B1020 | Roof Construction | \$13.88 | S.F. | 73,000 | 100 | 1906 | 2006 | 2052 | 37.00 % | 0.00 % | 37 | | | \$1,013,240 |
| B2010 | Exterior Walls | \$36.91 | S.F. | 73,000 | 100 | 1906 | 2006 | 2052 | 37.00 % | 0.36 % | 37 | | \$9,686.84 | \$2,694,430 |
| B2020 | Exterior Windows | \$18.01 | S.F. | 73,000 | 40 | 1991 | 2031 | | 40.00 % | 115.14 % | 16 | | \$1,513,843.23 | \$1,314,730 |
| B2030 | Exterior Doors | \$1.45 | S.F. | 73,000 | 25 | 2000 | 2025 | | 40.00 % | 6.60 % | 10 | | \$6,987.28 | \$105,850 |
| B3010105 | Built-Up | \$37.76 | S.F. | 23,799 | 20 | 1995 | 2015 | 2037 | 110.00 % | 89.73 % | 22 | | \$806,357.98 | \$898,650 |
| B3020 | Roof Openings | \$0.06 | S.F. | 73,000 | 20 | 1995 | 2015 | 2037 | 110.00 % | 0.00 % | 22 | | | \$4,380 |
| C1010 | Partitions | \$17.91 | S.F. | 73,000 | 100 | 1906 | 2006 | 2052 | 37.00 % | 0.00 % | 37 | | | \$1,307,430 |
| C1020 | Interior Doors | \$3.51 | S.F. | 73,000 | 40 | 1980 | 2020 | | 12.50 % | 13.03 % | 5 | | \$33,394.17 | \$256,230 |
| C1030 | Fittings | \$3.12 | S.F. | 73,000 | 40 | 2000 | 2040 | | 62.50 % | 9.66 % | 25 | | \$22,001.54 | \$227,760 |
| C2010 | Stair Construction | \$1.41 | S.F. | 73,000 | 100 | 1906 | 2006 | 2052 | 37.00 % | 0.00 % | 37 | | | \$102,930 |
| C3010230 | Paint & Covering | \$15.05 | S.F. | 73,000 | 10 | 2012 | 2022 | | 70.00 % | 22.20 % | 7 | | \$243,859.57 | \$1,098,650 |
| C3010232 | Wall Tile | \$0.79 | S.F. | 73,000 | 30 | 2000 | 2030 | | 50.00 % | 0.00 % | 15 | | | \$57,670 |
| C3020412 | Terrazzo & Tile | \$75.52 | S.F. | 1,460 | 50 | 2000 | 2050 | | 70.00 % | 0.00 % | 35 | | | \$110,259 |

Site Assessment Report - B263001;Sharswood

| System Code | System Description | Unit Price \$ | UoM | Qty | Life | Year Installed | Calc Next Renewal Year | Next Renewal Year | RSLI% | FCI% | RSL | eCR | Deficiency \$ | Replacement Value \$ |
|--------------|---------------------------------|---------------|------|--------|------|----------------|------------------------|-------------------|----------------|----------------|-----|-----|-----------------------|----------------------|
| C3020413 | Vinyl Flooring | \$9.68 | S.F. | 14,600 | 20 | 2000 | 2020 | | 25.00 % | 0.00 % | 5 | | | \$141,328 |
| C3020414 | Wood Flooring | \$22.27 | S.F. | 21,900 | 25 | 2000 | 2025 | | 40.00 % | 0.00 % | 10 | | | \$487,713 |
| C3020415 | Concrete Floor Finishes | \$0.97 | S.F. | 35,040 | 50 | 2000 | 2050 | | 70.00 % | 0.00 % | 35 | | | \$33,989 |
| C3030 | Ceiling Finishes | \$20.97 | S.F. | 73,000 | 25 | 2000 | 2025 | | 40.00 % | 5.71 % | 10 | | \$87,363.26 | \$1,530,810 |
| D1010 | Elevators and Lifts | \$3.56 | S.F. | 73,000 | 35 | | | | 0.00 % | 257.94 % | | | \$670,322.07 | \$259,880 |
| D2010 | Plumbing Fixtures | \$13.52 | S.F. | 73,000 | 35 | 1994 | 2029 | 2025 | 28.57 % | 6.14 % | 10 | | \$60,633.52 | \$986,960 |
| D2020 | Domestic Water Distribution | \$1.68 | S.F. | 73,000 | 25 | 1906 | 1931 | 2025 | 40.00 % | 0.00 % | 10 | | | \$122,640 |
| D2030 | Sanitary Waste | \$2.90 | S.F. | 73,000 | 25 | 1906 | 1931 | 2027 | 48.00 % | 169.16 % | 12 | | \$358,119.73 | \$211,700 |
| D2040 | Rain Water Drainage | \$2.32 | S.F. | 73,000 | 30 | 1906 | 1936 | 2027 | 40.00 % | 0.00 % | 12 | | | \$169,360 |
| D3020 | Heat Generating Systems | \$18.67 | S.F. | 73,000 | 35 | 1991 | 2026 | | 31.43 % | 0.00 % | 11 | | | \$1,362,910 |
| D3030 | Cooling Generating Systems | \$24.48 | S.F. | 73,000 | 30 | 1906 | 1936 | 2047 | 106.67 % | 40.44 % | 32 | | \$722,672.71 | \$1,787,040 |
| D3040 | Distribution Systems | \$42.99 | S.F. | 73,000 | 25 | 1906 | 1931 | 2042 | 108.00 % | 22.82 % | 27 | | \$716,264.14 | \$3,138,270 |
| D3050 | Terminal & Package Units | \$11.60 | S.F. | 73,000 | 20 | 1906 | 1926 | 2025 | 50.00 % | 0.00 % | 10 | | | \$846,800 |
| D3060 | Controls & Instrumentation | \$13.50 | S.F. | 73,000 | 20 | 1960 | 1980 | 2037 | 110.00 % | 132.68 % | 22 | | \$1,307,532.64 | \$985,500 |
| D4010 | Sprinklers | \$7.05 | S.F. | 73,000 | 35 | | | 2052 | 105.71 % | 202.91 % | 37 | | \$1,044,299.01 | \$514,650 |
| D4020 | Standpipes | \$1.01 | S.F. | 73,000 | 35 | | | | 0.00 % | 0.00 % | | | | \$73,730 |
| D5010 | Electrical Service/Distribution | \$9.70 | S.F. | 73,000 | 30 | 1906 | 1936 | 2047 | 106.67 % | 122.30 % | 32 | | \$865,981.29 | \$708,100 |
| D5020 | Lighting and Branch Wiring | \$34.68 | S.F. | 73,000 | 20 | 1906 | 1926 | 2037 | 110.00 % | 26.67 % | 22 | | \$675,295.89 | \$2,531,640 |
| D5030 | Communications and Security | \$12.99 | S.F. | 73,000 | 15 | 1906 | 1921 | 2032 | 113.33 % | 34.60 % | 17 | | \$328,123.29 | \$948,270 |
| D5090 | Other Electrical Systems | \$1.41 | S.F. | 73,000 | 30 | 1906 | 1936 | 2047 | 106.67 % | 206.92 % | 32 | | \$212,981.96 | \$102,930 |
| E1020 | Institutional Equipment | \$4.82 | S.F. | 73,000 | 35 | 1990 | 2025 | | 28.57 % | 25.81 % | 10 | | \$90,802.49 | \$351,860 |
| E1090 | Other Equipment | \$11.10 | S.F. | 73,000 | 35 | 2000 | 2035 | | 57.14 % | 0.00 % | 20 | | | \$810,300 |
| E2010 | Fixed Furnishings | \$2.13 | S.F. | 73,000 | 40 | 1980 | 2020 | | 12.50 % | 0.00 % | 5 | | | \$155,490 |
| Total | | | | | | | | | 61.27 % | 26.97 % | | | \$9,776,522.61 | \$36,249,119 |

System Notes

The facility description in the site executive summary contains an overview of each system. The notes listed below provide additional information on select systems found within the facility.

System: C3010 - Wall Finishes This system contains no images

Note: 95% - Paint & Coverings
5% - Wall Tile (3% glazed brick, 2% ceramic tile)

System: C3020 - Floor Finishes This system contains no images

Note: 2% - Terrazzo & tile (ceramic tile)
20% - Vinyl Flooring
30% - Wood Flooring
48% - Concrete Floor Finishes

System: D5010 - Electrical Service/Distribution



Note:

Renewal Schedule

eCOMET forecasts future Capital Renewal funding needed to address expiring systems based on the Next Renewal year found in the Cost Models. A 3% annual inflation factor is applied to the costs for systems expiring in future years. The table below reflects recommended Capital Renewal funding needs over the next 10 years. Note: Cells with a zero value indicate systems for which renewal is not scheduled in that year.

Inflation Rate: 3%

| System | Current Deficiencies | 2016 | 2017 | 2018 | 2019 | 2020 | 2021 | 2022 | 2023 | 2024 | 2025 | Total |
|-------------------------------------|----------------------|------------|------------|------------|------------|------------------|------------|--------------------|------------|------------|--------------------|---------------------|
| Total: | \$9,776,523 | \$0 | \$0 | \$0 | \$0 | \$705,248 | \$0 | \$1,486,321 | \$0 | \$0 | \$6,552,796 | \$18,520,888 |
| * A - Substructure | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| A10 - Foundations | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| A1010 - Standard Foundations | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| A1030 - Slab on Grade | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| A20 - Basement Construction | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| A2010 - Basement Excavation | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| A2020 - Basement Walls | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| B - Shell | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| B10 - Superstructure | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| B1010 - Floor Construction | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| B1020 - Roof Construction | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| B20 - Exterior Enclosure | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| B2010 - Exterior Walls | \$9,687 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$9,687 |
| B2020 - Exterior Windows | \$1,513,843 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$1,513,843 |
| B2030 - Exterior Doors | \$6,987 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$156,479 | \$163,466 |
| B30 - Roofing | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| B3010 - Roof Coverings | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| B3010105 - Built-Up | \$806,358 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$806,358 |
| B3020 - Roof Openings | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| C - Interiors | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| C10 - Interior Construction | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| C1010 - Partitions | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| C1020 - Interior Doors | \$33,394 | \$0 | \$0 | \$0 | \$0 | \$326,745 | \$0 | \$0 | \$0 | \$0 | \$0 | \$360,139 |
| C1030 - Fittings | \$22,002 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$22,002 |
| C20 - Stairs | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |

Site Assessment Report - B263001;Sharswood

| | | | | | | | | | | | | | |
|---|-------------|-----|-----|-----|-----|-----------|-----|-----|-------------|-----|-----|-------------|-------------|
| C2010 - Stair Construction | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| C30 - Interior Finishes | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| C3010 - Wall Finishes | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| C3010230 - Paint & Covering | \$243,860 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$1,486,321 | \$0 | \$0 | \$0 | \$1,730,181 |
| C3010232 - Wall Tile | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| C3020 - Floor Finishes | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| C3020412 - Terrazzo & Tile | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| C3020413 - Vinyl Flooring | \$0 | \$0 | \$0 | \$0 | \$0 | \$180,222 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$180,222 |
| C3020414 - Wood Flooring | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$720,990 | \$720,990 |
| C3020415 - Concrete Floor Finishes | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| C3030 - Ceiling Finishes | \$87,363 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$2,263,009 | \$2,350,372 |
| D - Services | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| D10 - Conveying | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| D1010 - Elevators and Lifts | \$670,322 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$670,322 |
| D20 - Plumbing | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| D2010 - Plumbing Fixtures | \$60,634 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$1,459,031 | \$1,519,664 |
| D2020 - Domestic Water Distribution | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$181,300 | \$181,300 |
| D2030 - Sanitary Waste | \$358,120 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$358,120 |
| D2040 - Rain Water Drainage | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| D30 - HVAC | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| D3020 - Heat Generating Systems | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| D3030 - Cooling Generating Systems | \$722,673 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$722,673 |
| D3040 - Distribution Systems | \$716,264 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$716,264 |
| D3050 - Terminal & Package Units | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$1,251,831 | \$1,251,831 |
| D3060 - Controls & Instrumentation | \$1,307,533 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$1,307,533 |
| D40 - Fire Protection | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| D4010 - Sprinklers | \$1,044,299 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$1,044,299 |
| D4020 - Standpipes | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| D50 - Electrical | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| D5010 - Electrical Service/Distribution | \$865,981 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$865,981 |
| D5020 - Lighting and Branch Wiring | \$675,296 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$675,296 |
| D5030 - Communications and Security | \$328,123 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$328,123 |
| D5090 - Other Electrical Systems | \$212,982 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$212,982 |


Site Assessment Report - B263001;Sharswood

| | | | | | | | | | | | | | |
|--|----------|-----|-----|-----|-----|-----------|-----|-----|-----|-----|-----|-----------|------------------|
| E - Equipment & Furnishings | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| E10 - Equipment | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| E1020 - Institutional Equipment | \$90,802 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$520,157 | \$610,960 |
| E1090 - Other Equipment | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| E20 - Furnishings | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| E2010 - Fixed Furnishings | \$0 | \$0 | \$0 | \$0 | \$0 | \$198,281 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$198,281 |

* Indicates non-renewable system

Forecasted Sustainment Requirement

The following chart shows the current building deficiencies and forecasting sustainment requirements over the next ten years.




10 Year FCI Forecast by Investment Scenario

The chart below illustrates the effect of various investment levels on the building FCI for the next 10 years. The levels of investment shown below include:

- Current FCI: a variable investment amount based on renewing expired systems to maintain the current FCI for the building
- 2% Investment: an annual investment of 2% of the replacement value of the building, escalated for inflation
- 4% Investment: an annual investment of 4% of the replacement value of the building, escalated for inflation


Facility Investment vs. FCI Forecast



| Year | Investment Amount Current FCI - 26.97% | 2% Investment | | 4% Investment | |
|---------------|---|-----------------------|---------|------------------------|---------|
| | | Amount | FCI | Amount | FCI |
| 2016 | \$0 | \$746,732.00 | 24.97 % | \$1,493,464.00 | 22.97 % |
| 2017 | \$13,559,759 | \$769,134.00 | 58.23 % | \$1,538,268.00 | 54.23 % |
| 2018 | \$0 | \$792,208.00 | 56.23 % | \$1,584,416.00 | 50.23 % |
| 2019 | \$0 | \$815,974.00 | 54.23 % | \$1,631,948.00 | 46.23 % |
| 2020 | \$705,248 | \$840,453.00 | 53.91 % | \$1,680,907.00 | 43.91 % |
| 2021 | \$0 | \$865,667.00 | 51.91 % | \$1,731,334.00 | 39.91 % |
| 2022 | \$1,486,321 | \$891,637.00 | 53.24 % | \$1,783,274.00 | 39.24 % |
| 2023 | \$0 | \$918,386.00 | 51.24 % | \$1,836,772.00 | 35.24 % |
| 2024 | \$0 | \$945,938.00 | 49.24 % | \$1,891,875.00 | 31.24 % |
| 2025 | \$6,552,796 | \$974,316.00 | 60.69 % | \$1,948,631.00 | 40.69 % |
| Total: | \$22,304,124 | \$8,560,445.00 | | \$17,120,889.00 | |

Deficiency Summary by System


Current deficiencies included assemblies that have reached or exceeded their design life or components of the assemblies that are in need of repair. Assemblies that have reached their design life are identified as current deficiencies and assigned the distress 'Beyond Useful Life'. The following chart lists all current deficiencies associated with this facility.



Budget Estimate Total: \$9,776,522.61

Deficiency Summary by Priority

The following chart shows the total repair costs broken down by priority. Assessors assigned deficiencies within eCOMET to one of the following priority categories:



Budget Estimate Total: \$9,776,522.61


Deficiency By Priority Investment Table

The table below shows the current investment cost grouped by deficiency priority and building system.

| System Code | System Description | 1 - Response Time (< 2 yr) | 2 - Response Time (2-3 yrs) | 3 - Response Time (3-4 yrs) | 4 - Response Time (4-5 yrs) | 5 - Response Time (> 5 yrs) | Total |
|-------------|---------------------------------|----------------------------|-----------------------------|-----------------------------|-----------------------------|-----------------------------|----------------|
| B2010 | Exterior Walls | \$0.00 | \$9,686.84 | \$0.00 | \$0.00 | \$0.00 | \$9,686.84 |
| B2020 | Exterior Windows | \$0.00 | \$0.00 | \$1,513,843.23 | \$0.00 | \$0.00 | \$1,513,843.23 |
| B2030 | Exterior Doors | \$0.00 | \$6,987.28 | \$0.00 | \$0.00 | \$0.00 | \$6,987.28 |
| B3010105 | Built-Up | \$806,357.98 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$806,357.98 |
| C1020 | Interior Doors | \$0.00 | \$0.00 | \$33,394.17 | \$0.00 | \$0.00 | \$33,394.17 |
| C1030 | Fittings | \$0.00 | \$9,778.55 | \$12,222.99 | \$0.00 | \$0.00 | \$22,001.54 |
| C3010230 | Paint & Covering | \$0.00 | \$0.00 | \$0.00 | \$243,859.57 | \$0.00 | \$243,859.57 |
| C3030 | Ceiling Finishes | \$0.00 | \$0.00 | \$87,363.26 | \$0.00 | \$0.00 | \$87,363.26 |
| D1010 | Elevators and Lifts | \$0.00 | \$670,322.07 | \$0.00 | \$0.00 | \$0.00 | \$670,322.07 |
| D2010 | Plumbing Fixtures | \$0.00 | \$0.00 | \$0.00 | \$60,633.52 | \$0.00 | \$60,633.52 |
| D2030 | Sanitary Waste | \$0.00 | \$0.00 | \$358,119.73 | \$0.00 | \$0.00 | \$358,119.73 |
| D3030 | Cooling Generating Systems | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$722,672.71 | \$722,672.71 |
| D3040 | Distribution Systems | \$0.00 | \$0.00 | \$716,264.14 | \$0.00 | \$0.00 | \$716,264.14 |
| D3060 | Controls & Instrumentation | \$0.00 | \$0.00 | \$0.00 | \$1,307,532.64 | \$0.00 | \$1,307,532.64 |
| D4010 | Sprinklers | \$0.00 | \$0.00 | \$0.00 | \$1,044,299.01 | \$0.00 | \$1,044,299.01 |
| D5010 | Electrical Service/Distribution | \$0.00 | \$865,981.29 | \$0.00 | \$0.00 | \$0.00 | \$865,981.29 |
| D5020 | Lighting and Branch Wiring | \$0.00 | \$675,295.89 | \$0.00 | \$0.00 | \$0.00 | \$675,295.89 |
| D5030 | Communications and Security | \$0.00 | \$328,123.29 | \$0.00 | \$0.00 | \$0.00 | \$328,123.29 |
| D5090 | Other Electrical Systems | \$0.00 | \$212,981.96 | \$0.00 | \$0.00 | \$0.00 | \$212,981.96 |
| E1020 | Institutional Equipment | \$0.00 | \$90,802.49 | \$0.00 | \$0.00 | \$0.00 | \$90,802.49 |
| | Total: | \$806,357.98 | \$2,869,959.66 | \$2,721,207.52 | \$2,656,324.74 | \$722,672.71 | \$9,776,522.61 |

Deficiency Summary by Category

The following chart shows the total repair costs broken down by deficiency categories. Assessors assigned deficiencies to one of the following categories:



Deficiency Details by Priority

The deficiency detail notes listed below provide additional information on identified deficiencies found within the facility.

Priority 1 - Response Time (< 2 yr):

System: B3010105 - Built-Up



Location: Roof

Distress: Beyond Service Life

Category: 3 - Operations / Maint.

Priority: 1 - Response Time (< 2 yr)

Correction: Remove and Replace Built Up Roof

Qty: 23,799.00

Unit of Measure: S.F.

Estimate: \$806,357.98

Assessor Name: System

Date Created: 09/01/2015

Notes: Replace built-up roofing system – leaking, failing, and beyond service life

Priority 2 - Response Time (2-3 yrs):

System: B2010 - Exterior Walls



Location: Parapit wall

Distress: Damaged

Category: 3 - Operations / Maint.

Priority: 2 - Response Time (2-3 yrs)

Correction: Repair cracks in masonry - replace missing mortar and repoint - SF of wall area

Qty: 300.00

Unit of Measure: S.F.

Estimate: \$9,686.84

Assessor Name: System

Date Created: 09/01/2015

Notes: Repair and re-point parapet walls

System: B2030 - Exterior Doors



Location: Ext. Entrance

Distress: Accessibility

Category: 2 - Code Compliance

Priority: 2 - Response Time (2-3 yrs)

Correction: Replace hardware with compliant hardware, paint and weatherstrip - per leaf

Qty: 2.00

Unit of Measure: Ea.

Estimate: \$6,987.28

Assessor Name: System

Date Created: 09/01/2015

Notes: Provide ADA compliant exterior door hardware at one entrance

System: C1030 - Fittings



Location: Toiles

Distress: Accessibility

Category: 2 - Code Compliance

Priority: 2 - Response Time (2-3 yrs)

Correction: Remove and replace damaged toilet paritions - handicap units

Qty: 10.00

Unit of Measure: Ea.

Estimate: \$9,778.55

Assessor Name: System

Date Created: 09/01/2015

Notes: Provide new toilet partitions and toilet accessories including grab bars for accessibility

System: D1010 - Elevators and Lifts



Location: B263001;Sharswood

Distress: Accessibility

Category: 2 - Code Compliance

Priority: 2 - Response Time (2-3 yrs)

Correction: Add interior elevator - 4 floors - adjust the electrical run lengths to hook up the elevator

Qty: 1.00

Unit of Measure: Ea.

Estimate: \$670,322.07

Assessor Name: System

Date Created: 09/01/2015

Notes: Install elevator for accessibility (location TBD)

System: D5010 - Electrical Service/Distribution



Location: Corridors
Distress: Beyond Service Life
Category: 3 - Operations / Maint.
Priority: 2 - Response Time (2-3 yrs)
Correction: Add Panelboard
Qty: 15.00
Unit of Measure: Ea.
Estimate: \$451,856.62
Assessor Name: System
Date Created: 08/12/2015

Notes: Replace the entire distribution system with new panels and new wiring/conduits. Approximate (15) 208/120V

System: D5010 - Electrical Service/Distribution



Location: Fan room
Distress: Inadequate
Category: 4 - Capital Improvement
Priority: 2 - Response Time (2-3 yrs)
Correction: Replace Switchboard
Qty: 1.00
Unit of Measure: Ea.
Estimate: \$414,124.67
Assessor Name: System
Date Created: 08/12/2015

Notes: The new service will be 480V/277V, 3 phase power, approximate 1000 Amperes and will be located in the vicinity of the existing electrical service.

System: D5020 - Lighting and Branch Wiring



Location: Entire school
Distress: Energy Efficiency
Category: 4 - Capital Improvement
Priority: 2 - Response Time (2-3 yrs)
Correction: Add Lighting Fixtures
Qty: 869.00
Unit of Measure: Ea.
Estimate: \$516,591.62
Assessor Name: System
Date Created: 08/12/2015

Notes: Approximate 90% of the lighting fixtures are provided with T-12 lamps. Provide lighting fixtures with T-8 lamps. Approximate 869 fixtures.

System: D5020 - Lighting and Branch Wiring



Location: Classrooms
Distress: Inadequate
Category: 4 - Capital Improvement
Priority: 2 - Response Time (2-3 yrs)
Correction: Add wiring device
Qty: 432.00
Unit of Measure: Ea.
Estimate: \$158,704.27
Assessor Name: System
Date Created: 08/12/2015

Notes: Provide (2)25FT of surface raceways with 24" receptacles on center and two-duplex wall mount receptacles. Approximate 27 classrooms

System: D5030 - Communications and Security



Location: Entire school
Distress: Life Safety / NFPA / PFD
Category: 1 - Health & Safety
Priority: 2 - Response Time (2-3 yrs)
Correction: Add fire alarm device
Qty: 100.00
Unit of Measure: Ea.
Estimate: \$187,360.25
Assessor Name: System
Date Created: 08/12/2015

Notes: Replace old fire alarm system with addressable type with audio/visual devices in the entire school. Approximate 100 devices

System: D5030 - Communications and Security



Location: Classrooms
Distress: Beyond Service Life
Category: 3 - Operations / Maint.
Priority: 2 - Response Time (2-3 yrs)
Correction: Add/Replace Clock System or Components
Qty: 55.00
Unit of Measure: Ea.
Estimate: \$112,560.22
Assessor Name: System
Date Created: 08/12/2015

Notes: Provide a new clock system, wireless battery operated. Approximate 55 clocks

System: D5030 - Communications and Security



Location: Auditorium
Distress: Inadequate
Category: 4 - Capital Improvement
Priority: 2 - Response Time (2-3 yrs)
Correction: Add/Replace Sound System
Qty: 1.00

Unit of Measure: LS
Estimate: \$28,202.82
Assessor Name: System
Date Created: 08/12/2015

Notes: Provide a more complete sound system

System: D5090 - Other Electrical Systems



Location: Outdoor
Distress: Beyond Service Life
Category: 3 - Operations / Maint.
Priority: 2 - Response Time (2-3 yrs)
Correction: Add Standby Generator System
Qty: 1.00

Unit of Measure: Ea.
Estimate: \$188,732.14
Assessor Name: System
Date Created: 08/12/2015

Notes: Provide an outdoor, diesel powered 75KW generator.

System: D5090 - Other Electrical Systems



Location: Roof
Distress: Building / MEP Codes
Category: 2 - Code Compliance
Priority: 2 - Response Time (2-3 yrs)
Correction: Repair Lightning Protection System
Qty: 1.00
Unit of Measure: Job
Estimate: \$24,249.82
Assessor Name: System
Date Created: 08/12/2015

Notes: Prepare a study to determine if existing lightning protection system provide the proper coverage to the school building.

System: E1020 - Institutional Equipment



Location: Auditorium
Distress: Inadequate
Category: 4 - Capital Improvement
Priority: 2 - Response Time (2-3 yrs)
Correction: Add/Replace Stage Theatrical Lighting System
Qty: 1.00
Unit of Measure: Ea.
Estimate: \$90,802.49
Assessor Name: System
Date Created: 08/12/2015

Notes: The auditorium is not provided with theatrical lighting nor dimming control system. Provide theatrical lighting and dimming control system

Priority 3 - Response Time (3-4 yrs):

System: B2020 - Exterior Windows



Location: Throughout

Distress: Energy Efficiency

Category: 4 - Capital Improvement

Priority: 3 - Response Time (3-4 yrs)

Correction: Remove and replace double slider windows

Qty: 300.00

Unit of Measure: Ea.

Estimate: \$1,513,843.23

Assessor Name: System

Date Created: 09/01/2015

Notes: Replace Plexiglas windows – hazed

System: C1020 - Interior Doors



Location: Int. doors

Distress: Accessibility

Category: 2 - Code Compliance

Priority: 3 - Response Time (3-4 yrs)

Correction: Replace door knobs with compliant lever type

Qty: 60.00

Unit of Measure: Ea.

Estimate: \$33,394.17

Assessor Name: System

Date Created: 09/01/2015

Notes: Provide ADA lever handle lock/latchsets on interior doors

System: C1030 - Fittings



Location: Throughout
Distress: Inadequate
Category: 4 - Capital Improvement
Priority: 3 - Response Time (3-4 yrs)
Correction: Replace missing or damaged signage - insert the number of rooms
Qty: 80.00
Unit of Measure: Ea.
Estimate: \$12,222.99
Assessor Name: System
Date Created: 09/01/2015

Notes: Install new ID signage

System: C3030 - Ceiling Finishes



Location: Basement
Distress: Appearance
Category: 3 - Operations / Maint.
Priority: 3 - Response Time (3-4 yrs)
Correction: Re-paint ceilings - SF of ceilings
Qty: 18,250.00
Unit of Measure: S.F.
Estimate: \$87,363.26
Assessor Name: System
Date Created: 09/01/2015

Notes: Repaint ceilings in basement

System: D2030 - Sanitary Waste



Location: Entire building

Distress: Beyond Service Life

Category: 3 - Operations / Maint.

Priority: 3 - Response Time (3-4 yrs)

Correction: Inspect sanitary waste piping and replace damaged sections. (+50KSF)

Qty: 73,000.00

Unit of Measure: S.F.

Estimate: \$358,119.73

Assessor Name: System

Date Created: 09/08/2015

Notes: Inspect drainage pipes and repair as needed.

System: D3040 - Distribution Systems



Location: Mechanical rooms

Distress: Obsolete

Category: 3 - Operations / Maint.

Priority: 3 - Response Time (3-4 yrs)

Correction: Install / replace HVAC unit for Auditorium (800 seat).

Qty: 800.00

Unit of Measure: Seat

Estimate: \$716,264.14

Assessor Name: System

Date Created: 09/08/2015

Notes: Replace obsolete air handlers and radiators with modern equipment including cooling coils and digital controls and renovate ductwork to supply fresh air to classrooms.

Priority 4 - Response Time (4-5 yrs):

System: C3010230 - Paint & Covering



Location: Basement, fire tower

Distress: Appearance

Category: 3 - Operations / Maint.

Priority: 4 - Response Time (4-5 yrs)

Correction: Repair and repaint all interior walls - SF of wall surface

Qty: 36,000.00

Unit of Measure: S.F.

Estimate: \$243,859.57

Assessor Name: System

Date Created: 09/01/2015

Notes: Repaint interior walls in basement fire towers

System: D2010 - Plumbing Fixtures



Location: Entire building

Distress: Accessibility

Category: 2 - Code Compliance

Priority: 4 - Response Time (4-5 yrs)

Correction: Remove and Replace Water Fountains - without ADA new recessed alcove

Qty: 8.00

Unit of Measure: Ea.

Estimate: \$60,633.52

Assessor Name: System

Date Created: 09/08/2015

Notes: Replace aged, non-accessible drinking fountains.

System: D3060 - Controls & Instrumentation



Location: Entire building
Distress: Obsolete
Category: 3 - Operations / Maint.
Priority: 4 - Response Time (4-5 yrs)
Correction: Replace pneumatic controls with DDC (150KSF)
Qty: 73,000.00
Unit of Measure: S.F.
Estimate: \$1,307,532.64
Assessor Name: System
Date Created: 09/08/2015

Notes: Upgrade obsolete pneumatic control system to digital.

System: D4010 - Sprinklers



Location: Entire building
Distress: Life Safety / NFPA / PFD
Category: 1 - Health & Safety
Priority: 4 - Response Time (4-5 yrs)
Correction: Install a fire protection sprinkler system
Qty: 73,000.00
Unit of Measure: S.F.
Estimate: \$1,044,299.01
Assessor Name: System
Date Created: 09/08/2015

Notes: Install fire sprinkler system including fire pump if needed.

Priority 5 - Response Time (> 5 yrs):

System: D3030 - Cooling Generating Systems



Location: Entire building

Distress: Inadequate

Category: 4 - Capital Improvement

Priority: 5 - Response Time (> 5 yrs)

Correction: Install chilled water system with distribution piping and pumps. (+75KSF)

Qty: 45,000.00

Unit of Measure: S.F.

Estimate: \$722,672.71

Assessor Name: System

Date Created: 09/08/2015

Notes: Install 150 ton central cooling system for entire building.

Equipment Inventory

The following table represents the inventory details of the inventory found in the building, which fall under the following subsystems:

| Subsystem | Inventory | Qty | UoM | Location | Manufacturer | Model Number | Serial Number | Barcode | Life | Install Date | Next Renewal | Raw Cost | Inventory Cost |
|--------------------------------|--|-------|-----|------------------|--------------|--------------|---------------|---------|------|--------------|--------------|---------------|---------------------|
| D3020 Heat Generating Systems | Boiler, gas/oil combination, cast iron, steam, gross output, 3270 MBH, includes burners, controls and insulated jacket, packaged | 2.00 | Ea. | Boile room | | | | | 35 | 1991 | 2026 | \$58,084.00 | \$127,784.80 |
| D3040 Distribution Systems | Air-handling unit, built-up, horizontal/vertical, constant volume, single zone, 27,000 CFM, with cooling/heating coil section, filters, mixing box | 3.00 | Ea. | Mechanical rooms | | | | | 25 | 1925 | 2042 | \$70,587.00 | \$232,937.10 |
| D3050 Terminal & Package Units | Hydronic heating, convector, multifin, with cabinet, 2 pipe, 21" H x 48" L, excludes main supply pipe | 36.00 | Ea. | Basement | | | | | 20 | 1945 | 1965 | \$419.43 | \$16,609.43 |
| | | | | | | | | | | | | Total: | \$377,331.33 |

Executive Summary

Building condition is evaluated based on the functional systems and elements of a building and organized according to the UNIFORMAT II Elemental Classification. The grouping of these systems and elements and applying a current replacement value to them develops a representative building cost model. Cost Models are developed for similar building types and functions. Systems and their elements are evaluated based on their current replacement values, life cycles, installation dates and next renewal dates. Systems and their elements that are within their useful lives are further evaluated to identify current deficient conditions that may have a significant impact on a system's or element's remaining service life, and to determine if they are beyond their predicted expected life. The system's or element's current replacement value is based on RS Means Commercial Cost Data.

Following are the cost model's system details for this facility. The Replacement Value is the amount needed to replace the property of the same present value. The Current Repair Amount, also known as Condition Needs, represents the budgeted contractor installed costs plus owner's soft costs for the repair, replacement or renewal for a component or system level deficiency. It excludes contributing costs for other components or systems that might also be associated with the corrective actions due to packaging the work. Facility Condition Index (FCI) FCI is an industry-standard measurement of facility condition calculated as the ratio of the costs to correct a facility's deficiencies to the facility's Current Replacement Value. It ranges from 0% (new) to 100% (very poor). Condition Index (CI) is calculated as the sum of a renewable system's Remaining Service Life (RSL) divided by the sum of a system's Replacement Value (both values exclude soft-cost to simplify calculation updates) expressed as a percentage ranging from 100% (new) to 0% (expired).

| | |
|--------------------|--------------|
| Function: | |
| Gross Area (SF): | 57,500 |
| Year Built: | 1906 |
| Last Renovation: | |
| Replacement Value: | \$1,261,625 |
| Repair Cost: | \$254,660.42 |
| Total FCI: | 20.19 % |
| Total RSLI: | 36.83 % |



Description:

Attributes:

General Attributes:

| | | | |
|----------|---------|----------|---------|
| Bldg ID: | S263001 | Site ID: | S263001 |
|----------|---------|----------|---------|

Condition Summary

The Table below shows the CI and FCI for each major building system shown at the UNIFORMAT classification Level II. Note that Systems with lower FCIs require less investment than systems with higher FCIs.

| UNIFORMAT Classification | RSLI % | FCI % | Current Repair Cost |
|---------------------------------|----------------|----------------|---------------------|
| G20 - Site Improvements | 50.10 % | 6.38 % | \$59,181.86 |
| G40 - Site Electrical Utilities | 0.00 % | 58.51 % | \$195,478.56 |
| Totals: | 36.83 % | 20.19 % | \$254,660.42 |

Condition Detail

This section of the report contains results of the Facility Condition Assessment. The building is separated into system components based on UNIFORMAT II classification. The columns in the System Listing table below represent the following:

1. System Code: A code that identifies the system.
2. System Description: A brief description of a system present in the building.
3. Unit Price \$: The unit price of the system.
4. UoM: The unit of measure for of the system.
5. Qty: The quantity for the system
6. Life: anticipated service life for thesystem based on Building Owners and Managers Association (BOMA) recommendations.
7. Year Installed: The date of system installation.
8. Calc Next Renewal Year: The date of system expiration based on the life, NR stands for non renewable.
9. Next Renewal Year: The suggested system expiration date by the assessor based on visual inspection.
10. CI: The Condition Index of the system.
11. FCI: The Facility Condition Index of the system.
12. RSL: Remaining Service Life.
13. eCR: eCOMET Condition Rating (not used).
14. Deficiency \$: The financial investment to repair/replace system.

System Listing

The System Listing table below lists each of the systems organized by their UNIFORMAT II classification. The assessment team was tasked with recording the most recent replacement year of each system, determining the remaining service life based on the theoretical life, and evaluating the condition to confirm the forecast next replacement year. The system listing is the basis for all data contained in the Building Assessment Report.

Additionally, a condition rating (eCR) based on the following guidelines is provided as observed at the time of the assessment.

- Excellent (E) - No noticeable distress or damage. The entire system is free from observable defect.
- Very Good (VG) - Overall no serviceability reduction for the entire system. No degradation of critical components and minor distress and defect noticeable for some but not non critical components within the system.
- Good (G) - Slight or no serviceability reduction for the entire system. There may be noticeable defects for some non critical components and slight noticeable degradation of the critical components.
- Fair (F) - Overall serviceability is degraded but adequate. There may be moderate deterioration for very few of the critical components and few of the non critical components may have severe degradation.
- Marginal (MA) - Overall serviceability and reliability loss. Most if not all of the non critical components suffer from severe degradation and a few of the critical component may have severe degradation.
- Moderate (MO) - Overall a significant serviceability loss. Most if not all the components have severe degradation with the reminder of the component showing visible distress.
- Very Poor (VP) - Overall the system is barely functional. All of the components are severely degraded.
- Non-Functional (NF) - Overall the system does not function with all the components having no serviceability and suffer from severe degradation.

| System Code | System Description | Unit Price \$ | UoM | Qty | Life | Year Installed | Calc Next Renewal Year | Next Renewal Year | RSLI% | FCI% | RSL | eCR | Deficiency \$ | Replacement Value \$ |
|--------------|--------------------------------|---------------|------|--------|------|----------------|------------------------|-------------------|----------------|----------------|-----|-----|---------------------|----------------------|
| G2020 | Parking Lots | \$8.50 | S.F. | 8,000 | 30 | 2000 | 2030 | | 50.00 % | 0.00 % | 15 | | | \$68,000 |
| G2030 | Pedestrian Paving | \$12.30 | S.F. | 49,500 | 40 | 2000 | 2040 | | 62.50 % | 9.72 % | 25 | | \$59,181.86 | \$608,850 |
| G2040 | Site Development | \$4.36 | S.F. | 57,500 | 25 | 1995 | 2020 | | 20.00 % | 0.00 % | 5 | | | \$250,700 |
| G4020 | Site Lighting | \$4.84 | S.F. | 57,500 | 30 | | | | 0.00 % | 42.65 % | | | \$118,697.96 | \$278,300 |
| G4030 | Site Communications & Security | \$0.97 | S.F. | 57,500 | 30 | | | | 0.00 % | 137.66 % | | | \$76,780.60 | \$55,775 |
| Total | | | | | | | | | 36.83 % | 20.19 % | | | \$254,660.42 | \$1,261,625 |

System Notes

The facility description in the site executive summary contains an overview of each system. The notes listed below provide additional information on select systems found within the facility.

No data found for this asset

Renewal Schedule

eCOMET forecasts future Capital Renewal funding needed to address expiring systems based on the Next Renewal year found in the Cost Models. A 3% annual inflation factor is applied to the costs for systems expiring in future years. The table below reflects recommended Capital Renewal funding needs over the next 10 years. Note: Cells with a zero value indicate systems for which renewal is not scheduled in that year.


Inflation Rate: 3%

| System | Current Deficiencies | 2016 | 2017 | 2018 | 2019 | 2020 | 2021 | 2022 | 2023 | 2024 | 2025 | Total |
|--|----------------------|------|------|------|------|-----------|------|------|------|------|------|-----------|
| Total: | \$254,660 | \$0 | \$0 | \$0 | \$0 | \$319,693 | \$0 | \$0 | \$0 | \$0 | \$0 | \$574,353 |
| G - Building Sitework | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| G20 - Site Improvements | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| G2020 - Parking Lots | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| G2030 - Pedestrian Paving | \$59,182 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$59,182 |
| G2040 - Site Development | \$0 | \$0 | \$0 | \$0 | \$0 | \$319,693 | \$0 | \$0 | \$0 | \$0 | \$0 | \$319,693 |
| G40 - Site Electrical Utilities | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| G4020 - Site Lighting | \$118,698 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$118,698 |
| G4030 - Site Communications & Security | \$76,781 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$76,781 |

** Indicates non-renewable system*

Forecasted Sustainment Requirement

The following chart shows the current building deficiencies and forecasting sustainment requirements over the next ten years.




10 Year FCI Forecast by Investment Scenario

The chart below illustrates the effect of various investment levels on the building FCI for the next 10 years. The levels of investment shown below include:

- Current FCI: a variable investment amount based on renewing expired systems to maintain the current FCI for the building
- 2% Investment: an annual investment of 2% of the replacement value of the building, escalated for inflation
- 4% Investment: an annual investment of 4% of the replacement value of the building, escalated for inflation


Facility Investment vs. FCI Forecast



| Year | Investment Amount Current FCI - 20.19% | 2% Investment | | 4% Investment | |
|---------------|---|---------------------|---------|---------------------|---------|
| | | Amount | FCI | Amount | FCI |
| 2016 | \$0 | \$25,989.00 | 18.19 % | \$51,979.00 | 16.19 % |
| 2017 | \$0 | \$26,769.00 | 16.19 % | \$53,538.00 | 12.19 % |
| 2018 | \$0 | \$27,572.00 | 14.19 % | \$55,144.00 | 8.19 % |
| 2019 | \$0 | \$28,399.00 | 12.19 % | \$56,799.00 | 4.19 % |
| 2020 | \$319,693 | \$29,251.00 | 32.04 % | \$58,503.00 | 22.04 % |
| 2021 | \$0 | \$30,129.00 | 30.04 % | \$60,258.00 | 18.04 % |
| 2022 | \$0 | \$31,033.00 | 28.04 % | \$62,066.00 | 14.04 % |
| 2023 | \$0 | \$31,964.00 | 26.04 % | \$63,928.00 | 10.04 % |
| 2024 | \$0 | \$32,923.00 | 24.04 % | \$65,845.00 | 6.04 % |
| 2025 | \$0 | \$33,910.00 | 22.04 % | \$67,821.00 | 2.04 % |
| Total: | \$319,693 | \$297,939.00 | | \$595,881.00 | |

Deficiency Summary by System


Current deficiencies included assemblies that have reached or exceeded their design life or components of the assemblies that are in need of repair. Assemblies that have reached their design life are identified as current deficiencies and assigned the distress 'Beyond Useful Life'. The following chart lists all current deficiencies associated with this facility.



Budget Estimate Total: \$254,660.42

Deficiency Summary by Priority

The following chart shows the total repair costs broken down by priority. Assessors assigned deficiencies within eCOMET to one of the following priority categories:



Budget Estimate Total: \$254,660.42


Deficiency By Priority Investment Table

The table below shows the current investment cost grouped by deficiency priority and building system.

| System Code | System Description | 1 - Response Time (< 2 yr) | 2 - Response Time (2-3 yrs) | 3 - Response Time (3-4 yrs) | 4 - Response Time (4-5 yrs) | 5 - Response Time (> 5 yrs) | Total |
|-------------|--------------------------------|----------------------------|-----------------------------|-----------------------------|-----------------------------|-----------------------------|--------------|
| G2030 | Pedestrian Paving | \$0.00 | \$0.00 | \$59,181.86 | \$0.00 | \$0.00 | \$59,181.86 |
| G4020 | Site Lighting | \$0.00 | \$118,697.96 | \$0.00 | \$0.00 | \$0.00 | \$118,697.96 |
| G4030 | Site Communications & Security | \$0.00 | \$76,780.60 | \$0.00 | \$0.00 | \$0.00 | \$76,780.60 |
| | Total: | \$0.00 | \$195,478.56 | \$59,181.86 | \$0.00 | \$0.00 | \$254,660.42 |

Deficiency Summary by Category

The following chart shows the total repair costs broken down by deficiency categories. Assessors assigned deficiencies to one of the following categories:



Deficiency Details by Priority

The deficiency detail notes listed below provide additional information on identified deficiencies found within the facility.

Priority 2 - Response Time (2-3 yrs):

System: G4020 - Site Lighting



Location: Outdoor

Distress: Health Hazard / Risk

Category: 1 - Health & Safety

Priority: 2 - Response Time (2-3 yrs)

Correction: Add Site Lighting - pole mounted - select the proper light and pole

Qty: 6.00

Unit of Measure: Ea.

Estimate: \$118,697.96

Assessor Name: Ben Nixon

Date Created: 08/12/2015

Notes: The school perimeter is illuminated from wall mounted fixtures, as a safety issue provide 6 pole mounted lighting fixtures in the parking area and playground.

System: G4030 - Site Communications & Security



Location: Outdoor

Distress: Health Hazard / Risk

Category: 1 - Health & Safety

Priority: 2 - Response Time (2-3 yrs)

Correction: Add Video Surveillance System

Qty: 4.00

Unit of Measure: Ea.

Estimate: \$48,982.61

Assessor Name: Ben Nixon

Date Created: 08/12/2015

Notes: Provide additional CCTV cameras to provide complete coverage of the building perimeter. Approximate 4

System: G4030 - Site Communications & Security



Location: Outdoor

Distress: Inadequate

Category: 4 - Capital Improvement

Priority: 2 - Response Time (2-3 yrs)

Correction: Add Site Paging System

Qty: 4.00

Unit of Measure: Ea.

Estimate: \$27,797.99

Assessor Name: Ben Nixon

Date Created: 08/12/2015

Notes: Provide two loud speakers in front of the parking lot and playground.

Priority 3 - Response Time (3-4 yrs):

System: G2030 - Pedestrian Paving



Location: Entrance

Distress: Accessibility

Category: 2 - Code Compliance

Priority: 3 - Response Time (3-4 yrs)

Correction: Install an exterior ADA ramp - based on 5' wide by the linear foot - up to 84" rise - per LF of ramp - figure 1 LF of ramp per inch of rise

Qty: 25.00

Unit of Measure: L.F.

Estimate: \$59,181.86

Assessor Name: Ben Nixon

Date Created: 09/01/2015

Notes: Provide ADA compliant ramp at one entrance (location TBD)

Equipment Inventory

The following table represents the inventory details of the inventory found in the building, which fall under the following subsystems:

No data found for this asset

Glossary

| | |
|------------|---|
| ABMA | American Boiler Manufacturers Association http://www.abma.com/ |
| ACEEE | American Council for an Energy-Efficient Economy |
| ACGIH | American Council of Governmental and Industrial Hygienists |
| AEE | Association of Energy Engineers |
| AFD | Adjustable Frequency Drive |
| AFTC | After Tax Cash Flow |
| AGA | American Gas Association |
| AHU | Air Handling Unit |
| Amp | Ampere |
| ANSI | American National Standards Institute |
| ARI | Air Conditioning and Refrigeration Institute |
| ASD | Adjustable Speed Drive |
| ASHRAE | American Society of Heating Refrigerating and Air-Conditioning Engineers Inc. |
| ASME | American Society of Mechanical Engineers |
| Assessment | Visual survey of a facility to determine its condition. It involves looking at the age of systems reviewing information from local sources and visual evidence of potential problems to assign a condition rating. It does not include destructive testing of materials or testing of systems or equipment for functionality. |
| ATS | After Tax Savings |
| AW | Annual worth |
| BACNET | Building Automation Control Network |
| BAS | Building Automation System |
| BCR | Benefit Cost Ratio |
| BEP | Business Energy Professional (AEE) |
| BF | Ballast Factor |
| BHP | Boiler Horsepower (boilers) |
| BHP | Brake Horsepower (motors) |
| BLCC | Building Life Cycle Cost analysis program (FEMP) |
| BOCA | Building Officials and Code Administrators |
| BTCF | Before Tax Cash Flow |

Site Assessment Report - S263001;Sharswood

| | |
|-------------------------|---|
| BTS | Before Tax Savings |
| Btu | British thermal unit |
| Building Addition | An area space or component of a building added to a building after the original building's year built date. |
| CAA | Clean Air Act |
| CAAA-90 | Clean Air Act Amendments of 1990 |
| CABO | Council of American Building Officials |
| CAC | Conventional Air Conditioning |
| CADDET | Center for the Analysis and Dissemination of Demonstrated Energy Technologies |
| Calculated Next Renewal | The year a system or element would be expected to expire based solely on the date it was installed and the expected useful lifetime for that kind of system. |
| Capital Renewal | Capital renewal is condition work (excluding suitability and energy audit work) that includes the replacement of building systems or elements (as they become obsolete or beyond their useful life) not normally included in an annual operating budget. Calculated next renewal The year a system or element would be expected to expire based solely on the date it was installed and the expected useful lifetime for that kind of system. Next renewal The assessor adjusted expected useful life of a system or element based on on-site inspection. |
| CDD | Cooling Degree Days |
| CDGP | Certified Distributed Generation Professional |
| CEC | California Energy Commission |
| CEM | Certified Energy Manager |
| CEP | Certified Energy Procurement Professional |
| CFC | Chlorofluorocarbon |
| CFD | Cash Flow Diagram |
| CFL | Compact Fluorescent Light |
| CFM cfm | Cubic Feet per Minute |
| CHP | Combined Heat and Power (a.k.a. cogeneration) |
| CHW | Chilled Water |
| Condition | Condition refers to the state of physical fitness or readiness of a facility system or system element for its intended use. |
| COP | Coefficient of Performance |
| Cp | Heat Capacity of Material |
| CPUC | California Public Utility Commission |
| CRI | Color Rendering Index |
| CRT | Cathode Ray Tube VDT HMI |

Site Assessment Report - S263001;Sharswood

| | |
|---------------------------------|---|
| CTC | Competitive Transition Charge |
| Cu | Coefficient of Utilization |
| Current Replacement Value (CRV) | CRV represents the hypothetical total cost of rebuilding or replacing an existing facility in current dollars to its optimal condition (excluding auxiliary facilities) under current codes and construction standards. |
| Cv | Value Coefficient |
| CWS | Chilled Water System |
| D d | Distance (usually feet) |
| DB | Dry Bulb |
| DCV | Demand Control Ventilation |
| DD | Degree Day |
| DDB | Double Declining Balance |
| DDC | Direct Digital Controls |
| Deferred maintenance | Deferred maintenance is condition work (excluding suitability and energy audit needs) deferred on a planned or unplanned basis to a future budget cycle or postponed until funds are available. |
| Deficiency | A deficiency is a repair item that is damaged missing inadequate or insufficient for an intended purpose. |
| Delta | Difference |
| Delta P | Pressure Difference |
| Delta T | Temperature Difference |
| DG | Distributed Generation |
| DOE | Department of Energy |
| DP | Dew Point |
| DR | Demand Response |
| DX | Direct Expansion Air Conditioner |
| EA | Energy Audit |
| EBITDA | Earnings before Interest Taxes Depreciation and Amortization |
| ECI | Energy Cost Index |
| ECM | Energy Conservation Measure |
| ECO | Energy Conservation Opportunity |
| ECPA | Energy Conservation and Production Act |
| ECR | Energy Conservation Recommendation |
| ECS | Energy Control System |

Site Assessment Report - S263001;Sharswood

| | |
|--|--|
| EER | Energy Efficiency Ratio |
| EERE | Energy Efficiency and Renewable Energy division of US DOE |
| EIA | Energy Information Agency |
| EIS | Energy Information System |
| EMCS | Energy Management Computer System |
| EMO | Energy Management Opportunity |
| EMP | Energy Management Project |
| EMR | Energy Management Recommendation |
| EMS | Energy Management System |
| Energy Utilization Index (EUI) | EUI is the measure of total energy consumed in the cooling or heating of a building in a period expressed as British thermal unit (BTU) per (cooled or heated) gross square foot. |
| EO | Executive Order |
| EPA | Environmental Protection Agency |
| EPACT | Energy Policy Act of 1992 |
| EPCA | Energy Production and Conservation Act of 1975 |
| EPRI | Electric Power Research Institute |
| EREN | Efficiency and Renewable Energy (Division of USDOE) |
| ERV | Energy Recovery Ventilator |
| ESCO | Energy Service Company |
| ESPC | Energy Savings Performance Contract |
| EUI | Energy Use Index |
| EWG | Exempt Wholesale Generators |
| Extended Facility Condition Index (EFCI) | EFCI is calculated as the condition needs for the current year plus facility system renewal needs going out to a set time in the future divided by Current Replacement Value. |
| f | Frequency |
| F | Fahrenheit |
| Facility | A facility refers to site(s) building(s) or building addition(s) or combinations thereof that provide a particular service. |
| Facility Condition Assessment (FCA) | FCA is a process for evaluating the condition of buildings and facilities for programming and budgetary purposes through an on site inspection and evaluation process. |
| Facility Condition Index (FCI) | FCI is an industry-standard measurement of a facility's condition that is the ratio of the cost to correct a facility's deficiencies to the Current Replacement Value of the facilities. The higher the FCI the poorer the condition of a facility. After an FCI is established for all buildings within a portfolio a building's condition can be ranked relative to other buildings. The FCI may also represent the condition of a portfolio based on the cumulative FCIs of the portfolio's facilities. |

Site Assessment Report - S263001;Sharswood

| | |
|-------------------------|---|
| FC | Footcandle |
| FCA | Fuel Cost Adjustment |
| FEMIA | Federal Energy Management Improvement Act of 1988 |
| FEMP | Federal Energy Management Program |
| FERC | Federal Energy Regulatory Commission |
| FESR | Fuel Energy Savings Ratio |
| FLA | Full Load Amps |
| FLF | Facility Load Factor (usually monthly) |
| FLRPM | Full Load Revolutions per Minute |
| FMS | Facility Management System |
| FPM fpm | Feet per Minute (velocity) |
| FSEC | Florida Solar Energy Center |
| Ft | Foot |
| GPM gpm | Gallons per Minute |
| GRI | Gas Research Institute |
| Gross Square Feet (GSF) | The size of the enclosed floor space of a building in square feet measured to the outside face of the enclosing wall. |
| GUI | Graphical User Interface |
| H h | Enthalpy Btu/lb |
| HCFC | Hydrochlorofluorocarbons |
| HDD | Heating Degree days |
| HFC | Hydrofluorocarbons |
| HHV | Higher Heating Value |
| HID | High Intensity Discharge (lamp) |
| HMI | Human Machine Interface |
| HMMI | Human Man Machine Interface |
| HO | High Output (lamp) |
| HP Hp hp | Horsepower |
| HPS | High Pressure Sodium (lamp) |
| HR | Humidity Ratio |
| Hr hr | Hour |

Site Assessment Report - S263001;Sharswood

| | |
|--------------|--|
| HRU | Heat Recovery Unit |
| HVAC | Heating Ventilation and Air-Conditioning |
| Hz | Hertz |
| I | Intensity (lumen output of lamp) |
| I i | Interest rate or Discount rate |
| IAQ | Indoor Air Quality |
| ICA | International Cogeneration Alliance |
| ICBO | International Conference of Buildings Officials |
| ICC | International Code Council |
| ICP | Institutional Conservation Program |
| IECC | International Energy Conservation Code |
| IEEE | Institute of Electrical and Electronic Engineers |
| IESNA | Illuminating Engineering Society of North America |
| Install year | The year a building or system was built or the most recent major renovation date (where a minimum of 70 of the system's Current Replacement Value (CRV) was replaced). |
| IRP | Integrated Resource Planning |
| IRR | Internal Rate of Return |
| ISO | Independent System Operator |
| ITA | Independent Tariff Administrator |
| k | Kilo multiple of thousands in SI system |
| K | Kelvins (color temperature of lamp) |
| K k | Thermal Conductivity of Material |
| KVA | Kilovolt Ampere |
| KVAR | Kilovolt Ampere Reactive |
| kW | kiloWatt |
| kWh | kiloWatt hour |
| L | Length (usually feet) |
| LCC | Life Cycle Costing |
| LDC | Local Distribution Company |
| LEED | Leadership in Energy and Environmental Design |
| LEED EB | LEED for Existing Buildings |

Site Assessment Report - S263001;Sharswood

| | |
|--------------|--|
| LEED NC | LEED for new construction |
| LF | Load Factor |
| LHV | Lower Heating Value |
| Life cycle | The period of time that a building or site system or element can be expected to adequately serve its intended function. |
| LPS | Low Pressure Sodium (lamp) |
| Lu | Lumen Output of a Lamp or Fixture |
| M | Mega multiple of millions in SI system |
| M&V | Measurement and Verification |
| MACRS | Modified Accelerated Cost Recovery System |
| MARR | Minimum Attractive Rate of Return |
| Mbtu | Thousand Btu |
| MCF | Thousand Cubic Feet (usually of gas) |
| MEC | Model Energy Code |
| Mm | Multiple of Thousands in I/P System |
| MMBtu | Million Btu |
| MMCS | Maintenance Management Computer System |
| MMI | Man Machine Interface |
| MMS | Maintenance Management System |
| MSE 2000 | Management System for Energy 2000 (ANSI Georgia Tech Univ) |
| MW | MegaWatt |
| MWH MWh | MegaWatt hour |
| NAAQS | National Ambient Air Quality Standards |
| NAESCO | National Association of Energy Service Companies |
| NAIMA | North American Insulation Manufacturers Association |
| NEA | National Energy Act of 1978 |
| NECPA | National Energy Conservation Policy Act |
| NEMA | National Electrical Manufacturer's Association |
| NERC | North American Electric Reliability Council |
| Next Renewal | The Next Renewal date is an override of the 'Calculated Next Renewal' date and is based upon the assessor's visual inspection. |

Site Assessment Report - S263001;Sharswood

| | |
|-----------|---|
| NFPA | National Fire Protection Association |
| NGPA | National Gas Policy Act of 1978 |
| NLRPM | No Load Revolutions per Minute (speed) |
| Nn | Equipment or Project lifetime in economic analysis |
| NOPR | Notice of Proposed Rule Making from FERC |
| NOx | Nitrogen Oxide Compounds |
| NPV | Net present value in economic analysis |
| NREL | National Renewable Energy Laboratory |
| NUG | Non-Utility Generator |
| O&M | Operation and Maintenance |
| OA | Outside Air |
| ODP | Ozone Depletion Potential |
| OPAC | Off-Peak Air Conditioning |
| P | Present value in economic analysis |
| PBR | Performance Based Rates |
| PEA | Preliminary Energy Audit |
| PF | Power Factor |
| PID | Proportional plus integral plus derivative (control system) |
| PM | Portfolio Manager in Energy Star rating system |
| PM | Preventive Maintenance |
| PoolCo | Power Pool Company or Organization |
| POU | Point of Use |
| PQ | Power Quality |
| PSC | Public Service Commission |
| PSIA psia | Pounds per square inch absolute (pressure) |
| PSIG psig | Pounds per square inch gauge (pressure) |
| PUC | Public Utility Commission |
| PUHCA | Public Utilities Holding Company Act of 1935 |
| PURPA | Public Utilities Regulatory Policies of 1978 |
| PV | Photovoltaic system |

Site Assessment Report - S263001;Sharswood

| | |
|-------------------------------------|---|
| PV | Present Value |
| PW | Present Worth |
| PX | Power Exchange |
| q | Rate of heat flow in Btu per hour |
| Q | Heat load due to conduction using degree days |
| QF | Qualifying Facility |
| R | Electrical resistance |
| R | Thermal Resistance |
| RC | Remote controller |
| RCR | Room Cavity Ratio |
| RCRA | Resource Conservation and Recovery Act |
| Remaining Service Life (RSL) | RSL is the number of years service remaining for a system or equipment item. It is automatically calculated based on the difference between the current year and the 'Calculated Next Renewal' date or the 'Next Renewal' date whichever one is the later date. |
| Remaining Service Life Index (RSLI) | RSLI is defined as a percentage ratio of the remaining service life of a system. It usually ranges from 0 to 100 |
| REMR | Repair Evaluation Maintenance Rehabilitation (REMR) is a scale used to objectively rank systems based on their condition |
| Renewal Schedule | A timeline that provides the items that need repair the year in which the repair is needed and the estimated price of the renewal. |
| RH | Relative Humidity |
| RLA | Running Load Amps |
| RMS | Root Mean Square |
| RO | Reverse Osmosis |
| ROI | Return on Investment |
| RPM | Revolutions Per Minute |
| RTG | Regional Transmission Group |
| RTO | Regional Transmission Organization |
| RTP | Real Time Pricing |
| SBCCI | Southern Building Code Congress International |
| SC | Scheduling Coordinator |
| SC | Shading Coefficient |
| SCADA | Supervisory Control and Data Acquisition Systems |

Site Assessment Report - S263001;Sharswood

| | |
|--------------|--|
| SEER | Seasonal Energy Efficiency Ratio |
| SHR | Sensible Heat Ratio |
| Site | The grounds and utilities roadways landscaping fencing and other typical land improvements needed to support the facility. |
| Soft Cost | An expense item that is not considered direct construction cost. Soft cost includes architectural engineering financing legal fees and other pre-and-post construction expenses. |
| SOx | Sulfur Oxide Compounds |
| SP | Static Pressure |
| SP SPB | Simple Payback |
| SPP | Simple Payback Period |
| SPP | Small Power Producers |
| STR | Stack Temperature Rise |
| SV | Specific Volume |
| System | System refers to building and related site work elements as described by ASTM Uniformat II Classification for Building Elements (E1557-97) a format for classifying major facility elements common to most buildings. Elements usually perform a given function regardless of the design specification construction method or materials used. See also Uniformat II. |
| T | Temperature |
| T | Tubular (lamps) |
| TAA | Technical Assistance Audit |
| TCP/IP | Transmission Control Protocol/Internet Protocol |
| TES | Thermal Energy Storage |
| THD | Total Harmonic Distortion |
| TOD | Time of Day |
| TOU | Time of Use |
| TQM | Total Quality Management |
| TransCo | Transmission Company |
| U | Thermal Conductance |
| UDC | Utility Distribution Company |
| UL | Underwriters Laboratories |
| UNIFORMAT II | The ASTM UNIFORMAT II Classification for Building Elements (E1557-97) a format for classifying major facility components common to most buildings. |
| USGBC | US Green Building Council |
| v | Specific Volume |

Site Assessment Report - S263001;Sharswood

| | |
|------------|---|
| V | Volts Voltage |
| V | Volume |
| VAV | Variable Air Volume |
| VDT | Video Display Terminal |
| VFD | Variable Frequency Drive |
| VHO | Very High Output |
| VSD | Variable Speed Drive |
| W | Watts |
| W | Width |
| WB | Wet bulb |
| WH Wh | Watt Hours |
| Year built | The year that a building or addition was originally built based on substantial completion or occupancy. |
| Z | Electrical Impedance |