

## Facility Condition Assessment Summary Report

This report provides a summary of the Facility Condition Index (FCI) value of a school facility and select major building systems. The FCI calculation represents the cost of needed repairs divided by the replacement value. The FCI is a numerical value of condition and helps to identify the need for renewal or replacement of specific parts of the facility. The FCI is particularly useful when comparing similar facilities within the same portfolio.

### Willard School

Governance	DISTRICT	Report Type	Elementary
Address	1930 E. Elkhart St. Philadelphia, Pa 19134	Enrollment	752
Phone/Fax	215-291-4714 / 215-291-4161	Grade Range	'00-04'
Website	Www.Philasd.Org/Schools/Willard	Admissions Category	Neighborhood
		Turnaround Model	N/A

### Building/System FCI Tiers

Facility Condition Index (FCI) = $\frac{\text{Cost of Assessed Deficiencies}}{\text{Replacement Value}}$				
< 15%	15 to 25%	25 to 45%	45 to 60%	> 60%
Buildings				
Minimal Current Capital Funding Required	Refurbish Systems in building	Replace Systems in building.	Building should be considered for major renovation.	Building should be considered for closing/replacement.
Systems				
Perform routine maintenance on system	System requires minor repairs	System should be studied to determine repair vs. replacement.	System is nearing end of its life expectancy and should be considered for replacement	System should be replaced as part of the Capital Program

### Building and Grounds

	FCI	Repair Costs	Replacement Cost
<b>Overall</b>	<b>00.46%</b>	<b>\$242,339</b>	<b>\$52,429,167</b>
Building	00.32 %	\$160,786	\$50,256,330
Grounds	03.75 %	\$81,553	\$2,172,837

### Major Building Systems

Building System	System FCI	Repair Costs	Replacement Cost
<b>Roof</b> (Shows physical condition of roof)	00.12 %	\$3,202	\$2,759,389
<b>Exterior Walls</b> (Shows condition of the structural condition of the exterior facade)	00.00 %	\$0	\$3,589,904
<b>Windows</b> (Shows functionality of exterior windows)	00.00 %	\$0	\$1,751,671
<b>Exterior Doors</b> (Shows condition of exterior doors)	00.00 %	\$0	\$141,028
<b>Interior Doors</b> (Classroom doors)	00.00 %	\$0	\$341,386
<b>Interior Walls</b> (Paint and Finishes)	00.00 %	\$0	\$1,634,957
<b>Plumbing Fixtures</b>	00.00 %	\$0	\$1,314,969
<b>Boilers</b>	00.00 %	\$0	\$1,815,863
<b>Chillers/Cooling Towers</b>	00.00 %	\$0	\$2,380,949
<b>Radiators/Unit Ventilators/HVAC</b>	00.00 %	\$0	\$4,181,250
<b>Heating/Cooling Controls</b>	00.00 %	\$0	\$1,313,024
<b>Electrical Service and Distribution</b>	00.00 %	\$0	\$943,432
<b>Lighting</b>	00.00 %	\$0	\$3,373,011
<b>Communications and Security</b> (Cameras, Pa System and Fire Alarm)	12.47 %	\$157,584	\$1,263,420

Please note that some FCIs may be over 100% because there are times when replacing a building system requires that other building systems be upgraded to complete the installation. A FCI of 0.0% represents that there are no current deficiencies with the associated system.

## Facility Condition Assessment Summary Report

This report provides a summary of the Facility Condition Index (FCI) value of a school facility and select major building systems. The FCI calculation represents the cost of needed repairs divided by the replacement value. The FCI is a numerical value of condition and helps to identify the need for renewal or replacement of specific parts of the facility. The FCI is particularly useful when comparing similar facilities within the same portfolio.

### Willard Annex School

Governance	DISTRICT	Report Type	Elementary
Address	3072 Frankford Ave Philadelphia, Pa 19134	Enrollment	
Phone/Fax	215-291-4714 / 215-291-4161	Grade Range	'00-04'
Website	Www.Philasd.Org/Schools/Willard	Admissions Category	Neighborhood
		Turnaround Model	N/A

### Building/System FCI Tiers

Facility Condition Index (FCI) = $\frac{\text{Cost of Assessed Deficiencies}}{\text{Replacement Value}}$				
< 15%	15 to 25%	25 to 45%	45 to 60%	> 60%
<b>Buildings</b>				
Minimal Current Capital Funding Required	Refurbish Systems in building	Replace Systems in building.	Building should be considered for major renovation.	Building should be considered for closing/replacement.
<b>Systems</b>				
Perform routine maintenance on system	System requires minor repairs	System should be studied to determine repair vs. replacement.	System is nearing end of its life expectancy and should be considered for replacement	System should be replaced as part of the Capital Program

### Building and Grounds

	FCI	Repair Costs	Replacement Cost
<b>Overall</b>	<b>26.06%</b>	<b>\$1,501,276</b>	<b>\$5,761,554</b>
Building	25.53 %	\$1,461,784	\$5,725,446
Grounds	109.37 %	\$39,492	\$36,108

### Major Building Systems

Building System	System FCI	Repair Costs	Replacement Cost
<b>Roof</b> (Shows physical condition of roof)	00.00 %	\$0	\$419,184
<b>Exterior Walls</b> (Shows condition of the structural condition of the exterior facade)	08.91 %	\$26,465	\$296,902
<b>Windows</b> (Shows functionality of exterior windows)	00.00 %	\$0	\$129,621
<b>Exterior Doors</b> (Shows condition of exterior doors)	00.00 %	\$0	\$15,882
<b>Interior Doors</b> (Classroom doors)	00.00 %	\$0	\$35,758
<b>Interior Walls</b> (Paint and Finishes)	00.00 %	\$0	\$159,863
<b>Plumbing Fixtures</b>	00.00 %	\$0	\$300,326
<b>Boilers</b>	00.00 %	\$0	\$177,552
<b>Chillers/Cooling Towers</b>	00.00 %	\$0	\$232,805
<b>Radiators/Unit Ventilators/HVAC</b>	213.23 %	\$871,739	\$408,835
<b>Heating/Cooling Controls</b>	158.90 %	\$204,009	\$128,385
<b>Electrical Service and Distribution</b>	00.00 %	\$0	\$92,247
<b>Lighting</b>	00.00 %	\$0	\$329,807
<b>Communications and Security</b> (Cameras, Pa System and Fire Alarm)	54.24 %	\$67,007	\$123,535

Please note that some FCIs may be over 100% because there are times when replacing a building system requires that other building systems be upgraded to complete the installation. A FCI of 0.0% represents that there are no current deficiencies with the associated system.

School District of Philadelphia  
**S544001;Willard**  
Final  
**Site Assessment Report**

January 31, 2017



## Table of Contents

Site Executive Summary	4
Site Condition Summary	10
<b><u>B544001:Willard</u></b>	12
Executive Summary	12
Condition Summary	13
Condition Detail	14
System Listing	15
System Notes	17
Renewal Schedule	18
Forecasted Sustainment Requirement	21
Condition Index Forecast by Investment Scenario	22
Deficiency Summary By System	23
Deficiency Summary By Priority	24
Deficiency By Priority Investment	25
Deficiency Summary By Category	26
Deficiency Details By Priority	27
Equipment Inventory Detail	29
<b><u>G544001:Grounds</u></b>	31
Executive Summary	31
Condition Summary	32
Condition Detail	33
System Listing	34
System Notes	35
Renewal Schedule	36
Forecasted Sustainment Requirement	37
Condition Index Forecast by Investment Scenario	38
Deficiency Summary By System	39
Deficiency Summary By Priority	40
Deficiency By Priority Investment	41

## Site Assessment Report

---

Deficiency Summary By Category	42
Deficiency Details By Priority	43
Equipment Inventory Detail	45
Glossary	46

## Site Executive Summary

The organization of this report, as displayed in the Table of Contents, follows the structure of the associated eCOMET database. The overall node for each school campus begins with the letter "S", which indicates the "Site" label. Each Site is comprised of separate "Building" and "Grounds" nodes; their asset names begin with the letters "B" and "G" respectively. Information rolls up to the Site node from the Building and Grounds nodes. This Site report combines facility information with subsections for the Buildings And Grounds nodes.

The basis for the evaluation of condition is the functional systems and elements of a building and grounds organized according to the UNIFORMAT II Elemental Classification. The grouping of these systems and elements and applying a current replacement value to them develops a representative building cost model. Cost Models are typically developed for similar building types and functions. Evaluation of systems and their elements takes into account their current replacement values, life cycles, installation dates and next renewal dates. Systems and their elements that are within their useful lives are further evaluated to identify current deficient conditions that may have a significant impact on a system's or element's remaining service life, and to determine if they are beyond their predicted expected life. The system's or element's current replacement value is based on RS Means Commercial Cost Data.

Following are the cost model's system details for this facility. The Replacement Value is the amount needed to replace the property of the same present value. The Current Repair Amount, also known as Condition Needs, represents the budgeted contractor installed costs plus owner's soft costs for the repair, replacement or renewal for a component or system level deficiency. It excludes contributing costs for other components or systems that might also be associated with the corrective actions due to packaging the work. Facility Condition Index (FCI) is an industry-standard measurement calculated as the ratio of the repair costs to correct a facility's deficiencies to the facility's Current Replacement Value. Condition Index (CI) for a system is calculated as the sum of the deficiencies divided by the sum of a system's Replacement Value (both values include soft-cost) expressed as a percentage ranging from 0% 100%.

Gross Area (SF):	97,261
Year Built:	2010
Last Renovation:	
Replacement Value:	\$52,429,167
Repair Cost:	\$242,339.34
Total FCI:	0.46 %
Total RSLI:	85.11 %



### Description:

Facility Assessment  
October, 2015

**School District of Philadelphia**  
**Willard Elementary School**  
**1930 E. Elkhart Street**  
**Philadelphia, PA 19134**

97,261 SF / 775 Students / LN 05

The Willard Elementary School building is located at 1930 E. Elkhart Street in Philadelphia, PA. The 97,261 square foot building was constructed in 2010. The building has no basement. The west wing and portion or the central core are 2 stories, the remainder is 1 story.

Mr. Scott Ovington, Facility Area Coordinator provided input to the Parsons assessment team on current problems and planned renovation projects. Mr. James Welsh, Building Engineer, accompanied us on our tour of the school and provided us with detailed information on the building systems and recent maintenance history.

### **STRUCTURAL/ EXTERIOR CLOSURE:**

The building typically rests on concrete spread and strip footings that are not showing signs of settlement or damage. The main structure is typically steel frame, columns and girders; floors are typically concrete slab over metal deck supported by bar joists. The superstructure is generally in very good condition.

The exterior walls typically comprise of stone cladding on the first floor and split face brick on the second floor; walls are insulated cavity type. Egress stairways and walls extending above main roof are clad with metal panels.

The roof structure is a metal deck supported by bar joists and wide flange framing and is typically flat with slopes to roof drains. The certain elements of the building such as Gym, Auditorium and second floor of the classroom wing are curved and supported by trusses and purlins.

Exterior windows are typically anodized aluminum curtain wall, double insulated units with tilt-in operating sections covered with integral security screens; Gym.

Exterior doors are typically aluminum, double insulated glazed and part of the curtain wall system; service doors are typically hollow metal in hollow metal frames, in very good condition.

Roofing typically consists of 2 types: mult-up over rigid insulation, and prefinished metal, standing seam roofing over curved roofs. All roofing is generally in very good condition except a small leak developing along the metal roof lashing above 3 kindergarten classrooms on the first floor.

### **INTERIORS:**

Partition wall types include painted CMU, ground face CMU, glazed aluminum store front and drywall, in very good condition. Portions of Gym walls are acoustic CMU; Walls in auditorium theatre are typically acoustic CMU and drywall with acoustic panels. The interior wall finishes are generally painted drywall in offices and CMU elsewhere.

Most ceilings are 2x2 suspended acoustical panels; ceiling in Gym, and main stairway is exposed metal deck, painted. Ceiling in the auditorium theatre is exposed with suspended acoustical baffles. All ceilings are in very good condition.

Flooring in most areas is generally vinyl composition tile, in very good condition. Flooring in library and offices is carpet in very good condition. Gym has artificial wood flooring in very good condition. Flooring in toilets and kitchen area is typically ceramic tiles in good condition.

Interior doors are generally solid core wood doors in hollow metal frames, in good condition. Doors in store front partitions are typically solid core, glazed.

Stairs are generally painted steel with concrete filled metal pan treads with non-slip nosings.

Interior identifying devices are of modular type directly affixed to wall surfaces.

Toilet partitions are mostly phenolic resin panels, ADA compliant, in very good condition, Accessories are in very good condition.

Institutional equipment includes library equipment; stage equipment; A/V equipment; and laboratory equipment; gym equipment – basketball backstops, scoreboards, etc. Other equipment includes kitchen equipment. All equipment is in very good condition.

### **CONVEYING EQUIPMENT:**

The building does have a 3500 lb hydraulic elevator, in good condition.

### **ACCESSIBILITY:**

The building does have accessible entrance and accessible routes, including walkways not exceeding 5% slope, per requirement. Toilets are generally in compliance with ADA. Door handles are typically lever type. Elevator is ADA compliant.

### **GROUNDS (SITE):**



## Site Assessment Report - S544001;Willard

---

There are two parking lots at the site, in good condition. Public parking for 48 vehicles has 3 accessible spaces; staff parking for 35 vehicles has no spaces designated as accessible. Compliant accessible signage is in good condition. Per ADA requirements 2 spaces are needed at staff parking.

Playground paving is generally asphalt a portion of which is covered with protective rubber mat. Walkways are concrete paved. Perimeter chain link fences are generally in good condition. Playground areas are enclosed with picket fences. The north and west portion of the site is landscaped with trees, shrubs and grass areas, generally in good condition, however a large grass area on the north side is deteriorated. The trees and shrubs are not fully mature.

### PLUMBING:

Plumbing Fixtures - The original plumbing fixtures remain in service. Fixtures in the restrooms on each floor consist of wall mounted push button flush valve water closets, wall hung urinals and lavatories with both wheel handle and lever faucets. The restrooms on each floor are equipped with at least one handicap accessible stall. No major issues with the plumbing fixtures were reported. The units are in good condition and should provide reliable service for the next 25-30 years.

Drinking fountains in the corridors and at the restrooms consist of wall hung fixtures with integral refrigerated coolers. They are within their service life and are accessible type.

A mop basin is available in a janitor closet in the corridor on each floor for use by the janitorial staff.

The Kitchen has one (1) sink; a three-compartment stainless steel sink with lever operated faucets. A grease trap is not installed. Chemicals are injected manually into the sanitizing basins.

Domestic Water Distribution - A 4" city water service enters the first floor Mechanical Room 168A on the North side of the building. Two (2) reduced pressure backflow preventers are installed in parallel. The domestic hot and cold water distribution piping is copper piping and sweat fittings. The maintenance staff reports no significant problems with scale build up in the domestic piping and the supply is adequate to the fixtures.

Two (2) A.O. Smith 100 gallon vertical domestic hot water heaters with circulating pump and Amtrol expansion tank provide domestic hot water for the building. The expansion tank is not used, according to the Building Engineer. Both units are original to the building, are gas fired, and are located in first floor Mechanical Room 168A room. The hot water heaters are equipped with T&P relief valves. The domestic hot water heaters are well within their service lives and reliable service should be provided for the next 5-8 years. A water softener is located in Mechanical Room 168A.

Sanitary Waste - The sanitary sewer piping is cast iron with no-hub fittings and is within its service life. The majority of sanitary piping is located under the building slab and within mechanical chases. The maintenance staff reported no problems with the sanitary waste piping systems and they are well within their service life.

A sewage ejector pit located in Mechanical Room 119 receives water from the surrounding area. It has dual submerged pumps that are original to the building and are within their service lives. The system appeared to be in good condition and the pit is sealed.

Rain Water Drainage - Rain water drains from the roof are routed through a combination of internal and external rain leaders. The internal roof drains are cast iron piping with no-hub fittings and are routed through mechanical chases in the building. Other roof drains lead to external rain leaders with PVC downspouts that run down the side of the building and connect to cast iron piping approximately twelve (12) feet above the ground. The system is original to the building and is within its service life. No issues were reported with the roof drains or rain leaders.

### MECHANICAL:

Energy Supply - An 8" city gas service enters Mechanical Room 168A from the parking lot on the North East side of the building. The gas meter is 4" and located in the Mechanical Room 168A room.

The reserve oil supply is stored in a 10,000 gallon underground storage tank (UST) located in the parking lot on the North East side of the school. Duplex 1/2HP pumps located in Mechanical Room 168A circulate oil through the system. Oil is used as a backup fuel and the District receives credit from the gas utility as an interruptible service. USTs have an anticipated service life of 20 years.

Heat Generating Systems - Building heating hot water is generated by two (2) 75HP HB Smith model 28HE RTS high efficiency cast iron sectional boilers with gross output of 2,513MBH. Each boiler is equipped with a Power Flame burner designed to operate on



## Site Assessment Report - S544001;Willard

---

natural gas or fuel oil. Combustion air makeup is supplied by louvers equipped with motorized dampers. Burner oil pumps are loose and not driven by the fan motor. The gas train serving the boilers does appear to have code required venting of the regulators and dual solenoid valves with venting of the chamber between. No major issues with the boilers were reported by the Building Engineer. Cast iron boilers have an anticipated service life of 35 years or more; these units have been in service 5 years. The District should provide reliable service for the next 25 to 30 years.

Cooling Generating Systems - Chilled water is generated by two (2) Carrier model 30HXC water-cooled twin rotary-screw chillers located in Mechanical Room 168A. Each chiller provides a nominal 210 tons of cooling, has three (3) compressors, and utilizes R-134a refrigerant. Heat from the chillers is rejected by two (2) roof mounted Evapco LSTB forced draft, counterflow cooling towers. Each chiller operates with an associated cooling tower. One (1) chiller is sufficient to hold the building on normal summer days; two (2) chillers are required on very hot days. Rotary screw compressor chillers have an anticipated service life of 20 years; these units have been in service 5 years. The District should provide reliable service for the next 12-15 years. Galvanized metal cooling towers have an anticipated service life of 18 years; these units have been in service 5 years. The District should provide reliable service for the next 10-13 years. The Building Engineer reported no issues with either the chillers or cooling towers.

Distribution Systems - A two-pipe, dual temperature distribution system supplies building heating or cooling water to the unit ventilators in classrooms and fan coil units in offices. Two (2) 10HP end-suction Bell and Gossett dual temperature supply pumps, P-7 and P-8, circulate building heating or cooling water to the unit ventilators. The pumps are in good condition and well within their service life.

A four-pipe distribution system supplies building heating and cooling water to the air handling units on the roof, in Mechanical Room 119, and Mechanical Room 219. Heating water is supplied to AHU-9 and AHU-10, which provide heating and ventilation only to the Gymnasium, by the hot water piping. Four (4) 7.5HP end-suction Bell and Gossett heating water supply pumps, P1, P2, P3, and P4, circulate building heating water. An expansion tank, air separator, and chemical treatment are installed on the heating water distribution system. Two (2) small in-line heating water supply pumps, P-5 and P-6, are on the supply side of the heating water. Four (4) 7.5HP end-suction Bell and Gossett chilled water return pumps, P-9, P-10, P-11, and P-12, circulate building chilled water. An air separator is installed on the chilled water return side. Two (2) 10HP end-suction Bell and Gossett chilled water supply pumps, P-13 and P-14, circulate building chilled water to the air handling units.

A two-pipe condenser water loop serves each respective chiller and cooling tower pair. There are four (4) 10HP end-suction Bell and Gossett condenser water supply pumps; P-15, P-16, P-17, and P-18. Pumps P-17 and P-18 serve chiller CH-1, pumps P-15 and P-16 serve chiller CH-2. Two (2) pumps serve each chiller/cooling tower combination with one (1) pump in operation and the other pump acting as a backup.

All pumps are original to the building, appear to be in good condition, and are within the anticipated service life of 25 years. All pumps, except P-5 and P-6, are equipped with VFDs for energy efficient operation. All main piping is black steel, covered with insulation, and appears to be in good condition. The condenser water piping is not covered with insulation and does not require it. Smaller branch piping is copper and covered in insulation. No problems with the distribution systems were reported.

Four (4) Annex Air, one (1) Racan Carrier, and five (5) Carrier air handling units (AHU) provide heating and cooling to specific spaces within the building. All AHUs are fed by a four pipe system for building hot and chilled water, except for AHU-9 and AHU-10 which provide heating only. A list of the air handling units and the spaces they serve is available in the eCOMET® file. AHU-1 is a Carrier model 39MN17 unit that serves the South corridor and is located in Mechanical Room 119. AHU-2 is a Carrier model 39MN08 unit that serves the Library and is located in Mechanical Room 219. AHU-3 is a Carrier model 39MN06 unit that serves the main office and is located in Mechanical Room 119. AHU-4 is an Annex Air model ERP unit that serves the Auditorium, has a 7.5HP supply fan, and is located on the roof. AHU-5 is a Carrier model 39MN17 unit that serves the Lobby and is located in Mechanical Room 119. AHU-6 is a Racan Carrier model A2D unit that serves the Cafeteria, has a 10HP supply fan, and is located on the roof. AHU-7 is an Annex Air model ERP unit that serves the North corridor, has a 7.5HP supply fan, and is located on the roof. AHU-8 is a Carrier model 39MN17 unit, serves the second floor corridor, and is located in Mechanical Room 219. AHU-9 and AHU-10 are Annex Air model ERP units that serve the Gymnasium, have a 7.5HP supply fan, are located on the roof, and provide heating and ventilation only. All units were operational during the site visit, are original to the building, and are well within their service life.

Unit ventilators provide heating and cooling for the classrooms. The unit ventilators are original to the building and are within their service life. Outdoor air for the building is provided by wall openings in the unit ventilators and by the air handling units. No major issues were reported with the unit ventilators. Fin tube radiators provide heating for hallways and stairwells. All radiators appeared to be in good condition. Fan coil units provide conditioned air to the various offices located throughout the building.

Terminal & Package Units - The building is exhausted by a total of seventeen (17) roof mounted exhaust fans. The lower roof has seven (7) exhaust fans, the upper roof has ten (10) exhaust fans. A list of the exhaust fans and the spaces they serve is available in the eCOMET® file. Two (2) power ventilators are also installed on the upper roof. The exhaust fans serve the various restrooms, IMF

## Site Assessment Report - S544001;Willard

---

room, mechanical room, and electrical rooms. The exhaust fans remove air from the ceiling plenum above the drop ceiling. The Building Engineer did not report any problems with the exhaust system. Roof mounted exhaust fans have an anticipated service life of twenty (20) years; these units have been in service 5 years; the District should provide reliable service for the next 12-15 years.

One (1) kitchen hood with a gas fired outdoor air make-up system is installed above the warming oven. The hood does not have integral fire suppression as only premade meals are served. The equipment is well within service life.

Controls & Instrumentation - A Niagara building management system (BMS) with DDC modules and communications network is installed in this building. The Building Engineer reported that the BMS, installed when the building was built, is operational. All major mechanical equipment (chillers, boilers, air handling units, pumps, fans, etc.) is able to be monitored and controlled by the system. Several valves are manual operation only, while most are able to be actuated by the controls system. This system is well within its service life and should provide reliable operation for the next 10-15 years.

Sprinklers - The building is equipped with a wet type sprinkler system. An 8" fire water line enters the building in Mechanical Room 168A along the same wall as the domestic water. The fire suppression system is the originally installed equipment and should not need replacement within the next 30 years.

The building is not equipped with fire stand pipes.

### **ELECTRICAL:**

Site electrical service - The primary power is at 13.2KV from the street power poles which goes underground and feeds a 1000KVA indoor transformer (13.2KV – 480V/277V). The electrical service is fairly new (2010) and has many years of useful life left. The main switchgear is rated at 1600 Amp, 480 V, 3 phase, and is located in main electrical room. The PECO meter (PECO 01 411196349) is located inside the electrical room as well. The electrical service entrance and the main building electrical distribution systems are fairly new and in very good condition. The electrical service has capacity for future growth.

Distribution system - The electrical distribution is accomplished with 120V distribution switchboards. Switchboards feed the 120V panels throughout the building (two in each floor). These panels are in good condition and do not need to be replaced.

Receptacles - There is adequate receptacles in classrooms, computer rooms, libraries, and other areas.

Lighting - Interior building is illuminated by various types of fixtures. They include fluorescent lighting (T-5 & T-8 lamps) in majority of the areas, including; classrooms, corridor, offices and Kitchen. Surface or pendent mounted industrial fluorescent used in mechanical and electrical rooms. Gymnasium is illuminated by metal halide enclosed glass fixture. The entire building's interior lighting fixtures are in good condition and have many years of useful life left in them.

Fire alarm - The present Fire Alarm system is automatic/addressable, and is in compliance with safety codes. There are manual pulls stations throughout the building. There are also sufficient number of horn/strobes installed in the classrooms, corridors, offices and other areas in the school.

Telephone/LAN - The school telephone and data systems are new and working adequately. A main distribution frame (MDF) along with a telephone PBX system is servicing the communication system of the building. School is also equipped with Wi-Fi system.

Public address - Separate PA system does not exist. School uses the telephone systems for public announcement. This system is working adequately. The present Intercom System is functioning fine. Each class room is provided by with intercom telephone service. The system is for paging and intercom communication between main office phone to classroom phones, classroom to main office, and classroom to classroom.

Clock and Program system - The present clock system is working adequately for most part, however, school prefers more clocks that are controlled by central master control panel.

Television System - Television system is not provided in the school. Most classes are provided with smart board having ability of connection to computer and internet.

Security Systems, access control, and video surveillance - The school is provided with adequate video surveillance system. There are sufficient number of cameras (about 64). They are installed at exit doors, corridors, exterior, and other critical areas. These cameras are controlled by a Closed Circuit Television system (CCTV).

## Site Assessment Report - S544001;Willard

---

Emergency Power System - School is provided with a 100 KW emergency generator to feed elevators, emergency lighting and other emergency loads from an Emergency Panel. Power is switched between Normal (Utility Power) and Emergency Power (Generator) via an Automatic Transfer Switch (ATS).

Emergency lighting system, including exit lighting - There are sufficient number of emergency lighting fixtures in corridors, and other exit ways. Exit signs and emergency fixtures are fairly new.

Lightning Protection System - There is adequate lightning protection system installed in the school. There are lightning rods installed on the roof. The rods are properly connected to the ground via stranded aluminum cables.

Grounding - The present grounding system is adequate. All the equipment in the school are properly bonded to the ground.

Site Lighting - Campus and parking area and building Perimeters are adequately lighted for safety of the people and security of property.

Site Paging - The present Site paging System is adequate. There are sufficient number of speakers located inside the building and on the building exterior walls.

Auditorium lighting and sound system - The auditorium general lighting is at proper illumination FC level. Stage lighting system and the sound systems are fairly new and functioning properly.

### RECOMMENDATIONS:

- Repair flashing on standing seam metal roof above kindergarten classrooms
- Stripe 2 accessible parking spaces and aisle on staff parking; install signage
- Re-sod grass section on the north side of the building
- Install an upgraded Clock System with enough capacity to provide clocks for the entire building

### Attributes:

#### General Attributes:

Active:	Open	Bldg Lot Tm:	Lot 3 / Tm 4
Status:	Accepted by SDP	Team:	Tm 4
Site ID:	S544001		

## Site Condition Summary

The Table below shows the CI and FCI for each major system shown at the UNIFORMAT classification Level II. Note that Systems with lower FCIs require less investment than systems with higher FCIs.


### Current Investment Requirement and Condition by Uniformat Classification

UNIFORMAT Classification	RSLI%	FCI %	Current Repair
A10 - Foundations	95.00 %	0.00 %	\$0.00
A20 - Basement Construction	95.00 %	0.00 %	\$0.00
B10 - Superstructure	95.00 %	0.00 %	\$0.00
B20 - Exterior Enclosure	92.22 %	0.00 %	\$0.00
B30 - Roofing	80.22 %	0.12 %	\$3,202.08
C10 - Interior Construction	92.97 %	0.00 %	\$0.00
C20 - Stairs	95.00 %	0.00 %	\$0.00
C30 - Interior Finishes	73.67 %	0.00 %	\$0.00
D10 - Conveying	85.71 %	0.00 %	\$0.00
D20 - Plumbing	84.16 %	0.00 %	\$0.00
D30 - HVAC	80.56 %	0.00 %	\$0.00
D40 - Fire Protection	85.71 %	0.00 %	\$0.00
D50 - Electrical	74.73 %	2.76 %	\$157,584.31
E10 - Equipment	85.71 %	0.00 %	\$0.00
E20 - Furnishings	87.50 %	0.00 %	\$0.00
G20 - Site Improvements	81.60 %	5.12 %	\$81,552.95
G40 - Site Electrical Utilities	83.33 %	0.00 %	\$0.00
<b>Totals:</b>	<b>85.11 %</b>	<b>0.46 %</b>	<b>\$242,339.34</b>

### Condition Deficiency Priority

Facility Name	Gross Area (S.F.)	FCI %	1 - Response Time (< 2 yr)	2 - Response Time (2-3 yrs)	3 - Response Time (3-4 yrs)	4 - Response Time (4-5 yrs)	5 - Response Time (> 5 yrs)
B544001;Willard	97,261	0.32	\$0.00	\$3,202.08	\$0.00	\$157,584.31	\$0.00
G544001;Grounds	133,500	3.75	\$0.00	\$0.00	\$0.00	\$1,364.65	\$80,188.30
<b>Total:</b>		<b>0.46</b>	<b>\$0.00</b>	<b>\$3,202.08</b>	<b>\$0.00</b>	<b>\$158,948.96</b>	<b>\$80,188.30</b>

### Deficiencies By Priority



- 1 - Response Time (< 2 yr)
- 2 - Response Time (2-3 yrs) - \$3,202.08
- 3 - Response Time (3-4 yrs)
- 4 - Response Time (4-5 yrs) - \$158,948.96
- 5 - Response Time (> 5 yrs) - \$80,188.30

**Budget Estimate Total: \$242,339.34**

## Executive Summary

Building condition is evaluated based on the functional systems and elements of a building and organized according to the UNIFORMAT II Elemental Classification. The grouping of these systems and elements and applying a current replacement value to them develops a representative building cost model. Cost Models are developed for similar building types and functions. Systems and their elements are evaluated based on their current replacement values, life cycles, installation dates and next renewal dates. Systems and their elements that are within their useful lives are further evaluated to identify current deficient conditions that may have a significant impact on a system's or element's remaining service life, and to determine if they are beyond their predicted expected life. The system's or element's current replacement value is based on RS Means Commercial Cost Data.

Following are the cost model's system details for this facility. The Replacement Value is the amount needed to replace the property of the same present value. The Current Repair Amount, also known as Condition Needs, represents the budgeted contractor installed costs plus owner's soft costs for the repair, replacement or renewal for a component or system level deficiency. It excludes contributing costs for other components or systems that might also be associated with the corrective actions due to packaging the work. Facility Condition Index (FCI) FCI is an industry-standard measurement of facility condition calculated as the ratio of the costs to correct a facility's deficiencies to the facility's Current Replacement Value. It ranges from 0% (new) to 100% (very poor). Condition Index (CI) is calculated as the sum of a renewable system's Remaining Service Life (RSL) divided by the sum of a system's Replacement Value (both values exclude soft-cost to simplify calculation updates) expressed as a percentage ranging from 100% (new) to 0% (expired).

Function:	Elementary School
Gross Area (SF):	97,261
Year Built:	2010
Last Renovation:	
Replacement Value:	\$50,256,330
Repair Cost:	\$160,786.39
Total FCI:	0.32 %
Total RSLI:	85.25 %



**Description:**

**Attributes:**

**General Attributes:**

Active:	Open	Bldg ID:	B544001
Sewage Ejector:	Yes	Status:	Accepted by SDP
Site ID:	S544001		



## Condition Summary

The Table below shows the CI and FCI for each major building system shown at the UNIFORMAT classification Level II. Note that Systems with lower FCIs require less investment than systems with higher FCIs.

UNIFORMAT Classification	RSLI %	FCI %	Current Repair Cost
A10 - Foundations	95.00 %	0.00 %	\$0.00
A20 - Basement Construction	95.00 %	0.00 %	\$0.00
B10 - Superstructure	95.00 %	0.00 %	\$0.00
B20 - Exterior Enclosure	92.22 %	0.00 %	\$0.00
B30 - Roofing	80.22 %	0.12 %	\$3,202.08
C10 - Interior Construction	92.97 %	0.00 %	\$0.00
C20 - Stairs	95.00 %	0.00 %	\$0.00
C30 - Interior Finishes	73.67 %	0.00 %	\$0.00
D10 - Conveying	85.71 %	0.00 %	\$0.00
D20 - Plumbing	84.16 %	0.00 %	\$0.00
D30 - HVAC	80.56 %	0.00 %	\$0.00
D40 - Fire Protection	85.71 %	0.00 %	\$0.00
D50 - Electrical	74.73 %	2.76 %	\$157,584.31
E10 - Equipment	85.71 %	0.00 %	\$0.00
E20 - Furnishings	87.50 %	0.00 %	\$0.00
<b>Totals:</b>	<b>85.25 %</b>	<b>0.32 %</b>	<b>\$160,786.39</b>

## Condition Detail

This section of the report contains results of the Facility Condition Assessment. The building is separated into system components based on UNIFORMAT II classification. The columns in the System Listing table below represent the following:

1. System Code: A code that identifies the system.
2. System Description: A brief description of a system present in the building.
3. Unit Price \$: The unit price of the system.
4. UoM: The unit of measure for of the system.
5. Qty: The quantity for the system
6. Life: anticipated service life for the system based on Building Owners and Managers Association (BOMA) recommendations.
7. Year Installed: The date of system installation.
8. Calc Next Renewal Year: The date of system expiration based on the life, NR stands for non renewable.
9. Next Renewal Year: The suggested system expiration date by the assessor based on visual inspection.
10. CI: The Condition Index of the system.
11. FCI: The Facility Condition Index of the system.
12. RSL: Remaining Service Life.
13. eCR: eCOMET Condition Rating (not used).
14. Deficiency \$: The financial investment to repair/replace system.

## System Listing

The System Listing table below lists each of the systems organized by their UNIFORMAT II classification. The assessment team was tasked with recording the most recent replacement year of each system, determining the remaining service life based on the theoretical life, and evaluating the condition to confirm the forecast next replacement year. The system listing is the basis for all data contained in the Building Assessment Report.

Additionally, a condition rating (eCR) based on the following guidelines is provided as observed at the time of the assessment.

- Excellent (E) - No noticeable distress or damage. The entire system is free from observable defect.
- Very Good (VG) - Overall no serviceability reduction for the entire system. No degradation of critical components and minor distress and defect noticeable for some but not non critical components within the system.
- Good (G) - Slight or no serviceability reduction for the entire system. There may be noticeable defects for some non critical components and slight noticeable degradation of the critical components.
- Fair (F) - Overall serviceability is degraded but adequate. There may be moderate deterioration for very few of the critical components and few of the non critical components may have severe degradation.
- Marginal (MA) - Overall serviceability and reliability loss. Most if not all of the non critical components suffer from severe degradation and a few of the critical component may have severe degradation.
- Moderate (MO) - Overall a significant serviceability loss. Most if not all the components have severe degradation with the reminder of the component showing visible distress.
- Very Poor (VP) - Overall the system is barely functional. All of the components are severely degraded.
- Non-Functional (NF) - Overall the system does not function with all the components having no serviceability and suffer from severe degradation.

System Code	System Description	Unit Price \$	UoM	Qty	Life	Year Installed	Calc Next Renewal Year	Next Renewal Year	RSLT%	FCI%	RSL	eCR	Deficiency \$	Replacement Value \$
A1010	Standard Foundations	\$18.40	S.F.	97,261	100	2010	2110		95.00 %	0.00 %	95			\$1,789,602
A1030	Slab on Grade	\$7.73	S.F.	97,261	100	2010	2110		95.00 %	0.00 %	95			\$751,828
A2010	Basement Excavation	\$6.55	S.F.	97,261	100	2010	2110		95.00 %	0.00 %	95			\$637,060
A2020	Basement Walls	\$12.70	S.F.	97,261	100	2010	2110		95.00 %	0.00 %	95			\$1,235,215
B1010	Floor Construction	\$75.10	S.F.	97,261	100	2010	2110		95.00 %	0.00 %	95			\$7,304,301
B1020	Roof Construction	\$13.88	S.F.	97,261	100	2010	2110		95.00 %	0.00 %	95			\$1,349,983
B2010	Exterior Walls	\$36.91	S.F.	97,261	100	2010	2110		95.00 %	0.00 %	95			\$3,589,904
B2020	Exterior Windows	\$18.01	S.F.	97,261	40	2010	2050		87.50 %	0.00 %	35			\$1,751,671
B2030	Exterior Doors	\$1.45	S.F.	97,261	25	2010	2035		80.00 %	0.00 %	20			\$141,028
B3010105	Built-Up	\$37.76	S.F.	27,160	20	2010	2030		75.00 %	0.00 %	15			\$1,025,562
B3010120	Single Ply Membrane	\$38.73	S.F.		20				0.00 %	0.00 %				\$0
B3010130	Preformed Metal Roofing	\$54.22	S.F.	31,870	30	2010	2040		83.33 %	0.19 %	25		\$3,202.08	\$1,727,991
B3010140	Shingle & Tile	\$38.73	S.F.		25	2010	2035		80.00 %	0.00 %	20			\$0
B3020	Roof Openings	\$0.06	S.F.	97,261	20	2010	2030		75.00 %	0.00 %	15			\$5,836
C1010	Partitions	\$17.91	S.F.	97,261	100	2010	2110		95.00 %	0.00 %	95			\$1,741,945
C1020	Interior Doors	\$3.51	S.F.	97,261	40	2010	2050		87.50 %	0.00 %	35			\$341,386
C1030	Fittings	\$3.12	S.F.	97,261	40	2010	2050		87.50 %	0.00 %	35			\$303,454
C2010	Stair Construction	\$1.41	S.F.	97,261	100	2010	2110		95.00 %	0.00 %	95			\$137,138

Site Assessment Report - B544001;Willard

System Code	System Description	Unit Price \$	UoM	Qty	Life	Year Installed	Calc Next Renewal Year	Next Renewal Year	RSLI%	FCI%	RSL	eCR	Deficiency \$	Replacement Value \$
C3010230	Paint & Covering	\$13.21	S.F.	97,261	10	2010	2020		50.00 %	0.00 %	5			\$1,284,818
C3010231	Vinyl Wall Covering	\$0.97	S.F.	97,261	15	2010	2025		66.67 %	0.00 %	10			\$94,343
C3010232	Wall Tile	\$2.63	S.F.	97,261	30	2010	2040		83.33 %	0.00 %	25			\$255,796
C3020411	Carpet	\$7.30	S.F.	2,400	10	2010	2020		50.00 %	0.00 %	5			\$17,520
C3020412	Terrazzo & Tile	\$75.52	S.F.	11,750	50	2010	2060		90.00 %	0.00 %	45			\$887,360
C3020413	Vinyl Flooring	\$9.68	S.F.	50,840	20	2010	2030		75.00 %	0.00 %	15			\$492,131
C3020414	Wood Flooring	\$22.27	S.F.	6,000	25	2010	2035		80.00 %	0.00 %	20			\$133,620
C3020415	Concrete Floor Finishes	\$0.97	S.F.	6,800	50	2010	2060		90.00 %	0.00 %	45			\$6,596
C3030	Ceiling Finishes	\$20.97	S.F.	97,261	25	2010	2035		80.00 %	0.00 %	20			\$2,039,563
D1010	Elevators and Lifts	\$1.53	S.F.	97,261	35	2010	2045		85.71 %	0.00 %	30			\$148,809
D2010	Plumbing Fixtures	\$13.52	S.F.	97,261	35	2010	2045		85.71 %	0.00 %	30			\$1,314,969
D2020	Domestic Water Distribution	\$1.68	S.F.	97,261	25	2010	2035		80.00 %	0.00 %	20			\$163,398
D2030	Sanitary Waste	\$2.90	S.F.	97,261	25	2010	2035		80.00 %	0.00 %	20			\$282,057
D2040	Rain Water Drainage	\$2.32	S.F.	97,261	30	2010	2040		83.33 %	0.00 %	25			\$225,646
D3020	Heat Generating Systems	\$18.67	S.F.	97,261	35	2010	2045		85.71 %	0.00 %	30			\$1,815,863
D3030	Cooling Generating Systems	\$24.48	S.F.	97,261	30	2010	2040		83.33 %	0.00 %	25			\$2,380,949
D3040	Distribution Systems	\$42.99	S.F.	97,261	25	2010	2035		80.00 %	0.00 %	20			\$4,181,250
D3050	Terminal & Package Units	\$11.60	S.F.	97,261	20	2010	2030		75.00 %	0.00 %	15			\$1,128,228
D3060	Controls & Instrumentation	\$13.50	S.F.	97,261	20	2010	2030		75.00 %	0.00 %	15			\$1,313,024
D4010	Sprinklers	\$7.05	S.F.	97,261	35	2010	2045		85.71 %	0.00 %	30			\$685,690
D4020	Standpipes	\$1.01	S.F.	97,261	35	2010	2045		85.71 %	0.00 %	30			\$98,234
D5010	Electrical Service/Distribution	\$9.70	S.F.	97,261	30	2010	2040		83.33 %	0.00 %	25			\$943,432
D5020	Lighting and Branch Wiring	\$34.68	S.F.	97,261	20	2010	2030		75.00 %	0.00 %	15			\$3,373,011
D5030	Communications and Security	\$12.99	S.F.	97,261	15	2010	2025	2025	66.67 %	12.47 %	10		\$157,584.31	\$1,263,420
D5090	Other Electrical Systems	\$1.41	S.F.	97,261	30	2010	2040		83.33 %	0.00 %	25			\$137,138
E1020	Institutional Equipment	\$4.82	S.F.	97,261	35	2010	2045		85.71 %	0.00 %	30			\$468,798
E1090	Other Equipment	\$11.10	S.F.	97,261	35	2010	2045		85.71 %	0.00 %	30			\$1,079,597
E2010	Fixed Furnishings	\$2.13	S.F.	97,261	40	2010	2050		87.50 %	0.00 %	35			\$207,166
<b>Total</b>									<b>85.25 %</b>	<b>0.32 %</b>			<b>\$160,786.39</b>	<b>\$50,256,330</b>

## System Notes

The facility description in the site executive summary contains an overview of each system. The notes listed below provide additional information on select systems found within the facility.

---

<b>System:</b> C3010 - Wall Finishes	This system contains no images
<b>Note:</b> Paint 95% Acoustic panels 5%	
<hr/>	
<b>System:</b> C3020 - Floor Finishes	This system contains no images
<b>Note:</b> VCT 65% Ceramic tile 4% Terrazzo 11% Wood (artificial) 8% Carpet 3% Concrete 9%	
<hr/>	
<b>System:</b> C3030 - Ceiling Finishes	This system contains no images
<b>Note:</b> ACT 60% Drywall 10% Exposed/painted 30%	

## Renewal Schedule

eCOMET forecasts future Capital Renewal funding needed to address expiring systems based on the Next Renewal year found in the Cost Models. A 3% annual inflation factor is applied to the costs for systems expiring in future years. The table below reflects recommended Capital Renewal funding needs over the next 10 years. Note: Cells with a zero value indicate systems for which renewal is not scheduled in that year.

*Inflation Rate: 3%*

System	Current Deficiencies	2016	2017	2018	2019	2020	2021	2022	2023	2024	2025	Total
<b>Total:</b>	\$160,786	\$0	\$0	\$0	\$0	\$1,660,744	\$0	\$0	\$0	\$0	\$2,007,192	\$3,828,721
<b>* A - Substructure</b>	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
<b>A10 - Foundations</b>	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
<b>A1010 - Standard Foundations</b>	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
<b>A1030 - Slab on Grade</b>	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
<b>A20 - Basement Construction</b>	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
<b>A2010 - Basement Excavation</b>	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
<b>A2020 - Basement Walls</b>	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
<b>B - Shell</b>	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
<b>B10 - Superstructure</b>	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
<b>B1010 - Floor Construction</b>	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
<b>B1020 - Roof Construction</b>	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
<b>B20 - Exterior Enclosure</b>	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
<b>B2010 - Exterior Walls</b>	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
<b>B2020 - Exterior Windows</b>	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
<b>B2030 - Exterior Doors</b>	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
<b>B30 - Roofing</b>	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
<b>B3010 - Roof Coverings</b>	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
<b>B3010105 - Built-Up</b>	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
<b>B3010120 - Single Ply Membrane</b>	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
<b>B3010130 - Preformed Metal Roofing</b>	\$3,202	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$3,202
<b>B3010140 - Shingle &amp; Tile</b>	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
<b>B3020 - Roof Openings</b>	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
<b>C - Interiors</b>	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
<b>C10 - Interior Construction</b>	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
<b>C1010 - Partitions</b>	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0



Site Assessment Report - B544001;Willard

C1020 - Interior Doors	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C1030 - Fittings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C20 - Stairs	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C2010 - Stair Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C30 - Interior Finishes	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C3010 - Wall Finishes	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C3010230 - Paint & Covering	\$0	\$0	\$0	\$0	\$0	\$1,638,402	\$0	\$0	\$0	\$0	\$0	\$0	\$1,638,402
C3010231 - Vinyl Wall Covering	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$139,468	\$139,468
C3010232 - Wall Tile	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C3020 - Floor Finishes	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C3020411 - Carpet	\$0	\$0	\$0	\$0	\$0	\$22,342	\$0	\$0	\$0	\$0	\$0	\$0	\$22,342
C3020412 - Terrazzo & Tile	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C3020413 - Vinyl Flooring	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C3020414 - Wood Flooring	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C3020415 - Concrete Floor Finishes	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C3030 - Ceiling Finishes	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D - Services	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D10 - Conveying	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D1010 - Elevators and Lifts	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D20 - Plumbing	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D2010 - Plumbing Fixtures	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D2020 - Domestic Water Distribution	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D2030 - Sanitary Waste	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D2040 - Rain Water Drainage	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D30 - HVAC	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D3020 - Heat Generating Systems	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D3030 - Cooling Generating Systems	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D3040 - Distribution Systems	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D3050 - Terminal & Package Units	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D3060 - Controls & Instrumentation	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D40 - Fire Protection	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D4010 - Sprinklers	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D4020 - Standpipes	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0


## Site Assessment Report - B544001;Willard

<b>D50 - Electrical</b>	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
<b>D5010 - Electrical Service/Distribution</b>	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
<b>D5020 - Lighting and Branch Wiring</b>	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
<b>D5030 - Communications and Security</b>	\$157,584	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$1,867,724	\$2,025,308
<b>D5090 - Other Electrical Systems</b>	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
<b>E - Equipment &amp; Furnishings</b>	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
<b>E10 - Equipment</b>	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
<b>E1020 - Institutional Equipment</b>	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
<b>E1090 - Other Equipment</b>	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
<b>E20 - Furnishings</b>	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
<b>E2010 - Fixed Furnishings</b>	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0

\* Indicates non-renewable system

## Forecasted Sustainment Requirement

The following chart shows the current building deficiencies and forecasting sustainment requirements over the next ten years.




## 10 Year FCI Forecast by Investment Scenario

The chart below illustrates the effect of various investment levels on the building FCI for the next 10 years. The levels of investment shown below include:

- Current FCI: a variable investment amount based on renewing expired systems to maintain the current FCI for the building
- 2% Investment: an annual investment of 2% of the replacement value of the building, escalated for inflation
- 4% Investment: an annual investment of 4% of the replacement value of the building, escalated for inflation


**Facility Investment vs. FCI Forecast**



Year	Investment Amount Current FCI - 0.32%	2% Investment		4% Investment	
		Amount	FCI	Amount	FCI
2016	\$0	\$1,035,280.00	-1.68 %	\$2,070,561.00	-3.68 %
2017	\$0	\$1,066,339.00	-3.68 %	\$2,132,678.00	-7.68 %
2018	\$0	\$1,098,329.00	-5.68 %	\$2,196,658.00	-11.68 %
2019	\$0	\$1,131,279.00	-7.68 %	\$2,262,558.00	-15.68 %
2020	\$1,660,744	\$1,165,217.00	-6.83 %	\$2,330,434.00	-16.83 %
2021	\$0	\$1,200,174.00	-8.83 %	\$2,400,347.00	-20.83 %
2022	\$0	\$1,236,179.00	-10.83 %	\$2,472,358.00	-24.83 %
2023	\$0	\$1,273,264.00	-12.83 %	\$2,546,529.00	-28.83 %
2024	\$0	\$1,311,462.00	-14.83 %	\$2,622,924.00	-32.83 %
2025	\$2,007,192	\$1,350,806.00	-13.86 %	\$2,701,612.00	-33.86 %
<b>Total:</b>	<b>\$3,667,935</b>	<b>\$11,868,329.00</b>		<b>\$23,736,659.00</b>	

## Deficiency Summary by System


Current deficiencies included assemblies that have reached or exceeded their design life or components of the assemblies that are in need of repair. Assemblies that have reached their design life are identified as current deficiencies and assigned the distress 'Beyond Useful Life'. The following chart lists all current deficiencies associated with this facility.



**Budget Estimate Total: \$160,786.39**

## Deficiency Summary by Priority

The following chart shows the total repair costs broken down by priority. Assessors assigned deficiencies within eCOMET to one of the following priority categories:



**Budget Estimate Total: \$160,786.39**




## Deficiency By Priority Investment Table

The table below shows the current investment cost grouped by deficiency priority and building system.

System Code	System Description	1 - Response Time (< 2 yr)	2 - Response Time (2-3 yrs)	3 - Response Time (3-4 yrs)	4 - Response Time (4-5 yrs)	5 - Response Time (> 5 yrs)	Total
B3010130	Preformed Metal Roofing	\$0.00	\$3,202.08	\$0.00	\$0.00	\$0.00	\$3,202.08
D5030	Communications and Security	\$0.00	\$0.00	\$0.00	\$157,584.31	\$0.00	\$157,584.31
	<b>Total:</b>	\$0.00	\$3,202.08	\$0.00	\$157,584.31	\$0.00	\$160,786.39

## Deficiency Summary by Category

The following chart shows the total repair costs broken down by deficiency categories. Assessors assigned deficiencies to one of the following categories:



## Deficiency Details by Priority

The deficiency detail notes listed below provide additional information on identified deficiencies found within the facility.

### Priority 2 - Response Time (2-3 yrs):

#### **System: B3010130 - Preformed Metal Roofing**



**Location:** Exterior

**Distress:** Failing

**Category:** 3 - Operations / Maint.

**Priority:** 2 - Response Time (2-3 yrs)

**Correction:** Rain gutter replacement - select the type of material and number of mitres

**Qty:** 84.00

**Unit of Measure:** L.F.

**Estimate:** \$3,202.08

**Assessor Name:** Wlodek Pieczonka

**Date Created:** 01/25/2016

**Notes:** Repair flashing on standing seam metal roof above kindergarten classrooms

---

**Priority 4 - Response Time (4-5 yrs):**

**System: D5030 - Communications and Security**



**Location:** throughout the building

**Distress:** Inadequate

**Category:** 4 - Capital Improvement

**Priority:** 4 - Response Time (4-5 yrs)

**Correction:** Add/Replace Clock System or Components

**Qty:** 0.00

**Unit of Measure:** Ea.

**Estimate:** \$157,584.31

**Assessor Name:** Wlodek Pieczonka

**Date Created:** 12/16/2015

**Notes:** Install an upgraded Clock System with enough capacity to provide clocks for the entire building.

Note: A multiplier of 1.4 was used (instead of 1.0) to cover the additional cost of other related construction.

---

## Equipment Inventory

The following table represents the inventory details of the inventory found in the building, which fall under the following subsystems:

Subsystem	Inventory	Qty	UoM	Location	Manufacturer	Model Number	Serial Number	Barcode	Life	Install Date	Next Renewal	Raw Cost	Inventory Cost
D1010 Elevators and Lifts	Hydraulic, passenger elevator, 3000 lb, 2 floors, 100 FPM	1.00	Ea.	building interior					30	2010	2040	\$73,815.00	\$81,196.50
D3020 Heat Generating Systems	Boiler, gas/oil combination, cast iron, steam, gross output, 2700 MBH, includes burners, controls and insulated jacket, packaged	2.00	Ea.	Mechanical Room 168A	HB Smith	28HE-S/W-10			35	2010	2045	\$50,376.70	\$110,828.74
D3020 Heat Generating Systems	Boiler, gas/oil combination, cast iron, steam, gross output, 2700 MBH, includes burners, controls and insulated jacket, packaged	2.00	Ea.	Mechanical Room 168A	HB Smith	28HE-S/W-10			35	2010	2045	\$50,376.70	\$110,828.74
D3030 Cooling Generating Systems	Cooling tower, packaged unit, galvanized steel, blow through, centrifugal type, 200 ton, includes standard controls, excludes pumps and piping	2.00	Ea.	Roof	Evapco	LSTB 5-512	8-354196		18	2010	2028	\$34,884.30	\$76,745.46
D3030 Cooling Generating Systems	Cooling tower, packaged unit, galvanized steel, blow through, centrifugal type, 200 ton, includes standard controls, excludes pumps and piping	2.00	Ea.	Roof	Evapco	LSTB 5-512	8-354195		18	2010	2028	\$34,884.30	\$76,745.46
D3030 Cooling Generating Systems	Water chiller, screw liquid chiller, packaged unit, water cooled, 200 ton, includes standard controls, excludes water tower	2.00	Ea.	Mechanical Room 168A	Carrier	30HXC206RZ-661BA	4509Q17993		20	2010	2030	\$114,064.50	\$250,941.90
D3030 Cooling Generating Systems	Water chiller, screw liquid chiller, packaged unit, water cooled, 200 ton, includes standard controls, excludes water tower	2.00	Ea.	Mechanical Room 168A	Carrier	30HXC206RZ-661BA	4509Q17993		20	2010	2030	\$114,064.50	\$250,941.90
D3040 Distribution Systems	Air handling unit, packaged weatherproof, with cooling/heating coil section, filters, mixing box, constant volume, single zone, 10,000 CFM, cooling coils may be chilled water or DX, heating coils may be hot water, steam or electric	1.00	Ea.	Roof	Annex Air	ERP-E-07-HW05-C-H	1463-01-0110		25	2010	2035	\$69,052.50	\$75,957.75
D3040 Distribution Systems	Air handling unit, packaged weatherproof, with cooling/heating coil section, filters, mixing box, constant volume, single zone, 15,000 CFM, cooling coils may be chilled water or DX, heating coils may be hot water, steam or electric	1.00	Ea.	Roof	Racan Carrier	A2D-58/74-DO	702072-001		25	2010	2035	\$99,742.50	\$109,716.75
D3040 Distribution Systems	Air-handling unit, built-up, horizontal or vertical, blow-thru fan, multizone, 7500 CFM, with cooling/heating coil section, filters, mixing box	3.00	Ea.	Mechanical Room 119	Carrier	39MN17C011 L2	4609U24727		25	2010	2035	\$20,153.10	\$66,505.23
D3040 Distribution Systems	Air-handling unit, built-up, horizontal or vertical, blow-thru fan, multizone, 7500 CFM, with cooling/heating coil section, filters, mixing box	3.00	Ea.	Mechanical Room 219	Carrier	39MN17C011 L2	4609U24731		25	2010	2035	\$20,153.10	\$66,505.23
D3040 Distribution Systems	Air-handling unit, built-up, horizontal or vertical, blow-thru fan, multizone, 7500 CFM, with cooling/heating coil section, filters, mixing box	3.00	Ea.	Mechanical Room 119	Carrier	39MN17C011 L2	4609U24720		25	2010	2035	\$20,153.10	\$66,505.23

# Site Assessment Report - B544001;Willard

D3040 Distribution Systems	Pump, circulating, cast iron, base mounted, coupling guard, bronze impeller, flanged joints, 10 H.P., to 600 GPM, 5" size	4.00	Ea.	Mechanical Room 168A	Bell and Gossett	1510 BF	C094726-04K90		25	2010	2035	\$19,608.00	\$86,275.20
D3040 Distribution Systems	Pump, circulating, cast iron, base mounted, coupling guard, bronze impeller, flanged joints, 10 H.P., to 600 GPM, 5" size	2.00	Ea.	Mechanical Room 168A	Bell and Gossett	1510 BF	C094722-02K90		25	2010	2035	\$19,608.00	\$43,137.60
D3040 Distribution Systems	Pump, circulating, cast iron, base mounted, coupling guard, bronze impeller, flanged joints, 10 H.P., to 600 GPM, 5" size	4.00	Ea.	Mechanical Room 168A	Bell and Gossett	1510 BF	C094726-01K90		25	2010	2035	\$19,608.00	\$86,275.20
D3040 Distribution Systems	Pump, circulating, cast iron, base mounted, coupling guard, bronze impeller, flanged joints, 10 H.P., to 600 GPM, 5" size	4.00	Ea.	Mechanical Room 168A	Bell and Gossett	1510 BF	C094726-03K90		25	2010	2035	\$19,608.00	\$86,275.20
D3040 Distribution Systems	Pump, circulating, cast iron, base mounted, coupling guard, bronze impeller, flanged joints, 10 H.P., to 600 GPM, 5" size	4.00	Ea.	Mechanical Room 168A	Bell and Gossett	1510 BF	C094726-02K90		25	2010	2035	\$19,608.00	\$86,275.20
D3040 Distribution Systems	Pump, circulating, cast iron, base mounted, coupling guard, bronze impeller, flanged joints, 10 H.P., to 600 GPM, 5" size	2.00	Ea.	Mechanical Room 168A	Bell and Gossett	1510 BF	C094722-01K90		25	2010	2035	\$19,608.00	\$43,137.60
D3040 Distribution Systems	Pump, circulating, cast iron, base mounted, coupling guard, bronze impeller, flanged joints, 10 H.P., to 600 GPM, 5" size	2.00	Ea.	Mechanical Room 168A	Bell and Gossett	1510 BF	C094724-02L90		25	2010	2035	\$19,608.00	\$43,137.60
D3040 Distribution Systems	Pump, circulating, cast iron, base mounted, coupling guard, bronze impeller, flanged joints, 10 H.P., to 600 GPM, 5" size	2.00	Ea.	Mechanical Room 168A	Bell and Gossett	1510 BF	C094724-01L90		25	2010	2035	\$19,608.00	\$43,137.60
D5010 Electrical Service/Distribution	Load interrupter switch, 2 position, 400 kVA & above, 13.8 kV, 600 amp w/CLF fuses, NEMA 1	1.00	Ea.	electrical room					30	2010	2040	\$42,849.00	\$47,133.90
D5010 Electrical Service/Distribution	Motor control center, structures, 22,000 rms, takes any combination of starters, 600 amp, up to 72" high	4.00	Ea.	electrical room					30	2010	2040	\$3,663.90	\$16,121.16
D5010 Electrical Service/Distribution	Switchboards, distribution section, aluminum bus bars, 4 W, 120/208 or 277/480 V, 1600 amp, excl breakers	3.00	Ea.	electrical room					30	2010	2040	\$7,358.85	\$24,284.21
D5010 Electrical Service/Distribution	Switchboards, no main disconnect, 4 wire, 277/480 V, 3000 amp, incl CT compartment, excl CT's or PT's	1.00	Ea.	electrical room					30	2010	2040	\$12,792.60	\$14,071.86
D5090 Other Electrical Systems	Generator set, diesel, 3 phase 4 wire, 277/480 V, 125 kW, incl battery, charger, muffler, & day tank, excl conduit, wiring, & concrete	1.00	Ea.	electrical room					30	2010	2040	\$50,797.80	\$55,877.58
												<b>Total:</b>	<b>\$2,018,558.80</b>

## Executive Summary

Building condition is evaluated based on the functional systems and elements of a building and organized according to the UNIFORMAT II Elemental Classification. The grouping of these systems and elements and applying a current replacement value to them develops a representative building cost model. Cost Models are developed for similar building types and functions. Systems and their elements are evaluated based on their current replacement values, life cycles, installation dates and next renewal dates. Systems and their elements that are within their useful lives are further evaluated to identify current deficient conditions that may have a significant impact on a system's or element's remaining service life, and to determine if they are beyond their predicted expected life. The system's or element's current replacement value is based on RS Means Commercial Cost Data.

Following are the cost model's system details for this facility. The Replacement Value is the amount needed to replace the property of the same present value. The Current Repair Amount, also known as Condition Needs, represents the budgeted contractor installed costs plus owner's soft costs for the repair, replacement or renewal for a component or system level deficiency. It excludes contributing costs for other components or systems that might also be associated with the corrective actions due to packaging the work. Facility Condition Index (FCI) FCI is an industry-standard measurement of facility condition calculated as the ratio of the costs to correct a facility's deficiencies to the facility's Current Replacement Value. It ranges from 0% (new) to 100% (very poor). Condition Index (CI) is calculated as the sum of a renewable system's Remaining Service Life (RSL) divided by the sum of a system's Replacement Value (both values exclude soft-cost to simplify calculation updates) expressed as a percentage ranging from 100% (new) to 0% (expired).

Function:	
Gross Area (SF):	133,500
Year Built:	2010
Last Renovation:	
Replacement Value:	\$2,172,837
Repair Cost:	\$81,552.95
Total FCI:	3.75 %
Total RSLI:	82.07 %



### Description:

### Attributes:

#### General Attributes:

Bldg ID:	S544001	Site ID:	S544001
----------	---------	----------	---------

## Condition Summary

The Table below shows the CI and FCI for each major building system shown at the UNIFORMAT classification Level II. Note that Systems with lower FCIs require less investment than systems with higher FCIs.

UNIFORMAT Classification	RSLI %	FCI %	Current Repair Cost
G20 - Site Improvements	81.60 %	5.12 %	\$81,552.95
G40 - Site Electrical Utilities	83.33 %	0.00 %	\$0.00
<b>Totals:</b>	<b>82.07 %</b>	<b>3.75 %</b>	<b>\$81,552.95</b>



## Condition Detail

This section of the report contains results of the Facility Condition Assessment. The building is separated into system components based on UNIFORMAT II classification. The columns in the System Listing table below represent the following:

1. System Code: A code that identifies the system.
2. System Description: A brief description of a system present in the building.
3. Unit Price \$: The unit price of the system.
4. UoM: The unit of measure for of the system.
5. Qty: The quantity for the system
6. Life: anticipated service life for thesystem based on Building Owners and Managers Association (BOMA) recommendations.
7. Year Installed: The date of system installation.
8. Calc Next Renewal Year: The date of system expiration based on the life, NR stands for non renewable.
9. Next Renewal Year: The suggested system expiration date by the assessor based on visual inspection.
10. CI: The Condition Index of the system.
11. FCI: The Facility Condition Index of the system.
12. RSL: Remaining Service Life.
13. eCR: eCOMET Condition Rating (not used).
14. Deficiency \$: The financial investment to repair/replace system.

## System Listing

The System Listing table below lists each of the systems organized by their UNIFORMAT II classification. The assessment team was tasked with recording the most recent replacement year of each system, determining the remaining service life based on the theoretical life, and evaluating the condition to confirm the forecast next replacement year. The system listing is the basis for all data contained in the Building Assessment Report.

Additionally, a condition rating (eCR) based on the following guidelines is provided as observed at the time of the assessment.

- Excellent (E) - No noticeable distress or damage. The entire system is free from observable defect.
- Very Good (VG) - Overall no serviceability reduction for the entire system. No degradation of critical components and minor distress and defect noticeable for some but not non critical components within the system.
- Good (G) - Slight or no serviceability reduction for the entire system. There may be noticeable defects for some non critical components and slight noticeable degradation of the critical components.
- Fair (F) - Overall serviceability is degraded but adequate. There may be moderate deterioration for very few of the critical components and few of the non critical components may have severe degradation.
- Marginal (MA) - Overall serviceability and reliability loss. Most if not all of the non critical components suffer from severe degradation and a few of the critical component may have severe degradation.
- Moderate (MO) - Overall a significant serviceability loss. Most if not all the components have severe degradation with the reminder of the component showing visible distress.
- Very Poor (VP) - Overall the system is barely functional. All of the components are severely degraded.
- Non-Functional (NF) - Overall the system does not function with all the components having no serviceability and suffer from severe degradation.

System Code	System Description	Unit Price \$	UoM	Qty	Life	Year Installed	Calc Next Renewal Year	Next Renewal Year	RSLI%	FCI%	RSL	eCR	Deficiency \$	Replacement Value \$
G2010	Roadways	\$11.52	S.F.		30	2010	2040		83.33 %	0.00 %	25			\$0
G2020	Parking Lots	\$7.65	S.F.	46,600	30	2010	2040		83.33 %	0.38 %	25		\$1,364.65	\$356,490
G2030	Pedestrian Paving	\$11.52	S.F.	42,000	40	2010	2050		87.50 %	0.00 %	35			\$483,840
G2040	Site Development	\$4.36	S.F.	133,500	25	2010	2035		80.00 %	0.00 %	20			\$582,060
G2050	Landscaping & Irrigation	\$3.78	S.F.	44,900	15	2010	2025		66.67 %	47.25 %	10		\$80,188.30	\$169,722
G4020	Site Lighting	\$3.58	S.F.	133,500	30	2010	2040	2040	83.33 %	0.00 %	25			\$477,930
G4030	Site Communications & Security	\$0.77	S.F.	133,500	30	2010	2040	2040	83.33 %	0.00 %	25			\$102,795
<b>Total</b>									<b>82.07 %</b>	<b>3.75 %</b>			<b>\$81,552.95</b>	<b>\$2,172,837</b>

## System Notes

The facility description in the site executive summary contains an overview of each system. The notes listed below provide additional information on select systems found within the facility.

No data found for this asset

## Renewal Schedule

eCOMET forecasts future Capital Renewal funding needed to address expiring systems based on the Next Renewal year found in the Cost Models. A 3% annual inflation factor is applied to the costs for systems expiring in future years. The table below reflects recommended Capital Renewal funding needs over the next 10 years. Note: Cells with a zero value indicate systems for which renewal is not scheduled in that year.


*Inflation Rate: 3%*

System	Current Deficiencies	2016	2017	2018	2019	2020	2021	2022	2023	2024	2025	Total
<b>Total:</b>	\$81,553	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$250,901	\$332,454
G - Building Sitework	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G20 - Site Improvements	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G2010 - Roadways	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G2020 - Parking Lots	\$1,365	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$1,365
G2030 - Pedestrian Paving	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G2040 - Site Development	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G2050 - Landscaping & Irrigation	\$80,188	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$250,901	\$331,089
G40 - Site Electrical Utilities	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G4020 - Site Lighting	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G4030 - Site Communications & Security	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0

*\* Indicates non-renewable system*

## Forecasted Sustainment Requirement

The following chart shows the current building deficiencies and forecasting sustainment requirements over the next ten years.




## 10 Year FCI Forecast by Investment Scenario

The chart below illustrates the effect of various investment levels on the building FCI for the next 10 years. The levels of investment shown below include:

- Current FCI: a variable investment amount based on renewing expired systems to maintain the current FCI for the building
- 2% Investment: an annual investment of 2% of the replacement value of the building, escalated for inflation
- 4% Investment: an annual investment of 4% of the replacement value of the building, escalated for inflation


**Facility Investment vs. FCI Forecast**



Year	Investment Amount Current FCI - 3.75%	2% Investment		4% Investment	
		Amount	FCI	Amount	FCI
2016	\$0	\$44,760.00	1.75 %	\$89,521.00	-0.25 %
2017	\$0	\$46,103.00	-0.25 %	\$92,207.00	-4.25 %
2018	\$0	\$47,486.00	-2.25 %	\$94,973.00	-8.25 %
2019	\$0	\$48,911.00	-4.25 %	\$97,822.00	-12.25 %
2020	\$0	\$50,378.00	-6.25 %	\$100,757.00	-16.25 %
2021	\$0	\$51,890.00	-8.25 %	\$103,779.00	-20.25 %
2022	\$0	\$53,446.00	-10.25 %	\$106,893.00	-24.25 %
2023	\$0	\$55,050.00	-12.25 %	\$110,099.00	-28.25 %
2024	\$0	\$56,701.00	-14.25 %	\$113,402.00	-32.25 %
2025	\$250,901	\$58,402.00	-7.65 %	\$116,804.00	-27.65 %
<b>Total:</b>	<b>\$250,901</b>	<b>\$513,127.00</b>		<b>\$1,026,257.00</b>	

## Deficiency Summary by System


Current deficiencies included assemblies that have reached or exceeded their design life or components of the assemblies that are in need of repair. Assemblies that have reached their design life are identified as current deficiencies and assigned the distress 'Beyond Useful Life'. The following chart lists all current deficiencies associated with this facility.



**Budget Estimate Total: \$81,552.95**

## Deficiency Summary by Priority

The following chart shows the total repair costs broken down by priority. Assessors assigned deficiencies within eCOMET to one of the following priority categories:



**Budget Estimate Total: \$81,552.95**




## Deficiency By Priority Investment Table

The table below shows the current investment cost grouped by deficiency priority and building system.

System Code	System Description	1 - Response Time (< 2 yr)	2 - Response Time (2-3 yrs)	3 - Response Time (3-4 yrs)	4 - Response Time (4-5 yrs)	5 - Response Time (> 5 yrs)	Total
G2020	Parking Lots	\$0.00	\$0.00	\$0.00	\$1,364.65	\$0.00	\$1,364.65
G2050	Landscaping & Irrigation	\$0.00	\$0.00	\$0.00	\$0.00	\$80,188.30	\$80,188.30
	<b>Total:</b>	\$0.00	\$0.00	\$0.00	\$1,364.65	\$80,188.30	\$81,552.95

### Deficiency Summary by Category

The following chart shows the total repair costs broken down by deficiency categories. Assessors assigned deficiencies to one of the following categories:



## Deficiency Details by Priority

The deficiency detail notes listed below provide additional information on identified deficiencies found within the facility.

### Priority 4 - Response Time (4-5 yrs):

#### System: G2020 - Parking Lots



**Location:** Grounds

**Distress:** Accessibility

**Category:** 2 - Code Compliance

**Priority:** 4 - Response Time (4-5 yrs)

**Correction:** Stripe parking stalls, install parking bumpers, provide handicap symbol and handicap post mounted sign - insert proper quantities in estimate

**Qty:** 2.00

**Unit of Measure:** Ea.

**Estimate:** \$1,364.65

**Assessor Name:** Wlodek Pieczonka

**Date Created:** 01/25/2016

**Notes:** Stripe 2 accessible parking spaces and aisle on staff parking; install signage

---

**Priority 5 - Response Time (> 5 yrs):**

**System: G2050 - Landscaping & Irrigation**



**Location:** Grounds

**Distress:** Damaged

**Category:** 3 - Operations / Maint.

**Priority:** 5 - Response Time (> 5 yrs)

**Correction:** Remove and replace or replace sod

**Qty:** 5,400.00

**Unit of Measure:** S.F.

**Estimate:** \$80,188.30

**Assessor Name:** Wlodek Pieczonka

**Date Created:** 01/25/2016

**Notes:** Re-sod grass section on the north side of the building

---

## Equipment Inventory

The following table represents the inventory details of the inventory found in the building, which fall under the following subsystems:

No data found for this asset

## Glossary

ABMA	American Boiler Manufacturers Association <a href="http://www.abma.com/">http://www.abma.com/</a>
ACEEE	American Council for an Energy-Efficient Economy
ACGIH	American Council of Governmental and Industrial Hygienists
AEE	Association of Energy Engineers
AFD	Adjustable Frequency Drive
AFTC	After Tax Cash Flow
AGA	American Gas Association
AHU	Air Handling Unit
Amp	Ampere
ANSI	American National Standards Institute
ARI	Air Conditioning and Refrigeration Institute
ASD	Adjustable Speed Drive
ASHRAE	American Society of Heating Refrigerating and Air-Conditioning Engineers Inc.
ASME	American Society of Mechanical Engineers
Assessment	Visual survey of a facility to determine its condition. It involves looking at the age of systems reviewing information from local sources and visual evidence of potential problems to assign a condition rating. It does not include destructive testing of materials or testing of systems or equipment for functionality.
ATS	After Tax Savings
AW	Annual worth
BACNET	Building Automation Control Network
BAS	Building Automation System
BCR	Benefit Cost Ratio
BEP	Business Energy Professional (AEE)
BF	Ballast Factor
BHP	Boiler Horsepower (boilers)
BHP	Brake Horsepower (motors)
BLCC	Building Life Cycle Cost analysis program (FEMP)
BOCA	Building Officials and Code Administrators
BTCF	Before Tax Cash Flow

## Site Assessment Report - S544001;Willard

---

BTS	Before Tax Savings
Btu	British thermal unit
Building Addition	An area space or component of a building added to a building after the original building's year built date.
CAA	Clean Air Act
CAAA-90	Clean Air Act Amendments of 1990
CABO	Council of American Building Officials
CAC	Conventional Air Conditioning
CADDET	Center for the Analysis and Dissemination of Demonstrated Energy Technologies
Calculated Next Renewal	The year a system or element would be expected to expire based solely on the date it was installed and the expected useful lifetime for that kind of system.
Capital Renewal	Capital renewal is condition work (excluding suitability and energy audit work) that includes the replacement of building systems or elements (as they become obsolete or beyond their useful life) not normally included in an annual operating budget. Calculated next renewal The year a system or element would be expected to expire based solely on the date it was installed and the expected useful lifetime for that kind of system. Next renewal The assessor adjusted expected useful life of a system or element based on on-site inspection.
CDD	Cooling Degree Days
CDGP	Certified Distributed Generation Professional
CEC	California Energy Commission
CEM	Certified Energy Manager
CEP	Certified Energy Procurement Professional
CFC	Chlorofluorocarbon
CFD	Cash Flow Diagram
CFL	Compact Fluorescent Light
CFM cfm	Cubic Feet per Minute
CHP	Combined Heat and Power (a.k.a. cogeneration)
CHW	Chilled Water
Condition	Condition refers to the state of physical fitness or readiness of a facility system or system element for its intended use.
COP	Coefficient of Performance
Cp	Heat Capacity of Material
CPUC	California Public Utility Commission
CRI	Color Rendering Index
CRT	Cathode Ray Tube VDT HMI

## Site Assessment Report - S544001;Willard

---

CTC	Competitive Transition Charge
Cu	Coefficient of Utilization
Current Replacement Value (CRV)	CRV represents the hypothetical total cost of rebuilding or replacing an existing facility in current dollars to its optimal condition (excluding auxiliary facilities) under current codes and construction standards.
Cv	Value Coefficient
CWS	Chilled Water System
D d	Distance (usually feet)
DB	Dry Bulb
DCV	Demand Control Ventilation
DD	Degree Day
DDB	Double Declining Balance
DDC	Direct Digital Controls
Deferred maintenance	Deferred maintenance is condition work (excluding suitability and energy audit needs) deferred on a planned or unplanned basis to a future budget cycle or postponed until funds are available.
Deficiency	A deficiency is a repair item that is damaged missing inadequate or insufficient for an intended purpose.
Delta	Difference
Delta P	Pressure Difference
Delta T	Temperature Difference
DG	Distributed Generation
DOE	Department of Energy
DP	Dew Point
DR	Demand Response
DX	Direct Expansion Air Conditioner
EA	Energy Audit
EBITDA	Earnings before Interest Taxes Depreciation and Amortization
ECI	Energy Cost Index
ECM	Energy Conservation Measure
ECO	Energy Conservation Opportunity
ECPA	Energy Conservation and Production Act
ECR	Energy Conservation Recommendation
ECS	Energy Control System



## Site Assessment Report - S544001;Willard

---

EER	Energy Efficiency Ratio
EERE	Energy Efficiency and Renewable Energy division of US DOE
EIA	Energy Information Agency
EIS	Energy Information System
EMCS	Energy Management Computer System
EMO	Energy Management Opportunity
EMP	Energy Management Project
EMR	Energy Management Recommendation
EMS	Energy Management System
Energy Utilization Index (EUI)	EUI is the measure of total energy consumed in the cooling or heating of a building in a period expressed as British thermal unit (BTU) per (cooled or heated) gross square foot.
EO	Executive Order
EPA	Environmental Protection Agency
EPACT	Energy Policy Act of 1992
EPCA	Energy Production and Conservation Act of 1975
EPRI	Electric Power Research Institute
EREN	Efficiency and Renewable Energy (Division of USDOE)
ERV	Energy Recovery Ventilator
ESCO	Energy Service Company
ESPC	Energy Savings Performance Contract
EUI	Energy Use Index
EWG	Exempt Wholesale Generators
Extended Facility Condition Index (EFCI)	EFCI is calculated as the condition needs for the current year plus facility system renewal needs going out to a set time in the future divided by Current Replacement Value.
f	Frequency
F	Fahrenheit
Facility	A facility refers to site(s) building(s) or building addition(s) or combinations thereof that provide a particular service.
Facility Condition Assessment (FCA)	FCA is a process for evaluating the condition of buildings and facilities for programming and budgetary purposes through an on site inspection and evaluation process.
Facility Condition Index (FCI)	FCI is an industry-standard measurement of a facility's condition that is the ratio of the cost to correct a facility's deficiencies to the Current Replacement Value of the facilities. The higher the FCI the poorer the condition of a facility. After an FCI is established for all buildings within a portfolio a building's condition can be ranked relative to other buildings. The FCI may also represent the condition of a portfolio based on the cumulative FCIs of the portfolio's facilities.

## Site Assessment Report - S544001;Willard

---

FC	Footcandle
FCA	Fuel Cost Adjustment
FEMIA	Federal Energy Management Improvement Act of 1988
FEMP	Federal Energy Management Program
FERC	Federal Energy Regulatory Commission
FESR	Fuel Energy Savings Ratio
FLA	Full Load Amps
FLF	Facility Load Factor (usually monthly)
FLRPM	Full Load Revolutions per Minute
FMS	Facility Management System
FPM fpm	Feet per Minute (velocity)
FSEC	Florida Solar Energy Center
Ft	Foot
GPM gpm	Gallons per Minute
GRI	Gas Research Institute
Gross Square Feet (GSF)	The size of the enclosed floor space of a building in square feet measured to the outside face of the enclosing wall.
GUI	Graphical User Interface
H h	Enthalpy Btu/lb
HCFC	Hydrochlorofluorocarbons
HDD	Heating Degree days
HFC	Hydrofluorocarbons
HHV	Higher Heating Value
HID	High Intensity Discharge (lamp)
HMI	Human Machine Interface
HMMI	Human Man Machine Interface
HO	High Output (lamp)
HP Hp hp	Horsepower
HPS	High Pressure Sodium (lamp)
HR	Humidity Ratio
Hr hr	Hour

## Site Assessment Report - S544001;Willard

---

HRU	Heat Recovery Unit
HVAC	Heating Ventilation and Air-Conditioning
Hz	Hertz
I	Intensity (lumen output of lamp)
I i	Interest rate or Discount rate
IAQ	Indoor Air Quality
ICA	International Cogeneration Alliance
ICBO	International Conference of Buildings Officials
ICC	International Code Council
ICP	Institutional Conservation Program
IECC	International Energy Conservation Code
IEEE	Institute of Electrical and Electronic Engineers
IESNA	Illuminating Engineering Society of North America
Install year	The year a building or system was built or the most recent major renovation date (where a minimum of 70 of the system's Current Replacement Value (CRV) was replaced).
IRP	Integrated Resource Planning
IRR	Internal Rate of Return
ISO	Independent System Operator
ITA	Independent Tariff Administrator
k	Kilo multiple of thousands in SI system
K	Kelvins (color temperature of lamp)
K k	Thermal Conductivity of Material
KVA	Kilovolt Ampere
KVAR	Kilovolt Ampere Reactive
kW	kiloWatt
kWh	kiloWatt hour
L	Length (usually feet)
LCC	Life Cycle Costing
LDC	Local Distribution Company
LEED	Leadership in Energy and Environmental Design
LEED EB	LEED for Existing Buildings

## Site Assessment Report - S544001;Willard

---

LEED NC	LEED for new construction
LF	Load Factor
LHV	Lower Heating Value
Life cycle	The period of time that a building or site system or element can be expected to adequately serve its intended function.
LPS	Low Pressure Sodium (lamp)
Lu	Lumen Output of a Lamp or Fixture
M	Mega multiple of millions in SI system
M&V	Measurement and Verification
MACRS	Modified Accelerated Cost Recovery System
MARR	Minimum Attractive Rate of Return
Mbtu	Thousand Btu
MCF	Thousand Cubic Feet (usually of gas)
MEC	Model Energy Code
Mm	Multiple of Thousands in I/P System
MMBtu	Million Btu
MMCS	Maintenance Management Computer System
MMI	Man Machine Interface
MMS	Maintenance Management System
MSE 2000	Management System for Energy 2000 (ANSI Georgia Tech Univ)
MW	MegaWatt
MWH MWh	MegaWatt hour
NAAQS	National Ambient Air Quality Standards
NAESCO	National Association of Energy Service Companies
NAIMA	North American Insulation Manufacturers Association
NEA	National Energy Act of 1978
NECPA	National Energy Conservation Policy Act
NEMA	National Electrical Manufacturer's Association
NERC	North American Electric Reliability Council
Next Renewal	The Next Renewal date is an override of the 'Calculated Next Renewal' date and is based upon the assessor's visual inspection.

## Site Assessment Report - S544001;Willard

---

NFPA	National Fire Protection Association
NGPA	National Gas Policy Act of 1978
NLRPM	No Load Revolutions per Minute (speed)
Nn	Equipment or Project lifetime in economic analysis
NOPR	Notice of Proposed Rule Making from FERC
NOx	Nitrogen Oxide Compounds
NPV	Net present value in economic analysis
NREL	National Renewable Energy Laboratory
NUG	Non-Utility Generator
O&M	Operation and Maintenance
OA	Outside Air
ODP	Ozone Depletion Potential
OPAC	Off-Peak Air Conditioning
P	Present value in economic analysis
PBR	Performance Based Rates
PEA	Preliminary Energy Audit
PF	Power Factor
PID	Proportional plus integral plus derivative (control system)
PM	Portfolio Manager in Energy Star rating system
PM	Preventive Maintenance
PoolCo	Power Pool Company or Organization
POU	Point of Use
PQ	Power Quality
PSC	Public Service Commission
PSIA psia	Pounds per square inch absolute (pressure)
PSIG psig	Pounds per square inch gauge (pressure)
PUC	Public Utility Commission
PUHCA	Public Utilities Holding Company Act of 1935
PURPA	Public Utilities Regulatory Policies of 1978
PV	Photovoltaic system

## Site Assessment Report - S544001;Willard

---

PV	Present Value
PW	Present Worth
PX	Power Exchange
q	Rate of heat flow in Btu per hour
Q	Heat load due to conduction using degree days
QF	Qualifying Facility
R	Electrical resistance
R	Thermal Resistance
RC	Remote controller
RCR	Room Cavity Ratio
RCRA	Resource Conservation and Recovery Act
Remaining Service Life (RSL)	RSL is the number of years service remaining for a system or equipment item. It is automatically calculated based on the difference between the current year and the 'Calculated Next Renewal' date or the 'Next Renewal' date whichever one is the later date.
Remaining Service Life Index (RSLI)	RSLI is defined as a percentage ratio of the remaining service life of a system. It usually ranges from 0 to 100
REMR	Repair Evaluation Maintenance Rehabilitation (REMR) is a scale used to objectively rank systems based on their condition
Renewal Schedule	A timeline that provides the items that need repair the year in which the repair is needed and the estimated price of the renewal.
RH	Relative Humidity
RLA	Running Load Amps
RMS	Root Mean Square
RO	Reverse Osmosis
ROI	Return on Investment
RPM	Revolutions Per Minute
RTG	Regional Transmission Group
RTO	Regional Transmission Organization
RTP	Real Time Pricing
SBCCI	Southern Building Code Congress International
SC	Scheduling Coordinator
SC	Shading Coefficient
SCADA	Supervisory Control and Data Acquisition Systems

## Site Assessment Report - S544001;Willard

---

SEER	Seasonal Energy Efficiency Ratio
SHR	Sensible Heat Ratio
Site	The grounds and utilities roadways landscaping fencing and other typical land improvements needed to support the facility.
Soft Cost	An expense item that is not considered direct construction cost. Soft cost includes architectural engineering financing legal fees and other pre-and-post construction expenses.
SOx	Sulfur Oxide Compounds
SP	Static Pressure
SP SPB	Simple Payback
SPP	Simple Payback Period
SPP	Small Power Producers
STR	Stack Temperature Rise
SV	Specific Volume
System	System refers to building and related site work elements as described by ASTM Uniformat II Classification for Building Elements (E1557-97) a format for classifying major facility elements common to most buildings. Elements usually perform a given function regardless of the design specification construction method or materials used. See also Uniformat II.
T	Temperature
T	Tubular (lamps)
TAA	Technical Assistance Audit
TCP/IP	Transmission Control Protocol/Internet Protocol
TES	Thermal Energy Storage
THD	Total Harmonic Distortion
TOD	Time of Day
TOU	Time of Use
TQM	Total Quality Management
TransCo	Transmission Company
U	Thermal Conductance
UDC	Utility Distribution Company
UL	Underwriters Laboratories
UNIFORMAT II	The ASTM UNIFORMAT II Classification for Building Elements (E1557-97) a format for classifying major facility components common to most buildings.
USGBC	US Green Building Council
v	Specific Volume

## Site Assessment Report - S544001;Willard

---

V	Volts Voltage
V	Volume
VAV	Variable Air Volume
VDT	Video Display Terminal
VFD	Variable Frequency Drive
VHO	Very High Output
VSD	Variable Speed Drive
W	Watts
W	Width
WB	Wet bulb
WH Wh	Watt Hours
Year built	The year that a building or addition was originally built based on substantial completion or occupancy.
Z	Electrical Impedance



School District of Philadelphia  
**S544101; Willard Annex**  
Final  
**Site Assessment Report**  
January 31, 2017



## Table of Contents

Site Executive Summary	4
Site Condition Summary	9
<b><u>B544101:Willard Annex</u></b>	11
Executive Summary	11
Condition Summary	12
Condition Detail	13
System Listing	14
System Notes	16
Renewal Schedule	17
Forecasted Sustainment Requirement	20
Condition Index Forecast by Investment Scenario	21
Deficiency Summary By System	22
Deficiency Summary By Priority	23
Deficiency By Priority Investment	24
Deficiency Summary By Category	25
Deficiency Details By Priority	26
Equipment Inventory Detail	32
<b><u>G544101:Grounds</u></b>	33
Executive Summary	33
Condition Summary	34
Condition Detail	35
System Listing	36
System Notes	37
Renewal Schedule	38
Forecasted Sustainment Requirement	39
Condition Index Forecast by Investment Scenario	40
Deficiency Summary By System	41
Deficiency Summary By Priority	42
Deficiency By Priority Investment	43

## Site Assessment Report

---

Deficiency Summary By Category	44
Deficiency Details By Priority	45
Equipment Inventory Detail	47
Glossary	48

## Site Executive Summary

The organization of this report, as displayed in the Table of Contents, follows the structure of the associated eCOMET database. The overall node for each school campus begins with the letter "S", which indicates the "Site" label. Each Site is comprised of separate "Building" and "Grounds" nodes; their asset names begin with the letters "B" and "G" respectively. Information rolls up to the Site node from the Building and Grounds nodes. This Site report combines facility information with subsections for the Buildings And Grounds nodes.

The basis for the evaluation of condition is the functional systems and elements of a building and grounds organized according to the UNIFORMAT II Elemental Classification. The grouping of these systems and elements and applying a current replacement value to them develops a representative building cost model. Cost Models are typically developed for similar building types and functions. Evaluation of systems and their elements takes into account their current replacement values, life cycles, installation dates and next renewal dates. Systems and their elements that are within their useful lives are further evaluated to identify current deficient conditions that may have a significant impact on a system's or element's remaining service life, and to determine if they are beyond their predicted expected life. The system's or element's current replacement value is based on RS Means Commercial Cost Data.

Following are the cost model's system details for this facility. The Replacement Value is the amount needed to replace the property of the same present value. The Current Repair Amount, also known as Condition Needs, represents the budgeted contractor installed costs plus owner's soft costs for the repair, replacement or renewal for a component or system level deficiency. It excludes contributing costs for other components or systems that might also be associated with the corrective actions due to packaging the work. Facility Condition Index (FCI) is an industry-standard measurement calculated as the ratio of the repair costs to correct a facility's deficiencies to the facility's Current Replacement Value. Condition Index (CI) for a system is calculated as the sum of the deficiencies divided by the sum of a system's Replacement Value (both values include soft-cost) expressed as a percentage ranging from 0% 100%.

Gross Area (SF):	9,510
Year Built:	1996
Last Renovation:	
Replacement Value:	\$5,761,554
Repair Cost:	\$1,501,276.16
Total FCI:	26.06 %
Total RSLI:	71.77 %



### Description:

Facility Assessment  
October, 2015

**School District of Philadelphia**  
**Willard Annex School**  
**3072 Frankford Avenue**  
**Philadelphia, PA 19134**

9,510 SF / 119 Students / LN 05

The Willard Annex school building is located at 3072 Frankford Avenue in Philadelphia, PA. The 1 story with a small partial basement and a small mezzanine, approximately 9,510 square foot building was originally constructed at unknown time; however a complete rehabilitation was conducted in 1996.

Mr. Scott Ovington, Facility Area Coordinator provided input to the Parsons assessment team on current problems and planned renovation projects. Mr. Edward Kalicki, building engineer, accompanied us on our tour of the school and provided us with as much information as he could on the building systems and recent maintenance history.

**STRUCTURAL/ EXTERIOR CLOSURE:**

The building typically rests on stone masonry foundations and bearing walls that are not showing signs of settlement or damage, although water penetration in Northwest corner of the boiler room has been reported.

The main structure consists typically of masonry load bearing walls and timber columns supporting heavy timber beams and joists, generally in good condition. Roof structure consists of sloped heavy timber trusses and purlins supporting wood plank structural deck. Floor above the basement is a concrete slab over galvanized steel structural deck.

The building envelope is typically face brick with solid brick backup. In general, masonry is in good condition except a section of west wall where mortar is missing from joints and some face brick deterioration is evident.

The original windows were replaced in 1996 with extruded aluminum fixed windows double glazed with. The windows are fitted with galvanized steel security screens. All windows and screens are generally in good condition.

The exterior doors are generally in fair condition; no weather-stripping is installed; some doors have vision glazing with security screens.

Roofing is typically built-up roofing installed in 1996 and is in good condition. No leaks have been reported. Roof openings consist of an access hatch and 12 skylights providing day light to classrooms.

Exterior doors and frames are typically hollow metal in good condition.

**INTERIORS:**

Partition wall types include primarily drywall. The interior wall finishes are generally painted drywall. Corridors have plastic panel wainscot below chair rails; toilets have ceramic tile wainscot. Generally, paint is in good condition, entire building was repainted in 2013.

Interior doors are generally solid core wood doors, some glazed in good condition, with accessible handles; doors leading to exits are hollow metal doors and frames in good condition.

Stair serving as an access to mezzanine is painted wood.

Interior identifying signage is typically applied to wall or door surfaces in poor condition; some signs are missing.

Most ceilings are exposed, painted drywall and 2x2 suspended acoustical panels in good condition.

Flooring is generally VCT with cove base in good condition (installed in 1996). Toilets and front lobby have ceramic tile flooring in good condition.

Furnishings include fixed casework in classrooms and staff lounge, generally in good condition; window shades/blinds, generally in fair condition.

**GROUNDS (SITE):**

There is neither parking nor playground at the site.

A small service yard on east side of the building is mostly dirt with weed patches. Severely deteriorated sections of concrete pavement are located in the front and rear of the yard.

**ACCESSIBILITY:**

The building does not have accessible entrance, but does have an accessible route inside. Toilets are equipped with accessible fixtures, partitions and accessories, such as grab bars. Most doors in the building have ADA required door handles.

**PLUMBING:**



## Site Assessment Report - S544101;Willard Annex

---

Plumbing Fixtures - Many of the plumbing fixtures were installed when the building was remodeled in 1996. Fixtures in the restrooms on each floor consist of both wall and floor mounted flush valve water closets and lavatories with both wheel handle and lever operated faucets. The building is equipped with several handicap accessible stalls. The fixtures are in good condition and should provide reliable service for the next 10-15 years.

Drinking fountains are stainless steel wall hung units with integral refrigerated coolers. The units appeared to be in good condition and are estimated to be within their service life. They are accessible type.

A janitor sink or mop basin is not available in this building for use by the janitorial staff.

There is a small Kitchen at Willard Annex, as all meals served are precooked. The Kitchen is equipped with a single large one-basin stainless steel sink with lever operated faucets.

Domestic Water Distribution - A 2" city water service enters the building from Frankford Avenue. The 2" meter and valves are located in the South side of the basement. Duplex reduced pressure backflow preventers are installed in parallel downstream of the water meter. The domestic hot and cold water distribution piping is copper piping with sweat fittings. The maintenance staff reports no significant problems with scale build up in the domestic piping and the supply is adequate to the fixtures, but the piping is approaching the end of its service life and should be inspected and replaced as necessary by a qualified contractor.

Two (2) Bradford White electric, 50 gallon, vertical domestic hot water heaters are installed; one (1) on the second floor and one (1) in the basement. Each heater has an associated expansion tank installed. The unit on the second floor was installed in 2015, serves the second floor, and is located in the second floor mechanical room. The unit in the basement was installed in 2007, has a circulating pump, and serves the first floor. The domestic hot water heater in the basement is approaching the end of its service life and should be replaced within the next 3-5 years.

Sanitary Waste - The sanitary sewer piping is a mixture of threaded galvanized piping and cast iron with hub and spigot fittings.

The maintenance staff reported no problems with the sanitary waste piping systems. The sewer piping has been in service for almost 20 years, is approaching the end of its service life, and will require more frequent attention from the maintenance staff as time passes. The District should hire a qualified contractor to examine the sanitary waste piping using video cameras to locate and replace any damaged piping and to further quantify the extent of potential failures.

A sewage ejector pit located in the basement mechanical room receives water from the surrounding area. It has dual submerged pumps that are of an unknown age. The system appeared to be in good condition and the pit is sealed. The Building Engineer reported no issues with the sewage ejector.

Rain Water Drainage - Rain water drains from the roof are routed through the building by PVC and cast iron piping with no hub fittings. It is estimated that this piping was installed in 1996 during the building renovation. The Building Engineer reported no problems with the rain leaders. The rain leaders should provide reliable service for the next 8-12 years.

### **MECHANICAL:**

Energy Supply - A 1-1/2" city gas service enters the building from Frankford Avenue. The gas meter is 1-1/2" and is located on the South side of the basement.

Heat Generating Systems - Building heating hot water is generated by one (1) 8.75HP Buderus Logamax Plus condensing boiler, installed in 2010, with a maximum output of 293MBH. The one (1) boiler handles the heating load in all winter weather conditions. The boiler is wall mounted in a room on the first floor and equipped with an internal burner designed to operate on natural gas. Two (2) associated circulating pumps, an air separator, and an expansion tank are installed. The Building Engineer reports no major issues with the boiler. Condensing boilers have an anticipated service life of approximately 15 years; as this unit has been in service 5 years it is within its service life.

Distribution Systems - The hot water distribution piping is black steel with threaded fittings in a two-pipe system. Hot water piping mains from the first floor level run through the building to the fin tube radiators and reheat coils in the variable air volume (VAV) boxes. The distribution piping has been in use approximately 20 years and is approaching the end of its service life. The District should hire a qualified contractor to examine the hot water distribution piping and perform additional testing to locate and replace any damaged piping and to further quantify the extent of potential failures. The District should budget for replacing this piping over the next 10 years.

## Site Assessment Report - S544101;Willard Annex

---

Two (2) air handling units (AHU) provide conditioned air for the building. AHU-1 is an electric heating and ventilation unit only and is installed on the second floor. This unit is covered in insulation and an equipment tag was not visible; the Building Engineer said this unit was installed in approximately 2010. AHU-2 is a roof mounted gas fired heating and electric cooling unit with an integral condenser. This unit is estimated to have been installed in 1996, is beyond its service life, and should be replaced. The manufacturer of this unit was not visible. VAV boxes in the six (6) classrooms, fed by building hot water, are ducted to the AHUs to provide more precise building temperatures.

Two-pipe fin tube radiators provide supplemental heating for perimeter spaces within the building. The radiators are original to the building and are within their service life. The fin tube radiators supplement the heat from the two (2) air handling units.

Only precooked meals are served in the Willard Annex and there is no cooking equipment in the building.

One (1) roof mounted exhaust fan serving the Kitchen is installed on the lower roof. One (1) roof mounted exhaust fan serving the restrooms is installed on the upper roof. The fans are operational according to the Building Engineer, but are approaching the end of their service lives and should be replaced.

Controls & Instrumentation - The temperature in the building is controlled by a single thermostat on the wall outside of the Building Engineer's office; the thermostats in the classrooms do not function. The temperature of the building is controlled by this single thermostat and is a very inefficient way to control the temperature. A new DDC control system with operable thermostats should be installed.

A new building automation system (BAS) with modern DDC modules and communications network should be installed to serve the HVAC systems in this building to improve reliability and energy efficiency. An interface should be provided with the preferred system in use throughout the District.

Sprinklers - The building is equipped with a wet type sprinkler system on the second floor and basement levels only. The first floor is not covered by the sprinkler system. The fire suppression system is estimated to have been installed in 1996 and should not need replacement within the next 15 years.

The building is not equipped with fire stand pipes.

### **ELECTRICAL:**

Site electrical service - The primary power (medium voltage) is from the street power poles feeding a pole-top transformer (PECO) and stepped down to 120V/240V, two phase. The power goes underground and feeds the main switchboard. The school's electrical service is at 400 Amp, 120V/240V, and is located in the electrical room (basement). The PECO meter (PECO) is also located inside the electrical room. The electrical service entrance and the main building electrical distribution systems are in poor condition. The electrical service has no capacity for future growth.

Distribution system - The electrical distribution is accomplished with a 120V distribution switchboard feeding the 120V panels throughout the building (two in each floor). These panels are in fair condition and do not need to be replaced for another 10 years.

Receptacles - There are adequate receptacles in classrooms, computer rooms, libraries, and other areas.

Lighting - Interior building is illuminated by various types of fixtures. They include fluorescent lights (T-5 & T-8 lamps) in majority of the areas, including; classrooms, corridor, and offices. Surface or pendant-mounted industrial fluorescent fixtures are used in mechanical and electrical rooms. The entire interior lighting fixtures are in fair condition and have not reached the end of their useful service.

Fire alarm - The present Fire Alarm system is automatic/addressable, and is in compliance with safety codes. There are manual pulls stations throughout the building. There are sufficient number of horn/strobes installed in the classrooms, corridors, offices and other areas in the school.

Telephone/LAN - The school telephone and data systems are working adequately. A Main Distribution Frame (MDF) along with a telephone PBX system provides the necessary communication function for the building. School is also equipped with Wi-Fi system.

Public address - Separate PA system does not exist. School uses the telephone systems for public announcement. This system is working adequately. The present Intercom System is functioning correctly. Each class room is provided by with intercom telephone service. The system is for paging and intercom communication between main office and classrooms, between classrooms and main

## Site Assessment Report - S544101;Willard Annex

---

office, and between classrooms to classrooms.

Clock and Program system - The present clock system is not working adequately for most part, and clocks not are controlled by central master control panel.

Television System - Television system is not provided in the school. Most classes are provided with smart boards having the ability to connect to computer and internet.

Security Systems-access control, video surveillance - The school is provided with adequate video surveillance system. Sufficient number of cameras is installed at exit doors, corridors, exterior, and other critical areas. These cameras are controlled by a Closed Circuit Television system (CCTV).

Emergency Power System - School is not provided with an emergency generator.

Emergency lighting system, including exit lighting - There is sufficient emergency lighting fixtures in corridors, and other exit ways. Exit signs and emergency fixtures are in fairly good condition with a few more years of useful service left in them.

Lightning Protection System - There is no lightning protection system installed in the school.

Grounding - The present grounding system is adequate. All equipment are properly connected and bonded to the ground.

Site Lighting – There is no site lighting installed.

Site Paging – There is no site paging installed.

### RECOMMENDATIONS:

- Repair deteriorated face brick on west wall and tuck-point
- Provide expansion joint in masonry at SE corner
- Provide new signage throughout the building
- Provide accessible ramp at the main entrance
- Provide concrete paving in service yard
- Hire a qualified contractor to perform a detailed inspection of the domestic water piping, which is approaching the end of its service life, and replace any damaged piping.
- Replace the 50 gallon, electric, vertical water heater in the basement which is approaching the end of its service life.
- Hire a qualified contractor to perform a detailed examination of the sanitary waste piping using visual inspection and video cameras to locate and replace any damaged piping and to further quantify the extent of potential failures.
- Hire a qualified contractor to examine the hot water distribution piping, in service for approximately 20 years, and perform additional testing to locate and replace any damaged piping and to further quantify the extent of potential failures.
- Replace AHU-2, a roof mounted gas fired heating and electric cooling unit with an integral condenser, which is beyond its service life.
- Replace the two (2) roof-mounted exhaust fans serving the Kitchen and restrooms, which are approaching the end of its service life.
- Replace the electric controls for the HVAC systems with modern DDC modules, valves and actuators to improve reliability and energy efficiency. Provide a new building automation system (BAS) with communication interface to the preferred system in use throughout the District.
- Install an upgraded clock system with enough capacity to provide clocks for the entire building
- Install a new emergency generator on a pad in the service yard.

### Attributes:

#### General Attributes:

Active:	Open	Bldg Lot Tm:	Lot 3 / Tm 4
Status:	Accepted by SDP	Team:	Tm 4
Site ID:	S544101		



## Site Condition Summary

The Table below shows the CI and FCI for each major system shown at the UNIFORMAT classification Level II. Note that Systems with lower FCIs require less investment than systems with higher FCIs.


### Current Investment Requirement and Condition by Uniformat Classification

UNIFORMAT Classification	RSLI%	FCI %	Current Repair
A10 - Foundations	81.00 %	0.00 %	\$0.00
A20 - Basement Construction	81.00 %	0.00 %	\$0.00
B10 - Superstructure	81.00 %	0.00 %	\$0.00
B20 - Exterior Enclosure	70.60 %	5.98 %	\$26,464.73
B30 - Roofing	110.00 %	0.00 %	\$0.00
C10 - Interior Construction	71.15 %	3.12 %	\$6,772.81
C20 - Stairs	81.00 %	0.00 %	\$0.00
C30 - Interior Finishes	56.91 %	0.00 %	\$0.00
D20 - Plumbing	53.86 %	38.64 %	\$149,451.08
D30 - HVAC	74.35 %	101.69 %	\$1,075,747.87
D40 - Fire Protection	40.69 %	0.00 %	\$0.00
D50 - Electrical	54.15 %	33.61 %	\$203,347.24
E10 - Equipment	31.87 %	0.00 %	\$0.00
E20 - Furnishings	52.50 %	0.00 %	\$0.00
G20 - Site Improvements	45.19 %	109.37 %	\$39,492.43
G40 - Site Electrical Utilities	0.00 %	0.00 %	\$0.00
<b>Totals:</b>	<b>71.77 %</b>	<b>26.06 %</b>	<b>\$1,501,276.16</b>

### Condition Deficiency Priority

Facility Name	Gross Area (S.F.)	FCI %	1 - Response Time (< 2 yr)	2 - Response Time (2-3 yrs)	3 - Response Time (3-4 yrs)	4 - Response Time (4-5 yrs)	5 - Response Time (> 5 yrs)
B544101;Willard Annex	9,510	25.53	\$0.00	\$903,083.69	\$241,848.78	\$121,613.73	\$195,237.53
G544101;Grounds	900	109.37	\$0.00	\$0.00	\$23,383.64	\$16,108.79	\$0.00
<b>Total:</b>		<b>26.06</b>	<b>\$0.00</b>	<b>\$903,083.69</b>	<b>\$265,232.42</b>	<b>\$137,722.52</b>	<b>\$195,237.53</b>

### Deficiencies By Priority



## Executive Summary

Building condition is evaluated based on the functional systems and elements of a building and organized according to the UNIFORMAT II Elemental Classification. The grouping of these systems and elements and applying a current replacement value to them develops a representative building cost model. Cost Models are developed for similar building types and functions. Systems and their elements are evaluated based on their current replacement values, life cycles, installation dates and next renewal dates. Systems and their elements that are within their useful lives are further evaluated to identify current deficient conditions that may have a significant impact on a system's or element's remaining service life, and to determine if they are beyond their predicted expected life. The system's or element's current replacement value is based on RS Means Commercial Cost Data.

Following are the cost model's system details for this facility. The Replacement Value is the amount needed to replace the property of the same present value. The Current Repair Amount, also known as Condition Needs, represents the budgeted contractor installed costs plus owner's soft costs for the repair, replacement or renewal for a component or system level deficiency. It excludes contributing costs for other components or systems that might also be associated with the corrective actions due to packaging the work. Facility Condition Index (FCI) FCI is an industry-standard measurement of facility condition calculated as the ratio of the costs to correct a facility's deficiencies to the facility's Current Replacement Value. It ranges from 0% (new) to 100% (very poor). Condition Index (CI) is calculated as the sum of a renewable system's Remaining Service Life (RSL) divided by the sum of a system's Replacement Value (both values exclude soft-cost to simplify calculation updates) expressed as a percentage ranging from 100% (new) to 0% (expired).

Function:	Annex
Gross Area (SF):	9,510
Year Built:	1996
Last Renovation:	
Replacement Value:	\$5,725,446
Repair Cost:	\$1,461,783.73
Total FCI:	25.53 %
Total RSLI:	71.94 %

### Description:

### Attributes:

#### General Attributes:

Active:	Open	Bldg ID:	B544101
Sewage Ejector:	Yes	Status:	Accepted by SDP
Site ID:	S544101		

## Condition Summary

The Table below shows the CI and FCI for each major building system shown at the UNIFORMAT classification Level II. Note that Systems with lower FCIs require less investment than systems with higher FCIs.

UNIFORMAT Classification	RSLI %	FCI %	Current Repair Cost
A10 - Foundations	81.00 %	0.00 %	\$0.00
A20 - Basement Construction	81.00 %	0.00 %	\$0.00
B10 - Superstructure	81.00 %	0.00 %	\$0.00
B20 - Exterior Enclosure	70.60 %	5.98 %	\$26,464.73
B30 - Roofing	110.00 %	0.00 %	\$0.00
C10 - Interior Construction	71.15 %	3.12 %	\$6,772.81
C20 - Stairs	81.00 %	0.00 %	\$0.00
C30 - Interior Finishes	56.91 %	0.00 %	\$0.00
D20 - Plumbing	53.87 %	38.64 %	\$149,451.08
D30 - HVAC	74.35 %	101.69 %	\$1,075,747.87
D40 - Fire Protection	40.69 %	0.00 %	\$0.00
D50 - Electrical	54.15 %	33.61 %	\$203,347.24
E10 - Equipment	31.87 %	0.00 %	\$0.00
E20 - Furnishings	52.50 %	0.00 %	\$0.00
<b>Totals:</b>	<b>71.94 %</b>	<b>25.53 %</b>	<b>\$1,461,783.73</b>

## Condition Detail

This section of the report contains results of the Facility Condition Assessment. The building is separated into system components based on UNIFORMAT II classification. The columns in the System Listing table below represent the following:

1. System Code: A code that identifies the system.
2. System Description: A brief description of a system present in the building.
3. Unit Price \$: The unit price of the system.
4. UoM: The unit of measure for of the system.
5. Qty: The quantity for the system
6. Life: anticipated service life for thesystem based on Building Owners and Managers Association (BOMA) recommendations.
7. Year Installed: The date of system installation.
8. Calc Next Renewal Year: The date of system expiration based on the life, NR stands for non renewable.
9. Next Renewal Year: The suggested system expiration date by the assessor based on visual inspection.
10. CI: The Condition Index of the system.
11. FCI: The Facility Condition Index of the system.
12. RSL: Remaining Service Life.
13. eCR: eCOMET Condition Rating (not used).
14. Deficiency \$: The financial investment to repair/replace system.

## System Listing

The System Listing table below lists each of the systems organized by their UNIFORMAT II classification. The assessment team was tasked with recording the most recent replacement year of each system, determining the remaining service life based on the theoretical life, and evaluating the condition to confirm the forecast next replacement year. The system listing is the basis for all data contained in the Building Assessment Report.

Additionally, a condition rating (eCR) based on the following guidelines is provided as observed at the time of the assessment.

- Excellent (E) - No noticeable distress or damage. The entire system is free from observable defect.
- Very Good (VG) - Overall no serviceability reduction for the entire system. No degradation of critical components and minor distress and defect noticeable for some but not non critical components within the system.
- Good (G) - Slight or no serviceability reduction for the entire system. There may be noticeable defects for some non critical components and slight noticeable degradation of the critical components.
- Fair (F) - Overall serviceability is degraded but adequate. There may be moderate deterioration for very few of the critical components and few of the non critical components may have severe degradation.
- Marginal (MA) - Overall serviceability and reliability loss. Most if not all of the non critical components suffer from severe degradation and a few of the critical component may have severe degradation.
- Moderate (MO) - Overall a significant serviceability loss. Most if not all the components have severe degradation with the reminder of the component showing visible distress.
- Very Poor (VP) - Overall the system is barely functional. All of the components are severely degraded.
- Non-Functional (NF) - Overall the system does not function with all the components having no serviceability and suffer from severe degradation.

System Code	System Description	Unit Price \$	UoM	Qty	Life	Year Installed	Calc Next Renewal Year	Next Renewal Year	RSLT%	FCI%	RSL	eCR	Deficiency \$	Replacement Value \$
A1010	Standard Foundations	\$24.32	S.F.	9,510	100	1996	2096		81.00 %	0.00 %	81			\$231,283
A1030	Slab on Grade	\$15.51	S.F.	9,510	100	1996	2096		81.00 %	0.00 %	81			\$147,500
A2010	Basement Excavation	\$13.07	S.F.	9,510	100	1996	2096		81.00 %	0.00 %	81			\$124,296
A2020	Basement Walls	\$23.02	S.F.	9,510	100	1996	2096		81.00 %	0.00 %	81			\$218,920
B1010	Floor Construction	\$92.20	S.F.	9,510	100	1996	2096		81.00 %	0.00 %	81			\$876,822
B1020	Roof Construction	\$24.11	S.F.	9,510	100	1996	2096		81.00 %	0.00 %	81			\$229,286
B2010	Exterior Walls	\$31.22	S.F.	9,510	100	1996	2096		81.00 %	8.91 %	81		\$26,464.73	\$296,902
B2020	Exterior Windows	\$13.63	S.F.	9,510	40	1996	2036		52.50 %	0.00 %	21			\$129,621
B2030	Exterior Doors	\$1.67	S.F.	9,510	25	1996	2021		24.00 %	0.00 %	6			\$15,882
B3010105	Built-Up	\$37.76	S.F.	10,930	20	1996	2016	2037	110.00 %	0.00 %	22			\$412,717
B3010120	Single Ply Membrane	\$38.73	S.F.		20				0.00 %	0.00 %				\$0
B3010130	Preformed Metal Roofing	\$54.22	S.F.		30				0.00 %	0.00 %				\$0
B3010140	Shingle & Tile	\$38.73	S.F.		20				0.00 %	0.00 %				\$0
B3020	Roof Openings	\$0.68	S.F.	9,510	20	1996	2016	2037	110.00 %	0.00 %	22			\$6,467
C1010	Partitions	\$14.93	S.F.	9,510	100	1996	2096		81.00 %	0.00 %	81			\$141,984
C1020	Interior Doors	\$3.76	S.F.	9,510	40	1996	2036		52.50 %	0.00 %	21			\$35,758
C1030	Fittings	\$4.12	S.F.	9,510	40	1996	2036		52.50 %	17.29 %	21		\$6,772.81	\$39,181
C2010	Stair Construction	\$1.28	S.F.	9,510	100	1996	2096		81.00 %	0.00 %	81			\$12,173

Site Assessment Report - B544101;Willard Annex

System Code	System Description	Unit Price \$	UoM	Qty	Life	Year Installed	Calc Next Renewal Year	Next Renewal Year	RSLI%	FCI%	RSL	eCR	Deficiency \$	Replacement Value \$
C3010230	Paint & Covering	\$13.21	S.F.	9,510	10	2013	2023		80.00 %	0.00 %	8			\$125,627
C3010231	Vinyl Wall Covering	\$0.97	S.F.	9,510	15				0.00 %	0.00 %				\$9,225
C3010232	Wall Tile	\$2.63	S.F.	9,510	30	1996	2026		36.67 %	0.00 %	11			\$25,011
C3020411	Carpet	\$7.30	S.F.		10				0.00 %	0.00 %				\$0
C3020412	Terrazzo & Tile	\$75.52	S.F.	760	50	1996	2046		62.00 %	0.00 %	31			\$57,395
C3020413	Vinyl Flooring	\$9.68	S.F.	8,559	20	1996	2016	2037	110.00 %	0.00 %	22			\$82,851
C3020414	Wood Flooring	\$22.27	S.F.		25				0.00 %	0.00 %				\$0
C3020415	Concrete Floor Finishes	\$0.97	S.F.	190	50	1996	2046		62.00 %	0.00 %	31			\$184
C3030	Ceiling Finishes	\$20.97	S.F.	9,510	25	1996	2021		24.00 %	0.00 %	6			\$199,425
D2010	Plumbing Fixtures	\$31.58	S.F.	9,510	35	1996	2031		45.71 %	0.00 %	16			\$300,326
D2020	Domestic Water Distribution	\$2.90	S.F.	9,510	25	1996	2021	2042	108.00 %	372.74 %	27		\$102,797.37	\$27,579
D2030	Sanitary Waste	\$2.90	S.F.	9,510	25	1996	2021	2042	108.00 %	169.16 %	27		\$46,653.71	\$27,579
D2040	Rain Water Drainage	\$3.29	S.F.	9,510	30	1996	2026		36.67 %	0.00 %	11			\$31,288
D3020	Heat Generating Systems	\$18.67	S.F.	9,510	15	2010	2025		66.67 %	0.00 %	10			\$177,552
D3030	Cooling Generating Systems	\$24.48	S.F.	9,510	30	1996	2026		36.67 %	0.00 %	11			\$232,805
D3040	Distribution Systems	\$42.99	S.F.	9,510	25	1996	2021	2042	108.00 %	213.23 %	27		\$871,738.51	\$408,835
D3050	Terminal & Package Units	\$11.60	S.F.	9,510	20				0.00 %	0.00 %				\$110,316
D3060	Controls & Instrumentation	\$13.50	S.F.	9,510	20	1996	2016	2037	110.00 %	158.90 %	22		\$204,009.36	\$128,385
D4010	Sprinklers	\$8.02	S.F.	9,510	35	1996	2031		45.71 %	0.00 %	16			\$76,270
D4020	Standpipes	\$0.99	S.F.	9,510	35				0.00 %	0.00 %				\$9,415
D5010	Electrical Service/Distribution	\$9.70	S.F.	9,510	30	1996	2026	2026	36.67 %	0.00 %	11			\$92,247
D5020	Lighting and Branch Wiring	\$34.68	S.F.	9,510	20	2006	2026	2026	55.00 %	0.00 %	11			\$329,807
D5030	Communications and Security	\$12.99	S.F.	9,510	15	2011	2026	2026	73.33 %	54.24 %	11		\$67,007.01	\$123,535
D5090	Other Electrical Systems	\$6.24	S.F.	9,510	30	1996	2026	2026	36.67 %	229.75 %	11		\$136,340.23	\$59,342
E1020	Institutional Equipment	\$4.82	S.F.	9,510	35				0.00 %	0.00 %				\$45,838
E1090	Other Equipment	\$11.10	S.F.	9,510	35	1996	2031		45.71 %	0.00 %	16			\$105,561
E2010	Fixed Furnishings	\$2.13	S.F.	9,510	40	1996	2036		52.50 %	0.00 %	21			\$20,256
<b>Total</b>									<b>71.94 %</b>	<b>25.53 %</b>			<b>\$1,461,783.73</b>	<b>\$5,725,446</b>

## System Notes

The facility description in the site executive summary contains an overview of each system. The notes listed below provide additional information on select systems found within the facility.

---

<b>System:</b> C3010 - Wall Finishes	This system contains no images
<b>Note:</b> Paint 95% Ceramic tile 5%	

---

<b>System:</b> C3020 - Floor Finishes	This system contains no images
<b>Note:</b> VCT 90% Ceramic tile 8% Concrete 2%	

---

<b>System:</b> C3030 - Ceiling Finishes	This system contains no images
<b>Note:</b> Exposed/ painted 80% ACT 15% Drywall 5%	



## Renewal Schedule

eCOMET forecasts future Capital Renewal funding needed to address expiring systems based on the Next Renewal year found in the Cost Models. A 3% annual inflation factor is applied to the costs for systems expiring in future years. The table below reflects recommended Capital Renewal funding needs over the next 10 years. Note: Cells with a zero value indicate systems for which renewal is not scheduled in that year.

*Inflation Rate: 3%*

System	Current Deficiencies	2016	2017	2018	2019	2020	2021	2022	2023	2024	2025	Total
<b>Total:</b>	<b>\$1,461,784</b>	<b>\$0</b>	<b>\$0</b>	<b>\$0</b>	<b>\$0</b>	<b>\$0</b>	<b>\$282,796</b>	<b>\$0</b>	<b>\$175,055</b>	<b>\$0</b>	<b>\$262,476</b>	<b>\$2,182,111</b>
<b>* A - Substructure</b>	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
<b>* A10 - Foundations</b>	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
<b>A1010 - Standard Foundations</b>	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
<b>A1030 - Slab on Grade</b>	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
<b>* A20 - Basement Construction</b>	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
<b>A2010 - Basement Excavation</b>	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
<b>A2020 - Basement Walls</b>	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
<b>B - Shell</b>	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
<b>B10 - Superstructure</b>	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
<b>B1010 - Floor Construction</b>	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
<b>B1020 - Roof Construction</b>	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
<b>B20 - Exterior Enclosure</b>	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
<b>B2010 - Exterior Walls</b>	\$26,465	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$26,465
<b>B2020 - Exterior Windows</b>	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
<b>B2030 - Exterior Doors</b>	\$0	\$0	\$0	\$0	\$0	\$0	\$20,860	\$0	\$0	\$0	\$0	\$20,860
<b>B30 - Roofing</b>	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
<b>B3010 - Roof Coverings</b>	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
<b>B3010105 - Built-Up</b>	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
<b>B3010120 - Single Ply Membrane</b>	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
<b>B3010130 - Preformed Metal Roofing</b>	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
<b>B3010140 - Shingle &amp; Tile</b>	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
<b>B3020 - Roof Openings</b>	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
<b>C - Interiors</b>	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
<b>C10 - Interior Construction</b>	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
<b>C1010 - Partitions</b>	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0

# Site Assessment Report - B544101;Willard Annex

C1020 - Interior Doors	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C1030 - Fittings	\$6,773	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$6,773
C20 - Stairs	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C2010 - Stair Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C30 - Interior Finishes	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C3010 - Wall Finishes	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C3010230 - Paint & Covering	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$175,055	\$0	\$0	\$0	\$175,055
C3010231 - Vinyl Wall Covering	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C3010232 - Wall Tile	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C3020 - Floor Finishes	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C3020411 - Carpet	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C3020412 - Terrazzo & Tile	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C3020413 - Vinyl Flooring	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C3020414 - Wood Flooring	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C3020415 - Concrete Floor Finishes	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C3030 - Ceiling Finishes	\$0	\$0	\$0	\$0	\$0	\$0	\$261,936	\$0	\$0	\$0	\$0	\$0	\$261,936
D - Services	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D20 - Plumbing	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D2010 - Plumbing Fixtures	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D2020 - Domestic Water Distribution	\$102,797	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$102,797
D2030 - Sanitary Waste	\$46,654	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$46,654
D2040 - Rain Water Drainage	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D30 - HVAC	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D3020 - Heat Generating Systems	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$262,476	\$262,476
D3030 - Cooling Generating Systems	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D3040 - Distribution Systems	\$871,739	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$871,739
D3050 - Terminal & Package Units	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D3060 - Controls & Instrumentation	\$204,009	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$204,009
D40 - Fire Protection	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D4010 - Sprinklers	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D4020 - Standpipes	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D50 - Electrical	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5010 - Electrical Service/Distribution	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0


## Site Assessment Report - B544101;Willard Annex

D5020 - Lighting and Branch Wiring	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5030 - Communications and Security	\$67,007	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$67,007
D5090 - Other Electrical Systems	\$136,340	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$136,340
E - Equipment & Furnishings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E10 - Equipment	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E1020 - Institutional Equipment	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E1090 - Other Equipment	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E20 - Furnishings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E2010 - Fixed Furnishings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0

\* Indicates non-renewable system

## Forecasted Sustainment Requirement

The following chart shows the current building deficiencies and forecasting sustainment requirements over the next ten years.




## 10 Year FCI Forecast by Investment Scenario

The chart below illustrates the effect of various investment levels on the building FCI for the next 10 years. The levels of investment shown below include:

- Current FCI: a variable investment amount based on renewing expired systems to maintain the current FCI for the building
- 2% Investment: an annual investment of 2% of the replacement value of the building, escalated for inflation
- 4% Investment: an annual investment of 4% of the replacement value of the building, escalated for inflation


**Facility Investment vs. FCI Forecast**



Year	Investment Amount Current FCI - 25.53%	2% Investment		4% Investment	
		Amount	FCI	Amount	FCI
2016	\$0	\$117,944.00	23.53 %	\$235,888.00	21.53 %
2017	\$1,277,168	\$121,483.00	42.56 %	\$242,965.00	38.56 %
2018	\$0	\$125,127.00	40.56 %	\$250,254.00	34.56 %
2019	\$0	\$128,881.00	38.56 %	\$257,762.00	30.56 %
2020	\$0	\$132,747.00	36.56 %	\$265,494.00	26.56 %
2021	\$282,796	\$136,730.00	38.69 %	\$273,459.00	26.69 %
2022	\$0	\$140,832.00	36.69 %	\$281,663.00	22.69 %
2023	\$175,055	\$145,056.00	37.11 %	\$290,113.00	21.11 %
2024	\$0	\$149,408.00	35.11 %	\$298,816.00	17.11 %
2025	\$262,476	\$153,890.00	36.52 %	\$307,781.00	16.52 %
<b>Total:</b>	<b>\$1,997,495</b>	<b>\$1,352,098.00</b>		<b>\$2,704,195.00</b>	

## Deficiency Summary by System


Current deficiencies included assemblies that have reached or exceeded their design life or components of the assemblies that are in need of repair. Assemblies that have reached their design life are identified as current deficiencies and assigned the distress 'Beyond Useful Life'. The following chart lists all current deficiencies associated with this facility.



**Budget Estimate Total: \$1,461,783.73**

## Deficiency Summary by Priority

The following chart shows the total repair costs broken down by priority. Assessors assigned deficiencies within eCOMET to one of the following priority categories:



**Budget Estimate Total: \$1,461,783.73**

## Deficiency By Priority Investment Table


The table below shows the current investment cost grouped by deficiency priority and building system.

System Code	System Description	1 - Response Time (< 2 yr)	2 - Response Time (2-3 yrs)	3 - Response Time (3-4 yrs)	4 - Response Time (4-5 yrs)	5 - Response Time (> 5 yrs)	Total
B2010	Exterior Walls	\$0.00	\$0.00	\$26,464.73	\$0.00	\$0.00	\$26,464.73
C1030	Fittings	\$0.00	\$0.00	\$0.00	\$0.00	\$6,772.81	\$6,772.81
D2020	Domestic Water Distribution	\$0.00	\$0.00	\$0.00	\$54,606.72	\$48,190.65	\$102,797.37
D2030	Sanitary Waste	\$0.00	\$0.00	\$0.00	\$0.00	\$46,653.71	\$46,653.71
D3040	Distribution Systems	\$0.00	\$699,074.33	\$79,043.82	\$0.00	\$93,620.36	\$871,738.51
D3060	Controls & Instrumentation	\$0.00	\$204,009.36	\$0.00	\$0.00	\$0.00	\$204,009.36
D5030	Communications and Security	\$0.00	\$0.00	\$0.00	\$67,007.01	\$0.00	\$67,007.01
D5090	Other Electrical Systems	\$0.00	\$0.00	\$136,340.23	\$0.00	\$0.00	\$136,340.23
	<b>Total:</b>	\$0.00	\$903,083.69	\$241,848.78	\$121,613.73	\$195,237.53	\$1,461,783.73



## Deficiency Summary by Category

The following chart shows the total repair costs broken down by deficiency categories. Assessors assigned deficiencies to one of the following categories:



## Deficiency Details by Priority

The deficiency detail notes listed below provide additional information on identified deficiencies found within the facility.

### Priority 2 - Response Time (2-3 yrs):

#### System: D3040 - Distribution Systems



**Location:** Roof

**Distress:** Beyond Service Life

**Category:** 3 - Operations / Maint.

**Priority:** 2 - Response Time (2-3 yrs)

**Correction:** Replace Rooftop Unit (25T) and air terminals

**Qty:** 25.00

**Unit of Measure:** Ton

**Estimate:** \$699,074.33

**Assessor Name:** Craig Anding

**Date Created:** 12/18/2015

**Notes:** Replace AHU-2, a roof mounted gas fired heating and electric cooling unit with an integral condenser, which is beyond its service life.

#### System: D3060 - Controls & Instrumentation



**Location:** Throughout building

**Distress:** Inadequate

**Category:** 4 - Capital Improvement

**Priority:** 2 - Response Time (2-3 yrs)

**Correction:** Replace pneumatic controls with DDC (75KSF)

**Qty:** 9,510.00

**Unit of Measure:** S.F.

**Estimate:** \$204,009.36

**Assessor Name:** Craig Anding

**Date Created:** 12/18/2015

**Notes:** Replace the electric controls for the HVAC systems with modern DDC modules, valves and actuators to improve reliability and energy efficiency. Provide a new building automation system (BAS) with communication interface to the preferred system in use throughout the District.

**Priority 3 - Response Time (3-4 yrs):**

**System: B2010 - Exterior Walls**



**Location:** Exterior

**Distress:** Building Envelope Integrity

**Category:** 3 - Operations / Maint.

**Priority:** 3 - Response Time (3-4 yrs)

**Correction:** Repair cracks in masonry - replace missing mortar and repoint - SF of wall area

**Qty:** 720.00

**Unit of Measure:** S.F.

**Estimate:** \$23,248.42

**Assessor Name:** Craig Anding

**Date Created:** 01/26/2016

**Notes:** Repair deteriorated face brick on west wall and tuck-point

---

**System: B2010 - Exterior Walls**



**Location:** Exterior

**Distress:** Maintenance Required

**Category:** 3 - Operations / Maint.

**Priority:** 3 - Response Time (3-4 yrs)

**Correction:** Remove and replace expansion joints at exterior walls

**Qty:** 36.00

**Unit of Measure:** L.F.

**Estimate:** \$3,216.31

**Assessor Name:** Craig Anding

**Date Created:** 01/26/2016

**Notes:** Provide expansion joint in masonry at SE corner

---

**System: D3040 - Distribution Systems**



**Location:** Roof  
**Distress:** Beyond Service Life  
**Category:** 3 - Operations / Maint.  
**Priority:** 3 - Response Time (3-4 yrs)  
**Correction:** Replace utility set exhaust fan (5 HP)  
**Qty:** 2.00  
**Unit of Measure:** Ea.  
**Estimate:** \$79,043.82  
**Assessor Name:** Craig Anding  
**Date Created:** 12/18/2015

**Notes:** Replace the two (2) roof mounted exhaust fans serving the Kitchen and restrooms, which are approaching the end of its service life.

---

**System: D5090 - Other Electrical Systems**

This deficiency has no image.

**Location:** electrical room  
**Distress:** Inadequate  
**Category:** 4 - Capital Improvement  
**Priority:** 3 - Response Time (3-4 yrs)  
**Correction:** Replace standby generator system  
**Qty:** 1.00  
**Unit of Measure:** Ea.  
**Estimate:** \$136,340.23  
**Assessor Name:** Craig Anding  
**Date Created:** 12/17/2015

**Notes:** Install a new Emergency generator.  
Note: there is no picture is attached, since presently there is no Emergency Generator in the building

---

**Priority 4 - Response Time (4-5 yrs):**

**System: D2020 - Domestic Water Distribution**



**Location:** Basement

**Distress:** Beyond Service Life

**Category:** 3 - Operations / Maint.

**Priority:** 4 - Response Time (4-5 yrs)

**Correction:** Replace vertical tank type gas-fired water heater (75 gal)

**Qty:** 1.00

**Unit of Measure:** Ea.

**Estimate:** \$54,606.72

**Assessor Name:** Craig Anding

**Date Created:** 12/18/2015

**Notes:** Replace the 50 gallon, electric, vertical water heater in the basement which is approaching the end of its service life.

---

**System: D5030 - Communications and Security**



**Location:** throughout the building

**Distress:** Beyond Service Life

**Category:** 3 - Operations / Maint.

**Priority:** 4 - Response Time (4-5 yrs)

**Correction:** Add/Replace Clock System or Components

**Qty:** 0.00

**Unit of Measure:** Ea.

**Estimate:** \$67,007.01

**Assessor Name:** Craig Anding

**Date Created:** 12/17/2015

**Notes:** Install an upgraded Clock System with enough capacity to provide clocks for the entire building  
Note: a multiplier of 1.4 is used (instead of 1.0) to cover the additional cost of other related construction cost.

---

**Priority 5 - Response Time (> 5 yrs):**

**System: C1030 - Fittings**



**Location:** Interior

**Distress:** Inadequate

**Category:** 4 - Capital Improvement

**Priority:** 5 - Response Time (> 5 yrs)

**Correction:** Replace missing or damaged signage - insert the number of rooms

**Qty:** 25.00

**Unit of Measure:** Ea.

**Estimate:** \$6,772.81

**Assessor Name:** Craig Anding

**Date Created:** 01/26/2016

**Notes:** Provide new signage throughout the building

---

**System: D2020 - Domestic Water Distribution**



**Location:** Throughout building

**Distress:** Beyond Service Life

**Category:** 3 - Operations / Maint.

**Priority:** 5 - Response Time (> 5 yrs)

**Correction:** Replace domestic water piping (75 KSF)

**Qty:** 9,510.00

**Unit of Measure:** S.F.

**Estimate:** \$48,190.65

**Assessor Name:** Craig Anding

**Date Created:** 12/18/2015

**Notes:** Hire a qualified contractor to perform a detailed inspection of the domestic water piping, which is approaching the end of its service life, and replace any damaged piping.

---



**System: D2030 - Sanitary Waste**



**Location:** Throughout building

**Distress:** Beyond Service Life

**Category:** 3 - Operations / Maint.

**Priority:** 5 - Response Time (> 5 yrs)

**Correction:** Inspect sanitary waste piping and replace damaged sections. (+50KSF)

**Qty:** 9,510.00

**Unit of Measure:** S.F.

**Estimate:** \$46,653.71

**Assessor Name:** Craig Anding

**Date Created:** 12/18/2015

**Notes:** Hire a qualified contractor to perform a detailed examination of the sanitary waste piping using visual inspection and video cameras to locate and replace any damaged piping and to further quantify the extent of potential failures.

---

**System: D3040 - Distribution Systems**



**Location:** Throughout building

**Distress:** Beyond Service Life

**Category:** 3 - Operations / Maint.

**Priority:** 5 - Response Time (> 5 yrs)

**Correction:** Replace hydronic heating piping (75KSF)

**Qty:** 9,510.00

**Unit of Measure:** S.F.

**Estimate:** \$93,620.36

**Assessor Name:** Craig Anding

**Date Created:** 12/18/2015

**Notes:** Hire a qualified contractor to examine the hot water distribution piping, in service for 20 years, and perform additional testing to locate and replace any damaged piping and to further quantify the extent of potential failures.

---

## Equipment Inventory

The following table represents the inventory details of the inventory found in the building, which fall under the following subsystems:

Subsystem	Inventory	Qty	UoM	Location	Manufacturer	Model Number	Serial Number	Barcode	Life	Install Date	Next Renewal	Raw Cost	Inventory Cost
D5010 Electrical Service/Distribution	Panelboards, 3 pole 3 wire, main circuit breaker, 240 V, 225 amp	4.00	Ea.	electrical room					30	1996	2026	\$3,105.00	\$13,662.00
<b>Total:</b>												<b>\$13,662.00</b>	



## Executive Summary

Building condition is evaluated based on the functional systems and elements of a building and organized according to the UNIFORMAT II Elemental Classification. The grouping of these systems and elements and applying a current replacement value to them develops a representative building cost model. Cost Models are developed for similar building types and functions. Systems and their elements are evaluated based on their current replacement values, life cycles, installation dates and next renewal dates. Systems and their elements that are within their useful lives are further evaluated to identify current deficient conditions that may have a significant impact on a system's or element's remaining service life, and to determine if they are beyond their predicted expected life. The system's or element's current replacement value is based on RS Means Commercial Cost Data.

Following are the cost model's system details for this facility. The Replacement Value is the amount needed to replace the property of the same present value. The Current Repair Amount, also known as Condition Needs, represents the budgeted contractor installed costs plus owner's soft costs for the repair, replacement or renewal for a component or system level deficiency. It excludes contributing costs for other components or systems that might also be associated with the corrective actions due to packaging the work. Facility Condition Index (FCI) FCI is an industry-standard measurement of facility condition calculated as the ratio of the costs to correct a facility's deficiencies to the facility's Current Replacement Value. It ranges from 0% (new) to 100% (very poor). Condition Index (CI) is calculated as the sum of a renewable system's Remaining Service Life (RSL) divided by the sum of a system's Replacement Value (both values exclude soft-cost to simplify calculation updates) expressed as a percentage ranging from 100% (new) to 0% (expired).

Function:	
Gross Area (SF):	900
Year Built:	1996
Last Renovation:	
Replacement Value:	\$36,108
Repair Cost:	\$39,492.43
Total FCI:	109.37 %
Total RSLI:	45.19 %



### Description:

### Attributes:

#### General Attributes:

Bldg ID:	S544101	Site ID:	S544101
----------	---------	----------	---------

## Condition Summary

The Table below shows the CI and FCI for each major building system shown at the UNIFORMAT classification Level II. Note that Systems with lower FCIs require less investment than systems with higher FCIs.

UNIFORMAT Classification	RSLI %	FCI %	Current Repair Cost
G20 - Site Improvements	45.19 %	109.37 %	\$39,492.43
G40 - Site Electrical Utilities	0.00 %	0.00 %	\$0.00
<b>Totals:</b>	<b>45.19 %</b>	<b>109.37 %</b>	<b>\$39,492.43</b>

## Condition Detail

This section of the report contains results of the Facility Condition Assessment. The building is separated into system components based on UNIFORMAT II classification. The columns in the System Listing table below represent the following:

1. System Code: A code that identifies the system.
2. System Description: A brief description of a system present in the building.
3. Unit Price \$: The unit price of the system.
4. UoM: The unit of measure for of the system.
5. Qty: The quantity for the system
6. Life: anticipated service life for thesystem based on Building Owners and Managers Association (BOMA) recommendations.
7. Year Installed: The date of system installation.
8. Calc Next Renewal Year: The date of system expiration based on the life, NR stands for non renewable.
9. Next Renewal Year: The suggested system expiration date by the assessor based on visual inspection.
10. CI: The Condition Index of the system.
11. FCI: The Facility Condition Index of the system.
12. RSL: Remaining Service Life.
13. eCR: eCOMET Condition Rating (not used).
14. Deficiency \$: The financial investment to repair/replace system.

## System Listing

The System Listing table below lists each of the systems organized by their UNIFORMAT II classification. The assessment team was tasked with recording the most recent replacement year of each system, determining the remaining service life based on the theoretical life, and evaluating the condition to confirm the forecast next replacement year. The system listing is the basis for all data contained in the Building Assessment Report.

Additionally, a condition rating (eCR) based on the following guidelines is provided as observed at the time of the assessment.

- Excellent (E) - No noticeable distress or damage. The entire system is free from observable defect.
- Very Good (VG) - Overall no serviceability reduction for the entire system. No degradation of critical components and minor distress and defect noticeable for some but not non critical components within the system.
- Good (G) - Slight or no serviceability reduction for the entire system. There may be noticeable defects for some non critical components and slight noticeable degradation of the critical components.
- Fair (F) - Overall serviceability is degraded but adequate. There may be moderate deterioration for very few of the critical components and few of the non critical components may have severe degradation.
- Marginal (MA) - Overall serviceability and reliability loss. Most if not all of the non critical components suffer from severe degradation and a few of the critical component may have severe degradation.
- Moderate (MO) - Overall a significant serviceability loss. Most if not all the components have severe degradation with the reminder of the component showing visible distress.
- Very Poor (VP) - Overall the system is barely functional. All of the components are severely degraded.
- Non-Functional (NF) - Overall the system does not function with all the components having no serviceability and suffer from severe degradation.

System Code	System Description	Unit Price \$	UoM	Qty	Life	Year Installed	Calc Next Renewal Year	Next Renewal Year	RSLI%	FCI%	RSL	eCR	Deficiency \$	Replacement Value \$
G2010	Roadways	\$11.52	S.F.		30				0.00 %	0.00 %				\$0
G2020	Parking Lots	\$8.50	S.F.		30				0.00 %	0.00 %				\$0
G2030	Pedestrian Paving	\$23.97	S.F.	1,120	40	1996	2036		52.50 %	147.11 %	21		\$39,492.43	\$26,846
G2040	Site Development	\$8.27	S.F.	1,120	25	1996	2021		24.00 %	0.00 %	6			\$9,262
G2050	Landscaping & Irrigation	\$4.36	S.F.		15				0.00 %	0.00 %				\$0
G4020	Site Lighting	\$4.84	S.F.		30				0.00 %	0.00 %				\$0
G4030	Site Communications & Security	\$0.97	S.F.		30				0.00 %	0.00 %				\$0
<b>Total</b>									<b>45.19 %</b>	<b>109.37 %</b>			<b>\$39,492.43</b>	<b>\$36,108</b>

## System Notes

The facility description in the site executive summary contains an overview of each system. The notes listed below provide additional information on select systems found within the facility.

No data found for this asset

## Renewal Schedule

eCOMET forecasts future Capital Renewal funding needed to address expiring systems based on the Next Renewal year found in the Cost Models. A 3% annual inflation factor is applied to the costs for systems expiring in future years. The table below reflects recommended Capital Renewal funding needs over the next 10 years. Note: Cells with a zero value indicate systems for which renewal is not scheduled in that year.


*Inflation Rate: 3%*

System	Current Deficiencies	2016	2017	2018	2019	2020	2021	2022	2023	2024	2025	Total
<b>Total:</b>	\$39,492	\$0	\$0	\$0	\$0	\$0	\$12,166	\$0	\$0	\$0	\$0	\$51,659
G - Building Sitework	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G20 - Site Improvements	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G2010 - Roadways	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G2020 - Parking Lots	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G2030 - Pedestrian Paving	\$39,492	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$39,492
G2040 - Site Development	\$0	\$0	\$0	\$0	\$0	\$0	\$12,166	\$0	\$0	\$0	\$0	\$12,166
G2050 - Landscaping & Irrigation	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G40 - Site Electrical Utilities	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G4020 - Site Lighting	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G4030 - Site Communications & Security	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0

\* Indicates non-renewable system

## Forecasted Sustainment Requirement

The following chart shows the current building deficiencies and forecasting sustainment requirements over the next ten years.




## 10 Year FCI Forecast by Investment Scenario

The chart below illustrates the effect of various investment levels on the building FCI for the next 10 years. The levels of investment shown below include:

- Current FCI: a variable investment amount based on renewing expired systems to maintain the current FCI for the building
- 2% Investment: an annual investment of 2% of the replacement value of the building, escalated for inflation
- 4% Investment: an annual investment of 4% of the replacement value of the building, escalated for inflation

**Facility Investment vs. FCI Forecast**




Year	Investment Amount Current FCI - 109.37%	2% Investment		4% Investment	
		Amount	FCI	Amount	FCI
2016	\$0	\$744.00	107.37 %	\$1,488.00	105.37 %
2017	\$0	\$766.00	105.37 %	\$1,532.00	101.37 %
2018	\$0	\$789.00	103.37 %	\$1,578.00	97.37 %
2019	\$0	\$813.00	101.37 %	\$1,626.00	93.37 %
2020	\$0	\$837.00	99.37 %	\$1,674.00	89.37 %
2021	\$12,166	\$862.00	125.59 %	\$1,725.00	113.59 %
2022	\$0	\$888.00	123.59 %	\$1,776.00	109.59 %
2023	\$0	\$915.00	121.59 %	\$1,830.00	105.59 %
2024	\$0	\$942.00	119.59 %	\$1,885.00	101.59 %
2025	\$0	\$971.00	117.59 %	\$1,941.00	97.59 %
<b>Total:</b>	<b>\$12,166</b>	<b>\$8,527.00</b>		<b>\$17,055.00</b>	




## Deficiency Summary by System

Current deficiencies included assemblies that have reached or exceeded their design life or components of the assemblies that are in need of repair. Assemblies that have reached their design life are identified as current deficiencies and assigned the distress 'Beyond Useful Life'. The following chart lists all current deficiencies associated with this facility.



## Deficiency Summary by Priority

The following chart shows the total repair costs broken down by priority. Assessors assigned deficiencies within eCOMET to one of the following priority categories:



**Budget Estimate Total: \$39,492.43**


## Deficiency By Priority Investment Table

The table below shows the current investment cost grouped by deficiency priority and building system.

System Code	System Description	1 - Response Time (< 2 yr)	2 - Response Time (2-3 yrs)	3 - Response Time (3-4 yrs)	4 - Response Time (4-5 yrs)	5 - Response Time (> 5 yrs)	Total
G2030	Pedestrian Paving	\$0.00	\$0.00	\$23,383.64	\$16,108.79	\$0.00	\$39,492.43
	<b>Total:</b>	\$0.00	\$0.00	\$23,383.64	\$16,108.79	\$0.00	\$39,492.43

## Deficiency Summary by Category

The following chart shows the total repair costs broken down by deficiency categories. Assessors assigned deficiencies to one of the following categories:



## Deficiency Details by Priority

The deficiency detail notes listed below provide additional information on identified deficiencies found within the facility.

### Priority 3 - Response Time (3-4 yrs):

#### System: G2030 - Pedestrian Paving



**Location:** Grounds

**Distress:** Accessibility

**Category:** 2 - Code Compliance

**Priority:** 3 - Response Time (3-4 yrs)

**Correction:** Install an exterior ADA ramp - based on 5' wide by the linear foot - up to a 48" rise - per LF of ramp - figure 1 LF per inch of rise

**Qty:** 18.00

**Unit of Measure:** L.F.

**Estimate:** \$23,383.64

**Assessor Name:** Craig Anding

**Date Created:** 01/26/2016

**Notes:** Provide accessible ramp at the main entrance

---

**Priority 4 - Response Time (4-5 yrs):**

**System: G2030 - Pedestrian Paving**



**Location:** Grounds

**Distress:** Beyond Service Life

**Category:** 3 - Operations / Maint.

**Priority:** 4 - Response Time (4-5 yrs)

**Correction:** Remove and replace concrete sidewalk or concrete paving - 4" concrete thickness

**Qty:** 1,120.00

**Unit of Measure:** S.F.

**Estimate:** \$16,108.79

**Assessor Name:** Craig Anding

**Date Created:** 01/26/2016

**Notes:** Provide concrete paving in service yard

---

## Equipment Inventory

The following table represents the inventory details of the inventory found in the building, which fall under the following subsystems:

No data found for this asset

## Glossary

ABMA	American Boiler Manufacturers Association <a href="http://www.abma.com/">http://www.abma.com/</a>
ACEEE	American Council for an Energy-Efficient Economy
ACGIH	American Council of Governmental and Industrial Hygienists
AEE	Association of Energy Engineers
AFD	Adjustable Frequency Drive
AFTC	After Tax Cash Flow
AGA	American Gas Association
AHU	Air Handling Unit
Amp	Ampere
ANSI	American National Standards Institute
ARI	Air Conditioning and Refrigeration Institute
ASD	Adjustable Speed Drive
ASHRAE	American Society of Heating Refrigerating and Air-Conditioning Engineers Inc.
ASME	American Society of Mechanical Engineers
Assessment	Visual survey of a facility to determine its condition. It involves looking at the age of systems reviewing information from local sources and visual evidence of potential problems to assign a condition rating. It does not include destructive testing of materials or testing of systems or equipment for functionality.
ATS	After Tax Savings
AW	Annual worth
BACNET	Building Automation Control Network
BAS	Building Automation System
BCR	Benefit Cost Ratio
BEP	Business Energy Professional (AEE)
BF	Ballast Factor
BHP	Boiler Horsepower (boilers)
BHP	Brake Horsepower (motors)
BLCC	Building Life Cycle Cost analysis program (FEMP)
BOCA	Building Officials and Code Administrators
BTCF	Before Tax Cash Flow



## Site Assessment Report - S544101;Willard Annex

---

BTS	Before Tax Savings
Btu	British thermal unit
Building Addition	An area space or component of a building added to a building after the original building's year built date.
CAA	Clean Air Act
CAAA-90	Clean Air Act Amendments of 1990
CABO	Council of American Building Officials
CAC	Conventional Air Conditioning
CADDET	Center for the Analysis and Dissemination of Demonstrated Energy Technologies
Calculated Next Renewal	The year a system or element would be expected to expire based solely on the date it was installed and the expected useful lifetime for that kind of system.
Capital Renewal	Capital renewal is condition work (excluding suitability and energy audit work) that includes the replacement of building systems or elements (as they become obsolete or beyond their useful life) not normally included in an annual operating budget. Calculated next renewal The year a system or element would be expected to expire based solely on the date it was installed and the expected useful lifetime for that kind of system. Next renewal The assessor adjusted expected useful life of a system or element based on on-site inspection.
CDD	Cooling Degree Days
CDGP	Certified Distributed Generation Professional
CEC	California Energy Commission
CEM	Certified Energy Manager
CEP	Certified Energy Procurement Professional
CFC	Chlorofluorocarbon
CFD	Cash Flow Diagram
CFL	Compact Fluorescent Light
CFM cfm	Cubic Feet per Minute
CHP	Combined Heat and Power (a.k.a. cogeneration)
CHW	Chilled Water
Condition	Condition refers to the state of physical fitness or readiness of a facility system or system element for its intended use.
COP	Coefficient of Performance
Cp	Heat Capacity of Material
CPUC	California Public Utility Commission
CRI	Color Rendering Index
CRT	Cathode Ray Tube VDT HMI

## Site Assessment Report - S544101;Willard Annex

---

CTC	Competitive Transition Charge
Cu	Coefficient of Utilization
Current Replacement Value (CRV)	CRV represents the hypothetical total cost of rebuilding or replacing an existing facility in current dollars to its optimal condition (excluding auxiliary facilities) under current codes and construction standards.
Cv	Value Coefficient
CWS	Chilled Water System
D d	Distance (usually feet)
DB	Dry Bulb
DCV	Demand Control Ventilation
DD	Degree Day
DDB	Double Declining Balance
DDC	Direct Digital Controls
Deferred maintenance	Deferred maintenance is condition work (excluding suitability and energy audit needs) deferred on a planned or unplanned basis to a future budget cycle or postponed until funds are available.
Deficiency	A deficiency is a repair item that is damaged missing inadequate or insufficient for an intended purpose.
Delta	Difference
Delta P	Pressure Difference
Delta T	Temperature Difference
DG	Distributed Generation
DOE	Department of Energy
DP	Dew Point
DR	Demand Response
DX	Direct Expansion Air Conditioner
EA	Energy Audit
EBITDA	Earnings before Interest Taxes Depreciation and Amortization
ECI	Energy Cost Index
ECM	Energy Conservation Measure
ECO	Energy Conservation Opportunity
ECPA	Energy Conservation and Production Act
ECR	Energy Conservation Recommendation
ECS	Energy Control System

## Site Assessment Report - S544101;Willard Annex

---

EER	Energy Efficiency Ratio
EERE	Energy Efficiency and Renewable Energy division of US DOE
EIA	Energy Information Agency
EIS	Energy Information System
EMCS	Energy Management Computer System
EMO	Energy Management Opportunity
EMP	Energy Management Project
EMR	Energy Management Recommendation
EMS	Energy Management System
Energy Utilization Index (EUI)	EUI is the measure of total energy consumed in the cooling or heating of a building in a period expressed as British thermal unit (BTU) per (cooled or heated) gross square foot.
EO	Executive Order
EPA	Environmental Protection Agency
EPACT	Energy Policy Act of 1992
EPCA	Energy Production and Conservation Act of 1975
EPRI	Electric Power Research Institute
EREN	Efficiency and Renewable Energy (Division of USDOE)
ERV	Energy Recovery Ventilator
ESCO	Energy Service Company
ESPC	Energy Savings Performance Contract
EUI	Energy Use Index
EWG	Exempt Wholesale Generators
Extended Facility Condition Index (EFCI)	EFCI is calculated as the condition needs for the current year plus facility system renewal needs going out to a set time in the future divided by Current Replacement Value.
f	Frequency
F	Fahrenheit
Facility	A facility refers to site(s) building(s) or building addition(s) or combinations thereof that provide a particular service.
Facility Condition Assessment (FCA)	FCA is a process for evaluating the condition of buildings and facilities for programming and budgetary purposes through an on site inspection and evaluation process.
Facility Condition Index (FCI)	FCI is an industry-standard measurement of a facility's condition that is the ratio of the cost to correct a facility's deficiencies to the Current Replacement Value of the facilities. The higher the FCI the poorer the condition of a facility. After an FCI is established for all buildings within a portfolio a building's condition can be ranked relative to other buildings. The FCI may also represent the condition of a portfolio based on the cumulative FCIs of the portfolio's facilities.

## Site Assessment Report - S544101;Willard Annex

---

FC	Footcandle
FCA	Fuel Cost Adjustment
FEMIA	Federal Energy Management Improvement Act of 1988
FEMP	Federal Energy Management Program
FERC	Federal Energy Regulatory Commission
FESR	Fuel Energy Savings Ratio
FLA	Full Load Amps
FLF	Facility Load Factor (usually monthly)
FLRPM	Full Load Revolutions per Minute
FMS	Facility Management System
FPM fpm	Feet per Minute (velocity)
FSEC	Florida Solar Energy Center
Ft	Foot
GPM gpm	Gallons per Minute
GRI	Gas Research Institute
Gross Square Feet (GSF)	The size of the enclosed floor space of a building in square feet measured to the outside face of the enclosing wall.
GUI	Graphical User Interface
H h	Enthalpy Btu/lb
HCFC	Hydrochlorofluorocarbons
HDD	Heating Degree days
HFC	Hydrofluorocarbons
HHV	Higher Heating Value
HID	High Intensity Discharge (lamp)
HMI	Human Machine Interface
HMMI	Human Man Machine Interface
HO	High Output (lamp)
HP Hp hp	Horsepower
HPS	High Pressure Sodium (lamp)
HR	Humidity Ratio
Hr hr	Hour

## Site Assessment Report - S544101;Willard Annex

---

HRU	Heat Recovery Unit
HVAC	Heating Ventilation and Air-Conditioning
Hz	Hertz
I	Intensity (lumen output of lamp)
I i	Interest rate or Discount rate
IAQ	Indoor Air Quality
ICA	International Cogeneration Alliance
ICBO	International Conference of Buildings Officials
ICC	International Code Council
ICP	Institutional Conservation Program
IECC	International Energy Conservation Code
IEEE	Institute of Electrical and Electronic Engineers
IESNA	Illuminating Engineering Society of North America
Install year	The year a building or system was built or the most recent major renovation date (where a minimum of 70 of the system's Current Replacement Value (CRV) was replaced).
IRP	Integrated Resource Planning
IRR	Internal Rate of Return
ISO	Independent System Operator
ITA	Independent Tariff Administrator
k	Kilo multiple of thousands in SI system
K	Kelvins (color temperature of lamp)
K k	Thermal Conductivity of Material
KVA	Kilovolt Ampere
KVAR	Kilovolt Ampere Reactive
kW	kiloWatt
kWh	kiloWatt hour
L	Length (usually feet)
LCC	Life Cycle Costing
LDC	Local Distribution Company
LEED	Leadership in Energy and Environmental Design
LEED EB	LEED for Existing Buildings

## Site Assessment Report - S544101;Willard Annex

---

LEED NC	LEED for new construction
LF	Load Factor
LHV	Lower Heating Value
Life cycle	The period of time that a building or site system or element can be expected to adequately serve its intended function.
LPS	Low Pressure Sodium (lamp)
Lu	Lumen Output of a Lamp or Fixture
M	Mega multiple of millions in SI system
M&V	Measurement and Verification
MACRS	Modified Accelerated Cost Recovery System
MARR	Minimum Attractive Rate of Return
Mbtu	Thousand Btu
MCF	Thousand Cubic Feet (usually of gas)
MEC	Model Energy Code
Mm	Multiple of Thousands in I/P System
MMBtu	Million Btu
MMCS	Maintenance Management Computer System
MMI	Man Machine Interface
MMS	Maintenance Management System
MSE 2000	Management System for Energy 2000 (ANSI Georgia Tech Univ)
MW	MegaWatt
MWH MWh	MegaWatt hour
NAAQS	National Ambient Air Quality Standards
NAESCO	National Association of Energy Service Companies
NAIMA	North American Insulation Manufacturers Association
NEA	National Energy Act of 1978
NECPA	National Energy Conservation Policy Act
NEMA	National Electrical Manufacturer's Association
NERC	North American Electric Reliability Council
Next Renewal	The Next Renewal date is an override of the 'Calculated Next Renewal' date and is based upon the assessor's visual inspection.

## Site Assessment Report - S544101;Willard Annex

---

NFPA	National Fire Protection Association
NGPA	National Gas Policy Act of 1978
NLRPM	No Load Revolutions per Minute (speed)
Nn	Equipment or Project lifetime in economic analysis
NOPR	Notice of Proposed Rule Making from FERC
NOx	Nitrogen Oxide Compounds
NPV	Net present value in economic analysis
NREL	National Renewable Energy Laboratory
NUG	Non-Utility Generator
O&M	Operation and Maintenance
OA	Outside Air
ODP	Ozone Depletion Potential
OPAC	Off-Peak Air Conditioning
P	Present value in economic analysis
PBR	Performance Based Rates
PEA	Preliminary Energy Audit
PF	Power Factor
PID	Proportional plus integral plus derivative (control system)
PM	Portfolio Manager in Energy Star rating system
PM	Preventive Maintenance
PoolCo	Power Pool Company or Organization
POU	Point of Use
PQ	Power Quality
PSC	Public Service Commission
PSIA psia	Pounds per square inch absolute (pressure)
PSIG psig	Pounds per square inch gauge (pressure)
PUC	Public Utility Commission
PUHCA	Public Utilities Holding Company Act of 1935
PURPA	Public Utilities Regulatory Policies of 1978
PV	Photovoltaic system

## Site Assessment Report - S544101;Willard Annex

---

PV	Present Value
PW	Present Worth
PX	Power Exchange
q	Rate of heat flow in Btu per hour
Q	Heat load due to conduction using degree days
QF	Qualifying Facility
R	Electrical resistance
R	Thermal Resistance
RC	Remote controller
RCR	Room Cavity Ratio
RCRA	Resource Conservation and Recovery Act
Remaining Service Life (RSL)	RSL is the number of years service remaining for a system or equipment item. It is automatically calculated based on the difference between the current year and the 'Calculated Next Renewal' date or the 'Next Renewal' date whichever one is the later date.
Remaining Service Life Index (RSLI)	RSLI is defined as a percentage ratio of the remaining service life of a system. It usually ranges from 0 to 100
REMR	Repair Evaluation Maintenance Rehabilitation (REMR) is a scale used to objectively rank systems based on their condition
Renewal Schedule	A timeline that provides the items that need repair the year in which the repair is needed and the estimated price of the renewal.
RH	Relative Humidity
RLA	Running Load Amps
RMS	Root Mean Square
RO	Reverse Osmosis
ROI	Return on Investment
RPM	Revolutions Per Minute
RTG	Regional Transmission Group
RTO	Regional Transmission Organization
RTP	Real Time Pricing
SBCCI	Southern Building Code Congress International
SC	Scheduling Coordinator
SC	Shading Coefficient
SCADA	Supervisory Control and Data Acquisition Systems



## Site Assessment Report - S544101;Willard Annex

---

SEER	Seasonal Energy Efficiency Ratio
SHR	Sensible Heat Ratio
Site	The grounds and utilities roadways landscaping fencing and other typical land improvements needed to support the facility.
Soft Cost	An expense item that is not considered direct construction cost. Soft cost includes architectural engineering financing legal fees and other pre-and-post construction expenses.
SOx	Sulfur Oxide Compounds
SP	Static Pressure
SP SPB	Simple Payback
SPP	Simple Payback Period
SPP	Small Power Producers
STR	Stack Temperature Rise
SV	Specific Volume
System	System refers to building and related site work elements as described by ASTM Uniformat II Classification for Building Elements (E1557-97) a format for classifying major facility elements common to most buildings. Elements usually perform a given function regardless of the design specification construction method or materials used. See also Uniformat II.
T	Temperature
T	Tubular (lamps)
TAA	Technical Assistance Audit
TCP/IP	Transmission Control Protocol/Internet Protocol
TES	Thermal Energy Storage
THD	Total Harmonic Distortion
TOD	Time of Day
TOU	Time of Use
TQM	Total Quality Management
TransCo	Transmission Company
U	Thermal Conductance
UDC	Utility Distribution Company
UL	Underwriters Laboratories
UNIFORMAT II	The ASTM UNIFORMAT II Classification for Building Elements (E1557-97) a format for classifying major facility components common to most buildings.
USGBC	US Green Building Council
v	Specific Volume

## Site Assessment Report - S544101;Willard Annex

---

V	Volts Voltage
V	Volume
VAV	Variable Air Volume
VDT	Video Display Terminal
VFD	Variable Frequency Drive
VHO	Very High Output
VSD	Variable Speed Drive
W	Watts
W	Width
WB	Wet bulb
WH Wh	Watt Hours
Year built	The year that a building or addition was originally built based on substantial completion or occupancy.
Z	Electrical Impedance