SCHOOL DISTRICT OF PHILADELPHIA



Asbestos Hazard Emergency Response Act "AHERA"

THREE-YEAR RE-INSPECTION 2015-2016

and ASBESTOS MANAGEMENT PLAN for the

Thomas G. Morton Elementary School

ULCS# 1380 Building # B138001-1 2501 S. 63rd Street Philadelphia, Pennsylvania 19142

Year Built: 1971

November 4, 2015

Conducted by:

Accredited Environmental Technologies, Incorporated
Batta Environmental Associates, Incorporated
Criterion Laboratories, Incorporated
Environmental Testing Consultants, LLC
G & C Environmental Services, Incorporated
KEM Partners, Incorporated
Synertech, Inc.
TTI Environmental, Inc.
USA Environmental Management, Inc.
The Vertex Companies, Inc.

Management Plan Prepared by: Criterion Labs, Inc and Synertech Inc.

This report must remain in the Main Office as mandated by the US EPA AHERA Regulations.

AHERA THREE-YEAR REINSPECTION VOLUME IX

Table of Contents

Transmittal Letter

Executive Summary

- I. Summary list of Confirmed Asbestos Containing Building Materials
- II. Summary list of Assumed Asbestos Contain Building Materials
- III. Summary list of Non-Asbestos Containing Building Materials
- IV. Summary list of Non Suspect Asbestos Containing Building Materials
- V. Summary List of Auditorium DATA for this location
- VI. Summary list of Attic and/or Crawlspace DATA for this location
- VII. Summary list of Pipe Chase/Pipe Shaft DATA for this location

Section I Report of Re-Inspection

- A. Introduction
- B. Three-Year Re-inspection IX Overview
- C. Post- Management Plan Activities and Changes
 - C.1 Sampling and Analysis
 - C.2 New Floor Tile Sampling
 - C.3 Abatement Activity
 - C.4 Periodic (Six-Month) Surveillance (Damaged Materials)

Section II Re-Inspection Data

- A. Introduction
- B. Re-Inspection Key Definitions
- C. Room by Room Location Log Report

Section III Certificates

A. Management Planner/Building Inspector Certificates

Section IV Cross Reference Table Page 1-8

Asbestos Management Program Page 9-19

SCHOOL DISTRICT OF PHILADELPHIA EDUCATIONAL CENTER

440 NORTH BROAD STREET PHILADELPHIA, PENNSYLVANIA 19130

OFFICE OF ENVIRONMENT AL MANAGEMENT AND SERVICES

PHONE (215)-400-4750

January 2016

TO: All Principals

All Building Administrators

FROM: Fran Burns

Chief Operating Officer

Francine Locke, M.S., Director

Office of Environmental Management and Services

SUBJECT: AHERA Three (3) Year Re-inspection IX report

In order to comply with the provisions of the Asbestos Hazard Emergency Response Act (AHERA) the attached report is submitted to you. The law requires that this report be kept in the Main/Principal's office. It cannot be removed from these locations. *If the school (program) is relocated to a different building, these environmental documents are to be safely retained for the next school/building occupants*. All asbestos reports must be available to the public and Federal EPA upon request.

Fran Burns

Chief Operation Officer

Francine Locke, M.S., Director Office of Environmental Management

and Services

AHERA-2d Revised 12/14/15

Executive Summary

This Asbestos Hazard Emergency Response Act (AHERA) Three-Year Re-inspection "Volume # IX" Management Plan at this location, has been completed and the report of re-inspection submitted to the School District of Philadelphia. The re-inspections in all School District of Philadelphia buildings of 2015-2016 were conducted and completed between October 5th, 2015 through March 30th, 2016 as a joint project by Accredited Environmental Technologies, Inc., Batta Environmental Associates, Inc., Criterion Laboratories, Inc., Environmental Testing Consultants, LLC, G & C Environmental Services, Inc., KEM Partners, Inc., Synertech, Inc., TTI Environmental, Inc., USA Environmental Management, Inc. and The Vertex Companies, Inc.

In general, the School District of Philadelphia Office of Environmental Management and Services conducts Environmental Impact Evaluations and provides Asbestos Inspection Reports prior to any renovation, demolition and/or maintenance activities. The AHERA report must be reviewed prior to any renovation, demolition and/or maintenance activities in order to avoid the unknowing disturbance to Asbestos Containing Building Materials identified within this location. In addition, prior to work activities above all drop ceilings this report should be reviewed to avoid potential disturbances to Asbestos Containing Materials. Refer to Section IV of the Cross Reference Table, for additional Asbestos Management Program information. Contact the Office of Environmental Management and Services to have an Environmental Impact Evaluation conducted prior to any renovation, demolition and/or maintenance activities within this facility.

The information contained in this report was obtained from the original Asbestos Management Plan for the school, from update reports on changes and activities since the completion of the 1st Management Plan for each location and from all prior inspections performed and documented in Volume # I through Volume VIII (dated respectively 1992, 1995, 1998, 2001, 2004, 2007, 2010 or 2013) (if applicable) - and by this Three-Year Re-inspection of this school. The re-inspection report/Management Plan of 2015-2016 were reviewed and prepared collectively by Management Planner Megan Vala, Mary Anne Lerro of Criterion Laboratories, Inc. and/or Monique Causley, of Synertech Inc.

The 2015-2016 inspection process included the addition of a comprehensive Room by Room Inventory of all Thermal (T), Surfacing (S) and Miscellaneous (M) Materials specific to each room of this facility. Inspections of each room's thermal, ceilings, walls, floors and miscellaneous items regardless of Asbestos Content are categorized on the Room by Room Location Log Report for this location. Rooms or areas of the facility that were not accessible at the time of the inspection are marked with an "X". The Room by Room Location Log Report is found in Section II C of this Management Plan.

All Presumed or Suspect Asbestos Containing Building Materials (ACBMs), listed in the following summary charts are categorized as Confirmed, Assumed, Non-Asbestos, and/or Non-Suspect (ACBMs) were identified in the original Management Plan, or in the Volume I through Volume VIII AHERA Three-Year Re-inspection reports, and were re-inspected as part of this project.

As mandated by the U S EPA AHERA regulations, periodic Six-Month inspections and Three-Year Re-inspections of this location will be performed and the Inspection Data in this report will be updated accordingly.

Please feel free to contact the School District of Philadelphia's Office of Environmental Management and Services (OEMS) regarding any comments, questions, or concerns regarding this report or any Environmental related topic. OEMS staff can be reached at (215) 400 4750, via fax at (215) 400 4751 or via e-mail at flocke@philasd.org and/or flocke@philasd.org.

Additional information can be found on our website. Here is the link to the OEMS website. http://webgui.phila.k12.pa.us/offices/e/environmental

I. Summary list of Confirmed Asbestos Containing Building Materials within this facility

These charts are to be used for a quick reference* in order to avoid the unknowing disturbance of Asbestos Containing Materials during any and all Operations, Maintenance, Renovation, and/or Demolition activities at this location. These materials have been sampled and Laboratory Analysis has CONFIRMED the presence of Asbestos. Contact OEMS prior to the disturbance of any of the following materials.

Confirmed Asbestos Containing Building Materials for this location

1			
	Black Mastic a/w Tan Floor Tile	Boiler Breeching	Floor Tile VAT 12" x 12"

^{*} Always refer to the Room by Room Logs for each specific material classification as the material classification findings may be different in various rooms throughout this facility.

^{**} Some Materials may have multiple classifications (Confirmed, Assumed, NAD and Non Suspect) within this facility.

II. Summary list of Assumed Asbestos Containing Building Materials within this facility

These charts are to be used for a quick reference* in order to avoid the unknowing disturbance of Asbestos Containing Materials during any and all Operations, Maintenance, Renovation, and/or Demolition activities at this location. These materials have not been sampled and should not be disturbed until verification of Asbestos Content. Contact OEMS for assessment and sampling prior to the disturbance of these materials.

Assumed Asbestos Containing Building Materials for this location

Floor Tile VAT 12" x 12"	Sectional Boiler	Sink Undercoat Mastic
Transite Electrical Panel	Unit Ventilator Insulation	Vibration Damper Cloth

^{*} Always refer to the Room by Room Logs for each specific material classification as the material classification findings may be different in various rooms throughout this facility.

^{**} Some Materials may have multiple classifications (Confirmed, Assumed, NAD and Non Suspect) within this facility.

III. Summary list of Non-Asbestos Containing Building Materials within this facility

These charts are to be used for a quick reference* in order to avoid the unknowing disturbance of Asbestos Containing Materials during any and all Operations, Maintenance, Renovation, and/or Demolition activities at this location. These materials have been sampled and Laboratory Analysis has indicated NO Asbestos present or NO ASBESTOS DETECTED (NAD).

Non- Asbestos Containing Building Materials for this location

Fireproofing	Pipe Fitting Insulation	Plaster Ceiling
Plaster Walls	Valve Cap Insulation	Valve Insulation

^{*} Always refer to the Room by Room Logs for each specific material classification as the material classification findings may be different in various rooms throughout this facility.

^{**} Some Materials may have multiple classifications (Confirmed, Assumed, NAD and Non Suspect) within this facility.

IV. Summary list of Non-Suspect Asbestos Containing Building Materials within this facility

These charts are to be used for a quick reference* in order to avoid the unknowing disturbance of Asbestos Containing Materials during any and all Operations, Maintenance, Renovation, and/or Demolition activities at this location. These materials are not typically known to contain Asbestos.

Non-Suspect Asbestos Containing Building Materials for this location

Brick Wall	Ceiling Tile 2' x 4'	Cement Floor
Ceramic Tile Floors	Ceramic Tile Walls	CMU
Concrete Block Wall	Concrete Ceiling	Fiberglass Ceiling Tile 2' x 4'
Fiberglass Pipe Fitting Insulation	Fiberglass Pipe Insulation	Metal Ceiling
Vinyl Vibration Damper Cloth		

^{*} Always refer to the Room by Room Logs for each specific material classification as the material classification findings may be different in various rooms throughout this facility.

^{**} Some Materials may have multiple classifications (Confirmed, Assumed, NAD and Non Suspect) within this facility.

V. Summary list of Auditorium DATA for this location

These charts are to be used for a quick reference of the Auditorium DATA within this facility. Sampling of the Auditorium Ceilings throughout the District is more difficult because of the various ceiling heights. As sampling occurs this information is updated on a case by case basis for each specific location and facility.

This is a list of known materials for this location's Auditorium

Auditorium										
Auditorium	Fiberglass Ceiling Tile 2' x 4'	Non Suspect ACM								
Auditorium	CMU	Non Suspect ACM								
Auditorium	Floor Tile VAT 12" x 12"	Assumed								
Auditorium Stage	CMU	Non Suspect ACM								
Auditorium Stage	Floor Tile VAT 12" x 12"	Assumed								

^{*} Always refer to the Room by Room Logs for each specific material classification as the material classification findings may be different in various rooms throughout this facility.

^{**} Some Materials may have multiple classifications (Confirmed, Assumed, NAD and Non Suspect) within this facility.

VI. Summary list of Attic and/or Crawlspace DATA for this location

These charts are to be used for a quick reference regarding the Attics and/or Crawlspaces inspection DATA within this facility. Contact OEMS prior to entering any attic or crawlspace within this facility and refer to the below chart and legend for Category Rank determination. The Data relative to these spaces is updated as conditions change regarding Abatement or Renovation activity on a case by case basis for each specific location and facility. In general, Crawlspaces are below the basement or 1st floor and Attics are above the floor space.

Category Rank Legend

- "A" No Asbestos Containing Materials Sample Results indicate NO ACM on pipes, fittings, elbows, or equipment located within this functional space, and NO VISIBLE DEBRIS or DAMAGE observed at time of this inspection.
- "B" Asbestos Containing Materials Exist Sample Results indicate ACM on pipes, fittings, elbows, or equipment located within this functional space, HOWEVER, NO VISIBLE DEBRIS or DAMAGE observed at time of this inspection.
- "C" Asbestos Containing Materials Exist Sample Results indicate ACM on pipes, fittings, elbows, or equipment located within this functional space, and LOCALIZED VISIBLE DEBRIS or DAMAGE observed at time of this inspection.
- "D" Asbestos Containing Materials Exist Sample Results indicate ACM on pipes, fittings, elbows, or equipment located within this functional space and DISTRIBUTED VISIBLE DEBRIS or SIGNIFICANT DAMAGE observed at time of this inspection.
- "E" No Bulk Sample Results Available SUSPECT ACM OBSERVED. Contact OEMS immediately for additional instructions.

Attic/Crawlspace	Access Area	Floor Surface	Category Rank	Comments
Attic	X	X	X	No Attic
Crawlspace	X	X	X	No Crawlspace

VII. Summary list of Pipe Chase/Pipe Shaft DATA for this location

These charts are to be used for a quick reference regarding the information known about the Pipe Chases and/or Pipe Shafts inspection DATA within this facility. Contact OEMS prior to performing renovation activities any Pipe Chase and/or Pipe Shaft within this facility and refer to the below chart and legend for Asbestos Content of various materials identified within each space. The Data relative to these spaces is updated as conditions change regarding Inspection, Abatement and/or Renovation activity on a case by case basis for each specific location and facility. In general, Pipe Chases are horizontal spaces and Pipe Shafts are vertical spaces.

Pipe Chases and Pipe Shafts need to be assessed.

Section I Report of Re-Inspection

- A. Introduction
- **B.** Three-Year Re-Inspection IX Overview
- C. Post-Management Plan Activities and Changes
 - **C.1** Sampling and Analysis
 - **C.2** New Floor Tile Sampling
 - **C.3** Abatement Activity
 - **C.4** Periodic Six-Month Surveillance (Damaged Materials)

Section I - A

Report of Re-inspection

Introduction

The Three-Year Re-inspection IX was performed to fulfill the requirements of 40 CFR Part 763 - the Asbestos Hazard Emergency Response Act (AHERA). As required by AHERA, each Local Education Agency (LEA) must re-inspect all known confirmed or assumed Asbestos Containing Building Material (ACBM) located in the LEA's facilities. This re-inspection is intended to update the original Asbestos Management Plan for the LEA's facilities.

Multiple Building Inspectors of several firms performed the 2015/2016 re-inspection. The reinspection report/Management Plan of 2015-2016 were reviewed and prepared collectively by Management Planner Megan Vala, Mary Anne Lerro of Criterion Laboratories, Inc. and Monique Causley, of Synertech Inc.

All of the certificates can be found in Section III.

During the re-inspection of each School District of Philadelphia facility, all of the Management Plans for that facility were reviewed. Information from the conclusions section of that report is included in this report. Additionally, information on activities such as abatements, cleanings, sampling and inspections, which have taken place since the completion of the original Management Plan, were reviewed during the re-inspection. Information on those activities is included in this report.

As mandated by the U S EPA AHERA regulations, all future periodic Six-Month inspections and Three-Year Re-inspections of this location will be performed and the Inspection Data in this report will be updated accordingly.

Section I - B

Three-Year Re-inspection IX Overview

Each homogeneous area of Asbestos Containing Building Material (ACBM) listed in the original Management Plan or in the 1992, 1995, 1998, 2001, etc., Three-Year Reinspection reports were inspected for the AHERA Three-Year Re-inspection Volume IX, and the information for that material verified. Any changes to a homogeneous area listed in the updates to the Management Plans were verified. Any area of suspected ACBM found in the course of the re-inspection, and not listed in the Management Plan or updates, were either assumed to contain asbestos or sampled and analyzed to determine their asbestos content. Any such new areas either assumed to contain asbestos or determined through analysis to contain asbestos were included in the report of the Three-Year Re-inspection. The results of the AHERA Three-Year Re-inspection IX are tabulated in the Room by Room log reports located in *Section II-C* of this report.

As previously noted, all future periodic Six-Month inspections and Three-Year Reinspections of this location will be performed and the Inspection Data in this report will be updated accordingly.

Post Management Plan Activities/Changes

Information on activities affecting Asbestos Containing Building Materials (ACBMs) at this location is contained in updates to the Management Plan. These updates are kept on file by the School District of Philadelphia and were reviewed for this project. Updates to the Management Plan include the following: Sampling and Analysis, New Tile Installation, Abatement Activity and Periodic Six-Month Surveillance Data.

Sampling and Analysis

Date	Floor	Room Type	Location	Material	Color	Results
2/29/2015	3rd	Hallway	IMC Hallway	Floor Tile 12" x 12"	Tan	Confirmed
8/13/2016	Basement	Mechanical Room	Pump Room	Hanger Insulation		Confirmed
8/13/2016	Basement	Mechanical Room	Pump Room	Pipe Fitting Insulation		NAD
8/13/2016	Basement	Mechanical Room	Pump Room	Valve Cap Insulation	White	NAD

Information on the installation of new floor tiles/renovation activities affecting Asbestos Containing Building Materials (ACBMs) at this location is contained in updates to the Management Plan. These updates are kept on file by the School District of Philadelphia and were reviewed for this project. Updates to the Management Plan include the following:

New Floor Tile Sampling

In the event that new tile is installed, the material must be tested prior to installation.

Information on the Asbestos Abatement and renovation activities affecting Asbestos Containing Building Materials (ACBMs) at this location is contained in updates to the Management Plan. These updates are kept on file by the School District of Philadelphia and were reviewed for this project. Updates to the Management Plan include the following:

Abatement Activity

In the event Abatement occurs, data will be listed here.

Information on the AHERA inspection that noted damage to various Building Materials at this location is contained in updates to the Management Plan. These updates are kept on file by the School District of Philadelphia and were reviewed for this project. Work orders are created for Corrective Action responses and tracked for completion. Updates to the Management Plan include the following:

Periodic (Six-Month) Surveillance (Damaged Materials)

Date	Element	Floor	On Site Room Name	Material	Amount of Material	of
				No changes in the material		
11/10/2016	X	X	X	were observed	X	X

Section II Re-Inspection Data

A. Introduction

B. Re-Inspection Key Definitions

C. Room by Room Location Log Report

Section II - A

Re-inspection Data

Introduction

The following information documents the Three-Year Re-inspection IX of the subject school/facility. The Homogeneous Area Reports were produced using the building inspector's field data on the facility. The key to the Homogeneous Area Report is outlined in the following pages of this report.

Section II - B (page 1 of 4)

SCHOOL DISTRICT OF PHILADELPHIA AHERA THREE YEAR RE-INSPECTION IX

ITEM	EFINITION									
ULCS#	Individual identification number assigned to each school within the School District of Philadelphia.									
HOMOGENEOUS AREA ID#	Identification number assigned to each homogeneous area in a school/facility. Each section of the homogeneous area ID is significant.									
	1010/01/01/01 A B C D									
	 A. Is the ULCS# for the school. B. Designates the specific building/building area within the school. C. Designates the floor or level within the building/building area. D. Designates the homogeneous material within that floor or level. Note: Item D may be a number or a letter. 									
SYSTEM AFFECTED	Corresponds to the AHERA system for classifying materials.									
AFFECIED	 T : Thermal System S : Surfacing System M : Miscellaneous 									
ITEM AFFECTED	Is a description of the homogeneous material.									
ORIGINAL INSPECTION DATA	This section contains the information found in the original Management Plan (1988-1989).									
AMOUNT OF MATERIAL/ UNIT	Quantity of material, and measuring unit. Units include: Square Feet (SF) Each (EA) Linear Feet (LF) Cubic Feet (CF).									

SCHOOL DISTRICT OF PHILADELPHIA AHERA THREE YEAR RE-INSPECTION IX

RE-INSPECTION FORM KEY

ITEM D	EFINITION
--------	------------------

CND Corresponds to AHERA condition rating for materials.

Condition

0 : No Damage1 : Damage

2 : Significant Damage

DP

Corresponds to the AHERA material assessment system.

Damage Potential

1 : Potential for Damage

2 : Potential for Significant Damage

ASMD Assumed Asbestos This means that a material was not sampled for asbestos content during the original Management Plan inspection.

RA

This corresponds to the AHERA system of response action rating for materials.

Response Action

Establish O&M Program

2 : Repair and Establish O&M Program

3 : Enclose
4 : Encapsulate
5 : Remove

6 : Partial Removal and Establish O&M Program

CHANGES

This section describes changes to the homogeneous material in the twenty-four years since the original AHERA inspection. The abbreviations are defined below.

RMVD Removed **Enclosed ENCL ENCP** Encapsulated **DMGD** Damaged **SMPLD** Sampled Material MTRL **RPRD** Repaired None Located N/L **RPLCD** Replaced

SCHOOL DISTRICT OF PHILADELPHIA AHERA THREE-YEAR RE-INSPECTION IX

RE-INSPECTION FORM KEY

ITEM DEFINITION

THREE YEAR RE-INSPECTION

This section contains the information obtained from the Three-Year Re-inspection IX. With three exceptions, the information categories are identical in format and meaning to those found in the original inspection data section. The three exceptions are defined below.

DMGD AMT Amount Damaged

This section gives the quantity of damaged material in a homogeneous area. The quantity is shown in the same format as the amount of material/unit section.

NF Newly Friable

This section identifies materials in the original Management Plan which have since become friable.

RA Response Action

This rating is based on the AHERA regulations, and is comparable to the RA rating found in the "Original Inspection Data" section. The following table details the response actions.

- 1. Establish O&M Program
- 2. Repair and Establish O&M Program
- 3. Enclose
- 4. Encapsulate
- **5.** Remove
- **6.** Partial Removal and Establish O&M Program

a. High Priority Response

The homogeneous material has been scheduled for abatement or other response action.

b. Medium Priority Response

The homogeneous material will be scheduled for abatement or other response action as soon as the high priority responses have been addressed.

c. Low Priority Response

The homogeneous material will be scheduled for abatement or other response action as soon as the medium priority responses have been addressed.

d. On-Going Response/Operations and Maintenance

The homogeneous material does not require abatement or other response action at present, and should be included in the facility's on-going operations and maintenance program.

SCHOOL DISTRICT OF PHILADELPHIA AHERA THREE-YEAR RE-INSPECTION IX

RE-INSPECTION FORM KEY

The information presented in the changes section has been compiled from a variety of sources, including the Re-inspection and the following:

- * Quality Control/Quality Assurance Reports of asbestos abatement projects, prepared by consultants to the School District.
- * Permit and Notification Forms for asbestos abatement projects.
- * Periodic Surveillance Forms
- * Operations and Maintenance activities performed by School District personnel.
- * Verbal information from School District personnel.
- * Reports of sampling and analysis of suspected materials by both School District personnel and outside consultants.

ROOM BY ROOM LOCATION LOG REPORT This section gives information, including damage amount and location, for a specific homogeneous material on a room-by-room basis and follows the Re-inspection form.

NOTE: The disparate nature of the above sources of information prohibits the verification of much information within the scope of the AHERA Three-Year Re-inspection. Discrepancies and omissions may exist in this information, and therefore is included on an "as is" basis. The inspectors for the Three-Year Re-inspection IX evaluated homogeneous areas based on the materials current condition and location, as evidenced during the inspector's site visit.

Section II - C

Room by Room Location Log Report

These charts are to be used for a quick reference* in order to avoid the unknowing disturbance of Asbestos Containing Materials during any and all Operations, Maintenance, Renovation, and/or Demolition activities at this location.

NOTE:

Contact OEMS prior to the disturbance of any of the materials that are listed as **Confirmed and/or Assumed**.

The quantities listed for (NAD) non-asbestos containing materials and/or Non-Suspect Materials are only estimated and were not measured for the purpose of this report. Field verification of quantities for renovation purposes would be necessary.

		School District of Philadelphia			ERA Three-Year Reins	mastics 2015 2016						Reinspection Date: 11-4-15	<u> </u>			
		Thomas G. Morton Elementary School		An	Room by Room Locat							Building Inspector: Shelton Williams	-			
		2501 S. 63rd Street, Philadelphia, PA 19142			Room by Room Locat	ion Log Report							+			
		· · ·										Number: 046177	-			
		ULCS# 1380										Management Planner: Megan Vala	-			
E		Year Built: 1971							I			Number: 740728				
1	F															
e	ī															
m e	0		0			Confirmed/Assumed/NAD	Amount of	SF LF	Amount of	SF LF	Color		Attic Crawl	Damage Potential	Newly Friable	Response
n t	o r	On Site Room Name	System Affected	Material Description	HID#	Non Suspect ACM	Material	SF LF EA	Damage	EA	required for VAT	Comments/Description/Notes	Space Ranking	(DP)	(NF)	Action (RA)
1	В	Stairwell to Basement next to Fan Room	N/A	Cement Floor		Non Suspect ACM	100	SF	0	SF				N/A	N/A	N/A
1	В	Stairwell to Basement next to Fan Room	M	Floor Tile VAT 12" x 12"	1380/01/0B/DD	Assumed	50	SF	0	SF	Tan			1	No	1/D
1	В	Stairwell to Basement next to Fan Room	N/A	CMU	1000/01/05/55	Non Suspect ACM	450	SF	0	SF	- run			N/A	N/A	N/A
1	В	Stairwell to Basement next to Fan Room	N/A	Metal Ceiling		Non Suspect ACM	150	SF	0	SF				N/A	N/A	N/A
1	В	Stairwell to Basement next to Fan Room	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	1	LF	0	LF				N/A	N/A	N/A
1	В	Pump Room	N/A	Cement Floor		Non Suspect ACM	450	SF	0	SF				N/A	N/A	N/A
1		Pump Room	N/A	CMU		Non Suspect ACM	1350	SF	0	SF				N/A	N/A	N/A
		Pump Room	N/A	Fireproofing		NAD	450	SF	0	SF		Sampled August 2015 G&C/AV		N/A	N/A	N/A
1	В	Pump Room	N/A	Valve Insulation		NAD	9	EA	0	EA		Sampled August 2015 G&C/AV		N/A	N/A	N/A
1	B	Pump Room Elevator Machine Room inside Pump Room	N/A N/A	Valve Cap Insulation Cement Floor		NAD Non Suspect ACM	9 80	EA SF	0	EA SF				N/A N/A	N/A N/A	N/A N/A
		Elevator Machine Room inside Pump Room	N/A	Concrete Block Wall		Non Suspect ACM	240	SF	0	SF				N/A	N/A	N/A
1	В	Elevator Machine Room inside Pump Room	N/A	Metal Ceiling		Non Suspect ACM	80	SF	0	SF				N/A	N/A	N/A
1		Fan Room	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	240	LF	0	LF				N/A	N/A	N/A
		Fan Room Fan Room	N/A N/A	Fiberglass Pipe Fitting Insulation Fireproofing		Non Suspect ACM NAD	50 450	EA SF	0	EA SF				N/A N/A	N/A N/A	N/A N/A
1		Fan Room	N/A N/A	CMU		Non Suspect ACM	1800	SF	0	SF				N/A N/A	N/A N/A	N/A N/A
1		Fan Room	N/A	Cement Floor		Non Suspect ACM	600	SF	0	SF				N/A	N/A	N/A
		Fan Room	N/A	Fireproofing		NAD	600	SF	0	SF				N/A	N/A	N/A
1		Fan Room	N/A N/A	Vinyl Vibration Damper Cloth		Non Suspect ACM	10 300	SF SF	0	SF SF		VDCs are black vinyl - Non Suspect ACV		N/A N/A	N/A N/A	N/A N/A
1	B	Electrical Room Electrical Room	N/A N/A	Concrete Ceiling		Non Suspect ACM Non Suspect ACM	1110	SF	0	SF				N/A N/A	N/A N/A	N/A N/A
1		Electrical Room	N/A	Cement Floor		Non Suspect ACM	300	SF	0	SF				N/A	N/A	N/A
	В	Electrical Room	N/A	Fireproofing		NAD	300	SF	0	SF				N/A	N/A	N/A
1		Electrical Room	M	Transite Electrical Panel	1380/01/0B/SYN/BB/2350	Assumed	100	SF	0	SF		Inside 13,200 Volt Transformer		1	No	1/D
1	B	Hallway outside of Electrical Room Hallway outside of Electrical Room	M N/A	Floor Tile VAT 12" x 12"	1380/01/0B/DD	Assumed Non Suspect ACM	140 420	SF SF	0	SF SF	Tan			N/A	No N/A	1/D N/A
		Hallway outside of Electrical Room	N/A	Fireproofing		NAD NAD	140	SF	0	SF				N/A	N/A	N/A
		Boiler Room	N/A	Pipe Fitting Insulation		NAD	5	EA	0	EA				N/A	N/A	N/A
1	В	Boiler Room	N/A	Fiberglass Pipe Fitting Insulation		Non Suspect ACM	1200	LF	0	LF				N/A	N/A	N/A
1		Boiler Room Boiler Room	T N/A	Boiler Breeching Concrete Ceiling	1380/01/0B/01	Confirmed Non Suspect ACM	390 1785	SF SF	0	SF SF				1 N/A	No N/A	1/D N/A
1		Boiler Room	N/A	CMU		Non Suspect ACM	2580	SF	0	SF				N/A	N/A	N/A
1	В	Boiler Room	N/A	Cement Floor		Non Suspect ACM	1785	SF	0	SF				N/A	N/A	N/A
		Boiler Room	N/A	Fireproofing		NAD	1785	SF	0	SF				N/A	N/A	N/A
1		Boiler Room Boiler Room	M T	Vibration Damper Cloth Sectional Boiler	1380/01/0B/AA 1380/01/0B/SYN/BB/1620	Assumed Assumed	20	SF FA	0	SF FA				1 1	No No	1/D 1/D
1		Mechanical Room	N/A	Pipe Fitting Insulation	1300/01/08/3114/88/1020	NAD	5	EA	0	EA				N/A	N/A	N/A
1	В	Mechanical Room	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	390	LF	0	LF				N/A	N/A	N/A
1		Mechanical Room	N/A	Concrete Ceiling		Non Suspect ACM	765	SF	0	SF				N/A	N/A	N/A
1	B B	Mechanical Room Mechanical Room	N/A N/A	CMU Cement Floor		Non Suspect ACM Non Suspect ACM	2500 765	SF SF	0	SF SF				N/A N/A	N/A N/A	N/A N/A
		Locker Room across from Building Engineer's				•								1000		
1	В	Office	M	Floor Tile VAT 12" x 12"	1380/01/0B/DD	Assumed	100	SF	0	SF	Tan		1	1	No	1/D
1	В	Locker Room across from Building Engineer's Office	N/A	СМИ		Non Suspect ACM	300	SF	0	SF				N/A	N/A	N/A
		Locker Room across from Building Engineer's								T .						
1	В	Office Locker Room across from Building Engineer's	N/A	Plaster Ceiling		NAD	100	SF	0	SF				N/A	N/A	N/A
_ 1	В	Office	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	3	LF	0	LF				N/A	N/A	N/A
1		Locker Room Restroom	N/A	Plaster Ceiling		NAD	25	SF	0	SF				N/A	N/A	N/A
1	B B	Locker Room Restroom	N/A N/A	CMU		Non Suspect ACM	75	SF SF	0	SF				N/A N/A	N/A N/A	N/A N/A
		Locker Room Restroom Hallway outside of Building Engineer's Office	M M	Ceramic Tile Floors Floor Tile VAT 12" x 12"	1380/01/0B/DD	Non Suspect ACM Assumed	25 168	SF	0	SF SF	Tan			1 1	N/A No	1/D
1	В	Hallway outside of Building Engineer's Office	N/A	CMU		Non Suspect ACM	504	SF	0	SF				N/A	N/A	N/A
1	В	Hallway outside of Building Engineer's Office	N/A	Fireproofing		NAD	168	SF	0	SF				N/A	N/A	N/A
1	В	Hallway outside of Building Engineer's Office Custodial Closet in Hallway outside of Building	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	135	LF	0	LF				N/A	N/A	N/A
_ 1	В	Engineer's Office	N/A	Cement Floor		Non Suspect ACM	16	SF	0	SF				N/A	N/A	N/A
		Custodial Closet in Hallway outside of Building		0.41						0.5						
1	В	Engineer's Office Custodial Closet in Hallway outside of Building	N/A	CMU		Non Suspect ACM	48	SF	0	SF				N/A	N/A	N/A
1	В	Engineer's Office	N/A	Plaster Ceiling		NAD	16	SF	0_	SF				N/A	N/A	N/A
1		Building Engineer's Office	N/A	Plaster Ceiling		NAD	150	SF	0	SF				N/A	N/A	N/A
1		Building Engineer's Office	N/A M	CMU Floor Tile VAT 12" x 12"	1380/01/0B/DD	Non Suspect ACM	450 150	SF SF	0	SF SF	Tan			N/A 1	N/A No	N/A 1/D
1	В	Building Engineer's Office Building Engineer's Office Restroom	M N/A	Ceramic Tile Floors	1380/01/08/DD	Assumed Non Suspect ACM	150 35	SF	0	SF	ran			N/A	No N/A	N/A
1	В	Building Engineer's Office Restroom	N/A	CMU		Non Suspect ACM	105	SF	0	SF				N/A	N/A	N/A
	В	Building Engineer's Office Restroom	N/A	Plaster Ceiling		NAD	35	SF	0	SF				N/A	N/A	N/A
1	В	Building Engineer's Office Restroom Shower	N/A N/A	Ceramic Tile Floors Ceramic Tile Walls		Non Suspect ACM	16 60	SF SF	0	SF SF				N/A N/A	N/A N/A	N/A N/A
	LΒ	Building Engineer's Office Restroom Shower	IN/A	Ceramic file walls		Non Suspect ACM	1 00	or		1 01		l		IN/A	IN/A	IN/A

		School District of Philadelphia		AHE	RA Three-Year Rein	spection 2015-2016						Reinspection Date: 11-4-15				
		Thomas G. Morton Elementary School			Room by Room Loca							Building Inspector: Shelton Williams	-			
		2501 S. 63rd Street, Philadelphia, PA 19142			Room by Room Loca	tion Log Report							-			
												Number: 046177	-			
		ULCS# 1380										Management Planner: Megan Vala	_			
		Year Built: 1971										Number: 740728				
E	F															
e	ī															
m e	o										Color		Attic Crawl	Damage	Newly	
n	0	On Site Room Name	System Affected	Material Description	HID#	Confirmed/Assumed/NAD Non Suspect ACM	Amount of Material	SF LF	Amount of Damage	SF LF EA	required for VAT	Comments/Description/Notes	Space Ranking	Potential (DP)	Friable (NF)	Response Action (RA)
1	В	Building Engineer's Office Restroom Shower	N/A	Plaster Ceiling	niD#	NAD	16	SF	0	SF	VAI	Comments/Description/Notes	Kanking	N/A	N/A	N/A
1	В	Stairwell next to Boiler Room	N/A	Cement Floor		Non Suspect ACM	150	SF	0	SF				N/A	N/A	N/A
1		Stairwell next to Boiler Room	N/A	Concrete Block Wall		Non Suspect ACM	450	SF	0	SF				N/A	N/A	N/A
1		Stairwell next to Boiler Room Stairwell next to Boiler Room	N/A N/A	Metal Ceiling Fireproofing		Non Suspect ACM NAD	150 75	SF SF	0	SF SF				N/A N/A	N/A N/A	N/A N/A
1		Stairwell next to Boiler Room	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	25	LF	0	LF				N/A	N/A	N/A
1	1	Classroom 100	N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	1120	SF	0	SF				N/A	N/A	N/A
1		Classroom 100	N/A	CMU		Non Suspect ACM	1632	SF	0	SF				N/A	N/A	N/A
1	1	Classroom 100 Classroom 100	M M	Floor Tile VAT 12" x 12" Unit Ventilator Insulation	1380/01/01/EE 1380/01/01/HH	Assumed Assumed	1120	SF EA	0	SF EA	Tan			1	No No	1/D 1/D
'-	-	Small Rear Hallway between Classrooms 100 &				Assumed									INU	1/0
1		101	M	Floor Tile VAT 12" x 12"	1380/01/01/EE	Assumed	60	SF	0	SF	Tan			1	No	1/D
1		Small Rear Hallway between Classrooms 100 & 101	N/A	CMU		Non Suspect ACM	180	SF	0	SF				N/A	N/A	N/A
		Small Rear Hallway between Classrooms 100 &														
1		101	N/A	Ceiling Tile 2' x 4'		Non Suspect ACM	60	SF	0	SF			1	N/A	N/A	N/A
1		Small Rear Hallway between Classrooms 100 & 101	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	6	LF	0	LF				N/A	N/A	N/A
		Closet in Small Rear Hallway between Classrooms									_					
1	В	100 & 101 Closet in Small Rear Hallway between Classrooms	М	Floor Tile VAT 12" x 12"	1380/01/01/EE	Assumed	50	SF	0	SF	Tan			1	No	1/D
1	В	100 & 101	N/A	CMU		Non Suspect ACM	150	SF	0	SF				N/A	N/A	N/A
		Closet in Small Rear Hallway between Classrooms				•										
1		100 & 101 Classroom 100 Restroom	N/A N/A	Ceiling Tile 2' x 4' Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM Non Suspect ACM	50 64	SF SF	0	SF SF				N/A N/A	N/A N/A	N/A N/A
1		Classroom 100 Restroom Classroom 100 Restroom	N/A N/A	CMU		Non Suspect ACM	288	SF	0	SF				N/A N/A	N/A N/A	N/A N/A
1		Classroom 100 Restroom	N/A	Ceramic Tile Floors		Non Suspect ACM	64	SF	0	SF				N/A	N/A	N/A
1		Classroom 101	N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	1120	SF	0	SF				N/A	N/A	N/A
1	1	Classroom 101	N/A M	CMU Floor Tile VAT 12" x 12"	1380/01/01/EE	Non Suspect ACM Assumed	1632 1120	SF SF	0	SF SF	Tan			N/A 1	N/A No	N/A 1/D
1		Classroom 101 Classroom 101	M	Unit Ventilator Insulation	1380/01/01/HH	Assumed	1120	EA	0	EA	ran			1	No	1/D
1		Classroom 101	M	Sink Undercoat Mastic	1380/01/01/RR	Assumed	4	SF	0	SF		1 Sink		1	No	1/D
1		Classroom 101 Restroom	N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	64	SF	0	SF				N/A	N/A	N/A
1		Classroom 101 Restroom Classroom 101 Restroom	N/A N/A	CMU Ceramic Tile Floors		Non Suspect ACM Non Suspect ACM	288 64	SF SF	0	SF SF				N/A N/A	N/A N/A	N/A N/A
1		Hallway at Classroom 101	N/A	Plaster Ceiling		NAD	24	SF	0	SF				N/A	N/A N/A	N/A N/A
1	1	Hallway at Classroom 101	N/A	CMU		Non Suspect ACM	480	SF	0	SF				N/A	N/A	N/A
1	1	Hallway at Classroom 101	M	Floor Tile VAT 12" x 12"	1380/01/01/EE	Assumed	24	SF	0	SF	Tan			1	No	1/D
1		Stairwell next to Classroom 101 Stairwell next to Classroom 101	M N/A	Floor Tile VAT 12" x 12" Cement Floor	1380/01/01/EE	Assumed Non Suspect ACM	200 100	SF SF	0	SF SF	Tan	Concrete Stairs and Landing		N/A	No N/A	1/D N/A
1	1	Stairwell next to Classroom 101	N/A	Concrete Block Wall		Non Suspect ACM	900	SF	0	SF		Concrete Stairs and Earluing		N/A	N/A	N/A
1	1	Stairwell next to Classroom 101	N/A	Metal Ceiling		Non Suspect ACM	700	SF	0	SF				N/A	N/A	N/A
1		Stairwell next to Classroom 101	N/A	Ceiling Tile 2' x 4'		Non Suspect ACM	200	SF	0	SF				N/A	N/A	N/A
1		Stairwell next to Classroom 101 Office next to Conference Room	N/A N/A	Fiberglass Pipe Insulation Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM Non Suspect ACM	20 520	LF SF	0	LF SF				N/A N/A	N/A N/A	N/A N/A
1		Office next to Conference Room	N/A	CMU		Non Suspect ACM	828	SF	0	SF				N/A	N/A	N/A
1	1	Office next to Conference Room	M	Floor Tile VAT 12" x 12"	1380/01/01/EE	Assumed	520	SF	0	SF	Tan			1	No	1/D
1		Classroom 102	M M	Floor Tile VAT 12" x 12"	1380/01/01/EE	Assumed	1000	SF	0	SF	Tan			1	No	1/D
1		Classroom 102 Classroom 102	M N/A	Unit Ventilator Insulation CMU	1380/01/01/HH	Assumed Non Suspect ACM	3000	EA SF	0	EA SF				N/A	No N/A	1/D N/A
1	1	Classroom 102	N/A	Ceiling Tile 2' x 4'		Non Suspect ACM	1000	SF	0	SF				N/A	N/A	N/A
1		Classroom 102	М	Sink Undercoat Mastic	1380/01/01/RR	Assumed	12	SF	0	SF		1 Sink		1	No	1/D
1		Classroom 102 Restrooom Classroom 102 Restrooom	N/A N/A	Plaster Ceiling CMU		NAD Non Suggest ACM	48 252	SF SF	0	SF SF				N/A N/A	N/A N/A	N/A N/A
1		Classroom 102 Restroom Classroom 102 Restroom	N/A N/A	Ceramic Tile Floors		Non Suspect ACM Non Suspect ACM	48	SF	0	SF				N/A N/A	N/A N/A	N/A N/A
1	1	Classroom 102 Restrooom	M	Sink Undercoat Mastic	1380/01/01/RR	Assumed	3	SF	0	SF				1	No	1/D
1	1	Hallway at Classroom 102 to Gym	N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	104	SF	0	SF				N/A	N/A	N/A
1		Hallway at Classroom 102 to Gym	N/A M	CMU Floor Tile VAT 12" x 12"	1380/01/01/EE	Non Suspect ACM Assumed	420 104	SF SF	0	SF SF	Tan			N/A 1	N/A No	N/A 1/D
1	1	Hallway at Classroom 102 to Gym Hallway at from Classroom 101 to Auditorium	N/A	Fiberglass Ceiling Tile 2' x 4'	1300/01/01/EE	Non Suspect ACM	1125	SF	0	SF	Tan			N/A	N/A	N/A
1	1	Hallway at from Classroom 101 to Auditorium	N/A	CMU		Non Suspect ACM	1800	SF	0	SF				N/A	N/A	N/A
1		Hallway at from Classroom 101 to Auditorium	M	Floor Tile VAT 12" x 12"	1380/01/01/EE	Assumed	1125	SF	0	SF	Tan			1	No	1/D
1		Auditorium Auditorium	N/A N/A	Fiberglass Ceiling Tile 2' x 4' CMU		Non Suspect ACM Non Suspect ACM	3500 3600	SF SF	0	SF SF				N/A N/A	N/A N/A	N/A N/A
1		Auditorium	M M	Floor Tile VAT 12" x 12"	1380/01/01/EE	Assumed	3500	SF	0	SF	Tan			1	No No	1/D
1	1	Auditorium Stage	N/A	CMU		Non Suspect ACM	2400	SF	0	SF				N/A	N/A	N/A
1		Auditorium Stage	M	Floor Tile VAT 12" x 12"	1380/01/01/EE	Assumed	1500	SF	0	SF	Tan		1	1	No	1/D
1		Main Office Main Office	N/A N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM Non Suspect ACM	520 828	SF SF	0	SF SF				N/A N/A	N/A N/A	N/A N/A
1	1	Main Office	M	Floor Tile VAT 12" x 12"	1380/01/01/EE	Assumed	520	SF	0	SF	Tan			1	No	1/D
1		Office in Main Office closest to Classroom 101	N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	160	SF	0	SF				N/A	N/A	N/A
1	1	Office in Main Office closest to Classroom 101	N/A	CMU	1200/01/01/55	Non Suspect ACM	468	SF SF	0	SF	Ton			N/A	N/A	N/A
1	1	Office in Main Office closest to Classroom 101	M	Floor Tile VAT 12" x 12"	1380/01/01/EE	Assumed	160) SF	0	SF	Tan	L		1	No	1/D

		School District of Philadelphia		AHE	RA Three-Year Rein	spection 2015-2016						Reinspection Date: 11-4-15				
		Thomas G. Morton Elementary School			Room by Room Loca	-						Building Inspector: Shelton Williams	7			
		2501 S. 63rd Street, Philadelphia, PA 19142							1			Number: 046177				
		ULCS# 1380											-			
												Management Planner: Megan Vala	-			
E		Year Built: 1971				T		1				Number: 740728		1		
1	F														1	
e m	i														1	
e	0		System			Confirmed/Assumed/NAD	Amount of	SF LF	Amount of	SF LF	Color		Attic Crawl Space	Damage Potential	Newly Friable	Response
n t	r	On Site Room Name	Affected	Material Description	HID#	Non Suspect ACM	Material	EA	Damage	EA	required for VAT	Comments/Description/Notes	Ranking	(DP)	(NF)	Action (RA)
1	1	Office in Main Office behind Principal's Office	N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	69	SF	0	SF		·		N/A	N/A	N/A
1		Office in Main Office behind Principal's Office Office in Main Office behind Principal's Office	N/A M	CMU Floor Tile VAT 12" x 12"	1380/01/01/EE	Non Suspect ACM Assumed	378 96	SF SF	0	SF SF	Tan			N/A 1	N/A No	N/A 1/D
1	1	Principal's Office	N/A	Fiberglass Ceiling Tile 2' x 4'	1300/01/01/EE	Non Suspect ACM	240	SF	0	SF	Tall			N/A	N/A	N/A
1		Principal's Office	N/A	CMU		Non Suspect ACM	576	SF	0	SF				N/A	N/A	N/A
1		Principal's Office	M	Floor Tile VAT 12" x 12"	1380/01/01/EE	Assumed	240	SF	0	SF	Blue			1	No	1/D
1	1	Principal's Office Restroom Principal's Office Restroom	N/A N/A	Plaster Ceiling CMU		NAD Non Suspect ACM	80 324	SF SF	0	SF SF				N/A N/A	N/A N/A	N/A N/A
1		Principal's Office Restroom	N/A	Ceramic Tile Floors		Non Suspect ACM	80	SF	0	SF				N/A	N/A	N/A
1	1	Men's Staff Restroom at Auditorium	N/A	Plaster Ceiling		NAD	80	SF	0	SF				N/A	N/A	N/A
1		Men's Staff Restroom at Auditorium	N/A	CMU	1000/01/01/05	Non Suspect ACM	324	SF	0	SF	_			N/A	N/A	N/A
1		Men's Staff Restroom at Auditorium Women's Staff Restroom at Auditorium	M N/A	Floor Tile VAT 12" x 12" Plaster Ceiling	1380/01/01/EE	Assumed NAD	80	SF SF	0	SF SF	Tan			1 N/A	No N/A	1/D N/A
1		Women's Staff Restroom at Auditorium	N/A	CMU		Non Suspect ACM	324	SF	0	SF				N/A	N/A	N/A
1	1	Women's Staff Restroom at Auditorium	N/A	Ceramic Tile Floors		Non Suspect ACM	80	SF	0	SF				N/A	N/A	N/A
1		Conference Room next to Principal's Office	N/A	Plaster Ceiling		NAD	200	SF	0	SF				N/A	N/A	N/A
1		Conference Room next to Principal's Office Conference Room next to Principal's Office	N/A M	CMU Floor Tile VAT 12" x 12"	1380/01/01/EE	Non Suspect ACM Assumed	540 200	SF SF	0	SF SF	Tan			N/A 1	N/A No	N/A 1/D
1	1	Office across from Conference Room	N/A	Fiberglass Ceiling Tile 2' x 4'	1300/01/01/EE	Non Suspect ACM	96	SF	0	SF	Tall			N/A	N/A	N/A
		Office across from Conference Room	N/A	CMU		Non Suspect ACM	360	SF	0	SF				N/A	N/A	N/A
1		Office across from Conference Room	M	Floor Tile VAT 12" x 12"	1380/01/01/EE	Assumed	96	SF	0	SF	Tan			1	No	1/D
1	1	Hallway at Nurse's Office Hallway at Nurse's Office	N/A N/A	Fiberglass Ceiling Tile 2' x 4' CMU		Non Suspect ACM Non Suspect ACM	96 360	SF SF	0	SF SF				N/A N/A	N/A N/A	N/A N/A
1		Hallway at Nurse's Office	M	Floor Tile VAT 12" x 12"	1380/01/01/EE	Assumed	96	SF	0	SF	Tan			1	No.	1/D
1	1	Office next to Nurse's Office	N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	90	SF	0	SF				N/A	N/A	N/A
1	1	Office next to Nurse's Office	N/A	CMU	1000/01/01/05	Non Suspect ACM	342	SF	0	SF	_			N/A	N/A	N/A
1	1	Office next to Nurse's Office Nurse's Office Room 108B	M M	Floor Tile VAT 12" x 12" Floor Tile VAT 12" x 12"	1380/01/01/EE 1380/01/01/EE	Assumed Assumed	90 100	SF SF	0	SF SF	Tan Tan			1 1	No No	1/D 1/D
1		Nurse's Office Room 108B	N/A	CMU	1000/01/01/22	Non Suspect ACM	300	SF	0	SF	run			N/A	N/A	N/A
1	1	Nurse's Office Room 108B	N/A	Ceiling Tile 2' x 4'		Non Suspect ACM	100	SF	0	SF				N/A	N/A	N/A
1		Nurse's Office Room 108C Nurse's Office Room 108C	M N/A	Floor Tile VAT 12" x 12" CMU	1380/01/01/EE	Assumed Non Suspect ACM	120 360	SF SF	0	SF SF	Tan			1 N/A	No N/A	1/D N/A
1		Nurse's Office Room 108C	N/A	Ceiling Tile 2' x 4'		Non Suspect ACM	120	SF	0	SF				N/A	N/A	N/A
1		Nurse's Office Restroom	N/A	Plaster Ceiling		NAD	36	SF	0	SF				N/A	N/A	N/A
1		Nurse's Office Restroom	N/A	CMU		Non Suspect ACM	432	SF	0	SF				N/A	N/A	N/A
1		Nurse's Office Restroom Hallway at Nurse's Office	N/A N/A	Ceramic Tile Floors Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM Non Suspect ACM	36 77	SF SF	0	SF SF				N/A N/A	N/A N/A	N/A N/A
1	1	Hallway at Nurse's Office	N/A	CMU		Non Suspect ACM	324	SF	0	SF				N/A	N/A	N/A
1		Hallway at Nurse's Office	M	Floor Tile VAT 12" x 12"	1380/01/01/EE	Assumed	77	SF	0	SF	Tan			1	No	1/D
1		Nurse's Office 1	N/A N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	60 288	SF SF	0	SF SF				N/A N/A	N/A N/A	N/A
1		Nurse's Office 1	M M	Floor Tile VAT 12" x 12"	1380/01/01/EE	Non Suspect ACM Assumed	60	SF	0	SF	Tan			1 1	N/A No	N/A 1/D
1		Nurse's Office 2	N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	180	SF	0	SF				N/A	N/A	N/A
1		Nurse's Office 2	N/A	CMU		Non Suspect ACM	522	SF	0	SF				N/A	N/A	N/A
1	1	Nurse's Office 2 Nurse's Office 3	M N/A	Floor Tile VAT 12" x 12" Fiberglass Ceiling Tile 2' x 4'	1380/01/01/EE	Assumed Non Suspect ACM	180 60	SF SF	0	SF SF	Tan			1 N/A	No N/A	1/D N/A
1		Nurse's Office 3	N/A	CMU		Non Suspect ACM	288	SF	0	SF				N/A	N/A	N/A
1	1	Nurse's Office 3	М	Floor Tile VAT 12" x 12"	1380/01/01/EE	Assumed	60	SF	0	SF	Tan			1	No	1/D
1	1	Boy's Restroom	N/A	Plaster Ceiling		NAD Nac Occasión A OM	80	SF	0	SF				N/A	N/A	N/A
1	1	Boy's Restroom Boy's Restroom	N/A N/A	CMU Ceramic Tile Floors		Non Suspect ACM Non Suspect ACM	324 80	SF SF	0	SF SF			-	N/A N/A	N/A N/A	N/A N/A
1		Girl's Restroom	N/A N/A	Plaster Ceiling		Non Suspect ACM NAD	80	SF	0	SF			+	N/A N/A	N/A N/A	N/A N/A
1	1	Girl's Restroom	N/A	CMU		Non Suspect ACM	324	SF	0	SF				N/A	N/A	N/A
		Girl's Restroom	N/A	Ceramic Tile Floors		Non Suspect ACM	80	SF	0	SF			_	N/A	N/A	N/A
1	1	Cafeteria Cafeteria	N/A N/A	Fiberglass Ceiling Tile 2' x 4' CMU		Non Suspect ACM Non Suspect ACM	3290 3510	SF SF	0	SF SF				N/A N/A	N/A N/A	N/A N/A
1	1	Cafeteria	M	Floor Tile VAT 12" x 12"	1380/01/01/EE	Assumed	3290	SF	0	SF	Tan			1	No	1/D
1		Cafeteria Serving Line	M	Floor Tile VAT 12" x 12"	1380/01/01/EE	Assumed	180	SF	0	SF	Tan			1	No	1/D
1		Cafeteria Serving Line	N/A	CMU Metal Calling		Non Suspect ACM	540	SF	0	SF				N/A	N/A	N/A
1	1	Cafeteria Serving Line Loading Dock	N/A N/A	Metal Ceiling Fiberglass Pipe Insulation		Non Suspect ACM Non Suspect ACM	180	SF	0	SF LF			+	N/A N/A	N/A N/A	N/A N/A
	_	Loading Dock	N/A	Plaster Ceiling		NAD NAD	900	SF	0	SF				N/A	N/A	N/A
1	1	Loading Dock	N/A	CMU		Non Suspect ACM	1800	SF	0	SF				N/A	N/A	N/A
1	1	Loading Dock	N/A M	Cement Floor	1380/01/01/BB	Non Suspect ACM Assumed	900	SF SF	0	SF SF		2 VDC - 3 SF Each	+	N/A 1	N/A No	N/A 1/D
		Loading Dock Ramp inside of Loading Dock	N/A	Vibration Damper Cloth Cement Floor	1300/01/01/BB	Non Suspect ACM	80	SF	0	SF		2 VDC - 3 SF EBUII	+	N/A	No N/A	N/A
1		Ramp inside of Loading Dock	N/A	CMU		Non Suspect ACM	160	SF	0	SF				N/A	N/A	N/A
1	1	Ramp inside of Loading Dock	N/A	Ceiling Tile 2' x 4'		Non Suspect ACM	80	SF	0	SF			_	N/A	N/A	N/A
1		Ramp inside of Loading Dock Storage Room inside of Loading Dock	N/A N/A	Fiberglass Pipe Insulation Cement Floor		Non Suspect ACM Non Suspect ACM	90	LF SF	0	LF SF			+	N/A N/A	N/A N/A	N/A N/A
1		Storage Room inside of Loading Dock	N/A	CMU		Non Suspect ACM	270	SF	0	SF				N/A	N/A	N/A
1	1	Storage Room inside of Loading Dock	N/A	Ceiling Tile 2' x 4'		Non Suspect ACM	90	SF	0	SF				N/A	N/A	N/A

		School District of Philadelphia		AUE	RA Three-Year Reins	enaction 2015-2016						Reinspection Date: 11-4-15				
		Thomas G. Morton Elementary School			Room by Room Local											
		2501 S. 63rd Street, Philadelphia, PA 19142			Room by Room Loca	non Log Report						Building Inspector: Shelton Williams	1			
												Number: 046177	+			
		ULCS# 1380										Management Planner: Megan Vala	-			
E		Year Built: 1971								_		Number: 740728				
1	F															1
e m	1															1
e	0		System			Confirmed/Assumed/NAD	Amount of	SF LF	Amount of	SE 1 E	Color		Attic Crawl Space	Damage Potential	Newly Friable	Response
n t	r	On Site Room Name	Affected	Material Description	HID#	Non Suspect ACM	Material	EA	Damage	EA EA	required for VAT	Comments/Description/Notes	Ranking	(DP)	(NF)	Action (RA)
1	1	Kitchen	N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	330	SF	0	SF		·		N/A	N/A	N/A
1		Kitchen	N/A	CMU		Non Suspect ACM	738	SF	0	SF				N/A	N/A	N/A
1		Kitchen Storage	N/A N/A	Ceramic Tile Floors Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM Non Suspect ACM	330 120	SF SF	0	SF SF				N/A N/A	N/A N/A	N/A N/A
1		Kitchen Storage	N/A	CMU		Non Suspect ACM	468	SF	0	SF				N/A	N/A	N/A
1	1	Kitchen Storage	М	Floor Tile VAT 12" x 12"	1380/01/01/EE	Assumed	120	SF	0	SF	Tan			1	No	1/D
1		Hallway from Classroom 100 to 110	N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	1240	SF	0	SF				N/A	N/A	N/A
1	1	Hallway from Classroom 100 to 110 Hallway from Classroom 100 to 110	N/A M	CMU Floor Tile VAT 12" x 12"	1380/01/01/EE	Non Suspect ACM Assumed	2680 1240	SF SF	0	SF SF	Tan			N/A 1	N/A No	N/A 1/D
		Music Room	N/A	Fiberglass Ceiling Tile 2' x 4'	1000/01/01/22	Non Suspect ACM	560	SF	0	SF	Tall			N/A	N/A	N/A
1	1	Music Room	N/A	CMU		Non Suspect ACM	864	SF	0	SF				N/A	N/A	N/A
1	1	Music Room	M M	Floor Tile VAT 12" x 12" Unit Ventilator Insulation	1380/01/01/EE 1380/01/01/HH	Assumed	560	SF	0	SF	Tan			1	No	1/D 1/D
1		Music Room Office Next to Music Room	N/A	Fiberglass Ceiling Tile 2' x 4'	1380/01/01/HH	Assumed Non Suspect ACM	336	EA SF	0	EA SF				N/A	No N/A	N/A
1	1	Office Next to Music Room	N/A	CMU		Non Suspect ACM	684	SF	0	SF				N/A	N/A	N/A
1	1	Office Next to Music Room	М	Floor Tile VAT 12" x 12"	1380/01/01/EE	Assumed	336	SF	0	SF	Tan			1	No	1/D
1	1	Lounge at Music Room Lounge at Music Room	N/A N/A	Fiberglass Ceiling Tile 2' x 4' CMU		Non Suspect ACM Non Suspect ACM	336 684	SF SF	0	SF SF				N/A N/A	N/A N/A	N/A N/A
1	1	Lounge at Music Room Lounge at Music Room	M M	Floor Tile VAT 12" x 12"	1380/01/01/EE	Assumed	336	SF	0	SF	Tan		1	1	N/A No	1/D
1		Hallway from Teacher's Lounge to Cafeteria	N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	600	SF	0	SF				N/A	N/A	N/A
1		Hallway from Teacher's Lounge to Cafeteria	N/A M	CMU Floor Tile VAT 12" x 12"	1380/01/01/EE	Non Suspect ACM	1400	SF	0	SF SF	_			N/A	N/A	N/A
1		Hallway from Teacher's Lounge to Cafeteria Girl's Restroom	N/A	Plaster Ceiling	1380/01/01/EE	Assumed NAD	600 80	SF SF	0	SF	Tan			1 N/A	No N/A	1/D N/A
		Girl's Restroom	N/A	CMU		Non Suspect ACM	324	SF	0	SF				N/A	N/A	N/A
1	1	Girl's Restroom	N/A	Ceramic Tile Floors		Non Suspect ACM	80	SF	0	SF				N/A	N/A	N/A
1	1	Hallway from Classroom 110 to Gym	N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	168	SF	0	SF				N/A	N/A	N/A
1	1	Hallway from Classroom 110 to Gym Hallway from Classroom 110 to Gym	N/A M	CMU Floor Tile VAT 12" x 12"	1380/01/01/EE	Non Suspect ACM Assumed	400 168	SF SF	0	SF SF	Tan			N/A 1	N/A No	N/A 1/D
1		Gym	N/A	CMU	1000/01/01/22	Non Suspect ACM	11200	SF	0	SF	Tan			N/A	N/A	N/A
1		Gym	М	Floor Tile VAT 12" x 12"	1380/01/01/EE	Assumed	4800	SF	0	SF	Tan			1	No	1/D
1		Gym Office Gym Office	N/A N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM Non Suspect ACM	240 618	SF SF	0	SF SF				N/A N/A	N/A N/A	N/A N/A
1		Gym Office	M	Floor Tile VAT 12" x 12"	1380/01/01/EE	Assumed	240	SF	0	SF	Tan			1	No.	1/D
1	1	Gym Storage next to Gym Office	N/A	Fiberglass Pipe Fitting Insulation		Non Suspect ACM	15	SF	0	SF				N/A	N/A	N/A
1		Gym Storage next to Gym Office	N/A	Plaster Walls		NAD	594	SF	0	SF				N/A	N/A	N/A
1		Gym Storage next to Gym Office Gym Storage next to Gym Office	N/A N/A	CMU Ceramic Tile Floors		Non Suspect ACM Non Suspect ACM	882 594	SF SF	0	SF SF				N/A N/A	N/A N/A	N/A N/A
1		Gym Storage in Corner	N/A	Fiberglass Pipe Fitting Insulation		Non Suspect ACM	10	SF	0	SF				N/A	N/A	N/A
1	1	Gym Storage in Corner	N/A	Plaster Walls		NAD	486	SF	0	SF				N/A	N/A	N/A
11		Gym Storage in Corner	N/A	CMU Ceramic Tile Floors		Non Suspect ACM	810 486	SF SF	0	SF SF				N/A N/A	N/A	N/A
1		Gym Storage in Corner Stairwell next to Teacher's Lounge	N/A M	Floor Tile VAT 12" x 12"	1380/01/01/EE	Non Suspect ACM Assumed	200	SF	0	SF	Tan			1 1	N/A No	N/A 1/D
		Stairwell next to Teacher's Lounge	N/A	Cement Floor		Non Suspect ACM	100	SF	0	SF		Concrete Stairs and Landing		N/A	N/A	N/A
1		Stairwell next to Teacher's Lounge	N/A	Concrete Block Wall		Non Suspect ACM	900	SF	0	SF				N/A	N/A	N/A
1		Stainwell next to Teacher's Lounge	N/A N/A	Metal Ceiling		Non Suspect ACM Non Suspect ACM	700 200	SF SF	0	SF SF				N/A N/A	N/A N/A	N/A N/A
1		Stairwell next to Teacher's Lounge Stairwell next to Teacher's Lounge	N/A N/A	Ceiling Tile 2' x 4' Fiberglass Pipe Insulation		Non Suspect ACM	16	LF	0	LF			1	N/A N/A	N/A N/A	N/A N/A
1	1	Stairwell to Basement next to Loading Dock	N/A	Cement Floor		Non Suspect ACM	100	SF	0	SF				N/A	N/A	N/A
1	1	Stairwell to Basement next to Loading Dock	N/A	Concrete Block Wall		Non Suspect ACM	300	SF	0	SF SF				N/A	N/A	N/A
1	1	Stairwell to Basement next to Loading Dock Stairwell behind Cafeteria/Auditorium	N/A N/A	Fireproofing Cement Floor		NAD Non Suspect ACM	100 200	SF SF	0	SF				N/A N/A	N/A N/A	N/A N/A
1	1	Stairwell behind Cafeteria/Auditorium	N/A	Concrete Block Wall		Non Suspect ACM	600	SF	0	SF				N/A	N/A	N/A
1		Stairwell behind Cafeteria/Auditorium	N/A	Metal Ceiling		Non Suspect ACM	200	SF	0	SF				N/A	N/A	N/A
1		Stairwell behind Cafeteria/Auditorium	N/A N/A	Fiberglass Pipe Insulation		Non Suspect ACM	15 1430	LF SF	0	LF SF				N/A N/A	N/A N/A	N/A N/A
1	2	Classroom 200 Classroom 200	N/A N/A	Fiberglass Ceiling Tile 2' x 4' CMU		Non Suspect ACM Non Suspect ACM	1620	SF	0	SF				N/A N/A	N/A N/A	N/A N/A
1	2	Classroom 200	М	Floor Tile VAT 12" x 12"	1380/01/02/FF	Assumed	1430	SF	0	SF	Tan			1	No	1/D
1	2	Classroom 200	М	Unit Ventilator Insulation	1380/01/02/LL	Assumed	2	EA	0	EA		1011		1	No	1/D
1	2	Classroom 200 Classroom 200 Storage Closet	M N/A	Sink Undercoat Mastic Cement Floor	1380/01/02/FF	Assumed Non Suspect ACM	64	SF SF	0	SF SF		1 Sink	1	1 N/A	No N/A	1/D N/A
1	2	Classroom 200 Storage Closet	N/A	CMU		Non Suspect ACM	192	SF	0	SF				N/A	N/A	N/A N/A
1	2	Classroom 200 Storage Closet	N/A	Ceiling Tile 2' x 4'		Non Suspect ACM	64	SF	0	SF				N/A	N/A	N/A
4	2	Vestibule in Classroom 200 to Outdoor Roof Play Deck	N/A	Cement Floor		Non Suspect ACM	36	SF	0	SF				N/A	N/A	N/A
-		Vestibule in Classroom 200 to Outdoor Roof Play							U							IN/A
1	2	Deck Vestibule in Classroom 200 to Outdoor Roof Play	N/A	CMU		Non Suspect ACM	108	SF	0	SF				N/A	N/A	N/A
1	2	Vestibule in Classroom 200 to Outdoor Roof Play Deck	N/A	Ceiling Tile 2' x 4'		Non Suspect ACM	36	SF	0	SF				N/A	N/A	N/A
	2	Vestibule in Classroom 200 to Outdoor Roof Play	N/A					LE	0	LF					N/A	
1		Deck Classroom 200 Restroom	N/A N/A	Fiberglass Pipe Insulation Ceramic Tile Floors		Non Suspect ACM Non Suspect ACM	80	SF	0	SF			1	N/A N/A	N/A N/A	N/A N/A
1	2	Classroom 200 Restroom	N/A	CMU		Non Suspect ACM	240	SF	0	SF				N/A	N/A	N/A
1	2	Classroom 200 Restroom	N/A	Plaster Ceiling		NAD	80	SF	0	SF				N/A	N/A	N/A


	School District of Philadelphia		AH	ERA Three-Year Rein	enection 2015-2016						Reinspection Date: 11-4-15				
	Thomas G. Morton Elementary School		An	Room by Room Loca	•						Building Inspector: Shelton Williams				
	2501 S. 63rd Street, Philadelphia, PA 19142			Room by Room Loca	tion Log Report			_							
	·										Number: 046177	-			
	ULCS# 1380										Management Planner: Megan Vala	_			
-	Year Built: 1971										Number: 740728				
ī ,	_														
e m	,														
e (04			0		05 15		05.6	Color		Attic Crawl	Damage	Newly	
n t	On Site Room Name	System Affected	Material Description	HID#	Confirmed/Assumed/NAD Non Suspect ACM	Amount of Material	EA	Amount of Damage	SF LF EA	required for VAT	Comments/Description/Notes	Space Ranking	Potential (DP)	Friable (NF)	Response Action (RA)
	Hallway Storage Closet across from Classroom				-										
1 :	2 202	N/A	Cement Floor		Non Suspect ACM	36	SF	0	SF				N/A	N/A	N/A
1 1 1 2	Hallway Storage Closet across from Classroom 202	N/A	СМП		Non Suspect ACM	108	SF	0	SF				N/A	N/A	N/A
	Hallway Storage Closet across from Classroom														
1 1	2 202 2 Stairwell by Classroom 200	N/A N/A	Ceiling Tile 2' x 4' Cement Floor		Non Suspect ACM	36 300	SF SF	0	SF SF				N/A N/A	N/A N/A	N/A N/A
1 3		N/A	Concrete Block Wall		Non Suspect ACM Non Suspect ACM	900	SF	200	SF		Loose/Flaking Paint		N/A	N/A	N/A
	Stairwell by Classroom 200	N/A	Metal Ceiling		Non Suspect ACM	300	SF	0	SF		255557 laking Fairk		N/A	N/A	N/A
1 2		N/A	Plaster Ceiling		NAD	128	SF	0	SF				N/A	N/A	N/A
1 2		N/A	CMU Coromio Tilo Flooro		Non Suspect ACM	480	SF	0	SF				N/A	N/A	N/A
1 1		N/A N/A	Ceramic Tile Floors Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM Non Suspect ACM	128 900	SF SF	0	SF SF				N/A N/A	N/A N/A	N/A N/A
1 3		N/A	CMU		Non Suspect ACM	1200	SF	0	SF				N/A	N/A	N/A
1 2	Classroom 201	М	Floor Tile VAT 12" x 12"	1380/01/02/FF	Assumed	900	SF	0	SF	Green			1	No	1/D
1 :		M	Unit Ventilator Insulation	1380/01/02/LL	Assumed	1 6	EA	0	EA		1 Cink		1	No No	1/D
1 :		M N/A	Sink Undercoat Mastic Fiberglass Ceiling Tile 2' x 4'	1380/01/02/FF	Assumed Non Suspect ACM	6 900	SF SF	0	SF SF		1 Sink		1 N/A	No N/A	1/D N/A
1 :		N/A	CMU		Non Suspect ACM	1200	SF	0	SF				N/A	N/A	N/A
1 2	Classroom 202	M	Floor Tile VAT 12" x 12"	1380/01/02/FF	Assumed	900	SF	0	SF	Green			1	No	1/D
1 :		М	Unit Ventilator Insulation	1380/01/02/LL	Assumed	1	EA	0	EA				1	No	1/D
1 2	Classroom 202 Room between Classroom 200 and Girl's	M	Sink Undercoat Mastic	1380/01/02/FF	Assumed	6	SF	0	SF		1 Sink		1	No	1/D
1 2	Restroom	×	×		×	l x	×	×	x	x			×	x	x
	Room between Classroom 200 and Girl's														
1 2		N/A	X Plaster Ceiling		X NAD	128	X SF	0 0	SF	X			N/A	N/A	N/A
1 3		N/A	CMU		Non Suspect ACM	480	SF	0	SF				N/A	N/A N/A	N/A
1 3		N/A	Ceramic Tile Floors		Non Suspect ACM	128	SF	0	SF				N/A	N/A	N/A
1 2	Boy's Restroom across from Classroom 202	N/A	Plaster Ceiling		NAD	128	SF	0	SF				N/A	N/A	N/A
1 1	Boy's Restroom across from Classroom 202 Boy's Restroom across from Classroom 202	N/A N/A	CMU Ceramic Tile Floors		Non Suspect ACM Non Suspect ACM	480 128	SF SF	0	SF SF				N/A N/A	N/A N/A	N/A N/A
	Classroom 203	N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	900	SF	0	SF				N/A	N/A	N/A
	Classroom 203	N/A	CMU		Non Suspect ACM	1200	SF	0	SF				N/A	N/A	N/A
1 :		M	Floor Tile VAT 12" x 12"	1380/01/02/FF	Assumed	900	SF	0	SF	Green			1	No	1/D
1 1		M	Unit Ventilator Insulation Sink Undercoat Mastic	1380/01/02/LL 1380/01/02/FF	Assumed Assumed	1 6	EA SF	0	EA SF		1 Sink		1 1	No No	1/D
1 3		N/A	Fiberglass Ceiling Tile 2' x 4'	1300/01/02/FF	Non Suspect ACM	450	SF	0	SF		1 Silik	_	N/A	N/A	N/A
1 2		N/A	CMU		Non Suspect ACM	860	SF	0	SF				N/A	N/A	N/A
1 :		M	Floor Tile VAT 12" x 12"	1380/01/02/FF	Assumed	450	SF	0	SF	Tan			1	No	1/D
1 :		M	Unit Ventilator Insulation Sink Undercoat Mastic	1380/01/02/LL 1380/01/02/FF	Assumed Assumed	6	EA SF	0	EA SF		1 Sink		1 1	No No	1/D 1/D
1 3		N/A	Cement Floor	1300/01/02/11	Non Suspect ACM	200	SF	0	SF		1 Silik		N/A	N/A	N/A
1 2	Hallway from Classrooms 200 to 204	N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	1080	SF	0	SF				N/A	N/A	N/A
1 :		N/A	CMU	400010	Non Suspect ACM	1280	SF	0	SF				N/A	N/A	N/A
1 1		M N/A	Floor Tile VAT 12" x 12" Fiberglass Ceiling Tile 2' x 4'	1380/01/02/FF	Assumed Non Suspect ACM	1080 900	SF SF	0	SF SF	Tan			1 N/A	No N/A	1/D N/A
	Classroom 205	N/A N/A	CMU		Non Suspect ACM	1200	SF	0	SF				N/A N/A	N/A N/A	N/A N/A
1 2	Classroom 205	M	Floor Tile VAT 12" x 12"	1380/01/02/FF	Assumed	900	SF	0	SF	Tan			1	No	1/D
1 :		M	Unit Ventilator Insulation	1380/01/02/LL	Assumed	1	EA	0	EA		4 Olah		1	No	1/D
1 :		M N/A	Sink Undercoat Mastic Ceramic Tile Floors	1380/01/02/FF	Assumed Non Suspect ACM	6 80	SF SF	0	SF SF		1 Sink		1 N/A	No N/A	1/D N/A
1 3		N/A	Ceramic file Floors CMU		Non Suspect ACM	240	SF	0	SF				N/A	N/A	N/A
1 2	Classrooom 205 Restroom	N/A	Plaster Ceiling		NAD	80	SF	0	SF				N/A	N/A	N/A
1 :		N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	900	SF	0	SF				N/A	N/A	N/A
1 2		N/A M	CMU Floor Tile VAT 12" x 12"	1380/01/02/FF	Non Suspect ACM Assumed	1200 900	SF SF	0	SF SF	Tan			N/A 1	N/A No	N/A 1/D
1 2		M	Unit Ventilator Insulation	1380/01/02/LL	Assumed	1	EA	0	EA	Tall			1	No	1/D
1 2	Classroom 206	M	Sink Undercoat Mastic	1380/01/02/FF	Assumed	6	SF	0	SF		1 Sink		1	No	1/D
1 2		N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	80	SF	0	SF				N/A	N/A	N/A
1 1		N/A N/A	CMU Ceramic Tile Floors		Non Suspect ACM Non Suspect ACM	680 80	SF SF	0	SF SF				N/A N/A	N/A N/A	N/A N/A
	Classroom 206 Restroom - along naliway walii Classroom 206 Storage Closet	N/A N/A	Ceramic Tile Floors Cement Floor		Non Suspect ACM	64	SF	0	SF				N/A N/A	N/A N/A	N/A N/A
1 2	Classroom 206 Storage Closet	N/A	CMU		Non Suspect ACM	192	SF	0	SF				N/A	N/A	N/A
1 2	Classroom 206 Storage Closet	N/A	Ceiling Tile 2' x 4'		Non Suspect ACM	64	SF	0	SF				N/A	N/A	N/A
1 1		N/A N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	80 680	SF SF	0	SF SF				N/A N/A	N/A N/A	N/A N/A
1 3	Classroom 206 Restroom - along exterior wall Classroom 206 Restroom - along exterior wall	N/A N/A	Ceramic Tile Floors		Non Suspect ACM Non Suspect ACM	80	SF	0	SF				N/A N/A	N/A N/A	N/A N/A
1 3		N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	400	SF	0	SF				N/A	N/A	N/A
	Hallway at Classroom 206	N/A	CMU		Non Suspect ACM	1600	SF	0	SF				N/A	N/A	N/A
	Hallway at Classroom 206	M N/A	Floor Tile VAT 12" x 12"	1380/01/02/FF	Assumed Non Suspect ACM	400	SF	0	SF	Tan			1 N/A	No N/A	1/D
1 :	Stairwell between Classrooms 206 and 207 Stairwell between Classrooms 206 and 207	N/A N/A	Cement Floor Concrete Block Wall		Non Suspect ACM Non Suspect ACM	364 1092	SF SF	50	SF SF		Loose/Flaking Paint		N/A N/A	N/A N/A	N/A N/A
		1 1073	DOMOROGO DIOUR TYUII		THOSE COUPCON PROVIDE	1 .002	, Ji	1 30	, U		1 / mining / min		1 .00		1 10/0

		School District of Philadelphia		AHE	ERA Three-Year Rein	spection 2015-2016						Reinspection Date: 11-4-15				
		Thomas G. Morton Elementary School			Room by Room Loca							Building Inspector: Shelton Williams				
		2501 S. 63rd Street, Philadelphia, PA 19142			Room by Room Loca	tion Log Report							1			
												Number: 046177	+			
		ULCS# 1380										Management Planner: Megan Vala	-			
		Year Built: 1971										Number: 740728				
E	F															
e	ī															
m e	0										Color		Attic Crawl	Damage	Newly	
n	0	On Site Room Name	System Affected	Material Description	HID#	Confirmed/Assumed/NAD Non Suspect ACM	Amount of Material	SF LF	Amount of Damage		required for VAT	Comments/Description/Notes	Space Ranking	Potential (DP)	Friable (NF)	Response Action (RA)
1	2	Stairwell between Classrooms 206 and 207	N/A	Metal Ceiling	111211	Non Suspect ACM	364	SF	0	SF	· ·	Commenter Descriptions Notes	raming	N/A	N/A	N/A
1	2	Stairwell between Classrooms 206 and 207	N/A	Ceiling Tile 2' x 4'		Non Suspect ACM	64	SF	0	SF				N/A	N/A	N/A
1	2	Stairwell between Classrooms 206 and 207	N/A N/A	Fiberglass Pipe Insulation		Non Suspect ACM NAD	8 64	LF SF	0	LF		Above ACTs		N/A N/A	N/A N/A	N/A
1		Stairwell between Classrooms 206 and 207 Outdoor Roof Play Deck	N/A N/A	Fireproofing Cement Floor		Non Suspect ACM	2000	SF	0	SF SF		Above ACTs		N/A N/A	N/A N/A	N/A N/A
1	2	Outdoor Roof Play Deck	N/A	Brick Wall		Non Suspect ACM	6000	SF	0	SF				N/A	N/A	N/A
1	2	Classroom 207	N/A	CMU		Non Suspect ACM	1200	SF	0	SF				N/A	N/A	N/A
1		Classroom 207	M M	Floor Tile VAT 12" x 12"	1380/01/02/FF	Assumed	900	SF	0	SF	Tan			1	No	1/D
1		Classroom 207 Classroom 207	M	Unit Ventilator Insulation Sink Undercoat Mastic	1380/01/02/LL 1380/01/02/FF	Assumed Assumed	6	EA SF	0	EA SF		1 Sink		1	No No	1/D 1/D
1		Classroom 207	N/A	Fiberglass Ceiling Tile 2' x 4'	1000/01/02/1	Non Suspect ACM	900	SF	0	SF		Tomk		N/A	N/A	N/A
		Classroom 207 Restroom	N/A	Ceramic Tile Floors		Non Suspect ACM	80	SF	0	SF				N/A	N/A	N/A
1	2	Classroom 207 Restroom Classroom 207 Restroom	N/A N/A	CMU Plaster Ceiling		Non Suspect ACM NAD	240 80	SF SF	0	SF SF			1	N/A N/A	N/A N/A	N/A N/A
1	2	Classroom 207 Storage Closet	N/A	Cement Floor		Non Suspect ACM	64	SF	0	SF				N/A	N/A	N/A
1		Classroom 207 Storage Closet	N/A	CMU		Non Suspect ACM	192	SF	0	SF				N/A	N/A	N/A
1		Classroom 207 Storage Closet	N/A	Ceiling Tile 2' x 4'		Non Suspect ACM	64	SF	0	SF				N/A	N/A	N/A
1	2	Room outside Classroom 207 by Classroom 208 Classroom 208	X N/A	X Fiberglass Ceiling Tile 2' x 4'		X Non Suspect ACM	900	X SF	0 0	X SF	X			X N/A	X N/A	X N/A
1		Classroom 208	N/A	CMU		Non Suspect ACM	1200	SF	0	SF				N/A	N/A	N/A N/A
1		Classroom 208	M	Floor Tile VAT 12" x 12"	1380/01/02/FF	Assumed	900	SF	0	SF	Tan			1	No	1/D
1		Classroom 208	М	Unit Ventilator Insulation	1380/01/02/LL	Assumed	1	EA	0	EA				1	No	1/D
		Classroom 208	M	Sink Undercoat Mastic	1380/01/02/FF	Assumed	6	SF	0	SF		1 Sink		1	No	1/D
1		Classroom 208 Restroom Classroom 208 Restroom	N/A N/A	Plaster Ceiling CMU		NAD Non Suspect ACM	80 680	SF SF	0	SF SF				N/A N/A	N/A N/A	N/A N/A
1		Classroom 208 Restroom	N/A	Ceramic Tile Floors		Non Suspect ACM	80	SF	0	SF				N/A	N/A	N/A
1	2	Center Hallway outside Classroom 215	N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	1300	SF	0	SF				N/A	N/A	N/A
1		Center Hallway outside Classroom 215	N/A	CMU	1000 10 1 100 155	Non Suspect ACM	2700	SF	0	SF	_			N/A	N/A	N/A
1	2	Center Hallway outside Classroom 215 Classroom 209	M N/A	Floor Tile VAT 12" x 12" Fiberglass Ceiling Tile 2' x 4'	1380/01/02/FF	Assumed Non Suspect ACM	1300 450	SF SF	0	SF SF	Tan			N/A	No N/A	1/D N/A
		Classroom 209	N/A	CMU		Non Suspect ACM	860	SF	0	SF				N/A	N/A	N/A
1		Classroom 209	М	Floor Tile VAT 12" x 12"	1380/01/02/FF	Assumed	450	SF	0	SF	Tan			1	No	1/D
1	2	Classroom 209	M M	Unit Ventilator Insulation Sink Undercoat Mastic	1380/01/02/LL 1380/01/02/FF	Assumed	6	EA SF	0	EA SF		1 Sink		1	No No	1/D 1/D
1		Classroom 209 Storage Room next to Classroom 204	N/A	CMU	1300/01/02/FF	Assumed Non Suspect ACM	600	SF	0	SF		1 SIIIK		N/A	N/A	N/A
1		Storage Room next to Classroom 204	N/A	Ceiling Tile 2' x 4'		Non Suspect ACM	200	SF	0	SF				N/A	N/A	N/A
1	2	Storage Room next to Classroom 209	N/A	Cement Floor		Non Suspect ACM	200	SF	0	SF				N/A	N/A	N/A
1		Storage Room next to Classroom 209 Storage Room next to Classroom 209	N/A N/A	CMU Ceiling Tile 2' x 4'		Non Suspect ACM Non Suspect ACM	600 200	SF SF	0	SF SF				N/A N/A	N/A N/A	N/A N/A
1		Classroom 210	N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	900	SF	0	SF				N/A	N/A N/A	N/A N/A
1		Classroom 210	N/A	CMU		Non Suspect ACM	12	SF	0	SF				N/A	N/A	N/A
		Classroom 210	M M	Floor Tile VAT 12" x 12"	1380/01/02/FF	Assumed	900	SF	0	SF	Tan			1	No	1/D
1	2	Classroom 210 Classroom 210	M M	Unit Ventilator Insulation Sink Undercoat Mastic	1380/01/02/LL 1380/01/02/FF	Assumed Assumed	6	EA SF	0	EA SF		1 Sink		1	No No	1/D 1/D
		Classroom 211	N/A	Fiberglass Ceiling Tile 2' x 4'	1000/01/02/11	Non Suspect ACM	900	SF	0	SF		TOTIK		N/A	N/A	N/A
		Classroom 211	N/A	CMU		Non Suspect ACM	1200	SF	0	SF				N/A	N/A	N/A
1		Classroom 211	M	Floor Tile VAT 12" x 12"	1380/01/02/FF	Assumed	900	SF	0	SF	Tan			1	No	1/D
1	2	Classroom 211 Classroom 211	M M	Unit Ventilator Insulation Sink Undercoat Mastic	1380/01/02/LL 1380/01/02/FF	Assumed Assumed	6	EA SF	0	EA SF		1 Sink		1	No No	1/D 1/D
<u> </u>		Elevator next to Girl's Restroom across from										I On M		<u> </u>		
1	2	Classroom 211	M	Floor Tile VAT 12" x 12"	1380/01/02/FF	Assumed	30	SF	0	SF	Tan			1	No	1/D
1		Girl's Restroom across from Classroom 211 Girl's Restroom across from Classroom 211	N/A N/A	Ceramic Tile Floors		Non Suspect ACM Non Suspect ACM	200 600	SF SF	0	SF SF			1	N/A N/A	N/A N/A	N/A N/A
1		Girl's Restroom across from Classroom 211	N/A	Plaster Ceiling		NAD	200	SF	0	SF				N/A	N/A	N/A
1		Boy's Restroom across from Classroom 211	N/A	Plaster Ceiling		NAD	200	SF	0	SF				N/A	N/A	N/A
	2	Boy's Restroom across from Classroom 211	N/A N/A	CMU		Non Suspect ACM	600	SF SF	0	SF SF				N/A N/A	N/A N/A	N/A
1	2	Boy's Restroom across from Classroom 211 Classroom 213 Storage Room/Electrical Closet	N/A N/A	Ceramic Tile Floors Cement Floor		Non Suspect ACM Non Suspect ACM	200 64	SF	0	SF				N/A N/A	N/A N/A	N/A N/A
1	2	Classroom 213 Storage Room/Electrical Closet	N/A	CMU		Non Suspect ACM	192	SF	0	SF				N/A	N/A	N/A
1	2	Classroom 213 Storage Room/Electrical Closet	N/A	Plaster Ceiling		NAD	64	SF	0	SF				N/A	N/A	N/A
1		Classroom 213 Classroom 213	N/A N/A	Fiberglass Ceiling Tile 2' x 4' CMU		Non Suspect ACM Non Suspect ACM	300 740	SF SF	0	SF SF			1	N/A N/A	N/A N/A	N/A N/A
1	2	Classroom 213	M M	Floor Tile VAT 12" x 12"	1380/01/02/FF	Assumed	300	SF	0	SF	Tan			1 1	N/A No	1/D
1	2	Classroom 213	М	Unit Ventilator Insulation	1380/01/02/LL	Assumed	1	EA	0	EA				1	No	1/D
1	2	Girl's Restroom next to Classroom 213	N/A	Plaster Ceiling		NAD	200	SF	0	SF				N/A	N/A	N/A
1	2	Girl's Restroom next to Classroom 213 Girl's Restroom next to Classroom 213	N/A N/A	CMU Ceramic Tile Floors		Non Suspect ACM Non Suspect ACM	600 200	SF SF	0	SF SF			1	N/A N/A	N/A N/A	N/A N/A
		Classroom 212	N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	900	SF	0	SF			1	N/A	N/A	N/A N/A
1	2	Classroom 212	N/A	CMU		Non Suspect ACM	1200	SF	0	SF				N/A	N/A	N/A
1		Classroom 212	M	Floor Tile VAT 12" x 12"	1380/01/02/FF	Assumed	900	SF	0	SF	Tan			1	No	1/D
		Classroom 212 Classroom 212	M M	Unit Ventilator Insulation Sink Undercoat Mastic	1380/01/02/LL 1380/01/02/FF	Assumed Assumed	6	EA SF	0	EA SF		1 Sink		1	No No	1/D 1/D
	1 4	01000100111 2 12	IVI	On In Office Coat Madub	1000/01/02/11	riodullicu		- 01				1 On m			110	110

		School District of Philadelphia		AHE	RA Three-Year Rein	spection 2015-2016						Reinspection Date: 11-4-15				
		Thomas G. Morton Elementary School			Room by Room Loca	•						Building Inspector: Shelton Williams				
		2501 S. 63rd Street, Philadelphia, PA 19142										Number: 046177				
		ULCS# 1380										Management Planner: Megan Vala	1			
													+			
E	_	Year Built: 1971										Number: 740728				
1	F															1
e m	1													_		1
e	0		System			Confirmed/Assumed/NAD	Amount of	SE IE	Amount of	SE I E	Color required for		Attic Crawl Space	Damage Potential	Newly Friable	Response
n t	r	On Site Room Name	Affected	Material Description	HID#	Non Suspect ACM	Material	EA	Damage		VAT	Comments/Description/Notes	Ranking	(DP)	(NF)	Action (RA)
1		Classroom 212 Restroom	N/A	Plaster Ceiling		NAD	80	SF	0	SF				N/A	N/A	N/A
1	2	Classroom 212 Restroom	N/A N/A	CMU Ceramic Tile Floors		Non Suspect ACM	680 80	SF SF	0	SF				N/A N/A	N/A N/A	N/A
1		Classroom 212 Restroom Classroom 214	N/A N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM Non Suspect ACM	675	SF	0	SF SF				N/A N/A	N/A N/A	N/A N/A
1		Classroom 214	N/A	CMU		Non Suspect ACM	1040	SF	0	SF				N/A	N/A	N/A
1	2	Classroom 214	М	Floor Tile VAT 12" x 12"	1380/01/02/FF	Assumed	675	SF	0	SF	Tan			1	No	1/D
1		Classroom 214 Storage	X	X		X	X	X	X	X	х			X	X	X
1		Hallway from Classrooms 209 to 214 Hallway from Classrooms 209 to 214	N/A N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM Non Suspect ACM	1080 1280	SF SF	0	SF SF				N/A N/A	N/A N/A	N/A N/A
1	2	Hallway from Classrooms 209 to 214	M M	Floor Tile VAT 12" x 12"	1380/01/02/FF	Assumed	1080	SF	0	SF	Tan			1	No No	1/D
1		Stairwell by Classroom 214	N/A	Cement Floor		Non Suspect ACM	300	SF	0	SF				N/A	N/A	N/A
1	2	Stairwell by Classroom 214	N/A	Concrete Block Wall		Non Suspect ACM	900	SF	200	SF		Loose/Flaking Paint		N/A	N/A	N/A
1	2	Stairwell by Classroom 214 Custodial Closet next to Classroom 212	N/A N/A	Metal Ceiling Cement Floor		Non Suspect ACM Non Suspect ACM	300 16	SF SF	0	SF SF				N/A N/A	N/A N/A	N/A N/A
1		Custodial Closet next to Classroom 212 Custodial Closet next to Classroom 212	N/A N/A	Concrete Block Wall		Non Suspect ACM Non Suspect ACM	16 48	SF	0	SF				N/A N/A	N/A N/A	N/A N/A
1		Custodial Closet next to Classroom 212	N/A	Ceiling Tile 2' x 4'		Non Suspect ACM	16	SF	0	SF				N/A	N/A	N/A
1		Custodial Closet next to Classroom 212	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	1	LF	0	LF				N/A	N/A	N/A
1	2	Custodial Closet next to Classroom 212	N/A	Fiberglass Pipe Fitting Insulation		Non Suspect ACM	900	EA	0	EA SF				N/A	N/A	N/A
1	3	Classroom 300 Classroom 300	N/A N/A	Fiberglass Ceiling Tile 2' x 4' CMU		Non Suspect ACM Non Suspect ACM	1200	SF SF	0	SF				N/A N/A	N/A N/A	N/A N/A
1	3	Classroom 300	M	Floor Tile VAT 12" x 12"	1380/01/03/GG	Assumed	900	SF	0	SF	Tan			1	No.	1/D
1		Classroom 300	М	Unit Ventilator Insulation	1380/01/03/MM	Assumed	1	EA	0	EA				1	No	1/D
		Classroom 300	М	Sink Undercoat Mastic	1380/01/03/PP	Assumed	6	SF	0	SF		1 Sink		1	No	1/D
1	3	Stairwell outside Classroom 300 Stairwell outside Classroom 300	N/A N/A	Cement Floor Concrete Block Wall		Non Suspect ACM Non Suspect ACM	300 900	SF SF	200	SF SF		Loose/Flaking Paint		N/A N/A	N/A N/A	N/A N/A
1	3	Stairwell outside Classroom 300 Stairwell outside Classroom 300	N/A N/A	Metal Ceiling		Non Suspect ACM	300	SF	200	SF		Loose/Flaking Paint Loose/Flaking Paint		N/A N/A	N/A N/A	N/A N/A
1		Custodial Closet next to Classroom 301	N/A	Cement Floor		Non Suspect ACM	25	SF	0	SF		E003C/T laking T aint		N/A	N/A	N/A
1	3	Custodial Closet next to Classroom 301	N/A	Concrete Block Wall		Non Suspect ACM	75	SF	0	SF				N/A	N/A	N/A
1	3	Custodial Closet next to Classroom 301	N/A	Ceiling Tile 2' x 4'		Non Suspect ACM	25	SF	0	SF				N/A	N/A	N/A
1		Classroom 301 Classroom 301	N/A N/A	Fiberglass Ceiling Tile 2' x 4' CMU		Non Suspect ACM Non Suspect ACM	900 1200	SF SF	0	SF SF				N/A N/A	N/A N/A	N/A N/A
1		Classroom 301	M	Floor Tile VAT 12" x 12"	1380/01/03/GG	Assumed	900	SF	0	SF	Pink			1	No.	1/D
1	3	Classroom 301	М	Unit Ventilator Insulation	1380/01/03/MM	Assumed	1	EA	0	EA				1	No	1/D
		Classroom 301	М	Sink Undercoat Mastic	1380/01/03/PP	Assumed	6	SF	0	SF		1 Sink		1	No	1/D
1	3	Staff Restroom next to Classroom 301 Staff Restroom next to Classroom 301	N/A N/A	Ceramic Tile Floors		Non Suspect ACM Non Suspect ACM	80 240	SF SF	0	SF SF				N/A N/A	N/A N/A	N/A N/A
1	3	Staff Restroom next to Classroom 301	N/A	Plaster Ceiling		NAD NAD	80	SF	0	SF				N/A	N/A	N/A N/A
		Office 302	N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	600	SF	0	SF				N/A	N/A	N/A
1	3	Office 302	N/A	CMU		Non Suspect ACM	900	SF	0	SF				N/A	N/A	N/A
1	3	Office 302	М	Floor Tile VAT 12" x 12"	1380/01/03/GG	Assumed	900	SF SF	0	SF SF	Tan			1	No	1/D
1		Classroom 303 Classroom 303	N/A N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM Non Suspect ACM	900	SF	0	SF				N/A N/A	N/A N/A	N/A N/A
1		Classroom 303	M	Floor Tile VAT 12" x 12"	1380/01/03/GG	Assumed	900	SF	0	SF	Tan			1	No	1/D
1	3	Classroom 303	М	Unit Ventilator Insulation	1380/01/03/MM	Assumed	1	EA	0	EA				1	No	1/D
1	3	Boy's Restroom across from Classroom 303	N/A	Plaster Ceiling		NAD	200	SF	0	SF				N/A	N/A	N/A
1	3	Boy's Restroom across from Classroom 303 Boy's Restroom across from Classroom 303	N/A N/A	CMU Ceramic Tile Floors		Non Suspect ACM Non Suspect ACM	600 200	SF SF	0	SF SF				N/A N/A	N/A N/A	N/A N/A
1		Girl's Restroom across from Classroom 303	N/A	Plaster Ceiling		NAD	200	SF	0	SF				N/A	N/A	N/A
1	3	Girl's Restroom across from Classroom 303	N/A	CMU		Non Suspect ACM	600	SF	0	SF				N/A	N/A	N/A
1	3	Girl's Restroom across from Classroom 303	N/A	Ceramic Tile Floors		Non Suspect ACM	200	SF	0	SF				N/A	N/A	N/A
1	3	Storage next to Girl's Restroom across from Classroom 303	N/A	Cement Floor		Non Suspect ACM	160	SF	0	SF				N/A	N/A	N/A
	Ť	Storage next to Girl's Restroom across from														
1	3	Classroom 303	N/A	Concrete Block Wall		Non Suspect ACM	480	SF	0	SF				N/A	N/A	N/A
1	3	Storage next to Girl's Restroom across from Classroom 303	N/A	Ceiling Tile 2' x 4'		Non Suspect ACM	160	SF	0	SF				N/A	N/A	N/A
1	3	Classroom 304	N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	900	SF	0	SF				N/A	N/A	N/A
1		Classroom 304	N/A	CMU		Non Suspect ACM	1200	SF	0	SF				N/A	N/A	N/A
1		Classroom 304 Classroom 304	M M	Floor Tile VAT 12" x 12" Unit Ventilator Insulation	1380/01/03/GG 1380/01/03/MM	Assumed Assumed	900	SF EA	0	SF EA	Tan			1 1	No No	1/D 1/D
1	3	Classroom 304 Classroom 304	M	Sink Undercoat Mastic	1380/01/03/MM 1380/01/03/PP	Assumed	6	SF	0	SF		1 Sink		1	No	1/D
1		Classroom 305	N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	350	SF	0	SF				N/A	N/A	N/A
1	_	Classroom 305	N/A	CMU		Non Suspect ACM	780	SF	0	SF				N/A	N/A	N/A
1	3	Classroom 305	M	Floor Tile VAT 12" x 12"	1380/01/03/GG	Assumed	350	SF	0	SF	Tan			1	No	1/D
1	3	Classroom 305 Classroom 305	M M	Unit Ventilator Insulation Sink Undercoat Mastic	1380/01/03/MM 1380/01/03/PP	Assumed Assumed	6	EA SF	0	EA SF		1 Sink	1	1 1	No No	1/D 1/D
1		Storage Room next to Classroom 305	N/A	Cement Floor	7300/01/03/11	Non Suspect ACM	200	SF	0	SF		1 Onik		N/A	N/A	N/A
1	3	Storage Room next to Classroom 305	N/A	CMU		Non Suspect ACM	600	SF	0	SF				N/A	N/A	N/A
1	3	Storage Room next to Classroom 305	N/A	Ceiling Tile 2' x 4'		Non Suspect ACM	200	SF	0	SF				N/A	N/A	N/A
1		Classroom 306 Classroom 306	N/A N/A	Fiberglass Ceiling Tile 2' x 4' CMU		Non Suspect ACM Non Suspect ACM	900 1200	SF SF	0	SF SF				N/A N/A	N/A N/A	N/A N/A
		Classroom 306	M M	Floor Tile VAT 12" x 12"	1380/01/03/GG	Assumed	900	SF	0	SF	Pink			1	N/A No	1/D
<u> </u>																

		Cohool District of Dhiladelati-										L				
		School District of Philadelphia		AH	ERA Three-Year Rein	•						Reinspection Date: 11-4-15				
		Thomas G. Morton Elementary School			Room by Room Loca	tion Log Keport			J			Building Inspector: Shelton Williams	_			
		2501 S. 63rd Street, Philadelphia, PA 19142										Number: 046177				
		ULCS# 1380										Management Planner: Megan Vala				
		Year Built: 1971										Number: 740728				
E	_															
e m	F															
m e	0										Color		Attic Crawl	Damage	Newly	
n	0	On Site Room Name	System Affected	Material Description	HID#	Confirmed/Assumed/NAD Non Suspect ACM	Amount of Material	SF LF EA		SF LF EA	required for VAT	Comments/Description/Notes	Space Ranking	Potential	Friable	Response
1	3	Classroom 306	M	Unit Ventilator Insulation	1380/01/03/MM	Assumed	iviateriai 1	EA	Damage 0	EA	VAI	Comments/Description/Notes	Ranking	(DP)	(NF) No	Action (RA)
1	3	Classroom 307	N/A	Fiberglass Ceiling Tile 2' x 4'	1000/01/00/WW	Non Suspect ACM	900	SF	0	SF				N/A	N/A	N/A
		Classroom 307	N/A	CMU		Non Suspect ACM	1200	SF	0	SF				N/A	N/A	N/A
		Classroom 307	М	Floor Tile VAT 12" x 12"	1380/01/03/GG	Assumed	900	SF	0	SF	Pink			1	No	1/D
1	_	Classroom 307 Classroom 307	M	Unit Ventilator Insulation Sink Undercoat Mastic	1380/01/03/MM 1380/01/03/PP	Assumed Assumed	6	EA SF	0	EA SF		1 Sink		1	No No	1/D 1/D
1		Hallway from Classrooms 300 to 306	N/A	Fiberglass Ceiling Tile 2' x 4'	1300/01/03/PP	Non Suspect ACM	1080	SF	0	SF		1 Silik		N/A	N/A	N/A
1	3	Hallway from Classrooms 300 to 306	N/A	CMU		Non Suspect ACM	2360	SF	ő	SF				N/A	N/A	N/A
1		Hallway from Classrooms 300 to 306	М	Floor Tile VAT 12" x 12"	1380/01/03/GG	Assumed	1080	SF	0	SF	Tan			1	No	1/D
1		IMC (Library)	N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	3360	SF	0	SF SF				N/A	N/A N/A	N/A N/A
		IMC (Library) IMC (Library)	N/A M	CMU Floor Tile VAT 12" x 12"	1380/01/03/GG	Non Suspect ACM Assumed	2400 3360	SF SF	0	SF	Green			N/A 1	N/A No	1/D
1		IMC (Library)	M	Unit Ventilator Insulation	1380/01/03/MM	Assumed	3	EA	0	EA	GIECH			1	No	1/D
1	3	Classroom 308A in IMC	N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	476	SF	Ō	SF				N/A	N/A	N/A
1		Classroom 308A in IMC	N/A	CMU		Non Suspect ACM	960	SF	0	SF				N/A	N/A	N/A
		Classroom 308A in IMC	M	Floor Tile VAT 12" x 12"	1380/01/03/GG	Assumed	476	SF	0	SF	Tan	4 Olyl		1	No	1/D
1		Classroom 308A in IMC Office 308B in IMC	M N/A	Sink Undercoat Mastic Fiberglass Ceiling Tile 2' x 4'	1380/01/03/PP	Assumed Non Suspect ACM	6 476	SF SF	0	SF SF		1 Sink		N/A	No N/A	1/D N/A
		Office 308B in IMC	N/A N/A	CMU		Non Suspect ACM Non Suspect ACM	960	SF	0	SF				N/A N/A	N/A N/A	N/A N/A
		Office 308B in IMC	М	Floor Tile VAT 12" x 12"	1380/01/03/GG	Assumed	476	SF	0	SF	Tan			1	No	1/D
1	3	Office 308B in IMC	М	Sink Undercoat Mastic	1380/01/03/PP	Assumed	6	SF	0	SF		1 Sink		1	No	1/D
1		Hallway outside of IMC	N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	1320	SF	0	SF				N/A	N/A	N/A
1		Hallway outside of IMC	N/A M	CMU	4000/04/04/11/04/11/0500	Non Suspect ACM	2840	SF	0	SF		Constitution A COAC HOARI Hordon		N/A	N/A	N/A
1		Hallway outside of IMC Hallway outside of IMC	M	Black Mastic a/w Tan Floor Tile Floor Tile VAT 12" x 12"	1380/01/01/USA/NJ/2500 1380/01/03/GG	Confirmed Confirmed	1320 1320	SF SF	0	SF SF	Tan	Sampled March 1, 2016 USA/N. Harrison Sampled March 1, 2016 USA/N. Harrison		1	No No	1/D 1/D
1		Classroom 309	N/A	Fiberglass Ceiling Tile 2' x 4'	1000/01/00/00	Non Suspect ACM	900	SF	0	SF	Tuit	Campion March 1, 2010 COVIII. Harrison		N/A	N/A	N/A
1	3	Classroom 309	N/A	CMU		Non Suspect ACM	1200	SF	0	SF				N/A	N/A	N/A
		Classroom 309	М	Floor Tile VAT 12" x 12"	1380/01/03/GG	Assumed	900	SF	0	SF	Green			1	No	1/D
1		Classroom 309	M M	Unit Ventilator Insulation	1380/01/03/MM 1380/01/03/PP	Assumed	1 6	EA SF	0	EA SF		1 Sink		1	No	1/D 1/D
	3	Classroom 309 Classroom 310	N/A	Sink Undercoat Mastic Fiberglass Ceiling Tile 2' x 4'	1380/01/03/PP	Assumed Non Suspect ACM	900	SF	0	SF		1 Sink		N/A	No N/A	N/A
	3	Classroom 310	N/A	CMU		Non Suspect ACM	1200	SF	0	SF				N/A	N/A	N/A
1		Classroom 310	М	Floor Tile VAT 12" x 12"	1380/01/03/GG	Assumed	900	SF	0	SF	Green			1	No	1/D
		Classroom 310	М	Unit Ventilator Insulation	1380/01/03/MM	Assumed	1	EA	0	EA				1	No	1/D
		Classroom 310	M	Sink Undercoat Mastic	1380/01/03/PP	Assumed	6	SF	0	SF		1 Sink		1	No	1/D
1	_	Classroom 311	N/A N/A	Fiberglass Ceiling Tile 2' x 4' CMU		Non Suspect ACM	900 1200	SF SF	0	SF SF				N/A N/A	N/A N/A	N/A N/A
1		Classroom 311 Classroom 311	M M	Floor Tile VAT 12" x 12"	1380/01/03/GG	Non Suspect ACM Assumed	900	SF	0	SF	Tan			1 1 1	No.	1/D
		Classroom 311	M	Unit Ventilator Insulation	1380/01/03/MM	Assumed	1	EA	0	EA	Tall			1	No	1/D
1	3	Classroom 311	М	Sink Undercoat Mastic	1380/01/03/PP	Assumed	6	SF	0	SF		1 Sink		1	No	1/D
1	3	Classroom 312	N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	900	SF	0	SF				N/A	N/A	N/A
		Classroom 312	N/A	CMU	4000/04/00/00	Non Suspect ACM	1200	SF	0	SF	T			N/A	N/A	N/A
1	3	Classroom 312 Classroom 312	M M	Floor Tile VAT 12" x 12" Unit Ventilator Insulation	1380/01/03/GG 1380/01/03/MM	Assumed Assumed	900	SF FA	0	SF EA	Tan			1	No No	1/D 1/D
1	-	Classroom 312	M	Sink Undercoat Mastic	1380/01/03/MW	Assumed	6	SF	0	SF		1 Sink		1	No	1/D
1	3	Hallway from IMC to Classroom 310	N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	840	SF	0	SF				N/A	N/A	N/A
	3	Hallway from IMC to Classroom 310	N/A	CMU	1000/07/	Non Suspect ACM	3360	SF	0	SF				N/A	N/A	N/A
1		Hallway from IMC to Classroom 310	M N/A	Floor Tile VAT 12" x 12" Cement Floor	1380/01/03/GG	Assumed Non Support ACM	840 364	SF SF	0	SF SF	Tan			N/A	No N/A	1/D N/A
1		Stairwell by Classroom 310 Stairwell by Classroom 310	N/A N/A	Cement Floor Concrete Block Wall		Non Suspect ACM Non Suspect ACM	1092	SF	0	SF				N/A N/A	N/A N/A	N/A N/A
1		Stairwell by Classroom 310	N/A	Metal Ceiling		Non Suspect ACM	364	SF	0	SF				N/A	N/A	N/A
1	3	Stairwell by Classroom 310	N/A	Ceiling Tile 2' x 4'		Non Suspect ACM	64	SF	0	SF				N/A	N/A	N/A
1		Stairwell by Classroom 310	N/A	Fireproofing		NAD	64	SF	0	SF		Above ACTs		N/A	N/A	N/A
		Classroom 314	N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	900	SF	0	SF				N/A	N/A	N/A
1	3	Classroom 314 Classroom 314	N/A M	CMU Floor Tile VAT 12" x 12"	1380/01/03/GG	Non Suspect ACM Assumed	1200 900	SF SF	0	SF SF	Tan			N/A 1	N/A No	N/A 1/D
1		Classroom 314	M	Unit Ventilator Insulation	1380/01/03/MM	Assumed	1	EA	0	EA	1411			1	No	1/D
1	3	Stairwell next to Classroom 315	М	Floor Tile VAT 12" x 12"	1380/01/01/EE	Assumed	200	SF	0	SF	Tan			1	No	1/D
		Stairwell next to Classroom 315	N/A	Cement Floor		Non Suspect ACM	100	SF	0	SF		Concrete Stairs and Landing		N/A	N/A	N/A
1		Stairwell next to Classroom 315	N/A	Concrete Block Wall		Non Suspect ACM	900	SF SF	0	SF SF		Lagas/Flaking Point		N/A	N/A	N/A
1		Stairwell next to Classroom 315 Stairwell next to Classroom 315	N/A N/A	Metal Ceiling Ceiling Tile 2' x 4'		Non Suspect ACM Non Suspect ACM	200	SF	200	SF		Loose/Flaking Paint		N/A N/A	N/A N/A	N/A N/A
1		Staff Restroom next to Classroom 315	N/A N/A	Plaster Ceiling		Non Suspect ACM NAD	80	SF	0	SF			+	N/A N/A	N/A N/A	N/A N/A
1		Staff Restroom next to Classroom 315	N/A	CMU		Non Suspect ACM	680	SF	0	SF				N/A	N/A	N/A
1		Staff Restroom next to Classroom 315	N/A	Ceramic Tile Floors		Non Suspect ACM	80	SF	0	SF				N/A	N/A	N/A
1		Custodial Closet next to Classroom 315	N/A	Plaster Ceiling		NAD	25	SF	0	SF				N/A	N/A	N/A
1		Custodial Closet next to Classroom 315	N/A	CMU		Non Suspect ACM	100	SF	0	SF				N/A	N/A	N/A
1		Custodial Closet next to Classroom 315 Classroom 313	N/A M	Ceramic Tile Floors Floor Tile VAT 12" x 12"	1380/01/03/GG	Non Suspect ACM Assumed	25 560	SF SF	0	SF SF	Tan			N/A 1	N/A No	N/A 1/D
		Classroom 313	M	Unit Ventilator Insulation	1380/01/03/MM	Assumed	1	EA	0	EA				1	No	1/D
1	3	Classroom 313	N/A	CMU		Non Suspect ACM	1680	SF	0	SF				N/A	N/A	N/A
		Classroom 313	N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	560	SF	0	SF				N/A	N/A	N/A

	School District of Philad	elphia		AH	ERA Three-Year Rein	spection 2015-2016						Reinspection Date: 11-4-15				
	Thomas G. Morton Elementary	School			Room by Room Loca	tion Log Report						Building Inspector: Shelton Williams				
	2501 S. 63rd Street, Philadelphia.				•							Number: 046177				
	ULCS# 1380	FA 19142										Management Planner: Megan Vala				
	Year Built: 1971											Number: 740728				
e m e n	F I O O O O O Site Room Name		System ffected	Material Description	HID#	Confirmed/Assumed/NAD Non Suspect ACM	Amount of Material	SF LF EA	Amount of Damage	SF LF EA	Color required for VAT	Comments/Description/Notes	Attic Crawl Space Ranking	Damage Potential (DP)	Newly Friable (NF)	Response Action (RA)
1	3 Classroom 313		N/A	Fiberglass Pipe Insulation	111011	Non Suspect ACM	20	LF	0	LF		Commenter Decomptions voted	rtaming	N/A	N/A	N/A
	3 Classroom 315		N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	900	SF	0	SF				N/A	N/A	N/A
	3 Classroom 315		N/A	CMU		Non Suspect ACM	1200	SF	0	SF				N/A	N/A	N/A
1			M	Floor Tile VAT 12" x 12"	1380/01/03/GG	Assumed	900	SF.	0	SF	Blue			1	No	1/D
1			M	Unit Ventilator Insulation	1380/01/03/MM	Assumed	1	EA.	0	EA	Dido			<u> </u>	No	1/D
1			M	Sink Undercoat Mastic	1380/01/03/PP	Assumed	6	SF	0	SF		1 Sink		1	No	1/D
1			N/A	Fiberglass Ceiling Tile 2' x 4'	100001100111	Non Suspect ACM	900	SF	1 0	SF				N/A	N/A	N/A
1			N/A	CMU		Non Suspect ACM	1200	SF	0	SF				N/A	N/A	N/A
1			M	Floor Tile VAT 12" x 12"	1380/01/03/GG	Assumed	900	SF	0	SF	Pink			1	No	1/D
	3 Classroom 316		M	Unit Ventilator Insulation	1380/01/03/MM	Assumed	1	EA	0	EA	1 11115			1	No	1/D
1			M	Sink Undercoat Mastic	1380/01/03/PP	Assumed	6	SF	0	SF		1 Sink		1	No	1/D
1			N/A	Cement Floor	1300/01/03/11	Non Suspect ACM	64	SF	0	SF		1 Olik		N/A	N/A	N/A
	3 Storage Room/Electrical Closet next to		N/A	CMU		Non Suspect ACM	192	SF	0	SF				N/A	N/A	N/A
1			N/A	Plaster Ceiling		NAD	64	SF	0	SF				N/A	N/A	N/A
1			N/A	Plaster Ceiling		NAD	200	SF	0	SF				N/A	N/A	N/A
1			N/A	CMU		Non Suspect ACM	600	SF	0	SF				N/A	N/A	N/A
1			N/A	Ceramic Tile Floors		Non Suspect ACM	200	SF	0	SF				N/A	N/A	N/A
	3 Girl's Restroom across from Classroom		N/A	Plaster Ceiling		NAD NAD	200	SF	0	SF				N/A	N/A	N/A
1			N/A	CMU		Non Suspect ACM	600	SF	0	SF				N/A	N/A	N/A
	3 Girl's Restroom across from Classroom		N/A	Ceramic Tile Floors		Non Suspect ACM	200	SF	0	SF				N/A	N/A	N/A
1			N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	900	SF	0	SF			_	N/A	N/A	N/A
1			N/A N/A	CMU		Non Suspect ACM Non Suspect ACM	1200	SF	0	SF				N/A N/A	N/A N/A	N/A N/A
1			M M	Floor Tile VAT 12" x 12"	1380/01/03/GG	Assumed	900	SF	0	SF	Black			1 1	No.	1/D
1			M						+		Віаск			+ · · · ·		
1			M	Unit Ventilator Insulation	1380/01/03/MM 1380/01/03/PP	Assumed	6	EA SF	0	EA SF		1 Sink		1 1	No No	1/D 1/D
			N/A	Sink Undercoat Mastic	1380/01/03/PP	Assumed						1 SIRK		N/A		N/A
1				Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	350 780	SF SF	0	SF SF					N/A	
1			N/A	CMU	1000/04/00/00	Non Suspect ACM					T			N/A	N/A	N/A
1			M M	Floor Tile VAT 12" x 12"	1380/01/03/GG 1380/01/03/MM	Assumed	350	SF EA	0	SF EA	Tan			1 1	No	1/D 1/D
			N/A	Unit Ventilator Insulation Cement Floor	138U/U1/U3/IVIVI	Assumed Non Suspect ACM	200	SF		SF	-			N/A	No N/A	1/D N/A
1			N/A N/A	Cement Floor CMU			600	SF	0	SF				N/A N/A	N/A N/A	N/A N/A
1			N/A N/A			Non Suspect ACM	200	SF	0	SF	-			N/A N/A	N/A N/A	N/A N/A
1			N/A N/A	Ceiling Tile 2' x 4'		Non Suspect ACM	900	SF	0	SF	1			N/A N/A	N/A N/A	N/A N/A
			N/A N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	1200	SF		SF	1			N/A N/A		N/A N/A
1					1000/04/00/00	Non Suspect ACM			0		T				N/A	
1		-	M	Floor Tile VAT 12" x 12"	1380/01/03/GG	Assumed	900	SF	0	SF	Tan			1	No	1/D
1			M	Unit Ventilator Insulation	1380/01/03/MM	Assumed	1	EA	0	EA	1	4 0/-/		1	No	1/D
1			M	Sink Undercoat Mastic	1380/01/03/PP	Assumed	6	SF	0	SF	-	1 Sink		1	No	1/D
1			N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	900	SF	0	SF				N/A	N/A	N/A
1			N/A	CMU	1000101100100	Non Suspect ACM	1200	SF	0	SF	-			N/A	N/A	N/A
1			M	Floor Tile VAT 12" x 12"	1380/01/03/GG	Assumed	900	SF	0	SF	Tan			1	No	1/D
	3 Classroom 320		M	Unit Ventilator Insulation	1380/01/03/MM	Assumed	1 1	EA	0	EA				1	No	1/D
	3 Hallway from Classrooms 314 to 318		N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	1080	SF	0	SF				N/A	N/A	N/A
	3 Hallway from Classrooms 314 to 318		N/A	CMU	1000101100100	Non Suspect ACM	2360	SF	0	SF	-			N/A	N/A	N/A
	3 Hallway from Classrooms 314 to 318		М	Floor Tile VAT 12" x 12"	1380/01/03/GG	Assumed	1080	SF	0	SF	Tan			1	No	1/D
	AT Attic		х	X		X	X	X	X	X		None	None	X	X	X
1 1 (CS Crawlspace	1	x I	X		X	1 x	l x	l x	l x	1	None	None	X	1 x	X



Section III - A

Management Planner/Building Inspector Certificates

These charts indicate the Name, Course Date, Expiration Date and Corresponding Certificate Number of the Management Planner and Building Inspector of individuals that participated in the AHERA 3 Year Inspection and Management Plan process of 2015/2016.

Management Planner	Date Granted	Expiration Date	Certificate Number
Monique Causley	2/15/2015	2/16/2016	ACC-0215-8-010
Monique Causley	2/16/2016	2/17/2017	ACC-0216-8-001
Megan Vala	5/22/2015	6/22/2016	740728
Mary Anne Lerro	4/5/2016	4/5/2017	742327

Building Inspector	Date Granted	Expiration Date	Certificate Number
Scott Magee	8/15/2015	8/15/2016	70016699C
William Garrity	8/15/2015	8/15/2016	70016699A
Bernard Brunner	10/2/2015	8/2/2016	45397
Mary Anne Lerro	3/3/2015	3/3/2016	740092
Mary Anne Lerro	4/5/2016	4/5/2017	742322
James Madden	12/11/2014	12/11/2015	ACC-1214-6-010
James Madden	12/3/2015	12/3/2016	ACC-1215-6-018
Troy Ray	3/15/2015	3/19/2016	ACC-0355-6-011
Ananth Vinjamuri	9/29/2015	9/29/2016	374
Shelton Williams	9/29/2015	9/29/2016	375
Paul Davis	2/12/2015	2/12/2016	ACC-0215-6-015
Paul Davis	2/2/2016	2/2/2017	741836
Bernard Bryson	2/16/2015	2/16/2016	ACC-0125-6-031
Bernard Bryson	2/15/2016	2/15/2017	ACC-0216-6-005
Alexander Roman	9/18/2015	9/18/2016	EHSBIR-150619-008
Norm Harrison	9/2/2015	9/2/2016	ACC-0915-6-011
Kelly Mayberry	2/20/2015	2/20/2016	EHSBIR-150220-005
Kelly Mayberry	2/18/2016	2/18/2017	EHSBIR-160218-006
Andrew Hine	5/6/2015	5/6/2016	AI05042015-3
Maryellen Leotta	2/12/2015	2/12/2016	ACC-0215-6-024

awarded to

Monique Causley

for successfully completing the prescribed course of study in

Pennsylvania Asbestos Management Planner Refresher Course

under TSCA Title II

presented by

ACCESS TRAINING SERVICES, INC. 7921 River Road, Pennsauken, NJ 08110

(856) 665-3449

Course Date

Exam Date

ACC-0215-8-010 Certificate Number

Social Security Number

Not Provided

Mark K. Schläger

Training Director

awarded to

Monique Causley for successfully completing the prescribed course of study in

Pennsylvania Asbestos Management Planner Refresher Course

under TSCA Title II

ACCESS TRAINING SERVICES, INC. presented by

7921 River Road, Pennsauken, NJ 08110 (856) 665-3449

2/15/16

Course Date

Not Provided
Social Security Number

Exam Date

ACC-0216-8-001 Certificate Number

2/15/17

Mark K. Schläger Training Director

Certificate of Iraining

CRITERION LABORATORIES, INC.

HEREBY CERTIFIES THAT

Megan Vala

HAS SUCCESSFULLY COMPLETED A 16 HOUR COURSE ENTITLED

Asbestos Management Planner Initial

INCLUDING CLASSROOM INSTRUCTION

05/21/2015 to 05/22/2015

Exam passed on this 22nd day of May 2015 - Score - 94

Approved for AHERA Accreditation Under TSCA Title II

3370 Progress Drive, Suite J
Bensalem, PA 19020
(215) 244-1300 - Phone

Course is conducted in English

www.criterionlabs.com

DIRECTOR:

Drive

James A. Weltz, CIH, President

Certificate of Iraining

CRITERION LABORATORIES, INC. HEREBY CERTIFIES THAT

Mary Anne Lerro

HAS SUCCESSFULLY COMPLETED A 4 HOUR COURSE ENTITLED

Asbestos Management Planner Refresher INCLUDING CLASSROOM INSTRUCTION

on this 5th day of April 2016

Approved for AHERA Accreditation Under TSCA Title II

3370 Progress Drive, Suite J (215) 244-1300 - Phone (215) 244-4349 - Fax Bensalem, PA 19020

Course is conducted in English

www.criterionlabs.com

DIRECTOR:

g-cust

James A. Weltz, CIH, President

EMSL ANALYTICAL, INC.

Certifies that

Scott Magee

has successfully completed the course of study for the

Asbestos Building Inspector Refresher Course

for Accreditation under TSCA Title II

EMSL Certificate No. 70016699C

Approved by:

Accreditation # 137 PA Dept of Labor and Industry

> Course Date: 8/15/2015 Granted: 8/15/2015

Expiration Date: 8/15/2016

Sponsored by:

EMSL Analytical, Inc. 200 Route 130 North Phone: (800) 220-3675 Cinnaminson, NJ 08077

Fax: (856) 786-5973 www.emsl.com

Training Director Michael P. Menz, CIH

My Dry Carlo

Environmental, Mold, Bacteria, IAQ, Asbestos, Lead, Forensic and Materials Testing Since 1981

EMSL ANALYTICAL, INC.

Certifies that

William Garrity

has successfully completed the course of study for the

Asbestos Building Inspector Refresher Course

for Accreditation under TSCA Title II

EMSL Certificate No. 70016699A

Approved by:

Accreditation # 137 PA Dept. of Labor and Industry

> Course Date: 8/15/2015 Expiration Date: 8/15/2016 Granted: 8/15/2015

Sponsored by:

Cinnaminson, NJ 08077 200 Route 130 North EMSL Analytical, Inc. Phone: (800) 220-3675

Fax: (856) 786-5973 www.cmsl.com

> Michael P. Menz, CIH Training Director

Environmental, Mold, Bacteria, IAQ, Asbestos, Lead, Forensic and Materials Testing Since 1981

45397

National Asbestos & Environmental Training Institute CERTIFICATE OF COMPLETION

AHERA/EPA Accredited Per 40 CFR Part 763
Asbestos Accreditation under TSCA Title II

This is to certify that •

Bernard Brunner, Jr.

Successfully completed the course entitled

1/2-Day New York State/EPA/AHERA Asbestos Building Inspector Annual Refresher on October 2, 2015

Examination Passed October 2, 2015

Expiration Date on October 2, 2016

President, NAETI

Per 10 NYCRR Part 73.2 (L) (1), DOH 2832 Certificate of Completion of Asbestos Safety Training is the only official record of training for N.Y.S. students.

Language: English

ABIH 1/2 CM POINT

3321 Doris Avenue, Building B, Ocean, NJ 07712

Phone (732) 531-5571

Fax (732) 531-5956

www.naeti.com

Certificate of Iraining

CRITERION LABORATORIES, INC.

HEREBY CERTIFIES THAT

Mary Anne Lerro

Asbestos Building Inspector Refresher

HAS SUCCESSFULLY COMPLETED A 4 HOUR COURSE ENTITLED

on this 3rd day of March 2015

Exam passed on this 3rd day of March 2015 - Score - 84

Approved for AHERA Accreditation Under TSCA Title II

3370 Progress Drive, Suite J

(215) 244-1300 - Phone

(215) 244-4349 - Fax

www.criterionlabs.com

Course is conducted in English

DIRECTOR:

g-custo

James A. Weltz, CIH, President

Certificate of Iraining

CRITERION LABORATORIES, INC. HEREBY CERTIFIES THAT

Mary Anne Lerro

HAS SUCCESSFULLY COMPLETED A 4 HOUR COURSE ENTITLED

Asbestos Building Inspector Refresher

INCLUDING CLASSROOM INSTRUCTION

on this 5th day of April 2016

Exam passed on this 5th day of April 2016 - Score - 88

Approved for AHERA Accreditation Under TSCA Title II

3370 Progress Drive, Suite J Bensalem, PA 19020 (215) 244-1300 - Phone

(215) 244-1300 - Phone (215) 244-4349 - Fax www.criterionlabs.com

Course is conducted in English

DIRECTOR:

gruss.

James A. Weltz, CIH, President

James Madden

for successfully completing the prescribed course of study in

Building Inspector Refresher Course Pennsylvania Asbestos

under TSCA Title II

presented by ACCESS TRAINING SERVICES, INC.

7921 River Road, Pennsauken, NJ 08110 (856) 665-3449

12/11/14
Course Date

N/A

Exam Date

12/11/1

Not Provided
Social Security Number

ACC-1214-6-010

Certificate Number

Expiration Date

Man

Mark K. Schläger Training Director

James Madden

for successfully completing the prescribed course of study in

Building Inspector Refresher Course Pennsylvania Asbestos

under TSCA Title II

presented by ACCESS TRAINING SERVICES, INC. 7921 River Road, Pennsauken, NJ 08110 (856) 665-3449

Course Date

Exam Date

ACC-1215-6-018

12/3/16
Expiration Date

Mark K. Schläger

Training Director

Certificate Number

ACA ACA ACA

Social Security Number **Not Provided**

Troy A. Ray for successfully completing the prescribed course of study in

Building Inspector Refresher Course Pennsylvania Asbestos under TSCA Title II

presented by

ACCESS TRAINING SERVICES, INC. 7921 River Road, Pennsauken, NJ 08110 (856) 665-3449

Social Security Number Not Provided Course Date 3/19/15 ACC-0355-6-011 Certificate Number 3/19/16
Expiration Date Mark K. Schläger Training Director

G&C Environmental Services, Inc. (#294) 2 Street Road, Newtown Square, Pennsylvania 19073

Telephone: (610) 993-9202 Facsimile: (610) 993-9232

Email: Training@gcenviro.com www.GCenviro.com

This document certifies that Ananth K. Vinjamuri has successfully completed this

State of New York Department of Health Approved AHERA BUILDING INSPECTOR

REFRESHER COURSE, completed as required for asbestos accreditation under the Toxic

Substances Control Act, Title II. This course was held from $\frac{09/29/2015}{MM$ DD YR MM DD YR successful completion of the examination ___ The examination date was $\frac{09/29/2015}{MM$ DD YR 09/29/2016.

The official record of successful training completion is the New York State Department of Health certificate of asbestos safety training completion (DPH 2832).

Hail M. Conner

Gail M. Conner Training Director

G&C Environmental Services, Inc. (#294)

2 Street Road, Newtown Square, Pennsylvania 19073 Telephone: (610) 993-9202 Facsimile: (610) 993-9232

Email: Training@gcenviro.com

www.GCenviro.com

This document certifies thatSh
<u>ıelton Williams</u>
has successfully completed this

State of New York Department of Health Approved AHERA BUILDING INSPECTOR REFRESHER COURSE, completed as required for asbestos accreditation under the Toxic

Substances Control Act, Title II. This course was held from $\frac{09/29/2015}{MM$ DD YR MM DD YR successful completion of the examination $\frac{09/29/2016}{MM$ DD YR The examination date was $\frac{09/29/2015}{MM$ DD YR

The official record of successful training completion is the New York State Department of Health certificate of asbestos safety training completion (DPH 2832).

Hailm, Conner

Gail M. Conner
Training Director

Paul M. Davis

for successfully completing the prescribed course of study in

Building Inspector Refresher Course Pennsylvania Asbestos

under TSCA Title II

presented by ACCESS TRAINING SERVICES, INC. 7921 River Road, Pennsauken, NJ 08110

(856) 665-3449

Social Security Number Not Provided Course Date ACC-0215-6-015 Certificate Number Exam Date Mark K. Schläger Expiration Date 2/12/16

Training Director

Number 741836

Expiration Date: 02/02/2017

Certificate of Irainas

CRITERION LABORATORIES, INC

HEREBY CERTIFIES THAT

Paul M. Davis

HAS SUCCESSFULLY COMPLETED A 4 HOUR COURSE ENTERLIED

Asbestos Building Inspector Refresher

NCL UDING OLASSROOM INSTRUCTION

on this 2nd day of February 2016

ed on this Znd day of Echruary 2016 - Score - 92

Iames A. Weltz, CIH, Presiden gruss

Course is conducted in English

3370 Progress Drive, Suite J (215) 244-1300 - Phone (215) 244-4349 - Fax

Bernard J. Bryson

for successfully completing the prescribed course of study in

Building Inspector Refresher Course Pennsylvania Asbestos under TSCA Title II

presented by
ACCESS TRAINING SERVICES, INC. 7921 River Road, Pennsauken, NJ 08110 (856) 665-3449

Social Security Number	Not Provided	Course Date	2/16/15
Certificate Number	ACC-0125-6-031	Exam Date	N/A
Mark K. Schläger Training Director	May 5 Serving	Expiration Date	2/16/16

Bernard J. Bryson

for successfully completing the prescribed course of study in


Building Inspector Refresher Course Pennsylvania Asbestos under TSCA Title II

presented by ACCESS TRAINING SERVICES, INC. 7921 River Road, Pennsauken, NJ 08110 (856) 665-3449

rtificate Number	CC-0216-6-005	Exam Date	N/A
/ Mark K. Schlager Training Director	Mah 2 soll	Expiration Date	2/15/17

Not Provided
Social Security Number

2/15/16
Course Date



Norman Harrison

for successfully completing the prescribed course of study in

Building Inspector Refresher Course Pennsylvania Asbestos under TSCA Title II

Illust 1904 rice is

presented by ACCESS TRAINING SERVICES, INC. 7921 River Road, Pennsauken, NJ 08109 (856) 665-3449

Social Security Number Not Provided Course Date ACC-0915-6-011 Certificate Number Exam Date Training Director Mark K. Schläge Expiration Date 9/2/16

EHS TRAINING INSTITUTE, INC.

A Division of BATTA, Inc.

Certificate of Completion AHERA Building Inspector (Refresher)

Awarded To:

Kelly Mayberry

SS#:XXX-XX-1551

Who has completed this 4-hour course and examination, EPA Approved under TSCA Title II AHERA / ASHARA Rule
40 CFR Part 763.

EHS TRAINING INSTITUTE, INC.

A Division of BATTA, Inc.

Delaware Industrial Park • 6 Garfield Way

Newark, DE 19713-5817

(302) 737-3376 • Fax (302) 737-5764

Course Date: February 20, 2015

Date of Expiration: February 20, 2016

Certification Number: EHSBIR 150220-005

Todd K. Zeisloft, Instructor

Neeraj K. Batta, President

EHS TRAINING INSTITUTE, INC.

A Division of BATTA, Inc

Certificate of Completion

AHERA Building Inspector (Refresher)

Awarded To:

Kelly Mayberry

SS#:XXX-XX-1551

Who has completed this 4-hour course and examination, EPA Approved under TSCA Title II AHERA / ASHARA Rule 40 CFR Part 763.

EHS TRAINING INSTITUTE, INC.

A Division of BATTA, Inc.

Delaware Industrial Park • 6 Garfield Way

Newark, DE 19713-5817

(302) 737-3376 • Fax (302) 737-5764

Course Date: February 18, 2016

Date of Expiration: February 18, 2017

Certification Number : EHSBIR 160218-006

Todd K. Zeisloft, Instructor

Neeraj K. Batta, President

AEROSOL MONITORING & ANALYSIS, INC.

This is to certify that

ANDREW HINE

has met the attendance requirements and successfully completed

the course entitled

3-DAY EPA AHERA INSPECTOR

For Accreditation Under TSCA Title II

Certification No.	AI05042015-3	Course Date	05/04/2015 to 05/06/2015
		Exam Date	05/06/2015
		Expiration Date	5/6/2016
Course Director	E. Rush Barnett	2.00	STEVE SIERACKI
	E. Rad Bandt		for & Nohn-

1331 Ashton Road

P.O.Box 646

Hanover, MD 21076

P: 410-684-3327

F: 410-684-3724

www.amatraining.com

Maryellen Leotta

for successfully completing the prescribed course of study in

Building Inspector Refresher Course Pennsylvania Asbestos under TSCA Title II

presented by

ACCESS TRAÍNING SERVICES, INC. 7921 River Road, Pennsauken, NJ 08110 (856) 665-3449

2/12/15 N/A
Course Date Exam Date

.

ACC-0215-6-024
Certificate Number

Not Provided
Social Security Number

2/12/16

Expiration Date

Mark K. Schläger
Training Director

Asbestos Hazard Emergency Response Act (AHERA) Environmental Compliance Audit Cross Reference Table

In response to the AHERA Environmental Compliance Audit a Cross Reference Table has been prepared for inclusion into the Environmental Management Plan. The purpose of this Cross Reference Table is to link the following documents to the AHERA Management Plan.

Cross Reference Table

3 Year Reinspection Report follows this Cross Reference Table documentation.

Subject Matter	Location of Required Documents		
Designated Person	Pages 1 - 3		
Annual Notification	Pages 4 - 5		
6 Month Periodic Surveillance Outline of Events	Page 6		
3 Year Re-inspections Outline of Events	Page 7		
Asbestos Management Program (operations and maintenance)	Pages 8 - 19		
Asbestos Investigation Report (AIR)	Attachment 1 Letter Dated August 4, 2006		
Training (included in the Asbestos Management Program)	The original records are centralized at the School District's Environment Library. Copies are maintained on staff and are required to be maintained the latest Reinspection Report. 2 hour awareness training records for all Building Engineers, Custod Assistants and maintenance personnel 40 hour worker/supervisor training records for the OEMS A-Team a various AST tradesmen.		
Response Actions	The original documents are on file at the School District's Environmen Library.		
(monthly mailings if applicable)	Copies of the original are mailed to the Schools Main Office for retenti with the Management Plan documentation. These documents are typica kept separate from the management plan in an update binder due to t potential volume of response action reports.		

SCHOOL DISTRICT OF PHILADELPHIA

ASBESTOS DESIGNATED PERSON

Gerald F Junod
Office of Capital Programs
Environmental Management & Services
440 N Broad Street, 3rd Floor
Philadelphia, PA 19130
Telephone: 215 400 6738
Fax: 215 400 4751

Drexel University- Asbestos Building Inspector Course

Drexel University- Asbestos Management Planner Course

Criterion Laboratories, Inc. - Asbestos Management Planner Course October 11-12, 2012 16 Hours

Annual Building Inspector Refreshers

1990 to Present

4 Hours
Drexel University
Criterion Laboratories, Inc
Access Training Services, Inc.

Annual Building Management Planner Refreshers

1990 to 1994

4 Hours
Drexel University
Criterion Laboratories, Inc
4 Hours

2013 to Present

Environmental Manager, School District of Philadelphia

Manages the design and implementation of asbestos and lead projects for the Capital Improvement Program and other District Departments including Facilities & Operations and Information Technology. Ensures that asbestos abatement and lead remediation projects are expertly designed and executed in accordance with industry best management practice standards and regulations.

Manager, City of Philadelphia Asbestos Control Program

Served as the Asbestos Control Program Manager for the City of Philadelphia, Department of Public Health, Air Management Services, Asbestos Control Unit from August 1, 2003 through October 23, 2006.

Mid Atlantic Regional Environmental Consortium (MAREC)

Former member with attendance and participation commitments of all quarterly EPA Region III and yearly National Asbestos Regulatory Conferences sponsored by the EPA and the National Conference of State Legislators respectively as a representative for the City of Philadelphia Department of Public Health Air Management Services from 1994 through 2006.

Philadelphia Environmental Task Force

Former member of the Philadelphia Environmental Task force as a representative and point of contact for the City of Philadelphia Department of Public Health Air Management Services Asbestos Control Unit from 2002 through 2006.

Asbestos Instructor

Worked as the primary instructor for the initial and annual Asbestos Project Inspector training and licensing program as mandated by City of Philadelphia Department of Pubic Health Asbestos Control Regulations from August 1994 through October 2006.

Worked as a lead instructor with an Environmental Consulting Firm and approved by the US EPA for the initial and annual refresher training courses for various asbestos occupational disciplines such as the Building Inspector, Management Planner and Worker/Supervisor from 1991 through 1994.

I certify that the general, local agency responsibilities as stipulated in Section 763.84 will be met.

Gerald F. Junod

Asbestos Designated Person

Environmental Manager

Office of Environmental Management and Services

SCHOOL DISTRICT OF PHILADELPHIA

Accreditation Information Statement

All persons who inspect for Asbestos Containing Building Materials (ACBM) and who will design or carry our response actions with respect to assumed and confirmed ACBM, will be accredited by an EPA approved course and/or a State Contractors AccreditationProgram under Sections 206 (c) and 206 (b) of Title II of the ACT.

Gerald F. Junod

Asbestos Designated Person Environmental Manager

Office of Environmental Management and Services

SCHOOL DISTRICT OF PHILADELPHIA OFFICE OF CAPITAL PROGRAMS 440 NORTH BROAD STREET, SUITE 373 PHILADELPHIA, PENNSYLVANIA 19130

OFFICE OF ENVIRONMENTAL MANAGEMENT AND SERVICES

PHONE (215)-400-4750

September 2015

TO:

Principals

Building Administrators/Occupants

Parents/Guardians

FROM:

Fran Burns

Chief Operating Officer

Francine Locke, M.S., Director

Office of Environmental Management and Services

SUBJECT:

Annual EPA Notification Letter

Pursuant to the Federal Environmental Protection Agency (EPA) mandate, as required by 40 C.F.R. 763.84 (c)(d) of public access to environmental records, this letter is to acknowledge the availability of your facility's Asbestos Hazard Emergency Response Act (AHERA) Management Plan.

Each member of the school staff, parents/guardians, temporary workers and/or contractors, are required to receive a copy of the Notification Letter. At the direction of the Principal, a copy is to be posted on the bulletin boards and an appropriate amount of copies are to be generated for distribution.

Note: The AHERA Three-Year Reinspection reports, in colored binders; White with Pink, Tan, Black, Red, Dark Blue, Green, Yellow and White, are Federal EPA mandated inspection documents. The School District of Philadelphia is subject to severe monetary penalties if the reports and associated paperwork are not available to the EPA and the public upon request.

It is incumbent on designated school personnel to gather and retain this data as it is delivered, in one location for future review. Acceptable locations include the Principal's Office or Main Office for the primary data. The Building Engineer should maintain any secondary or duplicate copies.

If you have any questions, please call 215-400-4750. Thank you for your cooperation.

Fran Burns

Chief Operating Officer

Francine Locke, M.S., Director

Office of Environmental Management

and Services

c: Danielle Floyd

AHERA-4 8/21/15



School District of Philadelphia OFFICIAL NOTICE

PLEASE POST

September 2015

TO:

Principals

Building Administrators Building Engineers Building Occupants Parents/Guardians

FROM:

Fran Burns

Chief Operating Officer

Francine Locke, M.S., Director

Office of Environmental Management and Services

SUBJECT:

Annual Notification Letter: Asbestos Hazard Emergency Response Act

The Federal Register published on October 30, 1987, Subpart E, in Schools: Final Rule and Notice, 763.84 (c)(d) states that each local education agency shall ensure that workers and building occupants or guardians are to be informed at least once each school year about inspections, response actions and post-response action activities including re-inspections and periodic surveillance activities. The School District as the Local Education Agency (LEA), retains such reports that are available for public inspection in the Office of the Principal or Building Administrator.

The Principal or Building Administrator is required to do the following with this notification:

Post in a Public Place or Main Office

2) Inform Building Occupants

3) Send a copy of this notification to Parents or Guardians

4) Insert a copy into the latest AHERA Three-Year Reinspection report (white/pink binder)

in your office or facility.

Fran Burns

Chief Operating Officer

Francine Locke, M.S., Director

Office of Environmental Management

and Services

c: Danielle Floyd

AHERA-4a 8/21/15

SCHOOL DISTRICT OF PHILADELPHIA

Education Center 440 North Broad Street Philadelphia, Pennsylvania 19130

Office of Environmental Management and Services

215-400-4750

AHERA Six Month Surveillance Outline of Events

- Pursuant to the Federal Environmental Protection Agency (EPA) mandate, as required by 40 CFR 763.92(b), the following procedure is to be implemented. At least once every six (6) months after a Management Plan is in effect, each Local Education Agency (LEA) shall conduct a periodic surveillance in each building that it owns or leases that contains Asbestos Containing Building Materials (ACBM) or is assumed to contain ACBM.
- The first Bi-Annual Inspection starts in the Spring (March, April, May) and again in the Fall (October, November, December) of each year. The Building Engineer/Assistant should assist the Building Inspector with appropriate access to all areas including (Crawlspaces/Attics) and rooms in the facility. There is no action required of the Principal.
- The Building Inspector shall visually inspect all areas that are identified in the Management Plan as ACBM or assumed ACBM. The date of the surveillance is recorded, the inspectors name and any changes in the conditions of the materials.
- The Building Inspector shall make a copy of the inspection document and insert into the front of the latest Management Plan (AHERA Three Year Reinspection report). The original document is returned to the LEA's Environmental Library and filed.

SCHOOL DISTRICT OF PHILADELPHIA

Education Center 440 North Broad Street Philadelphia, Pennsylvania 19130

Office of Environmental Management and Services

215-400-4750

AHERA Three Year Reinspection Outline of Events

- Pursuant to the Federal Environmental Protection Agency (EPA) mandate, as required by 40 CFR 763.85(b) the following procedure is to be implemented. At least once every three (3) years after a Management Plan is in effect, each Local Education Agency (LEA) shall conduct a reinspection of each building that it owns or leases that contains Asbestos Containing Building Material's (ACBM's) or is assumed to contain ACBM.
- Subsequent Three Year Re-inspections (2009, 2012, 2015, etc) shall start in the Fall (October, November, December, January). The Building Engineer/Assistant should assist the Building Inspector with appropriate access to all areas including (Crawlspaces/Attics) and rooms in the facility. There is no action required of the Principal.
- An accredited Building Inspector shall visually inspect and touch to determine friability, all areas that are identified in the Management Plan as ACBM or assumed ACBM. The date of the surveillance is recorded, the inspectors name and any changes in the conditions of the materials. The Building Inspectors state of accreditation and license number is required.
- After the inspection, the Building Inspector shall make a copy of the inspection documents and insert into the front of the latest Management Plan (AHERA Three Year Reinspection report). The original document is returned to the LEA's Environmental Library and filed.
- The Building Inspector shall return the reinspection data to the Management Planner to be assessed and determine appropriate response actions and a report issued (AHERA Three Year Reinspection report). One copy of the report is delivered to the schools Principal to be permanently retained with all previous environmental data. Another copy is retained in the LEA's Environmental Library.



School District of Philadelphia Office of Environmental Management & Services 440 North Broad Street Philadelphia, PA 19130 (215) 400-4750

School District of Philadelphia Asbestos Management Program

TABLE OF CONTENTS

De	finitionsPage 9
1.	IntroductionPage 10
	Summary of Asbestos Management Plan Asbestos Management Plan Execution
4.	Summary of Program Execution a. Asbestos Management Plan Execution
5.	Responsibilities a. OEMS b. Asbestos Worker/Supervisor "A-TEAM"
6.	Requirements
7.	AHERA O&M Plan
8.	O&M Response Actions
	9 References and Resources Page 1

DEFINITIONS / ACRONYMS

ACM/PACM: Asbestos Containing Material/Potential Asbestos Containing Material AHERA: Asbestos Hazard Emergency Response Act AIR FORM: **Asbestos Inspection Report Form** Water to which a surfactant (soap) has been added Amended Water: AMP: Asbestos Management Program/Asbestos Management Plan Asbestos Designate Person: Individual assigned by the district to oversee asbestos related issues. Asbestos Regulated Area: Location that is posted as an asbestos work area in which only approved and accredited personnel are permitted to enter AST: Asbestos Support Team involving approved and accredited school district tradespersons personnel that are school district person A-TEAM: School District of Philadelphia asbestos workers CIP: Capital Improvement Program Consultant: Asbestos consulting firm hired by the District **Demolition Directive:** Memorandum - August 4, 2006 from Patrick Henwood EPA: **Environmental Protection Agency** In House Personnel: School District of Philadelphia asbestos workers LEA: **Local Education Agency** 0&M: **Operations and Maintenance OEMS:** Office of Environmental Management and Services **OSHA:** Occupational Safety and Health Administration PEL: Permissible Exposure Limit PSD or SDP: Philadelphia School District/School District of Philadelphia

PSIT:

STEL:

Philadelphia School Improvement Team

1. Introduction

The School District of Philadelphia, Asbestos Policy Statement:

"The School District of Philadelphia is dedicated to providing a safe and healthful work environment for its employees, students, faculty, contractors and visitors. In recognition of the potential health problems associated with asbestos, the School District of Philadelphia is committed to a comprehensive asbestos control program. This program is implemented and maintained through the School District of Philadelphia's Office of Environmental Management and Services (OEMS)."

OEMS has the responsibility of establishing procedures for asbestos abatement, asbestos inspection, air monitoring, renovation and demolition activities within all School District of Philadelphia owned or leased facilities.

These procedures are developed to ensure that:

- (1) People are not exposed to significant levels of asbestos fibers
- (2) Asbestos waste is handled and disposed of properly
- (3) Members of the School District of Philadelphia community have access to the Office of Environmental Management and Services for information, assistance, guidance, and interpretation regarding asbestos related matters.
- (4) Members of the School District of Philadelphia community have access to the Asbestos Management Plans as required and outlined in the US EPA AHERA regulations including annual written notification to all parents.
- (5) Compliance with all applicable Federal, State and Local Asbestos Regulations

Requirements outlined in this manual are mandatory in nature where the word "SHALL" is used and are advisory in nature where the word "SHOULD" is used.

2. Summary of Asbestos Management Program

The School District of Philadelphia's Asbestos Management Program was established to meet the requirements of Federal, State, and Local Regulations.

These regulations include, but are not limited to:

- US Environmental Protection Agency Asbestos Hazard Emergency Response Act (US EPA AHERA) and National Emissions Standard for Hazardous Air Pollutants subpart M, Part 61 (NESHAP);
- US Department of Labor, Occupational Safety and Health Administration (OSHA) General Industry Standard (29 CFR 1910.1001) and the OSHA Asbestos Standard for the Construction Industry (29 CFR 1926.1101);
- The Commonwealth of Pennsylvania, Department of Labor and Industry, Asbestos Occupations, Accreditation and Certification Act;
- The City of Philadelphia, Department of Public Health, Asbestos Control Regulations.

3. Asbestos Management Program Execution

a) General Execution

The Office of Environmental Management and Services (OEMS) develops, implements and manages safety and health programs for the School District of Philadelphia faculty, staff and students and assists with ensuring that all contractors comply with Federal, State and Local Environmental Regulations. The OEMS provides the oversight of School District of Philadelphia employees (Asbestos A-Team), environmental consultants, and asbestos abatement contractors for all projects within the School District of Philadelphia concerning Asbestos Containing Materials.

The control of safety and health hazards at the School District of Philadelphia is primarily through the implementation of engineering, work practice and administrative controls. Personal Protective Equipment (PPE) is used to supplement these controls or whenever the controls are not feasible or are in the process of being implemented. PPE is also recommended whenever exposures to chemical, physical or biological agents can be prevented or reduced by its use.

This written program establishes the procedures necessary to:

- 1) meet established standards and federal regulations for occupational exposure to asbestos fibers;
- 2) meet the requirements of the City of Philadelphia Asbestos Control Regulations which encompasses the disturbance and/or abatement of asbestos containing building materials;
- 3) provide the necessary health and safety protection to the School District of Philadelphia staff, faculty, students, contractors and visitors.

This program is strengthened by input and cooperation with the Philadelphia Federation of Teachers (PFT), Health and Welfare Fund.

4. Summary of Program Execution

a) Asbestos Management Program Execution

The Asbestos Management Program is administered by the Office of Environmental Management and Services (OEMS). OEMS provides the following services primarily through professional consultants:

- (1) exposure monitoring services;
- (2) building inspection/surveys (bulk sampling) for the identification of asbestos containing materials;
- (3) asbestos project design services;
- (4) asbestos abatement project and air monitoring services;
- (5) emergency response to fiber release episodes;
- (6) education/information;
- (7) medical monitoring;
- (8) training for School District of Philadelphia personnel

5. Responsibilities

a) Office of Environmental Management and Services

OEMS is responsible for performing the following functions:

- (1) Developing and administering of the Asbestos Management Program.
- (2) Providing asbestos-related services to all School District of Philadelphia departments.
- (3) Conducting required training of the Asbestos Management Program and working jointly with departments to schedule training.
- (4) Identifying and posting areas where labeling/signage are required.
- (5) Medical Monitoring of OEMS "A-TEAM" and other departments "AST" Asbestos Program staff.

- (6) Certification and training as required for OEMS "A-TEAM" and other departments "AST" Asbestos program staff.
- (7) Record keeping as outlined in Section 3.5 and all records as by required by US EPA AHERA regulations.

b) Asbestos Worker/Supervisor - "A-TEAM"

- (1) OEMS shall ensure that all "A-TEAM" workers/supervisors adhere to the following requirements:
 - a) Attend an initial Worker/Supervisor Asbestos Course;
 - b) Maintain the annual re-certification per EPA AHERA requirements and Commonwealth of Pennsylvania Asbestos Occupations, Accreditation and Certifications Act;
 - c) Undergo an annual Asbestos Medical Evaluation;
 - d) Undergo an annual Respirator Medical Clearance;
 - e) Undergo an annual Respirator Fit Testing.

c) Asbestos Designated Person

The Asbestos Designated Person is responsible for:

- (1) Assuring the health and safety of employees, students and visitors in the School District of Philadelphia facilities under his/her control.
- (2) Being kept informed of all areas under his or her jurisdiction where potential asbestos exposures exist and initiating protection programs that adhere to the Asbestos Management Program requirements of this manual.
- (3) Assuring that Asbestos Management Program requirements are adhered to by principal investigators, project managers, supervisors, or division heads, and School District of Philadelphia personnel under their supervision.
- (4) Ensuring that all employees within the Asbestos Management Program comply with (OSHA 1910.1001 (j) (7) (iv)) and the US EPA AHERA regulations by attending the required training.
- (5) Ensure the posting of:
 - a) Warning labels/signage
 - b) Commonwealth of Pennsylvania Asbestos Abatement and Demolition/Renovation Notification form
 - c) Asbestos Inspection Reports (AIR) form (where required)
 - d) Ensuring that Construction Projects follow the Demolition Directive procedures as outlined in the August 4, 2006 letter.

d) Supervisor or Project Manager (Capital, Maintenance and Facilities)

Each person in charge of a project, maintenance/repair, renovation/demolition, or other activity from the Departments of Capital, Maintenance, and/or Facilities, where asbestos containing material may be present is responsible for:

Identifying, with the assistance of OEMS, asbestos containing building materials prior to any disturbance of these materials. Various Federal (EPA and OSHA) and Local (City of Philadelphia Asbestos Control Regulations) require Asbestos Inspections prior to renovation/demolition activities. This shall be accomplished by always following the Asbestos Management Program Procedures as follows:

(1) Ensure that the requirements of the Asbestos Management Program Procedures are followed by all personnel, trades, and contractors who are involved with the project;

- (2) Review of the required Asbestos Inspection Report (AIR) form (Attachment 1) and AHERA Management Plan documents prior to activities that may disturb any Asbestos Containing Materials;
- (3) Perform all project related duties as outlined in the Project Management Responsibilities;
- (4) Keep the department chairperson or director informed on any actions proposed or taken regarding the Asbestos Management Plan;
- (5) Ensuring that Construction Projects follow the Demolition Directive procedure outlined in the August 4, 2006 letter.

e) Employee - Capital

School District of Philadelphia Capital employees and/or consultants shall:

- (1) Ensure that no suspect or asbestos containing building materials are disturbed in the course of the projects they are performing or managing. This shall be accomplished by notifying their supervisor and OEMS by issuance of a work order permit (a.k.a PSIT Service Request Form) and verifying that the materials which may be disturbed are non-asbestos containing. If this information is not available or verification has not been made, these materials should not be disturbed.
- (2) Immediately notify OEMS and their supervisor in the event of a potential fiber release episode upon discovery of visible damage to asbestos containing materials.
- (3) Ensuring that Construction Projects follow the Demolition Directive procedures as outlined in the August 4, 2006 letter.

The types of projects represented as part of the Capital Improvement Program are as follows:

- (1) Complete Renovation of an existing building that addresses all facility component concerns and educational program needs;
- (2) Major Renovation of an existing building addressing significant facility component and educational improvements:
- (3) Addition to an existing building (either as an attachment or stand-alone structure) to accommodate needed program space;
- (4) Conversion of an existing facility to accommodate a change in educational program;
- (5) Facility Component Improvement of specific facility needs (i.e. electrical or HVAC system upgrades, ADA improvements, life safety improvements, exterior renovations, etc.)

f) Employee – Maintenance

School District of Philadelphia Maintenance employees shall:

- (1) Ensure that no suspect or asbestos containing building materials are disturbed in the course of their duties or work they are performing. This shall be accomplished by notifying their supervisor and OEMS by issuance of a work order permit and verifying that the materials which may be disturbed are non-asbestos containing. If this information is not available or verification has not been made, these materials should not be disturbed.
- (2) Immediately notify OEMS and their supervisor in the event of a potential fiber release episode or upon discovery of visible damage to asbestos containing materials.
- (3) All employees involved in maintenance activities shall attend required Asbestos Awareness training program within 60 days of employment.

g) Employee – Facilities & Custodial

School District of Philadelphia Facilities and Custodial employees shall:

- (1) Ensure that no suspect or asbestos containing building materials are disturbed in the course of their duties or work they are performing. This shall be accomplished by notifying their supervisor and OEMS by issuance of a work permit and verifying that the materials which may be disturbed are non-asbestos containing. If this information is not available or verification has not been made, these materials should not be disturbed;
- (2) Immediately notify OEMS and their supervisor in the event of a potential fiber release episode or upon discovery of visible damage to asbestos containing materials.
- (3) All employees involved in Facilities and Custodial activities shall attend require Asbestos Awareness training program within 60 days of employment.

6. Requirements

a) Employee Exposure Monitoring

When information indicates that an employee's exposure to asbestos fibers may equal or exceed an 8-hour time-weighted average of 0.1 f/cc * (per OSHA 1910.1001 & 1926.1101), OEMS shall develop and implement an asbestos exposure monitoring program. The sampling strategy shall be designed to identify employees by work task (job classification) that is exposed to asbestos fibers that exceed an 8-hour time-weighted average of 0.1 f/cc.

b) Employee Notification

OEMS shall notify in writing, each employee exposed to asbestos fibers at or above an 8-hour time weighted average of 0.1 f/cc.

c) Observation and Monitoring

OEMS shall provide employees or their representatives with an opportunity to observe any exposure measurements conducted.

d) Training Program

OEMS shall institute a training program which meets the requirements of AHERA for all employees who perform maintenance operations in a facility/school which contains asbestos containing materials or presumed asbestos containing materials and 1910.1001 (j), and the Commonwealth of Pennsylvania Department of Labor and Industry and the City of Philadelphia Asbestos Control Regulations. The affected departments shall ensure employee participation in this program. The OEMS "A-TEAM" and other departments "AST" Asbestos Program staff training shall be conducted annually for each employee as required by all Federal, State and Local for each asbestos discipline.

All Asbestos Awareness training as required by AHERA shall be performed within 60 days of employment and shall include:

- o Health effects of asbestos
- o Locations of ACM and PACM in the building/facility
- o Recognition of CM and PACM damage and deterioration
- o Requirements of the OSHA 1910.1001 standard relating to maintenance
- o Proper response to fiber release episodes
- o Procedure to be followed to isolate areas affected by fiber release

e) Access to Information

OEMS shall make available to affected employees or their representative's copies of the Occupational Safety and Health Administration (OSHA) General Industry Standard Part 1910.1001 and the department shall post a copy in the workplace.

f) Record Keeping

OEMS shall maintain an accurate record of all employee exposure measurements. OEMS and/or the School District of Philadelphia Human Resources Department shall maintain records of employee medical monitoring program. OEMS shall maintain all employee training records. All records shall be provided upon request to employees, former employees, representatives designated by the individual employee.

7. AHERA OPERATIONS AND MAINTENANCE PLAN

a) CONTROLS

i. Work Order System

Minimizing disruption of ACM/PACM during maintenance and renovation activities is the primary goal and task encountered by OEMS. Operations and maintenance employees and contractors should be warned to avoid conducting any maintenance work which may disturb ACM/PACM. Initiating a work order system, where all work orders or requests are channeled through the Office of Environmental Management and Services (OEMS), will be the method used to control and minimize disruption of ACM/PACM.

Any work performed by in-house personnel or contractors that could or will impact ACM/PACM shall be coordinated by OEMS. A completed Asbestos Inspection Report Form (Attachment 1) shall be issued to in-house personnel and/or all contractors whose work could impact ACM/PACM. This form should accompany each contract issued to an outside contractor and posted on the jobsite.

All work order requests for maintenance and renovation activities in areas where ACM/PACM is suspected or known to be present are to be submitted to OEMS prior to proceeding with work. OEMS is responsible for reviewing asbestos survey records for information about the presence of ACM/PACM in the area where the work is to be performed. OEMS should physically inspect the area to ensure existing records reflect actual conditions. If no asbestos is present, a work order is not necessary and the planned actions can proceed. If ACM/PACM is found to be present in the area, OEMS will sign the work order application and obtain an approved and accredited asbestos contractor or assign OEMS "A-TEAM" to abate the ACM/PACM.

ii. Regulated Areas

The owner will identify and regulate all areas where airborne concentrations of ACM/PACM exceed the Permissible Exposure Limit (PEL)* (Per OSHA determined to be 0.1 f/cc) and/or short term exposure limit (STEL) (Per OSHA determined to be 0.1 f/cc), or there is reasonable possibility that the (PEL) and/or (STEL) may be exceeded. All ACM/PACM removal activities involving thermal system insulation ACM/PACM (Class I), surfacing ACM/PACM (Class I), and miscellaneous ACM/PACM such as floor tile, roofing, and siding mastic, etc. (Class II), and repair and maintenance operations where thermal system insulation and surfacing ACM/PACM is likely to be disturbed (Class III) will be performed in accordance with federal, state, and local regulations. All asbestos abatement work and activities will be designed and managed as asbestos regulated areas. These areas will be demarcated and labeled.

iii. Warning Signs

Warning signs shall be displayed at all approaches to each asbestos regulated area. The asbestos abatement contractor will provide OSHA warning signs in all regulated areas during removal, repair, and other maintenance activities. OEMS will provide AIRs to all contractors who must inform all employees and supervisors working in locations contiguous to asbestos regulated areas of the potential hazards and work practices required.

iv. Warning Labels

Warning labels and or signage shall be affixed to all raw materials, mixtures, scrap, waste, debris, and other products containing asbestos fibers, or to their containers. Generally, the asbestos abatement contractor or OEMS A-Team personnel will provide all warning labels for ACM/PACM containment.

8. O & M RESPONSE ACTIONS

The Asbestos Management Program general O&M procedures are outlined in this section. Additional requirements specific to asbestos abatement activities are included in the Project Design documents for all Asbestos Abatement Work. Regular cleaning, inspection, and reporting of ACM/PACM deterioration or other problems must be diligently practiced by all employees including custodial and maintenance personnel.

a) Facility Maintenance Isolation of Area Responsibilities

Maintenance personnel are often required to work in areas where ACM/PACM may potentially be disturbed. Most maintenance activities are conducted by in-house staff, outside contractors, or a combination.

Emergency fiber release episodes, such as pipe fitting or valve breaks, emergency boiler work, or mechanical equipment repair will be responded to by OEMS A-Team personnel or asbestos abatement contractor personnel. The owner's maintenance staff will: (1) isolate the emergency fiber release area; (2) post warning signs to prevent unauthorized access, and (3) notify their supervisor and OEMS. OEMS will ensure that the fiber release area remains isolated and is properly cleaned by and approved and accredited abatement contractor or by OEMS A-TEAM personnel.

b) Unlikely Contact with ACM/PACM

Maintenance activities or repairs which can be performed without contacting or disturbing the ACM/PACM require little more than normal care and good workmanship. For example, valves which are either uncovered or covered with non-asbestos insulation can be packed or repaired without disturbing asbestos insulation on nearby pipes. The major precaution is to ensure that maintenance and custodial personnel are familiar with procedures such as isolating the area, posting warning signs, and notifying OEMS in the event of any accidental ACM/PACM disturbance.

c) Accidental Disturbance of ACM/PACM

Maintenance and facilities personnel shall notify OEMS any time a fiber release is suspected. If friable ACM/PACM becomes airborne in the building,

d) Planned Disturbance of ACM/PACM

Maintenance activities that may impact ACM/PACM include access to a valve, flange, duct, or related system component.

Where asbestos-containing insulation must be removed to maintain or repair the thermal system, the ACM/PACM will imminently be disturbed. ACM/PACM removal work shall be conducted by OEMS A-Team personnel or an approved and accredited asbestos abatement contractor.

If friable ACM/PACM becomes airborne in the building, maintenance and facilities personnel shall secure the area and contact OEMS. OEMS shall respond accordingly.

e) Miscellaneous ACM/PACM

Miscellaneous types of ACM/PACM may include vinyl asbestos floor tiles, mastics/adhesives and woven vibration dampers. Disturbance of these materials should be avoided. Routine maintenance activities involving these materials should not pose a problem if handled properly. Questions on the proper removal and disposal of miscellaneous ACM/PACM should be directed to OEMS. OEMS will contact an approved and accredited asbestos abatement contractor or utilize OEMS A-TEAM personnel to assist with miscellaneous ACM/PACM clean-up activities.

f) Vinyl Asbestos Floor Tile

Asbestos-containing floor tiles in good condition are considered non-friable unless they are crushed, drilled, sawed, sanded or disturbed by any activity that breaks up the material. Routine maintenance of these materials should employ the use of non-abrasive buffers and wet cleaning technique. Broken or loose floor tiles should be removed and disposed of as asbestos waste by OEMS. Remaining debris should be vacuumed with a HEPA vacuum and the area wet mopped using amended water.

g) Mastics/Adhesives

Mastics and adhesives containing asbestos in good condition are considered non-friable and do not pose a potential health concern unless crushed, drilled, sawed, sanded, or otherwise abraded. Questions on the proper removal should be directed to OEMS.

h) Woven Vibration Dampers

Woven vibration dampers in good condition are considered non-friable and do not pose a potential health concern unless cut, crushed, drilled, sawed, sanded, or otherwise abraded. Questions on the proper removal should be directed to OEMS.

i) Other Work Practices

Any special work not included in this section should be addressed to OEMS for review prior to the initiation of work that may involve the disturbance of ACM/PACM.

j) Fiber Release Episodes

Facilities and maintenance staff should report to OEMS the presence of asbestos debris, water or physical damage to ACM/PACM, or any other evidence of possible fiber release. OEMS should have the OEMS A-Team personnel or an approved and accredited abatement contractor respond to the site to clean up debris and make repairs as soon as possible. OEMS will also contact a consultant to conduct air monitoring and prepare a report and submit at project completion to OEMS for each episode. OEMS will forward the reports for each site location AHERA Management Plan accordingly.

9. REFERENCES and RESOURCES

Applicable regulations for asbestos projects impacted by renovation, demolition, and maintenance activities.

- Philadelphia Air Management Services Asbestos Control Unit
 http://www.phila.gov/health/units/ams/Asbestos/asbestos.html
- Pennsylvania Asbestos Occupations, Accreditation and Certification Act
 http://www.dli.state.pa.us/landi/cwp/view.asp?a=185&q=56262&landiNav=
- United States Environmental Protection Agency Asbestos Home Page
 http://www.epa.gov/asbestos/
- Occupational Safety and Health Administration (OSHA) Asbestos Home
 http://www.osha.gov/SLTC/asbestos