SCHOOL DISTRICT OF PHILADELPHIA



Asbestos Hazard Emergency Response Act "AHERA"

THREE-YEAR RE-INSPECTION 2015-2016

and ASBESTOS MANAGEMENT PLAN for the

A. Philip Randolph Career and Technical HS

ULCS# 6090 Building # B609001-1 3101 Henry Avenue Philadelphia, Pennsylvania 19129

February 2016

Conducted By:

Accredited Environmental Technologies, Incorporated
Batta Environmental Associates, Incorporated
Criterion Laboratories, Incorporated
Environmental Testing Consultants, LLC
G & C Environmental Services, Incorporated
KEM Partners, Incorporated
Synertech, Inc.
TTI Environmental, Inc.
USA Environmental Management, Inc.
The Vertex Companies, Inc.

Management Plan Prepared By: Criterion Labs, Inc and Synertech Inc.

This report must remain in the Main Office as mandated by the US EPA AHERA Regulations.

AHERA THREE-YEAR REINSPECTION VOLUME IX

Table of Contents

Transmittal Letter

Executive Summary

- I. Summary list of Confirmed Asbestos Containing Building Materials
- II. Summary list of Assumed Asbestos Contain Building Materials
- III. Summary list of Non-Asbestos Containing Building Materials
- IV. Summary list of Non Suspect Asbestos Containing Building Materials
- V. Summary List of Auditorium DATA for this location
- VI. Summary list of Attic and/or Crawlspace DATA for this location
- VII. Summary list of Pipe Chase/Pipe Shaft DATA for this location

Section I Report of Re-Inspection

- A. Introduction
- B. Three-Year Re-inspection IX Overview
- C. Post- Management Plan Activities and Changes
 - C.1 Sampling and Analysis
 - C.2 New Floor Tile Sampling
 - C.3 Abatement Activity
 - C.4 Periodic (Six-Month) Surveillance (Damaged Materials)

Section II Re-Inspection Data

- A. Introduction
- B. Re-Inspection Key Definitions
- C. Room by Room Location Log Report

Section III Certificates

A. Management Planner/Building Inspector Certificates

Section IV Cross Reference Table Page 1-8

Asbestos Management Program Page 9-19

SCHOOL DISTRICT OF PHILADELPHIA EDUCATIONAL CENTER

440 NORTH BROAD STREET PHILADELPHIA, PENNSYLVANIA 19130

OFFICE OF ENVIRONMENT AL MANAGEMENT AND SERVICES

PHONE (215)-400-4750

January 2016

TO:

All Principals

All Building Administrators

FROM:

Fran Burns

Chief Operating Officer

Francine Locke, M.S., Director

Office of Environmental Management and Services

SUBJECT: AHERA Three (3) Year Re-inspection IX report

In order to comply with the provisions of the Asbestos Hazard Emergency Response Act (AHERA) the attached report is submitted to you. The law requires that this report be kept in the Main/Principal's office. It cannot be removed from these locations. If the school (program) is relocated to a different building, these environmental documents are to be safely retained for the next school/building occupants. All asbestos reports must be available to the public and Federal EPA upon request.

Fran Burns

Chief Operation Officer

Francine Locke, M.S., Director Office of Environmental Management

and Services

AHERA-2d Revised 12/14/15

Executive Summary

This Asbestos Hazard Emergency Response Act (AHERA) Three-Year Re-inspection "Volume # IX" Management Plan at this location, has been completed and the report of re-inspection submitted to the School District of Philadelphia. The re-inspections in all School District of Philadelphia buildings of 2015-2016 were conducted and completed between October 5th, 2015 through March 30th, 2016 as a joint project by Accredited Environmental Technologies, Inc., Batta Environmental Associates, Inc., Criterion Laboratories, Inc., Environmental Testing Consultants, LLC, G & C Environmental Services, Inc., KEM Partners, Inc., Synertech, Inc., TTI Environmental, Inc., USA Environmental Management, Inc. and The Vertex Companies, Inc.

In general, the School District of Philadelphia Office of Environmental Management and Services conducts Environmental Impact Evaluations and provides Asbestos Inspection Reports prior to any renovation, demolition and/or maintenance activities. The AHERA report must be reviewed prior to any renovation, demolition and/or maintenance activities in order to avoid the unknowing disturbance to Asbestos Containing Building Materials identified within this location. In addition, prior to work activities above all drop ceilings this report should be reviewed to avoid potential disturbances to Asbestos Containing Materials. Refer to Section IV of the Cross Reference Table, for additional Asbestos Management Program information. Contact the Office of Environmental Management and Services to have an Environmental Impact Evaluation conducted prior to any renovation, demolition and/or maintenance activities within this facility.

The information contained in this report was obtained from the original Asbestos Management Plan for the school, from update reports on changes and activities since the completion of the 1st Management Plan for each location and from all prior inspections performed and documented in Volume # I through Volume VIII (dated respectively 1992, 1995, 1998, 2001, 2004, 2007, 2010 or 2013) (if applicable) - and by this Three-Year Re-inspection of this school. The re-inspection report/Management Plan of 2015-2016 were reviewed and prepared collectively by Management Planner Megan Vala, Mary Anne Lerro of Criterion Laboratories, Inc. and/or Monique Causley, of Synertech Inc.

The 2015-2016 inspection process included the addition of a comprehensive Room by Room Inventory of all Thermal (T), Surfacing (S) and Miscellaneous (M) Materials specific to each room of this facility. Inspections of each room's thermal, ceilings, walls, floors and miscellaneous items regardless of Asbestos Content are categorized on the Room by Room Location Log Report for this location. Rooms or areas of the facility that were not accessible at the time of the inspection are marked with an "X". The Room by Room Location Log Report is found in Section II C of this Management Plan.

All Presumed or Suspect Asbestos Containing Building Materials (ACBMs), listed in the following summary charts are categorized as Confirmed, Assumed, Non-Asbestos, and/or Non-Suspect (ACBMs) were identified in the original Management Plan, or in the Volume I through Volume VIII AHERA Three-Year Re-inspection reports, and were re-inspected as part of this project.

As mandated by the U S EPA AHERA regulations, periodic Six-Month inspections and Three-Year Re-inspections of this location will be performed and the Inspection Data in this report will be updated accordingly.

Please feel free to contact the School District of Philadelphia's Office of Environmental Management and Services (OEMS) regarding any comments, questions, or concerns regarding this report or any Environmental related topic. OEMS staff can be reached at (215) 400 4750, via fax at (215) 400 4751 or via e-mail at flocke@philasd.org and/or gfjunod@philasd.org.

Additional information can be found on our website. Here is the link to the OEMS website. http://webgui.phila.k12.pa.us/offices/e/environmental

I. Summary list of Confirmed Asbestos Containing Building Materials within this facility

These charts are to be used for a quick reference* in order to avoid the unknowing disturbance of Asbestos Containing Materials during any and all Operations, Maintenance, Renovation, and/or Demolition activities at this location. These materials have been sampled and Laboratory Analysis has CONFIRMED the presence of Asbestos. Contact OEMS prior to the disturbance of any of the following materials.

Confirmed Asbestos Containing Building Materials for this location

In the event that Confirmed Materials are found data will be listed here.

- * Always refer to the Room by Room Logs for each specific material classification as the material classification findings may be different in various rooms throughout this facility.
- ** Some Materials may have multiple classifications (Confirmed, Assumed, NAD and Non Suspect) within this facility.

II. Summary list of Assumed Asbestos Containing Building Materials within this facility

These charts are to be used for a quick reference* in order to avoid the unknowing disturbance of Asbestos Containing Materials during any and all Operations, Maintenance, Renovation, and/or Demolition activities at this location. These materials have not been sampled and should not be disturbed until verification of Asbestos Content. Contact OEMS for assessment and sampling prior to the disturbance of these materials.

Assumed Asbestos Containing Building Materials for this location

Floor Tile VAT 12" x 12"	Linoleum	Radiator Insulation
Sheetrock Ceiling	Sheetrock Wall	Sink Undercoat Mastic
Transite Sills	Vibration Damper Cloth	

^{*} Always refer to the Room by Room Logs for each specific material classification as the material classification findings may be different in various rooms throughout this facility.

^{**} Some Materials may have multiple classifications (Confirmed, Assumed, NAD and Non Suspect) within this facility.

III. Summary list of Non-Asbestos Containing Building Materials within this facility

These charts are to be used for a quick reference* in order to avoid the unknowing disturbance of Asbestos Containing Materials during any and all Operations, Maintenance, Renovation, and/or Demolition activities at this location. These materials have been sampled and Laboratory Analysis has indicated NO Asbestos present or NO ASBESTOS DETECTED (NAD).

Non- Asbestos Containing Building Materials for this location

Ceiling Tile 2' x 4'	Plaster Ceiling	Plaster Walls

^{*} Always refer to the Room by Room Logs for each specific material classification as the material classification findings may be different in various rooms throughout this facility.

^{**} Some Materials may have multiple classifications (Confirmed, Assumed, NAD and Non Suspect) within this facility.

IV. Summary list of Non-Suspect Asbestos Containing Building Materials within this facility

These charts are to be used for a quick reference* in order to avoid the unknowing disturbance of Asbestos Containing Materials during any and all Operations, Maintenance, Renovation, and/or Demolition activities at this location. These materials are not typically known to contain Asbestos.

Non-Suspect Asbestos Containing Building Materials for this location

Carpet	Cement Floor	Ceramic Tile Floors
Ceramic Tile Walls	Concrete Block Wall	Concrete Ceiling
Fiberglass Breeching	Fiberglass Ceiling Tile 2' x 4'	Fiberglass Pipe Fitting Insulation
Fiberglass Pipe Insulation	Metal Ceiling Deck	Wood Wall Panels


^{*} Always refer to the Room by Room Logs for each specific material classification as the material classification findings may be different in various rooms throughout this facility.

^{**} Some Materials may have multiple classifications (Confirmed, Assumed, NAD and Non Suspect) within this facility.

V. Summary list of Auditorium DATA for this location

These charts are to be used for a quick reference of the Auditorium DATA within this facility. Sampling of the Auditorium Ceilings throughout the District is more difficult because of the various ceiling heights. As sampling occurs this information is updated on a case by case basis for each specific location and facility.

No Auditorium exists at this location.



** Some Materials may have multiple classifications (Confirmed, Assumed, NAD and Non Suspect) within this facility.

VI. Summary list of Attic and/or Crawlspace DATA for this location

These charts are to be used for a quick reference regarding the Attics and/or Crawlspaces inspection DATA within this facility. Contact OEMS prior to entering any attic or crawlspace within this facility and refer to the below chart and legend for Category Rank determination. The Data relative to these spaces is updated as conditions change regarding Abatement or Renovation activity on a case by case basis for each specific location and facility. In general, Crawlspaces are below the basement or 1st floor and Attics are above the floor space.

Category Rank Legend


- "A" No Asbestos Containing Materials Sample Results indicate NO ACM on pipes, fittings, elbows, or equipment located within this functional space, and NO VISIBLE DEBRIS or DAMAGE observed at time of this inspection.
- "B" Asbestos Containing Materials Exist Sample Results indicate ACM on pipes, fittings, elbows, or equipment located within this functional space, HOWEVER, NO VISIBLE DEBRIS or DAMAGE observed at time of this inspection.
- "C" Asbestos Containing Materials Exist Sample Results indicate ACM on pipes, fittings, elbows, or equipment located within this functional space, and LOCALIZED VISIBLE DEBRIS or DAMAGE observed at time of this inspection.
- "D" Asbestos Containing Materials Exist Sample Results indicate ACM on pipes, fittings, elbows, or equipment located within this functional space and DISTRIBUTED VISIBLE DEBRIS or SIGNIFICANT DAMAGE observed at time of this inspection.
- "E" No Bulk Sample Results Available SUSPECT ACM OBSERVED. Contact OEMS immediately for additional instructions.

Attic/Crawlspace	Access Area	Floor Surface	Category Rank	Comments
Attic	Mezzanine	Wire Lathe/Ltd. Planking	A	Fiberglass; Plastic/PVC Caps (Non ACM)/
Crawlspace	Auto Shop	Dirt	D	Sealed/No Access

VII. Summary list of Pipe Chase/Pipe Shaft DATA for this location

These charts are to be used for a quick reference regarding the information known about the Pipe Chases and/or Pipe Shafts inspection DATA within this facility. Contact OEMS prior to performing renovation activities any Pipe Chase and/or Pipe Shaft within this facility and refer to the below chart and legend for Asbestos Content of various materials identified within each space. The Data relative to these spaces is updated as conditions change regarding Inspection, Abatement and/or Renovation activity on a case by case basis for each specific location and facility. In general, Pipe Chases are horizontal spaces and Pipe Shafts are vertical spaces.

Pipe Chases and Pipe Shafts need to be assessed.



Section I - A

Report of Re-inspection

Introduction

The Three-Year Re-inspection IX was performed to fulfill the requirements of 40 CFR Part 763 - the Asbestos Hazard Emergency Response Act (AHERA). As required by AHERA, each Local Education Agency (LEA) must re-inspect all known confirmed or assumed Asbestos Containing Building Material (ACBM) located in the LEA's facilities. This re-inspection is intended to update the original Asbestos Management Plan for the LEA's facilities.

Multiple Building Inspectors of several firms performed the 2015/2016 re-inspection. The reinspection report/Management Plan of 2015-2016 were reviewed and prepared collectively by Management Planner Megan Vala, Mary Anne Lerro of Criterion Laboratories, Inc. and Monique Causley, of Synertech Inc.

All of the certificates can be found in Section III.

During the re-inspection of each School District of Philadelphia facility, all of the Management Plans for that facility were reviewed. Information from the conclusions section of that report is included in this report. Additionally, information on activities such as abatements, cleanings, sampling and inspections, which have taken place since the completion of the original Management Plan, were reviewed during the re-inspection. Information on those activities is included in this report.

As mandated by the U S EPA AHERA regulations, all future periodic Six-Month inspections and Three-Year Re-inspections of this location will be performed and the Inspection Data in this report will be updated accordingly.

Section I - B

Three-Year Re-inspection IX Overview

Each homogeneous area of Asbestos Containing Building Material (ACBM) listed in the original Management Plan or in the 1992, 1995, 1998, 2001, etc., Three-Year Reinspection reports were inspected for the AHERA Three-Year Re-inspection Volume IX, and the information for that material verified. Any changes to a homogeneous area listed in the updates to the Management Plans were verified. Any area of suspected ACBM found in the course of the re-inspection, and not listed in the Management Plan or updates, were either assumed to contain asbestos or sampled and analyzed to determine their asbestos content. Any such new areas either assumed to contain asbestos or determined through analysis to contain asbestos were included in the report of the Three-Year Re-inspection. The results of the AHERA Three-Year Re-inspection IX are tabulated in the Room by Room log reports located in Section II-C of this report.

As previously noted, all future periodic Six-Month inspections and Three-Year Reinspections of this location will be performed and the Inspection Data in this report will be updated accordingly.

Section I – C.1

Post Management Plan Activities/Changes

Information on activities affecting Asbestos Containing Building Materials (ACBMs) at this location is contained in updates to the Management Plan. These updates are kept on file by the School District of Philadelphia and were reviewed for this project. Updates to the Management Plan include the following: *Sampling and Analysis, New Tile Installation, Abatement Activity and Periodic Six-Month Surveillance Data.*

Sampling and Analysis

In the event that Sampling occurs, data will be listed here.

Section I - C.2

Information on the installation of new floor tiles/renovation activities affecting Asbestos Containing Building Materials (ACBMs) at this location is contained in updates to the Management Plan. These updates are kept on file by the School District of Philadelphia and were reviewed for this project. Updates to the Management Plan include the following:

New Floor Tile Sampling

In the event that new tile is installed, the material must be tested prior to installation.

Section I – C.3

Information on the Asbestos Abatement and renovation activities affecting Asbestos Containing Building Materials (ACBMs) at this location is contained in updates to the Management Plan. These updates are kept on file by the School District of Philadelphia and were reviewed for this project. Updates to the Management Plan include the following:

Abatement Activity


In the event Abatement occurs, data will be listed here.

Section I - C.4

Information on the AHERA inspection that noted damage to various Building Materials at this location is contained in updates to the Management Plan. These updates are kept on file by the School District of Philadelphia and were reviewed for this project. Work orders are created for Corrective Action responses and tracked for completion. Updates to the Management Plan include the following:

Periodic (Six-Month) Surveillance (Damaged Materials)

						Amount
					Amount of	
Date	Element	Floor	On Site Room Name	Material	Material	Damage
7/18/2016	1	1	Hallway next to Classrooms 37 to 39	Sheetrock Wall	200 SF	10 SF
7/18/2016	1	1	Classroom 36	Sheetrock Wall	600 SF	10 SF
7/18/2016	1	1	Classroom 56	Floor Tile VAT 12" x 12"	700 SF	4 SF
7/18/2016	1	1	Hallway next to Classroom 56	Sheetrock Wall	400 SF	10 SF
7/18/2016	1	1	Gymnasium	Sheetrock Wall	300 SF	5 SF
7/18/2016	1	1	Custodial Closet 34 next to Lunchroom	Floor Tile VAT 12" x 12"	25 SF	1 SF
7/18/2016	1	1	Hallway next to Classrooms 25, 23, 22	Floor Tile VAT 12" x 12"	800 SF	25 SF
7/18/2016	1	1	Classroom 22	Sheetrock Wall	400 SF	10 SF
7/18/2016	1	1	Classroom 21	Floor Tile VAT 12" x 12"	800 SF	20 SF
7/18/2016	1	1	Classroom 79	Sheetrock Wall	900 SF	2 SF
7/18/2016	1	1	Classroom 82	Floor Tile VAT 12" x 12"	450 SF	5 SF



Section II - A

Re-inspection Data

Introduction

The following information documents the Three-Year Re-inspection IX of the subject school/facility. The Homogeneous Area Reports were produced using the building inspector's field data on the facility. The key to the Homogeneous Area Report is outlined in the following pages of this report.

Section II - B (page 1 of 4)

SCHOOL DISTRICT OF PHILADELPHIA AHERA THREE YEAR RE-INSPECTION IX

ULCS# Individual identification number assigned to each school within the School District of Philadelphia. HOMOGENEOUS AREA ID# Identification number assigned to each homogeneous area in a school/facility. Each section of the homogeneous area ID is significant. 1010/01/01/01 A B C D A. Is the ULCS# for the school. B. Designates the specific building/building area within the school. C. Designates the floor or level within the building/building area. D. Designates the homogeneous material within that floor or level. Note: Item D may be a number or a letter. SYSTEM AFFECTED T : Thermal System S : Surfacing System M : Miscellaneous ITEM AFFECTED Is a description of the homogeneous material. ORIGINAL INSPECTION DATA AMOUNT OF MATERIAL/ AMOUNT OF MATERIAL/ Units include: Square Feet (SF) Each (EA) Linear Feet (LF) Cubic Feet (CF).	
ULCS#	$oldsymbol{arphi}$
	 B. Designates the specific building/building area within the school. C. Designates the floor or level within the building/building area. D. Designates the homogeneous material within that floor or level.
	Corresponds to the AHERA system for classifying materials.
AFFECIED	S : Surfacing System
ITEM AFFECTED	Is a description of the homogeneous material.
INSPECTION	· · · · · · · · · · · · · · · · · · ·

SCHOOL DISTRICT OF PHILADELPHIA AHERA THREE YEAR RE-INSPECTION IX

RE-INSPECTION FORM KEY

CND Corresponds to AHERA condition rating for materials.

Condition

0 : No Damage1 : Damage

2 : Significant Damage

DP

Corresponds to the AHERA material assessment system.

Damage Potential

1 : Potential for Damage

2 : Potential for Significant Damage

ASMD Assumed Asbestos This means that a material was not sampled for asbestos content during the original Management Plan inspection.

RA

This corresponds to the AHERA system of response action rating for materials.

Response Action

Establish O&M Program

2 : Repair and Establish O&M Program

3 : Enclose 4 : Encapsulate 5 : Remove

6 : Partial Removal and Establish O&M Program

CHANGES

This section describes changes to the homogeneous material in the twenty-four years since the original AHERA inspection. The abbreviations are defined below.

Removed **RMVD** : **ENCL** Enclosed **ENCP** Encapsulated **DMGD** Damaged **SMPLD** Sampled Material MTRL **RPRD** Repaired None Located N/L **RPLCD** Replaced

SCHOOL DISTRICT OF PHILADELPHIA AHERA THREE-YEAR RE-INSPECTION IX

RE-INSPECTION FORM KEY

ITEM DEFINITION

THREE YEAR RE-INSPECTION

This section contains the information obtained from the Three-Year Re-inspection IX. With three exceptions, the information categories are identical in format and meaning to those found in the original inspection data section. The three exceptions are defined below.

DMGD AMT Amount Damaged

This section gives the quantity of damaged material in a homogeneous area. The quantity is shown in the same format as the amount of material/unit section.

NF Newly Friable

This section identifies materials in the original Management Plan which have since become friable.

RA Response Action

This rating is based on the AHERA regulations, and is comparable to the RA rating found in the "Original Inspection Data" section. The following table details the response actions.

- 1. Establish O&M Program
- 2. Repair and Establish O&M Program
- 3. Enclose
- 4. Encapsulate
- **5.** Remove
- **6.** Partial Removal and Establish O&M Program

a. High Priority Response

The homogeneous material has been scheduled for abatement or other response action.

b. Medium Priority Response

The homogeneous material will be scheduled for abatement or other response action as soon as the high priority responses have been addressed.

c. Low Priority Response

The homogeneous material will be scheduled for abatement or other response action as soon as the medium priority responses have been addressed.

d. On-Going Response/Operations and Maintenance

The homogeneous material does not require abatement or other response action at present, and should be included in the facility's on-going operations and maintenance program.

SCHOOL DISTRICT OF PHILADELPHIA AHERA THREE-YEAR RE-INSPECTION IX

RE-INSPECTION FORM KEY

The information presented in the changes section has been compiled from a variety of sources, including the Re-inspection and the following:

- * Quality Control/Quality Assurance Reports of asbestos abatement projects, prepared by consultants to the School District.
- * Permit and Notification Forms for asbestos abatement projects.
- * Periodic Surveillance Forms
- * Operations and Maintenance activities performed by School District personnel.
- * Verbal information from School District personnel.
- * Reports of sampling and analysis of suspected materials by both School District personnel and outside consultants.

ROOM BY ROOM LOCATION LOG REPORT This section gives information, including damage amount and location, for a specific homogeneous material on a room-by-room basis and follows the Re-inspection form.

NOTE: The disparate nature of the above sources of information prohibits the verification of much information within the scope of the AHERA Three-Year Re-inspection. Discrepancies and omissions may exist in this information, and therefore is included on an "as is" basis. The inspectors for the Three-Year Re-inspection IX evaluated homogeneous areas based on the materials current condition and location, as evidenced during the inspector's site visit.

.

Section II - C

Room by Room Location Log Report

These charts are to be used for a quick reference* in order to avoid the unknowing disturbance of Asbestos Containing Materials during any and all Operations, Maintenance, Renovation, and/or Demolition activities at this location.

NOTE:

Contact OEMS prior to the disturbance of any of the materials that are listed as **Confirmed and/or Assumed**.

The quantities listed for (NAD) non-asbestos containing materials and/or Non-Suspect Materials are only estimated and were not measured for the purpose of this report. Field verification of quantities for renovation purposes would be necessary.

	School District of Philadelphia		AHER	A Three-Year Reinsp	ection 2015-2016					Reinspection Date: 2/8/2016 - 2/9/2016				
ı	A. Philip Randolph Career and Technical High School	7		om by Room Locatio						Building Inspector: Mary Anne Lerro	1			
	3101 Henry Avenue	1	Red= Confirmed (Contact OEMS pr	•		and sanast a	lamaa				1			
-	3101 Henry Avenue	4								Certificate Number:740092	+			
	Philadelphia, PA 19129		Yellow= Assumed (Contact OEMS f and report damage)	or assessment and sampi	ing prior to the disturbance of	tnese mate	riais			Management Planner: Monique Causley				
1		1		Ion Suspect Material (The	se materials have been camp	led and		1		January Country	1			
			Green= Non Asbestos Containing/N Laboratory Analysis has indicated N	IO Asbestos present or N	O ASBESTOS DETECTED or th	ese material	s are							
L.	ULCS# 6090		not typically known to contain Asbe	stos)						Certificate Number:ACC-0215-8-010				
E														
=				1										
e F				1										
m I				1							A40-	B		
I e F m I e o n o		System		1	Confirmed Assumed NAD	Amount of	SF LF	Amount of	SF LF Color required		Attic Crawlspace	Damage Potential	Newly	Response
t r	On Site Room Name	Affected	Material Description	HID#	Non Suspect ACM	Material	EA	Damage	SF LF Color required EA for VAT	Comments/Description/Notes	Crawlspace Ranking	(DP)	Friable (NF)	Action (RA)
	Classroom 50	M	Floor Tile VAT 12" x 12"	6090/01/01/12	Assumed	600	SF	0	White			1	No	1/D
1 1	Classroom 50	N/A	Concrete Block Wall		Non Suspect ACM	1200	SF	0				N/A	N/A	N/A
1 1	Classroom 50	N/A M	Ceiling Tile 2' x 4'	6090/01/01/CRI/IH/2602	NAD	600	SF SF	0		Sampled during original inspection Oct. 1988		N/A	N/A No	N/A 1/D
1 1	Classroom 50 Classroom 50 Storage/Foyer	M	Sink Undercoat Mastic Floor Tile VAT 12" x 12"	6090/01/01/CRI/IH/2602 6090/01/01/12	Assumed Assumed	50	SF	0	Tan			1	No No	1/D 1/D
	Classroom 50 Storage/Fover	N/A	Concrete Block Wall	0090/01/01/12	Non Suspect ACM	150	SF	0	I dii		1	N/A	N/A	N/A
	Classroom 50 Storage/Foyer	N/A	Plaster Ceiling	†	NAD	50	SF	0		Sampled NAD March 1991	1	N/A	N/A	N/A
1 1	Classroom 51	N/A	Concrete Block Wall	1	Non Suspect ACM	700	SF	0			1	N/A	N/A	N/A
	Classroom 51	N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	300	SF	0				N/A	N/A	N/A
	Classroom 51	М	Floor Tile VAT 12" x 12"	6090/01/01/12	Assumed	300	SF	0	Tan			1	No	1/D
1 1	Corner Teacher's Lounge adjacent to Nurse Nurse's Office	M	Sheetrock Wall	6090/01/01/CRI/IH/2100	Assumed	700	SF	0				1	No	1/D
1 1	Corner Teacher's Lounge adjacent to Nurse Nurse's Office	N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	300	SF	0				N/A	N/A	N/A
1 1	Corner Teacher's Lounge adjacent to Nurse Nurse's Office	M	Floor Tile VAT 12" x 12"	6090/01/01/12	Assumed	300	SF	0	Tan		1	1	No	1/D
	Nurse's Patient Bed Area next to Nurse's Office	M	Sheetrock Wall	6090/01/01/CRI/IH/2100	Assumed	700	SF	0	-			1	No	1/D
	Nurse's Patient Bed Area next to Nurse's Office	N/A M	Fiberglass Ceiling Tile 2' x 4'	6000/04/04/40	Non Suspect ACM	300	SF	0	Ter		1	N/A	N/A	N/A
1 1	Nurse's Patient Bed Area next to Nurse's Office Conference Room adjacent to Nurse's Office	M	Floor Tile VAT 12" x 12" Sheetrock Wall	6090/01/01/12 6090/01/01/CRI/IH/2100	Assumed Assumed	300 700	SF SF	0	Tan		 	1	No No	1/D 1/D
1 1 1	Conference Room adjacent to Nurse's Office	N/A	Fiberglass Ceiling Tile 2' x 4'	0000/01/01/0N///1/2100	Non Suspect ACM	300	SF	0			 	N/A	N/A	N/A
	Conference Room adjacent to Nurse's Office	M	Floor Tile VAT 12" x 12"	6090/01/01/12	Assumed	300	SF	0	Tan			1	No	1/D
1 1	Hallway between Nurse's Office and Conference Room	M	Sheetrock Wall	6090/01/01/CRI/IH/2100	Assumed	400	SF	0				1	No	1/D
1 1	Hallway between Nurse's Office and Conference Room	N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	200	SF	0				N/A	N/A	N/A
1 1	Hallway between Nurse's Office and Conference Room	M	Floor Tile VAT 12" x 12"	6090/01/01/12	Assumed	200	SF	0	Tan			1	No	1/D
	Men's Restroom adjacent to Conference Room	N/A	Ceramic Tile Floors		Non Suspect ACM	50	SF	0				N/A	N/A	N/A
1 1	Men's Restroom adjacent to Conference Room	M	Sheetrock Wall	6090/01/01/CRI/IH/2100	Assumed	200	SF	0				1	No	1/D
	Men's Restroom adjacent to Conference Room	N/A	Fiberglass Ceiling Tile 2' x 4'	-	Non Suspect ACM	50	SF	0			ļ	N/A	N/A	N/A
	Women's Restroom adjacent to Conference Room Women's Restroom adjacent to Conference Room	N/A M	Ceramic Tile Floors Sheetrock Wall	6090/01/01/CRI/IH/2100	Non Suspect ACM	50 200	SF SF	0			-	N/A	N/A No	1/D
	Women's Restroom adjacent to Conference Room Women's Restroom adjacent to Conference Room	N/A	Fiberglass Ceiling Tile 2' x 4'	6090/01/01/CRI/IH/2100	Assumed Non Suspect ACM	50	SF	0				N/A	N/A	N/A
1 1	Nurse's Main Office	M	Sheetrock Wall	6090/01/01/CRI/IH/2100	Assumed	400	SF	0				1	No.	1/D
	Nurse's Main Office	N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	200	SF	0				N/A	N/A	N/A
1 1	Nurse's Main Office	M	Floor Tile VAT 12" x 12"	6090/01/01/12	Assumed	200	SF	0	Tan			1	No	1/D
1 1	Main Nurse's Office Restroom	N/A	Ceramic Tile Floors		Non Suspect ACM	50	SF	0				N/A	N/A	N/A
1 1	Main Nurse's Office Restroom	M	Sheetrock Wall	6090/01/01/CRI/IH/2100	Assumed	200	SF	0				1	No	1/D
	Main Nurse's Office Restroom	N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	50	SF	0				N/A	N/A	N/A
1 1	Hallway between Dental Lab, Conference Room and Offices near Main Office	M N/A	Sheetrock Wall	6090/01/01/CRI/IH/2100	Assumed	600 300	SF SF	0				N/A	No N/A	1/D N/A
	Hallway between Dental Lab, Conference Room and Offices near Main Office Hallway between Dental Lab, Conference Room and Offices near Main Office	M M	Fiberglass Ceiling Tile 2' x 4' Floor Tile VAT 12" x 12"	6090/01/01/12	Non Suspect ACM		SF	0	Orango			N/A 1	N/A No	1/D
	Hallway between Dental Lab, Conference Room and Offices near Main Office	M	Floor Tile VAT 12 x 12"	6090/01/01/12	Assumed Assumed	200	SF	0	Orange White			1	No.	1/D
	Hallway between Dental Lab, Conference Room and Offices near Main Office	N/A	Concrete Block Wall	0090/01/01/12	Non Suspect ACM	600	SF	0	AALIIG			N/A	N/A	N/A
1 1	Copy Room next to Main Office	M	Sheetrock Wall	6090/01/01/CRI/IH/2100	Assumed	900	SF	0			1	1	No	1/D
1 1	Copy Room next to Main Office	N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	450	SF	0				N/A	N/A	N/A
1 1	Copy Room next to Main Office	М	Floor Tile VAT 12" x 12"	6090/01/01/12	Assumed	450	SF	0	White			1	No	1/D
1 1	Office 5	M	Sheetrock Wall	6090/01/01/CRI/IH/2100	Assumed	500	SF	0	\longrightarrow		1	1	No	1/D
	Office 5	N/A	Fiberglass Ceiling Tile 2' x 4'	0000/04/04/45	Non Suspect ACM	200	SF	0	148-7			N/A	N/A	N/A
	Office 5	M M	Floor Tile VAT 12" x 12"	6090/01/01/12	Assumed	200	SF SF	0	White		 	1	No No	1/D 1/D
	Mini Conference Room 3 Mini Conference Room 3	N/A	Sheetrock Wall	6090/01/01/CRI/IH/2100	Assumed Non Suggest ACM	500 200	SF SF	0	 		 	N/A	No N/A	1/D N/A
	Initial Contracting MODIII 9		Fiberglass Ceiling Tile 2' x 4' Floor Tile VAT 12" x 12"	6090/01/01/12	Non Suspect ACM Assumed	200	SF	0	White		1	1N/A	N/A No	1/D
1 1	Mini Conference Room 3		1001 1110 VAL 12 A 12				SF	0	TTIME		1	1	No	1/D
1 1	Mini Conference Room 3 Office 9	M M	Sheetrock Wall	1 6090/01/01/CRI/IH/2100 I		500			 	 			N/A	N/A
1 1 1 1 1 1	Mini Conference Room 3 Office 9 Office 9	M M N/A	Sheetrock Wall Fiberglass Ceiling Tile 2' x 4'	6090/01/01/CRI/IH/2100	Assumed Non Suspect ACM	500 200	SF	0				N/A		1/D
1 1 1 1 1 1	Office 9 Office 9	М		6090/01/01/CRI/IH/2100 6090/01/01/12	Non Suspect ACM Assumed		SF SF	0	White			N/A 1	No	
1 1 1 1 1 1 1 1 1 1 1 1	Office 9 Office 9 Office 9 Office 9 Office 9 Office 9	M N/A M N/A	Fiberglass Ceiling Tile 2' x 4' Floor Tile VAT 12" x 12" Plaster Walls	6090/01/01/12	Non Suspect ACM Assumed NAD	200 200 300	SF SF		White SF	Sampled NAD March 1991			N/A	N/A
1 1 1 1 1 1 1 1 1 1 1 1 1 1	Office 9 Office 9 Office 9 Office 9 Office 9 Office 9	M N/A M N/A	Fiberglass Ceiling Tile 2' x 4' Floor Tile VAT 12" x 12" Plaster Walls Sheetrock Wall		Non Suspect ACM Assumed NAD Assumed	200 200 300 500	SF SF SF	0 20 0		Sampled NAD March 1991		1 N/A 1	N/A No	1/D
1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	Office 9 Office 9 Office 9 Office 9 Office 9 Office 9 Office 10 Office 10	M N/A M N/A M	Fiberglass Ceiling Tile 2' x 4' Floor Tile VAT 12" x 12" Plaster Walls Sheetrock Wall Fiberglass Ceiling Tile 2' x 4'	6090/01/01/12 6090/01/01/CRI/IH/2100	Non Suspect ACM Assumed NAD Assumed Non Suspect ACM	200 200 300 500 200	SF SF SF SF	0 20 0 0	SF	Sampled NAD March 1991		1 N/A 1 N/A	N/A No N/A	1/D N/A
1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	Office 9 Office 9 Office 9 Office 9 Office 9 Office 9 Office 10 Office 10	M N/A M N/A M N/A	Fiberglass Ceiling Tile 2' x 4' Floor Tile VAT 12" x 12" Plaster Walls Sheetrock Wall Fiberglass Ceiling Tile 2' x 4' Floor Tile VAT 12" x 12"	6090/01/01/12	Non Suspect ACM Assumed NAD Assumed Non Suspect ACM Assumed	200 200 300 500 200 200	SF SF SF SF	0 20 0 0				1 N/A 1 N/A 1	N/A No N/A No	1/D N/A 1/D
1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	Office 9 Office 9 Office 9 Office 9 Office 9 Office 9 Office 10 Office 10 Office 10 Office 10	M N/A M N/A M N/A M	Fiberglass Ceiling Tile 2' x 4' Floor Tile VAT 12" x 12" Plaster Walls Sheetrock Wall Fiberglass Ceiling Tile 2' x 4'	6090/01/01/12 6090/01/01/CRI/IH/2100	Non Suspect ACM Assumed NAD Assumed Non Suspect ACM Assumed NAD Assumed NAD	200 200 300 500 200 200 300	SF SF SF SF SF	0 20 0 0 0	SF White	Sampled NAD March 1991		1 N/A 1 N/A 1 N/A	N/A No N/A No N/A	1/D N/A 1/D N/A
1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	Office 9 Office 9 Office 9 Office 9 Office 9 Office 10 Office 10 Office 10 Office 10 Office 10 Office 10 Storage Room next to Office 9	M N/A M N/A M N/A M N/A X	Fiberglass Ceiling Tile 2' x 4' Floor Tile VAT 12" x 12" Plaster Walls Sheetrock Wall Fiberglass Ceiling Tile 2' x 4' Floor Tile VAT 12" x 12" Plaster Walls X	6090/01/01/12 6090/01/01/CRI/IH/2100 6090/01/01/12	Non Suspect ACM Assumed NAD Assumed Non Suspect ACM Assumed NAD X	200 200 300 500 200 200 300 X	SF SF SF SF SF SF	0 20 0 0 0 0 0	SF			1 N/A 1 N/A 1	N/A No N/A No N/A X	1/D N/A 1/D N/A X
1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	Office 9 Office 9 Office 9 Office 9 Office 9 Office 10 Office 10 Office 10 Office 10 Storage Room next to Office 9 Counselor Office 7	M N/A M N/A M N/A M	Fiberglass Ceiling Tile 2' x 4' Floor Tile WAT 12' x 12'' Plaster Walls Sheetrock Wall Fiberglass Ceiling Tile 2' x 4' Floor Tile VAT 12'' x 12'' Plaster Walls X Sheetrock Wall	6090/01/01/12 6090/01/01/CRI/IH/2100	Non Suspect ACM Assumed NAD Assumed Non Suspect ACM Assumed NAD X Assumed NAD X Assumed	200 200 300 500 200 200 300 X 500	SF SF SF SF SF SF SF	0 20 0 0 0	SF White	Sampled NAD March 1991		1 N/A 1 N/A 1 N/A	N/A No N/A No N/A	1/D N/A 1/D N/A
1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	Office 9 Office 9 Office 9 Office 9 Office 9 Office 10 Storage Room next to Office 9 Counselor Office 7 Counselor Office 7	M N/A M N/A M N/A M N/A X M N/A	Fiberqlass Ceiling Tile 2' x 4' Floor Tile VAT 12" x 12" Plaster Walls Sheetrock Wall Fiberqlass Ceiling Tile 2' x 4' Floor Tile VAT 12" x 12" Plaster Walls X Sheetrock Wall Fiberqlass Ceiling Tile 2' x 4'	6090/01/01/12 6090/01/01/CRI/IH/2100 6090/01/01/12 6090/01/01/CRI/IH/2100	Non Suspect ACM Assumed NAD Assumed Non Suspect ACM Assumed NAD X Assumed NAD X Assumed NON Suspect ACM	200 200 300 500 200 200 300 X 500 200	SF SF SF SF SF SF SF SF	0 20 0 0 0 0 0 X	SF White	Sampled NAD March 1991		1 N/A 1 N/A 1 N/A X	N/A No N/A No N/A X No N/A	1/D N/A 1/D N/A X 1/D N/A
1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	Office 9 Office 9 Office 9 Office 9 Office 9 Office 10 Office 10 Office 10 Office 10 Storage Room next to Office 9 Counselor Office 7 Counselor Office 7 Counselor Office 7	M N/A M N/A M N/A M N/A M N/A X M N/A	Fiberglass Ceiling Tile 2' x 4' Floor Tile WAT 12' x 12'' Plaster Walls Sheetrock Wall Fiberglass Ceiling Tile 2' x 4' Floor Tile VAT 12'' x 12'' Plaster Walls X Sheetrock Wall Fiberglass Ceiling Tile 2'' x 4'' Floor Tile VAT 12'' x 12'' Yet Tile WAT 12'' x 12'' Floor Tile WAT 12'' x 12''	6090/01/01/12 6090/01/01/CRI/IH/2100 6090/01/01/12	Non Suspect ACM Assumed NAD Assumed Non Suspect ACM Assumed NAD X Assumed NAD X Assumed	200 200 300 500 200 200 300 X 500 200 200 200	SF SF SF SF SF SF SF	0 20 0 0 0 0 0 X	SF White X X	Sampled NAD March 1991 No Access		1 N/A 1 N/A 1 N/A X	N/A No N/A No N/A X	1/D N/A 1/D N/A X
1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	Office 9 Office 9 Office 9 Office 9 Office 9 Office 9 Office 10 Office 10 Office 10 Office 10 Office 10 Office 10 Courselor Office 7	M N/A M	Fiberqlass Ceiling Tile 2' x 4' Floor Tile VAT 12" x 12" Plaster Walls Sheetrock Wall Fiberqlass Ceiling Tile 2' x 4' Floor Tile VAT 12" x 12" Plaster Walls X Sheetrock Wall Fiberqlass Ceiling Tile 2' x 4'	6090/01/01/12 6090/01/01/CRI/IH/2100 6090/01/01/12 6090/01/01/CRI/IH/2100	Non Suspect ACM Assumed NAD Assumed Non Suspect ACM Assumed Non Suspect ACM Assumed NAD X Assumed Non Suspect ACM Assumed Non Suspect ACM Assumed NaD Assumed NAD Assumed	200 200 300 500 200 200 300 X 500 200 200 200 200 500	SF SF SF SF SF SF SF SF SF SF	0 20 0 0 0 0 0 X 0 0	SF White X X	Sampled NAD March 1991		1 N/A 1 N/A 1 N/A X 1 N/A 1 N/A 1	N/A No N/A No N/A X No N/A No N/A No N/A	1/D N/A 1/D N/A X 1/D N/A X 1/D N/A 1/D N/A 1/D N/A 1/D N/A
1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	Office 9 Office 9 Office 9 Office 9 Office 9 Office 10 Office 10 Office 10 Office 10 Office 10 Office 10 Office 7 Courselor Office 7 Courselor Office 7 Courselor Office 7 Office 8 Office 8	M N/A M N/A M N/A M N/A X M N/A M N/A M N/A	Fiberglass Ceiling Tile 2' x 4' Floor Tile VAT 12' x 12' Plaster Walls Sheetrock Wall Fiberglass Ceiling Tile 2' x 4' Floor Tile VAT 12' x 12' Plaster Walls X Sheetrock Wall Fiberglass Ceiling Tile 2' x 4' Floor Tile VAT 12' x 12' Plaster Walls Fiberglass Ceiling Tile 2' x 4' Floor Tile VAT 12' x 12' Plaster Walls Sheetrock Wall Fiberglass Ceiling Tile 2' x 4'	6090/01/01/12 6090/01/01/CRI/IH/2100 6090/01/01/12 6090/01/01/CRI/IH/2100 6090/01/01/CRI/IH/2100	Non Suspect ACM Assumed NAD Assumed Non Suspect ACM Assumed NAD X Assumed NAD X Assumed Non Suspect ACM Assumed Non Suspect ACM Assumed Non Suspect ACM Assumed NAD NAD NAD NAD NAD NAD NAD	200 200 300 500 200 200 300 X 500 200 200 200 300 200 200	SF SF SF SF SF SF SF SF SF SF	0 20 0 0 0 0 0 X 0 0 0 0 0 0 0 0 0 0 0 0	SF White X X White	Sampled NAD March 1991 No Access		1 N/A 1 N/A 1 N/A X 1 N/A X	N/A No N/A No N/A X No N/A No N/A No N/A	1/D N/A 1/D N/A 1/D N/A X 1/D N/A 1/D N/A 1/D N/A 1/D N/A
1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	Office 9 Office 9 Office 9 Office 9 Office 9 Office 10 Office 10 Office 10 Office 10 Office 10 Office 10 Courselor Office 7 Counselor Office 7 Counselor Office 7 Counselor Office 7 Counselor Office 7 Office 8 Office 8	M N/A M N/A M N/A M N/A X M N/A M N/A M N/A	Fiberglass Ceiling Tile 2' x 4' Floor Tile VAT 12" x 12" Plaster Walls Sheetrock Wall Fiberglass Ceiling Tile 2' x 4' Floor Tile VAT 12" x 12" Plaster Walls X Sheetrock Wall Fiberglass Ceiling Tile 2' x 4' Floor Tile VAT 12" x 12" Plaster Walls Sheetrock Wall Fiberglass Ceiling Tile 2' x 4' Floor Tile VAT 12" x 12" Plaster Walls Sheetrock Wall Fiberglass Ceiling Tile 2' x 4' Floor Tile VAT 12" x 12"	6090/01/01/12 6090/01/01/CR//IH/2100 6090/01/01/12 6090/01/01/12 6090/01/01/12 6090/01/01/12 6090/01/01/12	Non Suspect ACM Assumed NAD Assumed Non Suspect ACM Assumed NAD X Assumed NAD X Assumed Non Suspect ACM Assumed Non Suspect ACM Assumed Non Suspect ACM Assumed NAD Assumed NAD Assumed NAD Assumed Nan Suspect ACM Assumed	200 200 300 500 200 200 200 300 X 500 200 200 500 500 200	SF SF SF SF SF SF SF SF SF SF SF	0 20 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	SF White X X	Sampled NAD March 1991 No Access		1 N/A 1 N/A 1 N/A X 1 N/A 1 N/A 1	N/A No N/A No N/A X No N/A No N/A No N/A No N/A	1/D N/A 1/D N/A X 1/D N/A X 1/D N/A 1/D N/A 1/D N/A 1/D N/A 1/D N/A 1/D N/A
1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	Office 9 Office 9 Office 9 Office 9 Office 9 Office 10 Office 7 Counselor Office 7 Counselor Office 7 Counselor Office 7 Office 8 Office 8 Office 8	M N/A M N/A M N/A M N/A X M N/A M N/A M N/A M M N/A	Fiberglass Ceiling Tile 2' x 4' Floor Tile VAT 12' x 12' Plaster Walls Sheetrock Wall Fiberglass Ceiling Tile 2' x 4' Floor Tile VAT 12' x 12' Plaster Walls X Sheetrock Wall Fiberglass Ceiling Tile 2' x 4' Floor Tile VAT 12' x 12' Plaster Walls Sheetrock Wall Fiberglass Ceiling Tile 2' x 4' Floor Tile VAT 12' x 12' Plaster Walls Sheetrock Wall Fiberglass Ceiling Tile 2' x 4' Floor Tile VAT 12' x 12' Sheetrock Wall	6090/01/01/12 6090/01/01/CRI/IH/2100 6090/01/01/12 6090/01/01/CRI/IH/2100 6090/01/01/CRI/IH/2100	Non Suspect ACM Assumed NAD Assumed Non Suspect ACM Assumed NAD Assumed NAD X Assumed Non Suspect ACM Assumed Non Suspect ACM Assumed Non Suspect ACM Assumed Assumed Assumed Assumed Assumed Assumed Assumed Assumed Assumed	200 200 300 500 200 200 300 X 500 200 200 200 200 200 200 200	SF SF SF SF SF SF SF SF SF SF SF SF	0 20 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	SF White X X White	Sampled NAD March 1991 No Access		1 N/A 1 N/A 1 N/A X 1 N/A 1 N/A 1 N/A 1 N/A 1	N/A No N/A No N/A No N/A X No N/A	1/D N/A 1/D N/A X 1/D N/A X 1/D N/A
1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	Office 9 Office 9 Office 9 Office 9 Office 9 Office 9 Office 10 Office 7 Counselor Office 7 Counselor Office 7 Counselor Office 7 Counselor Office 7 Office 8 Office 8 Office 8 Office 6 Office 6	M N/A M N/A M N/A M N/A X M N/A M N/A M M N/A M M N/A	Fiberqlass Ceiling Tile 2' x 4' Floor Tile VAT 12" x 12" Plaster Walls Sheetrock Wall Fiberqlass Ceiling Tile 2' x 4' Floor Tile VAT 12" x 12" Plaster Walls X Sheetrock Wall Fiberglass Ceiling Tile 2' x 4' Floor Tile VAT 12" x 12" Plaster Wall Fiberglass Ceiling Tile 2' x 4' Floor Tile VAT 12" x 12" Plaster Walls Sheetrock Wall Fiberglass Ceiling Tile 2' x 4' Floor Tile VAT 12" x 12" Sheetrock Wall Fiberglass Ceiling Tile 2' x 4' Floor Tile VAT 12" x 12" Sheetrock Wall	6090/01/01/12 6090/01/01/CRI/IH/2100 6090/01/01/12 6090/01/01/12 6090/01/01/12 6090/01/01/12 6090/01/01/CRI/IH/2100 6090/01/01/12 6090/01/01/12	Non Suspect ACM Assumed NAD Assumed Non Suspect ACM Assumed NAD X Assumed NAD X Assumed Non Suspect ACM Assumed Non Suspect ACM Assumed NAD Assumed NAD Assumed NAD Assumed Non Suspect ACM Assumed Non Suspect ACM Assumed Non Suspect ACM Assumed Assumed Assumed Assumed Assumed Non Suspect ACM	200 200 300 500 200 300 X 500 200 200 300 200 300 500 200 200 200 200 200 200	SF SF SF SF SF SF SF SF SF SF SF SF SF	0 20 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	SF White X X White White	Sampled NAD March 1991 No Access		1 N/A 1 N/A 1 N/A X 1 N/A 1 N/A 1	N/A No N/A No N/A No N/A X X No N/A	1/D N/A 1/D N/A X 1/D N/A X 1/D N/A
1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	Office 9 Office 9 Office 9 Office 9 Office 9 Office 10 Office 7 Counselor Office 7 Counselor Office 7 Counselor Office 7 Office 8 Office 8 Office 8	M N/A M N/A M N/A M N/A X M N/A M N/A M N/A M M N/A	Fiberglass Ceiling Tile 2' x 4' Floor Tile VAT 12' x 12' Plaster Walls Sheetrock Wall Fiberglass Ceiling Tile 2' x 4' Floor Tile VAT 12' x 12' Plaster Walls X Sheetrock Wall Fiberglass Ceiling Tile 2' x 4' Floor Tile VAT 12' x 12' Plaster Walls Sheetrock Wall Fiberglass Ceiling Tile 2' x 4' Floor Tile VAT 12' x 12' Plaster Walls Sheetrock Wall Fiberglass Ceiling Tile 2' x 4' Floor Tile VAT 12' x 12' Sheetrock Wall	6090/01/01/12 6090/01/01/CR//IH/2100 6090/01/01/12 6090/01/01/12 6090/01/01/12 6090/01/01/12 6090/01/01/12	Non Suspect ACM Assumed NAD Assumed Non Suspect ACM Assumed NAD Assumed NAD X Assumed Non Suspect ACM Assumed Non Suspect ACM Assumed Non Suspect ACM Assumed Assumed Assumed Assumed Assumed Assumed Assumed Assumed Assumed	200 200 300 500 200 200 300 X 500 200 200 200 200 200 200 200	SF SF SF SF SF SF SF SF SF SF SF SF	0 20 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	SF White X X White	Sampled NAD March 1991 No Access		1 N/A 1 N/A 1 N/A X 1 N/A 1 N/A 1 N/A 1 N/A 1	N/A No N/A No N/A No N/A X No N/A	1/D N/A 1/D N/A X 1/D N/A X 1/D N/A

										T				
	School District of Philadelphia	_	AHEF	RA Three-Year Reinspe	ection 2015-2016					Reinspection Date: 2/8/2016 - 2/9/2016	1			
	A. Philip Randolph Career and Technical High School	┙	R	oom by Room Location	n Log Report					Building Inspector: Mary Anne Lerro				
	3101 Henry Avenue		Red= Confirmed (Contact OEMS pr	rior to the disturbance of a	iny of the following materials	and report da	amag			Certificate Number:740092				
		7	Yellow= Assumed (Contact OEMS t					1			1			
1	Philadelphia, PA 19129	4	and report damage)							Management Planner: Monique Causley	1			ļ
			Green= Non Asbestos Containing/l Laboratory Analysis has indicated	Non Suspect Material (The	se materials have been samp	led and								
	ULCS# 6090		not typically known to contain Asb	NO ASDESTOS present or Ni estos)	ASBESTOS DETECTED OF th	ese materiais	s are			Certificate Number:ACC-0215-8-010				
			,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	1						Octanidate Namiber 1 (OC 02 10 0 0 10				
E I e F m I e o n o														1 1
l e F														1 1
m I												_		1 1
e o		System			Confirmed Assumed NAD	Amount of	9E 1 E	Amount of	SF LF Color required		Attic Crewlenace	Damage Potential	Newly	Response
t r	On Site Room Name	Affected	Material Description	HID#	Non Suspect ACM	Material	EÃ	Damage	EA for VAT	Comments/Description/Notes	Attic Crawispace Ranking	(DP)	Friable (NF)	Action (RA)
1 1	Data Server Room 4	N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	200	SF	0				N/A	N/A	N/A
1 1	Data Server Room 4	М	Floor Tile VAT 12" x 12"	6090/01/01/12	Assumed		SF	0	White			1	No	1/D
	Office to Right of Data Room 4	M	Sheetrock Wall	6090/01/01/CRI/IH/2100	Assumed		SF SF	0				1	No N/A	1/D
1 1	Office to Right of Data Room 4 Office to Right of Data Room 4	N/A M	Fiberglass Ceiling Tile 2' x 4' Floor Tile VAT 12" x 12"	6090/01/01/12	Non Suspect ACM Assumed	200 200	SF	0	White			N/A	N/A No	N/A 1/D
1 1	Principal's Office	M	Sheetrock Wall	6090/01/01/CRI/IH/2100	Assumed	800	SF	0	***************************************			1	No	1/D
1 1	Principal's Office	N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	400	SF	0				N/A	N/A	N/A
1 1	Principal's Office	M	Floor Tile VAT 12" x 12"	6090/01/01/12	Assumed	400	SF	0	Tan			1	No	1/D
1 1	Principal's Office	N/A	Wood Wall Panels	0000/04/04/05	Non Suspect ACM	400	SF SF	0			-	N/A	N/A	N/A 1/D
1 1	Principal's Office Main Office	M M	Transite Sills Sheetrock Wall	6090/01/01/09 6090/01/01/CRI/IH/2100	Assumed Assumed	16 1000	SF SF	0	 		-	1 1	No No	1/D 1/D
	Main Office	N/A	Ceiling Tile 2' x 4'	0030/01/01/GRIJI1/2100	NAD	550	SF	0		Sampled during original inspection Oct. 1988	 	N/A	N/A	N/A
	Main Office	M	Floor Tile VAT 12" x 12"	6090/01/01/12	Assumed	550	SF	0	Tan			1	No	1/D
1 1							05		QF.	Dental Lab has water stains throughout on				
	Dental Lab Classroom area with Smartboard Dental Lab Classroom area with Smartboard	N/A N/A	Concrete Block Wall Ceiling Tile 2' x 4'	+	Non Suspect ACM NAD	1000 550	SF SF	10 0	51	ceiling tile Sampled during original inspection Oct. 1988	-	N/A N/A	N/A N/A	N/A N/A
	Dental Lab Classroom area with Smartboard Dental Lab Classroom area with Smartboard	M M	Floor Tile VAT 12" x 12"	6090/01/01/12	Assumed	550	SF	0	White	Campica during original inspection Oct. 1900	I	1 1	No.	1/D
1 1	Large Dental Lab with sinks and training chairs	N/A	Concrete Block Wall		Non Suspect ACM	1800	SF	0				N/A	N/A	N/A
1 1	Large Dental Lab with sinks and training chairs	N/A	Ceiling Tile 2' x 4'		NAD	800	SF	6	SF	Sampled during original inspection Oct. 1988		N/A	N/A	N/A
1 1	Large Dental Lab with sinks and training chairs	М	Floor Tile VAT 12" x 12"	6090/01/01/12	Assumed		SF	0	White			1	No	1/D
1 1	Generator Room in Dental Lab	N/A	Cement Floor		Non Suspect ACM	50	SF	0				N/A	N/A	N/A
1 1	Generator Room in Dental Lab Generator Room in Dental Lab	N/A N/A	Concrete Block Wall Ceiling Tile 2' x 4'		Non Suspect ACM NAD	200 50	SF SF	2	SF	Sampled during original inspection Oct. 1988		N/A N/A	N/A N/A	N/A N/A
1 1	Storage Room in Dental Lab near Generator Room	N/A	Concrete Block Wall		Non Suspect ACM		SF	0	OI .	Combined with 38B		N/A	N/A	N/A
1 1	Storage Room in Dental Lab near Generator Room	N/A	Ceiling Tile 2' x 4'		NAD	75	SF	0		Sampled during original inspection Oct. 1988		N/A	N/A	N/A
1 1	Storage Room in Dental Lab near Generator Room	M	Floor Tile VAT 12" x 12"	6090/01/01/12	Assumed	75	SF	0	White			1	No	1/D
	Classroom 39	N/A M	Concrete Block Wall	0000/04/04/40	Non Suspect ACM		SF	0	T	Combined with 39		N/A	N/A	N/A
1 1	Classroom 39 Classroom 39	N/A	Floor Tile VAT 12" x 12" Fiberglass Ceiling Tile 2' x 4'	6090/01/01/12	Assumed Non Suspect ACM	600 600	SF SF	0	Tan			1 N/A	No N/A	1/D N/A
1 1	Classroom 39	M	Sheetrock Wall	6090/01/01/CRI/IH/2100	Assumed	800	SF	0				1	No	1/D
1 1	Closet in Hallway near Classrooms 39, 38 and 37	Х	X		X	Х	Х	Х	X X	No Access		Х	X	Х
1 1	Office/Storage outside Classroom 39	N/A	Concrete Block Wall		Non Suspect ACM	400	SF	0				N/A	N/A	N/A
1 1	Office/Storage outside Classroom 39	M	Floor Tile VAT 12" x 12"	6090/01/01/12	Assumed	150	SF	0	Orange			1	No	1/D
1 1	Office/Storage outside Classroom 39 Hallway next to Classrooms 37 to 39	N/A N/A	Fiberglass Ceiling Tile 2' x 4' Concrete Block Wall		Non Suspect ACM Non Suspect ACM	150 1400	SF SF	0				N/A N/A	N/A N/A	N/A N/A
	Hallway next to Classrooms 37 to 39	M	Floor Tile VAT 12" x 12"	6090/01/01/12	Assumed	700	SF	0	Tan			1	No	1/D
1 1	Hallway next to Classrooms 37 to 39	N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	700	SF	0				N/A	N/A	N/A
1111	Hallway next to Classrooms 37 to 39	l M	Sheetrock Wall	6090/01/01/CRI/IH/2100	Assumed	200	SF	10	QF	What kind of damage? Please fill out additional			No	6/C
	Classroom 36	N/A	Concrete Block Wall	0090/01/01/CKI/II1/2100	Non Suspect ACM		SF	0	JF.	conditions for Assumed Damaged Materials		N/A	N/A	N/A
1 1	Classroom 36	M	Floor Tile VAT 12" x 12"	6090/01/01/12	Assumed	750	SF	0	Red			1	No	1/D
1 1	Classroom 36	M	Floor Tile VAT 12" x 12"	6090/01/01/12	Assumed	100	SF	0	Tan			1	No	1/D
1 1 1	Classroom 36	l M	Sheetrock Wall	6090/01/01/CRI/IH/2100	Assumed	600	SF	10	SE	What kind of damage? Please fill out additional conditions for Assumed Damaged Materials		١ ,	No	6/C
	Classroom 36	N/A	Fiberglass Ceiling Tile 2' x 4'	200000000000000000000000000000000000000	Non Suspect ACM	850	SF	0	, , , , , , , , , , , , , , , , , , ,	25	1	N/A	N/A	N/A
1 1	Classroom 37	N/A	Concrete Block Wall		Non Suspect ACM	700	SF	0				N/A	N/A	N/A
1 1	Classroom 37	М	Floor Tile VAT 12" x 12"	6090/01/01/12	Assumed	700	SF	0	Orange			1	No	1/D
1 1	Classroom 37	N/A	Fiberglass Ceiling Tile 2' x 4'	0000/04/04/07/07/07	Non Suspect ACM	700	SF	4	SF		-	N/A	N/A	N/A
1 1 1	Classroom 37 Training Kitchen	M N/A	Sheetrock Wall Ceramic Tile Floors	6090/01/01/CRI/IH/2100	Assumed Non Suspect ACM	700 1500	SF SF	0		Combined with 58A		1 N/A	No N/A	1/D N/A
	Training Kitchen	N/A	Concrete Block Wall	1	Non Suspect ACM	3000	SF	0		Comparison with 50%	I	N/A	N/A	N/A
1 1	Training Kitchen	N/A	Plaster Ceiling		NAD	1500	SF	0		Sampled NAD March 1991		N/A	N/A	N/A
1 1	Eating Lounge in Front of Training Kitchen(next to classroom 79	N/A	Concrete Block Wall		Non Suspect ACM	1500	SF	0				N/A	N/A	N/A
1 1	Eating Lounge in Front of Training Kitchen(next to classroom 79	M	Floor Tile VAT 12" x 12"	6090/01/01/12	Assumed		SF	0	White			1 1	No	1/D
1 1 1	Eating Lounge in Front of Training Kitchen(next to classroom 79 Hallway next to Kitchen, Offices and Kitchen Restroom	N/A N/A	Fiberglass Ceiling Tile 2' x 4' Concrete Block Wall	+	Non Suspect ACM Non Suspect ACM	1100 800	SF SF	16	SF		-	N/A N/A	N/A N/A	N/A N/A
1 1	Hallway next to Kitchen, Offices and Kitchen Restroom Hallway next to Kitchen, Offices and Kitchen Restroom	M M	Floor Tile VAT 12" x 12"	6090/01/01/12	Assumed	500	SF	0	White			1 1	N/A No	1/D
1 1	Hallway next to Kitchen, Offices and Kitchen Restroom	N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM		SF	0	********			N/A	N/A	N/A
1 1	Classroom Connected to Front of Kitchen	N/A	Concrete Block Wall		Non Suspect ACM	1500	SF	0				N/A	N/A	N/A
1 1	Classroom Connected to Front of Kitchen	М	Floor Tile VAT 12" x 12"	6090/01/01/12	Assumed	800	SF	0	White			1	No	1/D
	Classroom Connected to Front of Kitchen	N/A	Fiberglass Ceiling Tile 2' x 4'	1	Non Suspect ACM		SF	0				N/A	N/A	N/A
1 1	Classroom 52 Classroom 52	N/A N/A	Fiberglass Ceiling Tile 2' x 4' Concrete Block Wall	1	Non Suspect ACM Non Suspect ACM	650 900	SF SF	0			l	N/A N/A	N/A N/A	N/A N/A
1 1	Classroom 52	M M	Floor Tile VAT 12" x 12"	6090/01/01/12	Assumed	650	SF	0	Tan			1 1	No No	1/D
1 1	Classroom 53	N/A	Concrete Block Wall		Non Suspect ACM	1400	SF	0		Combined with 54C		N/A	N/A	N/A
1 1	Classroom 53	М	Floor Tile VAT 12" x 12"	6090/01/01/12	Assumed	700	SF	0	Orange			1	No	1/D
1 1	Classroom 53	N/A N/A	Fiberglass Ceiling Tile 2' x 4'	+	Non Suspect ACM	700 400	SF SF	0			 	N/A N/A	N/A N/A	N/A N/A
1 1	Office in Classroom 53 Office in Classroom 53	M M	Concrete Block Wall Floor Tile VAT 12" x 12"	6090/01/01/12	Non Suspect ACM Assumed		SF	0	Tan		-	1 1 1	N/A No	1/D
	Office III Olassicotti 33	I IVI	I FIUUL LIIC VALLE A IZ	0030/01/01/12	Magnillen	100	OF.	U	I I I I I I	1			INU	110

		_													
	School District of Philadelphia	_		A Three-Year Reinspe							Reinspection Date: 2/8/2016 - 2/9/2016				
	A. Philip Randolph Career and Technical High School	4	1	om by Room Location							Building Inspector: Mary Anne Lerro	1			
	3101 Henry Avenue	4	Red= Confirmed (Contact OEMS pri								Certificate Number:740092	1			
	Philadelphia, PA 19129		Yellow= Assumed (Contact OEMS for and report damage)	r assessment and sampl	ing prior to the disturbance of	these mate	rials				Management Planner: Monique Causley				
		7	Green= Non Asbestos Containing/N Laboratory Analysis has indicated N	on Suspect Material (The	se materials have been sampl	led and]			. 4	1			
	ULCS# 6090		Laboratory Analysis has indicated N not typically known to contain Asbe	O Asbestos present or NO	O ASBESTOS DETECTED or the	ese material	ls are				Certificate Number:ACC-0215-8-010				
	02007 0000		not typically known to contain 755c	1							Certificate Number ACC-02 15-0-010				
Ę															
e F															
m I e o												Attic	Damage Potential		
e o n o	On Site Room Name	System Affected	Material Description	HID#	Confirmed Assumed NAD Non Suspect ACM	Amount of Material	SF LF	Amount of Damage	SF LF EA	Color required for VAT	Comments/Description/Notes	Crawispace Ranking	Potential (DP)	Newly Friable (NF)	Response Action (RA)
	Office in Classroom 53	N/A	Fiberglass Ceiling Tile 2' x 4'	7,10,11	Non Suspect ACM	150	SF	0		10, 1,1,		rannung	N/A	N/A	N/A
1 1	Classroom 54	N/A M	Concrete Block Wall	0000/04/04/40	Non Suspect ACM	2000	SF SF	0		14.10			N/A	N/A	N/A
	Classroom 54 Classroom 54	N/A	Floor Tile VAT 12" x 12" Concrete Ceiling	6090/01/01/12	Assumed Non Suspect ACM	1500 1500	SF	0		Multi			N/A	No N/A	1/D N/A
1111	Classroom 55	N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	650	SF	0					N/A	N/A	N/A
1 1	Classroom 55	N/A	Concrete Block Wall		Non Suspect ACM	900	SF	0		_			N/A	N/A	N/A
1 1	Classroom 55 Classroom 54 Restroom	M N/A	Floor Tile VAT 12" x 12" Cement Floor	6090/01/01/12	Assumed Non Suspect ACM	650 50	SF SF	0		Tan			N/A	No N/A	1/D N/A
1 1	Classroom 54 Restroom	N/A	Concrete Block Wall		Non Suspect ACM	200	SF	0					N/A	N/A	N/A
1 1	Classroom 54 Restroom	N/A	Ceiling Tile 2' x 4'		NAD	50	SF	0			Sampled during original inspection Oct. 1988 Sampled during original inspection Oct. 1988		N/A	N/A	N/A
	Hallway between Classrooms 53, 54, 55, 56	N/A	Ceiling Tile 2' x 4'		NAD	700	SF	2	SF		water stained		N/A	N/A	N/A
	Hallway between Classrooms 53, 54, 55, 56 Hallway between Classrooms 53, 54, 55, 56	N/A M	Concrete Block Wall Floor Tile VAT 12" x 12"	6090/01/01/12	Non Suspect ACM	1400	SF SF	0		Ton			N/A	N/A No	N/A 1/D
	Hallway between Classrooms 53, 54, 55, 56 Hallway between Classrooms 53, 54, 55, 56	M	Sheetrock Wall	6090/01/01/12 6090/01/01/CRI/IH/2100	Assumed Assumed	700 500	SF	0		Tan			1	No No	1/D
1 1	Classroom 56	N/A	Ceiling Tile 2' x 4'		NAD	700	SF	0			Sampled during original inspection Oct. 1988		N/A	N/A	N/A
1 1	Classroom 56	N/A	Concrete Block Wall		Non Suspect ACM	1400	SF	0			What kind of damage? Please fill out additional		N/A	N/A	N/A
1 1	Classroom 56	М	Floor Tile VAT 12" x 12"	6090/01/01/12	Assumed	700	SF	4	SF	Tan	conditions for Assumed Damaged Materials		1	No	6/C
1 1	Classroom 56	M N/A	Sheetrock Wall	6090/01/01/CRI/IH/2100	Assumed	400	SF	0					1	No N/A	1/D
1 1	Closet in Classroom 56 Closet in Classroom 56	N/A N/A	Cement Floor Concrete Block Wall		Non Suspect ACM Non Suspect ACM	50 150	SF SF	0					N/A N/A	N/A N/A	N/A N/A
1 1	Closet in Classroom 56	N/A	Ceiling Tile 2' x 4'		NAD	50	SF	0					N/A	N/A	N/A
1 1	Large Storage Closet in CLassroom 56	N/A	Cement Floor		Non Suspect ACM	200	SF	0					N/A	N/A	N/A
1 1	Large Storage Closet in CLassroom 56 Large Storage Closet in CLassroom 56	N/A N/A	Concrete Block Wall Ceiling Tile 2' x 4'		Non Suspect ACM NAD	400 200	SF SF	0					N/A N/A	N/A N/A	N/A N/A
1 1	Restroom in Classroom 56	N/A	Cement Floor		Non Suspect ACM	50	SF	0					N/A	N/A	N/A
	Restroom in Classroom 56	N/A	Concrete Block Wall		Non Suspect ACM	200	SF SF	0					N/A	N/A N/A	N/A
1 1	Restroom in Classroom 56 Restroom in Hallway outside Classroom 56	N/A N/A	Fiberglass Ceiling Tile 2' x 4' Cement Floor		Non Suspect ACM Non Suspect ACM	50 50	SF	0					N/A N/A	N/A N/A	N/A N/A
1 1	Restroom in Hallway outside Classroom 56	N/A	Concrete Block Wall		Non Suspect ACM	200	SF	0					N/A	N/A	N/A
1 1	Restroom in Hallway outside Classroom 56	N/A	Ceiling Tile 2' x 4'		NAD	50	SF	0					N/A	N/A	N/A
1 1	Storage Closet adjacent to Classroom 56 with Shower/lockers Storage Closet adjacent to Classroom 56 with Shower/lockers	N/A N/A	Cement Floor Concrete Block Wall		Non Suspect ACM Non Suspect ACM	50 200	SF SF	0					N/A N/A	N/A N/A	N/A N/A
1 1	Storage Closet adjacent to Classroom 56 with Shower/lockers	N/A	Ceiling Tile 2' x 4'		NAD	50	SF	0					N/A	N/A	N/A
1 1	Storage Closet adjacent to Classroom 56 with Shower/lockers Storage Closet adjacent to Classroom 56 with Shower/lockers	N/A N/A	Ceramic Tile Floors Ceramic Tile Walls		Non Suspect ACM Non Suspect ACM	50 70	SF SF	0					N/A N/A	N/A N/A	N/A N/A
	Boy's Restroom in Main Hall adjacent to Classroom 56	N/A	Cement Floor		Non Suspect ACM	350	SF	0					N/A	N/A	N/A
1 1	Boy's Restroom in Main Hall adjacent to CLassroom 56	N/A	Ceramic Tile Walls		Non Suspect ACM	700	SF	0					N/A	N/A	N/A
1 1	Boy's Restroom in Main Hall adjacent to CLassroom 56 Girl's Restroom in Main Hall adjacent to CLassroom 56	N/A N/A	Ceiling Tile 2' x 4' Cement Floor		NAD Non Suspect ACM	350 350	SF SF	0					N/A N/A	N/A N/A	N/A N/A
	Girl's Restroom in Main Hall adjacent to CLassroom 56	N/A	Cerranic Tile Walls		Non Suspect ACM	700	SF	0					N/A	N/A	N/A
	Girl's Restroom in Main Hall adjacent to CLassroom 56	N/A	Ceiling Tile 2' x 4'		NAD	350	SF	0					N/A	N/A	N/A
1 1	Hallway next to Classroom 56	N/A	Concrete Block Wall		Non Suspect ACM	800	SF	0			What kind of damage? Please fill out additional		N/A	N/A	N/A
	Hallway next to Classroom 56	М	Sheetrock Wall	6090/01/01/CRI/IH/2100	Assumed	400	SF	10	SF		What kind of damage? Please fill out additional conditions for Assumed Damaged Materials		11	No	6/C
	Hallway next to Classroom 56 Hallway next to Classroom 56	M N/A	Floor Tile VAT 12" x 12" Ceiling Tile 2' x 4'	6090/01/01/12	Assumed NAD	400 400	SF SF	0		Tan	Sampled during original inspection Oct. 1990	-	1 N/A	No N/A	1/D N/A
	Welding Classroom Corner Storage Closet	N/A N/A	Cement Floor		Non Suspect ACM	350	SF	0					N/A N/A	N/A N/A	N/A N/A
	Welding Classroom Corner Storage Closet	N/A	Ceiling Tile 2' x 4'		NAD	350	SF	25	SF		Sampled during original inspection Oct. 1991 Water Damage ceiling tile		N/A	N/A	N/A
	Welding Classroom Corner Storage Closet Welding Classroom Corner Storage Closet	N/A N/A	Concrete Block Wall		Non Suspect ACM	700	SF	0	ЭГ		water Damage cennig tile		N/A N/A	N/A N/A	N/A N/A
1 1	Welding Classroom Corner Storage Closet	N/A	Fiberglass Pipe Fitting Insulation		Non Suspect ACM	4	EA	0					N/A	N/A	N/A
	Welding Classroom Corner Storage Closet Welding Large Storage next to Classroom	N/A N/A	Fiberglass Pipe Insulation Cement Floor		Non Suspect ACM Non Suspect ACM	15 350	LF SF	0			Combined with 94D		N/A N/A	N/A N/A	N/A N/A
1 1	Welding Large Storage next to Classroom Welding Large Storage next to Classroom	N/A	Ceiling Tile 2' x 4'		NOTI SUSPECT ACM NAD	350	SF	0			Sampled during original inspection Oct. 1991		N/A	N/A	N/A
1 1	Welding Large Storage next to Classroom	N/A	Concrete Block Wall		Non Suspect ACM	700	SF	0					N/A	N/A	N/A
	Welding Classroom near Welding hands on Area Welding Classroom near Welding hands on Area	N/A N/A	Cement Floor Metal Ceiling Deck	+	Non Suspect ACM Non Suspect ACM	1000	SF SF	0				-	N/A N/A	N/A N/A	N/A N/A
1 1	Welding Classroom near Welding hands on Area	N/A	Concrete Block Wall		Non Suspect ACM	2000	SF	0					N/A	N/A	N/A
1 1	Welding Classroom near Welding hands on Area	N/A	Fiberglass Pipe Fitting Insulation		Non Suspect ACM	40	EA	0					N/A	N/A	N/A
1 1	Welding Classroom near Welding hands on Area Welding Classroom near Welding hands on Area	N/A M	Fiberglass Pipe Insulation Sheetrock Wall	6090/01/01/CRI/IH/2100	Non Suspect ACM Assumed	600	LF SF	0					N/A 1	N/A No	N/A 1/D
1 1	Storage/Lockers Room adjacent to Welding lockers	N/A	Cement Floor	555570 170 1701 (811 1/2 100	Non Suspect ACM	350	SF	0					N/A	N/A	N/A
1 1	Storage/Lockers Room adjacent to Welding lockers	N/A	Ceiling Tile 2' x 4'		NAD	350	SF	0			Sampled during original inspection Oct. 1991		N/A	N/A	N/A
	Storage/Lockers Room adjacent to Welding lockers Storage/Lockers Room adjacent to Welding lockers	N/A N/A	Concrete Block Wall Fiberglass Pipe Fitting Insulation	1	Non Suspect ACM Non Suspect ACM	700	SF EA	0					N/A N/A	N/A N/A	N/A N/A
1111	Storage/Lockers Room adjacent to Welding lockers	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	15	LF	0					N/A	N/A	N/A
1 1	Storage/Lockers Room adjacent to Welding lockers	N/A	Concrete Ceiling		Non Suspect ACM	350	SF	0					N/A	N/A	N/A

	Only and District of Diving delaying	1													
	School District of Philadelphia	+		A Three-Year Reinspo							Reinspection Date: 2/8/2016 - 2/9/2016	-			
1	A. Philip Randolph Career and Technical High School	+		om by Room Locatio							Building Inspector: Mary Anne Lerro				
1	3101 Henry Avenue	-	Red= Confirmed (Contact OEMS pri							9	Certificate Number:740092	-			
	Philadelphia, PA 19129	1	Yellow= Assumed (Contact OEMS fo and report damage)							1	Management Planner: Monique Causley				
	ULCS# 6090		Green= Non Asbestos Containing/N. Laboratory Analysis has indicated N. not typically known to contain Asbes	on Suspect Material (The O Asbestos present or Ni stos)	o ASBESTOS DETECTED or the	ed and ese material	ls are				Certificate Number:ACC-0215-8-010				
			,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,												1
E I e F m I															
e c		System			Confirmed Assumed NAD	Amount of	SF LF	Amount of	SF LF	Color required for VAT		Attic Crawispace Ranking	Damage Potential	Newly	Response
t i	On Site Room Name	Affected	Material Description	HID#	Non Suspect ACM			Damage 0	EA	for VAT	Comments/Description/Notes	Ranking	(DP)	Friable (NF)) Action (RA)
1 1	Storage next to Welding Locker Rooms Storage next to Welding Locker Rooms	N/A N/A	Cement Floor Ceiling Tile 2' x 4'		Non Suspect ACM NAD	350 350	SF SF	0			Sampled during original inspection Oct. 1991		N/A N/A	N/A N/A	N/A N/A
1 1	Storage next to Welding Locker Rooms	N/A	Concrete Block Wall		Non Suspect ACM	700	SF	0			Sampled daring original mopeonion con. 1001		N/A	N/A	N/A
1 1 1	Storage next to Welding Locker Rooms	N/A	Concrete Ceiling		Non Suspect ACM	350	SF	0					N/A	N/A	N/A
1 1	IMC Storage Closet IMC Office	X	X		X	X	X	X 0	X	Х			X	X	X
	IMC Office	N/A M	Fiberglass Ceiling Tile 2' x 4' Floor Tile VAT 12" x 12"	6090/01/01/12	Non Suspect ACM Assumed	400 400	SF SF	0		Grey			N/A 1	N/A No	N/A 1/D
1 1 1	IMC Office	N/A	Concrete Block Wall	0030/01/01/12	Non Suspect ACM	1000	SF	0		Oicy			N/A	N/A	N/A
1 1	IMC Room	N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	1300	SF	0					N/A	N/A	N/A
	IMC Room	M	Floor Tile VAT 12" x 12"	6090/01/01/12	Assumed	650	SF	0		Grey		-	1	No	1/D
1 1	IMC Room	N/A M	Concrete Block Wall Floor Tile VAT 12" x 12"	6090/01/01/12	Non Suspect ACM Assumed	2400 650	SF SF	0		Blue			N/A	N/A No	1/D
1 1	Classroom to the Right of the Auto Body Office	N/A	Fiberglass Ceiling Tile 2' x 4'	0030/01/01/12	Non Suspect ACM	300	SF	0		Dide			N/A	N/A	N/A
1 1	Classroom to the Right of the Auto Body Office	М	Floor Tile VAT 12" x 12"	6090/01/01/12	Assumed	300	SF	0		White			1	No	1/D
1 1	Classroom to the Right of the Auto Body Office	N/A	Concrete Block Wall		Non Suspect ACM	700	SF	0		\vdash			N/A	N/A	N/A
1 1	Student Restroom in Auto Garage area near garage doors Student Restroom in Auto Garage area near garage doors	N/A N/A	Cement Floor Ceiling Tile 2' x 4'	-	Non Suspect ACM NAD	25 25	SF SF	0	-		Sampled during original inspection Oct. 1991	 	N/A N/A	N/A N/A	N/A N/A
	Student Restroom in Auto Garage area near garage doors	N/A	Concrete Block Wall		Non Suspect ACM	150	SF	0			Sampled during original inspection Oct. 1991		N/A	N/A	N/A
1 1 1	Storage Room in Auto Area next to "Gentlemen's Restroom"	Х	X		X	X	X	X	Х	Х			X	X	X
1 1	Gentlemen's Restroom in Auto garage area	N/A	Cement Floor		Non Suspect ACM	25	SF	0					N/A	N/A	N/A
1 1	Gentlemen's Restroom in Auto garage area	M N/A	Sheetrock Ceiling	6090/01/01/CRI/IH/2101	Assumed Non Control of Control	25	SF SF	0					1 N/A	No N/A	1/D N/A
	Gentlemen's Restroom in Auto garage area Office to Left of Gentlemen's Restroom	N/A M	Concrete Block Wall Floor Tile VAT 12" x 12"	6090/01/01/12	Non Suspect ACM Assumed	150 800	SF	0		Tan			N/A	N/A No	1/D
1 1	Office to Left of Gentlemen's Restroom	N/A	Concrete Block Wall	0000/01/01/12	Non Suspect ACM	1600	SF	0		- run			N/A	N/A	N/A
	Office to Left of Gentlemen's Restroom	N/A	Ceiling Tile 2' x 4'		NAD	1600	SF	0		5	Sampled during original inspection Oct. 1991		N/A	N/A	N/A
1 1	Closet in Office next to Gentlemen's Restroom	X	X		X	X	X SF	X	X	X			X	N/A	X
1 1	Large Welding Hands on Area Large Welding Hands on Area	N/A N/A	Cement Floor Concrete Block Wall		Non Suspect ACM Non Suspect ACM	2500 4500	SF	0				-	N/A N/A	N/A N/A	N/A N/A
	Large Welding Hands on Area	N/A	Metal Ceiling Deck		Non Suspect ACM	2500	SF	0					N/A	N/A	N/A
1 1 1 1	Large Welding Hands on Area	N/A	Fiberglass Pipe Fitting Insulation		Non Suspect ACM	2	EA	0					N/A	N/A	N/A
1 1	Large Welding Hands on Area	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	20	LF	0					N/A	N/A	N/A
1 1	Auto Body Workshop Auto Body Workshop	N/A N/A	Cement Floor Concrete Block Wall		Non Suspect ACM Non Suspect ACM	1400 2800	SF SF	0					N/A N/A	N/A N/A	N/A N/A
								-			Sampled NAD March 1991 Damaged falling on				
1 1	Auto Body Workshop	N/A	Plaster Ceiling		NAD	1400	SF	75	SF	f	floor		N/A	N/A	N/A
1 1	Auto Body Workshop Auto Body Workshop	N/A N/A	Fiberglass Pipe Fitting Insulation Fiberglass Pipe Insulation		Non Suspect ACM Non Suspect ACM	28	EA LF	0					N/A N/A	N/A N/A	N/A N/A
1 1	Auto Body Workshop Auto Body Corner Workshop near Corner Office	N/A	Cement Floor		Non Suspect ACM	4000	SF	0					N/A	N/A	N/A
1 1	Auto Body Corner Workshop near Corner Office	N/A	Concrete Block Wall		Non Suspect ACM	8000	SF	0					N/A	N/A	N/A
1 1	Auto Body Corner Workshop near Corner Office	N/A	Plaster Ceiling		NAD	1400	SF	0		5	Sampled NAD March 1991		N/A	N/A	N/A
	Auto Body Corner Workshop near Corner Office Auto Body Corner Workshop near Corner Office	N/A N/A	Fiberglass Pipe Fitting Insulation		Non Suspect ACM Non Suspect ACM	24 60	EA LF	0					N/A N/A	N/A N/A	N/A N/A
	Auto Body Corner Workshop near Corner Office Auto Body Corner Workshop near Corner Office	N/A N/A	Fiberglass Pipe Insulation Metal Ceiling Deck		Non Suspect ACM Non Suspect ACM	3000	SF	0		 		 	N/A N/A	N/A N/A	N/A N/A
1 1	Auto Body Corner Workshop near Corner Office	N/A	Ceramic Tile Walls		Non Suspect ACM	1500	SF	Ö					N/A	N/A	N/A
1 1 1	Auto Body Shop Office	N/A	Ceiling Tile 2' x 4'	0000/01/21/12	NAD	200	SF	0		5	Sampled during original inspection Oct. 1991		N/A	N/A	N/A
111	Auto Body Shop Office Auto Body Shop Office	M N/A	Floor Tile VAT 12" x 12"	6090/01/01/12	Assumed Non Suspect ACM	200 500	SF SF	0		Pink		 	1 N/A	No N/A	1/D N/A
111	Office next to Welding Tool Room	N/A N/A	Ceramic Tile Walls Cement Floor		Non Suspect ACM Non Suspect ACM	1000	SF	0		 		 	N/A N/A	N/A N/A	N/A N/A
1 1	Office next to Welding Tool Room	N/A	Concrete Block Wall		Non Suspect ACM	2000	SF	Ö					N/A	N/A	N/A
	Office next to Welding Tool Room	N/A	Plaster Ceiling		NAD	1000	SF	0		5	Sampled NAD March 1991		N/A	N/A	N/A
1 1	Tool Room in Welding Area	N/A	Cement Floor		Non Suspect ACM	1000	SF SF	0		 		-	N/A	N/A N/A	N/A
1 1	Tool Room in Welding Area Tool Room in Welding Area	N/A N/A	Concrete Block Wall Plaster Ceiling		Non Suspect ACM NAD	2000 1000	SF	0			Sampled NAD March 1991	-	N/A N/A	N/A N/A	N/A N/A
1 1	Restroom in Auto Body Classroom	N/A	Ceramic Tile Floors		Non Suspect ACM	50	SF	0					N/A	N/A	N/A
1 1	Restroom in Auto Body Classroom	N/A	Ceiling Tile 2' x 4'		NAD	50	SF	0		5	Sampled during original inspection Oct. 1991		N/A	N/A	N/A
111	Restroom in Auto Body Classroom Classroom near Auto Classroom	N/A M	Concrete Block Wall Floor Tile VAT 12" x 12"	6090/01/01/12	Non Suspect ACM Assumed	200 400	SF SF	0		Tan		-	N/A	N/A No	N/A 1/D
	Classroom near Auto Classroom Classroom near Auto Classroom	N/A	Concrete Block Wall	0030/01/01/12	Non Suspect ACM	800	SF	0		ıdlı		I	N/A	N/A	N/A
1 1	Classroom near Auto Classroom	N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	400	SF	0					N/A	N/A	N/A
1 1	Storage near Welding area and Restroom	Х	X		X	Х	Х	Х	Х	Х			Х	Х	X
1 1	Gymnasium	N/A N/A	Concrete Block Wall		Non Suspect ACM NAD	3000 1500	SF SF	0	-	ļ .	Complet NAD Moreh 1001	<u> </u>	N/A N/A	N/A N/A	N/A N/A
1 1	Gymnasium Gymnasium	M/A	Plaster Ceiling Floor Tile VAT 12" x 12"	6090/01/01/12	NAD Assumed	1500	SF	0		Grev	Sampled NAD March 1991	l	N/A	N/A No	1/D
1 1	Gymnasium	N/A	Fiberglass Pipe Insulation	0030/01/01/12	Non Suspect ACM	10	LF	0		Sicy			N/A	N/A	N/A
1 1 1	Gymnasium	N/A	Fiberglass Pipe Fitting Insulation		Non Suspect ACM	2	EA	0					N/A	N/A	N/A
1 1	Gymnasium	T	Radiator Insulation	6090/01/01/CRI/IH/1600	Assumed	3	SF	0		 	Mhat kind of damage 2 Plant of W.		1	No	1/D
1 1	Gymnasium	м	Sheetrock Wall	6090/01/01/CRI/IH/2100	Assumed	300	SF	5	SF]	What kind of damage? Please fill out additional conditions for Assumed Damaged Materials	I	1	No	6/C
	Equipment Storage in Gym on Exterior Wall	M	Floor Tile VAT 12" x 12"	6090/01/01/12	Assumed	250	SF	0		Grey			1	No	1/D
	•								-						

	School District of Philadelphia		ΔHFR/	A Three-Year Reinsp	ection 2015-2016						Reinspection Date: 2/8/2016 - 2/9/2016				
	A. Philip Randolph Career and Technical High School	1		om by Room Locatio							Building Inspector: Mary Anne Lerro	1			
ł	• • • • • • • • • • • • • • • • • • • •	+	ed= Confirmed (Contact OEMS prior to the disturbance of any of the following materials and report damag									1			
	3101 Henry Avenue	+									Certificate Number:740092	-			
	Philadelphia, PA 19129		Yellow= Assumed (Contact OEMS fo and report damage)	r assessment and samp	ling prior to the disturbance or	tnese mate	riais				Management Planner: Monique Causley				
İ		1	Green= Non Asbestos Containing/No	on Suspect Material (The	ese materials have been sample	led and						1			
			Laboratory Analysis has indicated No	O Asbestos present or N	O ASBESTOS DETECTED or the	ese materia	ls are								
\vdash	ULCS# 6090		not typically known to contain Asbes	stos)		1					Certificate Number:ACC-0215-8-010				
E															
7 _															
e F															
e o						l	l		l			Attic	Damage		_
n 0	On Site Room Name	System Affected	Matarial Decembris	HID#	Confirmed Assumed NAD	Amount of	SFLF	Amount of	SFLF	Color require for VAT	d Comments/Description/Notes	Crawlspace Ranking	Potential (DP)	Newly Friable (NF)	Response Action (RA)
1 1	Equipment Storage in Gym on Exterior Wall	M	Material Description Sheetrock Ceiling	6090/01/01/CRI/IH/2101	Non Suspect ACM Assumed	250	SF	O		IOI VAI	Commenta/Description/Notes	renking	(DP)	No No	1/D
	Equipment Storage in Gym on Exterior Wall	N/A	Ceramic Tile Walls	0000/01/01/01/01/01/01	Non Suspect ACM	550	SF	0					N/A	N/A	N/A
1 1	Storage/ Exterior Access in Gym	М	Floor Tile VAT 12" x 12"	6090/01/01/12	Assumed	250	SF	0		Grey			1	No	1/D
1 1	Storage/ Exterior Access in Gym	M	Sheetrock Ceiling	6090/01/01/CRI/IH/2101	Assumed	250	SF	0					1	No	1/D
	Storage/ Exterior Access in Gym	N/A	Ceramic Tile Walls		Non Suspect ACM	550	SF	0		_			N/A	N/A	N/A
1 1	Locker Rooms in Gym Area	M	Floor Tile VAT 12" x 12"	6090/01/01/12	Assumed	500	SF SF	0		Grey			1	No	1/D
	Locker Rooms in Gym Area Locker Rooms in Gym Area	N/A N/A	Concrete Block Wall Ceiling Tile 2' x 4'		Non Suspect ACM NAD	1000 500	SF	0			Sampled during original inspection Oct. 1991		N/A N/A	N/A N/A	N/A N/A
	Center Gym Restroom	N/A	Cement Floor		Non Suspect ACM	450	SF	0			Sampled during original inspection Oct. 1991		N/A	N/A	N/A
1 1	Center Gym Restroom	N/A	Concrete Block Wall		Non Suspect ACM	850	SF	Ö					N/A	N/A	N/A
1 1	Center Gym Restroom	N/A	Plaster Ceiling		NAD	450	SF	0			Sampled NAD March 1991		N/A	N/A	N/A
1 1	Gym Restroom near Gym Entrance	M	Floor Tile VAT 12" x 12"	6090/01/01/12	Assumed	50	SF	0		Grey			1	No	1/D
	Gym Restroom near Gym Entrance	N/A	Concrete Block Wall		Non Suspect ACM	200	SF	0			Once I de la constitución de la	1	N/A	N/A	N/A
1 1	Gym Restroom near Gym Entrance Storage Near Front Restroom in Cym	N/A N/A	Ceiling Tile 2' x 4'		NAD NAD	50 150	SF SF	0	-		Sampled during original inspection Oct. 1991	1	N/A N/A	N/A N/A	N/A N/A
111	Storage Near Front Restroom in Gym Storage Near Front Restroom in Gym	N/A N/A	Ceiling Tile 2' x 4' Cement Floor		NAD Non Suspect ACM	150	SF	0	-		Sampled during original inspection Oct. 1991	 	N/A N/A	N/A N/A	N/A N/A
	Storage Near Front Restroom in Gym	N/A	Concrete Block Wall		Non Suspect ACM	500	SF	0					N/A	N/A	N/A
	Hallway adjacent to Auto Shop, Welding area and Gymnasium	М	Floor Tile VAT 12" x 12"	6090/01/01/12	Assumed	1400	SF	0		Tan			1	No	1/D
1 1	Hallway adjacent to Auto Shop, Welding area and Gymnasium	N/A	Concrete Block Wall		Non Suspect ACM	3700	SF	0					N/A	N/A	N/A
	Hallway adjacent to Auto Shop, Welding area and Gymnasium	N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	1400	SF	0					N/A	N/A	N/A
	Custodial Closet in Hallway outside Welding Area	N/A	Concrete Block Wall		Non Suspect ACM	150	SF	0					N/A	N/A	N/A
1 1	Custodial Closet in Hallway outside Welding Area Custodial Closet in Hallway outside Welding Area	N/A N/A	Cement Floor Concrete Ceiling		Non Suspect ACM Non Suspect ACM	25 25	SF SF	0					N/A N/A	N/A N/A	N/A N/A
	Storage Room across from Boiler Room	N/A	Cement Floor		Non Suspect ACM	200	SF	0					N/A	N/A	N/A
	Storage Room across from Boiler Room	N/A	Concrete Block Wall		Non Suspect ACM	500	SF	0					N/A	N/A	N/A
	Storage Room across from Boiler Room	N/A	Metal Ceiling Deck		Non Suspect ACM	200	SF	0					N/A	N/A	N/A
1 1	Storage Room across from Boiler Room	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	60	LF	0					N/A	N/A	N/A
1 1	Storage Room across from Boiler Room	N/A	Fiberglass Pipe Fitting Insulation		Non Suspect ACM	15	EA	0					N/A	N/A	N/A
1 1	Boiler Room	N/A	Cement Floor		Non Suspect ACM	1200	SF	0					N/A	N/A	N/A
	Boiler Room Boiler Room	N/A N/A	Concrete Block Wall Concrete Ceiling		Non Suspect ACM Non Suspect ACM	2600 1200	SF SF	0					N/A N/A	N/A N/A	N/A N/A
	Boiler Room	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	400	LF	20	LF				N/A	N/A	N/A
	Boiler Room	N/A	Fiberglass Pipe Fitting Insulation		Non Suspect ACM	32	EA	0					N/A	N/A	N/A
1 1 1	Boiler Room	N/A	Fiberglass Breeching		Non Suspect ACM	500	SF	0					N/A	N/A	N/A
	Boiler Room	М	Vibration Damper Cloth	6090/01/01/AA	Assumed	4	SF	0					1	No	1/D
1 1	Building Engineer's Office adjacent to Boiler Room	N/A	Cement Floor		Non Suspect ACM	200	SF	0					N/A	N/A	N/A
1 1	Building Engineer's Office adjacent to Boiler Room	N/A	Concrete Block Wall		Non Suspect ACM	600	SF SF	0					N/A	N/A	N/A
	Building Engineer's Office adjacent to Boiler Room Mezzanine Level Storage across from Building Engineer's Office	N/A X	Fiberglass Ceiling Tile 2' x 4' X		Non Suspect ACM X	200 X	X	X	¥	Х		<u> </u>	N/A X	N/A X	N/A X
	Large Office adjacent to Boiler Room	N/A	Cement Floor		Non Suspect ACM	200	SF	0	_^	^			N/A	N/A	N/A
1 1	Large Office adjacent to Boiler Room	N/A	Concrete Block Wall		Non Suspect ACM	600	SF.	0					N/A	N/A	N/A
1 1	Large Office adjacent to Boiler Room	N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	200	SF	0					N/A	N/A	N/A
1 1	Hallway near Boiler Room and Offices	N/A	Cement Floor		Non Suspect ACM	400	SF	0	_			1	N/A	N/A	N/A
1 1	Hallway near Boiler Room and Offices Hallway near Boiler Room and Offices	N/A N/A	Concrete Block Wall		Non Suspect ACM Non Suspect ACM	800 400	SF SF	0	-			-	N/A N/A	N/A N/A	N/A N/A
	Storage Room next to TA Room	N/A X	Fiberglass Ceiling Tile 2' x 4' X		Non Suspect ACM X	400 X	X	X	×	×	+	 	N/A X	N/A X	N/A X
1 1	TA Room in Hallway near Cafeteria	x	x		x	x	x	X	x	X		1	X	X	X
1 1	Hallway next to Cafeteria	M	Floor Tile VAT 12" x 12"	6090/01/01/12	Assumed	1200	SF	0		Tan			1	No	1/D
1 1	Hallway next to Cafeteria	N/A	Concrete Block Wall		Non Suspect ACM	2400	SF	0					N/A	N/A	N/A
1 1	Hallway next to Cafeteria	N/A	Ceiling Tile 2' x 4'		NAD	1200	SF	0			Sampled during original inspection Oct. 1991		N/A	N/A	N/A
1111	Custodial Closet 34 next to Lunchroom	l M	Floor Tile VAT 12" x 12"	6090/01/01/12	Assumed	25	SE	1 1	SF	White	What kind of damage? Please fill out additional conditions for Assumed Damaged Materials		1 1	No	6/C
1 1	Custodial Closet 34 next to Eunchroom Custodial Closet 34 next to Lunchroom	N/A	Concrete Block Wall	333331101112	Non Suspect ACM	250	SF	0	J.		Not previously listed		N/A	N/A	N/A
1 1	Custodial Closet 34 next to Lunchroom	N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	25	SF	0			Not previously listed		N/A	N/A	N/A
1 1	Kitchen Storage in Hallway across from Kitchen	N/A	Concrete Block Wall		Non Suspect ACM	850	SF	0					N/A	N/A	N/A
1 1	Kitchen Storage in Hallway across from Kitchen	N/A	Cement Floor		Non Suspect ACM	400	SF	0					N/A	N/A	N/A
1 1	Kitchen Storage in Hallway across from Kitchen	N/A N/A	Fiberglass Ceiling Tile 2' x 4' Concrete Block Wall		Non Suspect ACM	400 1600	SF SF	0	-			1	N/A N/A	N/A N/A	N/A N/A
	Large Cafeteria Storage Area near Loading Dock Large Cafeteria Storage Area near Loading Dock	N/A N/A	Concrete Block Wall Cement Floor		Non Suspect ACM Non Suspect ACM	1600 800	SF	0	-			 	N/A N/A	N/A N/A	N/A N/A
111	Large Cafeteria Storage Area near Loading Dock Large Cafeteria Storage Area near Loading Dock	N/A N/A	Metal Ceiling Deck		Non Suspect ACM	800	SF	0			<u> </u>	1	N/A	N/A	N/A
1 1	Kitchen	N/A	Ceramic Tile Floors		Non Suspect ACM	650	SF	0					N/A	N/A	N/A
1 1	Kitchen	N/A	Concrete Block Wall		Non Suspect ACM	1200	SF	0					N/A	N/A	N/A
1 1	Kitchen	N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	650	SF	0					N/A	N/A	N/A
1 1	Office in Kitchen	M	Floor Tile VAT 12" x 12"	6090/01/01/12	Assumed	70	SF	0	<u> </u>	Orange			1	No	1/D
	Office in Kitchen	N/A	Concrete Block Wall		Non Suspect ACM	150	SF SF	0	-			 	N/A	N/A N/A	N/A N/A
	Office in Kitchen Women's Restroom near Boiler Room	N/A X	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	70 X	X	0 X	Y	Y	+	l	N/A X	N/A X	N/A Y
	Men's Locker Room near Boiler Room	N/A	Concrete Block Wall		Non Suspect ACM	800	SF	0	<u> </u>	_^	1	1	N/A	N/A	N/A
	Men's Locker Room near Boiler Room	N/A	Cement Floor		Non Suspect ACM	450	SF	0					N/A	N/A	N/A

													-	
	School District of Philadelphia			A Three-Year Reinspe						Reinspection Date: 2/8/2016 - 2/9/2016				
	A. Philip Randolph Career and Technical High School		Ro	om by Room Locatior	1 Log Report					Building Inspector: Mary Anne Lerro				
	3101 Henry Avenue		Red= Confirmed (Contact OEMS pri	or to the disturbance of a	ny of the following materials	and report d	damag			Certificate Number:740092				
İ		1	Yellow= Assumed (Contact OEMS for	or assessment and sampli	ng prior to the disturbance of	these mater	rials							
-	Philadelphia, PA 19129	4	and report damage)							Management Planner: Monique Causley				
			Green= Non Asbestos Containing/N Laboratory Analysis has indicated N	on Suspect Material (The	se materials have been sample	led and	c 250							
	ULCS# 6090		not typically known to contain Asbe	stos)	ASBESTOS DETECTED OF UN	ese material	is are			Certificate Number:ACC-0215-8-010				
Ę														
l e F														
m I											A40-			
m I		System			Confirmed Assumed NAD	Amount of	SF LF	Amount of	SF LF Color require	d	Attic Crawlspace Ranking	Damage Potential	Newly	Response
t r	On Site Room Name	System Affected	Material Description	HID#	Non Suspect ACM	Material	EA	Damage	EA for VAT	Comments/Description/Notes	Ranking	(DP)	Friable (NF)) Action (RA)
	Men's Locker Room near Boiler Room	N/A	Ceiling Tile 2' x 4'		NAD	450	SF	0		Sampled during original inspection Oct. 1991		N/A	N/A	N/A
	Classroom 25 Office	N/A	Ceiling Tile 2' x 4'		NAD	200	SF SF	0		Sampled during original inspection Oct. 1991		N/A	N/A	N/A
1 1	Classroom 25 Office Classroom 25 Office	N/A M	Concrete Block Wall Floor Tile VAT 12" x 12"	6090/01/01/12	Non Suspect ACM Assumed	550 200	SF	0	Tan			N/A 1	N/A No	N/A 1/D
1 1	Classroom 25 Classroom 25	N/A	Ceiling Tile 2' x 4'	0090/01/01/12	NAD	800	SF	0	Tall	Sampled during original inspection Oct. 1991		N/A	N/A	N/A
	Classroom 25	N/A	Concrete Block Wall		Non Suspect ACM	1600	SF	0		Campica during original mopeculori doc. 1001		N/A	N/A	N/A
1 1	Classroom 25	M	Floor Tile VAT 12" x 12"	6090/01/01/12	Assumed	800	SF	0	Tan			1	No	1/D
1 1	Rectangular Office bordering Classroom 25	Х	X		Х	Х	Х	Х	X X			Х	Х	X
	Classroom 23	N/A	Ceiling Tile 2' x 4'	1	NAD	800	SF	0		Sampled during original inspection Oct. 1991		N/A	N/A	N/A
	Classroom 23	N/A M	Concrete Block Wall Floor Tile VAT 12" x 12"	6090/01/01/12	Non Suspect ACM	1600 800	SF SF	0	Tan	+		N/A	N/A No	N/A 1/D
1 1	Classroom 23 Classroom 24	N/A	Ceiling Tile 2' x 4'	6090/01/01/12	Assumed NAD		SF	0	ran	Sampled during original inspection Oct. 1991		N/A	No N/A	N/A
	Classroom 24	N/A	Concrete Block Wall	1	Non Suspect ACM	1600	SF	0				N/A	N/A	N/A
	Classroom 24	M	Floor Tile VAT 12" x 12"	6090/01/01/12	Assumed	800	SF	0	Tan			1	No	1/D
1 1		м	FI T'I \/A T 40" 40"			000	0.5	0.5	SE Tan	What kind of damage? Please fill out additional			No	0/0
	Hallway next to Classrooms 25, 23, 22 Hallway next to Classrooms 25, 23, 22	N/A	Floor Tile VAT 12" x 12"	6090/01/01/12	Assumed Non Suspect ACM	800 1600	SF SF	25 0	SF Tan	conditions for Assumed Damaged Materials		N/A	No N/A	6/C N/A
111	Hallway next to Classrooms 25, 23, 22 Hallway next to Classrooms 25, 23, 22	N/A N/A	Concrete Block Wall Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM Non Suspect ACM	800	SF	0				N/A N/A	N/A N/A	N/A N/A
1 1	Storage Closet in Main Hallway Adjacent to Classroom 39	X	X		X	X	X	X	x x			X	X	X
1 1	Classroom 20	X	X		X	X	X	X	X X			X	X	X
1 1	Classroom 22	M	Floor Tile VAT 12" x 12"	6090/01/01/12	Assumed	800	SF	0	Tan			1	No	1/D
1 1	Classroom 22	N/A	Concrete Block Wall		Non Suspect ACM	1600	SF	0				N/A	N/A	N/A
1 1	Classroom 22	N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	800	SF	0		Michigan Commence Com		N/A	N/A	N/A
1 1 1	Classroom 22	м	Sheetrock Wall	6090/01/01/CRI/IH/2100	Assumed	400	SF	10	SE	What kind of damage? Please fill out additional conditions for Assumed Damaged Materials		1 1	No	6/C
									0.	What kind of damage? Please fill out additional			110	
1 1	Classroom 21	M	Floor Tile VAT 12" x 12"	6090/01/01/12	Assumed	800	SF	20	SF Tan	conditions for Assumed Damaged Materials		1	No	6/C
	Classroom 21	N/A	Concrete Block Wall		Non Suspect ACM	1600	SF	0				N/A	N/A	N/A
1 1	Classroom 21 Classroom 21	N/A M	Fiberglass Ceiling Tile 2' x 4'	6090/01/01/CRI/IH/2100	Non Suspect ACM	800 400	SF SF	0				N/A	N/A No	N/A 1/D
1 1	Gas Meter Room in Classroom 21	X	Sheetrock Wall X	6090/01/01/CRI/IH/2100	Assumed X	X X	X	X	x x			X	X	X
	Main Hallway near Visitor Entrance through Classroom 25/23	N/A	Concrete Block Wall		Non Suspect ACM	4800	SF	0	~ ~			N/A	N/A	N/A
	Main Hallway near Visitor Entrance through Classroom 25/23	N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	2800	SF	0				N/A	N/A	N/A
1 1	Main Hallway near Visitor Entrance through Classroom 25/23	M	Floor Tile VAT 12" x 12"	6090/01/01/12	Assumed	2800	SF	0	Tan			1	No	1/D
	Cafeteria	N/A	Concrete Block Wall		Non Suspect ACM	2500	SF	0				N/A	N/A	N/A
1 1	Cafeteria	M N/A	Floor Tile VAT 12" x 12"	6090/01/01/12	Assumed	1800	SF	0	Blue			1	No	1/D N/A
1 1	Cafeteria Cafeteria Storage Room	N/A N/A	Ceiling Tile 2' x 4' Concrete Block Wall		NAD Non Suspect ACM	1800 400	SF SF	0		Sampled during original inspection Oct. 1991		N/A N/A	N/A N/A	N/A N/A
1 1	Cafeteria Storage Room Cafeteria Storage Room	N/A	Concrete Ceiling		Non Suspect ACM	200	SF	0				N/A	N/A	N/A
	Cafeteria Storage Room	N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	200	SF	0				N/A	N/A	N/A
1 1	Storage Near Training Kitchen and Restroom	N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	400	SF	0				N/A	N/A	N/A
1 1	Storage Near Training Kitchen and Restroom	N/A	Cement Floor		Non Suspect ACM	400	SF	0				N/A	N/A	N/A
	Storage Near Training Kitchen and Restroom	N/A	Concrete Block Wall		Non Suspect ACM	800	SF	0				N/A	N/A	N/A
111	Staff Restroom near Training Kitchen	N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	50	SF	0				N/A	N/A	N/A
1 1	Staff Restroom near Training Kitchen Staff Restroom near Training Kitchen	N/A N/A	Cement Floor Concrete Block Wall		Non Suspect ACM Non Suspect ACM	50 200	SF SF	0		1		N/A N/A	N/A N/A	N/A N/A
	Closet adjacent to Restroom near Training Kitchen	X	X		X	X X	X	X	x x			X	X	X
1 1	Office in rear Hallway of Training Kitchen	M	Floor Tile VAT 12" x 12"	6090/01/01/12	Assumed	200	SF	0	White			1	No	1/D
1 1	Office in rear Hallway of Training Kitchen	N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	200	SF	0				N/A	N/A	N/A
1 1	Office in rear Hallway of Training Kitchen	N/A	Concrete Block Wall		Non Suspect ACM	400	SF	0				N/A	N/A	N/A
1 1	Hot Water Room across from Carpentry Workshop	N/A	Plaster Ceiling		NAD NAD	400	SF	0		Sampled NAD March 1991		N/A	N/A	N/A
111	Hot Water Room across from Carpentry Workshop	N/A N/A	Concrete Block Wall		Non Suspect ACM		SF SF	0		+		N/A	N/A N/A	N/A N/A
111	Hot Water Room across from Carpentry Workshop Custodial Closet near Restroom adjacent to Training Kitchen	N/A N/A	Cement Floor Concrete Block Wall	+	Non Suspect ACM Non Suspect ACM	400 400	SF	0		1		N/A N/A	N/A N/A	N/A N/A
	Custodial Closet near Restroom adjacent to Training Ritchen	N/A	Cement Floor		Non Suspect ACM	200	SF	0		<u> </u>		N/A	N/A	N/A
1 1	Custodial Closet near Restroom adjacent to Training Kitchen	N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	200	SF	0				N/A	N/A	N/A
1 1	Custodial Closet near Restroom adjacent to Training Kitchen	N/A	Fiberglass Pipe Insulation		Non Suspect ACM		LF	0				N/A	N/A	N/A
1 1	Custodial Closet near Restroom adjacent to Training Kitchen	N/A	Fiberglass Pipe Fitting Insulation	1	Non Suspect ACM	2	EA	0				N/A	N/A	N/A
1 1	Second from Rear Office adjacent to Training Kitchen and Computer Lab	X	X		X	X	X	X	X X			X	X	X
1 1 1	Closet behind Custodial Closet near Training Kitchen	X N/A	X Concrete Block Wall	+	Non Suggest ACM	150	X SF	X	X X	+		X N/A	N/A	X N/A
1 1	Student Restrooms near Custodial Closet adjacent to Training Kitchen Student Restrooms near Custodial Closet adjacent to Training Kitchen	N/A N/A	Cement Floor		Non Suspect ACM Non Suspect ACM	150 50	SF	0		+		N/A N/A	N/A N/A	N/A N/A
	Student Restrooms near Custodial Closet adjacent to Training Ritchen	N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	50	SF	0				N/A	N/A	N/A
1111	Storage Room adjacent to Restroom neat Training Kitchen	X	X		X	X	X	X	X X			X	X	X
1 1			Floor Tile VAT 12" x 12"	6090/01/01/12	Assumed	200	SF	0	Tan			1	No	1/D
1 1	Storage Room in Rear of Kitchen between Hallways	M		0090/01/01/12					Tull					
1 1 1 1 1	Storage Room in Rear of Kitchen between Hallways	N/A	Concrete Block Wall	0090/01/01/12	Non Suspect ACM	400	SF	0	TGIT			N/A	N/A	N/A
1 1 1 1 1 1	Storage Room in Rear of Kitchen between Hallways Storage Room in Rear of Kitchen between Hallways	N/A N/A	Concrete Block Wall Plaster Ceiling		Non Suspect ACM NAD	400 200	SF SF	0		Sampled NAD March 1991		N/A N/A	N/A N/A	N/A N/A
1 1 1 1 1 1 1 1	Storage Room in Rear of Kitchen between Hallways	N/A	Concrete Block Wall	6090/01/01/12	Non Suspect ACM	400	SF	0	Tan	Sampled NAD March 1991 Sampled NAD March 1991		N/A	N/A	N/A

	Only and District of District database	_	=												
	School District of Philadelphia	-		A Three-Year Reinsp							Reinspection Date: 2/8/2016 - 2/9/2016	-			
	A. Philip Randolph Career and Technical High School	+	1	om by Room Locatio							Building Inspector: Mary Anne Lerro				
	3101 Henry Avenue	-	Red= Confirmed (Contact OEMS pri								Certificate Number:740092	-			
	Philadelphia, PA 19129	4	Yellow= Assumed (Contact OEMS for and report damage)								Management Planner: Monique Causley	-			
	ULCS# 6090		Green= Non Asbestos Containing/N Laboratory Analysis has indicated N not typically known to contain Asbe	O Asbestos present or N stos)	O ASBESTOS DETECTED or the	ese materia	ls are				Certificate Number:ACC-0215-8-010				
E I e F m I e o															
e o		System			Confirmed Assumed NAD	Amount of	SF LF	Amount of	SF LF	Color require	d	Attic Crawlspace	Damage Potential	Newly	Response
t r	On Site Room Name	Affected	Material Description	HID#	Non Suspect ACM				EA	Color require for VAT	Comments/Description/Notes	Crawispace Ranking	(DP)	Friable (NF)) Action (RA)
1 1	Hallway next to Computer Lab and Lockers Storage to Right of Computer Lab	N/A X	Concrete Block Wall		Non Suspect ACM X	1200 X	SF X	0 X	X	×			N/A X	N/A X	N/A X
1 1	Computer Lab	N/A	Concrete Block Wall		Non Suspect ACM	1400	SF	0	^	^			N/A	N/A	N/A
1111	Computer Lab	М	Floor Tile VAT 12" x 12"	6090/01/01/12	Assumed	700	SF	0		White			1	No	1/D
1 1	Computer Lab Classroom 71	N/A N/A	Fiberglass Ceiling Tile 2' x 4' Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	700 500	SF SF	8	SF		Stained Not previously listed		N/A N/A	N/A N/A	N/A N/A
	Classroom 71 Classroom 71	N/A N/A	Concrete Block Wall		Non Suspect ACM Non Suspect ACM	700	SF	0			Not previously listed Not previously listed		N/A N/A	N/A N/A	N/A N/A
1111	Classroom 71	M	Sheetrock Wall	6090/01/01/CRI/IH/2100	Assumed	400	SF	Ö			Not previously listed		1	No	1/D
1 1	Classroom 71	N/A	Ceramic Tile Floors		Non Suspect ACM	500	SF	0			Not previously listed		N/A	N/A	N/A
	Classroom 72 Classroom 72	N/A N/A	Fiberglass Ceiling Tile 2' x 4' Concrete Block Wall		Non Suspect ACM Non Suspect ACM	500 700	SF SF	0			Not previously listed Not previously listed	-	N/A N/A	N/A N/A	N/A N/A
1 1	Classroom 72	M M	Sheetrock Wall	6090/01/01/CRI/IH/2100	Assumed	400	SF	0			Not previously listed	1	1 1	No No	1/D
1 1	Classroom 72	N/A	Ceramic Tile Floors		Non Suspect ACM	500	SF	0			Not previously listed		N/A	N/A	N/A
	Classroom 73	M	Floor Tile VAT 12" x 12"	6090/01/01/12	Assumed	550	SF	0		White		 	1	No	1/D
	Classroom 73 Classroom 73	M N/A	Sheetrock Wall Ceiling Tile 2' x 4'	6090/01/01/CRI/IH/2100	Assumed NAD	1200 550	SF SF	0	-		Sampled during original inspection Oct. 1991	 	N/A	No N/A	1/D N/A
1 1	Classroom 74	М	Floor Tile VAT 12" x 12"	6090/01/01/12	Assumed	550	SF	0		White			1	No	1/D
1 1	Classroom 74	M	Sheetrock Wall	6090/01/01/CRI/IH/2100	Assumed	1200	SF	0					1	No	1/D
1 1	Classroom 74 Classroom 75	N/A M	Ceiling Tile 2' x 4' Floor Tile VAT 12" x 12"	6090/01/01/12	NAD Assumed	550 550	SF SF	0		White	Sampled during original inspection Oct. 1991		N/A	N/A No	N/A 1/D
	Classroom 75	M	Sheetrock Wall	6090/01/01/CRI/IH/2100	Assumed	1200	SF	0		vviille			1	No	1/D
1 1 1	Classroom 75	N/A	Ceiling Tile 2' x 4'		NAD	550	SF	0			Sampled during original inspection Oct. 1991		N/A	N/A	N/A
1 1	Fire Academy Large Meeting Room	M	Floor Tile VAT 12" x 12"	6090/01/01/12	Assumed	500	SF	0		White			1	No	1/D
	Fire Academy Large Meeting Room Fire Academy Large Meeting Room	N/A N/A	Concrete Block Wall Ceiling Tile 2' x 4'		Non Suspect ACM NAD	1200 500	SF SF	0			Sampled during original inspection Oct. 1991		N/A N/A	N/A N/A	N/A N/A
1 1	Fire Academy Computer Lab	N/A	Plaster Ceiling		NAD	800	SF	0			Sampled NAD March 1991		N/A	N/A	N/A
1 1	Fire Academy Computer Lab	M	Floor Tile VAT 12" x 12"	6090/01/01/12	Assumed	800	SF	0		White			1	No	1/D
	Fire Academy Computer Lab	N/A N/A	Concrete Block Wall		Non Suspect ACM	1600	SF SF	0					N/A	N/A N/A	N/A N/A
	Girl's Restroom in Fire Academy Girl's Restroom in Fire Academy	N/A N/A	Cement Floor Concrete Block Wall		Non Suspect ACM Non Suspect ACM	300 600	SF	0					N/A N/A	N/A	N/A
1 1	Girl's Restroom in Fire Academy	N/A	Ceiling Tile 2' x 4'		NAD	300	SF	0			Sampled during original inspection Oct. 1991		N/A	N/A	N/A
1 1	Boy's Restroom in Fire Academy	N/A	Cement Floor		Non Suspect ACM	300	SF	0					N/A	N/A	N/A
1 1	Boy's Restroom in Fire Academy Boy's Restroom in Fire Academy	N/A N/A	Concrete Block Wall Ceiling Tile 2' x 4'		Non Suspect ACM NAD	300	SF SF	0			Sampled during original inspection Oct. 1991		N/A N/A	N/A N/A	N/A N/A
1 1	Office in Fire Academy	N/A	Concrete Block Wall		Non Suspect ACM	1600	SF	0			Campion during original inopeditori Cot. 1001		N/A	N/A	N/A
	Office in Fire Academy	M	Floor Tile VAT 12" x 12"	6090/01/01/12	Assumed	800	SF	0		White			1	No	1/D
1 1	Office in Fire Academy Storage Room in Fire Academy	N/A X	Ceiling Tile 2' x 4'		NAD X	800 X	SF X	4 X	SF X	×	Sampled during original inspection Oct. 1991		N/A X	N/A X	N/A X
1 1	Classroom 78	M	Floor Tile VAT 12" x 12"	6090/01/01/12	Assumed	300	SF	0	_^	White			1	No	1/D
1 1	Classroom 78	N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	660	SF	0					N/A	N/A	N/A
1 1	Classroom 78 Staff Restroom near Classroom 78	N/A N/A	Concrete Block Wall Cement Floor		Non Suspect ACM	300 100	SF SF	0					N/A N/A	N/A N/A	N/A N/A
	Staff Restroom near Classroom 78	N/A N/A	Concrete Block Wall		Non Suspect ACM Non Suspect ACM	300	SF	0					N/A	N/A	N/A
1 1 1	Staff Restroom near Classroom 78	N/A	Ceiling Tile 2' x 4'		NAD	100	SF	0			Sampled during original inspection Oct. 1991		N/A	N/A	N/A
1 1	Classroom 79	N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	400	SF	0			Not previously listed		N/A	N/A	N/A
1 1	Classroom 79	М	Sheetrock Wall	6090/01/01/CRI/IH/2100	Assumed	900	SF	2	SF		What kind of damage? Please fill out additional conditions for Assumed Damaged Materials		1	No	6/C
1 1	Classroom 79	M	Floor Tile VAT 12" x 12"	6090/01/01/12	Assumed	400	SF	0		White			1	No	1/D
	Hallway near Fire Academy and Carpentry Workshop Hallway near Fire Academy and Carpentry Workshop	N/A N/A	Fiberglass Ceiling Tile 2' x 4' Concrete Block Wall		Non Suspect ACM Non Suspect ACM	2400 4800	SF SF	0		1		-	N/A N/A	N/A N/A	N/A N/A
	Hallway near Fire Academy and Carpentry Workshop	M M	Floor Tile VAT 12" x 12"	6090/01/01/12	Assumed	2400	SF	0		Tan			1 1	No	1/D
1 1	Dean's Office next to Classroom 57	M	Sheetrock Wall	6090/01/01/CRI/IH/2100	Assumed	500	SF	0					1	No	1/D
	Dean's Office next to Classroom 57	N/A M	Fiberglass Ceiling Tile 2' x 4'	0000/04/04/40	Non Suspect ACM	250	SF SF	0		Ton			N/A	N/A	N/A
1 1	Dean's Office next to Classroom 57 Classroom 57	M	Floor Tile VAT 12" x 12" Floor Tile VAT 12" x 12"	6090/01/01/12 6090/01/01/12	Assumed Assumed	250 600	SF	0		Tan Orange		 	1	No No	1/D 1/D
1 1	Classroom 57	M	Sheetrock Wall	6090/01/01/CRI/IH/2100	Assumed	1200	SF	Ö		Grange			1	No	1/D
1 1	Classroom 57	N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	600	SF	0					N/A	N/A	N/A
1 1	Custodial Closet in hallway outside Carpenter Workshop Custodial Closet in hallway outside Carpenter Workshop	N/A N/A	Cement Floor Concrete Block Wall		Non Suspect ACM Non Suspect ACM	25 200	SF SF	0				-	N/A N/A	N/A N/A	N/A N/A
	Custodial Closet in hallway outside Carpenter Workshop Custodial Closet in hallway outside Carpenter Workshop	N/A N/A	Concrete Block Wall Concrete Ceiling		Non Suspect ACM Non Suspect ACM	25	SF	0				-	N/A N/A	N/A N/A	N/A N/A
1 1	Custodial Closet in hallway outside Carpenter Workshop	N/A	Fiberglass Pipe Fitting Insulation		Non Suspect ACM	3	EA	0					N/A	N/A	N/A
1 1	Custodial Closet in hallway outside Carpenter Workshop	N/A	Fiberglass Pipe Insulation	0000/01/01/01	Non Suspect ACM	8	LF	0					N/A	N/A	N/A
	Office 79 Office 79	M M	Floor Tile VAT 12" x 12" Sheetrock Wall	6090/01/01/12 6090/01/01/CRI/IH/2100	Assumed Assumed	400 800	SF SF	0		Grey		 	1 1	No No	1/D 1/D
1 1	Office 79	N/A	Fiberglass Ceiling Tile 2' x 4'	22000 110 1101 112 100	Non Suspect ACM	400	SF	0					N/A	N/A	N/A
1 1	Office 83	Х	Х		X	X	Х	Х	Х	Х			X	Х	X
1 1	Classroom 82	м	Floor Tile VAT 12" x 12"	6090/01/01/12	Assumed	450	SF	5	SF	Tan	What kind of damage? Please fill out additional conditions for Assumed Damaged Materials	1	1	No	6/C
	Classroom 82	N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	800	SF	0					N/A	N/A	N/A
						_			_						

	Cahaal District of Dhiladalahia		ALIED	• 											
-	School District of Philadelphia	-		A Three-Year Reinsp							einspection Date: 2/8/2016 - 2/9/2016				
-	A. Philip Randolph Career and Technical High School	+	Room by Room Location Log Report Red= Confirmed (Contact OEMS prior to the disturbance of any of the following materials and report damage)							_	uilding Inspector: Mary Anne Lerro				
	3101 Henry Avenue	4	Yellow= Assumed (Contact OEMS for assessment and sampling prior to the disturbance of these materials						C	ertificate Number:740092					
	Philadelphia, PA 19129	1	and report damage)		3,					M	anagement Planner: Monique Causley				
	ULCS# 6090		Green= Non Asbestos Containing/Ni Laboratory Analysis has indicated Ni not typically known to contain Asbes	on Suspect Material (The O Asbestos present or No stos)	ese materials have been sampl O ASBESTOS DETECTED or the	ed and ese materia	ls are			c	ertificate Number:ACC-0215-8-010				
E I e F m I e o												Attic	Damaga		
n o	On Site Room Name	System Affected	Material Description	HID#	Confirmed Assumed NAD Non Suspect ACM	Amount of Material	SF LF	Amount of Damage	SF LF EA	Color required for VAT	Comments/Description/Notes	Crawispace Ranking	Damage Potential (DP)	Newly Friable (NF)	Response Action (RA)
1 1	Classroom 82	N/A	Concrete Block Wall		Non Suspect ACM	450	SF	0		10. 17.11	Commona 2 compacta volco	runnung	N/A	N/A	N/A
	Main Carpentry Workshop	N/A	Cement Floor		Non Suspect ACM	4000	SF	0					N/A	N/A	N/A
1 1	Main Carpentry Workshop	N/A	Concrete Block Wall		Non Suspect ACM	8000	SF	0					N/A	N/A	N/A
1 1	Main Carpentry Workshop Main Carpentry Workshop	N/A N/A	Metal Ceiling Deck Fiberglass Pipe Insulation		Non Suspect ACM Non Suspect ACM	4000 400	SF	0					N/A N/A	N/A N/A	N/A N/A
	Main Carpentry Workshop Main Carpentry Workshop	N/A	Fiberglass Pipe Insulation Fiberglass Pipe Fitting Insulation		Non Suspect ACM	45	EA	0					N/A	N/A	N/A N/A
	Large Storage in Corner of Carpenter Workshop with Shower	N/A	Carpet		Non Suspect ACM	250	SF	0					N/A	N/A	N/A
	Large Storage in Corner of Carpenter Workshop with Shower	N/A	Plaster Ceiling		NAD	250	SF	0		s	ampled NAD March 1991		N/A	N/A	N/A
	Large Storage in Corner of Carpenter Workshop with Shower	N/A	Concrete Block Wall		Non Suspect ACM	450	SF	0			•		N/A	N/A	N/A
	Large Storage in Corner of Carpenter Workshop with Shower	N/A	Ceramic Tile Walls		Non Suspect ACM	400	SF	0					N/A	N/A	N/A
	Large Storage in Corner of Carpenter Workshop with Shower	N/A	Ceramic Tile Floors		Non Suspect ACM	200	SF	0					N/A	N/A	N/A
	Conference Room in Carpenter Workshop	N/A	Carpet		Non Suspect ACM	400	SF	0					N/A	N/A	N/A
	Conference Room in Carpenter Workshop Conference Room in Carpenter Workshop	N/A N/A	Concrete Block Wall Ceiling Tile 2' x 4'		Non Suspect ACM NAD	800 400	SF SF	0		e	ampled during original inspection Oct. 1991		N/A N/A	N/A N/A	N/A N/A
1 1	Carpentry Locker Area	M M	Floor Tile VAT 12" x 12"	6090/01/01/12	Assumed	400	SF	0		Tan	ampled during original inspection Oct. 1991		N/A	No No	1/D
1 1	Carpentry Locker Area	N/A	Fiberglass Ceiling Tile 2' x 4'	0030/01/01/12	Non Suspect ACM	400	SF	0		Tall			N/A	N/A	N/A
1 1	Carpentry Locker Area	M	Linoleum	6090/01/01/CRI/IH/2200	Assumed	250	SF	0					1	No	1/D
	Carpentry Locker Area	N/A	Concrete Block Wall		Non Suspect ACM	850	SF	0					N/A	N/A	N/A
	Nail Storage Room in Carpentry Workshop	N/A	Cement Floor		Non Suspect ACM	250	SF	0					N/A	N/A	N/A
	Nail Storage Room in Carpentry Workshop	N/A N/A	Concrete Block Wall		Non Suspect ACM	450	SF SF	0					N/A	N/A N/A	N/A N/A
	Nail Storage Room in Carpentry Workshop Plumbing Storage Room in Carpentry Workshop	N/A N/A	Concrete Ceiling Cement Floor		Non Suspect ACM Non Suspect ACM	250 250	SF	0					N/A N/A	N/A N/A	N/A N/A
	Plumbing Storage Room in Carpentry Workshop	N/A	Concrete Block Wall		Non Suspect ACM	450	SF	0					N/A	N/A N/A	N/A
	Plumbing Storage Room in Carpentry Workshop	N/A	Concrete Ceiling		Non Suspect ACM	250	SF	0					N/A	N/A	N/A
1 1	Electrical Storage Room in Carpentry Workshop	N/A	Cement Floor		Non Suspect ACM	250	SF	0					N/A	N/A	N/A
	Electrical Storage Room in Carpentry Workshop	N/A	Concrete Block Wall		Non Suspect ACM	450	SF	0					N/A	N/A	N/A
	Electrical Storage Room in Carpentry Workshop	N/A	Concrete Ceiling		Non Suspect ACM	250	SF	0					N/A	N/A	N/A
	Carpentry Tool Room	N/A	Cement Floor		Non Suspect ACM	500	SF SF	0					N/A	N/A	N/A
	Carpentry Tool Room Carpentry Tool Room	N/A N/A	Concrete Block Wall Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM Non Suspect ACM	1000 500	SF	0					N/A N/A	N/A N/A	N/A N/A
	Closet in Carpentry Tool Room	X	X		X X	X	X	X	X	X			X	X	X
	Restrooms in Carpentry Workshop	N/A	Cement Floor		Non Suspect ACM	350	SF	0		^			N/A	N/A	N/A
1 1	Restrooms in Carpentry Workshop	N/A	Ceiling Tile 2' x 4'		NAD	350	SF	0		S	ampled during original inspection Oct. 1991		N/A	N/A	N/A
	Restrooms in Carpentry Workshop	N/A	Concrete Block Wall		Non Suspect ACM	650	SF	0					N/A	N/A	N/A
	Hard Hat Storage Room under stair to Mezzanine Classrooms	N/A	Cement Floor		Non Suspect ACM	450	SF	0					N/A	N/A	N/A
	Hard Hat Storage Room under stair to Mezzanine Classrooms Hard Hat Storage Room under stair to Mezzanine Classrooms	N/A N/A	Concrete Ceiling Fiberglass Pipe Fitting Insulation		Non Suspect ACM Non Suspect ACM	450 20	SF EA	0	-				N/A N/A	N/A N/A	N/A N/A
	Hard Hat Storage Room under stair to Mezzanine Classrooms Hard Hat Storage Room under stair to Mezzanine Classrooms	N/A N/A	Fiberglass Pipe Fitting Insulation Fiberglass Pipe Insulation		Non Suspect ACM Non Suspect ACM	40	LF	0					N/A N/A	N/A N/A	N/A N/A
	Hard Hat Storage Room under stair to Mezzanine Classrooms	N/A	Concrete Block Wall		Non Suspect ACM	800	SF	0					N/A	N/A	N/A
	Fire Academy Workshop Area	N/A	Cement Floor		Non Suspect ACM	1400	SF	0					N/A	N/A	N/A
1 1	Fire Academy Workshop Area	N/A	Concrete Block Wall		Non Suspect ACM	3200	SF	0					N/A	N/A	N/A
1 1	Fire Academy Workshop Area	N/A	Metal Ceiling Deck		Non Suspect ACM	1400	SF	0					N/A	N/A	N/A
	Computer Classroom on Mezzanine in Carpentry Workshop Area	N/A	Carpet		Non Suspect ACM	400	SF	0					N/A	N/A	N/A
	Computer Classroom on Mezzanine in Carpentry Workshop Area Computer Classroom on Mezzanine in Carpentry Workshop Area	M N/A	Sheetrock Wall	6090/01/01/CRI/IH/2100	Assumed Non Suspect ACM	800 400	SF SF	0		1			1 N/A	No N/A	1/D N/A
	Computer Classroom on Mezzanine in Carpentry Workshop Area Desk Classroom on Mezzanine in Carpentry Workshop Area	N/A N/A	Fiberglass Ceiling Tile 2' x 4' Concrete Block Wall		Non Suspect ACM Non Suspect ACM	800	SF	0	-	 			N/A N/A	N/A N/A	N/A N/A
	Z Desk Classroom on Mezzanine in Carpentry Workshop Area	N/A	Metal Ceiling Deck		Non Suspect ACM	400	SF	0					N/A	N/A	N/A N/A
	Z Desk Classroom on Mezzanine in Carpentry Workshop Area	N/A	Cement Floor		Non Suspect ACM	400	SF	0					N/A	N/A	N/A
							T			. F	berglass; Plastic/PVC Caps (Non ACM)/Wire	_			
	Attic-Mezzanine	X	X	X	X	I X	X	X	X		athe/Ltd. Planking	A	X	X	X
_ 1 C	Crawlspace in Auto Shop	X	X	X	X	X	Х	Х	X	X S	ealed/No Access/Dirt Floor	D	Х	X	X

,	
Section III	Certificates
	A. Management Planner/Building Inspector Certificates
	A. Management Planner/Building Inspector Certificates
	A. Management Planner/Building Inspector Certificates
	A. Management Planner/Building Inspector Certificates
	A. Management Planner/Building Inspector Certificates
	A. Management Planner/Building Inspector Certificates
	A. Management Planner/Building Inspector Certificates
	A. Management Planner/Building Inspector Certificates
	A. Management Planner/Building Inspector Certificates
	A. Management Planner/Building Inspector Certificates
	A. Management Planner/Building Inspector Certificates
	A. Management Planner/Building Inspector Certificates
	A. Management Planner/Building Inspector Certificates
	A. Management Planner/Building Inspector Certificates
	A. Management Planner/Building Inspector Certificates
	A. Management Planner/Building Inspector Certificates

Section III - A

Management Planner/Building Inspector Certificates

These charts indicate the Name, Course Date, Expiration Date and Corresponding Certificate Number of the Management Planner and Building Inspector of individuals that participated in the AHERA 3 Year Inspection and Management Plan process of 2015/2016.

Management Planner	Date Granted	Expiration Date	Certificate Number
Monique Causley	2/15/2015	2/16/2016	ACC-0215-8-010
Monique Causley	2/16/2016	2/17/2017	ACC-0216-8-001
Megan Vala	5/22/2015	6/22/2016	740728
Mary Anne Lerro	4/5/2016	4/5/2017	742327

Building Inspector	Date Granted	Expiration Date	Certificate Number
Scott Magee	8/15/2015	8/15/2016	70016699C
William Garrity	8/15/2015	8/15/2016	70016699A
Bernard Brunner	10/2/2015	8/2/2016	45397
Mary Anne Lerro	3/3/2015	3/3/2016	740092
Mary Anne Lerro	4/5/2016	4/5/2017	742322
James Madden	12/11/2014	12/11/2015	ACC-1214-6-010
James Madden	12/3/2015	12/3/2016	ACC-1215-6-018
Troy Ray	3/15/2015	3/19/2016	ACC-0355-6-011
Ananth Vinjamuri	9/29/2015	9/29/2016	374
Shelton Williams	9/29/2015	9/29/2016	375
Paul Davis	2/12/2015	2/12/2016	ACC-0215-6-015
Paul Davis	2/2/2016	2/2/2017	741836
Bernard Bryson	2/16/2015	2/16/2016	ACC-0125-6-031
Bernard Bryson	2/15/2016	2/15/2017	ACC-0216-6-005
Alexander Roman	9/18/2015	9/18/2016	EHSBIR-150619-008
Norm Harrison	9/2/2015	9/2/2016	ACC-0915-6-011
Kelly Mayberry	2/20/2015	2/20/2016	EHSBIR-150220-005
Kelly Mayberry	2/18/2016	2/18/2017	EHSBIR-160218-006
Andrew Hine	5/6/2015	5/6/2016	AI05042015-3
Maryellen Leotta	2/12/2015	2/12/2016	ACC-0215-6-024

awarded to

Monique Causley for successfully completing the prescribed course of study in

Pennsylvania Asbestos Management Planner Refresher Course

under TSCA Title II

presented by

ACCESS TRAINING SERVICES, INC. 7921 River Road, Pennsauken, NJ 08110

(856) 665-3449

Course Date 2/16/15

Exam Date

ACC-0215-8-010 Certificate Number

Social Security Number

Not Provided

Training Director Mark K. Schläger

awarded to

Monique Causley

for successfully completing the prescribed course of study in

Pennsylvania Asbestos Management Planner Refresher Course

under TSCA Title II

presented by

ACCESS TRAINING SERVICES, INC. 7921 River Road, Pennsauken, NJ 08110 (856) 665-3449

2/15/16 Course Date

Exam Date

2/15/17

Expiration

Not Provided

Social Security Number

ACC-0216-8-001
Certificate Number

Mark K. Schläger Training Director

Certificate of Iraining

CRITERION LABORATORIES, INC. HEREBY CERTIFIES THAT

Megan Vala

HAS SUCCESSFULLY COMPLETED A 16 HOUR COURSE ENTITLED

<u>Asbestos Management Planner Initial</u>

INCLUDING CLASSROOM INSTRUCTION

05/21/2015 to 05/22/2015

Exam passed on this 22nd day of May 2015 - Score - 94

Approved for AHERA Accreditation Under TSCA Title II

3370 Progress Drive, Suite J Bensalem, PA 19020 (215) 244-1300 - Phone (215) 244-4349 - Fax www.criterionlabs.com

Course is conducted in English

DIRECTOR:

grash-

James A. Weltz, CIH, President

Certificate of Iraining

CRITERION LABORATORIES, INC. HEREBY CERTIFIES THAT

Mary Anne Lerro

HAS SUCCESSFULLY COMPLETED A 4 HOUR COURSE ENTITLED

Asbestos Management Planner Refresher

INCLUDING CLASSROOM INSTRUCTION on this 5th day of April 2016

Approved for AHERA Accreditation Under TSCA Title II

3370 Progress Drive, Suite J Bensalem, PA 19020

(215) 244-1300 - Phone (215) 244-4349 - Fax

www.criterionlabs.com

Course is conducted in English

DIRECTOR:

8-Cuely

James A. Weltz, CIH, President

EMSL ANALYTICAL, INC.

Certifies that

Scott Magee

has successfully completed the course of study for the

Asbestos Building Inspector Refresher Course

for Accreditation under TSCA Title II

EMSL Certificate No. 70016699C

Approved by:
PA Dept. of Labor and Industry
Accreditation # 137

Course Date: 8/15/2015 Granted: 8/15/2015 Expiration Date: 8/15/2016

Sponsored by:

EMSL Analytical, Inc. 200 Route 130 North Cinnaminson, NJ 08077 Phone: (800) 220-3675 Fax: (856) 786-5973

www.emsl.com



Michael P. Menz, CIH Training Director

made Com

Environmental, Mold. Bacteria, IAQ, Asbestos, Lead, Forensic and Materials Testing Since 1981

EMSL ANALYTICAL, INC.

Certifies that

William Garrity

has successfully completed the course of study for the

Asbestos Building Inspector Refresher Course

for Accreditation under TSCA Title II

EMSL Certificate No. 70016699A

PA Dept. of Labor and Industry Accreditation # 137 Approved by:

Course Date: 8/15/2015 Granted: 8/15/2015 Expiration Date: 8/15/2016

Sponsored by:

EMSL Analytical, Inc. 200 Route 130 North Cinnaminson, NJ 08077 Phone: (800) 220-3675 Fax: (856) 786-5973

www.cmsl.com

TSINE OF THE PROPERTY OF THE P

Michael P. Menz, CIH
Training Director

Environmental, Mold, Bacteria, IAQ, Asbestos, Lead, Forensic and Materials Testing Since 1981

45397

National Asbestos & Environmental Training Institute CERTIFICATE OF COMPLETION

AHERA/EPA Accredited Per 40 CFR Part 763
Asbestos Accreditation under TSCA Title II

This is to certify that .

Bernard Brunner, Jr.

Successfully completed the course entitled

1/2-Day New York State/EPA/AHERA Asbestos Building Inspector Annual Refresher on October 2, 2015

Examination Passed October 2, 2015

Expiration Date on October 2, 2016

President, NAETI

Per I0 NYCRR Part 73.2 (L) (I), DOH 2832 Certificate of Completion of Asbestos Safety Training is the only official record of training for N.Y.S. students.

Language: English

ABIH 1/2 CM POINT

3321 Doris Avenue, Building B, Ocean, NJ 07712

Phone (732) 531-5571

Fax (732) 531-5956

/ww.naeti.com

Certificate of Iraining

CRITERION LABORATORIES, INC.

HEREBY CERTIFIES THAT

Mary Anne Lerro

HAS SUCCESSFULLY COMPLETED A 4 HOUR COURSE ENTITLED **Asbestos Building Inspector Refresher**

on this 3rd day of March 2015

Exam passed on this 3rd day of March 2015 - Score - 84

Approved for AHERA Accreditation Under TSCA Title II

3370 Progress Drive, Suite J Bensalem, PA 19020

(215) 244-1300 - Phone

www.criterionlabs.com

Course is conducted in English

クークスイヤー

James A. Weltz, CIH, President

Certificate of Iraining

CRITERION LABORATORIES, INC. HEREBY CERTIFIES THAT

Mary Anne Lerro

HAS SUCCESSFULLY COMPLETED A 4 HOUR COURSE ENTITLED

Asbestos Building Inspector Refresher

INCLUDING CLASSROOM INSTRUCTION on this 5th day of April 2016

Exam passed on this 5th day of April 2016 - Score - 88

Approved for AHERA Accreditation Under TSCA Title II

3370 Progress Drive, Suite J Bensalem, PA 19020

(215) 244-1300 - Phone (215) 244-4349 - Fax www.criterionlabs.com

Course is conducted in English

DIRECTOR:

grand

James A. Weltz, CIH, President

James Madden

for successfully completing the prescribed course of study in

Building Inspector Refresher Course Pennsylvania Asbestos under TSCA Title II

: :

Presented by ACCESS TRAINING SERVICES, INC. 7921 River Road, Pennsauken, NJ 08110 (856) 665-3449

12/11/14

Course Date

Not Provided

Social Security Number

N/A Exam Date

ACC-1214-6-010

Certificate Number

12/11/15

Expiration Date

Mark K. Schläger Training Director

James Madden

for successfully completing the prescribed course of study in

Building Inspector Refresher Course Pennsylvania Asbestos

under TSCA Title II

presented by
ACCESS TRAINING SERVICES, INC.
7921 River Road, Pennsauken, NJ 08110
(856) 665-3449

Social Security Number Not Provided Course Date 12/3/15 Certificate Number ACC-1215-6-018 Exam Date Mark K. Schläger 146 Expiration Date 12/3/16

Training Directo.

$\mathbf{Troy}\,\mathbf{A}.\,\mathbf{Ray}$ for successfully completing the prescribed course of study in

Building Inspector Refresher Course Pennsylvania Asbestos under TSCA Title II

presented by

ACCESS TRAINING SERVICES, INC. 7921 River Road, Pennsauken, NJ 08110 (856) 665-3449

/ Mark K. Schläger	Certificate Number	Social Security Lyumber
May of the May	ACC-0355-6-011	Not Provided
Expiration Date	Exam Date	Course Date
3/19/16	N/A	3/19/15

G&C Environmental Services, Inc. (#294)
2 Street Road, Newtown Square, Pennsylvania 19073
Telephone: (610) 993-9202 Facsimile: (610) 993-9232

Email: Training@gcenviro.com www.GCenviro.com

This document certifies that Ananth K. Vinjamuri has successfully completed this

State of New York Department of Health Approved AHERA BUILDING INSPECTOR

REFRESHER COURSE, completed as required for asbestos accreditation under the Toxic

Substances Control Act, Title II. This course was held from 09/29/2015 to 09/29/2015.

successful completion of the examination 09/29/2016. The examination date was $\frac{09/29/2015}{MM$ DD YR

The official record of successful training completion is the New York State Department of Health certificate of asbestos safety training completion (DPH 2832).

•

Hail M. Conner

Gail M. Conner
Training Director

G&C Environmental Services, Inc. (#294) 2 Street Road, Newtown Square, Pennsylvania 19073

Telephone: (610) 993-9202 Facsimile: (610) 993-9232

Email: Training@gcenviro.com

www.GCenviro.com

State of New York Department of Health Approved AHERA BUILDIN	This document certifies that
t of Health Approved <u>AF</u>	Shelton Williams has successf
IERA BUILDING INSPECTOR	_ has successfully completed th

REFRESHER COURSE, completed as required for asbestos accreditation under the Toxic

successful completion of the examination 09/29/2016. Substances Control Act, Title II. This course was held from $\frac{09/29/2015}{MM$ DD YR MM DD YR The examination date was $\frac{09/29/2015}{MM}$. This certificate expires one year from the date of

The official record of successful training completion is the New York State Department of Health certificate of asbestos safety training completion (DPH 2832).

Hail M. Conner

Gail M. Conner
Training Director

Paul M. Davis

for successfully completing the prescribed course of study in

Building Inspector Refresher Course Pennsylvania Asbestos

under TSCA Title II

ACCESS TRAINING SERVICES, INC. presented by

7921 River Road, Pennsauken, NJ 08110 (856) 665-3449

Course Date 2/12/15

Exam Date

Social Security Number Not Provided

Expiration Date

THE OF THE PARTY O

Mark K. Schläger

Certificate Number ACC-0215-6-015

Training Director

Number 741836

02/02/2017 Expiration Date

Certificate of Ironne

CRITERION LABORATORIES, INC. HEREBY CERTIFIES THAT

Paul M. Davis

HAS SUCCESSFULLY COMPLETED A 4 HOUR COURSE ENTITLED Asbestos Building Inspector Refresher

NCLUDING CLASSROOM INSTRUCTION

on this 2nd day of February 2016

ed on this 2nd day of Echruary 2016 - Score - 92

itation Under TSCA Title II

3370 Progress Drive, Suite J Bensalem, PA 19020

(215) 244-1300 - Phone (215) 244-4349 - Fax

Course is conducted in English

DIRECTOR:

James A. Weltz, CIH, Presiden

Bernard J. Bryson

for successfully completing the prescribed course of study in

Building Inspector Refresher Course Pennsylvania Asbestos

under TSCA Title II

presented by
ACCESS TRAINING SERVICES, INC.
7921 River Road, Pennsauken, NJ 08110
(856) 665-3449

Social Security Number Not Provided Course Date Certificate Number ACC-0125-6-031 Exam Date Mark K. Schläger Training Director Expiration Date

Bernard J. Bryson

for successfully completing the prescribed course of study in

Building Inspector Refresher Course Pennsylvania Asbestos under TSCA Title II

presented by

ACCESS TRAINING SERVICES, INC. 7921 River Road, Pennsauken, NJ 08110 (856) 665-3449

Exam Date

Exam Date

Expiration Date

ACC-0216-6-005


Certificate Number

Mark K. Schläger

Training Director

Not Provided
Social Security Number

Course Date



Norman Harrison

for successfully completing the prescribed course of study in

Building Inspector Refresher Course Pennsylvania Asbestos

under TSCA Title II

presented by ACCESS TRAINING SERVICES, INC. 7921 River Road, Pennsauken, NJ 08109 (856) 665-3449

Social Security Number	Not Provided	Course Date	9/2/15
Certificate Number	ACC-0915-6-011	Exam Date	N/A
Mark K. Schlager Training Director		Expiration Date	9/2/16

EHS TRAINING INSTITUTE, INC. A Division of BATTA, Inc.

Certificate of Completion

AHERA Building Inspector

(Refresher)

Awarded To:

Kelly Mayberry

SS#:XXX-XX-1551

Who has completed this 4-hour course and examination, EPA Approved under TSCA Title II

AHERA / ASHARA Rule

EHS TRAINING INSTITUTE, INC.

A Division of BATTA, Inc. Delaware Industrial Park • 6 Garfield Way Newark DE 19713-5817

Newark, DE 19713-5817

(302) 737-3376 • Fax (302) 737-5764

Course Date: February 20, 2015

Date of Expiration: February 20, 2016

Certification Number: EHSBIR 150220-005

Todd K. Zeisloft, Instructor

Neeraj K. Batta, President



AHERA Building Inspector Certificate of Completion

Awarded To:

(Refresher)

Kelly Mayberry

SS#:XXX-XX-1551

Who has completed this 4-hour course and examination, EPA Approved under TSCA Title II
AHERA / ASHARA Rule
40 CFR Part 763.

EHS TRAINING INSTITUTE, INC.

A Division of BATTA, Inc.

Delaware Industrial Park • 6 Garfield Way

Newark, DE 19713-5817 (302) 737-3376 • Fax (302) 737-5764

Course Date: February 18, 2016

Date of Expiration: **February 18, 2017**Certification Number: **EHSBIR 160218-006**

Todd K. Zeisloft, Instructo

Neeraj K. Batta, President

AEROSOL MONITORING & ANALYSIS, INC.

This is to certify that

ANDREW HINE

has met the attendance requirements and successfully completed the course entitled

3-DAY EPA AHERA INSPECTOR

For Accreditation Under TSCA Title II

Certification No.	AI05042015-3	Course Date	05/04/2015 to 05/06/2015
		Đ	05/06/2015 5/6/2016
9	E. Rush Barnett	Principal Instructor	STEVE SIERAGKI
	E. Rad Bankt		for & twhi-

1331 Ashton Road

P.O.Box 646

www.amatraining.com Hanover, MD 21076

P: 410-684-3327

F: 410-684-3724

Maryellen Leotta

for successfully completing the prescribed course of study in

Building Inspector Refresher Course Pennsylvania Asbestos

under TSCA Title II

presented by ACCESS TRAINING SERVICES, INC. 7921 River Road, Pennsauken, NJ 08110

(856) 665-3449

Course Date

Social Security Number Not Provided


Exam Date

ACC-0215-6-024 Certificate Number

2/12/16

Expiration Dat

Mark K. Schläger Training Director



Asbestos Hazard Emergency Response Act (AHERA) Environmental Compliance Audit Cross Reference Table

In response to the AHERA Environmental Compliance Audit a Cross Reference Table has been prepared for inclusion into the Environmental Management Plan. The purpose of this Cross Reference Table is to link the following documents to the AHERA Management Plan.

Cross Reference Table

3 Year Reinspection Report follows this Cross Reference Table documentation.

Pages 1 - 3			
Pages 4 - 5			
Page 6			
Page 7			
Pages 8 - 19			
Attachment 1 Letter Dated August 4, 2006			
The original records are centralized at the School District's Environment Library. Copies are maintained on staff and are required to be maintained the latest Reinspection Report. 2 hour awareness training records for all Building Engineers, Custodia Assistants and maintenance personnel 40 hour worker/supervisor training records for the OEMS A-Team are various AST tradesmen.			
The original documents are on file at the School District's Environment Library. Copies of the original are mailed to the Schools Main Office for retention with the Management Plan documentation. These documents are typical			

SCHOOL DISTRICT OF PHILADELPHIA

ASBESTOS DESIGNATED PERSON

Gerald F Junod
Office of Capital Programs
Environmental Management & Services
440 N Broad Street, 3rd Floor
Philadelphia, PA 19130
Telephone: 215 400 6738
Fax: 215 400 4751

Drexel University- Asbestos Building Inspector Course
Drexel University- Asbestos Management Planner Course
Criterion Laboratories, Inc. - Asbestos Management Planner Course October 11-12, 2012 16 Hours

Annual Building Inspector Refreshers

1990 to Present

4 Hours
Drexel University
Criterion Laboratories, Inc
Access Training Services, Inc.

Annual Building Management Planner Refreshers

1990 to 1994

4 Hours

Drexel University

Criterion Laboratories, Inc

2013 to Present

4 Hours

Environmental Manager, School District of Philadelphia

Manages the design and implementation of asbestos and lead projects for the Capital Improvement Program and other District Departments including Facilities & Operations and Information Technology. Ensures that asbestos abatement and lead remediation projects are expertly designed and executed in accordance with industry best management practice standards and regulations.

Manager, City of Philadelphia Asbestos Control Program

Served as the Asbestos Control Program Manager for the City of Philadelphia, Department of Public Health, Air Management Services, Asbestos Control Unit from August 1, 2003 through October 23, 2006.

Mid Atlantic Regional Environmental Consortium (MAREC)

Former member with attendance and participation commitments of all quarterly EPA Region III and yearly National Asbestos Regulatory Conferences sponsored by the EPA and the National Conference of State Legislators respectively as a representative for the City of Philadelphia Department of Public Health Air Management Services from 1994 through 2006.

Philadelphia Environmental Task Force

Former member of the Philadelphia Environmental Task force as a representative and point of contact for the City of Philadelphia Department of Public Health Air Management Services Asbestos Control Unit from 2002 through 2006.

Asbestos Instructor

Worked as the primary instructor for the initial and annual Asbestos Project Inspector training and licensing program as mandated by City of Philadelphia Department of Pubic Health Asbestos Control Regulations from August 1994 through October 2006.

Worked as a lead instructor with an Environmental Consulting Firm and approved by the US EPA for the initial and annual refresher training courses for various asbestos occupational disciplines such as the Building Inspector, Management Planner and Worker/Supervisor from 1991 through 1994.

I certify that the general, local agency responsibilities as stipulated in Section 763.84 will be met.

Gerald F. Junod

Asbestos Designated Person Environmental Manager

Office of Environmental Management and Services

SCHOOL DISTRICT OF PHILADELPHIA

Accreditation Information Statement

All persons who inspect for Asbestos Containing Building Materials (ACBM) and who will design or carry our response actions with respect to assumed and confirmed ACBM, will be accredited by an EPA approved course and/or a State Contractors AccreditationProgram under Sections 206 (c) and 206 (b) of Title II of the ACT.

Gerald F. Junod

Asbestos Designated Person Environmental Manager

Office of Environmental Management and Services

SCHOOL DISTRICT OF PHILADELPHIA

OFFICE OF CAPITAL PROGRAMS 440 NORTH BROAD STREET, SUITE 373 PHILADELPHIA, PENNSYLVANIA 19130

OFFICE OF ENVIRONMENTAL MANAGEMENT AND SERVICES

PHONE (215)-400-4750

September 2015

TO:

Principals

Building Administrators/Occupants

Parents/Guardians

FROM:

Fran Burns

Chief Operating Officer

Francine Locke, M.S., Director

Office of Environmental Management and Services

SUBJECT:

Annual EPA Notification Letter

Pursuant to the Federal Environmental Protection Agency (EPA) mandate, as required by 40 C.F.R. 763.84 (c)(d) of public access to environmental records, this letter is to acknowledge the availability of your facility's Asbestos Hazard Emergency Response Act (AHERA) Management Plan.

Each member of the school staff, parents/guardians, temporary workers and/or contractors, are required to receive a copy of the Notification Letter. At the direction of the Principal, a copy is to be posted on the bulletin boards and an appropriate amount of copies are to be generated for distribution.

Note: The AHERA Three-Year Reinspection reports, in colored binders; White with Pink, Tan, Black, Red, Dark Blue, Green, Yellow and White, are Federal EPA mandated inspection documents. The School District of Philadelphia is subject to severe monetary penalties if the reports and associated paperwork are not available to the EPA and the public upon request.

It is incumbent on designated school personnel to gather and retain this data as it is delivered, in one location for future review. Acceptable locations include the Principal's Office or Main Office for the primary data. The Building Engineer should maintain any secondary or duplicate copies.

If you have any questions, please call 215-400-4750. Thank you for your cooperation.

Fran Burns

Chief Operating Officer

Francine Locke, M.S., Director

Office of Environmental Management

and Services

c: Danielle Floyd

AHERA-4 8/21/15



School District of Philadelphia OFFICIAL NOTICE

PLEASE POST

September 2015

TO:

Principals

Building Administrators Building Engineers Building Occupants Parents/Guardians

FROM:

Fran Burns

Chief Operating Officer

Francine Locke, M.S., Director

Office of Environmental Management and Services

SUBJECT:

Annual Notification Letter: Asbestos Hazard Emergency Response Act

The Federal Register published on October 30, 1987, Subpart E, in Schools: Final Rule and Notice, 763.84 (c)(d) states that each local education agency shall ensure that workers and building occupants or guardians are to be informed at least once each school year about inspections, response actions and post-response action activities including re-inspections and periodic surveillance activities. The School District as the Local Education Agency (LEA), retains such reports that are available for public inspection in the Office of the Principal or Building Administrator.

The Principal or Building Administrator is required to do the following with this notification:

1) Post in a Public Place or Main Office

2) Inform Building Occupants

3) Send a copy of this notification to Parents or Guardians

4) Insert a copy into the latest AHERA Three-Year Reinspection report (white/pink binder)

in your office or facility.

Fran Burns

Chief Operating Officer

Francine Locke, M.S., Director

Office of Environmental Management

and Services

c: Danielle Floyd

AHERA-4a 8/21/15

SCHOOL DISTRICT OF PHILADELPHIA

Education Center 440 North Broad Street Philadelphia, Pennsylvania 19130

Office of Environmental Management and Services

215-400-4750

AHERA Six Month Surveillance Outline of Events

- Pursuant to the Federal Environmental Protection Agency (EPA) mandate, as required by 40 CFR 763.92(b), the following procedure is to be implemented. At least once every six (6) months after a Management Plan is in effect, each Local Education Agency (LEA) shall conduct a periodic surveillance in each building that it owns or leases that contains Asbestos Containing Building Materials (ACBM) or is assumed to contain ACBM.
- The first Bi-Annual Inspection starts in the Spring (March, April, May) and again in the Fall (October, November, December) of each year. The Building Engineer/Assistant should assist the Building Inspector with appropriate access to all areas including (Crawlspaces/Attics) and rooms in the facility. There is no action required of the Principal.
- The Building Inspector shall visually inspect all areas that are identified in the Management Plan as ACBM or assumed ACBM. The date of the surveillance is recorded, the inspectors name and any changes in the conditions of the materials.
- The Building Inspector shall make a copy of the inspection document and insert into the front of the latest Management Plan (AHERA Three Year Reinspection report). The original document is returned to the LEA's Environmental Library and filed.

SCHOOL DISTRICT OF PHILADELPHIA

Education Center 440 North Broad Street Philadelphia, Pennsylvania 19130

Office of Environmental Management and Services

215-400-4750

AHERA Three Year Reinspection Outline of Events

- Pursuant to the Federal Environmental Protection Agency (EPA) mandate, as required by 40 CFR 763.85(b) the following procedure is to be implemented. At least once every three (3) years after a Management Plan is in effect, each Local Education Agency (LEA) shall conduct a reinspection of each building that it owns or leases that contains Asbestos Containing Building Material's (ACBM's) or is assumed to contain ACBM.
- Subsequent Three Year Re-inspections (2009, 2012, 2015, etc) shall start in the Fall (October, November, December, January). The Building Engineer/Assistant should assist the Building Inspector with appropriate access to all areas including (Crawlspaces/Attics) and rooms in the facility. There is no action required of the Principal.
- An accredited Building Inspector shall visually inspect and touch to determine friability, all areas that are identified in the Management Plan as ACBM or assumed ACBM. The date of the surveillance is recorded, the inspectors name and any changes in the conditions of the materials. The Building Inspectors state of accreditation and license number is required.
- After the inspection, the Building Inspector shall make a copy of the inspection documents and insert into the front of the latest Management Plan (AHERA Three Year Reinspection report). The original document is returned to the LEA's Environmental Library and filed.
- The Building Inspector shall return the reinspection data to the Management Planner to be assessed and determine appropriate response actions and a report issued (AHERA Three Year Reinspection report). One copy of the report is delivered to the schools Principal to be permanently retained with all previous environmental data. Another copy is retained in the LEA's Environmental Library.



School District of Philadelphia
Office of Environmental Management & Services
440 North Broad Street
Philadelphia, PA 19130
(215) 400-4750

School District of Philadelphia **Asbestos Management Program**

TABLE OF CONTENTS

De	finitionsPage 9
1.	Introduction
	Summary of Asbestos Management Plan Asbestos Management Plan Execution
4.	Summary of Program Execution a. Asbestos Management Plan Execution
5.	Responsibilities a. OEMS b. Asbestos Worker/Supervisor "A-TEAM"
6.	Requirements
7.	AHERA O&M PlanPage 15 a. Controls
8.	O&M Response Actions
	O Deferences and Descriptions Page 1

DEFINITIONS / ACRONYMS

ACM/PACM: Asbestos Containing Material/Potential Asbestos Containing

Material

AHERA: Asbestos Hazard Emergency Response Act

AIR FORM: Asbestos Inspection Report Form

Amended Water: Water to which a surfactant (soap) has been added

AMP: Asbestos Management Program/Asbestos Management Plan

Asbestos Designate Person: Individual assigned by the district to oversee asbestos related

issues.

Asbestos Regulated Area: Location that is posted as an asbestos work area in which only

approved and accredited personnel are permitted to enter

AST: Asbestos Support Team involving approved and accredited

school district tradespersons personnel that are school district

person

A-TEAM: School District of Philadelphia asbestos workers

CIP: Capital Improvement Program

Consultant: Asbestos consulting firm hired by the District

Demolition Directive: Memorandum – August 4, 2006 from Patrick Henwood

EPA: Environmental Protection Agency

In House Personnel: School District of Philadelphia asbestos workers

LEA: Local Education Agency

O&M: Operations and Maintenance

OEMS: Office of Environmental Management and Services

OSHA: Occupational Safety and Health Administration

PEL: Permissible Exposure Limit

PSD or SDP: Philadelphia School District/School District of Philadelphia

PSIT: Philadelphia School Improvement Team

STEL: Short Term Exposure Limit

1. Introduction

The School District of Philadelphia, Asbestos Policy Statement:

"The School District of Philadelphia is dedicated to providing a safe and healthful work environment for its employees, students, faculty, contractors and visitors. In recognition of the potential health problems associated with asbestos, the School District of Philadelphia is committed to a comprehensive asbestos control program. This program is implemented and maintained through the School District of Philadelphia's Office of Environmental Management and Services (OEMS)."

OEMS has the responsibility of establishing procedures for asbestos abatement, asbestos inspection, air monitoring, renovation and demolition activities within all School District of Philadelphia owned or leased facilities.

These procedures are developed to ensure that:

- (1) People are not exposed to significant levels of asbestos fibers
- (2) Asbestos waste is handled and disposed of properly
- (3) Members of the School District of Philadelphia community have access to the Office of Environmental Management and Services for information, assistance, guidance, and interpretation regarding asbestos related matters.
- (4) Members of the School District of Philadelphia community have access to the Asbestos Management Plans as required and outlined in the US EPA AHERA regulations including annual written notification to all parents.
- (5) Compliance with all applicable Federal, State and Local Asbestos Regulations

Requirements outlined in this manual are mandatory in nature where the word "SHALL" is used and are advisory in nature where the word "SHOULD" is used.

2. Summary of Asbestos Management Program

The School District of Philadelphia's Asbestos Management Program was established to meet the requirements of Federal, State, and Local Regulations.

These regulations include, but are not limited to:

- US Environmental Protection Agency Asbestos Hazard Emergency Response Act (US EPA AHERA) and National Emissions Standard for Hazardous Air Pollutants subpart M, Part 61 (NESHAP);
- US Department of Labor, Occupational Safety and Health Administration (OSHA) General Industry Standard (29 CFR 1910.1001) and the OSHA Asbestos Standard for the Construction Industry (29 CFR 1926.1101);
- The Commonwealth of Pennsylvania, Department of Labor and Industry, Asbestos Occupations, Accreditation and Certification Act;
- The City of Philadelphia, Department of Public Health, Asbestos Control Regulations.

3. Asbestos Management Program Execution

a) General Execution

The Office of Environmental Management and Services (OEMS) develops, implements and manages safety and health programs for the School District of Philadelphia faculty, staff and students and assists with ensuring that all contractors comply with Federal, State and Local Environmental Regulations. The OEMS provides the oversight of School District of Philadelphia employees (Asbestos A-Team), environmental consultants, and asbestos abatement contractors for all projects within the School District of Philadelphia concerning Asbestos Containing Materials.

The control of safety and health hazards at the School District of Philadelphia is primarily through the implementation of engineering, work practice and administrative controls. Personal Protective Equipment (PPE) is used to supplement these controls or whenever the controls are not feasible or are in the process of being implemented. PPE is also recommended whenever exposures to chemical, physical or biological agents can be prevented or reduced by its use.

This written program establishes the procedures necessary to:

- 1) meet established standards and federal regulations for occupational exposure to asbestos fibers;
- 2) meet the requirements of the City of Philadelphia Asbestos Control Regulations which encompasses the disturbance and/or abatement of asbestos containing building materials;
- 3) provide the necessary health and safety protection to the School District of Philadelphia staff, faculty, students, contractors and visitors.

This program is strengthened by input and cooperation with the Philadelphia Federation of Teachers (PFT), Health and Welfare Fund.

4. Summary of Program Execution

a) Asbestos Management Program Execution

The Asbestos Management Program is administered by the Office of Environmental Management and Services (OEMS). OEMS provides the following services primarily through professional consultants:

- (1) exposure monitoring services;
- (2) building inspection/surveys (bulk sampling) for the identification of asbestos containing materials;
- (3) asbestos project design services;
- (4) asbestos abatement project and air monitoring services;
- (5) emergency response to fiber release episodes;
- (6) education/information;
- (7) medical monitoring;
- (8) training for School District of Philadelphia personnel

5. Responsibilities

a) Office of Environmental Management and Services

OEMS is responsible for performing the following functions:

- (1) Developing and administering of the Asbestos Management Program.
- (2) Providing asbestos-related services to all School District of Philadelphia departments.
- (3) Conducting required training of the Asbestos Management Program and working jointly with departments to schedule training.
- (4) Identifying and posting areas where labeling/signage are required.
- (5) Medical Monitoring of OEMS "A-TEAM" and other departments "AST" Asbestos Program staff.

- (6) Certification and training as required for OEMS "A-TEAM" and other departments "AST" Asbestos program staff.
- (7) Record keeping as outlined in Section 3.5 and all records as by required by US EPA AHERA regulations.

b) Asbestos Worker/Supervisor - "A-TEAM"

- (1) OEMS shall ensure that all "A-TEAM" workers/supervisors adhere to the following requirements:
 - a) Attend an initial Worker/Supervisor Asbestos Course;
 - b) Maintain the annual re-certification per EPA AHERA requirements and Commonwealth of Pennsylvania Asbestos Occupations, Accreditation and Certifications Act;
 - c) Undergo an annual Asbestos Medical Evaluation;
 - d) Undergo an annual Respirator Medical Clearance;
 - e) Undergo an annual Respirator Fit Testing.

c) Asbestos Designated Person

The Asbestos Designated Person is responsible for:

- (1) Assuring the health and safety of employees, students and visitors in the School District of Philadelphia facilities under his/her control.
- (2) Being kept informed of all areas under his or her jurisdiction where potential asbestos exposures exist and initiating protection programs that adhere to the Asbestos Management Program requirements of this manual.
- (3) Assuring that Asbestos Management Program requirements are adhered to by principal investigators, project managers, supervisors, or division heads, and School District of Philadelphia personnel under their supervision.
- (4) Ensuring that all employees within the Asbestos Management Program comply with (OSHA 1910.1001 (j) (7) (iv)) and the US EPA AHERA regulations by attending the required training.
- (5) Ensure the posting of:
 - a) Warning labels/signage
 - b) Commonwealth of Pennsylvania Asbestos Abatement and Demolition/Renovation Notification form
 - c) Asbestos Inspection Reports (AIR) form (where required)
 - d) Ensuring that Construction Projects follow the Demolition Directive procedures as outlined in the August 4, 2006 letter.

d) Supervisor or Project Manager (Capital, Maintenance and Facilities)

Each person in charge of a project, maintenance/repair, renovation/demolition, or other activity from the Departments of Capital, Maintenance, and/or Facilities, where asbestos containing material may be present is responsible for:

Identifying, with the assistance of OEMS, asbestos containing building materials prior to any disturbance of these materials. Various Federal (EPA and OSHA) and Local (City of Philadelphia Asbestos Control Regulations) require Asbestos Inspections prior to renovation/demolition activities. This shall be accomplished by always following the Asbestos Management Program Procedures as follows:

(1) Ensure that the requirements of the Asbestos Management Program Procedures are followed by all personnel, trades, and contractors who are involved with the project;

- (2) Review of the required Asbestos Inspection Report (AIR) form (Attachment 1) and AHERA Management Plan documents prior to activities that may disturb any Asbestos Containing Materials;
- (3) Perform all project related duties as outlined in the Project Management Responsibilities;
- (4) Keep the department chairperson or director informed on any actions proposed or taken regarding the Asbestos Management Plan;
- (5) Ensuring that Construction Projects follow the Demolition Directive procedure outlined in the August 4, 2006 letter.

e) Employee - Capital

School District of Philadelphia Capital employees and/or consultants shall:

- (1) Ensure that no suspect or asbestos containing building materials are disturbed in the course of the projects they are performing or managing. This shall be accomplished by notifying their supervisor and OEMS by issuance of a work order permit (a.k.a PSIT Service Request Form) and verifying that the materials which may be disturbed are non-asbestos containing. If this information is not available or verification has not been made, these materials should not be disturbed.
- (2) Immediately notify OEMS and their supervisor in the event of a potential fiber release episode upon discovery of visible damage to asbestos containing materials.
- (3) Ensuring that Construction Projects follow the Demolition Directive procedures as outlined in the August 4, 2006 letter.

The types of projects represented as part of the Capital Improvement Program are as follows:

- (1) Complete Renovation of an existing building that addresses all facility component concerns and educational program needs;
- (2) Major Renovation of an existing building addressing significant facility component and educational improvements;
- (3) Addition to an existing building (either as an attachment or stand-alone structure) to accommodate needed program space;
- (4) Conversion of an existing facility to accommodate a change in educational program;
- (5) Facility Component Improvement of specific facility needs (i.e. electrical or HVAC system upgrades, ADA improvements, life safety improvements, exterior renovations, etc.)

f) Employee - Maintenance

School District of Philadelphia Maintenance employees shall:

- (1) Ensure that no suspect or asbestos containing building materials are disturbed in the course of their duties or work they are performing. This shall be accomplished by notifying their supervisor and OEMS by issuance of a work order permit and verifying that the materials which may be disturbed are non-asbestos containing. If this information is not available or verification has not been made, these materials should not be disturbed.
- (2) Immediately notify OEMS and their supervisor in the event of a potential fiber release episode or upon discovery of visible damage to asbestos containing materials.
- (3) All employees involved in maintenance activities shall attend required Asbestos Awareness training program within 60 days of employment.

g) Employee - Facilities & Custodial

School District of Philadelphia Facilities and Custodial employees shall:

- (1) Ensure that no suspect or asbestos containing building materials are disturbed in the course of their duties or work they are performing. This shall be accomplished by notifying their supervisor and OEMS by issuance of a work permit and verifying that the materials which may be disturbed are non-asbestos containing. If this information is not available or verification has not been made, these materials should not be disturbed;
- (2) Immediately notify OEMS and their supervisor in the event of a potential fiber release episode or upon discovery of visible damage to asbestos containing materials.
- (3) All employees involved in Facilities and Custodial activities shall attend require Asbestos Awareness training program within 60 days of employment.

6. Requirements

a) Employee Exposure Monitoring

When information indicates that an employee's exposure to asbestos fibers may equal or exceed an 8-hour time-weighted average of 0.1 f/cc * (per OSHA 1910.1001 & 1926.1101), OEMS shall develop and implement an asbestos exposure monitoring program. The sampling strategy shall be designed to identify employees by work task (job classification) that is exposed to asbestos fibers that exceed an 8-hour time-weighted average of 0.1 f/cc.

b) Employee Notification

OEMS shall notify in writing, each employee exposed to asbestos fibers at or above an 8-hour time weighted average of 0.1 f/cc.

c) Observation and Monitoring

OEMS shall provide employees or their representatives with an opportunity to observe any exposure measurements conducted.

d) Training Program

OEMS shall institute a training program which meets the requirements of AHERA for all employees who perform maintenance operations in a facility/school which contains asbestos containing materials or presumed asbestos containing materials and 1910.1001 (j), and the Commonwealth of Pennsylvania Department of Labor and Industry and the City of Philadelphia Asbestos Control Regulations. The affected departments shall ensure employee participation in this program. The OEMS "A-TEAM" and other departments "AST" Asbestos Program staff training shall be conducted annually for each employee as required by all Federal, State and Local for each asbestos discipline.

All Asbestos Awareness training as required by AHERA shall be performed within 60 days of employment and shall include:

- o Health effects of asbestos
- o Locations of ACM and PACM in the building/facility
- Recognition of CM and PACM damage and deterioration
- o Requirements of the OSHA 1910.1001 standard relating to maintenance
- O Proper response to fiber release episodes
- o Procedure to be followed to isolate areas affected by fiber release

e) Access to Information

OEMS shall make available to affected employees or their representative's copies of the Occupational Safety and Health Administration (OSHA) General Industry Standard Part 1910.1001 and the department shall post a copy in the workplace.

f) Record Keeping

OEMS shall maintain an accurate record of all employee exposure measurements. OEMS and/or the School District of Philadelphia Human Resources Department shall maintain records of employee medical monitoring program. OEMS shall maintain all employee training records. All records shall be provided upon request to employees, former employees, representatives designated by the individual employee.

7. AHERA OPERATIONS AND MAINTENANCE PLAN

a) CONTROLS

i. Work Order System

Minimizing disruption of ACM/PACM during maintenance and renovation activities is the primary goal and task encountered by OEMS. Operations and maintenance employees and contractors should be warned to avoid conducting any maintenance work which may disturb ACM/PACM. Initiating a work order system, where all work orders or requests are channeled through the Office of Environmental Management and Services (OEMS), will be the method used to control and minimize disruption of ACM/PACM.

Any work performed by in-house personnel or contractors that could or will impact ACM/PACM shall be coordinated by OEMS. A completed Asbestos Inspection Report Form (Attachment 1) shall be issued to in-house personnel and/or all contractors whose work could impact ACM/PACM. This form should accompany each contract issued to an outside contractor and posted on the jobsite.

All work order requests for maintenance and renovation activities in areas where ACM/PACM is suspected or known to be present are to be submitted to OEMS prior to proceeding with work. OEMS is responsible for reviewing asbestos survey records for information about the presence of ACM/PACM in the area where the work is to be performed. OEMS should physically inspect the area to ensure existing records reflect actual conditions. If no asbestos is present, a work order is not necessary and the planned actions can proceed. If ACM/PACM is found to be present in the area, OEMS will sign the work order application and obtain an approved and accredited asbestos contractor or assign OEMS "A-TEAM" to abate the ACM/PACM.

ii. Regulated Areas

The owner will identify and regulate all areas where airborne concentrations of ACM/PACM exceed the Permissible Exposure Limit (PEL)* (Per OSHA determined to be 0.1 f/cc) and/or short term exposure limit (STEL) (Per OSHA determined to be 0.1 f/cc), or there is reasonable possibility that the (PEL) and/or (STEL) may be exceeded. All ACM/PACM removal activities involving thermal system insulation ACM/PACM (Class I), surfacing ACM/PACM (Class I), and miscellaneous ACM/PACM such as floor tile, roofing, and siding mastic, etc. (Class II), and repair and maintenance operations where thermal system insulation and surfacing ACM/PACM is likely to be disturbed (Class III) will be performed in accordance with federal, state, and local regulations. All asbestos abatement work and activities will be designed and managed as asbestos regulated areas. These areas will be demarcated and labeled.

iii. Warning Signs

Warning signs shall be displayed at all approaches to each asbestos regulated area. The asbestos abatement contractor will provide OSHA warning signs in all regulated areas during removal, repair, and other maintenance activities. OEMS will provide AIRs to all contractors who must inform all employees and supervisors working in locations contiguous to asbestos regulated areas of the potential hazards and work practices required.

iv. Warning Labels

Warning labels and./or signage shall be affixed to all raw materials, mixtures, scrap, waste, debris, and other products containing asbestos fibers, or to their containers. Generally, the asbestos abatement contractor or OEMS A-Team personnel will provide all warning labels for ACM/PACM containment.

8. O & M RESPONSE ACTIONS

The Asbestos Management Program general O&M procedures are outlined in this section. Additional requirements specific to asbestos abatement activities are included in the Project Design documents for all Asbestos Abatement Work. Regular cleaning, inspection, and reporting of ACM/PACM deterioration or other problems must be diligently practiced by all employees including custodial and maintenance personnel.

a) Facility Maintenance Isolation of Area Responsibilities

Maintenance personnel are often required to work in areas where ACM/PACM may potentially be disturbed. Most maintenance activities are conducted by in-house staff, outside contractors, or a combination.

Emergency fiber release episodes, such as pipe fitting or valve breaks, emergency boiler work, or mechanical equipment repair will be responded to by OEMS A-Team personnel or asbestos abatement contractor personnel. The owner's maintenance staff will: (1) isolate the emergency fiber release area; (2) post warning signs to prevent unauthorized access, and (3) notify their supervisor and OEMS. OEMS will ensure that the fiber release area remains isolated and is properly cleaned by and approved and accredited abatement contractor or by OEMS A-TEAM personnel.

b) Unlikely Contact with ACM/PACM

Maintenance activities or repairs which can be performed without contacting or disturbing the ACM/PACM require little more than normal care and good workmanship. For example, valves which are either uncovered or covered with non-asbestos insulation can be packed or repaired without disturbing asbestos insulation on nearby pipes. The major precaution is to ensure that maintenance and custodial personnel are familiar with procedures such as isolating the area, posting warning signs, and notifying OEMS in the event of any accidental ACM/PACM disturbance.

c) Accidental Disturbance of ACM/PACM

Maintenance and facilities personnel shall notify OEMS any time a fiber release is suspected. If friable ACM/PACM becomes airborne in the building,

d) Planned Disturbance of ACM/PACM

Maintenance activities that may impact ACM/PACM include access to a valve, flange, duct, or related system component.

Where asbestos-containing insulation must be removed to maintain or repair the thermal system, the ACM/PACM will imminently be disturbed. ACM/PACM removal work shall be conducted by OEMS A-Team personnel or an approved and accredited asbestos abatement contractor.

If friable ACM/PACM becomes airborne in the building, maintenance and facilities personnel shall secure the area and contact OEMS. OEMS shall respond accordingly.

e) Miscellaneous ACM/PACM

Miscellaneous types of ACM/PACM may include vinyl asbestos floor tiles, mastics/adhesives and woven vibration dampers. Disturbance of these materials should be avoided. Routine maintenance activities involving these materials should not pose a problem if handled properly. Questions on the proper removal and disposal of miscellaneous ACM/PACM should be directed to OEMS. OEMS will contact an approved and accredited asbestos abatement contractor or utilize OEMS A-TEAM personnel to assist with miscellaneous ACM/PACM clean-up activities.

f) Vinyl Asbestos Floor Tile

Asbestos-containing floor tiles in good condition are considered non-friable unless they are crushed, drilled, sawed, sanded or disturbed by any activity that breaks up the material. Routine maintenance of these materials should employ the use of non-abrasive buffers and wet cleaning technique. Broken or loose floor tiles should be removed and disposed of as asbestos waste by OEMS. Remaining debris should be vacuumed with a HEPA vacuum and the area wet mopped using amended water.

g) Mastics/Adhesives

Mastics and adhesives containing asbestos in good condition are considered non-friable and do not pose a potential health concern unless crushed, drilled, sawed, sanded, or otherwise abraded. Questions on the proper removal should be directed to OEMS.

h) Woven Vibration Dampers

Woven vibration dampers in good condition are considered non-friable and do not pose a potential health concern unless cut, crushed, drilled, sawed, sanded, or otherwise abraded. Questions on the proper removal should be directed to OEMS.

i) Other Work Practices

Any special work not included in this section should be addressed to OEMS for review prior to the initiation of work that may involve the disturbance of ACM/PACM.

j) Fiber Release Episodes

Facilities and maintenance staff should report to OEMS the presence of asbestos debris, water or physical damage to ACM/PACM, or any other evidence of possible fiber release. OEMS should have the OEMS A-Team personnel or an approved and accredited abatement contractor respond to the site to clean up debris and make repairs as soon as possible. OEMS will also contact a consultant to conduct air monitoring and prepare a report and submit at project completion to OEMS for each episode. OEMS will forward the reports for each site location AHERA Management Plan accordingly.

9. REFERENCES and RESOURCES

Applicable regulations for asbestos projects impacted by renovation, demolition, and maintenance activities.

- Philadelphia Air Management Services Asbestos Control Unit http://www.phila.gov/health/units/ams/Asbestos/asbestos.html
- Pennsylvania Asbestos Occupations, Accreditation and Certification Act
 http://www.dli.state.pa.us/landi/cwp/view.asp?a=185&q=56262&landiNav=
- United States Environmental Protection Agency Asbestos Home Page
 http://www.epa.gov/asbestos/
- Occupational Safety and Health Administration (OSHA) Asbestos Home
 http://www.osha.gov/SLTC/asbestos