SCHOOL DISTRICT OF PHILADELPHIA



Asbestos Hazard Emergency Response Act "AHERA"

THREE-YEAR RE-INSPECTION 2015-2016

and ASBESTOS MANAGEMENT PLAN for the

Henry H. Houston Elementary School

ULCS# 6260 Building # B626001-1 7300 Rural Lane Philadelphia, Pennsylvania 19119

Year Built: 1927

October 2015

Conducted by:

Accredited Environmental Technologies, Incorporated
Batta Environmental Associates, Incorporated
Criterion Laboratories, Incorporated
Environmental Testing Consultants, LLC
G & C Environmental Services, Incorporated
KEM Partners, Incorporated
Synertech, Inc.
TTI Environmental, Inc.
USA Environmental Management, Inc.
The Vertex Companies, Inc.

Management Plan Prepared by: Criterion Labs, Inc. and Synertech Inc.

This report must remain in the Main Office as mandated by the US EPA AHERA Regulations.

AHERA THREE-YEAR REINSPECTION VOLUME IX

Table of Contents

Transmittal Letter

Executive Summary

- I. Summary list of Confirmed Asbestos Containing Building Materials
- II. Summary list of Assumed Asbestos Contain Building Materials
- III. Summary list of Non-Asbestos Containing Building Materials
- IV. Summary list of Non Suspect Asbestos Containing Building Materials
- V. Summary List of Auditorium DATA for this location
- VI. Summary list of Attic and/or Crawlspace DATA for this location
- VII. Summary list of Pipe Chase/Pipe Shaft DATA for this location

Section I Report of Re-Inspection

- A. Introduction
- B. Three-Year Re-inspection IX Overview
- C. Post- Management Plan Activities and Changes
 - C.1 Sampling and Analysis
 - C.2 New Floor Tile Sampling
 - C.3 Abatement Activity
 - C.4 Periodic (Six-Month) Surveillance (Damaged Materials)

Section II Re-Inspection Data

- A. Introduction
- B. Re-Inspection Key Definitions
- C. Room by Room Location Log Report

Section III Certificates

A. Management Planner/Building Inspector Certificates

Section IV Cross Reference Table Page 1-8

Asbestos Management Program Page 9-19

SCHOOL DISTRICT OF PHILADELPHIA EDUCATIONAL CENTER

440 NORTH BROAD STREET PHILADELPHIA, PENNSYLVANIA 19130

OFFICE OF ENVIRONMENT AL MANAGEMENT AND SERVICES

PHONE (215)-400-4750

January 2016

TO: All Principals

All Building Administrators

FROM: Fran Burns

Chief Operating Officer

Francine Locke, M.S., Director

Office of Environmental Management and Services

SUBJECT: AHERA Three (3) Year Re-inspection IX report

In order to comply with the provisions of the Asbestos Hazard Emergency Response Act (AHERA) the attached report is submitted to you. The law requires that this report be kept in the Main/Principal's office. It cannot be removed from these locations. *If the school (program) is relocated to a different building, these environmental documents are to be safely retained for the next school/building occupants*. All asbestos reports must be available to the public and Federal EPA upon request.

Fran Burns

Chief Operation Officer

Francine Locke, M.S., Director Office of Environmental Management

and Services

AHERA-2d Revised 12/14/15

Executive Summary

This Asbestos Hazard Emergency Response Act (AHERA) Three-Year Re-inspection "Volume # IX" Management Plan at this location, has been completed and the report of re-inspection submitted to the School District of Philadelphia. The re-inspections in all School District of Philadelphia buildings of 2015-2016 were conducted and completed between October 5th, 2015 through March 30th, 2016 as a joint project by Accredited Environmental Technologies, Inc., Batta Environmental Associates, Inc., Criterion Laboratories, Inc., Environmental Testing Consultants, LLC, G & C Environmental Services, Inc., KEM Partners, Inc., Synertech, Inc., TTI Environmental, Inc., USA Environmental Management, Inc. and The Vertex Companies, Inc.

In general, the School District of Philadelphia Office of Environmental Management and Services conducts Environmental Impact Evaluations and provides Asbestos Inspection Reports prior to any renovation, demolition and/or maintenance activities. The AHERA report must be reviewed prior to any renovation, demolition and/or maintenance activities in order to avoid the unknowing disturbance to Asbestos Containing Building Materials identified within this location. In addition, prior to work activities above all drop ceilings this report should be reviewed to avoid potential disturbances to Asbestos Containing Materials. Refer to Section IV of the Cross Reference Table, for additional Asbestos Management Program information. Contact the Office of Environmental Management and Services to have an Environmental Impact Evaluation conducted prior to any renovation, demolition and/or maintenance activities within this facility.

The information contained in this report was obtained from the original Asbestos Management Plan for the school, from update reports on changes and activities since the completion of the 1st Management Plan for each location and from all prior inspections performed and documented in Volume # I through Volume VIII (dated respectively 1992, 1995, 1998, 2001, 2004, 2007, 2010 or 2013) (if applicable) - and by this Three-Year Re-inspection of this school. The re-inspection report/Management Plan of 2015-2016 were reviewed and prepared collectively by Management Planner Megan Vala, Mary Anne Lerro of Criterion Laboratories, Inc. and/or Monique Causley, of Synertech Inc.

The 2015-2016 inspection process included the addition of a comprehensive Room by Room Inventory of all Thermal (T), Surfacing (S) and Miscellaneous (M) Materials specific to each room of this facility. Inspections of each room's thermal, ceilings, walls, floors and miscellaneous items regardless of Asbestos Content are categorized on the Room by Room Location Log Report for this location. Rooms or areas of the facility that were not accessible at the time of the inspection are marked with an "X". The Room by Room Location Log Report is found in Section II C of this Management Plan.

All Presumed or Suspect Asbestos Containing Building Materials (ACBMs), listed in the following summary charts are categorized as Confirmed, Assumed, Non-Asbestos, and/or Non-Suspect (ACBMs) were identified in the original Management Plan, or in the Volume I through Volume VIII AHERA Three-Year Re-inspection reports, and were re-inspected as part of this project.

As mandated by the U S EPA AHERA regulations, periodic Six-Month inspections and Three-Year Re-inspections of this location will be performed and the Inspection Data in this report will be updated accordingly.

Please feel free to contact the School District of Philadelphia's Office of Environmental Management and Services (OEMS) regarding any comments, questions, or concerns regarding this report or any Environmental related topic. OEMS staff can be reached at (215) 400 4750, via fax at (215) 400 4751 or via e-mail at flocke@philasd.org and/or flocke@philasd.org.

Additional information can be found on our website. Here is the link to the OEMS website. http://webgui.phila.k12.pa.us/offices/e/environmental

I. Summary list of Confirmed Asbestos Containing Building Materials within this facility

These charts are to be used for a quick reference* in order to avoid the unknowing disturbance of Asbestos Containing Materials during any and all Operations, Maintenance, Renovation, and/or Demolition activities at this location. These materials have been sampled and Laboratory Analysis has CONFIRMED the presence of Asbestos. Contact OEMS prior to the disturbance of any of the following materials.

Confirmed Asbestos Containing Building Materials for this location

Floor Tile VAT 9" x 9"	Pipe Fitting Insulation	Pipe Insulation > 6 inch
Pipe Insulation 2-6 inch	Acoustical Plaster Ceiling	

^{*} Always refer to the Room by Room Logs for each specific material classification as the material classification findings may be different in various rooms throughout this facility.

^{**} Some Materials may have multiple classifications (Confirmed, Assumed, NAD and Non Suspect) within this facility.

II. Summary list of Assumed Asbestos Containing Building Materials within this facility

These charts are to be used for a quick reference* in order to avoid the unknowing disturbance of Asbestos Containing Materials during any and all Operations, Maintenance, Renovation, and/or Demolition activities at this location. These materials have not been sampled and should not be disturbed until verification of Asbestos Content. Contact OEMS for assessment and sampling prior to the disturbance of these materials.

Assumed Asbestos Containing Building Materials for this location

Blackboard Glue Dots	Sink Undercoat Mastic	Transite Electrical Panel
Ceiling Tile 1' x 1'	Spline Ceiling Glue Dots	Transite Sills
Floor Tile VAT 12" x 12"	Transite	Transite Stalls
Linoleum	Transite Closet	Vibration Damper Cloth

^{*} Always refer to the Room by Room Logs for each specific material classification as the material classification findings may be different in various rooms throughout this facility.

^{**} Some Materials may have multiple classifications (Confirmed, Assumed, NAD and Non Suspect) within this facility.

III. Summary list of Non-Asbestos Containing Building Materials within this facility

These charts are to be used for a quick reference* in order to avoid the unknowing disturbance of Asbestos Containing Materials during any and all Operations, Maintenance, Renovation, and/or Demolition activities at this location. These materials have been sampled and Laboratory Analysis has indicated NO Asbestos present or NO ASBESTOS DETECTED (NAD).

Non- Asbestos Containing Building Materials for this location

Plaster Wall	Ceiling Tile 1' x 1'	Plaster Ceiling

^{*} Always refer to the Room by Room Logs for each specific material classification as the material classification findings may be different in various rooms throughout this facility.

^{**} Some Materials may have multiple classifications (Confirmed, Assumed, NAD and Non Suspect) within this facility.

IV. Summary list of Non-Suspect Asbestos Containing Building Materials within this facility

These charts are to be used for a quick reference* in order to avoid the unknowing disturbance of Asbestos Containing Materials during any and all Operations, Maintenance, Renovation, and/or Demolition activities at this location. These materials are not typically known to contain Asbestos.

Non-Suspect Asbestos Containing Building Materials for this location

Boiler Breeching	Concrete Ceiling	Sheetrock Wall
Brick Wall	Concrete Wall	Terrazzo Floor
Carpet	Duct Work	Vinyl Vibration Damper Cloth
Ceiling Tile 2' x 4'	Fiberglass Ceiling Tile 2' x 4'	Wood Floor
Cement Floor	Fiberglass Pipe Insulation	Marble Wall
Ceramic Tile Floor	Glass Block Ceiling	Partition Room Dividers
Ceramic Tile Wall	Concrete Block Wall	

^{*} Always refer to the Room by Room Logs for each specific material classification as the material classification findings may be different in various rooms throughout this facility.

^{**} Some Materials may have multiple classifications (Confirmed, Assumed, NAD and Non Suspect) within this facility.

V. Summary list of Auditorium DATA for this location

These charts are to be used for a quick reference of the Auditorium DATA within this facility. Sampling of the Auditorium Ceilings throughout the District is more difficult because of the various ceiling heights. As sampling occurs this information is updated on a case by case basis for each specific location and facility.

This is a list of known materials for this location's Auditorium

Auditorium						
Auditorium	Concrete Block Wall	Non Suspect ACM				
Auditorium	Transite Sills	Assumed				
Auditorium	Floor Tile VAT 9" x 9"	Confirmed				
Auditorium	Floor Tile VAT 12" x 12"	Assumed				
Auditorium	Floor Tile VAT 12" x 12"	Assumed				
Auditorium	Cement Floor	Non Suspect ACM				
Auditorium	Acoustical Plaster Ceiling	Confirmed				

^{*} Always refer to the Room by Room Logs for each specific material classification as the material classification findings may be different in various rooms throughout this facility.

^{**} Some Materials may have multiple classifications (Confirmed, Assumed, NAD and Non Suspect) within this facility.

VI. Summary list of Attic and/or Crawlspace DATA for this location

These charts are to be used for a quick reference regarding the Attics and/or Crawlspaces inspection DATA within this facility. Contact OEMS prior to entering any attic or crawlspace within this facility and refer to the below chart and legend for Category Rank determination. The Data relative to these spaces is updated as conditions change regarding Abatement or Renovation activity on a case by case basis for each specific location and facility. In general, Crawlspaces are below the basement or 1st floor and Attics are above the floor space.

Category Rank Legend

- "A" No Asbestos Containing Materials Sample Results indicate NO ACM on pipes, fittings, elbows, or equipment located within this functional space, and NO VISIBLE DEBRIS or DAMAGE observed at time of this inspection.
- "B" Asbestos Containing Materials Exist Sample Results indicate ACM on pipes, fittings, elbows, or equipment located within this functional space, HOWEVER, NO VISIBLE DEBRIS or DAMAGE observed at time of this inspection.
- "C" Asbestos Containing Materials Exist Sample Results indicate ACM on pipes, fittings, elbows, or equipment located within this functional space, and LOCALIZED VISIBLE DEBRIS or DAMAGE observed at time of this inspection.
- "D" Asbestos Containing Materials Exist Sample Results indicate ACM on pipes, fittings, elbows, or equipment located within this functional space and DISTRIBUTED VISIBLE DEBRIS or SIGNIFICANT DAMAGE observed at time of this inspection.
- "E" No Bulk Sample Results Available SUSPECT ACM OBSERVED. Contact OEMS immediately for additional instructions.

Attic/Crawlspace	Access Area	Floor Surface	Category Rank	Comments
Attic/Crawispace	Access Area	Floor Surface	Kalik	Fiberglass PI, Hard Fittings,
	Third Floor Holl adjacent to	Wine I sales /Wis sal		
	Third Floor Hall adjacent to	Wire Lathe/Wood		Plastic Caps/Equipment, Concrete
Attic	Classroom 304	Planks	A	Floor
				1500 LF damaged Air Cell,150
				Hard Fittings, Visible Debris
				Poly/Critical on door, Wire Lathe
Crawl Space	Boiler Room	Concrete	C	Floor

VII. Summary list of Pipe Chase/Pipe Shaft DATA for this location

These charts are to be used for a quick reference regarding the information known about the Pipe Chases and/or Pipe Shafts inspection DATA within this facility. Contact OEMS prior to performing renovation activities any Pipe Chase and/or Pipe Shaft within this facility and refer to the below chart and legend for Asbestos Content of various materials identified within each space. The Data relative to these spaces is updated as conditions change regarding Inspection, Abatement and/or Renovation activity on a case by case basis for each specific location and facility. In general, Pipe Chases are horizontal spaces and Pipe Shafts are vertical spaces.

	1					
Element	Floor	On Site Room Name	Material	Confirmed Assumed NAD/Non Suspect	Amount of Material	Amount of Damage
			Fiberglass Pipe	•		
1	1	Girl's Restroom Pipe Chase	Insulation	Non Suspect ACM	30 LF	0
1	1	Girl's Restroom Pipe Chase	Concrete Ceiling	Non Suspect ACM	40 SF	0
1	1	Girl's Restroom Pipe Chase	Plaster Wall	NAD	265 SF	0
1	1	Girl's Restroom Pipe Chase	Concrete Block Wall	Non Suspect ACM	265 SF	0
1	1	Girl's Restroom Pipe Chase	Cement Floor	Non Suspect ACM	40 SF	0
1	1	Hallway Pipe Chase adjacent to 1st Floor Element 2 Boy's Restroom	X	X	X	X
			Fiberglass Pipe			
1	2	Boy's Restroom Pipe Chase	Insulation	Non Suspect ACM	50 LF	0
1	2	Girl's Restroom Pipe Chase	Fiberglass Pipe Insulation	Non Suspect ACM	30 LF	0
		Pipe Chase in Staff Restroom across from				
1	2	Classroom 212	X	X	X	X
1	3	Boy's Restroom Pipe Chase	Fiberglass Pipe Insulation	Non Suspect ACM	20 LF	0
			Fiberglass Pipe			
1	3	Girl's Restroom Pipe Chase	Insulation	Non Suspect ACM	30 LF	0
	_	Staff Restroom adjacent to Boy's Restroom	***	***	***	***
1	В	Pipe Chase	X	X	X	X
1	D	Storage Closet adjacent to Boy's Restroom	v	v	V	V
1	В	Pipe Chase	X Fiberglass Pipe	X	X	X
1	В	Boy's Restroom Pipe Chase for Urinals	Insulation	Non Suspect ACM	20 LF	0
1	В	Boy's Restroom Pipe Chase for Urinals	Concrete Ceiling	Non Suspect ACM	66 SF	0
1	В	Boy's Restroom Pipe Chase for Urinals	Concrete Block Wall	Non Suspect ACM	340 SF	0
1	В	Boy's Restroom Pipe Chase for Urinals	Brick Wall	Non Suspect ACM	265 SF	0
1	В	Boy's Restroom Pipe Chase for Urinals	Cement Floor	Non Suspect ACM	66 SF	0
1	В	Boy's Restroom Pipe Chase for Toilets	Fiberglass Pipe Insulation	Non Suspect ACM	40 LF	0
1	В	Girl's Restroom Pipe Chase	Fiberglass Pipe Insulation	Non Suspect ACM	20 LF	0
1	В	Storage Closet adjacent to Girl's Restroom Pipe Chase	Fiberglass Pipe Insulation	Non Suspect ACM	60 LF	0
1	В	Left Closet adjacent to Boy's Restroom Pipe Chase	X	X	X	X

Element	Floor	On Site Room Name	Material	Confirmed Assumed NAD/Non Suspect	Amount of Material	Amount of Damage
			Concrete			
1	В	Kitchen Office Restroom Pipe Chase	Ceiling	Non Suspect ACM	15 SF	0
			Concrete Block			
1	В	Kitchen Office Restroom Pipe Chase	Wall	Non Suspect ACM	160 SF	0
1	В	Kitchen Office Restroom Pipe Chase	Cement Floor	Non Suspect ACM	15 SF	0
			Vibration			
1	В	Kitchen Office Restroom Pipe Chase	Damper Cloth	Assumed	1 SF	0

Section I Report of Re-Inspection

- A. Introduction
- **B.** Three-Year Re-Inspection IX Overview
- C. Post-Management Plan Activities and Changes
 - **C.1** Sampling and Analysis
 - **C.2** New Floor Tile Sampling
 - **C.3** Abatement Activity
 - **C.4** Periodic Six-Month Surveillance (Damaged Materials)

Section I - A

Report of Re-inspection

Introduction

The Three-Year Re-inspection IX was performed to fulfill the requirements of 40 CFR Part 763 - the Asbestos Hazard Emergency Response Act (AHERA). As required by AHERA, each Local Education Agency (LEA) must re-inspect all known confirmed or assumed Asbestos Containing Building Material (ACBM) located in the LEA's facilities. This re-inspection is intended to update the original Asbestos Management Plan for the LEA's facilities.

Multiple Building Inspectors of several firms performed the 2015/2016 re-inspection. The reinspection report/Management Plan of 2015-2016 were reviewed and prepared collectively by Management Planner Megan Vala, Mary Anne Lerro of Criterion Laboratories, Inc. and Monique Causley, of Synertech Inc.

All of the certificates can be found in Section III.

During the re-inspection of each School District of Philadelphia facility, all of the Management Plans for that facility were reviewed. Information from the conclusions section of that report is included in this report. Additionally, information on activities such as abatements, cleanings, sampling and inspections, which have taken place since the completion of the original Management Plan, were reviewed during the re-inspection. Information on those activities is included in this report.

As mandated by the U S EPA AHERA regulations, all future periodic Six-Month inspections and Three-Year Re-inspections of this location will be performed and the Inspection Data in this report will be updated accordingly.

Section I - B

Three-Year Re-inspection IX Overview

Each homogeneous area of Asbestos Containing Building Material (ACBM) listed in the original Management Plan or in the 1992, 1995, 1998, 2001, etc., Three-Year Reinspection reports were inspected for the AHERA Three-Year Re-inspection Volume IX, and the information for that material verified. Any changes to a homogeneous area listed in the updates to the Management Plans were verified. Any area of suspected ACBM found in the course of the re-inspection, and not listed in the Management Plan or updates, were either assumed to contain asbestos or sampled and analyzed to determine their asbestos content. Any such new areas either assumed to contain asbestos or determined through analysis to contain asbestos were included in the report of the Three-Year Re-inspection. The results of the AHERA Three-Year Re-inspection IX are tabulated in the Room by Room log reports located in *Section II-C* of this report.

As previously noted, all future periodic Six-Month inspections and Three-Year Reinspections of this location will be performed and the Inspection Data in this report will be updated accordingly.

Post Management Plan Activities/Changes

Information on activities affecting Asbestos Containing Building Materials (ACBMs) at this location is contained in updates to the Management Plan. These updates are kept on file by the School District of Philadelphia and were reviewed for this project. Updates to the Management Plan include the following: Sampling and Analysis, New Tile Installation, Abatement Activity and Periodic Six-Month Surveillance Data.

Sampling and Analysis

In the event Sampling occurs, data will be listed here.

Information on the installation of new floor tiles/renovation activities affecting Asbestos Containing Building Materials (ACBMs) at this location is contained in updates to the Management Plan. These updates are kept on file by the School District of Philadelphia and were reviewed for this project. Updates to the Management Plan include the following:

New Floor Tile Sampling

In the event that new tile is installed, the material must be tested prior to installation.

Information on the Asbestos Abatement and renovation activities affecting Asbestos Containing Building Materials (ACBMs) at this location is contained in updates to the Management Plan. These updates are kept on file by the School District of Philadelphia and were reviewed for this project. Updates to the Management Plan include the following:

Abatement Activity

	Floor				Removed or	
Date	r	Location	Material	Color	Encapsulated	Quantity
12/5/2016	BS	Basement Art Room	Pipe Insulation 2-6 inch	N/A	Encapsulated	1 LF
12/5/2016	BS	Basement Art Room Meter Room	Pipe Insulation 2-6 inch and Pipe Fitting Insulation	N/A	Removed	26 LF
12/6/2016	BS	Basement Art Room Back Storage Area	Pipe Insulation 2-6 inch and Pipe Fitting Insulation	N/A	Removed	10 LF
		Basement Stairwell adjacent to				
12/6/2016	BS	Home and School Office	Floor Tile VAT 9" x 9"	Brown	Removed	4 SF
12/6/2016	3	Classroom 304	Pipe Insulation 2-6 inch	N/A	Encapsulated	1 LF
12/6/2016	1	Classroom 101	Pipe Insulation 2-6 inch	N/A	Encapsulated	1 LS
12/6/2016	1	Classroom 102	Pipe Insulation 2-6 inch	N/A	Encapsulated	1 LF

Information on the AHERA inspection that noted damage to various Building Materials at this location is contained in updates to the Management Plan. These updates are kept on file by the School District of Philadelphia and were reviewed for this project. Work orders are created for Corrective Action responses and tracked for completion. Updates to the Management Plan include the following:

Periodic (Six-Month) Surveillance (Damaged Materials)

	Element	Floor			of	Amount of
Date		3	On Site Room Name	Material	Material	
11/16/2016	1	1	Classroom 101	Pipe Insulation 2-6 inch	48 LF	1 LF
11/16/2016	1	1	Classroom 102	Pipe Insulation 2-6 inch	48 LF	1 LF
11/16/2016	1	1	Copy Room 103A	Floor Tile VAT 12" x 12"	180 SF	2 SF
11/16/2016	1	1	Classroom 109	Floor Tile VAT 12" x 12"	1360 SF	2 SF
11/16/2016	1	1	Classroom 112	Floor Tile VAT 9" x 9"	709 SF	1 SF
11/16/2016	1	1	Stage	Floor Tile VAT 9" x 9"	960 SF	5 SF
11/16/2016	1	1	Hallway outside Auditorium	Pipe Fitting Insulation	33 EA	1 EA
11/16/2016	1	2	Teacher Lounge 209A	Floor Tile VAT 12" x 12"	75 SF	2 SF
11/16/2016	1	3	Classroom 304	Pipe Insulation 2-6 inch	24 LF	1 LF
11/16/2016	1	В	Music Room 018	Floor Tile VAT 9" x 9"	896 SF	30 SF
11/16/2016	1	В	Home and School Office	Floor Tile VAT 9" x 9"	350 SF	200 SF
			Stairwell adjacent to Home and			
11/16/2016	1	В	School Office	Floor Tile VAT 9" x 9"	5 SF	5 SF
11/16/2016	1	В	Cafeteria	Floor Tile VAT 12" x 12"	5100 SF	6 SF

Section II Re-Inspection Data

A. Introduction

B. Re-Inspection Key Definitions

C. Room by Room Location Log Report

Section II - A

Re-inspection Data

Introduction

The following information documents the Three-Year Re-inspection IX of the subject school/facility. The Homogeneous Area Reports were produced using the building inspector's field data on the facility. The key to the Homogeneous Area Report is outlined in the following pages of this report.

Section II - B (page 1 of 4)

SCHOOL DISTRICT OF PHILADELPHIA AHERA THREE YEAR RE-INSPECTION IX

ITEM	DEFINITION			
ULCS#	Individual identification number assigned to each school within the School District of Philadelphia.			
HOMOGENEOUS AREA ID#	Identification number assigned to each homogeneous area in a school/facility. Each section of the homogeneous area ID is significant.			
	1010/01/01/01 A B C D			
	 A. Is the ULCS# for the school. B. Designates the specific building/building area within the school. C. Designates the floor or level within the building/building area. D. Designates the homogeneous material within that floor or level. Note: Item D may be a number or a letter. 			
SYSTEM AFFECTED	Corresponds to the AHERA system for classifying materials.			
	 T : Thermal System S : Surfacing System M : Miscellaneous 			
ITEM AFFECTED	Is a description of the homogeneous material.			
ORIGINAL INSPECTION DATA	This section contains the information found in the original Management Plan (1988-1989).			
AMOUNT OF MATERIAL/ UNIT	Quantity of material, and measuring unit. Units include: Square Feet (SF) Each (EA) Linear Feet (LF) Cubic Feet (CF).			

SCHOOL DISTRICT OF PHILADELPHIA AHERA THREE YEAR RE-INSPECTION IX

RE-INSPECTION FORM KEY

ITEM D	EFINITION
--------	------------------

CND Corresponds to AHERA condition rating for materials.

Condition

0 : No Damage1 : Damage

2 : Significant Damage

DP

Corresponds to the AHERA material assessment system.

Damage Potential

1 : Potential for Damage

2 : Potential for Significant Damage

ASMD Assumed Asbestos This means that a material was not sampled for asbestos content during the original Management Plan inspection.

RA

This corresponds to the AHERA system of response action rating for materials.

Response Action

1 : Establish O&M Program

2 : Repair and Establish O&M Program

3 : Enclose
4 : Encapsulate
5 : Remove

6 : Partial Removal and Establish O&M Program

CHANGES

This section describes changes to the homogeneous material in the twenty-four years since the original AHERA inspection. The abbreviations are defined below.

RMVD Removed **ENCL** Enclosed **ENCP** Encapsulated **DMGD** Damaged **SMPLD** Sampled Material MTRL **RPRD** Repaired None Located N/L **RPLCD** Replaced

SCHOOL DISTRICT OF PHILADELPHIA AHERA THREE-YEAR RE-INSPECTION IX

RE-INSPECTION FORM KEY

ITEM DEFINITION

THREE YEAR RE-INSPECTION

This section contains the information obtained from the Three-Year Re-inspection IX. With three exceptions, the information categories are identical in format and meaning to those found in the original inspection data section. The three exceptions are defined below.

DMGD AMT Amount Damaged

This section gives the quantity of damaged material in a homogeneous area. The quantity is shown in the same format as the amount of material/unit section.

NF Newly Friable

This section identifies materials in the original Management Plan which have since become friable.

RA Response Action

This rating is based on the AHERA regulations, and is comparable to the RA rating found in the "Original Inspection Data" section. The following table details the response actions.

- 1. Establish O&M Program
- 2. Repair and Establish O&M Program
- 3. Enclose
- 4. Encapsulate
- **5.** Remove
- **6.** Partial Removal and Establish O&M Program

a. High Priority Response

The homogeneous material has been scheduled for abatement or other response action.

b. Medium Priority Response

The homogeneous material will be scheduled for abatement or other response action as soon as the high priority responses have been addressed.

c. Low Priority Response

The homogeneous material will be scheduled for abatement or other response action as soon as the medium priority responses have been addressed.

d. On-Going Response/Operations and Maintenance

The homogeneous material does not require abatement or other response action at present, and should be included in the facility's on-going operations and maintenance program.

SCHOOL DISTRICT OF PHILADELPHIA AHERA THREE-YEAR RE-INSPECTION IX

RE-INSPECTION FORM KEY

The information presented in the changes section has been compiled from a variety of sources, including the Re-inspection and the following:

- * Quality Control/Quality Assurance Reports of asbestos abatement projects, prepared by consultants to the School District.
- * Permit and Notification Forms for asbestos abatement projects.
- * Periodic Surveillance Forms
- * Operations and Maintenance activities performed by School District personnel.
- * Verbal information from School District personnel.
- * Reports of sampling and analysis of suspected materials by both School District personnel and outside consultants.

ROOM BY ROOM LOCATION LOG REPORT This section gives information, including damage amount and location, for a specific homogeneous material on a room-by-room basis and follows the Re-inspection form.

NOTE: The disparate nature of the above sources of information prohibits the verification of much information within the scope of the AHERA Three-Year Re-inspection. Discrepancies and omissions may exist in this information, and therefore is included on an "as is" basis. The inspectors for the Three-Year Re-inspection IX evaluated homogeneous areas based on the materials current condition and location, as evidenced during the inspector's site visit.

.

Section II - C

Room by Room Location Log Report

These charts are to be used for a quick reference* in order to avoid the unknowing disturbance of Asbestos Containing Materials during any and all Operations, Maintenance, Renovation, and/or Demolition activities at this location.

NOTE:

Contact OEMS prior to the disturbance of any of the materials that are listed as **Confirmed and/or Assumed**.

The quantities listed for (NAD) non-asbestos containing materials and/or Non-Suspect Materials are only estimated and were not measured for the purpose of this report. Field verification of quantities for renovation purposes would be necessary.

School District of Philadelphia		AH	ERA Three-Year Reins	pection 2015-2016						Reinspection Date: 10/8/2015				
Henry H. Houston Elementary School (K-8)			Room by Room Locat	•						Building Inspector: Bernard Brunner				
7300 Rural Lane, Philadelphia, PA 19119	'			ion log Report			_			Certificate Number: 45397	_			
											-			
ULCS# 6260										Management Planner: Monique Causley	_			
Year Built: 1927			1	1			_	_		Certificate Number: ACC-0215-8-010				
E I														
e F														
m I												_		
e o n o	Suctom			Confirmed, Assumed, NAD.	Amount of	SF LF	Amount of	SF LF	Color required		Attic Crawl	Damage Potential	Newly Friable	Response
n o t r On Site Room Name	System Affected	Material Description	HID#	Non Suspect ACM	Material	EA	Damage		for VAT	Comments/Description/Notes	Space Ranking	(DP)	(NF)	Action (RA)
1 1 Classroom 101	Т	Pipe Insulation 2-6 inch	6260/01/01/09	Confirmed	48	LF	1	LF		Was DDC written for this damage?		1	No	2/B
1 1 Classroom 101	N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	792	SF	0	SF				N/A	N/A	N/A
1 1 Classroom 101	N/A	Plaster Ceiling		NAD	792	SF	0	SF				N/A	N/A	N/A
1 1 Classroom 101 1 1 Classroom 101	N/A N/A	Plaster Wall Partition Room Dividers		NAD Nan Support ACM	1080 290	SF SF	0	SF SF		Wood	_	N/A N/A	N/A N/A	N/A N/A
1 1 Classroom 101	N/A	Wood Floor		Non Suspect ACM Non Suspect ACM	792	SF	0	SF		VVOOd	-	N/A	N/A	N/A
1 1 Classroom 101	M	Blackboard Glue Dots	6260/01/01/AET/BB/2600	Assumed	90	SF	0	SF				1	No	1/D
1 1 Classroom 101 Closet	Т	Pipe Insulation 2-6 inch	6260/01/01/09	Confirmed	12	LF	0	LF		More insulation is likely present above ceiling tiles		1	No	1/D
1 1 Classroom 101 Closet	N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	100	SF	0	SF				N/A	N/A	N/A
1 1 Classroom 101 Closet	N/A	Plaster Ceiling		NAD	100	SF	0	SF				N/A	N/A	N/A
1 1 Classroom 101 Closet	N/A	Plaster Wall		NAD	600	SF	0	SF				N/A	N/A	N/A
1 1 Classroom 101 Closet	N/A	Wood Floor		Non Suspect ACM	100	SF	0	SF				N/A	N/A	N/A
1 1 Classroom 102	T	Pipe Insulation 2-6 inch	6260/01/01/09	Confirmed	48	LF	1	LF		Was DDC written for this damage?		1	No	2/B
1 1 Classroom 102	N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	875	SF	0	SF				N/A	N/A	N/A
1 1 Classroom 102	N/A N/A	Plaster Ceiling Plaster Wall		NAD NAD	875 1065	SF SF	0	SF SF				N/A N/A	N/A N/A	N/A N/A
1 1 Classroom 102 1 1 Classroom 102	N/A N/A	Plaster Wall Partition Room Dividers		Non Suspect ACM	350	SF	0	SF	_	Wood	_	N/A N/A	N/A N/A	N/A N/A
1 1 Classroom 102	N/A	Wood Floor		Non Suspect ACM	875	SF	0	SF		11000	_	N/A	N/A	N/A
1 1 Classroom 102	M	Blackboard Glue Dots	6260/01/01/AET/BB/2600	Assumed	80	SF	0	SF				1	No	1/D
1 1 Classroom 102 Closet	N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	80	SF	0	SF				N/A	N/A	N/A
1 1 Classroom 102 Closet	N/A	Plaster Ceiling		NAD	80	SF	0	SF				N/A	N/A	N/A
1 1 Classroom 102 Closet	N/A	Plaster Wall		NAD	445	SF	0	SF				N/A	N/A	N/A
1 1 Classroom 102 Closet	N/A	Concrete Block Wall		Non Suspect ACM	60	SF	0	SF				N/A	N/A	N/A
1 1 Classroom 102 Closet	N/A	Wood Floor		Non Suspect ACM	80	SF	0	SF				N/A	N/A	N/A
1 1 Copy Room 103A	T	Pipe Fitting Insulation	6260/01/01/21	Confirmed	9	EA	0	EA		More insulation is likely present above ceiling tiles		1	No	1/D
1 1 Copy Room 103A	Т	Pipe Insulation 2-6 inch	6260/01/01/09	Confirmed	34	LF	0	LF		More insulation is likely present above ceiling tiles		1	No	1/D
1 1 Copy Room 103A	N/A	Plaster Ceiling		NAD	180	SF	25	SF				N/A	N/A	N/A
1 1 Copy Room 103A	N/A M	Plaster Wall Floor Tile VAT 12" x 12"	6260/01/01/NN	NAD Assumed	675 180	SF SF	2	SF SF	Tan		_	N/A 1	N/A No	N/A 6/C
1 1 Copy Room 103A 1 1 Copy Room 103A	N/A	Wood Floor	6260/01/01/NN	Non Suspect ACM	180	SF	0	SF	Tall		_	N/A	N/A	N/A
1 1 Copy Room 103A Restroom	N/A	Concrete Ceiling		Non Suspect ACM	16	SF	0	SF				N/A	N/A	N/A
1 1 Copy Room 103A Restroom	N/A	Plaster Wall		NAD NAD	195	SF	0	SF				N/A	N/A	N/A
1 1 Copy Room 103A Restroom	N/A	Ceramic Tile Wall		Non Suspect ACM	195	SF	0	SF				N/A	N/A	N/A
1 1 Copy Room 103A Restroom	N/A	Ceramic Tile Floor		Non Suspect ACM	16	SF	0	SF				N/A	N/A	N/A
1 1 Classroom 103	T	Pipe Insulation 2-6 inch	6260/01/01/09	Confirmed	48	LF	0	LF		More insulation is likely present above ceiling tiles		1	No	1/D
1 1 Classroom 103	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	35	LF	1	LF		More insulation is likely present above ceiling tiles		N/A	N/A	N/A
1 1 Classroom 103	N/A	Ceiling Tile 2' x 4'		Non Suspect ACM	870	SF	0	SF				N/A	N/A	N/A
1 1 Classroom 103	N/A	Plaster Ceiling		NAD	870	SF	0	SF				N/A	N/A	N/A
1 1 Classroom 103	N/A	Plaster Wall		NAD	1065	SF	0	SF			_	N/A	N/A	N/A
1 1 Classroom 103	N/A	Partition Room Dividers		Non Suspect ACM	350	SF	0	SF		Wood		N/A	N/A	N/A
1 1 Classroom 103	N/A	Wood Floor		Non Suspect ACM	870	SF	20	SF		Possible buckling under area carpet		N/A	N/A	N/A
1 1 Classroom 103	м	Blackboard Glue Dots	6260/01/01/AET/BB/2600	Assumed	90	SF	0	SF				1	No	1/D
1 1 Classroom 103 Closet	T	Pipe Insulation 2-6 inch	6260/01/01/09	Confirmed	16	LF	0	LF		More insulation is likely present above ceiling tiles	_	1	No	1/D
1 1 Classroom 103 Closet	N/A	Fiberglass Ceiling Tile 2' x 4'	0200101101103	Non Suspect ACM	100	SF	0	SF		more modiation to intery present above ceiling tiles		N/A	N/A	N/A
1 1 Classroom 103 Closet	N/A	Plaster Ceiling		NAD NAD	100	SF	0	SF				N/A	N/A	N/A
1 1 Classroom 103 Closet	N/A	Plaster Wall		NAD	600	SF	0	SF				N/A	N/A	N/A
1 1 Classroom 103 Closet 1 1 Classroom 103 Closet	N/A N/A				100	SF	0	SF				N/A N/A	N/A N/A	N/A N/A
1 1 Classroom 103 Closet 1 1 Classroom 104	N/A T	Wood Floor Pipe Insulation 2-6 inch	6260/01/01/09	Non Suspect ACM Confirmed	36	I F	0	I F		More insulation is likely present above ceiling tiles	_	IN/A	N/A No	1/D
1 1 Classroom 104	N/A	Fiberglass Pipe Insulation	0200,01101100	Non Suspect ACM	31	LF	1	LF				N/A	N/A	N/A
1 1 Classroom 104	N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	812	SF	Ö	SF				N/A	N/A	N/A
1 1 Classroom 104	N/A	Plaster Ceiling		NAD	812	SF	0	SF				N/A	N/A	N/A
1 1 Classroom 104	N/A	Plaster Wall Partition Room Dividers		NAD Nan Support ACM	1045	SF SF	0	SF SF		Wood		N/A	N/A N/A	N/A
1 1 Classroom 104 1 1 Classroom 104	N/A N/A	Wood Floor		Non Suspect ACM Non Suspect ACM	350 812	SF	0	SF	_	Wood	_	N/A N/A	N/A N/A	N/A N/A
1 1 Classroom 104	M	Blackboard Glue Dots	6260/01/01/AET/BB/2600	Assumed	115	SF	0	SF				1	No	1/D
1 1 Classroom 104 Closet	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	4	LF	0	LF				N/A	N/A	N/A
1 1 Classroom 104 Closet	N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	100	SF	0	SF				N/A	N/A	N/A
1 1 Classroom 104 Closet	N/A	Plaster Ceiling		NAD	100	SF	0	SF				N/A	N/A	N/A
1 1 Classroom 104 Closet	N/A	Plaster Wall		NAD	600	SF	0	SF				N/A	N/A	N/A
1 1 Classroom 104 Closet	N/A	Wood Floor		Non Suspect ACM	100	SF	0	SF				N/A	N/A	N/A
Hallway Closet adjacent to Main Office	T	Pipe Insulation > 6 inch	6260/01/01/FF	Confirmed	7	LF	0	LF				1 1	No No	1/D
Hallway Closet adjacent to Main Office Hallway Closet adjacent to Main Office	N/A	Pipe insulation > 6 inch Plaster Ceiling	0200/01/01/FF	NAD	6	SF	0	SF				N/A	N/A	N/A
Hallway Closet adjacent to Main Office Hallway Closet adjacent to Main Office	N/A N/A				50	SF	0				+	N/A N/A		
		Plaster Wall		NAD Nan Sunnant ACM				SF	_	Dear in hallway	_		N/A N/A	N/A
1 1 Hallway Closet adjacent to Main Office 1 1 Main Office 105	N/A T	Cement Floor Pipe Fitting Insulation	6260/01/01/21	Non Suspect ACM Confirmed	6 2	SF EA	0	SF EA	_	Door in hallway More insulation is likely present above ceiling tiles	_	N/A	N/A No	1/D
1 1 Main Office 105	†	Pipe Insulation 2-6 inch	6260/01/01/09	Confirmed	36	LF	0	LF		More insulation is likely present above ceiling tiles		1	No	1/D
1 1 Main Office 105	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	2	LF	0	LF		,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,		N/A	N/A	N/A
1 1 Main Office 105	N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	420	SF	0	SF				N/A	N/A	N/A
1 1 Main Office 105	N/A	Plaster Ceiling		NAD	420	SF	0	SF				N/A	N/A	N/A

	School District of Philadelphia		AH	IERA Three-Year Reins	pection 2015-2016						Reinspection Date: 10/8/2015				
	Henry H. Houston Elementary School (K-8)			Room by Room Locati	ion Log Report						Building Inspector: Bernard Brunner	1			
	7300 Rural Lane, Philadelphia, PA 19119	1						,			Certificate Number: 45397	_			
	ULCS# 6260											-			
											Management Planner: Monique Causley	-			
	Year Built: 1927										Certificate Number: ACC-0215-8-010			,	
E			i				1								
e F m I e o			1							Color				Newly	
e o		System	1		Confirmed, Assumed, NAD.	Amount of	SF LF	Amount of	SF LF	required		Attic Crawl Space	Damage Potential	Friable	Response
t r	On Site Room Name	Affected	Material Description	HID#	Non Suspect ACM	Material	EA	Damage	EA	for VAT	Comments/Description/Notes	Ranking	(DP)	(NF)	Action (RA)
1 1	Main Office 105	N/A	Plaster Wall		NAD	1080	SF SF	0	SF				N/A	N/A	N/A
1 1	Main Office 105	M	Floor Tile VAT 12" x 12"	6260/01/01/NN	Assumed	420		0	SF	Blue			1	No	1/D
	Main Office 105	N/A	Wood Floor		Non Suspect ACM	420	SF	0	SF			$\overline{}$	N/A	N/A	N/A
1 1	Main Office Large Closet	N/A	Plaster Ceiling		NAD	45	SF	0	SF				N/A	N/A	N/A
1 1	Main Office Large Closet	N/A	Plaster Wall		NAD	280	SF	0	SF				N/A	N/A	N/A
1 1	Main Office Large Closet	M	Floor Tile VAT 12" x 12"	6260/01/01/NN	Assumed	45	SF	0	SF	Pink			1	No	1/D
	Main Office Large Closet	N/A	Wood Floor		Non Suspect ACM	45	SF	0	SF				N/A	N/A	N/A
	Main Office Small Closet	N/A	Plaster Ceiling		NAD	10	SF	0	SF				N/A	N/A	N/A
	Main Office Small Closet	N/A	Plaster Wall		NAD	80	SF	0	SF				N/A	N/A	N/A
	Main Office Small Closet	M M	Floor Tile VAT 12" x 12"	6260/01/01/NN	Assumed	10	SF	0	SF	Pink		+	1 1	No.	1/D
				6260/01/01/NN						PILIK		+			
	Main Office Small Closet	N/A	Wood Floor		Non Suspect ACM	10	SF	0	SF			+	N/A	N/A	N/A
	Principal's Office	T	Pipe Insulation 2-6 inch	6260/01/01/09	Confirmed	24	LF	0	LF		More insulation is likely present above ceiling tiles	+	1	No	1/D
	Principal's Office	N/A	Fiberglass Ceiling Tile 2' x 4'	 	Non Suspect ACM	308	SF	0	SF				N/A	N/A	N/A
	Principal's Office	N/A	Plaster Ceiling	<u> </u>	NAD	308	SF	0	SF				N/A	N/A	N/A
1 1	Principal's Office	N/A	Plaster Wall		NAD	940	SF	0	SF				N/A	N/A	N/A
1 1	Principal's Office	N/A	Wood Floor		Non Suspect ACM	308	SF	0	SF				N/A	N/A	N/A
	Principal's Office Restroom	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	3	LF	0	LF				N/A	N/A	N/A
	Principal's Office Restroom	N/A	Plaster Ceiling		NAD	18	SF	0	SF			1	N/A	N/A	N/A
	Principal's Office Restroom	N/A	Plaster Wall		NAD	110	SF	0	SF			\top	N/A	N/A	N/A
	Principal's Office Restroom	N/A	Ceramic Tile Wall		Non Suspect ACM	110	SF	0	SF			+	N/A	N/A	N/A
							SF								
1 1	Principal's Office Restroom Classroom 106	N/A	Ceramic Tile Floor Pipe Insulation 2-6 inch	6260/01/01/09	Non Suspect ACM Confirmed	18 48	LF	0	SF LF		More insulation is likely present above ceiling tiles		N/A	N/A No	N/A 1/D
1 1	Classroom 106	N/A	Fiberglass Ceiling Tile 2' x 4'	6260/01/01/09	Non Suspect ACM	812	SF	0	SF		infore insulation is likely present above ceiling tiles		N/A	N/A	N/A
1 1	Classroom 106	N/A	Plaster Ceiling		NAD	812	SF	0	SF				N/A	N/A	N/A
1 1	Classroom 106	N/A	Plaster Wall		NAD	1395	SF	0	SF				N/A	N/A	N/A
1 1	Classroom 106	N/A	Wood Floor		Non Suspect ACM	812	SF	0	SF				N/A	N/A	N/A
	Classroom 106	M	Blackboard Glue Dots	6260/01/01/AET/BB/2600	Assumed	190	SF	0	SF				1	No	1/D
1 1	Classroom 106 Closet	T	Pipe Insulation 2-6 inch	6260/01/01/09	Confirmed	16	LF	0	LF		More insulation is likely present above ceiling tiles		1	No	1/D
1 1	Classroom 106 Closet	N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	100	SF	0	SF				N/A	N/A	N/A
	Classroom 106 Closet	N/A	Plaster Ceiling		NAD	100	SF	0	SF				N/A	N/A	N/A
	Classroom 106 Closet	N/A	Plaster Wall		NAD	600	SF	0	SF				N/A	N/A	N/A
	Classroom 106 Closet	N/A	Wood Floor		Non Suspect ACM	100	SF	0	SF.			+	N/A	N/A	N/A
1 1	Girl's Restroom	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	15	I.F.	0	LF			+	N/A	N/A	N/A
1 1	Girl's Restroom	N/A	Plaster Ceiling		NAD	180	SF	Ö	SF				N/A	N/A	N/A
1 1	Girl's Restroom	N/A	Plaster Wall		NAD	600	SF	0	SF				N/A	N/A	N/A
	Girl's Restroom	N/A	Ceramic Tile Wall		Non Suspect ACM	600	SF	0	SF				N/A	N/A	N/A
	Girl's Restroom	N/A	Ceramic Tile Floor		Non Suspect ACM	180	SF	0	SF				N/A	N/A	N/A
1 1	Girl's Restroom Pipe Chase	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	30	LF	0	LF				N/A	N/A	N/A
1 1	Girl's Restroom Pipe Chase	N/A	Concrete Ceiling		Non Suspect ACM	40	SF	0	SF				N/A	N/A	N/A
1 1	Girl's Restroom Pipe Chase	N/A	Plaster Wall		NAD	265	SF	0	SF				N/A	N/A	N/A
	Girl's Restroom Pipe Chase	N/A	Concrete Block Wall		Non Suspect ACM	265	SF	0	SF				N/A	N/A	N/A
	Girl's Restroom Pipe Chase	N/A	Cement Floor		Non Suspect ACM	40	SF	0	SF				N/A	N/A	N/A
	Custodial Closet next to Girl's Restroom	X	X	1	X	X	Y	X	Y	X	No Access	1	X	Y	1 .v
1 1	Classroom 107	1 î	Pipe Insulation 2-6 inch	6260/01/01/09	Confirmed	48	LF	0	LF	_^	More insulation is likely present above ceiling tiles	+	1	No.	1/D
1 1	Classroom 107	N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	720	SF	2	SF				N/A	N/A	N/A
1 1	Classroom 107	N/A	Plaster Ceiling		NAD	720	SF	0	SF				N/A	N/A	N/A
	Classroom 107	N/A	Plaster Wall		NAD	1010	SF	0	SF				N/A	N/A	N/A
1 1	Classroom 107	N/A	Partition Room Dividers		Non Suspect ACM	290	SF	0	SF		Wood		N/A	N/A	N/A
1 1	Classroom 107	N/A N/A	Wood Floor		Non Suspect ACM	720	SF SF	0	SF SF			+	N/A	N/A N/A	N/A
	Classroom 107 Classroom 107	N/A M	Carpet Blackboard Glue Dots	6260/01/01/AET/BB/2600	Non Suspect ACM Assumed	265 90	SF	0	SF			+	N/A	N/A No	N/A 1/D
	Classroom 107 Closet	N/A	Concrete Ceiling	3200/01/01/AE1/BB/2000	Non Suspect ACM	70	SF	0	SF			+	N/A	N/A	N/A
				+								+			
	Classroom 107 Closet	N/A	Plaster Wall		NAD	400	SF	0	SF			+	N/A	N/A	N/A
	Classroom 107 Closet	N/A	Concrete Block Wall		Non Suspect ACM	60	SF	0	SF			+	N/A	N/A	N/A
	Classroom 107 Closet	N/A	Wood Floor	+	Non Suspect ACM	70	SF	0	SF				N/A	N/A	N/A
	Classroom 107 Restroom	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	4	LF	0	LF				N/A	N/A	N/A
	Classroom 107 Restroom	N/A	Concrete Ceiling		Non Suspect ACM	40	SF	0	SF				N/A	N/A	N/A
	Classroom 107 Restroom	N/A	Plaster Wall	[NAD	260	SF	0	SF				N/A	N/A	N/A
	Classroom 107 Restroom	N/A	Ceramic Tile Wall		Non Suspect ACM	260	SF	0	SF				N/A	N/A	N/A
1 1	Classroom 107 Restroom	N/A	Ceramic Tile Floor		Non Suspect ACM	40	SF	0	SF			1	N/A	N/A	N/A
	Classroom 108	T	Pipe Insulation 2-6 inch	6260/01/01/09	Confirmed	36	LF	0	LF		More insulation is likely present above ceiling tiles	_	1	No	1/D
1 1	Classroom 108	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	12	LF	5	LF				N/A	N/A	N/A
1 1		1 2000	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	720	SF	12	SF				N/A	N/A	N/A
1 1 1 1 1 1	Classroom 108	N/A													
1 1 1 1 1 1	Classroom 108 Classroom 108	N/A	Plaster Ceiling		NAD	720	SF	0	SF				N/A	N/A	N/A
1 1 1 1 1 1 1 1 1 1	Classroom 108 Classroom 108 Classroom 108	N/A N/A	Plaster Ceiling Plaster Wall		NAD NAD	720 1010	SF	5	SF		West	_	N/A	N/A	N/A
1 1 1 1 1 1 1 1 1 1 1 1	Classroom 108 Classroom 108	N/A	Plaster Ceiling		NAD	720		0 5 0	SF SF SF		Wood	#			

	School District of Philadelphia		АН	ERA Three-Year Reins	pection 2015-2016						Reinspection Date: 10/8/2015				
	Henry H. Houston Elementary School (K-8)			Room by Room Locati							Building Inspector: Bernard Brunner				
	7300 Rural Lane, Philadelphia, PA 19119	1		•	-			•			Certificate Number: 45397				
	ULCS# 6260										Management Planner: Monique Causley	7			
	Year Built: 1927										Certificate Number: ACC-0215-8-010				
E	Tear Bant. 1327										Octanicate Namber: AOO-0210-0-010	+			T
e F m I e c										Color		Attic Crawl	Damage	Newly	
n c	On Site Room Name	System Affected	Material Description	HID#	Confirmed, Assumed, NAD, Non Suspect ACM	Amount of Material	SF LF EA	Amount of	SF LF EA	required for VAT	Comments/Description/Notes	Space	Potential (DP)	Friable (NF)	Response Action (RA)
	Classroom 108	M	Blackboard Glue Dots	6260/01/01/AET/BB/2600	Assumed	40	SF	Damage 0	SF	IOI VAI	Comments/Description/Notes	Ranking	(DP)	No No	1/D
	Classroom 108 Closet	Т	Pipe Insulation 2-6 inch	6260/01/01/09	Confirmed	12	LF	0	LF		More insulation is likely present above ceiling tiles		1	No	1/D
1 1	Classroom 108 Closet	N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	120	SF	0	SF		,		N/A	N/A	N/A
1 1	Classroom 108 Closet	N/A	Plaster Ceiling		NAD	120	SF	0	SF				N/A	N/A	N/A
1 1	Classroom 108 Closet	N/A	Plaster Wall		NAD	700	SF	0	SF				N/A	N/A	N/A
	Classroom 108 Closet	N/A	Wood Floor		Non Suspect ACM	120	SF	0	SF				N/A	N/A	N/A
1 1	Classroom 109	T N/A	Pipe Insulation 2-6 inch	6260/01/01/09	Confirmed	45 18	LF	0	LF		More insulation is likely present above ceiling tiles		N/A	No N/A	1/D N/A
1 1	Classroom 109 Classroom 109	N/A N/A	Fiberglass Pipe Insulation Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM Non Suspect ACM	1360	LF SF	0	SF				N/A N/A	N/A N/A	N/A N/A
1 1	Classroom 109	N/A	Plaster Ceiling		NAD	1360	SF	0	SF				N/A	N/A	N/A
	Classroom 109	N/A	Plaster Wall		NAD	1225	SF	0	SF				N/A	N/A	N/A
1 1	Classroom 109 Classroom 109	M N/A	Floor Tile VAT 12" x 12" Wood Floor	6260/01/01/NN	Assumed Non Suspect ACM	1360 1360	SF SF	0	SF SF	Multi		+	N/A	No N/A	6/C N/A
1 1	Classroom 109	M M	Blackboard Glue Dots	6260/01/01/AET/BB/2600	Assumed	70	SF	0	SF			\pm	1	No	1/D
	Classroom 109 Large Closet	N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	80	SF	0	SF				N/A	N/A	N/A
	Classroom 109 Large Closet	N/A	Plaster Ceiling		NAD	80	SF	0	SF				N/A	N/A	N/A
1 1	Classroom 109 Large Closet	N/A	Plaster Wall		NAD	445	SF	0	SF				N/A	N/A	N/A
1 1	Classroom 109 Large Closet	N/A	Wood Floor		Non Suspect ACM	80	SF	0	SF				N/A	N/A	N/A
1 1	Classroom 109 Restroom	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	13	LF	0	LF				N/A	N/A	N/A
	Classroom 109 Restroom	N/A	Plaster Ceiling		NAD	60	SF	0	SF				N/A	N/A	N/A
	Classroom 109 Restroom	N/A	Ceramic Tile Wall		Non Suspect ACM	240	SF	0	SF				N/A	N/A	N/A
	Classroom 109 Restroom	N/A	Ceramic Tile Floor		Non Suspect ACM	60	SF	0	SF				N/A	N/A	N/A
	Classroom 109 Small Closet adjacent to Restroom	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	3	LF	0	LF				N/A	N/A	N/A
	Classroom 109 Small Closet adjacent to Restroom	N/A	Plaster Ceiling		NAD	48	SF	0	SF				N/A	N/A	N/A
	Classroom 109 Small Closet adjacent to Restroom	N/A	Plaster Wall		NAD	200	SF	0	SF				N/A	N/A	N/A
	Classroom 109 Small Closet adjacent to Restroom	N/A	Wood Floor		Non Suspect ACM	48	SF	0	SF				N/A	N/A	N/A
	Stairwell next to Classroom 101	N/A	Concrete Ceiling		Non Suspect ACM	180	SF	0	SF			-	N/A	N/A	N/A
	Stairwell next to Classroom 101	N/A	Brick Wall		Non Suspect ACM	1120	SF	0	SF			_	N/A	N/A	N/A
	Stainwell next to Classroom 101	N/A	Cement Floor	0000/04/04/00	Non Suspect ACM	180	SF	0	SF		Manada da Maria da Maria da Maria da Maria da Maria de Ma	+	N/A	N/A	N/A
	Hallway outside Classrooms 101-102 Hallway outside Classrooms 101-102	T N/A	Pipe Insulation 2-6 inch Fiberglass Ceiling Tile 2' x 4'	6260/01/01/09	Confirmed Non Suspect ACM	48 560	LF SF	0	LF SF		More insulation is likely present above ceiling tiles	+	1 N/A	No N/A	1/D N/A
	Hallway outside Classrooms 101-102	N/A	Plaster Ceiling		NAD NAD	560	SF	0	SF				N/A	N/A	N/A
	Hallway outside Classrooms 101-102	N/A	Plaster Wall		NAD	1780	SF	0	SF				N/A	N/A	N/A
	Hallway outside Classrooms 101-102	N/A	Marble Wall		Non Suspect ACM	595	SF	0	SF			1	N/A	N/A	N/A
	Hallway outside Classrooms 101-102	N/A	Cement Floor		Non Suspect ACM	560	SF	0	SF				N/A	N/A	N/A
	Hallway outside Classrooms 103-106	N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	1105	SF	0	SF				N/A	N/A	N/A
	Hallway outside Classrooms 103-106	N/A	Plaster Ceiling		NAD	1105	SF	0	SF				N/A	N/A	N/A
	Hallway outside Classrooms 103-106	N/A	Plaster Wall		NAD	2260	SF	0	SF				N/A	N/A	N/A
	Hallway outside Classrooms 103-106	N/A	Marble Wall		Non Suspect ACM	755	SF	0	SF				N/A	N/A	N/A
	Hallway outside Classrooms 103-106	N/A	Cement Floor		Non Suspect ACM	1105	SF	0	SF				N/A	N/A	N/A
1 1	Stairwell B	T	Pipe Fitting Insulation	6260/01/01/21	Confirmed	5	EA	0	EA				1	No	1/D
1 1	Stairwell B	T	Pipe Insulation 2-6 inch	6260/01/01/09	Confirmed	5	LF	0	LF				1	No	1/D
	Stairwell B	N/A	Plaster Ceiling		NAD	240	SF	100	SF				N/A	N/A	N/A
	Stainwell B	N/A	Plaster Wall		NAD	1360	SF	20	SF				N/A	N/A	N/A
	Stairwell B	N/A	Marble Wall		Non Suspect ACM	455	SF	0	SF				N/A	N/A	N/A
	Stairwell B	N/A	Cement Floor		Non Suspect ACM	240	SF	0	SF				N/A	N/A	N/A
	Main Entrance Stairwell	N/A	Plaster Ceiling		NAD	420	SF	0	SF	-		+	N/A	N/A	N/A
	Main Entrance Stairwell	N/A	Plaster Wall		NAD	1500	SF	0	SF			_	N/A	N/A	N/A
	Main Entrance Stairwell	N/A	Terazzo Floor	0000/01/01/01	Non Suspect ACM	420	SF	0	SF	-		+	N/A	N/A	N/A
	Stairwell A Stairwell A	T	Pipe Fitting Insulation	6260/01/01/21 6260/01/01/09	Confirmed Confirmed	4	EA LF	0	EA	_		+	1 1	No	1/D 1/D
	Stairwell A Stairwell A	N/A	Pipe Insulation 2-6 inch Plaster Ceiling	6260/01/01/09	NAD	240	SF	100	LF SF	_		+	1 N/A	No N/A	N/A
	Stairwell A Stairwell A	N/A N/A	Plaster Ceiling Plaster Wall		NAD NAD	1360	SF	20	SF			+	N/A N/A	N/A N/A	N/A N/A
	Stainwell A	N/A N/A	Marble Wall		Non Suspect ACM	455	SF	0	SF				N/A N/A	N/A N/A	N/A N/A
	Stairwell A	N/A	Cement Floor		Non Suspect ACM	240	SF	0	SF				N/A	N/A	N/A
	Hallway outside Classrooms 107-108	T	Pipe Insulation 2-6 inch	6260/01/01/09	Confirmed	36	LF	0	LF		More insulation is likely present above ceiling tiles		1	No	1/D
	Hallway outside Classrooms 107-108	N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	560	SF	0	SF		uporo coming mos		N/A	N/A	N/A
	Hallway outside Classrooms 107-108	N/A	Plaster Ceiling		NAD	560	SF	0	SF				N/A	N/A	N/A
	Hallway outside Classrooms 107-108	N/A	Plaster Wall		NAD	1780	SF	0	SF				N/A	N/A	N/A
	Hallway outside Classrooms 107-108	N/A	Marble Wall		Non Suspect ACM	595	SF	0	SF				N/A	N/A	N/A
	Hallway outside Classrooms 107-108	N/A	Cement Floor		Non Suspect ACM	560	SF	0	SF				N/A	N/A	N/A
	Fire Tower adjacent to Classroom 108	N/A	Concrete Ceiling		Non Suspect ACM	240	SF	0	SF				N/A	N/A	N/A
	Fire Tower adjacent to Classroom 108	N/A	Brick Wall	-	Non Suspect ACM	1360	SF	0	SF				N/A	N/A	N/A
_11	THE TOWER adjacent to classicom 100					1300							1407		

	School District of Philadelphia		AH	IERA Three-Year Reins	ection 2015-2016						Reinspection Date: 10/8/2015				
	Henry H. Houston Elementary School (K-8)			Room by Room Locati	on Log Report						Building Inspector: Bernard Brunner				
	7300 Rural Lane, Philadelphia, PA 19119										Certificate Number: 45397				
	ULCS# 6260										Management Planner: Monique Causley				
	Year Built: 1927										Certificate Number: ACC-0215-8-010				
E															
e F															
m I															
e o						l	SF LF	Amount of	SF LF	Color		Attic Crawl	Damage	Newly	_
n o	On Site Room Name	System Affected	Material Description	HID#	Confirmed, Assumed, NAD, Non Suspect ACM	Amount of Material	EA EA	Damage	SF LF EA	required for VAT	Comments/Description/Notes	Space Ranking	Potential (DP)	Friable (NF)	Response Action (RA)
	1st Floor Element 2 Boy's Restroom	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	4	LF	0	LF		,		N/A	N/A	N/A
	1st Floor Element 2 Boy's Restroom 1st Floor Element 2 Boy's Restroom	N/A N/A	Concrete Ceiling Concrete Block Wall		Non Suspect ACM Non Suspect ACM	112 440	SF SF	0	SF SF				N/A N/A	N/A N/A	N/A N/A
1 1	1st Floor Element 2 Boy's Restroom 1st Floor Element 2 Boy's Restroom	N/A N/A	Ceramic Tile Wall		Non Suspect ACM Non Suspect ACM	440	SF	0	SF			+	N/A N/A	N/A N/A	N/A N/A
	1st Floor Element 2 Boy's Restroom	M	Transite Sills	6260/01/01/AET/BB/2300	Assumed	1	SF	0	SF				1	No	1/D
1 1	1st Floor Element 2 Boy's Restroom	N/A	Ceramic Tile Floor		Non Suspect ACM	112	SF	0	SF				N/A	N/A	N/A
	Hallway Pipe Chase adjacent to 1st Floor Element 2 Boy's														
1 1	Restroom	X	X		X	X	X	X	X	X	No Access	_	X	X	+ X
	Custodial Closet adjacent to Element 2 Staff Restroom	X N/A	X Fiberalese Dine Insulation		X Non Suspect ACM	X	LF	X 0	LF	X		+	X N/A		X
	1st Floor Element 2 Staff Restroom 1st Floor Element 2 Staff Restroom	N/A N/A	Fiberglass Pipe Insulation Concrete Ceiling		Non Suspect ACM	5 90	SF	0	SF			_	N/A	N/A N/A	N/A N/A
1 1	1st Floor Element 2 Staff Restroom	N/A	Concrete Block Wall		Non Suspect ACM	380	SF	0	SF				N/A	N/A	N/A
1 1	1st Floor Element 2 Staff Restroom	N/A M	Ceramic Tile Wall	6260/01/01/AET/BB/2300	Non Suspect ACM	380	SF SF	0	SF SF				N/A 1	N/A	N/A
1 1	1st Floor Element 2 Staff Restroom 1st Floor Element 2 Staff Restroom	N/A	Transite Sills Ceramic Tile Floor	6260/01/01/AE1/BB/2300	Assumed Non Suspect ACM	90	SF	0	SF			_	N/A	No N/A	1/D N/A
1 1	Nurse's Office	T	Pipe Fitting Insulation	6260/01/01/21	Confirmed	4	EA	0	EA				1	No	1/D
	Nurse's Office	T	Pipe Insulation 2-6 inch	6260/01/01/09	Confirmed	16	LF SF	0	LF SF				1	No	1/D
1 1	Nurse's Office Nurse's Office	N/A N/A	Concrete Ceiling Concrete Block Wall		Non Suspect ACM Non Suspect ACM	270 740	SF	0	SF	<u> </u>		+	N/A N/A	N/A N/A	N/A N/A
1 1	Nurse's Office	M	Transite Sills	6260/01/01/AET/BB/2300	Assumed	4	SF	0	SF				1	No	1/D
	Nurse's Office	M	Transite Stalls	6260/01/01/AET/BB/2310	Assumed	44	SF	0	SF	T			1	No	1/D
	Nurse's Office Nurse's Office	M N/A	Floor Tile VAT 12" x 12" Cement Floor	6260/01/01/NN	Assumed Non Suspect ACM	270 270	SF SF	0	SF SF	Tan			1 N/A	No N/A	1/D N/A
	Nurse's Office Exam Room	T	Pipe Fitting Insulation	6260/01/01/21	Confirmed	2	EA	0	EA				1	No	1/D
	Nurse's Office Exam Room	T	Pipe Insulation 2-6 inch	6260/01/01/09	Confirmed	7	LF	0	LF				1	No	1/D
	Nurse's Office Exam Room	N/A	Concrete Ceiling		Non Suspect ACM	130	SF	0	SF				N/A	N/A	N/A
	Nurse's Office Exam Room	N/A	Concrete Block Wall		Non Suspect ACM	460	SF	0	SF				N/A	N/A	N/A
	Nurse's Office Exam Room	M	Transite Sills	6260/01/01/AET/BB/2300	Assumed	2	SF	0	SF				1	No	1/D
1 1	Nurse's Office Exam Room	М	Floor Tile VAT 12" x 12"	6260/01/01/NN	Assumed	130	SF	0	SF	Tan			1	No	1/D
1 1	Nurse's Office Exam Room	N/A	Cement Floor		Non Suspect ACM	130	SF	0	SF				N/A	N/A	N/A
	Nurse's Office Closet	N/A	Concrete Ceiling		Non Suspect ACM	6	SF	0	SF				N/A	N/A	N/A
	Nurse's Office Closet	N/A	Concrete Block Wall		Non Suspect ACM	100	SF	0	SF				N/A	N/A	N/A
	Nurse's Office Closet	M	Floor Tile VAT 12" x 12"	6260/01/01/NN	Assumed	6	SF	0	SF	Tan			1	No	1/D
	Nurse's Office Closet School Psychologist Office adjacent to Nurse's Office	N/A N/A	Cement Floor Concrete Ceiling		Non Suspect ACM Non Suspect ACM	100	SF SF	0	SF SF			-	N/A N/A	N/A N/A	N/A N/A
1 1	School Psychologist Office adjacent to Nurse's Office	N/A	Concrete Block Wall		Non Suspect ACM	400	SF	0	SF			_	N/A	N/A	N/A
1 1	School Psychologist Office adjacent to Nurse's Office	M	Floor Tile VAT 12" x 12"	6260/01/01/NN	Assumed	100	SF	0	SF	Tan			1	No	1/D
	School Psychologist Office adjacent to Nurse's Office Counselor's Office	N/A	Cement Floor Pipe Fitting Insulation	6260/01/01/21	Non Suspect ACM Confirmed	100	SF EA	0	SF EA			_	N/A 1	N/A No	N/A 1/D
	Counselor's Office	Ť	Pipe Insulation 2-6 inch	6260/01/01/09	Confirmed	15	LF	0	LF			_	1	No	1/D
1 1	Counselor's Office	N/A	Concrete Ceiling		Non Suspect ACM	245	SF	0	SF				N/A	N/A	N/A
1 1	Counselor's Office Counselor's Office	N/A M	Concrete Block Wall Transite Sills	6260/01/01/AET/BB/2300	Non Suspect ACM Assumed	740	SF SF	0	SF SF				N/A 1	N/A No	N/A 1/D
	Counselor's Office	M	Floor Tile VAT 12" x 12"	6260/01/01/NN	Assumed	245	SF	0	SF	Tan			1	No	1/D
	Counselor's Office	N/A	Cement Floor		Non Suspect ACM	245	SF	0	SF				N/A	N/A	N/A
	Counselor's Office Restroom	N/A	Concrete Ceiling		Non Suspect ACM	24	SF	0	SF				N/A	N/A	N/A
	Counselor's Office Restroom	N/A	Concrete Block Wall		Non Suspect ACM	200	SF	0	SF				N/A	N/A	N/A
	Counselor's Office Restroom	N/A	Ceramic Tile Wall	000010410415============================	Non Suspect ACM	200	SF	0	SF				N/A	N/A	N/A
	Counselor's Office Restroom Counselor's Office Restroom	M N/A	Transite Sills Ceramic Tile Floor	6260/01/01/AET/BB/2300	Assumed No. A CM	1 24	SF SF	0	SF SF	-		+	1 N/A	No N/A	1/D N/A
1 1	Counselor's Office Restroom Classroom 111	N/A T	Pipe Fitting Insulation	6260/01/01/21	Non Suspect ACM Confirmed	8	EA EA	0	EA EA			+	N/A 1	N/A No	1/D
1 1	Classroom 111	Ť	Pipe Insulation 2-6 inch	6260/01/01/09	Confirmed	30	LF	0	LF				i	No	1/D
1 1	Classroom 111	N/A	Concrete Ceiling		Non Suspect ACM	825	SF SF	0	SF				N/A	N/A	N/A
	Classroom 111 Classroom 111	N/A M	Concrete Block Wall Transite Closet	6260/01/01/DD	Non Suspect ACM Assumed	1150 30	SF SF	0	SF SF			+	N/A 1	N/A No	N/A 1/D
1 1	Classroom 111	M	Transite Sills	6260/01/01/AET/BB/2300	Assumed	12	SF	0	SF				1	No	1/D
1 1	Classroom 111	M	Floor Tile VAT 9" x 9"	6260/01/01/12	Confirmed	661	SF	0	SF	Grey			1	No	1/D
	Classroom 111	M	Floor Tile VAT 9" x 9"	6260/01/01/12	Confirmed	126	SF	0	SF	Black		_	1	No	1/D
	Classroom 111 Classroom 111	M M	Floor Tile VAT 9" x 9" Floor Tile VAT 12" x 12"	6260/01/01/12 6260/01/01/NN	Confirmed Assumed	20 18	SF SF	0	SF SF	White Black			1 1	No No	1/D 1/D
1 1	Classroom 111	N/A	Cement Floor		Non Suspect ACM	825	SF	0	SF	DIACK			N/A	N/A	N/A
1 1	Classroom 111	M	Blackboard Glue Dots	6260/01/01/AET/BB/2600	Assumed	160	SF	Ö	SF				1	No	1/D
	Classroom 111	M	Linoleum	6260/01/01/AET/BB/2200	Assumed	27	SF	0	SF		on top of book shelves	_	1	No	1/D
	Classroom 111 Closet	N/A	Concrete Ceiling		Non Suspect ACM	12	SF	0	SF			+	N/A	N/A	N/A
	Classroom 111 Closet Classroom 111 Closet	N/A M	Concrete Block Wall Floor Tile VAT 9" x 9"	6260/01/01/12	Non Suspect ACM Confirmed	140 12	SF SF	0	SF SF	Black			N/A 1	N/A No	N/A 1/D
	Classroom 111 Closet Classroom 111 Closet	N/A	Cement Floor	0200/01/01/12	Non Suspect ACM	12	SF	0	SF	DIACK			N/A	N/A	N/A
	Classroom 112	T	Pipe Fitting Insulation	6260/01/01/21	Confirmed	8	EA	0	EA				1	No.	1/D
1 1	Classroom 112	T	Pipe Insulation 2-6 inch	6260/01/01/09	Confirmed	30	LF	0	LF				1	No	1/D
1 1	Classroom 112 Classroom 112	N/A N/A	Concrete Ceiling Concrete Block Wall		Non Suspect ACM Non Suspect ACM	825 1150	SF SF	25 0	SF SF	-		+	N/A N/A	N/A N/A	N/A N/A
	Olassiooni i i 2	19/75	COTICIED BIOCK Wall	1	I NOII Suspect ACIVI	1 1100	J.		OI.				19/75	13/73	1977

	Oakaal District of Dhiladalahia														
	School District of Philadelphia		AH	ERA Three-Year Reins							Reinspection Date: 10/8/2015	4			
	Henry H. Houston Elementary School (K-8)			Room by Room Locati	on Log Report						Building Inspector: Bernard Brunner	1			
	7300 Rural Lane, Philadelphia, PA 19119										Certificate Number: 45397]			
	ULCS# 6260										Management Planner: Monique Causley				
	Year Built: 1927										Certificate Number: ACC-0215-8-010	1			
E															
l e F															
m I															
e o										Color		Attic Crawl	Damage	Newly	
n o	On Site Room Name	System Affected	Material Description	HID#	Confirmed, Assumed, NAD,	Amount of Material	SF LF EA	Amount of	SF LF EA	required for VAT	Comments/Description/Notes	Space	Potential (DP)	Friable (NF)	Response
	Classroom 112	M	Transite Closet	6260/01/01/DD	Non Suspect ACM Assumed	30	SF	Damage 0	SF	IOI VAI	Comments/Description/Notes	Ranking	(DP) 1	No No	Action (RA) 1/D
1 1	Classroom 112	M	Transite Sills	6260/01/01/AET/BB/2300	Assumed	12	SF	0	SF				1	No	1/D
1 1		M	Floor Tile VAT 9" x 9"	6260/01/01/12	Confirmed	709	SF	1	SF	Grey			1	No	6/C
1 1	Classroom 112	M	Floor Tile VAT 9" x 9"	6260/01/01/12	Confirmed	116	SF	0	SF	Black			1	No	1/D
1 1	Classroom 112 Classroom 112	N/A M	Cement Floor Blackboard Glue Dots	6260/01/01/AET/BB/2600	Non Suspect ACM Assumed	825 160	SF SF	0	SF SF				N/A	N/A No	N/A 1/D
1 1	Classroom 112	M	Linoleum	6260/01/01/AET/BB/2200	Assumed	27	SF	0	SF		on top of book shelves		1	No	1/D
	Classroom 112 Closet	N/A	Concrete Ceiling		Non Suspect ACM	12	SF	0	SF				N/A	N/A	N/A
	Classroom 112 Closet	N/A	Concrete Block Wall		Non Suspect ACM	140	SF	0	SF				N/A	N/A	N/A
	Classroom 112 Closet	M	Floor Tile VAT 9" x 9"	6260/01/01/12	Confirmed	12	SF	0	SF	Black			1	No	1/D
1 1	Classroom 112 Closet	N/A	Cement Floor		Non Suspect ACM	12	SF	0	SF				N/A	N/A	N/A
1 1	Auditorium	N/A M	Concrete Block Wall	000010410415 ====================================	Non Suspect ACM	3555	SF	0	SF				N/A	N/A	N/A
	Auditorium		Transite Sills	6260/01/01/AET/BB/2300	Assumed	8	SF	0	SF				1	No	1/D
1 1	Auditorium	M	Floor Tile VAT 9" x 9"	6260/01/01/12	Confirmed	3878	SF	0	SF	Multi			1	No	1/D
	Auditorium	M	Floor Tile VAT 12" x 12"	6260/01/01/NN	Assumed	103	SF	0	SF	Grey		-	1	No	1/D
	Auditorium	M	Floor Tile VAT 12" x 12"	6260/01/01/NN	Assumed	69	SF	0	SF	Black			1	No	1/D
	Auditorium	N/A	Cement Floor		Non Suspect ACM	4050	SF	0	SF				N/A	N/A	N/A
	Auditorium	M	Acoustical Plaster Ceiling	6260/01/01/MM	Confirmed	4050	SF	0	SF	-			1	No	1/D
1 1		T	Pipe Fitting Insulation	6260/01/01/21	Confirmed	12	EA	0	EA				1	No	1/D
1 1		T M	Pipe Insulation 2-6 inch	6260/01/01/09	Confirmed	74	LF	0	LF	0			1	No	1/D
1 1		M	Floor Tile VAT 9" x 9" Floor Tile VAT 9" x 9"	6260/01/01/12 6260/01/01/12	Confirmed Confirmed	960 280	SF SF	5	SF SF	Grey Black			1	No No	6/C 1/D
1 1		M	Floor Tile VAT 12" x 12"	6260/01/01/NN	Assumed	5	SF	0	SF	Grey			1	No	1/D
1 1		N/A	Cement Floor	0200/01/01/1010	Non Suspect ACM	1245	SF	0	SF	Gley			N/A	N/A	N/A
1 1		M	Vibration Damper Cloth	6260/01/01/EE	Assumed	25	SF	0	SF				1	No	1/D
1 1		M	Transite	6260/01/01/AET/BB/2305	Assumed	9	SF	0	SF		gauge panel		1	No	1/D
1 1		N/A	Fiberglass Pipe Insulation	0200/01/01/AE1/BB/2003	Non Suspect ACM	15	LF	0	LF		gauge parier		N/A	N/A	N/A
1 1		N/A	Concrete Ceiling		Non Suspect ACM	200	SF	50	SF				N/A	N/A	N/A
1 1		N/A	Concrete Block Wall		Non Suspect ACM	600	SF	25	SF				N/A	N/A	N/A
1 1		M	Transite Sills	6260/01/01/AET/BB/2300	Assumed	2	SF	0	SF				1	No	1/D
1 1	Storage Room behind Stage	N/A	Cement Floor		Non Suspect ACM	200	SF	0	SF				N/A	N/A	N/A
	Stairwell next to Stage	N/A	Concrete Ceiling		Non Suspect ACM	120	SF	0	SF				N/A	N/A	N/A
1 1	Stairwell next to Stage	N/A	Concrete Block Wall		Non Suspect ACM	700	SF	0	SF				N/A	N/A	N/A
1 1		M	Transite Sills	6260/01/01/AET/BB/2300	Assumed	3	SF	0	SF				1	No	1/D
1 1	Stairwell next to Stage	M	Floor Tile VAT 12" x 12"	6260/01/01/NN	Assumed	50	SF	0	SF	Tan			1	No	1/D
1 1	- territoria de la companya de la co	N/A	Cement Floor		Non Suspect ACM	120	SF	0	SF				N/A	N/A	N/A
1 1		T	Pipe Fitting Insulation	6260/01/01/21	Confirmed	14	EA	0	EA				1	No	1/D
1 1	Clair Wolf durono World Clader Com 112	Т	Pipe Insulation 2-6 inch	6260/01/01/09	Confirmed	55	LF	0	LF				1	No	1/D
	Stairwell across from Classroom 112	N/A	Concrete Ceiling		Non Suspect ACM	280	SF	0	SF				N/A	N/A	N/A
1 1	Stairwell across from Classroom 112	N/A	Concrete Block Wall		Non Suspect ACM	1215	SF	0	SF		Material quantities include entire stairwell from 2nd Floor to		N/A	N/A	N/A
1 1	Stairwell across from Classroom 112	M	Transite Sills	6260/01/01/AET/BB/2300	Assumed	2	SF	0	SF		Basement (break out floor during next reinspetion)		1	No	1/D
1 1	Stairwell across from Classroom 112	N/A	Cement Floor		Non Suspect ACM	280	SF	0	SF				N/A	N/A	N/A
1 1	Hallway outside Auditorium	Т	Pipe Fitting Insulation	6260/01/01/21	Confirmed	33	EA	1	EA		Was DDC written for this damage?		1	No	2/B
	Hallway outside Auditorium	Т	Pipe Insulation 2-6 inch	6260/01/01/09	Confirmed	115	LF	0	LF				1	No	1/D
	Hallway outside Auditorium	N/A	Concrete Ceiling		Non Suspect ACM	1260	SF	0	SF				N/A	N/A	N/A
	Hallway outside Auditorium	N/A	Concrete Block Wall		Non Suspect ACM	2700	SF	0	SF				N/A	N/A	N/A
1 1		M	Transite Sills	6260/01/01/AET/BB/2300	Assumed	9	SF	0	SF				1	No	1/D
1 1		N/A	Cement Floor		Non Suspect ACM	1260	SF	0	SF				N/A	N/A	N/A
1 1	Entrance Vestibule behind Auditorium	T	Pipe Fitting Insulation	6260/01/01/21	Confirmed	2	EA	0	EA				1	No	1/D
1 1		T	Pipe Insulation 2-6 inch	6260/01/01/09	Confirmed	2	LF	0	LF	-			1	No	1/D
1 1	Entrance Vestibale bening / taakenam	N/A	Concrete Ceiling		Non Suspect ACM	168	SF	0	SF				N/A	N/A	N/A
1 1	Entrance Vectorie permit / teaterian	N/A	Concrete Block Wall		Non Suspect ACM	380	SF SF	0	SF SF				N/A N/A	N/A	N/A
1 1	Entrance vectibale benina / taatenam	N/A T	Cement Floor	6260/04/04/42	Non Suspect ACM	168 14	SF	0	SF				N/A	N/A	N/A
1 1	Stairwell adjacent to Nurse's Office Stairwell adjacent to Nurse's Office	T	Pipe Fitting Insulation Pipe Insulation 2-6 inch	6260/01/01/12 6260/01/01/09	Confirmed Confirmed	30	LF	0	LF				1	No No	1/D 1/D
1 1		N/A	Concrete Ceiling	0200/01/01/09	Non Suspect ACM	180	SF	0	SF				N/A	N/A	N/A
	Stainwell adjacent to Nurse's Office	N/A	Concrete Block Wall		Non Suspect ACM	930	SF	0	SF				N/A	N/A	N/A
	Stainwell adjacent to Nurse's Office	N/A	Cement Floor		Non Suspect ACM	180	SF	0	SF				N/A	N/A	N/A
	Hallway to Library	N/A	Concrete Ceiling		Non Suspect ACM	112	SF	0	SF				N/A	N/A	N/A
	Hallway to Library	N/A	Concrete Block Wall		Non Suspect ACM	315	SF	0	SF				N/A	N/A	N/A
	Hallway to Library	N/A	Cement Floor		Non Suspect ACM	112	SF	0	SF				N/A	N/A	N/A
3 1	Library	N/A	Ceiling Tile 1' x 1'		NAD	1515	SF	40	SF				N/A	N/A	N/A
3 1		N/A	Concrete Ceiling		Non Suspect ACM	1515	SF	0	SF				N/A	N/A	N/A
		-		•				•	•	•	-			•	

	School District of Philadelphia			IFDA Thurs Very Deiner				1			D : :- D 40/9/9945	_			
			AH	ERA Three-Year Reinsp							Reinspection Date: 10/8/2015	-			
	Henry H. Houston Elementary School (K-8)	[Room by Room Locati	on Log Report			J			Building Inspector: Bernard Brunner	4			
	7300 Rural Lane, Philadelphia, PA 19119										Certificate Number: 45397	_			
	ULCS# 6260										Management Planner: Monique Causley				
	Year Built: 1927	l									Certificate Number: ACC-0215-8-010				
E															
l e F															
m I															
e o						l		l		Color		Attic Crawl	Damage	Newly	_
n o	On Site Room Name	System Affected	Material Description	HID#	Confirmed, Assumed, NAD, Non Suspect ACM	Amount of Material	SF LF EA	Amount of Damage	SF LF EA	required for VAT	Comments/Description/Notes	Space Ranking	Potential (DP)	Friable (NF)	Response Action (RA)
3 1		N/A	Concrete Wall	111211	Non Suspect ACM	2240	SF	n	SF	10. 17.1	Commenta Decomplian Notes	Kanking	N/A	N/A	N/A
3 1	Library	M	Floor Tile VAT 9" x 9"	6260/03/01/AET/BB/2050	Confirmed	1515	SF	0	SF	White	Below 12 x 12 tile		1	No	1/D
3 1	Library	M	Floor Tile VAT 12" x 12"	6260/01/01/NN	Assumed	1235	SF	0	SF		Over 9 x 9 tile		1	No	1/D
3 1	Library	M	Floor Tile VAT 12" x 12"	6260/01/01/NN	Assumed	130	SF	0	SF	Tan			1	No	1/D
3 1	Library	M	Floor Tile VAT 12" x 12"	6260/01/01/NN	Assumed	150	SF	0	SF	Pink			1	No	1/D
3 1	Library	N/A	Cement Floor		Non Suspect ACM	1515	SF	0	SF				N/A	N/A	N/A
3 1	Library	M	Spline Ceiling Glue Dots	6260/03/01/AET/BB/2603	Assumed	1515	SF	0	SF				1	No	1/D
3 1	Library	M	Sink Undercoat Mastic	6260/03/01/AET/BB/2602	Assumed	10	SF	0	SF	White			1	No	1/D
1 2	Classroom 201	Т	Pipe Insulation 2-6 inch	6260/01/02/13	Confirmed	48	LF	0	LF		More insulation is likely present above ceiling tiles		1	No	1/D
1 2	Classroom 201	N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	840	SF	0	SF				N/A	N/A	N/A
1 2	Classroom 201	N/A	Plaster Ceiling		NAD	840	SF	0	SF				N/A	N/A	N/A
	Classroom 201	N/A	Plaster Wall		NAD	1130	SF	0	SF				N/A	N/A	N/A
	Classroom 201	N/A	Partition Room Dividers		Non Suspect ACM	290	SF	0	SF		Wood		N/A	N/A	N/A
	Classroom 201	N/A	Wood Floor		Non Suspect ACM	840	SF	0	SF				N/A	N/A	N/A
	Classroom 201	М	Blackboard Glue Dots	6260/01/02/AET/BB/2600	Assumed	100	SF	0	SF			1	1	No	1/D
	Classroom 201 Closet	Т	Pipe Insulation 2-6 inch	6260/01/02/13	Confirmed	12	LF	0	LF		More insulation is likely present above ceiling tiles	1	1	No	1/D
	Classroom 201 Closet	N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	120	SF	0	SF				N/A	N/A	N/A
	Classroom 201 Closet	N/A	Plaster Ceiling		NAD	120	SF	0	SF				N/A	N/A	N/A
	Classroom 201 Closet	N/A	Plaster Wall		NAD	700	SF	20	SF				N/A	N/A	N/A
	Classroom 201 Closet	N/A	Wood Floor		Non Suspect ACM	120	SF	0	SF			_	N/A	N/A	N/A
	Classroom 202	T	Pipe Insulation 2-6 inch	6260/01/02/13	Confirmed	48	LF	0	LF		More insulation is likely present above ceiling tiles		1	No	1/D
1 2	Classroom 202	N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	840	SF	0	SF				N/A	N/A	N/A
	Classroom 202	N/A	Plaster Ceiling		NAD	840	SF	0	SF SF				N/A	N/A	N/A
	Classroom 202 Classroom 202	N/A N/A	Plaster Wall Partition Room Dividers		NAD Non Suspect ACM	1130 290	SF SF	0	SF		Wood	+	N/A N/A	N/A N/A	N/A N/A
	Classroom 202	N/A N/A	Wood Floor		Non Suspect ACM	840	SF	0	SF		WOOd	_	N/A	N/A	N/A
	Classroom 202	M M	Blackboard Glue Dots	6260/01/02/AET/BB/2600	Assumed	40	SF	0	SF				1 1 1	No.	1/D
	Classroom 202 Closet	T	Pipe Insulation 2-6 inch	6260/01/02/13	Confirmed	12	LF	0	LF		More insulation is likely present above ceiling tiles		1	No.	1/D
	Classroom 202 Closet	N/A	Fiberglass Ceiling Tile 2' x 4'	0200701702170	Non Suspect ACM	120	SF	2	SF		more mediation to interly present above coming these		N/A	N/A	N/A
	Classroom 202 Closet	N/A	Plaster Ceiling		NAD	120	SF	0	SF				N/A	N/A	N/A
	Classroom 202 Closet	N/A	Plaster Wall		NAD	700	SF	0	SF				N/A	N/A	N/A
	Classroom 202 Closet	N/A	Wood Floor		Non Suspect ACM	120	SF	0	SF				N/A	N/A	N/A
1 2	Boy's Restroom	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	31	LF	0	LF				N/A	N/A	N/A
1 2	Boy's Restroom	N/A	Plaster Ceiling		NAD	160	SF	1	SF				N/A	N/A	N/A
	Boy's Restroom	N/A	Plaster Wall		NAD	680	SF	0	SF				N/A	N/A	N/A
	Boy's Restroom	N/A	Ceramic Tile Wall		Non Suspect ACM	680	SF	0	SF				N/A	N/A	N/A
1 2	Boy's Restroom	N/A	Ceramic Tile Floor		Non Suspect ACM	160	SF	0	SF				N/A	N/A	N/A
	Boy's Restroom Pipe Chase	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	50	LF	0	LF				N/A	N/A	N/A
	Classroom 203	Т	Pipe Insulation 2-6 inch	6260/01/02/13	Confirmed	48	LF	0	LF		More insulation is likely present above ceiling tiles		1	No	1/D
	Classroom 203	N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	870	SF	4	SF				N/A	N/A	N/A
	Classroom 203	N/A	Plaster Ceiling		NAD	870	SF	0	SF			+	N/A	N/A	N/A
	Classroom 203	N/A	Plaster Wall		NAD Nan Oussia AOM	1415	SF	0	SF			1	N/A	N/A	N/A
1 2	Classroom 203	N/A M	Wood Floor	0000/04/00/2 == 155 155 1	Non Suspect ACM	870	SF	0	SF SF			-	N/A	N/A	N/A 1/D
1 2	Classroom 203	M T	Blackboard Glue Dots	6260/01/02/AET/BB/2600 6260/01/02/24	Assumed Confirmed	85	SF EA	0	SF EA	-		1	1	No No	1/D
1 2	Classroom 203 Small Closet Classroom 203 Small Closet	N/A	Pipe Fitting Insulation	0200/01/02/24	Non Suspect ACM	10	I F	0	LF.	-		+	N/A	No N/A	N/A
	Classroom 203 Small Closet Classroom 203 Small Closet	N/A N/A	Fiberglass Pipe Insulation Plaster Ceiling		Non Suspect ACM NAD	50	SF	0	SF			+	N/A N/A	N/A N/A	N/A N/A
	Classroom 203 Small Closet	N/A N/A	Plaster Wall		NAD NAD	370	SF	0	SF			1	N/A	N/A	N/A
	Classroom 203 Small Closet	N/A	Wood Floor		Non Suspect ACM	50	SF	0	SF				N/A	N/A	N/A
	Classroom 203 Large Closet	T	Pipe Insulation 2-6 inch	6260/01/02/13	Confirmed	16	LF	0	LF		More insulation is likely present above ceiling tiles		1	No	1/D
	Classroom 203 Large Closet	N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	120	SF	2	SF		, , ,		N/A	N/A	N/A
	Classroom 203 Large Closet	N/A	Plaster Ceiling		NAD	120	SF	0	SF				N/A	N/A	N/A
	Classroom 203 Large Closet	N/A	Plaster Wall		NAD	700	SF	5	SF				N/A	N/A	N/A
1 2	Classroom 203 Large Closet	N/A	Wood Floor		Non Suspect ACM	120	SF	0	SF		Vines around windows		N/A	N/A	N/A
1 2	Counselor's Office	Т	Pipe Insulation 2-6 inch	6260/01/02/13	Confirmed	24	LF	0	LF		More insulation is likely present above ceiling tiles		1	No	1/D
	Counselor's Office	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	6	LF	0	LF				N/A	N/A	N/A
	Counselor's Office	N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	288	SF	6	SF				N/A	N/A	N/A
1 2	Counselor's Office	N/A	Plaster Ceiling		NAD	288	SF	0	SF			1	N/A	N/A	N/A
	Counselor's Office	N/A	Plaster Wall		NAD	720	SF	0	SF			1	N/A	N/A	N/A
	Counselor's Office	N/A	Wood Floor		Non Suspect ACM	288	SF	0	SF				N/A	N/A	N/A
	Counselor's Office Restroom	N/A	Plaster Ceiling		NAD	50	SF	0	SF			+	N/A	N/A	N/A
1 2	Counselor's Office Restroom	N/A	Plaster Wall		NAD	370	SF	0	SF				N/A	N/A	N/A

North Howard Entering 1960 And Property Service Property Service		School District of Philadelphia		AH	ERA Three-Year Reins	pection 2015-2016						Reinspection Date: 10/8/2015				
Part Control Control												•	1			
			'										1			
Part																
Part													1			
P Comment	E	rear Bunt. 1327										Octanicate Number: ACC-0213-0-010				T
Part																
Part																
	e o												Attic Crawl			
1 1 Control Cont	n o	On Site Poom Name	System	Material Description	HID#	Confirmed, Assumed, NAD,	Amount of	SF LF	Amount of	SF LF	required for VAT	Comments/Description/Notes		Potential		Response
1 2 Common 9A					111211				n		101 1711	Commenta Decomplian Notes	Kanking	· ,	. ,	
1									0							
1 2 Demon-Trick Max					6260/01/02/13							More insulation is likely present above ceiling tiles				
1 2 2						Non Suspect ACM						, , , , , , , , , , , , , , , , , , ,		N/A		
1 2 Concern PA			N/A			NAD		SF	0	SF				N/A	N/A	N/A
1 2 Common 394	1 2	Classroom 204	N/A	Plaster Wall		NAD	1065	SF	0	SF				N/A	N/A	N/A
1 2 Selection Michael Control (1997) 2 Selection Michael Control (1997) 3 Selectio				Partition Room Dividers		Non Suspect ACM						Wood				
2 Consecure Sci Cluster	1 2	Classroom 204							-							
1 2 Conseron Mile Charles					6260/01/02/AET/BB/2600								1	-		
Part Common (St. Common (S													+			
1 1													+			
1 2													+			
1 2 Instance Content of Success Coloron 200 NA Place Wild NA NA NA NA NA NA NA N					6260/04/02/AA								+			
1 Petron Chest attended to Description NA Petron (Transport Company of the Company of th					626U/U1/U2/AA								+			
1 2 Common 250									-							
1 2 Classroon 255									-				+			
1 2 Classecon-255					6260/01/02/13				-			More insulation is likely present above ceiling tiles				
1 2 Clearson 265					0200/01/02/10							Word insulation is likely present above ceiling lies				
1 2 Classroom 265																
1 2																
1 2 Classroom 255															+	N/A
1 2 Classroom 205									0			Wood				
1 2 Deseron 205 Closet									0							
1 2 Glassoom 35 Closet					6260/01/02/AET/BB/2600				0						No	1/D
1 2 Classoon 265 Coxel	1 2	Classroom 205 Closet	N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	100	SF	0	SF				N/A	N/A	N/A
1 2 Classoom 205 Closet				Plaster Ceiling					0							
1 2 Classroom 205									_							
1 2 Classroom 206	1 2	Classroom 205 Closet														
1 2 Classroom 205			<u> </u>		6260/01/02/13							More insulation is likely present above ceiling tiles	+			
1 2 Classecom 206	1 2	Classroom 206	N/A	Plaster Ceiling		NAD NAD	870	SF		SF				N/A		
1 2 Classecom 206				Plaster Wall			1065							N/A		N/A
1 2 Classroom 206 Closest	1 2	Classroom 206						SF		SF		Wood	_			
1 2 Classroom 200 Closet					6260/01/02/AET/BB/2600											
1 2 Classroom 200 Closeet	1 2	Classroom 206 Closet	Т	Pipe Insulation 2-6 inch	6260/01/02/13	Confirmed	16	LF	0	LF		More insulation is likely present above ceiling tiles		1	No	1/D
1 2 Classroom 20G Closed				Fiberglass Ceiling Tile 2' x 4'			.=-		_							
1 2 Glassroom 206 Closet				Plaster Ceiling				_								
1 2 Girls Restroom				Plaster Wall		NAD	700		2						1	
1 2 Girls Restroom	1 2	Classroom 206 Closet		Wood Floor		Non Suspect ACM	120									
1 2 Girl's Restroom	1 2	Girl's Restroom											+			
1 2 Girts Restroom	1 2	Girl's Restroom	N/A	Plaster Wall		NAD	680	SF		SF				N/A	N/A	N/A
1 2 Girl's Restroom Pipe Chase	1 2	Girl's Restroom				Non Suspect ACM										
1 2 Custodial Closet by Gir's Restroom						Non Suspect ACM Non Suspect ACM			_				+			
1 2 Classroom 207	1 2	Custodial Closet by Girl's Restroom	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	32	LF	0	LF				N/A	N/A	N/A
1 2 Classroom 207	1 2	Classroom 207	T	Pipe Insulation 2-6 inch	6260/01/02/13	Confirmed				LF		More insulation is likely present above ceiling tiles				1/D
1 2 Classroom 207						Non Suspect ACM Non Suspect ACM							+			
1 2 Classroom 207 N/A Partition Room Dividers Non Suspect ACM 290 SF 0 SF Wood N/A	1 2	Classroom 207	N/A	Plaster Ceiling		NAD	840	SF	0	SF				N/A	N/A	N/A
1 2 Classroom 207	1 2	Classroom 207		Plaster Wall			1130		0	SF		Mond	_			
1 2 Classroom 207 Closet T Pipe Insulation 2-6 inch 6260/01/02/AET/BB/2600 Assumed 50 SF 0 SF SF	1 2	Classroom 207							10			vvoou	+			
1 2 Classroom 207 Closet					6260/01/02/AET/BB/2600	Assumed										
1 2 Classroom 207 Closet	1 2	Classroom 207 Closet	T		6260/01/02/13	Confirmed	16	LF	0	LF		More insulation is likely present above ceiling tiles		1	No	1/D
1 2 Classroom 207 Closet				Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	100								1	
1 2 Classroom 207 Closet N/A Wood Floor Non Suspect ACM 100 SF 0 SF Non Floor N/A																
1 2 Classroom 208 T Pipe Insulation 2-6 inch 6260/01/02/13 Confirmed 48 LF 0 LF More insulation is likely present above ceiling tiles 1 No 1/D 1 2 Classroom 208 N/A Fiberglass Ceiling Tile 2'x 4' No SF 3 SF No N/A N/A<																1
1 2 Classroom 208	1 2	Classroom 207 Closet				Non Suspect ACM									14071	
1 2 Classroom 208 N/A Plaster Ceiling NAD 840 SF 0 SF N/A	1 2	Classroom 208 Classroom 208		Pipe Insulation 2-6 inch Fiberglass Ceiling Tile 2' x 4'	6260/01/02/13				3			More insulation is likely present above ceiling tiles	+		No N/A	1/D N/A
1 2 Classroom 208 N/A Partition Room Dividers Non Suspect ACM 290 SF 0 SF Wood N/A	1 2	Classroom 208				NAD	840	SF	0	SF			_			
1 2 Classroom 208 N/A Wood Floor Non Suspect ACM 840 SF 0 SF N/A N/A N/A N/A							1130	SF		SF				N/A	N/A	
1 2 Classroom 208 M Blackboard Glue Dots 6260/01/02/AET/BB/2600 Assumed 50 SF 0 SF 1 No 1/0	1 2	Classroom 208 Classroom 208	N/A N/A			Non Suspect ACM	290					Wood	+			N/A N/A
				Blackboard Glue Dots	6260/01/02/AET/BB/2600	Assumed	50	SF					_	1	No.	

School District of Philadelphi	a	АН	ERA Three-Year Reins	pection 2015-2016						Reinspection Date: 10/8/2015				
Henry H. Houston Elementary School (K	(-8)		Room by Room Locati							Building Inspector: Bernard Brunner				
7300 Rural Lane, Philadelphia, PA 191		L								Certificate Number: 45397				
ULCS# 6260										Management Planner: Monique Causley				
Year Built: 1927										Certificate Number: ACC-0215-8-010				
E														
I e F														
m I														
e o n o	System			Confirmed. Assumed. NAD.	Amount of	SF LF	Amount of	SF LF	Color reauired		Attic Crawl	Damage Potential	Newly Friable	Response
t r On Site Room Name	Affected	Material Description	HID#	Non Suspect ACM	Material	EA	Damage	EA	for VAT	Comments/Description/Notes	Space Ranking	(DP)	(NF)	Action (RA
1 2 Classroom 208 Closet	Т	Pipe Insulation 2-6 inch	6260/01/02/13	Confirmed	12	LF	0	LF		More insulation is likely present above ceiling tiles		1	No	1/D
1 2 Classroom 208 Closet	N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	120	LF	8	LF				N/A	N/A	N/A
1 2 Classroom 208 Closet	N/A	Plaster Ceiling		NAD	120	SF	0	SF				N/A	N/A	N/A
1 2 Classroom 208 Closet 1 2 Classroom 208 Closet	N/A N/A	Plaster Wall Wood Floor		NAD Non Suspect ACM	700 120	SF SF	0	SF SF				N/A N/A	N/A N/A	N/A N/A
1 2 Classroom 209	N/A N/A	Fiberglass Pipe Insulation		Non Suspect ACM	10	LF	0	LF				N/A	N/A	N/A
1 2 Classroom 209	N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	775	LF	0	SF				N/A	N/A	N/A
1 2 Classroom 209 1 2 Classroom 209	N/A N/A	Plaster Ceiling Plaster Wall		NAD NAD	775 1415	SF SF	0	SF SF				N/A N/A	N/A N/A	N/A N/A
									Grey, Black			1471		
1 2 Classroom 209 1 2 Classroom 209	M N/A	Floor Tile VAT 12" x 12" Wood Floor	6260/01/02/QQ	Assumed Non Suspect ACM	775 775	SF SF	0	SF SF	Black	No Access		1 N/A	No N/A	1/D N/A
1 2 Classroom 209 1 2 Classroom 209	M M	Blackboard Glue Dots	6260/01/02/AET/BB/2600	Non Suspect ACM Assumed	175	SF	0	SF				1 1	N/A No	1/D
1 2 Classroom 209 Closet	N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	90	SF	0	SF				N/A	N/A	N/A
1 2 Classroom 209 Closet	N/A	Plaster Ceiling		NAD	90	SF	0	SF				N/A	N/A	N/A
1 2 Classroom 209 Closet	N/A	Plaster Wall		NAD	700	SF	0	SF				N/A	N/A	N/A
1 2 Classroom 209 Closet	M	Floor Tile VAT 12" x 12"	6260/01/02/QQ	Assumed	90	SF	0	SF	Grey	No Access		1	No	1/D
1 2 Classroom 209 Closet	N/A N/A	Wood Floor Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	90 150	SF SF	0	SF SF				N/A N/A	N/A N/A	N/A N/A
1 2 Teacher Lounge 209A 1 2 Teacher Lounge 209A	N/A	Plaster Ceiling		Non Suspect ACM NAD	150	SF	0	SF				N/A	N/A N/A	N/A N/A
1 2 Teacher Lounge 209A	N/A	Plaster Wall		NAD	450	SF	0	SF				N/A	N/A	N/A
1 2 Teacher Lounge 209A	M	Floor Tile VAT 12" x 12"	6260/01/02/QQ	Assumed	75	SF	2	SF	Grey			1	No	6/C
1 2 Teacher Lounge 209A	M	Floor Tile VAT 12" x 12"	6260/01/03/TT	Assumed	75	SF	0	SF	Red			1	No	1/D
1 2 Teacher Lounge 209A 1 2 Teacher Lounge 209A Restroom	N/A N/A	Wood Floor Fiberglass Pipe Insulation		Non Suspect ACM Non Suspect ACM	150 23	SF LF	0	SF LF				N/A N/A	N/A N/A	N/A N/A
1 2 Teacher Lounge 209A Restroom	N/A	Plaster Ceiling		NAD	60	SF	0	SF				N/A	N/A	N/A
1 2 Teacher Lounge 209A Restroom 1 2 Teacher Lounge 209A Restroom	N/A N/A	Plaster Wall Ceramic Tile Wall		NAD Non Suspect ACM	250 250	SF SF	0	SF SF				N/A N/A	N/A N/A	N/A N/A
1 2 Teacher Lounge 209A Restroom	N/A	Ceramic Tile Wall		Non Suspect ACM	60	SF	0	SF				N/A	N/A	N/A
Teacher Lounge 209A Telecommunication Equipr	ment X				.,	x		.,				×	.,	.,
1 2 Room 1 2 Stairwell adjacent to Classroom 201	N/A	X Concrete Ceiling		Non Suspect ACM	180	SF	15	SF	X	No Access		N/A	N/A	N/A
1 2 Stainwell adjacent to Classroom 201	N/A	Brick Wall		Non Suspect ACM	1120	SF	25	SF				N/A	N/A	N/A
1 2 Stairwell adjacent to Classroom 201	N/A	Cement Floor		Non Suspect ACM	180	SF	0	SF				N/A	N/A	N/A
1 2 Hallway outside Classrooms 201-202	Т	Pipe Insulation 2-6 inch	6260/01/02/13	Confirmed	48	LF	0	LF		More insulation is likely present above ceiling tiles		1	No	1/D
1 2 Hallway outside Classrooms 201-202	N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	560	SF	0	SF				N/A	N/A	N/A
1 2 Hallway outside Classrooms 201-202	N/A	Plaster Ceiling		NAD	560	SF	0	SF				N/A	N/A	N/A
1 2 Hallway outside Classrooms 201-202	N/A	Plaster Wall		NAD	1780	SF	0	SF				N/A	N/A	N/A
1 2 Hallway outside Classrooms 201-202	N/A	Marble Wall		Non Suspect ACM	595	SF	0	SF				N/A	N/A	N/A
1 2 Hallway outside Classrooms 201-202	N/A	Cement Floor		Non Suspect ACM	560	SF SF	0	SF				N/A	N/A N/A	N/A
Hallway outside Classrooms 203-206 Hallway outside Classrooms 203-206 Hallway outside Classrooms 203-206	N/A N/A	Fiberglass Ceiling Tile 2' x 4' Plaster Ceiling		Non Suspect ACM NAD	1105 1105	SF	0	SF SF				N/A N/A	N/A N/A	N/A N/A
1 2 Hallway outside Classrooms 203-206	N/A	Plaster Wall		NAD	2260	SF	0	SF				N/A	N/A	N/A
1 2 Hallway outside Classrooms 203-206	N/A	Marble Wall		Non Suspect ACM	755	SF	0	SF				N/A	N/A	N/A
1 2 Hallway outside Classrooms 203-206	N/A	Cement Floor		Non Suspect ACM	1105	SF	0	SF				N/A	N/A	N/A
1 2 Stairwell B	Т	Pipe Fitting Insulation	6260/01/02/24	Confirmed	5	EA	0	EA				1	No	1/D
1 2 Stairwell B	T	Pipe Insulation 2-6 inch	6260/01/02/13	Confirmed	6	SF	0	LF				1	No	1/D
1 2 Stainvell B	N/A	Plaster Ceiling		NAD	240	SF	20	SF				N/A	N/A N/A	N/A
1 2 Stainwell B	N/A	Plaster Wall		NAD	1360	SF	0	SF				N/A	1471	N/A
1 2 Stairwell B 1 2 Stairwell B	N/A N/A	Marble Wall Cement Floor		Non Suspect ACM Non Suspect ACM	455 240	SF SF	0	SF SF				N/A N/A	N/A N/A	N/A N/A
1 2 Stairwell B 1 2 Stairwell A	N/A T	Pipe Fitting Insulation	6260/01/02/24	Confirmed	3	EA	0	EA				N/A	N/A No	1/D
1 2 Stainwell A	T	Pipe Insulation 2-6 inch	6260/01/02/13	Confirmed	3	LF	0	LF				1	No	1/D
1 2 Stairwell A	N/A	Plaster Ceiling		NAD	240	SF	10	SF				N/A	N/A	N/A
1 2 Stairwell A	N/A	Plaster Wall		NAD	1360	SF	0	SF				N/A	N/A	N/A
1 2 Stairwell A	N/A	Marble Wall		Non Suspect ACM	455	SF	0	SF				N/A	N/A	N/A
1 2 Stairwell A	N/A	Cement Floor		Non Suspect ACM	240	SF	0	SF				N/A	N/A	N/A
1 2 Hallway outside Classrooms 201-202	T	Pipe Insulation 2-6 inch	6260/01/02/13	Confirmed	48	LF	0	LF		More insulation is likely present above ceiling tiles		1	No	1/D
1 2 Hallway outside Classrooms 201-202	N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	560	SF	5	SF SF	-			N/A	N/A	N/A
1 2 Hallway outside Classrooms 201-202 1 2 Hallway outside Classrooms 201-202	N/A N/A	Plaster Ceiling Plaster Wall		NAD NAD	560 1780	SF SF	0	SF				N/A N/A	N/A N/A	N/A N/A
1 2 Hallway outside Classrooms 201-202 1 2 Hallway outside Classrooms 201-202	N/A N/A	Marble Wall		Non Suspect ACM	595	SF	0	SF				N/A N/A	N/A N/A	N/A N/A
1 2 Hallway outside Classrooms 201-202	N/A	Cement Floor		Non Suspect ACM	560	SF	0	SF				N/A	N/A	N/A
1 2 Fire Tower adjacent to Classroom 208	N/A	Concrete Ceiling		Non Suspect ACM	240	SF	0	SF				N/A	N/A	N/A
											1			N/A
1 2 Fire Tower adjacent to Classroom 208 1 2 Fire Tower adjacent to Classroom 208	N/A	Brick Wall		Non Suspect ACM	1360	SF	0	SF				N/A	N/A	N/A

	School District of Philadelphia		ΛΗ	ERA Three-Year Reinsp	action 2015-2016						Reinspection Date: 10/8/2015				
	Henry H. Houston Elementary School (K-8)		A.,	Room by Room Locati							Building Inspector: Bernard Brunner	1			
	7300 Rural Lane, Philadelphia, PA 19119	"		Room by Room Locati	on Log Report			l			Certificate Number: 45397	1			
	ULCS# 6260										Management Planner: Monique Causley	1			
											Certificate Number: ACC-0215-8-010	1			
E	Year Built: 1927										Certificate Number: ACC-0215-8-010				
e F m I															
e o	On Site Room Name	System Affected	Material Description	HID#	Confirmed, Assumed, NAD, Non Suspect ACM	Amount of Material	SF LF EA		SF LF EA	Color required for VAT	Comments/Description/Notes	Attic Crawl Space	Damage Potential (DP)	Newly Friable (NF)	Response Action (RA)
1 2		X	X	HID#	X X	X	X	Damage X	X	X	Comments/Description/Notes	Ranking	X	X	X X
1 2	Classroom 210	Т	Pipe Insulation 2-6 inch	6260/01/02/13	Confirmed	8	LF	0	LF				1	No	1/D
1 2	Classroom 210	N/A M	Concrete Ceiling	0000/04/00/4 FT/DD/0000	Non Suspect ACM	405	SF SF	0	SF SF				N/A	N/A	N/A
	Classroom 210 Classroom 210	M	Transite Sills Floor Tile VAT 9" x 9"	6260/01/02/AET/BB/2300 6260/01/02/15	Assumed Confirmed	6 320	SF	0	SF	Grey			1	No No	1/D 1/D
1 2	Classroom 210	М	Floor Tile VAT 9" x 9"	6260/01/02/15	Confirmed	85	SF	0	SF	Black			1	No	1/D
1 2	Classroom 210	N/A	Cement Floor		Non Suspect ACM	405	SF	0	SF				N/A	N/A	N/A
1 2	Classroom 210	М	Blackboard Glue Dots	6260/01/02/AET/BB/2600	Assumed	160	SF	0	SF				1	No	1/D
	Classroom 210	M	Linoleum	6260/01/02/AET/BB/2200	Assumed	12	SF	0	SF		on top of book shelves		1	No	1/D
1 2	Classroom 210 Closet by Entrance	N/A N/A	Concrete Ceiling		Non Suspect ACM Non Suspect ACM	10	SF SF	0	SF SF				N/A N/A	N/A N/A	N/A N/A
	Classroom 210 Closet by Entrance Classroom 210 Closet by Entrance	M M	Concrete Block Wall Floor Tile VAT 9" x 9"	6260/01/02/15	Confirmed	120 10	SF	0	SF	Black			1 1	No.	1/D
	Classroom 210 Closet by Entrance	N/A	Cement Floor	0200/01/02/13	Non Suspect ACM	10	SF	0	SF	DIACK			N/A	N/A	N/A
	Classroom 210 Closet in Corner	X	X		X	X	X	X	X	х			X	X	X
	Speech Therapist Office between Classrooms 210 and		~												
1 2	211	T	Pipe Insulation 2-6 inch	6260/01/02/13	Confirmed	16	LF	0	LF				1	No	1/D
1 2	Speech Therapist Office between Classrooms 210 and 211	N/A	Concrete Ceiling		Non Suspect ACM	176	SF	0	SF				N/A	N/A	N/A
1 2	Speech Therapist Office between Classrooms 210 and	IN/A	Concrete Centrig		Non Suspect ACM		- 0.	- 0					IN/A	IN/A	IN/A
1 2	211	N/A	Concrete Block Wall		Non Suspect ACM	580	SF	0	SF				N/A	N/A	N/A
1 2	Speech Therapist Office between Classrooms 210 and 211	м	Transite Sills	6260/01/02/AET/BB/2300	Assumed	,	SF	0	SF				1	No	1/D
	Speech Therapist Office between Classrooms 210 and	IVI	Transite Sills	0200/01/02/AE1/BB/2300	Assumed		- 0.	-	-					INU	1/0
1 2	211	N/A	Cement Floor		Non Suspect ACM	176	SF	0	SF				N/A	N/A	N/A
1 2	Speech Therapist Office between Classrooms 210 and 211	м	Vibration Damper Cloth	6260/01/02/JJ	Assumed	,	SF	_	SF					No	1/D
		T	Pipe Insulation 2-6 inch	6260/01/02/33	Confirmed	16	LF	0	LF				1	No	1/D
1 2	Classroom 211 Classroom 211	N/A	Concrete Ceiling		Non Suspect ACM	825	SF	0	SF				N/A	N/A	N/A
1 2	Classroom 211 Classroom 211	N/A	Concrete Block Wall		Non Suspect ACM	1150	SF	0	SF				N/A	N/A	N/A
1 2	Classroom 211 Classroom 211	M M	Transite Closet Transite Sills	6260/01/02/PP 6260/01/02/AET/BB/2300	Assumed	30 12	SF SF	0	SF SF				1	No	1/D 1/D
1 2	Classroom 211	M	Floor Tile VAT 9" x 9"	6260/01/02/AE1/BB/2300	Assumed Confirmed	709	SF	0	SF	Grey			1	No No	1/D
	Classroom 211	М	Floor Tile VAT 9" x 9"	6260/01/02/15	Confirmed	116	SF	0	SF	Black			1	No	1/D
1 2	Classroom 211	N/A	Cement Floor		Non Suspect ACM	825	SF	0	SF				N/A	N/A	N/A
	Classroom 211	М	Blackboard Glue Dots	6260/01/02/AET/BB/2600	Assumed	160	SF	0	SF				1	No	1/D
1 2		М	Linoleum	6260/01/02/AET/BB/2200	Assumed	27	SF	0	SF		on top of book shelves		1	No	1/D
1 2		N/A	Concrete Ceiling		Non Suspect ACM	12	SF	0	SF				N/A	N/A	N/A
1 2		N/A M	Concrete Block Wall		Non Suspect ACM	140	SF	0	SF	Di i			N/A	N/A	N/A
	Classroom 211 Closet	N/A	Floor Tile VAT 9" x 9"	6260/01/02/15	Confirmed	12	SF SF	0	SF SF	Black			1 N/A	No N/A	1/D N/A
1 2	Classroom 211 Closet	N/A T	Cement Floor Pipe Insulation 2-6 inch	6260/01/02/13	Non Suspect ACM Confirmed	12 16	LF	0	LF				N/A	N/A No	1/D
1 2	Classroom 212 Classroom 212	N/A	Concrete Ceiling	0200/01/02/13	Non Suspect ACM	825	SF	0	SF				N/A	N/A	N/A
1 2	Classroom 212	N/A	Concrete Block Wall		Non Suspect ACM	1150	SF	0	SF				N/A	N/A	N/A
1 2	Classroom 212 Classroom 212	M M	Transite Closet	6260/01/02/PP 6260/01/02/AET/BB/2300	Assumed	30 12	SF SF	0	SF SF				1	No	1/D 1/D
1 2	Classroom 212 Classroom 212	M M	Transite Sills Floor Tile VAT 9" x 9"	6260/01/02/AET/BB/2300 6260/01/02/15	Assumed Confirmed	709	SF SF	0	SF SF	Grey		\vdash	1	No No	1/D 1/D
	Classroom 212	M	Floor Tile VAT 9" x 9"	6260/01/02/15	Confirmed	116	SF	0	SF	Black			1	No	1/D
1 2	Classroom 212	N/A	Cement Floor		Non Suspect ACM	825	SF	Ö	SF	Didox			N/A	N/A	N/A
1 2	Classroom 212	M	Blackboard Glue Dots	6260/01/02/AET/BB/2600	Assumed	160	SF	0	SF		and the office below		1	No	1/D
	Classroom 212	M	Linoleum	6260/01/02/AET/BB/2200	Assumed	27	SF	0	SF		on top of book shelves		1	No	1/D
1 2		N/A	Concrete Ceiling		Non Suspect ACM	12	SF SF	70	SF SF				N/A	N/A	N/A
	Classroom 212 Closet	N/A	Concrete Block Wall	0000/04/00/45	Non Suspect ACM	140		70		Black			N/A 1	N/A No	N/A
	Classroom 212 Closet Classroom 212 Closet	M N/A	Floor Tile VAT 9" x 9"	6260/01/02/15	Confirmed Non Support ACM	12	SF SF	0	SF SF	Black		\vdash	1 N/A	No N/A	1/D N/A
1 2	Classroom 212 Closet Staff Restroom across from Classroom 212	N/A N/A	Cement Floor Fiberglass Pipe Insulation		Non Suspect ACM Non Suspect ACM	12 10	SF LF	0	SF LF				N/A N/A	N/A N/A	N/A N/A
1 2	Staff Restroom across from Classroom 212	N/A	Concrete Ceiling		Non Suspect ACM	252	SF	100	SF				N/A	N/A	N/A
1 2	Staff Restroom across from Classroom 212	N/A	Ceramic Tile Wall		Non Suspect ACM	660	SF	0	SF				N/A	N/A	N/A
	Staff Restroom across from Classroom 212	N/A	Concrete Block Wall		Non Suspect ACM	660	SF	0	SF				N/A	N/A	N/A
1 2	Staff Restroom across from Classroom 212 Staff Restroom across from Classroom 212	M N/A	Transite Sills Ceramic Tile Floor	6260/01/02/AET/BB/2300	Assumed Non Suspect ACM	2 252	SF SF	0	SF SF			\vdash	1 N/A	No N/A	1/D N/A
1 2	Staff Restroom across from Classroom 212 Staff Restroom across from Classroom 212	N/A N/A	Vinyl Vibration Damper Cloth		Non Suspect ACM Non Suspect ACM	1	SF	0	SF				N/A N/A	N/A N/A	N/A N/A
1 2	Pipe Chase in Staff Restroom across from Classroom 212	X	X		X X	X	X	X	X	Х	No Access		X	X	X
	Stairwell across from Classroom 212	Т	Pipe Insulation 2-6 inch	6260/01/02/13	Confirmed	16	LF	0	LF				1	No	1/D
	Stairwell across from Classroom 212	N/A	Concrete Ceiling		Non Suspect ACM	280	SF	0	SF				N/A	N/A	N/A
	Stairwell across from Classroom 212	N/A	Concrete Block Wall		Non Suspect ACM	1215	SF	0	SF				N/A	N/A	N/A
1 2	Stairwell across from Classroom 212	м	Transite Cille	6260/01/02/AET/BB/2300		2	SF	0	SF		Material quantities include entire stairwell from 2nd Floor to	7	1	No	1/D
	Stairwell across from Classroom 212 Stairwell across from Classroom 212	N/A	Transite Sills Cement Floor	0200/01/02/AE1/BB/2300	Assumed Non Suspect ACM	280	SF	0	SF		Basement (break out floor during next reinspetion)		N/A	No N/A	N/A
	Hallway outside Classrooms 210-212	T T	Pipe Fitting Insulation	6260/01/02/24	Confirmed	1	EA	0	EA				1 1	No.	1/D
	Hallway outside Classrooms 210-212	T	Pipe Insulation 2-6 inch	6260/01/02/24	Confirmed	90	LF	0	LF				1	No	1/D
1 2	•	N/A	Concrete Ceiling	0200/01/02/13	Non Suspect ACM	750	SF	0	SF				N/A	N/A	N/A
	Hallway outside Classrooms 210-212 Hallway outside Classrooms 210-212	N/A N/A	Concrete Ceiling Concrete Block Wall		Non Suspect ACM Non Suspect ACM	1620	SF	0	SF				N/A N/A	N/A N/A	N/A N/A
1 1 2		13//5	CONGRES BIOCK WAII	1	I NOT GUAPEGE AGIN	1020	UF		UF.				17/1	1377	100

	School District of Philadelphia		AH	ERA Three-Year Reins	ection 2015-2016						Reinspection Date: 10/8/2015				
	Henry H. Houston Elementary School (K-8)			Room by Room Locati							Building Inspector: Bernard Brunner	1			
	7300 Rural Lane, Philadelphia, PA 19119	1		•							Certificate Number: 45397	1			
	ULCS# 6260										Management Planner: Monique Causley	1			
	Year Built: 1927										Certificate Number: ACC-0215-8-010	1			
E															
l e F															
mI															
e o							l			Color		Attic Crawl	Damage	Newly	
n o	On Site Room Name	System Affected	Material Description	HID#	Confirmed, Assumed, NAD, Non Suspect ACM	Amount of Material	SF LF EA	Amount of Damage	SF LF EA	required for VAT	Comments/Description/Notes	Space Ranking	Potential (DP)	Friable (NF)	Response Action (RA)
1 2	Hallway outside Classrooms 210-212	M	Transite Sills	6260/01/02/AET/BB/2300	Assumed	10	SF	0	SF			ruming	1	No	1/D
1 2	Hallway outside Classrooms 210-212	М	Floor Tile VAT 9" x 9"	6260/01/02/15	Confirmed	33	SF	0	SF	Black			1	No	1/D
1 2	Hallway outside Classrooms 210-212	N/A	Cement Floor		Non Suspect ACM	750	SF	0	SF				N/A	N/A	N/A
1 2	Stairwell adjacent to Classroom 210	Т	Pipe Insulation 2-6 inch	6260/01/02/13	Confirmed	18	LF	0	LF				1	No	1/D
1 2	Stairwell adjacent to Classroom 210	N/A	Concrete Ceiling		Non Suspect ACM	180	SF	0	SF				N/A	N/A	N/A
1 2	Stairwell adjacent to Classroom 210	N/A	Concrete Block Wall		Non Suspect ACM	930	SF	0	SF				N/A	N/A	N/A
		M	Transite Sills	6260/01/02/AET/BB/2300	Assumed	2	SF	0	SF				1	No	1/D
1 2	Stainwell adjacent to Classroom 210 Hallway from Element 1 to Stainwell adjacent to	N/A	Cement Floor		Non Suspect ACM	180	SF	0	SF				N/A	N/A	N/A
1 2	Classroom 210	Т	Pipe Insulation 2-6 inch	6260/01/02/13	Confirmed	18	LF	0	LF				1	No	1/D
1 2	Hallway from Element 1 to Stairwell adjacent to Classroom 210	N/A	Concrete Ceiling		Non Suspect ACM	510	SF	10	SF				N/A	N/A	N/A
2	Hallway from Element 1 to Stairwell adjacent to		Concrete Celling		NOTI Suspect ACM			10							IN/A
1 2	Classroom 210	N/A	Concrete Block Wall		Non Suspect ACM	1080	SF	0	SF				N/A	N/A	N/A
1 2	Hallway from Element 1 to Stairwell adjacent to Classroom 210	м	Transite Sills	6260/01/02/AET/BB/2300	Assumed	4	SF	0	SF				1	No	1/D
	Hallway from Element 1 to Stairwell adjacent to														
	Classroom 210	N/A	Cement Floor	0000/04/00/40	Non Suspect ACM	510	SF	0	SF		Mary lands to the transfer of the control of the co		N/A	N/A	N/A
1 3	Classroom 301 Classroom 301	N/A	Pipe Insulation 2-6 inch Fiberglass Ceiling Tile 2' x 4'	6260/01/03/16	Confirmed Non Suspect ACM	24 840	LF SF	0	LF SF		More insulation is likely present above ceiling tiles		N/A	No N/A	1/D N/A
1 3	Classroom 301	N/A	Plaster Ceiling		NAD	840	SF	0	SF				N/A	N/A	N/A
	Classroom 301 Classroom 301	N/A N/A	Plaster Wall Partition Room Dividers		NAD Nac Outstand A OM	1130 290	SF SF	0	SF SF		Wood		N/A N/A	N/A N/A	N/A N/A
	Classroom 301	N/A	Wood Floor		Non Suspect ACM Non Suspect ACM	840	SF	0	SF		WOOd		N/A	N/A	N/A
1 3	Classroom 301	M	Blackboard Glue Dots	6260/01/01/AET/BB/2600	Assumed	50	SF	0	SF				1	No	1/D
	Classroom 301 Closet Classroom 301 Closet	N/A N/A	Fiberglass Ceiling Tile 2' x 4' Plaster Ceiling		Non Suspect ACM NAD	120 120	SF SF	5 0	SF SF				N/A N/A	N/A N/A	N/A N/A
	Classroom 301 Closet	N/A	Plaster Wall		NAD	700	SF	5	SF				N/A	N/A	N/A N/A
1 3	Classroom 301 Closet	N/A	Wood Floor		Non Suspect ACM	120	SF	0	SF				N/A	N/A	N/A
	Classroom 302 Classroom 302	T N/A	Pipe Insulation 2-6 inch Fiberglass Ceiling Tile 2' x 4'	6260/01/03/16	Confirmed Non Suspect ACM	24 840	LF SF	0	LF SF		More insulation is likely present above ceiling tiles		1 N/A	No N/A	1/D N/A
1 3	Classroom 302	N/A	Plaster Ceiling		NAD NAD	840	SF	0	SF				N/A	N/A	N/A
1 3	Classroom 302	N/A	Plaster Wall		NAD	1130	SF	0	SF				N/A	N/A	N/A
	Classroom 302 Classroom 302	N/A N/A	Partition Room Dividers Wood Floor		Non Suspect ACM Non Suspect ACM	290 840	SF SF	0	SF SF		Wood		N/A N/A	N/A N/A	N/A N/A
1 3	Classroom 302	M	Blackboard Glue Dots	6260/01/03/AET/BB/2600	Assumed	50	SF	0	SF				1	No	1/D
1 3	Classroom 302 Closet	T N/A	Pipe Insulation 2-6 inch	6260/01/03/16	Confirmed	12	LF	0	LF		More insulation is likely present above ceiling tiles		1	No	1/D
	Classroom 302 Closet Classroom 302 Closet	N/A N/A	Fiberglass Ceiling Tile 2' x 4' Plaster Ceiling		Non Suspect ACM NAD	120 120	SF SF	0	SF SF				N/A N/A	N/A N/A	N/A N/A
	Classroom 302 Closet	N/A	Plaster Wall		NAD	700	SF	5	SF				N/A	N/A	N/A
	Classroom 302 Closet	N/A	Wood Floor		Non Suspect ACM	120	SF	0	SF				N/A	N/A	N/A
1 3	Boy's Restroom	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	16	LF	0	LF				N/A	N/A	N/A
1 3	Boy's Restroom Boy's Restroom	N/A N/A	Plaster Ceiling Plaster Wall		NAD NAD	160 680	SF SF	0	SF SF				N/A N/A	N/A N/A	N/A N/A
1 3	Boy's Restroom	N/A	Ceramic Tile Wall		Non Suspect ACM	680	SF	0	SF				N/A	N/A	N/A
	Boy's Restroom	N/A	Ceramic Tile Floor		Non Suspect ACM	160	SF	0	SF				N/A	N/A	N/A
	Boy's Restroom Pipe Chase	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	20	LF	0	LF				N/A	N/A	N/A
	Men's Restroom adjacent to Classroom 303	T	Pipe Fitting Insulation	6260/01/03/27	Confirmed	2	EA	0	EA			-	1 1	No	1/D
	Men's Restroom adjacent to Classroom 303 Men's Restroom adjacent to Classroom 303	N/A	Pipe Insulation 2-6 inch Plaster Ceiling	6260/01/03/16	Confirmed NAD	13 64	LF SF	0	LF SF				N/A	No N/A	1/D N/A
	Men's Restroom adjacent to Classroom 303 Men's Restroom adjacent to Classroom 303	N/A N/A	Plaster Ceiling Plaster Wall		NAD NAD	435	SF	0	SF			 	N/A N/A	N/A N/A	N/A N/A
	Men's Restroom adjacent to Classroom 303	N/A	Ceramic Tile Wall		Non Suspect ACM	435	SF	0	SF				N/A	N/A	N/A
	Men's Restroom adjacent to Classroom 303	N/A	Ceramic Tile Floor		Non Suspect ACM	64	SF	0	SF				N/A	N/A	N/A
1 3	Classroom 303	Т	Pipe Insulation 2-6 inch	6260/01/03/16	Confirmed	24	LF	0	LF		More insulation is likely present above ceiling tiles		1	No	1/D
	Classroom 303	N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	672	SF	0	SF				N/A	N/A	N/A
	Classroom 303	N/A	Plaster Ceiling		NAD	672	SF	0	SF				N/A	N/A	N/A
	Classroom 303	N/A	Plaster Wall		NAD NAD	1250	SF	0	SF				N/A	N/A	N/A
	Classroom 303	N/A M	Wood Floor	6260/04/02/457/00/026	Non Suspect ACM	672	SF SF	0	SF SF				N/A	N/A	N/A
1 3	Classroom 303 Classroom 303 Closet	M T	Blackboard Glue Dots Pipe Insulation 2-6 inch	6260/01/03/AET/BB/2600 6260/01/03/16	Assumed Confirmed	65 12	SF LF	0	SF LF				1 1	No No	1/D 1/D
1 3	Classroom 303 Closet	N/A	Plaster Ceiling		NAD	96	SF	0	SF				N/A	N/A	N/A
1 3	Classroom 303 Closet Classroom 303 Closet	N/A N/A	Plaster Wall Wood Floor		NAD Non Support ACM	345 96	SF SF	5	SF SF				N/A N/A	N/A N/A	N/A N/A
1 3	Reading Room between Classrooms 303 and 304	T T	Pipe Insulation 2-6 inch	6260/01/03/16	Non Suspect ACM Confirmed	12	LF	0	LF				1	N/A No	1/D
1 3	Reading Room between Classrooms 303 and 304	N/A	Plaster Ceiling		NAD	270	SF	0	SF				N/A	N/A	N/A
	Reading Room between Classrooms 303 and 304 Reading Room between Classrooms 303 and 304	N/A N/A	Plaster Wall Wood Floor		NAD Non Suspect ACM	650 270	SF SF	0	SF SF			-	N/A N/A	N/A N/A	N/A N/A
1 3		T	Pipe Insulation 2-6 inch	6260/01/03/16	Confirmed	24	LF	1	LF		Was DDC written for this damage?		1	No	2/B
1 3	Classroom 304	N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	870	SF	2	SF				N/A	N/A	N/A
1 3	Classroom 304 Classroom 304	N/A N/A	Plaster Ceiling Plaster Wall		NAD NAD	870 1065	SF SF	0	SF SF				N/A N/A	N/A N/A	N/A N/A
1 3	Classroom 304	N/A	Partition Room Dividers		Non Suspect ACM	350	SF	0	SF		Wood	 	N/A	N/A	N/A

Page		School District of Philadelphia		AH	ERA Three-Year Reins	pection 2015-2016						Reinspection Date: 10/8/2015				
Company Comp		Henry H. Houston Elementary School (K-8)			Room by Room Locati	on Log Report						Building Inspector: Bernard Brunner				
Company Comp			'		•				•			Certificate Number: 45397				
The State 1987																
Part																
P	F	rear Built. 1927	+							1		Certificate Number: ACC-0215-8-010	-		1	$\overline{}$
Part																
Part Common Service Common Service																
P P October Common State C	m I										Catan			D	Manulus	
For Continue			System			Confirmed Assumed NAD	Amount of	SELE	Amount of	SFIF						Response
1 1 1 1 1 1 1 1 1 1	t r	On Site Room Name	Affected	Material Description	HID#	Non Suspect ACM	Material	EA	Damage	EA	for VAT	Comments/Description/Notes		(DP)		Action (RA)
1 1	1 3	Classroom 304	N/A	Wood Floor		Non Suspect ACM	870	SF	0	SF				N/A	N/A	N/A
1 1 1 2 2 2 2 3 5 5 5 5 5 5 5 5 5				Blackboard Glue Dots	6260/01/03/AET/BB/2600	Assumed	110	SF							No	1/D
1 1 Security Security 1 1 1 1 1 1 1 1 1									-							
1 1 Control 20 Control 20 10 10 10 10 10 10 10													_			
1 1	1 3	Classroom 304 Closet											-			
1 Department 1	1 3	Hallway Closet next to Classroom 305				X					Х	No Access				X
1 1 Septembro 20			Т		6260/01/03/16	Confirmed	20	LF	0	LF		More insulation is likely present above ceiling tiles		1	No	1/D
1 1 1 1 1 1 1 1 1 1	1 3	Classroom 305				Non Suspect ACM	4	LF		LF						
1 1 Content 10						Non Suspect ACM										
1 Content 15	1 3	Classroom 305		Plaster Ceiling Plaster Wall			1045	SF					_			
1 1 Control 10 Control 1							350	SF	-	SF		Wood				
1 1	1 3	Classroom 305		Wood Floor	·	Non Suspect ACM	812			SF				N/A		N/A
1 1 Control M. Control					6260/01/03/AET/BB/2600											
1 1 Description 150 Description 15	1 3	Classroom 305 Closet	N/A N/A				120				-			N/A N/A		N/A N/A
1 1 Content 300 Chest																
1 3	1 3	Classroom 305 Closet		Wood Floor		Non Suspect ACM	120	SF	0	SF					N/A	N/A
1 3 Classcon 2004	1 3	Classroom 306	T	Pipe Insulation 2-6 inch	6260/01/03/16		24					More insulation is likely present above ceiling tiles		1		
1 3 Casseron 250									-							
1 3 Classeron MA									-		-					
1 2														1471		
1 1 1 1 1 1 1 1 1 1	1 3	Classroom 306										Wood				
1 2 Casseron 360 Coset					6260/01/03/AFT/RR/2600											
1 2 Colsection 25 Coper T Pipe Installation 2 in the 1 No. 10 10 10 10 10 10 10 1			T						-	EA		More insulation is likely present above ceiling tiles				
1 2 Generom 200 Closest	1 3	Classroom 306 Closet	Т	Pipe Insulation 2-6 inch	6260/01/03/16	Confirmed						More insulation is likely present above ceiling tiles				
1 3 Glassoom SN Closet																
1 3 Glasseom St Closes NA Person NA Person NA Person NA NA NA NA NA NA NA N																
3 Girk Restroom													_			
1 3 Girk Restorom													_			
1 3 Girk Restroom NA	1 3	Girl's Restroom				NAD								N/A		
1 3 Griff Retistorn NA	1 3	Girl's Restroom				NAD	680	SF	0	SF				N/A		
1 3 3 2 2 2 3 2 3 3 3	1 3	Girl's Restroom	N/A			Non Suspect ACM	680							N/A	N/A	N/A
1 3 Custodial Closet by Giff Restroom NA Plaster Celling NA NA NA NA NA NA NA N								_								
1 3 3 2 2016 2016 2017 2018													_			
1 3 Custodic Closet by Griffs Restroom N/A Plaster (Farly Wall Non Suspend ACM 195 SF 0 SF Non Signator ACM 13 3 Custodic Closet by Griffs Restroom N/A Ceramic Tie Wall Non Suspend ACM 20 SF 0 SF Non Signator ACM N/A													_			
1 3 Castodid Closet by Gir's Restroom													_			
1 3 Classors 307																
1 3 Classroom 327																
1 3 Classroom 307			N/A T		6260/01/03/16							More insulation is likely present above ceiling tiles	+			
T 3 Classroom 307			N/A		0200/01/03/10		840	SF		SF		INIOTE ITISUIATION IS likely present above celling tiles				
1 3 Classroom 307	1 3	Classroom 307	N/A	Plaster Ceiling		NAD	840	SF		SF				N/A	N/A	N/A
1 3 Classroom 307	1 3	Classroom 307		Plaster Wall												
1 3 Classroom 307						Non Suspect ACM	290					WOOD DOOR				N/A N/A
1 3 Classroom 307 Closet T Pipe Fitting Insulation 626001103/27 Confirmed 1 EA 0 EA More insulation is likely present above ceiling tiles 1 No 1/D 1 3 Classroom 307 Closet N/A Fiberglass Ceiling Tile 2 * 4" No No Suspect ACM 120 SF 0 SF 3 Classroom 307 Closet N/A Fiberglass Ceiling Tile 2 * 4" No No Suspect ACM 120 SF 0 SF 4 3 Classroom 307 Closet N/A Pilaster Vall No No Suspect ACM 120 SF 0 SF 5 Classroom 307 Closet N/A Pilaster Vall No No Suspect ACM 120 SF 0 SF 4 3 Classroom 307 Closet N/A Pilaster Vall No No Suspect ACM 120 SF 0 SF 5 Classroom 307 Closet N/A Pilaster Vall No No Suspect ACM 120 SF 0 SF 6 Classroom 307 Closet N/A Pilaster Vall No No Suspect ACM 120 SF 0 SF 7 Pipe Insulation 2-6 inch 6260/01/03/16 Confirmed 24 LF 0 LF More insulation is likely present above ceiling tiles 1 No 1/D 8 Classroom 308 T Pipe Insulation 2-6 inch 6260/01/03/16 Confirmed 24 LF 0 LF More insulation is likely present above ceiling tiles 1 No 1/D 8 Classroom 308 N/A Pilaster Ceiling N/A	1 3	Classroom 307	M		6260/01/03/AET/BB/2600								_			
1 3 Classroom 307 Closet						Confirmed			0	EA		More insulation is likely present above ceiling tiles		1		1/D
1 3 Classroom 307 Closet							13		0					1		
1 3 Classroom 307 Closet	1 3	Classroom 307 Closet	N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	120	SF	0	SF		,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,				N/A
1 3 Classroom 307 Closet	1 3	Classroom 307 Closet	N/A	Plaster Ceiling		NAD	120							N/A		
1 3 Classroom 308	1 3	Classroom 307 Closet	N/A				700			SF				N/A N/A	N/A	
1 3 Classroom 308	1 3	Classroom 308			6260/01/03/16							More insulation is likely present above ceiling tiles				
1 3 Classroom 308	1 3	Classroom 308	N/A	Fiberglass Ceiling Tile 2' x 4'	2222.27700770	Non Suspect ACM	840	SF	3	SF		The state of the s		N/A	N/A	N/A
1 3 Classroom 308	1 3	Classroom 308	N/A	Plaster Ceiling		NAD	840							N/A	N/A	N/A
1 3 Classroom 308												Wood	+			
1 3 Classroom 308 M Blackboard Glue Dots 6260/01/03/LET/BB/2600 Assumed 90 SF 0 SF	1 3	Classroom 308				Non Suspect ACM	840	SF		SF	-	YYUUU	+			
1 3 Classroom 308 Closet T Pipe Insulation 2-6 inch 6280/01/03/16 Confirmed 12 LF 0 LF More insulation is likely present above ceiling tiles 1 No 1/D	1 3						90	SF		SF						1/D
1 3 Classroom 308 Closet			Т			Confirmed	12	LF	0	LF		More insulation is likely present above ceiling tiles		1		
1 3 Classroom 308 Closet N/A Plaster Wall NAD 700 SF 0 SF NSF N/A			N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	120		0					N/A	N/A	N/A
1 3 Classroom 308 Closet N/A Plaster Wall NAD 700 SF 0 SF NSF N/A			N/A	Plaster Ceiling		NAD	120		0					N/A	N/A	N/A
1 3 Classroom 309 T Pipe Insulation 2-6 inch 6260/01/03/16 Confirmed 24 LF 0 LF More insulation is likely present above ceiling tiles 1 N N N N N N N N N	1 3	Classroom 308 Closet	N/A	Plaster Wall		NAD	700	SF	0	SF				N/A	N/A	N/A
1 3 Classroom 309 T Pipe Insulation 2-6 inch 6260/01/03/16 Confirmed 24 LF 0 LF More insulation is likely present above ceiling tiles 1 N N 1/D 1 3 Classroom 309 N/A Fiberglass Ceiling Tile 2'x 4' Non Suspect ACM 870 SF 0 SF N N/A	1 3	Classroom 308 Closet	N/A			Non Suspect ACM		SF	0					N/A		N/A
1 3 Classroom 309 N/A Plaster Ceiling NAD 870 SF 0 SF N/A	1 3	Classroom 309	T		6260/01/03/16	Confirmed			0			More insulation is likely present above ceiling tiles		1		
1 3 Classroom 309 N/A Plaster Wall NAD 1415 SF 0 SF N/A N/A N/A N/A	1 3	Classroom 309					870	SF		SF						
1 3 Classroom 309 N/A Wood Floor Non Suspect ACM 870 SF 0 SF N/A N/A N/A N/A N/A N/A	1 3	Classroom 309											_			
	1 3	Classroom 309				Non Suspect ACM	870		0					N/A		N/A

	School District of Philadelphia		АН	ERA Three-Year Reins							Reinspection Date: 10/8/2015				
	Henry H. Houston Elementary School (K-8)			Room by Room Locati	ion Log Report			_			Building Inspector: Bernard Brunner	1			
	7300 Rural Lane, Philadelphia, PA 19119										Certificate Number: 45397	_			
	ULCS# 6260										Management Planner: Monique Causley				ļ
	Year Built: 1927										Certificate Number: ACC-0215-8-010				
E															
m e e n		System Affected	Material Description	HID#	Confirmed, Assumed, NAD, Non Suspect ACM	Amount of Material	SF LF EA	Amount of Damage	SF LF EA	Color required for VAT	Comments/Description/Notes	Attic Crawl Space Ranking	Damage Potential (DP)	Newly Friable (NF)	Response Action (RA)
1 3		M	Blackboard Glue Dots	6260/01/03/AET/BB/2600	Assumed	190	SF	0	SF	10. 17.1	o difficility booking to the control of the control	Ranking	1	No	1/D
1 3		N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	120	SF	0	SF				N/A	N/A	N/A
1 3	Classroom 309 Closet	N/A	Plaster Ceiling		NAD	120	SF	0	SF				N/A	N/A	N/A
1 3	Classroom 309 Closet	N/A	Plaster Wall		NAD	700	SF	0	SF				N/A	N/A	N/A
1 3	Classroom 309 Closet	N/A	Wood Floor		Non Suspect ACM	120	SF	0	SF				N/A	N/A	N/A
1 3	Office 309A	N/A	Plaster Ceiling		NAD	235	SF	0	SF		No Access		N/A	N/A	N/A
1 3	Office 309A	N/A	Plaster Wall		NAD	625	SF	0	SF				N/A	N/A	N/A
1 3	Office 309A	M	Floor Tile VAT 12" x 12"	6260/01/03/TT	Assumed	118	SF	0	SF	Red			1	No	1/D
1 3	Office 309A	M	Floor Tile VAT 12" x 12"	6260/01/03/TT	Assumed	117	SF	0	SF	Blue			1	No	1/D
1 3	Office 309A	N/A	Wood Floor		Non Suspect ACM	235	SF	0	SF				N/A	N/A	N/A
1 3	Office 309A Restroom	N/A	Plaster Ceiling		NAD	80	SF	0	SF		No Access		N/A	N/A	N/A
1 3	Office 309A Restroom	N/A	Ceramic Tile Wall		Non Suspect ACM	435	SF	0	SF				N/A	N/A	N/A
	Office 309A Restroom	N/A	Ceramic Tile Floor		Non Suspect ACM	80	SF	0	SF				N/A	N/A	N/A
	Stairwell adjacent to Classroom 301	N/A	Concrete Ceiling		Non Suspect ACM	180	SF	0	SF				N/A	N/A	N/A
	Stairwell adjacent to Classroom 301	N/A	Brick Wall		Non Suspect ACM	1120	SF	0	SF				N/A	N/A	N/A
	Stairwell adjacent to Classroom 301	N/A	Cement Floor		Non Suspect ACM	180	SF	0	SF				N/A	N/A	N/A
	Hallway outside Rooms 301-302	Т	Pipe Insulation 2-6 inch	6260/01/03/16	Confirmed	24	LF	0	LF		More insulation is likely present above ceiling tiles		1	No	1/D
	Hallway outside Rooms 301-302	N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	560	SF	13	SF		,,,		N/A	N/A	N/A
	Hallway outside Rooms 301-302	N/A	Plaster Ceiling		NAD	560	SF	0	SF				N/A	N/A	N/A
	Hallway outside Rooms 301-302	N/A	Plaster Wall		NAD	1780	SF	0	SF				N/A	N/A	N/A
	Hallway outside Rooms 301-302	N/A	Marble Wall		Non Suspect ACM	595	SF	0	SF				N/A	N/A	N/A
	Hallway outside Rooms 301-302	N/A	Cement Floor		Non Suspect ACM	560	SF	0	SF				N/A	N/A	N/A
	Hallway outside Rooms 303-306	N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	1105	SF	3	SF				N/A	N/A	N/A
	Hallway outside Rooms 303-306	N/A	Plaster Ceiling		NAD	1105	SF	0	SF				N/A	N/A	N/A
	Hallway outside Rooms 303-306	N/A	Plaster Wall		NAD	2260	SF	0	SF				N/A	N/A	N/A
	Hallway outside Rooms 303-306	N/A	Marble Wall		Non Suspect ACM	755	SF	0	SF				N/A	N/A	N/A
	Hallway outside Rooms 303-306	N/A	Cement Floor		Non Suspect ACM	1105	SF	0	SF				N/A	N/A	N/A
1 1	Stainwell B	N/A	Plaster Ceiling		NAD NAD	240	SF	0	SF				N/A	N/A	N/A
	Stainwell B	N/A	Plaster Wall		NAD	1360	SF	0	SF				N/A	N/A	N/A
	Stairwell B	N/A	Marble Wall		Non Suspect ACM	455	SF	0	SF				N/A	N/A	N/A
	Stainwell B	N/A	Cement Floor		Non Suspect ACM	240	SF	0	SF				N/A	N/A	N/A
	Stairwell A	N/A	Plaster Ceiling		NAD NAD	240	SF	0	SF				N/A	N/A	N/A
	Stainwell A	N/A	Plaster Wall		NAD	1360	SF	5	SF				N/A	N/A	N/A
	Stainwell A	N/A	Marble Wall		Non Suspect ACM	455	SF	0	SF				N/A	N/A	N/A
	Stainwell A	N/A	Cement Floor		Non Suspect ACM	240	SF	0	SF				N/A	N/A	N/A
		T		6260/01/03/16	Confirmed	240	LF	0	LF		Mare inculation is likely assessed above spiling tiles		1	No No	1/D
	Hallway outside Rooms 307-308		Pipe Insulation 2-6 inch	6260/01/03/16				2			More insulation is likely present above ceiling tiles				
	Hallway outside Rooms 307-308 Hallway outside Rooms 307-308	N/A N/A	Fiberglass Ceiling Tile 2' x 4' Plaster Ceiling		Non Suspect ACM NAD	560 560	SF SF	0	SF SF				N/A N/A	N/A N/A	N/A N/A
	Hallway outside Rooms 307-308 Hallway outside Rooms 307-308	N/A N/A	Plaster Celling Plaster Wall		NAD	1780	SF	0	SF				N/A N/A	N/A N/A	N/A N/A
	Hallway outside Rooms 307-308 Hallway outside Rooms 307-308	N/A N/A	Marble Wall		Non Suspect ACM	595	SF	0	SF	-			N/A N/A	N/A N/A	N/A N/A
	Hallway outside Rooms 307-308 Hallway outside Rooms 307-308	N/A N/A	Cement Floor		Non Suspect ACM Non Suspect ACM	560	SF	0	SF				N/A N/A	N/A N/A	N/A N/A
	Fire Tower adjacent to Classroom 308	N/A N/A				240	SF	0	SF				N/A N/A	N/A N/A	N/A N/A
	Fire Tower adjacent to Classroom 308 Fire Tower adjacent to Classroom 308	N/A N/A	Concrete Ceiling Brick Wall		Non Suspect ACM Non Suspect ACM	1360	SF	0	SF				N/A N/A	N/A N/A	N/A N/A
	Fire Tower adjacent to Classroom 308 Fire Tower adjacent to Classroom 308	N/A N/A	Cement Floor		Non Suspect ACM	240	SF	0	SF				N/A N/A	N/A N/A	N/A N/A
	Staff Restroom adjacent to Boy's Restroom	N/A N/A	Fiberglass Pipe Insulation		Non Suspect ACM	3	SF	0	SF		No access		N/A N/A	N/A N/A	N/A N/A
	Staff Restroom adjacent to Boy's Restroom Staff Restroom adjacent to Boy's Restroom	N/A N/A	Concrete Ceiling		Non Suspect ACM	77	SF	0	SF		110 000000		N/A N/A	N/A N/A	N/A N/A
	Staff Restroom adjacent to Boy's Restroom Staff Restroom adjacent to Boy's Restroom	N/A N/A	Ceramic Tile Wall		Non Suspect ACM	1632	SF	0	SF				N/A N/A	N/A N/A	N/A N/A
	Staff Restroom adjacent to Boy's Restroom Staff Restroom adjacent to Boy's Restroom	N/A N/A	Ceramic Tile Wall		Non Suspect ACM Non Suspect ACM	77	SF	0	SF				N/A N/A	N/A N/A	N/A N/A
	Staff Restroom adjacent to Boy's Restroom Staff Restroom adjacent to Boy's Restroom Pipe Chase	X X	Ceramic Tile Floor		Non Suspect ACM	X	X	X	X	x			N/A X	N/A X	X X
	Staff Restroom adjacent to Boy's Restroom Pipe Chase Staff Restroom adjacent to Boy's Restroom Closet	N/A	Concrete Ceiling		Non Suspect ACM	50	SF	0	SF	<u> </u>			N/A	N/A	N/A
	Staff Restroom adjacent to Boy's Restroom Closet Staff Restroom adjacent to Boy's Restroom Closet	N/A N/A	Brick Wall		Non Suspect ACM Non Suspect ACM	200	SF	0	SF				N/A N/A	N/A N/A	N/A N/A
	Staff Restroom adjacent to Boy's Restroom Closet Staff Restroom adjacent to Boy's Restroom Closet	N/A N/A	Cement Floor		Non Suspect ACM	50	SF	0	SF			—	N/A N/A	N/A N/A	N/A N/A
	Storage Closet adjacent to Boy's Restroom Closet Storage Closet adjacent to Boy's Restroom	T T	Pipe Fitting Insulation	6260/01/0B/08	Confirmed	14	EA	0	EA				1 1	N/A No	1/D
		T						0					1		
	Storage Closet adjacent to Boy's Restroom	· ·	Pipe Insulation 2-6 inch	6260/01/0B/05	Confirmed	20	LF		LF				-	No	1/D
	Storage Closet adjacent to Boy's Restroom	N/A	Concrete Ceiling		Non Suspect ACM	40	SF	0	SF			-	N/A	N/A	N/A
	Storage Closet adjacent to Boy's Restroom	N/A	Brick Wall		Non Suspect ACM	315	SF	0	SF	_			N/A	N/A	N/A
	Storage Closet adjacent to Boy's Restroom	N/A	Cement Floor		Non Suspect ACM	40	SF	0	SF	,,		-	N/A	N/A	N/A
1 E	Storage Closet adjacent to Boy's Restroom Pipe Chase Boy's Restroom	X N/A	X Fiberglass Pipe Insulation		X Non Suspect ACM	90	X IF	X 0	X IF	X		-	X N/A	X N/A	X N/A
	Boy's Restroom	N/A	Concrete Ceiling		Non Suspect ACM	575	SF	400					N/A	N/A	N/A
1 E	Boy's Restroom	N/A	Ceramic Tile Wall		Non Suspect ACM	1150	SF	0	SF SF				N/A	N/A	N/A
1 E	Boy's Restroom	N/A	Ceramic Tile Floor		Non Suspect ACM	575	SF	0	SF				N/A	N/A	N/A
1 E	Boy's Restroom Pipe Chase for Urinals	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	20	LF	0	LF			1	N/A	N/A	N/A

	School District of Philadelphia		Al	IERA Three-Year Reins	pection 2015-2016						Reinspection Date: 10/8/2015				
	Henry H. Houston Elementary School (K-8)			Room by Room Locat							Building Inspector: Bernard Brunner	1			
	7300 Rural Lane, Philadelphia, PA 19119	1			203			1			Certificate Number: 45397	1			
	ULCS# 6260										Management Planner: Monique Causley	1			
	Year Built: 1927										Certificate Number: ACC-0215-8-010	+			
E	Tear Built: 1927	 									Certificate Number: ACC-0215-8-010				$\overline{}$
1															
e	; ,														
	6									Color		Attic Crawl	Damage	Newly	
n	o	System			Confirmed, Assumed, NAD,	Amount of	SF LF	Amount of	SF LF	required		Space	Potential	Friable	Response
t	On Site Room Name	Affected	Material Description	HID#	Non Suspect ACM	Material	EA	Damage	EA	for VAT	Comments/Description/Notes	Ranking	(DP)	(NF)	Action (RA)
	Boy's Restroom Pipe Chase for Urinals	N/A	Concrete Ceiling		Non Suspect ACM	66	SF	0	SF			-	N/A	N/A	N/A
	Boy's Restroom Pipe Chase for Urinals	N/A	Concrete Block Wall		Non Suspect ACM	340	SF	0	SF				N/A	N/A	N/A
	Boy's Restroom Pipe Chase for Urinals	N/A	Brick Wall		Non Suspect ACM	265	SF	0	SF				N/A	N/A	N/A
1	Boy's Restroom Pipe Chase for Urinals	N/A	Cement Floor		Non Suspect ACM	66	SF	0	SF		No Access. Pipe chase can also be accessed from adjacen		N/A	N/A	N/A
	Boy's Restroom Pipe Chase for Toilets	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	40	LF	0	LF		storage room.	`	N/A	N/A	N/A
	B Former Art Room	T	Pipe Insulation 2-6 inch	6260/01/0B/05	Confirmed	108	LF	0	LF				1	No	1/D
	Former Art Room Former Art Room	N/A M	Fiberglass Pipe Insulation Ceiling Tile 1' x 1'	6260/01/0B/AET/BB/1710	Non Suspect ACM Assumed	123 875	LF SF	0	LF SF				N/A 1	N/A	1/D
1	B Former Art Room	N/A	Plaster Ceiling	6260/01/0B/AE1/BB/1/10	NAD	875	SF	0	SF				N/A	No N/A	N/A
1	Former Art Room	N/A	Plaster Wall		NAD	720	SF	20	SF		Water damage		N/A	N/A	N/A
	Former Art Room	N/A	Brick Wall		Non Suspect ACM	720	SF	0	SF				N/A	N/A	N/A
	Former Art Room	N/A	Wood Floor		Non Suspect ACM	875	SF	0	SF				N/A	N/A	N/A
	Former Art Room	M	Spline Ceiling Glue Dots	6260/01/0B/AET/BB/2603	Assumed	875	SF	0	SF			1	1	No	1/D
	Former Art Room Small Front Closet	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	20	LF	0	LF		No access	-	N/A	N/A	N/A
	Former Art Room Small Front Closet	N/A	Concrete Ceiling		Non Suspect ACM	110	SF	0	SF	-		+	N/A	N/A	N/A
	3 Former Art Room Small Front Closet	N/A	Brick Wall		Non Suspect ACM	440	SF	0	SF			+	N/A	N/A	N/A
	Former Art Room Small Front Closet By Former Art Room Back Closet	N/A T	Wood Floor Pipe Insulation 2-6 inch	6260/01/0B/05	Non Suspect ACM Confirmed	110 37	SF	0	SF	_		+	N/A	N/A No	N/A 1/D
	B Former Art Room Back Closet	N/A	Plaster Ceiling	0200/01/06/03	NAD	37 50	SF	50	SF				N/A	N/A	N/A
1	Former Art Room Back Closet	N/A	Plaster Wall		NAD	180	SF	180	SF		No access. Limited visual inspection through window		N/A	N/A	N/A
	B Former Art Room Back Closet	N/A	Brick Wall		Non Suspect ACM	180	SF SF	0	SF SF				N/A	N/A N/A	N/A
	3 Former Art Room Back Closet 3 Former Art Room Large Storage Room	N/A T	Wood Floor Pipe Insulation 2-6 inch	6260/01/0B/05	Non Suspect ACM Confirmed	50 14	LF	0	LF				N/A 1	N/A No	N/A 1/D
	Former Art Room Large Storage Room	N/A	Fiberglass Pipe Insulation	0200101102100	Non Suspect ACM	18	LF	0	LF				N/A	N/A	N/A
1	Former Art Room Large Storage Room	N/A	Plaster Ceiling		NAD	120	SF	50	SF				N/A	N/A	N/A
1	Former Art Room Large Storage Room Former Art Room Large Storage Room	N/A N/A	Plaster Wall Wood Floor		NAD Non Suspect ACM	700 120	SF SF	200	SF SF				N/A N/A	N/A N/A	N/A N/A
	Stairs to Exterior Entrance near Boy' Restroom	N/A	Concrete Ceiling		Non Suspect ACM	100	SF	0	SF				N/A	N/A	N/A
	Stairs to Exterior Entrance near Boy' Restroom	N/A	Brick Wall		Non Suspect ACM	240	SF	0	SF				N/A	N/A	N/A
	3 Stairs to Exterior Entrance near Boy' Restroom	N/A	Cement Floor		Non Suspect ACM	100	SF	0	SF				N/A	N/A	N/A
	B Hallway outside Boy's Restroom	Т	Pipe Insulation 2-6 inch	6260/01/0B/05	Confirmed	30	LF	0	LF				1	No	1/D
	B Hallway outside Boy's Restroom	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	165	SF	0	SF				N/A	N/A	N/A
	Hallway outside Boy's Restroom	N/A	Concrete Ceiling		Non Suspect ACM	385	SF	0	SF				N/A	N/A	N/A
	Hallway outside Boy's Restroom	N/A	Brick Wall		Non Suspect ACM	1500	SF	0	SF				N/A	N/A	N/A
	Hallway outside Boy's Restroom	N/A	Cement Floor		Non Suspect ACM	385	SF	0	SF				N/A	N/A	N/A
	Boiler Room	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	500	LF	0	LF				N/A	N/A	N/A
	Boiler Room	N/A	Duct Work		Non Suspect ACM	45	LF	0	LF				N/A	N/A	N/A
	Boiler Room	N/A	Boiler Breeching		Non Suspect ACM	300	SF	0	SF				N/A	N/A	N/A
	Boiler Room	N/A	Concrete Ceiling		Non Suspect ACM	1480	SF	0	SF				N/A	N/A	N/A
	Boiler Room	N/A	Concrete Wall		Non Suspect ACM	2280	SF	0	SF				N/A	N/A	N/A
	Boiler Room	N/A	Brick Wall		Non Suspect ACM	800	SF	0	SF				N/A	N/A	N/A
	Boiler Room	N/A	Cement Floor		Non Suspect ACM	1480	SF	0	SF				N/A	N/A	N/A
	Water Meter Room	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	40	LF	20	LF				N/A	N/A	N/A
	Water Meter Room	N/A	Concrete Ceiling		Non Suspect ACM	370	SF	0	SF				N/A	N/A	N/A
	3 Water Meter Room 3 Water Meter Room	N/A N/A	Concrete Wall		Non Suspect ACM	940	SF SF	0	SF SF				N/A N/A	N/A N/A	N/A N/A
	3 Oil Pump Room	N/A	Cement Floor		Non Suspect ACM	370	LF	0 15	LF				N/A	N/A	N/A
1	3 Oil Pump Room	N/A	Fiberglass Pipe Insulation Concrete Ceiling		Non Suspect ACM Non Suspect ACM	100 525	SF	0	SF				N/A	N/A	N/A
1	3 Oil Pump Room	N/A	Concrete Wall		Non Suspect ACM	400	SF	0	SF			1	N/A	N/A	N/A
	3 Oil Pump Room	N/A	Brick Wall		Non Suspect ACM	1600	SF	0	SF			1	N/A	N/A	N/A
	3 Oil Pump Room	N/A	Cement Floor		Non Suspect ACM	525	SF	0	SF				N/A	N/A	N/A
	Mechanical Room between Boiler Room & Fan Room	T	Pipe Insulation 2-6 inch	6260/01/0B/05	Confirmed	40	LF	0	LF				1	No	1/D
	Mechanical Room between Boiler Room & Fan Room	T	Pipe Insulation > 6 inch	6260/01/0B/04	Confirmed	60	LF	0	LF			1	1	No	1/D
	Mechanical Room between Boiler Room & Fan Room	N/A	Concrete Ceiling		Non Suspect ACM	1400	SF	0	SF				N/A	N/A	N/A
	Mechanical Room between Boiler Room & Fan Room	N/A	Concrete Wall		Non Suspect ACM	3000	SF	0	SF				N/A	N/A	N/A
1	Mechanical Room between Boiler Room & Fan Room	N/A	Cement Floor		Non Suspect ACM	1400	SF	0	SF				N/A	N/A	N/A
	Boiler Room Hallway	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	115	LF	0	LF				N/A	N/A	N/A
	Boiler Room Hallway	N/A	Concrete Ceiling		Non Suspect ACM	152	SF	0	SF				N/A	N/A	N/A
	Boiler Room Hallway	N/A	Concrete Wall		Non Suspect ACM	610	SF	0	SF				N/A	N/A	N/A
	Boiler Room Hallway	N/A	Brick Wall		Non Suspect ACM	675	SF	0	SF				N/A	N/A	N/A
	Boiler Room Hallway	N/A	Cement Floor		Non Suspect ACM	152	SF	0	SF				N/A	N/A	N/A
	Boiler Room Hallway Storage Room	N/A	Plaster Ceiling		NAD	140	SF	0	SF				N/A	N/A	N/A
1	Boiler Room Hallway Storage Room Boiler Room Hallway Storage Room	N/A N/A	Plaster Wall Cement Floor		NAD Non Suspect ACM	300 140	SF SF	0	SF SF				N/A N/A	N/A N/A	N/A N/A

	School District of Philadelphia		АН	ERA Three-Year Reinsp							Reinspection Date: 10/8/2015				
	Henry H. Houston Elementary School (K-8)			Room by Room Locati	on Log Report						Building Inspector: Bernard Brunner				
	7300 Rural Lane, Philadelphia, PA 19119										Certificate Number: 45397				
	ULCS# 6260										Management Planner: Monique Causley	ļ			
	Year Built: 1927			1							Certificate Number: ACC-0215-8-010				
E I e F m I e o n o		System Affected			Confirmed, Assumed, NAD,	Amount of	SF_LF	Amount of	SF_LF	Color required		Attic Crawl Space	Damage Potential	Newly Friable	Response
t r	On Site Room Name		Material Description	HID#	Non Suspect ACM	Material	EA	Damage	EA	for VAT	Comments/Description/Notes	Ranking	(DP)	(NF)	Action (RA)
	Fan Room Fan Room	T N/A	Pipe Insulation > 6 inch Fiberglass Pipe Insulation	6260/01/0B/04	Confirmed Non Suspect ACM	30 150	LF LF	15	LF LF				N/A	No N/A	1/D N/A
	Fan Room	M	Vibration Damper Cloth	6260/01/0B/CC	Assumed	40	SF	0	SF				1	No	1/D
	Fan Room	N/A	Concrete Ceiling	0200/01/08/00	Non Suspect ACM	832	SF	832	SF				N/A	N/A	N/A
	Fan Room	N/A	Brick Wall		Non Suspect ACM	1860	SF	1860	SF				N/A	N/A	N/A
1 B	Fan Room	N/A	Cement Floor		Non Suspect ACM	832	SF	0	SF				N/A	N/A	N/A
	Physical Therapy Room	T	Pipe Insulation 2-6 inch	6260/01/0B/05	Confirmed	111	LF	0	LF				1	No	1/D
	Physical Therapy Room	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	50	SF	0	SF				N/A	N/A	N/A
	Physical Therapy Room	N/A	Plaster Ceiling		NAD	520	SF	0	SF				N/A	N/A	N/A
	Physical Therapy Room	N/A M	Brick Wall Floor Tile VAT 12" x 12"	6260/01/0B/RR	Non Suspect ACM Assumed	1100	SF SF	0	SF SF	Cross			N/A 1	N/A	N/A 1/D
	Physical Therapy Room Physical Therapy Room	N/A	Wood Floor	6260/01/0B/RR	Non Suspect ACM	520 520	SF	0	SF	Grey			N/A	No N/A	N/A
	Physical Therapy Room Closet	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	21	LF	0	LF				N/A	N/A	N/A
	Physical Therapy Room Closet	N/A	Plaster Ceiling		NAD	42	SF	0	SF				N/A	N/A	N/A
	Physical Therapy Room Closet	N/A	Brick Wall		Non Suspect ACM	160	SF	0	SF				N/A	N/A	N/A
	Physical Therapy Room Closet	N/A	Wood Floor		Non Suspect ACM	42	SF	0	SF				N/A	N/A	N/A
1 B	Physical Therapy Room Closet	М	Vibration Damper Cloth	6260/01/0B/CC	Assumed	1	SF	0	SF				1	No	1/D
	Girl's Restroom	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	90	LF	0	LF				N/A	N/A	N/A
	Girl's Restroom	N/A	Concrete Ceiling		Non Suspect ACM	506	SF	0	SF				N/A	N/A	N/A
	Girl's Restroom	N/A	Ceramic Tile Wall		Non Suspect ACM	1080	SF	0	SF				N/A	N/A	N/A
	Girl's Restroom Girl's Restroom Pipe Chase	N/A N/A	Ceramic Tile Floor Fiberglass Pipe Insulation		Non Suspect ACM	506	SF SF	0	SF SF		No. According to the control of the		N/A N/A	N/A N/A	N/A N/A
	Storage Closet adjacent to Girl's Restroom	N/A N/A	Fiberglass Pipe Insulation Fiberglass Pipe Insulation		Non Suspect ACM Non Suspect ACM	20 17	LF	0	LF		No Access. Pipe chase can also be accessed from hallway.		N/A N/A	N/A N/A	N/A N/A
	Storage Closet adjacent to Girl's Restroom	N/A	Concrete Ceiling		Non Suspect ACM	20	SF	0	SF				N/A	N/A	N/A
	Storage Closet adjacent to Girl's Restroom	N/A	Brick Wall		Non Suspect ACM	100	SF	0	SF				N/A	N/A	N/A
1 B		N/A	Cement Floor		Non Suspect ACM	20	SF	0	SF				N/A	N/A	N/A
1 B		N/A	Fiberglass Pipe Insulation		Non Suspect ACM	60	SF	0	SF				N/A	N/A	N/A
	Hallway outside Girl's Restroom	T	Pipe Insulation 2-6 inch	6260/01/0B/05	Confirmed	263	LF	0	LF				1	No	1/D
	Hallway outside Girl's Restroom	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	200	LF	0	LF				N/A	N/A	N/A
1 B		N/A	Concrete Ceiling		Non Suspect ACM	600	SF	0	SF				N/A	N/A	N/A
1 B		N/A	Brick Wall		Non Suspect ACM	1200	SF SF	0	SF SF				N/A	N/A	N/A
1 B		N/A T	Cement Floor Pipe Insulation 2-6 inch	6260/01/0B/05	Non Suspect ACM Confirmed	600 10	LF	0	LF				N/A 1	N/A No	N/A 1/D
	Stairwell adjacent to Girl's Restroom	N/A	Concrete Ceiling	0200101102103	Non Suspect ACM	180	SF	0	SF				N/A	N/A	N/A
	Stairwell adjacent to Girl's Restroom	N/A	Brick Wall		Non Suspect ACM	1120	SF	0	SF				N/A	N/A	N/A
	Stairwell adjacent to Girl's Restroom	N/A	Cement Floor		Non Suspect ACM	180	SF	0	SF				N/A	N/A	N/A
1 B		N/A	Plaster Ceiling		NAD	2800	SF	0	SF				N/A	N/A	N/A
1 B		N/A	Brick Wall		Non Suspect ACM	3520	SF	0	SF				N/A	N/A	N/A
1 B	Gym Gym Small Storage Room Closest to Building Engineer's	N/A	Wood Floor		Non Suspect ACM	2800	SF	0	SF				N/A	N/A	N/A
1 B	Office	N/A	Plaster Ceiling		NAD	168	SF	168	SF			L	N/A	N/A	N/A
1 B	Gym Small Storage Room Closest to Building Engineer's Office	N/A	-		Non Suggest ACM	625	SF	0	SF				N/A	N/A	N/A
	Gym Small Storage Room Closest to Building Engineer's		Brick Wall		Non Suspect ACM	625									
1 B	Office	N/A	Wood Floor		Non Suspect ACM	168	SF	0	SF				N/A	N/A	N/A
	Gym Office	N/A	Plaster Ceiling		NAD	108	SF	0	SF				N/A	N/A	N/A
	Gym Office	N/A	Brick Wall		Non Suspect ACM	580	SF	0	SF				N/A	N/A	N/A
	Gym Office Gym Large Storage Room on Boy's Restroom Side	N/A N/A	Wood Floor Fiberglass Pipe Insulation		Non Suspect ACM Non Suspect ACM	108 100	SF LF	0	SF LF				N/A N/A	N/A N/A	N/A N/A
	Gym Large Storage Room on Boy's Restroom Side	N/A	Glass Block Ceiling		Non Suspect ACM	600	SF	0	SF		Could not walk the entire room due to stored materials		N/A	N/A	N/A
	Gym Large Storage Room on Boy's Restroom Side	N/A	Brick Wall		Non Suspect ACM	2280	SF	0	SF		Source Hot Walk the Chillie room due to stored materials		N/A	N/A	N/A
	Gym Large Storage Room on Boy's Restroom Side	N/A	Cement Floor		Non Suspect ACM	600	SF	0	SF				N/A	N/A	N/A
	Gym Large Storage Room on Girl's Restroom Side	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	100	LF	0	LF		No Access		N/A	N/A	N/A
1 B	Gym Large Storage Room on Girl's Restroom Side	N/A	Glass Block Ceiling		Non Suspect ACM	600	SF	0	SF				N/A	N/A	N/A
	Gym Large Storage Room on Girl's Restroom Side	N/A	Brick Wall		Non Suspect ACM	2280	SF	0	SF				N/A	N/A	N/A
	Gym Large Storage Room on Girl's Restroom Side	N/A	Cement Floor		Non Suspect ACM	600	SF	0	SF				N/A	N/A	N/A
	Building Engineer's Office	N/A	Plaster Ceiling		NAD	135	SF	20	SF				N/A	N/A	N/A
	Building Engineer's Office	N/A N/A	Brick Wall Cement Floor		Non Suspect ACM Non Suspect ACM	265 135	SF SF	0	SF SF				N/A N/A	N/A N/A	N/A N/A
	Building Engineer's Office Hallway outside Building Engineer's Office	N/A T	Pipe Insulation 2-6 inch	6260/01/0B/05	Non Suspect ACM Confirmed	135	I F	0	LF				N/A 1	N/A No	1/D
	Hallway outside Building Engineer's Office	N/A	Pipe insulation 2-6 inch Plaster Ceiling	0200/01/00/00	NAD	72	SF	0	SF				N/A	N/A	N/A
	Hallway outside Building Engineer's Office	N/A	Plaster Wall		NAD	280	SF	0	SF				N/A	N/A	N/A
	Hallway outside Building Engineer's Office	N/A	Cement Floor		Non Suspect ACM	72	SF	0	SF				N/A	N/A	N/A

	School District of Philadelphia		AH	ERA Three-Year Reins	ection 2015-2016						Reinspection Date: 10/8/2015				
	Henry H. Houston Elementary School (K-8)			Room by Room Locati							Building Inspector: Bernard Brunner	1			
	7300 Rural Lane, Philadelphia, PA 19119	'						,			Certificate Number: 45397	1			
	ULCS# 6260										Management Planner: Monique Causley	7			
	Year Built: 1927										Certificate Number: ACC-0215-8-010	7			
E	100 - 2														
l e F															
m I															
e o n o		System			Confirmed, Assumed, NAD,	Amount of	SF LF	Amount of	SF LF	Color required		Attic Crawl	Damage Potential	Newly Friable	Response
t r	On Site Room Name	Affected	Material Description	HID#	Non Suspect ACM	Material	EA	Damage	EA	for VAT	Comments/Description/Notes	Space Ranking	(DP)	(NF)	Action (RA)
1 B		T	Pipe Fitting Insulation	6260/01/0B/08	Confirmed	8	EA	0	EA				1	No	1/D
1 B		Т	Pipe Insulation 2-6 inch	6260/01/0B/05	Confirmed	17	LF	0	LF				1	No	1/D
1 B		N/A	Plaster Ceiling		NAD	240	SF	0	SF				N/A	N/A	N/A
	Stairwell A	N/A	Plaster Wall		NAD	1360	SF	0	SF				N/A	N/A	N/A
1 B		N/A N/A	Marble Wall Cement Floor		Non Suspect ACM Non Suspect ACM	455 240	SF SF	0	SF SF				N/A N/A	N/A N/A	N/A N/A
1 B		T	Pipe Insulation 2-6 inch	6260/01/0B/05	Confirmed	8	LF	0	LF				1	No	1/D
1 B	, ,	N/A	Plaster Ceiling		NAD	98	SF	0	SF				N/A	N/A	N/A
1 B	Girl's Side Storage Room outside Gym	N/A	Brick Wall		Non Suspect ACM	250	SF	0	SF				N/A	N/A	N/A
	Girl's Side Storage Room outside Gym	N/A	Cement Floor		Non Suspect ACM	98	SF	0	SF				N/A	N/A	N/A
1 B	Hallway outside Gym Girl's Restroom Side	T N/A	Pipe Insulation 2-6 inch	6260/01/0B/05	Confirmed NAD	9 72	LF SF	0	LF SF				1 N/A	No N/A	1/D N/A
	Hallway outside Gym Girl's Restroom Side Hallway outside Gym Girl's Restroom Side	N/A N/A	Plaster Ceiling Plaster Wall		NAD NAD	72 280	SF SF	0	SF			+	N/A N/A	N/A N/A	N/A N/A
1 B	Hallway outside Gym Girl's Restroom Side	N/A	Cement Floor		Non Suspect ACM	72	SF	0	SF				N/A	N/A	N/A
1 B		Т	Pipe Fitting Insulation	6260/01/0B/08	Confirmed	7	EA	0	EA			1	1	No	1/D
1 B		Т	Pipe Insulation 2-6 inch	6260/01/0B/05	Confirmed	16	SF	0	LF				1	No	1/D
	Stairwell B	N/A	Plaster Ceiling		NAD	240	SF	0	SF				N/A	N/A	N/A
1 B 1 B		N/A N/A	Plaster Wall Marble Wall		NAD Non Suspect ACM	1360 455	SF SF	0	SF SF				N/A N/A	N/A N/A	N/A N/A
1 B		N/A	Cement Floor		Non Suspect ACM	240	SF	0	SF				N/A	N/A	N/A
	Boy's Restroom	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	32	LF	0	LF				N/A	N/A	N/A
	Boy's Restroom	N/A	Concrete Ceiling		Non Suspect ACM	90	SF	0	SF				N/A	N/A	N/A
	Boy's Restroom	N/A	Ceramic Tile Wall		Non Suspect ACM	420	SF	0	SF				N/A	N/A	N/A
	Boy's Restroom	M	Transite Sills	6260/01/0B/AET/BB/2300	Assumed	1	SF	0	SF				1	No	1/D
	Boy's Restroom	N/A	Ceramic Tile Floor		Non Suspect ACM	90	SF	0	SF				N/A	N/A	N/A
1 B		N/A	Concrete Ceiling		Non Suspect ACM	30	SF	0	SF				N/A	N/A	N/A
1 B		N/A N/A	Concrete Block Wall		Non Suspect ACM	120	SF SF	0	SF SF				N/A N/A	N/A N/A	N/A
1 B	Left Closet adjacent to Boy's Restroom Left Closet adjacent to Boy's Restroom Pipe Chase	N/A X	Cement Floor		Non Suspect ACM	30 X	X	X	X	×	No Access	-	N/A X	N/A X	N/A X
	Right Closet adjacent to Boy's Restroom	Ť	Pipe Insulation 2-6 inch	6260/01/0B/05	Confirmed	31	LF	0	LF	_^	NO Access		1	No	1/D
	Right Closet adjacent to Boy's Restroom	N/A	Fiberglass Pipe Insulation	020001100100	Non Suspect ACM	10	LF	0	LF				N/A	N/A	N/A
	Right Closet adjacent to Boy's Restroom	N/A	Concrete Ceiling		Non Suspect ACM	55	SF	55	SF				N/A	N/A	N/A
1 B	Right Closet adjacent to Boy's Restroom	N/A	Concrete Block Wall		Non Suspect ACM	220	SF	0	SF				N/A	N/A	N/A
	Right Closet adjacent to Boy's Restroom	N/A	Cement Floor		Non Suspect ACM	55	SF	0	SF				N/A	N/A	N/A
1 B		Т	Pipe Insulation 2-6 inch	6260/01/0B/05	Confirmed	103	LF	0	LF				1	No	1/D
1 B	,	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	15	LF	0	LF			-	N/A N/A	N/A N/A	N/A
1 B		N/A N/A	Concrete Ceiling Concrete Block Wall		Non Suspect ACM Non Suspect ACM	120 530	SF SF	0	SF SF			_	N/A N/A	N/A N/A	N/A N/A
1 B	, , , , , , , , , , , , , , , , , , , ,	M	Transite Sills	6260/01/0B/AET/BB/2300	Assumed	4	SF	0	SF			_	1	No	1/D
1 B	, , , , , , , , , , , , , , , , , , , ,	М	Transite Electrical Panel	6260/01/0B/AET/BB/2350	Assumed	16	SF	0	SF				1	No	1/D
-	Music Room 018	Т	Pipe Insulation 2-6 inch	6260/01/0B/05	Confirmed	54	LF	0	LF		More possible above ceiling		1	No	1/D
	Music Room 018	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	1034	LF	0	LF		Trenches in floor - Unknown interior		N/A	N/A	N/A
	Music Room 018	N/A	Concrete Ceiling		Non Suspect ACM	1034	SF	0	SF				N/A	N/A	N/A
	Music Room 018	N/A	Concrete Block Wall		Non Suspect ACM	1380	SF	0	SF			+	N/A	N/A	N/A
	Music Room 018 Music Room 018	M M	Transite Sills Floor Tile VAT 9" x 9"	6260/01/0B/AET/BB/2300 6260/01/0B/07	Assumed Confirmed	10 896	SF SF	30	SF SF	Cross		+	1	No No	1/D 6/C
	Music Room 018 Music Room 018	M	Floor Tile VAT 9" x 9" Floor Tile VAT 9" x 9"	6260/01/0B/07 6260/01/0B/07	Confirmed	138	SF	0	SF	Grey Black		+	1	No No	1/D
	Music Room 018	N/A	Cement Floor	0200101100101	Non Suspect ACM	1034	SF	0	SF	DIACK			N/A	N/A	N/A
	Music Room 018	M	Blackboard Glue Dots	6260/01/0B/AET/BB/2600	Assumed	100	SF	0	SF			1	1	No	1/D
	Home and School Office	Т	Pipe Insulation 2-6 inch	6260/01/0B/05	Confirmed	20	LF	0	LF		No access		1	No	1/D
1 B	Home and School Office	N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	350	SF	0	SF				N/A	N/A	N/A
	Home and School Office	N/A	Concrete Ceiling		Non Suspect ACM	350	SF	0	SF			_	N/A	N/A	N/A
	Home and School Office	N/A	Concrete Block Wall		Non Suspect ACM	390	SF	0	SF			+	N/A	N/A	N/A
	Home and School Office Home and School Office	N/A M	Sheetrock Wall Floor Tile VAT 9" x 9"	6260/01/0B/07	Non Suspect ACM Confirmed	390 350	SF SF	200	SF SF	Cross		+	N/A	N/A	N/A 6/C
	Home and School Office Home and School Office	M N/A	Floor Tile VAT 9" x 9" Cement Floor	626U/U1/UB/U/	Confirmed Non Suspect ACM	350 350	SF SF	200	SF	Grey		+	N/A	No N/A	6/C N/A
	Hallway from Cafeteria to Element 1	T T	Pipe Insulation 2-6 inch	6260/01/0B/05	Confirmed	404	LF	0	LF				1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	No No	1/D
	Hallway from Cafeteria to Element 1	N/A	Fiberglass Pipe Insulation	020010 1/0B/00	Non Suspect ACM	35	LF	0	LF				N/A	N/A	N/A
	Hallway from Cafeteria to Element 1	М	Transite Electrical Panel	6260/01/0B/AET/BB/2350	Assumed	16	SF	0	SF				1	No	1/D
1 B	Hallway from Cafeteria to Element 1	N/A	Concrete Ceiling		Non Suspect ACM	842	SF	0	SF				N/A	N/A	N/A
	Hallway from Cafeteria to Element 1	N/A	Concrete Block Wall		Non Suspect ACM	1680	SF	0	SF				N/A	N/A	N/A
	Hallway from Cafeteria to Element 1	M	Floor Tile VAT 12" x 12"	6260/01/0B/RR	Assumed	842	SF	0	SF				1	No	1/D
1 B	Hallway from Cafeteria to Element 1	N/A	Cement Floor	<u> </u>	Non Suspect ACM	842	SF	0	SF		<u> </u>		N/A	N/A	N/A

	School District of Philadelphia Henry H. Houston Elementary School (K-8)		АН	ERA Three-Year Reins Room by Room Locat							Reinspection Date: 10/8/2015 Building Inspector: Bernard Brunner				
	7300 Rural Lane, Philadelphia, PA 19119	-		•				,			Certificate Number: 45397	İ			
	ULCS# 6260										Management Planner: Monique Causley	1			
	Year Built: 1927										Certificate Number: ACC-0215-8-010	1			
E	fear Built: 1927	1							_		Certificate Number: ACC-0215-8-010				
e F m I e c n c	On Site Room Name	System Affected	Material Description	HID#	Confirmed, Assumed, NAD, Non Suspect ACM	Amount of Material	SF LF EA	Amount of Damage	SF LF EA	Color required for VAT	Comments/Description/Notes	Attic Crawl Space Ranking	Damage Potential (DP)	Newly Friable (NF)	Response Action (RA)
1 E		T	Pipe Fitting Insulation	6260/01/0B/08	Confirmed	12	EA	0	EA				1	No	1/D
1 E		T	Pipe Insulation 2-6 inch	6260/01/01/09	Confirmed	67	LF	0	LF				1	No	1/D
1 E		N/A	Concrete Ceiling		Non Suspect ACM	180	SF	0	SF				N/A	N/A	N/A
1 E		N/A	Concrete Block Wall		Non Suspect ACM	930	SF	0	SF	_			N/A	N/A	N/A
	Stairwell adjacent to Home and School Office	M	Floor Tile VAT 9" x 9"	6260/01/0B/07	Confirmed	5	SF	5	SF SF	Grey			1 N/A	No	6/C
	Stairwell adjacent to Home and School Office Cafeteria	N/A T	Cement Floor Pipe Insulation 2-6 inch	6260/01/0B/05	Non Suspect ACM Confirmed	180 254	SF LF	0	LF				1 1	N/A No	N/A 1/D
	Cafeteria	N/A	Fiberglass Pipe Insulation	6260/01/0B/05	Non Suspect ACM	18	LF	0	LF				N/A	NO N/A	N/A
	Cafeteria Cafeteria	M M		6260/01/0B/AET/BB/1710		5100	SF		SF				1 1		1/D
	Cafeteria Cafeteria	N/A	Ceiling Tile 1' x 1' Concrete Ceiling	0200/01/0D/AE1/DD/1/10	Assumed Non Suspect ACM	5100	SF	0	SF				N/A	No N/A	N/A
	Cafeteria Cafeteria	N/A	Concrete Block Wall		Non Suspect ACM	2900	SF	0	SF				N/A	N/A	N/A
	Cafeteria Cafeteria	N/A	Sheetrock Wall		Non Suspect ACM	240	SF	0	SF				N/A	N/A	N/A
	Cafeteria	M	Transite Sills	6260/01/0B/AET/BB/2300	Assumed	13	SF	0	SF				1	No	1/D
	Cafeteria	М	Floor Tile VAT 12" x 12"	6260/01/0B/RR	Assumed	5100	SF	6	SF	Multi			1	No	6/C
1 E	Cafeteria	N/A	Cement Floor		Non Suspect ACM	5100	SF	0	SF				N/A	N/A	N/A
	Cafeteria School Supply Room	Т	Pipe Insulation 2-6 inch	6260/01/0B/05	Confirmed	87	LF	0	LF		Room is labeled School Supply		1	No	1/D
	Cafeteria School Supply Room	N/A	Concrete Ceiling		Non Suspect ACM	276	SF	0	SF				N/A	N/A	N/A
	Cafeteria School Supply Room	N/A	Concrete Block Wall		Non Suspect ACM	840	SF	0	SF				N/A	N/A	N/A
1 E	Cafeteria School Supply Room	M	Transite Sills	6260/01/0B/AET/BB/2300	Assumed	4	SF	0	SF				1	No	1/D
1 E	Cafeteria School Supply Room	M	Floor Tile VAT 9" x 9"	6260/01/0B/07	Confirmed	10	SF	0	SF	Grey			1	No	1/D
	Cafeteria School Supply Room	N/A	Cement Floor		Non Suspect ACM	276	SF	0	SF				N/A	N/A	N/A
	Kitchen	Т	Pipe Insulation 2-6 inch	6260/01/0B/05	Confirmed	264	LF	0	LF				1	No	1/D
	Kitchen	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	4	LF	0	LF				N/A	N/A	N/A
	Kitchen	N/A	Plaster Ceiling		NAD	660	SF	5	SF				N/A	N/A	N/A
	Kitchen	N/A	Concrete Block Wall		Non Suspect ACM	740	SF	0	SF				N/A	N/A	N/A
	Kitchen	N/A	Cement Floor		Non Suspect ACM	660	SF	0	SF				N/A	N/A	N/A
	Kitchen Office	T	Pipe Insulation 2-6 inch	6260/01/0B/05	Confirmed	22	LF	0	LF				1	No	1/D
	Kitchen Office	N/A	Concrete Ceiling		Non Suspect ACM	54	SF	0	SF				N/A	N/A	N/A
-	Kitchen Office	N/A	Concrete Block Wall		Non Suspect ACM	300	SF	0	SF				N/A	N/A	N/A
	Kitchen Office	N/A T	Cement Floor	0000/04/00/05	Non Suspect ACM	54	SF LF	0	SF LF				N/A 1	N/A	N/A
	Kitchen Office Storage Closet Kitchen Office Storage Closet	N/A	Pipe Insulation 2-6 inch Cement Floor	6260/01/0B/05	Confirmed	17 35	SF	0	SF				N/A	No N/A	1/D N/A
	Kitchen Office Storage Closet Kitchen Office Storage Closet	N/A N/A	Concrete Block Wall		Non Suspect ACM Non Suspect ACM	240	SF	0	SF				N/A N/A	N/A N/A	N/A N/A
	Kitchen Office Storage Closet	N/A	Cement Floor		Non Suspect ACM	35	SF	0	SF				N/A	N/A	N/A
	Kitchen Office Restroom	N/A	Concrete Ceiling		Non Suspect ACM	30	SF	0	SF				N/A	N/A	N/A
	Kitchen Office Restroom	N/A	Concrete Block Wall		Non Suspect ACM	124	SF	0	SF				N/A	N/A	N/A
	Kitchen Office Restroom	N/A	Ceramic Tile Wall		Non Suspect ACM	124	SF	0	SF				N/A	N/A	N/A
	Kitchen Office Restroom	N/A	Ceramic Tile Floor		Non Suspect ACM	30	SF	0	SF				N/A	N/A	N/A
	Kitchen Office Restroom Pipe Chase	N/A	Concrete Ceiling		Non Suspect ACM	15	SF	0	SF				N/A	N/A	N/A
	Kitchen Office Restroom Pipe Chase	N/A	Concrete Block Wall		Non Suspect ACM	160	SF	0	SF				N/A	N/A	N/A
	Kitchen Office Restroom Pipe Chase	N/A	Cement Floor		Non Suspect ACM	15	SF	0	SF				N/A	N/A	N/A
	Kitchen Office Restroom Pipe Chase	M	Vibration Damper Cloth	6260/01/0B/CC	Assumed	1	SF	0	SF				1	No	1/D
	Walk-in Refrigerator	N/A	Concrete Ceiling		Non Suspect ACM	45	SF	0	SF				N/A	N/A	N/A
	Walk-in Refrigerator	N/A	Ceramic Tile Wall		Non Suspect ACM	160	SF	0	SF				N/A	N/A	N/A
	Walk-in Refrigerator	N/A	Ceramic Tile Floor		Non Suspect ACM	45	SF	0	SF				N/A	N/A	N/A
	Kitchen Dry Storage Room	Т	Pipe Insulation 2-6 inch	6260/01/0B/05	Confirmed	25	LF	0	LF				1	No	1/D
	Kitchen Dry Storage Room	N/A	Concrete Ceiling		Non Suspect ACM	100	SF	0	SF				N/A	N/A	N/A
	Kitchen Dry Storage Room	N/A	Concrete Block Wall		Non Suspect ACM	400	SF	0	SF				N/A	N/A	N/A
	Kitchen Dry Storage Room	N/A T	Cement Floor	6260/01/0B/05	Non Suspect ACM	100 63	SF LF	0	SF LF				N/A	N/A	N/A 1/D
	Hallway behind Kitchen		Pipe Insulation 2-6 inch	6260/01/0B/05	Confirmed				_				· ·	No N/A	
	Hallway behind Kitchen Hallway behind Kitchen	N/A M	Concrete Ceiling Floor Tile VAT 9" x 9"	6260/01/0B/07	Non Suspect ACM Confirmed	360 40	SF SF	0	SF SF	Grey		-	N/A 1	N/A No	N/A 1/D
	Hallway behind Kitchen Hallway behind Kitchen	N/A	Cement Floor	0200/01/00/07	Non Suspect ACM	360	SF	0	SF	Gley			N/A	N/A	N/A
1 A	Attic-Third Floor Hall adjacent to Classroom 304	X	X		Non Suspect ACM	X	X	X	X	x	Fiberglass PI, Hard Fittings, Plastic Caps/Equipment, Concrete Floor	A	X	X X	X X
	<u>'</u>										1500 LF damaged Air Cell,150 Hard Fittings, Visible Debris	_			
1 C	Crawl Space in Boiler Room	X	X		X	Х	Х	Х	Х	X	Poly/Critial on door, Wire Lathe Floor	С	X	X	X

,	
Section III	Certificates
	A. Management Planner/Building Inspector Certificates

Section III - A

Management Planner/Building Inspector Certificates

These charts indicate the Name, Course Date, Expiration Date and Corresponding Certificate Number of the Management Planner and Building Inspector of individuals that participated in the AHERA 3 Year Inspection and Management Plan process of 2015/2016.

Management Planner	Date Granted	Expiration Date	Certificate Number
Monique Causley	2/15/2015	2/16/2016	ACC-0215-8-010
Monique Causley	2/16/2016	2/17/2017	ACC-0216-8-001
Megan Vala	5/22/2015	6/22/2016	740728
Mary Anne Lerro	4/5/2016	4/5/2017	742327

Building Inspector	Date Granted	Expiration Date	Certificate Number
Scott Magee	8/15/2015	8/15/2016	70016699C
William Garrity	8/15/2015	8/15/2016	70016699A
Bernard Brunner	10/2/2015	8/2/2016	45397
Mary Anne Lerro	3/3/2015	3/3/2016	740092
Mary Anne Lerro	4/5/2016	4/5/2017	742322
James Madden	12/11/2014	12/11/2015	ACC-1214-6-010
James Madden	12/3/2015	12/3/2016	ACC-1215-6-018
Troy Ray	3/15/2015	3/19/2016	ACC-0355-6-011
Ananth Vinjamuri	9/29/2015	9/29/2016	374
Shelton Williams	9/29/2015	9/29/2016	375
Paul Davis	2/12/2015	2/12/2016	ACC-0215-6-015
Paul Davis	2/2/2016	2/2/2017	741836
Bernard Bryson	2/16/2015	2/16/2016	ACC-0125-6-031
Bernard Bryson	2/15/2016	2/15/2017	ACC-0216-6-005
Alexander Roman	9/18/2015	9/18/2016	EHSBIR-150619-008
Norm Harrison	9/2/2015	9/2/2016	ACC-0915-6-011
Kelly Mayberry	2/20/2015	2/20/2016	EHSBIR-150220-005
Kelly Mayberry	2/18/2016	2/18/2017	EHSBIR-160218-006
Andrew Hine	5/6/2015	5/6/2016	Al05042015-3
Maryellen Leotta	2/12/2015	2/12/2016	ACC-0215-6-024

awarded to

Monique Causley for successfully completing the prescribed course of study in

Pennsylvania Asbestos Management Planner Refresher Course

under TSCA Title II

presented by

ACCESS TRAINING SERVICES, INC. 7921 River Road, Pennsauken, NJ 08110

(856) 665-3449

Course Date 2/16/15

Exam Date

ACC-0215-8-010 Certificate Number

Social Security Number

Not Provided

Training Director Mark K. Schläger

awarded to

Monique Causley

for successfully completing the prescribed course of study in

Pennsylvania Asbestos Management Planner Refresher Course

under TSCA Title II

presented by

ACCESS TRAINING SERVICES, INC. 7921 River Road, Pennsauken, NJ 08110 (856) 665-3449

2/15/16 Course Date

Exam Date

2/15/17

Expiration

Not Provided

Social Security Number

ACC-0216-8-001
Certificate Number

Mark K. Schläger Training Director

Certificate of Iraining

CRITERION LABORATORIES, INC. HEREBY CERTIFIES THAT

Megan Vala

HAS SUCCESSFULLY COMPLETED A 16 HOUR COURSE ENTITLED

<u>Asbestos Management Planner Initial</u>

INCLUDING CLASSROOM INSTRUCTION

05/21/2015 to 05/22/2015

Exam passed on this 22nd day of May 2015 - Score - 94

Approved for AHERA Accreditation Under TSCA Title II

3370 Progress Drive, Suite J Bensalem, PA 19020 (215) 244-1300 - Phone (215) 244-4349 - Fax www.criterionlabs.com

Course is conducted in English

DIRECTOR:

grash-

James A. Weltz, CIH, President

Certificate of Iraining

CRITERION LABORATORIES, INC. HEREBY CERTIFIES THAT

Mary Anne Lerro

HAS SUCCESSFULLY COMPLETED A 4 HOUR COURSE ENTITLED

Asbestos Management Planner Refresher

INCLUDING CLASSROOM INSTRUCTION on this 5th day of April 2016

Approved for AHERA Accreditation Under TSCA Title II

3370 Progress Drive, Suite J Bensalem, PA 19020

(215) 244-1300 - Phone (215) 244-4349 - Fax

www.criterionlabs.com

Course is conducted in English

DIRECTOR:

8-Cuely

James A. Weltz, CIH, President

EMSL ANALYTICAL, INC.

Certifies that

Scott Magee

has successfully completed the course of study for the

Asbestos Building Inspector Refresher Course

for Accreditation under TSCA Title II

EMSL Certificate No. 70016699C

Approved by:
PA Dept. of Labor and Industry
Accreditation # 137

Course Date: 8/15/2015 Granted: 8/15/2015 Expiration Date: 8/15/2016

Sponsored by:

EMSL Analytical, Inc. 200 Route 130 North Cinnaminson, NJ 08077 Phone: (800) 220-3675 Fax: (856) 786-5973

www.emsl.com



Michael P. Menz, CIH Training Director

made Com

Environmental, Mold. Bacteria, IAQ, Asbestos, Lead, Forensic and Materials Testing Since 1981

EMSL ANALYTICAL, INC.

Certifies that

William Garrity

has successfully completed the course of study for the

Asbestos Building Inspector Refresher Course

for Accreditation under TSCA Title II

EMSL Certificate No. 70016699A

PA Dept. of Labor and Industry Accreditation # 137 Approved by:

Course Date: 8/15/2015 Granted: 8/15/2015 Expiration Date: 8/15/2016

Sponsored by:

EMSL Analytical, Inc. 200 Route 130 North Cinnaminson, NJ 08077 Phone: (800) 220-3675 Fax: (856) 786-5973

www.cmsl.com

TSINE OF THE PROPERTY OF THE P

Michael P. Menz, CIH
Training Director

Environmental, Mold, Bacteria, IAQ, Asbestos, Lead, Forensic and Materials Testing Since 1981

45397

National Asbestos & Environmental Training Institute CERTIFICATE OF COMPLETION

AHERA/EPA Accredited Per 40 CFR Part 763
Asbestos Accreditation under TSCA Title II

This is to certify that .

Bernard Brunner, Jr.

Successfully completed the course entitled

1/2-Day New York State/EPA/AHERA Asbestos Building Inspector Annual Refresher on October 2, 2015

Examination Passed October 2, 2015

Expiration Date on October 2, 2016

President, NAETI

Per I0 NYCRR Part 73.2 (L) (I), DOH 2832 Certificate of Completion of Asbestos Safety Training is the only official record of training for N.Y.S. students.

Language: English

ABIH 1/2 CM POINT

3321 Doris Avenue, Building B, Ocean, NJ 07712

Phone (732) 531-5571

Fax (732) 531-5956

/ww.naeti.com

Certificate of Iraining

CRITERION LABORATORIES, INC.

HEREBY CERTIFIES THAT

Mary Anne Lerro

Asbestos Building Inspector Refresher

HAS SUCCESSFULLY COMPLETED A 4 HOUR COURSE ENTITLED

on this 3rd day of March 2015

Exam passed on this 3rd day of March 2015 - Score - 84

Approved for AHERA Accreditation Under TSCA Title II

3370 Progress Drive, Suite J Bensalem, PA 19020

(215) 244-1300 - Phone

www.criterionlabs.com

Course is conducted in English

クークスイヤ

James A. Weltz, CIH, President

Certificate of Iraining

CRITERION LABORATORIES, INC. HEREBY CERTIFIES THAT

Mary Anne Lerro

HAS SUCCESSFULLY COMPLETED A 4 HOUR COURSE ENTITLED

Asbestos Building Inspector Refresher

INCLUDING CLASSROOM INSTRUCTION on this 5th day of April 2016

Exam passed on this 5th day of April 2016 - Score - 88

Approved for AHERA Accreditation Under TSCA Title II

3370 Progress Drive, Suite J Bensalem, PA 19020

(215) 244-1300 - Phone (215) 244-4349 - Fax www.criterionlabs.com

Course is conducted in English

DIRECTOR:

grand.

James A. Weltz, CIH, President

James Madden

for successfully completing the prescribed course of study in

Building Inspector Refresher Course Pennsylvania Asbestos under TSCA Title II

: :

Presented by ACCESS TRAINING SERVICES, INC. 7921 River Road, Pennsauken, NJ 08110 (856) 665-3449

12/11/14

Course Date

Not Provided

Social Security Number

N/A Exam Date

ACC-1214-6-010

Certificate Number

12/11/15

Expiration Date

Mark K. Schläger Training Director

James Madden

for successfully completing the prescribed course of study in

Building Inspector Refresher Course Pennsylvania Asbestos

under TSCA Title II

presented by
ACCESS TRAINING SERVICES, INC.
7921 River Road, Pennsauken, NJ 08110
(856) 665-3449

Social Security Number Not Provided Course Date 12/3/15 Certificate Number ACC-1215-6-018 Exam Date Mark K. Schläger 146 Expiration Date 12/3/16

Training Directo.

$\mathbf{Troy}\,\mathbf{A}.\,\mathbf{Ray}$ for successfully completing the prescribed course of study in

Building Inspector Refresher Course Pennsylvania Asbestos under TSCA Title II

presented by

ACCESS TRAINING SERVICES, INC. 7921 River Road, Pennsauken, NJ 08110 (856) 665-3449

/ Mark K. Schläger	Certificate Number	Social Security Number
May be to the one	ACC-0355-6-011	Not Provided
Expiration Date	Exam Date	Course Date
3/19/16	N/A	3/19/15

G&C Environmental Services, Inc. (#294)
2 Street Road, Newtown Square, Pennsylvania 19073
Telephone: (610) 993-9202 Facsimile: (610) 993-9232

Email: Training@gcenviro.com www.GCenviro.com

This document certifies that Ananth K. Vinjamuri has successfully completed this

State of New York Department of Health Approved AHERA BUILDING INSPECTOR

REFRESHER COURSE, completed as required for asbestos accreditation under the Toxic

Substances Control Act, Title II. This course was held from 09/29/2015 to 09/29/2015.

successful completion of the examination 09/29/2016. The examination date was $\frac{09/29/2015}{MM$ DD YR

The official record of successful training completion is the New York State Department of Health certificate of asbestos safety training completion (DPH 2832).

•

Hail M. Conner

Gail M. Conner
Training Director

G&C Environmental Services, Inc. (#294) 2 Street Road, Newtown Square, Pennsylvania 19073

Telephone: (610) 993-9202 Facsimile: (610) 993-9232

Email: Training@gcenviro.com

www.GCenviro.com

State of New York Department of Health Approved AHERA BUILDIN	This document certifies that
t of Health Approved <u>AH</u>	Shelton Williams has successf
IERA BUILDING INSPECTOR	_ has successfully completed th

REFRESHER COURSE, completed as required for asbestos accreditation under the Toxic

successful completion of the examination 09/29/2016. Substances Control Act, Title II. This course was held from $\frac{09/29/2015}{MM$ DD YR MM DD YR The examination date was $\frac{09/29/2015}{MM}$. This certificate expires one year from the date of

The official record of successful training completion is the New York State Department of Health certificate of asbestos safety training completion (DPH 2832).

Hail M. Conner

Gail M. Conner
Training Director

Paul M. Davis

for successfully completing the prescribed course of study in

Building Inspector Refresher Course Pennsylvania Asbestos

under TSCA Title II

ACCESS TRAINING SERVICES, INC. presented by

7921 River Road, Pennsauken, NJ 08110 (856) 665-3449

Course Date 2/12/15

Exam Date

Social Security Number Not Provided

Expiration Date

THE OF THE STATE O

Mark K. Schläger

Certificate Number ACC-0215-6-015

Training Director

Number 741836

02/02/2017 Expiration Date

Certificate of Ironne

CRITERION LABORATORIES, INC. HEREBY CERTIFIES THAT

Paul M. Davis

HAS SUCCESSFULLY COMPLETED A 4 HOUR COURSE ENTITLED Asbestos Building Inspector Refresher

NCLUDING CLASSROOM INSTRUCTION

on this 2nd day of February 2016

ed on this 2nd day of Echruary 2016 - Score - 92

itation Under TSCA Title II

3370 Progress Drive, Suite J Bensalem, PA 19020

(215) 244-1300 - Phone (215) 244-4349 - Fax

Course is conducted in English

DIRECTOR:

James A. Weltz, CIH, Presiden

Bernard J. Bryson

for successfully completing the prescribed course of study in

Building Inspector Refresher Course Pennsylvania Asbestos

under TSCA Title II

presented by
ACCESS TRAINING SERVICES, INC.
7921 River Road, Pennsauken, NJ 08110
(856) 665-3449

Social Security Number Not Provided Course Date Certificate Number ACC-0125-6-031 Exam Date Mark K. Schläger Training Director Expiration Date

Bernard J. Bryson

for successfully completing the prescribed course of study in

Building Inspector Refresher Course Pennsylvania Asbestos under TSCA Title II

presented by

ACCESS TRAINING SERVICES, INC. 7921 River Road, Pennsauken, NJ 08110 (856) 665-3449

Exam Date

Exam Date

Expiration Date

ACC-0216-6-005

Certificate Number

Mark K. Schläger

Training Director

Not Provided
Social Security Number

Course Date



Norman Harrison

for successfully completing the prescribed course of study in

Building Inspector Refresher Course Pennsylvania Asbestos

under TSCA Title II

presented by ACCESS TRAINING SERVICES, INC. 7921 River Road, Pennsauken, NJ 08109 (856) 665-3449

Social Security Number	Not Provided	Course Date	9/2/15
Certificate Number	ACC-0915-6-011	Exam Date	N/A
Mark K. Schlager Training Director		Expiration Date	9/2/16

EHS TRAINING INSTITUTE, INC. A Division of BATTA, Inc.

Certificate of Completion

AHERA Building Inspector

(Refresher)

Awarded To:

Kelly Mayberry

SS#:XXX-XX-1551

Who has completed this 4-hour course and examination, EPA Approved under TSCA Title II

AHERA / ASHARA Rule

EHS TRAINING INSTITUTE, INC.

A Division of BATTA, Inc. Delaware Industrial Park • 6 Garfield Way Newark DE 19713-5817

Newark, DE 19713-5817

(302) 737-3376 • Fax (302) 737-5764

Course Date: February 20, 2015

Date of Expiration: February 20, 2016

Certification Number: EHSBIR 150220-005

Todd K. Zeisloft, Instructor

Neeraj K. Batta, President



AHERA Building Inspector Certificate of Completion

Awarded To:

(Refresher)

Kelly Mayberry

SS#:XXX-XX-1551

Who has completed this 4-hour course and examination, EPA Approved under TSCA Title II
AHERA / ASHARA Rule
40 CFR Part 763.

EHS TRAINING INSTITUTE, INC.

A Division of BATTA, Inc.

Delaware Industrial Park • 6 Garfield Way

Newark, DE 19713-5817 (302) 737-3376 • Fax (302) 737-5764

Course Date: February 18, 2016

Date of Expiration: **February 18, 2017**Certification Number: **EHSBIR 160218-006**

Todd K. Zeisloft, Instructo

Neeraj K. Batta, President

AEROSOL MONITORING & ANALYSIS, INC.

This is to certify that

ANDREW HINE

has met the attendance requirements and successfully completed the course entitled

3-DAY EPA AHERA INSPECTOR

For Accreditation Under TSCA Title II

Certification No.	AI05042015-3	Course Date	05/04/2015 to 05/06/2015
		Đ	05/06/2015 5/6/2016
9	E. Rush Barnett	Principal Instructor	STEVE SIERAGKI
	E. Rad Bankt		for & twhi-

1331 Ashton Road

P.O.Box 646

www.amatraining.com Hanover, MD 21076

P: 410-684-3327

F: 410-684-3724

Maryellen Leotta

for successfully completing the prescribed course of study in

Building Inspector Refresher Course Pennsylvania Asbestos

under TSCA Title II

presented by ACCESS TRAINING SERVICES, INC. 7921 River Road, Pennsauken, NJ 08110

(856) 665-3449

Course Date

Social Security Number Not Provided

Exam Date

ACC-0215-6-024 Certificate Number

2/12/16

Expiration Dat

Mark K. Schläger Training Director



Asbestos Hazard Emergency Response Act (AHERA) Environmental Compliance Audit Cross Reference Table

In response to the AHERA Environmental Compliance Audit a Cross Reference Table has been prepared for inclusion into the Environmental Management Plan. The purpose of this Cross Reference Table is to link the following documents to the AHERA Management Plan.

Cross Reference Table

3 Year Reinspection Report follows this Cross Reference Table documentation.

	Location of Required Documents		
Designated Person	Pages 1 - 3		
Annual Notification	Pages 4 - 5		
6 Month Periodic Surveillance Outline of Events	Page 6		
3 Year Re-inspections Outline of Events	Page 7		
Asbestos Management Program (operations and maintenance)	Pages 8 - 19		
Asbestos Investigation Report (AIR)	Attachment 1 Letter Dated August 4, 2006		
Training (included in the Asbestos Management Program)	The original records are centralized at the School District's Environment Library. Copies are maintained on staff and are required to be maintained the latest Reinspection Report. 2 hour awareness training records for all Building Engineers, Custodia Assistants and maintenance personnel 40 hour worker/supervisor training records for the OEMS A-Team are various AST tradesmen.		
Response Actions (monthly mailings if applicable)	The original documents are on file at the School District's Environment Library. Copies of the original are mailed to the Schools Main Office for retention with the Management Plan documentation. These documents are typical		

SCHOOL DISTRICT OF PHILADELPHIA

ASBESTOS DESIGNATED PERSON

Gerald F Junod
Office of Capital Programs
Environmental Management & Services
440 N Broad Street, 3rd Floor
Philadelphia, PA 19130
Telephone: 215 400 6738
Fax: 215 400 4751

Drexel University- Asbestos Building Inspector Course
Drexel University- Asbestos Management Planner Course
Criterion Laboratories, Inc. - Asbestos Management Planner Course October 11-12, 2012 16 Hours

Annual Building Inspector Refreshers

1990 to Present

4 Hours
Drexel University
Criterion Laboratories, Inc
Access Training Services, Inc.

Annual Building Management Planner Refreshers

1990 to 1994

4 Hours

Drexel University

Criterion Laboratories, Inc

2013 to Present

4 Hours

Environmental Manager, School District of Philadelphia

Manages the design and implementation of asbestos and lead projects for the Capital Improvement Program and other District Departments including Facilities & Operations and Information Technology. Ensures that asbestos abatement and lead remediation projects are expertly designed and executed in accordance with industry best management practice standards and regulations.

Manager, City of Philadelphia Asbestos Control Program

Served as the Asbestos Control Program Manager for the City of Philadelphia, Department of Public Health, Air Management Services, Asbestos Control Unit from August 1, 2003 through October 23, 2006.

Mid Atlantic Regional Environmental Consortium (MAREC)

Former member with attendance and participation commitments of all quarterly EPA Region III and yearly National Asbestos Regulatory Conferences sponsored by the EPA and the National Conference of State Legislators respectively as a representative for the City of Philadelphia Department of Public Health Air Management Services from 1994 through 2006.

Philadelphia Environmental Task Force

Former member of the Philadelphia Environmental Task force as a representative and point of contact for the City of Philadelphia Department of Public Health Air Management Services Asbestos Control Unit from 2002 through 2006.

Asbestos Instructor

Worked as the primary instructor for the initial and annual Asbestos Project Inspector training and licensing program as mandated by City of Philadelphia Department of Pubic Health Asbestos Control Regulations from August 1994 through October 2006.

Worked as a lead instructor with an Environmental Consulting Firm and approved by the US EPA for the initial and annual refresher training courses for various asbestos occupational disciplines such as the Building Inspector, Management Planner and Worker/Supervisor from 1991 through 1994.

I certify that the general, local agency responsibilities as stipulated in Section 763.84 will be met.

Gerald F. Junod

Asbestos Designated Person Environmental Manager

Office of Environmental Management and Services

Accreditation Information Statement

All persons who inspect for Asbestos Containing Building Materials (ACBM) and who will design or carry our response actions with respect to assumed and confirmed ACBM, will be accredited by an EPA approved course and/or a State Contractors AccreditationProgram under Sections 206 (c) and 206 (b) of Title II of the ACT.

Gerald F. Junod

Asbestos Designated Person Environmental Manager

Office of Environmental Management and Services

OFFICE OF CAPITAL PROGRAMS 440 NORTH BROAD STREET, SUITE 373 PHILADELPHIA, PENNSYLVANIA 19130

OFFICE OF ENVIRONMENTAL MANAGEMENT AND SERVICES

PHONE (215)-400-4750

September 2015

TO:

Principals

Building Administrators/Occupants

Parents/Guardians

FROM:

Fran Burns

Chief Operating Officer

Francine Locke, M.S., Director

Office of Environmental Management and Services

SUBJECT:

Annual EPA Notification Letter

Pursuant to the Federal Environmental Protection Agency (EPA) mandate, as required by 40 C.F.R. 763.84 (c)(d) of public access to environmental records, this letter is to acknowledge the availability of your facility's Asbestos Hazard Emergency Response Act (AHERA) Management Plan.

Each member of the school staff, parents/guardians, temporary workers and/or contractors, are required to receive a copy of the Notification Letter. At the direction of the Principal, a copy is to be posted on the bulletin boards and an appropriate amount of copies are to be generated for distribution.

Note: The AHERA Three-Year Reinspection reports, in colored binders; White with Pink, Tan, Black, Red, Dark Blue, Green, Yellow and White, are Federal EPA mandated inspection documents. The School District of Philadelphia is subject to severe monetary penalties if the reports and associated paperwork are not available to the EPA and the public upon request.

It is incumbent on designated school personnel to gather and retain this data as it is delivered, in one location for future review. Acceptable locations include the Principal's Office or Main Office for the primary data. The Building Engineer should maintain any secondary or duplicate copies.

If you have any questions, please call 215-400-4750. Thank you for your cooperation.

Fran Burns

Chief Operating Officer

Francine Locke, M.S., Director

Office of Environmental Management

and Services

c: Danielle Floyd

AHERA-4 8/21/15



School District of Philadelphia OFFICIAL NOTICE

PLEASE POST

September 2015

TO:

Principals

Building Administrators Building Engineers Building Occupants Parents/Guardians

FROM:

Fran Burns

Chief Operating Officer

Francine Locke, M.S., Director

Office of Environmental Management and Services

SUBJECT:

Annual Notification Letter: Asbestos Hazard Emergency Response Act

The Federal Register published on October 30, 1987, Subpart E, in Schools: Final Rule and Notice, 763.84 (c)(d) states that each local education agency shall ensure that workers and building occupants or guardians are to be informed at least once each school year about inspections, response actions and post-response action activities including re-inspections and periodic surveillance activities. The School District as the Local Education Agency (LEA), retains such reports that are available for public inspection in the Office of the Principal or Building Administrator.

The Principal or Building Administrator is required to do the following with this notification:

1) Post in a Public Place or Main Office

2) Inform Building Occupants

3) Send a copy of this notification to Parents or Guardians

4) Insert a copy into the latest AHERA Three-Year Reinspection report (white/pink binder)

in your office or facility.

Fran Burns

Chief Operating Officer

Francine Locke, M.S., Director

Office of Environmental Management

and Services

c: Danielle Floyd

AHERA-4a 8/21/15

Education Center 440 North Broad Street Philadelphia, Pennsylvania 19130

Office of Environmental Management and Services

215-400-4750

AHERA Six Month Surveillance Outline of Events

- Pursuant to the Federal Environmental Protection Agency (EPA) mandate, as required by 40 CFR 763.92(b), the following procedure is to be implemented. At least once every six (6) months after a Management Plan is in effect, each Local Education Agency (LEA) shall conduct a periodic surveillance in each building that it owns or leases that contains Asbestos Containing Building Materials (ACBM) or is assumed to contain ACBM.
- The first Bi-Annual Inspection starts in the Spring (March, April, May) and again in the Fall (October, November, December) of each year. The Building Engineer/Assistant should assist the Building Inspector with appropriate access to all areas including (Crawlspaces/Attics) and rooms in the facility. There is no action required of the Principal.
- The Building Inspector shall visually inspect all areas that are identified in the Management Plan as ACBM or assumed ACBM. The date of the surveillance is recorded, the inspectors name and any changes in the conditions of the materials.
- The Building Inspector shall make a copy of the inspection document and insert into the front of the latest Management Plan (AHERA Three Year Reinspection report). The original document is returned to the LEA's Environmental Library and filed.

Education Center 440 North Broad Street Philadelphia, Pennsylvania 19130

Office of Environmental Management and Services

215-400-4750

AHERA Three Year Reinspection Outline of Events

- Pursuant to the Federal Environmental Protection Agency (EPA) mandate, as required by 40 CFR 763.85(b) the following procedure is to be implemented. At least once every three (3) years after a Management Plan is in effect, each Local Education Agency (LEA) shall conduct a reinspection of each building that it owns or leases that contains Asbestos Containing Building Material's (ACBM's) or is assumed to contain ACBM.
- Subsequent Three Year Re-inspections (2009, 2012, 2015, etc) shall start in the Fall (October, November, December, January). The Building Engineer/Assistant should assist the Building Inspector with appropriate access to all areas including (Crawlspaces/Attics) and rooms in the facility. There is no action required of the Principal.
- An accredited Building Inspector shall visually inspect and touch to determine friability, all areas that are identified in the Management Plan as ACBM or assumed ACBM. The date of the surveillance is recorded, the inspectors name and any changes in the conditions of the materials. The Building Inspectors state of accreditation and license number is required.
- After the inspection, the Building Inspector shall make a copy of the inspection documents and insert into the front of the latest Management Plan (AHERA Three Year Reinspection report). The original document is returned to the LEA's Environmental Library and filed.
- The Building Inspector shall return the reinspection data to the Management Planner to be assessed and determine appropriate response actions and a report issued (AHERA Three Year Reinspection report). One copy of the report is delivered to the schools Principal to be permanently retained with all previous environmental data. Another copy is retained in the LEA's Environmental Library.



School District of Philadelphia
Office of Environmental Management & Services
440 North Broad Street
Philadelphia, PA 19130
(215) 400-4750

School District of Philadelphia **Asbestos Management Program**

TABLE OF CONTENTS

DefinitionsPage 9	
1.	Introduction
	Summary of Asbestos Management Plan Asbestos Management Plan Execution
4.	Summary of Program Execution a. Asbestos Management Plan Execution
5.	Responsibilities a. OEMS b. Asbestos Worker/Supervisor "A-TEAM"
6.	Requirements
7.	AHERA O&M PlanPage 15 a. Controls
8.	O&M Response Actions
	O Deferences and Descriptions Page 1

DEFINITIONS / ACRONYMS

ACM/PACM: Asbestos Containing Material/Potential Asbestos Containing

Material

AHERA: Asbestos Hazard Emergency Response Act

AIR FORM: Asbestos Inspection Report Form

Amended Water: Water to which a surfactant (soap) has been added

AMP: Asbestos Management Program/Asbestos Management Plan

Asbestos Designate Person: Individual assigned by the district to oversee asbestos related

issues.

Asbestos Regulated Area: Location that is posted as an asbestos work area in which only

approved and accredited personnel are permitted to enter

AST: Asbestos Support Team involving approved and accredited

school district tradespersons personnel that are school district

person

A-TEAM: School District of Philadelphia asbestos workers

CIP: Capital Improvement Program

Consultant: Asbestos consulting firm hired by the District

Demolition Directive: Memorandum – August 4, 2006 from Patrick Henwood

EPA: Environmental Protection Agency

In House Personnel: School District of Philadelphia asbestos workers

LEA: Local Education Agency

O&M: Operations and Maintenance

OEMS: Office of Environmental Management and Services

OSHA: Occupational Safety and Health Administration

PEL: Permissible Exposure Limit

PSD or SDP: Philadelphia School District/School District of Philadelphia

PSIT: Philadelphia School Improvement Team

STEL: Short Term Exposure Limit

1. Introduction

The School District of Philadelphia, Asbestos Policy Statement:

"The School District of Philadelphia is dedicated to providing a safe and healthful work environment for its employees, students, faculty, contractors and visitors. In recognition of the potential health problems associated with asbestos, the School District of Philadelphia is committed to a comprehensive asbestos control program. This program is implemented and maintained through the School District of Philadelphia's Office of Environmental Management and Services (OEMS)."

OEMS has the responsibility of establishing procedures for asbestos abatement, asbestos inspection, air monitoring, renovation and demolition activities within all School District of Philadelphia owned or leased facilities.

These procedures are developed to ensure that:

- (1) People are not exposed to significant levels of asbestos fibers
- (2) Asbestos waste is handled and disposed of properly
- (3) Members of the School District of Philadelphia community have access to the Office of Environmental Management and Services for information, assistance, guidance, and interpretation regarding asbestos related matters.
- (4) Members of the School District of Philadelphia community have access to the Asbestos Management Plans as required and outlined in the US EPA AHERA regulations including annual written notification to all parents.
- (5) Compliance with all applicable Federal, State and Local Asbestos Regulations

Requirements outlined in this manual are mandatory in nature where the word "SHALL" is used and are advisory in nature where the word "SHOULD" is used.

2. Summary of Asbestos Management Program

The School District of Philadelphia's Asbestos Management Program was established to meet the requirements of Federal, State, and Local Regulations.

These regulations include, but are not limited to:

- US Environmental Protection Agency Asbestos Hazard Emergency Response Act (US EPA AHERA) and National Emissions Standard for Hazardous Air Pollutants subpart M, Part 61 (NESHAP);
- US Department of Labor, Occupational Safety and Health Administration (OSHA) General Industry Standard (29 CFR 1910.1001) and the OSHA Asbestos Standard for the Construction Industry (29 CFR 1926.1101);
- The Commonwealth of Pennsylvania, Department of Labor and Industry, Asbestos Occupations, Accreditation and Certification Act;
- The City of Philadelphia, Department of Public Health, Asbestos Control Regulations.

3. Asbestos Management Program Execution

a) General Execution

The Office of Environmental Management and Services (OEMS) develops, implements and manages safety and health programs for the School District of Philadelphia faculty, staff and students and assists with ensuring that all contractors comply with Federal, State and Local Environmental Regulations. The OEMS provides the oversight of School District of Philadelphia employees (Asbestos A-Team), environmental consultants, and asbestos abatement contractors for all projects within the School District of Philadelphia concerning Asbestos Containing Materials.

The control of safety and health hazards at the School District of Philadelphia is primarily through the implementation of engineering, work practice and administrative controls. Personal Protective Equipment (PPE) is used to supplement these controls or whenever the controls are not feasible or are in the process of being implemented. PPE is also recommended whenever exposures to chemical, physical or biological agents can be prevented or reduced by its use.

This written program establishes the procedures necessary to:

- 1) meet established standards and federal regulations for occupational exposure to asbestos fibers;
- 2) meet the requirements of the City of Philadelphia Asbestos Control Regulations which encompasses the disturbance and/or abatement of asbestos containing building materials;
- 3) provide the necessary health and safety protection to the School District of Philadelphia staff, faculty, students, contractors and visitors.

This program is strengthened by input and cooperation with the Philadelphia Federation of Teachers (PFT), Health and Welfare Fund.

4. Summary of Program Execution

a) Asbestos Management Program Execution

The Asbestos Management Program is administered by the Office of Environmental Management and Services (OEMS). OEMS provides the following services primarily through professional consultants:

- (1) exposure monitoring services;
- (2) building inspection/surveys (bulk sampling) for the identification of asbestos containing materials;
- (3) asbestos project design services;
- (4) asbestos abatement project and air monitoring services;
- (5) emergency response to fiber release episodes;
- (6) education/information;
- (7) medical monitoring;
- (8) training for School District of Philadelphia personnel

5. Responsibilities

a) Office of Environmental Management and Services

OEMS is responsible for performing the following functions:

- (1) Developing and administering of the Asbestos Management Program.
- (2) Providing asbestos-related services to all School District of Philadelphia departments.
- (3) Conducting required training of the Asbestos Management Program and working jointly with departments to schedule training.
- (4) Identifying and posting areas where labeling/signage are required.
- (5) Medical Monitoring of OEMS "A-TEAM" and other departments "AST" Asbestos Program staff.

- (6) Certification and training as required for OEMS "A-TEAM" and other departments "AST" Asbestos program staff.
- (7) Record keeping as outlined in Section 3.5 and all records as by required by US EPA AHERA regulations.

b) Asbestos Worker/Supervisor - "A-TEAM"

- (1) OEMS shall ensure that all "A-TEAM" workers/supervisors adhere to the following requirements:
 - a) Attend an initial Worker/Supervisor Asbestos Course;
 - b) Maintain the annual re-certification per EPA AHERA requirements and Commonwealth of Pennsylvania Asbestos Occupations, Accreditation and Certifications Act;
 - c) Undergo an annual Asbestos Medical Evaluation;
 - d) Undergo an annual Respirator Medical Clearance;
 - e) Undergo an annual Respirator Fit Testing.

c) Asbestos Designated Person

The Asbestos Designated Person is responsible for:

- (1) Assuring the health and safety of employees, students and visitors in the School District of Philadelphia facilities under his/her control.
- (2) Being kept informed of all areas under his or her jurisdiction where potential asbestos exposures exist and initiating protection programs that adhere to the Asbestos Management Program requirements of this manual.
- (3) Assuring that Asbestos Management Program requirements are adhered to by principal investigators, project managers, supervisors, or division heads, and School District of Philadelphia personnel under their supervision.
- (4) Ensuring that all employees within the Asbestos Management Program comply with (OSHA 1910.1001 (j) (7) (iv)) and the US EPA AHERA regulations by attending the required training.
- (5) Ensure the posting of:
 - a) Warning labels/signage
 - b) Commonwealth of Pennsylvania Asbestos Abatement and Demolition/Renovation Notification form
 - c) Asbestos Inspection Reports (AIR) form (where required)
 - d) Ensuring that Construction Projects follow the Demolition Directive procedures as outlined in the August 4, 2006 letter.

d) Supervisor or Project Manager (Capital, Maintenance and Facilities)

Each person in charge of a project, maintenance/repair, renovation/demolition, or other activity from the Departments of Capital, Maintenance, and/or Facilities, where asbestos containing material may be present is responsible for:

Identifying, with the assistance of OEMS, asbestos containing building materials prior to any disturbance of these materials. Various Federal (EPA and OSHA) and Local (City of Philadelphia Asbestos Control Regulations) require Asbestos Inspections prior to renovation/demolition activities. This shall be accomplished by always following the Asbestos Management Program Procedures as follows:

(1) Ensure that the requirements of the Asbestos Management Program Procedures are followed by all personnel, trades, and contractors who are involved with the project;

- (2) Review of the required Asbestos Inspection Report (AIR) form (Attachment 1) and AHERA Management Plan documents prior to activities that may disturb any Asbestos Containing Materials;
- (3) Perform all project related duties as outlined in the Project Management Responsibilities;
- (4) Keep the department chairperson or director informed on any actions proposed or taken regarding the Asbestos Management Plan;
- (5) Ensuring that Construction Projects follow the Demolition Directive procedure outlined in the August 4, 2006 letter.

e) Employee - Capital

School District of Philadelphia Capital employees and/or consultants shall:

- (1) Ensure that no suspect or asbestos containing building materials are disturbed in the course of the projects they are performing or managing. This shall be accomplished by notifying their supervisor and OEMS by issuance of a work order permit (a.k.a PSIT Service Request Form) and verifying that the materials which may be disturbed are non-asbestos containing. If this information is not available or verification has not been made, these materials should not be disturbed.
- (2) Immediately notify OEMS and their supervisor in the event of a potential fiber release episode upon discovery of visible damage to asbestos containing materials.
- (3) Ensuring that Construction Projects follow the Demolition Directive procedures as outlined in the August 4, 2006 letter.

The types of projects represented as part of the Capital Improvement Program are as follows:

- (1) Complete Renovation of an existing building that addresses all facility component concerns and educational program needs;
- (2) Major Renovation of an existing building addressing significant facility component and educational improvements;
- (3) Addition to an existing building (either as an attachment or stand-alone structure) to accommodate needed program space;
- (4) Conversion of an existing facility to accommodate a change in educational program;
- (5) Facility Component Improvement of specific facility needs (i.e. electrical or HVAC system upgrades, ADA improvements, life safety improvements, exterior renovations, etc.)

f) Employee - Maintenance

School District of Philadelphia Maintenance employees shall:

- (1) Ensure that no suspect or asbestos containing building materials are disturbed in the course of their duties or work they are performing. This shall be accomplished by notifying their supervisor and OEMS by issuance of a work order permit and verifying that the materials which may be disturbed are non-asbestos containing. If this information is not available or verification has not been made, these materials should not be disturbed.
- (2) Immediately notify OEMS and their supervisor in the event of a potential fiber release episode or upon discovery of visible damage to asbestos containing materials.
- (3) All employees involved in maintenance activities shall attend required Asbestos Awareness training program within 60 days of employment.

g) Employee - Facilities & Custodial

School District of Philadelphia Facilities and Custodial employees shall:

- (1) Ensure that no suspect or asbestos containing building materials are disturbed in the course of their duties or work they are performing. This shall be accomplished by notifying their supervisor and OEMS by issuance of a work permit and verifying that the materials which may be disturbed are non-asbestos containing. If this information is not available or verification has not been made, these materials should not be disturbed;
- (2) Immediately notify OEMS and their supervisor in the event of a potential fiber release episode or upon discovery of visible damage to asbestos containing materials.
- (3) All employees involved in Facilities and Custodial activities shall attend require Asbestos Awareness training program within 60 days of employment.

6. Requirements

a) Employee Exposure Monitoring

When information indicates that an employee's exposure to asbestos fibers may equal or exceed an 8-hour time-weighted average of 0.1 f/cc * (per OSHA 1910.1001 & 1926.1101), OEMS shall develop and implement an asbestos exposure monitoring program. The sampling strategy shall be designed to identify employees by work task (job classification) that is exposed to asbestos fibers that exceed an 8-hour time-weighted average of 0.1 f/cc.

b) Employee Notification

OEMS shall notify in writing, each employee exposed to asbestos fibers at or above an 8-hour time weighted average of 0.1 f/cc.

c) Observation and Monitoring

OEMS shall provide employees or their representatives with an opportunity to observe any exposure measurements conducted.

d) Training Program

OEMS shall institute a training program which meets the requirements of AHERA for all employees who perform maintenance operations in a facility/school which contains asbestos containing materials or presumed asbestos containing materials and 1910.1001 (j), and the Commonwealth of Pennsylvania Department of Labor and Industry and the City of Philadelphia Asbestos Control Regulations. The affected departments shall ensure employee participation in this program. The OEMS "A-TEAM" and other departments "AST" Asbestos Program staff training shall be conducted annually for each employee as required by all Federal, State and Local for each asbestos discipline.

All Asbestos Awareness training as required by AHERA shall be performed within 60 days of employment and shall include:

- o Health effects of asbestos
- o Locations of ACM and PACM in the building/facility
- Recognition of CM and PACM damage and deterioration
- o Requirements of the OSHA 1910.1001 standard relating to maintenance
- O Proper response to fiber release episodes
- o Procedure to be followed to isolate areas affected by fiber release

e) Access to Information

OEMS shall make available to affected employees or their representative's copies of the Occupational Safety and Health Administration (OSHA) General Industry Standard Part 1910.1001 and the department shall post a copy in the workplace.

f) Record Keeping

OEMS shall maintain an accurate record of all employee exposure measurements. OEMS and/or the School District of Philadelphia Human Resources Department shall maintain records of employee medical monitoring program. OEMS shall maintain all employee training records. All records shall be provided upon request to employees, former employees, representatives designated by the individual employee.

7. AHERA OPERATIONS AND MAINTENANCE PLAN

a) CONTROLS

i. Work Order System

Minimizing disruption of ACM/PACM during maintenance and renovation activities is the primary goal and task encountered by OEMS. Operations and maintenance employees and contractors should be warned to avoid conducting any maintenance work which may disturb ACM/PACM. Initiating a work order system, where all work orders or requests are channeled through the Office of Environmental Management and Services (OEMS), will be the method used to control and minimize disruption of ACM/PACM.

Any work performed by in-house personnel or contractors that could or will impact ACM/PACM shall be coordinated by OEMS. A completed Asbestos Inspection Report Form (Attachment 1) shall be issued to in-house personnel and/or all contractors whose work could impact ACM/PACM. This form should accompany each contract issued to an outside contractor and posted on the jobsite.

All work order requests for maintenance and renovation activities in areas where ACM/PACM is suspected or known to be present are to be submitted to OEMS prior to proceeding with work. OEMS is responsible for reviewing asbestos survey records for information about the presence of ACM/PACM in the area where the work is to be performed. OEMS should physically inspect the area to ensure existing records reflect actual conditions. If no asbestos is present, a work order is not necessary and the planned actions can proceed. If ACM/PACM is found to be present in the area, OEMS will sign the work order application and obtain an approved and accredited asbestos contractor or assign OEMS "A-TEAM" to abate the ACM/PACM.

ii. Regulated Areas

The owner will identify and regulate all areas where airborne concentrations of ACM/PACM exceed the Permissible Exposure Limit (PEL)* (Per OSHA determined to be 0.1 f/cc) and/or short term exposure limit (STEL) (Per OSHA determined to be 0.1 f/cc), or there is reasonable possibility that the (PEL) and/or (STEL) may be exceeded. All ACM/PACM removal activities involving thermal system insulation ACM/PACM (Class I), surfacing ACM/PACM (Class I), and miscellaneous ACM/PACM such as floor tile, roofing, and siding mastic, etc. (Class II), and repair and maintenance operations where thermal system insulation and surfacing ACM/PACM is likely to be disturbed (Class III) will be performed in accordance with federal, state, and local regulations. All asbestos abatement work and activities will be designed and managed as asbestos regulated areas. These areas will be demarcated and labeled.

iii. Warning Signs

Warning signs shall be displayed at all approaches to each asbestos regulated area. The asbestos abatement contractor will provide OSHA warning signs in all regulated areas during removal, repair, and other maintenance activities. OEMS will provide AIRs to all contractors who must inform all employees and supervisors working in locations contiguous to asbestos regulated areas of the potential hazards and work practices required.

iv. Warning Labels

Warning labels and./or signage shall be affixed to all raw materials, mixtures, scrap, waste, debris, and other products containing asbestos fibers, or to their containers. Generally, the asbestos abatement contractor or OEMS A-Team personnel will provide all warning labels for ACM/PACM containment.

8. O & M RESPONSE ACTIONS

The Asbestos Management Program general O&M procedures are outlined in this section. Additional requirements specific to asbestos abatement activities are included in the Project Design documents for all Asbestos Abatement Work. Regular cleaning, inspection, and reporting of ACM/PACM deterioration or other problems must be diligently practiced by all employees including custodial and maintenance personnel.

a) Facility Maintenance Isolation of Area Responsibilities

Maintenance personnel are often required to work in areas where ACM/PACM may potentially be disturbed. Most maintenance activities are conducted by in-house staff, outside contractors, or a combination.

Emergency fiber release episodes, such as pipe fitting or valve breaks, emergency boiler work, or mechanical equipment repair will be responded to by OEMS A-Team personnel or asbestos abatement contractor personnel. The owner's maintenance staff will: (1) isolate the emergency fiber release area; (2) post warning signs to prevent unauthorized access, and (3) notify their supervisor and OEMS. OEMS will ensure that the fiber release area remains isolated and is properly cleaned by and approved and accredited abatement contractor or by OEMS A-TEAM personnel.

b) Unlikely Contact with ACM/PACM

Maintenance activities or repairs which can be performed without contacting or disturbing the ACM/PACM require little more than normal care and good workmanship. For example, valves which are either uncovered or covered with non-asbestos insulation can be packed or repaired without disturbing asbestos insulation on nearby pipes. The major precaution is to ensure that maintenance and custodial personnel are familiar with procedures such as isolating the area, posting warning signs, and notifying OEMS in the event of any accidental ACM/PACM disturbance.

c) Accidental Disturbance of ACM/PACM

Maintenance and facilities personnel shall notify OEMS any time a fiber release is suspected. If friable ACM/PACM becomes airborne in the building,

d) Planned Disturbance of ACM/PACM

Maintenance activities that may impact ACM/PACM include access to a valve, flange, duct, or related system component.

Where asbestos-containing insulation must be removed to maintain or repair the thermal system, the ACM/PACM will imminently be disturbed. ACM/PACM removal work shall be conducted by OEMS A-Team personnel or an approved and accredited asbestos abatement contractor.

If friable ACM/PACM becomes airborne in the building, maintenance and facilities personnel shall secure the area and contact OEMS. OEMS shall respond accordingly.

e) Miscellaneous ACM/PACM

Miscellaneous types of ACM/PACM may include vinyl asbestos floor tiles, mastics/adhesives and woven vibration dampers. Disturbance of these materials should be avoided. Routine maintenance activities involving these materials should not pose a problem if handled properly. Questions on the proper removal and disposal of miscellaneous ACM/PACM should be directed to OEMS. OEMS will contact an approved and accredited asbestos abatement contractor or utilize OEMS A-TEAM personnel to assist with miscellaneous ACM/PACM clean-up activities.

f) Vinyl Asbestos Floor Tile

Asbestos-containing floor tiles in good condition are considered non-friable unless they are crushed, drilled, sawed, sanded or disturbed by any activity that breaks up the material. Routine maintenance of these materials should employ the use of non-abrasive buffers and wet cleaning technique. Broken or loose floor tiles should be removed and disposed of as asbestos waste by OEMS. Remaining debris should be vacuumed with a HEPA vacuum and the area wet mopped using amended water.

g) Mastics/Adhesives

Mastics and adhesives containing asbestos in good condition are considered non-friable and do not pose a potential health concern unless crushed, drilled, sawed, sanded, or otherwise abraded. Questions on the proper removal should be directed to OEMS.

h) Woven Vibration Dampers

Woven vibration dampers in good condition are considered non-friable and do not pose a potential health concern unless cut, crushed, drilled, sawed, sanded, or otherwise abraded. Questions on the proper removal should be directed to OEMS.

i) Other Work Practices

Any special work not included in this section should be addressed to OEMS for review prior to the initiation of work that may involve the disturbance of ACM/PACM.

j) Fiber Release Episodes

Facilities and maintenance staff should report to OEMS the presence of asbestos debris, water or physical damage to ACM/PACM, or any other evidence of possible fiber release. OEMS should have the OEMS A-Team personnel or an approved and accredited abatement contractor respond to the site to clean up debris and make repairs as soon as possible. OEMS will also contact a consultant to conduct air monitoring and prepare a report and submit at project completion to OEMS for each episode. OEMS will forward the reports for each site location AHERA Management Plan accordingly.

9. REFERENCES and RESOURCES

Applicable regulations for asbestos projects impacted by renovation, demolition, and maintenance activities.

- Philadelphia Air Management Services Asbestos Control Unit http://www.phila.gov/health/units/ams/Asbestos/asbestos.html
- Pennsylvania Asbestos Occupations, Accreditation and Certification Act
 http://www.dli.state.pa.us/landi/cwp/view.asp?a=185&q=56262&landiNav=
- United States Environmental Protection Agency Asbestos Home Page
 http://www.epa.gov/asbestos/
- Occupational Safety and Health Administration (OSHA) Asbestos Home
 http://www.osha.gov/SLTC/asbestos