### SCHOOL DISTRICT OF PHILADELPHIA



## Asbestos Hazard Emergency Response Act "AHERA"

## THREE-YEAR RE-INSPECTION 2015-2016

# and ASBESTOS MANAGEMENT PLAN for the

Samuel Pennypacker Elementary School

ULCS# 6350 Building # B635001-1 1858 E. Washington Lane Philadelphia, Pennsylvania 19138

Year Built: 1930

December 2015

Conducted by:

Accredited Environmental Technologies, Incorporated
Batta Environmental Associates, Incorporated
Criterion Laboratories, Incorporated
Environmental Testing Consultants, LLC
G & C Environmental Services, Incorporated
KEM Partners, Incorporated
Synertech, Inc.
TTI Environmental, Inc.
USA Environmental Management, Inc.
The Vertex Companies, Inc.

Management Plan Prepared by: Criterion Labs, Inc and Synertech Inc.

This report must remain in the Main Office as mandated by the US EPA AHERA Regulations.

#### AHERA THREE-YEAR REINSPECTION VOLUME IX

#### **Table of Contents**

#### **Transmittal Letter**

#### **Executive Summary**

- I. Summary list of Confirmed Asbestos Containing Building Materials
- II. Summary list of Assumed Asbestos Contain Building Materials
- III. Summary list of Non-Asbestos Containing Building Materials
- IV. Summary list of Non Suspect Asbestos Containing Building Materials
- V. Summary List of Auditorium DATA for this location
- VI. Summary list of Attic and/or Crawlspace DATA for this location
- VII. Summary list of Pipe Chase/Pipe Shaft DATA for this location

#### **Section I** Report of Re-Inspection

- A. Introduction
- B. Three-Year Re-inspection IX Overview
- C. Post- Management Plan Activities and Changes
  - C.1 Sampling and Analysis
  - C.2 New Floor Tile Sampling
  - C.3 Abatement Activity
  - C.4 Periodic (Six-Month) Surveillance (Damaged Materials)

#### **Section II** Re-Inspection Data

- A. Introduction
- B. Re-Inspection Key Definitions
- C. Room by Room Location Log Report

#### **Section III** Certificates

A. Management Planner/Building Inspector Certificates

#### **Section IV** Cross Reference Table Page 1-8

Asbestos Management Program Page 9-19

#### SCHOOL DISTRICT OF PHILADELPHIA EDUCATIONAL CENTER

## 440 NORTH BROAD STREET PHILADELPHIA, PENNSYLVANIA 19130

OFFICE OF ENVIRONMENT AL MANAGEMENT AND SERVICES

PHONE (215)-400-4750

January 2016

TO: All Principals

All Building Administrators

FROM: Fran Burns

**Chief Operating Officer** 

Francine Locke, M.S., Director

Office of Environmental Management and Services

SUBJECT: AHERA Three (3) Year Re-inspection IX report

In order to comply with the provisions of the Asbestos Hazard Emergency Response Act (AHERA) the attached report is submitted to you. The law requires that this report be kept in the Main/Principal's office. It cannot be removed from these locations. *If the school (program) is relocated to a different building, these environmental documents are to be safely retained for the next school/building occupants*. All asbestos reports must be available to the public and Federal EPA upon request.

Fran Burns

Chief Operation Officer

Francine Locke, M.S., Director Office of Environmental Management

and Services

AHERA-2d Revised 12/14/15

#### **Executive Summary**

This Asbestos Hazard Emergency Response Act (AHERA) Three-Year Re-inspection "Volume # IX" Management Plan at this location, has been completed and the report of re-inspection submitted to the School District of Philadelphia. The re-inspections in all School District of Philadelphia buildings of 2015-2016 were conducted and completed between October 5<sup>th</sup>, 2015 through March 30<sup>th</sup>, 2016 as a joint project by Accredited Environmental Technologies, Inc., Batta Environmental Associates, Inc., Criterion Laboratories, Inc., Environmental Testing Consultants, LLC, G & C Environmental Services, Inc., KEM Partners, Inc., Synertech, Inc., TTI Environmental, Inc., USA Environmental Management, Inc. and The Vertex Companies, Inc.

In general, the School District of Philadelphia Office of Environmental Management and Services conducts Environmental Impact Evaluations and provides Asbestos Inspection Reports prior to any renovation, demolition and/or maintenance activities. The AHERA report must be reviewed prior to any renovation, demolition and/or maintenance activities in order to avoid the unknowing disturbance to Asbestos Containing Building Materials identified within this location. In addition, prior to work activities above all drop ceilings this report should be reviewed to avoid potential disturbances to Asbestos Containing Materials. Refer to Section IV of the Cross Reference Table, for additional Asbestos Management Program information. Contact the Office of Environmental Management and Services to have an Environmental Impact Evaluation conducted prior to any renovation, demolition and/or maintenance activities within this facility.

The information contained in this report was obtained from the original Asbestos Management Plan for the school, from update reports on changes and activities since the completion of the 1<sup>st</sup> Management Plan for each location and from all prior inspections performed and documented in Volume # I through Volume VIII (dated respectively 1992, 1995, 1998, 2001, 2004, 2007, 2010 or 2013) (if applicable) - and by this Three-Year Re-inspection of this school. The re-inspection report/Management Plan of 2015-2016 were reviewed and prepared collectively by Management Planner Megan Vala, Mary Anne Lerro of Criterion Laboratories, Inc. and/or Monique Causley, of Synertech Inc.

The 2015-2016 inspection process included the addition of a comprehensive Room by Room Inventory of all Thermal (T), Surfacing (S) and Miscellaneous (M) Materials specific to each room of this facility. Inspections of each room's thermal, ceilings, walls, floors and miscellaneous items regardless of Asbestos Content are categorized on the Room by Room Location Log Report for this location. Rooms or areas of the facility that were not accessible at the time of the inspection are marked with an "X". The Room by Room Location Log Report is found in Section II C of this Management Plan.

All Presumed or Suspect Asbestos Containing Building Materials (ACBMs), listed in the following summary charts are categorized as Confirmed, Assumed, Non-Asbestos, and/or Non-Suspect (ACBMs) were identified in the original Management Plan, or in the Volume I through Volume VIII AHERA Three-Year Re-inspection reports, and were re-inspected as part of this project.

As mandated by the U S EPA AHERA regulations, periodic Six-Month inspections and Three-Year Re-inspections of this location will be performed and the Inspection Data in this report will be updated accordingly.

Please feel free to contact the School District of Philadelphia's Office of Environmental Management and Services (OEMS) regarding any comments, questions, or concerns regarding this report or any Environmental related topic. OEMS staff can be reached at (215) 400 4750, via fax at (215) 400 4751 or via e-mail at <a href="mailto:flocke@philasd.org">flocke@philasd.org</a> and/or <a href="mailto:flocke@philasd.org">flocke@philasd.org</a>.

Additional information can be found on our website. Here is the link to the OEMS website. http://webgui.phila.k12.pa.us/offices/e/environmental

#### I. Summary list of Confirmed Asbestos Containing Building Materials within this facility

These charts are to be used for a quick reference\* in order to avoid the unknowing disturbance of Asbestos Containing Materials during any and all Operations, Maintenance, Renovation, and/or Demolition activities at this location. These materials have been sampled and Laboratory Analysis has CONFIRMED the presence of Asbestos. Contact OEMS prior to the disturbance of any of the following materials.

#### **Confirmed Asbestos Containing Building Materials for this location**

Pipe Fitting Insulation	Pipe Insulation > 6 inch	Pipe Insulation 2-6 inch
Radiator Insulation	Transite Electrical Panel	

<sup>\*</sup> Always refer to the Room by Room Logs for each specific material classification as the material classification findings may be different in various rooms throughout this facility.

<sup>\*\*</sup> Some Materials may have multiple classifications (Confirmed, Assumed, NAD and Non Suspect) within this facility.

#### II. Summary list of Assumed Asbestos Containing Building Materials within this facility

These charts are to be used for a quick reference\* in order to avoid the unknowing disturbance of Asbestos Containing Materials during any and all Operations, Maintenance, Renovation, and/or Demolition activities at this location. These materials have not been sampled and should not be disturbed until verification of Asbestos Content. Contact OEMS for assessment and sampling prior to the disturbance of these materials.

#### **Assumed Asbestos Containing Building Materials for this location**

Blackboard Glue Dots	Floor Tile VAT 12" x 12"	Linoleum
Radiator Insulation	Sectional Boilers	Sink Undercoat Mastic

<sup>\*</sup> Always refer to the Room by Room Logs for each specific material classification as the material classification findings may be different in various rooms throughout this facility.

<sup>\*\*</sup> Some Materials may have multiple classifications (Confirmed, Assumed, NAD and Non Suspect) within this facility.

#### III. Summary list of Non-Asbestos Containing Building Materials within this facility

These charts are to be used for a quick reference\* in order to avoid the unknowing disturbance of Asbestos Containing Materials during any and all Operations, Maintenance, Renovation, and/or Demolition activities at this location. These materials have been sampled and Laboratory Analysis has indicated NO Asbestos present or NO ASBESTOS DETECTED (NAD).

#### Non- Asbestos Containing Building Materials for this location

Ceiling Tile 1' x 1'	Plaster Ceiling	Plaster Walls

<sup>\*</sup> Always refer to the Room by Room Logs for each specific material classification as the material classification findings may be different in various rooms throughout this facility.

<sup>\*\*</sup> Some Materials may have multiple classifications (Confirmed, Assumed, NAD and Non Suspect) within this facility.

#### IV. Summary list of Non-Suspect Asbestos Containing Building Materials within this facility

These charts are to be used for a quick reference\* in order to avoid the unknowing disturbance of Asbestos Containing Materials during any and all Operations, Maintenance, Renovation, and/or Demolition activities at this location. These materials are not typically known to contain Asbestos.

#### Non-Suspect Asbestos Containing Building Materials for this location

Brick Wall	Carpet	Ceiling Tile 2' x 4'
Cement Floor	Ceramic Tile Floors	Ceramic Tile Walls
Concrete Ceiling	Fiberglass Pipe Insulation	Wood Floor

<sup>\*</sup> Always refer to the Room by Room Logs for each specific material classification as the material classification findings may be different in various rooms throughout this facility.

<sup>\*\*</sup> Some Materials may have multiple classifications (Confirmed, Assumed, NAD and Non Suspect) within this facility.

#### V. Summary list of Auditorium DATA for this location

These charts are to be used for a quick reference of the Auditorium DATA within this facility. Sampling of the Auditorium Ceilings throughout the District is more difficult because of the various ceiling heights. As sampling occurs this information is updated on a case by case basis for each specific location and facility.

This is a list of known materials for this location's Auditorium

Auditorium										
Auditorium	Wood Floor	Non Suspect ACM								
Auditorium	Plaster Walls	NAD								
Auditorium	Plaster Ceiling	NAD								
Auditorium	Radiator Insulation	Confirmed								
Auditorium Stage	Wood Floor	Non Suspect ACM								
Auditorium Stage	Plaster Walls	NAD								
Auditorium Stage	Plaster Ceiling	NAD								
Auditorium Stage Restroom - Left	Ceramic Tile Floors	Non Suspect ACM								
Auditorium Stage Restroom - Left	Ceramic Tile Walls	Non Suspect ACM								
Auditorium Stage Restroom - Left	Ceiling Tile 2' x 4'	Non Suspect ACM								
Auditorium Stage Restroom - Right	Ceramic Tile Floors	Non Suspect ACM								
Auditorium Stage Restroom - Right	Ceramic Tile Walls	Non Suspect ACM								
Auditorium Stage Restroom - Right	Ceiling Tile 2' x 4'	Non Suspect ACM								

<sup>\*</sup> Always refer to the Room by Room Logs for each specific material classification as the material classification findings may be different in various rooms throughout this facility.

<sup>\*\*</sup> Some Materials may have multiple classifications (Confirmed, Assumed, NAD and Non Suspect) within this facility.

#### VI. Summary list of Attic and/or Crawlspace DATA for this location

These charts are to be used for a quick reference regarding the Attics and/or Crawlspaces inspection DATA within this facility. Contact OEMS prior to entering any attic or crawlspace within this facility and refer to the below chart and legend for Category Rank determination. The Data relative to these spaces is updated as conditions change regarding Abatement or Renovation activity on a case by case basis for each specific location and facility. In general, Crawlspaces are below the basement or 1st floor and Attics are above the floor space.

#### Category Rank Legend

- "A" No Asbestos Containing Materials Sample Results indicate NO ACM on pipes, fittings, elbows, or equipment located within this functional space, and NO VISIBLE DEBRIS or DAMAGE observed at time of this inspection.
- "B" Asbestos Containing Materials Exist Sample Results indicate ACM on pipes, fittings, elbows, or equipment located within this functional space, HOWEVER, NO VISIBLE DEBRIS or DAMAGE observed at time of this inspection.
- "C" Asbestos Containing Materials Exist Sample Results indicate ACM on pipes, fittings, elbows, or equipment located within this functional space, and LOCALIZED VISIBLE DEBRIS or DAMAGE observed at time of this inspection.
- "D" Asbestos Containing Materials Exist Sample Results indicate ACM on pipes, fittings, elbows, or equipment located within this functional space and DISTRIBUTED VISIBLE DEBRIS or SIGNIFICANT DAMAGE observed at time of this inspection.
- "E" No Bulk Sample Results Available SUSPECT ACM OBSERVED. Contact OEMS immediately for additional instructions.

Attic/Crawlspace	Access Area	Floor Surface	Category Rank	Comments
Attic	3 <sup>rd</sup> Floor Corridor	Wire Lathe	"A"	Horsehair
Attic above 3 <sup>rd</sup> Floor	Main Stairwell above 3 <sup>rd</sup> Floor	Wire Lathe/Wood Planks	"B"	150 Hard Fittings, 1000 LF Mag Block PI
Crawl Space	X	X	X	None exists

#### VII. Summary list of Pipe Chase/Pipe Shaft DATA for this location

These charts are to be used for a quick reference regarding the information known about the Pipe Chases and/or Pipe Shafts inspection DATA within this facility. Contact OEMS prior to performing renovation activities any Pipe Chase and/or Pipe Shaft within this facility and refer to the below chart and legend for Asbestos Content of various materials identified within each space. The Data relative to these spaces is updated as conditions change regarding Inspection, Abatement and/or Renovation activity on a case by case basis for each specific location and facility. In general, Pipe Chases are horizontal spaces and Pipe Shafts are vertical spaces.

Pipe Chases and Pipe Shafts need to be assessed.

#### Section I Report of Re-Inspection

- A. Introduction
- **B.** Three-Year Re-Inspection IX Overview
- C. Post-Management Plan Activities and Changes
  - **C.1** Sampling and Analysis
  - **C.2** New Floor Tile Sampling
  - **C.3** Abatement Activity
  - **C.4** Periodic Six-Month Surveillance (Damaged Materials)

#### Section I - A

#### **Report of Re-inspection**

#### Introduction

The Three-Year Re-inspection IX was performed to fulfill the requirements of 40 CFR Part 763 - the Asbestos Hazard Emergency Response Act (AHERA). As required by AHERA, each Local Education Agency (LEA) must re-inspect all known confirmed or assumed Asbestos Containing Building Material (ACBM) located in the LEA's facilities. This re-inspection is intended to update the original Asbestos Management Plan for the LEA's facilities.

Multiple Building Inspectors of several firms performed the 2015/2016 re-inspection. The reinspection report/Management Plan of 2015-2016 were reviewed and prepared collectively by Management Planner Megan Vala, Mary Anne Lerro of Criterion Laboratories, Inc. and Monique Causley, of Synertech Inc.

All of the certificates can be found in Section III.

During the re-inspection of each School District of Philadelphia facility, all of the Management Plans for that facility were reviewed. Information from the conclusions section of that report is included in this report. Additionally, information on activities such as abatements, cleanings, sampling and inspections, which have taken place since the completion of the original Management Plan, were reviewed during the re-inspection. Information on those activities is included in this report.

As mandated by the U S EPA AHERA regulations, all future periodic Six-Month inspections and Three-Year Re-inspections of this location will be performed and the Inspection Data in this report will be updated accordingly.

#### Section I - B

#### **Three-Year Re-inspection IX Overview**

Each homogeneous area of Asbestos Containing Building Material (ACBM) listed in the original Management Plan or in the 1992, 1995, 1998, 2001, etc., Three-Year Reinspection reports were inspected for the AHERA Three-Year Re-inspection Volume IX, and the information for that material verified. Any changes to a homogeneous area listed in the updates to the Management Plans were verified. Any area of suspected ACBM found in the course of the re-inspection, and not listed in the Management Plan or updates, were either assumed to contain asbestos or sampled and analyzed to determine their asbestos content. Any such new areas either assumed to contain asbestos or determined through analysis to contain asbestos were included in the report of the Three-Year Re-inspection. The results of the AHERA Three-Year Re-inspection IX are tabulated in the Room by Room log reports located in *Section II-C* of this report.

As previously noted, all future periodic Six-Month inspections and Three-Year Reinspections of this location will be performed and the Inspection Data in this report will be updated accordingly.

#### Post Management Plan Activities/Changes

Information on activities affecting Asbestos Containing Building Materials (ACBMs) at this location is contained in updates to the Management Plan. These updates are kept on file by the School District of Philadelphia and were reviewed for this project. Updates to the Management Plan include the following: Sampling and Analysis, New Tile Installation, Abatement Activity and Periodic Six-Month Surveillance Data.

#### Sampling and Analysis

In the event Sampling occurs, data will be listed here.

Information on the installation of new floor tiles/renovation activities affecting Asbestos Containing Building Materials (ACBMs) at this location is contained in updates to the Management Plan. These updates are kept on file by the School District of Philadelphia and were reviewed for this project. Updates to the Management Plan include the following:

#### New Floor Tile Sampling

In the event that new tile is installed, the material must be tested prior to installation.

Information on the Asbestos Abatement and renovation activities affecting Asbestos Containing Building Materials (ACBMs) at this location is contained in updates to the Management Plan. These updates are kept on file by the School District of Philadelphia and were reviewed for this project. Updates to the Management Plan include the following:

#### **Abatement Activity**

In the event Abatement occurs, data will be listed here.

Information on the AHERA inspection that noted damage to various Building Materials at this location is contained in updates to the Management Plan. These updates are kept on file by the School District of Philadelphia and were reviewed for this project. Work orders are created for Corrective Action responses and tracked for completion. Updates to the Management Plan include the following:

#### Periodic (Six-Month) Surveillance (Damaged Materials)

Date	Element	Floor	On Site Room Name	Material	Amount of Material	of
7/18/2016	1	3	Fire Tower across from Classroom 307	Pipe Insulation 2-6 inch	10 LF	1 LF
7/18/2016	1	3	Fire Tower across from Classroom 307	Pipe Fitting Insulation	1 EA	1 EA

Section II Re-Inspection Data

A. Introduction

**B. Re-Inspection Key Definitions** 

C. Room by Room Location Log Report

#### **Section II - A**

#### **Re-inspection Data**

Introduction

The following information documents the Three-Year Re-inspection IX of the subject school/facility. The Homogeneous Area Reports were produced using the building inspector's field data on the facility. The key to the Homogeneous Area Report is outlined in the following pages of this report.

## Section II - B (page 1 of 4)

## SCHOOL DISTRICT OF PHILADELPHIA AHERA THREE YEAR RE-INSPECTION IX

ITEM	DEFINITION								
ULCS#	Individual identification number assigned to each school within the School District of Philadelphia.								
HOMOGENEOUS AREA ID#	Identification number assigned to each homogeneous area in a school/facility. Each section of the homogeneous area ID is significant.								
	1010/01/01/01 <b>A B C D</b>								
	<ul> <li>A. Is the ULCS# for the school.</li> <li>B. Designates the specific building/building area within the school.</li> <li>C. Designates the floor or level within the building/building area.</li> <li>D. Designates the homogeneous material within that floor or level.</li> <li>Note: Item D may be a number or a letter.</li> </ul>								
SYSTEM AFFECTED	<ul> <li>B. Designates the specific building/building area within the school.</li> <li>C. Designates the floor or level within the building/building area.</li> <li>D. Designates the homogeneous material within that floor or level.</li> </ul>								
AFFECIED	S : Surfacing System								
ITEM AFFECTED	Is a description of the homogeneous material.								
ORIGINAL INSPECTION DATA	This section contains the information found in the original Management Plan (1988-1989).								
AMOUNT OF MATERIAL/ UNIT	Quantity of material, and measuring unit. Units include: Square Feet (SF) Each (EA) Linear Feet (LF) Cubic Feet (CF).								

## SCHOOL DISTRICT OF PHILADELPHIA AHERA THREE YEAR RE-INSPECTION IX

#### **RE-INSPECTION FORM KEY**

ITEM	<b>DEFINITION</b>
------	-------------------

**CND** Corresponds to AHERA condition rating for materials.

**Condition** 

0 : No Damage1 : Damage

2 : Significant Damage

DP

Corresponds to the AHERA material assessment system.

**Damage Potential** 

1 : Potential for Damage

2 : Potential for Significant Damage

ASMD Assumed Asbestos This means that a material was not sampled for asbestos content during the original Management Plan inspection.

RA

This corresponds to the AHERA system of response action rating for materials.

Response Action

Establish O&M Program

2 : Repair and Establish O&M Program

3 : Enclose
4 : Encapsulate
5 : Remove

6 : Partial Removal and Establish O&M Program

**CHANGES** 

This section describes changes to the homogeneous material in the twenty-four years since the original AHERA inspection. The abbreviations are defined below.

**RMVD** Removed **ENCL** Enclosed **ENCP** Encapsulated **DMGD** Damaged **SMPLD** Sampled Material MTRL **RPRD** Repaired None Located N/L **RPLCD** Replaced

#### SCHOOL DISTRICT OF PHILADELPHIA AHERA THREE-YEAR RE-INSPECTION IX

#### RE-INSPECTION FORM KEY

#### ITEM DEFINITION

## THREE YEAR RE-INSPECTION

This section contains the information obtained from the Three-Year Re-inspection IX. With three exceptions, the information categories are identical in format and meaning to those found in the original inspection data section. The three exceptions are defined below.

#### DMGD AMT Amount Damaged

This section gives the quantity of damaged material in a homogeneous area. The quantity is shown in the same format as the amount of material/unit section.

#### NF Newly Friable

This section identifies materials in the original Management Plan which have since become friable.

#### RA Response Action

This rating is based on the AHERA regulations, and is comparable to the RA rating found in the "Original Inspection Data" section. The following table details the response actions.

- 1. Establish O&M Program
- 2. Repair and Establish O&M Program
- 3. Enclose
- 4. Encapsulate
- **5.** Remove
- **6.** Partial Removal and Establish O&M Program

#### a. High Priority Response

The homogeneous material has been scheduled for abatement or other response action.

#### b. Medium Priority Response

The homogeneous material will be scheduled for abatement or other response action as soon as the high priority responses have been addressed.

#### c. Low Priority Response

The homogeneous material will be scheduled for abatement or other response action as soon as the medium priority responses have been addressed.

#### d. On-Going Response/Operations and Maintenance

The homogeneous material does not require abatement or other response action at present, and should be included in the facility's on-going operations and maintenance program.

#### SCHOOL DISTRICT OF PHILADELPHIA AHERA THREE-YEAR RE-INSPECTION IX

#### **RE-INSPECTION FORM KEY**

The information presented in the changes section has been compiled from a variety of sources, including the Re-inspection and the following:

- \* Quality Control/Quality Assurance Reports of asbestos abatement projects, prepared by consultants to the School District.
- \* Permit and Notification Forms for asbestos abatement projects.
- \* Periodic Surveillance Forms
- \* Operations and Maintenance activities performed by School District personnel.
- \* Verbal information from School District personnel.
- \* Reports of sampling and analysis of suspected materials by both School District personnel and outside consultants.

ROOM BY ROOM LOCATION LOG REPORT This section gives information, including damage amount and location, for a specific homogeneous material on a room-by-room basis and follows the Re-inspection form.

*NOTE:* The disparate nature of the above sources of information prohibits the verification of much information within the scope of the AHERA Three-Year Re-inspection. Discrepancies and omissions may exist in this information, and therefore is included on an "as is" basis. The inspectors for the Three-Year Re-inspection IX evaluated homogeneous areas based on the materials current condition and location, as evidenced during the inspector's site visit.

.

#### **Section II - C**

## **Room by Room Location Log Report**

These charts are to be used for a quick reference\* in order to avoid the unknowing disturbance of Asbestos Containing Materials during any and all Operations, Maintenance, Renovation, and/or Demolition activities at this location.

#### *NOTE:*

Contact OEMS prior to the disturbance of any of the materials that are listed as **Confirmed and/or Assumed**.

The quantities listed for (NAD) non-asbestos containing materials and/or Non-Suspect Materials are only estimated and were not measured for the purpose of this report. Field verification of quantities for renovation purposes would be necessary.

	School District of Philadelphia			HEDA Thron-Voor Do	inspection 2015-2016						Reinspection Date: 12/1/2015	1			
	· ·		A			,					-	-			
	Samuel Pennypacker Elementary School			Room by Room Lo	cation Log Report			]			Building Inspector: Bernard J Bryson	-			
	1858 E Washington Lane, Philadelphia, PA 19138										Number: ACC-0125-6-031				
	ULCS# 6350										Management Planner: Megan Vala	1			
												1			
E	Year Built: 1930	_		1		_	_		_	_	Number: 740728				
-														1	
e F												Attic/		1	
m I												Crawl	Damage	Newly	
m I e o n o		System			Confirmed/Assumed/NAD	Amount of	SFLF	Amount o	of SF L	Color F required		Space	Potential	Friable	Response
t r	On-Site Room Name	Affected	Material Description	HID#	Non Suspect ACM	Material	EA	Damage	EA	for VAT	Comments/Description/Notes	Ranking	(DP)	(NF)	Action (RA
1 B	Girl's Restroom by Classroom 003	N/A	Ceramic Tile Floors		Non Suspect ACM	500	SF	0					N/A	N/A	N/A
1 B	Girl's Restroom by Classroom 003	N/A	Ceramic Tile Walls		Non Suspect ACM	1500	SF	0					N/A	N/A	N/A
1 B	Girl's Restroom by Classroom 003	N/A	Concrete Ceiling		Non Suspect ACM	500	SF	0					N/A	N/A	N/A
	Girl's Restroom by Classroom 003	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	80	LF	0					N/A	N/A	N/A
1 B	Storage Room outside of Girl's Restroom - South Hallway	N/A	Cement Floor		Non Suspect ACM	100	SF	0	_	+		+	N/A	N/A	N/A
1 B	Storage Room outside of Girl's Restroom - South Hallway	N/A	Brick Wall		Non Suspect ACM	300 100	SF	0	+			+	N/A N/A	N/A N/A	N/A N/A
1 B	Storage Room outside of Girl's Restroom - South Hallway	N/A	Concrete Ceiling		Non Suspect ACM		SF LF		+			+	N/A N/A	N/A N/A	N/A N/A
1 D	Storage Room outside of Girl's Restroom - South Hallway  Teacher's Lounge/Food Service Room next to Classroom 003	N/A N/A	Fiberglass Pipe Insulation Wood Floor		Non Suspect ACM Non Suspect ACM	50 750	SF	0	+	_		+	N/A	N/A	N/A
	Teacher's Lounge/Food Service Room next to Classroom 003	N/A	Plaster Walls		NAD	2250	SF	0	_			+	N/A	N/A	N/A
1 B	Teacher's Lounge/Food Service Room next to Classroom 003	N/A	Ceiling Tile 2' x 4'		Non Suspect ACM	750	SF	0	+			+	N/A	N/A	N/A
	Teacher's Lounge/Food Service Room next to Classroom 003	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	50	LF	0					N/A	N/A	N/A
	Teacher's Lounge/Food Service Room next to Classroom 003	M	Blackboard Glue Dots	6350/01/0B/SYN/BB/2600	Assumed	20	SF	0					1	Yes	1/D
	Teacher's Lounge/Food Service Room next to Classroom 003	M	Sink Undercoat Mastic	6350/01/0B/SYN/BB/2602	Assumed	8	SF	0			1 Sink - 8 SF	1	1	Yes	1/D
1 B	Restroom inside Teacher's Lounge/Food Service Room next to Classroom 003	N/A	Ceramic Tile Floors		Non Suspect ACM	40	SF	0				1	N/A	N/A	N/A
	Restroom inside Teacher's Lounge/Food Service Room next to Classroom 003	N/A	Ceramic Tile Walls		Non Suspect ACM	120	SF	0					N/A	N/A	N/A
1 B	Restroom inside Teacher's Lounge/Food Service Room next to Classroom 003	N/A	Ceiling Tile 2' x 4'		Non Suspect ACM	40	SF	0					N/A	N/A	N/A
1 B	Classroom 003	N/A	Wood Floor		Non Suspect ACM	750	SF	0					N/A	N/A	N/A
1 B	Classroom 003	N/A	Plaster Walls		NAD	2250	SF	0					N/A	N/A	N/A
1 B	Classroom 003	N/A	Ceiling Tile 2' x 4'		Non Suspect ACM	750	SF	0	_				N/A	N/A	N/A
	Classroom 003	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	30	LF	0					N/A	N/A	N/A
	Classroom 003	M	Blackboard Glue Dots	6350/01/0B/SYN/BB/2600	Assumed	40	SF	0	_		4.01.4.05		1	Yes	1/D
	Classroom 003	M	Sink Undercoat Mastic	6350/01/0B/SYN/BB/2602	Assumed	8	SF	0	+		1 Sink - 8 SF	+	N/A	Yes N/A	1/D N/A
1 D	Classroom 003 Restroom Classroom 003 Restroom	N/A N/A	Ceramic Tile Floors Ceramic Tile Walls		Non Suspect ACM Non Suspect ACM	40 120	SF SF	0	+	+		+	N/A	N/A	N/A
	Classroom 003 Restroom	N/A N/A	Ceiling Tile 2' x 4'		Non Suspect ACM	40	SF	0		+		+	N/A	N/A	N/A
	Hallway from Girl's Restroom to Classroom 003	N/A	Cement Floor		Non Suspect ACM	1000	SF	0	_			+	N/A	N/A	N/A
1 B	Hallway from Girl's Restroom to Classroom 003	N/A	Brick Wall		Non Suspect ACM	3000	SF	0		1		+	N/A	N/A	N/A
	Hallway from Girl's Restroom to Classroom 003	N/A	Plaster Ceiling		NAD	1000	SF	0				1	N/A	N/A	N/A
	Hallway from Girl's Restroom to Classroom 003	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	100	LF	0					N/A	N/A	N/A
	Hallway from Girl's Restroom to Classroom 003	М	Blackboard Glue Dots	6350/01/0B/SYN/BB/2600	Assumed	80	SF	0				1	1	Yes	1/D
											Associated with Fiberglass Insulated Domestic Water				Т
1 B	Hallway from Girl's Restroom to Classroom 003	T	Pipe Fitting Insulation	6350/01/0B/04	Confirmed	15	EA	0			Lines		1	Yes	1/D
	Stairwell outside Classroom 003	N/A	Cement Floor		Non Suspect ACM	400	SF	0				+	N/A	N/A	N/A
1 B	Stairwell outside Classroom 003	N/A	Plaster Walls		NAD NAD	1200	SF SF	0	_	_		+	N/A N/A	N/A N/A	N/A N/A
		N/A N/A	Plaster Ceiling Cement Floor			400 400	SF	0	+			+	N/A N/A	N/A N/A	N/A N/A
1 B	Stairwell outside Girl's Restroom Stairwell outside Girl's Restroom	N/A	Brick Wall		Non Suspect ACM Non Suspect ACM	1200	SF	0	+			+	N/A	N/A	N/A
1 B	Stairwell outside Girl's Restroom	N/A	Plaster Ceiling		NAD	400	SF	0	_			+	N/A	N/A	N/A
	Center Hallway outside Classroom 004	N/A	Cement Floor		Non Suspect ACM	300	SF	0	1				N/A	N/A	N/A
1 B	Center Hallway outside Classroom 004	N/A	Brick Wall		Non Suspect ACM	900	SF	0				1	N/A	N/A	N/A
	Center Hallway outside Classroom 004	N/A	Plaster Ceiling		NAD	300	SF	0					N/A	N/A	N/A
	Center Hallway outside Classroom 004	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	150	LF	0					N/A	N/A	N/A
											Associated with Fiberglass Insulated Domestic Water			1 .	
1 B	Center Hallway outside Classroom 004	T	Pipe Fitting Insulation	6350/01/0B/04	Confirmed	32	EA	0	_	-	Lines		1 1	Yes	1/D
1 B	Classroom 004	M	Floor Tile VAT 12" x 12"	6350/01/0B/NN	Assumed	1200	SF	0	+	Brown		+	1 N/A	Yes	1/D
	Classroom 004 Classroom 004	N/A N/A	Brick Wall	<del> </del>	Non Suspect ACM NAD	3600 1200	SF SF	0	+			+	N/A N/A	N/A N/A	N/A N/A
	Classroom 004 Classroom 004	N/A N/A	Ceiling Tile 1' x 1' Fiberglass Pipe Insulation		Non Suspect ACM	32	LF	0	+			+	N/A N/A	N/A N/A	N/A N/A
1 R	Classroom 004 Classroom 004	M M	Blackboard Glue Dots	6350/01/0B/SYN/BB/2600	Assumed	50	SF	0	+				1	Yes	1/D
	Classroom 004	M	Sink Undercoat Mastic	6350/01/0B/SYN/BB/2602	Assumed	8	SF	0				+	1	Yes	1/D
1 B		N/A	Ceramic Tile Floors		Non Suspect ACM	50	SF	0					N/A	N/A	N/A
	Classroom 004 Restroom	N/A	Ceramic Tile Walls		Non Suspect ACM	150	SF	0					N/A	N/A	N/A
1 B	Classroom 004 Restroom	N/A	Ceiling Tile 2' x 4'		Non Suspect ACM	50	SF	0					N/A	N/A	N/A
1 B	Classroom 004 Restroom	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	18	LF	0					N/A	N/A	N/A
1 B	Boiler Room	N/A	Cement Floor		Non Suspect ACM	1400	SF	0	_				N/A	N/A	N/A
	Boiler Room	N/A	Brick Wall		Non Suspect ACM	4200	SF	0	+-			+	N/A	N/A	N/A
1 B	Boiler Room	N/A	Concrete Ceiling		Non Suspect ACM	1400	SF	0	+-	_	<u> </u>	+	N/A	N/A	N/A
1 B	Boiler Room	N/A	Fiberglass Pipe Insulation	COEC/04/0D/CVAL/DD/4000	Non Suspect ACM	300	LF	0	+		Circa 2012	+	N/A 1	N/A Yes	1/D
	Boiler Room Fan Room	N/A	Sectional Boilers Cement Floor	6350/01/0B/SYN/BB/1620	Assumed Non Suspect ACM	1400	EA SF	0	+	+	O110a 2012	+	N/A	N/A	N/A
	Fan Room	N/A N/A	Brick Wall		Non Suspect ACM Non Suspect ACM	4200	SF	0	+			+	N/A N/A	N/A N/A	N/A N/A
1 B	Fan Room	N/A	Concrete Ceiling		Non Suspect ACM	1400	SF	0	+				N/A	N/A	N/A
	Fan Room	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	300	LF	0	_			1	N/A	N/A	N/A
1 B	Fan Room	M	Transite Electrical Panel	6350/01/0B/JJ	Confirmed	100	SF	0					1	Yes	1/D
1 B	Old Ash Room/Storage Room	N/A	Cement Floor		Non Suspect ACM	1400	SF	0					N/A	N/A	N/A
1 B	Old Ash Room/Storage Room	N/A	Brick Wall		Non Suspect ACM	4200	SF	0					N/A	N/A	N/A
1 B	Old Ash Room/Storage Room	N/A	Concrete Ceiling		Non Suspect ACM	1400	SF	0					N/A	N/A	N/A
1 B	Old Ash Room/Storage Room	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	200	LF	0	_				N/A	N/A	N/A
	Old Coal Storage Room/Storage Room	N/A	Cement Floor		Non Suspect ACM	2000	SF	0	_				N/A	N/A	N/A
1 B	Old Coal Storage Room/Storage Room	N/A	Brick Wall		Non Suspect ACM	6000	SF	0	_			+	N/A	N/A	N/A
1 B	Old Coal Storage Room/Storage Room Old Coal Storage Room/Storage Room	N/A	Concrete Ceiling	1	Non Suspect ACM	2000	SF	0	+-	+		+	N/A	N/A	N/A
	II lid Ling Storage Poom/Storage Poom	N/A	Fiberglass Pipe Insulation	1	Non Suspect ACM	250	LF	0	1		1	1	N/A	N/A	N/A

	School District of Philadelphia		A	HERA Three-Year Re	inspection 2015-2016						Reinspection Date: 12/1/2015			-	
	Samuel Pennypacker Elementary School			Room by Room Lo	cation Log Report						Building Inspector: Bernard J Bryson	1			
	1858 E Washington Lane, Philadelphia, PA 19138	'									Number: ACC-0125-6-031				
												1			
	ULCS# 6350										Management Planner: Megan Vala				
	Year Built: 1930										Number: 740728				
E															
, i	:													ĺ	
e F m I e o n o												Attic/ Crawl	<b></b>	No.	
e 0		System			Confirmed/Assumed/NAD	Amount of	SFLF	Amount of	f SF LF	Color		Space	Damage Potential	Newly Friable	Response
n o	On-Site Room Name	Affected	Material Description	HID#	Non Suspect ACM	Material		Damage		required for VAT	Comments/Description/Notes	Ranking	(DP)	(NF)	Action (RA)
1 F	Hallway outside of Boiler Room, Fan Room, Old Ash Room and Old Coal Storage	N/A	Cement Floor		Non Suspect ACM	250	SF	0					N/A	N/A	N/A
	Hallway outside of Boiler Room, Fan Room, Old Ash Room and Old Coal Storage	N/A	Brick Wall		Non Suspect ACM	750	SF	0					N/A	N/A	N/A
1 E	Hallway outside of Boiler Room, Fan Room, Old Ash Room and Old Coal Storage	N/A	Concrete Ceiling		Non Suspect ACM	250	SF	0					N/A	N/A	N/A
1 B	Gym/Cafeteria	M	Floor Tile VAT 12" x 12"	6350/01/0B/NN	Assumed	1500	SF	0		White			1	Yes	1/D
1 P	Gym/Cafeteria	M	Floor Tile VAT 12" x 12"	6350/01/0B/NN	Assumed	1500	SF	0		Blue			1	Yes	1/D
1 P	3 Gym/Cafeteria	N/A	Brick Wall		Non Suspect ACM	9000	SF	0	_				N/A	N/A	N/A
1 8	Gym/Cafeteria	N/A	Plaster Ceiling		NAD	3000	SF	0	+	-			N/A	N/A	N/A
-1-8	3 Gym/Cafeteria	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	400	LF	0	+		Associated with Fiberglass Insulated Domestic Water		N/A	N/A	N/A
1 F	B Gym/Cafeteria	т	Pipe Fitting Insulation	6350/01/0B/04	Confirmed	25	FA	0			Lines		1	Yes	1/D
1 F	B Gym/Cafeteria	T	Pipe Fitting Insulation	6350/01/0B/04	Confirmed	2	EA	0			Applied to Roof Drain Lines		1	Yes	1/D
1 F	Gym/Cafeteria	T	Pipe Insulation > 6 inch	6350/01/0B/02	Confirmed	20	LF	0			Air-Cell Applied to Roof Drain Lines		1	Yes	1/D
1 B	Kitchen inside Gym/Cafeteria	М	Floor Tile VAT 12" x 12"	6350/01/0B/NN	Assumed	75	SF	0		White			1	Yes	1/D
1 F	Kitchen inside Gym/Cafeteria	М	Floor Tile VAT 12" x 12"	6350/01/0B/NN	Assumed	75	SF	0		Blue			1	Yes	1/D
	Kitchen inside Gym/Cafeteria	N/A	Brick Wall		Non Suspect ACM	450	SF	0	-	1		-	N/A	N/A	N/A
1 H.P	Kitchen inside Gym/Cafeteria	N/A	Plaster Ceiling	<del>                                     </del>	NAD Non Support ACM	150	SF	0	+	+			N/A	N/A	N/A
	Kitchen inside Gym/Cafeteria	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	15	LF	0	+		Associated with Fiberglass Insulated Domestic Water		N/A	N/A	N/A
1 B	B Kitchen inside Gym/Cafeteria	т	Pipe Fitting Insulation	6350/01/0B/04	Confirmed	4	EA	0			Lines		1	Yes	1/D
	3 Gym Storage Room	M	Floor Tile VAT 12" x 12"	6350/01/0B/NN	Assumed	75	SF	0	1	White			1	Yes	1/D
1 F	Gym Storage Room	M	Floor Tile VAT 12" x 12"	6350/01/0B/NN	Assumed	75	SF	0		Blue			1	Yes	1/D
1 B	Gym Storage Room	N/A	Brick Wall		Non Suspect ACM	450	SF	0					N/A	N/A	N/A
1 B	Gym Storage Room	N/A	Plaster Ceiling		NAD	150	SF	0					N/A	N/A	N/A
_1 P	Gym Storage Room	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	4	LF	0	-				N/A	N/A	N/A
4 6	0 0 0t P	-	Dina Cittina Insulation	6350/01/0B/04	Confirmed		EA	0			Associated with Fiberglass Insulated Domestic Water Lines			Yes	1/D
1 6	B Gym Storage Room B Gym Vestibule to School Yard	N/A	Pipe Fitting Insulation Cement Floor	6350/01/0B/04	Non Suspect ACM	150	SF	0	+		Lines		N/A	N/A	N/A
1 F	Gym Vestibule to School Yard	N/A	Brick Wall		Non Suspect ACM	450	SF	0	+				N/A	N/A	N/A
1 E	B Gym Vestibule to School Yard	N/A	Concrete Ceiling		Non Suspect ACM	150	SF	0					N/A	N/A	N/A
1 F	Hallway from Boy's Restroom to Classroom 008	N/A	Cement Floor		Non Suspect ACM	1000	SF	0					N/A	N/A	N/A
1 B	Hallway from Boy's Restroom to Classroom 008	N/A	Brick Wall		Non Suspect ACM	3000	SF	0					N/A	N/A	N/A
1 F	Hallway from Boy's Restroom to Classroom 008	N/A	Plaster Ceiling		NAD	1000	SF	0					N/A	N/A	N/A
	Hallway from Boy's Restroom to Classroom 008	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	100	LF	0					N/A	N/A	N/A
_1_P	Hallway from Boy's Restroom to Classroom 008	М	Blackboard Glue Dots	6350/01/0B/SYN/BB/2600	Assumed	20	SF	0					1	Yes	1/D
1 B	Hallway from Boy's Restroom to Classroom 008	т .	Pipe Fitting Insulation	6350/01/0B/04	Confirmed	10	EA	_			Associated with Fiberglass Insulated Domestic Water Lines		4	Yes	1/D
	Boy's Restroom next to Classroom 009	N/A	Ceramic Tile Floors	0330/01/0B/04	Non Suspect ACM	500	SF	0	+-		Lines		N/A	N/A	N/A
	Boy's Restroom next to Classroom 009	N/A	Ceramic Tile Walls		Non Suspect ACM	1500	SF	0					N/A	N/A	N/A
1 F	Boy's Restroom next to Classroom 009	N/A	Concrete Ceiling		Non Suspect ACM	500	SF	0					N/A	N/A	N/A
1 B	Boy's Restroom next to Classroom 009	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	80	LF	0					N/A	N/A	N/A
1 P	B Stairwell outside Boy's Restroom	N/A	Cement Floor		Non Suspect ACM	400	SF	0					N/A	N/A	N/A
	Stairwell outside Boy's Restroom	N/A	Brick Wall		Non Suspect ACM	1200	SF	0					N/A	N/A	N/A
1 P	Stairwell outside Boy's Restroom	N/A	Plaster Ceiling		NAD	400	SF	0					N/A	N/A	N/A
1 B	3 Stairwell outside Boy's Restroom	N/A N/A	Fiberglass Pipe Insulation	<del>                                     </del>	Non Suspect ACM	16	LF SF	0	+	+			N/A N/A	N/A N/A	N/A N/A
1 5	B Classroom 009 B Classroom 009	N/A N/A	Wood Floor Plaster Walls		Non Suspect ACM NAD	500 1500	SF	0	+	1			N/A N/A	N/A N/A	N/A N/A
118	Classroom 009	N/A	Ceiling Tile 2' x 4'		Non Suspect ACM	500	SF	0	1				N/A	N/A	N/A
1 F	3 Classroom 009	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	30	LF	0	1				N/A	N/A	N/A
1 F	Classroom 009	М	Blackboard Glue Dots	6350/01/0B/SYN/BB/2600	Assumed	160	SF	0					1	Yes	1/D
1 B	Classroom 009 Restroom	N/A	Ceramic Tile Floors		Non Suspect ACM	40	SF	0					N/A	N/A	N/A
1 F	Classroom 009 Restroom	N/A	Ceramic Tile Walls		Non Suspect ACM	120	SF	0					N/A	N/A	N/A
	Classroom 009 Restroom	N/A	Ceiling Tile 2' x 4'		Non Suspect ACM	40	SF	0					N/A	N/A	N/A
	Classroom 009 Restroom	N/A N/A	Fiberglass Pipe Insulation	<del>                                     </del>	Non Suspect ACM	12 500	LF SF	0	+	-		-	N/A N/A	N/A N/A	N/A N/A
1 5	3 Classroom 010 3 Classroom 010	N/A N/A	Wood Floor Plaster Walls		Non Suspect ACM NAD	1500	SF	0	+	+			N/A N/A	N/A N/A	N/A N/A
	Classroom 010	N/A	Ceiling Tile 2' x 4'		Non Suspect ACM	500	SF	0	+				N/A	N/A	N/A
	Classroom 010	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	20	LF	0	1				N/A	N/A	N/A
1 F	3 Classroom 010	M	Blackboard Glue Dots	6350/01/0B/SYN/BB/2600	Assumed	60	SF	0					1	Yes	1/D
1 B	Classroom 010	М	Sink Undercoat Mastic	6350/01/0B/SYN/BB/2602	Assumed	8	SF	0					1	Yes	1/D
1 B	Classroom 008	N/A	Carpet		Non Suspect ACM	500	SF	0					N/A	N/A	N/A
1 P	Classroom 008	N/A	Wood Floor		Non Suspect ACM	500	SF	0	_	1			N/A	N/A	N/A
	3 Classroom 008	N/A	Plaster Walls		NAD	1500	SF	0	+	1			N/A	N/A	N/A
1 1 5	3 Classroom 008	N/A N/A	Ceiling Tile 2' x 4'	<del>                                     </del>	Non Suspect ACM	500	SF LF	0	+	-			N/A N/A	N/A N/A	N/A N/A
1 5	3 Classroom 008 3 Classroom 008	N/A M	Fiberglass Pipe Insulation Blackboard Glue Dots	6350/01/0B/SYN/BB/2600	Non Suspect ACM Assumed	42 50	SF	0	+	1			1 1	Yes	1/D
	Classroom 008  Classroom 008 Storage Closet	N/A	Wood Floor	0330/0 I/OB/3 TN/BB/2000	Non Suspect ACM	120	SF	0	+	t		<del>                                     </del>	N/A	N/A	N/A
	Classroom 008 Storage Closet	N/A	Plaster Walls		NAD	360	SF	0	1	1			N/A	N/A	N/A
4 1 -	B Classroom 008 Storage Closet	N/A	Plaster Ceiling		NAD	120	SF	0					N/A	N/A	N/A
1 1 5	Stairwell outside Classroom 008	N/A	Cement Floor		Non Suspect ACM	400	SF	0					N/A	N/A	N/A
		N/A	Plaster Walls		NAD	1200	SF	0					N/A	N/A	N/A
1 B	Stairwell outside Classroom 008														
1 B 1 B	Stairwell outside Classroom 008	N/A	Plaster Ceiling		NAD	400	SF	0					N/A	N/A	N/A
1 B 1 B 1 B				6350/01/01/MM						Green			N/A 1 N/A	N/A Yes N/A	N/A 1/D N/A

	Only at District of Dhiladalahia														
	School District of Philadelphia		Al		inspection 2015-2016						Reinspection Date: 12/1/2015				
	Samuel Pennypacker Elementary School			Room by Room Lo	cation Log Report			]			Building Inspector: Bernard J Bryson				
	1858 E Washington Lane, Philadelphia, PA 19138										Number: ACC-0125-6-031				
	ULCS# 6350										Management Planner: Megan Vala	Ī			
E	Year Built: 1930			1			_		_		Number: 740728				
7															
e F												Attic/			
m I e o										Color		Crawl	Damage	Newly	
n o		System			Confirmed/Assumed/NAD	Amount of	SFLF	Amount of		required		Space	Potential	Friable	Response
t r	On-Site Room Name	Affected	Material Description	HID#	Non Suspect ACM	Material	EA	Damage	EA	for VAT	Comments/Description/Notes	Ranking	(DP)	(NF)	Action (RA)
1 1	Classroom 101	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	24	LF	0	-				N/A 1	N/A	N/A
1 1	Classroom 101	M M	Blackboard Glue Dots	6350/01/01/SYN/BB/2600 6350/01/01/SYN/BB/2602	Assumed	100	SF SF	0	-				1	Yes Yes	1/D 1/D
1 1	Classroom 101 Classroom 101 Boy's Restroom	N/A	Sink Undercoat Mastic Ceramic Tile Floors	6350/01/01/SYN/BB/2602	Assumed Non Suspect ACM	20	SF	0	-		-		N/A	N/A	N/A
	Classroom 101 Boy's Restroom	N/A	Ceramic Tile Ploors  Ceramic Tile Walls		Non Suspect ACM	60	SF	0	_				N/A	N/A	N/A
1 1	Classroom 101 Boy's Restroom	N/A	Plaster Ceiling		NAD	20	SF	0					N/A	N/A	N/A
1 1	Classroom 101 Boy's Restroom	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	40	LF	0					N/A	N/A	N/A
1 1	Classroom 101 Girl's Restroom	N/A	Ceramic Tile Floors		Non Suspect ACM	20	SF	0					N/A	N/A	N/A
1 1	Classroom 101 Girl's Restroom	N/A	Ceramic Tile Walls		Non Suspect ACM	60	SF	0					N/A	N/A	N/A
1 1	Classroom 101 Girl's Restroom	N/A	Plaster Ceiling		NAD	20	SF	0	1	<u> </u>			N/A	N/A	N/A
	Classroom 101 Storage Closet	M	Floor Tile VAT 12" x 12"	6350/01/01/MM	Assumed	120	SF	0	-	Green	1	-	1	Yes	1/D
1 1	Classroom 101 Storage Closet	N/A N/A	Plaster Walls		NAD Non Support ACM	360 120	SF SF	0	+	-	-	-	N/A N/A	N/A N/A	N/A N/A
1 1	Classroom 101 Storage Closet Women's Restroom next to Classroom 101	N/A N/A	Ceiling Tile 2' x 4' Ceramic Tile Floors		Non Suspect ACM Non Suspect ACM	120 150	SF	0	+		<u> </u>		N/A N/A	N/A N/A	N/A N/A
	Women's Restroom next to Classroom 101  Women's Restroom next to Classroom 101	N/A	Ceramic Tile Walls		Non Suspect ACM	450	SF	0	_		1		N/A	N/A	N/A
1 1	Women's Restroom next to Classroom 101	N/A	Ceiling Tile 2' x 4'		Non Suspect ACM	150	SF	0	1				N/A	N/A	N/A
1 1	Stairwell outside Classroom 101	N/A	Cement Floor		Non Suspect ACM	200	SF	0					N/A	N/A	N/A
1 1	Stairwell outside Classroom 101	N/A	Brick Wall		Non Suspect ACM	600	SF	0					N/A	N/A	N/A
1 1	Stairwell outside Classroom 101	N/A	Ceiling Tile 2' x 4'		Non Suspect ACM	200	SF	0					N/A	N/A	N/A
	Classroom 102	N/A	Wood Floor		Non Suspect ACM	900	SF	0	1				N/A	N/A	N/A
	Classroom 102 Classroom 102	N/A N/A	Plaster Walls		NAD Non Suspect ACM	2700 900	SF SF	0					N/A N/A	N/A N/A	N/A N/A
	Classroom 102 Classroom 102	N/A N/A	Ceiling Tile 2' x 4' Fiberglass Pipe Insulation		Non Suspect ACM Non Suspect ACM	16	LF	0	-				N/A N/A	N/A N/A	N/A N/A
1 1	Classroom 102	M	Blackboard Glue Dots	6350/01/01/SYN/BB/2600	Assumed	160	SF	0					1	Yes	1/D
1 1 1	Classroom 103	N/A	Wood Floor	000000000000000000000000000000000000000	Non Suspect ACM	900	SF	0					N/A	N/A	N/A
1 1	Classroom 103	N/A	Plaster Walls		NAD	2700	SF	0					N/A	N/A	N/A
1 1	Classroom 103	N/A	Ceiling Tile 2' x 4'		Non Suspect ACM	900	SF	0					N/A	N/A	N/A
1 1	Classroom 103	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	24	LF	0					N/A	N/A	N/A
1 1	Classroom 103	М	Blackboard Glue Dots	6350/01/01/SYN/BB/2600	Assumed	160	SF	0					1	Yes	1/D
1 1	Classroom 103 Restroom	N/A	Ceramic Tile Floors		Non Suspect ACM	40	SF	0	-				N/A	N/A	N/A
1 1	Classroom 103 Restroom Classroom 103 Restroom	N/A N/A	Ceramic Tile Walls Plaster Ceiling		Non Suspect ACM NAD	120 40	SF SF	0	-		-		N/A N/A	N/A N/A	N/A N/A
1 1	Classroom 103 Restroom	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	15	LF	0					N/A	N/A	N/A
1 1	Hallway from Classrooms 101 to 103	N/A	Cement Floor		Non Suspect ACM	1000	SF	0					N/A	N/A	N/A
	Hallway from Classrooms 101 to 103	N/A	Plaster Walls		NAD	3000	SF	0					N/A	N/A	N/A
	Hallway from Classrooms 101 to 103	N/A	Ceiling Tile 2' x 4'		Non Suspect ACM	1000	SF	0					N/A	N/A	N/A
	Stairwell outside Classroom 103	N/A	Cement Floor		Non Suspect ACM	400	SF	0					N/A	N/A	N/A
	Stairwell outside Classroom 103	N/A	Plaster Walls		NAD	1200	SF	0	-				N/A	N/A	N/A
1 1	Stairwell outside Classroom 103	N/A	Plaster Ceiling		NAD	400	SF	0			Basement - 1st Floor Landing - 16 SF; 1st - 2nd Floor		N/A	N/A	N/A
1 1	Stairwell outside Classroom 103	Т Т	Radiator Insulation	6350/01/01/DD	Confirmed	48	SF	0			Landing - 32 SF		1 1	Yes	1/D
1 1	Girl's Restroom next to Classroom 104	N/A	Ceramic Tile Floors		Non Suspect ACM	200	SF	0					N/A	N/A	N/A
1 1	Girl's Restroom next to Classroom 104	N/A	Ceramic Tile Walls		Non Suspect ACM	600	SF	0					N/A	N/A	N/A
1 1	Girl's Restroom next to Classroom 104	N/A	Plaster Ceiling		NAD	200	SF	0					N/A	N/A	N/A
1 1	Girl's Restroom next to Classroom 104	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	15	LF	0	-		1		N/A	N/A	N/A
1 1	Classroom 104	N/A	Wood Floor		Non Suspect ACM	900	SF	0	-	-			N/A	N/A	N/A
	Classroom 104 Classroom 104	N/A N/A	Plaster Walls Ceiling Tile 2' x 4'		NAD Non Suspect ACM	2700 900	SF SF	0	+		-		N/A N/A	N/A N/A	N/A N/A
1 1	Classroom 104 Classroom 104	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	24	LF	0	_			<del>                                     </del>	N/A	N/A	N/A
1 1	Classroom 104	M	Blackboard Glue Dots	6350/01/01/SYN/BB/2600	Assumed	160	SF	0	1				1	Yes	1/D
1 1	Main Office	М	Floor Tile VAT 12" x 12"	6350/01/01/MM	Assumed	175	SF	0		White			1	Yes	1/D
1 1	Main Office	М	Floor Tile VAT 12" x 12"	6350/01/01/MM	Assumed	175	SF	0		Blue			1	Yes	1/D
1 1	Main Office	N/A	Plaster Walls		NAD	1050	SF	0					N/A	N/A	N/A
	Main Office	N/A	Ceiling Tile 2' x 4'		Non Suspect ACM	350	SF	0	_	_			N/A	N/A	N/A
1 1	Main Office	N/A M	Fiberglass Pipe Insulation	00501041041030310051005	Non Suspect ACM	12	LF	0	+	-	<del> </del>		N/A 1	N/A	N/A 1/D
1 1	Main Office Main Office Storage Closet	M M	Blackboard Glue Dots Floor Tile VAT 12" x 12"	6350/01/01/SYN/BB/2600 6350/01/01/MM	Assumed Assumed	20 100	SF SF	0	+	White	+		1	Yes Yes	1/D 1/D
	Main Office Storage Closet  Main Office Storage Closet	M	Floor Tile VAT 12 x 12"	6350/01/01/MM	Assumed	100	SF	0	_	Blue	1		1	Yes	1/D
1 1	Main Office Storage Closet	N/A	Plaster Walls		NAD	600	SF	0					N/A	N/A	N/A
1 1	Main Office Storage Closet	N/A	Plaster Ceiling		NAD	200	SF	0					N/A	N/A	N/A
1 1	Main Office Storage Closet	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	80	LF	0					N/A	N/A	N/A
			D: 5'''	005010		_	<u>-</u> .	_			Associated with Fiberglass Insulated Domestic Water				4.5
1 1	Main Office Storage Closet	T M	Pipe Fitting Insulation	6350/01/01/07 6350/01/01/MM	Confirmed	220	EA	0	+	Brown	Lines		1	Yes	1/D 1/D
1 1	Principal's Office Principal's Office	N/A	Floor Tile VAT 12" x 12" Plaster Walls	6350/01/01/MM	Assumed NAD	660	SF SF	0	+	Brown	<del> </del>		N/A	Yes N/A	N/A
1 1	Principal's Office	N/A	Ceiling Tile 2' x 4'		Non Suspect ACM	220	SF	0	1				N/A	N/A	N/A
1 1	Principal's Office	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	24	LF	0					N/A	N/A	N/A
1 1	Principal's Office Storage Closet	М	Linoleum	6350/01/01/II	Assumed	32	SF	0		Brown			1	Yes	1/D
1 1	Principal's Office Storage Closet	N/A	Plaster Walls		NAD	100	SF	0					N/A	N/A	N/A
1 1	Principal's Office Storage Closet	N/A	Plaster Ceiling		NAD	32	SF	0	1	-			N/A	N/A	N/A
1 1	Principal's Office Storage Closet	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	10	LF	0	+	-	<u> </u>		N/A	N/A	N/A
1 1	Classroom 105 Classroom 105	N/A N/A	Wood Floor Plaster Walls		Non Suspect ACM NAD	900 2700	SF SF	0	+		<del> </del>		N/A N/A	N/A N/A	N/A N/A
	Oldobiooni 100	I IWA	FIASICI VVAIIS		INAU	2700	I OF				I .	1	1877	14//	1977


	School District of Philadelphia			UEDA Three Veer De	inguistics 2015 2016										
			A		inspection 2015-2016						Reinspection Date: 12/1/2015	-			
	Samuel Pennypacker Elementary School			Room by Room Lo	cation Log Report			]			Building Inspector: Bernard J Bryson	-			
	1858 E Washington Lane, Philadelphia, PA 19138										Number: ACC-0125-6-031				
	ULCS# 6350										Management Planner: Megan Vala				
	Year Built: 1930										Number: 740728				
E	Tear Bunt. 1900										Number: 740720				
_															
e F m I												Attic/			
e 0										Color		Crawl	Damage	Newly	_
n o	On-Site Room Name	System Affected	Material Description	HID#	Confirmed/Assumed/NAD	Amount of Material	SF LF EA	Amount o	f SF LF EA	required for VAT	Comments/Description/Notes	Space Ranking	Potential (DP)	Friable (NF)	Response Action (RA)
	Classroom 105	N/A	Ceiling Tile 2' x 4'	HID#	Non Suspect ACM Non Suspect ACM	900	SF	Damage 0	EA	TOF VAI	Comments/Description/Notes	Kanking	N/A	N/A	N/A
1 1		N/A	Fiberglass Pipe Insulation		Non Suspect ACM	12	LF	0					N/A	N/A	N/A
1 1	Classroom 105	М	Blackboard Glue Dots	6350/01/01/SYN/BB/2600	Assumed	220	SF	0					1	Yes	1/D
1 1	Stairs from Center Hallway to Auditorium across from Classroom 105	N/A	Cement Floor		Non Suspect ACM	200	SF	0					N/A	N/A	N/A
	Stairs from Center Hallway to Auditorium across from Classroom 105	N/A	Cernent Floor		Non Suspect ACM	200		- 0		_			IN/A	IN/A	IN/A
1 1		N/A	Plaster Walls		NAD	600	SF	0					N/A	N/A	N/A
1 1	Stairs from Center Hallway to Auditorium across from Classroom 105	N/A	Plaster Ceiling		NAD	200	SF	0					N/A	N/A	N/A
	Auditorium	N/A	Wood Floor		Non Suspect ACM	3500	SF	0					N/A	N/A	N/A
	Auditorium	N/A	Plaster Walls		NAD	10500	SF	0					N/A	N/A	N/A
	Auditorium	N/A	Plaster Ceiling		NAD	3500	SF	0					N/A	N/A	N/A
1 1	Auditorium	_	Dedictor: 1.0	0050012122	05		SF	0			Sides - 4 at 32 SF Each; Front - 5 at 10 SF Each; Rear - 6 at 10 SF Each			Yes	1/D
	Auditorium Auditorium Stage	N/A	Radiator Insulation Wood Floor	6350/01/01/DD	Confirmed Non Suspect ACM	238 1000	SF	0	1	+	- U at 10 OF EdGII		N/A	Yes N/A	N/A
	Auditorium Stage	N/A	Plaster Walls		NOTI SUSPECI ACMI	3000	SF	0	+	+			N/A	N/A	N/A
	Auditorium Stage	N/A	Plaster Ceiling		NAD	1000	SF	0	1	1			N/A	N/A	N/A
1 1	Auditorium Stage Restroom - Left	N/A	Ceramic Tile Floors		Non Suspect ACM	100	SF	0					N/A	N/A	N/A
1 1	Auditorium Stage Restroom - Left	N/A	Ceramic Tile Walls		Non Suspect ACM	300	SF	0					N/A	N/A	N/A
1 1	Auditorium Stage Restroom - Left	N/A	Ceiling Tile 2' x 4'	+	Non Suspect ACM	100	SF	0	+	+	1		N/A	N/A	N/A
	Auditorium Stage Restroom - Right Auditorium Stage Restroom - Right	N/A N/A	Ceramic Tile Floors Ceramic Tile Walls		Non Suspect ACM	100 300	SF SF	0	+	_	<del> </del>		N/A N/A	N/A N/A	N/A N/A
1 1	Auditorium Stage Restroom - Right	N/A	Ceiling Tile 2' x 4'		Non Suspect ACM Non Suspect ACM	100	SF	0					N/A	N/A	N/A
	Stairs from Center Hallway to Auditorium across from Classroom 106		<b>y</b>												
1 1		N/A	Cement Floor		Non Suspect ACM	200	SF	0	_	_			N/A	N/A	N/A
1 1	Stairs from Center Hallway to Auditorium across from Classroom 106	N/A	Plaster Walls		NAD	600	SF	0					N/A	N/A	N/A
	Stairs from Center Hallway to Auditorium across from Classroom 106														
1 1		N/A	Plaster Ceiling		NAD	200	SF	0					N/A	N/A	N/A
1 1	Stairs from Center Hallway to Auditorium across from Classroom 106	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	6	LF	0					N/A	N/A	N/A
1 1	Classroom 106	N/A	Wood Floor		Non Suspect ACM	900	SF	0					N/A	N/A	N/A
	Classroom 106	N/A	Plaster Walls		NAD	2700	SF	0					N/A	N/A	N/A
	Classroom 106	N/A	Ceiling Tile 2' x 4'		Non Suspect ACM	900	SF	0					N/A	N/A	N/A
	Classroom 106	N/A M	Fiberglass Pipe Insulation	6350/01/01/SYN/BB/2600	Non Suspect ACM	12	LF	0	_	_			N/A 1	N/A	N/A 1/D
	Classroom 106 Storage Room across from Classroom 106	N/A	Blackboard Glue Dots Cement Floor	6350/01/01/STN/BB/2600	Assumed Non Suspect ACM	220 200	SF SF	0					N/A	Yes N/A	N/A
1 1	Storage Room across from Classroom 106	N/A	Plaster Walls		NAD	600	SF	0					N/A	N/A	N/A
1 1	Storage Room across from Classroom 106	N/A	Plaster Ceiling		NAD	200	SF	0					N/A	N/A	N/A
1 1	Classroom 107	N/A	Wood Floor		Non Suspect ACM	900	SF	0					N/A	N/A	N/A
1 1	Classroom 107	N/A	Plaster Walls		NAD	2700	SF	0	_				N/A	N/A	N/A
	Classroom 107	N/A	Ceiling Tile 2' x 4'		Non Suspect ACM	900	SF LF	0	_	+			N/A N/A	N/A N/A	N/A N/A
1 1	Classroom 107 Classroom 107	N/A M	Fiberglass Pipe Insulation Blackboard Glue Dots	6350/01/01/SYN/BB/2600	Non Suspect ACM Assumed	22 220	SF	0	_				1	Yes	1/D
	Fire Tower across from Classroom 107			000000000000000000000000000000000000000											
1 1	5: 7 ( 0) (0)	N/A	Cement Floor		Non Suspect ACM	400	SF	0	_	_			N/A	N/A	N/A
1 1	Fire Tower across from Classroom 107	N/A	Brick Wall		Non Suspect ACM	1200	SF	0					N/A	N/A	N/A
	Fire Tower across from Classroom 107								1						
1 1	Control lathers from Books to Cirilla Books and	N/A N/A	Concrete Ceiling		Non Suspect ACM	400	SF	0	1	+	<del> </del>		N/A N/A	N/A N/A	N/A N/A
1 1	Center Hallway from Boy's to Girl's Restrooms  Center Hallway from Boy's to Girl's Restrooms	N/A N/A	Cement Floor Plaster Walls		Non Suspect ACM NAD	1500 4500	SF SF	0	1	+	1		N/A N/A	N/A N/A	N/A N/A
	Center Hallway from Boy's to Girl's Restrooms	N/A	Plaster Ceiling		NAD	1500	SF	0	+				N/A	N/A	N/A
1 1	Center Hallway from Boy's to Girl's Restrooms	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	24	LF	0					N/A	N/A	N/A
1 1	Boy's Restroom next to Classroom 107	N/A	Ceramic Tile Floors		Non Suspect ACM	200	SF	0					N/A	N/A	N/A
1 1	Boy's Restroom next to Classroom 107	N/A	Ceramic Tile Walls		Non Suspect ACM	600	SF	0	1	1			N/A	N/A	N/A
	Boy's Restroom next to Classroom 107	N/A	Plaster Ceiling	-	NAD Nas Sussest AGM	200	SF	0	+-	+	<del> </del>		N/A N/A	N/A N/A	N/A N/A
1 1	Boy's Restroom next to Classroom 107 Stairwell outside Classroom 108	N/A N/A	Fiberglass Pipe Insulation Cement Floor	1	Non Suspect ACM Non Suspect ACM	20 400	LF SF	0	+	+	<del> </del>		N/A N/A	N/A N/A	N/A N/A
1 1	Stairwell outside Classroom 108 Stairwell outside Classroom 108	N/A	Plaster Walls		NOTI SUSPECI ACMI	1200	SF	0	1	1	1		N/A	N/A	N/A
	Stairwell outside Classroom 108	N/A	Plaster Ceiling		NAD	400	SF	0	1				N/A	N/A	N/A
								-			Basement - 1st Floor Landing - 16 SF; 1st - 2nd Floor		1		
	Stairwell outside Classroom 108	T	Radiator Insulation	6350/01/01/DD	Confirmed	48	SF	0	_	-	Landing - 32 SF		1 N/A	Yes	1/D
1 1	Classroom 108 Classroom 108	N/A N/A	Wood Floor Plaster Walls	+	Non Suspect ACM NAD	900 2700	SF SF	0	+	+	+		N/A N/A	N/A N/A	N/A N/A
1 1	Classroom 108	N/A N/A	Ceiling Tile 2' x 4'	+	Non Suspect ACM	900	SF	0	+	_	1		N/A	N/A	N/A
1 1		N/A	Fiberglass Pipe Insulation		Non Suspect ACM	24	LF	0					N/A	N/A	N/A
1 1 1 1	Classroom 108			6350/01/01/SYN/BB/2600	Assumed	220	SF	0					1	Yes	1/D
1 1	Classroom 108 Classroom 108	M	Blackboard Glue Dots				SF	0		1		1	N/A	N/A	N/A
1 1	Classroom 108 Classroom 108 Classroom 109	M N/A	Wood Floor	000000000000000000000000000000000000000	Non Suspect ACM	900			+	_					
1 1 1 1 1 1	Classroom 108  Classroom 108  Classroom 109  Classroom 109	M N/A N/A	Wood Floor Plaster Walls	000000110110110110110101000	NAD	2700	SF	0					N/A	N/A	N/A
1 1 1 1 1 1 1 1	Classroom 108 Classroom 109 Classroom 109 Classroom 109 Classroom 109	M N/A N/A N/A	Wood Floor Plaster Walls Ceiling Tile 2' x 4'	000000000000000000000000000000000000000	NAD Non Suspect ACM	2700 900	SF SF	0					N/A N/A	N/A N/A	N/A N/A
1 1 1 1 1 1 1 1 1 1	Classroom 108 Classroom 109 Classroom 109 Classroom 109 Classroom 109 Classroom 109 Classroom 109	M N/A N/A N/A N/A	Wood Floor Plaster Walls Ceiling Tile 2' x 4' Fiberglass Pipe Insulation		NAD Non Suspect ACM Non Suspect ACM	2700 900 12	SF SF LF	0					N/A	N/A N/A N/A	N/A N/A N/A
1 1 1 1 1 1 1 1 1 1 1 1	Classroom 108 Classroom 109	M N/A N/A N/A	Wood Floor Plaster Walls Ceiling Tile 2' x 4'	6350/01/01/SYN/BB/2600	NAD Non Suspect ACM Non Suspect ACM Assumed	2700 900 12 220	SF SF	0 0					N/A N/A	N/A N/A	N/A N/A
1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	Classroom 108 Classroom 109 Classroom 109 Classroom 109 Classroom 109 Classroom 109 Classroom 109	M N/A N/A N/A N/A M	Wood Floor Plaster Walls Ceiling Tile 2' x 4' Fiberglass Pipe Insulation Blackboard Glue Dots		NAD Non Suspect ACM Non Suspect ACM	2700 900 12	SF SF LF SF	0 0 0 0					N/A N/A N/A	N/A N/A N/A Yes	N/A N/A N/A 1/D

School District of Philadelphia			HEDA Three-Vear De	inspection 2015-2016						Reinspection Date: 12/1/2015				
Samuel Pennypacker Elementary School		_	Room by Room Lo		•					Building Inspector: Bernard J Bryson	_			
			ROUIII DY ROUIII LO	Cation Log Report			1				_			
1858 E Washington Lane, Philadelphia, PA 19138										Number: ACC-0125-6-031				
ULCS# 6350										Management Planner: Megan Vala				
Year Built: 1930										Number: 740728				
E														
'e   F											****-1			
e F m I									Color		Attic/ Crawl	Damage	Newly	
e   o   n   o	System			Confirmed/Assumed/NAD	Amount of	SFLF	Amount o		F required		Space	Potential	Friable	Response
t r On-Site Room Name	Affected	Material Description	HID#	Non Suspect ACM	Material	EA	Damage	EA	for VAT	Comments/Description/Notes	Ranking	(DP)	(NF)	Action (RA
1 1 Classroom 110	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	30	LF	0					N/A 1	N/A	N/A
1 1 Classroom 110 1 1 Classroom 110	M M	Blackboard Glue Dots Sink Undercoat Mastic	6350/01/01/SYN/BB/2600 6350/01/01/SYN/BB/2602	Assumed Assumed	140	SF SF	0	_				1	Yes Yes	1/D 1/D
1 1 Stairwell outside Classroom 110	N/A	Cement Floor	0330/01/01/31N/BB/2002	Non Suspect ACM	200	SF	0	_				N/A	N/A	N/A
1 1 Stairwell outside Classroom 110	N/A	Brick Wall		Non Suspect ACM	600	SF	0					N/A	N/A	N/A
1 1 Stairwell outside Classroom 110	N/A	Ceiling Tile 2' x 4'		Non Suspect ACM	200	SF	0					N/A	N/A	N/A
1 1 Staff Restroom next to Classroom 110	N/A	Ceramic Tile Floors		Non Suspect ACM	150	SF	0	_				N/A	N/A	N/A
1 1 Staff Restroom next to Classroom 110 1 1 Staff Restroom next to Classroom 110	N/A N/A	Ceramic Tile Walls Ceiling Tile 2' x 4'		Non Suspect ACM	450 150	SF SF	0	_				N/A N/A	N/A N/A	N/A N/A
1 1 Staff Restroom next to Classroom 110	N/A	Fiberglass Pipe Insulation		Non Suspect ACM Non Suspect ACM	36	LF	0	_				N/A	N/A	N/A
1 1 Hallway from Classrooms 108 to 110	N/A	Cement Floor		Non Suspect ACM	1000	SF	0					N/A	N/A	N/A
1 1 Hallway from Classrooms 108 to 110	N/A	Plaster Walls		NAD	3000	SF	0					N/A	N/A	N/A
1 1 Hallway from Classrooms 108 to 110	N/A	Ceiling Tile 2' x 4'		Non Suspect ACM	1000	SF	0	_			-	N/A	N/A	N/A
1 1 Hallway from Classrooms 108 to 110 1 2 Classroom 201	N/A N/A	Fiberglass Pipe Insulation Wood Floor		Non Suspect ACM	12 900	LF SF	0	+	+			N/A N/A	N/A N/A	N/A N/A
1 2 Classroom 201	N/A N/A	Plaster Walls		Non Suspect ACM NAD	2700	SF	0		+			N/A	N/A	N/A
1 2 Classroom 201	N/A	Ceiling Tile 2' x 4'		Non Suspect ACM	900	SF	0					N/A	N/A	N/A
1 2 Classroom 201	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	30	LF	0					N/A	N/A	N/A
1 2 Classroom 201	M	Blackboard Glue Dots	6350/01/02/SYN/BB/2600	Assumed	160	SF	0	_				1	Yes	1/D
1 2 Classroom 201 1 2 Counselor's Office next to Classroom 201	M M	Sink Undercoat Mastic Floor Tile VAT 12" x 12"	6350/01/02/SYN/BB/2602 6350/01/02/BB	Assumed Assumed	140	SF SF	0	+	White		_	1	Yes Yes	1/D 1/D
1 2 Counselor's Office next to Classroom 201	M	Floor Tile VAT 12 x 12"	6350/01/02/BB	Assumed	140	SF	0		Blue			1	Yes	1/D
1 2 Counselor's Office next to Classroom 201	N/A	Plaster Walls	0000/01/02/03	NAD	840	SF	0		Bido			N/A	N/A	N/A
1 2 Counselor's Office next to Classroom 201	N/A	Ceiling Tile 2' x 4'		Non Suspect ACM	280	SF	0					N/A	N/A	N/A
1 2 Counselor's Office next to Classroom 201	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	6	LF	0					N/A	N/A	N/A
1 2 Counselor's Office next to Classroom 201 1 2 Counselor's Office Restroom	M N/A	Blackboard Glue Dots Ceramic Tile Floors	6350/01/02/SYN/BB/2600	Assumed	15 25	SF SF	0	_				1 N/A	Yes N/A	1/D N/A
1 2 Counselor's Office Restroom	N/A N/A	Ceramic Tile Floors  Ceramic Tile Walls		Non Suspect ACM Non Suspect ACM	100	SF	0	_				N/A	N/A	N/A
1 2 Counselor's Office Restroom	N/A	Ceiling Tile 2' x 4'		Non Suspect ACM	25	SF	0					N/A	N/A	N/A
1 2 Teacher's Lounge next to Nurse's Office	M	Floor Tile VAT 12" x 12"	6350/01/02/BB	Assumed	175	SF	0		White			1	Yes	1/D
1 2 Teacher's Lounge next to Nurse's Office	M	Floor Tile VAT 12" x 12"	6350/01/02/BB	Assumed	175	SF	0	_	Blue			1	Yes	1/D
1 2 Teacher's Lounge next to Nurse's Office 1 2 Teacher's Lounge next to Nurse's Office	N/A N/A	Plaster Walls Ceiling Tile 2' x 4'		NAD Non Suspect ACM	1050 350	SF SF	0	_				N/A N/A	N/A N/A	N/A N/A
1 2 Teacher's Lounge next to Nurse's Office	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	6	LF	0					N/A	N/A	N/A
1 2 Teacher's Lounge Restroom next to Nurse's Office	N/A	Ceramic Tile Floors		Non Suspect ACM	25	SF	0					N/A	N/A	N/A
1 2 Teacher's Lounge Restroom next to Nurse's Office	N/A	Ceramic Tile Walls		Non Suspect ACM	100	SF	0					N/A	N/A	N/A
1 2 Teacher's Lounge Restroom next to Nurse's Office	N/A	Ceiling Tile 2' x 4'		Non Suspect ACM	25	SF	0	_				N/A	N/A	N/A
1 2 Teacher's Lounge Restroom next to Nurse's Office 1 2 Nurse's Office	N/A N/A	Fiberglass Pipe Insulation  Ceramic Tile Floors		Non Suspect ACM Non Suspect ACM	175	LF SF	0	+				N/A N/A	N/A N/A	N/A N/A
1 2 Nurse's Office	N/A	Ceramic Tile Walls		Non Suspect ACM	525	SF	0	_				N/A	N/A	N/A
1 2 Nurse's Office	N/A	Ceiling Tile 2' x 4'		Non Suspect ACM	175	SF	0					N/A	N/A	N/A
1 2 Nurse's Exam Room	N/A	Ceramic Tile Floors		Non Suspect ACM	220	SF	0					N/A	N/A	N/A
1 2 Nurse's Exam Room	N/A	Ceramic Tile Walls		Non Suspect ACM	660	SF	0	_			_	N/A	N/A N/A	N/A
1 2 Nurse's Exam Room 1 2 Nurse's Exam Room	N/A N/A	Ceiling Tile 2' x 4' Fiberglass Pipe Insulation		Non Suspect ACM Non Suspect ACM	220 3	SF LF	0	+	+			N/A N/A	N/A N/A	N/A N/A
1 2 Nurse's Office Restroom	N/A	Ceramic Tile Floors		Non Suspect ACM	100	SF	0					N/A	N/A	N/A
1 2 Nurse's Office Restroom	N/A	Ceramic Tile Walls		Non Suspect ACM	300	SF	0					N/A	N/A	N/A
1 2 Nurse's Office Restroom	N/A	Ceiling Tile 2' x 4'		Non Suspect ACM	100	SF	0					N/A	N/A	N/A
1 2 Nurse's Office Storage Closet	N/A	Carpet		Non Suspect ACM	40	SF	0	+	+			N/A N/A	N/A	N/A N/A
1 2 Nurse's Office Storage Closet 1 2 Nurse's Office Storage Closet	N/A N/A	Plaster Walls Ceiling Tile 1' x 1'		NAD NAD	120 40	SF SF	0	+	+			N/A N/A	N/A N/A	N/A N/A
1 2 Classroom 202	N/A	Wood Floor		Non Suspect ACM	900	SF	0					N/A	N/A	N/A
1 2 Classroom 202	N/A	Plaster Walls		NAD	2700	SF	0					N/A	N/A	N/A
1 2 Classroom 202	N/A	Ceiling Tile 2' x 4'		Non Suspect ACM	900	SF	0					N/A	N/A	N/A
1 2 Classroom 202	N/A	Fiberglass Pipe Insulation	005010410010301030	Non Suspect ACM	12	LF	0	+	+	1		N/A 1	N/A	N/A
1 2 Classroom 202 1 2 Classroom 203	M N/A	Blackboard Glue Dots Wood Floor	6350/01/02/SYN/BB/2600	Assumed Non Suspect ACM	220 900	SF SF	0	+	+			N/A	Yes N/A	1/D N/A
1 2 Classroom 203	N/A	Plaster Walls		NAD	2700	SF	0					N/A	N/A	N/A
1 2 Classroom 203	N/A	Ceiling Tile 2' x 4'		Non Suspect ACM	900	SF	0					N/A	N/A	N/A
1 2 Classroom 203	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	34	LF	0					N/A	N/A	N/A
1 2 Classroom 203	M	Blackboard Glue Dots	6350/01/02/SYN/BB/2600	Assumed	220	SF	0	+	-	-	_	1 N/A	Yes	1/D
1         2         Stairwell outside Classroom 203           1         2         Stairwell outside Classroom 203	N/A N/A	Cement Floor Plaster Walls		Non Suspect ACM NAD	400 1200	SF SF	0	+	+			N/A N/A	N/A N/A	N/A N/A
1 2 Stairwell outside Classroom 203	N/A	Plaster Walls Plaster Ceiling		NAD	400	SF	0					N/A	N/A	N/A
1 2 Stairwell outside Classroom 203	T	Radiator Insulation	6350/01/02/SYN/BB/1600	Assumed	32	SF	0			2nd - 3rd Floor Landing - 32 SF		1	Yes	1/D
1 2 Hallway from Classrooms 201 to 203	N/A	Cement Floor		Non Suspect ACM	1000	SF	0					N/A	N/A	N/A
1 2 Hallway from Classrooms 201 to 203	N/A N/A	Plaster Walls		NAD Non Support ACM	3000	SF SF	0	+	+			N/A N/A	N/A N/A	N/A N/A
1 2 Hallway from Classrooms 201 to 203 1 2 Hallway from Classrooms 201 to 203	N/A M	Ceiling Tile 2' x 4' Blackboard Glue Dots	6350/01/02/SYN/BB/2600	Non Suspect ACM Assumed	1000	SF	0	+				1 N/A	N/A Yes	1/D
1 2 Girl's Restroom next to Classroom 204	N/A	Ceramic Tile Floors	20000 1102 0 110 00 2000	Non Suspect ACM	200	SF	0					N/A	N/A	N/A
1 2 Girl's Restroom next to Classroom 204	N/A	Ceramic Tile Walls		Non Suspect ACM	600	SF	0					N/A	N/A	N/A
1 2 Girl's Restroom next to Classroom 204	N/A	Plaster Ceiling		NAD	200	SF	0		_			N/A	N/A	N/A
1 2 Girl's Restroom next to Classroom 204	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	20	LF	0					N/A	N/A	N/A

School	District of Philadelphia		Α	HFRA Three-Year Re	inspection 2015-2016						Reinspection Date: 12/1/2015				
	ennypacker Elementary School			Room by Room Lo											
				ROUIII DY ROUIII EU	cation Log Report			l			Building Inspector: Bernard J Bryson				
1858 E Washin	ngton Lane, Philadelphia, PA 19138										Number: ACC-0125-6-031				
	ULCS# 6350										Management Planner: Megan Vala				
	Year Built: 1930										Number: 740728				
E	Total Builti 1000										Number: 110725				
!   _															
e												Attic/			
e o										Color		Crawl	Damage	Newly	_
n o		System		HID#	Confirmed/Assumed/NAD	Amount of Material		Amount o		required for VAT	0	Space	Potential (DP)	Friable (NF)	Response
1 2 Classroom 204	On-Site Room Name	Affected N/A	Material Description Wood Floor	HID#	Non Suspect ACM Non Suspect ACM	900	EA SF	Damage 0	EA	for VAI	Comments/Description/Notes	Ranking	N/A	N/A	Action (RA)
1 2 Classroom 204		N/A	Plaster Walls		NAD	2700	SF	0	+	_			N/A	N/A	N/A
1 2 Classroom 204		N/A	Ceiling Tile 2' x 4'		Non Suspect ACM	900	SF	0	+	_			N/A	N/A	N/A
1 2 Classroom 204		N/A	Fiberglass Pipe Insulation		Non Suspect ACM	22	LF	0					N/A	N/A	N/A
1 2 Classroom 204		М	Blackboard Glue Dots	6350/01/02/SYN/BB/2600	Assumed	160	SF	0					1	Yes	1/D
1 2 Classroom 205		N/A	Wood Floor		Non Suspect ACM	900	SF	0					N/A	N/A	N/A
1 2 Classroom 205		N/A	Plaster Walls		NAD	2700	SF	0					N/A	N/A	N/A
1 2 Classroom 205		N/A	Ceiling Tile 2' x 4'		Non Suspect ACM	900	SF	0					N/A	N/A	N/A
1 2 Classroom 205		N/A	Fiberglass Pipe Insulation		Non Suspect ACM	12	LF	0					N/A	N/A	N/A
1 2 Classroom 205		M	Blackboard Glue Dots	6350/01/02/SYN/BB/2600	Assumed	140	SF	0	_				1 1	Yes	1/D
1 2 Storage Room across from Cla	assroom 205	N/A	Cement Floor Plaster Walls		Non Suspect ACM NAD	80	SF SF	0	+-	+			N/A N/A	N/A N/A	N/A N/A
1 2 Storage Room across from Cla		N/A N/A	Plaster Walls Plaster Ceiling		NAD NAD	240 80	SF	0	+	+			N/A N/A	N/A N/A	N/A N/A
1 2 Storage Room across from Cla 1 2 Janitor's Closet inside Storage	Room across from Classroom 205	N/A N/A	Ceramic Tile Floors		Non Suspect ACM	20	SF	0	+	+		_	N/A	N/A	N/A
1 2 Janitor's Closet inside Storage	Room across from Classroom 205	N/A	Ceramic Tile Walls		Non Suspect ACM	80	SF	0	_	+			N/A	N/A	N/A
1 2 Janitor's Closet inside Storage	Room across from Classroom 205	N/A	Plaster Ceiling		NAD NAD	20	SF	0		1			N/A	N/A	N/A
1 2 IMC (Library)		M	Floor Tile VAT 12" x 12"	6350/01/02/BB	Assumed	900	SF	0		White			1	Yes	1/D
1 2 IMC (Library)		M	Floor Tile VAT 12" x 12"	6350/01/02/BB	Assumed	900	SF	0		Blue			1	Yes	1/D
1 2 IMC (Library)	-	N/A	Plaster Walls		NAD	5400	SF	0					N/A	N/A	N/A
1 2 IMC (Library)		N/A	Ceiling Tile 2' x 4'		Non Suspect ACM	1800	SF	0					N/A	N/A	N/A
1 2 IMC (Library)		N/A	Fiberglass Pipe Insulation		Non Suspect ACM	24	LF	0	_	1			N/A	N/A	N/A
1 2 IMC (Library)		M	Sink Undercoat Mastic	6350/01/02/SYN/BB/2602	Assumed	8	SF	0	1	+	No. Access		1	Yes	1/D
1 2 Storage/IT MDF Room across		X	X		X	X	X	X	X	X	No Access		X	X	X
Fire Tower across from Library	y 206	N/A	Cement Floor		Non Suspect ACM	400	SF	0					N/A	N/A	N/A
Fire Tower across from Library	y 206														
1   2		N/A	Brick Wall		Non Suspect ACM	1200	SF	0					N/A	N/A	N/A
Fire Tower across from Library	y 206	N/A	Concrete Ceiling		Non Suspect ACM	400	SF	0					N/A	N/A	N/A
1 2 Boy's Restroom next to Library	M.	N/A	Ceramic Tile Floors		Non Suspect ACM	200	SF	0	+	_			N/A	N/A	N/A
1 2 Boy's Restroom next to Library		N/A	Ceramic Tile Walls		Non Suspect ACM	600	SF	0					N/A	N/A	N/A
1 2 Boy's Restroom next to Library		N/A	Plaster Ceiling		NAD	200	SF	0					N/A	N/A	N/A
1 2 Boy's Restroom next to Library	y	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	6	LF	0					N/A	N/A	N/A
1 2 Center Hallway from Boy's to 0	Girl's Restrooms	N/A	Cement Floor		Non Suspect ACM	1500	SF	0					N/A	N/A	N/A
1 2 Center Hallway from Boy's to 0		N/A	Plaster Walls		NAD	4500	SF	0					N/A	N/A	N/A
1 2 Center Hallway from Boy's to 0	Girl's Restrooms	N/A	Ceiling Tile 2' x 4'		Non Suspect ACM	1500	SF	0	_				N/A	N/A	N/A
1 2 Center Hallway from Boy's to 0		M	Blackboard Glue Dots	6350/01/02/SYN/BB/2600	Assumed	40	SF	0	_	_			1	Yes	1/D
1 2 Stairwell outside Classroom 20		N/A	Cement Floor		Non Suspect ACM	400	SF	0	+	+			N/A	N/A	N/A
1 2 Stairwell outside Classroom 20 1 2 Stairwell outside Classroom 20		N/A N/A	Plaster Walls Plaster Ceiling		NAD NAD	1200 400	SF SF	0	+	+			N/A N/A	N/A N/A	N/A N/A
1 2 Stairwell outside Classroom 20		T	Radiator Insulation	6350/01/02/SYN/BB/1600	Assumed	32	SF	0	+	_	2nd - 3rd Floor Landing - 32 SF		1	Yes	1/D
1 2 Classroom 208	06	N/A	Wood Floor	0330/01/02/31N/BB/1000	Non Suspect ACM	900	SF	0	+	_	21d - 5ld 1 loof Earlaing - 52 of		N/A	N/A	N/A
1 2 Classroom 208		N/A	Plaster Walls		NAD	2700	SF	0	_				N/A	N/A	N/A
1 2 Classroom 208		N/A	Ceiling Tile 2' x 4'		Non Suspect ACM	900	SF	0					N/A	N/A	N/A
1 2 Classroom 208		N/A	Fiberglass Pipe Insulation		Non Suspect ACM	30	LF	0					N/A	N/A	N/A
1 2 Classroom 208		M	Blackboard Glue Dots	6350/01/02/SYN/BB/2600	Assumed	240	SF	0					1	Yes	1/D
1 2 Classroom 209		N/A	Wood Floor		Non Suspect ACM	900	SF	0	1	_			N/A	N/A	N/A
1 2 Classroom 209		N/A	Plaster Walls		NAD	2700	SF	0	_				N/A	N/A	N/A
1 2 Classroom 209		N/A	Ceiling Tile 2' x 4'		Non Suspect ACM	900	SF	0	+	+			N/A	N/A	N/A
1 2 Classroom 209		N/A M	Fiberglass Pipe Insulation Blackboard Glue Dots	6350/01/02/SYN/BB/2600	Non Suspect ACM Assumed	12 240	LF SF	0	+	+			N/A 1	N/A Yes	N/A 1/D
1 2 Classroom 209 1 2 Classroom 210		N/A	Wood Floor	033010 1102/3 1 N/DB/2000	Non Suspect ACM	900	SF	0	+	+			N/A	N/A	N/A
1 2 Classroom 210		N/A N/A	Plaster Walls		NOTI SUSPECI ACMI	2700	SF	0	1	1			N/A	N/A	N/A
1 2 Classroom 210		N/A	Ceiling Tile 2' x 4'		Non Suspect ACM	900	SF	0		1			N/A	N/A	N/A
1 2 Classroom 210		N/A	Fiberglass Pipe Insulation		Non Suspect ACM	18	LF	0	1				N/A	N/A	N/A
1 2 Classroom 210		М	Blackboard Glue Dots	6350/01/02/SYN/BB/2600	Assumed	220	SF	0					1	Yes	1/D
1 2 Storage Room outside Classro	pom 210	N/A	Wood Floor		Non Suspect ACM	300	SF	0					N/A	N/A	N/A
1 2 Storage Room outside Classro	oom 210	N/A	Plaster Walls		NAD	900	SF	0	_	1			N/A	N/A	N/A
1 2 Storage Room outside Classro	pom 210	N/A	Plaster Ceiling		NAD	300	SF	0	_	_			N/A	N/A	N/A
1 2 Storage Room outside Classro		N/A	Fiberglass Pipe Insulation		Non Suspect ACM	12	LF	0	+	1			N/A	N/A	N/A
1 2 Hallway from Classrooms 208		N/A	Cement Floor		Non Suspect ACM	1000	SF	0	+	+			N/A N/A	N/A N/A	N/A N/A
1 2 Hallway from Classrooms 208 1 2 Hallway from Classrooms 208	to 210	N/A N/A	Plaster Walls Ceiling Tile 2' x 4'		NAD Non Suspect ACM	3000 1000	SF SF	0	+	+			N/A N/A	N/A N/A	N/A N/A
1 2 Hallway from Classrooms 208		N/A	Fiberglass Pipe Insulation		Non Suspect ACM	12	LF	0	+	+			N/A	N/A	N/A
1 2 Hallway from Classrooms 208		M	Blackboard Glue Dots	6350/01/02/SYN/BB/2600	Assumed	20	SF	0		1			1	Yes	1/D
1 3 Classroom 301		N/A	Wood Floor		Non Suspect ACM	900	SF	0					N/A	N/A	N/A
1 3 Classroom 301		N/A	Plaster Walls		NAD	2700	SF	0					N/A	N/A	N/A
1 3 Classroom 301		N/A	Ceiling Tile 2' x 4'		Non Suspect ACM	900	SF	0					N/A	N/A	N/A
1 3 Classroom 301		N/A	Fiberglass Pipe Insulation		Non Suspect ACM	18	LF	0					N/A	N/A	N/A
1 3 Classroom 301		M	Blackboard Glue Dots	6350/01/03/SYN/BB/2600	Assumed	220	SF	0					1	Yes	1/D
1 3 Storage Room outside of Class		M	Floor Tile VAT 12" x 12"	6350/01/03/CC	Assumed	80	SF	0	+	White			1 1	Yes	1/D
1 3 Storage Room outside of Class		M	Floor Tile VAT 12" x 12"	6350/01/03/CC	Assumed	80	SF	0	-	Blue			1	Yes	1/D
1 3 Storage Room outside of Class		N/A	Plaster Walls		NAD Nas Sussest AGM	480	SF	0	+	+			N/A	N/A	N/A
1 3 Storage Room outside of Class	FUC INDUIS	N/A	Ceiling Tile 2' x 4'		Non Suspect ACM	160	SF	0			1		N/A	N/A	N/A

	School District of Philadelphia		A.1	JEDA Three Veer De	inspection 2015-2016										
			AI								Reinspection Date: 12/1/2015	-			
	Samuel Pennypacker Elementary School			Room by Room Lo	cation Log Report			]			Building Inspector: Bernard J Bryson				
	1858 E Washington Lane, Philadelphia, PA 19138										Number: ACC-0125-6-031				
	ULCS# 6350										Management Planner: Megan Vala				
	Year Built: 1930										Number: 740728				
E	Tour Bunt. 1999								1		Number: 740720				
1														ĺ	
e F												Attic/		ĺ	
m I e o										Color		Crawl	Damage	Newly	
n o	On-Site Room Name	System Affected	Material Description	HID#	Confirmed/Assumed/NAD	Amount of Material	SF LF EA	Amount of Damage	SFLF	required for VAT	Comments/Description/Notes	Space Ranking	Potential (DP)	Friable (NF)	Response Action (RA)
1 3		N/A	Ceramic Tile Floors	niu#	Non Suspect ACM Non Suspect ACM	50	SF	O ()	EA	IOI VAI	Comments/Description/Notes	Natikitiy	N/A	N/A	N/A
	Staff Restroom inside Storage Room outside of Classroom 301	N/A	Ceramic Tile Walls		Non Suspect ACM	150	SF	0					N/A	N/A	N/A
1 3	Staff Restroom inside Storage Room outside of Classroom 301	N/A	Ceiling Tile 2' x 4'		Non Suspect ACM	50	SF	0					N/A	N/A	N/A
1 3	Janitor's Closet inside Storage Room outside of Classroom 301	N/A	Ceramic Tile Floors		Non Suspect ACM	6	SF	0					N/A	N/A	N/A
1 3	Janitor's Closet inside Storage Room outside of Classroom 301	N/A	Ceramic Tile Walls		Non Suspect ACM	25	SF	0	_				N/A	N/A	N/A
1 3	Janitor's Closet inside Storage Room outside of Classroom 301 Classroom 311	N/A	Ceiling Tile 2' x 4'		Non Suspect ACM	6	SF	0	+				N/A N/A	N/A N/A	N/A N/A
	Classroom 311	N/A N/A	Wood Floor Plaster Walls		Non Suspect ACM NAD	900 2700	SF SF	0	1				N/A	N/A	N/A
1 3	Classroom 311	N/A	Ceiling Tile 2' x 4'		Non Suspect ACM	900	SF	0					N/A	N/A	N/A
1 3	Classroom 311	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	18	LF	0					N/A	N/A	N/A
1 3	Classroom 311	M	Blackboard Glue Dots	6350/01/03/SYN/BB/2600	Assumed	220	SF	0					1	Yes	1/D
1 3	Classroom 302	N/A	Wood Floor		Non Suspect ACM	900	SF	0					N/A	N/A	N/A
	Classroom 302	N/A	Plaster Walls		NAD Non Suggest ACM	2700	SF	0	-	-			N/A	N/A	N/A
	Classroom 302 Classroom 302	N/A N/A	Ceiling Tile 2' x 4' Fiberglass Pipe Insulation		Non Suspect ACM	900	SF LF	0	+		<del> </del>		N/A N/A	N/A N/A	N/A N/A
1 3	Classroom 302	M	Blackboard Glue Dots	6350/01/03/SYN/BB/2600	Non Suspect ACM Assumed	220	SF	0	1				1	Yes	1/D
1 3	Computer Lab 303	N/A	Wood Floor		Non Suspect ACM	900	SF	0					N/A	N/A	N/A
1 3	Computer Lab 303	N/A	Plaster Walls		NAD	2700	SF	0					N/A	N/A	N/A
1 3	Computer Lab 303	N/A	Ceiling Tile 2' x 4'		Non Suspect ACM	900	SF	0					N/A	N/A	N/A
	Computer Lab 303	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	18	LF	0	_				N/A	N/A	N/A
1 3	Computer Lab 303 Stairwell outside Classroom 303	M N/A	Blackboard Glue Dots Cement Floor	6350/01/03/SYN/BB/2600	Assumed Non Suspect ACM	220 400	SF SF	0	1				N/A	Yes N/A	1/D N/A
	Stairwell outside Classroom 303	N/A	Plaster Walls		NAD NAD	1200	SF	0	+				N/A	N/A	N/A
1 3	Stairwell outside Classroom 303	N/A	Plaster Ceiling		NAD	400	SF	0					N/A	N/A	N/A
1 3	Hallway from Classrooms 301 to 303	N/A	Cement Floor		Non Suspect ACM	1000	SF	0					N/A	N/A	N/A
1 3	Hallway from Classrooms 301 to 303	N/A	Plaster Walls		NAD	3000	SF	0					N/A	N/A	N/A
1 3	Hallway from Classrooms 301 to 303	N/A	Ceiling Tile 2' x 4'		Non Suspect ACM	1000	SF	0	-				N/A	N/A	N/A
1 3	Hallway from Classrooms 301 to 303 Girl's Restroom next to Classroom 304	M N/A	Blackboard Glue Dots Ceramic Tile Floors	6350/01/03/SYN/BB/2600	Assumed	200	SF SF	0	-				1 N/A	Yes N/A	1/D N/A
1 3	Girl's Restroom next to Classroom 304 Girl's Restroom next to Classroom 304	N/A N/A	Ceramic Tile Floors Ceramic Tile Walls		Non Suspect ACM Non Suspect ACM	600	SF	0	1				N/A N/A	N/A N/A	N/A N/A
1 3	Girl's Restroom next to Classroom 304	N/A	Plaster Ceiling		NAD	200	SF	0	+-				N/A	N/A	N/A
1 3	Girl's Restroom next to Classroom 304	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	20	LF	0					N/A	N/A	N/A
1 3	Classroom 304	N/A	Wood Floor		Non Suspect ACM	900	SF	0					N/A	N/A	N/A
	Classroom 304	N/A	Plaster Walls		NAD	2700	SF	0	_				N/A	N/A	N/A
	Classroom 304	N/A	Ceiling Tile 2' x 4'		Non Suspect ACM	900	SF	0	+				N/A	N/A	N/A N/A
1 3	Classroom 304 Classroom 304	N/A M	Fiberglass Pipe Insulation Blackboard Glue Dots	6350/01/03/SYN/BB/2600	Non Suspect ACM Assumed	140	LF SF	0	+		-		N/A 1	N/A Yes	1/D
1 3	Classroom 305	N/A	Wood Floor	0330/01/03/3114/BB/2000	Non Suspect ACM	900	SF	0	1				N/A	N/A	N/A
1 3	Classroom 305	N/A	Plaster Walls		NAD	2700	SF	0					N/A	N/A	N/A
1 3	Classroom 305	N/A	Ceiling Tile 2' x 4'		Non Suspect ACM	900	SF	0					N/A	N/A	N/A
	Classroom 305	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	6	LF	0	_				N/A	N/A	N/A
	Classroom 305	M	Blackboard Glue Dots	6350/01/03/SYN/BB/2600	Assumed	60	SF	0	_				1 N/A	Yes	1/D N/A
1 3	Classroom 306 Classroom 306	N/A N/A	Wood Floor Plaster Walls		Non Suspect ACM NAD	900 2700	SF SF	0	+			-	N/A N/A	N/A N/A	N/A N/A
	Classroom 306	N/A	Ceiling Tile 2' x 4'		Non Suspect ACM	900	SF	0					N/A	N/A	N/A
1 3	Classroom 306	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	6	LF	0					N/A	N/A	N/A
1 3	Classroom 306	M	Blackboard Glue Dots	6350/01/03/SYN/BB/2600	Assumed	60	SF	0					1	Yes	1/D
	Classroom 307	N/A	Wood Floor		Non Suspect ACM	900	SF	0	_		-		N/A	N/A	N/A
	Classroom 307 Classroom 307	N/A N/A	Plaster Walls Ceiling Tile 2' x 4'		NAD Non Suspect ACM	2700 900	SF SF	0	+		+		N/A N/A	N/A N/A	N/A N/A
1 3	Classroom 307	N/A N/A	Fiberglass Pipe Insulation		Non Suspect ACM Non Suspect ACM	900	LF	0			1		N/A	N/A	N/A
1 3	Classroom 307	M	Blackboard Glue Dots	6350/01/03/SYN/BB/2600	Assumed	140	SF	0					1	Yes	1/D
1 3	Storage Room across from Classroom 307 (next to Fire Tower)	N/A	Cement Floor		Non Suspect ACM	100	SF	0					N/A	N/A	N/A
1 3		N/A	Plaster Walls		NAD	300	SF	0					N/A	N/A	N/A
1 3	Storage Room across from Classroom 307 (next to Fire Tower) Fire Tower across from Classroom 307	N/A	Plaster Ceiling		NAD	100	SF	0	-				N/A	N/A	N/A
1 3	File Tower across (IOIII Classroom 307	N/A	Cement Floor		Non Suspect ACM	400	SF	0					N/A	N/A	N/A
	Fire Tower across from Classroom 307														
1 3	Fire Tower across from Classroom 307	N/A	Brick Wall		Non Suspect ACM	1200	SF	0	+-	-			N/A	N/A	N/A
1 3	I IIIG TOWER BUILDS HUITI CIDSSIUUITI 307	N/A	Concrete Ceiling		Non Suspect ACM	400	SF	0	L				N/A	N/A	N/A
	Fire Tower across from Classroom 307										Compressed Paper Pipe Insulation applied to Roof Dra				
1 3	Size Taylor and Classes 207	T	Pipe Insulation 2-6 inch	6350/01/03/014	Confirmed	10	LF	1	LF		Line		1	Yes	5/C
1 3	Fire Tower across from Classroom 307	т	Pipe Fitting Insulation	6350/01/03/16	Confirmed	1	EA	1	EA		applied to Roof Drain Line		1	Yes	5/C
1 3	Boy's Restroom next to Classroom 307	N/A	Ceramic Tile Floors		Non Suspect ACM	200	SF	0	T				N/A	N/A	N/A
1 3	Boy's Restroom next to Classroom 307	N/A	Ceramic Tile Walls		Non Suspect ACM	600	SF	0					N/A	N/A	N/A
1 3	Boy's Restroom next to Classroom 307	N/A	Plaster Ceiling		NAD	200	SF	0	SF				N/A	N/A	N/A
1 3	Boy's Restroom next to Classroom 307	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	12	LF	0	-				N/A	N/A	N/A
	Hallway from Boy's to Girl's Restrooms	N/A	Cement Floor		Non Suspect ACM	1500	SF SF	0	-	-	1		N/A N/A	N/A N/A	N/A N/A
1 3	Hallway from Boy's to Girl's Restrooms Hallway from Boy's to Girl's Restrooms	N/A N/A	Plaster Walls Ceiling Tile 2' x 4'		NAD Non Suspect ACM	4500 1500	SF	0	+	<b>—</b>	<u> </u>	-	N/A N/A	N/A N/A	N/A N/A
	Hallway from Boy's to Girl's Restrooms	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	24	LF	0					N/A	N/A	N/A
1 3	Hallway from Boy's to Girl's Restrooms	M	Blackboard Glue Dots	6350/01/03/SYN/BB/2600	Assumed	20	SF	0					1	Yes	1/D
											·				

	School District of Philadelphia Samuel Pennypacker Elementary School 1858 E Washington Lane, Philadelphia, PA 19138	AHERA Three-Year Reinspection 2015-2016 Room by Room Location Log Report								Reinspection Date: 12/1/2015 Building Inspector: Bernard J Bryson Number: ACC-0125-6-031					
	9 ' ' '														
	ULCS# 6350										Management Planner: Megan Vala				
	Year Built: 1930										Number: 740728				
E															
1	F													ı	
m												Attic/		ı	
e	0									Color		Crawl	Damage	Newly	1_
n t	o r On-Site Room Name	System Affected	Material Description	HID#	Confirmed/Assumed/NAD Non Suspect ACM	Amount of Material	SF LF EA	Amount of Damage	SF LF EA	required for VAT	Comments/Description/Notes	Space Ranking	Potential (DP)	Friable (NF)	Response Action (RA)
1	3 Stairwell outside Classroom 308	N/A	Cement Floor	HID#	Non Suspect ACM Non Suspect ACM	400	SF	Damage 0	EA	TOF VAI	Comments/Description/Notes	Kanking	N/A	N/A	N/A
1	3 Stainwell outside Classroom 308	N/A	Plaster Walls		NAD	1200	SF	0	_				N/A	N/A	N/A
1	3 Stainwell outside Classroom 308	N/A	Plaster Ceiling		NAD	400	SF	0					N/A	N/A	N/A
1		N/A	Wood Floor		Non Suspect ACM	900	SF	0					N/A	N/A	N/A
1	3 Classroom 308	N/A	Plaster Walls		NAD	2700	SF	0					N/A	N/A	N/A
1	3 Classroom 308	N/A	Ceiling Tile 2' x 4'		Non Suspect ACM	900	SF	0					N/A	N/A	N/A
1	3 Classroom 308	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	12	LF	0					N/A	N/A	N/A
1	3 Classroom 308	M	Blackboard Glue Dots	6350/01/03/SYN/BB/2600	Assumed	220	SF	0					1	Yes	1/D
1	3 Classroom 309	N/A	Wood Floor		Non Suspect ACM	900	SF	0					N/A	N/A	N/A
1	3 Classroom 309	N/A	Plaster Walls		NAD	2700	SF	0					N/A	N/A	N/A
1	3 Classroom 309	N/A	Ceiling Tile 2' x 4'		Non Suspect ACM	900	SF	0					N/A	N/A	N/A
1	3 Classroom 309	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	6	LF	0					N/A	N/A	N/A
1	3 Classroom 309	М	Blackboard Glue Dots	6350/01/03/SYN/BB/2600	Assumed	220	SF	0					1	Yes	1/D
1	3 Classroom 310	N/A	Wood Floor		Non Suspect ACM	900	SF	0					N/A	N/A	N/A
1	3 Classroom 310	N/A	Plaster Walls		NAD	2700	SF	0					N/A	N/A	N/A
	3 Classroom 310	N/A	Ceiling Tile 2' x 4'		Non Suspect ACM	900	SF	0					N/A	N/A	N/A
1	3 Classroom 310	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	12	LF	0					N/A	N/A	N/A
1	3 Classroom 310	М	Blackboard Glue Dots	6350/01/03/SYN/BB/2600	Assumed	220	SF	0					1	Yes	1/D
1	3 Storage Room outside Classroom 310	N/A	Wood Floor		Non Suspect ACM	300	SF	0					N/A	N/A	N/A
1	3 Storage Room outside Classroom 310	N/A	Plaster Walls		NAD	900	SF	0					N/A	N/A	N/A
1	3 Storage Room outside Classroom 310	N/A	Plaster Ceiling		NAD	300	SF	0					N/A	N/A	N/A
1	3 Hallway from Classrooms 308 to 310	N/A	Cement Floor		Non Suspect ACM	1000	SF	0					N/A	N/A	N/A
1	3 Hallway from Classrooms 308 to 310	N/A	Plaster Walls		NAD	3000	SF	0					N/A	N/A	N/A
1	3 Hallway from Classrooms 308 to 310	N/A	Ceiling Tile 2' x 4'		Non Suspect ACM	1000	SF	0					N/A	N/A	N/A
1	3 Hallway from Classrooms 308 to 310	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	6	LF	0					N/A	N/A	N/A
1	3 Hallway from Classrooms 308 to 310	М	Blackboard Glue Dots	6350/01/03/SYN/BB/2600	Assumed	20	SF	0					1	Yes	1/D
1	A Attic above 3rd Floor accessible by the Main Stairwell	X	X		X	X	X	Х	X	X	150 Hard Fittings, 1000 LF Mag Block	В	X	X	X
1	A Attic accessible to 3rd Floor Corridor	Х	X		X	Х	X	Х	X	Х	Horsehair	Α	Х	Х	Х
1	CS Crawl Space - None	X	X	1	X	X	X	X	X	X	None	None			



#### Section III - A

#### Management Planner/Building Inspector Certificates

These charts indicate the Name, Course Date, Expiration Date and Corresponding Certificate Number of the Management Planner and Building Inspector of individuals that participated in the AHERA 3 Year Inspection and Management Plan process of 2015/2016.

Management Planner	Date Granted	Expiration Date	Certificate Number
Monique Causley	2/15/2015	2/16/2016	ACC-0215-8-010
Monique Causley	2/16/2016	2/17/2017	ACC-0216-8-001
Megan Vala	5/22/2015	6/22/2016	740728
Mary Anne Lerro	4/5/2016	4/5/2017	742327

Building Inspector	Date Granted	Expiration Date	Certificate Number
Scott Magee	8/15/2015	8/15/2016	70016699C
William Garrity	8/15/2015	8/15/2016	70016699A
Bernard Brunner	10/2/2015	8/2/2016	45397
Mary Anne Lerro	3/3/2015	3/3/2016	740092
Mary Anne Lerro	4/5/2016	4/5/2017	742322
James Madden	12/11/2014	12/11/2015	ACC-1214-6-010
James Madden	12/3/2015	12/3/2016	ACC-1215-6-018
Troy Ray	3/15/2015	3/19/2016	ACC-0355-6-011
Ananth Vinjamuri	9/29/2015	9/29/2016	374
Shelton Williams	9/29/2015	9/29/2016	375
Paul Davis	2/12/2015	2/12/2016	ACC-0215-6-015
Paul Davis	2/2/2016	2/2/2017	741836
Bernard Bryson	2/16/2015	2/16/2016	ACC-0125-6-031
Bernard Bryson	2/15/2016	2/15/2017	ACC-0216-6-005
Alexander Roman	9/18/2015	9/18/2016	EHSBIR-150619-008
Norm Harrison	9/2/2015	9/2/2016	ACC-0915-6-011
Kelly Mayberry	2/20/2015	2/20/2016	EHSBIR-150220-005
Kelly Mayberry	2/18/2016	2/18/2017	EHSBIR-160218-006
Andrew Hine	5/6/2015	5/6/2016	AI05042015-3
Maryellen Leotta	2/12/2015	2/12/2016	ACC-0215-6-024

awarded to

### Monique Causley

for successfully completing the prescribed course of study in

## Pennsylvania Asbestos Management Planner Refresher Course

under TSCA Title II

presented by

ACCESS TRAINING SERVICES, INC. 7921 River Road, Pennsauken, NJ 08110

(856) 665-3449

Course Date

Exam Date

ACC-0215-8-010 Certificate Number

Social Security Number

Not Provided

Mark K. Schläger

Training Director

awarded to

## Monique Causley for successfully completing the prescribed course of study in

## Pennsylvania Asbestos Management Planner Refresher Course

under TSCA Title II

ACCESS TRAINING SERVICES, INC. presented by

7921 River Road, Pennsauken, NJ 08110 (856) 665-3449

2/15/16

Course Date

Not Provided
Social Security Number

Exam Date

ACC-0216-8-001 Certificate Number

2/15/17

Mark K. Schläger Training Director

# Certificate of Iraining

CRITERION LABORATORIES, INC.

HEREBY CERTIFIES THAT

Megan Vala

HAS SUCCESSFULLY COMPLETED A 16 HOUR COURSE ENTITLED

Asbestos Management Planner Initial

INCLUDING CLASSROOM INSTRUCTION

05/21/2015 to 05/22/2015

Exam passed on this 22nd day of May 2015 - Score - 94

Approved for AHERA Accreditation Under TSCA Title II

3370 Progress Drive, Suite J
Bensalem, PA 19020
(215) 244-1300 - Phone

Course is conducted in English

www.criterionlabs.com

DIRECTOR:

Drive

James A. Weltz, CIH, President

# Certificate of Iraining

CRITERION LABORATORIES, INC. HEREBY CERTIFIES THAT

Mary Anne Lerro

HAS SUCCESSFULLY COMPLETED A 4 HOUR COURSE ENTITLED

Asbestos Management Planner Refresher INCLUDING CLASSROOM INSTRUCTION

on this 5th day of April 2016

Approved for AHERA Accreditation Under TSCA Title II

3370 Progress Drive, Suite J (215) 244-1300 - Phone (215) 244-4349 - Fax Bensalem, PA 19020

Course is conducted in English

www.criterionlabs.com

DIRECTOR:

g-cust

James A. Weltz, CIH, President

# EMSL ANALYTICAL, INC.

Certifies that

### Scott Magee

has successfully completed the course of study for the

# **Asbestos Building Inspector Refresher Course**

for Accreditation under TSCA Title II

EMSL Certificate No. 70016699C

Approved by:

Accreditation # 137 PA Dept of Labor and Industry

> Course Date: 8/15/2015 Granted: 8/15/2015

Expiration Date: 8/15/2016

Sponsored by:

EMSL Analytical, Inc. 200 Route 130 North Phone: (800) 220-3675 Cinnaminson, NJ 08077

Fax: (856) 786-5973 www.emsl.com

Training Director Michael P. Menz, CIH

My Dry Carlo

Environmental, Mold, Bacteria, IAQ, Asbestos, Lead, Forensic and Materials Testing Since 1981

# EMSL ANALYTICAL, INC.

Certifies that

### William Garrity

has successfully completed the course of study for the

# Asbestos Building Inspector Refresher Course

for Accreditation under TSCA Title II

EMSL Certificate No. 70016699A

Approved by:

Accreditation # 137 PA Dept. of Labor and Industry

> Course Date: 8/15/2015 Expiration Date: 8/15/2016 Granted: 8/15/2015

Sponsored by:

Cinnaminson, NJ 08077 200 Route 130 North EMSL Analytical, Inc. Phone: (800) 220-3675

Fax: (856) 786-5973 www.cmsl.com

> Michael P. Menz, CIH Training Director

Environmental, Mold, Bacteria, IAQ, Asbestos, Lead, Forensic and Materials Testing Since 1981

45397

## National Asbestos & Environmental Training Institute CERTIFICATE OF COMPLETION

AHERA/EPA Accredited Per 40 CFR Part 763
Asbestos Accreditation under TSCA Title II

This is to certify that •

## Bernard Brunner, Jr.

Successfully completed the course entitled

1/2-Day New York State/EPA/AHERA Asbestos Building Inspector Annual Refresher on October 2, 2015

Examination Passed October 2, 2015

Expiration Date on October 2, 2016

President, NAETI

Per 10 NYCRR Part 73.2 (L) (1), DOH 2832 Certificate of Completion of Asbestos Safety Training is the only official record of training for N.Y.S. students.

Language: English

ABIH 1/2 CM POINT

3321 Doris Avenue, Building B, Ocean, NJ 07712

Phone (732) 531-5571

Fax (732) 531-5956

www.naeti.com

## Certificate of Iraining

CRITERION LABORATORIES, INC.

HEREBY CERTIFIES THAT

Mary Anne Lerro

Asbestos Building Inspector Refresher

HAS SUCCESSFULLY COMPLETED A 4 HOUR COURSE ENTITLED

on this 3rd day of March 2015

Exam passed on this 3rd day of March 2015 - Score - 84

Approved for AHERA Accreditation Under TSCA Title II

3370 Progress Drive, Suite J

(215) 244-1300 - Phone

(215) 244-4349 - Fax

www.criterionlabs.com

Course is conducted in English

DIRECTOR:

g-custo

James A. Weltz, CIH, President

# Certificate of Iraining

CRITERION LABORATORIES, INC. HEREBY CERTIFIES THAT

Mary Anne Lerro

HAS SUCCESSFULLY COMPLETED A 4 HOUR COURSE ENTITLED

Asbestos Building Inspector Refresher

INCLUDING CLASSROOM INSTRUCTION

on this 5th day of April 2016

Exam passed on this 5th day of April 2016 - Score - 88

Approved for AHERA Accreditation Under TSCA Title II

3370 Progress Drive, Suite J Bensalem, PA 19020 (215) 244-1300 - Phone

(215) 244-1300 - Phone (215) 244-4349 - Fax www.criterionlabs.com

Course is conducted in English

DIRECTOR:

gruss.

James A. Weltz, CIH, President

### James Madden

for successfully completing the prescribed course of study in

### **Building Inspector Refresher Course** Pennsylvania Asbestos

under TSCA Title II

presented by ACCESS TRAINING SERVICES, INC.

7921 River Road, Pennsauken, NJ 08110 (856) 665-3449

12/11/14
Course Date

N/A

Exam Date

12/11/1

Not Provided
Social Security Number

ACC-1214-6-010

Certificate Number

Expiration Date

Man

Mark K. Schläger Training Director

### James Madden

for successfully completing the prescribed course of study in

### **Building Inspector Refresher Course** Pennsylvania Asbestos

under TSCA Title II

presented by ACCESS TRAINING SERVICES, INC. 7921 River Road, Pennsauken, NJ 08110 (856) 665-3449

Course Date

Exam Date

ACC-1215-6-018

12/3/16
Expiration Date

Mark K. Schläger

Training Director

Certificate Number

ACA ACA ACA

Social Security Number **Not Provided** 

## Troy A. Ray for successfully completing the prescribed course of study in

### **Building Inspector Refresher Course** Pennsylvania Asbestos under TSCA Title II

presented by

ACCESS TRAINING SERVICES, INC. 7921 River Road, Pennsauken, NJ 08110 (856) 665-3449

Social Security Number Not Provided Course Date 3/19/15 ACC-0355-6-011 Certificate Number 3/19/16
Expiration Date Mark K. Schläger Training Director

G&C Environmental Services, Inc. (#294) 2 Street Road, Newtown Square, Pennsylvania 19073

Telephone: (610) 993-9202 Facsimile: (610) 993-9232

Email: Training@gcenviro.com www.GCenviro.com

This document certifies that Ananth K. Vinjamuri has successfully completed this

State of New York Department of Health Approved AHERA BUILDING INSPECTOR

REFRESHER COURSE, completed as required for asbestos accreditation under the Toxic

Substances Control Act, Title II. This course was held from  $\frac{09/29/2015}{MM$  DD YR MM DD YR successful completion of the examination \_\_\_ The examination date was  $\frac{09/29/2015}{MM$  DD YR 09/29/2016.

The official record of successful training completion is the New York State Department of Health certificate of asbestos safety training completion (DPH 2832).

Hail M. Conner

Gail M. Conner Training Director

G&C Environmental Services, Inc. (#294)

2 Street Road, Newtown Square, Pennsylvania 19073 Telephone: (610) 993-9202 Facsimile: (610) 993-9232

Email: Training@gcenviro.com

www.GCenviro.com

This document certifies thatSh
<u>ıelton Williams</u>
has successfully completed this

State of New York Department of Health Approved AHERA BUILDING INSPECTOR REFRESHER COURSE, completed as required for asbestos accreditation under the Toxic

Substances Control Act, Title II. This course was held from  $\frac{09/29/2015}{MM$  DD YR MM DD YR successful completion of the examination  $\frac{09/29/2016}{MM$  DD YR The examination date was  $\frac{09/29/2015}{MM$  DD YR

The official record of successful training completion is the New York State Department of Health certificate of asbestos safety training completion (DPH 2832).

Hailm, Conner

Gail M. Conner
Training Director

### Paul M. Davis

for successfully completing the prescribed course of study in

### **Building Inspector Refresher Course** Pennsylvania Asbestos

under TSCA Title II

presented by ACCESS TRAINING SERVICES, INC. 7921 River Road, Pennsauken, NJ 08110

(856) 665-3449

Social Security Number Not Provided Course Date ACC-0215-6-015 Certificate Number Exam Date Mark K. Schläger Expiration Date 2/12/16

Training Director

Number 741836

Expiration Date: 02/02/2017

# Certificate of Irainas

CRITERION LABORATORIES, INC

HEREBY CERTIFIES THAT

Paul M. Davis

HAS SUCCESSFULLY COMPLETED A 4 HOUR COURSE ENTERLIED

Asbestos Building Inspector Refresher

NCL UDING OLASSROOM INSTRUCTION

on this 2nd day of February 2016

ed on this Znd day of Echruary 2016 - Score - 92

Iames A. Weltz, CIH, Presiden gruss

Course is conducted in English

3370 Progress Drive, Suite J (215) 244-1300 - Phone (215) 244-4349 - Fax

### Bernard J. Bryson

for successfully completing the prescribed course of study in

### Building Inspector Refresher Course Pennsylvania Asbestos under TSCA Title II

presented by ACCESS TRAINING SERVICES, INC. 7921 River Road, Pennsauken, NJ 08110 (856) 665-3449

Social Security Number	Not Provided	Course Date	2/16/15
Certificate Number	ACC-0125-6-031	Exam Date	N/A
Mark K. Schläger Training Director	May 5 Serving	Expiration Date	2/16/16

## Bernard J. Bryson

for successfully completing the prescribed course of study in


### **Building Inspector Refresher Course** Pennsylvania Asbestos under TSCA Title II

presented by ACCESS TRAINING SERVICES, INC. 7921 River Road, Pennsauken, NJ 08110 (856) 665-3449

rtificate Number	CC-0216-6-005	Exam Date	N/A
/ Mark K. Schlager Training Director	Mah 2 soll	Expiration Date	2/15/17

Not Provided
Social Security Number

2/15/16
Course Date



### Norman Harrison

for successfully completing the prescribed course of study in

### **Building Inspector Refresher Course** Pennsylvania Asbestos under TSCA Title II

Illust 1904 rice is

presented by ACCESS TRAINING SERVICES, INC. 7921 River Road, Pennsauken, NJ 08109 (856) 665-3449

Social Security Number Not Provided Course Date ACC-0915-6-011 Certificate Number Exam Date Training Director Mark K. Schläge Expiration Date 9/2/16

## EHS TRAINING INSTITUTE, INC.

A Division of BATTA, Inc.

### Certificate of Completion AHERA Building Inspector (Refresher)

Awarded To:

## Kelly Mayberry

SS#:XXX-XX-1551

Who has completed this 4-hour course and examination, EPA Approved under TSCA Title II AHERA / ASHARA Rule
40 CFR Part 763.

EHS TRAINING INSTITUTE, INC.

A Division of BATTA, Inc.

Delaware Industrial Park • 6 Garfield Way

Newark, DE 19713-5817

(302) 737-3376 • Fax (302) 737-5764

Course Date: February 20, 2015

Date of Expiration: February 20, 2016

Certification Number: EHSBIR 150220-005

Todd K. Zeisloft, Instructor

Neeraj K. Batta, President

## EHS TRAINING INSTITUTE, INC.

A Division of BATTA, Inc

# **Certificate of Completion**

### AHERA Building Inspector (Refresher)

Awarded To:

### Kelly Mayberry

SS#:XXX-XX-1551

Who has completed this 4-hour course and examination, EPA Approved under TSCA Title II AHERA / ASHARA Rule 40 CFR Part 763.

EHS TRAINING INSTITUTE, INC.

A Division of BATTA, Inc.

Delaware Industrial Park • 6 Garfield Way

Newark, DE 19713-5817

(302) 737-3376 • Fax (302) 737-5764

Course Date: February 18, 2016

Date of Expiration: February 18, 2017

Certification Number : EHSBIR 160218-006

Todd K. Zeisloft, Instructor

Neeraj K. Batta, President

# **AEROSOL MONITORING & ANALYSIS, INC.**

This is to certify that

### ANDREW HINE

has met the attendance requirements and successfully completed

the course entitled

3-DAY EPA AHERA INSPECTOR

For Accreditation Under TSCA Title II

Certification No.	AI05042015-3	Course Date	05/04/2015 to 05/06/2015
		Exam Date	05/06/2015
		Expiration Date	5/6/2016
Course Director	E. Rush Barnett	2.00	STEVE SIERACKI
	E. Rad Bandt		for & Nohn-

1331 Ashton Road

P.O.Box 646

Hanover, MD 21076

P: 410-684-3327

F: 410-684-3724

www.amatraining.com

### Maryellen Leotta

for successfully completing the prescribed course of study in

### Building Inspector Refresher Course Pennsylvania Asbestos under TSCA Title II

presented by

ACCESS TRAÍNING SERVICES, INC. 7921 River Road, Pennsauken, NJ 08110 (856) 665-3449

2/12/15 N/A
Course Date Exam Date

.

ACC-0215-6-024
Certificate Number

Not Provided
Social Security Number

2/12/16

Expiration Date

Mark K. Schläger
Training Director

### Asbestos Hazard Emergency Response Act (AHERA) Environmental Compliance Audit Cross Reference Table

In response to the AHERA Environmental Compliance Audit a Cross Reference Table has been prepared for inclusion into the Environmental Management Plan. The purpose of this Cross Reference Table is to link the following documents to the AHERA Management Plan.

### **Cross Reference Table**

3 Year Reinspection Report follows this Cross Reference Table documentation.

Subject Matter	Location of Required Documents
Designated Person	Pages 1 - 3
Annual Notification	Pages 4 - 5
6 Month Periodic Surveillance Outline of Events	Page 6
3 Year Re-inspections Outline of Events	Page 7
Asbestos Management Program (operations and maintenance)	Pages 8 - 19
Asbestos Investigation Report (AIR)	Attachment 1 Letter Dated August 4, 2006
Training (included in the Asbestos Management Program)	The original records are centralized at the School District's Environmen Library. Copies are maintained on staff and are required to be maintained the latest Reinspection Report.  2 hour awareness training records for all Building Engineers, Custodi Assistants and maintenance personnel  40 hour worker/supervisor training records for the OEMS A-Team a various AST tradesmen.
Response Actions (monthly mailings if applicable)	The original documents are on file at the School District's Environmen Library.
	Copies of the original are mailed to the Schools Main Office for retenti with the Management Plan documentation. These documents are typica kept separate from the management plan in an update binder due to t potential volume of response action reports.

### SCHOOL DISTRICT OF PHILADELPHIA

### ASBESTOS DESIGNATED PERSON

Gerald F Junod
Office of Capital Programs
Environmental Management & Services
440 N Broad Street, 3<sup>rd</sup> Floor
Philadelphia, PA 19130
Telephone: 215 400 6738
Fax: 215 400 4751

Drexel University- Asbestos Building Inspector Course

Drexel University- Asbestos Management Planner Course

Criterion Laboratories, Inc. - Asbestos Management Planner Course October 11-12, 2012 16 Hours

### **Annual Building Inspector Refreshers**

1990 to Present

4 Hours
Drexel University
Criterion Laboratories, Inc
Access Training Services, Inc.

### **Annual Building Management Planner Refreshers**

1990 to 1994

4 Hours
Drexel University
Criterion Laboratories, Inc
4 Hours

2013 to Present

### Environmental Manager, School District of Philadelphia

Manages the design and implementation of asbestos and lead projects for the Capital Improvement Program and other District Departments including Facilities & Operations and Information Technology. Ensures that asbestos abatement and lead remediation projects are expertly designed and executed in accordance with industry best management practice standards and regulations.

### Manager, City of Philadelphia Asbestos Control Program

Served as the Asbestos Control Program Manager for the City of Philadelphia, Department of Public Health, Air Management Services, Asbestos Control Unit from August 1, 2003 through October 23, 2006.

### Mid Atlantic Regional Environmental Consortium (MAREC)

Former member with attendance and participation commitments of all quarterly EPA Region III and yearly National Asbestos Regulatory Conferences sponsored by the EPA and the National Conference of State Legislators respectively as a representative for the City of Philadelphia Department of Public Health Air Management Services from 1994 through 2006.

### Philadelphia Environmental Task Force

Former member of the Philadelphia Environmental Task force as a representative and point of contact for the City of Philadelphia Department of Public Health Air Management Services Asbestos Control Unit from 2002 through 2006.

### **Asbestos Instructor**

Worked as the primary instructor for the initial and annual Asbestos Project Inspector training and licensing program as mandated by City of Philadelphia Department of Pubic Health Asbestos Control Regulations from August 1994 through October 2006.

Worked as a lead instructor with an Environmental Consulting Firm and approved by the US EPA for the initial and annual refresher training courses for various asbestos occupational disciplines such as the Building Inspector, Management Planner and Worker/Supervisor from 1991 through 1994.

I certify that the general, local agency responsibilities as stipulated in Section 763.84 will be met.

Gerald F. Junod

Asbestos Designated Person

Environmental Manager

Office of Environmental Management and Services

### SCHOOL DISTRICT OF PHILADELPHIA

### **Accreditation Information Statement**

All persons who inspect for Asbestos Containing Building Materials (ACBM) and who will design or carry our response actions with respect to assumed and confirmed ACBM, will be accredited by an EPA approved course and/or a State Contractors AccreditationProgram under Sections 206 (c) and 206 (b) of Title II of the ACT.

Gerald F. Junod

Asbestos Designated Person Environmental Manager

Office of Environmental Management and Services

### SCHOOL DISTRICT OF PHILADELPHIA OFFICE OF CAPITAL PROGRAMS 440 NORTH BROAD STREET, SUITE 373 PHILADELPHIA, PENNSYLVANIA 19130

OFFICE OF ENVIRONMENTAL MANAGEMENT AND SERVICES

PHONE (215)-400-4750

September 2015

TO:

Principals

Building Administrators/Occupants

Parents/Guardians

FROM:

Fran Burns

Chief Operating Officer

Francine Locke, M.S., Director

Office of Environmental Management and Services

SUBJECT:

Annual EPA Notification Letter

Pursuant to the Federal Environmental Protection Agency (EPA) mandate, as required by 40 C.F.R. 763.84 (c)(d) of public access to environmental records, this letter is to acknowledge the availability of your facility's Asbestos Hazard Emergency Response Act (AHERA) Management Plan.

Each member of the school staff, parents/guardians, temporary workers and/or contractors, are required to receive a copy of the Notification Letter. At the direction of the Principal, a copy is to be posted on the bulletin boards and an appropriate amount of copies are to be generated for distribution.

Note: The AHERA Three-Year Reinspection reports, in colored binders; White with Pink, Tan, Black, Red, Dark Blue, Green, Yellow and White, are Federal EPA mandated inspection documents. The School District of Philadelphia is subject to severe monetary penalties if the reports and associated paperwork are not available to the EPA and the public upon request.

It is incumbent on designated school personnel to gather and retain this data as it is delivered, in one location for future review. Acceptable locations include the Principal's Office or Main Office for the primary data. The Building Engineer should maintain any secondary or duplicate copies.

If you have any questions, please call 215-400-4750. Thank you for your cooperation.

Fran Burns

Chief Operating Officer

Francine Locke, M.S., Director

Office of Environmental Management

and Services

c: Danielle Floyd

AHERA-4 8/21/15



### School District of Philadelphia OFFICIAL NOTICE

### PLEASE POST

September 2015

TO:

Principals

Building Administrators Building Engineers Building Occupants Parents/Guardians

FROM:

Fran Burns

Chief Operating Officer

Francine Locke, M.S., Director

Office of Environmental Management and Services

SUBJECT:

Annual Notification Letter: Asbestos Hazard Emergency Response Act

The Federal Register published on October 30, 1987, Subpart E, in Schools: Final Rule and Notice, 763.84 (c)(d) states that each local education agency shall ensure that workers and building occupants or guardians are to be informed at least once each school year about inspections, response actions and post-response action activities including re-inspections and periodic surveillance activities. The School District as the Local Education Agency (LEA), retains such reports that are available for public inspection in the Office of the Principal or Building Administrator.

The Principal or Building Administrator is required to do the following with this notification:

Post in a Public Place or Main Office

2) Inform Building Occupants

3) Send a copy of this notification to Parents or Guardians

4) Insert a copy into the latest AHERA Three-Year Reinspection report (white/pink binder)

in your office or facility.

Fran Burns

Chief Operating Officer

Francine Locke, M.S., Director

Office of Environmental Management

and Services

c: Danielle Floyd

AHERA-4a 8/21/15

### SCHOOL DISTRICT OF PHILADELPHIA

### Education Center 440 North Broad Street Philadelphia, Pennsylvania 19130

Office of Environmental Management and Services

215-400-4750

### AHERA Six Month Surveillance Outline of Events

- Pursuant to the Federal Environmental Protection Agency (EPA) mandate, as required by 40 CFR 763.92(b), the following procedure is to be implemented. At least once every six (6) months after a Management Plan is in effect, each Local Education Agency (LEA) shall conduct a periodic surveillance in each building that it owns or leases that contains Asbestos Containing Building Materials (ACBM) or is assumed to contain ACBM.
- The first Bi-Annual Inspection starts in the Spring (March, April, May) and again in the Fall (October, November, December) of each year. The Building Engineer/Assistant should assist the Building Inspector with appropriate access to all areas including (Crawlspaces/Attics) and rooms in the facility. There is no action required of the Principal.
- The Building Inspector shall visually inspect all areas that are identified in the Management Plan as ACBM or assumed ACBM. The date of the surveillance is recorded, the inspectors name and any changes in the conditions of the materials.
- The Building Inspector shall make a copy of the inspection document and insert into the front of the latest Management Plan (AHERA Three Year Reinspection report). The original document is returned to the LEA's Environmental Library and filed.

### SCHOOL DISTRICT OF PHILADELPHIA

### Education Center 440 North Broad Street Philadelphia, Pennsylvania 19130

Office of Environmental Management and Services

215-400-4750

### AHERA Three Year Reinspection Outline of Events

- Pursuant to the Federal Environmental Protection Agency (EPA) mandate, as required by 40 CFR 763.85(b) the following procedure is to be implemented. At least once every three (3) years after a Management Plan is in effect, each Local Education Agency (LEA) shall conduct a reinspection of each building that it owns or leases that contains Asbestos Containing Building Material's (ACBM's) or is assumed to contain ACBM.
- Subsequent Three Year Re-inspections (2009, 2012, 2015, etc) shall start in the Fall (October, November, December, January). The Building Engineer/Assistant should assist the Building Inspector with appropriate access to all areas including (Crawlspaces/Attics) and rooms in the facility. There is no action required of the Principal.
- An accredited Building Inspector shall visually inspect and touch to determine friability, all areas that are identified in the Management Plan as ACBM or assumed ACBM. The date of the surveillance is recorded, the inspectors name and any changes in the conditions of the materials. The Building Inspectors state of accreditation and license number is required.
- After the inspection, the Building Inspector shall make a copy of the inspection documents and insert into the front of the latest Management Plan (AHERA Three Year Reinspection report). The original document is returned to the LEA's Environmental Library and filed.
- The Building Inspector shall return the reinspection data to the Management Planner to be assessed and determine appropriate response actions and a report issued (AHERA Three Year Reinspection report). One copy of the report is delivered to the schools Principal to be permanently retained with all previous environmental data. Another copy is retained in the LEA's Environmental Library.



### School District of Philadelphia Office of Environmental Management & Services 440 North Broad Street Philadelphia, PA 19130 (215) 400-4750

School District of Philadelphia Asbestos Management Program

### TABLE OF CONTENTS

De	finitionsPage 9
1.	IntroductionPage 10
	Summary of Asbestos Management Plan Asbestos Management Plan Execution
4.	Summary of Program Execution a. Asbestos Management Plan Execution
5.	Responsibilities  a. OEMS  b. Asbestos Worker/Supervisor "A-TEAM"
6.	Requirements
7.	AHERA O&M Plan
8.	O&M Response Actions
	9 References and Resources Page 1

### **DEFINITIONS / ACRONYMS**

ACM/PACM: Asbestos Containing Material/Potential Asbestos Containing Material AHERA: Asbestos Hazard Emergency Response Act AIR FORM: **Asbestos Inspection Report Form** Water to which a surfactant (soap) has been added Amended Water: AMP: Asbestos Management Program/Asbestos Management Plan Asbestos Designate Person: Individual assigned by the district to oversee asbestos related issues. Asbestos Regulated Area: Location that is posted as an asbestos work area in which only approved and accredited personnel are permitted to enter AST: Asbestos Support Team involving approved and accredited school district tradespersons personnel that are school district person A-TEAM: School District of Philadelphia asbestos workers CIP: Capital Improvement Program Consultant: Asbestos consulting firm hired by the District **Demolition Directive:** Memorandum - August 4, 2006 from Patrick Henwood EPA: **Environmental Protection Agency** In House Personnel: School District of Philadelphia asbestos workers LEA: **Local Education Agency** 0&M: **Operations and Maintenance OEMS:** Office of Environmental Management and Services **OSHA:** Occupational Safety and Health Administration PEL: Permissible Exposure Limit PSD or SDP: Philadelphia School District/School District of Philadelphia

PSIT:

STEL:

Philadelphia School Improvement Team

### 1. Introduction

The School District of Philadelphia, Asbestos Policy Statement:

"The School District of Philadelphia is dedicated to providing a safe and healthful work environment for its employees, students, faculty, contractors and visitors. In recognition of the potential health problems associated with asbestos, the School District of Philadelphia is committed to a comprehensive asbestos control program. This program is implemented and maintained through the School District of Philadelphia's Office of Environmental Management and Services (OEMS)."

OEMS has the responsibility of establishing procedures for asbestos abatement, asbestos inspection, air monitoring, renovation and demolition activities within all School District of Philadelphia owned or leased facilities.

These procedures are developed to ensure that:

- (1) People are not exposed to significant levels of asbestos fibers
- (2) Asbestos waste is handled and disposed of properly
- (3) Members of the School District of Philadelphia community have access to the Office of Environmental Management and Services for information, assistance, guidance, and interpretation regarding asbestos related matters.
- (4) Members of the School District of Philadelphia community have access to the Asbestos Management Plans as required and outlined in the US EPA AHERA regulations including annual written notification to all parents.
- (5) Compliance with all applicable Federal, State and Local Asbestos Regulations

Requirements outlined in this manual are mandatory in nature where the word "SHALL" is used and are advisory in nature where the word "SHOULD" is used.

### 2. Summary of Asbestos Management Program

The School District of Philadelphia's Asbestos Management Program was established to meet the requirements of Federal, State, and Local Regulations.

These regulations include, but are not limited to:

- US Environmental Protection Agency Asbestos Hazard Emergency Response Act (US EPA AHERA) and National Emissions Standard for Hazardous Air Pollutants subpart M, Part 61 (NESHAP);
- US Department of Labor, Occupational Safety and Health Administration (OSHA) General Industry Standard (29 CFR 1910.1001) and the OSHA Asbestos Standard for the Construction Industry (29 CFR 1926.1101);
- The Commonwealth of Pennsylvania, Department of Labor and Industry, Asbestos Occupations, Accreditation and Certification Act;
- The City of Philadelphia, Department of Public Health, Asbestos Control Regulations.

### 3. Asbestos Management Program Execution

### a) General Execution

The Office of Environmental Management and Services (OEMS) develops, implements and manages safety and health programs for the School District of Philadelphia faculty, staff and students and assists with ensuring that all contractors comply with Federal, State and Local Environmental Regulations. The OEMS provides the oversight of School District of Philadelphia employees (Asbestos A-Team), environmental consultants, and asbestos abatement contractors for all projects within the School District of Philadelphia concerning Asbestos Containing Materials.

The control of safety and health hazards at the School District of Philadelphia is primarily through the implementation of engineering, work practice and administrative controls. Personal Protective Equipment (PPE) is used to supplement these controls or whenever the controls are not feasible or are in the process of being implemented. PPE is also recommended whenever exposures to chemical, physical or biological agents can be prevented or reduced by its use.

This written program establishes the procedures necessary to:

- 1) meet established standards and federal regulations for occupational exposure to asbestos fibers;
- 2) meet the requirements of the City of Philadelphia Asbestos Control Regulations which encompasses the disturbance and/or abatement of asbestos containing building materials;
- 3) provide the necessary health and safety protection to the School District of Philadelphia staff, faculty, students, contractors and visitors.

This program is strengthened by input and cooperation with the Philadelphia Federation of Teachers (PFT), Health and Welfare Fund.

### 4. Summary of Program Execution

### a) Asbestos Management Program Execution

The Asbestos Management Program is administered by the Office of Environmental Management and Services (OEMS). OEMS provides the following services primarily through professional consultants:

- (1) exposure monitoring services;
- (2) building inspection/surveys (bulk sampling) for the identification of asbestos containing materials;
- (3) asbestos project design services;
- (4) asbestos abatement project and air monitoring services;
- (5) emergency response to fiber release episodes;
- (6) education/information;
- (7) medical monitoring;
- (8) training for School District of Philadelphia personnel

### 5. Responsibilities

### a) Office of Environmental Management and Services

OEMS is responsible for performing the following functions:

- (1) Developing and administering of the Asbestos Management Program.
- (2) Providing asbestos-related services to all School District of Philadelphia departments.
- (3) Conducting required training of the Asbestos Management Program and working jointly with departments to schedule training.
- (4) Identifying and posting areas where labeling/signage are required.
- (5) Medical Monitoring of OEMS "A-TEAM" and other departments "AST" Asbestos Program staff.

- (6) Certification and training as required for OEMS "A-TEAM" and other departments "AST" Asbestos program staff.
- (7) Record keeping as outlined in Section 3.5 and all records as by required by US EPA AHERA regulations.

### b) Asbestos Worker/Supervisor - "A-TEAM"

- (1) OEMS shall ensure that all "A-TEAM" workers/supervisors adhere to the following requirements:
  - a) Attend an initial Worker/Supervisor Asbestos Course;
  - b) Maintain the annual re-certification per EPA AHERA requirements and Commonwealth of Pennsylvania Asbestos Occupations, Accreditation and Certifications Act;
  - c) Undergo an annual Asbestos Medical Evaluation;
  - d) Undergo an annual Respirator Medical Clearance;
  - e) Undergo an annual Respirator Fit Testing.

### c) Asbestos Designated Person

The Asbestos Designated Person is responsible for:

- (1) Assuring the health and safety of employees, students and visitors in the School District of Philadelphia facilities under his/her control.
- (2) Being kept informed of all areas under his or her jurisdiction where potential asbestos exposures exist and initiating protection programs that adhere to the Asbestos Management Program requirements of this manual.
- (3) Assuring that Asbestos Management Program requirements are adhered to by principal investigators, project managers, supervisors, or division heads, and School District of Philadelphia personnel under their supervision.
- (4) Ensuring that all employees within the Asbestos Management Program comply with (OSHA 1910.1001 (j) (7) (iv)) and the US EPA AHERA regulations by attending the required training.
- (5) Ensure the posting of:
  - a) Warning labels/signage
  - b) Commonwealth of Pennsylvania Asbestos Abatement and Demolition/Renovation Notification form
  - c) Asbestos Inspection Reports (AIR) form (where required)
  - d) Ensuring that Construction Projects follow the Demolition Directive procedures as outlined in the August 4, 2006 letter.

### d) Supervisor or Project Manager (Capital, Maintenance and Facilities)

Each person in charge of a project, maintenance/repair, renovation/demolition, or other activity from the Departments of Capital, Maintenance, and/or Facilities, where asbestos containing material may be present is responsible for:

Identifying, with the assistance of OEMS, asbestos containing building materials prior to any disturbance of these materials. Various Federal (EPA and OSHA) and Local (City of Philadelphia Asbestos Control Regulations) require Asbestos Inspections prior to renovation/demolition activities. This shall be accomplished by always following the Asbestos Management Program Procedures as follows:

(1) Ensure that the requirements of the Asbestos Management Program Procedures are followed by all personnel, trades, and contractors who are involved with the project;

- (2) Review of the required Asbestos Inspection Report (AIR) form (Attachment 1) and AHERA Management Plan documents prior to activities that may disturb any Asbestos Containing Materials;
- (3) Perform all project related duties as outlined in the Project Management Responsibilities;
- (4) Keep the department chairperson or director informed on any actions proposed or taken regarding the Asbestos Management Plan;
- (5) Ensuring that Construction Projects follow the Demolition Directive procedure outlined in the August 4, 2006 letter.

### e) Employee - Capital

School District of Philadelphia Capital employees and/or consultants shall:

- (1) Ensure that no suspect or asbestos containing building materials are disturbed in the course of the projects they are performing or managing. This shall be accomplished by notifying their supervisor and OEMS by issuance of a work order permit (a.k.a PSIT Service Request Form) and verifying that the materials which may be disturbed are non-asbestos containing. If this information is not available or verification has not been made, these materials should not be disturbed.
- (2) Immediately notify OEMS and their supervisor in the event of a potential fiber release episode upon discovery of visible damage to asbestos containing materials.
- (3) Ensuring that Construction Projects follow the Demolition Directive procedures as outlined in the August 4, 2006 letter.

The types of projects represented as part of the Capital Improvement Program are as follows:

- (1) Complete Renovation of an existing building that addresses all facility component concerns and educational program needs;
- (2) Major Renovation of an existing building addressing significant facility component and educational improvements:
- (3) Addition to an existing building (either as an attachment or stand-alone structure) to accommodate needed program space;
- (4) Conversion of an existing facility to accommodate a change in educational program;
- (5) Facility Component Improvement of specific facility needs (i.e. electrical or HVAC system upgrades, ADA improvements, life safety improvements, exterior renovations, etc.)

### f) Employee – Maintenance

School District of Philadelphia Maintenance employees shall:

- (1) Ensure that no suspect or asbestos containing building materials are disturbed in the course of their duties or work they are performing. This shall be accomplished by notifying their supervisor and OEMS by issuance of a work order permit and verifying that the materials which may be disturbed are non-asbestos containing. If this information is not available or verification has not been made, these materials should not be disturbed.
- (2) Immediately notify OEMS and their supervisor in the event of a potential fiber release episode or upon discovery of visible damage to asbestos containing materials.
- (3) All employees involved in maintenance activities shall attend required Asbestos Awareness training program within 60 days of employment.

### g) Employee – Facilities & Custodial

School District of Philadelphia Facilities and Custodial employees shall:

- (1) Ensure that no suspect or asbestos containing building materials are disturbed in the course of their duties or work they are performing. This shall be accomplished by notifying their supervisor and OEMS by issuance of a work permit and verifying that the materials which may be disturbed are non-asbestos containing. If this information is not available or verification has not been made, these materials should not be disturbed;
- (2) Immediately notify OEMS and their supervisor in the event of a potential fiber release episode or upon discovery of visible damage to asbestos containing materials.
- (3) All employees involved in Facilities and Custodial activities shall attend require Asbestos Awareness training program within 60 days of employment.

### 6. Requirements

### a) Employee Exposure Monitoring

When information indicates that an employee's exposure to asbestos fibers may equal or exceed an 8-hour time-weighted average of 0.1 f/cc \* (per OSHA 1910.1001 & 1926.1101), OEMS shall develop and implement an asbestos exposure monitoring program. The sampling strategy shall be designed to identify employees by work task (job classification) that is exposed to asbestos fibers that exceed an 8-hour time-weighted average of 0.1 f/cc.

### b) Employee Notification

OEMS shall notify in writing, each employee exposed to asbestos fibers at or above an 8-hour time weighted average of 0.1 f/cc.

### c) Observation and Monitoring

OEMS shall provide employees or their representatives with an opportunity to observe any exposure measurements conducted.

### d) Training Program

OEMS shall institute a training program which meets the requirements of AHERA for all employees who perform maintenance operations in a facility/school which contains asbestos containing materials or presumed asbestos containing materials and 1910.1001 (j), and the Commonwealth of Pennsylvania Department of Labor and Industry and the City of Philadelphia Asbestos Control Regulations. The affected departments shall ensure employee participation in this program. The OEMS "A-TEAM" and other departments "AST" Asbestos Program staff training shall be conducted annually for each employee as required by all Federal, State and Local for each asbestos discipline.

All Asbestos Awareness training as required by AHERA shall be performed within 60 days of employment and shall include:

- o Health effects of asbestos
- o Locations of ACM and PACM in the building/facility
- o Recognition of CM and PACM damage and deterioration
- o Requirements of the OSHA 1910.1001 standard relating to maintenance
- o Proper response to fiber release episodes
- o Procedure to be followed to isolate areas affected by fiber release

### e) Access to Information

OEMS shall make available to affected employees or their representative's copies of the Occupational Safety and Health Administration (OSHA) General Industry Standard Part 1910.1001 and the department shall post a copy in the workplace.

### f) Record Keeping

OEMS shall maintain an accurate record of all employee exposure measurements. OEMS and/or the School District of Philadelphia Human Resources Department shall maintain records of employee medical monitoring program. OEMS shall maintain all employee training records. All records shall be provided upon request to employees, former employees, representatives designated by the individual employee.

### 7. AHERA OPERATIONS AND MAINTENANCE PLAN

### a) CONTROLS

### i. Work Order System

Minimizing disruption of ACM/PACM during maintenance and renovation activities is the primary goal and task encountered by OEMS. Operations and maintenance employees and contractors should be warned to avoid conducting any maintenance work which may disturb ACM/PACM. Initiating a work order system, where all work orders or requests are channeled through the Office of Environmental Management and Services (OEMS), will be the method used to control and minimize disruption of ACM/PACM.

Any work performed by in-house personnel or contractors that could or will impact ACM/PACM shall be coordinated by OEMS. A completed Asbestos Inspection Report Form (Attachment 1) shall be issued to in-house personnel and/or all contractors whose work could impact ACM/PACM. This form should accompany each contract issued to an outside contractor and posted on the jobsite.

All work order requests for maintenance and renovation activities in areas where ACM/PACM is suspected or known to be present are to be submitted to OEMS prior to proceeding with work. OEMS is responsible for reviewing asbestos survey records for information about the presence of ACM/PACM in the area where the work is to be performed. OEMS should physically inspect the area to ensure existing records reflect actual conditions. If no asbestos is present, a work order is not necessary and the planned actions can proceed. If ACM/PACM is found to be present in the area, OEMS will sign the work order application and obtain an approved and accredited asbestos contractor or assign OEMS "A-TEAM" to abate the ACM/PACM.

### ii. Regulated Areas

The owner will identify and regulate all areas where airborne concentrations of ACM/PACM exceed the Permissible Exposure Limit (PEL)\* (Per OSHA determined to be 0.1 f/cc) and/or short term exposure limit (STEL) (Per OSHA determined to be 0.1 f/cc), or there is reasonable possibility that the (PEL) and/or (STEL) may be exceeded. All ACM/PACM removal activities involving thermal system insulation ACM/PACM (Class I), surfacing ACM/PACM (Class I), and miscellaneous ACM/PACM such as floor tile, roofing, and siding mastic, etc. (Class II), and repair and maintenance operations where thermal system insulation and surfacing ACM/PACM is likely to be disturbed (Class III) will be performed in accordance with federal, state, and local regulations. All asbestos abatement work and activities will be designed and managed as asbestos regulated areas. These areas will be demarcated and labeled.

### iii. Warning Signs

Warning signs shall be displayed at all approaches to each asbestos regulated area. The asbestos abatement contractor will provide OSHA warning signs in all regulated areas during removal, repair, and other maintenance activities. OEMS will provide AIRs to all contractors who must inform all employees and supervisors working in locations contiguous to asbestos regulated areas of the potential hazards and work practices required.

### iv. Warning Labels

Warning labels and or signage shall be affixed to all raw materials, mixtures, scrap, waste, debris, and other products containing asbestos fibers, or to their containers. Generally, the asbestos abatement contractor or OEMS A-Team personnel will provide all warning labels for ACM/PACM containment.

### 8. O & M RESPONSE ACTIONS

The Asbestos Management Program general O&M procedures are outlined in this section. Additional requirements specific to asbestos abatement activities are included in the Project Design documents for all Asbestos Abatement Work. Regular cleaning, inspection, and reporting of ACM/PACM deterioration or other problems must be diligently practiced by all employees including custodial and maintenance personnel.

### a) Facility Maintenance Isolation of Area Responsibilities

Maintenance personnel are often required to work in areas where ACM/PACM may potentially be disturbed. Most maintenance activities are conducted by in-house staff, outside contractors, or a combination.

Emergency fiber release episodes, such as pipe fitting or valve breaks, emergency boiler work, or mechanical equipment repair will be responded to by OEMS A-Team personnel or asbestos abatement contractor personnel. The owner's maintenance staff will: (1) isolate the emergency fiber release area; (2) post warning signs to prevent unauthorized access, and (3) notify their supervisor and OEMS. OEMS will ensure that the fiber release area remains isolated and is properly cleaned by and approved and accredited abatement contractor or by OEMS A-TEAM personnel.

### b) Unlikely Contact with ACM/PACM

Maintenance activities or repairs which can be performed without contacting or disturbing the ACM/PACM require little more than normal care and good workmanship. For example, valves which are either uncovered or covered with non-asbestos insulation can be packed or repaired without disturbing asbestos insulation on nearby pipes. The major precaution is to ensure that maintenance and custodial personnel are familiar with procedures such as isolating the area, posting warning signs, and notifying OEMS in the event of any accidental ACM/PACM disturbance.

### c) Accidental Disturbance of ACM/PACM

Maintenance and facilities personnel shall notify OEMS any time a fiber release is suspected. If friable ACM/PACM becomes airborne in the building,

### d) Planned Disturbance of ACM/PACM

Maintenance activities that may impact ACM/PACM include access to a valve, flange, duct, or related system component.

Where asbestos-containing insulation must be removed to maintain or repair the thermal system, the ACM/PACM will imminently be disturbed. ACM/PACM removal work shall be conducted by OEMS A-Team personnel or an approved and accredited asbestos abatement contractor.

If friable ACM/PACM becomes airborne in the building, maintenance and facilities personnel shall secure the area and contact OEMS. OEMS shall respond accordingly.

### e) Miscellaneous ACM/PACM

Miscellaneous types of ACM/PACM may include vinyl asbestos floor tiles, mastics/adhesives and woven vibration dampers. Disturbance of these materials should be avoided. Routine maintenance activities involving these materials should not pose a problem if handled properly. Questions on the proper removal and disposal of miscellaneous ACM/PACM should be directed to OEMS. OEMS will contact an approved and accredited asbestos abatement contractor or utilize OEMS A-TEAM personnel to assist with miscellaneous ACM/PACM clean-up activities.

### f) Vinyl Asbestos Floor Tile

Asbestos-containing floor tiles in good condition are considered non-friable unless they are crushed, drilled, sawed, sanded or disturbed by any activity that breaks up the material. Routine maintenance of these materials should employ the use of non-abrasive buffers and wet cleaning technique. Broken or loose floor tiles should be removed and disposed of as asbestos waste by OEMS. Remaining debris should be vacuumed with a HEPA vacuum and the area wet mopped using amended water.

### g) Mastics/Adhesives

Mastics and adhesives containing asbestos in good condition are considered non-friable and do not pose a potential health concern unless crushed, drilled, sawed, sanded, or otherwise abraded. Questions on the proper removal should be directed to OEMS.

### h) Woven Vibration Dampers

Woven vibration dampers in good condition are considered non-friable and do not pose a potential health concern unless cut, crushed, drilled, sawed, sanded, or otherwise abraded. Questions on the proper removal should be directed to OEMS.

### i) Other Work Practices

Any special work not included in this section should be addressed to OEMS for review prior to the initiation of work that may involve the disturbance of ACM/PACM.

### j) Fiber Release Episodes

Facilities and maintenance staff should report to OEMS the presence of asbestos debris, water or physical damage to ACM/PACM, or any other evidence of possible fiber release. OEMS should have the OEMS A-Team personnel or an approved and accredited abatement contractor respond to the site to clean up debris and make repairs as soon as possible. OEMS will also contact a consultant to conduct air monitoring and prepare a report and submit at project completion to OEMS for each episode. OEMS will forward the reports for each site location AHERA Management Plan accordingly.

### 9. REFERENCES and RESOURCES

Applicable regulations for asbestos projects impacted by renovation, demolition, and maintenance activities.

- Philadelphia Air Management Services Asbestos Control Unit
   http://www.phila.gov/health/units/ams/Asbestos/asbestos.html
- Pennsylvania Asbestos Occupations, Accreditation and Certification Act
   http://www.dli.state.pa.us/landi/cwp/view.asp?a=185&q=56262&landiNav=
- United States Environmental Protection Agency Asbestos Home Page http://www.epa.gov/asbestos/
- Occupational Safety and Health Administration (OSHA) Asbestos Home
   http://www.osha.gov/SLTC/asbestos