SCHOOL DISTRICT OF PHILADELPHIA



Asbestos Hazard Emergency Response Act "AHERA"

THREE-YEAR RE-INSPECTION 2015-2016

and ASBESTOS MANAGEMENT PLAN for the

James Dobson Elementary School

ULCS# 6450 Building # B6450001-1 4667 Umbria Street Philadelphia, Pennsylvania 19127 Year Built: 1930

January 2016

Conducted By:

Accredited Environmental Technologies, Incorporated
Batta Environmental Associates, Incorporated
Criterion Laboratories, Incorporated
Environmental Testing Consultants, LLC
G & C Environmental Services, Incorporated
KEM Partners, Incorporated
Synertech, Inc.
TTI Environmental, Inc.
USA Environmental Management, Inc.
The Vertex Companies, Inc.

Management Plan Prepared By: Criterion Labs, Inc and Synertech Inc.

This report must remain in the Main Office as mandated by the US EPA AHERA Regulations.

AHERA THREE-YEAR REINSPECTION VOLUME IX

Table of Contents

Transmittal Letter

Executive Summary

- I. Summary list of Confirmed Asbestos Containing Building Materials
- II. Summary list of Assumed Asbestos Contain Building Materials
- III. Summary list of Non-Asbestos Containing Building Materials
- IV. Summary list of Non Suspect Asbestos Containing Building Materials
- V. Summary List of Auditorium DATA for this location
- VI. Summary list of Attic and/or Crawlspace DATA for this location
- VII. Summary list of Pipe Chase/Pipe Shaft DATA for this location

Section I Report of Re-Inspection

- A. Introduction
- B. Three-Year Re-inspection IX Overview
- C. Post- Management Plan Activities and Changes
 - C.1 Sampling and Analysis
 - C.2 New Floor Tile Sampling
 - C.3 Abatement Activity
 - C.4 Periodic (Six-Month) Surveillance (Damaged Materials)

Section II Re-Inspection Data

- A. Introduction
- B. Re-Inspection Key Definitions
- C. Room by Room Location Log Report

Section III Certificates

A. Management Planner/Building Inspector Certificates

Section IV Cross Reference Table Page 1-8

Asbestos Management Program Page 9-19

SCHOOL DISTRICT OF PHILADELPHIA EDUCATIONAL CENTER

440 NORTH BROAD STREET PHILADELPHIA, PENNSYLVANIA 19130

OFFICE OF ENVIRONMENT AL MANAGEMENT AND SERVICES

PHONE (215)-400-4750

January 2016

TO:

All Principals

All Building Administrators

FROM:

Fran Burns

Chief Operating Officer

Francine Locke, M.S., Director

Office of Environmental Management and Services

SUBJECT: AHERA Three (3) Year Re-inspection IX report

In order to comply with the provisions of the Asbestos Hazard Emergency Response Act (AHERA) the attached report is submitted to you. The law requires that this report be kept in the Main/Principal's office. It cannot be removed from these locations. *If the school (program)* is relocated to a different building, these environmental documents are to be safely retained for the next school/building occupants. All asbestos reports must be available to the public and Federal EPA upon request.

Fran Burns

Chief Operation Officer

Francine Locke, M.S., Director

Office of Environmental Management

and Services

AHERA-2d Revised 12/14/15

Executive Summary

This Asbestos Hazard Emergency Response Act (AHERA) Three-Year Re-inspection "Volume # IX" Management Plan at this location, has been completed and the report of re-inspection submitted to the School District of Philadelphia. The re-inspections in all School District of Philadelphia buildings of 2015-2016 were conducted and completed between October 5th, 2015 through March 30th, 2016 as a joint project by Accredited Environmental Technologies, Inc., Batta Environmental Associates, Inc., Criterion Laboratories, Inc., Environmental Testing Consultants, LLC, G & C Environmental Services, Inc., KEM Partners, Inc., Synertech, Inc., TTI Environmental, Inc., USA Environmental Management, Inc. and The Vertex Companies, Inc.

In general, the School District of Philadelphia Office of Environmental Management and Services conducts Environmental Impact Evaluations and provides Asbestos Inspection Reports prior to any renovation, demolition and/or maintenance activities. The AHERA report must be reviewed prior to any renovation, demolition and/or maintenance activities in order to avoid the unknowing disturbance to Asbestos Containing Building Materials identified within this location. In addition, prior to work activities above all drop ceilings this report should be reviewed to avoid potential disturbances to Asbestos Containing Materials. Refer to Section IV of the Cross Reference Table, for additional Asbestos Management Program information. Contact the Office of Environmental Management and Services to have an Environmental Impact Evaluation conducted prior to any renovation, demolition and/or maintenance activities within this facility.

The information contained in this report was obtained from the original Asbestos Management Plan for the school, from update reports on changes and activities since the completion of the 1st Management Plan for each location and from all prior inspections performed and documented in Volume # I through Volume VIII (dated respectively 1992, 1995, 1998, 2001, 2004, 2007, 2010 or 2013) (if applicable) - and by this Three-Year Re-inspection of this school. The re-inspection report/Management Plan of 2015-2016 were reviewed and prepared collectively by Management Planner Megan Vala, Mary Anne Lerro of Criterion Laboratories, Inc. and/or Monique Causley, of Synertech Inc.

The 2015-2016 inspection process included the addition of a comprehensive Room by Room Inventory of all Thermal (T), Surfacing (S) and Miscellaneous (M) Materials specific to each room of this facility. Inspections of each room's thermal, ceilings, walls, floors and miscellaneous items regardless of Asbestos Content are categorized on the Room by Room Location Log Report for this location. Rooms or areas of the facility that were not accessible at the time of the inspection are marked with an "X". The Room by Room Location Log Report is found in Section II C of this Management Plan.

All Presumed or Suspect Asbestos Containing Building Materials (ACBMs), listed in the following summary charts are categorized as Confirmed, Assumed, Non-Asbestos, and/or Non-Suspect (ACBMs) were identified in the original Management Plan, or in the Volume I through Volume VIII AHERA Three-Year Re-inspection reports, and were re-inspected as part of this project.

As mandated by the U S EPA AHERA regulations, periodic Six-Month inspections and Three-Year Re-inspections of this location will be performed and the Inspection Data in this report will be updated accordingly.

Please feel free to contact the School District of Philadelphia's Office of Environmental Management and Services (OEMS) regarding any comments, questions, or concerns regarding this report or any Environmental related topic. OEMS staff can be reached at (215) 400 4750, via fax at (215) 400 4751 or via e-mail at flocke@philasd.org and/or gfjunod@philasd.org.

Additional information can be found on our website. Here is the link to the OEMS website. http://webgui.phila.k12.pa.us/offices/e/environmental

I. Summary list of Confirmed Asbestos Containing Building Materials within this facility

These charts are to be used for a quick reference* in order to avoid the unknowing disturbance of Asbestos Containing Materials during any and all Operations, Maintenance, Renovation, and/or Demolition activities at this location. These materials have been sampled and Laboratory Analysis has CONFIRMED the presence of Asbestos. Contact OEMS prior to the disturbance of any of the following materials.

Confirmed Asbestos Containing Building Materials for this location

Floor Tile VAT 9" x 9"	Pipe Fitting Insulation	Pipe Insulation > 6 inch
Pipe Insulation 2-6 inch	Transite	Transite Electrical Panel

^{*} Always refer to the Room by Room Logs for each specific material classification as the material classification findings may be different in various rooms throughout this facility.

^{**} Some Materials may have multiple classifications (Confirmed, Assumed, NAD and Non Suspect) within this facility.

II. Summary list of Assumed Asbestos Containing Building Materials within this facility

These charts are to be used for a quick reference* in order to avoid the unknowing disturbance of Asbestos Containing Materials during any and all Operations, Maintenance, Renovation, and/or Demolition activities at this location. These materials have not been sampled and should not be disturbed until verification of Asbestos Content. Contact OEMS for assessment and sampling prior to the disturbance of these materials.

Assumed Asbestos Containing Building Materials for this location

Blackboard Glue Dots	Ceiling Tile 2' x 2'	Emergency Generator Insulation
Fire Doors	Floor Tile VAT 12" x 12"	Linoleum
Pipe Insulation > 6 inch	Radiator Insulation	Sheetrock Wall
Sink Undercoat Mastic	Vibration Damper Cloth	Wire Wrap Insulation

^{*} Always refer to the Room by Room Logs for each specific material classification as the material classification findings may be different in various rooms throughout this facility.

^{**} Some Materials may have multiple classifications (Confirmed, Assumed, NAD and Non Suspect) within this facility.

III. Summary list of Non-Asbestos Containing Building Materials within this facility

These charts are to be used for a quick reference* in order to avoid the unknowing disturbance of Asbestos Containing Materials during any and all Operations, Maintenance, Renovation, and/or Demolition activities at this location. These materials have been sampled and Laboratory Analysis has indicated NO Asbestos present or NO ASBESTOS DETECTED (NAD).

Non- Asbestos Containing Building Materials for this location

Pipe Fitting Insulation	Plaster Ceiling	Plaster Walls

^{*} Always refer to the Room by Room Logs for each specific material classification as the material classification findings may be different in various rooms throughout this facility.

^{**} Some Materials may have multiple classifications (Confirmed, Assumed, NAD and Non Suspect) within this facility.

IV. Summary list of Non-Suspect Asbestos Containing Building Materials within this facility

These charts are to be used for a quick reference* in order to avoid the unknowing disturbance of Asbestos Containing Materials during any and all Operations, Maintenance, Renovation, and/or Demolition activities at this location. These materials are not typically known to contain Asbestos.

Non-Suspect Asbestos Containing Building Materials for this location

Brick Wall	Carpet	Ceiling Tile 1' x 1'
Ceiling Tile 2' x 4'	Cement Floor	Ceramic Tile Floors
Ceramic Tile Walls	Concrete Block Wall	Concrete Ceiling
Concrete Wall	Fiberglass Ceiling Tile 2' x 4'	Fiberglass Pipe Insulation
Fiberglass Tank Insulation	Marble Floor	Marble Wall
Marble Wall	Metal Boiler Breeching	Partition Room Dividers
Vinyl Vibration Damper Cloth	Wood Ceiling	

^{*} Always refer to the Room by Room Logs for each specific material classification as the material classification findings may be different in various rooms throughout this facility.

^{**} Some Materials may have multiple classifications (Confirmed, Assumed, NAD and Non Suspect) within this facility.

V. Summary list of Auditorium DATA for this location

These charts are to be used for a quick reference of the Auditorium DATA within this facility. Sampling of the Auditorium Ceilings throughout the District is more difficult because of the various ceiling heights. As sampling occurs this information is updated on a case by case basis for each specific location and facility.

Summary list of materials for this location's Auditorium

	Auditorium	
Auditorium	Plaster Ceiling	NAD
Auditorium	Plaster Walls	NAD
Auditorium	Wood Walls	Non Suspect ACM
Auditorium	Wood Floor	Non Suspect ACM
Auditorium	Radiator Insulation	Assumed
Auditorium Stage	Plaster Ceiling	NAD
Auditorium Stage	Plaster Walls	NAD
Auditorium Stage	Wood Floor	Non Suspect ACM

^{*} Always refer to the Room by Room Logs for each specific material classification as the material classification findings may be different in various rooms throughout this facility.

^{**} Some Materials may have multiple classifications (Confirmed, Assumed, NAD and Non Suspect) within this facility.

VI. Summary list of Attic and/or Crawlspace DATA for this location

These charts are to be used for a quick reference regarding the Attics and/or Crawlspaces inspection DATA within this facility. Contact OEMS prior to entering any attic or crawlspace within this facility and refer to the below chart and legend for Category Rank determination. The Data relative to these spaces is updated as conditions change regarding Abatement or Renovation activity on a case by case basis for each specific location and facility. In general, Crawlspaces are below the basement or 1st floor and Attics are above the floor space.

Category Rank Legend

- "A" No Asbestos Containing Materials Sample Results indicate NO ACM on pipes, fittings, elbows, or equipment located within this functional space, and NO VISIBLE DEBRIS or DAMAGE observed at time of this inspection.
- "B" Asbestos Containing Materials Exist Sample Results indicate ACM on pipes, fittings, elbows, or equipment located within this functional space, HOWEVER, NO VISIBLE DEBRIS or DAMAGE observed at time of this inspection.
- "C" Asbestos Containing Materials Exist Sample Results indicate ACM on pipes, fittings, elbows, or equipment located within this functional space, and LOCALIZED VISIBLE DEBRIS or DAMAGE observed at time of this inspection.
- "D" Asbestos Containing Materials Exist Sample Results indicate ACM on pipes, fittings, elbows, or equipment located within this functional space and DISTRIBUTED VISIBLE DEBRIS or SIGNIFICANT DAMAGE observed at time of this inspection.
- "E" No Bulk Sample Results Available SUSPECT ACM OBSERVED. Contact OEMS immediately for additional instructions.


Attic/Crawlspace	Access Area	Floor Surface	Category Rank	Comments
Attic	Third Floor Corridor	Dirt / Sand	В	Air Cell, Hard Fittings
				Dressing room, stage left; All
Attic	Auditorium	Wire Lathe	A	asbestos removed July 2010
Crawlspace	Basement Hallway	Wire Lathe	В	Air Cell, Hard Fittings

VII. Summary list of Pipe Chase/Pipe Shaft DATA for this location

These charts are to be used for a quick reference regarding the information known about the Pipe Chases and/or Pipe Shafts inspection DATA within this facility. Contact OEMS prior to performing renovation activities any Pipe Chase and/or Pipe Shaft within this facility and refer to the below chart and legend for Asbestos Content of various materials identified within each space. The Data relative to these spaces is updated as conditions change regarding Inspection, Abatement and/or Renovation activity on a case by case basis for each specific location and facility. In general, Pipe Chases are horizontal spaces and Pipe Shafts are vertical spaces.

Element	H			Confirmed Assumed NAD Non	Amount	Amount		
lent	Floor	On Site Room Name	Material Description	Suspect ACM	Materia l	of Damage	Color	Comments
			Fiberglass			9		
		3rd Floor Boy's	Pipe	Non Suspect				
1	3	Restroom Pipe Chase	Insulation	ACM	30 LF	0	X	
		3rd Floor Girl's	Fiberglass Pipe					
1	3	Restroom Pipe Shaft	Insulation	Confirmed	15 LF	0	X	
		3rd Floor Girl's	Concrete					
1	3	Restroom Pipe Shaft	Ceiling	Confirmed	15 SF	0	X	
		3rd Floor Girl's	Concrete	Non Suspect				
1	3	Restroom Pipe Chase	Block Wall	ACM	7 SF	0	X	
		2nd Floor Boy's						
1	2	Restroom Pipe Chase	Cement Floor	Confirmed	1 SF	0	X	
			Fiberglass					
		2nd Floor Boy's	Pipe	Non Suspect				
1	2	Restroom Pipe Chase	Insulation	ACM	95 LF	0	X	
		2nd Floor Girl's	Concrete					
1	2	Restroom Pipe Shaft	Ceiling	Confirmed	15 SF	0	X	
١.		2nd Floor Girl's	Concrete					
1	2	Restroom Pipe Shaft	Block Wall	Assumed	15 SF	0	X	
1		2nd Floor Girl's	Communication	Non Suspect		_		
1	2	Restroom Pipe Chase	Cement Floor	ACM	25 SF	0	X	
		Classroom 101 Girl's	Fiberglass Pipe					
1	1	Restroom Pipe Chase	Insulation		_	v	X	No access
1	Н	Resulvoin i ipe chase	Fiberglass	X	X	Х	Λ	140 access
		1st Floor Boy's	Pipe	Nam Comment				
1	1	Restroom Pipe Chase	Insulation	Non Suspect ACM	75 LF	5 LF	X	
		Classroom 106		710111	701	0 11		
		Laundry Room Pipe	Pipe Fitting					
1	1	Chase	Insulation	Assumed	110 EA	0	X	
			Fiberglass					
		1st Floor Girl's	Pipe					
1	1	Restroom Pipe Shaft	Insulation	Confirmed	15 LF	0	X	

				Confirmed Assumed				
E				NAD				
Element	Ħ			Non	Amount	Amount		
nei	Floor	On Site Room	Material	Suspect	of	of		
nt	r	Name	Description	ACM	Material	Damage	Color	Comments
		1st Floor Girl's	Pipe Insulation					
1	1	Restroom Pipe Shaft	> 6 inch	Assumed	15 LF	0	X	
		1st Floor Girl's	Fiberglass Pipe	Non Suspect				
1	1	Restroom Pipe Chase	Insulation	ACM	25 LF	5 LF	X	
		Basement Boy's	Fiberglass Pipe	Non Suspect				
1	В	Restroom Pipe Chase	Insulation	ACM	30 LF	0	X	
		Basement Boy's	Concrete	Non Suspect				
1	В	Restroom Pipe Chase	Ceiling	ACM	100 SF	0	X	
		Basement Boy's		Non Suspect				
1	В	Restroom Pipe Chase	Brick Wall	ACM	440 SF	0	X	
		Basement Boy's	Concrete Block	Non Suspect				
1	В	Restroom Pipe Chase	Wall	ACM	440 SF	0	X	
		Basement Boy's		Non Suspect				
1	В	Restroom Pipe Chase	Cement Floor	ACM	100 SF	0	X	
		Basement Girl's						
		Restroom Pipe Chase	Fiberglass Pipe	Non Suspect				
1	В	by Entrance	Insulation	ACM	12 LF	0	X	
		Basement Girl's						
		Restroom Pipe Chase	Concrete	Non Suspect		_		
1	В	by Entrance	Ceiling	ACM	36 SF	0	X	
		Basement Girl's						
		Restroom Pipe Chase	D : 1 W 1	Non Suspect	400 GE			
_ 1	В	by Entrance	Brick Wall	ACM	480 SF	0	X	
		Basement Girl's		N. G				
		Restroom Pipe Chase	Comment El	Non Suspect	26.05	0		
1	В	by Entrance	Cement Floor	ACM	36 SF	0	X	
		Basement Girl's	Eileandean Dire	Nan Caran				
1	ת	Restroom Pipe Chase	Fiberglass Pipe	Non Suspect	20.1.5	0		
1	В	on Far Wall	Insulation	ACM	30 LF	0	X	
		Basement Girl's	Vinyl Vihactica	Non Cumast				
1	В	Restroom Pipe Chase on Far Wall	Vinyl Vibration Damper Cloth	Non Suspect ACM	15 SF	0	37	
1	D	on rai wan	Damper Cloth	ACIVI	12.21	U	X	



Section I - A

Report of Re-inspection

Introduction

The Three-Year Re-inspection IX was performed to fulfill the requirements of 40 CFR Part 763 - the Asbestos Hazard Emergency Response Act (AHERA). As required by AHERA, each Local Education Agency (LEA) must re-inspect all known confirmed or assumed Asbestos Containing Building Material (ACBM) located in the LEA's facilities. This re-inspection is intended to update the original Asbestos Management Plan for the LEA's facilities.

Multiple Building Inspectors of several firms performed the 2015/2016 re-inspection. The reinspection report/Management Plan of 2015-2016 were reviewed and prepared collectively by Management Planner Megan Vala, Mary Anne Lerro of Criterion Laboratories, Inc. and Monique Causley, of Synertech Inc.

All of the certificates can be found in Section III.

During the re-inspection of each School District of Philadelphia facility, all of the Management Plans for that facility were reviewed. Information from the conclusions section of that report is included in this report. Additionally, information on activities such as abatements, cleanings, sampling and inspections, which have taken place since the completion of the original Management Plan, were reviewed during the re-inspection. Information on those activities is included in this report.

As mandated by the U S EPA AHERA regulations, all future periodic Six-Month inspections and Three-Year Re-inspections of this location will be performed and the Inspection Data in this report will be updated accordingly.

Section I - B

Three-Year Re-inspection IX Overview

Each homogeneous area of Asbestos Containing Building Material (ACBM) listed in the original Management Plan or in the 1992, 1995, 1998, 2001, etc., Three-Year Reinspection reports were inspected for the AHERA Three-Year Re-inspection Volume IX, and the information for that material verified. Any changes to a homogeneous area listed in the updates to the Management Plans were verified. Any area of suspected ACBM found in the course of the re-inspection, and not listed in the Management Plan or updates, were either assumed to contain asbestos or sampled and analyzed to determine their asbestos content. Any such new areas either assumed to contain asbestos or determined through analysis to contain asbestos were included in the report of the Three-Year Re-inspection. The results of the AHERA Three-Year Re-inspection IX are tabulated in the Room by Room log reports located in Section II-C of this report.

As previously noted, all future periodic Six-Month inspections and Three-Year Reinspections of this location will be performed and the Inspection Data in this report will be updated accordingly.

Section I - C.1

Post Management Plan Activities/Changes

Information on activities affecting Asbestos Containing Building Materials (ACBMs) at this location is contained in updates to the Management Plan. These updates are kept on file by the School District of Philadelphia and were reviewed for this project. Updates to the Management Plan include the following: *Sampling and Analysis, New Tile Installation, Abatement Activity and Periodic Six-Month Surveillance Data.*

Sampling and Analysis

Date	Floor	Room Type	Location	Material	Color	Results
5/16/2016	Basement	Small Cafeteria	Basement (Space # 002)	Plaster Ceiling (Skim Coat)	White	NAD

Section I - C.2

Information on the installation of new floor tiles/renovation activities affecting Asbestos Containing Building Materials (ACBMs) at this location is contained in updates to the Management Plan. These updates are kept on file by the School District of Philadelphia and were reviewed for this project. Updates to the Management Plan include the following:

New Floor Tile Sampling

In the event that new tile is installed, the material must be tested prior to installation.

Section I – C.3

Information on the Asbestos Abatement and renovation activities affecting Asbestos Containing Building Materials (ACBMs) at this location is contained in updates to the Management Plan. These updates are kept on file by the School District of Philadelphia and were reviewed for this project. Updates to the Management Plan include the following:

Abatement Activity


In the event Abatement occurs, data will be listed here.

Section I - C.4

Information on the AHERA inspection that noted damage to various Building Materials at this location is contained in updates to the Management Plan. These updates are kept on file by the School District of Philadelphia and were reviewed for this project. Work orders are created for Corrective Action responses and tracked for completion. Updates to the Management Plan include the following:

Periodic (Six-Month) Surveillance (Damaged Materials)

					Amount	Amount
Date	Element	Floor	On Site Room Name	Material	of Material	of Damage
7/12/2016	1	3	Teacher Lounge	Linoleum	380 SF	2 SF
7/12/2016	1	3	Classroom 307 Center Closet	Floor Tile VAT 12" x 12"	48 SF	1 SF
7/12/2016	1	2	Counselor's Office 210	Pipe Insulation 2-6 inch	48 LF	1 LF
7/12/2016	1	2	Counselor's Office 210	Floor Tile VAT 12" x 12"	252 SF	1 SF
			Auditorium Storage Room to Right of			
7/12/2016	1	1	Stage	Floor Tile VAT 12" x 12"	60 SF	1 SF
7/12/2016	1	В	Fan Room	Pipe Insulation 2-6 inch	350 LF	2 LF
7/12/2016	1	В	Fan Room	Vibration Damper Cloth	20 SF	2 SF
7/12/2016	1	В	Gym	Pipe Fitting Insulation	108 EA	1 EA
7/12/2016	1	В	Gym	Pipe Insulation 2-6 inch	335 LF	4 LF
			Hallway outside Basement Girl's			
7/12/2016	1	В	Restroom	Pipe Fitting Insulation	31 EA	2 EA



Section II - A

Re-inspection Data

Introduction

The following information documents the Three-Year Re-inspection IX of the subject school/facility. The Homogeneous Area Reports were produced using the building inspector's field data on the facility. The key to the Homogeneous Area Report is outlined in the following pages of this report.

Section II - B (page 1 of 4)

SCHOOL DISTRICT OF PHILADELPHIA AHERA THREE YEAR RE-INSPECTION IX

ITEM	DEFINITION		
ULCS#	Individual identification number assigned to each school within the School District of Philadelphia.		
HOMOGENEOUS AREA ID#	Identification number assigned to each homogeneous area in a school/facility. Each section of the homogeneous area ID is significant.		
	1010/01/01/01 A B C D		
	 A. Is the ULCS# for the school. B. Designates the specific building/building area within the school. C. Designates the floor or level within the building/building area. D. Designates the homogeneous material within that floor or level. Note: Item D may be a number or a letter. 		
SYSTEM AFFECTED	Corresponds to the AHERA system for classifying materials.		
AFFECIED	 T : Thermal System S : Surfacing System M : Miscellaneous 		
ITEM AFFECTED	Is a description of the homogeneous material.		
ORIGINAL INSPECTION DATA	This section contains the information found in the original Management Plan (1988-1989).		
AMOUNT OF MATERIAL/ UNIT	Quantity of material, and measuring unit. Units include: Square Feet (SF) Each (EA) Linear Feet (LF) Cubic Feet (CF).		

SCHOOL DISTRICT OF PHILADELPHIA AHERA THREE YEAR RE-INSPECTION IX

RE-INSPECTION FORM KEY

ITEM D	EFINITION
--------	------------------

CND Corresponds to AHERA condition rating for materials.

Condition

0 : No Damage1 : Damage

2 : Significant Damage

DP

Corresponds to the AHERA material assessment system.

Damage Potential

1 : Potential for Damage

2 : Potential for Significant Damage

ASMD Assumed Asbestos This means that a material was not sampled for asbestos content during the original Management Plan inspection.

RA

This corresponds to the AHERA system of response action rating for materials.

Response Action

Establish O&M Program

2 : Repair and Establish O&M Program

3 : Enclose 4 : Encapsulate 5 : Remove

6 : Partial Removal and Establish O&M Program

CHANGES

This section describes changes to the homogeneous material in the twenty-four years since the original AHERA inspection. The abbreviations are defined below.

Removed **RMVD** : **ENCL** Enclosed **ENCP** Encapsulated **DMGD** Damaged **SMPLD** Sampled Material MTRL **RPRD** Repaired None Located N/L **RPLCD** Replaced

SCHOOL DISTRICT OF PHILADELPHIA AHERA THREE-YEAR RE-INSPECTION IX

RE-INSPECTION FORM KEY

ITEM DEFINITION

THREE YEAR RE-INSPECTION

This section contains the information obtained from the Three-Year Re-inspection IX. With three exceptions, the information categories are identical in format and meaning to those found in the original inspection data section. The three exceptions are defined below.

DMGD AMT Amount Damaged

This section gives the quantity of damaged material in a

homogeneous area. The quantity is shown in the same format as the

amount of material/unit section.

NF

Newly Friable

This section identifies materials in the original Management Plan

which have since become friable.

RA

Response Action

This rating is based on the AHERA regulations, and is comparable

to the RA rating found in the "Original Inspection Data" section. The following table details the response actions.

- 1. Establish O&M Program
- 2. Repair and Establish O&M Program
- **3.** Enclose
- **4.** Encapsulate
- **5.** Remove
- **6.** Partial Removal and Establish O&M Program

a. High Priority Response

The homogeneous material has been scheduled for abatement or other response action.

b. Medium Priority Response

The homogeneous material will be scheduled for abatement or other response action as soon as the high priority responses have been addressed.

c. Low Priority Response

The homogeneous material will be scheduled for abatement or other response action as soon as the medium priority responses have been addressed.

d. On-Going Response/Operations and Maintenance

The homogeneous material does not require abatement or other response action at present, and should be included in the facility's on-going operations and maintenance program.

SCHOOL DISTRICT OF PHILADELPHIA AHERA THREE-YEAR RE-INSPECTION IX

RE-INSPECTION FORM KEY

The information presented in the changes section has been compiled from a variety of sources, including the Re-inspection and the following:

- * Quality Control/Quality Assurance Reports of asbestos abatement projects, prepared by consultants to the School District.
- * Permit and Notification Forms for asbestos abatement projects.
- * Periodic Surveillance Forms
- * Operations and Maintenance activities performed by School District personnel.
- * Verbal information from School District personnel.
- * Reports of sampling and analysis of suspected materials by both School District personnel and outside consultants.

ROOM BY ROOM LOCATION LOG REPORT This section gives information, including damage amount and location, for a specific homogeneous material on a room-by-room basis and follows the Re-inspection form.

NOTE: The disparate nature of the above sources of information prohibits the verification of much information within the scope of the AHERA Three-Year Re-inspection. Discrepancies and omissions may exist in this information, and therefore is included on an "as is" basis. The inspectors for the Three-Year Re-inspection IX evaluated homogeneous areas based on the materials current condition and location, as evidenced during the inspector's site visit.

Section II - C

Room by Room Location Log Report

These charts are to be used for a quick reference* in order to avoid the unknowing disturbance of Asbestos Containing Materials during any and all Operations, Maintenance, Renovation, and/or Demolition activities at this location.

NOTE:

Contact OEMS prior to the disturbance of any of the materials that are listed as **Confirmed and/or Assumed**.

The quantities listed for (NAD) non-asbestos containing materials and/or Non-Suspect Materials are only estimated and were not measured for the purpose of this report. Field verification of quantities for renovation purposes would be necessary.

	School District of Philadelphia		ļ	AHERA Three-Year	Reinspection 2015-2016	i					Reinspection Date: 1/22-29/2016				
ı	James Dobson Elementary School	1			Location Log Report			l			Building Inspector: Bernard Brunner	1			I
1	4667 Umbria Street, Philadelphia, PA 19127	1						1			Certificate Number: 45397	1			1
	·											†			1
1	ULCS# 6450										Management Planner: Monique Causley	+			1
-	Year Built: 1930					1					Certificate Number: ACC-0215-8-010				
E															1
11	_														1
	F														1
e	o								l	Color		Attic Crawl	Damage		1
n t	o r On Site Room Name	System Affected	Material Description	HID#	Confirmed, Assumed, NAD, Non Suspect ACM	Amount of Material	SF LF EA	Amount of Damage	SF LF EA	required for VAT	Comments/Description/Notes	Space Ranking	Potential (DP)	Newly Friable (NF)	Response Action (RA)
	3 IMC	N/A	Ceiling Tile 2' x 4'		Non Suspect ACM	1145	SF	16	SF				N/A	N/A	N/A
	3 IMC	N/A	Plaster Ceiling		NAD	1145	SF	0	SF				1	No	1/D
1	3 IMC 3 IMC	N/A M	Plaster Walls	6450/01/03/AET/BB/2100	NAD Assumed	1390	SF SF	0	SF				1	No	1/D
	3 IMC	N/A	Sheetrock Wall Wood Floor	6450/01/03/AE1/BB/2100	Non Suspect ACM	245 1145	SF	0	SF SF				1	No No	1/D 1/D
	3 IMC	M	Linoleum	6450/1/03/BB	Assumed	1145	SF	0	SF				1	No	1/D
1	3 IMC	T	Transite Electrical Panel	6450/01/03/23	Confirmed	25	SF	0	SF				1	No	1/D
1	3 IMC Reading Room	N/A	Ceiling Tile 2' x 4'		Non Suspect ACM	265	SF	0	SF				1	No	1/D
1	3 IMC Reading Room	N/A	Plaster Ceiling		NAD	265	SF	0	SF				1	No	1/D
1	3 IMC Reading Room	N/A	Plaster Walls	6450/01/03/AET/BB/2100	NAD	510	SF SF	0	SF			-	1	No No	1/D
1	3 IMC Reading Room 3 IMC Reading Room	M N/A	Sheetrock Wall Wood Floor	0400/01/03/AE1/BB/2100	Assumed Non Suspect ACM	245 265	SF SF	0	SF SF				1	No No	1/D
1	3 IMC Reading Room	M	Linoleum	6450/1/03/BB	Assumed	265	SF	0	SF				1	No	1/D
1	3 IMC Reading Room Large Closet	N/A	Ceiling Tile 2' x 4'		Non Suspect ACM	110	SF	0	SF				1	No	1/D
1	3 IMC Reading Room Large Closet	N/A	Plaster Ceiling		NAD	110	SF	0 30	SF				1	No	1/D
	3 IMC Reading Room Large Closet 3 IMC Reading Room Large Closet	N/A N/A	Plaster Walls Wood Floor		NAD Non Suspect ACM	530 110	SF SF	30	SF SF				N/A 1	N/A No	N/A 1/D
1	3 IMC Reading Room Large Closet	M	Linoleum	6450/1/03/BB	Assumed	110	SF	0	SF				1	No	1/D
1	3 IMC Reading Room Large Closet	N/A	Carpet		Non Suspect ACM	110	SF	0	SF				1	No	1/D
1	3 IMC Reading Room Small Closet	N/A	Plaster Ceiling		NAD	30	SF	0	SF				1	No	1/D
	3 IMC Reading Room Small Closet	N/A	Plaster Walls	0.450.04.004.00	NAD	180	SF	0	SF	D: 1			1	No	1/D
1	3 IMC Reading Room Small Closet 3 IMC Reading Room Small Closet	M N/A	Floor Tile VAT 12" x 12" Wood Floor	6450/01/03/GG	Assumed Non Suspect ACM	30 30	SF SF	0	SF SF	Pink			1	No No	1/D 1/D
	3 Custodial Closet adjacent to 3rd Floor Boy's Restroom	N/A	Plaster Ceiling		NAD	20	SF	0	SF				1	No	1/D
1	3 Custodial Closet adjacent to 3rd Floor Boy's Restroom	N/A	Plaster Walls		NAD	180	SF	0	SF				1	No	1/D
	3 Custodial Closet adjacent to 3rd Floor Boy's Restroom	N/A	Ceramic Tile Walls		Non Suspect ACM	180	SF	0	SF				1	No	1/D
1	3 Custodial Closet adjacent to 3rd Floor Boy's Restroom 3 3rd Floor Boy's Restroom	N/A N/A	Ceramic Tile Floors Plaster Ceiling		Non Suspect ACM NAD	20 160	SF SF	0	SF SF				1	No No	1/D 1/D
1	3 3rd Floor Boy's Restroom	N/A	Plaster Walls		NAD	625	SF	0	SF				1	No	1/D
1	3 3rd Floor Boy's Restroom	N/A	Ceramic Tile Walls		Non Suspect ACM	625	SF	0	SF				1	No	1/D
1	3 3rd Floor Boy's Restroom	N/A	Ceramic Tile Floors		Non Suspect ACM	160	SF	0	SF				1	No	1/D
1	3 3rd Floor Boy's Restroom Pipe Chase	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	30	LF	0	LF		Classrooms 303 and 304 are now one classroom		1	No	1/D
1	3 Classroom 303/304	N/A	Ceiling Tile 2' x 4'		Non Suspect ACM	485	SF	0	SF		with 2 closets. Quantities are still separated.		1	No	1/D
	3 Classroom 303/304	N/A	Plaster Ceiling		NAD	485	SF	0	SF				1	No	1/D
1	3 Classroom 303/304 3 Classroom 303/304	N/A M	Plaster Walls Sheetrock Wall	6450/01/03/AET/BB/2100	NAD Assumed	485 245	SF SF	0	SF SF				1	No No	1/D 1/D
	3 Classroom 303/304 3 Classroom 303/304	T	Transite	6450/01/03/AE1/BB/2100	Confirmed	55	SF	0	SF		Lab tabletops		1	No	1/D
	3 Classroom 303/304	N/A	Wood Floor		Non Suspect ACM	485	SF	0	SF				1	No	1/D
1	3 Classroom 303/304	М	Sink Undercoat Mastic	6450/01/03/AET/BB/2602	Assumed	8	SF	0	SF	White	White		1	No	1/D
1	3 Classroom 303/304 3 Classroom 303/304	N/A N/A	Ceiling Tile 2' x 4' Plaster Ceiling		Non Suspect ACM NAD	485 485	SF SF	8	SF SF				N/A 1	N/A No	N/A 1/D
	3 Classroom 303/304 3 Classroom 303/304	N/A N/A	Plaster Ceiling Plaster Walls		NAD NAD	485 485	SF	n	SF				1	No No	1/D
1	3 Classroom 303/304	М	Sheetrock Wall	6450/01/03/AET/BB/2100	Assumed	245	SF	Ö	SF				1	No	1/D
1	3 Classroom 303/304	N/A	Wood Floor		Non Suspect ACM	485	SF	0	SF				1	No	1/D
1	3 Classroom 303 Closet 3 Classroom 303 Closet	N/A N/A	Ceiling Tile 2' x 4' Plaster Ceiling		Non Suspect ACM NAD	265 265	SF SF	8	SF SF				N/A 1	N/A No	N/A 1/D
	3 Classroom 303 Closet 3 Classroom 303 Closet	N/A N/A	Plaster Ceiling Plaster Walls		NAD NAD	510	SF	0	SF				1	No	1/D
	3 Classroom 303 Closet	M	Sheetrock Wall	6450/01/03/AET/BB/2100	Assumed	245	SF	Ö	SF				1	No	1/D
1	3 Classroom 303 Closet	M	Floor Tile VAT 12" x 12"	6450/01/03/GG	Assumed	265	SF	0	SF	Tan			1	No	1/D
1	3 Classroom 303 Closet	N/A N/A	Wood Floor		Non Suspect ACM	265	SF SF	0	SF SF				1	No	1/D 1/D
1	3 Classroom 303 Closet 3 Classroom 304 Closet	N/A N/A	Vinyl Vibration Damper Cloth Ceiling Tile 2' x 4'		Non Suspect ACM Non Suspect ACM	3 265	SF	0	SF				1	No No	1/D
	3 Classroom 304 Closet	N/A	Plaster Ceiling		NAD NAD	265	SF	0	SF				1	No	1/D
1	3 Classroom 304 Closet	N/A	Plaster Walls		NAD	510	SF	0	SF				1	No	1/D
	3 Classroom 304 Closet	M	Sheetrock Wall	6450/01/03/AET/BB/2100	Assumed	245	SF	0	SF	-			1	No	1/D
1 1	3 Classroom 304 Closet 3 Classroom 304 Closet	M N/A	Floor Tile VAT 12" x 12" Wood Floor	6450/01/03/GG	Assumed Non Suspect ACM	265 265	SF SF	0	SF SF	Tan			1	No No	1/D 1/D
1	3 Teacher Lounge	T	Pipe Insulation 2-6 inch	6450/01/03/22	Confirmed	24	LF	0	LF		More likely above ceiling tile		1	No	1/D
1	3 Teacher Lounge	N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	380	SF	32	SF		, <u>,</u>		N/A	N/A	N/A
	3 Teacher Lounge	N/A	Plaster Ceiling		NAD	380	SF	0	SF				1	No	1/D
1	3 Teacher Lounge 3 Teacher Lounge	N/A N/A	Plaster Walls		NAD Non Suspect ACM	780 380	SF SF	0	SF SF				1	No No	1/D 1/D
1	3 Teacher Lounge 3 Teacher Lounge	M M	Cement Floor Blackboard Glue Dots	6450/01/03/AET/BB/2600	Assumed	380 85	SF	0	SF				1	No No	1/D
1	3 Teacher Lounge	M	Linoleum	6450/1/03/BB	Assumed	380	SF	2	SF		note type of damage		1	No	6/C
1	3 Teacher Lounge Kitchen	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	4	LF	0	LF				1	No	1/D
1	3 Teacher Lounge Kitchen	N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	77	SF	8	SF			1	N/A	N/A	N/A

	School District of Philadelphia		1		Reinspection 2015-2016						Reinspection Date: 1/22-29/2016			-	
	James Dobson Elementary School			Room by Room	Location Log Report						Building Inspector: Bernard Brunner				
	4667 Umbria Street, Philadelphia, PA 19127										Certificate Number: 45397				
	ULCS# 6450										Management Planner: Monique Causley				
	Year Built: 1930										Certificate Number: ACC-0215-8-010				
	1941 24111 1000													Ι	
E	On Site Room Name Teacher Lounge Kitchen	System Affected N/A	Material Description Plaster Ceiling	HID#	Confirmed, Assumed, NAD, Non Suspect ACM NAD	Amount of Material	SF LF EA	Amount of Damage	SF LF I	Color equired for VAT	Comments/Description/Notes	Attic Crawl Space Ranking	Damage Potential (DP)	Newly Friable (NF) No	Response Action (RA)
	Teacher Lounge Kitchen Teacher Lounge Kitchen	N/A	Plaster Walls		NAD	360	SF	0	SF				1	No	1/D
1 3	Teacher Lounge Kitchen	N/A	Cement Floor		Non Suspect ACM	77	SF	0	SF SF				1	No	1/D
1 3	Teacher Lounge Kitchen	М	Linoleum	6450/1/03/BB	Assumed	77	SF	0	SF				1	No	1/D
1 3	Teacher Lounge Closet	N/A	Plaster Ceiling		NAD	18	SF	0	SF				1	No	1/D
	Teacher Lounge Closet Teacher Lounge Closet	N/A N/A	Plaster Walls Cement Floor		NAD Non Suspect ACM	180 18	SF SF	0	SF SF				1	No No	1/D 1/D
1 3	Teacher Lounge Closet Teacher Lounge Closet	M M	Linoleum	6450/1/03/BB	Assumed	18	SF	0	SF				1	No	1/D
	Classroom 307	T	Pipe Insulation 2-6 inch	6450/01/03/22	Confirmed	24	LF	0	LF		More likely above ceiling tile		1_	No	1/D
1 3	Classroom 307	N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	1200	SF	0	SF				1	No	1/D
	Classroom 307	N/A	Plaster Ceiling		NAD	1200	SF	0	SF			_	1	No	1/D
1 3	Classroom 307	N/A M	Plaster Walls Floor Tile VAT 12" x 12"	6450/01/03/GG	NAD Accumed	1940	SF SF	25 0	SF SF	Multi			N/A 1	N/A	N/A
1 3	Classroom 307 Classroom 307	N/A	Wood Floor	0450/01/03/GG	Assumed Non Suspect ACM	1200 1200	SF	0	SF	Multi		_	1	No No	1/D 1/D
	Classroom 307	T T	Transite Electrical Panel	6450/01/03/23	Confirmed	20	SF	0	SF				1	No	1/D
	Classroom 307 Left Closet	N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	48	SF	0	SF				1	No	1/D
1 3	Classroom 307 Left Closet	N/A	Plaster Ceiling		NAD	48	SF	0	SF SF				1	No	1/D
1 3	Classroom 307 Left Closet	N/A	Plaster Walls		NAD	240	SF	5					N/A	N/A	N/A
1 3	Classroom 307 Left Closet Classroom 307 Left Closet	M M	Sheetrock Wall Floor Tile VAT 12" x 12"	6450/01/03/AET/BB/2100 6450/01/03/GG	Assumed Assumed	70 48	SF SF	0	SF SF	Pink			1	No No	1/D 1/D
	Classroom 307 Left Closet	N/A	Wood Floor	6450/01/03/GG	Non Suspect ACM	48	SF	0	SF	PIIK			1	No	1/D
	Classroom 307 Center Closet	T	Pipe Insulation 2-6 inch	6450/01/03/22	Confirmed	12	LF	0	LF		More likely above ceiling tile		1	No	1/D
	Classroom 307 Center Closet	N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	48	SF	0	SF				1	No	1/D
	Classroom 307 Center Closet	N/A	Plaster Ceiling		NAD	48	SF	0	SF				1	No	1/D
	Classroom 307 Center Closet	N/A M	Plaster Walls	0.450/0.4/0.0/A.5T/DD/0.400	NAD	240	SF SF	5	SF			_	N/A 1	N/A	N/A 1/D
	Classroom 307 Center Closet Classroom 307 Center Closet	M	Sheetrock Wall Floor Tile VAT 12" x 12"	6450/01/03/AET/BB/2100 6450/01/03/GG	Assumed Assumed	70 48	SF	1	SF SF	Pink	note type of damage		1	No No	6/C
1 3	Classroom 307 Center Closet	N/A	Wood Floor	0100/01/00/00	Non Suspect ACM	48	SF	0	SF		note type or damage		1	No	1/D
1 3	Classroom 307 Right Closet	N/A	Plaster Ceiling		NAD	30	SF	0	SF				1	No	1/D
	Classroom 307 Right Closet	N/A	Plaster Walls		NAD	200	SF	0	SF				1	No	1/D
	Classroom 307 Right Closet Classroom 307 Right Closet	M N/A	Floor Tile VAT 12" x 12" Wood Floor	6450/01/03/GG	Assumed Non Suspect ACM	30 30	SF SF	0	SF SF	Pink			1	No No	1/D 1/D
	Classroom 307 Cabinet Area	T	Pipe Insulation 2-6 inch	6450/01/03/22	Confirmed	12	I.F.	0	LF		More likely above ceiling tile		1	No	1/D
	Classroom 307 Cabinet Area	N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	234	SF	0	SF		and the same of th		1	No	1/D
1 3	Classroom 307 Cabinet Area	N/A	Plaster Ceiling		NAD	234	SF	0	SF				1	No	1/D
	Classroom 307 Cabinet Area	N/A M	Plaster Walls	6450/01/03/GG	NAD	620	SF SF	15 0	SF SF	Pink			N/A 1	N/A	N/A 1/D
1 3	Classroom 307 Cabinet Area Classroom 307 Cabinet Area	N/A	Floor Tile VAT 12" x 12" Wood Floor	6450/01/03/GG	Assumed Non Suspect ACM	234 234	SF	0	SF	PINK			1	No No	1/D
1 3	Classroom 307 Space at Rear Entrance	N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	55	SF	0	SF				1	No	1/D
1 3	Classroom 307 Space at Rear Entrance	N/A	Plaster Ceiling		NAD	55	SF	0	SF				1	No	1/D
1 3	Classroom 307 Space at Rear Entrance	N/A	Plaster Walls		NAD	330	SF	0	SF				1	No	1/D
1 3	Classroom 307 Space at Rear Entrance	M N/A	Floor Tile VAT 12" x 12"	6450/01/03/GG	Assumed	55 55	SF SF	0	SF	Pink		_	1	No No	1/D 1/D
1 3	Classroom 307 Space at Rear Entrance 3rd Floor Girl's Restroom	N/A N/A	Wood Floor Fiberglass Pipe Insulation		Non Suspect ACM Non Suspect ACM	55 15	LF	0	SF LF				1	No	1/D
1 3	3rd Floor Girl's Restroom	N/A	Plaster Ceiling		NAD	160	SF	0	SF				1	No	1/D
1 3	3rd Floor Girl's Restroom	N/A	Plaster Walls		NAD	625	SF	0	SF				1	No	1/D
	3rd Floor Girl's Restroom	N/A	Ceramic Tile Walls		Non Suspect ACM	625	SF	0	SF				1	No	1/D
1 3	3rd Floor Girl's Restroom 3rd Floor Girl's Restroom Pipe Shaft	N/A T	Ceramic Tile Floors Pipe Insulation 2-6 inch	6450/01/03/22	Non Suspect ACM Confirmed	160 15	SF LF	0	SF LF			+	1	No No	1/D 1/D
	3rd Floor Girl's Restroom Pipe Shaft 3rd Floor Girl's Restroom Pipe Shaft	†	Pipe Insulation 2-6 inch	6450/01/03/22	Confirmed	15	LF	0	LF				1	No	1/D
1 3	3rd Floor Girl's Restroom Pipe Chase	N/A	Fiberglass Pipe Insulation	2 .22.2 .700/00	Non Suspect ACM	7	LF	0	LF				1	No	1/D
1 3	Classroom 308	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	5	LF	3	LF				N/A	N/A	N/A
	Classroom 308	N/A	Ceiling Tile 2' x 4'		Non Suspect ACM	770	SF	0	SF				1	No	1/D
1 3	Classroom 308 Classroom 308	N/A N/A	Plaster Ceiling Plaster Walls		NAD NAD	770 1010	SF SF	10	SF SF			+	1 N/A	No N/A	1/D N/A
	Classroom 308	M	Sheetrock Wall	6450/01/03/AET/BB/2100	Assumed	245	SF	0	SF				1	No.	1/D
1 3	Classroom 308	N/A	Wood Floor		Non Suspect ACM	770	SF	0	SF				1	No	1/D
1 3	Classroom 308 Large Closet	N/A	Ceiling Tile 2' x 4'		Non Suspect ACM	105	SF	0	SF				1	No	1/D
	Classroom 308 Large Closet	N/A N/A	Plaster Ceiling Plaster Walls		NAD NAD	105 510	SF SF	0	SF SF				1	No No	1/D 1/D
1 3		N/A N/A	Wood Floor		Non Suspect ACM	105	SF SF	0	SF				1	No No	1/D 1/D
	Classroom 308 Small Closet	N/A	Plaster Ceiling		NAD	30	SF	0	SF				1	No	1/D
1 3	Classroom 308 Small Closet	N/A	Plaster Walls		NAD	200	SF	5	SF				N/A	N/A	N/A
	Classroom 308 Small Closet	N/A	Wood Floor	0.450/0.4755555	Non Suspect ACM	30	SF	0	SF				1	No	1/D
	Classroom 309	T N/A	Pipe Insulation 2-6 inch Fiberglass Ceiling Tile 2' x 4'	6450/01/03/22	Confirmed	12 770	LF SF	0 48	LF SF		More likely above ceiling tile	_	1 N/A	No N/A	1/D N/A
1 3	Classroom 309 Classroom 309	N/A N/A	Plaster Ceiling		Non Suspect ACM NAD	770	SF	48 5	SF				N/A N/A	N/A N/A	N/A N/A
	1	1	, idotor coming	l			<u> </u>				l			1	

### April 19 Bern Harden Part Part ### April 19 Bern Harden Part ### April 19 Bern Har		School District of Philadelphia			AHERA Three-Year	Reinspection 2015-2016						Reinspection Date: 1/22-29/2016				
## 1 Control Board Part Pa		James Dobson Elementary School			Room by Room	Location Log Report						Building Inspector: Bernard Brunner				ļ
March 1990			1		•	-							7			ļ
The Part 1900 The Part 1900 The Part The Pa			1										7			
F Control		I .	1										+			ļ
Part		Year Built: 1930		1				1				Certificate Number: ACC-0215-8-010	_			
1 1 Control 192	I e F m I e o		System			Confirmed, Assumed, NAD,			Amount of	SF LF rec	ulred fo		Attic Crawl Space	Potential	Newly	Response
1 1 1 1 1 1 1 1 1 1					HID#				Damage		VAI	Comments/Description/Notes	Ranking) Action (RA) N/A
1 3 Descript 50 American Section T. T. T. T. T. T. T. T					6450/01/03/AFT/BB/2100				0				+	1N/A		1/D
1 1 1 1 1 1 1 1 1 1					0100/01/00//12//22/2100				Ö					i		1/D
1 1 Displayer Celeford No. Propose C	1 3	Classroom 309			6450/01/03/AET/BB/2600		90	SF	0	SF				1		1/D
1 1 Description 1 De			Т		6450/01/03/22				0			More likely above ceiling tile				1/D
1 1																N/A
1 1 1 1 1 1 1 1 1 1	1 3	Classroom 309 Large Closet														1/D
1 1 1 1 1 1 1 1 1 1							510			SF						1/D 1/D
1 1 1 1 1 1 1 1 1 1	1 3	Classroom 309 Small Closet							0				+	1		1/D
1 1 1 1 2 2 2 2 2 2									0			1	1	1		1/D
1 1 1 1 1 1 1 1 1 1	1 3	Classroom 309 Small Closet							0							1/D
1 1 1 1 1 1 1 1 1 1	1 3	3rd Floor Faculty Restroom	N/A			Non Suspect ACM	4	LF	0	LF				11	No	1/D
1 1 1 1 1 1 1 1 1 1	1 3	3rd Floor Faculty Restroom		Ceiling Tile 2' x 4'		Non Suspect ACM										N/A
1 1 Sept Poor Faulty Relationes													+			N/A
3 3 State Pearly Reviewore No. Centern Ter Data No. Support ACM 192 57 0 57												1	+			1/D
1 3 Genze from advancer to 30° Floor Floor Packet Petrology NA Piper Floor (including to 1) 1 3 Genze from 313 NA Piper Floor (including to 1) 1 3 Genze from 313 NA Piper Floor (including to 1) 1 1 1 1 1 1 1 1 1	1 3	3rd Floor Faculty Restroom				Non Suspect ACM				SF			+			1/D 1/D
1 2				Ceramic Tile Floors	v	Non Suspect ACM	162	5F	U V			No access nadlocked	+	1		1/0
1 3 Constroom 13 1.	1 3	Classroom 313		Pine Fitting Insulation	^	NAD	2	FA	n	FA		INO access - padiocked		1		1/D
1 2 Dissessor 313					6450/01/03/22		25		0			More likely above ceiling tile		1		1/D
1 3 Galestoom 313	1 3	Classroom 313					1260		8			· ·		N/A	N/A	N/A
1 3 Glesseom 313	1 3	Classroom 313							0							1/D
1 3 Sept Closed souther Cleaseroom 313	1 3	Classroom 313							3	SF						N/A
1 3 Right Closer custate Cleaserom 313									0				+			1/D
T 3 Ref Closed culsive Classroom 313									0							N/A 1/D
1 3 Left Closed outsides Classroom 313				1 ladioi Tralic		1410			0					1		1/D
1 3 Let Closed outside Classroom 315						NAD			0					1		1/D
1 3 Classroom 313 Colar Closert	1 3	Left Closet outside Classroom 313		Plaster Walls		NAD			0					1	No	1/D
1 3 Classroom 313 Colar Closet			N/A						-							1/D
1 3 Classroom 313 Coard Closet			T		6450/01/03/22				0			More likely above ceiling tile				1/D
1 3 Classroom 313 Coal Closet	1 3	Classroom 313 Coat Closet							8				+			N/A 1/D
1 3 Classroom 312 Costed adjacent to Cost Closet N/A Wood Floor Non Suspeet ACM 80 SF 0 SF 1 No	1 3	Classroom 313 Coat Closet														1/D
1 3 Classroom 313 Closet adjacent to Coat Closet N/A Plaster Celling NAD 54 SF 0 SF 1 No 1 3 Classroom 313 Closet adjacent to Coat Closet N/A Vood Floor NAD SI SF 0 SF 1 No 1 3 Classroom 313 Closet adjacent to Coat Closet N/A Vood Floor NAD SI SF 0 SF 1 No 1 3 Classroom 312 Closet adjacent to Coat Closet N/A Vood Floor NAD SI SF 0 SF 1 No 1 3 Classroom 312 Closet to left of Entrance N/A Plaster Walls NAD S4 SF 0 SF 1 No 1 3 Classroom 312 Closet to left of Entrance N/A Plaster Walls NAD S4 SF 0 SF NAD SF NAD SF NAD NAD S4 SF NAD SF NAD NAD SF NAD SF NAD SF NAD NAD SF NAD NAD SF NAD NAD SF NAD	1 3	Classroom 313 Coat Closet							ő					1		1/D
1 3 Classroom 313 Closes to left of Entrance N/A Wood Floor Non Suppert ACM 54 SF 0 SF 1 No 1 3 Classroom 31 (Closes to left of Entrance N/A Plaster (Celling NAD 54 SF 0 SF 0 SF 1 No 1 3 Classroom 31 (Closes to left of Entrance N/A Plaster (Celling NAD 300 SF 0 SF 0 SF 1 No 1 3 Classroom 31 (Closes to left of Entrance N/A Wood Floor Non Suspect ACM 54 SF 0 SF 0 SF 1 No 1 3 Clearsroom 31 (Closes to left of Entrance N/A Wood Floor Non Suspect ACM 54 SF 0 SF 0 SF 1 No 1 3 Clearsroom 303/304 X	1 3	Classroom 313 Closet adjacent to Coat Closet							0					1		1/D
1 3 Classroom 313 Closet to left of Entrance	1 3	Classroom 313 Closet adjacent to Coat Closet														1/D
1 3 Classroom 313 Close to left of Enfrance												-	+			1/D
1 3 Classroom 313 Closes to left of Entrance	1 3	Classroom 313 Closet to left of Entrance		Plaster Ceiling								1	+			1/D 1/D
1 3 Left Closet across from Classroom 303/304												1	+			1/D
1 3 Center Closet across from Classroom 303/304					x							No Access	1			X
1 3 Center Closest across from Classroom 303/304			N/A				18	SF		SF						1/D
1 3 Center Closet across from Classroom 303/304	1 3	Center Closet across from Classroom 303/304	N/A	Plaster Walls		NAD	145	SF		SF					No	1/D
1 3 Right Closet across from Classroom 303/304 N/A Plaster Walls N/A Cement Floor Non Suspect ACM 18 SF 0 SF N No Access X X X X X X X X X																1/D
1 3 Right Closet across from Classroom 303/304													+			1/D 1/D
1 3 Left Closet across from Classroom 307									0				+	1		1/D 1/D
1 3 Center Closet across from Classroom 307 N/A Wood Celling N/A Plaster Walls NAD 145 SF 15 SF N/A					y				×			No Access	+	y I		1/D X
1 3 Center Closet across from Classroom 307	1 3	Center Closet across from Classroom 307			,				Î	SF						N/A
1 3 Center Closet across from Classroom 307	1 3	Center Closet across from Classroom 307	N/A			NAD	145	SF	15	SF					N/A	N/A
1 3 Right Closet across from Classroom 307 N/A Plaster Walls NAD 145 SF 0 SF 1 3 Right Closet across from Classroom 307 N/A Cement Floor Non Suspect ACM 18 SF 0 SF 3 SF 0 SF 0 SF 3 SF 0 SF 3 SF 0 SF 3 SF 0 SF 0 SF SF 0 SF 3 SF 0 SF 3 SF 5 SF 0 NA	1 3	Center Closet across from Classroom 307	N/A	Cement Floor		Non Suspect ACM							1			1/D
1 3 Right Closet across from Classroom 307 N/A Cement Floor Non Suspect ACM 18 SF 0 SF 1 3 Classroom 302 adjacent to IMC N/A Celling Title (2* 4*) Non Suspect ACM 320 SF 32 SF SF N/A N/A <t< td=""><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td>1</td><td>+</td><td>1 1</td><td></td><td>1/D</td></t<>												1	+	1 1		1/D
1 3 Classroom 302 adjacent to IMC	1 3	Right Closet across from Classroom 307											+			1/D 1/D
1 3 Classroom 302 adjacent to IMC	1 3	Classroom 302 adjacent to IMC				Non Suspect ACM						 	+			1/D N/A
1 3 Classroom 302 adjacent to IMC N/A Plaster Walls NAD 740 SF 20 SF N/A N/A <td< td=""><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td>1</td><td></td><td></td><td>N/A</td></td<>													1			N/A
1 3 Classroom 302 adjacent to IMC M Sheetrock Wall 6450/01/03/AET/BB/2100 Assumed 10 SF 0 SF 1 1 No 1 3 Classroom 302 adjacent to IMC N/A Marbie Wall Non Suspect ACM 300 SF 0 SF 0 SF 1 No 1 3 Classroom 302 adjacent to IMC N/A Carpet Non Suspect ACM 320 SF 0 SF 1 No 1 3 Classroom 302 adjacent to IMC N/A Cement Floor Non Suspect ACM 320 SF 0 SF 0 SF 1 3 Classroom 302 adjacent to IMC N/A Cement Floor Non Suspect ACM 320 SF 0 SF																N/A
1 3 Classroom 302 adjacent to IMC N/A Marble Wall Non Suspect ACM 300 SF 0 SF 1 No 1 3 Classroom 302 adjacent to IMC N/A Carpet Non Suspect ACM 320 SF 0 SF 1 No 1 3 Classroom 302 adjacent to IMC N/A Cerent Floor Non Suspect ACM 320 SF 0 SF 1 No 1 3 Hallway outside IMC T Pipe Insulation 2-6 inch 6450/01/03/22 Confirmed 12 LF 0 LF More likely above ceiling tile 1 No 1 3 Hallway outside IMC N/A Fiberglass Ceiling Tile 2' x 4' No No SF 24 SF SF	1 3	Classroom 302 adjacent to IMC	M	Sheetrock Wall	6450/01/03/AET/BB/2100	Assumed	100	SF		SF				1	No	1/D
1 3 Classroom 302 adjacent to IMC N/A Carpet Non Suspect ACM 320 SF 0 SF 1 1 No 1 3 Classroom 302 adjacent to IMC N/A Cement Floor Non Suspect ACM 320 SF 0 SF 0 SF 0 NF 1 No <	1 3	Classroom 302 adjacent to IMC		Marble Wall		Non Suspect ACM	300			SF					No	1/D
1 3 Hallway outside IMC T Pipe Insulation 2-6 inch 6450/01/03/22 Confirmed 12 LF 0 LF More likely above ceiling tile 1 No 1 3 Hallway outside IMC N/A Fiberglass Ceiling Tile 2' x 4' Non Suspect ACM 390 SF 24 SF N/A N/A	1 3	Classroom 302 adjacent to IMC											+			1/D
1 3 Hallway outside IMC N/A Fiberglass Ceiling Tile 2' x 4' Non Suspect ACM 390 SF 24 SF N/A N/A N/A			N/A		6450/04/00/00							Mara likely above colling 411-	+	1 1		1/D
1 3 Hallway outside IMC N/A Plaster Celling NAD 390 SF 5 SF N/A N/A N/A	1 3	Hallway outside IMC	N/A		b45U/U1/U3/22							iviore likely above celling tile	+	1 N/Δ		1/D N/A
	1 3	Hallway outside IMC											1			N/A
1 3 Hallway outside IMC N/A Plaster Walls NAD 780 SF 0 SF 1 No	1 3	Hallway outside IMC				1410			ő					1		1/D

	School District of Philadelphia			AHERA Three-Year	Reinspection 2015-2016						Reinspection Date: 1/22-29/2016				
ı	James Dobson Elementary School				Location Log Report		İ				Building Inspector: Bernard Brunner				Ī
1	-											_			
	4667 Umbria Street, Philadelphia, PA 19127										Certificate Number: 45397	-			
	ULCS# 6450										Management Planner: Monique Causley	_			
	Year Built: 1930		1								Certificate Number: ACC-0215-8-010				
_E															1
e F m I e o n o t r	On Site Room Name	System Affected	Material Description	HID#	Confirmed, Assumed, NAD, Non Suspect ACM	Amount of Material	SF LF EA	Amount of Damage	SF LF req	Color ulred for VAT	Comments/Description/Notes	Attic Crawl Space Ranking	Damage Potential (DP)	Newly Friable (NF)	Response Action (RA)
1 3		М	Sheetrock Wall	6450/01/03/AET/BB/2100	Assumed	100	SF	0	SF				1	No	1/D
1 3	Hallway outside IMC	N/A N/A	Marble Wall Cement Floor		Non Suspect ACM	315 390	SF SF	0	SF SF				1 1	No No	1/D 1/D
1 3	Hallway outside IMC Hallway outside Classrooms 303-307	N/A N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM Non Suspect ACM	1332	SF	48	SF				N/A	N/A	N/A
	Hallway outside Classrooms 303-307	N/A	Plaster Ceiling		NAD	1332	SF	0	SF				1	No	1/D
	Hallway outside Classrooms 303-307	N/A	Plaster Walls		NAD	2460	SF	0	SF				1	No	1/D
1 3	Hallway outside Classrooms 303-307	N/A	Marble Wall		Non Suspect ACM	985	SF	1	SF				N/A	N/A	N/A
1 3	Hallway outside Classrooms 303-307	N/A	Cement Floor		Non Suspect ACM	1332	SF	0	SF				1	No	1/D
	Hallway outside Classrooms 308-309	T	Pipe Insulation 2-6 inch	6450/01/03/22	Confirmed	12	LF	0	LF		More likely above ceiling tile		1	No No	1/D
	Hallway outside Classrooms 308-309 Hallway outside Classrooms 308-309	N/A N/A	Fiberglass Ceiling Tile 2' x 4' Plaster Ceiling		Non Suspect ACM NAD	430 430	SF SF	72 0	SF SF		1	_	N/A 1	N/A No	N/A 1/D
	Hallway outside Classrooms 308-309	N/A	Plaster Walls		NAD	1040	SF	15	SF				N/A	N/A	N/A
1 3	Hallway outside Classrooms 308-309	N/A	Marble Wall		Non Suspect ACM	345	SF	0	SF				1	No	1/D
	Hallway outside Classrooms 308-309	N/A	Cement Floor		Non Suspect ACM	430	SF	0	SF				1	No	1/D
1 3	Girl's Side Stairwell	T	Pipe Insulation 2-6 inch	6450/01/03/22	Confirmed	25	LF	0	LF		More likely above ceiling tile		1	No	1/D
	Girl's Side Stairwell	N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	265	SF	0	SF				1	No	1/D
1 3	Girl's Side Stairwell	N/A	Plaster Ceiling		NAD NAD	265	SF SF	0	SF SF				1	No No	1/D
1 3	Girl's Side Stairwell Girl's Side Stairwell	N/A N/A	Plaster Walls Marble Wall		Non Suspect ACM	1400 470	SF	50	SF			_	N/A 1	N/A No	N/A 1/D
	Girl's Side Stairwell	N/A	Cement Floor		Non Suspect ACM	265	SF	0	SF				1	No	1/D
	Boy's Side Stairwell	T	Pipe Insulation 2-6 inch	6450/01/03/22	Confirmed	25	LF.	0	LF		More likely above ceiling tile		1	No	1/D
1 3	Boy's Side Stairwell	N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	265	SF	80	SF				N/A	N/A	N/A
1 3	Boy's Side Stairwell	N/A	Plaster Ceiling		NAD	265	SF	0	SF				1	No	1/D
1 3	Boy's Side Stairwell	N/A	Plaster Walls		NAD	1400	SF	0	SF				1	No	1/D
	Boy's Side Stainwell	N/A	Marble Wall		Non Suspect ACM	470	SF	0	SF			_	1	No	1/D
	Boy's Side Stairwell Classroom 201	N/A N/A	Cement Floor Fiberglass Pipe Insulation		Non Suspect ACM Non Suspect ACM	265 4	SF LF	0	SF LF				1 1	No No	1/D 1/D
	Classroom 201	N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	770	SF	8	QE				N/A	N/A	N/A
1 2	Classroom 201	N/A	Plaster Ceiling		NAD	770	SF	0	SF				1	No	1/D
1 2	Classroom 201	N/A	Plaster Walls		NAD	1010	SF	0	SF				1	No	1/D
1 2	Classroom 201	N/A	Partition Room Dividers		Non Suspect ACM	245	SF	0	SF		Wood Partition open to 202		1	No	1/D
	Classroom 201	N/A M	Wood Floor	0.450/04/00/A ET/IDD/0000	Non Suspect ACM	770 90	SF SF	0	SF SF			_	1	No No	1/D 1/D
	Classroom 201 Classroom 201 Large Closet	N/A	Blackboard Glue Dots Fiberglass Pipe Insulation	6450/01/02/AET/BB/2600	Assumed Non Suspect ACM	17	I F	0	LF				1	No No	1/D
1 2	Classroom 201 Large Closet	N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	90	SF	0	SF				1	No	1/D
1 2	Classroom 201 Large Closet	N/A	Plaster Ceiling		NAD	90	SF	6	SF				N/A	N/A	N/A
1 2	Classroom 201 Large Closet	N/A	Plaster Walls		NAD	555	SF	0	SF				1	No	1/D
1 2		N/A	Wood Floor		Non Suspect ACM	90	SF	0	SF				1	No	1/D
1 2		N/A	Plaster Ceiling		NAD	25	SF SE	0	SF SF		-		1	No	1/D
1 2	Classroom 201 Small Closet Classroom 201 Small Closet	N/A N/A	Plaster Walls Wood Floor		NAD Non Suspect ACM	160 25	SF SF	0	SF SF		+		1 1	No No	1/D 1/D
	Classroom 201 Small Closet Classroom 202	N/A N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	770	SF	32	SF		1		N/A	N/A	N/A
	Classroom 202	N/A	Plaster Ceiling		NAD NAD	770	SF	0	SF				1	No	1/D
1 2	Classroom 202	N/A	Plaster Walls		NAD	1010	SF	0	SF				1	No	1/D
1 2	Classroom 202	N/A	Partition Room Dividers		Non Suspect ACM	245	SF	0	SF		Wood Partition open to 201		1	No	1/D
	Classroom 202	N/A	Wood Floor	0.450.004.004.55T.DD:	Non Suspect ACM	770	SF	0	SF		-		1	No	1/D
1 2	Classroom 202 Classroom 202 Large Closet	M N/A	Blackboard Glue Dots Fiberglass Ceiling Tile 2' x 4'	6450/01/02/AET/BB/2600	Assumed Non Suspect ACM	90 90	SF SF	0	SF SF				1 1	No No	1/D 1/D
1 2		N/A N/A	Plaster Ceiling		Non Suspect ACM NAD	90	SF	0	SF		1		1	No No	1/D
1 2		N/A	Plaster Walls		NAD	555	SF	0	SF				1	No	1/D
1 2	Classroom 202 Large Closet	N/A	Wood Floor		Non Suspect ACM	90	SF	0	SF				1	No	1/D
1 2	Classroom 202 Small Closet	N/A	Plaster Ceiling		NAD	25	SF	0	SF				1	No	1/D
	Classroom 202 Small Closet	N/A	Plaster Walls		NAD	160	SF	3	SF		-		N/A	N/A	N/A
1 2	Classroom 202 Small Closet Custodial Closet adjacent to 2nd Floor Boy's Restroom	N/A N/A	Wood Floor Plaster Ceiling		Non Suspect ACM NAD	25 20	SF SF	0	SF SF		-		1	No No	1/D 1/D
	Custodial Closet adjacent to 2nd Floor Boy's Restroom Custodial Closet adjacent to 2nd Floor Boy's Restroom	N/A N/A	Plaster Ceiling Plaster Walls		NAD NAD	180	SF	0	SF		1		1	No No	1/D
1 2	Custodial Closet adjacent to 2nd Floor Boy's Restroom Custodial Closet adjacent to 2nd Floor Boy's Restroom	N/A	Ceramic Tile Walls		Non Suspect ACM	180	SF	0	SF				1	No	1/D
1 2	Custodial Closet adjacent to 2nd Floor Boy's Restroom	N/A	Ceramic Tile Floors		Non Suspect ACM	20	SF	0	SF				1	No	1/D
1 2	2nd Floor Boy's Restroom	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	57	LF	0	LF				1	No	1/D
	2nd Floor Boy's Restroom	N/A	Concrete Ceiling		Non Suspect ACM	160	SF	0	SF		1		1	No	1/D
1 2	2nd Floor Boy's Restroom	N/A	Plaster Walls		NAD Nan Suggest ACM	625	SF SF	0	SF SF			_	1	No No	1/D
1 2	2nd Floor Boy's Restroom 2nd Floor Boy's Restroom	N/A N/A	Ceramic Tile Walls Ceramic Tile Floors		Non Suspect ACM Non Suspect ACM	625 160	SF SF	0	SF SF		+		1	No No	1/D 1/D
	2nd Floor Boy's Restroom Pipe Chase	T	Pipe Fitting Insulation	6450/01/02/16	Confirmed	1	EA	0	EA		1		1	No	1/D
	2nd Floor Boy's Restroom Pipe Chase	N/A	Fiberglass Pipe Insulation	2.22.2.002.10	Non Suspect ACM	95	LF	0	LF				1	No	1/D
1 2	Classroom 203	T	Pipe Insulation 2-6 inch	6450/01/02/17	Confirmed	24	LF	0	LF		More likely above ceiling tile		1	No	1/D
1 2	Classroom 203	N/A	Ceiling Tile 2' x 4'		Non Suspect ACM	770	SF	8	SF				N/A	N/A	N/A

	School District of Philadelphia				Reinspection 2015-2016						Reinspection Date: 1/22-29/2016				
1	James Dobson Elementary School	1		Room by Room	Location Log Report]			Building Inspector: Bernard Brunner	4			
	4667 Umbria Street, Philadelphia, PA 19127	1									Certificate Number: 45397	_			
	ULCS# 6450										Management Planner: Monique Causley				
	Year Built: 1930										Certificate Number: ACC-0215-8-010	7			
	Teal Duit, 1800										Germicate Number: ACC-0213-0-010				
E I e F m I e o n o t r		System Affected			Confirmed, Assumed, NAD,	Amount of	05.15.54	Amount of	SF LF red	Color julied for		Attic Crawl Space Ranking	Damage Potential	Newly	Response
		Affected N/A	Material Description	HID#	Non Suspect ACM NAD	Material 770	SF LF EA	Damage	EA CE	VAT	Comments/Description/Notes	Ranking	(DP)	Friable (NF)	Action (RA)
	Classroom 203 Classroom 203	N/A N/A	Plaster Ceiling Plaster Walls		NAD NAD	1010	SF SF	0	SF SF			-	1 1	No No	1/D
1 2	Classroom 203	M M	Sheetrock Wall	6450/01/02/AET/BB/2100	Assumed	245	SF	0	SF			_	1	No	1/D
1 2	Classroom 203	N/A	Wood Floor	0430/01/02/AE1/BB/2100	Non Suspect ACM	770	SF	0	SF				1	No	1/D
	Classroom 203	M	Blackboard Glue Dots	6450/01/02/AET/BB/2600	Assumed	125	SF	0	SF				1	No	1/D
	Classroom 203 Large Closet	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	12	LF	0	LF				1	No	1/D
1 2	Classroom 203 Large Closet	N/A	Ceiling Tile 2' x 4'		Non Suspect ACM	105	SF	8	SF				N/A	N/A	N/A
1 2	Classroom 203 Large Closet	N/A	Plaster Ceiling		NAD	105	SF	0	SF				1	No	1/D
1 2	Classroom 203 Large Closet	N/A	Plaster Walls		NAD	555	SF	0	SF				1	No	1/D
	Classroom 203 Large Closet	N/A	Wood Floor		Non Suspect ACM	105	SF	0	SF			1	1	No	1/D
1 2	Classroom 203 Small Closet	N/A N/A	Plaster Ceiling Plaster Walls		NAD NAD	30 180	SF SF	0	SF SF			+	1	No No	1/D 1/D
1 2	Classroom 203 Small Closet Classroom 203 Small Closet	N/A N/A	Wood Floor		Non Suspect ACM	30	SF	0	SF			+	1	No	1/D
1 2	Classroom 204	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	10	I F	4	IF.				N/A	N/A	N/A
1 2	Classroom 204	N/A	Ceiling Tile 2' x 4'		Non Suspect ACM	770	SF	0	SF			1	1	No	1/D
1 2	Classroom 204	N/A	Plaster Ceiling		NAD	770	SF	0	SF				1	No	1/D
1 2	Classroom 204	N/A	Plaster Walls		NAD	1010	SF	0	SF				1	No	1/D
1 2	Classroom 204	M	Sheetrock Wall	6450/01/02/AET/BB/2100	Assumed	245	SF	0	SF				1	No	1/D
1 2	Classroom 204	N/A	Wood Floor		Non Suspect ACM	770	SF	0	SF				1	No	1/D
	Classroom 204 Large Closet	N/A	Ceiling Tile 2' x 4'		Non Suspect ACM	105	SF	0	SF				1	No	1/D
	Classroom 204 Large Closet	N/A N/A	Plaster Ceiling Plaster Walls		NAD NAD	105 555	SF	0	SF				1	No No	1/D 1/D
	Classroom 204 Large Closet Classroom 204 Large Closet	N/A	Wood Floor		Non Suspect ACM	105	SF SF	0	SF SF			+	1	No	1/D
	Classroom 204 Small Closet	N/A	Plaster Ceiling		NAD	30	SF	0	SF				1	No	1/D
1 2	Classroom 204 Small Closet	N/A	Plaster Walls		NAD	180	SF	Ö	SF				1	No	1/D
	Classroom 204 Small Closet	N/A	Wood Floor		Non Suspect ACM	30	SF	0	SF				1	No	1/D
	Office 205	T	Pipe Fitting Insulation	6450/01/02/16	Confirmed	3	EA	0	EA		More likely above ceiling tile		1	No	1/D
1 2	Office 205	Т	Pipe Insulation 2-6 inch	6450/01/02/17	Confirmed	26 399	LF	0	LF		More likely above ceiling tile		1	No	1/D
1 2	Office 205	N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	399	SF	16	SF				N/A	N/A	N/A
	Office 205	N/A	Plaster Ceiling		NAD	399	SF	0	SF				1	No	1/D
	Office 205	N/A M	Plaster Walls Floor Tile VAT 9" x 9"	6450/01/02/15	NAD Confirmed	880 379	SF SF	0	SF SF	Green			1	No No	1/D 1/D
	Office 205 Office 205	M	Floor Tile VAT 12" x 12"	6450/01/02/FF	Assumed	20	SF	0	SF	Blue		+	1	No	1/D
	Office 205	N/A	Cement Floor	0430/01/02/11	Non Suspect ACM	399	SF	0	SF	blue			1	No	1/D
1 2	Office 205 Restroom	T	Pipe Fitting Insulation	6450/01/02/16	Confirmed	6	EA	0	EA				1	No	1/D
1 2	Office 205 Restroom	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	30	LF	2	LF				N/A	N/A	N/A
1 2	Office 205 Restroom	N/A	Plaster Ceiling		NAD	42	SF	3	SF				N/A	N/A	N/A
	Office 205 Restroom	N/A	Plaster Walls		NAD	290	SF	0	SF				1	No	1/D
1 2	Office 205 Restroom	N/A	Marble Wall		Non Suspect ACM	70	SF SF	0	SF				1 1	No	1/D
1 2	Office 205 Restroom Closet adjacent to Office 205	N/A N/A	Ceramic Tile Floors Plaster Ceiling		Non Suspect ACM NAD	42 42	SF SF	0	SF SF		 	1	1 1	No No	1/D 1/D
	Closet adjacent to Office 205 Closet adjacent to Office 205	N/A	Plaster Walls		NAD	290	SF	0	SF				1	No	1/D
	Closet adjacent to Office 205	N/A	Cement Floor		Non Suspect ACM	42	SF	0	SF				1	No	1/D
1 2	Classroom 206	N/A	Ceiling Tile 2' x 4'		Non Suspect ACM	770	SF	0	SF				1	No	1/D
1 2	Classroom 206	N/A	Plaster Ceiling		NAD	770	SF	0	SF				1	No	1/D
1 2	Classroom 206	N/A	Plaster Walls		NAD	1010	SF	0	SF				1	No	1/D
	Classroom 206	M N/A	Sheetrock Wall Wood Floor	6450/01/02/AET/BB/2100	Assumed	245	SF SF	0	SF SF				1	No No	1/D 1/D
	Classroom 206 Classroom 206 Large Closet	N/A T	Wood Floor Pipe Fitting Insulation	6450/01/02/16	Non Suspect ACM Confirmed	770 9	SF EA	0	SF EA		More likely above ceiling tile	1	1 1	No No	1/D 1/D
1 2	Classroom 206 Large Closet Classroom 206 Large Closet	N/A	Fiberglass Pipe Insulation	0430/01/02/16	Non Suspect ACM	50	LF	6	LF LF		iviore likely above celling tile		N/A	No N/A	N/A
1 2	Classroom 206 Large Closet Classroom 206 Large Closet	N/A	Ceiling Tile 2' x 4'		Non Suspect ACM	110	SF	0	SF				1	No No	1/D
	Classroom 206 Large Closet	N/A	Plaster Ceiling		NAD	110	SF	0	SF				1	No	1/D
1 2	Classroom 206 Large Closet	N/A	Plaster Walls		NAD	530	SF	0	SF				1	No	1/D
1 2	Classroom 206 Large Closet	N/A	Wood Floor		Non Suspect ACM	110	SF	0	SF				1	No	1/D
1 2	Classroom 206 Small Closet	х	x	Х	x	x	x	х	х		No Access	1	х	х	х
1 2	Classroom 207	+ .T	Pipe Insulation 2-6 inch	6450/01/02/17	Confirmed	24	LF	0	LF		More likely above ceiling tile	-	1	No No	1/D
	Classroom 207	N/A N/A	Fiberglass Ceiling Tile 2' x 4' Plaster Ceiling		Non Suspect ACM NAD	770 770	SF SF	0	SF SF				1 1	No No	1/D 1/D
	Classroom 207 Classroom 207	N/A N/A	Plaster Ceiling Plaster Walls	 	NAD NAD	1010	SF	0	SF		1		1	No	1/D
	Classroom 207	M M	Sheetrock Wall	6450/01/02/AET/BB/2100	Assumed	245	SF	0	SF				1	No	1/D
1 2	Classroom 207	N/A	Wood Floor	1	Non Suspect ACM	770	SF	0	SF			1	1	No	1/D
1 2	Classroom 207	M	Blackboard Glue Dots	6450/01/02/AET/BB/2600	Assumed	90	SF	0	SF				i	No	1/D
1 2	Classroom 207 Large Closet	T	Pipe Insulation 2-6 inch	6450/01/02/17	Confirmed	24	LF	0	LF		More likely above ceiling tile		1	No	1/D
1 2	Classroom 207 Large Closet	N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	110	SF	40	SF				N/A	N/A	N/A
1 2	Classroom 207 Large Closet	N/A	Plaster Ceiling		NAD NAD	110	SF SF	0	SF		<u> </u>	-	1	No	1/D 1/D
1 2	Classroom 207 Large Closet Classroom 207 Large Closet	N/A N/A	Plaster Walls Wood Floor		NAD Non Suspect ACM	530 110	SF SF	0	SF SF				1	No No	1/D 1/D
	Ciassicum 207 Large Closet	I IN/A	WOOD FIOOI		NOTI SUSPECT MOIN	110) or) or		1			INO	1/0

	School District of Philadelphia			NUEDA Thron-Voor	Reinspection 2015-2016						D-I			-	
-			1				,				Reinspection Date: 1/22-29/2016	-			ı
-	James Dobson Elementary School	-		Koom by Koom	Location Log Report]			Building Inspector: Bernard Brunner	-			ı
	4667 Umbria Street, Philadelphia, PA 19127										Certificate Number: 45397	_			ı
	ULCS# 6450										Management Planner: Monique Causley	_			ı
	Year Built: 1930										Certificate Number: ACC-0215-8-010				ı
								1							
E															
e F								'							
e F m I e o								'		Color		Attic Crawl	Damage		'
n o	On Site Room Name	System Affected	Material Description	HID#	Confirmed, Assumed, NAD, Non Suspect ACM	Amount of	SF LF EA	Amount of	SF LF I	required for VAT	Comments/Description/Notes	Space Ranking	Potential (DP)	Newly Friable (NF)	Response
1 2	Classroom 207 Small Closet	N/A	Plaster Ceiling	niv#	NAD NAD	Material 30	SF LF EA	Damage	SF	VAI	Continents/Description/Notes	reanking	1	No No) Action (RA) 1/D
	Classroom 207 Small Closet	N/A	Plaster Walls		NAD	180	SF	0	SF				1	No	1/D
	Classroom 207 Small Closet	N/A	Wood Floor		Non Suspect ACM	30	SF	0	SF				1	No	1/D
	2nd Floor Girl's Restroom	N/A N/A	Fiberglass Pipe Insulation		Non Suspect ACM	13 160	LF SF	0	LF SF				1	No No	1/D 1/D
1 2	2nd Floor Girl's Restroom 2nd Floor Girl's Restroom	N/A N/A	Concrete Ceiling Plaster Walls		Non Suspect ACM NAD	625	SF	0	SF				1	No	1/D
	2nd Floor Girl's Restroom	N/A	Ceramic Tile Walls		Non Suspect ACM	625	SF	0	SF				1	No	1/D
1 2	2nd Floor Girl's Restroom	N/A	Ceramic Tile Floors		Non Suspect ACM	160	SF	0	SF				1	No	1/D
	2nd Floor Girl's Restroom Pipe Shaft	T	Pipe Insulation 2-6 inch	6450/01/02/17	Confirmed	15	LF	0	LF				1	No	1/D
	2nd Floor Girl's Restroom Pipe Shaft 2nd Floor Girl's Restroom Pipe Chase	N/A	Pipe Insulation > 6 inch Fiberglass Pipe Insulation	6450/01/01/AET/BB/1110	Assumed Non Suspect ACM	15 25	LF I F	0	LF LF			_	1	No No	1/D 1/D
1 2	Classroom 208	T	Pipe Insulation 2-6 inch	6450/01/02/17	Confirmed	22	LF	0	LF		More likely above ceiling tile		1	No	1/D
1 2	Classroom 208	N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	770	SF	16	SF				N/A	N/A	N/A
	Classroom 208	N/A	Plaster Ceiling		NAD	770	SF	0	SF				1	No	1/D
	Classroom 208 Classroom 208	N/A N/A	Plaster Walls Partition Room Dividers		NAD Non Suspect ACM	1010 245	SF SF	0	SF SF		Wood Partition		1	No No	1/D 1/D
	Classroom 208	N/A	Wood Floor		Non Suspect ACM	770	SF	0	SF		YYOOG I GIGGOTI		1	No	1/D
1 2	Classroom 208	M	Blackboard Glue Dots	6450/01/02/AET/BB/2600	Assumed	130	SF	0	SF				1	No	1/D
	Classroom 208 Large Closet	N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	110	SF	16	SF				N/A	N/A	N/A
	Classroom 208 Large Closet	N/A	Plaster Ceiling		NAD	110	SF	0	SF				1	No	1/D
1 2	Classroom 208 Large Closet Classroom 208 Large Closet	N/A N/A	Plaster Walls Wood Floor		NAD Non Suspect ACM	530 110	SF SF	0	SF SF				1	No No	1/D 1/D
1 2	Classroom 208 Small Closet	N/A	Plaster Ceiling		NAD	30	SF	0	SF				1	No	1/D
	Classroom 208 Small Closet	N/A	Plaster Walls		NAD	180	SF	0	SF				1	No	1/D
	Classroom 208 Small Closet	N/A	Wood Floor		Non Suspect ACM	30	SF	0	SF				1	No	1/D
1 2	Classroom 209 Classroom 209	N/A	Pipe Insulation 2-6 inch Fiberglass Ceiling Tile 2' x 4'	6450/01/02/17	Confirmed Non Suspect ACM	24 770	LF SF	16	LF SF		More likely above ceiling tile		1 N/A	No N/A	1/D N/A
1 2	Classroom 209	N/A	Plaster Ceiling		NAD NAD	770	SF	0	SF				1	No.	1/D
1 2	Classroom 209	N/A	Plaster Walls		NAD	1010	SF	0	SF				1	No	1/D
	Classroom 209	N/A	Partition Room Dividers		Non Suspect ACM	245	SF	0	SF		Wood Partition		1	No	1/D
	Classroom 209 Classroom 209	N/A M	Wood Floor Blackboard Glue Dots	6450/01/02/AET/BB/2600	Non Suspect ACM Assumed	770 90	SF SF	0	SF SF				1	No No	1/D 1/D
	Classroom 209 Large Closet	T	Pipe Insulation 2-6 inch	6450/01/02/17	Confirmed	24	LF	0	LF		More likely above ceiling tile		1	No	1/D
1 2	Classroom 209 Large Closet	N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	110	SF	0	SF				1	No	1/D
1 2	Classroom 209 Large Closet	N/A	Plaster Ceiling		NAD	110	SF	0	SF				1	No	1/D
1 2	Classroom 209 Large Closet Classroom 209 Large Closet	N/A N/A	Plaster Walls Wood Floor		NAD Non Suspect ACM	530 110	SF SF	0	SF SF				1	No No	1/D 1/D
	Classroom 209 Small Closet	X	x	x	X	x	X	×	X		No Access		x	X	X X
1 2	Counselor's Office 210	Ť	Pipe Fitting Insulation	6450/01/02/16	Confirmed	1	EA	0	EA		More likely above ceiling tile		1	No	1/D
1 2	Counselor's Office 210	T	Pipe Insulation 2-6 inch	6450/01/02/17	Confirmed	48	LF	1	LF		Incidental DDC		1	Yes	5/B
	Counselor's Office 210	N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	252	SF SF	0 2	SF SF				1 N/A	No N/A	1/D
	Counselor's Office 210 Counselor's Office 210	N/A N/A	Plaster Ceiling Plaster Walls		NAD NAD	252 815	SF	5	SF				N/A N/A	N/A N/A	N/A N/A
1 2	Counselor's Office 210	М	Floor Tile VAT 12" x 12"	6450/01/02/FF	Assumed	252	SF	1	SF	Green	note type of damage		1	No	6/C
1 2	Counselor's Office 210	N/A	Cement Floor		Non Suspect ACM	252	SF	0	SF				1	No	1/D
1 2	Counselor's Office 210 Telecommunication Equipment Room (Former Projection	M	Blackboard Glue Dots	6450/01/02/AET/BB/2600	Assumed	100	SF	0	SF			+	1	No	1/D
1 2	Room)	N/A	Plaster Ceiling		NAD	96	SF	0	SF				1	No	1/D
1 0	Telecommunication Equipment Room (Former Projection	N/A	Digeter Wells		NAD	440	SF	0	SF				1	No	1/D
1 2	Room) Telecommunication Equipment Room (Former Projection		Plaster Walls									+	\vdash	INO	
1 2	Room)	N/A	Cement Floor		Non Suspect ACM	96	SF	0	SF				1 1	No	1/D
	Right Closet across from Classroom 206	N/A	Wood Ceiling Plaster Walls		Non Suspect ACM NAD	18 145	SF SF	0	SF SF			+	1	No No	1/D
1 2	Right Closet across from Classroom 206 Right Closet across from Classroom 206	N/A N/A	Cement Floor		NAD Non Suspect ACM	145	SF	0	SF			+	1	No No	1/D 1/D
1 2	Center Closet across from Classroom 206	N/A	Wood Ceiling		Non Suspect ACM	18	SF	0	SF			1	1	No	1/D
1 2	Center Closet across from Classroom 206	N/A	Plaster Walls		NAD	145	SF	0	SF				1	No	1/D
	Center Closet across from Classroom 206	N/A	Cement Floor		Non Suspect ACM	18	SF	0	SF				1	No No	1/D
	Left Closet across from Classroom 206 Left Closet across from Classroom 206	N/A N/A	Wood Ceiling Plaster Walls		Non Suspect ACM NAD	18 145	SF SF	0	SF SF			+	1	No No	1/D 1/D
1 2	Left Closet across from Classroom 206	N/A	Cement Floor		Non Suspect ACM	18	SF	0	SF				1	No	1/D
1 2	Right Closet across from Classroom 204	N/A	Wood Ceiling		Non Suspect ACM	18	SF	0	SF				1	No	1/D
	Right Closet across from Classroom 204	N/A	Plaster Walls		NAD	145	SF	0	SF				1	No	1/D
	Right Closet across from Classroom 204	N/A	Cement Floor		Non Suspect ACM	18	SF	0	SF				1	No	1/D
1 2			Wood Ceiling	I	Non Suspect ACM	18	SF I	1 0	SF I				1 1	No	1 1/D ·
1 2	Center Closet across from Classroom 204 Center Closet across from Classroom 204	N/A N/A	Wood Ceiling Plaster Walls		Non Suspect ACM NAD	18 145	SF SF	0	SF SF				1 1	No No	1/D 1/D

	School District of Philadelphia			AHERA Three-Year	Reinspection 2015-2016						Reinspection Date: 1/22-29/2016				
I	James Dobson Elementary School	İ			Location Log Report						Building Inspector: Bernard Brunner				I
	4667 Umbria Street, Philadelphia, PA 19127			•							Certificate Number: 45397				i
	ULCS# 6450	1									Management Planner: Monique Causley	_			
	1	1										-			
	Year Built: 1930										Certificate Number: ACC-0215-8-010				$\overline{}$
E I e F m I e o n o t r	On Site Room Name	System Affected	Material Description	HID#	Confirmed, Assumed, NAD, Non Suspect ACM	Amount of Material	SF LF EA	Amount of Damage	SF LF EA	Color required for VAT	Comments/Description/Notee	Attic Crawl Space Ranking	Damage Potential (DP)	Newly Friable (NF)	Response Action (RA)
	Left Closet across from Classroom 204	x	x	х	x	х	X	X	х		No Access		х	X	х
1 2	Hallway outside Classrooms 201-202	T N/A	Pipe Insulation 2-6 inch	6450/01/02/17	Confirmed	60	LF	0	LF		More likely above ceiling tile		1	No	1/D
1 2	Hallway outside Classrooms 201-202 Hallway outside Classrooms 201-202	N/A N/A	Fiberglass Pipe Insulation Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM Non Suspect ACM	34 639	LF SF	0	LF SF				1	No No	1/D 1/D
1 2	Hallway outside Classrooms 201-202	N/A	Plaster Ceiling		NAD	639	SF	0	SF				1	No	1/D
	Hallway outside Classrooms 201-202	N/A	Plaster Walls		NAD	1600	SF	0	SF				1	No	1/D
1 2	Hallway outside Classrooms 201-202	N/A	Marble Wall		Non Suspect ACM	605	SF	0	SF				1	No	1/D
	Hallway outside Classrooms 201-202	N/A	Cement Floor	0.450/0.4/00/45	Non Suspect ACM	639	SF	0	SF				1	No	1/D
1 2	Hallway outside Classrooms 203-207	T N/A	Pipe Insulation 2-6 inch	6450/01/02/17	Confirmed Non Suspect ACM	24 1332	LF LF	0	LF LF		More likely above ceiling tile	_	1	No No	1/D 1/D
1 2	Hallway outside Classrooms 203-207 Hallway outside Classrooms 203-207	N/A N/A	Fiberglass Ceiling Tile 2' x 4' Plaster Ceiling		Non Suspect ACM NAD	1332	SF	0	SF				1	No No	1/D
	Hallway outside Classrooms 203-207	N/A	Plaster Walls		NAD	2460	SF	0	SF				1	No	1/D
1 2	Hallway outside Classrooms 203-207	N/A	Marble Wall		Non Suspect ACM	985	SF	2	SF				N/A	N/A	N/A
1 2	Hallway outside Classrooms 203-207	N/A	Cement Floor		Non Suspect ACM	1332	SF	0	SF				1	No	1/D
1 2	Hallway outside Classrooms 208-209	T	Pipe Insulation 2-6 inch	6450/01/02/17	Confirmed	24	LF LF	0	LF LF		More likely above ceiling tile		1 1	No No	1/D
	Hallway outside Classrooms 208-209 Hallway outside Classrooms 208-209	N/A N/A	Fiberglass Pipe Insulation		Non Suspect ACM Non Suspect ACM	12 387	SF	0	SF				1	No	1/D 1/D
	Hallway outside Classrooms 208-209 Hallway outside Classrooms 208-209	N/A N/A	Fiberglass Ceiling Tile 2' x 4' Plaster Ceiling		Non Suspect ACM NAD	387	SF	0	SF				1	No No	1/D
	Hallway outside Classrooms 208-209	N/A	Plaster Walls		NAD	1040	SF	5	SF				N/A	N/A	N/A
	Hallway outside Classrooms 208-209	N/A	Marble Wall		Non Suspect ACM	380	SF	0	SF				1	No	1/D
1 2	Hallway outside Classrooms 208-209	N/A	Cement Floor		Non Suspect ACM	387	SF	0	SF				1	No	1/D
	Boy's Side Stairwell	T	Pipe Fitting Insulation	6450/01/02/16 6450/01/02/17	Confirmed	8	EA LF	0	EA LF				1 1	No No	1/D
	Boy's Side Stairwell Boy's Side Stairwell	N/A	Pipe Insulation 2-6 inch Concrete Ceiling	6450/01/02/17	Confirmed Non Suspect ACM	31 265	SF	5	SF				N/A	N/A	1/D N/A
1 2	Boy's Side Stairwell	N/A	Plaster Walls		NAD	1400	SF	0	SF				1	No	1/D
1 2	Boy's Side Stairwell	N/A	Marble Wall		Non Suspect ACM	470	SF	5	SF				N/A	N/A	N/A
1 2	Boy's Side Stairwell	N/A	Cement Floor		Non Suspect ACM	265	SF	0	SF				1	No	1/D
	Girl's Side Stairwell	Ţ	Pipe Fitting Insulation	6450/01/02/16	Confirmed	8	EA	0	EA				1	No	1/D
1 2	Girl's Side Stairwell Girl's Side Stairwell	N/A	Pipe Insulation 2-6 inch Concrete Ceiling	6450/01/02/17	Confirmed Non Suspect ACM	31 265	LF SF	5	LF SF				1 N/A	No N/A	1/D N/A
	Girl's Side Stairwell	N/A	Plaster Walls		NAD	1400	SF	25	SF				N/A	N/A	N/A
1 2	Girl's Side Stairwell	N/A	Marble Wall		Non Suspect ACM	470	SF	0	SF				1	No	1/D
	Girl's Side Stairwell	N/A	Cement Floor		Non Suspect ACM	265	SF	0	SF				1	No	1/D
	School Psychologist Office	T	Pipe Insulation 2-6 inch	6450/01/01/12	Confirmed	24	LF	0	LF		More likely above ceiling tile		1	No	1/D
	School Psychologist Office School Psychologist Office	N/A N/A	Fiberglass Ceiling Tile 2' x 4' Plaster Ceiling		Non Suspect ACM NAD	90 90	SF SF	8	SF SF			_	N/A 1	N/A No	N/A 1/D
1 1	School Psychologist Office	N/A	Plaster Walls		NAD	440	SF	0	SF				1	No	1/D
1 1	School Psychologist Office	M	Floor Tile VAT 9" x 9"	6450/01/01/10	Confirmed	90	SF	0	SF	Green			1	No	1/D
1 1	School Psychologist Office	N/A	Cement Floor		Non Suspect ACM	90	SF	0	SF				1	No	1/D
	Men's Restroom adjacent to Classroom 101	N/A	Ceiling Tile 2' x 4'		Non Suspect ACM	110	SF	0	SF				1	No	1/D
	Men's Restroom adjacent to Classroom 101	N/A	Plaster Ceiling		NAD	162	SF SF	5	SF SF				N/A 1	N/A	N/A
1 1	Men's Restroom adjacent to Classroom 101 Men's Restroom adjacent to Classroom 101	N/A N/A	Plaster Walls Ceramic Tile Walls		NAD Non Suspect ACM	540 540	SF	0	SF				1	No No	1/D 1/D
1 1	Men's Restroom adjacent to Classroom 101	N/A	Ceramic Tile Floors		Non Suspect ACM	162	SF	0	SF				1	No	1/D
1 1	Classroom 101	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	6	LF	0	LF				1	No	1/D
	Classroom 101	N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	1075	SF	32	SF				N/A	N/A	N/A
1 1	Classroom 101 Classroom 101	N/A N/A	Plaster Ceiling Plaster Walls		NAD NAD	1075 1455	SF SF	0	SF SF				1	No No	1/D 1/D
	Classroom 101 Classroom 101	N/A N/A	Cement Floor		Non Suspect ACM	1075	SF	0	SF				1	No No	1/D
1 1	Classroom 101	N/A	Carpet		Non Suspect ACM	170	SF	0	SF				1	No	1/D
1 1	Classroom 101	M	Blackboard Glue Dots	6450/01/01/AET/BB/2600	Assumed	100	SF	0	SF				1	No	1/D
1 1	Classroom 101	M	Linoleum	6450/01/01/AET/BB/2200	Assumed	1075	SF SF	0	SF				1	No	1/D
1 1	Classroom 101 Boy's Restroom Classroom 101 Boy's Restroom	N/A N/A	Fiberglass Pipe Insulation Plaster Ceiling		Non Suspect ACM NAD	8 50	SF LF	0	SF LF				1 1	No No	1/D 1/D
	Classroom 101 Boy's Restroom Classroom 101 Boy's Restroom	N/A N/A	Plaster Ceiling Plaster Walls		NAD NAD	360	SF	0	SF				1	No No	1/D 1/D
	Classroom 101 Boy's Restroom	N/A	Ceramic Tile Walls		Non Suspect ACM	360	SF	0	SF				1	No	1/D
1 1	Classroom 101 Boy's Restroom	N/A	Ceramic Tile Floors		Non Suspect ACM	50	SF	0	SF				1	No	1/D
1 1	Classroom 101 Small Closet	N/A	Plaster Ceiling		NAD	40	SF	0	SF				1	No	1/D
1 1	Classroom 101 Small Closet Classroom 101 Small Closet	N/A M	Plaster Walls	6450/01/01/AET/BB/2100	NAD Assumed	195 70	SF SF	0	SF SF				1	No No	1/D 1/D
	Classroom 101 Small Closet Classroom 101 Small Closet	N/A	Sheetrock Wall Cement Floor	0450/01/01/AE1/BB/2100	Assumed Non Suspect ACM	40	SF	0	SF				1	No No	1/D 1/D
	Classroom 101 Small Closet	M	Linoleum	6450/01/01/AET/BB/2200	Assumed	40	SF	0	SF				1	No	1/D
	Classroom 101 Large Closet	Т	Pipe Fitting Insulation	6450/01/01/09	Confirmed	2	EA	0	EA				1	No	1/D
1 1	Classroom 101 Large Closet	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	10	LF	0	LF				1	No	1/D
	Classroom 101 Large Closet	N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	60	SF	0	SF			_	1	No No	1/D
1 1	Classroom 101 Large Closet Classroom 101 Large Closet	N/A N/A	Plaster Ceiling Plaster Walls		NAD NAD	60 355	SF SF	0	SF SF				1 1	No No	1/D 1/D
444	Jointon Control To 1 Early Colodel	14//	i idotol VVallo		INAD	555	UI	J	U		i		_ '	110	

	School District of Philadelphia				Reinspection 2015-2016						Reinspection Date: 1/22-29/2016				
	James Dobson Elementary School			Room by Room	Location Log Report						Building Inspector: Bernard Brunner				
	4667 Umbria Street, Philadelphia, PA 19127										Certificate Number: 45397				
1	ULCS# 6450	I									Management Planner: Monique Causley	7			
1		1										7			
\vdash	Year Built: 1930					1					Certificate Number: ACC-0215-8-010				
m e n t	F I O O O O O O O O O O O O O O O O O O	System Affected	Material Description	HID#	Confirmed, Assumed, NAD, Non Suspect ACM	Amount of Material	SF LF EA	Amount of Damage	SF LF requ	Color ulred for VAT	Comments/Description/Notes	Attic Crawi Space Ranking	Damage Potential (DP)	Newly Friable (NF)	Response Action (RA)
	1 Classroom 101 Large Closet	M	Floor Tile VAT 12" x 12"	6450/01/01/EE	Assumed	60	SF	0		Tan			1	No	1/D
1 1	1 Classroom 101 Large Closet 1 Classroom 101 Girl's Restroom	N/A N/A	Cement Floor Plaster Ceiling		Non Suspect ACM NAD	60	SF SF	0	SF SF			-	1	No No	1/D 1/D
	1 Classroom 101 Girl's Restroom	N/A	Plaster Walls		NAD	355	SF	0	SF				1	No	1/D
	1 Classroom 101 Girl's Restroom	N/A	Ceramic Tile Walls		Non Suspect ACM	355	SF	0	SF				1	No	1/D
	1 Classroom 101 Girl's Restroom	N/A	Ceramic Tile Floors		Non Suspect ACM	60	SF	0	SF				1	No	1/D
1	1 Classroom 101 Girl's Restroom Pipe Chase	х	x	х	x	х	х	x	х		No Access - Ladder needed to access		х	х	x
1	1 Nurse's Office	N/A	Ceiling Tile 2' x 4'		Non Suspect ACM	220	SF	0	SF				1	No	1/D
	1 Nurse's Office	N/A	Plaster Ceiling		NAD	220	SF	0	SF				1	No	1/D
	1 Nurse's Office	N/A	Plaster Walls		NAD Nan Suggest ACM	750	SF	0	SF				1	No	1/D
	1 Nurse's Office	N/A	Ceramic Tile Walls		Non Suspect ACM	750	SF SF	0	SF SF			1	1	No No	1/D
1	1 Nurse's Office 1 Nurse's Office Restroom	N/A M	Ceramic Tile Floors Ceiling Tile 2' x 2'	6450/01/01/AET/BB/1730	Non Suspect ACM Assumed	220 50	SF	0	SF			1	1	No No	1/D 1/D
1	Nurse's Office Restroom	N/A	Plaster Ceiling	5.55.5 NO NAL NEBO 1750	NAD	50	SF	0	SF				1	No	1/D
1	1 Nurse's Office Restroom	N/A	Plaster Walls		NAD	260	SF	0	SF				1	No	1/D
1	1 Nurse's Office Restroom	N/A	Ceramic Tile Walls		Non Suspect ACM	260	SF	0	SF				1	No	1/D
	1 Nurse's Office Restroom	N/A	Ceramic Tile Floors		Non Suspect ACM	50	SF	0	SF				1	No	1/D
1	1 1st Floor Boy's Restroom	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	15	LF	1	LF				N/A	N/A	N/A
1	1 1st Floor Boy's Restroom	N/A	Concrete Ceiling		Non Suspect ACM	160	SF	0	SF				1	No	1/D
	1 1st Floor Boy's Restroom	N/A N/A	Plaster Walls Ceramic Tile Walls		NAD Non Suspect ACM	625	SF SF	0	SF SF				1	No No	1/D 1/D
1	1 1st Floor Boy's Restroom 1 1st Floor Boy's Restroom	N/A	Ceramic Tile Walls		Non Suspect ACM	625 160	SF	0	SF				1	No	1/D
1	1 1st Floor Boy's Restroom Pipe Chase	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	75	LF	5	LF				N/A	N/A	N/A
1	Custodial Closet adjacent to 1st Floor Boy's Restroom	N/A	Plaster Ceiling		NAD	20	SF	0	SF				1	No	1/D
1	Custodial Closet adjacent to 1st Floor Boy's Restroom	N/A	Plaster Walls		NAD	180	SF	0	SF				1	No	1/D
	Custodial Closet adjacent to 1st Floor Boy's Restroom	N/A	Ceramic Tile Walls		Non Suspect ACM	180	SF	0	SF				1	No	1/D
	1 Custodial Closet adjacent to 1st Floor Boy's Restroom	N/A	Ceramic Tile Floors	0.450/0.4/0.4/40	Non Suspect ACM	20	SF	0	SF				1	No	1/D
1	1 Classroom 103 1 Classroom 103	T N/A	Pipe Insulation 2-6 inch Fiberglass Ceiling Tile 2' x 4'	6450/01/01/12	Confirmed Non Suspect ACM	24 770	LF SF	0	LF SF		More likely above ceiling tile		1	No No	1/D 1/D
1	1 Classroom 103	N/A	Plaster Ceiling		NAD NAD	770	SF	0	SF				1	No	1/D
	1 Classroom 103	N/A	Plaster Walls		NAD	1010	SF	0	SF				1	No	1/D
	1 Classroom 103	N/A	Partition Room Dividers		Non Suspect ACM	245	SF	0	SF		Wood Partition		1	No	1/D
1	1 Classroom 103	N/A	Wood Floor		Non Suspect ACM	770	SF	0	SF				1	No	1/D
1	1 Classroom 103	M	Blackboard Glue Dots	6450/01/01/AET/BB/2600	Assumed	130	SF	0	SF				1	No	1/D
1	1 Classroom 103 Large Closet	T	Pipe Insulation 2-6 inch	6450/01/01/12	Confirmed	24	LF	0	LF		More likely above ceiling tile		1	No	1/D
	1 Classroom 103 Large Closet 1 Classroom 103 Large Closet	N/A N/A	Fiberglass Ceiling Tile 2' x 4' Plaster Ceiling		Non Suspect ACM NAD	110 110	SF SF	0	SF SF				N/A 1	N/A No	N/A 1/D
	1 Classroom 103 Large Closet	N/A	Plaster Walls		NAD	530	SF	0	SF				1	No	1/D
1	1 Classroom 103 Large Closet	N/A	Wood Floor		Non Suspect ACM	110	SF	0	SF				1	No	1/D
	1 Classroom 103 Small Closet	N/A	Plaster Ceiling		NAD	30	SF	0	SF				1	No	1/D
1	1 Classroom 103 Small Closet	N/A	Plaster Walls		NAD	180	SF	0	SF				1	No	1/D
	1 Classroom 103 Small Closet	N/A	Wood Floor		Non Suspect ACM	30	SF	0	SF				1	No	1/D
1 1	1 Classroom 104 1 Classroom 104	T	Pipe Fitting Insulation Pipe Insulation 2-6 inch	6450/01/01/09 6450/01/01/12	Confirmed Confirmed	8 24	EA LF	0	LF LF		More likely above ceiling tile	1	1	No No	1/D 1/D
	1 Classroom 104 1 Classroom 104	N/A	Fiberglass Ceiling Tile 2' x 4'	0430/01/01/12	Non Suspect ACM	814	SF	. U	SF		INFORCE III ADDOVE CEILING THE	1	N/A	No N/A	N/A
1	1 Classroom 104	N/A	Plaster Ceiling		NAD	814	SF	0	SF			1	1 1	No.	1/D
	1 Classroom 104	N/A	Plaster Walls		NAD	1055	SF	0	SF				1	No	1/D
1	1 Classroom 104	N/A	Partition Room Dividers		Non Suspect ACM	245	SF	0	SF		Wood Partition		1	No	1/D
1	1 Classroom 104	N/A	Wood Floor		Non Suspect ACM	814	SF	0	SF			1	1	No	1/D
1	1 Classroom 104	M N/A	Blackboard Glue Dots	6450/01/01/AET/BB/2600	Assumed	90 115	SF SF	0	SF SF			1	1	No	1/D 1/D
1	1 Classroom 104 Large Closet 1 Classroom 104 Large Closet	N/A N/A	Fiberglass Ceiling Tile 2' x 4' Plaster Ceiling		Non Suspect ACM NAD	115	SF SF	0	SF SF			+	1	No No	1/D 1/D
	1 Classroom 104 Large Closet 1 Classroom 104 Large Closet	N/A N/A	Plaster Ceiling Plaster Walls		NAD NAD	530	SF	0	SF				1	No No	1/D
	1 Classroom 104 Large Closet	N/A	Wood Floor		Non Suspect ACM	115	SF	0	SF				1	No	1/D
1	1 Classroom 104 Small Closet	N/A	Plaster Ceiling		NAD	40	SF	0	SF				11	No	1/D
1	1 Classroom 104 Small Closet	N/A	Plaster Walls		NAD	210	SF	0	SF				1	No	1/D
	1 Classroom 104 Small Closet	N/A	Wood Floor	0.450/0.11111	Non Suspect ACM	40	SF	0	SF				1	No	1/D
	1 Main Office	T	Pipe Fitting Insulation	6450/01/01/09	Confirmed	4	EA	0	EA		Mara likalu ahaya sailing 411-	-	1	No No	1/D
	1 Main Office 1 Main Office	N/A	Pipe Insulation 2-6 inch Fiberglass Pipe Insulation	6450/01/01/12	Confirmed Non Suspect ACM	36 4	LF LF	0	LF LF		More likely above ceiling tile	1	1	No No	1/D 1/D
	1 Main Office	N/A	Ceiling Tile 2' x 4'		Non Suspect ACM	460	SF	0	SF			1	1	No	1/D
1	1 Main Office	N/A	Plaster Ceiling		NAD NAD	460	SF	0	SF				1	No	1/D
1	1 Main Office	N/A	Plaster Walls		NAD	905	SF	0	SF				1	No	1/D
	1 Main Office	M	Floor Tile VAT 12" x 12"	6450/01/01/EE	Assumed	460	SF	0	SF (Grey			1	No	1/D
	1 Main Office	N/A	Cement Floor		Non Suspect ACM	460	SF	0	SF			-	1	No	1/D
	1 Main Office Large Closet	T T	Pipe Fitting Insulation	6450/01/01/09	Confirmed	4	EA	0	EA			1	1	No	1/D
	1 Main Office Large Closet	N/A	Fiberglass Pipe Insulation	I	Non Suspect ACM	36	LF	0	LF		I	1	11	No	1/D

	School District of Philadelphia			AHERA Three-Year	Reinspection 2015-2016						Reinspection Date: 1/22-29/2016				
	James Dobson Elementary School	1		Room by Room	Location Log Report			İ			Building Inspector: Bernard Brunner	1			I
1	4667 Umbria Street, Philadelphia, PA 19127	i		•							Certificate Number: 45397	1			I
1	ULCS# 6450	1									Management Planner: Monique Causley	1			1
	i e											+			1
	Year Built: 1930		1								Certificate Number: ACC-0215-8-010				
E															1
															1 1
e F															1 1
e o										Color		Attic Crawl	Damage		1 1
n o	On Site Room Name	System Affected	Material Description	HID#	Confirmed, Assumed, NAD, Non Suspect ACM	Amount of Material	SF LF EA	Amount of Damage	SF LF	required for VAT	Comments/Description/Notes	Space Ranking	Potential (DP)	Newly Friable (NF)	Response Action (RA)
	Main Office Large Closet	N/A	Plaster Ceiling	IIID#	NAD	96	SF	0	SF	V/\/	CommentarDescription (Notes	Reliving	1	No No	1/D
	Main Office Large Closet	N/A	Plaster Walls		NAD	485	SF	0	SF				1	No	1/D
1 1	Main Office Large Closet	M	Floor Tile VAT 12" x 12"	6450/01/01/EE	Assumed	96	SF	0	SF	Grey			1	No	1/D
1 1	Main Office Large Closet	N/A	Cement Floor		Non Suspect ACM	96 18	SF	0	SF				1	No	1/D
1 1	Main Office Small Closet Main Office Small Closet	N/A N/A	Plaster Ceiling Plaster Walls		NAD NAD	200	SF SF	0	SF SF				1	No No	1/D 1/D
	Main Office Small Closet	M	Floor Tile VAT 12" x 12"	6450/01/01/EE	Assumed	18	SF	0	SF	Grey			1	No	1/D
	Main Office Small Closet	N/A	Cement Floor		Non Suspect ACM	18	SF	0	SF				1	No	1/D
1 1	Principal's Office	Т	Pipe Insulation 2-6 inch	6450/01/01/12	Confirmed	12	LF	0	LF		More likely above ceiling tile		1	No	1/D
1 1	Principal's Office Principal's Office	N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	270 270	SF SF	0	SF SF				1	No	1/D
	Principal's Office Principal's Office	N/A N/A	Plaster Ceiling Plaster Walls		NAD NAD	705	SF	0	SF				1	No No	1/D 1/D
											Unable to determine if there is any floor tile below		'		
	Principal's Office	N/A	Carpet		Non Suspect ACM	270	SF	0	SF		the carpet		1	No	1/D
	Principal's Office Principal's Office Restroom	N/A N/A	Cement Floor Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM Non Suspect ACM	270 48	SF SF	0	SF SF				1	No No	1/D 1/D
	Principal's Office Restroom Principal's Office Restroom	N/A N/A	Plaster Ceiling		NOT SUSPECT ACM NAD	48	SF	0	SF				1	No	1/D
1 1	Principal's Office Restroom	N/A	Plaster Walls		NAD	310	SF	Ö	SF				1	No	1/D
1 1	Principal's Office Restroom	N/A	Ceramic Tile Walls		Non Suspect ACM	310	SF	0	SF				1	No	1/D
	Principal's Office Restroom	N/A	Ceramic Tile Floors		Non Suspect ACM	48	SF	0	SF				1	No	1/D
1 1	Classroom 106 Classroom 106	T N/A	Pipe Insulation 2-6 inch Fiberglass Ceiling Tile 2' x 4'	6450/01/01/12	Confirmed Non Suspect ACM	24 630	LF SF	0	LF SF		More likely above ceiling tile		1	No No	1/D 1/D
1 1	Classroom 106	N/A	Ceiling Tile 2' x 4'		Non Suspect ACM	60	SF	0	SF				1	No	1/D
1 1	Classroom 106	N/A	Plaster Ceiling		NAD	690	SF	0	SF				1	No	1/D
1 1	Classroom 106	N/A	Plaster Walls		NAD	1145	SF	0	SF				1	No	1/D
	Classroom 106 Classroom 106	N/A	Floor Tile VAT 12" x 12" Wood Floor	6450/01/01/EE	Assumed	690 690	SF SF	0	SF SF	Tan			1	No No	1/D 1/D
	Classroom 106	M M	Blackboard Glue Dots	6450/01/01/AET/BB/2600	Non Suspect ACM Assumed	190	SF	0	SF				1	No	1/D
	Classroom 106 Restroom	N/A	Fiberglass Pipe Insulation	0 100/0 1/0 1// 12 1/25/2000	Non Suspect ACM	16	LF	5	LF				N/A	N/A	N/A
1 1	Classroom 106 Restroom	N/A	Plaster Ceiling		NAD	40	SF	0	SF				1	No	1/D
	Classroom 106 Restroom	N/A N/A	Plaster Walls Ceramic Tile Walls		NAD NAT OWN	235 290	SF SF	0	SF SF				1	No No	1/D 1/D
	Classroom 106 Restroom Classroom 106 Restroom	M M	Sheetrock Wall	6450/01/01/AET/BB/2100	Non Suspect ACM Assumed	290 55	SF	0	SF				1	No	1/D
1 1	Classroom 106 Restroom	N/A	Ceramic Tile Floors	0430/01/01/AE1/BB/2100	Non Suspect ACM	40	SF	Ö	SF				1	No	1/D
1 1	Classroom 106 Laundry Room	N/A	Plaster Ceiling		NAD	40	SF	0	SF				1	No	1/D
	Classroom 106 Laundry Room	N/A M	Plaster Walls	6450/01/01/AET/BB/2100	NAD	235	SF	0	SF				1	No	1/D
	Classroom 106 Laundry Room Classroom 106 Laundry Room	M	Sheetrock Wall Floor Tile VAT 12" x 12"	6450/01/01/AE1/BB/2100	Assumed Assumed	55 40	SF SF	0	SF SF	Tan			1	No No	1/D
1 1	Classroom 106 Laundry Room	N/A	Wood Floor	0430/01/01/EE	Non Suspect ACM	40	SF	Ö	SF	Tan			1	No	1/D
1 1	Classroom 106 Laundry Room Pipe Chase	M	Sheetrock Wall	6450/01/01/AET/BB/2100	Assumed	110	SF	0	SF				1	No	1/D
	Classroom 106 Closet	N/A	Plaster Ceiling		NAD	25	SF	0	SF				1	No	1/D
	Classroom 106 Closet Classroom 106 Closet	N/A N/A	Plaster Walls Wood Floor		NAD Non Suspect ACM	180 25	SF SF	0	SF SF				1	No No	1/D 1/D
1 1	1st Floor Girl's Restroom	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	13	LF	0	LF				1	No	1/D
1 1	1st Floor Girl's Restroom	N/A	Concrete Ceiling		Non Suspect ACM	160	SF	0	SF				1	No	1/D
	1st Floor Girl's Restroom	N/A	Plaster Walls		NAD Nac Owner of AOM	625	SF	0	SF				1	No	1/D
	1st Floor Girl's Restroom 1st Floor Girl's Restroom	N/A N/A	Ceramic Tile Walls Ceramic Tile Floors		Non Suspect ACM Non Suspect ACM	625 160	SF SF	0	SF SF				1	No No	1/D 1/D
	1st Floor Girl's Restroom Pipe Shaft	T	Pipe Insulation 2-6 inch	6450/01/01/12	Confirmed	15	LF	0	LF				1	No	1/D
1 1	1st Floor Girl's Restroom Pipe Shaft	T	Pipe Insulation > 6 inch	6450/01/02/AET/BB/1110	Assumed	15	LF	0	LF				1	No	1/D
	1st Floor Girl's Restroom Pipe Chase	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	25	LF	5	LF				N/A	N/A	N/A
	Classroom 107 Classroom 107	T	Pipe Fitting Insulation Pipe Insulation 2-6 inch	6450/01/01/09 6450/01/01/12	Confirmed Confirmed	8 24	EA LF	0	EA LF		More likely above ceiling tile		1	No No	1/D 1/D
1 1	Classroom 107	N/A	Fiberglass Ceiling Tile 2' x 4'	0430/01/01/12	Non Suspect ACM	770	SF	56	SF		Word interly above ceiling the		N/A	N/A	N/A
1 1	Classroom 107	N/A	Plaster Ceiling		NAD	770	SF	0	SF				1	No	1/D
	Classroom 107	N/A	Plaster Walls		NAD	1010	SF	0	SF		W 15 W		1	No	1/D
	Classroom 107 Classroom 107	N/A N/A	Partition Room Dividers Wood Floor		Non Suspect ACM Non Suspect ACM	245 770	SF SF	0	SF SF		Wood Partition		1	No No	1/D 1/D
	Classroom 107	M	Blackboard Glue Dots	6450/01/01/AET/BB/2600	Assumed	130	SF	0	SF				1	No	1/D
1 1	Classroom 107 Large Closet	N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	90	SF	0	SF				1	No	1/D
1 1	Classroom 107 Large Closet	N/A	Plaster Ceiling		NAD	90	SF	0	SF				1	No	1/D
1 1	Classroom 107 Large Closet Classroom 107 Large Closet	N/A N/A	Plaster Walls Wood Floor		NAD Non Suspect ACM	555 90	SF SF	8	SF SF				1 N/A	No N/A	1/D N/A
	Classroom 107 Large Closet Classroom 107 Small Closet	N/A N/A	Plaster Ceiling		NOT SUSPECT ACM NAD	25	SF	0	SF				1 1	N/A No	1/D
1 1	Classroom 107 Small Closet	N/A	Plaster Walls		NAD	160	SF	0	SF				1	No	1/D
1 1	Classroom 107 Small Closet	N/A	Wood Floor	0.450.00	Non Suspect ACM	25	SF	0	SF				1	No	1/D
1 1 1	Classroom 108	T	Pipe Insulation 2-6 inch	6450/01/01/12	Confirmed	24	LF	0	LF		More likely above ceiling tile		1	No	1/D

Room by Room Location Log Report					Reinspection Date: 1/22-29/2016	$\overline{}$					Reinspection 2015-2016	AHEDA Three-Vest		T	School District of Philadelphia
## 1					•						•		•	1	·
Management Man								I			Location Log Report	Room by Room		1	
Part				1	Certificate Number: 45397	ŀ								1	4667 Umbria Street, Philadelphia, PA 19127
Fig. Fig.				1	Management Planner: Monique Causley	Į.								1	ULCS# 6450
April Continued Assemble Confirmed Assemble					Certificate Number: ACC-0215-8-010										Year Built: 1930
April Continued Assemble Confirmed Assemble															
											ļ				F
F F Control Section Co											ļ				é F
F F Control Section Co		Damana	l Da			Color					ļ				m 1
1 Conscion 150	Newly F	Potential	Pot	Attic Crawi Space		aulred for	SF LF	Amount of			Confirmed, Assumed, NAD,			System	n o
1	Friable (NF) A			Ranking	Comments/Description/Notes	VAT		Damage				HID#			
1	No No	1	+	\rightarrow		\longrightarrow		0				+			
1 Conserve 100	No	$\frac{1}{1}$	+			-		Ŭ				+			
1 Control Control Control Contro	No	1	1		Vood Partition	-	SF	0	SF	245					
1 Colorano 10 Large Coloral 7 Per Installation 20 into 1 1 1 1 1 1 1 1 1	No							0							
1 1 1 1 1 1 1 1 1 1	No		_	,		\longrightarrow		_						M	
1 1	No No		_		fore likely above ceiling tile			Ŭ		24		6450/01/01/12	Pipe Insulation 2-6 inch	T	1 1 Classroom 108 Large Closet
1	No No			\rightarrow		\longrightarrow	SF	-		110		+			
1	No	1	t			-		0				6450/01/01/AET/BB/2100			1 1 Classroom 108 Large Closet
1 1 Characterist Sharel Covert NA Planet Vision NA Planet	No	1					SF	0	SF	530	NAD		Plaster Walls	N/A	1 1 Classroom 108 Large Closet
1 1 Collegement (16 Senal Closed)	No	1	Ψ_			\longrightarrow		0							1 1 Classroom 108 Large Closet
1 1 Office elegent to Warmer's Recom	No	1	+-			\longrightarrow		0				 			
1 1 1 1 1 1 1 1 1 1	No No		_	\rightarrow		\longrightarrow	SF	Ŭ				 			1 1 Classroom 108 Small Closet
1 1 10 10 10 10 10 10	No				fore likely above ceiling tile							6450/01/01/12			
1 1 10 10 10 10 10 10	No		-		7		SF		SF	90	Non Suspect ACM			N/A	1 1 Office adjacent to Women's Room
1 1 Office adjacent b Woman's Room	No						SF		SF	90	NAD		Plaster Ceiling		1 1 Office adjacent to Women's Room
1 1 Nomer's Petron adjacent to Classroom 100	No			,			SF			420					
1 1 Women's Relations adjacent to Classroom 108	No		-	$\overline{}$		Tan		_				6450/01/01/EE			
1 1 Women's Relations adjacent to Classroom 108	No No		_			+		_				+			
1 1 Moment's Resistoon adjacent to Classocont 108	No					-		Ů			Non Suspect ACM				
1 1 Women's Restroom adjacent to Classroom 108	No	1					SF	0	SF	162					
1 1 Auditorium singue, responsible of the control of the con	No		_					Ů							1 1 Women's Restroom adjacent to Classroom 108
1 1 Audothrum	No		_	,				-							
1 1 Auditorium	No No	1	+	-		\longrightarrow		0				+			
1 1 Auditorium	No	+	+-	$\overline{}$		\rightarrow		0		5250		+			1 1 Auditorium
1 1 Auditorium Stage	No	1	1							1000					
1 1 Auditorium Stage	No		_					-						N/A	
1 1 Auditorium State N/A Plaster Walls N/A Plaster Celling N/A	No	1	₩					- ŭ				6450/01/01/KK		T	
1 1 Auditorium Storage Room to Left of Stage	No No	1	+			\longrightarrow		Ů				+			1 1 Auditorium Stage
1 1 Auditorium Storage Room to Left of Stage	No			\rightarrow		-						+			1 1 Auditorium Stage
1 1 Auditorium Storage Room to Left of Stage	No	1	T					0							1 1 Auditorium Storage Room to Left of Stage
1 1 Auditorium Storage Room to Left of Stage	No	1						0			10.00				1 1 Auditorium Storage Room to Left of Stage
1 1 Auditorium Storage Room to Right of Stage Restroom	No			,		Tan						6450/01/01/EE			1 1 Auditorium Storage Room to Left of Stage
1 Auditorium Storage Room to Right of Stage Restroom N/A	No No			-		\longrightarrow		_				+			1 1 Auditorium Storage Room to Left of Stage
1 Auditorium Storage Room to Right of Stage Restroom	No					\rightarrow				220		+	Plaster Walls		1 1 Auditorium Storage Room to Right of Stage Restroom
1 Auditorium Storage Room to Right of Stage Restroom N/A	No		_			-		_							
1 Auditorium Storage Room to Right of Stage Restroom NA Vinyl Vibration Damper Cloth Non Suspect ACM 1 SF 0 SF 1 SF 1 Auditorium Storage Room to Right of Stage NIA Plaster Walls NAD 410 SF 0 SF 0 SF 1 SF 1 Auditorium Storage Room to Right of Stage NIA Plaster Walls NAD 410 SF 0 SF 0 SF 1 SF Tan note type of damage 1 1 Auditorium Storage Room to Right of Stage NIA Plaster Walls NAD 410 SF 0 SF 1 SF Tan note type of damage 1 1 1 Left Closet across from Classroom 104 NIA Wood Floor Non Suspect ACM 60 SF 0 SF SF NIA Non Suspect ACM 18 SF 0 SF NIA NIA NIA Plaster Walls NIA Non Suspect ACM 18 SF 0 SF NIA NIA NIA Plaster Walls NIA NIA NIA Plaster Walls NIA No						SF		SF	20	Non Suspect ACM		Ceramic Tile Floors	N/A	1 1 Auditorium Storage Room to Right of Stage Restroom	
1 Auditorium Storage Room to Right of Stage N/A Plaster Walls NAD 410 SF 0 SF 1 SF Tan note type of damage 1 1 Auditorium Storage Room to Right of Stage N/A Wood Floor Non Suspect ACM 60 SF 1 SF Tan note type of damage 1 1 1 Auditorium Storage Room to Right of Stage N/A Wood Floor Non Suspect ACM 60 SF 0 SF SF Tan note type of damage 1 1 1 Left Closet across from Classroom 104 N/A Wood Celling Non Suspect ACM 18 SF 0 SF SF N/A SF N/A N/A Plaster Walls N/A N/A Cement Floor Non Suspect ACM 18 SF 0 SF N/A N/A Cement Floor Non Suspect ACM 18 SF 0 SF N/A N/A Cement Floor N/A N/A Plaster Walls N/A N/A N/A Plaster Walls N/A N/A Plaster Walls N/A N/A Plaster Walls N/A N/A Plaster Walls N/A N	No							_			Non Suspect ACM	1			1 1 Auditorium Storage Room to Right of Stage Restroom
1 Auditorium Storage Room to Right of Stage M Floor Tile VA1 12" x 12" 6450/01/01/EE Assumed 60 SF 1 SF Tan note type of damage 1	No No					\longrightarrow				60		 			1 1 Auditorium Storage Room to Right of Stage
1 Auditorium Storage Room to Right of Stage	No		_	\rightarrow	ote type of damage	Tan		_				6450/01/01/FF			
1 Left Closet across from Classroom 104	No			-	and the or demands					60		5 15 5 10 11 EL			
1 Left Closet across from Classroom 104	No	1					SF	0	SF	18	Non Suspect ACM			N/A	1 1 Left Closet across from Classroom 104
1 Center Closet across from Classroom 104	No	1	₩				SF								1 1 Left Closet across from Classroom 104
1 Center Closet across from Classroom 104	No No	1	+	$\overline{}$		\longrightarrow		_				+			
1 Center Closet across from Classroom 104	No No		_			\longrightarrow						+			
1 Right Closet across from Classroom 104	No	1	<u> </u>					_							
1 Right Closet across from Classroom 104	No		_				SF		SF	18	Non Suspect ACM		Wood Ceiling	N/A	1 1 Right Closet across from Classroom 104
1 Left Closet across from Classroom 106	No		-									1			1 1 Right Closet across from Classroom 104
1 1 Left Closet across from Classroom 106 N/A Plaster Walls NAD 145 SF 0 SF 1 1 Left Closet across from Classroom 106 N/A Cement Floor Non Suspect ACM 18 SF 0 SF 1 1 Center Closet across from Classroom 106 X X X X X X X X NO Non Suspect ACM 18 SF 0 SF 1 <	No No		_			\longrightarrow						+			
1 1 Left Closet across from Classroom 106 N/A Cement Floor Non Suspect ACM 18 SF 0 SF 1 1 Center Closet across from Classroom 106 X X X X X X X X X X X No Access X	No No	1	+	\rightarrow		\longrightarrow		_			NAD	+			
1 1 Center Closet across from Classroom 106 X X X X X X X X X X X No Access X 1 1 Right Closet across from Classroom 106 N/A Wod Ceiling Non Suspect ACM 18 SF 0 SF 1 1 1 Right Closet across from Classroom 106 N/A Plaster Walls NAD 145 SF 0 SF 1 1 1 Right Closet across from Classroom 106 N/A Cement Floor Non Suspect ACM 18 SF 0 SF 1 1	No	1	†			\rightarrow									
1 1 Right Closet across from Classroom 106 N/A Wood Celling Non Suspect ACM 18 SF 0 SF 1 1 Right Closet across from Classroom 106 N/A Plaster Walls NAD 145 SF 0 SF 1 1 Right Closet across from Classroom 106 N/A Cement Floor Non Suspect ACM 18 SF 0 SF	x	х			lo Access		х	_	Х	х	x	x	x	x	1 1 Center Closet across from Classroom 106
1 1 Right Closet across from Classroom 106 N/A Cement Floor Non Suspect ACM 18 SF 0 SF 1	No		_							18					1 1 Right Closet across from Classroom 106
	No	1	₩			\longrightarrow		0							
I 1 I 1 IC locat adjacent to Main Entrance I N/A I Plactor Calling I NAD I 30 I SE I 0 I SE I	No No	1	+			\longrightarrow	SF SF	0	SF SF	18 28	Non Suspect ACM NAD	+	Cement Floor Plaster Ceiling	N/A N/A	1 1 Right Closet across from Classroom 106 1 1 Closet adjacent to Main Entrance
1 1 Closet adjacent to Main Entrance	No			-		+						+			1 1 Closet adjacent to Main Entrance
1 1 Gloset adjacent to Main Entrance IV/A Cement Hillor Non Suspect ACM 28 SF 0 SF 1 1	No	1	1			$\overline{}$		v			11110				1 1 Closet adjacent to Main Entrance

	School District of Philadelphia		,		Reinspection 2015-2016						Reinspection Date: 1/22-29/2016				
	James Dobson Elementary School			Room by Room	Location Log Report						Building Inspector: Bernard Brunner	1			ļ
	4667 Umbria Street, Philadelphia, PA 19127										Certificate Number: 45397				ļ
	ULCS# 6450										Management Planner: Monique Causley				ļ
	Year Built: 1930										Certificate Number: ACC-0215-8-010	1			ļ
	Total Bulliu 1000										Orthodic Number: 760 0210 0 010				
E I e F m I e o n o t r	On Site Room Name	System Affected	Material Description	HID#	Confirmed, Assumed, NAD, Non Suspect ACM	Amount of Material	SF LF EA	Amount of Damage	SF LF	Color required for VAT	Comments/Description/Notes	Attic Crawl Space Ranking	Damage Potential (DP)	Newly Friable (NF)	Response Action (RA)
	Hallway outside Classroom 101	T	Pipe Fitting Insulation	6450/01/01/09	Confirmed	10	EA	0	EA				1	No	1/D
	Hallway outside Classroom 101	T	Pipe Insulation 2-6 inch	6450/01/01/12	Confirmed	24	LF	0	LF		More likely above ceiling tile		1	No	1/D
	Hallway outside Classroom 101 Hallway outside Classroom 101	N/A N/A	Fiberglass Pipe Insulation Ceiling Tile 2' x 4'		Non Suspect ACM Non Suspect ACM	36 387	LF SF	0	LF SF				1 1	No No	1/D 1/D
	Hallway outside Classroom 101	N/A	Plaster Ceiling		NAD	387	SF	0	SF				1	No	1/D
	Hallway outside Classroom 101	N/A	Plaster Walls		NAD	950	SF	0	SF				1	No	1/D
	Hallway outside Classroom 101	N/A	Marble Wall		Non Suspect ACM	380	SF	0	SF				1	No	1/D
	Hallway outside Classroom 101	N/A	Cement Floor		Non Suspect ACM	387	SF	0	SF				1	No No	1/D
1 1	Hallway outside Classrooms 103-106 Hallway outside Classrooms 103-106	N/A N/A	Ceiling Tile 2' x 4' Plaster Ceiling		Non Suspect ACM NAD	792 1332	SF SF	64 0	SF SF				N/A 1	N/A No	N/A 1/D
1 1	Hallway outside Classrooms 103-106	N/A	Plaster Walls		NAD NAD	2460	SF	20	SF				N/A	N/A	N/A
1 1	Hallway outside Classrooms 103-106	N/A	Marble Wall		Non Suspect ACM	985	SF	0	SF				1	No	1/D
	Hallway outside Classrooms 103-106	N/A	Cement Floor		Non Suspect ACM	792	SF	0	SF				1	No	1/D
1 1	Hallway outside Classrooms 103-106 Main Entrance	N/A N/A	Marble Floor Plaster Ceiling		Non Suspect ACM NAD	540 364	SF SF	0	SF SF				1	No No	1/D
1 1	Main Entrance Main Entrance	N/A N/A	Plaster Ceiling Plaster Walls		NAD NAD	364 880	SF SF	0	SF				1	No No	1/D 1/D
	Main Entrance	N/A	Marble Wall		Non Suspect ACM	260	SF	0	SF				1	No	1/D
	Main Entrance	N/A	Marble Floor		Non Suspect ACM	364	SF	0	SF				1	No	1/D
	Hallway outside Classrooms 107-108	T	Pipe Fitting Insulation	6450/01/01/09 6450/01/01/12	Confirmed	9 24	EA	0	EA		Mana Illiah i ahasia anilla a Alla		1	No	1/D
	Hallway outside Classrooms 107-108 Hallway outside Classrooms 107-108	N/A	Pipe Insulation 2-6 inch Fiberglass Pipe Insulation	6450/01/01/12	Confirmed Non Suspect ACM	11	LF IF	0	LF LF		More likely above ceiling tile		1	No No	1/D 1/D
1 1	Hallway outside Classrooms 107-108	N/A	Ceiling Tile 2' x 4'		Non Suspect ACM	387	SF	0	SF				1	No	1/D
1 1	Hallway outside Classrooms 107-108	N/A	Plaster Ceiling		NAD	387	SF	0	SF				1	No	1/D
1 1	Hallway outside Classrooms 107-108	N/A	Plaster Walls		NAD	950	SF SF	0	SF				1	No	1/D
	Hallway outside Classrooms 107-108 Hallway outside Classrooms 107-108	N/A N/A	Marble Wall Cement Floor		Non Suspect ACM Non Suspect ACM	380 387	SF SF	0	SF SF				1 1	No No	1/D 1/D
1 1	Girl's Side Stairwell	T	Pipe Fitting Insulation	6450/01/01/09	Confirmed	4	EA	0	EA				1	No	1/D
1 1	Girl's Side Stairwell	Т	Pipe Insulation 2-6 inch	6450/01/01/12	Confirmed	23	LF	0	LF				1	No	1/D
	Girl's Side Stairwell	N/A	Plaster Ceiling		NAD	50	SF SF	0	SF				1 1	No	1/D 1/D
	Girl's Side Stairwell Girl's Side Stairwell	N/A N/A	Concrete Ceiling Plaster Walls		Non Suspect ACM NAD	265 1400	SF	25	SF SF				N/A	No N/A	N/A
1 1	Girl's Side Stairwell	N/A	Marble Wall		Non Suspect ACM	470	SF	0	SF				1	No	1/D
	Girl's Side Stairwell	N/A	Cement Floor		Non Suspect ACM	315	SF	0	SF				1	No	1/D
	Boy's Side Stainwell	T	Pipe Fitting Insulation	6450/01/01/09 6450/01/01/12	Confirmed Confirmed	8	EA LF	0	EA LF				1	No	1/D 1/D
	Boy's Side Stairwell Boy's Side Stairwell	N/A	Pipe Insulation 2-6 inch Plaster Ceiling	6450/01/01/12	NAD	26 50	SF	10	SF				N/A	No N/A	N/A
1 1	Boy's Side Stairwell	N/A	Concrete Ceiling		Non Suspect ACM	265	SF	0	SF				1	No	1/D
1 1	Boy's Side Stairwell	N/A	Plaster Walls		NAD	1400	SF	5	SF				N/A	N/A	N/A
	Boy's Side Stairwell	N/A N/A	Marble Wall		Non Suspect ACM Non Suspect ACM	470 315	SF SF	0	SF SF				1	No No	1/D 1/D
1 B	Boy's Side Stairwell Basement Boy's Restroom	N/A	Cement Floor Fiberglass Pipe Insulation		Non Suspect ACM	90	SF	0	SF				1	No	1/D
1 B	Basement Boy's Restroom	N/A	Concrete Ceiling		Non Suspect ACM	624	SF	0	SF				1	No	1/D
1 B	Basement Boy's Restroom	N/A	Ceramic Tile Walls		Non Suspect ACM	1400	SF	0	SF				1	No	1/D
	Basement Boy's Restroom Basement Boy's Restroom Pipe Chase	N/A N/A	Ceramic Tile Floors Fiberglass Pipe Insulation		Non Suspect ACM Non Suspect ACM	624 30	SF LF	0	SF LF		No Access		1	No No	1/D 1/D
1 B	Basement Boy's Restroom Pipe Chase	N/A	Concrete Ceiling		Non Suspect ACM	100	SF	0	SF				1	No	1/D
1 B	Basement Boy's Restroom Pipe Chase	N/A	Brick Wall		Non Suspect ACM	440	SF	0	SF				1	No	1/D
	Basement Boy's Restroom Pipe Chase	N/A	Concrete Block Wall		Non Suspect ACM	440	SF SF	0	SF SF				1	No No	1/D
	Basement Boy's Restroom Pipe Chase Storage Room outside Basement Boy's Restroom	N/A N/A	Cement Floor Concrete Ceiling		Non Suspect ACM Non Suspect ACM	100 21	SF	0	SF		No Access - Door Stuck		1	No No	1/D 1/D
1 B	Storage Room outside Basement Boy's Restroom	N/A	Brick Wall		Non Suspect ACM	378	SF	0	SF				1	No	1/D
1 B	Storage Room outside Basement Boy's Restroom	N/A	Cement Floor		Non Suspect ACM	21	SF	0	SF				1	No	1/D
1 B	Custodial Closet outside Basement Boy's Restroom	M	Ceiling Tile 2' x 2'	6450/01/0B/AET/BB/1730	Assumed	10 x	SF	0 Y	SF x		Where is Pipe Chase in the Basement located?		1 x	No Y	1/D
	X Small Cafeteria	T T	Pipe Fitting Insulation	6450/01/0B/01	Confirmed	11	EA	0 0	EA	Α	More likely above ceiling tile		1 1	No No	1/D
1 B	Small Cafeteria	Т	Pipe Insulation 2-6 inch	6450/01/0B/02	Confirmed	33	SF	0	SF		More likely above ceiling tile		1	No	1/D
1 B	Small Cafeteria	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	10	LF SF	0	LF SF		Overseded		1	No	1/D
1 B	Small Cafeteria	N/A	Ceiling Tile 1' x 1'		Non Suspect ACM	1014		0			Suspended White Skim Coat sampled NAD 5/16/2016 KEM/B.		1	No	1/D
1 B	Small Cafeteria	N/A	Plaster Ceiling		NAD	1014	SF	1	SF		Joseph/		N/A	N/A	N/A
	Small Cafeteria	N/A N/A	Plaster Walls		NAD Nan Syanget ACM	780	SF SF	0	SF				1 1	No No	1/D 1/D
	Small Cafeteria Small Cafeteria	N/A T	Brick Wall Transite	6450/01/0B/06	Non Suspect ACM Confirmed	520 35	SF SF	0	SF SF		Lab table tops		1	No No	1/D 1/D
	Small Cafeteria	N/A	Wood Floor	3 100/3 1/0D/00	Non Suspect ACM	1014	SF	0	SF				1	No	1/D
1 B	Large Cafeteria	Т	Pipe Fitting Insulation	6450/01/0B/01	Confirmed	48	EA	0	EA		More likely above ceiling tile		1	No	1/D
1 B	Large Cafeteria	T N/A	Pipe Insulation 2-6 inch	6450/01/01/12	Confirmed	120 150	LF LF	0	LF LF		More likely above ceiling tile		1 1	No No	1/D 1/D
L I B	Large Cafeteria	I N/A	Fiberglass Pipe Insulation		Non Suspect ACM	150	LF	U	LF		<u> </u>		11	No	1/U

	School District of Philadelphia				Reinspection 2015-2016						Reinspection Date: 1/22-29/2016				
	James Dobson Elementary School			Room by Room	Location Log Report]			Building Inspector: Bernard Brunner				
	4667 Umbria Street, Philadelphia, PA 19127									- 1	Certificate Number: 45397				
1	ULCS# 6450	1								Г	Management Planner: Monique Causley	İ			i
1		1								- 1		ł			
\vdash	Year Built: 1930		1	1			1				Certificate Number: ACC-0215-8-010			1	
E I e I m e	7														
e d n d		System Affected	Material Description	HID#	Confirmed, Assumed, NAD, Non Suspect ACM	Amount of Material	SF LF EA	Amount of Damage	SF LF requi	olor ired for /AT	Comments/Description/Notes	Attic Crawl Space Ranking	Damage Potential (DP)	Newly Friable (NF)	Response Action (RA)
1 E	B Large Cafeteria	N/A	Ceiling Tile 1' x 1'		Non Suspect ACM	1419	SF	0	SF				1	No	1/D
	Large Cafeteria	N/A	Plaster Ceiling		NAD	1419	SF	10	SF				N/A	N/A	N/A
	3 Large Cafeteria	N/A	Brick Wall		Non Suspect ACM	1520	SF	0	SF					No	1/D
	3 Large Cafeteria 3 Large Cafeteria	N/A M	Cement Floor Vibration Damper Cloth	6450/01/0B/JJ	Non Suspect ACM Assumed	1419	SF SF	0	SF SF				1	No No	1/D 1/D
1 1	Storage Room adjacent to Large Cafeteria	T	Pipe Fitting Insulation	6450/01/0B/01	Confirmed	3	EA	0	EA				1	No	1/D
	Storage Room adjacent to Large Cafeteria	N/A	Fiberglass Pipe Insulation	0100/01/02/01	Non Suspect ACM	10	LF	0	LF				1	No	1/D
	Storage Room adjacent to Large Cafeteria	N/A	Plaster Ceiling		NAD	15	SF	15	SF				N/A	N/A	N/A
1 E	Storage Room adjacent to Large Cafeteria	N/A	Concrete Ceiling		Non Suspect ACM	15	SF	0	SF				1	No	1/D
1 E		N/A	Brick Wall		Non Suspect ACM	130 130	SF	0	SF				1	No	1/D
1 1 5	3 Storage Room adjacent to Large Cafeteria	N/A N/A	Concrete Block Wall		Non Suspect ACM	130 30	SF SF	0	SF SF	\dashv			1 1	No No	1/D 1/D
1 1	3 Storage Room adjacent to Large Cafeteria 3 Fan Room	T N/A	Cement Floor Pipe Fitting Insulation	6450/01/0B/01	Non Suspect ACM Confirmed	64	EA EA	0	EA EA				1 1	No No	1/D 1/D
	Fan Room	†	Pipe Insulation 2-6 inch	6450/01/01/12	Confirmed	350	LF	2	LF		Incidental DDC		1	Yes	5/B
1 E	Fan Room	T	Pipe Insulation > 6 inch	6450/01/0B/05	Confirmed	35	LF	0	LF				i	No	1/D
1 E	Fan Room	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	350	LF	0	LF		·		1	No	1/D
1 E	3 Fan Room	T	Transite Electrical Panel	6450/01/0B/06	Confirmed	60	SF	0	SF		500			No	1/D
	3 Fan Room	M T	Vibration Damper Cloth	6450/01/0B/JJ 6450/01/0B/AET/BB/1626	Assumed	20	SF LF	0	SF LF		fill in additional damage columns		1 1	No	6/C
	Fan Room Fan Room	N/A	Wire Wrap Insulation Concrete Ceiling	6450/01/0B/AE1/BB/1626	Assumed Non Suspect ACM	50 1750	SF	0	SF				1	No No	1/D 1/D
	B Fan Room	N/A	Brick Wall		Non Suspect ACM	2750	SF	0	SF				1	No	1/D
	Fan Room	N/A	Concrete Block Wall		Non Suspect ACM	550	SF	Ö	SF				1	No	1/D
1 E	Fan Room	N/A	Cement Floor		Non Suspect ACM	1750	SF	0	SF				1	No	1/D
	Boiler Room	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	500	LF	0	LF				1	No	1/D
1 E	Boiler Room	N/A	Metal Metal Boiler Breeching		Non Suspect ACM	350	SF	0	SF		Metal		11	No	1/D
1 1	Boiler Room	N/A	Fiberglass Fiberglass Tank Insulation		Non Suspect ACM	150	SF	5	SF		Fiberglass		N/A	N/A	N/A
	Boiler Room	N/A	Concrete Ceiling		Non Suspect ACM	1400	SF	0	SF		i iborgidoo		1	No	1/D
1 E	Boiler Room	N/A	Brick Wall		Non Suspect ACM	18200	SF	0	SF				1	No	1/D
	Boiler Room	N/A	Concrete Block Wall		Non Suspect ACM	9800	SF	0	SF				11	No	1/D
1 [Boller Room	N/A	Cement Floor	0.450/0.4/0.D/0.4	Non Suspect ACM Confirmed	1400	SF EA	0	SF				1 1	No	1/D 1/D
1 1	3 Old Coal Room 3 Old Coal Room	T	Pipe Fitting Insulation Pipe Insulation 2-6 inch	6450/01/0B/01 6450/01/01/12	Confirmed	20 60	LF	0	EA LF				1	No No	1/D
	3 Old Coal Room	N/A	Fiberglass Pipe Insulation	0430/01/01/12	Non Suspect ACM	75	LF	0	LF				1	No	1/D
	3 Old Coal Room	N/A	Concrete Ceiling		Non Suspect ACM	720	SF	0	SF				1	No	1/D
1 E	3 Old Coal Room	N/A	Brick Wall		Non Suspect ACM	9360	SF	0	SF				1	No	1/D
1 E	3 Old Coal Room	N/A	Concrete Block Wall		Non Suspect ACM	5650	SF	0	SF				11	No	1/D
1 E	3 Old Coal Room	N/A T	Cement Floor	0.450/0.4/0.7/0.4	Non Suspect ACM	720	SF	0	SF				1	No	1/D
	B Emergency Generator Room	N/A	Pipe Fitting Insulation	6450/01/0B/01	Confirmed	1 200	EA LF	10	EA LF				N/A	No N/A	1/D N/A
1 1	B Emergency Generator Room	IN/A	Fiberglass Pipe Insulation Emergency Generator		Non Suspect ACM			10					IN/A		
1 E		T	Insulation	6450/01/0B/AET/BB/2604	Assumed	40	LF	0	LF				1	No	1/D
	B Emergency Generator Room	N/A	Concrete Ceiling		Non Suspect ACM	900	SF	0	SF				1	No	1/D
	Emergency Generator Room Emergency Generator Room	N/A N/A	Brick Wall Concrete Block Wall		Non Suspect ACM Non Suspect ACM	17415 585	SF SF	0	SF SF	\rightarrow			1 1	No No	1/D 1/D
1 6	Emergency Generator Room	N/A	Cement Floor		Non Suspect ACM	900	SF	0	SF				1	No	1/D
1 E	Storage Room across from Girl's Side Stairwell	N/A	Concrete Ceiling		Non Suspect ACM	25	SF	0	SF				1	No	1/D
	Storage Room across from Girl's Side Stairwell	N/A	Brick Wall		Non Suspect ACM	150	SF	0	SF				1	No	1/D
	Storage Room across from Girl's Side Stairwell	N/A	Concrete Wall		Non Suspect ACM	50	SF	0	SF				1	No	1/D
	Storage Room across from Girl's Side Stairwell Pullding Engineerin Office	N/A T	Cement Floor	6450/01/0B/01	Non Suspect ACM	25	SF	0	SF				1 1	No No	1/D
1 1	Building Engineer's Office Building Engineer's Office	N/A	Pipe Fitting Insulation Fiberglass Pipe Insulation	0450/U1/UB/U1	Confirmed Non Suspect ACM	4 45	EA LF	0	EA I F	-			N/A	No N/A	1/D N/A
	Building Engineer's Office	N/A	Concrete Ceiling		Non Suspect ACM	115	SF	0	SF				1	No No	1/D
1 E	Building Engineer's Office	N/A	Brick Wall		Non Suspect ACM	220	SF	0	SF				1	No	1/D
1 E	Building Engineer's Office	N/A	Concrete Block Wall		Non Suspect ACM	90	SF	0	SF				1	No	1/D
1 E	Building Engineer's Office	N/A	Concrete Wall		Non Suspect ACM	130	SF	0	SF	[1	No	1/D
1 1	Building Engineer's Office	N/A N/A	Cement Floor		Non Suspect ACM	115 20	SF LF	0	SF LF				1 1	No No	1/D 1/D
	Building Engineer's Office Restroom Building Engineer's Office Restroom	N/A N/A	Fiberglass Pipe Insulation Concrete Ceiling		Non Suspect ACM Non Suspect ACM	20 115	SF SF	0	SF SF	\rightarrow			1	No No	1/D 1/D
	Building Engineer's Office Restroom Building Engineer's Office Restroom	N/A N/A	Ceramic Tile Walls		Non Suspect ACM	440	SF	0	SF	-			1	No	1/D
	Building Engineer's Office Restroom	N/A	Concrete Block Wall		Non Suspect ACM	90	SF	Ö	SF				1	No	1/D
1 E	Building Engineer's Office Restroom	N/A	Brick Wall		Non Suspect ACM	350	SF	0	SF				1	No	1/D
1 E	Building Engineer's Office Restroom	N/A	Ceramic Tile Floors		Non Suspect ACM	115	SF	0	SF				1	No	1/D
	Basement Girl's Restroom	T	Pipe Fitting Insulation	6450/01/0B/01	Confirmed	1	EA	0	EA					No	1/D
	Basement Girl's Restroom	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	50 850	LF SF	0	LF SF	-+			1 1	No No	1/D
1 1	Basement Girl's Restroom Basement Girl's Restroom	N/A N/A	Concrete Ceiling Ceramic Tile Walls		Non Suspect ACM Non Suspect ACM	1180	SF	0	SF				1	No No	1/D 1/D
	I Describent Ont 9 I/C91100111	I IN/A	CETAITHE THE VVAIIS	l	INUIT GUSPECT ACIVI	1100	J 31		ا اد					INU	1/0

	School District of Philadelphia James Dobson Elementary School		A		r Reinspection 2015-2016 Location Log Report						Reinspection Date: 1/22-29/2016 Building Inspector: Bernard Brunner				
	4667 Umbria Street, Philadelphia, PA 19127			_				-			Certificate Number: 45397]			
	ULCS# 6450										Management Planner: Monique Causley				
<u> </u>	Year Built: 1930										Certificate Number: ACC-0215-8-010				
m e	F 1 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	System			Confirmed, Assumed, NAD,	Amount of		Amount of	SF LF re	Color equired for		Attic Crawl	Damage Potential	Newly	Response
t	r On Site Room Name	System Affected	Material Description	HID#	Non Suspect ACM	Material	SF LF EA	Damage		equired for VAT	Comments/Description/Notes	Space Ranking	(DP)	Friable (NF)	Action (RA)
	B Basement Girl's Restroom B Basement Girl's Restroom Pipe Chase by Entrance	N/A N/A	Ceramic Tile Floors Fiberglass Pipe Insulation		Non Suspect ACM Non Suspect ACM	850 12	SF LF	0	SF LF				1 1	No No	1/D 1/D
	B Basement Girl's Restroom Pipe Chase by Entrance	N/A	Concrete Ceiling		Non Suspect ACM	36	SF	0	SF				1	No	1/D
1	B Basement Girl's Restroom Pipe Chase by Entrance	N/A	Brick Wall		Non Suspect ACM	480	SF	0	SF				1	No	1/D
1	B Basement Girl's Restroom Pipe Chase by Entrance	N/A N/A	Cement Floor		Non Suspect ACM	36 30	SF LF	0	SF LF			ļ	1	No No	1/D 1/D
	B Basement Girl's Restroom Pipe Chase on Far Wall B Basement Girl's Restroom Pipe Chase on Far Wall	N/A N/A	Fiberglass Pipe Insulation Vinyl Vibration Damper Cloth		Non Suspect ACM Non Suspect ACM	2	SF	0	SF				1	No No	1/D
	B Storage Room outside Basement Girl's Restroom	T	Pipe Fitting Insulation	6450/01/0B/01	Confirmed	3	EA	Ö	EA				1	No	1/D
	B Storage Room outside Basement Girl's Restroom	N/A	Concrete Ceiling		Non Suspect ACM	24	SF	0	SF				1	No	1/D
1	B Storage Room outside Basement Girl's Restroom B Storage Room outside Basement Girl's Restroom	N/A N/A	Brick Wall Cement Floor		Non Suspect ACM Non Suspect ACM	180 24	SF SF	0	SF SF				1	No No	1/D 1/D
	B Gym	T T	Pipe Fitting Insulation	6450/01/0B/01	Confirmed	108	EA	1	EA		Incidental DDC		1	Yes	5/B
1 1	B Gym	Ť	Pipe Insulation 2-6 inch	6450/01/01/12	Confirmed	335	LF	4	LF		Incidental DDC		i	Yes	5/B
1	B Gym	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	200	LF SF	0	LF				1	No	1/D
1	B Gym B Gym	N/A N/A	Plaster Ceiling Brick Wall		NAD Non Suspect ACM	3330 2555	SF SF	0	SF SF				N/A 1	N/A No	N/A 1/D
	B Gym	M	Floor Tile VAT 12" x 12"	6450/01/0B/HH	Assumed	3195	SF	0	SF	Tan			1	No	1/D
1	B Gym	M	Floor Tile VAT 12" x 12"	6450/01/0B/HH	Assumed	135	SF	0	SF	Green			1	No	1/D
1	B Gym	N/A	Cement Floor Radiator Insulation	6450/01/0B/LL	Non Suspect ACM Assumed	3330	SF SF	0	SF SF				1	No No	1/D
1	B Gym B Gym Storage Room	N/A	Plaster Ceiling	6450/01/0B/LL	NAD	345 168	SF	0	SF				1	No No	1/D 1/D
1	B Gym Storage Room	N/A	Brick Wall		Non Suspect ACM	575	SF	0	SF				1	No	1/D
	B Gym Storage Room	M	Floor Tile VAT 12" x 12"	6450/01/0B/HH	Assumed	168	SF	0	SF	Green			1	No	1/D
1	B Gym Storage Room B Gym Office	N/A T	Cement Floor Pipe Fitting Insulation	6450/01/0B/01	Non Suspect ACM Confirmed	168	SF EA	0	SF EA				1	No No	1/D 1/D
1	B Gym Office	†	Pipe Insulation 2-6 inch	6450/01/01/12	Confirmed	3	LF	0	LF				1	No	1/D
1	B Gym Office	N/A	Plaster Ceiling		NAD	168	SF	0	SF				1	No	1/D
	B Gym Office	N/A M	Brick Wall	6450/01/0B/HH	Non Suspect ACM	575	SF	0	SF	0			1	No No	1/D 1/D
1	B Gym Office B Gym Office	N/A	Floor Tile VAT 12" x 12" Cement Floor	6450/01/0B/HH	Assumed Non Suspect ACM	168 168	SF SF	0	SF SF	Green			1	No No	1/D
1	B Gym Storage Closet	N/A	Plaster Ceiling		NAD	30	SF	0	SF				1	No	1/D
1	B Gym Storage Closet	N/A	Brick Wall		Non Suspect ACM	260	SF	0	SF				1	No	1/D
	B Gym Storage Closet B Girl's Side Stairwell Large Closet	N/A N/A	Cement Floor Concrete Ceiling		Non Suspect ACM Non Suspect ACM	30 50	SF SF	5	SF SF				1 N/A	No N/A	1/D N/A
	B Girl's Side Stairwell Large Closet	N/A	Plaster Walls		NAD	340	SF	0	SF				1	No	1/D
1	B Girl's Side Stairwell Large Closet	N/A	Cement Floor		Non Suspect ACM	50	SF	0	SF				1	No	1/D
	B Girl's Side Stairwell Closet below Stairs B Girl's Side Stairwell Closet below Stairs	N/A N/A	Concrete Ceiling Plaster Walls		Non Suspect ACM NAD	18 120	SF SF	0	SF SF				1	No No	1/D 1/D
	B Girl's Side Stairwell Closet below Stairs	N/A	Cement Floor		Non Suspect ACM	18	SF	0	SF				1	No	1/D
1	B Hallway outside Basement Girl's Restroom	Т	Pipe Fitting Insulation	6450/01/0B/01	Confirmed	31	EA	2	EA		Incidental DDC		1	Yes	5/B
	B Hallway outside Basement Girl's Restroom	T	Pipe Insulation 2-6 inch	6450/01/01/12	Confirmed	34	LF LF	10	LF LF				1	No	1/D
	B Hallway outside Basement Girl's Restroom B Hallway outside Basement Girl's Restroom	N/A N/A	Fiberglass Pipe Insulation Plaster Ceiling		Non Suspect ACM NAD	225 700	LF SF	10	SF				N/A N/A	N/A N/A	N/A N/A
1	B Hallway outside Basement Girl's Restroom	N/A	Brick Wall		Non Suspect ACM	1800	SF	0	SF				1	No	1/D
1	B Hallway outside Basement Girl's Restroom	N/A	Cement Floor		Non Suspect ACM	700	SF	0	SF				1 1	No	1/D
1 1	B Girl's Side Stairwell B Girl's Side Stairwell	N/A N/A	Plaster Ceiling Concrete Ceiling		NAD Non Suspect ACM	140 125	SF SF	0	SF SF				1 1	No No	1/D 1/D
1	B Girl's Side Stairwell	N/A	Plaster Walls		NAD	1400	SF	40	SF				N/A	N/A	N/A
1	B Girl's Side Stairwell	N/A	Marble Wall		Non Suspect ACM	470	SF	1	SF				N/A	N/A	N/A
	B Girl's Side Stairwell B Hallway outside Large Cafeteria and Boiler Room	N/A T	Cement Floor Pipe Fitting Insulation	6450/01/0B/01	Non Suspect ACM Confirmed	265 9	SF EA	0	SF EA			-	1	No No	1/D 1/D
	B Hallway outside Large Careteria and Boiler Room B Hallway outside Large Cafeteria and Boiler Room	†	Pipe Fitting Insulation Pipe Insulation 2-6 inch	6450/01/08/01	Confirmed	38	LF	0	LF				1	No No	1/D
1	B Hallway outside Large Cafeteria and Boiler Room	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	15	LF	0	LF				1	No	1/D
	B Hallway outside Large Cafeteria and Boiler Room	N/A N/A	Plaster Ceiling Brick Wall		NAD Nan Sugaget ACM	550 2760	SF SF	0	SF SF				1	No No	1/D 1/D
	B Hallway outside Large Cafeteria and Boiler Room B Hallway outside Large Cafeteria and Boiler Room	N/A N/A	Brick Wall Cement Floor		Non Suspect ACM Non Suspect ACM	2760 550	SF SF	0	SF SF				1 1	No No	1/D 1/D
1	B Hallway outside Basement Boy's Restroom	T	Pipe Fitting Insulation	6450/01/0B/01	Confirmed	23	EA	0	EA				1	No	1/D
1	B Hallway outside Basement Boy's Restroom	T	Pipe Insulation 2-6 inch	6450/01/01/12	Confirmed	6	LF	0	LF				1	No	1/D
	B Hallway outside Basement Boy's Restroom B Hallway outside Basement Boy's Restroom	N/A N/A	Fiberglass Pipe Insulation Plaster Ceiling		Non Suspect ACM NAD	270 700	LF SF	10	LF SF				N/A 1	N/A No	N/A 1/D
	B Hallway outside Basement Boy's Restroom	N/A	Brick Wall		Non Suspect ACM	1800	SF	0	SF				1	No	1/D
1	B Hallway outside Basement Boy's Restroom	N/A	Cement Floor		Non Suspect ACM	700	SF	0	SF				1	No	1/D
	B Boy's Side Stairwell	T	Pipe Fitting Insulation	6450/01/0B/01	Confirmed	20	EA	0	EA				1	No	1/D
	B Boy's Side Stairwell B Boy's Side Stairwell	N/A	Pipe Insulation 2-6 inch Fiberglass Pipe Insulation	6450/01/01/12	Confirmed Non Suspect ACM	15 75	LF LF	0	LF LF			1	1	No No	1/D 1/D
1	B Boy's Side Stairwell	N/A	Plaster Ceiling		NAD NAD	140	SF	10	SF				N/A	N/A	N/A
1	B Boy's Side Stairwell	N/A	Concrete Ceiling		Non Suspect ACM	125	SF	0	SF				1	No	1/D

	School District of Philadelphia James Dobson Elementary School 4667 Umbria Street, Philadelphia, PA 19127 ULCS# 6450 Year Bullt: 1930		,		Reinspection 2015-2016 Location Log Report						Reinspection Date: 1/22-29/2016 Building Inspector: Bernard Brunner Certificate Number: 45397 Management Planner: Monique Causley Certificate Number: ACC-0215-8-010				
E I e F m I e o n o t r	On Site Room Name	System Affected	Material Description	HID#	Confirmed, Assumed, NAD, Non Suspect ACM		SF LF EA		EA	Color required for VAT	Comments/Description/Notes	Attic Crawl Space Ranking	Damage Potential (DP)		Response Action (RA)
1 B		N/A	Plaster Walls		NAD	1400	SF	50	SF			<u> </u>	N/A	N/A	N/A
1 B	Boy's Side Stairwell	N/A	Marble Wall		Non Suspect ACM	470	SF	0	SF				1	No	1/D
1 B	Boy's Side Stairwell	N/A	Cement Floor		Non Suspect ACM	265	SF	0	SF				11	No	1/D
1 B	Boy's Side Stairwell Recess Equipment Closet	N/A	Concrete Ceiling		Non Suspect ACM	50	SF	0	SF				1	No	1/D
1 B	Boy's Side Stairwell Recess Equipment Closet	N/A	Concrete Wall		Non Suspect ACM	200	SF	0	SF				11	No	1/D
1 B	Boy's Side Stairwell Recess Equipment Closet	N/A	Cement Floor		Non Suspect ACM	50	SF	0	SF				1	No	1/D
1 B	Boy's Side Stairwell Closet below Stairs	N/A	Concrete Ceiling		Non Suspect ACM	18	SF	0	SF				1	No	1/D
1 B	Boy's Side Stairwell Closet below Stairs	N/A	Plaster Walls		NAD	120	SF	0	SF				1	No	1/D
1 B	Boy's Side Stairwell Closet below Stairs	N/A	Cement Floor		Non Suspect ACM	18	SF	0	SF				1	No	1/D
1 A	Attic- Third Floor Corridor	X	X	X	X	X	х	X	Х	Х	Air Cell, Hrd Fittings	В	X	X	X
1.1.	Attic-Auditorium			v	,				l v		Dressing room, stage left; All asbestos removed July 2010			, !	v
	Crawlspace-Basement Hallway	X						^	_ ^	_ ^	501y 2010	_ ^	_ ^		

,	
Section III	Certificates
	A. Management Planner/Building Inspector Certificates

Section III - A

Management Planner/Building Inspector Certificates

These charts indicate the Name, Course Date, Expiration Date and Corresponding Certificate Number of the Management Planner and Building Inspector of individuals that participated in the AHERA 3 Year Inspection and Management Plan process of 2015/2016.

Management Planner	Date Granted	Expiration Date	Certificate Number
Monique Causley	2/15/2015	2/16/2016	ACC-0215-8-010
Monique Causley	2/16/2016	2/17/2017	ACC-0216-8-001
Megan Vala	5/22/2015	6/22/2016	740728
Mary Anne Lerro	4/5/2016	4/5/2017	742327

Building Inspector	Date Granted	Expiration Date	Certificate Number
Scott Magee	8/15/2015	8/15/2016	70016699C
William Garrity	8/15/2015	8/15/2016	70016699A
Bernard Brunner	10/2/2015	8/2/2016	45397
Mary Anne Lerro	3/3/2015	3/3/2016	740092
Mary Anne Lerro	4/5/2016	4/5/2017	742322
James Madden	12/11/2014	12/11/2015	ACC-1214-6-010
James Madden	12/3/2015	12/3/2016	ACC-1215-6-018
Troy Ray	3/15/2015	3/19/2016	ACC-0355-6-011
Ananth Vinjamuri	9/29/2015	9/29/2016	374
Shelton Williams	9/29/2015	9/29/2016	375
Paul Davis	2/12/2015	2/12/2016	ACC-0215-6-015
Paul Davis	2/2/2016	2/2/2017	741836
Bernard Bryson	2/16/2015	2/16/2016	ACC-0125-6-031
Bernard Bryson	2/15/2016	2/15/2017	ACC-0216-6-005
Alexander Roman	9/18/2015	9/18/2016	EHSBIR-150619-008
Norm Harrison	9/2/2015	9/2/2016	ACC-0915-6-011
Kelly Mayberry	2/20/2015	2/20/2016	EHSBIR-150220-005
Kelly Mayberry	2/18/2016	2/18/2017	EHSBIR-160218-006
Andrew Hine	5/6/2015	5/6/2016	Al05042015-3
Maryellen Leotta	2/12/2015	2/12/2016	ACC-0215-6-024

awarded to

Monique Causley for successfully completing the prescribed course of study in

Pennsylvania Asbestos Management Planner Refresher Course

under TSCA Title II

presented by

ACCESS TRAINING SERVICES, INC. 7921 River Road, Pennsauken, NJ 08110

(856) 665-3449

Course Date 2/16/15

Exam Date

ACC-0215-8-010 Certificate Number

Social Security Number

Not Provided

Training Director Mark K. Schläger

awarded to

Monique Causley

for successfully completing the prescribed course of study in

Pennsylvania Asbestos Management Planner Refresher Course

under TSCA Title II

presented by

ACCESS TRAINING SERVICES, INC. 7921 River Road, Pennsauken, NJ 08110 (856) 665-3449

2/15/16 Course Date

Exam Date

2/15/17

Expiration

Not Provided

Social Security Number

ACC-0216-8-001
Certificate Number

Mark K. Schläger Training Director

Certificate of Iraining

CRITERION LABORATORIES, INC. HEREBY CERTIFIES THAT

Megan Vala

HAS SUCCESSFULLY COMPLETED A 16 HOUR COURSE ENTITLED

<u>Asbestos Management Planner Initial</u>

INCLUDING CLASSROOM INSTRUCTION

05/21/2015 to 05/22/2015

Exam passed on this 22nd day of May 2015 - Score - 94

Approved for AHERA Accreditation Under TSCA Title II

3370 Progress Drive, Suite J Bensalem, PA 19020 (215) 244-1300 - Phone (215) 244-4349 - Fax www.criterionlabs.com

Course is conducted in English

DIRECTOR:

grash-

James A. Weltz, CIH, President

Certificate of Iraining

CRITERION LABORATORIES, INC. HEREBY CERTIFIES THAT

Mary Anne Lerro

HAS SUCCESSFULLY COMPLETED A 4 HOUR COURSE ENTITLED

Asbestos Management Planner Refresher

INCLUDING CLASSROOM INSTRUCTION on this 5th day of April 2016

Approved for AHERA Accreditation Under TSCA Title II

3370 Progress Drive, Suite J Bensalem, PA 19020

(215) 244-1300 - Phone (215) 244-4349 - Fax

www.criterionlabs.com

Course is conducted in English

DIRECTOR:

8-Cuely

James A. Weltz, CIH, President

EMSL ANALYTICAL, INC.

Certifies that

Scott Magee

has successfully completed the course of study for the

Asbestos Building Inspector Refresher Course

for Accreditation under TSCA Title II

EMSL Certificate No. 70016699C

Approved by:
PA Dept. of Labor and Industry
Accreditation # 137

Course Date: 8/15/2015 Granted: 8/15/2015 Expiration Date: 8/15/2016

Sponsored by:

EMSL Analytical, Inc. 200 Route 130 North Cinnaminson, NJ 08077 Phone: (800) 220-3675 Fax: (856) 786-5973

www.emsl.com



Michael P. Menz, CIH Training Director

made Com

Environmental, Mold. Bacteria, IAQ, Asbestos, Lead, Forensic and Materials Testing Since 1981

EMSL ANALYTICAL, INC.

Certifies that

William Garrity

has successfully completed the course of study for the

Asbestos Building Inspector Refresher Course

for Accreditation under TSCA Title II

EMSL Certificate No. 70016699A

PA Dept. of Labor and Industry Accreditation # 137 Approved by:

Course Date: 8/15/2015 Granted: 8/15/2015 Expiration Date: 8/15/2016

Sponsored by:

EMSL Analytical, Inc. 200 Route 130 North Cinnaminson, NJ 08077 Phone: (800) 220-3675 Fax: (856) 786-5973

www.cmsl.com

TSINE OF THE PROPERTY OF THE P

Michael P. Menz, CIH
Training Director

Environmental, Mold, Bacteria, IAQ, Asbestos, Lead, Forensic and Materials Testing Since 1981

45397

National Asbestos & Environmental Training Institute CERTIFICATE OF COMPLETION

AHERA/EPA Accredited Per 40 CFR Part 763
Asbestos Accreditation under TSCA Title II

This is to certify that .

Bernard Brunner, Jr.

Successfully completed the course entitled

1/2-Day New York State/EPA/AHERA Asbestos Building Inspector Annual Refresher on October 2, 2015

Examination Passed October 2, 2015

Expiration Date on October 2, 2016

President, NAETI

Per I0 NYCRR Part 73.2 (L) (I), DOH 2832 Certificate of Completion of Asbestos Safety Training is the only official record of training for N.Y.S. students.

Language: English

ABIH 1/2 CM POINT

3321 Doris Avenue, Building B, Ocean, NJ 07712

Phone (732) 531-5571

Fax (732) 531-5956

/ww.naeti.com

Certificate of Iraining

CRITERION LABORATORIES, INC.

HEREBY CERTIFIES THAT

Mary Anne Lerro

Asbestos Building Inspector Refresher

HAS SUCCESSFULLY COMPLETED A 4 HOUR COURSE ENTITLED

on this 3rd day of March 2015

Exam passed on this 3rd day of March 2015 - Score - 84

Approved for AHERA Accreditation Under TSCA Title II

3370 Progress Drive, Suite J Bensalem, PA 19020

(215) 244-1300 - Phone

www.criterionlabs.com

Course is conducted in English

クークスイヤー

James A. Weltz, CIH, President

Certificate of Iraining

CRITERION LABORATORIES, INC. HEREBY CERTIFIES THAT

Mary Anne Lerro

HAS SUCCESSFULLY COMPLETED A 4 HOUR COURSE ENTITLED

Asbestos Building Inspector Refresher

INCLUDING CLASSROOM INSTRUCTION on this 5th day of April 2016

Exam passed on this 5th day of April 2016 - Score - 88

Approved for AHERA Accreditation Under TSCA Title II

3370 Progress Drive, Suite J Bensalem, PA 19020

(215) 244-1300 - Phone (215) 244-4349 - Fax www.criterionlabs.com

Course is conducted in English

DIRECTOR:

grand.

James A. Weltz, CIH, President

James Madden

for successfully completing the prescribed course of study in

Building Inspector Refresher Course Pennsylvania Asbestos under TSCA Title II

: :

Presented by ACCESS TRAINING SERVICES, INC. 7921 River Road, Pennsauken, NJ 08110 (856) 665-3449

12/11/14

Course Date

Not Provided

Social Security Number

N/A Exam Date

ACC-1214-6-010

Certificate Number

12/11/15

Expiration Date

Mark K. Schläger Training Director

James Madden

for successfully completing the prescribed course of study in

Building Inspector Refresher Course Pennsylvania Asbestos

under TSCA Title II

presented by
ACCESS TRAINING SERVICES, INC.
7921 River Road, Pennsauken, NJ 08110
(856) 665-3449

Social Security Number Not Provided Course Date 12/3/15 Certificate Number ACC-1215-6-018 Exam Date Mark K. Schläger 146 Expiration Date 12/3/16

Training Directo.

$\mathbf{Troy}\,\mathbf{A}.\,\mathbf{Ray}$ for successfully completing the prescribed course of study in

Building Inspector Refresher Course Pennsylvania Asbestos under TSCA Title II

presented by

ACCESS TRAINING SERVICES, INC. 7921 River Road, Pennsauken, NJ 08110 (856) 665-3449

/ Mark K. Schläger	Certificate Number	Social Security Number
May be to the one	ACC-0355-6-011	Not Provided
Expiration Date	Exam Date	Course Date
3/19/16	N/A	3/19/15

G&C Environmental Services, Inc. (#294)
2 Street Road, Newtown Square, Pennsylvania 19073
Telephone: (610) 993-9202 Facsimile: (610) 993-9232

Email: Training@gcenviro.com www.GCenviro.com

This document certifies that Ananth K. Vinjamuri has successfully completed this

State of New York Department of Health Approved AHERA BUILDING INSPECTOR

REFRESHER COURSE, completed as required for asbestos accreditation under the Toxic

Substances Control Act, Title II. This course was held from 09/29/2015 to 09/29/2015.

successful completion of the examination 09/29/2016. The examination date was $\frac{09/29/2015}{MM$ DD YR

The official record of successful training completion is the New York State Department of Health certificate of asbestos safety training completion (DPH 2832).

•

Hail M. Conner

Gail M. Conner
Training Director

G&C Environmental Services, Inc. (#294) 2 Street Road, Newtown Square, Pennsylvania 19073

Telephone: (610) 993-9202 Facsimile: (610) 993-9232

Email: Training@gcenviro.com

www.GCenviro.com

State of New York Department of Health Approved AHERA BUILDIN	This document certifies that
t of Health Approved <u>AH</u>	Shelton Williams has successf
IERA BUILDING INSPECTOR	_ has successfully completed th

REFRESHER COURSE, completed as required for asbestos accreditation under the Toxic

successful completion of the examination 09/29/2016. Substances Control Act, Title II. This course was held from $\frac{09/29/2015}{MM$ DD YR MM DD YR The examination date was $\frac{09/29/2015}{MM}$. This certificate expires one year from the date of

The official record of successful training completion is the New York State Department of Health certificate of asbestos safety training completion (DPH 2832).

Hail M. Conner

Gail M. Conner
Training Director

Paul M. Davis

for successfully completing the prescribed course of study in

Building Inspector Refresher Course Pennsylvania Asbestos

under TSCA Title II

ACCESS TRAINING SERVICES, INC. presented by

7921 River Road, Pennsauken, NJ 08110 (856) 665-3449

Course Date 2/12/15

Exam Date

Social Security Number Not Provided

Expiration Date

THE OF THE STATE O

Mark K. Schläger

Certificate Number ACC-0215-6-015

Training Director

Number 741836

02/02/2017 Expiration Date

Certificate of Ironne

CRITERION LABORATORIES, INC. HEREBY CERTIFIES THAT

Paul M. Davis

HAS SUCCESSFULLY COMPLETED A 4 HOUR COURSE ENTITLED Asbestos Building Inspector Refresher

NCLUDING CLASSROOM INSTRUCTION

on this 2nd day of February 2016

ed on this 2nd day of Echruary 2016 - Score - 92

itation Under TSCA Title II

3370 Progress Drive, Suite J Bensalem, PA 19020

(215) 244-1300 - Phone (215) 244-4349 - Fax

Course is conducted in English

DIRECTOR:

James A. Weltz, CIH, Presiden

Bernard J. Bryson

for successfully completing the prescribed course of study in

Building Inspector Refresher Course Pennsylvania Asbestos

under TSCA Title II

presented by
ACCESS TRAINING SERVICES, INC.
7921 River Road, Pennsauken, NJ 08110
(856) 665-3449

Social Security Number Not Provided Course Date Certificate Number ACC-0125-6-031 Exam Date Mark K. Schläger Training Director Expiration Date

Bernard J. Bryson

for successfully completing the prescribed course of study in

Building Inspector Refresher Course Pennsylvania Asbestos under TSCA Title II

presented by

ACCESS TRAINING SERVICES, INC. 7921 River Road, Pennsauken, NJ 08110 (856) 665-3449

Exam Date

Exam Date

Expiration Date

ACC-0216-6-005

Certificate Number

Mark K. Schläger

Training Director

Not Provided
Social Security Number

Course Date



Norman Harrison

for successfully completing the prescribed course of study in

Building Inspector Refresher Course Pennsylvania Asbestos

under TSCA Title II

presented by ACCESS TRAINING SERVICES, INC. 7921 River Road, Pennsauken, NJ 08109 (856) 665-3449

Social Security Number	Not Provided	Course Date	9/2/15
Certificate Number	ACC-0915-6-011	Exam Date	N/A
Mark K. Schläger Training Director		Expiration Date	9/2/16

EHS TRAINING INSTITUTE, INC. A Division of BATTA, Inc.

Certificate of Completion

AHERA Building Inspector

(Refresher)

Awarded To:

Kelly Mayberry

SS#:XXX-XX-1551

Who has completed this 4-hour course and examination, EPA Approved under TSCA Title II

AHERA / ASHARA Rule

EHS TRAINING INSTITUTE, INC.

A Division of BATTA, Inc. Delaware Industrial Park • 6 Garfield Way Newark DE 19713-5817

Newark, DE 19713-5817

(302) 737-3376 • Fax (302) 737-5764

Course Date: February 20, 2015

Date of Expiration: February 20, 2016

Certification Number: EHSBIR 150220-005

Todd K. Zeisloft, Instructor

Neeraj K. Batta, President



AHERA Building Inspector Certificate of Completion

Awarded To:

(Refresher)

Kelly Mayberry

SS#:XXX-XX-1551

Who has completed this 4-hour course and examination, EPA Approved under TSCA Title II
AHERA / ASHARA Rule
40 CFR Part 763.

EHS TRAINING INSTITUTE, INC.

A Division of BATTA, Inc.

Delaware Industrial Park • 6 Garfield Way

Newark, DE 19713-5817 (302) 737-3376 • Fax (302) 737-5764

Course Date: February 18, 2016

Date of Expiration: **February 18, 2017**Certification Number: **EHSBIR 160218-006**

Todd K. Zeisloft, Instructo

Neeraj K. Batta, President

AEROSOL MONITORING & ANALYSIS, INC.

This is to certify that

ANDREW HINE

has met the attendance requirements and successfully completed the course entitled

3-DAY EPA AHERA INSPECTOR

For Accreditation Under TSCA Title II

Certification No.	AI05042015-3	Course Date	05/04/2015 to 05/06/2015
		מ	05/06/2015 5/6/2016
9	E. Rush Barnett	Principal Instructor	STEVE SIERAGKI
	E. Rad Band		for & twhi-

1331 Ashton Road

P.O.Box 646

www.amatraining.com Hanover, MD 21076

P: 410-684-3327

F: 410-684-3724

Maryellen Leotta

for successfully completing the prescribed course of study in

Building Inspector Refresher Course Pennsylvania Asbestos

under TSCA Title II

presented by ACCESS TRAINING SERVICES, INC. 7921 River Road, Pennsauken, NJ 08110

(856) 665-3449

Course Date

Social Security Number Not Provided

Exam Date

ACC-0215-6-024 Certificate Number

2/12/16

Expiration Dat

Mark K. Schläger Training Director



Asbestos Hazard Emergency Response Act (AHERA) Environmental Compliance Audit Cross Reference Table

In response to the AHERA Environmental Compliance Audit a Cross Reference Table has been prepared for inclusion into the Environmental Management Plan. The purpose of this Cross Reference Table is to link the following documents to the AHERA Management Plan.

Cross Reference Table

3 Year Reinspection Report follows this Cross Reference Table documentation.

	Location of Required Documents
Designated Person	Pages 1 - 3
Annual Notification	Pages 4 - 5
6 Month Periodic Surveillance Outline of Events	Page 6
3 Year Re-inspections Outline of Events	Page 7
Asbestos Management Program (operations and maintenance)	Pages 8 - 19
Asbestos Investigation Report (AIR)	Attachment 1 Letter Dated August 4, 2006
Training (included in the Asbestos Management Program)	The original records are centralized at the School District's Environment Library. Copies are maintained on staff and are required to be maintained the latest Reinspection Report. 2 hour awareness training records for all Building Engineers, Custodia Assistants and maintenance personnel 40 hour worker/supervisor training records for the OEMS A-Team are various AST tradesmen.
Response Actions (monthly mailings if applicable)	The original documents are on file at the School District's Environment Library. Copies of the original are mailed to the Schools Main Office for retention with the Management Plan documentation. These documents are typical

SCHOOL DISTRICT OF PHILADELPHIA

ASBESTOS DESIGNATED PERSON

Gerald F Junod
Office of Capital Programs
Environmental Management & Services
440 N Broad Street, 3rd Floor
Philadelphia, PA 19130
Telephone: 215 400 6738
Fax: 215 400 4751

Drexel University- Asbestos Building Inspector Course
Drexel University- Asbestos Management Planner Course
Criterion Laboratories, Inc. - Asbestos Management Planner Course October 11-12, 2012 16 Hours

Annual Building Inspector Refreshers

1990 to Present

4 Hours
Drexel University
Criterion Laboratories, Inc
Access Training Services, Inc.

Annual Building Management Planner Refreshers

1990 to 1994

4 Hours

Drexel University

Criterion Laboratories, Inc

2013 to Present

4 Hours

Environmental Manager, School District of Philadelphia

Manages the design and implementation of asbestos and lead projects for the Capital Improvement Program and other District Departments including Facilities & Operations and Information Technology. Ensures that asbestos abatement and lead remediation projects are expertly designed and executed in accordance with industry best management practice standards and regulations.

Manager, City of Philadelphia Asbestos Control Program

Served as the Asbestos Control Program Manager for the City of Philadelphia, Department of Public Health, Air Management Services, Asbestos Control Unit from August 1, 2003 through October 23, 2006.

Mid Atlantic Regional Environmental Consortium (MAREC)

Former member with attendance and participation commitments of all quarterly EPA Region III and yearly National Asbestos Regulatory Conferences sponsored by the EPA and the National Conference of State Legislators respectively as a representative for the City of Philadelphia Department of Public Health Air Management Services from 1994 through 2006.

Philadelphia Environmental Task Force

Former member of the Philadelphia Environmental Task force as a representative and point of contact for the City of Philadelphia Department of Public Health Air Management Services Asbestos Control Unit from 2002 through 2006.

Asbestos Instructor

Worked as the primary instructor for the initial and annual Asbestos Project Inspector training and licensing program as mandated by City of Philadelphia Department of Pubic Health Asbestos Control Regulations from August 1994 through October 2006.

Worked as a lead instructor with an Environmental Consulting Firm and approved by the US EPA for the initial and annual refresher training courses for various asbestos occupational disciplines such as the Building Inspector, Management Planner and Worker/Supervisor from 1991 through 1994.

I certify that the general, local agency responsibilities as stipulated in Section 763.84 will be met.

Gerald F. Junod

Asbestos Designated Person Environmental Manager

Office of Environmental Management and Services

SCHOOL DISTRICT OF PHILADELPHIA

Accreditation Information Statement

All persons who inspect for Asbestos Containing Building Materials (ACBM) and who will design or carry our response actions with respect to assumed and confirmed ACBM, will be accredited by an EPA approved course and/or a State Contractors AccreditationProgram under Sections 206 (c) and 206 (b) of Title II of the ACT.

Gerald F. Junod

Asbestos Designated Person Environmental Manager

Office of Environmental Management and Services

SCHOOL DISTRICT OF PHILADELPHIA

OFFICE OF CAPITAL PROGRAMS 440 NORTH BROAD STREET, SUITE 373 PHILADELPHIA, PENNSYLVANIA 19130

OFFICE OF ENVIRONMENTAL MANAGEMENT AND SERVICES

PHONE (215)-400-4750

September 2015

TO:

Principals

Building Administrators/Occupants

Parents/Guardians

FROM:

Fran Burns

Chief Operating Officer

Francine Locke, M.S., Director

Office of Environmental Management and Services

SUBJECT:

Annual EPA Notification Letter

Pursuant to the Federal Environmental Protection Agency (EPA) mandate, as required by 40 C.F.R. 763.84 (c)(d) of public access to environmental records, this letter is to acknowledge the availability of your facility's Asbestos Hazard Emergency Response Act (AHERA) Management Plan.

Each member of the school staff, parents/guardians, temporary workers and/or contractors, are required to receive a copy of the Notification Letter. At the direction of the Principal, a copy is to be posted on the bulletin boards and an appropriate amount of copies are to be generated for distribution.

Note: The AHERA Three-Year Reinspection reports, in colored binders; White with Pink, Tan, Black, Red, Dark Blue, Green, Yellow and White, are Federal EPA mandated inspection documents. The School District of Philadelphia is subject to severe monetary penalties if the reports and associated paperwork are not available to the EPA and the public upon request.

It is incumbent on designated school personnel to gather and retain this data as it is delivered, in one location for future review. Acceptable locations include the Principal's Office or Main Office for the primary data. The Building Engineer should maintain any secondary or duplicate copies.

If you have any questions, please call 215-400-4750. Thank you for your cooperation.

Fran Burns

Chief Operating Officer

Francine Locke, M.S., Director

Office of Environmental Management

and Services

c: Danielle Floyd

AHERA-4 8/21/15



School District of Philadelphia OFFICIAL NOTICE

PLEASE POST

September 2015

TO:

Principals

Building Administrators Building Engineers Building Occupants Parents/Guardians

FROM:

Fran Burns

Chief Operating Officer

Francine Locke, M.S., Director

Office of Environmental Management and Services

SUBJECT:

Annual Notification Letter: Asbestos Hazard Emergency Response Act

The Federal Register published on October 30, 1987, Subpart E, in Schools: Final Rule and Notice, 763.84 (c)(d) states that each local education agency shall ensure that workers and building occupants or guardians are to be informed at least once each school year about inspections, response actions and post-response action activities including re-inspections and periodic surveillance activities. The School District as the Local Education Agency (LEA), retains such reports that are available for public inspection in the Office of the Principal or Building Administrator.

The Principal or Building Administrator is required to do the following with this notification:

1) Post in a Public Place or Main Office

2) Inform Building Occupants

3) Send a copy of this notification to Parents or Guardians

4) Insert a copy into the latest AHERA Three-Year Reinspection report (white/pink binder)

in your office or facility.

Fran Burns

Chief Operating Officer

Francine Locke, M.S., Director

Office of Environmental Management

and Services

c: Danielle Floyd

AHERA-4a 8/21/15

SCHOOL DISTRICT OF PHILADELPHIA

Education Center 440 North Broad Street Philadelphia, Pennsylvania 19130

Office of Environmental Management and Services

215-400-4750

AHERA Six Month Surveillance Outline of Events

- Pursuant to the Federal Environmental Protection Agency (EPA) mandate, as required by 40 CFR 763.92(b), the following procedure is to be implemented. At least once every six (6) months after a Management Plan is in effect, each Local Education Agency (LEA) shall conduct a periodic surveillance in each building that it owns or leases that contains Asbestos Containing Building Materials (ACBM) or is assumed to contain ACBM.
- The first Bi-Annual Inspection starts in the Spring (March, April, May) and again in the Fall (October, November, December) of each year. The Building Engineer/Assistant should assist the Building Inspector with appropriate access to all areas including (Crawlspaces/Attics) and rooms in the facility. There is no action required of the Principal.
- The Building Inspector shall visually inspect all areas that are identified in the Management Plan as ACBM or assumed ACBM. The date of the surveillance is recorded, the inspectors name and any changes in the conditions of the materials.
- The Building Inspector shall make a copy of the inspection document and insert into the front of the latest Management Plan (AHERA Three Year Reinspection report). The original document is returned to the LEA's Environmental Library and filed.

SCHOOL DISTRICT OF PHILADELPHIA

Education Center 440 North Broad Street Philadelphia, Pennsylvania 19130

Office of Environmental Management and Services

215-400-4750

AHERA Three Year Reinspection Outline of Events

- Pursuant to the Federal Environmental Protection Agency (EPA) mandate, as required by 40 CFR 763.85(b) the following procedure is to be implemented. At least once every three (3) years after a Management Plan is in effect, each Local Education Agency (LEA) shall conduct a reinspection of each building that it owns or leases that contains Asbestos Containing Building Material's (ACBM's) or is assumed to contain ACBM.
- Subsequent Three Year Re-inspections (2009, 2012, 2015, etc) shall start in the Fall (October, November, December, January). The Building Engineer/Assistant should assist the Building Inspector with appropriate access to all areas including (Crawlspaces/Attics) and rooms in the facility. There is no action required of the Principal.
- An accredited Building Inspector shall visually inspect and touch to determine friability, all areas that are identified in the Management Plan as ACBM or assumed ACBM. The date of the surveillance is recorded, the inspectors name and any changes in the conditions of the materials. The Building Inspectors state of accreditation and license number is required.
- After the inspection, the Building Inspector shall make a copy of the inspection documents and insert into the front of the latest Management Plan (AHERA Three Year Reinspection report). The original document is returned to the LEA's Environmental Library and filed.
- The Building Inspector shall return the reinspection data to the Management Planner to be assessed and determine appropriate response actions and a report issued (AHERA Three Year Reinspection report). One copy of the report is delivered to the schools Principal to be permanently retained with all previous environmental data. Another copy is retained in the LEA's Environmental Library.



School District of Philadelphia
Office of Environmental Management & Services
440 North Broad Street
Philadelphia, PA 19130
(215) 400-4750

School District of Philadelphia **Asbestos Management Program**

TABLE OF CONTENTS

DefinitionsPage 9	
1.	Introduction
	Summary of Asbestos Management Plan Asbestos Management Plan Execution
4.	Summary of Program Execution a. Asbestos Management Plan Execution
5.	Responsibilities a. OEMS b. Asbestos Worker/Supervisor "A-TEAM"
6.	Requirements
7.	AHERA O&M PlanPage 15 a. Controls
8.	O&M Response Actions
	O Deferences and Descriptions Page 1

DEFINITIONS / ACRONYMS

ACM/PACM: Asbestos Containing Material/Potential Asbestos Containing

Material

AHERA: Asbestos Hazard Emergency Response Act

AIR FORM: Asbestos Inspection Report Form

Amended Water: Water to which a surfactant (soap) has been added

AMP: Asbestos Management Program/Asbestos Management Plan

Asbestos Designate Person: Individual assigned by the district to oversee asbestos related

issues.

Asbestos Regulated Area: Location that is posted as an asbestos work area in which only

approved and accredited personnel are permitted to enter

AST: Asbestos Support Team involving approved and accredited

school district tradespersons personnel that are school district

person

A-TEAM: School District of Philadelphia asbestos workers

CIP: Capital Improvement Program

Consultant: Asbestos consulting firm hired by the District

Demolition Directive: Memorandum – August 4, 2006 from Patrick Henwood

EPA: Environmental Protection Agency

In House Personnel: School District of Philadelphia asbestos workers

LEA: Local Education Agency

O&M: Operations and Maintenance

OEMS: Office of Environmental Management and Services

OSHA: Occupational Safety and Health Administration

PEL: Permissible Exposure Limit

PSD or SDP: Philadelphia School District/School District of Philadelphia

PSIT: Philadelphia School Improvement Team

STEL: Short Term Exposure Limit

1. Introduction

The School District of Philadelphia, Asbestos Policy Statement:

"The School District of Philadelphia is dedicated to providing a safe and healthful work environment for its employees, students, faculty, contractors and visitors. In recognition of the potential health problems associated with asbestos, the School District of Philadelphia is committed to a comprehensive asbestos control program. This program is implemented and maintained through the School District of Philadelphia's Office of Environmental Management and Services (OEMS)."

OEMS has the responsibility of establishing procedures for asbestos abatement, asbestos inspection, air monitoring, renovation and demolition activities within all School District of Philadelphia owned or leased facilities.

These procedures are developed to ensure that:

- (1) People are not exposed to significant levels of asbestos fibers
- (2) Asbestos waste is handled and disposed of properly
- (3) Members of the School District of Philadelphia community have access to the Office of Environmental Management and Services for information, assistance, guidance, and interpretation regarding asbestos related matters.
- (4) Members of the School District of Philadelphia community have access to the Asbestos Management Plans as required and outlined in the US EPA AHERA regulations including annual written notification to all parents.
- (5) Compliance with all applicable Federal, State and Local Asbestos Regulations

Requirements outlined in this manual are mandatory in nature where the word "SHALL" is used and are advisory in nature where the word "SHOULD" is used.

2. Summary of Asbestos Management Program

The School District of Philadelphia's Asbestos Management Program was established to meet the requirements of Federal, State, and Local Regulations.

These regulations include, but are not limited to:

- US Environmental Protection Agency Asbestos Hazard Emergency Response Act (US EPA AHERA) and National Emissions Standard for Hazardous Air Pollutants subpart M, Part 61 (NESHAP);
- US Department of Labor, Occupational Safety and Health Administration (OSHA) General Industry Standard (29 CFR 1910.1001) and the OSHA Asbestos Standard for the Construction Industry (29 CFR 1926.1101);
- The Commonwealth of Pennsylvania, Department of Labor and Industry, Asbestos Occupations, Accreditation and Certification Act;
- The City of Philadelphia, Department of Public Health, Asbestos Control Regulations.

3. Asbestos Management Program Execution

a) General Execution

The Office of Environmental Management and Services (OEMS) develops, implements and manages safety and health programs for the School District of Philadelphia faculty, staff and students and assists with ensuring that all contractors comply with Federal, State and Local Environmental Regulations. The OEMS provides the oversight of School District of Philadelphia employees (Asbestos A-Team), environmental consultants, and asbestos abatement contractors for all projects within the School District of Philadelphia concerning Asbestos Containing Materials.

The control of safety and health hazards at the School District of Philadelphia is primarily through the implementation of engineering, work practice and administrative controls. Personal Protective Equipment (PPE) is used to supplement these controls or whenever the controls are not feasible or are in the process of being implemented. PPE is also recommended whenever exposures to chemical, physical or biological agents can be prevented or reduced by its use.

This written program establishes the procedures necessary to:

- 1) meet established standards and federal regulations for occupational exposure to asbestos fibers;
- 2) meet the requirements of the City of Philadelphia Asbestos Control Regulations which encompasses the disturbance and/or abatement of asbestos containing building materials;
- 3) provide the necessary health and safety protection to the School District of Philadelphia staff, faculty, students, contractors and visitors.

This program is strengthened by input and cooperation with the Philadelphia Federation of Teachers (PFT), Health and Welfare Fund.

4. Summary of Program Execution

a) Asbestos Management Program Execution

The Asbestos Management Program is administered by the Office of Environmental Management and Services (OEMS). OEMS provides the following services primarily through professional consultants:

- (1) exposure monitoring services;
- (2) building inspection/surveys (bulk sampling) for the identification of asbestos containing materials;
- (3) asbestos project design services;
- (4) asbestos abatement project and air monitoring services;
- (5) emergency response to fiber release episodes;
- (6) education/information;
- (7) medical monitoring;
- (8) training for School District of Philadelphia personnel

5. Responsibilities

a) Office of Environmental Management and Services

OEMS is responsible for performing the following functions:

- (1) Developing and administering of the Asbestos Management Program.
- (2) Providing asbestos-related services to all School District of Philadelphia departments.
- (3) Conducting required training of the Asbestos Management Program and working jointly with departments to schedule training.
- (4) Identifying and posting areas where labeling/signage are required.
- (5) Medical Monitoring of OEMS "A-TEAM" and other departments "AST" Asbestos Program staff.

- (6) Certification and training as required for OEMS "A-TEAM" and other departments "AST" Asbestos program staff.
- (7) Record keeping as outlined in Section 3.5 and all records as by required by US EPA AHERA regulations.

b) Asbestos Worker/Supervisor - "A-TEAM"

- (1) OEMS shall ensure that all "A-TEAM" workers/supervisors adhere to the following requirements:
 - a) Attend an initial Worker/Supervisor Asbestos Course;
 - b) Maintain the annual re-certification per EPA AHERA requirements and Commonwealth of Pennsylvania Asbestos Occupations, Accreditation and Certifications Act;
 - c) Undergo an annual Asbestos Medical Evaluation;
 - d) Undergo an annual Respirator Medical Clearance;
 - e) Undergo an annual Respirator Fit Testing.

c) Asbestos Designated Person

The Asbestos Designated Person is responsible for:

- (1) Assuring the health and safety of employees, students and visitors in the School District of Philadelphia facilities under his/her control.
- (2) Being kept informed of all areas under his or her jurisdiction where potential asbestos exposures exist and initiating protection programs that adhere to the Asbestos Management Program requirements of this manual.
- (3) Assuring that Asbestos Management Program requirements are adhered to by principal investigators, project managers, supervisors, or division heads, and School District of Philadelphia personnel under their supervision.
- (4) Ensuring that all employees within the Asbestos Management Program comply with (OSHA 1910.1001 (j) (7) (iv)) and the US EPA AHERA regulations by attending the required training.
- (5) Ensure the posting of:
 - a) Warning labels/signage
 - b) Commonwealth of Pennsylvania Asbestos Abatement and Demolition/Renovation Notification form
 - c) Asbestos Inspection Reports (AIR) form (where required)
 - d) Ensuring that Construction Projects follow the Demolition Directive procedures as outlined in the August 4, 2006 letter.

d) Supervisor or Project Manager (Capital, Maintenance and Facilities)

Each person in charge of a project, maintenance/repair, renovation/demolition, or other activity from the Departments of Capital, Maintenance, and/or Facilities, where asbestos containing material may be present is responsible for:

Identifying, with the assistance of OEMS, asbestos containing building materials prior to any disturbance of these materials. Various Federal (EPA and OSHA) and Local (City of Philadelphia Asbestos Control Regulations) require Asbestos Inspections prior to renovation/demolition activities. This shall be accomplished by always following the Asbestos Management Program Procedures as follows:

(1) Ensure that the requirements of the Asbestos Management Program Procedures are followed by all personnel, trades, and contractors who are involved with the project;

- (2) Review of the required Asbestos Inspection Report (AIR) form (Attachment 1) and AHERA Management Plan documents prior to activities that may disturb any Asbestos Containing Materials;
- (3) Perform all project related duties as outlined in the Project Management Responsibilities;
- (4) Keep the department chairperson or director informed on any actions proposed or taken regarding the Asbestos Management Plan;
- (5) Ensuring that Construction Projects follow the Demolition Directive procedure outlined in the August 4, 2006 letter.

e) Employee - Capital

School District of Philadelphia Capital employees and/or consultants shall:

- (1) Ensure that no suspect or asbestos containing building materials are disturbed in the course of the projects they are performing or managing. This shall be accomplished by notifying their supervisor and OEMS by issuance of a work order permit (a.k.a PSIT Service Request Form) and verifying that the materials which may be disturbed are non-asbestos containing. If this information is not available or verification has not been made, these materials should not be disturbed.
- (2) Immediately notify OEMS and their supervisor in the event of a potential fiber release episode upon discovery of visible damage to asbestos containing materials.
- (3) Ensuring that Construction Projects follow the Demolition Directive procedures as outlined in the August 4, 2006 letter.

The types of projects represented as part of the Capital Improvement Program are as follows:

- (1) Complete Renovation of an existing building that addresses all facility component concerns and educational program needs;
- (2) Major Renovation of an existing building addressing significant facility component and educational improvements;
- (3) Addition to an existing building (either as an attachment or stand-alone structure) to accommodate needed program space;
- (4) Conversion of an existing facility to accommodate a change in educational program;
- (5) Facility Component Improvement of specific facility needs (i.e. electrical or HVAC system upgrades, ADA improvements, life safety improvements, exterior renovations, etc.)

f) Employee - Maintenance

School District of Philadelphia Maintenance employees shall:

- (1) Ensure that no suspect or asbestos containing building materials are disturbed in the course of their duties or work they are performing. This shall be accomplished by notifying their supervisor and OEMS by issuance of a work order permit and verifying that the materials which may be disturbed are non-asbestos containing. If this information is not available or verification has not been made, these materials should not be disturbed.
- (2) Immediately notify OEMS and their supervisor in the event of a potential fiber release episode or upon discovery of visible damage to asbestos containing materials.
- (3) All employees involved in maintenance activities shall attend required Asbestos Awareness training program within 60 days of employment.

g) Employee - Facilities & Custodial

School District of Philadelphia Facilities and Custodial employees shall:

- (1) Ensure that no suspect or asbestos containing building materials are disturbed in the course of their duties or work they are performing. This shall be accomplished by notifying their supervisor and OEMS by issuance of a work permit and verifying that the materials which may be disturbed are non-asbestos containing. If this information is not available or verification has not been made, these materials should not be disturbed;
- (2) Immediately notify OEMS and their supervisor in the event of a potential fiber release episode or upon discovery of visible damage to asbestos containing materials.
- (3) All employees involved in Facilities and Custodial activities shall attend require Asbestos Awareness training program within 60 days of employment.

6. Requirements

a) Employee Exposure Monitoring

When information indicates that an employee's exposure to asbestos fibers may equal or exceed an 8-hour time-weighted average of 0.1 f/cc * (per OSHA 1910.1001 & 1926.1101), OEMS shall develop and implement an asbestos exposure monitoring program. The sampling strategy shall be designed to identify employees by work task (job classification) that is exposed to asbestos fibers that exceed an 8-hour time-weighted average of 0.1 f/cc.

b) Employee Notification

OEMS shall notify in writing, each employee exposed to asbestos fibers at or above an 8-hour time weighted average of 0.1 f/cc.

c) Observation and Monitoring

OEMS shall provide employees or their representatives with an opportunity to observe any exposure measurements conducted.

d) Training Program

OEMS shall institute a training program which meets the requirements of AHERA for all employees who perform maintenance operations in a facility/school which contains asbestos containing materials or presumed asbestos containing materials and 1910.1001 (j), and the Commonwealth of Pennsylvania Department of Labor and Industry and the City of Philadelphia Asbestos Control Regulations. The affected departments shall ensure employee participation in this program. The OEMS "A-TEAM" and other departments "AST" Asbestos Program staff training shall be conducted annually for each employee as required by all Federal, State and Local for each asbestos discipline.

All Asbestos Awareness training as required by AHERA shall be performed within 60 days of employment and shall include:

- o Health effects of asbestos
- o Locations of ACM and PACM in the building/facility
- Recognition of CM and PACM damage and deterioration
- o Requirements of the OSHA 1910.1001 standard relating to maintenance
- O Proper response to fiber release episodes
- o Procedure to be followed to isolate areas affected by fiber release

e) Access to Information

OEMS shall make available to affected employees or their representative's copies of the Occupational Safety and Health Administration (OSHA) General Industry Standard Part 1910.1001 and the department shall post a copy in the workplace.

f) Record Keeping

OEMS shall maintain an accurate record of all employee exposure measurements. OEMS and/or the School District of Philadelphia Human Resources Department shall maintain records of employee medical monitoring program. OEMS shall maintain all employee training records. All records shall be provided upon request to employees, former employees, representatives designated by the individual employee.

7. AHERA OPERATIONS AND MAINTENANCE PLAN

a) CONTROLS

i. Work Order System

Minimizing disruption of ACM/PACM during maintenance and renovation activities is the primary goal and task encountered by OEMS. Operations and maintenance employees and contractors should be warned to avoid conducting any maintenance work which may disturb ACM/PACM. Initiating a work order system, where all work orders or requests are channeled through the Office of Environmental Management and Services (OEMS), will be the method used to control and minimize disruption of ACM/PACM.

Any work performed by in-house personnel or contractors that could or will impact ACM/PACM shall be coordinated by OEMS. A completed Asbestos Inspection Report Form (Attachment 1) shall be issued to in-house personnel and/or all contractors whose work could impact ACM/PACM. This form should accompany each contract issued to an outside contractor and posted on the jobsite.

All work order requests for maintenance and renovation activities in areas where ACM/PACM is suspected or known to be present are to be submitted to OEMS prior to proceeding with work. OEMS is responsible for reviewing asbestos survey records for information about the presence of ACM/PACM in the area where the work is to be performed. OEMS should physically inspect the area to ensure existing records reflect actual conditions. If no asbestos is present, a work order is not necessary and the planned actions can proceed. If ACM/PACM is found to be present in the area, OEMS will sign the work order application and obtain an approved and accredited asbestos contractor or assign OEMS "A-TEAM" to abate the ACM/PACM.

ii. Regulated Areas

The owner will identify and regulate all areas where airborne concentrations of ACM/PACM exceed the Permissible Exposure Limit (PEL)* (Per OSHA determined to be 0.1 f/cc) and/or short term exposure limit (STEL) (Per OSHA determined to be 0.1 f/cc), or there is reasonable possibility that the (PEL) and/or (STEL) may be exceeded. All ACM/PACM removal activities involving thermal system insulation ACM/PACM (Class I), surfacing ACM/PACM (Class I), and miscellaneous ACM/PACM such as floor tile, roofing, and siding mastic, etc. (Class II), and repair and maintenance operations where thermal system insulation and surfacing ACM/PACM is likely to be disturbed (Class III) will be performed in accordance with federal, state, and local regulations. All asbestos abatement work and activities will be designed and managed as asbestos regulated areas. These areas will be demarcated and labeled.

iii. Warning Signs

Warning signs shall be displayed at all approaches to each asbestos regulated area. The asbestos abatement contractor will provide OSHA warning signs in all regulated areas during removal, repair, and other maintenance activities. OEMS will provide AIRs to all contractors who must inform all employees and supervisors working in locations contiguous to asbestos regulated areas of the potential hazards and work practices required.

iv. Warning Labels

Warning labels and./or signage shall be affixed to all raw materials, mixtures, scrap, waste, debris, and other products containing asbestos fibers, or to their containers. Generally, the asbestos abatement contractor or OEMS A-Team personnel will provide all warning labels for ACM/PACM containment.

8. O & M RESPONSE ACTIONS

The Asbestos Management Program general O&M procedures are outlined in this section. Additional requirements specific to asbestos abatement activities are included in the Project Design documents for all Asbestos Abatement Work. Regular cleaning, inspection, and reporting of ACM/PACM deterioration or other problems must be diligently practiced by all employees including custodial and maintenance personnel.

a) Facility Maintenance Isolation of Area Responsibilities

Maintenance personnel are often required to work in areas where ACM/PACM may potentially be disturbed. Most maintenance activities are conducted by in-house staff, outside contractors, or a combination.

Emergency fiber release episodes, such as pipe fitting or valve breaks, emergency boiler work, or mechanical equipment repair will be responded to by OEMS A-Team personnel or asbestos abatement contractor personnel. The owner's maintenance staff will: (1) isolate the emergency fiber release area; (2) post warning signs to prevent unauthorized access, and (3) notify their supervisor and OEMS. OEMS will ensure that the fiber release area remains isolated and is properly cleaned by and approved and accredited abatement contractor or by OEMS A-TEAM personnel.

b) Unlikely Contact with ACM/PACM

Maintenance activities or repairs which can be performed without contacting or disturbing the ACM/PACM require little more than normal care and good workmanship. For example, valves which are either uncovered or covered with non-asbestos insulation can be packed or repaired without disturbing asbestos insulation on nearby pipes. The major precaution is to ensure that maintenance and custodial personnel are familiar with procedures such as isolating the area, posting warning signs, and notifying OEMS in the event of any accidental ACM/PACM disturbance.

c) Accidental Disturbance of ACM/PACM

Maintenance and facilities personnel shall notify OEMS any time a fiber release is suspected. If friable ACM/PACM becomes airborne in the building,

d) Planned Disturbance of ACM/PACM

Maintenance activities that may impact ACM/PACM include access to a valve, flange, duct, or related system component.

Where asbestos-containing insulation must be removed to maintain or repair the thermal system, the ACM/PACM will imminently be disturbed. ACM/PACM removal work shall be conducted by OEMS A-Team personnel or an approved and accredited asbestos abatement contractor.

If friable ACM/PACM becomes airborne in the building, maintenance and facilities personnel shall secure the area and contact OEMS. OEMS shall respond accordingly.

e) Miscellaneous ACM/PACM

Miscellaneous types of ACM/PACM may include vinyl asbestos floor tiles, mastics/adhesives and woven vibration dampers. Disturbance of these materials should be avoided. Routine maintenance activities involving these materials should not pose a problem if handled properly. Questions on the proper removal and disposal of miscellaneous ACM/PACM should be directed to OEMS. OEMS will contact an approved and accredited asbestos abatement contractor or utilize OEMS A-TEAM personnel to assist with miscellaneous ACM/PACM clean-up activities.

f) Vinyl Asbestos Floor Tile

Asbestos-containing floor tiles in good condition are considered non-friable unless they are crushed, drilled, sawed, sanded or disturbed by any activity that breaks up the material. Routine maintenance of these materials should employ the use of non-abrasive buffers and wet cleaning technique. Broken or loose floor tiles should be removed and disposed of as asbestos waste by OEMS. Remaining debris should be vacuumed with a HEPA vacuum and the area wet mopped using amended water.

g) Mastics/Adhesives

Mastics and adhesives containing asbestos in good condition are considered non-friable and do not pose a potential health concern unless crushed, drilled, sawed, sanded, or otherwise abraded. Questions on the proper removal should be directed to OEMS.

h) Woven Vibration Dampers

Woven vibration dampers in good condition are considered non-friable and do not pose a potential health concern unless cut, crushed, drilled, sawed, sanded, or otherwise abraded. Questions on the proper removal should be directed to OEMS.

i) Other Work Practices

Any special work not included in this section should be addressed to OEMS for review prior to the initiation of work that may involve the disturbance of ACM/PACM.

j) Fiber Release Episodes

Facilities and maintenance staff should report to OEMS the presence of asbestos debris, water or physical damage to ACM/PACM, or any other evidence of possible fiber release. OEMS should have the OEMS A-Team personnel or an approved and accredited abatement contractor respond to the site to clean up debris and make repairs as soon as possible. OEMS will also contact a consultant to conduct air monitoring and prepare a report and submit at project completion to OEMS for each episode. OEMS will forward the reports for each site location AHERA Management Plan accordingly.

9. REFERENCES and RESOURCES

Applicable regulations for asbestos projects impacted by renovation, demolition, and maintenance activities.

- Philadelphia Air Management Services Asbestos Control Unit http://www.phila.gov/health/units/ams/Asbestos/asbestos.html
- Pennsylvania Asbestos Occupations, Accreditation and Certification Act
 http://www.dli.state.pa.us/landi/cwp/view.asp?a=185&q=56262&landiNav=
- United States Environmental Protection Agency Asbestos Home Page
 http://www.epa.gov/asbestos/
- Occupational Safety and Health Administration (OSHA) Asbestos Home
 http://www.osha.gov/SLTC/asbestos