

SCHOOL DISTRICT OF PHILADELPHIA



Asbestos Hazard Emergency Response Act “AHERA”

THREE-YEAR RE-INSPECTION 2015-2016 and ASBESTOS MANAGEMENT PLAN for the

Woodrow Wilson Middle School

**ULCS# 8120
Building # B812001-1
1800 Cottman Avenue
Philadelphia, Pennsylvania
19111**

Year Built: 1928

December 2015

Conducted by:

Accredited Environmental Technologies, Incorporated
Batta Environmental Associates, Incorporated
Criterion Laboratories, Incorporated
Environmental Testing Consultants, LLC
G & C Environmental Services, Incorporated
KEM Partners, Incorporated
Synertech, Inc.
TTI Environmental, Inc.
USA Environmental Management, Inc.
The Vertex Companies, Inc.

Management Plan Prepared by:
Criterion Labs, Inc and Synertech Inc.

This report must remain in the Main Office as mandated by the US EPA AHERA Regulations.

AHERA THREE-YEAR REINSPECTION VOLUME IX

Table of Contents

Transmittal Letter

Executive Summary

- I. Summary list of Confirmed Asbestos Containing Building Materials
- II. Summary list of Assumed Asbestos Contain Building Materials
- III. Summary list of Non-Asbestos Containing Building Materials
- IV. Summary list of Non Suspect Asbestos Containing Building Materials
- V. Summary List of Auditorium DATA for this location
- VI. Summary list of Attic and/or Crawlspace DATA for this location
- VII. Summary list of Pipe Chase/Pipe Shaft DATA for this location

Section I Report of Re-Inspection

- A. Introduction
- B. Three-Year Re-inspection IX Overview
- C. Post- Management Plan Activities and Changes
 - C.1 - Sampling and Analysis
 - C.2 - New Floor Tile Sampling
 - C.3 - Abatement Activity
 - C.4 - Periodic (Six-Month) Surveillance (Damaged Materials)

Section II Re-Inspection Data

- A. Introduction
- B. Re-Inspection Key Definitions
- C. Room by Room Location Log Report

Section III Certificates

- A. Management Planner/Building Inspector Certificates

Section IV	Cross Reference Table	Page 1-8
	Asbestos Management Program	Page 9-19

SCHOOL DISTRICT OF PHILADELPHIA
EDUCATIONAL CENTER
440 NORTH BROAD STREET
PHILADELPHIA, PENNSYLVANIA 19130

OFFICE OF ENVIRONMENTAL MANAGEMENT AND SERVICES

PHONE (215)-400-4750

January 2016

TO: All Principals
All Building Administrators

FROM: Fran Burns
Chief Operating Officer

Francine Locke, M.S., Director
Office of Environmental Management and Services

SUBJECT: AHERA Three (3) Year Re-inspection IX report

In order to comply with the provisions of the Asbestos Hazard Emergency Response Act (AHERA) the attached report is submitted to you. The law requires that this report be kept in the Main/Principal's office. It cannot be removed from these locations. *If the school (program) is relocated to a different building, these environmental documents are to be safely retained for the next school/building occupants.* All asbestos reports must be available to the public and Federal EPA upon request.



Fran Burns
Chief Operation Officer

Francine Locke, M.S., Director
Office of Environmental Management
and Services

Executive Summary

This Asbestos Hazard Emergency Response Act (AHERA) Three-Year Re-inspection “Volume # IX” Management Plan at this location, has been completed and the report of re-inspection submitted to the School District of Philadelphia. The re-inspections in all School District of Philadelphia buildings of 2015-2016 were conducted and completed between October 5th, 2015 through March 30th, 2016 as a joint project by Accredited Environmental Technologies, Inc., Batta Environmental Associates, Inc., Criterion Laboratories, Inc., Environmental Testing Consultants, LLC, G & C Environmental Services, Inc., KEM Partners, Inc., Synertech, Inc., TTI Environmental, Inc., USA Environmental Management, Inc. and The Vertex Companies, Inc.

In general, the School District of Philadelphia Office of Environmental Management and Services conducts Environmental Impact Evaluations and provides Asbestos Inspection Reports prior to any renovation, demolition and/or maintenance activities. The AHERA report must be reviewed prior to any renovation, demolition and/or maintenance activities in order to avoid the unknowing disturbance to Asbestos Containing Building Materials identified within this location. In addition, prior to work activities above all drop ceilings this report should be reviewed to avoid potential disturbances to Asbestos Containing Materials. Refer to Section IV of the Cross Reference Table, for additional Asbestos Management Program information. Contact the Office of Environmental Management and Services to have an Environmental Impact Evaluation conducted prior to any renovation, demolition and/or maintenance activities within this facility.

The information contained in this report was obtained from the original Asbestos Management Plan for the school, from update reports on changes and activities since the completion of the 1st Management Plan for each location and from all prior inspections performed and documented in Volume # I through Volume VIII (dated respectively 1992, 1995, 1998, 2001, 2004, 2007, 2010 or 2013) (if applicable) - and by this Three-Year Re-inspection of this school. The re-inspection report/Management Plan of 2015-2016 were reviewed and prepared collectively by Management Planner Megan Vala, Mary Anne Lerro of Criterion Laboratories, Inc. and/or Monique Causley, of Synertech Inc.

The 2015-2016 inspection process included the addition of a comprehensive Room by Room Inventory of all Thermal (T), Surfacing (S) and Miscellaneous (M) Materials specific to each room of this facility. Inspections of each room's thermal, ceilings, walls, floors and miscellaneous items regardless of Asbestos Content are categorized on the Room by Room Location Log Report for this location. Rooms or areas of the facility that were not accessible at the time of the inspection are marked with an "X". The Room by Room Location Log Report is found in Section II C of this Management Plan.

All Presumed or Suspect Asbestos Containing Building Materials (ACBMs), listed in the following summary charts are categorized as Confirmed, Assumed, Non-Asbestos, and/or Non-Suspect (ACBMs) were identified in the original Management Plan, or in the Volume I through Volume VIII AHERA Three-Year Re-inspection reports, and were re-inspected as part of this project.

As mandated by the U S EPA AHERA regulations, periodic Six-Month inspections and Three-Year Re-inspections of this location will be performed and the Inspection Data in this report will be updated accordingly.

Please feel free to contact the School District of Philadelphia's Office of Environmental Management and Services (OEMS) regarding any comments, questions, or concerns regarding this report or any Environmental related topic. OEMS staff can be reached at (215) 400 4750, via fax at (215) 400 4751 or via e-mail at flocke@philasd.org and/or gfunod@philasd.org.

Additional information can be found on our website. Here is the link to the OEMS website.
<http://webgui.phila.k12.pa.us/offices/e/environmental>

I. Summary list of Confirmed Asbestos Containing Building Materials within this facility

These charts are to be used for a quick reference* in order to avoid the unknowing disturbance of Asbestos Containing Materials during any and all Operations, Maintenance, Renovation, and/or Demolition activities at this location. *These materials have been sampled and Laboratory Analysis has CONFIRMED the presence of Asbestos. Contact OEMS prior to the disturbance of any of the following materials.*

Confirmed Asbestos Containing Building Materials for this location

Floor Tile VAT 9" x 9"	Pipe Fitting Insulation	Pipe Insulation > 6 inch
Pipe Insulation 2-6 inch		

** Always refer to the Room by Room Logs for each specific material classification as the material classification findings may be different in various rooms throughout this facility.*

*** Some Materials may have multiple classifications (Confirmed, Assumed, NAD and Non Suspect) within this facility.*

II. Summary list of Assumed Asbestos Containing Building Materials within this facility

These charts are to be used for a quick reference* in order to avoid the unknowing disturbance of Asbestos Containing Materials during any and all Operations, Maintenance, Renovation, and/or Demolition activities at this location. These materials have not been sampled and should not be disturbed until verification of Asbestos Content. Contact OEMS for assessment and sampling prior to the disturbance of these materials.

Assumed Asbestos Containing Building Materials for this location

Black Mastic Damp Proofing	Blackboard Glue Dots	Boiler Breeching Gaskets
Brick Incinerator	Brown Caulk	Ceiling Tile 1' x 1'
Duct Seam Packing	Exterior Caulking (expansion seam, window, door, etc.)	Floor Tile VAT 12" x 12"
Horse Hair Pipe/Pipe Fitting Insulation	Incinerator Breeching Gaskets	Kiln
Radiator Insulation	Roofing Materials	Sink Undercoat Mastic
Transite Electrical Panel	Transite Sills	Transite Sink
Vibration Damper Cloth	Wall and Ceiling Glue Dots	Wire Insulation

** Always refer to the Room by Room Logs for each specific material classification as the material classification findings may be different in various rooms throughout this facility.*

*** Some Materials may have multiple classifications (Confirmed, Assumed, NAD and Non Suspect) within this facility.*

III. Summary list of Non-Asbestos Containing Building Materials within this facility

These charts are to be used for a quick reference* in order to avoid the unknowing disturbance of Asbestos Containing Materials during any and all Operations, Maintenance, Renovation, and/or Demolition activities at this location. *These materials have been sampled and Laboratory Analysis has indicated NO Asbestos present or NO ASBESTOS DETECTED (NAD).*

Non- Asbestos Containing Building Materials for this location

Acoustical Plaster Ceiling	Acoustical Plaster Walls	Ceiling Tile 1' x 1'
Concrete Ceiling	Fire Doors	Floor Tile VAT 12" x 12"
Mastic associated with Floor Tile	Package Boilers	Plaster Ceiling
Plaster Walls		

* *Always refer to the Room by Room Logs for each specific material classification as the material classification findings may be different in various rooms throughout this facility.*

** *Some Materials may have multiple classifications (Confirmed, Assumed, NAD and Non Suspect) within this facility.*

IV. Summary list of Non-Suspect Asbestos Containing Building Materials within this facility

These charts are to be used for a quick reference* in order to avoid the unknowing disturbance of Asbestos Containing Materials during any and all Operations, Maintenance, Renovation, and/or Demolition activities at this location. These materials are not typically known to contain Asbestos.

Non-Suspect Asbestos Containing Building Materials for this location

Brick Wall	Ceiling Tile 2' x 4'	Cement Floor
Ceramic Tile Floors	Ceramic Tile Walls	Concrete Block Wall
Concrete Ceiling	Concrete Floor	Duct Work
Emergency Generator Piping	Fiberglass Ceiling Tile 2' x 4'	Fiberglass Pipe Fitting Insulation
Fiberglass Pipe Insulation	Granite Floor	Granite Walls
Metal Duct	Metal Fan Unit	Metal Shelves
Metal Stairs	Metal Supply Ductwork	Plywood Walls
Sheetrock Wall	Vinyl Vibration Damper Cloth	Wood Catwalks
Wood Floor	Wood Wall Partition Room	Dividers

** Always refer to the Room by Room Logs for each specific material classification as the material classification findings may be different in various rooms throughout this facility.*

*** Some Materials may have multiple classifications (Confirmed, Assumed, NAD and Non Suspect) within this facility.*

V. Summary list of Auditorium DATA for this location

These charts are to be used for a quick reference of the Auditorium DATA within this facility. Sampling of the Auditorium Ceilings throughout the District is more difficult because of the various ceiling heights. As sampling occurs this information is updated on a case by case basis for each specific location and facility.

This is a list of known materials for this location's Auditorium

Auditorium		
Auditorium	Wood Floor	Non Suspect ACM
Auditorium	Acoustical Plaster Ceiling	NAD
Auditorium	Acoustical Plaster Walls	NAD
Auditorium	Radiator Insulation	Assumed
Auditorium	Wood Floor	Non Suspect ACM
Auditorium	Acoustical Plaster Ceiling	NAD
Auditorium	Acoustical Plaster Walls	NAD
Auditorium Balcony	Wood Floor	Non Suspect ACM
Auditorium Balcony	Plaster Walls	NAD
Auditorium Balcony	Plaster Ceiling	NAD

** Always refer to the Room by Room Logs for each specific material classification as the material classification findings may be different in various rooms throughout this facility.*

*** Some Materials may have multiple classifications (Confirmed, Assumed, NAD and Non Suspect) within this facility.*

VI. Summary list of Attic and/or Crawlspace DATA for this location

These charts are to be used for a quick reference regarding the Attics and/or Crawlspaces inspection DATA within this facility. Contact OEMS prior to entering any attic or crawlspace within this facility and refer to the below chart and legend for Category Rank determination. The Data relative to these spaces is updated as conditions change regarding Abatement or Renovation activity on a case by case basis for each specific location and facility. In general, Crawlspaces are below the basement or 1st floor and Attics are above the floor space.

Category Rank Legend

"A" - No Asbestos Containing Materials - Sample Results indicate NO ACM on pipes, fittings, elbows, or equipment located within this functional space, and NO VISIBLE DEBRIS or DAMAGE observed at time of this inspection.
"B" - Asbestos Containing Materials Exist - Sample Results indicate ACM on pipes, fittings, elbows, or equipment located within this functional space, HOWEVER, NO VISIBLE DEBRIS or DAMAGE observed at time of this inspection.
"C" - Asbestos Containing Materials Exist - Sample Results indicate ACM on pipes, fittings, elbows, or equipment located within this functional space, and LOCALIZED VISIBLE DEBRIS or DAMAGE observed at time of this inspection.
"D" - Asbestos Containing Materials Exist - Sample Results indicate ACM on pipes, fittings, elbows, or equipment located within this functional space and DISTRIBUTED VISIBLE DEBRIS or SIGNIFICANT DAMAGE observed at time of this inspection.
"E" - No Bulk Sample Results Available SUSPECT ACM OBSERVED. Contact OEMS immediately for additional instructions.

Attic/Crawlspace	Access Area	Floor Surface	Category Rank	Comments
Main Attic	Storage Rooms 410 and 411	Plaster/Wood Catwalks	"B"	No TSI, Black Mastic Damp Proofing applied to Brick Walls is Assumed
Attic above Auditorium	Storage Rooms 314A, 325, 327, and 328	Plaster/Wood Catwalks	"B"	No TSI, Black Mastic Damp Proofing applied to Brick Walls is Assumed
Crawl Space – Concrete Distribution Tunnel/Air Supply Plenum	Fan Room 1	Concrete	"A"	Runs under 1 st Floor Hallway
Crawl Space – Concrete Distribution Tunnel/Air Supply Plenum	Fan Room 2	Concrete	"A"	Runs under 1 st Floor Hallway

VII. Summary list of Pipe Chase/Pipe Shaft DATA for this location

These charts are to be used for a quick reference regarding the information known about the Pipe Chases and/or Pipe Shafts inspection DATA within this facility. Contact OEMS prior to performing renovation activities any Pipe Chase and/or Pipe Shaft within this facility and refer to the below chart and legend for Asbestos Content of various materials identified within each space. The Data relative to these spaces is updated as conditions change regarding Inspection, Abatement and/or Renovation activity on a case by case basis for each specific location and facility. In general, Pipe Chases are horizontal spaces and Pipe Shafts are vertical spaces.

<i>Element</i>	<i>Floor</i>	<i>On Site Room Name</i>	<i>Material</i>	<i>Confirmed /Assumed NAD/Non Suspect</i>	<i>Amount of Material</i>	<i>Amount of Damage</i>
1	4	Restroom Pipe Chase adjacent to Classroom 409 (access in Penthouse Tank Room across from Office 401)	Cement Floor	Non Suspect ACM	60 SF	0
1	4	Restroom Pipe Chase adjacent to Classroom 409	Concrete Block Wall	Non Suspect ACM	180 SF	0
1	4	Restroom Pipe Chase adjacent to Classroom 409	Concrete Ceiling	Non Suspect ACM	60 SF	0
1	4	Restroom Pipe Chase adjacent to Classroom 409	Fiberglass Pipe Insulation	Non Suspect ACM	25 LF	0
1	4	Restroom Pipe Chase adjacent to Classroom 409	Pipe Fitting Insulation	Confirmed	4 EA	0
1	3	Boy's Restroom Pipe Chase across from Classroom 302 (access from Custodial Closet)	Cement Floor	Non Suspect ACM	60 SF	0
1	3	Boy's Restroom Pipe Chase across from Classroom 302	Concrete Block Wall	Non Suspect ACM	180 SF	0
1	3	Boy's Restroom Pipe Chase across from Classroom 302	Concrete Ceiling	Non Suspect ACM	60 SF	0
1	3	Boy's Restroom Pipe Chase across from Classroom 302	Fiberglass Pipe Insulation	Non Suspect ACM	25 LF	0
1	3	Boy's Restroom Pipe Chase across from Classroom 302	Transite Shelf	Assumed	10 SF	0
1	3	Girl's Restroom Pipe Chase across from Classroom 314 (access from Custodial Closet)	Cement Floor	Non Suspect ACM	60 SF	0
1	3	Girl's Restroom Pipe Chase across from Classroom 314	Concrete Block Wall	Non Suspect ACM	180 SF	0
1	3	Girl's Restroom Pipe Chase across from Classroom 314	Concrete Ceiling	Non Suspect ACM	60 SF	0
1	3	Girl's Restroom Pipe Chase across from Classroom 314	Fiberglass Pipe Insulation	Non Suspect ACM	25 LF	0
1	3	Girl's Restroom Pipe Chase across from Classroom 314	Transite Shelf	Assumed	10 SF	0

VII. Summary list of Pipe Chase/Pipe Shaft DATA for this location (continued)

<i>Element</i>	<i>Floor</i>	<i>On Site Room Name</i>	<i>Material</i>	<i>Confirmed /Assumed NAD/Non Suspect</i>	<i>Amount of Material</i>	<i>Amount of Damage</i>
1	2	Boy's Restroom Pipe Chase across from Classroom 202 (access from Custodial Closet)	Cement Floor	Non Suspect ACM	60 SF	0
1	2	Boy's Restroom Pipe Chase across from Classroom 202	Concrete Block Wall	Non Suspect ACM	180 SF	0
1	2	Boy's Restroom Pipe Chase across from Classroom 202	Concrete Ceiling	Non Suspect ACM	60 SF	0
1	2	Boy's Restroom Pipe Chase across from Classroom 202	Fiberglass Pipe Insulation	Non Suspect ACM	25 LF	0
1	2	Boy's Restroom Pipe Chase across from Classroom 202	Transite Shelf	Assumed	10 SF	0
1	2	Girl's Restroom Pipe Chase across from Classroom 214 (access from Custodial Closet)	Cement Floor	Non Suspect ACM	60 SF	0
1	2	Girl's Restroom Pipe Chase across from Classroom 214	Concrete Block Wall	Non Suspect ACM	180 SF	0
1	2	Girl's Restroom Pipe Chase across from Classroom 214	Concrete Ceiling	Non Suspect ACM	60 SF	0
1	2	Girl's Restroom Pipe Chase across from Classroom 214	Fiberglass Pipe Insulation	Non Suspect ACM	25 LF	0
1	2	Girl's Restroom Pipe Chase across from Classroom 214	Transite Shelf	Assumed	20 SF	0
1	1	Girl's Restroom Pipe Chase across from Classroom 108A (access from Custodial Closet)	Cement Floor	Non Suspect ACM	60 SF	0
1	1	Girl's Restroom Pipe Chase across from Classroom 108A	Concrete Block Wall	Non Suspect ACM	180 SF	0
1	1	Girl's Restroom Pipe Chase across from Classroom 108A	Concrete Ceiling	Non Suspect ACM	60 SF	0
1	1	Girl's Restroom Pipe Chase across from Classroom 108A	Fiberglass Pipe Insulation	Non Suspect ACM	25 LF	0
1	1	Girl's Restroom Pipe Chase across from Classroom 108A	Transite Shelf	Assumed	10 SF	0
1	1	Boy's Restroom Pipe Chase across from Classroom 101 (access from Custodial Closet)	Cement Floor	Non Suspect ACM	60 SF	0
1	1	Boy's Restroom Pipe Chase across from Classroom 101	Concrete Block Wall	Non Suspect ACM	180 SF	0
1	1	Boy's Restroom Pipe Chase across from Classroom 101	Concrete Ceiling	Non Suspect ACM	60 SF	0
1	1	Boy's Restroom Pipe Chase across from Classroom 101	Fiberglass Pipe Insulation	Non Suspect ACM	25 LF	0
1	1	Boy's Restroom Pipe Chase across from Classroom 101	Transite Shelf	Assumed	20 SF	0

Section I

Report of Re-Inspection

A. Introduction

B. Three-Year Re-Inspection IX Overview

C. Post-Management Plan Activities and Changes

C.1 Sampling and Analysis

C.2 New Floor Tile Sampling

C.3 Abatement Activity

C.4 Periodic Six-Month Surveillance (Damaged Materials)

Section I - A

Report of Re-inspection

Introduction

The Three-Year Re-inspection IX was performed to fulfill the requirements of 40 CFR Part 763 - the Asbestos Hazard Emergency Response Act (AHERA). As required by AHERA, each Local Education Agency (LEA) must re-inspect all known confirmed or assumed Asbestos Containing Building Material (ACBM) located in the LEA's facilities. This re-inspection is intended to update the original Asbestos Management Plan for the LEA's facilities.

Multiple Building Inspectors of several firms performed the 2015/2016 re-inspection. The re-inspection report/Management Plan of 2015-2016 were reviewed and prepared collectively by Management Planner Megan Vala, Mary Anne Lerro of Criterion Laboratories, Inc. and Monique Causley, of Synertech Inc.

All of the certificates can be found in Section III.

During the re-inspection of each School District of Philadelphia facility, all of the Management Plans for that facility were reviewed. Information from the conclusions section of that report is included in this report. Additionally, information on activities such as abatements, cleanings, sampling and inspections, which have taken place since the completion of the original Management Plan, were reviewed during the re-inspection. Information on those activities is included in this report.

As mandated by the U S EPA AHERA regulations, all future periodic Six-Month inspections and Three-Year Re-inspections of this location will be performed and the Inspection Data in this report will be updated accordingly.

Section I - B

Three-Year Re-inspection IX Overview

Each homogeneous area of Asbestos Containing Building Material (ACBM) listed in the original Management Plan or in the 1992, 1995, 1998, 2001, etc., Three-Year Re-inspection reports were inspected for the AHERA Three-Year Re-inspection Volume IX, and the information for that material verified. Any changes to a homogeneous area listed in the updates to the Management Plans were verified. Any area of suspected ACBM found in the course of the re-inspection, and not listed in the Management Plan or updates, were either assumed to contain asbestos or sampled and analyzed to determine their asbestos content. Any such new areas either assumed to contain asbestos or determined through analysis to contain asbestos were included in the report of the Three-Year Re-inspection. The results of the AHERA Three-Year Re-inspection IX are tabulated in the Room by Room log reports located in *Section II-C* of this report.

As previously noted, all future periodic Six-Month inspections and Three-Year Re-inspections of this location will be performed and the Inspection Data in this report will be updated accordingly.

Section I – C.1

Post Management Plan Activities/Changes

Information on activities affecting Asbestos Containing Building Materials (ACBMs) at this location is contained in updates to the Management Plan. These updates are kept on file by the School District of Philadelphia and were reviewed for this project. Updates to the Management Plan include the following: *Sampling and Analysis, New Tile Installation, Abatement Activity and Periodic Six-Month Surveillance Data.*

Sampling and Analysis

In the event Sampling occurs, data will be listed here.

Section I – C.2

Information on the installation of new floor tiles/renovation activities affecting Asbestos Containing Building Materials (ACBMs) at this location is contained in updates to the Management Plan. These updates are kept on file by the School District of Philadelphia and were reviewed for this project. Updates to the Management Plan include the following:

New Floor Tile Sampling

In the event that new tile is installed, the material must be tested prior to installation.

Section I – C.3

Information on the Asbestos Abatement and renovation activities affecting Asbestos Containing Building Materials (ACBMs) at this location is contained in updates to the Management Plan. These updates are kept on file by the School District of Philadelphia and were reviewed for this project. Updates to the Management Plan include the following:

Abatement Activity

In the event Abatement occurs, data will be listed here.

Section I – C.4

Information on the AHERA inspection that noted damage to various Building Materials at this location is contained in updates to the Management Plan. These updates are kept on file by the School District of Philadelphia and were reviewed for this project. Work orders are created for Corrective Action responses and tracked for completion. Updates to the Management Plan include the following:

Periodic (Six-Month) Surveillance (Damaged Materials)

<i>Date</i>	<i>Element</i>	<i>Floor</i>	<i>On Site Room Name</i>	<i>Material</i>	<i>Amount of Material</i>	<i>Amount of Damage</i>
11/2/2016	1	3	Hallway outside Classrooms 304 - 311	Pipe Insulation 2-6 inch	72 LF	1 LF
11/2/2016	1	3	Hallway outside Classrooms 315 - 322	Pipe Insulation 2-6 inch	126 LF	1 LF
11/2/2016	1	3	Stairwell across from Classroom 314	Pipe Insulation 2-6 inch	22 LF	1 LF
11/2/2016	1	3	Stairwell across from Classroom 312	Pipe Insulation 2-6 inch	24 LF	1 LF
11/2/2016	1	3	Stairwell across from Classroom 303	Pipe Insulation 2-6 inch	22 LF	1 LF
11/2/2016	1	2	Stairwell across from Classroom 214	Pipe Insulation 2-6 inch	32 LF	1 LF
11/2/2016	1	2	Stairwell across from Classroom 212	Pipe Insulation 2-6 inch	32 LF	1 LF
11/2/2016	1	1	Hallway outside Cafeteria and Fan Rooms	Pipe Insulation 2-6 inch	132 LF	2 LF
11/2/2016	1	B	Emergency Generator/Oil Pump Room next to Boiler Room	Pipe Insulation 2-6 inch	60 LF	1 LF
11/2/2016	1	B	Rear Storage Room inside Girl's Gym	Pipe Insulation 2-6 inch	10 LF	1 LF
11/2/2016	1	B	Girl's Gym Office - Bottom of Stairs at Gym Entrance	Pipe Fitting Insulation	1 EA	1 EA
11/2/2016	1	B	Small Hallway to Girl's Gym Office - Bottom of Stairs at Gym Entrance	Pipe Fitting Insulation	6 EA	1 EA

Section II

Re-Inspection Data

A. Introduction

B. Re-Inspection Key Definitions

C. Room by Room Location Log Report

Section II - A

Re-inspection Data

Introduction

The following information documents the Three-Year Re-inspection IX of the subject school/facility. The Homogeneous Area Reports were produced using the building inspector's field data on the facility. The key to the Homogeneous Area Report is outlined in the following pages of this report.

Section II - B
(page 1 of 4)

SCHOOL DISTRICT OF PHILADELPHIA
AHERA THREE YEAR RE-INSPECTION IX

ITEM	DEFINITION
ULCS#	Individual identification number assigned to each school within the School District of Philadelphia.
HOMOGENEOUS AREA ID#	Identification number assigned to each homogeneous area in a school/facility. Each section of the homogeneous area ID is significant. 1010/01/01/01 A B C D A. Is the ULCS# for the school. B. Designates the specific building/building area within the school. C. Designates the floor or level within the building/building area. D. Designates the homogeneous material within that floor or level. Note: Item D may be a number or a letter.
SYSTEM AFFECTED	Corresponds to the AHERA system for classifying materials. T : Thermal System S : Surfacing System M : Miscellaneous
ITEM AFFECTED	Is a description of the homogeneous material.
ORIGINAL INSPECTION DATA	This section contains the information found in the original Management Plan (1988-1989).
AMOUNT OF MATERIAL/ UNIT	Quantity of material, and measuring unit. Units include: Square Feet (SF) Each (EA) Linear Feet (LF) Cubic Feet (CF).

**SCHOOL DISTRICT OF PHILADELPHIA
AHERA THREE YEAR RE-INSPECTION IX**

RE-INSPECTION FORM KEY

ITEM	DEFINITION
CND Condition	Corresponds to AHERA condition rating for materials. 0 : No Damage 1 : Damage 2 : Significant Damage
DP Damage Potential	Corresponds to the AHERA material assessment system. 1 : Potential for Damage 2 : Potential for Significant Damage
ASMD Assumed Asbestos	This means that a material was not sampled for asbestos content during the original Management Plan inspection.
RA Response Action	This corresponds to the AHERA system of response action rating for materials. 1 : Establish O&M Program 2 : Repair and Establish O&M Program 3 : Enclose 4 : Encapsulate 5 : Remove 6 : Partial Removal and Establish O&M Program
CHANGES	This section describes changes to the homogeneous material in the twenty-four years since the original AHERA inspection. The abbreviations are defined below. RMVD : Removed ENCL : Enclosed ENCP : Encapsulated DMGD : Damaged SMPLD : Sampled MTRL : Material RPRD : Repaired N/L : None Located RPLCD : Replaced

**SCHOOL DISTRICT OF PHILADELPHIA
AHERA THREE-YEAR RE-INSPECTION IX**

RE-INSPECTION FORM KEY

ITEM	DEFINITION																				
THREE YEAR RE-INSPECTION	<p>This section contains the information obtained from the Three-Year Re-inspection IX. With three exceptions, the information categories are identical in format and meaning to those found in the original inspection data section. The three exceptions are defined below.</p>																				
DMGD AMT Amount Damaged	<p>This section gives the quantity of damaged material in a homogeneous area. The quantity is shown in the same format as the amount of material/unit section.</p>																				
NF Newly Friable	<p>This section identifies materials in the original Management Plan which have since become friable.</p>																				
RA Response Action	<p>This rating is based on the AHERA regulations, and is comparable to the RA rating found in the "Original Inspection Data" section. The following table details the response actions.</p> <table><tr><td>1.</td><td>Establish O&M Program</td></tr><tr><td>2.</td><td>Repair and Establish O&M Program</td></tr><tr><td>3.</td><td>Enclose</td></tr><tr><td>4.</td><td>Encapsulate</td></tr><tr><td>5.</td><td>Remove</td></tr><tr><td>6.</td><td>Partial Removal and Establish O&M Program</td></tr><tr><td>a.</td><td>High Priority Response The homogeneous material has been scheduled for abatement or other response action.</td></tr><tr><td>b.</td><td>Medium Priority Response The homogeneous material will be scheduled for abatement or other response action as soon as the high priority responses have been addressed.</td></tr><tr><td>c.</td><td>Low Priority Response The homogeneous material will be scheduled for abatement or other response action as soon as the medium priority responses have been addressed.</td></tr><tr><td>d.</td><td>On-Going Response/Operations and Maintenance The homogeneous material does not require abatement or other response action at present, and should be included in the facility's on-going operations and maintenance program.</td></tr></table>	1.	Establish O&M Program	2.	Repair and Establish O&M Program	3.	Enclose	4.	Encapsulate	5.	Remove	6.	Partial Removal and Establish O&M Program	a.	High Priority Response The homogeneous material has been scheduled for abatement or other response action.	b.	Medium Priority Response The homogeneous material will be scheduled for abatement or other response action as soon as the high priority responses have been addressed.	c.	Low Priority Response The homogeneous material will be scheduled for abatement or other response action as soon as the medium priority responses have been addressed.	d.	On-Going Response/Operations and Maintenance The homogeneous material does not require abatement or other response action at present, and should be included in the facility's on-going operations and maintenance program.
1.	Establish O&M Program																				
2.	Repair and Establish O&M Program																				
3.	Enclose																				
4.	Encapsulate																				
5.	Remove																				
6.	Partial Removal and Establish O&M Program																				
a.	High Priority Response The homogeneous material has been scheduled for abatement or other response action.																				
b.	Medium Priority Response The homogeneous material will be scheduled for abatement or other response action as soon as the high priority responses have been addressed.																				
c.	Low Priority Response The homogeneous material will be scheduled for abatement or other response action as soon as the medium priority responses have been addressed.																				
d.	On-Going Response/Operations and Maintenance The homogeneous material does not require abatement or other response action at present, and should be included in the facility's on-going operations and maintenance program.																				

**SCHOOL DISTRICT OF PHILADELPHIA
AHERA THREE-YEAR RE-INSPECTION IX**

RE-INSPECTION FORM KEY

The information presented in the changes section has been compiled from a variety of sources, including the Re-inspection and the following:

- * Quality Control/Quality Assurance Reports of asbestos abatement projects, prepared by consultants to the School District.
- * Permit and Notification Forms for asbestos abatement projects.
- * Periodic Surveillance Forms
- * Operations and Maintenance activities performed by School District personnel.
- * Verbal information from School District personnel.
- * Reports of sampling and analysis of suspected materials by both School District personnel and outside consultants.

**ROOM BY
ROOM
LOCATION LOG
REPORT**

This section gives information, including damage amount and location, for a specific homogeneous material on a room-by-room basis and follows the Re-inspection form.

NOTE: The disparate nature of the above sources of information prohibits the verification of much information within the scope of the AHERA Three-Year Re-inspection. Discrepancies and omissions may exist in this information, and therefore is included on an "as is" basis. The inspectors for the Three-Year Re-inspection IX evaluated homogeneous areas based on the materials current condition and location, as evidenced during the inspector's site visit.

Section II - C

Room by Room Location Log Report

These charts are to be used for a quick reference* in order to avoid the unknowing disturbance of Asbestos Containing Materials during any and all Operations, Maintenance, Renovation, and/or Demolition activities at this location.

NOTE:

*Contact OEMS prior to the disturbance of any of the materials that are listed as **Confirmed and/or Assumed**.*

The quantities listed for (NAD) non-asbestos containing materials and/or Non-Suspect Materials are only estimated and were not measured for the purpose of this report. Field verification of quantities for renovation purposes would be necessary.

8120 Woodrow Wilson MS 2015 2016 AHERA Three-Year Report.xls

School District of Philadelphia Woodrow Wilson Middle School 1800 Cottman Ave, Philadelphia, PA 19111 ULCS# 8120 Year Built: 1928			AHERA Three-Year Reinspection 2015-2016 Room by Room Location Log Report										Reinspection Date: December 3, 2015 Building Inspector: Norman Harrison Number: 037951 Management Planner: Megan Vala Number: 740728				
E l e m e n t	F l o o r	On Site Room Name	System Affected	Material Description	HID#	Confirmed/Assumed/NAD/ Non Suspect ACM	Amount of Material	SF LF EA	Amount of Damage	SF LF EA	Color required for VAT	Comments/Description/Notes	Attic/ Crawl Space Ranking	Damage Potential (DP)	Newly Friable (NF)	Response Action (RA)	
1	R	Rooftop(s)	M	Roofing Materials	8120/01/0R/SYN/BB/2613	Assumed	63,000	SF	0	SF				1	No	1/D	
1	E	Exterior	M	Exterior Caulking (expansion seam, window, door, etc.)	8120/01/0B/SYN/BB/2625	Assumed	Q/U	LF	0	LF				1	No	1/D	
1	TH	Throughout	N/A	Fire Doors		NAD	150	EA	X	EA		The Management Plan states all assumed asbestos packed fire doors have been removed/replaced		N/A	N/A	N/A	
1	TH	Throughout	M	Wire Insulation	8120/01/TH/SYN/BB/1626	Assumed	16	EA	0	EA				1	No	1/D	
1	TH	Throughout	T	Pipe Insulation 2-6 inch	8120/01/TH/SYN/BB/1100	Confirmed	1800	LF	0	LF		Associated with the lateral sections of heating system piping above suspended ceiling tiles throughout the building (approx. 300 pipe risers)		1	No	1/D	
1	TH	Throughout	T	Pipe Fitting Insulation	8120/01/TH/SYN/BB/1120	Confirmed	1200	EA	0	EA		Associated with the lateral sections of heating system piping above suspended ceiling tiles throughout the building (approx. 300 pipe risers)		1	No	1/D	
1	PH	Penthouse Tank Room	N/A	Cement Floor		Non Suspect ACM	450	SF	X	SF				N/A	N/A	N/A	
				Metal Stairs													
1	PH	Penthouse Tank Room	N/A			Non Suspect ACM	1	EA	X	EA		Access to Penthouse Tank Room across from Office 401		N/A	N/A	N/A	
1	PH	Penthouse Tank Room	N/A	Brick Wall		Non Suspect ACM	1350	SF	X	SF				N/A	N/A	N/A	
1	PH	Penthouse Tank Room	N/A	Concrete Ceiling		Non Suspect ACM	450	SF	X	SF				N/A	N/A	N/A	
1	PH	Penthouse Tank Room	T	Pipe Insulation 2-6 inch	8120/01/05(PH)/DD	Confirmed	20	LF	0	LF				1	No	1/D	
1	PH	Penthouse Tank Room	T	Pipe Fitting Insulation	8120/01/05(PH)/74	Confirmed	11	EA	0	EA		Associated with ACPI		1	No	1/D	
1	PH	Penthouse Tank Room	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	50	LF	X	LF				N/A	N/A	N/A	
1	PH	Penthouse Tank Room	T	Pipe Fitting Insulation	8120/01/05(PH)/74	Confirmed	3	EA	0	EA		Associated with FGPI		1	No	1/D	
1	PH	Penthouse Exhaust Fan Room along Loretto Avenue	N/A	Cement Floor		Non Suspect ACM	150	SF	X	SF				N/A	N/A	N/A	
1	PH	Penthouse Exhaust Fan Room along Loretto Avenue	N/A	Brick Wall		Non Suspect ACM	450	SF	X	SF				N/A	N/A	N/A	
1	PH	Penthouse Exhaust Fan Room along Loretto Avenue	N/A	Concrete Ceiling		Non Suspect ACM	150	SF	X	SF				N/A	N/A	N/A	
1	PH	Penthouse Exhaust Fan Room along Loretto Avenue	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	2	LF	X	LF				N/A	N/A	N/A	
1	PH	Penthouse Exhaust Fan Room along Loretto Avenue	N/A	Vinyl Vibration Damper Cloth		Non Suspect ACM	1	SF	X	SF		Vibration Damper Cloth removed from the exhaust fan associated with the Boys Gym 011		N/A	N/A	N/A	
1	PH	Penthouse Exhaust Fan Room along Loretto Avenue	M	Transite Electrical Panel	8120/01/05(PH)/RR	Assumed	16	SF	0	SF				1	No	1/D	
1	PH	Large Penthouse Exhaust Fan Room along Englewood Street	N/A	Cement Floor		Non Suspect ACM	450	SF	X	SF		Vibration Damper Cloth removed from the exhaust fan associated with the 1st Floor Kitchen and Cafeteria		N/A	N/A	N/A	
1	PH	Large Penthouse Exhaust Fan Room along Englewood Street	N/A	Brick Wall		Non Suspect ACM	1350	SF	X	SF				N/A	N/A	N/A	
1	PH	Large Penthouse Exhaust Fan Room along Englewood Street	N/A	Concrete Ceiling		Non Suspect ACM	450	SF	X	SF				N/A	N/A	N/A	
1	PH	Large Penthouse Exhaust Fan Room along Englewood Street	T	Pipe Insulation 2-6 inch	8120/01/05(PH)/DD	Confirmed	35	LF	0	LF				1	No	1/D	
1	PH	Large Penthouse Exhaust Fan Room along Englewood Street	T	Pipe Fitting Insulation	8120/01/05(PH)/74	Confirmed	2	EA	0	EA				1	No	1/D	
1	PH	Large Penthouse Exhaust Fan Room along Englewood Street	T	Horse Hair Pipe/Pipe Fitting Insulation	8120/01/05(PH)/SYN/BB/1140	Assumed	20	LF	X	LF		Along floor at 2 entrances - Damage along pipe lengths; ACM assumed present below fittings		X	X	X	
1	PH	Penthouse Exhaust Fan Room along Frontenac Street	N/A	Cement Floor		Non Suspect ACM	150	SF	X	SF				N/A	N/A	N/A	
1	PH	Penthouse Exhaust Fan Room along Frontenac Street	N/A	Brick Wall		Non Suspect ACM	450	SF	X	SF				N/A	N/A	N/A	
1	PH	Penthouse Exhaust Fan Room along Frontenac Street	N/A	Concrete Ceiling		Non Suspect ACM	150	SF	X	SF				N/A	N/A	N/A	
1	PH	Penthouse Exhaust Fan Room along Frontenac Street	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	2	LF	X	LF				N/A	N/A	N/A	
1	PH	Penthouse Exhaust Fan Room along Frontenac Street	N/A	black vinyl vibration damper connectors		Non Suspect ACM	1	SF	X	SF		Vibration Damper Cloth removed from the exhaust fan associated with the Girls Gym 007		N/A	N/A	N/A	
1	A	Main Attic above Third Floor	N/A	Plaster Floor (3rd Floor Ceiling)		NAD	25,000	SF	X	SF		Foul airshafts and roof ventilators are covered with polyethylene sheeting	B	N/A	N/A	N/A	
1	A	Main Attic above Third Floor	N/A	Wood Catwalks		Non Suspect ACM	2500	SF	X	SF		Attic Entrances are in Storage Rooms 410 and 411	B	N/A	N/A	N/A	
1	A	Main Attic above Third Floor	N/A	Brick Wall		Non Suspect ACM	25,000	SF	X	SF		Black mastic damp-proofing applied to brick walls is assumed asbestos containing	B	N/A	N/A	N/A	
1	A	Main Attic above Third Floor	M	Black Mastic Damp Proofing	8120/01/0A/SYN/BB/2624	Assumed	25,000	SF	X	SF		Applied to brick walls	B	X	X	X	
1	A	Main Attic above Third Floor	N/A	Concrete Ceiling		Non Suspect ACM	12,500	SF	X	SF				B	N/A	N/A	N/A
1	A	Main Attic above Third Floor	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	3000	LF	X	LF				B	N/A	N/A	N/A
1	4	Restroom adjacent to Classroom 402	N/A	Cement Floor		Non Suspect ACM	187	SF	0	SF					N/A	N/A	N/A
1	4	Restroom adjacent to Classroom 402	N/A	Plaster Ceiling		NAD	187	SF	0	SF					N/A	N/A	N/A
1	4	Restroom adjacent to Classroom 402	N/A	Ceramic Tile Walls		Non Suspect ACM	200	SF	0	SF					N/A	N/A	N/A
1	4	Restroom adjacent to Classroom 402	N/A	Brick Wall		Non Suspect ACM	200	SF	0	SF					N/A	N/A	N/A
1	4	Restroom adjacent to Classroom 402	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	10	LF	0	LF					N/A	N/A	N/A
1	4	Penthouse Tank Room Entrance across fromfice 401	N/A	Cement Floor		Non Suspect ACM	30	SF	X	SF		Steep Stairs to Penthouse Tank Room		N/A	N/A	N/A	
1	4	Penthouse Tank Room Entrance across fromfice 401	N/A	Brick Wall		Non Suspect ACM	90	SF	X	SF				N/A	N/A	N/A	
1	4	Penthouse Tank Room Entrance across fromfice 401	N/A	Concrete Ceiling		Non Suspect ACM	30	SF	X	SF				N/A	N/A	N/A	
1	4	Penthouse Tank Room Entrance across fromfice 401	N/A	Metal Stairs		Non Suspect ACM	1	EA	X	EA				N/A	N/A	N/A	
1	4	Restroom adjacent to Classroom 409	N/A	Cement Floor		Non Suspect ACM	132	SF	0	SF				N/A	N/A	N/A	
1	4	Restroom adjacent to Classroom 409	N/A	Plaster Ceiling		NAD	132	SF	0	SF				N/A	N/A	N/A	
1	4	Restroom adjacent to Classroom 409	N/A	Ceramic Tile Walls		Non Suspect ACM	200	SF	0	SF				N/A	N/A	N/A	

8120 Woodrow Wilson MS 2015 2016 AHERA Three-Year Report.xls

		School District of Philadelphia Woodrow Wilson Middle School 1800 Cottman Ave, Philadelphia, PA 19111 ULCS# 8120 Year Built: 1928	AHERA Three-Year Reinspection 2015-2016 Room by Room Location Log Report										Reinspection Date: December 3, 2015 Building Inspector: Norman Harrison Number: 037951 Management Planner: Megan Vala Number: 740728						
E l e m e n t	F l o o r	On Site Room Name	System Affected	Material Description	HID#	Confirmed/Assumed/NAD/ Non Suspect ACM	Amount of Material	SF LF EA	Amount of Damage	SF LF EA	Color required for VAT	Comments/Description/Notes	Attic/ Crawl Space Ranking	Damage Potential (DP)	Newly Friable (NF)	Response Action (RA)			
1	4	Restroom adjacent to Classroom 409	N/A	Brick Wall		Non Suspect ACM	200	SF	0	SF				N/A	N/A	N/A			
1	4	Restroom adjacent to Classroom 409	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	10	LF	0	LF				N/A	N/A	N/A			
1	4	Pipe Chase - Restroom adjacent to Classroom 409	N/A	Cement Floor		Non Suspect ACM	60	SF	X	SF		Pipe Chase Access is in the Penthouse Tank Room Entrance across from Office 401		N/A	N/A	N/A			
1	4	Pipe Chase - Restroom adjacent to Classroom 409	N/A	Concrete Block Wall		Non Suspect ACM	180	SF	X	SF				N/A	N/A	N/A			
1	4	Pipe Chase - Restroom adjacent to Classroom 409	N/A	Concrete Ceiling		Non Suspect ACM	60	SF	X	SF				N/A	N/A	N/A			
1	4	Pipe Chase - Restroom adjacent to Classroom 409	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	25	LF	X	LF				N/A	N/A	N/A			
1	4	Pipe Chase - Restroom adjacent to Classroom 409	T	Pipe Fitting Insulation	8120/01/04/68	Confirmed	4	EA	0	EA		Associated with FGPI Main Attic Entrance		1	No	1/D			
1	4	North Storage Room adjacent to Main Attic	M	Floor Tile VAT 9" x 9"	8120/01/04/65	Confirmed	100	SF	0	SF	White			1	No	1/D			
1	4	North Storage Room adjacent to Main Attic	N/A	Ceiling Tile 2' x 4'		Non Suspect ACM	100	SF	0	SF				N/A	N/A	N/A			
1	4	North Storage Room adjacent to Main Attic	N/A	Sheetrock Wall		Non Suspect ACM	300	SF	0	SF				N/A	N/A	N/A			
												Main Attic Entrance							
1	4	South Storage Room adjacent to Main Attic	M	Floor Tile VAT 9" x 9"	8120/01/04/65	Confirmed	100	SF	0	SF				1	No	1/D			
1	4	South Storage Room adjacent to Main Attic	N/A	Sheetrock Wall		Non Suspect ACM	300	SF	X	SF				N/A	N/A	N/A			
1	4	South Storage Room adjacent to Main Attic	N/A	Ceiling Tile 1' x 1'		NAD	100	SF	X	SF				N/A	N/A	N/A			
1	4	South Storage Room adjacent to Main Attic	T	Pipe Insulation > 6 inch	8120/01/04/69	Confirmed	10	LF	0	LF		Above the suspended 1' x 1' Ceiling Tiles		1	No	1/D			
1	4	Classroom 409 (Music Studio)	M	Floor Tile VAT 9" x 9"	8120/01/04/65	Confirmed	70	SF	0	SF	Blue			1	No	1/D			
1	4	Classroom 409 (Music Studio)	N/A	Ceiling Tile 1' x 1'		NAD	70	SF	0	SF				N/A	N/A	N/A			
1	4	Classroom 409 (Music Studio)	N/A	Plaster Walls		NAD	100	SF	0	SF				N/A	N/A	N/A			
1	4	Classroom 409 (Music Studio)	M	Blackboard Glue Dots	8120/01/04/SYN/BB/2600	Assumed	40	SF	0	SF		Assumed Present behind Blackboards/Tackboards		1	No	1/D			
1	4	City Year Team Leader Office	M	Floor Tile VAT 9" x 9"	8120/01/04/65	Confirmed	70	SF	0	SF	Blue			1	No	1/D			
1	4	City Year Team Leader Office	N/A	Ceiling Tile 1' x 1'		NAD	70	SF	0	SF				N/A	N/A	N/A			
1	4	City Year Team Leader Office	N/A	Plaster Walls		NAD	100	SF	0	SF				N/A	N/A	N/A			
1	4	Classroom 407 (Music Practice)	M	Floor Tile VAT 9" x 9"	8120/01/04/65	Confirmed	70	SF	0	SF	Blue			1	No	1/D			
1	4	Classroom 407 (Music Practice)	N/A	Ceiling Tile 1' x 1'		NAD	70	SF	0	SF				N/A	N/A	N/A			
1	4	Classroom 407 (Music Practice)	N/A	Plaster Walls		NAD	100	SF	0	SF				N/A	N/A	N/A			
1	4	Storage Room adjacent to Room 407	M	Floor Tile VAT 9" x 9"	8120/01/04/65	Confirmed	70	SF	0	SF	Blue			1	No	1/D			
1	4	Storage Room adjacent to Room 407	N/A	Ceiling Tile 1' x 1'		NAD	70	SF	0	SF				N/A	N/A	N/A			
1	4	Storage Room adjacent to Room 407	N/A	Plaster Walls		NAD	100	SF	0	SF				N/A	N/A	N/A			
1	4	Classroom 404 (Music)	M	Floor Tile VAT 9" x 9"	8120/01/04/65	Confirmed	1628	SF	0	SF	Brown			1	No	1/D			
												Approximately 20 water stained ceiling tiles; No roof leak reported							
1	4	Classroom 404 (Music)	N/A	Ceiling Tile 1' x 1'		NAD	1628	SF	0	SF				N/A	N/A	N/A			
1	4	Classroom 404 (Music)	N/A	Plaster Walls		NAD	2000	SF	0	SF				N/A	N/A	N/A			
1	4	Classroom 404 (Music)	M	Blackboard Glue Dots	8120/01/04/SYN/BB/2600	Assumed	100	SF	0	SF		Assumed Present behind Blackboards/Tackboards		1	No	1/D			
1	4	Classroom 403 (Music)	M	Floor Tile VAT 9" x 9"	8120/01/04/65	Confirmed	980	SF	0	SF	Brown			1	No	1/D			
												Approximately 20 water stained ceiling tiles; staff reports an active roof leak							
1	4	Classroom 403 (Music)	N/A	Ceiling Tile 1' x 1'		NAD	980	SF	0	SF				N/A	N/A	N/A			
1	4	Classroom 403 (Music)	N/A	Plaster Walls		NAD	1200	SF	0	SF				N/A	N/A	N/A			
1	4	Classroom 403 (Music)	M	Blackboard Glue Dots	8120/01/04/SYN/BB/2600	Assumed	250	SF	0	SF		Assumed Present behind Blackboards/Tackboards		1	No	1/D			
1	4	Classroom 402 (Music)	M	Floor Tile VAT 9" x 9"	8120/01/04/65	Confirmed	1628	SF	0	SF	Brown			1	No	1/D			
1	4	Classroom 402 (Music)	N/A	Ceiling Tile 1' x 1'		NAD	1628	SF	0	SF				N/A	N/A	N/A			
1	4	Classroom 402 (Music)	N/A	Plaster Walls		NAD	2000	SF	0	SF				N/A	N/A	N/A			
1	4	Classroom 402 (Music)	M	Blackboard Glue Dots	8120/01/04/SYN/BB/2600	Assumed	100	SF	0	SF		Assumed Present behind Blackboards/Tackboards		1	No	1/D			
1	4	Classroom 402 (Music)	M	Sink Undercoat Mastic	8120/01/04/SYN/BB/2602	Assumed	6	SF	0	SF		1 Sink		1	No	1/D			
1	4	Office 401 City Year	M	Floor Tile VAT 9" x 9"	8120/01/04/65	Confirmed	340	SF	0	SF	White			1	No	1/D			
1	4	Office 401 City Year	N/A	Ceiling Tile 1' x 1'		NAD	340	SF	0	SF				N/A	N/A	N/A			
1	4	Office 401 City Year	N/A	Brick Wall		Non Suspect ACM	200	SF	0	SF				N/A	N/A	N/A			
1	4	Office 401 City Year	N/A	Plaster Walls		NAD	800	SF	0	SF				N/A	N/A	N/A			
1	4	Hallway from Classrooms 403 to 409	M	Floor Tile VAT 9" x 9"	8120/01/04/65	Confirmed	540	SF	0	SF	Brown			1	No	1/D			
1	4	Hallway from Classrooms 403 to 409	N/A	Ceiling Tile 1' x 1'		NAD	540	SF	0	SF		1 missing ceiling tile; staff reports an active roof leak		N/A	N/A	N/A			
1	4	Hallway from Classrooms 403 to 409	N/A	Plaster Walls		NAD	1000	SF	0	SF				N/A	N/A	N/A			
1	4	Hallway from Classrooms 403 to 409	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	101	LF	0	LF				N/A	N/A	N/A			
1	4	Hallway from Classrooms 410 to 415	M	Floor Tile VAT 9" x 9"	8120/01/04/65	Confirmed	258	SF	0	SF	Brown			1	No	1/D			
1	4	Hallway from Classrooms 410 to 415	N/A	Ceiling Tile 1' x 1'		NAD	258	SF	0	SF				N/A	N/A	N/A			
1	4	Hallway from Classrooms 410 to 415	N/A	Plaster Walls		NAD	600	SF	0	SF				N/A	N/A	N/A			
1	4	Hallway from Classrooms 410 to 415	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	101	LF	0	LF				N/A	N/A	N/A			
1	4	Hallway from Classrooms 410 to 415	N/A	Fiberglass Pipe Fitting Insulation		Non Suspect ACM	101	EA	0	EA				N/A	N/A	N/A			
1	4	Hallway from Office 401 to Classroom 411	M	Floor Tile VAT 9" x 9"	8120/01/04/65	Confirmed	396	SF	0	SF	Brown			1	No	1/D			
1	4	Hallway from Office 401 to Classroom 411	N/A	Ceiling Tile 1' x 1'		NAD	396	SF	0	SF				N/A	N/A	N/A			
1	4	Hallway from Office 401 to Classroom 411	N/A	Plaster Walls		NAD	1000	SF	0	SF				N/A	N/A	N/A			
1	4	Hallway from Office 401 to Classroom 411	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	101	LF	0	LF				N/A	N/A	N/A			
1	4	Hallway from Office 401 to Classroom 411	N/A	Fiberglass Pipe Fitting Insulation		Non Suspect ACM	101	EA	0	EA				N/A	N/A	N/A			
1	4	Hallway from Office 401 to Classroom 411	N/A	Fiberglass Pipe Fitting Insulation		Non Suspect ACM	101	EA	0	EA				N/A	N/A	N/A			
1	A	Attic above Auditorium	N/A	Plaster Floor (Auditorium Ceiling)		NAD	5,600	SF	X	SF		Attic Entrances are in Storage Rooms 314A, 325, 327 and 328	B	N/A	N/A	N/A			
1	A	Attic above Auditorium	N/A	Wood Catwalks		Non Suspect ACM	400	SF	X	SF			B	N/A	N/A	N/A			
1	A	Attic above Auditorium	N/A	Brick Wall		Non Suspect ACM	5,600	SF	X	SF		Black mastic damp-proofing applied to brick walls is assumed asbestos containing	B	X	X	X			
1	A	Attic above Auditorium	N/A	Black Mastic Damp Proofing	8120/01/0A/SYN/BB/2624	Assumed	5,600	SF	X	SF		Applied to brick walls	B	N/A	N/A	N/A			
1	3	Classroom 301	N/A	Concrete Ceiling		Non Suspect ACM	5,600	SF	X	SF		No TSI in Auditorium Attic	B	N/A	N/A	N/A			
1	3	Classroom 301	N/A	Wood Floor		Non Suspect ACM	768	SF	0	SF				N/A	N/A	N/A			
1	3	Classroom 301	N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	768	SF	0	SF				N/A	N/A	N/A			
1	3	Classroom 301	T	Pipe Insulation 2-6 inch	8120/01/03/57	Confirmed	25	LF	0	LF				1	No	1/D			

8120 Woodrow Wilson MS 2015 2016 AHERA Three-Year Report.xls

		School District of Philadelphia Woodrow Wilson Middle School 1800 Cottman Ave, Philadelphia, PA 19111 ULCS# 8120 Year Built: 1928		AHERA Three-Year Reinspection 2015-2016 Room by Room Location Log Report							Reinspection Date: December 3, 2015 Building Inspector: Norman Harrison Number: 037951 Management Planner: Megan Vala Number: 740728					
E l e m e n t	F l o o r	On Site Room Name	System Affected	Material Description	HID#	Confirmed/Assumed/NAD/ Non Suspect ACM	Amount of Material	SF LF EA	Amount of Damage	SF LF EA	Color required for VAT	Comments/Description/Notes	Attic/ Crawl Space Ranking	Damage Potential (DP)	Newly Friable (NF)	Response Action (RA)
1	3	Classroom 301	M	Blackboard Glue Dots	8120/01/03/SYN/BB/2600	Assumed	100	SF	0	SF		Assumed Present behind Blackboards/Tackboards		1	No	1/D
1	3	Classroom 301	N/A	Wood Wall Partition Room Dividers		Non Suspect ACM	200	SF	0	SF				N/A	N/A	N/A
1	3	Classroom 301	N/A	Plaster Walls		NAD	1200	SF	0	SF				N/A	N/A	N/A
1	3	Classroom 302	N/A	Wood Floor		Non Suspect ACM	720	SF	0	SF				N/A	N/A	N/A
1	3	Classroom 302	N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	720	SF	0	SF				N/A	N/A	N/A
1	3	Classroom 302	T	Pipe Insulation 2-6 inch	8120/01/03/57	Confirmed	25	LF	0	LF				1	No	1/D
1	3	Classroom 302	M	Blackboard Glue Dots	8120/01/03/SYN/BB/2600	Assumed	100	SF	0	SF		Assumed Present behind Blackboards/Tackboards		1	No	1/D
1	3	Classroom 302	N/A	Wood Wall Partition Room Dividers		Non Suspect ACM	200	SF	0	SF				N/A	N/A	N/A
1	3	Classroom 302	N/A	Plaster Walls		NAD	1200	SF	0	SF				N/A	N/A	N/A
1	3	Boy's Restroom across from Classroom 302	N/A	Cement Floor		Non Suspect ACM	297	SF	0	SF				N/A	N/A	N/A
1	3	Boy's Restroom across from Classroom 302	N/A	Plaster Ceiling		NAD	297	SF	0	SF				N/A	N/A	N/A
1	3	Boy's Restroom across from Classroom 302	N/A	Plaster Walls		NAD	500	SF	0	SF				N/A	N/A	N/A
1	3	Boy's Restroom across from Classroom 302	N/A	Fiberglass Pipe Fitting Insulation		Non Suspect ACM	5	LF	0	LF				N/A	N/A	N/A
1	3	Boy's Restroom across from Classroom 302	N/A	Ceramic Tile Walls		Non Suspect ACM	400	SF	0	SF				N/A	N/A	N/A
1	3	Custodial Closet next to Boy's Restroom across from Classroom 302	N/A	Cement Floor		Non Suspect ACM	25	SF	X	SF				N/A	N/A	N/A
1	3	Custodial Closet next to Boy's Restroom across from Classroom 302	N/A	Plaster Walls		NAD	70	SF	X	SF				N/A	N/A	N/A
1	3	Custodial Closet next to Boy's Restroom across from Classroom 302	N/A	Plaster Ceiling		NAD	25	SF	X	SF				N/A	N/A	N/A
1	3	Custodial Closet next to Boy's Restroom across from Classroom 302	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	60	LF	X	LF				N/A	N/A	N/A
1	3	Custodial Closet next to Boy's Restroom across from Classroom 302	T	Pipe Fitting Insulation	8120/01/03/61	Confirmed	6	EA	0	EA				1	No	1/D
1	3	Pipe Chase - Boy's Restroom across from Classroom 302	N/A	Cement Floor		Non Suspect ACM	60	SF	X	SF		Pipe Chase Access is in the Janitor's Closet beside the Boy's Restroom across from Classroom 302		N/A	N/A	N/A
1	3	Pipe Chase - Boy's Restroom across from Classroom 302	N/A	Concrete Block Wall		Non Suspect ACM	180	SF	X	SF				N/A	N/A	N/A
1	3	Pipe Chase - Boy's Restroom across from Classroom 302	N/A	Concrete Ceiling		Non Suspect ACM	60	SF	X	SF				N/A	N/A	N/A
1	3	Pipe Chase - Boy's Restroom across from Classroom 302	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	25	LF	X	LF				N/A	N/A	N/A
1	3	Pipe Chase - Boy's Restroom across from Classroom 302	M	Transite Sills	8120/01/03/62	Assumed	10	SF	0	SF		Transite Shelf inside Pipe Chase		1	No	1/D
1	3	Classroom 303	N/A	Wood Floor		Non Suspect ACM	768	SF	0	SF				N/A	N/A	N/A
1	3	Classroom 303	N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	768	SF	0	SF				N/A	N/A	N/A
1	3	Classroom 303	T	Pipe Insulation 2-6 inch	8120/01/03/57	Confirmed	25	LF	0	LF				1	No	1/D
1	3	Classroom 303	M	Blackboard Glue Dots	8120/01/03/SYN/BB/2600	Assumed	100	SF	0	SF		Assumed Present behind Blackboards/Tackboards		1	No	1/D
1	3	Classroom 303	N/A	Wood Wall Partition Room Dividers		Non Suspect ACM	100	SF	0	SF				N/A	N/A	N/A
1	3	Classroom 303	N/A	Plaster Walls		NAD	1200	SF	0	SF				N/A	N/A	N/A
1	3	Classroom 304	N/A	Wood Floor		Non Suspect ACM	768	SF	0	SF				N/A	N/A	N/A
1	3	Classroom 304	N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	768	SF	0	SF				N/A	N/A	N/A
1	3	Classroom 304	T	Pipe Insulation 2-6 inch	8120/01/03/57	Confirmed	25	LF	0	LF				1	No	1/D
1	3	Classroom 304	M	Blackboard Glue Dots	8120/01/03/SYN/BB/2600	Assumed	200	SF	0	SF		Assumed Present behind Blackboards/Tackboards		1	No	1/D
1	3	Classroom 304	N/A	Plaster Walls		NAD	1200	SF	0	SF				N/A	N/A	N/A
1	3	Classroom 305	N/A	Wood Floor		Non Suspect ACM	1008	SF	0	SF				N/A	N/A	N/A
1	3	Classroom 305	N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	1008	SF	0	SF				N/A	N/A	N/A
1	3	Classroom 305	T	Pipe Insulation 2-6 inch	8120/01/03/57	Confirmed	25	LF	0	LF				1	No	1/D
1	3	Classroom 305	M	Blackboard Glue Dots	8120/01/03/SYN/BB/2600	Assumed	200	SF	0	SF		Assumed Present behind Blackboards/Tackboards		1	No	1/D
1	3	Classroom 305	N/A	Plaster Walls		NAD	1500	SF	0	SF				N/A	N/A	N/A
1	3	Classroom 305	T	Pipe Insulation 2-6 inch	8120/01/03/57	Confirmed	25	LF	0	LF				1	No	1/D
1	3	Classroom 305	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	25	LF	0	LF				N/A	N/A	N/A
1	3	Classroom 305	T	Pipe Fitting Insulation	8120/01/03/61	Confirmed	6	EA	0	EA				1	No	1/D
1	3	Classroom 306	N/A	Wood Floor		Non Suspect ACM	816	SF	0	SF				N/A	N/A	N/A
1	3	Classroom 306	N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	816	SF	0	SF				N/A	N/A	N/A
1	3	Classroom 306	T	Pipe Insulation 2-6 inch	8120/01/03/57	Confirmed	25	LF	0	LF				1	No	1/D
1	3	Classroom 306	M	Blackboard Glue Dots	8120/01/03/SYN/BB/2600	Assumed	200	SF	0	SF		Assumed Present behind Blackboards/Tackboards		1	No	1/D
1	3	Classroom 306	N/A	Plaster Walls		NAD	1400	SF	0	SF				N/A	N/A	N/A
1	3	Classroom 307	N/A	Wood Floor		Non Suspect ACM	1089	SF	0	SF				N/A	N/A	N/A
1	3	Classroom 307	N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	1089	SF	0	SF				N/A	N/A	N/A
1	3	Classroom 307	T	Pipe Insulation 2-6 inch	8120/01/03/57	Confirmed	36	LF	0	LF				1	No	1/D
1	3	Classroom 307	M	Blackboard Glue Dots	8120/01/03/SYN/BB/2600	Assumed	200	SF	0	SF		Assumed Present behind Blackboards/Tackboards		1	No	1/D
1	3	Classroom 307	N/A	Plaster Walls		NAD	2000	SF	0	SF				N/A	N/A	N/A
1	3	Classroom 307	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	20	LF	0	LF				N/A	N/A	N/A
1	3	Classroom 308	N/A	Wood Floor		Non Suspect ACM	924	SF	0	SF				N/A	N/A	N/A
1	3	Classroom 308	N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	924	SF	0	SF				N/A	N/A	N/A
1	3	Classroom 308	T	Pipe Insulation 2-6 inch	8120/01/03/57	Confirmed	60	LF	0	LF				1	No	1/D
1	3	Classroom 308	M	Blackboard Glue Dots	8120/01/03/SYN/BB/2600	Assumed	200	SF	0	SF		Assumed Present behind Blackboards/Tackboards		1	No	1/D
1	3	Classroom 308	N/A	Plaster Walls		NAD	1200	SF	0	SF				N/A	N/A	N/A
1	3	Classroom 308	N/A	Wood Floor		Non Suspect ACM	768	SF	0	SF				N/A	N/A	N/A
1	3	Classroom 309	N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	768	SF	0	SF				N/A	N/A	N/A
1	3	Classroom 309	T	Pipe Insulation 2-6 inch	8120/01/03/57	Confirmed	25	LF	0	LF				1	No	1/D
1	3	Classroom 309	M	Blackboard Glue Dots	8120/01/03/SYN/BB/2600	Assumed	200	SF	0	SF		Assumed Present behind Blackboards/Tackboards		1	No	1/D

8120 Woodrow Wilson MS 2015 2016 AHERA Three-Year Report.xls

		School District of Philadelphia Woodrow Wilson Middle School 1800 Cottman Ave, Philadelphia, PA 19111 ULCS# 8120 Year Built: 1928		AHERA Three-Year Reinspection 2015-2016 Room by Room Location Log Report							Reinspection Date: December 3, 2015 Building Inspector: Norman Harrison Number: 037951 Management Planner: Megan Vala Number: 740728					
E l e m e n t	F l o o r	On Site Room Name	System Affected	Material Description	HID#	Confirmed/Assumed/NAD/ Non Suspect ACM	Amount of Material	SF LF EA	Amount of Damage	SF LF EA	Color required for VAT	Comments/Description/Notes	Attic/ Crawl Space Ranking	Damage Potential (DP)	Newly Friable (NF)	Response Action (RA)
1	3	Classroom 309	N/A	Plaster Walls		NAD	1200	SF	0	SF				N/A	N/A	N/A
1	3	Lab Prep Room between Classrooms 309 and 310	N/A	Wood Floor		Non Suspect ACM	180	SF	X	SF				N/A	N/A	N/A
1	3	Lab Prep Room between Classrooms 309 and 310	N/A	Plaster Walls		NAD	540	SF	X	SF				N/A	N/A	N/A
1	3	Lab Prep Room between Classrooms 309 and 310	N/A	Ceiling Tile 2' x 4'		Non Suspect ACM	180	SF	X	SF				N/A	N/A	N/A
1	3	Lab Prep Room between Classrooms 309 and 310	T	Pipe Insulation 2-6 inch	8120/01/03/57	Confirmed	12	LF	0	LF				1	No	1/D
1	3	Lab Prep Room between Classrooms 309 and 310	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	20	LF	X	LF				N/A	N/A	N/A
1	3	Lab Prep Room between Classrooms 309 and 310	M	Transite Sink	8120/01/03/SYN/BB/2340	Assumed	6	SF	0	SF		Associated with Wood Lab Table Top		1	No	1/D
1	3	Chemical Storage Closet inside Lab Prep Room between Classrooms 309 and 310	N/A	Cement Floor		Non Suspect ACM	32	SF	X	SF				N/A	N/A	N/A
1	3	Chemical Storage Closet inside Lab Prep Room between Classrooms 309 and 310	N/A	Plaster Walls		NAD	90	SF	X	SF				N/A	N/A	N/A
1	3	Chemical Storage Closet inside Lab Prep Room between Classrooms 309 and 310	N/A	Plaster Ceiling		NAD	32	SF	X	SF				N/A	N/A	N/A
1	3	Chemical Storage Closet inside Lab Prep Room between Classrooms 309 and 310	N/A	Metal Shelves		Non Suspect ACM	20	SF	X	SF		No TSI identified		N/A	N/A	N/A
1	3	Storage Closet inside Lab Prep Room between Classrooms 309 and 310	N/A	Wood Floor		Non Suspect ACM	32	SF	X	SF				N/A	N/A	N/A
1	3	Storage Closet inside Lab Prep Room between Classrooms 309 and 310	N/A	Plaster Walls		NAD	90	SF	X	SF				N/A	N/A	N/A
1	3	Storage Closet inside Lab Prep Room between Classrooms 309 and 310	N/A	Plaster Ceiling		NAD	32	SF	X	SF				N/A	N/A	N/A
1	3	Classroom 310	N/A	Wood Floor		Non Suspect ACM	960	SF	0	SF				N/A	N/A	N/A
1	3	Classroom 310	N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	960	SF	0	SF				N/A	N/A	N/A
1	3	Classroom 310	T	Pipe Insulation 2-6 inch	8120/01/03/57	Confirmed	36	LF	0	LF				1	No	1/D
1	3	Classroom 310	M	Blackboard Glue Dots	8120/01/03/SYN/BB/2600	Assumed	200	SF	0	SF		Assumed Present behind Blackboards/Tackboards		1	No	1/D
1	3	Classroom 310	N/A	Plaster Walls		NAD	1200	SF	0	SF				N/A	N/A	N/A
1	3	Classroom 311	N/A	Wood Floor		Non Suspect ACM	902	SF	0	SF				N/A	N/A	N/A
1	3	Classroom 311	N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	902	SF	0	SF				N/A	N/A	N/A
1	3	Classroom 311	T	Pipe Insulation 2-6 inch	8120/01/03/57	Confirmed	12	LF	0	LF				1	No	1/D
1	3	Classroom 311	M	Blackboard Glue Dots	8120/01/03/SYN/BB/2600	Assumed	200	SF	0	SF		Assumed Present behind Blackboards/Tackboards		1	No	1/D
1	3	Classroom 311	N/A	Plaster Walls		NAD	1200	SF	0	SF				N/A	N/A	N/A
1	3	Classroom 312	N/A	Wood Floor		Non Suspect ACM	768	SF	0	SF				N/A	N/A	N/A
1	3	Classroom 312	N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	768	SF	0	SF				N/A	N/A	N/A
1	3	Classroom 312	T	Pipe Insulation 2-6 inch	8120/01/03/57	Confirmed	25	LF	0	LF				1	No	1/D
1	3	Classroom 312	M	Blackboard Glue Dots	8120/01/03/SYN/BB/2600	Assumed	200	SF	0	SF		Assumed Present behind Blackboards/Tackboards		1	No	1/D
1	3	Classroom 312	N/A	Plaster Walls		NAD	1200	SF	0	SF				N/A	N/A	N/A
1	3	Classroom 313	N/A	Wood Floor		Non Suspect ACM	700	SF	0	SF				N/A	N/A	N/A
1	3	Classroom 313	N/A	Plaster Walls		NAD	2100	SF	0	SF				N/A	N/A	N/A
1	3	Classroom 313	N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	700	SF	0	SF				N/A	N/A	N/A
1	3	Classroom 313	T	Pipe Insulation 2-6 inch	8120/01/03/57	Confirmed	24	LF	0	LF				1	No	1/D
1	3	Classroom 314	N/A	Wood Floor		Non Suspect ACM	700	SF	0	SF				N/A	N/A	N/A
1	3	Classroom 314	N/A	Plaster Walls		NAD	2100	SF	0	SF				N/A	N/A	N/A
1	3	Classroom 314	T	Pipe Insulation 2-6 inch		Non Suspect ACM	700	SF	0	SF				N/A	N/A	N/A
1	3	Classroom 314	T	Pipe Insulation 2-6 inch	8120/01/03/57	Confirmed	24	LF	0	LF				1	No	1/D
1	3	Classroom 314	M	Blackboard Glue Dots	8120/01/03/SYN/BB/2600	Assumed	200	SF	0	SF		Assumed Present behind Blackboards/Tackboards		1	No	1/D
1	3	Girl's Restroom across from Classroom 314	N/A	Cement Floor		Non Suspect ACM	165	SF	0	SF				N/A	N/A	N/A
1	3	Girl's Restroom across from Classroom 314	N/A	Plaster Ceiling		NAD	165	SF	0	SF				N/A	N/A	N/A
1	3	Girl's Restroom across from Classroom 314	N/A	Plaster Walls		NAD	400	SF	0	SF				N/A	N/A	N/A
1	3	Girl's Restroom across from Classroom 314	N/A	Fiberglass Pipe Fitting Insulation		Non Suspect ACM	5	LF	0	LF				N/A	N/A	N/A
1	3	Girl's Restroom across from Classroom 314	N/A	Ceramic Tile Walls		Non Suspect ACM	400	SF	0	SF				N/A	N/A	N/A
1	3	Custodial Closet next to Girl's Restroom across from Classroom 314	N/A	Cement Floor		Non Suspect ACM	25	SF	X	SF				N/A	N/A	N/A
1	3	Custodial Closet next to Girl's Restroom across from Classroom 314	N/A	Plaster Walls		NAD	70	SF	X	SF				N/A	N/A	N/A
1	3	Custodial Closet next to Girl's Restroom across from Classroom 314	N/A	Plaster Ceiling		NAD	25	SF	X	SF				N/A	N/A	N/A
1	3	Custodial Closet next to Girl's Restroom across from Classroom 314	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	60	LF	X	LF				N/A	N/A	N/A
1	3	Custodial Closet next to Girl's Restroom across from Classroom 314	T	Pipe Fitting Insulation	8120/01/03/61	Confirmed	4	EA	0	EA				1	No	1/D
1	3	Pipe Chase - Girl's Restroom across from Classroom 314	N/A	Cement Floor		Non Suspect ACM	60	SF	X	SF		Pipe Chase Access is in the Janitor's Closet beside the Girl's Restroom across from Classroom 314		N/A	N/A	N/A
1	3	Pipe Chase - Girl's Restroom across from Classroom 314	N/A	Concrete Block Wall		Non Suspect ACM	180	SF	X	SF				N/A	N/A	N/A
1	3	Pipe Chase - Girl's Restroom across from Classroom 314	N/A	Concrete Ceiling		Non Suspect ACM	60	SF	X	SF				N/A	N/A	N/A
1	3	Pipe Chase - Girl's Restroom across from Classroom 314	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	25	LF	X	LF				N/A	N/A	N/A
1	3	Pipe Chase - Girl's Restroom across from Classroom 314	M	Transite Sills	8120/01/03/62	Assumed	10	SF	0	SF		Transite Shelf inside Pipe Chase		1	No	1/D
1	3	Classroom 315	N/A	Wood Floor		Non Suspect ACM	638	SF	0	SF				N/A	N/A	N/A
1	3	Classroom 315	N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	638	SF	0	SF				N/A	N/A	N/A
1	3	Classroom 315	T	Pipe Insulation 2-6 inch	8120/01/03/57	Confirmed	12	LF	0	LF				1	No	1/D
1	3	Classroom 315	M	Blackboard Glue Dots	8120/01/03/SYN/BB/2600	Assumed	200	SF	0	SF		Assumed Present behind Blackboards/Tackboards		1	No	1/D
1	3	Classroom 315	N/A	Plaster Walls		NAD	1200	SF	0	SF				N/A	N/A	N/A
1	3	Women's Lounge	N/A	Wood Floor		Non Suspect ACM	192	SF	0	SF				N/A	N/A	N/A

8120 Woodrow Wilson MS 2015 2016 AHERA Three-Year Report.xls

		School District of Philadelphia Woodrow Wilson Middle School 1800 Cottman Ave, Philadelphia, PA 19111 ULCS# 8120 Year Built: 1928		AHERA Three-Year Reinspection 2015-2016 Room by Room Location Log Report							Reinspection Date: December 3, 2015 Building Inspector: Norman Harrison Number: 037951 Management Planner: Megan Vala Number: 740728						
E l e m e n t	F l o o r	On Site Room Name		System Affected	Material Description	HID#	Confirmed/Assumed/NAD/ Non Suspect ACM	Amount of Material	SF LF EA	Amount of Damage	SF LF EA	Color required for VAT	Comments/Description/Notes	Attic/ Crawl Space Ranking	Damage Potential (DP)	Newly Friable (NF)	Response Action (RA)
1	3	Women's Lounge		N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	192	SF	0	SF				N/A	N/A	N/A
1	3	Women's Lounge		N/A	Plaster Walls		NAD	300	SF	0	SF				N/A	N/A	N/A
1	3	Women's Lounge		T	Pipe Insulation 2-6 inch	8120/01/03/57	Confirmed	12	LF	0	LF				1	No	1/D
1	3	Women's Lounge		M	Sink Undercoat Mastic	8120/01/03/SYN/BB/2602	Assumed	6	SF	0	SF		1 Sink		1	No	1/D
1	3	Women's Restroom		M	Floor Tile VAT 12" x 12"	8120/01/03/KK	Assumed	65	SF	0	SF	Tan			1	No	1/D
1	3	Women's Restroom		N/A	Plaster Ceiling		NAD	65	SF	10	SF		Loose/Flaking Paint		N/A	N/A	N/A
1	3	Women's Restroom		N/A	Plaster Walls		NAD	100	SF	10	SF		Loose/Flaking Paint		N/A	N/A	N/A
1	3	Classroom 316		N/A	Wood Floor		Non Suspect ACM	902	SF	0	SF				N/A	N/A	N/A
1	3	Classroom 316		T	Pipe Insulation 2-6 inch	8120/01/03/57	Confirmed	25	LF	0	LF				1	No	1/D
1	3	Classroom 316		N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	902	SF	0	SF				N/A	N/A	N/A
1	3	Classroom 316		M	Blackboard Glue Dots	8120/01/03/SYN/BB/2600	Assumed	200	SF	0	SF		Assumed Present behind Blackboards/Tackboards		1	No	1/D
1	3	Classroom 316		N/A	Plaster Walls		NAD	1200	SF	0	SF				N/A	N/A	N/A
1	3	Classroom 317		N/A	Wood Floor		Non Suspect ACM	768	SF	0	SF				N/A	N/A	N/A
1	3	Classroom 317		N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	768	SF	0	SF				N/A	N/A	N/A
1	3	Classroom 317		T	Pipe Insulation 2-6 inch	8120/01/03/57	Confirmed	12	LF	0	LF				1	No	1/D
1	3	Classroom 317		M	Blackboard Glue Dots	8120/01/03/SYN/BB/2600	Assumed	200	SF	0	SF		Assumed Present behind Blackboards/Tackboards		1	No	1/D
1	3	Classroom 317		N/A	Plaster Walls		NAD	1200	SF	0	SF				N/A	N/A	N/A
1	3	Classroom 318		N/A	Wood Floor		Non Suspect ACM	744	SF	0	SF				N/A	N/A	N/A
1	3	Classroom 318		N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	744	SF	0	SF				N/A	N/A	N/A
1	3	Classroom 318		T	Pipe Insulation 2-6 inch	8120/01/03/57	Confirmed	25	LF	0	LF				1	No	1/D
1	3	Classroom 318		M	Blackboard Glue Dots	8120/01/03/SYN/BB/2600	Assumed	200	SF	0	SF		Assumed Present behind Blackboards/Tackboards		1	No	1/D
1	3	Classroom 318		N/A	Plaster Walls		NAD	1200	SF	0	SF				N/A	N/A	N/A
1	3	Classroom 319		N/A	Wood Floor		Non Suspect ACM	768	SF	0	SF				N/A	N/A	N/A
1	3	Classroom 319		N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	768	SF	0	SF				N/A	N/A	N/A
1	3	Classroom 319		T	Pipe Insulation 2-6 inch	8120/01/03/57	Confirmed	25	LF	0	LF				1	No	1/D
1	3	Classroom 319		M	Blackboard Glue Dots	8120/01/03/SYN/BB/2600	Assumed	200	SF	0	SF		Assumed Present behind Blackboards/Tackboards		1	No	1/D
1	3	Classroom 319		N/A	Plaster Walls		NAD	1200	SF	0	SF				N/A	N/A	N/A
1	3	Classroom 320		N/A	Wood Floor		Non Suspect ACM	768	SF	0	SF				N/A	N/A	N/A
1	3	Classroom 320		N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	768	SF	0	SF				N/A	N/A	N/A
1	3	Classroom 320		T	Pipe Insulation 2-6 inch	8120/01/03/57	Confirmed	25	LF	0	LF				1	No	1/D
1	3	Classroom 320		M	Blackboard Glue Dots	8120/01/03/SYN/BB/2600	Assumed	200	SF	0	SF		Assumed Present behind Blackboards/Tackboards		1	No	1/D
1	3	Classroom 320		N/A	Plaster Walls		NAD	1200	SF	0	SF				N/A	N/A	N/A
1	3	Classroom 321		N/A	Wood Floor		Non Suspect ACM	816	SF	0	SF				N/A	N/A	N/A
1	3	Classroom 321		N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	816	SF	0	SF				N/A	N/A	N/A
1	3	Classroom 321		T	Pipe Insulation 2-6 inch	8120/01/03/57	Confirmed	25	LF	0	LF				1	No	1/D
1	3	Classroom 321		M	Blackboard Glue Dots	8120/01/03/SYN/BB/2600	Assumed	200	SF	0	SF		Assumed Present behind Blackboards/Tackboards		1	No	1/D
1	3	Classroom 321		N/A	Plaster Walls		NAD	1200	SF	0	SF				N/A	N/A	N/A
1	3	Classroom 322		N/A	Wood Floor		Non Suspect ACM	660	SF	0	SF				N/A	N/A	N/A
1	3	Classroom 322		N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	660	SF	0	SF				N/A	N/A	N/A
1	3	Classroom 322		T	Pipe Insulation 2-6 inch	8120/01/03/57	Confirmed	25	LF	0	LF				1	No	1/D
1	3	Classroom 322		M	Blackboard Glue Dots	8120/01/03/SYN/BB/2600	Assumed	200	SF	0	SF		Assumed Present behind Blackboards/Tackboards		1	No	1/D
1	3	Classroom 322		N/A	Plaster Walls		NAD	1200	SF	0	SF				N/A	N/A	N/A
1	3	Classroom 323		M	Floor Tile VAT 9" x 9"	8120/01/03/63	Confirmed	720	SF	0	SF	Tan			1	No	1/D
1	3	Classroom 323		N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	720	SF	0	SF				N/A	N/A	N/A
1	3	Classroom 323		T	Pipe Insulation 2-6 inch	8120/01/03/57	Confirmed	25	LF	0	LF				1	No	1/D
1	3	Classroom 323		M	Blackboard Glue Dots	8120/01/03/SYN/BB/2600	Assumed	200	SF	0	SF		Assumed Present behind Blackboards/Tackboards		1	No	1/D
1	3	Classroom 323		N/A	Plaster Walls		NAD	600	SF	0	SF				N/A	N/A	N/A
1	3	Classroom 323		N/A	Ceramic Tile Walls		Non Suspect ACM	600	SF	0	SF				N/A	N/A	N/A
1	3	Men's Lounge		N/A	Wood Floor		Non Suspect ACM	192	SF	0	SF				N/A	N/A	N/A
1	3	Men's Lounge		N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	192	SF	0	SF				N/A	N/A	N/A
1	3	Men's Lounge		N/A	Plaster Walls		NAD	300	SF	0	SF				N/A	N/A	N/A
1	3	Men's Lounge		T	Pipe Insulation 2-6 inch	8120/01/03/57	Confirmed	12	LF	0	LF				1	No	1/D
1	3	Men's Lounge		M	Sink Undercoat Mastic	8120/01/03/SYN/BB/2602	Assumed	6	SF	0	SF		1 Sink		1	No	1/D
1	3	Men's Restroom		M	Floor Tile VAT 12" x 12"	8120/01/03/KK	Assumed	65	SF	0	SF	Tan			1	No	1/D
1	3	Men's Restroom		N/A	Plaster Ceiling		NAD	65	SF	0	SF				N/A	N/A	N/A
1	3	Men's Restroom		N/A	Plaster Walls		NAD	100	SF	0	SF				N/A	N/A	N/A
1	3	Classroom 324A		M	Floor Tile VAT 9" x 9"	8120/01/03/63	Confirmed	720	SF	0	SF	Green			1	No	1/D
1	3	Classroom 324A		N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	720	SF	0	SF				N/A	N/A	N/A
1	3	Classroom 324A		T	Pipe Insulation 2-6 inch	8120/01/03/57	Confirmed	25	LF	0	LF				1	No	1/D
1	3	Classroom 324A		M	Blackboard Glue Dots	8120/01/03/SYN/BB/2600	Assumed	200	SF	0	SF		Assumed Present behind Blackboards/Tackboards		1	No	1/D
1	3	Classroom 324A		N/A	Plaster Walls		NAD	1200	SF	0	SF				N/A	N/A	N/A
1	3	Classroom 324A		N/A	Brick Wall		Non Suspect ACM	192	SF	0	SF				N/A	N/A	N/A
1	3	Boy's Restroom		N/A	Cement Floor		Non Suspect ACM	297	SF	0	SF				N/A	N/A	N/A
1	3	Boy's Restroom		N/A	Plaster Ceiling		NAD	297	SF	0	SF				N/A	N/A	N/A
1	3	Boy's Restroom		N/A	Plaster Walls		NAD	500	SF	0	SF				N/A	N/A	N/A
1	3	Boy's Restroom		N/A	Fiberglass Pipe Fitting Insulation		Non Suspect ACM	5	LF	0	LF				N/A	N/A	N/A
1	3	Boy's Restroom		N/A	Ceramic Tile Walls		Non Suspect ACM	400	SF	0	SF				N/A	N/A	N/A
1	3	Classroom 326		M	Floor Tile VAT 9" x 9"	8120/01/03/63	Confirmed	360	SF	0	SF	Tan			1	No	1/D
1	3	Classroom 326		N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	360	SF	0	SF				N/A	N/A	N/A
1	3	Classroom 326		T	Pipe Insulation 2-6 inch	8120/01/03/57	Confirmed	12	LF	0	LF				1	No	1/D
1	3	Classroom 326		N/A	Brick Wall		Non Suspect ACM	500	SF	0	SF				N/A	N/A	N/A
1	3	Storage Room across from Classroom 318		N/A	Wood Floor		Non Suspect ACM	420	SF	0	SF				N/A	N/A	N/A
1	3	Storage Room across from Classroom 318		N/A	Plaster Ceiling		NAD	420	SF	0	SF				N/A	N/A	N/A
1	3	Storage Room across from Classroom 318		N/A	Plaster Walls		NAD	650	SF	0	SF				N/A	N/A	N/A

8120 Woodrow Wilson MS 2015 2016 AHRA Three-Year Report.xls

School District of Philadelphia			AHERA Three-Year Reinspection 2015-2016 Room by Room Location Log Report										Reinspection Date: December 3, 2015				
Woodrow Wilson Middle School													Building Inspector: Norman Harrison				
1800 Cottman Ave, Philadelphia, PA 19111													Number: 037951				
ULCS# 8120													Management Planner: Megan Vala				
Year Built: 1928													Number: 740728				
E l e m e n t	F l o o r	On Site Room Name	System Affected	Material Description	HID#	Confirmed/Assumed/NAD/ Non Suspect ACM	Amount of Material	SF LF EA	Amount of Damage	SF LF EA	Color required for VAT	Comments/Description/Notes	Attic/ Crawl Space Ranking	Damage Potential (DP)	Newly Friable (NF)	Response Action (RA)	
1	3	Storage Room across from Classroom 318	N/A	Duct Work		Non Suspect ACM	350	SF	0	SF				N/A	N/A	N/A	
1	3	Storage Room across from Classroom 319	N/A	Wood Floor		Non Suspect ACM	420	SF	0	SF				N/A	N/A	N/A	
1	3	Storage Room across from Classroom 319	N/A	Plaster Ceiling		NAD	420	SF	0	SF				N/A	N/A	N/A	
1	3	Storage Room across from Classroom 319	N/A	Plaster Walls		NAD	650	SF	0	SF				N/A	N/A	N/A	
1	3	Storage Room across from Classroom 319	N/A	Duct Work		Non Suspect ACM	350	SF	0	SF				N/A	N/A	N/A	
1	3	Science Storage Room across from Classroom 309	N/A	Wood Floor		Non Suspect ACM	100	SF	X	SF				N/A	N/A	N/A	
1	3	Science Storage Room across from Classroom 309	N/A	Plaster Walls		NAD	300	SF	X	SF				N/A	N/A	N/A	
1	3	Science Storage Room across from Classroom 309	N/A	Plaster Ceiling		NAD	100	SF	X	SF				N/A	N/A	N/A	
1	3	Science Storage Room across from Classroom 306	N/A	Wood Floor		Non Suspect ACM	100	SF	X	SF				N/A	N/A	N/A	
1	3	Science Storage Room across from Classroom 306	N/A	Plaster Walls		NAD	300	SF	X	SF				N/A	N/A	N/A	
1	3	Science Storage Room across from Classroom 306	N/A	Plaster Ceiling		NAD	100	SF	X	SF				N/A	N/A	N/A	
1	3	Storage Room across from Classroom 308	N/A	Cement Floor		Non Suspect ACM	32	SF	X	SF		Storage Room is below stairs to 4th Floor		N/A	N/A	N/A	
1	3	Storage Room across from Classroom 308	N/A	Plaster Walls		NAD	90	SF	X	SF				N/A	N/A	N/A	
1	3	Storage Room across from Classroom 308	N/A	Plaster Ceiling		NAD	32	SF	X	SF				N/A	N/A	N/A	
1	3	Storage Room across from Classroom 307	N/A	Cement Floor		Non Suspect ACM	32	SF	X	SF		Storage Room is below stairs to 4th Floor		N/A	N/A	N/A	
1	3	Storage Room across from Classroom 307	N/A	Plaster Walls		NAD	90	SF	X	SF				N/A	N/A	N/A	
1	3	Storage Room across from Classroom 307	N/A	Plaster Ceiling		NAD	32	SF	X	SF				N/A	N/A	N/A	
1	3	Halfway outside Classrooms 301 - 303	N/A	Cement Floor		Non Suspect ACM	1000	SF	0	SF				N/A	N/A	N/A	
1	3	Halfway outside Classrooms 301 - 303	N/A	Granite Walls		Non Suspect ACM	1500	SF	0	SF		Glue Dots Assumed Present behind Granite Walls		N/A	N/A	N/A	
1	3	Halfway outside Classrooms 301 - 303	N/A	Plaster Walls		NAD	3000	SF	0	SF				N/A	N/A	N/A	
1	3	Halfway outside Classrooms 301 - 303	N/A	Ceiling Tile 2' x 4'		Non Suspect ACM	1000	SF	0	SF				N/A	N/A	N/A	
1	3	Halfway outside Classrooms 304 - 311	N/A	Cement Floor		Non Suspect ACM	3000	SF	0	SF				N/A	N/A	N/A	
1	3	Halfway outside Classrooms 304 - 311	N/A	Granite Walls		Non Suspect ACM	4500	SF	0	SF		Glue Dots Assumed Present behind Granite Walls		N/A	N/A	N/A	
1	3	Halfway outside Classrooms 304 - 311	N/A	Plaster Walls		NAD	9000	SF	0	SF				N/A	N/A	N/A	
1	3	Halfway outside Classrooms 304 - 311	N/A	Ceiling Tile 2' x 4'		Non Suspect ACM	3000	SF	0	SF				N/A	N/A	N/A	
1	3	Halfway outside Classrooms 304 - 311	T	Pipe Insulation 2-6 inch	8120/01/03/57	Confirmed	72	LF	1	LF				2	Yes	5/A	
1	3	Halfway outside Classrooms 312 - 314	N/A	Cement Floor		Non Suspect ACM	1000	SF	0	SF				N/A	N/A	N/A	
1	3	Halfway outside Classrooms 312 - 314	N/A	Granite Walls		Non Suspect ACM	1500	SF	0	SF		Glue Dots Assumed Present behind Granite Walls		N/A	N/A	N/A	
1	3	Halfway outside Classrooms 312 - 314	N/A	Plaster Walls		NAD	3000	SF	0	SF				N/A	N/A	N/A	
1	3	Halfway outside Classrooms 312 - 314	N/A	Ceiling Tile 2' x 4'		Non Suspect ACM	1000	SF	0	SF				N/A	N/A	N/A	
1	3	Halfway outside Classrooms 315 - 322	N/A	Cement Floor		Non Suspect ACM	3000	SF	0	SF				N/A	N/A	N/A	
1	3	Halfway outside Classrooms 315 - 322	N/A	Granite Walls		Non Suspect ACM	4500	SF	0	SF		Glue Dots Assumed Present behind Granite Walls		N/A	N/A	N/A	
1	3	Halfway outside Classrooms 315 - 322	N/A	Plaster Walls		NAD	9000	SF	0	SF				N/A	N/A	N/A	
1	3	Halfway outside Classrooms 315 - 322	N/A	Ceiling Tile 2' x 4'		Non Suspect ACM	3000	SF	0	SF				N/A	N/A	N/A	
1	3	Halfway outside Classrooms 315 - 322	T	Pipe Insulation 2-6 inch	8120/01/03/57	Confirmed	126	LF	1	LF				2	Yes	5/A	
1	3	Stairwell across from Classroom 314	N/A	Cement Floor		Non Suspect ACM	300	SF	0	SF				N/A	N/A	N/A	
1	3	Stairwell across from Classroom 314	N/A	Granite Walls		Non Suspect ACM	450	SF	0	SF		Glue Dots Assumed Present behind Granite Walls		N/A	N/A	N/A	
1	3	Stairwell across from Classroom 314	N/A	Plaster Walls		NAD	900	SF	0	SF				N/A	N/A	N/A	
1	3	Stairwell across from Classroom 314	N/A	Plaster Ceiling		NAD	300	SF	0	SF				N/A	N/A	N/A	
1	3	Stairwell across from Classroom 314	T	Pipe Insulation 2-6 inch	8120/01/03/57	Confirmed	22	LF	1	LF		2nd - 3rd Floor Landing		2	Yes	5/A	
1	3	Stairwell across from Classroom 312	N/A	Cement Floor		Non Suspect ACM	300	SF	0	SF				N/A	N/A	N/A	
1	3	Stairwell across from Classroom 312	N/A	Granite Walls		Non Suspect ACM	450	SF	0	SF		Glue Dots Assumed Present behind Granite Walls		N/A	N/A	N/A	
1	3	Stairwell across from Classroom 312	N/A	Plaster Walls		NAD	900	SF	0	SF				N/A	N/A	N/A	
1	3	Stairwell across from Classroom 312	N/A	Plaster Ceiling		NAD	300	SF	0	SF				N/A	N/A	N/A	
1	3	Stairwell across from Classroom 312	T	Pipe Insulation 2-6 inch	8120/01/03/57	Confirmed	24	LF	1	LF		2nd - 3rd Floor Landing		2	Yes	5/A	
1	3	Stairwell across from Classroom 303	N/A	Cement Floor		Non Suspect ACM	300	SF	0	SF				N/A	N/A	N/A	
1	3	Stairwell across from Classroom 303	N/A	Granite Walls		Non Suspect ACM	450	SF	0	SF		Glue Dots Assumed Present behind Granite Walls		N/A	N/A	N/A	
1	3	Stairwell across from Classroom 303	N/A	Plaster Walls		NAD	900	SF	0	SF				N/A	N/A	N/A	
1	3	Stairwell across from Classroom 303	N/A	Plaster Ceiling		NAD	300	SF	0	SF				N/A	N/A	N/A	
1	3	Stairwell across from Classroom 303	T	Pipe Insulation 2-6 inch	8120/01/03/57	Confirmed	22	LF	1	LF		2nd - 3rd Floor Landing		2	Yes	5/A	
1	3	Stairwell across from Classroom 301	N/A	Cement Floor		Non Suspect ACM	300	SF	0	SF				N/A	N/A	N/A	
1	3	Stairwell across from Classroom 301	N/A	Granite Walls		Non Suspect ACM	450	SF	0	SF		Glue Dots Assumed Present behind Granite Walls		N/A	N/A	N/A	
1	3	Stairwell across from Classroom 301	N/A	Plaster Walls		NAD	900	SF	0	SF				N/A	N/A	N/A	
1	3	Stairwell across from Classroom 301	N/A	Plaster Ceiling		NAD	300	SF	0	SF				N/A	N/A	N/A	
1	3	Stairwell across from Classroom 301	T	Pipe Insulation 2-6 inch	8120/01/03/57	Confirmed	22	LF	0	LF		2nd - 3rd Floor Landing		1	No	1/D	
1	3	Fire Tower Stairwell next to Classroom 321	N/A	Cement Floor		Non Suspect ACM	125	SF	0	SF				N/A	N/A	N/A	
1	3	Fire Tower Stairwell next to Classroom 321	N/A	Brick Wall		Non Suspect ACM	375	SF	0	SF				N/A	N/A	N/A	
1	3	Fire Tower Stairwell next to Classroom 321	N/A	Concrete Ceiling		Non Suspect ACM	125	SF	0	SF				N/A	N/A	N/A	
1	3	Fire Tower Stairwell next to Classroom 316	N/A	Cement Floor		Non Suspect ACM	125	SF	0	SF				N/A	N/A	N/A	
1	3	Fire Tower Stairwell next to Classroom 316	N/A	Brick Wall		Non Suspect ACM	375	SF	0	SF				N/A	N/A	N/A	
1	3	Fire Tower Stairwell next to Classroom 316	N/A	Concrete Ceiling		Non Suspect ACM	125	SF	0	SF				N/A	N/A	N/A	
1	2	Classroom 201	N/A	Wood Floor		Non Suspect ACM	768	SF	0	SF				N/A	N/A	N/A	
1	2	Classroom 201	N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	768	SF	0	SF				N/A	N/A	N/A	
1	2	Classroom 201	T	Pipe Insulation 2-6 inch	8120/01/02/51	Confirmed	25	LF	0	LF				1	No	1/D	
1	2	Classroom 201	M	Blackboard Glue Dots	8120/01/02/SYN/BB/2600	Assumed	200	SF	0	SF		Assumed Present behind Blackboards/Tackboards		1	No	1/D	
1	2	Classroom 201	N/A	Wood Wall Partition Room Dividers		Non Suspect ACM	200	SF	0	SF				N/A	N/A	N/A	
1	2	Classroom 201	N/A	Plaster Walls		NAD	1200	SF	0	SF				N/A	N/A	N/A	
1	2	Men's Lounge	N/A	Wood Floor		Non Suspect ACM	192	SF	0	SF				N/A	N/A	N/A	
1	2	Men's Lounge	N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	192	SF	0	SF				N/A	N/A	N/A	

8120 Woodrow Wilson MS 2015 2016 AHERA Three-Year Report.xls

School District of Philadelphia Woodrow Wilson Middle School 1800 Cottman Ave, Philadelphia, PA 19111 ULCS# 8120 Year Built: 1928			AHERA Three-Year Reinspection 2015-2016 Room by Room Location Log Report										Reinspection Date: December 3, 2015 Building Inspector: Norman Harrison Number: 037951 Management Planner: Megan Vala Number: 740728			
E l e m e n t	F l o o r	On Site Room Name	System Affected	Material Description	HID#	Confirmed/Assumed/NAD/ Non Suspect ACM	Amount of Material	SF LF EA	Amount of Damage	SF LF EA	Color required for VAT	Comments/Description/Notes	Attic/ Crawl Space Ranking	Damage Potential (DP)	Newly Friable (NF)	Response Action (RA)
1	2	Men's Lounge	N/A	Plaster Walls		NAD	300	SF	0	SF				N/A	N/A	N/A
1	2	Men's Lounge	T	Pipe Insulation 2-6 inch	8120/01/02/51	Confirmed	12	LF	0	LF				1	No	1/D
1	2	Men's Lounge	M	Sink Undercoat Mastic	8120/01/02/SYN/BB/2602	Assumed	6	SF	0	SF		1 Sink		1	No	1/D
1	2	Boy's Restroom across from Classroom 202	N/A	Cement Floor		Non Suspect ACM	192	SF	0	SF				N/A	N/A	N/A
1	2	Boy's Restroom across from Classroom 202	N/A	Plaster Ceiling		NAD	192	SF	0	SF				N/A	N/A	N/A
1	2	Boy's Restroom across from Classroom 202	N/A	Plaster Walls		NAD	500	SF	0	SF				N/A	N/A	N/A
1	2	Boy's Restroom across from Classroom 202	N/A	Fiberglass Pipe Fitting Insulation		Non Suspect ACM	5	LF	0	LF				N/A	N/A	N/A
1	2	Custodial Closet next to Boy's Restroom across from Classroom 202	N/A	Cement Floor		Non Suspect ACM	25	SF	X	SF				N/A	N/A	N/A
1	2	Custodial Closet next to Boy's Restroom across from Classroom 202	N/A	Plaster Walls		NAD	70	SF	X	SF				N/A	N/A	N/A
1	2	Custodial Closet next to Boy's Restroom across from Classroom 202	N/A	Plaster Ceiling		NAD	25	SF	X	SF				N/A	N/A	N/A
1	2	Custodial Closet next to Boy's Restroom across from Classroom 202	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	60	LF	X	LF				N/A	N/A	N/A
1	2	Custodial Closet next to Boy's Restroom across from Classroom 202	T	Pipe Fitting Insulation	8120/01/02/50	Confirmed	8	EA	0	EA		Pipe Chase Access is in the Janitor's Closet beside the Boy's Restroom across from Classroom 202		1	No	1/D
1	2	Pipe Chase - Boy's Restroom across from Classroom 202	N/A	Cement Floor		Non Suspect ACM	60	SF	X	SF				N/A	N/A	N/A
1	2	Pipe Chase - Boy's Restroom across from Classroom 202	N/A	Concrete Block Wall		Non Suspect ACM	180	SF	X	SF				N/A	N/A	N/A
1	2	Pipe Chase - Boy's Restroom across from Classroom 202	N/A	Concrete Ceiling		Non Suspect ACM	60	SF	X	SF				N/A	N/A	N/A
1	2	Pipe Chase - Boy's Restroom across from Classroom 202	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	25	LF	X	LF				N/A	N/A	N/A
1	2	Pipe Chase - Boy's Restroom across from Classroom 202	M	Transite Sills	8120/01/02/55	Assumed	10	SF	0	SF		Transite Shelf inside Pipe Chase		1	No	1/D
1	2	Men's Restroom	M	Floor Tile VAT 12" x 12"	8120/01/02/JJ	Assumed	65	SF	0	SF	Tan			1	No	1/D
1	2	Men's Restroom	N/A	Plaster Ceiling		NAD	65	SF	0	SF				N/A	N/A	N/A
1	2	Men's Restroom	N/A	Plaster Walls		NAD	100	SF	0	SF				N/A	N/A	N/A
1	2	Classroom 201	N/A	Wood Floor		Non Suspect ACM	720	SF	0	SF				N/A	N/A	N/A
1	2	Classroom 202	N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	720	SF	0	SF				N/A	N/A	N/A
1	2	Classroom 202	T	Pipe Insulation 2-6 inch	8120/01/02/51	Confirmed	25	LF	0	LF				1	No	1/D
1	2	Classroom 202	M	Blackboard Glue Dots	8120/01/02/SYN/BB/2600	Assumed	100	SF	0	SF		Assumed Present behind Blackboards/Tackboards		1	No	1/D
1	2	Classroom 202	N/A	Wood Wall Partition Room Dividers		Non Suspect ACM	200	SF	0	SF				N/A	N/A	N/A
1	2	Classroom 202	N/A	Plaster Walls		NAD	1200	SF	0	SF				N/A	N/A	N/A
1	2	Classroom 203	N/A	Wood Floor		Non Suspect ACM	768	SF	0	SF				N/A	N/A	N/A
1	2	Classroom 203	N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	768	SF	0	SF				N/A	N/A	N/A
1	2	Classroom 203	T	Pipe Insulation 2-6 inch	8120/01/02/51	Confirmed	25	LF	0	LF				1	No	1/D
1	2	Classroom 203	M	Blackboard Glue Dots	8120/01/02/SYN/BB/2600	Assumed	100	SF	0	SF		Assumed Present behind Blackboards/Tackboards		1	No	1/D
1	2	Classroom 203	N/A	Wood Wall Partition Room Dividers		Non Suspect ACM	200	SF	0	SF				N/A	N/A	N/A
1	2	Classroom 203	N/A	Plaster Walls		NAD	1200	SF	0	SF				N/A	N/A	N/A
1	2	Nurse's Office	N/A	Floor Tile VAT 12" x 12"		NAD	216	SF	0	SF	White	Sampled 9/1/15 (CLIM.Vala)		N/A	N/A	N/A
1	2	Nurse's Office	N/A	Mastic associated with Floor Tile		NAD	216	SF	0	SF		Sampled 9/1/15 (CLIM.Vala)		N/A	N/A	N/A
1	2	Nurse's Office	N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	216	SF	0	SF				N/A	N/A	N/A
1	2	Nurse's Office	N/A	Plaster Walls		NAD	500	SF	0	SF				N/A	N/A	N/A
1	2	Nurse's Office	T	Pipe Insulation 2-6 inch	8120/01/02/51	Confirmed	12	LF	0	LF				1	No	1/D
1	2	Nurse's Office Restroom	N/A	Floor Tile VAT 12" x 12"		NAD	25	SF	0	SF	White	Sampled 9/1/15 (CLIM.Vala)		N/A	N/A	N/A
1	2	Nurse's Office Restroom	N/A	Mastic associated with Floor Tile		NAD	25	SF	0	SF		Sampled 9/1/15 (CLIM.Vala)		N/A	N/A	N/A
1	2	Nurse's Office Restroom	N/A	Plaster Walls		NAD	75	SF	X	SF		3 SF Loose/Flaking Paint		N/A	N/A	N/A
1	2	Nurse's Office Restroom	N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	25	SF	0	SF				N/A	N/A	N/A
1	2	Nurse's Office Restroom	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	10	LF	X	LF				N/A	N/A	N/A
1	2	Counselor's Office #1	M	Floor Tile VAT 9" x 9"	8120/01/02/53	Confirmed	100	SF	0	SF	Green			1	No	1/D
1	2	Counselor's Office #1	N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	100	SF	0	SF				N/A	N/A	N/A
1	2	Counselor's Office #1	N/A	Plaster Walls		NAD	200	SF	0	SF				N/A	N/A	N/A
1	2	Counselor's Office #1	N/A	Sheetrock Wall		Non Suspect ACM	50	SF	X	SF		Interior Partition Walls		N/A	N/A	N/A
1	2	Counselor's Office #1	T	Pipe Insulation 2-6 inch	8120/01/02/51	Confirmed	10	LF	0	LF				1	No	1/D
1	2	Counselor's Office #2	M	Floor Tile VAT 9" x 9"	8120/01/02/53	Confirmed	100	SF	0	SF	Green			1	No	1/D
1	2	Counselor's Office #2	N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	100	SF	0	SF	Green			N/A	N/A	N/A
1	2	Counselor's Office #2	N/A	Plaster Walls		NAD	200	SF	0	SF				N/A	N/A	N/A
1	2	Counselor's Office #2	N/A	Sheetrock Wall		Non Suspect ACM	50	SF	X	SF		Interior Partition Walls		N/A	N/A	N/A
1	2	Counselor's Office #2	T	Pipe Insulation 2-6 inch	8120/01/02/51	Confirmed	10	LF	0	LF				1	No	1/D
1	2	Counselor's Office #3	M	Floor Tile VAT 9" x 9"	8120/01/02/53	Confirmed	96	SF	0	SF	Green			1	No	1/D
1	2	Counselor's Office #3	N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	96	SF	0	SF				N/A	N/A	N/A
1	2	Counselor's Office #3	N/A	Plaster Walls		NAD	200	SF	0	SF				N/A	N/A	N/A
1	2	Counselor's Office #3	N/A	Sheetrock Wall		Non Suspect ACM	50	SF	X	SF		Interior Partition Walls		N/A	N/A	N/A
1	2	Counselor's Office #3	T	Pipe Insulation 2-6 inch	8120/01/02/51	Confirmed	10	LF	0	LF				1	No	1/D
1	2	Counselor's Office #4	M	Floor Tile VAT 9" x 9"	8120/01/02/53	Confirmed	108	SF	0	SF	Green			1	No	1/D
1	2	Counselor's Office #4	N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	108	SF	0	SF				N/A	N/A	N/A
1	2	Counselor's Office #4	N/A	Plaster Walls		NAD	200	SF	0	SF				N/A	N/A	N/A
1	2	Counselor's Office #4	N/A	Plywood Walls		Non Suspect ACM	50	SF	X	SF		Interior Partition Walls		N/A	N/A	N/A
1	2	Counselor's Office #4	T	Pipe Insulation 2-6 inch	8120/01/02/51	Confirmed	10	LF	0	LF				1	No	1/D
1	2	Counselor's Office #5	M	Floor Tile VAT 9" x 9"	8120/01/02/53	Confirmed	90	SF	0	SF	Green			1	No	1/D

8120 Woodrow Wilson MS 2015 2016 AHERA Three-Year Report.xls

School District of Philadelphia			AHERA Three-Year Reinspection 2015-2016 Room by Room Location Log Report										Reinspection Date: December 3, 2015			
Woodrow Wilson Middle School													Building Inspector: Norman Harrison			
1800 Cottman Ave, Philadelphia, PA 19111													Number: 037951			
ULCS# 8120													Management Planner: Megan Vala			
Year Built: 1928													Number: 740728			
E l e m e n t	F l o o r	On Site Room Name	System Affected	Material Description	HID#	Confirmed/Assumed/NAD/ Non Suspect ACM	Amount of Material	SF LF EA	Amount of Damage	SF LF EA	Color required for VAT	Comments/Description/Notes	Attic/ Crawl Space Ranking	Damage Potential (DP)	Newly Friable (NF)	Response Action (RA)
1	2	Counselor's Office #5	N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	90	SF	0	SF				N/A	N/A	N/A
1	2	Counselor's Office #5	N/A	Plaster Walls		NAD	200	SF	0	SF				N/A	N/A	N/A
1	2	Counselor's Office #5	N/A	Plywood Walls		Non Suspect ACM	50	SF	X	SF		Interior Partition Walls		N/A	N/A	N/A
1	2	Counselor's Office #5	T	Pipe Insulation 2-6 inch	8120/01/02/51	Confirmed	10	LF	0	LF				1	No	1/D
1	2	Roster Office	N/A	Wood Floor		Non Suspect ACM	330	SF	0	SF				N/A	N/A	N/A
1	2	Roster Office	N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	330	SF	0	SF				N/A	N/A	N/A
1	2	Roster Office	N/A	Plaster Walls		NAD	500	SF	0	SF				N/A	N/A	N/A
1	2	Roster Office	T	Pipe Insulation 2-6 inch	8120/01/02/51	Confirmed	25	LF	0	LF				1	No	1/D
1	2	School Police Office next to Roster Office	N/A	Wood Floor		Non Suspect ACM	330	SF	0	SF				N/A	N/A	N/A
1	2	School Police Office next to Roster Office	N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	330	SF	0	SF				N/A	N/A	N/A
1	2	School Police Office next to Roster Office	N/A	Plaster Walls		NAD	300	SF	0	SF				N/A	N/A	N/A
1	2	School Police Office next to Roster Office	N/A	Wood Wall Partition Room Dividers		Non Suspect ACM	500	SF	X	SF				N/A	N/A	N/A
1	2	School Police Office next to Roster Office	T	Pipe Insulation 2-6 inch	8120/01/02/51	Confirmed	25	LF	0	LF				1	No	1/D
1	2	Small Hallway outside of School Police Office and School Psychologist	N/A	Floor Tile VAT 12" x 12"		NAD	110	SF	0	SF	Grey	sampled 1/14/2016 B. Joseph		N/A	N/A	N/A
1	2	Small Hallway outside of School Police Office and School Psychologist	N/A	Mastic associated with Floor Tile		NAD	110	SF	0	SF	Black	sampled 1/14/2016 B. Joseph		N/A	N/A	N/A
1	2	Small Hallway outside of School Police Office and School Psychologist	N/A	Plaster Walls		NAD	250	SF	X	SF				N/A	N/A	N/A
1	2	Small Hallway outside of School Police Office and School Psychologist	N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	110	SF	X	SF				N/A	N/A	N/A
1	2	Copy Room/Teacher's Lounge	N/A	Wood Floor		Non Suspect ACM	330	SF	X	SF				N/A	N/A	N/A
1	2	Copy Room/Teacher's Lounge	N/A	Plaster Walls		NAD	550	SF	X	SF				N/A	N/A	N/A
1	2	Copy Room/Teacher's Lounge	N/A	Wood Wall Partition Room Dividers		Non Suspect ACM	250	SF	X	SF				N/A	N/A	N/A
1	2	Copy Room/Teacher's Lounge	N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	330	SF	0	SF				N/A	N/A	N/A
1	2	Copy Room/Teacher's Lounge	T	Pipe Insulation 2-6 inch	8120/01/02/51	Confirmed	25	LF	0	LF				1	No	1/D
1	2	Restroom outside of School Police Office and School Psychologist	N/A	Ceramic Tile Floors		Non Suspect ACM	25	SF	X	SF				N/A	N/A	N/A
1	2	Restroom outside of School Police Office and School Psychologist	N/A	Plaster Walls		NAD	60	SF	X	SF				N/A	N/A	N/A
1	2	Restroom outside of School Police Office and School Psychologist	N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	25	SF	X	SF				N/A	N/A	N/A
1	2	School Police Office next to School Psychologist	M	Floor Tile VAT 9" x 9"	8120/01/02/53	Confirmed	100	SF	0	SF				1	No	1/D
1	2	School Police Office next to School Psychologist	N/A	Plaster Walls		NAD	250	SF	0	SF				N/A	N/A	N/A
1	2	School Police Office next to School Psychologist	N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	100	SF	0	SF				N/A	N/A	N/A
1	2	School Psychologist	N/A	Floor Tile VAT 12" x 12"		NAD	150	SF	0	SF	Grey	sampled 1/14/2016 B. Joseph		N/A	N/A	N/A
1	2	School Psychologist	N/A	Mastic associated with Floor Tile		NAD	150	SF	0	SF	Black	sampled 1/14/2016 B. Joseph		N/A	N/A	N/A
1	2	School Psychologist	N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	150	SF	0	SF				N/A	N/A	N/A
1	2	School Psychologist	N/A	Plaster Walls		NAD	400	SF	0	SF				N/A	N/A	N/A
1	2	School Psychologist	T	Pipe Insulation 2-6 inch	8120/01/02/51	Confirmed	25	LF	0	LF				1	No	1/D
1	2	Principal's Office	N/A	Wood Floor		Non Suspect ACM	270	SF	0	SF				N/A	N/A	N/A
1	2	Principal's Office	N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	270	SF	0	SF				N/A	N/A	N/A
1	2	Principal's Office	N/A	Plaster Walls		NAD	500	SF	0	SF				N/A	N/A	N/A
1	2	Principal's Office	T	Pipe Insulation 2-6 inch	8120/01/02/51	Confirmed	25	LF	0	LF				1	No	1/D
1	2	Principal's Office Restroom	M	Floor Tile VAT 12" x 12"	8120/01/02/JJ	Assumed	25	SF	0	SF				1	No	1/D
1	2	Principal's Office Restroom	N/A	Granite Walls		Non Suspect ACM	30	SF	X	SF		Glue Dots Assumed Present behind Granite Walls		N/A	N/A	N/A
1	2	Principal's Office Restroom	N/A	Plaster Walls		NAD	30	SF	X	SF				N/A	N/A	N/A
1	2	Principal's Office Restroom	N/A	Plaster Ceiling		NAD	25	SF	X	SF				N/A	N/A	N/A
1	2	Main Office	N/A	Wood Floor		Non Suspect ACM	528	SF	0	SF				N/A	N/A	N/A
1	2	Main Office	N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	528	SF	0	SF				N/A	N/A	N/A
1	2	Main Office	N/A	Plaster Walls		NAD	1000	SF	0	SF				N/A	N/A	N/A
1	2	Main Office	T	Pipe Insulation 2-6 inch	8120/01/02/51	Confirmed	50	LF	0	LF				1	No	1/D
1	2	Main Office	T	Pipe Fitting Insulation	8120/01/02/50	Confirmed	4	EA	0	EA				1	No	1/D
1	2	Grand Entrance Foyer Hallway	N/A	Granite Floor		Non Suspect ACM	1200	SF	0	SF				N/A	N/A	N/A
1	2	Grand Entrance Foyer Hallway	N/A	Granite Walls		Non Suspect ACM	1800	SF	0	SF		Glue Dots Assumed Present behind Granite Walls		N/A	N/A	N/A
1	2	Grand Entrance Foyer Hallway	N/A	Plaster Walls		NAD	1800	SF	0	SF				N/A	N/A	N/A
1	2	Grand Entrance Foyer Hallway	N/A	Plaster Ceiling		NAD	1200	SF	0	SF				N/A	N/A	N/A
1	2	Auditorium Balcony	N/A	Wood Floor		Non Suspect ACM	1500	SF	0	SF				N/A	N/A	N/A
1	2	Auditorium Balcony	N/A	Plaster Walls		NAD	4500	SF	0	SF				N/A	N/A	N/A
1	2	Auditorium Balcony	N/A	Plaster Ceiling		NAD	1500	SF	2	SF		Loose/Flaking Paint		N/A	N/A	N/A
1	2	Auditorium Balcony Projection Room	N/A	Concrete Floor		Non Suspect ACM	50	SF	0	SF				N/A	N/A	N/A
1	2	Auditorium Balcony Projection Room	N/A	Plaster Walls		NAD	150	SF	0	SF				N/A	N/A	N/A
1	2	Auditorium Balcony Projection Room	N/A	Plaster Ceiling		NAD	50	SF	0	SF				N/A	N/A	N/A
1	2	IMC Storage Room	M	Floor Tile VAT 12" x 12"	8120/01/02/JJ	Assumed	165	SF	0	SF	Grey			1	No	1/D
1	2	IMC Storage Room	N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	165	SF	0	SF				N/A	N/A	N/A
1	2	IMC Storage Room	N/A	Plaster Walls		NAD	300	SF	0	SF				N/A	N/A	N/A
1	2	IMC Storage Room	T	Pipe Insulation 2-6 inch	8120/01/02/51	Confirmed	50	LF	0	LF				1	No	1/D
1	2	IMC Office	M	Floor Tile VAT 12" x 12"	8120/01/02/JJ	Assumed	165	SF	0	SF	Grey			1	No	1/D
1	2	IMC Office	N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	165	SF	0	SF				N/A	N/A	N/A
1	2	IMC Office	N/A	Plaster Walls		NAD	300	SF	0	SF				N/A	N/A	N/A
1	2	IMC Office	T	Pipe Insulation 2-6 inch	8120/01/02/51	Confirmed	50	LF	0	LF				1	No	1/D
1	2	Computer Lab 209	N/A	Wood Floor		Non Suspect ACM	960	SF	0	SF		Previous location of IMC		N/A	N/A	N/A
1	2	Computer Lab 209	N/A	Fiberlass Ceiling Tile 2' x 4'		Non Suspect ACM	960	SF	0	SF				N/A	N/A	N/A

8120 Woodrow Wilson MS 2015 2016 AHERA Three-Year Report.xls

School District of Philadelphia Woodrow Wilson Middle School 1800 Cottman Ave, Philadelphia, PA 19111 ULCS# 8120 Year Built: 1928			AHERA Three-Year Reinspection 2015-2016 Room by Room Location Log Report										Reinspection Date: December 3, 2015 Building Inspector: Norman Harrison Number: 037951 Management Planner: Megan Vala Number: 740728						
E l e m e n t	F l o o r	On Site Room Name	System Affected	Material Description	HID#	Confirmed/Assumed/NAD/ Non Suspect ACM	Amount of Material	SF LF EA	Amount of Damage	SF LF EA	Color required for VAT	Comments/Description/Notes	Attic/ Crawl Space Ranking	Damage Potential (DP)	Newly Friable (NF)	Response Action (RA)			
1	2	Computer Lab 209	N/A	Plaster Walls		NAD	2880	SF	0	SF				N/A	N/A	N/A			
1	2	Computer Lab 209	N/A	Sheetrock Wall		Non Suspect ACM	250	SF	0	SF				N/A	N/A	N/A			
1	2	Computer Lab 209	N/A	Duct Work		Non Suspect ACM	200	SF	0	SF				N/A	N/A	N/A			
1	2	Computer Lab 209	T	Pipe Insulation 2-6 inch	8120/01/02/51	Confirmed	48	LF	0	LF				1	No	1/D			
1	2	Computer Lab 210	N/A	Wood Floor		Non Suspect ACM	960	SF	0	SF		Previous location of IMC		N/A	N/A	N/A			
1	2	Computer Lab 210	N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	960	SF	0	SF				N/A	N/A	N/A			
1	2	Computer Lab 210	N/A	Plaster Walls		NAD	2880	SF	0	SF				N/A	N/A	N/A			
1	2	Computer Lab 210	N/A	Sheetrock Wall		Non Suspect ACM	250	SF	0	SF				N/A	N/A	N/A			
1	2	Computer Lab 210	N/A	Duct Work		Non Suspect ACM	200	SF	0	SF				N/A	N/A	N/A			
1	2	Computer Lab 210	T	Pipe Insulation 2-6 inch	8120/01/02/51	Confirmed	60	LF	0	LF				1	No	1/D			
1	2	Classroom 211	N/A	Wood Floor		Non Suspect ACM	864	SF	0	SF				N/A	N/A	N/A			
1	2	Classroom 211	N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	864	SF	0	SF				N/A	N/A	N/A			
1	2	Classroom 211	N/A	Plaster Walls		NAD	1500	SF	0	SF				N/A	N/A	N/A			
1	2	Classroom 211	T	Pipe Insulation 2-6 inch	8120/01/02/51	Confirmed	60	LF	0	LF				1	No	1/D			
1	2	Classroom 212	N/A	Wood Floor		Non Suspect ACM	864	SF	0	SF		Fiberglass Utility Sink Present		N/A	N/A	N/A			
1	2	Classroom 212	N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	864	SF	0	SF				N/A	N/A	N/A			
1	2	Classroom 212	T	Pipe Insulation 2-6 inch	8120/01/02/51	Confirmed	34	LF	0	LF		4 Pipe Risers		1	No	1/D			
1	2	Classroom 212	M	Blackboard Glue Dots	8120/01/02/SYN/BB/2600	Assumed	65	SF	0	SF		Assumed Present behind Blackboards/Tackboards		1	No	1/D			
1	2	Classroom 212	N/A	Plaster Walls		NAD	1500	SF	0	SF		10 SF Plaster Wall Damage on Window Wall		N/A	N/A	N/A			
1	2	Storage Closet in Classroom 212	N/A	Wood Floor		Non Suspect ACM	25	SF	X	SF				N/A	N/A	N/A			
1	2	Storage Closet in Classroom 212	N/A	Plaster Walls		NAD	75	SF	X	SF				N/A	N/A	N/A			
1	2	Storage Closet in Classroom 212	N/A	Plaster Ceiling		NAD	25	SF	X	SF				N/A	N/A	N/A			
1	2	Classroom 213	N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	696	SF	0	SF				N/A	N/A	N/A			
1	2	Classroom 213	T	Pipe Insulation 2-6 inch	8120/01/02/51	Confirmed	50	LF	0	LF				1	No	1/D			
1	2	Classroom 213	M	Blackboard Glue Dots	8120/01/02/SYN/BB/2600	Assumed	200	SF	0	SF		Assumed Present behind Blackboards/Tackboards		1	No	1/D			
1	2	Classroom 213	N/A	Plaster Walls		NAD	1200	SF	0	SF				N/A	N/A	N/A			
1	2	Classroom 214	N/A	Wood Floor		Non Suspect ACM	744	SF	0	SF				N/A	N/A	N/A			
1	2	Classroom 214	N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	744	SF	0	SF				N/A	N/A	N/A			
1	2	Classroom 214	T	Pipe Insulation 2-6 inch	8120/01/02/51	Confirmed	50	LF	0	LF				1	No	1/D			
1	2	Classroom 214	M	Blackboard Glue Dots	8120/01/02/SYN/BB/2600	Assumed	200	SF	0	SF		Assumed Present behind Blackboards/Tackboards		1	No	1/D			
1	2	Classroom 214	N/A	Plaster Walls		NAD	1200	SF	0	SF				N/A	N/A	N/A			
1	2	Girl's Restroom across from Classroom 214	N/A	Cement Floor		Non Suspect ACM	192	SF	0	SF				N/A	N/A	N/A			
1	2	Girl's Restroom across from Classroom 214	N/A	Plaster Ceiling		NAD	192	SF	0	SF				N/A	N/A	N/A			
1	2	Girl's Restroom across from Classroom 214	N/A	Plaster Walls		NAD	500	SF	0	SF				N/A	N/A	N/A			
1	2	Girl's Restroom across from Classroom 214	N/A	Fiberglass Pipe Fitting Insulation		Non Suspect ACM	5	LF	0	LF				N/A	N/A	N/A			
1	2	Custodial Closet next to Girl's Restroom across from Classroom 214	N/A	Cement Floor		Non Suspect ACM	25	SF	X	SF				N/A	N/A	N/A			
1	2	Custodial Closet next to Girl's Restroom across from Classroom 214	N/A	Plaster Walls		NAD	70	SF	X	SF				N/A	N/A	N/A			
1	2	Custodial Closet next to Girl's Restroom across from Classroom 214	N/A	Plaster Ceiling		NAD	25	SF	X	SF				N/A	N/A	N/A			
1	2	Custodial Closet next to Girl's Restroom across from Classroom 214	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	60	LF	X	LF				N/A	N/A	N/A			
1	2	Custodial Closet next to Girl's Restroom across from Classroom 214	T	Pipe Fitting Insulation	8120/01/02/50	Confirmed	10	EA	0	EA				1	No	1/D			
1	2	Pipe Chase - Girl's Restroom across from Classroom 214	N/A	Cement Floor		Non Suspect ACM	60	SF	X	SF		Pipe Chase Access is in the Janitor's Closet beside the Girl's Restroom across from Classroom 214		N/A	N/A	N/A			
1	2	Pipe Chase - Girl's Restroom across from Classroom 214	N/A	Concrete Block Wall		Non Suspect ACM	180	SF	X	SF				N/A	N/A	N/A			
1	2	Pipe Chase - Girl's Restroom across from Classroom 214	N/A	Concrete Ceiling		Non Suspect ACM	60	SF	X	SF				N/A	N/A	N/A			
1	2	Pipe Chase - Girl's Restroom across from Classroom 214	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	25	LF	X	LF				N/A	N/A	N/A			
1	2	Pipe Chase - Girl's Restroom across from Classroom 214	M	Transite Sills	8120/01/02/55	Assumed	20	SF	0	SF		Fixed Transite Shelf and Loose Transite Shelf inside Pipe Chase		1	No	1/D			
1	2	Classroom 215	N/A	Wood Floor		Non Suspect ACM	660	SF	0	SF				N/A	N/A	N/A			
1	2	Classroom 215	N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	660	SF	0	SF				N/A	N/A	N/A			
1	2	Classroom 215	T	Pipe Insulation 2-6 inch	8120/01/02/51	Confirmed	50	LF	0	LF				1	No	1/D			
1	2	Classroom 215	M	Blackboard Glue Dots	8120/01/02/SYN/BB/2600	Assumed	200	SF	0	SF		Assumed Present behind Blackboards/Tackboards		1	No	1/D			
1	2	Classroom 215	N/A	Plaster Walls		NAD	1200	SF	0	SF				N/A	N/A	N/A			
1	2	Women's Lounge	N/A	Wood Floor		Non Suspect ACM	192	SF	0	SF				N/A	N/A	N/A			
1	2	Women's Lounge	N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	192	SF	0	SF				N/A	N/A	N/A			
1	2	Women's Lounge	N/A	Plaster Walls		NAD	300	SF	0	SF				N/A	N/A	N/A			
1	2	Women's Lounge	T	Pipe Insulation 2-6 inch	8120/01/02/51	Confirmed	12	LF	0	LF				1	No	1/D			
1	2	Women's Lounge	M	Sink Undercoat Mastic	8120/01/02/SYN/BB/2602	Assumed	6	SF	0	SF		1 Sink		1	No	1/D			
1	2	Women's Restroom	M	Floor Tile VAT 12" x 12"	8120/01/02/JJ	Assumed	65	SF	0	SF	Tan			1	No	1/D			
1	2	Women's Restroom	N/A	Plaster Ceiling		NAD	65	SF	0	SF				N/A	N/A	N/A			
1	2	Women's Restroom	N/A	Plaster Walls		NAD	100	SF	0	SF				N/A	N/A	N/A			
1	2	Classroom 216	N/A	Wood Floor		Non Suspect ACM	816	SF	0	SF				N/A	N/A	N/A			
1	2	Classroom 216	N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	816	SF	0	SF				N/A	N/A	N/A			
1	2	Classroom 216	T	Pipe Insulation 2-6 inch	8120/01/02/51	Confirmed	50	LF	0	LF				1	No	1/D			
1	2	Classroom 216	M	Blackboard Glue Dots	8120/01/02/SYN/BB/2600	Assumed	200	SF	0	SF		Assumed Present behind Blackboards/Tackboards		1	No	1/D			
1	2	Classroom 216	N/A	Plaster Walls		NAD	1200	SF	0	SF				N/A	N/A	N/A			
1	2	Classroom 217	N/A	Wood Floor		Non Suspect ACM	768	SF	0	SF				N/A	N/A	N/A			
1	2	Classroom 217	N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	768	SF	0	SF				N/A	N/A	N/A			

8120 Woodrow Wilson MS 2015 2016 AHERA Three-Year Report.xls

School District of Philadelphia		AHERA Three-Year Reinspection 2015-2016 Room by Room Location Log Report										Reinspection Date: December 3, 2015				
Woodrow Wilson Middle School												Building Inspector: Norman Harrison				
1800 Cottman Ave, Philadelphia, PA 19111												Number: 037951				
ULCS# 8120												Management Planner: Megan Vala				
Year Built: 1928												Number: 740728				
E l e m e n t	F l o o r	On Site Room Name	System Affected	Material Description	HID#	Confirmed/Assumed/NAD/ Non Suspect ACM	Amount of Material	SF LF EA	Amount of Damage	SF LF EA	Color required for VAT	Comments/Description/Notes	Attic/ Crawl Space Ranking	Damage Potential (DP)	Newly Friable (NF)	Response Action (RA)
1	2	Classroom 217	T	Pipe Insulation 2-6 inch	8120/01/02/51	Confirmed	50	LF	0	LF				1	No	1/D
1	2	Classroom 217	M	Blackboard Glue Dots	8120/01/02/SYN/BB/2600	Assumed	200	SF	0	SF		Assumed Present behind Blackboards/Tackboards		1	No	1/D
1	2	Classroom 217	N/A	Plaster Walls		NAD	1200	SF	0	SF				N/A	N/A	N/A
1	2	Classroom 218	N/A	Wood Floor		Non Suspect ACM	768	SF	0	SF				N/A	N/A	N/A
1	2	Classroom 218	N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	768	SF	0	SF				N/A	N/A	N/A
1	2	Classroom 218	T	Pipe Insulation 2-6 inch	8120/01/02/51	Confirmed	50	LF	0	LF				1	No	1/D
1	2	Classroom 218	M	Blackboard Glue Dots	8120/01/02/SYN/BB/2600	Assumed	200	SF	0	SF		Assumed Present behind Blackboards/Tackboards		1	No	1/D
1	2	Classroom 218	N/A	Plaster Walls		NAD	1200	SF	0	SF				N/A	N/A	N/A
1	2	Classroom 219	N/A	Wood Floor		Non Suspect ACM	768	SF	0	SF				N/A	N/A	N/A
1	2	Classroom 219	N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	768	SF	0	SF				N/A	N/A	N/A
1	2	Classroom 219	T	Pipe Insulation 2-6 inch	8120/01/02/51	Confirmed	36	LF	0	LF				1	No	1/D
1	2	Classroom 219	M	Blackboard Glue Dots	8120/01/02/SYN/BB/2600	Assumed	200	SF	0	SF		Assumed Present behind Blackboards/Tackboards		1	No	1/D
1	2	Classroom 219	N/A	Plaster Walls		NAD	1200	SF	0	SF				N/A	N/A	N/A
1	2	Classroom 224A	M	Floor Tile VAT 9" x 9"	8120/01/02/53	Confirmed	800	SF	0	SF	Tan			1	No	1/D
1	2	Classroom 224A	N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	800	SF	0	SF				N/A	N/A	N/A
1	2	Classroom 224A	N/A	Brick Wall		Non Suspect ACM	1000	SF	0	SF				N/A	N/A	N/A
1	2	Classroom 224A	N/A	Plaster Walls		NAD	1000	SF	0	SF				N/A	N/A	N/A
1	2	Classroom 224A	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	50	LF	0	LF				N/A	N/A	N/A
1	2	Classroom 224A	M	Blackboard Glue Dots	8120/01/02/SYN/BB/2600	Assumed	100	SF	0	SF		Assumed Present behind Blackboards/Tackboards		1	No	1/D
1	2	Office 223B (Special Education)	M	Floor Tile VAT 12" x 12"	8120/01/02/JJ	Assumed	330	SF	0	SF	Green			1	No	1/D
1	2	Office 223B (Special Education)	N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	330	SF	0	SF				N/A	N/A	N/A
1	2	Office 223B (Special Education)	N/A	Brick Wall		Non Suspect ACM	500	SF	0	SF				N/A	N/A	N/A
1	2	Office 223B (Special Education)	N/A	Plaster Walls		NAD	500	SF	0	SF				N/A	N/A	N/A
1	2	Office 223B (Special Education)	M	Blackboard Glue Dots	8120/01/02/SYN/BB/2600	Assumed	200	SF	0	SF		Assumed Present behind Blackboards/Tackboards		1	No	1/D
1	2	Office 223A (Mail Room)	M	Floor Tile VAT 12" x 12"	8120/01/02/JJ	Assumed	330	SF	0	SF	Green			1	No	1/D
1	2	Office 223A (Mail Room)	N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	330	SF	0	SF				N/A	N/A	N/A
1	2	Office 223A (Mail Room)	N/A	Brick Wall		Non Suspect ACM	500	SF	0	SF				N/A	N/A	N/A
1	2	Office 223A (Mail Room)	N/A	Plaster Walls		NAD	500	SF	0	SF				N/A	N/A	N/A
1	2	Office 223A (Mail Room)	M	Blackboard Glue Dots	8120/01/02/SYN/BB/2600	Assumed	200	SF	0	SF		Assumed Present behind Blackboards/Tackboards		1	No	1/D
1	2	Classroom 221	N/A	Wood Floor		Non Suspect ACM	816	SF	0	SF				N/A	N/A	N/A
1	2	Classroom 221	N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	816	SF	0	SF				N/A	N/A	N/A
1	2	Classroom 221	T	Pipe Insulation 2-6 inch	8120/01/02/51	Confirmed	50	LF	0	LF				1	No	1/D
1	2	Classroom 221	M	Blackboard Glue Dots	8120/01/02/SYN/BB/2600	Assumed	200	SF	0	SF		Assumed Present behind Blackboards/Tackboards		1	No	1/D
1	2	Classroom 221	N/A	Plaster Walls		NAD	1200	SF	0	SF				N/A	N/A	N/A
1	2	Classroom 220	N/A	Wood Floor		Non Suspect ACM	768	SF	0	SF				N/A	N/A	N/A
1	2	Classroom 220	N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	768	SF	0	SF				N/A	N/A	N/A
1	2	Classroom 220	T	Pipe Insulation 2-6 inch	8120/01/02/51	Confirmed	50	LF	0	LF				1	No	1/D
1	2	Classroom 220	M	Blackboard Glue Dots	8120/01/02/SYN/BB/2600	Assumed	200	SF	0	SF		Assumed Present behind Blackboards/Tackboards		1	No	1/D
1	2	Classroom 220	N/A	Plaster Walls		NAD	1200	SF	0	SF				N/A	N/A	N/A
1	2	Storage Room across from Classroom 219	N/A	Cement Floor		Non Suspect ACM	195	SF	0	SF				N/A	N/A	N/A
1	2	Storage Room across from Classroom 219	N/A	Plaster Ceiling		NAD	195	SF	0	SF				N/A	N/A	N/A
1	2	Storage Room across from Classroom 219	N/A	Plaster Walls		NAD	350	SF	0	SF				N/A	N/A	N/A
1	2	Storage Room across from Classroom 218	N/A	Cement Floor		Non Suspect ACM	195	SF	0	SF				N/A	N/A	N/A
1	2	Storage Room across from Classroom 218	N/A	Plaster Ceiling		NAD	195	SF	0	SF				N/A	N/A	N/A
1	2	Storage Room across from Classroom 218	N/A	Plaster Walls		NAD	350	SF	0	SF				N/A	N/A	N/A
1	2	Classroom next to Classroom 224A	N/A	Cement Floor		Non Suspect ACM	360	SF	0	SF				N/A	N/A	N/A
1	2	Classroom next to Classroom 224A	N/A	Concrete Ceiling		NAD	360	SF	0	SF				N/A	N/A	N/A
1	2	Classroom next to Classroom 224A	N/A	Brick Wall		Non Suspect ACM	400	SF	X	SF				N/A	N/A	N/A
1	2	Classroom next to Classroom 224A	N/A	Concrete Block Wall		Non Suspect ACM	400	SF	0	SF				N/A	N/A	N/A
1	2	Classroom next to Classroom 224A	N/A	Fiberglass Pipe Fitting Insulation		Non Suspect ACM	12	LF	0	LF				N/A	N/A	N/A
1	2	Classroom 222	N/A	Wood Floor		Non Suspect ACM	660	SF	0	SF				N/A	N/A	N/A
1	2	Classroom 222	N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	660	SF	0	SF				N/A	N/A	N/A
1	2	Classroom 222	T	Pipe Insulation 2-6 inch	8120/01/02/51	Confirmed	50	LF	0	LF				1	No	1/D
1	2	Classroom 222	M	Blackboard Glue Dots	8120/01/02/SYN/BB/2600	Assumed	200	SF	0	SF		Assumed Present behind Blackboards/Tackboards		1	No	1/D
1	2	Classroom 222	N/A	Plaster Walls		NAD	1200	SF	0	SF				N/A	N/A	N/A
1	2	Hallway outside Classrooms 201 - 203	N/A	Cement Floor		Non Suspect ACM	1000	SF	0	SF				N/A	N/A	N/A
1	2	Hallway outside Classrooms 201 - 203	N/A	Granite Walls		Non Suspect ACM	1500	SF	0	SF		Glue Dots Assumed Present behind Granite Walls		N/A	N/A	N/A
1	2	Hallway outside Classrooms 201 - 203	N/A	Plaster Walls		NAD	3000	SF	0	SF				N/A	N/A	N/A
1	2	Hallway outside Classrooms 201 - 203	N/A	Ceiling Tile 2' x 4'		Non Suspect ACM	1000	SF	0	SF				N/A	N/A	N/A
1	2	Hallway outside Main Office Suite	N/A	Cement Floor		Non Suspect ACM	1000	SF	0	SF				N/A	N/A	N/A
1	2	Hallway outside Main Office Suite	N/A	Granite Walls		Non Suspect ACM	1500	SF	0	SF		Glue Dots Assumed Present behind Granite Walls		N/A	N/A	N/A
1	2	Hallway outside Main Office Suite	N/A	Plaster Walls		NAD	3000	SF	0	SF				N/A	N/A	N/A
1	2	Hallway outside Main Office Suite	N/A	Ceiling Tile 2' x 4'		Non Suspect ACM	1000	SF	0	SF				N/A	N/A	N/A
1	2	Hallway outside Main Office Suite	T	Pipe Insulation 2-6 inch	8120/01/02/51	Confirmed	60	LF	0	LF				1	No	1/D
1	2	Hallway outside Computer Lab Classrooms 209 and 210	N/A	Cement Floor		Non Suspect ACM	1000	SF	0	SF				N/A	N/A	N/A
1	2	Hallway outside Computer Lab Classrooms 209 and 210	N/A	Granite Walls		Non Suspect ACM	1500	SF	0	SF		Glue Dots Assumed Present behind Granite Walls		N/A	N/A	N/A
1	2	Hallway outside Computer Lab Classrooms 209 and 210	N/A	Plaster Walls		NAD	3000	SF	0	SF				N/A	N/A	N/A
1	2	Hallway outside Computer Lab Classrooms 209 and 210	N/A	Ceiling Tile 2' x 4'		Non Suspect ACM	1000	SF	0	SF				N/A	N/A	N/A
1	2	Hallway outside Computer Lab Classrooms 209 and 210	T	Pipe Insulation 2-6 inch	8120/01/02/51	Confirmed	60	LF	0	LF				1	No	1/D
1	2	Hallway outside Classrooms 212 - 214	N/A	Cement Floor		Non Suspect ACM	1000	SF	0	SF				N/A	N/A	N/A

8120 Woodrow Wilson MS 2015 2016 AHERA Three-Year Report.xls

School District of Philadelphia Woodrow Wilson Middle School 1800 Cottman Ave, Philadelphia, PA 19111 ULCS# 8120 Year Built: 1928			AHERA Three-Year Reinspection 2015-2016 Room by Room Location Log Report										Reinspection Date: December 3, 2015 Building Inspector: Norman Harrison Number: 037951 Management Planner: Megan Vala Number: 740728			
E l e m e n t	F l o o r	On Site Room Name	System Affected	Material Description	HID#	Confirmed/Assumed/NAD/ Non Suspect ACM	Amount of Material	SF LF EA	Amount of Damage	SF LF EA	Color required for VAT	Comments/Description/Notes	Attic/ Crawl Space Ranking	Damage Potential (DP)	Newly Friable (NF)	Response Action (RA)
1	2	Hallway outside Classrooms 212 - 214	N/A	Granite Walls		Non Suspect ACM	1500	SF	0	SF		Glue Dots Assumed Present behind Granite Walls		N/A	N/A	N/A
1	2	Hallway outside Classrooms 212 - 214	N/A	Plaster Walls		NAD	3000	SF	0	SF				N/A	N/A	N/A
1	2	Hallway outside Classrooms 212 - 214	N/A	Ceiling Tile 2' x 4'		Non Suspect ACM	1000	SF	0	SF				N/A	N/A	N/A
1	2	Hallway outside Classrooms 215 - 222	N/A	Cement Floor		Non Suspect ACM	3000	SF	0	SF				N/A	N/A	N/A
1	2	Hallway outside Classrooms 215 - 222	N/A	Granite Walls		Non Suspect ACM	4500	SF	0	SF		Glue Dots Assumed Present behind Granite Walls		N/A	N/A	N/A
1	2	Hallway outside Classrooms 215 - 222	N/A	Plaster Walls		NAD	9000	SF	0	SF				N/A	N/A	N/A
1	2	Hallway outside Classrooms 215 - 222	N/A	Ceiling Tile 2' x 4'		Non Suspect ACM	3000	SF	0	SF				N/A	N/A	N/A
1	2	Hallway outside Classrooms 215 - 222	T	Pipe Insulation 2-6 inch	8120/01/02/51	Confirmed	168	LF	0	LF				1	No	1/D
1	2	Stairwell across from Classroom 214	N/A	Cement Floor		Non Suspect ACM	300	SF	0	SF				N/A	N/A	N/A
1	2	Stairwell across from Classroom 214	N/A	Granite Walls		Non Suspect ACM	450	SF	0	SF		Glue Dots Assumed Present behind Granite Walls		N/A	N/A	N/A
1	2	Stairwell across from Classroom 214	N/A	Plaster Walls		NAD	900	SF	0	SF				N/A	N/A	N/A
1	2	Stairwell across from Classroom 214	N/A	Plaster Ceiling		NAD	300	SF	0	SF				N/A	N/A	N/A
1	2	Stairwell across from Classroom 214	T	Pipe Insulation 2-6 inch	8120/01/02/51	Confirmed	32	LF	1	LF		1st - 2nd Floor Landing		2	Yes	5/A
1	2	Stairwell across from Classroom 214	T	Pipe Fitting Insulation	8120/01/02/50	Confirmed	8	EA	0	EA		1st - 2nd Floor Landing		1	No	1/D
1	2	Stairwell across from Classroom 212	N/A	Cement Floor		Non Suspect ACM	300	SF	0	SF				N/A	N/A	N/A
1	2	Stairwell across from Classroom 212	N/A	Granite Walls		Non Suspect ACM	450	SF	0	SF		Glue Dots Assumed Present behind Granite Walls		N/A	N/A	N/A
1	2	Stairwell across from Classroom 212	N/A	Plaster Walls		NAD	900	SF	0	SF				N/A	N/A	N/A
1	2	Stairwell across from Classroom 212	N/A	Plaster Ceiling		NAD	300	SF	0	SF				N/A	N/A	N/A
1	2	Stairwell across from Classroom 212	T	Pipe Insulation 2-6 inch	8120/01/02/51	Confirmed	32	LF	1	LF		1st - 2nd Floor Landing		2	Yes	5/A
1	2	Stairwell across from Classroom 212	T	Pipe Fitting Insulation	8120/01/02/50	Confirmed	8	EA	0	EA		1st - 2nd Floor Landing		1	No	1/D
1	2	Stairwell across from Classroom 203	N/A	Cement Floor		Non Suspect ACM	300	SF	0	SF				N/A	N/A	N/A
1	2	Stairwell across from Classroom 203	N/A	Granite Walls		Non Suspect ACM	450	SF	0	SF		Glue Dots Assumed Present behind Granite Walls		N/A	N/A	N/A
1	2	Stairwell across from Classroom 203	N/A	Plaster Walls		NAD	900	SF	0	SF				N/A	N/A	N/A
1	2	Stairwell across from Classroom 203	N/A	Plaster Ceiling		NAD	300	SF	0	SF				N/A	N/A	N/A
1	2	Stairwell across from Classroom 203	T	Pipe Insulation 2-6 inch	8120/01/02/51	Confirmed	30	LF	0	LF		1st - 2nd Floor Landing		1	No	1/D
1	2	Stairwell across from Classroom 203	T	Pipe Fitting Insulation	8120/01/02/50	Confirmed	8	EA	0	EA		1st - 2nd Floor Landing		1	No	1/D
1	2	Stairwell across from Classroom 201	N/A	Cement Floor		Non Suspect ACM	300	SF	0	SF				N/A	N/A	N/A
1	2	Stairwell across from Classroom 201	N/A	Granite Walls		Non Suspect ACM	450	SF	0	SF		Glue Dots Assumed Present behind Granite Walls		N/A	N/A	N/A
1	2	Stairwell across from Classroom 201	N/A	Plaster Walls		NAD	900	SF	0	SF				N/A	N/A	N/A
1	2	Stairwell across from Classroom 201	N/A	Plaster Ceiling		NAD	300	SF	0	SF				N/A	N/A	N/A
1	2	Stairwell across from Classroom 201	T	Pipe Insulation 2-6 inch	8120/01/02/51	Confirmed	30	LF	0	LF		1st - 2nd Floor Landing		1	No	1/D
1	2	Stairwell across from Classroom 201	T	Pipe Fitting Insulation	8120/01/02/50	Confirmed	8	EA	0	EA		1st - 2nd Floor Landing		1	No	1/D
1	2	Fire Tower Stairwell next to Classroom 221	N/A	Cement Floor		Non Suspect ACM	125	SF	0	SF				N/A	N/A	N/A
1	2	Fire Tower Stairwell next to Classroom 221	N/A	Brick Wall		Non Suspect ACM	375	SF	0	SF				N/A	N/A	N/A
1	2	Fire Tower Stairwell next to Classroom 221	N/A	Concrete Ceiling		Non Suspect ACM	125	SF	0	SF				N/A	N/A	N/A
1	2	Fire Tower Stairwell next to Classroom 216	N/A	Cement Floor		Non Suspect ACM	125	SF	0	SF				N/A	N/A	N/A
1	2	Fire Tower Stairwell next to Classroom 216	N/A	Brick Wall		Non Suspect ACM	375	SF	0	SF				N/A	N/A	N/A
1	2	Fire Tower Stairwell next to Classroom 216	N/A	Concrete Ceiling		Non Suspect ACM	125	SF	0	SF				N/A	N/A	N/A
1	2	Boy's Locker Room - Enter from the Boy's Gym Stairwell on the 1st Floor	N/A	Cement Floor		Non Suspect ACM	600	SF	X	SF				N/A	N/A	N/A
1	2	Boy's Locker Room - Enter from the Boy's Gym Stairwell on the 1st Floor	N/A	Brick Wall		Non Suspect ACM	1400	SF	X	SF				N/A	N/A	N/A
1	2	Boy's Locker Room - Enter from the Boy's Gym Stairwell on the 1st Floor	N/A	Concrete Ceiling		Non Suspect ACM	600	SF	X	SF				N/A	N/A	N/A
1	2	Boy's Locker Room - Enter from the Boy's Gym Stairwell on the 1st Floor	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	2	LF	X	LF		Applied to a Roof Drain		N/A	N/A	N/A
1	2	Storage Room inside Boy's Locker Room	x	x		x	x	x	X	x		No Access - Both Entrances are barricaded with Plywood		X	X	X
1	2	Restroom inside Boy's Locker Room	M	Floor Tile VAT 12" x 12"	8120/01/02/UJ	Assumed	60	SF	0	SF				1	No	1/D
1	2	Restroom inside Boy's Locker Room	N/A	Brick Wall		Non Suspect ACM	150	SF	X	SF				N/A	N/A	N/A
1	2	Restroom inside Boy's Locker Room	N/A	Concrete Ceiling		Non Suspect ACM	60	SF	X	SF				N/A	N/A	N/A
1	2	Restroom inside Boy's Locker Room	N/A	Metal Duct		Non Suspect ACM	1	EA	X	EA				N/A	N/A	N/A
1	2	Girl's Locker Room - Enter from the Girl's Gym Stairwell on the 1st Floor	N/A	Cement Floor		Non Suspect ACM	600	SF	X	SF				N/A	N/A	N/A
1	2	Girl's Locker Room - Enter from the Girl's Gym Stairwell on the 1st Floor	N/A	Brick Wall		Non Suspect ACM	1400	SF	X	SF		300 SF Loose/Flaking Paint		N/A	N/A	N/A
1	2	Girl's Locker Room - Enter from the Girl's Gym Stairwell on the 1st Floor	N/A	Concrete Ceiling		Non Suspect ACM	600	SF	X	SF		120 SF Loose/Flaking Paint		N/A	N/A	N/A
1	2	Storage Room inside Girl's Locker Room	N/A	Cement Floor		Non Suspect ACM	16	LF	X	LF				N/A	N/A	N/A
1	2	Storage Room inside Girl's Locker Room	N/A	Brick Wall		Non Suspect ACM	600	SF	X	SF				N/A	N/A	N/A
1	2	Storage Room inside Girl's Locker Room	N/A	Concrete Ceiling		Non Suspect ACM	250	SF	X	SF				N/A	N/A	N/A
1	2	Restroom inside Girl's Locker Room	M	Floor Tile VAT 12" x 12"	8120/01/02/UJ	Assumed	60	SF	0	SF				1	No	1/D
1	2	Restroom inside Girl's Locker Room	N/A	Brick Wall		Non Suspect ACM	150	SF	X	SF				N/A	N/A	N/A
1	2	Restroom inside Girl's Locker Room	N/A	Concrete Ceiling		Non Suspect ACM	60	SF	X	SF				N/A	N/A	N/A
1	2	Restroom inside Girl's Locker Room	N/A	Metal Duct		Non Suspect ACM	1	EA	X	EA				N/A	N/A	N/A
1	2	Restroom inside Girl's Locker Room	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	5	LF	X	LF		Below metal jacketing		N/A	N/A	N/A
1	1	Classroom 108A	M	Floor Tile VAT 9" x 9"	8120/01/01/12	Confirmed	1080	SF	0	SF	Green			1	No	1/D
1	1	Classroom 108A	N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	1080	SF	0	SF				N/A	N/A	N/A
1	1	Classroom 108A	N/A	Brick Wall		Non Suspect ACM	600	SF	0	SF				N/A	N/A	N/A
1	1	Classroom 108A	N/A	Plaster Walls		NAD	600	SF	0	SF				N/A	N/A	N/A
1	1	Classroom 108A	T	Pipe Insulation 2-6 inch	8120/01/01/13	Confirmed	50	LF	0	LF				1	No	1/D
1	1	Classroom 108A	T	Pipe Fitting Insulation	8120/01/01/15	Confirmed	3	EA	0	EA				1	No	1/D
1	1	Classroom 106 Closet	M	Floor Tile VAT 9" x 9"	8120/01/01/12	Confirmed	125	SF	0	SF	Tan			1	No	1/D
1	1	Classroom 106 Closet	N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	125	SF	0	SF				N/A	N/A	N/A
1	1	Classroom 106 Closet	T	Pipe Fitting Insulation	8120/01/01/15	Confirmed	4	EA	0	EA				1	No	1/D

8120 Woodrow Wilson MS 2015 2016 AHERA Three-Year Report.xls

School District of Philadelphia Woodrow Wilson Middle School 1800 Cottman Ave, Philadelphia, PA 19111 ULCS# 8120 Year Built: 1928			AHERA Three-Year Reinspection 2015-2016 Room by Room Location Log Report										Reinspection Date: December 3, 2015 Building Inspector: Norman Harrison Number: 037951 Management Planner: Megan Vala Number: 740728			
E l e m e n t	F l o o r	On Site Room Name	System Affected	Material Description	HID#	Confirmed/Assumed/NAD/ Non Suspect ACM	Amount of Material	SF LF EA	Amount of Damage	SF LF EA	Color required for VAT	Comments/Description/Notes	Attic/ Crawl Space Ranking	Damage Potential (DP)	Newly Friable (NF)	Response Action (RA)
1	1	Classroom 106 Closet	N/A	Plaster Walls		NAD	500	SF	0	SF				N/A	N/A	N/A
1	1	Classroom 106 Closet	T	Pipe Insulation 2-6 inch	8120/01/01/13	Confirmed	50	LF	0	LF				1	No	1/D
1	1	Classroom 105A Closet	M	Floor Tile VAT 9" x 9"	8120/01/01/12	Confirmed	125	SF	0	SF	Tan			1	No	1/D
1	1	Classroom 105A Closet	N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	125	SF	0	SF				N/A	N/A	N/A
1	1	Classroom 105A Closet	T	Pipe Fitting Insulation	8120/01/01/15	Confirmed	4	EA	0	EA				1	No	1/D
1	1	Classroom 105A Closet	N/A	Plaster Walls		NAD	500	SF	0	SF				N/A	N/A	N/A
1	1	Classroom 105A Closet	T	Pipe Insulation 2-6 inch	8120/01/01/13	Confirmed	50	LF	0	LF				1	No	1/D
1	1	Foyer outside Classrooms 103A & 103B	M	Floor Tile VAT 12" x 12"	8120/01/01/HH	Assumed	80	SF	0	SF	Tan			1	No	1/D
1	1	Foyer outside Classrooms 103A & 103B	N/A	Sheetrock Wall		Non Suspect ACM	160	SF	0	SF				N/A	N/A	N/A
1	1	Foyer outside Classrooms 103A & 103B	N/A	Ceiling Tile 2' x 4'		Non Suspect ACM	80	SF	0	SF				N/A	N/A	N/A
1	1	Classroom 103B	M	Floor Tile VAT 12" x 12"	8120/01/01/HH	Assumed	675	SF	0	SF	Tan			1	No	1/D
1	1	Classroom 103B	N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	675	SF	0	SF				N/A	N/A	N/A
1	1	Classroom 103B	N/A	Brick Wall		Non Suspect ACM	500	SF	0	SF				N/A	N/A	N/A
1	1	Classroom 103B	N/A	Plaster Walls		NAD	500	SF	0	SF				N/A	N/A	N/A
1	1	Classroom 103B	T	Pipe Insulation 2-6 inch	8120/01/01/13	Confirmed	24	LF	0	LF				1	No	1/D
1	1	Classroom 103B	M	Blackboard Glue Dots	8120/01/01/SYN/BB/2600	Assumed	32	SF	0	SF		Assumed Present behind Blackboards/Tackboards		1	No	1/D
1	1	Classroom 103A	M	Floor Tile VAT 12" x 12"	8120/01/01/HH	Assumed	770	SF	0	SF	Tan			1	No	1/D
1	1	Classroom 103A	N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	770	SF	0	SF				N/A	N/A	N/A
1	1	Classroom 103A	N/A	Brick Wall		Non Suspect ACM	600	SF	0	SF				N/A	N/A	N/A
1	1	Classroom 103A	N/A	Plaster Walls		NAD	600	SF	0	SF				N/A	N/A	N/A
1	1	Classroom 103A	T	Pipe Insulation 2-6 inch	8120/01/01/13	Confirmed	60	LF	0	LF				1	No	1/D
1	1	Classroom 103A	M	Blackboard Glue Dots	8120/01/01/SYN/BB/2600	Assumed	32	SF	0	SF		Assumed Present behind Blackboards/Tackboards		1	No	1/D
1	1	Building Engineer's Office	N/A	Cement Floor		Non Suspect ACM	108	SF	0	SF		Open to South Fan Room # 1		N/A	N/A	N/A
1	1	Building Engineer's Office	N/A	Concrete Ceiling		Non Suspect ACM	108	SF	0	SF				N/A	N/A	N/A
1	1	Building Engineer's Office	N/A	Brick Wall		Non Suspect ACM	250	SF	0	SF				N/A	N/A	N/A
1	1	Building Engineer's Office	T	Pipe Insulation 2-6 inch	8120/01/01/13	Confirmed	30	LF	0	LF				1	No	1/D
1	1	Building Engineer's Office	T	Pipe Fitting Insulation	8120/01/01/15	Confirmed	18	EA	0	EA				1	No	1/D
1	1	Building Engineer's Office Restroom	M	Floor Tile VAT 12" x 12"	8120/01/01/HH	Assumed	30	SF	0	SF	x			1	No	1/D
1	1	Building Engineer's Office Restroom	N/A	Granite Walls		Non Suspect ACM	60	SF	X	SF		Glue Dots Assumed Present behind Granite Walls		N/A	N/A	N/A
1	1	Building Engineer's Office Restroom	N/A	Brick Wall		Non Suspect ACM	90	SF	X	SF				N/A	N/A	N/A
1	1	Building Engineer's Office Restroom	N/A	Sheetrock Wall		Non Suspect ACM	40	SF	X	SF				N/A	N/A	N/A
1	1	Building Engineer's Office Restroom	N/A	Concrete Ceiling		Non Suspect ACM	30	SF	X	SF				N/A	N/A	N/A
1	1	Building Engineer's Office Restroom	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	6	LF	X	LF				N/A	N/A	N/A
1	1	Girl's Cafeteria	M	Floor Tile VAT 9" x 9"	8120/01/01/12	Confirmed	2240	SF	0	SF	Green			1	No	1/D
1	1	Girl's Cafeteria	M	Ceiling Tile 1' x 1'	8120/01/01/SYN/BB/1714	Assumed	2240	SF	0	SF		1' x 1' Metal Ceiling - ACM backing assumed present		1	No	1/D
1	1	Girl's Cafeteria	N/A	Brick Wall		Non Suspect ACM	1200	SF	0	SF				N/A	N/A	N/A
1	1	Girl's Cafeteria	N/A	Plaster Walls		NAD	1200	SF	0	SF				N/A	N/A	N/A
1	1	Auditorium	N/A	Wood Floor		Non Suspect ACM	5600	SF	0	SF				N/A	N/A	N/A
1	1	Auditorium	N/A	Acoustical Plaster Ceiling		NAD	5600	SF	0	SF				N/A	N/A	N/A
1	1	Auditorium	N/A	Acoustical Plaster Walls		NAD	9000	SF	0	SF				N/A	N/A	N/A
1	1	Auditorium	T	Radiator Insulation	8120/01/01/SYN/BB/1600	Assumed	240	SF	0	SF		6 Recessed Radiators - 40 SF Each		1	No	1/D
1	1	Auditorium	N/A	Wood Floor		Non Suspect ACM	609	SF	0	SF				N/A	N/A	N/A
1	1	Auditorium	N/A	Acoustical Plaster Ceiling		NAD	609	SF	0	SF				N/A	N/A	N/A
1	1	Auditorium	N/A	Acoustical Plaster Walls		NAD	1200	SF	0	SF				N/A	N/A	N/A
1	1	Girl's Restroom across from Classroom 108A	N/A	Cement Floor		Non Suspect ACM	264	SF	0	SF				N/A	N/A	N/A
1	1	Girl's Restroom across from Classroom 108A	N/A	Plaster Ceiling		NAD	264	SF	0	SF				N/A	N/A	N/A
1	1	Girl's Restroom across from Classroom 108A	N/A	Plaster Walls		NAD	500	SF	0	SF				N/A	N/A	N/A
1	1	Girl's Restroom across from Classroom 108A	N/A	Fiberglass Pipe Fitting Insulation		Non Suspect ACM	5	LF	0	LF				N/A	N/A	N/A
1	1	Custodial Closet next to Girl's Restroom across from Classroom 108A	N/A	Cement Floor		Non Suspect ACM	25	SF	X	SF				N/A	N/A	N/A
1	1	Custodial Closet next to Girl's Restroom across from Classroom 108A	N/A	Plaster Walls		NAD	70	SF	X	SF				N/A	N/A	N/A
1	1	Custodial Closet next to Girl's Restroom across from Classroom 108A	N/A	Plaster Ceiling		NAD	25	SF	X	SF				N/A	N/A	N/A
1	1	Custodial Closet next to Girl's Restroom across from Classroom 108A	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	60	LF	X	LF				N/A	N/A	N/A
1	1	Custodial Closet next to Girl's Restroom across from Classroom 108A	T	Pipe Fitting Insulation	8120/01/01/15	Confirmed	5	EA	0	EA				1	No	1/D
1	1	Pipe Chase - Girl's Restroom across from Classroom 108A	N/A	Cement Floor		Non Suspect ACM	60	SF	X	SF		Pipe Chase Access is in the Janitor's Closet beside the Girl's Restroom across from Classroom 108A		N/A	N/A	N/A
1	1	Pipe Chase - Girl's Restroom across from Classroom 108A	N/A	Concrete Block Wall		Non Suspect ACM	180	SF	X	SF				N/A	N/A	N/A
1	1	Pipe Chase - Girl's Restroom across from Classroom 108A	N/A	Concrete Ceiling		Non Suspect ACM	60	SF	X	SF				N/A	N/A	N/A
1	1	Pipe Chase - Girl's Restroom across from Classroom 108A	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	25	LF	X	LF				N/A	N/A	N/A
1	1	Pipe Chase - Girl's Restroom across from Classroom 108A	M	Transite Sills	8120/01/01/14	Assumed	10	SF	0	SF		Transite Shelf inside Pipe Chase		1	No	1/D
1	1	Closet between Custodial Closet and Stairwell across from Classroom 108A	N/A	Cement Floor		Non Suspect ACM	12	SF	X	SF		No TSI identified		N/A	N/A	N/A
1	1	Closet between Custodial Closet and Stairwell across from Classroom 108A	N/A	Plaster Walls		NAD	30	SF	X	SF				N/A	N/A	N/A
1	1	Closet between Custodial Closet and Stairwell across from Classroom 108A	N/A	Plaster Ceiling		NAD	12	SF	X	SF				N/A	N/A	N/A
1	1	Boy's Cafeteria	M	Floor Tile VAT 9" x 9"	8120/01/01/12	Confirmed	2240	SF	0	SF	Green			1	No	1/D
1	1	Boy's Cafeteria	M	Ceiling Tile 1' x 1'	8120/01/01/SYN/BB/1714	Assumed	2240	SF	0	SF		1' x 1' Metal Ceiling - ACM backing assumed present		1	No	1/D

8120 Woodrow Wilson MS 2015 2016 AHERA Three-Year Report.xls

School District of Philadelphia Woodrow Wilson Middle School 1800 Cottman Ave, Philadelphia, PA 19111 ULCS# 8120 Year Built: 1928			AHERA Three-Year Reinspection 2015-2016 Room by Room Location Log Report									Reinspection Date: December 3, 2015 Building Inspector: Norman Harrison Number: 037951 Management Planner: Megan Vala Number: 740728				
E l e m e n t	F l o o r	On Site Room Name	System Affected	Material Description	HID#	Confirmed/Assumed/NAD/ Non Suspect ACM	Amount of Material	SF LF EA	Amount of Damage	SF LF EA	Color required for VAT	Comments/Description/Notes	Attic/ Crawl Space Ranking	Damage Potential (DP)	Newly Friable (NF)	Response Action (RA)
1	1	Boy's Cafeteria	N/A	Brick Wall		Non Suspect ACM	1200	SF	0	SF				N/A	N/A	N/A
1	1	Boy's Cafeteria	N/A	Plaster Walls		NAD	1200	SF	0	SF				N/A	N/A	N/A
1	1	Administrative Office 116	M	Floor Tile VAT 12" x 12"	8120/01/01/HH	Assumed	700	SF	0	SF	Grey			1	No	1/D
1	1	Administrative Office 116	N/A	Plaster Walls		NAD	2800	SF	0	SF				N/A	N/A	N/A
1	1	Administrative Office 116	N/A	Ceiling Tile 2' x 4'		Non Suspect ACM	700	SF	0	SF				N/A	N/A	N/A
1	1	Administrative Office 116	T	Pipe Insulation 2-6 inch	8120/01/01/13	Confirmed	72	LF	0	LF				1	No	1/D
1	1	Administrative Office 116	T	Pipe Fitting Insulation	8120/01/01/15	Confirmed	6	EA	0	EA				1	No	1/D
1	1	Administrative Office 116	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	32	LF	0	LF				N/A	N/A	N/A
1	1	Kitchen	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	101	LF	X	LF				N/A	N/A	N/A
1	1	Kitchen	N/A	Fiberglass Pipe Fitting Insulation		Non Suspect ACM	101	EA	X	EA				N/A	N/A	N/A
1	1	Kitchen	N/A	Ceramic Tile Floors		Non Suspect ACM	1216	SF	X	SF				N/A	N/A	N/A
1	1	Kitchen	N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	1216	SF	X	SF				N/A	N/A	N/A
1	1	Kitchen	N/A	Brick Wall		Non Suspect ACM	1500	SF	X	SF				N/A	N/A	N/A
1	1	Office 112	M	Floor Tile VAT 9" x 9"	8120/01/01/12	Confirmed	700	SF	0	SF	Tan			1	No	1/D
1	1	Office 112	N/A	Brick Wall		Non Suspect ACM	2100	SF	0	SF				N/A	N/A	N/A
1	1	Office 112	N/A	Ceiling Tile 2' x 4'		Non Suspect ACM	700	SF	0	SF				N/A	N/A	N/A
1	1	Office 112	T	Pipe Insulation 2-6 inch	8120/01/01/13	Confirmed	48	LF	0	LF				1	No	1/D
1	1	Office 112	T	Pipe Fitting Insulation	8120/01/01/15	Confirmed	3	EA	0	EA				1	No	1/D
1	1	Office 112	M	Blackboard Glue Dots	8120/01/01/SYN/BB/2600	Assumed	100	SF	0	SF		Assumed Present behind Blackboards/Tackboards		1	No	1/D
1	1	Office 114	M	Floor Tile VAT 9" x 9"	8120/01/01/12	Confirmed	400	SF	0	SF	Tan			1	No	1/D
1	1	Office 114	N/A	Brick Wall		Non Suspect ACM	1200	SF	0	SF				N/A	N/A	N/A
1	1	Office 114	N/A	Ceiling Tile 2' x 4'		Non Suspect ACM	400	SF	0	SF				N/A	N/A	N/A
1	1	Office 114	T	Pipe Insulation 2-6 inch	8120/01/01/13	Confirmed	24	LF	0	LF				1	No	1/D
1	1	Office 114	M	Blackboard Glue Dots	8120/01/01/SYN/BB/2600	Assumed	100	SF	0	SF		Assumed Present behind Blackboards/Tackboards		1	No	1/D
1	1	Boy's Restroom	N/A	Cement Floor		Non Suspect ACM	250	SF	0	SF				N/A	N/A	N/A
1	1	Boy's Restroom	N/A	Plaster Walls		NAD	750	SF	20	SF		Loose/Flaking Paint		N/A	N/A	N/A
1	1	Boy's Restroom	N/A	Concrete Ceiling		Non Suspect ACM	250	SF	10	SF		Loose/Flaking Paint		N/A	N/A	N/A
1	1	Boy's Restroom	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	15	LF	0	LF				N/A	N/A	N/A
1	1	Custodial Closet next to Boy's Restroom across from Classroom 101	N/A	Cement Floor		Non Suspect ACM	25	SF	X	SF				N/A	N/A	N/A
1	1	Custodial Closet next to Boy's Restroom across from Classroom 101	N/A	Plaster Walls		NAD	70	SF	X	SF				N/A	N/A	N/A
1	1	Custodial Closet next to Boy's Restroom across from Classroom 101	N/A	Plaster Ceiling		NAD	25	SF	X	SF				N/A	N/A	N/A
1	1	Custodial Closet next to Boy's Restroom across from Classroom 101	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	60	LF	X	LF				N/A	N/A	N/A
1	1	Custodial Closet next to Boy's Restroom across from Classroom 101	T	Pipe Fitting Insulation	8120/01/01/15	Confirmed	4	EA	0	EA				1	No	1/D
1	1	Pipe Chase - Boy's Restroom across from Classroom 101	N/A	Cement Floor		Non Suspect ACM	60	SF	X	SF		Pipe Chase Access is in the Janitor's Closet beside the Boy's Restroom across from Classroom 101		N/A	N/A	N/A
1	1	Pipe Chase - Boy's Restroom across from Classroom 101	N/A	Concrete Block Wall		Non Suspect ACM	180	SF	X	SF				N/A	N/A	N/A
1	1	Pipe Chase - Boy's Restroom across from Classroom 101	N/A	Concrete Ceiling		Non Suspect ACM	60	SF	X	SF				N/A	N/A	N/A
1	1	Pipe Chase - Boy's Restroom across from Classroom 101	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	25	LF	X	LF				N/A	N/A	N/A
1	1	Pipe Chase - Boy's Restroom across from Classroom 101	M	Transite Sills	8120/01/01/14	Assumed	20	SF	0	SF		Fixed Transite Shelf and Loose Transite Shelf inside Pipe Chase		1	No	1/D
1	1	Closet between Custodial Closet and Stairwell across from Classroom 101	N/A	Cement Floor		Non Suspect ACM	12	SF	X	SF		No TSI identified		N/A	N/A	N/A
1	1	Closet between Custodial Closet and Stairwell across from Classroom 101	N/A	Plaster Walls		NAD	30	SF	X	SF				N/A	N/A	N/A
1	1	Closet between Custodial Closet and Stairwell across from Classroom 101	N/A	Plaster Ceiling		NAD	12	SF	X	SF				N/A	N/A	N/A
1	1	Classroom 110 across from Classroom 108	M	Floor Tile VAT 9" x 9"	8120/01/01/12	Confirmed	800	SF	0	SF	Green			1	No	1/D
1	1	Classroom 110 across from Classroom 108	N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	800	SF	0	SF				N/A	N/A	N/A
1	1	Classroom 110 across from Classroom 108	N/A	Brick Wall		Non Suspect ACM	1000	SF	0	SF				N/A	N/A	N/A
1	1	Classroom 110 across from Classroom 108	N/A	Plaster Walls		NAD	1000	SF	0	SF				N/A	N/A	N/A
1	1	Classroom 110 across from Classroom 108	T	Pipe Insulation 2-6 inch	8120/01/01/13	Confirmed	50	LF	0	LF				1	No	1/D
1	1	Classroom 110 across from Classroom 108	T	Pipe Fitting Insulation	8120/01/01/15	Confirmed	4	EA	0	EA				1	No	1/D
1	1	Classroom 110 across from Classroom 108	M	Blackboard Glue Dots	8120/01/01/SYN/BB/2600	Assumed	200	SF	0	SF		Assumed Present behind Blackboards/Tackboards		1	No	1/D
1	1	Storage Room next to Girl's Restroom across from Classroom 108	N/A	Ceramic Tile Floors		Non Suspect ACM	250	SF	X	SF				N/A	N/A	N/A
1	1	Storage Room next to Girl's Restroom across from Classroom 108	N/A	Concrete Block Wall		Non Suspect ACM	300	SF	X	SF				N/A	N/A	N/A
1	1	Storage Room next to Girl's Restroom across from Classroom 108	N/A	Plaster Walls		NAD	300	SF	X	SF				N/A	N/A	N/A
1	1	Storage Room next to Girl's Restroom across from Classroom 108	N/A	Plaster Ceiling		NAD	250	SF	X	SF				N/A	N/A	N/A
1	1	Storage Room next to Girl's Restroom across from Classroom 108	T	Pipe Insulation 2-6 inch	8120/01/01/13	Confirmed	40	LF	0	LF				1	No	1/D
1	1	Storage Room next to Girl's Restroom across from Classroom 108	T	Pipe Fitting Insulation	8120/01/01/15	Confirmed	6	EA	0	EA				1	No	1/D
1	1	Classroom 126	M	Floor Tile VAT 9" x 9"	8120/01/01/12	Confirmed	391	SF	0	SF	Multi			1	No	1/D
1	1	Classroom 126	N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	391	SF	0	SF				N/A	N/A	N/A
1	1	Classroom 126	N/A	Brick Wall		Non Suspect ACM	300	SF	0	SF				N/A	N/A	N/A
1	1	Classroom 126	N/A	Plaster Walls		NAD	300	SF	0	SF				N/A	N/A	N/A

8120 Woodrow Wilson MS 2015 2016 AHERA Three-Year Report.xls

School District of Philadelphia Woodrow Wilson Middle School 1800 Cottman Ave, Philadelphia, PA 19111 ULCS# 8120 Year Built: 1928			AHERA Three-Year Reinspection 2015-2016 Room by Room Location Log Report										Reinspection Date: December 3, 2015 Building Inspector: Norman Harrison Number: 037951 Management Planner: Megan Vala Number: 740728			
E l e m e n t	F l o o r	On Site Room Name	System Affected	Material Description	HID#	Confirmed/Assumed/NAD/ Non Suspect ACM	Amount of Material	SF LF EA	Amount of Damage	SF LF EA	Color required for VAT	Comments/Description/Notes	Attic/ Crawl Space Ranking	Damage Potential (DP)	Newly Friable (NF)	Response Action (RA)
1	1	Classroom 126	T	Pipe Insulation 2-6 inch	8120/01/01/13	Confirmed	40	LF	0	LF				1	No	1/D
1	1	Classroom 126	T	Pipe Fitting Insulation	8120/01/01/15	Confirmed	3	EA	0	EA				1	No	1/D
1	1	Classroom 108	M	Floor Tile VAT 9" x 9"	8120/01/01/12	Confirmed	1080	SF	0	SF	Green			1	No	1/D
1	1	Classroom 108	N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	1080	SF	0	SF				N/A	N/A	N/A
1	1	Classroom 108	N/A	Brick Wall		Non Suspect ACM	600	SF	0	SF				N/A	N/A	N/A
1	1	Classroom 108	N/A	Plaster Walls		NAD	600	SF	0	SF				N/A	N/A	N/A
1	1	Classroom 108	T	Pipe Insulation 2-6 inch	8120/01/01/13	Confirmed	50	LF	0	LF				1	No	1/D
1	1	Classroom 108	T	Pipe Fitting Insulation	8120/01/01/15	Confirmed	3	EA	0	EA				1	No	1/D
1	1	Classroom 107	M	Floor Tile VAT 9" x 9"	8120/01/01/12	Confirmed	600	SF	0	SF	Green			1	No	1/D
1	1	Classroom 107	N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	600	SF	0	SF				N/A	N/A	N/A
1	1	Classroom 107	N/A	Brick Wall		Non Suspect ACM	600	SF	0	SF				N/A	N/A	N/A
1	1	Classroom 107	N/A	Plaster Walls		NAD	600	SF	0	SF				N/A	N/A	N/A
1	1	Classroom 107	T	Pipe Insulation 2-6 inch	8120/01/01/13	Confirmed	25	LF	0	LF				1	No	1/D
1	1	Classroom 107	T	Pipe Fitting Insulation	8120/01/01/15	Confirmed	2	EA	0	EA				1	No	1/D
1	1	Classroom 106	M	Floor Tile VAT 9" x 9"	8120/01/01/12	Confirmed	1080	SF	0	SF	Green			1	No	1/D
1	1	Classroom 106	N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	1080	SF	0	SF				N/A	N/A	N/A
1	1	Classroom 106	N/A	Brick Wall		Non Suspect ACM	600	SF	0	SF				N/A	N/A	N/A
1	1	Classroom 106	N/A	Plaster Walls		NAD	600	SF	0	SF				N/A	N/A	N/A
1	1	Classroom 106	T	Pipe Insulation 2-6 inch	8120/01/01/13	Confirmed	50	LF	0	LF				1	No	1/D
1	1	Classroom 106	T	Pipe Fitting Insulation	8120/01/01/15	Confirmed	3	EA	0	EA				1	No	1/D
1	1	Classroom 105	M	Floor Tile VAT 9" x 9"	8120/01/01/12	Confirmed	1080	SF	0	SF	Green			1	No	1/D
1	1	Classroom 105	N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	1080	SF	0	SF				N/A	N/A	N/A
1	1	Classroom 105	N/A	Brick Wall		Non Suspect ACM	600	SF	0	SF				N/A	N/A	N/A
1	1	Classroom 105	N/A	Plaster Walls		NAD	600	SF	0	SF				N/A	N/A	N/A
1	1	Classroom 105	T	Pipe Insulation 2-6 inch	8120/01/01/13	Confirmed	70	LF	0	LF				1	No	1/D
1	1	Classroom 105	T	Pipe Fitting Insulation	8120/01/01/15	Confirmed	4	EA	0	EA				1	No	1/D
1	1	Classroom 104A	M	Floor Tile VAT 12" x 12"	8120/01/01/HH	Assumed	600	SF	0	SF	White			1	No	1/D
1	1	Classroom 104A	N/A	Brick Wall		Non Suspect ACM	600	SF	0	SF				N/A	N/A	N/A
1	1	Classroom 104A	N/A	Plaster Walls		NAD	600	SF	0	SF				N/A	N/A	N/A
1	1	Classroom 104A	N/A	Sheetrock Wall		Non Suspect ACM	250	SF	0	SF				N/A	N/A	N/A
1	1	Classroom 104A	N/A	Ceiling Tile 2' x 4'		Non Suspect ACM	600	SF	0	SF				N/A	N/A	N/A
1	1	Classroom 104A	T	Pipe Insulation 2-6 inch	8120/01/01/13	Confirmed	36	LF	0	LF				1	No	1/D
1	1	Classroom 104A	M	Blackboard Glue Dots	8120/01/01/SYN/BB/2600	Assumed	64	SF	0	SF		Assumed Present behind Blackboards/Tackboards		1	No	1/D
1	1	Classroom 104A Window Wall Closet	M	Floor Tile VAT 12" x 12"	8120/01/01/HH	Assumed	80	SF	0	SF	White			1	No	1/D
1	1	Classroom 104A Window Wall Closet	N/A	Brick Wall		Non Suspect ACM	80	SF	0	SF				N/A	N/A	N/A
1	1	Classroom 104A Window Wall Closet	N/A	Plaster Walls		NAD	160	SF	0	SF				N/A	N/A	N/A
1	1	Classroom 104A Window Wall Closet	N/A	Ceiling Tile 2' x 4'		Non Suspect ACM	80	SF	0	SF				N/A	N/A	N/A
1	1	Classroom 104A Window Wall Closet	T	Pipe Insulation 2-6 inch	8120/01/01/13	Confirmed	12	LF	0	LF				1	No	1/D
1	1	Classroom 104A Window Wall Closet	T	Pipe Fitting Insulation	8120/01/01/15	Confirmed	1	EA	0	EA				1	No	1/D
1	1	Classroom 104A Hallway Wall Closet	M	Floor Tile VAT 12" x 12"	8120/01/01/HH	Assumed	160	SF	0	SF	White			1	No	1/D
1	1	Classroom 104A Hallway Wall Closet	N/A	Plaster Walls		NAD	480	SF	0	SF				N/A	N/A	N/A
1	1	Classroom 104A Hallway Wall Closet	N/A	Ceiling Tile 2' x 4'		Non Suspect ACM	160	SF	0	SF				N/A	N/A	N/A
1	1	Classroom 104B	M	Floor Tile VAT 12" x 12"	8120/01/01/HH	Assumed	700	SF	0	SF	White			1	No	1/D
1	1	Classroom 104B	N/A	Brick Wall		Non Suspect ACM	700	SF	0	SF				N/A	N/A	N/A
1	1	Classroom 104B	N/A	Plaster Walls		NAD	700	SF	0	SF				N/A	N/A	N/A
1	1	Classroom 104B	N/A	Sheetrock Wall		Non Suspect ACM	250	SF	0	SF				N/A	N/A	N/A
1	1	Classroom 104B	N/A	Ceiling Tile 2' x 4'		Non Suspect ACM	700	SF	0	SF				N/A	N/A	N/A
1	1	Classroom 104B	T	Pipe Insulation 2-6 inch	8120/01/01/13	Confirmed	36	LF	0	LF				1	No	1/D
1	1	Classroom 104B	M	Blackboard Glue Dots	8120/01/01/SYN/BB/2600	Assumed	200	SF	0	SF		Assumed Present behind Blackboards/Tackboards		1	No	1/D
1	1	Foyer outside of Classrooms 104A & 104B	M	Floor Tile VAT 12" x 12"	8120/01/01/HH	Assumed	100	SF	0	SF	White			1	No	1/D
1	1	Foyer outside of Classrooms 104A & 104B	N/A	Sheetrock Wall		Non Suspect ACM	200	SF	0	SF				N/A	N/A	N/A
1	1	Foyer outside of Classrooms 104A & 104B	N/A	Ceiling Tile 2' x 4'		Non Suspect ACM	100	SF	0	SF				N/A	N/A	N/A
1	1	Classroom 102 (Art)	M	Floor Tile VAT 12" x 12"	8120/01/01/HH	Assumed	864	SF	0	SF				1	No	1/D
1	1	Classroom 102 (Art)	N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	864	SF	0	SF				N/A	N/A	N/A
1	1	Classroom 102 (Art)	T	Pipe Insulation 2-6 inch	8120/01/01/13	Confirmed	20	LF	0	LF				1	No	1/D
1	1	Classroom 102 (Art)	M	Blackboard Glue Dots	8120/01/01/SYN/BB/2600	Assumed	200	SF	0	SF		Assumed Present behind Blackboards/Tackboards		1	No	1/D
1	1	Classroom 102 Storage Room	M	Floor Tile VAT 12" x 12"	8120/01/01/HH	Assumed	100	SF	0	SF				1	No	1/D
1	1	Classroom 102 Storage Room	N/A	Brick Wall		Non Suspect ACM	100	SF	X	SF				N/A	N/A	N/A
1	1	Classroom 102 Storage Room	N/A	Plaster Walls		NAD	100	SF	X	SF				N/A	N/A	N/A
1	1	Classroom 102 Storage Room	N/A	Plaster Ceiling		NAD	100	SF	X	SF				N/A	N/A	N/A
1	1	Classroom 102 Storage Room	M	Kiln	8120/01/01/SYN/BB/1650	Assumed	1	EA	0	EA				1	No	1/D
1	1	Classroom 102 Storage Room	T	Pipe Insulation 2-6 inch	8120/01/01/13	Confirmed	15	LF	0	LF				1	No	1/D
1	1	Classroom 102 Storage Room	T	Pipe Fitting Insulation	8120/01/01/15	Confirmed	6	EA	0	EA				1	No	1/D
1	1	Classroom 101 (Art)	M	Floor Tile VAT 12" x 12"	8120/01/01/HH	Assumed	1104	SF	0	SF	Tan			1	No	1/D
1	1	Classroom 101 (Art)	N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	1104	SF	0	SF				N/A	N/A	N/A
1	1	Classroom 101 (Art)	T	Pipe Insulation 2-6 inch	8120/01/01/13	Confirmed	60	LF	0	LF				1	No	1/D
1	1	Classroom 101 (Art)	M	Blackboard Glue Dots	8120/01/01/SYN/BB/2600	Assumed	200	SF	0	SF		Assumed Present behind Blackboards/Tackboards		1	No	1/D
1	1	Classroom 101 (Art)	N/A	Brick Wall		Non Suspect ACM	200	SF	0	SF				N/A	N/A	N/A
1	1	Classroom 101 (Art)	N/A	Plaster Walls		NAD	2500	SF	0	SF				N/A	N/A	N/A
1	1	Classroom 101 Storage Room	N/A	Wood Floor		Non Suspect ACM	100	SF	X	SF		No TSI identified		N/A	N/A	N/A
1	1	Classroom 101 Storage Room	N/A	Brick Wall		Non Suspect ACM	250	SF	X	SF				N/A	N/A	N/A
1	1	Classroom 101 Storage Room	N/A	Plaster Ceiling		NAD	100	SF	X	SF				N/A	N/A	N/A
1	1	Cleaning Staff Office next to North Fan Room and Staff Parking Lot	N/A	Cement Floor		Non Suspect ACM	150	SF	0	SF		Open to North Fan Room # 2		N/A	N/A	N/A

8120 Woodrow Wilson MS 2015 2016 AHERA Three-Year Report.xls

School District of Philadelphia Woodrow Wilson Middle School 1800 Cottman Ave, Philadelphia, PA 19111 ULCS# 8120 Year Built: 1928			AHERA Three-Year Reinspection 2015-2016 Room by Room Location Log Report										Reinspection Date: December 3, 2015 Building Inspector: Norman Harrison Number: 037951 Management Planner: Megan Vala Number: 740728			
E l e m e n t	F l o o r	On Site Room Name	System Affected	Material Description	HID#	Confirmed/Assumed/NAD/ Non Suspect ACM	Amount of Material	SF LF EA	Amount of Damage	SF LF EA	Color required for VAT	Comments/Description/Notes	Attic/ Crawl Space Ranking	Damage Potential (DP)	Newly Friable (NF)	Response Action (RA)
1	1	Cleaning Staff Office next to North Fan Room and Staff Parking Lot	N/A	Brick Wall		Non Suspect ACM	450	SF	0	SF				N/A	N/A	N/A
1	1	Cleaning Staff Office next to North Fan Room and Staff Parking Lot	N/A	Sheetrock Wall		Non Suspect ACM	30	SF	0	SF				N/A	N/A	N/A
1	1	Cleaning Staff Office next to North Fan Room and Staff Parking Lot	N/A	Concrete Ceiling		Non Suspect ACM	150	SF	0	SF				N/A	N/A	N/A
1	1	Cleaning Staff Office next to North Fan Room and Staff Parking Lot	T	Pipe Insulation 2-6 inch	8120/01/01/13	Confirmed	30	LF	0	LF				1	No	1/D
1	1	Cleaning Staff Office next to North Fan Room and Staff Parking Lot	T	Pipe Fitting Insulation	8120/01/01/15	Confirmed	18	EA	0	EA				1	No	1/D
1	1	Cleaning Staff Office next to North Fan Room and Staff Parking Lot	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	20	LF	0	LF				N/A	N/A	N/A
1	1	Cleaning Staff Office Restroom next to North Fan Room and Staff Parking Lot	M	Floor Tile VAT 12" x 12"	8120/01/01/HH	Assumed	30	SF	0	SF	White			1	No	1/D
1	1	Cleaning Staff Office Restroom next to North Fan Room and Staff Parking Lot	N/A	Brick Wall		Non Suspect ACM	60	SF	0	SF				N/A	N/A	N/A
1	1	Cleaning Staff Office Restroom next to North Fan Room and Staff Parking Lot	N/A	Sheetrock Wall		Non Suspect ACM	30	SF	0	SF				N/A	N/A	N/A
1	1	Cleaning Staff Office Restroom next to North Fan Room and Staff Parking Lot	N/A	Concrete Ceiling		Non Suspect ACM	30	SF	0	SF				N/A	N/A	N/A
1	1	Cleaning Staff Office Restroom next to North Fan Room and Staff Parking Lot	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	4	LF	0	LF				N/A	N/A	N/A
1	1	Hallway outside Classrooms 101 - 102	N/A	Cement Floor		Non Suspect ACM	1000	SF	0	SF				N/A	N/A	N/A
1	1	Hallway outside Classrooms 101 - 102	N/A	Granite Walls		Non Suspect ACM	1500	SF	0	SF		Glue Dots Assumed Present behind Granite Walls		N/A	N/A	N/A
1	1	Hallway outside Classrooms 101 - 102	N/A	Plaster Walls		NAD	3000	SF	0	SF				N/A	N/A	N/A
1	1	Hallway outside Classrooms 101 - 102	M	Transite Electrical Panel	8120/01/01/SYN/BB/2350	Assumed	12	SF	0	SF		Between Classroom 101 & 102		1	No	1/D
1	1	Hallway outside Classrooms 101 - 102	N/A	Ceiling Tile 2' x 4'		Non Suspect ACM	1000	SF	0	SF				N/A	N/A	N/A
1	1	Hallway outside Classrooms 103 - 104	N/A	Cement Floor		Non Suspect ACM	1000	SF	0	SF				N/A	N/A	N/A
1	1	Hallway outside Classrooms 103 - 104	N/A	Granite Walls		Non Suspect ACM	1500	SF	0	SF		Glue Dots Assumed Present behind Granite Walls		N/A	N/A	N/A
1	1	Hallway outside Classrooms 103 - 104	N/A	Plaster Walls		NAD	3000	SF	0	SF				N/A	N/A	N/A
1	1	Hallway outside Classrooms 103 - 104	N/A	Ceiling Tile 2' x 4'		Non Suspect ACM	1000	SF	0	SF				N/A	N/A	N/A
1	1	Hallway outside Classrooms 103 - 104	T	Pipe Insulation 2-6 inch	8120/01/01/13	Confirmed	62	LF	0	LF				1	No	1/D
1	1	Hallway outside Classrooms 103 - 104	T	Pipe Fitting Insulation	8120/01/01/15	Confirmed	4	EA	0	EA				1	No	1/D
1	1	Hallway outside Classrooms 103 - 104	M	Transite Electrical Panel	8120/01/01/SYN/BB/2350	Assumed	12	SF	0	SF		Outside Classroom 103A		1	No	1/D
1	1	Grand Entrance Foyer Hallway	N/A	Granite Floor		Non Suspect ACM	4000	SF	0	SF				N/A	N/A	N/A
1	1	Grand Entrance Foyer Hallway	N/A	Granite Walls		Non Suspect ACM	12000	SF	0	SF		Glue Dots Assumed Present behind Granite Walls		N/A	N/A	N/A
1	1	Grand Entrance Foyer Hallway	N/A	Plaster Walls		NAD	2000	SF	0	SF				N/A	N/A	N/A
1	1	Grand Entrance Foyer Hallway	N/A	Plaster Ceiling		NAD	4000	SF	0	SF				N/A	N/A	N/A
1	1	Grand Entrance Foyer Hallway	T	Radiator Insulation	8120/01/01/SYN/BB/1600	Assumed	132	SF	0	SF		4 Recessed Radiators at 25 SF Each, 2 Recessed Radiators at 16 SF Each - 132 SF total		1	No	1/D
1	1	Women's Staff Restroom in Grand Entrance Foyer	M	Floor Tile VAT 12" x 12"	8120/01/01/HH	Assumed	300	SF	0	SF				1	No	1/D
1	1	Women's Staff Restroom in Grand Entrance Foyer	N/A	Granite Walls		Non Suspect ACM	400	SF	X	SF		Glue Dots Assumed Present behind Granite Walls		N/A	N/A	N/A
1	1	Women's Staff Restroom in Grand Entrance Foyer	N/A	Plaster Walls		NAD	400	SF	X	SF				N/A	N/A	N/A
1	1	Women's Staff Restroom in Grand Entrance Foyer	N/A	Plaster Ceiling		NAD	300	SF	X	SF				N/A	N/A	N/A
1	1	Women's Staff Restroom in Grand Entrance Foyer	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	100	LF	X	LF				N/A	N/A	N/A
1	1	Women's Staff Restroom in Grand Entrance Foyer	M	Sink Undercoat Mastic	8120/01/01/SYN/BB/2602	Assumed	18	SF	0	SF		3 Sinks - 6 SF Each		1	No	1/D
1	1	Storage Room next to Women's Staff Restroom in Grand Entrance Foyer	N/A	Cement Floor		Non Suspect ACM	100	SF	X	SF				N/A	N/A	N/A
1	1	Storage Room next to Women's Staff Restroom in Grand Entrance Foyer	N/A	Plaster Walls		NAD	250	SF	X	SF				N/A	N/A	N/A
1	1	Storage Room next to Women's Staff Restroom in Grand Entrance Foyer	N/A	Plaster Ceiling		NAD	100	SF	X	SF				N/A	N/A	N/A
1	1	Storage Room next to Women's Staff Restroom in Grand Entrance Foyer	T	Pipe Insulation 2-6 inch	8120/01/01/13	Confirmed	11	LF	0	LF				1	No	1/D
1	1	Storage Room next to Women's Staff Restroom in Grand Entrance Foyer	T	Pipe Fitting Insulation	8120/01/01/15	Confirmed	2	EA	0	EA				1	No	1/D
1	1	Men's Staff Restroom in Grand Entrance Foyer	M	Floor Tile VAT 12" x 12"	8120/01/01/HH	Assumed	200	SF	0	SF				1	No	1/D
1	1	Men's Staff Restroom in Grand Entrance Foyer	N/A	Granite Walls		Non Suspect ACM	250	SF	X	SF		Glue Dots Assumed Present behind Granite Walls		N/A	N/A	N/A
1	1	Men's Staff Restroom in Grand Entrance Foyer	N/A	Plaster Walls		NAD	250	SF	X	SF				N/A	N/A	N/A
1	1	Men's Staff Restroom in Grand Entrance Foyer	N/A	Plaster Ceiling		NAD	200	SF	X	SF				N/A	N/A	N/A
1	1	Men's Staff Restroom in Grand Entrance Foyer	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	80	LF	X	LF				N/A	N/A	N/A
1	1	Men's Staff Restroom in Grand Entrance Foyer	M	Sink Undercoat Mastic	8120/01/01/SYN/BB/2602	Assumed	12	SF	0	SF		2 Sinks - 6 SF Each		1	No	1/D
1	1	Storage Room next to Men's Staff Restroom in Grand Entrance Foyer	N/A	Cement Floor		Non Suspect ACM	100	SF	X	SF				N/A	N/A	N/A
1	1	Storage Room next to Men's Staff Restroom in Grand Entrance Foyer	N/A	Plaster Walls		NAD	250	SF	X	SF				N/A	N/A	N/A
1	1	Storage Room next to Men's Staff Restroom in Grand Entrance Foyer	N/A	Plaster Ceiling		NAD	100	SF	X	SF				N/A	N/A	N/A
1	1	Storage Room next to Men's Staff Restroom in Grand Entrance Foyer	T	Pipe Insulation 2-6 inch	8120/01/01/13	Confirmed	17	LF	0	LF				1	No	1/D
1	1	Storage Room next to Men's Staff Restroom in Grand Entrance Foyer	T	Pipe Fitting Insulation	8120/01/01/15	Confirmed	2	EA	0	EA				1	No	1/D
1	1	Hallway outside Classroom 105 to Office 116	N/A	Cement Floor		Non Suspect ACM	1000	SF	0	SF				N/A	N/A	N/A
1	1	Hallway outside Classroom 105 to Office 116	N/A	Granite Walls		Non Suspect ACM	1500	SF	0	SF		Glue Dots Assumed Present behind Granite Walls		N/A	N/A	N/A
1	1	Hallway outside Classroom 105 to Office 116	N/A	Plaster Walls		NAD	3000	SF	0	SF				N/A	N/A	N/A
1	1	Hallway outside Classroom 105 to Office 116	N/A	Plaster Ceiling		NAD	250	SF	0	SF		Exposed Plaster Ceiling Towards Rear Staff Parking Lot		N/A	N/A	N/A
1	1	Hallway outside Classroom 105 to Office 116	N/A	Ceiling Tile 2' x 4'		Non Suspect ACM	1000	SF	0	SF				N/A	N/A	N/A
1	1	Hallway outside Classroom 105 to Office 116	T	Pipe Insulation 2-6 inch	8120/01/01/13	Confirmed	72	LF	0	LF				1	No	1/D

8120 Woodrow Wilson MS 2015 2016 AHERA Three-Year Report.xls

School District of Philadelphia Woodrow Wilson Middle School 1800 Cottman Ave, Philadelphia, PA 19111 ULCS# 8120 Year Built: 1928			AHERA Three-Year Reinspection 2015-2016 Room by Room Location Log Report										Reinspection Date: December 3, 2015 Building Inspector: Norman Harrison Number: 037951 Management Planner: Megan Vala Number: 740728			
E l e m e n t	F l o o r	On Site Room Name	System Affected	Material Description	HID#	Confirmed/Assumed/NAD/ Non Suspect ACM	Amount of Material	SF LF EA	Amount of Damage	SF LF EA	Color required for VAT	Comments/Description/Notes	Attic/ Crawl Space Ranking	Damage Potential (DP)	Newly Friable (NF)	Response Action (RA)
1	1	Hallway outside Classroom 105 to Office 116	T	Pipe Fitting Insulation	8120/01/01/15	Confirmed	6	EA	0	EA		Towards Rear Staff Parking Lot		1	No	1/D
1	1	Hallway outside Classroom 105 to Office 116	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	50	LF	0	LF		Towards Rear Staff Parking Lot		N/A	N/A	N/A
1	1	Hallway outside Classrooms 108 - 109	N/A	Cement Floor		Non Suspect ACM	1000	SF	0	SF				N/A	N/A	N/A
1	1	Hallway outside Classrooms 108 - 109	N/A	Granite Walls		Non Suspect ACM	1500	SF	0	SF		Glue Dots Assumed Present behind Granite Walls		N/A	N/A	N/A
1	1	Hallway outside Classrooms 108 - 109	N/A	Plaster Walls		NAD	3000	SF	0	SF				N/A	N/A	N/A
1	1	Hallway outside Classrooms 108 - 109	N/A	Ceiling Tile 2' x 4'		Non Suspect ACM	1000	SF	0	SF				N/A	N/A	N/A
1	1	Hallway outside Cafeteria and Fan Rooms	N/A	Cement Floor		Non Suspect ACM	3000	SF	0	SF				N/A	N/A	N/A
1	1	Hallway outside Cafeteria and Fan Rooms	N/A	Granite Walls		Non Suspect ACM	4500	SF	0	SF		Glue Dots Assumed Present behind Granite Walls		N/A	N/A	N/A
1	1	Hallway outside Cafeteria and Fan Rooms	N/A	Plaster Walls		NAD	9000	SF	200	SF		Loose/Flaking Paint		N/A	N/A	N/A
1	1	Hallway outside Cafeteria and Fan Rooms	N/A	Plaster Ceiling		NAD	250	SF	125	SF		Exposed Plaster Ceiling Towards Rear Staff Parking Lot; Plaster Ceiling Damage		N/A	N/A	N/A
1	1	Hallway outside Cafeteria and Fan Rooms	N/A	Ceiling Tile 2' x 4'		Non Suspect ACM	3000	SF	0	SF				N/A	N/A	N/A
1	1	Hallway outside Cafeteria and Fan Rooms	T	Pipe Insulation 2-6 inch	8120/01/01/13	Confirmed	132	LF	2	LF				2	Yes	5/A
1	1	Hallway outside Cafeteria and Fan Rooms	T	Pipe Fitting Insulation	8120/01/01/15	Confirmed	7	EA	0	EA				1	No	1/D
1	1	Hallway outside Cafeteria and Fan Rooms	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	44	LF	0	LF				N/A	N/A	N/A
1	1	Stairwell next to Girl's Restroom	N/A	Cement Floor		Non Suspect ACM	300	SF	0	SF				N/A	N/A	N/A
1	1	Stairwell next to Girl's Restroom	N/A	Granite Walls		Non Suspect ACM	450	SF	0	SF		Glue Dots Assumed Present behind Granite Walls		N/A	N/A	N/A
1	1	Stairwell next to Girl's Restroom	N/A	Plaster Walls		NAD	900	SF	0	SF				N/A	N/A	N/A
1	1	Stairwell next to Girl's Restroom	N/A	Plaster Ceiling		NAD	300	SF	0	SF				N/A	N/A	N/A
1	1	Stairwell across from Classroom 108	N/A	Cement Floor		Non Suspect ACM	300	SF	0	SF				N/A	N/A	N/A
1	1	Stairwell across from Classroom 108	N/A	Granite Walls		Non Suspect ACM	450	SF	0	SF		Glue Dots Assumed Present behind Granite Walls		N/A	N/A	N/A
1	1	Stairwell across from Classroom 108	N/A	Plaster Walls		NAD	900	SF	0	SF				N/A	N/A	N/A
1	1	Stairwell across from Classroom 108	N/A	Plaster Ceiling		NAD	300	SF	0	SF				N/A	N/A	N/A
1	1	Stairwell across from Classroom 102	N/A	Cement Floor		Non Suspect ACM	300	SF	0	SF				N/A	N/A	N/A
1	1	Stairwell across from Classroom 102	N/A	Granite Walls		Non Suspect ACM	450	SF	0	SF		Glue Dots Assumed Present behind Granite Walls		N/A	N/A	N/A
1	1	Stairwell across from Classroom 102	N/A	Plaster Walls		NAD	900	SF	0	SF				N/A	N/A	N/A
1	1	Stairwell across from Classroom 102	N/A	Plaster Ceiling		NAD	300	SF	0	SF				N/A	N/A	N/A
1	1	Stairwell across from Classroom 101	N/A	Cement Floor		Non Suspect ACM	300	SF	0	SF				N/A	N/A	N/A
1	1	Stairwell across from Classroom 101	N/A	Granite Walls		Non Suspect ACM	450	SF	0	SF		Glue Dots Assumed Present behind Granite Walls		N/A	N/A	N/A
1	1	Stairwell across from Classroom 101	N/A	Plaster Walls		NAD	900	SF	0	SF				N/A	N/A	N/A
1	1	Stairwell across from Classroom 101	N/A	Plaster Ceiling		NAD	300	SF	0	SF				N/A	N/A	N/A
1	B	South Fan Room # 1 across from Classroom 101	N/A	Cement Floor		Non Suspect ACM	1000	SF	0	SF				N/A	N/A	N/A
1	B	South Fan Room # 1 across from Classroom 101	N/A	Brick Wall		Non Suspect ACM	2350	SF	0	SF		235 SF of Loose/Flaking Paint		N/A	N/A	N/A
1	B	South Fan Room # 1 across from Classroom 101	N/A	Concrete Ceiling		Non Suspect ACM	1000	SF	0	SF		100 SF of Loose/Flaking Paint		N/A	N/A	N/A
1	B	South Fan Room # 1 across from Classroom 101	N/A	Metal Fan Unit		Non Suspect ACM	1400	SF	X	SF		140 SF of Loose/Flaking Paint		N/A	N/A	N/A
1	B	South Fan Room # 1 across from Classroom 101	M	Brown Caulk	8120/01/0B/SYN/BB/2609	Assumed	20	LF	0	LF		Inside the Fresh Air Intake at the Metal Fan Unit/Brick Wall Connection		1	No	1/D
1	B	South Fan Room # 1 across from Classroom 101	M	Brown Caulk	8120/01/0B/SYN/BB/2609	Assumed	30	LF	0	LF		Inside the Primary Heating/Air Wash Chamber		1	No	1/D
1	B	South Fan Room # 1 across from Classroom 101	M	Brown Caulk	8120/01/0B/SYN/BB/2609	Assumed	20	LF	0	LF		Inside the Baffle/Fan Blade Chamber		1	No	1/D
1	B	South Fan Room # 1 across from Classroom 101	T	Duct Seam Packing	8120/01/0B/SYN/BB/1625	Assumed	20	LF	0	LF		Inside the Secondary Heating Chamber at the Metal Fan Unit/Brick Wall Connection		1	No	1/D
1	B	South Fan Room # 1 across from Classroom 101	M	Vibration Damper Cloth	8120/01/0B/09	Assumed	25	SF	0	SF				1	No	1/D
1	B	South Fan Room # 1 across from Classroom 101	T	Pipe Insulation > 6 inch	8120/01/0B/01	Confirmed	20	LF	0	LF				1	No	1/D
1	B	South Fan Room # 1 across from Classroom 101	T	Pipe Insulation 2-6 inch	8120/01/0B/02	Confirmed	100	LF	0	LF				1	No	1/D
1	B	South Fan Room # 1 across from Classroom 101	T	Pipe Fitting Insulation	8120/01/0B/04	Confirmed	54	EA	0	EA				1	No	1/D
1	B	South Fan Room # 1 across from Classroom 101	T	Horse Hair Pipe/Pipe Fitting Insulation	8120/01/05(PH)/SYN/BB/1140	Assumed	8	LF	0	LF		Inside the Fresh Air Intake		1	No	1/D
1	B	South Fan Room # 1 across from Classroom 101	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	285	LF	0	LF		Includes the quantity of FGPI in the Ramp between the Fan Room and the Return Airshaft		N/A	N/A	N/A
1	B	Ramp between Fan Room # 1 and the Auditorium Fan Room	N/A	Concrete Floor		Non Suspect ACM	400	SF	X	SF				N/A	N/A	N/A
1	B	Ramp between Fan Room # 1 and the Auditorium Fan Room	N/A	Concrete Ceiling		Non Suspect ACM	400	SF	X	SF				N/A	N/A	N/A
1	B	Ramp between Fan Room # 1 and the Auditorium Fan Room	N/A	Concrete Block Wall		Non Suspect ACM	1200	SF	X	SF				N/A	N/A	N/A
1	B	Ramp between Fan Room # 1 and the Auditorium Fan Room	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	40	LF	X	LF				N/A	N/A	N/A
1	B	South Fan Room # 1 and Auditorium Fan Room Return Airshaft/Pipe Shaft	N/A	Cement Floor		Non Suspect ACM	64	SF	X	SF				N/A	N/A	N/A
1	B	South Fan Room # 1 and Auditorium Fan Room Return Airshaft/Pipe Shaft	N/A	Brick Wall		Non Suspect ACM	64	SF	X	SF				N/A	N/A	N/A
1	B	South Fan Room # 1 and Auditorium Fan Room Return Airshaft/Pipe Shaft	N/A	Concrete Ceiling		Non Suspect ACM	2000	SF	X	SF				N/A	N/A	N/A
1	B	South Fan Room # 1 and Auditorium Fan Room Return Airshaft/Pipe Shaft	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	60	LF	X	LF		FGPI applied to the Main Steam Riser		N/A	N/A	N/A
1	B	North Fan Room # 2 next to Staff Parking Lot	N/A	Cement Floor		Non Suspect ACM	1000	SF	0	SF				N/A	N/A	N/A
1	B	North Fan Room # 2 next to Staff Parking Lot	N/A	Brick Wall		Non Suspect ACM	2350	SF	0	SF		235 SF of Loose/Flaking Paint		N/A	N/A	N/A
1	B	North Fan Room # 2 next to Staff Parking Lot	N/A	Concrete Ceiling		Non Suspect ACM	1000	SF	0	SF		100 SF of Loose/Flaking Paint		N/A	N/A	N/A
1	B	North Fan Room # 2 next to Staff Parking Lot	N/A	Metal Fan Unit		Non Suspect ACM	1400	SF	X	SF		140 SF of Loose/Flaking Paint		N/A	N/A	N/A
1	B	North Fan Room # 2 next to Staff Parking Lot	M	Brown Caulk	8120/01/0B/SYN/BB/2609	Assumed	20	LF	0	LF		Inside the Fresh Air Intake at the Metal Fan Unit/Brick Wall Connection		1	No	1/D
1	B	North Fan Room # 2 next to Staff Parking Lot	T	Duct Seam Packing	8120/01/0B/SYN/BB/1625	Assumed	3	LF	0	LF		Inside the Fresh Air Intake		1	No	1/D
1	B	North Fan Room # 2 next to Staff Parking Lot	T	Duct Seam Packing	8120/01/0B/SYN/BB/1625	Assumed	10	LF	0	LF		Inside the Primary Heating/Air Wash Chamber		1	No	1/D
1	B	North Fan Room # 2 next to Staff Parking Lot	T	Duct Seam Packing	8120/01/0B/SYN/BB/1625	Assumed	20	LF	0	LF		Inside the Secondary Heating Chamber at the Metal Fan Unit/Brick Wall Connection		1	No	1/D
1	B	North Fan Room # 2 next to Staff Parking Lot	M	Vibration Damper Cloth	8120/01/0B/09	Assumed	25	SF	0	SF				1	No	1/D
1	B	North Fan Room # 2 next to Staff Parking Lot	T	Pipe Insulation > 6 inch	8120/01/0B/01	Confirmed	20	LF	0	LF				1	No	1/D

8120 Woodrow Wilson MS 2015 2016 AHERA Three-Year Report.xls

School District of Philadelphia Woodrow Wilson Middle School 1800 Cottman Ave, Philadelphia, PA 19111 ULCS# 8120 Year Built: 1928				AHERA Three-Year Reinspection 2015-2016 Room by Room Location Log Report										Reinspection Date: December 3, 2015 Building Inspector: Norman Harrison Number: 037951 Management Planner: Megan Vala Number: 740728			
E l e m e n t	F l o o r	On Site Room Name	System Affected	Material Description	HID#	Confirmed/Assumed/NAD/ Non Suspect ACM	Amount of Material	SF LF EA	Amount of Damage	SF LF EA	Color required for VAT	Comments/Description/Notes	Attic/ Crawl Space Ranking	Damage Potential (DP)	Newly Friable (NF)	Response Action (RA)	
1	B	North Fan Room # 2 next to Staff Parking Lot	T	Pipe Insulation 2-6 inch	8120/01/0B/02	Confirmed	100	LF	0	LF				1	No	1/D	
1	B	North Fan Room # 2 next to Staff Parking Lot	T	Pipe Fitting Insulation	8120/01/0B/04	Confirmed	54	EA	0	EA				1	No	1/D	
1	B	North Fan Room # 2 next to Staff Parking Lot	T	Horse Hair Pipe/Pipe Fitting Insulation	8120/01/05(PH)/SYN/BB/1140	Assumed	16	LF	0	LF		Inside the Fresh Air Intake		1	No	1/D	
1	B	North Fan Room # 2 next to Staff Parking Lot	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	320	LF	0	LF		Includes the quantity of FGPI in the Ramp between the Fan Room and the Return Airshaft		N/A	N/A	N/A	
1	B	Ramp between Fan Room # 2 and the Return Airshaft	N/A	Concrete Floor		Non Suspect ACM	400	SF	X	SF				N/A	N/A	N/A	
1	B	Ramp between Fan Room # 2 and the Return Airshaft	N/A	Concrete Ceiling		Non Suspect ACM	400	SF	X	SF				N/A	N/A	N/A	
1	B	Ramp between Fan Room # 2 and the Return Airshaft	N/A	Concrete Block Wall		Non Suspect ACM	1200	SF	X	SF				N/A	N/A	N/A	
1	B	Ramp between Fan Room # 2 and the Return Airshaft	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	70	LF	X	LF				N/A	N/A	N/A	
1	B	North Fan Room # 2 Return Airshaft	N/A	Cement Floor		Non Suspect ACM	75	SF	X	SF				N/A	N/A	N/A	
1	B	North Fan Room # 2 Return Airshaft	N/A	Brick Wall		Non Suspect ACM	250	SF	X	SF		No TSI in the Return Airshaft		N/A	N/A	N/A	
1	B	North Fan Room # 2 Return Airshaft	N/A	Concrete Ceiling		Non Suspect ACM	75	SF	X	SF				N/A	N/A	N/A	
1	B	Auditorium Fan Room # 3	N/A	Cement Floor		Non Suspect ACM	1000	SF	0	SF				N/A	N/A	N/A	
1	B	Auditorium Fan Room # 3	N/A	Brick Wall		Non Suspect ACM	2350	SF	0	SF		2350 SF of Loose/Flaking Paint		N/A	N/A	N/A	
1	B	Auditorium Fan Room # 3	N/A	Concrete Ceiling		Non Suspect ACM	1000	SF	0	SF		1000 SF of Loose/Flaking Paint		N/A	N/A	N/A	
1	B	Auditorium Fan Room # 3	N/A	Metal Fan Unit		Non Suspect ACM	1400	SF	X	SF		1400 SF of Loose/Flaking Paint; No Interior Seam Packing or Caulk Identified		N/A	N/A	N/A	
1	B	Auditorium Fan Room # 3	T	Pipe Insulation 2-6 inch	8120/01/0B/02	Confirmed	95	LF	0	LF				1	No	1/D	
1	B	Auditorium Fan Room # 3	T	Pipe Insulation > 6 inch	8120/01/0B/01	Confirmed	40	LF	0	LF				1	No	1/D	
1	B	Auditorium Fan Room # 3	T	Pipe Fitting Insulation	8120/01/0B/04	Confirmed	25	EA	0	EA				1	No	1/D	
1	B	Auditorium Fan Room # 3	T	Horse Hair Pipe/Pipe Fitting Insulation	8120/01/05(PH)/SYN/BB/1140	Assumed	14	LF	0	LF		Inside the Fresh Air Intake		1	No	1/D	
1	B	Auditorium Fan Room # 3	M	Vibration Damper Cloth	8120/01/0B/09	Assumed	25	SF	0	SF				1	No	1/D	
1	B	Auditorium Fan Room # 3	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	80	LF	0	LF				N/A	N/A	N/A	
1	B	Foyer to Previous Restroom below Auditorium Stage	N/A	Concrete Floor		Non Suspect ACM	20	SF	X	SF				N/A	N/A	N/A	
1	B	Foyer to Previous Restroom below Auditorium Stage	N/A	Concrete Ceiling		Non Suspect ACM	50	SF	X	SF				N/A	N/A	N/A	
1	B	Foyer to Previous Restroom below Auditorium Stage	N/A	Concrete Block Wall		Non Suspect ACM	20	SF	X	SF				N/A	N/A	N/A	
1	B	Foyer to Previous Restroom below Auditorium Stage	T	Pipe Insulation 2-6 inch	8120/01/0B/02	Confirmed	3	LF	0	LF				1	No	1/D	
1	B	Foyer to Previous Restroom below Auditorium Stage	T	Pipe Fitting Insulation	8120/01/0B/04	Confirmed	1	EA	0	EA				1	No	1/D	
1	B	Foyer to Previous Restroom below Auditorium Stage	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	10	LF	X	LF				N/A	N/A	N/A	
1	B	Foyer to Previous Restroom below Auditorium Stage	T	Pipe Fitting Insulation	8120/01/0B/04	Confirmed	4	EA	0	EA		Associated with Fiberglass Pipe Insulation		1	No	1/D	
1	B	Previous Restroom below Auditorium Stage	N/A	Concrete Floor		Non Suspect ACM	300	SF	X	SF				N/A	N/A	N/A	
1	B	Previous Restroom below Auditorium Stage	N/A	Concrete Ceiling		Non Suspect ACM	300	SF	X	SF				N/A	N/A	N/A	
1	B	Previous Restroom below Auditorium Stage	N/A	Concrete Block Wall		Non Suspect ACM	900	SF	X	SF				N/A	N/A	N/A	
1	B	Old Dressing Room next to Auditorium Supply Plenum	N/A	Concrete Floor		Non Suspect ACM	750	SF	0	SF		Stairwell to Auditorium Stage has been Restricted	B	N/A	N/A	N/A	
1	B	Old Dressing Room next to Auditorium Supply Plenum	N/A	Concrete Ceiling		Non Suspect ACM	2250	SF	0	SF			B	N/A	N/A	N/A	
1	B	Old Dressing Room next to Auditorium Supply Plenum	N/A	Concrete Block Wall		Non Suspect ACM	750	SF	0	SF			B	N/A	N/A	N/A	
1	B	Old Dressing Room next to Auditorium Supply Plenum	T	Pipe Insulation 2-6 inch	8120/01/0B/02	Confirmed	24	LF	0	LF			B	1	No	1/D	
1	B	Auditorium Supply Plenum (below Auditorium)	N/A	Concrete Floor		Non Suspect ACM	5600	SF	0	SF			A	N/A	N/A	N/A	
1	B	Auditorium Supply Plenum (below Auditorium)	N/A	Concrete Ceiling		Non Suspect ACM	5600	SF	0	SF			A	N/A	N/A	N/A	
1	B	Auditorium Supply Plenum (below Auditorium)	N/A	Concrete Block Wall		Non Suspect ACM	5600	SF	0	SF			A	N/A	N/A	N/A	
1	B	Auditorium Supply Plenum (below Auditorium)	N/A	Metal Supply Ductwork		Non Suspect ACM	500	SF	X	SF			A	N/A	N/A	N/A	
1	B	Auditorium Supply Plenum (below Auditorium)	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	300	LF	0	LF			A	N/A	N/A	N/A	
1	B	Electrical Room between Auditorium Fan Room and Boiler Room	N/A	Cement Floor		Non Suspect ACM	1300	SF	0	SF				N/A	N/A	N/A	
1	B	Electrical Room between Auditorium Fan Room and Boiler Room	N/A	Brick Wall		Non Suspect ACM	1900	SF	0	SF		1900 SF of Loose/Flaking Paint		N/A	N/A	N/A	
1	B	Electrical Room between Auditorium Fan Room and Boiler Room	N/A	Concrete Ceiling		Non Suspect ACM	1300	SF	0	SF		1400 SF of Loose/Flaking Paint		N/A	N/A	N/A	
1	B	Electrical Room between Auditorium Fan Room and Boiler Room	T	Pipe Insulation 2-6 inch	8120/01/0B/02	Confirmed	100	LF	0	LF				1	No	1/D	
1	B	Electrical Room between Auditorium Fan Room and Boiler Room	T	Pipe Insulation > 6 inch	8120/01/0B/01	Confirmed	60	LF	0	LF				1	No	1/D	
1	B	Electrical Room between Auditorium Fan Room and Boiler Room	T	Pipe Fitting Insulation	8120/01/0B/04	Confirmed	30	EA	0	EA				1	No	1/D	
1	B	Electrical Room between Auditorium Fan Room and Boiler Room	M	Transite Electrical Panel	8120/01/0B/01/0B/BB/2350	Assumed	20	SF	0	SF				1	No	1/D	
1	B	Electrical Room between Auditorium Fan Room and Boiler Room	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	60	LF	0	LF				N/A	N/A	N/A	
1	B	Restroom inside Electrical Room between Auditorium Fan Room and Boiler Room	N/A	Cement Floor		Non Suspect ACM	40	SF	0	SF				N/A	N/A	N/A	
1	B	Restroom inside Electrical Room between Auditorium Fan Room and Boiler Room	N/A	Brick Wall		Non Suspect ACM	120	SF	30	SF		Loose/Flaking Paint		N/A	N/A	N/A	

8120 Woodrow Wilson MS 2015 2016 AHERA Three-Year Report.xls

		School District of Philadelphia Woodrow Wilson Middle School 1800 Cottman Ave, Philadelphia, PA 19111 ULCS# 8120 Year Built: 1928		AHERA Three-Year Reinspection 2015-2016 Room by Room Location Log Report								Reinspection Date: December 3, 2015 Building Inspector: Norman Harrison Number: 037951 Management Planner: Megan Vala Number: 740728							
E l e m e n t	F l o o r	On Site Room Name	System Affected	Material Description	HID#	Confirmed/Assumed/NAD/ Non Suspect ACM	Amount of Material	SF LF EA	Amount of Damage	SF LF EA	Color required for VAT	Comments/Description/Notes	Attic/ Crawl Space Ranking	Damage Potential (DP)	Newly Friable (NF)	Response Action (RA)			
1	B	Restroom inside Electrical Room between Auditorium Fan Room and Boiler Room	N/A	Concrete Ceiling		Non Suspect ACM	40	SF	10	SF		Loose/Flaking Paint		N/A	N/A	N/A			
1	B	Boiler Room	N/A	Cement Floor		Non Suspect ACM	3000	SF	0	SF				N/A	N/A	N/A			
1	B	Boiler Room	N/A	Brick Wall		Non Suspect ACM	4500	SF	3000	SF		4500 SF of Loose/Flaking Paint		N/A	N/A	N/A			
1	B	Boiler Room	N/A	Concrete Ceiling		Non Suspect ACM	3000	SF	1000	SF		3500 SF of Loose/Flaking Paint		N/A	N/A	N/A			
1	B	Boiler Room	N/A	Package Boilers		NAD	3	EA	1	EA		All internal materials associated with Boiler # 1 confirmed non-asbestos - Synertech Project # 010-4251. Boilers # 2 and # 3 are homogeneous to Boiler # 1		N/A	N/A	N/A			
1	B	Boiler Room	T	Boiler Breaching Gaskets	8120/01/0B/SYN/BB/0601	Assumed	3	EA	0	EA		One (1) gasket between the breaching flange connection at the top of each boiler is assumed present		1	No	1/D			
1	B	Boiler Room	T	Brick Incinerator	8120/01/0B/SYN/BB/1640	Assumed	1	EA	0	EA		5'x8'x7" High Steel Jacketed Brick Incinerator - Demolish Under Full Containment		1	No	1/D			
1	B	Boiler Room	T	Incinerator Breaching Gaskets	8120/01/0B/SYN/BB/1661	Assumed	3	EA	0	EA		Two (2) gaskets between breaching flange connections are assumed present		1	No	1/D			
1	B	Boiler Room	T	Pipe Insulation 2-6 inch	8120/01/0B/02	Confirmed	150	LF	0	LF				1	No	1/D			
1	B	Boiler Room	T	Pipe Insulation > 6 inch	8120/01/0B/01	Confirmed	45	LF	0	LF				1	No	1/D			
1	B	Boiler Room	T	Pipe Fitting Insulation	8120/01/0B/04	Confirmed	150	EA	0	EA				1	No	1/D			
1	B	Boiler Room	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	650	LF	0	LF				N/A	N/A	N/A			
1	B	Old Coal Storage Room	N/A	Cement Floor		Non Suspect ACM	1500	SF	X	SF		No TSI in Old Coal Storage Room		N/A	N/A	N/A			
1	B	Old Coal Storage Room	N/A	Concrete Block Wall		Non Suspect ACM	4500	SF	X	SF		Walls are Unpainted		N/A	N/A	N/A			
1	B	Old Coal Storage Room	N/A	Concrete Ceiling		Non Suspect ACM	1500	SF	X	SF		Ceiling is Unpainted; Major Water Infiltration		N/A	N/A	N/A			
1	B	Emergency Generator/Oil Pump Room next to Boiler Room	N/A	Cement Floor		Non Suspect ACM	1300	SF	0	SF				N/A	N/A	N/A			
1	B	Emergency Generator/Oil Pump Room next to Boiler Room	N/A	Brick Wall		Non Suspect ACM	3900	SF	0	SF		No Loose/Flaking Paint		N/A	N/A	N/A			
1	B	Emergency Generator/Oil Pump Room next to Boiler Room	N/A	Concrete Ceiling		Non Suspect ACM	1300	SF	0	SF		No Loose/Flaking Paint		N/A	N/A	N/A			
1	B	Emergency Generator/Oil Pump Room next to Boiler Room	T	Pipe Insulation 2-6 inch	8120/01/0B/02	Confirmed	60	LF	1	LF				1	Yes	5/C			
1	B	Emergency Generator/Oil Pump Room next to Boiler Room	T	Pipe Fitting Insulation	8120/01/0B/04	Confirmed	10	EA	0	EA				1	No	1/D			
1	B	Emergency Generator/Oil Pump Room next to Boiler Room	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	300	LF	0	LF				N/A	N/A	N/A			
1	B	Emergency Generator/Oil Pump Room next to Boiler Room	N/A	Emergency Generator Piping		Non Suspect ACM	65	LF	X	LF		Non-asbestos Calcium Silicate Pipe Insulation is applied to the Generator Exhaust Flue		N/A	N/A	N/A			
1	B	Girl's Gym	N/A	Cement Floor		Non Suspect ACM	6120	SF	0	SF		Painted Concrete Floor		N/A	N/A	N/A			
1	B	Girl's Gym	N/A	Concrete Ceiling		Non Suspect ACM	6120	SF	0	SF				N/A	N/A	N/A			
1	B	Girl's Gym	N/A	Brick Wall		Non Suspect ACM	7500	SF	0	SF				N/A	N/A	N/A			
1	B	Girl's Gym	M	Wall and Ceiling Glue Dots	8120/01/0B/SYN/BB/2610	Assumed	1000	SF	0	SF				1	No	1/D			
1	B	Boy's Gym	N/A	Cement Floor		Non Suspect ACM	6120	SF	0	SF		Painted Concrete Floor		N/A	N/A	N/A			
1	B	Boy's Gym	N/A	Concrete Ceiling		Non Suspect ACM	6120	SF	0	SF				N/A	N/A	N/A			
1	B	Boy's Gym	N/A	Plaster Ceiling		NAD	500	SF	X	SF				N/A	N/A	N/A			
1	B	Boy's Gym	N/A	Brick Wall		Non Suspect ACM	7500	SF	0	SF				N/A	N/A	N/A			
1	B	Boy's Gym	M	Wall and Ceiling Glue Dots	8120/01/0B/SYN/BB/2610	Assumed	1000	SF	0	SF				1	No	1/D			
1	B	Rear Storage Room inside Girl's Gym	N/A	Wood Floor		Non Suspect ACM	200	SF	0	SF	Tan			N/A	N/A	N/A			
1	B	Rear Storage Room inside Girl's Gym	N/A	Brick Wall		Non Suspect ACM	500	SF	0	SF				N/A	N/A	N/A			
1	B	Rear Storage Room inside Girl's Gym	N/A	Concrete Ceiling		Non Suspect ACM	200	SF	0	SF				N/A	N/A	N/A			
1	B	Rear Storage Room inside Girl's Gym	T	Pipe Insulation 2-6 inch	8120/01/0B/02	Confirmed	10	LF	1	LF				1	Yes	5/A			
1	B	Facilities Storage Room next to Rear Storage Room inside Girl's Gym	N/A	Cement Floor		Non Suspect ACM	300	SF	X	SF		Cannot be accessed through Girl's Gym. Quantities were established by looking through a window in the Girl's Gym. Access entrance to this room was not located.		N/A	N/A	N/A			
1	B	Facilities Storage Room next to Rear Storage Room inside Girl's Gym	N/A	Brick Wall		Non Suspect ACM	800	SF	X	SF				N/A	N/A	N/A			
1	B	Facilities Storage Room next to Rear Storage Room inside Girl's Gym	N/A	Concrete Ceiling		Non Suspect ACM	300	SF	X	SF				N/A	N/A	N/A			
1	B	Facilities Storage Room next to Rear Storage Room inside Girl's Gym	T	Pipe Insulation 2-6 inch	8120/01/0B/02	Confirmed	30	LF	0	LF				1	No	1/D			
1	B	Facilities Storage Room next to Rear Storage Room inside Girl's Gym	T	Pipe Fitting Insulation	8120/01/0B/04	Confirmed	6	EA	0	EA				1	No	1/D			
1	B	Girl's Gym Office - Bottom of Stairs at Gym Entrance	M	Floor Tile VAT 12" x 12"	8120/01/0B/LL	Assumed	150	SF	0	SF	Tan			1	No	1/D			
1	B	Girl's Gym Office - Bottom of Stairs at Gym Entrance	N/A	Plaster Walls		NAD	450	SF	90	SF		Loose/Flaking Paint		N/A	N/A	N/A			
1	B	Girl's Gym Office - Bottom of Stairs at Gym Entrance	N/A	Plaster Ceiling		NAD	150	SF	30	SF		Loose/Flaking Paint		N/A	N/A	N/A			
1	B	Girl's Gym Office - Bottom of Stairs at Gym Entrance	T	Pipe Insulation 2-6 inch	8120/01/0B/02	Confirmed	8	LF	0	LF				1	No	1/D			
1	B	Girl's Gym Office - Bottom of Stairs at Gym Entrance	T	Pipe Fitting Insulation	8120/01/0B/04	Confirmed	1	EA	1	EA				1	Yes	5/A			
1	B	Small Hallway to Girl's Gym Office - Bottom of Stairs at Gym Entrance	M	Floor Tile VAT 12" x 12"	8120/01/0B/LL	Assumed	32	SF	0	SF	Tan			1	No	1/D			
1	B	Small Hallway to Girl's Gym Office - Bottom of Stairs at Gym Entrance	N/A	Plaster Walls		NAD	96	SF	0	SF				N/A	N/A	N/A			
1	B	Small Hallway to Girl's Gym Office - Bottom of Stairs at Gym Entrance	N/A	Plaster Ceiling		NAD	32	SF	0	SF				N/A	N/A	N/A			
1	B	Small Hallway to Girl's Gym Office - Bottom of Stairs at Gym Entrance	T	Pipe Insulation 2-6 inch	8120/01/0B/02	Confirmed	5	LF	0	LF				1	No	1/D			

8120 Woodrow Wilson MS 2015 2016 AHERA Three-Year Report.xls

		School District of Philadelphia Woodrow Wilson Middle School 1800 Cottman Ave, Philadelphia, PA 19111 ULCS# 8120 Year Built: 1928		AHERA Three-Year Reinspection 2015-2016 Room by Room Location Log Report							Reinspection Date: December 3, 2015 Building Inspector: Norman Harrison Number: 037951 Management Planner: Megan Vala Number: 740728					
E l e m e n t	F l o o r	On Site Room Name	System Affected	Material Description	HID#	Confirmed/Assumed/NAD/ Non Suspect ACM	Amount of Material	SF LF EA	Amount of Damage	SF LF EA	Color required for VAT	Comments/Description/Notes	Attic/ Crawl Space Ranking	Damage Potential (DP)	Newly Friable (NF)	Response Action (RA)
1	B	Small Hallway to Girl's Gym Office - Bottom of Stairs at Gym Entrance	T	Pipe Fitting Insulation	8120/01/0B/04	Confirmed	6	EA	1	EA				1	Yes	5/A
1	B	Small Hallway to Girl's Gym Office - Bottom of Stairs at Gym Entrance	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	2	LF	0	LF				N/A	N/A	N/A
1	B	Gym Teacher's Restroom - Bottom of Stairs at Gym Entrance	M	Floor Tile VAT 12" x 12"	8120/01/0B/LL	Assumed	64	SF	0	SF	Tan			1	No	1/D
1	B	Gym Teacher's Restroom - Bottom of Stairs at Gym Entrance	N/A	Plaster Walls		NAD	192	SF	0	SF				N/A	N/A	N/A
1	B	Gym Teacher's Restroom - Bottom of Stairs at Gym Entrance	N/A	Plaster Ceiling		NAD	64	SF	0	SF				N/A	N/A	N/A
1	B	Girl's Gym Storage - Bottom of Stairs at Gym Entrance	M	Floor Tile VAT 12" x 12"	8120/01/0B/LL	Assumed	80	SF	0	SF				1	No	1/D
1	B	Girl's Gym Storage - Bottom of Stairs at Gym Entrance	N/A	Plaster Walls		NAD	200	SF	0	SF				N/A	N/A	N/A
1	B	Girl's Gym Storage - Bottom of Stairs at Gym Entrance	N/A	Plaster Ceiling		NAD	80	SF	0	SF				N/A	N/A	N/A
1	B	Girl's Gym Storage - Bottom of Stairs at Gym Entrance	T	Pipe Insulation 2-6 inch	8120/01/0B/02	Confirmed	32	LF	0	LF				1	No	1/D
1	B	Girl's Gym Storage - Bottom of Stairs at Gym Entrance	T	Pipe Fitting Insulation	8120/01/0B/04	Confirmed	7	EA	0	EA				1	No	1/D
1	B	Girl's Gym Storage Room Below Stairwell	N/A	Cement Floor		Non Suspect ACM	64	SF	X	SF				N/A	N/A	N/A
1	B	Girl's Gym Storage Room Below Stairwell	N/A	Brick Wall		Non Suspect ACM	150	SF	X	SF				N/A	N/A	N/A
1	B	Girl's Gym Storage Room Below Stairwell	N/A	Concrete Ceiling		Non Suspect ACM	64	SF	X	SF				N/A	N/A	N/A
1	B	Rear Storage Room inside Boy's Gym	N/A	Wood Floor		Non Suspect ACM	200	SF	X	SF				N/A	N/A	N/A
1	B	Rear Storage Room inside Boy's Gym	N/A	Brick Wall		Non Suspect ACM	500	SF	X	SF				N/A	N/A	N/A
1	B	Rear Storage Room inside Boy's Gym	N/A	Concrete Ceiling		Non Suspect ACM	200	SF	X	SF				N/A	N/A	N/A
1	B	Rear Storage Room inside Boy's Gym	T	Pipe Insulation 2-6 inch	8120/01/0B/02	Confirmed	10	LF	0	LF				1	No	1/D
1	B	Boy's Gym Storage - Bottom of Stairs at Gym Entrance	N/A	Wood Floor		Non Suspect ACM	80	SF	X	SF				N/A	N/A	N/A
1	B	Boy's Gym Storage - Bottom of Stairs at Gym Entrance	N/A	Plaster Walls		NAD	200	SF	X	SF				N/A	N/A	N/A
1	B	Boy's Gym Storage - Bottom of Stairs at Gym Entrance	N/A	Plaster Ceiling		NAD	80	SF	X	SF				N/A	N/A	N/A
1	B	Boy's Gym Storage Room Below Stairwell	N/A	Cement Floor		Non Suspect ACM	64	SF	X	SF				N/A	N/A	N/A
1	B	Boy's Gym Storage Room Below Stairwell	N/A	Brick Wall		Non Suspect ACM	150	SF	X	SF				N/A	N/A	N/A
1	B	Boy's Gym Storage Room Below Stairwell	N/A	Concrete Ceiling		Non Suspect ACM	64	SF	X	SF				N/A	N/A	N/A
1	B	Boy's Gym Office - Bottom of Stairs at Gym Entrance	M	Floor Tile VAT 12" x 12"	8120/01/0B/LL	Assumed	150	SF	0	SF	Tan			1	No	1/D
1	B	Boy's Gym Office - Bottom of Stairs at Gym Entrance	N/A	Plaster Walls		NAD	450	SF	100	SF		Loose/Flaking Paint		N/A	N/A	N/A
1	B	Boy's Gym Office - Bottom of Stairs at Gym Entrance	N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	150	SF	0	SF				N/A	N/A	N/A
1	B	Boy's Gym Office - Bottom of Stairs at Gym Entrance	T	Pipe Insulation 2-6 inch	8120/01/0B/02	Confirmed	10	LF	0	LF				1	No	1/D
1	B	Boy's Gym Office - Bottom of Stairs at Gym Entrance	T	Pipe Fitting Insulation	8120/01/0B/04	Confirmed	3	EA	0	EA				1	No	1/D
1	B	Small Hallway to Boy's Gym Office - Bottom of Stairs at Gym Entrance	M	Floor Tile VAT 12" x 12"	8120/01/0B/LL	Assumed	32	SF	0	SF	Tan			1	No	1/D
1	B	Small Hallway to Boy's Gym Office - Bottom of Stairs at Gym Entrance	N/A	Plaster Walls		NAD	96	SF	0	SF				N/A	N/A	N/A
1	B	Small Hallway to Boy's Gym Office - Bottom of Stairs at Gym Entrance	N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	32	SF	0	SF				N/A	N/A	N/A
1	B	Gym Teacher's Restroom - Bottom of Stairs at Gym Entrance	M	Floor Tile VAT 12" x 12"	8120/01/0B/LL	Assumed	64	SF	0	SF	Tan			1	No	1/D
1	B	Gym Teacher's Restroom - Bottom of Stairs at Gym Entrance	N/A	Plaster Walls		NAD	192	SF	0	SF				N/A	N/A	N/A
1	B	Gym Teacher's Restroom - Bottom of Stairs at Gym Entrance	N/A	Plaster Ceiling		NAD	64	SF	0	SF				N/A	N/A	N/A
1	SB	Concrete Distribution Tunnel/Air Supply Plenum connected to Fan Room # 1	N/A	Cement Floor		Non Suspect ACM	2000	SF	X	SF		Trash strewn throughout - Source of trash is from the supply vents in Classrooms above. Runs under 1st Floor Hallway.	A	N/A	N/A	N/A
1	SB	Concrete Distribution Tunnel/Air Supply Plenum connected to Fan Room # 1	N/A	Concrete Block Wall		Non Suspect ACM	2000	SF	X	SF		Runs under 1st Floor Hallway	A	N/A	N/A	N/A
1	SB	Concrete Distribution Tunnel/Air Supply Plenum connected to Fan Room # 1	N/A	Concrete Ceiling		Non Suspect ACM	2000	SF	X	SF		Runs under 1st Floor Hallway	A	N/A	N/A	N/A
1	SB	Concrete Distribution Tunnel/Air Supply Plenum connected to Fan Room # 1	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	250	LF	X	LF		Runs under 1st Floor Hallway	A	N/A	N/A	N/A
1	SB	Concrete Distribution Tunnel/Air Supply Plenum connected to Fan Room # 2	N/A	Cement Floor		Non Suspect ACM	2000	SF	X	SF		Trash strewn throughout - Source of trash is from the supply vents in Classrooms above. Runs under 1st Floor Hallway.	A	N/A	N/A	N/A
1	SB	Concrete Distribution Tunnel/Air Supply Plenum connected to Fan Room # 2	N/A	Concrete Block Wall		Non Suspect ACM	2000	SF	X	SF		Runs under 1st Floor Hallway	A	N/A	N/A	N/A
1	SB	Concrete Distribution Tunnel/Air Supply Plenum connected to Fan Room # 2	N/A	Concrete Ceiling		Non Suspect ACM	2000	SF	X	SF		Runs under 1st Floor Hallway	A	N/A	N/A	N/A
1	SB	Concrete Distribution Tunnel/Air Supply Plenum connected to Fan Room # 2	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	250	LF	X	LF		Runs under 1st Floor Hallway	A	N/A	N/A	N/A

Section III Certificates

A. Management Planner/Building Inspector Certificates

Section III – A

Management Planner/Building Inspector Certificates

These charts indicate the Name, Course Date, Expiration Date and Corresponding Certificate Number of the Management Planner and Building Inspector of individuals that participated in the AHERA 3 Year Inspection and Management Plan process of 2015/2016.

Management Planner	Date Granted	Expiration Date	Certificate Number
Monique Causley	2/15/2015	2/16/2016	ACC-0215-8-010
Monique Causley	2/16/2016	2/17/2017	ACC-0216-8-001
Megan Vala	5/22/2015	6/22/2016	740728
Mary Anne Lerro	4/5/2016	4/5/2017	742327

Building Inspector	Date Granted	Expiration Date	Certificate Number
Scott Magee	8/15/2015	8/15/2016	70016699C
William Garrity	8/15/2015	8/15/2016	70016699A
Bernard Brunner	10/2/2015	8/2/2016	45397
Mary Anne Lerro	3/3/2015	3/3/2016	740092
Mary Anne Lerro	4/5/2016	4/5/2017	742322
James Madden	12/11/2014	12/11/2015	ACC-1214-6-010
James Madden	12/3/2015	12/3/2016	ACC-1215-6-018
Troy Ray	3/15/2015	3/19/2016	ACC-0355-6-011
Ananth Vinjamuri	9/29/2015	9/29/2016	374
Shelton Williams	9/29/2015	9/29/2016	375
Paul Davis	2/12/2015	2/12/2016	ACC-0215-6-015
Paul Davis	2/2/2016	2/2/2017	741836
Bernard Bryson	2/16/2015	2/16/2016	ACC-0125-6-031
Bernard Bryson	2/15/2016	2/15/2017	ACC-0216-6-005
Alexander Roman	9/18/2015	9/18/2016	EHSBIR-150619-008
Norm Harrison	9/2/2015	9/2/2016	ACC-0915-6-011
Kelly Mayberry	2/20/2015	2/20/2016	EHSBIR-150220-005
Kelly Mayberry	2/18/2016	2/18/2017	EHSBIR-160218-006
Andrew Hine	5/6/2015	5/6/2016	AI05042015-3
Maryellen Leotta	2/12/2015	2/12/2016	ACC-0215-6-024

Certificate of Completion

awarded to

Monique Causley

for successfully completing the prescribed course of study in

Pennsylvania Asbestos Management Planner Refresher Course

under TSCA Title II

presented by

ACCESS TRAINING SERVICES, INC.
7921 River Road, Pennsauken, NJ 08110
(856) 665-3449

2/16/15

Course Date

N/A

Exam Date

2/16/16

Expiration Date

Not Provided

Social Security Number

ACC-0215-8-010

Certificate Number

Mark K. Schlager
Training Director

Certificate of Completion

awarded to

Monique Causley

for successfully completing the prescribed course of study in

Pennsylvania Asbestos Management Planner Refresher Course

under TSCA Title II

presented by

ACCESS TRAINING SERVICES, INC.
7921 River Road, Pennsauken, NJ 08110
(856) 665-3449

2/15/16

Course Date

N/A

Exam Date

2/15/17

Expiration Date

Not Provided

Social Security Number

ACC-0216-8-001

Certificate Number

Mark K. Schlüger
Training Director

Certificate of Training

CRITERION LABORATORIES, INC.

HEREBY CERTIFIES THAT

Megan Vala

HAS SUCCESSFULLY COMPLETED A 16 HOUR COURSE ENTITLED

Asbestos Management Planner Initial

INCLUDING CLASSROOM INSTRUCTION

05/21/2015 to 05/22/2015


Exam passed on this 22nd day of May 2015 - Score - 94

Approved for AHERA Accreditation Under TSCA Title II

3370 Progress Drive, Suite J
Bensalem, PA 19020
(215) 244-1300 - Phone
(215) 244-4349 - Fax
www.criterionlabs.com

Course is conducted in English

DIRECTOR:


James A. Welte, CIH, President

Certificate of Training

CRITERION LABORATORIES, INC.

HEREBY CERTIFIES THAT

Mary Anne Lerro

HAS SUCCESSFULLY COMPLETED A 4 HOUR COURSE ENTITLED
Asbestos Management Planner Refresher

INCLUDING CLASSROOM INSTRUCTION

on this 5th day of April 2016

Approved for AHERA Accreditation Under TSCA Title II

3370 Progress Drive, Suite J
Bensalem, PA 19020
(215) 244-1300 - Phone
(215) 244-4349 - Fax
www.criterionlabs.com

Course is conducted in English

DIRECTOR:

James A. Welts
James A. Welts, CIH, President

EMSL ANALYTICAL, INC.

Certifies that

Scott Magee

has successfully completed the course of study for the

Asbestos Building Inspector Refresher Course for Accreditation under TSCA Title II

EMSL Certificate No. 70016699C


Approved by:

PA Dept. of Labor and Industry
Accreditation # 137

Course Date: 8/15/2015
Granted: 8/15/2015
Expiration Date: 8/15/2016

Sponsored by:

EMSL Analytical, Inc.
200 Route 130 North
Cinnaminson, NJ 08077
Phone: (800) 220-3675
Fax: (856) 786-5973
www.emsl.com



Michael P. Menz

Michael P. Menz, CIH
Training Director

Environmental, Mold, Bacteria, IAQ, Asbestos, Lead, Forensic and Materials Testing Since 1981

EMSL ANALYTICAL, INC.

Certifies that

William Garrity

has successfully completed the course of study for the

Asbestos Building Inspector Refresher Course

for Accreditation under TSCA Title II

EMSL Certificate No. 70016699A


Approved by:

PA Dept. of Labor and Industry
Accreditation # 137

Course Date: 8/15/2015
Granted: 8/15/2015
Expiration Date: 8/15/2016

Sponsored by:

EMSL Analytical, Inc.
200 Route 130 North
Cinnaminson, NJ 08077
Phone: (800) 220-3675
Fax: (856) 786-5973
www.emsl.com



Michael P. Menz

Michael P. Menz, CIH
Training Director

Environmental, Mold, Bacteria, IAQ, Asbestos, Lead, Forensic and Materials Testing Since 1981

45397

National Asbestos & Environmental Training Institute

CERTIFICATE OF COMPLETION

AHERA/EPA Accredited Per 40 CFR Part 763
Asbestos Accreditation under TSCA Title II

This is to certify that

Bernard Brunner, Jr.

Successfully completed the course entitled

**1/2-Day New York State/EP A/AHERA Asbestos Building Inspector Annual Refresher on
October 2, 2015**

Examination Passed October 2, 2015

Expiration Date on October 2, 2016


Doris L. Adler
President, NAEETI

Per 10 NYCRR Part 73.2 (L) (1), DOH 2832 Certificate of Completion of Asbestos
Safety Training is the only official record of training for N.Y.S. students.

Language: English

ABIH 1/2 CM POINT

3321 Doris Avenue, Building B, Ocean, NJ 07712

Phone (732) 531-5571

Fax (732) 531-5956

www.naeti.com

Number 740092

Expiration Date:
03/03/2016

Certificate of Training

CRITERION LABORATORIES, INC.

HEREBY CERTIFIES THAT

Mary Anne Lerro

HAS SUCCESSFULLY COMPLETED A 4 HOUR COURSE ENTITLED

Asbestos Building Inspector Refresher

on this 3rd day of March 2015

Exam passed on this 3rd day of March 2015 - Score - 84

Approved for AHERA Accreditation Under TSCA Title II

3370 Progress Drive, Suite J
Bensalem, PA 19020
(215) 244-1300 - Phone
(215) 244-4349 - Fax
www.criterionlabs.com

Course is conducted in English

DIRECTOR:

James A. Welts

James A. Welts, CIH, President

Certificate of Training

CRITERION LABORATORIES, INC.

HEREBY CERTIFIES THAT

Mary Anne Lerro

HAS SUCCESSFULLY COMPLETED A 4 HOUR COURSE ENTITLED

Asbestos Building Inspector Refresher

INCLUDING CLASSROOM INSTRUCTION

on this 5th day of April 2016

Exam passed on this 5th day of April 2016 - Score - 88

Approved for AHERA Accreditation Under TSCA Title II

3370 Progress Drive, Suite J
Bensalem, PA 19020
(215) 244-1300 - Phone
(215) 244-4349 - Fax
www.criterionlabs.com

Course is conducted in English

DIRECTOR:

James A. Wells

James A. Wells, CIH, President

Certificate of Completion

James Madden

for successfully completing the prescribed course of study in

Pennsylvania Asbestos Building Inspector Refresher Course

under TSCA Title II

presented by

ACCESS TRAINING SERVICES, INC.
7921 River Road, Pennsauken, NJ 08110
(856) 665-3449

12/11/14

Course Date

N/A

Exam Date

12/11/15

Expiration Date

Not Provided

Social Security Number

ACC-1214-6-010

Certificate Number

Mark K. Schlager
Mark K. Schlager
Training Director

Certificate of Completion

James Madden

for successfully completing the prescribed course of study in

Pennsylvania Asbestos Building Inspector Refresher Course

under TSCA Title II

presented by

ACCESS TRAINING SERVICES, INC.
7921 River Road, Pennsauken, NJ 08110
(856) 665-3449

12/3/15

Course Date

N/A

Exam Date

12/3/16

Expiration Date

Not Provided

Social Security Number

ACC-1215-6-018

Certificate Number

Mark K. Schlager
Mark K. Schlager
Training Director

Certificate of Completion

Troy A. Ray

for successfully completing the prescribed course of study in

Pennsylvania Asbestos Building Inspector Refresher Course

under TSCA Title II

presented by

ACCESS TRAINING SERVICES, INC.
7921 River Road, Pennsauken, NJ 08110
(856) 665-3449

3/19/15

Course Date

N/A

Exam Date

3/19/16

Expiration Date

Not Provided

Social Security Number

ACC-0355-6-011

Certificate Number

Mark K. Schlager
Training Director

CERTIFICATE NO 374

G&C Environmental Services, Inc. (#294)

2 Street Road, Newtown Square, Pennsylvania 19073

Telephone: (610) 993-9202 Facsimile: (610) 993-9232

Email: Training@gcenviro.com

www.GCenviro.com

This document certifies that Ananth K. Vinjamuri has successfully completed this State of New York Department of Health Approved AHERA BUILDING INSPECTOR

REFRESHER COURSE, completed as required for asbestos accreditation under the Toxic

Substances Control Act, Title II. This course was held from 09/29/2015 to 09/29/2015.

The examination date was 09/29/2015. This certificate expires one year from the date of
successful completion of the examination 09/29/2016.

The official record of successful training completion is the New York State Department of Health certificate of asbestos safety training completion (DPH 2832).

Gail M. Conner
Training Director

Gail M. Conner

CERTIFICATE NO 375

G&C Environmental Services, Inc. (#294)

2 Street Road, Newtown Square, Pennsylvania 19073

Telephone: (610) 993-9202 Facsimile: (610) 993-9232

Email: Training@gcenviro.com

www.GCenviro.com

This document certifies that Shelton Williams has successfully completed this
State of New York Department of Health Approved AHERA BUILDING INSPECTOR

REFRESHER COURSE, completed as required for asbestos accreditation under the Toxic

Substances Control Act, Title II. This course was held from 09/29/2015 to 09/29/2015.
MM DD YR MM DD YR

The examination date was 09/29/2015. This certificate expires one year from the date of
MM DD YR MM DD YR
successful completion of the examination 09/29/2016.
MM DD YR

*The official record of successful training completion is the New York State Department of
Health certificate of asbestos safety training completion (DPH 2832).*

Gail M. Conner
Training Director

Gail M. Conner

Certificate of Completion

Paul M. Davis

for successfully completing the prescribed course of study in

Pennsylvania Asbestos Building Inspector Refresher Course

under TSCA Title II

presented by

ACCESS TRAINING SERVICES, INC.
7921 River Road, Pennsauken, NJ 08110
(856) 665-3449

2/12/15

Course Date

N/A

Exam Date

2/12/16

Expiration Date

Not Provided

Social Security Number

ACC-0215-6-015

Certificate Number

Mark K. Schlager
Training Director

Certificate of Training

CRITERION LABORATORIES, INC.

HEREBY CERTIFIES THAT

Paul M. Davis

HAS SUCCESSFULLY COMPLETED A 4 HOUR COURSE ENTITLED
Asbestos Building Inspector Refresher

INCLUDING CLASSROOM INSTRUCTION

on this 2nd day of February 2016

Exam passed on this 2nd day of February 2016 - Score - 92

Approved for AIHERA Accreditation Under ISCA Title II

3370 Progress Drive, Suite J
Bensalem, PA 19020
(215) 244-1300 - Phone
(215) 244-4349 - Fax
www.criterionlabs.com

Course is conducted in English

DIRECTOR:

James A. Wells

James A. Wells, CIH, President

Certificate of Completion

Bernard J. Bryson

for successfully completing the prescribed course of study in

Pennsylvania Asbestos Building Inspector Refresher Course

under TSCA Title II

presented by

ACCESS TRAINING SERVICES, INC.
7921 River Road, Pennsauken, NJ 08110
(856) 665-3449

2/16/15
Course Date

N/A

Exam Date

2/16/16

Expiration Date

Not Provided

Social Security Number

ACC-0125-6-031

Certificate Number

Mark K. Schlager
Training Director

Certificate of Completion

Bernard J. Bryson

for successfully completing the prescribed course of study in

Pennsylvania Asbestos Building Inspector Refresher Course

under TSCA Title II

presented by

ACCESS TRAINING SERVICES, INC.
7921 River Road, Pennsauken, NJ 08110
(856) 665-3449

2/15/16

Course Date

N/A

Exam Date

2/15/17

Expiration Date

Not Provided

Social Security Number

ACC-0216-6-005

Certificate Number

Mark K. Schlager
Training Director

EHS TRAINING INSTITUTE, INC.

A Division of BATTI, Inc.

Certificate of Completion

AHERA Building Inspector

(Refresher)

Awarded To:

Alexander Roman

SS#:XXX-XX-1743

Who has completed this 4-hour course and examination,

EPA Approved under TSCA Title II

AHERA / ASHARA Rule

40 CFR Part 763.

EHS TRAINING INSTITUTE, INC.

A Division of BATTI, Inc.

Delaware Industrial Park • 6 Garfield Way

Newark, DE 19713-5817

(302) 737-3376 • Fax (302) 737-5764

Course Date: September 18, 2015

Date of Expiration: September 18, 201

Certification Number : EHSBIR 150619-008


Todd K. Zeisloff, Instructor


Neeraj K. Batta, President

Certificate of Completion

Norman Harrison

for successfully completing the prescribed course of study in

Pennsylvania Asbestos Building Inspector Refresher Course

under TSCA Title II

presented by

ACCESS TRAINING SERVICES, INC.
7921 River Road, Pennsauken, NJ 08109
(856) 665-3449

9/2/15

Course Date

N/A

Exam Date

9/2/16


Expiration Date

Not Provided

Social Security Number

ACC-0915-6-011

Certificate Number


Mark A. Schlenger
Training Director

EHS TRAINING INSTITUTE, INC.
A Division of BATTI, Inc.

Certificate of Completion

AHERA Building Inspector

(Refresher)

Awarded To:

Kelly Mayberry

SS#:XXX-XX-1551

Who has completed this 4-hour course and examination,
EPA Approved under TSCA Title II
AHERA / ASHARA Rule
40 CFR Part 763.

EHS TRAINING INSTITUTE, INC.

A Division of BATTI, Inc.

Delaware Industrial Park • 6 Garfield Way

Newark, DE 19713-5817

(302) 737-3376 • Fax (302) 737-5764

Course Date: February 20, 2015

Date of Expiration: February 20, 2016

Certification Number : EHSBIR 150220-005


Todd K. Zeisloft, Instructor


Neeraj K. Batta, President

EHS TRAINING INSTITUTE, INC.
A Division of BATTI, Inc.

Certificate of Completion

AHERA Building Inspector

(Refresher)

Awarded To:

Kelly Mayberry

SS#:XXX-XX-1551

Who has completed this 4-hour course and examination,

EPA Approved under TSCA Title II

AHERA / ASHARA Rule

40 CFR Part 763.

EHS TRAINING INSTITUTE, INC.

A Division of BATTI, Inc.

Delaware Industrial Park • 6 Garfield Way

Newark, DE 19713-5817

(302) 737-3376 • Fax (302) 737-5764

Course Date: February 18, 2016

Date of Expiration: February 18, 2017

Certification Number : EHSBIR 160218-006



Todd K. Zeisloft, Instructor



Neeraj K. Batta, President

AEROSOL MONITORING & ANALYSIS, INC.

This is to certify that
ANDREW HINE

*has met the attendance requirements and successfully completed
the course entitled*

3-DAY EPA AHERA INSPECTOR
For Accreditation Under TSCA Title II

05/04/2015 to 05/06/2015

Course Date

05/06/2015

Exam Date

5/6/2016

Expiration Date

STEVE SIERAGI

Principal Instructor

Steve Sieragi

A105042015-3

Certification No.

E. Rush Barnett

Course Director

E. Rush Barnett

1331 Ashton Road

P.O.Box 646

Hanover, MD 21076

P: 410-684-3327

F: 410-684-3724

www.amatraining.com

Certificate of Completion

Maryellen Leotta

for successfully completing the prescribed course of study in

Pennsylvania Asbestos Building Inspector Refresher Course

under TSCA Title II

presented by

ACCESS TRAINING SERVICES, INC.
7921 River Road, Pennsauken, NJ 08110
(856) 665-3449

2/12/15

Course Date

N/A

Exam Date

2/12/16

Expiration Date

Not Provided

Social Security Number

ACC-0215-6-024

Certificate Number

Mark K. Schlüger
Training Director

Asbestos Hazard Emergency Response Act (AHERA) Environmental Compliance Audit Cross Reference Table

In response to the AHERA Environmental Compliance Audit a Cross Reference Table has been prepared for inclusion into the Environmental Management Plan. The purpose of this Cross Reference Table is to link the following documents to the AHERA Management Plan.

Cross Reference Table	
3 Year Reinspection Report follows this Cross Reference Table documentation.	
Subject Matter	Location of Required Documents
Designated Person	Pages 1 - 3
Annual Notification	Pages 4 - 5
6 Month Periodic Surveillance Outline of Events	Page 6
3 Year Re-inspections Outline of Events	Page 7
Asbestos Management Program (operations and maintenance)	Pages 8 - 19
Asbestos Investigation Report (AIR)	Attachment 1 Letter Dated August 4, 2006
Training (included in the Asbestos Management Program)	<p>The original records are centralized at the School District's Environmental Library. Copies are maintained on staff and are required to be maintained in the latest Reinspection Report.</p> <p>2 hour awareness training records for all Building Engineers, Custodian Assistants and maintenance personnel</p> <p>40 hour worker/supervisor training records for the OEMS A-Team and various AST tradesmen.</p>
Response Actions (monthly mailings if applicable)	<p>The original documents are on file at the School District's Environmental Library.</p> <p>Copies of the original are mailed to the Schools Main Office for retention with the Management Plan documentation. These documents are typically kept separate from the management plan in an update binder due to the potential volume of response action reports.</p>

SCHOOL DISTRICT OF PHILADELPHIA

ASBESTOS DESIGNATED PERSON

Gerald F Junod
Office of Capital Programs
Environmental Management & Services
440 N Broad Street, 3rd Floor
Philadelphia, PA 19130
Telephone: 215 400 6738
Fax: 215 400 4751

Drexel University- Asbestos Building Inspector Course	January 9-11, 1989 24 Hours
Drexel University- Asbestos Management Planner Course	January 12-13, 1989 16 Hours
Criterion Laboratories, Inc. - Asbestos Management Planner Course	October 11-12, 2012 16 Hours

<u>Annual Building Inspector Refreshers</u>	1990 to Present
4 Hours	
Drexel University	
Criterion Laboratories, Inc	
Access Training Services, Inc.	

<u>Annual Building Management Planner Refreshers</u>	1990 to 1994
4 Hours	
Drexel University	
Criterion Laboratories, Inc	2013 to Present
4 Hours	

Environmental Manager, School District of Philadelphia

Manages the design and implementation of asbestos and lead projects for the Capital Improvement Program and other District Departments including Facilities & Operations and Information Technology. Ensures that asbestos abatement and lead remediation projects are expertly designed and executed in accordance with industry best management practice standards and regulations.

Manager, City of Philadelphia Asbestos Control Program

Served as the Asbestos Control Program Manager for the City of Philadelphia, Department of Public Health, Air Management Services, Asbestos Control Unit from August 1, 2003 through October 23, 2006.

Mid Atlantic Regional Environmental Consortium (MAREC)

Former member with attendance and participation commitments of all quarterly EPA Region III and yearly National Asbestos Regulatory Conferences sponsored by the EPA and the National Conference of State Legislators respectively as a representative for the City of Philadelphia Department of Public Health Air Management Services from 1994 through 2006.

Philadelphia Environmental Task Force

Former member of the Philadelphia Environmental Task force as a representative and point of contact for the City of Philadelphia Department of Public Health Air Management Services Asbestos Control Unit from 2002 through 2006.

Asbestos Instructor

Worked as the primary instructor for the initial and annual Asbestos Project Inspector training and licensing program as mandated by City of Philadelphia Department of Public Health Asbestos Control Regulations from August 1994 through October 2006.

Worked as a lead instructor with an Environmental Consulting Firm and approved by the US EPA for the initial and annual refresher training courses for various asbestos occupational disciplines such as the Building Inspector, Management Planner and Worker/Supervisor from 1991 through 1994.

I certify that the general, local agency responsibilities as stipulated in Section 763.84 will be met.



Gerald F. Junod
Asbestos Designated Person
Environmental Manager
Office of Environmental Management and Services

SCHOOL DISTRICT OF PHILADELPHIA

Accreditation Information Statement

All persons who inspect for Asbestos Containing Building Materials (ACBM) and who will design or carry out response actions with respect to assumed and confirmed ACBM, will be accredited by an EPA approved course and/or a State Contractors Accreditation Program under Sections 206 (c) and 206 (b) of Title II of the ACT.

A handwritten signature in black ink, appearing to read 'Gerald F. Junod', is written over the printed name and title.

**Gerald F. Junod
Asbestos Designated Person
Environmental Manager
Office of Environmental Management and Services**

SCHOOL DISTRICT OF PHILADELPHIA
OFFICE OF CAPITAL PROGRAMS
440 NORTH BROAD STREET, SUITE 373
PHILADELPHIA, PENNSYLVANIA 19130

OFFICE OF ENVIRONMENTAL MANAGEMENT AND SERVICES

PHONE (215)-400-4750

September 2015

TO: Principals
Building Administrators/Occupants
Parents/Guardians

FROM: Fran Burns
Chief Operating Officer

Francine Locke, M.S., Director
Office of Environmental Management and Services

SUBJECT: Annual EPA Notification Letter

Pursuant to the Federal Environmental Protection Agency (EPA) mandate, as required by 40 C.F.R. 763.84 (c)(d) of public access to environmental records, this letter is to acknowledge the availability of your facility's Asbestos Hazard Emergency Response Act (AHERA) Management Plan.

Each member of the school staff, parents/guardians, temporary workers and/or contractors, are required to receive a copy of the Notification Letter. At the direction of the Principal, a copy is to be posted on the bulletin boards and an appropriate amount of copies are to be generated for distribution.


Note: The AHERA Three-Year Reinspection reports, in colored binders; White with Pink, Tan, Black, Red, Dark Blue, Green, Yellow and White, are Federal EPA mandated inspection documents. The School District of Philadelphia is subject to severe monetary penalties if the reports and associated paperwork are not available to the EPA and the public upon request.

It is incumbent on designated school personnel to gather and retain this data as it is delivered, in one location for future review. Acceptable locations include the Principal's Office or Main Office for the primary data. The Building Engineer should maintain any secondary or duplicate copies.

If you have any questions, please call 215-400-4750. Thank you for your cooperation.



Fran Burns
Chief Operating Officer



Francine Locke, M.S., Director
Office of Environmental Management
and Services

c: Danielle Floyd

AHERA-4
8/21/15



School District of Philadelphia
OFFICIAL NOTICE

PLEASE POST

September 2015

TO: Principals
Building Administrators
Building Engineers
Building Occupants
Parents/Guardians

FROM: Fran Burns
Chief Operating Officer

Francine Locke, M.S., Director
Office of Environmental Management and Services

SUBJECT: Annual Notification Letter: Asbestos Hazard Emergency Response Act

The Federal Register published on October 30, 1987, Subpart E, in Schools: Final Rule and Notice, 763.84 (c)(d) states that each local education agency shall ensure that workers and building occupants or guardians are to be informed at least once each school year about inspections, response actions and post-response action activities including re-inspections and periodic surveillance activities. The School District as the Local Education Agency (LEA), retains such reports that are available for public inspection in the Office of the Principal or Building Administrator.

The Principal or Building Administrator is required to do the following with this notification:

- 1) Post in a Public Place or Main Office
- 2) Inform Building Occupants
- 3) Send a copy of this notification to Parents or Guardians
- 4) Insert a copy into the latest AHERA Three-Year Reinspection report (white/pink binder) in your office or facility.

Handwritten signature of Fran Burns in black ink.

Fran Burns
Chief Operating Officer

Handwritten signature of Francine Locke in black ink.

Francine Locke, M.S., Director
Office of Environmental Management
and Services

c: Danielle Floyd

AHERA-4a
8/21/15

SCHOOL DISTRICT OF PHILADELPHIA
Education Center
440 North Broad Street
Philadelphia, Pennsylvania 19130

Office of Environmental Management and Services

215-400-4750

AHERA
Six Month Surveillance
Outline of Events

- Pursuant to the Federal Environmental Protection Agency (EPA) mandate, as required by 40 CFR 763.92(b), the following procedure is to be implemented. At least once every six (6) months after a Management Plan is in effect, each Local Education Agency (LEA) shall conduct a periodic surveillance in each building that it owns or leases that contains Asbestos Containing Building Materials (ACBM) or is assumed to contain ACBM.
- The first Bi-Annual Inspection starts in the Spring (March, April, May) and again in the Fall (October, November, December) of each year. The Building Engineer/Assistant should assist the Building Inspector with appropriate access to all areas including (Crawlspaces/Attics) and rooms in the facility. There is no action required of the Principal.
- The Building Inspector shall visually inspect all areas that are identified in the Management Plan as ACBM or assumed ACBM. The date of the surveillance is recorded, the inspectors name and any changes in the conditions of the materials.
- The Building Inspector shall make a copy of the inspection document and insert into the front of the latest Management Plan (AHERA Three Year Reinspection report). The original document is returned to the LEA's Environmental Library and filed.

SCHOOL DISTRICT OF PHILADELPHIA
Education Center
440 North Broad Street
Philadelphia, Pennsylvania 19130

Office of Environmental Management and Services

215-400-4750

AHERA
Three Year Reinspection
Outline of Events

- Pursuant to the Federal Environmental Protection Agency (EPA) mandate, as required by 40 CFR 763.85(b) the following procedure is to be implemented. At least once every three (3) years after a Management Plan is in effect, each Local Education Agency (LEA) shall conduct a reinspection of each building that it owns or leases that contains Asbestos Containing Building Material's (ACBM's) or is assumed to contain ACBM.
- Subsequent Three Year Re-inspections (2009, 2012, 2015, etc) shall start in the Fall (October, November, December, January). The Building Engineer/Assistant should assist the Building Inspector with appropriate access to all areas including (Crawlspaces/Attics) and rooms in the facility. There is no action required of the Principal.
- An accredited Building Inspector shall visually inspect and touch to determine friability, all areas that are identified in the Management Plan as ACBM or assumed ACBM. The date of the surveillance is recorded, the inspectors name and any changes in the conditions of the materials. The Building Inspectors state of accreditation and license number is required.
- After the inspection, the Building Inspector shall make a copy of the inspection documents and insert into the front of the latest Management Plan (AHERA Three Year Reinspection report). The original document is returned to the LEA's Environmental Library and filed.
- The Building Inspector shall return the reinspection data to the Management Planner to be assessed and determine appropriate response actions and a report issued (AHERA Three Year Reinspection report). One copy of the report is delivered to the schools Principal to be permanently retained with all previous environmental data. Another copy is retained in the LEA's Environmental Library.



School District of Philadelphia
Office of Environmental Management & Services
440 North Broad Street
Philadelphia, PA 19130
(215) 400-4750

**School District of Philadelphia
Asbestos Management Program**

TABLE OF CONTENTS

Definitions.....	Page 9
1. Introduction.....	Page 10
2. Summary of Asbestos Management Plan	
3. Asbestos Management Plan Execution.....	Page 11
a. General Execution	
4. Summary of Program Execution	
a. Asbestos Management Plan Execution	
5. Responsibilities	
a. OEMS	
b. Asbestos Worker/Supervisor “A-TEAM”.....	Page 12
c. Asbestos Designated Person	
d. Supervisor or Project Manager (Capital, Maintenance & Facilities)	
e. Employee Capital.....	Page 13
f. Employee Maintenance	
g. Employee Facilities and Custodial	
6. Requirements.....	Page 14
a. Employee Exposure Monitoring	
b. Employee Notification	
c. Observation of Monitoring	
d. Training Program	
e. Access of Information	
f. Record Keeping	
7. AHERA O&M Plan.....	Page 15
a. Controls	
8. O&M Response Actions.....	Page 16
a. Facility Maintenance Isolation of Area	
b. Unlikely Contact with ACM/PACM	
c. Accidental Disturbance of ACM/PACM	
d. Planned Disturbance of ACM/PACM	
e. Miscellaneous ACM/PACM.....	Page 17
f. Vinyl Asbestos Floor Tile	
g. Mastic/Adhesives	
h. Woven Vibration Dampers	
i. Other Work Practices	
j. Fiber Release Episodes	
9. References and Resources.....	Page 18

DEFINITIONS / ACRONYMS

ACM/PACM:	Asbestos Containing Material/Potential Asbestos Containing Material
AHERA:	Asbestos Hazard Emergency Response Act
AIR FORM:	Asbestos Inspection Report Form
Amended Water:	Water to which a surfactant (soap) has been added
AMP:	Asbestos Management Program/Asbestos Management Plan
Asbestos Designate Person:	Individual assigned by the district to oversee asbestos related issues.
Asbestos Regulated Area:	Location that is posted as an asbestos work area in which only approved and accredited personnel are permitted to enter
AST:	Asbestos Support Team involving approved and accredited school district tradespersons personnel that are school district person
A-TEAM:	School District of Philadelphia asbestos workers
CIP:	Capital Improvement Program
Consultant:	Asbestos consulting firm hired by the District
Demolition Directive:	Memorandum – August 4, 2006 from Patrick Henwood
EPA:	Environmental Protection Agency
In House Personnel:	School District of Philadelphia asbestos workers
LEA:	Local Education Agency
O&M:	Operations and Maintenance
OEMS:	Office of Environmental Management and Services
OSHA:	Occupational Safety and Health Administration
PEL:	Permissible Exposure Limit
PSD or SDP:	Philadelphia School District/School District of Philadelphia
PSIT:	Philadelphia School Improvement Team
STEL:	Short Term Exposure Limit

1. Introduction

The School District of Philadelphia, Asbestos Policy Statement:

“The School District of Philadelphia is dedicated to providing a safe and healthful work environment for its employees, students, faculty, contractors and visitors. In recognition of the potential health problems associated with asbestos, the School District of Philadelphia is committed to a comprehensive asbestos control program. This program is implemented and maintained through the School District of Philadelphia's Office of Environmental Management and Services (OEMS).”

OEMS has the responsibility of establishing procedures for asbestos abatement, asbestos inspection, air monitoring, renovation and demolition activities within all School District of Philadelphia owned or leased facilities.

These procedures are developed to ensure that:

- (1) People are not exposed to significant levels of asbestos fibers
- (2) Asbestos waste is handled and disposed of properly
- (3) Members of the School District of Philadelphia community have access to the Office of Environmental Management and Services for information, assistance, guidance, and interpretation regarding asbestos related matters.
- (4) Members of the School District of Philadelphia community have access to the Asbestos Management Plans as required and outlined in the US EPA AHERA regulations including annual written notification to all parents.
- (5) Compliance with all applicable Federal, State and Local Asbestos Regulations

Requirements outlined in this manual are mandatory in nature where the word “SHALL” is used and are advisory in nature where the word “SHOULD” is used.

2. Summary of Asbestos Management Program

The School District of Philadelphia’s Asbestos Management Program was established to meet the requirements of Federal, State, and Local Regulations.

These regulations include, but are not limited to:

- US Environmental Protection Agency Asbestos Hazard Emergency Response Act (US EPA AHERA) and National Emissions Standard for Hazardous Air Pollutants subpart M, Part 61 (NESHAP);
- US Department of Labor, Occupational Safety and Health Administration (OSHA) General Industry Standard (29 CFR 1910.1001) and the OSHA Asbestos Standard for the Construction Industry (29 CFR 1926.1101);
- The Commonwealth of Pennsylvania, Department of Labor and Industry, Asbestos Occupations, Accreditation and Certification Act;
- The City of Philadelphia, Department of Public Health, Asbestos Control Regulations.

3. Asbestos Management Program Execution

a) General Execution

The Office of Environmental Management and Services (OEMS) develops, implements and manages safety and health programs for the School District of Philadelphia faculty, staff and students and assists with ensuring that all contractors comply with Federal, State and Local Environmental Regulations. The OEMS provides the oversight of School District of Philadelphia employees (Asbestos A-Team), environmental consultants, and asbestos abatement contractors for all projects within the School District of Philadelphia concerning Asbestos Containing Materials.

The control of safety and health hazards at the School District of Philadelphia is primarily through the implementation of engineering, work practice and administrative controls. Personal Protective Equipment (PPE) is used to supplement these controls or whenever the controls are not feasible or are in the process of being implemented. PPE is also recommended whenever exposures to chemical, physical or biological agents can be prevented or reduced by its use.

This written program establishes the procedures necessary to:

- 1) meet established standards and federal regulations for occupational exposure to asbestos fibers;
- 2) meet the requirements of the City of Philadelphia Asbestos Control Regulations which encompasses the disturbance and/or abatement of asbestos containing building materials;
- 3) provide the necessary health and safety protection to the School District of Philadelphia staff, faculty, students, contractors and visitors.

This program is strengthened by input and cooperation with the Philadelphia Federation of Teachers (PFT), Health and Welfare Fund.

4. Summary of Program Execution

a) Asbestos Management Program Execution

The Asbestos Management Program is administered by the Office of Environmental Management and Services (OEMS). OEMS provides the following services primarily through professional consultants:

- (1) exposure monitoring services;
- (2) building inspection/surveys (bulk sampling) for the identification of asbestos containing materials;
- (3) asbestos project design services;
- (4) asbestos abatement project and air monitoring services;
- (5) emergency response to fiber release episodes;
- (6) education/information;
- (7) medical monitoring;
- (8) training for School District of Philadelphia personnel

5. Responsibilities

a) Office of Environmental Management and Services

OEMS is responsible for performing the following functions:

- (1) Developing and administering of the Asbestos Management Program.
- (2) Providing asbestos-related services to all School District of Philadelphia departments.
- (3) Conducting required training of the Asbestos Management Program and working jointly with departments to schedule training.
- (4) Identifying and posting areas where labeling/signage are required.
- (5) Medical Monitoring of OEMS "A-TEAM" and other departments "AST" Asbestos Program staff.

- (6) Certification and training as required for OEMS "A-TEAM" and other departments "AST" Asbestos program staff.
- (7) Record keeping as outlined in Section 3.5 and all records as by required by US EPA AHERA regulations.

b) Asbestos Worker/Supervisor - "A-TEAM"

- (1) OEMS shall ensure that all "A-TEAM" workers/supervisors adhere to the following requirements:
 - a) Attend an initial Worker/Supervisor Asbestos Course;
 - b) Maintain the annual re-certification per EPA AHERA requirements and Commonwealth of Pennsylvania Asbestos Occupations, Accreditation and Certifications Act;
 - c) Undergo an annual Asbestos Medical Evaluation;
 - d) Undergo an annual Respirator Medical Clearance;
 - e) Undergo an annual Respirator Fit Testing.

c) Asbestos Designated Person

The Asbestos Designated Person is responsible for:

- (1) Assuring the health and safety of employees, students and visitors in the School District of Philadelphia facilities under his/her control.
- (2) Being kept informed of all areas under his or her jurisdiction where potential asbestos exposures exist and initiating protection programs that adhere to the Asbestos Management Program requirements of this manual.
- (3) Assuring that Asbestos Management Program requirements are adhered to by principal investigators, project managers, supervisors, or division heads, and School District of Philadelphia personnel under their supervision.
- (4) Ensuring that all employees within the Asbestos Management Program comply with (OSHA 1910.1001 (j) (7) (iv)) and the US EPA AHERA regulations by attending the required training.
- (5) Ensure the posting of:
 - a) Warning labels/signage
 - b) Commonwealth of Pennsylvania Asbestos Abatement and Demolition/Renovation Notification form
 - c) Asbestos Inspection Reports (AIR) form (where required)
 - d) Ensuring that Construction Projects follow the Demolition Directive procedures as outlined in the August 4, 2006 letter.

d) Supervisor or Project Manager (Capital, Maintenance and Facilities)

Each person in charge of a project, maintenance/repair, renovation/demolition, or other activity from the Departments of Capital, Maintenance, and/or Facilities, where asbestos containing material may be present is responsible for:

Identifying, with the assistance of OEMS, asbestos containing building materials prior to any disturbance of these materials. Various Federal (EPA and OSHA) and Local (City of Philadelphia Asbestos Control Regulations) require Asbestos Inspections prior to renovation/demolition activities. This shall be accomplished by always following the Asbestos Management Program Procedures as follows:

- (1) Ensure that the requirements of the Asbestos Management Program Procedures are followed by all personnel, trades, and contractors who are involved with the project;

- (2) Review of the required Asbestos Inspection Report (AIR) form (Attachment 1) and AHERA Management Plan documents prior to activities that may disturb any Asbestos Containing Materials;
- (3) Perform all project related duties as outlined in the Project Management Responsibilities;
- (4) Keep the department chairperson or director informed on any actions proposed or taken regarding the Asbestos Management Plan;
- (5) Ensuring that Construction Projects follow the Demolition Directive procedure outlined in the August 4, 2006 letter.

e) Employee – Capital

School District of Philadelphia Capital employees and/or consultants shall:

- (1) Ensure that no suspect or asbestos containing building materials are disturbed in the course of the projects they are performing or managing. This shall be accomplished by notifying their supervisor and OEMS by issuance of a work order permit (a.k.a PSIT Service Request Form) and verifying that the materials which may be disturbed are non-asbestos containing. If this information is not available or verification has not been made, these materials should not be disturbed.
- (2) Immediately notify OEMS and their supervisor in the event of a potential fiber release episode upon discovery of visible damage to asbestos containing materials.
- (3) Ensuring that Construction Projects follow the Demolition Directive procedures as outlined in the August 4, 2006 letter.

The types of projects represented as part of the Capital Improvement Program are as follows:

- (1) Complete Renovation of an existing building that addresses all facility component concerns and educational program needs;
- (2) Major Renovation of an existing building addressing significant facility component and educational improvements;
- (3) Addition to an existing building (either as an attachment or stand-alone structure) to accommodate needed program space;
- (4) Conversion of an existing facility to accommodate a change in educational program;
- (5) Facility Component Improvement of specific facility needs (i.e. electrical or HVAC system upgrades, ADA improvements, life safety improvements, exterior renovations, etc.)

f) Employee – Maintenance

School District of Philadelphia Maintenance employees shall:

- (1) Ensure that no suspect or asbestos containing building materials are disturbed in the course of their duties or work they are performing. This shall be accomplished by notifying their supervisor and OEMS by issuance of a work order permit and verifying that the materials which may be disturbed are non-asbestos containing. If this information is not available or verification has not been made, these materials should not be disturbed.
- (2) Immediately notify OEMS and their supervisor in the event of a potential fiber release episode or upon discovery of visible damage to asbestos containing materials.
- (3) All employees involved in maintenance activities shall attend required Asbestos Awareness training program within 60 days of employment.

g) Employee – Facilities & Custodial

School District of Philadelphia Facilities and Custodial employees shall:

- (1) Ensure that no suspect or asbestos containing building materials are disturbed in the course of their duties or work they are performing. This shall be accomplished by notifying their supervisor and OEMS by issuance of a work permit and verifying that the materials which may be disturbed are non-asbestos containing. If this information is not available or verification has not been made, these materials should not be disturbed;
- (2) Immediately notify OEMS and their supervisor in the event of a potential fiber release episode or upon discovery of visible damage to asbestos containing materials.
- (3) All employees involved in Facilities and Custodial activities shall attend require Asbestos Awareness training program within 60 days of employment.

6. Requirements

a) Employee Exposure Monitoring

When information indicates that an employee's exposure to asbestos fibers may equal or exceed an 8-hour time-weighted average of 0.1 f/cc * (per OSHA 1910.1001 & 1926.1101), OEMS shall develop and implement an asbestos exposure monitoring program. The sampling strategy shall be designed to identify employees by work task (job classification) that is exposed to asbestos fibers that exceed an 8-hour time-weighted average of 0.1 f/cc.

b) Employee Notification

OEMS shall notify in writing, each employee exposed to asbestos fibers at or above an 8-hour time weighted average of 0.1 f/cc.

c) Observation and Monitoring

OEMS shall provide employees or their representatives with an opportunity to observe any exposure measurements conducted.

d) Training Program

OEMS shall institute a training program which meets the requirements of AHERA for all employees who perform maintenance operations in a facility/school which contains asbestos containing materials or presumed asbestos containing materials and 1910.1001 (j), and the Commonwealth of Pennsylvania Department of Labor and Industry and the City of Philadelphia Asbestos Control Regulations. The affected departments shall ensure employee participation in this program. The OEMS "A-TEAM" and other departments "AST" Asbestos Program staff training shall be conducted annually for each employee as required by all Federal, State and Local for each asbestos discipline.

All Asbestos Awareness training as required by AHERA shall be performed within 60 days of employment and shall include:

- Health effects of asbestos
- Locations of ACM and PACM in the building/facility
- Recognition of CM and PACM damage and deterioration
- Requirements of the OSHA 1910.1001 standard relating to maintenance
- Proper response to fiber release episodes
- Procedure to be followed to isolate areas affected by fiber release

e) Access to Information

OEMS shall make available to affected employees or their representative's copies of the Occupational Safety and Health Administration (OSHA) General Industry Standard Part 1910.1001 and the department shall post a copy in the workplace.

f) Record Keeping

OEMS shall maintain an accurate record of all employee exposure measurements. OEMS and/or the School District of Philadelphia Human Resources Department shall maintain records of employee medical monitoring program. OEMS shall maintain all employee training records. All records shall be provided upon request to employees, former employees, representatives designated by the individual employee.

7. AHERA OPERATIONS AND MAINTENANCE PLAN

a) CONTROLS

i. Work Order System

Minimizing disruption of ACM/PACM during maintenance and renovation activities is the primary goal and task encountered by OEMS. Operations and maintenance employees and contractors should be warned to avoid conducting any maintenance work which may disturb ACM/PACM. Initiating a work order system, where all work orders or requests are channeled through the Office of Environmental Management and Services (OEMS), will be the method used to control and minimize disruption of ACM/PACM.

Any work performed by in-house personnel or contractors that could or will impact ACM/PACM shall be coordinated by OEMS. A completed Asbestos Inspection Report Form (Attachment 1) shall be issued to in-house personnel and/or all contractors whose work could impact ACM/PACM. This form should accompany each contract issued to an outside contractor and posted on the jobsite.

All work order requests for maintenance and renovation activities in areas where ACM/PACM is suspected or known to be present are to be submitted to OEMS prior to proceeding with work. OEMS is responsible for reviewing asbestos survey records for information about the presence of ACM/PACM in the area where the work is to be performed. OEMS should physically inspect the area to ensure existing records reflect actual conditions. If no asbestos is present, a work order is not necessary and the planned actions can proceed. If ACM/PACM is found to be present in the area, OEMS will sign the work order application and obtain an approved and accredited asbestos contractor or assign OEMS "A-TEAM" to abate the ACM/PACM.

ii. Regulated Areas

The owner will identify and regulate all areas where airborne concentrations of ACM/PACM exceed the Permissible Exposure Limit (PEL)* (Per OSHA determined to be 0.1 f/cc) and/or short term exposure limit (STEL) (Per OSHA determined to be 0.1 f/cc), or there is reasonable possibility that the (PEL) and/or (STEL) may be exceeded. All ACM/PACM removal activities involving thermal system insulation ACM/PACM (Class I), surfacing ACM/PACM (Class I), and miscellaneous ACM/PACM such as floor tile, roofing, and siding mastic, etc. (Class II), and repair and maintenance operations where thermal system insulation and surfacing ACM/PACM is likely to be disturbed (Class III) will be performed in accordance with federal, state, and local regulations. All asbestos abatement work and activities will be designed and managed as asbestos regulated areas. These areas will be demarcated and labeled.

iii. Warning Signs

Warning signs shall be displayed at all approaches to each asbestos regulated area. The asbestos abatement contractor will provide OSHA warning signs in all regulated areas during removal, repair, and other maintenance activities. OEMS will provide AIRs to all contractors who must inform all employees and supervisors working in locations contiguous to asbestos regulated areas of the potential hazards and work practices required.

iv. Warning Labels

Warning labels and/or signage shall be affixed to all raw materials, mixtures, scrap, waste, debris, and other products containing asbestos fibers, or to their containers. Generally, the asbestos abatement contractor or OEMS A-Team personnel will provide all warning labels for ACM/PACM containment.

8. O & M RESPONSE ACTIONS

The Asbestos Management Program general O&M procedures are outlined in this section. Additional requirements specific to asbestos abatement activities are included in the Project Design documents for all Asbestos Abatement Work. Regular cleaning, inspection, and reporting of ACM/PACM deterioration or other problems must be diligently practiced by all employees including custodial and maintenance personnel.

a) Facility Maintenance Isolation of Area Responsibilities

Maintenance personnel are often required to work in areas where ACM/PACM may potentially be disturbed. Most maintenance activities are conducted by in-house staff, outside contractors, or a combination.

Emergency fiber release episodes, such as pipe fitting or valve breaks, emergency boiler work, or mechanical equipment repair will be responded to by OEMS A-Team personnel or asbestos abatement contractor personnel. The owner's maintenance staff will: (1) isolate the emergency fiber release area; (2) post warning signs to prevent unauthorized access, and (3) notify their supervisor and OEMS. OEMS will ensure that the fiber release area remains isolated and is properly cleaned by and approved and accredited abatement contractor or by OEMS A-TEAM personnel.

b) Unlikely Contact with ACM/PACM

Maintenance activities or repairs which can be performed without contacting or disturbing the ACM/PACM require little more than normal care and good workmanship. For example, valves which are either uncovered or covered with non-asbestos insulation can be packed or repaired without disturbing asbestos insulation on nearby pipes. The major precaution is to ensure that maintenance and custodial personnel are familiar with procedures such as isolating the area, posting warning signs, and notifying OEMS in the event of any accidental ACM/PACM disturbance.

c) Accidental Disturbance of ACM/PACM

Maintenance and facilities personnel shall notify OEMS any time a fiber release is suspected. If friable ACM/PACM becomes airborne in the building,

d) Planned Disturbance of ACM/PACM

Maintenance activities that may impact ACM/PACM include access to a valve, flange, duct, or related system component.

Where asbestos-containing insulation must be removed to maintain or repair the thermal system, the ACM/PACM will imminently be disturbed. ACM/PACM removal work shall be conducted by OEMS A-Team personnel or an approved and accredited asbestos abatement contractor.

If friable ACM/PACM becomes airborne in the building, maintenance and facilities personnel shall secure the area and contact OEMS. OEMS shall respond accordingly.

e) Miscellaneous ACM/PACM

Miscellaneous types of ACM/PACM may include vinyl asbestos floor tiles, mastics/adhesives and woven vibration dampers. Disturbance of these materials should be avoided. Routine maintenance activities involving these materials should not pose a problem if handled properly. Questions on the proper removal and disposal of miscellaneous ACM/PACM should be directed to OEMS. OEMS will contact an approved and accredited asbestos abatement contractor or utilize OEMS A-TEAM personnel to assist with miscellaneous ACM/PACM clean-up activities.

f) Vinyl Asbestos Floor Tile

Asbestos-containing floor tiles in good condition are considered non-friable unless they are crushed, drilled, sawed, sanded or disturbed by any activity that breaks up the material. Routine maintenance of these materials should employ the use of non-abrasive buffers and wet cleaning technique. Broken or loose floor tiles should be removed and disposed of as asbestos waste by OEMS. Remaining debris should be vacuumed with a HEPA vacuum and the area wet mopped using amended water.

g) Mastics/Adhesives

Mastics and adhesives containing asbestos in good condition are considered non-friable and do not pose a potential health concern unless crushed, drilled, sawed, sanded, or otherwise abraded. Questions on the proper removal should be directed to OEMS.

h) Woven Vibration Dampers

Woven vibration dampers in good condition are considered non-friable and do not pose a potential health concern unless cut, crushed, drilled, sawed, sanded, or otherwise abraded. Questions on the proper removal should be directed to OEMS.

i) Other Work Practices

Any special work not included in this section should be addressed to OEMS for review prior to the initiation of work that may involve the disturbance of ACM/PACM.

j) Fiber Release Episodes

Facilities and maintenance staff should report to OEMS the presence of asbestos debris, water or physical damage to ACM/PACM, or any other evidence of possible fiber release. OEMS should have the OEMS A-Team personnel or an approved and accredited abatement contractor respond to the site to clean up debris and make repairs as soon as possible. OEMS will also contact a consultant to conduct air monitoring and prepare a report and submit at project completion to OEMS for each episode. OEMS will forward the reports for each site location AHERA Management Plan accordingly.

9. REFERENCES and RESOURCES

Applicable regulations for asbestos projects impacted by renovation, demolition, and maintenance activities.

- **Philadelphia Air Management Services – Asbestos Control Unit**
<http://www.phila.gov/health/units/ams/Asbestos/asbestos.html>
- **Pennsylvania Asbestos Occupations, Accreditation and Certification Act**
<http://www.dli.state.pa.us/landi/cwp/view.asp?a=185&q=56262&landiNav=>
- **United States Environmental Protection Agency Asbestos Home Page**
<http://www.epa.gov/asbestos/>
- **Occupational Safety and Health Administration (OSHA) Asbestos Home**
<http://www.osha.gov/SLTC/asbestos>