

Facility Condition Assessment Summary Report

This report provides a summary of the Facility Condition Index (FCI) value of a school facility and select major building systems. The FCI calculation represents the cost of needed repairs divided by the replacement value. The FCI is a numerical value of condition and helps to identify the need for renewal or replacement of specific parts of the facility. The FCI is particularly useful when comparing similar facilities within the same portfolio.

Vare at Washington Elementary School

Governance	DISTRICT	Report Type	Elementarymiddle
Address	1198 S. 5Th St. Philadelphia, Pa 19147	Enrollment	366
Phone/Fax	215-952-8620 / 215-952-8508	Grade Range	'00-08'
Website	Www.Philasd.Org/Schools/Avare	Admissions Category	Neighborhood
		Turnaround Model	N/A

Building/System FCI Tiers

Facility Condition Index (FCI) = $\frac{\text{Cost of Assessed Deficiencies}}{\text{Replacement Value}}$				
< 15%	15 to 25%	25 to 45%	45 to 60%	> 60%
Buildings				
Minimal Current Capital Funding Required	Refurbish Systems in building	Replace Systems in building.	Building should be considered for major renovation.	Building should be considered for closing/replacement.
Systems				
Perform routine maintenance on system	System requires minor repairs	System should be studied to determine repair vs. replacement.	System is nearing end of its life expectancy and should be considered for replacement	System should be replaced as part of the Capital Program

Building and Grounds

	FCI	Repair Costs	Replacement Cost
Overall	35.84%	\$12,783,619	\$35,667,942
Building	34.92 %	\$12,238,759	\$35,051,109
Grounds	88.33 %	\$544,860	\$616,833

Major Building Systems

Building System	System FCI	Repair Costs	Replacement Cost
Roof (Shows physical condition of roof)	00.00 %	\$0	\$873,806
Exterior Walls (Shows condition of the structural condition of the exterior facade)	01.29 %	\$32,460	\$2,509,880
Windows (Shows functionality of exterior windows)	88.59 %	\$1,084,921	\$1,224,680
Exterior Doors (Shows condition of exterior doors)	129.31 %	\$127,502	\$98,600
Interior Doors (Classroom doors)	14.92 %	\$35,620	\$238,680
Interior Walls (Paint and Finishes)	04.05 %	\$46,262	\$1,143,080
Plumbing Fixtures	07.00 %	\$64,361	\$919,360
Boilers	00.00 %	\$0	\$1,269,560
Chillers/Cooling Towers	49.20 %	\$819,029	\$1,664,640
Radiators/Unit Ventilators/HVAC	115.10 %	\$3,364,864	\$2,923,320
Heating/Cooling Controls	158.90 %	\$1,458,745	\$918,000
Electrical Service and Distribution	107.63 %	\$709,940	\$659,600
Lighting	29.70 %	\$700,282	\$2,358,240
Communications and Security (Cameras, Pa System and Fire Alarm)	47.72 %	\$421,527	\$883,320

Please note that some FCIs may be over 100% because there are times when replacing a building system requires that other building systems be upgraded to complete the installation. A FCI of 0.0% represents that there are no current deficiencies with the associated system.

School District of Philadelphia

S273001; Washington ES

Final

Site Assessment Report

January 31, 2017



Table of Contents

Site Executive Summary	4
Site Condition Summary	11
<u>B273001:Washington ES</u>	13
Executive Summary	13
Condition Summary	14
Condition Detail	15
System Listing	16
System Notes	18
Renewal Schedule	19
Forecasted Sustainment Requirement	22
Condition Index Forecast by Investment Scenario	23
Deficiency Summary By System	24
Deficiency Summary By Priority	25
Deficiency By Priority Investment	26
Deficiency Summary By Category	27
Deficiency Details By Priority	28
Equipment Inventory Detail	46
<u>G273001:Grounds</u>	47
Executive Summary	47
Condition Summary	48
Condition Detail	49
System Listing	50
System Notes	51
Renewal Schedule	52
Forecasted Sustainment Requirement	53
Condition Index Forecast by Investment Scenario	54
Deficiency Summary By System	55
Deficiency Summary By Priority	56
Deficiency By Priority Investment	57

Site Assessment Report

Deficiency Summary By Category	58
Deficiency Details By Priority	59
Equipment Inventory Detail	63
Glossary	64

Site Executive Summary

The organization of this report, as displayed in the Table of Contents, follows the structure of the associated eCOMET database. The overall node for each school campus begins with the letter "S", which indicates the "Site" label. Each Site is comprised of separate "Building" and "Grounds" nodes; their asset names begin with the letters "B" and "G" respectively. Information rolls up to the Site node from the Building and Grounds nodes. This Site report combines facility information with subsections for the Buildings And Grounds nodes.

The basis for the evaluation of condition is the functional systems and elements of a building and grounds organized according to the UNIFORMAT II Elemental Classification. The grouping of these systems and elements and applying a current replacement value to them develops a representative building cost model. Cost Models are typically developed for similar building types and functions. Evaluation of systems and their elements takes into account their current replacement values, life cycles, installation dates and next renewal dates. Systems and their elements that are within their useful lives are further evaluated to identify current deficient conditions that may have a significant impact on a system's or element's remaining service life, and to determine if they are beyond their predicted expected life. The system's or element's current replacement value is based on RS Means Commercial Cost Data.

Following are the cost model's system details for this facility. The Replacement Value is the amount needed to replace the property of the same present value. The Current Repair Amount, also known as Condition Needs, represents the budgeted contractor installed costs plus owner's soft costs for the repair, replacement or renewal for a component or system level deficiency. It excludes contributing costs for other components or systems that might also be associated with the corrective actions due to packaging the work. Facility Condition Index (FCI) is an industry-standard measurement calculated as the ratio of the repair costs to correct a facility's deficiencies to the facility's Current Replacement Value. Condition Index (CI) for a system is calculated as the sum of the deficiencies divided by the sum of a system's Replacement Value (both values include soft-cost) expressed as a percentage ranging from 0% 100%.

Gross Area (SF):	95,500
Year Built:	1935
Last Renovation:	
Replacement Value:	\$35,667,942
Repair Cost:	\$12,783,618.87
Total FCI:	35.84 %
Total RSLI:	62.17 %



Description:

Facility Assessment
October 5th, 2015

School District of Philadelphia

Washington Elementary School

1198 S. 5th Street

Philadelphia, PA 19147

68,000 SF / 596 Students / LN 01

GENERAL

Mr. Tom Sharer, Facility Area Coordinator provided input to the Parsons Assessment team on current problems mainly in the mechanical systems Principal Zachary Duberstein provided additional information about building usage, and Mr. Malik Douglas Building Engineer accompanied us on our tour of the school and provided us with detailed information on the building systems and maintenance history.

The 4 story, 68,000 square foot building was originally constructed in 1935. The building has a one level basement.

ARCHITECTURAL/STRUCTURAL SYSTEMS

The building typically rests on concrete foundations and bearing walls that are not showing signs of settlement damage. The main structure consists typically of cast-in-place concrete columns, beams, and one way ribbed slab. The roof structure consists of concrete one-way slab supported by main structural frame. Roofing is built up application in fair condition with evidence of pooling in areas not sloped toward roof drains. The building envelope is masonry with face brick. Elevations are enhanced minimally with decorative concrete and stonework around entrances. In general, masonry is in fair to poor condition with multiple cracks and failing lintels around lower windows. The windows were replaced in early 1990s with extruded aluminum, double hung windows, Lexan Plexiglas with insect/security screens. All windows are generally in poor condition with heavy hazing and are not energy efficient. Exterior doors are typically hollow metal in poor condition and beyond service life. The building is not accessible per ADA requirements due to first floor- grade separation with no ramps or lifts.

Partition walls are plastered ceramic hollow blocks. Interior doors are generally rail and stile wood doors and frames with transoms in good condition. Doors leading to exit stairways are hollow metal frames with metal rail and stile doors with wire mesh glazing in fair condition. Interior doors do not have lever type handles. Fittings include: toilet accessories in fair condition; composite plastic and hollow metal toilet partitions, generally in fair to poor condition with some beyond service life; handrails and ornamental metals, generally in fair condition; and fixed metal wall lockers in fair condition. Toilet partitions and accessories are not ADA accessible. Interior identifying signage is typically directly painted on wall or door surfaces generally in good condition. Stair construction is generally concrete with terrazzo treads, risers, and nosing in good condition. Stair railings are cast iron balusters with wood handrail in fair condition.

The interior wall finishes are painted plaster or brick throughout with glazed brick wainscot in stairways, corridors, cafeteria, gym, and toilets in good condition and wood panel wainscot in auditorium in good condition. Main grand entrance has decorative marble and granite in good condition. Generally, paint is in good condition with a few small damages in various areas. Flooring types include hardwood in most classrooms, stage and auditorium in good condition; terrazzo tile in corridors, toilets, and stairways in good condition; vinyl tile in some classrooms, cafeteria, office areas, lounges, and gym in fair to poor condition with some new and some failing and beyond service life; carpet in portions of kindergarten rooms beyond service life; and concrete in basement service areas. Ceiling finishes include: suspended acoustic tile system in some classrooms, cafeteria, and offices in fair to poor condition with some beyond service life; painted plaster or structural concrete in toilets, auditorium, corridors, and gym in fair condition with damaged areas throughout. Multiple utility lines can be seen running through corridors and would benefit from an installed suspended acoustic tile ceiling system.

The building has no elevators.

Institutional and Commercial equipment includes: stage equipment and gym equipment in fair condition. Other equipment includes kitchen equipment (heat and serve only), generally in good condition.

Fixed furnishings include: fixed casework in classrooms, corridors and library, generally in fair to good condition; window shades/blinds in fair condition; and fixed auditorium seating in fair condition.

MECHANICAL SYSTEMS

Toilet room plumbing consists of wall hung porcelain lavatories, water closets, and urinals. The majority of fixtures are replacements installed over the life of the building. Flush valves are installed in pipe chases. Lavatories have separate hot and cold faucets with momentary action valves. Head Start children do not have the manual dexterity or physical strength to operate the faucets. The school cafeteria kitchen has a single basin, enamel on cast iron, floor standing, residential kitchen sink with integral drain board, ca. 1950 vintage. The sink is in good condition and sufficient for elementary school service, but the faucet leaks and should be replaced. There is a similar sink in the 3rd floor faculty lounge which apparently has drainage problems. Science room lab sinks have been renovated including acid resistant drains with neutralizers. There is 1 teacher sink and 2 wall sinks. There is no flow from the hot water valves, likely shut off due to leaks. Lab sink faucets should be repaired or replaced. Service sinks are enameled cast iron located in cleaning closets on each floor. Sinks are in fair condition, but their drain traps are too small and cause slow drainage. The traps should be replaced when the sanitary drain pipe in the building is repaired. The building originally had boys and girls shower rooms in the basement, but the plumbing has been partially demolished and the areas are now used for storage. The remaining plumbing should be removed when convenient. Drinking fountains in the hallways are porcelain, no accessible, and originally had 2 spouts. The third floor hallway is missing one fountain. The faculty lounge on the third floor has a floor standing sheet metal refrigerated fountain, but chiller does not work. Generally, all the fountains in the school should be replaced with accessible units with integral chillers.

Municipal water service enters the building from South 5th St. in a basement mechanical room via a 3 inch line with 3 inch water meter and bypass, then parallel 3 inch and 2 inch Y-strainers and reduced pressure backflow preventers, and finally a duplex pump pressure booster system without pressurized storage tank. The water service entry pipe and fittings is in fair condition with no cause for immediate concern. It should last 5 – 10 years more. A hydro-pneumatic storage tank should be installed for the booster system. Domestic water distribution pipe is mostly soldered copper, but some areas of threaded steel and copper pipe remain. Visible areas of pipe are corroded. The entire building should have domestic water distribution pipes replaced due to age. Hot water is provided by a Bradford White, 50 gallon, natural gas burning, water heater installed in 2013. It should provide reliable performance for 10 more years. There is a steam to water tube-and-shell heat exchanger that is used as a hot water storage tank now. The adjacent coal fired steam boiler has been abandoned in place. A circulation pump keeps the tank hot. Hot water was available at a third floor lavatory in less than 10 seconds. The storage tank is uninsulated and should have new insulation installed to conserve energy.

Sanitary drain piping is both hub and spigot cast iron and threaded galvanized steel. Several sink drains were observed to flow poorly. Some areas of cast iron pipe are very rusty. There were no visible recent repairs. The sanitary drain pipes should be inspected in greater detail and repaired or replaced as needed. There is a sewage ejector in a sump in the basement boiler room. It has 2 collection tanks and one tank is missing the level sensor. The sewage ejector system should be replaced during the drain pipe repairs. Sanitary drainage exits the building in the south side mechanical room in a 6 inch line next to the original air handler.

Rain water drain pipes are threaded galvanized steel and run inside the building. Rooftop drains are cast iron without overflows. Drain pipes are past their service life but there were no complaints or visible areas of concern, so they should last 5 – 10 more years. There is standing water on the floor of the basement in the south west corner and water infiltration in the gym from under the outside stairs at the north end of the building.

The building has hydronic heating serving unit vents and convectors with one air handler for the auditorium.

Two Weil-McLain, cast iron sectional, model H-1288 W5, 2329 MBH (70 HP) net capacity, boilers provide steam for heating the building. They are equipped with Power Flame oil and natural gas burners manufactured in 1989. Gas service enters the building from S. 5th St. (in the same room as the water service) through a 4 inch line with gas meter

and booster. There are two fuel oil pumps in the coal room behind the boiler room and an 8,000 gallon tank buried in the yard north of the building. Feedwater comes from duplex pump tank with separate feed lines. There is a vacuum condensate system on top of the feedwater tank, and a chemical injection system is next to it. The boilers have 9 years expected service life remaining and the associated equipment should remain serviceable for that period as well.

The building has no central cooling generating equipment. There are 19 window unit air conditioners and 1 mini split system which provide about 40 tons of cooling capacity to offices, etc. A chiller system with 170 ton capacity should be installed to provide cooling to the entire building.

The original air handler for the auditorium is still installed in a basement mechanical room under the stage. It has two steam heating sections with cast iron coils, air washer, and 3 HP fan. Estimated capacity was 15,000 cfm. It is completely obsolete, and should be replaced with a modern unit including a cooling section. Classrooms and gyms still have the original unit ventilators which have greatly exceeded their lifespan, so they should be replaced also. Classrooms air exhausted through vents in the coat closets up to the attic plenum and then out through gravity vents on the roof. The kitchen has no exhaust, (not even windows which have been bricked over,) but it has no fuel burning appliances, only an electric convection oven. Steam distribution pipe is threaded steel. There were no complaints about pipe leaks or steam trap failures. However, give the unknown age of the steam and condensate pipes, they should be inspected and repaired as needed.

Finned tube convection units with sheet metal cabinets supplement unit vents in classrooms and are the only heat for other areas like hallways, toilet rooms, and offices. They are likely the original equipment and have exceeded their expected service life. Some convectors are damaged and corroded. They should all be replaced with new equipment.

Building HVAC controls were pneumatic, but became inoperable year ago. Classrooms and gyms have wall mounted thermostats to control unit vents. The controls are obsolete and should be replaced with a DDC to control new HVAC equipment. There are two air compressors in the building. A single pump with tank and cooler is installed and operational in the boiler room. There is also a duplex pump with tank stored in the coal room not installed.

The building has dry stand pipes: threaded galvanized steel. There are no sprinklers. A fire sprinkler system should be installed to increase occupant safety, including a fire pump if needed.

ELECTRICAL SYSTEMS

A pole mounted transformer on Federal Street and an underground secondary conductors serve this building. The electrical service entrance is located in the basement which houses the utility main disconnect switch and utility metering PECO 221MU 53509. Many other electrical distribution equipment are also housed in the basement, including the Fire Alarm Panel, phase convertor transformers, building main power distribution panelboard, and several safety switches. The rating of the existing electrical service is 120/240V, 400A (estimated) and is original installation and has exceeded its 30 year useful life. It has no extra capacity for expansion or new Heating, Ventilation, Air Conditioning (HVAC) system. The electrical service entrance should be upgraded, using the present utility pole, and adding a pad mounted transformer on Federal Street. The new service will be 480V/277V, 3 phase power, approximate 1000 Amperes and will be located in the vicinity of the existing electrical service. The electrical service will feed a 480V Motor Control Center (MCC) and HVAC equipment and a 480V 3 phase to 120V/208V 3 phase 300 KVA step-down transformer to feed receptacles, lighting and other smaller loads.

There are 120/240V panel-boards in each floor for lighting and receptacles. These panelboards and associated wiring have exceeded the end of their useful life and are undersized to absorb new loads. The entire distribution system needs to be replaced with new 208/120 volt, 3 phase panelboards and new wiring. The raceway is mainly conduits run above the ceiling.

Site Assessment Report - S273001;Washington ES

There number of receptacles in 80% of the classrooms are inadequate. Teachers use extension cords. The teacher's whiteboard wall and the opposite of it need to be provided with double compartment surface raceways, the other two walls with minimum two duplex outlets each, when feasible.

Classrooms, corridors and cafeteria/gymnasium are illuminated with surface mounted fluorescent fixtures. The auditorium is illuminated with recessed, perimeter mounted fluorescent fixtures. Fluorescent fixtures in classrooms are provided with T12 lamps, in corridors and stairways with T-8 lamps. T-12 fluorescent lamps are becoming more expensive, consume more energy and are difficult to find therefore replace 70% of the fluorescent fixtures with T-12 lamps with pendant mounted up/down fixture with T-8 lamps

A tap ahead of the main disconnect switch serves the fire alarm control panel (FACP).The Fire Alarm system is manufactured by S.H. COUCH INC The system is approximately 30 years old. The present Fire Alarm system does not meet current code. Fire alarm system is tested every day in the morning. Provide a new addressable fire alarm system.

The present telephone system is adequate. During the assessment, randomly, we verified that each wall mounted handset is provided with dial tone.

An independent and separate PA system does not exist. School uses the telephone systems for public announcement. This system is working adequately for most part.

The clock system is composed of an old master control panel at the main office and inoperative clocks at the classrooms. Most of the clocks in the classrooms are battery operated stand-alone. Provide a synchronized clock system, wireless, battery operated.

There is not television system.

The security system consists of surveillance CCTV cameras. The third floor and the basement are provided with four surveillance CCTV cameras, each level has two cameras. The first floor and the auditorium are provided with a total of four surveillance CCTV cameras. The surveillance monitor is located in the Main office. Add CCTV cameras for a complete coverage of the school building interior

The emergency power system consists of a gas powered generator, manufactured by Onan, 15KW 120/240V. The present emergency power system serves the corridor lights, exit signs, boiler room, gymnasium/cafeteria and stairways. The gas powered generator, already exceeds its useful service life and should be replaced with 70KW outdoor diesel powered generator.

There is adequate UPS in the IT room.

The emergency lighting is obtained via selected lighting fixtures in corridors and stairs. Exit signs are located at each exit door and corridors and are connected to the school emergency system.

The school lightning protection system is accomplished with air terminals mounted on the chimney. A study needs to be conducted to verify if the air terminals provide the proper coverage.

The auditorium is provided with one row of pendant mounted theatrical lighting which are controlled from local panelboard. Modern school auditorium requires front, upstage, high side, back, theatrical lighting and to create different scenes theatrical lighting fixtures are controlled by a dimming system. Provide stage theatrical lighting and dimming control system.

The auditorium sound system is manufactured by AVT. System is approximately 10 years old and looks inoperative.

Provide the auditorium with new sound system.

GROUNDS SYSTEMS

The site surrounds the building on all four sides which is set back from the street. Play yard area on north and west sides are concrete paving in fair to poor condition with multiple cracks and areas of spalling. Grade level concrete at north entrance stoop has large crack allowing water intrusion into gymnasium office and basement ash room. No parking for staff vehicles on site. Chain link fence surrounding yard is in good condition. Metal fence surrounding site on south and east sides is rusted and failing. Landscaping is grass and medium trees along south and east sides in good condition.

Accessibility: the building does not have an accessible entrance, and accessible routes. None of the toilets are equipped with accessible fixtures, partitions and accessories, such as grab bars and accessible partitions. None of the doors in the building have ADA required door handles.

The school perimeter is poorly illuminated with wall mounted HID fixtures. Add outdoor wall mounted lighting fixtures to provide a safer and better illumination.

The outdoor security system is accomplished with five surveillance CCTV cameras around the building perimeter. Add surveillance CCTV cameras to provide a complete coverage of the building perimeter.

Outdoor loud speaker is not provided in front of the playground area. Provide an outdoor loud speaker facing the playground area

RECOMMENDATIONS

- Replace Plexiglas windows – hazed
- Replace exterior doors – rusted & failing
- Provide ADA lever handle lock/latchsets on interior doors
- Provide new toilet partitions and toilet accessories including grab bars for accessibility
- Replace VCT flooring – damaged & failing (30% of vinyl floor area)
- Replace carpet – beyond service life
- Repair and repaint interior ceiling (10% of painted ceiling surface)
- Install suspended acoustic tile ceiling system in corridors for appearance
- Install elevator for accessibility (location TBD)
- Provide ADA compliant ramp for at least one entrance (location TBD)
- Replace metal fence and gates – rusted and hazard to safety
- Replace head start, kitchen, and science room faucets due to leaks and other operational failures, 6 faucets
- Replace drinking fountains with accessible ones with chillers
- Install hydro-pneumatic storage tank for domestic water booster system
- Replace domestic water distribution pipe due to age
- Insulate domestic hot water storage tank to conserve energy
- Inspect and repair or replace sanitary drain pipe as needed due to age, operation, and appearance including sewage ejector replacement
- Install 170 ton chiller system to provide cooling for entire building
- Replace obsolete AHU serving auditorium
- Replace aged unit ventilators and convectors
- Inspect and repair steam and condensate pipes due to age
- Install DDC to replace obsolete pneumatic controls
- Install fire protection sprinkler system with fire pump if needed

Site Assessment Report - S273001;Washington ES

- Provide new service 480V/277V, 3 phase power, approximate 1000 Amperes.
- Replace the entire distribution system with new panels and new wiring/conduits. Approximate (15) 208/120V.
- The teacher's whiteboard wall and the opposite of it need to be provided with double compartment surface raceways, the other two walls with minimum two duplex outlets each. Approximate 390 receptacles.
- Replace 70% of the fluorescent fixtures with pendant mounted up/down fixture with T-8 lamps. Approximate 629 fixtures.
- Provide a new addressable fire alarm system. Approximate 90 devices.
- Provide a clock system with wireless, battery operated clocks. Approximate 50 clocks.
- Add surveillance CCTV cameras for a complete coverage of the school building interior. Approximate 30
- Provide an outdoor diesel powered generator. Approximate 70KW
- Prepare a study to determine if the air terminals installed in the chimney provide the proper coverage to the school.
- Provide the auditorium with dimming and theatrical lighting.
- Provide the auditorium with a sound system.
- Add outdoor wall mounted lighting fixtures to provide a safer and better illumination. Approximate 16 HID fixtures
- Add surveillance CCTV cameras to provide a complete coverage of the building perimeter. Approximate 10
- Provide an outdoor loud speaker facing the playground area

Attributes:

General Attributes:

Active:	Open	Bldg Lot Tm:	Lot 3 / Tm 3
Status:	Accepted by SDP	Team:	Tm 3
Site ID:	S273001		

Site Condition Summary

The Table below shows the CI and FCI for each major system shown at the UNIFORMAT classification Level II. Note that Systems with lower FCIs require less investment than systems with higher FCIs.


Current Investment Requirement and Condition by Uniformat Classification

UNIFORMAT Classification	RSLI%	FCI %	Current Repair
A10 - Foundations	20.00 %	0.00 %	\$0.00
A20 - Basement Construction	20.00 %	0.00 %	\$0.00
B10 - Superstructure	20.00 %	0.00 %	\$0.00
B20 - Exterior Enclosure	49.42 %	32.48 %	\$1,244,883.87
B30 - Roofing	30.00 %	0.00 %	\$0.00
C10 - Interior Construction	28.38 %	3.13 %	\$52,243.99
C20 - Stairs	20.00 %	0.00 %	\$0.00
C30 - Interior Finishes	76.48 %	6.04 %	\$262,122.03
D10 - Conveying	105.71 %	265.91 %	\$1,012,601.25
D20 - Plumbing	46.81 %	55.08 %	\$764,842.73
D30 - HVAC	94.35 %	74.60 %	\$5,642,637.35
D40 - Fire Protection	100.34 %	177.49 %	\$972,768.92
D50 - Electrical	110.11 %	49.86 %	\$1,993,063.70
E10 - Equipment	49.62 %	27.12 %	\$293,594.70
E20 - Furnishings	35.00 %	0.00 %	\$0.00
G20 - Site Improvements	105.49 %	61.74 %	\$274,021.84
G40 - Site Electrical Utilities	106.67 %	156.58 %	\$270,838.49
Totals:	62.17 %	35.84 %	\$12,783,618.87

Condition Deficiency Priority

Facility Name	Gross Area (S.F.)	FCI %	1 - Response Time (< 2 yr)	2 - Response Time (2-3 yrs)	3 - Response Time (3-4 yrs)	4 - Response Time (4-5 yrs)	5 - Response Time (> 5 yrs)
B273001;Washington ES	68,000	34.92	\$10,167.21	\$3,796,437.82	\$2,640,667.15	\$2,196,362.86	\$3,595,123.50
G273001;Grounds	27,500	88.33	\$25,981.81	\$56,243.11	\$376,174.38	\$86,461.03	\$0.00
Total:		35.84	\$36,149.02	\$3,852,680.93	\$3,016,841.53	\$2,282,823.89	\$3,595,123.50

Deficiencies By Priority




Executive Summary

Building condition is evaluated based on the functional systems and elements of a building and organized according to the UNIFORMAT II Elemental Classification. The grouping of these systems and elements and applying a current replacement value to them develops a representative building cost model. Cost Models are developed for similar building types and functions. Systems and their elements are evaluated based on their current replacement values, life cycles, installation dates and next renewal dates. Systems and their elements that are within their useful lives are further evaluated to identify current deficient conditions that may have a significant impact on a system's or element's remaining service life, and to determine if they are beyond their predicted expected life. The system's or element's current replacement value is based on RS Means Commercial Cost Data.

Following are the cost model's system details for this facility. The Replacement Value is the amount needed to replace the property of the same present value. The Current Repair Amount, also known as Condition Needs, represents the budgeted contractor installed costs plus owner's soft costs for the repair, replacement or renewal for a component or system level deficiency. It excludes contributing costs for other components or systems that might also be associated with the corrective actions due to packaging the work. Facility Condition Index (FCI) FCI is an industry-standard measurement of facility condition calculated as the ratio of the costs to correct a facility's deficiencies to the facility's Current Replacement Value. It ranges from 0% (new) to 100% (very poor). Condition Index (CI) is calculated as the sum of a renewable system's Remaining Service Life (RSL) divided by the sum of a system's Replacement Value (both values exclude soft-cost to simplify calculation updates) expressed as a percentage ranging from 100% (new) to 0% (expired).

Function:	Elementary School
Gross Area (SF):	68,000
Year Built:	1935
Last Renovation:	
Replacement Value:	\$35,051,109
Repair Cost:	\$12,238,758.54
Total FCI:	34.92 %
Total RSLI:	61.40 %



Description:

Attributes:

General Attributes:

Active:	Open	Bldg ID:	B273001
Sewage Ejector:	Yes	Status:	Accepted by SDP
Site ID:	S273001		

Condition Summary

The Table below shows the CI and FCI for each major building system shown at the UNIFORMAT classification Level II. Note that Systems with lower FCIs require less investment than systems with higher FCIs.

UNIFORMAT Classification	RSLI %	FCI %	Current Repair Cost
A10 - Foundations	20.00 %	0.00 %	\$0.00
A20 - Basement Construction	20.00 %	0.00 %	\$0.00
B10 - Superstructure	20.00 %	0.00 %	\$0.00
B20 - Exterior Enclosure	49.42 %	32.48 %	\$1,244,883.87
B30 - Roofing	30.00 %	0.00 %	\$0.00
C10 - Interior Construction	28.38 %	3.13 %	\$52,243.99
C20 - Stairs	20.00 %	0.00 %	\$0.00
C30 - Interior Finishes	76.48 %	6.04 %	\$262,122.03
D10 - Conveying	105.71 %	265.91 %	\$1,012,601.25
D20 - Plumbing	46.81 %	55.08 %	\$764,842.73
D30 - HVAC	94.35 %	74.60 %	\$5,642,637.35
D40 - Fire Protection	100.34 %	177.49 %	\$972,768.92
D50 - Electrical	110.11 %	49.86 %	\$1,993,063.70
E10 - Equipment	49.62 %	27.12 %	\$293,594.70
E20 - Furnishings	35.00 %	0.00 %	\$0.00
Totals:	61.40 %	34.92 %	\$12,238,758.54

Condition Detail

This section of the report contains results of the Facility Condition Assessment. The building is separated into system components based on UNIFORMAT II classification. The columns in the System Listing table below represent the following:

1. System Code: A code that identifies the system.
2. System Description: A brief description of a system present in the building.
3. Unit Price \$: The unit price of the system.
4. UoM: The unit of measure for of the system.
5. Qty: The quantity for the system
6. Life: anticipated service life for thesystem based on Building Owners and Managers Association (BOMA) recommendations.
7. Year Installed: The date of system installation.
8. Calc Next Renewal Year: The date of system expiration based on the life, NR stands for non renewable.
9. Next Renewal Year: The suggested system expiration date by the assessor based on visual inspection.
10. CI: The Condition Index of the system.
11. FCI: The Facility Condition Index of the system.
12. RSL: Remaining Service Life.
13. eCR: eCOMET Condition Rating (not used).
14. Deficiency \$: The financial investment to repair/replace system.

System Listing

The System Listing table below lists each of the systems organized by their UNIFORMAT II classification. The assessment team was tasked with recording the most recent replacement year of each system, determining the remaining service life based on the theoretical life, and evaluating the condition to confirm the forecast next replacement year. The system listing is the basis for all data contained in the Building Assessment Report.

Additionally, a condition rating (eCR) based on the following guidelines is provided as observed at the time of the assessment.

- Excellent (E) - No noticeable distress or damage. The entire system is free from observable defect.
- Very Good (VG) - Overall no serviceability reduction for the entire system. No degradation of critical components and minor distress and defect noticeable for some but not non critical components within the system.
- Good (G) - Slight or no serviceability reduction for the entire system. There may be noticeable defects for some non critical components and slight noticeable degradation of the critical components.
- Fair (F) - Overall serviceability is degraded but adequate. There may be moderate deterioration for very few of the critical components and few of the non critical components may have severe degradation.
- Marginal (MA) - Overall serviceability and reliability loss. Most if not all of the non critical components suffer from severe degradation and a few of the critical component may have severe degradation.
- Moderate (MO) - Overall a significant serviceability loss. Most if not all the components have severe degradation with the reminder of the component showing visible distress.
- Very Poor (VP) - Overall the system is barely functional. All of the components are severely degraded.
- Non-Functional (NF) - Overall the system does not function with all the components having no serviceability and suffer from severe degradation.

System Code	System Description	Unit Price \$	UoM	Qty	Life	Year Installed	Calc Next Renewal Year	Next Renewal Year	RSLI%	FCI%	RSL	eCR	Deficiency \$	Replacement Value \$
A1010	Standard Foundations	\$18.40	S.F.	68,000	100	1935	2035		20.00 %	0.00 %	20			\$1,251,200
A1030	Slab on Grade	\$7.73	S.F.	68,000	100	1935	2035		20.00 %	0.00 %	20			\$525,640
A2010	Basement Excavation	\$6.55	S.F.	68,000	100	1935	2035		20.00 %	0.00 %	20			\$445,400
A2020	Basement Walls	\$12.70	S.F.	68,000	100	1935	2035		20.00 %	0.00 %	20			\$863,600
B1010	Floor Construction	\$75.10	S.F.	68,000	100	1935	2035		20.00 %	0.00 %	20			\$5,106,800
B1020	Roof Construction	\$13.88	S.F.	68,000	100	1935	2035		20.00 %	0.00 %	20			\$943,840
B2010	Exterior Walls	\$36.91	S.F.	68,000	100	1935	2035		20.00 %	1.29 %	20		\$32,460.39	\$2,509,880
B2020	Exterior Windows	\$18.01	S.F.	68,000	40	1989	2029	2057	105.00 %	88.59 %	42		\$1,084,920.99	\$1,224,680
B2030	Exterior Doors	\$1.45	S.F.	68,000	25	1989	2014	2042	108.00 %	129.31 %	27		\$127,502.49	\$98,600
B3010105	Built-Up	\$37.76	S.F.	23,033	20	2001	2021		30.00 %	0.00 %	6			\$869,726
B3010120	Single Ply Membrane	\$38.73	S.F.		20				0.00 %	0.00 %				\$0
B3010130	Preformed Metal Roofing	\$54.22	S.F.		30				0.00 %	0.00 %				\$0
B3010140	Shingle & Tile	\$38.73	S.F.		25				0.00 %	0.00 %				\$0
B3020	Roof Openings	\$0.06	S.F.	68,000	20	2001	2021		30.00 %	0.00 %	6			\$4,080
C1010	Partitions	\$17.91	S.F.	68,000	100	1935	2035		20.00 %	0.00 %	20			\$1,217,880
C1020	Interior Doors	\$3.51	S.F.	68,000	40	1986	2026		27.50 %	14.92 %	11		\$35,620.45	\$238,680
C1030	Fittings	\$3.12	S.F.	68,000	40	1986	2026	2046	77.50 %	7.84 %	31		\$16,623.54	\$212,160
C2010	Stair Construction	\$1.41	S.F.	68,000	100	1935	2035		20.00 %	0.00 %	20			\$95,880

Site Assessment Report - B273001;Washington ES

System Code	System Description	Unit Price \$	UoM	Qty	Life	Year Installed	Calc Next Renewal Year	Next Renewal Year	RSLI%	FCI%	RSL	eCR	Deficiency \$	Replacement Value \$
C3010230	Paint & Covering	\$13.44	S.F.	68,000	10	2013	2023		80.00 %	5.06 %	8		\$46,262.21	\$913,920
C3010231	Vinyl Wall Covering	\$0.00	S.F.	68,000	15				0.00 %	0.00 %				\$0
C3010232	Wall Tile	\$3.37	S.F.	68,000	30	1986	2016	2036	70.00 %	0.00 %	21			\$229,160
C3020411	Carpet	\$7.30	S.F.	1,360	10	2001	2011	2027	120.00 %	153.30 %	12		\$15,219.44	\$9,928
C3020412	Terrazzo & Tile	\$75.52	S.F.	10,200	50	1937	1987	2037	44.00 %	0.00 %	22			\$770,304
C3020413	Vinyl Flooring	\$9.68	S.F.	15,640	20	1986	2006	2037	110.00 %	37.31 %	22		\$56,482.40	\$151,395
C3020414	Wood Flooring	\$22.27	S.F.	37,400	25	2001	2026		44.00 %	0.00 %	11			\$832,898
C3020415	Concrete Floor Finishes	\$0.97	S.F.	3,400	50	1986	2036		42.00 %	0.00 %	21			\$3,298
C3030	Ceiling Finishes	\$20.97	S.F.	68,000	25	1986	2011	2042	108.00 %	10.11 %	27		\$144,157.98	\$1,425,960
D1010	Elevators and Lifts	\$5.60	S.F.	68,000	35			2052	105.71 %	265.91 %	37		\$1,012,601.25	\$380,800
D2010	Plumbing Fixtures	\$13.52	S.F.	68,000	35	1950	1985	2030	42.86 %	7.00 %	15		\$64,361.07	\$919,360
D2020	Domestic Water Distribution	\$1.68	S.F.	68,000	25	1937	1962	2025	40.00 %	310.85 %	10		\$355,111.98	\$114,240
D2030	Sanitary Waste	\$2.90	S.F.	68,000	25	1937	1962	2035	80.00 %	175.14 %	20		\$345,369.68	\$197,200
D2040	Rain Water Drainage	\$2.32	S.F.	68,000	30	1937	1967	2025	33.33 %	0.00 %	10			\$157,760
D3020	Heat Generating Systems	\$18.67	S.F.	68,000	35	1989	2024		25.71 %	0.00 %	9			\$1,269,560
D3030	Cooling Generating Systems	\$24.48	S.F.	68,000	30			2047	106.67 %	49.20 %	32		\$819,029.04	\$1,664,640
D3040	Distribution Systems	\$42.99	S.F.	68,000	25	1937	1962	2042	108.00 %	115.10 %	27		\$3,364,863.56	\$2,923,320
D3050	Terminal & Package Units	\$11.60	S.F.	68,000	20	1937	1957	2037	110.00 %	0.00 %	22			\$788,800
D3060	Controls & Instrumentation	\$13.50	S.F.	68,000	20	1937	1957	2037	110.00 %	158.90 %	22		\$1,458,744.75	\$918,000
D4010	Sprinklers	\$7.05	S.F.	68,000	35			2052	105.71 %	202.91 %	37		\$972,768.92	\$479,400
D4020	Standpipes	\$1.01	S.F.	68,000	35	1937	1972	2037	62.86 %	0.00 %	22			\$68,680
D5010	Electrical Service/Distribution	\$9.70	S.F.	68,000	30	1937	1967	2047	106.67 %	107.63 %	32		\$709,940.38	\$659,600
D5020	Lighting and Branch Wiring	\$34.68	S.F.	68,000	20	1937	1957	2037	110.00 %	29.70 %	22		\$700,282.33	\$2,358,240
D5030	Communications and Security	\$12.99	S.F.	68,000	15	1937	1952	2032	113.33 %	47.72 %	17		\$421,526.78	\$883,320
D5090	Other Electrical Systems	\$1.41	S.F.	68,000	30	1937	1967	2047	106.67 %	168.25 %	32		\$161,314.21	\$95,880
E1020	Institutional Equipment	\$4.82	S.F.	68,000	35	1989	2024		25.71 %	89.58 %	9		\$293,594.70	\$327,760
E1090	Other Equipment	\$11.10	S.F.	68,000	35	2001	2036		60.00 %	0.00 %	21			\$754,800
E2010	Fixed Furnishings	\$2.13	S.F.	68,000	40	1989	2029		35.00 %	0.00 %	14			\$144,840
Total									61.40 %	34.92 %			\$12,238,758.54	\$35,051,109

System Notes

The facility description in the site executive summary contains an overview of each system. The notes listed below provide additional information on select systems found within the facility.

System: C3010 - Wall Finishes This system contains no images

Note: 80% - Paint & Covering
20% - Wall Tile (glazed brick)

System: C3020 - Floor Finishes This system contains no images

Note: 2% - Carpet
15% - Terrazzo & Tile (terrazzo)
23% - Vinyl Flooring
55% - Wood Flooring
5% - Concrete Floor Finishes

System: D5010 - Electrical Service/Distribution



Note: (10 75KVA and (1) 45KVA phase converters 240V-120/208V

Renewal Schedule

eCOMET forecasts future Capital Renewal funding needed to address expiring systems based on the Next Renewal year found in the Cost Models. A 3% annual inflation factor is applied to the costs for systems expiring in future years. The table below reflects recommended Capital Renewal funding needs over the next 10 years. Note: Cells with a zero value indicate systems for which renewal is not scheduled in that year.

Inflation Rate: 3%

System	Current Deficiencies	2016	2017	2018	2019	2020	2021	2022	2023	2024	2025	Total
Total:	\$12,238,759	\$0	\$0	\$0	\$0	\$0	\$1,147,708	\$0	\$1,273,499	\$2,292,554	\$402,100	\$17,354,619
* A - Substructure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
A10 - Foundations	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
A1010 - Standard Foundations	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
A1030 - Slab on Grade	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
A20 - Basement Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
A2010 - Basement Excavation	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
A2020 - Basement Walls	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B - Shell	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B10 - Superstructure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B1010 - Floor Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B1020 - Roof Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B20 - Exterior Enclosure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B2010 - Exterior Walls	\$32,460	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$32,460
B2020 - Exterior Windows	\$1,084,921	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$1,084,921
B2030 - Exterior Doors	\$127,502	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$127,502
B30 - Roofing	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3010 - Roof Coverings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3010105 - Built-Up	\$0	\$0	\$0	\$0	\$0	\$0	\$1,142,349	\$0	\$0	\$0	\$0	\$1,142,349
B3010120 - Single Ply Membrane	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3010130 - Preformed Metal Roofing	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3010140 - Shingle & Tile	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3020 - Roof Openings	\$0	\$0	\$0	\$0	\$0	\$0	\$5,359	\$0	\$0	\$0	\$0	\$5,359
C - Interiors	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C10 - Interior Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C1010 - Partitions	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0

Site Assessment Report - B273001;Washington ES

C1020 - Interior Doors	\$35,620	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$35,620
C1030 - Fittings	\$16,624	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$16,624
C20 - Stairs	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C2010 - Stair Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C30 - Interior Finishes	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C3010 - Wall Finishes	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C3010230 - Paint & Covering	\$46,262	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$1,273,499	\$0	\$0	\$1,319,761
C3010231 - Vinyl Wall Covering	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C3010232 - Wall Tile	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C3020 - Floor Finishes	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C3020411 - Carpet	\$15,219	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$15,219
C3020412 - Terrazzo & Tile	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C3020413 - Vinyl Flooring	\$56,482	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$56,482
C3020414 - Wood Flooring	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C3020415 - Concrete Floor Finishes	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C3030 - Ceiling Finishes	\$144,158	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$144,158
D - Services	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D10 - Conveying	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D1010 - Elevators and Lifts	\$1,012,601	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$1,012,601
D20 - Plumbing	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D2010 - Plumbing Fixtures	\$64,361	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$64,361
D2020 - Domestic Water Distribution	\$355,112	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$168,882	\$523,994
D2030 - Sanitary Waste	\$345,370	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$345,370
D2040 - Rain Water Drainage	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$233,218	\$233,218
D30 - HVAC	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D3020 - Heat Generating Systems	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$1,822,137	\$0	\$1,822,137
D3030 - Cooling Generating Systems	\$819,029	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$819,029
D3040 - Distribution Systems	\$3,364,864	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$3,364,864
D3050 - Terminal & Package Units	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D3060 - Controls & Instrumentation	\$1,458,745	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$1,458,745
D40 - Fire Protection	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D4010 - Sprinklers	\$972,769	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$972,769
D4020 - Standpipes	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0


Site Assessment Report - B273001;Washington ES

D50 - Electrical	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5010 - Electrical Service/Distribution	\$709,940	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$709,940
D5020 - Lighting and Branch Wiring	\$700,282	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$700,282
D5030 - Communications and Security	\$421,527	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$421,527
D5090 - Other Electrical Systems	\$161,314	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$161,314
E - Equipment & Furnishings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E10 - Equipment	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E1020 - Institutional Equipment	\$293,595	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$470,418	\$0	\$764,012
E1090 - Other Equipment	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E20 - Furnishings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E2010 - Fixed Furnishings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0

* Indicates non-renewable system

Forecasted Sustainment Requirement

The following chart shows the current building deficiencies and forecasting sustainment requirements over the next ten years.




10 Year FCI Forecast by Investment Scenario

The chart below illustrates the effect of various investment levels on the building FCI for the next 10 years. The levels of investment shown below include:

- Current FCI: a variable investment amount based on renewing expired systems to maintain the current FCI for the building
- 2% Investment: an annual investment of 2% of the replacement value of the building, escalated for inflation
- 4% Investment: an annual investment of 4% of the replacement value of the building, escalated for inflation


Facility Investment vs. FCI Forecast



Year	Investment Amount Current FCI - 34.92%	2% Investment		4% Investment	
		Amount	FCI	Amount	FCI
2016	\$0	\$722,053.00	32.92 %	\$1,444,106.00	30.92 %
2017	\$16,410,871	\$743,714.00	75.05 %	\$1,487,429.00	71.05 %
2018	\$0	\$766,026.00	73.05 %	\$1,532,052.00	67.05 %
2019	\$0	\$789,007.00	71.05 %	\$1,578,013.00	63.05 %
2020	\$0	\$812,677.00	69.05 %	\$1,625,354.00	59.05 %
2021	\$1,147,708	\$837,057.00	69.79 %	\$1,674,114.00	57.79 %
2022	\$0	\$862,169.00	67.79 %	\$1,724,338.00	53.79 %
2023	\$1,273,499	\$888,034.00	68.66 %	\$1,776,068.00	52.66 %
2024	\$2,292,554	\$914,675.00	71.67 %	\$1,829,350.00	53.67 %
2025	\$402,100	\$942,115.00	70.53 %	\$1,884,230.00	50.53 %
Total:	\$21,526,732	\$8,277,527.00		\$16,555,054.00	

Deficiency Summary by System


Current deficiencies included assemblies that have reached or exceeded their design life or components of the assemblies that are in need of repair. Assemblies that have reached their design life are identified as current deficiencies and assigned the distress 'Beyond Useful Life'. The following chart lists all current deficiencies associated with this facility.



Budget Estimate Total: \$12,238,758.54

Deficiency Summary by Priority

The following chart shows the total repair costs broken down by priority. Assessors assigned deficiencies within eCOMET to one of the following priority categories:



Budget Estimate Total: \$12,238,758.54


Deficiency By Priority Investment Table

The table below shows the current investment cost grouped by deficiency priority and building system.

System Code	System Description	1 - Response Time (< 2 yr)	2 - Response Time (2-3 yrs)	3 - Response Time (3-4 yrs)	4 - Response Time (4-5 yrs)	5 - Response Time (> 5 yrs)	Total
B2010	Exterior Walls	\$0.00	\$32,460.39	\$0.00	\$0.00	\$0.00	\$32,460.39
B2020	Exterior Windows	\$0.00	\$0.00	\$0.00	\$1,084,920.99	\$0.00	\$1,084,920.99
B2030	Exterior Doors	\$0.00	\$0.00	\$127,502.49	\$0.00	\$0.00	\$127,502.49
C1020	Interior Doors	\$0.00	\$0.00	\$35,620.45	\$0.00	\$0.00	\$35,620.45
C1030	Fittings	\$0.00	\$16,623.54	\$0.00	\$0.00	\$0.00	\$16,623.54
C3010230	Paint & Covering	\$0.00	\$46,262.21	\$0.00	\$0.00	\$0.00	\$46,262.21
C3020411	Carpet	\$0.00	\$0.00	\$15,219.44	\$0.00	\$0.00	\$15,219.44
C3020413	Vinyl Flooring	\$0.00	\$0.00	\$56,482.40	\$0.00	\$0.00	\$56,482.40
C3030	Ceiling Finishes	\$0.00	\$144,157.98	\$0.00	\$0.00	\$0.00	\$144,157.98
D1010	Elevators and Lifts	\$0.00	\$1,012,601.25	\$0.00	\$0.00	\$0.00	\$1,012,601.25
D2010	Plumbing Fixtures	\$0.00	\$64,361.07	\$0.00	\$0.00	\$0.00	\$64,361.07
D2020	Domestic Water Distribution	\$10,167.21	\$363.98	\$0.00	\$0.00	\$344,580.79	\$355,111.98
D2030	Sanitary Waste	\$0.00	\$0.00	\$345,369.68	\$0.00	\$0.00	\$345,369.68
D3030	Cooling Generating Systems	\$0.00	\$0.00	\$0.00	\$0.00	\$819,029.04	\$819,029.04
D3040	Distribution Systems	\$0.00	\$2,479,607.40	\$885,256.16	\$0.00	\$0.00	\$3,364,863.56
D3060	Controls & Instrumentation	\$0.00	\$0.00	\$0.00	\$0.00	\$1,458,744.75	\$1,458,744.75
D4010	Sprinklers	\$0.00	\$0.00	\$0.00	\$0.00	\$972,768.92	\$972,768.92
D5010	Electrical Service/Distribution	\$0.00	\$0.00	\$709,940.38	\$0.00	\$0.00	\$709,940.38
D5020	Lighting and Branch Wiring	\$0.00	\$0.00	\$141,546.72	\$558,735.61	\$0.00	\$700,282.33
D5030	Communications and Security	\$0.00	\$0.00	\$162,415.22	\$259,111.56	\$0.00	\$421,526.78
D5090	Other Electrical Systems	\$0.00	\$0.00	\$161,314.21	\$0.00	\$0.00	\$161,314.21
E1020	Institutional Equipment	\$0.00	\$0.00	\$0.00	\$293,594.70	\$0.00	\$293,594.70
	Total:	\$10,167.21	\$3,796,437.82	\$2,640,667.15	\$2,196,362.86	\$3,595,123.50	\$12,238,758.54

Deficiency Summary by Category

The following chart shows the total repair costs broken down by deficiency categories. Assessors assigned deficiencies to one of the following categories:



Deficiency Details by Priority

The deficiency detail notes listed below provide additional information on identified deficiencies found within the facility.

Priority 1 - Response Time (< 2 yr):

System: D2020 - Domestic Water Distribution



Location: Mechanical room

Distress: Energy Efficiency

Category: 4 - Capital Improvement

Priority: 1 - Response Time (< 2 yr)

Correction: Provide expansion tank for water heater.

Qty: 1.00

Unit of Measure: Ea.

Estimate: \$10,167.21

Assessor Name: System

Date Created: 01/21/2016

Notes: Install hydro-pneumatic storage tank for domestic water booster system

Priority 2 - Response Time (2-3 yrs):

System: B2010 - Exterior Walls



Location: Lower windows

Distress: Building Envelope Integrity

Category: 3 - Operations / Maint.

Priority: 2 - Response Time (2-3 yrs)

Correction: Remove and replacing failing steel lintels in brick wall construction

Qty: 50.00

Unit of Measure: L.F.

Estimate: \$32,460.39

Assessor Name: System

Date Created: 11/13/2015

Notes: Replace and repair failing window lintels and surrounding masonry

System: C1030 - Fittings



Location: Toilets

Distress: Accessibility

Category: 2 - Code Compliance

Priority: 2 - Response Time (2-3 yrs)

Correction: Remove and replace damaged toilet partitions - handicap units

Qty: 17.00

Unit of Measure: Ea.

Estimate: \$16,623.54

Assessor Name: System

Date Created: 11/13/2015

Notes: Provide new toilet partitions and toilet accessories including grab bars for accessibility

System: C3010230 - Paint & Covering



Location: Various

Distress: Damaged

Category: 3 - Operations / Maint.

Priority: 2 - Response Time (2-3 yrs)

Correction: Repair substrate and repaint interior walls - SF of wall surface

Qty: 5,400.00

Unit of Measure: S.F.

Estimate: \$46,262.21

Assessor Name: System

Date Created: 11/13/2015

Notes: Repair and repaint interior walls (5% of painted wall surface)

System: C3030 - Ceiling Finishes



Location: Corridors

Distress: Appearance

Category: 3 - Operations / Maint.

Priority: 2 - Response Time (2-3 yrs)

Correction: Remove and replace suspended acoustic ceilings - lighting not included

Qty: 10,000.00

Unit of Measure: S.F.

Estimate: \$99,536.10

Assessor Name: System

Date Created: 11/13/2015

Notes: Install suspended acoustic tile ceiling system in corridors for appearance

System: C3030 - Ceiling Finishes



Location: Various

Distress: Damaged

Category: 3 - Operations / Maint.

Priority: 2 - Response Time (2-3 yrs)

Correction: Repair and resurface plaster ceilings - 2 coats plaster

Qty: 3,400.00

Unit of Measure: S.F.

Estimate: \$44,621.88

Assessor Name: System

Date Created: 11/13/2015

Notes: Repair and repaint interior ceiling (10% of painted ceiling surface)

System: D1010 - Elevators and Lifts



Location: TBD

Distress: Accessibility

Category: 2 - Code Compliance

Priority: 2 - Response Time (2-3 yrs)

Correction: Add external 4 stop elevator - adjust the electrical run lengths to hook up the elevator

Qty: 1.00

Unit of Measure: Ea.


Estimate: \$1,012,601.25

Assessor Name: System

Date Created: 11/13/2015

Notes: Install elevator for accessibility (location TBD)

System: D2010 - Plumbing Fixtures



Location: Corridors

Distress: Accessibility

Category: 2 - Code Compliance

Priority: 2 - Response Time (2-3 yrs)

Correction: Remove and replace water fountains to meet ADA - includes high and low fountains and new recessed alcove

Qty: 4.00

Unit of Measure: Ea.


Estimate: \$62,771.59

Assessor Name: System

Date Created: 01/19/2016

Notes: Replace drinking fountains with accessible ones with chillers

System: D2010 - Plumbing Fixtures



Location: Kitchen, classrooms

Distress: Failing

Category: 3 - Operations / Maint.

Priority: 2 - Response Time (2-3 yrs)

Correction: Replace lavatory faucet

Qty: 6.00

Unit of Measure: Ea.

Estimate: \$1,589.48

Assessor Name: System

Date Created: 01/21/2016

Notes: Replace head start, kitchen, and science room faucets due to leaks and other operational failures

System: D2020 - Domestic Water Distribution



Location: Boiler room

Distress: Energy Efficiency

Category: 4 - Capital Improvement

Priority: 2 - Response Time (2-3 yrs)

Correction: Replace pipe and fittings

Qty: 1.00

Unit of Measure: L.F.

Estimate: \$363.98

Assessor Name: System

Date Created: 01/21/2016

Notes: Insulate domestic hot water storage tank to conserve energy

System: D3040 - Distribution Systems



Location: Classrooms, gym

Distress: Beyond Service Life

Category: 3 - Operations / Maint.

Priority: 2 - Response Time (2-3 yrs)

Correction: Replace classroom unit ventilator (htg/clg coils, 5 tons, 2,000 CFM)

Qty: 50.00

Unit of Measure: Ea.

Estimate: \$2,479,607.40

Assessor Name: System

Date Created: 01/22/2016

Notes: Replace aged unit ventilators and convectors

Priority 3 - Response Time (3-4 yrs):

System: B2030 - Exterior Doors



Location: Ext. doors

Distress: Failing

Category: 3 - Operations / Maint.

Priority: 3 - Response Time (3-4 yrs)

Correction: Remove and replace exterior doors - per leaf

Qty: 14.00

Unit of Measure: Ea.

Estimate: \$127,502.49

Assessor Name: System

Date Created: 11/13/2015

Notes: Replace exterior doors – rusted failing

System: C1020 - Interior Doors



Location: Throughout

Distress: Accessibility

Category: 2 - Code Compliance

Priority: 3 - Response Time (3-4 yrs)

Correction: Replace door knobs with compliant lever type

Qty: 64.00

Unit of Measure: Ea.

Estimate: \$35,620.45

Assessor Name: System

Date Created: 11/13/2015

Notes: Provide ADA lever handle lock/latchsets on interior doors

System: C3020411 - Carpet



Location: Kindergarten

Distress: Beyond Service Life

Category: 3 - Operations / Maint.

Priority: 3 - Response Time (3-4 yrs)

Correction: Remove and replace carpet

Qty: 1,360.00

Unit of Measure: S.F.

Estimate: \$15,219.44

Assessor Name: System

Date Created: 11/13/2015

Notes: Replace carpet – beyond service life

System: C3020413 - Vinyl Flooring



Location: Various

Distress: Beyond Service Life

Category: 3 - Operations / Maint.

Priority: 3 - Response Time (3-4 yrs)

Correction: Remove and replace VCT

Qty: 4,700.00

Unit of Measure: S.F.

Estimate: \$56,482.40

Assessor Name: System

Date Created: 11/13/2015

Notes: Replace VCT flooring – damaged failing (30% of vinyl floor area)

System: D2030 - Sanitary Waste



Location: Entire building

Distress: Failing

Category: 3 - Operations / Maint.

Priority: 3 - Response Time (3-4 yrs)

Correction: Inspect sanitary waste piping and replace damaged sections. (+50KSF)

Qty: 68,000.00

Unit of Measure: S.F.

Estimate: \$345,369.68

Assessor Name: System

Date Created: 01/21/2016

Notes: Inspect and repair or replace sanitary drain pipe as needed due to age, operation, and appearance including sewage ejector replacement

System: D3040 - Distribution Systems



Location: Entire building

Distress: Beyond Service Life

Category: 3 - Operations / Maint.

Priority: 3 - Response Time (3-4 yrs)

Correction: Perform testing to identify and replace damaged steam and condensate piping.

Qty: 68,000.00

Unit of Measure: S.F.

Estimate: \$643,305.24

Assessor Name: System

Date Created: 01/22/2016

Notes: Inspect and repair steam and condensate pipes due to age

System: D3040 - Distribution Systems



Location: Mechanical room

Distress: Obsolete

Category: 3 - Operations / Maint.

Priority: 3 - Response Time (3-4 yrs)

Correction: Install / replace HVAC unit for Auditorium (800 seat).

Qty: 800.00

Unit of Measure: Seat

Estimate: \$241,950.92

Assessor Name: System

Date Created: 01/22/2016

Notes: Replace obsolete AHU serving auditorium

System: D5010 - Electrical Service/Distribution



Location: Entire Building

Distress: Beyond Service Life

Category: 3 - Operations / Maint.

Priority: 3 - Response Time (3-4 yrs)

Correction: Replace Electrical Distribution System (U)

Qty: 1.00

Unit of Measure: Ea.

Estimate: \$369,048.20

Assessor Name: System

Date Created: 12/22/2015

Notes: Replace the entire distribution system with new panels and new wiring/conduits. Approximate (15) 208/120V.

System: D5010 - Electrical Service/Distribution



Location: Basement

Distress: Obsolete

Category: 3 - Operations / Maint.

Priority: 3 - Response Time (3-4 yrs)

Correction: Replace Switchboard

Qty: 1.00

Unit of Measure: Ea.


Estimate: \$340,892.18

Assessor Name: System

Date Created: 12/22/2015

Notes: Provide new service 480V/277V, 3 phase power, approximate 1000 Amperes.

System: D5020 - Lighting and Branch Wiring



Location: Entire Building

Distress: Inadequate

Category: 4 - Capital Improvement

Priority: 3 - Response Time (3-4 yrs)

Correction: Add wiring device

Qty: 390.00

Unit of Measure: Ea.

Estimate: \$141,546.72

Assessor Name: System

Date Created: 12/22/2015

Notes: The teacher's whiteboard wall and the opposite of it need to be provided with double compartment surface raceways, the other two walls with minimum two duplex outlets each. Approximate 390 receptacles

System: D5030 - Communications and Security



Location: Entire Building

Distress: Health Hazard / Risk

Category: 1 - Health & Safety

Priority: 3 - Response Time (3-4 yrs)

Correction: Replace fire alarm system

Qty: 1.00

Unit of Measure: S.F.

Estimate: \$162,415.22

Assessor Name: System

Date Created: 12/22/2015

Notes: Provide a new addressable fire alarm system. Approximate 90 devices.

System: D5090 - Other Electrical Systems



Location: Outdoor

Distress: Beyond Service Life

Category: 3 - Operations / Maint.

Priority: 3 - Response Time (3-4 yrs)

Correction: Add Standby Generator System

Qty: 1.00

Unit of Measure: Ea.

Estimate: \$137,064.39

Assessor Name: System

Date Created: 12/29/2015

Notes: Provide an outdoor diesel powered generator. Approximate 70KW

System: D5090 - Other Electrical Systems



Location: Roof

Distress: Building / MEP Codes

Category: 2 - Code Compliance

Priority: 3 - Response Time (3-4 yrs)

Correction: Repair Lightning Protection System

Qty: 1.00

Unit of Measure: Job

Estimate: \$24,249.82


Assessor Name: System

Date Created: 12/29/2015

Notes: Prepare a study to determine if the air terminals installed in the chimney provide the proper coverage to the school.

Priority 4 - Response Time (4-5 yrs):

System: B2020 - Exterior Windows



Location: Ext. windows

Distress: Energy Efficiency

Category: 4 - Capital Improvement

Priority: 4 - Response Time (4-5 yrs)

Correction: Remove and replace double slider windows

Qty: 215.00

Unit of Measure: Ea.


Estimate: \$1,084,920.99

Assessor Name: System

Date Created: 11/13/2015

Notes: Replace Plexiglas windows – hazed

System: D5020 - Lighting and Branch Wiring



Location: Entire Building

Distress: Obsolete

Category: 3 - Operations / Maint.

Priority: 4 - Response Time (4-5 yrs)

Correction: Add Lighting Fixtures

Qty: 629.00

Unit of Measure: Ea.


Estimate: \$558,735.61

Assessor Name: System

Date Created: 12/22/2015

Notes: Replace 70% of the fluorescent fixtures with pendant mounted up/down fixture with T-8 lamps. Approximate 629 fixtures.

System: D5030 - Communications and Security



Location: Entire Building
Distress: Security Issue
Category: 1 - Health & Safety
Priority: 4 - Response Time (4-5 yrs)
Correction: Add/Replace Video Surveillance System
Qty: 1.00
Unit of Measure: Ea.
Estimate: \$120,669.80
Assessor Name: System
Date Created: 12/28/2015

Notes: Add surveillance CCTV cameras for a complete coverage of the school building interior. Approximate 30

System: D5030 - Communications and Security



Location: Entire Building
Distress: Obsolete
Category: 3 - Operations / Maint.
Priority: 4 - Response Time (4-5 yrs)
Correction: Add/Replace Clock System or Components
Qty: 50.00
Unit of Measure: Ea.
Estimate: \$112,560.22
Assessor Name: System
Date Created: 12/28/2015

Notes: Provide a clock system with wireless, battery operated clocks. Approximate 50 clocks.

System: D5030 - Communications and Security



Location: Auditorium

Distress: Damaged

Category: 3 - Operations / Maint.

Priority: 4 - Response Time (4-5 yrs)

Correction: Add/Replace Sound System

Qty: 1.00

Unit of Measure: LS

Estimate: \$25,881.54

Assessor Name: System

Date Created: 12/29/2015

Notes: Provide the auditorium with a sound system.

System: E1020 - Institutional Equipment



Location: Auditorium

Distress: Inadequate

Category: 4 - Capital Improvement

Priority: 4 - Response Time (4-5 yrs)

Correction: Add/Replace Stage Theatrical Lighting System

Qty: 1.00

Unit of Measure: Ea.

Estimate: \$293,594.70

Assessor Name: System

Date Created: 12/29/2015

Notes: Provide the auditorium with dimming and theatrical lighting.

Priority 5 - Response Time (> 5 yrs):

System: D2020 - Domestic Water Distribution



Location: Entire building

Distress: Beyond Service Life

Category: 3 - Operations / Maint.

Priority: 5 - Response Time (> 5 yrs)

Correction: Replace domestic water piping (75 KSF)

Qty: 68,000.00

Unit of Measure: S.F.

Estimate: \$344,580.79

Assessor Name: System

Date Created: 01/21/2016

Notes: Replace domestic water distribution pipe due to age

System: D3030 - Cooling Generating Systems



Location: Entire building

Distress: Inadequate

Category: 4 - Capital Improvement

Priority: 5 - Response Time (> 5 yrs)

Correction: Install chilled water system with distribution piping and pumps. (+75KSF)

Qty: 51,000.00

Unit of Measure: S.F.

Estimate: \$819,029.04

Assessor Name: System

Date Created: 01/22/2016

Notes: Install 170 ton chiller system to provide cooling for entire building

System: D3060 - Controls & Instrumentation



Location: Entire building

Distress: Obsolete

Category: 3 - Operations / Maint.

Priority: 5 - Response Time (> 5 yrs)

Correction: Replace pneumatic controls with DDC (75KSF)

Qty: 68,000.00

Unit of Measure: S.F.

Estimate: \$1,458,744.75

Assessor Name: System

Date Created: 01/22/2016

Notes: Install DDC to replace obsolete pneumatic controls

System: D4010 - Sprinklers



Location: Entire building

Distress: Life Safety / NFPA / PFD

Category: 2 - Code Compliance

Priority: 5 - Response Time (> 5 yrs)

Correction: Install a fire protection sprinkler system

Qty: 68,000.00

Unit of Measure: S.F.

Estimate: \$972,768.92

Assessor Name: System

Date Created: 01/21/2016

Notes: Install fire protection sprinkler system with fire pump if needed

Equipment Inventory

The following table represents the inventory details of the inventory found in the building, which fall under the following subsystems:

Subsystem	Inventory	Qty	UoM	Location	Manufacturer	Model Number	Serial Number	Barcode	Life	Install Date	Next Renewal	Raw Cost	Inventory Cost
D2020 Domestic Water Distribution	Pump, pressure booster system, 3 HP pump, includes diaphragm tank, control and pressure switch	1.00	Ea.	Mechanical room					25	1995	2020	\$9,861.00	\$10,847.10
D3020 Heat Generating Systems	Boiler, gas/oil combination, cast iron, steam, gross output, 2040 MBH, includes burners, controls and insulated jacket, packaged	2.00	Ea.	Boiler room					35	1989	2024	\$43,116.20	\$94,855.64
D5010 Electrical Service/Distribution	Panelboards, 3 pole 3 wire, main lugs, 240 V, 400 amp, no main breaker	1.00	Ea.	Basement Electrical Room					30	1937	2047	\$2,297.70	\$2,527.47
												Total:	\$108,230.21

Executive Summary

Building condition is evaluated based on the functional systems and elements of a building and organized according to the UNIFORMAT II Elemental Classification. The grouping of these systems and elements and applying a current replacement value to them develops a representative building cost model. Cost Models are developed for similar building types and functions. Systems and their elements are evaluated based on their current replacement values, life cycles, installation dates and next renewal dates. Systems and their elements that are within their useful lives are further evaluated to identify current deficient conditions that may have a significant impact on a system's or element's remaining service life, and to determine if they are beyond their predicted expected life. The system's or element's current replacement value is based on RS Means Commercial Cost Data.

Following are the cost model's system details for this facility. The Replacement Value is the amount needed to replace the property of the same present value. The Current Repair Amount, also known as Condition Needs, represents the budgeted contractor installed costs plus owner's soft costs for the repair, replacement or renewal for a component or system level deficiency. It excludes contributing costs for other components or systems that might also be associated with the corrective actions due to packaging the work. Facility Condition Index (FCI) FCI is an industry-standard measurement of facility condition calculated as the ratio of the costs to correct a facility's deficiencies to the facility's Current Replacement Value. It ranges from 0% (new) to 100% (very poor). Condition Index (CI) is calculated as the sum of a renewable system's Remaining Service Life (RSL) divided by the sum of a system's Replacement Value (both values exclude soft-cost to simplify calculation updates) expressed as a percentage ranging from 100% (new) to 0% (expired).

Function:

Gross Area (SF): 27,500

Year Built: 1937

Last Renovation:

Replacement Value: \$616,833

Repair Cost: \$544,860.33

Total FCI: 88.33 %

Total RSLI: 105.82 %



Description:

Attributes:

General Attributes:

Bldg ID:	S273001	Site ID:	S273001
----------	---------	----------	---------

Condition Summary

The Table below shows the CI and FCI for each major building system shown at the UNIFORMAT classification Level II. Note that Systems with lower FCIs require less investment than systems with higher FCIs.

UNIFORMAT Classification	RSLI %	FCI %	Current Repair Cost
G20 - Site Improvements	105.49 %	61.74 %	\$274,021.84
G40 - Site Electrical Utilities	106.67 %	156.58 %	\$270,838.49
Totals:	105.82 %	88.33 %	\$544,860.33

Condition Detail

This section of the report contains results of the Facility Condition Assessment. The building is separated into system components based on UNIFORMAT II classification. The columns in the System Listing table below represent the following:

1. System Code: A code that identifies the system.
2. System Description: A brief description of a system present in the building.
3. Unit Price \$: The unit price of the system.
4. UoM: The unit of measure for of the system.
5. Qty: The quantity for the system
6. Life: anticipated service life for thesystem based on Building Owners and Managers Association (BOMA) recommendations.
7. Year Installed: The date of system installation.
8. Calc Next Renewal Year: The date of system expiration based on the life, NR stands for non renewable.
9. Next Renewal Year: The suggested system expiration date by the assessor based on visual inspection.
10. CI: The Condition Index of the system.
11. FCI: The Facility Condition Index of the system.
12. RSL: Remaining Service Life.
13. eCR: eCOMET Condition Rating (not used).
14. Deficiency \$: The financial investment to repair/replace system.

System Listing

The System Listing table below lists each of the systems organized by their UNIFORMAT II classification. The assessment team was tasked with recording the most recent replacement year of each system, determining the remaining service life based on the theoretical life, and evaluating the condition to confirm the forecast next replacement year. The system listing is the basis for all data contained in the Building Assessment Report.

Additionally, a condition rating (eCR) based on the following guidelines is provided as observed at the time of the assessment.

- Excellent (E) - No noticeable distress or damage. The entire system is free from observable defect.
- Very Good (VG) - Overall no serviceability reduction for the entire system. No degradation of critical components and minor distress and defect noticeable for some but not non critical components within the system.
- Good (G) - Slight or no serviceability reduction for the entire system. There may be noticeable defects for some non critical components and slight noticeable degradation of the critical components.
- Fair (F) - Overall serviceability is degraded but adequate. There may be moderate deterioration for very few of the critical components and few of the non critical components may have severe degradation.
- Marginal (MA) - Overall serviceability and reliability loss. Most if not all of the non critical components suffer from severe degradation and a few of the critical component may have severe degradation.
- Moderate (MO) - Overall a significant serviceability loss. Most if not all the components have severe degradation with the reminder of the component showing visible distress.
- Very Poor (VP) - Overall the system is barely functional. All of the components are severely degraded.
- Non-Functional (NF) - Overall the system does not function with all the components having no serviceability and suffer from severe degradation.

System Code	System Description	Unit Price \$	UoM	Qty	Life	Year Installed	Calc Next Renewal Year	Next Renewal Year	RSLI%	FCI%	RSL	eCR	Deficiency \$	Replacement Value \$
G2010	Roadways	\$11.52	S.F.		30				0.00 %	0.00 %				\$0
G2020	Parking Lots	\$8.50	S.F.		30				0.00 %	0.00 %				\$0
G2030	Pedestrian Paving	\$12.30	S.F.	25,700	40	1937	1977	2057	105.00 %	69.81 %	42		\$220,685.94	\$316,110
G2040	Site Development	\$4.36	S.F.	27,500	25	1937	1962	2042	108.00 %	44.48 %	27		\$53,335.90	\$119,900
G2050	Landscaping & Irrigation	\$4.36	S.F.	1,800	15	1937	1952	2028	86.67 %	0.00 %	13			\$7,848
G4020	Site Lighting	\$4.84	S.F.	27,500	30	1937	1967	2047	106.67 %	61.89 %	32		\$82,377.78	\$133,100
G4030	Site Communications & Security	\$1.45	S.F.	27,500	30	1937	1967	2047	106.67 %	472.63 %	32		\$188,460.71	\$39,875
Total									105.82 %	88.33 %			\$544,860.33	\$616,833

System Notes

The facility description in the site executive summary contains an overview of each system. The notes listed below provide additional information on select systems found within the facility.

No data found for this asset

Renewal Schedule

eCOMET forecasts future Capital Renewal funding needed to address expiring systems based on the Next Renewal year found in the Cost Models. A 3% annual inflation factor is applied to the costs for systems expiring in future years. The table below reflects recommended Capital Renewal funding needs over the next 10 years. Note: Cells with a zero value indicate systems for which renewal is not scheduled in that year.


Inflation Rate: 3%

System	Current Deficiencies	2016	2017	2018	2019	2020	2021	2022	2023	2024	2025	Total
Total:	\$544,860	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$544,860
G - Building Sitework	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G20 - Site Improvements	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G2010 - Roadways	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G2020 - Parking Lots	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G2030 - Pedestrian Paving	\$220,686	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$220,686
G2040 - Site Development	\$53,336	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$53,336
G2050 - Landscaping & Irrigation	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G40 - Site Electrical Utilities	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G4020 - Site Lighting	\$82,378	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$82,378
G4030 - Site Communications & Security	\$188,461	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$188,461

** Indicates non-renewable system*

Forecasted Sustainment Requirement

The following chart shows the current building deficiencies and forecasting sustainment requirements over the next ten years.




10 Year FCI Forecast by Investment Scenario

The chart below illustrates the effect of various investment levels on the building FCI for the next 10 years. The levels of investment shown below include:

- Current FCI: a variable investment amount based on renewing expired systems to maintain the current FCI for the building
- 2% Investment: an annual investment of 2% of the replacement value of the building, escalated for inflation
- 4% Investment: an annual investment of 4% of the replacement value of the building, escalated for inflation


Facility Investment vs. FCI Forecast



Year	Investment Amount Current FCI - 88.33%	2% Investment		4% Investment	
		Amount	FCI	Amount	FCI
2016	\$0	\$12,707.00	86.33 %	\$25,414.00	84.33 %
2017	\$710,680	\$13,088.00	192.93 %	\$26,176.00	188.93 %
2018	\$0	\$13,481.00	190.93 %	\$26,961.00	184.93 %
2019	\$0	\$13,885.00	188.93 %	\$27,770.00	180.93 %
2020	\$0	\$14,302.00	186.93 %	\$28,603.00	176.93 %
2021	\$0	\$14,731.00	184.93 %	\$29,461.00	172.93 %
2022	\$0	\$15,173.00	182.93 %	\$30,345.00	168.93 %
2023	\$0	\$15,628.00	180.93 %	\$31,255.00	164.93 %
2024	\$0	\$16,097.00	178.93 %	\$32,193.00	160.93 %
2025	\$0	\$16,579.00	176.93 %	\$33,159.00	156.93 %
Total:	\$710,680	\$145,671.00		\$291,337.00	

Deficiency Summary by System


Current deficiencies included assemblies that have reached or exceeded their design life or components of the assemblies that are in need of repair. Assemblies that have reached their design life are identified as current deficiencies and assigned the distress 'Beyond Useful Life'. The following chart lists all current deficiencies associated with this facility.



Budget Estimate Total: \$544,860.33

Deficiency Summary by Priority

The following chart shows the total repair costs broken down by priority. Assessors assigned deficiencies within eCOMET to one of the following priority categories:



Budget Estimate Total: \$544,860.33


Deficiency By Priority Investment Table

The table below shows the current investment cost grouped by deficiency priority and building system.

System Code	System Description	1 - Response Time (< 2 yr)	2 - Response Time (2-3 yrs)	3 - Response Time (3-4 yrs)	4 - Response Time (4-5 yrs)	5 - Response Time (> 5 yrs)	Total
G2030	Pedestrian Paving	\$25,981.81	\$2,907.21	\$191,796.92	\$0.00	\$0.00	\$220,685.94
G2040	Site Development	\$0.00	\$53,335.90	\$0.00	\$0.00	\$0.00	\$53,335.90
G4020	Site Lighting	\$0.00	\$0.00	\$0.00	\$82,377.78	\$0.00	\$82,377.78
G4030	Site Communications & Security	\$0.00	\$0.00	\$184,377.46	\$4,083.25	\$0.00	\$188,460.71
	Total:	\$25,981.81	\$56,243.11	\$376,174.38	\$86,461.03	\$0.00	\$544,860.33

Deficiency Summary by Category

The following chart shows the total repair costs broken down by deficiency categories. Assessors assigned deficiencies to one of the following categories:



Deficiency Details by Priority

The deficiency detail notes listed below provide additional information on identified deficiencies found within the facility.

Priority 1 - Response Time (< 2 yr):

System: G2030 - Pedestrian Paving



Location: Entrance

Distress: Accessibility

Category: 2 - Code Compliance

Priority: 1 - Response Time (< 2 yr)

Correction: Install an exterior ADA ramp - based on 5' wide by the linear foot - up to a 48" rise - per LF of ramp - figure 1 LF per inch of rise

Qty: 20.00

Unit of Measure: L.F.

Estimate: \$25,981.81

Assessor Name: Craig Anding

Date Created: 11/13/2015

Notes: Provide ADA compliant ramp for at least one entrance (location TBD)

Priority 2 - Response Time (2-3 yrs):

System: G2030 - Pedestrian Paving



Location: North entrance

Distress: Building Envelope Integrity

Category: 3 - Operations / Maint.

Priority: 2 - Response Time (2-3 yrs)

Correction: Remove and replace concrete paving - pedestrian or parking - 8" concrete thickness

Qty: 20.00

Unit of Measure: S.F.

Estimate: \$2,907.21

Assessor Name: Craig Anding

Date Created: 01/22/2016

Notes: Repair and seal large crack at north entrance stairs

System: G2040 - Site Development



Location: Site

Distress: Health Hazard / Risk

Category: 1 - Health & Safety

Priority: 2 - Response Time (2-3 yrs)

Correction: Remove and replace metal picket fence - input number of gates

Qty: 300.00

Unit of Measure: L.F.

Estimate: \$53,335.90

Assessor Name: Craig Anding

Date Created: 11/13/2015

Notes: Replace metal fence and gates – rusted and hazard to safety

Priority 3 - Response Time (3-4 yrs):

System: G2030 - Pedestrian Paving



Location: Playard

Distress: Damaged

Category: 3 - Operations / Maint.

Priority: 3 - Response Time (3-4 yrs)

Correction: Remove and replace concrete paving - pedestrian or parking - 8" concrete thickness

Qty: 7,300.00

Unit of Measure: S.F.

Estimate: \$191,796.92

Assessor Name: Craig Anding

Date Created: 11/13/2015

Notes: Repair damaged concrete play yard sections – (40% of play yard area)

System: G4030 - Site Communications & Security



Location: Building Perimeter

Distress: Security Issue

Category: 1 - Health & Safety

Priority: 3 - Response Time (3-4 yrs)

Correction: Add Video Surveillance System

Qty: 10.00

Unit of Measure: Ea.

Estimate: \$184,377.46

Assessor Name: Craig Anding

Date Created: 12/29/2015

Notes: Add surveillance CCTV cameras to provide a complete coverage of the building perimeter. Approximate 10

Priority 4 - Response Time (4-5 yrs):

System: G4020 - Site Lighting



Location: Building Perimeter

Distress: Security Issue

Category: 1 - Health & Safety

Priority: 4 - Response Time (4-5 yrs)

Correction: Add site lighting fixtures

Qty: 16.00

Unit of Measure: Ea.

Estimate: \$82,377.78

Assessor Name: Craig Anding

Date Created: 12/29/2015

Notes: Add outdoor wall mounted lighting fixtures to provide a safer and better illumination. Approximate 16 HID fixtures

System: G4030 - Site Communications & Security



Location: Building Perimeter

Distress: Inadequate

Category: 4 - Capital Improvement

Priority: 4 - Response Time (4-5 yrs)

Correction: Add Site Paging System

Qty: 1.00

Unit of Measure: Ea.

Estimate: \$4,083.25

Assessor Name: Craig Anding

Date Created: 12/29/2015

Notes: Provide an outdoor loud speaker facing the playground area

Equipment Inventory

The following table represents the inventory details of the inventory found in the building, which fall under the following subsystems:

No data found for this asset

Glossary

ABMA	American Boiler Manufacturers Association http://www.abma.com/
ACEEE	American Council for an Energy-Efficient Economy
ACGIH	American Council of Governmental and Industrial Hygienists
AEE	Association of Energy Engineers
AFD	Adjustable Frequency Drive
AFTC	After Tax Cash Flow
AGA	American Gas Association
AHU	Air Handling Unit
Amp	Ampere
ANSI	American National Standards Institute
ARI	Air Conditioning and Refrigeration Institute
ASD	Adjustable Speed Drive
ASHRAE	American Society of Heating Refrigerating and Air-Conditioning Engineers Inc.
ASME	American Society of Mechanical Engineers
Assessment	Visual survey of a facility to determine its condition. It involves looking at the age of systems reviewing information from local sources and visual evidence of potential problems to assign a condition rating. It does not include destructive testing of materials or testing of systems or equipment for functionality.
ATS	After Tax Savings
AW	Annual worth
BACNET	Building Automation Control Network
BAS	Building Automation System
BCR	Benefit Cost Ratio
BEP	Business Energy Professional (AEE)
BF	Ballast Factor
BHP	Boiler Horsepower (boilers)
BHP	Brake Horsepower (motors)
BLCC	Building Life Cycle Cost analysis program (FEMP)
BOCA	Building Officials and Code Administrators
BTCF	Before Tax Cash Flow

Site Assessment Report - S273001;Washington ES

BTS	Before Tax Savings
Btu	British thermal unit
Building Addition	An area space or component of a building added to a building after the original building's year built date.
CAA	Clean Air Act
CAAA-90	Clean Air Act Amendments of 1990
CABO	Council of American Building Officials
CAC	Conventional Air Conditioning
CADDET	Center for the Analysis and Dissemination of Demonstrated Energy Technologies
Calculated Next Renewal	The year a system or element would be expected to expire based solely on the date it was installed and the expected useful lifetime for that kind of system.
Capital Renewal	Capital renewal is condition work (excluding suitability and energy audit work) that includes the replacement of building systems or elements (as they become obsolete or beyond their useful life) not normally included in an annual operating budget. Calculated next renewal The year a system or element would be expected to expire based solely on the date it was installed and the expected useful lifetime for that kind of system. Next renewal The assessor adjusted expected useful life of a system or element based on on-site inspection.
CDD	Cooling Degree Days
CDGP	Certified Distributed Generation Professional
CEC	California Energy Commission
CEM	Certified Energy Manager
CEP	Certified Energy Procurement Professional
CFC	Chlorofluorocarbon
CFD	Cash Flow Diagram
CFL	Compact Fluorescent Light
CFM cfm	Cubic Feet per Minute
CHP	Combined Heat and Power (a.k.a. cogeneration)
CHW	Chilled Water
Condition	Condition refers to the state of physical fitness or readiness of a facility system or system element for its intended use.
COP	Coefficient of Performance
Cp	Heat Capacity of Material
CPUC	California Public Utility Commission
CRI	Color Rendering Index
CRT	Cathode Ray Tube VDT HMI

Site Assessment Report - S273001;Washington ES

CTC	Competitive Transition Charge
Cu	Coefficient of Utilization
Current Replacement Value (CRV)	CRV represents the hypothetical total cost of rebuilding or replacing an existing facility in current dollars to its optimal condition (excluding auxiliary facilities) under current codes and construction standards.
Cv	Value Coefficient
CWS	Chilled Water System
D d	Distance (usually feet)
DB	Dry Bulb
DCV	Demand Control Ventilation
DD	Degree Day
DDB	Double Declining Balance
DDC	Direct Digital Controls
Deferred maintenance	Deferred maintenance is condition work (excluding suitability and energy audit needs) deferred on a planned or unplanned basis to a future budget cycle or postponed until funds are available.
Deficiency	A deficiency is a repair item that is damaged missing inadequate or insufficient for an intended purpose.
Delta	Difference
Delta P	Pressure Difference
Delta T	Temperature Difference
DG	Distributed Generation
DOE	Department of Energy
DP	Dew Point
DR	Demand Response
DX	Direct Expansion Air Conditioner
EA	Energy Audit
EBITDA	Earnings before Interest Taxes Depreciation and Amortization
ECI	Energy Cost Index
ECM	Energy Conservation Measure
ECO	Energy Conservation Opportunity
ECPA	Energy Conservation and Production Act
ECR	Energy Conservation Recommendation
ECS	Energy Control System

Site Assessment Report - S273001;Washington ES

EER	Energy Efficiency Ratio
EERE	Energy Efficiency and Renewable Energy division of US DOE
EIA	Energy Information Agency
EIS	Energy Information System
EMCS	Energy Management Computer System
EMO	Energy Management Opportunity
EMP	Energy Management Project
EMR	Energy Management Recommendation
EMS	Energy Management System
Energy Utilization Index (EUI)	EUI is the measure of total energy consumed in the cooling or heating of a building in a period expressed as British thermal unit (BTU) per (cooled or heated) gross square foot.
EO	Executive Order
EPA	Environmental Protection Agency
EPACT	Energy Policy Act of 1992
EPCA	Energy Production and Conservation Act of 1975
EPRI	Electric Power Research Institute
EREN	Efficiency and Renewable Energy (Division of USDOE)
ERV	Energy Recovery Ventilator
ESCO	Energy Service Company
ESPC	Energy Savings Performance Contract
EUI	Energy Use Index
EWG	Exempt Wholesale Generators
Extended Facility Condition Index (EFCI)	EFCI is calculated as the condition needs for the current year plus facility system renewal needs going out to a set time in the future divided by Current Replacement Value.
f	Frequency
F	Fahrenheit
Facility	A facility refers to site(s) building(s) or building addition(s) or combinations thereof that provide a particular service.
Facility Condition Assessment (FCA)	FCA is a process for evaluating the condition of buildings and facilities for programming and budgetary purposes through an on site inspection and evaluation process.
Facility Condition Index (FCI)	FCI is an industry-standard measurement of a facility's condition that is the ratio of the cost to correct a facility's deficiencies to the Current Replacement Value of the facilities. The higher the FCI the poorer the condition of a facility. After an FCI is established for all buildings within a portfolio a building's condition can be ranked relative to other buildings. The FCI may also represent the condition of a portfolio based on the cumulative FCIs of the portfolio's facilities.

Site Assessment Report - S273001;Washington ES

FC	Footcandle
FCA	Fuel Cost Adjustment
FEMIA	Federal Energy Management Improvement Act of 1988
FEMP	Federal Energy Management Program
FERC	Federal Energy Regulatory Commission
FESR	Fuel Energy Savings Ratio
FLA	Full Load Amps
FLF	Facility Load Factor (usually monthly)
FLRPM	Full Load Revolutions per Minute
FMS	Facility Management System
FPM fpm	Feet per Minute (velocity)
FSEC	Florida Solar Energy Center
Ft	Foot
GPM gpm	Gallons per Minute
GRI	Gas Research Institute
Gross Square Feet (GSF)	The size of the enclosed floor space of a building in square feet measured to the outside face of the enclosing wall.
GUI	Graphical User Interface
H h	Enthalpy Btu/lb
HCFC	Hydrochlorofluorocarbons
HDD	Heating Degree days
HFC	Hydrofluorocarbons
HHV	Higher Heating Value
HID	High Intensity Discharge (lamp)
HMI	Human Machine Interface
HMMI	Human Man Machine Interface
HO	High Output (lamp)
HP Hp hp	Horsepower
HPS	High Pressure Sodium (lamp)
HR	Humidity Ratio
Hr hr	Hour

Site Assessment Report - S273001;Washington ES

HRU	Heat Recovery Unit
HVAC	Heating Ventilation and Air-Conditioning
Hz	Hertz
I	Intensity (lumen output of lamp)
I i	Interest rate or Discount rate
IAQ	Indoor Air Quality
ICA	International Cogeneration Alliance
ICBO	International Conference of Buildings Officials
ICC	International Code Council
ICP	Institutional Conservation Program
IECC	International Energy Conservation Code
IEEE	Institute of Electrical and Electronic Engineers
IESNA	Illuminating Engineering Society of North America
Install year	The year a building or system was built or the most recent major renovation date (where a minimum of 70 of the system's Current Replacement Value (CRV) was replaced).
IRP	Integrated Resource Planning
IRR	Internal Rate of Return
ISO	Independent System Operator
ITA	Independent Tariff Administrator
k	Kilo multiple of thousands in SI system
K	Kelvins (color temperature of lamp)
K k	Thermal Conductivity of Material
KVA	Kilovolt Ampere
KVAR	Kilovolt Ampere Reactive
kW	kiloWatt
kWh	kiloWatt hour
L	Length (usually feet)
LCC	Life Cycle Costing
LDC	Local Distribution Company
LEED	Leadership in Energy and Environmental Design
LEED EB	LEED for Existing Buildings

Site Assessment Report - S273001;Washington ES

LEED NC	LEED for new construction
LF	Load Factor
LHV	Lower Heating Value
Life cycle	The period of time that a building or site system or element can be expected to adequately serve its intended function.
LPS	Low Pressure Sodium (lamp)
Lu	Lumen Output of a Lamp or Fixture
M	Mega multiple of millions in SI system
M&V	Measurement and Verification
MACRS	Modified Accelerated Cost Recovery System
MARR	Minimum Attractive Rate of Return
Mbtu	Thousand Btu
MCF	Thousand Cubic Feet (usually of gas)
MEC	Model Energy Code
Mm	Multiple of Thousands in I/P System
MMBtu	Million Btu
MMCS	Maintenance Management Computer System
MMI	Man Machine Interface
MMS	Maintenance Management System
MSE 2000	Management System for Energy 2000 (ANSI Georgia Tech Univ)
MW	MegaWatt
MWH MWh	MegaWatt hour
NAAQS	National Ambient Air Quality Standards
NAESCO	National Association of Energy Service Companies
NAIMA	North American Insulation Manufacturers Association
NEA	National Energy Act of 1978
NECPA	National Energy Conservation Policy Act
NEMA	National Electrical Manufacturer's Association
NERC	North American Electric Reliability Council
Next Renewal	The Next Renewal date is an override of the 'Calculated Next Renewal' date and is based upon the assessor's visual inspection.

Site Assessment Report - S273001;Washington ES

NFPA	National Fire Protection Association
NGPA	National Gas Policy Act of 1978
NLRPM	No Load Revolutions per Minute (speed)
Nn	Equipment or Project lifetime in economic analysis
NOPR	Notice of Proposed Rule Making from FERC
NOx	Nitrogen Oxide Compounds
NPV	Net present value in economic analysis
NREL	National Renewable Energy Laboratory
NUG	Non-Utility Generator
O&M	Operation and Maintenance
OA	Outside Air
ODP	Ozone Depletion Potential
OPAC	Off-Peak Air Conditioning
P	Present value in economic analysis
PBR	Performance Based Rates
PEA	Preliminary Energy Audit
PF	Power Factor
PID	Proportional plus integral plus derivative (control system)
PM	Portfolio Manager in Energy Star rating system
PM	Preventive Maintenance
PoolCo	Power Pool Company or Organization
POU	Point of Use
PQ	Power Quality
PSC	Public Service Commission
PSIA psia	Pounds per square inch absolute (pressure)
PSIG psig	Pounds per square inch gauge (pressure)
PUC	Public Utility Commission
PUHCA	Public Utilities Holding Company Act of 1935
PURPA	Public Utilities Regulatory Policies of 1978
PV	Photovoltaic system

Site Assessment Report - S273001;Washington ES

PV	Present Value
PW	Present Worth
PX	Power Exchange
q	Rate of heat flow in Btu per hour
Q	Heat load due to conduction using degree days
QF	Qualifying Facility
R	Electrical resistance
R	Thermal Resistance
RC	Remote controller
RCR	Room Cavity Ratio
RCRA	Resource Conservation and Recovery Act
Remaining Service Life (RSL)	RSL is the number of years service remaining for a system or equipment item. It is automatically calculated based on the difference between the current year and the 'Calculated Next Renewal' date or the 'Next Renewal' date whichever one is the later date.
Remaining Service Life Index (RSLI)	RSLI is defined as a percentage ratio of the remaining service life of a system. It usually ranges from 0 to 100
REMR	Repair Evaluation Maintenance Rehabilitation (REMR) is a scale used to objectively rank systems based on their condition
Renewal Schedule	A timeline that provides the items that need repair the year in which the repair is needed and the estimated price of the renewal.
RH	Relative Humidity
RLA	Running Load Amps
RMS	Root Mean Square
RO	Reverse Osmosis
ROI	Return on Investment
RPM	Revolutions Per Minute
RTG	Regional Transmission Group
RTO	Regional Transmission Organization
RTP	Real Time Pricing
SBCCI	Southern Building Code Congress International
SC	Scheduling Coordinator
SC	Shading Coefficient
SCADA	Supervisory Control and Data Acquisition Systems

Site Assessment Report - S273001;Washington ES

SEER	Seasonal Energy Efficiency Ratio
SHR	Sensible Heat Ratio
Site	The grounds and utilities roadways landscaping fencing and other typical land improvements needed to support the facility.
Soft Cost	An expense item that is not considered direct construction cost. Soft cost includes architectural engineering financing legal fees and other pre-and-post construction expenses.
SOx	Sulfur Oxide Compounds
SP	Static Pressure
SP SPB	Simple Payback
SPP	Simple Payback Period
SPP	Small Power Producers
STR	Stack Temperature Rise
SV	Specific Volume
System	System refers to building and related site work elements as described by ASTM Unifomat II Classification for Building Elements (E1557-97) a format for classifying major facility elements common to most buildings. Elements usually perform a given function regardless of the design specification construction method or materials used. See also Unifomat II.
T	Temperature
T	Tubular (lamps)
TAA	Technical Assistance Audit
TCP/IP	Transmission Control Protocol/Internet Protocol
TES	Thermal Energy Storage
THD	Total Harmonic Distortion
TOD	Time of Day
TOU	Time of Use
TQM	Total Quality Management
TransCo	Transmission Company
U	Thermal Conductance
UDC	Utility Distribution Company
UL	Underwriters Laboratories
UNIFORMAT II	The ASTM UNIFORMAT II Classification for Building Elements (E1557-97) a format for classifying major facility components common to most buildings.
USGBC	US Green Building Council
v	Specific Volume

Site Assessment Report - S273001;Washington ES

V	Volts Voltage
V	Volume
VAV	Variable Air Volume
VDT	Video Display Terminal
VFD	Variable Frequency Drive
VHO	Very High Output
VSD	Variable Speed Drive
W	Watts
W	Width
WB	Wet bulb
WH Wh	Watt Hours
Year built	The year that a building or addition was originally built based on substantial completion or occupancy.
Z	Electrical Impedance