

Lead Safe Certification Assessment Report																									
Kennedy Crossan Elementary School																									
Inspection Dates: 7/22-7/24/2019						7350 Bingham St, Philadelphia, PA 19111																			
Name of Inspector: Adam Prefer																									
Inspection Company: Batta Environmental																									
E l e m e n t	F l o o r	Primary Component (see terms)	Substrate Material	Color	Description of Primary Damage (see terms)	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)	Additional Component (see terms)	Substrate Material	Color	Description of Paint and Plaster Damage (see terms)	Additional Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Additional Component XRF (positive/ negative)										
1	2	W1	Plaster	White	Chipping	1	17.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A										
1	2	W2	Plaster	White	Chipping	2	0.2	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A										
1	2	W3	Plaster	White	Chipping	1	16.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A										
1	2	W4	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A										
1	2	Ceiling	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A										
1	2	Floor	Wood	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A										
1	2	W1	Plaster	Tan	Chipping	2	7.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A										
1	2	W2	Plaster	Tan	Cracking	4	21.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A										
1	2	W2	N/A	N/A	N/A	N/A	N/A	N/A	Columns	Metal	White	Chipping	5	22.5	Positive										
1	2	W3	Plaster	Tan	Chipping	3	17.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A										
1	2	W4	Plaster	Tan	Chipping	3	-0.6	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A										
1	2	Ceiling	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A										
1	2	Floor	Wood	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A										
1	2	W1	Plaster	Tan	Chipping	2	12.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A										
1	2	W2	Plaster	Tan	Chipping	6	16.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A										
1	2	W3	Plaster	Tan	Chipping	1	23.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A										
1	2	W4	Plaster	Tan	Chipping	3	11.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A										
1	2	Ceiling	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A										
1	2	Floor	Wood	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A										
1	2	W1	Plaster	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A										
1	2	W2	Plaster	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A										
1	2	W3	Plaster	Tan	Cracking	8	23.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A										
1	2	W4	Plaster	Tan	Chipping	4	21.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A										
1	2	W1	N/A	N/A	N/A	N/A	N/A	N/A	Chalk ledge	Wood	Tan	Chipping	2	0.2	Negative										
1	2	Ceiling	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A										
1	2	Floor	Wood	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A										
1	2	W1	Plaster	Tan	Partially Inaccessible	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A										
1	2	W2	Plaster	Tan	Partially Inaccessible	2	21.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A										
1	2	W3	Plaster	Tan	Partially Inaccessible	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A										
1	2	W4	Plaster	Tan	Partially Inaccessible	2	24	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A										
1	2	Ceiling	Plaster	White	Partially Inaccessible/Cracki ng	3	16	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A										
1	2	Floor	Wood	Brown	Partially Inaccessible	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A										
1	2	W1	Wood	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A										
1	2	W2	Wood	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A										
1	2	W3	Wood	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A										
1	2	W4	Wood	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A										
1	2	Ceiling	Wood	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A										
1	2	Floor	Wood	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A										
1	2	W1	Plaster	Tan	Chipping	2	22.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A										
1	2	W2	Plaster	Tan	Moisture Damage	4	19.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A										
1	2	W3	Plaster	Tan	Cracking	3	25.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A										
1	2	W4	Plaster	Tan	Chipping	2	22.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A										

Lead Safe Certification Assessment Report																									
Kennedy Crossan Elementary School																									
Inspection Dates: 7/22-7/24/2019						7350 Bingham St, Philadelphia, PA 19111																			
Name of Inspector: Adam Prefer																									
Inspection Company: Batta Environmental																									
E l e m e n t	F l o o r	Primary Component (see terms)	Substrate Material	Color	Description of Primary Damage (see terms)	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)	Additional Component (see terms)	Substrate Material	Color	Description of Paint and Plaster Damage (see terms)	Additional Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Additional Component XRF (positive/ negative)										
1	2	W1	N/A	N/A	N/A	N/A	N/A	N/A	Chalk ledge	Wood	Tan	Chipping	3	0.1	Negative										
1	2	Ceiling	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A										
1	2	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A										
1	2	W1	Plaster	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A										
1	2	W2	Plaster	Tan	Cracking	3	17.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A										
1	2	W3	Plaster	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A										
1	2	W4	Plaster	Tan	Chipping	3	17.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A										
1	2	Ceiling	Plaster	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A										
1	2	Floor	Wood	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A										
1	2	W1	Wood	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A										
1	2	W2	Wood	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A										
1	2	W3	Wood	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A										
1	2	W4	Wood	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A										
1	2	Ceiling	Wood	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A										
1	2	Floor	Wood	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A										
1	2	W1	Plaster	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A										
1	2	W2	Plaster	Tan	Chipping	2	26.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A										
1	2	W2	N/A	N/A	N/A	N/A	N/A	N/A	Chalk ledge	Wood	Tan	Chipping	2	-0.1	Negative										
1	2	W3	Plaster	Tan	Cracking	7	31	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A										
1	2	W3	N/A	N/A	N/A	N/A	N/A	N/A	Radiator	Metal	Grey	Chipping	2	1.1	Positive										
1	2	W4	Plaster	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A										
1	2	Ceiling	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A										
1	2	Floor	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A										
1	2	W1	Plaster	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A										
1	2	W1	N/A	N/A	N/A	0	N/A	N/A	Chalk ledge	Wood	Tan	Chipping	2	0.1	Negative										
1	2	W2	Plaster	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A										
1	2	W3	Plaster	Tan	Cracking	2	25.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A										
1	2	W4	Plaster	Tan	Chipping	4	29.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A										
1	2	Ceiling	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A										
1	2	Floor	Wood	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A										
1	2	W1	Plaster	Tan	Partially Inaccessible	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A										
1	2	W2	Plaster	Tan	Partially Inaccessible	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A										
1	2	W3	Plaster	Tan	Partially Inaccessible	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A										
1	2	W4	Plaster	Tan	Partially Inaccessible	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A										
1	2	Ceiling	Plaster	White	Partially Inaccessible	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A										
1	2	Floor	Wood	Brown	Partially Inaccessible	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A										
1	2	W1	Plaster	Tan	Chipping	1	24.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A										
1	2	W1	N/A	N/A	N/A	0	N/A	N/A	Chalk ledge	Wood	Tan	Chipping	2	0.1	Negative										
1	2	W2	Plaster	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A										
1	2	W3	Plaster	Tan	Cracking	3	25	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A										
1	2	W3	N/A	N/A	N/A	0	N/A	N/A	Radiator	Metal	Grey	Chipping	2	0.2	Negative										
1	2	W4	Plaster	Tan	Cracking	3	26.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A										
1	2	Ceiling	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A										

Lead Safe Certification Assessment Report															
Kennedy Crossan Elementary School															
Inspection Dates: 7/22-7/24/2019															
Name of Inspector: Adam Prefer															
Inspection Company: Batta Environmental															
E l e m e n t	F l o o r	Primary Component (see terms)	Substrate Material	Color	Description of Primary Damage (see terms)	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)	Additional Component (see terms)	Substrate Material	Color	Description of Paint and Plaster Damage (see terms)	Additional Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Additional Component XRF (positive/ negative)
1	2	Floor	Wood	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	W1	Plaster	Tan	Partially Inaccessible	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	W2	Plaster	Tan	Partially Inaccessible/Cracki ng	2	25.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	W3	Plaster	Tan	Partially Inaccessible	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	W4	Plaster	Tan	Partially Inaccessible/Cracki ng	3	24.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Ceiling	Plaster	White	Partially Inaccessible	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Floor	Wood	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	W1	Plaster	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	W2	Plaster	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	W3	Plaster	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	W4	Plaster	Tan	Chipping	1	20.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Ceiling	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Floor	Concrete	Gray	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	W1	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	W2	Plaster	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	W3	Plaster	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	W4	Plaster	Tan	Flaking	2	26.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Ceiling	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Floor	Concrete	Gray	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	W1	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	White	Chipping	2	0.2	Negative
1	2	W2	Plaster	White	Partially Inaccessible	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	W3	Plaster	White	Partially Inaccessible	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	W4	Plaster	White	Partially Inaccessible	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Ceiling	Plaster	White	Partially Inaccessible	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Floor	Concrete	N/A	Partially Inaccessible	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	W1	Plaster	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	W2	Plaster	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	W3	Plaster	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	W4	Plaster	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Ceiling	Plaster	White	Moisture Damage	4	22	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	W1	Plaster	Tan	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	W1	N/A	N/A	N/A	N/A	N/A	N/A	Chalk ledge	Wood	Tan	Chipping	3	0.1	Negative
1	2	W2	Plaster	Tan	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	W3	Plaster	Tan	Cracking	3	27.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	W3	N/A	N/A	N/A	N/A	N/A	N/A	Radiator	Metal	Grey	Chipping	2	0.2	Negative
1	2	W4	Plaster	Tan	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A

Lead Safe Certification Assessment Report															
Kennedy Crossan Elementary School															
Inspection Dates: 7/22-7/24/2019															
Name of Inspector: Adam Prefer															
Inspection Company: Batta Environmental															
E l e m e n t	F l o o r	Primary Component (see terms)	Substrate Material	Color	Description of Primary Damage (see terms)	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)	Additional Component (see terms)	Substrate Material	Color	Description of Paint and Plaster Damage (see terms)	Additional Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Additional Component XRF (positive/ negative)
1	2	Ceiling	Plaster	White	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Floor	Wood	Brown	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	W1	Plaster	Tan	Partially Inaccessible	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	W2	Plaster	Tan	Partially Inaccessible/Cracki ng	1	1.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	W3	Plaster	Tan	Partially Inaccessible	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	W4	Plaster	Tan	Partially Inaccessible	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Ceiling	Plaster	Tan	Cracking	1	21.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Floor	Wood	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	W1	Plaster	Tan	Chipping	2	18.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	W1	Plaster	N/A	N/A	N/A	N/A	N/A	Chalk ledge	Wood	Tan	Chipping	3	0.1	Negative
1	2	W2	Plaster	Tan	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	W3	Plaster	Tan	Chipping	3	20.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	W3	N/A	N/A	N/A	N/A	N/A	N/A	Radiator	Metal	Grey	Chipping	1	0.1	Negative
1	2	W4	Plaster	Tan	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Ceiling	Plaster	Tan	Cracking	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Floor	Wood	Brown	Cracking	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	W1	Plaster	Tan	Partially Inaccessible	2	18.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	W2	Plaster	Tan	Partially Inaccessible	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	W3	Plaster	Tan	Partially Inaccessible	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	W3	N/A	N/A	N/A	N/A	N/A	N/A	Radiator	Metal	Grey	Chipping	3	7.9	Positive
1	2	W4	Plaster	Tan	Partially Inaccessible	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Ceiling	Plaster	Tan	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Floor	Wood	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	W1	Plaster	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door	Wood	Tan	Chipping	2	9.1	Positive
1	2	W2	Plaster	Tan	Cracking	2	-0.1	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	W3	Plaster	Tan	Cracking	5	33	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	W3	N/A	N/A	N/A	N/A	N/A	N/A	Columns	Metal	White	Cracking	9	28.6	Positive
1	2	W4	Plaster	Tan	Moisture Damage	14	35	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	W4	N/A	N/A	N/A	N/A	N/A	N/A	Newel posts	Wood	Grey	Chipping	5	12.4	Positive
1	2	Ceiling	Plaster	White	Moisture Damage	4	33	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Floor	Concrete	Grey	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	W1	Plaster	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door	Wood	Tan	Chipping	2	9.1	Positive
1	2	W2	Plaster	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	W2	N/A	N/A	N/A	N/A	N/A	N/A	Newel posts	Wood	Grey	Chipping	4	12.6	Positive
1	2	W3	Plaster	Tan	Cracking	1	29.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	W3	N/A	N/A	N/A	N/A	N/A	N/A	Columns	Metal	Tan	Cracking	5	9	Positive
1	2	W4	Plaster	Tan	Chipping	1	19.7	Positive	Chipping	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Ceiling	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Floor	Concrete	Gray	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A

Lead Safe Certification Assessment Report																									
Kennedy Crossan Elementary School																									
Inspection Dates: 7/22-7/24/2019						7350 Bingham St, Philadelphia, PA 19111																			
Name of Inspector: Adam Prefer																									
Inspection Company: Batta Environmental																									
E l e m e n t	F l o o r	Primary Component (see terms)	Substrate Material	Color	Description of Primary Damage (see terms)	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)	Additional Component (see terms)	Substrate Material	Color	Description of Paint and Plaster Damage (see terms)	Additional Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Additional Component XRF (positive/ negative)										
1	2	W1	Brick	Tan	Cracking	25	14	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A										
1	2	W2	Concrete	Tan	Cracking	5	0.1	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A										
1	2	W2	N/A	N/A	N/A	N/A	N/A	N/A	Window sill	Concrete	Grey	Cracking	4	0.5	Negative										
1	2	W2	N/A	N/A	N/A	N/A	N/A	N/A	Fire Tower grates	Metal	Grey	Cracking	4	20.8	Positive										
1	2	W2	N/A	N/A	N/A	N/A	N/A	N/A	Window frame	Concrete	Grey	Chipping	3	0.2	Negative										
1	2	W3	Concrete		Cracking	6	0.2	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A										
1	2	W3	N/A	N/A	N/A	N/A	N/A	N/A	Columns	Metal	Tan	Chipping	8	18.2	Positive										
1	2	W3	N/A	N/A	N/A	N/A	N/A	N/A	Window sill	Concrete	Grey	Cracking	6	18.9	Positive										
1	2	W3	N/A	N/A	N/A	N/A	N/A	N/A	Fire Tower grates	Metal	Grey	Cracking	2	17.8	Positive										
1	2	W4	Brick	Tan	Cracking	40	21.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A										
1	2	W4	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	Grey	Flaking	4	5.5	Positive										
1	2	W4	N/A	N/A	N/A	N/A	N/A	N/A	Door	Metal	Grey	Chipping	4	0.2	Negative										
1	2	Ceiling	Concrete	Tan	Chipping	50	38	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A										
1	2	Floor	Concrete	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A										
1	1	W1	Plaster	Tan	Chipping	1	34	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A										
1	1	W2	Plaster	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A										
1	1	W3	Plaster	Tan	Chipping	2	22.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A										
1	1	W4	Plaster	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A										
1	1	W4	N/A	N/A	N/A	N/A	N/A	N/A	Chalk ledge	Wood	Tan	Chipping	1	0.1	Negative										
1	1	Ceiling	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A										
1	1	Floor	Wood	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A										
1	2	W1	Plaster	Tan	Partially Inaccessible/Cracki ng	2	22.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A										
1	2	W2	Plaster	Tan	Partially Inaccessible	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A										
1	2	W3	Plaster	Tan	Partially Inaccessible	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A										
1	2	W4	Plaster	Tan	Partially Inaccessible	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A										
1	2	Ceiling	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A										
1	2	Floor	Wood	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A										
1	1	W1	Plaster	Tan	Chipping	5	17.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A										
1	1	W1	N/A	N/A	N/A	N/A	N/A	N/A	Chalk ledge	Wood	Tan	Chipping	1	0.2	Negative										
1	1	W2	Plaster	Tan	Chipping	2	27.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A										
1	1	W3	Plaster	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A										
1	1	W4	Plaster	Tan	Chipping	4	17.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A										
1	1	Ceiling	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A										
1	1	Floor	Wood	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A										
1	1	W1	Plaster	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A										
1	1	W2	Plaster	Tan	Cracking	2	19.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A										
1	1	W2	N/A	N/A	N/A	N/A	N/A	N/A	Columns	Metal	Grey	Chipping	2	21.5	Positive										
1	1	W3	Plaster	Tan	Cracking	4	-0.1	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A										
1	1	W4	Plaster	Tan	Moisture Damage	4	0.1	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A										
1	1	Ceiling	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A										
1	1	Floor	Wood	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A										
1	2	W1	Plaster	Tan	Cracking	1	23.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A										
1	2	W2	Plaster	Tan	Cracking	4	12.3	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A										
1	2	W3	Plaster	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A										

Lead Safe Certification Assessment Report																								
Kennedy Crossan Elementary School																								
Inspection Dates: 7/22-7/24/2019					7350 Bingham St, Philadelphia, PA 19111																			
Name of Inspector: Adam Prefer																								
Inspection Company: Batta Environmental																								
E l e m e n t	F l o o r	Primary Component (see terms)	Substrate Material	Color	Description of Primary Damage (see terms)	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)	Additional Component (see terms)	Substrate Material	Color	Description of Paint and Plaster Damage (see terms)	Additional Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Additional Component XRF (positive/ negative)									
1	2	W4	Plaster	Tan	Cracking	8	13	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A									
1	2	Ceiling	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A									
1	2	Floor	Wood	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A									
1	1	W1	Plaster	Tan	Cracking	5	19.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A									
1	1	W2	Plaster	Tan	Cracking	9	22.3	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A									
1	1	W2	N/A	N/A	N/A	N/A	N/A	N/A	Columns	Metal	White	Chipping	5	5.5	Positive									
1	1	W3	Plaster	Tan	Cracking	8	14	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A									
1	1	W4	Plaster	Tan	Partially Inaccessible	8	20	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A									
1	1	Ceiling	Plaster	White	Cracking	7	31	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A									
1	1	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A									
1	1	W1	Plaster	Tan	Chipping	1	25.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A									
1	1	W1	N/A	N/A	N/A	N/A	N/A	N/A	Chalk ledge	Wood	Tan	Chipping	3	0.2	Negative									
1	1	W2	Plaster	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A									
1	1	W3	Plaster	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A									
1	1	W4	Plaster	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A									
1	1	Ceiling	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A									
1	1	Floor	Wood	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A									
1	2	W1	Plaster	Tan	Partially Inaccessible	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A									
1	2	W2	Plaster	Tan	Partially Inaccessible	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A									
1	2	W3	Plaster	Tan	Partially Inaccessible	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A									
1	1	W4	Plaster	Tan	Partially Inaccessible	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A									
1	2	Ceiling	Plaster	White	Partially Inaccessible/Chipp ing	2	16.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A									
1	1	Floor	Wood	Brown	Partially Inaccessible	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A									
1	1	W1	Plaster	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A									
1	1	W2	Plaster	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A									
1	1	W3	Plaster	Tan	Cracking	3	24.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A									
1	1	W4	Plaster	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A									
1	1	Ceiling	Plaster	White	Chipping	15	21.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A									
1	1	Floor	Wood	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A									
1	1	W1	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A									
1	1	W2	Plaster	White	Partially Inaccessible	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A									
1	1	W3	Plaster	White	Partially Inaccessible	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A									
1	1	W4	Plaster	White	Partially Inaccessible	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A									
1	1	Ceiling	Plaster	White	Partially Inaccessible	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A									
1	1	Floor	Wood	Brown	Partially Inaccessible	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A									
1	1	W1	Plaster	Orange	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A									
1	1	W2	Plaster	Orange	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A									

Lead Safe Certification Assessment Report															
Kennedy Crossan Elementary School															
Inspection Dates: 7/22-7/24/2019															
Name of Inspector: Adam Prefer															
Inspection Company: Batta Environmental															
E l e m e n t	F l o o r	Primary Component (see terms)	Substrate Material	Color	Description of Primary Damage (see terms)	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)	Additional Component (see terms)	Substrate Material	Color	Description of Paint and Plaster Damage (see terms)	Additional Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Additional Component XRF (positive/ negative)
1	1	W3	Plaster	Orange	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	W4	Plaster	Orange	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Ceiling	Plaster	White	Cracking	2	30	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Floor	Wood	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	W1	Plaster	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	W2	Plaster	Tan	Chipping	1	-0.2	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	W3	Plaster	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	W4	Plaster	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Ceiling	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	W1	Plaster	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	W2	Plaster	Tan	Chipping	3	19.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	W3	Plaster	Tan	Chipping	4	21.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	W4	Plaster	Tan	Chipping	6	27	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Ceiling	Plaster	White	Chipping	8	22.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Floor	Wood	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	W1	Plaster	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	W2	Plaster	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	W3	Plaster	Tan	Cracking	4	33	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	W4	Plaster	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Ceiling	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Floor	Concrete	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	W1	Plaster	White	Cracking	2	11.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	W2	Plaster	White	Chipping	4	10.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	W3	Plaster	White	Chipping	2	-0.1	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	W4	Plaster	White	Cracking	3	8.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Ceiling	Plaster	Tan	Moisture Damage	28	9.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Floor	Wood	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	W1	Plaster	White	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Wood	White	Chipping	2	9.9	Positive
1	1	W2	Plaster	White	Cracking	24	24.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	W3	Plaster	White	Cracking	100	24.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	W4	Plaster	White	Cracking	12	26.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Ceiling	Plaster	Tan		12	22.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Floor	Wood	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	W1	Plaster	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	W2	Plaster	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	W3	Plaster	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	W4	Plaster	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Ceiling	Plaster	Tan	Cracking	1	19.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Floor	Wood	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	W1	Plaster	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	W2	Plaster	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	W3	Plaster	Tan	Cracking	3	18.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	W3	N/A	N/A	N/A	N/A	N/A	N/A	Radiator	Metal	Brown	Chipping	2	20.6	Positive
1	1	W4	Plaster	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Ceiling	Wood	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Floor	Wood	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A

Lead Safe Certification Assessment Report																								
Kennedy Crossan Elementary School																								
Inspection Dates: 7/22-7/24/2019					7350 Bingham St, Philadelphia, PA 19111																			
Name of Inspector: Adam Prefer																								
Inspection Company: Batta Environmental																								
E l e m e n t	F l o o r	Primary Component (see terms)	Substrate Material	Color	Description of Primary Damage (see terms)	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)	Additional Component (see terms)	Substrate Material	Color	Description of Paint and Plaster Damage (see terms)	Additional Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Additional Component XRF (positive/ negative)									
1	1	W1	Plaster	Tan	Cracking	2	15.3	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A									
1	1	W2	Plaster	Tan	Cracking	5	23	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A									
1	1	W3	Plaster	Tan	Cracking	3	20.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A									
1	1	W4	Plaster	Tan	Moisture Damage	8	0.5	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A									
1	1	Ceiling	Plaster	Tan	Chipping	1	0.6	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A									
1	1	Floor	Wood	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A									
1	1	W1	Plaster	Tan	None	8	22.3	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A									
1	1	W2	Plaster	Tan	Cracking	18	0.1	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A									
1	1	W3	Plaster	Tan	Moisture Damage	32	23.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A									
1	1	W4	Plaster	Tan	Cracking	20	1.3	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A									
1	1	Ceiling	Plaster	Tan	Chipping	4	20.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A									
1	1	Floor	Wood	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A									
1	1	W1	Plaster	Tan	Cracking	15	22.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A									
1	1	W1	N/A	N/A	N/A	N/A	N/A	N/A	Chalk ledge	Wood	Tan	Chipping	2	0.2	Negative									
1	1	W2	Plaster	Tan	Cracking	57	21.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A									
1	1	W3	Plaster	Tan	Chipping	4	27	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A									
1	1	W4	Plaster	Tan	Chipping	2	25.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A									
1	1	Ceiling	Plaster	White	Chipping	25	18.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A									
1	1	Floor	Wood	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A									
1	2	W1	Plaster	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A									
1	2	W2	Plaster	Tan	Chipping	5	22.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A									
1	2	W3	Plaster	Tan	Partially Inaccessible/Cracki ng	4	19.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A									
1	2	W4	Plaster	Tan	Cracking	5	22.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A									
1	2	Ceiling	Plaster	White	Chipping	12	15.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A									
1	2	Floor	Wood	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A									
1	1	W1	Plaster	Tan	Chipping	2	22.3	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A									
1	1	W1	N/A	N/A	N/A	N/A	N/A	N/A	Chalk ledge	Wood	Tan	Chipping	2	0.1	Negative									
1	1	W2	Plaster	Tan	Cracking	1	20	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A									
1	1	W3	Plaster	Tan	Chipping	6	24.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A									
1	1	W4	Plaster	Tan	Chipping	4	29.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A									
1	1	Ceiling	Plaster	White	Chipping	2	19.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A									
1	1	Floor	Wood	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A									
1	2	W1	Plaster	Tan	Partially Inaccessible	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A									
1	2	W2	Plaster	Tan	Partially Inaccessible/Chipp ing	5	19.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A									
1	2	W3	Plaster	Tan	Partially Inaccessible	2	18.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A									
1	2	W3	N/A	N/A	N/A	N/A	N/A	N/A	Columns	Metal	White	Chipping	1	15.8	Positive									
1	2	W4	Plaster	Tan	Partially Inaccessible	2	19	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A									
1	2	Ceiling	Plaster	White	Chipping	4	13.3	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A									
1	2	Floor	Wood	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A									
1	1	W1	Plaster	White	Cracking	3	23.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A									
1	1	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Wood	Tan	Chipping	4	20	Positive									
1	1	W1	N/A	N/A	N/A	N/A	N/A	N/A	Baseboard	Wood	Tan	Chipping	3	21.7	Positive									

Lead Safe Certification Assessment Report																								
Kennedy Crossan Elementary School																								
Inspection Dates: 7/22-7/24/2019					7350 Bingham St, Philadelphia, PA 19111																			
Name of Inspector: Adam Prefer																								
Inspection Company: Batta Environmental																								
E l e m e n t	F l o o r	Primary Component (see terms)	Substrate Material	Color	Description of Primary Damage (see terms)	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)	Additional Component (see terms)	Substrate Material	Color	Description of Paint and Plaster Damage (see terms)	Additional Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Additional Component XRF (positive/ negative)									
1	1	W2	Plaster	White	Chipping	6	30	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A									
1	1	W3	Plaster	White	Cracking	6	27.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A									
1	1	W3	N/A	N/A	N/A	N/A	N/A	N/A	Window frame	Wood	Tan	Chipping	2	14.8	Positive									
1	1	W4	Plaster	White	Cracking	3	37	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A									
1	1	W4	N/A	N/A	N/A	N/A	N/A	N/A	Built-in cabinet	Wood	Tan	Chipping	4	16.4	Positive									
1	1	Ceiling	Plaster	White	Cracking	5	27.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A									
1	1	Floor	Wood	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A									
1	2	W1	Plaster	White	Cracking	3	19	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A									
1	2	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door	Wood	Tan	Chipping	1	16.4	Positive									
1	2	W2	Plaster	White	Cracking	5	22	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A									
1	2	W2	N/A	N/A	N/A	N/A	N/A	N/A	Window frame	Wood	Tan	Chipping	1	6.5	Positive									
1	2	W2	N/A	N/A	N/A	N/A	N/A	N/A	Columns	Metal	Tan	Cracking	1	0.1	Negative									
1	2	W3	Plaster	White	Cracking	3	25.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A									
1	2	W4	Plaster	White	Chipping	6	32	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A									
1	2	Ceiling	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A									
1	2	Floor	Wood	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A									
1	1	W1	Plaster	Tan	Chipping	2	14.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A									
1	1	W2	Plaster	Tan	Cracking	10	15.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A									
1	1	W3	Plaster	Tan	Cracking	8	13.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A									
1	1	W3	N/A	N/A	N/A	N/A	N/A	N/A	Columns	Metal	Grey	Chipping	5	10.9	Positive									
1	1	W4	Plaster	Tan	Chipping	16	7.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A									
1	1	W4	N/A	N/A	N/A	N/A	N/A	N/A	Chalk ledge	Wood	Tan	Chipping	1	0.2	Positive									
1	1	Ceiling	Plaster	White	Cracking	12	23.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A									
1	1	Floor	Wood	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A									
1	1	W1	Plaster	Tan	Cracking	3	16.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A									
1	1	W2	Plaster	Tan	Cracking	3	16.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A									
1	1	W3	Plaster	Tan	Moisture Damage	9	-0.1	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A									
1	1	W4	Plaster	Tan	Cracking	1	13.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A									
1	1	W4	N/A	N/A	N/A	N/A	N/A	N/A	Columns	Metal	Grey	Chipping	4	7.5	Positive									
1	1	Ceiling	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A									
1	1	Floor	Concrete	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A									
1	2	W1	Plaster	Tan	Cracking	1	21.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A									
1	2	W2	Plaster	Tan	Partially Inaccessible	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A									
1	2	W3	Plaster	Tan	Partially Inaccessible	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A									
1	2	W4	Plaster	Tan	Partially Inaccessible/Chipp ing	1	15.3	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A									
1	2	Ceiling	Plaster	White	Cracking	3	21	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A									
1	2	Floor	Wood	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A									
2	1	W1	Plaster	Blue	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A									
2	1	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door	Metal	Grey	Chipping	3	0.1	Negative									
2	1	W2	Plaster	Blue	Chipping	4	0.3	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A									
2	1	W3	Plaster	Blue	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A									
2	1	W3	N/A	N/A	N/A	N/A	N/A	N/A	Door	Metal	Grey	Chipping	3	0	Negative									
2	1	W4	Plaster	Blue	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A									
2	1	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A									
2	1	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A									

Lead Safe Certification Assessment Report															
Kennedy Crossan Elementary School															
Inspection Dates: 7/22-7/24/2019															
Name of Inspector: Adam Prefer															
Inspection Company: Batta Environmental															
E l e m e n t	F l o o r	Primary Component (see terms)	Substrate Material	Color	Description of Primary Damage (see terms)	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)	Additional Component (see terms)	Substrate Material	Color	Description of Paint and Plaster Damage (see terms)	Additional Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Additional Component XRF (positive/ negative)
2	1	W1	Plaster	Blue	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	W2	Plaster	Blue	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	W3	Plaster	Blue	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	W4	Plaster	Blue	Chipping	1	0.2	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Ceiling	Plaster	White	Moisture Damage	3	0.1	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	W1	Plaster	Green	Cracking	1	0.1	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	W2	Plaster	Green	Chipping	3	0.2	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	W2	N/A	N/A	N/A	N/A	N/A	N/A	Columns	Metal	White	Chipping	3	0.3	Negative
2	1	W3	Plaster	Green	Chipping	2	0.3	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	W4	Plaster	Green	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Ceiling	Plaster	White	Cracking	3	0.1	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	W1	Plaster	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door	Wood	Tan	Friction	1	3.5	Positive
1	1	W2	Plaster	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	W2	N/A	N/A	N/A	N/A	N/A	N/A	Newel posts	Wood	Grey	Chipping	8	9.7	Positive
1	1	W3	Plaster	Tan	Cracking	1	18.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	W4	Plaster	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Ceiling	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Floor	Concrete	Grey	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	W1	Plaster	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door	Wood	Tan	Friction	1	7.1	Positive
1	1	W2	Plaster	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	W3	Plaster	Tan	Cracking	1	19.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	W3	N/A	N/A	N/A	N/A	N/A	N/A	Newel posts	Wood	Grey	Chipping	5	12.2	Positive
1	1	W3	N/A	N/A	N/A	N/A	N/A	N/A	Columns	Metal	Tan	Cracking	4	4.8	Positive
1	1	W4	Plaster	Tan	Cracking	2	19.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Ceiling	Plaster	White	Cracking	8	21.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Floor	Concrete	Grey	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	W1	Plaster	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	W2	Plaster	Tan	Cracking	3	20.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	W3	Plaster	Tan	Cracking	2	18.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	W4	Plaster	Tan	Cracking	4	21.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	W4	N/A	N/A	N/A	N/A	N/A	N/A	Columns	Metal	Tan	Chipping	3	3.4	Positive
1	1	Ceiling	Plaster	White	Moisture Damage	4	23.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Floor	Concrete	Grey	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	W1	Brick	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door	Wood	Tan	Chipping	1	-0.1	Negative
1	B	W2	Concrete	White	Cracking	20	27	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	W3	Brick	White	Cracking	4	20.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	W4	Brick	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	W4	N/A	N/A	N/A	N/A	N/A	N/A	Radiator	Metal	White	Chipping	4	12.8	Positive
1	B	Ceiling	Concrete	White	Moisture Damage	8	16.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	W1	Brick	White	Chipping	2	27.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	W2	Brick	White	Chipping	5	7.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	W3	Brick	White	Cracking	30	8.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A

Lead Safe Certification Assessment Report																									
Kennedy Crossan Elementary School																									
Inspection Dates: 7/22-7/24/2019						7350 Bingham St, Philadelphia, PA 19111																			
Name of Inspector: Adam Prefer																									
Inspection Company: Batta Environmental																									
E l e m e n t	F l o o r	Primary Component (see terms)	Substrate Material	Color	Description of Primary Damage (see terms)	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)	Additional Component (see terms)	Substrate Material	Color	Description of Paint and Plaster Damage (see terms)	Additional Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Additional Component XRF (positive/ negative)										
1	B	W4	Brick	White	Cracking	4	15.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A										
1	B	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A										
1	B	Floor	Concrete	Grey	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A										
1	B	W1	Brick	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A										
1	B	W2	Brick	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A										
1	B	W3	Brick	White	Chipping	14	15.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A										
1	B	W3	N/A	N/A	N/A	N/A	N/A	N/A	Window sill	Brick	White	Chipping	3	0	Negative										
1	B	W4	Brick	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A										
1	B	W4	N/A	N/A	N/A	N/A	N/A	N/A	Columns	Metal	Grey	Chipping	4	7.3	Positive										
1	B	Ceiling	Concrete	White	Chipping	6	16.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A										
1	B	Floor	Concrete	Grey	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A										
1	B	W1	Plaster	Yellow	Chipping	7	17.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A										
1	B	W2	Plaster	Yellow	Chipping	2	23	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A										
1	B	W3	Plaster	Yellow	Chipping	2	25.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A										
1	B	W3	N/A	N/A	N/A	N/A	N/A	N/A	Window frame	Wood	Brown	Chipping	3	0	Negative										
1	B	W4	Plaster	Yellow	Chipping	2	0.1	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A										
1	B	Ceiling	Plaster	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A										
1	B	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A										
1	B	W1	Plaster	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A										
1	B	W2	Plaster	Yellow	Chipping	7	19	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A										
1	B	W2	N/A	N/A	N/A	N/A	N/A	N/A	Columns	Metal	Yellow	Chipping	7	0.3	Negative										
1	B	W3	Plaster	Yellow	Moisture Damage	10	17.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A										
1	B	W3	N/A	N/A	N/A	N/A	N/A	N/A	Columns	Metal	Yellow	Chipping	2	12.9	Positive										
1	B	W4	Plaster	Yellow	Moisture Damage	3	19.3	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A										
1	B	Ceiling	Plaster	Yellow	Cracking	4	19.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A										
1	B	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A										
1	B	W1	Plaster	Tan	Chipping	6	17.3	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A										
1	B	W2	Plaster	Tan	Chipping	8	19.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A										
1	B	W3	Plaster	Tan	Chipping	4	17	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A										
1	B	W3	N/A	N/A	N/A	N/A	N/A	N/A	Columns	Metal	Grey	Chipping	6	10.5	Positive										
1	B	W4	Plaster	Tan	Chipping	2	17.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A										
1	B	W4	N/A	N/A	N/A	N/A	N/A	N/A	Built-in cabinet	Wood	Yellow	Chipping	2	10.8	Positive										
1	B	Ceiling	Plaster	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A										
1	B	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A										
1	B	W1	Brick	Grey	Chipping	130	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A										
1	B	W2	Brick	Grey	Chipping	15	0.1	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A										
1	B	W3	Concrete	Grey	Chipping	90	0.4	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A										
1	B	W4	Brick	Grey	Chipping	41	0.2	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A										
1	B	Ceiling	Concrete	White	Flaking	15	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A										
1	B	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	Columns	Metal	White	Flaking	25	0.1	Negative										
1	B	Floor	Concrete	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A										
1	B	W1	Brick	Grey	Flaking	15	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A										
1	B	W2	Brick	White	Chipping	6	0.1	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A										
1	B	W3	Concrete	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A										
1	B	W3	Concrete	N/A	N/A	N/A	N/A	N/A	Stair riser	Concrete	Grey	Chipping	8	0.2	Negative										
1	B	W4	Concrete	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A										
1	B	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A										
1	B	Floor	Concrete	N/A	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A										

Lead Safe Certification Assessment Report																									
Kennedy Crossan Elementary School																									
Inspection Dates: 7/22-7/24/2019						7350 Bingham St, Philadelphia, PA 19111																			
Name of Inspector: Adam Prefer																									
Inspection Company: Batta Environmental																									
E l e m e n t	F l o o r	Primary Component (see terms)	Substrate Material	Color	Description of Primary Damage (see terms)	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)	Additional Component (see terms)	Substrate Material	Color	Description of Paint and Plaster Damage (see terms)	Additional Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Additional Component XRF (positive/ negative)										
1	B	W1	Brick	Grey	Chipping	4	-0.1	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A										
1	B	W2	Brick	N/A	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A										
1	B	W3	Concrete	N/A	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A										
1	B	W4	Brick	Grey	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A										
1	B	Ceiling	Concrete	White	Chipping	40	0.3	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A										
1	B	Floor	Concrete	N/A	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A										
1	B	W1	Brick	Grey	Chipping	28	0.3	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A										
1	B	W1	N/A	N/A	N/A	N/A	N/A	N/A	Uni-vent	Metal	Grey	Flaking	140	18.5	Positive										
1	B	W2	Concrete	Grey	Chipping	15	0.2	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A										
1	B	W3	Concrete	Grey	Moisture Damage	40	0.1	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A										
1	B	W4	Brick	Grey	Chipping	30	1.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A										
1	B	Ceiling	Concrete	White	Chipping	20	0.2	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A										
1	B	Floor	Concrete	N/A	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A										
1	B	W1	Brick	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A										
1	B	W2	Brick	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A										
1	B	W2	N/A	N/A	N/A	N/A	N/A	N/A	Columns	Metal	White	Chipping	4	7.4	Positive										
1	B	W3	Brick	White	Flaking	2	13	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A										
1	B	W4	Brick	White	Cracking	5	3.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A										
1	B	Ceiling	Plaster	White	Moisture Damage	3	8.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A										
1	B	Floor	Concrete	Black	Friction	10	0.3	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A										
1	B	W1	Brick	Tan	Chipping	3	8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A										
1	B	W2	Brick	Tan	Chipping	3	9.3	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A										
1	B	W3	Brick	Tan	Partially Inaccessible/Chipp ing	2	10.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A										
1	B	W4	Brick	Tan	Partially Inaccessible	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A										
1	B	Ceiling	Concrete	White	Flaking	15	0.1	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A										
1	B	Floor	Concrete	N/A	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A										
1	B	W1	Brick	Tan	Cracking	4	9.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A										
1	B	W2	Brick	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A										
1	B	W3	Brick	Tan	Partially Inaccessible/Cracki ng	3	8.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A										
1	B	W4	Brick	Tan	Partially Inaccessible/Chipp ing	4	10.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A										
1	B	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A										
1	B	Floor	Concrete	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A										
1	B	W1	Brick	Tan	None	15	10.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A										
1	B	W2	Brick	Tan	Chipping	16	9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A										
1	B	W3	Brick	Tan	Chipping	5	12.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A										
1	B	W4	Brick	Tan	Chipping	5	11	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A										
1	B	Ceiling	Concrete	White	Moisture Damage	22	30.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A										
1	B	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A										
1	B	W1	Brick	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A										
1	B	W1	N/A	N/A	N/A	N/A	N/A	N/A	Stair tread	Metal	Grey	Friction	5	1	Positive										
1	B	W2	Brick	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A										
1	B	W2	N/A	N/A	N/A	N/A	N/A	N/A	Hand rails	Metal	Grey	Friction	2	3.5	Positive										

						Lead Safe Certification Assessment Report										
						Kennedy Crossan Elementary School										
Inspection Dates: 7/22-7/24/2019						7350 Bingham St, Philadelphia, PA 19111										
Name of Inspector: Adam Prefer																
Inspection Company: Batta Environmental																
E l e m e n t	F l o o r	Primary Component (see terms)	Substrate Material	Color	Description of Primary Damage (see terms)	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)	Additional Component (see terms)	Substrate Material	Color	Description of Paint and Plaster Damage (see terms)	Additional Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Additional Component XRF (positive/ negative)	
1	B	W3	Brick	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	B	W4	Brick	Tan	Chipping	7	8.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	B	W4	N/A	N/A	N/A	N/A	N/A	N/A	Door	Wood	Tan	Friction	1	5.9	Positive	
1	B	Ceiling	Concrete	White	Flaking	15	0.3	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	B	Floor	Concrete	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	B	W1	Plaster	Tan	Chipping	6	17.3	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	B	W2	Plaster	Tan	Chipping	1	14	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	B	W2	N/A	N/A	N/A	N/A	N/A	N/A	Door	Wood	Tan	Friction	2	6.5	Positive	
1	B	W2			N/A	N/A	N/A	N/A	Newel posts	Wood	Grey	Chipping	5	10.1	Positive	
1	B	W3	Plaster	Tan	Chipping	2	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	B	W4	Plaster	Tan	Cracking	1	26.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	B	Ceiling	Plaster	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	B	Floor	Concrete	Gray	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	B	W1	Plaster	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	B	W2	Plaster	Tan	Chipping	5	0.4	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	B	W2			N/A	N/A	N/A	N/A	Stair riser	Wood	Brown	Chipping	4	15	Positive	
1	B	W3	Plaster	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	B	W4	Plaster	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	B	W4			N/A	N/A	N/A	N/A	Newel posts	Wood	Grey	Chipping	4	14.2	Positive	
1	B	W4	N/A	N/A	N/A	N/A	N/A	N/A	Door	Wood	Tan	Friction	2	4.7	Positive	
1	B	Ceiling	Plaster	Tan	Chipping	2	16.3	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	B	Floor	Concrete	Grey	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	