

**Hopkinson Elementary School**

4001 L Street
Philadelphia, Pennsylvania

Paint and Plaster Stabilization Project Final Report**DECEMBER 3, 2020****PREPARED FOR:**

School District of Philadelphia
440 North Broad Street, Room 3053
Philadelphia, Pennsylvania
Attention: Mr. Edward Escobio

CONTROL NUMBER:

2018255009

WORK ORDER NUMBER:

1709065

PREPARED BY:

The Vertex Companies, Inc.
700 Turner Industrial Way
Aston, Pennsylvania 19014
PHONE 610.558.8902

VERTEX Project No: 62843

TABLE OF CONTENTS

- I. Introduction
- II. Methods Executive Summary
 - A. Preliminary Steps
 - i. Parent and Staff Notifications
 - ii. Decluttering
 - iii. Wall Hangings
 - iv. Swing Space
 - v. Facilities Building Cleaning Staff Training
 - B. Pre-Cleaning
 - C. Paint and Plaster Stabilization Procedures
 - i. Work Practices
 - ii. Oversight
 - D. Cleanup and Completion of Stabilization Work
 - i. Cleanup
 - ii. Testing
- III. Oversight
 - A. Scope of Work
 - B. EPA Checklist
 - C. Oversight
 - D. Sample Results

Appendix A. Scope of Work Table

Appendix B. EPA Checklist Table

Appendix C. Oversight Table

Appendix D. FAAS Sample Results

Appendix E. Photo Log

Appendix F. Environmental Firm Certifications

Appendix G. Paint Contractor Certifications

Appendix H. Documentation of Parent and Staff Notifications

I. Introduction

The School District of Philadelphia developed a Paint and Plaster Stabilization Project Plan and Procedures jointly with the District's Office of Environmental Management and Services (OEMS) and the Philadelphia Federation of Teacher's Health and Welfare Fund and Union's Director of Environmental Science and Occupational Safety and Health. The purpose of this work is to minimize the risk of children's exposure to lead-based paint while at school. Designated schools were inspected on a room-by-room basis to develop a Scope of Work for each school.

The Vertex Companies, Inc. (VERTEX) was contracted by OEMS to perform oversight and clearance testing during the paint and plaster stabilization project that was conducted at the Hopkinson Elementary School located at 4001 L Street in Philadelphia, PA. The project began on March 4, 2020 and was completed on July 8, 2020. Workers certified under the US Environmental Protection Agency (EPA) Lead Renovation, Repair, and Painting Rule (RRP) performed the removal of loose, peeling, flaking, and damaged paint and plaster as delineated in the Scope of Work. This work was overseen by a VERTEX certified environmental technician who verified workers were following RRP rules/procedures. The environmental technician also performed lead in dust wipe sampling in areas designated by the stabilization plan.

II. Methods Executive Summary

A. Preliminary Steps

i. Parent and Staff Notifications

An initial communication titled **Notice of Building Improvement Project: Paint and Plaster Stabilization**, along with a Questions and Answers sheet was mailed to staff and parents several weeks prior to the commencement of work. Parents of children in grades Pre-K to First Grade also received the EPA Lead RRP pamphlet in this mailing. Additionally, prior to the start of the project, parent and staff meetings were held by OEMS, Maintenance, and Operations to explain the process of the paint and plaster projects and to field any questions or concerns.

ii. Decluttering

Classrooms, closets, and other storage areas were decluttered prior to the commencement of the stabilization work. Coordination of decluttering activities was made between teachers and facilities staff to ensure that outdated and unneeded materials were discarded. Facilities staff assisted teachers in moving large and heavy materials to waste dumpsters.

iii. Wall Hangings

Posters, bulletin boards, framed art, and any other wall hangings present in the work areas were removed prior to the commencement of paint and plaster stabilization activities. This was coordinated with teachers by the Operations Division at the kick-off meeting, and during the phasing of the project, with the help of the Principal. Teachers were instructed to use bulletin boards or mounting putty to hang materials in the future. The use of staples or any kind of adhesive tape to hang materials moving forward is no longer permitted.

iv. Swing Space

Swing space was identified prior to the commencement of the stabilization work to ensure that classrooms were available during the school year. A plan was created on a school-by-school basis to relocate students and teachers from classrooms during the course of this work. Each work area was scheduled for cleaning by facilities staff after the paint stabilization work was completed by the painting contractor.

v. Facilities Building Cleaning Staff Training

Cleaning staff were provided with information about this project and expectations for post-cleaning. Post-cleaning activities included High Efficiency Particulate Air (HEPA) vacuuming and wet wiping all horizontal surfaces and polishing floors.

B. Pre-Cleaning

District Maintenance Environmental Staff performed HEPA vacuuming and wet wiping in areas that had significant paint chips or plaster debris on stored materials that needed to be moved prior to stabilization.

C. Paint and Plaster Stabilization Procedures

i. Work Practices

Prior to the commencement of the paint and plaster stabilization activities, facilities staff moved stored materials and furniture in each space into either the center of the room or into the hallway. Any remaining objects in each space were covered with plastic. All windows, non-entrance doors, and HVAC system openings were also sealed with plastic. The entrance to the space was covered with plastic sheeting and a plastic flap and had a lead warning sign attached as per EPA Lead RRP. A tacky walk-off pad was placed outside the entrance to limit the spread of dust from the work area. Any visible paint chips and dust were promptly HEPA vacuumed. Plastic floor coverings extended six-feet out from the vertical surfaces being stabilized, where physically possible.

All workers performing paint and plaster stabilization were certified as Lead RRP workers. Workers wore disposable clothing, foot coverings, and applicable respiratory protection inside each work area when performing paint and plaster stabilization. Stabilization work was performed in compliance with the EPA Lead RRP rules and guidelines. When stabilization work was completed, paint chips and debris were misted and folded up inside plastic floor coverings and disposed of in heavy duty plastic waste bags. Waste bags were tied with a “gooseneck” knot and sealed with tape. Waste was disposed of off-site as construction debris.

ii. Oversight

An environmental technician was on-site each day that any prep-work, stabilization, or painting was performed by the contractor. The overall responsibility of the technician was to ensure compliance with lead safe work practices. The technician maintained an oversight spreadsheet with the date each space was pre-cleaned, the contents were moved, the space was prepped, and the surfaces were stabilized. The technician also collected colorimetric wipes and flame atomic absorption spectrophotometry (FAAS) wipes where necessary and recorded the number of RRP wipes, colorimetric wipes, and the results of any wipes submitted for FAAS on this spreadsheet. RRP wipes collected by the painting contractor were verified as clean or passing by the technician.

In addition, the technician also completed an EPA Checklist spreadsheet. This spreadsheet confirmed that for each work area that lead warning signs were posted at the entrance, the work area was contained to prevent the spread of dust and debris, all objects in the work area were removed or covered with plastic sheeting, HVAC ducts were closed and covered, windows were closed, doors were closed and sealed, doors that must be used for passage were covered to prevent the spread of dust, floors were covered with taped down plastic, waste was contained on-site and while being transported off site, work areas were properly cleaned after renovation, all chips and debris were picked up, protective sheeting misted, folded dirty side inward, and taped for removal, light lenses were inspected, surfaces above light fixtures were inspected, and that surfaces were HEPA vacuumed or wiped with wet cloths.

D. Cleanup and Completion of Stabilization Work

The following cleanup and completion procedures were performed for each work area after the completion of the stabilization work:

i. Cleanup

Cleanup began once the contractor and environmental technician agreed that there were no signs of loose, peeling, flaking, bubbling, or crumbling paint or plaster on walls, ceilings, or any other painted surfaces. The protective sheeting was misted,

folded dirty side inward, taped, and bagged in heavy duty trash bags. Workers used HEPA vacuums and wet cloths to clean floors, windowsills, and any other horizontal surfaces. The environmental technician then performed a visual inspection to ensure there were no visible signs of paint chips, debris, or dust of any kind on surfaces in the work area or outside the contained and isolated work area.

ii. Testing

Testing performed in each work area was a combination of EPA RRP cleaning verification wipes, Colorimetric Wipe SKC, Inc. Full Disclosure Instant Wipes for instant detection of lead in dust, and laboratory analysis via flame atomic absorption spectrophotometry. Laboratory analysis was performed by EMSL Analytical, Inc. of Cinnaminson, New Jersey. Once each work area was stabilized, plastic coverings removed, and surfaces cleaned, the environmental technician performed a visual inspection. Upon passing the visual inspection, the contractor performed EPA RRP verification wipes as required by EPA Lead RRP. The contractor and technician had to agree that each wipe passed the cleanliness standard. If either the contractor or technician failed a wipe, the space was recleaned and retested until the wipes passed. For the majority of spaces, passing EPA RRP verification wipes were the only tests required.

In “Child-occupied area” spaces, at least one colorimetric wipe per space was collected. “Child-occupied areas” include but are not limited to classrooms, restrooms, cafeterias, gymnasiums, IMCs, and auditoriums that are routinely used by children in pre-kindergarten, kindergarten, and first grade. Common areas that these children only pass through, such as hallways and stairwells are not included. The Child-occupied areas were identified by the Principal. Due to the number of special needs students throughout the building, it was agreed that colorimetric wipes would be collected in every classroom. The colorimetric wipes have a detection limit of 18 micrograms (μg) of lead. If the wipe changes from a yellow or orange color to a pink or red color, it indicates that there is a concentration of lead greater than 18 μg and the wipe fails. If a colorimetric wipe failed, the space was recleaned until both passing EPA RRP verification wipes and colorimetric wipes were obtained.

Approximately ten percent of colorimetric wipes collected or at least one from each child occupied area and additional classrooms were sent to EMSL Analytical, Inc. for flame atomic absorption spectrophotometry. If laboratory results were greater than 10 μg , the space was recleaned and retested with EPA RRP verification wipes, colorimetric wipes, and flame atomic absorption until the results were less than 10 μg .

III. Oversight

A. Scope of Work

A Scope of Work for Hopkinson Elementary School was developed following a room-by-room inspection of the school. The assessor looked for cracking, chipping, gouging, holes, flaking, spalling, efflorescence, and significant moisture damage on walls and ceilings throughout the school. The assessor also recorded any observed paint chips or plaster debris on floors, windowsills, furniture, and stored materials. The observed damage for each space became the Scope of Work for this project. Additional areas of damage found behind wall hangings and inside decluttered closets were added to the scope of work as they were observed.

A copy of the Scope of Work can be found in Appendix A.

B. EPA Checklist

The on-site environmental technician completed an EPA Checklist spreadsheet. This spreadsheet confirmed that for each work area that warning signs were posted at the entrance, the work area was contained to prevent the spread of dust and debris, all objects in the work area were removed or covered, HVAC ducts were closed and covered, windows were closed, doors were closed and sealed, doors that must be used for passage were covered to prevent the spread of dust, floors were covered with taped down plastic sheeting, waste was contained on-site and while being transported off site, work areas were properly cleaned after renovation, all chips and debris were picked up, protective sheeting misted, folded dirty side inward, and taped for removal, and that surfaces were HEPA vacuumed or wiped with wet clothes. The technician also confirmed that a certified renovator performed post renovation cleaning verification and signed off that each of the previously listed requirements had occurred for each work area.

A copy of the EPA Checklist can be found in Appendix B.

C. Oversight

An environmental technician was on-site each day that any prep-work, stabilization, or painting was performed by the contractor. The overall responsibility of the technician was to ensure compliance with lead safe work practices. Each technician was a certified renovator and lead dust sampling technician. The technician maintained an oversight spreadsheet completing the date each space was pre-cleaned, the contents were moved, the space was prepped, and the surfaces were stabilized. The technician also collected colorimetric and FAAS wipes where necessary and recorded the number of RRP wipes, colorimetric wipes, and the results of any wipes submitted for FAAS on this spreadsheet.

A copy of the Oversight spreadsheet can be found in Appendix C.

D. Sample Results

Summary of Sample Results for Hopkinson Elementary School		
Number of RRP Wipes	Number of Colorimetric Wipes	Number of FAAS Samples
1,471	210	157

Specific locations for the RRP verification wipes and colorimetric wipes can be found in Appendix C. Specific results of flame atomic absorption samples can be found in Appendix D.

A copy of photos taken on sight are presented in Appendix E – Photo Log. A copy of VERTEX’s RRP certification and information on the environmental technician certifications is presented in Appendix F - Environmental Firm Certifications. A copy of the painting contractor’s RRP certification and information on the painter certifications is presented in Appendix G - Paint Contractor Certifications. The initial communication titled Notice of Building Improvement Project: Paint and Plaster Stabilization is presented in Appendix H - Documentation of Parent and Staff Notifications.

Appendix A. Scope of Work Table

Hopkinson

ULCS #	Element	BldgElmt ID	Floor	Space #	Space Type	On-Site Room Name	Student/Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/negative)	Additional Component	Substrate Material	Color	Description of Paint and Plaster Damage	Additional Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Additional Component XRF (positive/negative)	Debris Present (describe location)	Quantity (sf)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Comments/ Description/ Notes
7300	1	B730001-1	B	S2	Administrative Office	Faculty Office S2/ Classroom	yes	W1	Plaster	Beige	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	B	S2	Administrative Office	Faculty Office S2/ Classroom	yes	W2	Sheetrock	Beige	Cracking/Friction	10	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	B	S2	Administrative Office	Faculty Office S2/ Classroom	yes	W3	Plaster/CMU	Beige	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	B	S2	Administrative Office	Faculty Office S2/ Classroom	yes	Radiator	Metal	Silver	Alligatoring	20	0.17	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	B	S2	Administrative Office	Faculty Office S2/ Classroom	yes	W4	Plaster	Beige	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	B	S2	Administrative Office	Faculty Office S2/ Classroom	yes	Ceiling	Plaster	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	B	S2	Administrative Office	Faculty Office S2/ Classroom	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	B	S1	Primary Classroom S2	Classroom S2	yes	W1	Plaster	Beige	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	B	S1	Primary Classroom S2	Classroom S2	yes	W2	Sheetrock	Beige	Cracking/Friction	10	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	B	S1	Primary Classroom S2	Classroom S2	yes	W3	Plaster/CMU	Beige	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	B	S1	Primary Classroom S2	Classroom S2	yes	Radiator	Metal	Silver	Alligatoring	20	0.17	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	B	S1	Primary Classroom S2	Classroom S2	yes	W4	Plaster	Beige	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	B	S1	Primary Classroom S2	Classroom S2	yes	Ceiling	Plaster	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	B	S1	Primary Classroom S2	Classroom S2	yes	W3	Plaster	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	B	001A	Primary Classroom S1 (Music Room)	Classroom S1	yes	W1	Plaster	Beige	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	B	001	Primary Classroom S1	Classroom S1	yes	W2	Plaster	Beige	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	B	001	Primary Classroom S1	Classroom S1	yes	W3	Plaster	Beige	Flaking/Cracking	40	13.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	B	001	Primary Classroom S1	Classroom S1	yes	Radiator	Metal	Silver	Alligatoring	40	0.04	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	B	001	Primary Classroom S1	Classroom S1	yes	W4	Sheetrock	Multi	Alligatoring	300	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	B	001	Primary Classroom S1	Classroom S1	yes	Ceiling	Plaster	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	B	001	Primary Classroom S1	Classroom S1	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	B	001A	Storage Classroom S1 Closet	Classroom S1 Closet	yes	W1	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Prior to Repair	No	no	floor tile
7300	1	B730001-1	B	001A	Storage Classroom S1 Closet	Classroom S1 Closet	yes	W2	Plaster	White	Chipping/Flaking	100	15.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Prior to Repair	No	no	
7300	1	B730001-1	B	001A	Storage Classroom S1 Closet	Classroom S1 Closet	yes	W3	Plaster	White	Cracking	40	10.3	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Partially Inaccessible	No	no	
7300	1	B730001-1	B	001A	Storage Classroom S1 Closet	Classroom S1 Closet	yes	W4	Plaster	White	Cracking/Flaking	100	12.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Partially Inaccessible	No	no	
7300	1	B730001-1	B	001A	Storage Classroom S1 Closet	Classroom S1 Closet	yes	Ceiling	Plaster	White	Cracking	60	15.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	B	001A	Storage Classroom S1 Closet	Classroom S1 Closet	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	floor tile
7300	1	B730001-1	B	H01	Circulation (Hallway)	Hallway from Classroom S1 to Faculty Office	yes	W1	Brick	Blue	Flaking/Chipping	100	2.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	B	H01	Circulation (Hallway)	Hallway from Classroom S1 to Faculty Office	yes	W2	Brick	Blue	Flaking/Chipping	100	2.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	B	H01	Circulation (Hallway)	Hallway from Classroom S1 to Faculty Office	yes	W3	Plaster	Blue	Flaking/Chipping	100	5.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	B	H01	Circulation (Hallway)	Hallway from Classroom S1 to Faculty Office	yes	W4	Brick	Blue	Flaking/Chipping	100	5.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	B	H01	Circulation (Hallway)	Hallway from Classroom S1 to Faculty Office	yes	Ceiling	Plaster	White	Flaking/Chipping	100	1.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	B	H01	Circulation (Hallway)	Hallway from Classroom S1 to Faculty Office	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	B	S04	Stairs	Stairwell next to Classroom S1	yes	W1	Brick	Blue	Flaking/Chipping	100	9.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	B	S04	Stairs	Stairwell next to Classroom S1	yes	W2	Brick	Blue	Flaking/Chipping	100	5.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	B	S04	Stairs	Stairwell next to Classroom S1	yes	W3	Plaster	Blue	Flaking/Chipping	100	3.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	B	S04	Stairs	Stairwell next to Classroom S1	yes	W4	Brick	Blue	Flaking/Chipping	100	4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	B	S04	Stairs	Stairwell next to Classroom S1	yes	Ceiling	Plaster	White	Flaking/Chipping	100	15.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	B	S04	Stairs	Stairwell next to Classroom S1	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	B	S04	Stairs	Stairwell next to Classroom S1	yes	Tread	Concrete	Grey	Friction	30	5.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	B	S04	Stairs	Stairwell next to Classroom S1	yes	Stringer	Concrete	Grey	Friction	10	12.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	B	S04	Stairs	Stairwell next to Classroom S1	yes	Riser	Concrete	Grey	Friction	30	8.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	B	S04	Stairs	Stairwell next to Classroom S1	yes	Newell Post	Concrete	Grey	Friction	10	1.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	B	S04	Stairs	Stairwell next to Classroom S1	yes	Handrail	Metal	Grey	Friction	5	6.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	B	S04	Stairs	Stairwell next to Classroom S1	yes	Ballast	Metal	Grey	Friction	15	0.3	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	B	005	Cafetorium (Cafeteria / Gymnasium)	Cafetorium	yes	W1	Brick	Pink	Holes	10	5.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	B	005	Cafetorium (Cafeteria / Gymnasium)	Cafetorium	yes	W2	Brick	Pink	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	B	005	Cafetorium (Cafeteria / Gymnasium)	Cafetorium	yes	Stair Tread	Concrete	Brown	Friction	20	0.06	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	B	005	Cafetorium (Cafeteria / Gymnasium)	Cafetorium	yes	Stair Riser	Concrete	Brown	Friction	20	2.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	B	005	Cafetorium (Cafeteria / Gymnasium)	Cafetorium	yes	W3	Brick	Pink	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	B	005	Cafetorium (Cafeteria / Gymnasium)	Cafetorium	yes	Pipe	Metal	Brown	Chipping	6	0.22	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	B	005	Cafetorium (Cafeteria / Gymnasium)	Cafetorium	yes	W4	Brick	Pink	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	B	005	Cafetorium (Cafeteria / Gymnasium)	Cafetorium	yes	Stair Tread	Concrete	Brown	Friction	20	0.06	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	B	005	Cafetorium (Cafeteria / Gymnasium)	Cafetorium	yes	Stair Riser	Concrete	Brown	Friction	20	2.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	B	005	Cafetorium (Cafeteria / Gymnasium)	Cafetorium	yes	Ceiling	Plaster	White	Cracking/Chipping	50	24.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	B	005	Cafetorium (Cafeteria / Gymnasium)	Cafetorium	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	floor tile
7300	1	B730001-1	B	003	Storage Cafetorium Storage	Cafetorium Storage	yes	W1	Brick	Blue	Chipping	40	4.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Prior to Repair	No	no	
7300	1	B730001-1	B	003	Storage Cafetorium Storage	Cafetorium Storage	yes	W2	Brick	Blue	Chipping	20	3.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Prior to Repair	No	no	
7300	1	B730001-1	B	003	Storage Cafetorium Storage	Cafetorium Storage	yes	Pipe	Metal	Pink	Chipping	6	0.25	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	B	003	Storage Cafetorium Storage	Cafetorium Storage	yes	W3	Brick	Blue	Chipping/Cracking	50	1.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Prior to Repair	No	no	
7300	1	B730001-1	B	003	Storage Cafetorium Storage	Cafetorium Storage	yes	W4	Brick	Blue	Chipping/Cracking	50	2.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Prior to Repair	No	no	

Hopkinson

ULCS #	Element	BldgElmt ID	Floor	Space #	Space Type	On-Site Room Name	Student/Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/negative)	Additional Component	Substrate Material	Color	Description of Paint and Plaster Damage	Additional Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Additional Component XRF (positive/negative)	Debris Present (describe location)	Quantity (sf)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Comments/ Description/ Notes
7300	1	B730001-1	B	003	Storage	Cafeterium Storage	yes	Ceiling	Plaster	White	Efflorescence/Flaking	20	15.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	B	003	Storage	Cafeterium Storage	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	B	004	Administrative Office	Physical Education Office	yes	W1	Brick	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	B	004	Administrative Office	Physical Education Office	yes	W2	Brick	White	Chipping	10	4.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Partially Inaccessible	No	no	
7300	1	B730001-1	B	004	Administrative Office	Physical Education Office	yes	W3	Brick	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	B	004	Administrative Office	Physical Education Office	yes	W4	Brick	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	B	004	Administrative Office	Physical Education Office	yes	Ceiling	Plaster	White	Cracking	10	12.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Partially Inaccessible	No	no	
7300	1	B730001-1	B	004	Administrative Office	Physical Education Office	yes	Pipe	Metal	White	Chipping	50	6.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	B	004	Administrative Office	Physical Education Office	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	B	H05	Circulation (Hallway)	Cafeteria Exterior Exit Hallway	yes	W1	Brick	White	Alligating	30	5.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	B	H05	Circulation (Hallway)	Cafeteria Exterior Exit Hallway	yes	W2	Brick	White	Alligating	20	8.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	B	H05	Circulation (Hallway)	Cafeteria Exterior Exit Hallway	yes	Window Frame	Wood	White	Alligating	30	0.06	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	B	H05	Circulation (Hallway)	Cafeteria Exterior Exit Hallway	yes	W3	Brick	White	Flaking/Chipping	40	1.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	B	H05	Circulation (Hallway)	Cafeteria Exterior Exit Hallway	yes	W4	Brick	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	B	H05	Circulation (Hallway)	Cafeteria Exterior Exit Hallway	yes	Pipe	Metal	Pink	Flaking/Chipping	20	0.16	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	B	H05	Circulation (Hallway)	Cafeteria Exterior Exit Hallway	yes	Ceiling	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	B	H05	Circulation (Hallway)	Cafeteria Exterior Exit Hallway	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	B	H02	Circulation (Hallway)	Hallway outside Kitchen and Boiler Room	yes	W1	Brick	Blue	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	B	H02	Circulation (Hallway)	Hallway outside Kitchen and Boiler Room	yes	W2	Brick	Blue	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	B	H02	Circulation (Hallway)	Hallway outside Kitchen and Boiler Room	yes	W3	Brick	Blue	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	B	H02	Circulation (Hallway)	Hallway outside Kitchen and Boiler Room	yes	W4	Brick	Blue	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	B	H02	Circulation (Hallway)	Hallway outside Kitchen and Boiler Room	yes	Ceiling	Plaster	White	Flaking	100	13.3	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	B	H02	Circulation (Hallway)	Hallway outside Kitchen and Boiler Room	yes	Duct	Metal	White	Chipping/Flaking	100	16.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	B	H02	Circulation (Hallway)	Hallway outside Kitchen and Boiler Room	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	B	011	Boiler Room	Boiler Room	no	W1	Brick	White	Flaking	500	23.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	B	011	Boiler Room	Boiler Room	no	W2	Brick	White	Flaking	500	16.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	B	011	Boiler Room	Boiler Room	no	W3	Brick	White	Flaking	500	17.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	B	011	Boiler Room	Boiler Room	no	W4	Brick	White	Flaking	500	21.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	B	011	Boiler Room	Boiler Room	no	Ceiling	Concrete	White	Flaking	2000	26.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	B	011	Boiler Room	Boiler Room	no	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	unpainted
7300	1	B730001-1	B	012	Mechanical Room	Fan Room	no	W1	Brick	Blue	Flaking	200	16.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	B	012	Mechanical Room	Fan Room	no	W2	Brick	Blue	Flaking	100	29.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	B	012	Mechanical Room	Fan Room	no	Pipe	Metal	Blue	Flaking	10	6.3	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	B	012	Mechanical Room	Fan Room	no	W3	Brick	Blue	Flaking	300	29.3	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	B	012	Mechanical Room	Fan Room	no	W4	Brick	Blue	Flaking	200	21.3	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	B	012	Mechanical Room	Fan Room	no	Ceiling	Concrete	White	Flaking	500	20	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	B	012	Mechanical Room	Fan Room	no	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	B	014	Administrative Office	Building Engineer's Office	no	W1	Concrete	Pink	Flaking/Efflorescence	500	19.3	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	B	014	Administrative Office	Building Engineer's Office	no	W2	Concrete	Pink	Flaking/Efflorescence	500	10.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	B	014	Administrative Office	Building Engineer's Office	no	W3	Concrete	Pink	Flaking/Efflorescence	500	21.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	B	014	Administrative Office	Building Engineer's Office	no	W4	Concrete	Pink	Flaking/Efflorescence	500	22	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	B	014	Administrative Office	Building Engineer's Office	no	Ceiling	Concrete	White	Flaking/Efflorescence	1000	20	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	B	014	Administrative Office	Building Engineer's Office	no	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	B	013	Mechanical Room	Oil Tank Room	no	W1	Brick	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	unpainted
7300	1	B730001-1	B	013	Mechanical Room	Oil Tank Room	no	W2	Brick	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	unpainted
7300	1	B730001-1	B	013	Mechanical Room	Oil Tank Room	no	W3	Brick	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	unpainted
7300	1	B730001-1	B	013	Mechanical Room	Oil Tank Room	no	W4	Brick	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	unpainted
7300	1	B730001-1	B	013	Mechanical Room	Oil Tank Room	no	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	unpainted
7300	1	B730001-1	B	013	Mechanical Room	Oil Tank Room	no	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	unpainted
7300	1	B730001-1	B	007	Kitchen	Kitchen	yes	W1	Brick	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	B	007	Kitchen	Kitchen	yes	W2	Brick	White	Cracking	5	1.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	B	007	Kitchen	Kitchen	yes	W3	Brick	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	B	007	Kitchen	Kitchen	yes	W4	Brick	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	B	007	Kitchen	Kitchen	yes	Ceiling	Plaster	White	Flaking/Cracking/Moisture	40	4.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	B	007	Kitchen	Kitchen	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	floor tile
7300	1	B730001-1	B	007A	Kitchen Office	Kitchen Office	yes	W1	Brick	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Prior to Repair	No	no	
7300	1	B730001-1	B	007A	Kitchen Office	Kitchen Office	yes	W2	Brick	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Prior to Repair	No	no	
7300	1	B730001-1	B	007A	Kitchen Office	Kitchen Office	yes	W3	Brick	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Prior to Repair	No	no	

Hopkinson

ULCS #	Element	BldgElmt ID	Floor	Space #	Space Type	On-Site Room Name	Student/Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/negative)	Additional Component	Substrate Material	Color	Description of Paint and Plaster Damage	Additional Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Additional Component XRF (positive/negative)	Debris Present (describe location)	Quantity (sf)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Comments/ Description/ Notes
7300	1	B730001-1	B	007A	Kitchen Office	Kitchen Office	yes	W4	Erick	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Prior to Repair	No	no	
7300	1	B730001-1	B	007A	Kitchen Office	Kitchen Office	yes	Ceiling	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	B	007A	Kitchen Office	Kitchen Office	yes	Floor	Concrete	Grey	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	B	B2	Primary	Classroom B2 (Art Room)	yes	W1	Plaster	White	Chipping/Cracking	20	14.3	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Partially Inaccessible	No	no	
7300	1	B730001-1	B	B2	Primary	Classroom B2 (Art Room)	yes	W2	Sheetrock	White	Holes/Moisture Damage	20	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	B	B2	Primary	Classroom B2 (Art Room)	yes	W3	Plaster	White	Chipping/Flaking	30	1.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	B	B2	Primary	Classroom B2 (Art Room)	yes	Radiator	Metal	Silver	Alligatoring	20	0.03	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	B	B2	Primary	Classroom B2 (Art Room)	yes	W4	Plaster	White	Cracking	10	15.3	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	B	B2	Primary	Classroom B2 (Art Room)	yes	Ceiling	Plaster	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	B	B2	Primary	Classroom B2 (Art Room)	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	floor tile over concrete
7300	1	B730001-1	B	B2A	Storage	Classroom B2 Coat Room	yes	W1	Plaster	Yellow	Cracking	100	15.3	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Partially Inaccessible	No	no	
7300	1	B730001-1	B	B2A	Storage	Classroom B2 Coat Room	yes	W2	Plaster	Yellow	Cracking	20	4.3	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Partially Inaccessible	No	no	
7300	1	B730001-1	B	B2A	Storage	Classroom B2 Coat Room	yes	W3	Plaster	Yellow	Cracking	200	7.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Partially Inaccessible	No	no	
7300	1	B730001-1	B	B2A	Storage	Classroom B2 Coat Room	yes	W4	Plaster	Yellow	Cracking	20	10.3	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Partially Inaccessible	No	no	
7300	1	B730001-1	B	B2A	Storage	Classroom B2 Coat Room	yes	Ceiling	Plaster	Yellow	Cracking	300	19.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	floor tile over concrete
7300	1	B730001-1	B	B2A	Storage	Classroom B2 Coat Room	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	B	B2B	Storage	Classroom B2 Closet	yes	W1	Plaster	Yellow	Cracking/Flaking	100	10.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	B	B2B	Storage	Classroom B2 Closet	yes	W2	Plaster	Yellow	Cracking/Flaking	60	9.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	B	B2B	Storage	Classroom B2 Closet	yes	W3	Plaster	Yellow	Cracking/Flaking	150	9.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	B	B2B	Storage	Classroom B2 Closet	yes	W4	Plaster	Yellow	Cracking/Flaking/Spalling	80	9.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	B	B2B	Storage	Classroom B2 Closet	yes	Ceiling	Plaster	Yellow	Cracking/Flaking	200	10.3	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	B	B2B	Storage	Classroom B2 Closet	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	floor tile over concrete
7300	1	B730001-1	B	009	Primary	Classroom B1 (ESOL)	yes	W1	Plaster	White	Chippinh/Cracking	20	16.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Prior to Repair	No	no	
7300	1	B730001-1	B	009	Primary	Classroom B1 (ESOL)	yes	W2	Sheetrock	White	Peeling/Staple Holes	10	9.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Partially Inaccessible	No	no	
7300	1	B730001-1	B	009	Primary	Classroom B1 (ESOL)	yes	W3	Plaster	White	Efflorescence/Flaking/Chipping	60	13.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Partially Inaccessible	No	no	
7300	1	B730001-1	B	009	Primary	Classroom B1 (ESOL)	yes	W4	Sheetrock	White	Peeling/Staple Holes	30	1.3	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Prior to Repair	No	no	
7300	1	B730001-1	B	009	Primary	Classroom B1 (ESOL)	yes	Ceiling	Plaster	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	floor tile over concrete
7300	1	B730001-1	B	009	Primary	Classroom B1 (ESOL)	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	B	010	Storage	Classroom B1 Closet (Rear of Classroom)	yes	W1	Plaster	Beige	Efflorescence/Flaking	200	15.3	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	100	Prior to Repair	No	no	
7300	1	B730001-1	B	010	Storage	Classroom B1 Closet (Rear of Classroom)	yes	W2	Plaster	Beige	Efflorescence/Flaking	120	19.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Prior to Repair	No	no	
7300	1	B730001-1	B	010	Storage	Classroom B1 Closet (Rear of Classroom)	yes	W3	Plaster	Beige	Cracking/Efflorescence	100	10.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Prior to Repair	No	no	
7300	1	B730001-1	B	010	Storage	Classroom B1 Closet (Rear of Classroom)	yes	W4	Plaster	Beige	FlakingCracking/Efflorescence	130	4.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Prior to Repair	No	no	
7300	1	B730001-1	B	010	Storage	Classroom B1 Closet (Rear of Classroom)	yes	Ceiling	Plaster	Beige	FlakingCracking/Efflorescence	130	15.3	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	B	010	Storage	Classroom B1 Closet (Adjacent to Entrance)	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	floor tile over concrete
7300	1	B730001-1	B	011	Storage	Classroom B1 Closet (Adjacent to Entrance)	yes	W1	Plaster	Beige	Cracking/Chipping	30	10.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Prior to Repair	No	no	
7300	1	B730001-1	B	011	Storage	Classroom B1 Closet (Adjacent to Entrance)	yes	W2	Plaster	Beige	Flaking/Cracking	50	15.3	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Prior to Repair	No	no	
7300	1	B730001-1	B	011	Storage	Classroom B1 Closet (Adjacent to Entrance)	yes	W3	Plaster	Beige	Cracking	20	19.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Partially Inaccessible	No	no	
7300	1	B730001-1	B	011	Storage	Classroom B1 Closet (Adjacent to Entrance)	yes	W4	Plaster	Beige	Cracking	30	18.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Partially Inaccessible	No	no	
7300	1	B730001-1	B	011	Storage	Classroom B1 Closet (Adjacent to Entrance)	yes	Pipe	Metal	Beige	Chipping	6	1.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	B	011	Storage	Classroom B1 Closet (Adjacent to Entrance)	yes	Ceiling	Plaster	Beige	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	floor tile over concrete
7300	1	B730001-1	B	011	Storage	Classroom B1 Closet (Adjacent to Entrance)	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	B	S03	Stairs	Stairwell next to Classroom B1	yes	W1	Plaster	Beige	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	B	S03	Stairs	Stairwell next to Classroom B1	yes	W2	Plaster	Beige	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	B	S03	Stairs	Stairwell next to Classroom B1	yes	W3	Plaster	Beige	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	B	S03	Stairs	Stairwell next to Classroom B1	yes	W4	Plaster	Beige	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	B	S03	Stairs	Stairwell next to Classroom B1	yes	Ceiling	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	B	S03	Stairs	Stairwell next to Classroom B1	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	B	S03	Stairs	Stairwell next to Classroom B1	yes	Tread	Concrete	Grey	Friction	30	5.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	B	S03	Stairs	Stairwell next to Classroom B1	yes	Stringer	Concrete	Grey	Friction	10	12.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	B	S03	Stairs	Stairwell next to Classroom B1	yes	Riser	Concrete	Grey	Friction	30	8.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	B	S03	Stairs	Stairwell next to Classroom B1	yes	Newel Post	Concrete	Grey	Friction	10	1.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	B	S03	Stairs	Stairwell next to Classroom B1	yes	Handrail	Metal	Grey	Friction	5	6.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	B	S03	Stairs	Stairwell next to Classroom B1	yes	Ballast	Metal	Grey	Friction	15	0.3	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	B	H03	Circulation (Hallway)	Hallway outside Classrooms B1 and B2	yes	W1	Plaster	Blue	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	B	H03	Circulation (Hallway)	Hallway outside Classrooms B1 and B2	yes	W2	Plaster	Blue	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	B	H03	Circulation (Hallway)	Hallway outside Classrooms B1 and B2	yes	W3	Plaster	Blue	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	B	H03	Circulation (Hallway)	Hallway outside Classrooms B1 and B2	yes	Tread	Concrete	Grey	Friction	30	5.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	B	H03	Circulation (Hallway)	Hallway outside Classrooms B1 and B2	yes	Riser	Concrete	Grey	Friction	30	12.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	B	H03	Circulation (Hallway)	Hallway outside Classrooms B1 and B2	yes	Handrail	Metal	Grey	Friction	10	8.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	B	H03	Circulation (Hallway)	Hallway outside Classrooms B1 and B2	yes	W4	Plaster	Blue	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	B	H03	Circulation (Hallway)	Hallway outside Classrooms B1 and B2	yes	Ceiling	Plaster	White	Flaking/Holes/Efflorescence	80	2.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	B	H03	Circulation (Hallway)	Hallway outside Classrooms B1 and B2	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	113	General Administrative Reception Area	Main Office	yes	W1																			

Hopkinson

ULCS #	Element	Bldg/Eld ID	Floor	Space #	Space Type	On-Site Room Name	Student/Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/negative)	Additional Component	Substrate Material	Color	Description of Paint and Plaster Damage	Additional Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Additional Component XRF (positive/negative)	Debris Present (describe location)	Quantity (sf)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Comments/ Description/ Notes
7300	1	B730001-1	1	113	General Administrative Reception Area	Main Office	yes	Ceiling	Plaster	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	113	General Administrative Reception Area	Main Office	yes	Floor	Wood	Varnish	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	113A	Storage	Main Office Closet	yes	W1	Plaster	Yellow	Flaking/Cracking/Chipping	150	5.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Prior to Repair	No	no	
7300	1	B730001-1	1	113A	Storage	Main Office Closet	yes	Pipe	Metal	Yellow	Chipping	30	12	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	113A	Storage	Main Office Closet	yes	W2	Plaster	Yellow	Cracking	50	9.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Prior to Repair	No	no	
7300	1	B730001-1	1	113A	Storage	Main Office Closet	yes	W3	Plaster	Yellow	Holes/Cracking	50	6.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Prior to Repair	No	no	
7300	1	B730001-1	1	113A	Storage	Main Office Closet	yes	W4	Plaster	Yellow	Flaking	100	4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Prior to Repair	No	no	
7300	1	B730001-1	1	113A	Storage	Main Office Closet	yes	Ceiling	Plaster	Yellow	Flaking/Efflorescence/Moisture Damage	100	11.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	113A	Storage	Main Office Closet	yes	Floor	Wood	Varnish	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	114	Principal/Director's Office	Principal's Office	yes	W1	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Prior to Repair	No	no	
7300	1	B730001-1	1	114	Principal/Director's Office	Principal's Office	yes	W2	Plaster	White	Cracking	20	21.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Prior to Repair	No	no	
7300	1	B730001-1	1	114	Principal/Director's Office	Principal's Office	yes	W3	Plaster	White	Flaking	20	5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Prior to Repair	No	no	
7300	1	B730001-1	1	114	Principal/Director's Office	Principal's Office	yes	W4	Plaster	White	Cracking	20	23.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Prior to Repair	No	no	
7300	1	B730001-1	1	114	Principal/Director's Office	Principal's Office	yes	Ceiling	Plaster	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	114	Principal/Director's Office	Principal's Office	yes	Floor	Wood	Varnish	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	114A	Storage	Principal's Closet	yes	W1	Plaster	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Prior to Repair	No	no	
7300	1	B730001-1	1	114A	Storage	Principal's Closet	yes	W2	Plaster	Yellow	Cracking/Chipping	20	14.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Partially Inaccessible	No	no	
7300	1	B730001-1	1	114A	Storage	Principal's Closet	yes	W3	Plaster	Yellow	Cracking	10	20	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Prior to Repair	No	no	
7300	1	B730001-1	1	114A	Storage	Principal's Closet	yes	W4	Plaster	Yellow	Cracking	20	21	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Partially Inaccessible	No	no	
7300	1	B730001-1	1	114A	Storage	Principal's Closet	yes	Ceiling	Plaster	Yellow	Flaking/Hole	150	16	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	114A	Storage	Principal's Closet	yes	Floor	Wood	Varnish	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	114C	Restrooms, Staff - Male/Female	Principal's Restroom	yes	W1	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	114C	Restrooms, Staff - Male/Female	Principal's Restroom	yes	W2	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	114C	Restrooms, Staff - Male/Female	Principal's Restroom	yes	W3	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	114C	Restrooms, Staff - Male/Female	Principal's Restroom	yes	W4	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	114C	Restrooms, Staff - Male/Female	Principal's Restroom	yes	Ceiling	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	114C	Restrooms, Staff - Male/Female	Principal's Restroom	yes	Floor	Concrete	Blue	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	H114	Circulation (Hallway)	Principal's Hallway	yes	W1	Plaster	Blue	Cracking/Flaking	5	11.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	H114	Circulation (Hallway)	Principal's Hallway	yes	W2	Plaster	Blue	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	H114	Circulation (Hallway)	Principal's Hallway	yes	W3	Plaster	Blue	Cracking	5	10	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	H114	Circulation (Hallway)	Principal's Hallway	yes	W4	Plaster	Blue	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	H114	Circulation (Hallway)	Principal's Hallway	yes	Ceiling	Plaster	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	H114	Circulation (Hallway)	Principal's Hallway	yes	Floor	Wood	Varnish	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	S13	Stairs	Stairwell outside Classroom 101	yes	W1	Plaster	Beige	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	S13	Stairs	Stairwell outside Classroom 101	yes	W2	Plaster	Beige	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	S13	Stairs	Stairwell outside Classroom 101	yes	W3	Plaster	Beige	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	S13	Stairs	Stairwell outside Classroom 101	yes	W4	Plaster	Beige	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	S13	Stairs	Stairwell outside Classroom 101	yes	Ceiling	Plaster	Beige	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	S13	Stairs	Stairwell outside Classroom 101	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	S13	Stairs	Stairwell outside Classroom 101	yes	Tread	Concrete	Grey	Friction	20	0.03	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	S13	Stairs	Stairwell outside Classroom 101	yes	Riser	Concrete	Grey	Friction	10	2.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	S13	Stairs	Stairwell outside Classroom 101	yes	Stringer	Concrete	Grey	Friction	10	2.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	S13	Stairs	Stairwell outside Classroom 101	yes	Ballast	Metal	Brown	Friction	10	0.3	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	S13	Stairs	Stairwell outside Classroom 101	yes	Newel Post	Metal	Brown	Friction	6	2.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	100	Restrooms, Staff - Female	Women's Restroom next to Classroom 101	yes	W1	Plaster	Beige	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	100	Restrooms, Staff - Female	Women's Restroom next to Classroom 101	yes	W2	Plaster	Beige	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	100	Restrooms, Staff - Female	Women's Restroom next to Classroom 101	yes	W3	Plaster	Beige	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	100	Restrooms, Staff - Female	Women's Restroom next to Classroom 101	yes	Radiator	Metal	Silver	Alligating	10	0.03	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	100	Restrooms, Staff - Female	Women's Restroom next to Classroom 101	yes	Pipe	Metal	Beige	Flaking	10	0.04	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	100	Restrooms, Staff - Female	Women's Restroom next to Classroom 101	yes	W4	Plaster	Beige	Efflorescence	5	6.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	100	Restrooms, Staff - Female	Women's Restroom next to Classroom 101	yes	Ceiling	Plaster	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	100	Restrooms, Staff - Female	Women's Restroom next to Classroom 101	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	101	Primary	Classroom 101	yes	W1	Plaster	Beige	Chipping	30	23.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	101	Primary	Classroom 101	yes	W2	Plaster	Beige	Chipping/Cracking	20	10.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Partially Inaccessible	No	no	majority of wall covered by wooden bookcase
7300	1	B730001-1	1	101	Primary	Classroom 101	yes	W3	Plaster	Beige	Flaking/Efflorescence/ Cracking	60	11.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	101	Primary	Classroom 101	yes	W4	Plaster	Beige	Cracking/Chipping	40	9.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	101	Primary	Classroom 101	yes	Ceiling	Plaster	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	101	Primary	Classroom 101	yes	Floor	Wood	Varnish	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	101A	Storage	Classroom 101 Coat Room	yes	W1	Plaster	Beige	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	101A	Storage	Classroom 101 Coat Room	yes	W2	Plaster	Beige	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	101A	Storage	Classroom 101 Coat Room	yes	W3	Plaster	Beige	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	101A	Storage	Classroom 101 Coat Room	yes	W4	Plaster	Beige	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	

Hopkinson

ULCS #	E l e m e n t	BldgElmt ID	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)	Additional Component	Substrate Material	Color	Description of Paint and Plaster Damage	Additional Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Additional Component XRF (positive/ negative)	Debris Present (describe location)	Quantity (sf)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Comments/ Description/ Notes
7300	1	B730001-1	1	101A	Storage	Classroom 101 Coat Room	yes	Ceiling	Plaster	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	101A	Storage	Classroom 101 Coat Room	yes	Floor	Wood	Varnish	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	101B	Student Restrooms - Male/Female (Classroom)	Classroom 101 Restroom	yes	W1	Plaster	Beige	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	101B	Student Restrooms - Male/Female (Classroom)	Classroom 101 Restroom	yes	W2	Plaster	Beige	Cracking	10	23	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	101B	Student Restrooms - Male/Female (Classroom)	Classroom 101 Restroom	yes	W3	Plaster	Beige	Hole/Cracking	20	15.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	101B	Student Restrooms - Male/Female (Classroom)	Classroom 101 Restroom	yes	Radiator	Metal	Silver	Alligating	10	0.05	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	101B	Student Restrooms - Male/Female (Classroom)	Classroom 101 Restroom	yes	W4	Plaster	Beige	Cracking	60	21	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	101B	Student Restrooms - Male/Female (Classroom)	Classroom 101 Restroom	yes	Ceiling	Plaster	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	101B	Student Restrooms - Male/Female (Classroom)	Classroom 101 Restroom	yes	Floor	Concrete	Grey	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	102	Primary	Classroom 102	yes	W1	Plaster	Beige	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Partially Inaccessible	No	no	
7300	1	B730001-1	1	102	Primary	Classroom 102	yes	W2	Plaster	Beige	Holes/Chipping	10	10	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	102	Primary	Classroom 102	yes	W3	Plaster	Beige	Staple Holes/Flaking/Chipping	40	6.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	behind radiator
7300	1	B730001-1	1	102	Primary	Classroom 102	yes	W4	Plaster	Beige	Staple Holes	10	23.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	102	Primary	Classroom 102	yes	Ceiling	Plaster	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	102	Primary	Classroom 102	yes	Floor	Wood	Varnish	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	102A	Storage	Classroom 102 Coat Room	yes	W1	Plaster	Blue	Cracking	1	10.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Partially Inaccessible	No	no	wall covered by wooden book case/closet
7300	1	B730001-1	1	102A	Storage	Classroom 102 Coat Room	yes	W2	Plaster	Blue	Cracking/Chipping	30	11.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Partially Inaccessible	No	no	
7300	1	B730001-1	1	102A	Storage	Classroom 102 Coat Room	yes	W3	Plaster	Blue	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Partially Inaccessible	No	no	
7300	1	B730001-1	1	102A	Storage	Classroom 102 Coat Room	yes	W4	Plaster	Blue	Cracking	20	9.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Partially Inaccessible	No	no	
7300	1	B730001-1	1	102A	Storage	Classroom 102 Coat Room	yes	Ceiling	Plaster	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	102A	Storage	Classroom 102 Coat Room	yes	Floor	Wood	Varnish	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	103	Primary	Classroom 103	yes	W1	Plaster	Beige	Chipping/Cracking	30	23	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	103	Primary	Classroom 103	yes	W2	Plaster	Beige	Cracking/Flaking	10	15.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	103	Primary	Classroom 103	yes	W3	Plaster	Beige	Flaking/Chipping/Cracking	40	21	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	103	Primary	Classroom 103	yes	Radiator	Metal	Silver	Alligating	20	0.07	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	103	Primary	Classroom 103	yes	W4	Plaster	Beige	Chipping	10	10	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	103	Primary	Classroom 103	yes	Ceiling	Plaster	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	103	Primary	Classroom 103	yes	Floor	Wood	Varnish	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	half wood floor half floor tile over wood floor
7300	1	B730001-1	1	103A	Storage	Classroom 103 Coat Room	yes	W1	Plaster	Beige	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	103A	Storage	Classroom 103 Coat Room	yes	W2	Plaster	Beige	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	103A	Storage	Classroom 103 Coat Room	yes	W3	Plaster	Beige	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	103A	Storage	Classroom 103 Coat Room	yes	W4	Plaster	Beige	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	103A	Storage	Classroom 103 Coat Room	yes	Ceiling	Plaster	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	103A	Storage	Classroom 103 Coat Room	yes	Floor	Wood	Varnish	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	103B	Storage	Classroom 103 Storage Closet	yes	W1	Plaster	Beige	Efflorescence/Flaking	100	14	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	flaking above ceiling
7300	1	B730001-1	1	103B	Storage	Classroom 103 Storage Closet	yes	Radiator	Metal	Silver	Alligating	15	0.04	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	103B	Storage	Classroom 103 Storage Closet	yes	W2	Plaster	Beige	Efflorescence/Flaking/ Cracking	100	11	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	103B	Storage	Classroom 103 Storage Closet	yes	W3	Plaster	Beige	Chipping/Cracking	80	9.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Partially Inaccessible	No	no	wall blocked by wood bookshelf
7300	1	B730001-1	1	103B	Storage	Classroom 103 Storage Closet	yes	W4	Plaster	Beige	Cracking	60	10	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Partially Inaccessible	No	no	wall blocked by wood bookshelf
7300	1	B730001-1	1	103B	Storage	Classroom 103 Storage Closet	yes	Ceiling	Plaster	White	Flaking	60	21	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	103B	Storage	Classroom 103 Storage Closet	yes	Floor	Wood	Varnish	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	S12	Stairs	Stairwell outside Classroom 103	yes	W1	Plaster	White	Flaking	10	25.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	S12	Stairs	Stairwell outside Classroom 103	yes	Door	Metal	Brown	Friction	20	2.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	S12	Stairs	Stairwell outside Classroom 103	yes	Door Frame	Metal	Brown	Friction	20	9.3	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	S12	Stairs	Stairwell outside Classroom 103	yes	W2	Plaster	White	Flaking/Cracking	40	12.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	S12	Stairs	Stairwell outside Classroom 103	yes	W3	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	S12	Stairs	Stairwell outside Classroom 103	yes	Door	Metal	Brown	Friction	20	12.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	S12	Stairs	Stairwell outside Classroom 103	yes	Door Frame	Metal	Brown	Friction	20	11	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	S12	Stairs	Stairwell outside Classroom 103	yes	W4	Plaster	White	Moisture	10	14.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	S12	Stairs	Stairwell outside Classroom 103	yes	Ceiling	Plaster	White	Cracking	20	12.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	S12	Stairs	Stairwell outside Classroom 103	yes	Floor	Concrete	Grey	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	S12	Stairs	Stairwell outside Classroom 103	yes	Tread	Concrete	Grey	Friction	30	5.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	S12	Stairs	Stairwell outside Classroom 103	yes	Stringer	Concrete	Grey	Friction	10	12.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	S12	Stairs	Stairwell outside Classroom 103	yes	Riser	Concrete	Grey	Friction	30	8.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	S12	Stairs	Stairwell outside Classroom 103	yes	Newel Post	Concrete	Grey	Friction	10	1.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	S12	Stairs	Stairwell outside Classroom 103	yes	Handrail	Metal	Grey	Friction	5	6.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	S12	Stairs	Stairwell outside Classroom 103	yes	Ballast	Metal	Grey	Friction	15	0.3	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	H14	Circulation (Hallway)	Hallway from Classrooms 101 to 103	yes	W1	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	H14	Circulation (Hallway)	Hallway from Classrooms 101 to 103	yes	Door	Metal	Brown	Friction	20	2.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	H14	Circulation (Hallway)	Hallway from Classrooms 101 to 103	yes	Door Frame	Metal	Brown	Friction	20	4.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	H14	Circulation (Hallway)	Hallway from Classrooms 101 to 103	yes	W2	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	

Hopkinson

ULCS #	Element	BldgElmt ID	Floor	Space #	Space Type	On-Site Room Name	Student/Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/negative)	Additional Component	Substrate Material	Color	Description of Paint and Plaster Damage	Additional Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Additional Component XRF (positive/negative)	Debris Present (describe location)	Quantity (sf)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Comments/ Description/ Notes
7300	1	B730001-1	1	H14	Circulation (Hallway)	Hallway from Classrooms 101 to 103	yes	W3	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	H14	Circulation (Hallway)	Hallway from Classrooms 101 to 103	yes	W4	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	H14	Circulation (Hallway)	Hallway from Classrooms 101 to 103	yes	Ceiling	Plaster	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	H14	Circulation (Hallway)	Hallway from Classrooms 101 to 103	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	103B	Student Restrooms - Female (4-12)	Girl's Restroom	yes	W1	Plaster	Beige	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	103B	Student Restrooms - Female (4-12)	Girl's Restroom	yes	W2	Plaster	Beige	Chipping	20	12.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	103B	Student Restrooms - Female (4-12)	Girl's Restroom	yes	W3	Plaster	Beige	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	103B	Student Restrooms - Female (4-12)	Girl's Restroom	yes	W4	Plaster	Beige	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	103B	Student Restrooms - Female (4-12)	Girl's Restroom	yes	Ceiling	Plaster	White	Efflorescence/Moisture	50	23.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	103B	Student Restrooms - Female (4-12)	Girl's Restroom	yes	Floor	Concrete	Grey	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	104	Primary	Classroom 104	yes	W1	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	104	Primary	Classroom 104	yes	W2	Sheetrock	Blue	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	104	Primary	Classroom 104	yes	W3	Plaster	White	Flaking	10	9.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	behind radiator
7300	1	B730001-1	1	104	Primary	Classroom 104	yes	Radiator	Metal	Silver	Alligatoring	10	0.04	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	104	Primary	Classroom 104	yes	W4	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	104	Primary	Classroom 104	yes	Ceiling	Plaster	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	104	Primary	Classroom 104	yes	Floor	Wood	Varnish	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	104A	Storage	Classroom 104 Coat Room	yes	W1	Plaster	White	Chipping/Cracking	30	9.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	104A	Storage	Classroom 104 Coat Room	yes	W2	Plaster	White	Cracking	20	5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	104A	Storage	Classroom 104 Coat Room	yes	W3	Plaster	White	Chipping/Cracking	10	12.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Partially Inaccessible	No	no	most of wall covered by metal shelf
7300	1	B730001-1	1	104A	Storage	Classroom 104 Coat Room	yes	W4	Plaster	White	Cracking	5	4.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	104A	Storage	Classroom 104 Coat Room	yes	Ceiling	Plaster	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	104A	Storage	Classroom 104 Coat Room	yes	Floor	Wood	Varnish	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	105	Primary	Classroom 105	yes	W1	Plaster	Beige	Chipping/Cracking	40	10.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	105	Primary	Classroom 105	yes	W2	Sheetrock	Beige	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	105	Primary	Classroom 105	yes	W3	Plaster	Beige	Chipping/Cracking/Flaking	60	5.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	105	Primary	Classroom 105	yes	Radiator	Metal	Silver	Alligatoring	15	0.07	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	105	Primary	Classroom 105	yes	W4	Sheetrock	Beige	Chipping/Staple Holes	20	6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	105	Primary	Classroom 105	yes	Ceiling	Plaster	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	105	Primary	Classroom 105	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	floor tile over wood floor
7300	1	B730001-1	1	105A	Storage	Classroom 105 Coat Room	yes	W1	Plaster	Beige	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	105A	Storage	Classroom 105 Coat Room	yes	W2	Plaster	Beige	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	105A	Storage	Classroom 105 Coat Room	yes	W3	Plaster	Beige	Chipping/Holes	60	10.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	105A	Storage	Classroom 105 Coat Room	yes	W4	Plaster	Beige	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	105A	Storage	Classroom 105 Coat Room	yes	Ceiling	Plaster	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	105A	Storage	Classroom 105 Coat Room	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	floor tile over wood floor
7300	1	B730001-1	1	S15A	Stairs	Auditorium Entrance Staircase across from Classroom 105	yes	W1	Plaster	Beige	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	S15A	Stairs	Auditorium Entrance Staircase across from Classroom 105	yes	W2	Plaster	Beige	Cracking	30	12.3	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	S15A	Stairs	Auditorium Entrance Staircase across from Classroom 105	yes	W3	Plaster	Beige	Cracking	30	22.3	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	S15A	Stairs	Auditorium Entrance Staircase across from Classroom 105	yes	W4	Plaster	Beige	Cracking	30	10	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	S15A	Stairs	Auditorium Entrance Staircase across from Classroom 105	yes	Ceiling	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	S15A	Stairs	Auditorium Entrance Staircase across from Classroom 105	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	S15B	Stairs	Auditorium Entrance Staircase across from Classroom 106	yes	W1	Plaster	Beige	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	S15B	Stairs	Auditorium Entrance Staircase across from Classroom 106	yes	W2	Plaster	Beige	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	S15B	Stairs	Auditorium Entrance Staircase across from Classroom 106	yes	W3	Plaster	Beige	Cracking	30	9.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	S15B	Stairs	Auditorium Entrance Staircase across from Classroom 106	yes	W4	Plaster	Beige	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	S15B	Stairs	Auditorium Entrance Staircase across from Classroom 106	yes	Ceiling	Plaster	White	Flaking	10	10.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	S15B	Stairs	Auditorium Entrance Staircase across from Classroom 106	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	112	Auditorium	Auditorium	yes	W1	Plaster	Tan	Cracking	15	9.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	112	Auditorium	Auditorium	yes	W2	Plaster	Tan	Chipping/Cracking	30	7.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	112	Auditorium	Auditorium	yes	Door	Metal	Brown	Friction	20	0.07	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	112	Auditorium	Auditorium	yes	Door Frame	Metal	Brown	Friction	20	0.08	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	112	Auditorium	Auditorium	yes	W3	Plaster	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	112	Auditorium	Auditorium	yes	W4	Plaster	Tan	Chipping	10	19.3	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	112	Auditorium	Auditorium	yes	Door	Metal	Brown	Friction	20	0.05	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	112	Auditorium	Auditorium	yes	Door Frame	Metal	Brown	Friction	20	0.02	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	112	Auditorium	Auditorium	yes	Ceiling	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	112	Auditorium	Auditorium	yes	Floor	Wood	Varnish	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	112A	Stage	Stage	yes	W1	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	112A	Stage	Stage	yes	W2	Plaster	White	Chipping/Holes	20	19.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	112A	Stage	Stage	yes	W3	Plaster	White	Chipping/Cracking	40	10.3	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	112A	Stage	Stage	yes	W4	Plaster	White	Chipping/Cracking	40	19.3	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	112A	Stage	Stage	yes	Ceiling	Plaster	White	None	0	N/A														

Hopkinson

ULCS #	E l e m e n t	BldgElmt ID	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)	Additional Component	Substrate Material	Color	Description of Paint and Plaster Damage	Additional Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Additional Component XRF (positive/ negative)	Debris Present (describe location)	Quantity (sf)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Comments/ Description/ Notes
7300	1	B730001-1	1	112B	Storage	Stage Left Storage Room (Main Office Side)	yes	W3	Plaster	White	Moisture Damage/Efflorescence	20	21.3	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	112B	Storage	Stage Left Storage Room (Main Office Side)	yes	W4	Plaster	White	Efflorescence	20	17.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	112B	Storage	Stage Left Storage Room (Main Office Side)	yes	Ceiling	Plaster	White	Efflorescence	3	18.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	112B	Storage	Stage Left Storage Room (Main Office Side)	yes	Floor	Wood	Varnish	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	112C	Storage	Stage Right Storage Room (Classroom 110 Side)	yes	W1	Plaster	White	Cracking/Flaking	10	12.3	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Prior to Repair	No	no	
7300	1	B730001-1	1	112C	Storage	Stage Right Storage Room (Classroom 110 Side)	yes	W2	Plaster	White	Flaking/Cracking/Efflorescence	50	19.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Prior to Repair	No	no	
7300	1	B730001-1	1	112C	Storage	Stage Right Storage Room (Classroom 110 Side)	yes	W3	Plaster	White	Flaking/Cracking/Efflorescence	50	17.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Prior to Repair	No	no	
7300	1	B730001-1	1	112C	Storage	Stage Right Storage Room (Classroom 110 Side)	yes	W4	Plaster	White	Efflorescence	5	10.3	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Prior to Repair	No	no	
7300	1	B730001-1	1	112C	Storage	Stage Right Storage Room (Classroom 110 Side)	yes	Ceiling	Plaster	White	Flaking/Cacking	30	11	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	112C	Storage	Stage Right Storage Room (Classroom 110 Side)	yes	Floor	Wood	Varnish	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	112D	Administrative Office	Office 107A	yes	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	
7300	1	B730001-1	1	112D	Administrative Office	Office 107A	yes	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	
7300	1	B730001-1	1	112D	Administrative Office	Office 107A	yes	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	
7300	1	B730001-1	1	112D	Administrative Office	Office 107A	yes	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	
7300	1	B730001-1	1	112D	Administrative Office	Office 107A	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	
7300	1	B730001-1	1	112D	Administrative Office	Office 107A	yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	
7300	1	B730001-1	1	106	Primary	Classroom 106	yes	W1	Plaster	Beige	Chipping/Cracking/Staple Holes	50	21.3	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	106	Primary	Classroom 106	yes	W2	Wood	Varnish	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	partation wall
7300	1	B730001-1	1	106	Primary	Classroom 106	yes	W3	Plaster	Beige	Cracking/Chipping/Flaking	30	26.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	106	Primary	Classroom 106	yes	W4	Sheetrock	Beige	Staple Holes	10	20.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	106	Primary	Classroom 106	yes	Ceiling	Plaster	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	106	Primary	Classroom 106	yes	Floor	Wood	Varnish	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	106A	Storage	Classroom 106 Coat Room	yes	W1	Plaster	Yellow	Cracking/Chipping	50	29.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	106A	Storage	Classroom 106 Coat Room	yes	W2	Plaster	Yellow	Cracking	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	106A	Storage	Classroom 106 Coat Room	yes	W3	Plaster	Yellow	Cracking	10	12.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	106A	Storage	Classroom 106 Coat Room	yes	W4	Plaster	Yellow	Cracking/Chipping	20	10.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Partially Inaccessible	No	no	
7300	1	B730001-1	1	106A	Storage	Classroom 106 Coat Room	yes	Ceiling	Plaster	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	106A	Storage	Classroom 106 Coat Room	yes	Floor	Wood	Varnish	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	107	Primary	Classroom 107	yes	W1	Plaster	Blue/Green	Chipping/cracking/Staple Holes/Flaking	50	9.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	107	Primary	Classroom 107	yes	W2	Plaster	Blue/Green	Flaking/Cracking/Chipping	60	7.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	107	Primary	Classroom 107	yes	W3	Plaster	Blue/Green	Efflorescence/Flaking/Chipping/Cracking	60	10.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	107	Primary	Classroom 107	yes	Radiator	Metal	Silver	Alligatoring	20	0.4	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	107	Primary	Classroom 107	yes	W4	Plaster	Blue/Green	Flaking	10	16.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	107	Primary	Classroom 107	yes	Ceiling	Plaster	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	107	Primary	Classroom 107	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	107A	Storage	Classroom 107 Coat Room	yes	W1	Plaster	Blue/Green	Chipping	40	17.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	107A	Storage	Classroom 107 Coat Room	yes	W2	Plaster	Blue/Green	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	107A	Storage	Classroom 107 Coat Room	yes	W3	Plaster	Blue/Green	Chipping	40	7.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	107A	Storage	Classroom 107 Coat Room	yes	W4	Plaster	Blue/Green	Chipping	40	3.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	107A	Storage	Classroom 107 Coat Room	yes	Ceiling	Plaster	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	107A	Storage	Classroom 107 Coat Room	yes	Floor	Wood	Varnish	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	S14	Stairs	Fire Tower across from Classroom 107	yes	W1	Brick	White	Flaking	500	21.3	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	S14	Stairs	Fire Tower across from Classroom 107	yes	Door	Metal	Green	Flaking	20	26.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	S14	Stairs	Fire Tower across from Classroom 107	yes	Door Frame	Metal	Green	Flaking	20	29	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	S14	Stairs	Fire Tower across from Classroom 107	yes	W2	Brick	White	Flaking	500	17.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	S14	Stairs	Fire Tower across from Classroom 107	yes	Pipe	Metal	White	Flaking	20	2.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	S14	Stairs	Fire Tower across from Classroom 107	yes	W3	Brick	White	Flaking	500	26.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	S14	Stairs	Fire Tower across from Classroom 107	yes	Door	Metal	Grey	Flaking	20	10	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	S14	Stairs	Fire Tower across from Classroom 107	yes	Door Frame	Metal	Grey	Flaking	20	7.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	S14	Stairs	Fire Tower across from Classroom 107	yes	W4	Brick	White	Flaking	500	18.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	S14	Stairs	Fire Tower across from Classroom 107	yes	Window Safety Bars	Metal	Black	Flaking	120	26	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	S14	Stairs	Fire Tower across from Classroom 107	yes	Ceiling	Concrete	White	Flaking	1000	18.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	S14	Stairs	Fire Tower across from Classroom 107	yes	Floor	Concrete	Concrete	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
7300	1	B730001-1	1	107B	Student Restrooms - Male (4-12)	Boy's Restroom	yes	W1	Plaster	Blue	Efflorescence	5	5.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	107B	Student Restrooms - Male (4-12)	Boy's Restroom	yes	W2	Plaster	Blue	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	107B	Student Restrooms - Male (4-12)	Boy's Restroom	yes	W3	Plaster	Blue	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	107B	Student Restrooms - Male (4-12)	Boy's Restroom	yes	W4	Plaster	Blue	Cracking/Flaking	50	16.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	107B	Student Restrooms - Male (4-12)	Boy's Restroom	yes	Ceiling	Plaster	White	Moisture Damage	30	17.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	107B	Student Restrooms - Male (4-12)	Boy's Restroom	yes	Floor	Concrete	Grey	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	107B	Student Restrooms - Male (4-12)	Boy's Restroom	yes	W1	Plaster	Beige	Flaking/Efflorescence/ Cracking	50	17.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	H15	Circulation (Hallway)	Hallway from Classrooms 104 to 107	yes	W2	Plaster	Beige	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-																									

Hopkinson

ULCS #	Element	BldgElmt ID	Floor	Space #	Space Type	On-Site Room Name	Student/Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/negative)	Additional Component	Substrate Material	Color	Description of Paint and Plaster Damage	Additional Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Additional Component XRF (positive/negative)	Debris Present (describe location)	Quantity (sf)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Comments/ Description/ Notes
7300	1	B730001-1	1	H15	Circulation (Hallway)	Hallway from Classrooms 104 to 107	yes	W4	Plaster	Beige	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	H15	Circulation (Hallway)	Hallway from Classrooms 104 to 107	yes	Door	Metal	Brown	Friction	10	6.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	H15	Circulation (Hallway)	Hallway from Classrooms 104 to 107	yes	Door Frame	Metal	Brown	Friction	10	6.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	H15	Circulation (Hallway)	Hallway from Classrooms 104 to 107	yes	Radiator	Metal	Silver	Alligatoring	30	0.05	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	H15	Circulation (Hallway)	Hallway from Classrooms 104 to 107	yes	Pipe	Metal	Brown	Chipping	24	13.3	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	H15	Circulation (Hallway)	Hallway from Classrooms 104 to 107	yes	Electrical Panel	Metal	Brown	Chiooing	5	0.26	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	H15	Circulation (Hallway)	Hallway from Classrooms 104 to 107	yes	W4	Plaster	Beige	Cracking	40	15.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	H15	Circulation (Hallway)	Hallway from Classrooms 104 to 107	yes	Ceiling	Plaster	White	Flaking	20	14.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	H15	Circulation (Hallway)	Hallway from Classrooms 104 to 107	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	S11	Stairs	Stairwell next to Classroom 108	yes	W1	Plaster	White	Flaking	10	15.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	S11	Stairs	Stairwell next to Classroom 108	yes	Door	Metal	Brown	Friction	20	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	S11	Stairs	Stairwell next to Classroom 108	yes	Door Frame	Metal	Brown	Friction	20	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	S11	Stairs	Stairwell next to Classroom 108	yes	W2	Plaster	White	Flaking/Cracking	40	14.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	S11	Stairs	Stairwell next to Classroom 108	yes	W3	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	S11	Stairs	Stairwell next to Classroom 108	yes	Door	Metal	Brown	Friction	20	6.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	S11	Stairs	Stairwell next to Classroom 108	yes	Door Frame	Metal	Brown	Friction	20	0.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	S11	Stairs	Stairwell next to Classroom 108	yes	W4	Plaster	White	Moisture	10	16.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	S11	Stairs	Stairwell next to Classroom 108	yes	Ceiling	Plaster	White	Cracking	20	24.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	S11	Stairs	Stairwell next to Classroom 108	yes	Floor	Concrete	Grey	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	S11	Stairs	Stairwell next to Classroom 108	yes	Tread	Concrete	Grey	Friction	20	3.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	S11	Stairs	Stairwell next to Classroom 108	yes	Stringer	Concrete	Grey	Friction	10	0.25	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	S11	Stairs	Stairwell next to Classroom 108	yes	Riser	Concrete	Grey	Friction	10	14.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	S11	Stairs	Stairwell next to Classroom 108	yes	Ballast	Metal	Brown	Friction	20	0.4	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	S11	Stairs	Stairwell next to Classroom 108	yes	Newel Post	Metal	Grey	Friction	20	11.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	S11	Stairs	Stairwell next to Classroom 108	yes	Handrail	Metal	Brown	Friction	10	0.18	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	108	Primary	Classroom 108	yes	W1	Plaster	Beige	Chipping/Cracking	20	14.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	108	Primary	Classroom 108	yes	W2	Plaster	Beige	Chipping/Cracking	20	9.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	108	Primary	Classroom 108	yes	W3	Plaster	Beige	Chipping/Cracking/Flaking	40	5.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	damage behind radiator
7300	1	B730001-1	1	108	Primary	Classroom 108	yes	W4	Plaster	Beige	Chipping/Flaking	50	16.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	108	Primary	Classroom 108	yes	Ceiling	Plaster	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	108	Primary	Classroom 108	yes	Floor	Wood	Varnish	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	108B	Student Restrooms - Male/Female (Classroom)	Classroom 108 Restroom	yes	W1		White	Cracking/Flaking	10	11.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	108B	Student Restrooms - Male/Female (Classroom)	Classroom 108 Restroom	yes	W2	Plaster	White	Efflorescence/Moisture Damage	15	9.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	108B	Student Restrooms - Male/Female (Classroom)	Classroom 108 Restroom	yes	Pipe	Metal	White	Chipping	5	0.02	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	108B	Student Restrooms - Male/Female (Classroom)	Classroom 108 Restroom	yes	Radiator	Metal	Silver	Alligatoring	10	0.08	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	108B	Student Restrooms - Male/Female (Classroom)	Classroom 108 Restroom	yes	W3	Plaster	White	Flaking/Chipping	20	15	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	108B	Student Restrooms - Male/Female (Classroom)	Classroom 108 Restroom	yes	W4	Sheetrock	White	Moisture Damage/Cracking	10	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	108B	Student Restrooms - Male/Female (Classroom)	Classroom 108 Restroom	yes	Ceiling	Plaster	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	108B	Student Restrooms - Male/Female (Classroom)	Classroom 108 Restroom	yes	Floor	Ceramic Tile	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	108A	Storage	Classroom 108 Coat Room	yes	W1	Plaster	Yellow	Cracking	20	16.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	108A	Storage	Classroom 108 Coat Room	yes	W2	Plaster	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	108A	Storage	Classroom 108 Coat Room	yes	W3	Plaster	Yellow	Cracking	20	9.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	108A	Storage	Classroom 108 Coat Room	yes	W4	Plaster	Yellow	Cracking	20	4.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	108A	Storage	Classroom 108 Coat Room	yes	Ceiling	Plaster	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	108A	Storage	Classroom 108 Coat Room	yes	Floor	Wood	Varnish	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	109	Primary	Classroom 109	yes	W1	Plaster	Beige	Cracking/Holes	40	12.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	109	Primary	Classroom 109	yes	W2	Plaster	Beige	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	109	Primary	Classroom 109	yes	W3	Plaster	Beige	Flaking/Chipping/Cracking	50	18.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	109	Primary	Classroom 109	yes	Radiator	Metal	Silver	Alligatoring	30	0.08	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	109	Primary	Classroom 109	yes	W4	Plaster	Beige	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	109	Primary	Classroom 109	yes	Ceiling	Plaster	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	109	Primary	Classroom 109	yes	Floor	Wood	Varnish	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	109A	Storage	Classroom 109 Coat Room	yes	W1	Plaster	Blue	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	109A	Storage	Classroom 109 Coat Room	yes	W2	Plaster	Blue	Cracking/Chipping	40	15.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Prior to Repair	No	no	
7300	1	B730001-1	1	109A	Storage	Classroom 109 Coat Room	yes	W3	Plaster	Blue	Cracking	10	14.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Prior to Repair	No	no	
7300	1	B730001-1	1	109A	Storage	Classroom 109 Coat Room	yes	W4	Plaster	Blue	Cracking/Chipping	30	19.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Prior to Repair	No	no	
7300	1	B730001-1	1	109A	Storage	Classroom 109 Coat Room	yes	Ceiling	Plaster	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	109A	Storage	Classroom 109 Coat Room	yes	Floor	Wood	Varnish	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	110	Primary	Classroom 110	yes	W1	Plaster	Beige	Chipping/Cracking	40	6.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Prior to Repair	No	no	
7300	1	B730001-1	1	110	Primary	Classroom 110	yes	W2	Plaster	Beige	Chipping	30	4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Prior to Repair	No	no	
7300	1	B730001-1	1	110	Primary	Classroom 110	yes	W3	Plaster	Beige	Flaking/Chipping/Cracking	60	17.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Prior to Repair	No	no	flaking behind radiator
7300	1	B730001-1	1	110	Primary	Classroom 110	yes	W4	Plaster	Beige	Hole/Cracking	20															

Hopkinson

ULCS #	Element	BldgElmt ID	Floor	Space #	Space Type	On-Site Room Name	Student/Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/negative)	Additional Component	Substrate Material	Color	Description of Paint and Plaster Damage	Additional Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Additional Component XRF (positive/negative)	Debris Present (describe location)	Quantity (sf)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Comments/ Description/ Notes	
7300	1	B730001-1	1	110	Primary	Classroom 110	yes	Ceiling	Plaster	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	110	Primary	Classroom 110	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	110A	Storage	Classroom 110 Coat Room	yes	W1	Plaster	Beige	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	110A	Storage	Classroom 110 Coat Room	yes	W2	Plaster	Beige	Flaking/Chipping	50	16.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	110A	Storage	Classroom 110 Coat Room	yes	W3	Plaster	Beige	Flaking/Chipping/Cracking	50	16.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	110A	Storage	Classroom 110 Coat Room	yes	W4	Plaster	Beige	Chipping	5	9.3	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Partially Inaccessible	No	no	
7300	1	B730001-1	1	110A	Storage	Classroom 110 Coat Room	yes	Ceiling	Plaster	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	110A	Storage	Classroom 110 Coat Room	yes	Floor	Wood	Varnish	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	111	Restrooms, Staff - Male	Men's Restroom	yes	W1	Plaster	Beige	Cracking	20	10.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	111	Restrooms, Staff - Male	Men's Restroom	yes	W2	Plaster	Beige	Cracking	20	13.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	111	Restrooms, Staff - Male	Men's Restroom	yes	W3	Plaster	Beige	Cracking	20	11.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	111	Restrooms, Staff - Male	Men's Restroom	yes	W4	Plaster	Beige	Cracking	20	15	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	111	Restrooms, Staff - Male	Men's Restroom	yes	Ceiling	Plaster	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	111	Restrooms, Staff - Male	Men's Restroom	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	H16	Circulation (Hallway)	Hallway from Classrooms 108 to 110	yes	W1	Plaster	Beige	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	H16	Circulation (Hallway)	Hallway from Classrooms 108 to 110	yes	Door	Metal	Brown	Friction	20	6.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	H16	Circulation (Hallway)	Hallway from Classrooms 108 to 110	yes	Door Frame	Metal	Brown	Friction	20	4.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	H16	Circulation (Hallway)	Hallway from Classrooms 108 to 110	yes	W2	Plaster	Beige	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	H16	Circulation (Hallway)	Hallway from Classrooms 108 to 110	yes	Pipe	Metal	Brown	Chipping/Flaking	8	8.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	H16	Circulation (Hallway)	Hallway from Classrooms 108 to 110	yes	Radiator	Metal	Silver	Alligatoring	10	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	H16	Circulation (Hallway)	Hallway from Classrooms 108 to 110	yes	W3	Plaster	Beige	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	H16	Circulation (Hallway)	Hallway from Classrooms 108 to 110	yes	W4	Plaster	Beige	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	H16	Circulation (Hallway)	Hallway from Classrooms 108 to 110	yes	Ceiling	Plaster	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	H16	Circulation (Hallway)	Hallway from Classrooms 108 to 110	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	S17	Stairs	Stairwell outside Classroom 110	yes	W1	Plaster	Beige	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	S17	Stairs	Stairwell outside Classroom 110	yes	W2	Plaster	Beige	Cracking/Flaking	20	28.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	S17	Stairs	Stairwell outside Classroom 110	yes	W3	Plaster	Beige	Cracking/Flaking	20	26	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	S17	Stairs	Stairwell outside Classroom 110	yes	W4	Plaster	Beige	Cracking/Flaking	5	16.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	S17	Stairs	Stairwell outside Classroom 110	yes	Ceiling	Plaster	Beige	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	S17	Stairs	Stairwell outside Classroom 110	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	S17	Stairs	Stairwell outside Classroom 110	yes	Tread	Concrete	N/A	Friction	20	0.03	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	S17	Stairs	Stairwell outside Classroom 110	yes	Riser	Concrete	Grey	Friction	10	2.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	S17	Stairs	Stairwell outside Classroom 110	yes	Stringer	Concrete	Grey	Friction	10	20	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	S17	Stairs	Stairwell outside Classroom 110	yes	Ballast	Metal	Brown	Friction	10	0.3	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	1	S17	Stairs	Stairwell outside Classroom 110	yes	Newel Post	Metal	Brown	Friction	6	2.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	2	213	Teacher Lounge/Dining	Teacher's Lounge	yes	W1	Plaster	Green	Friction	20	18	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Partially Inaccessible	No	no	
7300	1	B730001-1	2	213	Teacher Lounge/Dining	Teacher's Lounge	yes	Door	Wood	Brown	Friction	10	0.06	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	2	213	Teacher Lounge/Dining	Teacher's Lounge	yes	Door Frame	Wood	Brown	Friction	10	0.03	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	2	213	Teacher Lounge/Dining	Teacher's Lounge	yes	W2	Plaster	Green	Holes	5	17.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Partially Inaccessible	No	no	
7300	1	B730001-1	2	213	Teacher Lounge/Dining	Teacher's Lounge	yes	door	Wood	Brown	Friction	10	0.03	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	2	213	Teacher Lounge/Dining	Teacher's Lounge	yes	door frame	Wood	Brown	Friction	10	0.04	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	2	213	Teacher Lounge/Dining	Teacher's Lounge	yes	W3	Plaster	Green	Efflorescence	10	16.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Partially Inaccessible	No	no	
7300	1	B730001-1	2	213	Teacher Lounge/Dining	Teacher's Lounge	yes	window sill	Wood	Brown	Friction	10	1.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	2	213	Teacher Lounge/Dining	Teacher's Lounge	yes	W4	Plaster	Green	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Partially Inaccessible	No	no	
7300	1	B730001-1	2	213	Teacher Lounge/Dining	Teacher's Lounge	yes	door frame	Wood	Brown	Friction	10	0.03	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	2	213	Teacher Lounge/Dining	Teacher's Lounge	yes	Ceiling	Plaster	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	2	213	Teacher Lounge/Dining	Teacher's Lounge	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	2	213A	Storage	Teacher's Lounge Closet	no	W1	Plaster	Green	Flaking	60	16.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Prior to Repair	No	no	
7300	1	B730001-1	2	213A	Storage	Teacher's Lounge Closet	no	W2	Plaster	Green	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Prior to Repair	No	no	
7300	1	B730001-1	2	213A	Storage	Teacher's Lounge Closet	no	Door Frame	Wood	Brown	Friction	10	0.02	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	2	213A	Storage	Teacher's Lounge Closet	no	W3	Plaster	Green	Flaking	40	11	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Prior to Repair	No	no	
7300	1	B730001-1	2	213A	Storage	Teacher's Lounge Closet	no	W4	Plaster	Green	Flaking	60	19.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Prior to Repair	No	no	
7300	1	B730001-1	2	213A	Storage	Teacher's Lounge Closet	no	Ceiling	Plaster	White	Flaking	100	10.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	2	213A	Storage	Teacher's Lounge Closet	no	Floor	Wood	Varnish	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	2	214A	Restrooms, Staff - Female	Women's Restroom adjacent to Teacher's Lounge	yes	W1	Plaster	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Prior to Repair	No	no	
7300	1	B730001-1	2	214A	Restrooms, Staff - Female	Women's Restroom adjacent to Teacher's Lounge	yes	W2	Plaster	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Prior to Repair	No	no	
7300	1	B730001-1	2	214A	Restrooms, Staff - Female	Women's Restroom adjacent to Teacher's Lounge	yes	pipe	Metal	Yellow	Moisture Damage, flaking	5	11.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730003-1	2	214A	Restrooms, Staff - Female	Women's Restroom adjacent to Teacher's Lounge	yes	Stall Doors	Wood	Brown	Friction	20	11.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	2	214A	Restrooms, Staff - Female	Women's Restroom adjacent to Teacher's Lounge	yes	W3	Plaster	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Prior to Repair	No	no	
7300	1	B730001-1	2	214A	Restrooms, Staff - Female	Women's Restroom adjacent to Teacher's Lounge	yes	W4	Plaster	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Prior to Repair	No	no	
7300	1	B730001-1	2	214A	Restrooms, Staff - Female																							

Hopkinson

ULCS #	E l e m e n t	BldgElmt ID	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)	Additional Component	Substrate Material	Color	Description of Paint and Plaster Damage	Additional Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Additional Component XRF (positive/ negative)	Debris Present (describe location)	Quantity (sf)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Comments/ Description/ Notes
7300	1	B730001-1	2	214A	Restrooms, Staff	Women's Restroom adjacent to Teacher's Lounge																None	0	No	No	no	floor tile
7300	1	B730001-1	2	214	Administrative Office	Counselor's Office 214	yes	W1	Plaster	Yellow	Chipping	20	12.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Partially Inaccessible	No	no	
7300	1	B730001-1	2	214	Administrative Office	Counselor's Office 214	yes	door	Wood	Brown	Friction	5	11.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	2	214	Administrative Office	Counselor's Office 214	yes	door frame	Wood	Brown	Friction	5	9.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	2	214	Administrative Office	Counselor's Office 214	yes	W2	Plaster	Yellow	Efflorescence, flaking	40	yes	10	Positive	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Partially Inaccessible	No	no	
7300	1	B730001-1	2	214	Administrative Office	Counselor's Office 214	yes	hutch	Wood	Yellow	Friction, chipping	20	3.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	2	214	Administrative Office	Counselor's Office 214	yes	W3	Plaster	Yellow	Chipping	20	16.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Partially Inaccessible	No	no	
7300	1	B730001-1	2	214	Administrative Office	Counselor's Office 214	yes	W4	Plaster	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Partially Inaccessible	No	no	
7300	1	B730001-1	2	214	Administrative Office	Counselor's Office 214	yes	Ceiling	Plaster	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	2	214	Administrative Office	Counselor's Office 214	yes	Floor	Wood	varnish	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	2	200	Health Service Room	Nurse's Office	yes	W1	Plaster	Green	chipping, cracking	5	17.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Prior to Repair	No	no	
7300	1	B730001-1	2	200	Health Service Room	Nurse's Office	yes	door	Wood	Brown	Friction	10	20.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	2	200	Health Service Room	Nurse's Office	yes	door frame	Wood	Brown	Friction	10	7.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	2	200	Health Service Room	Nurse's Office	yes	W2	Plaster	Green	chipping, flaking	100	13.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Prior to Repair	No	no	
7300	1	B730001-1	2	200	Health Service Room	Nurse's Office	yes	door	Wood	Brown	Friction	10	10.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	2	200	Health Service Room	Nurse's Office	yes	door frame	Wood	Brown	Friction	10	11.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	2	200	Health Service Room	Nurse's Office	yes	Hutch	Wood	Brown	Friction	20	11.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	2	200	Health Service Room	Nurse's Office	yes	W3	Plaster	Green	Efflorescence, spalling, flaking	60	14.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Prior to Repair	No	no	
7300	1	B730001-1	2	200	Health Service Room	Nurse's Office	yes	W4	Plaster	Green	Flaking	100	17.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Prior to Repair	No	no	
7300	1	B730001-1	2	200	Health Service Room	Nurse's Office	yes	Ceiling	Plaster	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	2	200	Health Service Room	Nurse's Office	yes	Floor	Wood	varnish	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	2	200A	Student Restrooms - Male/Female (Classroom)	Nurse's Restroom	yes	W1	Plaster	Green	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Prior to Repair	No	no	
7300	1	B730001-1	2	200A	Student Restrooms - Male/Female (Classroom)	Nurse's Restroom	yes	W2	Plaster	Green	Efflorescence, flaking	40	7.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Prior to Repair	No	no	
7300	1	B730001-1	2	200A	Student Restrooms - Male/Female (Classroom)	Nurse's Restroom	yes	W3	Plaster	Green	Efflorescence	10	9.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Prior to Repair	No	no	
7300	1	B730001-1	2	200A	Student Restrooms - Male/Female (Classroom)	Nurse's Restroom	yes	W4	Plaster	Green	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Prior to Repair	No	no	
7300	1	B730001-1	2	200A	Student Restrooms - Male/Female (Classroom)	Nurse's Restroom	yes	Ceiling	Plaster	Green	Efflorescence	5	8.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	2	200A	Student Restrooms - Male/Female (Classroom)	Nurse's Restroom	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	floor tile
7300	1	B730001-1	2	201	Primary Classroom 201	Classroom 201	yes	W1	Plaster	Beige	cracking, chipping	20	23.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Prior to Repair	No	no	
7300	1	B730001-1	2	201	Primary Classroom 201	Classroom 201	yes	W2	Plaster	Beige	chipping, holes	10	20	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Prior to Repair	No	no	
7300	1	B730001-1	2	201	Primary Classroom 201	Classroom 201	yes	W3	Plaster	Beige	chipping, flaking,	100	10.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Prior to Repair	No	no	
7300	1	B730001-1	2	201	Primary Classroom 201	Classroom 201	yes	W4	Plaster	Beige	Efflorescence, flaking	100	10	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Prior to Repair	No	no	
7300	1	B730001-1	2	201	Primary Classroom 201	Classroom 201	yes	Ceiling	Plaster	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	2	201	Primary Classroom 201	Classroom 201	yes	Floor	Wood	varnish	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	2	201A	Storage Classroom 201 Coat Room	Classroom 201 Coat Room	yes	W1	Plaster	Blue	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Prior to Repair	No	no	
7300	1	B730001-1	2	201A	Storage Classroom 201 Coat Room	Classroom 201 Coat Room	yes	W2	Plaster	Blue	flaking, chipping	200	2.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Prior to Repair	No	no	
7300	1	B730001-1	2	201A	Storage Classroom 201 Coat Room	Classroom 201 Coat Room	yes	W3	Plaster	Blue	Flaking	100	12.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Prior to Repair	No	no	
7300	1	B730001-1	2	201A	Storage Classroom 201 Coat Room	Classroom 201 Coat Room	yes	radiator	Metal	silver	Flaking	30	0.02	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	2	201A	Storage Classroom 201 Coat Room	Classroom 201 Coat Room	yes	W4	Plaster	Blue	flaking, cracking	100	12.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Prior to Repair	No	no	
7300	1	B730001-1	2	201A	Storage Classroom 201 Coat Room	Classroom 201 Coat Room	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	2	201A	Storage Classroom 201 Coat Room	Classroom 201 Coat Room	yes	Floor	Wood	varnish	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	2	202	Primary Classroom 202	Classroom 202	yes	W1	Plaster	Beige	chipping, holes	30	20.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Prior to Repair	No	no	
7300	1	B730001-1	2	202	Primary Classroom 202	Classroom 202	yes	W2	Plaster	Beige	holes, cracking	30	17.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Prior to Repair	No	no	
7300	1	B730001-1	2	202	Primary Classroom 202	Classroom 202	yes	W3	Plaster	Beige	Spalling	20	21.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Prior to Repair	No	yes	Behind radiator
7300	1	B730001-1	2	202	Primary Classroom 202	Classroom 202	yes	radiator	Silver	Aligatoring	30	0.03	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	2	202	Primary Classroom 202	Classroom 202	yes	W4	Plaster	Beige	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Prior to Repair	No	no	
7300	1	B730001-1	2	202	Primary Classroom 202	Classroom 202	yes	Ceiling	Plaster	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	2	202	Primary Classroom 202	Classroom 202	yes	Floor	Wood	varnish	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	2	202A	Storage Classroom 202 Coat Room	Classroom 202 Coat Room	yes	W1	Plaster	Blue	Chipping	10	20.3	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Prior to Repair	No	no	
7300	1	B730001-1	2	202A	Storage Classroom 202 Coat Room	Classroom 202 Coat Room	yes	W2	Plaster	Blue	holes, chipping	50	19.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Prior to Repair	No	yes	
7300	1	B730001-1	2	202A	Storage Classroom 202 Coat Room	Classroom 202 Coat Room	yes	W3	Plaster	Blue	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Prior to Repair	No	no	
7300	1	B730001-1	2	202A	Storage Classroom 202 Coat Room	Classroom 202 Coat Room	yes	W4	Plaster	Blue	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Prior to Repair	No	no	
7300	1	B730001-1	2	202A	Storage Classroom 202 Coat Room	Classroom 202 Coat Room	yes	Ceiling	Plaster	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	2	202A	Storage Classroom 202 Coat Room	Classroom 202 Coat Room	yes	Floor	Wood	varnish	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	2	203	Primary Classroom 203	Classroom 203	yes	W1	Plaster	Beige	chipping, holes	30	14.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Prior to Repair	No	no	
7300	1	B730001-1	2	203	Primary Classroom 203	Classroom 203	yes	W2	Plaster	Beige	Holes, flaking, cracking	60	15	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Prior to Repair	No	no	
7300	1	B730001-1	2	203	Primary Classroom 203	Classroom 203	yes	W3	Plaster	Beige	Holes, flaking	30	15.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Prior to Repair	No	no	Flaking behind the radiator.
7300	1	B730001-1	2	203	Primary Classroom 203	Classroom 203	yes	W4	Plaster	Beige	Holes	50	14.3	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Prior to Repair	No	no	
7300	1	B730001-1	2	203	Primary Classroom 203	Classroom 203	yes	Ceiling	Plaster	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	2	203	Primary Classroom 203	Classroom 203	yes	Floor	Wood	varnish	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	

Hopkinson

ULCS #	E l e m e n t	BldgID ID	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)	Additional Component	Substrate Material	Color	Description of Paint and Plaster Damage	Additional Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Additional Component XRF (positive/ negative)	Debris Present (describe location)	Quantity (sf)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Comments/ Description/ Notes
7300	1	B730001-1	2	203A	Storage	Classroom 203 Storage	yes	W1	Plaster	Blue	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Partially Inaccessible	No	no	
7300	1	B730001-1	2	203A	Storage	Classroom 203 Storage	yes	W2	Plaster	Blue	Cracking	30	19.5	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Prior to Repair	No	no	
7300	1	B730001-1	2	203A	Storage	Classroom 203 Storage	yes	W3	Plaster	Blue	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Prior to Repair	No	no	
7300	1	B730001-1	2	203A	Storage	Classroom 203 Storage	yes	W4	Plaster	Blue	Cracking	30	11.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Prior to Repair	No	no	
7300	1	B730001-1	2	203A	Storage	Classroom 203 Storage	yes	Ceiling	Plaster	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	2	203A	Storage	Classroom 203 Storage	yes	Floor	Wood	varnish	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	2	S22	Stairs	Stairwell next to Classroom 203	yes	W1	Plaster	White	Flaking	20	10.3	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Prior to Repair	No	no	
7300	1	B730001-1	2	S22	Stairs	Stairwell next to Classroom 203	yes	W2	Plaster	White	Chipping	10	24.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Prior to Repair	No	no	
7300	1	B730001-1	2	S22	Stairs	Stairwell next to Classroom 203	yes	W3	Plaster	White	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Prior to Repair	No	no	
7300	1	B730001-1	2	S22	Stairs	Stairwell next to Classroom 203	yes	Door	Metal	Brown	Friction	10	1.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	2	S22	Stairs	Stairwell next to Classroom 203	yes	Door Frame	Metal	Brown	Friction	10	3.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	2	S22	Stairs	Stairwell next to Classroom 203	yes	W4	Plaster	White	Cracking	20	14.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Prior to Repair	No	no	
7300	1	B730001-1	2	S22	Stairs	Stairwell next to Classroom 203	yes	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	2	S22	Stairs	Stairwell next to Classroom 203	yes	Floor	Concrete	Grey	Friction	100	0.23	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	2	S22	Stairs	Stairwell next to Classroom 203	yes	Newel Posts	Metal	Grey	Friction	20	2.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	2	S22	Stairs	Stairwell next to Classroom 203	yes	Ballast	Metal	Grey	Friction	40	0.24	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	2	S22	Stairs	Stairwell next to Classroom 203	yes	Handrail	Metal	Grey	Friction	10	0.2	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	2	H29	Circulation (Hallway)	Hallway from Classroom 201 to 203	yes	W1	Plaster	Beige	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Prior to Repair	No	no	
7300	1	B730001-1	2	H29	Circulation (Hallway)	Hallway from Classroom 201 to 203	yes	door	Metal	Brown	Friction	20	1.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	2	H29	Circulation (Hallway)	Hallway from Classroom 201 to 203	yes	door frame	Metal	Brown	Friction	20	2.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	2	H29	Circulation (Hallway)	Hallway from Classroom 201 to 203	yes	W2	Plaster	Beige	Chipping	20	14.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Prior to Repair	No	no	
7300	1	B730001-1	2	H29	Circulation (Hallway)	Hallway from Classroom 201 to 203	yes	W3	Plaster	Beige	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Prior to Repair	No	no	
7300	1	B730001-1	2	H29	Circulation (Hallway)	Hallway from Classroom 201 to 203	yes	W4	Plaster	Beige	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Prior to Repair	No	no	
7300	1	B730001-1	2	H29	Circulation (Hallway)	Hallway from Classroom 201 to 203	yes	Ceiling	Plaster	N/a	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	2	H29	Circulation (Hallway)	Hallway from Classroom 201 to 203	yes	Floor	Concrete	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	2	203B	Student Restrooms - Female (4-12)	Girl's Restroom	yes	W1	Plaster	Pink	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Prior to Repair	No	no	
7300	1	B730001-1	2	203B	Student Restrooms - Female (4-12)	Girl's Restroom	yes	W2	Plaster	Pink	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Prior to Repair	No	no	
7300	1	B730003-1	2	203B	Student Restrooms - Female (4-12)	Girl's Restroom	yes	Pipe	Metal	Pink	Friction	5	6.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	2	203B	Student Restrooms - Female (4-12)	Girl's Restroom	yes	W3	Plaster	Pink	Chipping	5	7.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	2	203B	Student Restrooms - Female (4-12)	Girl's Restroom	yes	W4	Plaster	Pink	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Prior to Repair	No	no	
7300	1	B730001-1	2	203B	Student Restrooms - Female (4-12)	Girl's Restroom	yes	Ceiling	Plaster	White	Moisture Damage, Flaking	10	10	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	2	203B	Student Restrooms - Female (4-12)	Girl's Restroom	yes	Floor	Concrete	Grey	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	2	204	Primary	Classroom 204	yes	W1	Plaster	Beige	Chipping/Staple Holes	30	23.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Prior to Repair	No	no	
7300	1	B730001-1	2	204	Primary	Classroom 204	yes	W2	Wood	Varnish	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	Partation Wall
7300	1	B730001-1	2	204	Primary	Classroom 204	yes	W3	Plaster	Beige	Moisture Damage/Cracking/Stap le Holes	50	26.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Prior to Repair	No	no	
7300	1	B730001-1	2	204	Primary	Classroom 204	yes	W4	Plaster	Beige	Chipping	20	20	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Prior to Repair	No	no	
7300	1	B730001-1	2	204	Primary	Classroom 204	yes	Ceiling	Plaster	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	2	204	Primary	Classroom 204	yes	Floor	Wood	Varnish	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	2	204A	Storage	Classroom 204 Coat Room	yes	W1	Plaster	Beige	Cracking	20	7.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Prior to Repair	No	no	
7300	1	B730001-1	2	204A	Storage	Classroom 204 Coat Room	yes	W2	Plaster	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Prior to Repair	No	no	
7300	1	B730001-1	2	204A	Storage	Classroom 204 Coat Room	yes	W3	Plaster	Beige	Spalling	20	4.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Prior to Repair	No	yes	
7300	1	B730001-1	2	204A	Storage	Classroom 204 Coat Room	yes	W4	Plaster	Beige	Cracking	20	2.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Partially Inaccessible	No	no	
7300	1	B730001-1	2	204A	Storage	Classroom 204 Coat Room	yes	Ceiling	Plaster	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	2	204A	Storage	Classroom 204 Coat Room	yes	Floor	Wood	Varnish	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	2	205	Primary	Classroom 205	yes	W1	Plaster	Beige	Holes/Chipping	40	19.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Prior to Repair	No	no	damage behind red poster on wall adjacent to wall #2; according to teacher
7300	1	B730001-1	2	205	Primary	Classroom 205	yes	W2	Wood	Varnish	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	2	205	Primary	Classroom 205	yes	W3	Plaster	N/A	Flaking/Chipping	20	11.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Prior to Repair	No	no	
7300	1	B730003-1	2	205	Primary	Classroom 205	yes	Radiator	Metal	Silver	Alligatoring	20	0.01	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	2	205	Primary	Classroom 205	yes	W4	Wood	Varnish	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	partation wall
7300	1	B730001-1	2	205	Primary	Classroom 205	yes	Ceiling	Plaster	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	2	205	Primary	Classroom 205	yes	Floor	Wood	Varnish	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	2	205A	Storage	Classroom 205 Coat Room	yes	W1	Plaster	Beige	Chipping	5	8.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Prior to Repair	No	no	
7300	1	B730001-1	2	205A	Storage	Classroom 205 Coat Room	yes	W2	Plaster	Beige	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Prior to Repair	No	no	
7300	1	B730001-1	2	205A	Storage	Classroom 205 Coat Room	yes	W3	Plaster	Beige	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Partially Inaccessible	No	no	walls covered by tall filing cabinets
7300	1	B730001-1	2	205A	Storage	Classroom 205 Coat Room	yes	W4	Plaster	Beige	Cracking	10	12.3	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	2	205A	Storage	Classroom 205 Coat Room	yes	Ceiling	Plaster	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	2	205A	Storage	Classroom 205 Coat Room	yes	Floor	Wood	Varnish	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	2	206	Primary	Classroom 206	yes	W1	Plaster	Beige	Chipping	20	19.3	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Prior to Repair	No	no	
7300	1	B730001-1	2	206	Primary	Classroom 206	yes	W2	Wood	Varnish	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	partation wall
7300	1	B730001-1	2	206	Primary	Classroom 206	yes	W3	Plaster	Beige	Chipping/Flaking	30	20	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Prior to Repair	No	no	flaking behind radiator
7300	1	B730003-1	2	206	Primary	Classroom 206	yes	Raiator	Metal	Silver	Alligatoring	20	0.05	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001																									

Hopkinson

ULCS #	E l e m e n t	BldgElmt ID	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)	Additional Component	Substrate Material	Color	Description of Paint and Plaster Damage	Additional Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Additional Component XRF (positive/ negative)	Debris Present (describe location)	Quantity (sf)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Comments/ Description/ Notes
7300	1	B730001-1	2	206A	Storage	Classroom 206 Coat Room	yes	W4	Plaster	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Partially Inaccessible	No	no	metal filling cabinet covering wall
7300	1	B730001-1	2	206A	Storage	Classroom 206 Coat Room	yes	Ceiling	Plaster	White	Flaking	15	10	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	2	206A	Storage	Classroom 206 Coat Room	yes	Floor	Wood	Varnish	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	2	207	Primary	Classroom 207	yes	W1	Plaster	Beige	Chipping/Cracking/Holes	50	20	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Prior to Repair	No	no	
7300	1	B730001-1	2	207	Primary	Classroom 207	yes	W2	Plaster	Beige	Moisture Damage/Flaking/Staple Holes	50	23.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Prior to Repair	No	no	
7300	1	B730001-1	2	207	Primary	Classroom 207	yes	W3	Plaster	Beige	Flaking/Chipping/Efflorescence	35	21	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Prior to Repair	No	no	flaking behind radiator
7300	1	B730003-1	2	207	Primary	Classroom 207	yes	Radiator	Metal	Silver	Alligatoring	10	0.08	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	2	207	Primary	Classroom 207	yes	W4	Wood	Varnish	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	parlation wall
7300	1	B730001-1	2	207	Primary	Classroom 207	yes	Ceiling	Plaster	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	2	207	Primary	Classroom 207	yes	Floor	Wood	Varnish	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	2	207A	Storage	Classroom 207 Coat Room	yes	W1	Plaster	Green	Cracking/Chipping/Holes	60	12	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Prior to Repair	No	no	
7300	1	B730001-1	2	207A	Storage	Classroom 207 Coat Room	yes	W2	Plaster	Green	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Prior to Repair	No	no	
7300	1	B730001-1	2	207A	Storage	Classroom 207 Coat Room	yes	W3	Plaster	Green	Cracking/Flaking	40	11.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Prior to Repair	No	no	
7300	1	B730003-1	2	207A	Storage	Classroom 207 Coat Room	yes	Pipe	Metal	Green	Flaking	12	0.11	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	2	207A	Storage	Classroom 207 Coat Room	yes	W4	Plaster	Green	Cracking/Flaking	40	9.3	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Prior to Repair	No	no	
7300	1	B730001-1	2	207A	Storage	Classroom 207 Coat Room	yes	Ceiling	Plaster	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	2	207A	Storage	Classroom 207 Coat Room	yes	Floor	Wood	Varnish	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	2	211	Telecommunications on Equipment Room	Telephone Room 211	no	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	None	0	No	No	no	
7300	1	B730001-1	2	211	Telecommunications on Equipment Room	Telephone Room 211	no	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	None	0	No	No	no	
7300	1	B730001-1	2	211	Telecommunications on Equipment Room	Telephone Room 211	no	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	None	0	No	No	no	
7300	1	B730001-1	2	211	Telecommunications on Equipment Room	Telephone Room 211	no	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	None	0	No	No	no	
7300	1	B730001-1	2	211	Telecommunications on Equipment Room	Telephone Room 211	no	Ceiling	Plaster	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	2	211	Telecommunications on Equipment Room	Telephone Room 211	no	Floor	Concrete	Varnish	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	2	S24	Stairs	Fire Tower across from Classroom 207	no	W1	Brick	White	Flaking	500	7.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730003-1	2	S24	Stairs	Fire Tower across from Classroom 207	yes	Door	Metal	Green	Flaking	20	7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	2	S24	Stairs	Fire Tower across from Classroom 207	no	Door Frame	Metal	Green	Flaking	20	8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730003-1	2	S24	Stairs	Fire Tower across from Classroom 207	yes	W2	Brick	White	Flaking	500	15.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730003-1	2	S24	Stairs	Fire Tower across from Classroom 207	yes	Pipe	Metal	White	Flaking	20	0.25	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	2	S24	Stairs	Fire Tower across from Classroom 207	no	W3	Brick	White	Flaking	500	8.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	2	S24	Stairs	Fire Tower across from Classroom 207	no	Door	Metal	Grey	Flaking	20	10	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	2	S24	Stairs	Fire Tower across from Classroom 207	no	Door Frame	Metal	Grey	Flaking	20	13	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730003-1	2	S24	Stairs	Fire Tower across from Classroom 207	yes	W4	Brick	White	Flaking	500	10.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730003-1	2	S24	Stairs	Fire Tower across from Classroom 207	yes	Window Safety Bars	Metal	Black	Flaking	120	21	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730003-1	2	S24	Stairs	Fire Tower across from Classroom 207	yes	Ceiling	Concrete	White	Flaking	1000	24	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	2	S24	Stairs	Fire Tower across from Classroom 207	no	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	2	207B	Student Restrooms - Male (4-12)	Boy's Restroom	yes	W1	Plaster	Blue	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	2	207B	Student Restrooms - Male (4-12)	Boy's Restroom	yes	W2	Plaster	Blue	Holes	5	15.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	ceiling... efflorescence 100
7300	1	B730001-1	2	207B	Student Restrooms - Male (4-12)	Boy's Restroom	yes	W3	Plaster	Blue	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	2	207B	Student Restrooms - Male (4-12)	Boy's Restroom	yes	W4	Plaster	Blue	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	2	207B	Student Restrooms - Male (4-12)	Boy's Restroom	yes	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	2	207B	Student Restrooms - Male (4-12)	Boy's Restroom	yes	Floor	Concrete	Varnish	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	2	H28	Circulation (Hallway)	Hallway from Classrooms 204 to 207	yes	W1	Plaster	Beige	Staple Holes/ Cracking	20	13.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Prior to Repair	No	no	
7300	1	B730003-1	2	H28	Circulation (Hallway)	Hallway from Classrooms 204 to 207	yes	Electrical Panel	Metal	Brown	Chipping	10	0.4	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	2	H28	Circulation (Hallway)	Hallway from Classrooms 204 to 207	yes	W2	Plaster	Beige	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Prior to Repair	No	no	
7300	1	B730001-1	2	H28	Circulation (Hallway)	Hallway from Classrooms 204 to 207	yes	W3	Plaster	Beige	Cracking/Staple Holes/Chipping	60	20.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Prior to Repair	No	no	
7300	1	B730003-1	2	H28	Circulation (Hallway)	Hallway from Classrooms 204 to 207	yes	Electrical Panel	Metal	Brown	Chipping	10	0.28	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730003-1	2	H28	Circulation (Hallway)	Hallway from Classrooms 204 to 207	yes	Radiator	Metal	Silver	Alligatoring	40	0.13	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730003-1	2	H28	Circulation (Hallway)	Hallway from Classrooms 204 to 207	yes	Pipe	Metal	Brown	Chipping	16	19.3	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730003-1	2	H28	Circulation (Hallway)	Hallway from Classrooms 204 to 207	yes	Door	Metal	Brown	Friction	10	0.11	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730003-1	2	H28	Circulation (Hallway)	Hallway from Classrooms 204 to 207	yes	Door Frame	Metal	Brown	Friction	10	0.1	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	2	H28	Circulation (Hallway)	Hallway from Classrooms 204 to 207	yes	W4	Plaster	Beige	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Prior to Repair	No	no	
7300	1	B730001-1	2	H28	Circulation (Hallway)	Hallway from Classrooms 204 to 207	yes	Ceiling	Plaster	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	2	H28	Circulation (Hallway)	Hallway from Classrooms 204 to 207	yes	Floor	Concrete	Varnish	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	2	S21	Stairs	Stairwell outside Classroom 208	yes	W1	Plaster	White	Flaking	10	21.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Prior to Repair	No	no	
7300	1	B730001-1	2	S21	Stairs	Stairwell outside Classroom 208	yes	W2	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Prior to Repair	No	no	
7300	1	B730001-1	2	S21	Stairs	Stairwell outside Classroom 208	yes	W3	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Prior to Repair	No	no	
7300	1	B730001-1	2	S21	Stairs	Stairwell outside Classroom 208	yes	Door	Metal	Brown	Friction	10	5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	

Hopkinson

ULCS #	E l e m e n t	BldgElmt ID	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)	Additional Component	Substrate Material	Color	Description of Paint and Plaster Damage	Additional Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Additional Component XRF (positive/ negative)	Debris Present (describe location)	Quantity (sf)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Comments/ Description/ Notes
7300	1	B730001-1	3	300	Administrative Office	Counselor's Office 300	yes	W4	Plaster	Green	Flaking/cracking	60	13.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Prior to Repair	No	no	
7300	1	B730001-1	3	300	Administrative Office	Counselor's Office 300	yes	Radiator	Metal	Silver	Chipping	30	0.02	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	3	300	Administrative Office	Counselor's Office 300	yes	Ceiling	Plaster	N/A	N/A	0	N/A	N/A	N/A	N/A	n/a	n/a	n/a	N/A	None	0	No	No	no		
7300	1	B730001-1	3	300	Administrative Office	Counselor's Office 300	yes	Floor	Wood	Varnish	None	0	N/A	N/A	N/A	N/A	n/a	n/a	n/a	N/A	None	0	No	No	no		
7300	1	B730001-1	3	300A	Restrooms, Staff - Male/Female	Staff Restroom at Counselor's Office	yes	W1	Plaster	Green	Flaking/cracking	50	6.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Prior to Repair	No	no	
7300	1	B730001-1	3	300A	Restrooms, Staff - Male/Female	Staff Restroom at Counselor's Office	yes	W2	Plaster	Green	Cracking	60	5.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Prior to Repair	No	no	
7300	1	B730001-1	3	300A	Restrooms, Staff - Male/Female	Staff Restroom at Counselor's Office	yes	Pipe	Metal	Green	Flaking	20	7.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	3	300A	Restrooms, Staff - Male/Female	Staff Restroom at Counselor's Office	yes	W3	Plaster	Green	Flaking/cracking	100	7.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Prior to Repair	No	no	
7300	1	B730001-1	3	300A	Restrooms, Staff - Male/Female	Staff Restroom at Counselor's Office	yes	Pipe	Metal	Green	Flaking	5	5.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	3	300A	Restrooms, Staff - Male/Female	Staff Restroom at Counselor's Office	yes	Radiator	Metal	Silver	Chipping	20	0.02	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	3	300A	Restrooms, Staff - Male/Female	Staff Restroom at Counselor's Office	yes	W4	Plaster	Green	Flaking/cracking	120	9.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Prior to Repair	No	no	
7300	1	B730001-1	3	300A	Restrooms, Staff - Male/Female	Staff Restroom at Counselor's Office	yes	Ceiling	Plaster	White	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	3	300A	Restrooms, Staff - Male/Female	Staff Restroom at Counselor's Office	yes	Floor	Concrete	N/A	N/A	0	N/A	N/A	N/A	N/A	n/a	n/a	n/a	N/A	None	0	No	No	no		
7300	1	B730001-1	3	301	Primary	Classroom 301	yes	W1	Plaster	Beige	Chipping/cracking	50	13.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Prior to Repair	No	no	
7300	1	B730001-1	3	301	Primary	Classroom 301	yes	W2	Plaster	Beige	Efflorescence/chipping	20	15.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Prior to Repair	No	no	
7300	1	B730001-1	3	301	Primary	Classroom 301	yes	W3	Plaster	Beige	Cracking/chipping	30	17.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Prior to Repair	No	no	
7300	1	B730001-1	3	301	Primary	Classroom 301	yes	Radiator	Metal	Silver	Chipping	10	0.01	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	3	301	Primary	Classroom 301	yes	W4	Plaster	Beige	Efflorescence/holes	50	11.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Prior to Repair	No	no	
7300	1	B730001-1	3	301	Primary	Classroom 301	yes	Ceiling	Plaster	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	3	301	Primary	Classroom 301	yes	Floor	Wood	Varnish	None	0	n/a	n/a	N/A	N/A	n/a	n/a	n/a	N/A	None	0	No	No	no		
7300	1	B730001-1	3	301A	Storage	Classroom 301 Coat Room	yes	W1	Plaster	Beige	Chipping/cracking	20	12.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Prior to Repair	No	no	
7300	1	B730001-1	3	301A	Storage	Classroom 301 Coat Room	yes	W2	Plaster	Beige	Efflorescence	20	17.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Prior to Repair	No	no	
7300	1	B730001-1	3	301A	Storage	Classroom 301 Coat Room	yes	W3	Plaster	Beige	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Prior to Repair	No	no	
7300	1	B730001-1	3	301A	Storage	Classroom 301 Coat Room	yes	W4	Plaster	Beige	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Prior to Repair	No	no	
7300	1	B730001-1	3	301A	Storage	Classroom 301 Coat Room	yes	Ceiling	Plaster	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	3	301A	Storage	Classroom 301 Coat Room	yes	Floor	Wood	Varnish	None	0	n/a	n/a	N/A	N/A	n/a	n/a	n/a	N/A	None	0	No	No	no		
7300	1	B730001-1	3	302	Primary	Classroom 302	yes	W1	Plaster	Beige	Cracking/chipping	40	11.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Prior to Repair	No	no	
7300	1	B730001-1	3	302	Primary	Classroom 302	yes	W2	Plaster	Beige	Holes/chipping	30	18.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Prior to Repair	No	no	
7300	1	B730001-1	3	302	Primary	Classroom 302	yes	W3	Plaster	Beige	Cracking/chipping	60	15.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Prior to Repair	No	no	
7300	1	B730001-1	3	302	Primary	Classroom 302	yes	Radiator	Metal	Silver	Chipping	20	0.02	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	3	302	Primary	Classroom 302	yes	W4	Plaster	Beige	Holes/chipping	50	17.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Prior to Repair	No	no	
7300	1	B730001-1	3	302	Primary	Classroom 302	yes	Ceiling	Plaster	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	3	302	Primary	Classroom 302	yes	Floor	Wood	Varnish	None	0	N/A	N/A	N/A	N/A	n/a	n/a	n/a	N/A	None	0	No	No	no		
7300	1	B730001-1	3	302A	Storage	Classroom 302 Coat Room	yes	W1	Plaster	Beige	chipping/cracking	20	15.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Prior to Repair	No	no	
7300	1	B730001-1	3	302A	Storage	Classroom 302 Coat Room	yes	W2	Plaster	Beige	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Partially Inaccessible	No	no	
7300	1	B730001-1	3	302A	Storage	Classroom 302 Coat Room	yes	W3	Plaster	Beige	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Prior to Repair	No	no	
7300	1	B730001-1	3	302A	Storage	Classroom 302 Coat Room	yes	W4	Plaster	Beige	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Partially Inaccessible	No	no	
7300	1	B730001-1	3	302A	Storage	Classroom 302 Coat Room	yes	Ceiling	Plaster	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	3	302A	Storage	Classroom 302 Coat Room	yes	Floor	Wood	Varnish	None	0	N/A	N/A	N/A	N/A	n/a	n/a	n/a	N/A	None	0	No	No	no		
7300	1	B730001-1	3	303	Primary	Classroom 311	yes	W1	Plaster	Beige	holes/chipping	20	16.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Prior to Repair	No	no	
7300	1	B730001-1	3	303	Primary	Classroom 311	yes	W2	Plaster	Beige	Chipping/cracking/holes	60	15.9	Positive	N/A	Beige	N/A	N/A	N/A	N/A	N/A	None	0	Prior to Repair	No	no	
7300	1	B730001-1	3	303	Primary	Classroom 311	yes	W3	Plaster	Beige	Efflorescence/chipping/flaking	80	19	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Prior to Repair	No	yes	
7300	1	B730001-1	3	303	Primary	Classroom 311	yes	Radiator	Metal	Silver	Chipping	40	0.02	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	3	303	Primary	Classroom 311	yes	W4	Plaster	Beige	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Prior to Repair	No	no	
7300	1	B730001-1	3	303	Primary	Classroom 311	yes	Ceiling	Plaster	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	3	303	Primary	Classroom 311	yes	Floor	Wood	Varnish	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	floor tile
7300	1	B730001-1	3	303A	Storage	Classroom 311 Closet	yes	W1	Plaster	Green	Flaking	300	17.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Prior to Repair	No	no	
7300	1	B730001-1	3	303A	Storage	Classroom 311 Closet	yes	pipe	Metal	Green	Flaking	12	11.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	3	303A	Storage	Classroom 311 Closet	yes	W2	Plaster	Green	Flaking	100	10	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Prior to Repair	No	no	
7300	1	B730001-1	3	303A	Storage	Classroom 311 Closet	yes	W3	Plaster	Green	Flaking	100	9.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Prior to Repair	No	no	
7300	1	B730001-1	3	303A	Storage	Classroom 311 Closet	yes	W4	Plaster	Green	Flaking	100	10.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Prior to Repair	No	no	
7300	1	B730001-1	3	303A	Storage	Classroom 311 Closet	yes	pipe	Metal	Green	Flaking	12	3.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	3	303A	Storage	Classroom 311 Closet	yes	Ceiling	Plaster	White	Moisture Damage/flaking	500	19.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	3	303A	Storage	Classroom 311 Closet	yes	Floor	Wood	Varnish	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	3	311	Primary	Classroom 303	yes	W1	Plaster	Beige	Efflorescence/moisture	60	20.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Prior to Repair	No	yes	
7300	1	B730001-1	3	311	Primary	Classroom 303	yes	W2	Plaster	Beige	Cracking	30	17.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Partially Inaccessible	No	no	
7300	1	B730001-1	3	311	Primary	Classroom 303	yes	W3	Plaster	Beige	Efflorescence/flaking	80	19.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Prior to Repair	No	yes	
7300	1	B730001-1	3	311	Primary	Classroom 303	yes	W4	Plaster	Beige	cracking/chipping	50	20.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Prior to Repair	No	no	
7300	1	B730001-1	3	311	Primary	Classroom 303	yes	Ceiling	Plaster	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	3	311	Primary	Classroom 303	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	floor tile
7300	1	B730001-1	3	311A	Storage	Classroom 303 Closet	yes	W1	Plaster	Beige	Cracking	40	11.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Prior to Repair	No	no	
7300	1	B730001-1	3	311A	Storage	Classroom 303 Closet	yes	W2</																			

Hopkinson

[illegible]

Hopkinson

ULCS #	E l e m e n t	BldgElmt ID	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)	Additional Component	Substrate Material	Color	Description of Paint and Plaster Damage	Additional Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Additional Component XRF (positive/ negative)	Debris Present (describe location)	Quantity (sf)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Comments/ Description/ Notes
7300	1	B730001-1	3	307	Primary	Classroom 307	yes	W3	Plaster	Beige	Efflorescence/flaking	40	12	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Prior to Repair	No	yes	
7300	1	B730001-1	3	307	Primary	Classroom 307	yes	W4	Sheetrock	Beige	Holes/Feeling	40	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Prior to Repair	No	no	
7300	1	B730001-1	3	307	Primary	Classroom 307	yes	Ceiling	Plaster	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	3	307	Primary	Classroom 307	yes	Floor	Wood	Varnish	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	Floor tile
7300	1	B730001-1	3	307	Primary	Classroom 307	yes	Divider (wall)	Sheetrock	Beige	Friction	50	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	3	307A	Storage	Classroom 307 Coat Room	yes	W1	Plaster	Beige	Cracking	30	23	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Partially Inaccessible	No	no	
7300	1	B730001-1	3	307A	Storage	Classroom 307 Coat Room	yes	W2	Plaster	Beige	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Prior to Repair	No	no	
7300	1	B730001-1	3	307A	Storage	Classroom 307 Coat Room	yes	W3	Plaster	Beige	holes	2	29.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Prior to Repair	No	no	
7300	1	B730001-1	3	307A	Storage	Classroom 307 Coat Room	yes	W4	Sheetrock	Beige	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Partially Inaccessible	No	no	
7300	1	B730001-1	3	307A	Storage	Classroom 307 Coat Room	yes	Ceiling	Plaster	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	3	307A	Storage	Classroom 307 Coat Room	yes	Floor	Wood	Varnish	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	3	310C	Administrative Office	Office 307A	yes	W1	Plaster	White	flaking/chipping	20	9.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Prior to Repair	No	no	
7300	1	B730001-1	3	310C	Administrative Office	Office 307A	yes	W2	Plaster	White	Chipping	5	8.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Prior to Repair	No	no	
7300	1	B730001-1	3	310C	Administrative Office	Office 307A	yes	radiator	Metal	silver	Alligatoring	10	0.03	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	3	310C	Administrative Office	Office 307A	yes	W3	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Partially Inaccessible	No	no	
7300	1	B730001-1	3	310C	Administrative Office	Office 307A	yes	W4	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Partially Inaccessible	No	no	
7300	1	B730001-1	3	310C	Administrative Office	Office 307A	yes	Ceiling	Plaster	Beige	Flaking/cracking/moistu re damage	12	15.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	3	310C	Administrative Office	Office 307A	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	rug over floor
7300	1	B730001-1	3	S34	Stairs	Fire Tower across from Classroom 307	no	W1	Brick	White	Flaking	500	7.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Prior to Repair	No	no	
7300	1	B730001-1	3	S34	Stairs	Fire Tower across from Classroom 307	no	door	Metal	Green	Flaking	20	7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	3	S34	Stairs	Fire Tower across from Classroom 307	no	door frame	Metal	Green	Flaking	20	8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	3	S34	Stairs	Fire Tower across from Classroom 307	no	W2	Brick	White	Flaking	500	15.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Prior to Repair	No	no	
7300	1	B730001-1	3	S34	Stairs	Fire Tower across from Classroom 307	no	pipe	Metal	White	Flaking	20	0.25	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	3	S34	Stairs	Fire Tower across from Classroom 307	no	W3	Brick	White	Flaking	500	8.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Prior to Repair	No	no	
7300	1	B730001-1	3	S34	Stairs	Fire Tower across from Classroom 307	no	door	Metal	Grey	Flaking	20	10	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	3	S34	Stairs	Fire Tower across from Classroom 307	no	door frame	Metal	Grey	Flaking	20	13	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	3	S34	Stairs	Fire Tower across from Classroom 307	no	W4	Brick	White	Flaking	500	10.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Prior to Repair	No	no	
7300	1	B730001-1	3	S34	Stairs	Fire Tower across from Classroom 307	no	window safety bars	Metal	Black	Flaking	120	21	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	3	S34	Stairs	Fire Tower across from Classroom 307	no	Ceiling	Concrete	White	Flaking	1000	24	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	3	S34	Stairs	Fire Tower across from Classroom 307	no	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	3	307B	Student Restrooms - Male (4-12)	Boy's Restroom	yes	W1	Plaster	Blue	Cracking	100	12.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Prior to Repair	No	no	
7300	1	B730001-1	3	307B	Student Restrooms - Male (4-12)	Boy's Restroom	yes	W2	Plaster	Blue	Cracking	100	11.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Prior to Repair	No	no	
7300	1	B730001-1	3	307B	Student Restrooms - Male (4-12)	Boy's Restroom	yes	W3	Plaster	Blue	Cracking	100	10.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Prior to Repair	No	no	
7300	1	B730001-1	3	307B	Student Restrooms - Male (4-12)	Boy's Restroom	yes	W4	Plaster	Blue	Cracking	100	10	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Prior to Repair	No	no	
7300	1	B730001-1	3	307B	Student Restrooms - Male (4-12)	Boy's Restroom	yes	Ceiling	Plaster	White	Cracking/Chipping	100	23.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	3	307B	Student Restrooms - Male (4-12)	Boy's Restroom	yes	Floor	Concrete	Grey	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	3	H311	Circulation (Hallway)	Hallway from Classrooms 303 to 307	yes	W1	Plaster	beige	cracking/holes	100	25.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Prior to Repair	No	yes	
7300	1	B730001-1	3	H311	Circulation (Hallway)	Hallway from Classrooms 303 to 307	yes	electrical panel	Metal	Brown	Chipping	5	0.26	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	3	H311	Circulation (Hallway)	Hallway from Classrooms 303 to 307	yes	W2	Plaster	beige	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Prior to Repair	No	no	
7300	1	B730001-1	3	H311	Circulation (Hallway)	Hallway from Classrooms 303 to 307	yes	W3	Plaster	beige	Efflorescence/flaking	200	16.3	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Prior to Repair	No	no	
7300	1	B730001-1	3	H311	Circulation (Hallway)	Hallway from Classrooms 303 to 307	yes	pipe	Metal	Black	Chipping	15	5.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	3	H311	Circulation (Hallway)	Hallway from Classrooms 303 to 307	yes	electrical panel	Metal	Brown	Chipping	10	0.27	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	3	H311	Circulation (Hallway)	Hallway from Classrooms 303 to 307	yes	door frame	Metal	Brown	Friction	10	3.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	3	H311	Circulation (Hallway)	Hallway from Classrooms 303 to 307	yes	door	Metal	Brown	Friction	20	4.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	3	H311	Circulation (Hallway)	Hallway from Classrooms 303 to 307	yes	W4	Plaster	beige	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Prior to Repair	No	no	
7300	1	B730001-1	3	H311	Circulation (Hallway)	Hallway from Classrooms 303 to 307	yes	radiator	Metal	Silver	Alligatoring	20	0.03	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	3	H311	Circulation (Hallway)	Hallway from Classrooms 303 to 307	yes	Ceiling	Plaster	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	3	H311	Circulation (Hallway)	Hallway from Classrooms 303 to 307	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	3	S31	Stairs	Stairwell outside Classroom 308	yes	W1	Plaster	beige	Moisture Damage/Cracking	60	16	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Prior to Repair	No	no	
7300	1	B730001-1	3	S31	Stairs	Stairwell outside Classroom 308	yes	W2	Plaster	Beige	Cracking	80	17.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Prior to Repair	No	no	
7300	1	B730001-1	3	S31	Stairs	Stairwell outside Classroom 308	yes	W3	Plaster	Beige	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Prior to Repair	No	no	
7300	1	B730001-1	3	S31	Stairs	Stairwell outside Classroom 308	yes	door	Metal	Brown	Friction	10	9.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	3	S31	Stairs	Stairwell outside Classroom 308	yes	door frame	Metal	Brown	Friction	10	4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	3	S31	Stairs	Stairwell outside Classroom 308	yes	W4	Plaster	Beige	Efflorescence,Cracking	40	14.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Prior to Repair	No	no	
7300	1	B730001-1	3	S31	Stairs	Stairwell outside Classroom 308	yes	Ceiling	Plaster	White	Efflorescence,Cracking	100	26.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	3	S31	Stairs	Stairwell outside Classroom 308	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	3	S31	Stairs	Stairwell outside Classroom 308	yes	ballast	Metal	Brown	Friction	25	0.26	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	3	S31	Stairs	Stairwell outside Classroom 308	yes	newel post	Metal	Brown	Friction	15	7.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	3	S31	Stairs	Stairwell outside Classroom 308	yes	handrail	Metal	Brown	Friction	5	0.4	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	3	308	Primary	Classroom 308	yes	W1	Plaster	beige	Efflorescence, chipping, holes	20	16.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Prior to Repair	No	no	
7300	1	B730001-1	3	308	Primary	Class																					

Hopkinson

ULCS #	E l e m e n t	BldgElmt ID	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)	Additional Component	Substrate Material	Color	Description of Paint and Plaster Damage	Additional Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Additional Component XRF (positive/ negative)	Debris Present (describe location)	Quantity (sf)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Comments/ Description/ Notes
7300	1	B730001-1	3	308	Primary	Classroom 308	yes	W3	Plaster	beige	chipping, flaking, cracking	100	23	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Prior to Repair	No	yes	
7300	1	B730001-1	3	308	Primary	Classroom 308	yes	W4	Plaster	beige	Efflorescence, flaking	100	22.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Prior to Repair	No	no	
7300	1	B730001-1	3	308	Primary	Classroom 308	yes	Ceiling	Plaster	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	3	308	Primary	Classroom 308	yes	Floor	Wood	Varnish	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	3	308A	Storage	Classroom 308 Closet	yes	W1	Plaster	Beige	Flaking	300	10.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Partially Inaccessible	No	no	
7300	1	B730001-1	3	308A	Storage	Classroom 308 Closet	yes	W2	Plaster	Beige	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Prior to Repair	No	no	
7300	1	B730001-1	3	308A	Storage	Classroom 308 Closet	yes	W3	Plaster	Beige	flaking, cracking	300	25.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Prior to Repair	No	no	
7300	1	B730001-1	3	308A	Storage	Classroom 308 Closet	yes	W4	Plaster	Beige	cracking, flaking	100	20.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Partially Inaccessible	No	no	
7300	1	B730001-1	3	308A	Storage	Classroom 308 Closet	yes	Ceiling	Plaster	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	3	308A	Storage	Classroom 308 Closet	yes	Floor	Wood	Varnish	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	3	309	Primary	Classroom 309	yes	W1	Plaster	Beige	chipping, holes	60	21	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Prior to Repair	No	no	
7300	1	B730001-1	3	309	Primary	Classroom 309	yes	W2	Plaster	Beige	chipping, holes	60	24.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Prior to Repair	No	no	
7300	1	B730001-1	3	309	Primary	Classroom 309	yes	W3	Plaster	Beige	cracking, chipping, efflorescence	100	23	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Prior to Repair	No	no	
7300	1	B730001-1	3	309	Primary	Classroom 309	yes	radiator	Metal	silver	Chipping	30	0.06	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	3	309	Primary	Classroom 309	yes	W4	Plaster	Beige	chipping, holes	60	23.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Prior to Repair	No	no	
7300	1	B730001-1	3	309	Primary	Classroom 309	yes	Ceiling	Plaster	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	3	309	Primary	Classroom 309	yes	Floor	Wood	varnish	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	3	309A	Storage	Classroom 309 Coat Room	yes	W1	Plaster	Beige	Cracking	10	29	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Prior to Repair	No	no	
7300	1	B730001-1	3	309A	Storage	Classroom 309 Coat Room	yes	W2	Plaster	Beige	chipping, cracking	60	10.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Prior to Repair	No	no	
7300	1	B730001-1	3	309A	Storage	Classroom 309 Coat Room	yes	W3	Plaster	Beige	Cracking	30	15.3	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Prior to Repair	No	no	
7300	1	B730001-1	3	309A	Storage	Classroom 309 Coat Room	yes	W4	Plaster	Beige	Cracking	60	12.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Prior to Repair	No	no	
7300	1	B730001-1	3	309A	Storage	Classroom 309 Coat Room	yes	Ceiling	Plaster	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	3	309A	Storage	Classroom 309 Coat Room	yes	Floor	Wood	varnish	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	3	310	Primary	Classroom 310	yes	W1	Plaster	Beige	chipping, cracking	20	12.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Prior to Repair	No	no	
7300	1	B730001-1	3	310	Primary	Classroom 310	yes	W2	Plaster	Beige	Moisture Damage, flaking	80	11	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Prior to Repair	No	no	
7300	1	B730001-1	3	310	Primary	Classroom 310	yes	W3	Plaster	Beige	Efflorescence, cracking, flaking	100	10.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Prior to Repair	No	no	
7300	1	B730001-1	3	310	Primary	Classroom 310	yes	radiator	Metal	silver	Alligatoring	30	0.02	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	3	310	Primary	Classroom 310	yes	W2	Plaster	Beige	holes, chipping	40	16	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Prior to Repair	No	no	
7300	1	B730001-1	3	310	Primary	Classroom 310	yes	Ceiling	Plaster	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	3	310	Primary	Classroom 310	yes	Floor	Wood	varnish	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	3	310B	Storage	Classroom 310 Coat Room	yes	W1	Plaster	Beige	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Prior to Repair	No	no	
7300	1	B730001-1	3	310B	Storage	Classroom 310 Coat Room	yes	W2	Plaster	Beige	Spalling, chipping	20	11	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Prior to Repair	No	no	
7300	1	B730001-1	3	310B	Storage	Classroom 310 Coat Room	yes	W3	Plaster	Beige	Cracking	30	10.3	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Prior to Repair	No	no	
7300	1	B730001-1	3	310B	Storage	Classroom 310 Coat Room	yes	W4	Plaster	Beige	holes, chipping	40	10.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Prior to Repair	No	no	
7300	1	B730001-1	3	310B	Storage	Classroom 310 Coat Room	yes	Ceiling	Plaster	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	3	310B	Storage	Classroom 310 Coat Room	yes	Floor	Wood	varnish	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	3	310A	Primary	Classroom 310A	yes	W1	Plaster	Yellow	chipping, cracking	30	15.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Prior to Repair	No	no	
7300	1	B730001-1	3	310A	Primary	Classroom 310A	yes	W2	Plaster	Yellow	spalling, cracking	60	11.3	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Partially Inaccessible	No	no	bookshelf
7300	1	B730001-1	3	310A	Primary	Classroom 310A	yes	W3	Plaster	Yellow	Efflorescence, flaking	100	20.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Prior to Repair	No	yes	
7300	1	B730001-1	3	310A	Primary	Classroom 310A	yes	radiator	Metal	silver	Alligatoring	30	0.03	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	3	310A	Primary	Classroom 310A	yes	W4	Plaster	Yellow	holes, chipping, cracking	50	1.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Prior to Repair	No	yes	
7300	1	B730001-1	3	310A	Primary	Classroom 310A	yes	Ceiling	Plaster	beige	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	3	310A	Primary	Classroom 310A	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	3	H312	Circulation (Hallway)	Hallway from Classrooms 308 to 310	yes	W1	Plaster	beige	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Prior to Repair	No	no	
7300	1	B730001-1	3	H312	Circulation (Hallway)	Hallway from Classrooms 308 to 310	yes	door	Metal	Brown	Friction	5	5.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	3	H312	Circulation (Hallway)	Hallway from Classrooms 308 to 310	yes	door frame	Metal	Brown	Friction	5	9.3	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	3	H312	Circulation (Hallway)	Hallway from Classrooms 308 to 310	yes	W2	Plaster	beige	chipping, flaking	80	11.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Prior to Repair	No	no	
7300	1	B730001-1	3	H312	Circulation (Hallway)	Hallway from Classrooms 308 to 310	yes	W3	Plaster	beige	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Prior to Repair	No	no	
7300	1	B730001-1	3	H312	Circulation (Hallway)	Hallway from Classrooms 308 to 310	yes	W4	Plaster	beige	holes, chipping	30	10.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Prior to Repair	No	no	
7300	1	B730001-1	3	H312	Circulation (Hallway)	Hallway from Classrooms 308 to 310	yes	Ceiling	Plaster	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	1	B730001-1	3	H312	Circulation (Hallway)	Hallway from Classrooms 308 to 310	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	2	B730003-1	1	001	Primary	Classroom 1	yes	W1	Concrete	Blue	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	2	B730003-1	1	001	Primary	Classroom 1	yes	W2	Concrete	Blue	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	2	B730003-1	1	001	Primary	Classroom 1	yes	W3	Concrete	Blue	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	2	B730003-1	1	001	Primary	Classroom 1	yes	W4	Concrete	Blue	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	2	B730003-1	1	001	Primary	Classroom 1	yes	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	2	B730003-1	1	001	Primary	Classroom 1	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	2	B730003-1	1	001B	Student Restrooms - Male/Female (Classroom)	Classroom 1 Restroom	yes	W1		Blue	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	2	B730003-1	1	001B	Student Restrooms - Male/Female (Classroom)	Classroom 1 Restroom	yes	W2		Concrete	Blue	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	2	B730003-1	1	001B	Student Restrooms - Male/Female (Classroom)	Classroom 1 Restroom	yes	W3		Sheetrock	Blue	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	2	B730003-1	1	001B	Student Restrooms - Male/Female (Classroom)	Classroom 1 Restroom	yes	W4		Sheetrock	Blue	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	2	B730003-1	1	001B	Student Restrooms - Male/Female (Classroom)																						

Hopkinson

ULCS #	E l e m e n t	BldgElmt ID	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)	Additional Component	Substrate Material	Color	Description of Paint and Plaster Damage	Additional Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Additional Component XRF (positive/ negative)	Debris Present (describe location)	Quantity (sf)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Comments/ Description/ Notes	
7300	2	B730003-1	1	002	Primary	Classroom 2	yes	W2	Concrete	Blue	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	2	B730003-1	1	002	Primary	Classroom 2	yes	W3	Concrete	Blue	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	2	B730003-1	1	002	Primary	Classroom 2	yes	W4	Concrete	Blue	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	2	B730003-1	1	002	Primary	Classroom 2	yes	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	2	B730003-1	1	002	Primary	Classroom 2	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	2	B730003-1	1	003	Administrative Office	Office P3	yes	W1	Concrete	Blue	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	2	B730003-1	1	003	Administrative Office	Office P3	yes	W2	Concrete	Blue	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	2	B730003-1	1	003	Administrative Office	Office P3	yes	W3	Concrete	Blue	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	2	B730003-1	1	003	Administrative Office	Office P3	yes	W4	Concrete	Blue	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	2	B730003-1	1	003	Administrative Office	Office P3	yes	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	2	B730003-1	1	003	Administrative Office	Office P3	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	floor tile
7300	2	B730003-1	1	003B	Student Restrooms - Male/Female (Classroom)	Classroom 2 Restroom	yes	W1	Concrete	Blue	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	2	B730003-1	1	003B	Student Restrooms - Male/Female (Classroom)	Classroom 2 Restroom	yes	W2	Sheetrock	Blue	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	2	B730003-1	1	003B	Student Restrooms - Male/Female (Classroom)	Classroom 2 Restroom	yes	W3	Sheetrock	Blue	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	2	B730003-1	1	003B	Student Restrooms - Male/Female (Classroom)	Classroom 2 Restroom	yes	W4	Concrete	Blue	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	2	B730003-1	1	003B	Student Restrooms - Male/Female (Classroom)	Classroom 2 Restroom	yes	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	2	B730003-1	1	003B	Student Restrooms - Male/Female (Classroom)	Classroom 2 Restroom	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	floor tile
7300	2	B730003-1	1	H04	Circulation (Hallway)	Entrance/Center Hallway	yes	W1	Concrete	Blue	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	2	B730003-1	1	H04	Circulation (Hallway)	Entrance/Center Hallway	yes	W2	Concrete	Blue	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	2	B730003-1	1	H04	Circulation (Hallway)	Entrance/Center Hallway	yes	W3	Concrete	Blue	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	2	B730003-1	1	H04	Circulation (Hallway)	Entrance/Center Hallway	yes	W4	Concrete	Blue	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	2	B730003-1	1	H04	Circulation (Hallway)	Entrance/Center Hallway	yes	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
7300	2	B730003-1	1	H04	Circulation (Hallway)	Entrance/Center Hallway	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	floor tile

Appendix B. EPA Checklist Table

Hopkinson

7300	1	B	009	Primary	Classroom B1 (ESOL)	yes	W3	Efflorescence/Flaking/Chip pings	Positive	N/A	N/A	N/A	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	N/A	Yes	Yes	Yes	Included with wall 1		Saheed Apenaola - Industrial Hygienist	5/30/20
7300	1	B	009	Primary	Classroom B1 (ESOL)	yes	W4	Peeling/Staple Holes	Positive	N/A	N/A	N/A	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	N/A	Yes	Yes	Yes	Included with wall 1		Saheed Apenaola - Industrial Hygienist	5/30/20
7300	1	B	010	Storage	Classroom B1 Closet (Rear of Classroom)	yes	W1	Efflorescence/Flaking	Positive	N/A	N/A	N/A	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	N/A	Yes	Yes	Yes	Included with ceiling		Saheed Apenaola - Industrial Hygienist	5/30/20
7300	1	B	010	Storage	Classroom B1 Closet (Rear of Classroom)	yes	W2	Efflorescence/Flaking	Positive	N/A	N/A	N/A	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	N/A	Yes	Yes	Yes	Included with ceiling		Saheed Apenaola - Industrial Hygienist	5/30/20
7300	1	B	010	Storage	Classroom B1 Closet (Rear of Classroom)	yes	W3	Cracking/Efflorescence	Positive	N/A	N/A	N/A	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	N/A	Yes	Yes	Yes	Included with ceiling		Saheed Apenaola - Industrial Hygienist	5/30/20
7300	1	B	010	Storage	Classroom B1 Closet (Rear of Classroom)	yes	W4	Flaking/Cracking/Efflorescence	Positive	N/A	N/A	N/A	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	N/A	Yes	Yes	Yes	Included with ceiling		Saheed Apenaola - Industrial Hygienist	5/30/20
7300	1	B	010	Storage	Classroom B1 Closet (Rear of Classroom)	yes	Ceiling	Flaking/Cracking/Efflorescence	Positive	N/A	N/A	N/A	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	N/A	Yes	Yes	Yes	2 RRP / 1 Colorimetric / 1 FAA		Saheed Apenaola - Industrial Hygienist	5/30/20
7300	1	B	011	Storage	Classroom B1 Closet (Adjacent to Entrance)	yes	W1	Cracking/Chipping	Positive	N/A	N/A	N/A	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	N/A	Yes	Yes	Yes	2 RRP		Saheed Apenaola - Industrial Hygienist	5/30/20
7300	1	B	011	Storage	Classroom B1 Closet (Adjacent to Entrance)	yes	W2	Flaking/Cracking	Positive	N/A	N/A	N/A	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	N/A	Yes	Yes	Yes	Included with wall 1		Saheed Apenaola - Industrial Hygienist	5/30/20
7300	1	B	011	Storage	Classroom B1 Closet (Adjacent to Entrance)	yes	W3	Cracking	Positive	N/A	N/A	N/A	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	N/A	Yes	Yes	Yes	Included with wall 1		Saheed Apenaola - Industrial Hygienist	5/30/20
7300	1	B	011	Storage	Classroom B1 Closet (Adjacent to Entrance)	yes	W4	Cracking	Positive	N/A	N/A	N/A	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	N/A	Yes	Yes	Yes	Included with wall 1		Saheed Apenaola - Industrial Hygienist	5/30/20
7300	1	B	011	Storage	Classroom B1 Closet (Adjacent to Entrance)	yes	Pipe	Chipping	Positive	N/A	N/A	N/A	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	N/A	Yes	Yes	Yes	Included with wall 1		Saheed Apenaola - Industrial Hygienist	5/30/20
7300	1	B	S03	Stairs	Stairwell next to Classroom B1	yes	Tread	Friction	Positive	N/A	N/A	N/A	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	N/A	Yes	Yes	Yes	2 RRP		Saheed Apenaola - Industrial Hygienist	5/7/20
7300	1	B	S03	Stairs	Stairwell next to Classroom B1	yes	Stringer	Friction	Positive	N/A	N/A	N/A	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	N/A	Yes	Yes	Yes	Included with Tread		Saheed Apenaola - Industrial Hygienist	5/7/20
7300	1	B	S03	Stairs	Stairwell next to Classroom B1	yes	Riser	Friction	Positive	N/A	N/A	N/A	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	N/A	Yes	Yes	Yes	Included with Tread		Saheed Apenaola - Industrial Hygienist	5/7/20
7300	1	B	S03	Stairs	Stairwell next to Classroom B1	yes	Newel Post	Friction	Positive	N/A	N/A	N/A	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	N/A	Yes	Yes	Yes	Included with Tread		Saheed Apenaola - Industrial Hygienist	5/7/20
7300	1	B	S03	Stairs	Stairwell next to Classroom B1	yes	Handrail	Friction	Positive	N/A	N/A	N/A	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	N/A	Yes	Yes	Yes	Included with Tread		Saheed Apenaola - Industrial Hygienist	5/7/20
7300	1	B	H03	Circulation (Hallway)	Hallway outside Classrooms B1 and B2	yes	Tread	Friction	Positive	N/A	N/A	N/A	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	N/A	Yes	Yes	Yes	Included with ceiling		Saheed Apenaola - Industrial Hygienist	5/13/20
7300	1	B	H03	Circulation (Hallway)	Hallway outside Classrooms B1 and B2	yes	Riser																							

Hopkinson

[illegible]

Hopkinson

7300	1	1	112C	Storage	Stage Right Storage Room (Classroom 110 Side)	yes	Ceiling	Flaking/Cracking	Positive	N/A	N/A	N/A	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	N/A	Yes	Yes	Yes	Yes	4 RRP / 1 FAA	Saeed Apenaoia - Industrial Hygienist	5/30/20	
7300	1	1	106	Primary	Classroom 106	yes	W1	Chipping/Cracking/Staple Holes	Positive	N/A	N/A	N/A	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	N/A	Yes	Yes	Yes	Yes	22 RRP / 3 Colormetric / 1 FAA	Saeed Apenaoia - Industrial Hygienist	5/7/20	
7300	1	1	106	Primary	Classroom 106	yes	W3	Cracking/Chipping/Flaking	Positive	N/A	N/A	N/A	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	N/A	Yes	Yes	Yes	Included with wall 1		Saeed Apenaoia - Industrial Hygienist	5/7/20	
7300	1	1	106	Primary	Classroom 106	yes	W4	Staple Holes	Positive	N/A	N/A	N/A	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	N/A	Yes	Yes	Yes	Included with wall 1		Saeed Apenaoia - Industrial Hygienist	5/7/20	
7300	1	1	106A	Storage	Classroom 106 Coat Room	yes	W1	Cracking/Chipping	Positive	N/A	N/A	N/A	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	N/A	Yes	Yes	Yes	Yes	2 RRP / 1 Colormetric / 1 FAA	Saeed Apenaoia - Industrial Hygienist	5/7/20	
7300	1	1	106A	Storage	Classroom 106 Coat Room	yes	W3	Cracking	Positive	N/A	N/A	N/A	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	N/A	Yes	Yes	Yes	Included with wall 1		Saeed Apenaoia - Industrial Hygienist	5/7/20	
7300	1	1	106A	Storage	Classroom 106 Coat Room	yes	W4	Cracking/Chipping	Positive	N/A	N/A	N/A	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	N/A	Yes	Yes	Yes	Included with wall 1		Saeed Apenaoia - Industrial Hygienist	5/7/20	
7300	1	1	107	Primary	Classroom 107	yes	W1	Chipping/cracking/Staple Holes/Flaking	Positive	N/A	N/A	N/A	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	N/A	Yes	Yes	Yes	Yes	22 RRP / 3 Colormetric / 1 FAA	Saeed Apenaoia - Industrial Hygienist	5/7/20	
7300	1	1	107	Primary	Classroom 107	yes	W2	Flaking/Cracking/Chipping	Positive	N/A	N/A	N/A	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	N/A	Yes	Yes	Yes	Included with wall 1		Saeed Apenaoia - Industrial Hygienist	5/7/20	
7300	1	1	107	Primary	Classroom 107	yes	W3	Efflorescence/Flaking/Chipping/Cracking	Positive	N/A	N/A	N/A	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	N/A	Yes	Yes	Yes	Included with wall 1		Saeed Apenaoia - Industrial Hygienist	5/7/20	
7300	1	1	107	Primary	Classroom 107	yes	W4	Flaking	Positive	N/A	N/A	N/A	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	N/A	Yes	Yes	Yes	Included with wall 1		Saeed Apenaoia - Industrial Hygienist	5/7/20	
7300	1	1	107A	Storage	Classroom 107 Coat Room	yes	W1	Chipping	Positive	N/A	N/A	N/A	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	N/A	Yes	Yes	Yes	Yes	2 RRP / 1 Colormetric / 1 FAA	Saeed Apenaoia - Industrial Hygienist	5/7/20	
7300	1	1	107A	Storage	Classroom 107 Coat Room	yes	W3	Chipping	Positive	N/A	N/A	N/A	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	N/A	Yes	Yes	Yes	Included with wall 1		Saeed Apenaoia - Industrial Hygienist	5/7/20	
7300	1	1	107A	Storage	Classroom 107 Coat Room	yes	W4	Chipping	Positive	N/A	N/A	N/A	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	N/A	Yes	Yes	Yes	Included with wall 1		Saeed Apenaoia - Industrial Hygienist	5/7/20	
7300	1	1	S14	Stairs	Fire Tower across from Classroom 107	yes	W1	Flaking	Positive	N/A	N/A	N/A	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	N/A	Yes	Yes	Yes	Included with ceiling		Saeed Apenaoia - Industrial Hygienist	5/8/20	
7300	1	1	S14	Stairs	Fire Tower across from Classroom 107	yes	Door	Flaking	Positive	N/A	N/A	N/A	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	N/A	Yes	Yes	Yes	Included with ceiling		Saeed Apenaoia - Industrial Hygienist	5/8/20	
7300	1	1	S14	Stairs	Fire Tower across from Classroom 107	yes	Door Frame	Flaking	Positive	N/A	N/A	N/A	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	N/A	Yes	Yes	Yes	Included with ceiling		Saeed Apenaoia - Industrial Hygienist	5/8/20	
7300	1	1	S14	Stairs	Fire Tower across from Classroom 107	yes	W2	Flaking	Positive	N/A	N/A	N/A	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	N/A	Yes	Yes	Yes	Included with ceiling		Saeed Apenaoia - Industrial Hygienist	5/8/20	
7300	1	1	S14	Stairs	Fire Tower across from Classroom 107	yes	Pipe	Flaking	Positive	N/A	N/A	N/A	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	N/A	Yes	Yes	Yes	Included with ceiling		Saeed Apenaoia - Industrial Hygienist	5/8/20	
7300	1	1	S14	Stairs	Fire Tower across from Classroom 107	yes	W3	Flaking	Positive	N/A	N/A	N/A	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	N/A	Yes	Yes	Yes	Included with ceiling		Saeed Apenaoia - Industrial Hygienist	5/8/20	
7300	1	1	S14	Stairs	Fire Tower across from Classroom 107	yes	Door	Flaking	Positive	N/A	N/A	N/A	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	N/A	Yes	Yes	Yes	Included with ceiling		Saeed Apenaoia - Industrial Hygienist	5/8/20	
7300	1	1	S14	Stairs	Fire Tower across from Classroom 107	yes	Door Frame	Flaking	Positive	N/A	N/A	N/A	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	N/A	Yes	Yes	Yes	Included with ceiling		Saeed Apenaoia - Industrial Hygienist	5/8/20	
7300	1	1	S14	Stairs	Fire Tower across from Classroom 107	yes	W4	Flaking	Positive	N/A	N/A	N/A	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	N/A	Yes	Yes	Yes	Included with ceiling		Saeed Apenaoia - Industrial Hygienist	5/8/20	
7300	1	1	S14	Stairs	Fire Tower across from Classroom 107	yes	Window Safety Bars	Flaking	Positive	N/A	N/A	N/A	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	N/A	Yes	Yes	Yes	Included with ceiling		Saeed Apenaoia - Industrial Hygienist	5/8/20	
7300	1	1	S14	Stairs	Fire Tower across from Classroom 107	yes	Ceiling	Flaking	Positive	N/A	N/A	N/A	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	N/A	Yes	Yes	Yes	Included with ceiling		Saeed Apenaoia - Industrial Hygienist	5/8/20	
7300	1	1	107B	Student Restrooms - Male (4-12)	Boy's Restroom	yes	W1	Efflorescence	Positive	N/A	N/A	N/A	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	N/A	Yes	Yes	Yes	Yes	6 RRP	Saeed Apenaoia - Industrial Hygienist	6/9/20	
7300	1	1	107B	Student Restrooms - Male (4-12)	Boy's Restroom	yes	W4	Cracking/Flaking	Positive	N/A	N/A	N/A	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	N/A	Yes	Yes	Yes	Included with ceiling		Saeed Apenaoia - Industrial Hygienist	6/9/20	
7300	1	1	107B	Student Restrooms - Male (4-12)	Boy's Restroom	yes	Ceiling	Moisture Damage	Positive	N/A	N/A	N/A	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	N/A	Yes	Yes	Yes	Yes	20 RRP / 4 Colormetric / 4 FAA	Saeed Apenaoia - Industrial Hygienist	6/9/20	
7300	1	1	H15	Circulation (Hallway)	Hallway from Classrooms 104 to 107	yes	W1	Flaking/Efflorescence/Cracking	Positive	N/A	N/A	N/A	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	N/A	Yes	Yes	Yes	Included with ceiling		Saeed Apenaoia - Industrial Hygienist	5/18/20	
7300	1	1	H15	Circulation (Hallway)	Hallway from Classrooms 104 to 107	yes	W3	Cracking	Positive	N/A	N/A	N/A	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	N/A	Yes	Yes	Yes	Included with ceiling		Saeed Apenaoia - Industrial Hygienist	5/18/20	
7300	1	1	H15	Circulation (Hallway)	Hallway from Classrooms 104 to 107	yes	Door	Friction	Positive	N/A	N/A	N/A	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	N/A	Yes	Yes	Yes	Included with ceiling		Saeed Apenaoia - Industrial Hygienist	5/18/20	
7300	1	1	H15	Circulation (Hallway)	Hallway from Classrooms 104 to 107	yes	Door Frame	Friction	Positive	N/A	N/A	N/A	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	N/A	Yes	Yes	Yes	Included with ceiling		Saeed Apenaoia - Industrial Hygienist	5/18/20	
7300	1	1	H15	Circulation (Hallway)	Hallway from Classrooms 104 to 107	yes	W4	Cracking	Positive	N/A	N/A	N/A	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	N/A	Yes	Yes	Yes	Included with ceiling		Saeed Apenaoia - Industrial Hygienist	5/18/20	
7300	1	1	H15	Circulation (Hallway)	Hallway from Classrooms 104 to 107	yes	Ceiling	Flaking	Positive	N/A	N/A	N/A	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	N/A	Yes	Yes	Yes	Yes	38 RRP	Saeed Apenaoia - Industrial Hygienist	5/18/20	
7300	1	1	S11	Stairs	Stairwell next to Classroom 108	yes	W1	Flaking	Positive	N/A	N/A	N/A	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	N/A	Yes	Yes	Yes	Included with ceiling		Saeed Apenaoia - Industrial Hygienist	4/9/20	
7300	1	1	S11	Stairs	Stairwell next to Classroom 108	yes	W2	Flaking/Cracking	Positive	N/A	N/A	N/A	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	N/A	Yes	Yes	Yes	Included with ceiling		Saeed Apenaoia - Industrial Hygienist	4/9/20	
7300	1	1	S11	Stairs	Stairwell next to Classroom 108	yes	Door	Friction	Positive	N/A	N/A	N/A	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	N/A	Yes	Yes	Yes	Included with ceiling		Saeed Apenaoia - Industrial Hygienist	4/9/20	
7300	1	1	S11	Stairs	Stairwell next to Classroom 108	yes	Door Frame	Friction	Positive	N/A	N/A	N/A	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	N/A	Yes	Yes	Yes	Included with ceiling		Saeed Apenaoia - Industrial Hygienist	4/9/20	
7300	1	1	S11	Stairs	Stairwell next to Classroom 108	yes	W4	Moisture	Positive	N/A	N/A	N/A	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	N/A	Yes	Yes	Yes	Included with ceiling		Saeed Apenaoia - Industrial Hygienist	4/9/20	
7300	1	1	S11	Stairs	Stairwell next to Classroom 108	yes	Ceiling	Cracking	Positive	N/A	N/A	N/A	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	N/A	Yes	Yes	Yes	Yes	8 RRP	Saeed Apenaoia - Industrial Hygienist	4/9/20	
7300	1	1	S11	Stairs	Stairwell next to Classroom 108	yes	Tread	Friction	Positive	N/A	N/A	N/A	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	N/A	Yes	Yes	Yes	Included with wall 1		Saeed Apenaoia - Industrial Hygienist	4/9/20	
7300	1	1	S11	Stairs	Stairwell next to Classroom 108	yes	Riser	Friction	Positive	N/A	N/A	N/A	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	N/A	Yes	Yes	Yes	Included with wall 1		Saeed Apenaoia - Industrial Hygienist	4/9/20	
7300	1	1	S11	Stairs	Stairwell next to Classroom 108	yes	Newel Post	Friction	Positive	N/A	N/A	N/A	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	N/A	Yes	Yes	Yes	Included with wall 1		Saeed Apenaoia - Industrial Hygienist	4/9/20	
7300	1	1	108	Primary	Classroom 108	yes	W1	Chipping/Cracking	Positive	N/A	N/A	N/A	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	N/A	Yes	Yes	Yes	Yes	Included with wall 1		Saeed Apenaoia - Industrial Hygienist	5/7/20
7300	1	1	108	Primary	Classroom 108	yes	W2	Chipping/Cracking	Positive	N/A	N/A	N/A	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	N/A	Yes	Yes	Yes	Included with wall 1		Saeed Apenaoia - Industrial Hygienist	5/7/20	
7300	1	1	108	Primary	Classroom 108	yes	W3	Chipping/Cracking/Flaking	Positive	N/A	N/A	N/A	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	N/A	Yes	Yes	Yes	Included with wall 1		Saeed Apenaoia - Industrial Hygienist	5/7/20	
7300	1	1	108	Primary	Classroom 108	yes	W4	Chipping/Flaking	Positive	N/A	N/A	N/A	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	N/A	Yes	Yes	Yes	Included with wall 1		Saeed Apenaoia - Industrial Hygienist	5/7/20	
7300	1	1	108B	Student Restrooms - Male/Female (Classroom)	Classroom 108 Restroom	yes	W1	Cracking/Flaking	Positive	N/A	N/A	N/A	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	N/A	Yes	Yes	Yes	Yes	2 RRP	Saeed Apenaoia - Industrial Hygienist	5/7/20	
7300	1	1	108B	Student Restrooms - Male/Female (Classroom)	Classroom 108 Restroom	yes	W2	Efflorescence/Moisture Damage	Positive	N/A	N/A	N/A	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	N/A	Yes	Yes	Yes	Included with wall 1		Saeed Apenaoia - Industrial Hygienist	5/7/20	
7300	1	1	108B	Student Restrooms - Male/Female (Classroom)	Classroom 108 Restroom	yes	W3	Flaking/Chipping	Positive	N/A	N/A	N/A	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	N/A	Yes	Yes	Yes	Included with wall 1		Saeed Apenaoia - Industrial Hygienist	5/7/20	
7300	1	1	108A	Storage	Classroom 108 Coat Room	yes	W1	Cracking	Positive	N/A	N/A	N/A	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	N/A	Yes	Yes	Yes	Yes	2 RRP / 1 Colormetric / 1 FAA	Saeed Apenaoia - Industrial Hygienist	5/7/20	
7300	1	1	108A	Storage	Classroom 108 Coat Room	yes	W3	Cracking	Positive	N/A	N/A	N/A	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	N/A	Yes	Yes	Yes	Included with wall 1		Saeed Apenaoia - Industrial Hygienist	5/7/20	
7300																																	

Hopkinson

7300	1	2	202	Primary	Classroom 202	yes	W3	Spalling	Positive	N/A	N/A	N/A	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	N/A	Yes	Yes	Yes	Included with wall 1		Saheed Apenaola - Industrial Hygienist	5/1/20
7300	1	2	202A	Storage	Classroom 202 Coat Room	yes	W1	Chipping	Positive	N/A	N/A	N/A	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	N/A	Yes	Yes	Yes	2 RRP / 1 Colorimetric / 1 FAA		Saheed Apenaola - Industrial Hygienist	5/1/20
7300	1	2	202A	Storage	Classroom 202 Coat Room	yes	W2	holes, chipping	Positive	N/A	N/A	N/A	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	N/A	Yes	Yes	Yes	Included with wall 1		Saheed Apenaola - Industrial Hygienist	5/1/20
7300	1	2	203	Primary	Classroom 203	yes	W1	chipping, holes	Positive	N/A	N/A	N/A	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	N/A	Yes	Yes	Yes	24 RRP / 3 Colorimetric / 1 FAA		Saheed Apenaola - Industrial Hygienist	4/11/20
7300	1	2	203	Primary	Classroom 203	yes	W2	Holes, flaking, cracking	Positive	N/A	N/A	N/A	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	N/A	Yes	Yes	Yes	Included with wall 1		Saheed Apenaola - Industrial Hygienist	4/11/20
7300	1	2	203	Primary	Classroom 203	yes	W3	Holes, flaking	Positive	N/A	N/A	N/A	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	N/A	Yes	Yes	Yes	Included with wall 1		Saheed Apenaola - Industrial Hygienist	4/11/20
7300	1	2	203	Primary	Classroom 203	yes	W4	Holes	Positive	N/A	N/A	N/A	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	N/A	Yes	Yes	Yes	Included with wall 1		Saheed Apenaola - Industrial Hygienist	4/11/20
7300	1	2	203A	Storage	Classroom 203 Storage	yes	W2	Cracking	Positive	N/A	N/A	N/A	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	N/A	Yes	Yes	Yes	4 RRP / 2 Colorimetric / 2 FAA		Saheed Apenaola - Industrial Hygienist	4/11/20
7300	1	2	203A	Storage	Classroom 203 Storage	yes	W4	Cracking	Positive	N/A	N/A	N/A	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	N/A	Yes	Yes	Yes	Included with wall 2		Saheed Apenaola - Industrial Hygienist	4/11/20
7300	1	2	S22	Stairs	Stairwell next to Classroom 203	yes	W1	Flaking	Positive	N/A	N/A	N/A	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	N/A	Yes	Yes	Yes	7 RRP		Saheed Apenaola - Industrial Hygienist	4/21/20
7300	1	2	S22	Stairs	Stairwell next to Classroom 203	yes	W2	Chipping	Positive	N/A	N/A	N/A	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	N/A	Yes	Yes	Yes	Included with wall 1		Saheed Apenaola - Industrial Hygienist	4/21/20
7300	1	2	S22	Stairs	Stairwell next to Classroom 203	yes	Door	Friction	Positive	N/A	N/A	N/A	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	N/A	Yes	Yes	Yes	Included with wall 1		Saheed Apenaola - Industrial Hygienist	4/21/20
7300	1	2	S22	Stairs	Stairwell next to Classroom 203	yes	Door Frame	Friction	Positive	N/A	N/A	N/A	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	N/A	Yes	Yes	Yes	Included with wall 1		Saheed Apenaola - Industrial Hygienist	4/21/20
7300	1	2	S22	Stairs	Stairwell next to Classroom 203	yes	W4	Cracking	Positive	N/A	N/A	N/A	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	N/A	Yes	Yes	Yes	Included with wall 1		Saheed Apenaola - Industrial Hygienist	4/21/20
7300	1	2	S22	Stairs	Stairwell next to Classroom 203	yes	Newel Posts	Friction	Positive	N/A	N/A	N/A	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	N/A	Yes	Yes	Yes	Included with wall 1		Saheed Apenaola - Industrial Hygienist	4/21/20
7300	1	2	H29	Circulation (Hallway)	Halfway from Classroom 201 to 203	yes	door	Friction	Positive	N/A	N/A	N/A	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	N/A	Yes	Yes	Yes	Included with wall 2		Saheed Apenaola - Industrial Hygienist	4/14/20
7300	1	2	H29	Circulation (Hallway)	Halfway from Classroom 201 to 203	yes	door frame	Friction	Positive	N/A	N/A	N/A	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	N/A	Yes	Yes	Yes	Included with wall 2		Saheed Apenaola - Industrial Hygienist	4/14/20
7300	1	2	H29	Circulation (Hallway)	Halfway from Classroom 201 to 203	yes	W2	Chipping	Positive	N/A	N/A	N/A	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	N/A	Yes	Yes	Yes	5 RRP		Saheed Apenaola - Industrial Hygienist	4/14/20
7300	1	2	203B	Student Restrooms - Female (4-12)</																										

Hopkinson

[illegible]

Hopkinson

7300	1	3	303A	Storage	Classroom 311 Closet	yes	W4	Flaking	Positive	N/A	N/A	N/A	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	N/A	Yes	Yes	Yes	Yes	Included with ceiling	Saheed Apenaola - Industrial Hygienist	4/20/20
7300	1	3	303A	Storage	Classroom 311 Closet	yes	pipe	Flaking	Positive	N/A	N/A	N/A	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	N/A	Yes	Yes	Yes	Yes	Included with ceiling	Saheed Apenaola - Industrial Hygienist	4/20/20
7300	1	3	303A	Storage	Classroom 311 Closet	yes	Ceiling	Moisture Damage/flaking	Positive	N/A	N/A	N/A	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	N/A	Yes	Yes	Yes	Yes	2 RRP / 1 Colorimetric / 1 FAA	Saheed Apenaola - Industrial Hygienist	4/20/20
7300	1	3	311	Primary	Classroom 303	yes	W1	Efflorescence/moisture	Positive	N/A	N/A	N/A	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	N/A	Yes	Yes	Yes	Yes	13 RRP / 2 Colorimetric / 1 FAA	Saheed Apenaola - Industrial Hygienist	4/16/20
7300	1	3	311	Primary	Classroom 303	yes	W2	Cracking	Positive	N/A	N/A	N/A	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	N/A	Yes	Yes	Yes	Yes	Included with wall 1	Saheed Apenaola - Industrial Hygienist	4/16/20
7300	1	3	311	Primary	Classroom 303	yes	W3	Efflorescence/flaking	Positive	N/A	N/A	N/A	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	N/A	Yes	Yes	Yes	Yes	Included with wall 1	Saheed Apenaola - Industrial Hygienist	4/16/20
7300	1	3	311	Primary	Classroom 303	yes	W4	cracking/chipping	Positive	N/A	N/A	N/A	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	N/A	Yes	Yes	Yes	Yes	Included with wall 1	Saheed Apenaola - Industrial Hygienist	4/16/20
7300	1	3	311A	Storage	Classroom 303 Closet	yes	W1	Cracking	Positive	N/A	N/A	N/A	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	N/A	Yes	Yes	Yes	Yes	4 RRP / 2 Colorimetric / 2 FAA	Saheed Apenaola - Industrial Hygienist	4/16/20
7300	1	3	311A	Storage	Classroom 303 Closet	yes	W2	Cracking	Positive	N/A	N/A	N/A	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	N/A	Yes	Yes	Yes	Yes	Included with wall 1	Saheed Apenaola - Industrial Hygienist	4/16/20
7300	1	3	311A	Storage	Classroom 303 Closet	yes	W4	Efflorescence/flaking/Cracking	Positive	N/A	N/A	N/A	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	N/A	Yes	Yes	Yes	Yes	Included with wall 1	Saheed Apenaola - Industrial Hygienist	4/16/20
7300	1	3	S32	Stairs	Stairwell outside Classroom 303	yes	W1	Flaking	Positive	N/A	N/A	N/A	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	N/A	Yes	Yes	Yes	Yes	7 RRP	Saheed Apenaola - Industrial Hygienist	5/4/20
7300	1	3	S32	Stairs	Stairwell outside Classroom 303	yes	Radiator	Alligatoring	Positive	N/A	N/A	N/A	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	N/A	Yes	Yes	Yes	Yes	Included with wall 1	Saheed Apenaola - Industrial Hygienist	5/4/20
7300	1	3	S32	Stairs	Stairwell outside Classroom 303	yes	W2	chipping/flaking	Positive	N/A	N/A	N/A	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	N/A	Yes	Yes	Yes	Yes	Included with wall 1	Saheed Apenaola - Industrial Hygienist	5/4/20
7300	1	3	S32	Stairs	Stairwell outside Classroom 303	yes	Door	Friction	Positive	N/A	N/A	N/A	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	N/A	Yes	Yes	Yes	Yes	Included with wall 1	Saheed Apenaola - Industrial Hygienist	5/4/20
7300	1	3	S32	Stairs	Stairwell outside Classroom 303	yes	Door Frame	Friction	Positive	N/A	N/A	N/A	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	N/A	Yes	Yes	Yes	Yes	Included with wall 1	Saheed Apenaola - Industrial Hygienist	5/4/20
7300	1	3	S32	Stairs	Stairwell outside Classroom 303	yes	W4	cracking/flaking	Positive	N/A	N/A	N/A	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	N/A	Yes	Yes	Yes	Yes	Included with wall 1	Saheed Apenaola - Industrial Hygienist	5/4/20
7300	1	3	S32	Stairs	Stairwell outside Classroom 303	yes	Newel Post	Friction	Positive	N/A	N/A	N/A	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	N/A	Yes	Yes	Yes	Yes	Included with wall 1	Saheed Apenaola - Industrial Hygienist	5/4/20
7300	1	3	H310	Circulation (Hallway)	Hallway from Classrooms 301 to 303	yes	Door	Friction	Positive	N/A	N/A	N/A	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	N/A	Yes	Yes	Yes	Yes	Included with wall 2	Saheed Apenaola - Industrial Hygienist	3/12/20
7300	1	3	H310	Circulation (Hallway)	Hallway from Classrooms 301 to 303	yes	Door Frame	Friction	Positive	N/A	N/A	N/A	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	N/A	Yes	Yes	Yes	Yes	Included with wall 2	Saheed Apenaola - Industrial Hygienist	3/12/20
7300	1	3	H310	Circulation (Hallway)	Hallway from Classrooms 301 to 303	yes	W2	holes/chipping	Positive	N/A	N/A	N/A	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	N/A	Yes	Yes	Yes	Yes	9 RRP	Saheed Apenaola - Industrial Hygienist	3/12/20
7300	1	3	H310	Circulation (Hallway)	Hallway from Classrooms 301 to 303	yes	W4	holes/chipping	Positive	N/A	N/A	N/A	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	N/A	Yes	Yes	Yes	Yes	Included with wall 2	Saheed Apenaola - Industrial Hygienist	3/12/20
7300	1	3	303B	Student Restrooms - Female (4-12)	Girl's Restroom	yes	W1	Efflorescence/cracking	Positive	N/A	N/A	N/A	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	N/A	Yes	Yes	Yes	Yes	Included with ceiling	Saheed Apenaola - Industrial Hygienist	4/20/20
7300	1	3	303B	Student Restrooms - Female (4-12)	Girl's Restroom	yes	W2	cracking/chipping	Positive	N/A	N/A	N/A	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	N/A	Yes	Yes	Yes	Yes	Included with ceiling	Saheed Apenaola - Industrial Hygienist	4/20/20
7300	1	3	303B	Student Restrooms - Female (4-12)	Girl's Restroom	yes	W3	Moisture Damage/cracking	Positive	N/A	N/A	N/A	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	N/A	Yes	Yes	Yes	Yes	Included with ceiling	Saheed Apenaola - Industrial Hygienist	4/20/20
7300	1	3	303B	Student Restrooms - Female (4-12)	Girl's Restroom	yes	W4	Cracking	Positive	N/A	N/A	N/A	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	N/A	Yes	Yes	Yes	Yes	Included with ceiling	Saheed Apenaola - Industrial Hygienist	4/20/20
7300	1	3	303B	Student Restrooms - Female (4-12)	Girl's Restroom	yes	pipe	Chipping	Positive	N/A	N/A	N/A	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	N/A	Yes	Yes	Yes	Yes	Included with ceiling	Saheed Apenaola - Industrial Hygienist	4/20/20
7300	1	3	303B	Student Restrooms - Female (4-12)	Girl's Restroom	yes	Ceiling	Flaking/cracking	Positive	N/A	N/A	N/A	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	N/A	Yes	Yes	Yes	Yes	10 RRP / 2 Colorimetric / 2 FAA	Saheed Apenaola - Industrial Hygienist	4/20/20
7300	1	3	304	Primary	Classroom 304	yes	W1	chipping/cracking	Positive	N/A	N/A	N/A	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	N/A	Yes	Yes	Yes	Yes	22 RRP / 3 Colorimetric / 1 FAA	Saheed Apenaola - Industrial Hygienist	4/16/20
7300	1	3	304	Primary	Classroom 304	yes	W2	holes	Positive	N/A	N/A	N/A	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	N/A	Yes	Yes	Yes	Yes	Included with wall 1	Saheed Apenaola - Industrial Hygienist	4/16/20
7300	1	3	304	Primary	Classroom 304	yes	W3	chipping/flaking/cracking	Positive	N/A	N/A	N/A	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	N/A	Yes	Yes	Yes	Yes	Included with wall 1	Saheed Apenaola - Industrial Hygienist	4/16/20
7300	1	3	304	Primary	Classroom 304	yes	W4	flaking/holes	Positive	N/A	N/A	N/A	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	N/A	Yes	Yes	Yes	Yes	Included with wall 1	Saheed Apenaola - Industrial Hygienist	4/16/20
7300	1	3	304A	Storage	Classroom 304 Coat Room	yes	W1	Cracking	Positive	N/A	N/A	N/A	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	N/A	Yes	Yes	Yes	Yes	6 RRP / 3 Colorimetric / 3 FAA	Saheed Apenaola - Industrial Hygienist	4/23/20
7300	1	3	304A	Storage	Classroom 304 Coat Room	yes	W3	Spalling	Positive	N/A	N/A	N/A	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	N/A	Yes	Yes	Yes	Yes	Included with wall 1	Saheed Apenaola - Industrial Hygienist	4/23/20
7300	1	3	304A	Storage	Classroom 304 Coat Room	yes	W4	Cracking	Positive	N/A	N/A	N/A	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	N/A	Yes	Yes	Yes	Yes	Included with wall 1	Saheed Apenaola - Industrial Hygienist	4/23/20
7300	1	3	305	Primary	Classroom 305	yes	W1	Cracking/chipping/holes	Positive	N/A	N/A	N/A	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	N/A	Yes	Yes	Yes	Yes	5 RRP / 1 Colorimetric / 1 FAA	Saheed Apenaola - Industrial Hygienist	4/16/20
7300	1	3	305	Primary	Classroom 305	yes	W3	Cracking/chipping	Positive	N/A	N/A	N/A	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	N/A	Yes	Yes	Yes	Yes	5 RRP	Saheed Apenaola - Industrial Hygienist	4/16/20
7300	1	3	305A	Storage	Classroom 305 Coat Room	yes	W1	Chipping	Positive	N/A	N/A	N/A	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	N/A	Yes	Yes	Yes	Yes	2 RRP / 1 Colorimetric / 1 FAA	Saheed Apenaola - Industrial Hygienist	4/16/20
7300	1	3	305A	Storage	Classroom 305 Coat Room	yes	W3	Spalling	Positive	N/A	N/A	N/A	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	N/A	Yes	Yes	Yes	Yes	Included with wall 1	Saheed Apenaola - Industrial Hygienist	4/16/20
7300	1	3	305A	Storage	Classroom 305 Coat Room	yes	W4	Chipping	Positive	N/A	N/A	N/A	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	N/A	Yes	Yes	Yes	Yes	Included with wall 1	Saheed Apenaola - Industrial Hygienist	4/16/20
7300	1	3	306	Primary	Classroom 306	yes	W1	Chipping/holes	Positive	N/A	N/A	N/A	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	N/A	Yes	Yes	Yes	Yes	5 RRP / 1 Colorimetric / 1 FAA	Saheed Apenaola - Industrial Hygienist	4/16/20
7300	1	3	306	Primary	Classroom 306	yes	W3	flaking/chipping	Positive	N/A	N/A	N/A	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	N/A	Yes	Yes	Yes	Yes	5 RRP	Saheed Apenaola - Industrial Hygienist	4/16/20
7300	1	3	306A	Storage	Classroom 306 Coat Room	yes	W1	Cracking	Positive	N/A	N/A	N/A	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	N/A	Yes	Yes	Yes	Yes	4 RRP / 2 Colorimetric / 2 FAA	Saheed Apenaola - Industrial Hygienist	4/20/20
7300	1	3	306B	Storage	Classroom 306 Closet	yes	W4	Flaking	Positive	N/A	N/A	N/A	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	N/A	Yes	Yes	Yes	Yes	Included with wall 1	Saheed Apenaola - Industrial Hygienist	4/20/20
7300	1	3	307	Primary	Classroom 307	yes	W1	flaking/cracking	Positive	N/A	N/A	N/A	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	N/A	Yes	Yes	Yes	Yes	44 RRP / 6 Colorimetric / 2 FAA	Saheed Apenaola - Industrial Hygienist	4/20/20
7300	1	3	307	Primary	Classroom 307	yes	W2	cracking/flaking	Positive	N/A	N/A	N/A	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	N/A	Yes	Yes	Yes	Yes	Included with wall 1	Saheed Apenaola - Industrial Hygienist	4/20/20
7300	1	3	307	Primary	Classroom 307	yes	W3	Efflorescence/flaking	Positive	N/A	N/A	N/A	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	N/A	Yes	Yes	Yes	Yes	Included with wall 1	Saheed Apenaola - Industrial Hygienist	4/20/20
7300	1	3	307A	Storage	Classroom 307 Coat Room	yes	W1	Cracking	Positive	N/A	N/A	N/A	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	N/A	Yes	Yes	Yes	Yes	4 RRP / 2 Colorimetric / 2 FAA	Saheed Apenaola - Industrial Hygienist	4/20/20
7300	1	3	307A	Storage	Classroom 307 Coat Room	yes	W3	holes	Positive	N/A	N/A	N/A	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	N/A	Yes	Yes	Yes	Yes	Included with wall 1	Saheed Apenaola - Industrial Hygienist	4/20/20
7300	1	3	310C	Administrative Office	Office 307A	yes	W1	flaking/chipping	Positive	N/A	N/A	N/A	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	N/A	Yes	Yes	Yes	Yes	Included with ceiling	Saheed Apenaola - Industrial Hygienist	5/7/20
7300	1	3	310C	Administrative Office	Office 307A	yes	W2	Chipping	Positive	N/A	N/A	N/A	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	N/A	Yes	Yes	Yes	Yes	Included with ceiling	Saheed Apenaola - Industrial Hygienist	5/7/20
7300	1	3	310C	Administrative Office	Office 307A	yes	Ceiling	Flaking/cracking/moisture damage	Positive	N/A	N/A	N/A	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	N/A	Yes	Yes	Yes	Yes	15 RRP / 5 Colorimetric / 5 FAA	Saheed Apenaola - Industrial Hygienist	5/7/20
7300	1	3	307B	Student Restrooms - Male (4-12)	Boy's Restroom	yes	W1	Cracking	Positive	N/A	N/A	N/A	Yes	Yes	Yes	Yes	Yes															

Hopkinson

7300	1	3	H311	Circulation (Hallway)	Hallway from Classrooms 303 to 307	yes	W3	Efflorescence/flaking	Positive	N/A	N/A
7300	1	3	H311	Circulation (Hallway)	Hallway from Classrooms 303 to 307	yes	pipe	Chipping	Positive	N/A	N/A
7300	1	3	H311	Circulation (Hallway)	Hallway from Classrooms 303 to 307	yes	door frame	Friction	Positive	N/A	N/A
7300	1	3	H311	Circulation (Hallway)	Hallway from Classrooms 303 to 307	yes	door	Friction	Positive	N/A	N/A
7300	1	3	S31	Stairs	Stairwell outside Classroom 308	yes	W1	Moisture Damage/Cracking	Positive	N/A	N/A
7300	1	3	S31	Stairs	Stairwell outside Classroom 308	yes	W2	Cracking	Positive	N/A	N/A
7300	1	3	S31	Stairs	Stairwell outside Classroom 308	yes	door	Friction	Positive	N/A	N/A
7300	1	3	S31	Stairs	Stairwell outside Classroom 308	yes	door frame	Friction	Positive	N/A	N/A
7300	1	3	S31	Stairs	Stairwell outside Classroom 308	yes	W4	Efflorescence,Cracking	Positive	N/A	N/A
7300	1	3	S31	Stairs	Stairwell outside Classroom 308	yes	Ceiling	Efflorescence,Cracking	Positive	N/A	N/A
7300	1	3	S31	Stairs	Stairwell outside Classroom 309	yes	newel post	Friction	Positive	N/A	N/A
7300	1	3	308	Primary	Classroom 308	yes	W1	Efflorescence, chipping, holes	Positive	N/A	N/A
7300	1	3	308	Primary	Classroom 308	yes	W2	chipping, holes, cracking	Positive	N/A	N/A
7300	1	3	308	Primary	Classroom 308	yes	W3	chipping, flaking, cracking	Positive	N/A	N/A
7300	1	3	308	Primary	Classroom 308	yes	W4	Efflorescence, flaking	Positive	N/A	N/A
7300	1	3	308A	Storage	Classroom 308 Closet	yes	W1	Flaking	Positive	N/A	N/A
7300	1	3	308A	Storage	Classroom 308 Closet	yes	W3	flaking, cracking	Positive	N/A	N/A
7300	1	3	308A	Storage	Classroom 308 Closet	yes	W4	cracking, flaking	Positive	N/A	N/A
7300	1	3	309	Primary	Classroom 309	yes	W1	chipping, holes	Positive	N/A	N/A
7300	1	3	309	Primary	Classroom 309	yes	W2	chipping, holes	Positive	N/A	N/A
7300	1	3	309	Primary	Classroom 309	yes	W3	cracking, chipping, efflorescence	Positive	N/A	N/A
7300	1	3	309	Primary	Classroom 309	yes	W4	chipping, holes	Positive	N/A	N/A
7300	1	3	309A	Storage	Classroom 309 Coat Room	yes	W1	Cracking	Positive	N/A	N/A
7300	1	3	309A	Storage	Classroom 309 Coat Room	yes	W2	chipping, cracking	Positive	N/A	N/A
7300	1	3	309A	Storage	Classroom 309 Coat Room	yes	W3	Cracking	Positive	N/A	N/A
7300	1	3	309A	Storage	Classroom 309 Coat Room	yes	W4	Cracking	Positive	N/A	N/A
7300	1	3	310	Primary	Classroom 310	yes	W1	chipping, cracking	Positive	N/A	N/A
7300	1	3	310	Primary	Classroom 310	yes	W2	Moisture Damage, flaking	Positive	N/A	N/A
7300	1	3	310	Primary	Classroom 310	yes	W3	Efflorescence, cracking, flaking	Positive	N/A	N/A
7300	1	3	310	Primary	Classroom 310	yes	W4	holes, chipping	Positive	N/A	N/A
7300	1	3	310B	Storage	Classroom 310 Coat Room	yes	W2	Spalling, chipping	Positive	N/A	N/A
7300	1	3	310B	Storage	Classroom 310 Coat Room	yes	W3	Cracking	Positive	N/A	N/A
7300	1	3	310B	Storage	Classroom 310 Coat Room	yes	W4	holes, chipping	Positive	N/A	N/A
7300	1	3	310A	Primary	Classroom 310A	yes	W1	chipping, cracking	Positive	N/A	N/A
7300	1	3	310A	Primary	Classroom 310A	yes	W2	spalling, cracking	Positive	N/A	N/A
7300	1	3	310A	Primary	Classroom 310A	yes	W3	Efflorescence, flaking	Positive	N/A	N/A
7300	1	3	310A	Primary	Classroom 310A	yes	W4	holes, chipping, cracking	Positive	N/A	N/A
7300	1	3	H312	Circulation (Hallway)	Hallway from Classrooms 308 to 310	yes	door	Friction	Positive	N/A	N/A
7300	1	3	H312	Circulation (Hallway)	Hallway from Classrooms 308 to 310	yes	door frame	Friction	Positive	N/A	N/A
7300	1	3	H312	Circulation (Hallway)	Hallway from Classrooms 308 to 310	yes	W2	chipping, flaking	Positive	N/A	N/A
7300	1	3	H312	Circulation (Hallway)	Hallway from Classrooms 308 to 310	yes	W4	holes, chipping	Positive	N/A	N/A

[illegible]

Appendix C. Oversight Table

Hopkinson

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Student/Teacher Occupied	Primary Component	Pre-Cleaning Completed (date)	Contents Moved (date)	Work Area Prepped (date)	Surfaces Stabilized (date)	Contents Back in Place (date)	Final Inspection Approval and Photos (date)	Square Footage of Work Area	Number of Required RRP Wipes	Number of Colorimetric Wipes Used to Pass	Final Colorimetric Wipe Submitted for AAS Analysis (yes/no)	AAS Analysis Results	Comments from Assessment	Comments from Oversight
	7300	1	B	001	Primary	Classroom S1	yes	W3	5/1/20	5/1/20	5/5/20	5/11/20	N/A	5/12/20	168	5	1	Yes	<10 ug/ft2		
	7300	1	B	001A	Storage	Classroom S1 Closet	yes	W2	5/1/20		5/5/20	5/11/20	N/A	5/12/20	Included with ceiling	Included with ceiling	-	-	-		
	7300	1	B	001A	Storage	Classroom S1 Closet	yes	W3	5/1/20		5/5/20	5/11/20	N/A	5/12/20	Included with ceiling	Included with ceiling	-	-	-		
	7300	1	B	001A	Storage	Classroom S1 Closet	yes	W4	5/1/20		5/5/20	5/11/20	N/A	5/12/20	Included with ceiling	Included with ceiling	-	-	-		
	7300	1	B	001A	Storage	Classroom S1 Closet	yes	Ceiling	5/1/20		5/5/20	5/11/20	N/A	5/12/20	60	4	2	Yes	<10 ug/ft2; 68 ug/ft2		
	7300	1	B	H01	Circulation (Hallway)	Hallway from Classroom S1 to Faculty Office	yes	W1	N/A	N/A	5/4/20	5/12/20	N/A	5/13/20	Included with ceiling	Included with ceiling	-	-	-		
	7300	1	B	H01	Circulation (Hallway)	Hallway from Classroom S1 to Faculty Office	yes	W2	N/A	N/A	5/4/20	5/12/20	N/A	5/13/20	Included with ceiling	Included with ceiling	-	-	-		
	7300	1	B	H01	Circulation (Hallway)	Hallway from Classroom S1 to Faculty Office	yes	W3	N/A	N/A	5/4/20	5/12/20	N/A	5/13/20	Included with ceiling	Included with ceiling	-	-	-		
	7300	1	B	H01	Circulation (Hallway)	Hallway from Classroom S1 to Faculty Office	yes	W4	N/A	N/A	5/4/20	5/12/20	N/A	5/13/20	Included with ceiling	Included with ceiling	-	-	-		
	7300	1	B	H01	Circulation (Hallway)	Hallway from Classroom S1 to Faculty Office	yes	Ceiling	N/A	N/A	5/4/20	5/12/20	N/A	5/13/20	781	20	0	N/A	N/A		
	7300	1	B	S04	Stairs	Stairwell next to Classroom S1	yes	W1	N/A	N/A	5/4/20	5/12/20	N/A	5/13/20	Included with ceiling	Included with ceiling	-	-	-		
	7300	1	B	S04	Stairs	Stairwell next to Classroom S1	yes	W2	N/A	N/A	5/4/20	5/12/20	N/A	5/13/20	Included with ceiling	Included with ceiling	-	-	-		
	7300	1	B	S04	Stairs	Stairwell next to Classroom S1	yes	W3	N/A	N/A	5/4/20	5/12/20	N/A	5/13/20	Included with ceiling	Included with ceiling	-	-	-		
	7300	1	B	S04	Stairs	Stairwell next to Classroom S1	yes	W4	N/A	N/A	5/4/20	5/12/20	N/A	5/13/20	Included with ceiling	Included with ceiling	-	-	-		
	7300	1	B	S04	Stairs	Stairwell next to Classroom S1	yes	Ceiling	N/A	N/A	5/4/20	5/12/20	N/A	5/13/20	230	6	0	N/A	N/A		
	7300	1	B	S04	Stairs	Stairwell next to Classroom S1	yes	Tread	N/A	N/A	5/4/20	5/12/20	N/A	5/13/20	Included with wall 1	Included with wall 1	-	-	-		
	7300	1	B	S04	Stairs	Stairwell next to Classroom S1	yes	Stringer	N/A	N/A	5/4/20	5/12/20	N/A	5/13/20	Included with wall 1	Included with wall 1	-	-	-		
	7300	1	B	S04	Stairs	Stairwell next to Classroom S1	yes	Riser	N/A	N/A	5/4/20	5/12/20	N/A	5/13/20	Included with wall 1	Included with wall 1	-	-	-		
	7300	1	B	S04	Stairs	Stairwell next to Classroom S1	yes	Newel Post	N/A	N/A	5/4/20	5/12/20	N/A	5/13/20	Included with wall 1	Included with wall 1	-	-	-		
	7300	1	B	S04	Stairs	Stairwell next to Classroom S1	yes	Handrail	N/A	N/A	5/4/20	5/12/20	N/A	5/13/20	Included with wall 1	Included with wall 1	-	-	-		
	7300	1	B	005	Cafetorium (Cafeteria / Gymnasium)	Cafetorium	yes	W1	5/1/20	5/1/20	5/4/20	5/13/20	N/A	5/18/20	Included with ceiling	Included with ceiling	-	-	-		
	7300	1	B	005	Cafetorium (Cafeteria / Gymnasium)	Cafetorium	yes	Stair Riser	5/1/20	5/1/20	5/4/20	5/13/20	N/A	5/18/20	Included with ceiling	Included with ceiling	-	-	-		
	7300	1	B	005	Cafetorium (Cafeteria / Gymnasium)	Cafetorium	yes	Stair Riser	5/1/20	5/1/20	5/4/20	5/13/20	N/A	5/18/20	Included with ceiling	Included with ceiling	-	-	-		
	7300	1	B	005	Cafetorium (Cafeteria / Gymnasium)	Cafetorium	yes	Ceiling	5/1/20	5/1/20	5/4/20	5/13/20	N/A	5/18/20	3608	91	10	Yes	(4) <10 ug/ft2		
	7300	1	B	003	Storage	Cafetorium Storage	yes	W1	5/1/20	5/1/20	5/4/20	5/13/20	N/A	5/18/20	Included with ceiling	Included with ceiling	-	-	-		
	7300	1	B	003	Storage	Cafetorium Storage	yes	W2	5/1/20	5/1/20	5/4/20	5/13/20	N/A	5/18/20	Included with ceiling	Included with ceiling	-	-	-		
	7300	1	B	003	Storage	Cafetorium Storage	yes	W3	5/1/20	5/1/20	5/4/20	5/13/20	N/A	5/18/20	Included with ceiling	Included with ceiling	-	-	-		
	7300	1	B	003	Storage	Cafetorium Storage	yes	W4	5/1/20	5/1/20	5/4/20	5/13/20	N/A	5/18/20	Included with ceiling	Included with ceiling	-	-	-		
	7300	1	B	003	Storage	Cafetorium Storage	yes	Ceiling	5/1/20	5/1/20	5/4/20	5/13/20	N/A	5/18/20	100	3	1	Yes	<10 ug/ft2		
	7300	1	B	004	Administrative Office	Physical Education Office	yes	W2	5/1/20	5/1/20	5/4/20	5/13/20	N/A	5/18/20	Included with ceiling	Included with ceiling	-	-	-		
	7300	1	B	004	Administrative Office	Physical Education Office	yes	Ceiling	5/1/20	5/1/20	5/4/20	5/13/20	N/A	5/18/20	144	4	1	Yes	<10 ug/ft2		
	7300	1	B	004	Administrative Office	Physical Education Office	yes	Pipe	5/1/20	5/1/20	5/4/20	5/13/20	N/A	5/18/20	Included with wall 2	Included with wall 2	-	-	-		
	7300	1	B	H05	Circulation (Hallway)	Cafeteria Exterior Exit Hallway	yes	W1	N/A	N/A	5/4/20	5/13/20	N/A	5/14/20	75	2	0	N/A	N/A		
	7300	1	B	H05	Circulation (Hallway)	Cafeteria Exterior Exit Hallway	yes	W2	N/A	N/A	5/4/20	5/13/20	N/A	5/14/20	Included with wall 1	Included with wall 1	-	-	-		
	7300	1	B	H05	Circulation (Hallway)	Cafeteria Exterior Exit Hallway	yes	W3	N/A	N/A	5/4/20	5/13/20	N/A	5/14/20	Included with wall 1	Included with wall 1	-	-	-		
	7300	1	B	H02	Circulation (Hallway)	Hallway outside Kitchen and Boiler Room	yes	Ceiling	N/A	N/A	5/4/20	5/13/20	N/A	5/14/20	385	10	0	N/A	N/A		
	7300	1	B	H02	Circulation (Hallway)	Hallway outside Kitchen and Boiler Room	yes	Duct	N/A	N/A	5/4/20	5/13/20	N/A	5/14/20	Included with ceiling	Included with ceiling	-	-	-		
	7300	1	B	007	Kitchen	Kitchen	yes	W2	N/A	N/A	5/13/20	5/22/20	N/A	5/27/20	Included with ceiling	Included with ceiling	-	-	-		

Hopkinson

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Student/Teacher Occupied	Primary Component	Pre-Cleaning Completed (date)	Contents Moved (date)	Work Area Prepped (date)	Surfaces Stabilized (date)	Contents Back in Place (date)	Final Inspection Approval and Photos (date)	Square Footage of Work Area	Number of Required RRP Wipes	Number of Colorimetric Wipes Used to Pass	Final Colorimetric Wipe Submitted for AAS Analysis (yes/no)	AAS Analysis Results	Comments from Assessment	Comments from Oversight
	7300	1	B	007	Kitchen	Kitchen	yes	Ceiling	N/A	N/A	5/13/20	5/22/20	N/A	5/27/20	621	16	2	Yes	(2) <10 ug/ft2		
	7300	1	B	B2	Primary	Classroom B2 (Art Room)	yes	W1	5/13/20	5/13/20	5/14/20	5/22/20	N/A	5/27/20	900	23	3	Yes	<10 ug/ft2		
	7300	1	B	B2	Primary	Classroom B2 (Art Room)	yes	W3	5/13/20	5/13/20	5/14/20	5/22/20	N/A	5/27/20	Included with wall 1	Included with wall 1	-	-	-		
	7300	1	B	B2	Primary	Classroom B2 (Art Room)	yes	W4	5/13/20	5/13/20	5/14/20	5/22/20	N/A	5/27/20	Included with wall 1	Included with wall 1	-	-	-		
	7300	1	B	B2A	Storage	Classroom B2 Coat Room	yes	W1	5/13/20	5/13/20	5/14/20	5/22/20	N/A	5/27/20	Included with ceiling	Included with ceiling	-	-	-		
	7300	1	B	B2A	Storage	Classroom B2 Coat Room	yes	W2	5/13/20	5/13/20	5/14/20	5/22/20	N/A	5/27/20	Included with ceiling	Included with ceiling	-	-	-		
	7300	1	B	B2A	Storage	Classroom B2 Coat Room	yes	W3	5/13/20	5/13/20	5/14/20	5/22/20	N/A	5/27/20	Included with ceiling	Included with ceiling	-	-	-		
	7300	1	B	B2A	Storage	Classroom B2 Coat Room	yes	W4	5/13/20	5/13/20	5/14/20	5/22/20	N/A	5/27/20	Included with ceiling	Included with ceiling	-	-	-		
	7300	1	B	B2A	Storage	Classroom B2 Coat Room	yes	Ceiling	5/13/20	5/13/20	5/14/20	5/22/20	N/A	5/27/20	120	6	2	Yes	50 ug/ft2; <10 ug/ft2		
	7300	1	B	B2B	Storage	Classroom B2 Closet	yes	W1	5/13/20	5/13/20	5/14/20	5/22/20	N/A	5/27/20	Included with ceiling	Included with ceiling	-	-	-		
	7300	1	B	B2B	Storage	Classroom B2 Closet	yes	W2	5/13/20	5/13/20	5/14/20	5/22/20	N/A	5/27/20	Included with ceiling	Included with ceiling	-	-	-		
	7300	1	B	B2B	Storage	Classroom B2 Closet	yes	W3	5/13/20	5/13/20	5/14/20	5/22/20	N/A	5/27/20	Included with ceiling	Included with ceiling	-	-	-		
	7300	1	B	B2B	Storage	Classroom B2 Closet	yes	W4	5/13/20	5/13/20	5/14/20	5/22/20	N/A	5/27/20	Included with ceiling	Included with ceiling	-	-	-		
	7300	1	B	B2B	Storage	Classroom B2 Closet	yes	Ceiling	5/13/20	5/13/20	5/14/20	5/22/20	N/A	5/27/20	60	6	3	Yes	58 ug/ft2; 30 ug/ft2; <10 ug/ft2		
	7300	1	B	009	Primary	Classroom B1 (ESOL)	yes	W1	5/13/20	5/13/20	5/14/20	5/22/20	N/A	5/27/20	960	24	3	Yes	<10 ug/ft2		
	7300	1	B	009	Primary	Classroom B1 (ESOL)	yes	W2	5/13/20	5/13/20	5/14/20	5/22/20	N/A	5/27/20	Included with wall 1	Included with wall 1	-	-	-		
	7300	1	B	009	Primary	Classroom B1 (ESOL)	yes	W3	5/13/20	5/13/20	5/14/20	5/22/20	N/A	5/27/20	Included with wall 1	Included with wall 1	-	-	-		
	7300	1	B	009	Primary	Classroom B1 (ESOL)	yes	W4	5/13/20	5/13/20	5/14/20	5/22/20	N/A	5/27/20	Included with wall 1	Included with wall 1	-	-	-		
	7300	1	B	010	Storage	Classroom B1 Closet (Rear of Classroom)	yes	W1	5/13/20	5/13/20	5/14/20	5/22/20	N/A	5/27/20	Included with ceiling	Included with ceiling	-	-	-		
	7300	1	B	010	Storage	Classroom B1 Closet (Rear of Classroom)	yes	W2	5/13/20	5/13/20	5/14/20	5/22/20	N/A	5/27/20	Included with ceiling	Included with ceiling	-	-	-		
	7300	1	B	010	Storage	Classroom B1 Closet (Rear of Classroom)	yes	W3	5/13/20	5/13/20	5/14/20	5/22/20	N/A	5/27/20	Included with ceiling	Included with ceiling	-	-	-		
	7300	1	B	010	Storage	Classroom B1 Closet (Rear of Classroom)	yes	W4	5/13/20	5/13/20	5/14/20	5/22/20	N/A	5/27/20	Included with ceiling	Included with ceiling	-	-	-		
	7300	1	B	010	Storage	Classroom B1 Closet (Rear of Classroom)	yes	Ceiling	5/13/20	5/13/20	5/14/20	5/22/20	N/A	5/27/20	50	2	1	Yes	<10 ug/ft2		
	7300	1	B	011	Storage	Classroom B1 Closet (Adjacent to Entrance)	yes	W1	5/13/20	5/13/20	5/14/20	5/22/20	N/A	5/27/20	50	2	0	N/A	N/A		
	7300	1	B	011	Storage	Classroom B1 Closet (Adjacent to Entrance)	yes	W2	5/13/20	5/13/20	5/14/20	5/22/20	N/A	5/27/20	Included with wall 1	Included with wall 1	-	-	-		
	7300	1	B	011	Storage	Classroom B1 Closet (Adjacent to Entrance)	yes	W3	5/13/20	5/13/20	5/14/20	5/22/20	N/A	5/27/20	Included with wall 1	Included with wall 1	-	-	-		
	7300	1	B	011	Storage	Classroom B1 Closet (Adjacent to Entrance)	yes	W4	5/13/20	5/13/20	5/14/20	5/22/20	N/A	5/27/20	Included with wall 1	Included with wall 1	-	-	-		
	7300	1	B	011	Storage	Classroom B1 Closet (Adjacent to Entrance)	yes	Pipe	5/13/20	5/13/20	5/14/20	5/22/20	N/A	5/27/20	Included with wall 1	Included with wall 1	-	-	-		
	7300	1	B	S03	Stairs	Stairwell next to Classroom B1	yes	Tread	N/A	N/A	4/29/20	5/6/20	N/A	5/7/20	55	2	0	N/A	N/A		
	7300	1	B	S03	Stairs	Stairwell next to Classroom B1	yes	Stringer	N/A	N/A	4/29/20	5/6/20	N/A	5/7/20	Included with Tread	Included with Tread	-	-	-		
	7300	1	B	S03	Stairs	Stairwell next to Classroom B1	yes	Riser	N/A	N/A	4/29/20	5/6/20	N/A	5/7/20	Included with Tread	Included with Tread	-	-	-		
	7300	1	B	S03	Stairs	Stairwell next to Classroom B1	yes	Newel Post	N/A	N/A	4/29/20	5/6/20	N/A	5/7/20	Included with Tread	Included with Tread	-	-	-		
	7300	1	B	S03	Stairs	Stairwell next to Classroom B1	yes	Handrail	N/A	N/A	4/29/20	5/6/20	N/A	5/7/20	Included with Tread	Included with Tread	-	-	-		
	7300	1	B	H03	Circulation (Hallway)	Hallway outside Classrooms B1 and B2	yes	Tread	N/A	N/A	4/27/20	5/12/20	N/A	5/13/20	Included with ceiling	Included with ceiling	-	-	-		
	7300	1	B	H03	Circulation (Hallway)	Hallway outside Classrooms B1 and B2	yes	Riser	N/A	N/A	4/27/20	5/12/20	N/A	5/13/20	Included with ceiling	Included with ceiling	-	-	-		
	7300	1	B	H03	Circulation (Hallway)	Hallway outside Classrooms B1 and B2	yes	Handrail	N/A	N/A	4/27/20	5/12/20	N/A	5/13/20	Included with ceiling	Included with ceiling	-	-	-		
	7300	1	B	H03	Circulation (Hallway)	Hallway outside Classrooms B1 and B2	yes	Ceiling	N/A	N/A	4/27/20	5/12/20	N/A	5/13/20	770	20	0	N/A	N/A		
	7300	1	1	113	General Administrative Reception Area	Main Office	yes	W1	N/A	4/29/20	4/30/20	5/5/20	5/19/20	5/7/20	504	13	2	Yes	<10 ug/ft2		

Hopkinson

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Student/Teacher Occupied	Primary Component	Pre-Cleaning Completed (date)	Contents Moved (date)	Work Area Prepped (date)	Surfaces Stabilized (date)	Contents Back in Place (date)	Final Inspection Approval and Photos (date)	Square Footage of Work Area	Number of Required RRP Wipes	Number of Colorimetric Wipes Used to Pass	Final Colorimetric Wipe Submitted for AAS Analysis (yes/no)	AAS Analysis Results	Comments from Assessment	Comments from Oversight
	7300	1	1	113	General Administrative Reception Area	Main Office	yes	W3	N/A	4/29/20	4/30/20	5/5/20	5/19/20	5/7/20	Included with wall 1	Included with wall 1	-	-	-		
	7300	1	1	113	General Administrative Reception Area	Main Office	yes	W4	N/A	4/29/20	4/30/20	5/5/20	5/19/20	5/7/20	Included with wall 1	Included with wall 1	-	-	-		
	7300	1	1	113A	Storage	Main Office Closet	yes	W1	N/A	4/29/20	4/30/20	5/5/20	5/19/20	5/7/20	Included with ceiling	Included with ceiling	-	-	-		
	7300	1	1	113A	Storage	Main Office Closet	yes	Pipe	N/A	4/29/20	4/30/20	5/5/20	5/19/20	5/7/20	Included with ceiling	Included with ceiling	-	-	-		
	7300	1	1	113A	Storage	Main Office Closet	yes	W2	N/A	4/29/20	4/30/20	5/5/20	5/19/20	5/7/20	Included with ceiling	Included with ceiling	-	-	-		
	7300	1	1	113A	Storage	Main Office Closet	yes	W3	N/A	4/29/20	4/30/20	5/5/20	5/19/20	5/7/20	Included with ceiling	Included with ceiling	-	-	-		
	7300	1	1	113A	Storage	Main Office Closet	yes	W4	N/A	4/29/20	4/30/20	5/5/20	5/19/20	5/7/20	Included with ceiling	Included with ceiling	-	-	-		
	7300	1	1	113A	Storage	Main Office Closet	yes	Ceiling	N/A	4/29/20	4/30/20	5/5/20	5/19/20	5/7/20	250	14	2	Yes	25 ug/ft2; <10 ug/ft2		
	7300	1	1	114	Principal/Director's Office	Principal's Office	yes	W2	N/A	4/29/20	4/30/20	5/5/20	5/19/20	5/7/20	210	6	1	Yes	<10 ug/ft2		
	7300	1	1	114	Principal/Director's Office	Principal's Office	yes	W3	N/A	4/29/20	4/30/20	5/5/20	5/19/20	5/7/20	Included with wall 2	Included with wall 2	-	-	-		
	7300	1	1	114	Principal/Director's Office	Principal's Office	yes	W4	N/A	4/29/20	4/30/20	5/5/20	5/19/20	5/7/20	Included with wall 2	Included with wall 2	-	-	-		
	7300	1	1	114A	Storage	Principal's Closet	yes	W2	N/A	4/29/20	4/30/20	5/5/20	5/19/20	5/7/20	Included with ceiling	Included with ceiling	-	-	-		
	7300	1	1	114A	Storage	Principal's Closet	yes	W3	N/A	4/29/20	4/30/20	5/5/20	5/19/20	5/7/20	Included with ceiling	Included with ceiling	-	-	-		
	7300	1	1	114A	Storage	Principal's Closet	yes	W4	N/A	4/29/20	4/30/20	5/5/20	5/19/20	5/7/20	Included with ceiling	Included with ceiling	-	-	-		
	7300	1	1	114A	Storage	Principal's Closet	yes	Ceiling	N/A	4/29/20	4/30/20	5/5/20	5/19/20	5/7/20	36	3	3	Yes	22 ug/ft2; 11 ug/ft2; <10 ug/ft2		
	7300	1	1	H114	Circulation (Hallway)	Principal's Hallway	yes	W1	N/A	4/29/20	4/30/20	5/5/20	N/A	5/7/20	60	2	0	N/A	N/A		
	7300	1	1	H114	Circulation (Hallway)	Principal's Hallway	yes	W3	N/A	4/29/20	4/30/20	5/5/20	N/A	5/7/20	Included with wall 1	Included with wall 1	-	-	-		
	7300	1	1	S13	Stairs	Stairwell outside Classroom 101	yes	Riser	N/A	N/A	4/14/20	4/20/20	N/A	5/7/20	120	3	0	N/A	N/A		
	7300	1	1	S13	Stairs	Stairwell outside Classroom 101	yes	Stringer	N/A	N/A	4/14/20	4/20/20	N/A	5/7/20	Included with riser	Included with riser	-	-	-		
	7300	1	1	S13	Stairs	Stairwell outside Classroom 101	yes	Newel Post	N/A	N/A	4/14/20	4/20/20	N/A	5/7/20	Included with riser	Included with riser	-	-	-		
	7300	1	1	100	Restrooms, Staff - Female	Women's Restroom next to Classroom 101	yes	W4	N/A	N/A	4/17/20	4/22/20	N/A	5/7/20	100	3	0	N/A	N/A		
	7300	1	1	101	Primary	Classroom 101	yes	W1	4/13/20	4/13/20	4/17/20	4/22/20	N/A	5/7/20	928	24	3	Yes	<10 ug/ft2		
	7300	1	1	101	Primary	Classroom 101	yes	W2	4/13/20	4/13/20	4/17/20	4/22/20	N/A	5/7/20	Included with wall 1	Included with wall 1	-	-	-	majority of wall covered by wooden bookcase	
	7300	1	1	101	Primary	Classroom 101	yes	W3	4/13/20	4/13/20	4/17/20	4/22/20	N/A	5/7/20	Included with wall 1	Included with wall 1	-	-	-		
	7300	1	1	101	Primary	Classroom 101	yes	W4	4/13/20	4/13/20	4/17/20	4/22/20	N/A	5/7/20	Included with wall 1	Included with wall 1	-	-	-		
	7300	1	1	101B	Student Restrooms - Male/Female (Classroom)	Classroom 101 Restroom	yes	W2	N/A	N/A	4/17/20	4/22/20	N/A	5/7/20	72	2	1	Yes	<10 ug/ft2		
	7300	1	1	101B	Student Restrooms - Male/Female (Classroom)	Classroom 101 Restroom	yes	W3	N/A	N/A	4/17/20	4/22/20	N/A	5/7/20	Included with wall 2	Included with wall 2	-	-	-		
	7300	1	1	101B	Student Restrooms - Male/Female (Classroom)	Classroom 101 Restroom	yes	W4	N/A	N/A	4/17/20	4/22/20	N/A	5/7/20	Included with wall 2	Included with wall 2	-	-	-		
	7300	1	1	102	Primary	Classroom 102	yes	W2	4/13/20	4/13/20	4/17/20	4/22/20	N/A	5/7/20	870	22	3	Yes	<10 ug/ft2		
	7300	1	1	102	Primary	Classroom 102	yes	W3	4/13/20	4/13/20	4/17/20	4/22/20	N/A	5/7/20	Included with wall 2	Included with wall 2	-	-	-	behind radiator	
	7300	1	1	102	Primary	Classroom 102	yes	W4	4/13/20	4/13/20	4/17/20	4/22/20	N/A	5/7/20	Included with wall 2	Included with wall 2	-	-	-		
	7300	1	1	102A	Storage	Classroom 102 Coat Room	yes	W1	4/13/20	4/13/20	4/17/20	4/22/20	N/A	5/7/20	78	2	1	Yes	<10 ug/ft2	wall covered by wooden book case/closet	
	7300	1	1	102A	Storage	Classroom 102 Coat Room	yes	W2	4/13/20	4/13/20	4/17/20	4/22/20	N/A	5/7/20	Included with wall 1	Included with wall 1	-	-	-		
	7300	1	1	102A	Storage	Classroom 102 Coat Room	yes	W4	4/13/20	4/13/20	4/17/20	4/22/20	N/A	5/7/20	Included with wall 1	Included with wall 1	-	-	-		
	7300	1	1	103	Primary	Classroom 103	yes	W1	4/13/20	4/13/20	4/17/20	4/22/20	N/A	5/7/20	928	24	3	Yes	<10 ug/ft2		
	7300	1	1	103	Primary	Classroom 103	yes	W2	4/13/20	4/13/20	4/17/20	4/22/20	N/A	5/7/20	Included with wall 1	Included with wall 1	-	-	-		

Hopkinson

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Student/ Teacher Occupied	Primary Component	Pre-Cleaning Completed (date)	Contents Moved (date)	Work Area Prepped (date)	Surfaces Stabilized (date)	Contents Back in Place (date)	Final Inspection Approval and Photos (date)	Square Footage of Work Area	Number of Required RRP Wipes	Number of Colorimetric Wipes Used to Pass	Final Colorimetric Wipe Submitted for AAS Analysis (yes/no)	AAS Analysis Results	Comments from Assessment	Comments from Oversight
	7300	1	1	103	Primary	Classroom 103	yes	W3	4/13/20	4/13/20	4/17/20	4/22/20	N/A	5/7/20	Included with wall 1	Included with wall 1	-	-	-		
	7300	1	1	103	Primary	Classroom 103	yes	W4	4/13/20	4/13/20	4/17/20	4/22/20	N/A	5/7/20	Included with wall 1	Included with wall 1	-	-	-		
	7300	1	1	103B	Storage	Classroom 103 Storage Closet	yes	W1	4/13/20	4/13/20	4/17/20	4/22/20	N/A	5/7/20	Included with ceiling	Included with ceiling	-	-	-	flaking above ceiling	
	7300	1	1	103B	Storage	Classroom 103 Storage Closet	yes	W2	4/13/20	4/13/20	4/17/20	4/22/20	N/A	5/7/20	Included with ceiling	Included with ceiling	-	-	-		
	7300	1	1	103B	Storage	Classroom 103 Storage Closet	yes	W3	4/13/20	4/13/20	4/17/20	4/22/20	N/A	5/7/20	Included with ceiling	Included with ceiling	-	-	-	wall blocked by wood bookshelf	
	7300	1	1	103B	Storage	Classroom 103 Storage Closet	yes	W4	4/13/20	4/13/20	4/17/20	4/22/20	N/A	5/7/20	Included with ceiling	Included with ceiling	-	-	-	wall blocked by wood bookshelf	
	7300	1	1	103B	Storage	Classroom 103 Storage Closet	yes	Ceiling	4/13/20	4/13/20	4/17/20	4/22/20	N/A	5/7/20	Included with ceiling	Included with ceiling	-	-	-		
	7300	1	1	S12	Stairs	Stairwell outside Classroom 103	yes	W1	N/A	N/A	4/14/20	4/20/20	N/A	4/22/20	Included with ceiling	Included with ceiling	-	-	-		
	7300	1	1	S12	Stairs	Stairwell outside Classroom 103	yes	Door	N/A	N/A	4/14/20	4/20/20	N/A	4/22/20	Included with ceiling	Included with ceiling	-	-	-		
	7300	1	1	S12	Stairs	Stairwell outside Classroom 103	yes	Door Frame	N/A	N/A	4/14/20	4/20/20	N/A	4/22/20	Included with ceiling	Included with ceiling	-	-	-		
	7300	1	1	S12	Stairs	Stairwell outside Classroom 103	yes	W2	N/A	N/A	4/14/20	4/20/20	N/A	4/22/20	Included with ceiling	Included with ceiling	-	-	-		
	7300	1	1	S12	Stairs	Stairwell outside Classroom 103	yes	Door	N/A	N/A	4/14/20	4/20/20	N/A	4/22/20	Included with ceiling	Included with ceiling	-	-	-		
	7300	1	1	S12	Stairs	Stairwell outside Classroom 103	yes	Door Frame	N/A	N/A	4/14/20	4/20/20	N/A	4/22/20	Included with ceiling	Included with ceiling	-	-	-		
	7300	1	1	S12	Stairs	Stairwell outside Classroom 103	yes	W4	N/A	N/A	4/14/20	4/20/20	N/A	4/22/20	Included with ceiling	Included with ceiling	-	-	-		
	7300	1	1	S12	Stairs	Stairwell outside Classroom 103	yes	Ceiling	N/A	N/A	4/14/20	4/20/20	N/A	4/22/20	Included with ceiling	Included with ceiling	-	-	-		
	7300	1	1	S12	Stairs	Stairwell outside Classroom 103	yes	Tread	N/A	N/A	4/14/20	4/20/20	N/A	4/22/20	Included with ceiling	Included with ceiling	-	-	-		
	7300	1	1	S12	Stairs	Stairwell outside Classroom 103	yes	Stringer	N/A	N/A	4/14/20	4/20/20	N/A	4/22/20	Included with ceiling	Included with ceiling	-	-	-		
	7300	1	1	S12	Stairs	Stairwell outside Classroom 103	yes	Riser	N/A	N/A	4/14/20	4/20/20	N/A	4/22/20	Included with ceiling	Included with ceiling	-	-	-		
	7300	1	1	S12	Stairs	Stairwell outside Classroom 103	yes	Newel Post	N/A	N/A	4/14/20	4/20/20	N/A	4/22/20	Included with ceiling	Included with ceiling	-	-	-		
	7300	1	1	S12	Stairs	Stairwell outside Classroom 103	yes	Handrail	N/A	N/A	4/14/20	4/20/20	N/A	4/22/20	Included with ceiling	Included with ceiling	-	-	-		
	7300	1	1	H14	Circulation (Hallway)	Hallway from Classrooms 101 to 103	yes	Door	N/A	N/A	5/20/20	5/22/20	N/A	5/22/20	50	2	0	N/A	N/A		
	7300	1	1	H14	Circulation (Hallway)	Hallway from Classrooms 101 to 103	yes	Door Frame	N/A	N/A	5/20/20	5/22/20	N/A	5/22/20	Included with door	Included with door	-	-	-		
	7300	1	1	103B	Student Restrooms - Female (4-12)	Girl's Restroom	yes	W2	N/A	N/A	4/13/20	4/20/20	N/A	5/7/20	Included with ceiling	Included with ceiling	-	-	-		
	7300	1	1	103B	Student Restrooms - Female (4-12)	Girl's Restroom	yes	Ceiling	N/A	N/A	4/13/20	4/20/20	N/A	5/7/20	186	5	0	N/A	N/A		
	7300	1	1	104	Primary	Classroom 104	yes	W3	4/13/20	4/13/20	4/17/20	4/20/20	N/A	5/7/20	175	5	1	Yes	<10 ug/ft2	behind radiator	
	7300	1	1	104A	Storage	Classroom 104 Coat Room	yes	W1	4/13/20	4/13/20	4/17/20	4/20/20	N/A	5/7/20	78	2	1	Yes	<10 ug/ft2		
	7300	1	1	104A	Storage	Classroom 104 Coat Room	yes	W2	4/13/20	4/13/20	4/17/20	4/20/20	N/A	5/7/20	Included with wall 1	Included with wall 1	-	-	-		
	7300	1	1	104A	Storage	Classroom 104 Coat Room	yes	W3	4/13/20	4/13/20	4/17/20	4/20/20	N/A	5/7/20	Included with wall 1	Included with wall 1	-	-	-	most of wall covered by metal shelf	
	7300	1	1	104A	Storage	Classroom 104 Coat Room	yes	W4	4/13/20	4/13/20	4/17/20	4/20/20	N/A	5/7/20	Included with wall 1	Included with wall 1	-	-	-		
	7300	1	1	105	Primary	Classroom 105	yes	W1	4/13/20	4/13/20	4/17/20	4/20/20	N/A	5/7/20	435	11	2	Yes	<10 ug/ft2		
	7300	1	1	105	Primary	Classroom 105	yes	W3	4/13/20	4/13/20	4/17/20	4/20/20	N/A	5/7/20	Included with wall 1	Included with wall 1	-	-	-		
	7300	1	1	105	Primary	Classroom 105	yes	W4	4/13/20	4/13/20	4/17/20	4/20/20	N/A	5/7/20	Included with wall 1	Included with wall 1	-	-	-		
	7300	1	1	105A	Storage	Classroom 105 Coat Room	yes	W3	4/13/20	4/13/20	4/17/20	4/20/20	N/A	5/7/20	90	3	1	Yes	<10 ug/ft2		
	7300	1	1	S15A	Stairs	Auditorium Entrance Staircase across from Classroom 105	yes	W2	N/A	N/A	4/23/20	5/8/20	N/A	5/8/20	300	8	0	N/A	N/A		
	7300	1	1	S15A	Stairs	Auditorium Entrance Staircase across from Classroom 105	yes	W3	N/A	N/A	4/23/20	5/8/20	N/A	5/8/20	Included with wall 2	Included with wall 2	-	-	-		
	7300	1	1	S15A	Stairs	Auditorium Entrance Staircase across from Classroom 105	yes	W4	N/A	N/A	4/23/20	5/8/20	N/A	5/8/20	Included with wall 2	Included with wall 2	-	-	-		
	7300	1	1	S15B	Stairs	Auditorium Entrance Staircase across from Classroom 106	yes	W3	N/A	N/A	4/23/20	5/8/20	N/A	5/8/20	Included with ceiling	Included with ceiling	-	-	-		
	7300	1	1	S15B	Stairs	Auditorium Entrance Staircase across from Classroom 106	yes	Ceiling	N/A	N/A	4/23/20	5/8/20	N/A	5/8/20	300	8	0	N/A	N/A		
	7300	1	1	112	Auditorium	Auditorium	yes	W1	N/A	N/A	5/6/20	5/22/20	N/A	5/30/20	2756	69	7	Yes	(4) <10 ug/ft2		
	7300	1	1	112	Auditorium	Auditorium	yes	W2	N/A	N/A	5/6/20	5/22/20	N/A	5/30/20	Included with wall 1	Included with wall 1	-	-	-		

Hopkinson

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Student/ Teacher Occupied	Primary Component	Pre-Cleaning Completed (date)	Contents Moved (date)	Work Area Prepped (date)	Surfaces Stabilized (date)	Contents Back in Place (date)	Final Inspection Approval and Photos (date)	Square Footage of Work Area	Number of Required RRP Wipes	Number of Colorimetric Wipes Used to Pass	Final Colorimetric Wipe Submitted for AAS Analysis (yes/no)	AAS Analysis Results	Comments from Assessment	Comments from Oversight
	7300	1	1	112	Auditorium	Auditorium	yes	W4	N/A	N/A	5/6/20	5/22/20	N/A	5/30/20	Included with wall 1	Included with wall 1	-	-	-		
	7300	1	1	112A	Stage	Stage	yes	W2	N/A	N/A	5/6/20	5/22/20	N/A	5/30/20	920	23	3	Yes	<10 ug/ft2		
	7300	1	1	112A	Stage	Stage	yes	W3	N/A	N/A	5/6/20	5/22/20	N/A	5/30/20	Included with wall 2	Included with wall 2	-	-	-		
	7300	1	1	112A	Stage	Stage	yes	W4	N/A	N/A	5/6/20	5/22/20	N/A	5/30/20	Included with wall 2	Included with wall 2	-	-	-		
	7300	1	1	112B	Storage	Stage Left Storage Room (Main Office Side)	yes	W1	N/A	N/A	5/6/20	5/21/20	N/A	5/30/20	Included with ceiling	Included with ceiling	-	-	-		
	7300	1	1	112B	Storage	Stage Left Storage Room (Main Office Side)	yes	W2	N/A	N/A	5/6/20	5/21/20	N/A	5/30/20	Included with ceiling	Included with ceiling	-	-	-		
	7300	1	1	112B	Storage	Stage Left Storage Room (Main Office Side)	yes	W3	N/A	N/A	5/6/20	5/21/20	N/A	5/30/20	Included with ceiling	Included with ceiling	-	-	-		
	7300	1	1	112B	Storage	Stage Left Storage Room (Main Office Side)	yes	W4	N/A	N/A	5/6/20	5/21/20	N/A	5/30/20	Included with ceiling	Included with ceiling	-	-	-		
	7300	1	1	112B	Storage	Stage Left Storage Room (Main Office Side)	yes	Ceiling	N/A	N/A	5/6/20	5/21/20	N/A	5/30/20	140	12	3	Yes	<10 ug/ft2; 13 ug/ft2; 14 ug/ft2		
	7300	1	1	112C	Storage	Stage Right Storage Room (Classroom 110 Side)	yes	W1	N/A	N/A	5/6/20	5/21/20	N/A	5/30/20	Included with ceiling	Included with ceiling	-	-	-		
	7300	1	1	112C	Storage	Stage Right Storage Room (Classroom 110 Side)	yes	W2	N/A	N/A	5/6/20	5/21/20	N/A	5/30/20	Included with ceiling	Included with ceiling	-	-	-		
	7300	1	1	112C	Storage	Stage Right Storage Room (Classroom 110 Side)	yes	W3	N/A	N/A	5/6/20	5/21/20	N/A	5/30/20	Included with ceiling	Included with ceiling	-	-	-		
	7300	1	1	112C	Storage	Stage Right Storage Room (Classroom 110 Side)	yes	W4	N/A	N/A	5/6/20	5/21/20	N/A	5/30/20	Included with ceiling	Included with ceiling	-	-	-		
	7300	1	1	112C	Storage	Stage Right Storage Room (Classroom 110 Side)	yes	Ceiling	N/A	N/A	5/6/20	5/21/20	N/A	5/30/20	140	4	1	Yes	<10 ug/ft2		
	7300	1	1	106	Primary	Classroom 106	yes	W1	4/13/20	4/13/20	4/20/20	4/23/20	N/A	5/7/20	870	22	3	Yes	<10 ug/ft2		
	7300	1	1	106	Primary	Classroom 106	yes	W3	4/13/20	4/13/20	4/20/20	4/23/20	N/A	5/7/20	Included with wall 1	Included with wall 1	-	-	-		
	7300	1	1	106	Primary	Classroom 106	yes	W4	4/13/20	4/13/20	4/20/20	4/23/20	N/A	5/7/20	Included with wall 1	Included with wall 1	-	-	-		
	7300	1	1	106A	Storage	Classroom 106 Coat Room	yes	W1	4/13/20	4/13/20	4/20/20	4/23/20	N/A	5/7/20	60	2	1	Yes	<10 ug/ft2		
	7300	1	1	106A	Storage	Classroom 106 Coat Room	yes	W3	4/13/20	4/13/20	4/20/20	4/23/20	N/A	5/7/20	Included with wall 1	Included with wall 1	-	-	-		
	7300	1	1	106A	Storage	Classroom 106 Coat Room	yes	W4	4/13/20	4/13/20	4/20/20	4/23/20	N/A	5/7/20	Included with wall 1	Included with wall 1	-	-	-		
	7300	1	1	107	Primary	Classroom 107	yes	W1	4/13/20	4/13/20	4/20/20	4/23/20	N/A	5/7/20	870	22	3	Yes	<10 ug/ft2		
	7300	1	1	107	Primary	Classroom 107	yes	W2	4/13/20	4/13/20	4/20/20	4/23/20	N/A	5/7/20	Included with wall 1	Included with wall 1	-	-	-		
	7300	1	1	107	Primary	Classroom 107	yes	W3	4/13/20	4/13/20	4/20/20	4/23/20	N/A	5/7/20	Included with wall 1	Included with wall 1	-	-	-		
	7300	1	1	107	Primary	Classroom 107	yes	W4	4/13/20	4/13/20	4/20/20	4/23/20	N/A	5/7/20	Included with wall 1	Included with wall 1	-	-	-		
	7300	1	1	107A	Storage	Classroom 107 Coat Room	yes	W1	4/13/20	4/13/20	4/20/20	4/23/20	N/A	5/7/20	60	2	1	Yes	<10 ug/ft2		
	7300	1	1	107A	Storage	Classroom 107 Coat Room	yes	W3	4/13/20	4/13/20	4/20/20	4/23/20	N/A	5/7/20	Included with wall 1	Included with wall 1	-	-	-		
	7300	1	1	107A	Storage	Classroom 107 Coat Room	yes	W4	4/13/20	4/13/20	4/20/20	4/23/20	N/A	5/7/20	Included with wall 1	Included with wall 1	-	-	-		
	7300	1	1	S14	Stairs	Fire Tower across from Classroom 107	yes	W1	N/A	N/A	4/30/20	5/6/20	N/A	5/8/20	Included with ceiling	Included with ceiling	-	-	-		
	7300	1	1	S14	Stairs	Fire Tower across from Classroom 107	yes	Door	N/A	N/A	4/30/20	5/6/20	N/A	5/8/20	Included with ceiling	Included with ceiling	-	-	-		
	7300	1	1	S14	Stairs	Fire Tower across from Classroom 107	yes	Door Frame	N/A	N/A	4/30/20	5/6/20	N/A	5/8/20	Included with ceiling	Included with ceiling	-	-	-		
	7300	1	1	S14	Stairs	Fire Tower across from Classroom 107	yes	W2	N/A	N/A	4/30/20	5/6/20	N/A	5/8/20	Included with ceiling	Included with ceiling	-	-	-		
	7300	1	1	S14	Stairs	Fire Tower across from Classroom 107	yes	Pipe	N/A	N/A	4/30/20	5/6/20	N/A	5/8/20	Included with ceiling	Included with ceiling	-	-	-		
	7300	1	1	S14	Stairs	Fire Tower across from Classroom 107	yes	W3	N/A	N/A	4/30/20	5/6/20	N/A	5/8/20	Included with ceiling	Included with ceiling	-	-	-		
	7300	1	1	S14	Stairs	Fire Tower across from Classroom 107	yes	Door	N/A	N/A	4/30/20	5/6/20	N/A	5/8/20	Included with ceiling	Included with ceiling	-	-	-		
	7300	1	1	S14	Stairs	Fire Tower across from Classroom 107	yes	Door Frame	N/A	N/A	4/30/20	5/6/20	N/A	5/8/20	Included with ceiling	Included with ceiling	-	-	-		
	7300	1	1	S14	Stairs	Fire Tower across from Classroom 107	yes	W4	N/A	N/A	4/30/20	5/6/20	N/A	5/8/20	Included with ceiling	Included with ceiling	-	-	-		
	7300	1	1	S14	Stairs	Fire Tower across from Classroom 107	yes	Window Safety Bars	N/A	N/A	4/30/20	5/6/20	N/A	5/8/20	Included with ceiling	Included with ceiling	-	-	-		
	7300	1	1	S14	Stairs	Fire Tower across from Classroom 107	yes	Ceiling	N/A	N/A	4/30/20	5/6/20	N/A	5/8/20	230	6	0	N/A	N/A		

Hopkinson

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Student/ Teacher Occupied	Primary Component	Pre-Cleaning Completed (date)	Contents Moved (date)	Work Area Prepped (date)	Surfaces Stabilized (date)	Contents Back in Place (date)	Final Inspection Approval and Photos (date)	Square Footage of Work Area	Number of Required RRP Wipes	Number of Colorimetric Wipes Used to Pass	Final Colorimetric Wipe Submitted for AAS Analysis (yes/no)	AAS Analysis Results	Comments from Assessment	Comments from Oversight
	7300	1	1	107B	Student Restrooms - Male (4-12)	Boy's Restroom	yes	W1	N/A	N/A	4/20/20	4/23/20	N/A	5/7/20	Included with ceiling	Included with ceiling	-	-	-		
	7300	1	1	107B	Student Restrooms - Male (4-12)	Boy's Restroom	yes	W4	N/A	N/A	4/20/20	4/23/20	N/A	5/7/20	Included with ceiling	Included with ceiling	-	-	-		
	7300	1	1	107B	Student Restrooms - Male (4-12)	Boy's Restroom	yes	Ceiling	N/A	N/A	4/20/20	4/23/20	N/A	5/7/20	186	20	4	Yes	190 ug/ft2; 12 ug/ft2; (2) <10 ug/ft2		
	7300	1	1	H15	Circulation (Hallway)	Hallway from Classrooms 104 to 107	yes	W1	N/A	N/A	4/23/20	5/15/20	N/A	5/18/20	Included with ceiling	Included with ceiling	-	-	-		
	7300	1	1	H15	Circulation (Hallway)	Hallway from Classrooms 104 to 107	yes	W3	N/A	N/A	4/23/20	5/15/20	N/A	5/18/20	Included with ceiling	Included with ceiling	-	-	-		
	7300	1	1	H15	Circulation (Hallway)	Hallway from Classrooms 104 to 107	yes	Door	N/A	N/A	4/23/20	5/15/20	N/A	5/18/20	Included with ceiling	Included with ceiling	-	-	-		
	7300	1	1	H15	Circulation (Hallway)	Hallway from Classrooms 104 to 107	yes	Door Frame	N/A	N/A	4/23/20	5/15/20	N/A	5/18/20	Included with ceiling	Included with ceiling	-	-	-		
	7300	1	1	H15	Circulation (Hallway)	Hallway from Classrooms 104 to 107	yes	W4	N/A	N/A	4/23/20	5/15/20	N/A	5/18/20	Included with ceiling	Included with ceiling	-	-	-		
	7300	1	1	H15	Circulation (Hallway)	Hallway from Classrooms 104 to 107	yes	Ceiling	N/A	N/A	4/23/20	5/15/20	N/A	5/18/20	1496	38	0	N/A	N/A		
	7300	1	1	S11	Stairs	Stairwell next to Classroom 108	yes	W1	N/A	N/A	3/27/20	4/9/20	N/A	4/9/20	Included with ceiling	Included with ceiling	-	-	-		
	7300	1	1	S11	Stairs	Stairwell next to Classroom 108	yes	W2	N/A	N/A	3/27/20	4/9/20	N/A	4/9/20	Included with ceiling	Included with ceiling	-	-	-		
	7300	1	1	S11	Stairs	Stairwell next to Classroom 108	yes	Door	N/A	N/A	3/27/20	4/9/20	N/A	4/9/20	Included with ceiling	Included with ceiling	-	-	-		
	7300	1	1	S11	Stairs	Stairwell next to Classroom 108	yes	Door Frame	N/A	N/A	3/27/20	4/9/20	N/A	4/9/20	Included with ceiling	Included with ceiling	-	-	-		
	7300	1	1	S11	Stairs	Stairwell next to Classroom 108	yes	W4	N/A	N/A	3/27/20	4/9/20	N/A	4/9/20	Included with ceiling	Included with ceiling	-	-	-		
	7300	1	1	S11	Stairs	Stairwell next to Classroom 108	yes	Ceiling	N/A	N/A	3/27/20	4/9/20	N/A	4/9/20	297	8	0	N/A	N/A		
	7300	1	1	S11	Stairs	Stairwell next to Classroom 108	yes	Tread	N/A	N/A	3/27/20	4/9/20	N/A	4/9/20	Included with wall 1	Included with wall 1	-	-	-		
	7300	1	1	S11	Stairs	Stairwell next to Classroom 108	yes	Riser	N/A	N/A	3/27/20	4/9/20	N/A	4/9/20	Included with wall 1	Included with wall 1	-	-	-		
	7300	1	1	S11	Stairs	Stairwell next to Classroom 108	yes	Newel Post	N/A	N/A	3/27/20	4/9/20	N/A	4/9/20	Included with wall 1	Included with wall 1	-	-	-		
	7300	1	1	108	Primary	Classroom 108	yes	W1	4/13/20	4/13/20	4/21/20	4/24/20		5/7/20	928	24	3	Yes	<10 ug/ft2		
	7300	1	1	108	Primary	Classroom 108	yes	W2	4/13/20	4/13/20	4/21/20	4/24/20		5/7/20	Included with wall 1	Included with wall 1	-	-	-		
	7300	1	1	108	Primary	Classroom 108	yes	W3	4/13/20	4/13/20	4/21/20	4/24/20		5/7/20	Included with wall 1	Included with wall 1	-	-	-	damage behind radiator	
	7300	1	1	108	Primary	Classroom 108	yes	W4	4/13/20	4/13/20	4/21/20	4/24/20		5/7/20	Included with wall 1	Included with wall 1	-	-	-		
	7300	1	1	108B	Student Restrooms - Male/Female (Classroom)	Classroom 108 Restroom	yes	W1	N/A	N/A	4/21/20	4/24/20		5/7/20	48	2	0	N/A	N/A		
	7300	1	1	108B	Student Restrooms - Male/Female (Classroom)	Classroom 108 Restroom	yes	W2	N/A	N/A	4/21/20	4/24/20		5/7/20	Included with wall 1	Included with wall 1	-	-	-		
	7300	1	1	108B	Student Restrooms - Male/Female (Classroom)	Classroom 108 Restroom	yes	W3	N/A	N/A	4/21/20	4/24/20		5/7/20	Included with wall 1	Included with wall 1	-	-	-		
	7300	1	1	108A	Storage	Classroom 108 Coat Room	yes	W1	4/13/20	4/13/20	4/21/20	4/24/20		5/7/20	60	2	1	Yes	<10 ug/ft2		
	7300	1	1	108A	Storage	Classroom 108 Coat Room	yes	W3	4/13/20	4/13/20	4/21/20	4/24/20		5/7/20	Included with wall 1	Included with wall 1	-	-	-		
	7300	1	1	108A	Storage	Classroom 108 Coat Room	yes	W4	4/13/20	4/13/20	4/21/20	4/24/20		5/7/20	Included with wall 1	Included with wall 1	-	-	-		
	7300	1	1	109	Primary	Classroom 109	yes	W1	4/13/20	4/13/20	4/21/20	4/24/20		5/7/20	870	22	3	Yes	<10 ug/ft2		
	7300	1	1	109	Primary	Classroom 109	yes	W3	4/13/20	4/13/20	4/21/20	4/24/20		5/7/20	Included with wall 1	Included with wall 1	-	-	-		
	7300	1	1	109A	Storage	Classroom 109 Coat Room	yes	W2	4/13/20	4/13/20	4/21/20	4/24/20		5/7/20	60	2	1	Yes	<10 ug/ft2		
	7300	1	1	109A	Storage	Classroom 109 Coat Room	yes	W3	4/13/20	4/13/20	4/21/20	4/24/20		5/7/20	Included with wall 2	Included with wall 2	-	-	-		
	7300	1	1	109A	Storage	Classroom 109 Coat Room	yes	W4	4/13/20	4/13/20	4/21/20	4/24/20		5/7/20	Included with wall 2	Included with wall 2	-	-	-		
	7300	1	1	110	Primary	Classroom 110	yes	W1	4/13/20	4/13/20	4/22/20	4/25/20		5/7/20	928	24	3	Yes	<10 ug/ft2		
	7300	1	1	110	Primary	Classroom 110	yes	W2	4/13/20	4/13/20	4/22/20	4/25/20		5/7/20	Included with wall 1	Included with wall 1	-	-	-		
	7300	1	1	110	Primary	Classroom 110	yes	W3	4/13/20	4/13/20	4/22/20	4/25/20		5/7/20	Included with wall 1	Included with wall 1	-	-	-	flaking behind radiator	

Hopkinson

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Student/ Teacher Occupied	Primary Component	Pre-Cleaning Completed (date)	Contents Moved (date)	Work Area Prepped (date)	Surfaces Stabilized (date)	Contents Back in Place (date)	Final Inspection Approval and Photos (date)	Square Footage of Work Area	Number of Required RRP Wipes	Number of Colorimetric Wipes Used to Pass	Final Colorimetric Wipe Submitted for AAS Analysis (yes/no)	AAS Analysis Results	Comments from Assessment	Comments from Oversight
	7300	1	1	110	Primary	Classroom 110	yes	W4	4/13/20	4/13/20	4/22/20	4/25/20		5/7/20	Included with wall 1	Included with wall 1	-	-	-		
	7300	1	1	110A	Storage	Classroom 110 Coat Room	yes	W2	4/13/20	4/13/20	4/22/20	4/25/20		5/7/20	60	2	1	Yes	<10 ug/ft2		
	7300	1	1	110A	Storage	Classroom 110 Coat Room	yes	W3	4/13/20	4/13/20	4/22/20	4/25/20		5/7/20	Included with wall 2	Included with wall 2	-	-	-		
	7300	1	1	110A	Storage	Classroom 110 Coat Room	yes	W4	4/13/20	4/13/20	4/22/20	4/25/20		5/7/20	Included with wall 2	Included with wall 2	-	-	-		
	7300	1	1	111	Restrooms, Staff - Male	Men's Restroom	yes	W1	N/A	N/A	4/22/20	4/25/20		5/7/20	90	3	0	N/A	N/A		
	7300	1	1	111	Restrooms, Staff - Male	Men's Restroom	yes	W2	N/A	N/A	4/22/20	4/25/20		5/7/20	Included with wall 1	Included with wall 1	-	-	-		
	7300	1	1	111	Restrooms, Staff - Male	Men's Restroom	yes	W3	N/A	N/A	4/22/20	4/25/20		5/7/20	Included with wall 1	Included with wall 1	-	-	-		
	7300	1	1	111	Restrooms, Staff - Male	Men's Restroom	yes	W4	N/A	N/A	4/22/20	4/25/20		5/7/20	Included with wall 1	Included with wall 1	-	-	-		
	7300	1	1	H16	Circulation (Hallway)	Hallway from Classrooms 108 to 110	yes	Door	N/A	N/A	4/22/20	5/15/20		5/18/20	Included with pipe	Included with pipe	-	-	-		
	7300	1	1	H16	Circulation (Hallway)	Hallway from Classrooms 108 to 110	yes	Door Frame	N/A	N/A	4/22/20	5/15/20		5/18/20	Included with pipe	Included with pipe	-	-	-		
	7300	1	1	H16	Circulation (Hallway)	Hallway from Classrooms 108 to 110	yes	Pipe	N/A	N/A	4/22/20	5/15/20		5/18/20	100	3	0	N/A	N/A		
	7300	1	1	S17	Stairs	Stairwell outside Classroom 110	yes	W2	N/A	N/A	4/22/20	5/15/20		5/15/20	120	3	0	N/A	N/A		
	7300	1	1	S17	Stairs	Stairwell outside Classroom 110	yes	W3	N/A	N/A	4/22/20	5/15/20		5/15/20	Included with wall 2	Included with wall 2	-	-	-		
	7300	1	1	S17	Stairs	Stairwell outside Classroom 110	yes	W4	N/A	N/A	4/22/20	5/15/20		5/15/20	Included with wall 2	Included with wall 2	-	-	-		
	7300	1	1	S17	Stairs	Stairwell outside Classroom 110	yes	Riser	N/A	N/A	4/22/20	5/15/20		5/15/20	Included with wall 2	Included with wall 2	-	-	-		
	7300	1	1	S17	Stairs	Stairwell outside Classroom 110	yes	Stringer	N/A	N/A	4/22/20	5/15/20		5/15/20	Included with wall 2	Included with wall 2	-	-	-		
	7300	1	1	S17	Stairs	Stairwell outside Classroom 110	yes	Newel Post	N/A	N/A	4/22/20	5/15/20		5/15/20	Included with wall 2	Included with wall 2	-	-	-		
	7300	1	2	213	Teacher Lounge/Dining	Teacher's Lounge	yes	W1	3/30/20	3/30/20	4/1/20	4/15/20		4/18/20	576	15	2	Yes	<10 ug/ft2		
	7300	1	2	213	Teacher Lounge/Dining	Teacher's Lounge	yes	W2	3/30/20	3/30/20	4/1/20	4/15/20		4/18/20	Included with wall 1	Included with wall 1	-	-	-		
	7300	1	2	213	Teacher Lounge/Dining	Teacher's Lounge	yes	W3	3/30/20	3/30/20	4/1/20	4/15/20		4/18/20	Included with wall 1	Included with wall 1	-	-	-		
	7300	1	2	213	Teacher Lounge/Dining	Teacher's Lounge	yes	window sill	3/30/20	3/30/20	4/1/20	4/15/20		4/18/20	Included with wall 1	Included with wall 1	-	-	-		
	7300	1	2	214A	Restrooms, Staff - Female	Women's Restroom adjacent to Teacher's Lounge	yes	pipe	N/A	N/A	4/1/20	4/15/20		4/18/20	80	2	1	Yes	<10 ug/ft2		
	7300	1	2	214A	Restrooms, Staff - Female	Women's Restroom adjacent to Teacher's Lounge	yes	Stall Doors	N/A	N/A	4/1/20	4/15/20		4/18/20	Included with pipe	Included with pipe	-	-	-		
	7300	1	2	214	Administrative Office	Counselor's Office 214	yes	W1	3/30/20	3/30/20	4/1/20	4/15/20		4/18/20	196	5	1	Yes	<10 ug/ft2		
	7300	1	2	214	Administrative Office	Counselor's Office 214	yes	door	3/30/20	3/30/20	4/1/20	4/15/20		4/18/20	Included with wall 1	Included with wall 1	-	-	-		
	7300	1	2	214	Administrative Office	Counselor's Office 214	yes	door frame	3/30/20	3/30/20	4/1/20	4/15/20		4/18/20	Included with wall 1	Included with wall 1	-	-	-		
	7300	1	2	214	Administrative Office	Counselor's Office 214	yes	W2	3/30/20	3/30/20	4/1/20	4/15/20		4/18/20	Included with wall 1	Included with wall 1	-	-	-		
	7300	1	2	214	Administrative Office	Counselor's Office 214	yes	hutch	3/30/20	3/30/20	4/1/20	4/15/20		4/18/20	Included with wall 1	Included with wall 1	-	-	-		
	7300	1	2	214	Administrative Office	Counselor's Office 214	yes	W3	3/30/20	3/30/20	4/1/20	4/15/20		4/18/20	Included with wall 1	Included with wall 1	-	-	-		
	7300	1	2	200	Health Service Room	Nurse's Office	yes	W1	3/30/20	3/30/20	4/1/20	5/5/20		5/7/20	264	7	1	Yes	<10 ug/ft2		
	7300	1	2	200	Health Service Room	Nurse's Office	yes	door	3/30/20	3/30/20	4/1/20	5/5/20		5/7/20	Included with wall 1	Included with wall 1	-	-	-		
	7300	1	2	200	Health Service Room	Nurse's Office	yes	door frame	3/30/20	3/30/20	4/1/20	5/5/20		5/7/20	Included with wall 1	Included with wall 1	-	-	-		
	7300	1	2	200	Health Service Room	Nurse's Office	yes	W2	3/30/20	3/30/20	4/1/20	5/5/20		5/7/20	Included with wall 1	Included with wall 1	-	-	-		
	7300	1	2	200	Health Service Room	Nurse's Office	yes	door	3/30/20	3/30/20	4/1/20	5/5/20		5/7/20	Included with wall 1	Included with wall 1	-	-	-		
	7300	1	2	200	Health Service Room	Nurse's Office	yes	door frame	3/30/20	3/30/20	4/1/20	5/5/20		5/7/20	Included with wall 1	Included with wall 1	-	-	-		
	7300	1	2	200	Health Service Room	Nurse's Office	yes	Hutch	3/30/20	3/30/20	4/1/20	5/5/20		5/7/20	Included with wall 1	Included with wall 1	-	-	-		
	7300	1	2	200	Health Service Room	Nurse's Office	yes	W3	3/30/20	3/30/20	4/1/20	5/5/20		5/7/20	Included with wall 1	Included with wall 1	-	-	-		
	7300	1	2	200	Health Service Room	Nurse's Office	yes	W4	3/30/20	3/30/20	4/1/20	5/5/20		5/7/20	Included with wall 1	Included with wall 1	-	-	-		

Hopkinson

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Student/Teacher Occupied	Primary Component	Pre-Cleaning Completed (date)	Contents Moved (date)	Work Area Prepped (date)	Surfaces Stabilized (date)	Contents Back in Place (date)	Final Inspection Approval and Photos (date)	Square Footage of Work Area	Number of Required RRP Wipes	Number of Colorimetric Wipes Used to Pass	Final Colorimetric Wipe Submitted for AAS Analysis (yes/no)	AAS Analysis Results	Comments from Assessment	Comments from Oversight
	7300	1	2	200A	Student Restrooms - Male/Female (Classroom)	Nurse's Restroom	yes	W2	N/A	N/A	4/1/20	5/5/20		5/7/20	Included with ceiling	Included with ceiling	-	-	-		
	7300	1	2	200A	Student Restrooms - Male/Female (Classroom)	Nurse's Restroom	yes	W3	N/A	N/A	4/1/20	5/5/20		5/7/20	Included with ceiling	Included with ceiling	-	-	-		
	7300	1	2	200A	Student Restrooms - Male/Female (Classroom)	Nurse's Restroom	yes	Ceiling	N/A	N/A	4/1/20	5/5/20		5/7/20	12	1	1	Yes	10 ug/ft2		
	7300	1	2	201	Primary	Classroom 201	yes	W1	3/30/20	3/30/20	4/1/20	4/15/20		4/18/20	928	24	3	Yes	<10 ug/ft2		
	7300	1	2	201	Primary	Classroom 201	yes	W2	3/30/20	3/30/20	4/1/20	4/15/20		4/18/20	Included with wall 1	Included with wall 1	-	-	-		
	7300	1	2	201	Primary	Classroom 201	yes	W3	3/30/20	3/30/20	4/1/20	4/15/20		4/18/20	Included with wall 1	Included with wall 1	-	-	-		
	7300	1	2	201	Primary	Classroom 201	yes	W4	3/30/20	3/30/20	4/1/20	4/15/20		4/18/20	Included with wall 1	Included with wall 1	-	-	-		
	7300	1	2	201A	Storage	Classroom 201 Coat Room	yes	W2	3/30/20	3/30/20	4/1/20	4/15/20		4/18/20	60	2	1	Yes	<10 ug/ft2		
	7300	1	2	201A	Storage	Classroom 201 Coat Room	yes	W3	3/30/20	3/30/20	4/1/20	4/15/20		4/18/20	Included with wall 2	Included with wall 2	-	-	-		
	7300	1	2	201A	Storage	Classroom 201 Coat Room	yes	W4	3/30/20	3/30/20	4/1/20	4/15/20		4/18/20	Included with wall 2	Included with wall 2	-	-	-		
	7300	1	2	202	Primary	Classroom 202	yes	W1	3/30/20	3/30/20	4/1/20	4/15/20		4/18/20	870	22	3	Yes	<10 ug/ft2		
	7300	1	2	202	Primary	Classroom 202	yes	W2	3/30/20	3/30/20	4/1/20	4/15/20		4/18/20	Included with wall 1	Included with wall 1	-	-	-		
	7300	1	2	202	Primary	Classroom 202	yes	W3	3/30/20	3/30/20	4/1/20	4/15/20		4/18/20	Included with wall 1	Included with wall 1	-	-	-	Behind radiator	
	7300	1	2	202A	Storage	Classroom 202 Coat Room	yes	W1	3/30/20	3/30/20	4/1/20	4/15/20		4/18/20	60	2	1	Yes	<10 ug/ft2		
	7300	1	2	202A	Storage	Classroom 202 Coat Room	yes	W2	3/30/20	3/30/20	4/1/20	4/15/20		4/18/20	Included with wall 1	Included with wall 1	-	-	-		
	7300	1	2	203	Primary	Classroom 203	yes	W1	3/30/20	3/30/20	4/1/20	4/13/20		4/14/20	928	24	3	Yes	10 ug/ft2		
	7300	1	2	203	Primary	Classroom 203	yes	W2	3/30/20	3/30/20	4/1/20	4/13/20		4/14/20	Included with wall 1	Included with wall 1	-	-	-		
	7300	1	2	203	Primary	Classroom 203	yes	W3	3/30/20	3/30/20	4/1/20	4/13/20		4/14/20	Included with wall 1	Included with wall 1	-	-	-	Flaking behind the radiator.	
	7300	1	2	203	Primary	Classroom 203	yes	W4	3/30/20	3/30/20	4/1/20	4/13/20		4/14/20	Included with wall 1	Included with wall 1	-	-	-		
	7300	1	2	203A	Storage	Classroom 203 Storage	yes	W2	3/30/20	3/30/20	4/1/20	4/13/20		4/14/20	60	4	2	Yes	(2) <10 ug/ft2		
	7300	1	2	203A	Storage	Classroom 203 Storage	yes	W4	3/30/20	3/30/20	4/1/20	4/13/20		4/14/20	Included with wall 2	Included with wall 2	-	-	-		
	7300	1	2	S22	Stairs	Stairwell next to Classroom 203	yes	W1	N/A	N/A	3/30/20	4/20/20	N/A	4/21/20	270	7	0	N/A	N/A		
	7300	1	2	S22	Stairs	Stairwell next to Classroom 203	yes	W2	N/A	N/A	3/30/20	4/20/20	N/A	4/21/20	Included with wall 1	Included with wall 1	-	-	-		
	7300	1	2	S22	Stairs	Stairwell next to Classroom 203	yes	Door	N/A	N/A	3/30/20	4/20/20	N/A	4/21/20	Included with wall 1	Included with wall 1	-	-	-		
	7300	1	2	S22	Stairs	Stairwell next to Classroom 203	yes	Door Frame	N/A	N/A	3/30/20	4/20/20	N/A	4/21/20	Included with wall 1	Included with wall 1	-	-	-		
	7300	1	2	S22	Stairs	Stairwell next to Classroom 203	yes	W4	N/A	N/A	3/30/20	4/20/20	N/A	4/21/20	Included with wall 1	Included with wall 1	-	-	-		
	7300	1	2	S22	Stairs	Stairwell next to Classroom 203	yes	Newel Posts	N/A	N/A	3/30/20	4/20/20	N/A	4/21/20	Included with wall 1	Included with wall 1	-	-	-		
	7300	1	2	H29	Circulation (Hallway)	Hallway from Classroom 201 to 203	yes	door	N/A	N/A	N/A	4/7/20	N/A	4/14/20	Included with wall 2	Included with wall 2	-	-	-		
	7300	1	2	H29	Circulation (Hallway)	Hallway from Classroom 201 to 203	yes	door frame	N/A	N/A	N/A	4/7/20	N/A	4/14/20	Included with wall 2	Included with wall 2	-	-	-		
	7300	1	2	H29	Circulation (Hallway)	Hallway from Classroom 201 to 203	yes	W2	N/A	N/A	N/A	4/7/20	N/A	4/14/20	175	5	0	N/A	N/A		
	7300	1	2	203B	Student Restrooms - Female (4-12)	Girl's Restroom	yes	Pipe	N/A	N/A	3/26/20	4/10/20	N/A	4/14/20	Included with ceiling	Included with ceiling	-	-	-		
	7300	1	2	203B	Student Restrooms - Female (4-12)	Girl's Restroom	yes	W3	N/A	N/A	3/26/20	4/10/20	N/A	4/14/20	Included with ceiling	Included with ceiling	-	-	-		
	7300	1	2	203B	Student Restrooms - Female (4-12)	Girl's Restroom	yes	Ceiling	N/A	N/A	3/26/20	4/10/20	N/A	4/14/20	186	10	2	Yes	25 ug/ft; <10 ug/ft2		
	7300	1	2	204	Primary	Classroom 204	yes	W1	3/30/20	3/30/20	4/2/20	4/10/20		4/14/20	870	22	3	Yes	<10 ug/ft2		
	7300	1	2	204	Primary	Classroom 204	yes	W3	3/30/20	3/30/20	4/2/20	4/10/20		4/14/20	Included with wall 1	Included with wall 1	-	-	-		
	7300	1	2	204	Primary	Classroom 204	yes	W4	3/30/20	3/30/20	4/2/20	4/10/20		4/14/20	Included with wall 1	Included with wall 1	-	-	-		
	7300	1	2	204A	Storage	Classroom 204 Coat Room	yes	W1	3/30/20	3/30/20	4/2/20	4/10/20		4/14/20	60	2	1	Yes	<10 ug/ft2		

Hopkinson

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Student/Teacher Occupied	Primary Component	Pre-Cleaning Completed (date)	Contents Moved (date)	Work Area Prepped (date)	Surfaces Stabilized (date)	Contents Back in Place (date)	Final Inspection Approval and Photos (date)	Square Footage of Work Area	Number of Required RRP Wipes	Number of Colorimetric Wipes Used to Pass	Final Colorimetric Wipe Submitted for AAS Analysis (yes/no)	AAS Analysis Results	Comments from Assessment	Comments from Oversight
	7300	1	2	204A	Storage	Classroom 204 Coat Room	yes	W3	3/30/20	3/30/20	4/2/20	4/10/20		4/14/20	Included with wall 1	Included with wall 1	-	-	-	damage behind red poster on wall adjacent to wall #2; according to teacher	
	7300	1	2	204A	Storage	Classroom 204 Coat Room	yes	W4	3/30/20	3/30/20	4/2/20	4/10/20		4/14/20	Included with wall 1	Included with wall 1	-	-	-		
	7300	1	2	205	Primary	Classroom 205	yes	W1	3/30/20	3/30/20	4/1/20	4/10/20		4/14/20	192	5	0	N/A	N/A		
	7300	1	2	205	Primary	Classroom 205	yes	W3	3/30/20	3/30/20	4/1/20	4/10/20		4/14/20	192	10	2	Yes	17 ug/ft2; <10 ug/ft2		
	7300	1	2	205A	Storage	Classroom 205 Coat Room	yes	W1	3/30/20	3/30/20	4/1/20	4/10/20		4/14/20	60	2	0	N/A	N/A		
	7300	1	2	205A	Storage	Classroom 205 Coat Room	yes	W4	3/30/20	3/30/20	4/1/20	4/10/20		4/14/20	Included with wall 1	Included with wall 1	-	-	-		
	7300	1	2	206	Primary	Classroom 206	yes	W1	3/30/20	3/30/20	4/1/20	4/10/20		4/14/20	192	10	2	Yes	(2) <10 ug/ft2	flaking behind radiator	
	7300	1	2	206	Primary	Classroom 206	yes	W3	3/30/20	3/30/20	4/1/20	4/10/20		4/14/20	192	5	0	N/A	N/A		
	7300	1	2	206A	Storage	Classroom 206 Coat Room	yes	W1	3/30/20	3/30/20	4/1/20	4/10/20		4/14/20	Included with ceiling	Included with ceiling	-	-	-		
	7300	1	2	206A	Storage	Classroom 206 Coat Room	yes	W3	3/30/20	3/30/20	4/1/20	4/10/20		4/14/20	Included with ceiling	Included with ceiling	-	-	-		
	7300	1	2	206A	Storage	Classroom 206 Coat Room	yes	Ceiling	3/30/20	3/30/20	4/1/20	4/10/20		4/14/20	60	2	1	Yes	<10 ug/ft2		
	7300	1	2	207	Primary	Classroom 207	yes	W1	3/30/20	3/30/20	4/1/20	4/10/20		4/14/20	192	5	1	Yes	<10 ug/ft2		
	7300	1	2	207	Primary	Classroom 207	yes	W2	3/30/20	3/30/20	4/1/20	4/10/20		4/14/20	180	5	0	N/A	N/A	flaking behind radiator	
	7300	1	2	207	Primary	Classroom 207	yes	W3	3/30/20	3/30/20	4/1/20	4/10/20		4/14/20	192	5	0	N/A	N/A		
	7300	1	2	207A	Storage	Classroom 207 Coat Room	yes	W1	3/30/20	3/30/20	4/1/20	4/10/20		4/14/20	60	4	2	Yes	13 ug/ft2; <10 ug/ft2		
	7300	1	2	207A	Storage	Classroom 207 Coat Room	yes	W3	3/30/20	3/30/20	4/1/20	4/10/20		4/14/20	Included with wall 1	Included with wall 1	-	-	-		
	7300	1	2	207A	Storage	Classroom 207 Coat Room	yes	W4	3/30/20	3/30/20	4/1/20	4/10/20		4/14/20	Included with wall 1	Included with wall 1	-	-	-		
	7300	1	2	S24	Stairs	Fire Tower across from Classroom 207	yes	Door	N/A	N/A	4/30/20	5/6/20	N/A	5/8/20	Included with ceiling	Included with wall 1	-	-	-		
	7300	1	2	S24	Stairs	Fire Tower across from Classroom 207	yes	W2	N/A	N/A	4/30/20	5/6/20	N/A	5/8/20	Included with ceiling	Included with wall 1	-	-	-	ceiling... efflorescence 100	
	7300	1	2	S24	Stairs	Fire Tower across from Classroom 207	yes	W4	N/A	N/A	4/30/20	5/6/20	N/A	5/8/20	Included with ceiling	Included with wall 1	-	-	-		
	7300	1	2	S24	Stairs	Fire Tower across from Classroom 207	yes	Window Safety Bars	N/A	N/A	4/30/20	5/6/20	N/A	5/8/20	Included with ceiling	Included with wall 1	-	-	-		
	7300	1	2	S24	Stairs	Fire Tower across from Classroom 207	yes	Ceiling	N/A	N/A	4/30/20	5/6/20	N/A	5/8/20	231	6	0	N/A	N/A		
	7300	1	2	207B	Student Restrooms - Male (4-12)	Boy's Restroom	yes	W2	N/A	N/A	3/26/20	4/10/20	N/A	4/14/20	125	8	2	Yes	61 ug/ft2; <10 ug/ft2		
	7300	1	2	H28	Circulation (Hallway)	Hallway from Classrooms 204 to 207	yes	W1	N/A	N/A	3/31/20	4/11/20	N/A	4/14/20	900	23	0	N/A	N/A		
	7300	1	2	H28	Circulation (Hallway)	Hallway from Classrooms 204 to 207	yes	W3	N/A	N/A	3/31/20	4/11/20	N/A	4/14/20	Included with wall 1	Included with wall 1	-	-	-		
	7300	1	2	H28	Circulation (Hallway)	Hallway from Classrooms 204 to 207	yes	Pipe	N/A	N/A	3/31/20	4/11/20	N/A	4/14/20	Included with wall 1	Included with wall 1	-	-	-		
	7300	1	2	S21	Stairs	Stairwell outside Classroom 208	yes	W1	N/A	N/A	3/27/20	4/9/20	N/A	4/9/20	297	8	0	N/A	N/A		
	7300	1	2	S21	Stairs	Stairwell outside Classroom 208	yes	Door	N/A	N/A	3/27/20	4/9/20	N/A	4/9/20	Included with wall 1	Included with wall 1	-	-	-		
	7300	1	2	S21	Stairs	Stairwell outside Classroom 208	yes	Door Frame	N/A	N/A	3/27/20	4/9/20	N/A	4/9/20	Included with wall 1	Included with wall 1	-	-	-		
	7300	1	2	S21	Stairs	Stairwell outside Classroom 208	yes	W4	N/A	N/A	3/27/20	4/9/20	N/A	4/9/20	Included with wall 1	Included with wall 1	-	-	-		
	7300	1	2	S21	Stairs	Stairwell outside Classroom 208	yes	Newel Posts	N/A	N/A	3/27/20	4/9/20	N/A	4/9/20	Included with wall 1	Included with wall 1	-	-	-		
	7300	1	2	S21	Stairs	Stairwell outside Classroom 208	yes	Handrail	N/A	N/A	3/27/20	4/9/20	N/A	4/9/20	Included with wall 1	Included with wall 1	-	-	-		
	7300	1	2	S21	Stairs	Stairwell outside Classroom 208	yes	Stringer	N/A	N/A	3/27/20	4/9/20	N/A	4/9/20	Included with wall 1	Included with wall 1	-	-	-		
	7300	1	2	208	Primary	Classroom 208	yes	W1	3/30/20	3/30/20	3/31/20	4/9/20		4/14/20	928	24	3	Yes	<10 ug/ft2	damage behind radiatore	
	7300	1	2	208	Primary	Classroom 208	yes	W2	3/30/20	3/30/20	3/31/20	4/9/20		4/14/20	Included with wall 1	Included with wall 1	-	-	-		
	7300	1	2	208	Primary	Classroom 208	yes	W3	3/30/20	3/30/20	3/31/20	4/9/20		4/14/20	Included with wall 1	Included with wall 1	-	-	-		
	7300	1	2	208	Primary	Classroom 208	yes	W4	3/30/20	3/30/20	3/31/20	4/9/20		4/14/20	Included with wall 1	Included with wall 1	-	-	-		
	7300	1	2	208A	Storage	Classroom 208 Coat Room	yes	W1	3/30/20	3/30/20	3/31/20	4/9/20		4/14/20	60	4	2	Yes	15 ug/ft2; <10 ug/ft2		
	7300	1	2	208A	Storage	Classroom 208 Coat Room	yes	W2	3/30/20	3/30/20	3/31/20	4/9/20		4/14/20	Included with wall 1	Included with wall 1	-	-	-		
	7300	1	2	208A	Storage	Classroom 208 Coat Room	yes	W4	3/30/20	3/30/20	3/31/20	4/9/20		4/14/20	Included with wall 1	Included with wall 1	-	-	-		

Hopkinson

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Student/Teacher Occupied	Primary Component	Pre-Cleaning Completed (date)	Contents Moved (date)	Work Area Prepped (date)	Surfaces Stabilized (date)	Contents Back in Place (date)	Final Inspection Approval and Photos (date)	Square Footage of Work Area	Number of Required RRP Wipes	Number of Colorimetric Wipes Used to Pass	Final Colorimetric Wipe Submitted for AAS Analysis (yes/no)	AAS Analysis Results	Comments from Assessment	Comments from Oversight
	7300	1	2	209	Primary	Classroom 209	yes	W1	3/30/20	3/30/20	3/31/20	4/9/20		4/14/20	870	22	3	Yes	<10 ug/ft2	flaking behind radiator	
	7300	1	2	209	Primary	Classroom 209	yes	W3	3/30/20	3/30/20	3/31/20	4/9/20		4/14/20	Included with wall 1	Included with wall 1	-	-	-		
	7300	1	2	209	Primary	Classroom 209	yes	W4	3/30/20	3/30/20	3/31/20	4/9/20		4/14/20	Included with wall 1	Included with wall 1	-	-	-		
	7300	1	2	209A	Storage	Classroom 209 Coat Room	yes	W2	3/30/20	3/30/20	3/31/20	4/9/20		4/14/20	78	6	3	Yes	18 ug/ft2; (2) <10 ug/ft2		
	7300	1	2	209A	Storage	Classroom 209 Coat Room	yes	W3	3/30/20	3/30/20	3/31/20	4/9/20		4/14/20	Included with wall 2	Included with wall 2	-	-	-	damage behind radiator	
	7300	1	2	209A	Storage	Classroom 209 Coat Room	yes	W4	3/30/20	3/30/20	3/31/20	4/9/20		4/14/20	Included with wall 2	Included with wall 2	-	-	-		
	7300	1	2	210	Primary	Classroom 210	yes	W1	3/30/20	3/30/20	3/31/20	4/9/20		4/14/20	928	24	3	Yes	(2) <10 ug/ft2		
	7300	1	2	210	Primary	Classroom 210	yes	W2	3/30/20	3/30/20	3/31/20	4/9/20		4/14/20	Included with wall 1	Included with wall 1	-	-	-		
	7300	1	2	210	Primary	Classroom 210	yes	Pipe	3/30/20	3/30/20	3/31/20	4/9/20		4/14/20	Included with wall 1	Included with wall 1	-	-	-	wall covered with boxes and metal cabinet	
	7300	1	2	210	Primary	Classroom 210	yes	W3	3/30/20	3/30/20	3/31/20	4/9/20		4/14/20	Included with wall 1	Included with wall 1	-	-	-		
	7300	1	2	210	Primary	Classroom 210	yes	W4	3/30/20	3/30/20	3/31/20	4/9/20		4/14/20	Included with wall 1	Included with wall 1	-	-	-		
	7300	1	2	210B	Storage	Classroom 210 Coat Room	yes	W2	3/30/20	3/30/20	3/31/20	4/9/20		4/14/20	60	4	2	Yes	18 ug/ft2; <10 ug/ft2		
	7300	1	2	210B	Storage	Classroom 210 Coat Room	yes	W3	3/30/20	3/30/20	3/31/20	4/9/20		4/14/20	Included with wall 2	Included with wall 2	-	-	-	part of wall covered by bookshelves	
	7300	1	2	210B	Storage	Classroom 210 Coat Room	yes	W4	3/30/20	3/30/20	3/31/20	4/9/20		4/14/20	Included with wall 2	Included with wall 2	-	-	-		
	7300	1	2	210A	Administrative Office	Office adjacent to Classroom 210	yes	W2	5/4/20	5/4/20	5/5/20	5/8/20		5/11/20	Included with ceiling	Included with ceiling	-	-	-		
	7300	1	2	210A	Administrative Office	Office adjacent to Classroom 210	yes	W3	5/4/20	5/4/20	5/5/20	5/8/20		5/11/20	Included with ceiling	Included with ceiling	-	-	-		
	7300	1	2	210A	Administrative Office	Office adjacent to Classroom 210	yes	W4	5/4/20	5/4/20	5/5/20	5/8/20		5/11/20	Included with ceiling	Included with ceiling	-	-	-		
	7300	1	2	210A	Administrative Office	Office adjacent to Classroom 210	yes	Ceiling	5/4/20	5/4/20	5/5/20	5/8/20		5/11/20	264	7	0	N/A	N/A		
	7300	1	2	H27	Circulation (Hallway)	Hallway from Classrooms 208 to 210	yes	Door	N/A	N/A	3/31/20	4/11/20	N/A	4/14/20	Included with wall 4	Included with wall 4	-	-	-		
	7300	1	2	H27	Circulation (Hallway)	Hallway from Classrooms 208 to 210	yes	Door Frame	N/A	N/A	3/31/20	4/11/20	N/A	4/14/20	Included with wall 4	Included with wall 4	-	-	-		
	7300	1	2	H27	Circulation (Hallway)	Hallway from Classrooms 208 to 210	yes	Pipe	N/A	N/A	3/31/20	4/11/20	N/A	4/14/20	Included with wall 4	Included with wall 4	-	-	-		
	7300	1	2	H27	Circulation (Hallway)	Hallway from Classrooms 208 to 210	yes	W4	N/A	N/A	3/31/20	4/11/20	N/A	4/14/20	224	6	0	N/A	N/A		
	7300	1	3	300	Administrative Office	Counselor's Office 300	yes	W2	3/5/20	3/5/20	3/5/20	3/10/20	3/16/20	3/11/20	176	10	2	Yes	24 ug/ft2; <10 ug/ft2		
	7300	1	3	300	Administrative Office	Counselor's Office 300	yes	W3	3/5/20	3/5/20	3/5/20	3/10/20	3/16/20	3/11/20	Included with wall 2	Included with wall 2	-	-	-		
	7300	1	3	300	Administrative Office	Counselor's Office 300	yes	W4	3/5/20	3/5/20	3/5/20	3/10/20	3/16/20	3/11/20	Included with wall 2	Included with wall 2	-	-	-		
	7300	1	3	300A	Restrooms, Staff - Male/Female	Staff Restroom at Counselor's Office	yes	W1	3/5/20	3/5/20	3/5/20	3/10/20	3/16/20	3/11/20	99	3	0	N/A	N/A		
	7300	1	3	300A	Restrooms, Staff - Male/Female	Staff Restroom at Counselor's Office	yes	W2	3/5/20	3/5/20	3/5/20	3/10/20	3/16/20	3/11/20	Included with wall 1	Included with wall 1	-	-	-		
	7300	1	3	300A	Restrooms, Staff - Male/Female	Staff Restroom at Counselor's Office	yes	Pipe	3/5/20	3/5/20	3/5/20	3/10/20	3/16/20	3/11/20	Included with wall 1	Included with wall 1	-	-	-		
	7300	1	3	300A	Restrooms, Staff - Male/Female	Staff Restroom at Counselor's Office	yes	W3	3/5/20	3/5/20	3/5/20	3/10/20	3/16/20	3/11/20	Included with wall 1	Included with wall 1	-	-	-		
	7300	1	3	300A	Restrooms, Staff - Male/Female	Staff Restroom at Counselor's Office	yes	Pipe	3/5/20	3/5/20	3/5/20	3/10/20	3/16/20	3/11/20	Included with wall 1	Included with wall 1	-	-	-		
	7300	1	3	300A	Restrooms, Staff - Male/Female	Staff Restroom at Counselor's Office	yes	W4	3/5/20	3/5/20	3/5/20	3/10/20	3/16/20	3/11/20	Included with wall 1	Included with wall 1	-	-	-		
	7300	1	3	301	Primary	Classroom 301	yes	W1	3/5/20	3/5/20	3/5/20	3/10/20	3/16/20	3/12/20	928	24	3	Yes	<10 ug/ft2		
	7300	1	3	301	Primary	Classroom 301	yes	W2	3/5/20	3/5/20	3/5/20	3/10/20	3/16/20	3/12/20	Included with wall 1	Included with wall 1	-	-	-		
	7300	1	3	301	Primary	Classroom 301	yes	W3	3/5/20	3/5/20	3/5/20	3/10/20	3/16/20	3/12/20	Included with wall 1	Included with wall 1	-	-	-		
	7300	1	3	301	Primary	Classroom 301	yes	W4	3/5/20	3/5/20	3/5/20	3/10/20	3/16/20	3/12/20	Included with wall 1	Included with wall 1	-	-	-		
	7300	1	3	301A	Storage	Classroom 301 Coat Room	yes	W1	3/5/20	3/5/20	3/5/20	3/10/20	3/16/20	3/12/20	60	4	2	Yes	16 ug/ft2; <10 ug/ft2		
	7300	1	3	301A	Storage	Classroom 301 Coat Room	yes	W2	3/5/20	3/5/20	3/5/20	3/10/20	3/16/20	3/12/20	Included with wall 1	Included with wall 1	-	-	-		
	7300	1	3	302	Primary	Classroom 302	yes	W1	3/4/20	3/4/20	3/4/20	3/10/20	3/16/20	3/12/20	870	22	3	Yes	<10 ug/ft2		
	7300	1	3	302	Primary	Classroom 302	yes	W2	3/4/20	3/4/20	3/4/20	3/10/20	3/16/20	3/12/20	Included with wall 1	Included with wall 1	-	-	-		
	7300	1	3	302	Primary	Classroom 302	yes	W3	3/4/20	3/4/20	3/4/20	3/10/20	3/16/20	3/12/20	Included with wall 1	Included with wall 1	-	-	-		

Hopkinson																				Comments from Assessment	Comments from Oversight
Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Student/Teacher Occupied	Primary Component	Pre-Cleaning Completed (date)	Contents Moved (date)	Work Area Prepped (date)	Surfaces Stabilized (date)	Contents Back in Place (date)	Final Inspection Approval and Photos (date)	Square Footage of Work Area	Number of Required RRP Wipes	Number of Colorimetric Wipes Used to Pass	Final Colorimetric Wipe Submitted for AAS Analysis (yes/no)	AAS Analysis Results		
	7300	1	3	302	Primary	Classroom 302	yes	W4	3/4/20	3/4/20	3/4/20	3/10/20	3/16/20	3/12/20	Included with wall 1	Included with wall 1	-	-	-		
	7300	1	3	302A	Storage	Classroom 302 Coat Room	yes	W1	3/4/20	3/4/20	3/4/20	3/10/20	3/16/20	3/12/20	60	4	2	Yes	12 ug/ft2; <10 ug/ft2		
	7300	1	3	303	Primary	Classroom 311	yes	W1	3/4/20	3/4/20	3/4/20	3/10/20	3/16/20	3/12/20	432	11	2	Yes	<10 ug/ft2		
	7300	1	3	303	Primary	Classroom 311	yes	W2	3/4/20	3/4/20	3/4/20	3/10/20	3/16/20	3/12/20	Included with wall 1	Included with wall 1	-	-	-		
	7300	1	3	303	Primary	Classroom 311	yes	W3	3/4/20	3/4/20	3/4/20	3/10/20	3/16/20	3/12/20	Included with wall 1	Included with wall 1	-	-	-		
	7300	1	3	303A	Storage	Classroom 311 Closet	yes	W1	3/4/20	3/4/20	3/4/20	3/10/20	3/16/20	3/12/20	Included with ceiling	Included with ceiling	-	-	-		
	7300	1	3	303A	Storage	Classroom 311 Closet	yes	pipe	3/4/20	3/4/20	3/4/20	3/10/20	3/16/20	3/12/20	Included with ceiling	Included with ceiling	-	-	-		
	7300	1	3	303A	Storage	Classroom 311 Closet	yes	W2	3/4/20	3/4/20	3/4/20	3/10/20	3/16/20	3/12/20	Included with ceiling	Included with ceiling	-	-	-		
	7300	1	3	303A	Storage	Classroom 311 Closet	yes	W3	3/4/20	3/4/20	3/4/20	3/10/20	3/16/20	3/12/20	Included with ceiling	Included with ceiling	-	-	-		
	7300	1	3	303A	Storage	Classroom 311 Closet	yes	W4	3/4/20	3/4/20	3/4/20	3/10/20	3/16/20	3/12/20	Included with ceiling	Included with ceiling	-	-	-		
	7300	1	3	303A	Storage	Classroom 311 Closet	yes	pipe	3/4/20	3/4/20	3/4/20	3/10/20	3/16/20	3/12/20	Included with ceiling	Included with ceiling	-	-	-		
	7300	1	3	303A	Storage	Classroom 311 Closet	yes	Ceiling	3/4/20	3/4/20	3/4/20	3/10/20	3/16/20	3/12/20	60	2	1	Yes	<10 ug/ft2		
	7300	1	3	311	Primary	Classroom 303	yes	W1	3/4/20	3/4/20	3/4/20	3/10/20	3/16/20	3/12/20	470	12	2	Yes	<10 ug/ft2		
	7300	1	3	311	Primary	Classroom 303	yes	W2	3/4/20	3/4/20	3/4/20	3/10/20	3/16/20	3/12/20	Included with wall 1	Included with wall 1	-	-	-		
	7300	1	3	311	Primary	Classroom 303	yes	W3	3/4/20	3/4/20	3/4/20	3/10/20	3/16/20	3/12/20	Included with wall 1	Included with wall 1	-	-	-		
	7300	1	3	311	Primary	Classroom 303	yes	W4	3/4/20	3/4/20	3/4/20	3/10/20	3/16/20	3/12/20	Included with wall 1	Included with wall 1	-	-	-		
	7300	1	3	311A	Storage	Classroom 303 Closet	yes	W1	3/4/20	3/4/20	3/4/20	3/10/20	3/16/20	3/12/20	60	4	2	Yes	59 ug/ft2; <10 ug/ft2		
	7300	1	3	311A	Storage	Classroom 303 Closet	yes	W2	3/4/20	3/4/20	3/4/20	3/10/20	3/16/20	3/12/20	Included with wall 1	Included with wall 1	-	-	-		
	7300	1	3	311A	Storage	Classroom 303 Closet	yes	W4	3/4/20	3/4/20	3/4/20	3/10/20	3/16/20	3/12/20	Included with wall 1	Included with wall 1	-	-	-		
	7300	1	3	S32	Stairs	Stairwell outside Classroom 303	yes	W1	N/A	N/A	3/30/20	5/1/20	N/A	5/4/20	270	7	0	N/A	N/A		
	7300	1	3	S32	Stairs	Stairwell outside Classroom 303	yes	Radiator	N/A	N/A	3/30/20	5/1/20	N/A	5/4/20	Included with wall 1	Included with wall 1	-	-	-		
	7300	1	3	S32	Stairs	Stairwell outside Classroom 303	yes	W2	N/A	N/A	3/30/20	5/1/20	N/A	5/4/20	Included with wall 1	Included with wall 1	-	-	-		
	7300	1	3	S32	Stairs	Stairwell outside Classroom 303	yes	Door	N/A	N/A	3/30/20	5/1/20	N/A	5/4/20	Included with wall 1	Included with wall 1	-	-	-		
	7300	1	3	S32	Stairs	Stairwell outside Classroom 303	yes	Door Frame	N/A	N/A	3/30/20	5/1/20	N/A	5/4/20	Included with wall 1	Included with wall 1	-	-	-		
	7300	1	3	S32	Stairs	Stairwell outside Classroom 303	yes	W4	N/A	N/A	3/30/20	5/1/20	N/A	5/4/20	Included with wall 1	Included with wall 1	-	-	-		
	7300	1	3	S32	Stairs	Stairwell outside Classroom 303	yes	Newel Post	N/A	N/A	3/30/20	5/1/20	N/A	5/4/20	Included with wall 1	Included with wall 1	-	-	-		
	7300	1	3	H310	Circulation (Hallway)	Hallway from Classrooms 301 to 303	yes	Door	N/A	N/A	3/26/20	4/1/20	N/A	3/12/20	Included with wall 2	Included with wall 2	-	-	-		
	7300	1	3	H310	Circulation (Hallway)	Hallway from Classrooms 301 to 303	yes	Door Frame	N/A	N/A	3/26/20	4/1/20	N/A	3/12/20	Included with wall 2	Included with wall 2	-	-	-		
	7300	1	3	H310	Circulation (Hallway)	Hallway from Classrooms 301 to 303	yes	W2	N/A	N/A	3/26/20	4/1/20	N/A	3/12/20	360	9	0	N/A	N/A		
	7300	1	3	H310	Circulation (Hallway)	Hallway from Classrooms 301 to 303	yes	W4	N/A	N/A	3/26/20	4/1/20	N/A	3/12/20	Included with wall 2	Included with wall 2	-	-	-		
	7300	1	3	303B	Student Restrooms - Female (4-12)	Girl's Restroom	yes	W1	N/A	N/A	3/11/20	3/13/20	N/A	3/12/20	Included with ceiling	Included with ceiling	-	-	-		
	7300	1	3	303B	Student Restrooms - Female (4-12)	Girl's Restroom	yes	W2	N/A	N/A	3/11/20	3/13/20	N/A	3/12/20	Included with ceiling	Included with ceiling	-	-	-		
	7300	1	3	303B	Student Restrooms - Female (4-12)	Girl's Restroom	yes	W3	N/A	N/A	3/11/20	3/13/20	N/A	3/12/20	Included with ceiling	Included with ceiling	-	-	-		
	7300	1	3	303B	Student Restrooms - Female (4-12)	Girl's Restroom	yes	W4	N/A	N/A	3/11/20	3/13/20	N/A	3/12/20	Included with ceiling	Included with ceiling	-	-	-		
	7300	1	3	303B	Student Restrooms - Female (4-12)	Girl's Restroom	yes	pipe	N/A	N/A	3/11/20	3/13/20	N/A	3/12/20	Included with ceiling	Included with ceiling	-	-	-		
	7300	1	3	303B	Student Restrooms - Female (4-12)	Girl's Restroom	yes	Ceiling	N/A	N/A	3/11/20	3/13/20	N/A	3/12/20	186	10	2	Yes	33 ug/ft2; <10 ug/ft2		
	7300	1	3	304	Primary	Classroom 304	yes	W1	3/6/20	3/6/20	3/6/20	3/10/20	3/16/20	3/12/20	870	22	3	Yes	<10 ug/ft2		
	7300	1	3	304	Primary	Classroom 304	yes	W2	3/6/20	3/6/20	3/6/20	3/10/20	3/16/20	3/12/20	Included with wall 1	Included with wall 1	-	-	-		

Hopkinson

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Student/Teacher Occupied	Primary Component	Pre-Cleaning Completed (date)	Contents Moved (date)	Work Area Prepped (date)	Surfaces Stabilized (date)	Contents Back in Place (date)	Final Inspection Approval and Photos (date)	Square Footage of Work Area	Number of Required RRP Wipes	Number of Colorimetric Wipes Used to Pass	Final Colorimetric Wipe Submitted for AAS Analysis (yes/no)	AAS Analysis Results	Comments from Assessment	Comments from Oversight
	7300	1	3	304	Primary	Classroom 304	yes	W3	3/6/20	3/6/20	3/6/20	3/10/20	3/16/20	3/12/20	Included with wall 1	Included with wall 1	-	-	-	flakikng behind radiator	
	7300	1	3	304	Primary	Classroom 304	yes	W4	3/6/20	3/6/20	3/6/20	3/10/20	3/16/20	3/12/20	Included with wall 1	Included with wall 1	-	-	-		
	7300	1	3	304A	Storage	Classroom 304 Coat Room	yes	W1	3/6/20	3/6/20	3/6/20	3/10/20	3/16/20	3/12/20	60	6	3	Yes	25 ug/ft2; 22 ug/ft2; <10 ug/ft2		
	7300	1	3	304A	Storage	Classroom 304 Coat Room	yes	W3	3/6/20	3/6/20	3/6/20	3/10/20	3/16/20	3/12/20	Included with wall 1	Included with wall 1	-	-	-		
	7300	1	3	304A	Storage	Classroom 304 Coat Room	yes	W4	3/6/20	3/6/20	3/6/20	3/10/20	3/16/20	3/12/20	Included with wall 1	Included with wall 1	-	-	-		
	7300	1	3	305	Primary	Classroom 305	yes	W1	3/6/20	3/6/20	3/6/20	3/10/20	3/16/20	3/12/20	192	5	1	Yes	<10 ug/ft2	radiator is covered, possible damage behind. Shelving units are screwed to the wall.	
	7300	1	3	305	Primary	Classroom 305	yes	W3	3/6/20	3/6/20	3/6/20	3/10/20	3/16/20	3/12/20	192	5	0	N/A	N/A		
	7300	1	3	305A	Storage	Classroom 305 Coat Room	yes	W1	3/6/20	3/6/20	3/6/20	3/10/20	3/16/20	3/12/20	60	2	1	Yes	<10 ug/ft2		
	7300	1	3	305A	Storage	Classroom 305 Coat Room	yes	W3	3/6/20	3/6/20	3/6/20	3/10/20	3/16/20	3/12/20	Included with wall 1	Included with wall 1	-	-	-		
	7300	1	3	305A	Storage	Classroom 305 Coat Room	yes	W4	3/6/20	3/6/20	3/6/20	3/10/20	3/16/20	3/12/20	Included with wall 1	Included with wall 1	-	-	-		
	7300	1	3	306	Primary	Classroom 306	yes	W1	3/6/20	3/6/20	3/6/20	3/10/20	3/16/20	3/12/20	192	5	1	Yes	<10 ug/ft2		
	7300	1	3	306	Primary	Classroom 306	yes	W3	3/6/20	3/6/20	3/6/20	3/10/20	3/16/20	3/12/20	192	5	0	N/A	N/A		
	7300	1	3	306A	Storage	Classroom 306 Coat Room	yes	W1	3/6/20	3/6/20	3/6/20	3/10/20	3/16/20	3/12/20	60	4	2	Yes	52 ug/ft2; <10 ug/ft2		
	7300	1	3	306B	Storage	Classroom 306 Closet	yes	W4	3/6/20	3/6/20	3/6/20	3/10/20	3/16/20	3/12/20	Included with wall 1	Included with wall 1	-	-	-		
	7300	1	3	307	Primary	Classroom 307	yes	W1	3/6/20	3/6/20	3/7/20	3/11/20	3/16/20	3/12/20	870	44	6	Yes	26 ug/ft2; <10 ug/ft2		
	7300	1	3	307	Primary	Classroom 307	yes	W2	3/6/20	3/6/20	3/7/20	3/11/20	3/16/20	3/12/20	Included with wall 1	Included with wall 1	0	N/A	N/A		
	7300	1	3	307	Primary	Classroom 307	yes	W3	3/6/20	3/6/20	3/7/20	3/11/20	3/16/20	3/12/20	Included with wall 1	Included with wall 1	0	N/A	N/A		
	7300	1	3	307A	Storage	Classroom 307 Coat Room	yes	W1	3/6/20	3/6/20	3/7/20	3/11/20	3/16/20	3/12/20	60	4	2	Yes	28 ug/ft2; <10 ug/ft2		
	7300	1	3	307A	Storage	Classroom 307 Coat Room	yes	W3	3/6/20	3/6/20	3/7/20	3/11/20	3/16/20	3/12/20	Included with wall 1	Included with wall 1	-	-	-		
	7300	1	3	310C	Administrative Office	Office 307A	yes	W1	3/6/20	3/6/20	3/7/20	3/11/20	3/16/20	3/12/20	Included with ceiling	Included with ceiling	-	-	-		
	7300	1	3	310C	Administrative Office	Office 307A	yes	W2	3/6/20	3/6/20	3/7/20	3/11/20	3/16/20	3/12/20	Included with ceiling	Included with ceiling	-	-	-		
	7300	1	3	310C	Administrative Office	Office 307A	yes	Ceiling	3/6/20	3/6/20	3/7/20	3/11/20	3/16/20	3/12/20	120	15	5	Yes	<10 ug/ft2; 66 ug/ft2; 20 ug/ft2; 19 ug/ft2; 330 ug/ft2		
	7300	1	3	307B	Student Restrooms - Male (4-12)	Boy's Restroom	yes	W1	N/A	N/A	3/11/20	3/13/20	N/A	3/12/20	Included with ceiling	Included with ceiling	-	-	-	Damage behind radiator	
	7300	1	3	307B	Student Restrooms - Male (4-12)	Boy's Restroom	yes	W2	N/A	N/A	3/11/20	3/13/20	N/A	3/12/20	Included with ceiling	Included with ceiling	-	-	-		
	7300	1	3	307B	Student Restrooms - Male (4-12)	Boy's Restroom	yes	W3	N/A	N/A	3/11/20	3/13/20	N/A	3/12/20	Included with ceiling	Included with ceiling	-	-	-		
	7300	1	3	307B	Student Restrooms - Male (4-12)	Boy's Restroom	yes	W4	N/A	N/A	3/11/20	3/13/20	N/A	3/12/20	Included with ceiling	Included with ceiling	-	-	-		
	7300	1	3	307B	Student Restrooms - Male (4-12)	Boy's Restroom	yes	Ceiling	N/A	N/A	3/11/20	3/13/20	N/A	3/12/20	186	10	2	Yes	170 ug/ft2; <10 ug/ft2		
	7300	1	3	H311	Circulation (Hallway)	Hallway from Classrooms 303 to 307	yes	W1	N/A	N/A	3/26/20	4/1/20	N/A	4/1/20	360	9	0	N/A	N/A		
	7300	1	3	H311	Circulation (Hallway)	Hallway from Classrooms 303 to 307	yes	W3	N/A	N/A	3/26/20	4/1/20	N/A	4/1/20	Included with wall 1	Included with wall 1	-	-	-		
	7300	1	3	H311	Circulation (Hallway)	Hallway from Classrooms 303 to 307	yes	pipe	N/A	N/A	3/26/20	4/1/20	N/A	4/1/20	Included with wall 1	Included with wall 1	-	-	-		
	7300	1	3	H311	Circulation (Hallway)	Hallway from Classrooms 303 to 307	yes	door frame	N/A	N/A	3/26/20	4/1/20	N/A	4/1/20	Included with wall 1	Included with wall 1	-	-	-		
	7300	1	3	H311	Circulation (Hallway)	Hallway from Classrooms 303 to 307	yes	door	N/A	N/A	3/26/20	4/1/20	N/A	4/1/20	Included with wall 1	Included with wall 1	-	-	-		
	7300	1	3	S31	Stairs	Stairwell outside Classroom 308	yes	W1	N/A	N/A	3/27/20	4/9/20	N/A	4/9/20	Included with ceiling	Included with ceiling	-	-	-		
	7300	1	3	S31	Stairs	Stairwell outside Classroom 308	yes	W2	N/A	N/A	3/27/20	4/9/20	N/A	4/9/20	Included with ceiling	Included with ceiling	-	-	-		
	7300	1	3	S31	Stairs	Stairwell outside Classroom 308	yes	door	N/A	N/A	3/27/20	4/9/20	N/A	4/9/20	Included with ceiling	Included with ceiling	-	-	-		
	7300	1	3	S31	Stairs	Stairwell outside Classroom 308	yes	door frame	N/A	N/A	3/27/20	4/9/20	N/A	4/9/20	Included with ceiling	Included with ceiling	-	-	-		

Hopkinson

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Student/Teacher Occupied	Primary Component	Pre-Cleaning Completed (date)	Contents Moved (date)	Work Area Prepped (date)	Surfaces Stabilized (date)	Contents Back in Place (date)	Final Inspection Approval and Photos (date)	Square Footage of Work Area	Number of Required RRP Wipes	Number of Colorimetric Wipes Used to Pass	Final Colorimetric Wipe Submitted for AAS Analysis (yes/no)	AAS Analysis Results	Comments from Assessment	Comments from Oversight
	7300	1	3	S31	Stairs	Stairwell outside Classroom 308	yes	W4	N/A	N/A	3/27/20	4/9/20	N/A	4/9/20	Included with ceiling	Included with ceiling	-	-	-	bookshelf	
	7300	1	3	S31	Stairs	Stairwell outside Classroom 308	yes	Ceiling	N/A	N/A	3/27/20	4/9/20	N/A	4/9/20	297	8	0	N/A	N/A		
	7300	1	3	S31	Stairs	Stairwell outside Classroom 308	yes	newel post	N/A	N/A	3/27/20	4/9/20	N/A	4/9/20	Included with wall 1	Included with wall 1	-	-	-		
	7300	1	3	308	Primary	Classroom 308	yes	W1	3/6/20	3/6/20	3/7/20	3/11/20	3/16/20	3/12/20	928	24	3	Yes	<10 ug/ft2		
	7300	1	3	308	Primary	Classroom 308	yes	W2	3/6/20	3/6/20	3/7/20	3/11/20	3/16/20	3/12/20	Included with wall 1	Included with wall 1	-	-	-		
	7300	1	3	308	Primary	Classroom 308	yes	W3	3/6/20	3/6/20	3/7/20	3/11/20	3/16/20	3/12/20	Included with wall 1	Included with wall 1	-	-	-		
	7300	1	3	308	Primary	Classroom 308	yes	W4	3/6/20	3/6/20	3/7/20	3/11/20	3/16/20	3/12/20	Included with wall 1	Included with wall 1	-	-	-		
	7300	1	3	308A	Storage	Classroom 308 Closet	yes	W1	3/6/20	3/6/20	3/7/20	3/11/20	3/16/20	3/12/20	60	4	2	Yes	120 ug/ft2; <10 ug/ft2		
	7300	1	3	308A	Storage	Classroom 308 Closet	yes	W3	3/6/20	3/6/20	3/7/20	3/11/20	3/16/20	3/12/20	Included with wall 1	Included with wall 1	-	-	-		
	7300	1	3	308A	Storage	Classroom 308 Closet	yes	W4	3/6/20	3/6/20	3/7/20	3/11/20	3/16/20	3/12/20	Included with wall 1	Included with wall 1	-	-	-		
	7300	1	3	309	Primary	Classroom 309	yes	W1	3/6/20	3/6/20	3/8/20	3/12/20	3/16/20	3/12/20	870	22	3	Yes	<10 ug/ft2		
	7300	1	3	309	Primary	Classroom 309	yes	W2	3/6/20	3/6/20	3/8/20	3/12/20	3/16/20	3/12/20	Included with wall 1	Included with wall 1	-	-	-		
	7300	1	3	309	Primary	Classroom 309	yes	W3	3/6/20	3/6/20	3/8/20	3/12/20	3/16/20	3/12/20	Included with wall 1	Included with wall 1	-	-	-		
	7300	1	3	309	Primary	Classroom 309	yes	W4	3/6/20	3/6/20	3/8/20	3/12/20	3/16/20	3/12/20	Included with wall 1	Included with wall 1	-	-	-		
	7300	1	3	309A	Storage	Classroom 309 Coat Room	yes	W1	3/6/20	3/6/20	3/8/20	3/12/20	3/16/20	3/12/20	60	4	2	Yes	30 ug/ft2; 10 ug/ft2		
	7300	1	3	309A	Storage	Classroom 309 Coat Room	yes	W2	3/6/20	3/6/20	3/8/20	3/12/20	3/16/20	3/12/20	Included with wall 1	Included with wall 1	-	-	-		
	7300	1	3	309A	Storage	Classroom 309 Coat Room	yes	W3	3/6/20	3/6/20	3/8/20	3/12/20	3/16/20	3/12/20	Included with wall 1	Included with wall 1	-	-	-		
	7300	1	3	309A	Storage	Classroom 309 Coat Room	yes	W4	3/6/20	3/6/20	3/8/20	3/12/20	3/16/20	3/12/20	Included with wall 1	Included with wall 1	-	-	-		
	7300	1	3	310	Primary	Classroom 310	yes	W1	3/6/20	3/6/20	3/8/20	3/12/20	3/16/20	3/12/20	960	24	3	Yes	<10 ug/ft2		
	7300	1	3	310	Primary	Classroom 310	yes	W2	3/6/20	3/6/20	3/8/20	3/12/20	3/16/20	3/12/20	Included with wall 1	Included with wall 1	-	-	-		
	7300	1	3	310	Primary	Classroom 310	yes	W3	3/6/20	3/6/20	3/8/20	3/12/20	3/16/20	3/12/20	Included with wall 1	Included with wall 1	-	-	-		
	7300	1	3	310	Primary	Classroom 310	yes	W4	3/6/20	3/6/20	3/8/20	3/12/20	3/16/20	3/12/20	Included with wall 1	Included with wall 1	-	-	-		
	7300	1	3	310B	Storage	Classroom 310 Coat Room	yes	W2	3/6/20	3/6/20	3/8/20	3/12/20	3/16/20	3/12/20	60	6	3	Yes	39 ug/ft2; (2) <10 ug/ft2		
	7300	1	3	310B	Storage	Classroom 310 Coat Room	yes	W3	3/6/20	3/6/20	3/8/20	3/12/20	3/16/20	3/12/20	Included with wall 2	Included with wall 2	-	-	-		
	7300	1	3	310B	Storage	Classroom 310 Coat Room	yes	W4	3/6/20	3/6/20	3/8/20	3/12/20	3/16/20	3/12/20	Included with wall 2	Included with wall 2	-	-	-		
	7300	1	3	310A	Primary	Classroom 310A	yes	W1	3/6/20	3/6/20	3/8/20	3/12/20	3/16/20	3/12/20	250	28	4	Yes	<10 ug/ft2; 16 ug/ft2; 26 ug/ft2; 88 ug/ft2		
	7300	1	3	310A	Primary	Classroom 310A	yes	W2	3/6/20	3/6/20	3/12/20	3/12/20	3/16/20	3/12/20	Included with wall 1	Included with wall 1	-	-	-		
	7300	1	3	310A	Primary	Classroom 310A	yes	W3	3/6/20	3/6/20	3/12/20	3/12/20	3/16/20	3/12/20	Included with wall 1	Included with wall 1	-	-	-		
	7300	1	3	310A	Primary	Classroom 310A	yes	W4	3/6/20	3/6/20	3/12/20	3/12/20	3/16/20	3/12/20	Included with wall 1	Included with wall 1	-	-	-		
	7300	1	3	H312	Circulation (Hallway)	Hallway from Classrooms 308 to 310	yes	door	N/A	N/A	3/26/20	4/1/20	N/A	4/1/20	Included with wall 2	Included with wall 2	-	-	-		
	7300	1	3	H312	Circulation (Hallway)	Hallway from Classrooms 308 to 310	yes	door frame	N/A	N/A	3/26/20	4/1/20	N/A	4/1/20	Included with wall 2	Included with wall 2	-	-	-		
	7300	1	3	H312	Circulation (Hallway)	Hallway from Classrooms 308 to 310	yes	W2	N/A	N/A	3/26/20	4/1/20	N/A	4/1/20	360	9	0	N/A	N/A		
	7300	1	3	H312	Circulation (Hallway)	Hallway from Classrooms 308 to 310	yes	W4	N/A	N/A	3/26/20	4/1/20	N/A	4/1/20	Included with wall 2	Included with wall 2	-	-	-		

Additional Sampling Locations

Principal's Office Bathroom	48 ug/ft2 (5/7/20); <10 ug/ft2 (5/12/20)
Room 101 Coat Room	<10 ug/ft2 (5/7/20)
Classroom S2	24 ug/ft2 (5/12/20); <10 ug/ft2 (5/18/20)
Classroom S2 Closet	<10 ug/ft2 (5/12/20)
Office P3	<10 ug/ft2 (5/30/20)
Classroom 2	<10 ug/ft2 (5/30/20)
Classroom 2 Restroom	<10 ug/ft2 (5/30/20)
Classroom 1	<10 ug/ft2 (5/30/20)
Classroom 1 Restroom	<10 ug/ft2 (5/30/20)

Appendix D. FAAS Sample Results

**EMSL Analytical, Inc.**

200 Route 130 North, Cinnaminson, NJ 08077

Phone/Fax: (856) 303-2500 / (856) 786-5974

<http://www.EMSL.com>cinnaminsonleadlab@emsl.com

EMSL Order: 202005974

CustomerID: VRTX78

CustomerPO:

ProjectID:

Attn: **Vertex Aston**
The Vertex Companies, Inc.
700 Turner Way, Suite 105
Aston, PA 19014

Phone: (610) 558-8902
Fax: (610) 558-8904
Received: 07/08/20 12:45 PM
Collected: 7/8/2020

Test Report: Lead in Dust by Flame AAS (SW 846 3050B/7000B)*

<i>Client Sample Description</i>	<i>Lab ID</i>	<i>Collected</i>	<i>Analyzed</i>	<i>Area Sampled</i>	<i>Lead Concentration</i>
1	202005974-0001	7/8/2020	7/9/2020	1 ft ²	<10 µg/ft ²
Site: art room closet					

Phillip Worby, Lead Laboratory Manager
or other approved signatory

EMSL maintains liability limited to cost of analysis. Interpretation and use of test results are the responsibility of the client. This report relates only to the samples reported above, and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. The report reflects the samples as received. Results are generated from the field sampling data (sampling volumes and areas, locations, etc.) provided by the client on the Chain of Custody. Samples are within quality control criteria and met method specifications unless otherwise noted. Analysis following Lead in Dust by EMSL SOP/Determination of Environmental Lead by FLAA. Reporting limit is 10 ug/wipe. Ug/wipe = ug/ft² x area sampled in ft². Unless noted, results in this report are not blank corrected. The lab is not responsible for data reported in ug/ft² which is dependent upon the area provided by non-lab personnel. "<" (less than) result signifies that the analyte was not detected at or above the reporting limit. Measurement of uncertainty is available upon request. Definitions of modifications are available upon request.

Samples analyzed by EMSL Analytical, Inc. Cinnaminson, NJ NELAP Certifications: NJ 03036, NY 10872, PA 68-00367, AIHA-LAP, LLC ELLAP 100194, A2LA 2845.01

Initial report from 07/09/2020 14:57:38

**EMSL Analytical, Inc.**

200 Route 130 North, Cinnaminson, NJ 08077

Phone/Fax: (856) 303-2500 / (856) 786-5974

<http://www.EMSL.com>cinnaminsonleadlab@emsl.com

EMSL Order: 202005393

CustomerID: VRTX78

CustomerPO:

ProjectID:

Attn: **Vertex Aston**
The Vertex Companies, Inc.
700 Turner Way, Suite 105
Aston, PA 19014

Phone: (610) 558-8902
Fax: (610) 558-8904
Received: 06/22/20 12:55 PM
Collected: 6/22/2020

Project: **62843****Test Report: Lead in Dust by Flame AAS (SW 846 3050B/7000B)***

<i>Client Sample Description</i>	<i>Lab ID</i>	<i>Collected</i>	<i>Analyzed</i>	<i>Area Sampled</i>	<i>Lead Concentration</i>
1	202005393-0001	6/22/2020	6/23/2020	1 ft ²	<10 µg/ft ²
Site: stage left					
2	202005393-0002	6/22/2020	6/23/2020	1 ft ²	58 µg/ft ²
Site: art room closet					

Phillip Worby, Lead Laboratory Manager
or other approved signatory

*Analysis following Lead in Dust by EMSL SOP/ Determination of Environmental Lead by FLAA. Reporting limit is 10 µg/wipe. ug/wipe =µg/ft² x area sampled in ft². Unless noted, results in this report are not blank corrected. EMSL maintain liability limited to cost of analysis. Interpretation and use of test results are the responsibility of the client. This report relates only to the samples reported above and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. The report reflects the samples as received. When the information supplied by the customer can affect the validity of the results, it will be noted on the report. The lab is not responsible for data reported in µg/ft² which is dependent on the area provided by non-lab personnel. The test results contained within this report meet the requirements of NELAP unless otherwise noted. "<" (less than) results signifies that the analyte was not detected at or above the reporting limit. Measurement of uncertainty is available upon request. The QC data associated with the sample results included in this report meet the recovery and precision requirements

Samples analyzed by EMSL Analytical, Inc. Cinnaminson, NJ NELAP Certifications: NJ 03036, NY 10872, PA 68-00367, AIHA-LAP, LLC ELLAP 100194, A2LA 2845.01

Initial report from 06/23/2020 15:11:03

**EMSL Analytical, Inc.**

200 Route 130 North, Cinnaminson, NJ 08077

Phone/Fax: (856) 303-2500 / (856) 786-5974

<http://www.EMSL.com>cinnaminsonleadlab@emsl.com

EMSL Order: 202004980

CustomerID: VRTX78

CustomerPO:

ProjectID:

Attn: **Vertex Aston**
The Vertex Companies, Inc.
700 Turner Way, Suite 105
Aston, PA 19014

Phone: (610) 558-8902
Fax: (610) 558-8904
Received: 06/09/20 12:55 PM
Collected: 6/9/2020

Project: 62843

Test Report: Lead in Dust by Flame AAS (SW 846 3050B/7000B)*

<i>Client Sample Description</i>	<i>Lab ID</i>	<i>Collected</i>	<i>Analyzed</i>	<i>Area Sampled</i>	<i>Lead Concentration</i>
1	202004980-0001	6/9/2020	6/10/2020	1 ft ²	<10 µg/ft ²
Site: Art Room Coatroom					
2	202004980-0002	6/9/2020	6/10/2020	1 ft ²	30 µg/ft ²
Site: Art Room Closet					
3	202004980-0003	6/9/2020	6/10/2020	1 ft ²	14 µg/ft ²
Site: Auditorium Stage Left					
4	202004980-0004	6/9/2020	6/10/2020	1 ft ²	<10 µg/ft ²
Site: Classroom 107 Bathroom					

Phillip Worby, Lead Laboratory Manager
or other approved signatory

*Analysis following Lead in Dust by EMSL SOP/ Determination of Environmental Lead by FLAA. Reporting limit is 10 µg/wipe. ug/wipe = µg/ft² x area sampled in ft². Unless noted, results in this report are not blank corrected. EMSL maintain liability limited to cost of analysis. Interpretation and use of test results are the responsibility of the client. This report relates only to the samples reported above and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. The report reflects the samples as received. When the information supplied by the customer can affect the validity of the results, it will be noted on the report. The lab is not responsible for data reported in µg/ft² which is dependent on the area provided by non-lab personnel. The test results contained within this report meet the requirements of NELAC unless otherwise noted. "<" (less than) results signifies that the analyte was not detected at or above the reporting limit. Measurement of uncertainty is available upon request. The QC data associated with the sample results included in this report meet the recovery and precision requirements

Samples analyzed by EMSL Analytical, Inc. Cinnaminson, NJ NELAP Certifications: NJ 03036, NY 10872, PA 68-00367, AIHA-LAP, LLC ELLAP 100194, A2LA 2845.01

Initial report from 06/10/2020 13:55:19

**EMSL Analytical, Inc.**

200 Route 130 North, Cinnaminson, NJ 08077

Phone/Fax: (856) 303-2500 / (856) 786-5974

<http://www.EMSL.com>cinnaminsonleadlab@emsl.com

EMSL Order: 202004722

CustomerID: VRTX78

CustomerPO:

ProjectID:

Attn: **Vertex Aston**
The Vertex Companies, Inc.
700 Turner Way, Suite 105
Aston, PA 19014

Phone: (610) 558-8902
 Fax: (610) 558-8904
 Received: 06/01/20 9:00 AM
 Collected: 5/30/2020

Project: 62843

Test Report: Lead in Dust by Flame AAS (SW 846 3050B/7000B)*

<i>Client Sample Description</i>	<i>Lab ID</i>	<i>Collected</i>	<i>Analyzed</i>	<i>Area Sampled</i>	<i>Lead Concentration</i>
1	202004722-0001	5/28/2020	6/1/2020	1 ft ²	<10 µg/ft ²
Site: ESOL					
2	202004722-0002	5/28/2020	6/1/2020	1 ft ²	<10 µg/ft ²
Site: ESOL Closet					
3	202004722-0003	5/28/2020	6/1/2020	1 ft ²	<10 µg/ft ²
Site: Kitchen W2					
4	202004722-0004	5/28/2020	6/1/2020	1 ft ²	<10 µg/ft ²
Site: Kitchen W4					
5	202004722-0005	5/30/2020	6/1/2020	1 ft ²	<10 µg/ft ²
Site: B1 - Artroom					
6	202004722-0006	5/30/2020	6/1/2020	1 ft ²	50 µg/ft ²
Site: B1 - Artroom Coatroom					
7	202004722-0007	5/30/2020	6/1/2020	1 ft ²	<10 µg/ft ²
Site: Auditorium W1					
8	202004722-0008	5/30/2020	6/1/2020	1 ft ²	<10 µg/ft ²
Site: Auditorium W2					
9	202004722-0009	5/30/2020	6/1/2020	1 ft ²	<10 µg/ft ²
Site: Auditorium W3					
10	202004722-0010	5/30/2020	6/1/2020	1 ft ²	<10 µg/ft ²
Site: Auditorium W4					
11	202004722-0011	5/30/2020	6/1/2020	1 ft ²	<10 µg/ft ²
Site: Stage Right					
12	202004722-0012	5/30/2020	6/1/2020	1 ft ²	13 µg/ft ²
Site: Stage Left					
13	202004722-0013	5/30/2020	6/1/2020	1 ft ²	<10 µg/ft ²
Site: Stage					
14	202004722-0014	5/30/2020	6/1/2020	1 ft ²	<10 µg/ft ²
Site: Bathroom 1					
15	202004722-0015	5/30/2020	6/1/2020	1 ft ²	<10 µg/ft ²
Site: Classroom 1					

Phillip Worby, Lead Laboratory Manager
 or other approved signatory

*Analysis following Lead in Dust by EMSL SOP/ Determination of Environmental Lead by FLAA. Reporting limit is 10 µg/wipe. ug/wipe =µg/ft² x area sampled in ft². Unless noted, results in this report are not blank corrected. EMSL maintain liability limited to cost of analysis. Interpretation and use of test results are the responsibility of the client. This report relates only to the samples reported above and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. The report reflects the samples as received. When the information supplied by the customer can affect the validity of the results, it will be noted on the report. The lab is not responsible for data reported in µg/ft² which is dependent on the area provided by non-lab personnel. The test results contained within this report meet the requirements of NELAC unless otherwise noted. "<" (less than) results signifies that the analyte was not detected at or above the reporting limit. Measurement of uncertainty is available upon request. The QC data associated with the sample results included in this report meet the recovery and precision requirements

Samples analyzed by EMSL Analytical, Inc. Cinnaminson, NJ NELAP Certifications: NJ 03036, NY 10872, PA 68-00367, AIHA-LAP, LLC ELLAP 100194, A2LA 2845.01

Initial report from 06/02/2020 11:03:55

**EMSL Analytical, Inc.**

200 Route 130 North, Cinnaminson, NJ 08077

Phone/Fax: (856) 303-2500 / (856) 786-5974

<http://www.EMSL.com>cinnaminsonleadlab@emsl.com

EMSL Order: 202004722

CustomerID: VRTX78

CustomerPO:

ProjectID:

Attn: **Vertex Aston**
The Vertex Companies, Inc.
700 Turner Way, Suite 105
Aston, PA 19014

Phone: (610) 558-8902
Fax: (610) 558-8904
Received: 06/01/20 9:00 AM
Collected: 5/30/2020

Project: **62843****Test Report: Lead in Dust by Flame AAS (SW 846 3050B/7000B)***

<i>Client Sample Description</i>	<i>Lab ID</i>	<i>Collected</i>	<i>Analyzed</i>	<i>Area Sampled</i>	<i>Lead Concentration</i>
16	202004722-0016	5/30/2020	6/1/2020	1 ft ²	<10 µg/ft ²
Site: Additional Space					
17	202004722-0017	5/30/2020	6/1/2020	1 ft ²	<10 µg/ft ²
Site: Bathroom 2					
18	202004722-0018	5/30/2020	6/1/2020	1 ft ²	<10 µg/ft ²
Site: Classroom 2					

Phillip Worby, Lead Laboratory Manager
or other approved signatory

*Analysis following Lead in Dust by EMSL SOP/ Determination of Environmental Lead by FLAA. Reporting limit is 10 µg/wipe. ug/wipe =µg/ft² x area sampled in ft². Unless noted, results in this report are not blank corrected. EMSL maintain liability limited to cost of analysis. Interpretation and use of test results are the responsibility of the client. This report relates only to the samples reported above and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. The report reflects the samples as received. When the information supplied by the customer can affect the validity of the results, it will be noted on the report. The lab is not responsible for data reported in µg/ft² which is dependent on the area provided by non-lab personnel. The test results contained within this report meet the requirements of NELAC unless otherwise noted. "<" (less than) results signifies that the analyte was not detected at or above the reporting limit. Measurement of uncertainty is available upon request. The QC data associated with the sample results included in this report meet the recovery and precision requirements

Samples analyzed by EMSL Analytical, Inc. Cinnaminson, NJ NELAP Certifications: NJ 03036, NY 10872, PA 68-00367, AIHA-LAP, LLC ELLAP 100194, A2LA 2845.01

Initial report from 06/02/2020 11:03:55

**EMSL Analytical, Inc.**

200 Route 130 North, Cinnaminson, NJ 08077

Phone/Fax: (856) 303-2500 / (856) 786-5974

<http://www.EMSL.com>cinnaminsonleadlab@emsl.com

EMSL Order: 202004355

CustomerID: VRTX78

CustomerPO:

ProjectID:

Attn: **Vertex Aston**
The Vertex Companies, Inc.
700 Turner Way, Suite 105
Aston, PA 19014

Phone: (610) 558-8902
Fax: (610) 558-8904
Received: 05/18/20 10:50 AM
Collected: 5/18/2020

Project: 62843

Test Report: Lead in Dust by Flame AAS (SW 846 3050B/7000B)*

Client Sample Description	Lab ID	Collected	Analyzed	Area Sampled	Lead Concentration
1	202004355-0001	5/15/2020	5/18/2020	1 ft ²	<10 µg/ft ²
Site: Gym: Rim 1					
2	202004355-0002	5/15/2020	5/18/2020	1 ft ²	<10 µg/ft ²
Site: Gym: Rim 2					
3	202004355-0003	5/15/2020	5/18/2020	1 ft ²	<10 µg/ft ²
Site: Gym: Center					
4	202004355-0004	5/15/2020	5/18/2020	1 ft ²	<10 µg/ft ²
Site: Gym: Rim 3					
5	202004355-0005	5/15/2020	5/18/2020	1 ft ²	<10 µg/ft ²
Site: Office 1					
6	202004355-0006	5/15/2020	5/18/2020	1 ft ²	<10 µg/ft ²
Site: Office 2					
7	202004355-0007	5/18/2020	5/18/2020	1 ft ²	<10 µg/ft ²
Site: Principal Closet					
8	202004355-0008	5/18/2020	5/18/2020	1 ft ²	<10 µg/ft ²
Site: Classroom S1 Closet					
9	202004355-0009	5/18/2020	5/18/2020	1 ft ²	<10 µg/ft ²
Site: Classroom S2					

Phillip Worby, Lead Laboratory Manager
or other approved signatory

*Analysis following Lead in Dust by EMSL SOP/ Determination of Environmental Lead by FLAA. Reporting limit is 10 µg/wipe. ug/wipe =µg/ft² x area sampled in ft². Unless noted, results in this report are not blank corrected. EMSL maintain liability limited to cost of analysis. Interpretation and use of test results are the responsibility of the client. This report relates only to the samples reported above and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. The report reflects the samples as received. When the information supplied by the customer can affect the validity of the results, it will be noted on the report. The lab is not responsible for data reported in µg/ft² which is dependent on the area provided by non-lab personnel. The test results contained within this report meet the requirements of NELAP unless otherwise noted. "<" (less than) results signifies that the analyte was not detected at or above the reporting limit. Measurement of uncertainty is available upon request. The QC data associated with the sample results included in this report meet the recovery and precision requirements

Samples analyzed by EMSL Analytical, Inc. Cinnaminson, NJ NELAP Certifications: NJ 03036, NY 10872, PA 68-00367, AIHA-LAP, LLC ELLAP 100194, A2LA 2845.01

Initial report from 05/19/2020 10:33:56

**EMSL Analytical, Inc.**

200 Route 130 North, Cinnaminson, NJ 08077

Phone/Fax: (856) 303-2500 / (856) 786-5974

<http://www.EMSL.com>cinnaminsonleadlab@emsl.com

EMSL Order: 202004266

CustomerID: VRTX78

CustomerPO:

ProjectID:

Attn: **Vertex Aston**
The Vertex Companies, Inc.
700 Turner Way, Suite 105
Aston, PA 19014

Phone: (610) 558-8902
Fax: (610) 558-8904
Received: 05/13/20 10:25 AM
Collected: 5/12/2020

Project: **62843****Test Report: Lead in Dust by Flame AAS (SW 846 3050B/7000B)***

<i>Client Sample Description</i>	<i>Lab ID</i>	<i>Collected</i>	<i>Analyzed</i>	<i>Area Sampled</i>	<i>Lead Concentration</i>
1	202004266-0001	5/12/2020	5/13/2020	144 in ²	<10 µg/ft ²
Site: Classroom S1					
2	202004266-0002	5/12/2020	5/13/2020	144 in ²	24 µg/ft ²
Site: Classroom S2					
3	202004266-0003	5/12/2020	5/13/2020	144 in ²	<10 µg/ft ²
Site: Classroom S2 Closet					
4	202004266-0004	5/12/2020	5/13/2020	144 in ²	68 µg/ft ²
Site: Classroom S1 Closet					
5	202004266-0005	5/12/2020	5/13/2020	144 in ²	<10 µg/ft ²
Site: Rm 210 Classroom					
6	202004266-0006	5/12/2020	5/13/2020	144 in ²	<10 µg/ft ²
Site: Rm 206 Office Space					
7	202004266-0007	5/12/2020	5/13/2020	144 in ²	190 µg/ft ²
Site: Rm 107 Bathroom					
8	202004266-0008	5/12/2020	5/13/2020	144 in ²	<10 µg/ft ²
Site: Main Office Closet					
9	202004266-0009	5/12/2020	5/13/2020	144 in ²	11 µg/ft ²
Site: Principal Office Closet					
10	202004266-0010	5/12/2020	5/13/2020	144 in ²	<10 µg/ft ²
Site: Principal Office Bathroom					

Phillip Worby, Lead Laboratory Manager
or other approved signatory

*Analysis following Lead in Dust by EMSL SOP/ Determination of Environmental Lead by FLAA. Reporting limit is 10 µg/wipe. ug/wipe =µg/ft² x area sampled in ft². Unless noted, results in this report are not blank corrected. EMSL maintain liability limited to cost of analysis. Interpretation and use of test results are the responsibility of the client. This report relates only to the samples reported above and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. The report reflects the samples as received. When the information supplied by the customer can affect the validity of the results, it will be noted on the report. The lab is not responsible for data reported in µg/ft² which is dependent on the area provided by non-lab personnel. The test results contained within this report meet the requirements of NELAC unless otherwise noted. "<" (less than) results signifies that the analyte was not detected at or above the reporting limit. Measurement of uncertainty is available upon request. The QC data associated with the sample results included in this report meet the recovery and precision requirements

Samples analyzed by EMSL Analytical, Inc. Cinnaminson, NJ NELAP Certifications: NJ 03036, NY 10872, PA 68-00367, AIHA-LAP, LLC ELLAP 100194, A2LA 2845.01

Initial report from 05/14/2020 12:22:57

**EMSL Analytical, Inc.**

200 Route 130 North, Cinnaminson, NJ 08077

Phone/Fax: (856) 303-2500 / (856) 786-5974

<http://www.EMSL.com>cinnaminsonleadlab@emsl.com

EMSL Order: 202004170

CustomerID: VRTX78

CustomerPO:

ProjectID:

Attn: **Vertex Aston**
The Vertex Companies, Inc.
700 Turner Way, Suite 105
Aston, PA 19014

Phone: (610) 558-8902
 Fax: (610) 558-8904
 Received: 05/07/20 3:30 PM
 Collected: 5/7/2020

Project: 62843

Test Report: Lead in Dust by Flame AAS (SW 846 3050B/7000B)*

<i>Client Sample Description</i>	<i>Lab ID</i>	<i>Collected</i>	<i>Analyzed</i>	<i>Area Sampled</i>	<i>Lead Concentration</i>
1	202004170-0001	5/7/2020	5/8/2020	1 ft ²	<10 µg/ft ²
Site: Rm 103 CL W1					
2	202004170-0002	5/7/2020	5/8/2020	1 ft ²	<10 µg/ft ²
Site: Rm 103A Coat Room W2					
3	202004170-0003	5/7/2020	5/8/2020	1 ft ²	<10 µg/ft ²
Site: Rm 102 CL W3					
4	202004170-0004	5/7/2020	5/8/2020	1 ft ²	<10 µg/ft ²
Site: Rm 102A Coat Room W4					
5	202004170-0005	5/7/2020	5/8/2020	1 ft ²	<10 µg/ft ²
Site: Rm 101 Classroom E1					
6	202004170-0006	5/7/2020	5/8/2020	1 ft ²	<10 µg/ft ²
Site: Rm 101 Coat Room W2					
7	202004170-0007	5/7/2020	5/8/2020	1 ft ²	<10 µg/ft ²
Site: Rm 101 Bathroom E3					
8	202004170-0008	5/7/2020	5/8/2020	1 ft ²	<10 µg/ft ²
Site: Rm 107B Male Bathroom W1					
9	202004170-0009	5/7/2020	5/8/2020	1 ft ²	<10 µg/ft ²
Site: Rm 107 Classroom W2					
10	202004170-0010	5/7/2020	5/8/2020	1 ft ²	25 µg/ft ²
Site: Main Office Closet W3					
11	202004170-0011	5/7/2020	5/8/2020	1 ft ²	<10 µg/ft ²
Site: Principal Office W4					
12	202004170-0012	5/7/2020	5/8/2020	1 ft ²	<10 µg/ft ²
Site: Rm 110 Classroom W1					
13	202004170-0013	5/7/2020	5/8/2020	1 ft ²	<10 µg/ft ²
Site: Rm 106 Classroom W2					
14	202004170-0014	5/7/2020	5/8/2020	1 ft ²	<10 µg/ft ²
Site: Rm 107A Coat Room W3					
15	202004170-0015	5/7/2020	5/8/2020	1 ft ²	<10 µg/ft ²
Site: Rom 109 Classroom W4					

Phillip Worby, Lead Laboratory Manager
 or other approved signatory

*Analysis following Lead in Dust by EMSL SOP/ Determination of Environmental Lead by FLAA. Reporting limit is 10 µg/wipe. ug/wipe =µg/ft² x area sampled in ft². Unless noted, results in this report are not blank corrected. EMSL maintain liability limited to cost of analysis. Interpretation and use of test results are the responsibility of the client. This report relates only to the samples reported above and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. The report reflects the samples as received. When the information supplied by the customer can affect the validity of the results, it will be noted on the report. The lab is not responsible for data reported in µg/ft² which is dependent on the area provided by non-lab personnel. The test results contained within this report meet the requirements of NELAC unless otherwise noted. "<" (less than) results signifies that the analyte was not detected at or above the reporting limit. Measurement of uncertainty is available upon request. The QC data associated with the sample results included in this report meet the recovery and precision requirements

Samples analyzed by EMSL Analytical, Inc. Cinnaminson, NJ NELAP Certifications: NJ 03036, NY 10872, PA 68-00367, AIHA-LAP, LLC ELLAP 100194, A2LA 2845.01

Initial report from 05/08/2020 15:22:42

**EMSL Analytical, Inc.**

200 Route 130 North, Cinnaminson, NJ 08077

Phone/Fax: (856) 303-2500 / (856) 786-5974

<http://www.EMSL.com>cinnaminsonleadlab@emsl.com

EMSL Order: 202004170

CustomerID: VRTX78

CustomerPO:

ProjectID:

Attn: **Vertex Aston**
The Vertex Companies, Inc.
700 Turner Way, Suite 105
Aston, PA 19014

Phone: (610) 558-8902
 Fax: (610) 558-8904
 Received: 05/07/20 3:30 PM
 Collected: 5/7/2020

Project: 62843

Test Report: Lead in Dust by Flame AAS (SW 846 3050B/7000B)*

<i>Client Sample Description</i>	<i>Lab ID</i>	<i>Collected</i>	<i>Analyzed</i>	<i>Area Sampled</i>	<i>Lead Concentration</i>
16	202004170-0016	5/7/2020	5/8/2020	1 ft ²	48 µg/ft ²
Site: Principal Office Bathroom W1					
17	202004170-0017	5/7/2020	5/8/2020	1 ft ²	<10 µg/ft ²
Site: Rm 110A Closet W2					
18	202004170-0018	5/7/2020	5/8/2020	1 ft ²	<10 µg/ft ²
Site: Rm 106A Closet W3					
19	202004170-0019	5/7/2020	5/8/2020	1 ft ²	<10 µg/ft ²
Site: Rm 108A Coat Room W4					
20	202004170-0020	5/7/2020	5/8/2020	1 ft ²	<10 µg/ft ²
Site: Main Office W1					
21	202004170-0021	5/7/2020	5/8/2020	1 ft ²	<10 µg/ft ²
Site: Rm 307A Office W2					
22	202004170-0022	5/7/2020	5/8/2020	1 ft ²	10 µg/ft ²
Site: Rm 200A Nurse Bathroom W3					
23	202004170-0023	5/7/2020	5/8/2020	1 ft ²	<10 µg/ft ²
Site: Rm 310A W4					
24	202004170-0024	5/7/2020	5/8/2020	1 ft ²	<10 µg/ft ²
Site: Rm 105 Classroom W1					
25	202004170-0025	5/7/2020	5/8/2020	1 ft ²	<10 µg/ft ²
Site: Rm 109A Coat Room W2					
26	202004170-0026	5/7/2020	5/8/2020	1 ft ²	<10 µg/ft ²
Site: Rm 200 Nurse Room W3					
27	202004170-0027	5/7/2020	5/8/2020	1 ft ²	12 µg/ft ²
Site: Rm 107 Bathroom W4					
28	202004170-0028	5/7/2020	5/8/2020	1 ft ²	<10 µg/ft ²
Site: Rm 104A Coat Room W1					
29	202004170-0029	5/7/2020	5/8/2020	1 ft ²	<10 µg/ft ²
Site: Rm 108 Classroom W2					
30	202004170-0030	5/7/2020	5/8/2020	1 ft ²	<10 µg/ft ²
Site: Rm 103B Girl's Bathroom W3					

Phillip Worby, Lead Laboratory Manager
 or other approved signatory

*Analysis following Lead in Dust by EMSL SOP/ Determination of Environmental Lead by FLAA. Reporting limit is 10 µg/wipe. ug/wipe =µg/ft² x area sampled in ft². Unless noted, results in this report are not blank corrected. EMSL maintain liability limited to cost of analysis. Interpretation and use of test results are the responsibility of the client. This report relates only to the samples reported above and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. The report reflects the samples as received. When the information supplied by the customer can affect the validity of the results, it will be noted on the report. The lab is not responsible for data reported in µg/ft² which is dependent on the area provided by non-lab personnel. The test results contained within this report meet the requirements of NELAP unless otherwise noted. "<" (less than) results signifies that the analyte was not detected at or above the reporting limit. Measurement of uncertainty is available upon request. The QC data associated with the sample results included in this report meet the recovery and precision requirements

Samples analyzed by EMSL Analytical, Inc. Cinnaminson, NJ NELAP Certifications: NJ 03036, NY 10872, PA 68-00367, AIHA-LAP, LLC ELLAP 100194, A2LA 2845.01

Initial report from 05/08/2020 15:22:42

**EMSL Analytical, Inc.**

200 Route 130 North, Cinnaminson, NJ 08077

Phone/Fax: (856) 303-2500 / (856) 786-5974

<http://www.EMSL.com>cinnaminsonleadlab@emsl.com

EMSL Order: 202004170

CustomerID: VRTX78

CustomerPO:

ProjectID:

Attn: **Vertex Aston**
The Vertex Companies, Inc.
700 Turner Way, Suite 105
Aston, PA 19014

Phone: (610) 558-8902
Fax: (610) 558-8904
Received: 05/07/20 3:30 PM
Collected: 5/7/2020

Project: **62843****Test Report: Lead in Dust by Flame AAS (SW 846 3050B/7000B)***

<i>Client Sample Description</i>	<i>Lab ID</i>	<i>Collected</i>	<i>Analyzed</i>	<i>Area Sampled</i>	<i>Lead Concentration</i>
31	202004170-0031	5/7/2020	5/8/2020	1 ft ²	22 µg/ft ²
Site: Principal Office Closet W4					
32	202004170-0032	5/7/2020	5/8/2020	1 ft ²	<10 µg/ft ²
Site: Rm 104 Classroom W1					
33	202004170-0033	5/7/2020	5/8/2020	1 ft ²	<10 µg/ft ²
Site: Rm 105A Coat Room W2					

Phillip Worby, Lead Laboratory Manager
or other approved signatory

*Analysis following Lead in Dust by EMSL SOP/ Determination of Environmental Lead by FLAA. Reporting limit is 10 µg/wipe. ug/wipe =µg/ft² x area sampled in ft². Unless noted, results in this report are not blank corrected. EMSL maintain liability limited to cost of analysis. Interpretation and use of test results are the responsibility of the client. This report relates only to the samples reported above and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. The report reflects the samples as received. When the information supplied by the customer can affect the validity of the results, it will be noted on the report. The lab is not responsible for data reported in µg/ft² which is dependent on the area provided by non-lab personnel. The test results contained within this report meet the requirements of NELAC unless otherwise noted. "<" (less than) results signifies that the analyte was not detected at or above the reporting limit. Measurement of uncertainty is available upon request. The QC data associated with the sample results included in this report meet the recovery and precision requirements

Samples analyzed by EMSL Analytical, Inc. Cinnaminson, NJ NELAP Certifications: NJ 03036, NY 10872, PA 68-00367, AIHA-LAP, LLC ELLAP 100194, A2LA 2845.01

Initial report from 05/08/2020 15:22:42

**EMSL Analytical, Inc.**

200 Route 130 North, Cinnaminson, NJ 08077

Phone/Fax: (856) 303-2500 / (856) 786-5974

<http://www.EMSL.com>cinnaminsonleadlab@emsl.com

EMSL Order: 202004033

CustomerID: VRTX78

CustomerPO:

ProjectID:

Attn: **Vertex Aston**
The Vertex Companies, Inc.
700 Turner Way, Suite 105
Aston, PA 19014

Phone: (610) 558-8902
Fax: (610) 558-8904
Received: 05/01/20 11:10 AM
Collected: 5/1/2020

Project: **62843****Test Report: Lead in Dust by Flame AAS (SW 846 3050B/7000B)***

Client Sample Description	Lab ID	Collected	Analyzed	Area Sampled	Lead Concentration
1	202004033-0001	5/1/2020	5/1/2020	1 ft ²	<10 µg/ft ²
Site: Rm 213 Teacher's Lounge (W1)					
2	202004033-0002	5/1/2020	5/1/2020	1 ft ²	<10 µg/ft ²
Site: Rm 214A Staff Women Restroom (W2)					
3	202004033-0003	5/1/2020	5/1/2020	1 ft ²	<10 µg/ft ²
Site: Rm 214 Counselor's Office (W1)					
4	202004033-0004	5/1/2020	5/1/2020	1 ft ²	<10 µg/ft ²
Site: Rm 202 Classroom (W1)					
5	202004033-0005	5/1/2020	5/1/2020	1 ft ²	<10 µg/ft ²
Site: Rm 202A Classroom Coat Room (W2)					
6	202004033-0006	5/1/2020	5/1/2020	1 ft ²	<10 µg/ft ²
Site: Rm 201 Classroom (W3)					
7	202004033-0007	5/1/2020	5/1/2020	1 ft ²	<10 µg/ft ²
Site: Rm 201A Coat Room (W4)					

Phillip Worby, Lead Laboratory Manager
or other approved signatory

*Analysis following Lead in Dust by EMSL SOP/ Determination of Environmental Lead by FLAA. Reporting limit is 10 µg/wipe. ug/wipe =µg/ft² x area sampled in ft². Unless noted, results in this report are not blank corrected. EMSL maintain liability limited to cost of analysis. Interpretation and use of test results are the responsibility of the client. This report relates only to the samples reported above and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. The report reflects the samples as received. When the information supplied by the customer can affect the validity of the results, it will be noted on the report. The lab is not responsible for data reported in µg/ft² which is dependent on the area provided by non-lab personnel. The test results contained within this report meet the requirements of NELAC unless otherwise noted. "<" (less than) results signifies that the analyte was not detected at or above the reporting limit. Measurement of uncertainty is available upon request. The QC data associated with the sample results included in this report meet the recovery and precision requirements

Samples analyzed by EMSL Analytical, Inc. Cinnaminson, NJ NELAP Certifications: NJ 03036, NY 10872, PA 68-00367, AIHA-LAP, LLC ELLAP 100194, A2LA 2845.01

Initial report from 05/04/2020 12:39:17

**EMSL Analytical, Inc.**

200 Route 130 North, Cinnaminson, NJ 08077

Phone/Fax: (856) 303-2500 / (856) 786-5974

<http://www.EMSL.com>cinnaminsonleadlab@emsl.com

EMSL Order: 202003891

CustomerID: VRTX78

CustomerPO:

ProjectID:

Attn: **Vertex Aston**
The Vertex Companies, Inc.
700 Turner Way, Suite 105
Aston, PA 19014

Phone: (610) 558-8902
Fax: (610) 558-8904
Received: 04/23/20 2:25 PM
Collected: 4/23/2020

Project: **62843 / Hopkinson 2nd Floor Retest****Test Report: Lead in Dust by Flame AAS (SW 846 3050B/7000B)***

<i>Client Sample Description</i>	<i>Lab ID</i>	<i>Collected</i>	<i>Analyzed</i>	<i>Area Sampled</i>	<i>Lead Concentration</i>
1	202003891-0001	4/23/2020	4/24/2020	144 in ²	<10 µg/ft ²
Site: Rm 210B Coat Room W2					
2	202003891-0002	4/23/2020	4/24/2020	144 in ²	<10 µg/ft ²
Site: Rm 209A Coat Room W3					
3	202003891-0003	4/23/2020	4/24/2020	144 in ²	<10 µg/ft ²
Site: Rm 208A Coat Room W4					
4	202003891-0004	4/23/2020	4/24/2020	144 in ²	<10 µg/ft ²
Site: Rm 207B Boy's Restroom W2					
5	202003891-0005	4/23/2020	4/24/2020	144 in ²	<10 µg/ft ²
Site: Rm 207A Coat Room W1					
6	202003891-0006	4/23/2020	4/24/2020	144 in ²	<10 µg/ft ²
Site: Rm 205 Classroom W3					
7	202003891-0007	4/23/2020	4/24/2020	144 in ²	<10 µg/ft ²
Site: Rm 203B Girls Restroom W2					

Phillip Worby, Lead Laboratory Manager
or other approved signatory

*Analysis following Lead in Dust by EMSL SOP/ Determination of Environmental Lead by FLAA. Reporting limit is 10 µg/wipe. ug/wipe = µg/ft² x area sampled in ft². Unless noted, results in this report are not blank corrected. EMSL maintain liability limited to cost of analysis. Interpretation and use of test results are the responsibility of the client. This report relates only to the samples reported above and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. The report reflects the samples as received. When the information supplied by the customer can affect the validity of the results, it will be noted on the report. The lab is not responsible for data reported in µg/ft² which is dependent on the area provided by non-lab personnel. The test results contained within this report meet the requirements of NELAC unless otherwise noted. "<" (less than) results signifies that the analyte was not detected at or above the reporting limit. Measurement of uncertainty is available upon request. The QC data associated with the sample results included in this report meet the recovery and precision requirements

Samples analyzed by EMSL Analytical, Inc. Cinnaminson, NJ NELAP Certifications: NJ 03036, NY 10872, PA 68-00367, AIHA-LAP, LLC ELLAP 100194, A2LA 2845.01

Initial report from 04/24/2020 15:21:03

**EMSL Analytical, Inc.**

200 Route 130 North, Cinnaminson, NJ 08077

Phone/Fax: (856) 303-2500 / (856) 786-5974

<http://www.EMSL.com>cinnaminsonleadlab@emsl.com

EMSL Order: 202003890

CustomerID: VRTX78

CustomerPO:

ProjectID:

Attn: **Vertex Aston**
The Vertex Companies, Inc.
700 Turner Way, Suite 105
Aston, PA 19014

Phone: (610) 558-8902
Fax: (610) 558-8904
Received: 04/23/20 2:25 PM
Collected: 4/23/2020

Project: **62843 / Hopkinson 3rd FL Retest - 3rd****Test Report: Lead in Dust by Flame AAS (SW 846 3050B/7000B)***

<i>Client Sample Description</i>	<i>Lab ID</i>	<i>Collected</i>	<i>Analyzed</i>	<i>Area Sampled</i>	<i>Lead Concentration</i>
1	202003890-0001	4/23/2020	4/24/2020	144 in ²	<10 µg/ft ²
Site: Rm 304A Coat Room W1					
2	202003890-0002	4/23/2020	4/24/2020	144 in ²	16 µg/ft ²
Site: Rm 310A Class Room W4					
3	202003890-0003	4/23/2020	4/24/2020	144 in ²	66 µg/ft ²
Site: Office 307A W1					

Phillip Worby, Lead Laboratory Manager
or other approved signatory

*Analysis following Lead in Dust by EMSL SOP/ Determination of Environmental Lead by FLAA. Reporting limit is 10 µg/wipe. ug/wipe = µg/ft² x area sampled in ft². Unless noted, results in this report are not blank corrected. EMSL maintain liability limited to cost of analysis. Interpretation and use of test results are the responsibility of the client. This report relates only to the samples reported above and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. The report reflects the samples as received. When the information supplied by the customer can affect the validity of the results, it will be noted on the report. The lab is not responsible for data reported in µg/ft² which is dependent on the area provided by non-lab personnel. The test results contained within this report meet the requirements of NELAC unless otherwise noted. "<" (less than) results signifies that the analyte was not detected at or above the reporting limit. Measurement of uncertainty is available upon request. The QC data associated with the sample results included in this report meet the recovery and precision requirements

Samples analyzed by EMSL Analytical, Inc. Cinnaminson, NJ NELAP Certifications: NJ 03036, NY 10872, PA 68-00367, AIHA-LAP, LLC ELLAP 100194, A2LA 2845.01

Initial report from 04/24/2020 15:20:20

**EMSL Analytical, Inc.**

200 Route 130 North, Cinnaminson, NJ 08077

Phone/Fax: (856) 303-2500 / (856) 786-5974

<http://www.EMSL.com>cinnaminsonleadlab@emsl.com

EMSL Order: 202003799

CustomerID: VRTX78

CustomerPO:

ProjectID:

Attn: **Vertex Aston**
The Vertex Companies, Inc.
700 Turner Way, Suite 105
Aston, PA 19014

Phone: (610) 558-8902
Fax: (610) 558-8904
Received: 04/17/20 1:50 PM
Collected: 4/11/2020

Project: **62843****Test Report: Lead in Dust by Flame AAS (SW 846 3050B/7000B)***

<i>Client Sample Description</i>	<i>Lab ID</i>	<i>Collected</i>	<i>Analyzed</i>	<i>Area Sampled</i>	<i>Lead Concentration</i>
1	202003799-0001	4/11/2020	4/17/2020	1 ft ²	<10 µg/ft ²
Site: rm 210 w1					
2	202003799-0002	4/11/2020	4/17/2020	1 ft ²	18 µg/ft ²
Site: rm 210B w2					
3	202003799-0003	4/11/2020	4/17/2020	1 ft ²	<10 µg/ft ²
Site: rm 209 w2					
4	202003799-0004	4/11/2020	4/17/2020	1 ft ²	18 µg/ft ²
Site: rm209A w3					
5	202003799-0005	4/11/2020	4/17/2020	1 ft ²	<10 µg/ft ²
Site: rm 208 w3					
6	202003799-0006	4/11/2020	4/17/2020	1 ft ²	15 µg/ft ²
Site: rm 208A w4					
7	202003799-0007	4/11/2020	4/17/2020	1 ft ²	61 µg/ft ²
Site: rm 207B w1					
8	202003799-0008	4/11/2020	4/17/2020	1 ft ²	<10 µg/ft ²
Site: rm207 w4					
9	202003799-0009	4/11/2020	4/17/2020	1 ft ²	13 µg/ft ²
Site: rm207A w1					
10	202003799-0010	4/11/2020	4/17/2020	1 ft ²	<10 µg/ft ²
Site: rm 206 w2					
11	202003799-0011	4/11/2020	4/17/2020	1 ft ²	<10 µg/ft ²
Site: rm 206A w3					
12	202003799-0012	4/11/2020	4/17/2020	1 ft ²	17 µg/ft ²
Site: rm 205 w3					
13	202003799-0013	4/11/2020	4/17/2020	1 ft ²	<10 µg/ft ²
Site: rm 203AA w4					
14	202003799-0014	4/11/2020	4/17/2020	1 ft ²	<10 µg/ft ²
Site: rm 204 w1					
15	202003799-0015	4/11/2020	4/17/2020	1 ft ²	<10 µg/ft ²
Site: rm 204 A w2					

Phillip Worby, Lead Laboratory Manager
or other approved signatory

*Analysis following Lead in Dust by EMSL SOP/ Determination of Environmental Lead by FLAA. Reporting limit is 10 µg/wipe. ug/wipe =µg/ft² x area sampled in ft². Unless noted, results in this report are not blank corrected. EMSL maintain liability limited to cost of analysis. Interpretation and use of test results are the responsibility of the client. This report relates only to the samples reported above and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. The report reflects the samples as received. When the information supplied by the customer can affect the validity of the results, it will be noted on the report. The lab is not responsible for data reported in µg/ft² which is dependent on the area provided by non-lab personnel. The test results contained within this report meet the requirements of NELAP unless otherwise noted. "<" (less than) results signifies that the analyte was not detected at or above the reporting limit. Measurement of uncertainty is available upon request. The QC data associated with the sample results included in this report meet the recovery and precision requirements

Samples analyzed by EMSL Analytical, Inc. Cinnaminson, NJ NELAP Certifications: NJ 03036, NY 10872, PA 68-00367, AIHA-LAP, LLC ELLAP 100194, A2LA 2845.01

Initial report from 04/20/2020 09:35:50

**EMSL Analytical, Inc.**

200 Route 130 North, Cinnaminson, NJ 08077

Phone/Fax: (856) 303-2500 / (856) 786-5974

<http://www.EMSL.com>cinnaminsonleadlab@emsl.com

EMSL Order: 202003799

CustomerID: VRTX78

CustomerPO:

ProjectID:

Attn: **Vertex Aston**
The Vertex Companies, Inc.
700 Turner Way, Suite 105
Aston, PA 19014

Phone: (610) 558-8902
Fax: (610) 558-8904
Received: 04/17/20 1:50 PM
Collected: 4/11/2020

Project: **62843****Test Report: Lead in Dust by Flame AAS (SW 846 3050B/7000B)***

<i>Client Sample Description</i>	<i>Lab ID</i>	<i>Collected</i>	<i>Analyzed</i>	<i>Area Sampled</i>	<i>Lead Concentration</i>
16	202003799-0016	4/11/2020	4/17/2020	1 ft ²	25 µg/ft ²
Site: rm 203 B w2					
17	202003799-0017	4/11/2020	4/17/2020	1 ft ²	10 µg/ft ²
Site: rm 203 w3					
18	202003799-0018	4/11/2020	4/17/2020	1 ft ²	<10 µg/ft ²
Site: rm 203A w4					

Phillip Worby, Lead Laboratory Manager
or other approved signatory

*Analysis following Lead in Dust by EMSL SOP/ Determination of Environmental Lead by FLAA. Reporting limit is 10 µg/wipe. ug/wipe = µg/ft² x area sampled in ft². Unless noted, results in this report are not blank corrected. EMSL maintain liability limited to cost of analysis. Interpretation and use of test results are the responsibility of the client. This report relates only to the samples reported above and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. The report reflects the samples as received. When the information supplied by the customer can affect the validity of the results, it will be noted on the report. The lab is not responsible for data reported in µg/ft² which is dependent on the area provided by non-lab personnel. The test results contained within this report meet the requirements of NELAP unless otherwise noted. "<" (less than) results signifies that the analyte was not detected at or above the reporting limit. Measurement of uncertainty is available upon request. The QC data associated with the sample results included in this report meet the recovery and precision requirements

Samples analyzed by EMSL Analytical, Inc. Cinnaminson, NJ NELAP Certifications: NJ 03036, NY 10872, PA 68-00367, AIHA-LAP, LLC ELLAP 100194, A2LA 2845.01

Initial report from 04/20/2020 09:35:50

**EMSL Analytical, Inc.**

200 Route 130 North, Cinnaminson, NJ 08077

Phone/Fax: (856) 303-2500 / (856) 786-5974

<http://www.EMSL.com>cinnaminsonleadlab@emsl.com

EMSL Order: 202003838

CustomerID: VRTX78

CustomerPO:

ProjectID:

Attn: **Vertex Aston**
The Vertex Companies, Inc.
700 Turner Way, Suite 105
Aston, PA 19014

Phone: (610) 558-8902
Fax: (610) 558-8904
Received: 04/21/20 11:15 AM
Collected: 4/20/2020

Project: **62843****Test Report: Lead in Dust by Flame AAS (SW 846 3050B/7000B)***

Client Sample Description	Lab ID	Collected	Analyzed	Area Sampled	Lead Concentration
1	202003838-0001	4/20/2020	4/21/2020	1 ft ²	<10 µg/ft ²
Site: rm 301A - coatroom - w1					
2	202003838-0002	4/20/2020	4/21/2020	1 ft ²	<10 µg/ft ²
Site: rm 302A - coatroom - W2					
3	202003838-0003	4/20/2020	4/21/2020	1 ft ²	<10 µg/ft ²
Site: rm 311 - closet - W3					
4	202003838-0004	4/20/2020	4/21/2020	1 ft ²	<10 µg/ft ²
Site: rm 303B - girls restroom - W4					
5	202003838-0005	4/20/2020	4/21/2020	1 ft ²	22 µg/ft ²
Site: rm 304 A - coatroom - W 1					
6	202003838-0006	4/20/2020	4/21/2020	1 ft ²	<10 µg/ft ²
Site: rm 306 A - coatroom - W2					
7	202003838-0007	4/20/2020	4/21/2020	1 ft ²	<10 µg/ft ²
Site: rm 307 - classroom - W3					
8	202003838-0008	4/20/2020	4/21/2020	1 ft ²	<10 µg/ft ²
Site: rm 307 A - coat room - W4					
9	202003838-0009	4/20/2020	4/21/2020	1 ft ²	<10 µg/ft ²
Site: rm 310 - closet 2 - W 4					
10	202003838-0010	4/20/2020	4/21/2020	1 ft ²	20 µg/ft ²
Site: office 307 A - W1					
11	202003838-0011	4/20/2020	4/21/2020	1 ft ²	<10 µg/ft ²
Site: rm 307B - boys restroom - W4					
12	202003838-0012	4/20/2020	4/21/2020	1 ft ²	<10 µg/ft ²
Site: rm 308A - closet - W2					
13	202003838-0013	4/20/2020	4/21/2020	1 ft ²	10 µg/ft ²
Site: rm 209A - coatroom - W4					
14	202003838-0014	4/20/2020	4/21/2020	1 ft ²	<10 µg/ft ²
Site: rm 310B - coatroom - W1					
15	202003838-0015	4/20/2020	4/21/2020	1 ft ²	26 µg/ft ²
Site: rm 310A - classroom - W4					

Phillip Worby, Lead Laboratory Manager
or other approved signatory

*Analysis following Lead in Dust by EMSL SOP/ Determination of Environmental Lead by FLAA. Reporting limit is 10 µg/wipe. ug/wipe =µg/ft² x area sampled in ft². Unless noted, results in this report are not blank corrected. EMSL maintain liability limited to cost of analysis. Interpretation and use of test results are the responsibility of the client. This report relates only to the samples reported above and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. The report reflects the samples as received. When the information supplied by the customer can affect the validity of the results, it will be noted on the report. The lab is not responsible for data reported in µg/ft² which is dependent on the area provided by non-lab personnel. The test results contained within this report meet the requirements of NELAC unless otherwise noted. "<" (less than) results signifies that the analyte was not detected at or above the reporting limit. Measurement of uncertainty is available upon request. The QC data associated with the sample results included in this report meet the recovery and precision requirements

Samples analyzed by EMSL Analytical, Inc. Cinnaminson, NJ NELAP Certifications: NJ 03036, NY 10872, PA 68-00367, AIHA-LAP, LLC ELLAP 100194, A2LA 2845.01

Initial report from 04/22/2020 09:03:17

**EMSL Analytical, Inc.**

200 Route 130 North, Cinnaminson, NJ 08077

Phone/Fax: (856) 303-2500 / (856) 786-5974

<http://www.EMSL.com>cinnaminsonleadlab@emsl.com

EMSL Order: 202003838

CustomerID: VRTX78

CustomerPO:

ProjectID:

Attn: **Vertex Aston**
The Vertex Companies, Inc.
700 Turner Way, Suite 105
Aston, PA 19014

Phone: (610) 558-8902
Fax: (610) 558-8904
Received: 04/21/20 11:15 AM
Collected: 4/20/2020

Project: 62843

Test Report: Lead in Dust by Flame AAS (SW 846 3050B/7000B)*

<i>Client Sample Description</i>	<i>Lab ID</i>	<i>Collected</i>	<i>Analyzed</i>	<i>Area Sampled</i>	<i>Lead Concentration</i>
16	202003838-0016	4/20/2020	4/21/2020	1 ft ²	<10 µg/ft ²
Site: rm 300 - Nurse room - W1					

Phillip Worby, Lead Laboratory Manager
or other approved signatory

*Analysis following Lead in Dust by EMSL SOP/ Determination of Environmental Lead by FLAA. Reporting limit is 10 µg/wipe. ug/wipe =µg/ft² x area sampled in ft². Unless noted, results in this report are not blank corrected. EMSL maintain liability limited to cost of analysis. Interpretation and use of test results are the responsibility of the client. This report relates only to the samples reported above and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. The report reflects the samples as received. When the information supplied by the customer can affect the validity of the results, it will be noted on the report. The lab is not responsible for data reported in µg/ft² which is dependent on the area provided by non-lab personnel. The test results contained within this report meet the requirements of NELAC unless otherwise noted. "<" (less than) results signifies that the analyte was not detected at or above the reporting limit. Measurement of uncertainty is available upon request. The QC data associated with the sample results included in this report meet the recovery and precision requirements

Samples analyzed by EMSL Analytical, Inc. Cinnaminson, NJ NELAP Certifications: NJ 03036, NY 10872, PA 68-00367, AIHA-LAP, LLC ELLAP 100194, A2LA 2845.01

Initial report from 04/22/2020 09:03:17

**EMSL Analytical, Inc.**

200 Route 130 North, Cinnaminson, NJ 08077

Phone/Fax: (856) 303-2500 / (856) 786-5974

<http://www.EMSL.com>cinnaminsonleadlab@emsl.com

EMSL Order: 202003781

CustomerID: VRTX78

CustomerPO:

ProjectID:

Attn: **Vertex Aston**
The Vertex Companies, Inc.
700 Turner Way, Suite 105
Aston, PA 19014

Phone: (610) 558-8902
 Fax: (610) 558-8904
 Received: 04/16/20 12:30 PM
 Collected: 4/16/2020

Project: **62843****Test Report: Lead in Dust by Flame AAS (SW 846 3050B/7000B)***

<i>Client Sample Description</i>	<i>Lab ID</i>	<i>Collected</i>	<i>Analyzed</i>	<i>Area Sampled</i>	<i>Lead Concentration</i>
1	202003781-0001	4/16/2020	4/17/2020	1 ft ²	24 µg/ft ²
Site: rm 300 - wall 2					
2	202003781-0002	4/16/2020	4/17/2020	1 ft ²	<10 µg/ft ²
Site: rm 301 - wall 1					
3	202003781-0003	4/16/2020	4/17/2020	1 ft ²	16 µg/ft ²
Site: rm 301A - wall 2					
4	202003781-0004	4/16/2020	4/17/2020	1 ft ²	<10 µg/ft ²
Site: rm 302 - wall 3					
5	202003781-0005	4/16/2020	4/17/2020	1 ft ²	12 µg/ft ²
Site: rm 302A - wall 1					
6	202003781-0006	4/16/2020	4/17/2020	1 ft ²	<10 µg/ft ²
Site: rm 303 - wall 2					
7	202003781-0007	4/16/2020	4/17/2020	1 ft ²	<10 µg/ft ²
Site: rm 303A - wall 4					
8	202003781-0008	4/16/2020	4/17/2020	1 ft ²	59 µg/ft ²
Site: rm 311A - wall 1					
9	202003781-0009	4/16/2020	4/17/2020	1 ft ²	33 µg/ft ²
Site: rm 303B - wall 4					
10	202003781-0010	4/16/2020	4/17/2020	1 ft ²	<10 µg/ft ²
Site: rm 304 - wall 1					
11	202003781-0011	4/16/2020	4/17/2020	1 ft ²	25 µg/ft ²
Site: rm 304A - wall 3					
12	202003781-0012	4/16/2020	4/17/2020	1 ft ²	<10 µg/ft ²
Site: rm 305 - wall 3					
13	202003781-0013	4/16/2020	4/17/2020	1 ft ²	<10 µg/ft ²
Site: rm 305A - wall 3					
14	202003781-0014	4/16/2020	4/17/2020	1 ft ²	<10 µg/ft ²
Site: rm 306 - wall 3					
15	202003781-0015	4/16/2020	4/17/2020	1 ft ²	52 µg/ft ²
Site: rm 306A - wall 1					

Phillip Worby, Lead Laboratory Manager
 or other approved signatory

*Analysis following Lead in Dust by EMSL SOP/ Determination of Environmental Lead by FLAA. Reporting limit is 10 µg/wipe. ug/wipe =µg/ft² x area sampled in ft². Unless noted, results in this report are not blank corrected. EMSL maintain liability limited to cost of analysis. Interpretation and use of test results are the responsibility of the client. This report relates only to the samples reported above and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. The report reflects the samples as received. When the information supplied by the customer can affect the validity of the results, it will be noted on the report. The lab is not responsible for data reported in µg/ft² which is dependent on the area provided by non-lab personnel. The test results contained within this report meet the requirements of NELAP unless otherwise noted. "<" (less than) results signifies that the analyte was not detected at or above the reporting limit. Measurement of uncertainty is available upon request. The QC data associated with the sample results included in this report meet the recovery and precision requirements

Samples analyzed by EMSL Analytical, Inc. Cinnaminson, NJ NELAP Certifications: NJ 03036, NY 10872, PA 68-00367, AIHA-LAP, LLC ELLAP 100194, A2LA 2845.01

Initial report from 04/17/2020 13:45:44

**EMSL Analytical, Inc.**

200 Route 130 North, Cinnaminson, NJ 08077

Phone/Fax: (856) 303-2500 / (856) 786-5974

<http://www.EMSL.com>cinnaminsonleadlab@emsl.com

EMSL Order: 202003781

CustomerID: VRTX78

CustomerPO:

ProjectID:

Attn: **Vertex Aston**
The Vertex Companies, Inc.
700 Turner Way, Suite 105
Aston, PA 19014

Phone: (610) 558-8902
 Fax: (610) 558-8904
 Received: 04/16/20 12:30 PM
 Collected: 4/16/2020

Project: 62843

Test Report: Lead in Dust by Flame AAS (SW 846 3050B/7000B)*

<i>Client Sample Description</i>	<i>Lab ID</i>	<i>Collected</i>	<i>Analyzed</i>	<i>Area Sampled</i>	<i>Lead Concentration</i>
16	202003781-0016	4/16/2020	4/17/2020	1 ft ²	26 µg/ft ²
Site: rm 307 - wall 2					
17	202003781-0017	4/16/2020	4/17/2020	1 ft ²	28 µg/ft ²
Site: rm 307A - wall 3					
18	202003781-0018	4/16/2020	4/17/2020	1 ft ²	19 µg/ft ²
Site: rm 310C - wall 2					
19	202003781-0019	4/16/2020	4/17/2020	1 ft ²	330 µg/ft ²
Site: 310C - office 307 A - wall 1					
20	202003781-0020	4/16/2020	4/17/2020	1 ft ²	170 µg/ft ²
Site: rm 307 B - wall 3					
21	202003781-0021	4/16/2020	4/17/2020	1 ft ²	<10 µg/ft ²
Site: rm 308 - wall 4					
22	202003781-0022	4/16/2020	4/17/2020	1 ft ²	120 µg/ft ²
Site: rm 308A - wall 4					
23	202003781-0023	4/16/2020	4/17/2020	1 ft ²	<10 µg/ft ²
Site: rm 309 - wall 1					
24	202003781-0024	4/16/2020	4/17/2020	1 ft ²	30 µg/ft ²
Site: rm 309A - wall 1					
25	202003781-0025	4/16/2020	4/17/2020	1 ft ²	<10 µg/ft ²
Site: rm 310 - wall 2					
26	202003781-0026	4/16/2020	4/17/2020	1 ft ²	39 µg/ft ²
Site: rm 310B - wall 4					
27	202003781-0027	4/16/2020	4/17/2020	1 ft ²	88 µg/ft ²
Site: rm 310A - wall 1					
28	202003781-0028	4/16/2020	4/17/2020	N/A	<10 µg/wipe
Site: rm 311 - wall 3					

Phillip Worby, Lead Laboratory Manager
 or other approved signatory

*Analysis following Lead in Dust by EMSL SOP/ Determination of Environmental Lead by FLAA. Reporting limit is 10 µg/wipe. ug/wipe =µg/ft² x area sampled in ft². Unless noted, results in this report are not blank corrected. EMSL maintain liability limited to cost of analysis. Interpretation and use of test results are the responsibility of the client. This report relates only to the samples reported above and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. The report reflects the samples as received. When the information supplied by the customer can affect the validity of the results, it will be noted on the report. The lab is not responsible for data reported in µg/ft² which is dependent on the area provided by non-lab personnel. The test results contained within this report meet the requirements of NELAP unless otherwise noted. "<" (less than) results signifies that the analyte was not detected at or above the reporting limit. Measurement of uncertainty is available upon request. The QC data associated with the sample results included in this report meet the recovery and precision requirements

Samples analyzed by EMSL Analytical, Inc. Cinnaminson, NJ NELAP Certifications: NJ 03036, NY 10872, PA 68-00367, AIHA-LAP, LLC ELLAP 100194, A2LA 2845.01

Initial report from 04/17/2020 13:45:44

Appendix E. Photo Log



Photograph 1 – Classroom prepped for stabilization



Photograph 2 – Restroom being prepped for stabilization

PROJECT PHOTOGRAPHS

Hopkinson ES
4001 L Street
Philadelphia, PA 19124

Vertex Project Number: 62843



Photograph 3 – Classroom undergoing stabilization (plastering)



Photograph 4 – Classroom being painted

PROJECT PHOTOGRAPHS

Hopkinson ES
4001 L Street
Philadelphia, PA 19124

Vertex Project Number: 62843



Photograph 5 – RRP wipe on wood floor



Photograph 6 – RRP wipe on tile floor

PROJECT PHOTOGRAPHS

Hopkinson ES
4001 L Street
Philadelphia, PA 19124

Vertex Project Number: 62843



Photograph 7 – Failing RRP wipe



Photograph 8 – Passing RRP wipe

PROJECT PHOTOGRAPHS

Hopkinson ES
4001 L Street
Philadelphia, PA 19124

Vertex Project Number: 62843



Photograph 9 – Classroom after stabilization and painting



Photograph 10 – Classroom after stabilization and painting

PROJECT PHOTOGRAPHS

Hopkinson ES
4001 L Street
Philadelphia, PA 19124

Vertex Project Number: 62843

Appendix F. Environmental Firm Certifications

United States Environmental Protection Agency

This is to certify that



The Vertex Companies, Inc.

has fulfilled the requirements of the Toxic Substances Control Act (TSCA) Section 402, and has received certification to conduct lead-based paint renovation, repair, and painting activities pursuant to 40 CFR Part 745.89

In the Jurisdiction of:

All EPA Administered States, Tribes, and Territories

This certification is valid from the date of issuance and expires March 20, 2024

NAT-F199670-1

Certification #

March 06, 2019

Issued On



Michelle Price

Michelle Price, Chief

Lead, Heavy Metals, and Inorganics Branch

School District of Philadelphia
Paint and Plaster Stabilization Project
Name of School

	A	B	C	D	E	F	G	H
	Name of Certified Contractor	Worker Name	US EPA RRP Training Provider (Firm/Individual)	US EPA RRP Certification Number	US EPA RRP Certification Expiration Date	Worker Trained on site (Yes/No)	Training Date	Comments
1								
2	The Vertex Companies, Inc.	Saheed Apenaola	Criterion Laboratories, Inc. / James Weltz	R-I-19014-20-750169	1/28/2025	No	1/28/2020	
3	The Vertex Companies, Inc.	Saheed Apenaola	Aerosol Monitoring & Analysis, Inc. / Mike Drabo and E. Rush Barnett	DC18-001-DST-1	12/19/2024	No	12/19/2024	Lead Dust Sampling Technician

Appendix G. Paint Contractor Certifications

United States Environmental Protection Agency

This is to certify that



Sioutis Coatings Enterprise, Inc.

has fulfilled the requirements of the Toxic Substances Control Act (TSCA) Section 402, and has received certification to conduct lead-based paint renovation, repair, and painting activities pursuant to 40 CFR Part 746.89

In the Jurisdiction of:

All EPA Administered States, Tribes, and Territories

This certification is valid from the date of issuance and expires November 09, 2023

NAT-67382-2

Certification #

October 26, 2018

Issued On



Michelle Price, Chief

Lead, Heavy Metals, and Inorganics Branch

A handwritten signature in black ink, appearing to read "Michelle Price".

School District of Philadelphia
Paint and Plaster Stabilization Project
Name of School

	A	B	C	D	E	F	G	H
1	Name of Certified Contractor	Worker Name	US EPA RRP Training Provider (Firm/Individual)	US EPA RRP Certification Number	US EPA RRP Certification Expiration Date	Worker Trained on site (Yes/No)	Training Date	Comments
2	Sioutis Coatings Enterprise, Inc.	David Picarelli	Finishing Trades Institute of the Mid-Atlantic Region/Martin McNulty	R-I-21936-12-00252	12/11/2023	No	12/11/2018	
3	Sioutis Coatings Enterprise, Inc.	Britt Horvath	Finishing Trades Institute of the Mid-Atlantic Region/Martin McNulty	R-I-21936-12-00251	12/11/2023	No	12/11/2018	
4	Sioutis Coatings Enterprise, Inc.	Mark Squilla	Finishing Trades Institute of the Mid-Atlantic Region/Martin McNulty	R-I-21936-12-00246	12/11/2023	No	12/11/2018	
5	Sioutis Coatings Enterprise, Inc.	Mihaly Horvath	Finishing Trades Institute of the Mid-Atlantic Region/Martin McNulty	R-I-21936-12-00250	12/11/2023	No	12/11/2018	
6	Sioutis Coatings Enterprise, Inc.	Lionel Henry	Finishing Trades Institute of the Mid-Atlantic Region/Martin McNulty	R-I-21936-12-00247	12/11/2023	No	12/11/2018	

School District of Philadelphia
Paint and Plaster Stabilization Project
Name of School

A		B	C	D	E	F	G	H
7	Sioutis Coatings Enterprise, Inc.	Joseph Hagan	Finishing Trades Institute of the Mid-Atlantic Region/Martin McNulty	R-I-21936-12-00245	12/11/2023	No	12/11/2018	

Appendix H. Documentation of Parent and Staff Notifications



Paint and Plaster Stabilization: Project Start

Dear School Families,

The School District of Philadelphia works daily to ensure that our students and staff have a safe, healthy environment in which to learn and work. On behalf of the School District, I am writing to share information with you about plans for renovation to remove loose and peeling paint in your child's school. The goal of the work is to enhance classroom environments and remove the risk of lead exposure to children in our school community.

The School District has begun paint and plaster stabilization work in school buildings constructed prior to 1978 that are likely to contain lead-based paint. Paint stabilization involves removing loose, peeling, flaking and crumbling paint and plaster under controlled conditions. Your child's school has been selected for this work because paint damage was documented in occupied spaces such as classrooms and classroom closets, administrative offices, cafeteria, auditorium, bathrooms, kitchen, hallways, and emergency exit stairways.

The work is being completed by individuals who are trained and certified in United States Environmental Protection Agency (EPA) lead-based paint renovation, repair and painting work practices. These work practices ensure that classrooms and other areas are free of paint chips, dust and debris. Each space will be assessed after the work is completed in each area to ensure that the spaces are ready for students and staff to safely occupy. Building staff will also look for signs of paint and plaster damage and clean paint and plaster dust and debris using a HEPA vacuum before, during, and after the project.

Details about the project including the environmental consultant's assessment report, project schedule and frequently asked questions are available in the school's main office or by visiting www.philasd.org/facilities/lead-safe. Copies will also be provided to the School Advisory Council and Home and School Association in the near future.

We understand that you likely will have additional questions, and we will work to address those promptly. The School District will host a meeting for families to share an overview of the repairs and to answer questions on **Wednesday, January 29, 2020 at 5:00 PM** in the school.

If you have questions or concerns, please do not hesitate to reach out to Eddie Escobio (Operations Project Manager) at 215 400-6235 and eescobio@philasd.org.

Thank you,

Eddie Escobio

Project Manager

School District of Philadelphia | Division of Operations

Email: eescobio@philasd.org

T: 215-400-6235

Estabilización de pintura y yeso: iniciación de proyecto

Estimadas familias de la escuela,

El Distrito Escolar de Filadelfia trabaja a diario para asegurar que nuestros alumnos y personal tengan un ambiente seguro y saludable en que puedan aprender y trabajar. De parte del distrito escolar, escribo para compartir con Uds. información sobre los planes de renovación para eliminar la pintura suelta y descascarada de la escuela de su hijo(a). La meta de este trabajo es mejorar nuestro ambiente de estudio y eliminar el peligro de la exposición al plomo de los niños de nuestra comunidad escolar.

El distrito escolar ha comenzado el trabajo de estabilización de pintura y yeso en los edificios escolares construidos antes de 1978 que es probable que contengan pintura con plomo. La estabilización de la pintura involucra eliminar el yeso y la pintura sueltas, descascaradas, desconchadas y molidas bajo condiciones controladas. La escuela ha sido seleccionada para este trabajo porque el deterioro de la pintura ha sido documentado en espacios habilitados tales como salones de clase, armarios de salones de clase, oficinas administrativas, la cafetería, el auditorio, los baños, la cocina, los pasillos y las escaleras de salida.

Llevarán a cabo el trabajo personas que están capacitadas y entrenadas en las prácticas laborales de pintura, reparación y renovación de pintura con plomo en la Agencia de Protección Ambiental de los Estados Unidos (*EPA* por sus siglas en inglés). Estas prácticas de trabajo aseguran que las salas de clase y otras áreas estén libres de esquilas, polvo y restos de pintura. Una vez terminado el trabajo en cada área se evaluará cada espacio para asegurarse de que esté listo para ser ocupado de manera segura por los estudiantes y el personal. El personal de construcción también revisará deterioros del yeso y la pintura y limpiará el polvo y restos del yeso y la pintura utilizando una aspiradora *HEPA* antes, durante y después del proyecto.

Detalles sobre el proyecto, incluyendo la evaluación del asesor medioambiental, el calendario del proyecto y preguntas frecuentes, están disponibles en la oficina central de la escuela o visitando el sitio web www.philasd.org/facilities/lead-safe. También se darán copias al Consejo Asesor Escolar y a la Asociación Hogar y Escuela a la brevedad.

Entendemos que Ud. probablemente tendrá preguntas adicionales y estaremos disponibles para contestarlas a la brevedad. El Distrito escolar ofrecerá una reunión para las familias para compartir un resumen de los arreglos y para contestar preguntas el miércoles, **29 de enero de 2020 a las 5:00 p.m.** en la escuela.

Si tiene preguntas o inquietudes, no dude en comunicarse con Eddie Escobio (Encargado de proyectos de operaciones) al 215 400-6235 y eescobio@philasd.org.

Gracias,

Eddie Escobio

Encargado de proyectos

Distrito Escolar de Filadelfia | Departamento de Operaciones

Email: eescobio@philasd.org

T: 215-400-6235