



EMSL Analytical, Inc.

307 West 38th Street New York, NY 10018

Tel/Fax: (212) 290-0051 / (212) 290-0058

<http://www.EMSL.com> / manhattanlab@emsl.com

EMSL Order: 032003805

Customer ID: VRTX78

Customer PO:

Project ID:

Attention: Don Heim
The Vertex Companies, Inc.
700 Turner Way, Suite 105
Aston, PA 19014

Phone: (610) 558-8902

Fax: (610) 558-8904

Received Date: 02/22/2020 13:02 PM

Analysis Date: 02/22/2020

Collected Date: 02/22/2020

Project: CLARA BARTON/ 62622

Test Report: Asbestos Fiber Analysis by Transmission Electron Microscopy (TEM) Performed by EPA 40 CFR Part 763 Appendix A to Subpart E

Sample	Location	Volume (Liters)	Area Analyzed (mm ²)	Non Asb	Asbestos Type(s)	#Structures		Analytical Sensitivity (S/cc)	Asbestos Concentration	
						≥0.5μ < 5μ	≥5μ		(S/mm ²)	(S/cc)
B-27 032003805-0001	ROOM 111A	1786.00	0.0508	2	None Detected	0	0	0.0042	<20.00	<0.0042
B-28 032003805-0002	ROOM 110	1777.00	0.0508	0	None Detected	0	0	0.0043	<20.00	<0.0043
B-29 032003805-0003	ROOM 110	1777.00	0.0508	1	None Detected	0	0	0.0043	<20.00	<0.0043
B-30 032003805-0004	ROOM 109	1767.00	0.0508	1	None Detected	0	0	0.0043	<20.00	<0.0043
B-31 032003805-0005	IMC	1739.00	0.0508	0	None Detected	0	0	0.0044	<20.00	<0.0044
B-32 032003805-0006	IMC	1739.00	0.0508	0	None Detected	0	0	0.0044	<20.00	<0.0044
B-33 032003805-0007	AUDITORIUM	1729.00	0.0508	0	None Detected	0	0	0.0044	<20.00	<0.0044
B-34 032003805-0008	AUDITORIUM	1720.00	0.0508	0	None Detected	0	0	0.0044	<20.00	<0.0044
B-35 032003805-0009	AUDITORIUM	1729.00	0.0508	0	None Detected	0	0	0.0044	<20.00	<0.0044
B-36 032003805-0010	ROOM 102	1720.00	0.0508	0	None Detected	0	0	0.0044	<20.00	<0.0044
B-37 032003805-0011	ROOM 102	1720.00	0.0508	0	None Detected	0	0	0.0044	<20.00	<0.0044
B-38 032003805-0012	ROOM 100	1729.00	0.0508	0	None Detected	0	0	0.0044	<20.00	<0.0044

Analyst(s)

Isaac Mendez (5)

Steven Dutter (7)

James Hall, Laboratory Manager
or other approved signatory

EMSL maintains liability limited to cost of analysis. This report relates only to the samples reported above and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. This report must not be used to claim product certification, approval, or endorsement by NVLAP, NIST, or any agency of the federal government. Results reported in both structures/cm3 and structures/mm2 are dependent on the volume of air sampled and measured by non-laboratory personnel are not the responsibility of EMSL and are not covered by the laboratory's NVLAP accreditation. Samples received in good condition unless otherwise noted. Estimated accuracy, precision and uncertainty data available upon request.

Samples analyzed by EMSL Analytical, Inc. New York, NY NVLAP Lab Code 101048-9, AIHA-LAP, LLC--IHLAP Accredited #102581, NYS ELAP 11506, NJ NY022, CT PH-0170, MA AA000170

Initial report from: 02/22/2020 20:24 PM