

SCHOOL DISTRICT OF PHILADELPHIA



Asbestos Hazard Emergency Response Act “AHERA”

THREE-YEAR RE-INSPECTION 2015-2016 and ASBESTOS MANAGEMENT PLAN for the

Philadelphia High School for Girls

**ULCS# 6050
Building # B605001-1
1400 W Olney Avenue
Philadelphia, Pennsylvania
19141**

January 2016

Conducted By:

Accredited Environmental Technologies, Incorporated
Batta Environmental Associates, Incorporated
Criterion Laboratories, Incorporated
Environmental Testing Consultants, LLC
G & C Environmental Services, Incorporated
KEM Partners, Incorporated
Synertech, Inc.
TTI Environmental, Inc.
USA Environmental Management, Inc.
The Vertex Companies, Inc.

Management Plan Prepared By:

Criterion Labs, Inc and Synertech Inc.

This report must remain in the Main Office as mandated by the US EPA AHERA Regulations.

AHERA THREE-YEAR REINSPECTION VOLUME IX

Table of Contents

Transmittal Letter

Executive Summary

- I. Summary list of Confirmed Asbestos Containing Building Materials
- II. Summary list of Assumed Asbestos Contain Building Materials
- III. Summary list of Non-Asbestos Containing Building Materials
- IV. Summary list of Non Suspect Asbestos Containing Building Materials
- V. Summary List of Auditorium DATA for this location
- VI. Summary list of Attic and/or Crawlspace DATA for this location
- VII. Summary list of Pipe Chase/Pipe Shaft DATA for this location

Section I Report of Re-Inspection

- A. Introduction
- B. Three-Year Re-inspection IX Overview
- C. Post- Management Plan Activities and Changes
 - C.1 - Sampling and Analysis
 - C.2 - New Floor Tile Sampling
 - C.3 - Abatement Activity
 - C.4 - Periodic (Six-Month) Surveillance (Damaged Materials)

Section II Re-Inspection Data

- A. Introduction
- B. Re-Inspection Key Definitions
- C. Room by Room Location Log Report

Section III Certificates

- A. Management Planner/Building Inspector Certificates

Section IV	Cross Reference Table	Page 1-8
	Asbestos Management Program	Page 9-19

SCHOOL DISTRICT OF PHILADELPHIA
EDUCATIONAL CENTER
440 NORTH BROAD STREET
PHILADELPHIA, PENNSYLVANIA 19130

OFFICE OF ENVIRONMENTAL MANAGEMENT AND SERVICES

PHONE (215)-400-4750

January 2016


TO: All Principals
All Building Administrators

FROM: Fran Burns
Chief Operating Officer


Francine Locke, M.S., Director
Office of Environmental Management and Services

SUBJECT: AHERA Three (3) Year Re-inspection IX report

In order to comply with the provisions of the Asbestos Hazard Emergency Response Act (AHERA) the attached report is submitted to you. The law requires that this report be kept in the Main/Principal's office. It cannot be removed from these locations. *If the school (program) is relocated to a different building, these environmental documents are to be safely retained for the next school/building occupants.* All asbestos reports must be available to the public and Federal EPA upon request.



Fran Burns
Chief Operation Officer



Francine Locke, M.S., Director
Office of Environmental Management
and Services

Executive Summary

This Asbestos Hazard Emergency Response Act (AHERA) Three-Year Re-inspection “Volume # IX” Management Plan at this location, has been completed and the report of re-inspection submitted to the School District of Philadelphia. The re-inspections in all School District of Philadelphia buildings of 2015-2016 were conducted and completed between October 5th, 2015 through March 30th, 2016 as a joint project by Accredited Environmental Technologies, Inc., Batta Environmental Associates, Inc., Criterion Laboratories, Inc., Environmental Testing Consultants, LLC, G & C Environmental Services, Inc., KEM Partners, Inc., Synertech, Inc., TTI Environmental, Inc., USA Environmental Management, Inc. and The Vertex Companies, Inc.

In general, the School District of Philadelphia Office of Environmental Management and Services conducts Environmental Impact Evaluations and provides Asbestos Inspection Reports prior to any renovation, demolition and/or maintenance activities. The AHERA report must be reviewed prior to any renovation, demolition and/or maintenance activities in order to avoid the unknowing disturbance to Asbestos Containing Building Materials identified within this location. In addition, prior to work activities above all drop ceilings this report should be reviewed to avoid potential disturbances to Asbestos Containing Materials. Refer to Section IV of the Cross Reference Table, for additional Asbestos Management Program information. Contact the Office of Environmental Management and Services to have an Environmental Impact Evaluation conducted prior to any renovation, demolition and/or maintenance activities within this facility.

The information contained in this report was obtained from the original Asbestos Management Plan for the school, from update reports on changes and activities since the completion of the 1st Management Plan for each location and from all prior inspections performed and documented in Volume # I through Volume VIII (dated respectively 1992, 1995, 1998, 2001, 2004, 2007, 2010 or 2013) (if applicable) - and by this Three-Year Re-inspection of this school. The re-inspection report/Management Plan of 2015-2016 were reviewed and prepared collectively by Management Planner Megan Vala, Mary Anne Lerro of Criterion Laboratories, Inc. and/or Monique Causley, of Synertech Inc.

The 2015-2016 inspection process included the addition of a comprehensive Room by Room Inventory of all Thermal (T), Surfacing (S) and Miscellaneous (M) Materials specific to each room of this facility. Inspections of each room's thermal, ceilings, walls, floors and miscellaneous items regardless of Asbestos Content are categorized on the Room by Room Location Log Report for this location. Rooms or areas of the facility that were not accessible at the time of the inspection are marked with an "X". The Room by Room Location Log Report is found in Section II C of this Management Plan.

All Presumed or Suspect Asbestos Containing Building Materials (ACBMs), listed in the following summary charts are categorized as Confirmed, Assumed, Non-Asbestos, and/or Non-Suspect (ACBMs) were identified in the original Management Plan, or in the Volume I through Volume VIII AHERA Three-Year Re-inspection reports, and were re-inspected as part of this project.

As mandated by the U S EPA AHERA regulations, periodic Six-Month inspections and Three-Year Re-inspections of this location will be performed and the Inspection Data in this report will be updated accordingly.

Please feel free to contact the School District of Philadelphia's Office of Environmental Management and Services (OEMS) regarding any comments, questions, or concerns regarding this report or any Environmental related topic. OEMS staff can be reached at (215) 400 4750, via fax at (215) 400 4751 or via e-mail at flocke@philasd.org and/or gfunod@philasd.org.

Additional information can be found on our website. Here is the link to the OEMS website.
<http://webgui.phila.k12.pa.us/offices/e/environmental>

I. Summary list of Confirmed Asbestos Containing Building Materials within this facility

These charts are to be used for a quick reference* in order to avoid the unknowing disturbance of Asbestos Containing Materials during any and all Operations, Maintenance, Renovation, and/or Demolition activities at this location. *These materials have been sampled and Laboratory Analysis has CONFIRMED the presence of Asbestos. Contact OEMS prior to the disturbance of any of the following materials.*

Confirmed Asbestos Containing Building Materials for this location

Boiler Breeching	Duct Insulation	Exterior Boiler Insulation
Floor Tile VAT 9" x 9"	Pipe Fitting Insulation	Pipe Insulation 2-6 inch
Tank Insulation		

* *Always refer to the Room by Room Logs for each specific material classification as the material classification findings may be different in various rooms throughout this facility.*

** *Some Materials may have multiple classifications (Confirmed, Assumed, NAD and Non Suspect) within this facility.*

II. Summary list of Assumed Asbestos Containing Building Materials within this facility

These charts are to be used for a quick reference* in order to avoid the unknowing disturbance of Asbestos Containing Materials during any and all Operations, Maintenance, Renovation, and/or Demolition activities at this location. These materials have not been sampled and should not be disturbed until verification of Asbestos Content. Contact OEMS for assessment and sampling prior to the disturbance of these materials.

Assumed Asbestos Containing Building Materials for this location

Ceiling Tile 1' x 4'	Duct Insulation	Floor Tile VAT 12" x 12"
Linoleum	Pipe Insulation 2-6 inch	Plaster Ceiling
Radiator Insulation	Spline Ceiling Tile Glue Dots	Textured Ceiling Paint
Transite	Vibration Damper Cloth	

** Always refer to the Room by Room Logs for each specific material classification as the material classification findings may be different in various rooms throughout this facility.*

*** Some Materials may have multiple classifications (Confirmed, Assumed, NAD and Non Suspect) within this facility.*

III. Summary list of Non-Asbestos Containing Building Materials within this facility

These charts are to be used for a quick reference* in order to avoid the unknowing disturbance of Asbestos Containing Materials during any and all Operations, Maintenance, Renovation, and/or Demolition activities at this location. *These materials have been sampled and Laboratory Analysis has indicated NO Asbestos present or NO ASBESTOS DETECTED (NAD).*

Non- Asbestos Containing Building Materials for this location

Ceiling Tile 1' x 1'	Plaster Walls
----------------------	---------------

* *Always refer to the Room by Room Logs for each specific material classification as the material classification findings may be different in various rooms throughout this facility.*

** *Some Materials may have multiple classifications (Confirmed, Assumed, NAD and Non Suspect) within this facility.*

IV. Summary list of Non-Suspect Asbestos Containing Building Materials within this facility

These charts are to be used for a quick reference* in order to avoid the unknowing disturbance of Asbestos Containing Materials during any and all Operations, Maintenance, Renovation, and/or Demolition activities at this location. These materials are not typically known to contain Asbestos.

Non-Suspect Asbestos Containing Building Materials for this location

Carpet	Ceiling Tile 2' x 4'	Cement Floor
Ceramic Tile Floors	Ceramic Tile Walls	Concrete Block Wall
Concrete Ceiling	Fiberglass Pipe Insulation	Partition Room Dividers
Pegboard Walls	Stone Floor	Stone Stalls
Stone Walls	Terra Cotta Tile Walls	Wood Floor

** Always refer to the Room by Room Logs for each specific material classification as the material classification findings may be different in various rooms throughout this facility.*

*** Some Materials may have multiple classifications (Confirmed, Assumed, NAD and Non Suspect) within this facility.*

V. Summary list of Auditorium DATA for this location

These charts are to be used for a quick reference of the Auditorium DATA within this facility. Sampling of the Auditorium Ceilings throughout the District is more difficult because of the various ceiling heights. As sampling occurs this information is updated on a case by case basis for each specific location and facility.

This is a list of known sampling information for this locations Auditorium

Auditorium		
Auditorium	Radiator Insulation	Assumed
Auditorium	Concrete Ceiling	Non Suspect ACM
Auditorium	Ceiling Tile 1' x 1'	NAD
Auditorium	Floor Tile VAT 9" x 9"	Confirmed
Auditorium	Plaster Walls	NAD

** Always refer to the Room by Room Logs for each specific material classification as the material classification findings may be different in various rooms throughout this facility.*

*** Some Materials may have multiple classifications (Confirmed, Assumed, NAD and Non Suspect) within this facility.*

VI. Summary list of Attic and/or Crawlspace DATA for this location

These charts are to be used for a quick reference regarding the Attics and/or Crawlspaces inspection DATA within this facility. Contact OEMS prior to entering any attic or crawlspace within this facility and refer to the below chart and legend for Category Rank determination. The Data relative to these spaces is updated as conditions change regarding Abatement or Renovation activity on a case by case basis for each specific location and facility. In general, Crawlspaces are below the basement or 1st floor and Attics are above the floor space.

Category Rank Legend

"A" - No Asbestos Containing Materials - Sample Results indicate NO ACM on pipes, fittings, elbows, or equipment located within this functional space, and NO VISIBLE DEBRIS or DAMAGE observed at time of this inspection.
"B" - Asbestos Containing Materials Exist - Sample Results indicate ACM on pipes, fittings, elbows, or equipment located within this functional space, HOWEVER, NO VISIBLE DEBRIS or DAMAGE observed at time of this inspection.
"C" - Asbestos Containing Materials Exist - Sample Results indicate ACM on pipes, fittings, elbows, or equipment located within this functional space, and LOCALIZED VISIBLE DEBRIS or DAMAGE observed at time of this inspection.
"D" - Asbestos Containing Materials Exist - Sample Results indicate ACM on pipes, fittings, elbows, or equipment located within this functional space and DISTRIBUTED VISIBLE DEBRIS or SIGNIFICANT DAMAGE observed at time of this inspection.
"E" - No Bulk Sample Results Available SUSPECT ACM OBSERVED. Contact OEMS immediately for additional instructions.

Attic/Crawlspace	Access Area	Floor Surface	Category Rank	Comments
Ground Floor Crawlspace	Fan Room #1 by Stairwell #1	X	C	Entrance door is signed not sealed
Sub Basement Crawlspace	Electrical Room in Boiler Room	Dirt	"C to B"	95 Hard Fitting/Fiberglass PI
Sub Basement Crawlspace	Elevator Lobby	X	C	Local Debris/ Not signed or sealed 1 damaged Fittings
Attic	X	X	None	No Attic

VII. Summary list of Pipe Chase/Pipe Shaft DATA for this location

These charts are to be used for a quick reference regarding the information known about the Pipe Chases and/or Pipe Shafts inspection DATA within this facility. Contact OEMS prior to performing renovation activities any Pipe Chase and/or Pipe Shaft within this facility and refer to the below chart and legend for Asbestos Content of various materials identified within each space. The Data relative to these spaces is updated as conditions change regarding Inspection, Abatement and/or Renovation activity on a case by case basis for each specific location and facility. In general, Pipe Chases are horizontal spaces and Pipe Shafts are vertical spaces.

Pipe Chases and Pipe Shafts need to be assessed.

Section I Report of Re-inspection

A. Introduction

B. Three-Year Re-inspection IX Overview

C. Post-Management Plan Activities and Changes

Section I - A

Report of Re-inspection

Introduction

The Three-Year Re-inspection IX was performed to fulfill the requirements of 40 CFR Part 763 - the Asbestos Hazard Emergency Response Act (AHERA). As required by AHERA, each Local Education Agency (LEA) must re-inspect all known confirmed or assumed Asbestos Containing Building Material (ACBM) located in the LEA's facilities. This re-inspection is intended to update the original Asbestos Management Plan for the LEA's facilities.

Multiple Building Inspectors of several firms performed the 2015/2016 re-inspection. The re-inspection report/Management Plan of 2015-2016 were reviewed and prepared collectively by Management Planner Megan Vala, Mary Anne Lerro of Criterion Laboratories, Inc. and Monique Causley, of Synertech Inc.

All of the certificates can be found in Section III.

During the re-inspection of each School District of Philadelphia facility, all of the Management Plans for that facility were reviewed. Information from the conclusions section of that report is included in this report. Additionally, information on activities such as abatements, cleanings, sampling and inspections, which have taken place since the completion of the original Management Plan, were reviewed during the re-inspection. Information on those activities is included in this report.

As mandated by the U S EPA AHERA regulations, all future periodic Six-Month inspections and Three-Year Re-inspections of this location will be performed and the Inspection Data in this report will be updated accordingly.

Section I - B

Three-Year Re-inspection IX Overview

Each homogeneous area of Asbestos Containing Building Material (ACBM) listed in the original Management Plan or in the 1992, 1995, 1998, 2001, etc., Three-Year Re-inspection reports were inspected for the AHERA Three-Year Re-inspection Volume IX, and the information for that material verified. Any changes to a homogeneous area listed in the updates to the Management Plans were verified. Any area of suspected ACBM found in the course of the re-inspection, and not listed in the Management Plan or updates, were either assumed to contain asbestos or sampled and analyzed to determine their asbestos content. Any such new areas either assumed to contain asbestos or determined through analysis to contain asbestos were included in the report of the Three-Year Re-inspection. The results of the AHERA Three-Year Re-inspection IX are tabulated in the Room by Room log reports located in *Section II-C* of this report.

As previously noted, all future periodic Six-Month inspections and Three-Year Re-inspections of this location will be performed and the Inspection Data in this report will be updated accordingly

Section I – C.1

Post Management Plan Activities/Changes

Information on activities affecting Asbestos Containing Building Materials (ACBMs) at this location is contained in updates to the Management Plan. These updates are kept on file by the School District of Philadelphia and were reviewed for this project. Updates to the Management Plan include the following: *Sampling and Analysis, New Tile Installation, Abatement Activity and Periodic Six-Month Surveillance Data.*

Sampling and Analysis

Date	Floor	Room Type	Location	Material	Color	Results
8/10/2016	Basement	Storage Area	Gym “A”	Duct Insulation	N/A	Confirmed

Section I – C.2

Information on the installation of new floor tiles/renovation activities affecting Asbestos Containing Building Materials (ACBMs) at this location is contained in updates to the Management Plan. These updates are kept on file by the School District of Philadelphia and were reviewed for this project. Updates to the Management Plan include the following:

New Floor Tile Sampling

In the event that new tile is installed, the material must be tested prior to installation.

Section I – C.3

Information on the Asbestos Abatement and renovation activities affecting Asbestos Containing Building Materials (ACBMs) at this location is contained in updates to the Management Plan. These updates are kept on file by the School District of Philadelphia and were reviewed for this project. Updates to the Management Plan include the following:

Abatement Activity

In the event that Abatement occurs, data will be listed here.

Section I – C.4

Information on the AHERA inspection that noted damage to various Building Materials at this location is contained in updates to the Management Plan. These updates are kept on file by the School District of Philadelphia and were reviewed for this project. Work orders are created for Corrective Action responses and tracked for completion. Updates to the Management Plan include the following:

Periodic (Six-Month) Surveillance (Damaged Materials)

<i>Date</i>	<i>Element</i>	<i>Floor</i>	<i>On Site Room Name</i>	<i>Material</i>	<i>Amount of Material</i>	<i>Amount of Damage</i>
8/04/2016	1	SB	Pump Room	Pipe Fitting Insulation	26 EA	4 EA
8/04/2016	1	SB	Main Mechanical Room Upper Level at new boilers	Pipe Fitting Insulation	70 EA	1EA
8/04/2016	1	SB	Main Mechanical Room Lower Level at old boilers	Exterior Boiler Insulation	600 SF	600 SF
8/04/2016	1	SB	Main Mechanical Room Lower Level at old boilers	Boiler Breeching	2000 SF	50 SF
8/04/2016	1	B	Gymnasium A Storage on the north wall	Duct Insulation	30 SF	4 SF
8/04/2016	1	B	Loading Dock	Pipe Fitting Insulation	31 EA	1 EA
8/04/2016	1	G	Classroom G017	Pipe Fitting Insulation	21 EA	7 EA
8/04/2016	1	G	G3 Cooking Room	Pipe Fitting Insulation	32 EA	2 EA
8/04/2016	1	2	Classroom 215	Pipe Fitting Insulation	16 EA	1 EA
8/04/2016	1	2	Computer Network Room 200A	Pipe Fitting Insulation	26 EA	2 EA
8/04/2016	1	3	Slop Sink in Hallway outside of Women's Lounge	Pipe Fitting Insulation	2 EA	2 EA

Section II Re-inspection Data

- A. Introduction
- B. Re-inspection Key Definitions
- C. Room by Room Asbestos Location Log

Section II - A

Re-inspection Data

Introduction

The following information documents the Three-Year Re-inspection IX of the subject school/facility. The Homogeneous Area Reports were produced using the building inspector's field data on the facility. The key to the Homogeneous Area Report is outlined in the following pages of this report.

Section II - B
(page 1 of 4)

SCHOOL DISTRICT OF PHILADELPHIA
AHERA THREE YEAR RE-INSPECTION IX

ITEM	DEFINITION
ULCS#	Individual identification number assigned to each school within the School District of Philadelphia.
HOMOGENEOUS AREA ID#	Identification number assigned to each homogeneous area in a school/facility. Each section of the homogeneous area ID is significant. 1010/01/01/01 A B C D A. Is the ULCS# for the school. B. Designates the specific building/building area within the school. C. Designates the floor or level within the building/building area. D. Designates the homogeneous material within that floor or level. Note: Item D may be a number or a letter.
SYSTEM AFFECTED	Corresponds to the AHERA system for classifying materials. T : Thermal System S : Surfacing System M : Miscellaneous
ITEM AFFECTED	Is a description of the homogeneous material.
ORIGINAL INSPECTION DATA	This section contains the information found in the original Management Plan (1988-1989).
AMOUNT OF MATERIAL/ UNIT	Quantity of material, and measuring unit. Units include: Square Feet (SF) Each (EA) Linear Feet (LF) Cubic Feet (CF).

**SCHOOL DISTRICT OF PHILADELPHIA
AHERA THREE YEAR RE-INSPECTION IX**

RE-INSPECTION FORM KEY

ITEM	DEFINITION
CND Condition	Corresponds to AHERA condition rating for materials. 0 : No Damage 1 : Damage 2 : Significant Damage
DP Damage Potential	Corresponds to the AHERA material assessment system. 1 : Potential for Damage 2 : Potential for Significant Damage
ASMD Assumed Asbestos	This means that a material was not sampled for asbestos content during the original Management Plan inspection.
RA Response Action	This corresponds to the AHERA system of response action rating for materials. 1 : Establish O&M Program 2 : Repair and Establish O&M Program 3 : Enclose 4 : Encapsulate 5 : Remove 6 : Partial Removal and Establish O&M Program
CHANGES	This section describes changes to the homogeneous material in the twenty-four years since the original AHERA inspection. The abbreviations are defined below. RMVD : Removed ENCL : Enclosed ENCP : Encapsulated DMGD : Damaged SMPLD : Sampled MTRL : Material RPRD : Repaired N/L : None Located RPLCD : Replaced

**SCHOOL DISTRICT OF PHILADELPHIA
AHERA THREE-YEAR RE-INSPECTION IX**

RE-INSPECTION FORM KEY

ITEM	DEFINITION												
THREE YEAR RE-INSPECTION	<p>This section contains the information obtained from the Three-Year Re-inspection IX. With three exceptions, the information categories are identical in format and meaning to those found in the original inspection data section. The three exceptions are defined below.</p>												
DMGD AMT Amount Damaged	<p>This section gives the quantity of damaged material in a homogeneous area. The quantity is shown in the same format as the amount of material/unit section.</p>												
NF Newly Friable	<p>This section identifies materials in the original Management Plan which have since become friable.</p>												
RA Response Action	<p>This rating is based on the AHERA regulations, and is comparable to the RA rating found in the "Original Inspection Data" section. The following table details the response actions.</p> <table><tr><td>1.</td><td>Establish O&M Program</td></tr><tr><td>2.</td><td>Repair and Establish O&M Program</td></tr><tr><td>3.</td><td>Enclose</td></tr><tr><td>4.</td><td>Encapsulate</td></tr><tr><td>5.</td><td>Remove</td></tr><tr><td>6.</td><td>Partial Removal and Establish O&M Program</td></tr></table> <p>a. High Priority Response The homogeneous material has been scheduled for abatement or other response action.</p> <p>b. Medium Priority Response The homogeneous material will be scheduled for abatement or other response action as soon as the high priority responses have been addressed.</p> <p>c. Low Priority Response The homogeneous material will be scheduled for abatement or other response action as soon as the medium priority responses have been addressed.</p> <p>d. On-Going Response/Operations and Maintenance The homogeneous material does not require abatement or other response action at present, and should be included in the facility's on-going operations and maintenance program.</p>	1.	Establish O&M Program	2.	Repair and Establish O&M Program	3.	Enclose	4.	Encapsulate	5.	Remove	6.	Partial Removal and Establish O&M Program
1.	Establish O&M Program												
2.	Repair and Establish O&M Program												
3.	Enclose												
4.	Encapsulate												
5.	Remove												
6.	Partial Removal and Establish O&M Program												

**SCHOOL DISTRICT OF PHILADELPHIA
AHERA THREE-YEAR RE-INSPECTION IX**

RE-INSPECTION FORM KEY

The information presented in the changes section has been compiled from a variety of sources, including the Re-inspection and the following:

- * Quality Control/Quality Assurance Reports of asbestos abatement projects, prepared by consultants to the School District.
- * Permit and Notification Forms for asbestos abatement projects.
- * Periodic Surveillance Forms
- * Operations and Maintenance activities performed by School District personnel.
- * Verbal information from School District personnel.
- * Reports of sampling and analysis of suspected materials by both School District personnel and outside consultants.

**ROOM BY
ROOM
LOCATION LOG
REPORT**

This section gives information, including damage amount and location, for a specific homogeneous material on a room-by-room basis and follows the Re-inspection form.

NOTE: The disparate nature of the above sources of information prohibits the verification of much information within the scope of the AHERA Three-Year Re-inspection . Discrepancies and omissions may exist in this information, and therefore is included on an "as is" basis. The inspectors for the Three-Year Re-inspection IX evaluated homogeneous areas based on the materials current condition and location, as evidenced during the inspector's site visit.

Section II - C

Room by Room Location Log Report

These charts are to be used for a quick reference* in order to avoid the unknowing disturbance of Asbestos Containing Materials during any and all Operations, Maintenance, Renovation, and/or Demolition activities at this location.

NOTE:

*Contact OEMS prior to the disturbance of any of the materials that are listed as **Confirmed and/or Assumed**.*

The quantities listed for (NAD) non-asbestos containing materials and/or Non-Suspect Materials are only estimated and were not measured for the purpose of this report. Field verification of quantities for renovation purposes would be necessary.

6050 Philadelphia High School for Girls 2015-2016 AHERA Three-Year Report.xls

Element		School District of Philadelphia		AHERA Three-Year Reinspection 2015-2016 Room by Room Location Log Report										Reinspection Date: 1/7/2016		Attic Crawlspace Ranking				Damage Potential (DP)				Newly Friable (NF)				Response Action (RA)					
		Philadelphia High School For Girls		1400 W Olney Avenue Philadelphia, PA 19141 ULCS# 6050																												Building Inspector: Alex Roman	
		Certification Number: EHSBIR-150619-008																															
		Management Planner: Monique Causley																															
		Certification Number: ACC-0215-8-010																															
On Site Room Name		System Affected		Material Description		HID#		Confirmed, Assumed, NAD, Non Suspect ACM		Amount of Material		SF LF EA		Amount of Damage		SF LF EA		Color required for VAT		Comments/Description/Notes													
1	SB	First Room in the Mechanical Space at the Entrance	N/A	Cement Floor			Non Suspect ACM	2000	SF	0											N/A	N/A	N/A										
1	SB	First Room in the Mechanical Space at the Entrance	N/A	Concrete Ceiling			Non Suspect ACM	2000	SF	0											N/A	N/A	N/A										
1	SB	First Room in the Mechanical Space at the Entrance	N/A	Concrete Block Wall			Non Suspect ACM	4000	SF	0											N/A	N/A	N/A										
1	SB	First Room in the Mechanical Space at the Entrance	M	Vibration Damper Cloth	6050/01/SB/05		Assumed	3	EA	0											1	No	1/D										
1	SB	First Room in the Mechanical Space at the Entrance	T	Pipe Fitting Insulation	6050/01/SB/08		Confirmed		EA	0											1	No	1/D										
1	SB	First Room in the Mechanical Space at the Entrance	N/A	Fiberglass Pipe Insulation			Non Suspect ACM	300	LF	6	LF										N/A	N/A	N/A										
1	SB	Food Service in Mechanical Room area	X	X	X		X	X	X	X	X										X	X	X										
1	SB	Men's Restroom in Mechanical Space	N/A	Cement Floor			Non Suspect ACM	200	SF	0											N/A	N/A	N/A										
1	SB	Men's Restroom in Mechanical Space	N/A	Concrete Ceiling			Non Suspect ACM	200	SF	0											N/A	N/A	N/A										
1	SB	Men's Restroom in Mechanical Space	N/A	Brick Wall			Non Suspect ACM	500	SF	0											N/A	N/A	N/A										
1	SB	Men's Restroom in Mechanical Space	T	Pipe Fitting Insulation	6050/01/SB/08		Confirmed	19	EA	0											1	No	1/D										
1	SB	Men's Restroom in Mechanical Space	N/A	Fiberglass Pipe Insulation			Non Suspect ACM	180	LF	2	LF										N/A	N/A	N/A										
1	SB	Storage area next to Men's Restroom in Mechanical Area	N/A	Concrete Ceiling			Non Suspect ACM	300	SF	0											N/A	N/A	N/A										
1	SB	Storage area next to Men's Restroom in Mechanical Area	N/A	Cement Floor			Non Suspect ACM	300	SF	0											N/A	N/A	N/A										
1	SB	Storage area next to Men's Restroom in Mechanical Area	N/A	Brick Wall			Non Suspect ACM	600	SF	0											N/A	N/A	N/A										
1	SB	Storage area next to Men's Restroom in Mechanical Area	T	Pipe Fitting Insulation	6050/01/SB/08		Confirmed	17	EA	0											1	No	1/D										
1	SB	Storage area next to Men's Restroom in Mechanical Area	N/A	Fiberglass Pipe Insulation			Non Suspect ACM	120	LF	10	LF										N/A	N/A	N/A										
1	SB	Pump Room	N/A	Cement Floor			Non Suspect ACM	500	SF	0											N/A	N/A	N/A										
1	SB	Pump Room	N/A	Concrete Ceiling			Non Suspect ACM	500	SF	0											N/A	N/A	N/A										
1	SB	Pump Room	N/A	Brick Wall			Non Suspect ACM	800	SF	0											N/A	N/A	N/A										
1	SB	Pump Room	T	Pipe Fitting Insulation	6050/01/SB/08		Confirmed	26	EA	4	EA										New damage, DDC written up/fill in addition damage material information for Confirmed materials	1	Yes	5/C									
1	SB	Pump Room	N/A	Fiberglass Pipe Insulation			Non Suspect ACM	100	LF	8	LF										What kind of damage?	N/A	N/A	N/A									
1	SB	Main Mechanical Room Upper Level at new boilers	N/A	Cement Floor			Non Suspect ACM	3000	SF	0											N/A	N/A	N/A										
1	SB	Main Mechanical Room Upper Level at new boilers	N/A	Concrete Ceiling			Non Suspect ACM	3000	SF	0											N/A	N/A	N/A										
1	SB	Main Mechanical Room Upper Level at new boilers	N/A	Brick Wall			Non Suspect ACM	4000	SF	0											N/A	N/A	N/A										
1	SB	Main Mechanical Room Upper Level at new boilers	T	Tank Insulation	6050/01/SB/05		Confirmed	600	SF	0											1	No	1/D										
1	SB	Main Mechanical Room Upper Level at new boilers	T	Pipe Fitting Insulation	6050/01/SB/08		Confirmed	70	EA	1	EA										New damage, DDC written up/fill in addition damage material information for Confirmed materials	1	Yes	5/C									
1	SB	Main Mechanical Room Upper Level at new boilers	N/A	Fiberglass Pipe Insulation			Non Suspect ACM	300	LF	36	LF										What kind of damage?	N/A	N/A	N/A									
1	SB	Main Mechanical Room Lower Level at old boilers	N/A	Cement Floor			Non Suspect ACM	3000	SF	0											N/A	N/A	N/A										
1	SB	Main Mechanical Room Lower Level at old boilers	N/A	Concrete Ceiling			Non Suspect ACM	3000	SF	0											N/A	N/A	N/A										
1	SB	Main Mechanical Room Lower Level at old boilers	N/A	Brick Wall			Non Suspect ACM	4000	SF	0											N/A	N/A	N/A										
1	SB	Main Mechanical Room Lower Level at old boilers	T	Exterior Boiler Insulation	6050/01/SB/07		Confirmed	600	SF	600	SF										1	Yes	5/C										
1	SB	Main Mechanical Room Lower Level at old boilers	T	Pipe Fitting Insulation	6050/01/SB/08		Confirmed	276	EA	0											1	No	1/D										
1	SB	Main Mechanical Room Lower Level at old boilers	N/A	Fiberglass Pipe Insulation			Non Suspect ACM	300	LF	30	LF										What kind of damage?	N/A	N/A	N/A									
1	SB	Main Mechanical Room Lower Level at old boilers	T	Boiler Breaching	6050/01/SB/06		Confirmed	2000	SF	50	SF										1	Yes	5/C										
1	SB	Lower Level under new boilers next to old boilers	N/A	Concrete Ceiling			Non Suspect ACM	3000	SF	0											N/A	N/A	N/A										
1	SB	Lower Level under new boilers next to old boilers	N/A	Cement Floor			Non Suspect ACM	3000	SF	0											N/A	N/A	N/A										
1	SB	Lower Level under new boilers next to old boilers	N/A	Concrete Block Wall			Non Suspect ACM	4000	SF	0											N/A	N/A	N/A										
1	SB	Lower Level under new boilers next to old boilers	T	Pipe Fitting Insulation	6050/01/SB/08		Confirmed	3	EA	0											1	No	1/D										
1	SB	Lower Level under new boilers next to old boilers	N/A	Fiberglass Pipe Insulation			Non Suspect ACM	40	LF	2	LF										What kind of damage?	N/A	N/A	N/A									
1	SB	Lower Level under the Pump Room next to the old boilers	N/A	Cement Floor			Non Suspect ACM	1000	SF	0											Area was flooded with no lights no other materials could be identified but it's assumed that pipe insulation may be present	N/A	N/A	N/A									
1	SB	Lower Level under the Pump Room next to the old boilers	N/A	Concrete Ceiling			Non Suspect ACM	1000	SF	0											N/A	N/A	N/A										
1	SB	Lower Level under the Pump Room next to the old boilers	N/A	Brick Wall			Non Suspect ACM	1500	SF	0											N/A	N/A	N/A										
1	SB	Former Coal Area	N/A	Cement Floor			Non Suspect ACM	2000	SF	0											N/A	N/A	N/A										
1	SB	Former Coal Area	N/A	Concrete Ceiling			Non Suspect ACM	2000	SF	0											N/A	N/A	N/A										
1	SB	Former Coal Area	N/A	Concrete Block Wall			Non Suspect ACM	4000	SF	0											N/A	N/A	N/A										
1	SB	Former Coal Area	T	Pipe Fitting Insulation	6050/01/SB/08		Confirmed	9	EA	0											1	No	1/D										
1	SB	Former Coal Area	N/A	Fiberglass Pipe Insulation			Non Suspect ACM	120	LF	0											N/A	N/A	N/A										
1	SB	Entrance Cove into the Coal Are	N/A	Cement Floor			Non Suspect ACM	300	SF	0											N/A	N/A	N/A										
1	SB	Entrance Cove into the Coal Are	N/A	Concrete Block Wall			Non Suspect ACM	600	SF	0											N/A	N/A	N/A										
1	SB	Entrance Cove into the Coal Are	N/A	Concrete Ceiling			Non Suspect ACM	300	SF	0											Steam Leak at Ceiling	N/A	N/A	N/A									
1	SB	Entrance Cove into the Coal Are	T	Pipe Fitting Insulation	6050/01/SB/08		Confirmed	3	EA	0											1	No	1/D										
1	SB	Entrance Cove into the Coal Are	N/A	Fiberglass Pipe Insulation			Non Suspect ACM	100	LF	0											N/A	N/A	N/A										
1	SB	Hallway leading to the Electrical Room	N/A	Concrete Ceiling			Non Suspect ACM	300	SF	0											N/A	N/A	N/A										
1	SB	Hallway leading to the Electrical Room	N/A	Cement Floor			Non Suspect ACM	300	SF	0											N/A	N/A	N/A										
1	SB	Hallway leading to the Electrical Room	N/A	Concrete Block Wall			Non Suspect ACM	600	SF	0											N/A	N/A	N/A										

6050 Philadelphia High School for Girls 2015-2016 AHERA Three-Year Report.xls

School District of Philadelphia		AHERA Three-Year Reinspection 2015-2016 Room by Room Location Log Report										Reinspection Date: 1/7/2016							
												Building Inspector: Alex Roman							
												Certification Number: EHSBIR-150619-008							
																Management Planner: Monique Causley			
Element	Floor	On Site Room Name	System Affected	Material Description	HID#	Confirmed, Assumed, NAD, Non Suspect ACM	Amount of Material	SF LF EA	Amount of Damage	SF LF EA	Color required for VAT	Comments/Description/Notes	Attic Crawlspace Ranking	Damage Potential (DP)	Newly Friable (NF)	Response Action (RA)			
1	SB	Electrical Room	N/A	Concrete Ceiling		Non Suspect ACM	800	SF	0						N/A	N/A	N/A		
1	SB	Electrical Room	N/A	Concrete Block Wall		Non Suspect ACM	1200	SF	0						N/A	N/A	N/A		
1	SB	Electrical Room	N/A	Cement Floor		Non Suspect ACM	800	SF	0						N/A	N/A	N/A		
1	SB	Crawl Space across the Electrical Room	N/A	Concrete Ceiling		Non Suspect ACM	3000	SF	0						N/A	N/A	N/A		
1	SB	Crawl Space across the Electrical Room	N/A	Concrete Block Wall		Non Suspect ACM	3000	SF	0						N/A	N/A	N/A		
1	SB	Crawl Space across the Electrical Room	N/A	Dirt Floor		Non Suspect ACM	3000	SF	0						N/A	N/A	N/A		
1	SB	Crawl Space across the Electrical Room	T	Pipe Fitting Insulation	6050/01/SB/08	Confirmed	95	EA	0						1	No	1/D		
1	SB	Crawl Space across the Electrical Room	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	300	LF	0						N/A	N/A	N/A		
1	SB	Crawl Space across the Electrical Room	M	Vibration Damper Cloth	6050/01/SB/05	Assumed	1	EA	0						1	No	1/D		
1	B	Gymnasium B	N/A	Wood Floor		Non Suspect ACM	3000	SF	0						N/A	N/A	N/A		
1	B	Gymnasium B	N/A	Concrete Block Wall		Non Suspect ACM	5000	SF	0						N/A	N/A	N/A		
1	B	Gymnasium B	N/A	Concrete Ceiling		Non Suspect ACM	3000	SF	0						N/A	N/A	N/A		
1	B	Gymnasium A	N/A	Wood Floor		Non Suspect ACM	3000	SF	0						N/A	N/A	N/A		
1	B	Gymnasium A	N/A	Concrete Block Wall		Non Suspect ACM	5000	SF	0						N/A	N/A	N/A		
1	B	Gymnasium A	N/A	Concrete Ceiling		Non Suspect ACM	3000	SF	0						N/A	N/A	N/A		
1	B	Gymnasium A	N/A	Partition Room Dividers		Non Suspect ACM	2000	SF	0						N/A	N/A	N/A		
1	B	Gymnasium Exit Foyer to the west	N/A	Concrete Ceiling		Non Suspect ACM	300	SF	0						N/A	N/A	N/A		
1	B	Gymnasium Exit Foyer to the west	N/A	Cement Floor		Non Suspect ACM	300	SF	0						N/A	N/A	N/A		
1	B	Gymnasium Exit Foyer to the west	N/A	Ceramic Tile Walls		Non Suspect ACM	500	SF	0						N/A	N/A	N/A		
1	B	Gymnasium Exit Foyer to the west	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	8	LF	0						N/A	N/A	N/A		
1	B	Gymnasium Exit Foyer to the west	T	Radiator Insulation	6050/01/0B/CRI/AR/1600	Assumed	1	EA	0						1	No	1/D		
1	B	Gymnasium Exit Foyer to the north by Boy's and Girls' Restrooms	N/A	Cement Floor		Non Suspect ACM	400	SF	0						N/A	N/A	N/A		
1	B	Gymnasium Exit Foyer to the north by Boy's and Girls' Restrooms	N/A	Concrete Ceiling		Non Suspect ACM	400	SF	0						N/A	N/A	N/A		
1	B	Gymnasium Exit Foyer to the north by Boy's and Girls' Restrooms	N/A	Ceramic Tile Walls		Non Suspect ACM	600	SF	0						N/A	N/A	N/A		
1	B	Men's Restroom to the north in Hallway from Gym A	N/A	Ceramic Tile Walls		Non Suspect ACM	400	SF	0						N/A	N/A	N/A		
1	B	Men's Restroom to the north in Hallway from Gym A	N/A	Cement Floor		Non Suspect ACM	300	SF	0						N/A	N/A	N/A		
1	B	Men's Restroom to the north in Hallway from Gym A	N/A	Concrete Ceiling		Non Suspect ACM	300	SF	0						N/A	N/A	N/A		
1	B	Men's Restroom to the north in Hallway from Gym A	T	Pipe Fitting Insulation	6050/01/0B/11	Confirmed	14	EA	0						1	No	1/D		
1	B	Men's Restroom to the north in Hallway from Gym A	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	10	LF	0						N/A	N/A	N/A		
1	B	Women's Restroom to the north in Hallway from Gym A	N/A	Cement Floor		Non Suspect ACM	300	SF	0						N/A	N/A	N/A		
1	B	Women's Restroom to the north in Hallway from Gym A	N/A	Concrete Ceiling		Non Suspect ACM	300	SF	0						N/A	N/A	N/A		
1	B	Women's Restroom to the north in Hallway from Gym A	N/A	Ceramic Tile Walls		Non Suspect ACM	600	SF	0						N/A	N/A	N/A		
1	B	Women's Restroom to the north in Hallway from Gym A	T	Pipe Fitting Insulation	6050/01/0B/11	Confirmed	15	EA	0						1	No	1/D		
1	B	Women's Restroom to the north in Hallway from Gym A	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	10	LF	0						N/A	N/A	N/A		
1	B	Stairs in the Hallway to the north of Gymnasium A above the Men's Restroom	N/A	Cement Floor		Non Suspect ACM	300	SF	0						N/A	N/A	N/A		
1	B	Stairs in the Hallway to the north of Gymnasium A above the Men's Restroom	N/A	Concrete Ceiling		Non Suspect ACM	300	SF	0						N/A	N/A	N/A		
1	B	Stairs in the Hallway to the north of Gymnasium A above the Men's Restroom	N/A	Ceramic Tile Walls		Non Suspect ACM	500	SF	0						N/A	N/A	N/A		
1	B	Stairs in the Hallway to the north of Gymnasium A above the Women's Restroom	N/A	Cement Floor		Non Suspect ACM	300	SF	0						N/A	N/A	N/A		
1	B	Stairs in the Hallway to the north of Gymnasium A above the Women's Restroom	N/A	Concrete Ceiling		Non Suspect ACM	300	SF	0						N/A	N/A	N/A		
1	B	Stairs in the Hallway to the north of Gymnasium A above the Women's Restroom	N/A	Ceramic Tile Walls		Non Suspect ACM	500	SF	0						N/A	N/A	N/A		
1	B	Gymnasium A Storage on the north wall	N/A	Cement Floor		Non Suspect ACM	300	SF	0						N/A	N/A	N/A		
1	B	Gymnasium A Storage on the north wall	N/A	Concrete Ceiling		Non Suspect ACM	300	SF	0						N/A	N/A	N/A		
1	B	Gymnasium A Storage on the north wall	N/A	Concrete Block Wall		Non Suspect ACM	500	SF	0						N/A	N/A	N/A		
1	B	Gymnasium A Storage on the north wall	T	Duct Insulation	6050/01/0B/DD	Confirmed	30	SF	4	SF		Sampled 8/10/2016 (CRI/IH) DDC written for removal		1	Yes	5/A			
1	B	Gymnasium A Storage on the north wall	T	Pipe Fitting Insulation	6050/01/0B/11	Confirmed	4	EA	0						1	No	1/D		
1	B	Gymnasium A Storage on the north wall	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	20	LF	0						N/A	N/A	N/A		
1	B	Gymnasium A Storage on the north wall	M	Vibration Damper Cloth	6050/01/0B/12	Assumed	1	EA	0						1	No	1/D		
1	B	Phys. Ed Room in Gym A Gym Office	M	Floor Tile VAT 9" x 9"	6050/01/0B/13	Confirmed	400	SF	0		Tan				1	No	1/D		
1	B	Phys. Ed Room in Gym A Gym Office	N/A	Concrete Ceiling		Non Suspect ACM	400	SF	0						N/A	N/A	N/A		
1	B	Phys. Ed Room in Gym A Gym Office	N/A	Concrete Block Wall		Non Suspect ACM	600	SF	0						N/A	N/A	N/A		
1	B	Phys. Ed Room in Gym A Gym Office	T	Pipe Fitting Insulation	6050/01/0B/11	Confirmed	10	EA	0						1	No	1/D		
1	B	Phys. Ed Room in Gym A Gym Office	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	40	LF	0						N/A	N/A	N/A		
1	B	Teacher's Locker Room in Gym Office in Gym A	N/A	Concrete Ceiling		Non Suspect ACM	200	SF	0						N/A	N/A	N/A		
1	B	Teacher's Locker Room in Gym Office in Gym A	N/A	Cement Floor		Non Suspect ACM	200	SF	0						N/A	N/A	N/A		

6050 Philadelphia High School for Girls 2015-2016 AHERA Three-Year Report.xls

		School District of Philadelphia		AHERA Three-Year Reinspection 2015-2016 Room by Room Location Log Report						Reinspection Date: 1/7/2016 Building Inspector: Alex Roman Certification Number: EHSBIR-150619-008 Management Planner: Monique Causley Certification Number: ACC-0215-8-010						
		Philadelphia High School For Girls 1400 W Olney Avenue Philadelphia, PA 19141 ULCS# 6050														
Element	Room	On Site Room Name	System Affected	Material Description	HID#	Confirmed, Assumed, NAD, Non Suspect ACM	Amount of Material	SF LF EA	Amount of Damage	SF LF EA	Color required for VAT	Comments/Description/Notes	Attic Crawlspace Ranking	Damage Potential (DP)	Newly Friable (NF)	Response Action (RA)
1	B	Teacher's Locker Room in Gym Office in Gym A	N/A	Ceramic Tile Walls		Non Suspect ACM	400	SF	0					N/A	N/A	N/A
1	B	Teacher's Locker Room in Gym Office in Gym A	T	Pipe Fitting Insulation	6050/01/0B/11	Confirmed	8	EA	0					1	No	1/D
1	B	Teacher's Locker Room in Gym Office in Gym A	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	40	LF	0					N/A	N/A	N/A
1	B	Storage Closet adjacent to the Hallway entrance to the Gymnasiums in Gym A	N/A	Cement Floor		Non Suspect ACM	400	SF	0					N/A	N/A	N/A
1	B	Storage Closet adjacent to the Hallway entrance to the Gymnasiums in Gym A	N/A	Concrete Ceiling		Non Suspect ACM	400	SF	0					N/A	N/A	N/A
1	B	Storage Closet adjacent to the Hallway entrance to the Gymnasiums in Gym A	N/A	Concrete Block Wall		Non Suspect ACM	600	SF	0					N/A	N/A	N/A
1	B	Storage Closet adjacent to the Hallway entrance to the Gymnasiums in Gym A	M	Vibration Damper Cloth	6050/01/0B/12	Assumed	2	EA	0					1	No	1/D
1	B	Storage Closet adjacent to the Hallway entrance to the Gymnasiums in Gym A	T	Pipe Fitting Insulation	6050/01/0B/11	Confirmed	22	EA	0					1	No	1/D
1	B	Storage Closet adjacent to the Hallway entrance to the Gymnasiums in Gym A	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	50	LF	2	LF		What kind of damage?		N/A	N/A	N/A
1	B	Hallway leading into the Gymnasiums	M	Floor Tile VAT 9" x 9"	6050/01/0B/13	Confirmed	400	SF	0		Tan			1	No	1/D
1	B	Hallway leading into the Gymnasiums	N/A	Ceramic Tile Walls		Non Suspect ACM	800	SF	0					N/A	N/A	N/A
1	B	Hallway leading into the Gymnasiums	N/A	Ceiling Tile 1' x 1'		NAD	400	SF	0					N/A	N/A	N/A
1	B	Hallway leading into the Gymnasiums	T	Pipe Fitting Insulation	6050/01/0B/11	Confirmed	6	EA	0					1	No	1/D
1	B	Hallway leading into the Gymnasiums	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	30	LF	0					N/A	N/A	N/A
1	B	Storage Closet nearest to the Main Entrance in Gym B	N/A	Cement Floor		Non Suspect ACM	300	SF	0			No access during Summer Inspection		N/A	N/A	N/A
1	B	Storage Closet nearest to the Main Entrance in Gym B	N/A	Concrete Ceiling		Non Suspect ACM	300	SF	0					N/A	N/A	N/A
1	B	Storage Closet nearest to the Main Entrance in Gym B	N/A	Concrete Block Wall		Non Suspect ACM	500	SF	0					N/A	N/A	N/A
1	B	Storage Closet nearest to the Main Entrance in Gym B	T	Pipe Fitting Insulation	6050/01/0B/11	Confirmed	12	EA	0					1	No	1/D
1	B	Storage Closet nearest to the Main Entrance in Gym B	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	50	LF	0					N/A	N/A	N/A
1	B	Storage Closet marked Phys. Ed. Room in Gym B	M	Floor Tile VAT 9" x 9"	6050/01/0B/13	Confirmed	200	SF	0		Tan			1	No	1/D
1	B	Storage Closet marked Phys. Ed. Room in Gym B	N/A	Concrete Ceiling		Non Suspect ACM	200	SF	0					N/A	N/A	N/A
1	B	Storage Closet marked Phys. Ed. Room in Gym B	N/A	Concrete Block Wall		Non Suspect ACM	400	SF	0					N/A	N/A	N/A
1	B	Storage Closet marked Phys. Ed. Room in Gym B	T	Pipe Fitting Insulation	6050/01/0B/11	Confirmed	4	EA	0					1	No	1/D
1	B	Storage Closet marked Phys. Ed. Room in Gym B	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	20	LF	0					N/A	N/A	N/A
1	B	Storage Closet	N/A	Concrete Ceiling		Non Suspect ACM	200	SF	0					N/A	N/A	N/A
1	B	Storage Closet marked Phys. Ed. Room in Gym B	M	Floor Tile VAT 9" x 9"	6050/01/0B/13	Confirmed	200	SF	0		Tan			1	No	1/D
1	B	Storage Closet	N/A	Concrete Block Wall		Non Suspect ACM	400	SF	0					N/A	N/A	N/A
1	B	Storage Closet marked Phys. Ed. Room in Gym B	M	Vibration Damper Cloth	6050/01/0B/12	Assumed	2	EA	0					1	No	1/D
1	B	Exterior Stairs to the south in Gym B	N/A	Cement Floor		Non Suspect ACM	200	SF	0			Stairs are outside of the building		N/A	N/A	N/A
1	B	Administrative office/Classroom associated with the Gym attached to the Phys Ed Department Office	N/A	Concrete Block Wall		Non Suspect ACM	500	SF	0					N/A	N/A	N/A
1	B	Administrative office/Classroom associated with the Gym attached to the Phys Ed Department Office	N/A	Concrete Ceiling		Non Suspect ACM	500	SF	0					N/A	N/A	N/A
1	B	Administrative office/Classroom associated with the Gym attached to the Phys Ed Department Office	M	Floor Tile VAT 12" x 12"	6050/01/0B/VER/AR/2004	Assumed	500	SF	0		Grey			1	No	1/D
1	B	Phys Ed Department Office	M	Floor Tile VAT 9" x 9"	6050/01/0B/13	Confirmed	500	SF	0		Tan			1	No	1/D
1	B	Phys Ed Department Office	N/A	Concrete Ceiling		Non Suspect ACM	500	SF	0					N/A	N/A	N/A
1	B	Phys Ed Department Office	N/A	Concrete Block Wall		Non Suspect ACM	600	SF	0					N/A	N/A	N/A
1	B	Phys Ed Department Office	T	Pipe Fitting Insulation	6050/01/0B/11	Confirmed	4	EA	0					1	No	1/D
1	B	Phys Ed Department Office	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	10	LF	0					N/A	N/A	N/A
1	B	Phys Ed Department Office Restroom	N/A	Concrete Ceiling		Non Suspect ACM	100	SF	0					N/A	N/A	N/A
1	B	Phys Ed Department Office Restroom	N/A	Concrete Block Wall		Non Suspect ACM	100	SF	0					N/A	N/A	N/A
1	B	Phys Ed Department Office Restroom	N/A	Ceramic Tile Floors		Non Suspect ACM	100	SF	0					N/A	N/A	N/A
1	B	Hallway from Phys Ed Department Office to Visitors Changing Room	N/A	Ceiling Tile 1' x 1'		NAD	800	SF	6	SF		Missing tiles exposing brown glue dots underneath		N/A	N/A	N/A
1	B	Hallway from Phys Ed Department Office to Visitors Changing Room	M	Spine Ceiling Tile Glue Dots	6050/01/0B/CR/1H/2603	Assumed	200	SF	0					1	No	1/D
1	B	Hallway from Phys Ed Department Office to Visitors Changing Room	M	Floor Tile VAT 9" x 9"	6050/01/0B/13	Confirmed	800	SF	0		Tan			1	No	1/D
1	B	Hallway from Phys Ed Department Office to Visitors Changing Room	N/A	Ceramic Tile Walls		Non Suspect ACM	1200	SF	0					N/A	N/A	N/A
1	B	Hallway from Phys Ed Department Office to Visitors Changing Room	T	Pipe Fitting Insulation	6050/01/0B/11	Confirmed	5	EA	0					1	No	1/D
1	B	Storage Closet across the Hall from the Phys Ed Department Office	N/A	Concrete Block Wall		Non Suspect ACM	400	SF	0					N/A	N/A	N/A
1	B	Storage Closet across the Hall from the Phys Ed Department Office	N/A	Cement Floor		Non Suspect ACM	400	SF	0					N/A	N/A	N/A
1	B	Storage Closet across the Hall from the Phys Ed Department Office	N/A	Concrete Ceiling		Non Suspect ACM	400	SF	0					N/A	N/A	N/A
1	B	Storage Closet across the Hall from the Phys Ed Department Office	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	30	LF	0					N/A	N/A	N/A

6050 Philadelphia High School for Girls 2015-2016 AHERA Three-Year Report.xls

		School District of Philadelphia		AHERA Three-Year Reinspection 2015-2016 Room by Room Location Log Report						Reinspection Date: 1/7/2016 Building Inspector: Alex Roman Certification Number: EHSBIR-150619-008 Management Planner: Monique Causley Certification Number: ACC-0215-8-010						
		Philadelphia High School For Girls 1400 W Olney Avenue Philadelphia, PA 19141 ULCS# 6050														
Element	Room	On Site Room Name	System Affected	Material Description	HID#	Confirmed, Assumed, NAD, Non Suspect ACM	Amount of Material	SF LF EA	Amount of Damage	SF LF EA	Color required for VAT	Comments/Description/Notes	Attic Crawlspace Ranking	Damage Potential (DP)	Newly Friable (NF)	Response Action (RA)
1	B	Hallway to the south of the Girl's Locker Room that leads to the Hallway in front of the Phys Ed Department Office	M	Floor Tile VAT 9" x 9"	6050/01/0B/13	Confirmed	500	SF	0		Tan			1	No	1/D
1	B	Hallway to the south of the Girl's Locker Room that leads to the Hallway in front of the Phys Ed Department Office	N/A	Ceiling Tile 1' x 1'		NAD	500	SF	0					N/A	N/A	N/A
1	B	Hallway to the south of the Girl's Locker Room that leads to the Hallway in front of the Phys Ed Department Office	N/A	Ceramic Tile Walls		Non Suspect ACM	700	SF	0					N/A	N/A	N/A
1	B	Hallway to the south of the Girl's Locker Room that leads to the Hallway in front of the Phys Ed Department Office	T	Pipe Fitting Insulation	6050/01/0B/11	Confirmed	15	EA	0					1	No	1/D
1	B	Hallway to the south of the Girl's Locker Room that leads to the Hallway in front of the Phys Ed Department Office	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	70	LF	0					N/A	N/A	N/A
1	B	Stairs leading to the south entrance to the Girls' Locker Room	N/A	Cement Floor		Non Suspect ACM	200	SF	0					N/A	N/A	N/A
1	B	Stairs leading to the south entrance to the Girls' Locker Room	N/A	Concrete Ceiling		Non Suspect ACM	200	SF	0					N/A	N/A	N/A
1	B	Stairs leading to the south entrance to the Girls' Locker Room	N/A	Ceramic Tile Walls		Non Suspect ACM	400	SF	0					N/A	N/A	N/A
1	B	Hallway/Foyer at the leading into the Girl's Locker Room from the south	N/A	Cement Floor		Non Suspect ACM	300	SF	0					N/A	N/A	N/A
1	B	Hallway/Foyer at the leading into the Girl's Locker Room from the south	N/A	Concrete Ceiling		Non Suspect ACM	300	SF	0					N/A	N/A	N/A
1	B	Hallway/Foyer at the leading into the Girl's Locker Room from the south	N/A	Ceramic Tile Walls		Non Suspect ACM	500	SF	0					N/A	N/A	N/A
1	B	Hallway in the Girl's Locker Room leading to the Showers	N/A	Ceramic Tile Walls		Non Suspect ACM	400	SF	0					N/A	N/A	N/A
1	B	Hallway in the Girl's Locker Room leading to the Showers	N/A	Concrete Ceiling		Non Suspect ACM	400	SF	0					N/A	N/A	N/A
1	B	Hallway in the Girl's Locker Room leading to the Showers	N/A	Cement Floor		Non Suspect ACM	400	SF	0					N/A	N/A	N/A
1	B	Main Entrance Hallway/Foyer to the Girl's Locker Room	N/A	Cement Floor		Non Suspect ACM	200	SF	0					N/A	N/A	N/A
1	B	Main Entrance Hallway/Foyer to the Girl's Locker Room	N/A	Concrete Ceiling		Non Suspect ACM	200	SF	0					N/A	N/A	N/A
1	B	Main Entrance Hallway/Foyer to the Girl's Locker Room	N/A	Ceramic Tile Walls		Non Suspect ACM	200	SF	0					N/A	N/A	N/A
1	B	Girl's Locker Room	N/A	Cement Floor		Non Suspect ACM	3000	SF	0					N/A	N/A	N/A
1	B	Girl's Locker Room	N/A	Concrete Ceiling		Non Suspect ACM	3000	SF	0					N/A	N/A	N/A
1	B	Girl's Locker Room	N/A	Concrete Block Wall		Non Suspect ACM	4000	SF	0					N/A	N/A	N/A
1	B	Girl's Locker Room	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	200	LF	0					N/A	N/A	N/A
1	B	Girl's Locker Room	T	Pipe Fitting Insulation	6050/01/0B/11	Confirmed	57	EA	0					1	No	1/D
1	B	Girl's Locker Room Custodial Closet near the Main Entrance	N/A	Cement Floor		Non Suspect ACM	100	SF	0			No access during Summer inspection		N/A	N/A	N/A
1	B	Girl's Locker Room Custodial Closet near the Main Entrance	N/A	Concrete Block Wall		Non Suspect ACM	100	SF	0					N/A	N/A	N/A
1	B	Girl's Locker Room Custodial Closet near the Main Entrance	N/A	Concrete Ceiling		Non Suspect ACM	100	SF	0					N/A	N/A	N/A
1	B	Girl's Locker Room Storage Closet to the left of the Main Entrance	X	X	X	X	X	X	X	X	X			X	X	X
1	B	Uniforms Closet	N/A	Cement Floor		Non Suspect ACM	150	SF	0			No access during Summer inspection		N/A	N/A	N/A
1	B	Uniforms Closet	N/A	Concrete Ceiling		Non Suspect ACM	150	SF	0					N/A	N/A	N/A
1	B	Uniforms Closet	N/A	Concrete Block Wall		Non Suspect ACM	150	SF	0					N/A	N/A	N/A
1	B	Lacrosse Closet	N/A	Concrete Ceiling		Non Suspect ACM	150	SF	0			No access during Summer inspection		N/A	N/A	N/A
1	B	Lacrosse Closet	N/A	Cement Floor		Non Suspect ACM	150	SF	0					N/A	N/A	N/A
1	B	Lacrosse Closet	N/A	Concrete Block Wall		Non Suspect ACM	150	SF	0					N/A	N/A	N/A
1	B	Girl's Locker Room Restroom	N/A	Cement Floor		Non Suspect ACM	400	SF	0					N/A	N/A	N/A
1	B	Girl's Locker Room Restroom	N/A	Ceramic Tile Walls		Non Suspect ACM	400	SF	0					N/A	N/A	N/A
1	B	Girl's Locker Room Restroom	N/A	Concrete Ceiling		Non Suspect ACM	400	SF	0					N/A	N/A	N/A
1	B	Girl's Locker Room Restroom	T	Pipe Fitting Insulation	6050/01/0B/11	Confirmed	5	EA	0					1	No	1/D
1	B	Girl's Locker Room Restroom	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	10	LF	0					N/A	N/A	N/A
1	B	Custodial Closet next to the Girl's Locker Room Restroom	S	Plaster Ceiling	6050/01/0B/VER/AR/1900	Assumed	500	SF	0					1	No	1/D
1	B	Custodial Closet next to the Girl's Locker Room Restroom	N/A	Concrete Ceiling		Non Suspect ACM	100	SF	0			No access during Summer inspection		N/A	N/A	N/A
1	B	Custodial Closet next to the Girl's Locker Room Restroom	N/A	Cement Floor		Non Suspect ACM	100	SF	0					N/A	N/A	N/A
1	B	Custodial Closet next to the Girl's Locker Room Restroom	N/A	Concrete Block Wall		Non Suspect ACM	150	SF	0					N/A	N/A	N/A
1	B	Custodial Closet next to the Girl's Locker Room Restroom	M	Vibration Damper Cloth	6050/01/0B/12	Assumed	1	EA	0					1	No	1/D
1	B	Stairs next to the P.E. Faculty Dressing Room	N/A	Concrete Ceiling		Non Suspect ACM	200	SF	0					N/A	N/A	N/A

6050 Philadelphia High School for Girls 2015-2016 AHERA Three-Year Report.xls

School District of Philadelphia		AHERA Three-Year Reinspection 2015-2016										Reinspection Date: 1/7/2016							
		Room by Room Location Log Report										Building Inspector: Alex Roman							
												Certification Number: EHSBIR-150619-008							
																		Management Planner: Monique Causley	
Element	Floor																		
		On Site Room Name	System Affected	Material Description	HID#	Confirmed, Assumed, NAD, Non Suspect ACM	Amount of Material	SF	LF	EA	Amount of Damage	SF	LF	EA	Color required for VAT	Comments/Description/Notes	Attic Crawlspace Ranking	Damage Potential (DP)	Newly Friable (NF)
1	B	Stairs next to the P.E. Faculty Dressing Room	N/A	Ceramic Tile Walls		Non Suspect ACM	200	SF		0							N/A	N/A	N/A
1	B	Stairs next to the P.E. Faculty Dressing Room	N/A	Cement Floor		Non Suspect ACM	200	SF		0							N/A	N/A	N/A
1	B	P.E. Faculty Dressing Room	N/A	Cement Floor		Non Suspect ACM	400	SF		0							N/A	N/A	N/A
1	B	P.E. Faculty Dressing Room	N/A	Concrete Block Wall		Non Suspect ACM	400	SF		0							N/A	N/A	N/A
1	B	P.E. Faculty Dressing Room	N/A	Concrete Ceiling		Non Suspect ACM	400	SF		0							N/A	N/A	N/A
1	B	P.E. Faculty Dressing Room	N/A	Ceramic Tile Walls		Non Suspect ACM	400	SF		0							N/A	N/A	N/A
1	B	P.E. Faculty Dressing Room	T	Pipe Fitting Insulation	6050/01/0B/11	Confirmed	8	EA		0							1	No	1/D
1	B	P.E. Faculty Dressing Room	T	Fiberglass Pipe Insulation		Non Suspect ACM	30	LF		0							N/A	N/A	N/A
1	B	P.E. Faculty Dressing Room Restroom	N/A	Cement Floor		Non Suspect ACM	200	SF		0							N/A	N/A	N/A
1	B	P.E. Faculty Dressing Room Restroom	N/A	Ceramic Tile Walls		Non Suspect ACM	200	SF		0							N/A	N/A	N/A
1	B	P.E. Faculty Dressing Room Restroom	N/A	Concrete Ceiling		Non Suspect ACM	200	SF		0							N/A	N/A	N/A
1	B	Visiting Team Locker Room	N/A	Cement Floor		Non Suspect ACM	200	SF		0							N/A	N/A	N/A
1	B	Visiting Team Locker Room	N/A	Concrete Ceiling		Non Suspect ACM	200	SF		0							N/A	N/A	N/A
1	B	Visiting Team Locker Room	N/A	Concrete Block Wall		Non Suspect ACM	200	SF		0							N/A	N/A	N/A
1	B	Visiting Team Locker Room Restroom	N/A	Cement Floor		Non Suspect ACM	200	SF		0							N/A	N/A	N/A
1	B	Visiting Team Locker Room Restroom	N/A	Ceramic Tile Walls		Non Suspect ACM	200	SF		0							N/A	N/A	N/A
1	B	Visiting Team Locker Room Restroom	N/A	Concrete Ceiling		Non Suspect ACM	200	SF		0							N/A	N/A	N/A
1	B	Visiting Team Locker Room Restroom	T	Pipe Fitting Insulation	6050/01/0B/11	Confirmed	2	EA		0							1	No	1/D
1	B	Visiting Team Locker Room Restroom	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	5	LF		0							N/A	N/A	N/A
1	B	Girl's Showers	T	Pipe Fitting Insulation	6050/01/0B/11	Confirmed	51	EA		0							1	No	1/D
1	B	Girl's Showers	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	200	LF		0							N/A	N/A	N/A
1	B	Girl's Showers	T	Pipe Insulation 2-6 inch	6050/01/0B/MM	Confirmed	100	LF		0							1	No	1/D
1	B	Girl's Showers	N/A	Cement Floor		Non Suspect ACM	2000	SF		0							N/A	N/A	N/A
1	B	Girl's Showers	N/A	Ceramic Tile Walls		Non Suspect ACM	2000	SF		0							N/A	N/A	N/A
1	B	Girl's Showers	N/A	Concrete Ceiling		Non Suspect ACM	2000	SF		0							N/A	N/A	N/A
1	B	Girl's Showers	N/A	Stone Stalls		Non Suspect ACM	1000	SF		0							N/A	N/A	N/A
1	B	Hallway to the north of the Showers	M	Floor Tile VAT 9" x 9"	6050/01/0B/13	Confirmed	700	SF		0				Tan			1	No	1/D
1	B	Hallway to the north of the Showers	N/A	Ceiling Tile 1' x 1'		NAD	700	SF		0							N/A	N/A	N/A
1	B	Hallway to the north of the Showers	N/A	Ceramic Tile Walls		Non Suspect ACM	800	SF		0							N/A	N/A	N/A
1	B	Hallway from the Elevator leading into the Operations/Building Engineer's Area	N/A	Cement Floor		Non Suspect ACM	400	SF		0							N/A	N/A	N/A
1	B	Hallway from the Elevator leading into the Operations/Building Engineer's Area	N/A	Concrete Ceiling		Non Suspect ACM	400	SF		0							N/A	N/A	N/A
1	B	Hallway from the Elevator leading into the Operations/Building Engineer's Area	N/A	Concrete Block Wall		Non Suspect ACM	400	SF		0							N/A	N/A	N/A
1	B	Stairs at the Operations Hallway across from the Elevator	N/A	Cement Floor		Non Suspect ACM	200	SF		0							N/A	N/A	N/A
1	B	Stairs at the Operations Hallway across from the Elevator	N/A	Ceramic Tile Walls		Non Suspect ACM	200	SF		0							N/A	N/A	N/A
1	B	Stairs at the Operations Hallway across from the Elevator	N/A	Concrete Ceiling		Non Suspect ACM	200	SF		0							N/A	N/A	N/A
1	B	Custodial Supervisor Office	N/A	Cement Floor		Non Suspect ACM	500	SF		0							N/A	N/A	N/A
1	B	Custodial Supervisor Office	N/A	Concrete Block Wall		Non Suspect ACM	500	SF		0							N/A	N/A	N/A
1	B	Custodial Supervisor Office	N/A	Concrete Ceiling		Non Suspect ACM	500	SF		0							N/A	N/A	N/A
1	B	Custodial Supervisor Office	T	Pipe Fitting Insulation	6050/01/0B/11	Confirmed	29	EA		0							1	No	1/D
1	B	Custodial Supervisor Office	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	80	LF		0							N/A	N/A	N/A
1	B	Custodial Office across Custodial Supervisor Office	N/A	Cement Floor		Non Suspect ACM	400	SF		0							N/A	N/A	N/A
1	B	Custodial Office across Custodial Supervisor Office	N/A	Concrete Ceiling		Non Suspect ACM	400	SF		0							N/A	N/A	N/A
1	B	Custodial Office across Custodial Supervisor Office	N/A	Concrete Block Wall		Non Suspect ACM	400	SF		0							N/A	N/A	N/A
1	B	Custodial Office across Custodial Supervisor Office	T	Pipe Fitting Insulation	6050/01/0B/11	Confirmed	12	EA		0							1	No	1/D
1	B	Custodial Office across Custodial Supervisor Office	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	100	LF		0							N/A	N/A	N/A
1	B	Building Engineer's Office behind the Elevator	N/A	Cement Floor		Non Suspect ACM	200	SF		0							N/A	N/A	N/A
1	B	Building Engineer's Office behind the Elevator	N/A	Concrete Ceiling		Non Suspect ACM	200	SF		0							N/A	N/A	N/A
1	B	Building Engineer's Office behind the Elevator	N/A	Concrete Block Wall		Non Suspect ACM	400	SF		0							N/A	N/A	N/A
1	B	Building Engineer's Office behind the Elevator	T	Pipe Fitting Insulation	6050/01/0B/11	Confirmed	12	EA		0							1	No	1/D
1	B	Building Engineer's Office behind the Elevator	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	40	LF		0							N/A	N/A	N/A
1	B	Custodial Office Restroom	N/A	Cement Floor		Non Suspect ACM	100	SF		0							N/A	N/A	N/A
1	B	Custodial Office Restroom	N/A	Concrete Ceiling		Non Suspect ACM	100	SF		0							N/A	N/A	N/A
1	B	Custodial Office Restroom	N/A	Ceramic Tile Walls		Non Suspect ACM	100	SF		0							N/A	N/A	N/A
1	B	Custodial Office Restroom	T	Pipe Fitting Insulation	6050/01/0B/11	Confirmed	2	EA		0							1	No	1/D
1	B	Custodial Office Restroom	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	20	LF		0							N/A	N/A	N/A
1	B	Hallway/Area leading to the Loading Dock	N/A	Cement Floor		Non Suspect ACM	500	SF		0							N/A	N/A	N/A
1	B	Hallway/Area leading to the Loading Dock	N/A	Concrete Block Wall		Non Suspect ACM	500	SF		0							N/A	N/A	N/A
1	B	Hallway/Area leading to the Loading Dock	N/A	Concrete Ceiling		Non Suspect ACM	500	SF		0							N/A	N/A	N/A
1	B	Hallway/Area leading to the Loading Dock	T	Pipe Fitting Insulation	6050/01/0B/11	Confirmed	4	EA		0							1	No	1/D
1	B	Hallway/Area leading to the Loading Dock	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	80	LF		0							N/A	N/A	N/A
1	B	Hallway/Area leading to the Loading Dock	M	Vibration Damper Cloth	6050/01/0B/12	Assumed	2	EA		0							1	No	1/D

6050 Philadelphia High School for Girls 2015-2016 AHERA Three-Year Report.xls

School District of Philadelphia		AHERA Three-Year Reinspection 2015-2016 Room by Room Location Log Report										Reinspection Date: 1/7/2016							
												Building Inspector: Alex Roman							
																Certification Number: EHSBIR-150619-008			
																Management Planner: Monique Causley			
																ULCS# 6050			
Element	Room	On Site Room Name	System Affected	Material Description	HID#	Confirmed, Assumed, NAD, Non Suspect ACM	Amount of Material	SF LF EA	Amount of Damage	SF LF EA	Color required for VAT	Comments/Description/Notes	Attic Crawlspace Ranking	Damage Potential (DP)	Newly Friable (NF)	Response Action (RA)			
1	B	Loading Dock	N/A	Cement Floor		Non Suspect ACM	800	SF	0						N/A	N/A	N/A		
1	B	Loading Dock	N/A	Concrete Block Wall		Non Suspect ACM	800	SF	0						N/A	N/A	N/A		
1	B	Loading Dock	N/A	Concrete Ceiling		Non Suspect ACM	800	SF	0						N/A	N/A	N/A		
1	B	Loading Dock	T	Pipe Fitting Insulation	6050/01/0B/11	Confirmed	31	EA	1		EA		New damage. DDC written up/fill in addition damage material information for Confirmed materials		1	Yes	5/C		
1	B	Loading Dock	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	200	LF	6		LF				N/A	N/A	N/A		
1	B	Receiving	N/A	Cement Floor		Non Suspect ACM	800	SF	0				No access during Summer inspection		N/A	N/A	N/A		
1	B	Receiving	N/A	Concrete Ceiling		Non Suspect ACM	800	SF	0						N/A	N/A	N/A		
1	B	Receiving	N/A	Concrete Block Wall		Non Suspect ACM	800	SF	0						N/A	N/A	N/A		
1	B	Receiving	T	Pipe Fitting Insulation	6050/01/0B/11	Confirmed	36	EA	0						1	No	1/D		
1	B	Receiving	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	200	LF	0						N/A	N/A	N/A		
1	B	Housekeeping	N/A	Cement Floor		Non Suspect ACM	300	SF	0						N/A	N/A	N/A		
1	B	Housekeeping	N/A	Concrete Ceiling		Non Suspect ACM	300	SF	0						N/A	N/A	N/A		
1	B	Housekeeping	N/A	Concrete Block Wall		Non Suspect ACM	300	SF	0						N/A	N/A	N/A		
1	B	Housekeeping	T	Pipe Fitting Insulation	6050/01/0B/11	Confirmed	2	EA	0						1	No	1/D		
1	B	Housekeeping	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	30	LF	0						N/A	N/A	N/A		
1	B	Woman's Restroom next to House Keeping	N/A	Cement Floor		Non Suspect ACM	200	SF	0						N/A	N/A	N/A		
1	B	Woman's Restroom next to House Keeping	N/A	Ceramic Tile Walls		Non Suspect ACM	400	SF	0						N/A	N/A	N/A		
1	B	Woman's Restroom next to House Keeping	N/A	Concrete Ceiling		Non Suspect ACM	200	SF	0						N/A	N/A	N/A		
1	B	Woman's Restroom next to House Keeping	T	Pipe Fitting Insulation	6050/01/0B/11	Confirmed	18	EA	0						1	No	1/D		
1	B	Woman's Restroom next to House Keeping	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	40	LF	0						N/A	N/A	N/A		
1	B	Women's Locker Room Lounge	N/A	Cement Floor		Non Suspect ACM	200	SF	0						N/A	N/A	N/A		
1	B	Women's Locker Room Lounge	N/A	Concrete Ceiling		Non Suspect ACM	200	SF	0						N/A	N/A	N/A		
1	B	Women's Locker Room Lounge	N/A	Ceramic Tile Walls		Non Suspect ACM	200	SF	0						N/A	N/A	N/A		
1	B	Women's Locker Room Lounge	T	Pipe Fitting Insulation	6050/01/0B/11	Confirmed	31	EA	0						1	No	1/D		
1	B	Women's Locker Room Lounge	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	150	LF	0						N/A	N/A	N/A		
1	B	Blower Room	N/A	Cement Floor		Non Suspect ACM	1000	SF	0						N/A	N/A	N/A		
1	B	Blower Room	N/A	Concrete Ceiling		Non Suspect ACM	1000	SF	0						N/A	N/A	N/A		
1	B	Blower Room	N/A	Concrete Block Wall		Non Suspect ACM	1200	SF	0						N/A	N/A	N/A		
1	B	Blower Room	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	200	LF	0						N/A	N/A	N/A		
1	B	Blower Room	M	Vibration Damper Cloth	6050/01/0B/12	Assumed	4	EA	0						1	No	1/D		
1	B	Blower Room	T	Tank Insulation	6050/01/0B/09	Confirmed	300	SF	0						1	No	1/D		
1	B	Blower Room	T	Pipe Fitting Insulation	6050/01/0B/11	Confirmed	50	EA	0						1	No	1/D		
1	B	Hallway in Operations area in front of Women's Restroom	N/A	Cement Floor		Non Suspect ACM	300	SF	0						N/A	N/A	N/A		
1	B	Hallway in Operations area in front of Women's Restroom	N/A	Concrete Block Wall		Non Suspect ACM	300	SF	0						N/A	N/A	N/A		
1	B	Hallway in Operations area in front of Women's Restroom	N/A	Concrete Ceiling		Non Suspect ACM	300	SF	0						N/A	N/A	N/A		
1	B	Hallway in Operations area in front of Women's Restroom	T	Pipe Fitting Insulation	6050/01/0B/11	Confirmed	16	EA	0						1	No	1/D		
1	B	Hallway in Operations area in front of Women's Restroom	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	80	LF	0						N/A	N/A	N/A		
1	B	Building Engineer's Office across from Woman's Restroom	N/A	Cement Floor		Non Suspect ACM	500	SF	0						N/A	N/A	N/A		
1	B	Building Engineer's Office across from Woman's Restroom	N/A	Concrete Ceiling		Non Suspect ACM	500	SF	0						N/A	N/A	N/A		
1	B	Building Engineer's Office across from Woman's Restroom	N/A	Concrete Block Wall		Non Suspect ACM	500	SF	0						N/A	N/A	N/A		
1	B	Building Engineer's Office across from Woman's Restroom	T	Pipe Fitting Insulation	6050/01/0B/11	Confirmed	53	EA	0						1	No	1/D		
1	B	Building Engineer's Office across from Woman's Restroom	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	300	LF	0						N/A	N/A	N/A		
1	B	Stairs leading from the Operations Area to the Kitchen	N/A	Cement Floor		Non Suspect ACM	200	SF	0						N/A	N/A	N/A		
1	B	Stairs leading from the Operations Area to the Kitchen	N/A	Ceramic Tile Walls		Non Suspect ACM	200	SF	0						N/A	N/A	N/A		
1	B	Stairs leading from the Operations Area to the Kitchen	N/A	Concrete Ceiling		Non Suspect ACM	200	SF	0						N/A	N/A	N/A		
1	B	Stairs leading from the Operations Area to the Kitchen	T	Pipe Fitting Insulation	6050/01/0B/11	Confirmed	12	EA	0						1	No	1/D		
1	B	Stairs leading from the Operations Area to the Kitchen	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	50	LF	0						N/A	N/A	N/A		
1	G	Classroom G12	N/A	Concrete Ceiling		Non Suspect ACM	800	SF	0						N/A	N/A	N/A		
1	G	Classroom G12	N/A	Concrete Block Wall		Non Suspect ACM	800	SF	0						N/A	N/A	N/A		
1	G	Classroom G12	M	Floor Tile VAT 9" x 9"	6050/01/0G/31	Confirmed	800	SF	0		Confirmed	Tan			1	No	1/D		
1	G	Classroom G12	T	Pipe Fitting Insulation	6050/01/GF/28	Confirmed	2	EA	0						1	No	1/D		
1	G	Classroom G12	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	10	LF	0						N/A	N/A	N/A		
1	G	Classroom G10	N/A	Concrete Ceiling		Non Suspect ACM	800	SF	0						N/A	N/A	N/A		
1	G	Classroom G10	N/A	Concrete Block Wall		Non Suspect ACM	800	SF	0						N/A	N/A	N/A		
1	G	Classroom G10	M	Floor Tile VAT 9" x 9"	6050/01/0G/31	Confirmed	800	SF	0			Tan			1	No	1/D		
1	G	Classroom G10	T	Pipe Fitting Insulation	6050/01/GF/28	Confirmed	10	EA	0						1	No	1/D		
1	G	Classroom G10	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	50	LF	0						N/A	N/A	N/A		

6050 Philadelphia High School for Girls 2015-2016 AHERA Three-Year Report.xls

Element		School District of Philadelphia		AHERA Three-Year Reinspection 2015-2016								Reinspection Date: 1/7/2016				
		Philadelphia High School For Girls		Room by Room Location Log Report								Building Inspector: Alex Roman				
		1400 W Olney Avenue										Certification Number: EHSBIR-150619-008				
		Philadelphia, PA 19141										Management Planner: Monique Causley				
		ULCS# 6050										Certification Number: ACC-0215-8-010				
		On Site Room Name	System Affected	Material Description	HID#	Confirmed, Assumed, NAD, Non Suspect ACM	Amount of Material	SF LF EA	Amount of Damage	SF LF EA	Color required for VAT	Comments/Description/Notes	Attic Crawlspace Ranking	Damage Potential (DP)	Newly Friable (NF)	Response Action (RA)
1	G	Classroom G017	N/A	Concrete Ceiling		Non Suspect ACM	800	SF	0					N/A	N/A	N/A
1	G	Classroom G017	N/A	Concrete Block Wall		Non Suspect ACM	800	SF	0					N/A	N/A	N/A
1	G	Classroom G017	M	Floor Tile VAT 9" x 9"	6050/01/0G/31	Confirmed	800	SF	0		Tan			1	No	1/D
1	G	Classroom G017	T	Pipe Fitting Insulation	6050/01/GF/28	Confirmed	21	EA	7	EA		Write DDC for this damage/fill in addition damage material information for Confirmed materials		2	Yes	5/A
1	G	Classroom G017	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	100	LF	0					N/A	N/A	N/A
1	G	Classroom G018	N/A	Concrete Ceiling		Non Suspect ACM	800	SF	0					N/A	N/A	N/A
1	G	Classroom G018	N/A	Concrete Block Wall		Non Suspect ACM	800	SF	0					N/A	N/A	N/A
1	G	Classroom G018	M	Floor Tile VAT 9" x 9"	6050/01/0G/31	Confirmed	800	SF	0		Tan			1	No	1/D
1	G	Classroom G018	T	Pipe Fitting Insulation	6050/01/GF/28	Confirmed	4	EA	0					1	No	1/D
1	G	Classroom G018	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	25	LF	0					N/A	N/A	N/A
1	G	Dance Studio Office	N/A	Concrete Ceiling		Non Suspect ACM	200	SF	0			No access during Summer inspection		N/A	N/A	N/A
1	G	Dance Studio Office	N/A	Concrete Block Wall		Non Suspect ACM	200	SF	0					N/A	N/A	N/A
1	G	Dance Studio Office	M	Floor Tile VAT 9" x 9"	6050/01/0G/31	Confirmed	200	SF	0		Grey			1	No	1/D
1	G	Dance Studio Closet	N/A	Cement Floor		Non Suspect ACM	200	SF	0			No access during Summer inspection		N/A	N/A	N/A
1	G	Dance Studio Closet	N/A	Concrete Ceiling		Non Suspect ACM	200	SF	0					N/A	N/A	N/A
1	G	Dance Studio Closet	N/A	Concrete Block Wall		Non Suspect ACM	200	SF	0					N/A	N/A	N/A
1	G	Dance Studio	N/A	Wood Floor		Non Suspect ACM	1200	SF	0					N/A	N/A	N/A
1	G	Dance Studio	N/A	Concrete Ceiling		Non Suspect ACM	1200	SF	0					N/A	N/A	N/A
1	G	Dance Studio	N/A	Concrete Block Wall		Non Suspect ACM	1500	SF	0					N/A	N/A	N/A
1	G	Dance Studio	T	Pipe Fitting Insulation	6050/01/GF/28	Confirmed	10	EA	0					1	No	1/D
1	G	Dance Studio	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	50	LF	0					N/A	N/A	N/A
1	G	Hallway at Classroom G12 to G18	M	Floor Tile VAT 9" x 9"	6050/01/0G/31	Confirmed	500	SF	0		Tan			1	No	1/D
1	G	Hallway at Classroom G12 to G18	N/A	Ceiling Tile 1' x 1'		NAD	500	SF	5	SF		Missing tiles exposing brown glue dots underneath		N/A	N/A	N/A
1	G	Hallway at Classroom G12 to G18	M	Spline Ceiling Tile Glue Dots	6050/01/0G/CR/IH/2604	Assumed	150	SF	0					1	No	1/D
1	G	Hallway at Classroom G12 to G18	N/A	Ceramic Tile Walls		Non Suspect ACM	500	SF	0					N/A	N/A	N/A
1	G	Hallway at Classroom G12 to G18	T	Pipe Fitting Insulation	6050/01/GF/28	Confirmed	12	EA	0					1	No	1/D
1	G	Hallway at Classroom G12 to G18	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	15	LF	0					N/A	N/A	N/A
1	G	Hallway at Closets Marked P.E. 1 and P 3	M	Floor Tile VAT 9" x 9"	6050/01/0G/31	Confirmed	400	SF	0		Green			1	No	1/D
1	G	Hallway at Closets Marked P.E. 1 and P 3	N/A	Ceiling Tile 1' x 1'		NAD	400	SF	2	SF		Missing tiles exposing brown glue dots underneath		N/A	N/A	N/A
1	G	Hallway at Closets Marked P.E. 1 and P 3	M	Spline Ceiling Tile Glue Dots	6050/01/0G/CR/IH/2604	Assumed	100	SF	0					1	No	1/D
1	G	Hallway at Closets Marked P.E. 1 and P 3	N/A	Concrete Block Wall		Non Suspect ACM	400	SF	0					N/A	N/A	N/A
1	G	Classroom G015 Robotics Lab	M	Floor Tile VAT 9" x 9"	6050/01/0G/31	Confirmed	800	SF	0		Tan	No access during Summer inspection		1	No	1/D
1	G	Classroom G015 Robotics Lab	N/A	Concrete Ceiling		Non Suspect ACM	800	SF	0					N/A	N/A	N/A
1	G	Classroom G015 Robotics Lab	N/A	Concrete Block Wall		Non Suspect ACM	1200	SF	0					N/A	N/A	N/A
1	G	Classroom G015 Robotics Lab Closet #1	M	Floor Tile VAT 9" x 9"	6050/01/0G/31	Confirmed	100	SF	0		Tan			1	No	1/D
1	G	Classroom G015 Robotics Lab Closet #1	N/A	Concrete Ceiling		Non Suspect ACM	100	SF	0					N/A	N/A	N/A
1	G	Classroom G015 Robotics Lab Closet #1	N/A	Concrete Block Wall		Non Suspect ACM	100	SF	0					N/A	N/A	N/A
1	G	Classroom G015 Robotics Lab Closet #2	M	Floor Tile VAT 9" x 9"	6050/01/0G/31	Confirmed	100	SF	0		Tan			1	No	1/D
1	G	Classroom G015 Robotics Lab Closet #2	N/A	Concrete Ceiling		Non Suspect ACM	100	SF	0					N/A	N/A	N/A
1	G	Classroom G015 Robotics Lab Closet #2	N/A	Concrete Block Wall		Non Suspect ACM	100	SF	0					N/A	N/A	N/A
1	G	Classroom G015 Robotics Lab Closet #3	M	Floor Tile VAT 9" x 9"	6050/01/0G/31	Confirmed	100	SF	0		Tan			1	No	1/D
1	G	Classroom G015 Robotics Lab Closet #3	N/A	Concrete Ceiling		Non Suspect ACM	100	SF	0					N/A	N/A	N/A
1	G	Classroom G015 Robotics Lab Closet #3	N/A	Concrete Block Wall		Non Suspect ACM	100	SF	0					N/A	N/A	N/A
1	G	Classroom G015 Robotics Lab Closet #4	M	Floor Tile VAT 9" x 9"	6050/01/0G/31	Confirmed	100	SF	0		Tan			1	No	1/D
1	G	Classroom G015 Robotics Lab Closet #4	N/A	Concrete Ceiling		Non Suspect ACM	100	SF	0					N/A	N/A	N/A
1	G	Classroom G015 Robotics Lab Closet #4	N/A	Concrete Block Wall		Non Suspect ACM	100	SF	0					N/A	N/A	N/A
1	G	Classroom G015 Robotics Lab Closet #4	T	Pipe Fitting Insulation	6050/01/GF/28	Confirmed	4	EA	0					1	No	1/D
1	G	Classroom G015 Robotics Lab Closet #4	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	10	LF	0					N/A	N/A	N/A
1	G	Classroom G015 Robotics Lab Closet #5	M	Floor Tile VAT 9" x 9"	6050/01/0G/31	Confirmed	100	SF	0		Tan			1	No	1/D
1	G	Classroom G015 Robotics Lab Closet #5	N/A	Concrete Ceiling		Non Suspect ACM	100	SF	0					N/A	N/A	N/A
1	G	Classroom G015 Robotics Lab Closet #5	N/A	Concrete Block Wall		Non Suspect ACM	100	SF	0					N/A	N/A	N/A
1	G	Classroom G015 Robotics Lab Gated Closet	M	Floor Tile VAT 9" x 9"	6050/01/0G/31	Confirmed	100	SF	0		Tan			1	No	1/D
1	G	Classroom G015 Robotics Lab Gated Closet	N/A	Concrete Ceiling		Non Suspect ACM	100	SF	0					N/A	N/A	N/A
1	G	Classroom G015 Robotics Lab Gated Closet	N/A	Concrete Block Wall		Non Suspect ACM	100	SF	0					N/A	N/A	N/A
1	G	Classroom G015 Robotics Lab Gated Closet	T	Pipe Fitting Insulation	6050/01/GF/28	Confirmed	14	EA	0					1	No	1/D
1	G	Classroom G015 Robotics Lab Gated Closet	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	60	LF	0					N/A	N/A	N/A
1	G	Stairs next to G13	N/A	Cement Floor		Non Suspect ACM	200	SF	0					N/A	N/A	N/A
1	G	Stairs next to G13	N/A	Concrete Ceiling		Non Suspect ACM	200	SF	0					N/A	N/A	N/A
1	G	Stairs next to G13	N/A	Ceramic Tile Walls		Non Suspect ACM	200	SF	0					N/A	N/A	N/A
1	G	Yearbook Room G21	M	Floor Tile VAT 9" x 9"	6050/01/0G/31	Confirmed	500	SF	0		Tan			1	No	1/D
1	G	Yearbook Room G21	N/A	Concrete Ceiling		Non Suspect ACM	500	SF	0					N/A	N/A	N/A
1	G	Yearbook Room G21	N/A	Concrete Block Wall		Non Suspect ACM	500	SF	0					N/A	N/A	N/A
1	G	Yearbook Room G21	T	Pipe Fitting Insulation	6050/01/GF/28	Confirmed	9	EA	0					1	No	1/D

6050 Philadelphia High School for Girls 2015-2016 AHERA Three-Year Report.xls

		School District of Philadelphia		AHERA Three-Year Reinspection 2015-2016									Reinspection Date: 1/7/2016			
		Philadelphia High School For Girls		Room by Room Location Log Report									Building Inspector: Alex Roman			
		1400 W Olney Avenue											Certification Number: EHSBIR-150619-008			
		Philadelphia, PA 19141											Management Planner: Monique Causley			
		ULCS# 6050											Certification Number: ACC-0215-8-010			
Element	Room	On Site Room Name	System Affected	Material Description	HID#	Confirmed, Assumed, NAD, Non Suspect ACM	Amount of Material	SF LF EA	Amount of Damage	SF LF EA	Color required for VAT	Comments/Description/Notes	Attic Crawlspace Ranking	Damage Potential (DP)	Newly Friable (NF)	Response Action (RA)
1	G	Yearbook Room G21	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	30	LF	0					N/A	N/A	N/A
1	G	Stairs that lead down into the Yearbook Room	N/A	Cement Floor		Non Suspect ACM	100	SF	0					N/A	N/A	N/A
1	G	Stairs # 5	N/A	Cement Floor		Non Suspect ACM	200	SF	0					N/A	N/A	N/A
1	G	Stairs # 5	N/A	Concrete Ceiling		Non Suspect ACM	200	SF	0					N/A	N/A	N/A
1	G	Stairs # 5	N/A	Ceramic Tile Walls		Non Suspect ACM	200	SF	0					N/A	N/A	N/A
1	G	Dance Studio Locker Room	N/A	Cement Floor		Non Suspect ACM	300	SF	0					N/A	N/A	N/A
1	G	Dance Studio Locker Room	N/A	Concrete Ceiling		Non Suspect ACM	300	SF	0					N/A	N/A	N/A
1	G	Dance Studio Locker Room	N/A	Concrete Block Wall		Non Suspect ACM	300	SF	0					N/A	N/A	N/A
1	G	Dance Studio Locker Room	T	Pipe Fitting Insulation	6050/01/GF/28	Confirmed	12	EA	0					1	No	1/D
1	G	Dance Studio Locker Room	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	25	LF	0					N/A	N/A	N/A
1	G	Hallway from Stairs #5 to Cafeteria	M	Floor Tile VAT 9" x 9"	6050/01/0G/31	Confirmed	800	SF	0		Tan			1	No	1/D
1	G	Hallway from Stairs #5 to Cafeteria	N/A	Ceiling Tile 1' x 1'		NAD	800	SF	5		SF	Missing tiles exposing brown glue dots underneath		N/A	N/A	N/A
1	G	Hallway from Stairs #5 to Cafeteria	M	Spline Ceiling Tile Glue Dots	6050/01/0G/CR/H/2604	Assumed	200	SF	0					1	No	1/D
1	G	Hallway from Stairs #5 to Cafeteria	N/A	Ceramic Tile Walls		Non Suspect ACM	800	SF	0					N/A	N/A	N/A
1	G	G013	M	Floor Tile VAT 9" x 9"	6050/01/0G/31	Confirmed	400	SF	0		Tan			1	No	1/D
1	G	G013	N/A	Concrete Ceiling		Non Suspect ACM	400	SF	0					N/A	N/A	N/A
1	G	G013	N/A	Concrete Block Wall		Non Suspect ACM	600	SF	0					N/A	N/A	N/A
1	G	G013	T	Pipe Fitting Insulation	6050/01/GF/28	Confirmed	14	EA	0					1	No	1/D
1	G	G013	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	80	LF	0					N/A	N/A	N/A
1	G	G9/G11	M	Floor Tile VAT 12" x 12"	6050/01/0G/VER/AR/2000	Assumed	800	SF	0		Tan			1	No	1/D
1	G	G9/G11	N/A	Concrete Ceiling		Non Suspect ACM	800	SF	0					N/A	N/A	N/A
1	G	G9/G11	N/A	Concrete Block Wall		Non Suspect ACM	1200	SF	0					N/A	N/A	N/A
1	G	G9/G11	T	Pipe Fitting Insulation	6050/01/GF/28	Confirmed	4	EA	0					1	No	1/D
1	G	G9/G11	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	10	LF	0					N/A	N/A	N/A
1	G	Stairs #3	N/A	Cement Floor		Non Suspect ACM	200	SF	0					N/A	N/A	N/A
1	G	Stairs #3	N/A	Ceramic Tile Walls		Non Suspect ACM	200	SF	0					N/A	N/A	N/A
1	G	Stairs #3	N/A	Concrete Ceiling		Non Suspect ACM	200	SF	0					N/A	N/A	N/A
1	G	Stairs #3	T	Radiator Insulation	6050/01/0G/CR/AR/1600	Assumed	1	EA	0					1	No	1/D
1	G	Room G6 School Store	M	Floor Tile VAT 9" x 9"	6050/01/0G/31	Confirmed	800	SF	0		Grey			1	No	1/D
1	G	Room G6 School Store	N/A	Concrete Ceiling		Non Suspect ACM	800	SF	0					N/A	N/A	N/A
1	G	Room G6 School Store	N/A	Concrete Block Wall		Non Suspect ACM	800	SF	0					N/A	N/A	N/A
1	G	Room G6 School Store	T	Pipe Fitting Insulation	6050/01/GF/28	Confirmed	12	EA	0					1	No	1/D
1	G	Room G6 School Store	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	80	LF	0					N/A	N/A	N/A
1	G	G31 Lounge	M	Floor Tile VAT 9" x 9"	6050/01/0G/31	Confirmed	300	SF	0		Tan			1	No	1/D
1	G	G31 Lounge	N/A	Concrete Ceiling		Non Suspect ACM	300	SF	0					N/A	N/A	N/A
1	G	G31 Lounge	N/A	Concrete Block Wall		Non Suspect ACM	300	SF	0					N/A	N/A	N/A
1	G	Restroom next to G31	N/A	Cement Floor		Non Suspect ACM	200	SF	0					N/A	N/A	N/A
1	G	Restroom next to G31	N/A	Concrete Ceiling		Non Suspect ACM	200	SF	0					N/A	N/A	N/A
1	G	Restroom next to G31	N/A	Ceramic Tile Walls		Non Suspect ACM	200	SF	0					N/A	N/A	N/A
1	G	Storage Closet in front of G31	X	X	X	X	X	X	X	X	X			X	X	X
1	G	Girl's Restroom across from Stairs #3	N/A	Ceramic Tile Walls		Non Suspect ACM	300	SF	0					N/A	N/A	N/A
1	G	Girl's Restroom across from Stairs #3	N/A	Cement Floor		Non Suspect ACM	200	SF	0					N/A	N/A	N/A
1	G	Girl's Restroom across from Stairs #3	N/A	Concrete Ceiling		Non Suspect ACM	200	SF	0					N/A	N/A	N/A
1	G	Girl's Restroom across from Stairs #3	T	Pipe Fitting Insulation	6050/01/GF/28	Confirmed	6	EA	0					1	No	1/D
1	G	Girl's Restroom across from Stairs #3	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	20	LF	0					N/A	N/A	N/A
1	G	School Police Office in Cafeteria	M	Floor Tile VAT 9" x 9"	6050/01/0G/31	Confirmed	200	SF	0		Green			1	No	1/D
1	G	School Police Office in Cafeteria	T	Pipe Fitting Insulation	6050/01/GF/28	Confirmed	3	EA	0					1	No	1/D
1	G	School Police Office in Cafeteria	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	30	LF	0					N/A	N/A	N/A
1	G	School Police Office in Cafeteria	N/A	Ceramic Tile Walls		Non Suspect ACM	200	SF	0					N/A	N/A	N/A
1	G	School Police Office in Cafeteria	N/A	Concrete Ceiling		Non Suspect ACM	200	SF	0					N/A	N/A	N/A
1	G	School Police Office in Cafeteria	M	Vibration Damper Cloth	6050/01/0G/33	Assumed	2	EA	0					1	No	1/D
1	G	Staff Dining Lounge	M	Floor Tile VAT 9" x 9"	6050/01/0G/31	Confirmed	900	SF	0		Green			1	No	1/D
1	G	Staff Dining Lounge	M	Ceiling Tile 1' x 4'	6050/01/0G/VER/AR/1709	Assumed	900	SF	0					1	No	1/D
1	G	Staff Dining Lounge	N/A	Ceramic Tile Walls		Non Suspect ACM	1200	SF	0					N/A	N/A	N/A
1	G	Staff Dining Lounge	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	60	LF	0					N/A	N/A	N/A
1	G	Cafeteria	M	Floor Tile VAT 9" x 9"	6050/01/0G/31	Confirmed	2000	SF	0		Green			1	No	1/D
1	G	Cafeteria	N/A	Ceramic Tile Walls		Non Suspect ACM	2000	SF	0					N/A	N/A	N/A
1	G	Cafeteria	M	Ceiling Tile 1' x 4'	6050/01/0G/VER/AR/1709	Assumed	2000	SF	0					1	No	1/D
1	G	Cafeteria	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	60	LF	0					N/A	N/A	N/A
1	G	Cafeteria	T	Pipe Fitting Insulation	6050/01/GF/28	Confirmed	7	EA	0					1	No	1/D
1	G	Staff Locker Room in Cafeteria	N/A	Ceramic Tile Walls		Non Suspect ACM	350	SF	0					N/A	N/A	N/A
1	G	Staff Locker Room in Cafeteria	N/A	Concrete Ceiling		Non Suspect ACM	200	SF	0					N/A	N/A	N/A
1	G	Staff Locker Room in Cafeteria	M	Vibration Damper Cloth	6050/01/0G/33	Assumed	2	EA	0					1	No	1/D
1	G	Staff Locker Room in Cafeteria	M	Floor Tile VAT 9" x 9"	6050/01/0G/31	Confirmed	200	SF	0		Green			1	No	1/D
1	G	Cafeteria Serving area	M	Floor Tile VAT 12" x 12"	6050/01/0G/VER/AR/2009	Assumed	1200	SF	0		Green			1	No	1/D

6050 Philadelphia High School for Girls 2015-2016 AHERA Three-Year Report.xls

School District of Philadelphia		AHERA Three-Year Reinspection 2015-2016 Room by Room Location Log Report										Reinspection Date: 1/7/2016																			
												Building Inspector: Alex Roman																			
												Certification Number: EHSBIR-150619-008																			
																Management Planner: Monique Causley															
																				Certification Number: ACC-0215-8-010											
Philadelphia High School For Girls		1400 W Olney Avenue		Philadelphia, PA 19141		ULCS# 6050																									
Element	Room	On Site Room Name		System Affected		Material Description		HID#		Confirmed, Assumed, NAD, Non Suspect ACM		Amount of Material		SF LF EA		Amount of Damage		SF LF EA		Color required for VAT		Comments/Description/Notes		Attic Crawlspace Ranking		Damage Potential (DP)		Newly Friable (NF)		Response Action (RA)	
1	G	Cafeteria Serving area		N/A		Ceramic Tile Walls				Non Suspect ACM		1200	SF		0											N/A		N/A	N/A		
1	G	Cafeteria Serving area		M		Ceiling Tile 1" x 4'		6050/01/0G/VER/AR/1709		Assumed		1200	SF		0											1	No		1/D		
1	G	Walk- In Freezer Room		N/A		Ceramic Tile Walls				Non Suspect ACM		500	SF		0											N/A		N/A	N/A		
1	G	Walk- In Freezer Room		N/A		Ceramic Tile Floors				Non Suspect ACM		500	SF		0											N/A		N/A	N/A		
1	G	Walk- In Freezer Room		N/A		Concrete Ceiling				Non Suspect ACM		500	SF		0											1	No		1/D		
1	G	Walk- In Freezer Room		T		Pipe Fitting Insulation		6050/01/GF/28		Confirmed		20	EA		0											1	No		1/D		
1	G	Walk- In Freezer Room		N/A		Fiberglass Pipe Insulation				Non Suspect ACM		80	LF		0											N/A		N/A	N/A		
1	G	Former Kitchen Office		N/A		Ceramic Tile Floors				Non Suspect ACM		400	SF		0											N/A		N/A	N/A		
1	G	Former Kitchen Office		N/A		Ceramic Tile Walls				Non Suspect ACM		400	SF		0											N/A		N/A	N/A		
1	G	Former Kitchen Office		N/A		Concrete Ceiling				Non Suspect ACM		400	SF		0											N/A		N/A	N/A		
1	G	Former Kitchen Office		N/A		Fiberglass Pipe Insulation				Non Suspect ACM		2	LF		0											N/A		N/A	N/A		
1	G	Former Kitchen Office		T		Pipe Fitting Insulation		6050/01/GF/28		Confirmed		10	EA		0											1	No		1/D		
1	G	Kitchen Office Restroom		N/A		Ceramic Tile Floors				Non Suspect ACM		100	SF		0											N/A		N/A	N/A		
1	G	Kitchen Office Restroom		N/A		Ceramic Tile Walls				Non Suspect ACM		100	SF		0											N/A		N/A	N/A		
1	G	Kitchen Office Restroom		N/A		Concrete Ceiling				Non Suspect ACM		100	SF		0											N/A		N/A	N/A		
1	G	Kitchen Office Safe Room		N/A		Ceramic Tile Floors				Non Suspect ACM		100	SF		0											N/A		N/A	N/A		
1	G	Kitchen Office Safe Room		N/A		Ceramic Tile Walls				Non Suspect ACM		100	SF		0											N/A		N/A	N/A		
1	G	Kitchen Office Safe Room		N/A		Concrete Ceiling				Non Suspect ACM		100	SF		0											N/A		N/A	N/A		
1	G	Main Kitchen		N/A		Terra Cotta Tile Walls				Non Suspect ACM		2000	SF		0					Red						N/A		N/A	N/A		
1	G	Main Kitchen		N/A		Ceramic Tile Floors				Non Suspect ACM		2000	SF		0											N/A		N/A	N/A		
1	G	Main Kitchen		N/A		Concrete Ceiling				Non Suspect ACM		2000	SF		0											N/A		N/A	N/A		
1	G	Main Kitchen		T		Pipe Fitting Insulation		6050/01/GF/28		Confirmed		72	EA		0											1	No		1/D		
1	G	Main Kitchen		T		Pipe Insulation 2-6 inch		6050/01/GF/PP		Confirmed		200	LF		0											1	No		1/D		
1	G	Kitchen Store Room		N/A		Ceramic Tile Walls				Non Suspect ACM		200	SF		0											N/A		N/A	N/A		
1	G	Kitchen Store Room		N/A		Ceramic Tile Floors				Non Suspect ACM		200	SF		0											N/A		N/A	N/A		
1	G	Kitchen Store Room		N/A		Concrete Ceiling				Non Suspect ACM		200	SF		0											N/A		N/A	N/A		
1	G	Kitchen Store Room		T		Pipe Fitting Insulation		6050/01/GF/28		Confirmed		40	EA		0											1	No		1/D		
1	G	Kitchen Store Room		T		Pipe Insulation 2-6 inch		6050/01/GF/PP		Confirmed		40	LF		0											1	No		1/D		
1	G	Operations Area		N/A		Ceramic Tile Walls				Non Suspect ACM		120	SF		0											N/A		N/A	N/A		
1	G	Kitchen Storage near the Stairs to the Basement Operations Area		N/A		Ceramic Tile Floors				Non Suspect ACM		120	SF		0												N/A		N/A	N/A	
1	G	Kitchen Storage near the Stairs to the Basement Operations Area		N/A		Ceiling Tile 2' x 4'				Non Suspect ACM		120	SF		0												N/A		N/A	N/A	
1	G	Kitchen Stairs leading to Operations Area in Basement		X		X		X		X		X	X		X					X						X	X		X		
1	G	Hallway/Foyer at the north end of the Gymnasiums		N/A		Cement Floor				Non Suspect ACM		400	SF		0												N/A		N/A	N/A	
1	G	Hallway/Foyer at the north end of the Gymnasiums		N/A		Concrete Ceiling				Non Suspect ACM		400	SF		0												N/A		N/A	N/A	
1	G	Hallway/Foyer at the north end of the Gymnasiums		N/A		Ceramic Tile Walls				Non Suspect ACM		400	SF		0												N/A		N/A	N/A	
1	G	Hallway/Foyer at the north end of the Gymnasiums		T		Radiator Insulation		6050/01/0G/CRI/AR/1600		Assumed		2	EA		0											1	No		1/D		
1	G	Girl's Restroom across Stairs #2		N/A		Cement Floor				Non Suspect ACM		300	SF		0												N/A		N/A	N/A	
1	G	Girl's Restroom across Stairs #2		N/A		Ceramic Tile Walls				Non Suspect ACM		300	SF		0												N/A		N/A	N/A	
1	G	Girl's Restroom across Stairs #2		N/A		Concrete Block Wall				Non Suspect ACM		300	SF		0												N/A		N/A	N/A	
1	G	Girl's Restroom across Stairs #2		N/A		Fiberglass Pipe Insulation				Non Suspect ACM		20	LF		0												N/A		N/A	N/A	
1	G	Girl's Restroom across Stairs #2		T		Pipe Fitting Insulation		6050/01/GF/28		Confirmed		3	EA		0											1	No		1/D		
1	G	Music Room Storage next to Girl's Restroom across from Stair #2		X		X		X		X		X	X		X											X	X		X		
1	G	Weight Room		M		Floor Tile VAT 9" x 9"		6050/01/0G/31		Confirmed		800	SF		0					Tan						1	No		1/D		
1	G	Weight Room		N/A		Ceiling Tile 2' x 4'				Non Suspect ACM		800	SF		0												N/A		N/A	N/A	
1	G	Weight Room		N/A		Concrete Block Wall				Non Suspect ACM		800	SF		0												N/A		N/A	N/A	
1	G	Weight Room		T		Pipe Fitting Insulation		6050/01/GF/28		Confirmed		20	EA		0											1	No		1/D		
1	G	Weight Room		N/A		Fiberglass Pipe Insulation				Non Suspect ACM		120	LF		0												N/A		N/A	N/A	
1	G	Art Storage area across Weight Room (all Rooms area connected and have partition room dividers)		T		Pipe Fitting Insulation		6050/01/GF/28		Confirmed		28	EA		0											1	No		1/D		
1	G	Art Storage area across Weight Room (all Rooms area connected and have partition room dividers)		N/A		Fiberglass Pipe Insulation				Non Suspect ACM		150	LF		0												N/A		N/A	N/A	
1	G	Art Storage area across Weight Room (all Rooms area connected and have partition room dividers)		M		Floor Tile VAT 9" x 9"		6050/01/0G/31		Confirmed		1200	SF		0					Tan						1	No		1/D		
1	G	Art Storage area across Weight Room (all Rooms area connected and have partition room dividers)		N/A		Ceiling Tile 2' x 4'				Non Suspect ACM		1200	SF		0												N/A		N/A	N/A	
1	G	Teacher's Conference Suite across the Hall from G1		M		Floor Tile VAT 9" x 9"		6050/01/0G/31		Confirmed		1200	SF		0					Green						1	No		1/D		
1	G	Teacher's Conference Suite across the Hall from G1		N/A		Concrete Ceiling				Non Suspect ACM		1200	SF		0												N/A		N/A	N/A	
1	G	Teacher's Conference Suite across the Hall from G1		N/A		Concrete Block Wall				Non Suspect ACM		1200	SF		0												N/A		N/A	N/A	
1	G	Teacher's Conference Suite across the Hall from G1		M		Floor Tile VAT 9" x 9"		6050/01/0G/31		Confirmed		100	SF		0					Tan						1	No		1/D		
1	G	Closet nearest to the entrance		N/A		Teacher's Conference Suite across the Hall from G1				Non Suspect ACM		100	SF		0												N/A		N/A	N/A	
1	G	Closet nearest to the entrance		N/A		Concrete Block Wall				Non Suspect ACM		100	SF		0												N/A		N/A	N/A	
1	G	Teacher's Conference Suite across the Hall from G1		N/A		Concrete Ceiling				Non Suspect ACM		100	SF		0												N/A		N/A	N/A	

6050 Philadelphia High School for Girls 2015-2016 AHERA Three-Year Report.xls

		School District of Philadelphia		AHERA Three-Year Reinspection 2015-2016 Room by Room Location Log Report						Reinspection Date: 1/7/2016 Building Inspector: Alex Roman Certification Number: EHSBIR-150619-008 Management Planner: Monique Causley Certification Number: ACC-0215-8-010						
		Philadelphia High School For Girls 1400 W Olney Avenue Philadelphia, PA 19141 ULCS# 6050														
Element	Room	On Site Room Name	System Affected	Material Description	HID#	Confirmed, Assumed, NAD, Non Suspect ACM	Amount of Material	SF LF EA	Amount of Damage	SF LF EA	Color required for VAT	Comments/Description/Notes	Attic Crawlspace Ranking	Damage Potential (DP)	Newly Friable (NF)	Response Action (RA)
1	G	Teacher's Conference Suite across the Hall from G1 Closet second nearest to the entrance	M	Floor Tile VAT 9" x 9"	6050/01/0G/31	Confirmed	100	SF	0		Tan			1	No	1/D
1	G	Teacher's Conference Suite across the Hall from G1 Closet second nearest to the entrance	N/A	Concrete Block Wall		Non Suspect ACM	100	SF	0					N/A	N/A	N/A
1	G	Teacher's Conference Suite across the Hall from G1 Closet second nearest to the entrance	N/A	Concrete Ceiling		Non Suspect ACM	100	SF	0					N/A	N/A	N/A
1	G	Teacher's Conference Suite across the Hall from G1 Closet Restroom	M	Floor Tile VAT 9" x 9"	6050/01/0G/31	Confirmed	100	SF	0		Black			1	No	1/D
1	G	Teacher's Conference Suite across the Hall from G1 Closet Restroom	N/A	Ceramic Tile Walls		Non Suspect ACM	100	SF	0					N/A	N/A	N/A
1	G	Teacher's Conference Suite across the Hall from G1 Closet Restroom	N/A	Concrete Ceiling		Non Suspect ACM	100	SF	0					N/A	N/A	N/A
1	G	Teacher's Conference Suite across the Hall from G1 Closet next to the Restroom	M	Floor Tile VAT 9" x 9"	6050/01/0G/31	Confirmed	100	SF	0		Tan			1	No	1/D
1	G	Teacher's Conference Suite across the Hall from G1 Closet next to the Restroom	N/A	Concrete Block Wall		Non Suspect ACM	100	SF	0					N/A	N/A	N/A
1	G	Teacher's Conference Suite across the Hall from G1 Closet next to the Restroom	N/A	Concrete Ceiling		Non Suspect ACM	100	SF	0					N/A	N/A	N/A
1	G	Teacher's Conference Suite across the Hall from G1 Closet next to the Restroom	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	3	LF	0					N/A	N/A	N/A
1	G	Teacher's Conference Suite across the Hall from G1 Kitchen	M	Floor Tile VAT 9" x 9"	6050/01/0G/31	Confirmed	300	SF	0		Black			1	No	1/D
1	G	Teacher's Conference Suite across the Hall from G1 Kitchen	N/A	Concrete Ceiling		Non Suspect ACM	300	SF	0					N/A	N/A	N/A
1	G	Teacher's Conference Suite across the Hall from G1 Kitchen	N/A	Concrete Block Wall		Non Suspect ACM	300	SF	0					N/A	N/A	N/A
1	G	Teacher's Conference Suite across the Hall from G1 Restroom next to the Kitchen	N/A	Cement Floor		Non Suspect ACM	300	SF	0					N/A	N/A	N/A
1	G	Teacher's Conference Suite across the Hall from G1 Restroom next to the Kitchen	N/A	Ceramic Tile Walls		Non Suspect ACM	300	SF	0					N/A	N/A	N/A
1	G	Teacher's Conference Suite across the Hall from G1 Restroom next to the Kitchen	N/A	Concrete Ceiling		Non Suspect ACM	300	SF	0					N/A	N/A	N/A
1	G	Teacher's Conference Suite across the Hall from G1 Restroom next to the Kitchen	M	Vibration Damper Cloth	6050/01/0G/33	Assumed	2	EA	0					1	No	1/D
1	G	Teacher's Conference Suite across the Hall from G1 Conference Room next to the Restroom	M	Floor Tile VAT 9" x 9"	6050/01/0G/31	Confirmed	800	SF	0		Tan			1	No	1/D
1	G	Teacher's Conference Suite across the Hall from G1 Conference Room next to the Restroom	N/A	Concrete Block Wall		Non Suspect ACM	800	SF	0					N/A	N/A	N/A
1	G	Teacher's Conference Suite across the Hall from G1 Conference Room next to the Restroom	N/A	Concrete Ceiling		Non Suspect ACM	800	SF	0					N/A	N/A	N/A
1	G	Teacher's Conference Suite across the Hall from G1 Conference Room next to the Restroom	T	Pipe Fitting Insulation	6050/01/GF/28	Confirmed	4	EA	0					1	No	1/D
1	G	Teacher's Conference Suite across the Hall from G1 Conference Room next to the Restroom	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	15	LF	0					N/A	N/A	N/A
1	G	Restroom next to the Weight Room	N/A	Cement Floor		Non Suspect ACM	300	SF	0					N/A	N/A	N/A
1	G	Restroom next to the Weight Room	N/A	Ceramic Tile Walls		Non Suspect ACM	300	SF	0					N/A	N/A	N/A
1	G	Restroom next to the Weight Room	N/A	Concrete Block Wall		Non Suspect ACM	300	SF	0					N/A	N/A	N/A
1	G	Restroom next to the Weight Room	M	Vibration Damper Cloth	6050/01/0G/33	Assumed	2	EA	0					1	No	1/D
1	G	Hallway from the Cafeteria Past the Weight Room	M	Floor Tile VAT 9" x 9"	6050/01/0G/31	Confirmed	700	SF	0		Tan			1	No	1/D
1	G	Hallway from the Cafeteria Past the Weight Room	N/A	Ceramic Tile Walls		Non Suspect ACM	700	SF	0					N/A	N/A	N/A
1	G	Hallway from the Cafeteria Past the Weight Room	N/A	Ceiling Tile 1' x 1'		NAD	700	SF	0					N/A	N/A	N/A
1	G	Classroom G1	M	Floor Tile VAT 9" x 9"	6050/01/0G/31	Confirmed	800	SF	0		Tan			1	No	1/D
1	G	Classroom G1	N/A	Concrete Ceiling		Non Suspect ACM	800	SF	0					N/A	N/A	N/A
1	G	Classroom G1	N/A	Concrete Block Wall		Non Suspect ACM	800	SF	0					N/A	N/A	N/A
1	G	Classroom G1	T	Pipe Fitting Insulation	6050/01/GF/28	Confirmed	12	EA	0					1	No	1/D
1	G	Classroom G1	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	40	LF	0					N/A	N/A	N/A
1	G	G3 Cooking Room	M	Floor Tile VAT 9" x 9"	6050/01/0G/31	Confirmed	800	SF	0		Tan			1	No	1/D
1	G	G3 Cooking Room	M	Floor Tile VAT 9" x 9"	6050/01/0G/31	Confirmed	300	SF	0		Black			1	No	1/D
1	G	G3 Cooking Room	N/A	Concrete Ceiling		Non Suspect ACM	1200	SF	0					N/A	N/A	N/A
1	G	G3 Cooking Room	N/A	Concrete Block Wall		Non Suspect ACM	1200	SF	0					N/A	N/A	N/A
1	G	G3 Cooking Room	T	Pipe Fitting Insulation	6050/01/GF/28	Confirmed	32	EA	2		EA	New damage. DDC written up/fill in addition damage material information for Confirmed materials		1	Yes	5/A
1	G	G3 Cooking Room	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	80	LF	6		LF			N/A	N/A	N/A
1	G	Hallway from G1 to the High Voltage Room	M	Floor Tile VAT 9" x 9"	6050/01/0G/31	Confirmed	700	SF	0		Tan			1	No	1/D
1	G	Hallway from G1 to the High Voltage Room	N/A	Ceiling Tile 1' x 1'		NAD	700	SF	0					N/A	N/A	N/A
1	G	Hallway from G1 to the High Voltage Room	N/A	Ceramic Tile Walls		Non Suspect ACM	700	SF	0					N/A	N/A	N/A
1	G	Hallway from G1 to the High Voltage Room	T	Pipe Fitting Insulation	6050/01/GF/28	Confirmed	8	EA	0					1	No	1/D
1	G	Hallway from G1 to the High Voltage Room	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	5	LF	0					N/A	N/A	N/A
1	G	Room across G3	X	X	X	X	X	X	X		X			X	X	X
1	G	Photography Room G5	M	Floor Tile VAT 9" x 9"	6050/01/0G/31	Confirmed	800	SF	0		Tan			1	No	1/D
1	G	Photography Room G5	N/A	Concrete Ceiling		Non Suspect ACM	800	SF	0					N/A	N/A	N/A

6050 Philadelphia High School for Girls 2015-2016 AHERA Three-Year Report.xls

School District of Philadelphia			AHERA Three-Year Reinspection 2015-2016 Room by Room Location Log Report										Reinspection Date: 1/7/2016 Building Inspector: Alex Roman Certification Number: EHSBIR-150619-008 Management Planner: Monique Causley Certification Number: ACC-0215-8-010								
Philadelphia High School For Girls 1400 W Olney Avenue Philadelphia, PA 19141 ULCS# 6050																					
Element	Floor	Room	On Site Room Name	System Affected	Material Description	HID#	Confirmed, Assumed, NAD, Non Suspect ACM	Amount of Material	SF	LF	EA	Amount of Damage	SF	LF	EA	Color required for VAT	Comments/Description/Notes	Attic Crawlspace Ranking	Damage Potential (DP)	Newly Friable (NF)	Response Action (RA)
1	G	Photography Room G5		N/A	Concrete Block Wall		Non Suspect ACM	800	SF			0							N/A	N/A	N/A
1	G	Photography Room G5		N/A	Fiberglass Pipe Insulation		Non Suspect ACM	120	LF			0							N/A	N/A	N/A
1	G	Photography Room G5		T	Pipe Fitting Insulation	6050/01/GF/28	Confirmed	12	EA			0							1	No	1/D
1	G	Photography Room G5		M	Vibration Damper Cloth	6050/01/OG/33	Assumed	1	EA			0							1	No	1/D
1	G	Photography Room G5 Closet		M	Floor Tile VAT 9" x 9"	6050/01/OG/31	Confirmed	100	SF			0				Tan			1	No	1/D
1	G	Photography Room G5 Closet		N/A	Concrete Block Wall		Non Suspect ACM	100	SF			0							N/A	N/A	N/A
1	G	Photography Room G5 Closet		N/A	Concrete Ceiling		Non Suspect ACM	100	SF			0							N/A	N/A	N/A
1	G	Photography Room G5 Closet		T	Pipe Fitting Insulation	6050/01/GF/28	Confirmed	7	EA			0							1	No	1/D
1	G	Photography Room G5 Closet		N/A	Fiberglass Pipe Insulation		Non Suspect ACM	40	LF			0							N/A	N/A	N/A
1	G	Photography Closet outside of G5		M	Floor Tile VAT 9" x 9"	6050/01/OG/31	Confirmed	120	SF			0				Tan			1	No	1/D
1	G	Photography Closet outside of G5		N/A	Concrete Block Wall		Non Suspect ACM	120	SF			0							N/A	N/A	N/A
1	G	Photography Closet outside of G5		N/A	Concrete Ceiling		Non Suspect ACM	120	SF			0							N/A	N/A	N/A
1	G	Photography Closet outside of G5		T	Pipe Fitting Insulation	6050/01/GF/28	Confirmed	4	EA			0							1	No	1/D
1	G	Photography Closet outside of G5		N/A	Fiberglass Pipe Insulation		Non Suspect ACM	20	LF			0							N/A	N/A	N/A
1	G	High Voltage Room		N/A	Cement Floor		Non Suspect ACM	800	SF			0							N/A	N/A	N/A
1	G	High Voltage Room		N/A	Concrete Block Wall		Non Suspect ACM	800	SF			0							N/A	N/A	N/A
1	G	High Voltage Room		N/A	Concrete Ceiling		Non Suspect ACM	800	SF			0							N/A	N/A	N/A
1	G	Mechanical Room under the Stage across from Dressing Room G23		N/A	Concrete Block Wall		Non Suspect ACM	2000	SF			0							N/A	N/A	N/A
1	G	Mechanical Room under the Stage across from Dressing Room G23		N/A	Cement Floor		Non Suspect ACM	2000	SF			0							N/A	N/A	N/A
1	G	Mechanical Room under the Stage across from Dressing Room G23		N/A	Concrete Ceiling		Non Suspect ACM	2000	SF			0							N/A	N/A	N/A
1	G	Mechanical Room under the Stage across from Dressing Room G23		N/A	Fiberglass Pipe Insulation		Non Suspect ACM	300	LF			6				LF			N/A	N/A	N/A
1	G	Mechanical Room under the Stage across from Dressing Room G23		T	Duct Insulation	6050/01/OG/00	Assumed	1000	SF			0							1	No	1/D
1	G	Mechanical Room under the Stage across from Dressing Room G23		T	Pipe Fitting Insulation	6050/01/GF/28	Confirmed	76	EA			0							1	No	1/D
1	G	Closet in Hall at entrance to G23		X	X	X	X	X	X			X				X			X	X	X
1	G	Women's Restroom at entrance to G23		N/A	Concrete Ceiling		Non Suspect ACM	200	SF			0							N/A	N/A	N/A
1	G	Women's Restroom at entrance to G23		N/A	Ceramic Tile Walls		Non Suspect ACM	200	SF			0							N/A	N/A	N/A
1	G	Women's Restroom at entrance to G23		N/A	Cement Floor		Non Suspect ACM	200	SF			0							N/A	N/A	N/A
1	G	Women's Restroom at entrance to G23		T	Pipe Fitting Insulation	6050/01/GF/28	Confirmed	16	EA			0							1	No	1/D
1	G	Women's Restroom at entrance to G23		N/A	Fiberglass Pipe Insulation		Non Suspect ACM	100	LF			0							N/A	N/A	N/A
1	G	Dressing Room G23 Costume Storage		N/A	Cement Floor		Non Suspect ACM	800	SF			0							N/A	N/A	N/A
1	G	Dressing Room G23 Costume Storage		N/A	Concrete Ceiling		Non Suspect ACM	800	SF			0							N/A	N/A	N/A
1	G	Dressing Room G23 Costume Storage		N/A	Concrete Block Wall		Non Suspect ACM	800	SF			0							N/A	N/A	N/A
1	G	Dressing Room G23 Costume Storage		T	Pipe Fitting Insulation	6050/01/GF/28	Confirmed	29	EA			0							1	No	1/D
1	G	Dressing Room G23 Costume Storage		N/A	Fiberglass Pipe Insulation		Non Suspect ACM	150	LF			0							N/A	N/A	N/A
1	G	Room between Dressing Room G23 Costume Storage and Room G20		N/A	Concrete Ceiling		Non Suspect ACM	500	SF			0							N/A	N/A	N/A
1	G	Room between Dressing Room G23 Costume Storage and Room G20		N/A	Cement Floor		Non Suspect ACM	500	SF			0							N/A	N/A	N/A
1	G	Room between Dressing Room G23 Costume Storage and Room G20		N/A	Concrete Block Wall		Non Suspect ACM	500	SF			0							N/A	N/A	N/A
1	G	Room between Dressing Room G23 Costume Storage and Room G20		T	Pipe Fitting Insulation	6050/01/GF/28	Confirmed	3	EA			0							1	No	1/D
1	G	Room between Dressing Room G23 Costume Storage and Room G20		N/A	Fiberglass Pipe Insulation		Non Suspect ACM	80	LF			0							N/A	N/A	N/A
1	G	Costume Storage Room G20		N/A	Concrete Ceiling		Non Suspect ACM	800	SF			0							N/A	N/A	N/A
1	G	Costume Storage Room G20		N/A	Concrete Block Wall		Non Suspect ACM	800	SF			0							N/A	N/A	N/A
1	G	Costume Storage Room G20		N/A	Cement Floor		Non Suspect ACM	800	SF			0							N/A	N/A	N/A
1	G	Costume Storage Room G20		T	Pipe Fitting Insulation	6050/01/GF/28	Confirmed	30	EA			0							1	No	1/D
1	G	Costume Storage Room G20		N/A	Fiberglass Pipe Insulation		Non Suspect ACM	120	LF			0							N/A	N/A	N/A
1	G	Storage Closet in Hall outside Room G20		N/A	Concrete Block Wall		Non Suspect ACM	100	SF			0							N/A	N/A	N/A
1	G	Storage Closet in Hall outside Room G20		N/A	Cement Floor		Non Suspect ACM	50	SF			0							N/A	N/A	N/A
1	G	Storage Closet in Hall outside Room G20		N/A	Concrete Ceiling		Non Suspect ACM	50	SF			0							N/A	N/A	N/A
1	G	Storage Closet in Hall outside Room G20		N/A	Fiberglass Pipe Insulation		Non Suspect ACM	10	LF			0							N/A	N/A	N/A
1	G	Storage Closet in Hall outside Room G20		M	Vibration Damper Cloth	6050/01/OG/33	Assumed	1	EA			0							1	No	1/D
1	G	Girl's Restroom outside Room G20		N/A	Concrete Ceiling		Non Suspect ACM	200	SF			0							N/A	N/A	N/A
1	G	Girl's Restroom outside Room G20		N/A	Cement Floor		Non Suspect ACM	200	SF			0							N/A	N/A	N/A
1	G	Girl's Restroom outside Room G20		N/A	Ceramic Tile Walls		Non Suspect ACM	200	SF			0							N/A	N/A	N/A
1	G	Girl's Restroom outside Room G20		T	Pipe Fitting Insulation	6050/01/GF/28	Confirmed	19	EA			0							1	No	1/D
1	G	Girl's Restroom outside Room G20		N/A	Fiberglass Pipe Insulation		Non Suspect ACM	50	LF			0							N/A	N/A	N/A
1	G	Closet in the Hallway under the Stairs outside Room G20		X	X	X	X	X	X			X				X			X	X	X
1	1	Stage in Auditorium		N/A	Wood Floor		Non Suspect ACM	1200	SF			0							N/A	N/A	N/A
1	1	Stage in Auditorium		N/A	Concrete Ceiling		Non Suspect ACM	1200	SF			0							N/A	N/A	N/A

6050 Philadelphia High School for Girls 2015-2016 AHERA Three-Year Report.xls

		School District of Philadelphia		AHERA Three-Year Reinspection 2015-2016 Room by Room Location Log Report						Reinspection Date: 1/7/2016 Building Inspector: Alex Roman Certification Number: EHSBIR-150619-008 Management Planner: Monique Causley Certification Number: ACC-0215-8-010						
		Philadelphia High School For Girls 1400 W Olney Avenue Philadelphia, PA 19141 ULCS# 6050														
Element	Floor	On Site Room Name	System Affected	Material Description	HID#	Confirmed, Assumed, NAD, Non Suspect ACM	Amount of Material	SF LF EA	Amount of Damage	SF LF EA	Color required for VAT	Comments/Description/Notes	Attic Crawlspace Ranking	Damage Potential (DP)	Newly Friable (NF)	Response Action (RA)
1	1	Stage in Auditorium	N/A	Concrete Block Wall		Non Suspect ACM	2000	SF	0					N/A	N/A	N/A
1	1	Stage in Auditorium	T	Pipe Fitting Insulation	6050/01/01/05	Confirmed	8	EA	0					1	No	1/D
1	1	Stage in Auditorium	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	100	LF	4	LF				N/A	N/A	N/A
1	1	Stairs at the north end of the Stage in the Hall	N/A	Concrete Ceiling		Non Suspect ACM	200	SF	0					N/A	N/A	N/A
1	1	Stairs at the north end of the Stage in the Hall	N/A	Cement Floor		Non Suspect ACM	200	SF	0					N/A	N/A	N/A
1	1	Stairs at the north end of the Stage in the Hall	N/A	Concrete Block Wall		Non Suspect ACM	200	SF	0					N/A	N/A	N/A
1	1	Stair at the south end of the Stage in the Hall	N/A	Concrete Ceiling		Non Suspect ACM	200	SF	0					N/A	N/A	N/A
1	1	Stair at the south end of the Stage in the Hall	N/A	Cement Floor		Non Suspect ACM	200	SF	0					N/A	N/A	N/A
1	1	Stair at the south end of the Stage in the Hall	N/A	Concrete Block Wall		Non Suspect ACM	200	SF	0					N/A	N/A	N/A
1	1	Equipment Storage/Sound Room on Stage to the south with Green Door	N/A	Wood Floor		Non Suspect ACM	200	SF	0			No access during Summer inspection		N/A	N/A	N/A
1	1	Equipment Storage/Sound Room on Stage to the south with Green Door	N/A	Concrete Block Wall		Non Suspect ACM	200	SF	0					N/A	N/A	N/A
1	1	Equipment Storage/Sound Room on Stage to the south with Green Door	N/A	Concrete Ceiling		Non Suspect ACM	200	SF	0					N/A	N/A	N/A
1	1	Equipment Storage/Sound Room on Stage to the south with Green Door	T	Pipe Fitting Insulation	6050/01/01/05	Confirmed	2	EA	0					1	No	1/D
1	1	Equipment Storage/Sound Room on Stage to the south with Green Door	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	10	LF	0					N/A	N/A	N/A
1	1	Auditorium	T	Radiator Insulation	6050/01/01/RR	Assumed	19	EA	0					1	No	1/D
1	1	Auditorium	N/A	Concrete Ceiling		Non Suspect ACM	3000	SF	0					N/A	N/A	N/A
1	1	Auditorium	N/A	Ceiling Tile 1" x 1"		NAD	3000	SF	15	SF		water stains		N/A	N/A	N/A
1	1	Auditorium	M	Floor Tile VAT 9" x 9"	6050/01/01/16	Confirmed	3000	SF	0		Tan			1	No	1/D
1	1	Auditorium	N/A	Plaster Walls		NAD	4000	SF	0					N/A	N/A	N/A
1	1	Horseshoe shaped Hallway that goes around the Auditorium	N/A	Stone Floor		Non Suspect ACM	3000	SF	0					N/A	N/A	N/A
1	1	Horseshoe shaped Hallway that goes around the Auditorium	N/A	Stone Walls		Non Suspect ACM	3000	SF	0					N/A	N/A	N/A
1	1	Horseshoe shaped Hallway that goes around the Auditorium	N/A	Ceiling Tile 1" x 1"		NAD	3000	SF	18	SF		water stains		N/A	N/A	N/A
1	1	Horseshoe shaped Hallway that goes around the Auditorium	T	Radiator Insulation	6050/01/01/RR	Assumed	19	EA	0					1	No	1/D
1	1	Women's Restroom outside of Auditorium	N/A	Cement Floor		Non Suspect ACM	150	SF	0					N/A	N/A	N/A
1	1	Women's Restroom outside of Auditorium	N/A	Ceramic Tile Walls		Non Suspect ACM	150	SF	0					N/A	N/A	N/A
1	1	Women's Restroom outside of Auditorium	S	Plaster Ceiling	6050/01/01/VER/AR/1900	Assumed	150	SF	0					1	No	1/D
1	1	Men's Restroom outside of Auditorium	N/A	Cement Floor		Non Suspect ACM	150	SF	0					N/A	N/A	N/A
1	1	Men's Restroom outside of Auditorium	N/A	Ceramic Tile Walls		Non Suspect ACM	150	SF	0					N/A	N/A	N/A
1	1	Men's Restroom outside of Auditorium	S	Plaster Ceiling	6050/01/01/VER/AR/1900	Assumed	150	SF	0					1	No	1/D
1	1	Hallway outside Instrumental Room 105	N/A	Ceiling Tile 1" x 1"		NAD	500	SF	0					N/A	N/A	N/A
1	1	Hallway outside Instrumental Room 105	N/A	Stone Floor		Non Suspect ACM	500	SF	0					N/A	N/A	N/A
1	1	Hallway outside Instrumental Room 105	N/A	Stone Walls		Non Suspect ACM	500	SF	0					N/A	N/A	N/A
1	1	Instrumental Room 105	M	Floor Tile VAT 9" x 9"	6050/01/01/16	Confirmed	1200	SF	0		Black			1	No	1/D
1	1	Instrumental Room 105	N/A	Ceiling Tile 1" x 1"		NAD	1200	SF	10	SF		New damage, chipped		N/A	N/A	N/A
1	1	Instrumental Room 105	N/A	Concrete Block Wall		Non Suspect ACM	1200	SF	0					N/A	N/A	N/A
1	1	Instrumental Room 105	T	Pipe Fitting Insulation	6050/01/01/05	Confirmed	22	EA	0					1	No	1/D
1	1	Instrumental Room 105	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	20	LF	0					N/A	N/A	N/A
1	1	Instrumental Room 105 Storage Closet to the north	M	Floor Tile VAT 9" x 9"	6050/01/01/16	Confirmed	200	SF	0		Grey	No access during Summer inspection		1	No	1/D
1	1	Instrumental Room 105 Storage Closet to the north	N/A	Ceiling Tile 1" x 1"		NAD	200	SF	0					N/A	N/A	N/A
1	1	Instrumental Room 105 Storage Closet to the north	N/A	Concrete Block Wall		Non Suspect ACM	200	SF	0					N/A	N/A	N/A
1	1	Instrumental Room 105 Storage Closet to the north	T	Pipe Fitting Insulation	6050/01/01/05	Confirmed	8	EA	0					1	No	1/D
1	1	Instrumental Room 105 Storage Closet to the north	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	20	LF	0					N/A	N/A	N/A
1	1	Instrumental Room 105 Storage Closet to the south	M	Floor Tile VAT 9" x 9"	6050/01/01/16	Confirmed	200	SF	0		Black	No access during Summer inspection		1	No	1/D
1	1	Instrumental Room 105 Storage Closet to the south	N/A	Concrete Block Wall		Non Suspect ACM	200	SF	0					N/A	N/A	N/A
1	1	Instrumental Room 105 Storage Closet to the south	N/A	Ceiling Tile 1" x 1"		NAD	200	SF	0					N/A	N/A	N/A
1	1	Instrumental Room 105 Storage Closet to the south	M	Vibration Damper Cloth	6050/01/01/17	Assumed	2	EA	0					1	No	1/D
1	1	Instrumental Room 105 Storage Closet to the south	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	15	LF	0					N/A	N/A	N/A
1	1	Instrumental Room 105 Storage Closet to the south	T	Duct Insulation	6050/01/01/SS	Assumed	10	SF	0					1	No	1/D
1	1	Music Room 101	M	Floor Tile VAT 9" x 9"	6050/01/01/16	Confirmed	1000	SF	0		Tan			1	No	1/D
1	1	Music Room 101	N/A	Concrete Ceiling		Non Suspect ACM	1000	SF	0					N/A	N/A	N/A
1	1	Music Room 101	N/A	Concrete Block Wall		Non Suspect ACM	1000	SF	0					N/A	N/A	N/A
1	1	Music Room 101	T	Pipe Fitting Insulation	6050/01/01/05	Confirmed	9	EA	0					1	No	1/D
1	1	Music Room 101	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	40	LF	0					N/A	N/A	N/A
1	1	Music Room 101 Practice Room A	M	Floor Tile VAT 9" x 9"	6050/01/01/16	Confirmed	100	SF	0		Tan			1	No	1/D
1	1	Music Room 101 Practice Room A	N/A	Ceiling Tile 1" x 1"		NAD	100	SF	0					N/A	N/A	N/A
1	1	Music Room 101 Practice Room A	N/A	Pegboard Walls		Non Suspect ACM	100	SF	0					N/A	N/A	N/A
1	1	Music Room 101 Practice Room B	M	Floor Tile VAT 9" x 9"	6050/01/01/16	Confirmed	100	SF	0		Tan			1	No	1/D
1	1	Music Room 101 Practice Room B	N/A	Ceiling Tile 1" x 1"		NAD	100	SF	0					N/A	N/A	N/A
1	1	Music Room 101 Practice Room B	N/A	Pegboard Walls		Non Suspect ACM	100	SF	0					N/A	N/A	N/A

6050 Philadelphia High School for Girls 2015-2016 AHERA Three-Year Report.xls

School District of Philadelphia			AHERA Three-Year Reinspection 2015-2016 Room by Room Location Log Report										Reinspection Date: 1/7/2016 Building Inspector: Alex Roman Certification Number: EHSBIR-150619-008 Management Planner: Monique Causley Certification Number: ACC-0215-8-010								
Philadelphia High School For Girls 1400 W Olney Avenue Philadelphia, PA 19141 ULCS# 6050																					
Element	Floor	Room	On Site Room Name	System Affected	Material Description	HID#	Confirmed, Assumed, NAD, Non Suspect ACM	Amount of Material	SF	LF	EA	Amount of Damage	SF	LF	EA	Color required for VAT	Comments/Description/Notes	Attic Crawlspace Ranking	Damage Potential (DP)	Newly Friable (NF)	Response Action (RA)
1	1		Music Room 101 Practice Room C	M	Floor Tile VAT 9" x 9"	6050/01/01/16	Confirmed	100	SF			0					Tan		1	No	1/D
1	1		Music Room 101 Practice Room C	N/A	Ceiling Tile 1' x 1'		NAD	100	SF			0							N/A	N/A	N/A
1	1		Music Room 101 Practice Room C	N/A	Pegboard Walls		Non Suspect ACM	100	SF			0							N/A	N/A	N/A
1	1		Music Room 101 Practice Room D	M	Floor Tile VAT 9" x 9"	6050/01/01/16	Confirmed	100	SF			0					Tan		1	No	1/D
1	1		Music Room 101 Practice Room D	N/A	Ceiling Tile 1' x 1'		NAD	100	SF			0							N/A	N/A	N/A
1	1		Music Room 101 Practice Room D	N/A	Pegboard Walls		Non Suspect ACM	100	SF			0							N/A	N/A	N/A
1	1		Music Room 101 Practice Room E	M	Floor Tile VAT 9" x 9"	6050/01/01/16	Confirmed	100	SF			0					Tan		1	No	1/D
1	1		Music Room 101 Practice Room E	N/A	Ceiling Tile 1' x 1'		NAD	100	SF			0							N/A	N/A	N/A
1	1		Music Room 101 Practice Room E	N/A	Pegboard Walls		Non Suspect ACM	100	SF			0							N/A	N/A	N/A
1	1		Music Room 101 Practice Room F	M	Floor Tile VAT 9" x 9"	6050/01/01/16	Confirmed	100	SF			0					Tan		1	No	1/D
1	1		Music Room 101 Practice Room F	N/A	Ceiling Tile 1' x 1'		NAD	100	SF			0							N/A	N/A	N/A
1	1		Music Room 101 Practice Room F	N/A	Pegboard Walls		Non Suspect ACM	100	SF			0							N/A	N/A	N/A
1	1		Stairs #1	N/A	Ceramic Tile Walls		Non Suspect ACM	200	SF			0							N/A	N/A	N/A
1	1		Stairs #1	N/A	Concrete Block Wall		Non Suspect ACM	200	SF			0							N/A	N/A	N/A
1	1		Stairs #1	N/A	Concrete Ceiling		Non Suspect ACM	200	SF			0							N/A	N/A	N/A
1	1		Classroom 100	M	Floor Tile VAT 9" x 9"	6050/01/01/16	Confirmed	800	SF			0					Tan		1	No	1/D
1	1		Classroom 100	N/A	Concrete Ceiling		Non Suspect ACM	800	SF			0							N/A	N/A	N/A
1	1		Classroom 100	N/A	Concrete Block Wall		Non Suspect ACM	800	SF			0							N/A	N/A	N/A
1	1		Classroom 100	T	Pipe Fitting Insulation	6050/01/01/05	Confirmed	4	EA			0							1	No	1/D
1	1		Classroom 100	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	50	LF			0							N/A	N/A	N/A
1	1		Room next to Classroom 100	X	X	X	X	X	X	X	X	X	X	X	X	X			X	X	X
1	1		Slop Sink outside Classroom 100	N/A	Cement Floor		Non Suspect ACM	50	SF			0							N/A	N/A	N/A
1	1		Slop Sink outside Classroom 100	N/A	Concrete Ceiling		Non Suspect ACM	50	SF			0							N/A	N/A	N/A
1	1		Slop Sink outside Classroom 100	N/A	Ceramic Tile Walls		Non Suspect ACM	100	SF			0							N/A	N/A	N/A
1	1		Slop Sink outside Classroom 100	T	Pipe Fitting Insulation	6050/01/01/05	Confirmed	1	EA			0							1	No	1/D
1	1		Girl's Restroom near Classroom 100	N/A	Cement Floor		Non Suspect ACM	300	SF			0							N/A	N/A	N/A
1	1		Girl's Restroom near Classroom 100	N/A	Ceramic Tile Walls		Non Suspect ACM	300	SF			0							N/A	N/A	N/A
1	1		Girl's Restroom near Classroom 100	N/A	Concrete Block Wall		Non Suspect ACM	300	SF			0							N/A	N/A	N/A
1	1		Girl's Restroom near Classroom 100	S	Plaster Ceiling	6050/01/01/VER/AR/1900	Assumed	300	SF			0							1	No	1/D
1	1		Women's Lounge near Classroom 100	M	Floor Tile VAT 9" x 9"	6050/01/01/16	Confirmed	200	SF			0					Tan		1	No	1/D
1	1		Women's Lounge near Classroom 100	N/A	Concrete Block Wall		Non Suspect ACM	200	SF			0							N/A	N/A	N/A
1	1		Women's Lounge near Classroom 100	N/A	Concrete Ceiling		Non Suspect ACM	200	SF			0							N/A	N/A	N/A
1	1		Women's Lounge near Classroom 100	T	Pipe Fitting Insulation	6050/01/01/05	Confirmed	4	EA			0							1	No	1/D
1	1		Women's Lounge near Classroom 100	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	10	LF			0							N/A	N/A	N/A
1	1		Women's Restroom associated with Women's Lounge near Classroom 100	N/A	Concrete Block Wall		Non Suspect ACM	200	SF			0							N/A	N/A	N/A
1	1		Women's Restroom associated with Women's Lounge near Classroom 100	N/A	Concrete Ceiling		Non Suspect ACM	200	SF			0							N/A	N/A	N/A
1	1		Women's Restroom associated with Women's Lounge near Classroom 100	N/A	Cement Floor		Non Suspect ACM	200	SF			0							N/A	N/A	N/A
1	1		Women's Restroom associated with Women's Lounge near Classroom 100	M	Vibration Damper Cloth	6050/01/01/17	Assumed	2	EA			0							1	No	1/D
1	1		Room 102 Archives	X	X	X	X	X	X	X	X	X	X	X	X	X			X	X	X
1	1		Room 104	M	Floor Tile VAT 9" x 9"	6050/01/01/16	Confirmed	500	SF			0					Tan		1	No	1/D
1	1		Room 104	N/A	Concrete Ceiling		Non Suspect ACM	500	SF			0							N/A	N/A	N/A
1	1		Room 104	N/A	Concrete Block Wall		Non Suspect ACM	500	SF			0							N/A	N/A	N/A
1	1		Room 104	T	Pipe Fitting Insulation	6050/01/01/05	Confirmed	12	EA			0							1	No	1/D
1	1		Room 104	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	40	LF			0							N/A	N/A	N/A
1	1		Room 104A	M	Floor Tile VAT 9" x 9"	6050/01/01/16	Confirmed	400	SF			0					Tan	No access during Summer inspection	1	No	1/D
1	1		Room 104A	N/A	Concrete Block Wall		Non Suspect ACM	400	SF			0							N/A	N/A	N/A
1	1		Room 104A	N/A	Concrete Ceiling		Non Suspect ACM	400	SF			0							N/A	N/A	N/A
1	1		Room 104A	T	Pipe Fitting Insulation	6050/01/01/05	Confirmed	4	EA			0							1	No	1/D
1	1		Room 104A	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	20	LF			0							N/A	N/A	N/A
1	1		Room 106A	X	X	X	X	X	X	X	X	X	X	X	X	X			X	X	X
1	1		Hallway from room 100 to Stairs #2	M	Floor Tile VAT 9" x 9"	6050/01/01/16	Confirmed	800	SF			0					Tan		1	No	1/D
1	1		Hallway from room 100 to Stairs #2	N/A	Ceiling Tile 1' x 1'		NAD	800	SF			0							N/A	N/A	N/A
1	1		Hallway from room 100 to Stairs #2	N/A	Ceramic Tile Walls		Non Suspect ACM	800	SF			0							N/A	N/A	N/A
1	1		Classroom 107	M	Floor Tile VAT 9" x 9"	6050/01/01/16	Confirmed	800	SF			0					Tan		1	No	1/D
1	1		Classroom 107	N/A	Concrete Ceiling		Non Suspect ACM	800	SF			0							N/A	N/A	N/A
1	1		Classroom 107	N/A	Concrete Block Wall		Non Suspect ACM	800	SF			0							N/A	N/A	N/A
1	1		Classroom 107	T	Pipe Fitting Insulation	6050/01/01/05	Confirmed	15	EA			0							1	No	1/D
1	1		Classroom 107	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	40	LF			0							N/A	N/A	N/A
1	1		Classroom 109	M	Floor Tile VAT 9" x 9"	6050/01/01/16	Confirmed	800	SF			0					Tan		1	No	1/D
1	1		Classroom 109	N/A	Concrete Ceiling		Non Suspect ACM	800	SF			0							N/A	N/A	N/A
1	1		Classroom 109	N/A	Concrete Block Wall		Non Suspect ACM	800	SF			0							N/A	N/A	N/A
1	1		Classroom 109	T	Pipe Fitting Insulation	6050/01/01/05	Confirmed	20	EA			0							1	No	1/D
1	1		Classroom 109	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	80	LF			0							N/A	N/A	N/A

6050 Philadelphia High School for Girls 2015-2016 AHERA Three-Year Report.xls

School District of Philadelphia		AHERA Three-Year Reinspection 2015-2016										Reinspection Date: 1/7/2016				
		Room by Room Location Log Report										Building Inspector: Alex Roman				
												Certification Number: EHSBIR-150619-008				
												Management Planner: Monique Causley				
												Certification Number: ACC-0215-8-010				
Element	Floor	On Site Room Name	System Affected	Material Description	HID#	Confirmed, Assumed, NAD, Non Suspect ACM	Amount of Material	SF LF EA	Amount of Damage	SF LF EA	Color required for VAT	Comments/Description/Notes	Attic Crawlspace Ranking	Damage Potential (DP)	Newly Friable (NF)	Response Action (RA)
1	1	Stairs #2	N/A	Cement Floor		Non Suspect ACM	200	SF	0					N/A	N/A	N/A
1	1	Stairs #2	N/A	Concrete Ceiling		Non Suspect ACM	200	SF	0					N/A	N/A	N/A
1	1	Stairs #2	N/A	Ceramic Tile Walls		Non Suspect ACM	200	SF	0					N/A	N/A	N/A
1	1	Room 106 Roster Office	M	Floor Tile VAT 9" x 9"	6050/01/01/16	Confirmed	800	SF	0		Tan			1	No	1/D
1	1	Room 106 Roster Office	N/A	Concrete Ceiling		Non Suspect ACM	800	SF	0					N/A	N/A	N/A
1	1	Room 106 Roster Office	T	Concrete Block Wall		Non Suspect ACM	800	SF	0					N/A	N/A	N/A
1	1	Room 106 Roster Office	N/A	Pipe Fitting Insulation	6050/01/01/05	Confirmed	6	EA	0					1	No	1/D
1	1	Room 106 Roster Office	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	30	LF	0					N/A	N/A	N/A
1	1	Room 108 College Information Center	M	Floor Tile VAT 9" x 9"	6050/01/01/16	Confirmed	800	SF	0		Tan			1	No	1/D
1	1	Room 108 College Information Center	N/A	Concrete Ceiling		Non Suspect ACM	800	SF	0					N/A	N/A	N/A
1	1	Room 108 College Information Center	N/A	Concrete Block Wall		Non Suspect ACM	800	SF	0					N/A	N/A	N/A
1	1	Room 108 College Information Center	T	Pipe Fitting Insulation	6050/01/01/05	Confirmed	6	EA	0					1	No	1/D
1	1	Room 108 College Information Center	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	30	LF	0					N/A	N/A	N/A
1	1	Room 108A	X	X	X	X	X	X	X	X	X			X	X	X
1	1	Room 110	M	Floor Tile VAT 9" x 9"	6050/01/01/16	Confirmed	800	SF	0		Tan			1	No	1/D
1	1	Room 110	N/A	Concrete Ceiling		Non Suspect ACM	800	SF	0					N/A	N/A	N/A
1	1	Room 110	N/A	Concrete Block Wall		Non Suspect ACM	800	SF	0					N/A	N/A	N/A
1	1	Room 110	T	Pipe Fitting Insulation	6050/01/01/05	Confirmed	7	EA	0					1	No	1/D
1	1	Room 110	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	40	LF	0					N/A	N/A	N/A
1	1	Room 112	M	Floor Tile VAT 9" x 9"	6050/01/01/16	Confirmed	800	SF	0		Tan			1	No	1/D
1	1	Room 112	N/A	Concrete Ceiling		Non Suspect ACM	800	SF	0					N/A	N/A	N/A
1	1	Room 112	N/A	Concrete Block Wall		Non Suspect ACM	800	SF	0					N/A	N/A	N/A
1	1	Room 112	T	Pipe Fitting Insulation	6050/01/01/05	Confirmed	10	EA	0					1	No	1/D
1	1	Room 112	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	30	LF	0					N/A	N/A	N/A
1	1	Room 114	M	Floor Tile VAT 9" x 9"	6050/01/01/16	Confirmed	800	SF	0		Tan			1	No	1/D
1	1	Room 114	N/A	Concrete Ceiling		Non Suspect ACM	800	SF	0					N/A	N/A	N/A
1	1	Room 114	N/A	Concrete Block Wall		Non Suspect ACM	800	SF	0					N/A	N/A	N/A
1	1	Room 114	T	Pipe Fitting Insulation	6050/01/01/05	Confirmed	8	EA	0					1	No	1/D
1	1	Room 114	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	30	LF	0					N/A	N/A	N/A
1	1	Room 116	M	Floor Tile VAT 9" x 9"	6050/01/01/16	Confirmed	800	SF	0		Tan			1	No	1/D
1	1	Room 116	N/A	Concrete Ceiling		Non Suspect ACM	800	SF	0					N/A	N/A	N/A
1	1	Room 116	N/A	Concrete Block Wall		Non Suspect ACM	800	SF	0					N/A	N/A	N/A
1	1	Room 116	T	Pipe Fitting Insulation	6050/01/01/05	Confirmed	9	EA	0					1	No	1/D
1	1	Room 116	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	35	LF	10	LF				N/A	N/A	N/A
1	1	Men's Lounge near Classroom 116	M	Floor Tile VAT 9" x 9"	6050/01/01/16	Confirmed	200	SF	0		Tan			1	No	1/D
1	1	Men's Lounge near Classroom 116	N/A	Concrete Block Wall		Non Suspect ACM	200	SF	0					N/A	N/A	N/A
1	1	Men's Lounge near Classroom 116	N/A	Concrete Ceiling		Non Suspect ACM	200	SF	0					N/A	N/A	N/A
1	1	Men's Lounge near Classroom 116	T	Pipe Fitting Insulation	6050/01/01/05	Confirmed	4	EA	0					1	No	1/D
1	1	Men's Lounge near Classroom 116	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	10	LF	0					N/A	N/A	N/A
1	1	Room 118	M	Floor Tile VAT 9" x 9"	6050/01/01/16	Confirmed	800	SF	0		Tan			1	No	1/D
1	1	Room 118	N/A	Concrete Ceiling		Non Suspect ACM	800	SF	0					N/A	N/A	N/A
1	1	Room 118	N/A	Concrete Block Wall		Non Suspect ACM	800	SF	0					N/A	N/A	N/A
1	1	Room 118	T	Pipe Fitting Insulation	6050/01/01/05	Confirmed	14	EA	0					1	No	1/D
1	1	Room 118	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	60	LF	0					N/A	N/A	N/A
1	1	Room 115	M	Floor Tile VAT 9" x 9"	6050/01/01/16	Confirmed	800	SF	0		Tan			1	No	1/D
1	1	Room 115	N/A	Concrete Ceiling		Non Suspect ACM	800	SF	0					N/A	N/A	N/A
1	1	Room 115	N/A	Concrete Block Wall		Non Suspect ACM	800	SF	0					N/A	N/A	N/A
1	1	Room 115	T	Pipe Fitting Insulation	6050/01/01/05	Confirmed	22	EA	0					1	No	1/D
1	1	Room 115	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	100	LF	0					N/A	N/A	N/A
1	1	Room 115 Closet closest to the entrance	M	Floor Tile VAT 9" x 9"	6050/01/01/16	Confirmed	200	SF	0		Tan			1	No	1/D
1	1	Room 115 Closet closest to the entrance	N/A	Concrete Block Wall		Non Suspect ACM	200	SF	0					N/A	N/A	N/A
1	1	Room 115 Closet closest to the entrance	N/A	Concrete Ceiling		Non Suspect ACM	200	SF	0					N/A	N/A	N/A
1	1	Room 115 Closet farthest the entrance	M	Floor Tile VAT 9" x 9"	6050/01/01/16	Confirmed	200	SF	0		Tan			1	No	1/D
1	1	Room 115 Closet farthest the entrance	N/A	Concrete Ceiling		Non Suspect ACM	200	SF	0					N/A	N/A	N/A
1	1	Room 115 Closet farthest the entrance	N/A	Concrete Block Wall		Non Suspect ACM	200	SF	0					N/A	N/A	N/A
1	1	Room 115 Closet farthest the entrance	T	Pipe Fitting Insulation	6050/01/01/05	Confirmed	4	EA	0					1	No	1/D
1	1	Room 115 Closet farthest the entrance	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	3	LF	0					N/A	N/A	N/A
1	1	Room 113	M	Floor Tile VAT 9" x 9"	6050/01/01/16	Confirmed	800	SF	0		Tan			1	No	1/D
1	1	Room 113	N/A	Concrete Ceiling		Non Suspect ACM	800	SF	0					N/A	N/A	N/A
1	1	Room 113	N/A	Concrete Block Wall		Non Suspect ACM	800	SF	0					N/A	N/A	N/A
1	1	Room 113	T	Pipe Fitting Insulation	6050/01/01/05	Confirmed	17	EA	0					1	No	1/D
1	1	Room 113	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	100	LF	0					N/A	N/A	N/A
1	1	Room 113 Closet	M	Floor Tile VAT 9" x 9"	6050/01/01/16	Confirmed	100	SF	0		Tan			1	No	1/D
1	1	Room 113 Closet	N/A	Concrete Block Wall		Non Suspect ACM	100	SF	0					N/A	N/A	N/A
1	1	Room 113 Closet	N/A	Concrete Ceiling		Non Suspect ACM	100	SF	0					N/A	N/A	N/A

6050 Philadelphia High School for Girls 2015-2016 AHERA Three-Year Report.xls

		School District of Philadelphia		AHERA Three-Year Reinspection 2015-2016 Room by Room Location Log Report								Reinspection Date: 1/7/2016				
		Philadelphia High School For Girls										Building Inspector: Alex Roman				
		1400 W Olney Avenue										Certification Number: EHSBIR-150619-008				
		Philadelphia, PA 19141										Management Planner: Monique Causley				
		ULCS# 6050										Certification Number: ACC-0215-8-010				
Element	Room	On Site Room Name	System Affected	Material Description	HID#	Confirmed, Assumed, NAD, Non Suspect ACM	Amount of Material	SF LF EA	Amount of Damage	SF LF EA	Color required for VAT	Comments/Description/Notes	Attic Crawlspace Ranking	Damage Potential (DP)	Newly Friable (NF)	Response Action (RA)
1	1	Art Room 111	M	Floor Tile VAT 9" x 9"	6050/01/01/16	Confirmed	800	SF	0		Tan			1	No	1/D
1	1	Art Room 111	N/A	Concrete Ceiling		Non Suspect ACM	800	SF	0					N/A	N/A	N/A
1	1	Art Room 111	N/A	Concrete Block Wall		Non Suspect ACM	800	SF	0					N/A	N/A	N/A
1	1	Art Room 111	T	Pipe Fitting Insulation	6050/01/01/05	Confirmed	21	EA	0					1	No	1/D
1	1	Art Room 111	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	80	LF	0					N/A	N/A	N/A
1	1	Art Room 111 Closet	M	Floor Tile VAT 9" x 9"	6050/01/01/16	Confirmed	200	SF	0		Tan			1	No	1/D
1	1	Art Room 111 Closet	N/A	Concrete Ceiling		Non Suspect ACM	200	SF	0					N/A	N/A	N/A
1	1	Art Room 111 Closet	N/A	Concrete Block Wall		Non Suspect ACM	200	SF	0					N/A	N/A	N/A
1	1	Art Room 111 Closet	T	Pipe Fitting Insulation	6050/01/01/05	Confirmed	7	EA	0					1	No	1/D
1	1	Art Room 111 Closet	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	40	LF	0					N/A	N/A	N/A
1	1	Art Storage Closet 115A in Hallway outside of Room 111	M	Floor Tile VAT 9" x 9"	6050/01/01/16	Confirmed	200	SF	0		Tan	No access during Summer inspection		1	No	1/D
1	1	Art Storage Closet 115A in Hallway outside of Room 111	N/A	Concrete Ceiling		Non Suspect ACM	200	SF	0					N/A	N/A	N/A
1	1	Art Storage Closet 115A in Hallway outside of Room 111	N/A	Concrete Block Wall		Non Suspect ACM	200	SF	0					N/A	N/A	N/A
1	1	Health Office 111A	M	Floor Tile VAT 12" x 12"	6050/01/01/A2	Assumed	800	SF	0		Red			1	No	1/D
1	1	Health Office 111A	N/A	Concrete Ceiling		Non Suspect ACM	800	SF	0					N/A	N/A	N/A
1	1	Health Office 111A	N/A	Concrete Block Wall		Non Suspect ACM	800	SF	0					N/A	N/A	N/A
1	1	Health Office 111A	T	Pipe Fitting Insulation	6050/01/01/05	Confirmed	2	EA	0					1	No	1/D
1	1	Health Office Infirmary area to the west	M	Floor Tile VAT 9" x 9"	6050/01/01/16	Confirmed	800	SF	0		Tan			1	No	1/D
1	1	Health Office Infirmary area to the west	N/A	Concrete Ceiling		Non Suspect ACM	800	SF	0					N/A	N/A	N/A
1	1	Health Office Infirmary area to the west	N/A	Concrete Block Wall		Non Suspect ACM	800	SF	0					N/A	N/A	N/A
1	1	Health Office Infirmary area to the west Restroom	N/A	Ceramic Tile Walls		Non Suspect ACM	100	SF	0					N/A	N/A	N/A
1	1	Health Office Infirmary area to the west Restroom	M	Floor Tile VAT 12" x 12"	6050/01/01/A2	Assumed	100	SF	0		Tan			1	No	1/D
1	1	Health Office Infirmary area to the west Restroom	N/A	Concrete Ceiling		Non Suspect ACM	100	SF	0					N/A	N/A	N/A
1	1	Health Office Exam Room first door to the south	N/A	Concrete Block Wall		Non Suspect ACM	300	SF	0					N/A	N/A	N/A
1	1	Health Office Exam Room first door to the south	N/A	Concrete Ceiling		Non Suspect ACM	300	SF	0					N/A	N/A	N/A
1	1	Health Office Exam Room first door to the south	M	Floor Tile VAT 12" x 12"	6050/01/01/A2	Assumed	300	SF	0		Grey			1	No	1/D
1	1	Health Office Exam Room first door to the south	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	20	LF	0					N/A	N/A	N/A
1	1	Health Office Exam Room second door to the south	M	Floor Tile VAT 9" x 9"	6050/01/01/16	Confirmed	300	SF	0		Tan			1	No	1/D
1	1	Health Office Exam Room second door to the south	N/A	Concrete Block Wall		Non Suspect ACM	300	SF	0					N/A	N/A	N/A
1	1	Health Office Exam Room second door to the south	N/A	Concrete Ceiling		Non Suspect ACM	300	SF	0					N/A	N/A	N/A
1	1	Health Office Exam Room second door to the south	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	50	LF	0					N/A	N/A	N/A
1	1	Health Office Hallway leading to Exam Rooms	M	Floor Tile VAT 9" x 9"	6050/01/01/16	Confirmed	200	SF	0		Tan			1	No	1/D
1	1	Health Office Hallway leading to Exam Rooms	N/A	Concrete Ceiling		Non Suspect ACM	200	SF	0					N/A	N/A	N/A
1	1	Health Office Hallway leading to Exam Rooms	N/A	Concrete Block Wall		Non Suspect ACM	200	SF	0					N/A	N/A	N/A
1	1	Conference Room 111B	M	Floor Tile VAT 9" x 9"	6050/01/01/16	Confirmed	300	SF	0		Tan			1	No	1/D
1	1	Conference Room 111B	N/A	Concrete Ceiling		Non Suspect ACM	300	SF	0					N/A	N/A	N/A
1	1	Conference Room 111B	N/A	Concrete Block Wall		Non Suspect ACM	300	SF	0					N/A	N/A	N/A
1	1	Counselor's Offices Foyer	M	Floor Tile VAT 9" x 9"	6050/01/01/16	Confirmed	600	SF	0		Tan			1	No	1/D
1	1	Counselor's Offices Foyer	N/A	Concrete Block Wall		Non Suspect ACM	600	SF	0					N/A	N/A	N/A
1	1	Counselor's Offices Foyer	N/A	Concrete Ceiling		Non Suspect ACM	600	SF	0					N/A	N/A	N/A
1	1	Counselor's Office 129	M	Floor Tile VAT 9" x 9"	6050/01/01/16	Confirmed	400	SF	0		Tan			1	No	1/D
1	1	Counselor's Office 129	N/A	Concrete Ceiling		Non Suspect ACM	400	SF	0					N/A	N/A	N/A
1	1	Counselor's Office 129	N/A	Concrete Block Wall		Non Suspect ACM	400	SF	0					N/A	N/A	N/A
1	1	Counselor's Office 129	T	Pipe Fitting Insulation	6050/01/01/05	Confirmed	6	EA	0					1	No	1/D
1	1	Counselor's Office 129	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	40	LF	0					N/A	N/A	N/A
1	1	Counselor's Office 130	M	Floor Tile VAT 9" x 9"	6050/01/01/16	Confirmed	400	SF	0		Tan			1	No	1/D
1	1	Counselor's Office 130	N/A	Concrete Ceiling		Non Suspect ACM	400	SF	0					N/A	N/A	N/A
1	1	Counselor's Office 130	N/A	Concrete Block Wall		Non Suspect ACM	400	SF	0					N/A	N/A	N/A
1	1	Counselor's Office 130	T	Pipe Fitting Insulation	6050/01/01/05	Confirmed	2	EA	0					1	No	1/D
1	1	Counselor's Office 130	M	Pipe Insulation 2-6 inch	6050/01/01/VER/AR/1100	Assumed	3	LF	0					1	No	1/D
1	1	Counselor's Office 131	M	Floor Tile VAT 9" x 9"	6050/01/01/16	Confirmed	400	SF	0		Grey			1	No	1/D
1	1	Counselor's Office 131	N/A	Concrete Ceiling		Non Suspect ACM	400	SF	0					N/A	N/A	N/A
1	1	Counselor's Office 131	N/A	Concrete Block Wall		Non Suspect ACM	400	SF	0					N/A	N/A	N/A
1	1	Counselor's Office 132	N/A	Floor Tile VAT 9" x 9"	6050/01/01/16	Confirmed	400	SF	0		Tan			1	No	1/D
1	1	Counselor's Office 132	N/A	Concrete Ceiling		Non Suspect ACM	400	SF	0					N/A	N/A	N/A
1	1	Counselor's Office 132	N/A	Concrete Block Wall		Non Suspect ACM	400	SF	0					N/A	N/A	N/A
1	1	Counselor's Office 132	T	Pipe Fitting Insulation	6050/01/01/05	Confirmed	4	EA	0					1	No	1/D
1	1	Hallway in front of the Counselor's Suite and the Main Office	N/A	Stone Floor		Non Suspect ACM	500	SF	0					N/A	N/A	N/A
1	1	Hallway in front of the Counselor's Suite and the Main Office	N/A	Stone Walls		Non Suspect ACM	500	SF	0					N/A	N/A	N/A
1	1	Hallway in front of the Counselor's Suite and the Main Office	N/A	Ceiling Tile 1' x 1'		NAD	500	SF	0					N/A	N/A	N/A
1	1	Main Office	M	Floor Tile VAT 12" x 12"	6050/01/01/A2	Assumed	800	SF	0		Tan			1	No	1/D

6050 Philadelphia High School for Girls 2015-2016 AHERA Three-Year Report.xls

School District of Philadelphia		AHERA Three-Year Reinspection 2015-2016										Reinspection Date: 1/7/2016				
		Room by Room Location Log Report										Building Inspector: Alex Roman				
												Certification Number: EHSBIR-150619-008				
																Management Planner: Monique Causley
ULCS# 6050										Certification Number: ACC-0215-8-010						
Element	Floor	On Site Room Name	System Affected	Material Description	HID#	Confirmed, Assumed, NAD, Non Suspect ACM	Amount of Material	SF LF EA	Amount of Damage	SF LF EA	Color required for VAT	Comments/Description/Notes	Attic Crawlspace Ranking	Damage Potential (DP)	Newly Friable (NF)	Response Action (RA)
1	1	Main Office	N/A	Concrete Ceiling		Non Suspect ACM	800	SF	0					N/A	N/A	N/A
1	1	Main Office	N/A	Concrete Block Wall		Non Suspect ACM	800	SF	0					N/A	N/A	N/A
1	1	Main Office	T	Pipe Fitting Insulation	6050/01/01/05	Confirmed	4	EA	0					1	No	1/D
1	1	Main Office	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	30	LF	0					N/A	N/A	N/A
1	1	Main Office	T	Pipe Insulation 2-6 inch	6050/01/01/VER/AR/1100	Assumed	4	LF	0					1	No	1/D
1	1	Main Office Restroom	M	Floor Tile VAT 9" x 9"	6050/01/01/16	Confirmed	100	SF	0		Green			1	No	1/D
1	1	Main Office Restroom	N/A	Concrete Ceiling		Non Suspect ACM	100	SF	0					N/A	N/A	N/A
1	1	Main Office Restroom	N/A	Ceramic Tile Walls		Non Suspect ACM	100	SF	0					N/A	N/A	N/A
1	1	Main Office Computer Network Room	M	Floor Tile VAT 9" x 9"	6050/01/01/16	Confirmed	200	SF	0		Grey	No access during Summer inspection		1	No	1/D
1	1	Main Office Computer Network Room	N/A	Concrete Ceiling		Non Suspect ACM	200	SF	0					N/A	N/A	N/A
1	1	Main Office Computer Network Room	N/A	Concrete Block Wall		Non Suspect ACM	200	SF	0					N/A	N/A	N/A
1	1	Main Office Computer Copier Room	M	Floor Tile VAT 9" x 9"	6050/01/01/16	Confirmed	200	SF	0		Tan			1	No	1/D
1	1	Main Office Computer Copier Room	N/A	Concrete Ceiling		Non Suspect ACM	200	SF	0					N/A	N/A	N/A
1	1	Main Office Computer Copier Room	N/A	Concrete Block Wall		Non Suspect ACM	200	SF	0					N/A	N/A	N/A
1	1	Principal's Conference Room	N/A	Carpet		Non Suspect ACM	500	SF	0			No access during Summer inspection		N/A	N/A	N/A
1	1	Principal's Conference Room	N/A	Ceiling Tile 1' x 1'		NAD	500	SF	0					N/A	N/A	N/A
1	1	Principal's Conference Room	N/A	Plaster Walls		NAD	500	SF	0					N/A	N/A	N/A
1	1	Principal's Conference Room	T	Pipe Fitting Insulation	6050/01/01/05	Confirmed	5	EA	0					1	No	1/D
1	1	Principal's Conference Room	T	Radiator Insulation	6050/01/01/RR	Assumed	2	EA	0					1	No	1/D
1	1	Principal's Office	N/A	Carpet		Non Suspect ACM	500	SF	0			No access during Summer inspection		N/A	N/A	N/A
1	1	Principal's Office	N/A	Plaster Walls		NAD	500	SF	0					N/A	N/A	N/A
1	1	Principal's Office	N/A	Ceiling Tile 1' x 1'		NAD	500	SF	0					N/A	N/A	N/A
1	1	Principal's Office	T	Radiator Insulation	6050/01/01/RR	Assumed	1	EA	0					1	No	1/D
1	1	Principal's Restroom	M	Floor Tile VAT 9" x 9"	6050/01/01/16	Confirmed	100	SF	0		Tan	No access during Summer inspection		1	No	1/D
1	1	Principal's Restroom	N/A	Ceramic Tile Walls		Non Suspect ACM	100	SF	0					N/A	N/A	N/A
1	1	Principal's Restroom	N/A	Concrete Ceiling		Non Suspect ACM	100	SF	0					N/A	N/A	N/A
1	1	Assistant Principal's Restroom	M	Floor Tile VAT 12" x 12"	6050/01/01/A2	Assumed	100	SF	0		Grey			1	No	1/D
1	1	Assistant Principal's Restroom	N/A	Ceramic Tile Walls		Non Suspect ACM	100	SF	0					N/A	N/A	N/A
1	1	Assistant Principal's Restroom	N/A	Concrete Ceiling		Non Suspect ACM	100	SF	0					N/A	N/A	N/A
1	1	109B Office Space leading to Assistant Principal's Office from the Main Office	M	Floor Tile VAT 9" x 9"	6050/01/01/16	Confirmed	400	SF	0		Tan			1	No	1/D
1	1	109B Office Space leading to Assistant Principal's Office from the Main Office	N/A	Concrete Ceiling		Non Suspect ACM	400	SF	0					N/A	N/A	N/A
1	1	109B Office Space leading to Assistant Principal's Office from the Main Office	N/A	Concrete Block Wall		Non Suspect ACM	400	SF	0					N/A	N/A	N/A
1	1	Assistant Principal's Office room 109A	M	Floor Tile VAT 9" x 9"	6050/01/01/16	Confirmed	400	SF	0		Tan			1	No	1/D
1	1	Assistant Principal's Office room 109A	N/A	Concrete Ceiling		Non Suspect ACM	400	SF	0					N/A	N/A	N/A
1	1	Assistant Principal's Office room 109A	N/A	Concrete Block Wall		Non Suspect ACM	400	SF	0					N/A	N/A	N/A
1	1	Assistant Principal's Office room 109A	T	Pipe Fitting Insulation	6050/01/01/05	Confirmed	14	EA	0					1	No	1/D
1	1	Assistant Principal's Office room 109A	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	50	LF	0					N/A	N/A	N/A
1	1	Room 112A behind Elevator	M	Floor Tile VAT 9" x 9"	6050/01/01/16	Confirmed	200	SF	0		Tan			1	No	1/D
1	1	Room 112A behind Elevator	N/A	Concrete Ceiling		Non Suspect ACM	200	SF	0					N/A	N/A	N/A
1	1	Room 112A behind Elevator	N/A	Concrete Block Wall		Non Suspect ACM	200	SF	0					N/A	N/A	N/A
1	1	Room 112A behind Elevator	T	Pipe Fitting Insulation	6050/01/01/05	Confirmed	14	EA	0					1	No	1/D
1	1	Room 112A behind Elevator	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	30	LF	0					N/A	N/A	N/A
1	1	Office 112B	M	Floor Tile VAT 9" x 9"	6050/01/01/16	Confirmed	200	SF	0		Tan	No access during Summer inspection		1	No	1/D
1	1	Office 112B	N/A	Concrete Ceiling		Non Suspect ACM	200	SF	0					N/A	N/A	N/A
1	1	Office 112B	N/A	Concrete Block Wall		Non Suspect ACM	200	SF	0					N/A	N/A	N/A
1	1	Office 112B	T	Pipe Fitting Insulation	6050/01/01/05	Confirmed	6	EA	0					1	No	1/D
1	1	Office 112B	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	30	LF	0					N/A	N/A	N/A
1	1	Men's Restroom across from Room 113	M	Floor Tile VAT 9" x 9"	6050/01/01/16	Confirmed	200	SF	0		Tan			1	No	1/D
1	1	Men's Restroom across from Room 113	N/A	Concrete Ceiling		Non Suspect ACM	200	SF	0					N/A	N/A	N/A
1	1	Men's Restroom across from Room 113	N/A	Concrete Block Wall		Non Suspect ACM	200	SF	0					N/A	N/A	N/A
1	1	Men's Restroom across from Room 113	T	Pipe Fitting Insulation	6050/01/01/05	Confirmed	4	EA	0					1	No	1/D
1	1	Men's Restroom across from Room 113	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	10	LF	0					N/A	N/A	N/A
1	1	Men's Restroom across from Room 113	M	Vibration Damper Cloth	6050/01/01/17	Assumed	2	EA	0					No	No	1/D
1	1	Girl's Restroom across from Room 113	N/A	Cement Floor		Non Suspect ACM	200	SF	0					N/A	N/A	N/A
1	1	Girl's Restroom across from Room 113	N/A	Concrete Ceiling		Non Suspect ACM	200	SF	0					N/A	N/A	N/A
1	1	Girl's Restroom across from Room 113	N/A	Ceramic Tile Walls		Non Suspect ACM	200	SF	0					N/A	N/A	N/A
1	1	Language Teacher's Book Room	M	Floor Tile VAT 9" x 9"	6050/01/01/16	Confirmed	200	SF	0		Tan			1	No	1/D
1	1	Language Teacher's Book Room	N/A	Concrete Ceiling		Non Suspect ACM	200	SF	0					N/A	N/A	N/A
1	1	Language Teacher's Book Room	N/A	Concrete Block Wall		Non Suspect ACM	200	SF	0					N/A	N/A	N/A
1	1	Language Teacher's Book Room	T	Pipe Fitting Insulation	6050/01/01/05	Confirmed	4	EA	0					1	No	1/D
1	1	Language Teacher's Book Room	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	20	LF	0					N/A	N/A	N/A
1	1	Stairs at Room 118 Stairs #5	N/A	Cement Floor		Non Suspect ACM	200	SF	0					N/A	N/A	N/A
1	1	Stairs at Room 118 Stairs #5	N/A	Concrete Ceiling		Non Suspect ACM	200	SF	0					N/A	N/A	N/A

6050 Philadelphia High School for Girls 2015-2016 AHERA Three-Year Report.xls

		School District of Philadelphia		AHERA Three-Year Reinspection 2015-2016 Room by Room Location Log Report						Reinspection Date: 1/7/2016 Building Inspector: Alex Roman Certification Number: EHSBIR-150619-008 Management Planner: Monique Causley Certification Number: ACC-0215-8-010						
		Philadelphia High School For Girls 1400 W Olney Avenue Philadelphia, PA 19141 ULCS# 6050														
Element	Room	On Site Room Name	System Affected	Material Description	HID#	Confirmed, Assumed, NAD, Non Suspect ACM	Amount of Material	SF LF EA	Amount of Damage	SF LF EA	Color required for VAT	Comments/Description/Notes	Attic Crawlspace Ranking	Damage Potential (DP)	Newly Friable (NF)	Response Action (RA)
1	1	Stairs at Room 118 Stairs #5	N/A	Ceramic Tile Walls		Non Suspect ACM	200	SF	0					N/A	N/A	N/A
1	1	Stairs #4	N/A	Cement Floor		Non Suspect ACM	200	SF	0					N/A	N/A	N/A
1	1	Stairs #4	N/A	Concrete Ceiling		Non Suspect ACM	200	SF	0					N/A	N/A	N/A
1	1	Stairs #4	N/A	Ceramic Tile Walls		Non Suspect ACM	200	SF	0					N/A	N/A	N/A
1	1	Stairs #3	N/A	Cement Floor		Non Suspect ACM	200	SF	0					N/A	N/A	N/A
1	1	Stairs #3	N/A	Concrete Ceiling		Non Suspect ACM	200	SF	0					N/A	N/A	N/A
1	1	Stairs #3	N/A	Ceramic Tile Walls		Non Suspect ACM	200	SF	0					N/A	N/A	N/A
1	2	Classroom 206	M	Floor Tile VAT 9" x 9"	6050/01/02/19	Confirmed	800	SF	0		Tan			1	No	1/D
1	2	Classroom 206	N/A	Concrete Ceiling		Non Suspect ACM	800	SF	0					N/A	N/A	N/A
1	2	Classroom 206	N/A	Concrete Block Wall		Non Suspect ACM	800	SF	0					N/A	N/A	N/A
1	2	Classroom 206	T	Pipe Fitting Insulation	6050/01/02/20	Confirmed	20	EA	0					1	No	1/D
1	2	Classroom 206	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	60	LF	0					N/A	N/A	N/A
1	2	Classroom 208	M	Floor Tile VAT 9" x 9"	6050/01/02/19	Confirmed	800	SF	0		Tan			1	No	1/D
1	2	Classroom 208	N/A	Concrete Ceiling		Non Suspect ACM	800	SF	0					N/A	N/A	N/A
1	2	Classroom 208	N/A	Concrete Block Wall		Non Suspect ACM	800	SF	0					N/A	N/A	N/A
1	2	Classroom 208	T	Pipe Fitting Insulation	6050/01/02/20	Confirmed	50	EA	0					1	No	1/D
1	2	Classroom 208	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	200	LF	0					N/A	N/A	N/A
1	2	Room 208A	M	Floor Tile VAT 9" x 9"	6050/01/02/19	Confirmed	400	SF	0		Tan			1	No	1/D
1	2	Room 208A	N/A	Concrete Ceiling		Non Suspect ACM	400	SF	0					N/A	N/A	N/A
1	2	Room 208A	N/A	Concrete Block Wall		Non Suspect ACM	400	SF	0					N/A	N/A	N/A
1	2	Room 208A	T	Pipe Fitting Insulation	6050/01/02/20	Confirmed	19	EA	0					1	No	1/D
1	2	Room 208A	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	100	LF	0					N/A	N/A	N/A
1	2	Classroom 210	M	Floor Tile VAT 9" x 9"	6050/01/02/19	Confirmed	800	SF	0		Tan			1	No	1/D
1	2	Classroom 210	N/A	Concrete Ceiling		Non Suspect ACM	800	SF	0					N/A	N/A	N/A
1	2	Classroom 210	N/A	Concrete Block Wall		Non Suspect ACM	800	SF	0					N/A	N/A	N/A
1	2	Classroom 210	T	Pipe Fitting Insulation	6050/01/02/20	Confirmed	50	EA	0					1	No	1/D
1	2	Classroom 210	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	200	LF	0					N/A	N/A	N/A
1	2	Classroom 212	M	Floor Tile VAT 9" x 9"	6050/01/02/19	Confirmed	800	SF	0		Tan			1	No	1/D
1	2	Classroom 212	N/A	Concrete Ceiling		Non Suspect ACM	800	SF	0					N/A	N/A	N/A
1	2	Classroom 212	N/A	Concrete Block Wall		Non Suspect ACM	800	SF	0					N/A	N/A	N/A
1	2	Classroom 212	T	Pipe Fitting Insulation	6050/01/02/20	Confirmed	23	EA	0					1	No	1/D
1	2	Classroom 212	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	100	LF	10		LF	water stains		N/A	N/A	N/A
1	2	Teacher's Lounge Room 212A across from Classroom 217	M	Floor Tile VAT 9" x 9"	6050/01/02/19	Confirmed	500	SF	0		Tan			1	No	1/D
1	2	Teacher's Lounge Room 212A across from Classroom 217	N/A	Concrete Ceiling		Non Suspect ACM	500	SF	0					N/A	N/A	N/A
1	2	Teacher's Lounge Room 212A across from Classroom 217	N/A	Concrete Block Wall		Non Suspect ACM	500	SF	0					N/A	N/A	N/A
1	2	Teacher's Lounge Room 212A across from Classroom 217	T	Pipe Fitting Insulation	6050/01/02/20	Confirmed	32	EA	0					1	No	1/D
1	2	Teacher's Lounge Room 212A across from Classroom 217	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	100	LF	4		LF			N/A	N/A	N/A
1	2	Classroom 214	M	Floor Tile VAT 9" x 9"	6050/01/02/19	Confirmed	800	SF	0		Tan			1	No	1/D
1	2	Classroom 214	N/A	Concrete Ceiling		Non Suspect ACM	800	SF	0					N/A	N/A	N/A
1	2	Classroom 214	N/A	Concrete Block Wall		Non Suspect ACM	800	SF	0					N/A	N/A	N/A
1	2	Classroom 214	T	Pipe Fitting Insulation	6050/01/02/20	Confirmed	52	EA	0					1	No	1/D
1	2	Classroom 214	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	200	LF	6		LF	water stains		N/A	N/A	N/A
1	2	Classroom 216	M	Floor Tile VAT 9" x 9"	6050/01/02/19	Confirmed	800	SF	0		Tan			1	No	1/D
1	2	Classroom 216	N/A	Concrete Ceiling		Non Suspect ACM	800	SF	0					N/A	N/A	N/A
1	2	Classroom 216	N/A	Concrete Block Wall		Non Suspect ACM	800	SF	0					N/A	N/A	N/A
1	2	Classroom 216	T	Pipe Fitting Insulation	6050/01/02/20	Confirmed	42	EA	0					1	No	1/D
1	2	Classroom 216	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	200	LF	2		LF	water stains		N/A	N/A	N/A
1	2	Classroom 218	M	Floor Tile VAT 9" x 9"	6050/01/02/19	Confirmed	800	SF	0		Tan	No access during Summer inspection		1	No	1/D
1	2	Classroom 218	N/A	Concrete Ceiling		Non Suspect ACM	800	SF	0					N/A	N/A	N/A
1	2	Classroom 218	N/A	Concrete Block Wall		Non Suspect ACM	800	SF	0					N/A	N/A	N/A
1	2	Classroom 218	T	Pipe Fitting Insulation	6050/01/02/20	Confirmed	14	EA	0					1	No	1/D
1	2	Classroom 218	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	50	LF	0					N/A	N/A	N/A
1	2	Classroom 214 Closet	X	X	X	X	X	X	X	X	X			X	X	X
1	2	Women's Lounge across from Stairs #4	M	Floor Tile VAT 9" x 9"	6050/01/02/19	Confirmed	200	SF	0		Tan			1	No	1/D
1	2	Women's Lounge across from Stairs #4	N/A	Concrete Block Wall		Non Suspect ACM	200	SF	0					N/A	N/A	N/A
1	2	Women's Lounge across from Stairs #4	N/A	Concrete Ceiling		Non Suspect ACM	200	SF	0					N/A	N/A	N/A
1	2	Women's Lounge across from Stairs #4	T	Pipe Fitting Insulation	6050/01/02/20	Confirmed	11	EA	0					1	No	1/D
1	2	Women's Lounge across from Stairs #4	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	50	LF	3		LF	water stains		N/A	N/A	N/A
1	2	Women's Lounge across from Stairs #4 Restroom	N/A	Cement Floor		Non Suspect ACM	200	SF	0					N/A	N/A	N/A
1	2	Women's Lounge across from Stairs #4 Restroom	N/A	Ceramic Tile Walls		Non Suspect ACM	200	SF	0					N/A	N/A	N/A
1	2	Women's Lounge across from Stairs #4 Restroom	N/A	Concrete Ceiling		Non Suspect ACM	200	SF	0					N/A	N/A	N/A
1	2	Women's Lounge across from Stairs #4 Restroom	T	Pipe Fitting Insulation	6050/01/02/20	Confirmed	3	EA	0					1	No	1/D

6050 Philadelphia High School for Girls 2015-2016 AHERA Three-Year Report.xls

School District of Philadelphia			AHERA Three-Year Reinspection 2015-2016 Room by Room Location Log Report										Reinspection Date: 1/7/2016 Building Inspector: Alex Roman Certification Number: EHSBIR-150619-008 Management Planner: Monique Causley Certification Number: ACC-0215-8-010			
Philadelphia High School For Girls 1400 W Olney Avenue Philadelphia, PA 19141 ULCS# 6050																
Element	Floor	On Site Room Name	System Affected	Material Description	HID#	Confirmed, Assumed, NAD, Non Suspect ACM	Amount of Material	SF LF EA	Amount of Damage	SF LF EA	Color required for VAT	Comments/Description/Notes	Attic Crawlspace Ranking	Damage Potential (DP)	Newly Friable (NF)	Response Action (RA)
1	2	Women's Lounge across from Stairs #4 Restroom	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	10	LF	0					N/A	N/A	N/A
1	2	Women's Lounge across from Stairs #4 Restroom	M	Vibration Damper Cloth	6050/01/02/21	Assumed	2	EA	0					1	No	1/D
1	2	Girl's Restroom Across Classroom 221	N/A	Cement Floor		Non Suspect ACM	200	SF	0					N/A	N/A	N/A
1	2	Girl's Restroom Across Classroom 221	N/A	Concrete Ceiling		Non Suspect ACM	200	SF	0					N/A	N/A	N/A
1	2	Girl's Restroom Across Classroom 221	N/A	Ceramic Tile Walls		Non Suspect ACM	200	SF	0					N/A	N/A	N/A
1	2	Storage Closet 218A next to Classroom 218	M	Floor Tile VAT 9" x 9"	6050/01/02/19	Confirmed	200	SF	0		Tan			1	No	1/D
1	2	Storage Closet 218A next to Classroom 218	N/A	Concrete Ceiling		Non Suspect ACM	200	SF	0					N/A	N/A	N/A
1	2	Storage Closet 218A next to Classroom 218	N/A	Concrete Block Wall		Non Suspect ACM	200	SF	0					N/A	N/A	N/A
1	2	Storage Closet 218A next to Classroom 218	T	Pipe Fitting Insulation	6050/01/02/20	Confirmed	4	EA	0					1	No	1/D
1	2	Storage Closet 218A next to Classroom 218	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	20	LF	0					N/A	N/A	N/A
1	2	Slop Sink Closet in Hall by Room 218B	N/A	Cement Floor		Non Suspect ACM	50	SF	0			No access during Summer inspection		N/A	N/A	N/A
1	2	Slop Sink Closet in Hall by Room 218B	N/A	Concrete Ceiling		Non Suspect ACM	50	SF	0					N/A	N/A	N/A
1	2	Slop Sink Closet in Hall by Room 218B	N/A	Ceramic Tile Walls		Non Suspect ACM	50	SF	0					N/A	N/A	N/A
1	2	Slop Sink Closet in Hall by Room 218B	T	Pipe Fitting Insulation	6050/01/02/20	Confirmed	8	EA	0					1	No	1/D
1	2	Slop Sink Closet in Hall by Room 218B	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	30	LF	0					N/A	N/A	N/A
1	2	Hallway from Classroom 218 to 206	M	Floor Tile VAT 9" x 9"	6050/01/02/19	Confirmed	800	SF	0		Tan			1	No	1/D
1	2	Hallway from Classroom 218 to 206	N/A	Ceiling Tile 1' x 1'		NAD	800	SF	0					N/A	N/A	N/A
1	2	Hallway from Classroom 218 to 206	N/A	Ceramic Tile Walls		Non Suspect ACM	800	SF	0					N/A	N/A	N/A
1	2	Stairs #5	N/A	Cement Floor		Non Suspect ACM	200	SF	0					N/A	N/A	N/A
1	2	Stairs #5	N/A	Ceramic Tile Walls		Non Suspect ACM	200	SF	0					N/A	N/A	N/A
1	2	Stairs #5	N/A	Concrete Ceiling		Non Suspect ACM	200	SF	0					N/A	N/A	N/A
1	2	Computer Room 223 Computer Science Office	M	Floor Tile VAT 9" x 9"	6050/01/02/19	Confirmed	400	SF	0		Tan	No access during Summer inspection		1	No	1/D
1	2	Computer Room 223 Computer Science Office	N/A	Concrete Ceiling		Non Suspect ACM	400	SF	0					N/A	N/A	N/A
1	2	Computer Room 223 Computer Science Office	N/A	Concrete Block Wall		Non Suspect ACM	400	SF	0					N/A	N/A	N/A
1	2	Computer Room 223 Computer Science Office	T	Pipe Fitting Insulation	6050/01/02/20	Confirmed	8	EA	0					1	No	1/D
1	2	Computer Room 223 Computer Science Office	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	30	LF	0					N/A	N/A	N/A
1	2	Computer Room 223	M	Floor Tile VAT 9" x 9"	6050/01/02/19	Confirmed	800	SF	0		Tan	No access during Summer inspection		1	No	1/D
1	2	Computer Room 223	N/A	Concrete Ceiling		Non Suspect ACM	800	SF	0					N/A	N/A	N/A
1	2	Computer Room 223	N/A	Concrete Block Wall		Non Suspect ACM	800	SF	0					N/A	N/A	N/A
1	2	Computer Room 223	T	Pipe Fitting Insulation	6050/01/02/20	Confirmed	3	EA	0					1	No	1/D
1	2	Computer Room 223	N/A	Partition Room Dividers		Non Suspect ACM	300	SF	0					N/A	N/A	N/A
1	2	Classroom 221	M	Floor Tile VAT 9" x 9"	6050/01/02/19	Confirmed	800	SF	0		Tan	No access during Summer inspection		1	No	1/D
1	2	Classroom 221	N/A	Concrete Ceiling		Non Suspect ACM	800	SF	0					N/A	N/A	N/A
1	2	Classroom 221	N/A	Concrete Block Wall		Non Suspect ACM	800	SF	0					N/A	N/A	N/A
1	2	Classroom 221	T	Pipe Fitting Insulation	6050/01/02/20	Confirmed	3	EA	0					1	No	1/D
1	2	Room 223A English Book Storage	N/A	Concrete Block Wall		Non Suspect ACM	400	SF	0			No access during Summer inspection		N/A	N/A	N/A
1	2	Room 223A English Book Storage	N/A	Concrete Ceiling		Non Suspect ACM	400	SF	0					N/A	N/A	N/A
1	2	Room 223A English Book Storage	M	Floor Tile VAT 9" x 9"	6050/01/02/19	Confirmed	400	SF	0		Tan			1	No	1/D
1	2	Hallway leading to Classrooms 221 and 223	M	Floor Tile VAT 9" x 9"	6050/01/02/19	Confirmed	300	SF	0		Tan			1	No	1/D
1	2	Hallway leading to Classrooms 221 and 223	N/A	Ceiling Tile 1' x 1'		NAD	300	SF	0					N/A	N/A	N/A
1	2	Hallway leading to Classrooms 221 and 223	N/A	Ceramic Tile Walls		Non Suspect ACM	300	SF	0					N/A	N/A	N/A
1	2	English Book Storage Room 221A	M	Floor Tile VAT 9" x 9"	6050/01/02/19	Confirmed	300	SF	0		Tan			1	No	1/D
1	2	English Book Storage Room 221A	N/A	Concrete Ceiling		Non Suspect ACM	300	SF	0					N/A	N/A	N/A
1	2	English Book Storage Room 221A	N/A	Concrete Block Wall		Non Suspect ACM	300	SF	0					N/A	N/A	N/A
1	2	English Book Storage Room 221B	M	Floor Tile VAT 9" x 9"	6050/01/02/19	Confirmed	300	SF	0		Tan			1	No	1/D
1	2	English Book Storage Room 221B	N/A	Concrete Ceiling		Non Suspect ACM	300	SF	0					N/A	N/A	N/A
1	2	English Book Storage Room 221B	N/A	Concrete Block Wall		Non Suspect ACM	300	SF	0					N/A	N/A	N/A
1	2	Stairs #4	N/A	Ceramic Tile Walls		Non Suspect ACM	200	SF	0					N/A	N/A	N/A
1	2	Stairs #4	N/A	Concrete Ceiling		Non Suspect ACM	200	SF	0					N/A	N/A	N/A
1	2	Stairs #4	N/A	Cement Floor		Non Suspect ACM	200	SF	0					N/A	N/A	N/A
1	2	Classroom 219	M	Floor Tile VAT 9" x 9"	6050/01/02/19	Confirmed	800	SF	0		Tan			1	No	1/D
1	2	Classroom 219	N/A	Concrete Ceiling		Non Suspect ACM	800	SF	0					N/A	N/A	N/A
1	2	Classroom 219	N/A	Concrete Block Wall		Non Suspect ACM	800	SF	0					N/A	N/A	N/A
1	2	Classroom 219	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	60	LF	0					N/A	N/A	N/A
1	2	Classroom 219	T	Pipe Fitting Insulation	6050/01/02/20	Confirmed	11	EA	0					1	No	1/D
1	2	Classroom 217	M	Floor Tile VAT 9" x 9"	6050/01/02/19	Confirmed	800	SF	0		Tan	No access during Summer inspection		1	No	1/D
1	2	Classroom 217	N/A	Concrete Ceiling		Non Suspect ACM	800	SF	0					N/A	N/A	N/A
1	2	Classroom 217	N/A	Concrete Block Wall		Non Suspect ACM	800	SF	0					N/A	N/A	N/A
1	2	Classroom 217	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	60	LF	0					N/A	N/A	N/A
1	2	Classroom 217	T	Pipe Fitting Insulation	6050/01/02/20	Confirmed	18	EA	0					1	No	1/D
1	2	Stairs #3	N/A	Cement Floor		Non Suspect ACM	200	SF	0					N/A	N/A	N/A
1	2	Stairs #3	N/A	Ceramic Tile Walls		Non Suspect ACM	200	SF	0					N/A	N/A	N/A
1	2	Stairs #3	N/A	Concrete Ceiling		Non Suspect ACM	200	SF	0					N/A	N/A	N/A
1	2	Classroom 215	M	Floor Tile VAT 9" x 9"	6050/01/02/19	Confirmed	800	SF	0		Tan			1	No	1/D
1	2	Classroom 215	N/A	Concrete Ceiling		Non Suspect ACM	800	SF	0					N/A	N/A	N/A

6050 Philadelphia High School for Girls 2015-2016 AHERA Three-Year Report.xls

School District of Philadelphia			AHERA Three-Year Reinspection 2015-2016 Room by Room Location Log Report										Reinspection Date: 1/7/2016			
													Building Inspector: Alex Roman			
													Certification Number: EHSBIR-150619-008			
													Management Planner: Monique Causley			
													Certification Number: ACC-0215-8-010			
Element	Floor	On Site Room Name	System Affected	Material Description	HID#	Confirmed, Assumed, NAD, Non Suspect ACM	Amount of Material	SF LF EA	Amount of Damage	SF LF EA	Color required for VAT	Comments/Description/Notes	Attic Crawlspace Ranking	Damage Potential (DP)	Newly Friable (NF)	Response Action (RA)
1	2	Classroom 215	N/A	Concrete Block Wall		Non Suspect ACM	800	SF	0					N/A	N/A	N/A
1	2	Classroom 215	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	100	LF	1	LF				N/A	N/A	N/A
1	2	Classroom 215	T	Pipe Fitting Insulation	6050/01/02/20	Confirmed	16	EA	1	EA		New damage. DDC written up/fill in addition damage material information for Confirmed materials		1	Yes	5/B
1	2	IMC (Library)	M	Floor Tile VAT 9" x 9"	6050/01/02/19	Confirmed	1500	SF	0		Tan	No access during Summer inspection		1	No	1/D
1	2	IMC (Library)	N/A	Ceiling Tile 1' x 1'		NAD	1500	SF	0					N/A	N/A	N/A
1	2	IMC (Library)	N/A	Concrete Block Wall		Non Suspect ACM	1500	SF	0					N/A	N/A	N/A
1	2	IMC (Library)	T	Pipe Fitting Insulation	6050/01/02/20	Confirmed	2	EA	0					1	No	1/D
1	2	IMC (Library)	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	20	LF	0					N/A	N/A	N/A
1	2	Library Staff Office	X	X	X	X	X	X	X	X	X		X	X	X	X
1	2	Library Media Room	X	X	X	X	X	X	X	X	X		X	X	X	X
1	2	TV Chanel Room	M	Floor Tile VAT 9" x 9"	6050/01/02/19	Confirmed	400	SF	0		Tan	No access during Summer inspection		1	No	1/D
1	2	TV Chanel Room	N/A	Ceiling Tile 1' x 1'		NAD	400	SF	0					N/A	N/A	N/A
1	2	TV Chanel Room	N/A	Plaster Walls		NAD	400	SF	0					N/A	N/A	N/A
1	2	Classroom 211	M	Floor Tile VAT 9" x 9"	6050/01/02/19	Confirmed	800	SF	0		Tan			1	No	1/D
1	2	Classroom 211	N/A	Concrete Ceiling		Non Suspect ACM	800	SF	0					N/A	N/A	N/A
1	2	Classroom 211	N/A	Concrete Block Wall		Non Suspect ACM	800	SF	0					N/A	N/A	N/A
1	2	Classroom 211	T	Pipe Fitting Insulation	6050/01/02/20	Confirmed	12	EA	0					1	No	1/D
1	2	Classroom 211	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	60	LF	0					N/A	N/A	N/A
1	2	IMC (Library) Closet closest to the wall adjoining Room 215	M	Floor Tile VAT 9" x 9"	6050/01/02/19	Confirmed	200	SF	0		Tan	No access during Summer inspection		1	No	1/D
1	2	IMC (Library) Closet closest to the wall adjoining Room 215	N/A	Concrete Ceiling		Non Suspect ACM	200	SF	0					N/A	N/A	N/A
1	2	IMC (Library) Closet closest to the wall adjoining Room 215	N/A	Concrete Block Wall		Non Suspect ACM	200	SF	0					N/A	N/A	N/A
1	2	IMC (Library) Teacher's Work Room	M	Floor Tile VAT 9" x 9"	6050/01/02/19	Confirmed	200	SF	0		Tan	No access during Summer inspection		1	No	1/D
1	2	IMC (Library) Teacher's Work Room	N/A	Concrete Ceiling		Non Suspect ACM	200	SF	0					N/A	N/A	N/A
1	2	IMC (Library) Teacher's Work Room	N/A	Concrete Block Wall		Non Suspect ACM	200	SF	0					N/A	N/A	N/A
1	2	Stairs #2	N/A	Cement Floor		Non Suspect ACM	200	SF	0					N/A	N/A	N/A
1	2	Stairs #2	N/A	Ceramic Tile Floors		Non Suspect ACM	200	SF	0					N/A	N/A	N/A
1	2	Stairs #2	N/A	Concrete Ceiling		Non Suspect ACM	200	SF	0					N/A	N/A	N/A
1	2	Classroom 209	M	Floor Tile VAT 9" x 9"	6050/01/02/19	Confirmed	800	SF	0		Tan			1	No	1/D
1	2	Classroom 209	N/A	Concrete Block Wall		Non Suspect ACM	800	SF	0					N/A	N/A	N/A
1	2	Classroom 209	N/A	Concrete Ceiling		Non Suspect ACM	800	SF	0					N/A	N/A	N/A
1	2	Classroom 209	T	Pipe Fitting Insulation	6050/01/02/20	Confirmed	19	EA	0					1	No	1/D
1	2	Classroom 207	M	Floor Tile VAT 9" x 9"	6050/01/02/19	Confirmed	800	SF	0		Tan			1	No	1/D
1	2	Classroom 207	N/A	Concrete Block Wall		Non Suspect ACM	800	SF	0					N/A	N/A	N/A
1	2	Classroom 207	N/A	Concrete Ceiling		Non Suspect ACM	800	SF	0					N/A	N/A	N/A
1	2	Classroom 207	T	Pipe Fitting Insulation	6050/01/02/20	Confirmed	13	EA	0					1	No	1/D
1	2	Classroom 207	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	50	LF	0					N/A	N/A	N/A
1	2	Room 207A	M	Floor Tile VAT 9" x 9"	6050/01/02/19	Confirmed	400	SF	0		Tan	No access during Summer inspection		1	No	1/D
1	2	Room 207A	N/A	Concrete Block Wall		Non Suspect ACM	400	SF	0					N/A	N/A	N/A
1	2	Room 207A	N/A	Concrete Ceiling		Non Suspect ACM	400	SF	0					N/A	N/A	N/A
1	2	Room 207A	T	Pipe Fitting Insulation	6050/01/02/20	Confirmed	6	EA	0					1	No	1/D
1	2	Room 207A	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	60	LF	0					N/A	N/A	N/A
1	2	Room 203	M	Floor Tile VAT 12" x 12"	6050/01/02A3	Assumed	400	SF	0		Tan			1	No	1/D
1	2	Room 203	N/A	Concrete Block Wall		Non Suspect ACM	400	SF	0					N/A	N/A	N/A
1	2	Room 203	N/A	Concrete Ceiling		Non Suspect ACM	400	SF	0					N/A	N/A	N/A
1	2	Room 203	T	Pipe Fitting Insulation	6050/01/02/20	Confirmed	15	EA	0					1	No	1/D
1	2	Room 203	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	150	LF	0					N/A	N/A	N/A
1	2	Music Office Room 201A	M	Floor Tile VAT 12" x 12"	6050/01/02A3	Assumed	400	SF	0		Grey			1	No	1/D
1	2	Music Office Room 201A	N/A	Concrete Block Wall		Non Suspect ACM	400	SF	0					N/A	N/A	N/A
1	2	Music Office Room 201A	N/A	Concrete Ceiling		Non Suspect ACM	400	SF	0					N/A	N/A	N/A
1	2	Music Office Room 201A	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	40	LF	0					N/A	N/A	N/A
1	2	Classroom 201	M	Floor Tile VAT 9" x 9"	6050/01/02/19	Confirmed	400	SF	0		Tan			1	No	1/D
1	2	Classroom 201	N/A	Concrete Block Wall		Non Suspect ACM	400	SF	0					N/A	N/A	N/A
1	2	Classroom 201	N/A	Concrete Ceiling		Non Suspect ACM	400	SF	0					N/A	N/A	N/A
1	2	Classroom 201	T	Pipe Fitting Insulation	6050/01/02/20	Confirmed	8	EA	0					1	No	1/D
1	2	Classroom 201	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	50	LF	0					N/A	N/A	N/A
1	2	Music Room 205	M	Floor Tile VAT 9" x 9"	6050/01/02/19	Confirmed	1200	SF	0		Grey	No access during Summer inspection		1	No	1/D
1	2	Music Room 205	N/A	Concrete Block Wall		Non Suspect ACM	1200	SF	0					N/A	N/A	N/A
1	2	Music Room 205	N/A	Ceiling Tile 1' x 1'		NAD	1200	SF	0					N/A	N/A	N/A
1	2	Music Room 205 Closet	X	X	X	X	X	X	X	X	X		X	X	X	X
1	2	Music Room 205 Back Storage Area	M	Floor Tile VAT 9" x 9"	6050/01/02/19	Confirmed	400	SF	0		Tan	No access during Summer inspection		1	No	1/D
1	2	Music Room 205 Back Storage Area	N/A	Concrete Ceiling		Non Suspect ACM	400	SF	0					N/A	N/A	N/A
1	2	Music Room 205 Back Storage Area	N/A	Concrete Block Wall		Non Suspect ACM	400	SF	0					N/A	N/A	N/A

6050 Philadelphia High School for Girls 2015-2016 AHERA Three-Year Report.xls

		School District of Philadelphia		AHERA Three-Year Reinspection 2015-2016 Room by Room Location Log Report						Reinspection Date: 1/7/2016						
		Philadelphia High School For Girls								Building Inspector: Alex Roman						
		1400 W Olney Avenue								Certification Number: EHSBIR-150619-008						
		Philadelphia, PA 19141								Management Planner: Monique Causley						
		ULCS# 6050								Certification Number: ACC-0215-8-010						
Element	Room	On Site Room Name	System Affected	Material Description	HID#	Confirmed, Assumed, NAD, Non Suspect ACM	Amount of Material	SF LF EA	Amount of Damage	SF LF EA	Color required for VAT	Comments/Description/Notes	Attic Crawlspace Ranking	Damage Potential (DP)	Newly Friable (NF)	Response Action (RA)
1	2	Music Room 205 Back Storage Area	T	Duct Insulation	6050/01/02/TT	Assumed	200	SF	0					1	No	1/D
1	2	Music Room 205 Back Storage Area	T	Pipe Fitting Insulation	6050/01/02/20	Confirmed	4	EA	0					1	No	1/D
1	2	Hallway in front of Music Room 205	M	Floor Tile VAT 9" x 9"	6050/01/02/19	Confirmed	800	SF	0		Tan			1	No	1/D
1	2	Hallway in front of Music Room 205	N/A	Ceiling Tile 1' x 1'		NAD	800	SF	0					N/A	N/A	N/A
1	2	Hallway in front of Music Room 205	T	Pipe Fitting Insulation	6050/01/02/20	Confirmed	4	EA	0					1	No	1/D
1	2	Hallway in front of Music Room 205	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	100	LF	0					N/A	N/A	N/A
1	2	Hallway in front of Music Room 205	T	Radiator Insulation	6050/01/02/CRI/AR/1600	Assumed	4	EA	0					1	No	1/D
1	2	Hallway in front of Music Room 205	N/A	Ceramic Tile Walls		Non Suspect ACM	800	SF	0					N/A	N/A	N/A
1	2	Hallway to the side of Music Room 205 and Auditorium Catwalk	M	Floor Tile VAT 9" x 9"	6050/01/02/19	Confirmed	400	SF	0		Tan			1	No	1/D
1	2	Hallway to the side of Music Room 205 and Auditorium Catwalk	N/A	Ceramic Tile Walls		Non Suspect ACM	400	SF	0					N/A	N/A	N/A
1	2	Hallway to the side of Music Room 205 and Auditorium Catwalk	N/A	Ceiling Tile 1' x 1'		NAD	400	SF	0					N/A	N/A	N/A
1	2	Stairs at the north east corner behind Music Room 205	N/A	Ceramic Tile Walls		Non Suspect ACM	200	SF	0					N/A	N/A	N/A
1	2	Stairs at the north east corner behind Music Room 205	N/A	Concrete Ceiling		Non Suspect ACM	200	SF	0					N/A	N/A	N/A
1	2	Stairs at the north east corner behind Music Room 205	N/A	Cement Floor		Non Suspect ACM	200	SF	0					N/A	N/A	N/A
1	2	Stairs at the north east corner behind Music Room 205	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	5	LF	0					N/A	N/A	N/A
1	2	Stairs #1	N/A	Ceramic Tile Walls		Non Suspect ACM	200	SF	0					N/A	N/A	N/A
1	2	Stairs #1	N/A	Concrete Ceiling		Non Suspect ACM	200	SF	0					N/A	N/A	N/A
1	2	Stairs #1	N/A	Cement Floor		Non Suspect ACM	200	SF	0					N/A	N/A	N/A
1	2	Classroom 200	M	Floor Tile VAT 9" x 9"	6050/01/02/19	Confirmed	800	SF	0		Tan			1	No	1/D
1	2	Classroom 200	N/A	Concrete Ceiling		Non Suspect ACM	800	SF	0					N/A	N/A	N/A
1	2	Classroom 200	N/A	Concrete Block Wall		Non Suspect ACM	800	SF	0					N/A	N/A	N/A
1	2	Classroom 200	T	Pipe Fitting Insulation	6050/01/02/20	Confirmed	4	EA	0					1	No	1/D
1	2	Classroom 200	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	50	LF	0					N/A	N/A	N/A
1	2	Classroom 202	M	Floor Tile VAT 9" x 9"	6050/01/02/19	Confirmed	800	SF	0		Tan			1	No	1/D
1	2	Classroom 202	N/A	Concrete Ceiling		Non Suspect ACM	800	SF	0					N/A	N/A	N/A
1	2	Classroom 202	N/A	Concrete Block Wall		Non Suspect ACM	800	SF	0					N/A	N/A	N/A
1	2	Classroom 202	T	Pipe Fitting Insulation	6050/01/02/20	Confirmed	36	EA	0					1	No	1/D
1	2	Classroom 202	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	60	LF	0					N/A	N/A	N/A
1	2	Classroom 204	M	Floor Tile VAT 9" x 9"	6050/01/02/19	Confirmed	800	SF	0		Tan			1	No	1/D
1	2	Classroom 204	N/A	Concrete Ceiling		Non Suspect ACM	800	SF	0					N/A	N/A	N/A
1	2	Classroom 204	N/A	Concrete Block Wall		Non Suspect ACM	800	SF	0					N/A	N/A	N/A
1	2	Classroom 204	T	Pipe Fitting Insulation	6050/01/02/20	Confirmed	28	EA	0					1	No	1/D
1	2	Classroom 204	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	100	LF	0					N/A	N/A	N/A
1	2	Computer Network Room 200A	M	Floor Tile VAT 9" x 9"	6050/01/02/19	Confirmed	300	SF	0		Tan	No access during Summer inspection		1	No	1/D
1	2	Computer Network Room 200A	N/A	Concrete Block Wall		Non Suspect ACM	300	SF	0					N/A	N/A	N/A
1	2	Computer Network Room 200A	N/A	Concrete Ceiling		Non Suspect ACM	300	SF	0					N/A	N/A	N/A
1	2	Computer Network Room 200A	T	Pipe Fitting Insulation	6050/01/02/20	Confirmed	26	EA	2	EA		Write DDC for this damage/fill in addition damage material information for Confirmed materials		1	Yes	5/B
1	2	Computer Network Room 200A	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	100	LF	4	LF				N/A	N/A	N/A
1	2	Closet in the Hall outside Room 200A	M	Floor Tile VAT 9" x 9"	6050/01/02/19	Confirmed	50	SF	0		Tan			1	No	1/D
1	2	Closet in the Hall outside Room 200A	N/A	Concrete Block Wall		Non Suspect ACM	50	SF	0					N/A	N/A	N/A
1	2	Closet in the Hall outside Room 200A	N/A	Concrete Ceiling		Non Suspect ACM	50	SF	0					N/A	N/A	N/A
1	2	Slop Sink in the Hall outside Room 200A	N/A	Concrete Ceiling		Non Suspect ACM	50	SF	0			No access during Summer inspection		N/A	N/A	N/A
1	2	Slop Sink in the Hall outside Room 200A	N/A	Ceramic Tile Walls		Non Suspect ACM	50	SF	0					N/A	N/A	N/A
1	2	Slop Sink in the Hall outside Room 200A	N/A	Cement Floor		Non Suspect ACM	50	SF	0					N/A	N/A	N/A
1	2	Slop Sink in the Hall outside Room 200A	T	Pipe Fitting Insulation	6050/01/02/20	Confirmed	6	EA	0					1	No	1/D
1	2	Men's Restroom across Room 207A	N/A	Cement Floor		Non Suspect ACM	200	SF	0					N/A	N/A	N/A
1	2	Men's Restroom across Room 207A	N/A	Concrete Ceiling		Non Suspect ACM	200	SF	0					N/A	N/A	N/A
1	2	Men's Restroom across Room 207A	N/A	Ceramic Tile Walls		Non Suspect ACM	200	SF	0					N/A	N/A	N/A
1	2	Men's Restroom across Room 207A	M	Vibration Damper Cloth	6050/01/02/21	Assumed	2	EA	0					1	No	1/D
1	2	Men's Restroom Lounge across Room 207A	M	Floor Tile VAT 12" x 12"	6050/01/02A3	Assumed	200	SF	0		Black			1	No	1/D
1	2	Men's Restroom Lounge across Room 207A	N/A	Concrete Ceiling		Non Suspect ACM	200	SF	0					N/A	N/A	N/A
1	2	Men's Restroom Lounge across Room 207A	N/A	Concrete Block Wall		Non Suspect ACM	200	SF	0					N/A	N/A	N/A
1	2	Men's Restroom Lounge across Room 207A	T	Pipe Fitting Insulation	6050/01/02/20	Confirmed	7	EA	0					1	No	1/D
1	2	Men's Restroom Lounge across Room 207A	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	10	LF	0					N/A	N/A	N/A
1	2	Girl's Restroom across Room 203	N/A	Ceramic Tile Walls		Non Suspect ACM	200	SF	0					N/A	N/A	N/A
1	2	Girl's Restroom across Room 203	N/A	Cement Floor		Non Suspect ACM	200	SF	0					N/A	N/A	N/A
1	2	Girl's Restroom across Room 203	N/A	Concrete Ceiling		Non Suspect ACM	200	SF	0					N/A	N/A	N/A
1	2	Closet in Hall across from Room 209	M	Floor Tile VAT 9" x 9"	6050/01/02/19	Confirmed	200	SF	0		Tan			1	No	1/D
1	2	Closet in Hall across from Room 209	N/A	Concrete Block Wall		Non Suspect ACM	200	SF	0					N/A	N/A	N/A
1	2	Closet in Hall across from Room 209	N/A	Concrete Ceiling		Non Suspect ACM	200	SF	0					N/A	N/A	N/A
1	2	Closet in Hall across from Room 209	T	Pipe Fitting Insulation	6050/01/02/20	Confirmed	6	EA	0					1	No	1/D
1	2	Closet in Hall across from Room 209	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	40	LF	0					N/A	N/A	N/A
1	2	Room 204B	M	Floor Tile VAT 9" x 9"	6050/01/02/19	Confirmed	400	SF	0		Tan			1	No	1/D

6050 Philadelphia High School for Girls 2015-2016 AHERA Three-Year Report.xls

School District of Philadelphia			AHERA Three-Year Reinspection 2015-2016 Room by Room Location Log Report										Reinspection Date: 1/7/2016					
Philadelphia High School For Girls													Building Inspector: Alex Roman					
1400 W Olney Avenue													Certification Number: EHSBIR-150619-008					
Philadelphia, PA 19141													Management Planner: Monique Causley					
ULCS# 6050													Certification Number: ACC-0215-8-010					
Element	Floor	On Site Room Name	System Affected	Material Description	HID#	Confirmed, Assumed, NAD, Non Suspect ACM	Amount of Material	SF LF EA	Amount of Damage	SF LF EA	Color required for VAT	Comments/Description/Notes	Attic Crawlspace Ranking	Damage Potential (DP)	Newly Friable (NF)	Response Action (RA)		
1	2	Room 204B	N/A	Concrete Block Wall		Non Suspect ACM	400	SF	0					N/A	N/A	N/A		
1	2	Room 204B	N/A	Concrete Ceiling		Non Suspect ACM	400	SF	0					N/A	N/A	N/A		
1	2	Room 204B	T	Pipe Fitting Insulation	6050/01/02/20	Confirmed	37	EA	0					1	No	1/D		
1	2	Room 204B	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	100	LF	0					N/A	N/A	N/A		
1	2	Hallway from Stairs #2 to Stairs #1	M	Floor Tile VAT 9" x 9"	6050/01/02/19	Confirmed	800	SF	0		Tan			1	No	1/D		
1	2	Hallway from Stairs #2 to Stairs #1	N/A	Ceiling Tile 1" x 1"		NAD	800	SF	3	SF		stained		N/A	N/A	N/A		
1	2	Hallway from Stairs #2 to Stairs #1	N/A	Ceramic Tile Walls		Non Suspect ACM	800	SF	0					N/A	N/A	N/A		
1	2	Hallway from Stairs #2 to Stairs #1	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	300	LF	0					N/A	N/A	N/A		
1	3	Hallway from Stairs #2 to Stairs #1	M	Floor Tile VAT 9" x 9"	6050/01/03/23	Confirmed	800	SF	0		Tan			1	No	1/D		
1	3	Hallway from Stairs #2 to Stairs #1	N/A	Ceiling Tile 1" x 1"		NAD	800	SF	4	SF		Missing tiles exposing glue dots		N/A	N/A	N/A		
1	3	Hallway from Stairs #2 to Stairs #1	N/A	Ceramic Tile Walls		Non Suspect ACM	800	SF	0					N/A	N/A	N/A		
1	3	Hallway from Stairs #2 to Stairs #1	M	Spline Ceiling Tile Glue Dots	6050/01/03/CR/1H/2607	Assumed	200	SF	0					1	No	1/D		
1	3	Stairs #1	N/A	Ceramic Tile Walls		Non Suspect ACM	200	SF	0					N/A	N/A	N/A		
1	3	Stairs #1	N/A	Concrete Block Wall		Non Suspect ACM	200	SF	0					N/A	N/A	N/A		
1	3	Stairs #1	N/A	Concrete Ceiling		Non Suspect ACM	200	SF	0					N/A	N/A	N/A		
1	3	Classroom 300	M	Floor Tile VAT 9" x 9"	6050/01/03/23	Confirmed	800	SF	0		Tan			1	No	1/D		
1	3	Classroom 300	N/A	Concrete Ceiling		Non Suspect ACM	800	SF	0					N/A	N/A	N/A		
1	3	Classroom 300	N/A	Concrete Block Wall		Non Suspect ACM	800	SF	0					N/A	N/A	N/A		
1	3	Women's Staff Lounge	M	Floor Tile VAT 9" x 9"	6050/01/03/23	Confirmed	400	SF	0		Green			1	No	1/D		
1	3	Women's Staff Lounge	S	Textured Ceiling Paint	6050/01/03/CR/1H/2611	Assumed	400	SF	0					1	No	1/D		
1	3	Women's Staff Lounge	N/A	Concrete Block Wall		Non Suspect ACM	400	SF	0					N/A	N/A	N/A		
1	3	Restroom in Women's Staff Lounge	N/A	Cement Floor		Non Suspect ACM	45	SF	0					N/A	N/A	N/A		
1	3	Restroom in Women's Staff Lounge	N/A	Concrete Block Wall		Non Suspect ACM	300	SF	0					N/A	N/A	N/A		
1	3	Restroom in Women's Staff Lounge	N/A	Concrete Ceiling		Non Suspect ACM	45	SF	0					N/A	N/A	N/A		
1	3	Slop Sink in Hallway outside of Women's Lounge	N/A	Cement Floor		Non Suspect ACM	50	SF	0					N/A	N/A	N/A		
1	3	Slop Sink in Hallway outside of Women's Lounge	N/A	Ceramic Tile Walls		Non Suspect ACM	50	SF	0					N/A	N/A	N/A		
1	3	Slop Sink in Hallway outside of Women's Lounge	N/A	Concrete Ceiling		Non Suspect ACM	50	SF	0					N/A	N/A	N/A		
1	3	Slop Sink in Hallway outside of Women's Lounge	T	Pipe Fitting Insulation	6050/01/03/24	Confirmed	2	EA	2	EA		Write DDC for this damage/fill in addition damage material information for Confirmed materials		2	Yes	5/B		
1	3	Slop Sink in Hallway outside of Women's Lounge	M	Vibration Damper Cloth	6050/01/03/25	Assumed	1	EA	0					1	No	1/D		
1	3	Girl's Restroom next to Room 302	N/A	Concrete Ceiling		Non Suspect ACM	300	SF	0					N/A	N/A	N/A		
1	3	Girl's Restroom next to Room 302	N/A	Ceramic Tile Walls		Non Suspect ACM	300	SF	0					N/A	N/A	N/A		
1	3	Girl's Restroom next to Room 302	N/A	Cement Floor		Non Suspect ACM	300	SF	0					N/A	N/A	N/A		
1	3	Classroom 302	M	Floor Tile VAT 9" x 9"	6050/01/03/23	Confirmed	800	SF	0		Tan			1	No	1/D		
1	3	Classroom 302	N/A	Concrete Ceiling		Non Suspect ACM	800	SF	0					N/A	N/A	N/A		
1	3	Classroom 302	N/A	Concrete Block Wall		Non Suspect ACM	800	SF	0					N/A	N/A	N/A		
1	3	Classroom 302 Lab Preparation Area	M	Floor Tile VAT 9" x 9"	6050/01/03/23	Confirmed	300	SF	0		Brown			1	No	1/D		
1	3	Classroom 302 Lab Preparation Area	N/A	Concrete Ceiling		Non Suspect ACM	300	SF	0					N/A	N/A	N/A		
1	3	Classroom 302 Lab Preparation Area	N/A	Concrete Block Wall		Non Suspect ACM	800	SF	0					N/A	N/A	N/A		
1	3	Classroom 304 Bio Lab	M	Floor Tile VAT 9" x 9"	6050/01/03/23	Confirmed	800	SF	0		Tan			1	No	1/D		
1	3	Classroom 304 Bio Lab	N/A	Concrete Ceiling		Non Suspect ACM	800	SF	0					N/A	N/A	N/A		
1	3	Classroom 304 Bio Lab	N/A	Concrete Block Wall		Non Suspect ACM	800	SF	0					N/A	N/A	N/A		
1	3	Classroom 304 Lab Preparation Area	M	Floor Tile VAT 9" x 9"	6050/01/03/23	Confirmed	300	SF	0		Tan			1	No	1/D		
1	3	Classroom 304 Lab Preparation Area	N/A	Concrete Ceiling		Non Suspect ACM	300	SF	0					N/A	N/A	N/A		
1	3	Classroom 304 Lab Preparation Area	N/A	Concrete Block Wall		Non Suspect ACM	300	SF	0					N/A	N/A	N/A		
1	3	Stairs #2	N/A	Cement Floor		Non Suspect ACM	200	SF	0					N/A	N/A	N/A		
1	3	Stairs #2	N/A	Concrete Ceiling		Non Suspect ACM	200	SF	0					N/A	N/A	N/A		
1	3	Stairs #2	N/A	Ceramic Tile Walls		Non Suspect ACM	200	SF	0					N/A	N/A	N/A		
1	3	Stairs #2	T	Pipe Fitting Insulation	6050/01/03/24	Confirmed	9	EA	0					1	No	1/D		
1	3	Stairs #2	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	40	LF	0					N/A	N/A	N/A		
1	3	Classroom 307	M	Floor Tile VAT 9" x 9"	6050/01/03/23	Confirmed	800	SF	0		Tan			1	No	1/D		
1	3	Classroom 307	N/A	Concrete Ceiling		Non Suspect ACM	800	SF	0					N/A	N/A	N/A		
1	3	Classroom 307	N/A	Concrete Block Wall		Non Suspect ACM	800	SF	0					N/A	N/A	N/A		
1	3	Classroom 307	T	Pipe Fitting Insulation	6050/01/03/24	Confirmed	8	EA	0					1	No	1/D		
1	3	Classroom 307	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	40	LF	0					N/A	N/A	N/A		
1	3	Classroom 305	M	Floor Tile VAT 9" x 9"	6050/01/03/23	Confirmed	500	SF	0		Tan	No access during Summer inspection		1	No	1/D		
1	3	Classroom 305	N/A	Concrete Ceiling		Non Suspect ACM	500	SF	0					N/A	N/A	N/A		
1	3	Classroom 305	N/A	Concrete Block Wall		Non Suspect ACM	500	SF	0					N/A	N/A	N/A		
1	3	Room 303A	M	Floor Tile VAT 9" x 9"	6050/01/03/23	Confirmed	400	SF	0		Tan	No access during Summer inspection		1	No	1/D		
1	3	Room 303A	N/A	Concrete Ceiling		Non Suspect ACM	400	SF	0					N/A	N/A	N/A		
1	3	Room 303A	N/A	Concrete Block Wall		Non Suspect ACM	400	SF	0					N/A	N/A	N/A		
1	3	Chemistry Lab Room 303	M	Linoleum	6050/01/0B/WW	Assumed	800	SF	0		Grey			1	No	1/D		
1	3	Chemistry Lab Room 303	N/A	Concrete Ceiling		Non Suspect ACM	800	SF	0					N/A	N/A	N/A		
1	3	Chemistry Lab Room 303	N/A	Concrete Block Wall		Non Suspect ACM	800	SF	0					N/A	N/A	N/A		
1	3	Chemistry Lab Room 303 Prep Area	M	Linoleum	6050/01/0B/WW	Assumed	300	SF	0		Grey			1	No	1/D		
1	3	Chemistry Lab Room 303 Prep Area	N/A	Concrete Ceiling		Non Suspect ACM	300	SF	0					N/A	N/A	N/A		

6050 Philadelphia High School for Girls 2015-2016 AHERA Three-Year Report.xls

		School District of Philadelphia				AHERA Three-Year Reinspection 2015-2016 Room by Room Location Log Report							Reinspection Date: 1/7/2016 Building Inspector: Alex Roman Certification Number: EHSBIR-150619-008 Management Planner: Monique Causley Certification Number: ACC-0215-8-010						
		Philadelphia High School For Girls 1400 W Olney Avenue Philadelphia, PA 19141 ULCS# 6050																	
Element	Floor	On Site Room Name		System Affected	Material Description	HID#	Confirmed, Assumed, NAD, Non Suspect ACM	Amount of Material	SF LF EA	Amount of Damage	SF LF EA	Color required for VAT	Comments/Description/Notes	Attic Crawlspace Ranking	Damage Potential (DP)	Newly Friable (NF)	Response Action (RA)		
1	3	Chemistry Lab Room 303 Prep Area		N/A	Concrete Block Wall		Non Suspect ACM	300	SF	0					N/A	N/A	N/A		
1	3	Chemistry Lab Room 303 Chemical Storage		X	X	X	X	X	X	X	X	X			X	X	X		
1	3	Classroom 309		M	Floor Tile VAT 9" x 9"	6050/01/03/23	Confirmed	800	SF	0		Tan			1	No	1/D		
1	3	Classroom 309		N/A	Concrete Ceiling		Non Suspect ACM	800	SF	0					N/A	N/A	N/A		
1	3	Classroom 309		N/A	Concrete Block Wall		Non Suspect ACM	800	SF	0					N/A	N/A	N/A		
1	3	Classroom 309		T	Pipe Fitting Insulation	6050/01/03/24	Confirmed	6	EA	0					1	No	1/D		
1	3	Classroom 309		N/A	Fiberglass Pipe Insulation		Non Suspect ACM	40	LF	0					N/A	N/A	N/A		
1	3	Room 309A		M	Floor Tile VAT 9" x 9"	6050/01/03/23	Confirmed	300	SF	0		Tan	No access during Summer inspection		1	No	1/D		
1	3	Room 309A		N/A	Concrete Ceiling		Non Suspect ACM	300	SF	0					N/A	N/A	N/A		
1	3	Room 309A		N/A	Concrete Block Wall		Non Suspect ACM	300	SF	0					N/A	N/A	N/A		
1	3	Classroom 311		M	Floor Tile VAT 9" x 9"	6050/01/03/23	Confirmed	800	SF	0		Tan			1	No	1/D		
1	3	Classroom 311		N/A	Concrete Ceiling		Non Suspect ACM	800	SF	0					N/A	N/A	N/A		
1	3	Classroom 311		N/A	Concrete Block Wall		Non Suspect ACM	800	SF	0					N/A	N/A	N/A		
1	3	Room 311A		M	Floor Tile VAT 9" x 9"	6050/01/03/23	Confirmed	300	SF	0		Tan	No access during Summer inspection		1	No	1/D		
1	3	Room 311A		N/A	Concrete Ceiling		Non Suspect ACM	300	SF	0					N/A	N/A	N/A		
1	3	Room 311A		N/A	Concrete Block Wall		Non Suspect ACM	300	SF	0					N/A	N/A	N/A		
1	3	Classroom 313		M	Floor Tile VAT 9" x 9"	6050/01/03/23	Confirmed	800	SF	0		Tan			1	No	1/D		
1	3	Classroom 313		N/A	Concrete Ceiling		Non Suspect ACM	800	SF	0					N/A	N/A	N/A		
1	3	Classroom 313		N/A	Concrete Block Wall		Non Suspect ACM	800	SF	0					N/A	N/A	N/A		
1	3	Room 313A		M	Floor Tile VAT 9" x 9"	6050/01/03/23	Confirmed	400	SF	0		Tan			1	No	1/D		
1	3	Room 313A		N/A	Concrete Ceiling		Non Suspect ACM	400	SF	0					N/A	N/A	N/A		
1	3	Room 313A		N/A	Concrete Block Wall		Non Suspect ACM	400	SF	0					N/A	N/A	N/A		
1	3	Room 313A		T	Pipe Fitting Insulation	6050/01/03/24	Confirmed	9	EA	0					1	No	1/D		
1	3	Room 313A		N/A	Fiberglass Pipe Insulation		Non Suspect ACM	30	LF	0					N/A	N/A	N/A		
1	3	Classroom 315		M	Floor Tile VAT 9" x 9"	6050/01/03/23	Confirmed	800	SF	0		Tan			1	No	1/D		
1	3	Classroom 315		N/A	Concrete Ceiling		Non Suspect ACM	800	SF	0					N/A	N/A	N/A		
1	3	Classroom 315		N/A	Concrete Block Wall		Non Suspect ACM	800	SF	0					N/A	N/A	N/A		
1	3	Classroom 315		T	Pipe Fitting Insulation	6050/01/03/24	Confirmed	6	EA	0					1	No	1/D		
1	3	Classroom 315		N/A	Fiberglass Pipe Insulation		Non Suspect ACM	30	LF	0					N/A	N/A	N/A		
1	3	Stairs #3		N/A	Ceramic Tile Walls		Non Suspect ACM	200	SF	0					N/A	N/A	N/A		
1	3	Stairs #3		N/A	Concrete Ceiling		Non Suspect ACM	200	SF	0					N/A	N/A	N/A		
1	3	Stairs #3		N/A	Cement Floor		Non Suspect ACM	200	SF	0					N/A	N/A	N/A		
1	3	Stairs #3		N/A	Fiberglass Pipe Insulation		Non Suspect ACM	35	LF	1	LF				N/A	N/A	N/A		
1	3	Stairs #3		T	Pipe Fitting Insulation	6050/01/03/24	Confirmed	4	EA	0					1	No	1/D		
1	3	Classroom 317		M	Floor Tile VAT 9" x 9"	6050/01/03/23	Confirmed	800	SF	0		Tan			1	No	1/D		
1	3	Classroom 317		N/A	Concrete Ceiling		Non Suspect ACM	800	SF	0					N/A	N/A	N/A		
1	3	Classroom 317		N/A	Concrete Block Wall		Non Suspect ACM	800	SF	0					N/A	N/A	N/A		
1	3	Stairs #4		N/A	Ceramic Tile Walls		Non Suspect ACM	200	SF	0					N/A	N/A	N/A		
1	3	Stairs #4		N/A	Concrete Ceiling		Non Suspect ACM	200	SF	0					N/A	N/A	N/A		
1	3	Stairs #4		N/A	Cement Floor		Non Suspect ACM	200	SF	0					N/A	N/A	N/A		
1	3	Book Closet next to Stairs #4		M	Floor Tile VAT 9" x 9"	6050/01/03/23	Confirmed	400	SF	0		Tan			1	No	1/D		
1	3	Book Closet next to Stairs #4		N/A	Concrete Block Wall		Non Suspect ACM	400	SF	0					N/A	N/A	N/A		
1	3	Book Closet next to Stairs #4		N/A	Concrete Ceiling		Non Suspect ACM	400	SF	0					N/A	N/A	N/A		
1	3	Classroom 319		M	Floor Tile VAT 9" x 9"	6050/01/03/23	Confirmed	800	SF	0		Tan			1	No	1/D		
1	3	Classroom 319		N/A	Concrete Ceiling		Non Suspect ACM	800	SF	0					N/A	N/A	N/A		
1	3	Classroom 319		N/A	Concrete Block Wall		Non Suspect ACM	800	SF	0					N/A	N/A	N/A		
1	3	Classroom 321		M	Floor Tile VAT 9" x 9"	6050/01/03/23	Confirmed	800	SF	0		Tan			1	No	1/D		
1	3	Classroom 321		N/A	Concrete Ceiling		Non Suspect ACM	800	SF	0					N/A	N/A	N/A		
1	3	Classroom 321		N/A	Concrete Block Wall		Non Suspect ACM	800	SF	0					N/A	N/A	N/A		
1	3	Stairs #5		N/A	Ceramic Tile Walls		Non Suspect ACM	200	SF	0					N/A	N/A	N/A		
1	3	Stairs #5		N/A	Concrete Ceiling		Non Suspect ACM	200	SF	0					N/A	N/A	N/A		
1	3	Stairs #5		N/A	Concrete Block Wall		Non Suspect ACM	200	SF	0					N/A	N/A	N/A		
1	3	Classroom 316		M	Floor Tile VAT 9" x 9"	6050/01/03/23	Confirmed	800	SF	0		Tan			1	No	1/D		
1	3	Classroom 316		N/A	Concrete Ceiling		Non Suspect ACM	800	SF	0					N/A	N/A	N/A		
1	3	Classroom 316		N/A	Concrete Block Wall		Non Suspect ACM	800	SF	0					N/A	N/A	N/A		
1	3	Men's Staff Lounge		M	Floor Tile VAT 9" x 9"	6050/01/03/23	Confirmed	400	SF	0		Tan			1	No	1/D		
1	3	Men's Staff Lounge		S	Textured Ceiling Paint	6050/01/03/CR/1H/2611	Assumed	25	SF	0					1	No	1/D		
1	3	Men's Staff Lounge		N/A	Concrete Block Wall		Non Suspect ACM	400	SF	0					N/A	N/A	N/A		
1	3	Restroom in Men's Staff Lounge		N/A	Cement Floor		Non Suspect ACM	45	SF	0					N/A	N/A	N/A		
1	3	Restroom in Men's Staff Lounge		N/A	Concrete Block Wall		Non Suspect ACM	300	SF	0					N/A	N/A	N/A		
1	3	Restroom in Men's Staff Lounge		N/A	Concrete Ceiling		Non Suspect ACM	45	SF	0					N/A	N/A	N/A		
1	3	Slop Sink in Hallway outside of Men's Lounge		X	X	X	X	X	X	X	X	X	No access during Summer inspection		X	X	X		
1	3	Girl's Restroom next to Classroom 314		N/A	Cement Floor		Non Suspect ACM	300	SF	0					N/A	N/A	N/A		
1	3	Girl's Restroom next to Classroom 314		N/A	Concrete Ceiling		Non Suspect ACM	300	SF	0					N/A	N/A	N/A		
1	3	Girl's Restroom next to Classroom 314		N/A	Ceramic Tile Walls		Non Suspect ACM	300	SF	0					N/A	N/A	N/A		

6050 Philadelphia High School for Girls 2015-2016 AHERA Three-Year Report.xls

School District of Philadelphia			AHERA Three-Year Reinspection 2015-2016 Room by Room Location Log Report										Reinspection Date: 1/7/2016 Building Inspector: Alex Roman Certification Number: EHSBIR-150619-008 Management Planner: Monique Causley Certification Number: ACC-0215-8-010			
Philadelphia High School For Girls 1400 W Olney Avenue Philadelphia, PA 19141 ULCS# 6050																
Element	Floor	On Site Room Name	System Affected	Material Description	HID#	Confirmed, Assumed, NAD, Non Suspect ACM	Amount of Material	SF LF EA	Amount of Damage	SF LF EA	Color required for VAT	Comments/Description/Notes	Attic Crawlspace Ranking	Damage Potential (DP)	Newly Friable (NF)	Response Action (RA)
1	3	Classroom 314	M	Floor Tile VAT 9" x 9"	6050/01/03/23	Confirmed	800	SF	0		Tan			1	No	1/D
1	3	Classroom 314	N/A	Concrete Ceiling		Non Suspect ACM	800	SF	0					N/A	N/A	N/A
1	3	Classroom 314	N/A	Concrete Block Wall		Non Suspect ACM	800	SF	0					N/A	N/A	N/A
1	3	Classroom 314	M	Vibration Damper Cloth	6050/01/03/25	Assumed	2	EA	0					1	No	1/D
1	3	Classroom 314	M	Transite	6050/01/03/JJ	Assumed	50	EA	0					1	No	1/D
1	3	Classroom 312 Lab Preparation Area	M	Floor Tile VAT 9" x 9"	6050/01/03/23	Confirmed	300	SF	0		Tan			1	No	1/D
1	3	Classroom 312 Lab Preparation Area	N/A	Concrete Ceiling		Non Suspect ACM	300	SF	0					N/A	N/A	N/A
1	3	Classroom 312 Lab Preparation Area	N/A	Concrete Block Wall		Non Suspect ACM	300	SF	0					N/A	N/A	N/A
1	3	Classroom 312	M	Floor Tile VAT 9" x 9"	6050/01/03/23	Confirmed	800	SF	0		Tan			1	No	1/D
1	3	Classroom 312	N/A	Concrete Ceiling		Non Suspect ACM	800	SF	0					N/A	N/A	N/A
1	3	Classroom 312	N/A	Concrete Block Wall		Non Suspect ACM	800	SF	0					N/A	N/A	N/A
1	3	Classroom 312	M	Vibration Damper Cloth	6050/01/03/25	Assumed	2	EA	0					1	No	1/D
1	3	Classroom 312	M	Transite	6050/01/03/JJ	Assumed	50	EA	0					1	No	1/D
1	3	Classroom 308	M	Floor Tile VAT 9" x 9"	6050/01/03/23	Confirmed	800	SF	0		Tan			1	No	1/D
1	3	Classroom 308	N/A	Concrete Ceiling		Non Suspect ACM	800	SF	0					N/A	N/A	N/A
1	3	Classroom 308	N/A	Concrete Block Wall		Non Suspect ACM	800	SF	0					N/A	N/A	N/A
1	3	Classroom 308	M	Vibration Damper Cloth	6050/01/03/25	Assumed	2	EA	0					1	No	1/D
1	3	Classroom 308	M	Transite	6050/01/03/JJ	Assumed	50	EA	0					1	No	1/D
1	3	Classroom 310	M	Floor Tile VAT 9" x 9"	6050/01/03/23	Confirmed	800	SF	0		Tan			1	No	1/D
1	3	Classroom 310	N/A	Concrete Ceiling		Non Suspect ACM	800	SF	0					N/A	N/A	N/A
1	3	Classroom 310	N/A	Concrete Block Wall		Non Suspect ACM	800	SF	0					N/A	N/A	N/A
1	3	Classroom 310 Lab Preparation Area	M	Floor Tile VAT 9" x 9"	6050/01/03/23	Confirmed	300	SF	0		Tan			1	No	1/D
1	3	Classroom 310 Lab Preparation Area	N/A	Concrete Ceiling		Non Suspect ACM	300	SF	0					N/A	N/A	N/A
1	3	Classroom 310 Lab Preparation Area	N/A	Concrete Block Wall		Non Suspect ACM	300	SF	0					N/A	N/A	N/A
1	3	Classroom 306 Lab Preparation Area	M	Floor Tile VAT 9" x 9"	6050/01/03/23	Confirmed	300	SF	0		Tan			1	No	1/D
1	3	Classroom 306 Lab Preparation Area	N/A	Concrete Ceiling		Non Suspect ACM	300	SF	0					N/A	N/A	N/A
1	3	Classroom 306 Lab Preparation Area	N/A	Concrete Block Wall		Non Suspect ACM	300	SF	0					N/A	N/A	N/A
1	3	Classroom 306	M	Floor Tile VAT 9" x 9"	6050/01/03/23	Confirmed	800	SF	0		Tan			1	No	1/D
1	3	Classroom 306	N/A	Concrete Ceiling		Non Suspect ACM	800	SF	0					N/A	N/A	N/A
1	3	Classroom 306	N/A	Concrete Block Wall		Non Suspect ACM	800	SF	0					N/A	N/A	N/A
1	3	Hallway from Stairs #5 to Classroom 306	M	Floor Tile VAT 9" x 9"	6050/01/03/23	Confirmed	800	SF	0		Tan			1	No	1/D
1	3	Hallway from Stairs #5 to Classroom 306	N/A	Ceramic Tile Walls		Non Suspect ACM	800	SF	0					N/A	N/A	N/A
1	3	Hallway from Stairs #5 to Classroom 306	N/A	Ceiling Tile 1' x 1'		NAD	800	SF	8		SF	Missing tiles with brown glue dots exposed		N/A	N/A	N/A
1	3	Hallway from Stairs #5 to Classroom 306	M	Spline Ceiling Tile Glue Dots	6050/01/03/CR/I/H/2607	Assumed	200	SF	0					1	No	1/D
1	C	Ground Fl. Crawl Space @ Fan Rm #1 by Stairwell #1	x	x	X	x	x	x	x	x	x	Entrance door is signed not sealed/	C	x	x	x
1	C	Sub Bsmnt/Crawlspace @ Elec Rm in Boiler Rm	x	x	X	x	x	x	x	x	x	50 Hard Fitting/Fiberglass PI	"C to B"	x	x	x
1	C	Sub Bsmnt/Crawl Space @ Elevator Lobby	x	x	X	x	x	x	x	x	x	Local Debris/ Not signed or sealed 1 damaged Fittings	C	x	x	x
1	A	Attic	x	x	X	x	x	x	x	x	x	None	None	x	x	x

Section III Certificates

A. Management Planner/Building Inspector Certificates

Section III – A

Management Planner/Building Inspector Certificates

These charts indicate the Name, Course Date, Expiration Date and Corresponding Certificate Number of the Management Planner and Building Inspector of individuals that participated in the AHERA 3 Year Inspection and Management Plan process of 2015/2016.

Management Planner	Date Granted	Expiration Date	Certificate Number
Monique Causley	2/15/2015	2/16/2016	ACC-0215-8-010
Monique Causley	2/16/2016	2/17/2017	ACC-0216-8-001
Megan Vala	5/22/2015	6/22/2016	740728
Mary Anne Lerro	4/5/2016	4/5/2017	742327

Building Inspector	Date Granted	Expiration Date	Certificate Number
Scott Magee	8/15/2015	8/15/2016	70016699C
William Garrity	8/15/2015	8/15/2016	70016699A
Bernard Brunner	10/2/2015	8/2/2016	45397
Mary Anne Lerro	3/3/2015	3/3/2016	740092
Mary Anne Lerro	4/5/2016	4/5/2017	742322
James Madden	12/11/2014	12/11/2015	ACC-1214-6-010
James Madden	12/3/2015	12/3/2016	ACC-1215-6-018
Troy Ray	3/15/2015	3/19/2016	ACC-0355-6-011
Ananth Vinjamuri	9/29/2015	9/29/2016	374
Shelton Williams	9/29/2015	9/29/2016	375
Paul Davis	2/12/2015	2/12/2016	ACC-0215-6-015
Paul Davis	2/2/2016	2/2/2017	741836
Bernard Bryson	2/16/2015	2/16/2016	ACC-0125-6-031
Bernard Bryson	2/15/2016	2/15/2017	ACC-0216-6-005
Alexander Roman	9/18/2015	9/18/2016	EHSBIR-150619-008
Norm Harrison	9/2/2015	9/2/2016	ACC-0915-6-011
Kelly Mayberry	2/20/2015	2/20/2016	EHSBIR-150220-005
Kelly Mayberry	2/18/2016	2/18/2017	EHSBIR-160218-006
Andrew Hine	5/6/2015	5/6/2016	AI05042015-3
Maryellen Leotta	2/12/2015	2/12/2016	ACC-0215-6-024

Certificate of Completion

awarded to

Monique Causley

for successfully completing the prescribed course of study in

Pennsylvania Asbestos Management Planner Refresher Course

under TSCA Title II

presented by

ACCESS TRAINING SERVICES, INC.
7921 River Road, Pennsauken, NJ 08110
(856) 665-3449

2/16/15

Course Date

N/A

Exam Date

2/16/16

Expiration Date

Not Provided

Social Security Number

ACC-0215-8-010

Certificate Number

Mark K. Schlüger
Training Director

Certificate of Completion

awarded to

Monique Causley

for successfully completing the prescribed course of study in

Pennsylvania Asbestos Management Planner Refresher Course

under TSCA Title II

presented by

ACCESS TRAINING SERVICES, INC.
7921 River Road, Pennsauken, NJ 08110
(856) 665-3449

2/15/16

Course Date

N/A

Exam Date

2/15/17

Expiration Date

Not Provided

Social Security Number

ACC-0216-8-001

Certificate Number

Mark K. Schlüger
Training Director

Certificate of Training

CRITERION LABORATORIES, INC.

HEREBY CERTIFIES THAT

Megan Vala

HAS SUCCESSFULLY COMPLETED A 16 HOUR COURSE ENTITLED

Asbestos Management Planner Initial

INCLUDING CLASSROOM INSTRUCTION

05/21/2015 to 05/22/2015

Exam passed on this 22nd day of May 2015 - Score - 94

Approved for AHERA Accreditation Under TSCA Title II

3370 Progress Drive, Suite J
Bensalem, PA 19020
(215) 244-1300 - Phone
(215) 244-4349 - Fax
www.criterionlabs.com

Course is conducted in English

DIRECTOR:



James A. Welts, CIH, President

Certificate of Training

CRITERION LABORATORIES, INC.

HEREBY CERTIFIES THAT

Mary Anne Lerro

HAS SUCCESSFULLY COMPLETED A 4 HOUR COURSE ENTITLED

Asbestos Management Planner Refresher

INCLUDING CLASSROOM INSTRUCTION


on this 5th day of April 2016

Approved for AHERA Accreditation Under TSCA Title II

3370 Progress Drive, Suite J
Bensalem, PA 19020
(215) 244-1300 - Phone
(215) 244-4349 - Fax
www.criterionlabs.com

Course is conducted in English

DIRECTOR:



James A. Welts, CIH, President

EMSL ANALYTICAL, INC.

Certifies that

Scott Magee

has successfully completed the course of study for the

Asbestos Building Inspector Refresher Course

for Accreditation under TSCA Title II

EMSL Certificate No. 70016699C


Approved by:

PA Dept. of Labor and Industry
Accreditation # 137

Course Date: 8/15/2015
Granted: 8/15/2015
Expiration Date: 8/15/2016

Sponsored by:

EMSL Analytical, Inc.
200 Route 130 North
Cinnaminson, NJ 08077
Phone: (800) 220-3675
Fax: (856) 786-5973
www.emsl.com



Michael P. Menz

Michael P. Menz, CIH
Training Director

Environmental, Mold, Bacteria, IAQ, Asbestos, Lead, Forensic and Materials Testing Since 1981

EMSL ANALYTICAL, INC.

Certifies that

William Garrity

has successfully completed the course of study for the

Asbestos Building Inspector Refresher Course for Accreditation under TSCA Title II

EMSL Certificate No. 70016699A


Approved by:

PA Dept. of Labor and Industry
Accreditation # 137

Course Date: 8/15/2015
Granted: 8/15/2015
Expiration Date: 8/15/2016

Sponsored by:

EMSL Analytical, Inc.
200 Route 130 North
Cinnaminson, NJ 08077
Phone: (800) 220-3675
Fax: (856) 786-5973
www.emsl.com



Michael P. Menz

Michael P. Menz, CIH
Training Director

Environmental, Mold, Bacteria, IAQ, Asbestos, Lead, Forensic and Materials Testing Since 1981

45397

National Asbestos & Environmental Training Institute

CERTIFICATE OF COMPLETION

AHERA/EPA Accredited Per 40 CFR Part 763
Asbestos Accreditation under TSCA Title II

This is to certify that

Bernard Brunner, Jr.

Successfully completed the course entitled

**1/2-Day New York State/EPA/AHERA Asbestos Building Inspector Annual Refresher on
October 2, 2015**

Examination Passed October 2, 2015

Expiration Date on October 2, 2016


Doris L. Adler
President, NAEETI

Per 10 NYCRR Part 73.2 (L) (1), DOH 2832 Certificate of Completion of Asbestos
Safety Training is the only official record of training for N.Y.S. students.

Language: English

ABIH 1/2 CM POINT

3321 Doris Avenue, Building B, Ocean, NJ 07712

Phone (732) 531-5571

Fax (732) 531-5956

www.naeti.com

Number 740092

Expiration Date:
03/03/2016

Certificate of Training

CRITERION LABORATORIES, INC.

HEREBY CERTIFIES THAT

Mary Anne Lerro

HAS SUCCESSFULLY COMPLETED A 4 HOUR COURSE ENTITLED

Asbestos Building Inspector Refresher

on this 3rd day of March 2015

Exam passed on this 3rd day of March 2015 - Score - 84

Approved for AHERA Accreditation Under TSCA Title II

3370 Progress Drive, Suite J
Bensalem, PA 19020
(215) 244-1300 - Phone
(215) 244-4349 - Fax
www.criterionlabs.com

Course is conducted in English

DIRECTOR:

James A. Weltz
James A. Weltz, CIH, President

Certificate of Training

CRITERION LABORATORIES, INC.

HEREBY CERTIFIES THAT

Mary Anne Lerro

HAS SUCCESSFULLY COMPLETED A 4 HOUR COURSE ENTITLED

Asbestos Building Inspector Refresher

INCLUDING CLASSROOM INSTRUCTION

on this 5th day of April 2016


Exam passed on this 5th day of April 2016 - Score - 88

Approved for AHERA Accreditation Under TSCA Title II

3370 Progress Drive, Suite J
Bensalem, PA 19020
(215) 244-1300 - Phone
(215) 244-4349 - Fax
www.criterionlabs.com

Course is conducted in English

DIRECTOR:



James A. Welts, CIH, President

Certificate of Completion

James Madden

for successfully completing the prescribed course of study in

Pennsylvania Asbestos Building Inspector Refresher Course

under TSCA Title II

presented by

ACCESS TRAINING SERVICES, INC.
7921 River Road, Pennsauken, NJ 08110
(856) 665-3449

12/11/14

Course Date

N/A

Exam Date

12/11/15

Expiration Date

Not Provided

Social Security Number

ACC-1214-6-010

Certificate Number

Mark K. Schlüger
Training Director

Certificate of Completion

James Madden

for successfully completing the prescribed course of study in

Pennsylvania Asbestos Building Inspector Refresher Course

under TSCA Title II

presented by

ACCESS TRAINING SERVICES, INC.
7921 River Road, Pennsauken, NJ 08110
(856) 665-3449

12/3/15

Course Date

N/A

Exam Date

12/3/16

Expiration Date

Not Provided

Social Security Number

ACC-1215-6-018

Certificate Number

Mark K. Schlüger
Training Director

Certificate of Completion

Troy A. Ray

for successfully completing the prescribed course of study in

Pennsylvania Asbestos Building Inspector Refresher Course

under TSCA Title II

presented by

ACCESS TRAINING SERVICES, INC.
7921 River Road, Pennsauken, NJ 08110
(856) 665-3449

3/19/15

Course Date

N/A

Exam Date

3/19/16

Expiration Date

Not Provided

Social Security Number

ACC-0355-6-011

Certificate Number

Mark K. Schlager
Training Director

CERTIFICATE NO 374

G&C Environmental Services, Inc. (#294)
2 Street Road, Newtown Square, Pennsylvania 19073
Telephone: (610) 993-9202 Facsimile: (610) 993-9232
Email: Training@gcenviro.com
www.GCenviro.com

This document certifies that Ananth K. Vinjamuri has successfully completed this
State of New York Department of Health Approved AHERA BUILDING INSPECTOR

REFRESHER COURSE, completed as required for asbestos accreditation under the Toxic

Substances Control Act, Title II. This course was held from 09/29/2015 to 09/29/2015.
MM DD YR MM DD YR

The examination date was 09/29/2015. This certificate expires one year from the date of
MM DD YR MM DD YR
successful completion of the examination 09/29/2016.
MM DD YR

*The official record of successful training completion is the New York State Department of
Health certificate of asbestos safety training completion (DPH 2832).*

Gail M. Conner
Training Director

Gail M. Conner

CERTIFICATE NO 375

G&C Environmental Services, Inc. (#294)

2 Street Road, Newtown Square, Pennsylvania 19073

Telephone: (610) 993-9202 Facsimile: (610) 993-9232

Email: Training@gcenviro.com

www.GCenviro.com

This document certifies that Shelton Williams has successfully completed this

State of New York Department of Health Approved AHERA BUILDING INSPECTOR

REFRESHER COURSE, completed as required for asbestos accreditation under the Toxic

Substances Control Act, Title II. This course was held from 09/29/2015 to 09/29/2015.

The examination date was 09/29/2015. This certificate expires one year from the date of

successful completion of the examination 09/29/2016.

The official record of successful training completion is the New York State Department of Health certificate of asbestos safety training completion (DPH 2832).

Gail M. Conner

Training Director

Gail M. Conner

Certificate of Completion

Paul M. Davis

for successfully completing the prescribed course of study in

Pennsylvania Asbestos Building Inspector Refresher Course

under TSCA Title II

presented by

ACCESS TRAINING SERVICES, INC.
7921 River Road, Pennsauken, NJ 08110
(856) 665-3449

2/12/15

Course Date

N/A

Exam Date

2/12/16

Expiration Date

Not Provided

Social Security Number

ACC-0215-6-015

Certificate Number

Mark K. Schlüger
Training Director

Certificate of Training

CRITERION LABORATORIES, INC.

HEREBY CERTIFIES THAT

Paul M. Davis

HAS SUCCESSFULLY COMPLETED A 4 HOUR COURSE ENTITLED

Asbestos Building Inspector Refresher

INCLUDING CLASSROOM INSTRUCTION

on this 2nd day of February 2016

Exam passed on this 2nd day of February 2016 - Score - 92

Approved for AHERA Accreditation Under TSCA Title II

3370 Progress Drive, Suite J
Bensalem, PA 19020
(215) 244-1300 - Phone
(215) 244-4349 - Fax
www.criterionlabs.com

Course is conducted in English

DIRECTOR:



James A. Welch, CIH, President

Certificate of Completion

Bernard J. Bryson


for successfully completing the prescribed course of study in

Pennsylvania Asbestos Building Inspector Refresher Course

under TSCA Title II

presented by

ACCESS TRAINING SERVICES, INC.
7921 River Road, Pennsauken, NJ 08110
(856) 665-3449

2/16/15	N/A	2/16/16
<i>Course Date</i>	<i>Exam Date</i>	<i>Expiration Date</i>
Not Provided	ACC-0125-6-031	
<i>Social Security Number</i>	<i>Certificate Number</i>	Mark K. Schlager <i>Training Director</i>

Certificate of Completion

Bernard J. Bryson

for successfully completing the prescribed course of study in

Pennsylvania Asbestos Building Inspector Refresher Course

under TSCA Title II

presented by

ACCESS TRAINING SERVICES, INC.
7921 River Road, Pennsauken, NJ 08110
(856) 665-3449

2/15/16

Course Date

N/A

Exam Date

2/15/17

Expiration Date

Not Provided

Social Security Number

ACC-0216-6-005

Certificate Number

Mark K. Schlager
Training Director

EHS TRAINING INSTITUTE, INC.
A Division of BATTI, Inc.

Certificate of Completion

AHERA Building Inspector

(Refresher)

Awarded To:

Alexander Roman

SS#:XXX-XX-1743
Who has completed this 4-hour course and examination,
EPA Approved under TSCA Title II
AHERA / ASHARA Rule
40 CFR Part 763.

EHS TRAINING INSTITUTE, INC.

A Division of BATTI, Inc.

Delaware Industrial Park • 6 Garfield Way

Newark, DE 19713-5817

(302) 737-3376 • Fax (302) 737-5764

Course Date: September 18, 2015

Date of Expiration: September 18, 201

Certification Number : EHSBIR 150619-008


Todd K. Zeisloff, Instructor


Neeraj K. Batta, President

Certificate of Completion

Norman Harrison

for successfully completing the prescribed course of study in

Pennsylvania Asbestos Building Inspector Refresher Course

under TSCA Title II

presented by
ACCESS TRAINING SERVICES, INC.
7921 River Road, Pennsauken, NJ 08109
(856) 665-3449

9/2/15

Course Date

N/A

Exam Date

9/2/16

Expiration Date

Not Provided

Social Security Number

ACC-0915-6-011

Certificate Number

Mark K. Schlager
Mark K. Schlager
Training Director

EHS TRAINING INSTITUTE, INC.
A Division of BATTI, Inc.

Certificate of Completion

AHERA Building Inspector

(Refresher)

Awarded To:

Kelly Mayberry

SS#:XXX-XX-1551

Who has completed this 4-hour course and examination,

EPA Approved under TSCA Title II

AHERA / ASHARA Rule

40 CFR Part 763.

EHS TRAINING INSTITUTE, INC.

A Division of BATTI, Inc.

Delaware Industrial Park • 6 Garfield Way

Newark, DE 19713-5817

(302) 737-3376 • Fax (302) 737-5764

Course Date: February 20, 2015

Date of Expiration: February 20, 2016

Certification Number : EHSBIR 150220-005


Todd K. Zeislott, Instructor


Neeraj K. Batta, President

EHS TRAINING INSTITUTE, INC.

A Division of BATA, Inc.

Certificate of Completion

AHERA Building Inspector

(Refresher)

Awarded To:

Kelly Mayberry

SS#:XXX-XX-1551

Who has completed this 4-hour course and examination,

EPA Approved under TSCA Title II

AHERA / ASHARA Rule

40 CFR Part 763.

EHS TRAINING INSTITUTE, INC.

A Division of BATA, Inc.

Delaware Industrial Park • 6 Garfield Way

Newark, DE 19713-5817

(302) 737-3376 • Fax (302) 737-5764

Course Date: February 18, 2016

Date of Expiration: February 18, 2017

Certification Number : EHSBIR 160218-006

Todd K. Zeisloff, Instructor

Neeraj K. Batta, President

AEROSOL MONITORING & ANALYSIS, INC.

This is to certify that
ANDREW HINE

*has met the attendance requirements and successfully completed
the course entitled*

3-DAY EPA AHERA INSPECTOR
For Accreditation Under TSCA Title II

05/04/2015 to 05/06/2015

Course Date

05/06/2015

Exam Date

5/6/2016

Expiration Date

STEVE SIERACKI

Principal Instructor

Steve Sieracki

A105042015-3

Certification No.

E. Rush Barnett

Course Director

E. Rush Barnett

1331 Ashton Road

P.O.Box 646

Hanover, MD 21076

P: 410-684-3327

F: 410-684-3724

www.amatraining.com

Certificate of Completion

Maryellen Leotta

for successfully completing the prescribed course of study in

Pennsylvania Asbestos Building Inspector Refresher Course

under TSCA Title II

presented by

ACCESS TRAINING SERVICES, INC.
7921 River Road, Pennsauken, NJ 08110
(856) 665-3449

2/12/15

Course Date

N/A

Exam Date

2/12/16

Expiration Date

Not Provided

Social Security Number

ACC-0215-6-024

Certificate Number

Mark K. Schlager
Training Director

Section IV Cross Reference Table

Asbestos Hazard Emergency Response Act (AHERA) Environmental Compliance Audit Cross Reference Table

In response to the AHERA Environmental Compliance Audit a Cross Reference Table has been prepared for inclusion into the Environmental Management Plan. The purpose of this Cross Reference Table is to link the following documents to the AHERA Management Plan.

Cross Reference Table	
3 Year Reinspection Report follows this Cross Reference Table documentation.	
Subject Matter	Location of Required Documents
Designated Person	Pages 1 - 3
Annual Notification	Pages 4 - 5
6 Month Periodic Surveillance Outline of Events	Page 6
3 Year Re-inspections Outline of Events	Page 7
Asbestos Management Program (operations and maintenance)	Pages 8 - 19
Asbestos Investigation Report (AIR)	Attachment 1 Letter Dated August 4, 2006
Training (included in the Asbestos Management Program)	<p>The original records are centralized at the School District's Environmental Library. Copies are maintained on staff and are required to be maintained in the latest Reinspection Report.</p> <p>2 hour awareness training records for all Building Engineers, Custodian Assistants and maintenance personnel</p> <p>40 hour worker/supervisor training records for the OEMS A-Team and various AST tradesmen.</p>
Response Actions (monthly mailings if applicable)	The original documents are on file at the School District's Environmental Library.
	Copies of the original are mailed to the Schools Main Office for retention with the Management Plan documentation. These documents are typically kept separate from the management plan in an update binder due to the potential volume of response action reports.

SCHOOL DISTRICT OF PHILADELPHIA

ASBESTOS DESIGNATED PERSON

Gerald F Junod
Office of Capital Programs
Environmental Management & Services
440 N Broad Street, 3rd Floor
Philadelphia, PA 19130
Telephone: 215 400 6738
Fax: 215 400 4751

Drexel University- Asbestos Building Inspector Course	January 9-11, 1989 24 Hours
Drexel University- Asbestos Management Planner Course	January 12-13, 1989 16 Hours
Criterion Laboratories, Inc. - Asbestos Management Planner Course	October 11-12, 2012 16 Hours

<u>Annual Building Inspector Refreshers</u> 4 Hours Drexel University Criterion Laboratories, Inc Access Training Services, Inc.	1990 to Present
---	------------------------

<u>Annual Building Management Planner Refreshers</u> 4 Hours Drexel University Criterion Laboratories, Inc 4 Hours	1990 to 1994 2013 to Present
---	---

Environmental Manager, School District of Philadelphia

Manages the design and implementation of asbestos and lead projects for the Capital Improvement Program and other District Departments including Facilities & Operations and Information Technology. Ensures that asbestos abatement and lead remediation projects are expertly designed and executed in accordance with industry best management practice standards and regulations.

Manager, City of Philadelphia Asbestos Control Program

Served as the Asbestos Control Program Manager for the City of Philadelphia, Department of Public Health, Air Management Services, Asbestos Control Unit from August 1, 2003 through October 23, 2006.

Mid Atlantic Regional Environmental Consortium (MAREC)

Former member with attendance and participation commitments of all quarterly EPA Region III and yearly National Asbestos Regulatory Conferences sponsored by the EPA and the National Conference of State Legislators respectively as a representative for the City of Philadelphia Department of Public Health Air Management Services from 1994 through 2006.

Philadelphia Environmental Task Force

Former member of the Philadelphia Environmental Task force as a representative and point of contact for the City of Philadelphia Department of Public Health Air Management Services Asbestos Control Unit from 2002 through 2006.

Asbestos Instructor

Worked as the primary instructor for the initial and annual Asbestos Project Inspector training and licensing program as mandated by City of Philadelphia Department of Public Health Asbestos Control Regulations from August 1994 through October 2006.

Worked as a lead instructor with an Environmental Consulting Firm and approved by the US EPA for the initial and annual refresher training courses for various asbestos occupational disciplines such as the Building Inspector, Management Planner and Worker/Supervisor from 1991 through 1994.

I certify that the general, local agency responsibilities as stipulated in Section 763.84 will be met.



Gerald F. Junod

Asbestos Designated Person

Environmental Manager

Office of Environmental Management and Services

SCHOOL DISTRICT OF PHILADELPHIA

Accreditation Information Statement

All persons who inspect for Asbestos Containing Building Materials (ACBM) and who will design or carry out response actions with respect to assumed and confirmed ACBM, will be accredited by an EPA approved course and/or a State Contractors Accreditation Program under Sections 206 (c) and 206 (b) of Title II of the ACT.



**Gerald F. Junod
Asbestos Designated Person
Environmental Manager
Office of Environmental Management and Services**

SCHOOL DISTRICT OF PHILADELPHIA
OFFICE OF CAPITAL PROGRAMS
440 NORTH BROAD STREET, SUITE 373
PHILADELPHIA, PENNSYLVANIA 19130

OFFICE OF ENVIRONMENTAL MANAGEMENT AND SERVICES

PHONE (215)-400-4750

September 2015

TO: Principals
Building Administrators/Occupants
Parents/Guardians

FROM: Fran Burns
Chief Operating Officer

Francine Locke, M.S., Director
Office of Environmental Management and Services

SUBJECT: Annual EPA Notification Letter


Pursuant to the Federal Environmental Protection Agency (EPA) mandate, as required by 40 C.F.R. 763.84 (c)(d) of public access to environmental records, this letter is to acknowledge the availability of your facility's Asbestos Hazard Emergency Response Act (AHERA) Management Plan.

Each member of the school staff, parents/guardians, temporary workers and/or contractors, are required to receive a copy of the Notification Letter. At the direction of the Principal, a copy is to be posted on the bulletin boards and an appropriate amount of copies are to be generated for distribution.


Note: The AHERA Three-Year Reinspection reports, in colored binders; White with Pink, Tan, Black, Red, Dark Blue, Green, Yellow and White, are Federal EPA mandated inspection documents. The School District of Philadelphia is subject to severe monetary penalties if the reports and associated paperwork are not available to the EPA and the public upon request.

It is incumbent on designated school personnel to gather and retain this data as it is delivered, in one location for future review. Acceptable locations include the Principal's Office or Main Office for the primary data. The Building Engineer should maintain any secondary or duplicate copies.

If you have any questions, please call 215-400-4750. Thank you for your cooperation.



Fran Burns
Chief Operating Officer



Francine Locke, M.S., Director
Office of Environmental Management
and Services

c: Danielle Floyd

AHERA-4
8/21/15



School District of Philadelphia
OFFICIAL NOTICE

PLEASE POST

September 2015

TO: Principals
Building Administrators
Building Engineers
Building Occupants
Parents/Guardians

FROM: Fran Burns
Chief Operating Officer

Francine Locke, M.S., Director
Office of Environmental Management and Services

SUBJECT: Annual Notification Letter: Asbestos Hazard Emergency Response Act

The Federal Register published on October 30, 1987, Subpart E, in Schools: Final Rule and Notice, 763.84 (c)(d) states that each local education agency shall ensure that workers and building occupants or guardians are to be informed at least once each school year about inspections, response actions and post-response action activities including re-inspections and periodic surveillance activities. The School District as the Local Education Agency (LEA), retains such reports that are available for public inspection in the Office of the Principal or Building Administrator.

The Principal or Building Administrator is required to do the following with this notification:

- 1) Post in a Public Place or Main Office
- 2) Inform Building Occupants
- 3) Send a copy of this notification to Parents or Guardians
- 4) Insert a copy into the latest AHERA Three-Year Reinspection report (white/pink binder) in your office or facility.

Fran Burns
Chief Operating Officer

Francine Locke, M.S., Director
Office of Environmental Management
and Services

c: Danielle Floyd

AHERA-4a
8/21/15

SCHOOL DISTRICT OF PHILADELPHIA
Education Center
440 North Broad Street
Philadelphia, Pennsylvania 19130

Office of Environmental Management and Services

215-400-4750

AHERA
Six Month Surveillance
Outline of Events

- Pursuant to the Federal Environmental Protection Agency (EPA) mandate, as required by 40 CFR 763.92(b), the following procedure is to be implemented. At least once every six (6) months after a Management Plan is in effect, each Local Education Agency (LEA) shall conduct a periodic surveillance in each building that it owns or leases that contains Asbestos Containing Building Materials (ACBM) or is assumed to contain ACBM.
- The first Bi-Annual Inspection starts in the Spring (March, April, May) and again in the Fall (October, November, December) of each year. The Building Engineer/Assistant should assist the Building Inspector with appropriate access to all areas including (Crawlspace/Attics) and rooms in the facility. There is no action required of the Principal.
- The Building Inspector shall visually inspect all areas that are identified in the Management Plan as ACBM or assumed ACBM. The date of the surveillance is recorded, the inspectors name and any changes in the conditions of the materials.
- The Building Inspector shall make a copy of the inspection document and insert into the front of the latest Management Plan (AHERA Three Year Reinspection report). The original document is returned to the LEA's Environmental Library and filed.

SCHOOL DISTRICT OF PHILADELPHIA
Education Center
440 North Broad Street
Philadelphia, Pennsylvania 19130

Office of Environmental Management and Services

215-400-4750

AHERA
Three Year Reinspection
Outline of Events

- Pursuant to the Federal Environmental Protection Agency (EPA) mandate, as required by 40 CFR 763.85(b) the following procedure is to be implemented. At least once every three (3) years after a Management Plan is in effect, each Local Education Agency (LEA) shall conduct a reinspection of each building that it owns or leases that contains Asbestos Containing Building Material's (ACBM's) or is assumed to contain ACBM.
- Subsequent Three Year Re-inspections (2009, 2012, 2015, etc) shall start in the Fall (October, November, December, January). The Building Engineer/Assistant should assist the Building Inspector with appropriate access to all areas including (Crawlspaces/Attics) and rooms in the facility. There is no action required of the Principal.
- An accredited Building Inspector shall visually inspect and touch to determine friability, all areas that are identified in the Management Plan as ACBM or assumed ACBM. The date of the surveillance is recorded, the inspectors name and any changes in the conditions of the materials. The Building Inspectors state of accreditation and license number is required.
- After the inspection, the Building Inspector shall make a copy of the inspection documents and insert into the front of the latest Management Plan (AHERA Three Year Reinspection report). The original document is returned to the LEA's Environmental Library and filed.
- The Building Inspector shall return the reinspection data to the Management Planner to be assessed and determine appropriate response actions and a report issued (AHERA Three Year Reinspection report). One copy of the report is delivered to the schools Principal to be permanently retained with all previous environmental data. Another copy is retained in the LEA's Environmental Library.



School District of Philadelphia
Office of Environmental Management & Services
440 North Broad Street
Philadelphia, PA 19130
(215) 400-4750

**School District of Philadelphia
Asbestos Management Program**

TABLE OF CONTENTS

Definitions.....	Page 9
1. Introduction.....	Page 10
2. Summary of Asbestos Management Plan	
3. Asbestos Management Plan Execution.....	Page 11
a. General Execution	
4. Summary of Program Execution	
a. Asbestos Management Plan Execution	
5. Responsibilities	
a. OEMS	
b. Asbestos Worker/Supervisor “A-TEAM”.....	Page 12
c. Asbestos Designated Person	
d. Supervisor or Project Manager (Capital, Maintenance & Facilities)	
e. Employee Capital.....	Page 13
f. Employee Maintenance	
g. Employee Facilities and Custodial	
6. Requirements.....	Page 14
a. Employee Exposure Monitoring	
b. Employee Notification	
c. Observation of Monitoring	
d. Training Program	
e. Access of Information	
f. Record Keeping	
7. AHERA O&M Plan.....	Page 15
a. Controls	
8. O&M Response Actions.....	Page 16
a. Facility Maintenance Isolation of Area	
b. Unlikely Contact with ACM/PACM	
c. Accidental Disturbance of ACM/PACM	
d. Planned Disturbance of ACM/PACM	
e. Miscellaneous ACM/PACM.....	Page 17
f. Vinyl Asbestos Floor Tile	
g. Mastic/Adhesives	
h. Woven Vibration Dampers	
i. Other Work Practices	
j. Fiber Release Episodes	
9. References and Resources.....	Page 18

DEFINITIONS / ACRONYMS

ACM/PACM:	Asbestos Containing Material/Potential Asbestos Containing Material
AHERA:	Asbestos Hazard Emergency Response Act
AIR FORM:	Asbestos Inspection Report Form
Amended Water:	Water to which a surfactant (soap) has been added
AMP:	Asbestos Management Program/Asbestos Management Plan
Asbestos Designate Person:	Individual assigned by the district to oversee asbestos related issues.
Asbestos Regulated Area:	Location that is posted as an asbestos work area in which only approved and accredited personnel are permitted to enter
AST:	Asbestos Support Team involving approved and accredited school district tradespersons personnel that are school district person
A-TEAM:	School District of Philadelphia asbestos workers
CIP:	Capital Improvement Program
Consultant:	Asbestos consulting firm hired by the District
Demolition Directive:	Memorandum – August 4, 2006 from Patrick Henwood
EPA:	Environmental Protection Agency
In House Personnel:	School District of Philadelphia asbestos workers
LEA:	Local Education Agency
O&M:	Operations and Maintenance
OEMS:	Office of Environmental Management and Services
OSHA:	Occupational Safety and Health Administration
PEL:	Permissible Exposure Limit
PSD or SDP:	Philadelphia School District/School District of Philadelphia
PSIT:	Philadelphia School Improvement Team
STEL:	Short Term Exposure Limit

1. Introduction

The School District of Philadelphia, Asbestos Policy Statement:

“The School District of Philadelphia is dedicated to providing a safe and healthful work environment for its employees, students, faculty, contractors and visitors. In recognition of the potential health problems associated with asbestos, the School District of Philadelphia is committed to a comprehensive asbestos control program. This program is implemented and maintained through the School District of Philadelphia's Office of Environmental Management and Services (OEMS).”

OEMS has the responsibility of establishing procedures for asbestos abatement, asbestos inspection, air monitoring, renovation and demolition activities within all School District of Philadelphia owned or leased facilities.

These procedures are developed to ensure that:

- (1) People are not exposed to significant levels of asbestos fibers
- (2) Asbestos waste is handled and disposed of properly
- (3) Members of the School District of Philadelphia community have access to the Office of Environmental Management and Services for information, assistance, guidance, and interpretation regarding asbestos related matters.
- (4) Members of the School District of Philadelphia community have access to the Asbestos Management Plans as required and outlined in the US EPA AHERA regulations including annual written notification to all parents.
- (5) Compliance with all applicable Federal, State and Local Asbestos Regulations

Requirements outlined in this manual are mandatory in nature where the word “SHALL” is used and are advisory in nature where the word “SHOULD” is used.

2. Summary of Asbestos Management Program

The School District of Philadelphia's Asbestos Management Program was established to meet the requirements of Federal, State, and Local Regulations.

These regulations include, but are not limited to:

- US Environmental Protection Agency Asbestos Hazard Emergency Response Act (US EPA AHERA) and National Emissions Standard for Hazardous Air Pollutants subpart M, Part 61 (NESHAP);
- US Department of Labor, Occupational Safety and Health Administration (OSHA) General Industry Standard (29 CFR 1910.1001) and the OSHA Asbestos Standard for the Construction Industry (29 CFR 1926.1101);
- The Commonwealth of Pennsylvania, Department of Labor and Industry, Asbestos Occupations, Accreditation and Certification Act;
- The City of Philadelphia, Department of Public Health, Asbestos Control Regulations.

3. Asbestos Management Program Execution

a) General Execution

The Office of Environmental Management and Services (OEMS) develops, implements and manages safety and health programs for the School District of Philadelphia faculty, staff and students and assists with ensuring that all contractors comply with Federal, State and Local Environmental Regulations. The OEMS provides the oversight of School District of Philadelphia employees (Asbestos A-Team), environmental consultants, and asbestos abatement contractors for all projects within the School District of Philadelphia concerning Asbestos Containing Materials.

The control of safety and health hazards at the School District of Philadelphia is primarily through the implementation of engineering, work practice and administrative controls. Personal Protective Equipment (PPE) is used to supplement these controls or whenever the controls are not feasible or are in the process of being implemented. PPE is also recommended whenever exposures to chemical, physical or biological agents can be prevented or reduced by its use.

This written program establishes the procedures necessary to:

- 1) meet established standards and federal regulations for occupational exposure to asbestos fibers;
- 2) meet the requirements of the City of Philadelphia Asbestos Control Regulations which encompasses the disturbance and/or abatement of asbestos containing building materials;
- 3) provide the necessary health and safety protection to the School District of Philadelphia staff, faculty, students, contractors and visitors.

This program is strengthened by input and cooperation with the Philadelphia Federation of Teachers (PFT), Health and Welfare Fund.

4. Summary of Program Execution

a) Asbestos Management Program Execution

The Asbestos Management Program is administered by the Office of Environmental Management and Services (OEMS). OEMS provides the following services primarily through professional consultants:

- (1) exposure monitoring services;
- (2) building inspection/surveys (bulk sampling) for the identification of asbestos containing materials;
- (3) asbestos project design services;
- (4) asbestos abatement project and air monitoring services;
- (5) emergency response to fiber release episodes;
- (6) education/information;
- (7) medical monitoring;
- (8) training for School District of Philadelphia personnel

5. Responsibilities

a) Office of Environmental Management and Services

OEMS is responsible for performing the following functions:

- (1) Developing and administering of the Asbestos Management Program.
- (2) Providing asbestos-related services to all School District of Philadelphia departments.
- (3) Conducting required training of the Asbestos Management Program and working jointly with departments to schedule training.
- (4) Identifying and posting areas where labeling/signage are required.
- (5) Medical Monitoring of OEMS "A-TEAM" and other departments "AST" Asbestos Program staff.

- (6) Certification and training as required for OEMS "A-TEAM" and other departments "AST" Asbestos program staff.
- (7) Record keeping as outlined in Section 3.5 and all records as by required by US EPA AHERA regulations.

b) Asbestos Worker/Supervisor - "A-TEAM"

- (1) OEMS shall ensure that all "A-TEAM" workers/supervisors adhere to the following requirements:
 - a) Attend an initial Worker/Supervisor Asbestos Course;
 - b) Maintain the annual re-certification per EPA AHERA requirements and Commonwealth of Pennsylvania Asbestos Occupations, Accreditation and Certifications Act;
 - c) Undergo an annual Asbestos Medical Evaluation;
 - d) Undergo an annual Respirator Medical Clearance;
 - e) Undergo an annual Respirator Fit Testing.

c) Asbestos Designated Person

The Asbestos Designated Person is responsible for:

- (1) Assuring the health and safety of employees, students and visitors in the School District of Philadelphia facilities under his/her control.
- (2) Being kept informed of all areas under his or her jurisdiction where potential asbestos exposures exist and initiating protection programs that adhere to the Asbestos Management Program requirements of this manual.
- (3) Assuring that Asbestos Management Program requirements are adhered to by principal investigators, project managers, supervisors, or division heads, and School District of Philadelphia personnel under their supervision.
- (4) Ensuring that all employees within the Asbestos Management Program comply with (OSHA 1910.1001 (j) (7) (iv)) and the US EPA AHERA regulations by attending the required training.
- (5) Ensure the posting of:
 - a) Warning labels/signage
 - b) Commonwealth of Pennsylvania Asbestos Abatement and Demolition/Renovation Notification form
 - c) Asbestos Inspection Reports (AIR) form (where required)
 - d) Ensuring that Construction Projects follow the Demolition Directive procedures as outlined in the August 4, 2006 letter.

d) Supervisor or Project Manager (Capital, Maintenance and Facilities)

Each person in charge of a project, maintenance/repair, renovation/demolition, or other activity from the Departments of Capital, Maintenance, and/or Facilities, where asbestos containing material may be present is responsible for:

Identifying, with the assistance of OEMS, asbestos containing building materials prior to any disturbance of these materials. Various Federal (EPA and OSHA) and Local (City of Philadelphia Asbestos Control Regulations) require Asbestos Inspections prior to renovation/demolition activities. This shall be accomplished by always following the Asbestos Management Program Procedures as follows:

- (1) Ensure that the requirements of the Asbestos Management Program Procedures are followed by all personnel, trades, and contractors who are involved with the project;

- (2) Review of the required Asbestos Inspection Report (AIR) form (Attachment 1) and AHERA Management Plan documents prior to activities that may disturb any Asbestos Containing Materials;
- (3) Perform all project related duties as outlined in the Project Management Responsibilities;
- (4) Keep the department chairperson or director informed on any actions proposed or taken regarding the Asbestos Management Plan;
- (5) Ensuring that Construction Projects follow the Demolition Directive procedure outlined in the August 4, 2006 letter.

e) Employee – Capital

School District of Philadelphia Capital employees and/or consultants shall:

- (1) Ensure that no suspect or asbestos containing building materials are disturbed in the course of the projects they are performing or managing. This shall be accomplished by notifying their supervisor and OEMS by issuance of a work order permit (a.k.a PSIT Service Request Form) and verifying that the materials which may be disturbed are non-asbestos containing. If this information is not available or verification has not been made, these materials should not be disturbed.
- (2) Immediately notify OEMS and their supervisor in the event of a potential fiber release episode upon discovery of visible damage to asbestos containing materials.
- (3) Ensuring that Construction Projects follow the Demolition Directive procedures as outlined in the August 4, 2006 letter.

The types of projects represented as part of the Capital Improvement Program are as follows:

- (1) Complete Renovation of an existing building that addresses all facility component concerns and educational program needs;
- (2) Major Renovation of an existing building addressing significant facility component and educational improvements;
- (3) Addition to an existing building (either as an attachment or stand-alone structure) to accommodate needed program space;
- (4) Conversion of an existing facility to accommodate a change in educational program;
- (5) Facility Component Improvement of specific facility needs (i.e. electrical or HVAC system upgrades, ADA improvements, life safety improvements, exterior renovations, etc.)

f) Employee – Maintenance

School District of Philadelphia Maintenance employees shall:

- (1) Ensure that no suspect or asbestos containing building materials are disturbed in the course of their duties or work they are performing. This shall be accomplished by notifying their supervisor and OEMS by issuance of a work order permit and verifying that the materials which may be disturbed are non-asbestos containing. If this information is not available or verification has not been made, these materials should not be disturbed.
- (2) Immediately notify OEMS and their supervisor in the event of a potential fiber release episode or upon discovery of visible damage to asbestos containing materials.
- (3) All employees involved in maintenance activities shall attend required Asbestos Awareness training program within 60 days of employment.

g) Employee – Facilities & Custodial

School District of Philadelphia Facilities and Custodial employees shall:

- (1) Ensure that no suspect or asbestos containing building materials are disturbed in the course of their duties or work they are performing. This shall be accomplished by notifying their supervisor and OEMS by issuance of a work permit and verifying that the materials which may be disturbed are non-asbestos containing. If this information is not available or verification has not been made, these materials should not be disturbed;
- (2) Immediately notify OEMS and their supervisor in the event of a potential fiber release episode or upon discovery of visible damage to asbestos containing materials.
- (3) All employees involved in Facilities and Custodial activities shall attend require Asbestos Awareness training program within 60 days of employment.

6. Requirements

a) Employee Exposure Monitoring

When information indicates that an employee's exposure to asbestos fibers may equal or exceed an 8-hour time-weighted average of 0.1 f/cc * (per OSHA 1910.1001 & 1926.1101), OEMS shall develop and implement an asbestos exposure monitoring program. The sampling strategy shall be designed to identify employees by work task (job classification) that is exposed to asbestos fibers that exceed an 8-hour time-weighted average of 0.1 f/cc.

b) Employee Notification

OEMS shall notify in writing, each employee exposed to asbestos fibers at or above an 8-hour time weighted average of 0.1 f/cc.

c) Observation and Monitoring

OEMS shall provide employees or their representatives with an opportunity to observe any exposure measurements conducted.

d) Training Program

OEMS shall institute a training program which meets the requirements of AHERA for all employees who perform maintenance operations in a facility/school which contains asbestos containing materials or presumed asbestos containing materials and 1910.1001 (j), and the Commonwealth of Pennsylvania Department of Labor and Industry and the City of Philadelphia Asbestos Control Regulations. The affected departments shall ensure employee participation in this program. The OEMS "A-TEAM" and other departments "AST" Asbestos Program staff training shall be conducted annually for each employee as required by all Federal, State and Local for each asbestos discipline.

All Asbestos Awareness training as required by AHERA shall be performed within 60 days of employment and shall include:

- Health effects of asbestos
- Locations of ACM and PACM in the building/facility
- Recognition of CM and PACM damage and deterioration
- Requirements of the OSHA 1910.1001 standard relating to maintenance
- Proper response to fiber release episodes
- Procedure to be followed to isolate areas affected by fiber release

e) Access to Information

OEMS shall make available to affected employees or their representative's copies of the Occupational Safety and Health Administration (OSHA) General Industry Standard Part 1910.1001 and the department shall post a copy in the workplace.

f) Record Keeping

OEMS shall maintain an accurate record of all employee exposure measurements. OEMS and/or the School District of Philadelphia Human Resources Department shall maintain records of employee medical monitoring program. OEMS shall maintain all employee training records. All records shall be provided upon request to employees, former employees, representatives designated by the individual employee.

7. AHERA OPERATIONS AND MAINTENANCE PLAN

a) CONTROLS

i. Work Order System

Minimizing disruption of ACM/PACM during maintenance and renovation activities is the primary goal and task encountered by OEMS. Operations and maintenance employees and contractors should be warned to avoid conducting any maintenance work which may disturb ACM/PACM. Initiating a work order system, where all work orders or requests are channeled through the Office of Environmental Management and Services (OEMS), will be the method used to control and minimize disruption of ACM/PACM.

Any work performed by in-house personnel or contractors that could or will impact ACM/PACM shall be coordinated by OEMS. A completed Asbestos Inspection Report Form (Attachment 1) shall be issued to in-house personnel and/or all contractors whose work could impact ACM/PACM. This form should accompany each contract issued to an outside contractor and posted on the jobsite.

All work order requests for maintenance and renovation activities in areas where ACM/PACM is suspected or known to be present are to be submitted to OEMS prior to proceeding with work. OEMS is responsible for reviewing asbestos survey records for information about the presence of ACM/PACM in the area where the work is to be performed. OEMS should physically inspect the area to ensure existing records reflect actual conditions. If no asbestos is present, a work order is not necessary and the planned actions can proceed. If ACM/PACM is found to be present in the area, OEMS will sign the work order application and obtain an approved and accredited asbestos contractor or assign OEMS "A-TEAM" to abate the ACM/PACM.

ii. Regulated Areas

The owner will identify and regulate all areas where airborne concentrations of ACM/PACM exceed the Permissible Exposure Limit (PEL)* (Per OSHA determined to be 0.1 f/cc) and/or short term exposure limit (STEL) (Per OSHA determined to be 0.1 f/cc), or there is reasonable possibility that the (PEL) and/or (STEL) may be exceeded. All ACM/PACM removal activities involving thermal system insulation ACM/PACM (Class I), surfacing ACM/PACM (Class I), and miscellaneous ACM/PACM such as floor tile, roofing, and siding mastic, etc. (Class II), and repair and maintenance operations where thermal system insulation and surfacing ACM/PACM is likely to be disturbed (Class III) will be performed in accordance with federal, state, and local regulations. All asbestos abatement work and activities will be designed and managed as asbestos regulated areas. These areas will be demarcated and labeled.

iii. Warning Signs

Warning signs shall be displayed at all approaches to each asbestos regulated area. The asbestos abatement contractor will provide OSHA warning signs in all regulated areas during removal, repair, and other maintenance activities. OEMS will provide AIRs to all contractors who must inform all employees and supervisors working in locations contiguous to asbestos regulated areas of the potential hazards and work practices required.

iv. Warning Labels

Warning labels and/or signage shall be affixed to all raw materials, mixtures, scrap, waste, debris, and other products containing asbestos fibers, or to their containers. Generally, the asbestos abatement contractor or OEMS A-Team personnel will provide all warning labels for ACM/PACM containment.

8. O & M RESPONSE ACTIONS

The Asbestos Management Program general O&M procedures are outlined in this section. Additional requirements specific to asbestos abatement activities are included in the Project Design documents for all Asbestos Abatement Work. Regular cleaning, inspection, and reporting of ACM/PACM deterioration or other problems must be diligently practiced by all employees including custodial and maintenance personnel.

a) Facility Maintenance Isolation of Area Responsibilities

Maintenance personnel are often required to work in areas where ACM/PACM may potentially be disturbed. Most maintenance activities are conducted by in-house staff, outside contractors, or a combination.

Emergency fiber release episodes, such as pipe fitting or valve breaks, emergency boiler work, or mechanical equipment repair will be responded to by OEMS A-Team personnel or asbestos abatement contractor personnel. The owner's maintenance staff will: (1) isolate the emergency fiber release area; (2) post warning signs to prevent unauthorized access, and (3) notify their supervisor and OEMS. OEMS will ensure that the fiber release area remains isolated and is properly cleaned by and approved and accredited abatement contractor or by OEMS A-TEAM personnel.

b) Unlikely Contact with ACM/PACM

Maintenance activities or repairs which can be performed without contacting or disturbing the ACM/PACM require little more than normal care and good workmanship. For example, valves which are either uncovered or covered with non-asbestos insulation can be packed or repaired without disturbing asbestos insulation on nearby pipes. The major precaution is to ensure that maintenance and custodial personnel are familiar with procedures such as isolating the area, posting warning signs, and notifying OEMS in the event of any accidental ACM/PACM disturbance.

c) Accidental Disturbance of ACM/PACM

Maintenance and facilities personnel shall notify OEMS any time a fiber release is suspected. If friable ACM/PACM becomes airborne in the building,

d) Planned Disturbance of ACM/PACM

Maintenance activities that may impact ACM/PACM include access to a valve, flange, duct, or related system component.

Where asbestos-containing insulation must be removed to maintain or repair the thermal system, the ACM/PACM will imminently be disturbed. ACM/PACM removal work shall be conducted by OEMS A-Team personnel or an approved and accredited asbestos abatement contractor.

If friable ACM/PACM becomes airborne in the building, maintenance and facilities personnel shall secure the area and contact OEMS. OEMS shall respond accordingly.

e) Miscellaneous ACM/PACM

Miscellaneous types of ACM/PACM may include vinyl asbestos floor tiles, mastics/adhesives and woven vibration dampers. Disturbance of these materials should be avoided. Routine maintenance activities involving these materials should not pose a problem if handled properly. Questions on the proper removal and disposal of miscellaneous ACM/PACM should be directed to OEMS. OEMS will contact an approved and accredited asbestos abatement contractor or utilize OEMS A-TEAM personnel to assist with miscellaneous ACM/PACM clean-up activities.

f) Vinyl Asbestos Floor Tile

Asbestos-containing floor tiles in good condition are considered non-friable unless they are crushed, drilled, sawed, sanded or disturbed by any activity that breaks up the material. Routine maintenance of these materials should employ the use of non-abrasive buffers and wet cleaning technique. Broken or loose floor tiles should be removed and disposed of as asbestos waste by OEMS. Remaining debris should be vacuumed with a HEPA vacuum and the area wet mopped using amended water.

g) Mastics/Adhesives

Mastics and adhesives containing asbestos in good condition are considered non-friable and do not pose a potential health concern unless crushed, drilled, sawed, sanded, or otherwise abraded. Questions on the proper removal should be directed to OEMS.

h) Woven Vibration Dampers

Woven vibration dampers in good condition are considered non-friable and do not pose a potential health concern unless cut, crushed, drilled, sawed, sanded, or otherwise abraded. Questions on the proper removal should be directed to OEMS.

i) Other Work Practices

Any special work not included in this section should be addressed to OEMS for review prior to the initiation of work that may involve the disturbance of ACM/PACM.

j) Fiber Release Episodes

Facilities and maintenance staff should report to OEMS the presence of asbestos debris, water or physical damage to ACM/PACM, or any other evidence of possible fiber release. OEMS should have the OEMS A-Team personnel or an approved and accredited abatement contractor respond to the site to clean up debris and make repairs as soon as possible. OEMS will also contact a consultant to conduct air monitoring and prepare a report and submit at project completion to OEMS for each episode. OEMS will forward the reports for each site location AHERA Management Plan accordingly.

9. REFERENCES and RESOURCES

Applicable regulations for asbestos projects impacted by renovation, demolition, and maintenance activities.

- **Philadelphia Air Management Services – Asbestos Control Unit**
<http://www.phila.gov/health/units/ams/Asbestos/asbestos.html>
- **Pennsylvania Asbestos Occupations, Accreditation and Certification Act**
<http://www.dli.state.pa.us/landi/cwp/view.asp?a=185&q=56262&landiNav=>
- **United States Environmental Protection Agency Asbestos Home Page**
<http://www.epa.gov/asbestos/>
- **Occupational Safety and Health Administration (OSHA) Asbestos Home**
<http://www.osha.gov/SLTC/asbestos>