

SCHOOL DISTRICT OF PHILADELPHIA



Asbestos Hazard Emergency Response Act “AHERA”

THREE-YEAR RE-INSPECTION 2015-2016 and ASBESTOS MANAGEMENT PLAN for the

Hill-Freedman World Academy at Leeds Campus

**ULCS# 6100/6460
Building # B610001-1
1100 E. Mount Pleasant Avenue
Philadelphia, Pennsylvania
19150**

Year Built: 1953

October 2015

Conducted by:

Accredited Environmental Technologies, Incorporated
Batta Environmental Associates, Incorporated
Criterion Laboratories, Incorporated
Environmental Testing Consultants, LLC
G & C Environmental Services, Incorporated
KEM Partners, Incorporated
Synertech, Inc.
TTI Environmental, Inc.
USA Environmental Management, Inc.
The Vertex Companies, Inc.

Management Plan Prepared by:
Criterion Labs, Inc and Synertech Inc.

This report must remain in the Main Office as mandated by the US EPA AHERA Regulations.

AHERA THREE-YEAR REINSPECTION VOLUME IX

Table of Contents

Transmittal Letter

Executive Summary

- I. Summary list of Confirmed Asbestos Containing Building Materials
- II. Summary list of Assumed Asbestos Contain Building Materials
- III. Summary list of Non-Asbestos Containing Building Materials
- IV. Summary list of Non Suspect Asbestos Containing Building Materials
- V. Summary List of Auditorium DATA for this location
- VI. Summary list of Attic and/or Crawlspace DATA for this location
- VII. Summary list of Pipe Chase/Pipe Shaft DATA for this location

Section I Report of Re-Inspection

- A. Introduction
- B. Three-Year Re-inspection IX Overview
- C. Post- Management Plan Activities and Changes
 - C.1 - Sampling and Analysis
 - C.2 - New Floor Tile Sampling
 - C.3 - Abatement Activity
 - C.4 - Periodic (Six-Month) Surveillance (Damaged Materials)

Section II Re-Inspection Data

- A. Introduction
- B. Re-Inspection Key Definitions
- C. Room by Room Location Log Report

Section III Certificates

- A. Management Planner/Building Inspector Certificates

Section IV	Cross Reference Table	Page 1-8
	Asbestos Management Program	Page 9-19

SCHOOL DISTRICT OF PHILADELPHIA
EDUCATIONAL CENTER
440 NORTH BROAD STREET
PHILADELPHIA, PENNSYLVANIA 19130

OFFICE OF ENVIRONMENTAL MANAGEMENT AND SERVICES

PHONE (215)-400-4750

January 2016

TO: All Principals
All Building Administrators


FROM: Fran Burns
Chief Operating Officer

Francine Locke, M.S., Director
Office of Environmental Management and Services

SUBJECT: AHERA Three (3) Year Re-inspection IX report

In order to comply with the provisions of the Asbestos Hazard Emergency Response Act (AHERA) the attached report is submitted to you. The law requires that this report be kept in the Main/Principal's office. It cannot be removed from these locations. *If the school (program) is relocated to a different building, these environmental documents are to be safely retained for the next school/building occupants.* All asbestos reports must be available to the public and Federal EPA upon request.



Fran Burns
Chief Operation Officer

Francine Locke, M.S., Director
Office of Environmental Management
and Services

Executive Summary

This Asbestos Hazard Emergency Response Act (AHERA) Three-Year Re-inspection “Volume # IX” Management Plan at this location, has been completed and the report of re-inspection submitted to the School District of Philadelphia. The re-inspections in all School District of Philadelphia buildings of 2015-2016 were conducted and completed between October 5th, 2015 through March 30th, 2016 as a joint project by Accredited Environmental Technologies, Inc., Batta Environmental Associates, Inc., Criterion Laboratories, Inc., Environmental Testing Consultants, LLC, G & C Environmental Services, Inc., KEM Partners, Inc., Synertech, Inc., TTI Environmental, Inc., USA Environmental Management, Inc. and The Vertex Companies, Inc.

In general, the School District of Philadelphia Office of Environmental Management and Services conducts Environmental Impact Evaluations and provides Asbestos Inspection Reports prior to any renovation, demolition and/or maintenance activities. The AHERA report must be reviewed prior to any renovation, demolition and/or maintenance activities in order to avoid the unknowing disturbance to Asbestos Containing Building Materials identified within this location. In addition, prior to work activities above all drop ceilings this report should be reviewed to avoid potential disturbances to Asbestos Containing Materials. Refer to Section IV of the Cross Reference Table, for additional Asbestos Management Program information. Contact the Office of Environmental Management and Services to have an Environmental Impact Evaluation conducted prior to any renovation, demolition and/or maintenance activities within this facility.

The information contained in this report was obtained from the original Asbestos Management Plan for the school, from update reports on changes and activities since the completion of the 1st Management Plan for each location and from all prior inspections performed and documented in Volume # I through Volume VIII (dated respectively 1992, 1995, 1998, 2001, 2004, 2007, 2010 or 2013) (if applicable) - and by this Three-Year Re-inspection of this school. The re-inspection report/Management Plan of 2015-2016 were reviewed and prepared collectively by Management Planner Megan Vala, Mary Anne Lerro of Criterion Laboratories, Inc. and/or Monique Causley, of Synertech Inc.

The 2015-2016 inspection process included the addition of a comprehensive Room by Room Inventory of all Thermal (T), Surfacing (S) and Miscellaneous (M) Materials specific to each room of this facility. Inspections of each room's thermal, ceilings, walls, floors and miscellaneous items regardless of Asbestos Content are categorized on the Room by Room Location Log Report for this location. Rooms or areas of the facility that were not accessible at the time of the inspection are marked with an "X". The Room by Room Location Log Report is found in Section II C of this Management Plan.

All Presumed or Suspect Asbestos Containing Building Materials (ACBMs), listed in the following summary charts are categorized as Confirmed, Assumed, Non-Asbestos, and/or Non-Suspect (ACBMs) were identified in the original Management Plan, or in the Volume I through Volume VIII AHERA Three-Year Re-inspection reports, and were re-inspected as part of this project.

As mandated by the U S EPA AHERA regulations, periodic Six-Month inspections and Three-Year Re-inspections of this location will be performed and the Inspection Data in this report will be updated accordingly.

Please feel free to contact the School District of Philadelphia's Office of Environmental Management and Services (OEMS) regarding any comments, questions, or concerns regarding this report or any Environmental related topic. OEMS staff can be reached at (215) 400 4750, via fax at (215) 400 4751 or via e-mail at flocke@philasd.org and/or gfunod@philasd.org.

Additional information can be found on our website. Here is the link to the OEMS website.
<http://webgui.phila.k12.pa.us/offices/e/environmental>

I. Summary list of Confirmed Asbestos Containing Building Materials within this facility

These charts are to be used for a quick reference* in order to avoid the unknowing disturbance of Asbestos Containing Materials during any and all Operations, Maintenance, Renovation, and/or Demolition activities at this location. *These materials have been sampled and Laboratory Analysis has CONFIRMED the presence of Asbestos. Contact OEMS prior to the disturbance of any of the following materials.*

Confirmed Asbestos Containing Building Materials for this location

Floor Tile VAT 9" x 9"	Pipe Fitting Insulation	Pipe Insulation > 6 inch
Pipe Insulation 2-6 inch	Transite Stalls	

** Always refer to the Room by Room Logs for each specific material classification as the material classification findings may be different in various rooms throughout this facility.*

*** Some Materials may have multiple classifications (Confirmed, Assumed, NAD and Non Suspect) within this facility.*

II. Summary list of Assumed Asbestos Containing Building Materials within this facility

These charts are to be used for a quick reference* in order to avoid the unknowing disturbance of Asbestos Containing Materials during any and all Operations, Maintenance, Renovation, and/or Demolition activities at this location. These materials have not been sampled and should not be disturbed until verification of Asbestos Content. Contact OEMS for assessment and sampling prior to the disturbance of these materials.

Assumed Asbestos Containing Building Materials for this location

Blackboard Glue Dots	Ceiling Tile 1' x 1'	Duct Insulation
Exterior Boiler Insulation	Fire Doors	Floor Tile VAT 12" x 12"
Package Boilers	Pipe Fitting Insulation	Pipe Insulation 2-6 inch
Radiator Insulation	Sink Undercoat Mastic	Spline Ceiling Glue Dots
Transite Electrical Panel	Vibration Damper Cloth	

** Always refer to the Room by Room Logs for each specific material classification as the material classification findings may be different in various rooms throughout this facility.*

*** Some Materials may have multiple classifications (Confirmed, Assumed, NAD and Non Suspect) within this facility.*

III. Summary list of Non-Asbestos Containing Building Materials within this facility

These charts are to be used for a quick reference* in order to avoid the unknowing disturbance of Asbestos Containing Materials during any and all Operations, Maintenance, Renovation, and/or Demolition activities at this location. *These materials have been sampled and Laboratory Analysis has indicated NO Asbestos present or NO ASBESTOS DETECTED (NAD).*

Non- Asbestos Containing Building Materials for this location

Plaster Ceiling	Plaster Walls	
-----------------	---------------	--

* *Always refer to the Room by Room Logs for each specific material classification as the material classification findings may be different in various rooms throughout this facility.*

** *Some Materials may have multiple classifications (Confirmed, Assumed, NAD and Non Suspect) within this facility.*

IV. Summary list of Non-Suspect Asbestos Containing Building Materials within this facility

These charts are to be used for a quick reference* in order to avoid the unknowing disturbance of Asbestos Containing Materials during any and all Operations, Maintenance, Renovation, and/or Demolition activities at this location. These materials are not typically known to contain Asbestos.

Non-Suspect Asbestos Containing Building Materials for this location

Brick Wall	Carpet	Ceiling Tile 2' x 4'
Cement Floor	Ceramic Tile Floors	Ceramic Tile Walls
CMU	Concrete Block Wall	Concrete Ceiling
Fiberglass Ceiling Tile 2' x 4'	Fiberglass Pipe Insulation	Metal Staircase
Pre-Fabricated Walls	Sheetrock Wall	Wood Floor
Wood	Stall Partitions	

** Always refer to the Room by Room Logs for each specific material classification as the material classification findings may be different in various rooms throughout this facility.*

*** Some Materials may have multiple classifications (Confirmed, Assumed, NAD and Non Suspect) within this facility.*

V. Summary list of Auditorium DATA for this location

These charts are to be used for a quick reference of the Auditorium DATA within this facility. Sampling of the Auditorium Ceilings throughout the District is more difficult because of the various ceiling heights. As sampling occurs this information is updated on a case by case basis for each specific location and facility.

This is a list of known materials for this location's Auditorium

Auditorium		
Auditorium	Acoustical Plaster Ceiling	Confirmed
Auditorium	Plaster Walls	NAD
Auditorium	Floor Tile VAT 9" x 9"	Confirmed
Auditorium	Cement Floor	Non Suspect ACM
Auditorium	Radiator Insulation	Assumed
Stage	Wood Floor	Non Suspect ACM
Stage	Acoustical Plaster Ceiling	Confirmed
Stage	Plaster Walls	NAD
Stage	Pipe Insulation 2-6 inch	Confirmed
Stage	Pipe Fitting Insulation	Confirmed

** Always refer to the Room by Room Logs for each specific material classification as the material classification findings may be different in various rooms throughout this facility.*

*** Some Materials may have multiple classifications (Confirmed, Assumed, NAD and Non Suspect) within this facility.*

VI. Summary list of Attic and/or Crawlspace DATA for this location

These charts are to be used for a quick reference regarding the Attics and/or Crawlspaces inspection DATA within this facility. Contact OEMS prior to entering any attic or crawlspace within this facility and refer to the below chart and legend for Category Rank determination. The Data relative to these spaces is updated as conditions change regarding Abatement or Renovation activity on a case by case basis for each specific location and facility. In general, Crawlspaces are below the basement or 1st floor and Attics are above the floor space.

Category Rank Legend

"A" - No Asbestos Containing Materials - Sample Results indicate NO ACM on pipes, fittings, elbows, or equipment located within this functional space, and NO VISIBLE DEBRIS or DAMAGE observed at time of this inspection.
"B" - Asbestos Containing Materials Exist - Sample Results indicate ACM on pipes, fittings, elbows, or equipment located within this functional space, HOWEVER, NO VISIBLE DEBRIS or DAMAGE observed at time of this inspection.
"C" - Asbestos Containing Materials Exist - Sample Results indicate ACM on pipes, fittings, elbows, or equipment located within this functional space, and LOCALIZED VISIBLE DEBRIS or DAMAGE observed at time of this inspection.
"D" - Asbestos Containing Materials Exist - Sample Results indicate ACM on pipes, fittings, elbows, or equipment located within this functional space and DISTRIBUTED VISIBLE DEBRIS or SIGNIFICANT DAMAGE observed at time of this inspection.
"E" - No Bulk Sample Results Available SUSPECT ACM OBSERVED. Contact OEMS immediately for additional instructions.

Attic/Crawlspace	Access Area	Floor Surface	Category Rank	Comments
Attic	Penthouse	Unknown	"A"	Abated Summer 2015
Attic	2 nd Floor Fan Room	Concrete	"A"	Abated Summer 2015
Crawl Space	Basement (Several areas throughout)	Unknown	"A"	Abated in May 2016
Crawl Space	Incinerator Room	Dirt/Sand	"A"	Abated in May 2016

VII. Summary list of Pipe Chase/Pipe Shaft DATA for this location

These charts are to be used for a quick reference regarding the information known about the Pipe Chases and/or Pipe Shafts inspection DATA within this facility. Contact OEMS prior to performing renovation activities any Pipe Chase and/or Pipe Shaft within this facility and refer to the below chart and legend for Asbestos Content of various materials identified within each space. The Data relative to these spaces is updated as conditions change regarding Inspection, Abatement and/or Renovation activity on a case by case basis for each specific location and facility. In general, Pipe Chases are horizontal spaces and Pipe Shafts are vertical spaces.

<i>Element</i>	<i>Floor</i>	<i>On Site Room Name</i>	<i>Material</i>	<i>Confirmed /Assumed NAD/Non Suspect</i>	<i>Amount of Material</i>	<i>Amount of Damage</i>
1	2	Classroom 221 Storage Closet (Pipe Chase adjoining) – No access	X	X	X	X

Section I

Report of Re-Inspection

A. Introduction

B. Three-Year Re-Inspection IX Overview

C. Post-Management Plan Activities and Changes

C.1 Sampling and Analysis

C.2 New Floor Tile Sampling

C.3 Abatement Activity

C.4 Periodic Six-Month Surveillance (Damaged Materials)

Section I - A

Report of Re-inspection

Introduction

The Three-Year Re-inspection IX was performed to fulfill the requirements of 40 CFR Part 763 - the Asbestos Hazard Emergency Response Act (AHERA). As required by AHERA, each Local Education Agency (LEA) must re-inspect all known confirmed or assumed Asbestos Containing Building Material (ACBM) located in the LEA's facilities. This re-inspection is intended to update the original Asbestos Management Plan for the LEA's facilities.

Multiple Building Inspectors of several firms performed the 2015/2016 re-inspection. The re-inspection report/Management Plan of 2015-2016 were reviewed and prepared collectively by Management Planner Megan Vala, Mary Anne Lerro of Criterion Laboratories, Inc. and Monique Causley, of Synertech Inc.

All of the certificates can be found in Section III.

During the re-inspection of each School District of Philadelphia facility, all of the Management Plans for that facility were reviewed. Information from the conclusions section of that report is included in this report. Additionally, information on activities such as abatements, cleanings, sampling and inspections, which have taken place since the completion of the original Management Plan, were reviewed during the re-inspection. Information on those activities is included in this report.

As mandated by the U S EPA AHERA regulations, all future periodic Six-Month inspections and Three-Year Re-inspections of this location will be performed and the Inspection Data in this report will be updated accordingly.

Section I - B

Three-Year Re-inspection IX Overview

Each homogeneous area of Asbestos Containing Building Material (ACBM) listed in the original Management Plan or in the 1992, 1995, 1998, 2001, etc., Three-Year Re-inspection reports were inspected for the AHERA Three-Year Re-inspection Volume IX, and the information for that material verified. Any changes to a homogeneous area listed in the updates to the Management Plans were verified. Any area of suspected ACBM found in the course of the re-inspection, and not listed in the Management Plan or updates, were either assumed to contain asbestos or sampled and analyzed to determine their asbestos content. Any such new areas either assumed to contain asbestos or determined through analysis to contain asbestos were included in the report of the Three-Year Re-inspection. The results of the AHERA Three-Year Re-inspection IX are tabulated in the Room by Room log reports located in *Section II-C* of this report.

As previously noted, all future periodic Six-Month inspections and Three-Year Re-inspections of this location will be performed and the Inspection Data in this report will be updated accordingly.

Section I – C.1

Post Management Plan Activities/Changes

Information on activities affecting Asbestos Containing Building Materials (ACBMs) at this location is contained in updates to the Management Plan. These updates are kept on file by the School District of Philadelphia and were reviewed for this project. Updates to the Management Plan include the following: *Sampling and Analysis, New Tile Installation, Abatement Activity and Periodic Six-Month Surveillance Data.*

Sampling and Analysis

In the event Sampling occurs, data will be listed here.

Section I – C.2

Information on the installation of new floor tiles/renovation activities affecting Asbestos Containing Building Materials (ACBMs) at this location is contained in updates to the Management Plan. These updates are kept on file by the School District of Philadelphia and were reviewed for this project. Updates to the Management Plan include the following:

New Floor Tile Sampling

In the event that new tile is installed, the material must be tested prior to installation.

Section I – C.3

Information on the Asbestos Abatement and renovation activities affecting Asbestos Containing Building Materials (ACBMs) at this location is contained in updates to the Management Plan. These updates are kept on file by the School District of Philadelphia and were reviewed for this project. Updates to the Management Plan include the following:

Abatement Activity

<i>Date</i>	<i>Floor</i>	<i>Location</i>	<i>Material</i>	<i>Color</i>	<i>Removed or Encapsulated</i>	<i>Quantity</i>
10/19/2015	2 nd	Library Room 201	Pipe Insulation 2-6 inch		Removed	6 LF
12/4/2015	1 st	Room 118B	Pipe Insulation 2-6 inch		Removed	3 LF
12/4/2015	G	Cafeteria – Roof Drain	Pipe Insulation 2-6 inch		Removed	6 LF
12/16/2015	1	Hallway near Teacher's Lounge 123	Pipe Insulation 2-6 inch		Encapsulated	1 LF
6/1/2016	B	Lower Level Incinerator Room	Contaminated Soil		Removed	400 SF
6/1/2016	CS	Crawl Space	Pipe Insulation 2-6 inch		Removed	9,500 LF

Section I – C.4

Information on the AHERA inspection that noted damage to various Building Materials at this location is contained in updates to the Management Plan. These updates are kept on file by the School District of Philadelphia and were reviewed for this project. Work orders are created for Corrective Action responses and tracked for completion. Updates to the Management Plan include the following:

Periodic (Six-Month) Surveillance (Damaged Materials)

<i>Date</i>	<i>Element</i>	<i>Floor</i>	<i>On Site Room Name</i>	<i>Material</i>	<i>Amount of Material</i>	<i>Amount of Damage</i>
11/30/2016	1	G	Wide Hallway near Classroom 3 to the North of Cafeteria	Ceiling Tile 1' x 1'	2000 SF	10 SF
11/30/2016	1	G	Classroom 3	Ceiling Tile 1' x 1'	900 SF	8 SF
11/30/2016	1	G	Classroom 3	Spline Ceiling Glue Dots	900 SF	8 SF
11/30/2016	1	G	Storage next to Girl's Restroom near Cafeteria Entrance	Pipe Fitting Insulation	3 EA	3 EA
11/30/2016	1	G	Storage next to Girl's Restroom near Cafeteria Entrance	Pipe Insulation 2-6 inch	30 LF	30 LF
11/30/2016	1	G	Main Mechanical Room UpStairwell and DownStairwell	Pakage Boilers	3 EA	2 EA
11/30/2016	1	1	Classroom connected to Classroom 102 at the Northeastern Corner	Ceiling Tile 1' x 1'	500 SF	500 SF
11/30/2016	1	1	Auditorium	Floor Tile VAT 9" x 9"	10000 SF	50 SF
11/30/2016	1	1	Stage	Acoustical Plaster Ceiling	1000 SF	100 SF
11/30/2016	1	2	Left Closet in Weight Room next to Gym to the Left	Pipe Insulation 2-6 inch	5 LF	1 LF
11/30/2016	1	2	Right Closet in Weight Room next to Gym to the Left	Pipe Insulation 2-6 inch	24 LF	1 LF

Section II

Re-Inspection Data

A. Introduction

B. Re-Inspection Key Definitions

C. Room by Room Location Log Report

Section II - A

Re-inspection Data

Introduction

The following information documents the Three-Year Re-inspection IX of the subject school/facility. The Homogeneous Area Reports were produced using the building inspector's field data on the facility. The key to the Homogeneous Area Report is outlined in the following pages of this report.

Section II - B
(page 1 of 4)

SCHOOL DISTRICT OF PHILADELPHIA
AHERA THREE YEAR RE-INSPECTION IX

ITEM	DEFINITION
ULCS#	Individual identification number assigned to each school within the School District of Philadelphia.
HOMOGENEOUS AREA ID#	Identification number assigned to each homogeneous area in a school/facility. Each section of the homogeneous area ID is significant. 1010/01/01/01 A B C D A. Is the ULCS# for the school. B. Designates the specific building/building area within the school. C. Designates the floor or level within the building/building area. D. Designates the homogeneous material within that floor or level. Note: Item D may be a number or a letter.
SYSTEM AFFECTED	Corresponds to the AHERA system for classifying materials. T : Thermal System S : Surfacing System M : Miscellaneous
ITEM AFFECTED	Is a description of the homogeneous material.
ORIGINAL INSPECTION DATA	This section contains the information found in the original Management Plan (1988-1989).
AMOUNT OF MATERIAL/ UNIT	Quantity of material, and measuring unit. Units include: Square Feet (SF) Each (EA) Linear Feet (LF) Cubic Feet (CF).

**SCHOOL DISTRICT OF PHILADELPHIA
AHERA THREE YEAR RE-INSPECTION IX**

RE-INSPECTION FORM KEY

ITEM	DEFINITION
CND Condition	Corresponds to AHERA condition rating for materials. 0 : No Damage 1 : Damage 2 : Significant Damage
DP Damage Potential	Corresponds to the AHERA material assessment system. 1 : Potential for Damage 2 : Potential for Significant Damage
ASMD Assumed Asbestos	This means that a material was not sampled for asbestos content during the original Management Plan inspection.
RA Response Action	This corresponds to the AHERA system of response action rating for materials. 1 : Establish O&M Program 2 : Repair and Establish O&M Program 3 : Enclose 4 : Encapsulate 5 : Remove 6 : Partial Removal and Establish O&M Program
CHANGES	This section describes changes to the homogeneous material in the twenty-four years since the original AHERA inspection. The abbreviations are defined below. RMVD : Removed ENCL : Enclosed ENCP : Encapsulated DMGD : Damaged SMPLD : Sampled MTRL : Material RPRD : Repaired N/L : None Located RPLCD : Replaced

**SCHOOL DISTRICT OF PHILADELPHIA
AHERA THREE-YEAR RE-INSPECTION IX**

RE-INSPECTION FORM KEY

ITEM	DEFINITION												
THREE YEAR RE-INSPECTION	<p>This section contains the information obtained from the Three-Year Re-inspection IX. With three exceptions, the information categories are identical in format and meaning to those found in the original inspection data section. The three exceptions are defined below.</p>												
DMGD AMT Amount Damaged	<p>This section gives the quantity of damaged material in a homogeneous area. The quantity is shown in the same format as the amount of material/unit section.</p>												
NF Newly Friable	<p>This section identifies materials in the original Management Plan which have since become friable.</p>												
RA Response Action	<p>This rating is based on the AHERA regulations, and is comparable to the RA rating found in the "Original Inspection Data" section. The following table details the response actions.</p> <table><tr><td>1.</td><td>Establish O&M Program</td></tr><tr><td>2.</td><td>Repair and Establish O&M Program</td></tr><tr><td>3.</td><td>Enclose</td></tr><tr><td>4.</td><td>Encapsulate</td></tr><tr><td>5.</td><td>Remove</td></tr><tr><td>6.</td><td>Partial Removal and Establish O&M Program</td></tr></table> <p>a. High Priority Response The homogeneous material has been scheduled for abatement or other response action.</p> <p>b. Medium Priority Response The homogeneous material will be scheduled for abatement or other response action as soon as the high priority responses have been addressed.</p> <p>c. Low Priority Response The homogeneous material will be scheduled for abatement or other response action as soon as the medium priority responses have been addressed.</p> <p>d. On-Going Response/Operations and Maintenance The homogeneous material does not require abatement or other response action at present, and should be included in the facility's on-going operations and maintenance program.</p>	1.	Establish O&M Program	2.	Repair and Establish O&M Program	3.	Enclose	4.	Encapsulate	5.	Remove	6.	Partial Removal and Establish O&M Program
1.	Establish O&M Program												
2.	Repair and Establish O&M Program												
3.	Enclose												
4.	Encapsulate												
5.	Remove												
6.	Partial Removal and Establish O&M Program												

**SCHOOL DISTRICT OF PHILADELPHIA
AHERA THREE-YEAR RE-INSPECTION IX**

RE-INSPECTION FORM KEY

The information presented in the changes section has been compiled from a variety of sources, including the Re-inspection and the following:

- * Quality Control/Quality Assurance Reports of asbestos abatement projects, prepared by consultants to the School District.
- * Permit and Notification Forms for asbestos abatement projects.
- * Periodic Surveillance Forms
- * Operations and Maintenance activities performed by School District personnel.
- * Verbal information from School District personnel.
- * Reports of sampling and analysis of suspected materials by both School District personnel and outside consultants.

**ROOM BY
ROOM
LOCATION LOG
REPORT**

This section gives information, including damage amount and location, for a specific homogeneous material on a room-by-room basis and follows the Re-inspection form.

NOTE: The disparate nature of the above sources of information prohibits the verification of much information within the scope of the AHERA Three-Year Re-inspection. Discrepancies and omissions may exist in this information, and therefore is included on an "as is" basis. The inspectors for the Three-Year Re-inspection IX evaluated homogeneous areas based on the materials current condition and location, as evidenced during the inspector's site visit.

Section II - C

Room by Room Location Log Report

These charts are to be used for a quick reference* in order to avoid the unknowing disturbance of Asbestos Containing Materials during any and all Operations, Maintenance, Renovation, and/or Demolition activities at this location.

NOTE:

*Contact OEMS prior to the disturbance of any of the materials that are listed as **Confirmed and/or Assumed**.*

The quantities listed for (NAD) non-asbestos containing materials and/or Non-Suspect Materials are only estimated and were not measured for the purpose of this report. Field verification of quantities for renovation purposes would be necessary.

6100/6460 Hill Freedman World Academy @ Leeds Campus 2015 2016 AHERA Three-Year Report.xls

School District of Philadelphia Hill Freedman World Academy @ Leeds Campus 1100 E. Mount Pleasant Avenue, Philadelphia, PA, 19150 ULCS# 6100 Year Built: 1953		AHERA Three-Year Reinspection 2015-2016 Room by Room Location Log Report										Reinspection Date: October 30, 2015 Building Inspector: A. Roman Number: 150619008 Management Planner: Megan Vala Number: 740728				Attic/ Crawl Space Ranking	Damage Potential (DP)	Newly Friable (NF)	Response Action (RA)
Element	Room	System Affected	Material Description	HID#	Confirmed/Assumed/NAD/ Non Suspect ACM	Amount of Material	SF LF EA	Amount of Damage	SF LF EA	Color required for VAT	Comments/Description/Notes								
	On Site Room Name																		
1	G Stairwell on the East Side of the Cafeteria	N/A	Cement Floor		Non Suspect ACM	200	SF	0	SF								N/A	N/A	N/A
1	G Stairwell on the East Side of the Cafeteria	N/A	Concrete Ceiling		Non Suspect ACM	200	SF	0	SF								N/A	N/A	N/A
1	G Stairwell on the East Side of the Cafeteria	N/A	Ceramic Tile Walls		Non Suspect ACM	500	SF	0	SF								N/A	N/A	N/A
1	G Stairwell on the East Side of the Cafeteria	T	Pipe Fitting Insulation	6100/01/0G/12	Confirmed	2	EA	0	EA								1	No	1/D
1	G Stairwell on the East Side of the Cafeteria	T	Pipe Insulation 2-6 inch	6100/01/0G/06	Confirmed	10	LF	0	LF								1	No	1/D
1	G Stairwell on the East Side of the Cafeteria	T	Radiator Insulation	6100/01/0G/SYNBB/1600	Assumed	25	SF	0	SF		1 Recessed Radiator - 25 SF						1	No	1/D
1	G Cafeteria	T	Pipe Fitting Insulation	6100/01/0G/12	Confirmed	17	EA	0	EA								1	No	1/D
1	G Cafeteria	T	Pipe Insulation 2-6 inch	6100/01/0G/06	Confirmed	250	LF	0	LF								1	No	1/D
1	G Cafeteria	M	Ceiling Tile 1' x 1'	6100/01/0G/VER/AR/1710	Assumed	11300	SF	0	SF								1	No	1/D
1	G Cafeteria	M	Spline Ceiling Glue Dots	6100/01/0G/VER/AR/2603	Assumed	11000	SF	0	SF								1	No	1/D
1	G Cafeteria	N/A	CMU		Non Suspect ACM	11000	SF	0	SF								N/A	N/A	N/A
1	G Cafeteria	M	Floor Tile VAT 12" x 12"	6100/01/0G/LJ	Assumed	11300	SF	0	SF	Multi							1	No	1/D
1	G Cafeteria	M	Blackboard Glue Dots	6100/01/0G/VER/AR/2600	Assumed	10	SF	0	SF								1	No	1/D
1	G Kitchen Prep/Refrigerator Area	T	Pipe Fitting Insulation	6100/01/0G/12	Confirmed	71	EA	0	EA								1	No	1/D
1	G Kitchen Prep/Refrigerator Area	T	Pipe Insulation 2-6 inch	6100/01/0G/06	Confirmed	200	LF	0	LF								1	No	1/D
1	G Kitchen Prep/Refrigerator Area	N/A	Cement Floor		Non Suspect ACM	1000	SF	0	SF								N/A	N/A	N/A
1	G Kitchen Prep/Refrigerator Area	N/A	Concrete Ceiling		Non Suspect ACM	1000	SF	0	SF								N/A	N/A	N/A
1	G Kitchen Prep/Refrigerator Area	N/A	Ceramic Tile Walls		Non Suspect ACM	2000	SF	0	SF								N/A	N/A	N/A
1	G Kitchen Office	N/A	Concrete Ceiling		Non Suspect ACM	100	SF	0	SF								N/A	N/A	N/A
1	G Kitchen Office	N/A	Cement Floor		Non Suspect ACM	100	SF	0	SF								N/A	N/A	N/A
1	G Kitchen Office	N/A	CMU		Non Suspect ACM	250	SF	0	SF								N/A	N/A	N/A
1	G Kitchen Office	T	Pipe Fitting Insulation	6100/01/0G/12	Confirmed	10	EA	0	EA								1	No	1/D
1	G Kitchen Office	T	Pipe Insulation 2-6 inch	6100/01/0G/06	Confirmed	20	LF	0	LF								1	No	1/D
1	G Kitchen Office Restroom	N/A	Concrete Ceiling		Non Suspect ACM	80	SF	0	SF								N/A	N/A	N/A
1	G Kitchen Office Restroom	N/A	Cement Floor		Non Suspect ACM	80	SF	0	SF								N/A	N/A	N/A
1	G Kitchen Office Restroom	N/A	CMU		Non Suspect ACM	150	SF	0	SF								N/A	N/A	N/A
1	G Kitchen Locker Room and Restroom	N/A	Concrete Ceiling		Non Suspect ACM	100	SF	0	SF								N/A	N/A	N/A
1	G Kitchen Locker Room and Restroom	N/A	CMU		Non Suspect ACM	200	SF	0	SF								N/A	N/A	N/A
1	G Kitchen Locker Room and Restroom	N/A	Cement Floor		Non Suspect ACM	100	SF	0	SF								N/A	N/A	N/A
1	G Kitchen Storage Area at the Southeastern most Corner in the Kitchen	T	Pipe Fitting Insulation	6100/01/0G/12	Confirmed	11	EA	0	EA								1	No	1/D
1	G Kitchen Storage Area at the Southeastern most Corner in the Kitchen	T	Pipe Insulation 2-6 inch	6100/01/0G/06	Confirmed	40	LF	0	LF								1	No	1/D
1	G Kitchen Storage Area at the Southeastern most Corner in the Kitchen	N/A	Concrete Ceiling		Non Suspect ACM	100	SF	0	SF								N/A	N/A	N/A
1	G Kitchen Storage Area at the Southeastern most Corner in the Kitchen	N/A	CMU		Non Suspect ACM	200	SF	0	SF								N/A	N/A	N/A
1	G Kitchen Storage Area at the Southeastern most Corner in the Kitchen	N/A	Cement Floor		Non Suspect ACM	100	SF	0	SF								N/A	N/A	N/A
1	G Kitchen Storage Area adjoining the walk in freezer to the east	N/A	Concrete Ceiling		Non Suspect ACM	48	SF	0	SF								N/A	N/A	N/A
1	G Kitchen Storage Area adjoining the walk in freezer to the east	N/A	CMU		Non Suspect ACM	100	SF	0	SF								N/A	N/A	N/A
1	G Kitchen Storage Area adjoining the walk in freezer to the east	N/A	Cement Floor		Non Suspect ACM	48	SF	0	SF								N/A	N/A	N/A
1	G Walk in Freezer in Kitchen	N/A	Cement Floor		Non Suspect ACM	150	SF	0	SF								N/A	N/A	N/A
1	G Walk in Freezer in Kitchen	N/A	Concrete Block Wall		Non Suspect ACM	450	SF	0	SF								N/A	N/A	N/A
1	G Walk in Freezer in Kitchen	N/A	Concrete Ceiling		Non Suspect ACM	150	SF	0	SF								N/A	N/A	N/A
1	G Storage Area in Kitchen adjacent to Stairwell at the East in Cafeteria	T	Pipe Fitting Insulation	6100/01/0G/12	Confirmed	8	EA	0	EA								1	No	1/D
1	G Storage Area in Kitchen adjacent to Stairwell at the East in Cafeteria	T	Pipe Insulation 2-6 inch	6100/01/0G/06	Confirmed	15	LF	0	LF								1	No	1/D
1	G Storage Area in Kitchen adjacent to Stairwell at the East in Cafeteria	N/A	Concrete Ceiling		Non Suspect ACM	144	SF	0	SF								N/A	N/A	N/A
1	G Storage Area in Kitchen adjacent to Stairwell at the East in Cafeteria	N/A	Ceramic Tile Walls		Non Suspect ACM	500	SF	0	SF								N/A	N/A	N/A
1	G Storage Area in Kitchen adjacent to Stairwell at the East in Cafeteria	N/A	Cement Floor		Non Suspect ACM	144	SF	0	SF								N/A	N/A	N/A
1	G Hallway leading from the Kitchen Walk-in Freezer to Outdoors	N/A	Concrete Ceiling		Non Suspect ACM	200	SF	0	SF								N/A	N/A	N/A
1	G Hallway leading from the Kitchen Walk-in Freezer to Outdoors	N/A	Ceramic Tile Walls		Non Suspect ACM	500	SF	0	SF								N/A	N/A	N/A
1	G Hallway leading from the Kitchen Walk-in Freezer to Outdoors	N/A	Cement Floor		Non Suspect ACM	200	SF	0	SF								N/A	N/A	N/A
1	G Unused Kitchen Space closest to the Boy's Restroom	T	Pipe Fitting Insulation	6100/01/0G/12	Confirmed	36	EA	0	EA								1	No	1/D
1	G Unused Kitchen Space closest to the Boy's Restroom	T	Pipe Insulation 2-6 inch	6100/01/0G/06	Confirmed	150	LF	0	LF								1	No	1/D
1	G Unused Kitchen Space closest to the Boy's Restroom	M	Ceiling Tile 1' x 1'	6100/01/0G/VER/AR/1710	Assumed	1000	SF	0	SF								1	No	1/D
1	G Unused Kitchen Space closest to the Boy's Restroom	M	Spline Ceiling Glue Dots	6100/01/0G/VER/AR/2603	Assumed	1000	SF	0	SF								1	No	1/D
1	G Unused Kitchen Space closest to the Boy's Restroom	N/A	CMU		Non Suspect ACM	1200	SF	0	SF								N/A	N/A	N/A
1	G Unused Kitchen Space closest to the Boy's Restroom	M	Floor Tile VAT 9" x 9"	6100/01/0G/14	Confirmed	1050	SF	0	SF	Green							1	No	1/D
1	G Closet at the Cafeteria Entrance	T	Pipe Fitting Insulation	6100/01/0G/12	Confirmed	4	EA	0	EA								1	No	1/D
1	G Closet at the Cafeteria Entrance	T	Pipe Insulation 2-6 inch	6100/01/0G/06	Confirmed	20	LF	0	LF								1	No	1/D
1	G Closet at the Cafeteria Entrance	N/A	CMU		Non Suspect ACM	200	SF	0	SF								N/A	N/A	N/A
1	G Closet at the Cafeteria Entrance	N/A	Concrete Ceiling		Non Suspect ACM	100	SF	0	SF								N/A	N/A	N/A
1	G Closet at the Cafeteria Entrance	N/A	Cement Floor		Non Suspect ACM	100	SF	0	SF								N/A	N/A	N/A
1	G Boy's Restroom at Cafeteria Entrance	T	Pipe Fitting Insulation	6100/01/0G/12	Confirmed	8	EA	0	EA								1	No	1/D
1	G Boy's Restroom at Cafeteria Entrance	T	Pipe Insulation 2-6 inch	6100/01/0G/06	Confirmed	15	LF	0	LF								1	No	1/D
1	G Boy's Restroom at Cafeteria Entrance	N/A	Concrete Ceiling		Non Suspect ACM	200	SF	0	SF								N/A	N/A	N/A
1	G Boy's Restroom at Cafeteria Entrance	N/A	Ceramic Tile Walls		Non Suspect ACM	700	SF	0	SF								N/A	N/A	N/A
1	G Boy's Restroom at Cafeteria Entrance	N/A	Cement Floor		Non Suspect ACM	200	SF	0	SF								N/A	N/A	N/A
1	G Storage Closet next to Boy's Restroom at Cafeteria	T	Pipe Fitting Insulation	6100/01/0G/12	Confirmed	9	EA	0	EA		Outer Lagging is beginning to delaminate						1	No	1/D
1	G Storage Closet next to Boy's Restroom at Cafeteria	T	Pipe Insulation 2-6 inch	6100/01/0G/06	Confirmed	100	LF	0	LF		Outer Lagging is beginning to delaminate						1	No	1/D
1	G Storage Closet next to Boy's Restroom at Cafeteria	N/A	Concrete Ceiling		Non Suspect ACM	100	SF	10	SF								N/A	N/A	N/A
1	G Storage Closet next to Boy's Restroom at Cafeteria	N/A	CMU		Non Suspect ACM	250	SF	0	SF								N/A	N/A	N/A
1	G Storage Closet next to Boy's Restroom at Cafeteria	N/A	Cement Floor		Non Suspect ACM	200	SF	0	SF								N/A	N/A	N/A
1	G Hallway at Cafeteria Entrance with Lockers	N/A	Concrete Ceiling		Non Suspect ACM	500	SF	0	SF								N/A	N/A	N/A
1	G Hallway at Cafeteria Entrance with Lockers	N/A	CMU		Non Suspect ACM	200	SF	0	SF								N/A	N/A	N/A

6100/6460 Hill Freedman World Academy @ Leeds Campus 2015 2016 AHERA Three-Year Report.xls

School District of Philadelphia Hill Freedman World Academy @ Leeds Campus 1100 E. Mount Pleasant Avenue, Philadelphia, PA, 19150 ULCS# 6100 Year Built: 1953			AHERA Three-Year Reinspection 2015-2016 Room by Room Location Log Report										Reinspection Date: October 30, 2015 Building Inspector: A. Roman Number: 150619008 Management Planner: Megan Vala Number: 740728								
Element	Floor	Room	On Site Room Name	System Affected	Material Description	HID#	Confirmed/Assumed/NAD/Non Suspect ACM	Amount of Material	SF	LF	EA	Amount of Damage	SF	LF	EA	Color required for VAT	Comments/Description/Notes	Attic/Crawl Space Ranking	Damage Potential (DP)	Newly Friable (NF)	Response Action (RA)
1	G		Hallway at Cafeteria Entrance with Lockers	M	Floor Tile VAT 9" x 9"	6100/01/0G/14	Confirmed	500	SF			0	SF			Green					1/D
1	G		Stairwell along the Cafeteria to the North in front of the Lockers in the Hallway	T	Pipe Fitting Insulation	6100/01/0G/12	Confirmed	2	EA			0	EA						1	No	1/D
1	G		Stairwell along the Cafeteria to the North in front of the Lockers in the Hallway	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	10	LF			10	LF						N/A	N/A	N/A
1	G		Stairwell along the Cafeteria to the North in front of the Lockers in the Hallway	N/A	Concrete Ceiling		Non Suspect ACM	200	SF			0	SF						N/A	N/A	N/A
1	G		Stairwell along the Cafeteria to the North in front of the Lockers in the Hallway	N/A	Cement Floor		Non Suspect ACM	200	SF			0	SF						N/A	N/A	N/A
1	G		Stairwell along the Cafeteria to the North in front of the Lockers in the Hallway	N/A	Ceramic Tile Walls		Non Suspect ACM	500	SF			0	SF						N/A	N/A	N/A
1	G		Stairwell along the Cafeteria to the North in front of the Lockers in the Hallway	T	Radiator Insulation	6100/01/0G/SYN/BB/1600	Assumed	25	SF			0	SF				1 Recessed Radiator - 25 SF		1	No	1/D
1	G		Wide Hallway near Classroom 3 to the North of Cafeteria	T	Pipe Fitting Insulation	6100/01/0G/12	Confirmed	10	EA			0	EA						1	No	1/D
1	G		Wide Hallway near Classroom 3 to the North of Cafeteria	T	Pipe Insulation 2-6 inch	6100/01/0G/06	Confirmed	45	LF			0	LF						1	No	1/D
1	G		Wide Hallway near Classroom 3 to the North of Cafeteria	M	Ceiling Tile 1' x 1'	6100/01/0G/VER/AR/1710	Assumed	2000	SF			10	SF						1	Yes	5/B
1	G		Wide Hallway near Classroom 3 to the North of Cafeteria	M	Spline Ceiling Glue Dots	6100/01/0G/VER/AR/2603	Assumed	2000	SF			0	SF						1	No	1/D
1	G		Wide Hallway near Classroom 3 to the North of Cafeteria	N/A	CMU		Non Suspect ACM	3000	SF			0	SF						N/A	N/A	N/A
1	G		Wide Hallway near Classroom 3 to the North of Cafeteria	M	Floor Tile VAT 9" x 9"	6100/01/0G/14	Confirmed	2000	SF			0	SF			Tan			1	No	1/D
1	G		Classroom 5	M	Floor Tile VAT 12" x 12"	6100/01/0G/JJ	Assumed	675	SF			0	SF			Blue	Room is actively experiencing mold remediation (F2016)		1	No	1/D
1	G		Classroom 5	M	Floor Tile VAT 12" x 12"	6100/01/0G/JJ	Assumed	675	SF			0	SF			White			1	No	1/D
1	G		Classroom 5	N/A	Concrete Block Wall		Non Suspect ACM	4050	SF			0	SF						N/A	N/A	N/A
1	G		Classroom 5	N/A	Sheetrock Wall		Non Suspect ACM	250	SF			0	SF						N/A	N/A	N/A
1	G		Classroom 5	N/A	Concrete Ceiling		Non Suspect ACM	1350	SF			0	SF						N/A	N/A	N/A
1	G		Classroom 5	M	Spline Ceiling Glue Dots	6100/01/0G/VER/AR/2603	Assumed	1350	SF			0	SF			Brown			1	No	1/D
1	G		Classroom 5	T	Pipe Insulation > 6 inch	6100/01/0G/08	Confirmed	36	LF			0	LF						1	No	1/D
1	G		Classroom 5	T	Pipe Insulation 2-6 inch	6100/01/0G/06	Confirmed	35	LF			0	LF						1	No	1/D
1	G		Classroom 5	T	Pipe Fitting Insulation	6100/01/0G/12	Confirmed	15	EA			0	EA						1	No	1/D
1	G		Classroom 5	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	3	LF			0	LF						N/A	N/A	N/A
1	G		Pump Room behind Classroom 5	M	Floor Tile VAT 12" x 12"	6100/01/0G/JJ	Assumed	100	SF			0	SF			White			1	No	1/D
1	G		Pump Room behind Classroom 5	N/A	Concrete Block Wall		Non Suspect ACM	300	SF			0	SF						N/A	N/A	N/A
1	G		Pump Room behind Classroom 5	N/A	Concrete Ceiling		Non Suspect ACM	100	SF			0	SF						N/A	N/A	N/A
1	G		Pump Room behind Classroom 5	M	Spline Ceiling Glue Dots	6100/01/0G/VER/AR/2603	Assumed	100	SF			0	SF			Brown			1	No	1/D
1	G		Classroom 4 (narrow Classroom between Classrooms 3 & 5)	M	Floor Tile VAT 9" x 9"	6100/01/0G/14	Confirmed	300	SF			0	SF			Tan			1	No	1/D
1	G		Classroom 4 (narrow Classroom between Classrooms 3 & 5)	N/A	Concrete Block Wall		Non Suspect ACM	650	SF			0	SF						N/A	N/A	N/A
1	G		Classroom 4 (narrow Classroom between Classrooms 3 & 5)	N/A	Sheetrock Wall		Non Suspect ACM	250	SF			0	SF						N/A	N/A	N/A
1	G		Classroom 4 (narrow Classroom between Classrooms 3 & 5)	M	Blackboard Glue Dots	6100/01/0G/SYN/BB/2600	Assumed	120	SF			0	SF						1	No	1/D
1	G		Classroom 4 (narrow Classroom between Classrooms 3 & 5)	N/A	Concrete Ceiling		Non Suspect ACM	300	SF			0	SF						N/A	N/A	N/A
1	G		Classroom 4 (narrow Classroom between Classrooms 3 & 5)	M	Ceiling Tile 1' x 1'	6100/01/0G/VER/AR/1710	Assumed	300	SF			0	SF						1	No	1/D
1	G		Classroom 4 (narrow Classroom between Classrooms 3 & 5)	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	20	LF			0	LF						N/A	N/A	N/A
1	G		Classroom 3	T	Pipe Fitting Insulation	6100/01/0G/12	Confirmed	11	EA			0	EA						1	No	1/D
1	G		Classroom 3	T	Pipe Insulation 2-6 inch	6100/01/0G/06	Confirmed	50	LF			0	LF						1	No	1/D
1	G		Classroom 3	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	20	LF			15	LF						N/A	N/A	N/A
1	G		Classroom 3	M	Ceiling Tile 1' x 1'	6100/01/0G/VER/AR/1710	Assumed	900	SF			8	SF						1	Yes	5/B
1	G		Classroom 3	M	Spline Ceiling Glue Dots	6100/01/0G/VER/AR/2603	Assumed	900	SF			8	SF						1	Yes	5/B
1	G		Classroom 3	N/A	CMU		Non Suspect ACM	1200	SF			0	SF						N/A	N/A	N/A
1	G		Classroom 3	M	Floor Tile VAT 9" x 9"	6100/01/0G/14	Confirmed	900	SF			0	SF			Tan			1	No	1/D
1	G		Classroom 3	M	Blackboard Glue Dots	6100/01/0G/VER/AR/2600	Assumed	10	SF			0	SF						1	No	1/D
1	G		Classroom adjacent to Classroom 3 to the North (Classroom 2)	M	Floor Tile VAT 9" x 9"	6100/01/0G/14	Confirmed	1200	SF			0	SF			Tan			1	No	1/D
1	G		Classroom adjacent to Classroom 3 to the North (Classroom 2)	N/A	Concrete Block Wall		Non Suspect ACM	3600	SF			0	SF						N/A	N/A	N/A
1	G		Classroom adjacent to Classroom 3 to the North (Classroom 2)	N/A	Concrete Ceiling		Non Suspect ACM	1200	SF			0	SF						N/A	N/A	N/A
1	G		Classroom adjacent to Classroom 3 to the North (Classroom 2)	M	Spline Ceiling Glue Dots	6100/01/0G/VER/AR/2603	Assumed	1200	SF			0	SF			Brown			1	No	1/D
1	G		Classroom adjacent to Classroom 3 to the North (Classroom 2)	T	Pipe Insulation > 6 inch	6100/01/0G/08	Confirmed	70	LF			0	LF						1	No	1/D
1	G		Classroom adjacent to Classroom 3 to the North (Classroom 2)	T	Pipe Insulation 2-6 inch	6100/01/0G/06	Confirmed	95	LF			0	LF						1	No	1/D
1	G		Classroom adjacent to Classroom 3 to the North (Classroom 2)	T	Pipe Fitting Insulation	6100/01/0G/12	Confirmed	21	EA			0	EA						1	No	1/D
1	G		Classroom adjacent to Classroom 3 to the North (Classroom 2)	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	125	LF			0	LF						N/A	N/A	N/A
1	G		Classroom caddy corner to Classroom 3 to the Northwest (Classroom 1)	X	X		X	X	X	X	X	X	X	X	X		No access		X	X	X
1	G		Small Hallway at the Northernmost Point leads to Exit Door (next to Classroom 1)	T	Pipe Fitting Insulation	6100/01/0G/12	Confirmed	4	EA			0	EA						1	No	1/D
1	G		Small Hallway at the Northernmost Point leads to Exit Door (next to Classroom 1)	T	Pipe Insulation 2-6 inch	6100/01/0G/06	Confirmed	21	LF			0	LF						1	No	1/D
1	G		Small Hallway at the Northernmost Point leads to Exit Door (next to Classroom 1)	M	Ceiling Tile 1' x 1'	6100/01/0G/VER/AR/1710	Assumed	200	SF			0	SF						1	No	1/D
1	G		Small Hallway at the Northernmost Point leads to Exit Door (next to Classroom 1)	M	Spline Ceiling Glue Dots	6100/01/0G/VER/AR/2603	Assumed	200	SF			0	SF						1	No	1/D
1	G		Small Hallway at the Northernmost Point leads to Exit Door (next to Classroom 1)	M	Floor Tile VAT 9" x 9"	6100/01/0G/14	Confirmed	200	SF			0	SF			Tan			1	No	1/D
1	G		Storage Room/Mechanical Room down Hallway from Classroom 1 near Cafeteria	N/A	Cement Floor		Non Suspect ACM	400	SF			0	SF				Entrance to Crawlpace - Steam leak identified inside crawlpace		N/A	N/A	N/A
1	G		Storage Room/Mechanical Room down Hallway from Classroom 1 near Cafeteria	N/A	Concrete Block Wall		Non Suspect ACM	1200	SF			0	SF						N/A	N/A	N/A
1	G		Storage Room/Mechanical Room down Hallway from Classroom 1 near Cafeteria	N/A	Concrete Ceiling		Non Suspect ACM	400	SF			0	SF						N/A	N/A	N/A
1	G		Storage Room/Mechanical Room down Hallway from Classroom 1 near Cafeteria	T	Pipe Insulation 2-6 inch	6100/01/0G/06	Confirmed	70	LF			0	LF						1	No	1/D
1	G		Storage Room/Mechanical Room down Hallway from Classroom 1 near Cafeteria	T	Pipe Fitting Insulation	6100/01/0G/12	Confirmed	15	EA			0	EA						1	No	1/D
1	G		Storage Room/Mechanical Room down Hallway from Classroom 1 near Cafeteria	M	Vibration Damper Cloth	6100/01/0G/13	Assumed	30	SF			0	SF						1	No	1/D
1	G		Stairwell outside the Entrance to the Building Engineer's Suite	N/A	Concrete Ceiling		Non Suspect ACM	200	SF			0	SF						N/A	N/A	N/A
1	G		Stairwell outside the Entrance to the Building Engineer's Suite	N/A	Cement Floor		Non Suspect ACM	200	SF			0	SF						N/A	N/A	N/A
1	G		Stairwell outside the Entrance to the Building Engineer's Suite	T	Pipe Fitting Insulation	6100/01/0G/12	Confirmed	7	EA			0	EA						1	No	1/D

6100/6460 Hill Freedman World Academy @ Leeds Campus 2015 2016 AHERA Three-Year Report.xls

School District of Philadelphia Hill Freedman World Academy @ Leeds Campus 1100 E. Mount Pleasant Avenue, Philadelphia, PA, 19150 ULCS# 6100 Year Built: 1953			AHERA Three-Year Reinspection 2015-2016 Room by Room Location Log Report										Reinspection Date: October 30, 2015 Building Inspector: A. Roman Number: 150619008 Management Planner: Megan Vala Number: 740728								
Element	Info	On Site Room Name	System Affected	Material Description	HID#	Confirmed/Assumed/NAD/Non Suspect ACM	Amount of Material	SF LF EA	Amount of Damage	SF LF EA	Color required for VAT	Comments/Description/Notes	Attic/Crawl Space Ranking	Damage Potential (DP)	Newly Friable (NF)	Response Action (RA)					
1	G	Stairwell outside the Entrance to the Building Engineer's Suite	T	Pipe Insulation 2-6 inch	6100/01/OG/06	Confirmed	20	LF	0	LF											
1	G	Stairwell outside the Entrance to the Building Engineer's Suite	N/A	Ceramic Tile Walls		Non Suspect ACM	500	SF	0	SF				N/A	N/A	N/A	N/A				
1	G	Stairwell outside the Entrance to the Building Engineer's Suite	T	Radiator Insulation	6100/01/OG/SYN/BB/1600	Assumed	25	SF	0	SF		1 Recessed Radiator		1	No	1/D					
1	G	Incinerator Room Storage	T	Pipe Fitting Insulation	6100/01/OG/12	Confirmed	2	EA	0	EA		Peeling Paint On Ceiling - Insulation is wrapped with wettable		1	No	1/D					
1	G	Incinerator Room Storage	T	Pipe Insulation 2-6 inch	6100/01/OG/06	Confirmed	10	LF	0	LF		Insulation is wrapped with wettable		1	No	1/D					
1	G	Incinerator Room Storage	N/A	CMU		Non Suspect ACM	500	SF	0	SF				N/A	N/A	N/A	N/A				
1	G	Incinerator Room Storage	N/A	Concrete Ceiling		Non Suspect ACM	700	SF	0	SF				N/A	N/A	N/A	N/A				
1	G	Incinerator Room Storage	N/A	Cement Floor		Non Suspect ACM	500	SF	0	SF				N/A	N/A	N/A	N/A				
1	G	Incinerator Room Storage	M	Fire Doors	6100/01/00/AA	Assumed	1	EA	0	EA				1	No	1/D					
1	G	Incinerator Room	T	Pipe Fitting Insulation	6100/01/OG/12	Confirmed	8	EA	0	EA				1	No	1/D					
1	G	Incinerator Room	T	Pipe Insulation 2-6 inch	6100/01/OG/06	Confirmed	25	LF	0	LF				1	No	1/D					
1	G	Incinerator Room	N/A	Concrete Ceiling		Non Suspect ACM	700	SF	0	SF				N/A	N/A	N/A	N/A				
1	G	Incinerator Room	N/A	CMU		Non Suspect ACM	1000	SF	0	SF				N/A	N/A	N/A	N/A				
1	G	Incinerator Room	N/A	Cement Floor		Non Suspect ACM	700	SF	0	SF				N/A	N/A	N/A	N/A				
1	G	Storage across from Cafeteria Entrance	N/A	Concrete Ceiling		Non Suspect ACM	500	SF	0	SF				N/A	N/A	N/A	N/A				
1	G	Storage across from Cafeteria Entrance	N/A	CMU		Non Suspect ACM	700	SF	0	SF				N/A	N/A	N/A	N/A				
1	G	Storage across from Cafeteria Entrance	M	Floor Tile VAT 9" x 9"	6100/01/OG/14	Confirmed	500	SF	0	SF	Green			1	No	1/D					
1	G	Storage across from Cafeteria Entrance Gas Meter Room	N/A	Concrete Ceiling		Non Suspect ACM	36	SF	0	SF				N/A	N/A	N/A	N/A				
1	G	Storage across from Cafeteria Entrance Gas Meter Room	N/A	Cement Floor		Non Suspect ACM	36	SF	0	SF				N/A	N/A	N/A	N/A				
1	G	Storage across from Cafeteria Entrance Gas Meter Room	N/A	CMU		Non Suspect ACM	100	SF	0	SF				N/A	N/A	N/A	N/A				
1	G	Former Truncy Court Men's Restroom	T	Pipe Fitting Insulation	6100/01/OG/12	Confirmed	10	EA	0	EA				1	No	1/D					
1	G	Former Truncy Court Men's Restroom	T	Pipe Insulation 2-6 inch	6100/01/OG/06	Confirmed	12	LF	0	LF				1	No	1/D					
1	G	Former Truncy Court Men's Restroom	N/A	CMU		Non Suspect ACM	300	SF	0	SF				N/A	N/A	N/A	N/A				
1	G	Former Truncy Court Men's Restroom	M	Floor Tile VAT 9" x 9"	6100/01/OG/14	Confirmed	150	SF	0	SF	Green	Discolored floor tile only		1	No	1/D					
1	G	Former Truncy Court Men's Restroom	N/A	Concrete Ceiling		Non Suspect ACM	150	SF	50	SF				N/A	N/A	N/A	N/A				
1	G	Former Truncy Court Women's Restroom	M	Transite Stalls	6100/01/OG/33	Confirmed	100	SF	0	SF		Small holes only, no debris observed		1	No	1/D					
1	G	Former Truncy Court Women's Restroom	M	Floor Tile VAT 9" x 9"	6100/01/OG/14	Confirmed	200	SF	0	SF	Green	Discolored floor tile only		1	No	1/D					
1	G	Former Truncy Court Women's Restroom	N/A	Concrete Ceiling		Non Suspect ACM	200	SF	150	SF				N/A	N/A	N/A	N/A				
1	G	Former Truncy Court Women's Restroom	N/A	CMU		Non Suspect ACM	300	SF	0	SF				N/A	N/A	N/A	N/A				
1	G	Former Truncy Court Women's Restroom	T	Pipe Fitting Insulation	6100/01/OG/12	Confirmed	2	EA	0	EA				1	No	1/D					
1	G	Former Truncy Court Women's Restroom	T	Pipe Insulation 2-6 inch	6100/01/OG/06	Confirmed	15	LF	0	LF				1	No	1/D					
1	G	Former Truncy Court Women's Restroom	M	Vibration Damper Cloth	6100/01/OG/13	Assumed	2	SF	0	SF				1	No	1/D					
1	G	Stairwell near the Cafeteria Entrance between Boy's and Girl's Restrooms	N/A	Concrete Ceiling		Non Suspect ACM	200	SF	0	SF				N/A	N/A	N/A	N/A				
1	G	Stairwell near the Cafeteria Entrance between Boy's and Girl's Restrooms	N/A	Cement Floor		Non Suspect ACM	200	SF	0	SF				N/A	N/A	N/A	N/A				
1	G	Stairwell near the Cafeteria Entrance between Boy's and Girl's Restrooms	N/A	Ceramic Tile Walls		Non Suspect ACM	500	SF	0	SF				N/A	N/A	N/A	N/A				
1	G	Stairwell near the Cafeteria Entrance between Boy's and Girl's Restrooms	T	Radiator Insulation	6100/01/OG/SYN/BB/1600	Assumed	25	SF	0	SF		1 Recessed Radiator		1	No	1/D					
1	G	Storage next to Girl's Restroom near Cafeteria Entrance	T	Pipe Fitting Insulation	6100/01/OG/12	Confirmed	3	EA	3	EA		Very brittle fittings, poor shape, potential for further damage by custodial crew, area used daily during lunch hours for cleaning storage		2	Yes	5/A					
1	G	Storage next to Girl's Restroom near Cafeteria Entrance	T	Pipe Insulation 2-6 inch	6100/01/OG/06	Confirmed	30	LF	30	LF		Very brittle fittings, poor shape, potential for further damage by custodial crew, area used daily during lunch hours for cleaning storage		2	Yes	5/A					
1	G	Storage next to Girl's Restroom near Cafeteria Entrance	N/A	Concrete Ceiling		Non Suspect ACM	100	SF	20	SF		Loose/Flaking Paint		N/A	N/A	N/A	N/A				
1	G	Storage next to Girl's Restroom near Cafeteria Entrance	N/A	CMU		Non Suspect ACM	200	SF	0	SF				N/A	N/A	N/A	N/A				
1	G	Storage next to Girl's Restroom near Cafeteria Entrance	N/A	Cement Floor		Non Suspect ACM	100	SF	0	SF				N/A	N/A	N/A	N/A				
1	G	Halfway at Incinerator Room from the Girl's Restroom to the Boy's Restroom	T	Pipe Fitting Insulation	6100/01/OG/12	Confirmed	9	EA	0	EA				1	No	1/D					
1	G	Halfway at Incinerator Room from the Girl's Restroom to the Boy's Restroom	T	Pipe Insulation 2-6 inch	6100/01/OG/06	Confirmed	45	LF	0	LF				1	No	1/D					
1	G	Halfway at Incinerator Room from the Girl's Restroom to the Boy's Restroom	N/A	Concrete Ceiling		Non Suspect ACM	900	SF	0	SF				N/A	N/A	N/A	N/A				
1	G	Halfway at Incinerator Room from the Girl's Restroom to the Boy's Restroom	N/A	CMU		Non Suspect ACM	1200	SF	0	SF				N/A	N/A	N/A	N/A				
1	G	Halfway at Incinerator Room from the Girl's Restroom to the Boy's Restroom	M	Floor Tile VAT 9" x 9"	6100/01/OG/14	Confirmed	900	SF	0	SF	Green			1	No	1/D					
1	G	Halfway at Incinerator Room from the Girl's Restroom to the Boy's Restroom	T	Radiator Insulation	6100/01/OG/SYN/BB/1600	Assumed	25	SF	0	SF		1 Recessed Radiator		1	No	1/D					
1	G	Girl's Restroom near Cafeteria Entrance	M	Transite Stalls	6100/01/OG/33	Confirmed	100	SF	0	SF		Small holes only, no debris observed		1	No	1/D					
1	G	Girl's Restroom near Cafeteria Entrance	T	Pipe Fitting Insulation	6100/01/OG/12	Confirmed	7	EA	0	EA				1	No	1/D					
1	G	Girl's Restroom near Cafeteria Entrance	T	Pipe Insulation 2-6 inch	6100/01/OG/06	Confirmed	15	LF	0	LF				1	No	1/D					
1	G	Girl's Restroom near Cafeteria Entrance	N/A	Concrete Ceiling		Non Suspect ACM	200	SF	0	SF				N/A	N/A	N/A	N/A				
1	G	Girl's Restroom near Cafeteria Entrance	N/A	Cement Floor		Non Suspect ACM	200	SF	0	SF				N/A	N/A	N/A	N/A				
1	G	Girl's Restroom near Cafeteria Entrance	N/A	Ceramic Tile Walls		Non Suspect ACM	700	SF	0	SF				N/A	N/A	N/A	N/A				
1	G	Facility on door/Former Truncy Court	M	Floor Tile VAT 9" x 9"	6100/01/OG/14	Confirmed	500	SF	0	SF	Green	Discolored floor tile only		1	No	1/D					
1	G	Facility on door/Former Truncy Court	T	Pipe Fitting Insulation	6100/01/OG/12	Confirmed	15	EA	0	EA				1	No	1/D					
1	G	Facility on door/Former Truncy Court	T	Pipe Insulation 2-6 inch	6100/01/OG/06	Confirmed	40	LF	0	LF				1	No	1/D					
1	G	Facility on door/Former Truncy Court	N/A	Concrete Ceiling		Non Suspect ACM	500	SF	0	SF				N/A	N/A	N/A	N/A				
1	G	Facility on door/Former Truncy Court	N/A	CMU		Non Suspect ACM	1000	SF	0	SF				N/A	N/A	N/A	N/A				
1	G	Classroom 1	T	Pipe Fitting Insulation	6100/01/OG/12	Confirmed	20	EA	0	EA				1	No	1/D					
1	G	Classroom 1	T	Pipe Insulation 2-6 inch	6100/01/OG/06	Confirmed	65	LF	0	LF				1	No	1/D					
1	G	Classroom 1	N/A	Concrete Ceiling		Non Suspect ACM	900	SF	0	SF				N/A	N/A	N/A	N/A				
1	G	Classroom 1	N/A	CMU		Non Suspect ACM	1200	SF	0	SF				N/A	N/A	N/A	N/A				
1	G	Classroom 1	M	Floor Tile VAT 12" x 12"	6100/01/OG/JJ	Assumed	900	SF	0	SF	Tan			1	No	1/D					
1	G	Classroom 1	M	Blackboard Glue Dots	6100/01/OG/VER/AR/2600	Assumed	10	SF	0	SF				1	No	1/D					
1	G	Room 2 - District 6 School Police Office	N/A	Carpet		Non Suspect ACM	1000	SF	0	SF				N/A	N/A	N/A	N/A				
1	G	Room 2 - District 6 School Police Office	M	Floor Tile VAT 9" x 9"	6100/01/OG/14	Confirmed	1000	SF	0	SF	Tan	Below Carpeting		1	No	1/D					
1	G	Room 2 - District 6 School Police Office	M	Floor Tile VAT 12" x 12"	6100/01/OG/JJ	Assumed	10	SF	0	SF	White	Atop Unit-Vents		1	No	1/D					
1	G	Room 2 - District 6 School Police Office	N/A	Concrete Block Wall		Non Suspect ACM	1000	SF	0	SF				N/A	N/A	N/A	N/A				
1	G	Room 2 - District 6 School Police Office	N/A	Sheetrock Wall		Non Suspect ACM	1000	SF	0	SF		No Joint Compound		N/A	N/A	N/A	N/A				
1	G	Room 2 - District 6 School Police Office	T	Pipe Insulation 2-6 inch	6100/01/OG/06	Confirmed	60	LF	0	LF				1	No	1/D					

6100/6460 Hill Freedman World Academy @ Leeds Campus 2015 2016 AHERA Three-Year Report.xls

School District of Philadelphia Hill Freedman World Academy @ Leeds Campus 1100 E. Mount Pleasant Avenue, Philadelphia, PA, 19150 ULCS# 6100 Year Built: 1953			AHERA Three-Year Reinspection 2015-2016 Room by Room Location Log Report										Reinspection Date: October 30, 2015 Building Inspector: A. Roman Number: 150619008 Management Planner: Megan Vala Number: 740728						
Element	Info	On Site Room Name	System Affected	Material Description	HID#	Confirmed/Assumed/NAD/ Non Suspect ACM	Amount of Material	SF LF EA	Amount of Damage	SF LF EA	Color required for VAT	Comments/Description/Notes	Attic/ Crawl/ Space Ranking	Damage Potential (DP)	Newly Friable (NF)	Response Action (RA)			
1	G	Room 2 - District 6 School Police Office	T	Pipe Fitting Insulation	6100/01/0G/12	Confirmed	18	EA	0	EA				1	No	1/D			
1	G	Conference Room 10	M	Blackboard Glue Dots	6100/01/0G/VER/AR/2600	Assumed	10	SF	0	SF		Blackboard is no longer there. Exposed Glue Dots		1	No	1/D			
1	G	Conference Room 10	T	Pipe Fitting Insulation	6100/01/0G/12	Confirmed	25	EA	0	EA				1	No	1/D			
1	G	Conference Room 10	T	Pipe Insulation 2-6 inch	6100/01/0G/06	Confirmed	125	LF	0	LF				1	No	1/D			
1	G	Conference Room 10	N/A	Concrete Ceiling		Non Suspect ACM	900	SF	0	SF				N/A	N/A	N/A			
1	G	Conference Room 10	N/A	CMU		Non Suspect ACM	1200	SF	0	SF				N/A	N/A	N/A			
1	G	Conference Room 10	M	Floor Tile VAT 12" x 12"	6100/01/0G/UJ	Assumed	900	SF	0	SF	Tan			1	No	1/D			
1	G	Room 4 Office to the Right	N/A	Carpet		Non Suspect ACM	400	SF	0	SF				N/A	N/A	N/A			
1	G	Room 4 Office to the Right	N/A	Plaster Ceiling		NAD	400	SF	0	SF				N/A	N/A	N/A			
1	G	Room 4 Office to the Right	N/A	CMU		Non Suspect ACM	200	SF	0	SF				N/A	N/A	N/A			
1	G	Room 4 Office to the Right	N/A	Pre-Fabricated Walls		Non Suspect ACM	800	SF	0	SF				N/A	N/A	N/A			
1	G	Room 4 Office to the Left	N/A	Carpet		Non Suspect ACM	400	SF	0	SF				N/A	N/A	N/A			
1	G	Room 4 Office to the Left	N/A	CMU		Non Suspect ACM	200	SF	0	SF				N/A	N/A	N/A			
1	G	Room 4 Office to the Left	N/A	Plaster Ceiling		NAD	400	SF	0	SF				N/A	N/A	N/A			
1	G	Room 4 Office to the Left	T	Pipe Fitting Insulation	6100/01/0G/12	Confirmed	4	EA	0	EA				1	No	1/D			
1	G	Room 4 Office to the Left	T	Pipe Insulation 2-6 inch	6100/01/0G/06	Confirmed	7	LF	0	LF				1	No	1/D			
1	G	Office Area across from Conference Room 10 Storage Closet nearest to the Entrance to the North	N/A	CMU		Non Suspect ACM	250	SF	0	SF		004C Was split into two separate rooms a closet and a restroom		N/A	N/A	N/A			
1	G	Office Area across from Conference Room 10 Storage Closet nearest to the Entrance to the North	M	Floor Tile VAT 9" x 9"	6100/01/0G/14	Confirmed	150	SF	0	SF	Black			1	No	1/D			
1	G	Office Area across from Conference Room 10 Storage Closet nearest to the Entrance to the North	N/A	Concrete Ceiling		Non Suspect ACM	150	SF	0	SF				N/A	N/A	N/A			
1	G	Office Area across from Conference Room 10 Storage Closet nearest to the Entrance to the North	N/A	Sheetrock Wall		Non Suspect ACM	100	SF	0	SF				N/A	N/A	N/A			
1	G	Office Area across the Hall from Conference Room 10 Restroom	N/A	CMU		Non Suspect ACM	250	SF	0	SF				N/A	N/A	N/A			
1	G	Office Area across the Hall from Conference Room 10 Restroom	M	Floor Tile VAT 12" x 12"	6100/01/0G/UJ	Assumed	150	SF	0	SF	Tan			1	No	1/D			
1	G	Office Area across the Hall from Conference Room 10 Restroom	N/A	Concrete Ceiling		Non Suspect ACM	150	SF	0	SF				N/A	N/A	N/A			
1	G	Office Area across the Hall from Conference Room 10 Restroom	N/A	Sheetrock Wall		Non Suspect ACM	100	SF	0	SF				N/A	N/A	N/A			
1	G	Office Area across the Hall from Conference Room 10 Foyer/Office Area Accepting Area	T	Pipe Fitting Insulation	6100/01/0G/12	Confirmed	4	EA	0	EA				1	No	1/D			
1	G	Office Area across the Hall from Conference Room 10 Foyer/Office Area Accepting Area	T	Pipe Insulation 2-6 inch	6100/01/0G/06	Confirmed	28	LF	0	LF				1	No	1/D			
1	G	Office Area across the Hall from Conference Room 10 Foyer/Office Area Accepting Area	N/A	Plaster Ceiling		NAD	400	SF	0	SF				N/A	N/A	N/A			
1	G	Office Area across the Hall from Conference Room 10 Foyer/Office Area Accepting Area	N/A	CMU		Non Suspect ACM	800	SF	0	SF				N/A	N/A	N/A			
1	G	Office Area across the Hall from Conference Room 10 Foyer/Office Area Accepting Area	N/A	Carpet		Non Suspect ACM	400	SF	0	SF				N/A	N/A	N/A			
1	G	Office with a Restroom across the Hall from Conference Room 10	T	Pipe Fitting Insulation	6100/01/0G/12	Confirmed	2	EA	0	EA				1	No	1/D			
1	G	Office with a Restroom across the Hall from Conference Room 10	T	Pipe Insulation 2-6 inch	6100/01/0G/06	Confirmed	5	LF	0	LF				1	No	1/D			
1	G	Office with a Restroom across the Hall from Conference Room 10	N/A	Concrete Ceiling		Non Suspect ACM	800	SF	0	SF				N/A	N/A	N/A			
1	G	Office with a Restroom across the Hall from Conference Room 10	N/A	Carpet		Non Suspect ACM	800	SF	0	SF				N/A	N/A	N/A			
1	G	Room #4	T	Pipe Fitting Insulation	6100/01/0G/12	Confirmed	13	EA	0	EA				1	No	1/D			
1	G	Room #4	T	Pipe Insulation 2-6 inch	6100/01/0G/06	Confirmed	50	LF	0	LF				1	No	1/D			
1	G	Room #4	N/A	Plaster Ceiling		NAD	800	SF	0	SF				N/A	N/A	N/A			
1	G	Room #4	N/A	CMU		Non Suspect ACM	600	SF	0	SF				N/A	N/A	N/A			
1	G	Room #4	N/A	Plaster Walls		NAD	600	SF	0	SF				N/A	N/A	N/A			
1	G	Room #4	M	Floor Tile VAT 9" x 9"	6100/01/0G/14	Confirmed	800	SF	0	SF	Black			1	No	1/D			
1	G	Room #4	M	Blackboard Glue Dots	6100/01/0G/VER/AR/2600	Assumed	10	SF	0	SF				1	No	1/D			
1	G	Entrance Hall/Foyer to Offices across from the middle Stairwell by the District 6 Hallway area	N/A	Carpet		Non Suspect ACM	280	SF	0	SF				N/A	N/A	N/A			
1	G	Entrance Hall/Foyer to Offices across from the middle Stairwell by the District 6 Hallway area	N/A	CMU		Non Suspect ACM	600	SF	0	SF				N/A	N/A	N/A			
1	G	Entrance Hall/Foyer to Offices across from the middle Stairwell by the District 6 Hallway area	N/A	Plaster Ceiling		NAD	280	SF	0	SF				N/A	N/A	N/A			
1	G	Entrance Hall/Foyer to Offices across from the middle Stairwell by the District 6 Hallway area	T	Pipe Insulation 2-6 inch	6100/01/0G/06	Confirmed	20	LF	0	LF				1	No	1/D			
1	G	Entrance Hall/Foyer to Offices across from the middle Stairwell by the District 6 Hallway area	T	Pipe Fitting Insulation	6100/01/0G/12	Confirmed	5	EA	0	EA				1	No	1/D			
1	G	Conference Room 3	T	Pipe Fitting Insulation	6100/01/0G/12	Confirmed	30	EA	0	EA				1	No	1/D			
1	G	Conference Room 3	T	Pipe Insulation 2-6 inch	6100/01/0G/06	Confirmed	125	LF	0	LF				1	No	1/D			
1	G	Conference Room 3	N/A	Plaster Ceiling		NAD	800	SF	0	SF				N/A	N/A	N/A			
1	G	Conference Room 3	N/A	CMU		Non Suspect ACM	1200	SF	0	SF				N/A	N/A	N/A			
1	G	Conference Room 3	N/A	Carpet		Non Suspect ACM	800	SF	0	SF				N/A	N/A	N/A			
1	G	Conference Room 3	M	Blackboard Glue Dots	6100/01/0G/VER/AR/2600	Assumed	800	SF	0	SF				1	No	1/D			
1	G	Conference Room 3 Closet	M	Floor Tile VAT 9" x 9"	6100/01/0G/14	Confirmed	5	SF	0	SF	Tan			1	No	1/D			
1	G	Conference Room 3 Closet	N/A	CMU		Non Suspect ACM	150	SF	0	SF				N/A	N/A	N/A			
1	G	Conference Room 3 Closet	N/A	Plaster Ceiling		NAD	5	SF	0	SF				N/A	N/A	N/A			
1	G	Stairwell at the Middle of District 6 Office Hallway to the West	N/A	Concrete Ceiling		Non Suspect ACM	200	SF	0	SF				N/A	N/A	N/A			
1	G	Stairwell at the Middle of District 6 Office Hallway to the West	N/A	Cement Floor		Non Suspect ACM	200	SF	0	SF				N/A	N/A	N/A			
1	G	Stairwell at the Middle of District 6 Office Hallway to the West	N/A	Ceramic Tile Walls		Non Suspect ACM	500	SF	0	SF				N/A	N/A	N/A			
1	G	Stairwell at the Middle of District 6 Office Hallway to the West	T	Radiator Insulation	6100/01/0G/SYN/BB/1600	Assumed	25	SF	0	SF		1 Recessed Radiator		1	No	1/D			
1	G	Men's Restroom across from Room 5	M	Transite Stalls	6100/01/0G/33	Confirmed	32	SF	0	SF		Holes drilled for toilet paper holders in all panels. Visible fibers observed		1	No	1/D			
1	G	Men's Restroom across from Room 5	N/A	Cement Floor		Non Suspect ACM	250	SF	0	SF				N/A	N/A	N/A			
1	G	Men's Restroom across from Room 5	T	Pipe Fitting Insulation	6100/01/0G/12	Confirmed	4	EA	0	EA				1	No	1/D			
1	G	Men's Restroom across from Room 5	T	Pipe Insulation 2-6 inch	6100/01/0G/06	Confirmed	17	LF	0	LF				1	No	1/D			
1	G	Men's Restroom across from Room 5	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	20	LF	0	LF				N/A	N/A	N/A			
1	G	Men's Restroom across from Room 5	N/A	Plaster Ceiling		NAD	250	SF	0	SF				N/A	N/A	N/A			
1	G	Men's Restroom across from Room 5	N/A	Ceramic Tile Walls		Non Suspect ACM	500	SF	0	SF				N/A	N/A	N/A			

6100/6460 Hill Freedman World Academy @ Leeds Campus 2015 2016 AHERA Three-Year Report.xls

School District of Philadelphia Hill Freedman World Academy @ Leeds Campus 1100 E. Mount Pleasant Avenue, Philadelphia, PA, 19150 ULCS# 6100 Year Built: 1953			AHERA Three-Year Reinspection 2015-2016 Room by Room Location Log Report										Reinspection Date: October 30, 2015 Building Inspector: A. Roman Number: 150619008 Management Planner: Megan Vala Number: 740728								
Item #	Floor	Room	On Site Room Name	System Affected	Material Description	HID#	Confirmed/Assumed/NAD/Non Suspect ACM	Amount of Material	SF	LF	EA	Amount of Damage	SF	LF	EA	Color required for VAT	Comments/Description/Notes	Attic/Crawl Space Potential Ranking	Damage Potential (DP)	Newly Friable (NF)	Response Action (RA)
1	G		Closet next to Men's Restroom	T	Pipe Fitting Insulation	6100/01/OG/12	Confirmed	4	EA	0	EA								1	No	1/D
1	G		Closet next to Men's Restroom	T	Pipe Insulation 2-6 inch	6100/01/OG/06	Confirmed	26	LF	0	LF								1	No	1/D
1	G		Closet next to Men's Restroom	N/A	Concrete Ceiling		Non Suspect ACM	50	SF	0	SF								N/A	N/A	N/A
1	G		Closet next to Men's Restroom	N/A	CMU		Non Suspect ACM	200	SF	0	SF								N/A	N/A	N/A
1	G		Closet next to Men's Restroom	N/A	Cement Floor		Non Suspect ACM	50	SF	0	SF								N/A	N/A	N/A
1	G		Hallway that connects the District 6 Suite of Rooms marked #5	N/A	Carpet		Non Suspect ACM	160	SF	0	SF								N/A	N/A	N/A
1	G		Hallway that connects the District 6 Suite of Rooms marked #5	N/A	CMU		Non Suspect ACM	300	SF	0	SF								N/A	N/A	N/A
1	G		Hallway that connects the District 6 Suite of Rooms marked #5	N/A	Concrete Ceiling		Non Suspect ACM	160	SF	0	SF								N/A	N/A	N/A
1	G		Hallway that connects the District 6 Suite of Rooms marked #5	M	Floor Tile VAT 9" x 9"	6100/01/OG/14	Confirmed	4	SF	0	SF					Green			1	No	1/D
1	G		Middle Room in the Area Marked Room 5	T	Pipe Fitting Insulation	6100/01/OG/12	Confirmed	2	EA	0	EA								1	No	1/D
1	G		Middle Room in the Area Marked Room 5	T	Pipe Insulation 2-6 inch	6100/01/OG/06	Confirmed	2	LF	0	LF								1	No	1/D
1	G		Middle Room in the Area Marked Room 5	N/A	Plaster Ceiling		NAD	300	SF	0	SF								N/A	N/A	N/A
1	G		Middle Room in the Area Marked Room 5	N/A	CMU		Non Suspect ACM	500	SF	0	SF								N/A	N/A	N/A
1	G		Middle Room in the Area Marked Room 5	N/A	Carpet		Non Suspect ACM	300	SF	0	SF								N/A	N/A	N/A
1	G		Office to the Left in the Area of Rooms marked Room 5	T	Pipe Fitting Insulation	6100/01/OG/12	Confirmed	7	EA	0	EA								1	No	1/D
1	G		Office to the Left in the Area of Rooms marked Room 5	T	Pipe Insulation 2-6 inch	6100/01/OG/06	Confirmed	40	LF	0	LF								1	No	1/D
1	G		Office to the Left in the Area of Rooms marked Room 5	N/A	Plaster Ceiling		NAD	400	SF	0	SF								N/A	N/A	N/A
1	G		Office to the Left in the Area of Rooms marked Room 5	N/A	CMU		Non Suspect ACM	500	SF	0	SF								N/A	N/A	N/A
1	G		Office to the Left in the Area of Rooms marked Room 5	N/A	Carpet		Non Suspect ACM	400	SF	0	SF								N/A	N/A	N/A
1	G		Office to the Left in the Area of Rooms marked Room 5	M	Blackboard Glue Dots	6100/01/OG/VER/AR/2600	Assumed	10	SF	0	SF								1	No	1/D
1	G		Office to the Left in the Area of Rooms marked Room 5 Storage Closet to the East	N/A	Plaster Ceiling		NAD	64	SF	0	SF								N/A	N/A	N/A
1	G		Office to the Left in the Area of Rooms marked Room 5 Storage Closet to the East	N/A	CMU		Non Suspect ACM	150	SF	0	SF								N/A	N/A	N/A
1	G		Office to the Left in the Area of Rooms marked Room 5 Storage Closet to the East	M	Floor Tile VAT 9" x 9"	6100/01/OG/14	Confirmed	64	SF	0	SF						Black		1	No	1/D
1	G		Office next to Stairwell 4	N/A	Carpet		Non Suspect ACM	300	SF	0	SF								N/A	N/A	N/A
1	G		Office next to Stairwell 4	N/A	Concrete Block Wall		Non Suspect ACM	900	SF	0	SF								N/A	N/A	N/A
1	G		Office next to Stairwell 4	N/A	Concrete Ceiling		Non Suspect ACM	300	SF	0	SF								N/A	N/A	N/A
1	G		Office next to Stairwell 4	M	Blackboard Glue Dots	6100/01/OG/VER/AR/2600	Assumed	40	SF	0	SF								1	No	1/D
1	G		Office next to Stairwell 4	T	Pipe Insulation 2-6 inch	6100/01/OG/06	Confirmed	10	LF	0	LF								1	No	1/D
1	G		Computer Lab Room 6	T	Pipe Fitting Insulation	6100/01/OG/12	Confirmed	15	EA	0	EA								1	No	1/D
1	G		Computer Lab Room 6	T	Pipe Insulation 2-6 inch	6100/01/OG/06	Confirmed	64	LF	0	LF								1	No	1/D
1	G		Computer Lab Room 6	N/A	Plaster Ceiling		NAD	800	SF	0	SF								N/A	N/A	N/A
1	G		Computer Lab Room 6	N/A	CMU		Non Suspect ACM	1200	SF	0	SF								N/A	N/A	N/A
1	G		Computer Lab Room 6	M	Floor Tile VAT 12" x 12"	6100/01/OG/JJ	Assumed	800	SF	0	SF						Blue		1	No	1/D
1	G		Administrative Office adjacent to the Computer Lab Room 6 to the South	T	Pipe Fitting Insulation	6100/01/OG/12	Confirmed	2	EA	0	EA								1	No	1/D
1	G		Administrative Office adjacent to the Computer Lab Room 6 to the South	T	Pipe Insulation 2-6 inch	6100/01/OG/06	Confirmed	3	EA	0	EA								1	No	1/D
1	G		Administrative Office adjacent to the Computer Lab Room 6 to the South	N/A	Plaster Ceiling		NAD	500	SF	0	SF								N/A	N/A	N/A
1	G		Administrative Office adjacent to the Computer Lab Room 6 to the South	N/A	CMU		Non Suspect ACM	800	SF	0	SF								N/A	N/A	N/A
1	G		Administrative Office adjacent to the Computer Lab Room 6 to the South	N/A	Carpet		Non Suspect ACM	500	SF	0	SF								N/A	N/A	N/A
1	G		Small Hallway that connects the District 6 Main Office Foyer/Acceptance Area to the Administrative Office adjoining the Computer Lab Room 6 to the South	T	Pipe Fitting Insulation	6100/01/OG/12	Confirmed	2	EA	0	EA								1	No	1/D
1	G		Small Hallway that connects the District 6 Main Office Foyer/Acceptance Area to the Administrative Office adjoining the Computer Lab Room 6 to the South	T	Pipe Insulation 2-6 inch	6100/01/OG/06	Confirmed	3	LF	0	LF								1	No	1/D
1	G		Small Hallway that connects the District 6 Main Office Foyer/Acceptance Area to the Administrative Office adjoining the Computer Lab Room 6 to the South	N/A	Plaster Ceiling		NAD	200	SF	0	SF								N/A	N/A	N/A
1	G		Small Hallway that connects the District 6 Main Office Foyer/Acceptance Area to the Administrative Office adjoining the Computer Lab Room 6 to the South	N/A	CMU		Non Suspect ACM	300	SF	0	SF								N/A	N/A	N/A
1	G		Small Hallway that connects the District 6 Main Office Foyer/Acceptance Area to the Administrative Office adjoining the Computer Lab Room 6 to the South	M	Floor Tile VAT 12" x 12"	6100/01/OG/JJ	Assumed	200	SF	0	SF						Blue		1	No	1/D
1	G		District 6 Main Office Storage Closet to the North	N/A	Plaster Ceiling		NAD	200	SF	0	SF								N/A	N/A	N/A
1	G		District 6 Main Office Storage Closet to the North	N/A	CMU		Non Suspect ACM	300	SF	0	SF								N/A	N/A	N/A
1	G		District 6 Main Office Storage Closet to the North	M	Floor Tile VAT 9" x 9"	6100/01/OG/14	Confirmed	200	SF	0	SF								1	No	1/D
1	G		Room 7	T	Pipe Fitting Insulation	6100/01/OG/12	Confirmed	7	EA	0	EA								1	No	1/D
1	G		Room 7	T	Pipe Insulation 2-6 inch	6100/01/OG/06	Confirmed	30	LF	0	LF								1	No	1/D
1	G		Room 7	N/A	Plaster Ceiling		NAD	800	SF	0	SF								N/A	N/A	N/A
1	G		Room 7	N/A	Carpet		Non Suspect ACM	800	SF	0	SF								N/A	N/A	N/A
1	G		Mail/IT Room next to Conference Room 9	N/A	CMU		Non Suspect ACM	250	SF	0	SF								N/A	N/A	N/A
1	G		Mail/IT Room next to Conference Room 9	N/A	Concrete Ceiling		Non Suspect ACM	100	SF	0	SF								N/A	N/A	N/A
1	G		Mail/IT Room next to Conference Room 9	M	Floor Tile VAT 9" x 9"	6100/01/OG/14	Confirmed	100	SF	0	SF								1	No	1/D
1	G		Conference Room Behind Mail/IT Room	T	Pipe Fitting Insulation	6100/01/OG/12	Confirmed	4	EA	0	EA								1	No	1/D
1	G		Conference Room Behind Mail/IT Room	T	Pipe Insulation 2-6 inch	6100/01/OG/06	Confirmed	12	LF	0	LF								1	No	1/D
1	G		Conference Room Behind Mail/IT Room	N/A	Concrete Ceiling		Non Suspect ACM	700	SF	0	SF								N/A	N/A	N/A
1	G		Conference Room Behind Mail/IT Room	N/A	CMU		Non Suspect ACM	1200	SF	0	SF								N/A	N/A	N/A
1	G		Conference Room Behind Mail/IT Room	N/A	Carpet		Non Suspect ACM	700	SF	0	SF								N/A	N/A	N/A
1	G		Conference Room Behind Mail/IT Room	M	Blackboard Glue Dots	6100/01/OG/VER/AR/2600	Assumed	10	SF	0	SF								1	No	1/D
1	G		Office across the Hall from the District 6 Main Office Entrance	T	Pipe Fitting Insulation	6100/01/OG/12	Confirmed	3	EA	0	EA								1	No	1/D
1	G		Office across the Hall from the District 6 Main Office Entrance	T	Pipe Insulation 2-6 inch	6100/01/OG/06	Confirmed	10	LF	0	LF								1	No	1/D
1	G		Office across the Hall from the District 6 Main Office Entrance	N/A	Concrete Ceiling		Non Suspect ACM	200	SF	0	SF								N/A	N/A	N/A
1	G		Office across the Hall from the District 6 Main Office Entrance	N/A	CMU		Non Suspect ACM	250	SF	0	SF								N/A	N/A	N/A
1	G		Office across the Hall from the District 6 Main Office Entrance	N/A	Carpet		Non Suspect ACM	200	SF	0	SF								N/A	N/A	N/A

6100/6460 Hill Freedman World Academy @ Leeds Campus 2015 2016 AHERA Three-Year Report.xls

School District of Philadelphia Hill Freedman World Academy @ Leeds Campus 1100 E. Mount Pleasant Avenue, Philadelphia, PA, 19150 ULCS# 6100 Year Built: 1953			AHERA Three-Year Reinspection 2015-2016 Room by Room Location Log Report										Reinspection Date: October 30, 2015 Building Inspector: A. Roman Number: 150619008 Management Planner: Megan Vala Number: 740728						
Element	Floor	Room	On Site Room Name	System Affected	Material Description	HID#	Confirmed/Assumed/NAD/ Non Suspect ACM	Amount of Material	SF LF EA	Amount of Damage	SF LF EA	Color required for VAT	Comments/Description/Notes	Attic/ Crawl/ Space Ranking	Damage Potential (DP)	Newly Friable (NF)	Response Action (RA)		
1	G		Office across the Hall from the District 6 Main Office Entrance	M	Blackboard Glue Dots	6100/01/0G/VER/AR/2600	Assumed	10	SF	0	SF								
1	G		Office across the Hall from the District 6 Main Office Entrance Closet	N/A	Concrete Ceiling		Non Suspect ACM	80	SF	0	SF				1	No	N/A		
1	G		Office across the Hall from the District 6 Main Office Entrance Closet	N/A	CMU		Non Suspect ACM	200	SF	0	SF				N/A	N/A	N/A		
1	G		Office across the Hall from the District 6 Main Office Entrance Closet	M	Floor Tile VAT 9" x 9"	6100/01/0G/14	Confirmed	80	SF	0	SF	Black			1	No	1/D		
1	G		Office to the Left in the Area of Rooms Marked Room 5 Storage Closet to the West	N/A	Concrete Ceiling		Non Suspect ACM	80	SF	0	SF				N/A	N/A	N/A		
1	G		Office to the Left in the Area of Rooms Marked Room 5 Storage Closet to the West	N/A	CMU		Non Suspect ACM	200	SF	0	SF				N/A	N/A	N/A		
1	G		Office to the Left in the Area of Rooms Marked Room 5 Storage Closet to the West	N/A	Carpet		Non Suspect ACM	80	SF	0	SF				N/A	N/A	N/A		
1	G		Superintendent Office/Conference Room	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	12	LF	0	LF				N/A	N/A	N/A		
1	G		Superintendent Office/Conference Room	N/A	Ceiling Tile 2' x 4'		Non Suspect ACM	700	SF	0	SF				N/A	N/A	N/A		
1	G		Superintendent Office/Conference Room	N/A	Plaster Walls		NAD	200	SF	0	SF				N/A	N/A	N/A		
1	G		Superintendent Office/Conference Room	N/A	CMU		Non Suspect ACM	1000	SF	0	SF				N/A	N/A	N/A		
1	G		Superintendent Office/Conference Room	N/A	Carpet		Non Suspect ACM	700	SF	0	SF				N/A	N/A	N/A		
1	G		District 6 Main Office Restroom to the South	N/A	Cement Floor		Non Suspect ACM	250	SF	0	SF				N/A	N/A	N/A		
1	G		District 6 Main Office Restroom to the South	N/A	Concrete Block Wall		Non Suspect ACM	750	SF	0	SF				N/A	N/A	N/A		
1	G		District 6 Main Office Restroom to the South	N/A	Wood Stall Partitions		Non Suspect ACM	80	SF	0	SF				N/A	N/A	N/A		
1	G		District 6 Main Office Restroom to the South	N/A	Concrete Ceiling		Non Suspect ACM	250	SF	0	SF				N/A	N/A	N/A		
1	G		District 6 Main Office Restroom to the South	T	Pipe Insulation 2-6 inch	6100/01/0G/06	Confirmed	7	LF	0	LF		Applied to Drain Line		1	No	1/D		
1	G		District 6 Main Office Restroom to the South	T	Pipe Fitting Insulation	6100/01/0G/12	Confirmed	1	EA	0	EA		Applied to Drain Line		1	No	1/D		
1	G		District 6 Main Office Restroom to the South	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	10	LF	0	LF				N/A	N/A	N/A		
1	G		Closet in District 6 Main Office Hallway	N/A	Concrete Ceiling		Non Suspect ACM	80	SF	0	SF				N/A	N/A	N/A		
1	G		Closet in District 6 Main Office Hallway	N/A	CMU		Non Suspect ACM	200	SF	0	SF				N/A	N/A	N/A		
1	G		Closet in District 6 Main Office Hallway	M	Floor Tile VAT 9" x 9"	6100/01/0G/14	Confirmed	80	SF	0	SF	Black			1	No	1/D		
1	G		Closet in District 6 Main Office Hallway	N/A	Concrete Ceiling		Non Suspect ACM	100	SF	0	SF				N/A	N/A	N/A		
1	G		Closet in District 6 Main Office Hallway	N/A	CMU		Non Suspect ACM	250	SF	0	SF				N/A	N/A	N/A		
1	G		Closet in District 6 Main Office Hallway	M	Floor Tile VAT 9" x 9"	6100/01/0G/14	Confirmed	100	SF	0	SF	Black			1	No	1/D		
1	G		District 6 Main Office Hallway	T	Pipe Insulation 2-6 inch	6100/01/0G/06	Confirmed	30	LF	0	LF				1	No	1/D		
1	G		District 6 Main Office Hallway	N/A	Ceiling Tile 2' x 4'		Non Suspect ACM	300	SF	0	SF				N/A	N/A	N/A		
1	G		District 6 Main Office Hallway	N/A	CMU		Non Suspect ACM	700	SF	0	SF				N/A	N/A	N/A		
1	G		District 6 Main Office Hallway	M	Floor Tile VAT 12" x 12"	6100/01/0G/UJ	Assumed	300	SF	0	SF	Blue			1	No	1/D		
1	G		Conference Room in Main Office District 6 Superintendent room #8	T	Pipe Insulation 2-6 inch	6100/01/0G/06	Confirmed	10	LF	0	LF				1	No	1/D		
1	G		Conference Room in Main Office District 6 Superintendent room #8	N/A	Ceiling Tile 2' x 4'		Non Suspect ACM	400	SF	0	SF				N/A	N/A	N/A		
1	G		Conference Room in Main Office District 6 Superintendent room #8	N/A	CMU		Non Suspect ACM	1200	SF	0	SF				N/A	N/A	N/A		
1	G		Conference Room in Main Office District 6 Superintendent room #8	N/A	Carpet		Non Suspect ACM	400	SF	0	SF				N/A	N/A	N/A		
1	G		Conference Room 9	T	Pipe Fitting Insulation	6100/01/0G/12	Confirmed	9	EA	0	EA				1	No	1/D		
1	G		Conference Room 9	T	Pipe Insulation 2-6 inch	6100/01/0G/06	Confirmed	30	LF	0	LF				1	No	1/D		
1	G		Conference Room 9	N/A	Concrete Ceiling		Non Suspect ACM	800	SF	0	SF				N/A	N/A	N/A		
1	G		Conference Room 9	N/A	CMU		Non Suspect ACM	1200	SF	0	SF				N/A	N/A	N/A		
1	G		Conference Room 9	N/A	Carpet		Non Suspect ACM	800	SF	0	SF				N/A	N/A	N/A		
1	G		Conference Room 9	M	Blackboard Glue Dots	6100/01/0G/VER/AR/2600	Assumed	10	SF	0	SF				1	No	1/D		
1	G		Conference Room 9 Storage Closet to the West	T	Pipe Fitting Insulation	6100/01/0G/12	Confirmed	9	EA	0	EA				1	No	1/D		
1	G		Conference Room 9 Storage Closet to the West	T	Pipe Insulation 2-6 inch	6100/01/0G/06	Confirmed	30	LF	0	LF				1	No	1/D		
1	G		Conference Room 9 Storage Closet to the West	N/A	Concrete Ceiling		Non Suspect ACM	144	SF	0	SF				N/A	N/A	N/A		
1	G		Conference Room 9 Storage Closet to the West	N/A	CMU		Non Suspect ACM	250	SF	0	SF				N/A	N/A	N/A		
1	G		Conference Room 9 Storage Closet to the West	M	Floor Tile VAT 9" x 9"	6100/01/0G/14	Confirmed	144	SF	0	SF	Tan			1	No	1/D		
1	G		Conference Room 9 Storage Closet to the East	N/A	Concrete Ceiling		Non Suspect ACM	144	SF	0	SF				N/A	N/A	N/A		
1	G		Conference Room 9 Storage Closet to the East	N/A	CMU		Non Suspect ACM	250	SF	0	SF				N/A	N/A	N/A		
1	G		Conference Room 9 Storage Closet to the East	M	Floor Tile VAT 9" x 9"	6100/01/0G/14	Confirmed	144	SF	0	SF	Green			1	No	1/D		
1	G		Conference Room 9 Storage Closet to the East	M	Vibration Damper Cloth	6100/01/0G/13	Assumed	2	EA	0	EA				1	No	1/D		
1	G		Women's Restroom at the Southeast corner of the Main Hallway in the District 6 Area	T	Pipe Fitting Insulation	6100/01/0G/12	Confirmed	1	EA	0	EA				1	No	1/D		
1	G		Women's Restroom at the Southeast corner of the Main Hallway in the District 6 Area	T	Pipe Insulation 2-6 inch	6100/01/0G/06	Confirmed	20	LF	0	LF				1	No	1/D		
1	G		Women's Restroom at the Southeast corner of the Main Hallway in the District 6 Area	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	10	LF	0	LF				N/A	N/A	N/A		
1	G		Women's Restroom at the Southeast corner of the Main Hallway in the District 6 Area	N/A	Concrete Ceiling		Non Suspect ACM	300	SF	0	SF				N/A	N/A	N/A		
1	G		Women's Restroom at the Southeast corner of the Main Hallway in the District 6 Area	N/A	Ceramic Tile Walls		Non Suspect ACM	700	SF	0	SF				N/A	N/A	N/A		
1	G		Women's Restroom at the Southeast corner of the Main Hallway in the District 6 Area	M	Floor Tile VAT 9" x 9"	6100/01/0G/14	Confirmed	40	SF	0	SF	Green			1	No	1/D		
1	G		Women's Restroom at the Southeast corner of the Main Hallway in the District 6 Area	N/A	Cement Floor		Non Suspect ACM	260	SF	0	SF				N/A	N/A	N/A		
1	G		Storage next to Women's Restroom at the Southeast of the main hallway in the District 6 Area	N/A	Concrete Ceiling		Non Suspect ACM	500	SF	0	SF				N/A	N/A	N/A		
1	G		Storage next to Women's Restroom at the Southeast of the main hallway in the District 6 Area	N/A	CMU		Non Suspect ACM	750	SF	0	SF				N/A	N/A	N/A		
1	G		Storage next to Women's Restroom at the Southeast of the main hallway in the District 6 Area	M	Floor Tile VAT 9" x 9"	6100/01/0G/14	Confirmed	500	SF	0	SF	Black			1	No	1/D		
1	G		Elevator	M	Floor Tile VAT 12" x 12"	6100/01/0G/UJ	Assumed	40	SF	0	SF	Tan			1	No	1/D		
1	G		District 6 Offices Hallway	T	Pipe Insulation 2-6 inch	6100/01/0G/06	Confirmed	12	SF	0	SF				1	No	1/D		
1	G		District 6 Offices Hallway	N/A	Concrete Ceiling		Non Suspect ACM	100	SF	0	SF				N/A	N/A	N/A		
1	G		District 6 Offices Hallway	N/A	CMU		Non Suspect ACM	200	SF	0	SF				N/A	N/A	N/A		
1	G		District 6 Offices Hallway	N/A	Cement Floor		Non Suspect ACM	100	SF	0	SF				N/A	N/A	N/A		

6100/6460 Hill Freedman World Academy @ Leeds Campus 2015 2016 AHERA Three-Year Report.xls

School District of Philadelphia Hill Freedman World Academy @ Leeds Campus 1100 E. Mount Pleasant Avenue, Philadelphia, PA, 19150 ULCS# 6100 Year Built: 1953			AHERA Three-Year Reinspection 2015-2016 Room by Room Location Log Report										Reinspection Date: October 30, 2015 Building Inspector: A. Roman Number: 150619008 Management Planner: Megan Vala Number: 740728						
E l e m e n t	F l o o r	On Site Room Name	System Affected	Material Description	HID#	Confirmed/Assumed/NAD/ Non Suspect ACM	Amount of Material	SF LF EA	Amount of Damage	SF LF EA	Color required for VAT	Comments/Description/Notes	Attic/ Crawl Space Ranking	Damage Potential (DP)	Newly Friable (NF)	Response Action (RA)			
1	G	District 6 Offices Hallway	T	Radiator Insulation	6100/01/0G/SYN/BB/1600	Assumed	25	SF	0	SF		1 Recessed Radiator		1	No	1/D			
1	G	District 6 Offices Hallway	M	Transite Electrical Panel	6100/01/0G/SYN/BB/2350	Assumed	20	SF	0	SF				1	No	1/D			
1	G	Hallway running East to West at Leeds Storage Closet	N/A	Concrete Ceiling		Non Suspect ACM	450	SF	0	SF				N/A	N/A	N/A			
1	G	Hallway running East to West at Leeds Storage Closet	N/A	CMU		Non Suspect ACM	1000	SF	0	SF				N/A	N/A	N/A			
1	G	Hallway running East to West at Leeds Storage Closet	M	Floor Tile VAT 9" x 9"	6100/01/0G/14	Confirmed	450	SF	0	SF	Green			1	No	1/D			
1	G	Hallway running East to West at Leeds Storage Closet	T	Radiator Insulation	6100/01/0G/SYN/BB/1600	Assumed	25	SF	0	SF		1 Recessed Radiator		1	No	1/D			
1	G	Stairwell in the Incinerator Room	N/A	Concrete Ceiling		Non Suspect ACM	200	SF	0	SF				N/A	N/A	N/A			
1	G	Stairwell in the Incinerator Room	N/A	Cement Floor		Non Suspect ACM	200	SF	0	SF				N/A	N/A	N/A			
1	G	Stairwell in the Incinerator Room	N/A	CMU		Non Suspect ACM	500	SF	0	SF				N/A	N/A	N/A			
1	G	Stairwell outside Leeds Supply Closet leading to the Parking Lot to the East	N/A	Ceramic Tile Walls		Non Suspect ACM	500	SF	0	SF				N/A	N/A	N/A			
1	G	Stairwell outside Leeds Supply Closet leading to the Parking Lot to the East	N/A	Cement Floor		Non Suspect ACM	200	SF	0	SF				N/A	N/A	N/A			
1	G	Stairwell outside Leeds Supply Closet leading to the Parking Lot to the East	N/A	Concrete Ceiling		Non Suspect ACM	200	SF	0	SF				N/A	N/A	N/A			
1	G	Stairwell outside Leeds Supply Closet leading to the Parking Lot to the East	T	Pipe Fitting Insulation	6100/01/0G/12	Confirmed	9	EA	0	EA				1	No	1/D			
1	G	Stairwell outside Leeds Supply Closet leading to the Parking Lot to the East	T	Pipe Insulation 2-6 inch	6100/01/0G/06	Confirmed	20	LF	0	LF				1	No	1/D			
1	G	Stairwell outside Leeds Supply Closet leading to the Parking Lot to the East	T	Radiator Insulation	6100/01/0G/SYN/BB/1600	Assumed	25	SF	0	SF		1 Recessed Radiator		1	No	1/D			
1	G	Mechanical Room to the Southeast	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	300	LF	0	LF				N/A	N/A	N/A			
1	G	Mechanical Room to the Southeast	N/A	Concrete Ceiling		Non Suspect ACM	2500	SF	0	SF				N/A	N/A	N/A			
1	G	Mechanical Room to the Southeast	N/A	CMU		Non Suspect ACM	5000	SF	0	SF				N/A	N/A	N/A			
1	G	Mechanical Room to the Southeast	N/A	Cement Floor		Non Suspect ACM	2500	SF	0	SF				N/A	N/A	N/A			
1	G	Stairwell leading to the Mechanical Room from the Building Engineer's Suite	N/A	Metal Staircase		Non Suspect ACM	200	SF	0	SF				N/A	N/A	N/A			
1	G	Stairwell leading to the Mechanical Room from the Building Engineer's Suite	N/A	Concrete Ceiling		Non Suspect ACM	200	SF	0	SF				N/A	N/A	N/A			
1	G	Stairwell leading to the Mechanical Room from the Building Engineer's Suite	N/A	Concrete Block Wall		Non Suspect ACM	500	SF	0	SF				N/A	N/A	N/A			
1	G	Stairwell in Mechanical Room at the Southeastern most Corner	N/A	CMU		Non Suspect ACM	500	SF	0	SF				N/A	N/A	N/A			
1	G	Stairwell in Mechanical Room at the Southeastern most Corner	N/A	Cement Floor		Non Suspect ACM	200	SF	0	SF				N/A	N/A	N/A			
1	G	Stairwell in Mechanical Room at the Southeastern most Corner	N/A	Concrete Ceiling		Non Suspect ACM	200	SF	0	SF				N/A	N/A	N/A			
1	G	Fan Room attached to the Storage Room to the Left of Leeds Supply Closet	T	Pipe Fitting Insulation	6100/01/0G/12	Confirmed	8	EA	0	EA				1	No	1/D			
1	G	Fan Room attached to the Storage Room to the Left of Leeds Supply Closet	T	Pipe Insulation 2-6 inch	6100/01/0G/06	Confirmed	20	LF	0	LF				1	No	1/D			
1	G	Fan Room attached to the Storage Room to the Left of Leeds Supply Closet	N/A	Concrete Ceiling		Non Suspect ACM	400	SF	0	SF				N/A	N/A	N/A			
1	G	Fan Room attached to the Storage Room to the Left of Leeds Supply Closet	N/A	CMU		Non Suspect ACM	700	SF	0	SF				N/A	N/A	N/A			
1	G	Fan Room attached to the Storage Room to the Left of Leeds Supply Closet	N/A	Cement Floor		Non Suspect ACM	400	SF	0	SF				N/A	N/A	N/A			
1	G	Fan Room attached to the Storage Room to the Left of Leeds Supply Closet	M	Vibration Damper Cloth	6100/01/0G/13	Assumed	4	EA	0	EA				1	No	1/D			
1	G	Storage to the Left of Leeds Supply Room	T	Pipe Fitting Insulation	6100/01/0G/12	Confirmed	39	EA	0	EA				1	No	1/D			
1	G	Storage to the Left of Leeds Supply Room	T	Pipe Insulation 2-6 inch	6100/01/0G/06	Confirmed	250	LF	0	LF				1	No	1/D			
1	G	Storage to the Left of Leeds Supply Room	N/A	Concrete Ceiling		Non Suspect ACM	800	SF	0	SF				N/A	N/A	N/A			
1	G	Storage to the Left of Leeds Supply Room	N/A	CMU		Non Suspect ACM	1200	SF	0	SF				N/A	N/A	N/A			
1	G	Storage to the Left of Leeds Supply Room	M	Floor Tile VAT 9" x 9"	6100/01/0G/14	Confirmed	800	SF	0	SF	Black			1	No	1/D			
1	G	Leeds Supply Closet	X	X		X	X	X	X	X		No Access; Door Knob is Missing		X	X	X			
1	G	Custodial Closet next to Hallway to Building Engineer's Office	N/A	Cement Floor		Non Suspect ACM	25	SF	0	SF				N/A	N/A	N/A			
1	G	Custodial Closet next to Hallway to Building Engineer's Office	N/A	Concrete Block Wall		Non Suspect ACM	75	SF	0	SF				N/A	N/A	N/A			
1	G	Custodial Closet next to Hallway to Building Engineer's Office	N/A	Concrete Ceiling		Non Suspect ACM	25	SF	0	SF				N/A	N/A	N/A			
1	G	Custodial Closet next to Hallway to Building Engineer's Office	T	Pipe Insulation 2-6 inch	6100/01/0G/06	Confirmed	10	LF	0	LF		No damage identified, however, MAG Asbestos Fibers have been released from lagging near ceiling - DDC Required for cleanup/repair		1	No	1/D			
1	G	Custodial Closet next to Hallway to Building Engineer's Office	T	Pipe Insulation > 6 inch	6100/01/0G/08	Confirmed	10	LF	0	LF		No damage identified, however, MAG Asbestos Fibers have been released from lagging near ceiling - DDC Required for cleanup/repair		1	No	1/D			
1	G	Building Engineer's Office	T	Pipe Fitting Insulation	6100/01/0G/12	Confirmed	2	EA	0	EA				1	No	1/D			
1	G	Building Engineer's Office	T	Pipe Insulation 2-6 inch	6100/01/0G/06	Confirmed	20	LF	0	LF				1	No	1/D			
1	G	Building Engineer's Office	N/A	Concrete Ceiling		Non Suspect ACM	300	SF	0	SF				N/A	N/A	N/A			
1	G	Building Engineer's Office	N/A	CMU		Non Suspect ACM	700	SF	0	SF				N/A	N/A	N/A			
1	G	Building Engineer's Office	N/A	Cement Floor		Non Suspect ACM	300	SF	0	SF				N/A	N/A	N/A			
1	G	Building Engineer's Office Closet	N/A	Cement Floor		Non Suspect ACM	20	SF	0	SF				N/A	N/A	N/A			
1	G	Building Engineer's Office Closet	N/A	Concrete Block Wall		Non Suspect ACM	60	SF	0	SF				N/A	N/A	N/A			
1	G	Building Engineer's Office Closet	N/A	Concrete Ceiling		Non Suspect ACM	20	SF	0	SF				N/A	N/A	N/A			
1	G	Building Engineer's Office Closet	T	Pipe Insulation 2-6 inch	6100/01/0G/06	Confirmed	3	LF	0	LF				1	No	1/D			
1	G	Building Engineer's Office Closet	T	Pipe Fitting Insulation	6100/01/0G/12	Confirmed	2	EA	0	EA				1	No	1/D			
1	G	Building Engineer's Office Restroom	N/A	Cement Floor		Non Suspect ACM	32	SF	0	SF				N/A	N/A	N/A			
1	G	Building Engineer's Office Restroom	N/A	Concrete Block Wall		Non Suspect ACM	96	SF	0	SF				N/A	N/A	N/A			
1	G	Building Engineer's Office Restroom	N/A	Concrete Ceiling		Non Suspect ACM	32	SF	0	SF				N/A	N/A	N/A			
1	G	Building Engineer's Office Restroom	T	Pipe Insulation 2-6 inch	6100/01/0G/06	Confirmed	16	LF	0	LF				1	No	1/D			
1	G	Building Engineer's Office Restroom	T	Pipe Fitting Insulation	6100/01/0G/12	Confirmed	5	EA	0	EA				1	No	1/D			
1	G	Building Engineer's Office Restroom	M	Transite Stairs	6100/01/0G/SYN/BB/2310	Confirmed	15	SF	0	SF				1	No	1/D			
1	G	Hallway in Building Engineer's Office	T	Pipe Fitting Insulation	6100/01/0G/12	Confirmed	8	EA	0	EA				1	No	1/D			
1	G	Hallway in Building Engineer's Office	T	Pipe Insulation 2-6 inch	6100/01/0G/06	Confirmed	20	LF	0	LF				1	No	1/D			
1	G	Hallway in Building Engineer's Office	N/A	Concrete Ceiling		Non Suspect ACM	400	SF	0	SF				N/A	N/A	N/A			
1	G	Hallway in Building Engineer's Office	N/A	CMU		Non Suspect ACM	900	SF	0	SF				N/A	N/A	N/A			
1	G	Hallway in Building Engineer's Office	N/A	Cement Floor		Non Suspect ACM	400	SF	0	SF				N/A	N/A	N/A			
1	G	Custodian Storage across from the Building Engineer	T	Pipe Fitting Insulation	6100/01/0G/12	Confirmed	15	EA	0	EA				1	No	1/D			
1	G	Custodian Storage across from the Building Engineer	T	Pipe Insulation 2-6 inch	6100/01/0G/06	Confirmed	50	LF	0	LF				1	No	1/D			
1	G	Custodian Storage across from the Building Engineer	T	Pipe Insulation > 6 inch	6100/01/0G/08	Confirmed	50	LF	0	LF				1	No	1/D			

6100/6460 Hill Freedman World Academy @ Leeds Campus 2015 2016 AHRA Three-Year Report.xls

School District of Philadelphia Hill Freedman World Academy @ Leeds Campus 1100 E. Mount Pleasant Avenue, Philadelphia, PA, 19150 ULCS# 6100 Year Built: 1953			AHERA Three-Year Reinspection 2015-2016 Room by Room Location Log Report										Reinspection Date: October 30, 2015 Building Inspector: A. Roman Number: 150619008 Management Planner: Megan Vala Number: 740728			Attic/ Crawl Space Ranking	Damage Potential (DP)	Newly Friable (NF)	Response Action (RA)
Element	Room	On Site Room Name	System Affected	Material Description	HID#	Confirmed/Assumed/NAD/ Non Suspect ACM	Amount of Material	SF LF EA	Amount of Damage	SF LF EA	Color required for VAT	Comments/Description/Notes							
1	G	Custodian Storage across from the Building Engineer	N/A	Concrete Ceiling		Non Suspect ACM	1000	SF	0	SF							N/A	N/A	N/A
1	G	Custodian Storage across from the Building Engineer	N/A	CMU		Non Suspect ACM	2500	SF	0	SF							N/A	N/A	N/A
1	G	Custodian Storage across from the Building Engineer	M	Floor Tile VAT 9" x 9"	6100/01/0G/14	Confirmed	1000	SF	0	SF	Black						1	No	1/D
1	G	Women's Lounge in Building Engineer's Area	T	Pipe Fitting Insulation	6100/01/0G/12	Confirmed	6	EA	0	EA							1	No	1/D
1	G	Women's Lounge in Building Engineer's Area	T	Pipe Insulation 2-6 inch	6100/01/0G/06	Confirmed	20	LF	0	LF							1	No	1/D
1	G	Women's Lounge in Building Engineer's Area	N/A	Concrete Ceiling		Non Suspect ACM	300	SF	0	SF							N/A	N/A	N/A
1	G	Women's Lounge in Building Engineer's Area	N/A	Cement Floor		Non Suspect ACM	300	SF	0	SF							N/A	N/A	N/A
1	G	Women's Lounge in Building Engineer's Area	N/A	CMU		Non Suspect ACM	700	SF	0	SF							N/A	N/A	N/A
1	G	Building Engineer's Women's Lounge Restroom	T	Pipe Fitting Insulation	6100/01/0G/12	Confirmed	7	EA	0	EA							1	No	1/D
1	G	Building Engineer's Women's Lounge Restroom	T	Pipe Insulation 2-6 inch	6100/01/0G/06	Confirmed	20	LF	0	LF							1	No	1/D
1	G	Building Engineer's Women's Lounge Restroom	N/A	Concrete Ceiling		Non Suspect ACM	100	SF	0	SF							N/A	N/A	N/A
1	G	Building Engineer's Women's Lounge Restroom	N/A	CMU		Non Suspect ACM	250	SF	0	SF							N/A	N/A	N/A
1	G	Building Engineer's Women's Lounge Restroom	N/A	Cement Floor		Non Suspect ACM	100	SF	0	SF							N/A	N/A	N/A
1	G	Hallway in Building Engineer's Office Area	N/A	Cement Floor		Non Suspect ACM	200	SF	0	SF							N/A	N/A	N/A
1	G	Hallway in Building Engineer's Office Area	N/A	Concrete Ceiling		Non Suspect ACM	200	SF	0	SF							N/A	N/A	N/A
1	G	Hallway in Building Engineer's Office Area	N/A	CMU		Non Suspect ACM	500	SF	0	SF							N/A	N/A	N/A
1	G	Hallway leading from the Building Engineer's Women's Lounge to the Room marked Workout Room	N/A	Concrete Ceiling		Non Suspect ACM	300	SF	0	SF							N/A	N/A	N/A
1	G	Hallway leading from the Building Engineer's Women's Lounge to the Room marked Workout Room	N/A	Cement Floor		Non Suspect ACM	300	SF	0	SF							N/A	N/A	N/A
1	G	Hallway leading from the Building Engineer's Women's Lounge to the Room marked Workout Room	N/A	CMU		Non Suspect ACM	600	SF	0	SF							N/A	N/A	N/A
1	G	Building Engineer's Lounge	T	Pipe Fitting Insulation	6100/01/0G/12	Confirmed	7	EA	0	EA							1	No	1/D
1	G	Building Engineer's Lounge	T	Pipe Insulation 2-6 inch	6100/01/0G/06	Confirmed	20	LF	0	LF							1	No	1/D
1	G	Building Engineer's Lounge	N/A	Cement Floor		Non Suspect ACM	400	SF	0	SF							N/A	N/A	N/A
1	G	Building Engineer's Lounge	N/A	CMU		Non Suspect ACM	1000	SF	0	SF							N/A	N/A	N/A
1	G	Building Engineer's Lounge	N/A	Concrete Ceiling		Non Suspect ACM	400	SF	0	SF							N/A	N/A	N/A
1	G	Building Engineer's Lounge Men's Restroom	T	Pipe Fitting Insulation	6100/01/0G/12	Confirmed	1	EA	0	EA							1	No	1/D
1	G	Building Engineer's Lounge Men's Restroom	T	Pipe Insulation 2-6 inch	6100/01/0G/06	Confirmed	1	LF	0	LF							1	No	1/D
1	G	Building Engineer's Lounge Men's Restroom	N/A	Concrete Ceiling		Non Suspect ACM	100	SF	0	SF							N/A	N/A	N/A
1	G	Building Engineer's Lounge Men's Restroom	N/A	Cement Floor		Non Suspect ACM	100	SF	0	SF							N/A	N/A	N/A
1	G	Building Engineer's Lounge Men's Restroom	N/A	CMU		Non Suspect ACM	250	SF	0	SF							N/A	N/A	N/A
1	G	Workout Room in Building Engineer's Area	T	Pipe Fitting Insulation	6100/01/0G/12	Confirmed	13	EA	0	EA							1	No	1/D
1	G	Workout Room in Building Engineer's Area	T	Pipe Insulation 2-6 inch	6100/01/0G/06	Confirmed	50	LF	0	LF							1	No	1/D
1	G	Workout Room in Building Engineer's Area	N/A	Concrete Ceiling		Non Suspect ACM	1000	SF	0	SF							N/A	N/A	N/A
1	G	Workout Room in Building Engineer's Area	N/A	CMU		Non Suspect ACM	1500	SF	0	SF							N/A	N/A	N/A
1	G	Workout Room in Building Engineer's Area	N/A	Cement Floor		Non Suspect ACM	1000	SF	0	SF							N/A	N/A	N/A
1	G	Stairwell from Hallway outside of Building Engineer's Office to Boiler Room	N/A	Cement Floor		Non Suspect ACM	200	SF	0	SF		No access					N/A	N/A	N/A
1	G	Stairwell from Hallway outside of Building Engineer's Office to Boiler Room	N/A	Concrete Block Wall		Non Suspect ACM	600	SF	0	SF							N/A	N/A	N/A
1	G	Stairwell from Hallway outside of Building Engineer's Office to Boiler Room	N/A	Concrete Ceiling		Non Suspect ACM	200	SF	0	SF							N/A	N/A	N/A
1	G	Main Mechanical Room UpStairwell and DownStairwell	T	Pakage Boilers	6100/01/0G/SYN/BB/1620	Assumed	3	EA	2	EA		2 of the 3 Boilers are Inoperable					1	Yes	5/C
1	G	Main Mechanical Room UpStairwell and DownStairwell	T	Dust Insulation	6100/01/0G/VER/AR/1670	Assumed	4000	SF	0	SF	Grey	Attached to three Boilers down on the ground floor					1	No	1/D
1	G	Main Mechanical Room UpStairwell and DownStairwell	N/A	CMU		Non Suspect ACM	2500	SF	0	SF							N/A	N/A	N/A
1	G	Main Mechanical Room UpStairwell and DownStairwell	N/A	Concrete Ceiling		Non Suspect ACM	2500	SF	0	SF							N/A	N/A	N/A
1	G	Main Mechanical Room UpStairwell and DownStairwell	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	300	LF	0	LF							N/A	N/A	N/A
1	G	Main Mechanical Room UpStairwell and DownStairwell	T	Exterior Boiler Insulation	6100/01/0G/VER/AR/1620	Assumed	680	SF	0	SF		On Boiler #1 and Boiler #2					1	No	1/D
1	G	Main Mechanical Room UpStairwell and DownStairwell	M	Vibration Damper Cloth	6100/01/0G/13	Assumed	4	EA	0	EA							1	No	1/D
1	G	Main Mechanical Room UpStairwell and DownStairwell	N/A	Cement Floor		Non Suspect ACM	2500	SF	0	SF							N/A	N/A	N/A
1	G	Mechanical Room underneath Room 017 (Work out room in Building Engineer's Area)	N/A	Cement Floor		Non Suspect ACM	2500	SF	0	SF							N/A	N/A	N/A
1	G	Mechanical Room underneath Room 017 (Work out room in Building Engineer's Area)	N/A	Concrete Ceiling		Non Suspect ACM	5000	SF	0	SF							N/A	N/A	N/A
1	G	Mechanical Room underneath Room 017 (Work out room in Building Engineer's Area)	N/A	CMU		Non Suspect ACM	2500	SF	0	SF							N/A	N/A	N/A
1	G	Mechanical Room underneath Room 017 (Work out room in Building Engineer's Area)	T	Pipe Fitting Insulation	6100/01/0G/12	Assumed	32	EA	0	EA		Could be fiberglass - out of reach dark setting					1	No	1/D
1	G	Mechanical Room underneath Room 017 (Work out room in Building Engineer's Area)	T	Pipe Insulation 2-6 inch	6100/01/0G/06	Assumed	300	LF	0	LF		Could be fiberglass - out of reach dark setting					1	No	1/D
1	1	Music Room 101	M	Ceiling Tile 1' x 1'	6100/01/01/VER/AR/1710	Assumed	900	SF	0	SF							1	No	1/D
1	1	Music Room 101	N/A	Plaster Ceiling		NAD	100	SF	100	SF		At the hallway from the band room to the stage					N/A	N/A	N/A
1	1	Music Room 101	N/A	CMU		Non Suspect ACM	1200	SF	0	SF							N/A	N/A	N/A
1	1	Music Room 101	M	Floor Tile VAT 9" x 9"	6100/01/01/20	Confirmed	900	SF	0	SF	Tan						1	No	1/D
1	1	Music Room 101	M	Blackboard Glue Dots	6100/01/01/VER/AR/2600	Assumed	10	SF	0	SF							1	No	1/D
1	1	Stairwell outside of Music Room 101	N/A	Plaster Ceiling		NAD	200	SF	0	SF							N/A	N/A	N/A
1	1	Stairwell outside of Music Room 101	N/A	Ceramic Tile Walls		Non Suspect ACM	550	SF	0	SF							N/A	N/A	N/A
1	1	Stairwell outside of Music Room 101	N/A	Cement Floor		Non Suspect ACM	200	SF	0	SF							N/A	N/A	N/A
1	1	Stairwell outside of Music Room 101	T	Radiator Insulation	6100/01/01/SYN/BB/1600	Assumed	25	SF	0	SF		1 Recessed Radiator					1	No	1/D
1	1	Music Practice Room #1	M	Ceiling Tile 1' x 1'	6100/01/01/VER/AR/1710	Assumed	100	SF	0	SF		Metal Panels					1	No	1/D
1	1	Music Practice Room #1	N/A	CMU		Non Suspect ACM	250	SF	0	SF							N/A	N/A	N/A
1	1	Music Practice Room #1	M	Floor Tile VAT 9" x 9"	6100/01/01/20	Confirmed	100	SF	0	SF	Tan						1	No	1/D
1	1	Music Practice Room #2	M	Ceiling Tile 1' x 1'	6100/01/01/VER/AR/1710	Assumed	100	SF	0	SF							1	No	1/D
1	1	Music Practice Room #2	N/A	CMU		Non Suspect ACM	250	SF	0	SF							N/A	N/A	N/A
1	1	Music Practice Room #2	M	Floor Tile VAT 9" x 9"	6100/01/01/20	Confirmed	100	SF	0	SF	Tan						1	No	1/D
1	1	Music Practice Room #3	M	Ceiling Tile 1' x 1'	6100/01/01/VER/AR/1710	Assumed	100	SF	0	SF							1	No	1/D
1	1	Music Practice Room #3	N/A	CMU		Non Suspect ACM	200	SF	0	SF							N/A	N/A	N/A
1	1	Music Practice Room #3	M	Floor Tile VAT 9" x 9"	6100/01/01/20	Confirmed	100	SF	0	SF	Tan						1	No	1/D
1	1	Music Practice Room #4	M	Ceiling Tile 1' x 1'	6100/01/01/VER/AR/1710	Assumed	100	SF	0	SF							1	No	1/D
1	1	Music Practice Room #4	N/A	CMU		Non Suspect ACM	200	SF	0	SF							N/A	N/A	N/A

6100/6460 Hill Freedman World Academy @ Leeds Campus 2015 2016 AHERA Three-Year Report.xls

School District of Philadelphia Hill Freedman World Academy @ Leeds Campus 1100 E. Mount Pleasant Avenue, Philadelphia, PA, 19150 ULCS# 6100 Year Built: 1953				AHERA Three-Year Reinspection 2015-2016 Room by Room Location Log Report										Reinspection Date: October 30, 2015 Building Inspector: A. Roman Number: 150619008 Management Planner: Megan Vala Number: 740728							
E l e m e n t	F l o o r	On Site Room Name	System Affected	Material Description	HID#	Confirmed/Assumed/NAD/ Non Suspect ACM	Amount of Material	SF LF EA	Amount of Damage	SF LF EA	Color required for VAT	Comments/Description/Notes	Attic/ Crawl Space Ranking	Damage Potential (DP)	Newly Friable (NF)	Response Action (RA)					
1	1	Music Practice Room #4	M	Floor Tile VAT 9" x 9"	6100/01/01/20	Confirmed	100	SF	0	SF	Tan			1	No	1/D					
1	1	HVAC Blower Room next to Music Practice Room #4	N/A	Plaster Ceiling		NAD	100	SF	0	SF				N/A	N/A	N/A					
1	1	HVAC Blower Room next to Music Practice Room #4	N/A	CMU		Non Suspect ACM	200	SF	0	SF				N/A	N/A	N/A					
1	1	HVAC Blower Room next to Music Practice Room #4	M	Floor Tile VAT 9" x 9"	6100/01/01/20	Confirmed	100	SF	0	SF	Tan			1	No	1/D					
1	1	HVAC Blower Room next to Music Practice Room #4	M	Vibration Damper Cloth	6100/01/01/21	Assumed	2	EA	0	EA				1	No	1/D					
1	1	Hallway that connects to Music Practice Rooms	N/A	CMU		NAD	200	SF	0	SF				N/A	N/A	N/A					
1	1	Hallway that connects to Music Practice Rooms	N/A	CMU		Non Suspect ACM	500	SF	0	SF				N/A	N/A	N/A					
1	1	Hallway that connects to Music Practice Rooms	M	Floor Tile VAT 9" x 9"	6100/01/01/20	Confirmed	200	SF	0	SF	Tan			1	No	1/D					
1	1	Classroom 102	M	Ceiling Tile 1' x 1'	6100/01/01/VER/AR/1710	Assumed	500	SF	0	SF				1	No	1/D					
1	1	Classroom 102	N/A	CMU		Non Suspect ACM	900	SF	0	SF				N/A	N/A	N/A					
1	1	Classroom 102	M	Floor Tile VAT 9" x 9"	6100/01/01/20	Confirmed	500	SF	0	SF	Green			1	No	1/D					
1	1	Classroom connected to Classroom 102 at the Northeastern Corner	M	Ceiling Tile 1' x 1'	6100/01/01/VER/AR/1710	Assumed	500	SF	500	SF		Metal 1'X1' CT - Severely water damaged		1	No	5/B					
1	1	Classroom connected to Classroom 102 at the Northeastern Corner	N/A	CMU		Non Suspect ACM	900	SF	0	SF				N/A	N/A	N/A					
1	1	Classroom connected to Classroom 102 at the Northeastern Corner	M	Floor Tile VAT 9" x 9"	6100/01/01/20	Confirmed	500	SF	0	SF	Tan			1	No	1/D					
1	1	Hallway leading from Classroom 102 to the Music Room	N/A	Plaster Ceiling		NAD	800	SF	0	SF				N/A	N/A	N/A					
1	1	Hallway leading from Classroom 102 to the Music Room	N/A	CMU		Non Suspect ACM	1200	SF	0	SF				N/A	N/A	N/A					
1	1	Hallway leading from Classroom 102 to the Music Room	M	Floor Tile VAT 9" x 9"	6100/01/01/20	Confirmed	800	SF	0	SF	Tan			1	No	1/D					
1	1	Classroom 103	M	Ceiling Tile 1' x 1'	6100/01/01/VER/AR/1710	Assumed	800	SF	0	SF				1	No	1/D					
1	1	Classroom 103	N/A	CMU		Non Suspect ACM	1200	SF	0	SF				N/A	N/A	N/A					
1	1	Classroom 103	M	Floor Tile VAT 9" x 9"	6100/01/01/20	Confirmed	700	SF	0	SF	Green			1	No	1/D					
1	1	Classroom 103	M	Floor Tile VAT 9" x 9"	6100/01/01/20	Confirmed	100	SF	0	SF	Tan			1	No	1/D					
1	1	Classroom 103	M	Blackboard Glue Dots	6100/01/01/VER/AR/2600	Assumed	10	SF	0	SF				1	No	1/D					
1	1	Classroom 103 Closet	N/A	Cement Floor		Non Suspect ACM	250	SF	0	SF		9"x9"s removed - black mastic residue remains on concrete floor		N/A	N/A	N/A					
1	1	Classroom 103 Closet	N/A	Concrete Block Wall		Non Suspect ACM	750	SF	0	SF				N/A	N/A	N/A					
1	1	Classroom 103 Closet	N/A	Concrete Ceiling		Non Suspect ACM	250	SF	0	SF				N/A	N/A	N/A					
1	1	Stage Storage Closet to the North across the Hall from Classroom 103	N/A	Plaster Ceiling		NAD	160	SF	0	SF				N/A	N/A	N/A					
1	1	Stage Storage Closet to the North across the Hall from Classroom 103	N/A	CMU		Non Suspect ACM	400	SF	120	SF		Severely cracked and water damaged CMU Block Wall		N/A	N/A	N/A					
1	1	Stage Storage Closet to the North across the Hall from Classroom 103	M	Floor Tile VAT 9" x 9"	6100/01/01/20	Confirmed	160	SF	0	SF	Black			1	No	1/D					
1	1	Stage Storage Closet to the North across the Hall from Classroom 103	M	Vibration Damper Cloth	6100/01/01/21	Assumed	1	EA	0	EA				1	No	1/D					
1	1	Storage Closet at the Side of Stage across from Classroom 103	N/A	Plaster Ceiling		NAD	200	SF	0	SF				N/A	N/A	N/A					
1	1	Storage Closet at the Side of Stage across from Classroom 103	N/A	CMU		Non Suspect ACM	400	SF	0	SF				N/A	N/A	N/A					
1	1	Storage Closet at the Side of Stage across from Classroom 103	M	Floor Tile VAT 9" x 9"	6100/01/01/20	Confirmed	200	SF	0	SF	Black			1	No	1/D					
1	1	Storage Closet at the Side of Stage across from Classroom 103	T	Pipe Fitting Insulation	6100/01/01/22	Confirmed	2	EA	0	EA				1	No	1/D					
1	1	Storage Closet at the Side of Stage across from Classroom 103	T	Pipe Insulation 2-6 inch	6100/01/01/15	Confirmed	20	LF	0	LF				1	No	1/D					
1	1	Storage Closet at the Side of Stage across from Classroom 103	N/A	Plaster Ceiling		NAD	200	SF	0	SF				N/A	N/A	N/A					
1	1	Storage Closet at the Side of Stage across from Classroom 103	N/A	CMU		Non Suspect ACM	400	SF	0	SF				N/A	N/A	N/A					
1	1	Storage Closet at the Side of Stage across from Classroom 103	N/A	Cement Floor		Non Suspect ACM	200	SF	0	SF				N/A	N/A	N/A					
1	1	Storage Closet at the Side of Stage across from Classroom 103	M	Vibration Damper Cloth	6100/01/01/21	Assumed	1	EA	0	EA				1	No	1/D					
1	1	Classroom 104	T	Pipe Fitting Insulation	6100/01/01/22	Confirmed	2	EA	0	EA				1	No	1/D					
1	1	Classroom 104	T	Pipe Insulation 2-6 inch	6100/01/01/15	Confirmed	10	LF	0	LF				1	No	1/D					
1	1	Classroom 104	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	10	LF	10	LF				N/A	N/A	N/A					
1	1	Classroom 104	M	Ceiling Tile 1' x 1'	6100/01/01/VER/AR/1710	Assumed	880	SF	0	SF				1	No	1/D					
1	1	Classroom 104	N/A	CMU		Non Suspect ACM	1200	SF	0	SF				N/A	N/A	N/A					
1	1	Classroom 104	M	Floor Tile VAT 12" x 12"	6100/01/01/EE	Assumed	800	SF	0	SF	Tan			1	No	1/D					
1	1	Classroom 104	M	Blackboard Glue Dots	6100/01/01/VER/AR/2600	Assumed	10	SF	0	SF				1	No	1/D					
1	1	Classroom 104 Closet	X	X		X	X	X	X	X		No access		X	X	X					
1	1	Hallway in front of Classrooms 103-104	T	Pipe Fitting Insulation	6100/01/01/22	Confirmed	8	EA	0	EA				1	No	1/D					
1	1	Hallway in front of Classrooms 103-104	T	Pipe Insulation 2-6 inch	6100/01/01/15	Confirmed	20	LF	0	LF				1	No	1/D					
1	1	Hallway in front of Classrooms 103-104	N/A	Plaster Ceiling		NAD	1000	SF	0	SF				N/A	N/A	N/A					
1	1	Hallway in front of Classrooms 103-104	N/A	CMU		Non Suspect ACM	3000	SF	0	SF				N/A	N/A	N/A					
1	1	Hallway in front of Classrooms 103-104	M	Floor Tile VAT 9" x 9"	6100/01/01/20	Confirmed	1000	SF	0	SF	Green			1	No	1/D					
1	1	Hallway in front of Classrooms 103-104	T	Radiator Insulation	6100/01/01/SYN/BB/1600	Assumed	25	SF	0	SF		1 Recessed Radiator		1	No	1/D					
1	1	Custodial Closet in Hallway next to Counselor's Office and Boy's Restroom	T	Pipe Fitting Insulation	6100/01/01/22	Confirmed	7	EA	0	EA		Outer Lagging is beginning to delaminate		1	No	1/D					
1	1	Custodial Closet in Hallway next to Counselor's Office and Boy's Restroom	T	Pipe Insulation 2-6 inch	6100/01/01/15	Confirmed	60	LF	0	LF		Outer Lagging is beginning to delaminate		1	No	1/D					
1	1	Custodial Closet in Hallway next to Counselor's Office and Boy's Restroom	N/A	Concrete Ceiling		Non Suspect ACM	48	SF	0	SF				N/A	N/A	N/A					
1	1	Custodial Closet in Hallway next to Counselor's Office and Boy's Restroom	N/A	CMU		Non Suspect ACM	150	SF	0	SF				N/A	N/A	N/A					
1	1	Custodial Closet in Hallway next to Counselor's Office and Boy's Restroom	N/A	Cement Floor		Non Suspect ACM	48	SF	0	SF				N/A	N/A	N/A					
1	1	Boy's Restroom next to Counselor's Office	T	Pipe Fitting Insulation	6100/01/01/22	Confirmed	2	EA	0	EA				1	No	1/D					
1	1	Boy's Restroom next to Counselor's Office	T	Pipe Insulation 2-6 inch	6100/01/01/15	Confirmed	5	LF	0	LF				1	No	1/D					
1	1	Boy's Restroom next to Counselor's Office	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	5	LF	5	LF				N/A	N/A	N/A					
1	1	Boy's Restroom next to Counselor's Office	N/A	Plaster Ceiling		NAD	300	SF	0	SF				N/A	N/A	N/A					
1	1	Boy's Restroom next to Counselor's Office	N/A	Ceramic Tile Walls		Non Suspect ACM	700	SF	0	SF				N/A	N/A	N/A					
1	1	Boy's Restroom next to Counselor's Office	N/A	Cement Floor		Non Suspect ACM	300	SF	0	SF				N/A	N/A	N/A					
1	1	Counselor's Office	T	Pipe Fitting Insulation	6100/01/01/22	Confirmed	2	EA	0	EA				1	No	1/D					
1	1	Counselor's Office	T	Pipe Insulation 2-6 inch	6100/01/01/15	Confirmed	36	LF	0	LF				1	No	1/D					
1	1	Counselor's Office	N/A	Plaster Ceiling		NAD	250	SF	5	SF				N/A	N/A	N/A					
1	1	Counselor's Office	N/A	CMU		Non Suspect ACM	400	SF	0	SF				N/A	N/A	N/A					
1	1	Counselor's Office	M	Floor Tile VAT 9" x 9"	6100/01/01/20	Confirmed	250	SF	0	SF	Black			1	No	1/D					
1	1	Counselor's Office #1	T	Pipe Fitting Insulation	6100/01/01/22	Confirmed	4	EA	0	EA				1	No	1/D					
1	1	Counselor's Office #1	T	Pipe Insulation 2-6 inch	6100/01/01/15	Confirmed	35	LF	0	LF				1	No	1/D					

6100/6460 Hill Freedman World Academy @ Leeds Campus 2015 2016 AHERA Three-Year Report.xls

School District of Philadelphia Hill Freedman World Academy @ Leeds Campus 1100 E. Mount Pleasant Avenue, Philadelphia, PA, 19150 ULCS# 6100 Year Built: 1953		AHERA Three-Year Reinspection 2015-2016 Room by Room Location Log Report										Reinspection Date: October 30, 2015 Building Inspector: A. Roman Number: 150619008 Management Planner: Megan Vala Number: 740728				Attic/ Crawl Space Ranking	Damage Potential (DP)	Newly Friable (NF)	Response Action (RA)
Element	Room	On Site Room Name	System Affected	Material Description	HID#	Confirmed/Assumed/NAD/ Non Suspect ACM	Amount of Material	SF LF EA	Amount of Damage	SF LF EA	Color required for VAT	Comments/Description/Notes							
1	1	Counselor's Office #1	N/A	Plaster Ceiling		NAD	200	SF	0	SF							N/A	N/A	N/A
1	1	Counselor's Office #1	N/A	CMU		Non Suspect ACM	500	SF	0	SF							N/A	N/A	N/A
1	1	Counselor's Office #1	M	Floor Tile VAT 12" x 12"	6100/01/01/EE	Assumed	200	SF	0	SF	Blue						1	No	1/D
1	1	Counselor's Office #2	T	Pipe Fitting Insulation	6100/01/01/22	Confirmed	4	EA	0	EA							1	No	1/D
1	1	Counselor's Office #2	T	Pipe Insulation 2-6 inch	6100/01/01/15	Confirmed	35	LF	0	LF							1	No	1/D
1	1	Counselor's Office #2	N/A	Plaster Ceiling		NAD	200	SF	0	SF							N/A	N/A	N/A
1	1	Counselor's Office #2	N/A	CMU		Non Suspect ACM	500	SF	0	SF							N/A	N/A	N/A
1	1	Counselor's Office #2	M	Floor Tile VAT 9" x 9"	6100/01/01/20	Confirmed	200	SF	0	SF	Tan						1	No	1/D
1	1	Counselor's Office #3	T	Pipe Fitting Insulation	6100/01/01/22	Confirmed	7	EA	0	EA							1	No	1/D
1	1	Counselor's Office #3	T	Pipe Insulation 2-6 inch	6100/01/01/15	Confirmed	35	LF	0	LF							1	No	1/D
1	1	Counselor's Office #3	N/A	Plaster Ceiling		NAD	200	SF	0	SF							N/A	N/A	N/A
1	1	Counselor's Office #3	N/A	CMU		Non Suspect ACM	500	SF	0	SF							N/A	N/A	N/A
1	1	Counselor's Office #3	M	Floor Tile VAT 9" x 9"	6100/01/01/20	Confirmed	200	SF	0	SF	Tan						1	No	1/D
1	1	Roster Office	T	Pipe Fitting Insulation	6100/01/01/22	Confirmed	2	EA	0	EA							1	No	1/D
1	1	Roster Office	T	Pipe Insulation 2-6 inch	6100/01/01/15	Confirmed	10	LF	0	LF							1	No	1/D
1	1	Roster Office	N/A	CMU		Non Suspect ACM	300	SF	0	SF							N/A	N/A	N/A
1	1	Roster Office	M	Floor Tile VAT 9" x 9"	6100/01/01/20	Confirmed	200	SF	0	SF	Tan						1	No	1/D
1	1	Roster Office	N/A	Plaster Ceiling		NAD	200	SF	0	SF							N/A	N/A	N/A
1	1	House Coordinator	T	Pipe Fitting Insulation	6100/01/01/22	Confirmed	9	EA	0	EA							1	No	1/D
1	1	House Coordinator	T	Pipe Insulation 2-6 inch	6100/01/01/15	Confirmed	36	LF	0	LF							1	No	1/D
1	1	House Coordinator	N/A	Plaster Ceiling		NAD	500	SF	0	SF							N/A	N/A	N/A
1	1	House Coordinator	N/A	CMU		Non Suspect ACM	900	SF	0	SF							N/A	N/A	N/A
1	1	House Coordinator	M	Floor Tile VAT 9" x 9"	6100/01/01/20	Confirmed	500	SF	0	SF	Green						1	No	1/D
1	1	Classroom 107	T	Pipe Fitting Insulation	6100/01/01/22	Confirmed	14	EA	0	EA							1	No	1/D
1	1	Classroom 107	T	Pipe Insulation 2-6 inch	6100/01/01/15	Confirmed	50	LF	0	LF							1	No	1/D
1	1	Classroom 107	N/A	Plaster Ceiling		NAD	500	SF	0	SF							N/A	N/A	N/A
1	1	Classroom 107	N/A	CMU		Non Suspect ACM	800	SF	0	SF							N/A	N/A	N/A
1	1	Classroom 107	M	Floor Tile VAT 9" x 9"	6100/01/01/20	Confirmed	500	SF	0	SF	Green						1	No	1/D
1	1	Nurse's Suite Room #2	N/A	Plaster Ceiling		NAD	500	SF	0	SF							N/A	N/A	N/A
1	1	Nurse's Suite Room #2	N/A	CMU		Non Suspect ACM	900	SF	0	SF							N/A	N/A	N/A
1	1	Nurse's Suite Room #2	T	Pipe Fitting Insulation	6100/01/01/22	Confirmed	6	EA	0	EA							1	No	1/D
1	1	Nurse's Suite Room #2	T	Pipe Insulation 2-6 inch	6100/01/01/15	Confirmed	42	LF	0	LF							1	No	1/D
1	1	Nurse's Suite Room #2	M	Floor Tile VAT 9" x 9"	6100/01/01/20	Confirmed	500	SF	0	SF	Tan						1	No	1/D
1	1	Nurse's Suite Room #2 Restroom	T	Pipe Fitting Insulation	6100/01/01/22	Confirmed	2	EA	0	EA							1	No	1/D
1	1	Nurse's Suite Room #2 Restroom	T	Pipe Insulation 2-6 inch	6100/01/01/15	Confirmed	8	LF	0	LF							1	No	1/D
1	1	Nurse's Suite Room #2 Restroom	M	Floor Tile VAT 9" x 9"	6100/01/01/20	Confirmed	48	SF	0	SF	Black						1	No	1/D
1	1	Nurse's Suite Room #2 Restroom	N/A	Plaster Ceiling		NAD	48	SF	0	SF							N/A	N/A	N/A
1	1	Nurse's Suite Room #2 Restroom	N/A	CMU		Non Suspect ACM	150	SF	0	SF							N/A	N/A	N/A
1	1	Nurse's Suite	T	Pipe Fitting Insulation	6100/01/01/22	Confirmed	2	EA	0	EA							1	No	1/D
1	1	Nurse's Suite	T	Pipe Insulation 2-6 inch	6100/01/01/15	Confirmed	36	LF	0	LF							1	No	1/D
1	1	Nurse's Suite	N/A	Plaster Ceiling		NAD	300	SF	0	SF							N/A	N/A	N/A
1	1	Nurse's Suite	N/A	CMU		Non Suspect ACM	800	SF	0	SF							N/A	N/A	N/A
1	1	Nurse's Suite	M	Floor Tile VAT 9" x 9"	6100/01/01/20	Confirmed	300	SF	0	SF	Tan						1	No	1/D
1	1	Hallway in the Nurse's Suite	N/A	Plaster Ceiling		NAD	200	SF	0	SF							N/A	N/A	N/A
1	1	Hallway in the Nurse's Suite	N/A	CMU		Non Suspect ACM	500	SF	0	SF							N/A	N/A	N/A
1	1	Hallway in the Nurse's Suite	M	Floor Tile VAT 9" x 9"	6100/01/01/20	Confirmed	200	SF	0	SF	Tan						1	No	1/D
1	1	Nurse's Suite 107 Restroom closest to the Entrance to the Nurse's Office	N/A	CMU		Non Suspect ACM	150	SF	0	SF							N/A	N/A	N/A
1	1	Nurse's Suite 107 Restroom closest to the Entrance to the Nurse's Office	N/A	Plaster Ceiling		NAD	48	SF	0	SF							N/A	N/A	N/A
1	1	Nurse's Suite 107 Restroom closest to the Entrance to the Nurse's Office	T	Pipe Fitting Insulation	6100/01/01/22	Confirmed	2	EA	0	EA							1	No	1/D
1	1	Nurse's Suite 107 Restroom closest to the Entrance to the Nurse's Office	M	Floor Tile VAT 9" x 9"	6100/01/01/20	Confirmed	48	SF	0	SF	Tan						1	No	1/D
1	1	Nurse's Suite Room #3	N/A	Plaster Ceiling		NAD	300	SF	0	SF							N/A	N/A	N/A
1	1	Nurse's Suite Room #3	N/A	CMU		Non Suspect ACM	800	SF	0	SF							N/A	N/A	N/A
1	1	Nurse's Suite Room #3	T	Pipe Fitting Insulation	6100/01/01/22	Confirmed	15	EA	0	EA							1	No	1/D
1	1	Nurse's Suite Room #3	T	Pipe Insulation 2-6 inch	6100/01/01/15	Confirmed	50	LF	0	LF							1	No	1/D
1	1	Nurse's Suite Room #3	M	Floor Tile VAT 9" x 9"	6100/01/01/20	Confirmed	300	SF	0	SF	Tan						1	No	1/D
1	1	Nurse's Suite Room #4	T	Pipe Fitting Insulation	6100/01/01/22	Confirmed	9	EA	0	EA							1	No	1/D
1	1	Nurse's Suite Room #4	T	Pipe Insulation 2-6 inch	6100/01/01/15	Confirmed	24	LF	0	LF							1	No	1/D
1	1	Nurse's Suite Room #4	M	Floor Tile VAT 9" x 9"	6100/01/01/20	Confirmed	200	SF	0	SF	Tan						1	No	1/D
1	1	Nurse's Suite Room #4	N/A	Plaster Ceiling		NAD	200	SF	0	SF							N/A	N/A	N/A
1	1	Nurse's Suite Room #4	N/A	CMU		Non Suspect ACM	500	SF	0	SF							N/A	N/A	N/A
1	1	Nurse's Suite Room #4 Closet	T	Pipe Fitting Insulation	6100/01/01/22	Confirmed	7	EA	0	EA							1	No	1/D
1	1	Nurse's Suite Room #4 Closet	T	Pipe Insulation 2-6 inch	6100/01/01/15	Confirmed	12	LF	0	LF							1	No	1/D
1	1	Nurse's Suite Room #4 Closet	M	Floor Tile VAT 9" x 9"	6100/01/01/20	Confirmed	36	SF	0	SF	Tan						1	No	1/D
1	1	Nurse's Suite Room #4 Closet	N/A	Plaster Ceiling		Non Suspect ACM	150	SF	0	SF							N/A	N/A	N/A
1	1	Nurse's Suite Room #4 Closet	N/A	CMU		NAD	36	SF	0	SF							N/A	N/A	N/A
1	1	Nurse's Suite Room #5	N/A	Plaster Ceiling		NAD	400	SF	0	SF							N/A	N/A	N/A
1	1	Nurse's Suite Room #5	N/A	CMU		Non Suspect ACM	900	SF	0	SF							N/A	N/A	N/A
1	1	Nurse's Suite Room #5	T	Pipe Fitting Insulation	6100/01/01/22	Confirmed	16	EA	0	EA							1	No	1/D
1	1	Nurse's Suite Room #5	T	Pipe Insulation 2-6 inch	6100/01/01/15	Confirmed	70	LF	0	LF							1	No	1/D
1	1	Nurse's Suite Room #5	M	Floor Tile VAT 9" x 9"	6100/01/01/20	Confirmed	400	SF	0	SF	Tan						1	No	1/D
1	1	Custodial Closet outside of Nurse's Suite	N/A	Cement Floor		Non Suspect ACM	20	SF	0	SF							N/A	N/A	N/A
1	1	Custodial Closet outside of Nurse's Suite	N/A	Concrete Block Wall		Non Suspect ACM	80	SF	0	SF							N/A	N/A	N/A
1	1	Custodial Closet outside of Nurse's Suite	N/A	Concrete Ceiling		Non Suspect ACM	20	SF	0	SF							N/A	N/A	N/A
1	1	Custodial Closet outside of Nurse's Suite	T	Pipe Insulation 2-6 inch	6100/01/01/15	Confirmed	3	LF	0	LF							1	No	1/D
1	1	Custodial Closet outside of Nurse's Suite	T	Pipe Fitting Insulation	6100/01/01/22	Confirmed	1	EA	0	EA							1	No	1/D
1	1	Nurse's Office	M	Floor Tile VAT 9" x 9"	6100/01/01/20	Confirmed	100	SF	0	SF	Tan						1	No	1/D
1	1	Nurse's Office	N/A	Concrete Block Wall		Non Suspect ACM	300	SF	0	SF							N/A	N/A	N/A
1	1	Nurse's Office	N/A	Concrete Ceiling		Non Suspect ACM	100	SF	0	SF							N/A	N/A	N/A

6100/6460 Hill Freedman World Academy @ Leeds Campus 2015 2016 AHERA Three-Year Report.xls

School District of Philadelphia Hill Freedman World Academy @ Leeds Campus 1100 E. Mount Pleasant Avenue, Philadelphia, PA, 19150 ULCS# 6100 Year Built: 1953		AHERA Three-Year Reinspection 2015-2016 Room by Room Location Log Report										Reinspection Date: October 30, 2015 Building Inspector: A. Roman Number: 150619008 Management Planner: Megan Vala Number: 740728				
E l e m e n t	F l o o r	On Site Room Name	System Affected	Material Description	HID#	Confirmed/Assumed/NAD/ Non Suspect ACM	Amount of Material	SF LF EA	Amount of Damage	SF LF EA	Color required for VAT	Comments/Description/Notes	Attic/ Crawl Space Ranking	Damage Potential (DP)	Newly Friable (NF)	Response Action (RA)
1	1	Nurse's Office	T	Pipe Insulation 2-6 inch	6100/01/01/15	Confirmed	26	LF	0	LF				1	No	1/D
1	1	Nurse's Office	T	Pipe Fitting Insulation	6100/01/01/22	Confirmed	10	EA	0	EA				1	No	1/D
1	1	Nurse's Office	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	50	LF	0	LF				N/A	N/A	N/A
1	1	Nurse's Office	M	Sink Undercoat Mastic	6100/01/01/SYN/BB/2602	Assumed	4	SF	0	SF		1 Sink - 4 SF		1	No	1/D
1	1	Nurse's Office Suite Staff Restroom	M	Floor Tile VAT 9" x 9"	6100/01/01/20	Confirmed	40	SF	0	SF	Tan			1	No	1/D
1	1	Nurse's Office Suite Staff Restroom	N/A	Sheetrock Wall		Non Suspect ACM	120	SF	0	SF				N/A	N/A	N/A
1	1	Nurse's Office Suite Staff Restroom	N/A	Concrete Ceiling		Non Suspect ACM	40	SF	0	SF				N/A	N/A	N/A
1	1	Nurse's Office Suite Staff Restroom	T	Pipe Insulation 2-6 inch	6100/01/01/15	Confirmed	15	LF	0	LF				1	No	1/D
1	1	Nurse's Office Suite Staff Restroom	T	Pipe Fitting Insulation	6100/01/01/22	Confirmed	3	EA	0	EA				1	No	1/D
1	1	Nurse's Office Suite Staff Restroom	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	13	LF	0	LF				N/A	N/A	N/A
1	1	Classroom 110	T	Pipe Fitting Insulation	6100/01/01/22	Confirmed	16	EA	0	EA				1	No	1/D
1	1	Classroom 110	T	Pipe Insulation 2-6 inch	6100/01/01/15	Confirmed	70	LF	0	LF				1	No	1/D
1	1	Classroom 110	N/A	Concrete Ceiling		Non Suspect ACM	1200	SF	0	SF				N/A	N/A	N/A
1	1	Classroom 110	N/A	Concrete Block Wall		Non Suspect ACM	3600	SF	0	SF				N/A	N/A	N/A
1	1	Classroom 110	M	Floor Tile VAT 9" x 9"	6100/01/01/20	Confirmed	1200	SF	0	SF	Tan			1	No	1/D
1	1	Classroom 110	M	Blackboard Glue Dots	6100/01/01/VER/AR/2600	Assumed	10	SF	0	SF				1	No	1/D
1	1	Classroom 110	M	Floor Tile VAT 12" x 12"	6100/01/01/EE	Assumed	16	SF	0	SF		Atop Unit-Vents		1	No	1/D
1	1	Classroom 110	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	250	LF	0	LF				N/A	N/A	N/A
1	1	Stairwell at Classrooms 111 and 110	T	Pipe Fitting Insulation	6100/01/01/22	Confirmed	9	EA	0	EA				1	No	1/D
1	1	Stairwell at Classrooms 111 and 110	T	Pipe Insulation 2-6 inch	6100/01/01/15	Confirmed	35	LF	0	LF				1	No	1/D
1	1	Stairwell at Classrooms 111 and 110	N/A	Plaster Ceiling		NAD	200	SF	0	SF				N/A	N/A	N/A
1	1	Stairwell at Classrooms 111 and 110	N/A	Ceramic Tile Walls		Non Suspect ACM	500	SF	0	SF				N/A	N/A	N/A
1	1	Stairwell at Classrooms 111 and 110	N/A	Cement Floor		Non Suspect ACM	200	SF	0	SF				N/A	N/A	N/A
1	1	Stairwell at Classrooms 111 and 110	T	Radiator Insulation	6100/01/01/SYN/BB/1600	Assumed	25	SF	0	SF		1 Recessed Radiator		1	No	1/D
1	1	Classroom 111	T	Pipe Fitting Insulation	6100/01/01/22	Confirmed	25	EA	0	EA				1	No	1/D
1	1	Classroom 111	T	Pipe Insulation 2-6 inch	6100/01/01/15	Confirmed	60	LF	0	LF				1	No	1/D
1	1	Classroom 111	N/A	Plaster Ceiling		NAD	800	SF	0	SF				N/A	N/A	N/A
1	1	Classroom 111	N/A	CMU		Non Suspect ACM	1200	SF	0	SF				N/A	N/A	N/A
1	1	Classroom 111	M	Floor Tile VAT 9" x 9"	6100/01/01/20	Confirmed	800	SF	0	SF	Tan			1	No	1/D
1	1	Classroom 109	M	Blackboard Glue Dots	6100/01/01/VER/AR/2600	Assumed	10	SF	0	SF				1	No	1/D
1	1	Classroom 109	T	Pipe Fitting Insulation	6100/01/01/22	Confirmed	36	EA	0	EA				1	No	1/D
1	1	Classroom 109	T	Pipe Insulation 2-6 inch	6100/01/01/15	Confirmed	80	LF	0	LF				1	No	1/D
1	1	Classroom 109	N/A	Plaster Ceiling		NAD	800	SF	0	SF				N/A	N/A	N/A
1	1	Classroom 109	N/A	CMU		Non Suspect ACM	1200	SF	0	SF				N/A	N/A	N/A
1	1	Classroom 109	M	Floor Tile VAT 9" x 9"	6100/01/01/20	Confirmed	800	SF	0	SF	Tan			1	No	1/D
1	1	Classroom 109	M	Blackboard Glue Dots	6100/01/01/VER/AR/2600	Assumed	10	SF	0	SF				1	No	1/D
1	1	Classroom 108	T	Pipe Fitting Insulation	6100/01/01/22	Confirmed	22	EA	0	EA				1	No	1/D
1	1	Classroom 108	T	Pipe Insulation 2-6 inch	6100/01/01/15	Confirmed	80	LF	0	LF				1	No	1/D
1	1	Classroom 108	N/A	Plaster Ceiling		NAD	800	SF	0	SF				N/A	N/A	N/A
1	1	Classroom 108	N/A	CMU		Non Suspect ACM	1200	SF	0	SF				N/A	N/A	N/A
1	1	Classroom 108	M	Floor Tile VAT 9" x 9"	6100/01/01/20	Confirmed	800	SF	0	SF	Tan			1	No	1/D
1	1	Classroom 108	M	Blackboard Glue Dots	6100/01/01/VER/AR/2600	Assumed	10	SF	0	SF				1	No	1/D
1	1	Classroom 105	T	Pipe Insulation 2-6 inch	6100/01/01/15	Confirmed	20	LF	0	LF				1	No	1/D
1	1	Classroom 105	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	30	LF	0	LF				N/A	N/A	N/A
1	1	Classroom 105	N/A	Plaster Ceiling		NAD	900	SF	10	SF				N/A	N/A	N/A
1	1	Classroom 105	M	Floor Tile VAT 9" x 9"	6100/01/01/20	Confirmed	1200	SF	0	SF				N/A	N/A	N/A
1	1	Classroom 105	M	CMU		Non Suspect ACM	900	SF	0	SF	Green			1	No	1/D
1	1	Classroom 105	M	Blackboard Glue Dots	6100/01/01/VER/AR/2600	Assumed	10	SF	0	SF				1	No	1/D
1	1	Hallway from Classrooms 105 to 111	T	Pipe Fitting Insulation	6100/01/01/22	Confirmed	7	EA	0	EA				1	No	1/D
1	1	Hallway from Classrooms 105 to 111	T	Pipe Insulation 2-6 inch	6100/01/01/15	Confirmed	35	LF	0	LF				1	No	1/D
1	1	Hallway from Classrooms 105 to 111	N/A	Plaster Ceiling		NAD	2000	SF	0	SF				N/A	N/A	N/A
1	1	Hallway from Classrooms 105 to 111	N/A	CMU		Non Suspect ACM	5000	SF	0	SF				N/A	N/A	N/A
1	1	Hallway from Classrooms 105 to 111	T	Floor Tile VAT 9" x 9"	6100/01/01/20	Confirmed	2000	SF	0	SF	Green			1	No	1/D
1	1	Stairwell between Classrooms 104 and 105	N/A	Plaster Ceiling		NAD	200	SF	0	SF				N/A	N/A	N/A
1	1	Stairwell between Classrooms 104 and 105	N/A	Ceramic Tile Walls		Non Suspect ACM	500	SF	0	SF				N/A	N/A	N/A
1	1	Stairwell between Classrooms 104 and 105	N/A	Cement Floor		Non Suspect ACM	200	SF	0	SF				N/A	N/A	N/A
1	1	Stairwell between Classrooms 104 and 105	T	Radiator Insulation	6100/01/01/SYN/BB/1600	Assumed	25	SF	0	SF		1 Recessed Radiator		1	No	1/D
1	1	Main Entrance Foyer next to Auditorium	N/A	Ceramic Tile Floors		Non Suspect ACM	200	SF	0	SF				N/A	N/A	N/A
1	1	Main Entrance Foyer next to Auditorium	N/A	Ceramic Tile Walls		Non Suspect ACM	400	SF	0	SF				N/A	N/A	N/A
1	1	Main Entrance Foyer next to Auditorium	N/A	Concrete Ceiling		Non Suspect ACM	200	SF	0	SF				N/A	N/A	N/A
1	1	Main Entrance Foyer next to Auditorium	T	Radiator Insulation	6100/01/01/SYN/BB/1600	Assumed	25	SF	0	SF		1 Recessed Radiator		1	No	1/D
1	1	Hallway at Main Entrance at the Auditorium	N/A	Plaster Ceiling		NAD	1200	SF	0	SF				N/A	N/A	N/A
1	1	Hallway at Main Entrance at the Auditorium	N/A	CMU		Non Suspect ACM	2000	SF	0	SF				N/A	N/A	N/A
1	1	Hallway at Main Entrance at the Auditorium	M	Floor Tile VAT 9" x 9"	6100/01/01/20	Confirmed	1200	SF	0	SF	Green			1	No	1/D
1	1	Hallway at Main Entrance at the Auditorium	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	10	LF	10	LF				N/A	N/A	N/A
1	1	Hallway at Main Entrance at the Auditorium	T	Radiator Insulation	6100/01/01/SYN/BB/1600	Assumed	25	SF	0	SF		1 Recessed Radiator		1	No	1/D
1	1	Auditorium	S	Acoustical Plaster Ceiling	6100/01/01/HH	Confirmed	10000	SF	0	SF		Is the whole ceiling acoustical textured plaster?		N/A	N/A	N/A
1	1	Auditorium	N/A	Plaster Walls		NAD	20000	SF	0	SF				N/A	N/A	N/A
1	1	Auditorium	M	Floor Tile VAT 9" x 9"	6100/01/01/20	Confirmed	10000	SF	50	SF	Tan	9"x9" VAT in Aisles, Loose/Lifting/Cracked Tile in Rear Corner below previous leak - DDC Required		1	Yes	S/A
1	1	Auditorium	N/A	Cement Floor		Non Suspect ACM	100	SF	0	SF		Below Seating		N/A	N/A	N/A
1	1	Auditorium	N/A	Radiator Insulation	6100/01/01/SYN/BB/1600	Assumed	100	SF	0	SF		5 Recessed Radiator - 20 SF		1	No	1/D
1	1	Stage	N/A	Wood Floor		Non Suspect ACM	1000	SF	0	SF				N/A	N/A	N/A
1	1	Stage	S	Acoustical Plaster Ceiling	6100/01/01/HH	Confirmed	1000	SF	100	SF		Is the whole ceiling acoustical textured plaster?		N/A	N/A	N/A
1	1	Stage	N/A	Plaster Walls		NAD	2000	SF	0	SF				N/A	N/A	N/A
1	1	Stage	T	Pipe Insulation 2-6 inch	6100/01/01/15	Confirmed	40	LF	0	LF				1	No	1/D
1	1	Stage	T	Pipe Fitting Insulation	6100/01/01/22	Confirmed	5	EA	0	EA				1	No	1/D
1	1	Music Instrument Storage Room next to Stage	N/A	Cement Floor		Non Suspect ACM	80	SF	0	SF				N/A	N/A	N/A
1	1	Music Instrument Storage Room next to Stage	N/A	Concrete Block Wall		Non Suspect ACM	80	SF	0	SF				N/A	N/A	N/A
1	1	Music Instrument Storage Room next to Stage	N/A	Concrete Ceiling		Non Suspect ACM	80	SF	0	SF				N/A	N/A	N/A

6100/6460 Hill Freedman World Academy @ Leeds Campus 2015 2016 AHERA Three-Year Report.xls

School District of Philadelphia Hill Freedman World Academy @ Leeds Campus 1100 E. Mount Pleasant Avenue, Philadelphia, PA, 19150 ULCS# 6100 Year Built: 1953			AHERA Three-Year Reinspection 2015-2016 Room by Room Location Log Report										Reinspection Date: October 30, 2015 Building Inspector: A. Roman Number: 150619008 Management Planner: Megan Vala Number: 740728						
Element	Room	On Site Room Name	System Affected	Material Description	HID#	Confirmed/Assumed/NAD/ Non Suspect ACM	Amount of Material	SF LF EA	Amount of Damage	SF LF EA	Color required for VAT	Comments/Description/Notes	Attic/ Crawl Space Ranking	Damage Potential (DP)	Newly Friable (NF)	Response Action (RA)			
1	1	Music Instrument Storage Room next to Stage	T	Pipe Insulation 2-6 inch	6100/01/01/15	Confirmed	11	LF	0	LF					1	No	1/D		
1	1	Music Instrument Storage Room next to Stage	T	Pipe Fitting Insulation	6100/01/01/22	Confirmed	3	EA	0	EA					1	No	1/D		
1	1	Custodial Closet next to Girl's Restroom across from Main Office	T	Pipe Fitting Insulation	6100/01/01/22	Confirmed	9	EA	0	EA					1	No	1/D		
1	1	Custodial Closet next to Girl's Restroom across from Main Office	T	Pipe Insulation 2-6 inch	6100/01/01/15	Confirmed	80	LF	0	LF					1	No	1/D		
1	1	Custodial Closet next to Girl's Restroom across from Main Office	N/A	Concrete Ceiling		Non Suspect ACM	80	SF	0	SF					N/A	N/A	N/A		
1	1	Custodial Closet next to Girl's Restroom across from Main Office	N/A	Cement Floor		Non Suspect ACM	80	SF	0	SF					N/A	N/A	N/A		
1	1	Custodial Closet next to Girl's Restroom across from Main Office	N/A	CMU		Non Suspect ACM	300	SF	0	SF					N/A	N/A	N/A		
1	1	Girl's Restroom across from Main Office	M	Transite Stalls	6100/01/01/19	Confirmed	6	EA	0	EA		Small holes only; no debris observed			1	No	1/D		
1	1	Girl's Restroom across from Main Office	T	Pipe Fitting Insulation	6100/01/01/22	Confirmed	4	EA	0	EA					1	No	1/D		
1	1	Girl's Restroom across from Main Office	T	Pipe Insulation 2-6 inch	6100/01/01/15	Confirmed	36	LF	0	LF					1	No	1/D		
1	1	Girl's Restroom across from Main Office	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	10	LF	10	LF					N/A	N/A	N/A		
1	1	Girl's Restroom across from Main Office	N/A	Plaster Ceiling		NAD	240	SF	0	SF					N/A	N/A	N/A		
1	1	Girl's Restroom across from Main Office	N/A	Ceramic Tile Walls		Non Suspect ACM	500	SF	0	SF					N/A	N/A	N/A		
1	1	Girl's Restroom across from Main Office	N/A	Cement Floor		Non Suspect ACM	240	SF	0	SF					N/A	N/A	N/A		
1	1	Stairwell between Boy's and Girl's Restrooms across from Auditorium Main Entrance	N/A	Plaster Ceiling		NAD	200	SF	0	SF					N/A	N/A	N/A		
1	1	Stairwell between Boy's and Girl's Restrooms across from Auditorium Main Entrance	N/A	Ceramic Tile Walls		Non Suspect ACM	500	SF	0	SF					N/A	N/A	N/A		
1	1	Stairwell between Boy's and Girl's Restrooms across from Auditorium Main Entrance	N/A	Cement Floor		Non Suspect ACM	200	SF	0	SF					N/A	N/A	N/A		
1	1	Stairwell between Boy's and Girl's Restrooms across from Auditorium Main Entrance	T	Radiator Insulation	6100/01/01/SYN/BB/1600	Assumed	25	SF	0	SF		1 Recessed Radiator			1	No	1/D		
1	1	IMC - Storage Area	T	Pipe Fitting Insulation	6100/01/01/22	Confirmed	17	EA	0	EA					1	No	1/D		
1	1	IMC - Storage Area	T	Pipe Insulation 2-6 inch	6100/01/01/15	Confirmed	80	LF	0	LF					1	No	1/D		
1	1	IMC - Storage Area	N/A	Plaster Ceiling		NAD	500	SF	0	SF					N/A	N/A	N/A		
1	1	IMC - Storage Area	N/A	CMU		Non Suspect ACM	800	SF	0	SF					N/A	N/A	N/A		
1	1	IMC - Storage Area	M	Floor Tile VAT 9" x 9"	6100/01/01/20	Confirmed	500	SF	0	SF		Tan			1	No	1/D		
1	1	Main Office	T	Pipe Insulation 2-6 inch	6100/01/01/15	Confirmed	20	LF	0	LF					1	No	1/D		
1	1	Main Office	N/A	Ceiling Tile 2' x 4'		Non Suspect ACM	800	SF	0	SF					N/A	N/A	N/A		
1	1	Main Office	N/A	CMU		Non Suspect ACM	1200	SF	0	SF					N/A	N/A	N/A		
1	1	Main Office	M	Floor Tile VAT 9" x 9"	6100/01/01/20	Confirmed	800	SF	0	SF		Black			1	No	1/D		
1	1	Main Office Storage Area/Former Office to the Northwest	T	Pipe Fitting Insulation	6100/01/01/22	Confirmed	8	EA	0	EA					1	No	1/D		
1	1	Main Office Storage Area/Former Office to the Northwest	T	Pipe Insulation 2-6 inch	6100/01/01/15	Confirmed	40	EA	0	EA					1	No	1/D		
1	1	Main Office Storage Area/Former Office to the Northwest	N/A	Plaster Ceiling		NAD	200	SF	0	SF					N/A	N/A	N/A		
1	1	Main Office Storage Area/Former Office to the Northwest	N/A	CMU		Non Suspect ACM	500	SF	0	SF					N/A	N/A	N/A		
1	1	Main Office Storage Area/Former Office to the Northwest	N/A	Carpet		Non Suspect ACM	200	SF	0	SF					N/A	N/A	N/A		
1	1	Main Office Storage Area/Former Office to the Northwest	T	Pipe Insulation 2-6 inch	6100/01/01/15	Confirmed	20	LF	0	LF					1	No	1/D		
1	1	Main Office Storage Area/Former Office to the Northwest	N/A	Plaster Ceiling		NAD	48	SF	0	SF					N/A	N/A	N/A		
1	1	Main Office Storage Area/Former Office to the Northwest	N/A	CMU		Non Suspect ACM	150	SF	0	SF					N/A	N/A	N/A		
1	1	Main Office Storage Area/Former Office to the Northwest	M	Floor Tile VAT 9" x 9"	6100/01/01/20	Confirmed	48	SF	0	SF		Black			1	No	1/D		
1	1	Main Office Storage Area/Former Office to the Northwest	N/A	Plaster Ceiling		NAD	48	SF	0	SF					N/A	N/A	N/A		
1	1	Main Office Storage Area/Former Office to the Northwest	N/A	CMU		Non Suspect ACM	150	SF	0	SF					N/A	N/A	N/A		
1	1	Main Office Storage Area/Former Office to the Northwest	M	Floor Tile VAT 9" x 9"	6100/01/01/20	Confirmed	48	SF	0	SF		Black			1	No	1/D		
1	1	Principal's Office	N/A	Ceiling Tile 2' x 4'		Non Suspect ACM	400	SF	0	SF					N/A	N/A	N/A		
1	1	Principal's Office	N/A	CMU		Non Suspect ACM	800	SF	0	SF					N/A	N/A	N/A		
1	1	Principal's Office	M	Floor Tile VAT 12" x 12"	6100/01/01/EE	Assumed	400	SF	0	SF		Grey			1	No	1/D		
1	1	Principal's Office Storage Closet	N/A	Plaster Ceiling		NAD	50	SF	0	SF					N/A	N/A	N/A		
1	1	Principal's Office Storage Closet	N/A	CMU		Non Suspect ACM	150	SF	0	SF					N/A	N/A	N/A		
1	1	Principal's Office Storage Closet	M	Floor Tile VAT 9" x 9"	6100/01/01/20	Confirmed	50	SF	0	SF		Green			1	No	1/D		
1	1	Principal's Office Restroom	T	Pipe Fitting Insulation	6100/01/01/22	Confirmed	1	EA	0	EA					1	No	1/D		
1	1	Principal's Office Restroom	T	Pipe Insulation 2-6 inch	6100/01/01/15	Confirmed	10	LF	0	LF					1	No	1/D		
1	1	Principal's Office Restroom	N/A	CMU		Non Suspect ACM	200	SF	0	SF					N/A	N/A	N/A		
1	1	Principal's Office Restroom	N/A	Plaster Ceiling		NAD	50	SF	0	SF					N/A	N/A	N/A		
1	1	Principal's Office Restroom	M	Floor Tile VAT 12" x 12"	6100/01/01/EE	Assumed	50	SF	0	SF		Grey			1	No	1/D		
1	1	Conference Room attached to Principal's Office	T	Pipe Insulation 2-6 inch	6100/01/01/15	Confirmed	24	LF	0	LF					1	No	1/D		
1	1	Conference Room attached to Principal's Office	N/A	Ceiling Tile 2' x 4'		Non Suspect ACM	400	SF	0	SF					N/A	N/A	N/A		
1	1	Conference Room attached to Principal's Office	N/A	CMU		Non Suspect ACM	700	SF	0	SF					N/A	N/A	N/A		
1	1	Conference Room attached to Principal's Office	M	Floor Tile VAT 12" x 12"	6100/01/01/EE	Assumed	400	SF	0	SF		Grey			1	No	1/D		
1	1	Small Hallway leading to the Vice Principal's Office - Labeled 116A	N/A	Ceiling Tile 2' x 4'		Non Suspect ACM	100	SF	0	SF					N/A	N/A	N/A		
1	1	Small Hallway leading to the Vice Principal's Office - Labeled 116A	N/A	CMU		Non Suspect ACM	200	SF	0	SF					N/A	N/A	N/A		
1	1	Small Hallway leading to the Vice Principal's Office - Labeled 116A	M	Floor Tile VAT 12" x 12"	6100/01/01/EE	Assumed	100	SF	0	SF		Blue			1	No	1/D		
1	1	Vice Principal's Office 116C	N/A	Carpet		Non Suspect ACM	200	SF	0	SF					N/A	N/A	N/A		
1	1	Vice Principal's Office 116C	N/A	Concrete Block Wall		Non Suspect ACM	600	SF	0	SF					N/A	N/A	N/A		
1	1	Vice Principal's Office 116C	N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	200	SF	0	SF					N/A	N/A	N/A		
1	1	Room 116B - next to Vice Principal's Office	N/A	Ceiling Tile 2' x 4'		Non Suspect ACM	200	SF	0	SF					N/A	N/A	N/A		
1	1	Room 116B - next to Vice Principal's Office	N/A	CMU		Non Suspect ACM	300	SF	0	SF					N/A	N/A	N/A		
1	1	Room 116B - next to Vice Principal's Office	M	Floor Tile VAT 12" x 12"	6100/01/01/EE	Assumed	200	SF	0	SF		Blue			1	No	1/D		
1	1	IMC Library	T	Pipe Fitting Insulation	6100/01/01/22	Confirmed	33	SF	0	SF					1	No	1/D		
1	1	IMC Library	T	Pipe Insulation 2-6 inch	6100/01/01/15	Confirmed	150	LF	0	LF					1	No	1/D		
1	1	IMC Library	N/A	Plaster Ceiling		NAD	2000	SF	0	SF					N/A	N/A	N/A		
1	1	IMC Library	N/A	CMU		Non Suspect ACM	5000	SF	0	SF					N/A	N/A	N/A		
1	1	IMC Library	M	Floor Tile VAT 9" x 9"	6100/01/01/20	Confirmed	2000	SF	0	SF		Green			1	No	1/D		

6100/6460 Hill Freedman World Academy @ Leeds Campus 2015 2016 AHERA Three-Year Report.xls

School District of Philadelphia Hill Freedman World Academy @ Leeds Campus 1100 E. Mount Pleasant Avenue, Philadelphia, PA, 19150 ULCS# 6100 Year Built: 1953			AHERA Three-Year Reinspection 2015-2016 Room by Room Location Log Report										Reinspection Date: October 30, 2015 Building Inspector: A. Roman Number: 150619008 Management Planner: Megan Vala Number: 740728						
Element	Room	On Site Room Name	System Affected	Material Description	HID#	Confirmed/Assumed/NAD/ Non Suspect ACM	Amount of Material	SF LF EA	Amount of Damage	SF LF EA	Color required for VAT	Comments/Description/Notes	Attic/ Crawl Space Potential Ranking	Damage Potential (DP)	Newly Friable (NF)	Response Action (RA)			
1	1	Classroom 114	T	Pipe Fitting Insulation	6100/01/01/22	Confirmed	17	EA	0	EA				1	No	1/D			
1	1	Classroom 114	T	Pipe Insulation 2-6 inch	6100/01/01/15	Confirmed	50	LF	0	LF				1	No	1/D			
1	1	Classroom 114	N/A	Plaster Ceiling		NAD	800	SF	0	SF				N/A	N/A	N/A			
1	1	Classroom 114	N/A	CMU		Non Suspect ACM	1200	SF	0	SF				N/A	N/A	N/A			
1	1	Classroom 114	M	Floor Tile VAT 9" x 9"	6100/01/01/20	Confirmed	800	SF	0	SF	Tan			1	No	1/D			
1	1	Women's Lounge across from Classroom 114	M	Floor Tile VAT 9" x 9"	6100/01/01/20	Confirmed	200	SF	0	SF	Green	Discolored floor tile only		1	No	1/D			
1	1	Women's Lounge across from Classroom 114	T	Pipe Fitting Insulation	6100/01/01/22	Confirmed	12	EA	0	EA				1	No	1/D			
1	1	Women's Lounge across from Classroom 114	T	Pipe Insulation 2-6 inch	6100/01/01/15	Confirmed	50	LF	0	LF				1	No	1/D			
1	1	Women's Lounge across from Classroom 114	N/A	Plaster Ceiling		NAD	200	SF	0	SF				N/A	N/A	N/A			
1	1	Women's Lounge across from Classroom 114	N/A	CMU		Non Suspect ACM	500	SF	0	SF				N/A	N/A	N/A			
1	1	Classroom 114	M	Blackboard Glue Dots	6100/01/01/VER/AR/2600	Assumed	10	SF	0	SF				1	No	1/D			
1	1	Restroom in Women's Lounge across Classroom 114	M	Floor Tile VAT 9" x 9"	6100/01/01/20	Confirmed	35	SF	0	SF	Black	Discolored floor tile only		1	No	1/D			
1	1	Restroom in Women's Lounge across Classroom 114	M	Floor Tile VAT 9" x 9"	6100/01/01/20	Confirmed	35	SF	0	SF	Green			1	No	1/D			
1	1	Restroom in Women's Lounge across Classroom 114	N/A	Concrete Ceiling		Non Suspect ACM	70	SF	0	SF				N/A	N/A	N/A			
1	1	Restroom in Women's Lounge across Classroom 114	N/A	Concrete Block Wall		Non Suspect ACM	70	SF	0	SF				N/A	N/A	N/A			
1	1	Restroom in Women's Lounge across Classroom 114	N/A	Sheetrock Wall		Non Suspect ACM	140	SF	0	SF				N/A	N/A	N/A			
1	1	Men's Lounge across from Classroom 114	T	Pipe Fitting Insulation	6100/01/01/22	Confirmed	6	EA	0	EA				1	No	1/D			
1	1	Men's Lounge across from Classroom 114	T	Pipe Insulation 2-6 inch	6100/01/01/15	Confirmed	10	LF	0	LF				1	No	1/D			
1	1	Men's Lounge across from Classroom 114	N/A	Plaster Ceiling		NAD	200	SF	0	SF				N/A	N/A	N/A			
1	1	Men's Lounge across from Classroom 114	N/A	CMU		Non Suspect ACM	500	SF	0	SF				N/A	N/A	N/A			
1	1	Men's Lounge across from Classroom 114	M	Floor Tile VAT 9" x 9"	6100/01/01/20	Confirmed	200	SF	0	SF	Tan			1	No	1/D			
1	1	Restroom in Men's Lounge across Classroom 114	M	Floor Tile VAT 12" x 12"	6100/01/01/EE	Assumed	60	SF	0	SF	Tan			1	No	1/D			
1	1	Restroom in Men's Lounge across Classroom 114	N/A	Concrete Ceiling		Non Suspect ACM	60	SF	0	SF				N/A	N/A	N/A			
1	1	Restroom in Men's Lounge across Classroom 114	N/A	Concrete Block Wall		Non Suspect ACM	60	SF	0	SF				N/A	N/A	N/A			
1	1	Restroom in Men's Lounge across Classroom 114	N/A	Sheetrock Wall		Non Suspect ACM	120	SF	0	SF				N/A	N/A	N/A			
1	1	Stairwell next to Classroom 115	N/A	Plaster Ceiling		NAD	200	SF	0	SF				N/A	N/A	N/A			
1	1	Stairwell next to Classroom 115	N/A	Ceramic Tile Walls		Non Suspect ACM	500	SF	0	SF				N/A	N/A	N/A			
1	1	Stairwell next to Classroom 115	N/A	Cement Floor		Non Suspect ACM	200	SF	0	SF				N/A	N/A	N/A			
1	1	Stairwell next to Classroom 115	T	Radiator Insulation	6100/01/01/SYN/BB/1600	Assumed	25	SF	0	SF		1 Recessed Radiator		1	No	1/D			
1	1	Boy's Restroom across from Classroom 115	T	Pipe Fitting Insulation	6100/01/01/22	Confirmed	4	EA	0	EA				1	No	1/D			
1	1	Boy's Restroom across from Classroom 115	T	Pipe Insulation 2-6 inch	6100/01/01/15	Confirmed	16	LF	0	LF				1	No	1/D			
1	1	Boy's Restroom across from Classroom 115	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	10	LF	10	LF				N/A	N/A	N/A			
1	1	Boy's Restroom across from Classroom 115	N/A	Plaster Ceiling		NAD	250	SF	0	SF				N/A	N/A	N/A			
1	1	Boy's Restroom across from Classroom 115	N/A	Ceramic Tile Walls		Non Suspect ACM	700	SF	0	SF				N/A	N/A	N/A			
1	1	Boy's Restroom across from Classroom 115	N/A	Cement Floor		Non Suspect ACM	250	SF	0	SF				N/A	N/A	N/A			
1	1	Custodial Closet across from Classroom 115	T	Pipe Fitting Insulation	6100/01/01/22	Confirmed	9	EA	0	EA				1	No	1/D			
1	1	Custodial Closet across from Classroom 115	T	Pipe Insulation 2-6 inch	6100/01/01/15	Confirmed	35	LF	0	LF				1	No	1/D			
1	1	Custodial Closet across from Classroom 115	N/A	Plaster Ceiling		NAD	48	SF	0	SF				N/A	N/A	N/A			
1	1	Custodial Closet across from Classroom 115	N/A	CMU		Non Suspect ACM	200	SF	0	SF				N/A	N/A	N/A			
1	1	Custodial Closet across from Classroom 115	N/A	Cement Floor		Non Suspect ACM	48	SF	0	SF				N/A	N/A	N/A			
1	1	Classroom 115	T	Pipe Fitting Insulation	6100/01/01/22	Confirmed	6	EA	0	EA				1	No	1/D			
1	1	Classroom 115	T	Pipe Insulation 2-6 inch	6100/01/01/15	Confirmed	76	LF	0	LF				1	No	1/D			
1	1	Classroom 115	N/A	Plaster Ceiling		NAD	800	SF	0	SF				N/A	N/A	N/A			
1	1	Classroom 115	N/A	CMU		Non Suspect ACM	1200	SF	0	SF				N/A	N/A	N/A			
1	1	Classroom 115	M	Floor Tile VAT 9" x 9"	6100/01/01/20	Confirmed	800	SF	0	SF	Tan			1	No	1/D			
1	1	Classroom 115	M	Blackboard Glue Dots	6100/01/01/VER/AR/2600	Assumed	10	SF	0	SF				1	No	1/D			
1	1	Classroom 117	T	Pipe Fitting Insulation	6100/01/01/22	Confirmed	13	EA	0	EA				1	No	1/D			
1	1	Classroom 117	T	Pipe Insulation 2-6 inch	6100/01/01/15	Confirmed	45	LF	0	LF				1	No	1/D			
1	1	Classroom 117	N/A	Plaster Ceiling		NAD	800	SF	0	SF				N/A	N/A	N/A			
1	1	Classroom 117	N/A	CMU		Non Suspect ACM	1200	SF	0	SF				N/A	N/A	N/A			
1	1	Classroom 117	M	Floor Tile VAT 9" x 9"	6100/01/01/20	Confirmed	800	SF	0	SF	Tan			1	No	1/D			
1	1	Classroom 117	M	Blackboard Glue Dots	6100/01/01/VER/AR/2600	Assumed	10	SF	0	SF				1	No	1/D			
1	1	Classroom 117 Storage/Additional Class Space to the Left of Classroom 117 Entrance	T	Pipe Fitting Insulation	6100/01/01/22	Confirmed	5	EA	0	EA				1	No	1/D			
1	1	Classroom 117 Storage/Additional Class Space to the Left of Classroom 117 Entrance	T	Pipe Insulation 2-6 inch	6100/01/01/15	Confirmed	20	LF	0	LF				1	No	1/D			
1	1	Classroom 117 Storage/Additional Class Space to the Left of Classroom 117 Entrance	N/A	Plaster Ceiling		NAD	500	SF	0	SF				N/A	N/A	N/A			
1	1	Classroom 117 Storage/Additional Class Space to the Left of Classroom 117 Entrance	N/A	CMU		Non Suspect ACM	900	SF	0	SF				N/A	N/A	N/A			
1	1	Classroom 117 Storage/Additional Class Space to the Left of Classroom 117 Entrance	M	Floor Tile VAT 9" x 9"	6100/01/01/20	Confirmed	500	SF	0	SF	Tan			1	No	1/D			
1	1	Classroom 117 Storage Closet	N/A	Plaster Ceiling		NAD	48	SF	0	SF				N/A	N/A	N/A			
1	1	Classroom 117 Storage Closet	N/A	CMU		Non Suspect ACM	150	SF	0	SF				N/A	N/A	N/A			
1	1	Classroom 117 Storage Closet	M	Floor Tile VAT 9" x 9"	6100/01/01/20	Confirmed	48	SF	0	SF	Tan			1	No	1/D			
1	1	Classroom 116	T	Pipe Fitting Insulation	6100/01/01/22	Confirmed	15	EA	0	EA				1	No	1/D			
1	1	Classroom 116	T	Pipe Insulation 2-6 inch	6100/01/01/15	Confirmed	60	LF	0	LF				1	No	1/D			
1	1	Classroom 116	N/A	Plaster Ceiling		NAD	800	SF	0	SF				N/A	N/A	N/A			
1	1	Classroom 116	N/A	CMU		Non Suspect ACM	1200	SF	0	SF				N/A	N/A	N/A			
1	1	Classroom 116	M	Floor Tile VAT 9" x 9"	6100/01/01/20	Confirmed	800	SF	0	SF	Tan			1	No	1/D			
1	1	Classroom 116	M	Blackboard Glue Dots	6100/01/01/VER/AR/2600	Assumed	10	SF	0	SF				1	No	1/D			
1	1	Classroom 118	T	Pipe Fitting Insulation	6100/01/01/22	Confirmed	8	EA	0	EA				1	No	1/D			
1	1	Classroom 118	T	Pipe Insulation 2-6 inch	6100/01/01/15	Confirmed	36	LF	0	LF				1	No	1/D			
1	1	Classroom 118	N/A	Plaster Ceiling		NAD	800	SF	0	SF				N/A	N/A	N/A			
1	1	Classroom 118	N/A	CMU		Non Suspect ACM	1200	SF	0	SF				N/A	N/A	N/A			
1	1	Classroom 118	M	Floor Tile VAT 9" x 9"	6100/01/01/20	Confirmed	800	SF	0	SF	Tan			1	No	1/D			
1	1	Classroom 118 Storage Closet	N/A	CMU		Non Suspect ACM	200	SF	0	SF				N/A	N/A	N/A			
1	1	Classroom 118 Storage Closet	N/A	Plaster Ceiling		NAD	50	SF	0	SF				N/A	N/A	N/A			
1	1	Classroom 118 Storage Closet	M	Floor Tile VAT 9" x 9"	6100/01/01/20	Confirmed	50	SF	0	SF	Tan			1	No	1/D			
1	1	Classroom 119	T	Pipe Fitting Insulation	6100/01/01/22	Confirmed	15	EA	0	EA				1	No	1/D			

6100/6460 Hill Freedman World Academy @ Leeds Campus 2015 2016 AHERA Three-Year Report.xls

School District of Philadelphia Hill Freedman World Academy @ Leeds Campus 1100 E. Mount Pleasant Avenue, Philadelphia, PA, 19150 ULCS# 6100 Year Built: 1953			AHERA Three-Year Reinspection 2015-2016 Room by Room Location Log Report										Reinspection Date: October 30, 2015 Building Inspector: A. Roman Number: 150619008 Management Planner: Megan Vala Number: 740728								
Element	Room	On Site Room Name	System Affected	Material Description	HID#	Confirmed/Assumed/NAD/ Non Suspect ACM	Amount of Material	SF LF EA	Amount of Damage	SF LF EA	Color required for VAT	Comments/Description/Notes	Attic/ Crawl Space Ranking	Damage Potential (DP)	Newly Friable (NF)	Response Action (RA)					
1	1	Classroom 119	T	Pipe Insulation 2-6 inch	6100/01/01/15	Confirmed	85	LF	0	LF				1	No	1/D					
1	1	Classroom 119	N/A	Plaster Ceiling		NAD	800	SF	0	SF				N/A	N/A	N/A					
1	1	Classroom 119	N/A	CMU		Non Suspect ACM	1200	SF	0	SF				N/A	N/A	N/A					
1	1	Classroom 119	M	Floor Tile VAT 9" x 9"	6100/01/01/20	Confirmed	800	SF	0	SF	Tan			1	No	1/D					
1	1	Classroom 119	M	Blackboard Glue Dots	6100/01/01/VER/AR/2600	Assumed	10	SF	0	SF				1	No	1/D					
1	1	Classroom 121	T	Pipe Fitting Insulation	6100/01/01/22	Confirmed	20	EA	0	EA				1	No	1/D					
1	1	Classroom 121	T	Pipe Insulation 2-6 inch	6100/01/01/15	Confirmed	150	LF	0	LF				1	No	1/D					
1	1	Classroom 121	N/A	Plaster Ceiling		NAD	800	SF	0	SF				N/A	N/A	N/A					
1	1	Classroom 121	N/A	CMU		Non Suspect ACM	1200	SF	0	SF				N/A	N/A	N/A					
1	1	Classroom 121	M	Floor Tile VAT 9" x 9"	6100/01/01/20	Confirmed	800	SF	0	SF	Green			1	No	1/D					
1	1	Classroom 121	M	Blackboard Glue Dots	6100/01/01/VER/AR/2600	Assumed	10	SF	0	SF				1	No	1/D					
1	1	Classroom 121 Storage Closet	T	Pipe Fitting Insulation	6100/01/01/22	Confirmed	6	EA	0	EA				1	No	1/D					
1	1	Classroom 121 Storage Closet	T	Pipe Insulation 2-6 inch	6100/01/01/15	Confirmed	15	LF	0	LF				1	No	1/D					
1	1	Classroom 121 Storage Closet	N/A	Plaster Ceiling		NAD	48	SF	0	SF				N/A	N/A	N/A					
1	1	Classroom 121 Storage Closet	N/A	CMU		Non Suspect ACM	150	SF	0	SF				N/A	N/A	N/A					
1	1	Classroom 121 Storage Closet	M	Floor Tile VAT 9" x 9"	6100/01/01/20	Confirmed	48	SF	0	SF	Green			1	No	1/D					
1	1	Classroom attached to Classroom 121	M	Floor Tile VAT 9" x 9"	6100/01/01/20	Confirmed	800	SF	0	SF	Green	For IEQ		1	No	1/D					
1	1	Classroom attached to Classroom 121	N/A	Plaster Ceiling		NAD	800	SF	0	SF				N/A	N/A	N/A					
1	1	Classroom attached to Classroom 121	N/A	CMU		Non Suspect ACM	1200	SF	0	SF				N/A	N/A	N/A					
1	1	Classroom attached to Classroom 121	M	Blackboard Glue Dots	6100/01/01/VER/AR/2600	Assumed	10	SF	0	SF				1	No	1/D					
1	1	Classroom 120	T	Pipe Fitting Insulation	6100/01/01/22	Confirmed	13	EA	0	EA				1	No	1/D					
1	1	Classroom 120	T	Pipe Insulation 2-6 inch	6100/01/01/15	Confirmed	60	LF	0	LF				1	No	1/D					
1	1	Classroom 120	N/A	Plaster Ceiling		NAD	800	SF	0	SF				N/A	N/A	N/A					
1	1	Classroom 120	N/A	CMU		Non Suspect ACM	1200	SF	0	SF				N/A	N/A	N/A					
1	1	Classroom 120	M	Floor Tile VAT 9" x 9"	6100/01/01/20	Confirmed	800	SF	0	SF	Tan			1	No	1/D					
1	1	Classroom 120	M	Blackboard Glue Dots	6100/01/01/VER/AR/2600	Assumed	10	SF	0	SF				1	No	1/D					
1	1	Classroom 122	T	Pipe Fitting Insulation	6100/01/01/22	Confirmed	18	EA	0	EA				1	No	1/D					
1	1	Classroom 122	T	Pipe Insulation 2-6 inch	6100/01/01/15	Confirmed	80	LF	0	LF				1	No	1/D					
1	1	Classroom 122	N/A	Plaster Ceiling		NAD	800	SF	0	SF				N/A	N/A	N/A					
1	1	Classroom 122	N/A	CMU		Non Suspect ACM	1200	SF	0	SF				N/A	N/A	N/A					
1	1	Classroom 122	M	Floor Tile VAT 9" x 9"	6100/01/01/20	Confirmed	900	SF	0	SF	Tan			1	No	1/D					
1	1	Classroom 122	M	Blackboard Glue Dots	6100/01/01/VER/AR/2600	Assumed	10	SF	0	SF				1	No	1/D					
1	1	Teacher's Lounge Room 123 at the Southeastern Corner of Main Hallway across from Classroom 122	T	Pipe Fitting Insulation	6100/01/01/22	Confirmed	8	EA	0	EA				1	No	1/D					
1	1	Teacher's Lounge Room 123 at the Southeastern Corner of Main Hallway across from Classroom 122	T	Pipe Insulation 2-6 inch	6100/01/01/15	Confirmed	35	LF	0	LF				1	No	1/D					
1	1	Teacher's Lounge Room 123 at the Southeastern Corner of Main Hallway across from Classroom 122	N/A	Plaster Ceiling		NAD	800	SF	0	SF				N/A	N/A	N/A					
1	1	Teacher's Lounge Room 123 at the Southeastern Corner of Main Hallway across from Classroom 122	N/A	CMU		Non Suspect ACM	1200	SF	0	SF				N/A	N/A	N/A					
1	1	Teacher's Lounge Room 123 at the Southeastern Corner of Main Hallway across from Classroom 122	M	Floor Tile VAT 9" x 9"	6100/01/01/20	Confirmed	800	SF	0	SF	Black			1	No	1/D					
1	1	Teacher's Lounge Room 123 at the Southeastern Corner of Main Hallway across from Classroom 122	M	Blackboard Glue Dots	6100/01/01/VER/AR/2600	Assumed	10	SF	0	SF				1	No	1/D					
1	1	Girl's Restroom next to Teacher's Lounge 123	M	Transite Stairs	6100/01/01/19	Confirmed	5	EA	0	EA		Small holes only, no debris observed		1	No	1/D					
1	1	Girl's Restroom next to Teacher's Lounge 123	T	Pipe Fitting Insulation	6100/01/01/22	Confirmed	3	EA	0	EA				1	No	1/D					
1	1	Girl's Restroom next to Teacher's Lounge 123	T	Pipe Insulation 2-6 inch	6100/01/01/15	Confirmed	32	LF	0	LF				1	No	1/D					
1	1	Girl's Restroom next to Teacher's Lounge 123	N/A	Plaster Ceiling		NAD	300	SF	0	SF				N/A	N/A	N/A					
1	1	Girl's Restroom next to Teacher's Lounge 123	N/A	Ceramic Tile Walls		Non Suspect ACM	500	SF	0	SF				N/A	N/A	N/A					
1	1	Girl's Restroom next to Teacher's Lounge 123	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	10	LF	10	LF				N/A	N/A	N/A					
1	1	Girl's Restroom next to Teacher's Lounge 123	N/A	Cement Floor		Non Suspect ACM	300	SF	0	SF				N/A	N/A	N/A					
1	1	Hallway from the Main Office to Classroom 122	T	Pipe Fitting Insulation	6100/01/01/22	Confirmed	15	EA	0	EA				1	No	1/D					
1	1	Hallway from the Main Office to Classroom 122	N/A	Plaster Ceiling		NAD	1200	SF	0	SF				N/A	N/A	N/A					
1	1	Hallway from the Main Office to Classroom 122	N/A	CMU		Non Suspect ACM	2500	SF	0	SF				N/A	N/A	N/A					
1	1	Hallway from the Main Office to Classroom 122	M	Floor Tile VAT 9" x 9"	6100/01/01/20	Confirmed	1200	SF	0	SF	Green			1	No	1/D					
1	1	Hallway from the Main Office to Classroom 122	T	Pipe Insulation 2-6 inch	6100/01/01/15	Confirmed	72	LF	0	LF				1	No	1/D					
1	1	Stairwell next to Classroom 122	N/A	Plaster Ceiling		NAD	200	SF	0	SF				N/A	N/A	N/A					
1	1	Stairwell next to Classroom 122	N/A	Ceramic Tile Walls		Non Suspect ACM	500	SF	0	SF				N/A	N/A	N/A					
1	1	Stairwell next to Classroom 122	N/A	Cement Floor		Non Suspect ACM	200	SF	0	SF				N/A	N/A	N/A					
1	1	Stairwell next to Classroom 122	T	Radiator Insulation	6100/01/01/SYN/BB/1600	Assumed	25	SF	0	SF		1 Recessed Radiator		1	No	1/D					
1	1	Stairwell next to Teacher's Lounge 123	N/A	Plaster Ceiling		NAD	200	SF	0	SF				N/A	N/A	N/A					
1	1	Stairwell next to Teacher's Lounge 123	N/A	Ceramic Tile Walls		Non Suspect ACM	500	SF	0	SF				N/A	N/A	N/A					
1	1	Stairwell next to Teacher's Lounge 123	N/A	Cement Floor		Non Suspect ACM	200	SF	0	SF				N/A	N/A	N/A					
1	1	Stairwell next to Teacher's Lounge 123	T	Radiator Insulation	6100/01/01/SYN/BB/1600	Assumed	25	SF	0	SF		1 Recessed Radiator		1	No	1/D					
1	1	Hallway at entrances to Former Locker Rooms	T	Pipe Fitting Insulation	6100/01/01/22	Confirmed	22	EA	0	EA				1	No	1/D					
1	1	Hallway at entrances to Former Locker Rooms	T	Pipe Insulation 2-6 inch	6100/01/01/15	Confirmed	35	LF	0	LF				1	No	1/D					
1	1	Hallway at entrances to Former Locker Rooms	N/A	Plaster Ceiling		NAD	500	SF	0	SF				N/A	N/A	N/A					
1	1	Hallway at entrances to Former Locker Rooms	N/A	CMU		Non Suspect ACM	1000	SF	0	SF				N/A	N/A	N/A					
1	1	Hallway at entrances to Former Locker Rooms	M	Floor Tile VAT 9" x 9"	6100/01/01/20	Confirmed	500	SF	0	SF	Green			1	No	1/D					
1	1	Custodial Closet 140 in Hallway at Entrance to Former Locker Rooms	N/A	Cement Floor		Non Suspect ACM	25	SF	0	SF				N/A	N/A	N/A					
1	1	Custodial Closet 140 in Hallway at Entrance to Former Locker Rooms	N/A	Concrete Block Wall		Non Suspect ACM	75	SF	0	SF				N/A	N/A	N/A					
1	1	Custodial Closet 140 in Hallway at Entrance to Former Locker Rooms	N/A	Concrete Ceiling		Non Suspect ACM	25	SF	0	SF				N/A	N/A	N/A					
1	1	Custodial Closet 140 in Hallway at Entrance to Former Locker Rooms	T	Pipe Insulation > 6 inch	6100/01/01/15	Confirmed	7	LF	0	LF		Applied to a drain line; Loose/Flaking Paint on TSI		1	No	1/D					
1	1	Custodial Closet 140 in Hallway at Entrance to Former Locker Rooms	T	Pipe Insulation 2-6 inch	6100/01/01/15	Confirmed	65	LF	0	LF		Loose/Flaking Paint on TSI		1	No	1/D					
1	1	Custodial Closet 140 in Hallway at Entrance to Former Locker Rooms	T	Pipe Fitting Insulation	6100/01/01/22	Confirmed	21	EA	0	EA		Loose/Flaking Paint on TSI		1	No	1/D					

6100/6460 Hill Freedman World Academy @ Leeds Campus 2015 2016 AHERA Three-Year Report.xls

School District of Philadelphia Hill Freedman World Academy @ Leeds Campus 1100 E. Mount Pleasant Avenue, Philadelphia, PA, 19150 ULCS# 6100 Year Built: 1953			AHERA Three-Year Reinspection 2015-2016 Room by Room Location Log Report										Reinspection Date: October 30, 2015 Building Inspector: A. Roman Number: 150619008 Management Planner: Megan Vala Number: 740728							
E l e m e n t	F l o o r	On Site Room Name	System Affected	Material Description	HID#	Confirmed/Assumed/NAD/ Non Suspect ACM	Amount of Material	SF LF EA	Amount of Damage	SF LF EA	Color required for VAT	Comments/Description/Notes	Attic/ Crawl/ Space Ranking	Damage Potential (DP)	Newly Friable (NF)	Response Action (RA)				
1	1	Former Girl's Locker Room	T	Pipe Fitting Insulation	6100/01/01/22	Confirmed	6	EA	0	EA		124, 125, 126 Locker Room Wing was renovated in the summer of 2016. All rooms require reinspection during the next 6 month surveillance.		1	No	1/D				
1	1	Former Girl's Locker Room	T	Pipe Insulation 2-6 inch	6100/01/01/15	Confirmed	50	LF	0	LF		124, 125, 126 Locker Room Wing was renovated in the summer of 2016. All rooms require reinspection during the next 6 month surveillance.		1	No	1/D				
1	1	Former Girl's Locker Room	T	Pipe Insulation > 6 inch	6100/01/01/18	Confirmed	15	LF	0	LF		124, 125, 126 Locker Room Wing was renovated in the summer of 2016. All rooms require reinspection during the next 6 month surveillance.		1	No	1/D				
1	1	Former Girl's Locker Room	N/A	Plaster Ceiling		NAD	3000	SF	0	SF		124, 125, 126 Locker Room Wing was renovated in the summer of 2016. All rooms require reinspection during the next 6 month surveillance.		N/A	N/A	N/A				
1	1	Former Girl's Locker Room	N/A	CMU		Non Suspect ACM	5000	SF	0	SF		124, 125, 126 Locker Room Wing was renovated in the summer of 2016. All rooms require reinspection during the next 6 month surveillance.		N/A	N/A	N/A				
1	1	Former Girl's Locker Room	N/A	Cement Floor		Non Suspect ACM	3000	SF	0	SF		124, 125, 126 Locker Room Wing was renovated in the summer of 2016. All rooms require reinspection during the next 6 month surveillance.		N/A	N/A	N/A				
1	1	Former Girl's Showers	N/A	Concrete Ceiling		Non Suspect ACM	800	SF	0	SF		124, 125, 126 Locker Room Wing was renovated in the summer of 2016. All rooms require reinspection during the next 6 month surveillance.		N/A	N/A	N/A				
1	1	Former Girl's Showers	N/A	Ceramic Tile Walls		Non Suspect ACM	1200	SF	0	SF		124, 125, 126 Locker Room Wing was renovated in the summer of 2016. All rooms require reinspection during the next 6 month surveillance.		N/A	N/A	N/A				
1	1	Former Girl's Showers	N/A	Cement Floor		Non Suspect ACM	800	SF	0	SF		124, 125, 126 Locker Room Wing was renovated in the summer of 2016. All rooms require reinspection during the next 6 month surveillance.		N/A	N/A	N/A				
1	1	Girl's Locker Room Restroom	M	Transite Stalls	6100/01/01/19	Confirmed	3	EA	0	EA		Small holes only; no debris observed - 124, 125, 126 Locker Room Wing was renovated in the summer of 2016. All rooms require reinspection during the next 6 month surveillance.		1	No	1/D				
1	1	Girl's Locker Room Restroom	N/A	Concrete Ceiling		Non Suspect ACM	300	SF	0	SF		124, 125, 126 Locker Room Wing was renovated in the summer of 2016. All rooms require reinspection during the next 6 month surveillance.		N/A	N/A	N/A				
1	1	Girl's Locker Room Restroom	N/A	Ceramic Tile Walls		Non Suspect ACM	500	SF	0	SF		124, 125, 126 Locker Room Wing was renovated in the summer of 2016. All rooms require reinspection during the next 6 month surveillance.		N/A	N/A	N/A				
1	1	Girl's Locker Room Restroom	N/A	Cement Floor		Non Suspect ACM	300	SF	0	SF		124, 125, 126 Locker Room Wing was renovated in the summer of 2016. All rooms require reinspection during the next 6 month surveillance.		N/A	N/A	N/A				
1	1	Girl's Locker Room Restroom	T	Pipe Fitting Insulation	6100/01/01/22	Confirmed	6	EA	0	EA		124, 125, 126 Locker Room Wing was renovated in the summer of 2016. All rooms require reinspection during the next 6 month surveillance.		1	No	1/D				
1	1	Girl's Locker Room Restroom	T	Pipe Insulation 2-6 inch	6100/01/01/15	Confirmed	7	LF	0	LF		124, 125, 126 Locker Room Wing was renovated in the summer of 2016. All rooms require reinspection during the next 6 month surveillance.		1	No	1/D				
1	1	Stairwell From the Girl's Former Locker Room to the Gym	N/A	Plaster Ceiling		NAD	200	SF	0	SF		124, 125, 126 Locker Room Wing was renovated in the summer of 2016. All rooms require reinspection during the next 6 month surveillance.		N/A	N/A	N/A				
1	1	Stairwell From the Girl's Former Locker Room to the Gym	N/A	Ceramic Tile Walls		Non Suspect ACM	500	SF	0	SF		124, 125, 126 Locker Room Wing was renovated in the summer of 2016. All rooms require reinspection during the next 6 month surveillance.		N/A	N/A	N/A				
1	1	Stairwell From the Girl's Former Locker Room to the Gym	N/A	Cement Floor		Non Suspect ACM	200	SF	0	SF		124, 125, 126 Locker Room Wing was renovated in the summer of 2016. All rooms require reinspection during the next 6 month surveillance.		N/A	N/A	N/A				
1	1	Stairwell From the Girl's Former Locker Room to the Gym	T	Radiator Insulation	6100/01/01/SYN/BB/1600	Assumed	25	SF	0	SF		1 Recessed Radiator - 25 SF - 124, 125, 126 Locker Room Wing was renovated in the summer of 2016. All rooms require reinspection during the next 6 month surveillance.		1	No	1/D				
1	1	Hallway to Rooms 124-125	T	Pipe Fitting Insulation	6100/01/01/22	Confirmed	2	EA	0	EA		124, 125, 126 Locker Room Wing was renovated in the summer of 2016. All rooms require reinspection during the next 6 month surveillance.		1	No	1/D				
1	1	Hallway to Rooms 124-125	T	Pipe Insulation 2-6 inch	6100/01/01/15	Confirmed	10	LF	0	LF		124, 125, 126 Locker Room Wing was renovated in the summer of 2016. All rooms require reinspection during the next 6 month surveillance.		1	No	1/D				
1	1	Hallway to Rooms 124-125	N/A	Plaster Ceiling		NAD	700	SF	0	SF		124, 125, 126 Locker Room Wing was renovated in the summer of 2016. All rooms require reinspection during the next 6 month surveillance.		N/A	N/A	N/A				
1	1	Hallway to Rooms 124-125	N/A	CMU		Non Suspect ACM	1200	SF	0	SF		124, 125, 126 Locker Room Wing was renovated in the summer of 2016. All rooms require reinspection during the next 6 month surveillance.		N/A	N/A	N/A				
1	1	Hallway to Rooms 124-125	M	Floor Tile VAT 9" x 9"	6100/01/01/20	Confirmed	700	SF	0	SF	Tan	124, 125, 126 Locker Room Wing was renovated in the summer of 2016. All rooms require reinspection during the next 6 month surveillance.		1	No	1/D				
1	1	Classroom 125 - Girl's Corrective Gymnastics	T	Pipe Fitting Insulation	6100/01/01/22	Confirmed	2	EA	0	EA		124, 125, 126 Locker Room Wing was renovated in the summer of 2016. All rooms require reinspection during the next 6 month surveillance.		1	No	1/D				
1	1	Classroom 125 - Girl's Corrective Gymnastics	T	Pipe Insulation 2-6 inch	6100/01/01/15	Confirmed	20	LF	0	LF		124, 125, 126 Locker Room Wing was renovated in the summer of 2016. All rooms require reinspection during the next 6 month surveillance.		1	No	1/D				
1	1	Classroom 125 - Girl's Corrective Gymnastics	N/A	Plaster Ceiling		NAD	800	SF	0	SF		124, 125, 126 Locker Room Wing was renovated in the summer of 2016. All rooms require reinspection during the next 6 month surveillance.		N/A	N/A	N/A				
1	1	Classroom 125 - Girl's Corrective Gymnastics	N/A	Ceramic Tile Walls		Non Suspect ACM	1200	SF	0	SF		124, 125, 126 Locker Room Wing was renovated in the summer of 2016. All rooms require reinspection during the next 6 month surveillance.		N/A	N/A	N/A				
1	1	Classroom 125 - Girl's Corrective Gymnastics	N/A	Wood Floor		Non Suspect ACM	800	SF	0	SF		124, 125, 126 Locker Room Wing was renovated in the summer of 2016. All rooms require reinspection during the next 6 month surveillance.		N/A	N/A	N/A				
1	1	Classroom 125 - Girl's Corrective Gymnastics Storage Closet	N/A	Plaster Ceiling		NAD	200	SF	0	SF		124, 125, 126 Locker Room Wing was renovated in the summer of 2016. All rooms require reinspection during the next 6 month surveillance.		N/A	N/A	N/A				
1	1	Classroom 125 - Girl's Corrective Gymnastics Storage Closet	N/A	CMU		Non Suspect ACM	300	SF	0	SF		124, 125, 126 Locker Room Wing was renovated in the summer of 2016. All rooms require reinspection during the next 6 month surveillance.		N/A	N/A	N/A				
1	1	Classroom 125 - Girl's Corrective Gymnastics Storage Closet	M	Floor Tile VAT 9" x 9"	6100/01/01/20	Confirmed	200	SF	0	SF	Black	124, 125, 126 Locker Room Wing was renovated in the summer of 2016. All rooms require reinspection during the next 6 month surveillance.		1	No	1/D				
1	1	Classroom 124	T	Pipe Fitting Insulation	6100/01/01/22	Confirmed	2	EA	0	EA		124, 125, 126 Locker Room Wing was renovated in the summer of 2016. All rooms require reinspection during the next 6 month surveillance.		1	No	1/D				
1	1	Classroom 124	T	Pipe Insulation 2-6 inch	6100/01/01/15	Confirmed	20	LF	0	LF		124, 125, 126 Locker Room Wing was renovated in the summer of 2016. All rooms require reinspection during the next 6 month surveillance.		1	No	1/D				
1	1	Classroom 124	N/A	Plaster Ceiling		NAD	800	SF	0	SF		124, 125, 126 Locker Room Wing was renovated in the summer of 2016. All rooms require reinspection during the next 6 month surveillance.		N/A	N/A	N/A				
1	1	Classroom 124	N/A	Ceramic Tile Walls		Non Suspect ACM	1200	SF	0	SF		124, 125, 126 Locker Room Wing was renovated in the summer of 2016. All rooms require reinspection during the next 6 month surveillance.		N/A	N/A	N/A				
1	1	Classroom 124	N/A	Wood Floor		Non Suspect ACM	800	SF	0	SF		124, 125, 126 Locker Room Wing was renovated in the summer of 2016. All rooms require reinspection during the next 6 month surveillance.		N/A	N/A	N/A				
1	1	Classroom 124 Storage Closet	N/A	Plaster Ceiling		NAD	200	SF	0	SF		124, 125, 126 Locker Room Wing was renovated in the summer of 2016. All rooms require reinspection during the next 6 month surveillance.		N/A	N/A	N/A				
1	1	Classroom 124 Storage Closet	N/A	CMU		Non Suspect ACM	300	SF	0	SF		124, 125, 126 Locker Room Wing was renovated in the summer of 2016. All rooms require reinspection during the next 6 month surveillance.		N/A	N/A	N/A				
1	1	Classroom 124 Storage Closet	M	Floor Tile VAT 9" x 9"	6100/01/01/20	Confirmed	200	SF	0	SF	Black	124, 125, 126 Locker Room Wing was renovated in the summer of 2016. All rooms require reinspection during the next 6 month surveillance.		1	No	1/D				
1	1	Hallway leading into Boy's Locker Room	T	Pipe Fitting Insulation	6100/01/01/22	Confirmed	12	EA	0	EA		124, 125, 126 Locker Room Wing was renovated in the summer of 2016. All rooms require reinspection during the next 6 month surveillance.		1	No	1/D				
1	1	Hallway leading into Boy's Locker Room	T	Pipe Insulation 2-6 inch	6100/01/01/15	Confirmed	50	LF	0	LF		124, 125, 126 Locker Room Wing was renovated in the summer of 2016. All rooms require reinspection during the next 6 month surveillance.		1	No	1/D				

6100/6460 Hill Freedman World Academy @ Leeds Campus 2015 2016 AHERA Three-Year Report.xls

School District of Philadelphia Hill Freedman World Academy @ Leeds Campus 1100 E. Mount Pleasant Avenue, Philadelphia, PA, 19150 ULCS# 6100 Year Built: 1953			AHERA Three-Year Reinspection 2015-2016 Room by Room Location Log Report										Reinspection Date: October 30, 2015 Building Inspector: A. Roman Number: 150619008 Management Planner: Megan Vala Number: 740728							
Element	Floor	On Site Room Name	System Affected	Material Description	HID#	Confirmed/Assumed/NAD/ Non Suspect ACM	Amount of Material	SF LF EA	Amount of Damage	SF LF EA	Color required for VAT	Comments/Description/Notes	Attic/ Crawl Space Ranking	Damage Potential (DP)	Newly Friable (NF)	Response Action (RA)				
1	1	Hallway leading into Boy's Locker Room	N/A	Plaster Ceiling		NAD	240	SF	0	SF		124, 125, 126 Locker Room Wing was renovated in the summer of 2016. All rooms require reinspection during the next 6 month surveillance.		N/A	N/A	N/A				
1	1	Hallway leading into Boy's Locker Room	N/A	Cement Floor		Non Suspect ACM	240	SF	0	SF		124, 125, 126 Locker Room Wing was renovated in the summer of 2016. All rooms require reinspection during the next 6 month surveillance.		N/A	N/A	N/A				
1	1	Hallway leading into Boy's Locker Room	N/A	Ceramic Tile Walls		Non Suspect ACM	600	SF	0	SF		124, 125, 126 Locker Room Wing was renovated in the summer of 2016. All rooms require reinspection during the next 6 month surveillance.		N/A	N/A	N/A				
1	1	Former Boy's Locker Room	T	Pipe Fitting Insulation	6100/01/01/22	Confirmed	2	EA	0	EA		124, 125, 126 Locker Room Wing was renovated in the summer of 2016. All rooms require reinspection during the next 6 month surveillance.		1	No	1/D				
1	1	Former Boy's Locker Room	T	Pipe Insulation 2-6 inch	6100/01/01/15	Confirmed	20	LF	0	LF		124, 125, 126 Locker Room Wing was renovated in the summer of 2016. All rooms require reinspection during the next 6 month surveillance.		1	No	1/D				
1	1	Former Boy's Locker Room	N/A	Concrete Ceiling		Non Suspect ACM	3000	SF	0	SF		124, 125, 126 Locker Room Wing was renovated in the summer of 2016. All rooms require reinspection during the next 6 month surveillance.		N/A	N/A	N/A				
1	1	Former Boy's Locker Room	N/A	Ceramic Tile Walls		Non Suspect ACM	5000	SF	0	SF		124, 125, 126 Locker Room Wing was renovated in the summer of 2016. All rooms require reinspection during the next 6 month surveillance.		N/A	N/A	N/A				
1	1	Former Boy's Locker Room	N/A	Cement Floor		Non Suspect ACM	3000	SF	0	SF		124, 125, 126 Locker Room Wing was renovated in the summer of 2016. All rooms require reinspection during the next 6 month surveillance.		N/A	N/A	N/A				
1	1	Former Boy's Locker Room - Restroom	N/A	Plaster Ceiling		NAD	400	SF	0	SF		124, 125, 126 Locker Room Wing was renovated in the summer of 2016. All rooms require reinspection during the next 6 month surveillance.		N/A	N/A	N/A				
1	1	Former Boy's Locker Room - Restroom	N/A	Ceramic Tile Walls		Non Suspect ACM	700	SF	0	SF		124, 125, 126 Locker Room Wing was renovated in the summer of 2016. All rooms require reinspection during the next 6 month surveillance.		N/A	N/A	N/A				
1	1	Former Boy's Locker Room - Restroom	N/A	Cement Floor		Non Suspect ACM	400	SF	0	SF		124, 125, 126 Locker Room Wing was renovated in the summer of 2016. All rooms require reinspection during the next 6 month surveillance.		N/A	N/A	N/A				
1	1	Former Boy's Locker Room - Restroom	T	Pipe Fitting Insulation	6100/01/01/22	Confirmed	6	EA	0	EA		124, 125, 126 Locker Room Wing was renovated in the summer of 2016. All rooms require reinspection during the next 6 month surveillance.		1	No	1/D				
1	1	Former Boy's Locker Room - Restroom	T	Pipe Insulation 2-6 inch	6100/01/01/15	Confirmed	20	SF	0	SF		124, 125, 126 Locker Room Wing was renovated in the summer of 2016. All rooms require reinspection during the next 6 month surveillance.		1	No	1/D				
1	1	Former Boy's Showers	N/A	Concrete Ceiling		Non Suspect ACM	800	SF	0	SF		124, 125, 126 Locker Room Wing was renovated in the summer of 2016. All rooms require reinspection during the next 6 month surveillance.		N/A	N/A	N/A				
1	1	Former Boy's Showers	N/A	Ceramic Tile Walls		Non Suspect ACM	1200	SF	0	SF		124, 125, 126 Locker Room Wing was renovated in the summer of 2016. All rooms require reinspection during the next 6 month surveillance.		N/A	N/A	N/A				
1	1	Former Boy's Showers	N/A	Cement Floor		Non Suspect ACM	800	SF	0	SF		124, 125, 126 Locker Room Wing was renovated in the summer of 2016. All rooms require reinspection during the next 6 month surveillance.		N/A	N/A	N/A				
1	1	Stairwell from the Boy's Former Locker Room to the Gym	N/A	Plaster Ceiling		NAD	200	SF	0	SF		124, 125, 126 Locker Room Wing was renovated in the summer of 2016. All rooms require reinspection during the next 6 month surveillance.		N/A	N/A	N/A				
1	1	Stairwell from the Boy's Former Locker Room to the Gym	N/A	Ceramic Tile Walls		Non Suspect ACM	500	SF	0	SF		124, 125, 126 Locker Room Wing was renovated in the summer of 2016. All rooms require reinspection during the next 6 month surveillance.		N/A	N/A	N/A				
1	1	Stairwell from the Boy's Former Locker Room to the Gym	N/A	Cement Floor		Non Suspect ACM	200	SF	0	SF		124, 125, 126 Locker Room Wing was renovated in the summer of 2016. All rooms require reinspection during the next 6 month surveillance.		N/A	N/A	N/A				
1	1	Stairwell from the Boy's Former Locker Room to the Gym	T	Pipe Fitting Insulation	6100/01/01/22	Confirmed	8	EA	0	EA		124, 125, 126 Locker Room Wing was renovated in the summer of 2016. All rooms require reinspection during the next 6 month surveillance.		1	No	1/D				
1	1	Stairwell from the Boy's Former Locker Room to the Gym	T	Pipe Insulation 2-6 inch	6100/01/01/15	Confirmed	65	LF	0	LF		124, 125, 126 Locker Room Wing was renovated in the summer of 2016. All rooms require reinspection during the next 6 month surveillance.		1	No	1/D				
1	1	Stairwell from the Boy's Former Locker Room to the Gym	T	Radiator Insulation	6100/01/01/SYN/BB/1600	Assumed	25	SF	0	SF		1 Recessed Radiator - 25 SF - 124, 125, 126 Locker Room Wing was renovated in the summer of 2016. All rooms require reinspection during the next 6 month surveillance.		1	No	1/D				
1	1	Stairwell from the Boy's Former Locker Room in the Back leading Outside to the Playing Fields	N/A	Cement Floor		Non Suspect ACM	150	SF	0	SF		124, 125, 126 Locker Room Wing was renovated in the summer of 2016. All rooms require reinspection during the next 6 month surveillance.		N/A	N/A	N/A				
1	1	Stairwell from the Boy's Former Locker Room in the Back leading Outside to the Playing Fields	N/A	Plaster Ceiling		NAD	200	SF	0	SF		124, 125, 126 Locker Room Wing was renovated in the summer of 2016. All rooms require reinspection during the next 6 month surveillance.		N/A	N/A	N/A				
1	1	Stairwell from the Boy's Former Locker Room in the Back leading Outside to the Playing Fields	N/A	CMU		Non Suspect ACM	300	SF	0	SF		124, 125, 126 Locker Room Wing was renovated in the summer of 2016. All rooms require reinspection during the next 6 month surveillance.		N/A	N/A	N/A				
1	1	Stairwell from the Boy's Former Locker Room in the Back leading Outside to the Playing Fields	T	Pipe Insulation 2-6 inch	6100/01/01/15	Confirmed	5	LF	0	LF		124, 125, 126 Locker Room Wing was renovated in the summer of 2016. All rooms require reinspection during the next 6 month surveillance.		1	No	1/D				
1	2	Gym to the Right/Southwest (Girl's side)	N/A	CMU		Non Suspect ACM	10000	SF	0	SF				N/A	N/A	N/A				
1	2	Gym to the Right/Southwest (Girl's side)	N/A	Concrete Ceiling		Non Suspect ACM	5000	SF	0	SF				N/A	N/A	N/A				
1	2	Gym to the Right/Southwest (Girl's side)	N/A	Wood Floor		Non Suspect ACM	5000	SF	0	SF				N/A	N/A	N/A				
1	2	Stairwell within the Right/West Gymnasium	T	Pipe Insulation 2-6 inch	6100/01/02/23	Confirmed	24	LF	0	LF				1	No	1/D				
1	2	Stairwell within the Right/West Gymnasium	T	Pipe Fitting Insulation	6100/01/02/29	Confirmed	4	EA	0	EA				1	No	1/D				
1	2	Stairwell within the Right/West Gymnasium	N/A	Plaster Ceiling		NAD	240	SF	0	SF				N/A	N/A	N/A				
1	2	Stairwell within the Right/West Gymnasium	N/A	Cement Floor		Non Suspect ACM	240	SF	0	SF				N/A	N/A	N/A				
1	2	Stairwell within the Right/West Gymnasium	T	Radiator Insulation	6100/01/02/SYN/BB/1600	Assumed	25	SF	0	SF		1 Recessed Radiator		1	No	1/D				
1	2	Stairwell within the Right/West Gymnasium	N/A	Ceramic Tile Walls		Non Suspect ACM	500	SF	0	SF				N/A	N/A	N/A				
1	2	Gym to the Right/West Gym Teacher's Office	T	Pipe Fitting Insulation	6100/01/02/29	Confirmed	3	EA	0	EA				1	No	1/D				
1	2	Gym to the Right/West Gym Teacher's Office	T	Pipe Insulation 2-6 inch	6100/01/02/23	Confirmed	10	LF	0	LF				1	No	1/D				
1	2	Gym to the Right/West Gym Teacher's Office	N/A	CMU		Non Suspect ACM	500	SF	0	SF				N/A	N/A	N/A				
1	2	Gym to the Right/West Gym Teacher's Office	N/A	Plaster Ceiling		NAD	200	SF	0	SF				N/A	N/A	N/A				
1	2	Gym to the Right/West Gym Teacher's Office	M	Floor Tile VAT 9" x 9"	6100/01/02/30	Confirmed	200	SF	0	SF	Green			1	No	1/D				
1	2	Gym to the Right/West Gym Teacher's Office Restroom	N/A	Plaster Ceiling		NAD	80	SF	0	SF				N/A	N/A	N/A				
1	2	Gym to the Right/West Gym Teacher's Office Restroom	N/A	CMU		Non Suspect ACM	200	SF	0	SF				N/A	N/A	N/A				
1	2	Gym to the Right/West Gym Teacher's Office Restroom	M	Floor Tile VAT 9" x 9"	6100/01/02/30	Confirmed	80	SF	0	SF	Black			1	No	1/D				
1	2	Gym to the Right/West Gym Teacher's Office Closet next to Restroom	N/A	Plaster Ceiling		NAD	80	SF	0	SF				N/A	N/A	N/A				
1	2	Gym to the Right/West Gym Teacher's Office Closet next to Restroom	N/A	CMU		Non Suspect ACM	150	SF	0	SF				N/A	N/A	N/A				
1	2	Gym to the Right/West Gym Teacher's Office Closet next to Restroom	M	Floor Tile VAT 9" x 9"	6100/01/02/30	Confirmed	80	SF	0	SF	Green			1	No	1/D				
1	2	Gym to the Right/West Gym Teacher's Office Closet next to Restroom	T	Pipe Fitting Insulation	6100/01/02/29	Confirmed	1	EA	0	EA				1	No	1/D				
1	2	Gym to the Right/West Gym Teacher's Office Closet next to Restroom	T	Pipe Insulation 2-6 inch	6100/01/02/23	Confirmed	16	LF	0	LF				1	No	1/D				
1	2	Gym to the Right/West Gym Teacher's Office Closet next to Restroom	T	Pipe Insulation > 6 inch	6100/01/02/25	Confirmed	12	LF	0	LF				1	No	1/D				
1	2	Gym to the Right/West Gym Teacher's Office Closet along the west wall	T	Pipe Insulation 2-6 inch	6100/01/02/23	Confirmed	5	LF	0	LF				1	No	1/D				

6100/6460 Hill Freedman World Academy @ Leeds Campus 2015 2016 AHERA Three-Year Report.xls

School District of Philadelphia Hill Freedman World Academy @ Leeds Campus 1100 E. Mount Pleasant Avenue, Philadelphia, PA, 19150 ULCS# 6100 Year Built: 1953			AHERA Three-Year Reinspection 2015-2016 Room by Room Location Log Report										Reinspection Date: October 30, 2015 Building Inspector: A. Roman Number: 150619008 Management Planner: Megan Vala Number: 740728							
Element	Floor	On Site Room Name	System Affected	Material Description	HID#	Confirmed/Assumed/NAD/ Non Suspect ACM	Amount of Material	SF LF EA	Amount of Damage	SF LF EA	Color required for VAT	Comments/Description/Notes	Attic/ Crawl Space Ranking	Damage Potential (DP)	Newly Friable (NF)	Response Action (RA)				
1	2	Gym to the Right/West Gym Teacher's Office Closet along the west wall	N/A	Plaster Ceiling		NAD	80	SF	0	SF				N/A	N/A	N/A				
1	2	Gym to the Right/West Gym Teacher's Office Closet along the west wall	N/A	CMU		Non Suspect ACM	150	SF	0	SF				N/A	N/A	N/A				
1	2	Gym to the Right/West Gym Teacher's Office Closet along the west wall	M	Floor Tile VAT 9" x 9"	6100/01/02/30	Confirmed	80	SF	0	SF	Black			1	No	1/D				
1	2	Gym to the Right/West - Storage Closet	T	Pipe Fitting Insulation	6100/01/02/29	Confirmed	1	EA	0	EA				1	No	1/D				
1	2	Gym to the Right/West - Storage Closet	T	Pipe Insulation 2-6 inch	6100/01/02/23	Confirmed	3	LF	0	LF				1	No	1/D				
1	2	Gym to the Right/West - Storage Closet	N/A	Plaster Ceiling		NAD	400	SF	0	SF				N/A	N/A	N/A				
1	2	Gym to the Right/West - Storage Closet	N/A	CMU		Non Suspect ACM	700	SF	0	SF				N/A	N/A	N/A				
1	2	Gym to the Right/West - Storage Closet	M	Floor Tile VAT 9" x 9"	6100/01/02/30	Confirmed	400	SF	0	SF	Black			1	No	1/D				
1	2	Gym to the Left/Southeast (Boy's side)	N/A	Plaster Ceiling		NAD	5000	SF	0	SF				N/A	N/A	N/A				
1	2	Gym to the Left/Southeast (Boy's side)	N/A	CMU		Non Suspect ACM	10000	SF	0	SF				N/A	N/A	N/A				
1	2	Gym to the Left/Southeast (Boy's side)	N/A	Wood Floor		Non Suspect ACM	5000	SF	0	SF				N/A	N/A	N/A				
1	2	Stairwell within the Left/East Gymnasium	N/A	Plaster Ceiling		NAD	240	SF	0	SF				N/A	N/A	N/A				
1	2	Stairwell within the Left/East Gymnasium	N/A	Cement Floor		Non Suspect ACM	240	SF	0	SF				N/A	N/A	N/A				
1	2	Stairwell within the Left/East Gymnasium	N/A	Ceramic Tile Walls		Non Suspect ACM	500	SF	0	SF				N/A	N/A	N/A				
1	2	Stairwell within the Left/East Gymnasium	T	Radiator Insulation	6100/01/02/SYN/BB/1600	Assumed	25	SF	0	SF		1 Recessed Radiator		1	No	1/D				
1	2	Weight Room next to Gym to the Left	N/A	Plaster Ceiling		NAD	500	SF	0	SF				N/A	N/A	N/A				
1	2	Weight Room next to Gym to the Left	N/A	CMU		Non Suspect ACM	800	SF	0	SF				N/A	N/A	N/A				
1	2	Weight Room next to Gym to the Left	M	Floor Tile VAT 9" x 9"	6100/01/02/30	Confirmed	500	SF	0	SF	Green			1	No	1/D				
1	2	Left Closet in Weight Room next to Gym to the Left	M	Floor Tile VAT 9" x 9"	6100/01/02/30	Confirmed	15	SF	0	SF	Green			1	No	1/D				
1	2	Left Closet in Weight Room next to Gym to the Left	N/A	Concrete Block Wall		Non Suspect ACM	60	SF	0	SF				N/A	N/A	N/A				
1	2	Left Closet in Weight Room next to Gym to the Left	N/A	Concrete Ceiling		Non Suspect ACM	16	SF	0	SF				N/A	N/A	N/A				
1	2	Left Closet in Weight Room next to Gym to the Left	T	Pipe Insulation 2-6 inch	6100/01/02/23	Confirmed	5	LF	1	LF		<1 LF of Compressed Paper Pipe Insulation Damaged/Hanging - DDC Required for Repair		2	Yes	5/B				
1	2	Right Closet in Weight Room next to Gym to the Left	M	Floor Tile VAT 9" x 9"	6100/01/02/30	Confirmed	30	SF	0	SF	Black			1	No	1/D				
1	2	Right Closet in Weight Room next to Gym to the Left	N/A	Concrete Block Wall		Non Suspect ACM	120	SF	0	SF				N/A	N/A	N/A				
1	2	Right Closet in Weight Room next to Gym to the Left	N/A	Concrete Ceiling		Non Suspect ACM	30	SF	0	SF				N/A	N/A	N/A				
1	2	Right Closet in Weight Room next to Gym to the Left	T	Pipe Insulation 2-6 inch	6100/01/02/23	Confirmed	24	LF	1	LF		<1 LF of Compressed Paper Pipe Insulation Damaged/Hanging - DDC Required for Repair		2	Yes	5/B				
1	2	Right Closet in Weight Room next to Gym to the Left	T	Pipe Fitting Insulation	6100/01/02/29	Confirmed	4	EA	0	EA				1	No	1/D				
1	2	Gym to the Left/East Gym Teacher's Office Closet next to Restroom	X	X		X	X	X	X	X		No access		X	X	X				
1	2	Gym to the Left/East Gym Teacher's Office Restroom closest to the Office Entrance to the Main Hallway	N/A	Plaster Ceiling		NAD	80	SF	0	SF				N/A	N/A	N/A				
1	2	Gym to the Left/East Gym Teacher's Office Restroom closest to the Office Entrance to the Main Hallway	N/A	CMU		Non Suspect ACM	150	SF	0	SF				N/A	N/A	N/A				
1	2	Gym to the Left/East Gym Teacher's Office Restroom closest to the Office Entrance to the Main Hallway	M	Floor Tile VAT 9" x 9"	6100/01/02/30	Confirmed	80	SF	0	SF	Green			1	No	1/D				
1	2	Gym to the Left/East Equipment Closet	M	Floor Tile VAT 9" x 9"	6100/01/02/30	Confirmed	230	SF	0	SF	Black			1	No	1/D				
1	2	Gym to the Left/East Equipment Closet	N/A	Concrete Block Wall		Non Suspect ACM	700	SF	0	SF				N/A	N/A	N/A				
1	2	Gym to the Left/East Equipment Closet	N/A	Concrete Ceiling		Non Suspect ACM	230	SF	0	SF				N/A	N/A	N/A				
1	2	Gym to the Left/East Equipment Closet	T	Pipe Insulation 2-6 inch	6100/01/02/23	Confirmed	75	LF	0	LF				1	No	1/D				
1	2	Gym to the Left/East Equipment Closet	T	Pipe Fitting Insulation	6100/01/02/29	Confirmed	15	EA	0	EA				1	No	1/D				
1	2	Hallway Running East to West at the Gymnasium Entrances	N/A	Plaster Ceiling		NAD	600	SF	0	SF				N/A	N/A	N/A				
1	2	Hallway Running East to West at the Gymnasium Entrances	N/A	CMU		Non Suspect ACM	800	SF	0	SF				N/A	N/A	N/A				
1	2	Hallway Running East to West at the Gymnasium Entrances	M	Floor Tile VAT 9" x 9"	6100/01/02/30	Confirmed	600	SF	0	SF	Green			1	No	1/D				
1	2	Stairwell along Classroom 222	N/A	Plaster Ceiling		NAD	240	SF	0	SF				N/A	N/A	N/A				
1	2	Stairwell along Classroom 222	N/A	Cement Floor		Non Suspect ACM	240	SF	0	SF				N/A	N/A	N/A				
1	2	Stairwell along Classroom 222	N/A	Ceramic Tile Walls		Non Suspect ACM	500	SF	0	SF				N/A	N/A	N/A				
1	2	Stairwell along Classroom 222	T	Radiator Insulation	6100/01/02/SYN/BB/1600	Assumed	25	SF	0	SF		1 Recessed Radiator		1	No	1/D				
1	2	Stairwell along Counselor's Office 223	N/A	Plaster Ceiling		NAD	240	SF	0	SF				N/A	N/A	N/A				
1	2	Stairwell along Counselor's Office 223	N/A	Cement Floor		Non Suspect ACM	240	SF	0	SF				N/A	N/A	N/A				
1	2	Stairwell along Counselor's Office 223	N/A	Ceramic Tile Walls		Non Suspect ACM	500	SF	0	SF				N/A	N/A	N/A				
1	2	Stairwell along Counselor's Office 223	T	Radiator Insulation	6100/01/02/SYN/BB/1600	Assumed	25	SF	0	SF		1 Recessed Radiator		1	No	1/D				
1	2	Counselor's Office 223	N/A	Plaster Ceiling		NAD	600	SF	0	SF				N/A	N/A	N/A				
1	2	Counselor's Office 223	N/A	CMU		Non Suspect ACM	900	SF	0	SF				N/A	N/A	N/A				
1	2	Counselor's Office 223	M	Floor Tile VAT 9" x 9"	6100/01/02/30	Confirmed	600	SF	0	SF	Black			1	No	1/D				
1	2	Counselor's Office 223	M	Vibration Damper Cloth	6100/01/02/27	Assumed	2	EA	0	EA				1	No	1/D				
1	2	Girl's Restroom next to Counselor's Office 223	M	Transite Stalls	6100/01/02/28	Confirmed	5	EA	0	EA		Small holes only; no debris observed		1	No	1/D				
1	2	Girl's Restroom next to Counselor's Office 223	T	Pipe Fitting Insulation	6100/01/02/29	Confirmed	4	EA	0	EA				1	No	1/D				
1	2	Girl's Restroom next to Counselor's Office 223	T	Pipe Insulation 2-6 inch	6100/01/02/23	Confirmed	16	LF	0	LF				1	No	1/D				
1	2	Girl's Restroom next to Counselor's Office 223	N/A	Plaster Ceiling		NAD	200	SF	0	SF				N/A	N/A	N/A				
1	2	Girl's Restroom next to Counselor's Office 223	N/A	Ceramic Tile Walls		Non Suspect ACM	400	SF	0	SF				N/A	N/A	N/A				
1	2	Girl's Restroom next to Counselor's Office 223	N/A	Cement Floor		Non Suspect ACM	200	SF	0	SF				N/A	N/A	N/A				
1	2	Classroom 222	N/A	Plaster Ceiling		NAD	800	SF	0	SF				N/A	N/A	N/A				
1	2	Classroom 222	N/A	CMU		Non Suspect ACM	1200	SF	0	SF				N/A	N/A	N/A				
1	2	Classroom 222	M	Floor Tile VAT 9" x 9"	6100/01/02/30	Confirmed	800	SF	0	SF	Tan			1	No	1/D				
1	2	Classroom 220	N/A	Plaster Ceiling		NAD	800	SF	0	SF				N/A	N/A	N/A				
1	2	Classroom 220	N/A	CMU		Non Suspect ACM	1200	SF	0	SF				N/A	N/A	N/A				
1	2	Classroom 220	M	Floor Tile VAT 9" x 9"	6100/01/02/30	Confirmed	800	SF	0	SF	Tan			1	No	1/D				
1	2	Classroom 220	M	Blackboard Glue Dots	6100/01/02/VER/AR/2600	Assumed	10	SF	0	SF				1	No	1/D				
1	2	Classroom 221	N/A	Plaster Ceiling		NAD	800	SF	0	SF				N/A	N/A	N/A				
1	2	Classroom 221	N/A	CMU		Non Suspect ACM	1200	SF	0	SF				N/A	N/A	N/A				
1	2	Classroom 221	M	Floor Tile VAT 9" x 9"	6100/01/02/30	Confirmed	800	SF	0	SF	Green			1	No	1/D				
1	2	Classroom 221	M	Blackboard Glue Dots	6100/01/02/VER/AR/2600	Assumed	10	SF	0	SF				1	No	1/D				
1	2	Classroom 221 Storage Closet	M	Floor Tile VAT 9" x 9"	6100/01/02/30	Confirmed	36	SF	0	SF	Green	Potential for additional pipe insulation in pipe chase adjoined to the closet		1	No	1/D				
1	2	Classroom 221 Storage Closet	N/A	Plaster Ceiling		NAD	36	SF	0	SF				N/A	N/A	N/A				
1	2	Classroom 221 Storage Closet	N/A	CMU		Non Suspect ACM	150	SF	0	SF				N/A	N/A	N/A				
1	2	Classroom 219	N/A	Plaster Ceiling		NAD	800	SF	0	SF				N/A	N/A	N/A				

6100/6460 Hill Freedman World Academy @ Leeds Campus 2015 2016 AHERA Three-Year Report.xls

School District of Philadelphia Hill Freedman World Academy @ Leeds Campus 1100 E. Mount Pleasant Avenue, Philadelphia, PA, 19150 ULCS# 6100 Year Built: 1953			AHERA Three-Year Reinspection 2015-2016 Room by Room Location Log Report										Reinspection Date: October 30, 2015 Building Inspector: A. Roman Number: 150619008 Management Planner: Megan Vala Number: 740728			Attic/ Crawl Space Ranking	Damage Potential (DP)	Newly Friable (NF)	Response Action (RA)
Element	Photo	On Site Room Name	System Affected	Material Description	HID#	Confirmed/Assumed/NAD/ Non Suspect ACM	Amount of Material	SF LF EA	Amount of Damage	SF LF EA	Color required for VAT	Comments/Description/Notes							
1	2	Classroom 219	N/A	CMU		Non Suspect ACM	1200	SF	0	SF						N/A	N/A	N/A	
1	2	Classroom 219	M	Floor Tile VAT 9" x 9"	6100/01/02/30	Confirmed	800	SF	0	SF	Tan					1	No	1/D	
1	2	Classroom 219	M	Blackboard Glue Dots	6100/01/02/VER/AR/2600	Assumed	10	SF	0	SF						1	No	1/D	
1	2	Classroom 218	N/A	Plaster Ceiling		NAD	800	SF	0	SF						N/A	N/A	N/A	
1	2	Classroom 218	N/A	CMU		Non Suspect ACM	1200	SF	0	SF						N/A	N/A	N/A	
1	2	Classroom 218	M	Floor Tile VAT 9" x 9"	6100/01/02/30	Confirmed	800	SF	0	SF	Tan					1	No	1/D	
1	2	Classroom 218 Closet	N/A	Plaster Ceiling		NAD	50	SF	0	SF						N/A	N/A	N/A	
1	2	Classroom 218 Closet	N/A	CMU		Non Suspect ACM	150	SF	0	SF						N/A	N/A	N/A	
1	2	Classroom 218 Closet	M	Floor Tile VAT 9" x 9"	6100/01/02/30	Confirmed	50	SF	0	SF	Tan					1	No	1/D	
1	2	Classroom 216	N/A	Plaster Ceiling		NAD	800	SF	0	SF						N/A	N/A	N/A	
1	2	Classroom 216	N/A	CMU		Non Suspect ACM	1200	SF	0	SF						N/A	N/A	N/A	
1	2	Classroom 216	M	Floor Tile VAT 9" x 9"	6100/01/02/30	Confirmed	800	SF	0	SF	Unknown					1	No	1/D	
1	2	Classroom 216	M	Blackboard Glue Dots	6100/01/02/VER/AR/2600	Assumed	10	SF	0	SF						1	No	1/D	
1	2	Classroom 217	N/A	Plaster Ceiling		NAD	800	SF	0	SF						N/A	N/A	N/A	
1	2	Classroom 217	N/A	CMU		Non Suspect ACM	1200	SF	0	SF						N/A	N/A	N/A	
1	2	Classroom 217	M	Floor Tile VAT 9" x 9"	6100/01/02/30	Confirmed	800	SF	0	SF	Tan					1	No	1/D	
1	2	Classroom 217	M	Blackboard Glue Dots	6100/01/02/VER/AR/2600	Assumed	10	SF	0	SF						1	No	1/D	
1	2	Classroom 217 Closet	N/A	Plaster Ceiling		NAD	50	SF	0	SF						N/A	N/A	N/A	
1	2	Classroom 217 Closet	N/A	CMU		Non Suspect ACM	150	SF	0	SF						N/A	N/A	N/A	
1	2	Classroom 217 Closet	M	Floor Tile VAT 9" x 9"	6100/01/02/30	Confirmed	50	SF	0	SF	Tan					1	No	1/D	
1	2	Classroom 215	N/A	Plaster Ceiling		NAD	800	SF	0	SF						N/A	N/A	N/A	
1	2	Classroom 215	N/A	CMU		Non Suspect ACM	1200	SF	0	SF						N/A	N/A	N/A	
1	2	Classroom 215	M	Floor Tile VAT 9" x 9"	6100/01/02/30	Confirmed	800	SF	0	SF	Tan					1	No	1/D	
1	2	Classroom 215	M	Blackboard Glue Dots	6100/01/02/VER/AR/2600	Assumed	10	SF	0	SF						1	No	1/D	
1	2	Custodial Closet across the Hall from Classroom 215	T	Pipe Fitting Insulation	6100/01/02/29	Confirmed	1	EA	0	EA						1	No	1/D	
1	2	Custodial Closet across the Hall from Classroom 215	T	Pipe Insulation 2-6 inch	6100/01/02/23	Confirmed	3	LF	0	LF						1	No	1/D	
1	2	Custodial Closet across the Hall from Classroom 215	N/A	Plaster Ceiling		NAD	50	SF	0	SF						N/A	N/A	N/A	
1	2	Custodial Closet across the Hall from Classroom 215	N/A	Cement Floor		Non Suspect ACM	50	SF	0	SF						N/A	N/A	N/A	
1	2	Custodial Closet across the Hall from Classroom 215	N/A	CMU		Non Suspect ACM	150	SF	0	SF						N/A	N/A	N/A	
1	2	Custodial Closet across the Hall from Classroom 215	M	Vibration Damper Cloth	6100/01/02/27	Assumed	2	EA	0	EA						1	No	1/D	
1	2	Stairwell between Classrooms 213 and 215	N/A	Plaster Ceiling		NAD	240	SF	0	SF						N/A	N/A	N/A	
1	2	Stairwell between Classrooms 213 and 215	N/A	Cement Floor		Non Suspect ACM	240	SF	0	SF						N/A	N/A	N/A	
1	2	Stairwell between Classrooms 213 and 215	N/A	Ceramic Tile Walls		Non Suspect ACM	500	SF	0	SF						N/A	N/A	N/A	
1	2	Stairwell between Classrooms 213 and 215	T	Radiator Insulation	6100/01/02/SYN/BB/1600	Assumed	25	SF	0	SF		1 Recessed Radiator				1	No	1/D	
1	2	Classroom 214	M	Floor Tile VAT 9" x 9"	6100/01/02/30	Confirmed	800	SF	0	SF	Tan					1	No	1/D	
1	2	Classroom 214	N/A	Plaster Ceiling		NAD	800	SF	0	SF						N/A	N/A	N/A	
1	2	Classroom 214	N/A	CMU		Non Suspect ACM	1200	SF	0	SF						N/A	N/A	N/A	
1	2	Classroom 214	M	Blackboard Glue Dots	6100/01/02/VER/AR/2600	Assumed	10	SF	0	SF						1	No	1/D	
1	2	Men's Restroom next to the South of Classroom 214	T	Pipe Insulation 2-6 inch	6100/01/02/23	Confirmed	21	LF	0	LF						1	No	1/D	
1	2	Men's Restroom next to the South of Classroom 214	N/A	Plaster Ceiling		NAD	200	SF	0	SF						N/A	N/A	N/A	
1	2	Men's Restroom next to the South of Classroom 214	N/A	Ceramic Tile Walls		Non Suspect ACM	500	SF	0	SF						N/A	N/A	N/A	
1	2	Men's Restroom next to the South of Classroom 214	M	Transite Stalls	6100/01/02/28	Confirmed	1	EA	0	EA						1	No	1/D	
1	2	Men's Restroom next to the South of Classroom 214	N/A	Cement Floor		Non Suspect ACM	200	SF	0	SF						N/A	N/A	N/A	
1	2	Classroom 213	N/A	Plaster Ceiling		NAD	800	SF	0	SF						N/A	N/A	N/A	
1	2	Classroom 213	N/A	CMU		Non Suspect ACM	1200	SF	0	SF						N/A	N/A	N/A	
1	2	Classroom 213	M	Floor Tile VAT 9" x 9"	6100/01/02/30	Confirmed	800	SF	0	SF	Tan					1	No	1/D	
1	2	Classroom 210	N/A	Plaster Ceiling		NAD	800	SF	0	SF						N/A	N/A	N/A	
1	2	Classroom 210	N/A	CMU		Non Suspect ACM	1200	SF	0	SF						N/A	N/A	N/A	
1	2	Classroom 210	M	Floor Tile VAT 9" x 9"	6100/01/02/30	Confirmed	800	SF	0	SF	Tan					1	No	1/D	
1	2	Classroom 209	N/A	Plaster Ceiling		NAD	800	SF	0	SF						N/A	N/A	N/A	
1	2	Classroom 209	N/A	CMU		Non Suspect ACM	1200	SF	0	SF						N/A	N/A	N/A	
1	2	Classroom 209	M	Floor Tile VAT 9" x 9"	6100/01/02/30	Confirmed	800	SF	0	SF	Tan					1	No	1/D	
1	2	Classroom 211	M	Floor Tile VAT 9" x 9"	6100/01/02/30	Confirmed	800	SF	0	SF	Tan					1	No	1/D	
1	2	Classroom 211	N/A	Plaster Ceiling		NAD	800	SF	0	SF						N/A	N/A	N/A	
1	2	Classroom 211	N/A	CMU		Non Suspect ACM	1200	SF	0	SF						N/A	N/A	N/A	
1	2	Roster Office	N/A	Plaster Ceiling		NAD	500	SF	0	SF						N/A	N/A	N/A	
1	2	Roster Office	N/A	CMU		Non Suspect ACM	800	SF	0	SF						N/A	N/A	N/A	
1	2	Roster Office	M	Floor Tile VAT 9" x 9"	6100/01/02/30	Confirmed	500	SF	0	SF	Green					1	No	1/D	
1	2	Room 211A - Roster Office	N/A	Plaster Ceiling		NAD	400	SF	0	SF						N/A	N/A	N/A	
1	2	Room 211A - Roster Office	N/A	CMU		Non Suspect ACM	800	SF	0	SF						N/A	N/A	N/A	
1	2	Room 211A - Roster Office	M	Floor Tile VAT 9" x 9"	6100/01/02/30	Confirmed	400	SF	0	SF	Tan					1	No	1/D	
1	2	Room 211A - Roster Office Restroom	M	Floor Tile VAT 9" x 9"	6100/01/02/30	Confirmed	100	SF	0	SF	Tan					1	No	1/D	
1	2	Room 211A - Roster Office Restroom	N/A	CMU		Non Suspect ACM	200	SF	0	SF						N/A	N/A	N/A	
1	2	Room 211A - Roster Office Restroom	N/A	Plaster Ceiling		NAD	100	SF	0	SF						N/A	N/A	N/A	
1	2	Room 211A - Roster Office Restroom	M	Transite Stalls	6100/01/02/28	Confirmed	40	SF	0	SF						1	No	1/D	
1	2	Room 211A - Roster Office Restroom	N/A	Plaster Ceiling		NAD	48	SF	0	SF						N/A	N/A	N/A	
1	2	Room 211A - Roster Office Restroom	N/A	CMU		Non Suspect ACM	150	SF	0	SF						N/A	N/A	N/A	
1	2	Room 211A - Roster Office Restroom	M	Floor Tile VAT 9" x 9"	6100/01/02/30	Confirmed	48	SF	0	SF	Tan					1	No	1/D	
1	2	Teacher's Lounge 208	M	Floor Tile VAT 9" x 9"	6100/01/02/30	Confirmed	800	SF	0	SF	Tan					1	No	1/D	
1	2	Teacher's Lounge 208	N/A	Plaster Ceiling		NAD	800	SF	0	SF						N/A	N/A	N/A	
1	2	Teacher's Lounge 208	N/A	CMU		Non Suspect ACM	1200	SF	0	SF						N/A	N/A	N/A	
1	2	Girls Restroom across from Teacher's Lounge 208	N/A	Plaster Ceiling		NAD	240	SF	0	SF	x					N/A	N/A	N/A	
1	2	Girls Restroom across from Teacher's Lounge 208	N/A	Ceramic Tile Walls		Non Suspect ACM	500	SF	0	SF						N/A	N/A	N/A	
1	2	Girls Restroom across from Teacher's Lounge 208	N/A	Cement Floor		Non Suspect ACM	240	SF	0	SF						N/A	N/A	N/A	
1	2	Girls Restroom across from Teacher's Lounge 208	T	Pipe Fitting Insulation	6100/01/02/29	Confirmed	2	EA	0	EA						1	No	1/D	
1	2	Girls Restroom across from Teacher's Lounge 208	T	Pipe Insulation 2-6 inch	6100/01/02/23	Confirmed	15	LF	0	LF						1	No	1/D	
1	2	Storage across the Hall from Teacher's Lounge 208 and next to Girl's Restroom	T	Pipe Fitting Insulation	6100/01/02/29	Confirmed	17	EA	0	EA		Outer Lagging is beginning to delaminate				1	No	1/D	
1	2	Storage across the Hall from Teacher's Lounge 208 and next to Girl's Restroom	T	Pipe Insulation 2-6 inch	6100/01/02/23	Confirmed	50	LF	0	LF		Outer Lagging is beginning to delaminate				1	No	1/D	

6100/6460 Hill Freedman World Academy @ Leeds Campus 2015 2016 AHERA Three-Year Report.xls

School District of Philadelphia Hill Freedman World Academy @ Leeds Campus 1100 E. Mount Pleasant Avenue, Philadelphia, PA, 19150 ULCS# 6100 Year Built: 1953			AHERA Three-Year Reinspection 2015-2016 Room by Room Location Log Report										Reinspection Date: October 30, 2015 Building Inspector: A. Roman Number: 150619008 Management Planner: Megan Vala Number: 740728			
E l e m e n t	F l o o r	On Site Room Name	System Affected	Material Description	HID#	Confirmed/Assumed/NAD/ Non Suspect ACM	Amount of Material	SF LF EA	Amount of Damage	SF LF EA	Color required for VAT	Comments/Description/Notes	Attic/ Crawl Space Ranking	Damage Potential (DP)	Newly Friable (NF)	Response Action (RA)
1	2	Storage across the Hall from Teacher's Lounge 208 and next to Girl's Restroom	N/A	Plaster Ceiling		NAD	48	SF	0	SF				N/A	N/A	N/A
1	2	Storage across the Hall from Teacher's Lounge 208 and next to Girl's Restroom	N/A	CMU		Non Suspect ACM	150	SF	0	SF				N/A	N/A	N/A
1	2	Storage across the Hall from Teacher's Lounge 208 and next to Girl's Restroom	N/A	Cement Floor		Non Suspect ACM	48	SF	0	SF				N/A	N/A	N/A
1	2	Storage across the Hall from Teacher's Lounge 208 and next to Girl's Restroom	M	Vibration Damper Cloth	6100/01/02/27	Assumed	7	EA	0	EA				1	No	1/D
1	2	Hallway from Teacher's Lounge 208 to Classroom 222	N/A	Plaster Ceiling		NAD	2500	SF	0	SF		Includes H24		N/A	N/A	N/A
1	2	Hallway from Teacher's Lounge 208 to Classroom 222	N/A	CMU		Non Suspect ACM	5000	SF	0	SF		Includes H24		N/A	N/A	N/A
1	2	Hallway from Teacher's Lounge 208 to Classroom 222	M	Floor Tile VAT 9" x 9"	6100/01/02/30	Confirmed	2500	SF	0	SF	Green	Includes H24		1	No	1/D
1	2	Stairwell closest to Teacher's Lounge 208	N/A	Plaster Ceiling		NAD	240	SF	0	SF				N/A	N/A	N/A
1	2	Stairwell closest to Teacher's Lounge 208	N/A	Cement Floor		Non Suspect ACM	240	SF	0	SF				N/A	N/A	N/A
1	2	Stairwell closest to Teacher's Lounge 208	N/A	Ceramic Tile Walls		Non Suspect ACM	500	SF	0	SF				N/A	N/A	N/A
1	2	Stairwell closest to Teacher's Lounge 208	T	Radiator Insulation	6100/01/02/SYN/BB/1600	Assumed	25	SF	0	SF		1 Recessed Radiator		1	No	1/D
1	2	Hallway between Teacher's Lounge 208 and the Principal's Office	T	Pipe Fitting Insulation	6100/01/02/29	Confirmed	14	EA	0	EA				1	No	1/D
1	2	Hallway between Teacher's Lounge 208 and the Principal's Office	T	Pipe Insulation 2-6 inch	6100/01/02/23	Confirmed	40	LF	0	LF				1	No	1/D
1	2	Hallway between Teacher's Lounge 208 and the Principal's Office	N/A	Plaster Ceiling		NAD	800	SF	0	SF				N/A	N/A	N/A
1	2	Hallway between Teacher's Lounge 208 and the Principal's Office	N/A	CMU		Non Suspect ACM	1200	SF	0	SF				N/A	N/A	N/A
1	2	Hallway between Teacher's Lounge 208 and the Principal's Office	M	Floor Tile VAT 12" x 12"	6100/01/02/30	Assumed	800	SF	0	SF	White			1	No	1/D
1	2	Custodial Closet next to Boy's Restroom near the Principal's Office	T	Pipe Insulation 2-6 inch	6100/01/02/23	Confirmed	45	LF	0	LF				1	No	1/D
1	2	Custodial Closet next to Boy's Restroom near the Principal's Office	T	Pipe Fitting Insulation	6100/01/02/29	Confirmed	13	EA	0	EA				1	No	1/D
1	2	Custodial Closet next to Boy's Restroom near the Principal's Office	N/A	Plaster Ceiling		NAD	48	SF	0	SF				N/A	N/A	N/A
1	2	Custodial Closet next to Boy's Restroom near the Principal's Office	N/A	CMU		Non Suspect ACM	150	SF	0	SF				N/A	N/A	N/A
1	2	Custodial Closet next to Boy's Restroom near the Principal's Office	N/A	Cement Floor		Non Suspect ACM	48	SF	0	SF				N/A	N/A	N/A
1	2	Custodial Closet next to Boy's Restroom near the Principal's Office	M	Vibration Damper Cloth	6100/01/02/27	Assumed	1	EA	0	EA				1	No	1/D
1	2	Boy's Restroom next to Principal's Office	T	Pipe Fitting Insulation	6100/01/02/29	Confirmed	2	EA	0	EA				1	No	1/D
1	2	Boy's Restroom next to Principal's Office	T	Pipe Insulation 2-6 inch	6100/01/02/23	Confirmed	10	LF	0	LF				1	No	1/D
1	2	Boy's Restroom next to Principal's Office	N/A	Plaster Ceiling		NAD	240	SF	0	SF				N/A	N/A	N/A
1	2	Boy's Restroom next to Principal's Office	N/A	Cement Floor		Non Suspect ACM	240	SF	0	SF				N/A	N/A	N/A
1	2	Boy's Restroom next to Principal's Office	N/A	Ceramic Tile Walls		Non Suspect ACM	500	SF	0	SF				N/A	N/A	N/A
1	2	Library Storage closest to Boy's Restroom	N/A	Plaster Ceiling		NAD	200	SF	0	SF				N/A	N/A	N/A
1	2	Library Storage closest to Boy's Restroom	N/A	CMU		Non Suspect ACM	500	SF	0	SF				N/A	N/A	N/A
1	2	Library Storage closest to Boy's Restroom	M	Floor Tile VAT 9" x 9"	6100/01/02/30	Confirmed	200	SF	0	SF	Tan			1	No	1/D
1	2	Library Storage in 2nd Floor Library	T	Pipe Fitting Insulation	6100/01/02/29	Confirmed	3	EA	0	EA				1	No	1/D
1	2	Library Storage in 2nd Floor Library	T	Pipe Insulation 2-6 inch	6100/01/02/23	Confirmed	15	LF	0	LF				1	No	1/D
1	2	Library Storage in 2nd Floor Library	N/A	Plaster Ceiling		NAD	500	SF	0	SF				N/A	N/A	N/A
1	2	Library Storage in 2nd Floor Library	N/A	CMU		Non Suspect ACM	800	SF	0	SF				N/A	N/A	N/A
1	2	Library Storage in 2nd Floor Library	M	Floor Tile VAT 9" x 9"	6100/01/02/30	Confirmed	500	SF	0	SF	Tan			1	No	1/D
1	2	2nd Floor Library	N/A	Ceiling Tile 2' x 4'	6100/01/02/30	Confirmed	500	SF	0	SF				1	No	1/D
1	2	2nd Floor Library	N/A	CMU		Non Suspect ACM	900	SF	0	SF				N/A	N/A	N/A
1	2	2nd Floor Library	N/A	CMU		Non Suspect ACM	1200	SF	0	SF				N/A	N/A	N/A
1	2	2nd Floor Library	M	Floor Tile VAT 9" x 9"	6100/01/02/30	Confirmed	900	SF	0	SF	Tan			1	No	1/D
1	2	Stairwell across from the 2nd Floor Library	N/A	Plaster Ceiling		NAD	240	SF	0	SF				N/A	N/A	N/A
1	2	Stairwell across from the 2nd Floor Library	N/A	Cement Floor		Non Suspect ACM	240	SF	0	SF				N/A	N/A	N/A
1	2	Stairwell across from the 2nd Floor Library	N/A	Ceramic Tile Walls		Non Suspect ACM	500	SF	0	SF				N/A	N/A	N/A
1	2	Stairwell across from the 2nd Floor Library	T	Radiator Insulation	6100/01/02/SYN/BB/1600	Assumed	25	SF	0	SF		1 Recessed Radiator		1	No	1/D
1	2	Hallway from Main Hallway to the Library	T	Pipe Fitting Insulation	6100/01/02/29	Confirmed	6	EA	0	EA				1	No	1/D
1	2	Hallway from Main Hallway to the Library	T	Pipe Insulation 2-6 inch	6100/01/02/23	Confirmed	25	LF	0	LF				1	No	1/D
1	2	Hallway from Main Hallway to the Library	N/A	Plaster Ceiling		NAD	800	SF	0	SF				N/A	N/A	N/A
1	2	Hallway from Main Hallway to the Library	N/A	CMU		Non Suspect ACM	1200	SF	0	SF				N/A	N/A	N/A
1	2	Hallway from Main Hallway to the Library	M	Floor Tile VAT 12" x 12"	6100/01/02/GG	Assumed	800	SF	0	SF	White			1	No	1/D
1	2	Hallway from Main Hallway to the Library	T	Radiator Insulation	6100/01/02/SYN/BB/1600	Assumed	25	SF	0	SF		1 Recessed Radiator		1	No	1/D
1	2	Principal's Office	N/A	Plaster Ceiling		NAD	500	SF	0	SF				N/A	N/A	N/A
1	2	Principal's Office	N/A	CMU		Non Suspect ACM	800	SF	0	SF				N/A	N/A	N/A
1	2	Principal's Office	M	Floor Tile VAT 12" x 12"	6100/01/02/GG	Assumed	500	SF	0	SF	Tan			1	No	1/D
1	2	Principal's Office Restroom	M	Transite Stalls	6100/01/02/28	Confirmed	2	EA	0	EA		Fibers are protruding from the matrix. No access F2016		1	No	1/D
1	2	Principal's Office Restroom	T	Pipe Fitting Insulation	6100/01/02/29	Confirmed	2	EA	0	EA				1	No	1/D
1	2	Principal's Office Restroom	T	Pipe Insulation 2-6 inch	6100/01/02/23	Confirmed	20	LF	0	LF				1	No	1/D
1	2	Principal's Office Restroom	N/A	Plaster Ceiling		NAD	200	SF	0	SF				N/A	N/A	N/A
1	2	Principal's Office Restroom	N/A	CMU		Non Suspect ACM	500	SF	0	SF				N/A	N/A	N/A
1	2	Main Office	N/A	Ceiling Tile 2' x 4'		Non Suspect ACM	800	SF	0	SF				N/A	N/A	N/A
1	2	Main Office	N/A	CMU		Non Suspect ACM	1200	SF	0	SF				N/A	N/A	N/A
1	2	Main Office	M	Floor Tile VAT 12" x 12"	6100/01/02/GG	Assumed	800	SF	0	SF	Tan			1	No	1/D
1	2	Classroom 203	X	X		X	X	X	X	X		No access		X	X	X
1	2	Room 203 SCDC	N/A	Plaster Ceiling		NAD	200	SF	0	SF				N/A	N/A	N/A
1	2	Room 203 SCDC	N/A	CMU		Non Suspect ACM	500	SF	0	SF				N/A	N/A	N/A
1	2	Room 203 SCDC	M	Floor Tile VAT 9" x 9"	6100/01/02/30	Confirmed	200	SF	0	SF	Tan			1	No	1/D
1	2	Room 203 SCDC	M	Blackboard Glue Dots	6100/01/02/VER/AR/2600	Assumed	10	SF	0	SF				1	No	1/D
1	2	Classroom 205	N/A	CMU		Non Suspect ACM	2000	SF	0	SF				N/A	N/A	N/A
1	2	Classroom 205	N/A	Plaster Ceiling		NAD	1200	SF	0	SF				N/A	N/A	N/A
1	2	Classroom 205	M	Floor Tile VAT 9" x 9"	6100/01/02/30	Confirmed	1200	SF	0	SF	Tan			1	No	1/D

6100/6460 Hill Freedman World Academy @ Leeds Campus 2015 2016 AHERA Three-Year Report.xls

School District of Philadelphia Hill Freedman World Academy @ Leeds Campus 1100 E. Mount Pleasant Avenue, Philadelphia, PA, 19150 ULCS# 6100 Year Built: 1953			AHERA Three-Year Reinspection 2015-2016 Room by Room Location Log Report										Reinspection Date: October 30, 2015 Building Inspector: A. Roman Number: 150619008 Management Planner: Megan Vala Number: 740728							
Element	Floor	On Site Room Name	System Affected	Material Description	HID#	Confirmed/Assumed/NAD/ Non Suspect ACM	Amount of Material	SF LF EA	Amount of Damage	SF LF EA	Color required for VAT	Comments/Description/Notes	Attic/ Crawl Space Ranking	Damage Potential (DP)	Newly Friable (NF)	Response Action (RA)				
1	2	Classroom 205 Closet	N/A	Plaster Ceiling		NAD	200	SF	0	SF				N/A	N/A	N/A				
1	2	Classroom 205 Closet	N/A	CMU		Non Suspect ACM	500	SF	0	SF				N/A	N/A	N/A				
1	2	Classroom 205 Closet	M	Floor Tile VAT 9" x 9"	6100/01/02/30	Confirmed	200	SF	0	SF	Black			1	No	1/D				
1	2	SPO (School Police Office)	N/A	Plaster Ceiling		NAD	300	SF	0	SF				N/A	N/A	N/A				
1	2	SPO (School Police Office)	N/A	CMU		Non Suspect ACM	500	SF	0	SF				N/A	N/A	N/A				
1	2	SPO (School Police Office)	M	Floor Tile VAT 12" x 12"	6100/01/02/GG	Assumed	300	SF	0	SF	Tan			1	No	1/D				
1	2	Office 204	N/A	Plaster Ceiling		NAD	600	SF	0	SF				N/A	N/A	N/A				
1	2	Office 204	N/A	CMU		Non Suspect ACM	800	SF	0	SF				N/A	N/A	N/A				
1	2	Office 204	M	Floor Tile VAT 12" x 12"	6100/01/02/GG	Assumed	800	SF	0	SF	Tan			1	No	1/D				
1	2	Classroom 206	N/A	Plaster Ceiling		NAD	800	SF	0	SF				N/A	N/A	N/A				
1	2	Classroom 206	N/A	CMU		Non Suspect ACM	1200	SF	0	SF				N/A	N/A	N/A				
1	2	Classroom 206	M	Floor Tile VAT 9" x 9"	6100/01/02/30	Confirmed	800	SF	0	SF	Tan			1	No	1/D				
1	2	Room 206A (Laboratory Storage attached to Classroom 206)	N/A	Plaster Ceiling		NAD	300	SF	0	SF				N/A	N/A	N/A				
1	2	Room 206A (Laboratory Storage attached to Classroom 206)	N/A	CMU		Non Suspect ACM	500	SF	0	SF				N/A	N/A	N/A				
1	2	Room 206A (Laboratory Storage attached to Classroom 206)	M	Floor Tile VAT 9" x 9"	6100/01/02/30	Confirmed	300	SF	0	SF	Tan			1	No	1/D				
1	2	Classroom 207	N/A	Plaster Ceiling		NAD	800	SF	0	SF				N/A	N/A	N/A				
1	2	Classroom 207	N/A	CMU		Non Suspect ACM	1200	SF	0	SF				N/A	N/A	N/A				
1	2	Classroom 207	M	Floor Tile VAT 9" x 9"	6100/01/02/30	Confirmed	800	SF	0	SF	Tan			1	No	1/D				
1	2	Classroom 207 Closet	N/A	Plaster Ceiling		NAD	200	SF	0	SF				N/A	N/A	N/A				
1	2	Classroom 207 Closet	N/A	CMU		Non Suspect ACM	500	SF	0	SF				N/A	N/A	N/A				
1	2	Classroom 207 Closet	M	Floor Tile VAT 9" x 9"	6100/01/02/30	Confirmed	200	SF	0	SF	Black			1	No	1/D				
1	2	Hallway from Main Office to Classrooms 206	N/A	Plaster Ceiling		NAD	2500	SF	0	SF				N/A	N/A	N/A				
1	2	Hallway from Main Office to Classrooms 206	N/A	CMU		Non Suspect ACM	5000	SF	0	SF				N/A	N/A	N/A				
1	2	Hallway from Main Office to Classrooms 206	M	Floor Tile VAT 12" x 12"	6100/01/02/GG	Assumed	2500	SF	0	SF	White			1	No	1/D				
1	2	Hallway from Main Office to Classrooms 206	T	Radiator Insulation	6100/01/02/SYN/BB/1600	Assumed	25	SF	0	SF		1 Recessed Radiator		1	No	1/D				
1	2	Stairwell at Classrooms 206 and 207	N/A	Plaster Ceiling		NAD	240	SF	0	SF				N/A	N/A	N/A				
1	2	Stairwell at Classrooms 206 and 207	N/A	Cement Floor		Non Suspect ACM	240	SF	0	SF				N/A	N/A	N/A				
1	2	Stairwell at Classrooms 206 and 207	N/A	Ceramic Tile Walls		Non Suspect ACM	500	SF	0	SF				N/A	N/A	N/A				
1	3	Mechanical Room above the Gymnasium	N/A	Brick Wall		Non Suspect ACM	8000	SF	0	SF				N/A	N/A	N/A				
1	3	Mechanical Room above the Gymnasium	N/A	Concrete Ceiling		Non Suspect ACM	4000	SF	0	SF				N/A	N/A	N/A				
1	3	Mechanical Room above the Gymnasium	N/A	Cement Floor		Non Suspect ACM	4000	SF	0	SF				N/A	N/A	N/A				
1	3	Mechanical Room above the Gymnasium	T	Pipe Fitting Insulation	6100/01/04/BB	Confirmed	51	EA	0	EA				1	No	1/D				
1	3	Mechanical Room above the Gymnasium	T	Pipe Insulation 2-6 inch	6100/01/04/DD	Confirmed	150	LF	0	LF				1	No	1/D				
1	3	Mechanical Room above the Gymnasium	M	Vibration Damper Cloth	6100/01/04/CC	Assumed	18	EA	0	EA				1	No	1/D				
1	3	Mechanical Room above the Gymnasium	T	Pipe Insulation > 6 inch	6100/01/04/FF	Confirmed	50	LF	0	LF				1	No	1/D				
1	3	Mechanical Room above Auditorium	N/A	Concrete Ceiling		Non Suspect ACM	1500	SF	0	SF				N/A	N/A	N/A				
1	3	Mechanical Room above Auditorium	N/A	Cement Floor		Non Suspect ACM	1500	SF	0	SF				N/A	N/A	N/A				
1	3	Mechanical Room above Auditorium	N/A	Brick Wall		Non Suspect ACM	4000	SF	0	SF				N/A	N/A	N/A				
1	3	Mechanical Room above Auditorium	M	Vibration Damper Cloth	6100/01/04/CC	Assumed	18	EA	0	EA				1	No	1/D				
1	3	Mechanical Room above Auditorium	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	150	LF	0	LF				N/A	N/A	N/A				
1	AT	Attic - Penthouse	X	X		X	X	X	X	X		Abated Summer 2014	A	X	X	X				
1	AT	Attic - 2nd Floor Fan Room	X	X		X	X	X	X	X		Abated Summer 2014	A	X	X	X				
1	CS	Crawl Space - Basement	X	X		X	X	X	X	X		Abated Summer 2014	A	X	X	X				
1	CS	Crawl Space - Incinerator Room	X	X		X	X	X	X	X		Abated Summer 2014	A	X	X	X				

Section III Certificates

A. Management Planner/Building Inspector Certificates

Section III – A

Management Planner/Building Inspector Certificates

These charts indicate the Name, Course Date, Expiration Date and Corresponding Certificate Number of the Management Planner and Building Inspector of individuals that participated in the AHERA 3 Year Inspection and Management Plan process of 2015/2016.

Management Planner	Date Granted	Expiration Date	Certificate Number
Monique Causley	2/15/2015	2/16/2016	ACC-0215-8-010
Monique Causley	2/16/2016	2/17/2017	ACC-0216-8-001
Megan Vala	5/22/2015	6/22/2016	740728
Mary Anne Lerro	4/5/2016	4/5/2017	742327

Building Inspector	Date Granted	Expiration Date	Certificate Number
Scott Magee	8/15/2015	8/15/2016	70016699C
William Garrity	8/15/2015	8/15/2016	70016699A
Bernard Brunner	10/2/2015	8/2/2016	45397
Mary Anne Lerro	3/3/2015	3/3/2016	740092
Mary Anne Lerro	4/5/2016	4/5/2017	742322
James Madden	12/11/2014	12/11/2015	ACC-1214-6-010
James Madden	12/3/2015	12/3/2016	ACC-1215-6-018
Troy Ray	3/15/2015	3/19/2016	ACC-0355-6-011
Ananth Vinjamuri	9/29/2015	9/29/2016	374
Shelton Williams	9/29/2015	9/29/2016	375
Paul Davis	2/12/2015	2/12/2016	ACC-0215-6-015
Paul Davis	2/2/2016	2/2/2017	741836
Bernard Bryson	2/16/2015	2/16/2016	ACC-0125-6-031
Bernard Bryson	2/15/2016	2/15/2017	ACC-0216-6-005
Alexander Roman	9/18/2015	9/18/2016	EHSBIR-150619-008
Norm Harrison	9/2/2015	9/2/2016	ACC-0915-6-011
Kelly Mayberry	2/20/2015	2/20/2016	EHSBIR-150220-005
Kelly Mayberry	2/18/2016	2/18/2017	EHSBIR-160218-006
Andrew Hine	5/6/2015	5/6/2016	AI05042015-3
Maryellen Leotta	2/12/2015	2/12/2016	ACC-0215-6-024

Certificate of Completion

awarded to

Monique Causley

for successfully completing the prescribed course of study in

Pennsylvania Asbestos Management Planner Refresher Course

under TSCA Title II

presented by

ACCESS TRAINING SERVICES, INC.
7921 River Road, Pennsauken, NJ 08110
(856) 665-3449

2/16/15

Course Date

N/A

Exam Date

2/16/16

Expiration Date

Not Provided

Social Security Number

ACC-0215-8-010

Certificate Number

Mark K. Schlager
Training Director

Certificate of Completion

awarded to

Monique Causley

for successfully completing the prescribed course of study in

Pennsylvania Asbestos Management Planner Refresher Course

under TSCA Title II

presented by

ACCESS TRAINING SERVICES, INC.
7921 River Road, Pennsauken, NJ 08110
(856) 665-3449

2/15/16

Course Date

N/A

Exam Date

2/15/17

Expiration Date

Not Provided

Social Security Number

ACC-0216-8-001

Certificate Number

Mark K. Schlüger
Training Director

Certificate of Training

CRITERION LABORATORIES, INC.

HEREBY CERTIFIES THAT

Megan Vala

HAS SUCCESSFULLY COMPLETED A 16 HOUR COURSE ENTITLED

Asbestos Management Planner Initial

INCLUDING CLASSROOM INSTRUCTION

05/21/2015 to 05/22/2015


Exam passed on this 22nd day of May 2015 - Score - 94

Approved for AHERA Accreditation Under TSCA Title II

3370 Progress Drive, Suite J
Bensalem, PA 19020
(215) 244-1300 - Phone
(215) 244-4349 - Fax
www.criterionlabs.com

Course is conducted in English

DIRECTOR:


James A. Welte, CIH, President

Certificate of Training

CRITERION LABORATORIES, INC.

HEREBY CERTIFIES THAT

Mary Anne Lerro

HAS SUCCESSFULLY COMPLETED A 4 HOUR COURSE ENTITLED

Asbestos Management Planner Refresher

INCLUDING CLASSROOM INSTRUCTION

on this 5th day of April 2016

Approved for AHERA Accreditation Under TSCA Title II

3370 Progress Drive, Suite J
Bensalem, PA 19020
(215) 244-1300 - Phone
(215) 244-4349 - Fax
www.criterionlabs.com

Course is conducted in English

DIRECTOR:

James A. Welts
James A. Welts, CIH, President

EMSL ANALYTICAL, INC.

Certifies that

Scott Magee

has successfully completed the course of study for the

Asbestos Building Inspector Refresher Course

for Accreditation under TSCA Title II

EMSL Certificate No. 70016699C


Approved by:

PA Dept. of Labor and Industry
Accreditation # 137

Course Date: 8/15/2015
Granted: 8/15/2015
Expiration Date: 8/15/2016

Sponsored by:

EMSL Analytical, Inc.
200 Route 130 North
Cinnaminson, NJ 08077
Phone: (800) 220-3675
Fax: (856) 786-5973
www.emsl.com



Michael P. Menz

Michael P. Menz, CIH
Training Director

Environmental, Mold, Bacteria, IAQ, Asbestos, Lead, Forensic and Materials Testing Since 1981

EMSL ANALYTICAL, INC.

Certifies that

William Garrity

has successfully completed the course of study for the

Asbestos Building Inspector Refresher Course

for Accreditation under TSCA Title II

EMSL Certificate No. 70016699A


Approved by:

PA Dept. of Labor and Industry
Accreditation # 137

Course Date: 8/15/2015
Granted: 8/15/2015
Expiration Date: 8/15/2016

Sponsored by:

EMSL Analytical, Inc.
200 Route 130 North
Cinnaminson, NJ 08077
Phone: (800) 220-3675
Fax: (856) 786-5973
www.emsl.com



Michael P. Menz

Michael P. Menz, CIH
Training Director

Environmental, Mold, Bacteria, IAQ, Asbestos, Lead, Forensic and Materials Testing Since 1981

45397

National Asbestos & Environmental Training Institute

CERTIFICATE OF COMPLETION

AHERA/EPA Accredited Per 40 CFR Part 763
Asbestos Accreditation under TSCA Title II

This is to certify that


Bernard Brunner, Jr.

Successfully completed the course entitled

**1/2-Day New York State/EP A/AHERA Asbestos Building Inspector Annual Refresher on
October 2, 2015**

Examination Passed October 2, 2015

Expiration Date on October 2, 2016


Doris L. Adler
President, NAEETI

Per 10 NYCRR Part 73.2 (L) (1), DOH 2832 Certificate of Completion of Asbestos
Safety Training is the only official record of training for N.Y.S. students.

Language: English

ABIH 1/2 CM POINT

3321 Doris Avenue, Building B, Ocean, NJ 07712

Phone (732) 531-5571

Fax (732) 531-5956

www.naeti.com

Number 740092

Expiration Date:
03/03/2016

Certificate of Training

CRITERION LABORATORIES, INC.

HEREBY CERTIFIES THAT

Mary Anne Lerro

HAS SUCCESSFULLY COMPLETED A 4 HOUR COURSE ENTITLED

Asbestos Building Inspector Refresher

on this 3rd day of March 2015

Exam passed on this 3rd day of March 2015 - Score - 84

Approved for AHERA Accreditation Under TSCA Title II

3370 Progress Drive, Suite J
Bensalem, PA 19020
(215) 244-1300 - Phone
(215) 244-4349 - Fax
www.criterionlabs.com

Course is conducted in English

DIRECTOR:

James A. Welts

James A. Welts, CIH, President

Certificate of Training

CRITERION LABORATORIES, INC.

HEREBY CERTIFIES THAT

Mary Anne Lerro

HAS SUCCESSFULLY COMPLETED A 4 HOUR COURSE ENTITLED

Asbestos Building Inspector Refresher

INCLUDING CLASSROOM INSTRUCTION

on this 5th day of April 2016

Exam passed on this 5th day of April 2016 - Score - 88

Approved for AHERA Accreditation Under TSCA Title II

3370 Progress Drive, Suite J
Bensalem, PA 19020
(215) 244-1300 - Phone
(215) 244-4349 - Fax
www.criterionlabs.com

Course is conducted in English

DIRECTOR:

James A. Welts

James A. Welts, CIH, President

Certificate of Completion

James Madden

for successfully completing the prescribed course of study in

Pennsylvania Asbestos Building Inspector Refresher Course

under TSCA Title II

presented by

ACCESS TRAINING SERVICES, INC.
7921 River Road, Pennsauken, NJ 08110
(856) 665-3449

12/11/14

Course Date

N/A

Exam Date

12/11/15

Expiration Date

Not Provided

Social Security Number

ACC-1214-6-010

Certificate Number

Mark K. Schlager
Training Director

Certificate of Completion

James Madden

for successfully completing the prescribed course of study in

Pennsylvania Asbestos Building Inspector Refresher Course

under TSCA Title II

presented by

ACCESS TRAINING SERVICES, INC.
7921 River Road, Pennsauken, NJ 08110
(856) 665-3449

12/3/15

Course Date

N/A

Exam Date

12/3/16

Expiration Date

Not Provided

Social Security Number

ACC-1215-6-018

Certificate Number

Mark K. Schlager
Mark K. Schlager
Training Director

Certificate of Completion

Troy A. Ray

for successfully completing the prescribed course of study in

Pennsylvania Asbestos Building Inspector Refresher Course

under TSCA Title II

presented by

ACCESS TRAINING SERVICES, INC.
7921 River Road, Pennsauken, NJ 08110
(856) 665-3449

3/19/15

Course Date

N/A

Exam Date

3/19/16

Expiration Date

Not Provided

Social Security Number

ACC-0355-6-011

Certificate Number

Mark K. Schlager
Training Director

CERTIFICATE NO 374

G&C Environmental Services, Inc. (#294)

2 Street Road, Newtown Square, Pennsylvania 19073

Telephone: (610) 993-9202 Facsimile: (610) 993-9232

Email: Training@gcenviro.com

www.GCenviro.com

This document certifies that Ananth K. Vinjamuri has successfully completed this State of New York Department of Health Approved AHERA BUILDING INSPECTOR

REFRESHER COURSE, completed as required for asbestos accreditation under the Toxic

Substances Control Act, Title II. This course was held from 09/29/2015 to 09/29/2015.

The examination date was 09/29/2015. This certificate expires one year from the date of
successful completion of the examination 09/29/2016.

The official record of successful training completion is the New York State Department of Health certificate of asbestos safety training completion (DPH 2832).

Gail M. Conner
Training Director

Gail M. Conner

CERTIFICATE NO 375

G&C Environmental Services, Inc. (#294)

2 Street Road, Newtown Square, Pennsylvania 19073

Telephone: (610) 993-9202 Facsimile: (610) 993-9232

Email: Training@gcenviro.com

www.GCenviro.com

This document certifies that Shelton Williams has successfully completed this

State of New York Department of Health Approved AHERA BUILDING INSPECTOR

REFRESHER COURSE, completed as required for asbestos accreditation under the Toxic

Substances Control Act, Title II. This course was held from 09/29/2015 to 09/29/2015.

MM DD YR MM DD YR

The examination date was 09/29/2015. This certificate expires one year from the date of

MM DD YR

successful completion of the examination 09/29/2016.

MM DD YR

The official record of successful training completion is the New York State Department of Health certificate of asbestos safety training completion (DPH 2832).

Gail M. Conner

Training Director

Gail M. Conner

Certificate of Completion

Paul M. Davis

for successfully completing the prescribed course of study in

Pennsylvania Asbestos Building Inspector Refresher Course

under TSCA Title II

presented by

ACCESS TRAINING SERVICES, INC.
7921 River Road, Pennsauken, NJ 08110
(856) 665-3449

2/12/15

Course Date

N/A

Exam Date

2/12/16

Expiration Date

Not Provided

Social Security Number

ACC-0215-6-015

Certificate Number

Mark K. Schlager
Training Director

Certificate of Training

CRITERION LABORATORIES, INC.

HEREBY CERTIFIES THAT

Paul M. Davis

HAS SUCCESSFULLY COMPLETED A 4 HOUR COURSE ENTITLED
Asbestos Building Inspector Refresher

INCLUDING CLASSROOM INSTRUCTION

on this 2nd day of February 2016

Exam passed on this 2nd day of February 2016 - Score - 92

Approved for AHERA Accreditation Under ISCA Title II

3370 Progress Drive, Suite J
Bensalem, PA 19020
(215) 244-1300 - Phone
(215) 244-4349 - Fax
www.criterionlabs.com

Course is conducted in English

DIRECTOR:

James A. Wells

James A. Wells, CIH, President

Certificate of Completion

Bernard J. Bryson

for successfully completing the prescribed course of study in

Pennsylvania Asbestos Building Inspector Refresher Course

under TSCA Title II

presented by

ACCESS TRAINING SERVICES, INC.
7921 River Road, Pennsauken, NJ 08110
(856) 665-3449

2/16/15
Course Date

N/A

Exam Date

2/16/16

Expiration Date

Not Provided

Social Security Number

ACC-0125-6-031

Certificate Number

Mark K. Schlager
Training Director

Certificate of Completion

Bernard J. Bryson

for successfully completing the prescribed course of study in

Pennsylvania Asbestos Building Inspector Refresher Course

under TSCA Title II

presented by

ACCESS TRAINING SERVICES, INC.
7921 River Road, Pennsauken, NJ 08110
(856) 665-3449

2/15/16

Course Date

N/A

Exam Date

2/15/17

Expiration Date

Not Provided

Social Security Number

ACC-0216-6-005

Certificate Number

Mark K. Schlager
Training Director

EHS TRAINING INSTITUTE, INC.

A Division of BATTI, Inc.

Certificate of Completion

AHERA Building Inspector

(Refresher)

Awarded To:

Alexander Roman

SS#:XXX-XX-1743

Who has completed this 4-hour course and examination,

EPA Approved under TSCA Title II

AHERA / ASHARA Rule

40 CFR Part 763.

EHS TRAINING INSTITUTE, INC.

A Division of BATTI, Inc.

Delaware Industrial Park • 6 Garfield Way


Newark, DE 19713-5817

(302) 737-3376 • Fax (302) 737-5764

Course Date: September 18, 2015

Date of Expiration: September 18, 201

Certification Number : EHSBIR 150619-008


Todd K. Zeisloff, Instructor


Neeraj K. Batta, President

Certificate of Completion

Norman Harrison

for successfully completing the prescribed course of study in

Pennsylvania Asbestos Building Inspector Refresher Course

under TSCA Title II

presented by

ACCESS TRAINING SERVICES, INC.
7921 River Road, Pennsauken, NJ 08109
(856) 665-3449

9/2/15

Course Date

N/A

Exam Date

9/2/16


Expiration Date

Not Provided

Social Security Number

ACC-0915-6-011

Certificate Number


Mark A. Schlenger
Training Director

EHS TRAINING INSTITUTE, INC.
A Division of BATTI, Inc.

Certificate of Completion

AHERA Building Inspector

(Refresher)

Awarded To:

Kelly Mayberry

SS#:XXX-XX-1551

Who has completed this 4-hour course and examination,
EPA Approved under TSCA Title II
AHERA / ASHARA Rule
40 CFR Part 763.

EHS TRAINING INSTITUTE, INC.

A Division of BATTI, Inc.

Delaware Industrial Park • 6 Garfield Way

Newark, DE 19713-5817

(302) 737-3376 • Fax (302) 737-5764

Course Date: February 20, 2015

Date of Expiration: February 20, 2016

Certification Number : EHSBIR 150220-005


Todd K. Zeisloft, Instructor


Neeraj K. Batta, President

EHS TRAINING INSTITUTE, INC.
A Division of BATTI, Inc.

Certificate of Completion

AHERA Building Inspector

(Refresher)

Awarded To:

Kelly Mayberry

SS#:XXX-XX-1551

Who has completed this 4-hour course and examination,

EPA Approved under TSCA Title II

AHERA / ASHARA Rule

40 CFR Part 763.

EHS TRAINING INSTITUTE, INC.

A Division of BATTI, Inc.

Delaware Industrial Park • 6 Garfield Way

Newark, DE 19713-5817

(302) 737-3376 • Fax (302) 737-5764

Course Date: February 18, 2016

Date of Expiration: February 18, 2017

Certification Number : EHSBIR 160218-006



Todd K. Zeisloft, Instructor



Neeraj K. Batta, President

AEROSOL MONITORING & ANALYSIS, INC.

This is to certify that
ANDREW HINE

*has met the attendance requirements and successfully completed
the course entitled*

3-DAY EPA AHERA INSPECTOR
For Accreditation Under TSCA Title II

05/04/2015 to 05/06/2015

Course Date

05/06/2015

Exam Date

5/6/2016

Expiration Date

STEVE SIERAGI

Principal Instructor

Steve Sieragi

A105042015-3

Certification No.

E. Rush Barnett

Course Director

E. Rush Barnett

1331 Ashton Road

P.O.Box 646

Hanover, MD 21076

P: 410-684-3327

F: 410-684-3724

www.amatraining.com

Certificate of Completion

Maryellen Leotta

for successfully completing the prescribed course of study in

Pennsylvania Asbestos Building Inspector Refresher Course

under TSCA Title II

presented by

ACCESS TRAINING SERVICES, INC.
7921 River Road, Pennsauken, NJ 08110
(856) 665-3449

2/12/15

Course Date

N/A

Exam Date

2/12/16

Expiration Date

Not Provided

Social Security Number

ACC-0215-6-024

Certificate Number

Mark K. Schlüger
Training Director

Asbestos Hazard Emergency Response Act (AHERA) Environmental Compliance Audit Cross Reference Table

In response to the AHERA Environmental Compliance Audit a Cross Reference Table has been prepared for inclusion into the Environmental Management Plan. The purpose of this Cross Reference Table is to link the following documents to the AHERA Management Plan.

Cross Reference Table	
3 Year Reinspection Report follows this Cross Reference Table documentation.	
Subject Matter	Location of Required Documents
Designated Person	Pages 1 - 3
Annual Notification	Pages 4 - 5
6 Month Periodic Surveillance Outline of Events	Page 6
3 Year Re-inspections Outline of Events	Page 7
Asbestos Management Program (operations and maintenance)	Pages 8 - 19
Asbestos Investigation Report (AIR)	Attachment 1 Letter Dated August 4, 2006
Training (included in the Asbestos Management Program)	<p>The original records are centralized at the School District's Environmental Library. Copies are maintained on staff and are required to be maintained in the latest Reinspection Report.</p> <p>2 hour awareness training records for all Building Engineers, Custodian Assistants and maintenance personnel</p> <p>40 hour worker/supervisor training records for the OEMS A-Team and various AST tradesmen.</p>
Response Actions (monthly mailings if applicable)	The original documents are on file at the School District's Environmental Library.
	Copies of the original are mailed to the Schools Main Office for retention with the Management Plan documentation. These documents are typically kept separate from the management plan in an update binder due to the potential volume of response action reports.

SCHOOL DISTRICT OF PHILADELPHIA

ASBESTOS DESIGNATED PERSON

Gerald F Junod
Office of Capital Programs
Environmental Management & Services
440 N Broad Street, 3rd Floor
Philadelphia, PA 19130
Telephone: 215 400 6738
Fax: 215 400 4751

Drexel University- Asbestos Building Inspector Course	January 9-11, 1989 24 Hours
Drexel University- Asbestos Management Planner Course	January 12-13, 1989 16 Hours
Criterion Laboratories, Inc. - Asbestos Management Planner Course	October 11-12, 2012 16 Hours

<u>Annual Building Inspector Refreshers</u>	1990 to Present
4 Hours	
Drexel University	
Criterion Laboratories, Inc	
Access Training Services, Inc.	

<u>Annual Building Management Planner Refreshers</u>	1990 to 1994
4 Hours	
Drexel University	
Criterion Laboratories, Inc	2013 to Present
4 Hours	

Environmental Manager, School District of Philadelphia

Manages the design and implementation of asbestos and lead projects for the Capital Improvement Program and other District Departments including Facilities & Operations and Information Technology. Ensures that asbestos abatement and lead remediation projects are expertly designed and executed in accordance with industry best management practice standards and regulations.

Manager, City of Philadelphia Asbestos Control Program

Served as the Asbestos Control Program Manager for the City of Philadelphia, Department of Public Health, Air Management Services, Asbestos Control Unit from August 1, 2003 through October 23, 2006.

Mid Atlantic Regional Environmental Consortium (MAREC)

Former member with attendance and participation commitments of all quarterly EPA Region III and yearly National Asbestos Regulatory Conferences sponsored by the EPA and the National Conference of State Legislators respectively as a representative for the City of Philadelphia Department of Public Health Air Management Services from 1994 through 2006.

Philadelphia Environmental Task Force

Former member of the Philadelphia Environmental Task force as a representative and point of contact for the City of Philadelphia Department of Public Health Air Management Services Asbestos Control Unit from 2002 through 2006.

Asbestos Instructor

Worked as the primary instructor for the initial and annual Asbestos Project Inspector training and licensing program as mandated by City of Philadelphia Department of Public Health Asbestos Control Regulations from August 1994 through October 2006.

Worked as a lead instructor with an Environmental Consulting Firm and approved by the US EPA for the initial and annual refresher training courses for various asbestos occupational disciplines such as the Building Inspector, Management Planner and Worker/Supervisor from 1991 through 1994.

I certify that the general, local agency responsibilities as stipulated in Section 763.84 will be met.



Gerald F. Junod
Asbestos Designated Person
Environmental Manager
Office of Environmental Management and Services

SCHOOL DISTRICT OF PHILADELPHIA

Accreditation Information Statement

All persons who inspect for Asbestos Containing Building Materials (ACBM) and who will design or carry out response actions with respect to assumed and confirmed ACBM, will be accredited by an EPA approved course and/or a State Contractors Accreditation Program under Sections 206 (c) and 206 (b) of Title II of the ACT.

A handwritten signature in black ink, appearing to read 'Gerald F. Junod', is written over the printed name and title.

Gerald F. Junod
Asbestos Designated Person
Environmental Manager
Office of Environmental Management and Services

SCHOOL DISTRICT OF PHILADELPHIA
OFFICE OF CAPITAL PROGRAMS
440 NORTH BROAD STREET, SUITE 373
PHILADELPHIA, PENNSYLVANIA 19130

OFFICE OF ENVIRONMENTAL MANAGEMENT AND SERVICES

PHONE (215)-400-4750

September 2015

TO: Principals
Building Administrators/Occupants
Parents/Guardians

FROM: Fran Burns
Chief Operating Officer

Francine Locke, M.S., Director
Office of Environmental Management and Services

SUBJECT: Annual EPA Notification Letter

Pursuant to the Federal Environmental Protection Agency (EPA) mandate, as required by 40 C.F.R. 763.84 (c)(d) of public access to environmental records, this letter is to acknowledge the availability of your facility's Asbestos Hazard Emergency Response Act (AHERA) Management Plan.

Each member of the school staff, parents/guardians, temporary workers and/or contractors, are required to receive a copy of the Notification Letter. At the direction of the Principal, a copy is to be posted on the bulletin boards and an appropriate amount of copies are to be generated for distribution.


Note: The AHERA Three-Year Reinspection reports, in colored binders; White with Pink, Tan, Black, Red, Dark Blue, Green, Yellow and White, are Federal EPA mandated inspection documents. The School District of Philadelphia is subject to severe monetary penalties if the reports and associated paperwork are not available to the EPA and the public upon request.

It is incumbent on designated school personnel to gather and retain this data as it is delivered, in one location for future review. Acceptable locations include the Principal's Office or Main Office for the primary data. The Building Engineer should maintain any secondary or duplicate copies.

If you have any questions, please call 215-400-4750. Thank you for your cooperation.



Fran Burns
Chief Operating Officer



Francine Locke, M.S., Director
Office of Environmental Management
and Services

c: Danielle Floyd

AHERA-4
8/21/15



School District of Philadelphia
OFFICIAL NOTICE

PLEASE POST

September 2015

TO: Principals
Building Administrators
Building Engineers
Building Occupants
Parents/Guardians

FROM: Fran Burns
Chief Operating Officer

Francine Locke, M.S., Director
Office of Environmental Management and Services

SUBJECT: Annual Notification Letter: Asbestos Hazard Emergency Response Act

The Federal Register published on October 30, 1987, Subpart E, in Schools: Final Rule and Notice, 763.84 (c)(d) states that each local education agency shall ensure that workers and building occupants or guardians are to be informed at least once each school year about inspections, response actions and post-response action activities including re-inspections and periodic surveillance activities. The School District as the Local Education Agency (LEA), retains such reports that are available for public inspection in the Office of the Principal or Building Administrator.

The Principal or Building Administrator is required to do the following with this notification:

- 1) Post in a Public Place or Main Office
- 2) Inform Building Occupants
- 3) Send a copy of this notification to Parents or Guardians
- 4) Insert a copy into the latest AHERA Three-Year Reinspection report (white/pink binder) in your office or facility.

Handwritten signature of Fran Burns in black ink.

Fran Burns
Chief Operating Officer

Handwritten signature of Francine Locke in black ink.

Francine Locke, M.S., Director
Office of Environmental Management
and Services

c: Danielle Floyd

AHERA-4a
8/21/15

SCHOOL DISTRICT OF PHILADELPHIA
Education Center
440 North Broad Street
Philadelphia, Pennsylvania 19130

Office of Environmental Management and Services

215-400-4750

AHERA
Six Month Surveillance
Outline of Events

- Pursuant to the Federal Environmental Protection Agency (EPA) mandate, as required by 40 CFR 763.92(b), the following procedure is to be implemented. At least once every six (6) months after a Management Plan is in effect, each Local Education Agency (LEA) shall conduct a periodic surveillance in each building that it owns or leases that contains Asbestos Containing Building Materials (ACBM) or is assumed to contain ACBM.
- The first Bi-Annual Inspection starts in the Spring (March, April, May) and again in the Fall (October, November, December) of each year. The Building Engineer/Assistant should assist the Building Inspector with appropriate access to all areas including (Crawlspaces/Attics) and rooms in the facility. There is no action required of the Principal.
- The Building Inspector shall visually inspect all areas that are identified in the Management Plan as ACBM or assumed ACBM. The date of the surveillance is recorded, the inspectors name and any changes in the conditions of the materials.
- The Building Inspector shall make a copy of the inspection document and insert into the front of the latest Management Plan (AHERA Three Year Reinspection report). The original document is returned to the LEA's Environmental Library and filed.

SCHOOL DISTRICT OF PHILADELPHIA
Education Center
440 North Broad Street
Philadelphia, Pennsylvania 19130

Office of Environmental Management and Services

215-400-4750

AHERA
Three Year Reinspection
Outline of Events

- Pursuant to the Federal Environmental Protection Agency (EPA) mandate, as required by 40 CFR 763.85(b) the following procedure is to be implemented. At least once every three (3) years after a Management Plan is in effect, each Local Education Agency (LEA) shall conduct a reinspection of each building that it owns or leases that contains Asbestos Containing Building Material's (ACBM's) or is assumed to contain ACBM.
- Subsequent Three Year Re-inspections (2009, 2012, 2015, etc) shall start in the Fall (October, November, December, January). The Building Engineer/Assistant should assist the Building Inspector with appropriate access to all areas including (Crawlspaces/Attics) and rooms in the facility. There is no action required of the Principal.
- An accredited Building Inspector shall visually inspect and touch to determine friability, all areas that are identified in the Management Plan as ACBM or assumed ACBM. The date of the surveillance is recorded, the inspectors name and any changes in the conditions of the materials. The Building Inspectors state of accreditation and license number is required.
- After the inspection, the Building Inspector shall make a copy of the inspection documents and insert into the front of the latest Management Plan (AHERA Three Year Reinspection report). The original document is returned to the LEA's Environmental Library and filed.
- The Building Inspector shall return the reinspection data to the Management Planner to be assessed and determine appropriate response actions and a report issued (AHERA Three Year Reinspection report). One copy of the report is delivered to the schools Principal to be permanently retained with all previous environmental data. Another copy is retained in the LEA's Environmental Library.



School District of Philadelphia
Office of Environmental Management & Services
440 North Broad Street
Philadelphia, PA 19130
(215) 400-4750

**School District of Philadelphia
Asbestos Management Program**

TABLE OF CONTENTS

Definitions.....	Page 9
1. Introduction.....	Page 10
2. Summary of Asbestos Management Plan	
3. Asbestos Management Plan Execution.....	Page 11
a. General Execution	
4. Summary of Program Execution	
a. Asbestos Management Plan Execution	
5. Responsibilities	
a. OEMS	
b. Asbestos Worker/Supervisor "A-TEAM".....	Page 12
c. Asbestos Designated Person	
d. Supervisor or Project Manager (Capital, Maintenance & Facilities)	
e. Employee Capital.....	Page 13
f. Employee Maintenance	
g. Employee Facilities and Custodial	
6. Requirements.....	Page 14
a. Employee Exposure Monitoring	
b. Employee Notification	
c. Observation of Monitoring	
d. Training Program	
e. Access of Information	
f. Record Keeping	
7. AHERA O&M Plan.....	Page 15
a. Controls	
8. O&M Response Actions.....	Page 16
a. Facility Maintenance Isolation of Area	
b. Unlikely Contact with ACM/PACM	
c. Accidental Disturbance of ACM/PACM	
d. Planned Disturbance of ACM/PACM	
e. Miscellaneous ACM/PACM.....	Page 17
f. Vinyl Asbestos Floor Tile	
g. Mastic/Adhesives	
h. Woven Vibration Dampers	
i. Other Work Practices	
j. Fiber Release Episodes	
9. References and Resources.....	Page 18

DEFINITIONS / ACRONYMS

ACM/PACM:	Asbestos Containing Material/Potential Asbestos Containing Material
AHERA:	Asbestos Hazard Emergency Response Act
AIR FORM:	Asbestos Inspection Report Form
Amended Water:	Water to which a surfactant (soap) has been added
AMP:	Asbestos Management Program/Asbestos Management Plan
Asbestos Designate Person:	Individual assigned by the district to oversee asbestos related issues.
Asbestos Regulated Area:	Location that is posted as an asbestos work area in which only approved and accredited personnel are permitted to enter
AST:	Asbestos Support Team involving approved and accredited school district tradespersons personnel that are school district person
A-TEAM:	School District of Philadelphia asbestos workers
CIP:	Capital Improvement Program
Consultant:	Asbestos consulting firm hired by the District
Demolition Directive:	Memorandum – August 4, 2006 from Patrick Henwood
EPA:	Environmental Protection Agency
In House Personnel:	School District of Philadelphia asbestos workers
LEA:	Local Education Agency
O&M:	Operations and Maintenance
OEMS:	Office of Environmental Management and Services
OSHA:	Occupational Safety and Health Administration
PEL:	Permissible Exposure Limit
PSD or SDP:	Philadelphia School District/School District of Philadelphia
PSIT:	Philadelphia School Improvement Team
STEL:	Short Term Exposure Limit

1. Introduction

The School District of Philadelphia, Asbestos Policy Statement:

“The School District of Philadelphia is dedicated to providing a safe and healthful work environment for its employees, students, faculty, contractors and visitors. In recognition of the potential health problems associated with asbestos, the School District of Philadelphia is committed to a comprehensive asbestos control program. This program is implemented and maintained through the School District of Philadelphia's Office of Environmental Management and Services (OEMS).”

OEMS has the responsibility of establishing procedures for asbestos abatement, asbestos inspection, air monitoring, renovation and demolition activities within all School District of Philadelphia owned or leased facilities.

These procedures are developed to ensure that:

- (1) People are not exposed to significant levels of asbestos fibers
- (2) Asbestos waste is handled and disposed of properly
- (3) Members of the School District of Philadelphia community have access to the Office of Environmental Management and Services for information, assistance, guidance, and interpretation regarding asbestos related matters.
- (4) Members of the School District of Philadelphia community have access to the Asbestos Management Plans as required and outlined in the US EPA AHERA regulations including annual written notification to all parents.
- (5) Compliance with all applicable Federal, State and Local Asbestos Regulations

Requirements outlined in this manual are mandatory in nature where the word “SHALL” is used and are advisory in nature where the word “SHOULD” is used.

2. Summary of Asbestos Management Program

The School District of Philadelphia’s Asbestos Management Program was established to meet the requirements of Federal, State, and Local Regulations.

These regulations include, but are not limited to:

- US Environmental Protection Agency Asbestos Hazard Emergency Response Act (US EPA AHERA) and National Emissions Standard for Hazardous Air Pollutants subpart M, Part 61 (NESHAP);
- US Department of Labor, Occupational Safety and Health Administration (OSHA) General Industry Standard (29 CFR 1910.1001) and the OSHA Asbestos Standard for the Construction Industry (29 CFR 1926.1101);
- The Commonwealth of Pennsylvania, Department of Labor and Industry, Asbestos Occupations, Accreditation and Certification Act;
- The City of Philadelphia, Department of Public Health, Asbestos Control Regulations.

3. Asbestos Management Program Execution

a) General Execution

The Office of Environmental Management and Services (OEMS) develops, implements and manages safety and health programs for the School District of Philadelphia faculty, staff and students and assists with ensuring that all contractors comply with Federal, State and Local Environmental Regulations. The OEMS provides the oversight of School District of Philadelphia employees (Asbestos A-Team), environmental consultants, and asbestos abatement contractors for all projects within the School District of Philadelphia concerning Asbestos Containing Materials.

The control of safety and health hazards at the School District of Philadelphia is primarily through the implementation of engineering, work practice and administrative controls. Personal Protective Equipment (PPE) is used to supplement these controls or whenever the controls are not feasible or are in the process of being implemented. PPE is also recommended whenever exposures to chemical, physical or biological agents can be prevented or reduced by its use.

This written program establishes the procedures necessary to:

- 1) meet established standards and federal regulations for occupational exposure to asbestos fibers;
- 2) meet the requirements of the City of Philadelphia Asbestos Control Regulations which encompasses the disturbance and/or abatement of asbestos containing building materials;
- 3) provide the necessary health and safety protection to the School District of Philadelphia staff, faculty, students, contractors and visitors.

This program is strengthened by input and cooperation with the Philadelphia Federation of Teachers (PFT), Health and Welfare Fund.

4. Summary of Program Execution

a) Asbestos Management Program Execution

The Asbestos Management Program is administered by the Office of Environmental Management and Services (OEMS). OEMS provides the following services primarily through professional consultants:

- (1) exposure monitoring services;
- (2) building inspection/surveys (bulk sampling) for the identification of asbestos containing materials;
- (3) asbestos project design services;
- (4) asbestos abatement project and air monitoring services;
- (5) emergency response to fiber release episodes;
- (6) education/information;
- (7) medical monitoring;
- (8) training for School District of Philadelphia personnel

5. Responsibilities

a) Office of Environmental Management and Services

OEMS is responsible for performing the following functions:

- (1) Developing and administering of the Asbestos Management Program.
- (2) Providing asbestos-related services to all School District of Philadelphia departments.
- (3) Conducting required training of the Asbestos Management Program and working jointly with departments to schedule training.
- (4) Identifying and posting areas where labeling/signage are required.
- (5) Medical Monitoring of OEMS "A-TEAM" and other departments "AST" Asbestos Program staff.

- (6) Certification and training as required for OEMS "A-TEAM" and other departments "AST" Asbestos program staff.
- (7) Record keeping as outlined in Section 3.5 and all records as by required by US EPA AHERA regulations.

b) Asbestos Worker/Supervisor - "A-TEAM"

- (1) OEMS shall ensure that all "A-TEAM" workers/supervisors adhere to the following requirements:
 - a) Attend an initial Worker/Supervisor Asbestos Course;
 - b) Maintain the annual re-certification per EPA AHERA requirements and Commonwealth of Pennsylvania Asbestos Occupations, Accreditation and Certifications Act;
 - c) Undergo an annual Asbestos Medical Evaluation;
 - d) Undergo an annual Respirator Medical Clearance;
 - e) Undergo an annual Respirator Fit Testing.

c) Asbestos Designated Person

The Asbestos Designated Person is responsible for:

- (1) Assuring the health and safety of employees, students and visitors in the School District of Philadelphia facilities under his/her control.
- (2) Being kept informed of all areas under his or her jurisdiction where potential asbestos exposures exist and initiating protection programs that adhere to the Asbestos Management Program requirements of this manual.
- (3) Assuring that Asbestos Management Program requirements are adhered to by principal investigators, project managers, supervisors, or division heads, and School District of Philadelphia personnel under their supervision.
- (4) Ensuring that all employees within the Asbestos Management Program comply with (OSHA 1910.1001 (j) (7) (iv)) and the US EPA AHERA regulations by attending the required training.
- (5) Ensure the posting of:
 - a) Warning labels/signage
 - b) Commonwealth of Pennsylvania Asbestos Abatement and Demolition/Renovation Notification form
 - c) Asbestos Inspection Reports (AIR) form (where required)
 - d) Ensuring that Construction Projects follow the Demolition Directive procedures as outlined in the August 4, 2006 letter.

d) Supervisor or Project Manager (Capital, Maintenance and Facilities)

Each person in charge of a project, maintenance/repair, renovation/demolition, or other activity from the Departments of Capital, Maintenance, and/or Facilities, where asbestos containing material may be present is responsible for:

Identifying, with the assistance of OEMS, asbestos containing building materials prior to any disturbance of these materials. Various Federal (EPA and OSHA) and Local (City of Philadelphia Asbestos Control Regulations) require Asbestos Inspections prior to renovation/demolition activities. This shall be accomplished by always following the Asbestos Management Program Procedures as follows:

- (1) Ensure that the requirements of the Asbestos Management Program Procedures are followed by all personnel, trades, and contractors who are involved with the project;

- (2) Review of the required Asbestos Inspection Report (AIR) form (Attachment 1) and AHERA Management Plan documents prior to activities that may disturb any Asbestos Containing Materials;
- (3) Perform all project related duties as outlined in the Project Management Responsibilities;
- (4) Keep the department chairperson or director informed on any actions proposed or taken regarding the Asbestos Management Plan;
- (5) Ensuring that Construction Projects follow the Demolition Directive procedure outlined in the August 4, 2006 letter.

e) Employee – Capital

School District of Philadelphia Capital employees and/or consultants shall:

- (1) Ensure that no suspect or asbestos containing building materials are disturbed in the course of the projects they are performing or managing. This shall be accomplished by notifying their supervisor and OEMS by issuance of a work order permit (a.k.a PSIT Service Request Form) and verifying that the materials which may be disturbed are non-asbestos containing. If this information is not available or verification has not been made, these materials should not be disturbed.
- (2) Immediately notify OEMS and their supervisor in the event of a potential fiber release episode upon discovery of visible damage to asbestos containing materials.
- (3) Ensuring that Construction Projects follow the Demolition Directive procedures as outlined in the August 4, 2006 letter.

The types of projects represented as part of the Capital Improvement Program are as follows:

- (1) Complete Renovation of an existing building that addresses all facility component concerns and educational program needs;
- (2) Major Renovation of an existing building addressing significant facility component and educational improvements;
- (3) Addition to an existing building (either as an attachment or stand-alone structure) to accommodate needed program space;
- (4) Conversion of an existing facility to accommodate a change in educational program;
- (5) Facility Component Improvement of specific facility needs (i.e. electrical or HVAC system upgrades, ADA improvements, life safety improvements, exterior renovations, etc.)

f) Employee – Maintenance

School District of Philadelphia Maintenance employees shall:

- (1) Ensure that no suspect or asbestos containing building materials are disturbed in the course of their duties or work they are performing. This shall be accomplished by notifying their supervisor and OEMS by issuance of a work order permit and verifying that the materials which may be disturbed are non-asbestos containing. If this information is not available or verification has not been made, these materials should not be disturbed.
- (2) Immediately notify OEMS and their supervisor in the event of a potential fiber release episode or upon discovery of visible damage to asbestos containing materials.
- (3) All employees involved in maintenance activities shall attend required Asbestos Awareness training program within 60 days of employment.

g) Employee – Facilities & Custodial

School District of Philadelphia Facilities and Custodial employees shall:

- (1) Ensure that no suspect or asbestos containing building materials are disturbed in the course of their duties or work they are performing. This shall be accomplished by notifying their supervisor and OEMS by issuance of a work permit and verifying that the materials which may be disturbed are non-asbestos containing. If this information is not available or verification has not been made, these materials should not be disturbed;
- (2) Immediately notify OEMS and their supervisor in the event of a potential fiber release episode or upon discovery of visible damage to asbestos containing materials.
- (3) All employees involved in Facilities and Custodial activities shall attend require Asbestos Awareness training program within 60 days of employment.

6. Requirements

a) Employee Exposure Monitoring

When information indicates that an employee's exposure to asbestos fibers may equal or exceed an 8-hour time-weighted average of 0.1 f/cc * (per OSHA 1910.1001 & 1926.1101), OEMS shall develop and implement an asbestos exposure monitoring program. The sampling strategy shall be designed to identify employees by work task (job classification) that is exposed to asbestos fibers that exceed an 8-hour time-weighted average of 0.1 f/cc.

b) Employee Notification

OEMS shall notify in writing, each employee exposed to asbestos fibers at or above an 8-hour time weighted average of 0.1 f/cc.

c) Observation and Monitoring

OEMS shall provide employees or their representatives with an opportunity to observe any exposure measurements conducted.

d) Training Program

OEMS shall institute a training program which meets the requirements of AHERA for all employees who perform maintenance operations in a facility/school which contains asbestos containing materials or presumed asbestos containing materials and 1910.1001 (j), and the Commonwealth of Pennsylvania Department of Labor and Industry and the City of Philadelphia Asbestos Control Regulations. The affected departments shall ensure employee participation in this program. The OEMS "A-TEAM" and other departments "AST" Asbestos Program staff training shall be conducted annually for each employee as required by all Federal, State and Local for each asbestos discipline.

All Asbestos Awareness training as required by AHERA shall be performed within 60 days of employment and shall include:

- Health effects of asbestos
- Locations of ACM and PACM in the building/facility
- Recognition of CM and PACM damage and deterioration
- Requirements of the OSHA 1910.1001 standard relating to maintenance
- Proper response to fiber release episodes
- Procedure to be followed to isolate areas affected by fiber release

e) Access to Information

OEMS shall make available to affected employees or their representative's copies of the Occupational Safety and Health Administration (OSHA) General Industry Standard Part 1910.1001 and the department shall post a copy in the workplace.

f) Record Keeping

OEMS shall maintain an accurate record of all employee exposure measurements. OEMS and/or the School District of Philadelphia Human Resources Department shall maintain records of employee medical monitoring program. OEMS shall maintain all employee training records. All records shall be provided upon request to employees, former employees, representatives designated by the individual employee.

7. AHERA OPERATIONS AND MAINTENANCE PLAN

a) CONTROLS

i. Work Order System

Minimizing disruption of ACM/PACM during maintenance and renovation activities is the primary goal and task encountered by OEMS. Operations and maintenance employees and contractors should be warned to avoid conducting any maintenance work which may disturb ACM/PACM. Initiating a work order system, where all work orders or requests are channeled through the Office of Environmental Management and Services (OEMS), will be the method used to control and minimize disruption of ACM/PACM.

Any work performed by in-house personnel or contractors that could or will impact ACM/PACM shall be coordinated by OEMS. A completed Asbestos Inspection Report Form (Attachment 1) shall be issued to in-house personnel and/or all contractors whose work could impact ACM/PACM. This form should accompany each contract issued to an outside contractor and posted on the jobsite.

All work order requests for maintenance and renovation activities in areas where ACM/PACM is suspected or known to be present are to be submitted to OEMS prior to proceeding with work. OEMS is responsible for reviewing asbestos survey records for information about the presence of ACM/PACM in the area where the work is to be performed. OEMS should physically inspect the area to ensure existing records reflect actual conditions. If no asbestos is present, a work order is not necessary and the planned actions can proceed. If ACM/PACM is found to be present in the area, OEMS will sign the work order application and obtain an approved and accredited asbestos contractor or assign OEMS "A-TEAM" to abate the ACM/PACM.

ii. Regulated Areas

The owner will identify and regulate all areas where airborne concentrations of ACM/PACM exceed the Permissible Exposure Limit (PEL)* (Per OSHA determined to be 0.1 f/cc) and/or short term exposure limit (STEL) (Per OSHA determined to be 0.1 f/cc), or there is reasonable possibility that the (PEL) and/or (STEL) may be exceeded. All ACM/PACM removal activities involving thermal system insulation ACM/PACM (Class I), surfacing ACM/PACM (Class I), and miscellaneous ACM/PACM such as floor tile, roofing, and siding mastic, etc. (Class II), and repair and maintenance operations where thermal system insulation and surfacing ACM/PACM is likely to be disturbed (Class III) will be performed in accordance with federal, state, and local regulations. All asbestos abatement work and activities will be designed and managed as asbestos regulated areas. These areas will be demarcated and labeled.

iii. Warning Signs

Warning signs shall be displayed at all approaches to each asbestos regulated area. The asbestos abatement contractor will provide OSHA warning signs in all regulated areas during removal, repair, and other maintenance activities. OEMS will provide AIRs to all contractors who must inform all employees and supervisors working in locations contiguous to asbestos regulated areas of the potential hazards and work practices required.

iv. Warning Labels

Warning labels and/or signage shall be affixed to all raw materials, mixtures, scrap, waste, debris, and other products containing asbestos fibers, or to their containers. Generally, the asbestos abatement contractor or OEMS A-Team personnel will provide all warning labels for ACM/PACM containment.

8. O & M RESPONSE ACTIONS

The Asbestos Management Program general O&M procedures are outlined in this section. Additional requirements specific to asbestos abatement activities are included in the Project Design documents for all Asbestos Abatement Work. Regular cleaning, inspection, and reporting of ACM/PACM deterioration or other problems must be diligently practiced by all employees including custodial and maintenance personnel.

a) Facility Maintenance Isolation of Area Responsibilities

Maintenance personnel are often required to work in areas where ACM/PACM may potentially be disturbed. Most maintenance activities are conducted by in-house staff, outside contractors, or a combination.

Emergency fiber release episodes, such as pipe fitting or valve breaks, emergency boiler work, or mechanical equipment repair will be responded to by OEMS A-Team personnel or asbestos abatement contractor personnel. The owner's maintenance staff will: (1) isolate the emergency fiber release area; (2) post warning signs to prevent unauthorized access, and (3) notify their supervisor and OEMS. OEMS will ensure that the fiber release area remains isolated and is properly cleaned by and approved and accredited abatement contractor or by OEMS A-TEAM personnel.

b) Unlikely Contact with ACM/PACM

Maintenance activities or repairs which can be performed without contacting or disturbing the ACM/PACM require little more than normal care and good workmanship. For example, valves which are either uncovered or covered with non-asbestos insulation can be packed or repaired without disturbing asbestos insulation on nearby pipes. The major precaution is to ensure that maintenance and custodial personnel are familiar with procedures such as isolating the area, posting warning signs, and notifying OEMS in the event of any accidental ACM/PACM disturbance.

c) Accidental Disturbance of ACM/PACM

Maintenance and facilities personnel shall notify OEMS any time a fiber release is suspected. If friable ACM/PACM becomes airborne in the building,

d) Planned Disturbance of ACM/PACM

Maintenance activities that may impact ACM/PACM include access to a valve, flange, duct, or related system component.

Where asbestos-containing insulation must be removed to maintain or repair the thermal system, the ACM/PACM will imminently be disturbed. ACM/PACM removal work shall be conducted by OEMS A-Team personnel or an approved and accredited asbestos abatement contractor.

If friable ACM/PACM becomes airborne in the building, maintenance and facilities personnel shall secure the area and contact OEMS. OEMS shall respond accordingly.

e) Miscellaneous ACM/PACM

Miscellaneous types of ACM/PACM may include vinyl asbestos floor tiles, mastics/adhesives and woven vibration dampers. Disturbance of these materials should be avoided. Routine maintenance activities involving these materials should not pose a problem if handled properly. Questions on the proper removal and disposal of miscellaneous ACM/PACM should be directed to OEMS. OEMS will contact an approved and accredited asbestos abatement contractor or utilize OEMS A-TEAM personnel to assist with miscellaneous ACM/PACM clean-up activities.

f) Vinyl Asbestos Floor Tile

Asbestos-containing floor tiles in good condition are considered non-friable unless they are crushed, drilled, sawed, sanded or disturbed by any activity that breaks up the material. Routine maintenance of these materials should employ the use of non-abrasive buffers and wet cleaning technique. Broken or loose floor tiles should be removed and disposed of as asbestos waste by OEMS. Remaining debris should be vacuumed with a HEPA vacuum and the area wet mopped using amended water.

g) Mastics/Adhesives

Mastics and adhesives containing asbestos in good condition are considered non-friable and do not pose a potential health concern unless crushed, drilled, sawed, sanded, or otherwise abraded. Questions on the proper removal should be directed to OEMS.

h) Woven Vibration Dampers

Woven vibration dampers in good condition are considered non-friable and do not pose a potential health concern unless cut, crushed, drilled, sawed, sanded, or otherwise abraded. Questions on the proper removal should be directed to OEMS.

i) Other Work Practices

Any special work not included in this section should be addressed to OEMS for review prior to the initiation of work that may involve the disturbance of ACM/PACM.

j) Fiber Release Episodes

Facilities and maintenance staff should report to OEMS the presence of asbestos debris, water or physical damage to ACM/PACM, or any other evidence of possible fiber release. OEMS should have the OEMS A-Team personnel or an approved and accredited abatement contractor respond to the site to clean up debris and make repairs as soon as possible. OEMS will also contact a consultant to conduct air monitoring and prepare a report and submit at project completion to OEMS for each episode. OEMS will forward the reports for each site location AHERA Management Plan accordingly.

9. REFERENCES and RESOURCES

Applicable regulations for asbestos projects impacted by renovation, demolition, and maintenance activities.

- **Philadelphia Air Management Services – Asbestos Control Unit**
<http://www.phila.gov/health/units/ams/Asbestos/asbestos.html>
- **Pennsylvania Asbestos Occupations, Accreditation and Certification Act**
<http://www.dli.state.pa.us/landi/cwp/view.asp?a=185&q=56262&landiNav=>
- **United States Environmental Protection Agency Asbestos Home Page**
<http://www.epa.gov/asbestos/>
- **Occupational Safety and Health Administration (OSHA) Asbestos Home**
<http://www.osha.gov/SLTC/asbestos>