

# SCHOOL DISTRICT OF PHILADELPHIA



## Asbestos Hazard Emergency Response Act “AHERA”

### THREE-YEAR RE-INSPECTION 2015-2016 and ASBESTOS MANAGEMENT PLAN for the

**New Abraham Lincoln High School**

**ULCS# 8010  
Building # B801001-1  
3201 Ryan Avenue  
Philadelphia, Pennsylvania  
19136**

**Year Built: 2009**

December 2016

*Conducted By:*

Accredited Environmental Technologies, Incorporated  
Batta Environmental Associates, Incorporated  
Criterion Laboratories, Incorporated  
Environmental Testing Consultants, LLC  
G & C Environmental Services, Incorporated  
KEM Partners, Incorporated  
Synertech, Inc.  
TTI Environmental, Inc.  
USA Environmental Management, Inc.  
The Vertex Companies, Inc.

*Management Plan Prepared By:*

Criterion Labs, Inc and Synertech Inc.

*This report must remain in the Main Office as mandated by the US EPA AHERA Regulations.*

# **AHERA THREE-YEAR REINSPECTION VOLUME IX**

## **Table of Contents**

### **Transmittal Letter**

### **Executive Summary**

- I. Summary list of Confirmed Asbestos Containing Building Materials
- II. Summary list of Assumed Asbestos Contain Building Materials
- III. Summary list of Non-Asbestos Containing Building Materials
- IV. Summary list of Non Suspect Asbestos Containing Building Materials
- V. Summary List of Auditorium DATA for this location
- VI. Summary list of Attic and/or Crawlspace DATA for this location
- VII. Summary list of Pipe Chase/Pipe Shaft DATA for this location

### **Section I Report of Re-Inspection**

- A. Introduction
- B. Three-Year Re-inspection IX Overview
- C. Post- Management Plan Activities and Changes
  - C.1 - Sampling and Analysis
  - C.2 - New Floor Tile Sampling
  - C.3 - Abatement Activity
  - C.4 - Periodic (Six-Month) Surveillance (Damaged Materials)

### **Section II Re-Inspection Data**

- A. Introduction
- B. Re-Inspection Key Definitions
- C. Room by Room Location Log Report

### **Section III Certificates**

- A. Management Planner/Building Inspector Certificates

<b>Section IV</b>	<b>Cross Reference Table</b>	Page 1-8
	Asbestos Management Program	Page 9-19

SCHOOL DISTRICT OF PHILADELPHIA  
EDUCATIONAL CENTER  
440 NORTH BROAD STREET  
PHILADELPHIA, PENNSYLVANIA 19130

OFFICE OF ENVIRONMENTAL MANAGEMENT AND SERVICES

PHONE (215)-400-4750

January 2016


TO: All Principals  
All Building Administrators

FROM: Fran Burns  
Chief Operating Officer


Francine Locke, M.S., Director  
Office of Environmental Management and Services

SUBJECT: AHERA Three (3) Year Re-inspection IX report

In order to comply with the provisions of the Asbestos Hazard Emergency Response Act (AHERA) the attached report is submitted to you. The law requires that this report be kept in the Main/Principal's office. It cannot be removed from these locations. *If the school (program) is relocated to a different building, these environmental documents are to be safely retained for the next school/building occupants.* All asbestos reports must be available to the public and Federal EPA upon request.



Fran Burns  
Chief Operation Officer



Francine Locke, M.S., Director  
Office of Environmental Management  
and Services

## **Executive Summary**

This Asbestos Hazard Emergency Response Act (AHERA) Three-Year Re-inspection “Volume # IX” Management Plan at this location, has been completed and the report of re-inspection submitted to the School District of Philadelphia. The re-inspections in all School District of Philadelphia buildings of 2015-2016 were conducted and completed between October 5<sup>th</sup>, 2015 through March 30<sup>th</sup>, 2016 as a joint project by Accredited Environmental Technologies, Inc., Batta Environmental Associates, Inc., Criterion Laboratories, Inc., Environmental Testing Consultants, LLC, G & C Environmental Services, Inc., KEM Partners, Inc., Synertech, Inc., TTI Environmental, Inc., USA Environmental Management, Inc. and The Vertex Companies, Inc.

In general, the School District of Philadelphia Office of Environmental Management and Services conducts Environmental Impact Evaluations and provides Asbestos Inspection Reports prior to any renovation, demolition and/or maintenance activities. The AHERA report must be reviewed prior to any renovation, demolition and/or maintenance activities in order to avoid the unknowing disturbance to Asbestos Containing Building Materials identified within this location. In addition, prior to work activities above all drop ceilings this report should be reviewed to avoid potential disturbances to Asbestos Containing Materials. Refer to Section IV of the Cross Reference Table, for additional Asbestos Management Program information. Contact the Office of Environmental Management and Services to have an Environmental Impact Evaluation conducted prior to any renovation, demolition and/or maintenance activities within this facility.

The information contained in this report was obtained from the original Asbestos Management Plan for the school, from update reports on changes and activities since the completion of the 1<sup>st</sup> Management Plan for each location and from all prior inspections performed and documented in Volume # I through Volume VIII (dated respectively 1992, 1995, 1998, 2001, 2004, 2007, 2010 or 2013) (if applicable)- and by this Three-Year Re-inspection of this school. The re-inspection report/Management Plan of 2015-2016 were reviewed and prepared collectively by Management Planner Megan Vala, Mary Anne Lerro of Criterion Laboratories, Inc. and/or Monique Causley, of Synertech Inc.

The 2015-2016 inspection process included the addition of a comprehensive Room by Room Inventory of all Thermal (T), Surfacing (S) and Miscellaneous (M) Materials specific to each room of this facility. Inspections of each room's thermal, ceilings, walls, floors and miscellaneous items regardless of Asbestos Content are categorized on the Room by Room Location Log Report for this location. Rooms or areas of the facility that were not accessible at the time of the inspection are marked with an "X". The Room by Room Location Log Report is found in Section II C of this Management Plan.

All Presumed or Suspect Asbestos Containing Building Materials (ACBMs), listed in the following summary charts are categorized as Confirmed, Assumed, Non-Asbestos, and/or Non-Suspect (ACBMs) were identified in the original Management Plan, or in the Volume I through Volume VIII AHERA Three-Year Re-inspection reports, and were re-inspected as part of this project.

As mandated by the U S EPA AHERA regulations, periodic Six-Month inspections and Three-Year Re-inspections of this location will be performed and the Inspection Data in this report will be updated accordingly.

Please feel free to contact the School District of Philadelphia's Office of Environmental Management and Services (OEMS) regarding any comments, questions, or concerns regarding this report or any Environmental related topic. OEMS staff can be reached at (215) 400 4750, via fax at (215) 400 4751 or via e-mail at [flocke@philasd.org](mailto:flocke@philasd.org) and/or [gfunod@philasd.org](mailto:gfunod@philasd.org).

Additional information can be found on our website. Here is the link to the OEMS website.  
<http://webgui.phila.k12.pa.us/offices/e/environmental>

## **I. Summary list of Confirmed Asbestos Containing Building Materials within this facility**

These charts are to be used for a quick reference\* in order to avoid the unknowing disturbance of Asbestos Containing Materials during any and all Operations, Maintenance, Renovation, and/or Demolition activities at this location. *These materials have been sampled and Laboratory Analysis has CONFIRMED the presence of Asbestos. Contact OEMS prior to the disturbance of any of the following materials.*

### **Confirmed Asbestos Containing Building Materials for this location**

*Since this facility was fully renovated and/or built after December 31, 1980 all suspect friable asbestos containing building materials do not exist in this facility.*

## **II. Summary list of Assumed Asbestos Containing Building Materials within this facility**

These charts are to be used for a quick reference\* in order to avoid the unknowing disturbance of Asbestos Containing Materials during any and all Operations, Maintenance, Renovation, and/or Demolition activities at this location. These materials have not been sampled and should not be disturbed until verification of Asbestos Content. Contact OEMS for assessment and sampling prior to the disturbance of these materials.

### **Assumed Asbestos Containing Building Materials for this location**

*Since this facility was fully renovated and/or built after December 31, 1980 all suspect friable asbestos containing building materials do not exist in this facility.*

### III. Summary list of Non-Asbestos Containing Building Materials within this facility

These charts are to be used for a quick reference\* in order to avoid the unknowing disturbance of Asbestos Containing Materials during any and all Operations, Maintenance, Renovation, and/or Demolition activities at this location. *These materials have been sampled and Laboratory Analysis has indicated NO Asbestos present or NO ASBESTOS DETECTED (NAD).*

#### Non- Asbestos Containing Building Materials for this location

Floor Tile VAT 12" x 12"		
--------------------------	--	--

*\* Always refer to the Room by Room Logs for each specific material classification as the material classification findings may be different in various rooms throughout this facility.*

*\*\* Some Materials may have multiple classifications (Confirmed, Assumed, NAD and Non Suspect) within this facility.*



#### **IV. Summary list of Non-Suspect Asbestos Containing Building Materials within this facility**

These charts are to be used for a quick reference\* in order to avoid the unknowing disturbance of Asbestos Containing Materials during any and all Operations, Maintenance, Renovation, and/or Demolition activities at this location. These materials are not typically known to contain Asbestos.

##### **Non-Suspect Asbestos Containing Building Materials for this location**

Brick Wall	Carpet	Ceiling Tile 2' x 4'
Ceramic Tile Floors	Concrete Block Wall	Concrete Floor
Corrugated Metal Ceiling	Emergency Generator	Emergency Generator Insulation
Fiberglass Duct Insulation	Fiberglass Panels	Fiberglass Pipe Insulation
Fireproofing	Glass Wall	Kiln
Lab Table Tops/Sinks	Metal Ceiling	Metal Duct
Metal Walls	Neoprene Duct Insulation	Neoprene Pipe Insulation
Rubber Mat Floor	Rubber Tread Floor	Sheetrock Ceiling
Sheetrock Wall	Vinyl Vibration Damper Cloth	Wood Ceiling
Wood Floor		

*\* Always refer to the Room by Room Logs for each specific material classification as the material classification findings may be different in various rooms throughout this facility.*

*\*\* Some Materials may have multiple classifications (Confirmed, Assumed, NAD and Non Suspect) within this facility.*

## V. Summary list of Auditorium DATA for this location

These charts are to be used for a quick reference of the Auditorium DATA within this facility. Sampling of the Auditorium Ceilings throughout the District is more difficult because of the various ceiling heights. As sampling occurs this information is updated on a case by case basis for each specific location and facility.

### This is a list of known materials for this location's Auditorium

Auditorium 193	Floor Tile VAT 12" x 12"	NAD
Auditorium 193	Carpet	Non Suspect ACM
Auditorium 193	Concrete Block Wall	Non Suspect ACM
Auditorium 193	Corrugated Metal Ceiling	Non Suspect ACM
Auditorium 193	Fiberglass Pipe Insulation	Non Suspect ACM
Auditorium Stage	Wood Floor	Non Suspect ACM
Auditorium Stage	Concrete Block Wall	Non Suspect ACM
Auditorium Stage	Corrugated Metal Ceiling	Non Suspect ACM
Auditorium Stage	Fiberglass Pipe Insulation	Non Suspect ACM

*\* Always refer to the Room by Room Logs for each specific material classification as the material classification findings may be different in various rooms throughout this facility.*

*\*\* Some Materials may have multiple classifications (Confirmed, Assumed, NAD and Non Suspect) within this facility.*

## VI. Summary list of Attic and/or Crawlspace DATA for this location

These charts are to be used for a quick reference regarding the Attics and/or Crawlspaces inspection DATA within this facility. Contact OEMS prior to entering any attic or crawlspace within this facility and refer to the below chart and legend for Category Rank determination. The Data relative to these spaces is updated as conditions change regarding Abatement or Renovation activity on a case by case basis for each specific location and facility. In general, Crawlspaces are below the basement or 1<sup>st</sup> floor and Attics are above the floor space.

### *Category Rank Legend*

"A" - No Asbestos Containing Materials - Sample Results indicate NO ACM on pipes, fittings, elbows, or equipment located within this functional space, and NO VISIBLE DEBRIS or DAMAGE observed at time of this inspection.
"B" - Asbestos Containing Materials Exist - Sample Results indicate ACM on pipes, fittings, elbows, or equipment located within this functional space, HOWEVER, NO VISIBLE DEBRIS or DAMAGE observed at time of this inspection.
"C" - Asbestos Containing Materials Exist - Sample Results indicate ACM on pipes, fittings, elbows, or equipment located within this functional space, and LOCALIZED VISIBLE DEBRIS or DAMAGE observed at time of this inspection.
"D" - Asbestos Containing Materials Exist - Sample Results indicate ACM on pipes, fittings, elbows, or equipment located within this functional space and DISTRIBUTED VISIBLE DEBRIS or SIGNIFICANT DAMAGE observed at time of this inspection.
"E" - No Bulk Sample Results Available SUSPECT ACM OBSERVED. Contact OEMS immediately for additional instructions.

Attic/Crawlspace	Access Area	Floor Surface	Category Rank	Comments
Attic	X	X	X	No Attic
Crawlspace	X	X	X	No Crawlspace

## **VII. Summary list of Pipe Chase/Pipe Shaft DATA for this location**

These charts are to be used for a quick reference regarding the information known about the Pipe Chases and/or Pipe Shafts inspection DATA within this facility. Contact OEMS prior to performing renovation activities any Pipe Chase and/or Pipe Shaft within this facility and refer to the below chart and legend for Asbestos Content of various materials identified within each space. The Data relative to these spaces is updated as conditions change regarding Inspection, Abatement and/or Renovation activity on a case by case basis for each specific location and facility. In general, Pipe Chases are horizontal spaces and Pipe Shafts are vertical spaces.

***Pipe Chases and Pipe Shafts need to be assessed.***

**Section I                      Report of Re-Inspection**

**A. Introduction**

**B. Three-Year Re-Inspection IX Overview**

**C. Post-Management Plan Activities and Changes**

**C.1      Sampling and Analysis**

**C.2      New Floor Tile Sampling**

**C.3      Abatement Activity**

**C.4      Periodic Six-Month Surveillance (Damaged Materials)**

## **Section I - A**

### **Report of Re-inspection**

#### **Introduction**

The Three-Year Re-inspection IX was performed to fulfill the requirements of 40 CFR Part 763 - the Asbestos Hazard Emergency Response Act (AHERA). As required by AHERA, each Local Education Agency (LEA) must re-inspect all known confirmed or assumed Asbestos Containing Building Material (ACBM) located in the LEA's facilities. This re-inspection is intended to update the original Asbestos Management Plan for the LEA's facilities.

Multiple Building Inspectors of several firms performed the 2015/2016 re-inspection. The re-inspection report/Management Plan of 2015-2016 were reviewed and prepared collectively by Management Planner Megan Vala, Mary Anne Lerro of Criterion Laboratories, Inc. and Monique Causley, of Synertech Inc.

All of the certificates can be found in Section III.

During the re-inspection of each School District of Philadelphia facility, all of the Management Plans for that facility were reviewed. Information from the conclusions section of that report is included in this report. Additionally, information on activities such as abatements, cleanings, sampling and inspections, which have taken place since the completion of the original Management Plan, were reviewed during the re-inspection. Information on those activities are included in this report.

As mandated by the U S EPA AHERA regulations, all future periodic Six-Month inspections and Three-Year Re-inspections of this location will be performed and the Inspection Data in this report will be updated accordingly.

## Section I - B

### **Three-Year Re-inspection IX Overview**

Each homogeneous area of Asbestos Containing Building Material (ACBM) listed in the original Management Plan or in the 1992, 1995, 1998, 2001, etc., Three-Year Re-inspection reports were inspected for the AHERA Three-Year Re-inspection Volume IX, and the information for that material verified. Any changes to a homogeneous area listed in the updates to the Management Plans were verified. Any area of suspected ACBM found in the course of the re-inspection, and not listed in the Management Plan or updates, were either assumed to contain asbestos or sampled and analyzed to determine their asbestos content. Any such new areas either assumed to contain asbestos or determined through analysis to contain asbestos were included in the report of the Three-Year Re-inspection. The results of the AHERA Three-Year Re-inspection IX are tabulated in the Room by Room log reports located in *Section II-C* of this report.

As previously noted, all future periodic Six-Month inspections and Three-Year Re-inspections of this location will be performed and the Inspection Data in this report will be updated accordingly.

## Section I – C.1

### **Post Management Plan Activities/Changes**

Information on activities affecting Asbestos Containing Building Materials (ACBMs) at this location is contained in updates to the Management Plan. These updates are kept on file by the School District of Philadelphia and were reviewed for this project. Updates to the Management Plan include the following: *Sampling and Analysis, New Tile Installation, Abatement Activity and Periodic Six-Month Surveillance Data.*

#### **Sampling and Analysis**

*In the event Sampling occurs, data will be listed here.*



## **Section I – C.2**

Information on the installation of new floor tiles/renovation activities affecting Asbestos Containing Building Materials (ACBMs) at this location is contained in updates to the Management Plan. These updates are kept on file by the School District of Philadelphia and were reviewed for this project. Updates to the Management Plan include the following:

### **New Floor Tile Sampling**

***In the event that new tile is installed, the material must be tested prior to installation.***

## **Section I – C.3**

Information on the Asbestos Abatement and renovation activities affecting Asbestos Containing Building Materials (ACBMs) at this location is contained in updates to the Management Plan. These updates are kept on file by the School District of Philadelphia and were reviewed for this project. Updates to the Management Plan include the following:

### **Abatement Activity**

*In the event that Abatement occurs, data will be listed here.*

## Section I – C.4

Information on the AHERA inspection that noted damage to various Building Materials at this location is contained in updates to the Management Plan. These updates are kept on file by the School District of Philadelphia and were reviewed for this project. Work orders are created for Corrective Action responses and tracked for completion. Updates to the Management Plan include the following:

### **Periodic (Six-Month) Surveillance (Damaged Materials)**

*This building is excluded from having any asbestos-containing materials via sampling data. However, our inspections may, if observed, report findings of damaged materials in order for work orders to be issued for material repairs/corrective action as necessary.*

*Damaged materials reported in this section will be forwarded to maintenance for repairs.*

<i>Date</i>	<i>Element</i>	<i>Floor</i>	<i>On Site Room Name</i>	<i>Material</i>	<i>Amount of Material</i>	<i>Amount of Damage</i>
5/1/2017	1	1	Flower Shop 100A	Ceiling Tile 2' x 4'	550 SF	6 EA
5/1/2017	1	1	Classroom 105	Ceiling Tile 2' x 4'	1200 SF	2 EA
5/1/2017	1	1	Boy's Restroom across from Classroom 108	Ceiling Tile 2' x 4'	500 SF	3 EA
5/1/2017	1	1	Classroom 123	Sheetrock Wall	7500 SF	4 SF
5/1/2017	1	1	Classroom 123	Ceiling Tile 2' x 4'	2500 SF	6 EA
5/1/2017	1	1	Office 136A inside IMC (Library) 133	Ceiling Tile 2' x 4'	150 SF	2 EA
5/1/2017	1	1	Computer Room 156	Ceiling Tile 2' x 4'	1800 SF	12 EA
5/1/2017	1	1	Office 146	Ceiling Tile 2' x 4'	1400 SF	5 EA
5/1/2017	1	1	Science Classroom 160	Ceiling Tile 2' x 4'	1500 SF	5 EA
5/1/2017	1	1	Science Classroom 162	Ceiling Tile 2' x 4'	1500 SF	5 EA
5/1/2017	1	1	Classroom 170	Ceiling Tile 2' x 4'	900 SF	3 EA
5/1/2017	1	1	Front Storage Room inside Music Classroom 190	Ceiling Tile 2' x 4'	120 SF	13 EA
5/1/2017	1	1	Rear Storage Room inside Music Classroom 190	Ceiling Tile 2' x 4'	120 SF	8 EA
5/1/2017	1	1	Boy's Locker Room 196A	Sheetrock Ceiling	2500 SF	2 SF
5/1/2017	1	2	Science Classroom 201	Ceiling Tile 2' x 4'	1500 SF	5 EA

## **Section II**

### **Re-Inspection Data**

#### **A. Introduction**

#### **B. Re-Inspection Key Definitions**

#### **C. Room by Room Location Log Report**

## **Section II - A**

### **Re-inspection Data**

#### Introduction

The following information documents the Three-Year Re-inspection IX of the subject school/facility. The Homogeneous Area Reports were produced using the building inspector's field data on the facility. The key to the Homogeneous Area Report is outlined in the following pages of this report.

**Section II - B**  
**(page 1 of 4)**

**SCHOOL DISTRICT OF PHILADELPHIA**  
**AHERA THREE YEAR RE-INSPECTION IX**

<b>ITEM</b>	<b>DEFINITION</b>
<b>ULCS#</b>	Individual identification number assigned to each school within the School District of Philadelphia.
<b>HOMOGENEOUS AREA ID#</b>	Identification number assigned to each homogeneous area in a school/facility. Each section of the homogeneous area ID is significant.  1010/01/01/01 <b>A B C D</b>  <b>A.</b> Is the ULCS# for the school. <b>B.</b> Designates the specific building/building area within the school. <b>C.</b> Designates the floor or level within the building/building area. <b>D.</b> Designates the homogeneous material within that floor or level. Note: Item D may be a number or a letter.
<b>SYSTEM AFFECTED</b>	Corresponds to the AHERA system for classifying materials.  <b>T</b> : Thermal System <b>S</b> : Surfacing System <b>M</b> : Miscellaneous
<b>ITEM AFFECTED</b>	Is a description of the homogeneous material.
<b>ORIGINAL INSPECTION DATA</b>	This section contains the information found in the original Management Plan (1988-1989).
<b>AMOUNT OF MATERIAL/ UNIT</b>	Quantity of material, and measuring unit. Units include: Square Feet (SF) Each (EA) Linear Feet (LF) Cubic Feet (CF).

**SCHOOL DISTRICT OF PHILADELPHIA  
AHERA THREE YEAR RE-INSPECTION IX**

**RE-INSPECTION FORM KEY**

<b>ITEM</b>	<b>DEFINITION</b>
<b>CND Condition</b>	Corresponds to AHERA condition rating for materials.  <b>0</b> : No Damage <b>1</b> : Damage <b>2</b> : Significant Damage
<b>DP Damage Potential</b>	Corresponds to the AHERA material assessment system.  <b>1</b> : Potential for Damage <b>2</b> : Potential for Significant Damage
<b>ASMD Assumed Asbestos</b>	This means that a material was not sampled for asbestos content during the original Management Plan inspection.
<b>RA Response Action</b>	This corresponds to the AHERA system of response action rating for materials.  <b>1</b> : Establish O&M Program <b>2</b> : Repair and Establish O&M Program <b>3</b> : Enclose <b>4</b> : Encapsulate <b>5</b> : Remove <b>6</b> : Partial Removal and Establish O&M Program
<b>CHANGES</b>	This section describes changes to the homogeneous material in the twenty-four years since the original AHERA inspection. The abbreviations are defined below.  <b>RMVD</b> : Removed <b>ENCL</b> : Enclosed <b>ENCP</b> : Encapsulated <b>DMGD</b> : Damaged <b>SMPLD</b> : Sampled <b>MTRL</b> : Material <b>RPRD</b> : Repaired <b>N/L</b> : None Located <b>RPLCD</b> : Replaced

**SCHOOL DISTRICT OF PHILADELPHIA  
AHERA THREE-YEAR RE-INSPECTION IX**

**RE-INSPECTION FORM KEY**

<b>ITEM</b>	<b>DEFINITION</b>												
<b>THREE YEAR RE-INSPECTION</b>	<p>This section contains the information obtained from the Three-Year Re-inspection IX. With three exceptions, the information categories are identical in format and meaning to those found in the original inspection data section. The three exceptions are defined below.</p>												
<b>DMGD AMT Amount Damaged</b>	<p>This section gives the quantity of damaged material in a homogeneous area. The quantity is shown in the same format as the amount of material/unit section.</p>												
<b>NF Newly Friable</b>	<p>This section identifies materials in the original Management Plan which have since become friable.</p>												
<b>RA Response Action</b>	<p>This rating is based on the AHERA regulations, and is comparable to the RA rating found in the "Original Inspection Data" section. The following table details the response actions.</p> <table><tr><td>1.</td><td>Establish O&amp;M Program</td></tr><tr><td>2.</td><td>Repair and Establish O&amp;M Program</td></tr><tr><td>3.</td><td>Enclose</td></tr><tr><td>4.</td><td>Encapsulate</td></tr><tr><td>5.</td><td>Remove</td></tr><tr><td>6.</td><td>Partial Removal and Establish O&amp;M Program</td></tr></table> <p>a.   <b>High Priority Response</b> The homogeneous material has been scheduled for abatement or other response action.</p> <p>b.   <b>Medium Priority Response</b> The homogeneous material will be scheduled for abatement or other response action as soon as the high priority responses have been addressed.</p> <p>c.   <b>Low Priority Response</b> The homogeneous material will be scheduled for abatement or other response action as soon as the medium priority responses have been addressed.</p> <p>d.   <b>On-Going Response/Operations and Maintenance</b> The homogeneous material does not require abatement or other response action at present, and should be included in the facility's on-going operations and maintenance program.</p>	1.	Establish O&M Program	2.	Repair and Establish O&M Program	3.	Enclose	4.	Encapsulate	5.	Remove	6.	Partial Removal and Establish O&M Program
1.	Establish O&M Program												
2.	Repair and Establish O&M Program												
3.	Enclose												
4.	Encapsulate												
5.	Remove												
6.	Partial Removal and Establish O&M Program												



**SCHOOL DISTRICT OF PHILADELPHIA  
AHERA THREE-YEAR RE-INSPECTION IX**

**RE-INSPECTION FORM KEY**

---

The information presented in the changes section has been compiled from a variety of sources, including the Re-inspection and the following:

- \* Quality Control/Quality Assurance Reports of asbestos abatement projects, prepared by consultants to the School District.
- \* Permit and Notification Forms for asbestos abatement projects.
- \* Periodic Surveillance Forms
- \* Operations and Maintenance activities performed by School District personnel.
- \* Verbal information from School District personnel.
- \* Reports of sampling and analysis of suspected materials by both School District personnel and outside consultants.

**ROOM BY  
ROOM  
LOCATION LOG  
REPORT**

This section gives information, including damage amount and location, for a specific homogeneous material on a room-by-room basis and follows the Re-inspection form.

*NOTE:* The disparate nature of the above sources of information prohibits the verification of much information within the scope of the AHERA Three-Year Re-inspection. Discrepancies and omissions may exist in this information, and therefore is included on an "as is" basis. The inspectors for the Three-Year Re-inspection IX evaluated homogeneous areas based on the materials current condition and location, as evidenced during the inspector's site visit.

## Section II - C

### Room by Room Location Log Report

These charts are to be used for a quick reference\* in order to avoid the unknowing disturbance of Asbestos Containing Materials during any and all Operations, Maintenance, Renovation, and/or Demolition activities at this location.

*NOTE:*

*Contact OEMS prior to the disturbance of any of the materials that are listed as **Confirmed and/or Assumed**.*

*The quantities listed for (NAD) non-asbestos containing materials and/or Non-Suspect Materials are only estimated and were not measured for the purpose of this report. Field verification of quantities for renovation purposes would be necessary.*

# 8010 New Lincoln - Room by Room Location Log Report.xls

		School District of Philadelphia New Lincoln High School 3201 Ryan Avenue, Philadelphia, PA 19136 ULCS# 8010 Year Built: 2009	AHERA Three-Year Reinspection 2015-2016 Room by Room Location Log Report								Reinspection Date: December 30, 2016	
											Building Inspector: Bernard J Bryson	
											Number: ACC-0125-6-031	
											Management Planner: Megan Vala	
											Number: 740728	
<i>E l e m e n t</i>	<i>F l o o r</i>	<i>On Site Room Name</i>	<i>System Affected</i>	<i>Material Description</i>	<i>Confirmed/Assumed/NAD/ Non Suspect ACM</i>	<i>Amount of Material</i>	<i>SF LF EA</i>	<i>Amount of Damage</i>	<i>SF LF EA</i>	<i>Color required for VAT</i>	<i>Comments/Description/Notes</i>	<i>Attic/ Crawl Space Ranking</i>
1	1	Main Entrance Vestibule	N/A	Rubber Tread Floor	Non Suspect ACM	200	SF	0	SF	Black		
1	1	Main Entrance Vestibule	N/A	Glass Wall	Non Suspect ACM	600	SF	0	SF			
1	1	Main Entrance Vestibule	N/A	Sheetrock Ceiling	Non Suspect ACM	200	SF	0	SF			
1	1	Main Entrance Hallway	N/A	Floor Tile VAT 12" x 12"	NAD	10,000	SF	0	SF	Grey		
1	1	Main Entrance Hallway	N/A	Brick Wall	Non Suspect ACM	10,000	SF	0	SF			
1	1	Main Entrance Hallway	N/A	Concrete Block Wall	Non Suspect ACM	10,000	SF	0	SF			
1	1	Main Entrance Hallway	N/A	Sheetrock Wall	Non Suspect ACM	10,000	SF	0	SF			
1	1	Main Entrance Hallway	N/A	Corrugated Metal Ceiling	Non Suspect ACM	8500	SF	0	SF			
1	1	Main Entrance Hallway	N/A	Ceiling Tile 2' x 4'	Non Suspect ACM	1500	SF	0	SF			
1	1	Main Entrance Hallway	N/A	Fiberglass Pipe Insulation	Non Suspect ACM	500	LF	0	LF			
1	1	Main Entrance Hallway	N/A	Fireproofing	Non Suspect ACM	100	SF	0	SF			
1	1	Cafeteria	N/A	Floor Tile VAT 12" x 12"	NAD	10,000	SF	0	SF	Grey	12"x 12" Grey with a few Red Floor Tile Accents	
1	1	Cafeteria	N/A	Concrete Block Wall	Non Suspect ACM	30,000	SF	0	SF			
1	1	Cafeteria	N/A	Corrugated Metal Ceiling	Non Suspect ACM	10,000	SF	0	SF			
1	1	Cafeteria	N/A	Sheetrock Ceiling	Non Suspect ACM	500	SF	0	SF		Sheetrock Soffits along Kitchen Serving Line	
1	1	Cafeteria	N/A	Fiberglass Pipe Insulation	Non Suspect ACM	200	LF	0	LF			
1	1	Cafeteria	N/A	Fiberglass Duct Insulation	Non Suspect ACM	40	SF	0	SF			
1	1	Cafeteria	N/A	Fireproofing	Non Suspect ACM	60	SF	0	SF			
1	1	Kitchen	N/A	Ceramic Tile Floors	Non Suspect ACM	2200	SF	0	SF			
1	1	Kitchen	N/A	Concrete Block Wall	Non Suspect ACM	3300	SF	0	SF			
1	1	Kitchen	N/A	Sheetrock Wall	Non Suspect ACM	3300	SF	0	SF			
1	1	Kitchen	N/A	Ceiling Tile 2' x 4'	Non Suspect ACM	2200	SF	0	SF			
1	1	Food Storage Room	N/A	Concrete Floor	Non Suspect ACM	800	SF	0	SF			
1	1	Food Storage Room	N/A	Concrete Block Wall	Non Suspect ACM	1200	SF	0	SF			
1	1	Food Storage Room	N/A	Sheetrock Wall	Non Suspect ACM	1200	SF	0	SF			
1	1	Food Storage Room	N/A	Corrugated Metal Ceiling	Non Suspect ACM	800	SF	0	SF			
1	1	Food Storage Room	N/A	Fiberglass Pipe Insulation	Non Suspect ACM	100	LF	0	LF			
1	1	Food Storage Room	N/A	Neoprene Duct Insulation	Non Suspect ACM	5	SF	0	SF		Around Heating Coils	
1	1	Food Storage Room	N/A	Vinyl Vibration Damper Cloth	Non Suspect ACM	5	SF	0	SF			
1	1	Walk-In Refrigerator – Right	N/A	Ceramic Tile Floors	Non Suspect ACM	225	SF	0	SF			
1	1	Walk-In Refrigerator – Right	N/A	Metal Walls	Non Suspect ACM	675	SF	0	SF			
1	1	Walk-In Refrigerator – Right	N/A	Metal Ceiling	Non Suspect ACM	225	SF	0	SF			
1	1	Walk-In Freezer – Left	N/A	Ceramic Tile Floors	Non Suspect ACM	225	SF	0	SF			
1	1	Walk-In Freezer – Left	N/A	Metal Walls	Non Suspect ACM	675	SF	0	SF			
1	1	Walk-In Freezer – Left	N/A	Metal Ceiling	Non Suspect ACM	225	SF	0	SF			
1	1	Food Services Staff Restroom	N/A	Ceramic Tile Floors	Non Suspect ACM	80	SF	0	SF			
1	1	Food Services Staff Restroom	N/A	Concrete Block Wall	Non Suspect ACM	240	SF	0	SF			
1	1	Food Services Staff Restroom	N/A	Ceiling Tile 2' x 4'	Non Suspect ACM	80	SF	0	SF			
1	1	Food Services Staff Locker Room 182B	N/A	Floor Tile VAT 12" x 12"	NAD	70	SF	0	SF	Grey		
1	1	Food Services Staff Locker Room 182B	N/A	Concrete Block Wall	Non Suspect ACM	210	SF	0	SF			

# 8010 New Lincoln - Room by Room Location Log Report.xls

		School District of Philadelphia New Lincoln High School 3201 Ryan Avenue, Philadelphia, PA 19136 ULCS# 8010 Year Built: 2009	AHERA Three-Year Reinspection 2015-2016 Room by Room Location Log Report								Reinspection Date: December 30, 2016	
											Building Inspector: Bernard J Bryson	
											Number: ACC-0125-6-031	
											Management Planner: Megan Vala	
											Number: 740728	
E l e m e n t	F l o o r	On Site Room Name	System Affected	Material Description	Confirmed/Assumed/NAD/ Non Suspect ACM	Amount of Material	SF LF EA	Amount of Damage	SF LF EA	Color required for VAT	Comments/Description/Notes	Attic/ Crawl/ Space Ranking
1	1	Food Services Staff Locker Room 182B	N/A	Ceiling Tile 2' x 4'	Non Suspect ACM	70	SF	0	SF			
1	1	Food Services Staff Locker Room 182B	N/A	Fiberglass Pipe Insulation	Non Suspect ACM	8	LF	0	LF			
1	1	Storage Room 182A	N/A	Concrete Floor	Non Suspect ACM	70	SF	0	SF			
1	1	Storage Room 182A	N/A	Concrete Block Wall	Non Suspect ACM	210	SF	0	SF			
1	1	Storage Room 182A	N/A	Corrugated Metal Ceiling	Non Suspect ACM	70	SF	0	SF			
1	1	Storage Room 182A	N/A	Fiberglass Pipe Insulation	Non Suspect ACM	25	LF	0	LF			
1	1	Office 182	N/A	Floor Tile VAT 12" x 12"	NAD	100	SF	0	SF	Grey		
1	1	Office 182	N/A	Concrete Block Wall	Non Suspect ACM	300	SF	0	SF			
1	1	Office 182	N/A	Ceiling Tile 2' x 4'	Non Suspect ACM	100	SF	0	SF			
1	1	Hallway from Kitchen to Facilities Staff Hallway	N/A	Floor Tile VAT 12" x 12"	NAD	850	SF	0	SF	Grey		
1	1	Hallway from Kitchen to Facilities Staff Hallway	N/A	Concrete Block Wall	Non Suspect ACM	2550	SF	0	SF			
1	1	Hallway from Kitchen to Facilities Staff Hallway	N/A	Ceiling Tile 2' x 4'	Non Suspect ACM	850	SF	0	SF			
1	1	Staff Cafeteria (Dining Area) 181	N/A	Floor Tile VAT 12" x 12"	NAD	770	SF	0	SF	Grey		
1	1	Staff Cafeteria (Dining Area) 181	N/A	Concrete Block Wall	Non Suspect ACM	2310	SF	0	SF			
1	1	Staff Cafeteria (Dining Area) 181	N/A	Ceiling Tile 2' x 4'	Non Suspect ACM	770	SF	0	SF			
1	1	Hearing Office 180	N/A	Floor Tile VAT 12" x 12"	NAD	850	SF	0	SF	Grey		
1	1	Hearing Office 180	N/A	Concrete Block Wall	Non Suspect ACM	2550	SF	0	SF			
1	1	Hearing Office 180	N/A	Ceiling Tile 2' x 4'	Non Suspect ACM	850	SF	0	SF			
1	1	Electrical Room 180B	N/A	Concrete Floor	Non Suspect ACM	1000	SF	0	SF			
1	1	Electrical Room 180B	N/A	Concrete Block Wall	Non Suspect ACM	3000	SF	0	SF			
1	1	Electrical Room 180B	N/A	Corrugated Metal Ceiling	Non Suspect ACM	1000	SF	0	SF			
1	1	Electrical Room 180B	N/A	Fiberglass Panels	Non Suspect ACM	100	SF	0	SF		Inside the 13,200V Switchgear	
1	1	Facilities Staff Hallway/Hallway to Loading Dock	N/A	Concrete Floor	Non Suspect ACM	2000	SF	0	SF			
1	1	Facilities Staff Hallway/Hallway to Loading Dock	N/A	Concrete Block Wall	Non Suspect ACM	6000	SF	0	SF			
1	1	Facilities Staff Hallway/Hallway to Loading Dock	N/A	Sheetrock Wall	Non Suspect ACM	1200	SF	0	SF			
1	1	Facilities Staff Hallway/Hallway to Loading Dock	N/A	Ceiling Tile 2' x 4'	Non Suspect ACM	650	SF	0	SF			
1	1	Facilities Staff Hallway/Hallway to Loading Dock	N/A	Corrugated Metal Ceiling	Non Suspect ACM	1350	SF	0	SF			
1	1	Facilities Staff Hallway/Hallway to Loading Dock	N/A	Fiberglass Pipe Insulation	Non Suspect ACM	200	LF	0	LF			
1	1	Boiler Room	N/A	Concrete Floor	Non Suspect ACM	3750	SF	0	SF			
1	1	Boiler Room	N/A	Concrete Block Wall	Non Suspect ACM	11,250	SF	0	SF			
1	1	Boiler Room	N/A	Sheetrock Wall	Non Suspect ACM	1200	SF	0	SF			
1	1	Boiler Room	N/A	Corrugated Metal Ceiling	Non Suspect ACM	3750	SF	0	SF			
1	1	Boiler Room	N/A	Fiberglass Pipe Insulation	Non Suspect ACM	750	LF	0	LF			
1	1	Boiler Room	N/A	Vinyl Vibration Damper Cloth	Non Suspect ACM	20	SF	0	SF		Inside HV#1 and HV#2 (supply the Boiler Room with Fresh Air)	
1	1	Hallway outside of Cafeteria	N/A	Floor Tile VAT 12" x 12"	NAD	4100	SF	0	SF	Grey		
1	1	Hallway outside of Cafeteria	N/A	Concrete Block Wall	Non Suspect ACM	8200	SF	0	SF			
1	1	Hallway outside of Cafeteria	N/A	Ceiling Tile 2' x 4'	Non Suspect ACM	4100	SF	0	SF			

# 8010 New Lincoln - Room by Room Location Log Report.xls

		School District of Philadelphia New Lincoln High School 3201 Ryan Avenue, Philadelphia, PA 19136 ULCS# 8010 Year Built: 2009	AHERA Three-Year Reinspection 2015-2016 Room by Room Location Log Report										Reinspection Date: December 30, 2016	
											Building Inspector: Bernard J Bryson			
											Number: ACC-0125-6-031			
											Management Planner: Megan Vala			
											Number: 740728			
<i>E l e m e n t</i>	<i>F l o o r</i>	<i>On Site Room Name</i>	<i>System Affected</i>	<i>Material Description</i>	<i>Confirmed/Assumed/NAD/ Non Suspect ACM</i>	<i>Amount of Material</i>	<i>SF LF EA</i>	<i>Amount of Damage</i>	<i>SF LF EA</i>	<i>Color required for VAT</i>	<i>Comments/Description/Notes</i>	<i>Attic/ Crawl Space Ranking</i>		
1	1	Generator Room 184	N/A	Concrete Floor	Non Suspect ACM	300	SF	0	SF					
1	1	Generator Room 184	N/A	Concrete Block Wall	Non Suspect ACM	900	SF	0	SF					
1	1	Generator Room 184	N/A	Corrugated Metal Ceiling	Non Suspect ACM	300	SF	0	SF					
1	1	Generator Room 184	N/A	Emergency Generator	Non Suspect ACM	1	EA	0	EA					
1	1	Generator Room 184	N/A	Emergency Generator Insulation	Non Suspect ACM	60	SF	0	SF					
1	1	Storage Room 185	N/A	Concrete Floor	Non Suspect ACM	150	SF	0	SF					
1	1	Storage Room 185	N/A	Concrete Block Wall	Non Suspect ACM	450	SF	0	SF					
1	1	Storage Room 185	N/A	Corrugated Metal Ceiling	Non Suspect ACM	150	SF	0	SF					
1	1	Storage Room 185	N/A	Fireproofing	Non Suspect ACM	50	SF	0	SF					
1	1	Building Engineer's Office 186	N/A	Floor Tile VAT 12" x 12"	NAD	150	SF	0	SF	Grey				
1	1	Building Engineer's Office 186	N/A	Concrete Block Wall	Non Suspect ACM	450	SF	0	SF					
1	1	Building Engineer's Office 186	N/A	Ceiling Tile 2' x 4'	Non Suspect ACM	150	SF	0	SF					
1	1	Men's Locker Room 186A	N/A	Floor Tile VAT 12" x 12"	NAD	100	SF	0	SF	Grey				
1	1	Men's Locker Room 186A	N/A	Concrete Block Wall	Non Suspect ACM	300	SF	0	SF					
1	1	Men's Locker Room 186A	N/A	Ceiling Tile 2' x 4'	Non Suspect ACM	100	SF	0	SF					
1	1	Women's Locker Room 186B	N/A	Floor Tile VAT 12" x 12"	NAD	100	SF	0	SF	Grey				
1	1	Women's Locker Room 186B	N/A	Concrete Block Wall	Non Suspect ACM	300	SF	0	SF					
1	1	Women's Locker Room 186B	N/A	Ceiling Tile 2' x 4'	Non Suspect ACM	100	SF	0	SF					
1	1	Chiller Room 187	N/A	Concrete Floor	Non Suspect ACM	2500	SF	0	SF					
1	1	Chiller Room 187	N/A	Concrete Block Wall	Non Suspect ACM	7500	SF	0	SF					
1	1	Chiller Room 187	N/A	Corrugated Metal Ceiling	Non Suspect ACM	2500	SF	0	SF					
1	1	Chiller Room 187	N/A	Fireproofing	Non Suspect ACM	200	SF	0	SF					
1	1	Chiller Room 187	N/A	Neoprene Pipe Insulation	Non Suspect ACM	5	LF	0	LF					
1	1	Chiller Room 187	N/A	Fiberglass Pipe Insulation	Non Suspect ACM	200	LF	0	LF					
1	1	Storage Room 188	N/A	Concrete Floor	Non Suspect ACM	150	SF	0	SF					
1	1	Storage Room 188	N/A	Concrete Block Wall	Non Suspect ACM	450	SF	0	SF					
1	1	Storage Room 188	N/A	Ceiling Tile 2' x 4'	Non Suspect ACM	150	SF	0	SF					
1	1	Electrical Room 192A	N/A	Concrete Floor	Non Suspect ACM	1400	SF	0	SF					
1	1	Electrical Room 192A	N/A	Concrete Block Wall	Non Suspect ACM	4200	SF	0	SF					
1	1	Electrical Room 192A	N/A	Corrugated Metal Ceiling	Non Suspect ACM	1400	SF	0	SF					
1	1	Electrical Room 192A	N/A	Fireproofing	Non Suspect ACM	100	SF	0	SF					
1	1	Electrical Room 192A	N/A	Fiberglass Pipe Insulation	Non Suspect ACM	10	LF	0	LF					
1	1	Stairwell next to Flower Shop 100A	N/A	Concrete Floor	Non Suspect ACM	600	SF	0	SF					
1	1	Stairwell next to Flower Shop 100A	N/A	Concrete Block Wall	Non Suspect ACM	1800	SF	0	SF					
1	1	Stairwell next to Flower Shop 100A	N/A	Corrugated Metal Ceiling	Non Suspect ACM	600	SF	0	SF					
1	1	Stairwell next to Flower Shop 100A	N/A	Fiberglass Pipe Insulation	Non Suspect ACM	50	LF	0	LF					
1	1	Flower Shop 100A	N/A	Concrete Block Wall	Non Suspect ACM	825	SF	0	SF					
1	1	Flower Shop 100A	N/A	Sheetrock Wall	Non Suspect ACM	825	SF	0	SF					
1	1	Flower Shop 100A	N/A	Ceiling Tile 2' x 4'	Non Suspect ACM	550	SF	6	EA		6 Stained ACTs			
1	1	Classroom 100	N/A	Floor Tile VAT 12" x 12"	NAD	1000	SF	0	SF	Grey				
1	1	Classroom 100	N/A	Concrete Block Wall	Non Suspect ACM	750	SF	0	SF					
1	1	Classroom 100	N/A	Sheetrock Wall	Non Suspect ACM	2250	SF	0	SF					
1	1	Classroom 100	N/A	Ceiling Tile 2' x 4'	Non Suspect ACM	1000	SF	0	SF					
1	1	Science Classroom 101	N/A	Floor Tile VAT 12" x 12"	NAD	1500	SF	0	SF	Grey				
1	1	Science Classroom 101	N/A	Concrete Block Wall	Non Suspect ACM	2250	SF	0	SF					
1	1	Science Classroom 101	N/A	Sheetrock Wall	Non Suspect ACM	2250	SF	0	SF					
1	1	Science Classroom 101	N/A	Ceiling Tile 2' x 4'	Non Suspect ACM	1500	SF	0	SF					
1	1	Science Classroom 101	N/A	Lab Table Tops/Sinks	Non Suspect ACM	200	SF	0	SF	Black				
1	1	Science Lab Prep Room 101A	N/A	Floor Tile VAT 12" x 12"	NAD	350	SF	0	SF	Grey				
1	1	Science Lab Prep Room 101A	N/A	Concrete Block Wall	Non Suspect ACM	800	SF	0	SF					
1	1	Science Lab Prep Room 101A	N/A	Sheetrock Wall	Non Suspect ACM	250	SF	0	SF					
1	1	Science Lab Prep Room 101A	N/A	Ceiling Tile 2' x 4'	Non Suspect ACM	350	SF	0	SF					

# 8010 New Lincoln - Room by Room Location Log Report.xls

		School District of Philadelphia New Lincoln High School 3201 Ryan Avenue, Philadelphia, PA 19136 ULCS# 8010 Year Built: 2009	AHERA Three-Year Reinspection 2015-2016 Room by Room Location Log Report								Reinspection Date: December 30, 2016	
											Building Inspector: Bernard J Bryson	
											Number: ACC-0125-6-031	
											Management Planner: Megan Vala	
											Number: 740728	
E l e m e n t	F l o o r	On Site Room Name	System Affected	Material Description	Confirmed/Assumed/NAD/ Non Suspect ACM	Amount of Material	SF LF EA	Amount of Damage	SF LF EA	Color required for VAT	Comments/Description/Notes	Attic/ Crawl Space Ranking
1	1	Science Lab Prep Room 101A	N/A	Lab Table Tops/Sinks	Non Suspect ACM	50	SF	0	SF	Black		
1	1	Science Classroom 103	N/A	Floor Tile VAT 12" x 12"	NAD	1500	SF	0	SF	Grey		
1	1	Science Classroom 103	N/A	Concrete Block Wall	Non Suspect ACM	2250	SF	0	SF			
1	1	Science Classroom 103	N/A	Sheetrock Wall	Non Suspect ACM	2250	SF	0	SF			
1	1	Science Classroom 103	N/A	Ceiling Tile 2' x 4'	Non Suspect ACM	1500	SF	0	SF			
1	1	Science Classroom 103	N/A	Lab Table Tops/Sinks	Non Suspect ACM	200	SF	0	SF	Black		
1	1	Administrative Office 102A	N/A	Floor Tile VAT 12" x 12"	NAD	150	SF	0	SF	Grey		
1	1	Administrative Office 102A	N/A	Concrete Block Wall	Non Suspect ACM	110	SF	0	SF			
1	1	Administrative Office 102A	N/A	Sheetrock Wall	Non Suspect ACM	330	SF	0	SF			
1	1	Administrative Office 102A	N/A	Ceiling Tile 2' x 4'	Non Suspect ACM	150	SF	0	SF			
1	1	Vo Tech Classroom 102	N/A	Floor Tile VAT 12" x 12"	NAD	2500	SF	0	SF	Grey		
1	1	Vo Tech Classroom 102	N/A	Sheetrock Wall	Non Suspect ACM	7500	SF	0	SF			
1	1	Vo Tech Classroom 102	N/A	Ceiling Tile 2' x 4'	Non Suspect ACM	2500	SF	0	SF			
1	1	Staff Restroom outside of Vo Tech Classroom 102 - Left	N/A	Ceramic Tile Floors	Non Suspect ACM	80	SF	0	SF			
1	1	Staff Restroom outside of Vo Tech Classroom 102 - Left	N/A	Concrete Block Wall	Non Suspect ACM	240	SF	0	SF			
1	1	Staff Restroom outside of Vo Tech Classroom 102 - Left	N/A	Ceiling Tile 2' x 4'	Non Suspect ACM	80	SF	0	SF			
1	1	Staff Restroom outside of Vo Tech Classroom 102 - Right	N/A	Ceramic Tile Floors	Non Suspect ACM	80	SF	0	SF			
1	1	Staff Restroom outside of Vo Tech Classroom 102 - Right	N/A	Concrete Block Wall	Non Suspect ACM	240	SF	0	SF			
1	1	Staff Restroom outside of Vo Tech Classroom 102 - Right	N/A	Ceiling Tile 2' x 4'	Non Suspect ACM	80	SF	0	SF			
1	1	Large Storage Room inside Vo Tech Classroom 102	N/A	Floor Tile VAT 12" x 12"	NAD	300	SF	0	SF	Grey		
1	1	Large Storage Room inside Vo Tech Classroom 102	N/A	Sheetrock Wall	Non Suspect ACM	900	SF	0	SF			
1	1	Large Storage Room inside Vo Tech Classroom 102	N/A	Ceiling Tile 2' x 4'	Non Suspect ACM	300	SF	0	SF			
1	1	Classroom 104	N/A	Floor Tile VAT 12" x 12"	NAD	1000	SF	0	SF	Grey		
1	1	Classroom 104	N/A	Concrete Block Wall	Non Suspect ACM	1500	SF	0	SF			
1	1	Classroom 104	N/A	Sheetrock Wall	Non Suspect ACM	1500	SF	0	SF			
1	1	Classroom 104	N/A	Ceiling Tile 2' x 4'	Non Suspect ACM	1000	SF	0	SF			
1	1	Classroom 105	N/A	Floor Tile VAT 12" x 12"	NAD	1200	SF	0	SF	Grey		
1	1	Classroom 105	N/A	Concrete Block Wall	Non Suspect ACM	900	SF	0	SF			
1	1	Classroom 105	N/A	Sheetrock Wall	Non Suspect ACM	2700	SF	0	SF			
1	1	Classroom 105	N/A	Ceiling Tile 2' x 4'	Non Suspect ACM	1200	SF	2	EA		2 Stained ACTs	
1	1	Student Restroom inside Classroom 105	N/A	Floor Tile VAT 12" x 12"	NAD	100	SF	0	SF	Grey		
1	1	Student Restroom inside Classroom 105	N/A	Sheetrock Wall	Non Suspect ACM	300	SF	0	SF			
1	1	Student Restroom inside Classroom 105	N/A	Ceiling Tile 2' x 4'	Non Suspect ACM	100	SF	0	SF			
1	1	Instructional Kitchen inside Classroom 105	N/A	Floor Tile VAT 12" x 12"	NAD	150	SF	0	SF	Grey		
1	1	Instructional Kitchen inside Classroom 105	N/A	Concrete Block Wall	Non Suspect ACM	110	SF	0	SF			
1	1	Instructional Kitchen inside Classroom 105	N/A	Sheetrock Wall	Non Suspect ACM	340	SF	0	SF			
1	1	Instructional Kitchen inside Classroom 105	N/A	Ceiling Tile 2' x 4'	Non Suspect ACM	150	SF	0	SF			
1	1	Hallway Storage Room 105A	N/A	Concrete Floor	Non Suspect ACM	100	SF	0	SF			
1	1	Hallway Storage Room 105A	N/A	Concrete Block Wall	Non Suspect ACM	300	SF	0	SF			
1	1	Hallway Storage Room 105A	N/A	Corrugated Metal Ceiling	Non Suspect ACM	100	SF	0	SF			
1	1	Hallway Storage Room 105C	N/A	Concrete Floor	Non Suspect ACM	100	SF	0	SF			
1	1	Hallway Storage Room 105C	N/A	Concrete Block Wall	Non Suspect ACM	300	SF	0	SF			
1	1	Hallway Storage Room 105C	N/A	Corrugated Metal Ceiling	Non Suspect ACM	100	SF	0	SF			
1	1	Elevator	N/A	Floor Tile VAT 12" x 12"	NAD	30	SF	0	SF	Grey		
1	1	Elevator	N/A	Metal Walls	Non Suspect ACM	100	SF	0	SF			
1	1	Elevator	N/A	Metal Ceiling	Non Suspect ACM	30	SF	0	SF			
1	1	Boy's Restroom across from Classroom 108	N/A	Ceramic Tile Floors	Non Suspect ACM	500	SF	0	SF			
1	1	Boy's Restroom across from Classroom 108	N/A	Concrete Block Wall	Non Suspect ACM	1500	SF	0	SF			

# 8010 New Lincoln - Room by Room Location Log Report.xls

		School District of Philadelphia New Lincoln High School 3201 Ryan Avenue, Philadelphia, PA 19136 ULCS# 8010 Year Built: 2009	AHERA Three-Year Reinspection 2015-2016 Room by Room Location Log Report								Reinspection Date: December 30, 2016	
											Building Inspector: Bernard J Bryson	
											Number: ACC-0125-6-031	
											Management Planner: Megan Vala	
											Number: 740728	
E l e m e n t	F l o o r	On Site Room Name	System Affected	Material Description	Confirmed/Assumed/NAD/ Non Suspect ACM	Amount of Material	SF LF EA	Amount of Damage	SF LF EA	Color required for VAT	Comments/Description/Notes	Attic/ Crawl Space Ranking
1	1	Boy's Restroom across from Classroom 108	N/A	Ceiling Tile 2' x 4'	Non Suspect ACM	500	SF	3	EA		3 Stained ACTs	
1	1	Stairwell next to Classroom 104	N/A	Concrete Floor	Non Suspect ACM	600	SF	0	SF			
1	1	Stairwell next to Classroom 104	N/A	Concrete Block Wall	Non Suspect ACM	1800	SF	0	SF			
1	1	Stairwell next to Classroom 104	N/A	Corrugated Metal Ceiling	Non Suspect ACM	600	SF	0	SF			
1	1	Stairwell next to Classroom 104	N/A	Fiberglass Pipe Insulation	Non Suspect ACM	50	LF	0	LF			
1	1	Science Classroom 107	N/A	Floor Tile VAT 12" x 12"	NAD	1500	SF	0	SF	Grey		
1	1	Science Classroom 107	N/A	Concrete Block Wall	Non Suspect ACM	2250	SF	0	SF			
1	1	Science Classroom 107	N/A	Sheetrock Wall	Non Suspect ACM	2250	SF	0	SF			
1	1	Science Classroom 107	N/A	Ceiling Tile 2' x 4'	Non Suspect ACM	1500	SF	0	SF			
1	1	Science Classroom 107	N/A	Lab Table Tops/Sinks	Non Suspect ACM	200	SF	0	SF	Black		
1	1	Science Lab Prep Room 107A	N/A	Floor Tile VAT 12" x 12"	NAD	350	SF	0	SF	Grey		
1	1	Science Lab Prep Room 107A	N/A	Concrete Block Wall	Non Suspect ACM	800	SF	0	SF			
1	1	Science Lab Prep Room 107A	N/A	Sheetrock Wall	Non Suspect ACM	250	SF	0	SF			
1	1	Science Lab Prep Room 107A	N/A	Ceiling Tile 2' x 4'	Non Suspect ACM	350	SF	0	SF			
1	1	Science Lab Prep Room 107A	N/A	Lab Table Tops/Sinks	Non Suspect ACM	50	SF	0	SF	Black		
1	1	Science Classroom 111	N/A	Floor Tile VAT 12" x 12"	NAD	1500	SF	0	SF	Grey		
1	1	Science Classroom 111	N/A	Concrete Block Wall	Non Suspect ACM	2250	SF	0	SF			
1	1	Science Classroom 111	N/A	Sheetrock Wall	Non Suspect ACM	2250	SF	0	SF			
1	1	Science Classroom 111	N/A	Ceiling Tile 2' x 4'	Non Suspect ACM	1500	SF	0	SF			
1	1	Science Classroom 111	N/A	Lab Table Tops/Sinks	Non Suspect ACM	200	SF	0	SF	Black		
1	1	Office 109	N/A	Floor Tile VAT 12" x 12"	NAD	100	SF	0	SF	Grey		
1	1	Office 109	N/A	Sheetrock Wall	Non Suspect ACM	300	SF	0	SF			
1	1	Office 109	N/A	Ceiling Tile 2' x 4'	Non Suspect ACM	100	SF	0	SF			
1	1	Classroom 106	N/A	Floor Tile VAT 12" x 12"	NAD	1200	SF	0	SF	Grey		
1	1	Classroom 106	N/A	Concrete Block Wall	Non Suspect ACM	900	SF	0	SF			
1	1	Classroom 106	N/A	Sheetrock Wall	Non Suspect ACM	2700	SF	0	SF			
1	1	Classroom 106	N/A	Ceiling Tile 2' x 4'	Non Suspect ACM	1200	SF	0	SF			
1	1	Classroom 108	N/A	Floor Tile VAT 12" x 12"	NAD	1000	SF	0	SF	Grey		
1	1	Classroom 108	N/A	Concrete Block Wall	Non Suspect ACM	750	SF	0	SF			
1	1	Classroom 108	N/A	Sheetrock Wall	Non Suspect ACM	2250	SF	0	SF			
1	1	Classroom 108	N/A	Ceiling Tile 2' x 4'	Non Suspect ACM	1000	SF	0	SF			
1	1	Classroom 110	N/A	Floor Tile VAT 12" x 12"	NAD	1000	SF	0	SF	Grey		
1	1	Classroom 110	N/A	Concrete Block Wall	Non Suspect ACM	750	SF	0	SF			
1	1	Classroom 110	N/A	Sheetrock Wall	Non Suspect ACM	2250	SF	0	SF			
1	1	Classroom 110	N/A	Ceiling Tile 2' x 4'	Non Suspect ACM	1000	SF	0	SF			
1	1	Classroom 112	N/A	Floor Tile VAT 12" x 12"	NAD	1000	SF	0	SF	Grey		
1	1	Classroom 112	N/A	Concrete Block Wall	Non Suspect ACM	750	SF	0	SF			
1	1	Classroom 112	N/A	Sheetrock Wall	Non Suspect ACM	2250	SF	0	SF			
1	1	Classroom 112	N/A	Ceiling Tile 2' x 4'	Non Suspect ACM	1000	SF	0	SF			
1	1	Classroom 114	N/A	Floor Tile VAT 12" x 12"	NAD	1000	SF	0	SF	Grey		
1	1	Classroom 114	N/A	Concrete Block Wall	Non Suspect ACM	750	SF	0	SF			
1	1	Classroom 114	N/A	Sheetrock Wall	Non Suspect ACM	2250	SF	0	SF			
1	1	Classroom 114	N/A	Ceiling Tile 2' x 4'	Non Suspect ACM	1000	SF	0	SF			
1	1	Classroom 116	N/A	Floor Tile VAT 12" x 12"	NAD	1000	SF	0	SF	Grey		
1	1	Classroom 116	N/A	Concrete Block Wall	Non Suspect ACM	750	SF	0	SF			
1	1	Classroom 116	N/A	Sheetrock Wall	Non Suspect ACM	2250	SF	0	SF			
1	1	Classroom 116	N/A	Ceiling Tile 2' x 4'	Non Suspect ACM	1000	SF	0	SF			
1	1	Classroom 118	N/A	Floor Tile VAT 12" x 12"	NAD	1500	SF	0	SF	Grey		
1	1	Classroom 118	N/A	Concrete Block Wall	Non Suspect ACM	1500	SF	0	SF			
1	1	Classroom 118	N/A	Sheetrock Wall	Non Suspect ACM	3000	SF	0	SF			
1	1	Classroom 118	N/A	Ceiling Tile 2' x 4'	Non Suspect ACM	1500	SF	0	SF			
1	1	Custodial Closet 107A	N/A	Concrete Floor	Non Suspect ACM	20	SF	0	SF			

# 8010 New Lincoln - Room by Room Location Log Report.xls

		School District of Philadelphia New Lincoln High School 3201 Ryan Avenue, Philadelphia, PA 19136 ULCS# 8010 Year Built: 2009	AHERA Three-Year Reinspection 2015-2016 Room by Room Location Log Report								Reinspection Date: December 30, 2016		Attic/ Crawl Space Ranking
											Building Inspector: Bernard J Bryson		
											Number: ACC-0125-6-031		
											Management Planner: Megan Vala		
											Number: 740728		
E l e m e n t	F l o o r	On Site Room Name	System Affected	Material Description	Confirmed/Assumed/NAD/ Non Suspect ACM	Amount of Material	SF LF EA	Amount of Damage	SF LF EA	Color required for VAT	Comments/Description/Notes		
1	1	Custodial Closet 107A	N/A	Concrete Block Wall	Non Suspect ACM	80	SF	0	SF				
1	1	Custodial Closet 107A	N/A	Corrugated Metal Ceiling	Non Suspect ACM	20	SF	0	SF				
1	1	Hallway Storage Closet 107B	N/A	Concrete Floor	Non Suspect ACM	20	SF	0	SF				
1	1	Hallway Storage Closet 107B	N/A	Concrete Block Wall	Non Suspect ACM	80	SF	0	SF				
1	1	Hallway Storage Closet 107B	N/A	Corrugated Metal Ceiling	Non Suspect ACM	20	SF	0	SF				
1	1	Hallway Storage Closet 107C	N/A	Concrete Floor	Non Suspect ACM	20	SF	0	SF				
1	1	Hallway Storage Closet 107C	N/A	Concrete Block Wall	Non Suspect ACM	80	SF	0	SF				
1	1	Hallway Storage Closet 107C	N/A	Corrugated Metal Ceiling	Non Suspect ACM	20	SF	0	SF				
1	1	Girl's Restroom across from Classroom 116	N/A	Ceramic Tile Floors	Non Suspect ACM	500	SF	0	SF				
1	1	Girl's Restroom across from Classroom 116	N/A	Concrete Block Wall	Non Suspect ACM	1500	SF	0	SF				
1	1	Girl's Restroom across from Classroom 116	N/A	Ceiling Tile 2' x 4'	Non Suspect ACM	500	SF	0	SF				
1	1	Stairwell next to Classroom 120	N/A	Concrete Floor	Non Suspect ACM	600	SF	0	SF				
1	1	Stairwell next to Classroom 120	N/A	Concrete Block Wall	Non Suspect ACM	1800	SF	0	SF				
1	1	Stairwell next to Classroom 120	N/A	Corrugated Metal Ceiling	Non Suspect ACM	600	SF	0	SF				
1	1	Stairwell next to Classroom 120	N/A	Fiberglass Pipe Insulation	Non Suspect ACM	50	LF	0	LF				
1	1	Staff Restroom across from Classroom 116 - Left	N/A	Ceramic Tile Floors	Non Suspect ACM	80	SF	0	SF				
1	1	Staff Restroom across from Classroom 116 - Left	N/A	Concrete Block Wall	Non Suspect ACM	240	SF	0	SF				
1	1	Staff Restroom across from Classroom 116 - Left	N/A	Ceiling Tile 2' x 4'	Non Suspect ACM	80	SF	0	SF				
1	1	Staff Restroom across from Classroom 116 - Right	N/A	Ceramic Tile Floors	Non Suspect ACM	80	SF	0	SF				
1	1	Staff Restroom across from Classroom 116 - Right	N/A	Concrete Block Wall	Non Suspect ACM	240	SF	0	SF				
1	1	Staff Restroom across from Classroom 116 - Right	N/A	Ceiling Tile 2' x 4'	Non Suspect ACM	80	SF	0	SF				
1	1	Hallway Storage Closet 121A	N/A	Concrete Floor	Non Suspect ACM	20	SF	0	SF				
1	1	Hallway Storage Closet 121A	N/A	Concrete Block Wall	Non Suspect ACM	80	SF	0	SF				
1	1	Hallway Storage Closet 121A	N/A	Corrugated Metal Ceiling	Non Suspect ACM	20	SF	0	SF				
1	1	Hallway Electrical Room 121B	N/A	Concrete Floor	Non Suspect ACM	20	SF	0	SF				
1	1	Hallway Electrical Room 121B	N/A	Concrete Block Wall	Non Suspect ACM	80	SF	0	SF				
1	1	Hallway Electrical Room 121B	N/A	Corrugated Metal Ceiling	Non Suspect ACM	20	SF	0	SF				
1	1	Hallway IT MDF Room 121C	N/A	Concrete Floor	Non Suspect ACM	20	SF	0	SF				
1	1	Hallway IT MDF Room 121C	N/A	Concrete Block Wall	Non Suspect ACM	80	SF	0	SF				
1	1	Hallway IT MDF Room 121C	N/A	Corrugated Metal Ceiling	Non Suspect ACM	20	SF	0	SF				
1	1	Hallway IT MDF Room 121C	N/A	Fiberglass Pipe Insulation	Non Suspect ACM	10	LF	0	LF				
1	1	Classroom 120	N/A	Floor Tile VAT 12" x 12"	NAD	1000	SF	0	SF	Grey			
1	1	Classroom 120	N/A	Concrete Block Wall	Non Suspect ACM	750	SF	0	SF				
1	1	Classroom 120	N/A	Sheetrock Wall	Non Suspect ACM	2250	SF	0	SF				
1	1	Classroom 120	N/A	Ceiling Tile 2' x 4'	Non Suspect ACM	1000	SF	0	SF				
1	1	Classroom 121	N/A	Floor Tile VAT 12" x 12"	NAD	1000	SF	0	SF	Grey			
1	1	Classroom 121	N/A	Concrete Block Wall	Non Suspect ACM	750	SF	0	SF				
1	1	Classroom 121	N/A	Sheetrock Wall	Non Suspect ACM	2250	SF	0	SF				
1	1	Classroom 121	N/A	Ceiling Tile 2' x 4'	Non Suspect ACM	1000	SF	0	SF				
1	1	Classroom 122	N/A	Floor Tile VAT 12" x 12"	NAD	1000	SF	0	SF	Grey			
1	1	Classroom 122	N/A	Concrete Block Wall	Non Suspect ACM	750	SF	0	SF				
1	1	Classroom 122	N/A	Sheetrock Wall	Non Suspect ACM	2250	SF	0	SF				
1	1	Classroom 122	N/A	Ceiling Tile 2' x 4'	Non Suspect ACM	1000	SF	0	SF				
1	1	Classroom 123	N/A	Floor Tile VAT 12" x 12"	NAD	2500	SF	0	SF	Grey			
1	1	Classroom 123	N/A	Sheetrock Wall	Non Suspect ACM	7500	SF	4	SF		4 SF damaged sheetrock along window wall		
1	1	Classroom 123	N/A	Ceiling Tile 2' x 4'	Non Suspect ACM	2500	SF	6	EA		6 Stained ACTs		
1	1	Solarium inside Classroom 123	N/A	Concrete Floor	Non Suspect ACM	250	SF	0	SF				
1	1	Solarium inside Classroom 123	N/A	Sheetrock Wall	Non Suspect ACM	750	SF	0	SF				
1	1	Solarium inside Classroom 123	N/A	Corrugated Metal Ceiling	Non Suspect ACM	250	SF	0	SF				
1	1	Solarium inside Classroom 123	N/A	Fiberglass Pipe Insulation	Non Suspect ACM	100	LF	0	LF				
1	1	Storage Room inside Classroom 123	N/A	Concrete Floor	Non Suspect ACM	100	SF	0	SF				



# 8010 New Lincoln - Room by Room Location Log Report.xls

		School District of Philadelphia New Lincoln High School 3201 Ryan Avenue, Philadelphia, PA 19136 ULCS# 8010 Year Built: 2009	AHERA Three-Year Reinspection 2015-2016 Room by Room Location Log Report								Reinspection Date: December 30, 2016	
											Building Inspector: Bernard J Bryson	
											Number: ACC-0125-6-031	
											Management Planner: Megan Vala	
											Number: 740728	
<i>E l e m e n t</i>	<i>F l o o r</i>	<i>On Site Room Name</i>	<i>System Affected</i>	<i>Material Description</i>	<i>Confirmed/Assumed/NAD/ Non Suspect ACM</i>	<i>Amount of Material</i>	<i>SF LF EA</i>	<i>Amount of Damage</i>	<i>SF LF EA</i>	<i>Color required for VAT</i>	<i>Comments/Description/Notes</i>	<i>Attic/ Crawl Space Ranking</i>
1	1	Storage Room inside Classroom 123	N/A	Sheetrock Wall	Non Suspect ACM	300	SF	0	SF			
1	1	Storage Room inside Classroom 123	N/A	Ceiling Tile 2' x 4'	Non Suspect ACM	100	SF	0	SF			
1	1	Office between Classrooms 121 and 123	N/A	Floor Tile VAT 12" x 12"	NAD	100	SF	0	SF	Grey		
1	1	Office between Classrooms 121 and 123	N/A	Sheetrock Wall	Non Suspect ACM	300	SF	0	SF			
1	1	Office between Classrooms 121 and 123	N/A	Ceiling Tile 2' x 4'	Non Suspect ACM	100	SF	0	SF			
1	1	Classroom 124	N/A	Floor Tile VAT 12" x 12"	NAD	1000	SF	0	SF	Grey		
1	1	Classroom 124	N/A	Concrete Block Wall	Non Suspect ACM	750	SF	0	SF			
1	1	Classroom 124	N/A	Sheetrock Wall	Non Suspect ACM	2250	SF	0	SF			
1	1	Classroom 124	N/A	Ceiling Tile 2' x 4'	Non Suspect ACM	1000	SF	0	SF			
1	1	Classroom 125	N/A	Floor Tile VAT 12" x 12"	NAD	1000	SF	0	SF	Grey		
1	1	Classroom 125	N/A	Concrete Block Wall	Non Suspect ACM	750	SF	0	SF			
1	1	Classroom 125	N/A	Sheetrock Wall	Non Suspect ACM	2250	SF	0	SF			
1	1	Classroom 125	N/A	Ceiling Tile 2' x 4'	Non Suspect ACM	1000	SF	0	SF			
1	1	Classroom 126	N/A	Floor Tile VAT 12" x 12"	NAD	1000	SF	0	SF	Grey		
1	1	Classroom 126	N/A	Concrete Block Wall	Non Suspect ACM	750	SF	0	SF			
1	1	Classroom 126	N/A	Sheetrock Wall	Non Suspect ACM	2250	SF	0	SF			
1	1	Classroom 126	N/A	Ceiling Tile 2' x 4'	Non Suspect ACM	1000	SF	0	SF			
1	1	Classroom 128	N/A	Floor Tile VAT 12" x 12"	NAD	1000	SF	0	SF	Grey		
1	1	Classroom 128	N/A	Concrete Block Wall	Non Suspect ACM	750	SF	0	SF			
1	1	Classroom 128	N/A	Sheetrock Wall	Non Suspect ACM	2250	SF	0	SF			
1	1	Classroom 128	N/A	Ceiling Tile 2' x 4'	Non Suspect ACM	1000	SF	0	SF			
1	1	Classroom 129	N/A	Floor Tile VAT 12" x 12"	NAD	1000	SF	0	SF	Grey		
1	1	Classroom 129	N/A	Concrete Block Wall	Non Suspect ACM	750	SF	0	SF			
1	1	Classroom 129	N/A	Sheetrock Wall	Non Suspect ACM	2250	SF	0	SF			
1	1	Classroom 129	N/A	Ceiling Tile 2' x 4'	Non Suspect ACM	1000	SF	0	SF			
1	1	Stairwell next to Classroom 129	N/A	Concrete Floor	Non Suspect ACM	600	SF	0	SF			
1	1	Stairwell next to Classroom 129	N/A	Concrete Block Wall	Non Suspect ACM	1800	SF	0	SF			
1	1	Stairwell next to Classroom 129	N/A	Corrugated Metal Ceiling	Non Suspect ACM	600	SF	0	SF			
1	1	Stairwell next to Classroom 129	N/A	Fiberglass Pipe Insulation	Non Suspect ACM	50	LF	0	LF			
1	1	Art Classroom 132	N/A	Floor Tile VAT 12" x 12"	NAD	1500	SF	0	SF	Grey		
1	1	Art Classroom 132	N/A	Sheetrock Wall	Non Suspect ACM	4500	SF	0	SF			
1	1	Art Classroom 132	N/A	Corrugated Metal Ceiling	Non Suspect ACM	1500	SF	0	SF			
1	1	Art Classroom 132	N/A	Fiberglass Pipe Insulation	Non Suspect ACM	200	LF	0	LF			
1	1	Office inside Art Classroom 132	N/A	Floor Tile VAT 12" x 12"	NAD	150	SF	0	SF	Grey		
1	1	Office inside Art Classroom 132	N/A	Sheetrock Wall	Non Suspect ACM	450	SF	0	SF			
1	1	Office inside Art Classroom 132	N/A	Ceiling Tile 2' x 4'	Non Suspect ACM	150	SF	0	SF			
1	1	Storage Room inside Art Classroom 132	N/A	Concrete Floor	Non Suspect ACM	150	SF	0	SF			
1	1	Storage Room inside Art Classroom 132	N/A	Concrete Block Wall	Non Suspect ACM	125	SF	0	SF			
1	1	Storage Room inside Art Classroom 132	N/A	Sheetrock Wall	Non Suspect ACM	325	SF	0	SF			
1	1	Storage Room inside Art Classroom 132	N/A	Ceiling Tile 2' x 4'	Non Suspect ACM	150	SF	0	SF			
1	1	Storage Room inside Art Classroom 132	N/A	Kiln	Non Suspect ACM	1	EA	0	EA		Portable Kiln	
1	1	Electrical Room 132C	N/A	Concrete Floor	Non Suspect ACM	100	SF	0	SF			
1	1	Electrical Room 132C	N/A	Concrete Block Wall	Non Suspect ACM	300	SF	0	SF			
1	1	Electrical Room 132C	N/A	Corrugated Metal Ceiling	Non Suspect ACM	100	SF	0	SF			
1	1	Electrical Room 181A	N/A	Concrete Floor	Non Suspect ACM	100	SF	0	SF			
1	1	Electrical Room 181A	N/A	Concrete Block Wall	Non Suspect ACM	300	SF	0	SF			
1	1	Electrical Room 181A	N/A	Corrugated Metal Ceiling	Non Suspect ACM	100	SF	0	SF			
1	1	Hallway outside Classrooms 100 - 105	N/A	Floor Tile VAT 12" x 12"	NAD	1700	SF	0	SF	Grey		
1	1	Hallway outside Classrooms 100 - 105	N/A	Floor Tile VAT 12" x 12"	NAD	800	SF	0	SF	Yellow		
1	1	Hallway outside Classrooms 100 - 105	N/A	Concrete Block Wall	Non Suspect ACM	4000	SF	0	SF			
1	1	Hallway outside Classrooms 100 - 105	N/A	Sheetrock Wall	Non Suspect ACM	1000	SF	0	SF			
1	1	Hallwav outside Classrooms 100 - 105	N/A	Ceiling Tile 2' x 4'	Non Suspect ACM	2500	SF	0	SF			

# 8010 New Lincoln - Room by Room Location Log Report.xls

		School District of Philadelphia New Lincoln High School 3201 Ryan Avenue, Philadelphia, PA 19136 ULCS# 8010 Year Built: 2009	AHERA Three-Year Reinspection 2015-2016 Room by Room Location Log Report								Reinspection Date: December 30, 2016		
											Building Inspector: Bernard J Bryson		
											Number: ACC-0125-6-031		
											Management Planner: Megan Vala		
											Number: 740728		
<i>E l e m e n t</i>	<i>F l o o r</i>	<i>On Site Room Name</i>	<i>System Affected</i>	<i>Material Description</i>	<i>Confirmed/Assumed/NAD/ Non Suspect ACM</i>	<i>Amount of Material</i>	<i>SF LF EA</i>	<i>Amount of Damage</i>	<i>SF LF EA</i>	<i>Color required for VAT</i>	<i>Comments/Description/Notes</i>	<i>Attic/ Crawl Space Ranking</i>	
1	1	Hallway outside Classrooms 106 - 118	N/A	Floor Tile VAT 12" x 12"	NAD	1700	SF	0	SF	Grey			
1	1	Hallway outside Classrooms 106 - 118	N/A	Floor Tile VAT 12" x 12"	NAD	800	SF	0	SF	Yellow			
1	1	Hallway outside Classrooms 106 - 118	N/A	Concrete Block Wall	Non Suspect ACM	4000	SF	0	SF				
1	1	Hallway outside Classrooms 106 - 118	N/A	Sheetrock Wall	Non Suspect ACM	1000	SF	0	SF				
1	1	Hallway outside Classrooms 106 - 118	N/A	Ceiling Tile 2' x 4'	Non Suspect ACM	2500	SF	0	SF				
1	1	Hallway outside Classrooms 120 - 129	N/A	Floor Tile VAT 12" x 12"	NAD	1700	SF	0	SF	Grey			
1	1	Hallway outside Classrooms 120 - 129	N/A	Floor Tile VAT 12" x 12"	NAD	800	SF	0	SF	Yellow			
1	1	Hallway outside Classrooms 120 - 129	N/A	Concrete Block Wall	Non Suspect ACM	4000	SF	0	SF				
1	1	Hallway outside Classrooms 120 - 129	N/A	Sheetrock Wall	Non Suspect ACM	1000	SF	0	SF				
1	1	Hallway outside Classrooms 120 - 129	N/A	Ceiling Tile 2' x 4'	Non Suspect ACM	2500	SF	0	SF				
1	1	IMC (Library) 133	N/A	Floor Tile VAT 12" x 12"	NAD	400	SF	0	SF	Green			
1	1	IMC (Library) 133	N/A	Carpet	Non Suspect ACM	5500	SF	0	SF				
1	1	IMC (Library) 133	N/A	Sheetrock Wall	Non Suspect ACM	16,500	SF	0	SF				
1	1	IMC (Library) 133	N/A	Corrugated Metal Ceiling	Non Suspect ACM	5500	SF	0	SF				
1	1	IMC (Library) 133	N/A	Ceiling Tile 2' x 4'	Non Suspect ACM	400	SF	0	SF				
1	1	IMC (Library) 133	N/A	Fiberglass Pipe Insulation	Non Suspect ACM	50	LF	0	LF				
1	1	Computer Lab 135 inside IMC (Library) 133	N/A	Floor Tile VAT 12" x 12"	NAD	900	SF	0	SF	Green			
1	1	Computer Lab 135 inside IMC (Library) 133	N/A	Sheetrock Wall	Non Suspect ACM	2,700	SF	0	SF				
1	1	Computer Lab 135 inside IMC (Library) 133	N/A	Ceiling Tile 2' x 4'	Non Suspect ACM	900	SF	0	SF				
1	1	IT MDF Room 134 inside IMC (Library) 133	N/A	Floor Tile VAT 12" x 12"	NAD	500	SF	0	SF	Green			
1	1	IT MDF Room 134 inside IMC (Library) 133	N/A	Concrete Block Wall	Non Suspect ACM	750	SF	0	SF				
1	1	IT MDF Room 134 inside IMC (Library) 133	N/A	Sheetrock Wall	Non Suspect ACM	750	SF	0	SF				
1	1	IT MDF Room 134 inside IMC (Library) 133	N/A	Corrugated Metal Ceiling	Non Suspect ACM	500	SF	0	SF				
1	1	IT MDF Room 134 inside IMC (Library) 133	N/A	Fireproofing	Non Suspect ACM	50	SF	0	SF				
1	1	IT MDF Room 134 inside IMC (Library) 133	N/A	Fiberglass Pipe Insulation	Non Suspect ACM	60	LF	0	LF				
1	1	Audio-Visual Equipment Room 133B inside IMC (Library) 133	N/A	Floor Tile VAT 12" x 12"	NAD	200	SF	0	SF	Green			
1	1	Audio-Visual Equipment Room 133B inside IMC (Library) 133	N/A	Concrete Block Wall	Non Suspect ACM	600	SF	0	SF				
1	1	Audio-Visual Equipment Room 133B inside IMC (Library) 133	N/A	Ceiling Tile 2' x 4'	Non Suspect ACM	200	SF	0	SF				
1	1	Office 139 inside IMC (Library) 133	N/A	Carpet	Non Suspect ACM	200	SF	0	SF				
1	1	Office 139 inside IMC (Library) 133	N/A	Sheetrock Wall	Non Suspect ACM	600	SF	0	SF				
1	1	Office 139 inside IMC (Library) 133	N/A	Ceiling Tile 2' x 4'	Non Suspect ACM	200	SF	0	SF				
1	1	Office 138 inside IMC (Library) 133	N/A	Floor Tile VAT 12" x 12"	NAD	400	SF	0	SF	Green			
1	1	Office 138 inside IMC (Library) 133	N/A	Sheetrock Wall	Non Suspect ACM	1,200	SF	0	SF				
1	1	Office 138 inside IMC (Library) 133	N/A	Ceiling Tile 2' x 4'	Non Suspect ACM	400	SF	0	SF				
1	1	Storage Room 133A inside IMC (Library) 133	N/A	Floor Tile VAT 12" x 12"	NAD	750	SF	0	SF	Green			
1	1	Storage Room 133A inside IMC (Library) 133	N/A	Sheetrock Wall	Non Suspect ACM	2,250	SF	0	SF				
1	1	Storage Room 133A inside IMC (Library) 133	N/A	Ceiling Tile 2' x 4'	Non Suspect ACM	750	SF	0	SF				
1	1	Office 137A inside IMC (Library) 133	N/A	Floor Tile VAT 12" x 12"	NAD	150	SF	0	SF	Green			
1	1	Office 137A inside IMC (Library) 133	N/A	Sheetrock Wall	Non Suspect ACM	450	SF	0	SF				
1	1	Office 137A inside IMC (Library) 133	N/A	Ceiling Tile 2' x 4'	Non Suspect ACM	150	SF	0	SF				
1	1	Storage Room 137 inside IMC (Library) 133	N/A	Floor Tile VAT 12" x 12"	NAD	750	SF	0	SF	Green			
1	1	Storage Room 137 inside IMC (Library) 133	N/A	Sheetrock Wall	Non Suspect ACM	2,250	SF	0	SF				
1	1	Storage Room 137 inside IMC (Library) 133	N/A	Ceiling Tile 2' x 4'	Non Suspect ACM	750	SF	0	SF				
1	1	Office 136A inside IMC (Library) 133	N/A	Floor Tile VAT 12" x 12"	NAD	150	SF	0	SF	Green			
1	1	Office 136A inside IMC (Library) 133	N/A	Sheetrock Wall	Non Suspect ACM	450	SF	0	SF				
1	1	Office 136A inside IMC (Library) 133	N/A	Ceiling Tile 2' x 4'	Non Suspect ACM	150	SF	2	EA		2 Stained ACTs		
1	1	Office 136 inside IMC (Library) 133	N/A	Carpet	Non Suspect ACM	150	SF	0	SF				
1	1	Office 136 inside IMC (Library) 133	N/A	Sheetrock Wall	Non Suspect ACM	450	SF	0	SF				
1	1	Office 136 inside IMC (Library) 133	N/A	Ceiling Tile 2' x 4'	Non Suspect ACM	150	SF	0	SF				
1	1	Hallway Electrical Room 131B	N/A	Concrete Floor	Non Suspect ACM	100	SF	0	SF				

# 8010 New Lincoln - Room by Room Location Log Report.xls

		School District of Philadelphia New Lincoln High School 3201 Ryan Avenue, Philadelphia, PA 19136 ULCS# 8010 Year Built: 2009	AHERA Three-Year Reinspection 2015-2016 Room by Room Location Log Report								Reinspection Date: December 30, 2016		
											Building Inspector: Bernard J Bryson		
											Number: ACC-0125-6-031		
											Management Planner: Megan Vala		
											Number: 740728		
<i>E l e m e n t</i>	<i>F l o o r</i>	<i>On Site Room Name</i>	<i>System Affected</i>	<i>Material Description</i>	<i>Confirmed/Assumed/NAD/ Non Suspect ACM</i>	<i>Amount of Material</i>	<i>SF LF EA</i>	<i>Amount of Damage</i>	<i>SF LF EA</i>	<i>Color required for VAT</i>	<i>Comments/Description/Notes</i>	<i>Attic/ Crawl Space Ranking</i>	
1	1	Hallway Electrical Room 131B	N/A	Sheetrock Wall	Non Suspect ACM	300	SF	0	SF				
1	1	Hallway Electrical Room 131B	N/A	Corrugated Metal Ceiling	Non Suspect ACM	100	SF	0	SF				
1	1	Hallway Storage Room 131A	N/A	Concrete Floor	Non Suspect ACM	100	SF	0	SF				
1	1	Hallway Storage Room 131A	N/A	Sheetrock Wall	Non Suspect ACM	300	SF	0	SF				
1	1	Hallway Storage Room 131A	N/A	Corrugated Metal Ceiling	Non Suspect ACM	100	SF	0	SF				
1	1	Hallway Storage Room 131A	N/A	Fiberglass Pipe Insulation	Non Suspect ACM	100	LF	0	LF				
1	1	Hallway Storage Room 131A	N/A	Fiberglass Duct Insulation	Non Suspect ACM	100	SF	0	SF				
1	1	School Police Office 131	N/A	Floor Tile VAT 12" x 12"	NAD	200	SF	0	SF	Grey			
1	1	School Police Office 131	N/A	Sheetrock Wall	Non Suspect ACM	600	SF	0	SF				
1	1	School Police Office 131	N/A	Ceiling Tile 2' x 4'	Non Suspect ACM	200	SF	0	SF				
1	1	Office 150	N/A	Carpet	Non Suspect ACM	100	SF	0	SF				
1	1	Office 150	N/A	Sheetrock Wall	Non Suspect ACM	300	SF	0	SF				
1	1	Office 150	N/A	Ceiling Tile 2' x 4'	Non Suspect ACM	100	SF	0	SF				
1	1	Office 151	N/A	Floor Tile VAT 12" x 12"	NAD	200	SF	0	SF	Grey			
1	1	Office 151	N/A	Sheetrock Wall	Non Suspect ACM	600	SF	0	SF				
1	1	Office 151	N/A	Ceiling Tile 2' x 4'	Non Suspect ACM	200	SF	0	SF				
1	1	Office 151	N/A	Floor Tile VAT 12" x 12"	NAD	800	SF	0	SF	Grey			
1	1	Office 152	N/A	Carpet	Non Suspect ACM	100	SF	0	SF				
1	1	Office 152	N/A	Sheetrock Wall	Non Suspect ACM	2,700	SF	0	SF				
1	1	Office 152	N/A	Ceiling Tile 2' x 4'	Non Suspect ACM	900	SF	0	SF				
1	1	Office 158	N/A	Floor Tile VAT 12" x 12"	NAD	100	SF	0	SF	Grey			
1	1	Office 158	N/A	Sheetrock Wall	Non Suspect ACM	300	SF	0	SF				
1	1	Office 158	N/A	Ceiling Tile 2' x 4'	Non Suspect ACM	100	SF	0	SF				
1	1	Office 153	N/A	Carpet	Non Suspect ACM	100	SF	0	SF				
1	1	Office 153	N/A	Sheetrock Wall	Non Suspect ACM	300	SF	0	SF				
1	1	Office 153	N/A	Ceiling Tile 2' x 4'	Non Suspect ACM	100	SF	0	SF				
1	1	Office 154	N/A	Carpet	Non Suspect ACM	100	SF	0	SF				
1	1	Office 154	N/A	Sheetrock Wall	Non Suspect ACM	300	SF	0	SF				
1	1	Office 154	N/A	Ceiling Tile 2' x 4'	Non Suspect ACM	100	SF	0	SF				
1	1	Office 155	N/A	Carpet	Non Suspect ACM	100	SF	0	SF				
1	1	Office 155	N/A	Sheetrock Wall	Non Suspect ACM	300	SF	0	SF				
1	1	Office 155	N/A	Ceiling Tile 2' x 4'	Non Suspect ACM	100	SF	0	SF				
1	1	Computer Room 156	N/A	Floor Tile VAT 12" x 12"	NAD	1800	SF	0	SF	Grey			
1	1	Computer Room 156	N/A	Sheetrock Wall	Non Suspect ACM	5,400	SF	0	SF				
1	1	Computer Room 156	N/A	Ceiling Tile 2' x 4'	Non Suspect ACM	1800	SF	12	EA		12 Stained ACTs		
1	1	Office 157	N/A	Floor Tile VAT 12" x 12"	NAD	200	SF	0	SF	Grey			
1	1	Office 157	N/A	Sheetrock Wall	Non Suspect ACM	600	SF	0	SF				
1	1	Office 157	N/A	Ceiling Tile 2' x 4'	Non Suspect ACM	200	SF	0	SF				
1	1	Hallway outside of Main Office Suite	N/A	Floor Tile VAT 12" x 12"	NAD	2500	SF	0	SF	Grey			
1	1	Hallway outside of Main Office Suite	N/A	Concrete Block Wall	Non Suspect ACM	5500	SF	0	SF				
1	1	Hallway outside of Main Office Suite	N/A	Sheetrock Wall	Non Suspect ACM	2000	SF	0	SF				
1	1	Hallway outside of Main Office Suite	N/A	Ceiling Tile 2' x 4'	Non Suspect ACM	2500	SF	0	SF				
1	1	Office 130	N/A	Carpet	Non Suspect ACM	100	SF	0	SF				
1	1	Office 130	N/A	Sheetrock Wall	Non Suspect ACM	300	SF	0	SF				
1	1	Office 130	N/A	Ceiling Tile 2' x 4'	Non Suspect ACM	100	SF	0	SF				
1	1	Storage Room 130A	N/A	x	x	x	x	x	x	x	No Access		
1	1	Storage Room 130B	N/A	Floor Tile VAT 12" x 12"	NAD	60	SF	0	SF	Grey			
1	1	Storage Room 130B	N/A	Sheetrock Wall	Non Suspect ACM	180	SF	0	SF				
1	1	Storage Room 130B	N/A	Ceiling Tile 2' x 4'	Non Suspect ACM	60	SF	0	SF				
1	1	Office 141	N/A	Carpet	Non Suspect ACM	150	SF	0	SF				
1	1	Office 141	N/A	Sheetrock Wall	Non Suspect ACM	450	SF	0	SF				
1	1	Office 141	N/A	Ceiling Tile 2' x 4'	Non Suspect ACM	150	SF	0	SF				

# 8010 New Lincoln - Room by Room Location Log Report.xls

		School District of Philadelphia New Lincoln High School 3201 Ryan Avenue, Philadelphia, PA 19136 ULCS# 8010 Year Built: 2009	AHERA Three-Year Reinspection 2015-2016 Room by Room Location Log Report								Reinspection Date: December 30, 2016		
											Building Inspector: Bernard J Bryson		
											Number: ACC-0125-6-031		
											Management Planner: Megan Vala		
											Number: 740728		
E l e m e n t	F l o o r	On Site Room Name	System Affected	Material Description	Confirmed/Assumed/NAD/ Non Suspect ACM	Amount of Material	SF LF EA	Amount of Damage	SF LF EA	Color required for VAT	Comments/Description/Notes	Attic/ Crawl/ Space Ranking	
1	1	Office 141 Restroom	N/A	Ceramic Tile Floors	Non Suspect ACM	20	SF	0	SF				
1	1	Office 141 Restroom	N/A	Concrete Block Wall	Non Suspect ACM	80	SF	0	SF				
1	1	Office 141 Restroom	N/A	Ceiling Tile 2' x 4'	Non Suspect ACM	20	SF	0	SF				
1	1	Main Office 140	N/A	Floor Tile VAT 12" x 12"	NAD	400	SF	0	SF	Grey			
1	1	Main Office 140	N/A	Carpet	Non Suspect ACM	1200	SF	0	SF				
1	1	Main Office 140	N/A	Sheetrock Wall	Non Suspect ACM	4,800	SF	0	SF				
1	1	Main Office 140	N/A	Ceiling Tile 2' x 4'	Non Suspect ACM	1600	SF	0	SF				
1	1	Main Office 140	N/A	Ceiling Tile 2' x 4'	Non Suspect ACM	1600	SF	0	SF				
1	1	Storage Closet inside Main Office 140	N/A	Carpet	Non Suspect ACM	30	SF	0	SF				
1	1	Storage Closet inside Main Office 140	N/A	Sheetrock Wall	Non Suspect ACM	100	SF	0	SF				
1	1	Storage Closet inside Main Office 140	N/A	Ceiling Tile 2' x 4'	Non Suspect ACM	30	SF	0	SF				
1	1	Office 142	N/A	Carpet	Non Suspect ACM	150	SF	0	SF				
1	1	Office 142	N/A	Sheetrock Wall	Non Suspect ACM	450	SF	0	SF				
1	1	Office 142	N/A	Ceiling Tile 2' x 4'	Non Suspect ACM	150	SF	0	SF				
1	1	Office 143	N/A	Floor Tile VAT 12" x 12"	NAD	100	SF	0	SF	Grey			
1	1	Office 143	N/A	Sheetrock Wall	Non Suspect ACM	300	SF	0	SF				
1	1	Office 143	N/A	Ceiling Tile 2' x 4'	Non Suspect ACM	100	SF	0	SF				
1	1	Office 144	N/A	Floor Tile VAT 12" x 12"	NAD	100	SF	0	SF	Grey			
1	1	Office 144	N/A	Sheetrock Wall	Non Suspect ACM	300	SF	0	SF				
1	1	Office 144	N/A	Ceiling Tile 2' x 4'	Non Suspect ACM	100	SF	0	SF				
1	1	Office 145	N/A	Floor Tile VAT 12" x 12"	NAD	100	SF	0	SF	Grey			
1	1	Office 145	N/A	Sheetrock Wall	Non Suspect ACM	300	SF	0	SF				
1	1	Office 145	N/A	Ceiling Tile 2' x 4'	Non Suspect ACM	100	SF	0	SF				
1	1	Office 146	N/A	Floor Tile VAT 12" x 12"	NAD	1400	SF	0	SF	Grey			
1	1	Office 146	N/A	Sheetrock Wall	Non Suspect ACM	4,200	SF	0	SF				
1	1	Office 146	N/A	Ceiling Tile 2' x 4'	Non Suspect ACM	1400	SF	5	EA		5 Stained ACTs		
1	1	Office 147	N/A	Carpet	Non Suspect ACM	150	SF	0	SF				
1	1	Office 147	N/A	Sheetrock Wall	Non Suspect ACM	450	SF	0	SF				
1	1	Office 147	N/A	Ceiling Tile 2' x 4'	Non Suspect ACM	150	SF	0	SF				
1	1	Office 147A	N/A	Floor Tile VAT 12" x 12"	NAD	200	SF	0	SF	Grey			
1	1	Office 147A	N/A	Sheetrock Wall	Non Suspect ACM	600	SF	0	SF				
1	1	Office 147A	N/A	Ceiling Tile 2' x 4'	Non Suspect ACM	200	SF	0	SF				
1	1	Office 148	N/A	Floor Tile VAT 12" x 12"	NAD	200	SF	0	SF	Grey			
1	1	Office 148	N/A	Sheetrock Wall	Non Suspect ACM	600	SF	0	SF				
1	1	Office 148	N/A	Ceiling Tile 2' x 4'	Non Suspect ACM	200	SF	0	SF				
1	1	Staff Restroom in the Main Office Suite	N/A	Ceramic Tile Floors	Non Suspect ACM	100	SF	0	SF				
1	1	Staff Restroom in the Main Office Suite	N/A	Concrete Block Wall	Non Suspect ACM	300	SF	0	SF				
1	1	Staff Restroom in the Main Office Suite	N/A	Ceiling Tile 2' x 4'	Non Suspect ACM	100	SF	0	SF				
1	1	Hallway behind Main Office Suite	N/A	Floor Tile VAT 12" x 12"	NAD	1200	SF	0	SF	Grey			
1	1	Hallway behind Main Office Suite	N/A	Sheetrock Wall	Non Suspect ACM	3,600	SF	0	SF				
1	1	Hallway behind Main Office Suite	N/A	Ceiling Tile 2' x 4'	Non Suspect ACM	1200	SF	0	SF				
1	1	Nurse's Office 149 Hallway	N/A	Carpet	Non Suspect ACM	750	SF	0	SF				
1	1	Nurse's Office 149 Hallway	N/A	Sheetrock Wall	Non Suspect ACM	2,250	SF	0	SF				
1	1	Nurse's Office 149 Hallway	N/A	Ceiling Tile 2' x 4'	Non Suspect ACM	750	SF	0	SF				
1	1	Staff Restroom inside Nurse's Office 149 - Right	N/A	Ceramic Tile Floors	Non Suspect ACM	80	SF	0	SF				
1	1	Staff Restroom inside Nurse's Office 149 - Right	N/A	Concrete Block Wall	Non Suspect ACM	240	SF	0	SF				
1	1	Staff Restroom inside Nurse's Office 149 - Right	N/A	Ceiling Tile 2' x 4'	Non Suspect ACM	80	SF	0	SF				
1	1	Student Restroom inside Nurse's Office 149 - Left	N/A	Ceramic Tile Floors	Non Suspect ACM	80	SF	0	SF				
1	1	Student Restroom inside Nurse's Office 149 - Left	N/A	Concrete Block Wall	Non Suspect ACM	240	SF	0	SF				
1	1	Student Restroom inside Nurse's Office 149 - Left	N/A	Ceiling Tile 2' x 4'	Non Suspect ACM	80	SF	0	SF				
1	1	Office 149E	N/A	Carpet	Non Suspect ACM	100	SF	0	SF				
1	1	Office 149E	N/A	Sheetrock Wall	Non Suspect ACM	300	SF	0	SF				

# 8010 New Lincoln - Room by Room Location Log Report.xls

		School District of Philadelphia New Lincoln High School 3201 Ryan Avenue, Philadelphia, PA 19136 ULCS# 8010 Year Built: 2009	AHERA Three-Year Reinspection 2015-2016 Room by Room Location Log Report								Reinspection Date: December 30, 2016	
											Building Inspector: Bernard J Bryson	
											Number: ACC-0125-6-031	
											Management Planner: Megan Vala	
											Number: 740728	
<i>E l e m e n t</i>	<i>F l o o r</i>	<i>On Site Room Name</i>	<i>System Affected</i>	<i>Material Description</i>	<i>Confirmed/Assumed/NAD/ Non Suspect ACM</i>	<i>Amount of Material</i>	<i>SF LF EA</i>	<i>Amount of Damage</i>	<i>SF LF EA</i>	<i>Color required for VAT</i>	<i>Comments/Description/Notes</i>	<i>Attic/ Crawl Space Ranking</i>
1	1	Office 149E	N/A	Ceiling Tile 2' x 4'	Non Suspect ACM	100	SF	0	SF			
1	1	Office 149D	N/A	Carpet	Non Suspect ACM	100	SF	0	SF			
1	1	Office 149D	N/A	Sheetrock Wall	Non Suspect ACM	300	SF	0	SF			
1	1	Office 149D	N/A	Ceiling Tile 2' x 4'	Non Suspect ACM	100	SF	0	SF			
1	1	Office 149	N/A	Carpet	Non Suspect ACM	100	SF	0	SF			
1	1	Office 149	N/A	Sheetrock Wall	Non Suspect ACM	300	SF	0	SF			
1	1	Office 149	N/A	Ceiling Tile 2' x 4'	Non Suspect ACM	100	SF	0	SF			
1	1	Office 149A	N/A	Carpet	Non Suspect ACM	100	SF	0	SF			
1	1	Office 149A	N/A	Sheetrock Wall	Non Suspect ACM	300	SF	0	SF			
1	1	Office 149A	N/A	Ceiling Tile 2' x 4'	Non Suspect ACM	100	SF	0	SF			
1	1	Office 149B	N/A	Floor Tile VAT 12" x 12"	NAD	100	SF	0	SF	Grey		
1	1	Office 149B	N/A	Sheetrock Wall	Non Suspect ACM	300	SF	0	SF			
1	1	Office 149B	N/A	Ceiling Tile 2' x 4'	Non Suspect ACM	100	SF	0	SF			
1	1	Office 149C	N/A	Floor Tile VAT 12" x 12"	NAD	100	SF	0	SF	Grey		
1	1	Office 149C	N/A	Sheetrock Wall	Non Suspect ACM	300	SF	0	SF			
1	1	Office 149C	N/A	Ceiling Tile 2' x 4'	Non Suspect ACM	100	SF	0	SF			
1	1	Hallway outside Classrooms 160 - 165	N/A	Floor Tile VAT 12" x 12"	NAD	900	SF	0	SF	Grey	12"x 12" Grey with a few Yellow Floor Tile Accents	
1	1	Hallway outside Classrooms 160 - 165	N/A	Concrete Block Wall	Non Suspect ACM	1500	SF	0	SF			
1	1	Hallway outside Classrooms 160 - 165	N/A	Sheetrock Wall	Non Suspect ACM	300	SF	0	SF			
1	1	Hallway outside Classrooms 160 - 165	N/A	Ceiling Tile 2' x 4'	Non Suspect ACM	900	SF	0	SF			
1	1	Hallway outside Classrooms 162 - 169	N/A	Floor Tile VAT 12" x 12"	NAD	1800	SF	0	SF	Grey	12"x 12" Grey with a few Yellow Floor Tile Accents	
1	1	Hallway outside Classrooms 162 - 169	N/A	Concrete Block Wall	Non Suspect ACM	3000	SF	0	SF			
1	1	Hallway outside Classrooms 162 - 169	N/A	Sheetrock Wall	Non Suspect ACM	600	SF	0	SF			
1	1	Hallway outside Classrooms 162 - 169	N/A	Ceiling Tile 2' x 4'	Non Suspect ACM	1800	SF	0	SF			
1	1	Science Classroom 160	N/A	Floor Tile VAT 12" x 12"	NAD	1500	SF	0	SF	Yellow		
1	1	Science Classroom 160	N/A	Concrete Block Wall	Non Suspect ACM	2250	SF	0	SF			
1	1	Science Classroom 160	N/A	Sheetrock Wall	Non Suspect ACM	2250	SF	0	SF			
1	1	Science Classroom 160	N/A	Ceiling Tile 2' x 4'	Non Suspect ACM	1500	SF	5	EA		5 Stained ACTs	
1	1	Science Classroom 160	N/A	Lab Table Tops/Sinks	Non Suspect ACM	200	SF	0	SF	Black		
1	1	Science Lab Prep Room 160A	N/A	Floor Tile VAT 12" x 12"	NAD	350	SF	0	SF	Yellow		
1	1	Science Lab Prep Room 160A	N/A	Concrete Block Wall	Non Suspect ACM	800	SF	0	SF			
1	1	Science Lab Prep Room 160A	N/A	Sheetrock Wall	Non Suspect ACM	250	SF	0	SF			
1	1	Science Lab Prep Room 160A	N/A	Ceiling Tile 2' x 4'	Non Suspect ACM	350	SF	0	SF			
1	1	Science Lab Prep Room 160A	N/A	Lab Table Tops/Sinks	Non Suspect ACM	50	SF	0	SF	Black		
1	1	Science Classroom 162	N/A	Floor Tile VAT 12" x 12"	NAD	1500	SF	0	SF	Yellow		
1	1	Science Classroom 162	N/A	Concrete Block Wall	Non Suspect ACM	2250	SF	0	SF			
1	1	Science Classroom 162	N/A	Sheetrock Wall	Non Suspect ACM	2250	SF	0	SF			
1	1	Science Classroom 162	N/A	Ceiling Tile 2' x 4'	Non Suspect ACM	1500	SF	5	EA		5 Stained ACTs	
1	1	Science Classroom 162	N/A	Lab Table Tops/Sinks	Non Suspect ACM	200	SF	0	SF	Black		
1	1	Science Lab Prep Room 162A	N/A	Floor Tile VAT 12" x 12"	NAD	350	SF	0	SF	Yellow		
1	1	Science Lab Prep Room 162A	N/A	Concrete Block Wall	Non Suspect ACM	800	SF	0	SF			
1	1	Science Lab Prep Room 162A	N/A	Sheetrock Wall	Non Suspect ACM	250	SF	0	SF			
1	1	Science Lab Prep Room 162A	N/A	Ceiling Tile 2' x 4'	Non Suspect ACM	350	SF	0	SF			
1	1	Science Lab Prep Room 162A	N/A	Lab Table Tops/Sinks	Non Suspect ACM	50	SF	0	SF	Black		
1	1	Science Classroom 164	N/A	Floor Tile VAT 12" x 12"	NAD	1500	SF	0	SF	Yellow		
1	1	Science Classroom 164	N/A	Concrete Block Wall	Non Suspect ACM	2250	SF	0	SF			
1	1	Science Classroom 164	N/A	Sheetrock Wall	Non Suspect ACM	2250	SF	0	SF			
1	1	Science Classroom 164	N/A	Ceiling Tile 2' x 4'	Non Suspect ACM	1500	SF	0	SF			
1	1	Science Classroom 164	N/A	Lab Table Tops/Sinks	Non Suspect ACM	200	SF	0	SF	Black		
1	1	Classroom 166	N/A	Floor Tile VAT 12" x 12"	NAD	1000	SF	0	SF	Yellow		

# 8010 New Lincoln - Room by Room Location Log Report.xls

		School District of Philadelphia New Lincoln High School 3201 Ryan Avenue, Philadelphia, PA 19136 ULCS# 8010 Year Built: 2009	AHERA Three-Year Reinspection 2015-2016 Room by Room Location Log Report								Reinspection Date: December 30, 2016		
											Building Inspector: Bernard J Bryson		
											Number: ACC-0125-6-031		
											Management Planner: Megan Vala		
											Number: 740728		
E l e m e n t	F l o o r	On Site Room Name	System Affected	Material Description	Confirmed/Assumed/NAD/ Non Suspect ACM	Amount of Material	SF LF EA	Amount of Damage	SF LF EA	Color required for VAT	Comments/Description/Notes	Attic/ Crawl/ Space Ranking	
1	1	Classroom 166	N/A	Concrete Block Wall	Non Suspect ACM	1500	SF	0	SF				
1	1	Classroom 166	N/A	Sheetrock Wall	Non Suspect ACM	1500	SF	0	SF				
1	1	Classroom 166	N/A	Ceiling Tile 2' x 4'	Non Suspect ACM	1000	SF	0	SF				
1	1	Classroom 168	N/A	Floor Tile VAT 12" x 12"	NAD	1000	SF	0	SF	Yellow			
1	1	Classroom 168	N/A	Concrete Block Wall	Non Suspect ACM	1500	SF	0	SF				
1	1	Classroom 168	N/A	Sheetrock Wall	Non Suspect ACM	1500	SF	0	SF				
1	1	Classroom 168	N/A	Ceiling Tile 2' x 4'	Non Suspect ACM	1000	SF	0	SF				
1	1	Classroom 161	N/A	Floor Tile VAT 12" x 12"	NAD	1000	SF	0	SF	Yellow			
1	1	Classroom 161	N/A	Concrete Block Wall	Non Suspect ACM	1500	SF	0	SF				
1	1	Classroom 161	N/A	Sheetrock Wall	Non Suspect ACM	1500	SF	0	SF				
1	1	Classroom 161	N/A	Ceiling Tile 2' x 4'	Non Suspect ACM	1000	SF	0	SF				
1	1	Classroom 163	N/A	Floor Tile VAT 12" x 12"	NAD	1000	SF	0	SF	Yellow			
1	1	Classroom 163	N/A	Concrete Block Wall	Non Suspect ACM	1500	SF	0	SF				
1	1	Classroom 163	N/A	Sheetrock Wall	Non Suspect ACM	1500	SF	0	SF				
1	1	Classroom 163	N/A	Ceiling Tile 2' x 4'	Non Suspect ACM	1000	SF	0	SF				
1	1	Classroom 165	N/A	Floor Tile VAT 12" x 12"	NAD	1000	SF	0	SF	Yellow			
1	1	Classroom 165	N/A	Concrete Block Wall	Non Suspect ACM	1500	SF	0	SF				
1	1	Classroom 165	N/A	Sheetrock Wall	Non Suspect ACM	1500	SF	0	SF				
1	1	Classroom 165	N/A	Ceiling Tile 2' x 4'	Non Suspect ACM	1000	SF	0	SF				
1	1	Classroom 167	N/A	Floor Tile VAT 12" x 12"	NAD	1000	SF	0	SF	Yellow			
1	1	Classroom 167	N/A	Concrete Block Wall	Non Suspect ACM	1500	SF	0	SF				
1	1	Classroom 167	N/A	Sheetrock Wall	Non Suspect ACM	1500	SF	0	SF				
1	1	Classroom 167	N/A	Ceiling Tile 2' x 4'	Non Suspect ACM	1000	SF	0	SF				
1	1	Classroom 169	N/A	Floor Tile VAT 12" x 12"	NAD	1000	SF	0	SF	Yellow			
1	1	Classroom 169	N/A	Concrete Block Wall	Non Suspect ACM	1500	SF	0	SF				
1	1	Classroom 169	N/A	Sheetrock Wall	Non Suspect ACM	1500	SF	0	SF				
1	1	Classroom 169	N/A	Ceiling Tile 2' x 4'	Non Suspect ACM	1000	SF	0	SF				
1	1	Electrical Room 165A	N/A	Concrete Floor	Non Suspect ACM	50	SF	0	SF				
1	1	Electrical Room 165A	N/A	Concrete Block Wall	Non Suspect ACM	150	SF	0	SF				
1	1	Electrical Room 165A	N/A	Corrugated Metal Ceiling	Non Suspect ACM	50	SF	0	SF				
1	1	Electrical Room 165A	N/A	Fireproofing	Non Suspect ACM	25	SF	0	SF				
1	1	Storage Room 165B	N/A	Floor Tile VAT 12" x 12"	NAD	50	SF	0	SF	Grey			
1	1	Storage Room 165B	N/A	Concrete Block Wall	Non Suspect ACM	150	SF	0	SF				
1	1	Storage Room 165B	N/A	Corrugated Metal Ceiling	Non Suspect ACM	50	SF	0	SF				
1	1	Storage Room 165B	N/A	Fiberglass Duct Insulation	Non Suspect ACM	70	SF	0	SF				
1	1	Girl's Restroom next to Classroom 165	N/A	Ceramic Tile Floors	Non Suspect ACM	500	SF	0	SF				
1	1	Girl's Restroom next to Classroom 165	N/A	Concrete Block Wall	Non Suspect ACM	1500	SF	0	SF				
1	1	Girl's Restroom next to Classroom 165	N/A	Ceiling Tile 2' x 4'	Non Suspect ACM	500	SF	0	SF				
1	1	Boy's Restroom next to Classroom 167	N/A	Ceramic Tile Floors	Non Suspect ACM	500	SF	0	SF				
1	1	Boy's Restroom next to Classroom 167	N/A	Concrete Block Wall	Non Suspect ACM	1500	SF	0	SF				
1	1	Boy's Restroom next to Classroom 167	N/A	Ceiling Tile 2' x 4'	Non Suspect ACM	500	SF	0	SF				
1	1	IT MDF Room 167A	N/A	Concrete Floor	Non Suspect ACM	50	SF	0	SF				
1	1	IT MDF Room 167A	N/A	Concrete Block Wall	Non Suspect ACM	150	SF	0	SF				
1	1	IT MDF Room 167A	N/A	Corrugated Metal Ceiling	Non Suspect ACM	50	SF	0	SF				
1	1	IT MDF Room 167A	N/A	Fiberglass Duct Insulation	Non Suspect ACM	40	SF	0	SF				
1	1	IT MDF Room 167A	N/A	Fiberglass Pipe Insulation	Non Suspect ACM	20	LF	0	LF				
1	1	Electrical Room 167B	N/A	Concrete Floor	Non Suspect ACM	50	SF	0	SF				
1	1	Electrical Room 167B	N/A	Concrete Block Wall	Non Suspect ACM	150	SF	0	SF				
1	1	Electrical Room 167B	N/A	Corrugated Metal Ceiling	Non Suspect ACM	50	SF	0	SF				
1	1	Custodial Closet 171A	N/A	Concrete Floor	Non Suspect ACM	20	SF	0	SF				
1	1	Custodial Closet 171A	N/A	Concrete Block Wall	Non Suspect ACM	80	SF	0	SF				
1	1	Custodial Closet 171A	N/A	Corrugated Metal Ceiling	Non Suspect ACM	20	SF	0	SF				

# 8010 New Lincoln - Room by Room Location Log Report.xls

		School District of Philadelphia New Lincoln High School 3201 Ryan Avenue, Philadelphia, PA 19136 ULCS# 8010 Year Built: 2009	AHERA Three-Year Reinspection 2015-2016 Room by Room Location Log Report								Reinspection Date: December 30, 2016	
											Building Inspector: Bernard J Bryson	
											Number: ACC-0125-6-031	
											Management Planner: Megan Vala	
											Number: 740728	
<i>E l e m e n t</i>	<i>F l o o r</i>	<i>On Site Room Name</i>	<i>System Affected</i>	<i>Material Description</i>	<i>Confirmed/Assumed/NAD/ Non Suspect ACM</i>	<i>Amount of Material</i>	<i>SF LF EA</i>	<i>Amount of Damage</i>	<i>SF LF EA</i>	<i>Color required for VAT</i>	<i>Comments/Description/Notes</i>	<i>Attic/ Crawl/ Space Ranking</i>
1	1	Custodial Closet 171A	N/A	Fiberglass Pipe Insulation	Non Suspect ACM	25	LF	0	LF			
1	1	Staff Restroom next to Classroom 171 - Left	N/A	Ceramic Tile Floors	Non Suspect ACM	80	SF	0	SF			
1	1	Staff Restroom next to Classroom 171 - Left	N/A	Concrete Block Wall	Non Suspect ACM	240	SF	0	SF			
1	1	Staff Restroom next to Classroom 171 - Left	N/A	Ceiling Tile 2' x 4'	Non Suspect ACM	80	SF	0	SF			
1	1	Staff Restroom next to Classroom 171 - Right	N/A	Ceramic Tile Floors	Non Suspect ACM	80	SF	0	SF			
1	1	Staff Restroom next to Classroom 171 - Right	N/A	Concrete Block Wall	Non Suspect ACM	240	SF	0	SF			
1	1	Staff Restroom next to Classroom 171 - Right	N/A	Ceiling Tile 2' x 4'	Non Suspect ACM	80	SF	0	SF			
1	1	Classroom 170	N/A	Floor Tile VAT 12" x 12"	NAD	900	SF	0	SF	Yellow		
1	1	Classroom 170	N/A	Sheetrock Wall	Non Suspect ACM	2700	SF	0	SF			
1	1	Classroom 170	N/A	Ceiling Tile 2' x 4'	Non Suspect ACM	900	SF	3	EA		3 Stained ACTs	
1	1	Classroom 171	N/A	Floor Tile VAT 12" x 12"	NAD	900	SF	0	SF	Yellow		
1	1	Classroom 171	N/A	Sheetrock Wall	Non Suspect ACM	2700	SF	0	SF			
1	1	Classroom 171	N/A	Ceiling Tile 2' x 4'	Non Suspect ACM	900	SF	0	SF			
1	1	Classroom 172	N/A	Floor Tile VAT 12" x 12"	NAD	900	SF	0	SF	Yellow		
1	1	Classroom 172	N/A	Sheetrock Wall	Non Suspect ACM	2700	SF	0	SF			
1	1	Classroom 172	N/A	Ceiling Tile 2' x 4'	Non Suspect ACM	900	SF	0	SF			
1	1	Classroom 173	N/A	Floor Tile VAT 12" x 12"	NAD	900	SF	0	SF	Yellow		
1	1	Classroom 173	N/A	Sheetrock Wall	Non Suspect ACM	2700	SF	0	SF			
1	1	Classroom 173	N/A	Ceiling Tile 2' x 4'	Non Suspect ACM	900	SF	0	SF			
1	1	Classroom 174	N/A	Floor Tile VAT 12" x 12"	NAD	900	SF	0	SF	Yellow		
1	1	Classroom 174	N/A	Sheetrock Wall	Non Suspect ACM	2700	SF	0	SF			
1	1	Classroom 174	N/A	Ceiling Tile 2' x 4'	Non Suspect ACM	900	SF	0	SF			
1	1	Classroom 175	N/A	Floor Tile VAT 12" x 12"	NAD	900	SF	0	SF	Yellow		
1	1	Classroom 175	N/A	Sheetrock Wall	Non Suspect ACM	2700	SF	0	SF			
1	1	Classroom 175	N/A	Ceiling Tile 2' x 4'	Non Suspect ACM	900	SF	0	SF			
1	1	Classroom 176	N/A	Floor Tile VAT 12" x 12"	NAD	900	SF	0	SF	Yellow		
1	1	Classroom 176	N/A	Sheetrock Wall	Non Suspect ACM	2700	SF	0	SF			
1	1	Classroom 176	N/A	Ceiling Tile 2' x 4'	Non Suspect ACM	900	SF	0	SF			
1	1	Classroom 177	N/A	Floor Tile VAT 12" x 12"	NAD	900	SF	0	SF	Yellow		
1	1	Classroom 177	N/A	Sheetrock Wall	Non Suspect ACM	2700	SF	0	SF			
1	1	Classroom 177	N/A	Ceiling Tile 2' x 4'	Non Suspect ACM	900	SF	0	SF			
1	1	Hallway outside Classrooms 170 - 177	N/A	Floor Tile VAT 12" x 12"	NAD	2000	SF	0	SF	Grey	12"x 12" Grey with a few Yellow Floor Tile Accents	
1	1	Hallway outside Classrooms 170 - 177	N/A	Concrete Block Wall	Non Suspect ACM	3000	SF	0	SF			
1	1	Hallway outside Classrooms 170 - 177	N/A	Sheetrock Wall	Non Suspect ACM	1,000	SF	0	SF			
1	1	Hallway outside Classrooms 170 - 177	N/A	Ceiling Tile 2' x 4'	Non Suspect ACM	2000	SF	0	SF			
1	1	Entrance Vestibule next to Gymnasium	N/A	Rubber Tread Floor	Non Suspect ACM	200	SF	0	SF	Black		
1	1	Entrance Vestibule next to Gymnasium	N/A	Glass Wall	Non Suspect ACM	400	SF	0	SF			
1	1	Entrance Vestibule next to Gymnasium	N/A	Concrete Block Wall	Non Suspect ACM	200	SF	0	SF			
1	1	Entrance Vestibule next to Gymnasium	N/A	Sheetrock Ceiling	Non Suspect ACM	200	SF	0	SF			
1	1	Entrance Vestibule next to Gymnasium	N/A	Fiberglass Pipe Insulation	Non Suspect ACM	120	LF	0	LF			
1	1	Main Hallway outside of Gymnasium and Auditorium	N/A	Floor Tile VAT 12" x 12"	NAD	10,350	SF	0	SF	Grey		
1	1	Main Hallway outside of Gymnasium and Auditorium	N/A	Brick Wall	Non Suspect ACM	10,350	SF	0	SF			
1	1	Main Hallway outside of Gymnasium and Auditorium	N/A	Concrete Block Wall	Non Suspect ACM	10,350	SF	0	SF			
1	1	Main Hallway outside of Gymnasium and Auditorium	N/A	Sheetrock Wall	Non Suspect ACM	10,350	SF	0	SF			
1	1	Main Hallway outside of Gymnasium and Auditorium	N/A	Corrugated Metal Ceiling	Non Suspect ACM	750	SF	0	SF			
1	1	Main Hallway outside of Gymnasium and Auditorium	N/A	Ceiling Tile 2' x 4'	Non Suspect ACM	9600	SF	0	SF			
1	1	Storage Room 194E	N/A	Carpet	Non Suspect ACM	150	SF	0	SF			
1	1	Storage Room 194E	N/A	Sheetrock Wall	Non Suspect ACM	450	SF	0	SF			
1	1	Storage Room 194E	N/A	Ceiling Tile 2' x 4'	Non Suspect ACM	150	SF	0	SF			
1	1	Water Main Room 194D	N/A	Concrete Floor	Non Suspect ACM	100	SF	0	SF			
1	1	Water Main Room 194D	N/A	Sheetrock Wall	Non Suspect ACM	300	SF	0	SF			

# 8010 New Lincoln - Room by Room Location Log Report.xls

		School District of Philadelphia New Lincoln High School 3201 Ryan Avenue, Philadelphia, PA 19136 ULCS# 8010 Year Built: 2009	AHERA Three-Year Reinspection 2015-2016 Room by Room Location Log Report								Reinspection Date: December 30, 2016	
											Building Inspector: Bernard J Bryson	
											Number: ACC-0125-6-031	
											Management Planner: Megan Vala	
											Number: 740728	
E l e m e n t	F l o o r	On Site Room Name	System Affected	Material Description	Confirmed/Assumed/NAD/ Non Suspect ACM	Amount of Material	SF LF EA	Amount of Damage	SF LF EA	Color required for VAT	Comments/Description/Notes	Attic/ Crawl Space Ranking
1	1	Water Main Room 194D	N/A	Corrugated Metal Ceiling	Non Suspect ACM	100	SF	0	SF			
1	1	Water Main Room 194D	N/A	Fiberglass Pipe Insulation	Non Suspect ACM	30	LF	0	LF			
1	1	Girl's Restroom across from Gymnasium 194	N/A	Ceramic Tile Floors	Non Suspect ACM	200	SF	0	SF			
1	1	Girl's Restroom across from Gymnasium 194	N/A	Concrete Block Wall	Non Suspect ACM	600	SF	0	SF			
1	1	Girl's Restroom across from Gymnasium 194	N/A	Ceiling Tile 2' x 4'	Non Suspect ACM	200	SF	0	SF			
1	1	Boy's Restroom across from Gymnasium 194	N/A	Ceramic Tile Floors	Non Suspect ACM	200	SF	0	SF			
1	1	Boy's Restroom across from Gymnasium 194	N/A	Concrete Block Wall	Non Suspect ACM	600	SF	0	SF			
1	1	Boy's Restroom across from Gymnasium 194	N/A	Ceiling Tile 2' x 4'	Non Suspect ACM	200	SF	0	SF			
1	1	Girl's Restroom across from Auditorium 193	N/A	Ceramic Tile Floors	Non Suspect ACM	500	SF	0	SF			
1	1	Girl's Restroom across from Auditorium 193	N/A	Concrete Block Wall	Non Suspect ACM	1500	SF	0	SF			
1	1	Girl's Restroom across from Auditorium 193	N/A	Ceiling Tile 2' x 4'	Non Suspect ACM	500	SF	0	SF			
1	1	Boy's Restroom across from Auditorium 193	N/A	Ceramic Tile Floors	Non Suspect ACM	500	SF	0	SF			
1	1	Boy's Restroom across from Auditorium 193	N/A	Concrete Block Wall	Non Suspect ACM	1500	SF	0	SF			
1	1	Boy's Restroom across from Auditorium 193	N/A	Ceiling Tile 2' x 4'	Non Suspect ACM	500	SF	0	SF			
1	1	Music Classroom 190	N/A	Floor Tile VAT 12" x 12"	NAD	1600	SF	0	SF	Grey		
1	1	Music Classroom 190	N/A	Concrete Block Wall	Non Suspect ACM	2400	SF	0	SF			
1	1	Music Classroom 190	N/A	Sheetrock Wall	Non Suspect ACM	2,400	SF	0	SF			
1	1	Music Classroom 190	N/A	Ceiling Tile 2' x 4'	Non Suspect ACM	1600	SF	0	SF		1 Wet Ceiling Mounted Light Fixture	
1	1	Front Storage Room inside Music Classroom 190	N/A	Floor Tile VAT 12" x 12"	NAD	120	SF	0	SF	Grey		
1	1	Front Storage Room inside Music Classroom 190	N/A	Concrete Block Wall	Non Suspect ACM	180	SF	0	SF			
1	1	Front Storage Room inside Music Classroom 190	N/A	Sheetrock Wall	Non Suspect ACM	180	SF	0	SF			
1	1	Front Storage Room inside Music Classroom 190	N/A	Ceiling Tile 2' x 4'	Non Suspect ACM	120	SF	13	EA		13 Stained ACTs	
1	1	Rear Storage Room inside Music Classroom 190	N/A	Floor Tile VAT 12" x 12"	NAD	120	SF	0	SF	Grey		
1	1	Rear Storage Room inside Music Classroom 190	N/A	Concrete Block Wall	Non Suspect ACM	180	SF	0	SF			
1	1	Rear Storage Room inside Music Classroom 190	N/A	Sheetrock Wall	Non Suspect ACM	180	SF	0	SF			
1	1	Rear Storage Room inside Music Classroom 190	N/A	Ceiling Tile 2' x 4'	Non Suspect ACM	120	SF	8	EA		8 Stained ACTs	
1	1	Music Classroom 191	N/A	Floor Tile VAT 12" x 12"	NAD	1800	SF	0	SF	Grey		
1	1	Music Classroom 191	N/A	Concrete Block Wall	Non Suspect ACM	2700	SF	0	SF			
1	1	Music Classroom 191	N/A	Sheetrock Wall	Non Suspect ACM	2700	SF	0	SF			
1	1	Music Classroom 191	N/A	Ceiling Tile 2' x 4'	Non Suspect ACM	1800	SF	0	SF			
1	1	Music Practice Room 191A	N/A	Carpet	Non Suspect ACM	80	SF	0	SF			
1	1	Music Practice Room 191A	N/A	Sheetrock Wall	Non Suspect ACM	240	SF	0	SF			
1	1	Music Practice Room 191A	N/A	Ceiling Tile 2' x 4'	Non Suspect ACM	80	SF	0	SF			
1	1	Music Practice Room 191B	N/A	Carpet	Non Suspect ACM	80	SF	0	SF			
1	1	Music Practice Room 191B	N/A	Sheetrock Wall	Non Suspect ACM	240	SF	0	SF			
1	1	Music Practice Room 191B	N/A	Ceiling Tile 2' x 4'	Non Suspect ACM	80	SF	0	SF			
1	1	Music Practice Room 191C	N/A	Carpet	Non Suspect ACM	80	SF	0	SF			
1	1	Music Practice Room 191C	N/A	Sheetrock Wall	Non Suspect ACM	240	SF	0	SF			
1	1	Music Practice Room 191C	N/A	Ceiling Tile 2' x 4'	Non Suspect ACM	80	SF	0	SF			
1	1	Art Classroom 192	N/A	Concrete Floor	Non Suspect ACM	1250	SF	0	SF			
1	1	Art Classroom 192	N/A	Concrete Block Wall	Non Suspect ACM	1875	SF	0	SF			
1	1	Art Classroom 192	N/A	Sheetrock Wall	Non Suspect ACM	1875	SF	0	SF			
1	1	Art Classroom 192	N/A	Ceiling Tile 2' x 4'	Non Suspect ACM	1250	SF	0	SF			
1	1	Art Classroom 192	N/A	Fiberglass Pipe Insulation	Non Suspect ACM	100	LF	0	LF			
1	1	Narrow Hallway outside of Art Classroom 192 and Auditorium	N/A	Floor Tile VAT 12" x 12"	NAD	1000	SF	0	SF	Grey		
1	1	Narrow Hallway outside of Art Classroom 192 and Auditorium	N/A	Concrete Block Wall	Non Suspect ACM	1500	SF	0	SF			
1	1	Narrow Hallway outside of Art Classroom 192 and Auditorium	N/A	Sheetrock Wall	Non Suspect ACM	1500	SF	0	SF			
1	1	Narrow Hallway outside of Art Classroom 192 and Auditorium	N/A	Ceiling Tile 2' x 4'	Non Suspect ACM	660	SF	0	SF			



# 8010 New Lincoln - Room by Room Location Log Report.xls

		School District of Philadelphia New Lincoln High School 3201 Ryan Avenue, Philadelphia, PA 19136 ULCS# 8010 Year Built: 2009	AHERA Three-Year Reinspection 2015-2016 Room by Room Location Log Report								Reinspection Date: December 30, 2016	
											Building Inspector: Bernard J Bryson	
											Number: ACC-0125-6-031	
											Management Planner: Megan Vala	
											Number: 740728	
E l e m e n t	F l o o r	On Site Room Name	System Affected	Material Description	Confirmed/Assumed/NAD/ Non Suspect ACM	Amount of Material	SF LF EA	Amount of Damage	SF LF EA	Color required for VAT	Comments/Description/Notes	Attic/ Crawl Space Ranking
1	1	Narrow Hallway outside of Art Classroom 192 and Auditorium	N/A	Corrugated Metal Ceiling	Non Suspect ACM	340	SF	0	SF			
1	1	Narrow Hallway outside of Art Classroom 192 and Auditorium	N/A	Fiberglass Duct Insulation	Non Suspect ACM	200	SF	0	SF			
1	1	Narrow Hallway outside of Art Classroom 192 and Auditorium	N/A	Fiberglass Pipe Insulation	Non Suspect ACM	150	LF	0	LF			
1	1	Narrow Hallway outside of Art Classroom 192 and Auditorium	N/A	Neoprene Duct Insulation	Non Suspect ACM	5	SF	0	SF		Around Heating Coils	
1	1	Narrow Hallway outside of Music Classrooms 190 and 191	N/A	Floor Tile VAT 12" x 12"	NAD	600	SF	0	SF	Grey		
1	1	Narrow Hallway outside of Music Classrooms 190 and 191	N/A	Concrete Block Wall	Non Suspect ACM	900	SF	0	SF			
1	1	Narrow Hallway outside of Music Classrooms 190 and 191	N/A	Sheetrock Wall	Non Suspect ACM	900	SF	0	SF			
1	1	Narrow Hallway outside of Music Classrooms 190 and 191	N/A	Ceiling Tile 2' x 4'	Non Suspect ACM	600	SF	0	SF			
1	1	Staff Restroom in Narrow Hallway outside of Art Classroom 192 and Auditorium - Left	N/A	Ceramic Tile Floors	Non Suspect ACM	80	SF	0	SF			
1	1	Staff Restroom in Narrow Hallway outside of Art Classroom 192 and Auditorium - Left	N/A	Concrete Block Wall	Non Suspect ACM	160	SF	0	SF			
1	1	Staff Restroom in Narrow Hallway outside of Art Classroom 192 and Auditorium - Left	N/A	Sheetrock Wall	Non Suspect ACM	80	SF	0	SF			
1	1	Staff Restroom in Narrow Hallway outside of Art Classroom 192 and Auditorium - Left	N/A	Ceiling Tile 2' x 4'	Non Suspect ACM	80	SF	0	SF			
1	1	Staff Restroom in Narrow Hallway outside of Art Classroom 192 and Auditorium - Right	N/A	Ceramic Tile Floors	Non Suspect ACM	80	SF	0	SF			
1	1	Staff Restroom in Narrow Hallway outside of Art Classroom 192 and Auditorium - Right	N/A	Concrete Block Wall	Non Suspect ACM	160	SF	0	SF			
1	1	Staff Restroom in Narrow Hallway outside of Art Classroom 192 and Auditorium - Right	N/A	Sheetrock Wall	Non Suspect ACM	80	SF	0	SF			
1	1	Staff Restroom in Narrow Hallway outside of Art Classroom 192 and Auditorium - Right	N/A	Ceiling Tile 2' x 4'	Non Suspect ACM	80	SF	0	SF			
1	1	IT MDF Room 193A	N/A	Concrete Floor	Non Suspect ACM	100	SF	0	SF			
1	1	IT MDF Room 193A	N/A	Concrete Block Wall	Non Suspect ACM	300	SF	0	SF			
1	1	IT MDF Room 193A	N/A	Wood Ceiling	Non Suspect ACM	100	SF	0	SF			
1	1	Storage Room 193C	N/A	Concrete Floor	Non Suspect ACM	100	SF	0	SF			
1	1	Storage Room 193C	N/A	Concrete Block Wall	Non Suspect ACM	900	SF	0	SF			
1	1	Storage Room 193C	N/A	Corrugated Metal Ceiling	Non Suspect ACM	100	SF	0	SF			
1	1	Storage Room 193C	N/A	Metal Duct	Non Suspect ACM	100	SF	0	SF			
1	1	Auditorium 193	N/A	Floor Tile VAT 12" x 12"	NAD	6000	SF	0	SF	Grey		
1	1	Auditorium 193	N/A	Carpet	Non Suspect ACM	1500	SF	0	SF			
1	1	Auditorium 193	N/A	Concrete Block Wall	Non Suspect ACM	22,500	SF	0	SF			
1	1	Auditorium 193	N/A	Corrugated Metal Ceiling	Non Suspect ACM	7500	SF	0	SF			
1	1	Auditorium 193	N/A	Fiberglass Pipe Insulation	Non Suspect ACM	50	LF	0	LF			
1	1	Auditorium Stage	N/A	Wood Floor	Non Suspect ACM	2200	SF	0	SF			
1	1	Auditorium Stage	N/A	Concrete Block Wall	Non Suspect ACM	6600	SF	0	SF			
1	1	Auditorium Stage	N/A	Corrugated Metal Ceiling	Non Suspect ACM	2200	SF	0	SF			
1	1	Auditorium Stage	N/A	Fiberglass Pipe Insulation	Non Suspect ACM	120	LF	0	LF			
1	1	Auditorium Projection Room 193J	N/A	Floor Tile VAT 12" x 12"	NAD	260	SF	0	SF	Grey		
1	1	Auditorium Projection Room 193J	N/A	Concrete Block Wall	Non Suspect ACM	780	SF	0	SF			
1	1	Auditorium Projection Room 193J	N/A	Ceiling Tile 2' x 4'	Non Suspect ACM	260	SF	0	SF			
1	1	Auditorium Storage Closet - Left of Stage	N/A	Concrete Floor	Non Suspect ACM	160	SF	0	SF			
1	1	Auditorium Storage Closet - Left of Stage	N/A	Concrete Block Wall	Non Suspect ACM	960	SF	0	SF			
1	1	Auditorium Storage Closet - Left of Stage	N/A	Corrugated Metal Ceiling	Non Suspect ACM	160	SF	0	SF			
1	1	Auditorium Costume Storage - Left of Stage	N/A	Concrete Floor	Non Suspect ACM	370	SF	0	SF			
1	1	Auditorium Costume Storage - Left of Stage	N/A	Concrete Block Wall	Non Suspect ACM	2200	SF	0	SF			
1	1	Auditorium Costume Storage - Left of Stage	N/A	Corrugated Metal Ceiling	Non Suspect ACM	370	SF	0	SF			

# 8010 New Lincoln - Room by Room Location Log Report.xls

		School District of Philadelphia New Lincoln High School 3201 Ryan Avenue, Philadelphia, PA 19136 ULCS# 8010 Year Built: 2009	AHERA Three-Year Reinspection 2015-2016 Room by Room Location Log Report										Reinspection Date: December 30, 2016		
											Building Inspector: Bernard J Bryson				
											Number: ACC-0125-6-031				
											Management Planner: Megan Vala				
											Number: 740728				
E l e m e n t	F l o o r	On Site Room Name	System Affected	Material Description	Confirmed/Assumed/NAD/ Non Suspect ACM	Amount of Material	SF LF EA	Amount of Damage	SF LF EA	Color required for VAT	Comments/Description/Notes	Attic/ Crawl/ Space Ranking			
1	1	Auditorium Costume Storage - Left of Stage	N/A	Fiberglass Pipe Insulation	Non Suspect ACM	110	LF	0	LF						
1	1	Narrow Hallway between Gymnasium and Auditorium	N/A	Floor Tile VAT 12" x 12"	NAD	1000	SF	0	SF	Grey					
1	1	Narrow Hallway between Gymnasium and Auditorium	N/A	Concrete Block Wall	Non Suspect ACM	1500	SF	0	SF						
1	1	Narrow Hallway between Gymnasium and Auditorium	N/A	Sheetrock Wall	Non Suspect ACM	1500	SF	0	SF						
1	1	Narrow Hallway between Gymnasium and Auditorium	N/A	Ceiling Tile 2' x 4'	Non Suspect ACM	1000	SF	0	SF						
1	1	Storage Room 193F	N/A	Concrete Floor	Non Suspect ACM	500	SF	0	SF						
1	1	Storage Room 193F	N/A	Concrete Block Wall	Non Suspect ACM	3000	SF	0	SF						
1	1	Storage Room 193F	N/A	Corrugated Metal Ceiling	Non Suspect ACM	500	SF	0	SF						
1	1	Storage Room 193F	N/A	Fiberglass Pipe Insulation	Non Suspect ACM	200	LF	0	LF						
1	1	IT MDF Room 193G	N/A	Concrete Floor	Non Suspect ACM	100	SF	0	SF						
1	1	IT MDF Room 193G	N/A	Concrete Block Wall	Non Suspect ACM	900	SF	0	SF						
1	1	IT MDF Room 193G	N/A	Corrugated Metal Ceiling	Non Suspect ACM	100	SF	0	SF						
1	1	Mechanical Room 193H	N/A	Concrete Floor	Non Suspect ACM	150	SF	0	SF						
1	1	Mechanical Room 193H	N/A	Concrete Block Wall	Non Suspect ACM	1000	SF	0	SF						
1	1	Mechanical Room 193H	N/A	Corrugated Metal Ceiling	Non Suspect ACM	150	SF	0	SF						
1	1	Gymnasium 194	N/A	Wood Floor	Non Suspect ACM	20,000	SF	0	SF		Includes 194, 194A and 194B				
1	1	Gymnasium 194	N/A	Concrete Block Wall	Non Suspect ACM	60,000	SF	0	SF						
1	1	Gymnasium 194	N/A	Corrugated Metal Ceiling	Non Suspect ACM	20,000	SF	0	SF						
1	1	Gymnasium 194	N/A	Fireproofing	Non Suspect ACM	500	SF	0	SF						
1	1	Gymnasium 194	N/A	Fiberglass Pipe Insulation	Non Suspect ACM	120	LF	0	LF						
1	1	Storage Room 194C inside Gymnasium 194	N/A	Concrete Floor	Non Suspect ACM	350	SF	0	SF						
1	1	Storage Room 194C inside Gymnasium 194	N/A	Concrete Block Wall	Non Suspect ACM	1050	SF	0	SF						
1	1	Storage Room 194C inside Gymnasium 194	N/A	Ceiling Tile 2' x 4'	Non Suspect ACM	350	SF	0	SF						
1	1	Narrow Hallway between Gymnasium Locker Rooms	N/A	Floor Tile VAT 12" x 12"	NAD	1000	SF	0	SF	Grey					
1	1	Narrow Hallway between Gymnasium Locker Rooms	N/A	Concrete Block Wall	Non Suspect ACM	1500	SF	0	SF						
1	1	Narrow Hallway between Gymnasium Locker Rooms	N/A	Sheetrock Wall	Non Suspect ACM	1500	SF	0	SF						
1	1	Narrow Hallway between Gymnasium Locker Rooms	N/A	Ceiling Tile 2' x 4'	Non Suspect ACM	1000	SF	0	SF						
1	1	Office 195	N/A	Floor Tile VAT 12" x 12"	NAD	250	SF	0	SF	Grey					
1	1	Office 195	N/A	Concrete Block Wall	Non Suspect ACM	750	SF	0	SF						
1	1	Office 195	N/A	Ceiling Tile 2' x 4'	Non Suspect ACM	250	SF	0	SF						
1	1	Electrical Room 195A	N/A	Concrete Floor	Non Suspect ACM	100	SF	0	SF						
1	1	Electrical Room 195A	N/A	Concrete Block Wall	Non Suspect ACM	900	SF	0	SF						
1	1	Electrical Room 195A	N/A	Corrugated Metal Ceiling	Non Suspect ACM	100	SF	0	SF						
1	1	Girl's Locker Room 196A	N/A	Floor Tile VAT 12" x 12"	NAD	1800	SF	0	SF	Grey					
1	1	Girl's Locker Room 196A	N/A	Ceramic Tile Floors	Non Suspect ACM	700	SF	0	SF						
1	1	Girl's Locker Room 196A	N/A	Concrete Block Wall	Non Suspect ACM	7500	SF	0	SF						
1	1	Girl's Locker Room 196A	N/A	Sheetrock Ceiling	Non Suspect ACM	2500	SF	0	SF						
1	1	Boy's Locker Room 196A	N/A	Floor Tile VAT 12" x 12"	NAD	1800	SF	0	SF	Grey					
1	1	Boy's Locker Room 196A	N/A	Ceramic Tile Floors	Non Suspect ACM	700	SF	0	SF						
1	1	Boy's Locker Room 196A	N/A	Concrete Block Wall	Non Suspect ACM	7500	SF	0	SF						
1	1	Boy's Locker Room 196A	N/A	Sheetrock Ceiling	Non Suspect ACM	2500	SF	2	SF		2 SF Water Damaged Sheetrock Ceiling - Appears Dry				
1	1	Gymnasium Training Room Office 196	N/A	Floor Tile VAT 12" x 12"	NAD	900	SF	0	SF	Grey					
1	1	Gymnasium Training Room Office 196	N/A	Concrete Block Wall	Non Suspect ACM	2700	SF	0	SF						
1	1	Gymnasium Training Room Office 196	N/A	Ceiling Tile 2' x 4'	Non Suspect ACM	900	SF	0	SF						
1	1	Storage Closet inside Gymnasium Training Room Office 196	N/A	Floor Tile VAT 12" x 12"	NAD	100	SF	0	SF	Grey					
1	1	Storage Closet inside Gymnasium Training Room Office 196	N/A	Concrete Block Wall	Non Suspect ACM	300	SF	0	SF						
1	1	Storage Closet inside Gymnasium Training Room Office 196	N/A	Ceiling Tile 2' x 4'	Non Suspect ACM	100	SF	0	SF						
1	1	Visitor's Locker Room 197A	N/A	Floor Tile VAT 12" x 12"	NAD	1000	SF	0	SF	Grey					
1	1	Visitor's Locker Room 197A	N/A	Ceramic Tile Floors	Non Suspect ACM	350	SF	0	SF						

# 8010 New Lincoln - Room by Room Location Log Report.xls

		School District of Philadelphia New Lincoln High School 3201 Ryan Avenue, Philadelphia, PA 19136 ULCS# 8010 Year Built: 2009	AHERA Three-Year Reinspection 2015-2016 Room by Room Location Log Report										Reinspection Date: December 30, 2016		
											Building Inspector: Bernard J Bryson				
											Number: ACC-0125-6-031				
											Management Planner: Megan Vala				
											Number: 740728				
E l e m e n t	F l o o r	On Site Room Name	System Affected	Material Description	Confirmed/Assumed/NAD/ Non Suspect ACM	Amount of Material	SF LF EA	Amount of Damage	SF LF EA	Color required for VAT	Comments/Description/Notes	Attic/ Crawl Space Ranking			
1	1	Visitor's Locker Room 197A	N/A	Concrete Block Wall	Non Suspect ACM	4050	SF	0	SF						
1	1	Visitor's Locker Room 197A	N/A	Sheetrock Ceiling	Non Suspect ACM	1350	SF	0	SF						
1	1	Gym Teacher's Office 197	N/A	Floor Tile VAT 12" x 12"	NAD	500	SF	0	SF	Grey					
1	1	Gym Teacher's Office 197	N/A	Concrete Block Wall	Non Suspect ACM	1500	SF	0	SF						
1	1	Gym Teacher's Office 197	N/A	Ceiling Tile 2' x 4'	Non Suspect ACM	500	SF	0	SF						
1	1	Gym Teacher's Office 197 Restroom	N/A	Ceramic Tile Floors	Non Suspect ACM	300	SF	0	SF						
1	1	Gym Teacher's Office 197 Restroom	N/A	Concrete Block Wall	Non Suspect ACM	900	SF	0	SF						
1	1	Gym Teacher's Office 197 Restroom	N/A	Ceiling Tile 2' x 4'	Non Suspect ACM	300	SF	0	SF						
1	1	Gym Teacher's Office 198	N/A	Floor Tile VAT 12" x 12"	NAD	500	SF	0	SF	Grey					
1	1	Gym Teacher's Office 198	N/A	Concrete Block Wall	Non Suspect ACM	1500	SF	0	SF						
1	1	Gym Teacher's Office 198	N/A	Ceiling Tile 2' x 4'	Non Suspect ACM	500	SF	0	SF						
1	1	Gym Teacher's Office 198 Restroom	N/A	Ceramic Tile Floors	Non Suspect ACM	300	SF	0	SF						
1	1	Gym Teacher's Office 198 Restroom	N/A	Concrete Block Wall	Non Suspect ACM	900	SF	0	SF						
1	1	Gym Teacher's Office 198 Restroom	N/A	Ceiling Tile 2' x 4'	Non Suspect ACM	300	SF	0	SF						
1	1	Fitness/Weight Room 199	N/A	Rubber Mat Floor	Non Suspect ACM	5000	SF	0	SF	Black					
1	1	Fitness/Weight Room 199	N/A	Concrete Block Wall	Non Suspect ACM	15,000	SF	0	SF						
1	1	Fitness/Weight Room 199	N/A	Corrugated Metal Ceiling	Non Suspect ACM	5000	SF	0	SF						
1	1	Fitness/Weight Room 199	N/A	Fiberglass Duct Insulation	Non Suspect ACM	750	SF	0	SF						
1	1	Fitness/Weight Room 199	N/A	Fiberglass Pipe Insulation	Non Suspect ACM	200	LF	0	LF						
1	1	Narrow Hallway to Small Gymnasium	N/A	Floor Tile VAT 12" x 12"	NAD	1200	SF	0	SF	Grey					
1	1	Narrow Hallway to Small Gymnasium	N/A	Concrete Block Wall	Non Suspect ACM	3600	SF	0	SF						
1	1	Narrow Hallway to Small Gymnasium	N/A	Ceiling Tile 2' x 4'	Non Suspect ACM	1200	SF	0	SF						
1	1	Small Gymnasium	N/A	Wood Floor	Non Suspect ACM	6500	SF	0	SF		Includes 194, 194A and 194B				
1	1	Small Gymnasium	N/A	Concrete Block Wall	Non Suspect ACM	19,500	SF	0	SF						
1	1	Small Gymnasium	N/A	Corrugated Metal Ceiling	Non Suspect ACM	6500	SF	0	SF						
1	1	Small Gymnasium	N/A	Fiberglass Pipe Insulation	Non Suspect ACM	600	LF	0	LF						
1	1	Storage Room inside Small Gymnasium	N/A	Concrete Floor	Non Suspect ACM	200	SF	0	SF						
1	1	Storage Room inside Small Gymnasium	N/A	Concrete Block Wall	Non Suspect ACM	600	SF	0	SF						
1	1	Storage Room inside Small Gymnasium	N/A	Corrugated Metal Ceiling	Non Suspect ACM	200	SF	0	SF						
1	1	Storage Room inside Small Gymnasium	N/A	Fiberglass Pipe Insulation	Non Suspect ACM	120	LF	0	LF						
2	1	Pre-K Classroom 1	N/A	Floor Tile VAT 12" x 12"	NAD	1200	SF	0	SF	Grey					
2	1	Pre-K Classroom 1	N/A	Concrete Block Wall	Non Suspect ACM	1800	SF	0	SF						
2	1	Pre-K Classroom 1	N/A	Sheetrock Wall	Non Suspect ACM	1800	SF	0	SF						
2	1	Pre-K Classroom 1	N/A	Ceiling Tile 2' x 4'	Non Suspect ACM	1200	SF	0	SF						
2	1	Pre-K Classroom 1 Restroom	N/A	Ceramic Tile Floors	Non Suspect ACM	100	SF	0	SF						
2	1	Pre-K Classroom 1 Restroom	N/A	Sheetrock Wall	Non Suspect ACM	300	SF	0	SF						
2	1	Pre-K Classroom 1 Restroom	N/A	Ceiling Tile 2' x 4'	Non Suspect ACM	100	SF	0	SF						
2	1	Office 2 in Pre-K Wing	N/A	Floor Tile VAT 12" x 12"	NAD	80	SF	0	SF	Grey					
2	1	Office 2 in Pre-K Wing	N/A	Sheetrock Wall	Non Suspect ACM	240	SF	0	SF						
2	1	Office 2 in Pre-K Wing	N/A	Ceiling Tile 2' x 4'	Non Suspect ACM	80	SF	0	SF						
2	1	Storage Room 3 in Pre-K Wing	N/A	Concrete Floor	Non Suspect ACM	250	SF	0	SF						
2	1	Storage Room 3 in Pre-K Wing	N/A	Concrete Block Wall	Non Suspect ACM	375	SF	0	SF						
2	1	Storage Room 3 in Pre-K Wing	N/A	Sheetrock Wall	Non Suspect ACM	375	SF	0	SF						
2	1	Storage Room 3 in Pre-K Wing	N/A	Ceiling Tile 2' x 4'	Non Suspect ACM	250	SF	0	SF						
2	1	Storage Room 3 in Pre-K Wing	N/A	Fiberglass Pipe Insulation	Non Suspect ACM	100	LF	0	LF						
2	1	Electrical Room 4 in Pre-K Wing	N/A	x	x	x	x	x	x	x	No Access				
2	1	Kitchen 5 in Pre-K Wing	N/A	Floor Tile VAT 12" x 12"	NAD	350	SF	0	SF	Grey					
2	1	Kitchen 5 in Pre-K Wing	N/A	Concrete Block Wall	Non Suspect ACM	525	SF	0	SF						
2	1	Kitchen 5 in Pre-K Wing	N/A	Sheetrock Wall	Non Suspect ACM	525	SF	0	SF						
2	1	Kitchen 5 in Pre-K Wing	N/A	Ceiling Tile 2' x 4'	Non Suspect ACM	350	SF	0	SF						
2	1	Pre-K Classroom 6	N/A	Floor Tile VAT 12" x 12"	NAD	700	SF	0	SF	Grev					

# 8010 New Lincoln - Room by Room Location Log Report.xls

		School District of Philadelphia New Lincoln High School 3201 Ryan Avenue, Philadelphia, PA 19136 ULCS# 8010 Year Built: 2009	AHERA Three-Year Reinspection 2015-2016 Room by Room Location Log Report								Reinspection Date: December 30, 2016		
											Building Inspector: Bernard J Bryson		
											Number: ACC-0125-6-031		
											Management Planner: Megan Vala		
											Number: 740728		
<i>E l e m e n t</i>	<i>F l o o r</i>	<i>On Site Room Name</i>	<i>System Affected</i>	<i>Material Description</i>	<i>Confirmed/Assumed/NAD/ Non Suspect ACM</i>	<i>Amount of Material</i>	<i>SF LF EA</i>	<i>Amount of Damage</i>	<i>SF LF EA</i>	<i>Color required for VAT</i>	<i>Comments/Description/Notes</i>	<i>Attic/ Crawl Space Ranking</i>	
2	1	Pre-K Classroom 6	N/A	Sheetrock Wall	Non Suspect ACM	2100	SF	0	SF				
2	1	Pre-K Classroom 6	N/A	Ceiling Tile 2' x 4'	Non Suspect ACM	700	SF	0	SF				
2	1	Mechanical Room 7 in Pre-K Wing	N/A	x	x	x	x	x	x	x	No Access		
2	1	Pre-K Classroom 8	N/A	Floor Tile VAT 12" x 12"	NAD	1200	SF	0	SF	Grey			
2	1	Pre-K Classroom 8	N/A	Concrete Block Wall	Non Suspect ACM	1800	SF	0	SF				
2	1	Pre-K Classroom 8	N/A	Sheetrock Wall	Non Suspect ACM	1800	SF	0	SF				
2	1	Pre-K Classroom 8	N/A	Ceiling Tile 2' x 4'	Non Suspect ACM	1200	SF	0	SF				
2	1	Pre-K Classroom 8 Restroom	N/A	Ceramic Tile Floors	Non Suspect ACM	100	SF	0	SF				
2	1	Pre-K Classroom 8 Restroom	N/A	Sheetrock Wall	Non Suspect ACM	300	SF	0	SF				
2	1	Pre-K Classroom 8 Restroom	N/A	Ceiling Tile 2' x 4'	Non Suspect ACM	100	SF	0	SF				
2	1	Hallway in Pre-K Wing	N/A	Floor Tile VAT 12" x 12"	NAD	400	SF	0	SF	Grey			
2	1	Hallway in Pre-K Wing	N/A	Sheetrock Wall	Non Suspect ACM	1200	SF	0	SF				
2	1	Hallway in Pre-K Wing	N/A	Ceiling Tile 2' x 4'	Non Suspect ACM	400	SF	0	SF				
1	2	Stairwell next to Classroom 200	N/A	Concrete Floor	Non Suspect ACM	600	SF	0	SF				
1	2	Stairwell next to Classroom 200	N/A	Concrete Block Wall	Non Suspect ACM	1800	SF	0	SF				
1	2	Stairwell next to Classroom 200	N/A	Corrugated Metal Ceiling	Non Suspect ACM	600	SF	0	SF				
1	2	Stairwell next to Classroom 200	N/A	Fireproofing	Non Suspect ACM	60	SF	0	SF				
1	2	Stairwell next to Classroom 200	N/A	Fiberglass Pipe Insulation	Non Suspect ACM	15	LF	0	LF				
1	2	Stairwell next to Classroom 208	N/A	Concrete Floor	Non Suspect ACM	600	SF	0	SF				
1	2	Stairwell next to Classroom 208	N/A	Concrete Block Wall	Non Suspect ACM	1800	SF	0	SF				
1	2	Stairwell next to Classroom 208	N/A	Corrugated Metal Ceiling	Non Suspect ACM	600	SF	0	SF				
1	2	Stairwell next to Classroom 208	N/A	Fireproofing	Non Suspect ACM	150	SF	0	SF				
1	2	Stairwell next to Classroom 208	N/A	Fiberglass Pipe Insulation	Non Suspect ACM	5	LF	0	LF				
1	2	Stairwell next to Classroom 222	N/A	Concrete Floor	Non Suspect ACM	600	SF	0	SF				
1	2	Stairwell next to Classroom 222	N/A	Concrete Block Wall	Non Suspect ACM	1800	SF	0	SF				
1	2	Stairwell next to Classroom 222	N/A	Corrugated Metal Ceiling	Non Suspect ACM	600	SF	0	SF				
1	2	Stairwell next to Classroom 228	N/A	Concrete Floor	Non Suspect ACM	600	SF	0	SF				
1	2	Stairwell next to Classroom 228	N/A	Concrete Block Wall	Non Suspect ACM	1800	SF	0	SF				
1	2	Stairwell next to Classroom 228	N/A	Corrugated Metal Ceiling	Non Suspect ACM	600	SF	0	SF				
1	2	Stairwell next to Classroom 228	N/A	Fireproofing	Non Suspect ACM	150	SF	0	SF				
1	2	Stairwell next to Classroom 228	N/A	Fiberglass Pipe Insulation	Non Suspect ACM	5	LF	0	LF				
1	2	Vestibule outside of Classrooms 228 and 229	N/A	Floor Tile VAT 12" x 12"	NAD	350	SF	0	SF	Grey			
1	2	Vestibule outside of Classrooms 228 and 229	N/A	Concrete Block Wall	Non Suspect ACM	750	SF	0	SF				
1	2	Vestibule outside of Classrooms 228 and 229	N/A	Glass Wall	Non Suspect ACM	250	SF	0	SF				
1	2	Vestibule outside of Classrooms 228 and 229	N/A	Corrugated Metal Ceiling	Non Suspect ACM	350	SF	0	SF				
1	2	Vestibule outside of Classrooms 228 and 229	N/A	Fireproofing	Non Suspect ACM	30	SF	0	SF				
1	2	Vestibule outside of Classrooms 200 and 201	N/A	Floor Tile VAT 12" x 12"	NAD	350	SF	0	SF	Grey			
1	2	Vestibule outside of Classrooms 200 and 201	N/A	Concrete Block Wall	Non Suspect ACM	750	SF	0	SF				
1	2	Vestibule outside of Classrooms 200 and 201	N/A	Glass Wall	Non Suspect ACM	250	SF	0	SF				
1	2	Vestibule outside of Classrooms 200 and 201	N/A	Corrugated Metal Ceiling	Non Suspect ACM	350	SF	0	SF				
1	2	Vestibule outside of Classrooms 200 and 201	N/A	Fireproofing	Non Suspect ACM	30	SF	0	SF				
1	2	Hallway outside Classrooms 221 and 229	N/A	Floor Tile VAT 12" x 12"	NAD	2000	SF	0	SF	Grey			
1	2	Hallway outside Classrooms 221 and 229	N/A	Floor Tile VAT 12" x 12"	NAD	1000	SF	0	SF	Yellow			
1	2	Hallway outside Classrooms 221 and 229	N/A	Concrete Block Wall	Non Suspect ACM	4500	SF	0	SF				
1	2	Hallway outside Classrooms 221 and 229	N/A	Sheetrock Wall	Non Suspect ACM	4500	SF	0	SF				
1	2	Hallway outside Classrooms 221 and 229	N/A	Ceiling Tile 2' x 4'	Non Suspect ACM	3000	SF	0	SF				
1	2	Hallway outside Classrooms 207 and 220	N/A	Floor Tile VAT 12" x 12"	NAD	2000	SF	0	SF	Grey			
1	2	Hallway outside Classrooms 207 and 220	N/A	Floor Tile VAT 12" x 12"	NAD	1000	SF	0	SF	Yellow			
1	2	Hallway outside Classrooms 207 and 220	N/A	Concrete Block Wall	Non Suspect ACM	4500	SF	0	SF				
1	2	Hallway outside Classrooms 207 and 220	N/A	Sheetrock Wall	Non Suspect ACM	4500	SF	0	SF				
1	2	Hallway outside Classrooms 207 and 220	N/A	Ceiling Tile 2' x 4'	Non Suspect ACM	3000	SF	0	SF				
1	2	Hallway outside Classrooms 200 and 205	N/A	Floor Tile VAT 12" x 12"	NAD	2000	SF	0	SF	Grey			

# 8010 New Lincoln - Room by Room Location Log Report.xls

		School District of Philadelphia New Lincoln High School 3201 Ryan Avenue, Philadelphia, PA 19136 ULCS# 8010 Year Built: 2009	AHERA Three-Year Reinspection 2015-2016 Room by Room Location Log Report								Reinspection Date: December 30, 2016		
											Building Inspector: Bernard J Bryson		
											Number: ACC-0125-6-031		
											Management Planner: Megan Vala		
											Number: 740728		
<i>E l e m e n t</i>	<i>F l o o r</i>	<i>On Site Room Name</i>	<i>System Affected</i>	<i>Material Description</i>	<i>Confirmed/Assumed/NAD/ Non Suspect ACM</i>	<i>Amount of Material</i>	<i>SF LF EA</i>	<i>Amount of Damage</i>	<i>SF LF EA</i>	<i>Color required for VAT</i>	<i>Comments/Description/Notes</i>	<i>Attic/ Crawl Space Ranking</i>	
1	2	Hallway outside Classrooms 200 and 205	N/A	Floor Tile VAT 12" x 12"	NAD	1000	SF	0	SF	Yellow			
1	2	Hallway outside Classrooms 200 and 205	N/A	Concrete Block Wall	Non Suspect ACM	4500	SF	0	SF				
1	2	Hallway outside Classrooms 200 and 205	N/A	Sheetrock Wall	Non Suspect ACM	4500	SF	0	SF				
1	2	Hallway outside Classrooms 200 and 205	N/A	Ceiling Tile 2' x 4'	Non Suspect ACM	3000	SF	0	SF				
1	2	Classroom 200	N/A	Floor Tile VAT 12" x 12"	NAD	1200	SF	0	SF	Grey			
1	2	Classroom 200	N/A	Concrete Block Wall	Non Suspect ACM	1800	SF	0	SF				
1	2	Classroom 200	N/A	Sheetrock Wall	Non Suspect ACM	1800	SF	0	SF				
1	2	Classroom 200	N/A	Ceiling Tile 2' x 4'	Non Suspect ACM	1200	SF	0	SF				
1	2	Science Classroom 201	N/A	Floor Tile VAT 12" x 12"	NAD	1500	SF	0	SF	Grey			
1	2	Science Classroom 201	N/A	Concrete Block Wall	Non Suspect ACM	2250	SF	0	SF				
1	2	Science Classroom 201	N/A	Sheetrock Wall	Non Suspect ACM	2250	SF	0	SF				
1	2	Science Classroom 201	N/A	Ceiling Tile 2' x 4'	Non Suspect ACM	1500	SF	5	EA		5 Stained ACTs		
1	2	Science Classroom 201	N/A	Lab Table Tops/Sinks	Non Suspect ACM	200	SF	0	SF	Black			
1	2	Science Lab Prep Room 201A	N/A	Floor Tile VAT 12" x 12"	NAD	350	SF	0	SF	Grey			
1	2	Science Lab Prep Room 201A	N/A	Concrete Block Wall	Non Suspect ACM	800	SF	0	SF				
1	2	Science Lab Prep Room 201A	N/A	Sheetrock Wall	Non Suspect ACM	250	SF	0	SF				
1	2	Science Lab Prep Room 201A	N/A	Ceiling Tile 2' x 4'	Non Suspect ACM	350	SF	0	SF				
1	2	Science Lab Prep Room 201A	N/A	Lab Table Tops/Sinks	Non Suspect ACM	50	SF	0	SF	Black			
1	2	Science Classroom 203	N/A	Floor Tile VAT 12" x 12"	NAD	1500	SF	0	SF	Grey			
1	2	Science Classroom 203	N/A	Concrete Block Wall	Non Suspect ACM	2250	SF	0	SF				
1	2	Science Classroom 203	N/A	Sheetrock Wall	Non Suspect ACM	2250	SF	0	SF				
1	2	Science Classroom 203	N/A	Ceiling Tile 2' x 4'	Non Suspect ACM	1500	SF	0	SF				
1	2	Science Classroom 203	N/A	Lab Table Tops/Sinks	Non Suspect ACM	200	SF	0	SF	Black			
1	2	Nurse Training Classroom 202	N/A	Floor Tile VAT 12" x 12"	NAD	2000	SF	0	SF	Grey			
1	2	Nurse Training Classroom 202	N/A	Concrete Block Wall	Non Suspect ACM	3000	SF	0	SF				
1	2	Nurse Training Classroom 202	N/A	Sheetrock Wall	Non Suspect ACM	3000	SF	0	SF				
1	2	Nurse Training Classroom 202	N/A	Ceiling Tile 2' x 4'	Non Suspect ACM	2000	SF	0	SF				
1	2	Nurse Training Classroom 202	N/A	Lab Table Tops/Sinks	Non Suspect ACM	100	SF	0	SF	Black			
1	2	Storage Room inside Nurse Training Classroom 202	N/A	Concrete Floor	Non Suspect ACM	150	SF	0	SF				
1	2	Storage Room inside Nurse Training Classroom 202	N/A	Concrete Block Wall	Non Suspect ACM	225	SF	0	SF				
1	2	Storage Room inside Nurse Training Classroom 202	N/A	Sheetrock Wall	Non Suspect ACM	225	SF	0	SF				
1	2	Storage Room inside Nurse Training Classroom 202	N/A	Ceiling Tile 2' x 4'	Non Suspect ACM	150	SF	0	SF				
1	2	Office between Classrooms 200 and 202	N/A	Floor Tile VAT 12" x 12"	NAD	150	SF	0	SF	Grey			
1	2	Office between Classrooms 200 and 202	N/A	Concrete Block Wall	Non Suspect ACM	225	SF	0	SF				
1	2	Office between Classrooms 200 and 202	N/A	Sheetrock Wall	Non Suspect ACM	225	SF	0	SF				
1	2	Office between Classrooms 200 and 202	N/A	Ceiling Tile 2' x 4'	Non Suspect ACM	150	SF	0	SF				
1	2	Staff Restroom outside of Classroom 202 - Left	N/A	Ceramic Tile Floors	Non Suspect ACM	80	SF	0	SF				
1	2	Staff Restroom outside of Classroom 202 - Left	N/A	Concrete Block Wall	Non Suspect ACM	160	SF	0	SF				
1	2	Staff Restroom outside of Classroom 202 - Left	N/A	Sheetrock Wall	Non Suspect ACM	80	SF	0	SF				
1	2	Staff Restroom outside of Classroom 202 - Left	N/A	Ceiling Tile 2' x 4'	Non Suspect ACM	80	SF	0	SF				
1	2	Staff Restroom outside of Classroom 202 - Right	N/A	Ceramic Tile Floors	Non Suspect ACM	80	SF	0	SF				
1	2	Staff Restroom outside of Classroom 202 - Right	N/A	Concrete Block Wall	Non Suspect ACM	160	SF	0	SF				
1	2	Staff Restroom outside of Classroom 202 - Right	N/A	Sheetrock Wall	Non Suspect ACM	80	SF	0	SF				
1	2	Staff Restroom outside of Classroom 202 - Right	N/A	Ceiling Tile 2' x 4'	Non Suspect ACM	80	SF	0	SF				
1	2	Classroom 204	N/A	Floor Tile VAT 12" x 12"	NAD	1000	SF	0	SF	Grey			
1	2	Classroom 204	N/A	Concrete Block Wall	Non Suspect ACM	1500	SF	0	SF				
1	2	Classroom 204	N/A	Sheetrock Wall	Non Suspect ACM	1500	SF	0	SF				
1	2	Classroom 204	N/A	Ceiling Tile 2' x 4'	Non Suspect ACM	1000	SF	0	SF				
1	2	Office 206	N/A	Floor Tile VAT 12" x 12"	NAD	150	SF	0	SF	Grey			
1	2	Office 206	N/A	Carpet	Non Suspect ACM	400	SF	0	SF				
1	2	Office 206	N/A	Sheetrock Wall	Non Suspect ACM	1800	SF	0	SF				
1	2	Office 206	N/A	Ceiling Tile 2' x 4'	Non Suspect ACM	650	SF	0	SF				

# 8010 New Lincoln - Room by Room Location Log Report.xls

		School District of Philadelphia New Lincoln High School 3201 Ryan Avenue, Philadelphia, PA 19136 ULCS# 8010 Year Built: 2009	AHERA Three-Year Reinspection 2015-2016 Room by Room Location Log Report								Reinspection Date: December 30, 2016	
											Building Inspector: Bernard J Bryson	
											Number: ACC-0125-6-031	
											Management Planner: Megan Vala	
											Number: 740728	
E l e m e n t	F l o o r	On Site Room Name	System Affected	Material Description	Confirmed/Assumed/NAD/ Non Suspect ACM	Amount of Material	SF LF EA	Amount of Damage	SF LF EA	Color required for VAT	Comments/Description/Notes	Attic/ Crawl Space Ranking
1	2	Office 206 Restroom	N/A	Ceramic Tile Floors	Non Suspect ACM	80	SF	0	SF			
1	2	Office 206 Restroom	N/A	Sheetrock Wall	Non Suspect ACM	240	SF	0	SF			
1	2	Office 206 Restroom	N/A	Ceiling Tile 2' x 4'	Non Suspect ACM	80	SF	0	SF			
1	2	Classroom 205	N/A	Floor Tile VAT 12" x 12"	NAD	1200	SF	0	SF	Grey		
1	2	Classroom 205	N/A	Concrete Block Wall	Non Suspect ACM	1800	SF	0	SF			
1	2	Classroom 205	N/A	Sheetrock Wall	Non Suspect ACM	1800	SF	0	SF			
1	2	Classroom 205	N/A	Ceiling Tile 2' x 4'	Non Suspect ACM	1200	SF	0	SF			
1	2	Classroom 207	N/A	Floor Tile VAT 12" x 12"	NAD	900	SF	0	SF	Grey		
1	2	Classroom 207	N/A	Concrete Block Wall	Non Suspect ACM	1350	SF	0	SF			
1	2	Classroom 207	N/A	Sheetrock Wall	Non Suspect ACM	1350	SF	0	SF			
1	2	Classroom 207	N/A	Ceiling Tile 2' x 4'	Non Suspect ACM	900	SF	0	SF			
1	2	Classroom 208	N/A	Floor Tile VAT 12" x 12"	NAD	1200	SF	0	SF	Grey		
1	2	Classroom 208	N/A	Concrete Block Wall	Non Suspect ACM	1800	SF	0	SF			
1	2	Classroom 208	N/A	Sheetrock Wall	Non Suspect ACM	1800	SF	0	SF			
1	2	Classroom 208	N/A	Ceiling Tile 2' x 4'	Non Suspect ACM	1200	SF	0	SF			
1	2	Classroom 209	N/A	Floor Tile VAT 12" x 12"	NAD	900	SF	0	SF	Grey		
1	2	Classroom 209	N/A	Concrete Block Wall	Non Suspect ACM	1350	SF	0	SF			
1	2	Classroom 209	N/A	Sheetrock Wall	Non Suspect ACM	1350	SF	0	SF			
1	2	Classroom 209	N/A	Ceiling Tile 2' x 4'	Non Suspect ACM	900	SF	0	SF			
1	2	Classroom 210	N/A	Floor Tile VAT 12" x 12"	NAD	900	SF	0	SF	Grey		
1	2	Classroom 210	N/A	Concrete Block Wall	Non Suspect ACM	1350	SF	0	SF			
1	2	Classroom 210	N/A	Sheetrock Wall	Non Suspect ACM	1350	SF	0	SF			
1	2	Classroom 210	N/A	Ceiling Tile 2' x 4'	Non Suspect ACM	900	SF	0	SF			
1	2	Classroom 211	N/A	Floor Tile VAT 12" x 12"	NAD	900	SF	0	SF	Grey		
1	2	Classroom 211	N/A	Concrete Block Wall	Non Suspect ACM	1350	SF	0	SF			
1	2	Classroom 211	N/A	Sheetrock Wall	Non Suspect ACM	1350	SF	0	SF			
1	2	Classroom 211	N/A	Ceiling Tile 2' x 4'	Non Suspect ACM	900	SF	0	SF			
1	2	Classroom 212	N/A	Floor Tile VAT 12" x 12"	NAD	900	SF	0	SF	Grey		
1	2	Classroom 212	N/A	Concrete Block Wall	Non Suspect ACM	1350	SF	0	SF			
1	2	Classroom 212	N/A	Sheetrock Wall	Non Suspect ACM	1350	SF	0	SF			
1	2	Classroom 212	N/A	Ceiling Tile 2' x 4'	Non Suspect ACM	900	SF	0	SF			
1	2	Classroom 213	N/A	Floor Tile VAT 12" x 12"	NAD	900	SF	0	SF	Grey		
1	2	Classroom 213	N/A	Concrete Block Wall	Non Suspect ACM	1350	SF	0	SF			
1	2	Classroom 213	N/A	Sheetrock Wall	Non Suspect ACM	1350	SF	0	SF			
1	2	Classroom 213	N/A	Ceiling Tile 2' x 4'	Non Suspect ACM	900	SF	0	SF			
1	2	Classroom 214	N/A	Floor Tile VAT 12" x 12"	NAD	900	SF	0	SF	Grey		
1	2	Classroom 214	N/A	Concrete Block Wall	Non Suspect ACM	1350	SF	0	SF			
1	2	Classroom 214	N/A	Sheetrock Wall	Non Suspect ACM	1350	SF	0	SF			
1	2	Classroom 214	N/A	Ceiling Tile 2' x 4'	Non Suspect ACM	900	SF	0	SF			
1	2	Classroom 216	N/A	Floor Tile VAT 12" x 12"	NAD	900	SF	0	SF	Grey		
1	2	Classroom 216	N/A	Concrete Block Wall	Non Suspect ACM	1350	SF	0	SF			
1	2	Classroom 216	N/A	Sheetrock Wall	Non Suspect ACM	1350	SF	0	SF			
1	2	Classroom 216	N/A	Ceiling Tile 2' x 4'	Non Suspect ACM	900	SF	0	SF			
1	2	Classroom 218	N/A	Floor Tile VAT 12" x 12"	NAD	900	SF	0	SF	Grey		
1	2	Classroom 218	N/A	Concrete Block Wall	Non Suspect ACM	1350	SF	0	SF			
1	2	Classroom 218	N/A	Sheetrock Wall	Non Suspect ACM	1350	SF	0	SF			
1	2	Classroom 218	N/A	Ceiling Tile 2' x 4'	Non Suspect ACM	900	SF	0	SF			
1	2	Computer Lab 220	N/A	Floor Tile VAT 12" x 12"	NAD	1500	SF	0	SF	Grey		
1	2	Computer Lab 220	N/A	Concrete Block Wall	Non Suspect ACM	2250	SF	0	SF			
1	2	Computer Lab 220	N/A	Sheetrock Wall	Non Suspect ACM	2250	SF	0	SF			
1	2	Computer Lab 220	N/A	Ceiling Tile 2' x 4'	Non Suspect ACM	1500	SF	0	SF			
1	2	Classroom 221	N/A	Floor Tile VAT 12" x 12"	NAD	900	SF	0	SF	Grey		

# 8010 New Lincoln - Room by Room Location Log Report.xls

		School District of Philadelphia New Lincoln High School 3201 Ryan Avenue, Philadelphia, PA 19136 ULCS# 8010 Year Built: 2009	AHERA Three-Year Reinspection 2015-2016 Room by Room Location Log Report								Reinspection Date: December 30, 2016		
											Building Inspector: Bernard J Bryson		
											Number: ACC-0125-6-031		
											Management Planner: Megan Vala		
											Number: 740728		
<i>E l e m e n t</i>	<i>F l o o r</i>	<i>On Site Room Name</i>	<i>System Affected</i>	<i>Material Description</i>	<i>Confirmed/Assumed/NAD/ Non Suspect ACM</i>	<i>Amount of Material</i>	<i>SF LF EA</i>	<i>Amount of Damage</i>	<i>SF LF EA</i>	<i>Color required for VAT</i>	<i>Comments/Description/Notes</i>	<i>Attic/ Crawl Space Ranking</i>	
1	2	Classroom 221	N/A	Concrete Block Wall	Non Suspect ACM	1350	SF	0	SF				
1	2	Classroom 221	N/A	Sheetrock Wall	Non Suspect ACM	1350	SF	0	SF				
1	2	Classroom 221	N/A	Ceiling Tile 2' x 4'	Non Suspect ACM	900	SF	0	SF				
1	2	Classroom 222	N/A	Floor Tile VAT 12" x 12"	NAD	900	SF	0	SF	Grey			
1	2	Classroom 222	N/A	Concrete Block Wall	Non Suspect ACM	1350	SF	0	SF				
1	2	Classroom 222	N/A	Sheetrock Wall	Non Suspect ACM	1350	SF	0	SF				
1	2	Classroom 222	N/A	Ceiling Tile 2' x 4'	Non Suspect ACM	900	SF	0	SF				
1	2	Classroom 223	N/A	Floor Tile VAT 12" x 12"	NAD	900	SF	0	SF	Grey			
1	2	Classroom 223	N/A	Concrete Block Wall	Non Suspect ACM	1350	SF	0	SF				
1	2	Classroom 223	N/A	Sheetrock Wall	Non Suspect ACM	1350	SF	0	SF				
1	2	Classroom 223	N/A	Ceiling Tile 2' x 4'	Non Suspect ACM	900	SF	0	SF				
1	2	Computer Lab 224	N/A	Floor Tile VAT 12" x 12"	NAD	1500	SF	0	SF	Grey			
1	2	Computer Lab 224	N/A	Concrete Block Wall	Non Suspect ACM	2250	SF	0	SF				
1	2	Computer Lab 224	N/A	Sheetrock Wall	Non Suspect ACM	2250	SF	0	SF				
1	2	Computer Lab 224	N/A	Ceiling Tile 2' x 4'	Non Suspect ACM	1500	SF	0	SF				
1	2	Office 224A outside of Computer Lab 224	N/A	Floor Tile VAT 12" x 12"	NAD	100	SF	0	SF	Grey			
1	2	Office 224A outside of Computer Lab 224	N/A	Sheetrock Wall	Non Suspect ACM	300	SF	0	SF				
1	2	Office 224A outside of Computer Lab 224	N/A	Ceiling Tile 2' x 4'	Non Suspect ACM	100	SF	0	SF				
1	2	Storage Room 224B inside Computer Lab 224	N/A	Concrete Floor	Non Suspect ACM	150	SF	0	SF				
1	2	Storage Room 224B inside Computer Lab 224	N/A	Concrete Block Wall	Non Suspect ACM	225	SF	0	SF				
1	2	Storage Room 224B inside Computer Lab 224	N/A	Sheetrock Wall	Non Suspect ACM	225	SF	0	SF				
1	2	Storage Room 224B inside Computer Lab 224	N/A	Ceiling Tile 2' x 4'	Non Suspect ACM	150	SF	0	SF				
1	2	Computer Lab 226	N/A	Floor Tile VAT 12" x 12"	NAD	1500	SF	0	SF	Grey			
1	2	Computer Lab 226	N/A	Concrete Block Wall	Non Suspect ACM	2250	SF	0	SF				
1	2	Computer Lab 226	N/A	Sheetrock Wall	Non Suspect ACM	2250	SF	0	SF				
1	2	Computer Lab 226	N/A	Ceiling Tile 2' x 4'	Non Suspect ACM	1500	SF	0	SF				
1	2	Office 226A outside of Computer Lab 226	N/A	Floor Tile VAT 12" x 12"	NAD	100	SF	0	SF	Grey			
1	2	Office 226A outside of Computer Lab 226	N/A	Sheetrock Wall	Non Suspect ACM	300	SF	0	SF				
1	2	Office 226A outside of Computer Lab 226	N/A	Ceiling Tile 2' x 4'	Non Suspect ACM	100	SF	0	SF				
1	2	Storage Room 226B inside Computer Lab 226	N/A	Concrete Floor	Non Suspect ACM	150	SF	0	SF				
1	2	Storage Room 226B inside Computer Lab 226	N/A	Concrete Block Wall	Non Suspect ACM	225	SF	0	SF				
1	2	Storage Room 226B inside Computer Lab 226	N/A	Sheetrock Wall	Non Suspect ACM	225	SF	0	SF				
1	2	Storage Room 226B inside Computer Lab 226	N/A	Ceiling Tile 2' x 4'	Non Suspect ACM	150	SF	0	SF				
1	2	Classroom 225	N/A	Floor Tile VAT 12" x 12"	NAD	900	SF	0	SF	Grey			
1	2	Classroom 225	N/A	Concrete Block Wall	Non Suspect ACM	1350	SF	0	SF				
1	2	Classroom 225	N/A	Sheetrock Wall	Non Suspect ACM	1350	SF	0	SF				
1	2	Classroom 225	N/A	Ceiling Tile 2' x 4'	Non Suspect ACM	900	SF	0	SF				
1	2	Classroom 227	N/A	Floor Tile VAT 12" x 12"	NAD	900	SF	0	SF	Grey			
1	2	Classroom 227	N/A	Concrete Block Wall	Non Suspect ACM	1350	SF	0	SF				
1	2	Classroom 227	N/A	Sheetrock Wall	Non Suspect ACM	1350	SF	0	SF				
1	2	Classroom 227	N/A	Ceiling Tile 2' x 4'	Non Suspect ACM	900	SF	0	SF				
1	2	Classroom 228	N/A	Floor Tile VAT 12" x 12"	NAD	900	SF	0	SF	Grey			
1	2	Classroom 228	N/A	Concrete Block Wall	Non Suspect ACM	1350	SF	0	SF				
1	2	Classroom 228	N/A	Sheetrock Wall	Non Suspect ACM	1350	SF	0	SF				
1	2	Classroom 228	N/A	Ceiling Tile 2' x 4'	Non Suspect ACM	900	SF	0	SF				
1	2	Classroom 229	N/A	Floor Tile VAT 12" x 12"	NAD	900	SF	0	SF	Grey			
1	2	Classroom 229	N/A	Concrete Block Wall	Non Suspect ACM	1350	SF	0	SF				
1	2	Classroom 229	N/A	Sheetrock Wall	Non Suspect ACM	1350	SF	0	SF				
1	2	Classroom 229	N/A	Ceiling Tile 2' x 4'	Non Suspect ACM	900	SF	0	SF				
1	2	Electrical Room 200A	N/A	Concrete Floor	Non Suspect ACM	100	SF	0	SF				
1	2	Electrical Room 200A	N/A	Concrete Block Wall	Non Suspect ACM	300	SF	0	SF				
1	2	Electrical Room 200A	N/A	Corrugated Metal Ceiling	Non Suspect ACM	100	SF	0	SF				

# 8010 New Lincoln - Room by Room Location Log Report.xls

		School District of Philadelphia New Lincoln High School 3201 Ryan Avenue, Philadelphia, PA 19136 ULCS# 8010 Year Built: 2009	AHERA Three-Year Reinspection 2015-2016 Room by Room Location Log Report								Reinspection Date: December 30, 2016		
											Building Inspector: Bernard J Bryson		
											Number: ACC-0125-6-031		
											Management Planner: Megan Vala		
											Number: 740728		
E l e m e n t	F l o o r	On Site Room Name	System Affected	Material Description	Confirmed/Assumed/NAD/ Non Suspect ACM	Amount of Material	SF LF EA	Amount of Damage	SF LF EA	Color required for VAT	Comments/Description/Notes	Attic/ Crawl Space Ranking	
1	2	Electrical Room 200A	N/A	Fireproofing	Non Suspect ACM	25	SF	0	SF				
1	2	Hallway Storage Room 205A	N/A	Concrete Floor	Non Suspect ACM	100	SF	0	SF				
1	2	Hallway Storage Room 205A	N/A	Concrete Block Wall	Non Suspect ACM	300	SF	0	SF				
1	2	Hallway Storage Room 205A	N/A	Corrugated Metal Ceiling	Non Suspect ACM	100	SF	0	SF				
1	2	Hallway Storage Room 205B	N/A	Concrete Floor	Non Suspect ACM	100	SF	0	SF				
1	2	Hallway Storage Room 205B	N/A	Concrete Block Wall	Non Suspect ACM	300	SF	0	SF				
1	2	Hallway Storage Room 205B	N/A	Corrugated Metal Ceiling	Non Suspect ACM	100	SF	0	SF				
1	2	Custodial Closet 207A	N/A	Concrete Floor	Non Suspect ACM	20	SF	0	SF				
1	2	Custodial Closet 207A	N/A	Concrete Block Wall	Non Suspect ACM	80	SF	0	SF				
1	2	Custodial Closet 207A	N/A	Corrugated Metal Ceiling	Non Suspect ACM	20	SF	0	SF				
1	2	Hallway Storage Closet 207B	N/A	Concrete Floor	Non Suspect ACM	20	SF	0	SF				
1	2	Hallway Storage Closet 207B	N/A	Concrete Block Wall	Non Suspect ACM	80	SF	0	SF				
1	2	Hallway Storage Closet 207B	N/A	Corrugated Metal Ceiling	Non Suspect ACM	20	SF	0	SF				
1	2	Hallway Storage Closet 207B	N/A	Fiberglass Duct Insulation	Non Suspect ACM	25	SF	0	SF				
1	2	Hallway Storage Closet 207C	N/A	Concrete Floor	Non Suspect ACM	20	SF	0	SF				
1	2	Hallway Storage Closet 207C	N/A	Concrete Block Wall	Non Suspect ACM	80	SF	0	SF				
1	2	Hallway Storage Closet 207C	N/A	Corrugated Metal Ceiling	Non Suspect ACM	20	SF	0	SF				
1	2	Hallway Storage Closet 207C	N/A	Fiberglass Duct Insulation	Non Suspect ACM	25	SF	0	SF				
1	2	Hallway Storage Closet 207C	N/A	Fiberglass Pipe Insulation	Non Suspect ACM	30	LF	0	LF				
1	2	Boy's Restroom across from Classroom 208	N/A	Ceramic Tile Floors	Non Suspect ACM	500	SF	0	SF				
1	2	Boy's Restroom across from Classroom 208	N/A	Concrete Block Wall	Non Suspect ACM	1500	SF	0	SF				
1	2	Boy's Restroom across from Classroom 208	N/A	Ceiling Tile 2' x 4'	Non Suspect ACM	500	SF	0	SF				
1	2	Girl's Restroom across from Classroom 208	N/A	Ceramic Tile Floors	Non Suspect ACM	500	SF	0	SF				
1	2	Girl's Restroom across from Classroom 208	N/A	Concrete Block Wall	Non Suspect ACM	1500	SF	0	SF				
1	2	Girl's Restroom across from Classroom 208	N/A	Ceiling Tile 2' x 4'	Non Suspect ACM	500	SF	0	SF				
1	2	Hallway Storage Room 221A	N/A	Concrete Floor	Non Suspect ACM	100	SF	0	SF				
1	2	Hallway Storage Room 221A	N/A	Concrete Block Wall	Non Suspect ACM	300	SF	0	SF				
1	2	Hallway Storage Room 221A	N/A	Sheetrock Ceiling	Non Suspect ACM	100	SF	0	SF				
1	2	Electrical Room 221B	N/A	Concrete Floor	Non Suspect ACM	100	SF	0	SF				
1	2	Electrical Room 221B	N/A	Concrete Block Wall	Non Suspect ACM	300	SF	0	SF				
1	2	Electrical Room 221B	N/A	Corrugated Metal Ceiling	Non Suspect ACM	100	SF	0	SF				
1	2	IT MDF Room 221C	N/A	Concrete Floor	Non Suspect ACM	100	SF	0	SF				
1	2	IT MDF Room 221C	N/A	Concrete Block Wall	Non Suspect ACM	300	SF	0	SF				
1	2	IT MDF Room 221C	N/A	Corrugated Metal Ceiling	Non Suspect ACM	100	SF	0	SF				
1	2	IT MDF Room 221C	N/A	Fiberglass Pipe Insulation	Non Suspect ACM	10	LF	0	LF				
1	2	Staff Restroom outside of Classroom 220 - Right	N/A	Ceramic Tile Floors	Non Suspect ACM	80	SF	0	SF				
1	2	Staff Restroom outside of Classroom 220 - Right	N/A	Concrete Block Wall	Non Suspect ACM	160	SF	0	SF				
1	2	Staff Restroom outside of Classroom 220 - Right	N/A	Sheetrock Wall	Non Suspect ACM	80	SF	0	SF				
1	2	Staff Restroom outside of Classroom 220 - Right	N/A	Ceiling Tile 2' x 4'	Non Suspect ACM	80	SF	0	SF				
1	2	Staff Restroom outside of Classroom 220 - Left	N/A	Ceramic Tile Floors	Non Suspect ACM	80	SF	0	SF				
1	2	Staff Restroom outside of Classroom 220 - Left	N/A	Concrete Block Wall	Non Suspect ACM	160	SF	0	SF				
1	2	Staff Restroom outside of Classroom 220 - Left	N/A	Sheetrock Wall	Non Suspect ACM	80	SF	0	SF				
1	2	Staff Restroom outside of Classroom 220 - Left	N/A	Ceiling Tile 2' x 4'	Non Suspect ACM	80	SF	0	SF				
1	2	Hallway Storage Room 213A	N/A	Concrete Floor	Non Suspect ACM	20	SF	0	SF				
1	2	Hallway Storage Room 213A	N/A	Concrete Block Wall	Non Suspect ACM	80	SF	0	SF				
1	2	Hallway Storage Room 213A	N/A	Corrugated Metal Ceiling	Non Suspect ACM	20	SF	0	SF				
1	2	Hallway Storage Room 213A	N/A	Fiberglass Duct Insulation	Non Suspect ACM	80	SF	0	SF				
1	2	Hallway Storage Room 213A	N/A	Fiberglass Pipe Insulation	Non Suspect ACM	30	LF	0	LF				
1	2	Electrical Room 229A	N/A	Concrete Floor	Non Suspect ACM	100	SF	0	SF				
1	2	Electrical Room 229A	N/A	Concrete Block Wall	Non Suspect ACM	300	SF	0	SF				
1	2	Electrical Room 229A	N/A	Corrugated Metal Ceiling	Non Suspect ACM	100	SF	0	SF				
1	2	Electrical Room 229A	N/A	Fireproofing	Non Suspect ACM	25	SF	0	SF				



8010 New Lincoln - Room by Room Location Log Report.xls

		School District of Philadelphia New Lincoln High School 3201 Ryan Avenue, Philadelphia, PA 19136 ULCS# 8010 Year Built: 2009	AHERA Three-Year Reinspection 2015-2016 Room by Room Location Log Report								Reinspection Date: December 30, 2016		
											Building Inspector: Bernard J Bryson		
											Number: ACC-0125-6-031		
											Management Planner: Megan Vala		
											Number: 740728		
E l e m e n t	F l o o r												
		On Site Room Name	System Affected	Material Description	Confirmed/Assumed/NAD/ Non Suspect ACM	Amount of Material	SF LF EA	Amount of Damage	SF LF EA	Color required for VAT	Comments/Description/Notes	Attic/ Crawl Space Ranking	
1	AT	Attic - None	X	X	X	X	X	X	X		None	None	
1	CS	Crawl Space - None	X	X	X	X	X	X	X		None	None	

### **Section III    Certificates**

#### **A. Management Planner/Building Inspector Certificates**

### Section III – A

#### Management Planner/Building Inspector Certificates

These charts indicate the Name, Course Date, Expiration Date and Corresponding Certificate Number of the Management Planner and Building Inspector of individuals that participated in the AHERA 3 Year Inspection and Management Plan process of 2015/2016.

Management Planner	Date Granted	Expiration Date	Certificate Number
Monique Causley	2/15/2015	2/16/2016	ACC-0215-8-010
Monique Causley	2/16/2016	2/17/2017	ACC-0216-8-001
Megan Vala	5/22/2015	6/22/2016	740728
Mary Anne Lerro	4/5/2016	4/5/2017	742327

Building Inspector	Date Granted	Expiration Date	Certificate Number
Scott Magee	8/15/2015	8/15/2016	70016699C
William Garrity	8/15/2015	8/15/2016	70016699A
Bernard Brunner	10/2/2015	8/2/2016	45397
Mary Anne Lerro	3/3/2015	3/3/2016	740092
Mary Anne Lerro	4/5/2016	4/5/2017	742322
James Madden	12/11/2014	12/11/2015	ACC-1214-6-010
James Madden	12/3/2015	12/3/2016	ACC-1215-6-018
Troy Ray	3/15/2015	3/19/2016	ACC-0355-6-011
Ananth Vinjamuri	9/29/2015	9/29/2016	374
Shelton Williams	9/29/2015	9/29/2016	375
Paul Davis	2/12/2015	2/12/2016	ACC-0215-6-015
Paul Davis	2/2/2016	2/2/2017	741836
Bernard Bryson	2/16/2015	2/16/2016	ACC-0125-6-031
Bernard Bryson	2/15/2016	2/15/2017	ACC-0216-6-005
Alexander Roman	9/18/2015	9/18/2016	EHSBIR-150619-008
Norm Harrison	9/2/2015	9/2/2016	ACC-0915-6-011
Kelly Mayberry	2/20/2015	2/20/2016	EHSBIR-150220-005
Kelly Mayberry	2/18/2016	2/18/2017	EHSBIR-160218-006
Andrew Hine	5/6/2015	5/6/2016	AI05042015-3
Maryellen Leotta	2/12/2015	2/12/2016	ACC-0215-6-024

# Certificate of Completion

*awarded to*

**Monique Causley**

*for successfully completing the prescribed course of study in*

## **Pennsylvania Asbestos Management Planner Refresher Course**

*under TSCA Title II*

*presented by*

**ACCESS TRAINING SERVICES, INC.**  
7921 River Road, Pennsauken, NJ 08110  
(856) 665-3449

**2/16/15**

*Course Date*

**N/A**

*Exam Date*

**2/16/16**

*Expiration Date*

**Not Provided**

*Social Security Number*

**ACC-0215-8-010**

*Certificate Number*

**Mark K. Schlager**  
*Training Director*

# Certificate of Completion

*awarded to*

**Monique Causley**

*for successfully completing the prescribed course of study in*

## **Pennsylvania Asbestos Management Planner Refresher Course**

**under TSCA Title II**

*presented by*

**ACCESS TRAINING SERVICES, INC.  
7921 River Road, Pennsauken, NJ 08110  
(856) 665-3449**

**2/15/16**

*Course Date*

**N/A**

*Exam Date*

**2/15/17**

*Expiration Date*

**Not Provided**

*Social Security Number*

**ACC-0216-8-001**

*Certificate Number*

**Mark K. Schlüger**  
*Training Director*

# *Certificate of Training*

CRITERION LABORATORIES, INC.

HEREBY CERTIFIES THAT

Megan Vala

HAS SUCCESSFULLY COMPLETED A 16 HOUR COURSE ENTITLED

Asbestos Management Planner Initial

INCLUDING CLASSROOM INSTRUCTION

05/21/2015 to 05/22/2015


Exam passed on this 22nd day of May 2015 - Score - 94

Approved for AHERA Accreditation Under TSCA Title II

3370 Progress Drive, Suite J  
Bensalem, PA 19020  
(215) 244-1300 - Phone  
(215) 244-4349 - Fax  
www.criterionlabs.com

Course is conducted in English

DIRECTOR:

  
James A. Welte, CIH, President

# *Certificate of Training*

CRITERION LABORATORIES, INC.

HEREBY CERTIFIES THAT

Mary Anne Lerro

HAS SUCCESSFULLY COMPLETED A 4 HOUR COURSE ENTITLED  
Asbestos Management Planner Refresher

INCLUDING CLASSROOM INSTRUCTION


on this 5th day of April 2016

Approved for AHERA Accreditation Under TSCA Title II

3370 Progress Drive, Suite J  
Bensalem, PA 19020  
(215) 244-1300 - Phone  
(215) 244-4349 - Fax  
www.criterionlabs.com

Course is conducted in English

DIRECTOR:

  
James A. Wells, CIH, President

# EMSL ANALYTICAL, INC.

Certifies that

Scott Magee

has successfully completed the course of study for the

## Asbestos Building Inspector Refresher Course

for Accreditation under TSCA Title II

EMSL Certificate No. 70016699C


### Approved by:

PA Dept. of Labor and Industry  
Accreditation # 137

Course Date: 8/15/2015  
Granted: 8/15/2015  
Expiration Date: 8/15/2016

### Sponsored by:

EMSL Analytical, Inc.  
200 Route 130 North  
Cinnaminson, NJ 08077  
Phone: (800) 220-3675  
Fax: (856) 786-5973  
[www.emsl.com](http://www.emsl.com)



*Michael P. Menz*

Michael P. Menz, CIH  
Training Director

Environmental, Mold, Bacteria, IAQ, Asbestos, Lead, Forensic and Materials Testing Since 1981



# EMSL ANALYTICAL, INC.

Certifies that

William Garrity

has successfully completed the course of study for the

## Asbestos Building Inspector Refresher Course

for Accreditation under TSCA Title II

EMSL Certificate No. 70016699A


Approved by:

PA Dept. of Labor and Industry  
Accreditation # 137

Course Date: 8/15/2015  
Granted: 8/15/2015  
Expiration Date: 8/15/2016

Sponsored by:

EMSL Analytical, Inc.  
200 Route 130 North  
Cinnaminson, NJ 08077  
Phone: (800) 220-3675  
Fax: (856) 786-5973  
[www.emsl.com](http://www.emsl.com)



*Michael P. Menz*

Michael P. Menz, CIH  
Training Director

Environmental, Mold, Bacteria, IAQ, Asbestos, Lead, Forensic and Materials Testing Since 1981

45397

# *National Asbestos & Environmental Training Institute*

## **CERTIFICATE OF COMPLETION**

AHERA/EPA Accredited Per 40 CFR Part 763  
Asbestos Accreditation under TSCA Title II

*This is to certify that*


***Bernard Brunner, Jr.***

*Successfully completed the course entitled*

**1/2-Day New York State/EP A/AHERA Asbestos Building Inspector Annual Refresher on  
October 2, 2015**

*Examination Passed October 2, 2015*

*Expiration Date on October 2, 2016*

  
**Doris L. Adler**  
*President, NAEETI*

Per 10 NYCRR Part 73.2 (L) (1), DOH 2832 Certificate of Completion of Asbestos  
Safety Training is the only official record of training for N.Y.S. students.

Language: English

ABIH 1/2 CM POINT

3321 Doris Avenue, Building B, Ocean, NJ 07712

Phone (732) 531-5571

Fax (732) 531-5956

[www.naeti.com](http://www.naeti.com)

Number 740092

Expiration Date:  
03/03/2016

# *Certificate of Training*

CRITERION LABORATORIES, INC.

HEREBY CERTIFIES THAT

Mary Anne Lerro

HAS SUCCESSFULLY COMPLETED A 4 HOUR COURSE ENTITLED

Asbestos Building Inspector Refresher

on this 3rd day of March 2015

Exam passed on this 3rd day of March 2015 - Score - 84

Approved for AHERA Accreditation Under TSCA Title II

3370 Progress Drive, Suite J

Bensalem, PA 19020

(215) 244-1300 - Phone

(215) 244-4349 - Fax

www.criterionlabs.com

Course is conducted in English

DIRECTOR:

James A. Welts

James A. Welts, CIH, President

Number 742322

Expiration Date:  
04/05/2017

# *Certificate of Training*

**CRITERION LABORATORIES, INC.**

**HEREBY CERTIFIES THAT**

**Mary Anne Lerro**

**HAS SUCCESSFULLY COMPLETED A 4 HOUR COURSE ENTITLED**

**Asbestos Building Inspector Refresher**

**INCLUDING CLASSROOM INSTRUCTION**

**on this 5th day of April 2016**

**Exam passed on this 5th day of April 2016 - Score - 88**

**Approved for AHERA Accreditation Under TSCA Title II**

3370 Progress Drive, Suite J  
Bensalem, PA 19020  
(215) 244-1300 - Phone  
(215) 244-4349 - Fax  
www.criterionlabs.com

*Course is conducted in English*

**DIRECTOR:**

*James A. Welts*

*James A. Welts, CIH, President*

# Certificate of Completion

**James Madden**

*for successfully completing the prescribed course of study in*

## **Pennsylvania Asbestos Building Inspector Refresher Course**

under TSCA Title II

*presented by*

**ACCESS TRAINING SERVICES, INC.**  
7921 River Road, Pennsauken, NJ 08110  
(856) 665-3449

12/11/14

*Course Date*

N/A

*Exam Date*

12/11/15


*Expiration Date*

Not Provided

*Social Security Number*

ACC-1214-6-010

*Certificate Number*

  
**Mark K. Schlager**  
*Training Director*

# Certificate of Completion

**James Madden**

*for successfully completing the prescribed course of study in*

## **Pennsylvania Asbestos Building Inspector Refresher Course**

under TSCA Title II

*presented by*

**ACCESS TRAINING SERVICES, INC.**  
7921 River Road, Pennsauken, NJ 08110  
(856) 665-3449

**12/3/15**

*Course Date*

**N/A**

*Exam Date*

**12/3/16**

*Expiration Date*

**Not Provided**

*Social Security Number*

**ACC-1215-6-018**

*Certificate Number*

**Mark K. Schlager**  
*Training Director*

# Certificate of Completion

**Troy A. Ray**

*for successfully completing the prescribed course of study in*

## **Pennsylvania Asbestos Building Inspector Refresher Course**

under TSCA Title II

*presented by*

**ACCESS TRAINING SERVICES, INC.  
7921 River Road, Pennsauken, NJ 08110  
(856) 665-3449**

**3/19/15**

*Course Date*

**N/A**

*Exam Date*

**3/19/16**

*Expiration Date*

**Not Provided**

*Social Security Number*

**ACC-0355-6-011**

*Certificate Number*

**Mark K. Schlager**  
*Training Director*



# CERTIFICATE NO 374

G&C Environmental Services, Inc. (#294)

2 Street Road, Newtown Square, Pennsylvania 19073

Telephone: (610) 993-9202 Facsimile: (610) 993-9232

Email: Training@gcenviro.com

www.GCenviro.com

This document certifies that Ananth K. Vinjamuri has successfully completed this

State of New York Department of Health Approved AHERA BUILDING INSPECTOR

REFRESHER COURSE, completed as required for asbestos accreditation under the Toxic

Substances Control Act, Title II. This course was held from 09/29/2015 to 09/29/2015.

The examination date was 09/29/2015. This certificate expires one year from the date of

successful completion of the examination 09/29/2016.

*The official record of successful training completion is the New York State Department of Health certificate of asbestos safety training completion (DPH 2832).*

Gail M. Conner

Training Director

Gail M. Conner



## CERTIFICATE NO 375

G&C Environmental Services, Inc. (#294)

2 Street Road, Newtown Square, Pennsylvania 19073

Telephone: (610) 993-9202 Facsimile: (610) 993-9232

Email: Training@gcenviro.com

www.GCenviro.com

This document certifies that Shelton Williams has successfully completed this  
State of New York Department of Health Approved AHERA BUILDING INSPECTOR

REFRESHER COURSE, completed as required for asbestos accreditation under the Toxic

Substances Control Act, Title II. This course was held from 09/29/2015 to 09/29/2015.  
MM DD YR MM DD YR

The examination date was 09/29/2015. This certificate expires one year from the date of  
MM DD YR  
successful completion of the examination 09/29/2016.  
MM DD YR

*The official record of successful training completion is the New York State Department of  
Health certificate of asbestos safety training completion (DPH 2832).*

Gail M. Conner  
Training Director

Gail M. Conner

# Certificate of Completion

**Paul M. Davis**

*for successfully completing the prescribed course of study in*

## **Pennsylvania Asbestos Building Inspector Refresher Course**

under TSCA Title II

*presented by*

**ACCESS TRAINING SERVICES, INC.**  
7921 River Road, Pennsauken, NJ 08110  
(856) 665-3449

**2/12/15**

*Course Date*

**N/A**

*Exam Date*

**2/12/16**

*Expiration Date*

**Not Provided**

*Social Security Number*

**ACC-0215-6-015**

*Certificate Number*

**Mark K. Schlager**  
*Training Director*

# Certificate of Training

CRITERION LABORATORIES, INC.

HEREBY CERTIFIES THAT

Paul M. Davis

HAS SUCCESSFULLY COMPLETED A 4 HOUR COURSE ENTITLED  
Asbestos Building Inspector Refresher

INCLUDING CLASSROOM INSTRUCTION

on this 2nd day of February 2016

Exam passed on this 2nd day of February 2016 - Score - 92

Approved for AHERA Accreditation Under ISCA Title II

3370 Progress Drive, Suite J  
Bensalem, PA 19020  
(215) 244-1300 - Phone  
(215) 244-4349 - Fax  
www.criterionlabs.com

Course is conducted in English

DIRECTOR:

*James A. Wells*

James A. Wells, CIH, President

# Certificate of Completion

**Bernard J. Bryson**

*for successfully completing the prescribed course of study in*

## **Pennsylvania Asbestos Building Inspector Refresher Course**

under TSCA Title II

*presented by*

**ACCESS TRAINING SERVICES, INC.**  
7921 River Road, Pennsauken, NJ 08110  
(856) 665-3449

**2/16/15**  
*Course Date*

**N/A**

*Exam Date*

**2/16/16**

*Expiration Date*

**Not Provided**

*Social Security Number*

**ACC-0125-6-031**

*Certificate Number*

**Mark K. Schlager**  
*Training Director*

# Certificate of Completion

**Bernard J. Bryson**

*for successfully completing the prescribed course of study in*

## **Pennsylvania Asbestos Building Inspector Refresher Course**

under TSCA Title II

*presented by*

**ACCESS TRAINING SERVICES, INC.**  
7921 River Road, Pennsauken, NJ 08110  
(856) 665-3449

**2/15/16**

*Course Date*

**N/A**

*Exam Date*

**2/15/17**

*Expiration Date*

**Not Provided**

*Social Security Number*

**ACC-0216-6-005**

*Certificate Number*

**Mark K. Schlager**  
*Training Director*



**EHS TRAINING INSTITUTE, INC.**  
A Division of BATTI, Inc.

# **Certificate of Completion**

## **AHERA Building Inspector**

**(Refresher)**

**Awarded To:**

**Alexander Roman**

SS#:XXX-XX-1743  
Who has completed this 4-hour course and examination,  
EPA Approved under TSCA Title II  
AHERA / ASHARA Rule  
40 CFR Part 763.

**EHS TRAINING INSTITUTE, INC.**

A Division of BATTI, Inc.  
Delaware Industrial Park • 6 Garfield Way  
Newark, DE 19713-5817  
(302) 737-3376 • Fax (302) 737-5764

Course Date: **September 18, 2015**  
Date of Expiration: **September 18, 201**  
Certification Number : **EHSBIR 150619-008**

  
Todd K. Zeisloff, Instructor

  
Neeraj K. Batta, President

# Certificate of Completion

**Norman Harrison**

*for successfully completing the prescribed course of study in*

## **Pennsylvania Asbestos Building Inspector Refresher Course**

under TSCA Title II

*presented by*

**ACCESS TRAINING SERVICES, INC.**  
7921 River Road, Pennsauken, NJ 08109  
(856) 665-3449

**9/2/15**

*Course Date*

**N/A**

*Exam Date*

**9/2/16**


*Expiration Date*

**Not Provided**

*Social Security Number*

**ACC-0915-6-011**

*Certificate Number*

  
**Mark A. Schlenger**  
*Training Director*

**EHS TRAINING INSTITUTE, INC.**  
A Division of BATTI, Inc.

# **Certificate of Completion**

## **AHERA Building Inspector**

**(Refresher)**

**Awarded To:**

**Kelly Mayberry**

SS#:XXX-XX-1551

Who has completed this 4-hour course and examination,  
EPA Approved under TSCA Title II  
AHERA / ASHARA Rule  
40 CFR Part 763.

**EHS TRAINING INSTITUTE, INC.**

A Division of BATTI, Inc.

*Delaware Industrial Park • 6 Garfield Way*

*Newark, DE 19713-5817*


*(302) 737-3376 • Fax (302) 737-5764*

**Course Date: February 20, 2015**

**Date of Expiration: February 20, 2016**

**Certification Number : EHSBIR 150220-005**

  
Todd K. Zeisloft, Instructor

  
Neeraj K. Batta, President



**EHS TRAINING INSTITUTE, INC.**  
A Division of BATTI, Inc.

# **Certificate of Completion**

## **AHERA Building Inspector**

**(Refresher)**

**Awarded To:**

**Kelly Mayberry**

SS#:XXX-XX-1551  
Who has completed this 4-hour course and examination,  
EPA Approved under TSCA Title II  
AHERA / ASHARA Rule  
40 CFR Part 763.

**EHS TRAINING INSTITUTE, INC.**

A Division of BATTI, Inc.

Delaware Industrial Park • 6 Garfield Way  
Newark, DE 19713-5817  
(302) 737-3376 • Fax (302) 737-5764

Course Date: February 18, 2016  
Date of Expiration: February 18, 2017  
Certification Number : EHSBIR 160218-006

  
Todd K. Zeisloft, Instructor

  
Neeraj K. Batta, President

# AEROSOL MONITORING & ANALYSIS, INC.

*This is to certify that*  
**ANDREW HINE**

*has met the attendance requirements and successfully completed  
the course entitled*

**3-DAY EPA AHERA INSPECTOR**  
*For Accreditation Under TSCA Title II*

05/04/2015 to 05/06/2015

**Course Date**

05/06/2015

**Exam Date**

5/6/2016

**Expiration Date**

STEVE SIERAGI

**Principal Instructor**

*Steve Sieragi*

A105042015-3

**Certification No.**

E. Rush Barnett

**Course Director**

*E. Rush Barnett*

1331 Ashton Road

P.O.Box 646

Hanover, MD 21076

P: 410-684-3327

F: 410-684-3724

[www.amatraining.com](http://www.amatraining.com)

# Certificate of Completion

**Maryellen Leotta**

*for successfully completing the prescribed course of study in*

## **Pennsylvania Asbestos Building Inspector Refresher Course**

under TSCA Title II

*presented by*

**ACCESS TRAINING SERVICES, INC.**  
7921 River Road, Pennsauken, NJ 08110  
(856) 665-3449

**2/12/15**

*Course Date*

**N/A**

*Exam Date*

**2/12/16**

*Expiration Date*

**Not Provided**

*Social Security Number*

**ACC-0215-6-024**

*Certificate Number*

**Mark K. Schlüger**  
*Training Director*

# Asbestos Hazard Emergency Response Act (AHERA) Environmental Compliance Audit Cross Reference Table

In response to the AHERA Environmental Compliance Audit a Cross Reference Table has been prepared for inclusion into the Environmental Management Plan. The purpose of this Cross Reference Table is to link the following documents to the AHERA Management Plan.

<b>Cross Reference Table</b>	
3 Year Reinspection Report follows this Cross Reference Table documentation.	
<b>Subject Matter</b>	<b>Location of Required Documents</b>
Designated Person	Pages 1 - 3
Annual Notification	Pages 4 - 5
6 Month Periodic Surveillance Outline of Events	Page 6
3 Year Re-inspections Outline of Events	Page 7
Asbestos Management Program (operations and maintenance)	Pages 8 - 19
Asbestos Investigation Report (AIR)	Attachment 1 Letter Dated August 4, 2006
Training (included in the Asbestos Management Program)	<p>The original records are centralized at the School District's Environmental Library. Copies are maintained on staff and are required to be maintained in the latest Reinspection Report.</p> <p>2 hour awareness training records for all Building Engineers, Custodian Assistants and maintenance personnel</p> <p>40 hour worker/supervisor training records for the OEMS A-Team and various AST tradesmen.</p>
Response Actions (monthly mailings if applicable)	<p>The original documents are on file at the School District's Environmental Library.</p> <p>Copies of the original are mailed to the Schools Main Office for retention with the Management Plan documentation. These documents are typically kept separate from the management plan in an update binder due to the potential volume of response action reports.</p>

# **SCHOOL DISTRICT OF PHILADELPHIA**

## **ASBESTOS DESIGNATED PERSON**

**Gerald F Junod**  
**Office of Capital Programs**  
**Environmental Management & Services**  
**440 N Broad Street, 3<sup>rd</sup> Floor**  
**Philadelphia, PA 19130**  
**Telephone: 215 400 6738**  
**Fax: 215 400 4751**

<b>Drexel University- Asbestos Building Inspector Course</b>	<b>January 9-11, 1989 24 Hours</b>
<b>Drexel University- Asbestos Management Planner Course</b>	<b>January 12-13, 1989 16 Hours</b>
<b>Criterion Laboratories, Inc. - Asbestos Management Planner Course</b>	<b>October 11-12, 2012 16 Hours</b>

<b><u>Annual Building Inspector Refreshers</u></b>	<b>1990 to Present</b>
<b>4 Hours</b>	
<b>Drexel University</b>	
<b>Criterion Laboratories, Inc</b>	
<b>Access Training Services, Inc.</b>	

<b><u>Annual Building Management Planner Refreshers</u></b>	<b>1990 to 1994</b>
<b>4 Hours</b>	
<b>Drexel University</b>	
<b>Criterion Laboratories, Inc</b>	<b>2013 to Present</b>
<b>4 Hours</b>	

### **Environmental Manager, School District of Philadelphia**

**Manages the design and implementation of asbestos and lead projects for the Capital Improvement Program and other District Departments including Facilities & Operations and Information Technology. Ensures that asbestos abatement and lead remediation projects are expertly designed and executed in accordance with industry best management practice standards and regulations.**

### **Manager, City of Philadelphia Asbestos Control Program**

**Served as the Asbestos Control Program Manager for the City of Philadelphia, Department of Public Health, Air Management Services, Asbestos Control Unit from August 1, 2003 through October 23, 2006.**

### **Mid Atlantic Regional Environmental Consortium (MAREC)**

**Former member with attendance and participation commitments of all quarterly EPA Region III and yearly National Asbestos Regulatory Conferences sponsored by the EPA and the National Conference of State Legislators respectively as a representative for the City of Philadelphia Department of Public Health Air Management Services from 1994 through 2006.**

### **Philadelphia Environmental Task Force**


**Former member of the Philadelphia Environmental Task force as a representative and point of contact for the City of Philadelphia Department of Public Health Air Management Services Asbestos Control Unit from 2002 through 2006.**

**Asbestos Instructor**

Worked as the primary instructor for the initial and annual Asbestos Project Inspector training and licensing program as mandated by City of Philadelphia Department of Public Health Asbestos Control Regulations from August 1994 through October 2006.

Worked as a lead instructor with an Environmental Consulting Firm and approved by the US EPA for the initial and annual refresher training courses for various asbestos occupational disciplines such as the Building Inspector, Management Planner and Worker/Supervisor from 1991 through 1994.

I certify that the general, local agency responsibilities as stipulated in Section 763.84 will be met.



Gerald F. Junod  
Asbestos Designated Person  
Environmental Manager  
Office of Environmental Management and Services

## **SCHOOL DISTRICT OF PHILADELPHIA**

### **Accreditation Information Statement**

All persons who inspect for Asbestos Containing Building Materials (ACBM) and who will design or carry out response actions with respect to assumed and confirmed ACBM, will be accredited by an EPA approved course and/or a State Contractors Accreditation Program under Sections 206 (c) and 206 (b) of Title II of the ACT.

A handwritten signature in black ink, appearing to read 'Gerald F. Junod', is written over the printed name and title.

**Gerald F. Junod**  
**Asbestos Designated Person**  
**Environmental Manager**  
**Office of Environmental Management and Services**

SCHOOL DISTRICT OF PHILADELPHIA  
OFFICE OF CAPITAL PROGRAMS  
440 NORTH BROAD STREET, SUITE 373  
PHILADELPHIA, PENNSYLVANIA 19130

OFFICE OF ENVIRONMENTAL MANAGEMENT AND SERVICES

PHONE (215)-400-4750

September 2015

TO: Principals  
Building Administrators/Occupants  
Parents/Guardians

FROM: Fran Burns  
Chief Operating Officer

Francine Locke, M.S., Director  
Office of Environmental Management and Services

SUBJECT: Annual EPA Notification Letter

Pursuant to the Federal Environmental Protection Agency (EPA) mandate, as required by 40 C.F.R. 763.84 (c)(d) of public access to environmental records, this letter is to acknowledge the availability of your facility's Asbestos Hazard Emergency Response Act (AHERA) Management Plan.

Each member of the school staff, parents/guardians, temporary workers and/or contractors, are required to receive a copy of the Notification Letter. At the direction of the Principal, a copy is to be posted on the bulletin boards and an appropriate amount of copies are to be generated for distribution.


Note: The AHERA Three-Year Reinspection reports, in colored binders; White with Pink, Tan, Black, Red, Dark Blue, Green, Yellow and White, are Federal EPA mandated inspection documents. The School District of Philadelphia is subject to severe monetary penalties if the reports and associated paperwork are not available to the EPA and the public upon request.

It is incumbent on designated school personnel to gather and retain this data as it is delivered, in one location for future review. Acceptable locations include the Principal's Office or Main Office for the primary data. The Building Engineer should maintain any secondary or duplicate copies.

If you have any questions, please call 215-400-4750. Thank you for your cooperation.



Fran Burns  
Chief Operating Officer



Francine Locke, M.S., Director  
Office of Environmental Management  
and Services

c: Danielle Floyd

AHERA-4  
8/21/15





**School District of Philadelphia**  
**OFFICIAL NOTICE**

**PLEASE POST**

September 2015

TO: Principals  
Building Administrators  
Building Engineers  
Building Occupants  
Parents/Guardians

FROM: Fran Burns  
Chief Operating Officer

Francine Locke, M.S., Director  
Office of Environmental Management and Services

SUBJECT: Annual Notification Letter: Asbestos Hazard Emergency Response Act

The Federal Register published on October 30, 1987, Subpart E, in Schools: Final Rule and Notice, 763.84 (c)(d) states that each local education agency shall ensure that workers and building occupants or guardians are to be informed at least once each school year about inspections, response actions and post-response action activities including re-inspections and periodic surveillance activities. The School District as the Local Education Agency (LEA), retains such reports that are available for public inspection in the Office of the Principal or Building Administrator.

The Principal or Building Administrator is required to do the following with this notification:

- 1) Post in a Public Place or Main Office
- 2) Inform Building Occupants
- 3) Send a copy of this notification to Parents or Guardians
- 4) Insert a copy into the latest AHERA Three-Year Reinspection report (white/pink binder) in your office or facility.

Handwritten signature of Fran Burns in black ink.

Fran Burns  
Chief Operating Officer

Handwritten signature of Francine Locke in black ink.

Francine Locke, M.S., Director  
Office of Environmental Management  
and Services

c: Danielle Floyd

AHERA-4a  
8/21/15

SCHOOL DISTRICT OF PHILADELPHIA  
Education Center  
440 North Broad Street  
Philadelphia, Pennsylvania 19130

Office of Environmental Management and Services

215-400-4750

AHERA  
Six Month Surveillance  
Outline of Events

- Pursuant to the Federal Environmental Protection Agency (EPA) mandate, as required by 40 CFR 763.92(b), the following procedure is to be implemented. At least once every six (6) months after a Management Plan is in effect, each Local Education Agency (LEA) shall conduct a periodic surveillance in each building that it owns or leases that contains Asbestos Containing Building Materials (ACBM) or is assumed to contain ACBM.
- The first Bi-Annual Inspection starts in the Spring (March, April, May) and again in the Fall (October, November, December) of each year. The Building Engineer/Assistant should assist the Building Inspector with appropriate access to all areas including (Crawlspaces/Attics) and rooms in the facility. There is no action required of the Principal.
- The Building Inspector shall visually inspect all areas that are identified in the Management Plan as ACBM or assumed ACBM. The date of the surveillance is recorded, the inspectors name and any changes in the conditions of the materials.
- The Building Inspector shall make a copy of the inspection document and insert into the front of the latest Management Plan (AHERA Three Year Reinspection report). The original document is returned to the LEA's Environmental Library and filed.

SCHOOL DISTRICT OF PHILADELPHIA  
Education Center  
440 North Broad Street  
Philadelphia, Pennsylvania 19130

Office of Environmental Management and Services

215-400-4750

AHERA  
Three Year Reinspection  
Outline of Events

- Pursuant to the Federal Environmental Protection Agency (EPA) mandate, as required by 40 CFR 763.85(b) the following procedure is to be implemented. At least once every three (3) years after a Management Plan is in effect, each Local Education Agency (LEA) shall conduct a reinspection of each building that it owns or leases that contains Asbestos Containing Building Material's (ACBM's) or is assumed to contain ACBM.
- Subsequent Three Year Re-inspections (2009, 2012, 2015, etc) shall start in the Fall (October, November, December, January). The Building Engineer/Assistant should assist the Building Inspector with appropriate access to all areas including (Crawlspaces/Attics) and rooms in the facility. There is no action required of the Principal.
- An accredited Building Inspector shall visually inspect and touch to determine friability, all areas that are identified in the Management Plan as ACBM or assumed ACBM. The date of the surveillance is recorded, the inspectors name and any changes in the conditions of the materials. The Building Inspectors state of accreditation and license number is required.
- After the inspection, the Building Inspector shall make a copy of the inspection documents and insert into the front of the latest Management Plan (AHERA Three Year Reinspection report). The original document is returned to the LEA's Environmental Library and filed.
- The Building Inspector shall return the reinspection data to the Management Planner to be assessed and determine appropriate response actions and a report issued (AHERA Three Year Reinspection report). One copy of the report is delivered to the schools Principal to be permanently retained with all previous environmental data. Another copy is retained in the LEA's Environmental Library.



**School District of Philadelphia**  
Office of Environmental Management & Services  
440 North Broad Street  
Philadelphia, PA 19130  
(215) 400-4750

**School District of Philadelphia  
Asbestos Management Program**

## TABLE OF CONTENTS

Definitions.....	Page 9
1. Introduction.....	Page 10
2. Summary of Asbestos Management Plan	
3. Asbestos Management Plan Execution.....	Page 11
a. General Execution	
4. Summary of Program Execution	
a. Asbestos Management Plan Execution	
5. Responsibilities	
a. OEMS	
b. Asbestos Worker/Supervisor "A-TEAM".....	Page 12
c. Asbestos Designated Person	
d. Supervisor or Project Manager (Capital, Maintenance & Facilities)	
e. Employee Capital.....	Page 13
f. Employee Maintenance	
g. Employee Facilities and Custodial	
6. Requirements.....	Page 14
a. Employee Exposure Monitoring	
b. Employee Notification	
c. Observation of Monitoring	
d. Training Program	
e. Access of Information	
f. Record Keeping	
7. AHERA O&M Plan.....	Page 15
a. Controls	
8. O&M Response Actions.....	Page 16
a. Facility Maintenance Isolation of Area	
b. Unlikely Contact with ACM/PACM	
c. Accidental Disturbance of ACM/PACM	
d. Planned Disturbance of ACM/PACM	
e. Miscellaneous ACM/PACM.....	Page 17
f. Vinyl Asbestos Floor Tile	
g. Mastic/Adhesives	
h. Woven Vibration Dampers	
i. Other Work Practices	
j. Fiber Release Episodes	
9. References and Resources.....	Page 18

## **DEFINITIONS / ACRONYMS**

<b>ACM/PACM:</b>	<b>Asbestos Containing Material/Potential Asbestos Containing Material</b>
<b>AHERA:</b>	<b>Asbestos Hazard Emergency Response Act</b>
<b>AIR FORM:</b>	<b>Asbestos Inspection Report Form</b>
<b>Amended Water:</b>	<b>Water to which a surfactant (soap) has been added</b>
<b>AMP:</b>	<b>Asbestos Management Program/Asbestos Management Plan</b>
<b>Asbestos Designate Person:</b>	<b>Individual assigned by the district to oversee asbestos related issues.</b>
<b>Asbestos Regulated Area:</b>	<b>Location that is posted as an asbestos work area in which only approved and accredited personnel are permitted to enter</b>
<b>AST:</b>	<b>Asbestos Support Team involving approved and accredited school district tradespersons personnel that are school district person</b>
<b>A-TEAM:</b>	<b>School District of Philadelphia asbestos workers</b>
<b>CIP:</b>	<b>Capital Improvement Program</b>
<b>Consultant:</b>	<b>Asbestos consulting firm hired by the District</b>
<b>Demolition Directive:</b>	<b>Memorandum – August 4, 2006 from Patrick Henwood</b>
<b>EPA:</b>	<b>Environmental Protection Agency</b>
<b>In House Personnel:</b>	<b>School District of Philadelphia asbestos workers</b>
<b>LEA:</b>	<b>Local Education Agency</b>
<b>O&amp;M:</b>	<b>Operations and Maintenance</b>
<b>OEMS:</b>	<b>Office of Environmental Management and Services</b>
<b>OSHA:</b>	<b>Occupational Safety and Health Administration</b>
<b>PEL:</b>	<b>Permissible Exposure Limit</b>
<b>PSD or SDP:</b>	<b>Philadelphia School District/School District of Philadelphia</b>
<b>PSIT:</b>	<b>Philadelphia School Improvement Team</b>
<b>STEL:</b>	<b>Short Term Exposure Limit</b>

## **1. Introduction**

The School District of Philadelphia, Asbestos Policy Statement:

“The School District of Philadelphia is dedicated to providing a safe and healthful work environment for its employees, students, faculty, contractors and visitors. In recognition of the potential health problems associated with asbestos, the School District of Philadelphia is committed to a comprehensive asbestos control program. This program is implemented and maintained through the School District of Philadelphia's Office of Environmental Management and Services (OEMS).”

OEMS has the responsibility of establishing procedures for asbestos abatement, asbestos inspection, air monitoring, renovation and demolition activities within all School District of Philadelphia owned or leased facilities.

These procedures are developed to ensure that:

- (1) People are not exposed to significant levels of asbestos fibers
- (2) Asbestos waste is handled and disposed of properly
- (3) Members of the School District of Philadelphia community have access to the Office of Environmental Management and Services for information, assistance, guidance, and interpretation regarding asbestos related matters.
- (4) Members of the School District of Philadelphia community have access to the Asbestos Management Plans as required and outlined in the US EPA AHERA regulations including annual written notification to all parents.
- (5) Compliance with all applicable Federal, State and Local Asbestos Regulations

Requirements outlined in this manual are mandatory in nature where the word “SHALL” is used and are advisory in nature where the word “SHOULD” is used.

## **2. Summary of Asbestos Management Program**

The School District of Philadelphia's Asbestos Management Program was established to meet the requirements of Federal, State, and Local Regulations.

These regulations include, but are not limited to:

- US Environmental Protection Agency Asbestos Hazard Emergency Response Act (US EPA AHERA) and National Emissions Standard for Hazardous Air Pollutants subpart M, Part 61 (NESHAP);
- US Department of Labor, Occupational Safety and Health Administration (OSHA) General Industry Standard (29 CFR 1910.1001) and the OSHA Asbestos Standard for the Construction Industry (29 CFR 1926.1101);
- The Commonwealth of Pennsylvania, Department of Labor and Industry, Asbestos Occupations, Accreditation and Certification Act;
- The City of Philadelphia, Department of Public Health, Asbestos Control Regulations.

### **3. Asbestos Management Program Execution**

#### **a) General Execution**

The Office of Environmental Management and Services (OEMS) develops, implements and manages safety and health programs for the School District of Philadelphia faculty, staff and students and assists with ensuring that all contractors comply with Federal, State and Local Environmental Regulations. The OEMS provides the oversight of School District of Philadelphia employees (Asbestos A-Team), environmental consultants, and asbestos abatement contractors for all projects within the School District of Philadelphia concerning Asbestos Containing Materials.

The control of safety and health hazards at the School District of Philadelphia is primarily through the implementation of engineering, work practice and administrative controls. Personal Protective Equipment (PPE) is used to supplement these controls or whenever the controls are not feasible or are in the process of being implemented. PPE is also recommended whenever exposures to chemical, physical or biological agents can be prevented or reduced by its use.

This written program establishes the procedures necessary to:

- 1) meet established standards and federal regulations for occupational exposure to asbestos fibers;
- 2) meet the requirements of the City of Philadelphia Asbestos Control Regulations which encompasses the disturbance and/or abatement of asbestos containing building materials;
- 3) provide the necessary health and safety protection to the School District of Philadelphia staff, faculty, students, contractors and visitors.

This program is strengthened by input and cooperation with the Philadelphia Federation of Teachers (PFT), Health and Welfare Fund.

### **4. Summary of Program Execution**

#### **a) Asbestos Management Program Execution**

The Asbestos Management Program is administered by the Office of Environmental Management and Services (OEMS). OEMS provides the following services primarily through professional consultants:

- (1) exposure monitoring services;
- (2) building inspection/surveys (bulk sampling) for the identification of asbestos containing materials;
- (3) asbestos project design services;
- (4) asbestos abatement project and air monitoring services;
- (5) emergency response to fiber release episodes;
- (6) education/information;
- (7) medical monitoring;
- (8) training for School District of Philadelphia personnel

### **5. Responsibilities**

#### **a) Office of Environmental Management and Services**

OEMS is responsible for performing the following functions:

- (1) Developing and administering of the Asbestos Management Program.
- (2) Providing asbestos-related services to all School District of Philadelphia departments.
- (3) Conducting required training of the Asbestos Management Program and working jointly with departments to schedule training.
- (4) Identifying and posting areas where labeling/signage are required.
- (5) Medical Monitoring of OEMS "A-TEAM" and other departments "AST" Asbestos Program staff.



- (6) Certification and training as required for OEMS “A-TEAM” and other departments “AST” Asbestos program staff.
- (7) Record keeping as outlined in Section 3.5 and all records as by required by US EPA AHERA regulations.

**b) Asbestos Worker/Supervisor - “A-TEAM”**

- (1) OEMS shall ensure that all “A-TEAM” workers/supervisors adhere to the following requirements:
  - a) Attend an initial Worker/Supervisor Asbestos Course;
  - b) Maintain the annual re-certification per EPA AHERA requirements and Commonwealth of Pennsylvania Asbestos Occupations, Accreditation and Certifications Act;
  - c) Undergo an annual Asbestos Medical Evaluation;
  - d) Undergo an annual Respirator Medical Clearance;
  - e) Undergo an annual Respirator Fit Testing.

**c) Asbestos Designated Person**

The Asbestos Designated Person is responsible for:

- (1) Assuring the health and safety of employees, students and visitors in the School District of Philadelphia facilities under his/her control.
- (2) Being kept informed of all areas under his or her jurisdiction where potential asbestos exposures exist and initiating protection programs that adhere to the Asbestos Management Program requirements of this manual.
- (3) Assuring that Asbestos Management Program requirements are adhered to by principal investigators, project managers, supervisors, or division heads, and School District of Philadelphia personnel under their supervision.
- (4) Ensuring that all employees within the Asbestos Management Program comply with (OSHA 1910.1001 (j) (7) (iv)) and the US EPA AHERA regulations by attending the required training.
- (5) Ensure the posting of:
  - a) Warning labels/signage
  - b) Commonwealth of Pennsylvania Asbestos Abatement and Demolition/Renovation Notification form
  - c) Asbestos Inspection Reports (AIR) form (where required)
  - d) Ensuring that Construction Projects follow the Demolition Directive procedures as outlined in the August 4, 2006 letter.

**d) Supervisor or Project Manager (Capital, Maintenance and Facilities)**

Each person in charge of a project, maintenance/repair, renovation/demolition, or other activity from the Departments of Capital, Maintenance, and/or Facilities, where asbestos containing material may be present is responsible for:

Identifying, with the assistance of OEMS, asbestos containing building materials prior to any disturbance of these materials. Various Federal (EPA and OSHA) and Local (City of Philadelphia Asbestos Control Regulations) require Asbestos Inspections prior to renovation/demolition activities. This shall be accomplished by always following the Asbestos Management Program Procedures as follows:

- (1) Ensure that the requirements of the Asbestos Management Program Procedures are followed by all personnel, trades, and contractors who are involved with the project;

- (2) Review of the required Asbestos Inspection Report (AIR) form (Attachment 1) and AHERA Management Plan documents prior to activities that may disturb any Asbestos Containing Materials;
- (3) Perform all project related duties as outlined in the Project Management Responsibilities;
- (4) Keep the department chairperson or director informed on any actions proposed or taken regarding the Asbestos Management Plan;
- (5) Ensuring that Construction Projects follow the Demolition Directive procedure outlined in the August 4, 2006 letter.

**e) Employee – Capital**

School District of Philadelphia Capital employees and/or consultants shall:

- (1) Ensure that no suspect or asbestos containing building materials are disturbed in the course of the projects they are performing or managing. This shall be accomplished by notifying their supervisor and OEMS by issuance of a work order permit (a.k.a PSIT Service Request Form) and verifying that the materials which may be disturbed are non-asbestos containing. If this information is not available or verification has not been made, these materials should not be disturbed.
- (2) Immediately notify OEMS and their supervisor in the event of a potential fiber release episode upon discovery of visible damage to asbestos containing materials.
- (3) Ensuring that Construction Projects follow the Demolition Directive procedures as outlined in the August 4, 2006 letter.

The types of projects represented as part of the Capital Improvement Program are as follows:

- (1) Complete Renovation of an existing building that addresses all facility component concerns and educational program needs;
- (2) Major Renovation of an existing building addressing significant facility component and educational improvements;
- (3) Addition to an existing building (either as an attachment or stand-alone structure) to accommodate needed program space;
- (4) Conversion of an existing facility to accommodate a change in educational program;
- (5) Facility Component Improvement of specific facility needs (i.e. electrical or HVAC system upgrades, ADA improvements, life safety improvements, exterior renovations, etc.)

**f) Employee – Maintenance**

School District of Philadelphia Maintenance employees shall:

- (1) Ensure that no suspect or asbestos containing building materials are disturbed in the course of their duties or work they are performing. This shall be accomplished by notifying their supervisor and OEMS by issuance of a work order permit and verifying that the materials which may be disturbed are non-asbestos containing. If this information is not available or verification has not been made, these materials should not be disturbed.
- (2) Immediately notify OEMS and their supervisor in the event of a potential fiber release episode or upon discovery of visible damage to asbestos containing materials.
- (3) All employees involved in maintenance activities shall attend required Asbestos Awareness training program within 60 days of employment.

**g) Employee – Facilities & Custodial**

School District of Philadelphia Facilities and Custodial employees shall:

- (1) Ensure that no suspect or asbestos containing building materials are disturbed in the course of their duties or work they are performing. This shall be accomplished by notifying their supervisor and OEMS by issuance of a work permit and verifying that the materials which may be disturbed are non-asbestos containing. If this information is not available or verification has not been made, these materials should not be disturbed;
- (2) Immediately notify OEMS and their supervisor in the event of a potential fiber release episode or upon discovery of visible damage to asbestos containing materials.
- (3) All employees involved in Facilities and Custodial activities shall attend require Asbestos Awareness training program within 60 days of employment.

## **6. Requirements**

### **a) Employee Exposure Monitoring**

When information indicates that an employee's exposure to asbestos fibers may equal or exceed an 8-hour time-weighted average of 0.1 f/cc \* (per OSHA 1910.1001 & 1926.1101), OEMS shall develop and implement an asbestos exposure monitoring program. The sampling strategy shall be designed to identify employees by work task (job classification) that is exposed to asbestos fibers that exceed an 8-hour time-weighted average of 0.1 f/cc.

### **b) Employee Notification**

OEMS shall notify in writing, each employee exposed to asbestos fibers at or above an 8-hour time weighted average of 0.1 f/cc.

### **c) Observation and Monitoring**

OEMS shall provide employees or their representatives with an opportunity to observe any exposure measurements conducted.

### **d) Training Program**

OEMS shall institute a training program which meets the requirements of AHERA for all employees who perform maintenance operations in a facility/school which contains asbestos containing materials or presumed asbestos containing materials and 1910.1001 (j), and the Commonwealth of Pennsylvania Department of Labor and Industry and the City of Philadelphia Asbestos Control Regulations. The affected departments shall ensure employee participation in this program. The OEMS "A-TEAM" and other departments "AST" Asbestos Program staff training shall be conducted annually for each employee as required by all Federal, State and Local for each asbestos discipline.

All Asbestos Awareness training as required by AHERA shall be performed within 60 days of employment and shall include:

- Health effects of asbestos
- Locations of ACM and PACM in the building/facility
- Recognition of CM and PACM damage and deterioration
- Requirements of the OSHA 1910.1001 standard relating to maintenance
- Proper response to fiber release episodes
- Procedure to be followed to isolate areas affected by fiber release

### **e) Access to Information**

OEMS shall make available to affected employees or their representative's copies of the Occupational Safety and Health Administration (OSHA) General Industry Standard Part 1910.1001 and the department shall post a copy in the workplace.

### **f) Record Keeping**

OEMS shall maintain an accurate record of all employee exposure measurements. OEMS and/or the School District of Philadelphia Human Resources Department shall maintain records of employee medical monitoring program. OEMS shall maintain all employee training records. All records shall be provided upon request to employees, former employees, representatives designated by the individual employee.

## **7. AHERA OPERATIONS AND MAINTENANCE PLAN**

### **a) CONTROLS**

#### **i. Work Order System**

Minimizing disruption of ACM/PACM during maintenance and renovation activities is the primary goal and task encountered by OEMS. Operations and maintenance employees and contractors should be warned to avoid conducting any maintenance work which may disturb ACM/PACM. Initiating a work order system, where all work orders or requests are channeled through the Office of Environmental Management and Services (OEMS), will be the method used to control and minimize disruption of ACM/PACM.

Any work performed by in-house personnel or contractors that could or will impact ACM/PACM shall be coordinated by OEMS. A completed Asbestos Inspection Report Form (Attachment 1) shall be issued to in-house personnel and/or all contractors whose work could impact ACM/PACM. This form should accompany each contract issued to an outside contractor and posted on the jobsite.

All work order requests for maintenance and renovation activities in areas where ACM/PACM is suspected or known to be present are to be submitted to OEMS prior to proceeding with work. OEMS is responsible for reviewing asbestos survey records for information about the presence of ACM/PACM in the area where the work is to be performed. OEMS should physically inspect the area to ensure existing records reflect actual conditions. If no asbestos is present, a work order is not necessary and the planned actions can proceed. If ACM/PACM is found to be present in the area, OEMS will sign the work order application and obtain an approved and accredited asbestos contractor or assign OEMS "A-TEAM" to abate the ACM/PACM.

#### **ii. Regulated Areas**

The owner will identify and regulate all areas where airborne concentrations of ACM/PACM exceed the Permissible Exposure Limit (PEL)\* (Per OSHA determined to be 0.1 f/cc) and/or short term exposure limit (STEL) (Per OSHA determined to be 0.1 f/cc), or there is reasonable possibility that the (PEL) and/or (STEL) may be exceeded. All ACM/PACM removal activities involving thermal system insulation ACM/PACM (Class I), surfacing ACM/PACM (Class I), and miscellaneous ACM/PACM such as floor tile, roofing, and siding mastic, etc. (Class II), and repair and maintenance operations where thermal system insulation and surfacing ACM/PACM is likely to be disturbed (Class III) will be performed in accordance with federal, state, and local regulations. All asbestos abatement work and activities will be designed and managed as asbestos regulated areas. These areas will be demarcated and labeled.

#### **iii. Warning Signs**

Warning signs shall be displayed at all approaches to each asbestos regulated area. The asbestos abatement contractor will provide OSHA warning signs in all regulated areas during removal, repair, and other maintenance activities. OEMS will provide AIRs to all contractors who must inform all employees and supervisors working in locations contiguous to asbestos regulated areas of the potential hazards and work practices required.

#### **iv. Warning Labels**

Warning labels and/or signage shall be affixed to all raw materials, mixtures, scrap, waste, debris, and other products containing asbestos fibers, or to their containers. Generally, the asbestos abatement contractor or OEMS A-Team personnel will provide all warning labels for ACM/PACM containment.

## **8. O & M RESPONSE ACTIONS**

The Asbestos Management Program general O&M procedures are outlined in this section. Additional requirements specific to asbestos abatement activities are included in the Project Design documents for all Asbestos Abatement Work. Regular cleaning, inspection, and reporting of ACM/PACM deterioration or other problems must be diligently practiced by all employees including custodial and maintenance personnel.

### **a) Facility Maintenance Isolation of Area Responsibilities**

Maintenance personnel are often required to work in areas where ACM/PACM may potentially be disturbed. Most maintenance activities are conducted by in-house staff, outside contractors, or a combination.

Emergency fiber release episodes, such as pipe fitting or valve breaks, emergency boiler work, or mechanical equipment repair will be responded to by OEMS A-Team personnel or asbestos abatement contractor personnel. The owner's maintenance staff will: (1) isolate the emergency fiber release area; (2) post warning signs to prevent unauthorized access, and (3) notify their supervisor and OEMS. OEMS will ensure that the fiber release area remains isolated and is properly cleaned by and approved and accredited abatement contractor or by OEMS A-TEAM personnel.

### **b) Unlikely Contact with ACM/PACM**

Maintenance activities or repairs which can be performed without contacting or disturbing the ACM/PACM require little more than normal care and good workmanship. For example, valves which are either uncovered or covered with non-asbestos insulation can be packed or repaired without disturbing asbestos insulation on nearby pipes. The major precaution is to ensure that maintenance and custodial personnel are familiar with procedures such as isolating the area, posting warning signs, and notifying OEMS in the event of any accidental ACM/PACM disturbance.

### **c) Accidental Disturbance of ACM/PACM**

Maintenance and facilities personnel shall notify OEMS any time a fiber release is suspected. If friable ACM/PACM becomes airborne in the building,

### **d) Planned Disturbance of ACM/PACM**

Maintenance activities that may impact ACM/PACM include access to a valve, flange, duct, or related system component.

Where asbestos-containing insulation must be removed to maintain or repair the thermal system, the ACM/PACM will imminently be disturbed. ACM/PACM removal work shall be conducted by OEMS A-Team personnel or an approved and accredited asbestos abatement contractor.

If friable ACM/PACM becomes airborne in the building, maintenance and facilities personnel shall secure the area and contact OEMS. OEMS shall respond accordingly.

**e) Miscellaneous ACM/PACM**

Miscellaneous types of ACM/PACM may include vinyl asbestos floor tiles, mastics/adhesives and woven vibration dampers. Disturbance of these materials should be avoided. Routine maintenance activities involving these materials should not pose a problem if handled properly. Questions on the proper removal and disposal of miscellaneous ACM/PACM should be directed to OEMS. OEMS will contact an approved and accredited asbestos abatement contractor or utilize OEMS A-TEAM personnel to assist with miscellaneous ACM/PACM clean-up activities.

**f) Vinyl Asbestos Floor Tile**

Asbestos-containing floor tiles in good condition are considered non-friable unless they are crushed, drilled, sawed, sanded or disturbed by any activity that breaks up the material. Routine maintenance of these materials should employ the use of non-abrasive buffers and wet cleaning technique. Broken or loose floor tiles should be removed and disposed of as asbestos waste by OEMS. Remaining debris should be vacuumed with a HEPA vacuum and the area wet mopped using amended water.

**g) Mastics/Adhesives**

Mastics and adhesives containing asbestos in good condition are considered non-friable and do not pose a potential health concern unless crushed, drilled, sawed, sanded, or otherwise abraded. Questions on the proper removal should be directed to OEMS.

**h) Woven Vibration Dampers**

Woven vibration dampers in good condition are considered non-friable and do not pose a potential health concern unless cut, crushed, drilled, sawed, sanded, or otherwise abraded. Questions on the proper removal should be directed to OEMS.

**i) Other Work Practices**

Any special work not included in this section should be addressed to OEMS for review prior to the initiation of work that may involve the disturbance of ACM/PACM.

**j) Fiber Release Episodes**

Facilities and maintenance staff should report to OEMS the presence of asbestos debris, water or physical damage to ACM/PACM, or any other evidence of possible fiber release. OEMS should have the OEMS A-Team personnel or an approved and accredited abatement contractor respond to the site to clean up debris and make repairs as soon as possible. OEMS will also contact a consultant to conduct air monitoring and prepare a report and submit at project completion to OEMS for each episode. OEMS will forward the reports for each site location AHERA Management Plan accordingly.



## 9. REFERENCES and RESOURCES

Applicable regulations for asbestos projects impacted by renovation, demolition, and maintenance activities.

- **Philadelphia Air Management Services – Asbestos Control Unit**  
<http://www.phila.gov/health/units/ams/Asbestos/asbestos.html>
- **Pennsylvania Asbestos Occupations, Accreditation and Certification Act**  
<http://www.dli.state.pa.us/landi/cwp/view.asp?a=185&q=56262&landiNav=>
- **United States Environmental Protection Agency Asbestos Home Page**  
<http://www.epa.gov/asbestos/>
- **Occupational Safety and Health Administration (OSHA) Asbestos Home**  
<http://www.osha.gov/SLTC/asbestos>