

# SCHOOL DISTRICT OF PHILADELPHIA



## Asbestos Hazard Emergency Response Act “AHERA”

### THREE-YEAR RE-INSPECTION 2015-2016 and ASBESTOS MANAGEMENT PLAN for the

**C.C.A. Baldi Middle School**

**ULCS# 8160  
Building # B816001-1  
8801 Verree Road  
Philadelphia, Pennsylvania  
19115**

**Year Built: 1971**

January 2016

*Conducted by:*

Accredited Environmental Technologies, Incorporated  
Batta Environmental Associates, Incorporated  
Criterion Laboratories, Incorporated  
Environmental Testing Consultants, LLC  
G & C Environmental Services, Incorporated  
KEM Partners, Incorporated  
Synertech, Inc.  
TTI Environmental, Inc.  
USA Environmental Management, Inc.  
The Vertex Companies, Inc.

*Management Plan Prepared by:*  
Criterion Labs, Inc and Synertech Inc.

*This report must remain in the Main Office as mandated by the US EPA AHERA Regulations.*

# **AHERA THREE-YEAR REINSPECTION VOLUME IX**

## **Table of Contents**

### **Transmittal Letter**

### **Executive Summary**

- I. Summary list of Confirmed Asbestos Containing Building Materials
- II. Summary list of Assumed Asbestos Contain Building Materials
- III. Summary list of Non-Asbestos Containing Building Materials
- IV. Summary list of Non Suspect Asbestos Containing Building Materials
- V. Summary List of Auditorium DATA for this location
- VI. Summary list of Attic and/or Crawlspace DATA for this location
- VII. Summary list of Pipe Chase/Pipe Shaft DATA for this location

### **Section I Report of Re-Inspection**

- A. Introduction
- B. Three-Year Re-inspection IX Overview
- C. Post- Management Plan Activities and Changes
  - C.1 - Sampling and Analysis
  - C.2 - New Floor Tile Sampling
  - C.3 - Abatement Activity
  - C.4 - Periodic (Six-Month) Surveillance (Damaged Materials)

### **Section II Re-Inspection Data**

- A. Introduction
- B. Re-Inspection Key Definitions
- C. Room by Room Location Log Report

### **Section III Certificates**

- A. Management Planner/Building Inspector Certificates

<b>Section IV</b>	<b>Cross Reference Table</b>	Page 1-8
	Asbestos Management Program	Page 9-19

SCHOOL DISTRICT OF PHILADELPHIA  
EDUCATIONAL CENTER  
440 NORTH BROAD STREET  
PHILADELPHIA, PENNSYLVANIA 19130

OFFICE OF ENVIRONMENTAL MANAGEMENT AND SERVICES

PHONE (215)-400-4750

January 2016

TO: All Principals  
All Building Administrators

FROM: Fran Burns  
Chief Operating Officer

Francine Locke, M.S., Director  
Office of Environmental Management and Services

SUBJECT: AHERA Three (3) Year Re-inspection IX report

In order to comply with the provisions of the Asbestos Hazard Emergency Response Act (AHERA) the attached report is submitted to you. The law requires that this report be kept in the Main/Principal's office. It cannot be removed from these locations. *If the school (program) is relocated to a different building, these environmental documents are to be safely retained for the next school/building occupants.* All asbestos reports must be available to the public and Federal EPA upon request.

  
\_\_\_\_\_  
Fran Burns  
Chief Operation Officer  
\_\_\_\_\_  
Francine Locke, M.S., Director  
Office of Environmental Management  
and Services

## **Executive Summary**

This Asbestos Hazard Emergency Response Act (AHERA) Three-Year Re-inspection “Volume # IX” Management Plan at this location, has been completed and the report of re-inspection submitted to the School District of Philadelphia. The re-inspections in all School District of Philadelphia buildings of 2015-2016 were conducted and completed between October 5<sup>th</sup>, 2015 through March 30<sup>th</sup>, 2016 as a joint project by Accredited Environmental Technologies, Inc., Batta Environmental Associates, Inc., Criterion Laboratories, Inc., Environmental Testing Consultants, LLC, G & C Environmental Services, Inc., KEM Partners, Inc., Synertech, Inc., TTI Environmental, Inc., USA Environmental Management, Inc. and The Vertex Companies, Inc.

In general, the School District of Philadelphia Office of Environmental Management and Services conducts Environmental Impact Evaluations and provides Asbestos Inspection Reports prior to any renovation, demolition and/or maintenance activities. The AHERA report must be reviewed prior to any renovation, demolition and/or maintenance activities in order to avoid the unknowing disturbance to Asbestos Containing Building Materials identified within this location. In addition, prior to work activities above all drop ceilings this report should be reviewed to avoid potential disturbances to Asbestos Containing Materials. Refer to Section IV of the Cross Reference Table, for additional Asbestos Management Program information. Contact the Office of Environmental Management and Services to have an Environmental Impact Evaluation conducted prior to any renovation, demolition and/or maintenance activities within this facility.

The information contained in this report was obtained from the original Asbestos Management Plan for the school, from update reports on changes and activities since the completion of the 1<sup>st</sup> Management Plan for each location and from all prior inspections performed and documented in Volume # I through Volume VIII (dated respectively 1992, 1995, 1998, 2001, 2004, 2007, 2010 or 2013) (if applicable) - and by this Three-Year Re-inspection of this school. The re-inspection report/Management Plan of 2015-2016 were reviewed and prepared collectively by Management Planner Megan Vala, Mary Anne Lerro of Criterion Laboratories, Inc. and/or Monique Causley, of Synertech Inc.

The 2015-2016 inspection process included the addition of a comprehensive Room by Room Inventory of all Thermal (T), Surfacing (S) and Miscellaneous (M) Materials specific to each room of this facility. Inspections of each room's thermal, ceilings, walls, floors and miscellaneous items regardless of Asbestos Content are categorized on the Room by Room Location Log Report for this location. Rooms or areas of the facility that were not accessible at the time of the inspection are marked with an "X". The Room by Room Location Log Report is found in Section II C of this Management Plan.

All Presumed or Suspect Asbestos Containing Building Materials (ACBMs), listed in the following summary charts are categorized as Confirmed, Assumed, Non-Asbestos, and/or Non-Suspect (ACBMs) were identified in the original Management Plan, or in the Volume I through Volume VIII AHERA Three-Year Re-inspection reports, and were re-inspected as part of this project.

As mandated by the U S EPA AHERA regulations, periodic Six-Month inspections and Three-Year Re-inspections of this location will be performed and the Inspection Data in this report will be updated accordingly.

Please feel free to contact the School District of Philadelphia's Office of Environmental Management and Services (OEMS) regarding any comments, questions, or concerns regarding this report or any Environmental related topic. OEMS staff can be reached at (215) 400 4750, via fax at (215) 400 4751 or via e-mail at [flocke@philasd.org](mailto:flocke@philasd.org) and/or [gfunod@philasd.org](mailto:gfunod@philasd.org).

Additional information can be found on our website. Here is the link to the OEMS website.  
<http://webgui.phila.k12.pa.us/offices/e/environmental>

## **I. Summary list of Confirmed Asbestos Containing Building Materials within this facility**

These charts are to be used for a quick reference\* in order to avoid the unknowing disturbance of Asbestos Containing Materials during any and all Operations, Maintenance, Renovation, and/or Demolition activities at this location. *These materials have been sampled and Laboratory Analysis has CONFIRMED the presence of Asbestos. Contact OEMS prior to the disturbance of any of the following materials.*

### **Confirmed Asbestos Containing Building Materials for this location**

Black Mastic a/w Floor Tile VAT 12" x 12"	Plaster Ceiling
---	-----------------

*\* Always refer to the Room by Room Logs for each specific material classification as the material classification findings may be different in various rooms throughout this facility.*

*\*\* Some Materials may have multiple classifications (Confirmed, Assumed, NAD and Non Suspect) within this facility.*

## II. Summary list of Assumed Asbestos Containing Building Materials within this facility

These charts are to be used for a quick reference\* in order to avoid the unknowing disturbance of Asbestos Containing Materials during any and all Operations, Maintenance, Renovation, and/or Demolition activities at this location. These materials have not been sampled and should not be disturbed until verification of Asbestos Content. Contact OEMS for assessment and sampling prior to the disturbance of these materials.

### Assumed Asbestos Containing Building Materials for this location

Floor Tile VAT 12" x 12"	Sheetrock Ceiling	Spline Ceiling Tile Glue Dots
Radiator Insulation	Sheetrock Wall	Textured Ceiling Paint
Seam Caulking	Sink Undercoat Mastic	Vibration Damper Cloth

*\* Always refer to the Room by Room Logs for each specific material classification as the material classification findings may be different in various rooms throughout this facility.*

*\*\* Some Materials may have multiple classifications (Confirmed, Assumed, NAD and Non Suspect) within this facility.*

### III. Summary list of Non-Asbestos Containing Building Materials within this facility

These charts are to be used for a quick reference\* in order to avoid the unknowing disturbance of Asbestos Containing Materials during any and all Operations, Maintenance, Renovation, and/or Demolition activities at this location. *These materials have been sampled and Laboratory Analysis has indicated NO Asbestos present or NO ASBESTOS DETECTED (NAD).*

#### Non- Asbestos Containing Building Materials for this location

Black Glue Dots	Ceiling Tile 3' x 6'	Vibration Damper Cloth
Ceiling Tile 1' x 1'	Fiberglass Ceiling Tile 2' x 4'	
Ceiling Tile 2' x 4'	Floor Tile VAT 12" x 12"	

*\* Always refer to the Room by Room Logs for each specific material classification as the material classification findings may be different in various rooms throughout this facility.*

*\*\* Some Materials may have multiple classifications (Confirmed, Assumed, NAD and Non Suspect) within this facility.*



#### IV. Summary list of Non-Suspect Asbestos Containing Building Materials within this facility

These charts are to be used for a quick reference\* in order to avoid the unknowing disturbance of Asbestos Containing Materials during any and all Operations, Maintenance, Renovation, and/or Demolition activities at this location. These materials are not typically known to contain Asbestos.

##### Non-Suspect Asbestos Containing Building Materials for this location

Carpet	Fiberglass Ceiling Tile 2' x 4'	Metal Walls
Cement Floor	Fiberglass Pipe Fitting Insulation	Partition Room Dividers
Ceramic Tile Floors	Fiberglass Pipe Insulation	Steel Ceiling
Concrete Block Wall	Glass Ceiling	Vinyl Vibration Damper Cloth
Concrete Ceiling	Metal Ceiling	Wood Floor
Concrete Wall	Metal Sheeting Ceiling	

\* *Always refer to the Room by Room Logs for each specific material classification as the material classification findings may be different in various rooms throughout this facility.*

\*\* *Some Materials may have multiple classifications (Confirmed, Assumed, NAD and Non Suspect) within this facility.*

## V. Summary list of Auditorium DATA for this location

These charts are to be used for a quick reference of the Auditorium DATA within this facility. Sampling of the Auditorium Ceilings throughout the District is more difficult because of the various ceiling heights. As sampling occurs this information is updated on a case by case basis for each specific location and facility.

### This is a list of known materials for this location's Auditorium

Auditorium	Ceiling Tile 3' x 6'	NAD
Auditorium	Concrete Block Wall	Non Suspect ACM
Auditorium	Carpet	Non Suspect ACM
Auditorium	Cement Floor	Non Suspect ACM
Auditorium Stage	Fiberglass Pipe Insulation	Non Suspect ACM
Auditorium Stage	Fiberglass Pipe Fitting Insulation	Non Suspect ACM
Auditorium Stage	Concrete Ceiling	Non Suspect ACM
Auditorium Stage	Concrete Block Wall	Non Suspect ACM
Auditorium Stage	Wood Floor	Non Suspect ACM

*\* Always refer to the Room by Room Logs for each specific material classification as the material classification findings may be different in various rooms throughout this facility.*

*\*\* Some Materials may have multiple classifications (Confirmed, Assumed, NAD and Non Suspect) within this facility.*

## VI. Summary list of Attic and/or Crawlspace DATA for this location

These charts are to be used for a quick reference regarding the Attics and/or Crawlspaces inspection DATA within this facility. Contact OEMS prior to entering any attic or crawlspace within this facility and refer to the below chart and legend for Category Rank determination. The Data relative to these spaces is updated as conditions change regarding Abatement or Renovation activity on a case by case basis for each specific location and facility. In general, Crawlspaces are below the basement or 1<sup>st</sup> floor and Attics are above the floor space.

### *Category Rank Legend*

"A" - No Asbestos Containing Materials - Sample Results indicate NO ACM on pipes, fittings, elbows, or equipment located within this functional space, and NO VISIBLE DEBRIS or DAMAGE observed at time of this inspection.
"B" - Asbestos Containing Materials Exist - Sample Results indicate ACM on pipes, fittings, elbows, or equipment located within this functional space, HOWEVER, NO VISIBLE DEBRIS or DAMAGE observed at time of this inspection.
"C" - Asbestos Containing Materials Exist - Sample Results indicate ACM on pipes, fittings, elbows, or equipment located within this functional space, and LOCALIZED VISIBLE DEBRIS or DAMAGE observed at time of this inspection.
"D" - Asbestos Containing Materials Exist - Sample Results indicate ACM on pipes, fittings, elbows, or equipment located within this functional space and DISTRIBUTED VISIBLE DEBRIS or SIGNIFICANT DAMAGE observed at time of this inspection.
"E" - No Bulk Sample Results Available SUSPECT ACM OBSERVED. Contact OEMS immediately for additional instructions.

Attic/Crawlspace	Access Area	Floor Surface	Category Rank	Comments
Attic	X	X	X	No Attic
Crawlspace	X	X	X	No Crawlspace

## **VII. Summary list of Pipe Chase/Pipe Shaft DATA for this location**

These charts are to be used for a quick reference regarding the information known about the Pipe Chases and/or Pipe Shafts inspection DATA within this facility. Contact OEMS prior to performing renovation activities any Pipe Chase and/or Pipe Shaft within this facility and refer to the below chart and legend for Asbestos Content of various materials identified within each space. The Data relative to these spaces is updated as conditions change regarding Inspection, Abatement and/or Renovation activity on a case by case basis for each specific location and facility. In general, Pipe Chases are horizontal spaces and Pipe Shafts are vertical spaces.

***Pipe Chases and Pipe Shafts need to be assessed.***

## **Section I**

### **Report of Re-Inspection**

#### **A. Introduction**

#### **B. Three-Year Re-Inspection IX Overview**

#### **C. Post-Management Plan Activities and Changes**

##### **C.1 Sampling and Analysis**

##### **C.2 New Floor Tile Sampling**

##### **C.3 Abatement Activity**

##### **C.4 Periodic Six-Month Surveillance (Damaged Materials)**

## **Section I - A**

### **Report of Re-inspection**

#### **Introduction**

The Three-Year Re-inspection IX was performed to fulfill the requirements of 40 CFR Part 763 - the Asbestos Hazard Emergency Response Act (AHERA). As required by AHERA, each Local Education Agency (LEA) must re-inspect all known confirmed or assumed Asbestos Containing Building Material (ACBM) located in the LEA's facilities. This re-inspection is intended to update the original Asbestos Management Plan for the LEA's facilities.

Multiple Building Inspectors of several firms performed the 2015/2016 re-inspection. The re-inspection report/Management Plan of 2015-2016 were reviewed and prepared collectively by Management Planner Megan Vala, Mary Anne Lerro of Criterion Laboratories, Inc. and Monique Causley, of Synertech Inc.

All of the certificates can be found in Section III.

During the re-inspection of each School District of Philadelphia facility, all of the Management Plans for that facility were reviewed. Information from the conclusions section of that report is included in this report. Additionally, information on activities such as abatements, cleanings, sampling and inspections, which have taken place since the completion of the original Management Plan, were reviewed during the re-inspection. Information on those activities is included in this report.

As mandated by the U S EPA AHERA regulations, all future periodic Six-Month inspections and Three-Year Re-inspections of this location will be performed and the Inspection Data in this report will be updated accordingly.

## Section I - B

### **Three-Year Re-inspection IX Overview**

Each homogeneous area of Asbestos Containing Building Material (ACBM) listed in the original Management Plan or in the 1992, 1995, 1998, 2001, etc., Three-Year Re-inspection reports were inspected for the AHERA Three-Year Re-inspection Volume IX, and the information for that material verified. Any changes to a homogeneous area listed in the updates to the Management Plans were verified. Any area of suspected ACBM found in the course of the re-inspection, and not listed in the Management Plan or updates, were either assumed to contain asbestos or sampled and analyzed to determine their asbestos content. Any such new areas either assumed to contain asbestos or determined through analysis to contain asbestos were included in the report of the Three-Year Re-inspection. The results of the AHERA Three-Year Re-inspection IX are tabulated in the Room by Room log reports located in *Section II-C* of this report.

As previously noted, all future periodic Six-Month inspections and Three-Year Re-inspections of this location will be performed and the Inspection Data in this report will be updated accordingly.

## Section I – C.1

### **Post Management Plan Activities/Changes**

Information on activities affecting Asbestos Containing Building Materials (ACBMs) at this location is contained in updates to the Management Plan. These updates are kept on file by the School District of Philadelphia and were reviewed for this project. Updates to the Management Plan include the following: *Sampling and Analysis, New Tile Installation, Abatement Activity and Periodic Six-Month Surveillance Data.*

#### **Sampling and Analysis**

<b>Date</b>	<b>Floor</b>	<b>Room Type</b>	<b>Location</b>	<b>Material</b>	<b>Color</b>	<b>Results</b>
7/16/2015	Ground	Classroom	Room# G8	Floor Tile 12" x 12"	Tan	ASBESTOS WAS DETECTED
7/16/2015	Ground	Classroom	Room# G8	Floor Tile 12" x 12"	Tan	NO ASBESTOS WAS DETECTED



## Section I – C.2

Information on the installation of new floor tiles/renovation activities affecting Asbestos Containing Building Materials (ACBMs) at this location is contained in updates to the Management Plan. These updates are kept on file by the School District of Philadelphia and were reviewed for this project. Updates to the Management Plan include the following:

### **New Floor Tile Sampling**

***In the event that new tile is installed, the material must be tested prior to installation.***

## Section I – C.3

Information on the Asbestos Abatement and renovation activities affecting Asbestos Containing Building Materials (ACBMs) at this location is contained in updates to the Management Plan. These updates are kept on file by the School District of Philadelphia and were reviewed for this project. Updates to the Management Plan include the following:

### *Abatement Activity*

<i>Date</i>	<i>Floor</i>	<i>Location</i>	<i>Material</i>	<i>Color</i>	<i>Removed or Encapsulated</i>	<i>Quantity</i>
6/25/2015	1st	Room 105	Floor Tile 9" x 9"		Removed	100 SF

## Section I – C.4

Information on the AHERA inspection that noted damage to various Building Materials at this location is contained in updates to the Management Plan. These updates are kept on file by the School District of Philadelphia and were reviewed for this project. Work orders are created for Corrective Action responses and tracked for completion. Updates to the Management Plan include the following:

### *Periodic (Six-Month) Surveillance (Damaged Materials)*

<i>Date</i>	<i>Element</i>	<i>Floor</i>	<i>On Site Room Name</i>	<i>Material</i>	<i>Amount of Material</i>	<i>Amount of Damage</i>
3/15/2016	1	ML	Yellow Cafeteria	Floor Tile VAT 12" x 12"	2150 SF	10 SF
3/15/2016	1	ML	Blue Cafeteria	Floor Tile VAT 12" x 12"	2150 SF	10 SF

## **Section II**

### **Re-Inspection Data**

#### **A. Introduction**

#### **B. Re-Inspection Key Definitions**

#### **C. Room by Room Location Log Report**

## **Section II - A**

### **Re-inspection Data**

#### Introduction

The following information documents the Three-Year Re-inspection IX of the subject school/facility. The Homogeneous Area Reports were produced using the building inspector's field data on the facility. The key to the Homogeneous Area Report is outlined in the following pages of this report.

**Section II - B**  
**(page 1 of 4)**

**SCHOOL DISTRICT OF PHILADELPHIA**  
**AHERA THREE YEAR RE-INSPECTION IX**

<b>ITEM</b>	<b>DEFINITION</b>
<b>ULCS#</b>	Individual identification number assigned to each school within the School District of Philadelphia.
<b>HOMOGENEOUS AREA ID#</b>	Identification number assigned to each homogeneous area in a school/facility. Each section of the homogeneous area ID is significant.  1010/01/01/01 <b>A B C D</b>  <b>A.</b> Is the ULCS# for the school. <b>B.</b> Designates the specific building/building area within the school. <b>C.</b> Designates the floor or level within the building/building area. <b>D.</b> Designates the homogeneous material within that floor or level. Note: Item D may be a number or a letter.
<b>SYSTEM AFFECTED</b>	Corresponds to the AHERA system for classifying materials.  <b>T</b> : Thermal System <b>S</b> : Surfacing System <b>M</b> : Miscellaneous
<b>ITEM AFFECTED</b>	Is a description of the homogeneous material.
<b>ORIGINAL INSPECTION DATA</b>	This section contains the information found in the original Management Plan (1988-1989).
<b>AMOUNT OF MATERIAL/ UNIT</b>	Quantity of material, and measuring unit. Units include: Square Feet (SF) Each (EA) Linear Feet (LF) Cubic Feet (CF).

**SCHOOL DISTRICT OF PHILADELPHIA  
AHERA THREE YEAR RE-INSPECTION IX**

**RE-INSPECTION FORM KEY**

<b>ITEM</b>	<b>DEFINITION</b>
<b>CND Condition</b>	Corresponds to AHERA condition rating for materials.  <b>0</b> : No Damage <b>1</b> : Damage <b>2</b> : Significant Damage
<b>DP Damage Potential</b>	Corresponds to the AHERA material assessment system.  <b>1</b> : Potential for Damage <b>2</b> : Potential for Significant Damage
<b>ASMD Assumed Asbestos</b>	This means that a material was not sampled for asbestos content during the original Management Plan inspection.
<b>RA Response Action</b>	This corresponds to the AHERA system of response action rating for materials.  <b>1</b> : Establish O&M Program <b>2</b> : Repair and Establish O&M Program <b>3</b> : Enclose <b>4</b> : Encapsulate <b>5</b> : Remove <b>6</b> : Partial Removal and Establish O&M Program
<b>CHANGES</b>	This section describes changes to the homogeneous material in the twenty-four years since the original AHERA inspection. The abbreviations are defined below.  <b>RMVD</b> : Removed <b>ENCL</b> : Enclosed <b>ENCP</b> : Encapsulated <b>DMGD</b> : Damaged <b>SMPLD</b> : Sampled <b>MTRL</b> : Material <b>RPRD</b> : Repaired <b>N/L</b> : None Located <b>RPLCD</b> : Replaced

**SCHOOL DISTRICT OF PHILADELPHIA  
AHERA THREE-YEAR RE-INSPECTION IX**

**RE-INSPECTION FORM KEY**

<b>ITEM</b>	<b>DEFINITION</b>												
<b>THREE YEAR RE-INSPECTION</b>	<p>This section contains the information obtained from the Three-Year Re-inspection IX. With three exceptions, the information categories are identical in format and meaning to those found in the original inspection data section. The three exceptions are defined below.</p>												
<b>DMGD AMT Amount Damaged</b>	<p>This section gives the quantity of damaged material in a homogeneous area. The quantity is shown in the same format as the amount of material/unit section.</p>												
<b>NF Newly Friable</b>	<p>This section identifies materials in the original Management Plan which have since become friable.</p>												
<b>RA Response Action</b>	<p>This rating is based on the AHERA regulations, and is comparable to the RA rating found in the "Original Inspection Data" section. The following table details the response actions.</p> <table><tr><td>1.</td><td>Establish O&amp;M Program</td></tr><tr><td>2.</td><td>Repair and Establish O&amp;M Program</td></tr><tr><td>3.</td><td>Enclose</td></tr><tr><td>4.</td><td>Encapsulate</td></tr><tr><td>5.</td><td>Remove</td></tr><tr><td>6.</td><td>Partial Removal and Establish O&amp;M Program</td></tr></table> <p>a.   <b>High Priority Response</b> The homogeneous material has been scheduled for abatement or other response action.</p> <p>b.   <b>Medium Priority Response</b> The homogeneous material will be scheduled for abatement or other response action as soon as the high priority responses have been addressed.</p> <p>c.   <b>Low Priority Response</b> The homogeneous material will be scheduled for abatement or other response action as soon as the medium priority responses have been addressed.</p> <p>d.   <b>On-Going Response/Operations and Maintenance</b> The homogeneous material does not require abatement or other response action at present, and should be included in the facility's on-going operations and maintenance program.</p>	1.	Establish O&M Program	2.	Repair and Establish O&M Program	3.	Enclose	4.	Encapsulate	5.	Remove	6.	Partial Removal and Establish O&M Program
1.	Establish O&M Program												
2.	Repair and Establish O&M Program												
3.	Enclose												
4.	Encapsulate												
5.	Remove												
6.	Partial Removal and Establish O&M Program												



**SCHOOL DISTRICT OF PHILADELPHIA  
AHERA THREE-YEAR RE-INSPECTION IX**

**RE-INSPECTION FORM KEY**

---

The information presented in the changes section has been compiled from a variety of sources, including the Re-inspection and the following:

- \* Quality Control/Quality Assurance Reports of asbestos abatement projects, prepared by consultants to the School District.
- \* Permit and Notification Forms for asbestos abatement projects.
- \* Periodic Surveillance Forms
- \* Operations and Maintenance activities performed by School District personnel.
- \* Verbal information from School District personnel.
- \* Reports of sampling and analysis of suspected materials by both School District personnel and outside consultants.

**ROOM BY  
ROOM  
LOCATION LOG  
REPORT**

This section gives information, including damage amount and location, for a specific homogeneous material on a room-by-room basis and follows the Re-inspection form.

*NOTE:* The disparate nature of the above sources of information prohibits the verification of much information within the scope of the AHERA Three-Year Re-inspection. Discrepancies and omissions may exist in this information, and therefore is included on an "as is" basis. The inspectors for the Three-Year Re-inspection IX evaluated homogeneous areas based on the materials current condition and location, as evidenced during the inspector's site visit.

## Section II - C

### Room by Room Location Log Report

These charts are to be used for a quick reference\* in order to avoid the unknowing disturbance of Asbestos Containing Materials during any and all Operations, Maintenance, Renovation, and/or Demolition activities at this location.

*NOTE:*

*Contact OEMS prior to the disturbance of any of the materials that are listed as **Confirmed and/or Assumed**.*

*The quantities listed for (NAD) non-asbestos containing materials and/or Non-Suspect Materials are only estimated and were not measured for the purpose of this report. Field verification of quantities for renovation purposes would be necessary.*

# 8160 Baldi MS- 2015 2016 AHERA Three-Year Report .xls

		School District of Philadelphia C.C.A Baldi Middle School 8801 Verree Road, Philadelphia, PA 19115 ULCS# 8160 Year Built: 1971		AHERA Three-Year Reinspection 2015-2016 Room by Room Location Log Report							Reinspection Date: 1/15/2016 Building Inspector: Paul Davis Number: ACC-0215-6-015 Managment Planner: Mary Anne Lerro Number: 740092					
E l e m e n t	F l o o r	On Site Room Name	System Affected	Material Description	HID#	Confirmed, Assumed, NAD, Non Suspect ACM	Amount of Material	(SF/LF/EA)	Amount of Damage	SF LF EA	Color required for VAT	Comments/Description/Notes	Attic/Crawlsp ace Ranking	Damage Potential (DP)	Newly Friable (NF)	Response Action (RA)
1	UL	HVAC Penthouse 1A2 on Roof	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	100	LF	0	LF				N/A	N/A	N/A
1	UL	HVAC Penthouse 1A2 on Roof	N/A	Fiberglass Pipe Fitting		Non Suspect ACM	20	EA	0	EA				N/A	N/A	N/A
1	UL	HVAC Penthouse 1A2 on Roof	N/A	Metal Sheetting Ceiling		Non Suspect ACM	576	SF	0	SF				N/A	N/A	N/A
1	UL	HVAC Penthouse 1A2 on Roof	N/A	Concrete Block Wall		Non Suspect ACM	960	SF	0	SF				N/A	N/A	N/A
1	UL	HVAC Penthouse 1A2 on Roof	N/A	Cement Floor		Non Suspect ACM	576	SF	0	SF				N/A	N/A	N/A
1	UL	HVAC Penthouse 2A1 on Roof	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	100	LF	0	LF				N/A	N/A	N/A
1	UL	HVAC Penthouse 2A1 on Roof	N/A	Fiberglass Pipe Fitting		Non Suspect ACM	20	EA	0	EA				N/A	N/A	N/A
1	UL	HVAC Penthouse 2A1 on Roof	N/A	Vinyl Vibration Damper Cloth		Non Suspect ACM	10	SF	0	SF				N/A	N/A	N/A
1	UL	HVAC Penthouse 2A1 on Roof	N/A	Metal Sheetting Ceiling		Non Suspect ACM	576	SF	0	SF				N/A	N/A	N/A
1	UL	HVAC Penthouse 2A1 on Roof	N/A	Concrete Block Wall		Non Suspect ACM	960	SF	0	SF				N/A	N/A	N/A
1	UL	HVAC Penthouse 2A1 on Roof	N/A	Cement Floor		Non Suspect ACM	576	SF	0	SF				N/A	N/A	N/A
1	UL	Organization Room near Main Office	N/A	Ceiling Tile 2' x 4'		NAD	120	SF	0	SF				N/A	N/A	N/A
1	UL	Organization Room near Main Office	N/A	Concrete Block Wall		Non Suspect ACM	396	SF	0	SF				N/A	N/A	N/A
1	UL	Organization Room near Main Office	M	Floor Tile VAT 12" x 12"	8160/01/UL/EE	Assumed	120	SF	0	SF	Tan			1	No	1/D
1	UL	Hallway from Hall next to Organization Room to Roster Office	N/A	Ceiling Tile 2' x 4'		NAD	24	SF	0	SF				N/A	N/A	N/A
1	UL	Hallway from Hall next to Organization Room to Roster Office	N/A	Concrete Block Wall		Non Suspect ACM	144	SF	0	SF				N/A	N/A	N/A
1	UL	Hallway from Hall next to Organization Room to Roster Office	M	Floor Tile VAT 12" x 12"	8160/01/UL/EE	Assumed	24	SF	0	SF	Black			1	No	1/D
1	UL	Vice Principal's Office	N/A	Ceiling Tile 2' x 4'		NAD	154	SF	0	SF				N/A	N/A	N/A
1	UL	Vice Principal's Office	N/A	Concrete Block Wall		Non Suspect ACM	450	SF	0	SF				N/A	N/A	N/A
1	UL	Vice Principal's Office	N/A	Carpet		Non Suspect ACM	154	SF	0	SF				N/A	N/A	N/A
1	UL	Main Office	N/A	Ceiling Tile 2' x 4'		NAD	612	SF	0	SF				N/A	N/A	N/A
1	UL	Main Office	N/A	Concrete Block Wall		Non Suspect ACM	936	SF	0	SF				N/A	N/A	N/A
1	UL	Main Office	M	Floor Tile VAT 12" x 12"	8160/01/UL/EE	Assumed	612	SF	0	SF	Tan			1	No	1/D
1	UL	Copy Room in back right corner of Main Office	N/A	Ceiling Tile 2' x 4'		NAD	126	SF	0	SF		Pipe Chase Access in Room.		N/A	N/A	N/A
1	UL	Copy Room in back right corner of Main Office	N/A	Concrete Block Wall		Non Suspect ACM	414	SF	0	SF		Pipe Chase Access in Room.		N/A	N/A	N/A
1	UL	Copy Room in back right corner of Main Office	N/A	Carpet		Non Suspect ACM	126	SF	0	SF		Pipe Chase Access in Room.		N/A	N/A	N/A
1	UL	Copy Room's Restroom	N/A	Ceiling Tile 2' x 4'		NAD	20	SF	0	SF				N/A	N/A	N/A
1	UL	Copy Room's Restroom	N/A	Concrete Block Wall		Non Suspect ACM	162	SF	0	SF				N/A	N/A	N/A
1	UL	Copy Room's Restroom	N/A	Ceramic Tile Floors		Non Suspect ACM	20	SF	0	SF				N/A	N/A	N/A
1	UL	Roster Office in Main Office	N/A	Ceiling Tile 2' x 4'		NAD	180	SF	0	SF				N/A	N/A	N/A
1	UL	Roster Office in Main Office	N/A	Concrete Block Wall		Non Suspect ACM	486	SF	0	SF				N/A	N/A	N/A
1	UL	Roster Office in Main Office	M	Floor Tile VAT 12" x 12"	8160/01/UL/EE	Assumed	180	SF	0	SF	Tan			1	No	1/D
1	UL	Main Office Storage Room	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	50	LF	4	LF				N/A	N/A	N/A
1	UL	Main Office Storage Room	N/A	Fiberglass Pipe Fitting		Non Suspect ACM	4	EA	0	EA				N/A	N/A	N/A
1	UL	Main Office Storage Room	N/A	Concrete Ceiling		Non Suspect ACM	50	SF	0	SF				N/A	N/A	N/A
1	UL	Main Office Storage Room	N/A	Concrete Block Wall		Non Suspect ACM	300	SF	0	SF				N/A	N/A	N/A
1	UL	Main Office Storage Room	N/A	Cement Floor		Non Suspect ACM	50	SF	0	SF				N/A	N/A	N/A
1	UL	Principal's Office	N/A	Ceiling Tile 2' x 4'		NAD	252	SF	0	SF				N/A	N/A	N/A
1	UL	Principal's Office	N/A	Concrete Block Wall		Non Suspect ACM	576	SF	0	SF				N/A	N/A	N/A
1	UL	Principal's Office	N/A	Carpet		Non Suspect ACM	252	SF	0	SF				N/A	N/A	N/A
1	UL	Main Office Mail Room	N/A	Ceiling Tile 2' x 4'		NAD	280	SF	0	SF				N/A	N/A	N/A
1	UL	Main Office Mail Room	N/A	Concrete Block Wall		Non Suspect ACM	612	SF	0	SF				N/A	N/A	N/A
1	UL	Main Office Mail Room	M	Floor Tile VAT 12" x 12"	8160/01/UL/EE	Assumed	280	SF	0	SF	Tan			1	No	1/D
1	UL	Vice Principal's Office next to Mail Room	N/A	Ceiling Tile 2' x 4'		NAD	144	SF	0	SF				N/A	N/A	N/A
1	UL	Vice Principal's Office next to Mail Room	N/A	Concrete Block Wall		Non Suspect ACM	450	SF	0	SF				N/A	N/A	N/A
1	UL	Vice Principal's Office next to Mail Room	N/A	Carpet		Non Suspect ACM	144	SF	0	SF				N/A	N/A	N/A
1	UL	Nurse's Office Waiting Area	N/A	Ceiling Tile 2' x 4'		NAD	160	SF	0	SF				N/A	N/A	N/A
1	UL	Nurse's Office Waiting Area	N/A	Concrete Block Wall		Non Suspect ACM	504	SF	0	SF				N/A	N/A	N/A
1	UL	Nurse's Office Waiting Area	M	Floor Tile VAT 12" x 12"	8160/01/UL/EE	Assumed	160	SF	0	SF	Tan			1	No	1/D
1	UL	Nurse's Office Waiting Area Restroom	N/A	Concrete Ceiling		Non Suspect ACM	25	SF	0	SF				N/A	N/A	N/A
1	UL	Nurse's Office Waiting Area Restroom	N/A	Concrete Block Wall		Non Suspect ACM	200	SF	0	SF				N/A	N/A	N/A
1	UL	Nurse's Office Waiting Area Restroom	N/A	Ceramic Tile Floors		Non Suspect ACM	25	SF	0	SF				N/A	N/A	N/A
1	UL	Nurse's Office	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	5	LF	1	LF				N/A	N/A	N/A
1	UL	Nurse's Office	N/A	Fiberglass Pipe Fitting		Non Suspect ACM	2	EA	0	EA				N/A	N/A	N/A
1	UL	Nurse's Office	N/A	Ceiling Tile 2' x 4'		NAD	500	SF	0	SF				N/A	N/A	N/A
1	UL	Nurse's Office	N/A	Concrete Block Wall		Non Suspect ACM	810	SF	0	SF				N/A	N/A	N/A
1	UL	Nurse's Office	M	Sink Undercoat Mastic	8160/01/UL/KEM/PD/260	Assumed	5	SF	0	SF				1	No	1/D
1	UL	Nurse's Office	M	Floor Tile VAT 12" x 12"	8160/01/UL/EE	Assumed	500	SF	0	SF	Tan			1	No	1/D
1	UL	Nurse's Office Storage Room	N/A	Ceiling Tile 2' x 4'		NAD	100	SF	0	SF				N/A	N/A	N/A

# 8160 Baldi MS- 2015 2016 AHERA Three-Year Report .xls

1	UL	Nurse's Office Storage Room	N/A	Concrete Block Wall		Non Suspect ACM	360	SF	0	SF				N/A	N/A	N/A
1	UL	Nurse's Office Storage Room	M	Floor Tile VAT 12" x 12"	8160/01/UL/EE	Assumed	100	SF	0	SF	Tan			1	No	1/D
1	UL	Community Room next to Exit A-3	N/A	Ceiling Tile 2' x 4'		NAD	875	SF	0	SF				N/A	N/A	N/A
1	UL	Community Room next to Exit A-3	N/A	Concrete Block Wall		Non Suspect ACM	1080	SF	0	SF				N/A	N/A	N/A
1	UL	Community Room next to Exit A-3	S	Sheetrock Ceiling	8160/01/UL/KEM/PD/210	Assumed	54	SF	0	SF				1	No	1/D
1	UL	Community Room next to Exit A-3	M	Floor Tile VAT 12" x 12"	8160/01/UL/EE	Assumed	875	SF	0	SF	Orange			1	No	1/D
1	UL	Computer Server Room in Community Room	N/A	Concrete Ceiling		Non Suspect ACM	84	SF	0	SF				N/A	N/A	N/A
1	UL	Computer Server Room in Community Room	N/A	Concrete Block Wall		Non Suspect ACM	400	SF	0	SF				N/A	N/A	N/A
1	UL	Computer Server Room in Community Room	N/A	Cement Floor		Non Suspect ACM	84	SF	0	SF				N/A	N/A	N/A
1	UL	Storage Closet in Community Room	N/A	Concrete Ceiling		Non Suspect ACM	32	SF	0	SF				N/A	N/A	N/A
1	UL	Storage Closet in Community Room	N/A	Concrete Block Wall		Non Suspect ACM	200	SF	0	SF				N/A	N/A	N/A
1	UL	Storage Closet in Community Room	M	Floor Tile VAT 12" x 12"	8160/01/UL/EE	Assumed	32	SF	0	SF	Orange			1	No	1/D
1	UL	Stairwell next to Community Room and Boy's Restroom	N/A	Concrete Ceiling		Non Suspect ACM	432	SF	0	SF				N/A	N/A	N/A
1	UL	Stairwell next to Community Room and Boy's Restroom	N/A	Concrete Block Wall		Non Suspect ACM	1720	SF	0	SF				N/A	N/A	N/A
1	UL	Stairwell next to Community Room and Boy's Restroom	N/A	Cement Floor		Non Suspect ACM	432	SF	0	SF				N/A	N/A	N/A
1	UL	Boy's Restroom near Community Room	N/A	Concrete Ceiling		Non Suspect ACM	228	SF	0	SF				N/A	N/A	N/A
1	UL	Boy's Restroom near Community Room	N/A	Concrete Block Wall		Non Suspect ACM	682	SF	0	SF				N/A	N/A	N/A
1	UL	Boy's Restroom near Community Room	T	Radiator Insulation	8160/01/UL/KEM/PD/160	Assumed	12	SF	0	SF				1	No	1/D
1	UL	Boy's Restroom near Community Room	N/A	Ceramic Tile Floors		Non Suspect ACM	228	SF	0	SF				N/A	N/A	N/A
1	UL	Men's Restroom near Community Room	N/A	Concrete Ceiling		Non Suspect ACM	88	SF	0	SF				N/A	N/A	N/A
1	UL	Men's Restroom near Community Room	N/A	Concrete Block Wall		Non Suspect ACM	418	SF	0	SF				N/A	N/A	N/A
1	UL	Men's Restroom near Community Room	N/A	Ceramic Tile Floors		Non Suspect ACM	88	SF	0	SF				N/A	N/A	N/A
1	UL	Girl's Restroom near Community Room	N/A	Concrete Ceiling		Non Suspect ACM	252	SF	0	SF				N/A	N/A	N/A
1	UL	Girl's Restroom near Community Room	N/A	Concrete Block Wall		Non Suspect ACM	704	SF	0	SF				N/A	N/A	N/A
1	UL	Girl's Restroom near Community Room	T	Radiator Insulation	8160/01/UL/KEM/PD/160	Assumed	12	SF	0	SF				1	No	1/D
1	UL	Girl's Restroom near Community Room	N/A	Ceramic Tile Floors		Non Suspect ACM	252	SF	0	SF				N/A	N/A	N/A
1	UL	Women's Restroom near Community Room	N/A	Concrete Ceiling		Non Suspect ACM	96	SF	0	SF				N/A	N/A	N/A
1	UL	Women's Restroom near Community Room	N/A	Concrete Block Wall		Non Suspect ACM	440	SF	0	SF				N/A	N/A	N/A
1	UL	Women's Restroom near Community Room	N/A	Ceramic Tile Floors		Non Suspect ACM	96	SF	0	SF				N/A	N/A	N/A
1	UL	Custodial Closet next to Women's Restroom	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	50	LF	0	LF			Pipe Chase is Located in Room.	N/A	N/A	N/A
1	UL	Custodial Closet next to Women's Restroom	N/A	Fiberglass Pipe Fitting		Non Suspect ACM	20	EA	0	EA			Pipe Chase is Located in Room.	N/A	N/A	N/A
1	UL	Custodial Closet next to Women's Restroom	N/A	Concrete Ceiling		Non Suspect ACM	105	SF	0	SF			Pipe Chase is Located in Room.	N/A	N/A	N/A
1	UL	Custodial Closet next to Women's Restroom	N/A	Concrete Block Wall		Non Suspect ACM	440	SF	0	SF			Pipe Chase is Located in Room.	N/A	N/A	N/A
1	UL	Custodial Closet next to Women's Restroom	N/A	Cement Floor		Non Suspect ACM	105	SF	0	SF			Pipe Chase is Located in Room.	N/A	N/A	N/A
1	UL	Classroom 202	N/A	Ceiling Tile 2' x 4'		NAD	576	SF	0	SF				N/A	N/A	N/A
1	UL	Classroom 202	N/A	Concrete Block Wall		Non Suspect ACM	864	SF	0	SF				N/A	N/A	N/A
1	UL	Classroom 202	M	Sink Undercoat Mastic	8160/01/UL/KEM/PD/260	Assumed	5	SF	0	SF				1	No	1/D
1	UL	Classroom 202	M	Floor Tile VAT 12" x 12"	8160/01/UL/EE	Assumed	576	SF	0	SF	Orange			1	No	1/D
1	UL	Classroom 202 Closet	N/A	Concrete Ceiling		Non Suspect ACM	40	SF	0	SF			No Access; Not Inspected.	N/A	N/A	N/A
1	UL	Classroom 202 Closet	N/A	Concrete Block Wall		Non Suspect ACM	260	SF	0	SF			No Access; Not Inspected.	N/A	N/A	N/A
1	UL	Classroom 202 Closet	N/A	Cement Floor		Non Suspect ACM	40	SF	0	SF			No Access; Not Inspected.	N/A	N/A	N/A
1	UL	Room 201 Weight Room	N/A	Ceiling Tile 2' x 4'		NAD	960	SF	0	SF				N/A	N/A	N/A
1	UL	Room 201 Weight Room	N/A	Concrete Block Wall		Non Suspect ACM	1116	SF	0	SF				N/A	N/A	N/A
1	UL	Room 201 Weight Room	M	Sink Undercoat Mastic	8160/01/UL/KEM/PD/260	Assumed	6	SF	0	SF				1	No	1/D
1	UL	Room 201 Weight Room	M	Floor Tile VAT 12" x 12"	8160/01/UL/EE	Assumed	960	SF	0	SF	Orange			1	No	1/D
1	UL	Room 200 Storage and Copy Room	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	25	LF	0	LF				N/A	N/A	N/A
1	UL	Room 200 Storage and Copy Room	N/A	Fiberglass Pipe Fitting		Non Suspect ACM	2	EA	0	EA				N/A	N/A	N/A
1	UL	Room 200 Storage and Copy Room	N/A	Concrete Ceiling		Non Suspect ACM	80	SF	0	SF				N/A	N/A	N/A
1	UL	Room 200 Storage and Copy Room	N/A	Concrete Block Wall		Non Suspect ACM	396	SF	0	SF				N/A	N/A	N/A
1	UL	Room 200 Storage and Copy Room	M	Floor Tile VAT 12" x 12"	8160/01/UL/EE	Assumed	80	SF	0	SF	Orange			1	No	1/D
1	UL	Room 200 File Room and Storage	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	22	LF	0	LF				N/A	N/A	N/A
1	UL	Room 200 File Room and Storage	N/A	Fiberglass Pipe Fitting		Non Suspect ACM	5	EA	0	EA				N/A	N/A	N/A
1	UL	Room 200 File Room and Storage	N/A	Ceiling Tile 2' x 4'		NAD	153	SF	0	SF				N/A	N/A	N/A
1	UL	Room 200 File Room and Storage	N/A	Concrete Block Wall		Non Suspect ACM	468	SF	0	SF				N/A	N/A	N/A
1	UL	Room 200 File Room and Storage	M	Floor Tile VAT 12" x 12"	8160/01/UL/EE	Assumed	153	SF	0	SF	Orange			1	No	1/D
1	UL	Room 200 Special Education Liason Office	N/A	Ceiling Tile 2' x 4'		NAD	768	SF	0	SF				N/A	N/A	N/A
1	UL	Room 200 Special Education Liason Office	N/A	Concrete Block Wall		Non Suspect ACM	1152	SF	0	SF				N/A	N/A	N/A
1	UL	Room 200 Special Education Liason Office	M	Floor Tile VAT 12" x 12"	8160/01/UL/EE	Assumed	768	SF	0	SF	Orange			1	No	1/D
1	UL	Stairwell near Room 200	N/A	Concrete Ceiling		Non Suspect ACM	432	SF	0	SF				N/A	N/A	N/A
1	UL	Stairwell near Room 200	N/A	Concrete Block Wall		Non Suspect ACM	1720	SF	0	SF				N/A	N/A	N/A
1	UL	Stairwell near Room 200	N/A	Cement Floor		Non Suspect ACM	432	SF	0	SF				N/A	N/A	N/A
1	UL	Home Economics A (includes three classrooms)	N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	3100	SF	0	SF				N/A	N/A	N/A
1	UL	Home Economics A (includes three classrooms)	N/A	Concrete Block Wall		Non Suspect ACM	2358	SF	0	SF				N/A	N/A	N/A
1	UL	Home Economics A (includes three classrooms)	M	Sink Undercoat Mastic	8160/01/UL/KEM/PD/260	Assumed	90	SF	0	SF				1	No	1/D
1	UL	Home Economics A (includes three classrooms)	M	Floor Tile VAT 12" x 12"	8160/01/UL/EE	Assumed	3100	SF	0	SF	Orange			1	No	1/D
1	UL	Home Economics A Locker Room	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	20	LF	0	LF				N/A	N/A	N/A
1	UL	Home Economics A Locker Room	N/A	Fiberglass Pipe Fitting		Non Suspect ACM	4	EA	0	EA				N/A	N/A	N/A

# 8160 Baldi MS- 2015 2016 AHERA Three-Year Report .xls

1	UL	Home Economics A Locker Room	N/A	Concrete Ceiling		Non Suspect ACM	63	SF	0	SF				N/A	N/A	N/A
1	UL	Home Economics A Locker Room	N/A	Concrete Block Wall		Non Suspect ACM	352	SF	0	SF				N/A	N/A	N/A
1	UL	Home Economics A Locker Room	M	Floor Tile VAT 12" x 12"	8160/01/UL/EE	Assumed	63	SF	0	SF	Orange			1	No	1/D
1	UL	Home Economics A Middle Storage Room	N/A	Concrete Ceiling		Non Suspect ACM	105	SF	0	SF		No Access; Not Inspected.		N/A	N/A	N/A
1	UL	Home Economics A Middle Storage Room	N/A	Concrete Block Wall		Non Suspect ACM	484	SF	0	SF		No Access; Not Inspected.		N/A	N/A	N/A
1	UL	Home Economics A Middle Storage Room	N/A	Cement Floor		Non Suspect ACM	105	SF	0	SF		No Access; Not Inspected.		N/A	N/A	N/A
1	UL	Home Economics A Mid-Right Storage Room	N/A	Concrete Ceiling		Non Suspect ACM	136	SF	0	SF		No Access; Not Inspected.		N/A	N/A	N/A
1	UL	Home Economics A Mid-Right Storage Room	N/A	Concrete Block Wall		Non Suspect ACM	500	SF	0	SF		No Access; Not Inspected.		N/A	N/A	N/A
1	UL	Home Economics A Mid-Right Storage Room	N/A	Cement Floor		Non Suspect ACM	136	SF	0	SF		No Access; Not Inspected.		N/A	N/A	N/A
1	UL	Home Economics A Right Storage Room	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	1	LF	0	LF		No Access; Not Inspected.		N/A	N/A	N/A
1	UL	Home Economics A Right Storage Room	N/A	Concrete Ceiling		Non Suspect ACM	140	SF	0	SF		No Access; Not Inspected.		N/A	N/A	N/A
1	UL	Home Economics A Right Storage Room	N/A	Concrete Block Wall		Non Suspect ACM	594	SF	0	SF		No Access; Not Inspected.		N/A	N/A	N/A
1	UL	Home Economics A Right Storage Room	N/A	Cement Floor		Non Suspect ACM	140	SF	0	SF		No Access; Not Inspected.		N/A	N/A	N/A
1	UL	Stairwell A1 at Main Entrance	N/A	Ceiling Tile 2' x 4'		NAD	280	SF	0	SF		Includes Mezzanine Area.		N/A	N/A	N/A
1	UL	Stairwell A1 at Main Entrance	N/A	Concrete Ceiling		Non Suspect ACM	1000	SF	0	SF		Includes Mezzanine Area.		N/A	N/A	N/A
1	UL	Stairwell A1 at Main Entrance	N/A	Concrete Block Wall		Non Suspect ACM	4000	SF	0	SF		Includes Mezzanine Area.		N/A	N/A	N/A
1	UL	Stairwell A1 at Main Entrance	M	Floor Tile VAT 12" x 12"	8160/01/UL/EE	Assumed	1472	SF	0	SF	Black	Includes Mezzanine Area.		1	No	1/D
1	UL	Stairwell A1 at Main Entrance	N/A	Cement Floor		Non Suspect ACM	165	SF	0	SF		Includes Mezzanine Area.		N/A	N/A	N/A
1	UL	Home and School Office in Library	N/A	Ceiling Tile 2' x 4'		NAD	238	SF	0	SF				N/A	N/A	N/A
1	UL	Home and School Office in Library	N/A	Concrete Block Wall		Non Suspect ACM	558	SF	0	SF				N/A	N/A	N/A
1	UL	Home and School Office in Library	M	Floor Tile VAT 12" x 12"	8160/01/UL/EE	Assumed	238	SF	0	SF	Orange			1	No	1/D
1	UL	Dean of Students Office	N/A	Ceiling Tile 2' x 4'		NAD	400	SF	0	SF				N/A	N/A	N/A
1	UL	Dean of Students Office	N/A	Concrete Block Wall		Non Suspect ACM	720	SF	0	SF				N/A	N/A	N/A
1	UL	Dean of Students Office	M	Floor Tile VAT 12" x 12"	8160/01/UL/EE	Assumed	400	SF	0	SF	Orange			1	No	1/D
1	UL	IMC/Library Computer Testing Area	N/A	Concrete Ceiling		Non Suspect ACM	1150	SF	0	SF				N/A	N/A	N/A
1	UL	IMC/Library Computer Testing Area	N/A	Concrete Block Wall		Non Suspect ACM	1300	SF	0	SF				N/A	N/A	N/A
1	UL	IMC/Library Computer Testing Area	N/A	Carpet		Non Suspect ACM	1150	SF	0	SF				N/A	N/A	N/A
1	UL	Storage Room next to Computer Testing Area in IMC/Library	N/A	Ceiling Tile 2' x 4'		NAD	270	SF	0	SF				N/A	N/A	N/A
1	UL	Storage Room next to Computer Testing Area in IMC/Library	N/A	Concrete Block Wall		Non Suspect ACM	702	SF	0	SF				N/A	N/A	N/A
1	UL	Storage Room next to Computer Testing Area in IMC/Library	M	Sink Undercoat Mastic	8160/01/UL/KEM/PD/260 2	Assumed	5	SF	0	SF				1	No	1/D
1	UL	Storage Room next to Computer Testing Area in IMC/Library	M	Floor Tile VAT 12" x 12"	8160/01/UL/EE	Assumed	270	SF	0	SF	Orange			1	No	1/D
1	UL	IMC/Library Office	N/A	Ceiling Tile 2' x 4'		NAD	255	SF	0	SF				N/A	N/A	N/A
1	UL	IMC/Library Office	N/A	Concrete Block Wall		Non Suspect ACM	576	SF	0	SF				N/A	N/A	N/A
1	UL	IMC/Library Office	M	Floor Tile VAT 12" x 12"	8160/01/UL/EE	Assumed	255	SF	0	SF	Orange			1	No	1/D
1	UL	Stairwell C-7 next to IMC/Library	N/A	Ceiling Tile 2' x 4'		NAD	390	SF	0	SF				N/A	N/A	N/A
1	UL	Stairwell C-7 next to IMC/Library	N/A	Concrete Block Wall		Non Suspect ACM	738	SF	0	SF				N/A	N/A	N/A
1	UL	Stairwell C-7 next to IMC/Library	M	Floor Tile VAT 12" x 12"	8160/01/UL/EE	Assumed	192	SF	0	SF	Black			1	No	1/D
1	UL	Stairwell C-7 next to IMC/Library	N/A	Cement Floor		Non Suspect ACM	198	SF	0	SF				N/A	N/A	N/A
1	UL	IMC/Library Rear Storage Room	N/A	Ceiling Tile 2' x 4'		NAD	247	SF	0	SF				N/A	N/A	N/A
1	UL	IMC/Library Rear Storage Room	N/A	Concrete Block Wall		Non Suspect ACM	576	SF	0	SF				N/A	N/A	N/A
1	UL	IMC/Library Rear Storage Room	M	Sink Undercoat Mastic	8160/01/UL/KEM/PD/260 2	Assumed	5	SF	0	SF				1	No	1/D
1	UL	IMC/Library Rear Storage Room	M	Floor Tile VAT 12" x 12"	8160/01/UL/EE	Assumed	247	SF	0	SF	Orange			1	No	1/D
1	UL	IMC/Library Main Area	N/A	Concrete Ceiling		Non Suspect ACM	4032	SF	0	SF				N/A	N/A	N/A
1	UL	IMC/Library Main Area	N/A	Concrete Block Wall		Non Suspect ACM	3500	SF	0	SF				N/A	N/A	N/A
1	UL	IMC/Library Main Area	N/A	Carpet		Non Suspect ACM	4032	SF	0	SF				N/A	N/A	N/A
1	UL	Foreign Language Lab next to IMC/Library	N/A	Ceiling Tile 2' x 4'		NAD	980	SF	0	SF				N/A	N/A	N/A
1	UL	Foreign Language Lab next to IMC/Library	N/A	Concrete Block Wall		Non Suspect ACM	1134	SF	0	SF				N/A	N/A	N/A
1	UL	Foreign Language Lab next to IMC/Library	M	Floor Tile VAT 12" x 12"	8160/01/UL/EE	Assumed	980	SF	0	SF	Orange			1	No	1/D
1	UL	Foreign Language Lab Storage Room	N/A	Concrete Ceiling		Non Suspect ACM	130	SF	0	SF				N/A	N/A	N/A
1	UL	Foreign Language Lab Storage Room	N/A	Concrete Block Wall		Non Suspect ACM	460	SF	0	SF				N/A	N/A	N/A
1	UL	Foreign Language Lab Storage Room	N/A	Cement Floor		Non Suspect ACM	130	SF	0	SF				N/A	N/A	N/A
1	UL	Hallway and Stairwell C-6 between Foreign Language Lab and Mechanical Room	N/A	Ceiling Tile 2' x 4'		NAD	280	SF	0	SF				N/A	N/A	N/A
1	UL	Hallway and Stairwell C-6 between Foreign Language Lab and Mechanical Room	N/A	Concrete Block Wall		Non Suspect ACM	1360	SF	0	SF				N/A	N/A	N/A
1	UL	Hallway and Stairwell C-6 between Foreign Language Lab and Mechanical Room	M	Floor Tile VAT 12" x 12"	8160/01/UL/EE	Assumed	120	SF	0	SF	Black			1	No	1/D
1	UL	Hallway and Stairwell C-6 between Foreign Language Lab and Mechanical Room	N/A	Cement Floor		Non Suspect ACM	160	SF	0	SF				N/A	N/A	N/A
1	UL	Air Handler Room C-6	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	150	LF	0	LF				N/A	N/A	N/A
1	UL	Air Handler Room C-6	N/A	Fiberglass Pipe Fitting		Non Suspect ACM	50	EA	0	EA				N/A	N/A	N/A
1	UL	Air Handler Room C-6	N/A	Concrete Ceiling		Non Suspect ACM	1305	SF	0	SF				N/A	N/A	N/A
1	UL	Air Handler Room C-6	N/A	Concrete Block Wall		Non Suspect ACM	1628	SF	0	SF				N/A	N/A	N/A
1	UL	Air Handler Room C-6	N/A	Vibration Damper Cloth		NAD	24	SF	0	SF				N/A	N/A	N/A
1	UL	Air Handler Room C-6	N/A	Cement Floor		Non Suspect ACM	1305	SF	0	SF				N/A	N/A	N/A
1	UL	Hallway from Stairwell C-7 to Stairwell C-6	N/A	Ceiling Tile 2' x 4'		NAD	336	SF	0	SF				N/A	N/A	N/A
1	UL	Hallway from Stairwell C-7 to Stairwell C-6	N/A	Concrete Block Wall		Non Suspect ACM	368	SF	0	SF				N/A	N/A	N/A
1	UL	Hallway from Stairwell C-7 to Stairwell C-6	M	Floor Tile VAT 12" x 12"	8160/01/UL/EE	Assumed	336	SF	0	SF	Black			1	No	1/D
1	UL	Hallway from Stairwell C-6 to Elevator	N/A	Ceiling Tile 2' x 4'		NAD	336	SF	0	SF				N/A	N/A	N/A
1	UL	Hallway from Stairwell C-6 to Elevator	N/A	Concrete Block Wall		Non Suspect ACM	368	SF	0	SF				N/A	N/A	N/A
1	UL	Hallway from Stairwell C-6 to Elevator	M	Floor Tile VAT 12" x 12"	8160/01/UL/EE	Assumed	336	SF	0	SF	Black			1	No	1/D
1	UL	Hallway near Elevator to Hall by Upper Auditorium	N/A	Ceiling Tile 2' x 4'		NAD	336	SF	0	SF				N/A	N/A	N/A
1	UL	Hallway near Elevator to Hall by Upper Auditorium	N/A	Concrete Block Wall		Non Suspect ACM	368	SF	0	SF				N/A	N/A	N/A

# 8160 Baldi MS- 2015 2016 AHERA Three-Year Report .xls

1	UL	Hallway near Elevator to Hall by Upper Auditorium	M	Floor Tile VAT 12" x 12"	8160/01/UL/EE	Assumed	336	SF	0	SF	Black		1	No	1/D
1	UL	Hallway from Upper Auditorium to Stairwell C-7	N/A	Ceiling Tile 2' x 4'		NAD	336	SF	0	SF			N/A	N/A	N/A
1	UL	Hallway from Upper Auditorium to Stairwell C-7	N/A	Concrete Block Wall		Non Suspect ACM	368	SF	0	SF			N/A	N/A	N/A
1	UL	Hallway from Upper Auditorium to Stairwell C-7	M	Floor Tile VAT 12" x 12"	8160/01/UL/EE	Assumed	336	SF	0	SF	Black		1	No	1/D
1	UL	Hallway from Stairwell by Community Room and Boy's Restroom to Exit by Dean's Office	N/A	Ceiling Tile 2' x 4'		NAD	1080	SF	0	SF			N/A	N/A	N/A
1	UL	Hallway from Stairwell by Community Room and Boy's Restroom to Exit by Dean's Office	N/A	Concrete Block Wall		Non Suspect ACM	2322	SF	0	SF			N/A	N/A	N/A
1	UL	Hallway from Stairwell by Community Room and Boy's Restroom to Exit by Dean's Office	M	Floor Tile VAT 12" x 12"	8160/01/UL/EE	Assumed	1080	SF	0	SF	Black		1	No	1/D
1	UL	Hallway from Exit Doors by Dean's Office to Room 200	N/A	Ceiling Tile 2' x 4'		NAD	1080	SF	0	SF			N/A	N/A	N/A
1	UL	Hallway from Exit Doors by Dean's Office to Room 200	N/A	Concrete Block Wall		Non Suspect ACM	2322	SF	0	SF			N/A	N/A	N/A
1	UL	Hallway from Exit Doors by Dean's Office to Room 200	M	Floor Tile VAT 12" x 12"	8160/01/UL/EE	Assumed	1080	SF	0	SF	Black		1	No	1/D
1	UL	Hallway from Room 200 to Stairwell A-1 near Main Entrance	N/A	Ceiling Tile 2' x 4'		NAD	900	SF	0	SF			N/A	N/A	N/A
1	UL	Hallway from Room 200 to Stairwell A-1 near Main Entrance	N/A	Concrete Block Wall		Non Suspect ACM	1800	SF	0	SF			N/A	N/A	N/A
1	UL	Hallway from Room 200 to Stairwell A-1 near Main Entrance	M	Floor Tile VAT 12" x 12"	8160/01/UL/EE	Assumed	900	SF	0	SF	Black		1	No	1/D
1	UL	Hallway from Stairwell A-1 near Main Entrance to Stairwell near Community Room and Boy's Restroom	N/A	Ceiling Tile 2' x 4'		NAD	900	SF	0	SF			N/A	N/A	N/A
1	UL	Hallway from Stairwell A-1 near Main Entrance to Stairwell near Community Room and Boy's Restroom	N/A	Concrete Block Wall		Non Suspect ACM	1800	SF	0	SF			N/A	N/A	N/A
1	UL	Hallway from Stairwell A-1 near Main Entrance to Stairwell near Community Room and Boy's Restroom	M	Floor Tile VAT 12" x 12"	8160/01/UL/EE	Assumed	900	SF	0	SF	Black		1	No	1/D
1	ML	Auditorium	N/A	Ceiling Tile 3' x 6'		NAD	8085	SF	0	SF			N/A	N/A	N/A
1	ML	Auditorium	N/A	Concrete Block Wall		Non Suspect ACM	7462	SF	0	SF			N/A	N/A	N/A
1	ML	Auditorium	N/A	Carpet		Non Suspect ACM	4851	SF	0	SF			N/A	N/A	N/A
1	ML	Auditorium	N/A	Cement Floor		Non Suspect ACM	3234	SF	0	SF			N/A	N/A	N/A
1	ML	Auditorium Stage	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	15	LF	0	LF			N/A	N/A	N/A
1	ML	Auditorium Stage	N/A	Fiberglass Pipe Fitting Insulation		Non Suspect ACM	8	EA	0	EA			N/A	N/A	N/A
1	ML	Auditorium Stage	N/A	Concrete Ceiling		Non Suspect ACM	2240	SF	0	SF			N/A	N/A	N/A
1	ML	Auditorium Stage	N/A	Concrete Block Wall		Non Suspect ACM	2680	SF	0	SF			N/A	N/A	N/A
1	ML	Auditorium Stage	N/A	Wood Floor		Non Suspect ACM	2240	SF	0	SF			N/A	N/A	N/A
1	ML	Hallway between Auditorium and Main Entrance	N/A	Ceiling Tile 2' x 4'		NAD	550	SF	0	SF			N/A	N/A	N/A
1	ML	Hallway between Auditorium and Main Entrance	N/A	Concrete Block Wall		Non Suspect ACM	756	SF	0	SF			N/A	N/A	N/A
1	ML	Hallway between Auditorium and Main Entrance	M	Floor Tile VAT 12" x 12"	8160/01/ML/DD	Assumed	550	SF	0	SF	Black		1	No	1/D
1	ML	Large Storage Room in Hallway between Auditorium and Main Entrance (Under Stairs)	N/A	Concrete Ceiling		Non Suspect ACM	189	SF	0	SF			N/A	N/A	N/A
1	ML	Large Storage Room in Hallway between Auditorium and Main Entrance (Under Stairs)	N/A	Concrete Block Wall		Non Suspect ACM	600	SF	0	SF			N/A	N/A	N/A
1	ML	Large Storage Room in Hallway between Auditorium and Main Entrance (Under Stairs)	N/A	Cement Floor		Non Suspect ACM	189	SF	0	SF			N/A	N/A	N/A
1	ML	Small Storage Room in Hallway between Auditorium and Main Entrance	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	5	LF	0	LF			N/A	N/A	N/A
1	ML	Small Storage Room in Hallway between Auditorium and Main Entrance	N/A	Fiberglass Pipe Fitting Insulation		Non Suspect ACM	1	EA	0	EA			N/A	N/A	N/A
1	ML	Small Storage Room in Hallway between Auditorium and Main Entrance	N/A	Concrete Ceiling		Non Suspect ACM	36	SF	0	SF			N/A	N/A	N/A
1	ML	Small Storage Room in Hallway between Auditorium and Main Entrance	N/A	Concrete Block Wall		Non Suspect ACM	260	SF	0	SF			N/A	N/A	N/A
1	ML	Small Storage Room in Hallway between Auditorium and Main Entrance	M	Floor Tile VAT 12" x 12"	8160/01/ML/DD	Assumed	36	SF	0	SF	Black		1	No	1/D
1	ML	Computer Lab C	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	3	LF	0	LF			N/A	N/A	N/A
1	ML	Computer Lab C	N/A	Concrete Ceiling		Non Suspect ACM	1575	SF	0	SF			N/A	N/A	N/A
1	ML	Computer Lab C	M	Seam Caulking	8160/01/ML/KEM/PD/260	Assumed	50	SF	0	SF			1	No	1/D
1	ML	Computer Lab C	N/A	Concrete Block Wall		Non Suspect ACM	1760	SF	0	SF			N/A	N/A	N/A
1	ML	Computer Lab C	S	Sheetrock Wall	8160/01/ML/KEM/PD/210	Assumed	140	SF	0	SF			1	No	1/D
1	ML	Computer Lab C	M	Floor Tile VAT 12" x 12"	8160/01/ML/DD	Assumed	1575	SF	0	SF	Grey		1	No	1/D
1	ML	Computer Lab C Storage Room	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	60	LF	0	LF			N/A	N/A	N/A
1	ML	Computer Lab C Storage Room	N/A	Fiberglass Pipe Fitting Insulation		Non Suspect ACM	8	EA	0	EA			N/A	N/A	N/A
1	ML	Computer Lab C Storage Room	N/A	Concrete Ceiling		Non Suspect ACM	320	SF	0	SF			N/A	N/A	N/A
1	ML	Computer Lab C Storage Room	M	Seam Caulking	8160/01/ML/KEM/PD/260	Assumed	9	SF	0	SF			1	No	1/D
1	ML	Computer Lab C Storage Room	N/A	Concrete Block Wall		Non Suspect ACM	792	SF	0	SF			N/A	N/A	N/A
1	ML	Computer Lab C Storage Room	M	Floor Tile VAT 12" x 12"	8160/01/ML/DD	Assumed	320	SF	0	SF	Grey		1	No	1/D
1	ML	Computer Lab C Storage Room in rear of Storage Room	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	40	LF	0	LF			N/A	N/A	N/A
1	ML	Computer Lab C Storage Room in rear of Storage Room	N/A	Fiberglass Pipe Fitting Insulation		Non Suspect ACM	10	EA	0	EA			N/A	N/A	N/A
1	ML	Computer Lab C Storage Room in rear of Storage Room	N/A	Concrete Ceiling		Non Suspect ACM	64	SF	0	SF			N/A	N/A	N/A
1	ML	Computer Lab C Storage Room in rear of Storage Room	M	Seam Caulking	8160/01/ML/KEM/PD/260	Assumed	2	SF	0	SF			1	No	1/D

# 8160 Baldi MS- 2015 2016 AHERA Three-Year Report .xls

1	ML	Computer Lab C Storage Room in rear of Storage Room	N/A	Concrete Block Wall		Non Suspect ACM	352	SF	0	SF			N/A	N/A	N/A
1	ML	Computer Lab C Storage Room in rear of Storage Room	M	Floor Tile VAT 12" x 12"	8160/01/ML/DD	Assumed	64	SF	0	SF	Grey		1	No	1/D
1	ML	Computer Lab A	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	150	LF	0	LF			N/A	N/A	N/A
1	ML	Computer Lab A	N/A	Fiberglass Pipe Fitting Insulation		Non Suspect ACM	21	EA	0	EA			N/A	N/A	N/A
1	ML	Computer Lab A	N/A	Concrete Ceiling		Non Suspect ACM	1500	SF	0	SF			N/A	N/A	N/A
1	ML	Computer Lab A	M	Seam Caulking	8160/01/ML/KEM/PD/2608	Assumed	40	SF	0	SF			1	No	1/D
1	ML	Computer Lab A	N/A	Concrete Block Wall		Non Suspect ACM	1760	SF	0	SF			N/A	N/A	N/A
1	ML	Computer Lab A	M	Floor Tile VAT 12" x 12"	8160/01/ML/DD	Assumed	1500	SF	0	SF	Tan		1	No	1/D
1	ML	Computer Lab A Storage Room in Rear	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	85	LF	0	LF			N/A	N/A	N/A
1	ML	Computer Lab A Storage Room in Rear	N/A	Fiberglass Pipe Fitting Insulation		Non Suspect ACM	18	EA	0	EA			N/A	N/A	N/A
1	ML	Computer Lab A Storage Room in Rear	N/A	Concrete Ceiling		Non Suspect ACM	192	SF	0	SF			N/A	N/A	N/A
1	ML	Computer Lab A Storage Room in Rear	M	Seam Caulking	8160/01/ML/KEM/PD/2608	Assumed	4	SF	0	SF			1	No	1/D
1	ML	Computer Lab A Storage Room in Rear	N/A	Concrete Block Wall		Non Suspect ACM	616	SF	0	SF			N/A	N/A	N/A
1	ML	Computer Lab A Storage Room in Rear	T	Vibration Damper Cloth	8150/01/ML/26	Assumed	1	SF	0	SF			1	No	1/D
1	ML	Computer Lab A Storage Room in Rear	N/A	Vinyl Vibration Damper Cloth		Non Suspect ACM	3	SF	0	SF			N/A	N/A	N/A
1	ML	Computer Lab A Storage Room in Rear	N/A	Cement Floor		Non Suspect ACM	192	SF	0	SF			N/A	N/A	N/A
1	ML	Computer Lab A Storage Room by Entrance	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	10	LF	0	LF			N/A	N/A	N/A
1	ML	Computer Lab A Storage Room by Entrance	N/A	Concrete Ceiling		Non Suspect ACM	80	SF	0	SF			N/A	N/A	N/A
1	ML	Computer Lab A Storage Room by Entrance	M	Seam Caulking	8160/01/ML/KEM/PD/2608	Assumed	2	SF	0	SF			1	No	1/D
1	ML	Computer Lab A Storage Room by Entrance	N/A	Concrete Block Wall		Non Suspect ACM	396	SF	0	SF			N/A	N/A	N/A
1	ML	Computer Lab A Storage Room by Entrance	N/A	Cement Floor		Non Suspect ACM	80	SF	0	SF			N/A	N/A	N/A
1	ML	Men's Restroom and Shower next to Building Engineer's Office	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	40	LF	0	LF		Per Executive Summary; Ceiling Plaster Removal is verified.	N/A	N/A	N/A
1	ML	Men's Restroom and Shower next to Building Engineer's Office	N/A	Fiberglass Pipe Fitting Insulation		Non Suspect ACM	5	EA	0	EA		Per Executive Summary; Ceiling Plaster Removal is verified.	N/A	N/A	N/A
1	ML	Men's Restroom and Shower next to Building Engineer's Office	N/A	Concrete Ceiling		Non Suspect ACM	144	SF	0	SF		Per Executive Summary; Ceiling Plaster Removal is verified.	N/A	N/A	N/A
1	ML	Men's Restroom and Shower next to Building Engineer's Office	M	Seam Caulking	8160/01/ML/KEM/PD/2608	Assumed	3	SF	0	SF		Per Executive Summary; Ceiling Plaster Removal is verified.	1	No	1/D
1	ML	Men's Restroom and Shower next to Building Engineer's Office	N/A	Concrete Block Wall		Non Suspect ACM	528	SF	0	SF		Per Executive Summary; Ceiling Plaster Removal is verified.	N/A	N/A	N/A
1	ML	Men's Restroom and Shower next to Building Engineer's Office	N/A	Cement Floor		Non Suspect ACM	144	SF	0	SF		Per Executive Summary; Ceiling Plaster Removal is verified.	N/A	N/A	N/A
1	ML	Women's Restroom and Shower near Building Engineer's Office	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	50	LF	0	LF			N/A	N/A	N/A
1	ML	Women's Restroom and Shower near Building Engineer's Office	N/A	Fiberglass Pipe Fitting Insulation		Non Suspect ACM	6	EA	0	EA			N/A	N/A	N/A
1	ML	Women's Restroom and Shower near Building Engineer's Office	N/A	Concrete Ceiling		Non Suspect ACM	144	SF	0	SF			N/A	N/A	N/A
1	ML	Women's Restroom and Shower near Building Engineer's Office	M	Seam Caulking	8160/01/ML/KEM/PD/2608	Assumed	3	SF	0	SF		Per Executive Summary; Ceiling Plaster Removal is verified.	1	No	1/D
1	ML	Women's Restroom and Shower near Building Engineer's Office	N/A	Concrete Block Wall		Non Suspect ACM	528	SF	0	SF			N/A	N/A	N/A
1	ML	Women's Restroom and Shower near Building Engineer's Office	N/A	Cement Floor		Non Suspect ACM	144	SF	0	SF			N/A	N/A	N/A
1	ML	Building Engineer's Office	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	15	LF	0	LF		Per Executive Summary; Ceiling Plaster Removal is verified.	N/A	N/A	N/A
1	ML	Building Engineer's Office	N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	84	SF	0	SF		Per Executive Summary; Ceiling Plaster Removal is verified.	N/A	N/A	N/A
1	ML	Building Engineer's Office	N/A	Concrete Block Wall		Non Suspect ACM	304	SF	0	SF		Per Executive Summary; Ceiling Plaster Removal is verified.	N/A	N/A	N/A
1	ML	Building Engineer's Office	N/A	Carpet		Non Suspect ACM	84	SF	0	SF		Per Executive Summary; Ceiling Plaster Removal is verified.	N/A	N/A	N/A
1	ML	Maintenance Staff Office between Building Engineer's Office and Restrooms	N/A	Concrete Ceiling		Non Suspect ACM	104	SF	0	SF			N/A	N/A	N/A
1	ML	Maintenance Staff Office between Building Engineer's Office and Restrooms	M	Seam Caulking	8160/01/ML/KEM/PD/2608	Assumed	4	SF	0	SF			1	No	1/D
1	ML	Maintenance Staff Office between Building Engineer's Office and Restrooms	N/A	Concrete Block Wall		Non Suspect ACM	462	SF	0	SF			N/A	N/A	N/A
1	ML	Maintenance Staff Office between Building Engineer's Office and Restrooms	M	Floor Tile VAT 12" x 12"	8160/01/ML/DD	Assumed	104	SF	0	SF	Orange		1	No	1/D
1	ML	Maintenance Staff Breakroom and Dining Area	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	5	LF	0	LF			N/A	N/A	N/A
1	ML	Maintenance Staff Breakroom and Dining Area	N/A	Fiberglass Pipe Fitting Insulation		Non Suspect ACM	1	EA	0	EA			N/A	N/A	N/A
1	ML	Maintenance Staff Breakroom and Dining Area	N/A	Concrete Ceiling		Non Suspect ACM	84	SF	0	SF			N/A	N/A	N/A
1	ML	Maintenance Staff Breakroom and Dining Area	M	Seam Caulking	8160/01/ML/KEM/PD/2608	Assumed	1	SF	0	SF			1	No	1/D
1	ML	Maintenance Staff Breakroom and Dining Area	N/A	Concrete Block Wall		Non Suspect ACM	418	SF	0	SF			N/A	N/A	N/A
1	ML	Maintenance Staff Breakroom and Dining Area	M	Floor Tile VAT 12" x 12"	8160/01/ML/DD	Assumed	84	SF	0	SF	Orange		1	No	1/D
1	ML	"Ante Room" Maintenance Storage Area next to Loading Dock	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	130	LF	0	LF			N/A	N/A	N/A
1	ML	"Ante Room" Maintenance Storage Area next to Loading Dock	N/A	Fiberglass Pipe Fitting Insulation		Non Suspect ACM	18	EA	0	EA			N/A	N/A	N/A
1	ML	"Ante Room" Maintenance Storage Area next to Loading Dock	N/A	Concrete Ceiling		Non Suspect ACM	425	SF	0	SF			N/A	N/A	N/A
1	ML	"Ante Room" Maintenance Storage Area next to Loading Dock	M	Seam Caulking	8160/01/ML/KEM/PD/2608	Assumed	8	SF	0	SF			1	No	1/D

# 8160 Baldi MS- 2015 2016 AHERA Three-Year Report .xls

1	ML	"Ante Room" Maintenance Storage Area next to Loading Dock	N/A	Concrete Block Wall		Non Suspect ACM	924	SF	0	SF			N/A	N/A	N/A
1	ML	"Ante Room" Maintenance Storage Area next to Loading Dock	N/A	Cement Floor		Non Suspect ACM	425	SF	0	SF			N/A	N/A	N/A
1	ML	Cage Storage Area in "Ante Room"	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	60	LF	0	LF			N/A	N/A	N/A
1	ML	Cage Storage Area in "Ante Room"	N/A	Concrete Ceiling		Non Suspect ACM	400	SF	0	SF			N/A	N/A	N/A
1	ML	Cage Storage Area in "Ante Room"	N/A	Concrete Block Wall		Non Suspect ACM	660	SF	0	SF			N/A	N/A	N/A
1	ML	Cage Storage Area in "Ante Room"	N/A	Cement Floor		Non Suspect ACM	400	SF	0	SF			N/A	N/A	N/A
1	ML	Storage Room with Walk-in Refrigerator and Freezer across from Art Lab A-B	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	80	LF	0	LF			N/A	N/A	N/A
1	ML	Storage Room with Walk-in Refrigerator and Freezer across from Art Lab A-B	N/A	Fiberglass Pipe Fitting Insulation		Non Suspect ACM	9	EA	0	EA			N/A	N/A	N/A
1	ML	Storage Room with Walk-in Refrigerator and Freezer across from Art Lab A-B	N/A	Concrete Ceiling		Non Suspect ACM	400	SF	0	SF			N/A	N/A	N/A
1	ML	Storage Room with Walk-in Refrigerator and Freezer across from Art Lab A-B	N/A	Concrete Block Wall		Non Suspect ACM	880	SF	0	SF			N/A	N/A	N/A
1	ML	Storage Room with Walk-in Refrigerator and Freezer across from Art Lab A-B	N/A	Cement Floor		Non Suspect ACM	400	SF	0	SF			N/A	N/A	N/A
1	ML	Computer Lab B	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	95	LF	0	LF			N/A	N/A	N/A
1	ML	Computer Lab B	N/A	Fiberglass Pipe Fitting Insulation		Non Suspect ACM	11	EA	0	EA			N/A	N/A	N/A
1	ML	Computer Lab B	N/A	Concrete Ceiling		Non Suspect ACM	1480	SF	0	SF			N/A	N/A	N/A
1	ML	Computer Lab B	M	Seam Caulking	8160/01/ML/KEM/PD/2608	Assumed	40	SF	0	SF			1	No	1/D
1	ML	Computer Lab B	N/A	Concrete Block Wall		Non Suspect ACM	1540	SF	0	SF			N/A	N/A	N/A
1	ML	Computer Lab B	M	Floor Tile VAT 12" x 12"	8160/01/ML/DD	Assumed	1480	SF	0	SF	Tan		1	No	1/D
1	ML	Computer Lab B Right Side Storage Room	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	32	LF	0	LF		Per Executive Summary; Ceiling Plaster Removal is verified.	N/A	N/A	N/A
1	ML	Computer Lab B Right Side Storage Room	N/A	Concrete Ceiling		Non Suspect ACM	256	SF	0	SF		Per Executive Summary; Ceiling Plaster Removal is verified.	N/A	N/A	N/A
1	ML	Computer Lab B Right Side Storage Room	M	Seam Caulking	8160/01/ML/KEM/PD/2608	Assumed	6	SF	0	SF		Per Executive Summary; Ceiling Plaster Removal is verified.	1	No	1/D
1	ML	Computer Lab B Right Side Storage Room	N/A	Concrete Block Wall		Non Suspect ACM	704	SF	0	SF		Per Executive Summary; Ceiling Plaster Removal is verified.	N/A	N/A	N/A
1	ML	Computer Lab B Right Side Storage Room	M	Sink Undercoat Mastic	8160/01/ML/KEM/PD/2602	Assumed	6	SF	0	SF		Per Executive Summary; Ceiling Plaster Removal is verified.	1	No	1/D
1	ML	Computer Lab B Right Side Storage Room	M	Floor Tile VAT 12" x 12"	8160/01/ML/DD	Assumed	256	SF	0	SF	Black	Per Executive Summary; Ceiling Plaster Removal is verified.	1	No	1/D
1	ML	Computer Lab B Left Side Storage Room	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	10	LF	0	LF			N/A	N/A	N/A
1	ML	Computer Lab B Left Side Storage Room	N/A	Concrete Ceiling		Non Suspect ACM	130	SF	0	SF			N/A	N/A	N/A
1	ML	Computer Lab B Left Side Storage Room	M	Seam Caulking	8160/01/ML/KEM/PD/2608	Assumed	4	SF	0	SF			1	No	1/D
1	ML	Computer Lab B Left Side Storage Room	N/A	Concrete Block Wall		Non Suspect ACM	506	SF	0	SF			N/A	N/A	N/A
1	ML	Computer Lab B Left Side Storage Room	N/A	Cement Floor		Non Suspect ACM	130	SF	0	SF			N/A	N/A	N/A
1	ML	Music Room - 1	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	2	LF	0	LF			N/A	N/A	N/A
1	ML	Music Room - 1	N/A	Fiberglass Pipe Fitting Insulation		Non Suspect ACM	2	EA	0	EA			N/A	N/A	N/A
1	ML	Music Room - 1	N/A	Concrete Ceiling		Non Suspect ACM	1500	SF	0	SF			N/A	N/A	N/A
1	ML	Music Room - 1	M	Seam Caulking	8160/01/ML/KEM/PD/2608	Assumed	8	SF	0	SF			1	No	1/D
1	ML	Music Room - 1	N/A	Concrete Block Wall		Non Suspect ACM	1300	SF	0	SF			N/A	N/A	N/A
1	ML	Music Room - 1	M	Floor Tile VAT 12" x 12"	8160/01/ML/DD	Assumed	42	SF	0	SF	Grey		1	No	1/D
1	ML	Music Room - 1	N/A	Carpet		Non Suspect ACM	1458	SF	0	SF			N/A	N/A	N/A
1	ML	Music Room - 1 Storage Room in Rear	N/A	Concrete Ceiling		Non Suspect ACM	36	SF	0	SF			N/A	N/A	N/A
1	ML	Music Room - 1 Storage Room in Rear	M	Seam Caulking	8160/01/ML/KEM/PD/2608	Assumed	1	SF	0	SF			1	No	1/D
1	ML	Music Room - 1 Storage Room in Rear	N/A	Concrete Block Wall		Non Suspect ACM	264	SF	0	SF			N/A	N/A	N/A
1	ML	Music Room - 1 Storage Room in Rear	N/A	Cement Floor		Non Suspect ACM	36	SF	0	SF			N/A	N/A	N/A
1	ML	Music Room - 2	N/A	Concrete Ceiling		Non Suspect ACM	1575	SF	0	SF			N/A	N/A	N/A
1	ML	Music Room - 2	M	Seam Caulking	8160/01/ML/KEM/PD/2608	Assumed	24	SF	0	SF			1	No	1/D
1	ML	Music Room - 2	N/A	Concrete Block Wall		Non Suspect ACM	1600	SF	0	SF			N/A	N/A	N/A
1	ML	Music Room - 2	M	Floor Tile VAT 12" x 12"	8160/01/ML/DD	Assumed	1575	SF	0	SF	Blue		1	No	1/D
1	ML	Music Room - 2 Office	N/A	Ceiling Tile 2' x 4'		NAD	176	SF	3	SF			N/A	N/A	N/A
1	ML	Music Room - 2 Office	N/A	Concrete Block Wall		Non Suspect ACM	540	SF	0	SF			N/A	N/A	N/A
1	ML	Music Room - 2 Office	M	Floor Tile VAT 12" x 12"	8160/01/ML/DD	Assumed	176	SF	0	SF	Orange		1	No	1/D
1	ML	Hallway between Instrument Music Practice Rooms	N/A	Ceiling Tile 2' x 4'		NAD	88	SF	0	SF			N/A	N/A	N/A
1	ML	Hallway between Instrument Music Practice Rooms	N/A	Concrete Block Wall		Non Suspect ACM	416	SF	0	SF			N/A	N/A	N/A
1	ML	Hallway between Instrument Music Practice Rooms	S	Sheetrock Wall	8160/01/ML/KEM/PD/2100	Assumed	3	SF	0	SF			1	No	1/D
1	ML	Hallway between Instrument Music Practice Rooms	M	Floor Tile VAT 12" x 12"	8160/01/ML/DD	Assumed	88	SF	0	SF	Orange		1	No	1/D
1	ML	Practice Room (Used for Storage) next to Music Room 2	N/A	Ceiling Tile 2' x 4'		NAD	66	SF	0	SF			N/A	N/A	N/A
1	ML	Practice Room (Used for Storage) next to Music Room 2	N/A	Concrete Block Wall		Non Suspect ACM	272	SF	0	SF			N/A	N/A	N/A
1	ML	Practice Room (Used for Storage) next to Music Room 2	M	Floor Tile VAT 12" x 12"	8160/01/ML/DD	Assumed	66	SF	0	SF	Orange		1	No	1/D
1	ML	Practice Room (Bass Only) near Music Room 2	N/A	Ceiling Tile 2' x 4'		NAD	66	SF	2	SF			N/A	N/A	N/A
1	ML	Practice Room (Bass Only) near Music Room 2	N/A	Concrete Block Wall		Non Suspect ACM	272	SF	0	SF			N/A	N/A	N/A
1	ML	Practice Room (Bass Only) near Music Room 2	M	Floor Tile VAT 12" x 12"	8160/01/ML/DD	Assumed	66	SF	0	SF	Orange		1	No	1/D



# 8160 Baldi MS- 2015 2016 AHERA Three-Year Report .xls

1	ML	Middle Practice Room (Used for Storage)	N/A	Ceiling Tile 2' x 4'		NAD	66	SF	0	SF				N/A	N/A	N/A
1	ML	Middle Practice Room (Used for Storage)	N/A	Concrete Block Wall		Non Suspect ACM	272	SF	0	SF				N/A	N/A	N/A
1	ML	Middle Practice Room (Used for Storage)	M	Floor Tile VAT 12" x 12"	8160/01/ML/DD	Assumed	66	SF	0	SF	Orange			1	No	1/D
1	ML	Right Practice Room next to Instrument Music Room	N/A	Ceiling Tile 2' x 4'		NAD	81	SF	2	SF				N/A	N/A	N/A
1	ML	Right Practice Room next to Instrument Music Room	N/A	Concrete Block Wall		Non Suspect ACM	288	SF	0	SF				N/A	N/A	N/A
1	ML	Right Practice Room next to Instrument Music Room	M	Floor Tile VAT 12" x 12"	8160/01/ML/DD	Assumed	81	SF	0	SF	Orange			1	No	1/D
1	ML	Left Practice Room next to Instrument Music Room	N/A	Ceiling Tile 2' x 4'		NAD	66	SF	0	SF				N/A	N/A	N/A
1	ML	Left Practice Room next to Instrument Music Room	N/A	Concrete Block Wall		Non Suspect ACM	272	SF	0	SF				N/A	N/A	N/A
1	ML	Left Practice Room next to Instrument Music Room	M	Floor Tile VAT 12" x 12"	8160/01/ML/DD	Assumed	66	SF	0	SF	Orange			1	No	1/D
1	ML	Instrument Music Room Drum Room (Sink in Room)	N/A	Ceiling Tile 2' x 4'		NAD	1480	SF	0	SF				N/A	N/A	N/A
1	ML	Instrument Music Room Drum Room (Sink in Room)	N/A	Concrete Block Wall		Non Suspect ACM	1232	SF	0	SF				N/A	N/A	N/A
1	ML	Instrument Music Room Drum Room (Sink in Room)	M	Floor Tile VAT 12" x 12"	8160/01/ML/DD	Assumed	1480	SF	0	SF	Orange			1	No	1/D
1	ML	Instrument Music Room	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	10	LF	0	LF				N/A	N/A	N/A
1	ML	Instrument Music Room	N/A	Fiberglass Pipe Fitting Insulation		Non Suspect ACM	1	EA	0	EA				N/A	N/A	N/A
1	ML	Instrument Music Room	N/A	Ceiling Tile 1' x 1'		NAD	620	SF	20	SF				N/A	N/A	N/A
1	ML	Instrument Music Room	M	Spline Ceiling Tile Glue Dots	8160/01/ML/KEM/PD/2603	Assumed	155	SF	0	SF				1	No	1/D
1	ML	Instrument Music Room	N/A	Concrete Block Wall		Non Suspect ACM	918	SF	0	SF				N/A	N/A	N/A
1	ML	Instrument Music Room	M	Floor Tile VAT 12" x 12"	8160/01/ML/DD	Assumed	620	SF	0	SF	White			1	No	1/D
1	ML	Sprinkler System Room in Stairwell next to Instrument Music Room	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	50	LF	0	LF				N/A	N/A	N/A
1	ML	Sprinkler System Room in Stairwell next to Instrument Music Room	N/A	Fiberglass Pipe Fitting Insulation		Non Suspect ACM	14	EA	0	EA				N/A	N/A	N/A
1	ML	Sprinkler System Room in Stairwell next to Instrument Music Room	N/A	Concrete Ceiling		Non Suspect ACM	100	SF	0	SF				N/A	N/A	N/A
1	ML	Sprinkler System Room in Stairwell next to Instrument Music Room	M	Seam Caulking	8160/01/ML/KEM/PD/2608	Assumed	2	SF	0	SF				1	No	1/D
1	ML	Sprinkler System Room in Stairwell next to Instrument Music Room	N/A	Concrete Block Wall		Non Suspect ACM	880	SF	0	SF				N/A	N/A	N/A
1	ML	Sprinkler System Room in Stairwell next to Instrument Music Room	N/A	Cement Floor		Non Suspect ACM	100	SF	0	SF				N/A	N/A	N/A
1	ML	Stairwell next to Instrument Music Room and Boy's Restroom	N/A	Concrete Ceiling		Non Suspect ACM	448	SF	0	SF				N/A	N/A	N/A
1	ML	Stairwell next to Instrument Music Room and Boy's Restroom	M	Seam Caulking	8160/01/ML/KEM/PD/2608	Assumed	4	SF	0	SF				1	No	1/D
1	ML	Stairwell next to Instrument Music Room and Boy's Restroom	N/A	Concrete Block Wall		Non Suspect ACM	1056	SF	0	SF				N/A	N/A	N/A
1	ML	Stairwell next to Instrument Music Room and Boy's Restroom	T	Radiator Insulation	8160/01/ML/KEM/PD/1600	Assumed	15	SF	0	SF				1	No	1/D
1	ML	Stairwell next to Instrument Music Room and Boy's Restroom	N/A	Cement Floor		Non Suspect ACM	448	SF	0	SF				N/A	N/A	N/A
1	ML	Boy's Restroom	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	50	LF	0	LF				N/A	N/A	N/A
1	ML	Boy's Restroom	N/A	Concrete Ceiling		Non Suspect ACM	247	SF	0	SF				N/A	N/A	N/A
1	ML	Boy's Restroom	M	Seam Caulking	8160/01/ML/KEM/PD/2608	Assumed	4	SF	0	SF				1	No	1/D
1	ML	Boy's Restroom	N/A	Concrete Block Wall		Non Suspect ACM	704	SF	0	SF				N/A	N/A	N/A
1	ML	Boy's Restroom	T	Radiator Insulation	8160/01/ML/KEM/PD/1600	Assumed	12	SF	0	SF				1	No	1/D
1	ML	Boy's Restroom	N/A	Ceramic Tile Floors		Non Suspect ACM	247	SF	0	SF				N/A	N/A	N/A
1	ML	Girl's Restroom	N/A	Concrete Ceiling		Non Suspect ACM	252	SF	0	SF			Per Executive Summary; Ceiling Plaster Removal is verified.	N/A	N/A	N/A
1	ML	Girl's Restroom	M	Seam Caulking	8160/01/ML/KEM/PD/2608	Assumed	4	SF	0	SF				1	No	1/D
1	ML	Girl's Restroom	N/A	Concrete Block Wall		Non Suspect ACM	704	SF	0	SF			Per Executive Summary; Ceiling Plaster Removal is verified.	N/A	N/A	N/A
1	ML	Girl's Restroom	T	Radiator Insulation	8160/01/ML/KEM/PD/1600	Assumed	12	SF	0	SF				1	No	1/D
1	ML	Girl's Restroom	N/A	Ceramic Tile Floors		Non Suspect ACM	252	SF	0	SF			Per Executive Summary; Ceiling Plaster Removal is verified.	N/A	N/A	N/A
1	ML	Women's Restroom	N/A	Concrete Ceiling		Non Suspect ACM	96	SF	0	SF				N/A	N/A	N/A
1	ML	Women's Restroom	M	Seam Caulking	8160/01/ML/KEM/PD/2608	Assumed	2	SF	0	SF				1	No	1/D
1	ML	Women's Restroom	N/A	Concrete Block Wall		Non Suspect ACM	400	SF	0	SF				N/A	N/A	N/A
1	ML	Women's Restroom	N/A	Ceramic Tile Floors		Non Suspect ACM	96	SF	0	SF				N/A	N/A	N/A
1	ML	Custodial Closet next to Women's Restroom	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	100	LF	0	LF			Pipe Chase Located in Room.	N/A	N/A	N/A
1	ML	Custodial Closet next to Women's Restroom	N/A	Fiberglass Pipe Fitting Insulation		Non Suspect ACM	12	EA	0	EA			Pipe Chase Located in Room.	N/A	N/A	N/A
1	ML	Custodial Closet next to Women's Restroom	N/A	Concrete Ceiling		Non Suspect ACM	48	SF	0	SF			Pipe Chase Located in Room.	N/A	N/A	N/A
1	ML	Custodial Closet next to Women's Restroom	M	Seam Caulking	8160/01/ML/KEM/PD/2608	Assumed	1	SF	0	SF				1	No	1/D
1	ML	Custodial Closet next to Women's Restroom	N/A	Concrete Block Wall		Non Suspect ACM	352	SF	0	SF			Pipe Chase Located in Room.	N/A	N/A	N/A
1	ML	Custodial Closet next to Women's Restroom	N/A	Cement Floor		Non Suspect ACM	48	SF	0	SF			Pipe Chase Located in Room.	N/A	N/A	N/A
1	ML	Hallway from Custodial Closet to Girl's Restroom	N/A	Ceiling Tile 2' x 4'		NAD	40	SF	0	SF				N/A	N/A	N/A
1	ML	Hallway from Custodial Closet to Girl's Restroom	N/A	Concrete Block Wall		Non Suspect ACM	224	SF	0	SF				N/A	N/A	N/A

# 8160 Baldi MS- 2015 2016 AHERA Three-Year Report .xls

1	ML	Hallway from Custodial Closet to Girl's Restroom	M	Floor Tile VAT 12" x 12"	8160/01/ML/DD	Assumed	40	SF	0	SF	Black		1	No	1/D
1	ML	Art Lab A-B	N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	3080	SF	0	SF			N/A	N/A	N/A
1	ML	Art Lab A-B	N/A	Concrete Block Wall		Non Suspect ACM	2280	SF	0	SF			N/A	N/A	N/A
1	ML	Art Lab A-B	M	Sink Undercoat Mastic	8160/01/ML/KEM/PD/260 2	Assumed	28	SF	0	SF			1	No	1/D
1	ML	Art Lab A-B	M	Floor Tile VAT 12" x 12"	8160/01/ML/DD	Assumed	3080	SF	0	SF	Tan		1	No	1/D
1	ML	Art Lab A-B Storage Room near Entrance	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	15	LF	0	LF			N/A	N/A	N/A
1	ML	Art Lab A-B Storage Room near Entrance	N/A	Fiberglass Pipe Fitting Insulation		Non Suspect ACM	8	EA	0	EA			N/A	N/A	N/A
1	ML	Art Lab A-B Storage Room near Entrance	N/A	Concrete Ceiling		Non Suspect ACM	108	SF	0	SF			N/A	N/A	N/A
1	ML	Art Lab A-B Storage Room near Entrance	M	Seam Caulking	8160/01/ML/KEM/PD/260 8	Assumed	2	SF	0	SF			1	No	1/D
1	ML	Art Lab A-B Storage Room near Entrance	N/A	Concrete Block Wall		Non Suspect ACM	420	SF	0	SF			N/A	N/A	N/A
1	ML	Art Lab A-B Storage Room near Entrance	N/A	Cement Floor		Non Suspect ACM	108	SF	0	SF			N/A	N/A	N/A
1	ML	Art Lab A-B Storage Room and Klin Room	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	10	LF	0	LF			N/A	N/A	N/A
1	ML	Art Lab A-B Storage Room and Klin Room	N/A	Fiberglass Pipe Fitting Insulation		Non Suspect ACM	1	EA	0	EA			N/A	N/A	N/A
1	ML	Art Lab A-B Storage Room and Klin Room	N/A	Concrete Ceiling		Non Suspect ACM	130	SF	0	SF			N/A	N/A	N/A
1	ML	Art Lab A-B Storage Room and Klin Room	M	Seam Caulking	8160/01/ML/KEM/PD/260 8	Assumed	2	SF	0	SF			1	No	1/D
1	ML	Art Lab A-B Storage Room and Klin Room	N/A	Concrete Block Wall		Non Suspect ACM	460	SF	0	SF			N/A	N/A	N/A
1	ML	Art Lab A-B Storage Room and Klin Room	M	Sink Undercoat Mastic	8160/01/ML/KEM/PD/260 2	Assumed	5	SF	0	SF			1	No	1/D
1	ML	Art Lab A-B Storage Room and Klin Room	M	Floor Tile VAT 12" x 12"	8160/01/ML/DD	Assumed	130	SF	0	SF	Tan		1	No	1/D
1	ML	Art Lab A-B Storage Room third in from Entrance	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	20	LF	0	LF			N/A	N/A	N/A
1	ML	Art Lab A-B Storage Room third in from Entrance	N/A	Fiberglass Pipe Fitting Insulation		Non Suspect ACM	3	EA	0	EA			N/A	N/A	N/A
1	ML	Art Lab A-B Storage Room third in from Entrance	N/A	Concrete Ceiling		Non Suspect ACM	169	SF	0	SF			N/A	N/A	N/A
1	ML	Art Lab A-B Storage Room third in from Entrance	N/A	Concrete Block Wall		Non Suspect ACM	520	SF	0	SF			N/A	N/A	N/A
1	ML	Art Lab A-B Storage Room third in from Entrance	N/A	Cement Floor		Non Suspect ACM	169	SF	0	SF			N/A	N/A	N/A
1	ML	Art Lab A-B Storage Room fourth in from Entrance	N/A	Concrete Ceiling		Non Suspect ACM	143	SF	0	SF			N/A	N/A	N/A
1	ML	Art Lab A-B Storage Room fourth in from Entrance	N/A	Concrete Block Wall		Non Suspect ACM	480	SF	0	SF			N/A	N/A	N/A
1	ML	Art Lab A-B Storage Room fourth in from Entrance	M	Floor Tile VAT 12" x 12"	8160/01/ML/DD	Assumed	143	SF	0	SF	Black		1	No	1/D
1	ML	Art Lab A-B Office	N/A	Concrete Ceiling		Non Suspect ACM	182	SF	0	SF			N/A	N/A	N/A
1	ML	Art Lab A-B Office	N/A	Concrete Block Wall		Non Suspect ACM	540	SF	0	SF			N/A	N/A	N/A
1	ML	Art Lab A-B Office	M	Floor Tile VAT 12" x 12"	8160/01/ML/DD	Assumed	182	SF	0	SF	Tan		1	No	1/D
1	ML	Stairwell C-7 near Art Lab A-B Office	N/A	Ceiling Tile 2' x 4'		NAD	540	SF	0	SF			N/A	N/A	N/A
1	ML	Stairwell C-7 near Art Lab A-B Office	N/A	Concrete Block Wall		Non Suspect ACM	816	SF	0	SF			N/A	N/A	N/A
1	ML	Stairwell C-7 near Art Lab A-B Office	M	Floor Tile VAT 12" x 12"	8160/01/ML/DD	Assumed	540	SF	0	SF	Black		1	No	1/D
1	ML	Storage and Fan Room on Girl's side of Gym	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	30	LF	0	LF			N/A	N/A	N/A
1	ML	Storage and Fan Room on Girl's side of Gym	N/A	Fiberglass Pipe Fitting Insulation		Non Suspect ACM	7	EA	0	EA			N/A	N/A	N/A
1	ML	Storage and Fan Room on Girl's side of Gym	N/A	Concrete Ceiling		Non Suspect ACM	286	SF	0	SF			N/A	N/A	N/A
1	ML	Storage and Fan Room on Girl's side of Gym	N/A	Concrete Block Wall		Non Suspect ACM	770	SF	0	SF			N/A	N/A	N/A
1	ML	Storage and Fan Room on Girl's side of Gym	N/A	Vinyl Vibration Damper Cloth		Non Suspect ACM	17	SF	0	SF			N/A	N/A	N/A
1	ML	Storage and Fan Room on Girl's side of Gym	N/A	Cement Floor		Non Suspect ACM	286	SF	0	SF			N/A	N/A	N/A
1	ML	Gym Office on Girl's side of Gym	N/A	Concrete Ceiling		Non Suspect ACM	210	SF	0	SF			N/A	N/A	N/A
1	ML	Gym Office on Girl's side of Gym	N/A	Concrete Block Wall		Non Suspect ACM	638	SF	0	SF			N/A	N/A	N/A
1	ML	Gym Office on Girl's side of Gym	M	Floor Tile VAT 12" x 12"	8160/01/ML/DD	Assumed	210	SF	0	SF	Orange		1	No	1/D
1	ML	Gym Office Restroom on Girl's side of Gym	N/A	Concrete Ceiling		Non Suspect ACM	96	SF	0	SF			N/A	N/A	N/A
1	ML	Gym Office Restroom on Girl's side of Gym	N/A	Concrete Block Wall		Non Suspect ACM	440	SF	0	SF			N/A	N/A	N/A
1	ML	Gym Office Restroom on Girl's side of Gym	N/A	Ceramic Tile Floors		Non Suspect ACM	96	SF	0	SF			N/A	N/A	N/A
1	ML	Gym Office on Boy's side of Gym	N/A	Concrete Ceiling		Non Suspect ACM	210	SF	0	SF			N/A	N/A	N/A
1	ML	Gym Office on Boy's side of Gym	N/A	Concrete Block Wall		Non Suspect ACM	638	SF	0	SF			N/A	N/A	N/A
1	ML	Gym Office on Boy's side of Gym	M	Floor Tile VAT 12" x 12"	8160/01/ML/DD	Assumed	210	SF	0	SF	Orange		1	No	1/D
1	ML	Gym Office Restroom on Boy's side of Gym	N/A	Concrete Ceiling		Non Suspect ACM	96	SF	0	SF			N/A	N/A	N/A
1	ML	Gym Office Restroom on Boy's side of Gym	N/A	Concrete Block Wall		Non Suspect ACM	440	SF	0	SF			N/A	N/A	N/A
1	ML	Gym Office Restroom on Boy's side of Gym	N/A	Ceramic Tile Floors		Non Suspect ACM	96	SF	0	SF			N/A	N/A	N/A
1	ML	Storage and Fan Room on Boy's side of Gym	N/A	Concrete Ceiling		Non Suspect ACM	286	SF	0	SF			N/A	N/A	N/A
1	ML	Storage and Fan Room on Boy's side of Gym	N/A	Concrete Block Wall		Non Suspect ACM	770	SF	0	SF			N/A	N/A	N/A
1	ML	Storage and Fan Room on Boy's side of Gym	N/A	Vinyl Vibration Damper Cloth		Non Suspect ACM	17	SF	0	SF			N/A	N/A	N/A
1	ML	Storage and Fan Room on Boy's side of Gym	N/A	Cement Floor		Non Suspect ACM	286	SF	0	SF			N/A	N/A	N/A
1	ML	Girl's Gym	N/A	Fiberglass Pipe Fitting Insulation		Non Suspect ACM	1	EA	0	EA			N/A	N/A	N/A
1	ML	Girl's Gym	N/A	Ceiling Tile 3' x 6'		NAD	5376	SF	0	SF			N/A	N/A	N/A
1	ML	Girl's Gym	N/A	Concrete Block Wall		Non Suspect ACM	6032	SF	0	SF			N/A	N/A	N/A
1	ML	Girl's Gym	N/A	Wood Floor		Non Suspect ACM	5376	SF	0	SF			N/A	N/A	N/A
1	ML	Boy's Gym	N/A	Fiberglass Pipe Fitting Insulation		Non Suspect ACM	1	EA	0	EA			N/A	N/A	N/A
1	ML	Boy's Gym	N/A	Ceiling Tile 3' x 6'		NAD	5376	SF	0	SF			N/A	N/A	N/A
1	ML	Boy's Gym	N/A	Concrete Block Wall		Non Suspect ACM	6032	SF	0	SF			N/A	N/A	N/A
1	ML	Boy's Gym	N/A	Wood Floor		Non Suspect ACM	5376	SF	0	SF			N/A	N/A	N/A
1	ML	Hallway and Stairs between Commons Area and Gym	N/A	Ceiling Tile 2' x 4'		NAD	896	SF	0	SF			N/A	N/A	N/A
1	ML	Hallway and Stairs between Commons Area and Gym	N/A	Concrete Block Wall		Non Suspect ACM	1560	SF	0	SF			N/A	N/A	N/A
1	ML	Hallway and Stairs between Commons Area and Gym	M	Floor Tile VAT 12" x 12"	8160/01/ML/DD	Assumed	336	SF	0	SF	Black		1	No	1/D
1	ML	Hallway and Stairs between Commons Area and Gym	N/A	Cement Floor		Non Suspect ACM	560	SF	0	SF			N/A	N/A	N/A

# 8160 Baldi MS- 2015 2016 AHERA Three-Year Report .xls

1	ML	Art Lab C-D	N/A	Ceiling Tile 2' x 4'		NAD	2728	SF	0	SF				N/A	N/A	N/A
1	ML	Art Lab C-D	N/A	Concrete Block Wall		Non Suspect ACM	2120	SF	0	SF				N/A	N/A	N/A
1	ML	Art Lab C-D	M	Sink Undercoat Mastic	8160/01/ML/KEM/PD/260 2	Assumed	27	SF	0	SF				1	No	1/D
1	ML	Art Lab C-D	M	Floor Tile VAT 12" x 12"	8160/01/ML/DD	Assumed	2728	SF	0	SF	Tan			1	No	1/D
1	ML	Art Lab C-D Storage Room near Entrance	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	22	LF	0	LF		No Access; Not Inspected.		N/A	N/A	N/A
1	ML	Art Lab C-D Storage Room near Entrance	N/A	Fiberglass Pipe Fitting		Non Suspect ACM	17	EA	0	EA		No Access; Not Inspected.		N/A	N/A	N/A
1	ML	Art Lab C-D Storage Room near Entrance	N/A	Concrete Ceiling		Non Suspect ACM	140	SF	0	SF		No Access; Not Inspected.		N/A	N/A	N/A
1	ML	Art Lab C-D Storage Room near Entrance	N/A	Concrete Block Wall		Non Suspect ACM	528	SF	0	SF		No Access; Not Inspected.		N/A	N/A	N/A
1	ML	Art Lab C-D Storage Room near Entrance	N/A	Cement Floor		Non Suspect ACM	140	SF	0	SF		No Access; Not Inspected.		N/A	N/A	N/A
1	ML	Art Lab C-D Storage Room and Kiln Room	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	15	LF	0	LF		No Access; Not Inspected.		N/A	N/A	N/A
1	ML	Art Lab C-D Storage Room and Kiln Room	N/A	Fiberglass Pipe Fitting		Non Suspect ACM	3	EA	0	EA		No Access; Not Inspected.		N/A	N/A	N/A
1	ML	Art Lab C-D Storage Room and Kiln Room	N/A	Concrete Ceiling		Non Suspect ACM	99	SF	0	SF		No Access; Not Inspected.		N/A	N/A	N/A
1	ML	Art Lab C-D Storage Room and Kiln Room	N/A	Concrete Block Wall		Non Suspect ACM	440	SF	0	SF		No Access; Not Inspected.		N/A	N/A	N/A
1	ML	Art Lab C-D Storage Room and Kiln Room	M	Sink Undercoat Mastic	8160/01/ML/KEM/PD/260 2	Assumed	5	SF	0	SF		No Access; Not Inspected.		1	No	1/D
1	ML	Art Lab C-D Storage Room and Kiln Room	M	Floor Tile VAT 12" x 12"	8160/01/ML/DD	Assumed	99	SF	0	SF	Tan	No Access; Not Inspected.		1	No	1/D
1	ML	Art Lab C-D Storage Room third in from Entrance	N/A	Concrete Ceiling		Non Suspect ACM	90	SF	0	SF				N/A	N/A	N/A
1	ML	Art Lab C-D Storage Room third in from Entrance	N/A	Concrete Block Wall		Non Suspect ACM	418	SF	0	SF				N/A	N/A	N/A
1	ML	Art Lab C-D Storage Room third in from Entrance	N/A	Cement Floor		Non Suspect ACM	90	SF	0	SF				N/A	N/A	N/A
1	ML	Art Lab C-D Office	N/A	Concrete Ceiling		Non Suspect ACM	168	SF	0	SF				N/A	N/A	N/A
1	ML	Art Lab C-D Office	N/A	Concrete Block Wall		Non Suspect ACM	572	SF	0	SF				N/A	N/A	N/A
1	ML	Art Lab C-D Office	M	Floor Tile VAT 12" x 12"	8160/01/ML/DD	Assumed	168	SF	0	SF	Tan			1	No	1/D
1	ML	Women's Restroom near Art Lab C-D	N/A	Concrete Ceiling		Non Suspect ACM	117	SF	0	SF				N/A	N/A	N/A
1	ML	Women's Restroom near Art Lab C-D	N/A	Concrete Block Wall		Non Suspect ACM	484	SF	0	SF				N/A	N/A	N/A
1	ML	Women's Restroom near Art Lab C-D	N/A	Ceramic Tile Floors		Non Suspect ACM	117	SF	0	SF	Tan			N/A	N/A	N/A
1	ML	Girl's Restroom next to Women's Restroom	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	20	LF	0	LF		Pipe Chase Access in Room.		N/A	N/A	N/A
1	ML	Girl's Restroom next to Women's Restroom	N/A	Fiberglass Pipe Fitting		Non Suspect ACM	1	EA	0	EA		Pipe Chase Access in Room.		N/A	N/A	N/A
1	ML	Girl's Restroom next to Women's Restroom	N/A	Concrete Ceiling		Non Suspect ACM	270	SF	0	SF		Pipe Chase Access in Room.		N/A	N/A	N/A
1	ML	Girl's Restroom next to Women's Restroom	M	Seam Caulking	8160/01/ML/KEM/PD/260 8	Assumed	2	SF	0	SF				1	No	1/D
1	ML	Girl's Restroom next to Women's Restroom	N/A	Concrete Block Wall		Non Suspect ACM	858	SF	0	SF		Pipe Chase Access in Room.		N/A	N/A	N/A
1	ML	Girl's Restroom next to Women's Restroom	N/A	Ceramic Tile Floors		Non Suspect ACM	270	SF	0	SF		Pipe Chase Access in Room.		N/A	N/A	N/A
1	ML	Room 102 Custodial Closet between Girl's Restroom and Men's Restroom	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	50	LF	0	LF		Pipe Chase Access in Room.		N/A	N/A	N/A
1	ML	Room 102 Custodial Closet between Girl's Restroom and Men's Restroom	N/A	Fiberglass Pipe Fitting		Non Suspect ACM	16	EA	0	EA		Pipe Chase Access in Room.		N/A	N/A	N/A
1	ML	Room 102 Custodial Closet between Girl's Restroom and Men's Restroom	N/A	Concrete Ceiling		Non Suspect ACM	24	SF	0	SF		Pipe Chase Access in Room.		N/A	N/A	N/A
1	ML	Room 102 Custodial Closet between Girl's Restroom and Men's Restroom	M	Seam Caulking	8160/01/ML/KEM/PD/260 8	Assumed	1	SF	0	SF				1	No	1/D
1	ML	Room 102 Custodial Closet between Girl's Restroom and Men's Restroom	N/A	Concrete Block Wall		Non Suspect ACM	220	SF	0	SF		Pipe Chase Access in Room.		N/A	N/A	N/A
1	ML	Room 102 Custodial Closet between Girl's Restroom and Men's Restroom	N/A	Cement Floor		Non Suspect ACM	24	SF	0	SF		Pipe Chase Access in Room.		N/A	N/A	N/A
1	ML	Men's Restroom between Custodial Closet and Boy's Restroom	N/A	Concrete Ceiling		Non Suspect ACM	84	SF	0	SF				N/A	N/A	N/A
1	ML	Men's Restroom between Custodial Closet and Boy's Restroom	M	Seam Caulking	8160/01/ML/KEM/PD/260 8	Assumed	2	SF	0	SF				1	No	1/D
1	ML	Men's Restroom between Custodial Closet and Boy's Restroom	N/A	Concrete Block Wall		Non Suspect ACM	418	SF	0	SF				N/A	N/A	N/A
1	ML	Men's Restroom between Custodial Closet and Boy's Restroom	N/A	Ceramic Tile Floors		Non Suspect ACM	84	SF	0	SF				N/A	N/A	N/A
1	ML	Boy's Restroom next to Men's Restroom	N/A	Concrete Ceiling		Non Suspect ACM	264	SF	0	SF				N/A	N/A	N/A
1	ML	Boy's Restroom next to Men's Restroom	M	Seam Caulking	8160/01/ML/KEM/PD/260 8	Assumed	5	SF	0	SF				1	No	1/D
1	ML	Boy's Restroom next to Men's Restroom	N/A	Concrete Block Wall		Non Suspect ACM	748	SF	0	SF				N/A	N/A	N/A
1	ML	Boy's Restroom next to Men's Restroom	N/A	Ceramic Tile Floors		Non Suspect ACM	264	SF	0	SF				N/A	N/A	N/A
1	ML	Teacher's Lounge	N/A	Ceiling Tile 2' x 4'		NAD	364	SF	0	SF				N/A	N/A	N/A
1	ML	Teacher's Lounge	N/A	Concrete Block Wall		Non Suspect ACM	528	SF	0	SF				N/A	N/A	N/A
1	ML	Teacher's Lounge	S	Sheetrock Wall	8160/01/ML/KEM/PD/210 0	Assumed	107	SF	0	SF				1	No	1/D
1	ML	Teacher's Lounge	M	Floor Tile VAT 12" x 12"	8160/01/ML/DD	Assumed	364	SF	0	SF	Brown			1	No	1/D
1	ML	Computer Server Room next to Teacher's Lounge	N/A	Ceiling Tile 2' x 4'		NAD	120	SF	0	SF		No Access; Not Inspected.		N/A	N/A	N/A
1	ML	Computer Server Room next to Teacher's Lounge	N/A	Concrete Block Wall		Non Suspect ACM	176	SF	0	SF		No Access; Not Inspected.		N/A	N/A	N/A
1	ML	Computer Server Room next to Teacher's Lounge	S	Sheetrock Wall	8160/01/ML/KEM/PD/210 0	Assumed	107	SF	0	SF		No Access; Not Inspected.		1	No	1/D
1	ML	Computer Server Room next to Teacher's Lounge	M	Floor Tile VAT 12" x 12"	8160/01/ML/DD	Assumed	120	SF	0	SF	Brown	No Access; Not Inspected.		1	No	1/D
1	ML	Classroom G-101	N/A	Concrete Ceiling		Non Suspect ACM	1160	SF	0	SF				N/A	N/A	N/A
1	ML	Classroom G-101	M	Seam Caulking	8160/01/ML/KEM/PD/260 8	Assumed	17	SF	0	SF				1	No	1/D
1	ML	Classroom G-101	N/A	Concrete Block Wall		Non Suspect ACM	1518	SF	0	SF				N/A	N/A	N/A
1	ML	Classroom G-101	M	Floor Tile VAT 12" x 12"	8160/01/ML/DD	Assumed	1160	SF	0	SF	Orange			1	No	1/D
1	ML	Classroom G-101 Storage Room	N/A	Concrete Ceiling		Non Suspect ACM	72	SF	0	SF				N/A	N/A	N/A
1	ML	Classroom G-101 Storage Room	M	Seam Caulking	8160/01/ML/KEM/PD/260 8	Assumed	1	SF	0	SF				1	No	1/D
1	ML	Classroom G-101 Storage Room	N/A	Concrete Block Wall		Non Suspect ACM	330	SF	0	SF				N/A	N/A	N/A
1	ML	Classroom G-101 Storage Room	M	Floor Tile VAT 12" x 12"	8160/01/ML/DD	Assumed	72	SF	0	SF	Orange			1	No	1/D
1	ML	Stairwell (S-10) next to Classroom G-102	N/A	Concrete Ceiling		Non Suspect ACM	364	SF	0	SF				N/A	N/A	N/A

# 8160 Baldi MS- 2015 2016 AHERA Three-Year Report .xls

1	ML	Stairwell (S-10) next to Classroom G-102	M	Seam Caulking	8160/01/ML/KEM/PD/2608	Assumed	10	SF	0	SF			1	No	1/D
1	ML	Stairwell (S-10) next to Classroom G-102	N/A	Concrete Block Wall		Non Suspect ACM	960	SF	0	SF			N/A	N/A	N/A
1	ML	Stairwell (S-10) next to Classroom G-102	N/A	Cement Floor		Non Suspect ACM	364	SF	0	SF			N/A	N/A	N/A
1	ML	Classroom G-102	N/A	Concrete Ceiling		Non Suspect ACM	660	SF	0	SF			N/A	N/A	N/A
1	ML	Classroom G-102	M	Seam Caulking	8160/01/ML/KEM/PD/2608	Assumed	12	SF	0	SF			1	No	1/D
1	ML	Classroom G-102	N/A	Concrete Block Wall		Non Suspect ACM	572	SF	0	SF			N/A	N/A	N/A
1	ML	Classroom G-102	S	Sheetrock Wall	8160/01/ML/KEM/PD/2100	Assumed	240	SF	0	SF			1	No	1/D
1	ML	Classroom G-102	M	Sink Undercoat Mastic	8160/01/ML/KEM/PD/2602	Assumed	5	SF	0	SF			1	No	1/D
1	ML	Classroom G-102	M	Floor Tile VAT 12" x 12"	8160/01/ML/DD	Assumed	660	SF	0	SF	Tan		1	No	1/D
1	ML	Women's Restroom across from Classroom G-102	N/A	Concrete Ceiling		Non Suspect ACM	140	SF	0	SF			N/A	N/A	N/A
1	ML	Women's Restroom across from Classroom G-102	M	Seam Caulking	8160/01/ML/KEM/PD/2608	Assumed	2	SF	0	SF			1	No	1/D
1	ML	Women's Restroom across from Classroom G-102	N/A	Concrete Block Wall		Non Suspect ACM	528	SF	0	SF			N/A	N/A	N/A
1	ML	Women's Restroom across from Classroom G-102	N/A	Ceramic Tile Floors		Non Suspect ACM	140	SF	0	SF			N/A	N/A	N/A
1	ML	Custodial Closet next to Women's Restroom	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	10	LF	0	LF		Pipe Chase in Room.	N/A	N/A	N/A
1	ML	Custodial Closet next to Women's Restroom	S	Plaster Ceiling	8160/01/ML/25	Confirmed	12	SF	0	SF		Pipe Chase in Room.	1	No	1/D
1	ML	Custodial Closet next to Women's Restroom	N/A	Concrete Block Wall		Non Suspect ACM	88	SF	0	SF		Pipe Chase in Room.	N/A	N/A	N/A
1	ML	Custodial Closet next to Women's Restroom	N/A	Cement Floor		Non Suspect ACM	12	SF	0	SF		Pipe Chase in Room.	N/A	N/A	N/A
1	ML	Classroom G-103	N/A	Concrete Ceiling		Non Suspect ACM	660	SF	0	SF			N/A	N/A	N/A
1	ML	Classroom G-103	M	Seam Caulking	8160/01/ML/KEM/PD/2608	Assumed	12	SF	0	SF			1	No	1/D
1	ML	Classroom G-103	N/A	Concrete Block Wall		Non Suspect ACM	242	SF	0	SF			N/A	N/A	N/A
1	ML	Classroom G-103	S	Sheetrock Wall	8160/01/ML/KEM/PD/2100	Assumed	416	SF	0	SF			1	No	1/D
1	ML	Classroom G-103	M	Floor Tile VAT 12" x 12"	8160/01/ML/DD	Assumed	660	SF	0	SF	Tan		1	No	1/D
1	ML	Classroom G-104	N/A	Concrete Ceiling		Non Suspect ACM	660	SF	0	SF			N/A	N/A	N/A
1	ML	Classroom G-104	M	Seam Caulking	8160/01/ML/KEM/PD/2608	Assumed	12	SF	0	SF			1	No	1/D
1	ML	Classroom G-104	N/A	Concrete Block Wall		Non Suspect ACM	242	SF	0	SF			N/A	N/A	N/A
1	ML	Classroom G-104	S	Sheetrock Wall	8160/01/ML/KEM/PD/2100	Assumed	416	SF	0	SF			1	No	1/D
1	ML	Classroom G-104	M	Floor Tile VAT 12" x 12"	8160/01/ML/DD	Assumed	660	SF	0	SF	Tan		1	No	1/D
1	ML	Classroom G-105	N/A	Concrete Ceiling		Non Suspect ACM	660	SF	0	SF			N/A	N/A	N/A
1	ML	Classroom G-105	M	Seam Caulking	8160/01/ML/KEM/PD/2608	Assumed	12	SF	0	SF			1	No	1/D
1	ML	Classroom G-105	N/A	Concrete Block Wall		Non Suspect ACM	572	SF	0	SF			N/A	N/A	N/A
1	ML	Classroom G-105	S	Sheetrock Wall	8160/01/ML/KEM/PD/2100	Assumed	240	SF	0	SF			1	No	1/D
1	ML	Classroom G-105	M	Sink Undercoat Mastic	8160/01/ML/KEM/PD/2602	Assumed	5	SF	0	SF			1	No	1/D
1	ML	Classroom G-105	M	Floor Tile VAT 12" x 12"	8160/01/ML/DD	Assumed	660	SF	0	SF	Tan		1	No	1/D
1	ML	Classroom Y-105	N/A	Concrete Ceiling		Non Suspect ACM	660	SF	0	SF			N/A	N/A	N/A
1	ML	Classroom Y-105	M	Seam Caulking	8160/01/ML/KEM/PD/2608	Assumed	12	SF	0	SF			1	No	1/D
1	ML	Classroom Y-105	N/A	Concrete Block Wall		Non Suspect ACM	572	SF	0	SF			N/A	N/A	N/A
1	ML	Classroom Y-105	S	Sheetrock Wall	8160/01/ML/KEM/PD/2100	Assumed	240	SF	0	SF			1	No	1/D
1	ML	Classroom Y-105	M	Floor Tile VAT 12" x 12"	8160/01/ML/DD	Assumed	660	SF	0	SF	Tan		1	No	1/D
1	ML	Boy's Restroom across from Classroom Y-104	N/A	Concrete Ceiling		Non Suspect ACM	140	SF	0	SF			N/A	N/A	N/A
1	ML	Boy's Restroom across from Classroom Y-104	M	Seam Caulking	8160/01/ML/KEM/PD/2608	Assumed	3	SF	0	SF			1	No	1/D
1	ML	Boy's Restroom across from Classroom Y-104	N/A	Concrete Block Wall		Non Suspect ACM	528	SF	0	SF			N/A	N/A	N/A
1	ML	Boy's Restroom across from Classroom Y-104	N/A	Ceramic Tile Floors		Non Suspect ACM	140	SF	0	SF			N/A	N/A	N/A
1	ML	Classroom Y-104	N/A	Concrete Ceiling		Non Suspect ACM	660	SF	0	SF			N/A	N/A	N/A
1	ML	Classroom Y-104	M	Seam Caulking	8160/01/ML/KEM/PD/2608	Assumed	12	SF	0	SF			1	No	1/D
1	ML	Classroom Y-104	N/A	Concrete Block Wall		Non Suspect ACM	242	SF	0	SF			N/A	N/A	N/A
1	ML	Classroom Y-104	S	Sheetrock Wall	8160/01/ML/KEM/PD/2100	Assumed	416	SF	0	SF			1	No	1/D
1	ML	Classroom Y-104	M	Sink Undercoat Mastic	8160/01/ML/KEM/PD/2602	Assumed	4	SF	0	SF			1	No	1/D
1	ML	Classroom Y-104	M	Floor Tile VAT 12" x 12"	8160/01/ML/DD	Assumed	660	SF	0	SF	Tan		1	No	1/D
1	ML	Classroom Y-103	N/A	Concrete Ceiling		Non Suspect ACM	660	SF	0	SF			N/A	N/A	N/A
1	ML	Classroom Y-103	M	Seam Caulking	8160/01/ML/KEM/PD/2608	Assumed	12	SF	0	SF			1	No	1/D
1	ML	Classroom Y-103	N/A	Concrete Block Wall		Non Suspect ACM	242	SF	0	SF			N/A	N/A	N/A
1	ML	Classroom Y-103	S	Sheetrock Wall	8160/01/ML/KEM/PD/2100	Assumed	416	SF	0	SF			1	No	1/D
1	ML	Classroom Y-103	M	Sink Undercoat Mastic	8160/01/ML/KEM/PD/2602	Assumed	4	SF	0	SF			1	No	1/D
1	ML	Classroom Y-103	M	Floor Tile VAT 12" x 12"	8160/01/ML/DD	Assumed	660	SF	0	SF	Tan		1	No	1/D
1	ML	Classroom Y-102	N/A	Concrete Ceiling		Non Suspect ACM	660	SF	0	SF			N/A	N/A	N/A
1	ML	Classroom Y-102	M	Seam Caulking	8160/01/ML/KEM/PD/2608	Assumed	12	SF	0	SF			1	No	1/D
1	ML	Classroom Y-102	N/A	Concrete Block Wall		Non Suspect ACM	572	SF	0	SF			N/A	N/A	N/A
1	ML	Classroom Y-102	S	Sheetrock Wall	8160/01/ML/KEM/PD/2100	Assumed	240	SF	0	SF			1	No	1/D
1	ML	Classroom Y-102	M	Floor Tile VAT 12" x 12"	8160/01/ML/DD	Assumed	660	SF	0	SF	Tan		1	No	1/D

# 8160 Baldi MS- 2015 2016 AHERA Three-Year Report .xls

1	ML	Classroom Y-101	N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	1160	SF	0	SF				N/A	N/A	N/A
1	ML	Classroom Y-101	N/A	Concrete Block Wall		Non Suspect ACM	1380	SF	0	SF				N/A	N/A	N/A
1	ML	Classroom Y-101	M	Floor Tile VAT 12" x 12"	8160/01/ML/DD	Assumed	1160	SF	0	SF	Orange			1	No	1/D
1	ML	Classroom Y-101 Storage Room	N/A	Concrete Ceiling		Non Suspect ACM	72	SF	0	SF			No Access; Not Inspected.	N/A	N/A	N/A
1	ML	Classroom Y-101 Storage Room	N/A	Concrete Block Wall		Non Suspect ACM	396	SF	0	SF			No Access; Not Inspected.	N/A	N/A	N/A
1	ML	Classroom Y-101 Storage Room	M	Floor Tile VAT 12" x 12"	8160/01/ML/DD	Assumed	72	SF	0	SF	Orange		No Access; Not Inspected.	1	No	1/D
1	ML	Classroom H-101	N/A	Ceiling Tile 2' x 4'		NAD	1680	SF	0	SF				N/A	N/A	N/A
1	ML	Classroom H-101	N/A	Concrete Block Wall		Non Suspect ACM	1720	SF	0	SF				N/A	N/A	N/A
1	ML	Classroom H-101	M	Floor Tile VAT 12" x 12"	8160/01/ML/DD	Assumed	1680	SF	0	SF	Blue			1	No	1/D
1	ML	Hallway from Classroom H-101 to Classroom O-101	N/A	Ceiling Tile 2' x 4'		NAD	234	SF	1	SF				N/A	N/A	N/A
1	ML	Hallway from Classroom H-101 to Classroom O-101	N/A	Concrete Block Wall		Non Suspect ACM	549	SF	0	SF				N/A	N/A	N/A
1	ML	Hallway from Classroom H-101 to Classroom O-101	M	Floor Tile VAT 12" x 12"	8160/01/ML/DD	Assumed	234	SF	0	SF	Black			1	No	1/D
1	ML	Stairwell near Classrooms Y-101 and O-101	N/A	Concrete Ceiling		Non Suspect ACM	336	SF	0	SF				N/A	N/A	N/A
1	ML	Stairwell near Classrooms Y-101 and O-101	M	Seam Caulking	8160/01/ML/KEM/PD/2608	Assumed	6	SF	0	SF				1	No	1/D
1	ML	Stairwell near Classrooms Y-101 and O-101	N/A	Concrete Block Wall		Non Suspect ACM	1520	SF	0	SF				N/A	N/A	N/A
1	ML	Stairwell near Classrooms Y-101 and O-101	N/A	Cement Floor		Non Suspect ACM	336	SF	0	SF				N/A	N/A	N/A
1	ML	Hallway from Classroom H-101 to Classroom Y-101	N/A	Ceiling Tile 2' x 4'		NAD	234	SF	0	SF				N/A	N/A	N/A
1	ML	Hallway from Classroom H-101 to Classroom Y-101	N/A	Concrete Block Wall		Non Suspect ACM	550	SF	0	SF				N/A	N/A	N/A
1	ML	Hallway from Classroom H-101 to Classroom Y-101	M	Floor Tile VAT 12" x 12"	8160/01/ML/DD	Assumed	234	SF	0	SF	Black			1	No	1/D
1	ML	Classroom O-101	N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	1160	SF	0	SF				N/A	N/A	N/A
1	ML	Classroom O-101	N/A	Concrete Block Wall		Non Suspect ACM	1518	SF	0	SF				N/A	N/A	N/A
1	ML	Classroom O-101	M	Floor Tile VAT 12" x 12"	8160/01/ML/DD	Assumed	1160	SF	0	SF	Orange			1	No	1/D
1	ML	Classroom O-101 Storage Room	S	Plaster Ceiling	8160/01/ML/25	Confirmed	72	SF	0	SF				1	No	1/D
1	ML	Classroom O-101 Storage Room	N/A	Concrete Block Wall		Non Suspect ACM	396	SF	0	SF				N/A	N/A	N/A
1	ML	Classroom O-101 Storage Room	M	Floor Tile VAT 12" x 12"	8160/01/ML/DD	Assumed	72	SF	0	SF	Orange			1	No	1/D
1	ML	Classroom O-102	N/A	Concrete Ceiling		Non Suspect ACM	660	SF	0	SF				N/A	N/A	N/A
1	ML	Classroom O-102	M	Seam Caulking	8160/01/ML/KEM/PD/2608	Assumed	13	SF	0	SF				1	No	1/D
1	ML	Classroom O-102	N/A	Concrete Block Wall		Non Suspect ACM	600	SF	0	SF				N/A	N/A	N/A
1	ML	Classroom O-102	N/A	Partition Room Dividers		Non Suspect ACM	300	SF	0	SF				N/A	N/A	N/A
1	ML	Classroom O-102	M	Floor Tile VAT 12" x 12"	8160/01/ML/DD	Assumed	660	SF	0	SF	Tan			1	No	1/D
1	ML	Classroom O-103	N/A	Concrete Ceiling		Non Suspect ACM	660	SF	0	SF				N/A	N/A	N/A
1	ML	Classroom O-103	M	Seam Caulking	8160/01/ML/KEM/PD/2608	Assumed	12	SF	0	SF				1	No	1/D
1	ML	Classroom O-103	N/A	Concrete Block Wall		Non Suspect ACM	300	SF	0	SF				N/A	N/A	N/A
1	ML	Classroom O-103	N/A	Partition Room Dividers		Non Suspect ACM	600	SF	0	SF				N/A	N/A	N/A
1	ML	Classroom O-103	M	Sink Undercoat Mastic	8160/01/ML/KEM/PD/2602	Assumed	4	SF	0	SF				1	No	1/D
1	ML	Classroom O-103	M	Floor Tile VAT 12" x 12"	8160/01/ML/DD	Assumed	660	SF	0	SF	Tan			1	No	1/D
1	ML	Classroom O-104	N/A	Concrete Ceiling		Non Suspect ACM	660	SF	0	SF				N/A	N/A	N/A
1	ML	Classroom O-104	M	Seam Caulking	8160/01/ML/KEM/PD/2608	Assumed	12	SF	0	SF				1	No	1/D
1	ML	Classroom O-104	N/A	Concrete Block Wall		Non Suspect ACM	300	SF	0	SF				N/A	N/A	N/A
1	ML	Classroom O-104	N/A	Partition Room Dividers		Non Suspect ACM	600	SF	0	SF				N/A	N/A	N/A
1	ML	Classroom O-104	M	Sink Undercoat Mastic	8160/01/ML/KEM/PD/2602	Assumed	4	SF	0	SF				1	No	1/D
1	ML	Classroom O-104	M	Floor Tile VAT 12" x 12"	8160/01/ML/DD	Assumed	660	SF	0	SF	Tan			1	No	1/D
1	ML	Classroom O-105	N/A	Concrete Ceiling		Non Suspect ACM	660	SF	0	SF				N/A	N/A	N/A
1	ML	Classroom O-105	M	Seam Caulking	8160/01/ML/KEM/PD/2608	Assumed	12	SF	0	SF				1	No	1/D
1	ML	Classroom O-105	N/A	Concrete Block Wall		Non Suspect ACM	600	SF	0	SF				N/A	N/A	N/A
1	ML	Classroom O-105	N/A	Partition Room Dividers		Non Suspect ACM	300	SF	0	SF				N/A	N/A	N/A
1	ML	Classroom O-105	M	Floor Tile VAT 12" x 12"	8160/01/ML/DD	Assumed	660	SF	0	SF	Tan			1	No	1/D
1	ML	Classroom B-105	N/A	Concrete Ceiling		Non Suspect ACM	660	SF	0	SF				N/A	N/A	N/A
1	ML	Classroom B-105	M	Seam Caulking	8160/01/ML/KEM/PD/2608	Assumed	12	SF	0	SF				1	No	1/D
1	ML	Classroom B-105	N/A	Concrete Block Wall		Non Suspect ACM	600	SF	0	SF				N/A	N/A	N/A
1	ML	Classroom B-105	N/A	Partition Room Dividers		Non Suspect ACM	300	SF	0	SF				N/A	N/A	N/A
1	ML	Classroom B-105	M	Sink Undercoat Mastic	8160/01/ML/KEM/PD/2602	Assumed	4	SF	0	SF				1	No	1/D
1	ML	Classroom B-105	M	Floor Tile VAT 12" x 12"	8160/01/ML/DD	Assumed	660	SF	0	SF	Tan			1	No	1/D
1	ML	Classroom B-104	N/A	Concrete Ceiling		Non Suspect ACM	660	SF	0	SF				N/A	N/A	N/A
1	ML	Classroom B-104	M	Seam Caulking	8160/01/ML/KEM/PD/2608	Assumed	12	SF	0	SF				1	No	1/D
1	ML	Classroom B-104	N/A	Concrete Block Wall		Non Suspect ACM	300	SF	0	SF				N/A	N/A	N/A
1	ML	Classroom B-104	N/A	Partition Room Dividers		Non Suspect ACM	600	SF	0	SF				N/A	N/A	N/A
1	ML	Classroom B-104	M	Floor Tile VAT 12" x 12"	8160/01/ML/DD	Assumed	660	SF	0	SF	Tan			1	No	1/D
1	ML	Classroom B-103	N/A	Concrete Ceiling		Non Suspect ACM	660	SF	0	SF				N/A	N/A	N/A
1	ML	Classroom B-103	M	Seam Caulking	8160/01/ML/KEM/PD/2608	Assumed	12	SF	0	SF				1	No	1/D
1	ML	Classroom B-103	N/A	Concrete Block Wall		Non Suspect ACM	300	SF	0	SF				N/A	N/A	N/A
1	ML	Classroom B-103	N/A	Partition Room Dividers		Non Suspect ACM	600	SF	0	SF				N/A	N/A	N/A
1	ML	Classroom B-103	M	Floor Tile VAT 12" x 12"	8160/01/ML/DD	Assumed	660	SF	0	SF	Tan			1	No	1/D
1	ML	Men's Restroom across from Classroom O-104	N/A	Concrete Ceiling		Non Suspect ACM	140	SF	0	SF				N/A	N/A	N/A

# 8160 Baldi MS- 2015 2016 AHERA Three-Year Report .xls

1	ML	Men's Restroom across from Classroom O-104	M	Seam Caulking	8160/01/ML/KEM/PD/2608	Assumed	2	SF	0	SF				1	No	1/D
1	ML	Men's Restroom across from Classroom O-104	N/A	Concrete Block Wall		Non Suspect ACM	528	SF	0	SF				N/A	N/A	N/A
1	ML	Men's Restroom across from Classroom O-104	N/A	Ceramic Tile Floors		Non Suspect ACM	140	SF	0	SF				N/A	N/A	N/A
1	ML	Women's Restroom near Classroom B-102	N/A	Concrete Ceiling		Non Suspect ACM	140	SF	0	SF				N/A	N/A	N/A
1	ML	Women's Restroom near Classroom B-102	M	Seam Caulking	8160/01/ML/KEM/PD/2608	Assumed	3	SF	0	SF				1	No	1/D
1	ML	Women's Restroom near Classroom B-102	N/A	Concrete Block Wall		Non Suspect ACM	528	SF	0	SF				N/A	N/A	N/A
1	ML	Women's Restroom near Classroom B-102	N/A	Ceramic Tile Floors		Non Suspect ACM	140	SF	0	SF				N/A	N/A	N/A
1	ML	Classroom B-102	N/A	Concrete Ceiling		Non Suspect ACM	660	SF	0	SF				N/A	N/A	N/A
1	ML	Classroom B-102	M	Seam Caulking	8160/01/ML/KEM/PD/2608	Assumed	12	SF	0	SF				1	No	1/D
1	ML	Classroom B-102	N/A	Concrete Block Wall		Non Suspect ACM	600	SF	0	SF				N/A	N/A	N/A
1	ML	Classroom B-102	N/A	Partition Room Dividers		Non Suspect ACM	300	SF	0	SF				N/A	N/A	N/A
1	ML	Classroom B-102	M	Sink Undercoat Mastic	8160/01/ML/KEM/PD/2602	Assumed	4	SF	0	SF				1	No	1/D
1	ML	Classroom B-102	M	Floor Tile VAT 12" x 12"	8160/01/ML/DD	Assumed	660	SF	0	SF	Tan			1	No	1/D
1	ML	Stairwell next to Classroom B-102	N/A	Concrete Ceiling		Non Suspect ACM	364	SF	0	SF				N/A	N/A	N/A
1	ML	Stairwell next to Classroom B-102	M	Seam Caulking	8160/01/ML/KEM/PD/2608	Assumed	10	SF	0	SF				1	No	1/D
1	ML	Stairwell next to Classroom B-102	N/A	Concrete Block Wall		Non Suspect ACM	960	SF	0	SF				N/A	N/A	N/A
1	ML	Stairwell next to Classroom B-102	N/A	Cement Floor		Non Suspect ACM	364	SF	0	SF				N/A	N/A	N/A
1	ML	Classroom B-101	N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	1160	SF	0	SF				N/A	N/A	N/A
1	ML	Classroom B-101	N/A	Concrete Block Wall		Non Suspect ACM	1200	SF	0	SF				N/A	N/A	N/A
1	ML	Classroom B-101	M	Floor Tile VAT 12" x 12"	8160/01/ML/DD	Assumed	1160	SF	0	SF	Orange			1	No	1/D
1	ML	Classroom B-101 Storage Room	N/A	Concrete Ceiling		Non Suspect ACM	72	SF	0	SF				N/A	N/A	N/A
1	ML	Classroom B-101 Storage Room	M	Seam Caulking	8160/01/ML/KEM/PD/2608	Assumed	2	SF	0	SF				1	No	1/D
1	ML	Classroom B-101 Storage Room	N/A	Concrete Block Wall		Non Suspect ACM	330	SF	0	SF				N/A	N/A	N/A
1	ML	Classroom B-101 Storage Room	M	Floor Tile VAT 12" x 12"	8160/01/ML/DD	Assumed	72	SF	0	SF	Orange			1	No	1/D
1	ML	Food Service Manager's Office	N/A	Concrete Ceiling		Non Suspect ACM	91	SF	0	SF		No Access; Not Inspected.		N/A	N/A	N/A
1	ML	Food Service Manager's Office	N/A	Concrete Block Wall		Non Suspect ACM	440	SF	0	SF		No Access; Not Inspected.		N/A	N/A	N/A
1	ML	Food Service Manager's Office	M	Floor Tile VAT 12" x 12"	8160/01/ML/DD	Assumed	91	SF	0	SF	Black			1	No	1/D
1	ML	Food Service Manager's Office Restroom	N/A	Concrete Ceiling		Non Suspect ACM	30	SF	0	SF		No Access; Not Inspected.		N/A	N/A	N/A
1	ML	Food Service Manager's Office Restroom	N/A	Concrete Block Wall		Non Suspect ACM	242	SF	0	SF		No Access; Not Inspected.		N/A	N/A	N/A
1	ML	Food Service Manager's Office Restroom	N/A	Ceramic Tile Floors		Non Suspect ACM	30	SF	0	SF		No Access; Not Inspected.		N/A	N/A	N/A
1	ML	Storage Room next to Food Service Manager's Office	S	Plaster Ceiling	8160/01/ML/25	Confirmed	128	SF	0	SF		No Access; Not Inspected.		1	No	1/D
1	ML	Storage Room next to Food Service Manager's Office	N/A	Concrete Block Wall		Non Suspect ACM	528	SF	0	SF		No Access; Not Inspected.		N/A	N/A	N/A
1	ML	Storage Room next to Food Service Manager's Office	N/A	Cement Floor		Non Suspect ACM	128	SF	0	SF		No Access; Not Inspected.		N/A	N/A	N/A
1	ML	Kitchen Pantry A for the Blue and Green Cafeterias	N/A	Concrete Ceiling		Non Suspect ACM	306	SF	0	SF				N/A	N/A	N/A
1	ML	Kitchen Pantry A for the Blue and Green Cafeterias	M	Seam Caulking	8160/01/ML/KEM/PD/2608	Assumed	14	SF	0	SF				1	No	1/D
1	ML	Kitchen Pantry A for the Blue and Green Cafeterias	N/A	Concrete Block Wall		Non Suspect ACM	560	SF	0	SF				N/A	N/A	N/A
1	ML	Kitchen Pantry A for the Blue and Green Cafeterias	M	Floor Tile VAT 12" x 12"	8160/01/ML/DD	Assumed	306	SF	0	SF	Tan			1	No	1/D
1	ML	Green Cafeteria	N/A	Ceiling Tile 1' x 1'		NAD	1082	SF	0	SF				N/A	N/A	N/A
1	ML	Green Cafeteria	M	Spline Ceiling Tile Glue Dots	8160/01/ML/KEM/PD/2603	Assumed	108	SF	0	SF				1	No	1/D
1	ML	Green Cafeteria	N/A	Ceiling Tile 2' x 4'		NAD	816	SF	0	SF				N/A	N/A	N/A
1	ML	Green Cafeteria	N/A	Concrete Block Wall		Non Suspect ACM	2232	SF	0	SF				N/A	N/A	N/A
1	ML	Green Cafeteria	M	Floor Tile VAT 12" x 12"	8160/01/ML/DD	Assumed	2150	SF	0	SF	Tan			1	No	1/D
1	ML	Yellow Cafeteria	N/A	Ceiling Tile 1' x 1'		NAD	1082	SF	0	SF				N/A	N/A	N/A
1	ML	Yellow Cafeteria	M	Spline Ceiling Tile Glue Dots	8160/01/ML/KEM/PD/2603	Assumed	108	SF	0	SF				1	No	1/D
1	ML	Yellow Cafeteria	N/A	Ceiling Tile 2' x 4'		NAD	816	SF	0	SF				N/A	N/A	N/A
1	ML	Yellow Cafeteria	N/A	Concrete Block Wall		Non Suspect ACM	2232	SF	0	SF				N/A	N/A	N/A
1	ML	Yellow Cafeteria	M	Floor Tile VAT 12" x 12"	8160/01/ML/DD	Assumed	2150	SF	10	SF	Tan			1	No	1/C
1	ML	Kitchen Pantry B for the Orange and Yellow Cafeterias	N/A	Concrete Ceiling		Non Suspect ACM	306	SF	0	SF				N/A	N/A	N/A
1	ML	Kitchen Pantry B for the Orange and Yellow Cafeterias	M	Seam Caulking	8160/01/ML/KEM/PD/2608	Assumed	14	SF	0	SF				1	No	1/D
1	ML	Kitchen Pantry B for the Orange and Yellow Cafeterias	N/A	Concrete Block Wall		Non Suspect ACM	560	SF	0	SF				N/A	N/A	N/A
1	ML	Kitchen Pantry B for the Orange and Yellow Cafeterias	M	Floor Tile VAT 12" x 12"	8160/01/ML/DD	Assumed	306	SF	0	SF	Tan			1	No	1/D
1	ML	Orange Cafeteria	N/A	Ceiling Tile 1' x 1'		NAD	1082	SF	0	SF				N/A	N/A	N/A
1	ML	Orange Cafeteria	M	Spline Ceiling Tile Glue Dots	8160/01/ML/KEM/PD/2603	Assumed	108	SF	0	SF				1	No	1/D
1	ML	Orange Cafeteria	N/A	Ceiling Tile 2' x 4'		NAD	816	SF	0	SF				N/A	N/A	N/A
1	ML	Orange Cafeteria	N/A	Concrete Block Wall		Non Suspect ACM	2232	SF	0	SF				N/A	N/A	N/A
1	ML	Orange Cafeteria	M	Floor Tile VAT 12" x 12"	8160/01/ML/DD	Assumed	2150	SF	0	SF	Tan			1	No	1/D
1	ML	Blue Cafeteria	N/A	Ceiling Tile 1' x 1'		NAD	1082	SF	0	SF				N/A	N/A	N/A
1	ML	Blue Cafeteria	M	Spline Ceiling Tile Glue Dots	8160/01/ML/KEM/PD/2603	Assumed	108	SF	0	SF				1	No	1/D
1	ML	Blue Cafeteria	N/A	Ceiling Tile 2' x 4'		NAD	816	SF	0	SF				N/A	N/A	N/A
1	ML	Blue Cafeteria	N/A	Concrete Block Wall		Non Suspect ACM	2232	SF	0	SF				N/A	N/A	N/A
1	ML	Blue Cafeteria	M	Floor Tile VAT 12" x 12"	8160/01/ML/DD	Assumed	2150	SF	10	SF	Tan			1	No	1/C

# 8160 Baldi MS- 2015 2016 AHERA Three-Year Report .xls

1	ML	Hallway from Teacher's Lounge to Classroom G-104	N/A	Ceiling Tile 2' x 4'		NAD	1845	SF	0	SF			N/A	N/A	N/A
1	ML	Hallway from Teacher's Lounge to Classroom G-104	N/A	Concrete Block Wall		Non Suspect ACM	2214	SF	0	SF			N/A	N/A	N/A
1	ML	Hallway from Teacher's Lounge to Classroom G-104	M	Floor Tile VAT 12" x 12"	8160/01/ML/DD	Assumed	1845	SF	0	SF	Black		1	No	1/D
1	ML	Hallway from Classroom G-105 to Kitchen Pantry B	N/A	Ceiling Tile 2' x 4'		NAD	1200	SF	2	SF			N/A	N/A	N/A
1	ML	Hallway from Classroom G-105 to Kitchen Pantry B	N/A	Concrete Block Wall		Non Suspect ACM	1800	SF	0	SF			N/A	N/A	N/A
1	ML	Hallway from Classroom G-105 to Kitchen Pantry B	M	Floor Tile VAT 12" x 12"	8160/01/ML/DD	Assumed	1200	SF	0	SF	Black		1	No	1/D
1	ML	Hallway from Classroom Y-101 to Classroom O-101	N/A	Ceiling Tile 2' x 4'		NAD	1155	SF	0	SF			N/A	N/A	N/A
1	ML	Hallway from Classroom Y-101 to Classroom O-101	N/A	Concrete Block Wall		Non Suspect ACM	990	SF	0	SF			N/A	N/A	N/A
1	ML	Hallway from Classroom Y-101 to Classroom O-101	M	Floor Tile VAT 12" x 12"	8160/01/ML/DD	Assumed	1155	SF	0	SF	Black		1	No	1/D
1	ML	Hallway from Lockers near Classroom O-102 to Classroom B-105	N/A	Ceiling Tile 2' x 4'		NAD	882	SF	0	SF			N/A	N/A	N/A
1	ML	Hallway from Lockers near Classroom O-102 to Classroom B-105	N/A	Concrete Block Wall		Non Suspect ACM	1764	SF	0	SF			N/A	N/A	N/A
1	ML	Hallway from Lockers near Classroom O-102 to Classroom B-105	M	Floor Tile VAT 12" x 12"	8160/01/ML/DD	Assumed	882	SF	0	SF	Black		1	No	1/D
1	ML	Hallway from Classroom B-104 to Storage Room next to Food Service Manager's Office	N/A	Ceiling Tile 2' x 4'		NAD	1800	SF	0	SF			N/A	N/A	N/A
1	ML	Hallway from Classroom B-104 to Storage Room next to Food Service Manager's Office	N/A	Concrete Block Wall		Non Suspect ACM	2160	SF	0	SF			N/A	N/A	N/A
1	ML	Hallway from Classroom B-104 to Storage Room next to Food Service Manager's Office	M	Floor Tile VAT 12" x 12"	8160/01/ML/DD	Assumed	1800	SF	0	SF	Black		1	No	1/D
1	ML	Stairwell and Hallway around Stairwell between Art Lab C-D and Boy's Restroom	N/A	Ceiling Tile 2' x 4'		NAD	1100	SF	0	SF			N/A	N/A	N/A
1	ML	Stairwell and Hallway around Stairwell between Art Lab C-D and Boy's Restroom	N/A	Concrete Block Wall		Non Suspect ACM	1242	SF	0	SF			N/A	N/A	N/A
1	ML	Stairwell and Hallway around Stairwell between Art Lab C-D and Boy's Restroom	M	Floor Tile VAT 12" x 12"	8160/01/ML/DD	Assumed	1100	SF	0	SF	Black		1	No	1/D
1	ML	Center Atrium near Gym	N/A	Concrete Ceiling		Non Suspect ACM	882	SF	0	SF			N/A	N/A	N/A
1	ML	Center Atrium near Gym	N/A	Glass Ceiling		Non Suspect ACM	882	SF	0	SF			N/A	N/A	N/A
1	ML	Center Atrium near Gym	N/A	Concrete Block Wall		Non Suspect ACM	1000	SF	0	SF			N/A	N/A	N/A
1	ML	Center Atrium near Gym	M	Floor Tile VAT 12" x 12"	8160/01/ML/DD	Assumed	1764	SF	0	SF	Tan		1	No	1/D
1	ML	Hallway around Atrium	N/A	Ceiling Tile 2' x 4'		NAD	1280	SF	12	SF			N/A	N/A	N/A
1	ML	Hallway around Atrium	N/A	Concrete Block Wall		Non Suspect ACM	2688	SF	0	SF			N/A	N/A	N/A
1	ML	Hallway around Atrium	M	Floor Tile VAT 12" x 12"	8160/01/ML/DD	Assumed	1280	SF	0	SF	Black		1	No	1/D
1	ML	Security Office (NTA) Storage Room	N/A	Concrete Ceiling		Non Suspect ACM	96	SF	0	SF			N/A	N/A	N/A
1	ML	Security Office (NTA) Storage Room	M	Seam Caulking	8160/01/ML/KEM/PD/2608	Assumed	1	SF	0	SF			1	No	1/D
1	ML	Security Office (NTA) Storage Room	N/A	Concrete Block Wall		Non Suspect ACM	440	SF	0	SF			N/A	N/A	N/A
1	ML	Security Office (NTA) Storage Room	N/A	Cement Floor		Non Suspect ACM	96	SF	0	SF			N/A	N/A	N/A
1	ML	Security Office (NTA)	N/A	Concrete Ceiling		Non Suspect ACM	345	SF	0	SF			N/A	N/A	N/A
1	ML	Security Office (NTA)	M	Seam Caulking	8160/01/ML/KEM/PD/2608	Assumed	3	SF	0	SF			1	No	1/D
1	ML	Security Office (NTA)	N/A	Concrete Block Wall		Non Suspect ACM	836	SF	0	SF			N/A	N/A	N/A
1	ML	Security Office (NTA)	N/A	Cement Floor		Non Suspect ACM	345	SF	0	SF			N/A	N/A	N/A
1	ML	Men's Restroom near Instrument Music Room	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	30	LF	0	LF		Pipe Chase Access in Room.	N/A	N/A	N/A
1	ML	Men's Restroom near Instrument Music Room	N/A	Fiberglass Pipe Fitting		Non Suspect ACM	8	EA	0	EA		Pipe Chase Access in Room.	N/A	N/A	N/A
1	ML	Men's Restroom near Instrument Music Room	N/A	Concrete Ceiling		Non Suspect ACM	165	SF	0	SF		Pipe Chase Access in Room.	N/A	N/A	N/A
1	ML	Men's Restroom near Instrument Music Room	M	Seam Caulking	8160/01/ML/KEM/PD/2608	Assumed	1	SF	0	SF			1	No	1/D
1	ML	Men's Restroom near Instrument Music Room	N/A	Concrete Block Wall		Non Suspect ACM	572	SF	0	SF		Pipe Chase Access in Room.	N/A	N/A	N/A
1	ML	Men's Restroom near Instrument Music Room	N/A	Ceramic Tile Floors		Non Suspect ACM	165	SF	0	SF		Pipe Chase Access in Room.	N/A	N/A	N/A
1	ML	Hallway from Boy's Restroom to Security Office	N/A	Ceiling Tile 2' x 4'		NAD	1125	SF	3	SF			N/A	N/A	N/A
1	ML	Hallway from Boy's Restroom to Security Office	N/A	Concrete Block Wall		Non Suspect ACM	2072	SF	0	SF			N/A	N/A	N/A
1	ML	Hallway from Boy's Restroom to Security Office	M	Floor Tile VAT 12" x 12"	8160/01/ML/DD	Assumed	1125	SF	0	SF	Black		1	No	1/D
1	ML	Hallway outside Art Lab A-B	N/A	Ceiling Tile 2' x 4'		NAD	240	SF	1	SF		Not Listed; Added to Map.	N/A	N/A	N/A
1	ML	Hallway outside Art Lab A-B	N/A	Concrete Block Wall		Non Suspect ACM	256	SF	0	SF		Not Listed; Added to Map.	N/A	N/A	N/A
1	ML	Hallway outside Art Lab A-B	M	Floor Tile VAT 12" x 12"	8160/01/ML/DD	Assumed	240	SF	0	SF	Black	Not Listed; Added to Map.	1	No	1/D
1	ML	Hallway along back of Stage and Maintenance Areas	N/A	Ceiling Tile 2' x 4'		NAD	900	SF	2	SF			N/A	N/A	N/A
1	ML	Hallway along back of Stage and Maintenance Areas	N/A	Concrete Block Wall		Non Suspect ACM	1600	SF	0	SF			N/A	N/A	N/A
1	ML	Hallway along back of Stage and Maintenance Areas	M	Floor Tile VAT 12" x 12"	8160/01/ML/DD	Assumed	900	SF	0	SF	Black		1	No	1/D
1	ML	Hallway from Computer Lab A to Computer Lab C	N/A	Ceiling Tile 2' x 4'		NAD	800	SF	1	SF			N/A	N/A	N/A
1	ML	Hallway from Computer Lab A to Computer Lab C	N/A	Concrete Block Wall		Non Suspect ACM	1424	SF	0	SF			N/A	N/A	N/A
1	ML	Hallway from Computer Lab A to Computer Lab C	M	Floor Tile VAT 12" x 12"	8160/01/ML/DD	Assumed	800	SF	0	SF	Black		1	No	1/D
1	ML	Hallway between Auditorium and Music Rooms	N/A	Ceiling Tile 2' x 4'		NAD	783	SF	0	SF			N/A	N/A	N/A
1	ML	Hallway between Auditorium and Music Rooms	N/A	Concrete Block Wall		Non Suspect ACM	1392	SF	0	SF			N/A	N/A	N/A
1	ML	Hallway between Auditorium and Music Rooms	M	Floor Tile VAT 12" x 12"	8160/01/ML/DD	Assumed	783	SF	0	SF	Black		1	No	1/D
1	ML	Stairwell near Computer Lab A	N/A	Concrete Ceiling		Non Suspect ACM	448	SF	0	SF			N/A	N/A	N/A
1	ML	Stairwell near Computer Lab A	M	Seam Caulking	8160/01/ML/KEM/PD/2608	Assumed	4	SF	0	SF			1	No	1/D
1	ML	Stairwell near Computer Lab A	N/A	Concrete Block Wall		Non Suspect ACM	1056	SF	0	SF			N/A	N/A	N/A

# 8160 Baldi MS- 2015 2016 AHERA Three-Year Report .xls

1	ML	Stairwell near Computer Lab A	T	Radiator Insulation	8160/01/ML/KEM/PD/1600	Assumed	15	SF	0	SF				1	No	1/D
1	ML	Stairwell near Computer Lab A	N/A	Cement Floor		Non Suspect ACM	448	SF	0	SF				N/A	N/A	N/A
1	LL	Passenger Elevator	N/A	Metal Ceiling		Non Suspect ACM	35	SF	0	SF				N/A	N/A	N/A
1	LL	Passenger Elevator	N/A	Metal Walls		Non Suspect ACM	192	SF	0	SF				N/A	N/A	N/A
1	LL	Passenger Elevator	M	Floor Tile VAT 12" x 12"	8160/01/LL/CC	Assumed	35	SF	0	SF	Orange			1	No	1/D
1	LL	Seminar Room 17 Physical Therapy	N/A	Ceiling Tile 2' x 4'		NAD	540	SF	0	SF				N/A	N/A	N/A
1	LL	Seminar Room 17 Physical Therapy	N/A	Concrete Block Wall		Non Suspect ACM	752	SF	0	SF				N/A	N/A	N/A
1	LL	Seminar Room 17 Physical Therapy	M	Floor Tile VAT 12" x 12"	8160/01/LL/CC	Assumed	540	SF	0	SF	Black			1	No	1/D
1	LL	Classroom G-1	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	2	LF	0	LF				N/A	N/A	N/A
1	LL	Classroom G-1	N/A	Fiberglass Pipe Fitting Insulation		Non Suspect ACM	1	EA	0	EA				N/A	N/A	N/A
1	LL	Classroom G-1	N/A	Concrete Ceiling		Non Suspect ACM	1160	SF	0	SF				N/A	N/A	N/A
1	LL	Classroom G-1	M	Seam Caulking	8160/01/LL/KEM/PD/2608	Assumed	14	SF	0	SF				1	No	1/D
1	LL	Classroom G-1	N/A	Concrete Block Wall		Non Suspect ACM	1518	SF	0	SF				N/A	N/A	N/A
1	LL	Classroom G-1	M	Floor Tile VAT 12" x 12"	8160/01/LL/CC	Assumed	1160	SF	0	SF	Orange			1	No	1/D
1	LL	Classroom G-1 Storage Room	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	15	LF	0	LF				N/A	N/A	N/A
1	LL	Classroom G-1 Storage Room	N/A	Fiberglass Pipe Fitting Insulation		Non Suspect ACM	2	EA	0	EA				N/A	N/A	N/A
1	LL	Classroom G-1 Storage Room	N/A	Concrete Ceiling		Non Suspect ACM	72	SF	0	SF				N/A	N/A	N/A
1	LL	Classroom G-1 Storage Room	M	Seam Caulking	8160/01/LL/KEM/PD/2608	Assumed	2	SF	0	SF				1	No	1/D
1	LL	Classroom G-1 Storage Room	N/A	Concrete Block Wall		Non Suspect ACM	330	SF	0	SF				N/A	N/A	N/A
1	LL	Classroom G-1 Storage Room	M	Floor Tile VAT 12" x 12"	8160/01/LL/CC	Assumed	72	SF	0	SF	Orange			1	No	1/D
1	LL	Stairwell next to Classroom G-2	N/A	Concrete Ceiling		Non Suspect ACM	364	SF	0	SF				N/A	N/A	N/A
1	LL	Stairwell next to Classroom G-2	N/A	Concrete Block Wall		Non Suspect ACM	960	SF	0	SF				N/A	N/A	N/A
1	LL	Stairwell next to Classroom G-2	T	Radiator Insulation	8160/01/LL/KEM/PD/1600	Assumed	15	SF	0	SF				1	No	1/D
1	LL	Stairwell next to Classroom G-2	N/A	Cement Floor		Non Suspect ACM	364	SF	0	SF				N/A	N/A	N/A
1	LL	Classroom G-2	N/A	Concrete Ceiling		Non Suspect ACM	660	SF	0	SF				N/A	N/A	N/A
1	LL	Classroom G-2	M	Seam Caulking	8160/01/LL/KEM/PD/2608	Assumed	12	SF	0	SF				1	No	1/D
1	LL	Classroom G-2	N/A	Concrete Block Wall		Non Suspect ACM	484	SF	0	SF				N/A	N/A	N/A
1	LL	Classroom G-2	N/A	Partition Room Dividers		Non Suspect ACM	330	SF	0	SF				N/A	N/A	N/A
1	LL	Classroom G-2	M	Sink Undercoat Mastic	8160/01/LL/KEM/PD/2602	Assumed	5	SF	0	SF				1	No	1/D
1	LL	Classroom G-2	M	Floor Tile VAT 12" x 12"	8160/01/LL/CC	Assumed	660	SF	0	SF	Orange			1	No	1/D
1	LL	Room G-10 Storage Room with Transformer	N/A	Ceiling Tile 2' x 4'		NAD	182	SF	2	SF				N/A	N/A	N/A
1	LL	Room G-10 Storage Room with Transformer	N/A	Concrete Block Wall		Non Suspect ACM	369	SF	0	SF				N/A	N/A	N/A
1	LL	Room G-10 Storage Room with Transformer	M	Floor Tile VAT 12" x 12"	8160/01/LL/CC	Assumed	182	SF	0	SF	Tan			1	No	1/D
1	LL	Girl's Restroom near Classroom G-2	N/A	Concrete Ceiling		Non Suspect ACM	140	SF	0	SF				N/A	N/A	N/A
1	LL	Girl's Restroom near Classroom G-2	M	Seam Caulking	8160/01/LL/KEM/PD/2608	Assumed	2	SF	0	SF				1	No	1/D
1	LL	Girl's Restroom near Classroom G-2	N/A	Concrete Block Wall		Non Suspect ACM	528	SF	0	SF				N/A	N/A	N/A
1	LL	Girl's Restroom near Classroom G-2	N/A	Ceramic Tile Floors		Non Suspect ACM	140	SF	0	SF				N/A	N/A	N/A
1	LL	Custodial Closet near Classroom G-3	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	35	LF	0	LF	Pipe Chase in Room.			N/A	N/A	N/A
1	LL	Custodial Closet near Classroom G-3	N/A	Fiberglass Pipe Fitting Insulation		Non Suspect ACM	8	EA	0	EA	Pipe Chase in Room.			N/A	N/A	N/A
1	LL	Custodial Closet near Classroom G-3	N/A	Concrete Ceiling		Non Suspect ACM	24	SF	0	SF	Pipe Chase in Room.			N/A	N/A	N/A
1	LL	Custodial Closet near Classroom G-3	N/A	Concrete Block Wall		Non Suspect ACM	242	SF	0	SF	Pipe Chase in Room.			N/A	N/A	N/A
1	LL	Custodial Closet near Classroom G-3	N/A	Cement Floor		Non Suspect ACM	24	SF	0	SF	Pipe Chase in Room.			N/A	N/A	N/A
1	LL	Classroom G-3	N/A	Concrete Ceiling		Non Suspect ACM	660	SF	0	SF				N/A	N/A	N/A
1	LL	Classroom G-3	M	Seam Caulking	8160/01/LL/KEM/PD/2608	Assumed	12	SF	0	SF				1	No	1/D
1	LL	Classroom G-3	N/A	Concrete Block Wall		Non Suspect ACM	242	SF	0	SF				N/A	N/A	N/A
1	LL	Classroom G-3	N/A	Partition Room Dividers		Non Suspect ACM	572	SF	0	SF				N/A	N/A	N/A
1	LL	Classroom G-3	M	Floor Tile VAT 12" x 12"	8160/01/LL/CC	Assumed	660	SF	0	SF	Orange			1	No	1/D
1	LL	Classroom G-4	N/A	Concrete Ceiling		Non Suspect ACM	660	SF	0	SF				N/A	N/A	N/A
1	LL	Classroom G-4	M	Seam Caulking	8160/01/LL/KEM/PD/2608	Assumed	12	SF	0	SF				1	No	1/D
1	LL	Classroom G-4	N/A	Concrete Block Wall		Non Suspect ACM	242	SF	0	SF				N/A	N/A	N/A
1	LL	Classroom G-4	N/A	Partition Room Dividers		Non Suspect ACM	572	SF	0	SF				N/A	N/A	N/A
1	LL	Classroom G-4	M	Floor Tile VAT 12" x 12"	8160/01/LL/CC	Assumed	660	SF	0	SF	Orange			1	No	1/D
1	LL	Classroom G-5	N/A	Concrete Ceiling		Non Suspect ACM	660	SF	0	SF				N/A	N/A	N/A
1	LL	Classroom G-5	M	Seam Caulking	8160/01/LL/KEM/PD/2608	Assumed	12	SF	0	SF				1	No	1/D
1	LL	Classroom G-5	N/A	Concrete Block Wall		Non Suspect ACM	484	SF	0	SF				N/A	N/A	N/A
1	LL	Classroom G-5	N/A	Partition Room Dividers		Non Suspect ACM	330	SF	0	SF				N/A	N/A	N/A
1	LL	Classroom G-5	M	Sink Undercoat Mastic	8160/01/LL/KEM/PD/2602	Assumed	4	SF	0	SF				1	No	1/D
1	LL	Classroom G-5	M	Floor Tile VAT 12" x 12"	8160/01/LL/CC	Assumed	660	SF	0	SF	Orange			1	No	1/D
											Inspector - please verify existence of Room G-7 - sampled NAD on 8/14/15 (CL/MR). This Room was renovated (no longer exists) and is now part of Seminar 18 Room..Please verify amounts			N/A	N/A	N/A
1	LL	Room G-7?	N/A	Black Glue Dots		NAD								N/A	N/A	N/A
1	LL	Room G-8?	N/A	Floor Tile VAT 12" x 12"		NAD	400	SF	0	SF	Tan	Inspector - please verify existence of Room G-8 - sampled NAD on 7/16/15 (CL/EW). This Room was renovated (no longer exists) and is now part of Seminar 18 Room.		N/A	N/A	N/A



# 8160 Baldi MS- 2015 2016 AHERA Three-Year Report .xls

													Inspector - please verify existence of Room G-8 - sampled Confirmed on 7/16/15 (CLU/EW). This Room was renovated (no longer exists) and is now part of Seminar 18 Room.			
1	LL	Room G-8?	M	Black Mastic a/w Floor Tile VAT 12" x 12"	8160/01/LL/KEM/2500	Confirmed	400	SF	0	SF	Black			1	No	1/D
1	LL	Classroom Y-5	N/A	Concrete Ceiling		Non Suspect ACM	660	SF	0	SF				N/A	N/A	N/A
1	LL	Classroom Y-5	M	Seam Caulking	8160/01/LL/KEM/PD/2608	Assumed	12	SF	0	SF				1	No	1/D
1	LL	Classroom Y-5	N/A	Concrete Block Wall		Non Suspect ACM	484	SF	0	SF				N/A	N/A	N/A
1	LL	Classroom Y-5	N/A	Partition Room Dividers		Non Suspect ACM	330	SF	0	SF				N/A	N/A	N/A
1	LL	Classroom Y-5	M	Floor Tile VAT 12" x 12"	8160/01/LL/CC	Assumed	660	SF	0	SF	Orange			1	No	1/D
1	LL	Boy's Restroom across from Classroom Y-4	N/A	Concrete Ceiling		Non Suspect ACM	140	SF	0	SF				N/A	N/A	N/A
1	LL	Boy's Restroom across from Classroom Y-4	M	Seam Caulking	8160/01/LL/KEM/PD/2608	Assumed	2	SF	0	SF				1	No	1/D
1	LL	Boy's Restroom across from Classroom Y-4	N/A	Concrete Block Wall		Non Suspect ACM	528	SF	0	SF				N/A	N/A	N/A
1	LL	Boy's Restroom across from Classroom Y-4	N/A	Ceramic Tile Floors		Non Suspect ACM	140	SF	0	SF				N/A	N/A	N/A
1	LL	Classroom Y-4	N/A	Concrete Ceiling		Non Suspect ACM	660	SF	0	SF				N/A	N/A	N/A
1	LL	Classroom Y-4	M	Seam Caulking	8160/01/LL/KEM/PD/2608	Assumed	12	SF	0	SF				1	No	1/D
1	LL	Classroom Y-4	N/A	Concrete Block Wall		Non Suspect ACM	242	SF	0	SF				N/A	N/A	N/A
1	LL	Classroom Y-4	N/A	Partition Room Dividers		Non Suspect ACM	572	SF	0	SF				N/A	N/A	N/A
1	LL	Classroom Y-4	M	Sink Undercoat Mastic	8160/01/LL/KEM/PD/2602	Assumed	4	SF	0	SF				1	No	1/D
1	LL	Classroom Y-4	M	Floor Tile VAT 12" x 12"	8160/01/LL/CC	Assumed	660	SF	0	SF	Orange			1	No	1/D
1	LL	Y-10 Storage Room across from Classroom Y-4	N/A	Ceiling Tile 2' x 4'		NAD	182	SF	2	SF				N/A	N/A	N/A
1	LL	Y-10 Storage Room across from Classroom Y-4	N/A	Concrete Block Wall		Non Suspect ACM	486	SF	0	SF				N/A	N/A	N/A
1	LL	Y-10 Storage Room across from Classroom Y-4	M	Floor Tile VAT 12" x 12"	8160/01/LL/CC	Assumed	182	SF	0	SF	Tan			1	No	1/D
1	LL	Classroom Y-3	N/A	Concrete Ceiling		Non Suspect ACM	660	SF	0	SF				N/A	N/A	N/A
1	LL	Classroom Y-3	M	Seam Caulking	8160/01/LL/KEM/PD/2608	Assumed	12	SF	0	SF				1	No	1/D
1	LL	Classroom Y-3	N/A	Concrete Block Wall		Non Suspect ACM	242	SF	0	SF				N/A	N/A	N/A
1	LL	Classroom Y-3	M	Sink Undercoat Mastic	8160/01/LL/KEM/PD/2602	Assumed	5	SF	0	SF				1	No	1/D
1	LL	Classroom Y-3	N/A	Partition Room Dividers		Non Suspect ACM	572	SF	0	SF				N/A	N/A	N/A
1	LL	Classroom Y-3	M	Floor Tile VAT 12" x 12"	8160/01/LL/CC	Assumed	660	SF	0	SF	Orange			1	No	1/D
1	LL	Classroom Y-2	N/A	Concrete Ceiling		Non Suspect ACM	660	SF	0	SF				N/A	N/A	N/A
1	LL	Classroom Y-2	M	Seam Caulking	8160/01/LL/KEM/PD/2608	Assumed	12	SF	0	SF				1	No	1/D
1	LL	Classroom Y-2	N/A	Concrete Block Wall		Non Suspect ACM	484	SF	0	SF				N/A	N/A	N/A
1	LL	Classroom Y-2	N/A	Partition Room Dividers		Non Suspect ACM	330	SF	0	SF				N/A	N/A	N/A
1	LL	Classroom Y-2	M	Floor Tile VAT 12" x 12"	8160/01/LL/CC	Assumed	660	SF	0	SF	Orange			1	No	1/D
1	LL	Room Y-17 Speech Therapy Office	N/A	Ceiling Tile 2' x 4'		NAD	420	SF	0	SF				N/A	N/A	N/A
1	LL	Room Y-17 Speech Therapy Office	N/A	Concrete Block Wall		Non Suspect ACM	704	SF	0	SF				N/A	N/A	N/A
1	LL	Room Y-17 Speech Therapy Office	M	Floor Tile VAT 12" x 12"	8160/01/LL/CC	Assumed	420	SF	0	SF	Orange			1	No	1/D
1	LL	Classroom Y-1	N/A	Concrete Ceiling		Non Suspect ACM	1160	SF	0	SF				N/A	N/A	N/A
1	LL	Classroom Y-1	M	Seam Caulking	8160/01/LL/KEM/PD/2608	Assumed	16	SF	0	SF				1	No	1/D
1	LL	Classroom Y-1	N/A	Concrete Block Wall		Non Suspect ACM	1518	SF	0	SF				N/A	N/A	N/A
1	LL	Classroom Y-1	M	Floor Tile VAT 12" x 12"	8160/01/LL/CC	Assumed	1160	SF	0	SF	Orange			1	No	1/D
1	LL	Classroom Y-1 Storage Room	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	10	LF	0	LF				N/A	N/A	N/A
1	LL	Classroom Y-1 Storage Room	N/A	Fiberglass Pipe Fitting Insulation		Non Suspect ACM	2	EA	0	EA				N/A	N/A	N/A
1	LL	Classroom Y-1 Storage Room	N/A	Concrete Ceiling		Non Suspect ACM	98	SF	0	SF				N/A	N/A	N/A
1	LL	Classroom Y-1 Storage Room	M	Seam Caulking	8160/01/LL/KEM/PD/2608	Assumed	1	SF	0	SF				1	No	1/D
1	LL	Classroom Y-1 Storage Room	N/A	Concrete Block Wall		Non Suspect ACM	462	SF	0	SF				N/A	N/A	N/A
1	LL	Classroom Y-1 Storage Room	M	Floor Tile VAT 12" x 12"	8160/01/LL/CC	Assumed	98	SF	0	SF	Orange			1	No	1/D
1	LL	Lower Lecture Hall	N/A	Ceiling Tile 2' x 4'		NAD	1568	SF	0	SF				N/A	N/A	N/A
1	LL	Lower Lecture Hall	N/A	Concrete Block Wall		Non Suspect ACM	1400	SF	0	SF				N/A	N/A	N/A
1	LL	Lower Lecture Hall	M	Floor Tile VAT 12" x 12"	8160/01/LL/CC	Assumed	1568	SF	0	SF	Orange			1	No	1/D
1	LL	Stairwell (S-9) next to Lower Lecture Hall	N/A	Concrete Ceiling		Non Suspect ACM	168	SF	0	SF				N/A	N/A	N/A
1	LL	Stairwell (S-9) next to Lower Lecture Hall	N/A	Steel Ceiling		Non Suspect ACM	168	SF	0	SF				N/A	N/A	N/A
1	LL	Stairwell (S-9) next to Lower Lecture Hall	N/A	Concrete Block Wall		Non Suspect ACM	912	SF	0	SF				N/A	N/A	N/A
1	LL	Stairwell (S-9) next to Lower Lecture Hall	N/A	Cement Floor		Non Suspect ACM	336	SF	0	SF				N/A	N/A	N/A
1	LL	Hallway from Classroom Y-1 to Lower Lecture Hall	N/A	Ceiling Tile 2' x 4'		NAD	312	SF	0	SF				N/A	N/A	N/A
1	LL	Hallway from Classroom Y-1 to Lower Lecture Hall	N/A	Concrete Block Wall		Non Suspect ACM	512	SF	0	SF				N/A	N/A	N/A
1	LL	Hallway from Classroom Y-1 to Lower Lecture Hall	M	Floor Tile VAT 12" x 12"	8160/01/LL/CC	Assumed	312	SF	0	SF	Black			1	No	1/D
1	LL	Hallway from Classroom O-1 to Lower Lecture Hall	N/A	Ceiling Tile 2' x 4'		NAD	312	SF	0	SF				N/A	N/A	N/A
1	LL	Hallway from Classroom O-1 to Lower Lecture Hall	N/A	Concrete Block Wall		Non Suspect ACM	512	SF	0	SF				N/A	N/A	N/A
1	LL	Hallway from Classroom O-1 to Lower Lecture Hall	M	Floor Tile VAT 12" x 12"	8160/01/LL/CC	Assumed	312	SF	0	SF	Black			1	No	1/D
1	LL	Classroom O-1	N/A	Concrete Ceiling		Non Suspect ACM	1160	SF	0	SF				N/A	N/A	N/A
1	LL	Classroom O-1	M	Seam Caulking	8160/01/LL/KEM/PD/2608	Assumed	16	SF	0	SF				1	No	1/D
1	LL	Classroom O-1	N/A	Concrete Block Wall		Non Suspect ACM	1518	SF	0	SF				N/A	N/A	N/A
1	LL	Classroom O-1	M	Floor Tile VAT 12" x 12"	8160/01/LL/CC	Assumed	1160	SF	0	SF	Orange			1	No	1/D
1	LL	Classroom O-1 Storage Room	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	25	LF	0	LF			No Access; Not Inspected.	N/A	N/A	N/A
1	LL	Classroom O-1 Storage Room	N/A	Fiberglass Pipe Fitting Insulation		Non Suspect ACM	5	EA	0	EA			No Access; Not Inspected.	N/A	N/A	N/A
1	LL	Classroom O-1 Storage Room	N/A	Concrete Ceiling		Non Suspect ACM	98	SF	0	SF			No Access; Not Inspected.	N/A	N/A	N/A
1	LL	Classroom O-1 Storage Room	N/A	Concrete Block Wall		Non Suspect ACM	462	SF	0	SF			No Access; Not Inspected.	N/A	N/A	N/A
1	LL	Classroom O-1 Storage Room	M	Floor Tile VAT 12" x 12"	8160/01/LL/CC	Assumed	98	SF	0	SF	Orange			1	No	1/D

# 8160 Baldi MS- 2015 2016 AHERA Three-Year Report .xls

1	LL	Office across from Classroom O-2	N/A	Ceiling Tile 2' x 4'		NAD	420	SF	2	SF				N/A	N/A	N/A
1	LL	Office across from Classroom O-2	N/A	Concrete Block Wall		Non Suspect ACM	704	SF	0	SF				N/A	N/A	N/A
1	LL	Office across from Classroom O-2	M	Floor Tile VAT 12" x 12"	8160/01/LL/CC	Assumed	420	SF	0	SF	Orange			1	No	1/D
1	LL	Classroom O-2	N/A	Concrete Ceiling		Non Suspect ACM	660	SF	0	SF				N/A	N/A	N/A
1	LL	Classroom O-2	M	Seam Caulking	8160/01/LL/KEM/PP/260 8	Assumed	12	SF	0	SF				1	No	1/D
1	LL	Classroom O-2	N/A	Concrete Block Wall		Non Suspect ACM	484	SF	0	SF				N/A	N/A	N/A
1	LL	Classroom O-2	N/A	Partition Room Dividers		Non Suspect ACM	330	SF	0	SF				N/A	N/A	N/A
1	LL	Classroom O-2	M	Floor Tile VAT 12" x 12"	8160/01/LL/CC	Assumed	660	SF	0	SF	Orange			1	No	1/D
1	LL	Classroom O-3	N/A	Concrete Ceiling		Non Suspect ACM	660	SF	0	SF				N/A	N/A	N/A
1	LL	Classroom O-3	M	Seam Caulking	8160/01/LL/KEM/PP/260 8	Assumed	12	SF	0	SF				1	No	1/D
1	LL	Classroom O-3	N/A	Concrete Block Wall		Non Suspect ACM	242	SF	0	SF				N/A	N/A	N/A
1	LL	Classroom O-3	N/A	Partition Room Dividers		Non Suspect ACM	572	SF	0	SF				N/A	N/A	N/A
1	LL	Classroom O-3	M	Sink Undercoat Mastic	8160/01/LL/KEM/PP/260 2	Assumed	4	SF	0	SF				1	No	1/D
1	LL	Classroom O-3	M	Floor Tile VAT 12" x 12"	8160/01/LL/CC	Assumed	660	SF	0	SF	Orange			1	No	1/D
1	LL	O-10 Storage Room across from Classroom O-4	N/A	Ceiling Tile 2' x 4'		NAD	182	SF	0	SF				N/A	N/A	N/A
1	LL	O-10 Storage Room across from Classroom O-4	N/A	Concrete Block Wall		Non Suspect ACM	369	SF	0	SF				N/A	N/A	N/A
1	LL	O-10 Storage Room across from Classroom O-4	M	Floor Tile VAT 12" x 12"	8160/01/LL/CC	Assumed	182	SF	0	SF	Tan			1	No	1/D
1	LL	Classroom O-4	N/A	Concrete Ceiling		Non Suspect ACM	660	SF	0	SF				N/A	N/A	N/A
1	LL	Classroom O-4	M	Seam Caulking	8160/01/LL/KEM/PP/260 8	Assumed	12	SF	0	SF				1	No	1/D
1	LL	Classroom O-4	N/A	Concrete Block Wall		Non Suspect ACM	242	SF	0	SF				N/A	N/A	N/A
1	LL	Classroom O-4	N/A	Partition Room Dividers		Non Suspect ACM	572	SF	0	SF				N/A	N/A	N/A
1	LL	Classroom O-4	M	Sink Undercoat Mastic	8160/01/LL/KEM/PP/260 2	Assumed	4	SF	0	SF				1	No	1/D
1	LL	Classroom O-4	M	Floor Tile VAT 12" x 12"	8160/01/LL/CC	Assumed	660	SF	0	SF	Orange			1	No	1/D
1	LL	Boy's Restroom across from Classroom O-4	N/A	Concrete Ceiling		Non Suspect ACM	140	SF	0	SF				N/A	N/A	N/A
1	LL	Boy's Restroom across from Classroom O-4	M	Seam Caulking	8160/01/LL/KEM/PP/260 8	Assumed	2	SF	0	SF				1	No	1/D
1	LL	Boy's Restroom across from Classroom O-4	N/A	Concrete Block Wall		Non Suspect ACM	48	SF	0	SF				N/A	N/A	N/A
1	LL	Boy's Restroom across from Classroom O-4	N/A	Ceramic Tile Floors		Non Suspect ACM	140	SF	0	SF				N/A	N/A	N/A
1	LL	Classroom O-5	N/A	Concrete Ceiling		Non Suspect ACM	660	SF	0	SF				N/A	N/A	N/A
1	LL	Classroom O-5	M	Seam Caulking	8160/01/LL/KEM/PP/260 8	Assumed	12	SF	0	SF				1	No	1/D
1	LL	Classroom O-5	N/A	Concrete Block Wall		Non Suspect ACM	484	SF	0	SF				N/A	N/A	N/A
1	LL	Classroom O-5	N/A	Partition Room Dividers		Non Suspect ACM	330	SF	0	SF				N/A	N/A	N/A
1	LL	Classroom O-5	M	Floor Tile VAT 12" x 12"	8160/01/LL/CC	Assumed	660	SF	0	SF	Orange			1	No	1/D
1	LL	Classroom B-5	N/A	Concrete Ceiling		Non Suspect ACM	660	SF	0	SF				N/A	N/A	N/A
1	LL	Classroom B-5	M	Seam Caulking	8160/01/LL/KEM/PP/260 8	Assumed	12	SF	0	SF				1	No	1/D
1	LL	Classroom B-5	N/A	Concrete Block Wall		Non Suspect ACM	484	SF	0	SF				N/A	N/A	N/A
1	LL	Classroom B-5	N/A	Partition Room Dividers		Non Suspect ACM	330	SF	0	SF				N/A	N/A	N/A
1	LL	Classroom B-5	M	Sink Undercoat Mastic	8160/01/LL/KEM/PP/260 2	Assumed	4	SF	0	SF				1	No	1/D
1	LL	Classroom B-5	M	Floor Tile VAT 12" x 12"	8160/01/LL/CC	Assumed	660	SF	0	SF	Orange			1	No	1/D
1	LL	Classroom B-4	N/A	Concrete Ceiling		Non Suspect ACM	660	SF	0	SF				N/A	N/A	N/A
1	LL	Classroom B-4	M	Seam Caulking	8160/01/LL/KEM/PP/260 8	Assumed	12	SF	0	SF				1	No	1/D
1	LL	Classroom B-4	N/A	Concrete Block Wall		Non Suspect ACM	242	SF	0	SF				N/A	N/A	N/A
1	LL	Classroom B-4	N/A	Partition Room Dividers		Non Suspect ACM	572	SF	0	SF				N/A	N/A	N/A
1	LL	Classroom B-4	M	Floor Tile VAT 12" x 12"	8160/01/LL/CC	Assumed	660	SF	0	SF	Orange			1	No	1/D
1	LL	Classroom B-3	N/A	Concrete Ceiling		Non Suspect ACM	660	SF	0	SF				N/A	N/A	N/A
1	LL	Classroom B-3	M	Seam Caulking	8160/01/LL/KEM/PP/260 8	Assumed	12	SF	0	SF				1	No	1/D
1	LL	Classroom B-3	N/A	Concrete Block Wall		Non Suspect ACM	242	SF	0	SF				N/A	N/A	N/A
1	LL	Classroom B-3	N/A	Partition Room Dividers		Non Suspect ACM	572	SF	0	SF				N/A	N/A	N/A
1	LL	Classroom B-3	M	Floor Tile VAT 12" x 12"	8160/01/LL/CC	Assumed	660	SF	0	SF	Orange			1	No	1/D
1	LL	Girl's Restroom near Classroom B-2	N/A	Concrete Ceiling		Non Suspect ACM	140	SF	0	SF		Pipe Chase Access in Room.		N/A	N/A	N/A
1	LL	Girl's Restroom near Classroom B-2	M	Seam Caulking	8160/01/LL/KEM/PP/260 8	Assumed	2	SF	0	SF				1	No	1/D
1	LL	Girl's Restroom near Classroom B-2	N/A	Concrete Block Wall		Non Suspect ACM	528	SF	0	SF		Pipe Chase Access in Room.		N/A	N/A	N/A
1	LL	Girl's Restroom near Classroom B-2	N/A	Ceramic Tile Floors		Non Suspect ACM	140	SF	0	SF		Pipe Chase Access in Room.		N/A	N/A	N/A
1	LL	B-10 Storage Room next to Girl's Restroom	N/A	Ceiling Tile 2' x 4'		NAD	182	SF	0	SF				N/A	N/A	N/A
1	LL	B-10 Storage Room next to Girl's Restroom	N/A	Concrete Block Wall		Non Suspect ACM	486	SF	0	SF				N/A	N/A	N/A
1	LL	B-10 Storage Room next to Girl's Restroom	M	Floor Tile VAT 12" x 12"	8160/01/LL/CC	Assumed	182	SF	0	SF	Tan			1	No	1/D
1	LL	Classroom B-2	N/A	Concrete Ceiling		Non Suspect ACM	660	SF	0	SF				N/A	N/A	N/A
1	LL	Classroom B-2	M	Seam Caulking	8160/01/LL/KEM/PP/260 8	Assumed	12	SF	0	SF				1	No	1/D
1	LL	Classroom B-2	N/A	Concrete Block Wall		Non Suspect ACM	484	SF	0	SF				N/A	N/A	N/A
1	LL	Classroom B-2	N/A	Partition Room Dividers		Non Suspect ACM	330	SF	0	SF				N/A	N/A	N/A
1	LL	Classroom B-2	M	Sink Undercoat Mastic	8160/01/LL/KEM/PP/260 2	Assumed	4	SF	0	SF				1	No	1/D
1	LL	Classroom B-2	M	Floor Tile VAT 12" x 12"	8160/01/LL/CC	Assumed	660	SF	0	SF	Orange			1	No	1/D
1	LL	Stairwell next to Classroom B-2	N/A	Concrete Ceiling		Non Suspect ACM	364	SF	0	SF				N/A	N/A	N/A
1	LL	Stairwell next to Classroom B-2	T	Radiator Insulation	8160/01/LL/KEM/PP/160 0	Assumed	15	SF	0	SF				1	No	1/D
1	LL	Stairwell next to Classroom B-2	N/A	Concrete Block Wall		Non Suspect ACM	960	SF	0	SF				N/A	N/A	N/A
1	LL	Stairwell next to Classroom B-2	N/A	Cement Floor		Non Suspect ACM	364	SF	0	SF				N/A	N/A	N/A

# 8160 Baldi MS- 2015 2016 AHERA Three-Year Report .xls

1	LL	Classroom B-1	N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	1160	SF	0	SF				N/A	N/A	N/A
1	LL	Classroom B-1	N/A	Concrete Block Wall		Non Suspect ACM	1200	SF	0	SF				N/A	N/A	N/A
1	LL	Classroom B-1	M	Floor Tile VAT 12" x 12"	8160/01/LL/CC	Assumed	1160	SF	0	SF	Orange			1	No	1/D
1	LL	Classroom B-1 Storage Room	N/A	Concrete Ceiling		Non Suspect ACM	72	SF	0	SF				N/A	N/A	N/A
1	LL	Classroom B-1 Storage Room	M	Seam Caulking	8160/01/LL/KEM/PD/2608	Assumed	2	SF	0	SF				1	No	1/D
1	LL	Classroom B-1 Storage Room	N/A	Concrete Block Wall		Non Suspect ACM	330	SF	0	SF				N/A	N/A	N/A
1	LL	Classroom B-1 Storage Room	M	Floor Tile VAT 12" x 12"	8160/01/LL/CC	Assumed	72	SF	0	SF	Orange			1	No	1/D
1	LL	Seminar Room 19	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	30	LF	0	LF				N/A	N/A	N/A
1	LL	Seminar Room 19	N/A	Fiberglass Pipe Fitting Insulation		Non Suspect ACM	2	EA	0	EA				N/A	N/A	N/A
1	LL	Seminar Room 19	N/A	Concrete Ceiling		Non Suspect ACM	240	SF	0	SF				N/A	N/A	N/A
1	LL	Seminar Room 19	M	Textured Ceiling Paint	8160/01/LL/KEM/PD/2611	Assumed	240	SF	0	SF				1	No	1/D
1	LL	Seminar Room 19	M	Seam Caulking	8160/01/LL/KEM/PD/2608	Assumed	4	SF	0	SF				1	No	1/D
1	LL	Seminar Room 19	N/A	Concrete Block Wall		Non Suspect ACM	517	SF	0	SF				N/A	N/A	N/A
1	LL	Seminar Room 19	M	Floor Tile VAT 12" x 12"	8160/01/LL/CC	Assumed	240	SF	0	SF	Black			1	No	1/D
1	LL	Stairwell next to Restrooms	N/A	Ceiling Tile 2' x 4'		NAD	952	SF	0	SF				N/A	N/A	N/A
1	LL	Stairwell next to Restrooms	N/A	Concrete Block Wall		Non Suspect ACM	1116	SF	0	SF				N/A	N/A	N/A
1	LL	Stairwell next to Restrooms	M	Floor Tile VAT 12" x 12"	8160/01/LL/CC	Assumed	952	SF	0	SF	Black			1	No	1/D
1	LL	Boy's Restroom in Lower Commons Area	N/A	Concrete Ceiling		Non Suspect ACM	286	SF	0	SF				N/A	N/A	N/A
1	LL	Boy's Restroom in Lower Commons Area	M	Seam Caulking	8160/01/LL/KEM/PD/2608	Assumed	5	SF	0	SF				1	No	1/D
1	LL	Boy's Restroom in Lower Commons Area	N/A	Concrete Block Wall		Non Suspect ACM	770	SF	0	SF				N/A	N/A	N/A
1	LL	Boy's Restroom in Lower Commons Area	N/A	Ceramic Tile Floors		Non Suspect ACM	286	SF	0	SF				N/A	N/A	N/A
1	LL	Men's Restroom in Lower Commons Area	N/A	Concrete Ceiling		Non Suspect ACM	70	SF	0	SF				N/A	N/A	N/A
1	LL	Men's Restroom in Lower Commons Area	M	Seam Caulking	8160/01/LL/KEM/PD/2608	Assumed	2	SF	0	SF				1	No	1/D
1	LL	Men's Restroom in Lower Commons Area	N/A	Concrete Block Wall		Non Suspect ACM	374	SF	0	SF				N/A	N/A	N/A
1	LL	Men's Restroom in Lower Commons Area	N/A	Ceramic Tile Floors		Non Suspect ACM	70	SF	0	SF				N/A	N/A	N/A
1	LL	Custodial Closet between Men's Restroom and Girl's Restroom in Lower Commons Area	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	30	LF	0	LF		Pipe Chase in this Room.		N/A	N/A	N/A
1	LL	Custodial Closet between Men's Restroom and Girl's Restroom in Lower Commons Area	N/A	Fiberglass Pipe Fitting Insulation		Non Suspect ACM	10	EA	0	EA		Pipe Chase in this Room.		N/A	N/A	N/A
1	LL	Custodial Closet between Men's Restroom and Girl's Restroom in Lower Commons Area	N/A	Concrete Ceiling		Non Suspect ACM	28	SF	0	SF		Pipe Chase in this Room.		N/A	N/A	N/A
1	LL	Custodial Closet between Men's Restroom and Girl's Restroom in Lower Commons Area	M	Seam Caulking	8160/01/LL/KEM/PD/2608	Assumed	1	SF	0	SF		Not Listed; Added to Map.		1	No	1/D
1	LL	Custodial Closet between Men's Restroom and Girl's Restroom in Lower Commons Area	N/A	Concrete Block Wall		Non Suspect ACM	242	SF	0	SF		Pipe Chase in this Room.		N/A	N/A	N/A
1	LL	Custodial Closet between Men's Restroom and Girl's Restroom in Lower Commons Area	N/A	Cement Floor		Non Suspect ACM	28	SF	0	SF		Pipe Chase in this Room.		N/A	N/A	N/A
1	LL	Girl's Restroom next to Women's Restroom in Lower Commons Area	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	15	LF	0	LF		Pipe Chase in this Room.		N/A	N/A	N/A
1	LL	Girl's Restroom next to Women's Restroom in Lower Commons Area	N/A	Fiberglass Pipe Fitting Insulation		Non Suspect ACM	2	EA	0	EA		Pipe Chase in this Room.		N/A	N/A	N/A
1	LL	Girl's Restroom next to Women's Restroom in Lower Commons Area	N/A	Concrete Ceiling		Non Suspect ACM	280	SF	0	SF		Pipe Chase in this Room.		N/A	N/A	N/A
1	LL	Girl's Restroom next to Women's Restroom in Lower Commons Area	M	Seam Caulking	8160/01/LL/KEM/PD/2608	Assumed	2	SF	0	SF				1	No	1/D
1	LL	Girl's Restroom next to Women's Restroom in Lower Commons Area	N/A	Concrete Block Wall		Non Suspect ACM	946	SF	0	SF		Pipe Chase in this Room.		N/A	N/A	N/A
1	LL	Girl's Restroom next to Women's Restroom in Lower Commons Area	N/A	Ceramic Tile Floors		Non Suspect ACM	280	SF	0	SF		Pipe Chase in this Room.		N/A	N/A	N/A
1	LL	Women's Restroom next to Girl's Restroom in Lower Commons Area	N/A	Concrete Ceiling		Non Suspect ACM	117	SF	0	SF				N/A	N/A	N/A
1	LL	Women's Restroom next to Girl's Restroom in Lower Commons Area	N/A	Concrete Block Wall		Non Suspect ACM	484	SF	0	SF				N/A	N/A	N/A
1	LL	Lower Commons Area	N/A	Ceramic Tile Floors		Non Suspect ACM	117	SF	0	SF				N/A	N/A	N/A
1	LL	Hallway C-7a to Outside Exit	N/A	Ceiling Tile 2' x 4'		NAD	520	SF	2	SF				N/A	N/A	N/A
1	LL	Hallway C-7a to Outside Exit	N/A	Concrete Block Wall		Non Suspect ACM	1104	SF	0	SF				N/A	N/A	N/A
1	LL	Hallway C-7a to Outside Exit	M	Floor Tile VAT 12" x 12"	8160/01/LL/CC	Assumed	520	SF	0	SF	Black			1	No	1/D
1	LL	Hallway from Hallway C-7a to Elevator	N/A	Ceiling Tile 2' x 4'		NAD	544	SF	6	SF				N/A	N/A	N/A
1	LL	Hallway from Hallway C-7a to Elevator	N/A	Concrete Block Wall		Non Suspect ACM	1088	SF	0	SF				N/A	N/A	N/A
1	LL	Hallway from Hallway C-7a to Elevator	M	Floor Tile VAT 12" x 12"	8160/01/LL/CC	Assumed	544	SF	0	SF	Black			1	No	1/D
1	LL	Hallway between Elevator Machine Room and Room S-1	N/A	Ceiling Tile 2' x 4'		NAD	280	SF	0	SF				N/A	N/A	N/A
1	LL	Hallway between Elevator Machine Room and Room S-1	N/A	Concrete Block Wall		Non Suspect ACM	432	SF	0	SF				N/A	N/A	N/A
1	LL	Hallway between Elevator Machine Room and Room S-1	M	Floor Tile VAT 12" x 12"	8160/01/LL/CC	Assumed	280	SF	0	SF	Black			1	No	1/D
1	LL	Elevator Machine Room	N/A	Concrete Ceiling		Non Suspect ACM	102	SF	0	SF		Not Listed; Added to Map.		N/A	N/A	N/A
1	LL	Elevator Machine Room	N/A	Concrete Block Wall		Non Suspect ACM	506	SF	0	SF		Not Listed; Added to Map.		N/A	N/A	N/A
1	LL	Elevator Machine Room	N/A	Cement Floor		Non Suspect ACM	102	SF	0	SF		Not Listed; Added to Map.		N/A	N/A	N/A
1	LL	S-1 Storage Room	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	20	LF	0	LF		Pipe Chase Access in Room.		N/A	N/A	N/A
1	LL	S-1 Storage Room	N/A	Fiberglass Pipe Fitting Insulation		Non Suspect ACM	6	EA	0	EA		Pipe Chase Access in Room.		N/A	N/A	N/A
1	LL	S-1 Storage Room	N/A	Concrete Ceiling		Non Suspect ACM	204	SF	0	SF		Pipe Chase Access in Room.		N/A	N/A	N/A
1	LL	S-1 Storage Room	N/A	Concrete Block Wall		Non Suspect ACM	638	SF	0	SF		Pipe Chase Access in Room.		N/A	N/A	N/A
1	LL	S-1 Storage Room	N/A	Cement Floor		Non Suspect ACM	204	SF	0	SF		Pipe Chase Access in Room.		N/A	N/A	N/A

# 8160 Baldi MS- 2015 2016 AHERA Three-Year Report .xls

1	LL	Storage Room and Air Handler Equipment Room across from the Adaptive Gym	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	50	LF	0	LF				N/A	N/A	N/A
1	LL	Storage Room and Air Handler Equipment Room across from the Adaptive Gym	N/A	Fiberglass Pipe Fitting Insulation		Non Suspect ACM	10	EA	0	EA				N/A	N/A	N/A
1	LL	Storage Room and Air Handler Equipment Room across from the Adaptive Gym	N/A	Concrete Ceiling		Non Suspect ACM	512	SF	0	SF				N/A	N/A	N/A
1	LL	Storage Room and Air Handler Equipment Room across from the Adaptive Gym	N/A	Concrete Block Wall		Non Suspect ACM	1056	SF	0	SF				N/A	N/A	N/A
1	LL	Storage Room and Air Handler Equipment Room across from the Adaptive Gym	N/A	Vinyl Vibration Damper Cloth		Non Suspect ACM	20	SF	0	SF				N/A	N/A	N/A
1	LL	Storage Room and Air Handler Equipment Room across from the Adaptive Gym	N/A	Cement Floor		Non Suspect ACM	512	SF	0	SF				N/A	N/A	N/A
1	LL	Hallway from Storage and Air Handler Equipment Room to Girl's Locker Room	N/A	Ceiling Tile 2' x 4'		NAD	350	SF	4	SF				N/A	N/A	N/A
1	LL	Hallway from Storage and Air Handler Equipment Room to Girl's Locker Room	N/A	Concrete Block Wall		Non Suspect ACM	856	SF	0	SF				N/A	N/A	N/A
1	LL	Hallway from Storage and Air Handler Equipment Room to Girl's Locker Room	M	Floor Tile VAT 12" x 12"	8160/01/LL/CC	Assumed	350	SF	0	SF	Black			1	No	1/D
1	LL	Stairwell next to Storage and Air Handler Equipment Room	N/A	Concrete Ceiling		Non Suspect ACM	96	SF	0	SF				N/A	N/A	N/A
1	LL	Stairwell next to Storage and Air Handler Equipment Room	N/A	Concrete Block Wall		Non Suspect ACM	320	SF	0	SF				N/A	N/A	N/A
1	LL	Stairwell next to Storage and Air Handler Equipment Room	N/A	Cement Floor		Non Suspect ACM	96	SF	0	SF				N/A	N/A	N/A
1	LL	Girl's Locker Room Restroom	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	30	LF	0	LF				N/A	N/A	N/A
1	LL	Girl's Locker Room Restroom	N/A	Fiberglass Pipe Fitting Insulation		Non Suspect ACM	4	EA	0	EA				N/A	N/A	N/A
1	LL	Girl's Locker Room Restroom	N/A	Concrete Ceiling		Non Suspect ACM	200	SF	0	SF				N/A	N/A	N/A
1	LL	Girl's Locker Room Restroom	M	Seam Caulking	8160/01/LL/KEM/PD/2608	Assumed	3	SF	0	SF				1	No	1/D
1	LL	Girl's Locker Room Restroom	N/A	Concrete Block Wall		Non Suspect ACM	660	SF	0	SF				N/A	N/A	N/A
1	LL	Girl's Locker Room Restroom	N/A	Ceramic Tile Floors		Non Suspect ACM	200	SF	0	SF				N/A	N/A	N/A
1	LL	Girl's Locker Room Shower Area	N/A	Concrete Ceiling		Non Suspect ACM	242	SF	0	SF				N/A	N/A	N/A
1	LL	Girl's Locker Room Shower Area	M	Seam Caulking	8160/01/LL/KEM/PD/2608	Assumed	6	SF	0	SF				1	No	1/D
1	LL	Girl's Locker Room Shower Area	N/A	Concrete Block Wall		Non Suspect ACM	605	SF	0	SF				N/A	N/A	N/A
1	LL	Girl's Locker Room Shower Area	N/A	Ceramic Tile Floors		Non Suspect ACM	242	SF	0	SF				N/A	N/A	N/A
1	LL	Girl's Locker Room Storage Room between Showers and Restroom	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	20	LF	0	LF				N/A	N/A	N/A
1	LL	Girl's Locker Room Storage Room between Showers and Restroom	N/A	Fiberglass Pipe Fitting Insulation		Non Suspect ACM	6	EA	0	EA				N/A	N/A	N/A
1	LL	Girl's Locker Room Storage Room between Showers and Restroom	N/A	Concrete Ceiling		Non Suspect ACM	60	SF	0	SF				N/A	N/A	N/A
1	LL	Girl's Locker Room Storage Room between Showers and Restroom	M	Seam Caulking	8160/01/LL/KEM/PD/2608	Assumed	1	SF	0	SF				1	No	1/D
1	LL	Girl's Locker Room Storage Room between Showers and Restroom	N/A	Concrete Block Wall		Non Suspect ACM	352	SF	0	SF				N/A	N/A	N/A
1	LL	Girl's Locker Room Storage Room between Showers and Restroom	N/A	Cement Floor		Non Suspect ACM	60	SF	0	SF				N/A	N/A	N/A
1	LL	Girl's Locker Room	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	120	LF	0	LF				N/A	N/A	N/A
1	LL	Girl's Locker Room	N/A	Fiberglass Pipe Fitting Insulation		Non Suspect ACM	10	EA	0	EA				N/A	N/A	N/A
1	LL	Girl's Locker Room	N/A	Concrete Ceiling		Non Suspect ACM	2080	SF	0	SF				N/A	N/A	N/A
1	LL	Girl's Locker Room	M	Seam Caulking	8160/01/LL/KEM/PD/2608	Assumed	36	SF	0	SF				1	No	1/D
1	LL	Girl's Locker Room	N/A	Concrete Block Wall		Non Suspect ACM	2134	SF	0	SF				N/A	N/A	N/A
1	LL	Girl's Locker Room	N/A	Cement Floor		Non Suspect ACM	2080	SF	0	SF				N/A	N/A	N/A
1	LL	Stairwell from Girl's Locker Room to Girl's side of Gym	N/A	Concrete Ceiling		Non Suspect ACM	80	SF	0	SF				N/A	N/A	N/A
1	LL	Stairwell from Girl's Locker Room to Girl's side of Gym	N/A	Steel Ceiling		Non Suspect ACM	80	SF	0	SF				N/A	N/A	N/A
1	LL	Stairwell from Girl's Locker Room to Girl's side of Gym	N/A	Concrete Block Wall		Non Suspect ACM	624	SF	0	SF				N/A	N/A	N/A
1	LL	Stairwell from Girl's Locker Room to Girl's side of Gym	N/A	Cement Floor		Non Suspect ACM	160	SF	0	SF				N/A	N/A	N/A
1	LL	Adaptive Gym	N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	990	SF	0	SF				N/A	N/A	N/A
1	LL	Adaptive Gym	N/A	Concrete Block Wall		Non Suspect ACM	1188	SF	0	SF				N/A	N/A	N/A
1	LL	Adaptive Gym	N/A	Wood Floor		Non Suspect ACM	990	SF	0	SF				N/A	N/A	N/A
1	LL	Adaptive Gym's Rear Storage Room	N/A	Concrete Ceiling		Non Suspect ACM	48	SF	0	SF				N/A	N/A	N/A
1	LL	Adaptive Gym's Rear Storage Room	M	Seam Caulking	8160/01/LL/KEM/PD/2608	Assumed	1	SF	0	SF				1	No	1/D
1	LL	Adaptive Gym's Rear Storage Room	N/A	Concrete Block Wall		Non Suspect ACM	418	SF	0	SF				N/A	N/A	N/A
1	LL	Adaptive Gym's Rear Storage Room	N/A	Cement Floor		Non Suspect ACM	48	SF	0	SF				N/A	N/A	N/A
1	LL	Adaptive Gym's Front Storage Room	N/A	Concrete Ceiling		Non Suspect ACM	48	SF	0	SF				N/A	N/A	N/A
1	LL	Adaptive Gym's Front Storage Room	M	Seam Caulking	8160/01/LL/KEM/PD/2608	Assumed	1	SF	0	SF				1	No	1/D
1	LL	Adaptive Gym's Front Storage Room	N/A	Concrete Block Wall		Non Suspect ACM	418	SF	0	SF				N/A	N/A	N/A
1	LL	Adaptive Gym's Front Storage Room	N/A	Cement Floor		Non Suspect ACM	48	SF	0	SF				N/A	N/A	N/A
1	LL	Stairwell near Adaptive Gym	N/A	Concrete Ceiling		Non Suspect ACM	96	SF	0	SF				N/A	N/A	N/A
1	LL	Stairwell near Adaptive Gym	N/A	Concrete Block Wall		Non Suspect ACM	320	SF	0	SF				N/A	N/A	N/A
1	LL	Stairwell near Adaptive Gym	N/A	Cement Floor		Non Suspect ACM	96	SF	0	SF				N/A	N/A	N/A
1	LL	Hallway from Adaptive Gym to Boy's Locker Room	N/A	Ceiling Tile 2' x 4'		NAD	350	SF	0	SF				N/A	N/A	N/A
1	LL	Hallway from Adaptive Gym to Boy's Locker Room	N/A	Concrete Block Wall		Non Suspect ACM	856	SF	0	SF				N/A	N/A	N/A

# 8160 Baldi MS- 2015 2016 AHERA Three-Year Report .xls

1	LL	Hallway from Adaptive Gym to Boy's Locker Room	M	Floor Tile VAT 12" x 12"	8160/01/LL/CC	Assumed	350	SF	0	SF	Black		1	No	1/D
1	LL	Boy's Locker Room	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	160	LF	0	LF			N/A	N/A	N/A
1	LL	Boy's Locker Room	N/A	Fiberglass Pipe Fitting Insulation		Non Suspect ACM	19	EA	0	EA			N/A	N/A	N/A
1	LL	Boy's Locker Room	N/A	Concrete Ceiling		Non Suspect ACM	4216	SF	0	SF			N/A	N/A	N/A
1	LL	Boy's Locker Room	M	Seam Caulking	8160/01/LL/KEM/PD/260 8	Assumed	36	SF	0	SF			1	No	1/D
1	LL	Boy's Locker Room	N/A	Concrete Block Wall		Non Suspect ACM	2860	SF	0	SF			N/A	N/A	N/A
1	LL	Boy's Locker Room	N/A	Cement Floor		Non Suspect ACM	4216	SF	0	SF			N/A	N/A	N/A
1	LL	Boy's Locker Room Restroom	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	14	LF	0	LF		Pipe Chase Access in Room.	N/A	N/A	N/A
1	LL	Boy's Locker Room Restroom	N/A	Fiberglass Pipe Fitting Insulation		Non Suspect ACM	6	EA	0	EA		Pipe Chase Access in Room.	N/A	N/A	N/A
1	LL	Boy's Locker Room Restroom	N/A	Concrete Ceiling		Non Suspect ACM	108	SF	0	SF		Pipe Chase Access in Room.	N/A	N/A	N/A
1	LL	Boy's Locker Room Restroom	M	Seam Caulking	8160/01/LL/KEM/PD/260 8	Assumed	2	SF	0	SF			1	No	1/D
1	LL	Boy's Locker Room Restroom	N/A	Concrete Block Wall		Non Suspect ACM	528	SF	0	SF		Pipe Chase Access in Room.	N/A	N/A	N/A
1	LL	Boy's Locker Room Restroom	N/A	Ceramic Tile Floors		Non Suspect ACM	108	SF	0	SF		Pipe Chase Access in Room.	N/A	N/A	N/A
1	LL	Boy's Locker Room Storage Room	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	15	LF	0	LF		Pipe Chase Access in Room.	N/A	N/A	N/A
1	LL	Boy's Locker Room Storage Room	N/A	Fiberglass Pipe Fitting Insulation		Non Suspect ACM	4	EA	0	EA		Pipe Chase Access in Room.	N/A	N/A	N/A
1	LL	Boy's Locker Room Storage Room	N/A	Concrete Ceiling		Non Suspect ACM	50	SF	0	SF		Pipe Chase Access in Room.	N/A	N/A	N/A
1	LL	Boy's Locker Room Storage Room	M	Seam Caulking	8160/01/LL/KEM/PD/260 8	Assumed	1	SF	0	SF			1	No	1/D
1	LL	Boy's Locker Room Storage Room	N/A	Concrete Block Wall		Non Suspect ACM	330	SF	0	SF		Pipe Chase Access in Room.	N/A	N/A	N/A
1	LL	Boy's Locker Room Storage Room	N/A	Cement Floor		Non Suspect ACM	50	SF	0	SF		Pipe Chase Access in Room.	N/A	N/A	N/A
1	LL	Boy's Locker Room Shower Area	N/A	Concrete Ceiling		Non Suspect ACM	242	SF	0	SF			N/A	N/A	N/A
1	LL	Boy's Locker Room Shower Area	M	Seam Caulking	8160/01/LL/KEM/PD/260 8	Assumed	5	SF	0	SF			1	No	1/D
1	LL	Boy's Locker Room Shower Area	N/A	Concrete Block Wall		Non Suspect ACM	605	SF	0	SF			N/A	N/A	N/A
1	LL	Boy's Locker Room Shower Area	N/A	Ceramic Tile Floors		Non Suspect ACM	242	SF	0	SF			N/A	N/A	N/A
1	LL	Stairwell from Boy's Locker Room to Boy's side of Gym	N/A	Fiberglass Pipe Fitting Insulation		Non Suspect ACM	2	EA	0	EA			N/A	N/A	N/A
1	LL	Stairwell from Boy's Locker Room to Boy's side of Gym	N/A	Concrete Ceiling		Non Suspect ACM	80	SF	0	SF			N/A	N/A	N/A
1	LL	Stairwell from Boy's Locker Room to Boy's side of Gym	N/A	Steel Ceiling		Non Suspect ACM	80	SF	0	SF			N/A	N/A	N/A
1	LL	Stairwell from Boy's Locker Room to Boy's side of Gym	N/A	Concrete Block Wall		Non Suspect ACM	624	SF	0	SF			N/A	N/A	N/A
1	LL	Stairwell from Boy's Locker Room to Boy's side of Gym	N/A	Cement Floor		Non Suspect ACM	160	SF	0	SF			N/A	N/A	N/A
1	LL	Boiler Room	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	600	LF	0	LF			N/A	N/A	N/A
1	LL	Boiler Room	N/A	Fiberglass Pipe Fitting Insulation		Non Suspect ACM	75	EA	0	EA			N/A	N/A	N/A
1	LL	Boiler Room	N/A	Concrete Ceiling		Non Suspect ACM	2520	SF	0	SF			N/A	N/A	N/A
1	LL	Boiler Room	M	Seam Caulking	8160/01/LL/KEM/PD/260 8	Assumed	24	SF	0	SF			1	No	1/D
1	LL	Boiler Room	N/A	Concrete Block Wall		Non Suspect ACM	2652	SF	0	SF			N/A	N/A	N/A
1	LL	Boiler Room	N/A	Vinyl Vibration Damper Cloth		Non Suspect ACM	14	SF	0	SF			N/A	N/A	N/A
1	LL	Boiler Room	N/A	Cement Floor		Non Suspect ACM	2520	SF	0	SF			N/A	N/A	N/A
1	LL	Electrical Room in Boiler Room	N/A	Concrete Ceiling		Non Suspect ACM	464	SF	0	SF			N/A	N/A	N/A
1	LL	Electrical Room in Boiler Room	M	Seam Caulking	8160/01/LL/KEM/PD/260 8	Assumed	8	SF	0	SF			1	No	1/D
1	LL	Electrical Room in Boiler Room	N/A	Concrete Block Wall		Non Suspect ACM	1170	SF	0	SF			N/A	N/A	N/A
1	LL	Electrical Room in Boiler Room	N/A	Cement Floor		Non Suspect ACM	464	SF	0	SF			N/A	N/A	N/A
1	LL	Hallway along back side of Boiler Room to Outside Steps	N/A	Concrete Ceiling		Non Suspect ACM	420	SF	0	SF			N/A	N/A	N/A
1	LL	Hallway along back side of Boiler Room to Outside Steps	N/A	Concrete Block Wall		Non Suspect ACM	1306	SF	0	SF			N/A	N/A	N/A
1	LL	Hallway along back side of Boiler Room to Outside Steps	M	Seam Caulking	8160/01/LL/KEM/PD/260 8	Assumed	6	SF	0	SF			1	No	1/D
1	LL	Hallway along back side of Boiler Room to Outside Steps	N/A	Concrete Wall		Non Suspect ACM	435	SF	0	SF			N/A	N/A	N/A
1	LL	Hallway along back side of Boiler Room to Outside Steps	N/A	Cement Floor		Non Suspect ACM	420	SF	0	SF			N/A	N/A	N/A
1	LL	Seminar Room 18 Restroom	N/A	Ceiling Tile 2' x 4'		NAD	121	SF	0	SF			N/A	N/A	N/A
1	LL	Seminar Room 18 Restroom	N/A	Concrete Block Wall		Non Suspect ACM	88	SF	0	SF			N/A	N/A	N/A
1	LL	Seminar Room 18 Restroom	S	Sheetrock Wall	8160/01/LL/KEM/PD/210 0	Assumed	155	SF	0	SF			1	No	1/D
1	LL	Seminar Room 18 Restroom	M	Floor Tile VAT 12" x 12"	8160/01/LL/CC	Assumed	121	SF	0	SF	Tan		1	No	1/D
1	LL	Seminar Room 18 Special Education	N/A	Ceiling Tile 2' x 4'		NAD	2184	SF	0	SF			N/A	N/A	N/A
1	LL	Seminar Room 18 Special Education	N/A	Concrete Block Wall		Non Suspect ACM	1504	SF	0	SF			N/A	N/A	N/A
1	LL	Seminar Room 18 Special Education	S	Sheetrock Wall	8160/01/LL/KEM/PD/210 0	Assumed	155	SF	0	SF			1	No	1/D
1	LL	Seminar Room 18 Special Education	M	Floor Tile VAT 12" x 12"	8160/01/LL/CC	Assumed	1092	SF	0	SF	Tan		1	No	1/D
1	LL	Seminar Room 18 Special Education	M	Floor Tile VAT 12" x 12"	8160/01/LL/CC	Assumed	1092	SF	0	SF	Orange		1	No	1/D
1	LL	Classroom G-6	N/A	Ceiling Tile 2' x 4'		NAD	840	SF	0	SF			N/A	N/A	N/A
1	LL	Classroom G-6	N/A	Concrete Block Wall		Non Suspect ACM	992	SF	0	SF			N/A	N/A	N/A
1	LL	Classroom G-6	M	Floor Tile VAT 12" x 12"	8160/01/LL/CC	Assumed	840	SF	0	SF	Tan		1	No	1/D
1	LL	Book Storage Room Y-11 across from Classroom Y-3	N/A	Ceiling Tile 2' x 4'		NAD	187	SF	0	SF			N/A	N/A	N/A
1	LL	Book Storage Room Y-11 across from Classroom Y-3	N/A	Concrete Block Wall		Non Suspect ACM	504	SF	0	SF			N/A	N/A	N/A

# 8160 Baldi MS- 2015 2016 AHERA Three-Year Report .xls

1	LL	Book Storage Room Y-11 across from Classroom Y-3	M	Floor Tile VAT 12" x 12"	8160/01/LL/CC	Assumed	187	SF	0	SF	Tan			1	No	1/D
1	LL	Yellow Office Suite File and Locker Room	N/A	Ceiling Tile 2' x 4'		NAD	820	SF	0	SF				N/A	N/A	N/A
1	LL	Yellow Office Suite File and Locker Room	N/A	Concrete Block Wall		Non Suspect ACM	918	SF	0	SF				N/A	N/A	N/A
1	LL	Yellow Office Suite File and Locker Room	M	Sink Undercoat Mastic	8160/01/LL/KEM/PD/260 2	Assumed	4	SF	0	SF				1	No	1/D
1	LL	Yellow Office Suite File and Locker Room	M	Floor Tile VAT 12" x 12"	8160/01/LL/CC	Assumed	820	SF	0	SF	Tan			1	No	1/D
1	LL	Room Y-13 in Yellow Office Suite - Second Counselor's Office on Left Side	N/A	Ceiling Tile 2' x 4'		NAD	90	SF	0	SF				N/A	N/A	N/A
1	LL	Room Y-13 in Yellow Office Suite - Second Counselor's Office on Left Side	N/A	Concrete Block Wall		Non Suspect ACM	342	SF	0	SF				N/A	N/A	N/A
1	LL	Room Y-13 in Yellow Office Suite - Second Counselor's Office on Left Side	M	Floor Tile VAT 12" x 12"	8160/01/LL/CC	Assumed	90	SF	0	SF	Tan			1	No	1/D
1	LL	Room Y-12 in Yellow Office Suite - First Counselor's Office on Left Side	N/A	Ceiling Tile 2' x 4'		NAD	81	SF	0	SF				N/A	N/A	N/A
1	LL	Room Y-12 in Yellow Office Suite - First Counselor's Office on Left Side	N/A	Concrete Block Wall		Non Suspect ACM	324	SF	0	SF				N/A	N/A	N/A
1	LL	Room Y-12 in Yellow Office Suite - First Counselor's Office on Left Side	M	Floor Tile VAT 12" x 12"	8160/01/LL/CC	Assumed	81	SF	0	SF	Tan			1	No	1/D
1	LL	Room Y-15 in Yellow Office Suite - Counselor's Office on Right Side	N/A	Ceiling Tile 2' x 4'		NAD	126	SF	0	SF				N/A	N/A	N/A
1	LL	Room Y-15 in Yellow Office Suite - Counselor's Office on Right Side	N/A	Concrete Block Wall		Non Suspect ACM	414	SF	0	SF				N/A	N/A	N/A
1	LL	Room Y-15 in Yellow Office Suite - Counselor's Office on Right Side	M	Floor Tile VAT 12" x 12"	8160/01/LL/CC	Assumed	126	SF	0	SF	Tan			1	No	1/D
1	LL	Yellow Office Suite Hallway and Waiting Area	N/A	Ceiling Tile 2' x 4'		NAD	225	SF	0	SF				N/A	N/A	N/A
1	LL	Yellow Office Suite Hallway and Waiting Area	N/A	Concrete Block Wall		Non Suspect ACM	540	SF	0	SF				N/A	N/A	N/A
1	LL	Yellow Office Suite Hallway and Waiting Area	M	Floor Tile VAT 12" x 12"	8160/01/LL/CC	Assumed	225	SF	0	SF	Tan			1	No	1/D
1	LL	Book Storage Room across from Classroom Y-2	N/A	Ceiling Tile 2' x 4'		NAD	54	SF	0	SF			No Access; Not Inspected.	N/A	N/A	N/A
1	LL	Book Storage Room across from Classroom Y-2	N/A	Concrete Block Wall		Non Suspect ACM	240	SF	0	SF			No Access; Not Inspected.	N/A	N/A	N/A
1	LL	Book Storage Room across from Classroom Y-2	M	Floor Tile VAT 12" x 12"	8160/01/LL/CC	Assumed	54	SF	0	SF	Tan		No Access; Not Inspected.	1	No	1/D
1	LL	Classroom O-7	N/A	Ceiling Tile 2' x 4'		NAD	924	SF	0	SF				N/A	N/A	N/A
1	LL	Classroom O-7	N/A	Concrete Block Wall		Non Suspect ACM	1024	SF	0	SF				N/A	N/A	N/A
1	LL	Classroom O-7	M	Floor Tile VAT 12" x 12"	8160/01/LL/CC	Assumed	924	SF	0	SF	Tan			1	No	1/D
1	LL	Classroom O-6	N/A	Ceiling Tile 2' x 4'		NAD	924	SF	0	SF				N/A	N/A	N/A
1	LL	Classroom O-6	N/A	Concrete Block Wall		Non Suspect ACM	1024	SF	0	SF				N/A	N/A	N/A
1	LL	Classroom O-6	M	Floor Tile VAT 12" x 12"	8160/01/LL/CC	Assumed	924	SF	0	SF	Tan			1	No	1/D
1	LL	Book Storage Room B-11 across from Classroom B-2	N/A	Ceiling Tile 2' x 4'		NAD	187	SF	0	SF			No Access; Not Inspected.	N/A	N/A	N/A
1	LL	Book Storage Room B-11 across from Classroom B-2	N/A	Concrete Block Wall		Non Suspect ACM	504	SF	0	SF			No Access; Not Inspected.	N/A	N/A	N/A
1	LL	Book Storage Room B-11 across from Classroom B-2	M	Floor Tile VAT 12" x 12"	8160/01/LL/CC	Assumed	187	SF	0	SF	Tan		No Access; Not Inspected.	1	No	1/D
1	LL	Blue Office Suite File and Locker Room	N/A	Ceiling Tile 2' x 4'		NAD	820	SF	0	SF				N/A	N/A	N/A
1	LL	Blue Office Suite File and Locker Room	N/A	Concrete Block Wall		Non Suspect ACM	1098	SF	0	SF				N/A	N/A	N/A
1	LL	Blue Office Suite File and Locker Room	M	Sink Undercoat Mastic	8160/01/LL/KEM/PD/260 2	Assumed	5	SF	0	SF				1	No	1/D
1	LL	Blue Office Suite File and Locker Room	M	Floor Tile VAT 12" x 12"	8160/01/LL/CC	Assumed	820	SF	0	SF	Tan			1	No	1/D
1	LL	Room B-13 in Blue Office Suite - Second Counselor's Office on Left Side	N/A	Ceiling Tile 2' x 4'		NAD	90	SF	0	SF				N/A	N/A	N/A
1	LL	Room B-13 in Blue Office Suite - Second Counselor's Office on Left Side	N/A	Concrete Block Wall		Non Suspect ACM	342	SF	0	SF				N/A	N/A	N/A
1	LL	Room B-13 in Blue Office Suite - Second Counselor's Office on Left Side	M	Floor Tile VAT 12" x 12"	8160/01/LL/CC	Assumed	90	SF	0	SF	Tan			1	No	1/D
1	LL	Room B-12 in Blue Office Suite - First Counselor's Office on Left Side	N/A	Ceiling Tile 2' x 4'		NAD	90	SF	0	SF				N/A	N/A	N/A
1	LL	Room B-12 in Blue Office Suite - First Counselor's Office on Left Side	N/A	Concrete Block Wall		Non Suspect ACM	342	SF	0	SF				N/A	N/A	N/A
1	LL	Room B-12 in Blue Office Suite - First Counselor's Office on Left Side	M	Floor Tile VAT 12" x 12"	8160/01/LL/CC	Assumed	90	SF	0	SF	Tan			1	No	1/D
1	LL	Room B-15 in Blue Office Suite - Counselor's Office on Right Side	N/A	Ceiling Tile 2' x 4'		NAD	135	SF	0	SF				N/A	N/A	N/A
1	LL	Room B-15 in Blue Office Suite - Counselor's Office on Right Side	N/A	Concrete Block Wall		Non Suspect ACM	432	SF	0	SF				N/A	N/A	N/A
1	LL	Room B-15 in Blue Office Suite - Counselor's Office on Right Side	M	Floor Tile VAT 12" x 12"	8160/01/LL/CC	Assumed	135	SF	0	SF	Tan			1	No	1/D
1	LL	Blue Office Suite Hallway and Waiting Area	N/A	Ceiling Tile 2' x 4'		NAD	225	SF	0	SF				N/A	N/A	N/A
1	LL	Blue Office Suite Hallway and Waiting Area	N/A	Concrete Block Wall		Non Suspect ACM	540	SF	0	SF				N/A	N/A	N/A
1	LL	Blue Office Suite Hallway and Waiting Area	M	Floor Tile VAT 12" x 12"	8160/01/LL/CC	Assumed	225	SF	0	SF	Tan			1	No	1/D
1	LL	"Hub" Copy Room between Blue and Yellow Office Suites	N/A	Ceiling Tile 2' x 4'		NAD	400	SF	0	SF				N/A	N/A	N/A
1	LL	"Hub" Copy Room between Blue and Yellow Office Suites	N/A	Concrete Block Wall		Non Suspect ACM	720	SF	0	SF				N/A	N/A	N/A
1	LL	"Hub" Copy Room between Blue and Yellow Office Suites	M	Floor Tile VAT 12" x 12"	8160/01/LL/CC	Assumed	400	SF	0	SF	Orange			1	No	1/D
1	LL	Room B-17 Food Service Closet next to Seminar Room 18	X	X	X	X	X	SF	X	SF	X		No Access; Not Inspected.	X	X	X
1	LL	Hallway from Seminar Room 17 to Classroom G-4	N/A	Ceiling Tile 2' x 4'		NAD	1860	SF	1	SF				N/A	N/A	N/A
1	LL	Hallway from Seminar Room 17 to Classroom G-4	N/A	Concrete Block Wall		Non Suspect ACM	2232	SF	0	SF				N/A	N/A	N/A
1	LL	Hallway from Seminar Room 17 to Classroom G-4	M	Floor Tile VAT 12" x 12"	8160/01/LL/CC	Assumed	1860	SF	0	SF	Black			1	No	1/D
1	LL	Hallway from Classroom G-5 to end of Lockers passed Room Y-17	N/A	Ceiling Tile 2' x 4'		NAD	882	SF	1	SF				N/A	N/A	N/A
1	LL	Hallway from Classroom G-5 to end of Lockers passed Room Y-17	N/A	Concrete Block Wall		Non Suspect ACM	1764	SF	0	SF				N/A	N/A	N/A

# 8160 Baldi MS- 2015 2016 AHERA Three-Year Report .xls

1	LL	Hallway from Classroom G-5 to end of Lockers passed Room Y-17	M	Floor Tile VAT 12" x 12"	8160/01/LL/CC	Assumed	882	SF	0	SF	Black			1	No	1/D
1	LL	Hallway between Classrooms Y-1 and O-1	N/A	Ceiling Tile 2' x 4'		NAD	1176	SF	0	SF				N/A	N/A	N/A
1	LL	Hallway between Classrooms Y-1 and O-1	N/A	Concrete Block Wall		Non Suspect ACM	1200	SF	0	SF				N/A	N/A	N/A
1	LL	Hallway between Classrooms Y-1 and O-1	M	Floor Tile VAT 12" x 12"	8160/01/LL/CC	Assumed	1176	SF	0	SF	Black			1	No	1/D
1	LL	Hallway from Lockers next to Classroom O-1 to Classroom B-5	N/A	Ceiling Tile 2' x 4'		NAD	882	SF	2	SF				N/A	N/A	N/A
1	LL	Hallway from Lockers next to Classroom O-1 to Classroom B-5	N/A	Concrete Block Wall		Non Suspect ACM	1764	SF	0	SF				N/A	N/A	N/A
1	LL	Hallway from Lockers next to Classroom O-1 to Classroom B-5	M	Floor Tile VAT 12" x 12"	8160/01/LL/CC	Assumed	882	SF	0	SF	Black			1	No	1/D
1	LL	Hallway from Classroom B-4 to Seminar Room 19	N/A	Ceiling Tile 2' x 4'		NAD	1860	SF	2	SF				N/A	N/A	N/A
1	LL	Hallway from Classroom B-4 to Seminar Room 19	N/A	Concrete Block Wall		Non Suspect ACM	2232	SF	0	SF				N/A	N/A	N/A
1	LL	Hallway from Classroom B-4 to Seminar Room 19	M	Floor Tile VAT 12" x 12"	8160/01/LL/CC	Assumed	1860	SF	0	SF	Black			1	No	1/D
1	A	X	X	X	X	X	X	X	X	X	X	None		X	X	X
1	C	X	X	X	X	X	X	X	X	X	X	None		X	X	X

## **Section III    Certificates**

### **A. Management Planner/Building Inspector Certificates**



## Section III – A

### Management Planner/Building Inspector Certificates

These charts indicate the Name, Course Date, Expiration Date and Corresponding Certificate Number of the Management Planner and Building Inspector of individuals that participated in the AHERA 3 Year Inspection and Management Plan process of 2015/2016.

Management Planner	Date Granted	Expiration Date	Certificate Number
Monique Causley	2/15/2015	2/16/2016	ACC-0215-8-010
Monique Causley	2/16/2016	2/17/2017	ACC-0216-8-001
Megan Vala	5/22/2015	6/22/2016	740728
Mary Anne Lerro	4/5/2016	4/5/2017	742327

Building Inspector	Date Granted	Expiration Date	Certificate Number
Scott Magee	8/15/2015	8/15/2016	70016699C
William Garrity	8/15/2015	8/15/2016	70016699A
Bernard Brunner	10/2/2015	8/2/2016	45397
Mary Anne Lerro	3/3/2015	3/3/2016	740092
Mary Anne Lerro	4/5/2016	4/5/2017	742322
James Madden	12/11/2014	12/11/2015	ACC-1214-6-010
James Madden	12/3/2015	12/3/2016	ACC-1215-6-018
Troy Ray	3/15/2015	3/19/2016	ACC-0355-6-011
Ananth Vinjamuri	9/29/2015	9/29/2016	374
Shelton Williams	9/29/2015	9/29/2016	375
Paul Davis	2/12/2015	2/12/2016	ACC-0215-6-015
Paul Davis	2/2/2016	2/2/2017	741836
Bernard Bryson	2/16/2015	2/16/2016	ACC-0125-6-031
Bernard Bryson	2/15/2016	2/15/2017	ACC-0216-6-005
Alexander Roman	9/18/2015	9/18/2016	EHSBIR-150619-008
Norm Harrison	9/2/2015	9/2/2016	ACC-0915-6-011
Kelly Mayberry	2/20/2015	2/20/2016	EHSBIR-150220-005
Kelly Mayberry	2/18/2016	2/18/2017	EHSBIR-160218-006
Andrew Hine	5/6/2015	5/6/2016	AI05042015-3
Maryellen Leotta	2/12/2015	2/12/2016	ACC-0215-6-024

# Certificate of Completion

*awarded to*

**Monique Causley**

*for successfully completing the prescribed course of study in*

## Pennsylvania Asbestos Management Planner Refresher Course

under TSCA Title II

*presented by*

ACCESS TRAINING SERVICES, INC.  
7921 River Road, Pennsauken, NJ 08110  
(856) 665-3449

2/16/15

*Course Date*

N/A

*Exam Date*

2/16/16

*Expiration Date*

Not Provided

*Social Security Number*

ACC-0215-8-010

*Certificate Number*

Mark K. Schlüger  
*Training Director*

# Certificate of Completion

*awarded to*

**Monique Causley**

*for successfully completing the prescribed course of study in*

## Pennsylvania Asbestos Management Planner Refresher Course

under TSCA Title II

*presented by*

**ACCESS TRAINING SERVICES, INC.**  
7921 River Road, Pennsauken, NJ 08110  
(856) 665-3449

**2/15/16**

*Course Date*

**N/A**

*Exam Date*

**2/15/17**

*Expiration Date*

**Not Provided**

*Social Security Number*

**ACC-0216-8-001**

*Certificate Number*

**Mark K. Schlüger**  
*Training Director*

# *Certificate of Training*

## CRITERION LABORATORIES, INC.

HEREBY CERTIFIES THAT

Megan Vala

HAS SUCCESSFULLY COMPLETED A 16 HOUR COURSE ENTITLED

Asbestos Management Planner Initial

INCLUDING CLASSROOM INSTRUCTION

05/21/2015 to 05/22/2015

Exam passed on this 22nd day of May 2015 - Score - 94

Approved for AHERA Accreditation Under TSCA Title II

3370 Progress Drive, Suite J  
Bensalem, PA 19020  
(215) 244-1300 - Phone  
(215) 244-4349 - Fax  
www.criterionlabs.com

*Course is conducted in English*

DIRECTOR:



*James A. Welts, CIH, President*

# *Certificate of Training*

## CRITERION LABORATORIES, INC.

HEREBY CERTIFIES THAT

Mary Anne Lerro

HAS SUCCESSFULLY COMPLETED A 4 HOUR COURSE ENTITLED

Asbestos Management Planner Refresher

INCLUDING CLASSROOM INSTRUCTION


on this 5th day of April 2016

Approved for AHERA Accreditation Under TSCA Title II

3370 Progress Drive, Suite J  
Bensalem, PA 19020  
(215) 244-1300 - Phone  
(215) 244-4349 - Fax  
www.criterionlabs.com

*Course is conducted in English*

DIRECTOR:



*James A. Welts, CIH, President*

# EMSL ANALYTICAL, INC.

Certifies that

Scott Magee

has successfully completed the course of study for the

## Asbestos Building Inspector Refresher Course

for Accreditation under TSCA Title II

EMSL Certificate No. 70016699C


### Approved by:

PA Dept. of Labor and Industry  
Accreditation # 137

Course Date: 8/15/2015  
Granted: 8/15/2015  
Expiration Date: 8/15/2016

### Sponsored by:

EMSL Analytical, Inc.  
200 Route 130 North  
Cinnaminson, NJ 08077  
Phone: (800) 220-3675  
Fax: (856) 786-5973  
[www.emsl.com](http://www.emsl.com)



*Michael P. Menz*

Michael P. Menz, CIH  
Training Director

Environmental, Mold, Bacteria, IAQ, Asbestos, Lead, Forensic and Materials Testing Since 1981



# EMSL ANALYTICAL, INC.

Certifies that

William Garrity

has successfully completed the course of study for the

## Asbestos Building Inspector Refresher Course for Accreditation under TSCA Title II

EMSL Certificate No. 70016699A


### Approved by:

PA Dept. of Labor and Industry  
Accreditation # 137

Course Date: 8/15/2015  
Granted: 8/15/2015  
Expiration Date: 8/15/2016

### Sponsored by:

EMSL Analytical, Inc.  
200 Route 130 North  
Cinnaminson, NJ 08077  
Phone: (800) 220-3675  
Fax: (856) 786-5973  
[www.emsl.com](http://www.emsl.com)



*Michael P. Menz*

Michael P. Menz, CIH  
Training Director

Environmental, Mold, Bacteria, IAQ, Asbestos, Lead, Forensic and Materials Testing Since 1981

45397

# *National Asbestos & Environmental Training Institute*

## CERTIFICATE OF COMPLETION

AHERA/EPA Accredited Per 40 CFR Part 763  
Asbestos Accreditation under TSCA Title II

*This is to certify that*

***Bernard Brunner, Jr.***

*Successfully completed the course entitled*

**1/2-Day New York State/EPA/AHERA Asbestos Building Inspector Annual Refresher on  
October 2, 2015**

*Examination Passed October 2, 2015*

*Expiration Date on October 2, 2016*

  
*Doris L. Adler*  
*President, NAEETI*

Per 10 NYCRR Part 73.2 (L) (1), DOH 2832 Certificate of Completion of Asbestos  
Safety Training is the only official record of training for N.Y.S. students.

Language: English

ABIH 1/2 CM POINT

3321 Doris Avenue, Building B, Ocean, NJ 07712

Phone (732) 531-5571

Fax (732) 531-5956

[www.naeti.com](http://www.naeti.com)



Number 740092

Expiration Date:  
03/03/2016

# *Certificate of Training*

CRITERION LABORATORIES, INC.

HEREBY CERTIFIES THAT

Mary Anne Lerro

HAS SUCCESSFULLY COMPLETED A 4 HOUR COURSE ENTITLED

Asbestos Building Inspector Refresher

on this 3rd day of March 2015

Exam passed on this 3rd day of March 2015 - Score - 84

Approved for AHERA Accreditation Under TSCA Title II

3370 Progress Drive, Suite J  
Bensalem, PA 19020  
(215) 244-1300 - Phone  
(215) 244-4349 - Fax  
[www.criterionlabs.com](http://www.criterionlabs.com)

Course is conducted in English

DIRECTOR:

*James A. Welts*  
James A. Welts, CIH, President

# *Certificate of Training*

## CRITERION LABORATORIES, INC.

HEREBY CERTIFIES THAT

Mary Anne Lerro

HAS SUCCESSFULLY COMPLETED A 4 HOUR COURSE ENTITLED

Asbestos Building Inspector Refresher

INCLUDING CLASSROOM INSTRUCTION

on this 5th day of April 2016


Exam passed on this 5th day of April 2016 - Score - 88

Approved for AHERA Accreditation Under TSCA Title II

3370 Progress Drive, Suite J  
Bensalem, PA 19020  
(215) 244-1300 - Phone  
(215) 244-4349 - Fax  
www.criterionlabs.com

Course is conducted in English

DIRECTOR:



James A. Welts, CIH, President

# Certificate of Completion

**James Madden**

*for successfully completing the prescribed course of study in*

## **Pennsylvania Asbestos Building Inspector Refresher Course**

under TSCA Title II

*presented by*  
**ACCESS TRAINING SERVICES, INC.**  
7921 River Road, Pennsauken, NJ 08110  
(856) 665-3449

**12/11/14**

*Course Date*

**N/A**

*Exam Date*

**12/11/15**

*Expiration Date*

**Not Provided**

*Social Security Number*

**ACC-1214-6-010**

*Certificate Number*

**Mark K. Schlüger**  
*Training Director*

# Certificate of Completion

**James Madden**

*for successfully completing the prescribed course of study in*

## **Pennsylvania Asbestos Building Inspector Refresher Course**

under TSCA Title II

*presented by*

**ACCESS TRAINING SERVICES, INC.**  
7921 River Road, Pennsauken, NJ 08110  
(856) 665-3449

**12/3/15**

*Course Date*

**N/A**

*Exam Date*

**12/3/16**

*Expiration Date*

**Not Provided**

*Social Security Number*

**ACC-1215-6-018**

*Certificate Number*

**Mark K. Schlüger**  
*Training Director*

# Certificate of Completion

**Troy A. Ray**


*for successfully completing the prescribed course of study in*

## **Pennsylvania Asbestos Building Inspector Refresher Course**

under TSCA Title II

*presented by*

**ACCESS TRAINING SERVICES, INC.**  
7921 River Road, Pennsauken, NJ 08110  
(856) 665-3449

3/19/15	N/A	3/19/16
<i>Course Date</i>	<i>Exam Date</i>	<i>Expiration Date</i>
Not Provided	ACC-0355-6-011	
<i>Social Security Number</i>	<i>Certificate Number</i>	<b>Mark K. Schlager</b> <i>Training Director</i>

# CERTIFICATE NO 374

G&C Environmental Services, Inc. (#294)  
2 Street Road, Newtown Square, Pennsylvania 19073  
Telephone: (610) 993-9202 Facsimile: (610) 993-9232  
Email: Training@gcenviro.com  
www.GCenviro.com

This document certifies that Ananth K. Vinjamuri has successfully completed this  
State of New York Department of Health Approved AHERA BUILDING INSPECTOR

REFRESHER COURSE, completed as required for asbestos accreditation under the Toxic

Substances Control Act, Title II. This course was held from 09/29/2015 to 09/29/2015.  
MM DD YR MM DD YR

The examination date was 09/29/2015. This certificate expires one year from the date of  
MM DD YR MM DD YR  
successful completion of the examination 09/29/2016.  
MM DD YR

*The official record of successful training completion is the New York State Department of  
Health certificate of asbestos safety training completion (DPH 2832).*

Gail M. Conner  
Training Director

Gail M. Conner

# CERTIFICATE NO 375

G&C Environmental Services, Inc. (#294)  
2 Street Road, Newtown Square, Pennsylvania 19073  
Telephone: (610) 993-9202 Facsimile: (610) 993-9232  
Email: Training@gcenviro.com  
www.GCenviro.com

This document certifies that Shelton Williams has successfully completed this  
State of New York Department of Health Approved AHERA BUILDING INSPECTOR

REFRESHER COURSE, completed as required for asbestos accreditation under the Toxic

Substances Control Act, Title II. This course was held from 09/29/2015 to 09/29/2015.

The examination date was 09/29/2015. This certificate expires one year from the date of

successful completion of the examination 09/29/2016.

*The official record of successful training completion is the New York State Department of  
Health certificate of asbestos safety training completion (DPH 2832).*

Gail M. Conner  
Training Director

Gail M. Conner



# Certificate of Completion

**Paul M. Davis**

*for successfully completing the prescribed course of study in*

## **Pennsylvania Asbestos Building Inspector Refresher Course**

under TSCA Title II

*presented by*

**ACCESS TRAINING SERVICES, INC.**  
7921 River Road, Pennsauken, NJ 08110  
(856) 665-3449

**2/12/15**

*Course Date*

**N/A**

*Exam Date*

**2/12/16**

*Expiration Date*

**Not Provided**

*Social Security Number*

**ACC-0215-6-015**

*Certificate Number*

**Mark K. Schlüger**  
*Training Director*



# *Certificate of Training*

**CRITERION LABORATORIES, INC.**

HEREBY CERTIFIES THAT

**Paul M. Davis**

HAS SUCCESSFULLY COMPLETED A 4 HOUR COURSE ENTITLED

**Asbestos Building Inspector Refresher**

INCLUDING CLASSROOM INSTRUCTION

on this 2nd day of February 2016

Exam passed on this 2nd day of February 2016 - Score - 92

Approved for AHERA Accreditation Under TSCA Title II

3370 Progress Drive, Suite J  
Bensalem, PA 19020  
(215) 244-1300 - Phone  
(215) 244-4349 - Fax  
[www.criterionlabs.com](http://www.criterionlabs.com)

*Course is conducted in English*

DIRECTOR:



*James A. Welch, CIH, President*

# Certificate of Completion

**Bernard J. Bryson**


*for successfully completing the prescribed course of study in*

## **Pennsylvania Asbestos Building Inspector Refresher Course**

under TSCA Title II

*presented by*

**ACCESS TRAINING SERVICES, INC.**  
7921 River Road, Pennsauken, NJ 08110  
(856) 665-3449

<b>2/16/15</b>	<b>N/A</b>	<b>2/16/16</b>
<i>Course Date</i>	<i>Exam Date</i>	<i>Expiration Date</i>
<b>Not Provided</b>	<b>ACC-0125-6-031</b>	
<i>Social Security Number</i>	<i>Certificate Number</i>	<b>Mark K. Schlager</b> <i>Training Director</i>

# Certificate of Completion

**Bernard J. Bryson**

*for successfully completing the prescribed course of study in*

## **Pennsylvania Asbestos Building Inspector Refresher Course**

under TSCA Title II

*presented by*

**ACCESS TRAINING SERVICES, INC.**  
7921 River Road, Pennsauken, NJ 08110  
(856) 665-3449

**2/15/16**

*Course Date*

**N/A**

*Exam Date*

**2/15/17**

*Expiration Date*

**Not Provided**

*Social Security Number*

**ACC-0216-6-005**

*Certificate Number*

**Mark K. Schlager**  
*Training Director*

**EHS TRAINING INSTITUTE, INC.**  
A Division of BATTI, Inc.

# **Certificate of Completion**

## **AHERA Building Inspector**

**(Refresher)**

**Awarded To:**

**Alexander Roman**

SS#:XXX-XX-1743  
Who has completed this 4-hour course and examination,  
EPA Approved under TSCA Title II  
AHERA / ASHARA Rule  
40 CFR Part 763.

**EHS TRAINING INSTITUTE, INC.**

A Division of BATTI, Inc.

*Delaware Industrial Park • 6 Garfield Way*

*Newark, DE 19713-5817*

*(302) 737-3376 • Fax (302) 737-5764*

**Course Date: September 18, 2015**

**Date of Expiration: September 18, 201**

**Certification Number : EHSBIR 150619-008**

  
Todd K. Zeisloff, Instructor

  
Neeraj K. Batta, President

# Certificate of Completion

**Norman Harrison**

*for successfully completing the prescribed course of study in*

## **Pennsylvania Asbestos Building Inspector Refresher Course**

under TSCA Title II

*presented by*

**ACCESS TRAINING SERVICES, INC.  
7921 River Road, Pennsauken, NJ 08109  
(856) 665-3449**

**9/2/15**

*Course Date*

**N/A**

*Exam Date*

**9/2/16**


*Expiration Date*

**Not Provided**

*Social Security Number*

**ACC-0915-6-011**

*Certificate Number*

  
**Mark K. Schlager**  
*Training Director*



**EHS TRAINING INSTITUTE, INC.**  
A Division of BATTI, Inc.

# **Certificate of Completion**

## **AHERA Building Inspector**

**(Refresher)**

**Awarded To:**

**Kelly Mayberry**

SS#:XXX-XX-1551

Who has completed this 4-hour course and examination,

EPA Approved under TSCA Title II

AHERA / ASHARA Rule

40 CFR Part 763.

**EHS TRAINING INSTITUTE, INC.**

A Division of BATTI, Inc.

*Delaware Industrial Park • 6 Garfield Way*

*Newark, DE 19713-5817*

*(302) 737-3376 • Fax (302) 737-5764*

**Course Date: February 20, 2015**

**Date of Expiration: February 20, 2016**

**Certification Number : EHSBIR 150220-005**

  
**Todd K. Zeislott, Instructor**

  
**Neeraj K. Batta, President**

**EHS TRAINING INSTITUTE, INC.**

A Division of BATA, Inc.

# **Certificate of Completion**

## **AHERA Building Inspector**

**(Refresher)**

**Awarded To:**

***Kelly Mayberry***

SS#:XXX-XX-1551

Who has completed this 4-hour course and examination,

EPA Approved under TSCA Title II

AHERA / ASHARA Rule

40 CFR Part 763.

**EHS TRAINING INSTITUTE, INC.**

A Division of BATA, Inc.

*Delaware Industrial Park • 6 Garfield Way*

*Newark, DE 19713-5817*

*(302) 737-3376 • Fax (302) 737-5764*

**Course Date: February 18, 2016**

**Date of Expiration: February 18, 2017**

**Certification Number : EHSBIR 160218-006**

**Todd K. Zeisloff, Instructor**

**Neeraj K. Batta, President**

# AEROSOL MONITORING & ANALYSIS, INC.

*This is to certify that*  
**ANDREW HINE**

*has met the attendance requirements and successfully completed*

*the course entitled*

## **3-DAY EPA AHERA INSPECTOR**

*For Accreditation Under TSCA Title II*

05/04/2015 to 05/06/2015

**Course Date**

05/06/2015

**Exam Date**

5/6/2016

**Expiration Date**

STEVE SIERACKI

**Principal Instructor**

*Steve Sieracki*

A105042015-3

**Certification No.**

E. Rush Barnett

**Course Director**

*E. Rush Barnett*

1331 Ashton Road

P.O.Box 646

Hanover, MD 21076

P: 410-684-3327

F: 410-684-3724

[www.amatraining.com](http://www.amatraining.com)



# Certificate of Completion

**Maryellen Leotta**

*for successfully completing the prescribed course of study in*

## **Pennsylvania Asbestos Building Inspector Refresher Course**

under TSCA Title II

*presented by*

**ACCESS TRAINING SERVICES, INC.**  
7921 River Road, Pennsauken, NJ 08110  
(856) 665-3449

**2/12/15**

*Course Date*

**N/A**

*Exam Date*

**2/12/16**

*Expiration Date*

**Not Provided**

*Social Security Number*

**ACC-0215-6-024**

*Certificate Number*

**Mark K. Schlager**  
*Training Director*

**Section IV      Cross Reference Table**

# Asbestos Hazard Emergency Response Act (AHERA) Environmental Compliance Audit Cross Reference Table

In response to the AHERA Environmental Compliance Audit a Cross Reference Table has been prepared for inclusion into the Environmental Management Plan. The purpose of this Cross Reference Table is to link the following documents to the AHERA Management Plan.

<b>Cross Reference Table</b>	
3 Year Reinspection Report follows this Cross Reference Table documentation.	
<b>Subject Matter</b>	<b>Location of Required Documents</b>
Designated Person	Pages 1 - 3
Annual Notification	Pages 4 - 5
6 Month Periodic Surveillance Outline of Events	Page 6
3 Year Re-inspections Outline of Events	Page 7
Asbestos Management Program (operations and maintenance)	Pages 8 - 19
Asbestos Investigation Report (AIR)	Attachment 1 Letter Dated August 4, 2006
Training (included in the Asbestos Management Program)	<p>The original records are centralized at the School District's Environmental Library. Copies are maintained on staff and are required to be maintained in the latest Reinspection Report.</p> <p>2 hour awareness training records for all Building Engineers, Custodian Assistants and maintenance personnel</p> <p>40 hour worker/supervisor training records for the OEMS A-Team and various AST tradesmen.</p>
Response Actions (monthly mailings if applicable)	The original documents are on file at the School District's Environmental Library.
	Copies of the original are mailed to the Schools Main Office for retention with the Management Plan documentation. These documents are typically kept separate from the management plan in an update binder due to the potential volume of response action reports.

## **SCHOOL DISTRICT OF PHILADELPHIA**

### **ASBESTOS DESIGNATED PERSON**

**Gerald F Junod**  
**Office of Capital Programs**  
**Environmental Management & Services**  
**440 N Broad Street, 3<sup>rd</sup> Floor**  
**Philadelphia, PA 19130**  
**Telephone: 215 400 6738**  
**Fax: 215 400 4751**

<b>Drexel University- Asbestos Building Inspector Course</b>	<b>January 9-11, 1989 24 Hours</b>
<b>Drexel University- Asbestos Management Planner Course</b>	<b>January 12-13, 1989 16 Hours</b>
<b>Criterion Laboratories, Inc. - Asbestos Management Planner Course</b>	<b>October 11-12, 2012 16 Hours</b>

<b><u>Annual Building Inspector Refreshers</u></b> <b>4 Hours</b> <b>Drexel University</b> <b>Criterion Laboratories, Inc</b> <b>Access Training Services, Inc.</b>	<b>1990 to Present</b>
---	------------------------

<b><u>Annual Building Management Planner Refreshers</u></b> <b>4 Hours</b> <b>Drexel University</b> <b>Criterion Laboratories, Inc</b> <b>4 Hours</b>	<b>1990 to 1994</b>    <b>2013 to Present</b>
---	---

#### **Environmental Manager, School District of Philadelphia**

**Manages the design and implementation of asbestos and lead projects for the Capital Improvement Program and other District Departments including Facilities & Operations and Information Technology. Ensures that asbestos abatement and lead remediation projects are expertly designed and executed in accordance with industry best management practice standards and regulations.**

#### **Manager, City of Philadelphia Asbestos Control Program**

**Served as the Asbestos Control Program Manager for the City of Philadelphia, Department of Public Health, Air Management Services, Asbestos Control Unit from August 1, 2003 through October 23, 2006.**

#### **Mid Atlantic Regional Environmental Consortium (MAREC)**

**Former member with attendance and participation commitments of all quarterly EPA Region III and yearly National Asbestos Regulatory Conferences sponsored by the EPA and the National Conference of State Legislators respectively as a representative for the City of Philadelphia Department of Public Health Air Management Services from 1994 through 2006.**

#### **Philadelphia Environmental Task Force**

**Former member of the Philadelphia Environmental Task force as a representative and point of contact for the City of Philadelphia Department of Public Health Air Management Services Asbestos Control Unit from 2002 through 2006.**

**Asbestos Instructor**

Worked as the primary instructor for the initial and annual Asbestos Project Inspector training and licensing program as mandated by City of Philadelphia Department of Public Health Asbestos Control Regulations from August 1994 through October 2006.

Worked as a lead instructor with an Environmental Consulting Firm and approved by the US EPA for the initial and annual refresher training courses for various asbestos occupational disciplines such as the Building Inspector, Management Planner and Worker/Supervisor from 1991 through 1994.

I certify that the general, local agency responsibilities as stipulated in Section 763.84 will be met.



Gerald F. Junod

Asbestos Designated Person

Environmental Manager

Office of Environmental Management and Services

## **SCHOOL DISTRICT OF PHILADELPHIA**

### **Accreditation Information Statement**

**All persons who inspect for Asbestos Containing Building Materials (ACBM) and who will design or carry out response actions with respect to assumed and confirmed ACBM, will be accredited by an EPA approved course and/or a State Contractors Accreditation Program under Sections 206 (c) and 206 (b) of Title II of the ACT.**



**Gerald F. Junod  
Asbestos Designated Person  
Environmental Manager  
Office of Environmental Management and Services**

SCHOOL DISTRICT OF PHILADELPHIA  
OFFICE OF CAPITAL PROGRAMS  
440 NORTH BROAD STREET, SUITE 373  
PHILADELPHIA, PENNSYLVANIA 19130

OFFICE OF ENVIRONMENTAL MANAGEMENT AND SERVICES

PHONE (215)-400-4750

September 2015

TO: Principals  
Building Administrators/Occupants  
Parents/Guardians

FROM: Fran Burns  
Chief Operating Officer

Francine Locke, M.S., Director  
Office of Environmental Management and Services

SUBJECT: Annual EPA Notification Letter


Pursuant to the Federal Environmental Protection Agency (EPA) mandate, as required by 40 C.F.R. 763.84 (c)(d) of public access to environmental records, this letter is to acknowledge the availability of your facility's Asbestos Hazard Emergency Response Act (AHERA) Management Plan.


Each member of the school staff, parents/guardians, temporary workers and/or contractors, are required to receive a copy of the Notification Letter. At the direction of the Principal, a copy is to be posted on the bulletin boards and an appropriate amount of copies are to be generated for distribution.

Note: The AHERA Three-Year Reinspection reports, in colored binders; White with Pink, Tan, Black, Red, Dark Blue, Green, Yellow and White, are Federal EPA mandated inspection documents. The School District of Philadelphia is subject to severe monetary penalties if the reports and associated paperwork are not available to the EPA and the public upon request.

It is incumbent on designated school personnel to gather and retain this data as it is delivered, in one location for future review. Acceptable locations include the Principal's Office or Main Office for the primary data. The Building Engineer should maintain any secondary or duplicate copies.

If you have any questions, please call 215-400-4750. Thank you for your cooperation.

  
\_\_\_\_\_  
Fran Burns  
Chief Operating Officer

  
\_\_\_\_\_  
Francine Locke, M.S., Director  
Office of Environmental Management  
and Services

c: Danielle Floyd

AHERA-4  
8/21/15



**School District of Philadelphia**  
**OFFICIAL NOTICE**

**PLEASE POST**

September 2015

TO: Principals  
Building Administrators  
Building Engineers  
Building Occupants  
Parents/Guardians

FROM: Fran Burns  
Chief Operating Officer

Francine Locke, M.S., Director  
Office of Environmental Management and Services

SUBJECT: Annual Notification Letter: Asbestos Hazard Emergency Response Act

The Federal Register published on October 30, 1987, Subpart E, in Schools: Final Rule and Notice, 763.84 (c)(d) states that each local education agency shall ensure that workers and building occupants or guardians are to be informed at least once each school year about inspections, response actions and post-response action activities including re-inspections and periodic surveillance activities. The School District as the Local Education Agency (LEA), retains such reports that are available for public inspection in the Office of the Principal or Building Administrator.

The Principal or Building Administrator is required to do the following with this notification:

- 1) Post in a Public Place or Main Office
- 2) Inform Building Occupants
- 3) Send a copy of this notification to Parents or Guardians
- 4) Insert a copy into the latest AHERA Three-Year Reinspection report (white/pink binder) in your office or facility.

A handwritten signature of Fran Burns in black ink, positioned above a horizontal line.

Fran Burns  
Chief Operating Officer

A handwritten signature of Francine Locke in black ink, positioned above a horizontal line.

Francine Locke, M.S., Director  
Office of Environmental Management  
and Services

c: Danielle Floyd

AHERA-4a  
8/21/15



SCHOOL DISTRICT OF PHILADELPHIA  
Education Center  
440 North Broad Street  
Philadelphia, Pennsylvania 19130

Office of Environmental Management and Services

215-400-4750

AHERA  
Six Month Surveillance  
Outline of Events

- Pursuant to the Federal Environmental Protection Agency (EPA) mandate, as required by 40 CFR 763.92(b), the following procedure is to be implemented. At least once every six (6) months after a Management Plan is in effect, each Local Education Agency (LEA) shall conduct a periodic surveillance in each building that it owns or leases that contains Asbestos Containing Building Materials (ACBM) or is assumed to contain ACBM.
- The first Bi-Annual Inspection starts in the Spring (March, April, May) and again in the Fall (October, November, December) of each year. The Building Engineer/Assistant should assist the Building Inspector with appropriate access to all areas including (Crawlspace/Attics) and rooms in the facility. There is no action required of the Principal.
- The Building Inspector shall visually inspect all areas that are identified in the Management Plan as ACBM or assumed ACBM. The date of the surveillance is recorded, the inspectors name and any changes in the conditions of the materials.
- The Building Inspector shall make a copy of the inspection document and insert into the front of the latest Management Plan (AHERA Three Year Reinspection report). The original document is returned to the LEA's Environmental Library and filed.

SCHOOL DISTRICT OF PHILADELPHIA  
Education Center  
440 North Broad Street  
Philadelphia, Pennsylvania 19130

Office of Environmental Management and Services

215-400-4750

AHERA  
Three Year Reinspection  
Outline of Events

- Pursuant to the Federal Environmental Protection Agency (EPA) mandate, as required by 40 CFR 763.85(b) the following procedure is to be implemented. At least once every three (3) years after a Management Plan is in effect, each Local Education Agency (LEA) shall conduct a reinspection of each building that it owns or leases that contains Asbestos Containing Building Material's (ACBM's) or is assumed to contain ACBM.
- Subsequent Three Year Re-inspections (2009, 2012, 2015, etc) shall start in the Fall (October, November, December, January). The Building Engineer/Assistant should assist the Building Inspector with appropriate access to all areas including (Crawlspaces/Attics) and rooms in the facility. There is no action required of the Principal.
- An accredited Building Inspector shall visually inspect and touch to determine friability, all areas that are identified in the Management Plan as ACBM or assumed ACBM. The date of the surveillance is recorded, the inspectors name and any changes in the conditions of the materials. The Building Inspectors state of accreditation and license number is required.
- After the inspection, the Building Inspector shall make a copy of the inspection documents and insert into the front of the latest Management Plan (AHERA Three Year Reinspection report). The original document is returned to the LEA's Environmental Library and filed.
- The Building Inspector shall return the reinspection data to the Management Planner to be assessed and determine appropriate response actions and a report issued (AHERA Three Year Reinspection report). One copy of the report is delivered to the schools Principal to be permanently retained with all previous environmental data. Another copy is retained in the LEA's Environmental Library.



**School District of Philadelphia**  
Office of Environmental Management & Services  
440 North Broad Street  
Philadelphia, PA 19130  
(215) 400-4750

**School District of Philadelphia  
Asbestos Management Program**

## TABLE OF CONTENTS

<b>Definitions.....</b>	<b>Page 9</b>
<b>1. Introduction.....</b>	<b>Page 10</b>
<b>2. Summary of Asbestos Management Plan</b>	
<b>3. Asbestos Management Plan Execution.....</b>	<b>Page 11</b>
a. General Execution	
<b>4. Summary of Program Execution</b>	
a. Asbestos Management Plan Execution	
<b>5. Responsibilities</b>	
a. OEMS	
b. Asbestos Worker/Supervisor “A-TEAM”.....	<b>Page 12</b>
c. Asbestos Designated Person	
d. Supervisor or Project Manager (Capital, Maintenance & Facilities)	
e. Employee Capital.....	<b>Page 13</b>
f. Employee Maintenance	
g. Employee Facilities and Custodial	
<b>6. Requirements.....</b>	<b>Page 14</b>
a. Employee Exposure Monitoring	
b. Employee Notification	
c. Observation of Monitoring	
d. Training Program	
e. Access of Information	
f. Record Keeping	
<b>7. AHERA O&amp;M Plan.....</b>	<b>Page 15</b>
a. Controls	
<b>8. O&amp;M Response Actions.....</b>	<b>Page 16</b>
a. Facility Maintenance Isolation of Area	
b. Unlikely Contact with ACM/PACM	
c. Accidental Disturbance of ACM/PACM	
d. Planned Disturbance of ACM/PACM	
e. Miscellaneous ACM/PACM.....	<b>Page 17</b>
f. Vinyl Asbestos Floor Tile	
g. Mastic/Adhesives	
h. Woven Vibration Dampers	
i. Other Work Practices	
j. Fiber Release Episodes	
<b>9. References and Resources.....</b>	<b>Page 18</b>

## **DEFINITIONS / ACRONYMS**

<b>ACM/PACM:</b>	<b>Asbestos Containing Material/Potential Asbestos Containing Material</b>
<b>AHERA:</b>	<b>Asbestos Hazard Emergency Response Act</b>
<b>AIR FORM:</b>	<b>Asbestos Inspection Report Form</b>
<b>Amended Water:</b>	<b>Water to which a surfactant (soap) has been added</b>
<b>AMP:</b>	<b>Asbestos Management Program/Asbestos Management Plan</b>
<b>Asbestos Designate Person:</b>	<b>Individual assigned by the district to oversee asbestos related issues.</b>
<b>Asbestos Regulated Area:</b>	<b>Location that is posted as an asbestos work area in which only approved and accredited personnel are permitted to enter</b>
<b>AST:</b>	<b>Asbestos Support Team involving approved and accredited school district tradespersons personnel that are school district person</b>
<b>A-TEAM:</b>	<b>School District of Philadelphia asbestos workers</b>
<b>CIP:</b>	<b>Capital Improvement Program</b>
<b>Consultant:</b>	<b>Asbestos consulting firm hired by the District</b>
<b>Demolition Directive:</b>	<b>Memorandum – August 4, 2006 from Patrick Henwood</b>
<b>EPA:</b>	<b>Environmental Protection Agency</b>
<b>In House Personnel:</b>	<b>School District of Philadelphia asbestos workers</b>
<b>LEA:</b>	<b>Local Education Agency</b>
<b>O&amp;M:</b>	<b>Operations and Maintenance</b>
<b>OEMS:</b>	<b>Office of Environmental Management and Services</b>
<b>OSHA:</b>	<b>Occupational Safety and Health Administration</b>
<b>PEL:</b>	<b>Permissible Exposure Limit</b>
<b>PSD or SDP:</b>	<b>Philadelphia School District/School District of Philadelphia</b>
<b>PSIT:</b>	<b>Philadelphia School Improvement Team</b>
<b>STEL:</b>	<b>Short Term Exposure Limit</b>

## **1. Introduction**

The School District of Philadelphia, Asbestos Policy Statement:

“The School District of Philadelphia is dedicated to providing a safe and healthful work environment for its employees, students, faculty, contractors and visitors. In recognition of the potential health problems associated with asbestos, the School District of Philadelphia is committed to a comprehensive asbestos control program. This program is implemented and maintained through the School District of Philadelphia's Office of Environmental Management and Services (OEMS).”

OEMS has the responsibility of establishing procedures for asbestos abatement, asbestos inspection, air monitoring, renovation and demolition activities within all School District of Philadelphia owned or leased facilities.

These procedures are developed to ensure that:

- (1) People are not exposed to significant levels of asbestos fibers
- (2) Asbestos waste is handled and disposed of properly
- (3) Members of the School District of Philadelphia community have access to the Office of Environmental Management and Services for information, assistance, guidance, and interpretation regarding asbestos related matters.
- (4) Members of the School District of Philadelphia community have access to the Asbestos Management Plans as required and outlined in the US EPA AHERA regulations including annual written notification to all parents.
- (5) Compliance with all applicable Federal, State and Local Asbestos Regulations

Requirements outlined in this manual are mandatory in nature where the word “SHALL” is used and are advisory in nature where the word “SHOULD” is used.

## **2. Summary of Asbestos Management Program**

The School District of Philadelphia's Asbestos Management Program was established to meet the requirements of Federal, State, and Local Regulations.

These regulations include, but are not limited to:

- US Environmental Protection Agency Asbestos Hazard Emergency Response Act (US EPA AHERA) and National Emissions Standard for Hazardous Air Pollutants subpart M, Part 61 (NESHAP);
- US Department of Labor, Occupational Safety and Health Administration (OSHA) General Industry Standard (29 CFR 1910.1001) and the OSHA Asbestos Standard for the Construction Industry (29 CFR 1926.1101);
- The Commonwealth of Pennsylvania, Department of Labor and Industry, Asbestos Occupations, Accreditation and Certification Act;
- The City of Philadelphia, Department of Public Health, Asbestos Control Regulations.

### **3. Asbestos Management Program Execution**

#### **a) General Execution**

The Office of Environmental Management and Services (OEMS) develops, implements and manages safety and health programs for the School District of Philadelphia faculty, staff and students and assists with ensuring that all contractors comply with Federal, State and Local Environmental Regulations. The OEMS provides the oversight of School District of Philadelphia employees (Asbestos A-Team), environmental consultants, and asbestos abatement contractors for all projects within the School District of Philadelphia concerning Asbestos Containing Materials.

The control of safety and health hazards at the School District of Philadelphia is primarily through the implementation of engineering, work practice and administrative controls. Personal Protective Equipment (PPE) is used to supplement these controls or whenever the controls are not feasible or are in the process of being implemented. PPE is also recommended whenever exposures to chemical, physical or biological agents can be prevented or reduced by its use.

This written program establishes the procedures necessary to:

- 1) meet established standards and federal regulations for occupational exposure to asbestos fibers;
- 2) meet the requirements of the City of Philadelphia Asbestos Control Regulations which encompasses the disturbance and/or abatement of asbestos containing building materials;
- 3) provide the necessary health and safety protection to the School District of Philadelphia staff, faculty, students, contractors and visitors.

This program is strengthened by input and cooperation with the Philadelphia Federation of Teachers (PFT), Health and Welfare Fund.

### **4. Summary of Program Execution**

#### **a) Asbestos Management Program Execution**

The Asbestos Management Program is administered by the Office of Environmental Management and Services (OEMS). OEMS provides the following services primarily through professional consultants:

- (1) exposure monitoring services;
- (2) building inspection/surveys (bulk sampling) for the identification of asbestos containing materials;
- (3) asbestos project design services;
- (4) asbestos abatement project and air monitoring services;
- (5) emergency response to fiber release episodes;
- (6) education/information;
- (7) medical monitoring;
- (8) training for School District of Philadelphia personnel

### **5. Responsibilities**

#### **a) Office of Environmental Management and Services**

OEMS is responsible for performing the following functions:

- (1) Developing and administering of the Asbestos Management Program.
- (2) Providing asbestos-related services to all School District of Philadelphia departments.
- (3) Conducting required training of the Asbestos Management Program and working jointly with departments to schedule training.
- (4) Identifying and posting areas where labeling/signage are required.
- (5) Medical Monitoring of OEMS "A-TEAM" and other departments "AST" Asbestos Program staff.

- (6) Certification and training as required for OEMS "A-TEAM" and other departments "AST" Asbestos program staff.
- (7) Record keeping as outlined in Section 3.5 and all records as by required by US EPA AHERA regulations.

**b) Asbestos Worker/Supervisor - "A-TEAM"**

- (1) OEMS shall ensure that all "A-TEAM" workers/supervisors adhere to the following requirements:
  - a) Attend an initial Worker/Supervisor Asbestos Course;
  - b) Maintain the annual re-certification per EPA AHERA requirements and Commonwealth of Pennsylvania Asbestos Occupations, Accreditation and Certifications Act;
  - c) Undergo an annual Asbestos Medical Evaluation;
  - d) Undergo an annual Respirator Medical Clearance;
  - e) Undergo an annual Respirator Fit Testing.

**c) Asbestos Designated Person**

The Asbestos Designated Person is responsible for:

- (1) Assuring the health and safety of employees, students and visitors in the School District of Philadelphia facilities under his/her control.
- (2) Being kept informed of all areas under his or her jurisdiction where potential asbestos exposures exist and initiating protection programs that adhere to the Asbestos Management Program requirements of this manual.
- (3) Assuring that Asbestos Management Program requirements are adhered to by principal investigators, project managers, supervisors, or division heads, and School District of Philadelphia personnel under their supervision.
- (4) Ensuring that all employees within the Asbestos Management Program comply with (OSHA 1910.1001 (j) (7) (iv)) and the US EPA AHERA regulations by attending the required training.
- (5) Ensure the posting of:
  - a) Warning labels/signage
  - b) Commonwealth of Pennsylvania Asbestos Abatement and Demolition/Renovation Notification form
  - c) Asbestos Inspection Reports (AIR) form (where required)
  - d) Ensuring that Construction Projects follow the Demolition Directive procedures as outlined in the August 4, 2006 letter.

**d) Supervisor or Project Manager (Capital, Maintenance and Facilities)**

Each person in charge of a project, maintenance/repair, renovation/demolition, or other activity from the Departments of Capital, Maintenance, and/or Facilities, where asbestos containing material may be present is responsible for:

Identifying, with the assistance of OEMS, asbestos containing building materials prior to any disturbance of these materials. Various Federal (EPA and OSHA) and Local (City of Philadelphia Asbestos Control Regulations) require Asbestos Inspections prior to renovation/demolition activities. This shall be accomplished by always following the Asbestos Management Program Procedures as follows:

- (1) Ensure that the requirements of the Asbestos Management Program Procedures are followed by all personnel, trades, and contractors who are involved with the project;



- (2) Review of the required Asbestos Inspection Report (AIR) form (Attachment 1) and AHERA Management Plan documents prior to activities that may disturb any Asbestos Containing Materials;
- (3) Perform all project related duties as outlined in the Project Management Responsibilities;
- (4) Keep the department chairperson or director informed on any actions proposed or taken regarding the Asbestos Management Plan;
- (5) Ensuring that Construction Projects follow the Demolition Directive procedure outlined in the August 4, 2006 letter.

**e) Employee – Capital**

School District of Philadelphia Capital employees and/or consultants shall:

- (1) Ensure that no suspect or asbestos containing building materials are disturbed in the course of the projects they are performing or managing. This shall be accomplished by notifying their supervisor and OEMS by issuance of a work order permit (a.k.a PSIT Service Request Form) and verifying that the materials which may be disturbed are non-asbestos containing. If this information is not available or verification has not been made, these materials should not be disturbed.
- (2) Immediately notify OEMS and their supervisor in the event of a potential fiber release episode upon discovery of visible damage to asbestos containing materials.
- (3) Ensuring that Construction Projects follow the Demolition Directive procedures as outlined in the August 4, 2006 letter.

The types of projects represented as part of the Capital Improvement Program are as follows:

- (1) Complete Renovation of an existing building that addresses all facility component concerns and educational program needs;
- (2) Major Renovation of an existing building addressing significant facility component and educational improvements;
- (3) Addition to an existing building (either as an attachment or stand-alone structure) to accommodate needed program space;
- (4) Conversion of an existing facility to accommodate a change in educational program;
- (5) Facility Component Improvement of specific facility needs (i.e. electrical or HVAC system upgrades, ADA improvements, life safety improvements, exterior renovations, etc.)

**f) Employee – Maintenance**

School District of Philadelphia Maintenance employees shall:

- (1) Ensure that no suspect or asbestos containing building materials are disturbed in the course of their duties or work they are performing. This shall be accomplished by notifying their supervisor and OEMS by issuance of a work order permit and verifying that the materials which may be disturbed are non-asbestos containing. If this information is not available or verification has not been made, these materials should not be disturbed.
- (2) Immediately notify OEMS and their supervisor in the event of a potential fiber release episode or upon discovery of visible damage to asbestos containing materials.
- (3) All employees involved in maintenance activities shall attend required Asbestos Awareness training program within 60 days of employment.

**g) Employee – Facilities & Custodial**

School District of Philadelphia Facilities and Custodial employees shall:

- (1) Ensure that no suspect or asbestos containing building materials are disturbed in the course of their duties or work they are performing. This shall be accomplished by notifying their supervisor and OEMS by issuance of a work permit and verifying that the materials which may be disturbed are non-asbestos containing. If this information is not available or verification has not been made, these materials should not be disturbed;
- (2) Immediately notify OEMS and their supervisor in the event of a potential fiber release episode or upon discovery of visible damage to asbestos containing materials.
- (3) All employees involved in Facilities and Custodial activities shall attend require Asbestos Awareness training program within 60 days of employment.

## **6. Requirements**

### **a) Employee Exposure Monitoring**

When information indicates that an employee's exposure to asbestos fibers may equal or exceed an 8-hour time-weighted average of 0.1 f/cc \* (per OSHA 1910.1001 & 1926.1101), OEMS shall develop and implement an asbestos exposure monitoring program. The sampling strategy shall be designed to identify employees by work task (job classification) that is exposed to asbestos fibers that exceed an 8-hour time-weighted average of 0.1 f/cc.

### **b) Employee Notification**

OEMS shall notify in writing, each employee exposed to asbestos fibers at or above an 8-hour time weighted average of 0.1 f/cc.

### **c) Observation and Monitoring**

OEMS shall provide employees or their representatives with an opportunity to observe any exposure measurements conducted.

### **d) Training Program**

OEMS shall institute a training program which meets the requirements of AHERA for all employees who perform maintenance operations in a facility/school which contains asbestos containing materials or presumed asbestos containing materials and 1910.1001 (j), and the Commonwealth of Pennsylvania Department of Labor and Industry and the City of Philadelphia Asbestos Control Regulations. The affected departments shall ensure employee participation in this program. The OEMS "A-TEAM" and other departments "AST" Asbestos Program staff training shall be conducted annually for each employee as required by all Federal, State and Local for each asbestos discipline.

All Asbestos Awareness training as required by AHERA shall be performed within 60 days of employment and shall include:

- Health effects of asbestos
- Locations of ACM and PACM in the building/facility
- Recognition of CM and PACM damage and deterioration
- Requirements of the OSHA 1910.1001 standard relating to maintenance
- Proper response to fiber release episodes
- Procedure to be followed to isolate areas affected by fiber release

### **e) Access to Information**

OEMS shall make available to affected employees or their representative's copies of the Occupational Safety and Health Administration (OSHA) General Industry Standard Part 1910.1001 and the department shall post a copy in the workplace.

### **f) Record Keeping**

OEMS shall maintain an accurate record of all employee exposure measurements. OEMS and/or the School District of Philadelphia Human Resources Department shall maintain records of employee medical monitoring program. OEMS shall maintain all employee training records. All records shall be provided upon request to employees, former employees, representatives designated by the individual employee.

## **7. AHERA OPERATIONS AND MAINTENANCE PLAN**

### **a) CONTROLS**

#### **i. Work Order System**

Minimizing disruption of ACM/PACM during maintenance and renovation activities is the primary goal and task encountered by OEMS. Operations and maintenance employees and contractors should be warned to avoid conducting any maintenance work which may disturb ACM/PACM. Initiating a work order system, where all work orders or requests are channeled through the Office of Environmental Management and Services (OEMS), will be the method used to control and minimize disruption of ACM/PACM.

Any work performed by in-house personnel or contractors that could or will impact ACM/PACM shall be coordinated by OEMS. A completed Asbestos Inspection Report Form (Attachment 1) shall be issued to in-house personnel and/or all contractors whose work could impact ACM/PACM. This form should accompany each contract issued to an outside contractor and posted on the jobsite.

All work order requests for maintenance and renovation activities in areas where ACM/PACM is suspected or known to be present are to be submitted to OEMS prior to proceeding with work. OEMS is responsible for reviewing asbestos survey records for information about the presence of ACM/PACM in the area where the work is to be performed. OEMS should physically inspect the area to ensure existing records reflect actual conditions. If no asbestos is present, a work order is not necessary and the planned actions can proceed. If ACM/PACM is found to be present in the area, OEMS will sign the work order application and obtain an approved and accredited asbestos contractor or assign OEMS "A-TEAM" to abate the ACM/PACM.

#### **ii. Regulated Areas**

The owner will identify and regulate all areas where airborne concentrations of ACM/PACM exceed the Permissible Exposure Limit (PEL)\* (Per OSHA determined to be 0.1 f/cc) and/or short term exposure limit (STEL) (Per OSHA determined to be 0.1 f/cc), or there is reasonable possibility that the (PEL) and/or (STEL) may be exceeded. All ACM/PACM removal activities involving thermal system insulation ACM/PACM (Class I), surfacing ACM/PACM (Class I), and miscellaneous ACM/PACM such as floor tile, roofing, and siding mastic, etc. (Class II), and repair and maintenance operations where thermal system insulation and surfacing ACM/PACM is likely to be disturbed (Class III) will be performed in accordance with federal, state, and local regulations. All asbestos abatement work and activities will be designed and managed as asbestos regulated areas. These areas will be demarcated and labeled.

#### **iii. Warning Signs**

Warning signs shall be displayed at all approaches to each asbestos regulated area. The asbestos abatement contractor will provide OSHA warning signs in all regulated areas during removal, repair, and other maintenance activities. OEMS will provide AIRs to all contractors who must inform all employees and supervisors working in locations contiguous to asbestos regulated areas of the potential hazards and work practices required.

#### **iv. Warning Labels**

Warning labels and/or signage shall be affixed to all raw materials, mixtures, scrap, waste, debris, and other products containing asbestos fibers, or to their containers. Generally, the asbestos abatement contractor or OEMS A-Team personnel will provide all warning labels for ACM/PACM containment.

## **8. O & M RESPONSE ACTIONS**

The Asbestos Management Program general O&M procedures are outlined in this section. Additional requirements specific to asbestos abatement activities are included in the Project Design documents for all Asbestos Abatement Work. Regular cleaning, inspection, and reporting of ACM/PACM deterioration or other problems must be diligently practiced by all employees including custodial and maintenance personnel.

### **a) Facility Maintenance Isolation of Area Responsibilities**

Maintenance personnel are often required to work in areas where ACM/PACM may potentially be disturbed. Most maintenance activities are conducted by in-house staff, outside contractors, or a combination.

Emergency fiber release episodes, such as pipe fitting or valve breaks, emergency boiler work, or mechanical equipment repair will be responded to by OEMS A-Team personnel or asbestos abatement contractor personnel. The owner's maintenance staff will: (1) isolate the emergency fiber release area; (2) post warning signs to prevent unauthorized access, and (3) notify their supervisor and OEMS. OEMS will ensure that the fiber release area remains isolated and is properly cleaned by and approved and accredited abatement contractor or by OEMS A-TEAM personnel.

### **b) Unlikely Contact with ACM/PACM**

Maintenance activities or repairs which can be performed without contacting or disturbing the ACM/PACM require little more than normal care and good workmanship. For example, valves which are either uncovered or covered with non-asbestos insulation can be packed or repaired without disturbing asbestos insulation on nearby pipes. The major precaution is to ensure that maintenance and custodial personnel are familiar with procedures such as isolating the area, posting warning signs, and notifying OEMS in the event of any accidental ACM/PACM disturbance.

### **c) Accidental Disturbance of ACM/PACM**

Maintenance and facilities personnel shall notify OEMS any time a fiber release is suspected. If friable ACM/PACM becomes airborne in the building,

### **d) Planned Disturbance of ACM/PACM**

Maintenance activities that may impact ACM/PACM include access to a valve, flange, duct, or related system component.

Where asbestos-containing insulation must be removed to maintain or repair the thermal system, the ACM/PACM will imminently be disturbed. ACM/PACM removal work shall be conducted by OEMS A-Team personnel or an approved and accredited asbestos abatement contractor.

If friable ACM/PACM becomes airborne in the building, maintenance and facilities personnel shall secure the area and contact OEMS. OEMS shall respond accordingly.

**e) Miscellaneous ACM/PACM**

Miscellaneous types of ACM/PACM may include vinyl asbestos floor tiles, mastics/adhesives and woven vibration dampers. Disturbance of these materials should be avoided. Routine maintenance activities involving these materials should not pose a problem if handled properly. Questions on the proper removal and disposal of miscellaneous ACM/PACM should be directed to OEMS. OEMS will contact an approved and accredited asbestos abatement contractor or utilize OEMS A-TEAM personnel to assist with miscellaneous ACM/PACM clean-up activities.

**f) Vinyl Asbestos Floor Tile**

Asbestos-containing floor tiles in good condition are considered non-friable unless they are crushed, drilled, sawed, sanded or disturbed by any activity that breaks up the material. Routine maintenance of these materials should employ the use of non-abrasive buffers and wet cleaning technique. Broken or loose floor tiles should be removed and disposed of as asbestos waste by OEMS. Remaining debris should be vacuumed with a HEPA vacuum and the area wet mopped using amended water.

**g) Mastics/Adhesives**

Mastics and adhesives containing asbestos in good condition are considered non-friable and do not pose a potential health concern unless crushed, drilled, sawed, sanded, or otherwise abraded. Questions on the proper removal should be directed to OEMS.

**h) Woven Vibration Dampers**

Woven vibration dampers in good condition are considered non-friable and do not pose a potential health concern unless cut, crushed, drilled, sawed, sanded, or otherwise abraded. Questions on the proper removal should be directed to OEMS.

**i) Other Work Practices**

Any special work not included in this section should be addressed to OEMS for review prior to the initiation of work that may involve the disturbance of ACM/PACM.

**j) Fiber Release Episodes**

Facilities and maintenance staff should report to OEMS the presence of asbestos debris, water or physical damage to ACM/PACM, or any other evidence of possible fiber release. OEMS should have the OEMS A-Team personnel or an approved and accredited abatement contractor respond to the site to clean up debris and make repairs as soon as possible. OEMS will also contact a consultant to conduct air monitoring and prepare a report and submit at project completion to OEMS for each episode. OEMS will forward the reports for each site location AHERA Management Plan accordingly.

## **9. REFERENCES and RESOURCES**

Applicable regulations for asbestos projects impacted by renovation, demolition, and maintenance activities.

- **Philadelphia Air Management Services – Asbestos Control Unit**  
<http://www.phila.gov/health/units/ams/Asbestos/asbestos.html>
- **Pennsylvania Asbestos Occupations, Accreditation and Certification Act**  
<http://www.dli.state.pa.us/landi/cwp/view.asp?a=185&q=56262&landiNav=>
- **United States Environmental Protection Agency Asbestos Home Page**  
<http://www.epa.gov/asbestos/>
- **Occupational Safety and Health Administration (OSHA) Asbestos Home**  
<http://www.osha.gov/SLTC/asbestos>