

SCHOOL DISTRICT OF PHILADELPHIA



Asbestos Hazard Emergency Response Act “AHERA”

THREE-YEAR RE-INSPECTION 2015-2016 and ASBESTOS MANAGEMENT PLAN for the

**Motivation High School
KIPP Turner West Middle School**

**ULCS# 1160
Building # B116001-1
5900 Baltimore Avenue
Philadelphia, Pennsylvania
19143**

Year Built: 1969

September 2015

Conducted by:

Accredited Environmental Technologies, Incorporated
Batta Environmental Associates, Incorporated
Criterion Laboratories, Incorporated
Environmental Testing Consultants, LLC
G & C Environmental Services, Incorporated
KEM Partners, Incorporated
Synertech, Inc.
TTI Environmental, Inc.
USA Environmental Management, Inc.
The Vertex Companies, Inc.

Management Plan Prepared by:
Criterion Labs, Inc and Synertech Inc.

This report must remain in the Main Office as mandated by the US EPA AHERA Regulations.

AHERA THREE-YEAR REINSPECTION VOLUME IX

Table of Contents

Transmittal Letter

Executive Summary

- I. Summary list of Confirmed Asbestos Containing Building Materials
- II. Summary list of Assumed Asbestos Contain Building Materials
- III. Summary list of Non-Asbestos Containing Building Materials
- IV. Summary list of Non Suspect Asbestos Containing Building Materials
- V. Summary List of Auditorium DATA for this location
- VI. Summary list of Attic and/or Crawlspace DATA for this location
- VII. Summary list of Pipe Chase/Pipe Shaft DATA for this location

Section I Report of Re-Inspection

- A. Introduction
- B. Three-Year Re-inspection IX Overview
- C. Post- Management Plan Activities and Changes
 - C.1 - Sampling and Analysis
 - C.2 - New Floor Tile Sampling
 - C.3 - Abatement Activity
 - C.4 - Periodic (Six-Month) Surveillance (Damaged Materials)

Section II Re-Inspection Data

- A. Introduction
- B. Re-Inspection Key Definitions
- C. Room by Room Location Log Report

Section III Certificates

- A. Management Planner/Building Inspector Certificates

Section IV	Cross Reference Table	Page 1-8
	Asbestos Management Program	Page 9-19

SCHOOL DISTRICT OF PHILADELPHIA
EDUCATIONAL CENTER
440 NORTH BROAD STREET
PHILADELPHIA, PENNSYLVANIA 19130

OFFICE OF ENVIRONMENTAL MANAGEMENT AND SERVICES

PHONE (215)-400-4750

January 2016


TO: All Principals
All Building Administrators

FROM: Fran Burns
Chief Operating Officer

Francine Locke, M.S., Director
Office of Environmental Management and Services

SUBJECT: AHERA Three (3) Year Re-inspection IX report

In order to comply with the provisions of the Asbestos Hazard Emergency Response Act (AHERA) the attached report is submitted to you. The law requires that this report be kept in the Main/Principal's office. It cannot be removed from these locations. *If the school (program) is relocated to a different building, these environmental documents are to be safely retained for the next school/building occupants.* All asbestos reports must be available to the public and Federal EPA upon request.



Fran Burns
Chief Operation Officer



Francine Locke, M.S., Director
Office of Environmental Management
and Services

Executive Summary

This Asbestos Hazard Emergency Response Act (AHERA) Three-Year Re-inspection “Volume # IX” Management Plan at this location, has been completed and the report of re-inspection submitted to the School District of Philadelphia. The re-inspections in all School District of Philadelphia buildings of 2015-2016 were conducted and completed between October 5th, 2015 through March 30th, 2016 as a joint project by Accredited Environmental Technologies, Inc., Batta Environmental Associates, Inc., Criterion Laboratories, Inc., Environmental Testing Consultants, LLC, G & C Environmental Services, Inc., KEM Partners, Inc., Synertech, Inc., TTI Environmental, Inc., USA Environmental Management, Inc. and The Vertex Companies, Inc.

In general, the School District of Philadelphia Office of Environmental Management and Services conducts Environmental Impact Evaluations and provides Asbestos Inspection Reports prior to any renovation, demolition and/or maintenance activities. The AHERA report must be reviewed prior to any renovation, demolition and/or maintenance activities in order to avoid the unknowing disturbance to Asbestos Containing Building Materials identified within this location. In addition, prior to work activities above all drop ceilings this report should be reviewed to avoid potential disturbances to Asbestos Containing Materials. Refer to Section IV of the Cross Reference Table, for additional Asbestos Management Program information. Contact the Office of Environmental Management and Services to have an Environmental Impact Evaluation conducted prior to any renovation, demolition and/or maintenance activities within this facility.

The information contained in this report was obtained from the original Asbestos Management Plan for the school, from update reports on changes and activities since the completion of the 1st Management Plan for each location and from all prior inspections performed and documented in Volume # I through Volume VIII (dated respectively 1992, 1995, 1998, 2001, 2004, 2007, 2010 or 2013) (if applicable) - and by this Three-Year Re-inspection of this school. The re-inspection report/Management Plan of 2015-2016 were reviewed and prepared collectively by Management Planner Megan Vala, Mary Anne Lerro of Criterion Laboratories, Inc. and/or Monique Causley, of Synertech Inc.

The 2015-2016 inspection process included the addition of a comprehensive Room by Room Inventory of all Thermal (T), Surfacing (S) and Miscellaneous (M) Materials specific to each room of this facility. Inspections of each room's thermal, ceilings, walls, floors and miscellaneous items regardless of Asbestos Content are categorized on the Room by Room Location Log Report for this location. Rooms or areas of the facility that were not accessible at the time of the inspection are marked with an "X". The Room by Room Location Log Report is found in Section II C of this Management Plan.

All Presumed or Suspect Asbestos Containing Building Materials (ACBMs), listed in the following summary charts are categorized as Confirmed, Assumed, Non-Asbestos, and/or Non-Suspect (ACBMs) were identified in the original Management Plan, or in the Volume I through Volume VIII AHERA Three-Year Re-inspection reports, and were re-inspected as part of this project.

As mandated by the U S EPA AHERA regulations, periodic Six-Month inspections and Three-Year Re-inspections of this location will be performed and the Inspection Data in this report will be updated accordingly.

Please feel free to contact the School District of Philadelphia's Office of Environmental Management and Services (OEMS) regarding any comments, questions, or concerns regarding this report or any Environmental related topic. OEMS staff can be reached at (215) 400 4750, via fax at (215) 400 4751 or via e-mail at flocke@philasd.org and/or gfunod@philasd.org.

Additional information can be found on our website. Here is the link to the OEMS website.
<http://webgui.phila.k12.pa.us/offices/e/environmental>

I. Summary list of Confirmed Asbestos Containing Building Materials within this facility

These charts are to be used for a quick reference* in order to avoid the unknowing disturbance of Asbestos Containing Materials during any and all Operations, Maintenance, Renovation, and/or Demolition activities at this location. *These materials have been sampled and Laboratory Analysis has CONFIRMED the presence of Asbestos. Contact OEMS prior to the disturbance of any of the following materials.*

Confirmed Asbestos Containing Building Materials for this location

Boiler Breeching	Fiberglass Pipe Fitting Insulation	Transite Lab Counters
Boiler Rope Insulation	Fiberglass Pipe Insulation	Transite Sills
Duct Insulation	Floor Tile VAT 9" x 9"	Transite Sink
Duct Work	Textured Ceiling Paint	
External Boiler Mud Insulation	Transite	

* *Always refer to the Room by Room Logs for each specific material classification as the material classification findings may be different in various rooms throughout this facility.*

** *Some Materials may have multiple classifications (Confirmed, Assumed, NAD and Non Suspect) within this facility.*

II. Summary list of Assumed Asbestos Containing Building Materials within this facility

These charts are to be used for a quick reference* in order to avoid the unknowing disturbance of Asbestos Containing Materials during any and all Operations, Maintenance, Renovation, and/or Demolition activities at this location. These materials have not been sampled and should not be disturbed until verification of Asbestos Content. Contact OEMS for assessment and sampling prior to the disturbance of these materials.

Assumed Asbestos Containing Building Materials for this location

Blackboard Glue Dots	Plaster Ceiling	Vibration Damper Cloth
Ceiling Tile 1' x 1'	Sink Undercoat Mastic	Vinyl Vibration Damper Cloth
Floor Tile VAT 12" x 12"	Stage Curtains	
Kiln	Transite	

* *Always refer to the Room by Room Logs for each specific material classification as the material classification findings may be different in various rooms throughout this facility.*

** *Some Materials may have multiple classifications (Confirmed, Assumed, NAD and Non Suspect) within this facility.*

III. Summary list of Non-Asbestos Containing Building Materials within this facility

These charts are to be used for a quick reference* in order to avoid the unknowing disturbance of Asbestos Containing Materials during any and all Operations, Maintenance, Renovation, and/or Demolition activities at this location. *These materials have been sampled and Laboratory Analysis has indicated NO Asbestos present or NO ASBESTOS DETECTED (NAD).*

Non- Asbestos Containing Building Materials for this location

Pipe Fitting Insulation	Plaster Ceiling	Tank Insulation
Unit Ventilator Insulation		

* *Always refer to the Room by Room Logs for each specific material classification as the material classification findings may be different in various rooms throughout this facility.*

** *Some Materials may have multiple classifications (Confirmed, Assumed, NAD and Non Suspect) within this facility.*

IV. Summary list of Non-Suspect Asbestos Containing Building Materials within this facility

These charts are to be used for a quick reference* in order to avoid the unknowing disturbance of Asbestos Containing Materials during any and all Operations, Maintenance, Renovation, and/or Demolition activities at this location. These materials are not typically known to contain Asbestos.

Non-Suspect Asbestos Containing Building Materials for this location

Carpet	Concrete Block Wall	Partition Room Dividers
Ceiling Tile 2' x 4'	Concrete Ceiling	Sheetrock Wall
Cement Floor	Fiberglass Ceiling Tile 2' x 4'	Terrazzo Floors
Ceramic Tile Floors	Fiberglass Pipe Fitting Insulation	Wood Floor
Ceramic Tile Walls	Fiberglass Pipe Insulation	Wood Panel Walls

* *Always refer to the Room by Room Logs for each specific material classification as the material classification findings may be different in various rooms throughout this facility.*

** *Some Materials may have multiple classifications (Confirmed, Assumed, NAD and Non Suspect) within this facility.*

V. Summary list of Auditorium DATA for this location

These charts are to be used for a quick reference of the Auditorium DATA within this facility. Sampling of the Auditorium Ceilings throughout the District is more difficult because of the various ceiling heights. As sampling occurs this information is updated on a case by case basis for each specific location and facility.

This is a list of known materials for this location's Auditorium

Auditorium	Textured Ceiling Paint	Confirmed
Auditorium	Carpet	Non Suspect ACM
Auditorium	Cement Floor	Non Suspect ACM
Auditorium	Concrete Block Wall	Non Suspect ACM
Auditorium	Partition Room Dividers	Non Suspect ACM
Auditorium Stage	Fiberglass Pipe Insulation	Non Suspect ACM
Auditorium Stage	Fiberglass Pipe Insulation	Non Suspect ACM
Auditorium Stage	Fiberglass Pipe Fitting Insulation	Non Suspect ACM
Auditorium Stage	Wood Floor	Non Suspect ACM
Auditorium Stage	Concrete Ceiling	Non Suspect ACM
Auditorium Stage	Stage Curtains	Assumed

** Always refer to the Room by Room Logs for each specific material classification as the material classification findings may be different in various rooms throughout this facility.*

*** Some Materials may have multiple classifications (Confirmed, Assumed, NAD and Non Suspect) within this facility.*

VI. Summary list of Attic and/or Crawlspace DATA for this location

These charts are to be used for a quick reference regarding the Attics and/or Crawlspaces inspection DATA within this facility. Contact OEMS prior to entering any attic or crawlspace within this facility and refer to the below chart and legend for Category Rank determination. The Data relative to these spaces is updated as conditions change regarding Abatement or Renovation activity on a case by case basis for each specific location and facility. In general, Crawlspaces are below the basement or 1st floor and Attics are above the floor space.

Category Rank Legend

"A" - No Asbestos Containing Materials - Sample Results indicate NO ACM on pipes, fittings, elbows, or equipment located within this functional space, and NO VISIBLE DEBRIS or DAMAGE observed at time of this inspection.
"B" - Asbestos Containing Materials Exist - Sample Results indicate ACM on pipes, fittings, elbows, or equipment located within this functional space, HOWEVER, NO VISIBLE DEBRIS or DAMAGE observed at time of this inspection.
"C" - Asbestos Containing Materials Exist - Sample Results indicate ACM on pipes, fittings, elbows, or equipment located within this functional space, and LOCALIZED VISIBLE DEBRIS or DAMAGE observed at time of this inspection.
"D" - Asbestos Containing Materials Exist - Sample Results indicate ACM on pipes, fittings, elbows, or equipment located within this functional space and DISTRIBUTED VISIBLE DEBRIS or SIGNIFICANT DAMAGE observed at time of this inspection.
"E" - No Bulk Sample Results Available SUSPECT ACM OBSERVED. Contact OEMS immediately for additional instructions.

Attic/Crawlspace	Access Area	Floor Surface	Category Rank	Comments
Attic	X	X	X	No Attic
Crawlspace	X	X	X	No Crawlspace

VII. Summary list of Pipe Chase/Pipe Shaft DATA for this location

These charts are to be used for a quick reference regarding the information known about the Pipe Chases and/or Pipe Shafts inspection DATA within this facility. Contact OEMS prior to performing renovation activities any Pipe Chase and/or Pipe Shaft within this facility and refer to the below chart and legend for Asbestos Content of various materials identified within each space. The Data relative to these spaces is updated as conditions change regarding Inspection, Abatement and/or Renovation activity on a case by case basis for each specific location and facility. In general, Pipe Chases are horizontal spaces and Pipe Shafts are vertical spaces.

Pipe Chases and Pipe Shafts need to be assessed.

Section I

Report of Re-Inspection

A. Introduction

B. Three-Year Re-Inspection IX Overview

C. Post-Management Plan Activities and Changes

C.1 Sampling and Analysis

C.2 New Floor Tile Sampling

C.3 Abatement Activity

C.4 Periodic Six-Month Surveillance (Damaged Materials)

Section I - A

Report of Re-inspection

Introduction

The Three-Year Re-inspection IX was performed to fulfill the requirements of 40 CFR Part 763 - the Asbestos Hazard Emergency Response Act (AHERA). As required by AHERA, each Local Education Agency (LEA) must re-inspect all known confirmed or assumed Asbestos Containing Building Material (ACBM) located in the LEA's facilities. This re-inspection is intended to update the original Asbestos Management Plan for the LEA's facilities.

Multiple Building Inspectors of several firms performed the 2015/2016 re-inspection. The re-inspection report/Management Plan of 2015-2016 were reviewed and prepared collectively by Management Planner Megan Vala, Mary Anne Lerro of Criterion Laboratories, Inc. and Monique Causley, of Synertech Inc.

All of the certificates can be found in Section III.

During the re-inspection of each School District of Philadelphia facility, all of the Management Plans for that facility were reviewed. Information from the conclusions section of that report is included in this report. Additionally, information on activities such as abatements, cleanings, sampling and inspections, which have taken place since the completion of the original Management Plan, were reviewed during the re-inspection. Information on those activities is included in this report.

As mandated by the U S EPA AHERA regulations, all future periodic Six-Month inspections and Three-Year Re-inspections of this location will be performed and the Inspection Data in this report will be updated accordingly.

Section I - B

Three-Year Re-inspection IX Overview

Each homogeneous area of Asbestos Containing Building Material (ACBM) listed in the original Management Plan or in the 1992, 1995, 1998, 2001, etc., Three-Year Re-inspection reports were inspected for the AHERA Three-Year Re-inspection Volume IX, and the information for that material verified. Any changes to a homogeneous area listed in the updates to the Management Plans were verified. Any area of suspected ACBM found in the course of the re-inspection, and not listed in the Management Plan or updates, were either assumed to contain asbestos or sampled and analyzed to determine their asbestos content. Any such new areas either assumed to contain asbestos or determined through analysis to contain asbestos were included in the report of the Three-Year Re-inspection. The results of the AHERA Three-Year Re-inspection IX are tabulated in the Room by Room log reports located in *Section II-C* of this report.

As previously noted, all future periodic Six-Month inspections and Three-Year Re-inspections of this location will be performed and the Inspection Data in this report will be updated accordingly.

Section I – C.1

Post Management Plan Activities/Changes

Information on activities affecting Asbestos Containing Building Materials (ACBMs) at this location is contained in updates to the Management Plan. These updates are kept on file by the School District of Philadelphia and were reviewed for this project. Updates to the Management Plan include the following: *Sampling and Analysis, New Tile Installation, Abatement Activity and Periodic Six-Month Surveillance Data.*

Sampling and Analysis

In the event Sampling occurs, data will be listed here.

Section I – C.2

Information on the installation of new floor tiles/renovation activities affecting Asbestos Containing Building Materials (ACBMs) at this location is contained in updates to the Management Plan. These updates are kept on file by the School District of Philadelphia and were reviewed for this project. Updates to the Management Plan include the following:

New Floor Tile Sampling

In the event that new tile is installed, the material must be tested prior to installation.

Section I – C.3

Information on the Asbestos Abatement and renovation activities affecting Asbestos Containing Building Materials (ACBMs) at this location is contained in updates to the Management Plan. These updates are kept on file by the School District of Philadelphia and were reviewed for this project. Updates to the Management Plan include the following:

Abatement Activity

<i>Date</i>	<i>Floor</i>	<i>Location</i>	<i>Material</i>	<i>Color</i>	<i>Removed or Encapsulated</i>	<i>Quantity</i>
4/20/2016	G	SOCCA Community Room (Multi-Purpose Room)	Pipe Insulation 2-6 inch	White	Removed	36 LF
4/20/2016	G	Classroom 139B	Floor Tile VAT 12" x 12"	Multi	Removed	100 SF
4/25/2016	G	SOCCA Teachers' Lounge	Pipe Insulation 2-6 inch	White	Removed	15 LF

Section I – C.4

Information on the AHERA inspection that noted damage to various Building Materials at this location is contained in updates to the Management Plan. These updates are kept on file by the School District of Philadelphia and were reviewed for this project. Work orders are created for Corrective Action responses and tracked for completion. Updates to the Management Plan include the following:

Periodic (Six-Month) Surveillance (Damaged Materials)

<i>Date</i>	<i>Element</i>	<i>Floor</i>	<i>On Site Room Name</i>	<i>Material</i>	<i>Amount of Material</i>	<i>Amount of Damage</i>
11/12/2015	1	1	Boiler Room	Boiler Breeching	1106 SF	2 SF

Section II

Re-Inspection Data

A. Introduction

B. Re-Inspection Key Definitions

C. Room by Room Location Log Report

Section II - A

Re-inspection Data

Introduction

The following information documents the Three-Year Re-inspection IX of the subject school/facility. The Homogeneous Area Reports were produced using the building inspector's field data on the facility. The key to the Homogeneous Area Report is outlined in the following pages of this report.

Section II - B
(page 1 of 4)

SCHOOL DISTRICT OF PHILADELPHIA
AHERA THREE YEAR RE-INSPECTION IX

ITEM	DEFINITION
ULCS#	Individual identification number assigned to each school within the School District of Philadelphia.
HOMOGENEOUS AREA ID#	Identification number assigned to each homogeneous area in a school/facility. Each section of the homogeneous area ID is significant. 1010/01/01/01 A B C D A. Is the ULCS# for the school. B. Designates the specific building/building area within the school. C. Designates the floor or level within the building/building area. D. Designates the homogeneous material within that floor or level. Note: Item D may be a number or a letter.
SYSTEM AFFECTED	Corresponds to the AHERA system for classifying materials. T : Thermal System S : Surfacing System M : Miscellaneous
ITEM AFFECTED	Is a description of the homogeneous material.
ORIGINAL INSPECTION DATA	This section contains the information found in the original Management Plan (1988-1989).
AMOUNT OF MATERIAL/ UNIT	Quantity of material, and measuring unit. Units include: Square Feet (SF) Each (EA) Linear Feet (LF) Cubic Feet (CF).

**SCHOOL DISTRICT OF PHILADELPHIA
AHERA THREE YEAR RE-INSPECTION IX**

RE-INSPECTION FORM KEY

ITEM	DEFINITION
CND Condition	Corresponds to AHERA condition rating for materials. 0 : No Damage 1 : Damage 2 : Significant Damage
DP Damage Potential	Corresponds to the AHERA material assessment system. 1 : Potential for Damage 2 : Potential for Significant Damage
ASMD Assumed Asbestos	This means that a material was not sampled for asbestos content during the original Management Plan inspection.
RA Response Action	This corresponds to the AHERA system of response action rating for materials. 1 : Establish O&M Program 2 : Repair and Establish O&M Program 3 : Enclose 4 : Encapsulate 5 : Remove 6 : Partial Removal and Establish O&M Program
CHANGES	This section describes changes to the homogeneous material in the twenty-four years since the original AHERA inspection. The abbreviations are defined below. RMVD : Removed ENCL : Enclosed ENCP : Encapsulated DMGD : Damaged SMPLD : Sampled MTRL : Material RPRD : Repaired N/L : None Located RPLCD : Replaced

**SCHOOL DISTRICT OF PHILADELPHIA
AHERA THREE-YEAR RE-INSPECTION IX**

RE-INSPECTION FORM KEY

ITEM	DEFINITION
THREE YEAR RE-INSPECTION	This section contains the information obtained from the Three-Year Re-inspection IX. With three exceptions, the information categories are identical in format and meaning to those found in the original inspection data section. The three exceptions are defined below.
DMGD AMT Amount Damaged	This section gives the quantity of damaged material in a homogeneous area. The quantity is shown in the same format as the amount of material/unit section.
NF Newly Friable	This section identifies materials in the original Management Plan which have since become friable.
RA Response Action	<p>This rating is based on the AHERA regulations, and is comparable to the RA rating found in the "Original Inspection Data" section. The following table details the response actions.</p> <ol style="list-style-type: none">1. Establish O&M Program2. Repair and Establish O&M Program3. Enclose4. Encapsulate5. Remove6. Partial Removal and Establish O&M Program <ol style="list-style-type: none">a. High Priority Response The homogeneous material has been scheduled for abatement or other response action.b. Medium Priority Response The homogeneous material will be scheduled for abatement or other response action as soon as the high priority responses have been addressed.c. Low Priority Response The homogeneous material will be scheduled for abatement or other response action as soon as the medium priority responses have been addressed.d. On-Going Response/Operations and Maintenance The homogeneous material does not require abatement or other response action at present, and should be included in the facility's on-going operations and maintenance program.

**SCHOOL DISTRICT OF PHILADELPHIA
AHERA THREE-YEAR RE-INSPECTION IX**

RE-INSPECTION FORM KEY

The information presented in the changes section has been compiled from a variety of sources, including the Re-inspection and the following:

- * Quality Control/Quality Assurance Reports of asbestos abatement projects, prepared by consultants to the School District.
- * Permit and Notification Forms for asbestos abatement projects.
- * Periodic Surveillance Forms
- * Operations and Maintenance activities performed by School District personnel.
- * Verbal information from School District personnel.
- * Reports of sampling and analysis of suspected materials by both School District personnel and outside consultants.

**ROOM BY
ROOM
LOCATION LOG
REPORT**

This section gives information, including damage amount and location, for a specific homogeneous material on a room-by-room basis and follows the Re-inspection form.

NOTE: The disparate nature of the above sources of information prohibits the verification of much information within the scope of the AHERA Three-Year Re-inspection. Discrepancies and omissions may exist in this information, and therefore is included on an "as is" basis. The inspectors for the Three-Year Re-inspection IX evaluated homogeneous areas based on the materials current condition and location, as evidenced during the inspector's site visit.

Section II - C

Room by Room Location Log Report

These charts are to be used for a quick reference* in order to avoid the unknowing disturbance of Asbestos Containing Materials during any and all Operations, Maintenance, Renovation, and/or Demolition activities at this location.

NOTE:

*Contact OEMS prior to the disturbance of any of the materials that are listed as **Confirmed and/or Assumed**.*

The quantities listed for (NAD) non-asbestos containing materials and/or Non-Suspect Materials are only estimated and were not measured for the purpose of this report. Field verification of quantities for renovation purposes would be necessary.

1160 Motivation HS/KIPP West @ Turner - 2015-2016 AHERA Three-Year Report.xls

E I S I O N R		School District of Philadelphia Motivation High School and KIPP Turner West Middle School 5900 Baltimore Avenue, Philadelphia, PA 19143 ULCS# 1160 Year Built: 1969		AHERA Three-Year Reinspection 2015-2016 Room by Room Location Log Report							Reinspection Date: 9/29/15		Attic/ Crawl Space Ranking	Damage Potential (DP)	Newly Friable (NF)	Response Action (RA)
				On Site Room Name		System Affected	Material Description	HID#	Confirmed/Assumed/NAD/ Non Suspect ACM	Amount of Material	SF LF EA	Amount of Damage				
1	3	Classroom 301	M	Floor Tile VAT 12" x 12"	1160/01/03/FF	Assumed	768	SF	0	SF	Tan		1	No	1/D	
1	3	Classroom 301	N/A	Concrete Block Wall		Non Suspect ACM	644	SF	0	SF			N/A	N/A	N/A	
1	3	Classroom 301	S	Textured Ceiling Paint	1160/01/03/33	Confirmed	768	SF	0	SF			1	No	1/D	
1	3	Classroom 301	M	Blackboard Glue Dots	1160/01/03/BATTA/AH/2600	Assumed	128	SF	0	SF			1	No	1/D	
1	3	Classroom 301	N/A	Unit Ventilator Insulation		NAD	27	SF	0	SF			N/A	N/A	N/A	
1	3	Classrooms 302 - 305 Pod Entrance	S	Textured Ceiling Paint	1160/01/03/33	Confirmed	816	SF	0	SF			1	No	1/D	
1	3	Classrooms 302 - 305 Pod Entrance	N/A	Concrete Block Wall		Non Suspect ACM	1340	SF	0	SF			N/A	N/A	N/A	
1	3	Classrooms 302 - 305 Pod Entrance	M	Floor Tile VAT 12" x 12"	1160/01/03/FF	Assumed	816	SF	0	SF	Grey		1	No	1/D	
1	3	Classroom 302	N/A	Concrete Block Wall		Non Suspect ACM	1160	SF	0	SF			N/A	N/A	N/A	
1	3	Classroom 302	M	Floor Tile VAT 12" x 12"	1160/01/03/FF	Assumed	805	SF	0	SF	Tan		1	No	1/D	
1	3	Classroom 302	N/A	Unit Ventilator Insulation		NAD	42	SF	0	SF			N/A	N/A	N/A	
1	3	Classroom 302	S	Textured Ceiling Paint	1160/01/03/33	Confirmed	805	SF	0	SF			1	No	1/D	
1	3	Classroom 302	M	Blackboard Glue Dots	1160/01/03/BATTA/AH/2600	Assumed	144	SF	0	SF			1	No	1/D	
1	3	Classroom 302	N/A	Sheetrock Wall		Non Suspect ACM	250	SF	0	SF			N/A	N/A	N/A	
1	3	Classroom 302	M	Sink Undercoat Mastic	1160/01/03/BATTA/AH/2602	Assumed	6	SF	0	SF			1	No	1/D	
1	3	Classroom 302	M	Transite Sills	1160/01/03/34	Confirmed	1	SF	0	SF		Fire Extinguisher Sill	1	No	1/D	
1	3	Computer Room 303/304	N/A	Concrete Block Wall		Non Suspect ACM	1160	SF	0	SF			N/A	N/A	N/A	
1	3	Computer Room 303/304	M	Floor Tile VAT 12" x 12"	1160/01/03/FF	Assumed	805	SF	0	SF	Tan		1	No	1/D	
1	3	Computer Room 303/304	N/A	Unit Ventilator Insulation		NAD	42	SF	0	SF			N/A	N/A	N/A	
1	3	Computer Room 303/304	M	Blackboard Glue Dots	1160/01/03/BATTA/AH/2600	Assumed	64	SF	0	SF			1	No	1/D	
1	3	Computer Room 303/304	S	Textured Ceiling Paint	1160/01/03/33	Confirmed	805	SF	0	SF			1	No	1/D	
1	3	Computer Room 303/304	M	Sink Undercoat Mastic	1160/01/03/BATTA/AH/2602	Assumed	12	SF	0	SF			1	No	1/D	
1	3	Computer Room 303/304	N/A	Sheetrock Wall		Non Suspect ACM	250	SF	0	SF			N/A	N/A	N/A	
1	3	Classroom 305	M	Sink Undercoat Mastic	1160/01/03/BATTA/AH/2602	Assumed	6	SF	0	SF			1	No	1/D	
1	3	Classroom 305	N/A	Sheetrock Wall		Non Suspect ACM	250	SF	0	SF			N/A	N/A	N/A	
1	3	Classroom 305	S	Textured Ceiling Paint	1160/01/03/33	Confirmed	713	SF	0	SF			1	No	1/D	
1	3	Classroom 305	N/A	Concrete Block Wall		Non Suspect ACM	580	SF	0	SF			N/A	N/A	N/A	
1	3	Classroom 305	M	Floor Tile VAT 12" x 12"	1160/01/03/FF	Assumed	713	SF	0	SF	Tan		1	No	1/D	
1	3	Classroom 305	N/A	Unit Ventilator Insulation		NAD	27	SF	0	SF			N/A	N/A	N/A	
1	3	Classroom 305	M	Blackboard Glue Dots	1160/01/03/BATTA/AH/2600	Assumed	144	SF	0	SF			1	No	1/D	
1	3	Classrooms 302 - 305 Pod Entrance Closet	N/A	Concrete Block Wall		Non Suspect ACM	340	SF	0	SF			N/A	N/A	N/A	
1	3	Classrooms 302 - 305 Pod Entrance Closet	N/A	Cement Floor		Non Suspect ACM	66	SF	0	SF			N/A	N/A	N/A	
1	3	Classrooms 302 - 305 Pod Entrance Closet	S	Textured Ceiling Paint	1160/01/03/33	Confirmed	66	SF	0	SF			1	No	1/D	
1	3	Roster Office 305B	N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	110	SF	0	SF			N/A	N/A	N/A	
1	3	Roster Office 305B	M	Floor Tile VAT 12" x 12"	1160/01/03/FF	Assumed	110	SF	0	SF	Grey		1	No	1/D	
1	3	Roster Office 305B	N/A	Concrete Block Wall		Non Suspect ACM	420	SF	0	SF			N/A	N/A	N/A	
1	3	Blue Team Leader Office next to Custodial Closet 306A	N/A	Ceiling Tile 2' x 4'		Non Suspect ACM	110	SF	0	SF			N/A	N/A	N/A	
1	3	Blue Team Leader Office next to Custodial Closet 306A	M	Floor Tile VAT 12" x 12"	1160/01/03/FF	Assumed	110	SF	0	SF	Grey		1	No	1/D	
1	3	Blue Team Leader Office next to Custodial Closet 306A	N/A	Concrete Block Wall		Non Suspect ACM	420	SF	0	SF			N/A	N/A	N/A	
1	3	Stair 2 next to Classroom 306	N/A	Cement Floor		Non Suspect ACM	288	SF	0	SF			N/A	N/A	N/A	
1	3	Stair 2 next to Classroom 306	S	Textured Ceiling Paint	1160/01/03/33	Confirmed	288	SF	0	SF			1	No	1/D	
1	3	Stair 2 next to Classroom 306	N/A	Concrete Block Wall		Non Suspect ACM	1224	SF	0	SF			N/A	N/A	N/A	
1	3	Custodial Closet 306A	N/A	Concrete Block Wall		Non Suspect ACM	700	SF	0	SF			N/A	N/A	N/A	
1	3	Custodial Closet 306A	N/A	Cement Floor		Non Suspect ACM	126	SF	0	SF		No access F2016 inspection	N/A	N/A	N/A	
1	3	Custodial Closet 306A	N/A	Concrete Ceiling		Non Suspect ACM	126	SF	0	SF		No access F2016 inspection	N/A	N/A	N/A	
1	3	Men's Restroom Entrance Lobby	M	Floor Tile VAT 12" x 12"	1160/01/03/FF	Assumed	81	SF	0	SF	Grey	No access F2016 inspection	N/A	N/A	N/A	
1	3	Men's Restroom Entrance Lobby	N/A	Concrete Block Wall		Non Suspect ACM	324	SF	0	SF			1	No	1/D	
1	3	Men's Restroom Entrance Lobby	N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	81	SF	0	SF			N/A	N/A	N/A	
1	3	Men's Restroom across from Classroom 306	N/A	Ceramic Tile Floors		Non Suspect ACM	40	SF	0	SF			N/A	N/A	N/A	
1	3	Men's Restroom across from Classroom 306	N/A	Concrete Block Wall		Non Suspect ACM	234	SF	0	SF			N/A	N/A	N/A	
1	3	Men's Restroom across from Classroom 306	S	Plaster Ceiling	1160/01/03/BATTA/AH/1900	Assumed	40	SF	0	SF			1	No	1/D	
1	3	Boy's Restroom across from Classroom 306	N/A	Ceramic Tile Floors		Non Suspect ACM	280	SF	3	SF			N/A	N/A	N/A	
1	3	Boy's Restroom across from Classroom 306	N/A	Concrete Block Wall		Non Suspect ACM	544	SF	0	SF			N/A	N/A	N/A	
1	3	Boy's Restroom across from Classroom 306	S	Plaster Ceiling	1160/01/03/BATTA/AH/1900	Assumed	280	SF	0	SF			1	No	1/D	
1	3	Girl's Restroom across from Classroom 306	N/A	Ceramic Tile Floors		Non Suspect ACM	180	SF	0	SF			N/A	N/A	N/A	
1	3	Girl's Restroom across from Classroom 306	N/A	Concrete Block Wall		Non Suspect ACM	540	SF	0	SF			N/A	N/A	N/A	
1	3	Girl's Restroom across from Classroom 306	S	Plaster Ceiling	1160/01/03/BATTA/AH/1900	Assumed	180	SF	0	SF			1	No	1/D	
1	3	Classroom 306 Entrance	M	Floor Tile VAT 12" x 12"	1160/01/03/FF	Assumed	165	SF	0	SF	Grey		1	No	1/D	
1	3	Classroom 306 Entrance	N/A	Concrete Block Wall		Non Suspect ACM	468	SF	0	SF			N/A	N/A	N/A	
1	3	Classroom 306 Entrance	N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	165	SF	0	SF			N/A	N/A	N/A	
1	3	Classroom 306 Entrance Office	M	Floor Tile VAT 12" x 12"	1160/01/03/FF	Assumed	154	SF	0	SF	Grey		1	No	1/D	
1	3	Classroom 306 Entrance Office	N/A	Concrete Block Wall		Non Suspect ACM	450	SF	0	SF			N/A	N/A	N/A	
1	3	Classroom 306 Entrance Office	N/A	Ceiling Tile 2' x 4'		Non Suspect ACM	154	SF	1	SF			N/A	N/A	N/A	
1	3	Classroom 306 Entrance Storage Room on Classroom 307 side	M	Floor Tile VAT 12" x 12"	1160/01/03/FF	Assumed	121	SF	0	SF	Grey		1	No	1/D	
1	3	Classroom 306 Entrance Storage Room on Classroom 307 side	N/A	Concrete Block Wall		Non Suspect ACM	396	SF	0	SF			N/A	N/A	N/A	
1	3	Classroom 306 Entrance Storage Room on Classroom 307 side	N/A	Ceiling Tile 2' x 4'		Non Suspect ACM	121	SF	0	SF			N/A	N/A	N/A	

1160 Motivation HS/KIPP West @ Turner - 2015-2016 AHERA Three-Year Report.xls

		School District of Philadelphia Motivation High School and KIPP Turner West Middle School 5900 Baltimore Avenue, Philadelphia, PA 19143 ULCS# 1160 Year Built: 1969		AHERA Three-Year Reinspection 2015-2016 Room by Room Location Log Report							Reinspection Date: 9/29/15						
											Building Inspector: William Garrity, Jr.						
											Number: 70016699A						
											Management Planner: Mary Anne Lerro						
											Number: 740728						
E l e m e n t	F l o o r	On Site Room Name		System Affected	Material Description	HID#	Confirmed/Assumed/NAD/ Non Suspect ACM	Amount of Material	SF LF EA	Amount of Damage	SF LF EA	Color required for VAT	Comments/Description/Notes	Attic/ Crawl Space Ranking	Damage Potential (DP)	Newly Friable (NF)	Response Action (RA)
1	3	Classroom 306 Entrance Storage Room Closet	M	Floor Tile VAT 12" x 12"	1160/01/03/FF	Assumed	12	SF	0	SF		Grey			1	No	1/D
1	3	Classroom 306 Entrance Storage Room Closet	N/A	Concrete Block Wall		Non Suspect ACM	126	SF	0	SF					N/A	N/A	N/A
1	3	Classroom 306 Entrance Storage Room Closet	N/A	Ceiling Tile 2' x 4'		Non Suspect ACM	12	SF	0	SF					N/A	N/A	N/A
1	3	Classroom 306 Storage Room	M	Floor Tile VAT 12" x 12"	1160/01/03/FF	Assumed	121	SF	0	SF		Grey			1	No	1/D
1	3	Classroom 306 Storage Room	N/A	Concrete Block Wall		Non Suspect ACM	396	SF	0	SF					N/A	N/A	N/A
1	3	Classroom 306 Storage Room	N/A	Ceiling Tile 2' x 4'		Non Suspect ACM	121	SF	0	SF					N/A	N/A	N/A
1	3	Classroom 306	M	Floor Tile VAT 12" x 12"	1160/01/03/FF	Assumed	945	SF	0	SF		Grey			1	No	1/D
1	3	Classroom 306	N/A	Concrete Block Wall		Non Suspect ACM	1320	SF	0	SF					N/A	N/A	N/A
1	3	Classroom 306	S	Textured Ceiling Paint	1160/01/03/33	Confirmed	945	SF	0	SF					1	No	1/D
1	3	Classroom 306	N/A	Fiberglass Pipe Fitting Insulation		Non Suspect ACM	6	EA	0	EA					N/A	N/A	N/A
1	3	Classroom 306	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	30	LF	0	LF					N/A	N/A	N/A
1	3	Classroom 306	M	Sink Undercoat Mastic	1160/01/03/BATTA/AH/2602	Assumed	6	SF	0	SF					1	No	1/D
1	3	IMC	M	Floor Tile VAT 12" x 12"	1160/01/03/FF	Assumed	3900	SF	0	SF		Blue			1	No	1/D
1	3	IMC	M	Ceiling Tile 1' x 1'	1160/01/03/BATTA/AH/1710	Assumed	3900	SF	0	SF					1	No	1/D
1	3	IMC	N/A	Ceiling Tile 2' x 4'		Non Suspect ACM	830	SF	0	SF					N/A	N/A	N/A
1	3	IMC	N/A	Concrete Block Wall		Non Suspect ACM	4250	SF	0	SF					N/A	N/A	N/A
1	3	IMC	N/A	Transite Sills	1160/01/03/34	Confirmed	2	SF	0	SF			Fire Extinguisher Sill		1	No	1/D
1	3	IMC Storage Room (former Office)	M	Ceiling Tile 2' x 4'		Non Suspect ACM	264	SF	0	SF					N/A	N/A	N/A
1	3	IMC Storage Room (former Office)	N/A	Concrete Block Wall		Non Suspect ACM	544	SF	0	SF					N/A	N/A	N/A
1	3	IMC Storage Room (former Office)	M	Floor Tile VAT 12" x 12"	1160/01/03/FF	Assumed	264	SF	0	SF		Blue			1	No	1/D
1	3	IMC AV Storage / Elevator Access	N/A	Concrete Block Wall		Non Suspect ACM	640	SF	0	SF					N/A	N/A	N/A
1	3	IMC AV Storage / Elevator Access	N/A	Ceiling Tile 2' x 4'		Non Suspect ACM	400	SF	0	SF					N/A	N/A	N/A
1	3	IMC AV Storage / Elevator Access	M	Floor Tile VAT 12" x 12"	1160/01/03/FF	Assumed	400	SF	0	SF		Blue			1	No	1/D
1	3	IMC Book Closet	N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	42	SF	0	SF					N/A	N/A	N/A
1	3	IMC Book Closet	M	Floor Tile VAT 12" x 12"	1160/01/03/FF	Assumed	42	SF	0	SF		Grey			1	No	1/D
1	3	IMC Book Closet	N/A	Concrete Block Wall		Non Suspect ACM	208	SF	0	SF					N/A	N/A	N/A
1	3	IMC Conference Room	N/A	Ceiling Tile 2' x 4'		Non Suspect ACM	480	SF	0	SF					N/A	N/A	N/A
1	3	IMC Conference Room	N/A	Concrete Block Wall		Non Suspect ACM	736	SF	0	SF					N/A	N/A	N/A
1	3	IMC Conference Room	M	Floor Tile VAT 12" x 12"	1160/01/03/FF	Assumed	480	SF	0	SF		Blue			1	No	1/D
1	3	IMC Conference Room	M	Blackboard Glue Dots	1160/01/03/BATTA/AH/2600	Assumed	128	SF	0	SF					1	No	1/D
1	3	IMC Conference Room	N/A	Partition Room Dividers		Non Suspect ACM	128	SF	0	SF			Vinyl accordion type		N/A	N/A	N/A
1	3	IMC Mechanical Production Storage / Access to Mechanical Loft	M	Floor Tile VAT 12" x 12"	1160/01/03/FF	Assumed	68	SF	0	SF		Grey			1	No	1/D
1	3	IMC Mechanical Production Storage / Access to Mechanical Loft	M	Floor Tile VAT 9" x 9"	1160/01/01/01	Confirmed	68	SF	0	SF		Grey			1	No	1/D
1	3	IMC Mechanical Production Storage / Access to Mechanical Loft	N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	136	SF	2	SF					N/A	N/A	N/A
1	3	IMC Mechanical Production Storage / Access to Mechanical Loft	N/A	Concrete Block Wall		Non Suspect ACM	400	SF	0	SF					N/A	N/A	N/A
1	3	IMC Mechanical Production Storage / Access to Mechanical Loft	M	Sink Undercoat Mastic	1160/01/03/BATTA/AH/2602	Assumed	4	SF	0	SF					1	No	1/D
1	3	IMC Storage Room (former Language Lab 1)	N/A	Ceiling Tile 2' x 4'		Non Suspect ACM	805	SF	0	SF					N/A	N/A	N/A
1	3	IMC Storage Room (former Language Lab 1)	N/A	Concrete Block Wall		Non Suspect ACM	1160	SF	0	SF					N/A	N/A	N/A
1	3	IMC Storage Room (former Language Lab 1)	M	Floor Tile VAT 12" x 12"	1160/01/03/FF	Assumed	805	SF	0	SF		Blue			1	No	1/D
1	3	Classroom 307	M	Floor Tile VAT 12" x 12"	1160/01/03/FF	Assumed	782	SF	0	SF		Tan			1	No	1/D
1	3	Classroom 307	N/A	Concrete Block Wall		Non Suspect ACM	1140	SF	0	SF					N/A	N/A	N/A
1	3	Classroom 307	S	Textured Ceiling Paint	1160/01/03/33	Confirmed	782	SF	0	SF					1	No	1/D
1	3	Classroom 307	N/A	Unit Ventilator Insulation		NAD	24	SF	0	SF					N/A	N/A	N/A
1	3	Classroom 307	N/A	Partition Room Dividers		Non Suspect ACM	150	SF	0	SF			Made of wood		N/A	N/A	N/A
1	3	Hallway between 302-305 Pod and Classroom 307	N/A	Concrete Block Wall		Non Suspect ACM	1904	SF	0	SF					N/A	N/A	N/A
1	3	Hallway between 302-305 Pod and Classroom 307	N/A	Ceiling Tile 2' x 4'		Non Suspect ACM	1090	SF	0	SF					N/A	N/A	N/A
1	3	Hallway between 302-305 Pod and Classroom 307	N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	550	SF	0	SF					N/A	N/A	N/A
1	3	Hallway between 302-305 Pod and Classroom 307	M	Floor Tile VAT 12" x 12"	1160/01/03/FF	Assumed	1090	SF	0	SF		Multi			1	No	1/D
1	3	Hallway between 302-305 Pod and Classroom 307	M	Transite Sills	1160/01/03/34	Confirmed	2	SF	0	SF			Fire Extinguisher Sill		1	No	1/D
1	3	Classrooms 308 - 311 Pod Entrance	S	Textured Ceiling Paint	1160/01/03/33	Confirmed	702	SF	0	SF					1	No	1/D
1	3	Classrooms 308 - 311 Pod Entrance	N/A	Concrete Block Wall		Non Suspect ACM	1260	SF	0	SF					N/A	N/A	N/A
1	3	Classrooms 308 - 311 Pod Entrance	M	Floor Tile VAT 12" x 12"	1160/01/03/FF	Assumed	702	SF	0	SF		Grey			1	No	1/D
1	3	Classrooms 308 - 311 Pod Entrance	M	Transite Sills	1160/01/03/34	Confirmed	1	SF	0	SF			Fire Extinguisher Sill		1	No	1/D
1	3	Classrooms 308 - 311 Pod Entrance Book Closet	N/A	Cement Floor		Non Suspect ACM	66	SF	0	SF			No access F2016 inspection		N/A	N/A	N/A
1	3	Classrooms 308 - 311 Pod Entrance Book Closet	N/A	Concrete Block Wall		Non Suspect ACM	408	SF	0	SF			No access F2016 inspection		N/A	N/A	N/A
1	3	Classrooms 308 - 311 Pod Entrance Book Closet	N/A	Concrete Ceiling		Non Suspect ACM	66	SF	0	SF			No access F2016 inspection		N/A	N/A	N/A
1	3	Classroom 308	M	Floor Tile VAT 12" x 12"	1160/01/03/FF	Assumed	805	SF	0	SF		Tan			1	No	1/D
1	3	Classroom 308	N/A	Concrete Block Wall		Non Suspect ACM	1160	SF	0	SF					N/A	N/A	N/A
1	3	Classroom 308	S	Textured Ceiling Paint	1160/01/03/33	Confirmed	805	SF	0	SF					1	No	1/D
1	3	Classroom 308	N/A	Unit Ventilator Insulation		NAD	24	SF	0	SF					N/A	N/A	N/A
1	3	Classroom 308	N/A	Partition Room Dividers		Non Suspect ACM	150	SF	0	SF			Made of wood		N/A	N/A	N/A
1	3	Classroom 308	M	Sink Undercoat Mastic	1160/01/03/BATTA/AH/2602	Assumed	6	SF	0	SF					1	No	1/D
1	3	Classroom 309	N/A	Concrete Block Wall		Non Suspect ACM	860	SF	0	SF					N/A	N/A	N/A
1	3	Classroom 309	M	Floor Tile VAT 12" x 12"	1160/01/03/FF	Assumed	805	SF	0	SF		Tan			1	No	1/D
1	3	Classroom 309	S	Textured Ceiling Paint	1160/01/03/33	Confirmed	805	SF	0	SF					1	No	1/D
1	3	Classroom 309	M	Blackboard Glue Dots	1160/01/03/BATTA/AH/2600	Assumed	160	SF	0	SF					1	No	1/D

1160 Motivation HS/KIPP West @ Turner - 2015-2016 AHERA Three-Year Report.xls

		School District of Philadelphia Motivation High School and KIPP Turner West Middle School 5900 Baltimore Avenue, Philadelphia, PA 19143 ULCS# 1160 Year Built: 1969		AHERA Three-Year Reinspection 2015-2016 Room by Room Location Log Report							Reinspection Date: 9/29/15						
											Building Inspector: William Garrity, Jr.						
											Number: 70016699A						
											Management Planner: Mary Anne Lerro						
											Number: 740728						
E l e m e n t	F l o o r	On Site Room Name		System Affected	Material Description	HID#	Confirmed/Assumed/NAD/ Non Suspect ACM	Amount of Material	SF LF EA	Amount of Damage	SF LF EA	Color required for VAT	Comments/Description/Notes	Attic/ Crawl Space Ranking	Damage Potential (DP)	Newly Friable (NF)	Response Action (RA)
		1	3	Classroom 309	N/A	Unit Ventilator Insulation		NAD	27	SF	0	SF					N/A
1	3	Classroom 309	N/A	Sheetrock Wall		Non Suspect ACM	300	SF	0	SF					N/A	N/A	N/A
1	3	Classroom 310	S	Textured Ceiling Paint	1160/01/03/33	Confirmed	713	SF	0	SF					1	No	1/D
1	3	Classroom 310	N/A	Sheetrock Wall		Non Suspect ACM	680	SF	0	SF					N/A	N/A	N/A
1	3	Classroom 310	N/A	Concrete Block Wall		Non Suspect ACM	400	SF	0	SF					N/A	N/A	N/A
1	3	Classroom 310	M	Floor Tile VAT 12" x 12"	1160/01/03/FF	Assumed	713	SF	0	SF	Tan				1	No	1/D
1	3	Classroom 311	M	Floor Tile VAT 12" x 12"	1160/01/03/FF	Assumed	713	SF	0	SF	Tan				1	No	1/D
1	3	Classroom 311	S	Textured Ceiling Paint	1160/01/03/33	Confirmed	713	SF	0	SF					1	No	1/D
1	3	Classroom 311	M	Blackboard Glue Dots	1160/01/03/BATTA/AH/2600	Assumed	200	SF	0	SF	240				1	No	1/D
1	3	Classroom 311	N/A	Unit Ventilator Insulation		NAD	27	SF	0	SF	27				N/A	N/A	N/A
1	3	Classroom 311	N/A	Concrete Block Wall		Non Suspect ACM	1080	SF	0	SF					N/A	N/A	N/A
1	3	Classroom 311	N/A	Sheetrock Wall		Non Suspect ACM	300	SF	0	SF					N/A	N/A	N/A
1	3	Classroom 311	M	Sink Undercoat Mastic	1160/01/03/BATTA/AH/2602	Assumed	9	SF	0	SF					1	No	1/D
1	3	Stair 3 next to Classroom 312	S	Textured Ceiling Paint	1160/01/03/33	Confirmed	288	SF	0	SF					1	No	1/D
1	3	Stair 3 next to Classroom 312	N/A	Cement Floor		Non Suspect ACM	288	SF	0	SF					N/A	N/A	N/A
1	3	Stair 3 next to Classroom 312	N/A	Concrete Block Wall		Non Suspect ACM	1224	SF	0	SF					N/A	N/A	N/A
1	3	Classroom 312	N/A	Concrete Block Wall		Non Suspect ACM	1980	SF	0	SF					N/A	N/A	N/A
1	3	Classroom 312	M	Floor Tile VAT 12" x 12"	1160/01/03/FF	Assumed	1548	SF	0	SF	Grey				1	No	1/D
1	3	Classroom 312	S	Textured Ceiling Paint	1160/01/03/33	Confirmed	1548	SF	0	SF					1	No	1/D
1	3	Classroom 312	M	Blackboard Glue Dots	1160/01/03/BATTA/AH/2600	Assumed	56	SF	0	SF					1	No	1/D
1	3	Classroom 312	N/A	Unit Ventilator Insulation		NAD	54	SF	0	SF					N/A	N/A	N/A
1	3	Classroom 312	M	Transite Sink	1160/01/03/34	Confirmed	30	SF	0	SF					1	No	1/D
1	3	Classroom 312	M	Transite Lab Counters	1160/01/03/34	Confirmed	210	SF	0	SF					1	No	1/D
1	3	Classroom 312	N/A	Fiberglass Pipe Fitting Insulation		Non Suspect ACM	8	EA	0	EA					N/A	N/A	N/A
1	3	Classroom 312	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	50	LF	0	LF					N/A	N/A	N/A
1	3	Classroom 312 Preparation Room	N/A	Concrete Block Wall		Non Suspect ACM	616	SF	0	SF					N/A	N/A	N/A
1	3	Classroom 312 Preparation Room	M	Floor Tile VAT 12" x 12"	1160/01/03/FF	Assumed	160	SF	0	SF	Grey				1	No	1/D
1	3	Classroom 312 Preparation Room	S	Textured Ceiling Paint	1160/01/03/33	Confirmed	160	SF	0	SF					1	No	1/D
1	3	Classroom 312 Preparation Room	M	Transite Lab Counters	1160/01/03/34	Confirmed	22	SF	0	SF					1	No	1/D
1	3	Classroom 312 Preparation Room	M	Transite Sink	1160/01/03/34	Confirmed	5	SF	0	SF					1	No	1/D
1	3	Empty Office 312A	M	Floor Tile VAT 12" x 12"	1160/01/03/FF	Assumed	204	SF	0	SF	Grey				1	No	1/D
1	3	Empty Office 312A	N/A	Concrete Block Wall		Non Suspect ACM	580	SF	0	SF					N/A	N/A	N/A
1	3	Empty Office 312A	N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	204	SF	0	SF					N/A	N/A	N/A
1	3	Storage Room 312B	M	Floor Tile VAT 12" x 12"	1160/01/03/FF	Assumed	204	SF	0	SF	Grey				1	No	1/D
1	3	Storage Room 312B	N/A	Concrete Block Wall		Non Suspect ACM	580	SF	0	SF					N/A	N/A	N/A
1	3	Storage Room 312B	N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	204	SF	0	SF					N/A	N/A	N/A
1	3	Classroom 313	N/A	Concrete Block Wall		Non Suspect ACM	1140	SF	0	SF					N/A	N/A	N/A
1	3	Classroom 313	M	Floor Tile VAT 12" x 12"	1160/01/03/FF	Assumed	770	SF	0	SF	Tan				1	No	1/D
1	3	Classroom 313	S	Textured Ceiling Paint	1160/01/03/33	Confirmed	770	SF	0	SF					1	No	1/D
1	3	Classroom 313	M	Blackboard Glue Dots	1160/01/03/BATTA/AH/2600	Assumed	176	SF	0	SF					1	No	1/D
1	3	Classroom 313	N/A	Unit Ventilator Insulation		NAD	27	SF	0	SF					N/A	N/A	N/A
1	3	Hallway from 308-311 Pod to Classroom 313	M	Floor Tile VAT 12" x 12"	1160/01/03/FF	Assumed	1090	SF	0	SF	Grey				1	No	1/D
1	3	Hallway from 308-311 Pod to Classroom 313	N/A	Concrete Block Wall		Non Suspect ACM	1904	SF	0	SF					N/A	N/A	N/A
1	3	Hallway from 308-311 Pod to Classroom 313	N/A	Ceiling Tile 2' x 4'		Non Suspect ACM	550	SF	0	SF					N/A	N/A	N/A
1	3	Hallway from 308-311 Pod to Classroom 313	N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	550	SF	0	SF					N/A	N/A	N/A
1	3	Hallway from 308-311 Pod to Classroom 313	M	Floor Tile VAT 12" x 12"	1160/01/03/FF	Assumed	64	SF	0	SF	Red				1	No	1/D
1	3	Hallway from 308-311 Pod to Classroom 313	M	Transite Sills	1160/01/03/34	Confirmed	2	SF	0	SF			Fire Extinguisher Sill		1	No	1/D
1	3	Classrooms 314 - 317 Pod Entrance	S	Textured Ceiling Paint	1160/01/03/33	Confirmed	702	SF	0	SF					1	No	1/D
1	3	Classrooms 314 - 317 Pod Entrance	N/A	Concrete Block Wall		Non Suspect ACM	1260	SF	0	SF					N/A	N/A	N/A
1	3	Classrooms 314 - 317 Pod Entrance	M	Floor Tile VAT 12" x 12"	1160/01/03/FF	Assumed	702	SF	0	SF	Grey				1	No	1/D
1	3	Classrooms 314 - 317 Pod Entrance	M	Transite Sills	1160/01/03/34	Confirmed	1	SF	0	SF			Fire Extinguisher Sill		1	No	1/D
1	3	Classroom 314	N/A	Concrete Block Wall		Non Suspect ACM	860	SF	0	SF					N/A	N/A	N/A
1	3	Classroom 314	M	Floor Tile VAT 12" x 12"	1160/01/03/FF	Assumed	805	SF	0	SF	Tan				1	No	1/D
1	3	Classroom 314	S	Textured Ceiling Paint	1160/01/03/33	Confirmed	805	SF	0	SF					1	No	1/D
1	3	Classroom 314	M	Blackboard Glue Dots	1160/01/03/BATTA/AH/2600	Assumed	140	SF	0	SF					1	No	1/D
1	3	Classroom 314	N/A	Unit Ventilator Insulation		NAD	27	SF	0	SF					N/A	N/A	N/A
1	3	Classroom 314	N/A	Sheetrock Wall		Non Suspect ACM	300	SF	0	SF					N/A	N/A	N/A
1	3	Classroom 314	M	Transite Sills	1160/01/03/34	Confirmed	1	SF	0	SF			Fire Extinguisher Sill		1	No	1/D
1	3	Classroom 315	N/A	Concrete Block Wall		Non Suspect ACM	860	SF	0	SF					N/A	N/A	N/A
1	3	Classroom 315	M	Floor Tile VAT 12" x 12"	1160/01/03/FF	Assumed	805	SF	0	SF	Tan				1	No	1/D
1	3	Classroom 315	S	Textured Ceiling Paint	1160/01/03/33	Confirmed	805	SF	0	SF					1	No	1/D
1	3	Classroom 315	M	Blackboard Glue Dots	1160/01/03/BATTA/AH/2600	Assumed	96	SF	0	SF					1	No	1/D
1	3	Classroom 315	N/A	Unit Ventilator Insulation		NAD	27	SF	0	SF					N/A	N/A	N/A
1	3	Classroom 315	N/A	Sheetrock Wall		Non Suspect ACM	300	SF	0	SF					N/A	N/A	N/A
1	3	Classroom 315	M	Sink Undercoat Mastic	1160/01/03/BATTA/AH/2602	Assumed	12	SF	0	SF					1	No	1/D
1	3	Classroom 316	N/A	Concrete Block Wall		Non Suspect ACM	400	SF	0	SF					N/A	N/A	N/A
1	3	Classroom 316	M	Floor Tile VAT 12" x 12"	1160/01/03/FF	Assumed	713	SF	0	SF	Tan				1	No	1/D
1	3	Classroom 316	S	Textured Ceiling Paint	1160/01/03/33	Confirmed	713	SF	0	SF					1	No	1/D
1	3	Classroom 316	M	Blackboard Glue Dots	1160/01/03/BATTA/AH/2600	Assumed	96	SF	0	SF					1	No	1/D
1	3	Classroom 316	N/A	Unit Ventilator Insulation		NAD	27	SF	0	SF					N/A	N/A	N/A
1	3	Classroom 316	N/A	Sheetrock Wall		Non Suspect ACM	680	SF	0	SF					N/A	N/A	N/A

1160 Motivation HS/KIPP West @ Turner - 2015-2016 AHERA Three-Year Report.xls

		School District of Philadelphia Motivation High School and KIPP Turner West Middle School 5900 Baltimore Avenue, Philadelphia, PA 19143 ULCS# 1160 Year Built: 1969		AHERA Three-Year Reinspection 2015-2016 Room by Room Location Log Report							Reinspection Date: 9/29/15						
											Building Inspector: William Garrity, Jr.						
											Number: 70016699A						
											Management Planner: Mary Anne Lerro						
											Number: 740728						
E l e m e n t	F l o o r	On Site Room Name		System Affected	Material Description	HID#	Confirmed/Assumed/NAD/ Non Suspect ACM	Amount of Material	SF LF EA	Amount of Damage	SF LF EA	Color required for VAT	Comments/Description/Notes	Attic/ Crawl Space Ranking	Damage Potential (DP)	Newly Friable (NF)	Response Action (RA)
1	3	Classroom 317	N/A	Concrete Block Wall			Non Suspect ACM	780	SF	0	SF				N/A	N/A	N/A
1	3	Classroom 317	M	Floor Tile VAT 12" x 12"	1160/01/03/FF		Assumed	713	SF	0	SF	Tan			1	No	1/D
1	3	Classroom 317	S	Textured Ceiling Paint	1160/01/03/33		Confirmed	713	SF	0	SF				1	No	1/D
1	3	Classroom 317	M	Blackboard Glue Dots	1160/01/03/BATTA/AH/2600		Assumed	156	SF	0	SF				1	No	1/D
1	3	Classroom 317	N/A	Unit Ventilator Insulation			NAD	27	SF	0	SF				N/A	N/A	N/A
1	3	Classroom 317	N/A	Sheetrock Wall			Non Suspect ACM	300	SF	0	SF				N/A	N/A	N/A
1	3	Classroom 317	M	Sink Undercoat Mastic	1160/01/03/BATTA/AH/2602		Assumed	6	SF	0	SF				1	No	1/D
1	3	Classrooms 314 - 317 Pod Entrance Book Closet	X	X			X	X	X	X	X		No access		X	X	X
1	3	Stair 4 next to Classroom 318	S	Textured Ceiling Paint	1160/01/03/33		Confirmed	288	SF	0	SF				1	No	1/D
1	3	Stair 4 next to Classroom 318	N/A	Cement Floor			Non Suspect ACM	288	SF	0	SF				N/A	N/A	N/A
1	3	Stair 4 next to Classroom 318	N/A	Concrete Block Wall			Non Suspect ACM	1224	SF	0	SF				N/A	N/A	N/A
1	3	Classroom 318 Entrance	M	Floor Tile VAT 12" x 12"	1160/01/03/FF		Assumed	154	SF	0	SF	Grey			1	No	1/D
1	3	Classroom 318 Entrance	N/A	Concrete Block Wall			Non Suspect ACM	500	SF	0	SF				N/A	N/A	N/A
1	3	Classroom 318 Entrance	N/A	Fiberglass Ceiling Tile 2' x 4'			Non Suspect ACM	154	SF	0	SF				N/A	N/A	N/A
1	3	Special Education Liasion Office	M	Floor Tile VAT 12" x 12"	1160/01/03/FF		Assumed	121	SF	0	SF	Grey			1	No	1/D
1	3	Special Education Liasion Office	N/A	Concrete Block Wall			Non Suspect ACM	440	SF	0	SF				N/A	N/A	N/A
1	3	Special Education Liasion Office	N/A	Ceiling Tile 2' x 4'			Non Suspect ACM	121	SF	0	SF				N/A	N/A	N/A
1	3	Special Education Liasion Office Closet	M	Floor Tile VAT 12" x 12"	1160/01/03/FF		Assumed	9	SF	0	SF	Grey			1	No	1/D
1	3	Special Education Liasion Office Closet	N/A	Concrete Block Wall			Non Suspect ACM	120	SF	0	SF				N/A	N/A	N/A
1	3	Special Education Liasion Office Closet	N/A	Ceiling Tile 2' x 4'			Non Suspect ACM	9	SF	0	SF				N/A	N/A	N/A
1	3	Classroom 318 Storage Room	M	Floor Tile VAT 12" x 12"	1160/01/03/FF		Assumed	154	SF	0	SF	Grey			1	No	1/D
1	3	Classroom 318 Storage Room	N/A	Concrete Block Wall			Non Suspect ACM	500	SF	0	SF				N/A	N/A	N/A
1	3	Classroom 318 Storage Room	N/A	Ceiling Tile 2' x 4'			Non Suspect ACM	154	SF	0	SF				N/A	N/A	N/A
1	3	Classroom 318 Storage Room	M	Blackboard Glue Dots	1160/01/03/BATTA/AH/2600		Assumed	32	SF	0	SF				1	No	1/D
1	3	Classroom 318 Entrance Storage Room	M	Floor Tile VAT 12" x 12"	1160/01/03/FF		Assumed	154	SF	0	SF	Grey			1	No	1/D
1	3	Classroom 318 Entrance Storage Room	N/A	Concrete Block Wall			Non Suspect ACM	500	SF	0	SF				N/A	N/A	N/A
1	3	Classroom 318 Entrance Storage Room	N/A	Ceiling Tile 2' x 4'			Non Suspect ACM	154	SF	0	SF	3			N/A	N/A	N/A
1	3	Classroom 318	N/A	Concrete Block Wall			Non Suspect ACM	1340	SF	0	SF				N/A	N/A	N/A
1	3	Classroom 318	M	Floor Tile VAT 12" x 12"	1160/01/03/FF		Assumed	990	SF	0	SF	Brown			1	No	1/D
1	3	Classroom 318	S	Textured Ceiling Paint	1160/01/03/33		Confirmed	990	SF	0	SF				1	No	1/D
1	3	Classroom 318	M	Sink Undercoat Mastic	1160/01/03/BATTA/AH/2602		Assumed	6	SF	0	SF				1	No	1/D
1	3	Classroom 318	N/A	Fiberglass Pipe Insulation			Non Suspect ACM	12	LF	0	LF				N/A	N/A	N/A
1	3	Classroom 318	N/A	Fiberglass Pipe Fitting Insulation			Non Suspect ACM	4	EA	0	EA				N/A	N/A	N/A
1	3	Girl's Restroom across from Classroom 318	N/A	Concrete Block Wall			Non Suspect ACM	450	SF	0	SF				N/A	N/A	N/A
1	3	Girl's Restroom across from Classroom 318	S	Plaster Ceiling	1160/01/03/BATTA/AH/1900		Assumed	150	SF	0	SF				1	No	1/D
1	3	Girl's Restroom across from Classroom 318	N/A	Ceramic Tile Floors			Non Suspect ACM	150	SF	0	SF				N/A	N/A	N/A
1	3	Custodial Closet across from Classroom 318	X	X			X	X	X	X		No access			X	X	X
1	3	Boy's Restroom across from Classroom 318	N/A	Ceramic Tile Floors			Non Suspect ACM	150	SF	0	SF				N/A	N/A	N/A
1	3	Boy's Restroom across from Classroom 318	N/A	Concrete Block Wall			Non Suspect ACM	450	SF	0	SF				N/A	N/A	N/A
1	3	Boy's Restroom across from Classroom 318	S	Plaster Ceiling	1160/01/03/BATTA/AH/1900		Assumed	150	SF	0	SF				1	No	1/D
1	3	Women's Restroom Entrance Lounge	N/A	Fiberglass Ceiling Tile 2' x 4'			Non Suspect ACM	81	SF	0	SF				N/A	N/A	N/A
1	3	Women's Restroom Entrance Lounge	N/A	Concrete Block Wall			Non Suspect ACM	324	SF	0	SF				N/A	N/A	N/A
1	3	Women's Restroom Entrance Lounge	M	Floor Tile VAT 12" x 12"	1160/01/03/FF		Assumed	81	SF	0	SF	Grey			1	No	1/D
1	3	Women's Restroom	S	Plaster Ceiling	1160/01/03/BATTA/WG/1900		Assumed	40	SF	0	SF				1	No	1/D
1	3	Women's Restroom	N/A	Concrete Block Wall			Non Suspect ACM	234	SF	0	SF				N/A	N/A	N/A
1	3	Women's Restroom	N/A	Ceramic Tile Floors			Non Suspect ACM	40	SF	0	SF				N/A	N/A	N/A
1	3	Classroom 319	M	Blackboard Glue Dots	1160/01/03/BATTA/AH/2600		Assumed	160	SF	0	SF				1	No	1/D
1	3	Classroom 319	M	Floor Tile VAT 12" x 12"	1160/01/03/FF		Assumed	770	SF	0	SF	Tan			1	No	1/D
1	3	Classroom 319	N/A	Concrete Block Wall			Non Suspect ACM	1140	SF	0	SF				N/A	N/A	N/A
1	3	Classroom 319	S	Textured Ceiling Paint	1160/01/03/33		Confirmed	770	SF	0	SF				1	No	1/D
1	3	Classroom 319	N/A	Unit Ventilator Insulation			NAD	27	SF	0	SF				N/A	N/A	N/A
1	3	Classroom 319	N/A	Partition Room Dividers			Non Suspect ACM	170	SF	0	SF		Made of wood		N/A	N/A	N/A
1	3	Climate Support Staff Office across from Classroom 319	N/A	Concrete Block Wall			Non Suspect ACM	352	SF	0	SF				N/A	N/A	N/A
1	3	Climate Support Staff Office across from Classroom 319	N/A	Ceiling Tile 2' x 4'			Non Suspect ACM	121	SF	0	SF				N/A	N/A	N/A
1	3	Climate Support Staff Office across from Classroom 319	M	Floor Tile VAT 12" x 12"	1160/01/03/FF		Assumed	121	SF	0	SF	Grey			1	No	1/D
1	3	Empty Office next to Climate Support Office	N/A	Fiberglass Ceiling Tile 2' x 4'			Non Suspect ACM	121	SF	0	SF				N/A	N/A	N/A
1	3	Empty Office next to Climate Support Office	N/A	Concrete Block Wall			Non Suspect ACM	440	SF	0	SF				N/A	N/A	N/A
1	3	Empty Office next to Climate Support Office	M	Floor Tile VAT 12" x 12"	1160/01/03/FF		Assumed	121	SF	0	SF	Grey			1	No	1/D
1	3	Hallway from 314-317 Pod to Classroom 319	M	Transite Sills	1160/01/03/FF		Confirmed	2	SF	0	SF				1	No	1/D
1	3	Hallway from 314-317 Pod to Classroom 319	N/A	Concrete Block Wall			Non Suspect ACM	1904	SF	0	SF				N/A	N/A	N/A
1	3	Hallway from 314-317 Pod to Classroom 319	N/A	Ceiling Tile 2' x 4'			Non Suspect ACM	550	SF	0	SF				N/A	N/A	N/A
1	3	Hallway from 314-317 Pod to Classroom 319	M	Floor Tile VAT 12" x 12"	1160/01/03/FF		Assumed	1090	SF	0	SF	Grey			1	No	1/D
1	3	Hallway from 314-317 Pod to Classroom 319	N/A	Fiberglass Ceiling Tile 2' x 4'			Non Suspect ACM	550	SF	0	SF				N/A	N/A	N/A
1	3	Classrooms 320 - 323 Pod Entrance	S	Textured Ceiling Paint	1160/01/03/33		Confirmed	702	SF	0	SF				1	No	1/D
1	3	Classrooms 320 - 323 Pod Entrance	N/A	Concrete Block Wall			Non Suspect ACM	1260	SF	0	SF				N/A	N/A	N/A
1	3	Classrooms 320 - 323 Pod Entrance	M	Floor Tile VAT 12" x 12"	1160/01/03/FF		Assumed	702	SF	0	SF		Please verify color		1	No	1/D
1	3	Classroom 320	N/A	Concrete Block Wall			Non Suspect ACM	1160	SF	0	SF				N/A	N/A	N/A
1	3	Classroom 320	M	Floor Tile VAT 12" x 12"	1160/01/03/FF		Assumed	805	SF	0	SF	Tan			1	No	1/D

1160 Motivation HS/KIPP West @ Turner - 2015-2016 AHERA Three-Year Report.xls

E l e m e n t		F l o o r		School District of Philadelphia Motivation High School and KIPP Turner West Middle School 5900 Baltimore Avenue, Philadelphia, PA 19143 ULCS# 1160 Year Built: 1969		AHERA Three-Year Reinspection 2015-2016 Room by Room Location Log Report						Reinspection Date: 9/29/15		Attic/ Crawl Space Ranking	Damage Potential (DP)	Newly Friable (NF)	Response Action (RA)
						On Site Room Name		System Affected	Material Description	HID#	Confirmed/Assumed/NAD/ Non Suspect ACM	Amount of Material	SF LF EA				
1	3	Classroom 320	S	Textured Ceiling Paint	1160/01/03/33	Confirmed	805	SF	0	SF				1	No	1/D	
1	3	Classroom 320	N/A	Unit Ventilator Insulation		NAD	27	SF	0	SF				N/A	N/A	N/A	
1	3	Classroom 320	N/A	Partition Room Dividers		Non Suspect ACM	150	SF	0	SF		Made of wood		N/A	N/A	N/A	
1	3	Classroom 320	M	Sink Undercoat Mastic	1160/01/03/BATTA/AH/2602	Assumed	6	SF	0	SF				1	No	1/D	
1	3	Classroom 320	M	Transite Sills	1160/01/03/34	Confirmed	1	SF	0	SF		Fire Extinguisher Sill		1	No	1/D	
1	3	Classroom 321	N/A	Sheetrock Wall		Non Suspect ACM	1160	SF	0	SF				N/A	N/A	N/A	
1	3	Classroom 321	N/A	Concrete Block Wall		Non Suspect ACM	1160	SF	0	SF				N/A	N/A	N/A	
1	3	Classroom 321	M	Floor Tile VAT 12" x 12"	1160/01/03/FF	Assumed	805	SF	0	SF	Tan			1	No	1/D	
1	3	Classroom 321	S	Textured Ceiling Paint	1160/01/03/33	Confirmed	805	SF	0	SF				1	No	1/D	
1	3	Classroom 321	N/A	Unit Ventilator Insulation		NAD	27	SF	0	SF				N/A	N/A	N/A	
1	3	Classroom 321	M	Blackboard Glue Dots	1160/01/03/BATTA/AH/2600	Assumed	128	SF	0	SF				1	No	1/D	
1	3	Classroom 321	M	Sink Undercoat Mastic	1160/01/03/BATTA/AH/2602	Assumed	12	SF	0	SF				1	No	1/D	
1	3	Classroom 322	N/A	Sheetrock Wall		Non Suspect ACM	1080	SF	0	SF				N/A	N/A	N/A	
1	3	Classroom 322	N/A	Concrete Block Wall		Non Suspect ACM	1080	SF	0	SF				N/A	N/A	N/A	
1	3	Classroom 322	M	Floor Tile VAT 12" x 12"	1160/01/03/FF	Assumed	713	SF	0	SF	Tan			1	No	1/D	
1	3	Classroom 322	S	Textured Ceiling Paint	1160/01/03/33	Confirmed	713	SF	0	SF				1	No	1/D	
1	3	Classroom 322	N/A	Unit Ventilator Insulation		NAD	27	SF	0	SF				N/A	N/A	N/A	
1	3	Classroom 322	M	Blackboard Glue Dots	1160/01/03/BATTA/AH/2600	Assumed	160	SF	0	SF				1	No	1/D	
1	3	Classroom 323	M	Floor Tile VAT 12" x 12"	1160/01/03/FF	Assumed	805	SF	0	SF	Tan			1	No	1/D	
1	3	Classroom 323	N/A	Concrete Block Wall		Non Suspect ACM	1160	SF	0	SF				N/A	N/A	N/A	
1	3	Classroom 323	S	Textured Ceiling Paint	1160/01/03/33	Confirmed	805	SF	0	SF				1	No	1/D	
1	3	Classroom 323	M	Sink Undercoat Mastic	1160/01/03/BATTA/AH/2602	Assumed	6	SF	0	SF				1	No	1/D	
1	3	Classroom 323	N/A	Unit Ventilator Insulation		NAD	27	SF	0	SF				N/A	N/A	N/A	
1	3	Classrooms 320 - 323 Pod Entrance Closet	X	X	X	X	X	X	X	X		No access		X	X	X	
1	3	Stair 1 across from Guidance Office 323A	N/A	Cement Floor		Non Suspect ACM	288	SF	0	SF				N/A	N/A	N/A	
1	3	Stair 1 across from Guidance Office 323A	N/A	Concrete Block Wall		Non Suspect ACM	1224	SF	0	SF				N/A	N/A	N/A	
1	3	Stair 1 across from Guidance Office 323A	S	Textured Ceiling Paint	1160/01/03/33	Confirmed	288	SF	0	SF				1	No	1/D	
1	3	Guidance Office 323A	M	Floor Tile VAT 12" x 12"	1160/01/03/FF	Assumed	220	SF	0	SF	Grey			1	No	1/D	
1	3	Guidance Office 323A	N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	220	SF	0	SF				N/A	N/A	N/A	
1	3	Guidance Office 323A	N/A	Concrete Block Wall		Non Suspect ACM	496	SF	0	SF				N/A	N/A	N/A	
1	3	Guidance Office 323A Closet	M	Floor Tile VAT 12" x 12"	1160/01/03/FF	Assumed	33	SF	0	SF	Grey			1	No	1/D	
1	3	Guidance Office 323A Closet	N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	33	SF	0	SF				N/A	N/A	N/A	
1	3	Guidance Office 323A Closet	N/A	Concrete Block Wall		Non Suspect ACM	252	SF	0	SF				N/A	N/A	N/A	
1	3	Storage Room 323B	N/A	Concrete Block Wall		Non Suspect ACM	784	SF	0	SF				N/A	N/A	N/A	
1	3	Storage Room 323B	N/A	Concrete Ceiling		Non Suspect ACM	132	SF	0	SF				N/A	N/A	N/A	
1	3	Storage Room 323B	M	Floor Tile VAT 12" x 12"	1160/01/03/FF	Assumed	132	SF	0	SF	Grey			1	No	1/D	
1	3	Classroom 324	N/A	Concrete Block Wall		Non Suspect ACM	1580	SF	0	SF				N/A	N/A	N/A	
1	3	Classroom 324	M	Floor Tile VAT 12" x 12"	1160/01/03/FF	Assumed	1548	SF	0	SF	Blue			1	No	1/D	
1	3	Classroom 324	S	Textured Ceiling Paint	1160/01/03/33	Confirmed	1548	SF	0	SF				1	No	1/D	
1	3	Classroom 324	M	Blackboard Glue Dots	1160/01/03/BATTA/AH/2600	Assumed	96	SF	0	SF				1	No	1/D	
1	3	Classroom 324	N/A	Unit Ventilator Insulation		NAD	54	SF	0	SF				N/A	N/A	N/A	
1	3	Classroom 324 Preparation Room	N/A	Concrete Block Wall		Non Suspect ACM	616	SF	0	SF				N/A	N/A	N/A	
1	3	Classroom 324 Preparation Room	M	Floor Tile VAT 12" x 12"	1160/01/03/FF	Assumed	160	SF	0	SF	Blue			1	No	1/D	
1	3	Classroom 324 Preparation Room	S	Textured Ceiling Paint	1160/01/03/33	Confirmed	160	SF	0	SF			1 sf water stain	1	No	1/D	
1	3	Testing Office 301A	N/A	Ceiling Tile 2' x 4'		Non Suspect ACM	220	SF	0	SF				N/A	N/A	N/A	
1	3	Testing Office 301A	M	Floor Tile VAT 12" x 12"	1160/01/03/FF	Assumed	220	SF	0	SF	Brown			1	No	1/D	
1	3	Testing Office 301A	N/A	Concrete Block Wall		Non Suspect ACM	620	SF	0	SF				N/A	N/A	N/A	
1	3	Testing Office 301A Closet	N/A	Ceiling Tile 2' x 4'		Non Suspect ACM	15	SF	0	SF		No access F2016 inspection		N/A	N/A	N/A	
1	3	Testing Office 301A Closet	M	Floor Tile VAT 12" x 12"	1160/01/03/FF	Assumed	15	SF	0	SF	Brown	No access F2016 inspection		1	No	1/D	
1	3	Testing Office 301A Closet	N/A	Concrete Block Wall		Non Suspect ACM	128	SF	0	SF		No access F2016 inspection		N/A	N/A	N/A	
1	3	Storage Room 301B	N/A	Concrete Block Wall		Non Suspect ACM	672	SF	0	SF				N/A	N/A	N/A	
1	3	Storage Room 301B	M	Floor Tile VAT 12" x 12"	1160/01/03/FF	Assumed	108	SF	0	SF	Grey			1	No	1/D	
1	3	Storage Room 301B	N/A	Concrete Ceiling		Non Suspect ACM	108	SF	0	SF				N/A	N/A	N/A	
1	3	Hallway from 320-323 Pod to Classroom 301	M	Floor Tile VAT 12" x 12"	1160/01/03/FF	Assumed	1090	SF	0	SF	Grey			1	No	1/D	
1	3	Hallway from 320-323 Pod to Classroom 301	N/A	Concrete Block Wall		Non Suspect ACM	1904	SF	0	SF				N/A	N/A	N/A	
1	3	Hallway from 320-323 Pod to Classroom 301	N/A	Ceiling Tile 2' x 4'		Non Suspect ACM	540	SF	0	SF				N/A	N/A	N/A	
1	3	Hallway from 320-323 Pod to Classroom 301	N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	550	SF	0	SF				N/A	N/A	N/A	
1	3	Hallway from 320-323 Pod to Classroom 301	M	Transite Sills	1160/01/03/34	Confirmed	2	SF	0	SF		Fire Extinguisher Sill		1	No	1/D	
1	2	Multipurpose Room 200	M	Floor Tile VAT 12" x 12"	1160/01/02/EE	Assumed	1548	SF	0	SF	Multi			1	No	1/D	
1	2	Multipurpose Room 200	S	Textured Ceiling Paint	1160/01/02/21	Confirmed	1548	SF	0	SF				1	No	1/D	
1	2	Multipurpose Room 200	N/A	Concrete Block Wall		Non Suspect ACM	1580	SF	0	SF				N/A	N/A	N/A	
1	2	Multipurpose Room 200	M	Transite Sink	1160/01/02/22	Confirmed	27	SF	0	SF				1	No	1/D	
1	2	Multipurpose Room 200	M	Transite Lab Counters	1160/01/02/22	Confirmed	270	SF	0	SF				1	No	1/D	
1	2	Multipurpose Room 200	N/A	Unit Ventilator Insulation		NAD	54	SF	0	SF				N/A	N/A	N/A	
1	2	Multipurpose Room 200	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	60	LF	0	LF				N/A	N/A	N/A	
1	2	Multipurpose Room 200	N/A	Fiberglass Pipe Fitting Insulation		Non Suspect ACM	16	EA	0	EA				N/A	N/A	N/A	
1	2	Multipurpose Room 200 Closet	S	Textured Ceiling Paint	1160/01/02/21	Confirmed	160	SF	0	SF				1	No	1/D	
1	2	Multipurpose Room 200 Closet	N/A	Concrete Block Wall		Non Suspect ACM	616	SF	0	SF				N/A	N/A	N/A	
1	2	Multipurpose Room 200 Closet	M	Floor Tile VAT 12" x 12"	1160/01/02/EE	Assumed	160	SF	0	SF	Grey			1	No	1/D	
1	2	Classroom 201	M	Floor Tile VAT 12" x 12"	1160/01/02/EE	Assumed	770	SF	0	SF	Tan			1	No	1/D	
1	2	Classroom 201	S	Textured Ceiling Paint	1160/01/02/21	Confirmed	770	SF	0	SF				1	No	1/D	

1160 Motivation HS/KIPP West @ Turner - 2015-2016 AHERA Three-Year Report.xls

E I L I N E I D		School District of Philadelphia Motivation High School and KIPP Turner West Middle School 5900 Baltimore Avenue, Philadelphia, PA 19143 ULCS# 1160 Year Built: 1969		AHERA Three-Year Reinspection 2015-2016 Room by Room Location Log Report							Reinspection Date: 9/29/15		Attic/ Crawl Space Ranking	Damage Potential (DP)	Newly Friable (NF)	Response Action (RA)
				On Site Room Name		System Affected	Material Description	HID#	Confirmed/Assumed/NAD/ Non Suspect ACM	Amount of Material	SF EA	Amount of Damage				
1	2	Classroom 201	N/A	Concrete Block Wall		Non Suspect ACM	1368	SF	0	SF			N/A	N/A	N/A	
1	2	Classroom 201	M	Blackboard Glue Dots	1160/01/02/BATTA/AH/2600	Assumed	200	SF	0	SF			1	No	1/D	
1	2	Classroom 201	N/A	Unit Ventilator Insulation		NAD	27	SF	0	SF			N/A	N/A	N/A	
1	2	Classroom 201	M	Transite Sills	1160/01/02/BB	Confirmed	1	SF	0	SF		Fire Extinguisher Sill	1	No	1/D	
1	2	Copy Room across from Classroom 201	M	Floor Tile VAT 12" x 12"	1160/01/02/EE	Assumed	782	SF	0	SF	Brown		1	No	1/D	
1	2	Copy Room across from Classroom 201	N/A	Concrete Block Wall		Non Suspect ACM	1140	SF	0	SF			N/A	N/A	N/A	
1	2	Copy Room across from Classroom 201	N/A	Ceiling Tile 2' x 4'		Non Suspect ACM	782	SF	0	SF			N/A	N/A	N/A	
1	2	Copy Room Closet	M	Floor Tile VAT 12" x 12"	1160/01/02/EE	Assumed	15	SF	0	SF	Grey	No access F2016 inspection	1	No	1/D	
1	2	Copy Room Closet	N/A	Concrete Block Wall		Non Suspect ACM	128	SF	0	SF		No access F2016 inspection	N/A	N/A	N/A	
1	2	Copy Room Closet	N/A	Ceiling Tile 2' x 4'		Non Suspect ACM	15	SF	0	SF		No access F2016 inspection	N/A	N/A	N/A	
1	2	School Store across from Classroom 201	N/A	Concrete Ceiling		Non Suspect ACM	256	SF	0	SF			N/A	N/A	N/A	
1	2	School Store across from Classroom 201	N/A	Concrete Block Wall		Non Suspect ACM	640	SF	0	SF			N/A	N/A	N/A	
1	2	School Store across from Classroom 201	M	Floor Tile VAT 12" x 12"	1160/01/02/EE	Assumed	256	SF	0	SF	Grey		1	No	1/D	
1	2	6th Grade Pod (Classrooms 202-205) Entrance	S	Textured Ceiling Paint	1160/01/02/21	Confirmed	735	SF	0	SF			1	No	1/D	
1	2	6th Grade Pod (Classrooms 202-205) Entrance	N/A	Concrete Block Wall		Non Suspect ACM	1280	SF	0	SF			N/A	N/A	N/A	
1	2	6th Grade Pod (Classrooms 202-205) Entrance	M	Floor Tile VAT 12" x 12"	1160/01/02/EE	Assumed	735	SF	0	SF	Tan		1	No	1/D	
1	2	6th Grade Pod Entrance Closet	N/A	Concrete Block Wall		Non Suspect ACM	460	SF	0	SF			N/A	N/A	N/A	
1	2	6th Grade Pod Entrance Closet	N/A	Cement Floor		Non Suspect ACM	102	SF	0	SF			N/A	N/A	N/A	
1	2	6th Grade Pod Entrance Closet	S	Textured Ceiling Paint	1160/01/02/21	Confirmed	102	SF	0	SF			1	No	1/D	
1	2	Classroom 202	M	Floor Tile VAT 12" x 12"	1160/01/02/EE	Assumed	736	SF	0	SF	Tan		1	No	1/D	
1	2	Classroom 202	S	Textured Ceiling Paint	1160/01/02/21	Confirmed	736	SF	0	SF	Tan		1	No	1/D	
1	2	Classroom 202	N/A	Concrete Block Wall		Non Suspect ACM	840	SF	0	SF			N/A	N/A	N/A	
1	2	Classroom 202	N/A	Sheetrock Wall		Non Suspect ACM	300	SF	0	SF			N/A	N/A	N/A	
1	2	Classroom 202	M	Blackboard Glue Dots	1160/01/02/BATTA/AH/2600	Assumed	196	SF	0	SF			1	No	1/D	
1	2	Classroom 202	M	Sink Undercoat Mastic	1160/01/02/BATTA/AH/2602	Assumed	6	SF	0	SF			1	No	1/D	
1	2	Classroom 202	N/A	Unit Ventilator Insulation		NAD	27	SF	0	SF			N/A	N/A	N/A	
1	2	Classroom 202	M	Transite Sills	1160/01/02/BB	Confirmed	1	SF	0	SF		Fire Extinguisher Sill	1	No	1/D	
1	2	Classroom 203	M	Floor Tile VAT 12" x 12"	1160/01/02/EE	Assumed	805	SF	0	SF	Tan		1	No	1/D	
1	2	Classroom 203	S	Textured Ceiling Paint	1160/01/02/21	Confirmed	805	SF	0	SF			1	No	1/D	
1	2	Classroom 203	N/A	Concrete Block Wall		Non Suspect ACM	860	SF	0	SF			N/A	N/A	N/A	
1	2	Classroom 203	N/A	Sheetrock Wall		Non Suspect ACM	300	SF	0	SF			N/A	N/A	N/A	
1	2	Classroom 203	M	Blackboard Glue Dots	1160/01/02/BATTA/AH/2600	Assumed	160	SF	0	SF			1	No	1/D	
1	2	Classroom 203	M	Sink Undercoat Mastic	1160/01/02/BATTA/AH/2602	Assumed	12	SF	0	SF			1	No	1/D	
1	2	Classroom 203	N/A	Unit Ventilator Insulation		NAD	27	SF	0	SF			N/A	N/A	N/A	
1	2	Classroom 204	M	Floor Tile VAT 12" x 12"	1160/01/02/EE	Assumed	736	SF	0	SF	Tan		1	No	1/D	
1	2	Classroom 204	S	Textured Ceiling Paint	1160/01/02/21	Confirmed	736	SF	0	SF			1	No	1/D	
1	2	Classroom 204	N/A	Concrete Block Wall		Non Suspect ACM	1100	SF	0	SF			N/A	N/A	N/A	
1	2	Classroom 204	N/A	Sheetrock Wall		Non Suspect ACM	540	SF	0	SF			N/A	N/A	N/A	
1	2	Classroom 204	M	Blackboard Glue Dots	1160/01/02/BATTA/AH/2600	Assumed	54	SF	0	SF			1	No	1/D	
1	2	Classroom 205	M	Floor Tile VAT 12" x 12"	1160/01/02/EE	Assumed	736	SF	0	SF	Tan		1	No	1/D	
1	2	Classroom 205	S	Textured Ceiling Paint	1160/01/02/21	Confirmed	736	SF	0	SF			1	No	1/D	
1	2	Classroom 205	N/A	Concrete Block Wall		Non Suspect ACM	830	SF	0	SF			N/A	N/A	N/A	
1	2	Classroom 205	N/A	Sheetrock Wall		Non Suspect ACM	270	SF	0	SF			N/A	N/A	N/A	
1	2	Classroom 205	M	Sink Undercoat Mastic	1160/01/02/BATTA/AH/2602	Assumed	6	SF	0	SF			1	No	1/D	
1	2	Classroom 205	N/A	Unit Ventilator Insulation		NAD	27	SF	0	SF			N/A	N/A	N/A	
1	2	Classroom 205	M	Blackboard Glue Dots	1160/01/02/BATTA/AH/2600	Assumed	208	SF	0	SF			1	No	1/D	
1	2	Achievement Area across from 6th Grade Pod	M	Floor Tile VAT 12" x 12"	1160/01/02/EE	Assumed	90	SF	0	SF	Grey		1	No	1/D	
1	2	Achievement Area across from 6th Grade Pod	N/A	Concrete Block Wall		Non Suspect ACM	304	SF	0	SF			N/A	N/A	N/A	
1	2	Achievement Area across from 6th Grade Pod	N/A	Ceiling Tile 2' x 4'		Non Suspect ACM	90	SF	0	SF			N/A	N/A	N/A	
1	2	Social Work Office next to Nurse's Office	M	Floor Tile VAT 12" x 12"	1160/01/02/EE	Assumed	100	SF	0	SF	Grey		1	No	1/D	
1	2	Social Work Office next to Nurse's Office	N/A	Ceiling Tile 2' x 4'		Non Suspect ACM	100	SF	4	SF			N/A	N/A	N/A	
1	2	Social Work Office next to Nurse's Office	N/A	Concrete Block Wall		Non Suspect ACM	320	SF	0	SF			N/A	N/A	N/A	
1	2	Stair 2 next to KIPP Regional Office 206	S	Textured Ceiling Paint	1160/01/02/21	Confirmed	288	SF	0	SF			1	No	1/D	
1	2	Stair 2 next to KIPP Regional Office 206	N/A	Cement Floor		Non Suspect ACM	288	SF	0	SF			N/A	N/A	N/A	
1	2	Stair 2 next to KIPP Regional Office 206	N/A	Concrete Block Wall		Non Suspect ACM	1224	SF	0	SF			N/A	N/A	N/A	
1	2	KIPP Regional Office Reception	M	Floor Tile VAT 12" x 12"	1160/01/02/EE	Assumed	165	SF	0	SF	Grey		1	No	1/D	
1	2	KIPP Regional Office Reception	N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	165	SF	0	SF			N/A	N/A	N/A	
1	2	KIPP Regional Office Reception	N/A	Concrete Block Wall		Non Suspect ACM	520	SF	0	SF			N/A	N/A	N/A	
1	2	KIPP Regional Main Office 206C	M	Floor Tile VAT 12" x 12"	1160/01/02/EE	Assumed	902	SF	0	SF	Grey		1	No	1/D	
1	2	KIPP Regional Main Office 206C	S	Textured Ceiling Paint	1160/01/02/21	Confirmed	902	SF	0	SF			1	No	1/D	
1	2	KIPP Regional Main Office 206C	N/A	Concrete Block Wall		Non Suspect ACM	1260	SF	0	SF			N/A	N/A	N/A	
1	2	KIPP Regional Main Office 206C	N/A	Fiberglass Pipe Fitting Insulation		Non Suspect ACM	8	EA	0	EA			N/A	N/A	N/A	
1	2	KIPP Regional Main Office 206C	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	25	LF	0	LF			N/A	N/A	N/A	
1	2	KIPP Regional Main Office 206C	M	Sink Undercoat Mastic	1160/01/02/BATTA/AH/2602	Assumed	6	SF	0	SF			1	No	1/D	
1	2	KIPP Regional Main Office Closet	N/A	Plaster Ceiling		NAD	16	SF	0	SF			N/A	N/A	N/A	
1	2	KIPP Regional Main Office Closet	N/A	Concrete Block Wall		Non Suspect ACM	120	SF	0	SF			N/A	N/A	N/A	
1	2	KIPP Regional Main Office Closet	M	Floor Tile VAT 12" x 12"	1160/01/02/EE	Assumed	16	SF	0	SF		Please verify color	1	No	1/D	
1	2	KIPP Regional Office Conference Room 206A	M	Floor Tile VAT 12" x 12"	1160/01/02/EE	Assumed	165	SF	0	SF	Grey		1	No	1/D	
1	2	KIPP Regional Office Conference Room 206A	N/A	Ceiling Tile 2' x 4'		Non Suspect ACM	165	SF	0	SF			N/A	N/A	N/A	
1	2	KIPP Regional Office Conference Room 206A	N/A	Concrete Block Wall		Non Suspect ACM	520	SF	0	SF			N/A	N/A	N/A	
1	2	Conference Room 206A Closet	M	Floor Tile VAT 12" x 12"	1160/01/02/EE	Assumed	6	SF	0	SF	Grey		1	No	1/D	

1160 Motivation HS/KIPP West @ Turner - 2015-2016 AHERA Three-Year Report.xls

E l e m e n t		F l o o r		School District of Philadelphia Motivation High School and KIPP Turner West Middle School 5900 Baltimore Avenue, Philadelphia, PA 19143 ULCS# 1160 Year Built: 1969		AHERA Three-Year Reinspection 2015-2016 Room by Room Location Log Report						Reinspection Date: 9/29/15		Attic/ Crawl Space Ranking	Damage Potential (DP)	Newly Friable (NF)	Response Action (RA)
						On Site Room Name		System Affected	Material Description	HID#	Confirmed/Assumed/NAD/ Non Suspect ACM	Amount of Material	SF LF EA				
1	2	Conference Room 206A Closet	N/A	Ceiling Tile 2' x 4'		Non Suspect ACM	6	SF	0	SF				N/A	N/A	N/A	
1	2	Conference Room 206A Closet	N/A	Concrete Block Wall		Non Suspect ACM	80	SF	0	SF				N/A	N/A	N/A	
1	2	KIPP CEO's Office 206B	M	Floor Tile VAT 12" x 12"	1160/01/02/EE	Assumed	180	SF	0	SF	Grey			1	No	1/D	
1	2	KIPP CEO's Office 206B	N/A	Ceiling Tile 2' x 4'		Non Suspect ACM	180	SF	0	SF				N/A	N/A	N/A	
1	2	KIPP CEO's Office 206B	N/A	Concrete Block Wall		Non Suspect ACM	540	SF	0	SF				N/A	N/A	N/A	
1	2	CEO's Office 206B Closet	M	Floor Tile VAT 12" x 12"	1160/01/02/EE	Assumed	143	SF	0	SF	Grey			1	No	1/D	
1	2	CEO's Office 206B Closet	N/A	Ceiling Tile 2' x 4'		Non Suspect ACM	143	SF	0	SF				N/A	N/A	N/A	
1	2	CEO's Office 206B Closet	N/A	Concrete Block Wall		Non Suspect ACM	480	SF	0	SF				N/A	N/A	N/A	
1	2	KIPP Regional / CEO Conference Room	M	Floor Tile VAT 12" x 12"	1160/01/02/EE	Assumed	154	SF	0	SF	Grey			1	No	1/D	
1	2	KIPP Regional / CEO Conference Room	N/A	Ceiling Tile 2' x 4'		Non Suspect ACM	154	SF	0	SF				N/A	N/A	N/A	
1	2	KIPP Regional / CEO Conference Room	N/A	Concrete Block Wall		Non Suspect ACM	1224	SF	0	SF				N/A	N/A	N/A	
1	2	KIPP Regional / CEO Conference Room	M	Blackboard Glue Dots	1160/01/02/BATTA/AH/2600	Assumed	40	SF	0	SF				1	No	1/D	
1	2	Nurse's Office	N/A	Concrete Block Wall		Non Suspect ACM	460	SF	0	SF				N/A	N/A	N/A	
1	2	Nurse's Office	N/A	Cement Floor		Non Suspect ACM	112	SF	0	SF				N/A	N/A	N/A	
1	2	Nurse's Office	N/A	Concrete Ceiling		Non Suspect ACM	112	SF	0	SF				N/A	N/A	N/A	
1	2	Men's Restroom Entrance	M	Floor Tile VAT 12" x 12"	1160/01/02/EE	Assumed	96	SF	0	SF	Grey			1	No	1/D	
1	2	Men's Restroom Entrance	N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	96	SF	0	SF				N/A	N/A	N/A	
1	2	Men's Restroom Entrance	N/A	Concrete Block Wall		Non Suspect ACM	270	SF	0	SF				N/A	N/A	N/A	
1	2	Men's Restroom Entrance	N/A	Ceramic Tile Floors		Non Suspect ACM	45	SF	0	SF				N/A	N/A	N/A	
1	2	Men's Restroom Entrance	N/A	Concrete Block Wall		Non Suspect ACM	224	SF	0	SF				N/A	N/A	N/A	
1	2	Men's Restroom Entrance	N/A	Plaster Ceiling		NAD	45	SF	0	SF				N/A	N/A	N/A	
1	2	Boy's Restroom across from KIPP Regional Office	N/A	Ceramic Tile Floors		Non Suspect ACM	140	SF	0	SF				N/A	N/A	N/A	
1	2	Boy's Restroom across from KIPP Regional Office	N/A	Concrete Block Wall		Non Suspect ACM	432	SF	0	SF				N/A	N/A	N/A	
1	2	Boy's Restroom across from KIPP Regional Office	N/A	Plaster Ceiling		NAD	140	SF	0	SF				N/A	N/A	N/A	
1	2	Girl's Restroom across from KIPP Regional Office	N/A	Ceramic Tile Floors		Non Suspect ACM	140	SF	0	SF				N/A	N/A	N/A	
1	2	Girl's Restroom across from KIPP Regional Office	N/A	Concrete Block Wall		Non Suspect ACM	432	SF	0	SF				N/A	N/A	N/A	
1	2	Girl's Restroom across from KIPP Regional Office	N/A	Plaster Ceiling		NAD	140	SF	0	SF				N/A	N/A	N/A	
1	2	Custodial Closet across from KIPP Regional Office	N/A	Cement Floor		Non Suspect ACM	28	SF	0	SF				N/A	N/A	N/A	
1	2	Custodial Closet across from KIPP Regional Office	N/A	Concrete Block Wall		Non Suspect ACM	220	SF	0	SF				N/A	N/A	N/A	
1	2	Custodial Closet across from KIPP Regional Office	S	Textured Ceiling Paint	1160/01/02/21	Confirmed	28	SF	0	SF		also on duct		1	No	1/D	
1	2	KIPP Library 207	N/A	Concrete Block Wall		Non Suspect ACM	1140	SF	0	SF				N/A	N/A	N/A	
1	2	KIPP Library 207	M	Floor Tile VAT 12" x 12"	1160/01/02/EE	Assumed	782	SF	0	SF	Tan			1	No	1/D	
1	2	KIPP Library 207	S	Textured Ceiling Paint	1160/01/02/21	Confirmed	782	SF	0	SF				1	No	1/D	
1	2	KIPP Library 207	M	Blackboard Glue Dots	1160/01/02/BATTA/AH/2600	Assumed	128	SF	0	SF				1	No	1/D	
1	2	KIPP Library 207	N/A	Partition Room Dividers		Non Suspect ACM	170	SF	0	SF				N/A	N/A	N/A	
1	2	KIPP Library 207	M	Transite Sills	1160/01/02/BB	Confirmed	1	SF	0	SF		Fire Extinguisher Sill		1	No	1/D	
1	2	Hallway between 6th Grade Pod and Classroom 207	M	Floor Tile VAT 12" x 12"	1160/01/02/EE	Assumed	1210	SF	0	SF	Grey			1	No	1/D	
1	2	Hallway between 6th Grade Pod and Classroom 207	N/A	Ceiling Tile 2' x 4'		Non Suspect ACM	1210	SF	0	SF				N/A	N/A	N/A	
1	2	Hallway between 6th Grade Pod and Classroom 207	N/A	Concrete Block Wall		Non Suspect ACM	2178	SF	0	SF				N/A	N/A	N/A	
1	2	Hallway between 6th Grade Pod and Classroom 207	M	Transite Sills	1160/01/02/BB	Confirmed	2	SF	0	SF		Fire Extinguisher Sill		1	No	1/D	
1	2	5th Grade Pod (Classrooms 208-211) Entrance	M	Floor Tile VAT 12" x 12"	1160/01/02/EE	Assumed	735	SF	0	SF	Tan			1	No	1/D	
1	2	5th Grade Pod (Classrooms 208-211) Entrance	S	Textured Ceiling Paint	1160/01/02/21	Confirmed	735	SF	0	SF				1	No	1/D	
1	2	5th Grade Pod (Classrooms 208-211) Entrance	N/A	Concrete Block Wall		Non Suspect ACM	1280	SF	0	SF				N/A	N/A	N/A	
1	2	5th Grade Pod (Classrooms 208-211) Entrance	M	Transite Sills	1160/01/02/BB	Confirmed	1	SF	0	SF		Fire Extinguisher Sill		1	No	1/D	
1	2	Classroom 208	M	Floor Tile VAT 12" x 12"	1160/01/02/EE	Assumed	648	SF	0	SF	Tan			1	No	1/D	
1	2	Classroom 208	S	Textured Ceiling Paint	1160/01/02/21	Confirmed	648	SF	0	SF				1	No	1/D	
1	2	Classroom 208	N/A	Concrete Block Wall		Non Suspect ACM	1120	SF	0	SF				N/A	N/A	N/A	
1	2	Classroom 208	N/A	Unit Ventilator Insulation		NAD	27	SF	0	SF				N/A	N/A	N/A	
1	2	Classroom 208	N/A	Partition Room Dividers		Non Suspect ACM	180	SF	0	SF				N/A	N/A	N/A	
1	2	Classroom 208	M	Blackboard Glue Dots	1160/01/02/BATTA/AH/2600	Assumed	48	SF	0	SF				1	No	1/D	
1	2	Classroom 208	M	Sink Undercoat Mastic	1160/01/02/BATTA/AH/2602	Assumed	6	SF	0	SF				1	No	1/D	
1	2	Classroom 209	M	Floor Tile VAT 12" x 12"	1160/01/02/EE	Assumed	864	SF	0	SF	Tan			1	No	1/D	
1	2	Classroom 209	S	Textured Ceiling Paint	1160/01/02/21	Confirmed	864	SF	0	SF				1	No	1/D	
1	2	Classroom 209	N/A	Concrete Block Wall		Non Suspect ACM	900	SF	0	SF				N/A	N/A	N/A	
1	2	Classroom 209	N/A	Unit Ventilator Insulation		NAD	27	SF	0	SF				N/A	N/A	N/A	
1	2	Classroom 209	N/A	Sheetrock Wall		Non Suspect ACM	300	SF	0	SF				N/A	N/A	N/A	
1	2	Classroom 209	M	Blackboard Glue Dots	1160/01/02/BATTA/AH/2600	Assumed	120	SF	0	SF				1	No	1/D	
1	2	Classroom 209	M	Sink Undercoat Mastic	1160/02/02/BATTA/AH/2602	Assumed	12	SF	0	SF				1	No	1/D	
1	2	Classroom 210	M	Floor Tile VAT 12" x 12"	1160/01/02/EE	Assumed	648	SF	0	SF	Tan			1	No	1/D	
1	2	Classroom 210	S	Textured Ceiling Paint	1160/01/02/21	Confirmed	648	SF	0	SF				1	No	1/D	
1	2	Classroom 210	N/A	Concrete Block Wall		Non Suspect ACM	1020	SF	0	SF				N/A	N/A	N/A	
1	2	Classroom 210	N/A	Unit Ventilator Insulation		NAD	27	SF	0	SF				N/A	N/A	N/A	
1	2	Classroom 210	M	Blackboard Glue Dots	1160/01/02/BATTA/AH/2600	Assumed	60	SF	0	SF				1	No	1/D	
1	2	Classroom 210	N/A	Sheetrock Wall		Non Suspect ACM	250	SF	0	SF				N/A	N/A	N/A	
1	2	Classroom 211	M	Floor Tile VAT 12" x 12"	1160/01/02/EE	Assumed	720	SF	0	SF	Tan			1	No	1/D	
1	2	Classroom 211	S	Textured Ceiling Paint	1160/01/02/21	Confirmed	648	SF	0	SF				1	No	1/D	
1	2	Classroom 211	N/A	Concrete Block Wall		Non Suspect ACM	648	SF	0	SF				N/A	N/A	N/A	
1	2	Classroom 211	N/A	Unit Ventilator Insulation		NAD	27	SF	0	SF				N/A	N/A	N/A	
1	2	Classroom 211	M	Sink Undercoat Mastic	1160/01/02/BATTA/AH/2602	Assumed	6	SF	0	SF				1	No	1/D	
1	2	Classroom 211	N/A	Sheetrock Wall		Non Suspect ACM	300	SF	0	SF				N/A	N/A	N/A	
1	2	5th Grade Pod Entrance Closet	N/A	Concrete Block Wall		Non Suspect ACM	480	SF	0	SF				N/A	N/A	N/A	

1160 Motivation HS/KIPP West @ Turner - 2015-2016 AHERA Three-Year Report.xls

E I S I O N S		School District of Philadelphia Motivation High School and KIPP Turner West Middle School 5900 Baltimore Avenue, Philadelphia, PA 19143 ULCS# 1160 Year Built: 1969		AHERA Three-Year Reinspection 2015-2016 Room by Room Location Log Report							Reinspection Date: 9/29/15		Attic/ Crawl Space Ranking	Damage Potential (DP)	Newly Friable (NF)	Response Action (RA)				
				System Affected		Material Description		HID#		Confirmed/Assumed/NAD/ Non Suspect ACM		Amount of Material					SF LF EA		Amount of Damage	
1	2	On Site Room Name																		
1	2	5th Grade Pod Entrance Closet	N/A	Cement Floor			Non Suspect ACM	108	SF	0	SF									
1	2	5th Grade Pod Entrance Closet	N/A	Concrete Ceiling			Non Suspect ACM	108	SF	0	SF									
1	2	Stair 3 next to Classroom 212	N/A	Cement Floor			Non Suspect ACM	288	SF	0	SF									
1	2	Stair 3 next to Classroom 212	N/A	Concrete Block Wall			Non Suspect ACM	1224	SF	0	SF									
1	2	Stair 3 next to Classroom 212	S	Textured Ceiling Paint	1160/01/02/21		Confirmed	288	SF	0	SF									
1	2	Computer Room 212	M	Floor Tile VAT 12" x 12"	1160/01/02/EE		Assumed	1305	SF	0	SF	Blue	No access F2016 inspection	1	No	1/D				
1	2	Computer Room 212	S	Textured Ceiling Paint	1160/01/02/21		Confirmed	1305	SF	0	SF		No access F2016 inspection	1	No	1/D				
1	2	Computer Room 212	N/A	Concrete Block Wall			Non Suspect ACM	1776	SF	0	SF		No access F2016 inspection	N/A	N/A	N/A				
1	2	Computer Room 212	N/A	Unit Ventilator Insulation			NAD	54	SF	0	SF		No access F2016 inspection	N/A	N/A	N/A				
1	2	Computer Room 212	N/A	Fiberglass Pipe Fitting Insulation			Non Suspect ACM	8	EA	0	EA		No access F2016 inspection	N/A	N/A	N/A				
1	2	Computer Room 212	N/A	Fiberglass Pipe Insulation			Non Suspect ACM	50	LF	0	LF		No access F2016 inspection	N/A	N/A	N/A				
1	2	Classroom 213	M	Floor Tile VAT 12" x 12"	1160/01/02/EE		Assumed	805	SF	0	SF	Tan		1	No	1/D				
1	2	Classroom 213	S	Textured Ceiling Paint	1160/01/02/21		Confirmed	805	SF	0	SF			1	No	1/D				
1	2	Classroom 213	N/A	Concrete Block Wall			Non Suspect ACM	1160	SF	0	SF			N/A	N/A	N/A				
1	2	Classroom 213	N/A	Unit Ventilator Insulation			NAD	27	SF	0	SF			N/A	N/A	N/A				
1	2	Classroom 213	M	Blackboard Glue Dots	1160/01/02/BATTA/AH/2600		Assumed	175	SF	0	SF			1	No	1/D				
1	2	Classroom 213	M	Transite Sills	1160/01/02/BB		Confirmed	1	SF	0	SF		Fire Extinguisher Sill	1	No	1/D				
1	2	Hallway from 5th Grade Pod to Classroom 213	M	Floor Tile VAT 12" x 12"	1160/01/02/EE		Assumed	1210	SF	0	SF	Brown		1	No	1/D				
1	2	Hallway from 5th Grade Pod to Classroom 213	N/A	Ceiling Tile 2' x 4'			Non Suspect ACM	1210	SF	0	SF			N/A	N/A	N/A				
1	2	Hallway from 5th Grade Pod to Classroom 213	N/A	Concrete Block Wall			Non Suspect ACM	2178	SF	0	SF			N/A	N/A	N/A				
1	2	Hallway from 5th Grade Pod to Classroom 213	M	Transite Sills	1160/01/02/BB		Confirmed	2	SF	0	SF		Fire Extinguisher Sill	1	No	1/D				
1	2	8th Grade Pod (Classrooms 214-217) Entrance	M	Floor Tile VAT 12" x 12"	1160/01/02/EE		Assumed	816	SF	0	SF	Tan		1	No	1/D				
1	2	8th Grade Pod (Classrooms 214-217) Entrance	S	Textured Ceiling Paint	1160/01/02/21		Confirmed	816	SF	0	SF			1	No	1/D				
1	2	8th Grade Pod (Classrooms 214-217) Entrance	N/A	Concrete Block Wall			Non Suspect ACM	1340	SF	0	SF			N/A	N/A	N/A				
1	2	Classroom 214	M	Floor Tile VAT 12" x 12"	1160/01/02/EE		Assumed	864	SF	0	SF	Tan		1	No	1/D				
1	2	Classroom 214	S	Textured Ceiling Paint	1160/01/02/21		Confirmed	864	SF	0	SF			1	No	1/D				
1	2	Classroom 214	N/A	Concrete Block Wall			Non Suspect ACM	900	SF	0	SF			N/A	N/A	N/A				
1	2	Classroom 214	N/A	Unit Ventilator Insulation			NAD	27	SF	0	SF			N/A	N/A	N/A				
1	2	Classroom 214	M	Blackboard Glue Dots	1160/01/02/BATTA/AH/2600		Assumed	120	SF	0	SF			1	No	1/D				
1	2	Classroom 214	N/A	Sheetrock Wall			Non Suspect ACM	300	SF	0	SF			N/A	N/A	N/A				
1	2	Classroom 214	M	Sink Undercoat Mastic	1160/01/02/BATTA/AH/2602		Assumed	6	SF	0	SF			1	No	1/D				
1	2	Classroom 214	M	Transite Sills	1160/01/02/BB		Confirmed	1	SF	0	SF		Fire Extinguisher Sill	1	No	1/D				
1	2	Classroom 215	M	Floor Tile VAT 12" x 12"	1160/01/02/EE		Assumed	864	SF	0	SF	Tan		1	No	1/D				
1	2	Classroom 215	S	Textured Ceiling Paint	1160/01/02/21		Confirmed	864	SF	0	SF			1	No	1/D				
1	2	Classroom 215	N/A	Concrete Block Wall			Non Suspect ACM	900	SF	0	SF			N/A	N/A	N/A				
1	2	Classroom 215	N/A	Unit Ventilator Insulation			NAD	27	SF	0	SF			N/A	N/A	N/A				
1	2	Classroom 215	M	Blackboard Glue Dots	1160/01/02/BATTA/AH/2600		Assumed	140	SF	0	SF			1	No	1/D				
1	2	Classroom 215	N/A	Sheetrock Wall			Non Suspect ACM	300	SF	0	SF			N/A	N/A	N/A				
1	2	Classroom 216	M	Floor Tile VAT 12" x 12"	1160/01/02/EE		Assumed	768	SF	0	SF	Tan		1	No	1/D				
1	2	Classroom 216	S	Textured Ceiling Paint	1160/01/02/21		Confirmed	768	SF	0	SF			1	No	1/D				
1	2	Classroom 216	N/A	Concrete Block Wall			Non Suspect ACM	560	SF	0	SF			N/A	N/A	N/A				
1	2	Classroom 216	N/A	Unit Ventilator Insulation			NAD	27	SF	0	SF			N/A	N/A	N/A				
1	2	Classroom 216	M	Blackboard Glue Dots	1160/01/02/BATTA/AH/2600		Assumed	64	SF	0	SF			1	No	1/D				
1	2	Classroom 216	N/A	Sheetrock Wall			Non Suspect ACM	560	SF	0	SF			N/A	N/A	N/A				
1	2	Classroom 217	M	Floor Tile VAT 12" x 12"	1160/01/02/EE		Assumed	768	SF	0	SF	Tan		1	No	1/D				
1	2	Classroom 217	S	Textured Ceiling Paint	1160/01/02/21		Confirmed	768	SF	0	SF			1	No	1/D				
1	2	Classroom 217	N/A	Concrete Block Wall			Non Suspect ACM	1120	SF	0	SF			N/A	N/A	N/A				
1	2	Classroom 217	N/A	Unit Ventilator Insulation			NAD	27	SF	0	SF			N/A	N/A	N/A				
1	2	Classroom 217	M	Blackboard Glue Dots	1160/01/02/BATTA/AH/2600		Assumed	56	SF	0	SF			1	No	1/D				
1	2	8th Grade Pod Entrance Closet	N/A	Concrete Block Wall			Non Suspect ACM	340	SF	0	SF			N/A	N/A	N/A				
1	2	8th Grade Pod Entrance Closet	N/A	Cement Floor			Non Suspect ACM	66	SF	0	SF			N/A	N/A	N/A				
1	2	8th Grade Pod Entrance Closet	N/A	Concrete Ceiling			Non Suspect ACM	66	SF	0	SF			N/A	N/A	N/A				
1	2	Stair 4 next to KIPP Main Office	S	Textured Ceiling Paint	1160/01/02/21		Confirmed	288	SF	0	SF			1	No	1/D				
1	2	Stair 4 next to KIPP Main Office	N/A	Cement Floor			Non Suspect ACM	288	SF	0	SF			N/A	N/A	N/A				
1	2	Stair 4 next to KIPP Main Office	N/A	Concrete Block Wall			Non Suspect ACM	1224	SF	0	SF			N/A	N/A	N/A				
1	2	KIPP Main Office Reception	N/A	Ceiling Tile 2' x 4'			Non Suspect ACM	168	SF	0	SF			N/A	N/A	N/A				
1	2	KIPP Main Office Reception	N/A	Concrete Block Wall			Non Suspect ACM	416	SF	0	SF			N/A	N/A	N/A				
1	2	KIPP Main Office Reception	M	Floor Tile VAT 12" x 12"	1160/01/02/EE		Assumed	168	SF	0	SF	Grey		1	No	1/D				
1	2	KIPP Main Office	M	Floor Tile VAT 12" x 12"	1160/01/02/EE		Assumed	180	SF	0	SF	Grey		1	No	1/D				
1	2	KIPP Main Office	S	Textured Ceiling Paint	1160/01/02/21		Confirmed	180	SF	0	SF			1	No	1/D				
1	2	KIPP Main Office	N/A	Concrete Block Wall			Non Suspect ACM	540	SF	0	SF			N/A	N/A	N/A				
1	2	KIPP Main Office	M	Sink Undercoat Mastic	1160/01/02/BATTA/AH/2602		Assumed	6	SF	0	SF			1	No	1/D				
1	2	KIPP Main Office Closet	N/A	Plaster Ceiling			NAD	16	SF	0	SF			N/A	N/A	N/A				
1	2	KIPP Main Office Closet	N/A	Concrete Block Wall			Non Suspect ACM	160	SF	0	SF			N/A	N/A	N/A				
1	2	KIPP Main Office Closet	M	Floor Tile VAT 12" x 12"	1160/01/02/EE		Assumed	16	SF	0	SF	Grey		1	No	1/D				
1	2	KIPP Main Office Conference Room	M	Floor Tile VAT 12" x 12"	1160/01/02/EE		Assumed	154	SF	0	SF	Grey		1	No	1/D				
1	2	KIPP Main Office Conference Room	N/A	Ceiling Tile 2' x 4'			Non Suspect ACM	154	SF	0	SF			N/A	N/A	N/A				
1	2	KIPP Main Office Conference Room	N/A	Concrete Block Wall			Non Suspect ACM	500	SF	0	SF			N/A	N/A	N/A				
1	2	School Leader's Office 218B	M	Floor Tile VAT 12" x 12"	1160/01/02/EE		Assumed	180	SF	0	SF	Grey		1	No	1/D				
1	2	School Leader's Office 218B	N/A	Ceiling Tile 2' x 4'			Non Suspect ACM	180	SF	0	SF			N/A	N/A	N/A				
1	2	School Leader's Office 218B	N/A	Concrete Block Wall			Non Suspect ACM	540	SF	0	SF			N/A	N/A	N/A				

1160 Motivation HS/KIPP West @ Turner - 2015-2016 AHERA Three-Year Report.xls

E F I O N T		School District of Philadelphia Motivation High School and KIPP Turner West Middle School 5900 Baltimore Avenue, Philadelphia, PA 19143 ULCS# 1160 Year Built: 1969		AHERA Three-Year Reinspection 2015-2016 Room by Room Location Log Report							Reinspection Date: 9/29/15		Attic/ Crawl Space Ranking	Damage Potential (DP)	Newly Friable (NF)	Response Action (RA)
				On Site Room Name		System Affected	Material Description	HID#	Confirmed/Assumed/NAD/ Non Suspect ACM	Amount of Material	SF LF EA	Amount of Damage				
1	2	School Leader's Office Closet	M	Floor Tile VAT 12" x 12"	1160/01/02/EE	Assumed	8	SF	0	SF	Grey		1	No	1/D	
1	2	School Leader's Office Closet	N/A	Ceiling Tile 2' x 4'		Non Suspect ACM	8	SF	0	SF			N/A	N/A	N/A	
1	2	School Leader's Office Closet	N/A	Concrete Block Wall		Non Suspect ACM	96	SF	0	SF			N/A	N/A	N/A	
1	2	Director of Operations Office 218A	M	Floor Tile VAT 12" x 12"	1160/01/02/EE	Assumed	180	SF	0	SF	Brown	No access F2016 inspection	1	No	1/D	
1	2	Director of Operations Office 218A	N/A	Ceiling Tile 2' x 4'		Non Suspect ACM	180	SF	0	SF		No access F2016 inspection	N/A	N/A	N/A	
1	2	Director of Operations Office 218A	N/A	Concrete Block Wall		Non Suspect ACM	540	SF	0	SF		No access F2016 inspection	N/A	N/A	N/A	
1	2	Office 218A Closet	M	Floor Tile VAT 12" x 12"	1160/01/02/EE	Assumed	6	SF	0	SF	Brown	No access F2016 inspection	1	No	1/D	
1	2	Office 218A Closet	N/A	Ceiling Tile 2' x 4'		Non Suspect ACM	6	SF	0	SF		No access F2016 inspection	N/A	N/A	N/A	
1	2	Office 218A Closet	N/A	Concrete Block Wall		Non Suspect ACM	100	SF	0	SF		No access F2016 inspection	N/A	N/A	N/A	
1	2	Boy's Restroom across from KIPP Main Office	N/A	Ceramic Tile Floors		Non Suspect ACM	140	SF	0	SF			N/A	N/A	N/A	
1	2	Boy's Restroom across from KIPP Main Office	N/A	Concrete Block Wall		Non Suspect ACM	432	SF	0	SF			N/A	N/A	N/A	
1	2	Boy's Restroom across from KIPP Main Office	N/A	Plaster Ceiling		NAD	140	SF	0	SF			N/A	N/A	N/A	
1	2	Girl's Restroom across from KIPP Main Office	N/A	Ceramic Tile Floors		Non Suspect ACM	140	SF	0	SF			N/A	N/A	N/A	
1	2	Girl's Restroom across from KIPP Main Office	N/A	Concrete Block Wall		Non Suspect ACM	432	SF	0	SF			N/A	N/A	N/A	
1	2	Girl's Restroom across from KIPP Main Office	N/A	Plaster Ceiling		NAD	140	SF	0	SF			N/A	N/A	N/A	
1	2	Custodial Closet across from KIPP Main Office	S	Textured Ceiling Paint	1160/01/02/21	Confirmed	28	SF	0	SF			1	No	1/D	
1	2	Custodial Closet across from KIPP Main Office	N/A	Cement Floor		Non Suspect ACM	28	SF	0	SF			N/A	N/A	N/A	
1	2	Custodial Closet across from KIPP Main Office	N/A	Concrete Block Wall		Non Suspect ACM	220	SF	0	SF			N/A	N/A	N/A	
1	2	Women's Restroom Entrance	M	Floor Tile VAT 12" x 12"	1160/01/02/EE	Assumed	108	SF	0	SF	Grey		1	No	1/D	
1	2	Women's Restroom Entrance	N/A	Concrete Block Wall		Non Suspect ACM	420	SF	0	SF			N/A	N/A	N/A	
1	2	Women's Restroom Entrance	N/A	Ceiling Tile 2' x 4'		Non Suspect ACM	108	SF	0	SF			N/A	N/A	N/A	
1	2	Women's Restroom	N/A	Ceramic Tile Floors		Non Suspect ACM	96	SF	0	SF			N/A	N/A	N/A	
1	2	Women's Restroom	N/A	Concrete Block Wall		Non Suspect ACM	360	SF	0	SF			N/A	N/A	N/A	
1	2	Women's Restroom	N/A	Plaster Ceiling		NAD	96	SF	0	SF			N/A	N/A	N/A	
1	2	Classroom 219	M	Floor Tile VAT 12" x 12"	1160/01/02/EE	Assumed	770	SF	0	SF	Tan		1	No	1/D	
1	2	Classroom 219	S	Textured Ceiling Paint	1160/01/02/21	Confirmed	770	SF	0	SF			1	No	1/D	
1	2	Classroom 219	N/A	Concrete Block Wall		Non Suspect ACM	1140	SF	0	SF			N/A	N/A	N/A	
1	2	Classroom 219	N/A	Unit Ventilator Insulation		NAD	27	SF	0	SF			N/A	N/A	N/A	
1	2	Classroom 219	M	Blackboard Glue Dots	1160/01/02/BATTA/AH/2600	Assumed	128	SF	0	SF			1	No	1/D	
1	2	Classroom 219	N/A	Partition Room Dividers		Non Suspect ACM	200	SF	0	SF			N/A	N/A	N/A	
1	2	Classroom 219	M	Transite Sills	1160/01/02/BB	Confirmed	1	SF	0	SF		Fire Extinguisher Sill	1	No	1/D	
1	2	Copy Room across from Classroom 219	M	Floor Tile VAT 12" x 12"	1160/01/02/EE	Assumed	132	SF	0	SF	Grey		1	No	1/D	
1	2	Copy Room across from Classroom 219	N/A	Concrete Block Wall		Non Suspect ACM	414	SF	0	SF			N/A	N/A	N/A	
1	2	Copy Room across from Classroom 219	N/A	Ceiling Tile 2' x 4'		Non Suspect ACM	132	SF	0	SF			N/A	N/A	N/A	
1	2	Director of Student Life's Office across from Classroom 219	M	Floor Tile VAT 12" x 12"	1160/01/02/EE	Assumed	121	SF	0	SF	Grey		1	No	1/D	
1	2	Director of Student Life's Office across from Classroom 219	N/A	Concrete Block Wall		Non Suspect ACM	396	SF	0	SF			N/A	N/A	N/A	
1	2	Director of Student Life's Office across from Classroom 219	N/A	Ceiling Tile 2' x 4'		Non Suspect ACM	121	SF	0	SF			N/A	N/A	N/A	
1	2	Hallway from 8th Grade Pod to Classroom 219	M	Floor Tile VAT 12" x 12"	1160/01/02/EE	Assumed	1210	SF	0	SF	Brown		1	No	1/D	
1	2	Hallway from 8th Grade Pod to Classroom 219	N/A	Ceiling Tile 2' x 4'		Non Suspect ACM	1210	SF	0	SF			N/A	N/A	N/A	
1	2	Hallway from 8th Grade Pod to Classroom 219	N/A	Concrete Block Wall		Non Suspect ACM	2178	SF	0	SF			N/A	N/A	N/A	
1	2	Hallway from 8th Grade Pod to Classroom 219	M	Transite Sills	1160/01/02/BB	Confirmed	2	SF	0	SF		Fire Extinguisher Sill	1	No	1/D	
1	2	7th Grade Pod (Classrooms 220-223) Entrance	M	Floor Tile VAT 12" x 12"	1160/01/02/EE	Assumed	816	SF	0	SF	Tan		1	No	1/D	
1	2	7th Grade Pod (Classrooms 220-223) Entrance	S	Textured Ceiling Paint	1160/01/02/21	Confirmed	816	SF	0	SF			1	No	1/D	
1	2	7th Grade Pod (Classrooms 220-223) Entrance	N/A	Concrete Block Wall		Non Suspect ACM	1340	SF	0	SF			N/A	N/A	N/A	
1	2	Classroom 220	M	Floor Tile VAT 12" x 12"	1160/01/02/EE	Assumed	805	SF	0	SF	Tan		1	No	1/D	
1	2	Classroom 220	S	Textured Ceiling Paint	1160/01/02/21	Confirmed	805	SF	0	SF			1	No	1/D	
1	2	Classroom 220	N/A	Concrete Block Wall		Non Suspect ACM	1160	SF	0	SF			N/A	N/A	N/A	
1	2	Classroom 220	N/A	Unit Ventilator Insulation		NAD	27	SF	0	SF			N/A	N/A	N/A	
1	2	Classroom 220	M	Blackboard Glue Dots	1160/01/02/BATTA/AH/2600	Assumed	64	SF	0	SF			1	No	1/D	
1	2	Classroom 220	N/A	Partition Room Dividers		Non Suspect ACM	200	SF	0	SF			N/A	N/A	N/A	
1	2	Classroom 220	M	Sink Undercoat Mastic	1160/01/02/BATTA/AH/2602	Assumed	6	SF	0	SF			1	No	1/D	
1	2	Classroom 220	M	Transite Sills	1160/01/02/BB	Confirmed	1	SF	0	SF		Fire Extinguisher Sill	1	No	1/D	
1	2	Classroom 221	M	Floor Tile VAT 12" x 12"	1160/01/02/EE	Assumed	805	SF	0	SF	Blue		1	No	1/D	
1	2	Classroom 221	S	Textured Ceiling Paint	1160/01/02/21	Confirmed	805	SF	0	SF			1	No	1/D	
1	2	Classroom 221	N/A	Concrete Block Wall		Non Suspect ACM	860	SF	0	SF			N/A	N/A	N/A	
1	2	Classroom 221	N/A	Unit Ventilator Insulation		NAD	27	SF	0	SF			N/A	N/A	N/A	
1	2	Classroom 221	M	Blackboard Glue Dots	1160/01/02/BATTA/AH/2600	Assumed	72	SF	0	SF			1	No	1/D	
1	2	Classroom 221	N/A	Sheetrock Wall		Non Suspect ACM	300	SF	0	SF			N/A	N/A	N/A	
1	2	Classroom 221	M	Sink Undercoat Mastic	1160/01/02/BATTA/AH/2602	Assumed	12	SF	0	SF			1	No	1/D	
1	2	Classroom 222	M	Floor Tile VAT 12" x 12"	1160/01/02/EE	Assumed	713	SF	0	SF	Blue		1	No	1/D	
1	2	Classroom 222	S	Textured Ceiling Paint	1160/01/02/21	Confirmed	713	SF	0	SF			1	No	1/D	
1	2	Classroom 222	N/A	Concrete Block Wall		Non Suspect ACM	380	SF	0	SF			N/A	N/A	N/A	
1	2	Classroom 222	N/A	Sheetrock Wall		Non Suspect ACM	700	SF	0	SF			N/A	N/A	N/A	
1	2	Classroom 222	N/A	Unit Ventilator Insulation		NAD	27	SF	0	SF			N/A	N/A	N/A	
1	2	Classroom 223	M	Floor Tile VAT 12" x 12"	1160/01/02/EE	Assumed	713	SF	0	SF	Tan		1	No	1/D	
1	2	Classroom 223	S	Textured Ceiling Paint	1160/01/02/21	Confirmed	713	SF	0	SF			1	No	1/D	
1	2	Classroom 223	N/A	Concrete Block Wall		Non Suspect ACM	780	SF	0	SF			N/A	N/A	N/A	
1	2	Classroom 223	N/A	Unit Ventilator Insulation		NAD	27	SF	0	SF			N/A	N/A	N/A	

1160 Motivation HS/KIPP West @ Turner - 2015-2016 AHERA Three-Year Report.xls

		School District of Philadelphia Motivation High School and KIPP Turner West Middle School 5900 Baltimore Avenue, Philadelphia, PA 19143 ULCS# 1160 Year Built: 1969		AHERA Three-Year Reinspection 2015-2016 Room by Room Location Log Report							Reinspection Date: 9/29/15						
											Building Inspector: William Garrity, Jr.						
											Number: 70016699A						
											Management Planner: Mary Anne Lerro						
											Number: 740728						
E I L I N G	F L O O R	On Site Room Name		System Affected	Material Description	HID#	Confirmed/Assumed/NAD/ Non Suspect ACM	Amount of Material	SF EA	Amount of Damage	SF EA	Color required for VAT	Comments/Description/Notes	Attic/ Crawl Space Ranking	Damage Potential (DP)	Newly Friable (NF)	Response Action (RA)
		1	2	Classroom 223	N/A	Sheetrock Wall			Non Suspect ACM	300	SF	0	SF				N/A
1	2	Classroom 223	M	Sink Undercoat Mastic	1160/01/02/BATTA/AH/2602		Assumed	6	SF	0	SF				1	No	1/D
1	2	7th Grade Pod Entrance Closet	N/A	Concrete Block Wall			Non Suspect ACM	340	SF	0	SF		No access F2016 inspection		N/A	N/A	N/A
1	2	7th Grade Pod Entrance Closet	N/A	Cement Floor			Non Suspect ACM	66	SF	0	SF		No access F2016 inspection		N/A	N/A	N/A
1	2	7th Grade Pod Entrance Closet	S	Textured Ceiling Paint	1160/01/02/21		Confirmed	66	SF	0	SF		No access F2016 inspection		1	No	1/D
1	2	Conference Room across from Multipurpose Room 200	M	Floor Tile VAT 12" x 12"	1160/01/02/EE		Assumed	759	SF	0	SF	Grey			1	No	1/D
1	2	Conference Room across from Multipurpose Room 200	N/A	Concrete Block Wall			Non Suspect ACM	1568	SF	0	SF				N/A	N/A	N/A
1	2	Conference Room across from Multipurpose Room 200	N/A	Ceiling Tile 2' x 4'			Non Suspect ACM	759	SF	0	SF				N/A	N/A	N/A
1	2	Stair 1 next to Multipurpose Room 200	S	Textured Ceiling Paint	1160/01/02/21		Confirmed	288	SF	0	SF				1	No	1/D
1	2	Stair 1 next to Multipurpose Room 200	N/A	Cement Floor			Non Suspect ACM	288	SF	0	SF				N/A	N/A	N/A
1	2	Stair 1 next to Multipurpose Room 200	N/A	Concrete Block Wall			Non Suspect ACM	1224	SF	0	SF				N/A	N/A	N/A
1	2	Faculty Lounge across from Stair 1	M	Floor Tile VAT 12" x 12"	1160/01/02/EE		Assumed	240	SF	0	SF	Grey			1	No	1/D
1	2	Faculty Lounge across from Stair 1	N/A	Concrete Block Wall			Non Suspect ACM	576	SF	0	SF				N/A	N/A	N/A
1	2	Faculty Lounge across from Stair 1	N/A	Ceiling Tile 2' x 4'			Non Suspect ACM	240	SF	0	SF				N/A	N/A	N/A
1	2	Faculty Lounge Closet	M	Floor Tile VAT 12" x 12"	1160/01/02/EE		Assumed	36	SF	0	SF	Grey			1	No	1/D
1	2	Faculty Lounge Closet	N/A	Concrete Block Wall			Non Suspect ACM	240	SF	0	SF				N/A	N/A	N/A
1	2	Faculty Lounge Closet	N/A	Ceiling Tile 2' x 4'			Non Suspect ACM	36	SF	0	SF				N/A	N/A	N/A
1	2	Storage Room across from Stair 1	N/A	Concrete Block Wall			Non Suspect ACM	240	SF	0	SF		No access F2016 inspection		N/A	N/A	N/A
1	2	Storage Room across from Stair 1	N/A	Cement Floor			Non Suspect ACM	36	SF	0	SF		No access F2016 inspection		N/A	N/A	N/A
1	2	Storage Room across from Stair 1	N/A	Concrete Ceiling			Non Suspect ACM	36	SF	0	SF		No access F2016 inspection		N/A	N/A	N/A
1	2	Hallway between 7th Grade Pod and Classroom 201	M	Floor Tile VAT 12" x 12"	1160/01/02/EE		Assumed	1210	SF	0	SF	Grey			1	No	1/D
1	2	Hallway between 7th Grade Pod and Classroom 201	N/A	Ceiling Tile 2' x 4'			Non Suspect ACM	1210	SF	0	SF				N/A	N/A	N/A
1	2	Hallway between 7th Grade Pod and Classroom 201	N/A	Concrete Block Wall			Non Suspect ACM	2178	SF	0	SF				N/A	N/A	N/A
1	2	Hallway between 7th Grade Pod and Classroom 201	M	Transite Sills	1160/01/02/BB		Confirmed	2	SF	0	SF		Fire Extinguisher Sill		1	No	1/D
3	1	Theater Stage Crafts Storage Room next to 59th St Exit	N/A	Concrete Block Wall			Non Suspect ACM	792	SF	0	SF				N/A	N/A	N/A
3	1	Theater Stage Crafts Storage Room next to 59th St Exit	N/A	Concrete Ceiling			Non Suspect ACM	252	SF	0	SF				N/A	N/A	N/A
3	1	Theater Stage Crafts Storage Room next to 59th St Exit	N/A	Cement Floor			Non Suspect ACM	252	SF	0	SF				N/A	N/A	N/A
3	1	Theater Stage Crafts Storage Room next to 59th St Exit	N/A	Fiberglass Pipe Fitting Insulation			Non Suspect ACM	8	EA	0	EA				N/A	N/A	N/A
3	1	Theater Stage Crafts Storage Room next to 59th St Exit	N/A	Fiberglass Pipe Insulation			Non Suspect ACM	45	LF	0	LF				N/A	N/A	N/A
3	1	Art Room	M	Floor Tile VAT 12" x 12"	1160/01/01/DD		Assumed	4550	SF	0	SF	Grey			1	No	1/D
3	1	Art Room	S	Textured Ceiling Paint	1160/01/01/03		Confirmed	4550	SF	0	SF				1	No	1/D
3	1	Art Room	N/A	Concrete Block Wall			Non Suspect ACM	5280	SF	0	SF				N/A	N/A	N/A
3	1	Art Room	M	Sink Undercoat Mastic	1160/01/01/JJ		Assumed	144	SF	0	SF				1	No	1/D
3	1	Art Room	N/A	Fiberglass Pipe Insulation			Non Suspect ACM	130	LF	0	LF				N/A	N/A	N/A
3	1	Art Room	N/A	Fiberglass Pipe Fitting Insulation			Non Suspect ACM	8	EA	0	EA				N/A	N/A	N/A
3	1	Art Room	M	Blackboard Glue Dots	1160/03/01/BATTA/AH/2600		Assumed	168	SF	0	SF				1	No	1/D
3	1	Art Room	N/A	Ceiling Tile 2' x 4'			Non Suspect ACM	200	SF	16	SF				N/A	N/A	N/A
3	1	Art Room	M	Kiln	1160/01/01/BATTA/AH/1650		Assumed	10	SF	0	SF				1	No	1/D
3	1	Art Room Closet C-115a	N/A	Concrete Block Wall			Non Suspect ACM	792	SF	0	SF				N/A	N/A	N/A
3	1	Art Room Closet C-115a	N/A	Concrete Ceiling			Non Suspect ACM	252	SF	0	SF				N/A	N/A	N/A
3	1	Art Room Closet C-115a	N/A	Cement Floor			Non Suspect ACM	252	SF	0	SF				N/A	N/A	N/A
3	1	Art Room Closet C-115a	N/A	Fiberglass Pipe Fitting Insulation			Non Suspect ACM	15	EA	0	EA				N/A	N/A	N/A
3	1	Art Room Closet C-115a	N/A	Fiberglass Pipe Insulation			Non Suspect ACM	1	LF	0	LF				N/A	N/A	N/A
3	1	Art Room Closet C-115	N/A	Concrete Block Wall			Non Suspect ACM	2808	SF	0	SF				N/A	N/A	N/A
3	1	Art Room Closet C-115	N/A	Concrete Ceiling			Non Suspect ACM	2492	SF	0	SF				N/A	N/A	N/A
3	1	Art Room Closet C-115	N/A	Cement Floor			Non Suspect ACM	2492	SF	0	SF				N/A	N/A	N/A
3	1	Art Room Closet C-115	N/A	Fiberglass Pipe Fitting Insulation			Non Suspect ACM	1	EA	0	EA				N/A	N/A	N/A
3	1	Art Room Closet C-115	N/A	Fiberglass Pipe Insulation			Non Suspect ACM	25	LF	0	LF				N/A	N/A	N/A
3	1	Art Room Office across from C-115	M	Floor Tile VAT 12" x 12"	1160/01/01/DD		Assumed	168	SF	0	SF	Tan			1	No	1/D
3	1	Art Room Office across from C-115	N/A	Ceiling Tile 2' x 4'			Non Suspect ACM	168	SF	8	SF				N/A	N/A	N/A
3	1	Art Room Office across from C-115	N/A	Concrete Block Wall			Non Suspect ACM	520	SF	0	SF				N/A	N/A	N/A
3	1	Art Room Offices Locker Room	N/A	Concrete Block Wall			Non Suspect ACM	380	SF	0	SF				N/A	N/A	N/A
3	1	Art Room Offices Locker Room	N/A	Plaster Ceiling			NAD	88	SF	0	SF				N/A	N/A	N/A
3	1	Art Room Offices Locker Room	N/A	Cement Floor			Non Suspect ACM	88	SF	0	SF				N/A	N/A	N/A
3	1	Art Room Office across from C-114	M	Floor Tile VAT 12" x 12"	1160/01/01/DD		Assumed	272	SF	0	SF	Tan			1	No	1/D
3	1	Art Room Office across from C-114	N/A	Ceiling Tile 2' x 4'			Non Suspect ACM	272	SF	0	SF				N/A	N/A	N/A
3	1	Art Room Office across from C-114	N/A	Concrete Block Wall			Non Suspect ACM	528	SF	0	SF				N/A	N/A	N/A
3	1	Art Room Closet C-114	N/A	Concrete Block Wall			Non Suspect ACM	384	SF	0	SF		No access F2016 inspection		N/A	N/A	N/A
3	1	Art Room Closet C-114	N/A	Concrete Ceiling			Non Suspect ACM	128	SF	0	SF		No access F2016 inspection		N/A	N/A	N/A
3	1	Art Room Closet C-114	N/A	Cement Floor			Non Suspect ACM	128	SF	0	SF		No access F2016 inspection		N/A	N/A	N/A
3	1	Art Room Closet C-113	N/A	Concrete Block Wall			Non Suspect ACM	360	SF	0	SF				N/A	N/A	N/A
3	1	Art Room Closet C-113	N/A	Concrete Ceiling			Non Suspect ACM	96	SF	0	SF				N/A	N/A	N/A
3	1	Art Room Closet C-113	N/A	Cement Floor			Non Suspect ACM	96	SF	0	SF				N/A	N/A	N/A

1160 Motivation HS/KIPP West @ Turner - 2015-2016 AHERA Three-Year Report.xls

		School District of Philadelphia Motivation High School and KIPP Turner West Middle School 5900 Baltimore Avenue, Philadelphia, PA 19143 ULCS# 1160 Year Built: 1969		AHERA Three-Year Reinspection 2015-2016 Room by Room Location Log Report							Reinspection Date: 9/29/15						
											Building Inspector: William Garrity, Jr.						
											Number: 70016699A						
											Management Planner: Mary Anne Lerro						
											Number: 740728						
E I L e m e n t	F l o o r	On Site Room Name		System Affected	Material Description	HID#	Confirmed/Assumed/NAD/ Non Suspect ACM	Amount of Material	SF LF EA	Amount of Damage	SF LF EA	Color required for VAT	Comments/Description/Notes	Attic/ Crawl Space Ranking	Damage Potential (DP)	Newly Friable (NF)	Response Action (RA)
		3	1	Hallway from Theater Storage Room to former Band Room		N/A	Concrete Block Wall		Non Suspect ACM	6360	SF	0	SF				N/A
3	1	Hallway from Theater Storage Room to former Band Room		M	Ceiling Tile 1' x 1'	1160/01/01/HH	Assumed	200	SF	0	SF				1	No	1/D
3	1	Hallway from Theater Storage Room to former Band Room		M	Floor Tile VAT 12" x 12"	1160/01/01/DD	Assumed	3965	SF	0	SF	Grey			1	No	1/D
3	1	Hallway from Theater Storage Room to former Band Room		N/A	Ceiling Tile 2' x 4'		Non Suspect ACM	3180	SF	0	SF				N/A	N/A	N/A
3	1	Hallway from Theater Storage Room to former Band Room		N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	3180	SF	0	SF				N/A	N/A	N/A
3	1	Hallway from Theater Storage Room to former Band Room		M	Transite Sills	1160/03/01/BATTA/WG/2300	Confirmed	12	SF	0	SF		Fire Extinguisher Sill		1	No	1/D
3	1	Auditorium		S	Textured Ceiling Paint	1160/01/01/03	Confirmed	3392	SF	0	SF				1	No	1/D
3	1	Auditorium		N/A	Carpet		Non Suspect ACM	800	SF	0	SF				N/A	N/A	N/A
3	1	Auditorium		N/A	Cement Floor		Non Suspect ACM	2992	SF	0	SF				N/A	N/A	N/A
3	1	Auditorium		N/A	Concrete Block Wall		Non Suspect ACM	5148	SF	0	SF				N/A	N/A	N/A
3	1	Auditorium		N/A	Partition Room Dividers		Non Suspect ACM	2090	SF	0	SF				N/A	N/A	N/A
3	1	Auditorium Stage		N/A	Fiberglass Pipe Insulation		Non Suspect ACM	100	LF	0	LF				N/A	N/A	N/A
3	1	Auditorium Stage		N/A	Fiberglass Pipe Insulation		Non Suspect ACM	155	LF	0	LF				N/A	N/A	N/A
3	1	Auditorium Stage		N/A	Fiberglass Pipe Fitting Insulation		Non Suspect ACM	13	EA	0	EA				N/A	N/A	N/A
3	1	Auditorium Stage		N/A	Wood Floor		Non Suspect ACM	1800	SF	0	SF				N/A	N/A	N/A
3	1	Auditorium Stage		N/A	Concrete Ceiling		Non Suspect ACM	1800	SF	0	SF				N/A	N/A	N/A
3	1	Auditorium Stage		M	Stage Curtains	1160/01/01/BATTA/AH/2606	Assumed	2300	SF	0	SF				1	No	1/D
3	1	Storage next to Band Room		N/A	Ceiling Tile 2' x 4'		Non Suspect ACM	192	SF	0	SF		No access F2016 inspection		N/A	N/A	N/A
3	1	Storage next to Band Room		N/A	Concrete Block Wall		Non Suspect ACM	512	SF	0	SF		No access F2016 inspection		N/A	N/A	N/A
3	1	Storage next to Band Room		M	Floor Tile VAT 12" x 12"	1160/01/01/DD	Assumed	192	SF	0	SF	Tan	No access F2016 inspection		1	No	1/D
3	1	Storage next to Band Room		M	Kiln	1160/01/01/BATTA/AH/1650	Assumed	16	SF	0	SF		No access F2016 inspection		1	No	1/D
3	1	Band Room		M	Ceiling Tile 1' x 1'	1160/01/01/HH	Assumed	1428	SF	0	SF				1	No	1/D
3	1	Band Room		N/A	Concrete Block Wall		Non Suspect ACM	2432	SF	0	SF				N/A	N/A	N/A
3	1	Band Room		M	Floor Tile VAT 12" x 12"	1160/01/01/DD	Assumed	1428	SF	0	SF	Brown			1	No	1/D
3	1	Band Room Closet C-117		N/A	Concrete Block Wall		Non Suspect ACM	253	SF	0	SF				N/A	N/A	N/A
3	1	Band Room Closet C-117		N/A	Concrete Ceiling		Non Suspect ACM	50	SF	0	SF				N/A	N/A	N/A
3	1	Band Room Closet C-117		N/A	Cement Floor		Non Suspect ACM	50	SF	0	SF				N/A	N/A	N/A
3	1	Band Room Exit Stair next to Closet C-117		N/A	Ceiling Tile 2' x 4'		Non Suspect ACM	45	SF	0	SF				N/A	N/A	N/A
3	1	Band Room Exit Stair next to Closet C-117		M	Concrete Block Wall		Non Suspect ACM	280	SF	0	SF				N/A	N/A	N/A
3	1	Band Room Exit Stair next to Closet C-117		N/A	Floor Tile VAT 12" x 12"	1160/01/01/DD	Assumed	45	SF	0	SF	Tan			1	No	1/D
3	1	Music Practice Room D		N/A	Fiberglass Pipe Insulation		Non Suspect ACM	11	LF	0	LF				N/A	N/A	N/A
3	1	Music Practice Room D		N/A	Ceiling Tile 2' x 4'		Non Suspect ACM	144	SF	0	SF				N/A	N/A	N/A
3	1	Music Practice Room D		N/A	Concrete Block Wall		Non Suspect ACM	624	SF	0	SF				N/A	N/A	N/A
3	1	Music Practice Room D		M	Floor Tile VAT 12" x 12"	1160/01/01/DD	Assumed	144	SF	0	SF	Tan			1	No	1/D
3	1	Music Practice Room E		N/A	Ceiling Tile 2' x 4'		Non Suspect ACM	70	SF	0	SF				N/A	N/A	N/A
3	1	Music Practice Room E		N/A	Concrete Block Wall		Non Suspect ACM	272	SF	0	SF				N/A	N/A	N/A
3	1	Music Practice Room E		M	Floor Tile VAT 12" x 12"	1160/01/01/DD	Assumed	70	SF	0	SF	Tan			1	No	1/D
3	1	Music Practice Room C		N/A	Fiberglass Pipe Insulation		Non Suspect ACM	2	LF	0	LF				N/A	N/A	N/A
3	1	Music Practice Room C		N/A	Fiberglass Pipe Fitting Insulation		Non Suspect ACM	4	EA	0	EA				N/A	N/A	N/A
3	1	Music Practice Room C		N/A	Ceiling Tile 2' x 4'		Non Suspect ACM	96	SF	0	SF				N/A	N/A	N/A
3	1	Music Practice Room C		N/A	Concrete Block Wall		Non Suspect ACM	320	SF	0	SF				N/A	N/A	N/A
3	1	Music Practice Room C		M	Floor Tile VAT 12" x 12"	1160/01/01/DD	Assumed	96	SF	0	SF	Tan			1	No	1/D
3	1	Music Practice Room B		N/A	Fiberglass Pipe Insulation		Non Suspect ACM	2	LF	0	LF				N/A	N/A	N/A
3	1	Music Practice Room B		N/A	Fiberglass Pipe Fitting Insulation		Non Suspect ACM	4	EA	0	EA				N/A	N/A	N/A
3	1	Music Practice Room B		N/A	Ceiling Tile 2' x 4'		Non Suspect ACM	14	SF	16	SF				N/A	N/A	N/A
3	1	Music Practice Room B		N/A	Concrete Block Wall		Non Suspect ACM	144	SF	0	SF				N/A	N/A	N/A
3	1	Music Practice Room B		M	Floor Tile VAT 12" x 12"	1160/01/01/DD	Assumed	14	SF	0	SF	Tan			1	No	1/D
3	1	Music Practice Room A		N/A	Fiberglass Pipe Insulation		Non Suspect ACM	2	LF	0	LF				N/A	N/A	N/A
3	1	Music Practice Room A		N/A	Fiberglass Pipe Fitting Insulation		Non Suspect ACM	4	EA	0	EA				N/A	N/A	N/A
3	1	Music Practice Room A		N/A	Ceiling Tile 2' x 4'		Non Suspect ACM	35	SF	0	SF				N/A	N/A	N/A
3	1	Music Practice Room A		N/A	Concrete Block Wall		Non Suspect ACM	216	SF	0	SF				N/A	N/A	N/A
3	1	Music Practice Room A		M	Floor Tile VAT 12" x 12"	1160/01/01/DD	Assumed	35	SF	0	SF	Tan			1	No	1/D
3	1	Music Office		N/A	Ceiling Tile 2' x 4'		Non Suspect ACM	132	SF	0	SF				N/A	N/A	N/A
3	1	Music Office		N/A	Concrete Block Wall		Non Suspect ACM	552	SF	0	SF				N/A	N/A	N/A
3	1	Music Office		M	Floor Tile VAT 12" x 12"	1160/01/01/DD	Assumed	132	SF	0	SF	Grey			1	No	1/D
3	1	Music Practice Room Hallway		N/A	Ceiling Tile 2' x 4'		Non Suspect ACM	152	SF	0	SF				N/A	N/A	N/A
3	1	Music Practice Room Hallway		N/A	Concrete Block Wall		Non Suspect ACM	672	SF	0	SF				N/A	N/A	N/A
3	1	Music Practice Room Hallway		M	Floor Tile VAT 12" x 12"	1160/01/01/DD	Assumed	152	SF	0	SF	Tan			1	No	1/D
3	1	Former Band Room (not in use)		M	Ceiling Tile 1' x 1'	1160/01/01/HH	Assumed	1911	SF	0	SF				1	No	1/D
3	1	Former Band Room (not in use)		N/A	Concrete Block Wall		Non Suspect ACM	2816	SF	0	SF				N/A	N/A	N/A
3	1	Former Band Room (not in use)		M	Floor Tile VAT 12" x 12"	1160/01/01/DD	Assumed	1911	SF	0	SF	Tan			1	No	1/D
3	1	Former Band Room (not in use)		M	Sink Undercoat Mastic	1160/01/01/JJ	Assumed	16	SF	0	SF				1	No	1/D
3	1	Former Band Room (not in use)		M	Blackboard Glue Dots	1160/03/01/BATTA/AH/2600	Assumed	80	SF	0	SF				1	No	1/D
3	1	Former Band Room Instrument Storage		X	X		X	X	X	X	X		No access		X	X	X
3	1	Former Band Room Closet C-116		X	X		X	X	X	X	X		No access		X	X	X
3	1	Former Band Room Closet C-116a		X	X		X	X	X	X	X		No access		X	X	X

1160 Motivation HS/KIPP West @ Turner - 2015-2016 AHERA Three-Year Report.xls

		School District of Philadelphia Motivation High School and KIPP Turner West Middle School 5900 Baltimore Avenue, Philadelphia, PA 19143 ULCS# 1160 Year Built: 1969		AHERA Three-Year Reinspection 2015-2016 Room by Room Location Log Report							Reinspection Date: 9/29/15						
											Building Inspector: William Garrity, Jr.						
											Number: 70016699A						
											Management Planner: Mary Anne Lerro						
											Number: 740728						
E l e m e n t	F l o o r	On Site Room Name		System Affected	Material Description	HID#	Confirmed/Assumed/NAD/ Non Suspect ACM	Amount of Material	SF LF EA	Amount of Damage	SF LF EA	Color required for VAT	Comments/Description/Notes	Attic/ Crawl Space Ranking	Damage Potential (DP)	Newly Friable (NF)	Response Action (RA)
		3	1	Auditorium Lobby	N/A	Terrazzo Floors		Non Suspect ACM	484	SF	0	SF					N/A
3	1	Auditorium Lobby	N/A	Concrete Block Wall		Non Suspect ACM	792	SF	0	SF					N/A	N/A	N/A
3	1	Auditorium Lobby	N/A	Ceiling Tile 2' x 4'		Non Suspect ACM	484	SF	0	SF					N/A	N/A	N/A
3	1	Auditorium Lobby Boy's Rest Room	N/A	Ceramic Tile Floors		Non Suspect ACM	264	SF	0	SF					N/A	N/A	N/A
3	1	Auditorium Lobby Boy's Rest Room	N/A	Concrete Block Wall		Non Suspect ACM	840	SF	0	SF					N/A	N/A	N/A
3	1	Auditorium Lobby Boy's Rest Room	N/A	Plaster Ceiling		NAD	264	SF	0	SF					N/A	N/A	N/A
3	1	Auditorium Lobby Men's Restroom	N/A	Ceramic Tile Floors		Non Suspect ACM	170	SF	0	SF					N/A	N/A	N/A
3	1	Auditorium Lobby Men's Restroom	N/A	Concrete Block Wall		Non Suspect ACM	432	SF	0	SF					N/A	N/A	N/A
3	1	Auditorium Lobby Men's Restroom	N/A	Plaster Ceiling		NAD	170	SF	0	SF					N/A	N/A	N/A
3	1	Mechanical Room off Men's Restroom	X	X		X	X	X	X	X					X	X	X
3	1	Auditorium Lobby Women's Restroom	N/A	Ceramic Tile Floors		Non Suspect ACM	2492	SF	0	SF					N/A	N/A	N/A
3	1	Auditorium Lobby Women's Restroom	N/A	Concrete Block Wall		Non Suspect ACM	2808	SF	0	SF					N/A	N/A	N/A
3	1	Auditorium Lobby Women's Restroom	N/A	Plaster Ceiling		NAD	2492	SF	0	SF					N/A	N/A	N/A
3	1	Auditorium Lobby Girl's Restroom	N/A	Ceramic Tile Floors		Non Suspect ACM	2492	SF	0	SF					N/A	N/A	N/A
3	1	Auditorium Lobby Girl's Restroom	N/A	Concrete Block Wall		Non Suspect ACM	2808	SF	0	SF					N/A	N/A	N/A
3	1	Auditorium Lobby Girl's Restroom	N/A	Plaster Ceiling		NAD	2492	SF	0	SF					N/A	N/A	N/A
1	1	Main Entrance Lobby	N/A	Terrazzo Floors		Non Suspect ACM	2628	SF	0	SF					N/A	N/A	N/A
1	1	Main Entrance Lobby	N/A	Concrete Block Wall		Non Suspect ACM	2398	SF	0	SF					N/A	N/A	N/A
1	1	Main Entrance Lobby	M	Ceiling Tile 1' x 1'		Assumed	2628	SF	0	SF					1	No	1/D
1	1	Motivation HS Main Office	M	Floor Tile VAT 12" x 12"	1160/01/01/DD	Assumed	651	SF	0	SF		Grey			1	No	1/D
1	1	Motivation HS Main Office	N/A	Concrete Block Wall		Non Suspect ACM	1200	SF	0	SF					N/A	N/A	N/A
1	1	Motivation HS Main Office	N/A	Ceiling Tile 2' x 4'		Non Suspect ACM	851	SF	0	SF					N/A	N/A	N/A
1	1	Motivation HS Main Office	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	10	LF	0	LF					N/A	N/A	N/A
1	1	Main Office Copy Room	M	Floor Tile VAT 12" x 12"	1160/01/01/DD	Assumed	162	SF	0	SF		Grey			1	No	1/D
1	1	Main Office Copy Room	N/A	Concrete Block Wall		Non Suspect ACM	540	SF	0	SF					N/A	N/A	N/A
1	1	Main Office Copy Room	N/A	Ceiling Tile 2' x 4'		Non Suspect ACM	162	SF	0	SF					N/A	N/A	N/A
1	1	Main Office Copy Room	M	Sink Undercoat Mastic	1160/01/01/JJ	Assumed	6	SF	0	SF					1	No	1/D
1	1	Nurse's Office	M	Floor Tile VAT 12" x 12"	1160/01/01/DD	Assumed	272	SF	0	SF		Grey			1	No	1/D
1	1	Nurse's Office	N/A	Concrete Block Wall		Non Suspect ACM	528	SF	0	SF					N/A	N/A	N/A
1	1	Nurse's Office	N/A	Ceiling Tile 2' x 4'		Non Suspect ACM	272	SF	0	SF					N/A	N/A	N/A
1	1	Nurse's Office Infirmary	M	Floor Tile VAT 12" x 12"	1160/01/01/DD	Assumed	84	SF	0	SF		Brown			1	No	1/D
1	1	Nurse's Office Infirmary	N/A	Concrete Block Wall		Non Suspect ACM	304	SF	0	SF					N/A	N/A	N/A
1	1	Nurse's Office Infirmary	N/A	Ceiling Tile 2' x 4'		Non Suspect ACM	84	SF	0	SF					N/A	N/A	N/A
1	1	Infirmary Restroom	N/A	Ceramic Tile Floors		Non Suspect ACM	24	SF	0	SF					N/A	N/A	N/A
1	1	Infirmary Restroom	N/A	Concrete Block Wall		Non Suspect ACM	176	SF	0	SF					N/A	N/A	N/A
1	1	Infirmary Restroom	N/A	Plaster Ceiling		NAD	24	SF	0	SF					N/A	N/A	N/A
1	1	Nurse's Office Storage	M	Floor Tile VAT 12" x 12"	1160/01/01/DD	Assumed	99	SF	0	SF		Brown			1	No	1/D
1	1	Nurse's Office Storage	N/A	Concrete Block Wall		Non Suspect ACM	320	SF	0	SF					N/A	N/A	N/A
1	1	Nurse's Office Storage	N/A	Ceiling Tile 2' x 4'		Non Suspect ACM	99	SF	0	SF					N/A	N/A	N/A
1	1	Nurse's Storage Room Restroom	N/A	Ceramic Tile Floors		Non Suspect ACM	24	SF	0	SF			No access F2016 inspection		N/A	N/A	N/A
1	1	Nurse's Storage Room Restroom	N/A	Concrete Block Wall		Non Suspect ACM	176	SF	0	SF			No access F2016 inspection		N/A	N/A	N/A
1	1	Nurse's Storage Room Restroom	N/A	Plaster Ceiling		NAD	24	SF	0	SF					N/A	N/A	N/A
1	1	Nurse's Examination Room	M	Floor Tile VAT 12" x 12"	1160/01/01/DD	Assumed	121	SF	0	SF		Grey			1	No	1/D
1	1	Nurse's Examination Room	N/A	Concrete Block Wall		Non Suspect ACM	352	SF	0	SF					N/A	N/A	N/A
1	1	Nurse's Examination Room	N/A	Ceiling Tile 2' x 4'		Non Suspect ACM	121	SF	0	SF					N/A	N/A	N/A
1	1	Nurse's Office Closet next to back hall door	N/A	Ceiling Tile 2' x 4'		Non Suspect ACM	12	SF	0	SF					N/A	N/A	N/A
1	1	Nurse's Office Closet next to back hall door	M	Floor Tile VAT 12" x 12"	1160/01/01/DD	Assumed	12	SF	0	SF		Grey			1	No	1/D
1	1	Nurse's Office Closet next to back hall door	N/A	Concrete Block Wall		Non Suspect ACM	112	SF	0	SF					N/A	N/A	N/A
1	1	Nurse's Office Closet across from sink	X	X		X	X	X	X	X			No access		X	X	X
1	1	Main Office Server Room	X	X		X	X	X	X	X			No access		X	X	X
1	1	School Psychologist's Office	M	Floor Tile VAT 12" x 12"	1160/01/01/DD	Assumed	120	SF	0	SF		Grey			1	No	1/D
1	1	School Psychologist's Office	N/A	Concrete Block Wall		Non Suspect ACM	368	SF	0	SF					N/A	N/A	N/A
1	1	School Psychologist's Office	N/A	Ceiling Tile 2' x 4'		Non Suspect ACM	120	SF	0	SF					N/A	N/A	N/A
1	1	Motivation Main Office Hallway	M	Floor Tile VAT 12" x 12"	1160/01/01/DD	Assumed	450	SF	0	SF		Grey			1	No	1/D
1	1	Motivation Main Office Hallway	N/A	Concrete Block Wall		Non Suspect ACM	1620	SF	0	SF					N/A	N/A	N/A
1	1	Motivation Main Office Hallway	N/A	Ceiling Tile 2' x 4'		Non Suspect ACM	450	SF	0	SF					N/A	N/A	N/A
1	1	Main Office Hallway Supply Closet	M	Floor Tile VAT 12" x 12"	1160/01/01/DD	Assumed	8	SF	0	SF			Please verify color		1	No	1/D
1	1	Main Office Hallway Supply Closet	N/A	Concrete Block Wall		Non Suspect ACM	8	SF	0	SF					N/A	N/A	N/A
1	1	Main Office Hallway Supply Closet	N/A	Ceiling Tile 2' x 4'		Non Suspect ACM	96	SF	0	SF					N/A	N/A	N/A
1	1	Main Office Mail Room	M	Floor Tile VAT 12" x 12"	1160/01/01/DD	Assumed	256	SF	0	SF		Grey			1	No	1/D
1	1	Main Office Mail Room	N/A	Concrete Block Wall		Non Suspect ACM	640	SF	0	SF					N/A	N/A	N/A
1	1	Main Office Mail Room	N/A	Ceiling Tile 2' x 4'		Non Suspect ACM	256	SF	0	SF					N/A	N/A	N/A
1	1	Climate Support Office	M	Floor Tile VAT 12" x 12"	1160/01/01/DD	Assumed	128	SF	0	SF		Grey			1	No	1/D
1	1	Climate Support Office	N/A	Concrete Block Wall		Non Suspect ACM	384	SF	0	SF					N/A	N/A	N/A
1	1	Climate Support Office	N/A	Ceiling Tile 2' x 4'		Non Suspect ACM	128	SF	0	SF					N/A	N/A	N/A
1	1	Chill Out Room next to Operations Office	M	Floor Tile VAT 12" x 12"	1160/01/01/DD	Assumed	128	SF	0	SF		Grey			1	No	1/D
1	1	Chill Out Room next to Operations Office	N/A	Concrete Block Wall		Non Suspect ACM	384	SF	0	SF					N/A	N/A	N/A
1	1	Chill Out Room next to Operations Office	N/A	Ceiling Tile 2' x 4'		Non Suspect ACM	128	SF	0	SF					N/A	N/A	N/A
1	1	Operations Office	M	Floor Tile VAT 12" x 12"	1160/01/01/DD	Assumed	128	SF	0	SF		Grey			1	No	1/D
1	1	Operations Office	N/A	Concrete Block Wall		Non Suspect ACM	384	SF	0	SF					N/A	N/A	N/A
1	1	Operations Office	N/A	Ceiling Tile 2' x 4'		Non Suspect ACM	128	SF	0	SF					N/A	N/A	N/A

1160 Motivation HS/KIPP West @ Turner - 2015-2016 AHERA Three-Year Report.xls

		School District of Philadelphia Motivation High School and KIPP Turner West Middle School 5900 Baltimore Avenue, Philadelphia, PA 19143 ULCS# 1160 Year Built: 1969		AHERA Three-Year Reinspection 2015-2016 Room by Room Location Log Report							Reinspection Date: 9/29/15						
											Building Inspector: William Garrity, Jr.						
											Number: 70016699A						
											Management Planner: Mary Anne Lerro						
											Number: 740728						
E I L I N T	F J O R	On Site Room Name		System Affected	Material Description	HID#	Confirmed/Assumed/NAD/ Non Suspect ACM	Amount of Material	SF EA	Amount of Damage	SF EA	Color required for VAT	Comments/Description/Notes	Attic/ Crawl Space Ranking	Damage Potential (DP)	Newly Friable (NF)	Response Action (RA)
		1	1	Elevator Mechanical Room		N/A	Cement Floor		Non Suspect ACM	100	SF	0	SF				N/A
1	1	Maintenance Break Room next to Building Engineer's Office		M	Floor Tile VAT 12" x 12"	1160/01/01/DD	Assumed	144	SF	0	SF	Grey			1	No	1/D
1	1	Engineer's Office		N/A	Concrete Block Wall		Non Suspect ACM	500	SF	0	SF				N/A	N/A	N/A
1	1	Maintenance Break Room next to Building Engineer's Office		N/A	Ceiling Tile 2' x 4'		Non Suspect ACM	144	SF	0	SF				N/A	N/A	N/A
1	1	Maintenance Break Room Women's Locker Room		M	Floor Tile VAT 12" x 12"	1160/01/01/DD	Assumed	72	SF	0	SF	Brown			1	No	1/D
1	1	Maintenance Break Room Women's Locker Room		N/A	Concrete Block Wall		Non Suspect ACM	340	SF	0	SF				N/A	N/A	N/A
1	1	Maintenance Break Room Women's Locker Room		N/A	Ceiling Tile 2' x 4'		Non Suspect ACM	72	SF	0	SF		3 stained ct		N/A	N/A	N/A
1	1	Maintenance Break Room Women's Restroom		N/A	Ceramic Tile Floors		Non Suspect ACM	54	SF	0	SF				N/A	N/A	N/A
1	1	Maintenance Break Room Women's Restroom		N/A	Concrete Block Wall		Non Suspect ACM	300	SF	0	SF				N/A	N/A	N/A
1	1	Maintenance Break Room Women's Restroom		N/A	Plaster Ceiling		NAD	54	SF	0	SF				N/A	N/A	N/A
1	1	Maintenance Break Room Men's Locker Room		M	Floor Tile VAT 12" x 12"	1160/01/01/DD	Assumed	72	SF	0	SF	Grey			1	No	1/D
1	1	Maintenance Break Room Men's Locker Room		N/A	Concrete Block Wall		Non Suspect ACM	340	SF	0	SF				N/A	N/A	N/A
1	1	Maintenance Break Room Men's Locker Room		N/A	Ceiling Tile 2' x 4'		Non Suspect ACM	72	SF	0	SF				N/A	N/A	N/A
1	1	Maintenance Break Room Men's Restroom		N/A	Ceramic Tile Floors		Non Suspect ACM	54	SF	0	SF				N/A	N/A	N/A
1	1	Maintenance Break Room Men's Restroom		N/A	Concrete Block Wall		Non Suspect ACM	300	SF	0	SF				N/A	N/A	N/A
1	1	Maintenance Break Room Men's Restroom		N/A	Plaster Ceiling		NAD	54	SF	0	SF				N/A	N/A	N/A
1	1	Boiler Room		N/A	Cement Floor		Non Suspect ACM	1410	SF	0	SF		Boilers 2 & 3 enclosed and being abated by A-Team		N/A	N/A	N/A
1	1	Boiler Room		N/A	Concrete Block Wall		Non Suspect ACM	2156	SF	0	SF				N/A	N/A	N/A
1	1	Boiler Room		N/A	Concrete Ceiling		Non Suspect ACM	1410	SF	0	SF				N/A	N/A	N/A
1	1	Boiler Room		T	Boiler Breaching	1160/01/01/05	Confirmed	1106	SF	2	SF		Please fill out damage conditions		1	Yes	2/B
1	1	Boiler Room		N/A	Fiberglass Pipe Insulation		Non Suspect ACM	640	LF	0	LF				N/A	N/A	N/A
1	1	Boiler Room		N/A	Fiberglass Pipe Fitting Insulation		Non Suspect ACM	61	EA	0	EA				N/A	N/A	N/A
1	1	Boiler Room		T	Boiler Rope Insulation	1160/01/01/MM	Confirmed	216	SF	0	SF		Sampled November 2012. Provide amounts; boilers 2&3 under containment by A-Team; qty for boiler 1 only		1	No	1/D
1	1	Boiler Room		T	External Boiler Mud Insulation	1160/01/01/BATTA/AH/1690	Confirmed	216	SF	0	SF		Sampled November 2012. Provide amounts; boilers 2&3 under containment by A-Team; qty for boiler 1 only		1	No	1/D
1	1	Boiler Room		M	Duct Insulation	1160/01/01/06	Confirmed	30	SF	0	SF		Qty is for small duct on opposite side of chimney from breaching.		1	No	1/D
1	1	Boiler Room		N/A	Tank Insulation		NAD		SF	0	SF		Provide amounts		N/A	N/A	N/A
1	1	Electrical Room		N/A	Concrete Ceiling		Non Suspect ACM	893	SF	0	SF				N/A	N/A	N/A
1	1	Electrical Room		N/A	Cement Floor		Non Suspect ACM	893	SF	0	SF				N/A	N/A	N/A
1	1	Electrical Room		N/A	Concrete Block Wall		Non Suspect ACM	1452	SF	0	SF				N/A	N/A	N/A
1	1	Electrical Room		N/A	Pipe Fitting Insulation		NAD	4	EA	0	EA				N/A	N/A	N/A
1	1	Maintenance Loading Dock / Storage Cage		N/A	Cement Floor		Non Suspect ACM	1150	SF	0	SF				N/A	N/A	N/A
1	1	Maintenance Loading Dock / Storage Cage		N/A	Concrete Ceiling		Non Suspect ACM	1150	SF	0	SF				N/A	N/A	N/A
1	1	Maintenance Loading Dock / Storage Cage		N/A	Concrete Block Wall		Non Suspect ACM	1752	SF	0	SF				N/A	N/A	N/A
1	1	Maintenance Loading Dock / Storage Cage		N/A	Fiberglass Pipe Fitting Insulation		Non Suspect ACM	322	EA	0	EA				N/A	N/A	N/A
1	1	Maintenance Loading Dock / Storage Cage		N/A	Fiberglass Pipe Insulation		Non Suspect ACM	27	LF	0	LF				N/A	N/A	N/A
1	1	Incinerator Room next to Building Engineer's Office		N/A	Concrete Block Wall		Non Suspect ACM	704	SF	0	SF				N/A	N/A	N/A
1	1	Incinerator Room next to Building Engineer's Office		N/A	Cement Floor		Non Suspect ACM	252	SF	0	SF				N/A	N/A	N/A
1	1	Incinerator Room next to Building Engineer's Office		N/A	Concrete Ceiling		Non Suspect ACM	252	SF	0	SF				N/A	N/A	N/A
1	1	Incinerator Room next to Building Engineer's Office		N/A	Fiberglass Pipe Insulation		Non Suspect ACM	25	LF	0	LF				N/A	N/A	N/A
1	1	Incinerator Room next to Building Engineer's Office		N/A	Fiberglass Pipe Fitting Insulation		Non Suspect ACM	4	EA	0	EA				N/A	N/A	N/A
1	1	Building Engineer's Office		M	Floor Tile VAT 12" x 12"	1160/01/01/DD	Assumed	72	SF	0	SF	Grey			1	No	1/D
1	1	Building Engineer's Office		N/A	Concrete Block Wall		Non Suspect ACM	340	SF	0	SF				N/A	N/A	N/A
1	1	Building Engineer's Office		N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	72	SF	0	SF				N/A	N/A	N/A
1	1	Stair 3 next to Kitchen		N/A	Terrazzo Floors		Non Suspect ACM	288	SF	0	SF				N/A	N/A	N/A
1	1	Stair 3 next to Kitchen		N/A	Concrete Block Wall		Non Suspect ACM	1800	SF	0	SF				N/A	N/A	N/A
1	1	Stair 3 next to Kitchen		S	Textured Ceiling Paint	1160/01/01/03	Confirmed	288	SF	0	SF				1	No	1/D
1	1	Girl's Restroom across from IT Room 124		N/A	Ceramic Tile Floors		Non Suspect ACM	156	SF	0	SF				N/A	N/A	N/A
1	1	Girl's Restroom across from IT Room 124		N/A	Concrete Block Wall		Non Suspect ACM	500	SF	0	SF				N/A	N/A	N/A
1	1	Girl's Restroom across from IT Room 124		N/A	Plaster Ceiling		NAD	156	SF	0	SF		Inspector- please verify if this material is Plaster or Sheetrock		N/A	N/A	N/A
1	1	Custodial Closet		N/A	Concrete Block Wall		Non Suspect ACM	312	SF	0	SF				N/A	N/A	N/A
1	1	Custodial Closet		N/A	Cement Floor		Non Suspect ACM	42	SF	0	SF				N/A	N/A	N/A
1	1	Custodial Closet		S	Textured Ceiling Paint	1160/01/01/03	Confirmed	42	SF	0	SF				1	No	1/D
1	1	Custodial Closet		M	Fiberglass Pipe Fitting Insulation	1160/01/01/BATTA/WG/2611	Confirmed	11	EA	0	EA		Covered with positive textured ceiling paint. Please verify if the paint present is the same as the textured ceiling paint.		1	No	1/D
1	1	Custodial Closet		M	Fiberglass Pipe Insulation	1160/01/01/BATTA/WG/2611	Confirmed	20	LF	0	LF		Covered with positive textured ceiling paint. Please verify if the paint present is the same as the textured ceiling paint.		1	No	1/D
1	1	Boy's Restroom across from Stair 2		N/A	Ceramic Tile Floors		Non Suspect ACM	132	SF	0	SF				N/A	N/A	N/A
1	1	Boy's Restroom across from Stair 2		N/A	Concrete Block Wall		Non Suspect ACM	460	SF	0	SF				N/A	N/A	N/A
1	1	Boy's Restroom across from Stair 2		N/A	Plaster Ceiling		NAD	132	SF	0	SF		Inspector- please verify if this material is Plaster or Sheetrock		N/A	N/A	N/A
1	1	Cafeteria		N/A	Terrazzo Floors		Non Suspect ACM	7715	SF	0	SF				N/A	N/A	N/A

1160 Motivation HS/KIPP West @ Turner - 2015-2016 AHERA Three-Year Report.xls

		School District of Philadelphia Motivation High School and KIPP Turner West Middle School 5900 Baltimore Avenue, Philadelphia, PA 19143 ULCS# 1160 Year Built: 1969		AHERA Three-Year Reinspection 2015-2016 Room by Room Location Log Report							Reinspection Date: 9/29/15						
											Building Inspector: William Garrity, Jr.						
											Number: 70016699A						
											Management Planner: Mary Anne Lerro						
											Number: 740728						
E I L I N E	F L O O R	On Site Room Name		System Affected	Material Description	HID#	Confirmed/Assumed/NAD/ Non Suspect ACM	Amount of Material	SF LF EA	Amount of Damage	SF LF EA	Color required for VAT	Comments/Description/Notes	Attic/ Crawl Space Ranking	Damage Potential (DP)	Newly Friable (NF)	Response Action (RA)
		1	1	Cafeteria	N/A	Concrete Block Wall		Non Suspect ACM	5270	SF	0	SF					N/A
1	1	Cafeteria	M	Ceiling Tile 1' x 1'	1160/01/01/HH	Assumed	5700	SF	0	SF					1	No	1/D
1	1	Cafeteria	N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	2015	SF	0	SF					N/A	N/A	N/A
1	1	Cafeteria	M	Transite Sills	1160/01/01/AA	Confirmed	4	SF	0	SF			Fire Extinguisher Sill		1	No	1/D
1	1	Cafeteria Mechanical Room	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	601	LF	0	LF					N/A	N/A	N/A
1	1	Cafeteria Mechanical Room	N/A	Fiberglass Pipe Fitting Insulation		Non Suspect ACM	70	EA	0	EA					N/A	N/A	N/A
1	1	Cafeteria Mechanical Room	M	Vibration Damper Cloth	1160/01/01/10	Assumed	15	SF	0	SF					1	No	1/D
1	1	Cafeteria Mechanical Room	N/A	Concrete Block Wall		Non Suspect ACM	1480	SF	0	SF					N/A	N/A	N/A
1	1	Cafeteria Mechanical Room	N/A	Cement Floor		Non Suspect ACM	322	SF	0	SF					N/A	N/A	N/A
1	1	Cafeteria Mechanical Room	N/A	Concrete Ceiling		Non Suspect ACM	322	SF	0	SF					N/A	N/A	N/A
1	1	Kitchen	N/A	Terrazzo Floors		Non Suspect ACM	465	SF	0	SF					N/A	N/A	N/A
1	1	Kitchen	N/A	Plaster Ceiling		NAD	465	SF	0	SF					N/A	N/A	N/A
1	1	Kitchen	N/A	Concrete Block Wall		Non Suspect ACM	828	SF	0	SF					N/A	N/A	N/A
1	1	Kitchen Staff Locker Room	N/A	Ceiling Tile 2' x 4'		Non Suspect ACM	35	SF	0	SF					N/A	N/A	N/A
1	1	Kitchen Staff Locker Room	N/A	Concrete Block Wall		Non Suspect ACM	192	SF	0	SF					N/A	N/A	N/A
1	1	Kitchen Staff Locker Room	N/A	Terrazzo Floors		Non Suspect ACM	35	SF	0	SF					N/A	N/A	N/A
1	1	Kitchen Staff Restroom	N/A	Ceiling Tile 2' x 4'		Non Suspect ACM	35	SF	0	SF					N/A	N/A	N/A
1	1	Kitchen Staff Restroom	N/A	Concrete Block Wall		Non Suspect ACM	192	SF	0	SF					N/A	N/A	N/A
1	1	Kitchen Staff Restroom	N/A	Terrazzo Floors		Non Suspect ACM	35	SF	0	SF					N/A	N/A	N/A
1	1	Kitchen Office	N/A	Plaster Ceiling		NAD	89	SF	0	SF					N/A	N/A	N/A
1	1	Kitchen Office	N/A	Concrete Block Wall		Non Suspect ACM	304	SF	0	SF					N/A	N/A	N/A
1	1	Kitchen Office	N/A	Terrazzo Floors		Non Suspect ACM	89	SF	0	SF					N/A	N/A	N/A
1	1	Kitchen Custodial Closet	N/A	Terrazzo Floors		Non Suspect ACM	30	SF	0	SF					N/A	N/A	N/A
1	1	Kitchen Custodial Closet	N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	30	SF	0	SF					N/A	N/A	N/A
1	1	Kitchen Custodial Closet	N/A	Concrete Block Wall		Non Suspect ACM	198	SF	0	SF					N/A	N/A	N/A
1	1	Cafeteria Food Storage Room	N/A	Terrazzo Floors		Non Suspect ACM	2015	SF	0	SF					N/A	N/A	N/A
1	1	Cafeteria Food Storage Room	N/A	Sheetrock Wall		Non Suspect ACM	1920	SF	0	SF					N/A	N/A	N/A
1	1	Cafeteria Food Storage Room	N/A	Ceiling Tile 2' x 4'		Non Suspect ACM	2015	SF	0	SF					N/A	N/A	N/A
1	1	Cafeteria Trash Room	N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	136	SF	0	SF					N/A	N/A	N/A
1	1	Cafeteria Trash Room	N/A	Sheetrock Wall		Non Suspect ACM	200	SF	0	SF					N/A	N/A	N/A
1	1	Cafeteria Trash Room	N/A	Concrete Block Wall		Non Suspect ACM	200	SF	0	SF					N/A	N/A	N/A
1	1	Cafeteria Trash Room	N/A	Terrazzo Floors		Non Suspect ACM	136	SF	0	SF					N/A	N/A	N/A
1	1	Men's Restroom across from Main Office Mail Room	N/A	Ceramic Tile Floors		Non Suspect ACM	120	SF	0	SF					N/A	N/A	N/A
1	1	Men's Restroom across from Main Office Mail Room	M	Floor Tile VAT 12" x 12"	1160/01/01/DD	Assumed	120	SF	0	SF		Grey			1	No	1/D
1	1	Men's Restroom across from Main Office Mail Room	N/A	Ceiling Tile 2' x 4'		Non Suspect ACM	120	SF	0	SF					N/A	N/A	N/A
1	1	Men's Restroom across from Main Office Mail Room	N/A	Plaster Ceiling		NAD	120	SF	0	SF					N/A	N/A	N/A
1	1	Men's Restroom across from Main Office Mail Room	N/A	Concrete Block Wall		Non Suspect ACM	440	SF	0	SF					N/A	N/A	N/A
1	1	Women's Restroom across from Main Office Mail Room	N/A	Ceramic Tile Floors		Non Suspect ACM	154	SF	0	SF					N/A	N/A	N/A
1	1	Women's Restroom across from Main Office Mail Room	M	Floor Tile VAT 12" x 12"	1160/01/01/DD	Assumed	154	SF	0	SF		Grey			1	No	1/D
1	1	Women's Restroom across from Main Office Mail Room	N/A	Ceiling Tile 2' x 4'		Non Suspect ACM	154	SF	3	SF					N/A	N/A	N/A
1	1	Women's Restroom across from Main Office Mail Room	N/A	Plaster Ceiling		NAD	154	SF	0	SF					N/A	N/A	N/A
1	1	Women's Restroom across from Main Office Mail Room	N/A	Concrete Block Wall		Non Suspect ACM	500	SF	0	SF					N/A	N/A	N/A
1	1	Stair 1 next to Motivation Office	S	Textured Ceiling Paint	1160/01/01/03	Confirmed	432	SF	0	SF					1	No	1/D
1	1	Stair 1 next to Motivation Office	N/A	Concrete Block Wall		Non Suspect ACM	1152	SF	0	SF					N/A	N/A	N/A
1	1	Stair 1 next to Motivation Office	N/A	Cement Floor		Non Suspect ACM	432	SF	0	SF					N/A	N/A	N/A
1	1	Motivation Faculty Dining Room 139D	N/A	Concrete Block Wall		Non Suspect ACM	1034	SF	0	SF					N/A	N/A	N/A
1	1	Motivation Faculty Dining Room 139D	S	Textured Ceiling Paint	1160/01/01/03	Confirmed	546	SF	0	SF					1	No	1/D
1	1	Motivation Faculty Dining Room 139D	M	Floor Tile VAT 12" x 12"	1160/01/01/DD	Assumed	346	SF	0	SF		Grey			1	No	1/D
1	1	Motivation Faculty Dining Room 139D	M	Floor Tile VAT 12" x 12"	1160/01/01/DD	Assumed	200	SF	0	SF		Black			1	No	1/D
1	1	Motivation Faculty Dining Room 139D	N/A	Fiberglass Pipe Fitting Insulation		Non Suspect ACM	32	EA	0	EA					N/A	N/A	N/A
1	1	Motivation Faculty Dining Room 139D	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	360	LF	0	LF					N/A	N/A	N/A
1	1	Motivation Faculty Dining Room 139D	M	Blackboard Glue Dots	1160/01/01/BATTA/AH/2600	Assumed	16	SF	0	SF					1	No	1/D
1	1	KWPEA ECU/Penn Pod Entrance	N/A	Ceiling Tile 2' x 4'		Non Suspect ACM	472	SF	0	SF					N/A	N/A	N/A
1	1	KWPEA ECU/Penn Pod Entrance	N/A	Concrete Block Wall		Non Suspect ACM	783	SF	0	SF					N/A	N/A	N/A
1	1	KWPEA ECU/Penn Pod Entrance	M	Floor Tile VAT 12" x 12"	1160/01/01/DD	Assumed	472	SF	0	SF		Grey			1	No	1/D
1	1	KWPEA ECU Classroom	M	Floor Tile VAT 12" x 12"	1160/01/01/DD	Assumed	748	SF	0	SF		Grey			1	No	1/D
1	1	KWPEA ECU Classroom	S	Textured Ceiling Paint	1160/01/01/03	Confirmed	748	SF	0	SF					1	No	1/D
1	1	KWPEA ECU Classroom	N/A	Concrete Block Wall		Non Suspect ACM	800	SF	0	SF					N/A	N/A	N/A
1	1	KWPEA ECU Classroom	N/A	Sheetrock Wall		Non Suspect ACM	500	SF	0	SF					N/A	N/A	N/A
1	1	KWPEA ECU Classroom	M	Blackboard Glue Dots	1160/01/01/BATTA/AH/2600	Assumed	32	SF	0	SF					1	No	1/D
1	1	KWPEA ECU Classroom	N/A	Fiberglass Pipe Fitting Insulation		Non Suspect ACM	15	EA	0	EA					N/A	N/A	N/A
1	1	KWPEA ECU Classroom	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	170	LF	0	LF					N/A	N/A	N/A
1	1	ECU Classroom Materials Closet	N/A	Cement Floor		Non Suspect ACM	72	SF	0	SF					N/A	N/A	N/A
1	1	ECU Classroom Materials Closet	N/A	Ceiling Tile 2' x 4'		Non Suspect ACM	72	SF	0	SF					N/A	N/A	N/A
1	1	ECU Classroom Materials Closet	N/A	Concrete Block Wall		Non Suspect ACM	340	SF	0	SF					N/A	N/A	N/A
1	1	ECU Classroom Coat Closet	N/A	Cement Floor		Non Suspect ACM	72	SF	0	SF					N/A	N/A	N/A

1160 Motivation HS/KIPP West @ Turner - 2015-2016 AHERA Three-Year Report.xls

		School District of Philadelphia Motivation High School and KIPP Turner West Middle School 5900 Baltimore Avenue, Philadelphia, PA 19143 ULCS# 1160 Year Built: 1969		AHERA Three-Year Reinspection 2015-2016 Room by Room Location Log Report							Reinspection Date: 9/29/15						
											Building Inspector: William Garrity, Jr.						
											Number: 70016699A						
											Management Planner: Mary Anne Lerro						
											Number: 740728						
E I S I O N R	F J O O R	On Site Room Name		System Affected	Material Description	HID#	Confirmed/Assumed/NAD/ Non Suspect ACM	Amount of Material	SF LF	Amount of Damage	SF LF	Color required for VAT	Comments/Description/Notes	Attic/ Crawl Space Ranking	Damage Potential (DP)	Newly Friable (NF)	Response Action (RA)
		1	1	ECU Classroom Coat Closet	N/A	Ceiling Tile 2' x 4'			Non Suspect ACM	72	SF	0	SF				N/A
1	1	ECU Classroom Coat Closet	N/A	Concrete Block Wall			Non Suspect ACM	340	SF	0	SF				N/A	N/A	N/A
1	1	KWPEA Grinnell College Classroom	M	Floor Tile VAT 12" x 12"	1160/01/01/DD		Assumed	734	SF	0	SF	Grey			1	No	1/D
1	1	KWPEA Grinnell College Classroom	S	Textured Ceiling Paint	1160/01/01/03		Confirmed	1034	SF	0	SF				1	No	1/D
1	1	KWPEA Grinnell College Classroom	N/A	Concrete Block Wall			Non Suspect ACM	1518	SF	0	SF				N/A	N/A	N/A
1	1	KWPEA Grinnell College Classroom	N/A	Sheetrock Wall			Non Suspect ACM	1518	SF	0	SF				N/A	N/A	N/A
1	1	KWPEA Grinnell College Classroom	M	Floor Tile VAT 12" x 12"	1160/01/01/DD		Assumed	300	SF	0	SF	Black			1	No	1/D
1	1	KWPEA Grinnell College Classroom	N/A	Fiberglass Pipe Fitting Insulation			Non Suspect ACM	455	EA	0	EA				N/A	N/A	N/A
1	1	KWPEA Grinnell College Classroom	N/A	Fiberglass Pipe Insulation			Non Suspect ACM	13	LF	0	LF				N/A	N/A	N/A
1	1	KWPEA Penn Classroom	S	Textured Ceiling Paint	1160/01/01/03		Confirmed	877	SF	0	SF				1	No	1/D
1	1	KWPEA Penn Classroom	N/A	Concrete Block Wall			Non Suspect ACM	1166	SF	0	SF				N/A	N/A	N/A
1	1	KWPEA Penn Classroom	N/A	Sheetrock Wall			Non Suspect ACM	198	SF	0	SF				N/A	N/A	N/A
1	1	KWPEA Penn Classroom	M	Floor Tile VAT 12" x 12"	1160/01/01/DD		Assumed	877	SF	0	SF	Grey			1	No	1/D
1	1	KWPEA Penn Classroom	M	Sink Undercoat Mastic	1160/01/01/JJ		Assumed	6	SF	0	SF				1	No	1/D
1	1	KWPEA Penn Classroom	N/A	Fiberglass Pipe Insulation			Non Suspect ACM	300	LF	0	LF				N/A	N/A	N/A
1	1	KWPEA Penn Classroom	N/A	Fiberglass Pipe Fitting Insulation			Non Suspect ACM	30	EA	0	EA				N/A	N/A	N/A
1	1	Penn Classroom Closet	N/A	Ceiling Tile 2' x 4'			Non Suspect ACM	96	SF	0	SF				N/A	N/A	N/A
1	1	Penn Classroom Closet	N/A	Concrete Block Wall			Non Suspect ACM	320	SF	0	SF				N/A	N/A	N/A
1	1	Penn Classroom Closet	M	Floor Tile VAT 12" x 12"	1160/01/01/DD		Assumed	96	SF	0	SF	Grey			1	No	1/D
1	1	KWPEA Shenendoah Orchestra Room	N/A	Concrete Block Wall			Non Suspect ACM	1752	SF	0	SF				N/A	N/A	N/A
1	1	KWPEA Shenendoah Orchestra Room	S	Textured Ceiling Paint	1160/01/01/03		Confirmed	1122	SF	0	SF				1	No	1/D
1	1	KWPEA Shenendoah Orchestra Room	M	Floor Tile VAT 12" x 12"	1160/01/01/DD		Assumed	1122	SF	0	SF	Grey			1	No	1/D
1	1	KWPEA Orchestra Room Server Closet	M	Floor Tile VAT 12" x 12"	1160/01/01/DD		Assumed	80	SF	0	SF		Please verify color. No access F2016 inspection		1	No	1/D
1	1	KWPEA Orchestra Room Server Closet	N/A	Concrete Block Wall			Non Suspect ACM	324	SF	0	SF		No access F2016 inspection		N/A	N/A	N/A
1	1	KWPEA Orchestra Room Server Closet	N/A	Ceiling Tile 2' x 4'			Non Suspect ACM	80	SF	0	SF		No access F2016 inspection		N/A	N/A	N/A
1	1	KWPEA Orchestra Room Mechanical Room	N/A	Concrete Block Wall			Non Suspect ACM	418	SF	0	SF		No access F2016 inspection		N/A	N/A	N/A
1	1	KWPEA Orchestra Room Mechanical Room	N/A	Concrete Ceiling			Non Suspect ACM	88	SF	0	SF		No access F2016 inspection		N/A	N/A	N/A
1	1	KWPEA Orchestra Room Mechanical Room	N/A	Cement Floor			Non Suspect ACM	88	SF	0	SF		No access F2016 inspection		N/A	N/A	N/A
1	1	KWPEA Orchestra Room Mechanical Room	M	Vibration Damper Cloth	1160/01/01/10		Assumed	8	SF	0	SF		No access F2016 inspection		1	No	1/D
1	1	KWPEA Girl's Restroom next to Cafeteria	N/A	Plaster Ceiling			NAD	252	SF	0	SF				N/A	N/A	N/A
1	1	KWPEA Girl's Restroom next to Cafeteria	N/A	Concrete Block Wall			Non Suspect ACM	792	SF	0	SF				N/A	N/A	N/A
1	1	KWPEA Girl's Restroom next to Cafeteria	N/A	Ceramic Tile Floors			Non Suspect ACM	252	SF	0	SF				N/A	N/A	N/A
1	1	KWPEA Custodial Closet next to Cafeteria	S	Textured Ceiling Paint	1160/01/01/03		Confirmed	42	SF	0	SF				1	No	1/D
1	1	KWPEA Custodial Closet next to Cafeteria	N/A	Concrete Block Wall			Non Suspect ACM	312	SF	0	SF				N/A	N/A	N/A
1	1	KWPEA Custodial Closet next to Cafeteria	N/A	Cement Floor			Non Suspect ACM	42	SF	0	SF				N/A	N/A	N/A
1	1	KWPEA Custodial Closet next to Cafeteria	M	Fiberglass Pipe Insulation	1160/01/01/BATTA/WG/2611		Confirmed	20	LF	0	LF		Covered with positive textured ceiling paint. Please verify if the paint present is the same as the textured ceiling paint.		1	No	1/D
1	1	KWPEA Custodial Closet next to Cafeteria	M	Fiberglass Pipe Fitting Insulation	1160/01/01/BATTA/WG/2611		Confirmed	11	EA	0	EA		Covered with positive textured ceiling paint. Please verify if the paint present is the same as the textured ceiling paint.		1	No	1/D
1	1	KWPEA Boy's Restroom next to Cafeteria	N/A	Plaster Ceiling			NAD	252	SF	0	SF				N/A	N/A	N/A
1	1	KWPEA Boy's Restroom next to Cafeteria	N/A	Concrete Block Wall			Non Suspect ACM	792	SF	0	SF				N/A	N/A	N/A
1	1	KWPEA Boy's Restroom next to Cafeteria	N/A	Ceramic Tile Floors			Non Suspect ACM	252	SF	0	SF				N/A	N/A	N/A
1	1	Stair 4 next to KWPEA Orchestra Room	N/A	Terrazzo Floors			Non Suspect ACM	288	SF	0	SF				N/A	N/A	N/A
1	1	Stair 4 next to KWPEA Orchestra Room	N/A	Concrete Block Wall			Non Suspect ACM	1800	SF	0	SF				N/A	N/A	N/A
1	1	Stair 4 next to KWPEA Orchestra Room	S	Textured Ceiling Paint	1160/01/01/03		Confirmed	288	SF	0	SF				1	No	1/D
1	1	KWPEA Main Office	S	Textured Ceiling Paint	1160/01/01/03		Confirmed	726	SF	0	SF				1	No	1/D
1	1	KWPEA Main Office	N/A	Concrete Block Wall			Non Suspect ACM	1012	SF	0	SF				N/A	N/A	N/A
1	1	KWPEA Main Office	N/A	Sheetrock Wall			Non Suspect ACM	352	SF	0	SF				N/A	N/A	N/A
1	1	KWPEA Main Office	M	Floor Tile VAT 12" x 12"	1160/01/01/DD		Assumed	726	SF	0	SF	Grey			1	No	1/D
1	1	KWPEA Main Office	M	Fiberglass Pipe Insulation	1160/01/01/BATTA/WG/2611		Confirmed	128	LF	0	LF		Covered with positive textured ceiling paint. Please verify if the paint present is the same as the textured ceiling paint.		1	No	1/D
1	1	KWPEA Main Office	M	Fiberglass Pipe Fitting Insulation	1160/01/01/BATTA/WG/2611		Confirmed	17	EA	0	EA		Covered with positive textured ceiling paint. Please verify if the paint present is the same as the textured ceiling paint.		1	No	1/D
1	1	KWPEA Leadership Office	S	Textured Ceiling Paint	1160/01/01/03		Confirmed	224	SF	0	SF				1	No	1/D
1	1	KWPEA Leadership Office	N/A	Concrete Block Wall			Non Suspect ACM	110	SF	0	SF				N/A	N/A	N/A
1	1	KWPEA Leadership Office	N/A	Sheetrock Wall			Non Suspect ACM	462	SF	0	SF				N/A	N/A	N/A
1	1	KWPEA Leadership Office	M	Floor Tile VAT 12" x 12"	1160/01/01/DD		Assumed	224	SF	0	SF	Grey			1	No	1/D
1	1	KWPEA Leadership Office	M	Duct Work	1160/01/01/BATTA/WG/1670		Confirmed	110	SF	0	SF		Partially covered with ACM textured paint. Please verify what kind of material		1	No	1/D
1	1	KWPEA Leadership Office	M	Fiberglass Pipe Insulation	1160/01/01/BATTA/WG/2611		Confirmed	154	LF	0	LF		Covered with positive textured ceiling paint. Please verify if the paint present is the same as the textured ceiling paint.		1	No	1/D
1	1	KWPEA Leadership Office	M	Fiberglass Pipe Fitting Insulation	1160/01/01/BATTA/WG/2611		Confirmed	17	EA	0	EA		Covered with positive textured ceiling paint. Please verify if the paint present is the same as the textured ceiling paint.		1	No	1/D
1	1	KWPEA Main Office Conference Room	S	Textured Ceiling Paint	1160/01/01/03		Confirmed	140	SF	0	SF				1	No	1/D
1	1	KWPEA Main Office Conference Room	N/A	Concrete Block Wall			Non Suspect ACM	275	SF	0	SF				N/A	N/A	N/A
1	1	KWPEA Main Office Conference Room	N/A	Sheetrock Wall			Non Suspect ACM	275	SF	0	SF				N/A	N/A	N/A
1	1	KWPEA Main Office Conference Room	M	Floor Tile VAT 12" x 12"	1160/01/01/DD		Assumed	140	SF	0	SF	Grey			1	No	1/D

1160 Motivation HS/KIPP West @ Turner - 2015-2016 AHERA Three-Year Report.xls

		School District of Philadelphia Motivation High School and KIPP Turner West Middle School 5900 Baltimore Avenue, Philadelphia, PA 19143 ULCS# 1160 Year Built: 1969		AHERA Three-Year Reinspection 2015-2016 Room by Room Location Log Report							Reinspection Date: 9/29/15						
											Building Inspector: William Garrity, Jr.						
											Number: 70016699A						
											Management Planner: Mary Anne Lerro						
											Number: 740728						
E I S I O N S	F L O O R	On Site Room Name		System Affected	Material Description	HID#	Confirmed/Assumed/NAD/ Non Suspect ACM	Amount of Material	SF LF EA	Amount of Damage	SF LF EA	Color required for VAT	Comments/Description/Notes	Attic/ Crawl Space Ranking	Damage Potential (DP)	Newly Friable (NF)	Response Action (RA)
		1	1	KWPEA Main Office Conference Room	M	Fiberglass Pipe Insulation	1160/01/01/BATTA/WG/2611	Confirmed	105	LF	0	LF			Covered with positive textured ceiling paint. Please verify if the paint present is the same as the textured ceiling paint.		1
1	1	KWPEA Nurse's Office	S	Textured Ceiling Paint	1160/01/01/03	Confirmed	297	SF	0	SF					1	No	1/D
1	1	KWPEA Nurse's Office	N/A	Concrete Block Wall		Non Suspect ACM	550	SF	0	SF					N/A	N/A	N/A
1	1	KWPEA Nurse's Office	N/A	Sheetrock Wall		Non Suspect ACM	330	SF	0	SF					N/A	N/A	N/A
1	1	KWPEA Nurse's Office	M	Floor Tile VAT 12" x 12"	1160/01/01/DD	Assumed	297	SF	0	SF	Grey				1	No	1/D
1	1	KWPEA Nurse's Office	M	Fiberglass Pipe Insulation	1160/01/01/BATTA/WG/2611	Confirmed	60	LF	0	LF			Covered with positive textured ceiling paint. Please verify if the paint present is the same as the textured ceiling paint.		1	No	1/D
1	1	KWPEA Nurse's Office	M	Fiberglass Pipe Fitting Insulation	1160/01/01/BATTA/WG/2611	Confirmed	8	EA	0	EA			Covered with positive textured ceiling paint. Please verify if the paint present is the same as the textured ceiling paint.		1	No	1/D
1	1	KWPEA Nurse's Office Closet	N/A	Concrete Ceiling		Non Suspect ACM	92	SF	0	SF					N/A	N/A	N/A
1	1	KWPEA Nurse's Office Closet	N/A	Concrete Block Wall		Non Suspect ACM	418	SF	0	SF					N/A	N/A	N/A
1	1	KWPEA Nurse's Office Closet	M	Floor Tile VAT 12" x 12"	1160/01/01/DD	Assumed	92	SF	0	SF	Grey				1	No	1/D
1	1	KWPEA Faculty Lounge	N/A	Ceiling Tile 2' x 4'		Non Suspect ACM	185	SF	0	SF					N/A	N/A	N/A
1	1	KWPEA Faculty Lounge	N/A	Concrete Block Wall		Non Suspect ACM	522	SF	0	SF					N/A	N/A	N/A
1	1	KWPEA Faculty Lounge	M	Floor Tile VAT 12" x 12"	1160/01/01/DD	Assumed	185	SF	0	SF	Grey				1	No	1/D
1	1	KWPEA Faculty Lounge Closet	N/A	Concrete Block Wall		Non Suspect ACM	132	SF	0	SF					N/A	N/A	N/A
1	1	KWPEA Faculty Lounge Closet	N/A	Concrete Ceiling		Non Suspect ACM	8	SF	0	SF					N/A	N/A	N/A
1	1	KWPEA Faculty Lounge Closet	M	Floor Tile VAT 12" x 12"	1160/01/01/DD	Assumed	8	SF	0	SF	Grey				1	No	1/D
1	1	Closest across from Faculty Lounge	X	X		X	X	X	X	X			No access		X	X	X
1	1	KWPEA Bloomsburg Classroom	S	Textured Ceiling Paint	1160/01/01/03	Confirmed	1128	SF	0	SF					1	No	1/D
1	1	KWPEA Bloomsburg Classroom	N/A	Concrete Block Wall		Non Suspect ACM	1562	SF	0	SF					N/A	N/A	N/A
1	1	KWPEA Bloomsburg Classroom	M	Floor Tile VAT 12" x 12"	1160/01/01/DD	Assumed	1128	SF	0	SF	Grey				1	No	1/D
1	1	KWPEA Bloomsburg Classroom	M	Fiberglass Pipe Insulation	1160/01/01/BATTA/WG/2611	Confirmed	30	LF	0	LF			Covered with positive textured ceiling paint. Please verify if the paint present is the same as the textured ceiling paint.		1	No	1/D
1	1	KWPEA Bloomsburg Classroom	M	Fiberglass Pipe Fitting Insulation	1160/01/01/BATTA/WG/2611	Confirmed	5	EA	0	EA			Covered with positive textured ceiling paint. Please verify if the paint present is the same as the textured ceiling paint.		1	No	1/D
1	1	Bloomsburg Classroom Darm Room Closet	N/A	Plaster Ceiling		NAD	153	SF	0	SF					N/A	N/A	N/A
1	1	Bloomsburg Classroom Cot Closet	N/A	Concrete Block Wall		Non Suspect ACM	500	SF	0	SF					N/A	N/A	N/A
1	1	Bloomsburg Classroom Cot Closet	M	Floor Tile VAT 12" x 12"	1160/01/01/DD	Assumed	153	SF	0	SF	Grey				1	No	1/D
1	1	Bloomsburg Classroom Cot Closet	M	Sink Undercoat Mastic	1160/01/01/JJ	Assumed	12	SF	0	SF					1	No	1/D
1	1	Bloomsburg Classroom Book Closet	N/A	Concrete Block Wall		Non Suspect ACM	440	SF	0	SF					N/A	N/A	N/A
1	1	Bloomsburg Classroom Book Closet	N/A	Concrete Ceiling		Non Suspect ACM	88	SF	0	SF					N/A	N/A	N/A
1	1	Bloomsburg Classroom Book Closet	N/A	Cement Floor		Non Suspect ACM	88	SF	0	SF					N/A	N/A	N/A
1	1	KWPEA Gym	M	Floor Tile VAT 12" x 12"	1160/01/01/DD	Assumed	1632	SF	0	SF	Tan				1	No	1/D
1	1	KWPEA Gym	S	Textured Ceiling Paint	1160/01/01/03	Confirmed	1632	SF	0	SF					1	No	1/D
1	1	KWPEA Gym	N/A	Concrete Block Wall		Non Suspect ACM	1804	SF	0	SF					N/A	N/A	N/A
1	1	KWPEA Gym	M	Fiberglass Pipe Fitting Insulation	1160/01/01/BATTA/WG/2611	Confirmed	33	EA	0	EA			Covered with positive textured ceiling paint. Please verify if the paint present is the same as the textured ceiling paint.		1	No	1/D
1	1	KWPEA Gym	M	Fiberglass Pipe Insulation	1160/01/01/BATTA/WG/2611	Confirmed	300	LF	0	LF			Covered with positive textured ceiling paint. Please verify if the paint present is the same as the textured ceiling paint.		1	No	1/D
1	1	KWPEA Gym	M	Sink Undercoat Mastic	1160/01/01/JJ	Assumed	6	SF	0	SF					1	No	1/D
1	1	KWPEA Gym Closet	N/A	Concrete Block Wall		Non Suspect ACM	429	SF	0	SF					N/A	N/A	N/A
1	1	KWPEA Gym Closet	N/A	Concrete Ceiling		Non Suspect ACM	94	SF	0	SF					N/A	N/A	N/A
1	1	KWPEA Gym Closet	N/A	Cement Floor		Non Suspect ACM	94	SF	0	SF					N/A	N/A	N/A
1	1	KWPEA Hallway from ECU/Penn Pod to Loading Dock	N/A	Ceiling Tile 2' x 4'		Non Suspect ACM	2814	SF	0	SF					N/A	N/A	N/A
1	1	KWPEA Hallway from ECU/Penn Pod to Loading Dock	N/A	Concrete Block Wall		Non Suspect ACM	2790	SF	0	SF					N/A	N/A	N/A
1	1	KWPEA Hallway from ECU/Penn Pod to Loading Dock	M	Floor Tile VAT 12" x 12"	1160/01/01/DD	Assumed	2814	SF	0	SF	Multi				1	No	1/D
1	1	KWPEA Hallway from ECU/Penn Pod to Loading Dock	M	Transite Sills	1160/01/01/AA	Confirmed	1	SF	0	SF			Fire Extinguisher Sill		1	No	1/D
1	1	KWPEA Hallway from ECU/Penn Pod to Loading Dock	M	Transite	1160/01/01/AA	Assumed	14	SF	0	SF			panel above display case		1	No	1/D
1	1	KWPEA Hallway from ECU/Penn Pod to Loading Dock	M	Fiberglass Pipe Insulation	1160/01/01/BATTA/WG/2611	Confirmed	330	LF	0	LF			Covered with positive textured ceiling paint. Please verify if the paint present is the same as the textured ceiling paint.		1	No	1/D
1	1	KWPEA Hallway from ECU/Penn Pod to Loading Dock	M	Fiberglass Pipe Fitting Insulation	1160/01/01/BATTA/WG/2611	Confirmed	42	EA	0	EA			Covered with positive textured ceiling paint. Please verify if the paint present is the same as the textured ceiling paint.		1	No	1/D
1	1	Hallway around Cafeteria	N/A	Ceiling Tile 2' x 4'		Non Suspect ACM	4080	SF	0	SF					N/A	N/A	N/A
1	1	Hallway around Cafeteria	N/A	Concrete Block Wall		Non Suspect ACM	8360	SF	0	SF					N/A	N/A	N/A
1	1	Hallway around Cafeteria	M	Floor Tile VAT 12" x 12"	1160/01/01/DD	Assumed	4080	SF	0	SF	Brown				1	No	1/D
1	1	Hallway around Cafeteria	M	Transite	1160/01/01/AA	Confirmed	30	SF	0	SF			Board above display case		1	No	1/D
2	1	Head Start Office / Main Hallway	S	Textured Ceiling Paint	1160/01/01/03	Confirmed	882	SF	0	SF					1	No	1/D
2	1	Head Start Office / Main Hallway	N/A	Terrazzo Floors		Non Suspect ACM	882	SF	0	SF					N/A	N/A	N/A

1160 Motivation HS/KIPP West @ Turner - 2015-2016 AHERA Three-Year Report.xls

		School District of Philadelphia Motivation High School and KIPP Turner West Middle School 5900 Baltimore Avenue, Philadelphia, PA 19143 ULCS# 1160 Year Built: 1969		AHERA Three-Year Reinspection 2015-2016 Room by Room Location Log Report							Reinspection Date: 9/29/15						
											Building Inspector: William Garrity, Jr.						
											Number: 70016699A						
											Management Planner: Mary Anne Lerro						
											Number: 740728						
E I S I T E	F L O O R	On Site Room Name		System Affected	Material Description	HID#	Confirmed/Assumed/NAD/ Non Suspect ACM	Amount of Material	SF LF EA	Amount of Damage	SF LF EA	Color required for VAT	Comments/Description/Notes	Attic/ Crawl Space Ranking	Damage Potential (DP)	Newly Friable (NF)	Response Action (RA)
		2	1	Head Start Office / Main Hallway	N/A	Sheetrock Wall			Non Suspect ACM	1608	SF	0	SF				N/A
2	1	Head Start Office / Main Hallway	N/A	Fiberglass Pipe Fitting Insulation			Non Suspect ACM	11	EA	0	EA				N/A	N/A	N/A
2	1	Head Start Office / Main Hallway	N/A	Fiberglass Pipe Insulation			Non Suspect ACM	90	LF	0	LF				N/A	N/A	N/A
2	1	Head Start Office / Main Hallway	M	Vinyl Vibration Damper Cloth	1160/01/01/10		Assumed	6	SF	0	SF				1	No	1/D
2	1	Head Start Office / Main Hallway	M	Transite Sills	1160/02/01/BATTA/WG/2300		Confirmed	1	SF	0	SF		Fire Extinguisher Sill		1	No	1/D
2	1	Head Start Classroom 2	S	Textured Ceiling Paint	1160/01/01/03		Confirmed	720	SF	0	SF				1	No	1/D
2	1	Head Start Classroom 2	N/A	Terrazzo Floors			Non Suspect ACM	720	SF	0	SF				N/A	N/A	N/A
2	1	Head Start Classroom 2	N/A	Sheetrock Wall			Non Suspect ACM	1188	SF	0	SF				N/A	N/A	N/A
2	1	Head Start Classroom 2	N/A	Fiberglass Pipe Insulation			Non Suspect ACM	50	LF	0	LF				N/A	N/A	N/A
2	1	Head Start Classroom 2	N/A	Fiberglass Pipe Fitting Insulation			Non Suspect ACM	2	EA	0	EA				N/A	N/A	N/A
2	1	Storage Room across from Head Start Room 2	S	Textured Ceiling Paint	1160/01/01/03		Confirmed	90	SF	0	SF				1	No	1/D
2	1	Storage Room across from Head Start Room 2	N/A	Terrazzo Floors			Non Suspect ACM	90	SF	0	SF				N/A	N/A	N/A
2	1	Storage Room across from Head Start Room 2	N/A	Sheetrock Wall			Non Suspect ACM	304	SF	0	SF				N/A	N/A	N/A
2	1	Head Start Classroom 1	S	Textured Ceiling Paint	1160/01/01/03		Confirmed	720	SF	0	SF				1	No	1/D
2	1	Head Start Classroom 1	N/A	Terrazzo Floors			Non Suspect ACM	720	SF	0	SF				N/A	N/A	N/A
2	1	Head Start Classroom 1	N/A	Sheetrock Wall			Non Suspect ACM	1188	SF	0	SF				N/A	N/A	N/A
2	1	Head Start Classroom 1	N/A	Fiberglass Pipe Insulation			Non Suspect ACM	90	LF	0	LF				N/A	N/A	N/A
2	1	Head Start Classroom 1	N/A	Fiberglass Pipe Fitting Insulation			Non Suspect ACM	2	EA	0	EA				N/A	N/A	N/A
2	1	Small Head Start Mechanical Room	M	Vibration Damper Cloth	1160/01/01/10		Assumed	10	SF	0	SF				1	No	1/D
2	1	Small Head Start Mechanical Room	S	Textured Ceiling Paint	1160/01/01/03		Confirmed	90	SF	0	SF				1	No	1/D
2	1	Small Head Start Mechanical Room	N/A	Terrazzo Floors			Non Suspect ACM	90	SF	0	SF				N/A	N/A	N/A
2	1	Small Head Start Mechanical Room	N/A	Sheetrock Wall			Non Suspect ACM	304	SF	0	SF				N/A	N/A	N/A
2	1	Large Head Start Mechanical Room	N/A	Concrete Ceiling			Non Suspect ACM	286	SF	0	SF				N/A	N/A	N/A
2	1	Large Head Start Mechanical Room	N/A	Concrete Block Wall			Non Suspect ACM	568	SF	0	SF				N/A	N/A	N/A
2	1	Large Head Start Mechanical Room	N/A	Cement Floor			Non Suspect ACM	286	SF	0	SF				N/A	N/A	N/A
2	1	Large Head Start Mechanical Room	N/A	Fiberglass Pipe Insulation			Non Suspect ACM	70	LF	0	LF				N/A	N/A	N/A
2	1	Large Head Start Mechanical Room	N/A	Fiberglass Pipe Fitting Insulation			Non Suspect ACM	10	EA	0	EA				N/A	N/A	N/A
2	1	Hallway between Head Start Large Mechanical Room and Girl's Restroom	S	Textured Ceiling Paint	1160/01/01/03		Confirmed	590	SF	0	SF				1	No	1/D
2	1	Hallway between Head Start Large Mechanical Room and Girl's Restroom	N/A	Terrazzo Floors			Non Suspect ACM	590	SF	0	SF				N/A	N/A	N/A
2	1	Hallway between Head Start Large Mechanical Room and Girl's Restroom	N/A	Sheetrock Wall			Non Suspect ACM	1518	SF	0	SF				N/A	N/A	N/A
2	1	Hallway between Head Start Large Mechanical Room and Girl's Restroom	N/A	Unit Ventilator Insulation			NAD	24	SF	0	SF				N/A	N/A	N/A
2	1	Hallway from Head Start Large Mechanical Room to Girl's Restroom	M	Transite Sills	1160/02/01/BATTA/WG/2300		Confirmed	1	SF	0	SF		Fire Extinguisher Sill		1	No	1/D
2	1	Head Start Kitchen	M	Floor Tile VAT 12" x 12"	1160/02/01/BATTA/WG/2000		Assumed	270	SF	0	SF	Tan			1	No	1/D
2	1	Head Start Kitchen	N/A	Ceiling Tile 2' x 4'			Non Suspect ACM	270	SF	0	SF				N/A	N/A	N/A
2	1	Head Start Kitchen	N/A	Concrete Block Wall			Non Suspect ACM	660	SF	0	SF				N/A	N/A	N/A
2	1	Head Start Kitchen	N/A	Fiberglass Pipe Fitting Insulation			Non Suspect ACM	2	EA	0	EA				N/A	N/A	N/A
2	1	Head Start Kitchen	N/A	Fiberglass Pipe Insulation			Non Suspect ACM	20	LF	0	LF				N/A	N/A	N/A
2	1	Head Start Kitchen Locker Room	N/A	Concrete Block Wall			Non Suspect ACM	260	SF	0	SF				N/A	N/A	N/A
2	1	Head Start Kitchen Locker Room	N/A	Fiberglass Ceiling Tile 2' x 4'			Non Suspect ACM	40	SF	0	SF				N/A	N/A	N/A
2	1	Head Start Kitchen Locker Room	N/A	Cement Floor			Non Suspect ACM	40	SF	0	SF				N/A	N/A	N/A
2	1	Head Start Kitchen Restroom	N/A	Ceramic Tile Floors			Non Suspect ACM	35	SF	0	SF				N/A	N/A	N/A
2	1	Head Start Kitchen Restroom	N/A	Ceramic Tile Walls			Non Suspect ACM	120	SF	0	SF				N/A	N/A	N/A
2	1	Head Start Kitchen Restroom	N/A	Plaster Ceiling			NAD	35	SF	0	SF				N/A	N/A	N/A
2	1	Hallway from Head Start Girl's Restroom to Kitchen	M	Floor Tile VAT 12" x 12"	1160/02/01/BATTA/WG/2004		Assumed	280	SF	0	SF	Grey			1	No	1/D
2	1	Hallway from Head Start Girl's Restroom to Kitchen	N/A	Ceiling Tile 2' x 4'			Non Suspect ACM	280	SF	0	SF				N/A	N/A	N/A
2	1	Hallway from Head Start Girl's Restroom to Kitchen	N/A	Concrete Block Wall			Non Suspect ACM	860	SF	0	SF				N/A	N/A	N/A
2	1	Hallway from Head Start Girl's Restroom to Kitchen	M	Transite Sills	1160/02/01/BATTA/WG/2300		Confirmed	1	SF	0	SF		Fire Extinguisher Sill		1	No	1/D
2	1	Head Start Girl's Restroom	N/A	Ceramic Tile Floors			Non Suspect ACM	154	SF	0	SF				N/A	N/A	N/A
2	1	Head Start Girl's Restroom	N/A	Concrete Block Wall			Non Suspect ACM	500	SF	0	SF				N/A	N/A	N/A
2	1	Head Start Girl's Restroom	N/A	Plaster Ceiling			NAD	154	SF	0	SF				N/A	N/A	N/A
2	1	Head Start Boy's Restroom	N/A	Ceramic Tile Floors			Non Suspect ACM	110	SF	0	SF				N/A	N/A	N/A
2	1	Head Start Boy's Restroom	N/A	Concrete Block Wall			Non Suspect ACM	420	SF	0	SF				N/A	N/A	N/A
2	1	Head Start Boy's Restroom	N/A	Plaster Ceiling			NAD	110	SF	0	SF				N/A	N/A	N/A
2	1	Hallway from Head Start Girl's Restroom to Boy's Restroom	S	Textured Ceiling Paint	1160/01/01/03		Confirmed	540	SF	0	SF				1	No	1/D
2	1	Hallway from Head Start Girl's Restroom to Boy's Restroom	N/A	Terrazzo Floors			Non Suspect ACM	540	SF	0	SF				N/A	N/A	N/A
2	1	Hallway from Head Start Girl's Restroom to Boy's Restroom	N/A	Sheetrock Wall			Non Suspect ACM	856	SF	0	SF				N/A	N/A	N/A
2	1	Hallway from Head Start Girl's Restroom to Boy's Restroom	N/A	Wood Panel Walls			Non Suspect ACM	800	SF	0	SF				N/A	N/A	N/A
2	1	Main Gymnasium	N/A	Wood Floor			Non Suspect ACM	10680	SF	0	SF				N/A	N/A	N/A
2	1	Main Gymnasium	N/A	Concrete Ceiling			Non Suspect ACM	10680	SF	0	SF				N/A	N/A	N/A
2	1	Main Gymnasium	N/A	Concrete Block Wall			Non Suspect ACM	10450	SF	0	SF				N/A	N/A	N/A
2	1	Main Gymnasium	N/A	Partition Room Dividers			Non Suspect ACM	1600	SF	0	SF				N/A	N/A	N/A
2	1	Main Gymnasium	M	Transite Sills	1160/02/01/BATTA/WG/2300		Confirmed	4	SF	0	SF		Fire Extinguisher Sill		1	No	1/D
2	1	Girl's Locker Room	N/A	Cement Floor			Non Suspect ACM	322	SF	0	SF				N/A	N/A	N/A

1160 Motivation HS/KIPP West @ Turner - 2015-2016 AHERA Three-Year Report.xls

		School District of Philadelphia Motivation High School and KIPP Turner West Middle School 5900 Baltimore Avenue, Philadelphia, PA 19143 ULCS# 1160 Year Built: 1969		AHERA Three-Year Reinspection 2015-2016 Room by Room Location Log Report							Reinspection Date: 9/29/15						
											Building Inspector: William Garrity, Jr.						
											Number: 70016699A						
											Management Planner: Mary Anne Lerro						
											Number: 740728						
E I e m e n t	F l o o r	On Site Room Name		System Affected	Material Description	HID#	Confirmed/Assumed/NAD/ Non Suspect ACM	Amount of Material	SF LF EA	Amount of Damage	SF LF EA	Color required for VAT	Comments/Description/Notes	Attic/ Crawl Space Ranking	Damage Potential (DP)	Newly Friable (NF)	Response Action (RA)
		2	1	Girl's Locker Room	N/A	Concrete Block Wall		Non Suspect ACM	460	SF	0	SF					N/A
2	1	Girl's Locker Room	N/A	Concrete Ceiling		Non Suspect ACM	156	SF	0	SF					N/A	N/A	N/A
2	1	Girl's Locker Room	N/A	Ceramic Tile Floors		Non Suspect ACM	340	SF	0	SF					N/A	N/A	N/A
2	1	Girl's Locker Room	N/A	Fiberglass Pipe Fitting Insulation		Non Suspect ACM	32	EA	0	EA					N/A	N/A	N/A
2	1	Girl's Locker Room	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	540	LF	0	LF					N/A	N/A	N/A
2	1	Girl's side Gym Equipment Storage Room	N/A	Concrete Ceiling		Non Suspect ACM	221	SF	0	SF					N/A	N/A	N/A
2	1	Girl's side Gym Equipment Storage Room	N/A	Cement Floor		Non Suspect ACM	221	SF	0	SF					N/A	N/A	N/A
2	1	Girl's side Gym Equipment Storage Room	N/A	Concrete Block Wall		Non Suspect ACM	720	SF	0	SF					N/A	N/A	N/A
2	1	Girl's side Gym Equipment Storage Room	N/A	Fiberglass Pipe Fitting Insulation		Non Suspect ACM	1	EA	0	EA					N/A	N/A	N/A
2	1	Girl's side Gym Equipment Storage Room	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	58	LF	0	LF					N/A	N/A	N/A
2	1	Weight Room	N/A	Wood Floor		Non Suspect ACM	972	SF	0	SF					N/A	N/A	N/A
2	1	Weight Room	N/A	Concrete Block Wall		Non Suspect ACM	1512	SF	0	SF					N/A	N/A	N/A
2	1	Weight Room	N/A	Concrete Ceiling		Non Suspect ACM	972	SF	0	SF					N/A	N/A	N/A
2	1	Weight Room	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	120	LF	0	LF					N/A	N/A	N/A
2	1	Boy's side Gym Equipment Storage Room	N/A	Concrete Ceiling		Non Suspect ACM	286	SF	0	SF			No access F2016 inspection		N/A	N/A	N/A
2	1	Boy's side Gym Equipment Storage Room	N/A	Cement Floor		Non Suspect ACM	286	SF	0	SF			No access F2016 inspection		N/A	N/A	N/A
2	1	Boy's side Gym Equipment Storage Room	N/A	Concrete Block Wall		Non Suspect ACM	840	SF	0	SF			No access F2016 inspection		N/A	N/A	N/A
2	1	Boy's side Gym Equipment Storage Room	N/A	Fiberglass Pipe Fitting Insulation		Non Suspect ACM	14	EA	0	EA			No access F2016 inspection		N/A	N/A	N/A
2	1	Boy's side Gym Equipment Storage Room	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	100	LF	0	LF			No access F2016 inspection		N/A	N/A	N/A
2	1	Boy's side Gym Equipment Storage Room	M	Vibration Damper Cloth	1160/01/01/10	Assumed	6	SF	0	SF			No access F2016 inspection		1	No	1/D
2	1	Boy's Locker Room	N/A	Cement Floor		Non Suspect ACM	322	SF	0	SF					N/A	N/A	N/A
2	1	Boy's Locker Room	N/A	Concrete Block Wall		Non Suspect ACM	460	SF	0	SF					N/A	N/A	N/A
2	1	Boy's Locker Room	N/A	Concrete Ceiling		Non Suspect ACM	156	SF	0	SF					N/A	N/A	N/A
2	1	Boy's Locker Room	N/A	Ceramic Tile Floors		Non Suspect ACM	340	SF	0	SF					N/A	N/A	N/A
2	1	Boy's Locker Room	N/A	Fiberglass Pipe Fitting Insulation		Non Suspect ACM	26	EA	0	EA					N/A	N/A	N/A
2	1	Boy's Locker Room	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	330	LF	0	LF					N/A	N/A	N/A
2	1	Gym Teacher's Office	M	Floor Tile VAT 12' x 12"	1160/02/01/BATTA/WG/2000	Assumed	270	SF	0	SF		Tan			1	No	1/D
2	1	Gym Teacher's Office	N/A	Ceiling Tile 2' x 4'		Non Suspect ACM	270	SF	0	SF					N/A	N/A	N/A
2	1	Gym Teacher's Office	N/A	Concrete Block Wall		Non Suspect ACM	660	SF	0	SF					N/A	N/A	N/A
2	1	Gym Teacher's Office Locker Room	N/A	Concrete Block Wall		Non Suspect ACM	260	SF	0	SF					N/A	N/A	N/A
2	1	Gym Teacher's Office Locker Room	N/A	Fiberglass Ceiling Tile 2' x 4'		Non Suspect ACM	40	SF	0	SF					N/A	N/A	N/A
2	1	Gym Teacher's Office Locker Room	N/A	Cement Floor		Non Suspect ACM	40	SF	0	SF					N/A	N/A	N/A
2	1	Gym Teacher's Office Restroom	N/A	Ceramic Tile Floors		Non Suspect ACM	32	SF	0	SF					N/A	N/A	N/A
2	1	Gym Teacher's Office Restroom	N/A	Ceramic Tile Walls		Non Suspect ACM	240	SF	0	SF					N/A	N/A	N/A
2	1	Gym Teacher's Office Restroom	N/A	Plaster Ceiling		NAD	32	SF	0	SF					N/A	N/A	N/A
2	1	Hallway from Main Building to Gym (KIPP Main Entrance)	N/A	Unit Ventilator Insulation		NAD	27	SF	0	SF					N/A	N/A	N/A
2	1	Hallway from Main Building to Gym (KIPP Main Entrance)	M	Floor Tile VAT 12' x 12"	1160/02/01/BATTA/WG/2000	Assumed	280	SF	0	SF		Tan			1	No	1/D
2	1	Hallway from Main Building to Gym (KIPP Main Entrance)	N/A	Concrete Block Wall		Non Suspect ACM	860	SF	0	SF					N/A	N/A	N/A
2	1	Hallway from Main Building to Gym (KIPP Main Entrance)	N/A	Ceiling Tile 2' x 4'		Non Suspect ACM	280	SF	0	SF					N/A	N/A	N/A
1	A	Attic	X	X		X	X	X	X	X		X	None		X	X	X
1	C	Crawl Space	X	X		X	X	X	X	X		X	None		X	X	X

Section III Certificates

A. Management Planner/Building Inspector Certificates

Section III – A

Management Planner/Building Inspector Certificates

These charts indicate the Name, Course Date, Expiration Date and Corresponding Certificate Number of the Management Planner and Building Inspector of individuals that participated in the AHERA 3 Year Inspection and Management Plan process of 2015/2016.

Management Planner	Date Granted	Expiration Date	Certificate Number
Monique Causley	2/15/2015	2/16/2016	ACC-0215-8-010
Monique Causley	2/16/2016	2/17/2017	ACC-0216-8-001
Megan Vala	5/22/2015	6/22/2016	740728
Mary Anne Lerro	4/5/2016	4/5/2017	742327

Building Inspector	Date Granted	Expiration Date	Certificate Number
Scott Magee	8/15/2015	8/15/2016	70016699C
William Garrity	8/15/2015	8/15/2016	70016699A
Bernard Brunner	10/2/2015	8/2/2016	45397
Mary Anne Lerro	3/3/2015	3/3/2016	740092
Mary Anne Lerro	4/5/2016	4/5/2017	742322
James Madden	12/11/2014	12/11/2015	ACC-1214-6-010
James Madden	12/3/2015	12/3/2016	ACC-1215-6-018
Troy Ray	3/15/2015	3/19/2016	ACC-0355-6-011
Ananth Vinjamuri	9/29/2015	9/29/2016	374
Shelton Williams	9/29/2015	9/29/2016	375
Paul Davis	2/12/2015	2/12/2016	ACC-0215-6-015
Paul Davis	2/2/2016	2/2/2017	741836
Bernard Bryson	2/16/2015	2/16/2016	ACC-0125-6-031
Bernard Bryson	2/15/2016	2/15/2017	ACC-0216-6-005
Alexander Roman	9/18/2015	9/18/2016	EHSBIR-150619-008
Norm Harrison	9/2/2015	9/2/2016	ACC-0915-6-011
Kelly Mayberry	2/20/2015	2/20/2016	EHSBIR-150220-005
Kelly Mayberry	2/18/2016	2/18/2017	EHSBIR-160218-006
Andrew Hine	5/6/2015	5/6/2016	AI05042015-3
Maryellen Leotta	2/12/2015	2/12/2016	ACC-0215-6-024

Certificate of Completion

awarded to

Monique Causley

for successfully completing the prescribed course of study in

**Pennsylvania Asbestos Management Planner
Refresher Course**

under TSCA Title II

presented by

ACCESS TRAINING SERVICES, INC.
7921 River Road, Pennsauken, NJ 08110
(856) 665-3449

2/16/15

Course Date

N/A

Exam Date

2/16/16

Expiration Date

Not Provided

Social Security Number

ACC-0215-8-010

Certificate Number

Mark K. Schlüger
Training Director



Certificate of Completion

awarded to

Monique Causley

for successfully completing the prescribed course of study in

**Pennsylvania Asbestos Management Planner
Refresher Course**

under TSCA Title II

presented by

ACCESS TRAINING SERVICES, INC.
7921 River Road, Pennsauken, NJ 08110
(856) 665-3449

2/15/16

Course Date

N/A

Exam Date

2/15/17

Expiration Date


Not Provided

Social Security Number

ACC-0216-8-001

Certificate Number

Mark K. Schlüger
Training Director



Certificate of Training

CRITERION LABORATORIES, INC.

HEREBY CERTIFIES THAT

Megan Vala

HAS SUCCESSFULLY COMPLETED A 16 HOUR COURSE ENTITLED

Asbestos Management Planner Initial

INCLUDING CLASSROOM INSTRUCTION

05/21/2015 to 05/22/2015

Exam passed on this 22nd day of May 2015 - Score - 94

Approved for AHERA Accreditation Under TSCA Title II

DIRECTOR:



James A. Welts, CIH, President

3370 Progress Drive, Suite J

Bensalem, PA 19020

(215) 244-1300 - Phone

(215) 244-4349 - Fax

www.criterionlabs.com

Course is conducted in English

Certificate of Training

CRITERION LABORATORIES, INC.

HEREBY CERTIFIES THAT

Mary Anne Lerro

HAS SUCCESSFULLY COMPLETED A 4 HOUR COURSE ENTITLED

Asbestos Management Planner Refresher

INCLUDING CLASSROOM INSTRUCTION


on this 5th day of April 2016

Approved for AHERA Accreditation Under TSCA Title II

3370 Progress Drive, Suite J
Bensalem, PA 19020
(215) 244-1300 - Phone
(215) 244-4349 - Fax
www.criterionlabs.com

Course is conducted in English

DIRECTOR:



James A. Welts, CIH, President

EMSL ANALYTICAL, INC.

Certifies that

Scott Magee

has successfully completed the course of study for the

Asbestos Building Inspector Refresher Course

for Accreditation under TSCA Title II

EMSL Certificate No. 70016699C

Approved by:

PA Dept. of Labor and Industry
Accreditation # 137


Course Date: 8/15/2015

Granted: 8/15/2015

Expiration Date: 8/15/2016

Sponsored by:

EMSL Analytical, Inc.
200 Route 130 North
Cinnaminson, NJ 08077
Phone: (800) 220-3675
Fax: (856) 786-5973
www.emsl.com



Michael P. Menz
Michael P. Menz, CIH
Training Director

Environmental, Mold, Bacteria, IAQ, Asbestos, Lead, Forensic and Materials Testing Since 1981

EMSL ANALYTICAL, INC.

Certifies that

William Garrity

has successfully completed the course of study for the

Asbestos Building Inspector Refresher Course

for Accreditation under TSCA Title II


EMSL Certificate No. 70016699A

Approved by:
PA Dept. of Labor and Industry
Accreditation # 137

Course Date: 8/15/2015
Granted: 8/15/2015
Expiration Date: 8/15/2016

Sponsored by:

EMSL Analytical, Inc.
200 Route 130 North
Cinnaminson, NJ 08077
Phone: (800) 220-3675
Fax: (856) 786-5973
www.emsl.com



Michael P. Menz

Michael P. Menz, CIH
Training Director

Environmental, Mold, Bacteria, IAQ, Asbestos, Lead, Forensic and Materials Testing Since 1981

45397

National Asbestos & Environmental Training Institute

CERTIFICATE OF COMPLETION

AHERA/EPA Accredited Per 40 CFR Part 763
Asbestos Accreditation under TSCA Title II

This is to certify that


Bernard Brunner, Jr.

Successfully completed the course entitled

**1/2-Day New York State/EPA/AHERA Asbestos Building Inspector Annual Refresher on
October 2, 2015**

Examination Passed October 2, 2015

Expiration Date on October 2, 2016


Doris I. Adler
President, NAEETI

Per 10 NYCRR Part 73.2 (L) (1), DOH 2832 Certificate of Completion of Asbestos
Safety Training is the only official record of training for N.Y.S. students.

Language: English

ABIH 1/2 CM POINT

3321 Doris Avenue, Building B, Ocean, NJ 07712

Phone (732) 531-5571

Fax (732) 531-5956

www.naeti.com

Number 740092

Expiration Date:
03/03/2016

Certificate of Training

CRITERION LABORATORIES, INC.

HEREBY CERTIFIES THAT

Mary Anne Lerro

HAS SUCCESSFULLY COMPLETED A 4 HOUR COURSE ENTITLED

Asbestos Building Inspector Refresher

on this 3rd day of March 2015

Exam passed on this 3rd day of March 2015 - Score - 84

Approved for AHERA Accreditation Under TSCA Title II

3370 Progress Drive, Suite J
Bensalem, PA 19020
(215) 244-1300 - Phone
(215) 244-4349 - Fax
www.criterionlabs.com

Course is conducted in English

DIRECTOR:


James A. Welch, CIH, President

Certificate of Training

CRITERION LABORATORIES, INC.

HEREBY CERTIFIES THAT

Mary Anne Lerro

HAS SUCCESSFULLY COMPLETED A 4 HOUR COURSE ENTITLED

Asbestos Building Inspector Refresher

INCLUDING CLASSROOM INSTRUCTION

on this 5th day of April 2016

Exam passed on this 5th day of April 2016 - Score - 88

Approved for AHERA Accreditation Under TSCA Title II

3370 Progress Drive, Suite J
Bensalem, PA 19020
(215) 244-1300 - Phone
(215) 244-4349 - Fax
www.criterionlabs.com

Course is conducted in English

DIRECTOR:



James A. Welts, CIH, President

Certificate of Completion

James Madden

for successfully completing the prescribed course of study in

Pennsylvania Asbestos Building Inspector Refresher Course

under TSCA Title II

presented by
ACCESS TRAINING SERVICES, INC.
7921 River Road, Pennsauken, NJ 08110
(856) 665-3449

12/11/14

Course Date

N/A

Exam Date

12/11/15

Expiration Date

Not Provided

Social Security Number

ACC-1214-6-010

Certificate Number

Mark K. Schlüger
Mark K. Schlüger
Training Director

Certificate of Completion

James Madden

for successfully completing the prescribed course of study in

Pennsylvania Asbestos Building Inspector Refresher Course

under TSCA Title II

presented by

ACCESS TRAINING SERVICES, INC.
7921 River Road, Pennsauken, NJ 08110
(856) 665-3449

12/3/15

Course Date

N/A

Exam Date

12/3/16

Expiration Date

Not Provided

Social Security Number

ACC-1215-6-018

Certificate Number

Mark K. Schlüger
Mark K. Schlüger
Training Director

Certificate of Completion

Troy A. Ray

for successfully completing the prescribed course of study in

Pennsylvania Asbestos Building Inspector Refresher Course

under TSCA Title II

presented by

ACCESS TRAINING SERVICES, INC.
7921 River Road, Pennsauken, NJ 08110
(856) 665-3449

3/19/15
Course Date

N/A
Exam Date

3/19/16
Expiration Date

Not Provided
Social Security Number

ACC-0355-6-011
Certificate Number

Mark K. Schlager
Mark K. Schlager
Training Director

CERTIFICATE NO 374

G&C Environmental Services, Inc. (#294)
2 Street Road, Newtown Square, Pennsylvania 19073
Telephone: (610) 993-9202 Facsimile: (610) 993-9232
Email: Training@gcenviro.com
www.GCenviro.com

This document certifies that Ananth K. Vinjamuri has successfully completed this
State of New York Department of Health Approved AHERA BUILDING INSPECTOR

REFRESHER COURSE, completed as required for asbestos accreditation under the Toxic

Substances Control Act, Title II. This course was held from 09/29/2015 to 09/29/2015.
MM DD YR MM DD YR

The examination date was 09/29/2015. This certificate expires one year from the date of
MM DD YR MM DD YR
successful completion of the examination 09/29/2016.
MM DD YR

*The official record of successful training completion is the New York State Department of
Health certificate of asbestos safety training completion (DPH 2832).*

Gail M. Conner
Training Director

Gail M. Conner

CERTIFICATE NO 375

G&C Environmental Services, Inc. (#294)
2 Street Road, Newtown Square, Pennsylvania 19073
Telephone: (610) 993-9202 Facsimile: (610) 993-9232
Email: Training@gcenviro.com
www.GCenviro.com

This document certifies that Shelton Williams has successfully completed this
State of New York Department of Health Approved AHERA BUILDING INSPECTOR

REFRESHER COURSE, completed as required for asbestos accreditation under the Toxic

Substances Control Act, Title II. This course was held from 09/29/2015 to 09/29/2015.

The examination date was 09/29/2015. This certificate expires one year from the date of
successful completion of the examination 09/29/2016.

*The official record of successful training completion is the New York State Department of
Health certificate of asbestos safety training completion (DPH 2832).*

Gail M. Conner
Training Director

Gail M. Conner

Certificate of Completion

Paul M. Davis

for successfully completing the prescribed course of study in

Pennsylvania Asbestos Building Inspector Refresher Course

under TSCA Title II

presented by

ACCESS TRAINING SERVICES, INC.
7921 River Road, Pennsauken, NJ 08110
(856) 665-3449

2/12/15

Course Date

N/A

Exam Date

2/12/16

Expiration Date

Not Provided

Social Security Number

ACC-0215-6-015

Certificate Number


Mark K. Schlüger
Training Director

Certificate of Training

CRITERION LABORATORIES, INC.

HEREBY CERTIFIES THAT

PAUL M. DAVIS

HAS SUCCESSFULLY COMPLETED A 4 HOUR COURSE ENTITLED
Asbestos Building Inspector Refresher

INCLUDING CLASSROOM INSTRUCTION

on this 2nd day of February 2016

Exam passed on this 2nd day of February 2016 - Score - 92

Approved for AHERA Accreditation Under ISCA Title II

DIRECTOR:

James A. Wertz, CIH, President

3370 Progress Drive, Suite J
Bensalem, PA 19020

(215) 244-1300 - Phone

(215) 244-4349 - Fax
www.criterionlabs.com

Course is conducted in English

Certificate of Completion

Bernard J. Bryson

for successfully completing the prescribed course of study in

Pennsylvania Asbestos Building Inspector Refresher Course

under TSCA Title II

presented by

ACCESS TRAINING SERVICES, INC.
7921 River Road, Pennsauken, NJ 08110
(856) 665-3449

2/16/15

Course Date

N/A

Exam Date

2/16/16

Expiration Date

Not Provided

Social Security Number

ACC-0125-6-031

Certificate Number

Mark K. Schlager
Training Director

Certificate of Completion

Bernard J. Bryson

for successfully completing the prescribed course of study in

Pennsylvania Asbestos Building Inspector Refresher Course

under TSCA Title II

presented by

ACCESS TRAINING SERVICES, INC.
7921 River Road, Pennsauken, NJ 08110
(856) 665-3449

2/15/16

Course Date

N/A

Exam Date

2/15/17

Expiration Date

Not Provided

Social Security Number

ACC-0216-6-005

Certificate Number

Mark K. Schlager
Mark K. Schlager
Training Director

EHS TRAINING INSTITUTE, INC.
A Division of BATA, Inc.

Certificate of Completion

AHERA Building Inspector

(Refresher)

Awarded To:

Alexander Roman

SS#:XXX-XX-1743
Who has completed this 4-hour course and examination,
EPA Approved under TSCA Title II
AHERA / ASHARA Rule
40 CFR Part 763.

EHS TRAINING INSTITUTE, INC.
A Division of BATA, Inc.
Delaware Industrial Park • 6 Garfield Way
Newark, DE 19713-5817
(302) 737-3376 • Fax (302) 737-5764

Course Date: **September 18, 2015**
Date of Expiration: **September 18, 201**
Certification Number : **EHSBIR 150619-008**


Todd K. Zeisloff, Instructor


Neeraj K. Batta, President

Certificate of Completion


Norman Harrison

for successfully completing the prescribed course of study in

**Pennsylvania Asbestos
Building Inspector Refresher Course**

under TSCA Title II

presented by
ACCESS TRAINING SERVICES, INC.
7921 River Road, Pennsauken, NJ 08109
(856) 665-3449

9/2/15 <i>Course Date</i>	N/A <i>Exam Date</i>	9/2/16 <i>Expiration Date</i>
Not Provided <i>Social Security Number</i>	ACC-0915-6-011 <i>Certificate Number</i>	 Mark K. Schlager <i>Training Director</i>

EHS TRAINING INSTITUTE, INC.
A Division of BATTI, Inc.

Certificate of Completion

AHERA Building Inspector (Refresher)

Awarded To:
Kelly Mayberry

SS#:XXX-XX-1551
Who has completed this 4-hour course and examination,
EPA Approved under TSCA Title II
AHERA / ASHARA Rule
40 CFR Part 763.

EHS TRAINING INSTITUTE, INC.
A Division of BATTI, Inc.
Delaware Industrial Park • 6 Garfield Way
Newark, DE 19713-5817
(302) 737-3376 • Fax (302) 737-5764

Course Date: February 20, 2015
Date of Expiration: February 20, 2016
Certification Number : EHSBIR 150220-005


Todd K. Zeisloff, Instructor


Neeraj K. Batta, President

EHS TRAINING INSTITUTE, INC.

A Division of BATTI, Inc.

Certificate of Completion

AHERA Building Inspector (Refresher)

Awarded To:

Kelly Mayberry

SS#:XXX-XX-1551

Who has completed this 4-hour course and examination,

EPA Approved under TSCA Title II

AHERA / ASHARA Rule

40 CFR Part 763.

EHS TRAINING INSTITUTE, INC.

A Division of BATTI, Inc.

Delaware Industrial Park • 6 Garfield Way


Newark, DE 19713-5817

(302) 737-3376 • Fax (302) 737-5764

Course Date: February 18, 2016

Date of Expiration: February 18, 2017

Certification Number : EHSBIR 160218-006


Todd K. Zeisloff, Instructor


Neeraj K. Batta, President

AEROSOL MONITORING & ANALYSIS, INC.

This is to certify that
ANDREW HINE

has met the attendance requirements and successfully completed

the course entitled

3-DAY EPA AHERA INSPECTOR

For Accreditation Under TSCA Title II

05/04/2015 to 05/06/2015

Course Date

05/06/2015

Exam Date

5/6/2016

Expiration Date

STEVE STERAGKI

Principal Instructor



A105042015-3

Certification No.

E. Rush Barnett

Course Director



1331 Ashton Road

P.O.Box 646

Hanover, MD 21076

P: 410-684-3327

F: 410-684-3724

www.amatrainig.com

Certificate of Completion

Maryellen Leotta

for successfully completing the prescribed course of study in

Pennsylvania Asbestos Building Inspector Refresher Course

under TSCA Title II

presented by

ACCESS TRAINING SERVICES, INC.
7921 River Road, Pennsauken, NJ 08110
(856) 665-3449

2/12/15

Course Date

N/A

Exam Date

2/12/16

Expiration Date

Not Provided

Social Security Number

ACC-0215-6-024

Certificate Number

Mark K. Schlager
Training Director



Section IV Cross Reference Table

Asbestos Hazard Emergency Response Act (AHERA) Environmental Compliance Audit Cross Reference Table

In response to the AHERA Environmental Compliance Audit a Cross Reference Table has been prepared for inclusion into the Environmental Management Plan. The purpose of this Cross Reference Table is to link the following documents to the AHERA Management Plan.

Cross Reference Table	
3 Year Reinspection Report follows this Cross Reference Table documentation.	
Subject Matter	Location of Required Documents
Designated Person	Pages 1 - 3
Annual Notification	Pages 4 - 5
6 Month Periodic Surveillance Outline of Events	Page 6
3 Year Re-inspections Outline of Events	Page 7
Asbestos Management Program (operations and maintenance)	Pages 8 - 19
Asbestos Investigation Report (AIR)	Attachment 1 Letter Dated August 4, 2006
Training (included in the Asbestos Management Program)	<p>The original records are centralized at the School District's Environmental Library. Copies are maintained on staff and are required to be maintained in the latest Reinspection Report.</p> <p>2 hour awareness training records for all Building Engineers, Custodian Assistants and maintenance personnel</p> <p>40 hour worker/supervisor training records for the OEMS A-Team and various AST tradesmen.</p>
Response Actions (monthly mailings if applicable)	<p>The original documents are on file at the School District's Environmental Library.</p> <p>Copies of the original are mailed to the Schools Main Office for retention with the Management Plan documentation. These documents are typically kept separate from the management plan in an update binder due to the potential volume of response action reports.</p>

SCHOOL DISTRICT OF PHILADELPHIA

ASBESTOS DESIGNATED PERSON

Gerald F Junod
Office of Capital Programs
Environmental Management & Services
440 N Broad Street, 3rd Floor
Philadelphia, PA 19130
Telephone: 215 400 6738
Fax: 215 400 4751

Drexel University- Asbestos Building Inspector Course January 9-11, 1989 24 Hours
Drexel University- Asbestos Management Planner Course January 12-13, 1989 16 Hours
Criterion Laboratories, Inc. - Asbestos Management Planner Course October 11-12, 2012 16 Hours

Annual Building Inspector Refreshers 1990 to Present
4 Hours
Drexel University
Criterion Laboratories, Inc
Access Training Services, Inc.

Annual Building Management Planner Refreshers 1990 to 1994
4 Hours
Drexel University
Criterion Laboratories, Inc 2013 to Present
4 Hours

Environmental Manager, School District of Philadelphia
Manages the design and implementation of asbestos and lead projects for the Capital Improvement Program and other District Departments including Facilities & Operations and Information Technology. Ensures that asbestos abatement and lead remediation projects are expertly designed and executed in accordance with industry best management practice standards and regulations.

Manager, City of Philadelphia Asbestos Control Program
Served as the Asbestos Control Program Manager for the City of Philadelphia, Department of Public Health, Air Management Services, Asbestos Control Unit from August 1, 2003 through October 23, 2006.

Mid Atlantic Regional Environmental Consortium (MAREC)
Former member with attendance and participation commitments of all quarterly EPA Region III and yearly National Asbestos Regulatory Conferences sponsored by the EPA and the National Conference of State Legislators respectively as a representative for the City of Philadelphia Department of Public Health Air Management Services from 1994 through 2006.


Philadelphia Environmental Task Force
Former member of the Philadelphia Environmental Task force as a representative and point of contact for the City of Philadelphia Department of Public Health Air Management Services Asbestos Control Unit from 2002 through 2006.

Asbestos Instructor

Worked as the primary instructor for the initial and annual Asbestos Project Inspector training and licensing program as mandated by City of Philadelphia Department of Public Health Asbestos Control Regulations from August 1994 through October 2006.

Worked as a lead instructor with an Environmental Consulting Firm and approved by the US EPA for the initial and annual refresher training courses for various asbestos occupational disciplines such as the Building Inspector, Management Planner and Worker/Supervisor from 1991 through 1994.

I certify that the general, local agency responsibilities as stipulated in Section 763.84 will be met.



**Gerald F. Junod
Asbestos Designated Person
Environmental Manager
Office of Environmental Management and Services**

SCHOOL DISTRICT OF PHILADELPHIA

Accreditation Information Statement

All persons who inspect for Asbestos Containing Building Materials (ACBM) and who will design or carry out response actions with respect to assumed and confirmed ACBM, will be accredited by an EPA approved course and/or a State Contractors Accreditation Program under Sections 206 (c) and 206 (b) of Title II of the ACT.



Gerald F. Junod
Asbestos Designated Person
Environmental Manager
Office of Environmental Management and Services

SCHOOL DISTRICT OF PHILADELPHIA
OFFICE OF CAPITAL PROGRAMS
440 NORTH BROAD STREET, SUITE 373
PHILADELPHIA, PENNSYLVANIA 19130

OFFICE OF ENVIRONMENTAL MANAGEMENT AND SERVICES

PHONE (215)-400-4750

September 2015

TO: Principals
Building Administrators/Occupants
Parents/Guardians

FROM: Fran Burns
Chief Operating Officer

Francine Locke, M.S., Director
Office of Environmental Management and Services

SUBJECT: Annual EPA Notification Letter

Pursuant to the Federal Environmental Protection Agency (EPA) mandate, as required by 40 C.F.R. 763.84 (c)(d) of public access to environmental records, this letter is to acknowledge the availability of your facility's Asbestos Hazard Emergency Response Act (AHERA) Management Plan.

Each member of the school staff, parents/guardians, temporary workers and/or contractors, are required to receive a copy of the Notification Letter. At the direction of the Principal, a copy is to be posted on the bulletin boards and an appropriate amount of copies are to be generated for distribution.


Note: The AHERA Three-Year Reinspection reports, in colored binders; White with Pink, Tan, Black, Red, Dark Blue, Green, Yellow and White, are Federal EPA mandated inspection documents. The School District of Philadelphia is subject to severe monetary penalties if the reports and associated paperwork are not available to the EPA and the public upon request.

It is incumbent on designated school personnel to gather and retain this data as it is delivered, in one location for future review. Acceptable locations include the Principal's Office or Main Office for the primary data. The Building Engineer should maintain any secondary or duplicate copies.

If you have any questions, please call 215-400-4750. Thank you for your cooperation.



Fran Burns
Chief Operating Officer



Francine Locke, M.S., Director
Office of Environmental Management
and Services

c: Danielle Floyd

AHERA-4
8/21/15



School District of Philadelphia
OFFICIAL NOTICE

PLEASE POST

September 2015

TO: Principals
Building Administrators
Building Engineers
Building Occupants
Parents/Guardians

FROM: Fran Burns
Chief Operating Officer

Francine Locke, M.S., Director
Office of Environmental Management and Services

SUBJECT: Annual Notification Letter: Asbestos Hazard Emergency Response Act

The Federal Register published on October 30, 1987, Subpart E, in Schools: Final Rule and Notice, 763.84 (c)(d) states that each local education agency shall ensure that workers and building occupants or guardians are to be informed at least once each school year about inspections, response actions and post-response action activities including re-inspections and periodic surveillance activities. The School District as the Local Education Agency (LEA), retains such reports that are available for public inspection in the Office of the Principal or Building Administrator.

The Principal or Building Administrator is required to do the following with this notification:

- 1) Post in a Public Place or Main Office
- 2) Inform Building Occupants
- 3) Send a copy of this notification to Parents or Guardians
- 4) Insert a copy into the latest AHERA Three-Year Reinspection report (white/pink binder) in your office or facility.

Handwritten signature of Fran Burns in black ink.

Fran Burns
Chief Operating Officer

Handwritten signature of Francine Locke in black ink.

Francine Locke, M.S., Director
Office of Environmental Management
and Services

c: Danielle Floyd

AHERA-4a
8/21/15

SCHOOL DISTRICT OF PHILADELPHIA
Education Center
440 North Broad Street
Philadelphia, Pennsylvania 19130

Office of Environmental Management and Services

215-400-4750

AHERA
Six Month Surveillance
Outline of Events

- Pursuant to the Federal Environmental Protection Agency (EPA) mandate, as required by 40 CFR 763.92(b), the following procedure is to be implemented. At least once every six (6) months after a Management Plan is in effect, each Local Education Agency (LEA) shall conduct a periodic surveillance in each building that it owns or leases that contains Asbestos Containing Building Materials (ACBM) or is assumed to contain ACBM.
- The first Bi-Annual Inspection starts in the Spring (March, April, May) and again in the Fall (October, November, December) of each year. The Building Engineer/Assistant should assist the Building Inspector with appropriate access to all areas including (Crawlspace/Attics) and rooms in the facility. There is no action required of the Principal.
- The Building Inspector shall visually inspect all areas that are identified in the Management Plan as ACBM or assumed ACBM. The date of the surveillance is recorded, the inspectors name and any changes in the conditions of the materials.
- The Building Inspector shall make a copy of the inspection document and insert into the front of the latest Management Plan (AHERA Three Year Reinspection report). The original document is returned to the LEA's Environmental Library and filed.

SCHOOL DISTRICT OF PHILADELPHIA
Education Center
440 North Broad Street
Philadelphia, Pennsylvania 19130

Office of Environmental Management and Services

215-400-4750

AHERA
Three Year Reinspection
Outline of Events

- Pursuant to the Federal Environmental Protection Agency (EPA) mandate, as required by 40 CFR 763.85(b) the following procedure is to be implemented. At least once every three (3) years after a Management Plan is in effect, each Local Education Agency (LEA) shall conduct a reinspection of each building that it owns or leases that contains Asbestos Containing Building Material's (ACBM's) or is assumed to contain ACBM.
- Subsequent Three Year Re-inspections (2009, 2012, 2015, etc) shall start in the Fall (October, November, December, January). The Building Engineer/Assistant should assist the Building Inspector with appropriate access to all areas including (Crawlspace/Attics) and rooms in the facility. There is no action required of the Principal.
- An accredited Building Inspector shall visually inspect and touch to determine friability, all areas that are identified in the Management Plan as ACBM or assumed ACBM. The date of the surveillance is recorded, the inspectors name and any changes in the conditions of the materials. The Building Inspectors state of accreditation and license number is required.
- After the inspection, the Building Inspector shall make a copy of the inspection documents and insert into the front of the latest Management Plan (AHERA Three Year Reinspection report). The original document is returned to the LEA's Environmental Library and filed.
- The Building Inspector shall return the reinspection data to the Management Planner to be assessed and determine appropriate response actions and a report issued (AHERA Three Year Reinspection report). One copy of the report is delivered to the schools Principal to be permanently retained with all previous environmental data. Another copy is retained in the LEA's Environmental Library.



School District of Philadelphia
Office of Environmental Management & Services
440 North Broad Street
Philadelphia, PA 19130
(215) 400-4750

**School District of Philadelphia
Asbestos Management Program**

TABLE OF CONTENTS

Definitions.....	Page 9
1. Introduction.....	Page 10
2. Summary of Asbestos Management Plan	
3. Asbestos Management Plan Execution.....	Page 11
a. General Execution	
4. Summary of Program Execution	
a. Asbestos Management Plan Execution	
5. Responsibilities	
a. OEMS	
b. Asbestos Worker/Supervisor “A-TEAM”.....	Page 12
c. Asbestos Designated Person	
d. Supervisor or Project Manager (Capital, Maintenance & Facilities)	
e. Employee Capital.....	Page 13
f. Employee Maintenance	
g. Employee Facilities and Custodial	
6. Requirements.....	Page 14
a. Employee Exposure Monitoring	
b. Employee Notification	
c. Observation of Monitoring	
d. Training Program	
e. Access of Information	
f. Record Keeping	
7. AHERA O&M Plan.....	Page 15
a. Controls	
8. O&M Response Actions.....	Page 16
a. Facility Maintenance Isolation of Area	
b. Unlikely Contact with ACM/PACM	
c. Accidental Disturbance of ACM/PACM	
d. Planned Disturbance of ACM/PACM	
e. Miscellaneous ACM/PACM.....	Page 17
f. Vinyl Asbestos Floor Tile	
g. Mastic/Adhesives	
h. Woven Vibration Dampers	
i. Other Work Practices	
j. Fiber Release Episodes	
9. References and Resources.....	Page 18

DEFINITIONS / ACRONYMS

ACM/PACM:	Asbestos Containing Material/Potential Asbestos Containing Material
AHERA:	Asbestos Hazard Emergency Response Act
AIR FORM:	Asbestos Inspection Report Form
Amended Water:	Water to which a surfactant (soap) has been added
AMP:	Asbestos Management Program/Asbestos Management Plan
Asbestos Designate Person:	Individual assigned by the district to oversee asbestos related issues.
Asbestos Regulated Area:	Location that is posted as an asbestos work area in which only approved and accredited personnel are permitted to enter
AST:	Asbestos Support Team involving approved and accredited school district tradespersons personnel that are school district person
A-TEAM:	School District of Philadelphia asbestos workers
CIP:	Capital Improvement Program
Consultant:	Asbestos consulting firm hired by the District
Demolition Directive:	Memorandum – August 4, 2006 from Patrick Henwood
EPA:	Environmental Protection Agency
In House Personnel:	School District of Philadelphia asbestos workers
LEA:	Local Education Agency
O&M:	Operations and Maintenance
OEMS:	Office of Environmental Management and Services
OSHA:	Occupational Safety and Health Administration
PEL:	Permissible Exposure Limit
PSD or SDP:	Philadelphia School District/School District of Philadelphia
PSIT:	Philadelphia School Improvement Team
STEL:	Short Term Exposure Limit

1. Introduction

The School District of Philadelphia, Asbestos Policy Statement:

“The School District of Philadelphia is dedicated to providing a safe and healthful work environment for its employees, students, faculty, contractors and visitors. In recognition of the potential health problems associated with asbestos, the School District of Philadelphia is committed to a comprehensive asbestos control program. This program is implemented and maintained through the School District of Philadelphia's Office of Environmental Management and Services (OEMS).”

OEMS has the responsibility of establishing procedures for asbestos abatement, asbestos inspection, air monitoring, renovation and demolition activities within all School District of Philadelphia owned or leased facilities.

These procedures are developed to ensure that:

- (1) People are not exposed to significant levels of asbestos fibers
- (2) Asbestos waste is handled and disposed of properly
- (3) Members of the School District of Philadelphia community have access to the Office of Environmental Management and Services for information, assistance, guidance, and interpretation regarding asbestos related matters.
- (4) Members of the School District of Philadelphia community have access to the Asbestos Management Plans as required and outlined in the US EPA AHERA regulations including annual written notification to all parents.
- (5) Compliance with all applicable Federal, State and Local Asbestos Regulations

Requirements outlined in this manual are mandatory in nature where the word “SHALL” is used and are advisory in nature where the word “SHOULD” is used.

2. Summary of Asbestos Management Program

The School District of Philadelphia's Asbestos Management Program was established to meet the requirements of Federal, State, and Local Regulations.

These regulations include, but are not limited to:

- US Environmental Protection Agency Asbestos Hazard Emergency Response Act (US EPA AHERA) and National Emissions Standard for Hazardous Air Pollutants subpart M, Part 61 (NESHAP);
- US Department of Labor, Occupational Safety and Health Administration (OSHA) General Industry Standard (29 CFR 1910.1001) and the OSHA Asbestos Standard for the Construction Industry (29 CFR 1926.1101);
- The Commonwealth of Pennsylvania, Department of Labor and Industry, Asbestos Occupations, Accreditation and Certification Act;
- The City of Philadelphia, Department of Public Health, Asbestos Control Regulations.

3. Asbestos Management Program Execution

a) General Execution

The Office of Environmental Management and Services (OEMS) develops, implements and manages safety and health programs for the School District of Philadelphia faculty, staff and students and assists with ensuring that all contractors comply with Federal, State and Local Environmental Regulations. The OEMS provides the oversight of School District of Philadelphia employees (Asbestos A-Team), environmental consultants, and asbestos abatement contractors for all projects within the School District of Philadelphia concerning Asbestos Containing Materials.

The control of safety and health hazards at the School District of Philadelphia is primarily through the implementation of engineering, work practice and administrative controls. Personal Protective Equipment (PPE) is used to supplement these controls or whenever the controls are not feasible or are in the process of being implemented. PPE is also recommended whenever exposures to chemical, physical or biological agents can be prevented or reduced by its use.

This written program establishes the procedures necessary to:

- 1) meet established standards and federal regulations for occupational exposure to asbestos fibers;
- 2) meet the requirements of the City of Philadelphia Asbestos Control Regulations which encompasses the disturbance and/or abatement of asbestos containing building materials;
- 3) provide the necessary health and safety protection to the School District of Philadelphia staff, faculty, students, contractors and visitors.

This program is strengthened by input and cooperation with the Philadelphia Federation of Teachers (PFT), Health and Welfare Fund.

4. Summary of Program Execution

a) Asbestos Management Program Execution

The Asbestos Management Program is administered by the Office of Environmental Management and Services (OEMS). OEMS provides the following services primarily through professional consultants:

- (1) exposure monitoring services;
- (2) building inspection/surveys (bulk sampling) for the identification of asbestos containing materials;
- (3) asbestos project design services;
- (4) asbestos abatement project and air monitoring services;
- (5) emergency response to fiber release episodes;
- (6) education/information;
- (7) medical monitoring;
- (8) training for School District of Philadelphia personnel

5. Responsibilities

a) Office of Environmental Management and Services

OEMS is responsible for performing the following functions:

- (1) Developing and administering of the Asbestos Management Program.
- (2) Providing asbestos-related services to all School District of Philadelphia departments.
- (3) Conducting required training of the Asbestos Management Program and working jointly with departments to schedule training.
- (4) Identifying and posting areas where labeling/signage are required.
- (5) Medical Monitoring of OEMS "A-TEAM" and other departments "AST" Asbestos Program staff.

- (6) Certification and training as required for OEMS "A-TEAM" and other departments "AST" Asbestos program staff.
- (7) Record keeping as outlined in Section 3.5 and all records as by required by US EPA AHERA regulations.

b) Asbestos Worker/Supervisor - "A-TEAM"

- (1) OEMS shall ensure that all "A-TEAM" workers/supervisors adhere to the following requirements:
 - a) Attend an initial Worker/Supervisor Asbestos Course;
 - b) Maintain the annual re-certification per EPA AHERA requirements and Commonwealth of Pennsylvania Asbestos Occupations, Accreditation and Certifications Act;
 - c) Undergo an annual Asbestos Medical Evaluation;
 - d) Undergo an annual Respirator Medical Clearance;
 - e) Undergo an annual Respirator Fit Testing.

c) Asbestos Designated Person

The Asbestos Designated Person is responsible for:

- (1) Assuring the health and safety of employees, students and visitors in the School District of Philadelphia facilities under his/her control.
- (2) Being kept informed of all areas under his or her jurisdiction where potential asbestos exposures exist and initiating protection programs that adhere to the Asbestos Management Program requirements of this manual.
- (3) Assuring that Asbestos Management Program requirements are adhered to by principal investigators, project managers, supervisors, or division heads, and School District of Philadelphia personnel under their supervision.
- (4) Ensuring that all employees within the Asbestos Management Program comply with (OSHA 1910.1001 (j) (7) (iv)) and the US EPA AHERA regulations by attending the required training.
- (5) Ensure the posting of:
 - a) Warning labels/signage
 - b) Commonwealth of Pennsylvania Asbestos Abatement and Demolition/Renovation Notification form
 - c) Asbestos Inspection Reports (AIR) form (where required)
 - d) Ensuring that Construction Projects follow the Demolition Directive procedures as outlined in the August 4, 2006 letter.

d) Supervisor or Project Manager (Capital, Maintenance and Facilities)

Each person in charge of a project, maintenance/repair, renovation/demolition, or other activity from the Departments of Capital, Maintenance, and/or Facilities, where asbestos containing material may be present is responsible for:

Identifying, with the assistance of OEMS, asbestos containing building materials prior to any disturbance of these materials. Various Federal (EPA and OSHA) and Local (City of Philadelphia Asbestos Control Regulations) require Asbestos Inspections prior to renovation/demolition activities. This shall be accomplished by always following the Asbestos Management Program Procedures as follows:

- (1) Ensure that the requirements of the Asbestos Management Program Procedures are followed by all personnel, trades, and contractors who are involved with the project;

- (2) Review of the required Asbestos Inspection Report (AIR) form (Attachment 1) and AHERA Management Plan documents prior to activities that may disturb any Asbestos Containing Materials;
- (3) Perform all project related duties as outlined in the Project Management Responsibilities;
- (4) Keep the department chairperson or director informed on any actions proposed or taken regarding the Asbestos Management Plan;
- (5) Ensuring that Construction Projects follow the Demolition Directive procedure outlined in the August 4, 2006 letter.

e) Employee – Capital

School District of Philadelphia Capital employees and/or consultants shall:

- (1) Ensure that no suspect or asbestos containing building materials are disturbed in the course of the projects they are performing or managing. This shall be accomplished by notifying their supervisor and OEMS by issuance of a work order permit (a.k.a PSIT Service Request Form) and verifying that the materials which may be disturbed are non-asbestos containing. If this information is not available or verification has not been made, these materials should not be disturbed.
- (2) Immediately notify OEMS and their supervisor in the event of a potential fiber release episode upon discovery of visible damage to asbestos containing materials.
- (3) Ensuring that Construction Projects follow the Demolition Directive procedures as outlined in the August 4, 2006 letter.

The types of projects represented as part of the Capital Improvement Program are as follows:

- (1) Complete Renovation of an existing building that addresses all facility component concerns and educational program needs;
- (2) Major Renovation of an existing building addressing significant facility component and educational improvements;
- (3) Addition to an existing building (either as an attachment or stand-alone structure) to accommodate needed program space;
- (4) Conversion of an existing facility to accommodate a change in educational program;
- (5) Facility Component Improvement of specific facility needs (i.e. electrical or HVAC system upgrades, ADA improvements, life safety improvements, exterior renovations, etc.)

f) Employee – Maintenance

School District of Philadelphia Maintenance employees shall:

- (1) Ensure that no suspect or asbestos containing building materials are disturbed in the course of their duties or work they are performing. This shall be accomplished by notifying their supervisor and OEMS by issuance of a work order permit and verifying that the materials which may be disturbed are non-asbestos containing. If this information is not available or verification has not been made, these materials should not be disturbed.
- (2) Immediately notify OEMS and their supervisor in the event of a potential fiber release episode or upon discovery of visible damage to asbestos containing materials.
- (3) All employees involved in maintenance activities shall attend required Asbestos Awareness training program within 60 days of employment.

g) Employee – Facilities & Custodial

School District of Philadelphia Facilities and Custodial employees shall:

- (1) Ensure that no suspect or asbestos containing building materials are disturbed in the course of their duties or work they are performing. This shall be accomplished by notifying their supervisor and OEMS by issuance of a work permit and verifying that the materials which may be disturbed are non-asbestos containing. If this information is not available or verification has not been made, these materials should not be disturbed;
- (2) Immediately notify OEMS and their supervisor in the event of a potential fiber release episode or upon discovery of visible damage to asbestos containing materials.
- (3) All employees involved in Facilities and Custodial activities shall attend require Asbestos Awareness training program within 60 days of employment.

6. Requirements

a) Employee Exposure Monitoring

When information indicates that an employee's exposure to asbestos fibers may equal or exceed an 8-hour time-weighted average of 0.1 f/cc * (per OSHA 1910.1001 & 1926.1101), OEMS shall develop and implement an asbestos exposure monitoring program. The sampling strategy shall be designed to identify employees by work task (job classification) that is exposed to asbestos fibers that exceed an 8-hour time-weighted average of 0.1 f/cc.

b) Employee Notification

OEMS shall notify in writing, each employee exposed to asbestos fibers at or above an 8-hour time weighted average of 0.1 f/cc.

c) Observation and Monitoring

OEMS shall provide employees or their representatives with an opportunity to observe any exposure measurements conducted.

d) Training Program

OEMS shall institute a training program which meets the requirements of AHERA for all employees who perform maintenance operations in a facility/school which contains asbestos containing materials or presumed asbestos containing materials and 1910.1001 (j), and the Commonwealth of Pennsylvania Department of Labor and Industry and the City of Philadelphia Asbestos Control Regulations. The affected departments shall ensure employee participation in this program. The OEMS "A-TEAM" and other departments "AST" Asbestos Program staff training shall be conducted annually for each employee as required by all Federal, State and Local for each asbestos discipline.

All Asbestos Awareness training as required by AHERA shall be performed within 60 days of employment and shall include:

- Health effects of asbestos
- Locations of ACM and PACM in the building/facility
- Recognition of CM and PACM damage and deterioration
- Requirements of the OSHA 1910.1001 standard relating to maintenance
- Proper response to fiber release episodes
- Procedure to be followed to isolate areas affected by fiber release

e) Access to Information

OEMS shall make available to affected employees or their representative's copies of the Occupational Safety and Health Administration (OSHA) General Industry Standard Part 1910.1001 and the department shall post a copy in the workplace.

f) Record Keeping

OEMS shall maintain an accurate record of all employee exposure measurements. OEMS and/or the School District of Philadelphia Human Resources Department shall maintain records of employee medical monitoring program. OEMS shall maintain all employee training records. All records shall be provided upon request to employees, former employees, representatives designated by the individual employee.

7. AHERA OPERATIONS AND MAINTENANCE PLAN

a) CONTROLS

i. Work Order System

Minimizing disruption of ACM/PACM during maintenance and renovation activities is the primary goal and task encountered by OEMS. Operations and maintenance employees and contractors should be warned to avoid conducting any maintenance work which may disturb ACM/PACM. Initiating a work order system, where all work orders or requests are channeled through the Office of Environmental Management and Services (OEMS), will be the method used to control and minimize disruption of ACM/PACM.

Any work performed by in-house personnel or contractors that could or will impact ACM/PACM shall be coordinated by OEMS. A completed Asbestos Inspection Report Form (Attachment 1) shall be issued to in-house personnel and/or all contractors whose work could impact ACM/PACM. This form should accompany each contract issued to an outside contractor and posted on the jobsite.

All work order requests for maintenance and renovation activities in areas where ACM/PACM is suspected or known to be present are to be submitted to OEMS prior to proceeding with work. OEMS is responsible for reviewing asbestos survey records for information about the presence of ACM/PACM in the area where the work is to be performed. OEMS should physically inspect the area to ensure existing records reflect actual conditions. If no asbestos is present, a work order is not necessary and the planned actions can proceed. If ACM/PACM is found to be present in the area, OEMS will sign the work order application and obtain an approved and accredited asbestos contractor or assign OEMS "A-TEAM" to abate the ACM/PACM.

ii. Regulated Areas

The owner will identify and regulate all areas where airborne concentrations of ACM/PACM exceed the Permissible Exposure Limit (PEL)* (Per OSHA determined to be 0.1 f/cc) and/or short term exposure limit (STEL) (Per OSHA determined to be 0.1 f/cc), or there is reasonable possibility that the (PEL) and/or (STEL) may be exceeded. All ACM/PACM removal activities involving thermal system insulation ACM/PACM (Class I), surfacing ACM/PACM (Class I), and miscellaneous ACM/PACM such as floor tile, roofing, and siding mastic, etc. (Class II), and repair and maintenance operations where thermal system insulation and surfacing ACM/PACM is likely to be disturbed (Class III) will be performed in accordance with federal, state, and local regulations. All asbestos abatement work and activities will be designed and managed as asbestos regulated areas. These areas will be demarcated and labeled.

iii. Warning Signs

Warning signs shall be displayed at all approaches to each asbestos regulated area. The asbestos abatement contractor will provide OSHA warning signs in all regulated areas during removal, repair, and other maintenance activities. OEMS will provide AIRs to all contractors who must inform all employees and supervisors working in locations contiguous to asbestos regulated areas of the potential hazards and work practices required.

iv. Warning Labels

Warning labels and/or signage shall be affixed to all raw materials, mixtures, scrap, waste, debris, and other products containing asbestos fibers, or to their containers. Generally, the asbestos abatement contractor or OEMS A-Team personnel will provide all warning labels for ACM/PACM containment.

8. O & M RESPONSE ACTIONS

The Asbestos Management Program general O&M procedures are outlined in this section. Additional requirements specific to asbestos abatement activities are included in the Project Design documents for all Asbestos Abatement Work. Regular cleaning, inspection, and reporting of ACM/PACM deterioration or other problems must be diligently practiced by all employees including custodial and maintenance personnel.

a) Facility Maintenance Isolation of Area Responsibilities

Maintenance personnel are often required to work in areas where ACM/PACM may potentially be disturbed. Most maintenance activities are conducted by in-house staff, outside contractors, or a combination.

Emergency fiber release episodes, such as pipe fitting or valve breaks, emergency boiler work, or mechanical equipment repair will be responded to by OEMS A-Team personnel or asbestos abatement contractor personnel. The owner's maintenance staff will: (1) isolate the emergency fiber release area; (2) post warning signs to prevent unauthorized access, and (3) notify their supervisor and OEMS. OEMS will ensure that the fiber release area remains isolated and is properly cleaned by and approved and accredited abatement contractor or by OEMS A-TEAM personnel.

b) Unlikely Contact with ACM/PACM

Maintenance activities or repairs which can be performed without contacting or disturbing the ACM/PACM require little more than normal care and good workmanship. For example, valves which are either uncovered or covered with non-asbestos insulation can be packed or repaired without disturbing asbestos insulation on nearby pipes. The major precaution is to ensure that maintenance and custodial personnel are familiar with procedures such as isolating the area, posting warning signs, and notifying OEMS in the event of any accidental ACM/PACM disturbance.

c) Accidental Disturbance of ACM/PACM

Maintenance and facilities personnel shall notify OEMS any time a fiber release is suspected. If friable ACM/PACM becomes airborne in the building,

d) Planned Disturbance of ACM/PACM

Maintenance activities that may impact ACM/PACM include access to a valve, flange, duct, or related system component.

Where asbestos-containing insulation must be removed to maintain or repair the thermal system, the ACM/PACM will imminently be disturbed. ACM/PACM removal work shall be conducted by OEMS A-Team personnel or an approved and accredited asbestos abatement contractor.

If friable ACM/PACM becomes airborne in the building, maintenance and facilities personnel shall secure the area and contact OEMS. OEMS shall respond accordingly.

e) Miscellaneous ACM/PACM

Miscellaneous types of ACM/PACM may include vinyl asbestos floor tiles, mastics/adhesives and woven vibration dampers. Disturbance of these materials should be avoided. Routine maintenance activities involving these materials should not pose a problem if handled properly. Questions on the proper removal and disposal of miscellaneous ACM/PACM should be directed to OEMS. OEMS will contact an approved and accredited asbestos abatement contractor or utilize OEMS A-TEAM personnel to assist with miscellaneous ACM/PACM clean-up activities.

f) Vinyl Asbestos Floor Tile

Asbestos-containing floor tiles in good condition are considered non-friable unless they are crushed, drilled, sawed, sanded or disturbed by any activity that breaks up the material. Routine maintenance of these materials should employ the use of non-abrasive buffers and wet cleaning technique. Broken or loose floor tiles should be removed and disposed of as asbestos waste by OEMS. Remaining debris should be vacuumed with a HEPA vacuum and the area wet mopped using amended water.

g) Mastics/Adhesives

Mastics and adhesives containing asbestos in good condition are considered non-friable and do not pose a potential health concern unless crushed, drilled, sawed, sanded, or otherwise abraded. Questions on the proper removal should be directed to OEMS.

h) Woven Vibration Dampers

Woven vibration dampers in good condition are considered non-friable and do not pose a potential health concern unless cut, crushed, drilled, sawed, sanded, or otherwise abraded. Questions on the proper removal should be directed to OEMS.

i) Other Work Practices

Any special work not included in this section should be addressed to OEMS for review prior to the initiation of work that may involve the disturbance of ACM/PACM.

j) Fiber Release Episodes

Facilities and maintenance staff should report to OEMS the presence of asbestos debris, water or physical damage to ACM/PACM, or any other evidence of possible fiber release. OEMS should have the OEMS A-Team personnel or an approved and accredited abatement contractor respond to the site to clean up debris and make repairs as soon as possible. OEMS will also contact a consultant to conduct air monitoring and prepare a report and submit at project completion to OEMS for each episode. OEMS will forward the reports for each site location AHERA Management Plan accordingly.

9. REFERENCES and RESOURCES

Applicable regulations for asbestos projects impacted by renovation, demolition, and maintenance activities.

- **Philadelphia Air Management Services – Asbestos Control Unit**
<http://www.phila.gov/health/units/ams/Asbestos/asbestos.html>
- **Pennsylvania Asbestos Occupations, Accreditation and Certification Act**
<http://www.dli.state.pa.us/landi/cwp/view.asp?a=185&q=56262&landiNav=>
- **United States Environmental Protection Agency Asbestos Home Page**
<http://www.epa.gov/asbestos/>
- **Occupational Safety and Health Administration (OSHA) Asbestos Home**
<http://www.osha.gov/SLTC/asbestos>