									School	District	t of Phil	adelphi	а									
								Le	ad Safe C	Certification	on Asses	sment Re	port									
										r Arthur E			•									
Na	me of Inspector: Ananth	K. Vinjamu	uri						0110010	. Attion E		y conce						Inspec	tion Dates: 6/10-6	6/14/2019		
	pection Company: Crite																	ULCS#				
E I E F M I E O N O	On-Site Room Name	Student/ Teacher Occupied	Primary	Substrate Material	Color	Description of Primary	Primary Component Damage	XRF Reading	Primary Component XRF (positive/	Additional	Substrate Material	Color	Description of Paint and Plaster	Additional Component Damage	XRF Reading	Additional Component XRF (positive/	Debris Present (describe	Quantity	Contents Need to be	On-going Moisture Intrusion	Plastering Needed	Comments/ Description/
t r Fu	el Oil Tank and Fuel Oil Pump	(yes/no)	Component			Damage	Quantity (sf)	(mg/cm2)	negative)	Component			Damage	Quantity (sf)	(mg/cm2)	negative)	location)	(sf)			(yes or no)	Notes
1 BS	Room in Boiler Room el Oil Tank and Fuel Oil Pump	no	W1	Concrete	Grey/White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	\vdash
1 BS	Room in Boiler Room	no	W2	Concrete	Grey/White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	\vdash
1 BS	el Oil Tank and Fuel Oil Pump Room in Boiler Room	no	W3	Concrete	Grey	Flaking, Efflorescence	10	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 BS Fu	el Oil Tank and Fuel Oil Pump Room in Boiler Room	no	W3	Concrete	White	Flaking, Efflorescence	10	0.01	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
Fu	el Oil Tank and Fuel Oil Pump											,		,								
	Room in Boiler Room el Oil Tank and Fuel Oil Pump	no	W4	Concrete	Grey/White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 BS	Room in Boiler Room el Oil Tank and Fuel Oil Pump	no	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 BS	Room in Boiler Room	no	Floor	Concrete	Grey	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 BS S	torage Room next to Fuel Oil Tank Room	no	W1	Concrete	Blue	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 BS S	torage Room next to Fuel Oil Tank Room	no	W2	Concrete	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
S	torage Room next to Fuel Oil											,										
1 BS S	Tank Room torage Room next to Fuel Oil	no	W3	Concrete	Green	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	\vdash
1 BS	Tank Room torage Room next to Fuel Oil	no	W4	Concrete	Blue	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 BS S	Tank Room torage Room next to Fuel Oil	no	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 BS	Tank Room Boiler Room	no	Floor W1	Concrete	Grey	None	5	N/A	N/A	N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	0	No	No	no	
1 BS	Boiler Room Boiler Room	no no	W1 W2	Cinderblock	Grey Grey	Flaking Flaking	10	0.05	Negative Negative	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	0	No No	No No	no no	\vdash
1 BS	Boiler Room	no	W3	Concrete	Grey	Flaking	10	0.03	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 BS	Boiler Room	no	W4	Concrete	Grey	Flaking	15	0.16	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 BS	Boiler Room Boiler Room	no	W4	Concrete	White White	Flaking	15	0.08 N/A	Negative	N/A N/A	N/A	N/A	N/A N/A	N/A N/A	N/A N/A	N/A	N/A N/A	0	No No	No No	no	_
1 BS	Boiler Room	no no	Ceiling	Concrete	Grey	None Cracking	20	0.12	N/A Negative	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A	0	No	No	no no	\vdash
1 BS	Boiler Room	no	Floor	N/A	N/A	N/A	N/A	N/A	N/A	Tank Support Pad	Concrete	Grey	Flaking	20	0.08	Negative	N/A	0	No	No	no	
1 BS	Boiler Room	no	Floor	N/A	N/A	N/A	N/A	N/A	N/A	Generator Support Pad	Concrete	Green	Flaking	10	0.14	Negative	N/A	0	No	No	no	
1 BS	Electrical Room	no	W1	Cinderblock	White/Grey	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 BS	Electrical Room	no	W2	Cinderblock	White/Grey	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	\vdash
1 BS	Electrical Room Electrical Room	no no	W3 W4	Cinderblock	White/Grey White/Grey	None None	0	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	0	No No	No No	no no	\vdash
1 BS	Electrical Room	no	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 BS	Electrical Room	no	Floor	Concrete	Grey	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 BS	Gymnasium	yes	W1	Cinderblock	Blue/White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 BS	Gymnasium Gymnasium	yes	W2 W3	Cinderblock	Blue/White Blue	None Flaking	5	N/A 0.06	N/A Negative	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	0	No No	No No	no no	Upper wall
1 BS	Gymnasium	yes	W3	Concrete	White	Flaking	5	0.04	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	Lower wall
1 BS	Gymnasium	yes	W4	Cinderblock	Blue/White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 BS	Gymnasium	yes	Ceiling	Concrete	White	None	0	N/A N/A	N/A	N/A	N/A	N/A White	N/A	N/A 3	N/A	N/A	N/A N/A	0	No	No	no	\vdash
1 BS	Gymnasium Gymnasium	yes	Ceiling	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	Ductwork N/A	Metal N/A	N/A	Flaking N/A	N/A	0.07 N/A	Negative N/A	N/A N/A	0	No No	No No	no no	9" Floor Tile
	Stairwell in Gym near Girl's Restroom	yes	W1	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	1 20 20 20
	Stairwell in Gym near Girl's Restroom	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door	Wood	Brown	Flaking	4	0.02	Negative	N/A	0	No	No	no	
	Stairwell in Gym near Girl's Restroom	yes	W2	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
	Stairwell in Gym near Girl's Restroom	yes	W3	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 BS	Stairwell in Gym near Girl's Restroom	yes	W4	Concrete	Yellow	Friction	3	0.07	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 BS	Stairwell in Gym near Girl's Restroom	yes	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 BS	Stairwell in Gym near Girl's Restroom	ves	Floor	Concrete	Grev	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 BS	Girl's Restroom in Gym	yes	W1	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 BS	Girl's Restroom in Gym	yes	W2	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 BS	Girl's Restroom in Gym Girl's Restroom in Gym	yes	W3 W4	Cinderblock Cinderblock	Yellow	None None	0	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	0	No No	No No	no	\vdash
1 BS	Girl's Restroom in Gym	yes yes	VV4 Ceiling	Plaster	White	None	0	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	0	No No	No No	no no	\vdash
1 BS	Girl's Restroom in Gym	yes	Floor	Concrete	Grey	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 BS	Boy's Restroom in Gym	yes	W1	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	\vdash
1 BS	Boy's Restroom in Gym	yes	W2	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	

									School	District	t of Phil	adelphi	а									
								Le		Certification			•									
	Name of Inspector: Ananth	K Viniamı	ıri						Cneste	r Arthur E	ementar	у Бспооі						Inspec	tion Dates: 6/10- 6	3/14/2019		
	nspection Company: Crite																	ULCS#		#1-#2010		
E I e F m I e o		Student/ Teacher				Description	Primary Component		Primary Component XRF	Additional	Substrate		Description of Paint and	Additional Component		Additional Component XRF	Debris Present			On-going	Plastering	Comments/
n o t r	On-Site Room Name	Occupied (yes/no)	Primary Component	Substrate Material	Color	of Primary Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	(positive/ negative)	Component	Material	Color	Plaster Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	(positive/ negative)	(describe location)	Quantity (sf)	Contents Need to be Moved	Moisture Intrusion	Needed (yes or no)	Description/ Notes
1 BS	Boy's Restroom in Gym Boy's Restroom in Gym	yes yes	W3 W4	Cinderblock Cinderblock	Yellow	None None	0	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	0	No No	No No	no no	
1 BS	Boy's Restroom in Gym	yes	Ceiling	Plaster	White	Flaking	2	0.02	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 BS	Boy's Restroom in Gym	yes	Floor	Concrete	Grey	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 BS	Former Kitchen/Storage Room in Gym	yes	W1	Cinderblock	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 BS	Former Kitchen/Storage Room in Gym	yes	W2	Cinderblock	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 BS	Former Kitchen/Storage Room in Gym	yes	W3	Concrete	White	Flaking, Efflorescence	10	0.09	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 BS	Former Kitchen/Storage Room in Gym	yes	W4	Concrete	White	Flaking, Efflorescence	10	0.03	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 BS	Former Kitchen/Storage Room in Gym	yes	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 BS	Former Kitchen/Storage Room in Gym	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	12" Floor Tile
1 BS	Stairs near Kitchen from Gym to Hallway	yes	W1	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 BS	Stairs near Kitchen from Gym to Hallway	yes	W2	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 BS	Stairs near Kitchen from Gym to Hallway	yes	W3	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 BS	Stairs near Kitchen from Gym to Hallway	yes	W4	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 BS	Stairs near Kitchen from Gym to Hallway	yes	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 BS	Stairs near Kitchen from Gym to Hallway	ves	Floor	Concrete	Grev	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 BS	Gym Storage Room in Far Corner	yes	W1	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
	Gym Storage Room in Far Corner	yes	W2	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
	Gym Storage Room in Far Corner	yes	W3	Cinderblock	Yellow	Friction	3	0.06	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	Bottom
	Gym Storage Room in Far Corner Gym Storage Room in Far Corner	yes yes	W3 W4	Cinderblock Cinderblock	Brown Yellow	Flaking Flaking	4 15	0.05	Negative Negative	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	0	No No	No No	no no	Course
1 RS	Gym Storage Room in Far Corner	yes	W4	Cinderblock	Brown	Flaking	6	0.07	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	Bottom course
	Gym Storage Room in Far Corner	yes	Ceiling	Plaster	White	Cracking	6	0.02	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	course
1 BS	Gym Storage Room in Far Corner	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	9" Floor Tile
1 BS 1 BS	Gym Coat Room Gym Coat Room	yes	W1 W2	Cinderblock Cinderblock	Blue/White Blue/White	None None	0	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	0	No No	No No	no no	
1 BS	Gym Coat Room	yes	W3	Concrete	Blue/White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 BS	Gym Coat Room	yes	W3	Concrete	Brown	Flaking	5	0.14	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	Bottom course
1 BS	Gym Coat Room Gym Coat Room	yes	W4	Concrete	Blue/White	None	0	0.14 N/A	N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A	N/A N/A	N/A N/A	N/A N/A	0	No No	No No	no	course
1 BS	Gym Coat Room	yes	Ceiling	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 BS	Gym Coat Room Gym Storage Room near Gym	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	9" Floor Tile
1 BS	Office Gym Storage Room near Gym	yes	W1	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 BS	Office Gym Storage Room near Gym	yes	W2	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 BS	Office Gym Storage Room near Gym	yes	W3	Concrete	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 BS	Office Gym Storage Room near Gym	yes	W4	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 BS	Office Gym Storage Room near Gym	yes	Ceiling	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 BS	Office Restroom and Shower located in	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	9" Floor Tile
1 BS	Gym Office Restroom and Shower located in	yes	W1	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 BS	Gym Office Restroom and Shower located in	yes	W2	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 BS	Gym Office Restroom and Shower located in	yes	W3	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 BS	Gym Office Restroom and Shower located in	yes	W4	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 BS	Gym Office Restroom and Shower located in	yes	Ceiling	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 BS	Gym Office	yes	Floor	Concrete	Grey	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 BS	Gym Office	yes	W1	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 BS 1 BS	Gym Office Gym Office	yes yes	W2 W3	Cinderblock Concrete	Yellow Yellow	None None	0	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	0	No No	No No	no no	
1 BS	Gym Office	yes	W4	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	

									School	l Distric	t of Phil	adelphi	а									
								Le	ad Safe C	Certification	on Asses	sment Re	port									
										r Arthur E			•									
	Name of Inspector: Ananth	h K Viniamı	uri						Cileste	Aithui	lemema	y School						Inenec	tion Dates: 6/10-6	1/14/2019		
	Inspection Company: Crit																	ULCS#		// 1-1/2010		
Ę																						
e F m I e o n o t r		Student/ Teacher Occupied	Primary	Substrate		Description of Primary	Primary Component Damage	XRF Reading	Primary Component XRF (positive/	Additional	Substrate		Description of Paint and Plaster	Additional Component Damage	XRF Reading	Additional Component XRF (positive/	Debris Present (describe	Quantity	Contents Need to be	On-going Moisture	Plastering Needed	Comments/ Description/
1 BS	On-Site Room Name Gym Office	(yes/no) yes	Component	Material Plaster	Color White	Damage None	Quantity (sf)	(mg/cm2) N/A	negative) N/A	Component N/A	Material N/A	Color N/A	Damage N/A	Quantity (sf) N/A	(mg/cm2) N/A	negative) N/A	location) N/A	(sf) 0	Moved No	Intrusion No	(yes or no)	Notes
1 BS	Gym Office	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 BS		yes	W1	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 BS		yes	W2 W3	Concrete	Yellow	None	0	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	0	No No	No No	no no	-
1 BS		yes	W4	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 BS		yes	Ceiling	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 BS		yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	9" Floor Tile
1 BS	Fan Room located over Gym Girl's and Boy's Restrooms and the Former Kitchen	no	W1	Cinderblock	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	No paint
	Fan Room located over Gym Girl's and Boy's Restrooms and the				Ĺ	<u> </u>	ĺ				,		ĺ	,	,	<u> </u>						
1 BS	Fan Room located over Gym Girl's and Boy's Restrooms and the	no	W2	Cinderblock	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	No paint
1 BS	Former Kitchen Fan Room located over Gym Girl's and Boy's Restrooms and the	no	W3	Cinderblock	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	No paint
1 BS	Former Kitchen Fan Room located over Gym Girl's	no	W4	Cinderblock	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	No paint
1 BS	and Boy's Restrooms and the Former Kitchen Fan Room located over Gym Girl's	no	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	No paint
1 BS	and Boy's Restrooms and the Former Kitchen	no	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	No paint
1 BS	Stairwell near Gym Office	yes	W1	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 BS	Stairwell near Gym Office	yes	W2	Cinderblock	Yellow	None Flaking,	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 BS		yes	W3	Cinderblock	Yellow	Efflorescence	20	0.3	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 BS		yes	W4	Cinderblock	Yellow White	None None	0	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	0	No No	No No	no	
1 BS		yes	Ceiling	Concrete	Grey	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no no	
1 BS	Hallway near Gym Office to Main	yes	W1	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 BS	Hallway near Gym Office to Main	yes	W2	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 BS	Hallway near Gym Office to Main		W3	Cinderblock			0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No No	No No		
П	Basement Hallway Hallway near Gym Office to Main	yes			Yellow	None	0	.,,	,		,	.,,		,				0			no	
1 BS	Basement Hallway Hallway near Gym Office to Main Basement Hallway	yes	W4 Ceiling	Cinderblock	Yellow	None	0	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	0	No No	No No	no no	
1 BS	Hallway near Gym Office to Main Basement Hallway	yes	Floor	Concrete	Grey	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 BS	Custodial Closet in Hallway near Gym Office	no	W1	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 BS		no	W2	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 BS	Custodial Closet in Hallway near Gym Office Custodial Closet in Hallway near	no	W3	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 BS	Gym Office Custodial Closet in Hallway near	no	W4	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 BS	Custodial Closet in Hallway near	no	Ceiling	Concrete	White	None	0	N/A	N/A	N/A N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A N/A	0	No No	No No	no	Ol Floor T''
1 BS	Gym Office Storage Room at end of Main Hallway	no	Floor W1	N/A Cinderblock	N/A N/A	N/A	N/A	N/A	N/A N/A	N/A N/A	N/A	N/A N/A	N/A N/A	N/A	N/A	N/A	N/A N/A	0	No No	No No	no	9" Floor Tile
1 BS	Storage Room at end of Main	no	W1 W2	Cinderblock	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	0	No No	No No	no	No Paint No Paint
1 BS	Storage Room at end of Main	no	W2 W3	Cinderblock	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	0	No No	No No	no	No Paint No Paint
1 BS	Storage Room at end of Main	no	W4	Cinderblock	N/A N/A	N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	0	No	No	no	No Paint
1 BS	Storage Room at end of Main Hallway	no	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	No Paint
1 BS	Storage Room at end of Main Hallway	no	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	No Paint
1 BS		no	W1	Cinderblock	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	No Paint
1 BS		no	W2	Cinderblock	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	No Paint
1 BS	Storage Room at end of Main Hallway near Boiler Room Door	no	W3	Cinderblock	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	No Paint

									School	Distric	t of Phil	adelphi	ia									
								Le	ead Safe (Certificati	on Asses	sment Re	eport									
									Cheste	r Arthur E	Elementai	y School	l									
	Name of Inspector: Ananth																		tion Dates: 6/10- 6	/14/2019		
-	Inspection Company: Crite	erion Labs,	Inc.															ULCS#	2480			
e F m I e o n o t r	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)	Additional Component	Substrate Material	Color	Description of Paint and Plaster Damage	Additional Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Additional Component XRF (positive/ negative)	Debris Present (describe location)	Quantity (sf)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Comments/ Description/ Notes
1 BS	Storage Room at end of Main Hallway near Boiler Room Door	no	W4	Cinderblock	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	No Paint
П	Storage Room at end of Main					<u> </u>	<u> </u>	,		N/A	,			,				0			no	
1 BS	Storage Room at end of Main	no	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A		N/A	N/A	N/A	N/A	N/A	N/A	N/A		No	No	no	No Paint
1 BS 1 BS		no no	Floor W1	Concrete Cinderblock	N/A Blue/Yellow	N/A None	N/A 0	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	0	No No	No No	no no	No Paint
1 BS	Building Engineer's Office	no	W2	Cinderblock	Blue/Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 BS 1 BS		no	W3 W4	Cinderblock Cinderblock	Blue/Yellow	None None	0	N/A N/A	N/A	N/A N/A	N/A	N/A	N/A	N/A	N/A N/A	N/A N/A	N/A N/A	0	No No	No No	no	
1 BS		no no	Ceiling	Concrete	Blue/Yellow White	None	0	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	0	No No	No No	no no	
1 BS	Building Engineer's Office	no	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	9" Floor Tile
1 BS	Building Engineer's Office Restroom and Shower Building Engineer's Office	no	W1	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 BS	Restroom and Shower	no	W2	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 BS	Building Engineer's Office Restroom and Shower	no	W3	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 BS	Building Engineer's Office Restroom and Shower	no	W4	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
	Building Engineer's Office																					No ceiling - Open to the B.E. Office
1 BS	Restroom and Shower Building Engineer's Office	no	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	Ceiling
1 BS	Restroom and Shower Hallway from Health Room to	no	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	9" Floor Tile
1 BS	Storage Rooms and along Building Engineer's Office	yes	W1	Cinderblock	White/Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
	Hallway from Health Room to Storage Rooms and along Building																					
1 BS	Engineer's Office Hallway from Health Room to Storage Rooms and along Building	yes	W2	Cinderblock	White/Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 BS	Engineer's Office Hallway from Health Room to Storage Rooms and along Building	yes	W3	Cinderblock	White/Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 BS	Engineer's Office Hallway from Health Room to Storage Rooms and along Building	yes	W4	Cinderblock	White/Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 BS	Engineer's Office Hallway from Health Room to Storage Rooms and along Building	yes	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 BS	Engineer's Office Hallway from Stairs near Health	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	9" Floor Tile
1 BS	Room to Elevator Hallway from Stairs near Health	yes	W1	Cinderblock	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 BS	Room to Elevator Hallway from Stairs near Health	yes	W2	Cinderblock	White/Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 BS	Room to Elevator Hallway from Stairs near Health	yes	W3	Cinderblock	White	Flaking	4	0.28	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	Upper Wall
1 BS	Room to Elevator Hallway from Stairs near Health	yes	W4	Cinderblock	White/Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 BS	Room to Elevator Hallway from Stairs near Health	yes	Ceiling	Concrete	White	Flaking	4	0.03	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 BS	Room to Elevator Health Room across from Building Engineer's Office	yes yes	Floor W1	N/A Cinderblock	N/A Blue/Yellow	N/A None	N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	0	No No	No No	no no	9" Floor Tile
1 BS	Health Room across from Building Engineer's Office	yes	W2	Cinderblock	Blue/Yellow	None	0	N/A N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A N/A	0	No No	No	no	
1 BS	Health Room across from Building	yes	W2 W3	Cinderblock	Blue/Yellow	None		N/A	N/A	N/A N/A	N/A N/A	N/A N/A	N/A	N/A N/A	N/A	N/A	N/A N/A	0	No No	No No	no	
1	Engineer's Office Health Room across from Building	,			,	1	_	.,	1,4,1,		.,,	.,			.,							
1 BS	Engineer's Office Health Room across from Building Engineer's Office	yes	W3 W3	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	Columns	Concrete	Yellow	Flaking	2	0.07	Negative Negative	N/A N/A	0	No No	No No	no	
1 BS	Health Room across from Building Engineer's Office	yes	W4	Cinderblock	Blue/Yellow	None	.4	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
	Health Room across from Building Engineer's Office	ves	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	1' x1' Ceiling T
1 BS	Health Room across from Building	,	1		N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No			
1 1	Engineer's Office Room 108 School Store Office	yes yes	Floor W1	N/A Cinderblock	N/A Yellow	N/A None	N/A 0	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	0	No No	No No	no no	9" Floor Tile
1 1	Room 108 School Store Office	yes	W2	Cinderblock	Yellow	Flaking	5	0.01	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 1		yes	W3 W4	Cinderblock Cinderblock	Yellow Yellow	None None	0	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	0	No No	No No	no no	
11.		,	1						1			1	1 .4/11			1						

									School	l Distric	t of Phil	adelphi	a									
								L.e		Certification												
										r Arthur E												
	Name of Inspector: Ananth								2.10010			,							tion Dates: 6/10- 6	/14/2019		
E	Inspection Company: Crite	erion Labs,	Inc.															ULCS#	2480			
e F m I e o n o t r	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)	Additional Component	Substrate Material	Color	Description of Paint and Plaster Damage	Additional Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Additional Component XRF (positive/ negative)	Debris Present (describe location)	Quantity (sf)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Comments/ Description/ Notes
1 1	Room 108 School Store Office	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	1' x1' Ceiling Tile
1 1	Room 108 School Store Office Room 107 Security Surveillance	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	9" Floor Tile
1 1	Room	yes	W1	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 1	Room 107 Security Surveillance Room	yes	W2	Cinderblock	Yellow	Flaking	10	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 1	Room 107 Security Surveillance Room	yes	W3	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 1	Room 107 Security Surveillance Room	yes	W4	Cinderblock	Yellow	Flaking	4	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 1	Room 107 Security Surveillance Room	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	1' x1' Ceiling Tile
1 1	Room 107 Security Surveillance Room	ves	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	9" Floor Tile
1 1	Auditorium	yes	W1	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	9 FIOUI THE
1 1	Auditorium Auditorium	yes	W1 W1	N/A N/A	N/A N/A	N/A N/A	0	N/A N/A	N/A N/A	Columns	Concrete Concrete	Yellow Brown	Cracking Cracking	3	0.04	Negative Negative	N/A N/A	0	No No	No No	no no	Bottom
1 1	Auditorium	yes	W2	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 1	Auditorium Auditorium	yes yes	W3 W4	Cinderblock Wood	Yellow Tan	None None	0	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	0	No No	No No	no no	
1 1	Auditorium	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	1' x1' Ceiling Tile
1 1	Auditorium Auditorium Stage	yes yes	Floor W1	N/A Cinderblock	N/A Yellow	N/A None	N/A 0	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	0	No No	No No	no no	9" Floor Tile
1 1	Auditorium Stage	yes	W2	Cinderblock	Yellow	None	0	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	0	No	No	no	
1 1	Auditorium Stage Auditorium Stage	yes yes	W3 W4	Cinderblock Cinderblock	Yellow Yellow	None None	0	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	0	No No	No No	no no	
1 1	Auditorium Stage	yes	Ceiling	Concrete	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 1	Auditorium Stage Stairwell next to Stage Area	yes yes	Floor W1	N/A Cinderblock	N/A Green	N/A Flaking	N/A 5	N/A 0.02	N/A Negative	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	0	No No	No No	no no	9" Floor Tile
1 1	Stairwell next to Stage Area	yes	W2	Cinderblock	Green	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 1	Stairwell next to Stage Area Stairwell next to Stage Area	yes yes	W3 W4	Cinderblock Cinderblock	Green Green	None None	0	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	0	No No	No No	no no	
1 1	Stairwell next to Stage Area	yes	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 1	Stairwell next to Stage Area Stairwell No. 4 near rear Auditorium and Main Entrance to School Building	yes	Floor W1	Concrete	N/A Yellow	None	0	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	0	No No	No No	no	
1 1	Stairwell No. 4 near rear Auditorium and Main Entrance to School Building	yes	W2	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
	Stairwell No. 4 near rear Auditorium and Main Entrance to School	,									,	,			<u> </u>	,						
1 1	Building Stairwell No. 4 near rear Auditorium and Main Entrance to School	yes	W3	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 1	Building Stairwell No. 4 near rear Auditorium and Main Entrance to School	yes	W4	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 1	Building Stairwell No. 4 near rear Auditorium and Main Entrance to School	yes	Ceiling	Concrete	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 1	Building Hallway between Auditorium and	yes	Floor	Concrete	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 1	Main Office Hallway between Auditorium and	yes	W1	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	—
1 1	Main Office Hallway between Auditorium and	yes	W2	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	—
1 1	Main Office Hallway between Auditorium and	yes	W3	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	<u> </u>
1 1	Main Office	yes	W4	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	11 v11 Collin-
1 1	Hallway between Auditorium and Main Office Hallway between Auditorium and	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	1' x1' Ceiling Tile
1 1	Main Office Women's Restroom between	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	9" Floor Tile
1 1	Auditorium and Main Office Women's Restroom between	yes	W1	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 1	Auditorium and Main Office Women's Restroom between	yes	W2	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	<u> </u>
1 1	Auditorium and Main Office Women's Restroom between	yes	W3	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 1	Auditorium and Main Office	yes	W4	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	1

									School	Distric	t of Phil	adelphi	а									
								Le	ead Safe C	Certificati	on Asses	sment Re	port									
									Cheste	r Arthur E	Elementa	rv School	_ -									
	Name of Inspector: Ananth	n K. Vinjamı	uri									,						Inspect	tion Dates: 6/10- 6	/14/2019		
	Inspection Company: Crit	erion Labs,	Inc.															ULCS#	2480			
E F m I e o n o t r	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)	Additional Component	Substrate Material	Color	Description of Paint and Plaster Damage	Additional Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Additional Component XRF (positive/ negative)	Debris Present (describe	Quantity (sf)	Contents Need to be	On-going Moisture Intrusion	Plastering Needed (ves or no)	Comments/ Description/ Notes
1 1	Women's Restroom between Auditorium and Main Office	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	1' x1' Ceiling Tile
ш	Women's Restroom between							,	<u> </u>													
1 1	Auditorium and Main Office Men's Restroom between	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	12" Floor Tile
1 1	Auditorium and Main Office	yes	W1	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 1	Men's Restroom between Auditorium and Main Office	yes	W2	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 1	Men's Restroom between Auditorium and Main Office	yes	W3	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 1	Men's Restroom between		10/4	Cindothlook	Vollaus	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No		
++	Auditorium and Main Office Men's Restroom between	yes	W4	Cinderblock	Yellow	None		N/A	N/A	N/A	N/A	T	N/A	N/A	N/A	,	N/A		No	No	no	
1 1	Auditorium and Main Office Men's Restroom between	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	1' x1' Ceiling
1 1	Auditorium and Main Office	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	12" Floor Tile
1 1	Stairwell No. 3 by Rear Door of School Building	yes	W1	Cinderblock	Green	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 1	Stairwell No. 3 by Rear Door of School Building	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door	Metal	Green	Flaking	1	0.04	Negative	N/A	0	No	No	no	
	Stairwell No. 3 by Rear Door of					1.,	.,	.,	14,11				1									
1 1	School Building Stairwell No. 3 by Rear Door of	yes	W2	Cinderblock	Green	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 1	School Building Stairwell No. 3 by Rear Door of	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A	Stair stringer	Concrete	Green	Flaking	2	0.02	Negative	N/A	0	No	No	no	
1 1	School Building	yes	W3	Cinderblock	Green	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 1	Stairwell No. 3 by Rear Door of School Building	yes	W4	Cinderblock	Green	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 1	Stairwell No. 3 by Rear Door of School Building	1400	Cailing	Concrete	White	None	_	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
H	Stairwell No. 3 by Rear Door of	yes	Ceiling					,	1			<u> </u>		.,	1	.,						
1 1	School Building Classroom 100	yes yes	Floor W1	Concrete Cinderblock	N/A Yellow	None None	0	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	0	No No	No No	no no	
1 1	Classroom 100	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	Brown	Scratched	4	0.13	Negative	N/A	0	No	No	no	
1 1	Classroom 100 Classroom 100	yes	W1 W2	N/A Cinderblock	N/A Yellow	N/A None	N/A 0	N/A N/A	N/A N/A	Locker Door N/A	Metal N/A	Brown N/A	Scratched N/A	4 N/A	0.13 N/A	Negative N/A	N/A N/A	0	No No	No No	no no	
1 1		yes	W2	N/A	N/A	N/A	N/A	N/A	N/A	Columns	Concrete	Yellow	Flaking	1	0.01	Negative	N/A	0	No	No	no	
1 1	Classroom 100	yes	W3	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 1	Classroom 100 Classroom 100	yes yes	W4 W4	Wood N/A	Tan N/A	None N/A	0 N/A	N/A N/A	N/A N/A	N/A Beam	N/A Concrete	N/A White	N/A Cracking	N/A 3	N/A 0.02	N/A Negative	N/A N/A	0	No No	No No	no no	
1 1	Classroom 100	yes	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 1	Classroom 100 Classroom 102	yes	Floor W1	N/A Cinderblock	N/A Yellow	N/A None	N/A 0	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	0	No No	No No	no no	12" Floor Tile
1 1	Classroom 102	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door	Wood	Brown	Scratched	2	0	Negative	N/A	0	No	No	no	
1 1	Classroom 102 Classroom 102	yes	W1 W2	N/A Cinderblock	N/A Vellow	N/A None	N/A	N/A	N/A N/A	Door Frame N/A	Metal N/A	Brown N/A	Scratched N/A	2 N/A	0.01	Negative	N/A N/A	0	No No	No	no	
1 1		yes yes	W3	Wood	Yellow Tan	None None	0	N/A N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A N/A	N/A N/A	N/A	0	No No	No No	no no	
1 1	Classroom 102 Classroom 102	yes	W4 W4	Cinderblock N/A	Yellow N/A	None	0 N/A	N/A N/A	N/A N/A	N/A	N/A	N/A	N/A	N/A	N/A 0.01	N/A	N/A N/A	0	No No	No No	no	
1 1	Classroom 102 Classroom 102	yes yes	W4 Ceiling	N/A Concrete	N/A White	N/A None	N/A 0	N/A N/A	N/A N/A	Columns N/A	Concrete N/A	Yellow N/A	Flaking N/A	1 N/A	0.01 N/A	Negative N/A	N/A N/A	0	No No	No No	no no	
1 1	Classroom 102	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	12" Floor Tile
1 1	Faculty Lounge Faculty Lounge	yes yes	W1 W2	Cinderblock Cinderblock	Green Green	None None	0 0	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	0	No No	No No	no no	
1 1	Faculty Lounge	yes	W3	Cinderblock	Green	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 1	Faculty Lounge Faculty Lounge	yes	W4 Ceiling	Cinderblock N/A	Green N/A	None N/A	N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	0	No No	No No	no no	1' x1' Ceiling
1 1	Faculty Lounge	yes yes	Floor	N/A N/A	N/A	N/A N/A		N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A N/A	N/A	0	No No	No	no	12" Floor Tile
1 1	· esamy · resim eterage	yes	W1	Cinderblock	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 1	Faculty Room Storage Faculty Room Storage	yes yes	W2 W3	Cinderblock Cinderblock	White White	None None		N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	0	No No	No No	no no	
1 1	Faculty Room Storage	yes	W4	Cinderblock	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 1	Faculty Room Storage Faculty Room Storage	yes	Ceiling	Concrete N/A	White N/A	None N/A	0 N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	0	No No	No No	no no	9" Floor Tile
1 1	Classroom 104	yes	W1	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 1	Classroom 104 Classroom 104	yes	W2 W2	Cinderblock N/A	Yellow N/A	None N/A	N/A	N/A N/A	N/A N/A	N/A Columns	N/A Concrete	N/A Yellow	N/A Flaking	N/A	N/A 0.04	N/A Negative	N/A N/A	0	No No	No No	no	
1 1	Classroom 104	yes yes	W3	N/A Cinderblock	Yellow	N/A None		N/A N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A N/A	0	No No	No	no no	
1 1	Classroom 104 Classroom 104	yes	W4	Cinderblock	Yellow	None		N/A	N/A	N/A N/A	N/A	N/A N/A	N/A	N/A N/A	N/A N/A	N/A	N/A N/A	0	No No	No No	no	
1 1	Classroom 104 Classroom 104	yes yes	Ceiling	Concrete N/A	White N/A	Spalling N/A	20 N/A	0.01 N/A	Negative N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	0	No No	No No	no no	9" Floor Tile
	Book 1 Closet across from																					
1 1	Classroom 104	yes	W1	Cinderblock	Green	Efflorescence	20	0.02	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	1

									School	District	of Phil	adelphi	а									
								l e		Certification												
										r Arthur E			port									
	Name of Inspector: Ananth	K. Vinjamu	uri						Oneste	i Aitiiui L	.ieiiieiita	y School						Inspec	tion Dates: 6/10- 6	/14/2019		
	Inspection Company: Crite																	ULCS#				
E F F O O O O O O O O O O O O O O O O O	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)	Additional Component	Substrate Material	Color	Description of Paint and Plaster Damage	Additional Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Additional Component XRF (positive/ negative)	Debris Present (describe location)	Quantity (sf)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Comments/ Description/ Notes
1 1	Book 1 Closet across from Classroom 104	yes	W2	Cinderblock	Green	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 1	Book 1 Closet across from Classroom 104	ves	w3	Cinderblock	Green	Efflorescence	30	0.03	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 1	Book 1 Closet across from Classroom 104	yes	W4	Cinderblock	Green	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
	Book 1 Closet across from																	0				at duct
1 1	Classroom 104 Book 1 Closet across from	yes	Ceiling	Concrete	White	Flaking	4	0.03	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A		No	No	no	penetration
1 1	Classroom 104 Classroom 106	yes	Floor W1	N/A Cinderblock	N/A Yellow	N/A None	N/A 0	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	0	No No	No No	no no	9" Floor Tile
1 1	Classroom 106	yes	W2	Cinderblock	Yellow	None	0	N/A	N/A		N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	Hadasaba'
	Classroom 106	wee	W2	N/A	N/A	N/A	N/A	N/A	N/A	Beam	Concrete	White	Flaking	10	0.02	Negative	N/A	0	No	No	po.	Horizontal Beam near ceiling
1 1	Classroom 106 Classroom 106	yes	W2 W3	N/A Cinderblock	N/A Yellow	N/A None	N/A 0	N/A N/A	N/A N/A	Beam N/A	N/A	N/A	Flaking N/A	10 N/A	0.02 N/A	Negative N/A	N/A N/A	0	No No	No No	no no	
Г																	-					Horizontal Beam near
1 1	Classroom 106 Classroom 106	yes yes	W2 W4	N/A Cinderblock	N/A Yellow	N/A None	N/A 0	N/A N/A	N/A N/A	Beam N/A	Concrete N/A	White N/A	Flaking N/A	5 N/A	0.02 N/A	Negative N/A	N/A N/A	0	No No	No No	no no	ceiling
ΗŤ		,		223101001		1		,	1			***	ļ		1	ļ						Horizontal Beam near
1 1	Classroom 106 Classroom 106	yes	W2	N/A	N/A	N/A	N/A 0	N/A	N/A	Beam	Concrete	White	Flaking	3	0.02	Negative	N/A	0	No	No	no	ceiling
1 1		yes yes	Ceiling Floor	Concrete N/A	White N/A	None N/A	N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	0	No No	No No	no no	9" Floor Tile
1 1	Restroom for Classroom 106 located in the Hallway	yes	W1	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 1	Restroom for Classroom 106 located in the Hallway	yes	W2	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1.	Restroom for Classroom 106						0	N/A		N/A	.,,	N/A	.,		N/A	N/A	N/A	0	No.	No.		
1 1	Restroom for Classroom 106 located in the Hallway	yes	W3 W4	Cinderblock	Yellow	None	0	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A	N/A N/A	N/A N/A	0	No No	No No	no	
1 1	Restroom for Classroom 106	VPS	Ceiling	Concrete	Yellow	Flaking	40	0.01	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No.	No	no	
	Restroom for Classroom 106	,										1,4,1										
1 1	located in the Hallway Girl's Restroom near IMC	yes yes	Floor W1	Concrete Cinderblock	Blue Yellow	None None	0	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	0	No No	No No	no no	-
1 1	Girl's Restroom near IMC Girl's Restroom near IMC	yes	W2	Cinderblock	Yellow	None	_	N/A	N/A		N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No No	No	no	
1 1		yes yes	W3 W4	Cinderblock Cinderblock	Yellow Yellow	None None	0 0	N/A N/A	N/A N/A		N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	0	No No	No No	no no	\vdash
1 1	Girl's Restroom near IMC	yes	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 1	Girl's Restroom near IMC Boy's Restroom near IMC	yes ves	Floor W1	Concrete	Grey Yellow	None None	0	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	0	No No	No No	no no	\vdash
1 1		yes	W2	Cinderblock	Yellow	None		N/A	N/A		N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 1	Boy's Restroom near IMC Boy's Restroom near IMC	yes	W3 W4	Cinderblock	Yellow	None None		N/A	N/A N/A		N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	0	No No	No No	no	\perp
1 1	Boy's Restroom near IMC	yes	Ceiling	Cinderblock	Yellow White	None	0	N/A N/A	N/A		N/A N/A	N/A	N/A	N/A N/A	N/A N/A	N/A	N/A N/A	0	No	No	no no	
1 1	Boy's Restroom near IMC	yes	Floor	Concrete	Grey	None		N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 1	Stairwell No. 1 near Girl's Restroom side	yes	W1	Cinderblock	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 1	Stairwell No. 1 near Girl's Restroom side Stairwell No. 1 near Girl's Restroom	yes	W2	Cinderblock	Green	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 1	side Stairwell No. 1 near Girl's Restroom	yes	W3	Cinderblock	Green	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 1	Stairwell No. 1 near Girl's Restroom side Stairwell No. 1 near Girl's Restroom	yes	W4	Cinderblock	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 1	side	yes	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	\sqcup
1 1	Stairwell No. 1 near Girl's Restroom side	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	12" Floor Tile
1 1	Stairwell No. 2 near Boy's Restroom side	yes	W1	Cinderblock	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 1	Stairwell No. 2 near Boy's Restroom side	yes	W2	Cinderblock	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 1	Stairwell No. 2 near Boy's Restroom side	yes	W3	Cinderblock	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 1	Stairwell No. 2 near Boy's Restroom side	yes	W4	Cinderblock	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 1	Stairwell No. 2 near Boy's Restroom side	yes	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 1	Stairwell No. 2 near Boy's Restroom side	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	12" Floor Tile

								School	Distric	t of Phil	adelphi	 а									
							1.0	ad Safe C			•										
							Le					•									
Name of Inspector: Ananth	ı K. Viniamu	uri						Crieste	r Arthur E	_iemental	y School						Inspect	tion Dates: 6/10- 6	/14/2019		
Inspection Company: Crit																	ULCS#				
E	Student/ Teacher Occupied	Primary	Substrate		Description of Primary	Primary Component Damage	XRF Reading	Primary Component XRF (positive/	Additional	Substrate		Description of Paint and Plaster	Additional Component Damage	XRF Reading	Additional Component XRF (positive/	Debris Present (describe	Quantity	Contents Need to be	On-going Moisture	Plastering Needed	Comments/ Description/
t r On-Site Room Name	(yes/no)	Component	Material	Color	Damage	Quantity (sf)	(mg/cm2)	negative)	Component	Material	Color	Damage	Quantity (sf)	(mg/cm2)	negative)	location)	(sf)	Moved Moved	Intrusion	(yes or no)	Notes
Hallway from Boy's and Girl's Restrooms near IMC to Stairwells 1 and 2	yes	W1	Cinderblock	Blue/Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
Hallway from Boy's and Girl's Restrooms near IMC to Stairwells 1 and 2	yes	No Wall	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
Hallway from Boy's and Girl's Restrooms near IMC to Stairwells 1 1 1 1						0		ľ	N/A		N/A		ĺ	N/A	N/A		0				
Hallway from Boy's and Girl's Restrooms near IMC to Stairwells 1	yes	W3	Cinderblock	Blue/Yellow	None	-	N/A	N/A		N/A		N/A	N/A	N/A	,	N/A		No	No	no	
1 1 and 2 Hallway from Boy's and Girl's Restrooms near IMC to Stairwells 1	yes	W4	Cinderblock	Blue/Yellow	None		N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 1 and 2 Hallway from Boy's and Girl's Restrooms near IMC to Stairwells 1	yes	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 1 and 2 Hallway from IMC to Classroom 1 1 1 106	yes	Floor W1	N/A Cinderblock	N/A Blue/Yellow	N/A None	N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	0	No No	No No	no no	9" Floor Tile
Hallway from IMC to Classroom	yes	W1 W2	Cinderblock	Blue/Yellow	None		N/A N/A	N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	0	No No	No	no	
1 1 Hallway from IMC to Classroom 106	yes	No Wall	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
Hallway from IMC to Classroom 106	yes	W4	Cinderblock	Blue/Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
Hallway from IMC to Classroom	yes	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
Hallway from IMC to Classroom 1	yes yes	Floor W1	N/A Cinderblock	N/A Yellow	N/A None	N/A 0	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	0	No No	No No	no no	9" Floor Tile
1 1 IMC/Library	yes	W2	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 1 IMC/Library	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A	Columns	Concrete	Yellow	Flaking	1	0.03	Negative	N/A	0	No	No	no	
1 1 IMC/Library 1 1 IMC/Library	yes	W3 W4	Cinderblock Cinderblock	Yellow Yellow	None None	0	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	0	No No	No No	no no	
1 1 IMC/Library	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A	Columns	Concrete	Yellow	Flaking	1	0.03	Negative	N/A	0	No	No	no	Pipe
1 1 IMC/Library	yes	Ceiling	Concrete	White	Flaking	2	0.02	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	penetration by W2 windows
1 1 IMC/Library	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	12" Floor Tile
1 1 Main Office Secured Storage Room 1 1 Main Office Secured Storage Room	yes	W1 W2	Cinderblock Cinderblock	Yellow Yellow	None None	0	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	0	No No	No No	no no	
1 1 Main Office Secured Storage Room	yes	W3	Cinderblock	Yellow	None	0	N/A N/A	N/A N/A	N/A N/A	N/A	N/A N/A	N/A N/A	N/A	N/A N/A	N/A N/A	N/A N/A	0	No	No	no	
1 1 Main Office Secured Storage Room	yes	W4	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 1 Main Office Secured Storage Room	yes	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 1 Main Office Secured Storage Room	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	9" Floor Tile
1 1 Main Office Closet 1 1 Main Office Closet	yes	W1	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No No	No	no	
1 1 Main Office Closet 1 1 Main Office Closet	yes	W2 W3	Cinderblock Cinderblock	Yellow Yellow	None None	0	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	0	No No	No No	no no	
1 1 Main Office Closet Main Office Closet	yes	W4	Cinderblock	Yellow	None	0	N/A N/A	N/A N/A	N/A N/A	N/A	N/A N/A	N/A N/A	N/A	N/A N/A	N/A N/A	N/A N/A	0	No	No	no	
1 1 Main Office Closet	yes	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 1 Main Office Closet Lead Teacher's Office in Main	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	9" Floor Tile
1	yes	W1 W2	Cinderblock Cinderblock	Yellow	None None	0	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	0	No No	No No	no	
Lead Teacher's Office in Main Office Area	yes	W3	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
Lead Teacher's Office in Main Office Area	yes	W4	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
Lead Teacher's Office in Main Office Area Lead Teacher's Office in Main	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	1'x1' Ceiling Tile
1 1 Office Area	yes	Floor	N/A Cindothlask	N/A Vallau	N/A None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No No	No	no	12" Floor Tile
1 1 Lead Teacher's Office Closet 1 1 Lead Teacher's Office Closet	yes	W1 W2	Cinderblock Cinderblock	Yellow Yellow	None None	0	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	0	No No	No No	no no	
1 1 Lead Teacher's Office Closet	yes	W3	Cinderblock	Yellow	None	0	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	0	No	No	no	
1 1 Lead Teacher's Office Closet	yes	W4	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 1 Lead Teacher's Office Closet	yes	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 1 Lead Teacher's Office Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	9" Floor Tile
1 1 Principal's Office	yes	W1	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 1 Principal's Office	yes	W2	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 1 Principal's Office	yes	W3	Cinderblock	Yellow	Friction	5	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	L

	lame of Inspector: Ananth rspection Company: Crite On-Site Room Name Principal's Office	Student/ Teacher						Le	ead Safe C	ertificati	on Asses	sment Re	nort									
E I E I E I E I E I E E	On-Site Room Name Principal's Office	Student/ Teacher																				
E I E I E I E I E I E E	On-Site Room Name Principal's Office	Student/ Teacher				_			Chasta	r Arthur E		ry School	•									
E I E I E I E I E I E E	On-Site Room Name Principal's Office	Student/ Teacher							Crieste	Artiliur	Liementai	y School						Inches	tion Dates: 6/10- 6	14.412040		
E F F F F F F F F F	On-Site Room Name Principal's Office	Student/ Teacher	inc.															ULCS#		/14/2019		
n o t r 1 1 1 1 1 1 1 1 1 1 1 1	Principal's Office	Teacher																ULC3#	2460			
1 1 1 1 1 1 1 1	Principal's Office	Occupied	Primary	Substrate	Color	Description of Primary	Primary Component Damage	XRF Reading		Additional	Substrate		Description of Paint and Plaster	Additional Component Damage	XRF Reading	Additional Component XRF (positive/	Debris Present (describe	Quantity		On-going Moisture	Plastering Needed	Comments/ Description/
1 1 1 1 1 1 1 1		(yes/no) yes	Component W4	Material Cinderblock	Yellow	Damage None	Quantity (sf)	(mg/cm2) N/A	negative) N/A	Component N/A	Material N/A	Color N/A	Damage N/A	Quantity (sf)	(mg/cm2) N/A	negative) N/A	location) N/A	(sf)	Moved No	Intrusion No	(yes or no)	Notes
1 1 1 1																						1'x1' Ceiling
1 1 1 1	Principal's Office Principal's Office	yes	Ceiling Floor	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	0	No No	No No	no no	Tile Carpet
	Principal's Office Restroom	yes	W1	Cinderblock	Blue	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	Carpet
1 1	Principal's Office Restroom	yes	W2	Cinderblock	Blue	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
	Principal's Office Restroom	yes	W3	Cinderblock	Blue	None		N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 1	Principal's Office Restroom Principal's Office Restroom	yes	W4 Ceiling	Cinderblock N/A	Blue N/A	None N/A		N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	0	No No	No No	no no	1'x1' Ceiling
1 1	Principal's Office Restroom	yes	Floor		N/A			N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	12" Floor Tile
1 1	Principal's Office Closet	yes	W1	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 1	Principal's Office Closet	yes	W2	Cinderblock	Yellow	None		N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 1	Principal's Office Closet Principal's Office Closet	yes	W3 W4	Cinderblock Cinderblock	Yellow	None None		N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	0	No No	No No	no no	+
1 1	Principal's Office Closet	yes	Ceiling	Concrete	White	None		N/A	N/A N/A	N/A N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A N/A	0	No	No	no	1'x1' Ceiling
1 1	Principal's Office Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	12" Floor Tile
1 1	Main Office	yes	W1	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 1	Main Office Main Office	yes yes	W2 W3	Cinderblock Cinderblock	Yellow Yellow	None None	0	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	0	No No	No No	no no	
1 1	Main Office	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A	Columns	Concrete	Yellow	Cracking	1	0.02	Negative	N/A	0	No	No	no	
1 1	Main Office	yes	W4	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	1' x1' Ceiling
1 1	Main Office Main Office	yes yes	Ceiling Floor	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	0	No No	No No	no no	Tile 12" Floor Tile
1 1	Community Partnership Coordinator's Office	yes	W1	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 1	Community Partnership Coordinator's Office	yes	W2	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 1	Community Partnership Coordinator's Office Community Partnership	yes	W3	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 1	Coordinator's Office Community Partnership	yes	W4	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	1'x1' Ceiling
1 1	Coordinator's Office Community Partnership	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	Tile
1 1	Coordinator's Office	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	12" Floor Tile
1 1	Nurse's Office Exam Room Nurse's Office Exam Room	yes	W1 W2	Cinderblock Cinderblock	Blue	None Friction	0 10	N/A 0	N/A Negative	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	0	No No	No No	no no	
1 1	Nurse's Office Exam Room	yes	W3	Cinderblock	Blue	None		N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 1	Nurse's Office Exam Room	yes	W4	Cinderblock	Blue	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 1	Nurse's Office Exam Room	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	1'x1' Ceiling
1 1	Nurse's Office Exam Room Nurse's Office Restroom	yes	Floor W1	N/A Cinderblock	N/A Blue	N/A Friction	N/A 2	N/A 0	N/A Negative	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	0	No No	No No	no no	12" Floor Tile
1 1	Nurse's Office Restroom	yes	W2	Cinderblock	Blue	Friction	1	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 1	Nurse's Office Restroom	yes	W3	Cinderblock	Blue	Friction	10	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 1	Nurse's Office Restroom Nurse's Office Restroom	yes	W4	Cinderblock N/A	Blue N/A	Friction N/A	N/A	0 N/A	Negative N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	0	No No	No No	no no	11v11 Cellinn
1 1	Nurse's Office Restroom Nurse's Office Restroom	yes yes	Ceiling	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A	N/A N/A	N/A N/A	0	No No	No	no	1'x1' Ceiling 12" Floor Tile
1 1	Nurse's Office	yes	W1	Cinderblock	Blue	Friction	4	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 1	Nurse's Office	yes	W2	Cinderblock	Blue	Friction	2	(Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 1	Nurse's Office Nurse's Office	yes	W3 W4	Cinderblock Cinderblock	Blue	Friction	2	0	Negative Negative	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	0	No No	No No	no no	-
1 1	Nurse's Office	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A N/A	0	No	No	no	1'x1' Ceiling
1 1	Nurse's Office	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	12" Floor Tile
1 1	Hallway from Classroom 100 to Classroom 106	yes	W1	W1	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 1	Hallway from Classroom 100 to Classroom 106	yes	W2	W2	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 1	Hallway from Classroom 100 to Classroom 106 Hallway from Classroom 100 to	yes	W3	W3	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 1	Hallway from Classroom 100 to Classroom 106 Hallway from Classroom 100 to	yes	W4	W4	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 1	Classroom 106 Hallway from Classroom 100 to	yes	Ceiling	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 1 Ci	Classroom 106	yes	Floor	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 1 Ci	Classroom 100 sustodial Closet near Elevator and	yes	W1	Cinderblock	White/Brown	None None	0	N/A N/A	N/A	N/A N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A N/A	0	No No	No No	no	
1 1 Ci	Classroom 100 fustodial Closet near Elevator and Classroom 100	yes	W2 W3	Cinderblock	White/Brown	None	-	N/A	N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A	N/A N/A	N/A N/A	0	No No	No No	no	

									School	District	t of Phil	adelphi	а									-
								م ا		Certification												
										r Arthur E			port									
	Name of Inspector: Ananth	K. Vinjamı	uri						Oneste	Artilui	-ieinentai	y School						Inspect	tion Dates: 6/10-6	/14/2019		
	Inspection Company: Crite	erion Labs,	Inc.															ULCS#	2480			
E I e F m I e o n o	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)	Additional Component	Substrate Material	Color	Description of Paint and Plaster Damage	Additional Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Additional Component XRF (positive/ negative)	Debris Present (describe location)	Quantity (sf)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Comments/ Description/ Notes
1 1	Custodial Closet near Elevator and Classroom 100	ves	W4	Cinderblock	White/Brown	None		N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no no	Notes
111	Custodial Closet near Elevator and Classroom 100	,		N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No No	No	no	
111	Custodial Closet near Elevator and	yes	Ceiling		,	ľ		,			,	,		1477.	1	, , , , , , , , , , , , , , , , , , ,						1'x1' Ceiling Ti
1 1	Classroom 100 Computer Server Room in Main	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0 No	No	No	no	12" Floor Tile
1 1	Office Computer Server Room in Main	yes	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Access	No Access	No Access	No Access	
1 1	Office Computer Server Room in Main	yes	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Access	No Access	No Access	No Access	
1 1	Office	yes	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Access	No Access	No Access	No Access	
1 1	Computer Server Room in Main Office	yes	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	
1 1	Computer Server Room in Main Office	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	<u> </u>
1 1	Computer Server Room in Main Office	yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	
	Stairwell No. 3 near Classroom 201 Stairwell No. 3 near Classroom 201	yes yes	W1 W2	Cinderblock Cinderblock	Green	None None	0	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	0	No No	No No	no no	
1 2	Stairwell No. 3 near Classroom 201	yes	W3	Cinderblock	Green	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
	Stairwell No. 3 near Classroom 201 Stairwell No. 3 near Classroom 201	yes	W4 Ceiling	Cinderblock Concrete	Green White	None None	0	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	0	No No	No No	no no	-
	Stairwell No. 3 near Classroom 201	yes	Floor	Concrete	Grey	None	0	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	0	No	No	no	
1 2	Classroom 201	yes	W1	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 2	Classroom 201 Classroom 201	yes	W2 W3	Cinderblock Cinderblock	Yellow Yellow	None None	0	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	0	No No	No No	no no	
1 2	Classroom 201	yes	W4	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 2		yes	Ceiling	Concrete	White	Cracking	5	0.02	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 2		yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	9" Floor Tile
1 2		yes	W1 W2	Cinderblock Cinderblock	Yellow Yellow	None None	0	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	0	No No	No No	no no	
1 2	Classroom 200	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A	Beam	Concrete	Yellow	Efflorescence	1	1.1	Positive	N/A	0	No	No	no	
1 2	Classroom 200	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A	Columns	Concrete	Yellow	Efflorescence	1	1.1	Positive	N/A	0	No	No	no	
1 2		yes	W2	N/A	N/A	N/A	N/A	N/A	N/A	Radiator cover	Metal	Brown	Scratched	4	0.13	Negative	N/A	0	No	No	no	
1 2		yes yes	W3 W4	Cinderblock Sheetrock	Yellow Yellow	None Flaking	0 5	N/A 0	N/A Negative	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	0	No No	No No	no no	-
112																			-			Flaking paint at pipe penetration
1 2	Classroom 200 Classroom 200	yes yes	Ceiling	Concrete N/A	White N/A	Flaking N/A	1 N/A	0.02 N/A	Negative N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	0	No No	No No	no no	by window
1 2	Hallway to Classrooms 203 and 205	yes	W1	Cinderblock	Blue/Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	TE TIOUT THE
1 2	Hallway to Classrooms 203 and 205	yes	W2	Cinderblock	Blue/Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 2	Hallway to Classrooms 203 and 205	yes	W3	Cinderblock	Blue/Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 2	Hallway to Classrooms 203 and 205	yes	W4	Cinderblock	Blue/Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 2	Hallway to Classrooms 203 and 205	yes	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 2	Hallway to Classrooms 203 and 205	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	9" Floor Tile
1 2	Classroom 203	yes	W1	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 2		yes	W1	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	Door Frame	Metal Metal	Brown	Chipping Scratched	3	0.06	Negative Negative	N/A N/A	0	No No	No No	no no	
1 2		yes yes	W1 W2	N/A Cinderblock	N/A Yellow	N/A None	N/A 0	N/A N/A	N/A N/A	Locker Door N/A	Metal N/A	Brown N/A	Scratched N/A	N/A	0.02 N/A	Negative N/A	N/A N/A	0	No No	No No	no	
1 2	Classroom 203	yes	W3	Cinderblock	Yellow	Flaking	3	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 2	Classroom 203	yes	W4	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	L
1 2	Classroom 203	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A	Columns	Concrete	Yellow	Efflorescence	2	0.02	Negative	N/A	0	No	No	no	Both sides of the middle column Both sides of
1 2	Classroom 203	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A	Radiator cover	Metal	Brown	Scratched	3	0.13	Negative	N/A	0	No	No	no	the middle column
1 2	Classroom 203	yes	Ceiling	Concrete	White	Cracking	11	0.01	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 2	Classroom 203 Classroom 205	yes	Floor W1	N/A Cinderblock	N/A Yellow	N/A None	N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	0	No No	No No	no	9" Floor Tile
1 2	Classroom 205 Classroom 205	yes	W1 W1	N/A	N/A	None N/A	0 N/A	N/A N/A	N/A N/A	N/A Door Frame	N/A Metal	N/A Brown	N/A Chipping	N/A 3	0.03	N/A Negative	N/A N/A	0	No No	No No	no no	
1 2	Classroom 205	yes	W2	Cinderblock	Yellow	Flaking	2	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 2	Classroom 205	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A	Columns	Concrete	Yellow	Flaking	1	1.2	Positive	N/A	0	No	No	no	at the top of middle column

									School	Distric	of Phil	adelphi	а									
								l e		Certification												
										r Arthur E			•									
Н	Name of Inspector: Ananth	n K. Viniamı	uri						Cileste	AILIIUI E	lemema	y School						Inspect	tion Dates: 6/10- 6	/14/2019		
	Inspection Company: Crit																	ULCS#				
E F F O O O O O O O O O O O O O O O O O	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)	Additional Component	Substrate Material	Color	Description of Paint and Plaster Damage	Additional Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Additional Component XRF (positive/ negative)	Debris Present (describe location)	Quantity (sf)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Comments/ Description/ Notes
1 2	Classroom 205	yes	W3	Cinderblock	Yellow	Flaking	2	0.01	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 2	Classroom 205	yes	W4	Cinderblock	Yellow	Flaking	4	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 2	Classroom 205 Classroom 205	yes yes	Ceiling	Cinderblock N/A	White N/A	None N/A	0 N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	0	No No	No No	no no	9" Floor Tile
1 2	Men's Restroom across from Classroom 202	yes	W1	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	y riodi riic
1 2	Men's Restroom across from Classroom 202	yes	W2	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 2	Men's Restroom across from Classroom 202 Men's Restroom across from	yes	W3	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 2	Classroom 202 Men's Restroom across from	yes	W4	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	-
1 2	Classroom 202 Men's Restroom across from	yes	Ceiling	Cinderblock	Yellow	Cracking	1	0.03	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 2	Classroom 202 Women's Restroom across from	yes	Floor W1	N/A	N/A	N/A	N/A 0	N/A N/A	N/A N/A	N/A N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A N/A	0	No No	No	no	12" Floor Tile
1 2	Classroom 202 Women's Restroom across from Classroom 202	yes	W1 W2	Cinderblock	Yellow	None None	0	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	0	No No	No No	no	
1 2	Women's Restroom across from Classroom 202	yes	W3	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 2	Women's Restroom across from Classroom 202	yes	W4	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 2	Women's Restroom across from Classroom 202	yes	Ceiling	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 2	Women's Restroom across from Classroom 202	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	12" Floor Tile
1 2		yes yes	W1 W1	Cinderblock N/A	Yellow N/A	None N/A	0 N/A	N/A N/A	N/A N/A	N/A Door Frame	N/A Metal	N/A Brown	N/A Chipping	N/A 7	N/A 0.02	N/A Negative	N/A N/A	0	No No	No No	no no	
1 2		yes	W2	Sheetrock	Yellow	Flaking	10	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 2	Classroom 202	yes	W2	Concrete	Yellow	Cracking	3	1.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	Beam
1 2	Classroom 202 Classroom 202	yes	W3 W4	Cinderblock Cinderblock	Yellow	None None	0	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	0	No No	No No	no no	
1 2		yes	Ceiling	Concrete	White	Cracking	5	0.04	Negative	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	0	No	No	no	
1 2		yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	9" Floor Tile
1 2	Hallway to Classroom 207	yes	W1	Cinderblock	Blue/Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 2		yes	W2	Cinderblock	Blue/Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 2		yes yes	W3 W4	Cinderblock Cinderblock	Blue/Yellow Blue/Yellow	None None	0	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	0	No No	No No	no no	-
1 2	Hallway to Classroom 207	yes	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
		yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	9" Floor Tile
1 2		yes	W1 W2	Cinderblock	Yellow	None None	0	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	0	No No	No No	no	
1 2		yes yes	W3	Cinderblock Cinderblock	Yellow	Flaking	2	0 0	Negative	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	0	No No	No	no no	-
1 2	Classroom 207	yes	W4	Cinderblock	Yellow	Flaking	15	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 2	Classroom 207	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A	Columns	Concrete	Yellow	Flaking	1	0.03	Negative	N/A	0	No	No	no	
1 2	Classroom 207 Classroom 207	yes	W4 Ceiling	N/A Concrete	N/A Yellow	N/A None	N/A N/A	N/A N/A	N/A N/A	Pipe Jacket N/A	Metal N/A	Yellow N/A	Flaking N/A	5 N/A	0.03 N/A	Negative N/A	N/A N/A	0	No No	No No	no no	
1 2		yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 2	Classroom 204 Girl's Restroom across from	yes	W1	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 2	Classroom 204 Girl's Restroom across from	yes	W2	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No No	No	no	
1 2	Classroom 204 Girl's Restroom across from Classroom 204	yes	W3 W4	Cinderblock Cinderblock	Yellow	None	0	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	0	No No	No No	no	
1 2	Girl's Restroom across from Classroom 204	yes	Ceiling	Concrete	Yellow	None Cracking	3	1,2	N/A Positive	N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	0	No No	No No	no	
1 2	Girl's Restroom across from Classroom 204	yes	Floor	Concrete	Grey	Scratched	10	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 2	Boy's Restroom across from Classroom 206	yes	W1	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 2	Boy's Restroom across from Classroom 206	yes	W2	Cinderblock	Yellow	Flaking	2	0.03	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	At the urinals
1 2	Boy's Restroom across from Classroom 206 Boy's Restroom across from	yes	W3	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 2	Classroom 206 Boy's Restroom across from	yes	W4	Cinderblock	Yellow	Flaking	3	0.01	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	At the toilets
1 2	Classroom 206	yes	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	

									School	District	t of Phil	adelphi	а									
										Certification												
								Le														
	Name of Inspector: Ananth	K Vinjami	uri						Cneste	r Arthur E	ementar	y School						Inenoc	tion Dates: 6/10- 6	/1//2019		T
	Inspection Company: Crite																	ULCS#		114/2019		
Ę.	.,	,																				
e F m I e o n o t r	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)	Additional Component	Substrate Material	Color	Description of Paint and Plaster Damage	Additional Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Additional Component XRF (positive/ negative)	Debris Present (describe location)	Quantity (sf)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Comments/ Description/ Notes
	Boy's Restroom across from												, i					\ <i>,</i>				140163
1 2	Classroom 206 Book Closet across from	yes	Floor	Concrete	Grey	Scratched	2	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 2	Classroom 206	yes	W1	Cinderblock	Green	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	Limited
1 2	Book Closet across from Classroom 206	yes	W2	Cinderblock	Green	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	Assessment - Cabinets in the way
1 2	Book Closet across from Classroom 206	yes	W3	Cinderblock	Green	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 2	Book Closet across from Classroom 206	yes	W4	Cinderblock	Green	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 2	Book Closet across from																					
1 2	Classroom 206 Book Closet across from	yes	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	+
1 2	Classroom 206	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	9" Floor Tile
1 2	Classroom 204 Classroom 204	yes	W1 W2	Cinderblock Cinderblock	Yellow Yellow	None Cracking	2	N/A 0	N/A Negative	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	0	No No	No No	no no	+
1 2	Classroom 204	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A	Columns	Concrete	Yellow	Cracking	1	0.03	Negative	N/A	0	No	No	no	
1 2	Classroom 204 Classroom 204	yes	W3 W4	Cinderblock Cinderblock	Yellow Yellow	None None	0	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	0	No No	No No	no no	
						Flaking/Cracki																Flaking in coat area (3
1 2	Classroom 204	yes	Ceiling	Concrete N/A	White	ng	5	1.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No No	No	no	SF)
1 2	Classroom 204 Classroom 206	yes	Floor W1	N/A Cinderblock	N/A Yellow	N/A None	N/A 0	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	0	No No	No No	no	-
1 2	Classroom 206	yes	W2	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 2	Classroom 206	yes	W3	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 2	Classroom 206 Classroom 206	yes	W4 Ceiling	Cinderblock	Yellow White	None Cracking	2	N/A 0.02	N/A Negative	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	0	No No	No No	no	
1 2	Classroom 206	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	9" Floor Tile
	Stairwell No. 1 near Classroom 206 Stairwell No. 1 near Classroom 206	yes	W1	Cinderblock	White/Yellow	None None	0	N/A	N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A	N/A	N/A	N/A N/A	0	No No	No	no	
1 2	Stairwell No. 1 near Classroom 206	yes	W2 W3	Cinderblock Cinderblock	White/Yellow White/Yellow	None None	0	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	0	No No	No No	no no	+
1 2	Stairwell No. 1 near Classroom 206	yes	W4	Cinderblock	White/Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
	Stairwell No. 1 near Classroom 206 Stairwell No. 1 near Classroom 206	yes	Ceiling	Concrete	White	None None	0	N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A	N/A N/A	N/A N/A	0	No No	No No	no	
	Book Closet near Classroom 209	yes	Floor W1	Concrete Cinderblock	Grey Green	None	0	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A	N/A N/A	N/A N/A	N/A N/A	0	No No	No	no no	
1 2	Book Closet near Classroom 209	yes	W2	Cinderblock	Green	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 2	Book Closet near Classroom 209 Book Closet near Classroom 209	yes	W3 W4	Cinderblock Cinderblock	Green Green	None None	0	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	0	No No	No No	no no	─
	Book Closet near Classroom 209	yes	Ceiling	Concrete	White	None	0	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	0	No No	No	no	
1 2	Book Closet near Classroom 209	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	9" Floor Tile
1 2	Stairwell No. 2 near Classroom 209 Stairwell No. 2 near Classroom 209	yes	W1 W2	Cinderblock Cinderblock	White/Yellow White/Yellow	None None	0	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	0	No No	No No	no	
	Stairwell No. 2 near Classroom 209	yes	W3	Cinderblock	White/Yellow	None	0	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	0	No	No	no	
1 2	Stairwell No. 2 near Classroom 209	yes	W4	Cinderblock	White/Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 2	Stairwell No. 2 near Classroom 209 Stairwell No. 2 near Classroom 209	yes	Ceiling	Concrete	White Grey	None None	0	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	0	No No	No No	no no	
1 2		yes	W1	Concrete	Blue/Yellow	None	0	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	0	No	No	no	\vdash
1 2	Hallway to Classroom 209	yes	W2	Cinderblock	Blue/Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	1
1 2	Hallway to Classroom 209 Hallway to Classroom 209	yes	W3 W4	Cinderblock Cinderblock	Blue/Yellow Blue/Yellow	None None	0	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	0	No No	No No	no no	
1 2	Hallway to Classroom 209 Hallway to Classroom 209	yes	Ceiling	Concrete	White	None	0	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	0	No No	No	no	
1 2	Hallway to Classroom 209	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	9" Floor Tile
1 2	Classroom 209 Classroom 209	yes	W1 W1	Cinderblock N/A	Yellow N/A	None N/A	0 N/A	N/A N/A	N/A N/A	N/A Door Frame	N/A Metal	N/A Brown	N/A Scratched	N/A 1	N/A 0.03	N/A Negative	N/A N/A	0	No No	No No	no	+
1	0.000.00111 200	7 63		11/0	.4/5	/^	/.	/5	//	Door I failed	. ideal	D. JWII	Scrattifeu		0.03	regative	140		0	.40	110	Near the top
1 2	Classroom 209	yes	W2	Cinderblock	Yellow	Flaking	5	0.01	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	of the radiator
1 2	Classroom 209	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A	Columns	Concrete	Yellow	Cracking	2	1.1	Positive	N/A	0	No No	No	no	-
\Box	Classroom 209	yes	W3	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	Below
1 2	Classroom 209 Classroom 209	yes	W4 Ceiling	Cinderblock	Yellow	Cracking Flaking, Cracking	7 20	0.02	Negative Negative	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	0	No No	No No	no	Mostly in the Coat Area
1 2	Classroom 209	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	9" Floor Tile
1 2	Hallway from Stairwell No. 1 near Classroom 206 to Stairwell No. 3 near Classroom 201	yes	W1	Cinderblock	Blue/Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 2	Hallway from Stairwell No. 1 near Classroom 206 to Stairwell No. 3 near Classroom 201	yes	W2	Cinderblock	Blue/Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	

	School District of Philadelphia Lead Safe Certification Assessment Report																					
								Le														
										r Arthur E			•									
	Name of Inspector: Ananth	K. Vinjamı	uri						0.10310	. Adams E		. , 5511001						Inspect	tion Dates: 6/10- 6	/14/2019		
	Inspection Company: Crite	erion Labs,	Inc.															ULCS#	2480			
E I e F m I e o n o t r	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)	Additional Component	Substrate Material	Color	Description of Paint and Plaster Damage	Additional Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Additional Component XRF (positive/ negative)	Debris Present (describe location)	Quantity (sf)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Comments/ Description/ Notes
1 2	Hallway from Stairwell No. 1 near Classroom 206 to Stairwell No. 3 near Classroom 201	yes	W3	Cinderblock	Blue/Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 2	Hallway from Stairwell No. 1 near Classroom 206 to Stairwell No. 3 near Classroom 201	yes	W4	Cinderblock	Blue/Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 2	Hallway from Stairwell No. 1 near Classroom 206 to Stairwell No. 3 near Classroom 201	yes	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 2	Hallway from Stairwell No. 1 near Classroom 206 to Stairwell No. 3 near Classroom 201	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	9" Floor Tile
1 2	Custodial Closet near Classroom 203	no	W1	Cinderblock	Brown/Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 2	Custodial Closet near Classroom 203	no	W2	Cinderblock	Brown	Flaking	2	0.02	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	Lower Wall
1 2	Custodial Closet near Classroom 203	no	W2	Cinderblock	Yellow	Flaking	2	1.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	Upper Wall
1 2	Custodial Closet near Classroom 203	no	W3	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	Upper Wall
1 2	Custodial Closet near Classroom 203	no	W3	Cinderblock	Brown	None	4	1.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	Lower Wall
1 2	Custodial Closet near Classroom 203	no	W3	N/A	N/A	N/A	N/A	N/A	N/A	Columns	Concrete	Yellow	Flaking	3	1.3	Positive	N/A	0	No	No	no	Upper
1 2	Custodial Closet near Classroom 203	no	W3	N/A	N/A	N/A	N/A	N/A	N/A	Columns	Concrete	Brown	Flaking	1	0.02	Negative	N/A	0	No	No	no	Lower
1 2	Custodial Closet near Classroom 203	no	W4	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	Upper Wall
1 2	Custodial Closet near Classroom 203	no	W4	Cinderblock	Brown	Flaking	4	0.04	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	Lower Wall
1 2	Custodial Closet near Classroom 203	no	Ceiling	Concrete	Yellow	Flaking	12	0.04	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 2	Custodial Closet near Classroom 203	no	Floor	Concrete	Grey	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 2	Storage Room next to Classroom 203	no	W1	Cinderblock	Green	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 2	Storage Room next to Classroom 203	no	W2	Cinderblock	Green	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 2	Storage Room next to Classroom 203	no	W3	Cinderblock	Green	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 2	Storage Room next to Classroom 203	no	W4	Cinderblock	Green	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 2	Storage Room next to Classroom 203	no	W4	N/A	N/A	N/A	N/A	N/A	N/A	Pipe	Metal	Green	Flaking	4	0.26	Negative	N/A	0	No	No	no	
1 2	Storage Room next to Classroom 203	no	Ceiling	Concrete	Yellow	Flaking	30	0.02	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 2	Storage Room next to Classroom 203	no	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	9" Floor Tile
1 2	Room 207-A Room 207-A	yes	W1 W1	Cinderblock N/A	Yellow N/A	None N/A	0 N/A	N/A N/A	N/A N/A	N/A Door Frame	N/A Metal	N/A Brown	N/A Chipping	N/A 2	N/A 0.2	N/A Negative	N/A N/A	0	No No	No No	no	Both doors
1 2	Room 207-A	yes	W1 W2	N/A Cinderblock	N/A Yellow	N/A None	N/A 0	N/A N/A	N/A N/A	N/A	Metai N/A	N/A	N/A	N/A	N/A	Negative N/A	N/A N/A	0	No No	No	no no	DULI GOOFS
1 2	Room 207-A	yes	W3 W4	Cinderblock	Yellow	Flaking	2	0	Negative N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	0	No No	No No	no	
1 2	Room 207-A	yes	W4 Ceiling	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A N/A	0	No No	No No	no	Concrete only at windows. Rest of the ceiling is 1' x 1' ceiling tile
1 2	Room 207-A	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	9" Floor Tile
1 3	Elevator Elevator	yes yes	W1 W2	Metal Metal	White White	None None	0	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	0	No No	No No	no no	
1 3	Elevator	yes	W3	Metal	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 3	Elevator Elevator	yes	W4 Ceiling	Metal Metal	White White	None	0	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	0	No No	No No	no	
1 3	Elevator Elevator	yes yes	Ceiling	Metal N/A	White N/A	None N/A	N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	0	No No	No No	no no	12" Floor Tile
1 3	Classroom 309	yes	W1	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 3	Classroom 309	yes yes	W1 W1	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	Door Door Frame	Wood Metal	Brown Brown	Scratched Scratched	3 5	0.11	Negative Negative	N/A N/A	0	No No	No No	no no	
1 3	Classroom 309	yes	W2	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 3	Classroom 309 Classroom 309	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A	Beam Columns	Concrete	White Yellow	Cracking	2	1.1	Positive	N/A	0	No No	No No	no	Horizontal Beam above windows
1 3		yes	W2	N/A	N/A	N/A	N/A	N/A	N/A		Concrete		Scratched		0.07	Negative	N/A	0	No	No	no	Far right
1 3	Classroom 309 Classroom 309	yes	W3 W4	Cinderblock Cinderblock	Yellow Yellow	None Cracking	5	N/A 0	N/A Negative	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	0	No No	No No	no no	corner

									School	Distric	t of Phil	adelphi	а									
								Le	ad Safe C	Certification	on Asses	sment Re	port									
										r Arthur E			•									
	Name of Inspector: Ananth	K. Vinjamı	uri									,						Inspec	tion Dates: 6/10-6	5/14/2019		
	Inspection Company: Crite	erion Labs,	Inc.															ULCS#	2480			
E I e F m I e o n o t r	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)	Additional Component	Substrate Material	Color	Description of Paint and Plaster Damage	Additional Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Additional Component XRF (positive/ negative)	Debris Present (describe location)	Quantity (sf)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Comments/ Description/ Notes
1 3		ves	W4	Concrete	White	Cracking	4	0.04	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	Beam above blackboard
1 3	Classroom 309	yes	Ceiling	Concrete	White	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	Diackboard
1 3	Classroom 309	yes	Floor	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	9" Floor Tile
	Stainwell No. 2 near Classroom 309 Stainwell No. 2 near Classroom 309	yes yes	W1 W2	Cinderblock Cinderblock	White White	None None	0	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	0	No No	No No	no no	Along beam and by window
	Stairwell No. 2 near Classroom 309	yes	W3	Cinderblock	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 3		yes	W4	Cinderblock	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
	Stairwell No. 2 near Classroom 309 Stairwell No. 2 near Classroom 309	yes	Ceiling	Concrete	White Grey	None None	0	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	0	No No	No No	no no	-
	Book Closet near Classroom 309	yes	W1	Cinderblock	Green	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 3		yes	W2	Cinderblock	Green	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 3	Book Closet near Classroom 309 Book Closet near Classroom 309	yes	W3 W4	Cinderblock Cinderblock	Green Green	None None	0	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	0	No No	No No	no no	
	Book Closet near Classroom 309	yes	Ceiling	Concrete	White	Flaking	10	0.01	N/A Negative	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A	0	No	No	no	Spread Out
1 3	Book Closet near Classroom 309	yes	Floor	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	9" Floor Tile
	Stairwell No. 1 near Classroom 306 Stairwell No. 1 near Classroom 306	yes	W1 W2	Cinderblock	White White	None None	0	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	0	No No	No No	no no	
	Stairwell No. 1 near Classroom 306	yes	W3	Cinderblock	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
	Stairwell No. 1 near Classroom 306	yes	W3	N/A	N/A	N/A	0	N/A	N/A	Window sill	Slate	Tan	Scratched	2	0.01	Negative	N/A	0	No	No	no	
1 3	Stairwell No. 1 near Classroom 306 Stairwell No. 1 near Classroom 306	yes	W4 Ceiling	Concrete	White White	None None	0	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	0	No No	No No	no no	
	Stairwell No. 1 near Classroom 306	yes	Floor	Concrete	Grey	None	0	N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	0	No	No	no	
1 3	Hallway to Classroom 309	yes	W1	Cinderblock	Blue	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 3		yes	W2	Cinderblock	Blue	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No No	No	no	
1 3		yes	W3 W4	N/A Cinderblock	N/A Blue	N/A None	N/A 0	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	0	No No	No No	no no	
1 3		yes	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 3		yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 3	Book Closet across from	yes	W1	Cinderblock	Green	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 3	Classroom 306 Book Closet across from	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	Brown	Scratched	5	0.06	Negative	N/A	0	No	No	no	
1 3	Classroom 306	yes	W2	Cinderblock	Green	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	Limited access - Misc
1 3	Book Closet across from	yes	W3	Cinderblock	Green	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	materials in the way Limited access - Cabinets against the
1 3	Classroom 306 Book Closet across from	yes	W4	Cinderblock	Green	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	wall
1 3	Classroom 306 Book Closet across from Classroom 306	yes	Ceiling	Concrete N/A	White N/A	None N/A	0 N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	0	No No	No No	no	9" Floor Tile
1 3	Boy's Restroom across from Classroom 306	yes	W1	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 3	Boy's Restroom across from Classroom 306	yes	W1	N/A	N/A	N/A	0	N/A	N/A	Door Frame	Metal	Grey	Scratched	5	0.07	Negative	N/A	0	No	No	no	
1 3	Boy's Restroom across from Classroom 306 Boy's Restroom across from	yes	W2	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 3	Classroom 306 Boy's Restroom across from	yes	W3	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	-
1 3	Classroom 306 Boy's Restroom across from	yes	W4	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 3	Classroom 306 Boy's Restroom across from	yes	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 3	Classroom 306 Girl's Restroom across from Classroom 304	yes	Floor W1	Concrete	Grey	None	0	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	0	No No	No No	no	
1 3	Girl's Restroom across from Classroom 304	yes	W1 W1	Cinderblock N/A	Yellow N/A	None N/A	N/A	N/A N/A	N/A N/A	N/A Door	N/A Wood	N/A Brown	N/A Scratched	N/A 2	N/A 0	N/A Negative	N/A N/A	0	No No	No No	no	
1 3	Girl's Restroom across from Classroom 304	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	Brown	Scratched	5	0.05	Negative	N/A	0	No	No	no	
1 3	Girl's Restroom across from Classroom 304	yes	W2	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 3	Girl's Restroom across from Classroom 304	yes	W3	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	

									Schoo	District	t of Phil	adelphi	а									
								Le		Certification												
										r Arthur E			•									
	Name of Inspector: Ananti	h K Viniamı	uri						Cileste	Artilui	lemema	y School						Inspect	tion Dates: 6/10-6	/14/2019		
	Inspection Company: Crit																	ULCS#		14/2010		
E I E F M I E O N O		Student/ Teacher Occupied	Primary	Substrate		Description of Primary	Primary Component Damage	XRF Reading	Primary Component XRF (positive/	Additional	Substrate		Description of Paint and Plaster	Additional Component Damage	XRF Reading	Additional Component XRF (positive/	Debris Present (describe	Quantity	Contents Need to be	On-going Moisture	Plastering Needed	Comments/ Description/
t r	On-Site Room Name	(yes/no)	Component	Material	Color	Damage	Quantity (sf)	(mg/cm2)	negative)	Component	Material	Color	Damage	Quantity (sf)	(mg/cm2)	negative)	location)	(sf)	Moved	Intrusion	(yes or no)	Notes
1 3	Girl's Restroom across from Classroom 304	yes	W4	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 3	Girl's Restroom across from Classroom 304	yes	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 3	Girl's Restroom across from Classroom 304	yes	Floor	Concrete	Grey	Cracking	20	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 3	Classroom 306	yes	W1	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 3	Classroom 306	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	Pipe	Metal	Yellow	Flaking	2	0.21	Negative	N/A	0	No	No	no	
1 3	Classroom 306 Classroom 306	yes	W1 W2	N/A Cinderblock	N/A Yellow	N/A None	N/A 0	N/A N/A	N/A N/A	Door Frame N/A	Metal N/A	Brown N/A	Scratched N/A	6 N/A	0.02 N/A	Negative N/A	N/A N/A	0	No No	No No	no no	
1 3	Classroom 306	yes	W3	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No No	No	no	Crack along the perimeter seam and by right corner
1 3	Classroom 306	yes	W4	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 3	Classroom 306	yes yes	W4 Ceiling	N/A Concrete	N/A White	N/A None	N/A 0	N/A N/A	N/A N/A	Columns N/A	Concrete N/A	Yellow N/A	Cracking N/A	2 N/A	0.01 N/A	Negative N/A	N/A N/A	0	No No	No No	no no	
1 3	Classroom 306	yes	Floor	N/A	N/A	N/A	N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	0	No	No	no	
1 3	Classroom 304	yes	W1	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 3	Classroom 304 Classroom 304	yes yes	W1 W2	N/A Cinderblock	N/A Yellow	N/A None	N/A 0	N/A N/A	N/A N/A	Door Frame N/A	Metal N/A	Brown N/A	Scratched N/A	5 N/A	0.03 N/A	Negative N/A	N/A N/A	0	No No	No No	no no	
1 3	Classroom 304	yes	W3	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 3	Classroom 304	yes	W4	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 3	Classroom 304 Classroom 304	yes yes	Ceiling	Concrete N/A	White N/A	None N/A	0 N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	0	No No	No No	no no	9" Floor Tile
1 3	Classroom 307	yes	W1	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	9 FIOOI THE
1 3	Classroom 307	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	Brown	Scratched	10	0.12	Negative	N/A	0	No	No	no	
1 3	Classroom 307 Classroom 307	yes	W2 W3	Cinderblock Cinderblock	Yellow	Cracking None	3	0 N/A	Negative N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	0	No No	No No	no no	
1 3	Classroom 307	yes yes	W3 W4	Cinderblock	Yellow	None	0	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	0	No No	No No	no	
1 3	Classroom 307	ves	W4	N/A	N/A	N/A	N/A	N/A	N/A	Columns	Concrete	Yellow	Flaking	1	0.05	Negative	on top of radiator vent at middle column	,	No	No	no	
1 3	Classroom 307	yes	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 3	Classroom 307	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	9" Floor Tile
1 3	Hallway to Classroom 307 Hallway to Classroom 307	yes yes	W1 W2	Cinderblock Cinderblock	Yellow/Blue Yellow/Blue	None None	0	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	0	No No	No No	no no	
1 3	Hallway to Classroom 307 Hallway to Classroom 307	yes yes	W3 W4	N/A Cinderblock	Yellow/Blue=i f(3645:J="No Access","No Access",IF (3645:J=" N/A"," N/A","")) Yellow/Blue	N/A None	N/A 0	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	0 0	No No	No No	no no	
1 3	Hallway to Classroom 307	yes	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 3	Hallway to Classroom 307 Classroom 307-A	yes	Floor	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	1
1 3	Classroom 307-A Classroom 307-A	yes	W1 W1	Cinderblock N/A	Yellow N/A	None N/A	0	N/A N/A	N/A N/A	N/A Door Frame	N/A Metal	N/A Brown	N/A Scratched	N/A 3	N/A 0.05	N/A Negative	N/A N/A	0	No No	No No	no no	Left Door
1 3	Classroom 307-A	yes	W1	N/A	N/A	N/A	0	N/A	N/A	Door Frame	Metal	Brown	Scratched	3	0.15	Negative	N/A	0	No	No	no	Right Door
1 3	Classroom 307-A	yes	W2	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No No	No	no	
1 3	Classroom 307-A Classroom 307-A	yes	W3 W4	Cinderblock Cinderblock	Yellow Yellow	None None	0	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	0	No No	No No	no no	-
1 3	Classroom 307-A	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	1' x 1' Spline Ceiling Tiles
1 3	Classroom 307-A	yes	Floor	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	0	No	No	no	Cenning rines
1 3	Classrooms 300 and 302	yes	W1	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 3	Classrooms 300 and 302	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	Brown	Scratched	4	0.02	Negative	N/A	0	No	No	no	Right side door
1 3	Classrooms 300 and 302 Classrooms 300 and 302	yes	W2 W2	Cinderblock N/A	Yellow N/A	None N/A	0 N/A	N/A N/A	N/A N/A	N/A Beam	N/A Concrete	N/A White	N/A Flaking	N/A 1	N/A 0.03	N/A Negative	N/A N/A	0	No No	No No	no no	+
1 3	Classrooms 300 and 302	yes	W3	Sheetrock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 3	Classrooms 300 and 302	yes	W4	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 3	Classrooms 300 and 302	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A	Columns	Concrete	Yellow	Flaking	1	0.02	Negative	N/A	0	No	No	no	Spread out.
1 3	Classrooms 300 and 302 Classrooms 300 and 302	yes yes	Ceiling Floor	Concrete N/A	White N/A	Flaking, Cracking N/A	40 N/A	0.03 N/A	Negative N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	0	No No	No No	no no	Including middle beam 12" Floor Tile
1 3	Classrooms 300 and 302 Restricted Storage Room	yes	W1	Sheetrock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 3	Classrooms 300 and 302 Restricted Storage Room	yes	W2	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	

	School District of Philadelphia Lead Safe Certification Assessment Report																					
								Le														
										r Arthur E												
	Name of Inspector: Ananth								Gilooto	- Artinar E		y 0011001							tion Dates: 6/10-6	/14/2019		
-	Inspection Company: Crite	rion Labs,	Inc.															ULCS#	2480			
e F m I e o n o	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)	Additional Component	Substrate Material	Color	Description of Paint and Plaster Damage	Additional Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Additional Component XRF (positive/ negative)	Debris Present (describe location)	Quantity (sf)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Comments/ Description/ Notes
1 3	Classrooms 300 and 302 Restricted Storage Room	ves	W3	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 3	Classrooms 300 and 302 Restricted Storage Room	yes	W4	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 2	Classrooms 300 and 302 Restricted Storage Room	yes	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 3	Classrooms 300 and 302										,							0	·			12" Floor Tile
1 3	Restricted Storage Room Classrooms 300 and 302 Storage	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A		No	No	no	12" Floor Tile
1 3	Room Classrooms 300 and 302 Storage	yes	W1	Sheetrock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 3	Room Classrooms 300 and 302 Storage	yes	W2	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 3	Room Classrooms 300 and 302 Storage	yes	W3	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 3	Room Room	yes	W4	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	Spread out.
1 3	Classrooms 300 and 302 Storage Room	yes	Ceiling	Concrete	White	Flaking, Cracking	4	0.02	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	Includes beam
1 3	Room	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	12" Floor Tile
1 3	Stairwell No. 3 near Classroom 301 Stairwell No. 3 near Classroom 301	yes	W1 W2	Cinderblock Cinderblock	Yellow Yellow	None None	0	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	0	No No	No No	no no	
1 3	Stairwell No. 3 near Classroom 301 Stairwell No. 3 near Classroom 301	yes ves	W3 W4	Cinderblock Cinderblock	Yellow Yellow	None None	0	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	0	No No	No No	no no	
	Stairwell No. 3 near Classroom 301	yes	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 3	Stairwell No. 3 near Classroom 301	yes	Floor	Concrete	Grey	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 3	Classroom 301 Classroom 301	yes	W1 W1	Cinderblock N/A	Yellow N/A	None N/A	0 N/A	N/A N/A	N/A N/A	N/A Door Frame	N/A Metal	N/A Brown	N/A Scratched	N/A	N/A 0.07	N/A	N/A N/A	0	No No	No No	no no	
1 3	Classroom 301	yes	W2	N/A Cinderblock	Yellow	None None	N/A 0	N/A N/A	N/A N/A	N/A	N/A	N/A	N/A	N/A	N/A	Negative N/A	N/A N/A	0	No	No	no	
1 3	Classroom 301	ves	W3	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	Crack in wall by coat area
1 3	Classroom 301	yes	W4	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	by coat area
1 3	Classroom 301	yes	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 3	Classroom 301 Women's Restroom across from Classroom 302	yes	Floor W1	N/A Cinderblock	N/A Yellow	N/A None	N/A 0	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	0	No No	No No	no	
1 3	Women's Restroom across from Classroom 302	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	Brown	Flaking/Scratc hed	3	0.02	Negative	N/A	0	No	No	no	
1 3	Women's Restroom across from Classroom 302	yes	W2	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 3	Classroom 302	yes	W3	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 3	Women's Restroom across from Classroom 302	yes	W4	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
	Women's Restroom across from					Flaking,																3 SF is cracking/flaki ng. Another 10 SF appears to have been scraped but needs to be
1 3	Classroom 302 Women's Restroom across from	yes	Ceiling	Concrete	Beige	Cracking	3	0.05	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	re-painted
1 3	Classroom 302 Men's Restroom across from	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	12" Floor Tile
1 3	Classroom 302 Men's Restroom across from	yes	W1	Cinderblock N/A	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A Flaking/Scratc	N/A	N/A	N/A	N/A	0	No No	No No	no	
1 3	Classroom 302 Men's Restroom across from	yes	W1		N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	Brown	hed		0.05	Negative	N/A		No No	No No	no	
1 3	Classroom 302 Men's Restroom across from	yes	W2	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 3	Classroom 302 Men's Restroom across from	yes	W3	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 3	Classroom 302 Men's Restroom across from	yes	W4	Cinderblock	Yellow	None Flaking,	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 3	Classroom 302 Men's Restroom across from	yes	Ceiling	Concrete	Beige	Cracking	2	0.05	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	-
1 3 1 3	Classroom 302 Classroom 305	yes	Floor W1	N/A Cinderblock	N/A Yellow	N/A None	N/A 0	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	0	No No	No No	no no	12" Floor Tile
1 3	Classroom 305 Classroom 305	yes	W1 W2	N/A Cinderblock	N/A Yellow	N/A None	N/A 0	N/A N/A	N/A N/A	Door Frame	Metal N/A	Brown N/A	Scratched N/A	3 N/A	0.01 N/A	Negative N/A	N/A N/A	0	No No	No No	no	
1 3	Classroom 305 Classroom 305	yes	W2 W2	Cinderblock Cinderblock	Yellow	None N/A	0 N/A	N/A N/A	N/A N/A	N/A Columns	N/A Concrete	N/A Yellow	N/A Flaking and Efflorescence	N/A 2	0.07	N/A Negative	N/A Window Sill, radiator	1	No No	No Unknown	no No	Column side facing the window
1 3		yes	W3	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	Unknown	no	

									School	l District	of Phil	adelphi	<u></u>									
								Le		Certification		•										
										r Arthur E												
	Name of Inspector: Ananth	n K. Vinjamu	uri						Oneste	Aithui	icincinai	y ochool						Inspec	tion Dates: 6/10- 6	/14/2019		
	Inspection Company: Crit	erion Labs,	Inc.													ULCS#	2480					
E I E F M I E O n O t r	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)	Additional Component	Substrate Material	Color	Description of Paint and Plaster Damage	Additional Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Additional Component XRF (positive/ negative)	Debris Present (describe location)	Quantity (sf)	Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Comments/ Description/ Notes
1 3 1 3	Classroom 305 Classroom 305	yes yes	W4 Ceiling	Cinderblock Concrete	Yellow White	None None	0	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	0	No No	Unknown	no no	
1 3	Classroom 305	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Floor	1	No	Unknown	no	by window
1 3		yes	W1	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 3		yes	W1	N/A	N/A	N/A	0 4	N/A 0	N/A	Door Frame	Metal	Brown	Scratched	3	0.07	Negative	N/A	0	No No	No	no	the Dece
1 3		yes yes	W2 W3	Cinderblock Cinderblock	Yellow Yellow	Cracking None	0	N/A	Negative N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A	N/A N/A	N/A N/A	N/A N/A	0	No No	No No	no no	on the Beam
1 3	Classroom 303	yes	W4	Cinderblock	Yellow	Cracking	8	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 3		yes	W4	N/A	N/A	N/A	N/A	N/A	N/A	Columns	Concrete	Yellow	Efflorescence	2	0.03	Negative	N/A	0	No No	No	no	
1 3		yes yes	Ceiling	Concrete N/A	White N/A	None N/A	0 N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	0	No No	No No	no no	9" Floor Tile
H	Hallway to Classrooms 303 and	,																			110	- TIOUT THE
1 3	305 Hallway to Classrooms 303 and 305	yes	W1 W2	Cinderblock	Blue/Yellow Blue/Yellow	None None	0	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	0	No No	No No	no	
1	Hallway to Classrooms 303 and																					
1 3	305 Hallway to Classrooms 303 and 305	yes	W3 W4	Cinderblock Cinderblock	Blue/Yellow Blue/Yellow	None None	0	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	0	No No	No No	no	
1 3	Hallway to Classrooms 303 and 305	yes	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 3	Hallway to Classrooms 303 and 305	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	9" Floor Tile
1 2	Custodial Staff Office and Storage next to Classroom 303	no	W1	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
	Custodial Staff Office and Storage							1,11			,	,	_ ·					0				
1 3	next to Classroom 303 Custodial Staff Office and Storage	no	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	Brown	Scratched	10	0.08	Negative	N/A		No	No	no	
1 3	next to Classroom 303 Custodial Staff Office and Storage	no	W2	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	+
1 3	next to Classroom 303 Custodial Staff Office and Storage next to Classroom 303	no no	W3 W4	Cinderblock	Yellow	Cracking	0	0.01 N/A	Negative N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	0	No No	No No	no	
1 3	Custodial Staff Office and Storage next to Classroom 303	no	Ceiling	Concrete	Yellow	Flaking	200	0.02	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	Severe Flaking Paint
1 3	Custodial Staff Office and Storage next to Classroom 303	no	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	9" Floor Tile
1 3	Custodial Closet near Classroom 303	no	W1	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 3	Custodial Closet near Classroom 303	no	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	Brown	Scratched	7	0.07	Negative	N/A	0	No	No	no	
1 3	Custodial Closet near Classroom 303	no	W2	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 3	Custodial Closet near Classroom 303	no	W3	Cinderblock	Brown	Cracking	10	0.05	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	Lower Wall
1 3	Custodial Closet near Classroom 303	no	W4	Cinderblock	Yellow	Efflorescence	20	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	Upper Wall
1 3	Custodial Closet near Classroom 303	no	Ceiling	Concrete	Yellow	Cracking	10	0.03	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 3	Custodial Closet near Classroom 303 Hallway from Stairwell No. 3 near	no	Floor	Concrete	Grey	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 3	Classroom 301 to Stairwell No. 1 near Classroom 306	yes	W1	Cinderblock	Blue/Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 3	Hallway from Stairwell No. 3 near Classroom 301 to Stairwell No. 1 near Classroom 306	yes	W2	Cinderblock	Blue/Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 3	Hallway from Stairwell No. 3 near Classroom 301 to Stairwell No. 1 near Classroom 306	yes	W3	Cinderblock	Blue/Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 3	Hallway from Stairwell No. 3 near Classroom 301 to Stairwell No. 1 near Classroom 306	yes	W4	Cinderblock	Blue/Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 3	Hallway from Stairwell No. 3 near Classroom 301 to Stairwell No. 1 near Classroom 306	yes	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	
1 3	Hallway from Stairwell No. 3 near Classroom 301 to Stairwell No. 1 near Classroom 306	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	no	9" Floor Tile