										hool Dist												
										Safe Certifi												
	Name of Inspector: Ryan Hutsel	1							F.	S. Edmon	as Eleme	ntary Sc	nooi					Inspection D	Dates: 06/11- 06/	15/2019		
	Inspection Company: Synertech									r	-						1	ULCS# 6210			1	1
E I e m e n t	F I o o <u>On-Site Room Name</u>	Student Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)	Additional Component	Substrate Material	Color	Description of Paint and Plaster Damage	Additional Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Additional Component XRF (positive/ negative)	Debris Present (describe location)	Quantity (sf)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Comments/ Description/ Notes
1	Storage between Boiler Room and Building B Engineer's Office	Yes	W1	Concrete	White	Chipping	12	0.01	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Prior to Repair	No	No	
1	Storage between Boiler Room and Building Engineer's Office	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	White	Chipping	1	0.04	Negative	None	0	Prior to Repair	No	No	
1	Storage between Boiler Room and Building B Engineer's Office	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	Pipe Riser	Metal	White	Cracking	4	0.4	Negative	None	0	Prior to Repair	No	No	
1	Storage between Boiler Room and Building B Engineer's Office	Yes	W2	Concrete	White	Cracking	2	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Prior to Repair	No	No	
1	Storage between Boiler Room and Building Engineer's Office	Yes	W3	Concrete	White	Cracking	2	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Prior to Repair	No	No	
1	Storage between Boiler Room and Building B Engineer's Office	Yes	W4	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Prior to Repair	No	No	
1	Storage between Boiler Room and Building B Engineer's Office	Yes	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	
1	Storage between Boiler Room and Building B Engineer's Office	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	Ductwork	Metal	White	None	3	0	Negative	None	0	No	No	No	
1	Storage between Boiler Room and Building B Engineer's Office	Yes	Floor	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	
<u>.</u>	B Boy's Restroom	Yes	W1	Concrete	White/Tan		3			N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	Ceramic Tile - Not damaged, but
++						Chipping	-		Negative			ĺ í		IN/A				U	ON	IND	NO	glazing is positive Ceramic Tile - Not damaged, but
1	B Boy's Restroom B Boy's Restroom B Boy's Restroom	Yes Yes	W1 W2	N/A Concrete	N/A White White	N/A N/A N/A	N/A N/A	N/A N/A	N/A N/A	Door Frame N/A	Metal N/A	Brown N/A	Chipping N/A N/A	1 N/A	0.4 N/A	Negative N/A	None None	0	No No	No No	No	glazing is positive
	B Boy's Restroom B Boy's Restroom	Yes Yes	W3 W4	Concrete	White White	N/A Chipping	N/A 4	N/A	N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A N/A	N/A N/A	N/A N/A	None None	0	No No	No No	No No	
1	B Boy's Restroom	Yes	W4	Concrete N/A	N/A	Chipping N/A	4 N/A	0.04 N/A	Negative N/A	Radiator cover	Motal	Brown	Chipping	N/A 4	0.43	Negative	None	0	No	No	No	
1	B Boy's Restroom B Boy's Restroom	Yes Yes	W4 Ceiling	N/A Concrete	N/A White	N/A None	N/A 0	N/A N/A	N/A N/A	Pipe Riser N/A	Metal N/A	Brown N/A	Chipping N/A	4 N/A	0.1 N/A	Negative	None None	0	No No	No	No	
1	B Boy's Restroom	Yes	Floor	Ceramic Tile	White N/A	None None	0	N/A N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A N/A	None	0	No	No	No	Ceramic Tile - Not damaged, but
1	B Girl's Restroom	Yes	W1	Concrete	White	Chipping	3	0.02	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	glazing is positive Ceramic Tile - Not damaged, but
1	B Girl's Restroom	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	Brown	Chipping	3	0.4	Negative	None	0	No	No	No	glazing is positive
1	B Girl's Restroom B Girl's Restroom	Yes Yes	W2 W3	Concrete Concrete	White	None Chipping	0	N/A 0.01	N/A Negative	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	None	0	No	No	No	
1	B Girl's Restroom	Yes	W3	N/A	N/A	N/A None	N/A	N/A	N/A	Radiator cover	Metal	Brown	Chipping	1	0.34	Negative N/A	None	0	No	No	No	
1	B Girl's Restroom B Girl's Restroom	Yes Yes	W4 Ceiling	None Concrete	White White	None Cracking	3	N/A 0	N/A Negative	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	None None	0	No	No	No	
1	B Girl's Restroom Custodial Closet between Boy's and Girl's	Yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A N/A	None	0	No	No	No	Floor Tile Present
1	Restrooms Custodial Closet between Boy's and Girl's Restrooms Restrooms Restrooms	No	W1	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	
1		No	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	White	Chipping	2	0.2	Negative	None	0	No	No	No	
	B Restrooms	No	W2	Concrete	White	None	Ö	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	
1	Custodial Closet between Boy's and Girl's B Restrooms	No	W3	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	
1	Custodial Closet between Boy's and Girl's Restrooms Custodial Closet between Boy's and Girl's	No	W4	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	
1	B Restrooms	No	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	
	Custodial Closet between Boy's and Girl's Restrooms	No	Floor	Concrete	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Prior to Repair	No	No	
1	B Building Engineer's Office	No	W1	Concrete	White	Chipping N/A	7	0.02	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	
1	B Building Engineer's Office B Building Engineer's Office	No	W1 W2	N/A Concrete	N/A White	N/A Flaking	N/A 6	N/A 0	N/A Negative	Door Frame N/A	Metal N/A	White N/A	Chipping N/A	1 N/A	0.2 N/A	Negative N/A	None None	0	No Prior to Repair	No	No	
1	B Building Engineer's Office	No No	W3 W3	Concrete N/A	White N/A	Chipping N/A	6 N/A	0.1 N/A	Negative N/A	N/A Radiator cover	N/A Metal	N/A White	N/A	N/A	N/A 0.7	N/A Positive	None None	0	Prior to Repair No	No	No	
1	B Building Engineer's Office B Building Engineer's Office	No	W3	N/A	N/A	N/A	N/A	N/A N/A	N/A N/A	Pipe Riser	Metal	White	Chipping Chipping	1	0.5	Negative	None	0	No	No	No	
1	B Building Engineer's Office B Building Engineer's Office	No	W4 Ceiling	Concrete Concrete	White White	Cracking None	4	0 N/A	Negative N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	None None	0	Prior to Repair No	No	No	
1	B Building Engineer's Office	No	Floor	Concrete	White	None	0	N/A N/A	N/A N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	
1	B Building Engineer's Office Restroom	No No	W1 W1	Concrete N/A	White N/A	None N/A	0 N/A	N/A N/A	N/A N/A	N/A	N/A Metal	N/A White	N/A	N/A	N/A	N/A	None	0	No No	No	No	
1	B Building Engineer's Office Restroom B Building Engineer's Office Restroom	No	W2	Concrete	White	None	0	N/A	N/A	Door Frame N/A	N/A	N/A	Chipping N/A	N/A	0.2 N/A	Negative N/A	None None	0	No	No	No	
1	B Building Engineer's Office Restroom	No	W3	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A N/A	N/A	N/A	N/A	N/A	None	0	No	No No	No	
1	B Building Engineer's Office Restroom B Building Engineer's Office Restroom	No No	W4 Ceiling Floor	Concrete Concrete	White White	None None	0	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	None None	0	No No	No	No	
1	B Building Engineer's Office Restroom B Office next to Building Engineer's Office	No	Floor W1	Concrete Concrete	N/A White	None None	0	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	None None	0	No	No No	No	
1	B Office next to Building Engineer's Office	No	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	White	Chipping	2	0.15	Negative	None	0	No	No	No	
1	B Office next to Building Engineer's Office B Office next to Building Engineer's Office	No No	W2 W3	Concrete Concrete	White White	None None	0	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	None None	0	No	No	No	
1	B Office next to Building Engineer's Office	No	W4	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	
1	B Office next to Building Engineer's Office B Office next to Building Engineer's Office	No	Ceiling	Concrete Concrete	White N/A	None None	0	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	None None	0	No	No	No	
	B Office next to Building Engineer's Office Restroom inside Office next to Building B Engineer's Office	Yes	W1	Concrete	White	Cracking	2	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	
· -	Bestreem inside Office post to Building	Yes	W1 W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	White		1	0.25		None	0	No	No	No	
	B Engineer's Office Restroom inside Office next to Building												Chipping	1		Negative						
1	B Engineer's Office Restroom inside Office next to Building	Yes	W2	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	
1	B Engineer's Office Restroom inside Office next to Building B Engineer's Office	Yes	W3	Concrete	White	Flaking	2	0.04	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	
1		Yes	W4	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	
_1	B Engineer's Office Restroom inside Office next to Building	Yes	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	
1	B Engineer's Office Office next to Building Engineer's Office on	Yes	Floor	Concrete	Red	Chipping	150	0.2	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	Door jammed; No Doorknob or
1	B Corner	Yes	W1	No Access	No Access	No Access	No Access	No Access	No Access	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	key
1	Office next to Building Engineer's Office on Corner Office next to Building Engineer's Office on	Yes	W2	No Access	No Access	No Access	No Access	No Access	No Access	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	
1	B Corner	Yes	W3	No Access	No Access	No Access	No Access	No Access	No Access	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	
	Office next to Building Engineer's Office on B Corner Office next to Building Engineer's Office on	Yes	W4	No Access	No Access	No Access	No Access	No Access	No Access	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	
1	D Conter																					

1 1									Sc	hool Dist	trict of F	hilade	Iphia									
Interference Interference Interference Interference Interference Interference	Name of Inspector: Ryan Huteol		1						F.	S. Edmon	ds Eleme	ntary Sc	hool					Inspection F)atos: 06/11, 06/	15/2019		
				_	-	_									-		-			15/2019	_	
1 1	n o	Teacher Occupied	Primary			Primary	Component Damage		Component XRF (positive/	Additional			Paint and	Component Damage		Component XRF (positive/	(describe				Needed (yes or	Comments/ Description/ Notes
1 1	Office next to Building Engineer's Office on		Component							Component			Damage						De Moved	Ne	No	Comments/ Description/ Notes
1 1	Storage Closet "D" next to Small Hallway to									N/A	ĺ ĺ	1 í	1 í		L Ó	1 í		0	NO	NO	NO	
1 1	Storage Closet "D" next to Small Hallway to	NO												N/A				U			INO	
> 1 > 1 P P P P	1 B Exterior next to Kitchen Storage Storage Closet "D" next to Small Hallway to	No												2		1		0			No	
> 1 > 1 P P P P	1 B Exterior next to Kitchen Storage Storage Closet "D" next to Small Hallway to		1			1																
1 1	1 B Exterior next to Kitchen Storage Storage Closet "D" next to Small Hallway to	No	W3	Concrete		Cracking	_			N/A	N/A			N/A			None	0	No	No	No	
I I	1 B Exterior next to Kitchen Storage Storage Closet "D" next to Small Hallway to	No	W4	Concrete		None						-					None	0		No	No	
1 1	1 B Exterior next to Kitchen Storage Storage Closet "D" next to Small Hallway to	No	Ceiling	Concrete		None				N/A			-			, i i i i i i i i i i i i i i i i i i i	None	0	No	No	No	
1 1	I B Exterior riext to Ritcherr Storage	No	Floor W1		N/A White	None	N/A	N/A N/A	N/A		N/A	N/A N/A	N/A N/A	N/A N/A	N/A	N/A	None	0		No		
1 1	1 B Storage next to Classroom 5	No	W1	N/A	N/A	N/A		N/A	N/A	Door Frame	Metal	White	Chipping	1	0.24	Negative	None	0	No		No	
1 1	1 B Storage next to Classroom 5	No	W3	Concrete	White	Cracking	4	0.3	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	
	B Storage next to Classroom 5 B Storage next to Classroom 5			Concrete	White		0	N/A	N/A	N/A		N/A	N/A	N/A	N/A	N/A		0				
1 1 0	1 B Storage next to Classroom 5	No	Floor	Concrete	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No		No	
1 1	 B Storage Closet "E" next to Classroom 5 	No	W1	N/A	N/A	N/A	N/A	N/A N/A	N/A	Door Frame	Metal	White		2	0.29	Negative	None	0	No		No	
1 1 0 000000000000000000000000000000000000	 B Storage Closet "E" next to Classroom 5 	No	W3	Concrete	White	Cracking	0	0.28	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	
1 1	1 B Storage Closet "E" next to Classroom 5	No	W4	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0				
1 1 0	1 B Storage Closet "E" next to Classroom 5	No	Floor	Concrete	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	
1 1 0	1 B Classroom 5 1 B Classroom 5	Yes	W1	N/A	N/A	N/A		N/A	N/A	Door Frame	Metal	White	Chipping	2	2.5	Negative	None	0	Prior to Repair		No	
1 1 5	1 B Classroom 5 1 B Classroom 5	Yes	W2 W3			Cracking	4	0.32	Negative Negative	N/A N/A	N/A N/A		N/A N/A	N/A N/A	N/A N/A	N/A N/A		0	Prior to Repair Prior to Repair	No		
1 1 0	1 B Classroom 5		W3				5	0.4	Negative	N/A	N/A		N/A	N/A		N/A		0		No		
1 1 1 0	1 B Classroom 5	Yes	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	I N/A	None	0	No		No	
1 1	1 B Classroom 5 1 B Kitchen Storage				N/A White		0 4	N/A 0.02	N/A Negative	N/A N/A	N/A N/A		N/A N/A	N/A N/A		N/A N/A		0				
1 1	1 B Kitchen Storage	Yes			N/A	N/A	N/A	N/A	N/A	Door Frame	Metal		Chipping N/A	1 N/A	0.46	Negative	None	0	No	No	No	
1 1	1 B Kitchen Storage	Yes	W3	Concrete	White	Flaking	7	0.02	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	
1 1 0	1 B Kitchen Storage	Yes		Concrete	White	Cracking	N/A 1	0		N/A	N/A	N/A	N/A	4 N/A	N/A	N/A		0				
1 1 0 Depic 0 Opec 1 0 Depic No No No No No </td <td>1 B Kitchen Storage</td> <td>Yes</td> <td>Ceiling</td> <td></td> <td>White N/A</td> <td>Cracking</td> <td>3</td> <td>0.02 N/A</td> <td>Negative N/A</td> <td>N/A N/A</td> <td>N/A N/A</td> <td>N/A N/A</td> <td>N/A N/A</td> <td>N/A N/A</td> <td>N/A N/A</td> <td>N/A N/A</td> <td>None</td> <td>0</td> <td></td> <td></td> <td></td> <td>Floor Tile</td>	1 B Kitchen Storage	Yes	Ceiling		White N/A	Cracking	3	0.02 N/A	Negative N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	None	0				Floor Tile
1 1 0 Description 0 Description 0 Description 0 0 0 0	1 B Kitchen	Yes	W1	Concrete		Cracking	2	0					N/A	N/A		N/A	None	0				
1 1 0 Chain Num	1 B Kitchen 1 B Kitchen	Yes	W2	Concrete	White	Efflorescence	4	0	Negative	N/A	N/A	N/A	N/A	Z N/A	N/A	N/A	None	0	No	Steam leak	Yes	
1 1 0 Chain Num	1 B Kitchen 1 B Kitchen	Yes Yes	W2 W3	N/A	N/A White	N/A	N/A 0	N/A N/A	N/A	Radiator cover N/A	Metal N/A	Red N/A	Chipping N/A	2 N/A	0.6 N/A	Negative N/A		0	No	No	No	
1 0	1 B Kitchen	Yes		N/A	N/A	N/A		N/A	N/A	Door Frame	Metal	Red	Chipping	3	0.34	Negative		0				
1 0 0 0 N	1 B Kitchen	Yes	Ceiling	Concrete	White	Cracking	7	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	
1 8 Cascond Yas Yas <td>1 B Classroom 4</td> <td>Yes</td> <td>W1</td> <td>Concrete</td> <td>White</td> <td>Flaking</td> <td>15</td> <td>0.02</td> <td>Negative</td> <td>N/A</td> <td>N/A N/A</td> <td>N/A</td> <td>N/A N/A</td> <td>N/A N/A</td> <td>N/A</td> <td>N/A N/A</td> <td>None</td> <td>0</td> <td>Prior to Repair</td> <td>No</td> <td>No</td> <td></td>	1 B Classroom 4	Yes	W1	Concrete	White	Flaking	15	0.02	Negative	N/A	N/A N/A	N/A	N/A N/A	N/A N/A	N/A	N/A N/A	None	0	Prior to Repair	No	No	
1 1	1 B Classroom 4 1 B Classroom 4	Yes	W1 W2	N/A Concrete	N/A White	N/A Cracking	N/A 12	N/A 0.04	N/A Negative		Metal N/A	Red N/A	Chipping N/A	1 N/A	0.25 N/A	Negative N/A	None	0	Prior to Repair Prior to Repair	No		
1 1	1 B Classroom 4	Yes	W3	Concrete	White	Flaking		0.01	Negative	N/A	N/A Matal	N/A	N/A		N/A		None	0	Prior to Repair	No	No	
1 8 Classroon 4 Yrs Proc Centro Tent Best of the set of the se	1 B Classroom 4	Yes	W4	Concrete	White	Cracking	2	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Prior to Repair		No	
1 1 0 Calebra mark bildbarn Yes With Number 0 Number N	1 B Classroom 4	Yes	Floor	Ceramic Tile	Beige	None	9	0 N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	
1 0 Carbon Yes W4 Concrete White Chipping 1.5 0.02 Negative NA N/A	1 B Cafeteria next to Kitchen	Yes	W1	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A N/A	N/A	N/A N/A	None	0	No	No	No	
1 B Definition reads Distance Data	1 B Cafeteria next to Kitchen	Yes	W3	Concrete	White	Chipping		0.02	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No			
1 5 Calibration location The image of the image	1 B Cafeteria next to Kitchen	Yes	Ceiling	Concrete	White	Cracking	20	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No		
1 B Calebra nexts Classcond 4 Ves W1 Concrete White Chipping 30 0.02 Negative N/A	I B Caleteria next to Kitchen	Yes	Floor	Concrete	N/A	None	N/A 0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No		No	
1 8 Caffeterinancto Classroom 4 Yes With Concrete White Chipping 6 0 NA NA NA N/A	1 B Cafeteria next to Classroom 4	Yes	W1	Concrete	White	Chipping		0.02	Negative	N/A	N/A N/A	N/A	N/A	N/A N/A	N/A	I N/A	None	0	No	No	No	
1 B Calterian extr Colassroom 4 Yes Celling N/A N/A <	1 B Cafeteria next to Classroom 4	Yes	W3	Concrete	White	Chipping	6	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	Ő	No	No	No	
1 B Calterian extr Colassroom 4 Yes Celling N/A N/A <	 B Cafeteria next to Classroom 4 	Yes	Ceiling	Concrete	White	Chipping	12	0.02	Negative	N/A N/A	N/A	N/A	N/A N/A	N/A N/A	N/A	N/A N/A	None	0				
1 8 Cafetrianext Stainvell Yes Yes Yes Operation of the Stainvell Yes Wes Operation of the Stainvell Yes Wes Operation of the Stainvell Name	1 B Cafeteria next to Classroom 4 1 B Cafeteria next to Classroom 4	Yes	Ceiling Floor	N/A Concrete	N/A N/A	N/A None	N/A 0	N/A N/A	N/A N/A	Pipe Insulation N/A	N/A		Cracking N/A		0.45 N/A			0	No No	No No	No	
1 B Cafferin exity Stainveil Yes Vi3 Concrete White None 0 No No No 1 B Cafferin exity Stainveil Yes Visit Chrorete White Chriping 1.2 0.2 Nogative NA N/A	1 B Cafeteria next to Stairwell	Yes	W1	Concrete		Chipping					N/A		N/A			N/A		0				
1 B Cafetrianexto Stainveil Yes Celling Concrete White Cracking S 0.04 Negative N/A	1 B Cafeteria next to Stairwell	Yes	W3	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	ŏ	No	No	No	
1 B Cafetria next D Starveil Yes Celling NA	 B Cafeteria next to Stairwell 	Yes	Ceiling	Concrete	White	Cracking	8	0.04	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	
I B Casaroon 18 Yes Vit None O N/A N/A<	B Cafeteria next to Stairwell B Cafeteria next to Stairwell	Yes	Ceiling	N/A	N/A N/A	N/A	N/A 0	N/A N/A	N/A	Pipe Insulation	N/A N/A	White	Cracking	20 N/A	0.39 N/A	Negative	None	0		No		
I B Classroom 1B Yes W1 Concrete W1/Le None 0 N/A <	1 B Classroom 1B		W1							N/A				N/A				n	Partially	No	No	
1 B Classroom 1B Yes Visit Concrete White None 0 N/A N/A <td>1 B Classroom 1B</td> <td>Yes</td> <td></td> <td>N/A</td> <td>N/A</td> <td>N/A</td> <td></td> <td>N/A</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td>2</td> <td></td> <td></td> <td></td> <td>0</td> <td>No</td> <td>No</td> <td></td> <td></td>	1 B Classroom 1B	Yes		N/A	N/A	N/A		N/A						2				0	No	No		
I B Caseroon 18 Yes Wa NAA NAA NAA Door Frame Metal White Chipping 1 D. 3.5 Negative None 0 None None None 1 B Caseroon 18 Yes V4 Concrete White None 0 N/A																		0	Inaccessible		No	
1 B Classroom 18 Yes W3 NA														N/A				0	Partially Partially			
1 B Classroom 1B Yes Ceiling Concrete White None 0 N/A														1 N/A				0	Inaccessible			
	1 B Classroom 1B	Yes	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0 C	No	No	No	
1 B (Electrical Room No W1 Concrete White None O N/A	1 B Classroom 1B 1 B Electrical Room	Yes No	Floor W1	Concrete	White	None	0	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	None	0	No	No	NO	

										hool Dis												
										Safe Certifi												
			-						F.	S. Edmon	ds Eleme	ntary Sc	hool						D. (1 = 100 10		
	Name of Inspector: Ryan Hutse Inspection Company: Synertect		-															ULCS# 621	Dates: 06/11- 06/	15/2019		
E	inspection company. cyneneel																		.			
e	F								Primary							Additional						
m	1	Student Teacher				Description of	Primary		Component XRF				Description of	Additional		Component XRF	Debris Present			0	Plastering	
e n	0	Occupied	Primary	Substrate		Description of Primary	Component Damage	XRF Reading	(positive/	Additional	Substrate		Paint and Plaster	Component Damage	XRF Reading	(positive/	(describe		Contents Need to	On-going Moisture	Needed (yes or	
t	r On-Site Room Name	(yes/no)	Component	Material	Color	Damage	Quantity (sf)	(mg/cm2)	negative)	Component	Material	Color	Damage	Quantity (sf)	(mg/cm2)	negative)	location)	Quantity (sf)	be Moved	Intrusion	no)	Comments/ Description/ Notes
1	B Electrical Room B Electrical Room	No	W2 W3	Concrete Concrete	White White	None	0	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	None None	0	No	No	No	
1	B Electrical Room	No	W4	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	
1	B Electrical Room B Electrical Room	No	Ceiling Floor	Concrete Concrete	White Grey	None None	0	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	None	0	No	No	No	
			W1						N/A	N/A	N/A		N/A	N/A					No		No	Ceramic Tile - Not damaged, but
1	B Stairwell next to Cafeteria	Yes		Ceramic Tile	Tan	None	U	N/A			-	N/A		N/A	N/A	N/A	None	0		No		glazing is positive Ceramic Tile - Not damaged, but
1	B Stairwell next to Cafeteria	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door	Metal	Brown	Chipping	2	0.1	Negative	None	0	No	No	No	glazing is positive Ceramic Tile - Not damaged, but
1	B Stairwell next to Cafeteria	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	Brown	Chipping	2	4	Positive	None	0	No	No	No	glazing is positive
1	B Stairwell next to Cafeteria B Stairwell next to Cafeteria	Yes Yes	W2 W2	Ceramic Tile N/A	Tan N/A	None N/A	0 N/A	N/A N/A	N/A N/A	N/A Radiator Cover	N/A Metal	N/A Brown	N/A Chipping	N/A	N/A	N/A Positive	None None	0	No	No	No	
		Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A	Hand Rail	Metal	Brown N/A	Chipping	1	3.7	Positive	None	0	No	No	No	
1	B Stainweil next to Cafeteria B Stainweil next to Cafeteria B Stainweil next to Cafeteria	Yes Yes	W3 W3	Ceramic Tile N/A	Tan N/A	None N/A	0 N/A	N/A N/A	N/A N/A	N/A Door	N/A Metal	N/A Brown	N/A Chipping	N/A 2	N/A 0.1	N/A Negative	None	0	No	No	No	
1	B Stairwell next to Cafeteria	Yes	W3	N/A	N/A	N/A	N/A N/A	N/A	N/A	Door Frame	Metal	Brown	Chipping	2	4	Positive	None	0	No	No	No	
1	B Stairwell next to Cafeteria B Stairwell next to Cafeteria B Stairwell next to Cafeteria Stairwell next to Cafeteria Stairwell next to Cafeteria	Yes Yes	W4 W4	Ceramic Tile N/A	Tan N/A	None N/A	0 N/A	N/A N/A	N/A N/A	N/A Radiator Cover	N/A Metal	N/A Brown	N/A Chipping	N/A 2	N/A 1.1	N/A Positive	None None	0	No	No	No No	
		Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A	Hand Rail	Metal	Brown N/A	Chipping	1	3.8	Positive	None	ő	No	No	No	
1	B Stairwell next to Cafeteria B Stairwell next to Cafeteria	Yes Yes	Ceiling Floor	Metal Concrete	Brown Grey	None	0	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	None None	0	No	No	No	
		Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	Stair stringer	Metal	Brown	Chipping	10	4.5	Positive	None	ő	No	No	No	
1	B Stainweil next to Cafeteria B Stainweil next to Cafeteria B Stainweil next to Cafeteria	Yes	Floor Floor	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	Stair riser Newel posts	Metal Metal	Brown Brown	Chipping Chipping	8	2.7	Positive Positive	None	0	No	No	No	
1	B Stairwell next to Cafeteria	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	Stair Spindles	Metal	Brown	Chipping	20	4.2	Positive	None	0	No	No	No	
	B Stairwell next to Boiler Room	Yes	W1	Ceramic Tile	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	Ceramic Tile - Not damaged, but glazing is positive
										2						Newser					No	Ceramic Tile - Not damaged, but
1	B Stairwell next to Boiler Room	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door	Metal	Brown	Chipping	2	0.1	Negative	None	U	No	No		glazing is positive Ceramic Tile - Not damaged, but
1	B Stairwell next to Boiler Room	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	Brown N/A	Chipping N/A	2 N/A	4	Positive N/A	None	0	No	No	No	glazing is positive
1	B Stairwell next to Boiler Room B Stairwell next to Boiler Room	Yes	W2 W2	Ceramic Tile N/A	Tan N/A	None N/A	N/A	N/A N/A	N/A N/A	N/A Radiator Cover	N/A Metal	Brown	Chipping	N/A 2	N/A 0.9	Positive	None	0	No	No	No	
1	B Stairwell next to Boiler Room	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A	Hand Rail	Metal	Brown	Chipping	1	3.7	Positive	None	0	No	No	No	
	B Stairwell next to Boiler Room B Stairwell next to Boiler Room	Yes Yes	W3 W3	Ceramic Tile N/A	Tan N/A	None N/A	N/A	N/A N/A	N/A N/A	N/A Door	N/A Metal	N/A Brown	N/A Chipping	N/A 2	N/A 0.1	N/A Negative	None	0	No	No	No	
1	B Stairwell next to Boiler Room	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	Brown	Chipping	2	4	Positive	None	0	No	No	No	
1	B Stairwell next to Boiler Room B Stairwell next to Boiler Room	Yes Yes	W4 W4	Ceramic Tile N/A	Tan N/A	None N/A	0 N/A	N/A N/A	N/A N/A	N/A Radiator Cover	N/A Metal	N/A Brown	N/A Chipping	N/A	N/A	N/A Positive	None	0	No	No	No	
1	B Stairwell next to Boiler Room	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A	Hand Rail	Metal	Brown	Chipping Chipping	2	3.7	Positive	None	0	No	No	No	
	B Stairwell next to Boiler Room B Stairwell next to Boiler Room	Yes Yes	Ceiling Floor	Metal Concrete	Brown Grey	None	0	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	None	0	No	No	No	
1	B Stairwell next to Boiler Room	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	Stair stringer	Metal	Brown	Chipping	12	4.3	Positive	None	0	No	No	No	
1	B Stairwell next to Boiler Room B Stairwell next to Boiler Room	Yes Yes	Floor	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	Stair riser Newel posts	Metal Metal	Brown Brown	Chipping	8	2.9	Positive Positive	None	0	No	No	No	
1	B Stairwell next to Boiler Room	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	Stair Spindles	Metal	Brown	Chipping	18	4	Positive	None	0	No	No	No	
1	B Hallway from Boiler Room to Exit B Hallway from Boiler Room to Exit	Yes Yes	W1 W2	Concrete Concrete	White White	Chipping None	12	0 N/A	Negative N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	None	0	No	No	No	
1	B Hallway from Boiler Room to Exit	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	Brown	Chipping	3	0.4	Negative	None	Ö	No	No	No	
1	B Hallway from Boiler Room to Exit B Hallway from Boiler Room to Exit	Yes Yes	W3 W3	Concrete N/A	White N/A	Chipping N/A	10 N/A	0.02 N/A	Negative N/A	N/A Door	N/A Metal	N/A Brown	N/A Chipping	N/A	N/A	N/A Negative	None	0	No	No	No	
1	B Hallway from Boiler Room to Exit	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	Brown	Chipping	4	0.38	Negative	None	Ö	No	No	No	
1	B Hallway from Boiler Room to Exit B Hallway from Boiler Room to Exit	Yes Yes	W4 Ceiling	Concrete	White White	None Cracking	6	N/A 0.02	N/A Negative	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	None	0	No	No	No	
1	B Hallway from Boiler Room to Exit	Yes	Floor	Concrete	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	Floor Tile
1	Small Hallway to Exterior next to Kitchen B Storage	Yes	W1	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	
	Small Hallway to Exterior next to Kitchen B Storage	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	Brown	Chipping	2	0.27	Negative	None	0	No	No	No	
	Small Hallway to Exterior next to Kitchen	Yes	w2	Concrete	White			N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A			No		No	
1	B Storage Small Hallway to Exterior next to Kitchen					None	U			1007	10/1			1673			None	0		IND	110	
	B Storage Small Hallway to Exterior next to Kitchen	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	No Wall
1	B Storage Small Hallway to Exterior next to Kitchen	Yes	W4	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	
1	Small Hallway to Exterior next to Kitchen B Storage	Yes	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	
	B Storage Small Hallway to Exterior next to Kitchen B Storage	Yes	Floor	Concrete	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	
1	B Hallway from Classroom 5 to Crawl Space	Yes	W1	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	
1	B Hallway from Classroom 5 to Crawl Space B Hallway from Classroom 5 to Crawl Space	Yes	W1 W1	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	Door Door Frame	Metal Metal	Brown Brown	Chipping	3	0.25	Negative Negative	None	0	No	No	No	
1	B Hallway from Classroom 5 to Crawl Space	Yes	W2	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	
1	B Hallway from Classroom 5 to Crawl Space B Hallway from Classroom 5 to Crawl Space	Yes Yes	W3 W4	Concrete Concrete	White White	None	0	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	None None	0	No No	No	No No	
1	B Hallway from Classroom 5 to Crawl Space	Yes	Ceiling	Concrete	White	None	Ő	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	ō	No	No	No	
1	B Hallway from Classroom 5 to Crawl Space Storage Room at the End of Hallway Storage Room at the End of Hallway	Yes No	Floor W1	Concrete Concrete	N/A White	None	0	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	None	0	No Prior to Repair	No	No	
1	B Storage Room at the End of Hallway	No	W2	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Prior to Repair	No	No	
1	B Storage Room at the End of Hallway B Storage Room at the End of Hallway	No	W3 W4	Concrete	White	None	0	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	None	0	Prior to Repair Prior to Repair	No	No	
1	B Storage Room at the End of Hallway	No	Ceiling	Concrete	White	None	ŏ	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	ŏ	No	No	No	
1	B Storage Room at the End of Hallway	No	Floor	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	Ceramic Tile - Not damaged, but
1	1 Stairwell across from Classroom 115	Yes	W1	Ceramic Tile	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	glazing is positive
1	1 Stairwell across from Classroom 115	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door	Metal	Brown	Chipping	2	0.14	Negative	None	0	No	No	No	Ceramic Tile - Not damaged, but glazing is positive
		Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A		Metal	Brown		-	3.5	Positive			No	Ne	No	Ceramic Tile - Not damaged, but glazing is positive
1	Stairwell across from Classroom 115 Stairwell across from Classroom 115	Yes Yes	W1 W2	N/A Ceramic Tile	N/A Tan	N/A None	N/A 0	N/A N/A	N/A N/A	Door Frame N/A	Metal N/A	Brown N/A	Chipping N/A	1 N/A	3.5 N/A	Positive N/A	None None	0	No	No	No	glazing is positive
1	1 Stairwell across from Classroom 115	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A	Radiator Cover	Metal	Brown	Chipping	4	0.8	Positive	None	0	No	No	No	
1	Stairwell across from Classroom 115 Stairwell across from Classroom 115	Yes Yes	W2 W3	N/A Ceramic Tile	N/A Tan	N/A None	N/A 0	N/A N/A	N/A N/A	Hand Rail N/A	Metal N/A	Brown N/A	Chipping N/A	1 N/A	4.1 N/A	Positive N/A	None	0	No	No No	No	
1	Stairwell across from Classroom 115 Stairwell across from Classroom 115	Yes	W3	N/A	N/A	N/A	N/A	N/A N/A	N/A	Door	Metal	Brown	Chipping	2	0.15	Negative	None	0	No	No	No	
	I courrent across from Classroom 115	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	Brown	Chipping	2	3.9	Positive	None	1 0	NO	No	No	1

										nool Dist												
										afe Certifi												
	Name of Inspector: Ryan Hutse	11							F.	S. Edmon	ds Eleme	ntary Sc	hool					Inspection	Dates: 06/11- 06/	15/2019		
	Inspection Company: Synertech	ı 1					•							•				ULCS# 621		10/2013		
E P m e n t	F I 0 0 7 0 0 0 Site Room Name 1 1 0 	Student Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)	Additional Component	Substrate Material	Color	Description of Paint and Plaster Damage	Additional Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Additional Component XRF (positive/ negative)	Debris Present (describe location)	Quantity (sf)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Comments/ Description/ Notes
1	Stairwell across from Classroom 115 Stairwell across from Classroom 115	Yes Yes	W4 W4	Ceramic Tile N/A	Tan N/A	None N/A	N/A	N/A N/A	N/A N/A	N/A Radiator Cover	N/A Metal	N/A Brown	N/A Chipping	N/A 4	N/A 1	N/A Positive	None None	0	No	No No	No No	
1	Stairwell across from Classroom 115 Stairwell across from Classroom 115	Yes Yes	W4 Ceiling	N/A Metal	N/A Brown	N/A None	N/A 0	N/A N/A	N/A N/A	Hand Rail N/A	Metal N/A	Brown N/A	Chipping N/A	1 N/A	4.2 N/A	Positive N/A	None None	0	No	No	No	
1	Stairwell across from Classroom 115 Stairwell across from Classroom 115	Yes Yes	Floor	Concrete N/A	Grey N/A	None N/A	0 N/A	N/A N/A	N/A N/A	N/A	N/A Metal	N/A Brown	N/A	N/A	N/A 4.6	N/A Positive	None None	0	No	No No	No	
1	1 Stairwell across from Classroom 115	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	Stair stringer Stair riser	Metal	Brown	Chipping Chipping	6	4	Positive	None	0	No	No	No	
1	Stairwell across from Classroom 115 Stairwell across from Classroom 115	Yes	Floor	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	Newel posts Stair Spindles	Metal	Brown Brown	Chipping Chipping	3	3.8	Positive	None	0	No	No	No	
1	1 Stairwell next to Classroom 111	Yes	W1	Ceramic Tile	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	Ceramic Tile - Not damaged, but glazing is positive Ceramic Tile - Not damaged, but
1	Stainwell next to Classroom 111 Stainwell next to Classroom 111	Yes	W1	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	Door Door Frame	Metal Metal	Brown	Chipping	2	0.1	Negative Positive	None	0	No	No	No	glazing is positive Ceramic Tile - Not damaged, but glazing is positive
1	1 Stairwell next to Classroom 111	Yes	W2	Ceramic Tile	Tan	None	0	N/A N/A	N/A	N/A	N/A Metal	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	2. 2.1
1 1	Stairwell next to Classroom 111 Stairwell next to Classroom 111	Yes Yes	W2 W2	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A	N/A N/A	Radiator Cover Hand Rail	Metal	Brown Brown	Chipping Chipping	1	3.7	Positive Positive	None None	0	No	No No	No No	
1	Stairwell next to Classroom 111 Stairwell next to Classroom 111 Stairwell next to Classroom 111	Yes Yes	W3 W3	Ceramic Tile N/A	Tan N/A	None N/A	0 N/A	N/A N/A	N/A N/A	N/A Door	N/A Metal	N/A Brown	N/A Chipping	N/A 2	N/A 0.2	N/A Negative	None None	0	No	No No	No	
1	1 Stairwell next to Classroom 111	Yes	W3	N/A	N/A	N/A	N/A 0	N/A	N/A N/A	Door Frame	Metal N/A	Brown	Chipping	2	3.4	Positive	None	0	No	No	No	
1	Stairwell next to Classroom 111 Stairwell next to Classroom 111	Yes Yes	W4 W4	Ceramic Tile N/A	Tan N/A	None N/A	N/A	N/A N/A	N/A	N/A Radiator Cover	Metal	N/A Brown	N/A Chipping	N/A 2	N/A 1.5	N/A Positive	None None	0	No No	No No	No No	
1	Stairwell next to Classroom 111 Stairwell next to Classroom 111	Yes Yes	W4 Ceiling	N/A Metal	N/A Brown	N/A None	N/A	N/A N/A	N/A N/A	Hand Rail N/A	Metal N/A	Brown N/A	Chipping N/A	1 N/A	4.1 N/A	Positive N/A	None None	0	No	No	No	
1	1 Stairwell next to Classroom 111	Yes	Floor	Concrete	Grey	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	Ő	No	No	No	
1	Stairwell next to Classroom 111 Stairwell next to Classroom 111	Yes Yes	Floor Floor	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	Stair stringer Stair riser	Metal Metal	Brown Brown	Chipping Chipping	10	2.8	Positive Positive	None	0	No	No No	No	
1	Stairwell next to Classroom 111 Stairwell next to Classroom 111 Stairwell next to Classroom 111	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	Newel posts	Metal	Brown	Chipping	4	4.3	Positive	None	0	No	No	No	
1	Stairwell next to Classroom 111 Teacher's Lounge 115A next to Classroom 115	Yes Yes	Floor W1	N/A Concrete	N/A White/Tan	N/A None	N/A 0	N/A N/A	N/A N/A	Stair Spindles N/A	Metal N/A	Brown N/A	Chipping N/A	20 N/A	4.5 N/A	Positive N/A	None None	0	No No	No No	No No	
1	Teacher's Lounge 115A next to Classroom 115 Teacher's Lounge 115A next to Classroom 115	Yes Yes	W2 W3	Concrete Concrete	White/Tan White/Tan	None None	0	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	None None	0	No	No	No	
1	1 Teacher's Lounge 115A next to Classroom 115	Yes	W4	Concrete	White/Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	
1	Teacher's Lounge 115A next to Classroom 115 Teacher's Lounge 115A next to Classroom 115	Yes	Ceiling Floor	Concrete Concrete	White/Tan White/Tan	None None	0	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	None None	0	No	No No	No	
1	Storage Closet inside Teacher's Lounge 115A 1 next to Classroom 115	Yes	W1	Concrete	White/Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Prior to Repair	No	No	
1	Storage Closet inside Teacher's Lounge 115A next to Classroom 115	Yes	W2	Concrete	White/Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Prior to Repair	No	No	
1	Storage Closet inside Teacher's Lounge 115A 1 next to Classroom 115	Yes	W3	Concrete	White/Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Prior to Repair	No	No	
1	Staff Restroom inside Teacher's Lounge 115A 1 next to Classroom 115	Yes	W4	Concrete	White/Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	Ö	No	No	No	
1	Staff Restroom inside Teacher's Lounge 115A 1 next to Classroom 115	Yes	Ceiling	Concrete	White/Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	ō	No	No	No	
1	Staff Restroom inside Teacher's Lounge 115A 1 next to Classroom 115	Yes	Floor	Concrete	White/Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	
1	Storage 118 next to Boy's Restroom across from Classroom 115 Storage 118 next to Boy's Restroom across	Yes	W1	Concrete	White/Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Partially Inaccessible Partially	No	No	
1	1 from Classroom 115 Storage 118 next to Boy's Restroom across	Yes	W2	Concrete	White/Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Inaccessible	No	No	
1	1 from Classroom 115 Storage 118 next to Boy's Restroom across	Yes	W3	Concrete	White/Tan	None	0	N/A	N/A	N/A N/A	N/A N/A	N/A	N/A	N/A N/A	N/A	N/A	None	0	Inaccessible Partially	No	No	
1	from Classroom 115 Storage 118 next to Boy's Restroom across from Classroom 115	Yes	W4 Ceiling	Concrete	White/Tan White/Tan	None	0	N/A N/A	N/A N/A	N/A N/A	N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	None	0	Inaccessible	No	No	
1	Storage 118 next to Boy's Restroom across 1 from Classroom 115	Yes	Floor	Concrete	White/Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	Ceramic Tile - Not damaged, but
1	1 Boy's Restroom across from Classroom 115	Yes	W1	Ceramic Tile	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	glazing is positive
1	Boy's Restroom across from Classroom 115 Boy's Restroom across from Classroom 115	Yes	W2 W3	Ceramic Tile Ceramic Tile	Tan Tan	None	0	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	None None	0	No	No No	No	
1	1 Boy's Restroom across from Classroom 115	Yes	W4	Ceramic Tile	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	
1	1 Boy's Restroom across from Classroom 115	Yes Yes	W4 W4	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	Columns Radiator Cover	Concrete Metal	White Brown	Chipping Chipping	2	0.04	Negative Negative	None None	0	No No	No No	No No	
1	Boy's Restroom across from Classroom 115 Boy's Restroom across from Classroom 115	Yes Yes	Ceiling Floor	Concrete Ceramic Tile	White N/A	None None	0	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	None None	0	No	No	No	
1	1 Girl's Restroom across from Classroom 115	Yes	W1	Ceramic Tile	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	Ceramic Tile - Not damaged, but glazing is positive
1	Girl's Restroom across from Classroom 115 Girl's Restroom across from Classroom 115	Yes Yes	W2 W3	Ceramic Tile Ceramic Tile	Tan Tan	None None	0	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	None None	0	No	No No	No	
1	1 Girl's Restroom across from Classroom 115 1 Girl's Restroom across from Classroom 115	Yes	W4 W4	Ceramic Tile N/A	Tan N/A	None N/A	0 N/A	N/A N/A	N/A N/A	N/A Columns	N/A Concrete	N/A White	N/A Chipping	N/A	N/A 0	N/A Negative	None None	0	No	No	No	
1	1 Girl's Restroom across from Classroom 115	Yes	W4	N/A	N/A	N/A	N/A N/A	N/A	N/A	Radiator Cover	Metal	Brown	Chipping	1	0.5	Negative	None	0	No	No	No	
1	Girl's Restroom across from Classroom 115 Girl's Restroom across from Classroom 115	Yes Yes	Ceiling Floor	Concrete Ceramic Tile	White N/A	None None	0	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	None None	0	No	No No	No	
1	Storage between Restrooms across from 1 Classroom 115	Yes	W1	Concrete	Tan	Cracking	3	0.05	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Prior to Repair	No	No	
1	Storage between Restrooms across from Classroom 115 Storage between Restrooms across from	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	White	Chipping	1	0.2	Negative	None	0	Prior to Repair	No	No	
1	1 Classroom 115 Storage between Restrooms across from	Yes	W2	Concrete	Tan	Cracking	1	0.02	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Prior to Repair	No	No	
1	Classroom 115 Storage between Restrooms across from Classroom 116	Yes	W3 W4	Concrete	Tan Tan	Cracking	4	0	Negative	N/A N/A	N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	None	0	Prior to Repair	No	No	
1	Classroom 115 Storage between Restrooms across from Classroom 115	Yes	W4 Ceiling	Concrete	Tan Tan	Cracking Cracking	3	0.02	Negative Negative	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	None	0	Prior to Repair No	No	No	
1	Storage between Restrooms across from Classroom 115	Yes	Floor	Concrete	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	
1	1 Classroom 115	Yes	W1	Concrete	White/Tan	Cracking	4	0.03	Negative	N/A	N/A	N/A	N/A	N/A N/A	N/A	N/A	None	0	Prior to Repair	No	No	
1	1 Classroom 115 1 Classroom 115	Yes Yes	W1 W2	N/A Concrete	N/A White/Tan	N/A Efflorescence	N/A 1	N/A 0.04	N/A Negative	Door Frame N/A	Metal N/A	White N/A	Chipping N/A	2 N/A	0.2 N/A	Negative N/A	None None	0	Prior to Repair Prior to Repair	No No	No	
1	1 Classroom 115	Yes	W3	Concrete	White/Tan N/A	Flaking	4 N/A	0.02	Negative N/A	N/A	N/A Metal	N/A	N/A	N/A	N/A 0.45	N/A N/A	None	0	Prior to Repair	No	No	
1	1 Classroom 115 1 Classroom 115	Yes Yes	W3 W4		N/A White/Tan	N/A Flaking	N/A 7	N/A 0.02	N/A Negative	Pipe Riser N/A	Metal N/A	White N/A	Flaking N/A	2 N/A	0.45 N/A	Negative N/A	None None	0	Prior to Repair Prior to Repair	No No	No	

										hool Dist afe Certifi												
										S. Edmon												
	Name of Inspector: Ryan Hutsel	1							г.	S. Eumon	us ciemei	itary Sc						Inspection [Dates: 06/11- 06/	15/2019		
	Inspection Company: Synertech													-				ULCS# 6210			_	
E I e n t 1	o On-Site Room Name	Student Teacher Occupied (yes/no) Yes	Primary Component Ceiling	Substrate Material Concrete	Color White	Description of Primary Damage Efflorescence	Primary Component Damage Quantity (sf) 21	XRF Reading (mg/cm2) 0.02	Primary Component XRF (positive/ negative) Negative N/A	Additional Component N/A	Substrate Material N/A	Color N/A	Description of Paint and Plaster Damage N/A	Additional Component Damage Quantity (sf) N/A	XRF Reading (mg/cm2) N/A	Additional Component XRF (positive/ negative) N/A	Debris Present (describe location) None	Quantity (sf)	Contents Need to be Moved No	On-going Moisture Intrusion Unknown	Plastering Needed (yes or no) No	Comments/ Description/ Notes Additional Cracking
1	1 Classroom 115 1 Classroom 116	Yes Yes	Floor W1	Concrete Concrete	N/A White	None Cracking	0	N/A	N/A Negative	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	None	0	No Prior to Repair	No	No	Floor Tile
1	1 Classroom 116	Yes	W1	Plaster	White	Cracking	1	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Prior to Repair	No	No	
1	1 Classroom 116 1 Classroom 116	Yes Yes	W1 W1	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	Door Frame Pipe Riser	Metal	White White	Chipping Flaking	3	0.7	Positive Negative	None	0	Prior to Repair Prior to Repair	No	No	
1	1 Classroom 116	Yes	W2	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Prior to Repair	No	No	
1	1 Classroom 116 1 Classroom 116	Yes	W3	Concrete N/A	White N/A	Cracking N/A	3	0.02 N/A	Negative N/A	N/A Radiator Cover	N/A Metal	N/A White	N/A	N/A	N/A	N/A	None	0	Prior to Repair	No	No	
1	1 Classroom 116	Yes Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A	Pipe Riser N/A	Metal	White	Chipping Flaking	3	0.55	Negative Negative N/A	None	0	Prior to Repair Prior to Repair	No	No	
1	1 Classroom 116	Yes	W4	Concrete	White White	Cracking	2	0.02	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Prior to Repair	No	No	
1	1 Classroom 116 1 Classroom 116	Yes Yes	Ceiling Floor	Concrete Concrete	N/A	Cracking None	0	0 N/A	Negative N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	None None	0	No No	No	No	Floor Tile
1 1	1 Classroom 113	Yes	W1	Concrete	White/Tan White	Cracking Flaking	2	0	Negative	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	None N/A	0 N/A	Prior to Repair	No	No	
1	1 Classroom 113 1 Classroom 113	Yes Yes	W1 W1	Plaster N/A	White N/A	Flaking N/A	4 N/A	0 N/A	Negative N/A	N/A Pipe Riser	N/A Metal	N/A White	N/A Chipping	N/A 2	0.3	N/A Negative	N/A None	N/A 0	Prior to Repair Prior to Repair	No	No	
1	1 Classroom 113	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	White	Chipping	2	0.28	Negative	None	0	Prior to Repair	No	No	
	1 Classroom 113 1 Classroom 113	Yes Yes	W2 W3	Concrete Concrete	White/Tan White/Tan	Cracking Cracking	2	0	Negative Negative	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	None	0	Prior to Repair Prior to Repair	No	No	
1	1 Classroom 113	Yes	W3	Concrete N/A	N/A	N/A	N/A	N/A	N/A	Radiator Cover	Metal	White	Chipping	1	0.8	Positive	None	ō	Prior to Repair	No	No	
1	1 Classroom 113 1 Classroom 113	Yes Yes	W3 W4	N/A Concrete	N/A White/Tan	N/A Chipping	N/A 2	N/A 0.02	N/A Negative	Pipe Riser N/A	Metal N/A	White N/A	Flaking N/A	5 N/A	0.62 N/A	Negative N/A	None None	0	Prior to Repair Prior to Repair	No	No	
1	1 Classroom 113	Yes	Ceiling	Concrete	White	Cracking	8	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	Ő	No	No	No	
1	1 Classroom 113 1 Classroom 114	Yes Yes	Floor W1	Concrete Concrete	N/A White	None None	0	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	None None	0	No Prior to Repair	No	No No	Floor Tile
1	1 Classroom 114 1 Classroom 114	Yes	W1	N/A	N/A	N/A	N/A	N/A N/A	N/A	Door Frame	Metal	White	Chipping	2	1.5	Positive	None	0	Prior to Repair	No	No	
1	1 Classroom 114	Yes	W2	Concrete	White	Flaking	10	0	Negativo	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Partially	No	No	
1	1 Classroom 114	Yes	W3	Concrete	White	Flaking	24	0.1	Negative Negative	N/A	N/A N/A	N/A	N/A	N/A N/A	N/A	N/A	None	0	Inaccessible Prior to Repair	No	No	Additional Cracking, Chipping
1	1 Classroom 114	Yes	W3 W3	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	Radiator Cover	Metal	White	Chipping	3	0.6	Negative	None	0	Prior to Repair	No	No	
	1 Classroom 114						N/A			Pipe Riser			Flaking	10		Negative		0	Prior to Repair Partially	No		
1		Yes	W4	Concrete	White	Flaking	8	0.08	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Inaccessible	No	No	
1	1 Classroom 114 1 Classroom 114	Yes Yes	Ceiling Floor	Concrete Concrete	White N/A	Flaking None	10	0.02 N/A	Negative N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	None None	0	No	Brick Pointing No	No	Additional Efflorescence Floor Tile
1	1 Nurse's Office	Yes	W1	Concrete	Yellow/White	Chipping	5	0.02	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	Ő	No	No	No	
1	1 Nurse's Office 1 Nurse's Office	Yes Yes	W2 W3	Concrete Concrete	Yellow/White Yellow/White	Chipping Chipping	3	0.02	Negative Negative	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	None	0	No No	No	No	
1	1 Nurse's Office	Yes	W4	Concrete	Yellow/White	Chipping	8	0.02	Negative	N/A	N/A	N/A	N/A	N/A N/A	N/A	N/A	None	0	No	No	No	
1	1 Nurse's Office	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A	Radiator Cover	Metal	White	Chipping	1	0.3	Negative	None	0	No	No	No	
1	1 Nurse's Office 1 Nurse's Office	Yes Yes	W4 Ceiling	N/A Concrete	N/A White	N/A None	N/A 0	N/A N/A	N/A N/A	Pipe Riser N/A	Metal N/A	White N/A	Flaking N/A	5 N/A	0.28 N/A	Negative N/A	None	0	No No	No	No	
1	Nurse's Office Office next to Nurse's Office	Yes	Floor	Concrete	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No Dries to Depois	No	No	
1	1 Office next to Nurse's Office	Yes Yes	W1 W2	Concrete Concrete	Tan/White Tan/White	Flaking Flaking	20	0.04	Negative Negative	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	None	0	Prior to Repair Prior to Repair	No	No	
1	Office next to Nurse's Office Office next to Nurse's Office Office next to Nurse's Office	Yes	W3	Concrete	Tan/White	Flaking	4	0.04	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	Ő	Prior to Repair	No	No	
	1 Office next to Nurse's Office 1 Office next to Nurse's Office	Yes Yes	W4 Ceiling	Concrete Concrete	Tan/White White	Flaking Flaking	14	0.06	Negative Negative	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	None	0	Prior to Repair No	No	No	
1	1 Office next to Nurse's Office	Yes	Floor	Concrete	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	Ő	No	No	No	
1	Storage next to Nurse's Office Storage next to Nurse's Office	Yes Yes	W1	Concrete N/A	White/Yellow N/A	Flaking N/A	4 N/A	0 N/A	Negative N/A	N/A Door Frame	N/A Metal	N/A White	N/A Chipping	N/A N/A	N/A N/A	N/A N/A	None N/A	0 N/A	Prior to Repair Prior to Repair	No	No	
1	1 Storage next to Nurse's Office	Yes	W1 W2	Concrete	White/Yellow	Flaking	N/A 12	0.02	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Prior to Repair	No	No	
1	1 Storage next to Nurse's Office	Yes	W3	Concrete	White/Yellow	Flaking	3	0.02	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Prior to Repair	No	No	
1	1 Storage next to Nurse's Office	Yes Yes	Ceiling Floor	Concrete Concrete	White N/A	None None	0	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	None	0	No	No	No	
1	1 Hallway at Nurse's Office	Yes	W1	Concrete	White	Flaking	36	0 N/A	Negative N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	
1	1 Hallway at Nurse's Office 1 Hallway at Nurse's Office	Yes Yes	W1 W2	N/A Concrete	N/A White	N/A Flaking	N/A 8	0.02	N/A Negative	Door Frame N/A	Metal N/A	White N/A	Chipping N/A	1 N/A	0.9 N/A	Positive N/A	None None	0	No	No	No	
1	1 Hallway at Nurse's Office	Yes	W3	Concrete	White	Flaking	18	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	Ō	No	No	No	
	1 Hallway at Nurse's Office 1 Hallway at Nurse's Office	Yes Yes	W4 Ceiling	Concrete Concrete	White White	Flaking None	6 0	0 N/A	Negative N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	None	0	No	No	No	
1	1 Hallway at Nurse's Office	Yes	Floor	Concrete	N/A	None	Ő	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	Ő	No	No	No	
1	1 Classroom 111 1 Classroom 111	Yes Yes	W1 W1	Concrete Plaster	Tan White	Efflorescence Flaking	7	0.02	Negative Negative	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	None None	0	Prior to Repair Prior to Repair	Unknown	No	
1	1 Classroom 111	Yes	W1 W1	N/A	N/A	N/A	4 N/A	N/A	N/A	Door Frame	Metal	White	Chipping	1	0.29	Negative	None	0	Prior to Repair	No	No	
1	1 Classroom 111 1 Classroom 111	Yes	W2 W3	Concrete Concrete	Tan Tan	None Flaking	0	N/A	N/A Negative	N/A N/A	N/A N/A	N/A N/A	N/A	N/A N/A	N/A N/A	N/A N/A	None None	0	Prior to Repair Prior to Repair	No	No	
1	1 Classroom 111 1 Classroom 111	Yes Yes	W3 W3	N/A	Tan N/A	N/A	8 N/A	0.02 N/A	N/A	Radiator cover	N/A Metal	N/A White	N/A Cracking Flaking	1	N/A 0.7	Positive	None	0	Prior to Repair Prior to Repair	No	No	
1	1 Classroom 111	Yes	W3 W4	N/A	N/A Tan	N/A	N/A	N/A	N/A	Pipe Riser N/A	Metal N/A	White N/A	Flaking N/A	6 N/A	0.5 N/A	Negative N/A	None None	0	Prior to Repair	No No	No	
1	1 Classroom 111 1 Classroom 111	Yes Yes	W4 Ceiling	Concrete Concrete	l an White	Cracking Efflorescence	7	0.02	Negative Negative	N/A N/A	N/A N/A		N/A N/A	N/A N/A		N/A N/A	None	0	Prior to Repair No	No	No	
1	1 Classroom 111	Yes	Floor	Concrete	N/A	None	0	0 N/A	N/A	N/A	N/A	N/A N/A	N/A	N/A	N/A N/A	N/A	None	Ő	No	No	No	
1	Hallway from Faculty Lounge to Classroom 1 111	Yes	W1	Concrete	White	Chipping	16	0.06	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	
	Hallway from Faculty Lounge to Classroom																					
	1 111 Hallway from Faculty Lounge to Classroom	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Wood	Tan	Chipping	8	0.3	Negative	None	0	No	No	No	
1	1 111 Hallway from Faculty Lounge to Classroom	Yes	W2	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	
1	1 111	Yes	W3	Concrete	White	Chipping	12	0.02	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	
1	Hallway from Faculty Lounge to Classroom	Yes	W4	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	
	Hallway from Faculty Lounge to Classroom																	-				
1	1 111 Hallway from Faculty Lounge to Classroom 1 111	Yes	Ceiling	Concrete	White	Cracking	8	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	
1	1 111	Yes	Floor	Concrete	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	Floor Tile
1	1 Storage at Main Office on Nurse's Office Side	Yes	W1	Concrete	White	Cracking	8	0.04	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No Partially	No	No	
1	1 Storage at Main Office on Nurse's Office Side	Yes	W2	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Inaccessible	No	No	
1	1 Storono at Main Office Numeric Office Office	Yes	W3	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None		Partially Inaccessible	No	No	
\vdash	1 Storage at Main Office on Nurse's Office Side	res					U											U	Partially	INU	INU	
1	1 Storage at Main Office on Nurse's Office Side	Yes	W4 Coiling	Concrete	White White	None	0	N/A 0.02	N/A Nogativo	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	None	0	Inaccessible	No	No	
1	Storage at Main Office on Nurse's Office Side Storage at Main Office on Nurse's Office Side	Yes Yes	Ceiling Floor	Concrete Concrete	N/A	Cracking None	0	N/A	Negative N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No No	No	No	
1	1 Storage at Main Office on Hallway Side	Yes	W1	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	

										hool Dist												
										Safe Certifi												
	Name of Inspector: Ryan Hutsel		1						F.	S. Edmon	as Eleme	ntary Sc	nooi					Inspection	Dates: 06/11- 06/	15/2019		
	Inspection Company: Synertech	h			-					-	-	_						ULCS# 621	0	13/2013		
E I e m e n t	F I 0 0 7 0n-Site Room Name	Student Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)	Additional Component	Substrate Material	Color	Description of Paint and Plaster Damage	Additional Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Additional Component XRF (positive/ negative)	Debris Present (describe location)	Quantity (sf)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Comments/ Description/ Notes
	Storage at Main Office on Hallway Side Storage at Main Office on Hallway Side	Yes Yes	W2 W3	Concrete Concrete	White White	Cracking None	2	0.02 N/A	Negative N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	None	0	No	No No	No	
1	Storage at Main Office on Hallway Side Storage at Main Office on Hallway Side Storage at Main Office on Hallway Side	Yes	W4	Concrete	White	None	Ö	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	ŏ	No	No	No	
1	Storage at Main Office on Hallway Side Storage at Main Office on Hallway Side	Yes	Ceiling Floor	Concrete Concrete	White White	None None	0	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	None	0	No	No No	No	
1	1 Men's Staff Restroom outside of Main Office	Yes	W1	Concrete	White	None	Ö	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	
1	Men's Staff Restroom outside of Main Office Men's Staff Restroom outside of Main Office	Yes	W2 W3	Concrete Concrete	White White	None None	0	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	None	0	No	No No	No	
1	1 Men's Staff Restroom outside of Main Office	Yes	W4	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	
1	Men's Staff Restroom outside of Main Office Men's Staff Restroom outside of Main Office	Yes Yes	Ceiling Floor	Concrete Concrete	White N/A	Cracking None	0	N/A	Negative N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	None None	0	No	No No	No	
1	1 Main Office 1 Main Office	Yes	W1 W2	Concrete Concrete	White White	None	0	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	None	0	Prior to Repair Prior to Repair	No No	No	Recently Painted Recently Painted
1	1 Main Office	Yes	W3	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Prior to Repair	No	No	Recently Painted
1	1 Main Office 1 Main Office	Yes	W4 Ceiling	Concrete Concrete	White White	None None	0	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	None	0	Prior to Repair No	No	No	Recently Painted Recently Painted
1	1 Main Office	Yes	Floor	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	Recently Painted
1	1 Principal's Office 1 Principal's Office	Yes	W1 W2	Concrete Concrete	White White	None	0	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	None	0	Prior to Repair Prior to Repair	No No	No	Recently Painted Recently Painted
1	1 Principal's Office	Yes	W3	Concrete	White	None	ŏ	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	ŏ	Prior to Repair	No	No	Recently Painted
1	1 Principal's Office 1 Principal's Office	Yes	W4 Ceiling	Concrete Concrete	White White	None	0	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	None None	0	Prior to Repair No	No No	No	Recently Painted Recently Painted
1	1 Principal's Office	Yes	Floor	Concrete	White	None	0	N/A 5.2	N/A Positive	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	None	0	No	No	No	Recently Painted
1	1 Auditorium 1 Auditorium	Yes	W1 W1	Concrete N/A	White N/A	Flaking N/A	12 N/A	5.2 N/A	Positive N/A	N/A Door Frame	N/A Metal	N/A Brown	N/A Cracking	N/A 2	0.5		None	0	No	No	No	
1	1 Auditorium	Yes	W2	Concrete	White	Flaking	10	4.7	Positive	N/A N/A	N/A	N/A N/A	N/A N/A	N/A N/A	N/A	Negative N/A	None	0	No	Brick Pointing No	Yes	Additional Efflorescence
1	1 Auditorium 1 Auditorium	Yes	W3 W3	Concrete N/A	White N/A	Cracking N/A	N/A	N/A	Positive N/A	Door Frame	N/A Metal	Tan	N/A Chipping N/A	2	N/A 2.5	N/A Positive	None	0	No	No	No	
1	1 Auditorium 1 Auditorium	Yes Yes	W4 W4	Concrete N/A	White N/A	Efflorescence	12 N/A	5.2 N/A	Positive N/A	N/A Door Frame	N/A Metal	N/A		N/A	N/A	N/A Desitive	None	0	No No	Unknown	Yes	Additional Efflorescence
1	1 Auditorium	Yes	Ceiling	Concrete	White	N/A Cracking	20	N/A	N/A	N/A	N/A	Tan N/A	Chipping N/A	4 N/A	4.1 N/A	Positive N/A	None None	0	No	No	No	
1	1 Auditorium 1 Auditorium	Yes	Ceiling Floor	N/A Concrete	N/A N/A	N/A None	N/A	N/A N/A	N/A N/A	Ductwork N/A	Metal N/A	White N/A	Chipping N/A	10 N/A	N/A N/A	N/A N/A	None	0	No	No	No	Eloor Tile
1	1 Main Entrance Foyer next to Auditorium	Yes	W1	Metal	Brown	None	0	N/A N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	11001 The
1	Main Entrance Foyer next to Auditorium Main Entrance Foyer next to Auditorium	Yes	W2 W2	Plaster N/A	White/Yellow N/A	None N/A	0 N/A	N/A N/A	N/A N/A	N/A Door	N/A Wood	N/A Yellow/Blue	N/A Chipping	N/A 4	N/A 0.45	N/A Negative	None	0	No No	No	No	
1	1 Main Entrance Foyer next to Auditorium	Yes	W3	Wood	N/A	None	Ö	N/A	N/A	N/A	Wood N/A	N/A	N/A	N/A	N/A	Negative N/A	None	ŏ	No	No	No	
1	Main Entrance Foyer next to Auditorium Main Entrance Foyer next to Auditorium	Yes	W3 W4	N/A Plaster	N/A Yellow	N/A None	N/A 0	N/A N/A	N/A N/A	Door Frame N/A	Wood N/A	White N/A	Chipping N/A	8 N/A	0.1 N/A	Negative N/A	None	0	No	No	No	
1	1 Main Entrance Foyer next to Auditorium	Yes	Ceiling	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	Ő	No	No	No	
1	Main Entrance Foyer next to Auditorium Gym	Yes	Floor W1	Concrete	N/A Tan	None Flaking	33	N/A 0.1	N/A Negative	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	None	0	No Prior to Repair	No	No	
1	1 Gym	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	Tan Tan	Chipping	2	0.3	Negative	None	0	No	No	No	
1	1 Gym 1 Gym	Yes	W1 W2	N/A Concrete	N/A Tan	N/A Cracking	N/A 100	N/A 0.6	N/A Negative	Radiator Cover N/A	Metal N/A	N/A	Chipping N/A	N/A	0.55 N/A	Negative N/A	None	0	No Prior to Repair	No No	No	
4	1 6-	Yes	W3	Concrete	Tan		22	0.2	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None		Dries to Depois	Roof leak	No	Additional Efflorescence,
	1 Gym	Yes	W3 W3	N/A	N/A	Flaking N/A	2.3 N/A	N/A	Negative N/A	N/A Radiator Cover	Metal	Tan	N/A Chipping N/A	N/A 3	0.4	N/A Negative N/A	None	0	Prior to Repair No	No	No	Cracking
1	1 Gym 1 Gym	Yes	W4 W4	Concrete N/A	Tan N/A	Cracking N/A	18 N/A	0.05 N/A	Negative N/A	N/A	N/A Metal	N/A		N/A	N/A		None	0	Prior to Repair	No	No	
	i Gym	Yes								Radiator Cover		Tan	Chipping	1	0.5	Negative	None	0	Ceiling too high to test - assume	No	No	Ceiling Too High to Test -
1	1 Gym	Yes	Ceiling	Concrete	White	Flaking	54	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Positive	None	0	Ceiling too high to test - assume	No	No	Assume Positive Until Tested Ceiling Too High to Test -
1	1 Gym	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	Ductwork	Metal	White	Flaking	24	N/A	Positive	None	0	Ceiling too high to test - assume	No	No	Assume Positive Until Tested Ceiling Too High to Test -
1	1 Gym	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	Steel Beams	Metal	White	Flaking	30	N/A	Positive	None	0	Ceiling too high to test - assume	No	No	Assume Positive Until Tested
1	1 Gym	Yes	Ceiling	N/A None	N/A N/A	N/A None	N/A	N/A N/A	N/A	Drain Pipes	Metal	White	Flaking N/A	16 N/A	N/A	Positive N/A	None	0	positive	No	No	
1	- Official and a second s						U		1975		1671	N/A	147					0	No Partially	NO	No	+
1	Storage off of Auditorium Storage off of Auditorium	Yes	W1 W1	Concrete N/A	White N/A	None N/A	0 N/A	N/A N/A	N/A N/A	N/A Door Frame	N/A Metal	N/A White	N/A Chipping	N/A 1	N/A 0.37	N/A Negative	None None	0	Inaccessible Prior to Repair	No	No	+
1	Storage off of Auditorium Storage off of Auditorium	Yes	W1 W2	Concrete	White	N/A	0	N/A N/A	N/A N/A	N/A	N/A	N/A	N/A	N/A	0.37 N/A	Negative N/A	None	0	Partially Inaccessible	No	No	
1	1 Storage off of Auditorium	Yes	W3	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Partially Inaccessible Partially	No	No	
1	1 Storage off of Auditorium	Yes	W4	Concrete	White White	None	0	N/A	N/A	N/A	N/A N/A	N/A	N/A N/A	N/A N/A	N/A	N/A	None	0	Inaccessible	No	No	
1	Storage off of Auditorium Storage off of Auditorium	Yes	Ceiling Floor	Concrete Concrete	N/A	None None	0	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	None None	0	No	No	No	<u>t</u>
1	1 Storage at Gym next to Boys Restroom	Yes	W1	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Partially Inaccessible Partially	No	No	
1	1 Storage at Gym next to Boys Restroom	Yes	W2	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Inaccessible	No	No	
1	Storage at Gym next to Boys Restroom Storage at Gym next to Boys Restroom	Yes	W3 W4	Concrete	White	None	0	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A	N/A N/A	N/A N/A	None	0	Inaccessible Partially Inaccessible	No	No	
1	1 Storage at Gym next to Boys Restroom	Yes Yes Yes	Ceiling Eloor	Concrete Concrete Concrete	White White White	None None None	0	N/A N/A	N/A N/A N/A	N/A N/A N/A	N/A N/A	N/A N/A	N/A N/A N/A	N/A N/A	N/A N/A	N/A N/A N/A	None None None	0	No No	No No	No No	1
	1 Storage at Gym next to Boys Restroom						U											U		INU		Ceramic Tile - Not damaged, but
1	Boy's Restroom behind Gym Boy's Restroom behind Gym	Yes	W1 W2	Ceramic Tile Ceramic Tile	Tan Tan	None	0	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	None	0	No	No No	No	glazing is positive
1	1 Boy's Restroom behind Gym	Yes	W3	Ceramic Tile	Tan	None	ŏ	N/A	N/A	N/A	N/A N/A	N/A	N/A N/A	N/A N/A	N/A N/A	N/A	None	ŏ	No	No	No	
1	1 Boy's Restroom behind Gym 1 Boy's Restroom behind Gym	Yes Yes	W4 Ceiling	Ceramic Tile Concrete	Tan White	None Cracking	8	N/A 0.02	N/A Negative	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	None	0	No No	No No	No	<u> </u>
1	Boy's Restroom behind Gym Storage between Gym Restrooms	Yes	Floor	Ceramic Tile Concrete	Tan	None	0	0.02 N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A	N/A N/A	N/A N/A	None	0	No Partially Inaccessible	No	No	
1	1 Storage between Gym Restrooms	Yes	W1	N/A	N/A	N/A	N/A	N/A N/A	N/A	Door Frame	Metal	White	N/A Chipping	2	0.27	Negative	None	0	Prior to Repair Partially	No	No	
1	1 Storage between Gym Restrooms	Yes	W2	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Inaccessible	No	No	

										hool Dis												
										afe Certifi S. Edmon												
	Name of Inspector: Ryan Hutse	11							<u>г</u> .	S. Eamon	as Elemei	ntary Sc	nooi					Inspection	Dates: 06/11- 06/	15/2019		
_	Inspection Company: Synertech							-	1	1				1			1	ULCS# 6210)		-	
E I e m e n	F I o o r On-Site Room Name	Student Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)	Additional Component	Substrate Material	Color	Description of Paint and Plaster Damage	Additional Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Additional Component XRF (positive/ negative)	Debris Present (describe location)	Quantity (sf)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Comments/ Description/ Notes
1	1 Storage between Gym Restrooms	Yes	W3	Concrete	White	None		N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None		Partially Inaccessible	No	No	
			W4				-												Partially			
1	Storage between Gym Restrooms Storage between Gym Restrooms	Yes	W4 Ceiling	Concrete Concrete	White White	None None	0	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	None	0	Inaccessible No	No	No	
1	1 Storage between Gym Restrooms	Yes	Floor	Concrete	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	Ceramic Tile - Not damaged, but
1	1 Girl's Restroom behind Gym 1 Girl's Restroom behind Gym	Yes Yes	W1 W2	Ceramic Tile Ceramic Tile	Tan Tan	None None	0	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A	None None	0	No	No	No	glazing is positive
1	1 Girl's Restroom behind Gym	Yes	W3	Ceramic Tile	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A N/A	None	0	No	No	No	
	1 Girl's Restroom behind Gym 1 Girl's Restroom behind Gym	Yes	W4 Ceiling	Ceramic Tile Concrete	Tan White	None Cracking	5	N/A 0	N/A Negative	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	None None	0	No No	No	No	
1	1 Girl's Restroom behind Gym	Yes	Floor	Ceramic Tile	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No Partially	No	No	
1	1 Storage next to Girl's Restroom behind Gym	Yes	W1	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Inaccessible Partially	No	No	
1	1 Storage next to Girl's Restroom behind Gym	Yes	W2	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Inaccessible	No	No	
1	1 Storage next to Girl's Restroom behind Gym	Yes	W3	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Inaccessible	No	No	
1	1 Storage next to Girl's Restroom behind Gym	Yes	W4	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Partially Inaccessible	No	No	
	Storage next to Girl's Restroom behind Gym Storage next to Girl's Restroom behind Gym	Yes Yes	Ceiling Floor	Concrete Concrete	White N/A	None	0	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	None None	0	No No	No No	No	
1	1 Hallway behind Gym 1 Hallway behind Gym	Yes	W1 W2	Concrete Concrete	White White	Chipping None	12	0.02 N/A	Negative N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A N/A	None None	0	No	No	No	
1	1 Hallway behind Gym	Yes	W3	Concrete	White	Cracking	8	0.04	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	
1	1 Hallway behind Gym 1 Hallway behind Gym	Yes	W4 Ceiling	Concrete Concrete	White White	None Cracking	10	N/A 0	N/A Negative	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	None None	0	No No	No No	No	
1	1 Hallway behind Gym 1 Main Office Hallway	Yes	Floor W1	Concrete Concrete	N/A White	None	0	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	None	0	No	No	No	
1	1 Main Office Hallway 1 Main Office Hallway	Yes	W2 W3	Concrete Concrete	White	None	0	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	None	0	No	No	No	Recently Painted Recently Painted
1	1 Main Office Hallway	Yes	W4	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	Recently Painted
	1 Main Office Hallway 1 Main Office Hallway	Yes	Ceiling Floor	Concrete Concrete	White White	None	0	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	None	0	No No	No No	No	Recently Painted Recently Painted
1	1 Storage next to Classroom 109	Yes	W1	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Partially Inaccessible	No	No	Recently Painted
1	1 Storage next to Classroom 109	Yes	W2	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Partially Inaccessible	No	No	
		Yes	W3	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None		Partially Inaccessible	Ne	No	
	1 Storage next to Classroom 109					None	-		N/A	N/A	N/A		N/A	N/A	N/A N/A	N/A			Partially	No	No	
1	1 Storage next to Classroom 109	Yes		Concrete	White		0	N/A				N/A	14/1	N/A			None	0	Inaccessible Partially	No	No	
1	1 Storage next to Classroom 109	Yes	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Inaccessible Partially Inaccessible	No	No	
1	1 Storage next to Classroom 109	Yes	Floor	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0		No	No	Current Classroom Modification
1	1 Classroom 109	Yes	W1	Concrete	Tan	Flaking	8	0.06	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	Project Ongoing Current Classroom Modification
1	1 Classroom 109	Yes	W1	Plaster	White	Cracking	2	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	Project Ongoing Current Classroom Modification
1	1 Classroom 109	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	Red	Chipping	2	0.25	Negative	None	0	No	No	No	Project Ongoing
1	1 Classroom 109	Yes	W2	Concrete	Tan	Cracking	9	0.04	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	Project Ongoing
1	1 Classroom 109	Yes	W3	Concrete	Tan	Cracking	10	0.02	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	Current Classroom Modification Project Ongoing Current Classroom Modification
1	1 Classroom 109	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A	Pipe Riser	Metal	White	Flaking	8	0.45	Negative	None	0	No	No	No	Current Classroom Modification Project Ongoing Current Classroom Modification
1	1 Classroom 109	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A	Radiator Cover	Metal	White	Chipping	1	0.8	Positive	None	0	No	No	No	Current Classroom Modification Project Ongoing
1	1 Classroom 109	Yes	W4	Concrete	Tan	Flaking	12	0.04	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	Current Classroom Modification Project Ongoing
																		1				Current Classroom Modification Project Ongoing; Additional
1	1 Classroom 109	Yes	Ceiling	Concrete	White	Efflorescence	6	0.02	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	Unknown	No	Cracking Current Classroom Modification
1	1 Classroom 109	Yes	Floor	Concrete	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	Project Ongoing; Floor Tile
1	1 Storage Room "C-1" next to Classroom 109	Yes	W1	Concrete	Tan	Cracking	1	0.06	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	Current Classroom Modification Project Ongoing
1	1 Storage Room "C-1" next to Classroom 109	Yes	W2	Concrete	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	Current Classroom Modification Project Ongoing Current Classroom Modification
1	1 Storage Room "C-1" next to Classroom 109	Yes	W3	Concrete	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	Current Classroom Modification Project Ongoing
1	1 Storage Room "C-1" next to Classroom 109	Yes	W4	Concrete	Tan	Cracking	3	0.04	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	Project Ongoing Current Classroom Modification Project Ongoing
1	1 Storage Room "C-1" next to Classroom 109	Yes	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	Current Classroom Modification Project Ongoing
1	1 Storage Room "C-1" next to Classroom 109	Yes	Floor	Concrete	N/A	None		N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None		No	No	No	Current Classroom Modification Project Ongoing
		Yes	W1		Tan	Cracking		0.02		N/A	N/A	N/A	N/A	N/A	N/A	N/A N/A			No			Current Classroom Modification
	1 Storage Room "B-1" next to Classroom 109			Concrete			-		Negative	N/A N/A					N/A N/A		None	-		No	No	Project Ongoing Current Classroom Modification
	1 Storage Room "B-1" next to Classroom 109	Yes	W2	Concrete	Tan	None	0	N/A	N/A		N/A	N/A	N/A	N/A		N/A	None	U	No	No		Project Ongoing Current Classroom Modification
1	1 Storage Room "B-1" next to Classroom 109	Yes	W3	Concrete	Tan	Cracking	2	0.02	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	Project Ongoing Current Classroom Modification
1	1 Storage Room "B-1" next to Classroom 109	Yes	W4	Concrete	Tan	Cracking	3	0.06	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	Project Ongoing Current Classroom Modification
1	1 Storage Room "B-1" next to Classroom 109	Yes	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	Project Ongoing Current Classroom Modification
1	1 Storage Room "B-1" next to Classroom 109	Yes	Floor	Concrete	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	Project Ongoing
1	1 Classroom 110	Yes	W1	Concrete	White	Flaking	14	0.02	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	Current Classroom Modification Project Ongoing
1	1 Classroom 110	Yes	W1	Plaster	White	Cracking	4	0.02	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	Current Classroom Modification Project Ongoing
· · · ·																						

										hool Dist												
										Safe Certifi												
	Name of Inspector: Ryan Hutse		1						۴.	S. Edmon	ds Eleme	ntary Sc	hool					Incraction D	Dates: 06/11- 06/	15/2010		
	Inspection Company: Synertec	h		_					-	_		-	_					ULCS# 6210		15/2019		
E																						
e m e	F 	Student Teacher				Descriptions of	Primary		Primary Component				Description of Paint and	Additional		Additional Component XRF	Debris Present			0	Plastering	
e n t	o r On-Site Room Name	Occupied (yes/no)	Primary	Substrate Material	Color	Description of Primary Damage	Component Damage Quantity (sf)	XRF Reading (mg/cm2)	(positive/ negative)	Additional	Substrate Material	Color	Plaster	Component Damage Quantity (sf)	XRF Reading (mg/cm2)	(positive/ negative)	(describe location)	Quantity (sf)	Contents Need to be Moved	On-going Moisture Intrusion	Needed (yes or no)	Comments/ Description/ Notes
	1 Classroom 110	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	Red	Chipping		0.3	Negative	None	Quantity (01)	Ne	No	No	Current Classroom Modification Project Ongoing
		Yes	W2		White	Flaking	9	0.06			N/A		N/A	N/A	N/A			-	NO	No	No	Current Classroom Modification
1	1 Classroom 110			Concrete					Negative	N/A		N/A				N/A	None	U	No			Project Ongoing Current Classroom Modification
1	1 Classroom 110	Yes	W3	Concrete	White	Flaking	14	0.04	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	Project Ongoing Current Classroom Modification
1	1 Classroom 110	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A	Radiator Cover	Metal	Red	Chipping	4	0.47	Negative	None	0	No	No	No	Project Ongoing Current Classroom Modification
1	1 Classroom 110	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A	Pipe Riser	Metal	Red	Chipping	4	0.4	Negative	None	0	No	No	No	Project Ongoing Current Classroom Modification
1	1 Classroom 110	Yes	W4	Concrete	White	Flaking	12	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	Project Ongoing Current Classroom Modification
1	1 Classroom 110	Yes	Ceiling	Concrete	White	Cracking	2	0.02	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	Project Ongoing Current Classroom Modification
1	1 Classroom 110	Yes	Floor	Concrete	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	Project Ongoing
1	1 Stairwell next to Classroom 110	Yes	W1	Ceramic Tile	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	Ceramic Tile - Not damaged, but glazing is positive
1	1 Stairwell next to Classroom 110	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door	Metal	Brown	Chipping	2	0.25	Negative	None	0	No	No	No	Ceramic Tile - Not damaged, but glazing is positive
1	1 Stairwell next to Classroom 110	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	Brown	Chipping	1	3.9	Positive	None	n	No	No	No	Ceramic Tile - Not damaged, but glazing is positive
1	1 Stairwell next to Classroom 110	Yes	W1 W2 W2	Ceramic Tile N/A	Tan N/A	N/A None N/A	0 N/A	N/A N/A N/A	N/A N/A N/A	N/A	N/A Metal	N/A	N/A	N/A	3.9 N/A 4.2	N/A	None None	0	No	No No	No	givening is positive
1	Stairwell next to Classroom 110 Stairwell next to Classroom 110	Yes	W2	N/A	N/A	N/A	N/A N/A	N/A	N/A	Radiator Cover Hand Rail	Metal	Brown Brown	Chipping Chipping	1	4.1	Positive Positive	None	0	No No	No	No	
1	Stairwell next to Classroom 110 Stairwell next to Classroom 110	Yes	W3 W3	Ceramic Tile N/A	Tan N/A	None N/A	0 N/A	N/A N/A	N/A N/A	N/A Door	N/A Metal	N/A Brown	N/A Chipping	N/A 1	N/A 0.3	N/A Negative	None	0	No No	No	No	
1	1 Stairwell next to Classroom 110	Yes	W3	N/A	N/A	N/A	N/A 0	N/A	N/A	Door Frame N/A	Metal	Brown N/A	Chipping N/A	2	2.9 N/A	Positive	None	0	No	No	No	
1	Stairwell next to Classroom 110 Stairwell next to Classroom 110	Yes Yes	W4 W4	Ceramic Tile N/A	Tan N/A	None N/A	N/A	N/A N/A	N/A N/A	Radiator Cover	N/A Metal	Brown	Chipping	N/A 3	N/A 3.4	N/A Positive	None None	0	No	No No	No	
1	Stairwell next to Classroom 110 Stairwell next to Classroom 110	Yes	W4 Ceiling	N/A Metal	N/A Brown	N/A None	N/A 0	N/A N/A	N/A N/A	Hand Rail N/A	Metal N/A	Brown N/A	Chipping N/A	1 N/A	4 N/A	Positive N/A	None None	0	No No	No No	No	
1	Stairwell next to Classroom 110 Stairwell next to Classroom 110	Yes	Ceiling Floor Floor	Concrete N/A	Grey N/A	None N/A	0 N/A	N/A N/A	N/A N/A	N/A Stair stringer	N/A Metal	N/A Brown	N/A Chipping	N/A 10	N/A 4.1	N/A Positive	None None	0	No No	No No	No	
1	1 Stairwell next to Classroom 110	Yes	Floor	N/A	N/A	N/A N/A	N/A	N/A	N/A	Stair riser	Metal Metal	Brown	Chipping	10	3.7	Positive	None	0	No	No	No	
1	Stairwell next to Classroom 110 Stairwell next to Classroom 110	Yes	Floor	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	Newel posts Stair Spindles	Metal Metal	Brown Brown	Chipping Chipping	3 20	2.9 3.9	Positive Positive	None	0	No No	No No	No	
1	1 Stairwell between Classrooms 102 & 104	Yes	W1	Ceramic Tile	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	Ceramic Tile - Not damaged, but glazing is positive
1	1 Stairwell between Classrooms 102 & 104	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door	Metal	Brown	Chipping	1	0.35	Negative	None	0	No	No	No	Ceramic Tile - Not damaged, but glazing is positive
	1 Stairwell between Classrooms 102 & 104	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	Brown			3.2	Positive	None	0	Ne	No	No	Ceramic Tile - Not damaged, but
1	1 Stairwell between Classrooms 102 & 104	Yes	W2	Ceramic Tile	Tan	None	0	N/A	N/A	N/A	N/A	N/A	Chipping N/A	N/A	N/A	N/A	None	0	No	No	No	glazing is positive
1	Stairwell between Classrooms 102 & 104 Stairwell between Classrooms 102 & 104	Yes	W2 W2	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	Radiator Cover Hand Rail	Metal Metal	Brown Brown	Chipping Chipping	2	4.5	Positive Positive	None None	0	No	No No	No	
1	1 Stairwell between Classrooms 102 & 104	Yes	W3	Ceramic Tile	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	
1	Stairwell between Classrooms 102 & 104 Stairwell between Classrooms 102 & 104	Yes	W3 W3	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	Door Door Frame	Metal Metal	Brown Brown	Chipping Chipping	2	0.39	Negative Positive	None None	0	No No	No No	No	
	Stairwell between Classrooms 102 & 104 Stairwell between Classrooms 102 & 104	Yes	W4 W4	Ceramic Tile N/A	Tan N/A	None N/A	0 N/A	N/A N/A	N/A N/A	N/A Radiator Cover	N/A Metal	N/A Brown	N/A Chipping	N/A	N/A 2.7	N/A Positive	None	0	No	No	No	
	Stailweir between Classrooms 102 & 104 Stairwell between Classrooms 102 & 104	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A	Hand Rail	Metal	Brown	Chipping	2	4.9	Positive	None	0	No	No	No	
1	1 Stairwell between Classrooms 102 & 104	Yes	Ceiling Floor	Metal	Brown	None None	0	N/A N/A	N/A	N/A	N/A	N/A	N/A N/A	N/A N/A	N/A N/A	N/A	None	0	No	No No	No No	
1	1 Stairwell between Classrooms 102 & 104	Yes		Concrete	Grey				N/A	N/A	N/A	N/A				N/A	None	U	No	NO		Current Classroom Modification
1	1 Classroom 107	Yes	W1	Concrete	White	Flaking	7	0.02	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	Project Ongoing Current Classroom Modification
1	1 Classroom 107	Yes	W1	Plaster	White	Cracking	2	0.02	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	Project Ongoing Current Classroom Modification
1	1 Classroom 107	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	White	Chipping	2	0.6	Negative	None	0	No	No	No	Project Ongoing Current Classroom Modification
1	1 Classroom 107	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	Pipe Riser	Metal	White	Chipping	2	0.5	Negative	None	0	No	No	No	Project Ongoing
1	1 Classroom 107	Yes	W2	Concrete	White	Cracking	6	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	Current Classroom Modification Project Ongoing
1	1 Classroom 107	Yes	W3	Concrete	White	Cracking	2	0.02	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	Current Classroom Modification Project Ongoing
1	1 Classroom 107	Yes	W4	Concrete	White	Cracking	3	0.02	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	Current Classroom Modification Project Ongoing
1	1 Classroom 107	Yes	Ceiling	Concrete	White	Cracking	9	n	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	Current Classroom Modification Project Ongoing
1	1 Classroom 107	Yes	Floor	Concrete	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	Current Classroom Modification
1	1 Teacher's Lounge 1 Teacher's Lounge	Yes	W1 W1	Concrete N/A	Yellow/White N/A	Cracking N/A	2 N/A	0 N/A	Negative N/A	N/A Door Frame	N/A Metal	N/A White	N/A Chipping	N/A 1	N/A 0.3	N/A Negative	None None	0	No No	Unknown No	No	+
1	1 Teacher's Lounge	Yes	W2	Concrete	Yellow	Cracking	2	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	
1	1 Teacher's Lounge 1 Teacher's Lounge	Yes	W3 W3	Concrete N/A	Yellow N/A	None N/A	0 N/A	N/A N/A	N/A N/A	N/A Radiator Cover	N/A Metal	N/A White	N/A Chipping	N/A 1	N/A 0.7	N/A Positive	None	0	No No	No No	No	
1	1 Teacher's Lounge	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A	Pipe Riser N/A	Metal	White	Chipping Flaking	4	0.55	Negative	None	ō	No	No	No	
1	1 Teacher's Lounge 1 Teacher's Lounge	Yes	W4 Ceiling	Concrete	Yellow White	Cracking None	2	0.02 N/A	Negative N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	None	0	No	No Brick Pointing	No	
	1 Teacher's Lounge	Yes	Floor	Concrete	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	ō	No	No	No	Floor Tile
1	1 Classroom 108	Yes	W1	Concrete	Tan	Chipping	5	0.04	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	Project Ongoing
1	1 Classroom 108	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	White	Chipping	2	0.5	Negative	None	0	No	No	No	Current Classroom Modification Project Ongoing
1	1 Classroom 108	Yes	W2	Concrete	Tan	Cracking	6	0.04	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	Current Classroom Modification Project Ongoing
1	1 Classroom 108	Yes	W3	Concrete	Tan	Chipping	10	0.06	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	Current Classroom Modification
	1 Classes 400			N/A					N/A		Metal				0.8				N-	No	No	Project Ongoing Current Classroom Modification
1	1 Classroom 108	Yes			N/A	N/A	N/A	N/A		Radiator Cover		White	Chipping	2		Positive	None	U	No			Project Ongoing Current Classroom Modification
1	1 Classroom 108	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A	Pipe Riser	Metal	White	Flaking	5	0.5	Negative	None	0	No	No	No	Project Ongoing Current Classroom Modification
1	1 Classroom 108	Yes	W4	Concrete	Tan	None	4	0.02	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	Project Ongoing Current Classroom Modification

										hool Dist												
										Safe Certifi												
	Name of Inspector: Ryan Hutse								F.	S. Edmon	as Eleme	ntary Sc	nooi					Inspection [Dates: 06/11- 06/*	5/2019		
- 1	Inspection Company: Synertec	h h					1	1		r	1						1	ULCS# 6210			1	1
E I e m e n		Student Teacher Occupied	Primary	Substrate	Color	Description of Primary	Primary Component Damage	XRF Reading	Primary Component XRF (positive/	Additional	Substrate		Description of Paint and Plaster	Additional Component Damage	XRF Reading	Additional Component XRF (positive/	Debris Present (describe		Contents Need to	On-going Moisture	Plastering Needed (yes or	
t	r On-Site Room Name	(yes/no)	Component	Material		Damage	Quantity (sf)	(mg/cm2)	negative)	Component	Material	Color	Damage	Quantity (sf)	(mg/cm2)	negative)	location)	Quantity (sf)	be Moved	Intrusion	no)	Comments/ Description/ Notes Current Classroom Modification
1	1 Classroom 108	Yes	Floor	Concrete	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	Project Ongoing Current Classroom Modification
1	1 Classroom 106	Yes	W1	Concrete	White	Flaking	16	0.04	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	Project Ongoing Current Classroom Modification
1	1 Classroom 106	Yes	W1	Plaster	White	Flaking	8	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	Project Ongoing Current Classroom Modification
1	1 Classroom 106	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	White	Chipping	1	0.32	Negative	None	0	No	No	No	Project Ongoing Current Classroom Modification
1	1 Classroom 106	Yes	W2	Concrete	White	Chipping	5	0.04	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	Project Ongoing
1	1 Classroom 106	Yes	W3	Concrete	White	Flaking	8	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	Current Classroom Modification Project Ongoing
1	1 Classroom 106	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A	Radiator Cover	Metal	White	Chipping	1	0.54	Negative	None	0	No	No	No	Current Classroom Modification Project Ongoing
1	1 Classroom 106	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A	Pipe Riser	Metal	White	Flaking	2	0.38	Negative	None	0	No	No	No	Project Ongoing Current Classroom Modification Project Ongoing
	1 Classroom 106	Yes	W4	Concrete	White	Cracking	2	0.02	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	Current Classroom Modification
							_											-				Project Ongoing Current Classroom Modification
1	1 Classroom 106	Yes	Ceiling	Concrete	White	Cracking	2	U	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	U	No	No	No	Project Ongoing Current Classroom Modification
1	1 Classroom 106	Yes	Floor	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	Project Ongoing; Floor Tile Current Classroom Modification
1	1 Classroom 105	Yes	W1	Concrete	White	Flaking	10	0.02	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	Project Ongoing Current Classroom Modification
1	1 Classroom 105	Yes	W1	Plaster	White	Cracking	6	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	Project Ongoing Current Classroom Modification
1	1 Classroom 105	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	White	Chipping	2	0.54	Negative	None	0	No	No	No	Project Ongoing
1	1 Classroom 105	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	Pipe Riser	Metal	White	Chipping	2	0.4	Negative	None	0	No	No	No	Current Classroom Modification Project Ongoing
1	1 Classroom 105	Yes	W2	Concrete	White	Cracking	10	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	Current Classroom Modification Project Ongoing
1	1 Classroom 105	Yes	W3	Concrete	White	Cracking	5	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	Current Classroom Modification Project Ongoing
1	1 Classroom 105	Yes	W4	Concrete	White	Cracking	5	0.02	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	Current Classroom Modification Project Ongoing
		Yes	Ceiling	Concrete	White		12	0.02		N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	Current Classroom Modification
1	1 Classroom 105					Cracking		-	Negative									0				Project Ongoing Current Classroom Modification
1	1 Classroom 105	Yes	Floor	Concrete	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	Project Ongoing Ceramic Tile - Not damaged, but
1	1 Classroom 105 Restroom	Yes	W1	Concrete	Yellow	Cracking	3	0.04	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	glazing is positive Ceramic Tile - Not damaged, but
1	1 Classroom 105 Restroom	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	Red	Chipping	2	0.27	Negative	None	0	No	No	No	glazing is positive
1	1 Classroom 105 Restroom	Yes	W2	Concrete	Yellow	Flaking	6	0.04	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	Project Ongoing Current Classroom Modification
1	1 Classroom 105 Restroom	Yes	W3	Concrete	Yellow	Flaking	9	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	Project Ongoing
1	1 Classroom 105 Restroom	Yes	W4	Concrete	Yellow	None	0	0.02	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	Current Classroom Modification Project Ongoing
1	1 Classroom 105 Restroom	Yes	Ceiling	Concrete	White	None	0	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	Current Classroom Modification Project Ongoing
1	1 Classroom 105 Restroom	Yes	Floor	Concrete	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	Current Classroom Modification Project Ongoing
1	Classroom 105 Storage Closet towards 1 Classroom 103	Yes	W1	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	Current Classroom Modification Project Ongoing
	Classroom 105 Storage Closet towards	Yes	W2	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	Current Classroom Modification
	1 Classroom 103 Classroom 105 Storage Closet towards						0						1					-				Project Ongoing Current Classroom Modification
1	1 Classroom 103 Classroom 105 Storage Closet towards	Yes	W3	Concrete	White	Cracking	2	0.02	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	Project Ongoing Current Classroom Modification
1	1 Classroom 103 Classroom 105 Storage Closet towards	Yes	W4	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	Project Ongoing Current Classroom Modification
1	Classroom 103 Classroom 105 Storage Closet towards	Yes	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	Project Ongoing Current Classroom Modification
1	1 Classroom 103	Yes	Floor	Concrete	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	Project Ongoing Ceramic Tile - Not damaged, but
1	1 Girl's Restroom across from Classroom 103	Yes	W1	Ceramic Tile	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	glazing is positive
1	1 Girl's Restroom across from Classroom 103	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	Brown	Chipping	1	0.5	Negative	None	0	No	No	No	Ceramic Tile - Not damaged, but glazing is positive
1	Girl's Restroom across from Classroom 103 Girl's Restroom across from Classroom 103	Yes Yes	W2 W3 W4	Ceramic Tile Ceramic Tile	Tan Tan	None None	0	N/A N/A N/A	N/A N/A N/A	N/A N/A	N/A N/A N/A	N/A N/A	N/A N/A N/A	N/A N/A N/A	N/A N/A	N/A N/A N/A	None None	0	No No	No No	No No	<u> </u>
1	Girl's Restroom across from Classroom 103 Girl's Restroom across from Classroom 103	Yes	W4 Ceiling	Ceramic Tile Concrete	Tan White	None Efflorescence	0 20	N/A 0.02	N/A Negative	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	None	0	No No	No Steam leak	No	
1	1 Girl's Restroom across from Classroom 103	Yes	Floor	Ceramic Tile	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	Ő	No	No	No	Ceramic Tile - Not damaged, but
1	1 Girl's Restroom across from Classroom 103	Yes	W1	Concrete	White	Cracking	3	0.04	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	glazing is positive
1	1 Girl's Restroom across from Classroom 103	Yes	W1	Ceramic Tile	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	Ceramic Tile - Not damaged, but glazing is positive
1	Girl's Restroom across from Classroom 103 Girl's Restroom across from Classroom 103	Yes	W2 W2	Concrete Ceramic Tile	White Tan	Flaking None	25	0 N/A	Negative N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	None None	0	No No	No No	No	
1	1 Girl's Restroom across from Classroom 103 1 Girl's Restroom across from Classroom 103	Yes Yes	W3 W3	Ceramic Tile Concrete	Tan White	None Flaking	0	N/A 0	N/A Negative	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	None	0	No No	No No	No	
1	1 Girl's Restroom across from Classroom 103	Yes	W4	Ceramic Tile	Tan	None	0	N/A	N/A	N/A	N/A N/A	N/A	N/A	N/A N/A	N/A	N/A	None	0	No	No	No	
1	Girl's Restroom across from Classroom 103 Girl's Restroom across from Classroom 103 Girl's Restroom across from Classroom 103	Yes Yes	Ceiling Floor	Concrete Ceramic Tile	White Tan	Cracking None	0	0 N/A	Negative N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	None None	0	No	No No	No	
1	Storage outside Girl's Restroom across from Classroom 103	Yes	W1	Concrete	White	Cracking	3	0.02	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	
1	Storage outside Girl's Restroom across from Classroom 103	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	Red	Chipping	1	0.32	Negative	None	0	No	No	No	
1	Storage outside Girl's Restroom across from Classroom 103	Yes	W2	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	
1	Storage outside Girl's Restroom across from Classroom 103	Yes	W3	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	
1	Storage outside Girl's Restroom across from 1 Classroom 103	Yes	W4	Concrete	White	Cracking	3	0.04	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	
	Storage outside Girl's Restroom across from Classroom 103				1		-					1	1		-	1		-				

I I											hool Dist												
N N																							
Name Name <th< th=""><th></th><th>Name of Inspector: Rvan Hutse</th><th></th><th></th><th></th><th></th><th></th><th></th><th></th><th>F.</th><th>S. Edmon</th><th>ds Eleme</th><th>ntary Sc</th><th>hool</th><th></th><th></th><th></th><th></th><th>Inspection</th><th>Dates: 06/11- 06/1</th><th>15/2019</th><th></th><th></th></th<>		Name of Inspector: Rvan Hutse								F.	S. Edmon	ds Eleme	ntary Sc	hool					Inspection	Dates: 06/11- 06/1	15/2019		
1 1		Inspection Company: Synertech	h h		1			1		T	1	1		1	1			1	ULCS# 621			1	
1 1	E e m e n	F I o On Site Beem Name	Occupied	Primary		Calar	Primary	Component Damage		Component XRF (positive/		Substrate	Calar	Paint and Plaster	Component Damage		Component XRF (positive/	(describe	Quantity (al)	Contents Need to	On-going Moisture	Needed (yes or	Comments/ Description/ Notes
1 1	1	Storage outside Girl's Restroom across from																	Quantity (st)				Comments/ Description/ Notes
1 1 1 1 1 <	1	Storage outside Girl's Restroom across from				1		-	-	· · · ·									0				
I I	1	Storage outside Girl's Restroom across from 1 Classroom 103						N/A							1				0			No	
1 1 1 1 1 0	1	1 Classroom 103	Yes	W2	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	
I I	1	1 Classroom 103	Yes	W3	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	
I I Image is a strain of a strain	1	1 Classroom 103	Yes	W4	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	
1 1 0	1	1 Classroom 103	Yes	Ceiling	Concrete	White	Cracking		-	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	
1 1 2 2 2 2 2 4 3	1			Floor	Concrete		None			N/A								None	0	No			Current Classroom Modification
1 1 2 2 2 2 3	1	1 Classroom 103	Yes	W1	Concrete			10	0.02	Negative	N/A		N/A	N/A	N/A		N/A	None	0	No	No	No	Project Ongoing Current Classroom Modification
1 1 1 1 1 1 0	1	1 Classroom 103						6	0						N/A				0				Current Classroom Modification
1 1	1	1 Classroom 103												1	2				0				Project Ongoing Current Classroom Modification
1 1 2 3 3 3 3 3 0 N	1	1 Classroom 103													_				0				Project Ongoing Current Classroom Modification
1 1 0 0mme 1 0 0mme 0mme 1 0 0mme 1 0 0mme 0mm	1	1 Classroom 103						10	0	Negative							<i>,</i>		0	No			Current Classroom Modification
1 1 2 assessmelle 3 3 3 3 3 3 3 3 3 3 3 3 3 3 5 5 5 5	1						1	5	0						N/A				0	No			Current Classroom Modification
1 1 2 0	1	1 Classroom 103													2				0				Current Classroom Modification
1 1 2 Description 3 Description Descripion Description Descr	1	1 Classroom 103													2				0				Current Classroom Modification
1 1 2 3 Description Yes Yes <td>1</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td>0.02</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td>0</td> <td></td> <td></td> <td></td> <td>Current Classroom Modification</td>	1								0.02										0				Current Classroom Modification
I I Base Base Base Base Base Base Base Base	1						1		0										0				Current Classroom Modification
I I Description Bind model bands Part Bind Bind Bind Bind Bind Bind Bind Bind		Classroom 103 Storage Closet towards																	0				Current Classroom Modification
1 1 0	1	Classroom 103 Storage Closet towards									,			ĺ ĺ	N/A				0				Current Classroom Modification
I I Converts With Other Other State	1	Classroom 103 Storage Closet towards			-	· · ·									1				0				Current Classroom Modification
1 1 0	1	Classroom 103 Storage Closet towards																	0				Current Classroom Modification
1 1 0 0xxxx 0xxx 0xxx 0xxx 0xxx 0xxx <td>1</td> <td>Classroom 103 Storage Closet towards</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td>6</td> <td></td> <td></td> <td>,</td> <td></td> <td></td> <td></td> <td></td> <td>í.</td> <td>,</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td>Current Classroom Modification</td>	1	Classroom 103 Storage Closet towards						6			,					í.	,						Current Classroom Modification
I N Norm Norm<	1	Classroom 103 Storage Closet towards						2											0				Current Classroom Modification
1 1 0 Control 100 from Cold hourse Yes	1	Classroom 103 Storage Closet towards		Eloor				0											0	No			Current Classroom Modification
I Concernent 100 Strange Concent under 100 Strange Conce	1	Classroom 103 Storage Closet towards		W1				0						N/A		-			0	No	No		Current Classroom Modification
1 0 Description 10 sharege Color bandle yes you Description 10 sharege NA NA NA NA NA	1	Classroom 103 Storage Closet towards	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	White	Chipping	1	0.4	Negative	None	0	No	No	No	Current Classroom Modification
1 Classroom 103 Biologic Class bandle Vie Vie Code Code Withe Code Code No. No. </td <td>1</td> <td>Classroom 103 Storage Closet towards</td> <td></td> <td>W2</td> <td></td> <td></td> <td></td> <td>8</td> <td>0</td> <td>Negative</td> <td></td> <td></td> <td></td> <td></td> <td>N/A</td> <td></td> <td></td> <td></td> <td>0</td> <td>No</td> <td>No</td> <td></td> <td>Current Classroom Modification</td>	1	Classroom 103 Storage Closet towards		W2				8	0	Negative					N/A				0	No	No		Current Classroom Modification
1 Classion 103 Starge Case bands Yes M Owner With No.e Vith No.e N	1	Classroom 103 Storage Closet towards	Yes	W3	Concrete			4	0.02		N/A	N/A	N/A	N/A	N/A		N/A	None	0	No	No	No	Current Classroom Modification
1 1 0 Casing Course With None 0 NA	1	Classroom 103 Storage Closet towards 1 Classroom 101	Yes	W4	Concrete	White	None	0		N/A		N/A	N/A	N/A	N/A		N/A	None	0	No	No	No	Current Classroom Modification Project Ongoing
1 1 0 Cancerée N/A	1	Classroom 103 Storage Closet towards 1 Classroom 101	Yes	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	Current Classroom Modification
I I Description Yes Yes	1	Classroom 103 Storage Closet towards	Yes	Floor	Concrete	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	Project Ongoing
1 1 2 Disarcom 103 Boy's Restroom Yes With N/A	1		Yes	W1	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	Current Classroom Modification Project Ongoing
1 1 Classroom 103 Boy's Restroom Yes W2 Concrete White Chipping 6 0 Negative N/A	1	1 Classroom 103 Boy's Restroom	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	White	Chipping	1	0.45	Negative	None	0	No	No	No	Project Ongoing
1 1 0 1 0 N/A	1	1 Classroom 103 Boy's Restroom	Yes	W2	Concrete	White	Chipping	6	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	Current Classroom Modification Project Ongoing
1 1 Classroom 103 Boy's Restroom Yes V4 Correct White Chipping 2 0 Negative N/A	1		Yes	W3	Concrete	White		0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	Project Ongoing
1 Classroom 103 Bory's Restroom Yes Celling Correct White None 0 N/A	1	1 Classroom 103 Boy's Restroom	Yes	W4	Concrete	White	Chipping	2	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	Current Classroom Modification Project Ongoing
1 1 Classroom 1038 Day's Restroom Yes Floor Concrete N/A N/A <th< td=""><td>1</td><td>1 Classroom 103 Boy's Restroom</td><td>Yes</td><td>Ceiling</td><td>Concrete</td><td>White</td><td>None</td><td>0</td><td>N/A</td><td>N/A</td><td>N/A</td><td>N/A</td><td>N/A</td><td>N/A</td><td>N/A</td><td>N/A</td><td>N/A</td><td>None</td><td>0</td><td>No</td><td>No</td><td>No</td><td>Project Ongoing</td></th<>	1	1 Classroom 103 Boy's Restroom	Yes	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	Project Ongoing
1 Classroom 103 Girl's Restroom Yes Vit Concrete White No N/A N/A <t< td=""><td>1</td><td>1 Classroom 103 Boy's Restroom</td><td>Yes</td><td>Floor</td><td>Concrete</td><td>N/A</td><td>None</td><td>0</td><td>N/A</td><td>N/A</td><td>N/A</td><td>N/A</td><td>N/A</td><td>N/A</td><td>N/A</td><td>N/A</td><td>N/A</td><td>None</td><td>0</td><td>No</td><td>No</td><td>No</td><td>Project Ongoing</td></t<>	1	1 Classroom 103 Boy's Restroom	Yes	Floor	Concrete	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	Project Ongoing
1 1 Classroom 103 Girl's Restroom Yes W2 Correte White C racking 5 0.02 Negative N/A	1	1 Classroom 103 Girl's Restroom	Yes	W1	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	Current Classroom Modification Project Ongoing
1 1 Classroom 103 Girl's Restroom Yes W3 Correcte White No 0 NA N/A N/A<	1	1 Classroom 103 Girl's Restroom	Yes	W2	Concrete	White	Cracking	5	0.02	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	Project Ongoing
1 Classroom 103 Girl's Restroom Yes W4 Concrete Wite Cracking 4 O.44 Ngative N/A	1	1 Classroom 103 Girl's Restroom	Yes	W3	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	Project Ongoing
1 1 Classroom 103 Gir's Restroom Yes Correcte White None 0 N/A N	1	1 Classroom 103 Girl's Restroom	Yes	W4	Concrete	White	Cracking	4	0.04	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	Current Classroom Modification Project Ongoing
1 1 Classroom 103 Girl's Restroom Yes Floor Concrete N/A N/A <th< td=""><td>1</td><td>1 Classroom 103 Girl's Restroom</td><td>Yes</td><td>Ceiling</td><td>Concrete</td><td>White</td><td>None</td><td>0</td><td>N/A</td><td>N/A</td><td>N/A</td><td>N/A</td><td>N/A</td><td>N/A</td><td>N/A</td><td>N/A</td><td>N/A</td><td>None</td><td>0</td><td>No</td><td>No</td><td>No</td><td>Project Ongoing</td></th<>	1	1 Classroom 103 Girl's Restroom	Yes	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	Project Ongoing
1 1 Hallway at Classroom 103 Yes W1 Concrete White None 0 N/A N/A <td>1</td> <td>1 Classroom 103 Girl's Restroom</td> <td>Yes</td> <td>Floor</td> <td>Concrete</td> <td>N/A</td> <td>None</td> <td>0</td> <td>N/A</td> <td>N/A</td> <td>N/A</td> <td>N/A</td> <td>N/A</td> <td>N/A</td> <td>N/A</td> <td>N/A</td> <td>N/A</td> <td>None</td> <td>0</td> <td>No</td> <td>No</td> <td>No</td> <td>Project Ongoing</td>	1	1 Classroom 103 Girl's Restroom	Yes	Floor	Concrete	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	Project Ongoing
1 1 Hallway at Classroom 103 Yes W2 Concrete White None 0 N/A	1	1 Hallway at Classroom 103	Yes	W1	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	Project Ongoing
	1	1 Hallway at Classroom 103	Yes	W2	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	
1 1 Hallway at Classroom 103 Yes W3 Concrete White None 0 No No Project Original 1 1 Hallway at Classroom 103 Yes W3 Concrete White No N/A	1	1 Hallway at Classroom 103	Yes	W3	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	

										nool Dist												
										afe Certifi												
	Name of Inspector: Ryan Hutse								F.	S. Edmon	as Elemei	ntary Sc	nooi					Inspection [Dates: 06/11- 06/	15/2019		
	Inspection Company: Synertech																	ULCS# 6210)	10/2010		
E e m e n	F I 0 0 7 0 0-Site Room Name	Student Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)	Additional Component	Substrate Material	Color	Description of Paint and Plaster Damage	Additional Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Additional Component XRF (positive/ negative)	Debris Present (describe location)	Quantity (sf)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Comments/ Description/ Notes
1	1 Hallway at Classroom 103	Yes	W4	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	Current Classroom Modification Project Ongoing
	1 Hallway at Classroom 103	Yes	Ceiling	Concrete	White	None		N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None		No	No	No	Current Classroom Modification
1			Eloor		N/A	None	0	N/A N/A	N/A	N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A		0	No			Project Ongoing Current Classroom Modification
1	1 Hallway at Classroom 103	Yes		Concrete			0										None	0		No	No	Project Ongoing Current Classroom Modification
1	1 Classroom 103 Hallway Storage	Yes	W1	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	Project Ongoing Current Classroom Modification
1	1 Classroom 103 Hallway Storage	Yes	W2	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	Project Ongoing Current Classroom Modification
1	1 Classroom 103 Hallway Storage	Yes	W3	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	Project Ongoing Current Classroom Modification
1	1 Classroom 103 Hallway Storage	Yes	W4	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	Project Ongoing Current Classroom Modification
1	1 Classroom 103 Hallway Storage	Yes	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	Project Ongoing Current Classroom Modification
1	1 Classroom 103 Hallway Storage	Yes	Floor	Concrete	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	Project Ongoing Current Classroom Modification
1	1 Classroom 104	Yes	W1	Concrete	White	Flaking	60	0.02	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	Current Classroom Modification Project Ongoing Current Classroom Modification
1	1 Classroom 104	Yes	W1	Plaster	White	Flaking	60	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	Project Ongoing
1	1 Classroom 104	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	Red	Chipping	1	0.27	Negative	None	0	No	No	No	Current Classroom Modification Project Ongoing Current Classroom Modification
1	1 Classroom 104	Yes	W2	Concrete	White	Cracking	10	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	Project Ongoing
1	1 Classroom 104	Yes	W3	Concrete	White	Efflorescence	50	0.04	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	Brick Pointing	No	Current Classroom Modification Project Ongoing
1	1 Classroom 104	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A	Radiator Cover	Metal	White	Chipping	2	0.55	Negative	None	0	No	No	No	Current Classroom Modification Project Ongoing
1	1 Classroom 104	Yes	W4	Concrete	White	Efflorescence	10	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	Current Classroom Modification Project Ongoing
1	1 Classroom 104	Yes	Ceiling	Concrete	White	Cracking	10	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	Current Classroom Modification Project Ongoing
	1 Classroom 104	Yes	Eloor	Concrete	N/A	None	0	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	Current Classroom Modification
	i Classioni Iu-	Yes	W1				Ŭ	0		N/A	N/A		N/A	N/A	N/A N/A			-	No	No	No	Project Ongoing Current Classroom Modification
1	1 Classroom 102			Concrete	White	Chipping	35	0	Negative			N/A		N/A		N/A	None	0		No	No	Project Ongoing Current Classroom Modification
1		Yes	W1	Plaster	White	Flaking	15	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	Project Ongoing Current Classroom Modification
1	1 Classroom 102	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	Red	Chipping	3	0.24	Negative	None	0	No	No	No	Project Ongoing Current Classroom Modification
1	1 Classroom 102	Yes	W2	Concrete	White	Flaking	10	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	Project Ongoing Current Classroom Modification
1	1 Classroom 102	Yes	W3	Concrete	White	Efflorescence	5	0.02	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	Brick Pointing	No	Project Ongoing Current Classroom Modification
1	1 Classroom 102	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A	Radiator Cover	Metal	White	Chipping	2	0.54	Negative	None	0	No	No	No	Project Ongoing Current Classroom Modification
1	1 Classroom 102	Yes	W4	Concrete	White	Efflorescence	5	0.02	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	Project Ongoing Current Classroom Modification
1	1 Classroom 102	Yes	Ceiling	Concrete	White	Efflorescence	6	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	Roof leak	No	Project Ongoing Current Classroom Modification
1	1 Classroom 102	Yes	Floor	Concrete	N/A	None	0	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	Project Ongoing Current Classroom Modification
1	Hallway/Stairs to Exterior between Classrooms 1 101 & 102	Yes	W1	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	Project Ongoing
1	Hallway/Stairs to Exterior between Classrooms 1 101 & 102	Yes	W2	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	Current Classroom Modification Project Ongoing
1	Hallway/Stairs to Exterior between Classrooms 1 101 & 102	Yes	W3	Concrete	White	None	Ö	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	Current Classroom Modification Project Ongoing Current Classroom Modification
1	Hallway/Stairs to Exterior between Classrooms 1 101 & 102	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	Brown	Flaking	6	2.9	Positive	None	0	No	No	No	Project Ongoing
1	Hallway/Stairs to Exterior between Classrooms 1 101 & 102	Yes	W4	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	Current Classroom Modification
1	Hallway/Stairs to Exterior between Classrooms 1 101 & 102	Yes	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	Project Ongoing Current Classroom Modification Project Ongoing
1	Hallway/Stairs to Exterior between Classrooms 1 101 & 102	Yes	Floor	Concrete	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	Current Classroom Modification Project Ongoing
1	1 Classroom 101	Yes		Concrete	White	Chipping	10		Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None		No	No	No	Current Classroom Modification
1	1 Classroom 101	Yes	W1	Plaster	White	Cracking	2	0.02	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A N/A	None	0	No	No	No	Project Ongoing Current Classroom Modification Project Ongoing
-		Yes	W1 W1				N/A	0.02 N/A						IN/A	0.24							Current Classroom Modification
1	1 Classroom 101			N/A	N/A	N/A	N/A		N/A	Door Frame	Metal	White	Chipping	2		Negative	None	0	No	No	No	Project Ongoing Current Classroom Modification
1	1 Classroom 101	Yes	W2	Concrete	White	Chipping	8	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	Project Ongoing Current Classroom Modification
1	1 Classroom 101	Yes	W3	Concrete	White	Chipping	12	0.04	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	Project Ongoing Current Classroom Modification
1	1 Classroom 101	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A	Radiator Cover	Metal	White	Chipping	2	0.8	Positive	None	0	No	No	No	Project Ongoing Current Classroom Modification
1	1 Classroom 101	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A	Pipe Riser	Metal	White	Chipping	3	0.3	Negative	None	0	No	No	No	Project Ongoing Current Classroom Modification
1	1 Classroom 101	Yes	W4	Concrete	White	Chipping	8	0.04	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	Project Ongoing Current Classroom Modification
1	1 Classroom 101	Yes	Ceiling	Concrete	White	Cracking	10	0.04	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	Project Ongoing Current Classroom Modification
1	1 Classroom 101	Yes	Floor	Concrete	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	Project Ongoing Current Classroom Modification
1	1 Classroom 101 Restroom	Yes	W1	Concrete	White N/A	Chipping N/A	2 N/A	0.02 N/A	Negative	N/A Door Frame	N/A Metal	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	Current Classroom Modification Project Ongoing
1	1 Classroom 101 Restroom	Yes	W1	Concrete		1673	N/A					White	Chipping	1	0.5	Negative	None	U		No		Current Classroom Modification
1	1 Classroom 101 Restroom	Yes	W2	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	Project Ongoing Current Classroom Modification
1	1 Classroom 101 Restroom	Yes	W3	Concrete	White	Chipping	4	0.06	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	Project Ongoing Current Classroom Modification
1	1 Classroom 101 Restroom	Yes	W4	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	Project Ongoing

										hool Dis												
										Safe Certifi												
	Name of Inspector: Ryan Huts	ell							г.	S. Edmon	as Eleme	ntary Sci	nooi					Inspection I	Dates: 06/11- 06/*	15/2019		
E	Inspection Company: Synertee	ch			1			1	r	1	1	1	1	r	1		T	ULCS# 6210)		1	1
I e F m I e o n o t r	On-Site Room Name	Student Teacher Occupied (ves/no)	Primary	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)	Additional	Substrate Material	Color	Description of Paint and Plaster Damage	Additional Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Additional Component XRF (positive/ negative)	Debris Present (describe location)	Quantity (sf)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Comments/ Description/ Notes
1 1	Classroom 101 Restroom	Yes	Ceiling	Concrete	White	None		N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	Quantity (SI)	No	No	No	Current Classroom Modification Project Ongoing
1 1		Yes	Floor	Concrete	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	Current Classroom Modification Project Ongoing
1 1	Classroom 101 Restroom	Yes	W1	Concrete	White	Chipping	5	0.06	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	Current Classroom Modification Project Ongoing
1 1	Classroom 101 Restroom	Yes	W1	Concrete	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	White	Chipping	2	0.37	Negative	None	Ö	No	No	No	Current Classroom Modification
1 1	Classroom 101 Restroom	Yes	W2	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	Project Ongoing Current Classroom Modification
1 1	Classroom 101 Restroom	Yes	W3	Concrete	White	Cracking	5	0.02	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	Project Ongoing Current Classroom Modification
1 1	Classroom 101 Restroom	Yes	W4	Concrete	White	Chipping	9	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	Project Ongoing Current Classroom Modification
1 1	Classroom 101 Restroom	Yes	Ceiling	Concrete	White	None	0	0.04	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	Project Ongoing Current Classroom Modification
1 1	Classroom 101 Restroom	Yes	Floor	Concrete	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	Project Ongoing Current Classroom Modification
1 1	Classroom 101 Storage	Yes	W1	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	Project Ongoing Current Classroom Modification
1 1	Classroom 101 Storage	Yes	W2	Concrete	White	Cracking	3	0.02	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	Project Ongoing Current Classroom Modification
1 1	Classroom 101 Storage	Yes	W3	Concrete	White	Chipping	4	0.02	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	Project Ongoing Current Classroom Modification
1 1	Classroom 101 Storage	Yes	W4	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	Project Ongoing Current Classroom Modification
1 1	Classroom 101 Storage	Yes	Ceiling	Concrete	White	Cracking	2	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	Project Ongoing Current Classroom Modification
	Classroom 101 Storage	Yes	Floor	Concrete	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	Project Ongoing Current Classroom Modification
1 1 1 1	Hallway at Classroom 101 Hallway at Classroom 101	Yes	W1 W1	Concrete Concrete	White N/A	Chipping N/A	4 N/A	0 N/A	Negative N/A	N/A Door Frame	N/A Metal	N/A White	N/A Chipping	N/A 1	N/A 0.61	N/A Negative	None None	0	No No	No No	No No	Project Ongoing
1 1	Hallway at Classroom 101	Yes	W2	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	Current Classroom Modification Project Ongoing
	Hallway at Classroom 101	Yes	W3	Concrete	White	None	0	N/A	N/A	N/A	N/A N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	Current Classroom Modification Project Ongoing
1 1	Hallway at Classroom 101	Yes	W3	Concrete	White	None	0	N/A	N/A	N/A		N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	Current Classroom Modification
1 1	Hallway at Classroom 101	Yes	W4	Concrete	White	Chipping	7	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	Project Ongoing Current Classroom Modification
1 1	Hallway at Classroom 101	Yes	Ceiling	Concrete	White	Cracking	4	0.04	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	Project Ongoing Current Classroom Modification
1 1	Hallway at Classroom 101	Yes	Floor	Concrete	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	Project Ongoing Current Classroom Modification
1 1	Classroom 101 Hallway Storage	Yes	W1	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	Project Ongoing Current Classroom Modification
1 1	Classroom 101 Hallway Storage	Yes	W2	Concrete	White	Cracking	4	0.02	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	Project Ongoing Current Classroom Modification
1 1	Classroom 101 Hallway Storage	Yes	W3	Concrete	White	None	0 4	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	Project Ongoing Current Classroom Modification
1 1	Classroom 101 Hallway Storage	Yes	W4	Concrete	White	Chipping	4	0.06	Negative	N/A N/A	N/A N/A	N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	None	0	No	No	No	Project Ongoing Current Classroom Modification
1 1	Classroom 101 Hallway Storage		Ceiling	Concrete		Cracking			Negative			N/A	N/A N/A				None	0		No		Project Ongoing Current Classroom Modification
1 1	Classroom 101 Hallway Storage	Yes	Floor W1	Concrete	N/A	None	0	N/A	N/A	N/A	N/A	N/A		N/A	N/A	N/A	None	0	No	No	No	Project Ongoing Current Classroom Modification
1 1	Storage at Classroom 101 Storage at Classroom 101	Yes	W1 W2		White	Cracking	2	0.04	Negative Negative	N/A	N/A	N/A	N/A N/A	N/A	N/A N/A	N/A	None	0	No	No	No	Project Ongoing Current Classroom Modification
1 1	Storage at Classroom 101 Storage at Classroom 101	Yes	W2 W3	Concrete	White	None	0	0.04 N/A	Negative N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	None	0	No	No	No	Project Ongoing Current Classroom Modification
		Yes	W4	Concrete	White	Cracking	3	0.04	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	Project Ongoing Current Classroom Modification
1 4	Storage at Classroom 101 Storage at Classroom 101	Yes	Ceiling	Concrete	White	None	0	0.04 N/A	N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A	N/A N/A	None	0	No	No	No	Project Ongoing Current Classroom Modification Project Ongoing
1 4	Storage at Classroom 101	Yes	Floor	Concrete	N/A	None	0	N/A	N/A	N/A N/A	N/A	N/A	N/A	N/A N/A	N/A	N/A	None	0	No	No	No	Current Classroom Modification Project Ongoing
1 4	Main Entrance Hallway	Yes	W1	Concrete	White	Chipping	6	0.08	Negative	N/A	N/A	N/A	N/A N/A	N/A N/A	N/A	N/A	None	0	No	No	No	Current Classroom Modification Project Ongoing
1 1	Main Entrance Hallway	Yes	W1	Concrete	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	White	Chinning	2	0.54	Negative	None	0	No	No	No	Current Classroom Modification Project Ongoing
1 1	Main Entrance Hallway	Yes	W2	Concrete	White	Chipping	10	0.04	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	Current Classroom Modification Project Ongoing
1 1	Main Entrance Hallway	Yes	W3	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	Current Classroom Modification Project Ongoing
1 1	Main Entrance Hallway	Yes	W3	Concrete	White	Chipping	8	0.02	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	Current Classroom Modification Project Ongoing
	Main Entrance Hallway	Yes	W4	Concrete	White	Chipping	,	0.02	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	Current Classroom Modification Project Ongoing
1 1	Main Entrance Hallway	Yes	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	Current Classroom Modification Project Ongoing
1 1	Main Entrance Hallway	Yes	Floor	Concrete	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	Current Classroom Modification Project Ongoing
1 2	Classroom 201	Yes	W1	Concrete	White	Flaking	200	0.03	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	Unknown	Yes	Current Classroom Modification Project Ongoing
1 2	Classroom 201	Yes	W1	Plaster	White	Flaking	15	0.04	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	Current Classroom Modification Project Ongoing
1 2	Classroom 201	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	Blue	Chipping	10	0.4	Negative	None	0	No	No	No	Current Classroom Modification Project Ongoing
1 2	Classroom 201	Yes	W2	Concrete	White	Flaking	50	0.01	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	Current Classroom Modification Project Ongoing
1 2	Classroom 201	Yes	W3	Concrete	White	Flaking	40	0.05	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	Brick Pointing	Yes	Current Classroom Modification Project Ongoing
1 2	Classroom 201	Yes	W4	Concrete	White	Flaking	40	0.05	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	Brick Pointing	Yes	Current Classroom Modification Project Ongoing
	Classroom 201	Yes	Ceiling	Concrete	White	Flaking	30	0.06	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None		No	Roof leak	No	Current Classroom Modification Project Ongoing

										nool Dist												
										afe Certifi												
	Name of Inspector: Ryan Hutse								F.	S. Edmon	as Eleme	ntary Sc	nooi						Dates: 06/11- 06/	15/2019		
E	Inspection Company: Synertech	1			1			1						1			1	ULCS# 6210				
l m e n t	F I o o r On-Site Room Name	Student Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)	Additional	Substrate Material	Color	Description of Paint and Plaster Damage	Additional Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Additional Component XRF (positive/ negative)	Debris Present (describe location)	Quantity (sf)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Comments/ Description/ Notes
1	2 Classroom 201	Yes	Floor	Concrete	Grey	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	Current Classroom Modification Project Ongoing
1	2 Classroom 202	Yes	W1	Concrete	White	Flaking	70	0.01	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	Current Classroom Modification Project Ongoing
1	2 Classroom 202	Yes	W1	Plaster	White	Flaking	14	0.01	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	Current Classroom Modification Project Ongoing Current Classroom Modification
1	2 Classroom 202	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	Blue	Chipping	8	0.4	Negative	None	0	No	No	No	Project Ongoing
1	2 Classroom 202	Yes	W2	Concrete	White	Flaking	10	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	Current Classroom Modification Project Ongoing
1	2 Classroom 202	Yes	W3	Concrete	White	Flaking	50	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	Current Classroom Modification Project Ongoing
1	2 Classroom 202	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A	Radiator cover	Metal	Tan	Chipping	4	0.6	Negative	None	0	No	No	No	Current Classroom Modification Project Ongoing
1	2 Classroom 202	Yes	W4	Concrete	White	Flaking	20	0.04	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	Unknown	Yes	Current Classroom Modification Project Ongoing
1	2 Classroom 202	Yes	Ceiling	Concrete	White	Flaking	50	0.05	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	Current Classroom Modification Project Ongoing
1	2 Classroom 202	Yes	Floor	Concrete	Grey	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	Current Classroom Modification Project Ongoing
1	2 Classroom 203	Yes	W1	Concrete	White	Flaking	45	0.05	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	Current Classroom Modification Project Ongoing
1	2 Classroom 203	Yes	W1	Plaster	White	Flaking	20	0.05	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	Current Classroom Modification Project Ongoing
1	2 Classroom 203	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	Blue	Chipping	12	0.4	Negative	None	0	No	No	No	Current Classroom Modification Project Ongoing
1	2 Classroom 203	Yes	W2	Concrete	White	Flaking	2	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	Current Classroom Modification Project Ongoing
1	2 Classroom 203	Yes	W3	Concrete	White	Flaking	30	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	Unknown	Yes	Current Classroom Modification Project Ongoing
		Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A	Radiator cover	Metal	Tan	Chipping	6	0.3	N/A	None	0	No	No	No	Current Classroom Modification Project Ongoing
4	2 Classroom 203 2 Classroom 203	Yes	W4	Concrete	White	Cracking	3	0	Negative	N/A	N/A	N/A	N/A	N/A	0.3	N/A	None	0	No	No	No	Current Classroom Modification Project Ongoing
	2 Classroom 203	Yes	Ceiling	Concrete	White	Cracking	2	0		N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	Current Classroom Modification
1	2 Classroom 203		Eloor				0	N/A	Negative	N/A	N/A N/A		N/A	N/A	N/A N/A			0	No	No		Project Ongoing Current Classroom Modification
1	2 Classroom 203	Yes	Floor	Concrete	Grey	None	-	N/A	N/A			N/A			1	N/A	None	0	No	No	No	Project Ongoing Current Classroom Modification
1	2 Classroom 204	Yes	W1	Concrete	White	Flaking	100	0	Negative	N/A N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	Project Ongoing Current Classroom Modification
		Yes	W1	Plaster	White	Flaking	10	0	Negative		N/A	N/A	N/A	N/A	N/A	N/A	None	0	No		No	Project Ongoing Current Classroom Modification
1	2 Classroom 204	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	Blue	Chipping	9	0.5	Negative	None	0	No	No	No	Project Ongoing Current Classroom Modification
1	2 Classroom 204	Yes	W2	Concrete	White	Flaking	20	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	Project Ongoing Current Classroom Modification
1	2 Classroom 204	Yes	W3	Concrete	White	Flaking	80	0.01	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	Brick Pointing	Yes	Project Ongoing Current Classroom Modification
1	2 Classroom 204	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A	Radiator cover	Metal	Tan	Chipping	3	0.45	Negative	None	0	No	No	No	Project Ongoing Current Classroom Modification
1	2 Classroom 204	Yes	W4	Concrete	White	Flaking	20	0.05	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	Project Ongoing Current Classroom Modification
1	2 Classroom 204	Yes	Ceiling	Concrete	White	Flaking	30	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	Roof leak	Yes	Project Ongoing Current Classroom Modification
1	2 Classroom 204	Yes	Floor	Concrete	Grey	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	Project Ongoing Ceramic Tile - Not damaged, but
· ·	2 Boy's Restroom across from Classroom 205 2 Boy's Restroom across from Classroom 205	Yes Yes	W1 W2	Ceramic Tile Ceramic Tile	Tan Tan	None None	0	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	None None	0	No	No No	No	glazing is positive
1	2 Boy's Restroom across from Classroom 205	Yes Yes	W3 W4	Ceramic Tile Ceramic Tile	Tan	None None	0	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	None None	0	No	No No	No	
1	2 Boy's Restroom across from Classroom 205 2 Boy's Restroom across from Classroom 205 2 Day's Restroom across from Classroom 205	Yes	Ceiling	Concrete	White	Cracking	10	0.02	Negative N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A	None	0	No	No	No	
	2 Boy's Restroom across from Classroom 205	Yes		Ceramic Tile	Tan		-	N/A								N/A		-	OVI			Ceramic Tile - Not damaged, but
1	2 Girl's Restroom across from Classroom 205 2 Girl's Restroom across from Classroom 205	Yes Yes	W1 W2	Ceramic Tile Ceramic Tile	Tan Tan	None None	0	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	None None	0	No No	No No	No No	glazing is positive
1	2 Girl's Restroom across from Classroom 205 2 Girl's Restroom across from Classroom 205	Yes Yes	W3 W4	Ceramic Tile Ceramic Tile	Tan Tan	None None	0	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	None None	0	No No	No No	No	
1	2 Girl's Restroom across from Classroom 205 2 Girl's Restroom across from Classroom 205	Yes	Ceiling	Concrete Ceramic Tile	White Tan	Cracking None	3	0 N/A	Negative N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	None None	0	No	No No	No	
1		Yes	W1		Tan		20	0.06		N/A	N/A N/A	N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	None	0	No	No	No	Current Classroom Modification
	2 Classroom 205 2 Classroom 205	Yes	W1	Concrete Plaster	White	Cracking Cracking	30	0.02	Negative Negative	N/A	N/A	N/A	N/A	N/A N/A	N/A	N/A	None	0	No	No	No	Project Ongoing
	2 Classroom 205	Yes	W1	N/A	N/A	N/A	N/A	N/A	Negative	Door Frame	Metal	Red	Chipping	1	0.31	Negative	None	0	No	No	No	Current Classroom Modification
1	2 Classroom 205	Yes	W2	Concrete	Tan	Flaking	50	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	Project Ongoing Current Classroom Modification
1	2 Classroom 205 2 Classroom 205	Yes Yes	W3 W3	Concrete N/A	Tan N/A	Flaking N/A	10 N/A	0.04 N/A	Negative N/A	N/A Radiator Cover	N/A Metal	N/A White	N/A Chipping	N/A 3	N/A 0.6	N/A Negative	None None	0	No No	No No	No No	Project Ongoing
1	2 Classroom 205	Yes	W4	Concrete	Tan	Cracking	10	0.02	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	Current Classroom Modification Project Ongoing Current Classroom Modification
1	2 Classroom 205	Yes	Ceiling	Concrete	White	Cracking	20	0.02	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	Brick Pointing	No	Project Ongoing; Additional Efflorescence
1	2 Classroom 205	Yes	Floor	Concrete	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	Current Classroom Modification Project Ongoing
1	2 Classroom 206	Yes	W1	Concrete	Tan	Flaking	20	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	Current Classroom Modification Project Ongoing
1	2 Classroom 206 2 Classroom 206	Yes Yes	W1 W1	Plaster N/A	White N/A	Cracking N/A	10 N/A	0 N/A	Negative N/A	N/A Door Frame	N/A Metal	N/A Red	N/A Chipping	N/A 2	N/A 0.32	N/A Negative	None None	0	No	No No	No	
1	2 Classroom 206	Yes	W2	Concrete	Tan	Flaking	3	0.02	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	Current Classroom Modification Project Ongoing
1	Classroom 206 Classroom 206 Classroom 206	Yes	W2 W3 W3	Concrete N/A	Tan N/A	Cracking N/A	50 N/A	0.02 0 N/A	Negative Negative N/A	N/A N/A Radiator Cover	N/A Metal	N/A N/A White	N/A N/A Chipping	N/A N/A 4	N/A N/A 0.8	N/A N/A Positive	None	0	No No	No No	No	Current Classroom Modification Project Ongoing
			1		1	1 /						1					1			1	1	Current Classroom Modification

										Safe Certifi		hilade										
										S. Edmon												
	Name of Inspector: Ryan Hutsell																	Inspection I	Dates: 06/11- 06/	15/2019		
F	Inspection Company: Synertech					1			1				1					ULCS# 6210				1
e m e n	F I o o r On-Site Room Name	Student Teacher Occupied (yes/no)	Primary	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)	Additional Component	Substrate Material	Color	Description of Paint and Plaster Damage	Additional Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Additional Component XRF (positive/	Debris Present (describe location)	Quantity (sf)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Comments/ Description/ Note
1	2 Classroom 206	Yes	Ceiling	Concrete	White	Cracking	10	0.02	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	Current Classroom Modification Project Ongoing
1	2 Classroom 206	Yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	Current Classroom Modification Project Ongoing
1	2 Classroom 207	Yes	W1	Concrete	Tan	Cracking	6	0.06	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	Ö	Prior to Repair	No	No	Troject ongoing
1	2 Classroom 207 2 Classroom 207	Yes	W1 W1	Plaster N/A	White N/A	Cracking N/A	2 N/A	0.02 N/A	Negative N/A	N/A Door Frame	N/A Metal	N/A Red	N/A Chipping	N/A 2	N/A 0.25	N/A Negative	None None	0	Prior to Repair Prior to Repair	No No	No	
1	2 Classroom 207 2 Classroom 207	Yes Yes	W2 W3	Concrete Concrete	Tan Tan	Chipping Cracking	10	0	Negative Negative	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	None None	0	Prior to Repair Prior to Repair	No No	No	
1	2 Classroom 207	Yes	W3 W3	N/A	N/A	N/A	N/A	N/A	N/A	Radiator Cover	Metal	White	Chipping	2	0.56	Negative	None	0	Prior to Repair	No	No	
1	2 Classroom 207 2 Classroom 207	Yes	W4 Ceiling	Concrete Concrete	Tan White	Cracking Cracking	5	0.04 N/A	Negative N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	None	0	Prior to Repair No	No	No	
1	2 Classroom 207	Yes	Ceiling Floor	Concrete	N/A	None	0	N/A	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	
1	2 Classroom 208 2 Classroom 208	Yes	W1 W1	Concrete Plaster	Tan White	Cracking Cracking	8	0.02	Negative Negative	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	None	0	Prior to Repair Prior to Repair	No	No	
1	2 Classroom 208	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	Red	Chipping	1	0.29	Negative	None	0	Prior to Repair	No	No	
1	2 Classroom 208 2 Classroom 208	Yes	W2 W3	Concrete Concrete	Tan Tan	Chipping Flaking	14	0.04	Negative Negative	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	None	0	Prior to Repair Prior to Repair	No No	No	
1	2 Classroom 208	Yes	W3	N/A	N/A	N/A	N/A	N/A	Negative	Radiator Cover	Metal	White	Chipping	3	0.66	Negative	None	0	Prior to Repair	No	No	
1	2 Classroom 208 2 Classroom 208	Yes	W4 Ceiling	Concrete Concrete	Tan White	Chipping Cracking	8	0	Negative Negative	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	None None	0	Prior to Repair No	No No	No	
1	2 Classroom 208	Yes	Ceiling Floor	Concrete	N/A	None	0	N/A	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No Brier to Repair	No	No	+
1 :	2 Classroom 209 2 Classroom 209	Yes Yes	W1 W1	Concrete Plaster	Tan White	Cracking Cracking	2	0.02	Negative Negative	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	None None	0	Prior to Repair Prior to Repair	No No	No	
1	2 Classroom 209 2 Classroom 209	Yes Yes	W1 W2	N/A Concrete	N/A Tan	N/A Flaking	N/A 6	N/A 0.04	N/A Negative	Door Frame N/A	Metal N/A	Red N/A	Chipping N/A	2 N/A	0.27 N/A	Negative N/A	None None	0	Prior to Repair Prior to Repair	No	No	
1	2 Classroom 209	Yes	W3	Concrete N/A	Tan	Flaking	12	0.04	Negative N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Prior to Repair	No	No	
1	2 Classroom 209 2 Classroom 209	Yes	W3 W4	N/A Concrete	N/A Tan	N/A Chipping	N/A 10	N/A 0.04	N/A Negative	Radiator Cover N/A	Metal N/A	White N/A	Chipping N/A	4 N/A	0.7 N/A	Positive N/A	None None	0	Prior to Repair Prior to Repair	No	No	
1	2 Classroom 209	Yes	Ceiling	Concrete	White	Chipping None	4	0.02	Negative	N/A	N/A N/A	N/A	N/A N/A	N/A	I N/A	N/A N/A	None	0	No	No	No	
1	2 Classroom 209	Yes	Floor	Concrete	N/A	None	0	N/A	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	Current Classroom Modification
1	2 Classroom 210	Yes	W1	Concrete	Tan	Cracking	8	0.02	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	Project Ongoing Current Classroom Modification
1	2 Classroom 210	Yes	W1	Plaster	White	Cracking	2	0.02	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	Project Ongoing Current Classroom Modification
1	2 Classroom 210	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	Red	Chipping	2	0.36	Negative	None	0	No	No	No	Current Classroom Modification Project Ongoing Current Classroom Modification
1	2 Classroom 210	Yes	W2	Concrete	Tan	Efflorescence	3	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	Project Ongoing
1	2 Classroom 210	Yes	W3	Concrete	Tan	Flaking	30	0.02	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	Current Classroom Modification Project Ongoing
1	2 Classroom 210	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A	Radiator Cover	Metal	White	Chipping	2	0.5	Negative	None	0	No	No	No	Current Classroom Modification Project Ongoing
1	2 Classroom 210	Yes	W4	Concrete	Tan	Efflorescence	60	0.04	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	Current Classroom Modification Project Ongoing
1	2 Classroom 210	Yes	Ceiling	Concrete	White	Cracking	2	0.04	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	Current Classroom Modification Project Ongoing
								0				l í	1		1	í í		0		NU	NO	Current Classroom Modification
1	2 Classroom 210 2 Classroom 211	Yes	Floor W1	Concrete Concrete	N/A Tan	None Cracking	0	0.04	Negative Negative	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	None None	0	No Prior to Repair	No No	No	Project Ongoing
1	2 Classroom 211	Yes	W1 W1	Plaster N/A	White N/A	Cracking N/A	4 N/A	0.02 N/A	Negative N/A	N/A	N/A Metal	N/A Red	N/A	N/A	N/A 0.3	N/A	None None	0	Prior to Repair	No No	No	
1	2 Classroom 211 2 Classroom 211	Yes	W2	Concrete	Tan	Cracking	8	Ó	N/A Negative	Door Frame N/A	N/A	N/A	Chipping N/A	N/A	N/A	Negative N/A	None	0	Prior to Repair Prior to Repair	No	No	
	2 Classroom 211 2 Classroom 211	Yes Yes	W3 W3	Concrete N/A	Tan N/A	Flaking N/A	14 N/A	0.02 N/A	Negative N/A	N/A Radiator Cover	N/A Metal	N/A White	N/A Chipping	N/A 4	N/A 0.56	N/A Nogativo	None	0	Prior to Repair Prior to Repair	No	No	
1	2 Classroom 211	Yes	W4	Concrete	Tan	Cracking	10	0.04	Negative	N/A	N/A	N/A	Chipping N/A	N/A	N/A	Negative N/A	None	ő	Prior to Repair	No	No	
1	2 Classroom 211 2 Classroom 211	Yes	Ceiling	Concrete Concrete	White N/A	Chipping None	6	0.02 N/A	Negative Negative	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	None	0	No	No	No	
1	2 Teacher Lounge next to Classroom 211	Yes	W1	Concrete	White	Flaking	13	0.1	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	Ö	No	Unknown	No	
1	2 Teacher Lounge next to Classroom 211 2 Teacher Lounge next to Classroom 211	Yes	W1 W1	Plaster N/A	White N/A	Flaking N/A	9 N/A	0.02 N/A	Negative N/A	N/A Door Frame	N/A Metal	N/A Red	N/A Chipping	N/A 1	N/A 0.26	N/A Negative	None	0	No	No No	No	
1	2 Teacher Lounge next to Classroom 211	Yes	W2	Concrete	White	Cracking	3	0.02	Negative	N/A	N/A	N/A	Chipping N/A	N/A	N/A	Negative N/A	None	ō	No	No	No	
1	2 Teacher Lounge next to Classroom 211 2 Teacher Lounge next to Classroom 211	Yes	W3 W3	Concrete N/A	White N/A	Flaking N/A	4 N/A	0.04 N/A	Negative N/A	N/A Radiator Cover	N/A Metal	N/A White	N/A Chipping	N/A 1	N/A 0.7	N/A Positive	None	0	No No	No No	No	+
1	2 Teacher Lounge next to Classroom 211	Yes	W3 W4	N/A	N/A	N/A	N/A	N/A 0.02	N/A	Pipe Riser N/A	Metal N/A	White N/A	Chipping Flaking N/A	4 N/A	0.55 N/A	Negative	None	0	No	No	No	
	2 Teacher Lounge next to Classroom 211 2 Teacher Lounge next to Classroom 211	Yes Yes	W4 Ceiling	Concrete Concrete	White White	Cracking Efflorescence	3	0	Negative Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A N/A	None None	0	No	No Brick Pointing	No	
	2 Teacher Lounge next to Classroom 211 Teacher's Lounge Restroom next to Classroom	Yes	Floor	Concrete	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	Floor Tile
1	2 211	Yes	W1	Concrete	Tan	Cracking	16	0.02	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	1
1	Teacher's Lounge Restroom next to Classroom 2 211	Yes	W2	Concrete	Tan	Cracking	20	0.02	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	
1	Teacher's Lounge Restroom next to Classroom 2 211	Yes	W3	Concrete	Tan	Efflorescence	16	0.02	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	Roof leak	No	
1	Teacher's Lounge Restroom next to Classroom 2 211	Yes	W4	Concrete	Tan	Flaking	20	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	
	Teacher's Lounge Restroom next to Classroom	Yes			White		20	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A		0	No	No	Ne	1
	2 211 Teacher's Lounge Restroom next to Classroom		Ceiling	Concrete		None	U										None	U U			NO	
1	2 211 Storage Closet inside Teacher's Lounge 217A	Yes	Floor	Concrete	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	1
1	2 next to Classroom 217 Storage Closet inside Teacher's Lounge 217A	Yes	W1	Concrete	White	Cracking	5	0.04	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Prior to Repair	No	No	
1	2 next to Classroom 217 Storage Closet inside Teacher's Lounge 217A	Yes	W2	Concrete	White	Cracking	2	0.02	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Prior to Repair	No	No	+
1	2 next to Classroom 217 Storage Closet inside Teacher's Lounge 217A	Yes	W3	Concrete	White	Cracking	1	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Prior to Repair	No	No	+
1	2 next to Classroom 217 Storage Closet inside Teacher's Lounge 217A	Yes	W4	Concrete	White	Cracking	1	0.02	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Prior to Repair	No	No	
1	2 next to Classroom 217 Storage Closet inside Teacher's Lounge 217A Storage Closet inside Teacher's Lounge 217A	Yes	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	1
1	2 next to Classroom 217	Yes	Floor	Concrete	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	-
1	2 Hallway from Classrooms 201-211	Yes	W1	Concrete	White	Chipping	16	0.04	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	Current Classroom Modification Project Ongoing Current Classroom Modification
1	2 Hallway from Classrooms 201-211	Yes	W2	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	Project Ongoing
																						Current Classroom Modification

										hool Dist												
										afe Certifi S. Edmon												
Na	ame of Inspector: Rvan Hutsell								г.	S. Eumon	us Eleme	mary Sc	nooi					Inspection	Dates: 06/11- 06/	15/2019		
	spection Company: Synertech			1				1	1	1	T		1	1			1	ULCS# 621	0			1
E I M I e o n o	On-Site Room Name	Student Teacher Occupied	Primary	Substrate Material	Color	Description of Primary	Primary Component Damage	XRF Reading	Primary Component XRF (positive/	Additional	Substrate Material	O lui	Description of Paint and Plaster	Additional Component Damage	XRF Reading	Additional Component XRF (positive/	Debris Present (describe	0	Contents Need to be Moved	On-going Moisture	Plastering Needed (yes or	
t r		(yes/no)	W4			Damage	Quantity (sf)	(mg/cm2)	negative)	Component N/A	N/A	COIOI	Damage	Quantity (sf)	(mg/cm2)	negative)	location)	Quantity (sf)	De Woved	Intrusion	no)	Comments/ Description/ Notes Current Classroom Modification
	Iway from Classrooms 201-211	Yes		Concrete	White	None	0	N/A	N/A	,		N/A	N/A		N/A	N/A	None	0	No		No	Project Ongoing Current Classroom Modification
1 2 Hall	Iway from Classrooms 201-211	Yes	Ceiling	Concrete	White	Flaking	40	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	Roof leak	No	Project Ongoing Current Classroom Modification
1 2 Hall	Iway from Classrooms 201-211	Yes	Floor	Concrete	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	Project Ongoing Current Classroom Modification
1 2 Hall	Iway from Classrooms 213 - 219	Yes	W1	Concrete	White	Flaking	20	0.05	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	Project Ongoing Current Classroom Modification
1 2 Hal	Iway from Classrooms 213 - 219	Yes	W2	Concrete	White	Chipping	10	0.02	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	Project Ongoing Current Classroom Modification
1 2 Hall	Iway from Classrooms 213 - 219	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	White	Chipping	4	0.3	Negative	None	0	No	No	No	Project Ongoing
1 2 Hal	lway from Classrooms 213 - 219	Yes	W3	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	Current Classroom Modification Project Ongoing
1 2 Hall	lway from Classrooms 213 - 219	Yes	W4	Concrete	White	Chipping	10	0.06	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	Current Classroom Modification Project Ongoing
1 2 Hall	lway from Classrooms 213 - 219	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	White	Chipping	5	0.29	Negative	None	0	No	No	No	Current Classroom Modification Project Ongoing
	Iway from Classrooms 213 - 219	Yes	Ceiling	Concrete	White	Flaking	60	0.04	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	Roof leak	No	Current Classroom Modification Project Ongoing
	lway from Classrooms 213 - 219	Yes		Concrete	N/A		0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A		0	No	No	No	Current Classroom Modification
1 2 Hal 1 2 Cla 1 2 Cla	issroom 213	Yes Yes Yes	Floor W1	Concrete Concrete N/A	N/A Tan N/A	None Cracking N/A	4	Ó	N/A Negative N/A	N/A	N/A	N/A	N/A	N/A N/A	N/A	N/A	None None	0	No	No	No	Project Ongoing
1 2 Cla	issroom 213	Yes	W1 W2	Concrete	Tan	None	N/A 0	N/A N/A	N/A	Door Frame N/A	Metal N/A	Red N/A	Chipping N/A	2 N/A	0.37 N/A	Negative N/A	None None	0	No Prior to Repair	No No	No No	
1 2 Clar 1 2 Clar	ssroom 213	Yes Yes	W3 W3	Concrete N/A	Tan N/A	Chipping N/A	6 N/A	0 N/A	Negative N/A	N/A Radiator Cover	N/A Metal	N/A Tan	N/A Chipping	N/A 2	N/A 0.6	N/A Negative	None None	0	Prior to Repair Prior to Repair	No No	No	
1 2 Cla 1 2 Cla	ssroom 213	Yes Yes	W4 Ceiling	Concrete Concrete	Tan White	Cracking Chipping	5	0.04	Negative Negative	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	None	0	Prior to Repair No	No No	No	
1 2 Clar	issroom 213	Yes	Floor	Concrete	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	Floor Tile
1 2 Cla 1 2 Cla 1 2 Cla 1 2 Cla	issroom 215 issroom 215	Yes Yes	W1 W2	Concrete Concrete	Tan Tan	Cracking Cracking	5	0.04	Negative Negative N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	None None	0	Prior to Repair Prior to Repair	No No	No	
1 2 Cla	ssroom 215	Yes Yes	W3 W4	Concrete Concrete	Tan Tan	None None	0	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	None None	0	Prior to Repair Prior to Repair	No	No	
1 2 Cla 1 2 Cla	ssroom 215	Yes	Ceiling	Concrete	White N/A	None	0	N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A	N/A	N/A N/A	N/A N/A	None	0	No	No	No	Floor Tile
1 2 Cla 1 2 Cla 1 2 Cla	ssroom 215 ssroom 217	Yes Yes	Floor W1	Concrete Concrete	Tan/White	None Cracking	25	N/A 0.04	Negative	N/A	N/A	N/A	N/A N/A	N/A N/A	N/A	N/A	None None	0	Prior to Repair	No No	No	FIGOR THE
1 2 Cla 1 2 Cla	ssroom 217 ssroom 217	Yes	W1 W2	N/A Concrete	N/A Tan/White	N/A Cracking	N/A 20	N/A 0	N/A Negative	Door Frame N/A	Metal N/A	White N/A	Chipping N/A	2 N/A	0.4 N/A	Negative N/A	None None	0	Prior to Repair Prior to Repair	No	No	
1 2 Cla 1 2 Cla 1 2 Cla 1 2 Cla	ssroom 217	Yes Yes	W3 W3	Concrete N/A	Tan/White N/A	Cracking N/A	40 N/A	0.02 N/A	Negative N/A	N/A Radiator Cover	N/A Metal	N/A White	N/A Chipping	N/A	N/A 0.8	N/A Positive	None None	0	Prior to Repair Prior to Repair	No No	No	
1 2 Cla	ssroom 217	Yes	W4	Concrete	Tan/White	Cracking	40	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Prior to Repair	No	No	
1 2 Clar 1 2 Clar	issroom 217 issroom 217	Yes Yes	Ceiling Floor	Concrete Concrete	White N/A	Flaking None	60 0	0.02 N/A	Negative N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	None None	0	No No	No No	No No	
1 2 Tea 1 2 Tea	acher's Lounge 217A next to Classroom 217 acher's Lounge 217A next to Classroom 217	Yes	W1 W2	Concrete Concrete	Tan Tan	Cracking Flaking	50 100	0.02	Negative Negative	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	None None	0	No	No	No No	
1 2 Tea 1 2 Tea	acher's Lounge 217A next to Classroom 217 acher's Lounge 217A next to Classroom 217 acher's Lounge 217A next to Classroom 217	Yes Yes	W3 W4	Concrete Concrete	Tan Tan	Cracking Flaking	30	0.02	Negative Negative	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	None Floor	0	No Prior to Repair	No	No	
1 2 Tea	acher's Lounge 217A next to Classroom 217 acher's Lounge 217A next to Classroom 217 acher's Lounge 217A next to Classroom 217	Yes	Ceiling Floor	Concrete	White N/A	Cracking	3	0.02 0 N/A	Negative N/A	N/A N/A	N/A N/A N/A	N/A	N/A N/A N/A	N/A N/A N/A	N/A N/A	N/A	None	0	No	No	No	Figure T11
Sto	rage Closet inside Teacher's Lounge 217A	Yes		Concrete		None	0					N/A				N/A	None	0	No Partially	No	No	Floor Tile
1 2 nex	t to Classroom 217 rage Closet inside Teacher's Lounge 217A	Yes	W1	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Inaccessible Partially	No	No	
1 2 nex	t to Classroom 217 rage Closet inside Teacher's Lounge 217A	Yes	W2	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Inaccessible Partially	No	No	
1 2 nex	t to Classroom 217	Yes	W3	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Inaccessible	No	No	
1 2 nex	rage Closet inside Teacher's Lounge 217A tt to Classroom 217	Yes	W4	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Inaccessible	No	No	
1 2 nex	rage Closet inside Teacher's Lounge 217A tt to Classroom 217	Yes	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Partially Inaccessible	No	No	
1 2 nex	rage Closet inside Teacher's Lounge 217A t to Classroom 217 ff Restroom inside Teacher's Lounge 217A	Yes	Floor	Concrete	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Partially Inaccessible	No	No	
1 2 nex	t to Classroom 217	Yes	W1	Concrete	White	Cracking	10	0.06	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	
	ff Restroom inside Teacher's Lounge 217A tt to Classroom 217 ff Restroom inside Teacher's Lounge 217A	Yes	W2	Concrete	White	Cracking	20	0.1	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	
1 2 nex	ff Restroom inside Teacher's Lounge 217A tt to Classroom 217	Yes	W3	Concrete	White	Cracking	6	0.02	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	
1 2 per	t to Classroom 217 ff Restroom inside Teacher's Lounge 217A t to Classroom 217	Yes	W4	Concrete	White	Cracking	10	0.04	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	
1 2 Sta	t to Classroom 217 ff Restroom inside Teacher's Lounge 217A tt to Classroom 217	Yes	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Ne	No	No	
Star	ff Restroom inside Teacher's Lounge 217A	Yes	Floor	Concrete	N/A	None	~	N/A N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None		No	No	No	
	t to Classroom 217									N/A									NO		NO	Ceramic Tile - Not damaged, but
1 2 Boy	/'s Restroom across from Classroom 217 /'s Restroom across from Classroom 217	Yes	W1 W2	Ceramic Tile Ceramic Tile	Tan Tan	None None	0	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	None None	0	No	No No	No	glazing is positive
1 2 Boy	's Restroom across from Classroom 217	Yes Yes	W3 W4	Ceramic Tile Ceramic Tile	Tan Tan	None None	0	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	None None	0	No No	No No	No	
1 2 Boy	/s Restroom across from Classroom 217 /s Restroom across from Classroom 217 /s Restroom across from Classroom 217	Yes	Ceiling Floor	Concrete Ceramic Tile	White Tan	None	0	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	None	0	No	No	No	
Hall	/'s Restroom across from Classroom 217 Iway Storage Room "H2" next to Boy's	Yes	HIDOF W1		White	None	0	N/A N/A	N/A N/A	N/A	N/A	N/A N/A	N/A N/A	N/A	N/A N/A	N/A N/A			Partially	No	No	
Hal	stroom across from Classroom 217 Iway Storage Room "H2" next to Boy's			Concrete			U										None	U	Inaccessible Partially		No	
1 2 Res Hall	stroom across from Classroom 217 Iway Storage Room "H2" next to Boy's	Yes	W2	Concrete	White	Cracking	3	0.08	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Inaccessible Partially	No	No	
1 2 Res	stroom across from Classroom 217	Yes	W3	Concrete	White	Chipping	3	0.04	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Inaccessible Partially	No	No	
1 2 Res	stroom across from Classroom 217	Yes	W4	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Inaccessible	No	No	
1 2 Res	way Storage Room "H2" next to Boy's stroom across from Classroom 217 Iway Storage Room "H2" next to Boy's stroom across from Classroom 217 Iway Storage Room "H2" next to Boy's	Yes	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	
1 2 Res	stroom across from Classroom 217	Yes	Floor	Concrete	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	
	's Restroom across from Classroom 217	Yes	W1	Ceramic Tile	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	Ceramic Tile - Not damaged, bu glazing is positive
1 2 Girl	I's Restroom across from Classroom 217 I's Restroom across from Classroom 217	Yes Yes	W2 W2	Ceramic Tile N/A	Tan N/A	None N/A	0 N/A	N/A N/A	N/A N/A	N/A Stall	N/A Metal	N/A Brown	N/A Chipping	N/A 4	N/A 4.5	N/A Positive	None	0	No	No	No	
1 2 Girl	's Restroom across from Classroom 217	Yes	W3	Ceramic Tile	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	

									Lead S	hool Dist Safe Certifi	cation As	sessmer	nt Report									
<u> </u>	Name of Inspector: Ryan Hutsel	-	_						F.	S. Edmon	ds Eleme	ntary Scl	hool					Inspection F	Dates: 06/11- 06/	15/2019		
	Inspection Company: Synertech		1	T			I	T	1	I	1		1				1	ULCS# 6210	1	10/2010	1	
E I M I e o n o t r	On-Site Room Name	Student Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)	Additional Component	Substrate Material	Color	Description of Paint and Plaster Damage	Additional Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Additional Component XRF (positive/ negative)	Debris Present (describe location)	Quantity (sf)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Comments/ Description/ Notes
1 2 1 2	Girl's Restroom across from Classroom 217 Girl's Restroom across from Classroom 217	Yes Yes	W4 Ceiling	Ceramic Tile Concrete	Tan White	None Cracking	2	N/A 0	N/A Negative	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	None None	0	No No	No No	No	
1 2	Girl's Restroom across from Classroom 217 IMC (Library)	Yes Yes	Floor W1	Ceramic Tile Concrete	Tan White	None Cracking	2	N/A 0.04	N/A Negative	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	None None	0	No Prior to Repair	No	No	
1 2	IMC (Library) IMC (Library) IMC (Library)	Yes Yes	W1 W1	Plaster N/A	White N/A	Cracking N/A	2 N/A	0 N/A	Negative N/A	N/A Pipe Riser	N/A Metal	N/A Blue	N/A None	N/A	N/A N/A	N/A N/A	None N/A	0 N/A	Prior to Repair Prior to Repair	No	No	
1 2	IMC (Library)	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	Yellow	None	0	N/A	N/A	N/A	N/A	Prior to Repair	No	No	No Wall
1 2	IMC (Library)	Yes Yes	W2 W3	N/A Concrete	N/A Yellow	N/A Cracking	N/A 2	N/A 0.02	N/A Negative	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	None None	0	Prior to Repair Prior to Repair	No No	No No	No Wall
1 2	IMC (Library) IMC (Library)	Yes Yes	W3 W4	N/A Concrete	N/A Blue	N/A None	N/A 0	N/A N/A	N/A N/A	Radiator Cover N/A	Metal N/A	Yellow N/A	Chipping N/A	2 N/A	0.54 N/A	Negative N/A	None None	0	Prior to Repair No	No	No	
1 2	IMC (Library)	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	Yellow	Chipping	1	0.27	Negative	None	0	No Partially	No	No	
1 2	IMC (Library)	Yes	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Inaccessible	No	No	Suspended Ceiling
1 2	IMC (Library)	Yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Partially Inaccessible	No	No	Carpet
1 2	IMC (Library) IMC (Library)	Yes Yes	W1 W1	Concrete Plaster	Blue White	Cracking Cracking	2	0.04	Negative Negative	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	None None	0	Prior to Repair Prior to Repair	No No	No	
1 2 1 2	IMC (Library)	Yes	W1 W2	N/A Concrete	N/A Yellow/Purple	N/A None	N/A	N/A N/A	N/A N/A	Door Frame N/A	Metal N/A	Yellow N/A	Chipping N/A	1 N/A	0.2 N/A	Negative N/A	None None	0	Prior to Repair Prior to Repair	No No	No	
1 2	IMC (Library)	Yes	W2 W3 W3	Concrete	Blue N/A	Cracking	3 N/A	0.02 N/A	Negative N/A	N/A N/A Radiator Cover	N/A N/A Metal	N/A Yellow	N/A	N/A	N/A N/A 0.54	N/A	None	0	Prior to Repair	No	No	
1 2	IMC (Library) IMC (Library) IMC (Library)	Yes Yes	W4	N/A	N/A N/A N/A	N/A N/A N/A		N/A	N/A	N/A	N/A	N/A	Chipping N/A	2 N/A	N/A	Negative N/A	None	0	Prior to Repair Prior to Repair	No	No	No Wall
1 2 1 2	IMC (Library) IMC (Library)	Yes	Ceiling Floor	N/A N/A	N/A N/A	N/A N/A	N/A N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	None None	0	No No	No No	No No	Suspended Ceiling Carpet
1 2	Storage in Hallway across from Classroom 213 (2 over from IMC)	Yes	W1	No Access	No Access	No Access	No Access	No Access	No Access	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Prior to Repair	No	No	
1 2	Storage in Hallway across from Classroom 213 (2 over from IMC)	Yes	W2	No Access	No Access	No Access	No Access	No Access	No Access	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Prior to Repair	No	No	
1 2	Storage in Hallway across from Classroom 213 (2 over from IMC)	Yes	W3	No Access	No Access	No Access	No Access	No Access	No Access	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Prior to Repair	No	No	
1 2	Storage in Hallway across from Classroom 213 (2 over from IMC)	Yes	W4	No Access	No Access	No Access	No Access	No Access	No Access	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Prior to Repair	No	No	
1 2	Storage in Hallway across from Classroom 213 (2 over from IMC)	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	
1 2	Storage in Hallway across from Classroom 213 (2 over from IMC)	Yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	
1 2							NO ACCESS					1						-	Partially		NO	
1 2	Storage in Hallway at IMC (Back Room)	Yes	W1	Concrete	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Inaccessible Partially	No	No	
1 2	Storage in Hallway at IMC (Back Room)	Yes	W2	Concrete	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Inaccessible Partially	No	No	
1 2	Storage in Hallway at IMC (Back Room)	Yes	W3	Concrete	Tan	Chipping	5	0.02	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Inaccessible Partially	No	No	
1 2	Storage in Hallway at IMC (Back Room) Storage in Hallway at IMC (Back Room)	Yes Yes	W4	Concrete Concrete	Tan White	Chipping None	4	0.02 N/A	Negative N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	None None	0	Inaccessible	No No	No No	
1 2	Storage in Hallway at IMC (Back Room)	Yes	Ceiling Floor	Concrete	Tan	None	0	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	None	0	No	No	No	
1 2	Storage in Hallway across from Classroom 213 (next to IMC)	Yes	W1	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Partially Inaccessible	No	No	
1 2	Storage in Hallway across from Classroom 213 (next to IMC)	Yes	W2	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	ō	Partially Inaccessible	No	No	
1 2	Storage in Hallway across from Classroom 213 (next to IMC)	Yes	W3	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Partially Inaccessible	No	No	
1 2	Storage in Hallway across from Classroom 213 (next to IMC)	Yes	W4	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Partially Inaccessible	No	No	
1 2	Storage in Hallway across from Classroom 213	Yes	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	
1 2	(next to IMC) Storage in Hallway across from Classroom 213						-											0				
1 2	(next to IMC) Storage between to Restrooms across from	Yes	Floor	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	U	No Partially	No	No	
1 2	Classroom 217 Storage between to Restrooms across from	Yes	W1	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Inaccessible Partially	No	No	
1 2	Classroom 217 Storage between to Restrooms across from	Yes	W2	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Inaccessible Partially	No	No	
1 2	Classroom 217 Storage between to Restrooms across from	Yes	W3	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Inaccessible Partially	No	No	
1 2	Classroom 217 Storage between to Restrooms across from	Yes	W4	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Inaccessible	No	No	
1 2	Classroom 217	Yes	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	ļ
1 2	Storage between to Restrooms across from Classroom 217	Yes	Floor	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	
1 2	Classroom 218 Classroom 218	Yes	W1 W1	Concrete N/A	Tan N/A	Cracking N/A	10 N/A	0.02 N/A	Negative N/A	N/A Door Frame	N/A Metal	N/A White	N/A Chipping	N/A 2	N/A 0.3	N/A Negative	None None	0	Prior to Repair Prior to Repair	No No	No No	
1 2 1 2		Yes Yes	W2 W3	Concrete Concrete	Tan Tan	Cracking Cracking	2	0	Negative Negative	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	None None	0	Prior to Repair Prior to Repair	No No	No No	
1 2	Classroom 218	Yes	W3 W4	N/A	N/A Tan	N/A	N/A	N/A 0.04	N/A	Radiator Cover N/A	Metal N/A	White N/A	Chipping	1 N/A	0.7 N/A	Positive N/A	None	0	Prior to Repair	No No	No	
1 2	Classroom 218 Classroom 218	Yes	Ceiling	Concrete Concrete	White	Efflorescence Efflorescence	15	0.04	Negative Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Prior to Repair No	Roof leak	No	Additional Cracking
1 2	Classroom 218 Classroom 219	Yes Yes	Floor W1	Concrete Concrete	N/A Tan	None Flaking	0 60	N/A 0.02	N/A Negative	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	None None	0	No Prior to Repair	No No	No No	Floor Tile
1 2	Classroom 219 Classroom 219 Classroom 219	Yes	W2 W3	Concrete Concrete	Tan Tan	Cracking Cracking	20	0.02	Negative Negative	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	None	0	Prior to Repair Prior to Repair	No	No	
1 2	Classroom 219	Yes	W4	Concrete	Tan	Cracking	10	0.06	Negative	N/A	N/A	N/A	N/A N/A N/A	N/A N/A N/A	N/A	N/A	None	0	Prior to Repair	No	No	
	Classroom 219 Classroom 219	Yes Yes	Ceiling Floor	Concrete Concrete	White N/A	Efflorescence None	25 0	0.02 N/A	Negative N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	None None	0	No No	Roof leak No	No No	Floor Tile
1 2	Storage next to Classroom 219	Yes	W1	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Partially Inaccessible	No	No	
1 2	Storage next to Classroom 219	Yes	W2	Concrete	White	Cracking	3	0.02	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Partially Inaccessible	No	No	
1 2	Storage next to Classroom 219	Yes	W3	Concrete	White	Cracking	5	0.02	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Partially Inaccessible	No	No	
			W4		White		6	0.02		NIA			1007	1071	N/A				Partially	Ne	Ne	
1 2	Storage next to Classroom 219 Storage next to Classroom 219 Storage next to Classroom 219	Yes	Ceiling	Concrete Concrete	White	Cracking None	6	N/A	Negative N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A	N/A N/A	None None	0	Inaccessible No	NO	No	
1 2	Storage next to Classroom 219 Right Storage Room in Hallway across from Classroom 211	Yes	Floor	Concrete	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	
1 2	Liassroom 211	Yes	W1	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	

										hool Dist												
										Safe Certifi												
	Name of Inspector: Ryan Hutse	11							F.	S. Edmon	as Eleme	ntary Sc	1001					Inspection [Dates: 06/11- 06/	15/2019		
	Inspection Company: Synertech			-			-				-	-			_	-		ULCS# 6210		15/2019		
E I e m e n	F 0	Student Teacher Occupied	Primary	Substrate		Description of Primary	Primary Component Damage	XRF Reading	Primary Component XRF (positive/	Additional	Substrate		Description of Paint and Plaster	Additional Component Damage	XRF Reading	Additional Component XRF (positive/	Debris Present (describe		Contents Need to	On-going Moisture	Plastering Needed (yes or	
t	r On-Site Room Name Right Storage Room in Hallway across from	(yes/no)	Component	Material	Color	Damage	Quantity (sf)	(mg/cm2)	negative)	Component	Material	Color	Damage	Quantity (sf)	(mg/cm2)	negative)	location)	Quantity (sf)	be Moved	Intrusion	no)	Comments/ Description/ Notes
1	2 Classroom 211 Right Storage Room in Hallway across from 2 Classroom 211	Yes	W2	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	
1	2 Classroom 211 Right Storage Room in Hallway across from	Yes	W3	Concrete	White	Cracking	4	0.02	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	
1	2 Classroom 211 Right Storage Room in Hallway across from	Yes	W4	Concrete	White	Cracking	2	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	
1	2 Classroom 211 Right Storage Room in Hallway across from	Yes	Ceiling	Concrete	White	Cracking	2	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	
1	2 Classroom 211	Yes	Floor	Concrete	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	
1	2 Left Storage Room in Hallway across from 2 Classroom 211 Left Storage Room in Hallway across from	Yes	W1	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	
1	2 Classroom 211	Yes	W2	Concrete	White	Cracking	3	0.04	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	
1	Left Storage Room in Hallway across from 2 Classroom 211	Yes	W3	Concrete	White	Cracking	1	0.09	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	
1	Left Storage Room in Hallway across from 2 Classroom 211	Yes	W4	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	
1	Left Storage Room in Hallway across from 2 Classroom 211	Yes	Ceiling	Concrete	White	Cracking	2	0.02	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	
1	Left Storage Room in Hallway across from Classroom 211	Yes	Floor	Concrete	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	
	2 Classroom 211 Storage in Hallway around Corner from 2 Classroom 213 (2nd Room in)	Yes	W1	No Access	No Access	No Access	No Access	No Access	No Access	N/A	N/A	N/A	N/A	N/A N/A	N/A	N/A	None	0	No	No	No	
	Storage in Hallway around Corner from										í í	i i						-				
1	2 Classroom 213 (2nd Room in) Storage in Hallway around Corner from	Yes	W2	No Access	No Access	No Access	No Access	No Access	No Access	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	
1	2 IClassroom 213 (2nd Room in)	Yes	W3	No Access	No Access	No Access	No Access	No Access	No Access	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	
1	Storage in Hallway around Corner from Classroom 213 (2nd Room in) Storage in Hallway around Corner from	Yes	W4	No Access	No Access	No Access	No Access	No Access	No Access	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	
1	2 Classroom 213 (2nd Room in) Storage in Hallway around Corner from	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	
1	2 Classroom 213 (2nd Room in) Storage in Hallway around Corner from	Yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	
1	2 Classroom 213 (Corner Room)	Yes	W1	No Access	No Access	No Access	No Access	No Access	No Access	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	
1	2 Classroom 213 (Corner Room) Storage in Hallway around Corner from	Yes	W2	No Access	No Access	No Access	No Access	No Access	No Access	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	
1	2 Classroom 213 (Corner Room)	Yes	W3	No Access	No Access	No Access	No Access	No Access	No Access	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	
1	2 Storage in Hallway around Corner from 2 Classroom 213 (Corner Room)	Yes	W4	No Access	No Access	No Access	No Access	No Access	No Access	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	
1	Storage in Hallway around Corner from 2 Classroom 213 (Corner Room)	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	
1	Storage in Hallway around Corner from 2 Classroom 213 (Corner Room)	Yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	
1	Gym Fan Room next to Stairwell adjacent to 2 Classroom 213	Yes	W1	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	
	Gym Fan Room next to Stairwell adjacent to Classroom 213	Yes	W2	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	
	Gym Fan Room next to Stairwell adjacent to						0	N/A N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A		0	No	No	NO	
1	2 Classroom 213 Gym Fan Room next to Stairwell adjacent to	Yes		Concrete	White	None				10/1				iii/A			None		110		No	
1	2 Classroom 213 Gym Fan Room next to Stairwell adjacent to	Yes	W4	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	
1	2 Classroom 213 Gym Fan Room next to Stairwell adjacent to	Yes	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	
1	2 Classroom 213 2 Fan Room in Hallway next to Gym Fan Room	Yes No	Floor W1	Concrete Concrete	Grey White	None None	0	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	None None	0	No No	No No	No	
1	2 Fan Room in Hallway next to Gym Fan Room	No	W2	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A N/A	None	0	No	No	No	
	2 Fan Room in Hallway next to Gym Fan Room 2 Fan Room in Hallway next to Gym Fan Room	No	W3 W4	Concrete Concrete	White White	None None	0	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	None None	0	No No	No No	No	
1	2 Fan Room in Hallway next to Gym Fan Room	No	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	
1	2 Fan Room in Hallway next to Gym Fan Room	No	Floor	Concrete N/A	Grey N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	
1	Stairwell between Classrooms 102 & 104 Stairwell between Classrooms 102 & 104	Yes	Floor	N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	Stair stringer Stair riser	Metal Metal	Brown Brown	Chipping Chipping	12	5.1	Positive Positive	None	0	No	No	No	
1	1 Stairwell between Classrooms 102 & 104	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	Newel posts	Metal	Brown	Chipping	2	4.5	Positive	None	0	No	No	No	
1	1 Stairwell between Classrooms 102 & 104	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	Stair Spindles	Metal	Brown	Chipping	14	3.9	Positive	None	0	No	No	No	Ceramic Tile - Not damaged, but
1	2 Stairwell next to Classroom 213	Yes	W1	Ceramic Tile	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	glazing is positive
1	2 Stairwell next to Classroom 213	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door	Metal	Brown	Chipping	1	0.3	Negative	None	0	No	No	No	Ceramic Tile - Not damaged, but glazing is positive
1	2 Stairwell next to Classroom 213	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	Brown	Chipping	3	4.5	Positive	None	0	No	No	No	Ceramic Tile - Not damaged, but glazing is positive
	2 Stairwell next to Classroom 213	Yes	W2	Ceramic Tile	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	Õ	No	No	No	
	2 Stairwell next to Classroom 213	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A	Radiator Cover	Metal	Brown	Chipping	2	2.8	Positive	None	0	No	No	No	
	2 Stairwell next to Classroom 213 2 Stairwell next to Classroom 213	Yes	W2 W3	N/A Ceramic Tile	N/A Tan	N/A None	N/A	N/A N/A	N/A N/A	Hand Rail N/A	Metal N/A	Brown N/A	Chipping N/A	2 N/A	5.2 N/A	Positive N/A	None		No No	No No	No	
	2 Stairwell next to Classroom 213 2 Stairwell next to Classroom 213	Yes	W3 W3	N/A	N/A	None N/A	N/A	N/A N/A	N/A N/A	Door	Metal	Brown	Chipping	2	2.5	N/A Negative	None	0	No	NO	No	
1	2 Stairwell next to Classroom 213	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	Brown	Chipping	2	2.8	Positive	None	Ö	No	No	No	
	2 Stairwell next to Classroom 213	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A	Cage	Metal	Brown	Chipping N/A	12	6	Positive	None	0	No	No	No	Chain link access to attic
1	2 Stairwell next to Classroom 213 2 Stairwell next to Classroom 213	Yes Yes	W4 W4	Ceramic Tile N/A	Tan N/A	None N/A	0 N/A	N/A N/A	N/A N/A	N/A Radiator Cover	N/A Metal	N/A Brown	N/A Chipping	N/A 2	N/A 2.1	N/A Positive	None	0	No	No	No	
1	2 Stairwell next to Classroom 213	Yes	W4	N/A	N/A	N/A N/A	N/A	N/A N/A	N/A	Hand Rail	Metal	Brown	Chipping	ĩ	4.2	Positive	None	ŏ	No	No	No	
	2 Stairwell next to Classroom 213	Yes	Ceiling	Metal	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	
	2 Stairwell next to Classroom 213 2 Stairwell next to Classroom 213	Yes	Floor	Concrete N/A	Grey N/A	None N/A	0 N/A	N/A N/A	N/A N/A	N/A Stair stringer	N/A Metal	N/A Brown	N/A Chipping	N/A 11	N/A 4.6	N/A Positive	None	0	No	No	No	
1	2 Stairwell next to Classroom 213 2 Stairwell next to Classroom 213	Yes	Floor	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	Stair stringer Stair riser	Metal	Brown	Chipping Chipping	10	4.6	Positive	None	0	No	NO	No	
1	2 Stairwell next to Classroom 213	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	Newel posts	Metal	Brown	Chipping	4	4.4	Positive	None	0	No	No	No	
1	2 Stairwell next to Classroom 213	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	Stair Spindles	Metal	Brown	Chipping	8	4	Positive	None	0	No	No	No	Ceramic Tile - Not damaged, but
1	2 Stairwell next to Classroom 218	Yes	W1	Ceramic Tile	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	glazing is positive
1	2 Stairwell next to Classroom 218	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door	Metal	Brown	Chipping	2	2.5	Negative	None	0	No	No	No	Ceramic Tile - Not damaged, but glazing is positive
1	2 Stairwell next to Classroom 218	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	Brown	Chipping	2	21	Positive	None	0	No	No	No	Ceramic Tile - Not damaged, but glazing is positive
1	2 Stairwell next to Classroom 218 2 Stairwell next to Classroom 218 2 Stairwell next to Classroom 218	Yes	W2	Ceramic Tile	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	giozing is positive
1		Yes	W2	N/A N/A	N/A N/A	N/A N/A	N/A	N/A N/A	N/A N/A	Radiator Cover	Metal	Brown	Chipping	2	2.8	Positive Positive	None None	0	No	No	No No	
	2 Stairwell next to Classroom 218	Yes	W2				N/A			Hand Rail	Metal	Brown	Chipping						No	No No		

										hool Dist												
										Safe Certifi												
									F.	S. Edmon	ds Eleme	entary Sc	hool							1 = 100 10		
	Name of Inspector: Ryan Hutsell Inspection Company: Synertech		+															ULCS# 6210	Dates: 06/11- 06/	15/2019		
E I F T I O O		Student Teacher Occupied	Primary	Substrate		Description of Primary	Primary Component Damage	XRF Reading	Primary Component XRF (positive/	Additional	Substrate		Description of Paint and Plaster	Additional Component Damage	XRF Reading	Additional Component XRF (positive/	Debris Present (describe	0200# 0210	Contents Need to	On-going Moisture	Plastering Needed (yes or	
t r	On-Site Room Name	(yes/no)	Component	Material	Color	Damage	Quantity (sf)	(mg/cm2)	negative)	Component	Material	Color	Damage	Quantity (sf)	(mg/cm2)	negative)	location)	Quantity (sf)	be Moved	Intrusion	no)	Comments/ Description/ Notes
1 2	Stairwell next to Classroom 218 Stairwell next to Classroom 218	Yes	W3 W3	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	Door Door Frame	Metal	Brown Brown	Chipping Chipping	2	3.1	Negative Positive	None	0	No	No No	No	
	Stairwell next to Classroom 218	Yes	W4	Ceramic Tile	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	
1 2 1 2	Stairwell next to Classroom 218 Stairwell next to Classroom 218	Yes	W4 W4	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	Radiator Cover Hand Rail	Metal Metal	Brown Brown	Chipping Chipping	3	2.4	Positive Positive	None None	0	No No	No No	No	
1 2	Stairwell next to Classroom 218	Yes	Ceiling	Metal	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	
1 2	Stairwell next to Classroom 218	Yes	Floor	Concrete	Grey	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	
1 2	Stairwell next to Classroom 218	Yes	Floor	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	Stair stringer Stair riser	Metal	Brown Brown	Chipping	10	4.6	Positive Positive	None	0	No	No	No	
	Stairwell next to Classroom 218	Yes	Floor	N/A N/A	N/A N/A	N/A	N/A N/A	N/A N/A	N/A N/A	Newel posts	Metal	Brown	Chipping Chipping	3	4.5	Positive	None	0	No	No	No	
1 2	Stairwell next to Classroom 218	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	Stair Spindles	Metal	Brown	Chipping	10	3.7	Positive	None	0	No	No	No	
1 2	Stairwell next to Classroom 210	Yes	W1	Ceramic Tile	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	Ceramic Tile - Not damaged, but glazing is positive Ceramic Tile - Not damaged, but
1 2	Stairwell next to Classroom 210	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door	Metal	Brown	Chipping	1	3.7	Negative	None	0	No	No	No	glazing is positive Ceramic Tile - Not damaged, but
1 2	Stairwell next to Classroom 210 Stairwell next to Classroom 210	Yes	W1 W2	N/A Ceramic Tile	N/A Tan	N/A None	N/A 0	N/A N/A	N/A N/A	Door Frame N/A	Metal N/A	Brown N/A	Chipping N/A	1 N/A	3.5 N/A	Positive N/A	None None	0	No	No No	No	glazing is positive
1 2	Stairwell next to Classroom 210	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A	Radiator Cover	Metal	Brown	Chipping	2	2.2	Positive	None	ŏ	No	No	No	
	Stairwell next to Classroom 210	Yes	W2	N/A Caregoria Tila	N/A	N/A	N/A	N/A	N/A	Hand Rail	Metal	Brown	Chipping	1	4.3	Positive	None	0	No	No	No	
1 2 1 2	Stairwell next to Classroom 210 Stairwell next to Classroom 210	Yes Yes	W3 W3	Ceramic Tile N/A	Tan N/A	None N/A	0 N/A	N/A N/A	N/A N/A	N/A Door	N/A Metal	N/A Brown	N/A Chipping	N/A 3	N/A 1.9	N/A Negative	None	0	No	No	No	+
1 2	Stairwell next to Classroom 210	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	Brown	Chipping	2	2.5	Positive	None	ŏ	No	No	No	
1 2	Stairwell next to Classroom 210	Yes	W4	Ceramic Tile N/A	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	
1 2	Stairwell next to Classroom 210 Stairwell next to Classroom 210	Yes	W4 W4	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	Radiator Cover Hand Rail	Metal	Brown Brown	Chipping	3	2.9	Positive	None	0	No	No	No	
1 2		Yes	Ceiling	Metal	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	
1 2	Stairwell next to Classroom 210	Yes	Floor	Concrete	Grey	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	
	Stairwell next to Classroom 210 Stairwell next to Classroom 210	Yes	Floor Floor	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	Stair stringer Stair riser	Metal Metal	Brown Brown	Chipping Chipping	8	5.4	Positive Positive	None None	0	No No	No	No	
1 2	Stairwell next to Classroom 210	Yes	Floor	N/A N/A	N/A N/A	N/A	N/A	N/A	N/A	Newel posts	Metal	Brown	Chipping	2	3.9	Positive	None	0	No	No	No	
1 2	Stairwell next to Classroom 210	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	Stair Spindles	Metal	Brown	Chipping	8	4.2	Positive	None	0	No	No	No	
1 2	Stairwell between Classrooms 202 & 204	Yes	W1	Ceramic Tile	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	Ceramic Tile - Not damaged, but glazing is positive Ceramic Tile - Not damaged, but
1 2	Stairwell between Classrooms 202 & 204	Yes	W1	N/A N/A	N/A	N/A N/A	N/A	N/A N/A	N/A N/A	Door Door Frame	Metal	Brown	Chipping	2	3.1	Negative	None	0	No	No	No	glazing is positive Ceramic Tile - Not damaged, but
1 2	Stairwell between Classrooms 202 & 204 Stairwell between Classrooms 202 & 204	Yes	W1 W2	N/A Ceramic Tile	Tan	N/A	0 N/A	N/A N/A	N/A N/A	N/A	N/A	N/A	Chipping N/A	N/A	2.6 N/A	N/A	None	0	NO	No	No	glazing is positive
1 2	Stairwell between Classrooms 202 & 204	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A	Radiator Cover	Metal	Brown	Chipping	1	1	Positive	None	0	No	No	No	
1 2	Stairwell between Classrooms 202 & 204	Yes	W2 W3	N/A Ceramic Tile	N/A Tan	N/A None	N/A	N/A N/A	N/A N/A	Hand Rail N/A	Metal N/A	Brown N/A	Chipping N/A	2 N/A	3.9 N/A	Positive N/A	None	0	No	No	No	
	Stairwell between Classrooms 202 & 204 Stairwell between Classrooms 202 & 204	Yes	W3 W3	N/A	N/A	None N/A	N/A	N/A N/A	N/A N/A	Door	N/A Metal	Brown	Chipping	N/A 2	1.9	N/A Negative	None	0	NO	No	NO	
1 2	Stairwell between Classrooms 202 & 204	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	Brown	Chipping	2	2.6	Positive	None	0	No	No	No	
1 2	Stairwell between Classrooms 202 & 204	Yes	W4	Ceramic Tile	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	
1 2	Stairwell between Classrooms 202 & 204 Stairwell between Classrooms 202 & 204	Yes	W4 W4	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	Radiator Cover Hand Rail	Metal Metal	Brown Brown	Chipping	2	2.6	Positive	None None	0	No	No No	No	+
1 2	Stairwell between Classrooms 202 & 204	Yes	Ceiling	Metal	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	ő	No	No	No	
1 2	Stairwell between Classrooms 202 & 204	Yes	Floor	Concrete	Grey	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	
1 2	Stairwell between Classrooms 202 & 204 Stairwell between Classrooms 202 & 204	Yes	Floor Floor	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	Stair stringer Stair riser	Metal Metal	Brown Brown	Chipping Chipping	8	4.5	Positive Positive	None	0	No	No	No	
1 2	Stairwell between Classrooms 202 & 204	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	Newel posts	Metal	Brown	Chipping	2	4.8	Positive	None	ŏ	No	No	No	
1 2	Stairwell between Classrooms 202 & 204 3rd Floor Room up Stairwell next to Classroom 213	Yes	Floor W1	N/A No Access	N/A N/A	N/A N/A	N/A	N/A N/A	N/A	Stair Spindles	Metal N/A	Brown N/A	Chipping N/A	12 N/A	4.1 N/A	Positive N/A	None N/A	0 N/A	No N/A	No N/A	No N/A	No key at time of inspection
1 3	3rd Floor Room up Stairwell next to Classroom 213	No	W2	No Access	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	the ney de unie of maplettion
1 3	3rd Floor Room up Stairwell next to Classroom 213 3rd Floor Room up Stairwell next to Classroom	No	W3	No Access	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1 3	213 3rd Floor Room up Stairwell next to Classroom 213	No	W4 Ceiling	No Access	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A	N/A N/A	N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	
1 3	3rd Floor Room up Stairwell next to Classroom 213	No	Floor	No Access	N/A N/A	N/A N/A	N/A	N/A N/A	N/A	N/A N/A	N/A	N/A	N/A	N/A N/A	N/A N/A	N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	
1 2	Hallway from Classrooms 213-211	Yes	W1	Concrete	White	Flaking	20	0.02	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	Current Classroom Modification Project Ongoing Current Classroom Modification
1 2	Hallway from Classrooms 213-211	Yes	W2	Concrete	White	Chipping	12	0.04	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	Project Ongoing Current Classroom Modification
1 2	Hallway from Classrooms 213-211 Hallway from Classrooms 213-211	Yes	W2 W3	N/A Concrete	N/A White	N/A None	N/A 0	N/A N/A	N/A N/A	Door Frame N/A	Metal N/A	White N/A	Chipping N/A	3 N/A	0.35 N/A	Negative N/A	None	0	No	No	No	Project Ongoing Current Classroom Modification Project Ongoing
1 2	Hallway from Classrooms 213-211	Yes	W4	Concrete	White	Chipping	15	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	Current Classroom Modification Project Ongoing
1 2	Hallway from Classrooms 213-211	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	White	Chipping	4	0.3	Negative	None	0	No	No	No	Current Classroom Modification Project Ongoing Current Classroom Modification
1 2	Hallway from Classrooms 213-211	Yes	Ceiling	Concrete	White	Flaking	45	0.02	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	Roof leak	No	Project Ongoing Current Classroom Modification
1 2	Hallway from Classrooms 213-211	Yes	Floor	Concrete	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	No	Project Ongoing