

Rudolph Blankenburg Lead Safe Certification Assessment Report

School District of Philadelphia																									
Lead Safe Certification Assessment Report																									
Rudolph Blankenburg Elementary School																									
Name of Inspectors: Ananth K. Vinjamuri, Melissa Billingsley															Inspection Dates: 6/17 - 24/2019										
Inspection Company: Criterion Labs, Inc.															ULCS# 1490										
Elementary	Floor	Room	On-Site Room Name	Student/Teacher Occupied (Yes/No)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sq ft)	XRF Reading (ppm)	Primary Component XRF (positive/negative)	Additional Contaminant	Substrate Material	Color	Description of Paint and Plaster Damage	Additional Component Damage Quantity (sq ft)	XRF Reading (ppm)	Additional Component XRF (positive/negative)	Leads Present (describe location)	Quantity (sq ft)	Contents Need to be Moved	On-going Moisture	Plastering Needed (yes/no)	Comments/Description/Notes	
1	1	1	Classroom 103	yes	W3	Plaster	Blue	Chipping	2	17.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	1	Classroom 103	yes	W3	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	1	Classroom 103	yes	W3	Plaster	Tan	Chipping/Cracking	5	24.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	1	Classroom 103	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A	Columns	Plaster	Tan	Cracking/Flaking	5	33.7	Positive	N/A	None	0	No	No	no	Tan is bottom. Top is white
1	1	1	Classroom 103	yes	W4	Plaster	Tan	Chipping	1	31.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	1	Classroom 103	yes	W4	Plaster	White	Efflorescence	10	39.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	Unknown
1	1	1	Classroom 103	yes	Floor	Wood	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	Damage is near windows
1	1	1	Classroom 103 Closet	yes	W1	Plaster	White	Partially Inaccessible/Chipping	2	37.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	1	Classroom 103 Closet	yes	W2	Plaster	White	Partially Inaccessible	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	1	Classroom 103 Closet	yes	W3	Plaster	White	Partially Inaccessible/Chipping	5	17.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	1	Classroom 103 Closet	yes	W4	Plaster	White	Partially Inaccessible/Chipping/Flaking	3	33.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	1	Classroom 103 Closet	yes	Ceiling	Plaster	White	Chipping/Cracking	5	29.3	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	1	Classroom 103 Closet	yes	Floor	Wood	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	1	Classroom 103	yes	W1	Plaster	Blue	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	1	Classroom 102	yes	W2	Plaster	Blue	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	1	Classroom 102	yes	W3	Plaster	Blue	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	1	Classroom 102	yes	W4	Plaster	Blue	Efflorescence/Chipping	5	22.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	1	Classroom 102	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A	Columns	Plaster	Blue	Chipping	3	17.9	Positive	N/A	None	0	No	No	no	
1	1	1	Classroom 102	yes	W4	Plaster	Blue	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	1	Classroom 102	yes	Ceiling	Plaster	White	Chipping	3	33.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	Damage is near windows
1	1	1	Classroom 102	yes	Floor	Wood	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	1	Classroom 101	yes	W1	Plaster	Blue	Chipping	5	17.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	1	Classroom 101	yes	W2	Plaster	Blue	Chipping	3	21.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	1	Classroom 101	yes	W3	Plaster	Blue	Chipping	6	16.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	1	Classroom 101	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A	Columns	Plaster	Blue	Chipping	5	12.3	Positive	N/A	None	0	No	No	no	
1	1	1	Classroom 101	yes	W1	Plaster	Blue	Chipping	2	16.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	1	Classroom 101	yes	Ceiling	Plaster	White	Chipping	5	25.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	1	Classroom 101	yes	Floor	Wood	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	1	Classroom 101 Closet	yes	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Door has a padlock on it
1	1	1	Classroom 101 Closet	yes	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Door has a padlock on it
1	1	1	Classroom 101 Closet	yes	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Door has a padlock on it
1	1	1	Classroom 101 Closet	yes	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Door has a padlock on it
1	1	1	Classroom 101 Closet	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Door has a padlock on it
1	1	1	Classroom 101 Closet	yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Door has a padlock on it
1	1	1	Classroom 101 Restroom	yes	W1	Plaster	Blue	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	Bottom
1	1	1	Classroom 101 Restroom	yes	W2	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	1	Classroom 101 Restroom	yes	W3	Plaster	Blue	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	1	Classroom 101 Restroom	yes	W4	Plaster	White	Cracking	5	15.3	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	1	Classroom 101 Restroom	yes	W1	Plaster	Blue	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	1	Classroom 101 Restroom	yes	W2	Plaster	Blue	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	1	Classroom 101 Restroom	yes	W3	Plaster	White	Cracking	3	17.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	Unknown
1	1	1	Classroom 101 Restroom	yes	W4	Plaster	White	Cracking	5	15.3	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	1	Classroom 101 Restroom	yes	Floor	Concrete	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	1	Classroom 101 Restroom	yes	W1	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	Unpainted concrete
1	1	1	Classroom 101 Restroom	yes	W2	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	1	Classroom 101 Restroom	yes	W3	Plaster	White	Efflorescence	10	12.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	At windows
1	1	1	Classroom 101 Restroom	yes	W4	Plaster	White	Cracking	10	13.3	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	Unknown
1	1	1	Classroom 101 Restroom	yes	Ceiling	Plaster	White	Efflorescence	5	20.3	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	Unknown
1	1	1	Classroom 101 Restroom	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	12x12 tile
1	1	1	Fire Tower Hallway adjacent to Hallway from Classrooms 101 to 103	yes	W1	Brick	White	Cracking	20	10.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	1	Fire Tower Hallway adjacent to Hallway from Classrooms 101 to 104	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	Baseboard	Concrete	Gray	Chipping	1	0.03	Negative	None	0	No	No	no	no	
1	1	1	Fire Tower Hallway adjacent to Hallway from Classrooms 101 to 103	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door	Metal	Brown	Chipping	2	0	Negative	None	0	No	No	no	no	
1	1	1	Fire Tower Hallway adjacent to Hallway from Classrooms 101 to 103	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	Brown	Chipping	2	0	Negative	None	0	No	No	no	no	
1	1	1	Fire Tower Hallway adjacent to Hallway from Classrooms 101 to 103	yes	W2	Brick	White	Cracking	20	17.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	1	Fire Tower Hallway adjacent to Hallway from Classrooms 101 to 103	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A	Baseboard	Concrete	Gray	Chipping	1	0.11	Negative	None	0	No	No	no	no	
1	1	1	Fire Tower Hallway adjacent to Hallway from Classrooms 101 to 103	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A	Window sill/Grate	Metal	Brown	Chipping	8	1.2	Positive	None	0	No	No	no	no	
1	1	1	Fire Tower Hallway adjacent to Hallway from Classrooms 101 to 103	yes	W2	Brick	White	Cracking	20	11.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	1	Fire Tower Hallway adjacent to Hallway from Classrooms 101 to 103	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A	Baseboard	Concrete	Gray	Chipping	1	0.03	Negative	None	0	No	No	no	no	
1	1	1	Fire Tower Hallway adjacent to Hallway from Classrooms 101 to 103	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A	Pipe	Metal	Gray	Cracking										

Rudolph Blankenburg Lead Safe Certification Assessment Report

School District of Philadelphia Lead Safe Certification Assessment Report Rudolph Blankenburg Elementary School

Name of Inspectors: Ananth K. Vinjamuri, Melissa Billingsley																				Inspection Dates: 6/17, 24/2019			
Inspection Company: Criterion Labs, Inc.																				ULCS# 1490			
Element	Floor	On-Site Room Name	Student/Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sq ft)	XRF Reading (ppm)	XRF (positive/negative)	Additional Component	Substrate Material	Color	Description of Paint and Plaster Damage	Additional Component Damage Quantity (sq ft)	XRF Reading (ppm)	Additional Component XRF (positive/negative)	Debris (describe location)	Quantity (sq ft)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Comments/Description/Notes
1	2	Nurse's Office	yes	W3	Plaster	Yellow	None	0	N/A	N/A	Baseboard	Wood	Brown	Flaking	N/A	N/A	N/A	None	0	No	No	no	
1	2	Nurse's Office	yes	W4	Plaster	White	Flaking	3	8.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	Appears to be have been repaired once
1	2	Nurse's Office	yes	W4	Plaster	Yellow	Flaking, Efflorescence	4	27.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	Unknown	yes	Appears to be have been repaired once
1	2	Nurse's Office	yes	W4	Plaster	White	Flaking	3	8.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	Unknown	yes	at drain pipe penetration
1	2	Nurse's Office	yes	W3	Plaster	Yellow	Efflorescence, Spalling	8	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	Unknown	yes	
1	2	Nurse's Restroom	yes	W1	Wood	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Nurse's Restroom	yes	W1	Plaster	Yellow	Flaking	16	34	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Nurse's Restroom	yes	W3	Plaster	Yellow	Flaking	4	27.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Nurse's Restroom	yes	W3	Plaster	Yellow	Flaking	3	27.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Nurse's Restroom	yes	W1	Plaster	Yellow	Cracking	2	37.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Nurse's Restroom	yes	W4	Plaster	Yellow	Cracking, Efflorescence	7	26.3	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	Unknown	yes	
1	2	Nurse's Restroom	yes	W3	Plaster	Yellow	Flaking	5	45.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	Unknown	yes	
1	2	Nurse's Restroom	yes	W1	Wood	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	Floor Tile
1	2	Starwell M (near Classroom 212)	yes	W1	Plaster	White/Grey	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Starwell M (near Classroom 212)	yes	W2	Plaster	White/Grey	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Starwell M (near Classroom 212)	yes	W4	Plaster	White	Damaged Plaster	6	37.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	Unknown	yes	
1	2	Starwell M (near Classroom 212)	yes	W4	Plaster	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Starwell M (near Classroom 212)	yes	W2	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Starwell M (near Classroom 212)	yes	W3	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	Unknown	yes	
1	2	Starwell M (near Classroom 212)	yes	W4	Plaster	Yellow	Cracking, damaged plaster	4	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Starwell M (near Classroom 212)	yes	W1	Plaster	White	None	0	N/A	N/A	Baseboard	Trim	Grey	Flaking	5	5.8	Positive	None	0	No	No	no	
1	2	Classroom 212	yes	W1	Plaster	White	Flaking	2	31.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Classroom 212	yes	W1	Plaster	White	Flaking	3	33.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Classroom 212	yes	W2	Plaster	White	Cracking, Spalling	8	33.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	Unknown	yes	Window sill
1	2	Classroom 212	yes	W2	Plaster	Yellow	Flaking	2	19.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Classroom 212	yes	W3	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Classroom 212	yes	W3	Plaster	Yellow	Flaking	3	17.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Classroom 212	yes	W4	Plaster	Blue	Flaking	2	30.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Classroom 212	yes	W2	Plaster	White	Efflorescence, Flaking	8	30.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	Unknown	yes	
1	2	Classroom 212	yes	W1	Wood	None	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Classroom 212 Closet	yes	W1	Plaster	White	Flaking, Damaged Plaster	10	23.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	Unknown	yes	
1	2	Classroom 212 Closet	yes	W1	Plaster	Yellow	Cracking, crack in plaster	10	23.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	Unknown	yes	
1	2	Classroom 212 Closet	yes	W2	Plaster	Yellow	Flaking, Cracking	55	34.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Classroom 212 Closet	yes	W2	Plaster	Yellow	Flaking, Cracking	24	30.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Classroom 212 Closet	yes	W4	Plaster	Yellow	Flaking	5	31	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Classroom 213 Closet	yes	W1	Plaster	White	Flaking	15	30.3	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	Unknown	yes	
1	2	Classroom 213 Closet	yes	W2	Plaster	Yellow	Flaking and damaged plaster	15	12.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	Unknown	yes	
1	2	Classroom 213 Closet	yes	W1	Wood	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Classroom 213	yes	W1	Plaster	White	Flaking	4	27.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Classroom 213	yes	W1	Plaster	Yellow	None	6	32.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Classroom 213	yes	W2	Wood	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Classroom 213	yes	W3	Plaster	White	Flaking	2	28.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Classroom 213	yes	W4	Plaster	Yellow	Flaking	60	29.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Classroom 213	yes	W2	Plaster	White	Cracking	2	32.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Classroom 213	yes	W4	Plaster	Yellow	Flaking	10	26	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Classroom 213	yes	W2	Plaster	White	Flaking	4	16.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Classroom 213	yes	W1	Wood	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Classroom 213 Closet	yes	W1	Plaster	White	Flaking	2	25.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Classroom 213 Closet	yes	W2	Plaster	White	Flaking	15	13.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Classroom 213 Closet	yes	W1	Plaster	White	Flaking	4	27.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Classroom 213 Closet	yes	W2	Plaster	Yellow	Flaking, Damaged Plaster	10	12.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	Unknown	yes	
1	2	Classroom 213 Closet	yes	W3	Plaster	White	Cracking	3	24.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Classroom 213 Closet	yes	W4	Plaster	Yellow	Cracking	3	14.3	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Classroom 213 Closet	yes	W4	Plaster	None	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Classroom 213 Closet	yes	W4	Plaster	Yellow	Cracking, Spalling	10	25.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Classroom 213 Closet	yes	W1	Wood	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Classroom 214	yes	W1	Plaster	White	Flaking	3	21.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Classroom 214	yes	W1	Plaster	Yellow	Chipping	2	33.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Classroom 214	yes	W2	Wood	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Classroom 214	yes	W3	Plaster	White	Chipping	3	30.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Classroom 214	yes	W3	Plaster	Yellow	Chipping	2	7.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Classroom 214	yes	W4	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Classroom 214	yes	W4	Plaster	White	Damaged plaster	3	11.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	Unknown	yes	
1	2	Classroom 214	yes	W1	Wood	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Classroom 214	yes	W1	Plaster	White	Cracking	4															

Rudolph Blankenburg Lead Safe Certification Assessment Report

School District of Philadelphia Lead Safe Certification Assessment Report Rudolph Blankenburg Elementary School

Name of Inspectors: Ananth K. Vinjamuri, Melissa Billingsley																				Inspection Dates: 6/17, 24/2019				
Inspection Company: Criterion Labs, Inc.																				ULCS# 1490				
Element	Room	On-Site Room Name	Student/Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sq ft)	XRF Reading (ppm)	Primary Component XRF (positive/negative)	Additional Component	Substrate Material	Color	Description of Paint and Plaster Damage	Additional Component Quantity (sq ft)	XRF Reading (ppm)	Additional Component XRF (positive/negative)	Leads Present (describe location)	Quantity (sq ft)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes/no)	Comments/Description/Notes	
1	2	Teacher's Kitchen (for Lounge)	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	No	Floor Tile
1	2	Classroom 210	yes	W2	Plaster	White	Flaking	10	23.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	No	
1	2	Classroom 210	yes	W1	Plaster	Yellow	Flaking	4	30.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	No	
1	2	Classroom 210	yes	W2	Plaster	White	Flaking	4	4.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	No	
1	2	Classroom 210	yes	W3	Plaster	Yellow	Flaking	12	4.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	No	
1	2	Classroom 210	yes	W3	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	No	
1	2	Classroom 210	yes	W4	Plaster	Brown	None	0	2.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	No	
1	2	Classroom 210	yes	Celling	Plaster	White	Flaking, Efflorescence	25	25.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	Unknown	yes	
1	2	Classroom 210	yes	Floor	Wood	Brown	None	8	21.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	No	
1	2	Classroom 210 Closet	yes	W1	Plaster	White	Cracking	6	2.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	No	Along coat hanger
1	2	Classroom 210 Closet	yes	W1	Plaster	White	Cracking	8	2.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	No	Along coat hanger
1	2	Classroom 210 Closet	yes	W2	Plaster	White	Cracking	12	26.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	No	Along coat hanger
1	2	Classroom 210 Closet	yes	W2	Plaster	Yellow	Cracking	4	3.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	No	Along coat hanger
1	2	Classroom 210 Closet	yes	W3	Plaster	Yellow	Flaking, Cracking	8	11.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	No	Along coat hanger
1	2	Classroom 210 Closet	yes	W4	Plaster	Yellow	Flaking, Cracking	12	29	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	No	Along coat hanger
1	2	Classroom 210 Closet	yes	W4	Plaster	Yellow	Flaking, Cracking	12	25.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	No	
1	2	Classroom 210 Closet	yes	Celling	Plaster	White	Flaking	30	17.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	No	
1	2	Classroom 210 Closet	yes	Floor	Wood	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	No	
1	2	Starwell G (near Classroom 211)	yes	W1	Plaster	White	Efflorescence	6	19.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	Unknown	yes	
1	2	Starwell G (near Classroom 211)	yes	W1	Plaster	Yellow	Friction	3	13.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	No	
1	2	Starwell G (near Classroom 211)	yes	W2	Plaster	White	Flaking	10	26.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	No	
1	2	Starwell G (near Classroom 211)	yes	W2	Plaster	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	No	
1	2	Starwell G (near Classroom 211)	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	No	
1	2	Starwell G (near Classroom 211)	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	No	
1	2	Starwell G (near Classroom 211)	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	No	
1	2	Starwell G (near Classroom 211)	yes	W4	Plaster	White	Cracking	8	34.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	No	
1	2	Starwell G (near Classroom 211)	yes	W4	Plaster	Yellow	Cracking	4	4.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	No	
1	2	Starwell G (near Classroom 211)	yes	Celling	Plaster	White	Efflorescence	2	2.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	Unknown	yes	
1	2	Starwell G (near Classroom 211)	yes	Floor	Concrete	Grey	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	No	
1	3	Women's Restroom (near Classroom 316)	yes	W1	Plaster	White/Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	No	
1	3	Women's Restroom (near Classroom 316)	yes	W2	Plaster	White/Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	No	
1	3	Women's Restroom (near Classroom 316)	yes	W3	Plaster	Yellow	Efflorescence, cracking	4	14.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	Unknown	yes	
1	3	Women's Restroom (near Classroom 316)	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	No	
1	3	Women's Restroom (near Classroom 316)	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	No	
1	3	Women's Restroom (near Classroom 316)	yes	W4	Plaster	White	Efflorescence	4	1.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	Unknown	yes	Repaired area but spalling/efflorescence again
1	3	Women's Restroom (near Classroom 316)	yes	W4	Plaster	Yellow	Efflorescence, Spalling	8	24.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	Unknown	yes	Repaired area but spalling/efflorescence again. This appears to be new damage. Other damage appears to have been repaired.
1	3	Women's Restroom (near Classroom 316)	yes	Celling	Plaster	White	Efflorescence	5	26.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	Unknown	yes	Repaired area but spalling/efflorescence again
1	3	Women's Restroom (near Classroom 316)	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	No	
1	3	Custodial Closet adjacent to Classroom 318	no	W1	Plaster	White	Flaking	30	18.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	No	Floor Tile
1	3	Custodial Closet adjacent to Classroom 318	no	W1	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	No	
1	3	Custodial Closet adjacent to Classroom 318	no	W2	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	No	
1	3	Custodial Closet adjacent to Classroom 318	no	W3	Plaster	White	Flaking	30	19.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	No	
1	3	Custodial Closet adjacent to Classroom 318	no	W3	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	No	
1	3	Custodial Closet adjacent to Classroom 318	no	W4	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	No	
1	3	Custodial Closet adjacent to Classroom 318	no	W4	Plaster	White	Cracking	30	26	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	No	
1	3	Custodial Closet adjacent to Classroom 318	no	W4	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	No	
1	3	Custodial Closet adjacent to Classroom 318	no	Celling	Metal	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	No	
1	3	Custodial Closet adjacent to Classroom 318	no	Floor	Concrete	Grey	Flaking	3	10.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	No	
1	3	Girls Restroom (near Classroom 319)	yes	W1	Plaster/Ceramic	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	No	
1	3	Girls Restroom (near Classroom 319)	yes	W2	Plaster/Ceramic/Block	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	No	
1	3	Girls Restroom (near Classroom 319)	yes	W3	Plaster/Ceramic	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	No	
1	3	Girls Restroom (near Classroom 319)	yes	W4	Plaster/Ceramic	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	No	
1	3	Girls Restroom (near Classroom 319)	yes	Celling	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	No	
1	3	Girls Restroom (near Classroom 319)	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	No	No paint
1	3	Boys Restroom (near Classroom 320)	yes	W1	Plaster/Ceramic	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	No	
1	3	Boys Restroom (near Classroom 320)	yes	W2	Plaster/Ceramic	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	No	
1	3	Boys Restroom (near Classroom 320)	yes	W3	Plaster/Ceramic	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	No	
1	3	Boys Restroom (near Classroom 320)	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	No	
1	3	Boys Restroom (near Classroom 320)	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	No	
1	3	Boys Restroom (near Classroom 320)	yes	W4	Plaster/Ceramic/Block	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	No	
1	3	Boys Restroom (near Classroom 320)	yes	Celling	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	No	No	No	
1																								

Rudolph Blankenburg Lead Safe Certification Assessment Report

School District of Philadelphia Lead Safe Certification Assessment Report Rudolph Blankenburg Elementary School

Name of Inspectors: Ananth K. Vinjamuri, Melissa Billingsley		Inspection Company: Criterion Labs, Inc.		Inspection Dates: 6/17 - 24/2019		ULCS# 1490																	
Element	Room	On-Site Room Name	Student/Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Quantity (sq ft)	XRF Reading (ppm)	Primary Component XRF (positive/negative)	Additional Component	Substrate Material	Color	Description of Paint and Plaster Damage	Additional Component Quantity (sq ft)	XRF Reading (ppm)	Additional Component XRF (positive/negative)	Leads (describe location)	Quantity (sq ft)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes/no)	Comments/Description/Notes
1	3	Fire Tower adjacent to Hallway from Classrooms 325 to 328	yes	Floor	Concrete	Grey	Flaking	20	2.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	3	Hallway from Classrooms 325 to 328	yes	W1	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	3	Hallway from Classrooms 325 to 328	yes	W2	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	3	Hallway from Classrooms 325 to 328	yes	W3	N/A	N/A	Efflorescence, Spalling	30	1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	Unknown	yes	
1	3	Hallway from Classrooms 325 to 328	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A	Radiator cover	Metal	Brown	Friction	3	0.01	Negative	None	0	No	No	no	
1	3	Hallway from Classrooms 325 to 328	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A	Window sill	Plaster	Grey	Damaged plaster	4	3.6	Positive	None	0	No	Unknown	Yes	At window across from Classroom 327
1	3	Hallway from Classrooms 325 to 328	yes	W4	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	3	Hallway from Classrooms 325 to 328	yes	W4	Plaster	White	Cracking	3	27.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	Near Stairwell
1	3	Hallway from Classrooms 325 to 328	yes	W1	Concrete	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	3	Starwell G (near Classroom 319)	yes	Floor	Plaster	White	Efflorescence, Spalling	30	28.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	3	Starwell G (near Classroom 319)	yes	W1	Plaster	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	3	Starwell G (near Classroom 319)	yes	W2	Plaster	White	Friction	3	9.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	3	Starwell G (near Classroom 319)	yes	W2	Plaster	Yellow	Friction	3	13.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	3	Starwell G (near Classroom 319)	yes	W3	Plaster	White/Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	3	Starwell G (near Classroom 319)	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A	Door	Brown	Friction, repeated contact	4	4	2	Positive	None	0	No	No	no	
1	3	Starwell G (near Classroom 319)	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A	Stair riser	Concrete	Grey	Flaking	10	3	Positive	None	0	No	No	no	
1	3	Starwell G (near Classroom 319)	yes	W4	Concrete	White	Friction	30	32.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	3	Starwell G (near Classroom 319)	yes	W4	Plaster	Yellow	Friction	2	18.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	3	Starwell G (near Classroom 319)	yes	W4	Plaster	White	Flaking	20	32.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	3	Starwell G (near Classroom 319)	yes	Floor	Concrete	Grey	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	3	Fire Tower Hallway adjacent Hallway from Classrooms 316 to 319	yes	W1	Brick	White	Cracking	8	14.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	3	Fire Tower Hallway adjacent Hallway from Classrooms 316 to 319	yes	W2	Brick	White	Cracking	20	19.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	3	Fire Tower Hallway adjacent Hallway from Classrooms 316 to 319	yes	W3	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	3	Fire Tower Hallway adjacent Hallway from Classrooms 316 to 319	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A	Window sill	Metal	Grey	Flaking	10	2.8	Positive	None	0	No	No	no	
1	3	Fire Tower Hallway adjacent Hallway from Classrooms 316 to 319	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A	Pipe	Metal	Grey	Flaking	5	0.3	Negative	None	0	No	No	no	
1	3	Fire Tower Hallway adjacent Hallway from Classrooms 316 to 319	yes	W4	Brick	White	Cracking	15	15.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	3	Fire Tower Hallway adjacent Hallway from Classrooms 316 to 319	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A	Window sill	Metal	Grey	Flaking	10	2.4	Positive	None	0	No	No	no	
1	3	Fire Tower Hallway adjacent Hallway from Classrooms 316 to 319	yes	W4	Concrete	White	Cracking	20	1.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	3	Fire Tower Hallway adjacent Hallway from Classrooms 316 to 319	yes	Floor	Concrete	Grey	Flaking	10	0.06	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	Along perimeter
1	3	Fire Tower adjacent to Hallway from Classrooms 316 to 319	yes	W1	Concrete	White	Flaking	3	13.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	3	Fire Tower adjacent to Hallway from Classrooms 316 to 319	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door	Metal	Grey	Friction	2	0	Negative	None	0	No	No	no	
1	3	Fire Tower adjacent to Hallway from Classrooms 316 to 319	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	Grey	Flaking	10	0	Negative	None	0	No	No	no	
1	3	Fire Tower adjacent to Hallway from Classrooms 316 to 319	yes	W2	Brick	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	3	Fire Tower adjacent to Hallway from Classrooms 316 to 319	yes	W3	Brick	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	3	Fire Tower adjacent to Hallway from Classrooms 316 to 319	yes	W4	N/A	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	3	Fire Tower adjacent to Hallway from Classrooms 316 to 319	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A	Window frame	Metal	Grey	Flaking	10	17.7	Positive	None	0	No	No	no	
1	3	Fire Tower adjacent to Hallway from Classrooms 316 to 319	yes	W4	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	3	Fire Tower adjacent to Hallway from Classrooms 316 to 319	yes	Floor	Concrete	Grey	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	3	Hallway from Classrooms 316 to 319	yes	W1	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	3	Hallway from Classrooms 316 to 319	yes	W2	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	3	Hallway from Classrooms 316 to 319	yes	W3	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	3	Hallway from Classrooms 316 to 319	yes	W4	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	3	Hallway from Classrooms 316 to 319	yes	W4	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	3	Hallway from Classrooms 316 to 319	yes	W4	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	3	Hallway from Classrooms 316 to 319	yes	W4	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	3	Hallway from Classrooms 316 to 319	yes	W4	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	3	Hallway from Classrooms 316 to 319	yes	W4	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	3	Hallway from Classrooms 316 to 319	yes	W4	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	3	Hallway from Classrooms 316 to 319	yes	W4	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	3	Hallway from Classrooms 316 to 319	yes	W4	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	3	Hallway from Classrooms 316 to 319	yes	W4	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	3	Hallway from Classrooms 316 to 319	yes	W4	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	3	Hallway from Classrooms 316 to 319	yes	W4	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	3	Hallway from Classrooms 316 to 319	yes	W4	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	3	Hallway from Classrooms 316 to 319	yes	W4	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	3	Hallway from Classrooms 316 to 319	yes	W4	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	3	Hallway from Classrooms 316 to 319	yes	W4	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	3	Hallway from Classrooms 316 to 319	yes	W4	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	3	Hallway from Classrooms 316 to 319	yes	W4	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	3	Hallway from Classrooms 316 to 319	yes	W4	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	3	Hallway from Classrooms 316 to 319	yes	W4	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	3	Hallway from Classrooms 316 to 319	yes	W4	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	3	Hallway from Classrooms 316 to 319	yes	W4	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1																							

Rudolph Blankenburg Lead Safe Certification Assessment Report

School District of Philadelphia																						
Lead Safe Certification Assessment Report																						
Rudolph Blankenburg Elementary School																						
Name of Inspectors: Ananth K. Vinjamuri, Melissa Billingsley															Inspection Dates: 6/17 -24/2019							
Inspection Company: Criterion Labs, Inc.															ULCS# 1490							
E l e m e n t #	On-Site Room Name	Student/Teacher Occupied (year(s))	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/negative)	Additional Component	Substrate Material	Color	Description of Paint and Plaster Damage	Additional Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Additional Component XRF (positive/negative)	debris Present (describe location)	Quantity (sf)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Comments/ Description/ Notes
2	1	Kitchen 33	yes	W1	N/A	N/A	N/A	N/A	N/A	Door	Wood	Grey	Chipping	2	0	Negative	None	0	No	No	no	
2	1	Kitchen 33	yes	W1	N/A	N/A	N/A	N/A	N/A	Door Frame	Metals	Grey	Chipping	2	0	Negative	None	0	No	No	no	
2	1	Kitchen 33	yes	W2	Sheetrock	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
2	1	Kitchen 33	yes	W3	Sheetrock	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
2	1	Kitchen 33	yes	W5	N/A	N/A	N/A	N/A	N/A	Radiator cover	Metals	Teal	Chipping	2	0.1	Negative	None	0	No	No	no	
2	1	Kitchen 33	yes	W3	N/A	N/A	N/A	N/A	N/A	Door	Metals	Grey	Chipping	2	0	Negative	None	0	No	No	no	
2	1	Kitchen 33	yes	W3	N/A	N/A	N/A	N/A	N/A	door Frame	Metals	Grey	Chipping	2	0	Negative	None	0	No	No	no	
2	1	Kitchen 33	yes	W4	Sheetrock	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
2	1	Kitchen 33	yes	Ceiling	Sheetrock	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
2	1	Kitchen 33	yes	Floor	Sheetrock	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
2	1	Center Hallway	yes	W1	Sheetrock	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
2	1	Center Hallway	yes	W2	Sheetrock	White	Flaking	1	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
2	1	Center Hallway	yes	W5	Sheetrock	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
2	1	Center Hallway	yes	W4	Sheetrock	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
2	1	Center Hallway	yes	Ceiling	Sheetrock	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
2	1	Center Hallway	yes	Floor	Sheetrock	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	