

School District of Philadelphia
Lead Safe Certification Inspection Report
Francis Scott Key School

		Name of Inspector: Charles Rhodes Inspection Company: Batta Environmental															Inspection Dates: 7/1-7/9/2019						
																	ULCS# 2540						
Element	Floor	On-Site Room Name	Student Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/negative)	Additional Component	Substrate Material	Color	Description of Paint and Plaster Damage	Additional Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Additional Component XRF (positive/negative)	Debris Present (describe location)	Quantity (sf)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Comments/Description/ Notes
1	B	Store Room 8 - Fan Room next to Cafeteria (Fan Room # 1)	no	W1	Brick	White	Flaking	380	0.2	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	B	Store Room 8 - Fan Room next to Cafeteria (Fan Room # 1)	no	W2	Brick	White	Partially Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	B	Store Room 8 - Fan Room next to Cafeteria (Fan Room # 1)	no	W3	Brick	White	Flaking	30	0.1	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	B	Store Room 8 - Fan Room next to Cafeteria (Fan Room # 1)	no	W3	N/A	N/A	N/A	N/A	N/A	N/A	Radiator	Metal	Brown	Chipping	50	9	Positive	None	N/A	No	No	no	duck work
1	B	Store Room 8 - Fan Room next to Cafeteria (Fan Room # 1)	no	W4	Brick	White	Flaking	30	0.1	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	B	Store Room 8 - Fan Room next to Cafeteria (Fan Room # 1)	no	Ceiling	Plaster	White	Flaking	190	0.5	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	B	Store Room 8 - Fan Room next to Cafeteria (Fan Room # 1)	no	Floor	Concrete	Grey	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	B	Boy's Restroom outside of Cafeteria	yes	W1	Brick	Tan	Chipping	4	0.4	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	B	Boy's Restroom outside of Cafeteria	yes	W2	Concrete	Tan	Chipping	18	0.1	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	B	Boy's Restroom outside of Cafeteria	yes	W3	Plaster	Tan	Chipping	65	0.2	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	B	Boy's Restroom outside of Cafeteria	yes	W4	Brick	Tan	Cracking	20	0.5	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	B	Boy's Restroom outside of Cafeteria	yes	Ceiling	Plaster	Tan	Chipping	130	0.5	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	yes	
1	B	Boy's Restroom outside of Cafeteria	yes	Floor	Concrete	Grey	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	B	Store Room 6	no	W1	Brick	White	Flaking	27	0.1	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	B	Store Room 6	no	W2	Brick	White	Flaking	30	0.1	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	B	Store Room 6	no	W3	Brick	White	Flaking	48	0.2	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	B	Store Room 6	no	W4	Brick	White	Flaking	130	0.1	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	B	Store Room 6	no	Ceiling	Plaster	White	Spalling	80	0.1	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	B	Store Room 6	no	Floor	Brick	White	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	B	Store Room 5	no	W1	Brick	White	Flaking	1	0.1	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	B	Store Room 5	no	W2	Brick	White	Flaking	25	0.1	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	B	Store Room 5	no	W3	Brick	White	Flaking	20	-0.1	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	B	Store Room 5	no	W4	Brick	White	Flaking	18	0.2	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	B	Store Room 5	no	Ceiling	Plaster	White	Flaking	9	0.1	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	B	Store Room 5	no	Floor	Concrete	Grey	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	B	Store Room 4	no	W1	Brick	White	Flaking	17	0.1	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	B	Store Room 4	no	W2	Brick	White	Chipping	20	0.1	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	B	Store Room 4	no	W3	Brick	White	Cracking	10	0.1	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	B	Store Room 4	no	W4	Brick	White	Chipping	28	0.1	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	B	Store Room 4	no	Ceiling	Plaster	White	Cracking	6	0.2	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	yes	
1	B	Store Room 4	no	Floor	Concrete	Grey	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	B	Store Room 3	no	W1	Metal	Brown	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	B	Store Room 3	no	W2	Brick	White	Flaking	70	0.3	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	B	Store Room 3	no	W3	Brick	White	Flaking	30	0.5	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	B	Store Room 3	no	W4	Brick	White	Flaking	10	0.1	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	B	Store Room 3	no	Ceiling	Plaster	White	Flaking	6	-0.3	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	B	Store Room 3	no	Floor	Concrete	Grey	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	B	Store Room 2	no	W1	Brick	White	Flaking	2	0.2	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	B	Store Room 2	no	W2	Brick	White	Spalling	30	0.3	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	B	Store Room 2	no	W3	Brick	White	Flaking	17	0.1	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	B	Store Room 2	no	W4	Brick	White	Spalling	60	0.1	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	B	Store Room 2	no	Ceiling	Plaster	White	Spalling	24	0.2	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	B	Store Room 2	no	Floor	Concrete	Grey	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	B	Staff Restroom next to Store Room 2	yes	W1	Plaster	White	Cracking	8	0.2	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	B	Staff Restroom next to Store Room 2	yes	W2	Plaster	White	Flaking	24	0.2	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	B	Staff Restroom next to Store Room 2	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A	Radiator	Metal	White	Flaking	9	11.5	Positive	None	N/A	No	No	no	
1	B	Staff Restroom next to Store Room 2	yes	W3	Plaster	White	Flaking	21	0.2	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	B	Staff Restroom next to Store Room 2	yes	W4	Plaster	White	Flaking	47	0.1	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	B	Staff Restroom next to Store Room 2	yes	Ceiling	Plaster	White	Flaking	60	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	B	Staff Restroom next to Store Room 2	yes	Floor	Concrete	Black	Chipping	13	1.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	B	Store Room 7	no	W1	Metal	Brown	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	B	Store Room 7	no	W2	Brick	White	Spalling	200	0.1	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	B	Store Room 7	no	W3	Brick	White	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	B	Store Room 7	no	W4	Brick	White	Flaking	120	0.2	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	B	Store Room 7	no	Ceiling	Plaster	White	Flaking	36	-0.4	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	B	Store Room 7	no	Floor	Concrete	Black	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	B	Stairwell next to Boy's Restroom	yes	W1	Metal	Brown	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	B	Stairwell next to Boy's Restroom	yes	W2	Wood	Tan	Chipping	1	0.3	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	B	Stairwell next to Boy's Restroom	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A	Hand rails	Wood	Brown	Chipping	9	-0.1	Negative	None	N/A	No	No	no	
1	B	Stairwell next to Boy's Restroom	yes	W3	Plaster	Tan	Spalling	15	0.2	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	B	Stairwell next to Boy's Restroom	yes	W4	Plaster	Tan	Cracking	17	0.1	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	B	Stairwell next to Boy's Restroom	yes	Ceiling	Plaster	Tan	Cracking	3	-0.2	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	B	Stairwell next to Boy's Restroom	yes	Floor	Concrete	Black	Chipping	4	0.3	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	B	Storage Area below Stairwell next to Boy's Restroom	no	W1	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	B	Storage Area below Stairwell next to Boy's Restroom	no	W2	Plaster	Tan	Flaking	180	0.1	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	B	Storage Area below Stairwell next to Boy's Restroom	no	W3	Plaster	Tan	Spalling	30	0.1	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	B	Storage Area below Stairwell next to Boy's Restroom	no	W4	Plaster	Tan	Flaking	190	0.2	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	

School District of Philadelphia
Lead Safe Certification Inspection Report
Francis Scott Key School

		Name of Inspector: Charles Rhodes Inspection Company: Batta Environmental															Inspection Dates: 7/1-7/9/2019						
																	ULCS# 2540						
Element	Floor	On-Site Room Name	Student Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/negative)	Additional Component	Substrate Material	Color	Description of Paint and Plaster Damage	Additional Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Additional Component XRF (positive/negative)	Debris Present (describe location)	Quantity (sf)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Comments/Description/Notes
1	B	Storage Area below Stairwell next to Boy's Restroom	no	Ceiling	Plaster	Tan	Spalling	120	0.1	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	duck work is 10.8 flaking 55 sf tan
1	B	Storage Area below Stairwell next to Boy's Restroom	no	Floor	Concrete	Tan	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	B	Food Storage Room next to Cafeteria (labeled Elec MDP)	no	W1	Brick	White	Cracking	12	0.1	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	B	Food Storage Room next to Cafeteria (labeled Elec MDP)	no	W2	Wood	White	Chipping	2	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	B	Food Storage Room next to Cafeteria (labeled Elec MDP)	no	W3	Brick	White	Cracking	15	0.1	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	B	Food Storage Room next to Cafeteria (labeled Elec MDP)	no	W4	Brick	White	Cracking	4	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	B	Food Storage Room next to Cafeteria (labeled Elec MDP)	no	Ceiling	Plaster	White	Flaking	35	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	yes	
1	B	Food Storage Room next to Cafeteria (labeled Elec MDP)	no	Floor	Concrete	White	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	B	Storage Room next to Cafeteria	no	W1	Wood	White	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	B	Storage Room next to Cafeteria	no	W2	Plaster	White	Cracking	50	0.1	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	B	Storage Room next to Cafeteria	no	W3	Plaster	White	Cracking	4	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	B	Storage Room next to Cafeteria	no	W4	Plaster	White	Cracking	22	0.3	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	B	Storage Room next to Cafeteria	no	Ceiling	Plaster	White	Cracking	5	0.2	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	B	Storage Room next to Cafeteria	no	Floor	Concrete	Black	Chipping	3	0.3	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	B	Gas Main/Storage Room next to Cafeteria	no	W1	Wood	Brown	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	B	Gas Main/Storage Room next to Cafeteria	no	W2	Plaster	White	Flaking	90	0.2	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	B	Gas Main/Storage Room next to Cafeteria	no	W3	Plaster	White	Flaking	30	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	B	Gas Main/Storage Room next to Cafeteria	no	W4	Plaster	White	Flaking	50	0.1	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	B	Gas Main/Storage Room next to Cafeteria	no	Ceiling	Plaster	White	Flaking	34	0.2	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	B	Gas Main/Storage Room next to Cafeteria	no	Floor	Concrete	Black	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	B	Cafeteria	yes	W1	Plaster	Tan	Chipping	5	15.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	B	Cafeteria	yes	W2	Plaster	Blue	Spalling	42	9.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	yes	
1	B	Cafeteria	yes	W3	Plaster	Tan	Spalling	78	4.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	yes	
1	B	Cafeteria	yes	W4	Brick	Tan	Flaking	54	11.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	B	Cafeteria	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A	Columns	Brick	Tan	Chipping	5	5.7	Positive	None	N/A	No	No	no	includes all in the room
1	B	Cafeteria	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	N/A	drop down ceiling tiles
1	B	Cafeteria	yes	Floor	Concrete	Grey	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	B	Stairwell next to Cafeteria	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	B	Stairwell next to Cafeteria	yes	W2	Plaster	Tan	Chipping	6	21.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	B	Stairwell next to Cafeteria	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A	Hand rails	Wood	Brown	Chipping	10	-0.1	Negative	None	N/A	No	No	no	
1	B	Stairwell next to Cafeteria	yes	W3	Brick	Tan	Chipping	3	40	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	B	Stairwell next to Cafeteria	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	Tan	Chipping	12	-0.1	Negative	None	N/A	No	No	no	
1	B	Stairwell next to Cafeteria	yes	W4	Plaster	Tan	Chipping	12	0.1	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	B	Stairwell next to Cafeteria	yes	Ceiling	Plaster	Tan	Cracking	4	0.5	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	B	Stairwell next to Cafeteria	yes	Floor	Concrete	Black	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	B	Hallway next to Cafeteria	yes	W1	Plaster	Tan	Flaking	62	0.6	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	B	Hallway next to Cafeteria	yes	W2	Plaster	Tan	Chipping	18	0.1	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	B	Hallway next to Cafeteria	yes	W2	Wood	Tan	Chipping	12	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	B	Hallway next to Cafeteria	yes	W3	Plaster	Tan	Chipping	1	0.3	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	B	Hallway next to Cafeteria	yes	W4	Plaster	Tan	Chipping	6	0.3	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	includes brick
1	B	Hallway next to Cafeteria	yes	Ceiling	Concrete	Tan	Flaking	500	-0.2	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	yes	
1	B	Hallway next to Cafeteria	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	Radiator	Metal	Tan	Chipping	300	12.5	Positive	None	N/A	No	No	no	duct and piping
1	B	Hallway next to Cafeteria	yes	Floor	Concrete	Black	Chipping	50	0.2	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	B	Hallway from Store Room 1 to the Girl's Restroom	no	W1	Plaster	Tan	Chipping	2	0.3	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	B	Hallway from Store Room 1 to the Girl's Restroom	no	W2	Plaster	Tan	Flaking	80	0.3	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	includes brick
1	B	Hallway from Store Room 1 to the Girl's Restroom	no	W2	N/A	N/A	N/A	N/A	N/A	N/A	Radiator	Metal	Tan	Cracking	150	0	Negative	None	N/A	No	No	no	piping
1	B	Hallway from Store Room 1 to the Girl's Restroom	no	W3	Brick	Tan	Chipping	1	0.1	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	B	Hallway from Store Room 1 to the Girl's Restroom	no	W4	Plaster	Tan	Cracking	25	0.5	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	includes stone and brick
1	B	Hallway from Store Room 1 to the Girl's Restroom	no	Ceiling	Concrete	Tan	Chipping	500	-0.5	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	yes	
1	B	Hallway from Store Room 1 to the Girl's Restroom	no	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	Uni-vent	Metal	Tan	Partially Inaccessible	300	9.5	Positive	None	N/A	No	No	no	
1	B	Hallway from Store Room 1 to the Girl's Restroom	no	Floor	Concrete	Black	Chipping	30	0.2	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	B	Store Room 1 (Fan Room across from Cafeteria)	no	W1	Plaster	Green	Flaking	110	0.4	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	includes white brick and stone
1	B	Store Room 1 (Fan Room across from Cafeteria)	no	W2	Plaster	Green	Flaking	40	0.2	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	includes white brick and stone
1	B	Store Room 1 (Fan Room across from Cafeteria)	no	W3	Plaster	Green	Partially Inaccessible	130	0.3	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	includes white brick and stone and flaking
1	B	Store Room 1 (Fan Room across from Cafeteria)	no	W4	Plaster	Green	Partially Inaccessible	45	4.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	yes	includes white brick and stone and flaking
1	B	Store Room 1 (Fan Room across from Cafeteria)	no	W4	N/A	N/A	N/A	N/A	N/A	N/A	Window trim	Wood	Green	Flaking	5	7.9	Negative	None	N/A	No	No	no	
1	B	Store Room 1 (Fan Room across from Cafeteria)	no	Ceiling	Plaster	White	Flaking	110	-0.4	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	yes	

School District of Philadelphia
Lead Safe Certification Inspection Report
Francis Scott Key School

		Name of Inspector: Charles Rhodes Inspection Company: Batta Environmental														Inspection Dates: 7/1-7/9/2019							
Element	Floor	On-Site Room Name	Student Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/negative)	Additional Component	Substrate Material	Color	Description of Paint and Plaster Damage	Additional Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Additional Component XRF (positive/negative)	Debris Present (describe location)	Quantity (sf)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Comments/Description/ Notes
1	B	Store Room 1 (Fan Room across from Cafeteria)	no	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	Uni-vent	Metal	Tan	Flaking	60	4.5	Positive	None	N/A	No	No	no	
1	B	Store Room 1 (Fan Room across from Cafeteria) - Rear of Fan Unit	no	Floor	Concrete	Grey	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	B	Store Room 1 (Fan Room across from Cafeteria) - Rear of Fan Unit	no	W1	Plaster	Green	Flaking	90	0.4	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	includes white brick and stone
1	B	Store Room 1 (Fan Room across from Cafeteria) - Rear of Fan Unit	no	W2	Plaster	Green	Flaking	320	0.2	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	includes white brick and stone
1	B	Store Room 1 (Fan Room across from Cafeteria) - Rear of Fan Unit	no	W3	Plaster	Green	Partially Inaccessible	35	0.3	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	includes white brick and stone and flaking
1	B	Store Room 1 (Fan Room across from Cafeteria) - Rear of Fan Unit	no	W3	N/A	N/A	N/A	N/A	N/A	N/A	Uni-vent	Metal	Grey	Chipping	700	14.9	Positive	None	N/A	No	No	no	with red primer fan
1	B	Store Room 1 (Fan Room across from Cafeteria) - Rear of Fan Unit	no	W4	Plaster	Green	Partially Inaccessible	90	4.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	includes white brick and stone and flaking
1	B	Store Room 1 (Fan Room across from Cafeteria) - Rear of Fan Unit	no	W4	N/A	N/A	N/A	N/A	N/A	N/A	Window trim	Wood	Green	Flaking	5	7.9	Negative	None	N/A	No	No	no	
1	B	Store Room 1 (Fan Room across from Cafeteria) - Rear of Fan Unit	no	Ceiling	Plaster	White	Flaking	750	-0.4	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	yes	
1	B	Store Room 1 (Fan Room across from Cafeteria) - Rear of Fan Unit	no	Floor	Concrete	Grey	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	B	Mechanical Room/Building Engineers Office next to Old Boiler Room	no	W1	Concrete	Blue	Spalling	5	0.1	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	B	Mechanical Room/Building Engineers Office next to Old Boiler Room	no	W2	Brick	White	Chipping	4	0.2	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	B	Mechanical Room/Building Engineers Office next to Old Boiler Room	no	W3	Brick	Blue	Spalling	5	0.2	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	B	Mechanical Room/Building Engineers Office next to Old Boiler Room	no	W4	Brick	White	Spalling	36	0.3	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	B	Mechanical Room/Building Engineers Office next to Old Boiler Room	no	Ceiling	Concrete	White	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	B	Mechanical Room/Building Engineers Office next to Old Boiler Room	no	Floor	Concrete	Grey	Chipping	10	0.1	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	B	Old Boiler Room - Inactive Boilers	no	W1	Brick	White	Chipping	25	0.1	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	B	Old Boiler Room - Inactive Boilers	no	W2	Brick	White	Flaking	35	0.2	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	B	Old Boiler Room - Inactive Boilers	no	W3	Concrete	White	Spalling	200	0.3	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	B	Old Boiler Room - Inactive Boilers	no	W4	Brick	White	Spalling	10	20.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	B	Old Boiler Room - Inactive Boilers	no	Ceiling	Plaster	White	Partially Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	B	Old Boiler Room - Inactive Boilers	no	Floor	Concrete	Brown	Chipping	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	B	Boiler Room - Active Boilers	no	W1	Brick	White	Chipping	3	0.2	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	B	Boiler Room - Active Boilers	no	W2	Brick	White	Chipping	5	0.2	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	B	Boiler Room - Active Boilers	no	W2	N/A	N/A	N/A	N/A	N/A	N/A	Hand rails	Metal	Black	Chipping	55	5.8	Positive	None	N/A	No	No	no	includes stairs and landing
1	B	Boiler Room - Active Boilers	no	W3	Concrete	White	Flaking	40	0.3	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	B	Boiler Room - Active Boilers	no	W4	Plaster	White	Flaking	35	0.2	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	includes blue paint
1	B	Boiler Room - Active Boilers	no	Ceiling	Plaster	White	Flaking	N/A	0.4	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	B	Boiler Room - Active Boilers	no	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	Uni-vent	Concrete	White	Flaking	90	12.9	Positive	None	N/A	No	No	no	
1	B	Boiler Room - Active Boilers	no	Floor	Brick	Brown	Chipping	600	0.2	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	B	Basement Custodial Break Room beside Girls Restroom	no	W1	Brick	White	Spalling	1	0.1	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	B	Basement Custodial Break Room beside Girls Restroom	no	W2	Brick	White	Spalling	20	0.1	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	B	Basement Custodial Break Room beside Girls Restroom	no	W3	Brick	White	Spalling	6	0.3	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	yes	
1	B	Basement Custodial Break Room beside Girls Restroom	no	W3	N/A	N/A	N/A	N/A	N/A	N/A	Window sill	Brick	White	Spalling	5	5.3	Positive	None	N/A	No	No	no	includes window trim
1	B	Basement Custodial Break Room beside Girls Restroom	no	W4	Brick	White	Spalling	1	0.1	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	B	Basement Custodial Break Room beside Girls Restroom	no	Ceiling	Concrete	White	Flaking	190	0.2	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	B	Basement Custodial Break Room beside Girls Restroom	no	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	Uni-vent	Plaster	White	Flaking	105	15.7	Positive	None	N/A	No	No	no	
1	B	Basement Custodial Break Room beside Girls Restroom	no	Floor	Concrete	Black	Flaking	45	0.2	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	B	Girl's Restroom	yes	W1	Plaster	Tan	Cracking	8	-0.2	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	B	Girl's Restroom	yes	W2	Plaster	Tan	Cracking	15	8.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	B	Girl's Restroom	yes	W3	Plaster	Tan	Flaking	32	6.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	includes brick wall
1	B	Girl's Restroom	yes	W4	Plaster	Tan	Spalling	20	0.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	B	Girl's Restroom	yes	Ceiling	Concrete	Tan	Chipping	160	0.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	B	Girl's Restroom	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	Radiator	Metal	Tan	Flaking	85	11.3	Positive	None	N/A	No	No	no	
1	B	Girl's Restroom	yes	Floor	Concrete	Grey	Chipping	7	0.2	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	B	Storage Room across from Girl's Restroom	no	W1	Brick	Green	Flaking	5	0.1	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	B	Storage Room across from Girl's Restroom	no	W2	Brick	Green	Flaking	40	0.3	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	B	Storage Room across from Girl's Restroom	no	W3	Brick	Green	Partially Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	B	Storage Room across from Girl's Restroom	no	W4	Plaster	Green	Spalling	320	0.2	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	B	Storage Room across from Girl's Restroom	no	Ceiling	Concrete	Green	Flaking	80	0.3	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	B	Storage Room across from Girl's Restroom	no	Floor	Concrete	Grey	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	B	Storage Closet outside of Girl's Restroom	no	W1	Brick	Green	Cracking	1	0.1	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	B	Storage Closet outside of Girl's Restroom	no	W2	Brick	Green	Cracking	5	0.1	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	B	Storage Closet outside of Girl's Restroom	no	W3	Brick	Green	Cracking	1	0.3	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	B	Storage Closet outside of Girl's Restroom	no	W3	N/A	N/A	N/A	N/A	N/A	N/A	Window frame	Wood	Green	Flaking	10	9.9	Positive	None	N/A	No	No	no	

School District of Philadelphia
Lead Safe Certification Inspection Report
Francis Scott Key School

		Name of Inspector: Charles Rhodes Inspection Company: Batta Environmental															Inspection Dates: 7/1-7/9/2019			ULCS# 2540			
Element	Floor	On-Site Room Name	Student Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/negative)	Additional Component	Substrate Material	Color	Description of Paint and Plaster Damage	Additional Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Additional Component XRF (positive/negative)	Debris Present (describe location)	Quantity (sf)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Comments/ Description/ Notes
1	B	Storage Closet outside of Girl's Restroom	no	W4	Brick	Green	Cracking	1	0.1	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	No	No	no	
1	B	Storage Closet outside of Girl's Restroom	no	W4	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	No	No	no	
1	B	Storage Closet outside of Girl's Restroom	no	Ceiling	Concrete	Grey	Cracking	1	0.2	Negative	Built-in cabinet	Wood	Green	Chipping	0	0	Negative	None	N/A	No	No	no	
1	B	Storage Closet outside of Girl's Restroom	no	Floor	Concrete	Grey	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	No	No	no	
1	B	Domestic Hot Water Heater Closet outside of Girl's Restroom	no	W1	Brick	Tan	Flaking	40	0.1	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	no	
1	B	Domestic Hot Water Heater Closet outside of Girl's Restroom	no	W2	Brick	Tan	Flaking	40	0.2	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	no	
1	B	Domestic Hot Water Heater Closet outside of Girl's Restroom	no	W3	Plaster	Tan	Flaking	30	0.2	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	no	
1	B	Domestic Hot Water Heater Closet outside of Girl's Restroom	no	W3	N/A	N/A	N/A	N/A	N/A	N/A	Window sill	Brick	Green	Flaking	10	9.9	Positive	None	N/A	No	no	no	
1	B	Domestic Hot Water Heater Closet outside of Girl's Restroom	no	W4	Brick	Tan	Flaking	65	0.1	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	no	
1	B	Domestic Hot Water Heater Closet outside of Girl's Restroom	no	Ceiling	Concrete	Tan	Flaking	75	0.3	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	no	yes
1	B	Domestic Hot Water Heater Closet outside of Girl's Restroom	no	Floor	Concrete	Tan	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	no	no
1	B	Stairwell next to Girl's Restroom	yes	W1	Brick	Tan	Cracking	40	13	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	no	
1	B	Stairwell next to Girl's Restroom	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	Hand rails	Metal	Brown	Chipping	24	0.6	Negative	None	N/A	No	No	no	includes all in the room
1	B	Stairwell next to Girl's Restroom	yes	W2	Brick	Tan	Chipping	3	13.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	B	Stairwell next to Girl's Restroom	yes	W3	Brick	Tan	Cracking	25	13.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	B	Stairwell next to Girl's Restroom	yes	W4	Brick	Tan	Cracking	3	21.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	B	Stairwell next to Girl's Restroom	yes	Ceiling	Concrete	Tan	Flaking	5	1.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	B	Stairwell next to Girl's Restroom	yes	Floor	Concrete	Black	Cracking	16	0.2	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	1	Stairwell next to Gym	yes	W1	Wood	Tan	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	1	Stairwell next to Gym	yes	W2	Plaster	Tan	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	1	Stairwell next to Gym	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A	Baseboard	Wood	Brown	Chipping	8	0.2	Negative	None	N/A	No	No	no	includes all in the room and stringer
1	1	Stairwell next to Gym	yes	W2	Brick	Tan	Chipping	3	17.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	1	Stairwell next to Gym	yes	W3	Plaster	Tan	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	1	Stairwell next to Gym	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A	Hand rails	Wood	Brown	Chipping	30	0.3	Negative	None	N/A	No	No	no	includes all in the room
1	1	Stairwell next to Gym	yes	W3	Wood	Tan	Chipping	7	0.1	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	1	Stairwell next to Gym	yes	W4	Plaster	Tan	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	1	Stairwell next to Gym	yes	Ceiling	Plaster	Tan	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	1	Stairwell next to Gym	yes	Floor	Concrete	Grey	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	1	Stairwell next to Main Office	yes	W1	Wood	N/A	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	1	Stairwell next to Main Office	yes	W2	Plaster	Tan	Chipping	1	32	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	1	Stairwell next to Main Office	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A	Hand rails	Wood	Brown	Chipping	36	0	Negative	None	N/A	No	No	no	includes all in the room
1	1	Stairwell next to Main Office	yes	W3	Plaster	Red	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	1	Stairwell next to Main Office	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	Red	Chipping	4	0	Negative	None	N/A	No	No	no	
1	1	Stairwell next to Main Office	yes	W4	Plaster	Tan	Chipping	7	30	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	1	Stairwell next to Main Office	yes	Ceiling	Plaster	Tan	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	1	Stairwell next to Main Office	yes	Floor	Concrete	Grey	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	1	Fire Tower # 1	yes	W1	Brick	White	Flaking	115	41	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	1	Fire Tower # 1	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door	Wood	Brown	Chipping	15	1.1	Positive	None	N/A	No	No	no	
1	1	Fire Tower # 1	yes	W2	Brick	White	Chipping	83	41	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	1	Fire Tower # 1	yes	W3	Brick	White	Cracking	150	35	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	1	Fire Tower # 1	yes	W4	Brick	White	Flaking	115	41	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	1	Fire Tower # 1	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A	Hand rails	Metal	Brown	Chipping	25	0.6	Negative	None	N/A	No	No	no	includes all in the room
1	1	Fire Tower # 1	yes	Ceiling	Plaster	White	Flaking	155	46	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	1	Fire Tower # 1	yes	Floor	Concrete	Grey	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	1	Fire Tower # 2	yes	W1	Brick	White	Flaking	75	31	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	1	Fire Tower # 2	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door	Metal	Brown	Chipping	25	0.6	Negative	None	N/A	No	No	no	
1	1	Fire Tower # 2	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door	Wood	Brown	Chipping	7	0.8	Negative	None	N/A	No	No	no	
1	1	Fire Tower # 2	yes	W2	Brick	White	Flaking	75	28.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	1	Fire Tower # 2	yes	W3	Brick	White	Cracking	70	37	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	1	Fire Tower # 2	yes	W4	Brick	White	Cracking	85	34	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	1	Fire Tower # 2	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A	Hand rails	Metal	Brown	Chipping	25	0.6	Negative	None	N/A	No	No	no	includes all in the room
1	1	Fire Tower # 2	yes	Ceiling	Plaster	White	Flaking	195	36	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	1	Fire Tower # 2	yes	Floor	Concrete	Grey	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	1	Fire Tower # 3	yes	W1	Brick	White	Chipping	6	15.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	1	Fire Tower # 3	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door	Metal	Brown	Chipping	17	0	Negative	None	N/A	No	No	no	
1	1	Fire Tower # 3	yes	W2	Brick	White	Chipping	9	15.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	1	Fire Tower # 3	yes	W3	Brick	White	Chipping	16	19	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	1	Fire Tower # 3	yes	W4	Brick	White	Chipping	4	18.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	1	Fire Tower # 3	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A	Hand rails	Metal	Brown	Chipping	11	0.5	Negative	None	N/A	No	No	no	includes all in the room
1	1	Fire Tower # 3	yes	Ceiling	Plaster	White	Cracking	10	27.3	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	1	Fire Tower # 3	yes	Floor	Concrete	Grey	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	1	Fire Tower # 4	yes	W1	Brick	White	Chipping	10	16.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	1	Fire Tower # 4	yes	W2	Brick	White	Chipping	5	14.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	1	Fire Tower # 4	yes	W3	Brick	White	Chipping	14	19.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	1	Fire Tower # 4	yes	W4	Brick	White	Chipping	14	17.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	1	Fire Tower # 4	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A	Hand rails	Metal	Brown	Chipping	85	0.4	Negative	None	N/A	No	No	no	includes all in the room
1	1	Fire Tower # 4	yes	Ceiling	Plaster	White	Flaking	54	28.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	1	Fire Tower # 4	yes	Floor	Concrete	Grey	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	1	Hallway outside Classrooms 2 -6	yes	W1	Wood	Blue	Flaking	12	0.1	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	1	Hallway outside Classrooms 2 -6	yes	W2	Plaster	Tan	Flaking	8	26.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	1	Hallway outside Classrooms 2 -6	yes	W2	Brick	Blue	Chipping	16	21.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	includes Wall 4 of brick

School District of Philadelphia
Lead Safe Certification Inspection Report
Francis Scott Key School

		Name of Inspector: Charles Rhodes Inspection Company: Batta Environmental															Inspection Dates: 7/1-7/9/2019 ULCS# 2540						
Element	Floor	On-Site Room Name	Student Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/negative)	Additional Component	Substrate Material	Color	Description of Paint and Damage	Additional Component Quantity (sf)	XRF Reading (mg/cm2)	Additional Component XRF (positive/negative)	Debris Present (describe location)	Quantity (sf)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Comments/ Description/ Notes
1	1	Hallway outside Classrooms 2 -6	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A	Chair rail	Wood	Red	Chipping	25	1.8	Positive	None	N/A	No	No	no	includes Wall 2 and 4
1	1	Hallway outside Classrooms 2 -6	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A	Radiator	Metal	Grey	Flaking	110	4.1	Positive	None	N/A	No	No	no	includes all in room
1	1	Hallway outside Classrooms 2 -6	yes	W3	Metal	Red	Chipping	7	0.2	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	Wall with front door
1	1	Hallway outside Classrooms 2 -6	yes	W4	Plaster	Tan	Flaking	5	33	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	1	Hallway outside Classrooms 2 -6	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A	Chalkboard frame	Wood	Red	Chipping	1	2.8	Positive	None	N/A	No	No	no	
1	1	Hallway outside Classrooms 2 -6	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	drop down ceiling tiles
1	1	Hallway outside Classrooms 2 -6	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	1	Hallway outside Classrooms 8 -11	yes	W1	Brick	Blue	Chipping	15	18	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	1	Hallway outside Classrooms 8 -11	yes	W2	Plaster	Tan	Flaking	27	29.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	1	Hallway outside Classrooms 8 -11	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A	Window sill	Wood	White	Chipping	8	0.3	Negative	None	N/A	No	No	no	
1	1	Hallway outside Classrooms 8 -11	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A	Radiator	Metal	Grey	Chipping	84	7	Positive	None	N/A	No	No	no	includes all in the room
1	1	Hallway outside Classrooms 8 -11	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A	Baseboard	Wood	Brown	Chipping	5	1.4	Positive	None	N/A	No	No	no	
1	1	Hallway outside Classrooms 8 -11	yes	W3	Plaster	Tan	Flaking	10	28.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	1	Hallway outside Classrooms 8 -11	yes	W4	Plaster	Tan	Flaking	5	24	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	1	Hallway outside Classrooms 8 -11	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	drop down ceiling tiles
1	1	Hallway outside Classrooms 8 -11	yes	Floor	Wood	Brown	Chipping	20	0.1	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	1	Gym	yes	W1	Plaster	White	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	1	Gym	yes	W2	Plaster	White	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	1	Gym	yes	W3	Plaster	White	Flaking	4	0.3	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	1	Gym	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A	Baseboard	Wood	Brown	Chipping	12	0.3	Negative	None	N/A	No	No	no	includes all baseboards in room.
1	1	Gym	yes	W4	Plaster	White	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	1	Gym	yes	Ceiling	Concrete	White	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	1	Gym	yes	Floor	Wood	Brown	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	1	Gym Storage Closet	yes	W1	Brick	White	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	includes Wall 1,3,4
1	1	Gym Storage Closet	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door	Wood	Tan	Cracking	55	0.5	Negative	None	N/A	No	No	no	includes door frame and trim
1	1	Gym Storage Closet	yes	W2	Brick	White	Partially Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	1	Gym Storage Closet	yes	W3	Brick	White	Flaking	36	19.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	1	Gym Storage Closet	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A	Chair rail	Wood	White	Chipping	24	0.7	Negative	None	N/A	No	No	no	
1	1	Gym Storage Closet	yes	W4	Brick	White	Partially Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	1	Gym Storage Closet	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A	Window trim	Wood	White	Chipping	3	0.8	Negative	None	N/A	No	No	no	trim and sill window
1	1	Gym Storage Closet	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	1	Gym Storage Closet	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	1	Classroom 2	yes	W1	Plaster	White	Spalling	4	32	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	1	Classroom 2	yes	W2	Wood	White	Cracking	56	0.4	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	1	Classroom 2	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A	Columns	Wood	White	Cracking	28	8	Positive	None	N/A	No	No	no	
1	1	Classroom 2	yes	W3	Brick	Blue	Flaking	22	21.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	1	Classroom 2	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A	Window sill	Wood	White	Cracking	5	0.2	Negative	None	N/A	No	No	no	
1	1	Classroom 2	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A	Radiator	Metal	Grey	Flaking	25	5.2	Positive	None	N/A	No	No	no	
1	1	Classroom 2	yes	W4	Brick	Blue	Flaking	29	19.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	1	Classroom 2	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A	Window sill	Wood	White	Chipping	5	0.2	Negative	None	N/A	No	No	no	
1	1	Classroom 2	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A	Radiator	Metal	Grey	Flaking	45	5.9	Positive	None	N/A	No	No	no	includes all in room
1	1	Classroom 2	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A	Chair rail	Wood	White	Flaking	25	1.3	Positive	None	N/A	No	No	no	
1	1	Classroom 2	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	1	Classroom 2	yes	Floor	Wood	Brown	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	1	Classroom 2 Storage Closet	yes	W1	Brick	Tan	Cracking	66	19.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	1	Classroom 2 Storage Closet	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Wood	Tan	Chipping	40	0.4	Negative	None	N/A	No	No	no	
1	1	Classroom 2 Storage Closet	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door	Wood	Tan	Cracking	19	0.3	Negative	None	N/A	No	No	no	
1	1	Classroom 2 Storage Closet	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	Chair rail	Wood	Tan	Chipping	15	1.7	Positive	None	N/A	No	No	no	includes all in room
1	1	Classroom 2 Storage Closet	yes	W2	Brick	Tan	Chipping	51	21.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	includes window sill and trim
1	1	Classroom 2 Storage Closet	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A	Window trim	Wood	Tan	Cracking	7	13.7	Positive	None	N/A	No	No	no	
1	1	Classroom 2 Storage Closet	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A	Radiator	Metal	Grey	Chipping	3	2.4	Positive	None	N/A	No	No	no	
1	1	Classroom 2 Storage Closet	yes	W3	Brick	Tan	Partially Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	No	No	no	
1	1	Classroom 2 Storage Closet	yes	W4	Brick	Tan	Cracking	27	0.3	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	No	No	no	
1	1	Classroom 2 Storage Closet	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	No	No	no	
1	1	Classroom 2 Storage Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	No	No	no	
1	1	Classroom 3	yes	W1	Plaster	White	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	No	No	no	
1	1	Classroom 3	yes	W1	Brick	White	Chipping	27	0.4	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	1	Classroom 3	yes	W2	Wood	White	Cracking	20	8.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	1	Classroom 3	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A	Baseboard	Wood	White	Chipping	4	0.9	Positive	None	N/A	No	No	no	
1	1	Classroom 3	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A	Columns	Wood	White	Chipping	3	11.5	Positive	None	N/A	No	No	no	
1	1	Classroom 3	yes	W3	Brick	Tan	Flaking	24	22.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	1	Classroom 3	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A	Radiator	Metal	Grey	Flaking	13	0.6	Negative	None	N/A	No	No	no	
1	1	Classroom 3	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A	Window sill	Wood	Orange	Chipping	6	0.9	Negative	None	N/A	No	No	no	
1	1	Classroom 3	yes	W4	Wood	White	Chipping	64	1.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	1	Classroom 3	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	No	No	no	
1	1	Classroom 3	yes	Floor	Wood	Brown	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	No	No	no	
1	1	Classroom 3 Storage Closet	yes	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Classroom 3 Storage Closet	yes	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Classroom 3 Storage Closet	yes	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Classroom 3 Storage Closet	yes	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Classroom 3 Storage Closet	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Classroom 3 Storage Closet	yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Classroom 4	yes	W1	Plaster	Yellow	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	

School District of Philadelphia
Lead Safe Certification Inspection Report
Francis Scott Key School

		Name of Inspector: Charles Rhodes Inspection Company: Batta Environmental														Inspection Dates: 7/1-7/9/2019							
																ULCS# 2540							
Element	Form	On-Site Room Name	Student Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/negative)	Additional Component	Substrate Material	Color	Description of Paint and Plaster Damage	Additional Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Additional Component XRF (positive/negative)	Debris Present (describe location)	Quantity (sf)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Comments/ Description/ Notes
1	1	Classroom 4	yes	W1	N/A	N/A	Chipping	4	0.3	Negative	Chalkboard frame	Wood	Blue	Chipping	11	0.6	Negative	None	N/A	No	No	no	
1	1	Classroom 4	yes	W2	Wood	Yellow	Chipping	4	0.3	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	1	Classroom 4	yes	W3	Brick	Tan	Flaking	54	21.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	1	Classroom 4	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A	Radiator	Metal	Grey	Flaking	24	7	Positive	None	N/A	No	No	no	
1	1	Classroom 4	yes	W4	Wood	Yellow	Chipping	12	8.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	1	Classroom 4	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	1	Classroom 4	yes	Floor	Wood	Brown	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	1	Classroom 4 Storage Closet	yes	W1	Brick	White	Chipping	4	34	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	1	Classroom 4 Storage Closet	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Wood	White	Chipping	4	0.2	Negative	None	N/A	No	No	no	
1	1	Classroom 4 Storage Closet	yes	W2	Wood	White	Partially Inaccessible	4	34	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	1	Classroom 4 Storage Closet	yes	W3	Brick	White	Inaccessible	4	34	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	1	Classroom 4 Storage Closet	yes	W4	Wood	Brown	Partially Inaccessible	4	34	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	1	Classroom 4 Storage Closet	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	1	Classroom 4 Storage Closet	yes	Floor	Wood	Brown	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	1	Classroom 5	yes	W1	Plaster	Green	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	1	Classroom 5	yes	W2	Wood	Tan	Chipping	11	0.2	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	1	Classroom 5	yes	W3	Brick	Tan	Flaking	85	20.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	1	Classroom 5	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A	Radiator	Metal	Grey	Flaking	25	5.5	Positive	None	N/A	No	No	no	
1	1	Classroom 5	yes	W4	Wood	White	Chipping	23	0.7	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	1	Classroom 5	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	drop down ceiling tiles
1	1	Classroom 5	yes	Floor	Wood	Brown	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	1	Classroom 5 Storage Closet	yes	W1	Brick	Green	Chipping	22	23.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	includes readings for all Walls
1	1	Classroom 5 Storage Closet	yes	W2	Wood	Green	Partially Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	1	Classroom 5 Storage Closet	yes	W3	Brick	Green	Partially Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	1	Classroom 5 Storage Closet	yes	W4	Wood	Green	Partially Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	1	Classroom 5 Storage Closet	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	drop down ceiling tiles
1	1	Classroom 5 Storage Closet	yes	Floor	Wood	Brown	Partially Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	1	Classroom 6	yes	W1	Brick	Tan	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	1	Classroom 6	yes	W2	Brick	Tan	Cracking	15	18.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	1	Classroom 6	yes	W3	Brick	Tan	Cracking	82	20.3	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	1	Classroom 6	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A	Window trim	Metal	White	Chipping	7	0.6	Negative	None	N/A	No	No	no	
1	1	Classroom 6	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A	Radiator	Metal	Grey	Flaking	62	3.9	Positive	None	N/A	No	No	no	includes all radiators in room
1	1	Classroom 6	yes	W4	Brick	Tan	Cracking	29	0.3	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	1	Classroom 6	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	1	Classroom 6	yes	Floor	Wood	Brown	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	1	Classroom 6 Storage Closet	yes	W1	Brick	Green	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	1	Classroom 6 Storage Closet	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	Chair rail	Wood	Green	Chipping	27	0.4	Negative	None	N/A	No	No	no	includes all in room
1	1	Classroom 6 Storage Closet	yes	W2	Brick	Green	Cracking	12	28.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	1	Classroom 6 Storage Closet	yes	W3	Brick	Green	Cracking	12	28.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	1	Classroom 6 Storage Closet	yes	W4	Brick	Green	Cracking	5	25	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	1	Classroom 6 Storage Closet	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	1	Classroom 6 Storage Closet	yes	Floor	Wood	Brown	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	1	Counselor's Office - Front Area	yes	W1	Plaster	Red	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	1	Counselor's Office - Front Area	yes	W2	Plaster	Red	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	1	Counselor's Office - Front Area	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A	Built-in cabinet	Wood	Grey	Chipping	1	6.6	Positive	None	N/A	No	No	no	includes all in room
1	1	Counselor's Office - Front Area	yes	W3	Plaster	Red	Chipping	1	29.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	1	Counselor's Office - Front Area	yes	W4	Plaster	Red	Chipping	2	30.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	1	Counselor's Office - Front Area	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	drop down ceiling tiles
1	1	Counselor's Office - Front Area	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	drop down ceiling tiles
1	1	Counselor's Office - Left Rear Room	yes	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Counselor's Office - Left Rear Room	yes	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Counselor's Office - Left Rear Room	yes	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Counselor's Office - Left Rear Room	yes	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Counselor's Office - Left Rear Room	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Counselor's Office - Left Rear Room	yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Counselor's Office - Right Rear Room	yes	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Counselor's Office - Right Rear Room	yes	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Counselor's Office - Right Rear Room	yes	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Counselor's Office - Right Rear Room	yes	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Counselor's Office - Right Rear Room	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Counselor's Office - Right Rear Room	yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Staff Restroom across from Classroom 5	yes	W1	Plaster	White	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	1	Staff Restroom across from Classroom 5	yes	W2	Plaster	White	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	1	Staff Restroom across from Classroom 5	yes	W3	Plaster	White	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	1	Staff Restroom across from Classroom 5	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A	Radiator	Metal	Grey	Flaking	2	2.1	Positive	None	N/A	No	No	no	
1	1	Staff Restroom across from Classroom 5	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A	Baseboard	Wood	Brown	Chipping	9	4	Positive	None	N/A	No	No	no	includes all in room
1	1	Staff Restroom across from Classroom 5	yes	W4	Plaster	White	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	1	Staff Restroom across from Classroom 5	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	1	Staff Restroom across from Classroom 5	yes	Floor	Wood	Brown	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	1	Custodial Closet next to Counselor's Office	yes	W1	Brick	Tan	Chipping	4	16.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	1	Custodial Closet next to Counselor's Office	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	

School District of Philadelphia
Lead Safe Certification Inspection Report
Francis Scott Key School

Name of Inspector: Charles Rhodes
 Inspection Company: Batta Environmental

Inspection Dates: 7/1-7/9/2019
 ULCS# 2540

Element	Room	On-Site Room Name	Student Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/negative)	Additional Component	Substrate Material	Color	Description of Plaster and Paint Damage	Additional Component Quantity (sf)	XRF Reading (mg/cm2)	Additional Component XRF (positive/negative)	Debris Present (describe location)	Quantity (sf)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Comments/Description/Notes
1	1	Classroom 10	yes	W3	Plaster	White	Cracking	4	25.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	1	Classroom 10	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A	Chalkboard frame	Wood	White	Cracking	31	0.6	Negative	None	N/A	No	No	no	includes all chalkboards
1	1	Classroom 10	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A	Baseboard	Wood	Blue	Chipping	18	1.3	Positive	None	N/A	No	No	no	includes all baseboards
1	1	Classroom 10	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A	Radiator	Metal	Grey	Flaking	42	0.8	Negative	None	N/A	No	No	no	includes all radiators
1	1	Classroom 10	yes	W4	Plaster	White	Cracking	24	9.3	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	1	Classroom 10	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A	Window trim	Wood	Tan	Cracking	99	0.4	Negative	None	N/A	No	No	no	
1	1	Classroom 10	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	1	Classroom 10	yes	Floor	Wood	Brown	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	1	Classroom 10 Restroom	yes	W1	Plaster	Tan	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	1	Classroom 10 Restroom	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	Window trim	Wood	Tan	Cracking	19	2.3	Positive	None	N/A	No	No	no	
1	1	Classroom 10 Restroom	yes	W2	Plaster	Tan	Cracking	6	6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	1	Classroom 10 Restroom	yes	W3	Plaster	Tan	Cracking	8	23.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	1	Classroom 10 Restroom	yes	W3	Plaster	Brown	Flaking	26	6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	1	Classroom 10 Restroom	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	1	Classroom 10 Restroom	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A	Window trim	Wood	Tan	Cracking	10	0.3	Negative	None	N/A	No	No	no	
1	1	Classroom 10 Restroom	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A	Radiator	Metal	Grey	Cracking	6	12.6	Positive	None	N/A	No	No	no	
1	1	Classroom 10 Restroom	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	1	Classroom 10 Restroom	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	1	Classroom 10 Storage Closet	yes	W1	Plaster	Tan	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	1	Classroom 10 Storage Closet	yes	W2	Plaster	Tan	Cracking	42	23.3	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	1	Classroom 10 Storage Closet	yes	W3	Plaster	Tan	Cracking	6	6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	1	Classroom 10 Storage Closet	yes	W4	Plaster	Tan	Cracking	78	28.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	1	Classroom 10 Storage Closet	yes	Ceiling	Plaster	Tan	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	1	Classroom 10 Storage Closet	yes	Floor	Wood	Tan	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	1	Classroom 11	yes	W1	Plaster	White	Flaking	39	28.5338	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	1	Classroom 11	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	1	Classroom 11	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	Chalkboard frame	Wood	Pink	Chipping	1	0.3	Negative	None	N/A	No	No	no	
1	1	Classroom 11	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	Baseboard	Wood	White	Chipping	12	0.5	Negative	None	N/A	No	No	no	
1	1	Classroom 11	yes	W2	Plaster	White	Flaking	9	26.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	1	Classroom 11	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A	Chalkboard frame	Wood	Green	Cracking	3	0	Negative	None	N/A	No	No	no	
1	1	Classroom 11	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A	Baseboard	Wood	White	Chipping	7	0.5	Negative	None	N/A	No	No	no	
1	1	Classroom 11	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A	Radiator	Metal	Grey	Cracking	21	4.2	Positive	None	N/A	No	No	no	
1	1	Classroom 11	yes	W3	Plaster	White	Cracking	4	27.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	1	Classroom 11	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	1	Classroom 11	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A	Window trim	Wood	White	Cracking	63	0.6	Negative	None	N/A	No	No	no	
1	1	Classroom 11	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A	Radiator	Metal	Grey	Flaking	30	4.3	Positive	None	N/A	No	No	no	
1	1	Classroom 11	yes	W4	Plaster	Green	Flaking	32	24.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	1	Classroom 11	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A	Chalkboard frame	Wood	Blue	Chipping	22	0.2	Negative	None	N/A	No	No	no	
1	1	Classroom 11	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	1	Classroom 11	yes	Floor	Wood	Tan	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	1	Classroom 11 Restroom	yes	W1	Plaster	White	Cracking	2	23.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	1	Classroom 11 Restroom	yes	W2	Plaster	White	Cracking	4	26.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	1	Classroom 11 Restroom	yes	W3	Plaster	White	Chipping	11	23.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	yes	
1	1	Classroom 11 Restroom	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A	Chair rail	Wood	White	Chipping	3	2.2	Positive	None	N/A	No	No	no	
1	1	Classroom 11 Restroom	yes	W4	Plaster	White	Cracking	9	23.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	1	Classroom 11 Restroom	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	1	Classroom 11 Restroom	yes	Floor	Wood	Brown	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	1	Classroom 11 Storage Closet	yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Classroom 11 Storage Closet	yes	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Classroom 11 Storage Closet	yes	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Classroom 11 Storage Closet	yes	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Classroom 11 Storage Closet	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Classroom 11 Storage Closet	yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Vestibule to Exterior across from Music Classroom 9	yes	W1	Brick	Red	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	1	Vestibule to Exterior across from Music Classroom 9	yes	W2	Brick	Red	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	1	Vestibule to Exterior across from Music Classroom 9	yes	W3	Brick	Red	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	1	Vestibule to Exterior across from Music Classroom 9	yes	W4	Brick	Red	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	1	Vestibule to Exterior across from Music Classroom 9	yes	Ceiling	Concrete	White	Partially Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	1	Classroom 9	yes	Floor	Concrete	Black	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	2	Stairwell next to Classroom 12	yes	W1	Wood	Tan	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	2	Stairwell next to Classroom 12	yes	W2	Wood	Tan	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	2	Stairwell next to Classroom 12	yes	W2	Brick	Tan	Chipping	2	11.3	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	2	Stairwell next to Classroom 12	yes	W3	Plaster	Tan	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	2	Stairwell next to Classroom 12	yes	W3	Brick	Tan	Cracking	3	25.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	2	Stairwell next to Classroom 12	yes	W4	Plaster	Tan	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	2	Stairwell next to Classroom 12	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A	Hand rails	Wood	Grey	Chipping	20	0.3	Negative	None	N/A	No	No	no	
1	2	Stairwell next to Classroom 12	yes	Ceiling	Plaster	Tan	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	2	Stairwell next to Classroom 12	yes	Floor	Wood	Tan	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	2	Stairwell next to Classroom 18	yes	W1	Wood	Tan	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	2	Stairwell next to Classroom 18	yes	W2	Plaster	Tan	Chipping	7	35	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	2	Stairwell next to Classroom 18	yes	W3	Plaster	Tan	Chipping	72	35	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	2	Stairwell next to Classroom 18	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A	Window sill	Wood	Tan	Chipping	1	0.5	Negative	None	N/A	No	No	no	

School District of Philadelphia
Lead Safe Certification Inspection Report
Francis Scott Key School

Name of Inspector: Charles Rhodes
 Inspection Company: Batta Environmental

Inspection Dates: 7/1-7/9/2019
 ULCS# 2540

Element	Room	On-Site Room Name	Student Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/negative)	Additional Component	Substrate Material	Color	Description of Paint and Plaster Damage	Additional Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Additional Component XRF (positive/negative)	Debris Present (describe location)	Quantity (sf)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Comments/Description/ Notes
1	2	Classroom 12 Storage Closet	yes	W2	Wood	Tan	Chipping	1	0.4	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	No	No	no	
1	2	Classroom 12 Storage Closet	yes	W3	Brick	Tan	Cracking	103	23.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	No	No	no	
1	2	Classroom 12 Storage Closet	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A	Chair rail	Wood	Tan	Chipping	7	0.9	Positive	None	N/A	No	No	no	
1	2	Classroom 12 Storage Closet	yes	W4	Brick	Tan	Flaking	24	25.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	No	No	no	
1	2	Classroom 12 Storage Closet	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A	Window sill	Wood	Tan	Chipping	1	2.4	Positive	None	N/A	No	No	no	
1	2	Classroom 12 Storage Closet	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	No	No	no	
1	2	Classroom 12 Storage Closet	yes	Floor	Wood	Brown	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	No	No	no	
1	2	Classroom 13	yes	W1	Plaster	Tan	Flaking	7	36	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	No	No	no	
1	2	Classroom 13	yes	W2	Plaster	Tan	Cracking	27	34	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	No	No	no	
1	2	Classroom 13	yes	W2	Plaster	Green	Chipping	14	0.1	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	No	No	no	
1	2	Classroom 13	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A	Baseboard	Wood	White	Chipping	7	10.3	Positive	None	N/A	No	No	no	
1	2	Classroom 13	yes	W3	Brick	Tan	Flaking	15	21.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	No	No	no	
1	2	Classroom 13	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A	Window sill	Wood	Tan	Chipping	1	1.5	Positive	None	N/A	No	No	no	
1	2	Classroom 13	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A	Radiator	Metal	Grey	Flaking	25	0.7	Negative	None	N/A	No	No	no	
1	2	Classroom 13	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A	Baseboard	Wood	White	Chipping	5	15.3	Positive	None	N/A	No	No	no	
1	2	Classroom 13	yes	W4	Plaster	Tan	Cracking	10	37	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	No	No	no	
1	2	Classroom 13	yes	W4	Brick	Tan	Cracking	60	26.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	No	No	no	
1	2	Classroom 13	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A	Window sill	Wood	Tan	Chipping	8	0.5	Negative	None	N/A	No	No	no	
1	2	Classroom 13	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A	Radiator	Metal	Grey	Flaking	53	5.9	Positive	None	N/A	No	No	no	
1	2	Classroom 13	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A	Baseboard	Wood	White	Chipping	11	13.5	Positive	None	N/A	No	No	no	
1	2	Classroom 13	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	No	No	no	
1	2	Classroom 13	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	No	No	no	
1	2	Classroom 13 Storage Closet	yes	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access
1	2	Classroom 13 Storage Closet	yes	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access
1	2	Classroom 13 Storage Closet	yes	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access
1	2	Classroom 13 Storage Closet	yes	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access
1	2	Classroom 13 Storage Closet	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access
1	2	Classroom 13 Storage Closet	yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access
1	2	Library	yes	W1	Plaster	Tan	Chipping	2	0.1	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	No	No	no	
1	2	Library	yes	W2	Plaster	Tan	Chipping	21	-0.1	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	No	No	no	
1	2	Library	yes	W3	Plaster	Tan	Chipping	2	36	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	No	No	no	
1	2	Library	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A	Window sill	Wood	Tan	Chipping	3	0.5	Negative	None	N/A	No	No	no	
1	2	Library	yes	W4	Plaster	Tan	Flaking	21	34	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	No	No	no	
1	2	Library	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	No	No	no	
1	2	Library	yes	Floor	Wood	Brown	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	No	No	no	
1	2	Library Office	yes	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access
1	2	Library Office	yes	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access
1	2	Library Office	yes	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access
1	2	Library Office	yes	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access
1	2	Library Office	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access
1	2	Library Office	yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access
1	2	Library Storage Closet	yes	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access
1	2	Library Storage Closet	yes	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access
1	2	Library Storage Closet	yes	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access
1	2	Library Storage Closet	yes	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access
1	2	Library Storage Closet	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access
1	2	Library Storage Closet	yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access
1	2	Nurse's Office	yes	W1	Plaster	Tan	Cracking	4	39	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	No	No	no	
1	2	Nurse's Office	yes	W2	Plaster	Tan	Chipping	5	39	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	No	No	no	
1	2	Nurse's Office	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	No	No	no	
1	2	Nurse's Office	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A	Radiator	Metal	Grey	Flaking	44	7.5	Positive	None	N/A	No	No	no	
1	2	Nurse's Office	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A	Window trim	Wood	Tan	Cracking	19	4.7	Positive	None	N/A	No	No	no	
1	2	Nurse's Office	yes	W4	Plaster	Tan	Cracking	1	11.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	No	No	no	
1	2	Nurse's Office	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A	Chair rail	Wood	Yellow	Chipping	1	7.7	Positive	None	N/A	No	No	no	
1	2	Nurse's Office	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A	Baseboard	Wood	Black	Cracking	7	0.7	Positive	None	N/A	No	No	no	
1	2	Nurse's Office	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	No	No	no	
1	2	Nurse's Office	no	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	No	No	no	
1	2	Custodial Closet next to Nurse's Office	no	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access
1	2	Custodial Closet next to Nurse's Office	no	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access
1	2	Custodial Closet next to Nurse's Office	no	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access
1	2	Custodial Closet next to Nurse's Office	no	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access
1	2	Custodial Closet next to Nurse's Office	no	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access
1	2	Custodial Closet next to Nurse's Office	no	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access
1	2	Book Closet next to Staff Restroom across from Classroom 16	yes	W1	Brick	Tan	Chipping	5	0.2	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	No	No	no	
1	2	Book Closet next to Staff Restroom across from Classroom 16	yes	W2	Brick	Tan	Chipping	2	0.2	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	No	No	no	
1	2	Book Closet next to Staff Restroom across from Classroom 16	yes	W3	Brick	Tan	Chipping	3	0.1	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	No	No	no	
1	2	Book Closet next to Staff Restroom across from Classroom 16	yes	W4	Brick	Tan	Chipping	1	0.1	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	No	No	no	
1	2	Book Closet next to Staff Restroom across from Classroom 16	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A	Built-in cabinet	Wood	Grey	Chipping	20	0	Negative	None	N/A	No	No	no	
1	2	Book Closet next to Staff Restroom across from Classroom 16	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	No	No	no	
1	2	Book Closet next to Staff Restroom across from Classroom 16	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	No	No	no	
1	2	Classroom 16	yes	W1	Plaster	Blue	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	No	No	no	

School District of Philadelphia
Lead Safe Certification Inspection Report
Francis Scott Key School

Name of Inspector: Charles Rhodes
 Inspection Company: Batta Environmental

Inspection Dates: 7/1-7/9/2019
 ULCS# 2540

Element	Floor	On-Site Room Name	Student Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/negative)	Additional Component	Substrate Material	Color	Description of Paint and Plaster Damage	Additional Component Quantity (sf)	XRF Reading (mg/cm2)	Additional Component XRF (positive/negative)	Debris Present (describe location)	Quantity (sf)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Comments/ Description/ Notes
1	2	Classroom 16	yes	W1	N/A	N/A	Chipping	34	0.6	Negative	Chalkboard frame	Wood	Grey	Chipping	3	0.7	Positive	None	N/A	No	No	no	
1	2	Classroom 16	yes	W2	Wood	Tan	Chipping	5	35	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	2	Classroom 16	yes	W3	Plaster	Blue	Flaking	26	21.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	2	Classroom 16	yes	W3	Brick	Tan	Flaking	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	2	Classroom 16	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A	Radiator	Metal	Grey	Flaking	24	5.8	Positive	None	N/A	No	No	no	
1	2	Classroom 16	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A	Window trim	Wood	Tan	Chipping	1	0.7	Negative	None	N/A	No	No	no	
1	2	Classroom 16	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	2	Classroom 16	yes	W4	Plaster	N/A	N/A	N/A	N/A	N/A	Baseboard	Wood	Tan	Chipping	4	9.6	Positive	None	N/A	No	No	no	
1	2	Classroom 16	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	2	Classroom 16	yes	Floor	Wood	Brown	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	2	Classroom 16 Storage Closet	yes	W1	Brick	Green	Cracking	4	27.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	2	Classroom 16 Storage Closet	yes	W2	Plaster	Green	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	2	Classroom 16 Storage Closet	yes	W3	Brick	Green	Cracking	17	22.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	2	Classroom 16 Storage Closet	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	2	Classroom 16 Storage Closet	yes	W4	Wood	Tan	Chipping	1	0.3	Negative	Chair rail	Wood	Green	Chipping	18	2.7	Positive	None	N/A	No	No	no	
1	2	Classroom 16 Storage Closet	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	2	Classroom 16 Storage Closet	yes	Floor	Wood	Brown	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	2	Classroom 17	yes	W1	Plaster	Tan	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	2	Classroom 17	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	Baseboard	Wood	Tan	Chipping	8	14.4	Positive	None	N/A	No	No	no	
1	2	Classroom 17	yes	W2	Brick	Tan	Flaking	30	33	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	2	Classroom 17	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A	Chalkboard frame	Wood	Green	Flaking	50	9.2	Positive	None	N/A	No	No	no	
1	2	Classroom 17	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A	Radiator	Metal	Grey	Flaking	30	14.6	Positive	None	N/A	No	No	no	
1	2	Classroom 17	yes	W3	Brick	Tan	Flaking	72	37.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	2	Classroom 17	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A	Radiator	Metal	Grey	Flaking	24	0.3	Negative	None	N/A	No	No	no	
1	2	Classroom 17	yes	W4	Wood	Tan	Cracking	3	0.5	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	2	Classroom 17	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	2	Classroom 17	yes	Floor	Wood	Brown	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	2	Classroom 17 Storage Closet	yes	W1	Brick	Tan	Chipping	3	25.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	2	Classroom 17 Storage Closet	yes	W2	Wood	Tan	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	2	Classroom 17 Storage Closet	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Wood	Tan	Cracking	1	0.6	Negative	None	N/A	No	No	no	
1	2	Classroom 17 Storage Closet	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A	Door	Wood	Tan	Chipping	1	0.4	Negative	None	N/A	No	No	no	
1	2	Classroom 17 Storage Closet	yes	W3	Brick	Tan	Chipping	2	25.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	2	Classroom 17 Storage Closet	yes	W4	Brick	Tan	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	2	Classroom 17 Storage Closet	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	2	Classroom 17 Storage Closet	yes	Floor	Wood	Brown	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	2	Staff Restroom across from Classroom 16	yes	W1	Plaster	Tan	Cracking	1	37	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	2	Staff Restroom across from Classroom 16	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door	Wood	Tan	Chipping	19	0.2	Negative	None	N/A	No	No	no	door and frame
1	2	Staff Restroom across from Classroom 16	yes	W2	Plaster	Tan	Spalling	3	36	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	2	Staff Restroom across from Classroom 16	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A	Baseboard	Wood	Brown	Chipping	20	9	Positive	None	N/A	No	No	no	includes all in the room
1	2	Staff Restroom across from Classroom 16	yes	W3	Plaster	Tan	Flaking	9	18.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	2	Staff Restroom across from Classroom 16	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A	Radiator	Metal	Grey	Flaking	5	5.5	Positive	None	N/A	No	No	no	
1	2	Staff Restroom across from Classroom 16	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A	Window frame	Wood	Tan	Cracking	1	1.1	Positive	None	N/A	No	No	no	
1	2	Staff Restroom across from Classroom 16	yes	W4	Plaster	Tan	Chipping	1	18.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	2	Staff Restroom across from Classroom 16	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	2	Staff Restroom across from Classroom 16	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	2	Classroom 18	yes	W1	Plaster	Tan	Chipping	9	28.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	2	Classroom 18	yes	W2	Plaster	Tan	Chipping	6	0.2	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	2	Classroom 18	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A	Chalkboard frame	Wood	Tan	Cracking	12	0.6	Negative	None	N/A	No	No	no	
1	2	Classroom 18	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A	Baseboard	Wood	Tan	Cracking	3	0.2	Negative	None	N/A	No	No	no	
1	2	Classroom 18	yes	W3	Plaster	Tan	Flaking	17	20.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	2	Classroom 18	yes	W4	Plaster	Tan	Flaking	107	28.3	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	2	Classroom 18	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A	Radiator	Metal	Grey	Flaking	45	4.6	Positive	None	N/A	No	No	no	
1	2	Classroom 18	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A	Window trim	Wood	Tan	Cracking	24	0.5	Negative	None	N/A	No	No	no	
1	2	Classroom 18	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	2	Classroom 18	yes	Floor	Wood	Brown	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	2	Classroom 18 Storage Closet	yes	W1	Brick	Tan	Flaking	25	24.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	2	Classroom 18 Storage Closet	yes	W2	Brick	Tan	Flaking	48	19.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	2	Classroom 18 Storage Closet	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A	Window sill	Wood	Tan	Cracking	3	0.5	Negative	None	N/A	No	No	no	
1	2	Classroom 18 Storage Closet	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A	Window trim	Wood	Tan	Cracking	3	0.5	Negative	None	N/A	No	No	no	
1	2	Classroom 18 Storage Closet	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A	Radiator	Metal	Grey	Flaking	5	1	Positive	None	N/A	No	No	no	
1	2	Classroom 18 Storage Closet	yes	W3	Brick	Tan	Cracking	3	21.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	2	Classroom 18 Storage Closet	yes	W4	Wood	Tan	Cracking	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	2	Classroom 18 Storage Closet	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	2	Classroom 18 Storage Closet	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A	Door Frame	Wood	Tan	Cracking	9	0.5	Negative	None	N/A	No	No	no	
1	2	Classroom 19	yes	W1	Plaster	Tan	Spalling	8	31	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	2	Classroom 19	yes	W2	Plaster	Blue	Cracking	6	19.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	2	Classroom 19	yes	W3	Plaster	Tan	Flaking	45	31	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	2	Classroom 19	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A	Window trim	Wood	Tan	Cracking	24	0.6	Negative	None	N/A	No	No	no	
1	2	Classroom 19	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A	Radiator	Metal	Grey	Flaking	27	7.6	Positive	None	N/A	No	No	no	
1	2	Classroom 19	yes	W4	Plaster	Tan	Cracking	12	0.1	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	2	Classroom 19	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A	Radiator	Metal	Grey	Flaking	24	7.4	Positive	None	N/A	No	No	no	
1	2	Classroom 19	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	2	Classroom 19	yes	Floor	Wood	Brown	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	2	Classroom 19 Storage Closet	yes	W1	Plaster	Tan	Cracking	24	24.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	2	Classroom 19 Storage Closet	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	Window frame	Wood	Tan	Cracking	33	0.3	Negative	None	N/A	No	No	no	
1	2	Classroom 19 Storage Closet	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Wood	Tan	Cracking	21								

School District of Philadelphia
Lead Safe Certification Inspection Report
Francis Scott Key School

Name of Inspector: Charles Rhodes
 Inspection Company: Batta Environmental

Inspection Dates: 7/1-7/9/2019
 ULCS# 2540

Element	Room	On-Site Room Name	Student Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/negative)	Additional Component	Substrate Material	Color	Description of Paint and Plaster Damage	Additional Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Additional Component XRF (positive/negative)	Debris Present (describe location)	Quantity (sf)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Comments/ Description/ Notes
1	2	Classroom 19 Storage Closet	yes	W2	Plaster	Tan	Cracking	6	22.7	Positive	N/A	N/A	N/A	Cracking	7	23.2	Positive	N/A	N/A	No	No	no	
1	2	Classroom 19 Storage Closet	yes	W3	Plaster	Tan	Cracking	1	1.8	Positive	N/A	N/A	N/A	Cracking	1	1.8	Positive	N/A	N/A	No	No	no	
1	2	Classroom 19 Storage Closet	yes	W4	Plaster	Tan	Cracking	N/A	N/A	N/A	N/A	N/A	N/A	Cracking	20	0.3	Negative	None	N/A	No	No	no	
1	2	Classroom 19 Storage Closet	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A	Window trim	Wood	Tan	Cracking	4	1.6	Positive	None	N/A	No	No	no	
1	2	Classroom 19 Storage Closet	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A	Radiator	Metal	Grey	Flaking	27	5.5	Positive	None	N/A	No	No	no	
1	2	Classroom 19 Storage Closet	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	2	Classroom 19 Storage Closet	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	2	Classroom 20	yes	W1	Plaster	Tan	Chipping	16	29.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	2	Classroom 20	yes	W2	Plaster	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	2	Classroom 20	yes	W3	Plaster	Tan	Flaking	86	22.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	2	Classroom 20	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A	Window trim	Wood	Tan	Cracking	45	0.4	Negative	None	N/A	No	No	no	
1	2	Classroom 20	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A	Radiator	Metal	Grey	Flaking	27	5.5	Positive	None	N/A	No	No	no	
1	2	Classroom 20	yes	W4	Plaster	Tan	Alligatoring	21	26.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	2	Classroom 20	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	2	Classroom 20	yes	Floor	Wood	Brown	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	2	Classroom 20 Storage Closet	yes	W1	Plaster	Tan	Chipping	45	25.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	2	Classroom 20 Storage Closet	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Wood	Tan	Cracking	33	0.5	Negative	None	N/A	No	No	no	
1	2	Classroom 20 Storage Closet	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door	Wood	Tan	Cracking	16	0.3	Negative	None	N/A	No	No	no	
1	2	Classroom 20 Storage Closet	yes	W2	Plaster	Tan	Cracking	12	27.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	2	Classroom 20 Storage Closet	yes	W3	Plaster	Tan	Cracking	54	27.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	2	Classroom 20 Storage Closet	yes	W4	Plaster	Tan	Cracking	28	24.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	2	Classroom 20 Storage Closet	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A	Window trim	Wood	Tan	Cracking	11	1	Positive	None	N/A	No	No	no	
1	2	Classroom 20 Storage Closet	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A	Radiator	Metal	Grey	Flaking	8	3.5	Positive	None	N/A	No	No	no	
1	2	Classroom 20 Storage Closet	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	2	Classroom 20 Storage Closet	yes	Floor	Wood	Brown	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	2	Classroom 22	yes	W1	Plaster	Tan	Cracking	1	23	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	2	Classroom 22	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	Chalkboard frame	Wood	Tan	Cracking	8	0.6	Negative	None	N/A	No	No	no	
1	2	Classroom 22	yes	W2	Plaster	Tan	Flaking	49	27.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	2	Classroom 22	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A	Chalkboard frame	Wood	Tan	Chipping	6	0.2	Negative	None	N/A	No	No	no	
1	2	Classroom 22	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A	Radiator	Metal	Grey	Flaking	25	7.8	Positive	None	N/A	No	No	no	
1	2	Classroom 22	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A	Baseboard	Wood	Tan	Chipping	8	0.3	Negative	None	N/A	No	No	no	
1	2	Classroom 22	yes	W3	Plaster	Tan	Cracking	98	34	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	2	Classroom 22	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A	Window trim	Wood	Tan	Flaking	24	0.4	Negative	None	N/A	No	No	no	
1	2	Classroom 22	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A	Radiator	Metal	Grey	Flaking	27	5.6	Positive	None	N/A	No	No	no	
1	2	Classroom 22	yes	W4	Plaster	Tan	Flaking	43	24.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	2	Classroom 22	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A	Chalkboard frame	Wood	Tan	Chipping	3	0.5	Negative	None	N/A	No	No	no	
1	2	Classroom 22	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	2	Classroom 22	yes	Floor	Wood	Brown	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	2	Classroom 22 Storage Closet	yes	W1	Plaster	Tan	Cracking	33	25.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	2	Classroom 22 Storage Closet	yes	W2	Plaster	Tan	Moisture Damage	33	27.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	2	Classroom 22 Storage Closet	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A	Window trim	Wood	Tan	Chipping	19	0.6	Negative	None	N/A	No	No	no	
1	2	Classroom 22 Storage Closet	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A	Radiator	Metal	Grey	Flaking	9	1.6	Positive	None	N/A	No	No	no	
1	2	Classroom 22 Storage Closet	yes	W3	Plaster	Tan	Chipping	8	28.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	2	Classroom 22 Storage Closet	yes	W4	Wood	Tan	Cracking	16	0.2	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	2	Classroom 22 Storage Closet	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	2	Classroom 22 Storage Closet	yes	Floor	Wood	Brown	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	2	Classroom 21	yes	W1	Plaster	Tan	Chipping	4	26.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	2	Classroom 21	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	Chalkboard frame	Wood	Blue	Chipping	16	0.5	Negative	None	N/A	No	No	no	
1	2	Classroom 21	yes	W2	Plaster	Tan	Chipping	2	30	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	2	Classroom 21	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A	Chalkboard frame	Wood	Blue	Chipping	6	0.8	Positive	None	N/A	No	No	no	
1	2	Classroom 21	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A	Chalk ledge	Wood	Tan	Chipping	16	0.4	Negative	None	N/A	No	No	no	
1	2	Classroom 21	yes	W3	Plaster	Tan	Flaking	20	24.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	2	Classroom 21	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A	Radiator	Metal	Grey	Chipping	20	4	Positive	None	N/A	No	No	no	
1	2	Classroom 21	yes	W4	Plaster	Tan	Flaking	75	28.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	2	Classroom 21	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A	Radiator	Metal	Grey	Chipping	30	4.2	Positive	None	N/A	No	No	no	
1	2	Classroom 21	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	2	Classroom 22	yes	Floor	Wood	Tan	Cracking	70	27.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	2	Classroom 21 Storage Closet	yes	W1	Plaster	Tan	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	2	Classroom 21 Storage Closet	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Wood	Tan	Cracking	30	0.4	Negative	None	N/A	No	No	no	
1	2	Classroom 21 Storage Closet	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door	Wood	Tan	Cracking	13	0.3	Negative	None	N/A	No	No	no	
1	2	Classroom 21 Storage Closet	yes	W2	Wood	Tan	Chipping	6	0.4	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	2	Classroom 21 Storage Closet	yes	W3	Plaster	Tan	Chipping	72	33	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	2	Classroom 21 Storage Closet	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A	Chair rail	Wood	Tan	Chipping	6	0.5	Negative	None	N/A	No	No	no	
1	2	Classroom 21 Storage Closet	yes	W4	Plaster	Tan	Flaking	15	25.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	2	Classroom 21 Storage Closet	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A	Window trim	Wood	Tan	Cracking	23	0.6	Negative	None	N/A	No	No	no	
1	2	Classroom 21 Storage Closet	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A	Radiator	Metal	Grey	Flaking	11	5.6	Positive	None	N/A	No	No	no	
1	2	Classroom 21 Storage Closet	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	2	Classroom 21 Storage Closet	yes	Floor	Wood	Brown	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	3	Stairwell next to Classroom 23	yes	W1	Wood	Brown	Chipping	2	0.2	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	3	Stairwell next to Classroom 23	yes	W2	Brick	Tan	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	3	Stairwell next to Classroom 23	yes	W3	Brick	Tan	Chipping	1	23.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	3	Stairwell next to Classroom 23	yes	W3	Brick	Tan	Chipping	1	35	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	3	Stairwell next to Classroom 23	yes	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	Chair rail	Wood	Tan	Chipping	1	1.1	Positive	None	N/A	No	No	no	
1	3	Stairwell next to Classroom 23	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	Hand rails	Metal	Black	Chipping	10	0.2	Negative	None	N/A	No	No	no	
1	3	Stairwell next to Classroom 29	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	Stair tread	Concrete	Black	Chipping	1	0	Negative	None	N/A	No	No	no	
1	3	Stairwell next to Classroom 29	yes	W1	Wood	Brown	None																

School District of Philadelphia
Lead Safe Certification Inspection Report
Francis Scott Key School

Name of Inspector: Charles Rhodes
 Inspection Company: Batta Environmental

Inspection Dates: 7/1-7/9/2019
 ULCS# 2540

Element	FLOOR	On-Site Room Name	Student Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/negative)	Additional Component	Substrate Material	Color	Description of Paint and Plaster Damage	Additional Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Additional Component XRF (positive/negative)	Debris Present (describe location)	Quantity (sf)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Comments/Description/ Notes
1	3	Stairwell next to Classroom 29	yes	W1	N/A	N/A	Chipping	1	32	Positive	N/A	N/A	Brown	Chipping	2	0.1	Negative	None	N/A	No	No	no	
1	3	Stairwell next to Classroom 29	yes	W2	Plaster	N/A	Chipping	1	32	Positive	N/A	N/A	N/A	Chipping	3	N/A	N/A	None	N/A	No	No	no	
1	3	Stairwell next to Classroom 29	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A	Chair rail	Wood	Tan	Chipping	1	1.2	Positive	None	N/A	No	No	no	
1	3	Stairwell next to Classroom 29	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A	Hand rails	Wood	Grey	Chipping	10	0	Negative	None	N/A	No	No	no	
1	3	Stairwell next to Classroom 29	yes	W3	Plaster	Tan	Cracking	48	36	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	3	Stairwell next to Classroom 29	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A	Baseboard	Wood	Black	Chipping	5	2.6	Positive	None	N/A	No	No	no	
1	3	Stairwell next to Classroom 29	yes	W4	Brick	Tan	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	3	Stairwell next to Classroom 29	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A	Hand rails	Plaster	Black	Chipping	10	0.1	Negative	None	N/A	No	No	no	
1	3	Stairwell next to Classroom 29	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A	Newel posts	Metal	Black	Chipping	5	2.5	Positive	None	N/A	No	No	no	
1	3	Stairwell next to Classroom 29	yes	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	3	Stairwell next to Classroom 29	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	3	Fire Tower # 1	yes	W1	Brick	Tan	Chipping	300	44	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	3	Fire Tower # 1	yes	W2	Brick	Tan	Chipping	230	33	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	3	Fire Tower # 1	yes	W3	Brick	Tan	Chipping	280	9.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	3	Fire Tower # 1	yes	W4	Brick	Tan	Chipping	170	39	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	3	Fire Tower # 1	yes	Ceiling	Concrete	White	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	3	Fire Tower # 1	yes	Floor	Concrete	Brown	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	3	Fire Tower # 2	yes	W1	Brick	Tan	Chipping	250	42	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	3	Fire Tower # 2	yes	W2	Brick	Tan	Chipping	170	19.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	3	Fire Tower # 2	yes	W3	Brick	Tan	Chipping	220	3.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	3	Fire Tower # 2	yes	W4	Brick	Tan	Chipping	130	1.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	3	Fire Tower # 2	yes	Ceiling	Concrete	White	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	3	Fire Tower # 2	yes	Floor	Concrete	Brown	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	3	Fire Tower # 3	yes	W1	Brick	Tan	Cracking	1	13.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	3	Fire Tower # 3	yes	W2	Brick	Tan	Cracking	2	10.3	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	3	Fire Tower # 3	yes	W3	Brick	Tan	Flaking	19	16.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	3	Fire Tower # 3	yes	W4	Brick	Tan	Chipping	5	17.3	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	3	Fire Tower # 3	yes	Ceiling	Concrete	White	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	3	Fire Tower # 3	yes	Floor	Concrete	Brown	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	3	Fire Tower # 4	yes	W1	Brick	Tan	Flaking	9	13.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	3	Fire Tower # 4	yes	W2	Brick	Tan	Chipping	4	17.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	3	Fire Tower # 4	yes	W3	Brick	Tan	Chipping	8	16	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	3	Fire Tower # 4	yes	W4	Brick	Tan	Chipping	8	13.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	3	Fire Tower # 4	yes	Ceiling	Concrete	White	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	3	Fire Tower # 4	yes	Floor	Concrete	Brown	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	3	Hallway outside Classrooms 23 - 28	yes	W1	Plaster	Tan	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	3	Hallway outside Classrooms 23 - 28	yes	W2	Plaster	Tan	Chipping	7	37	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	3	Hallway outside Classrooms 23 - 28	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A	Radiator	Metal	Grey	Chipping	15	19.4	Positive	None	N/A	No	No	no	
1	3	Hallway outside Classrooms 23 - 28	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A	Crown molding	Wood	Black	Chipping	7	1.1	Positive	None	N/A	No	No	no	
1	3	Hallway outside Classrooms 23 - 28	yes	W3	Plaster	Tan	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	3	Hallway outside Classrooms 23 - 28	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A	Crown molding	Wood	Black	Chipping	23	1.1	Positive	None	N/A	No	No	no	
1	3	Hallway outside Classrooms 23 - 28	yes	W4	Plaster	Tan	Chipping	3	36	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	3	Hallway outside Classrooms 23 - 28	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	3	Hallway outside Classrooms 23 - 28	yes	Floor	Wood	Brown	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	3	Hallway outside Classrooms 29 - 33	yes	W1	Plaster	Tan	Chipping	1	35	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	3	Hallway outside Classrooms 29 - 33	yes	W2	Plaster	Tan	Chipping	36	14.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	3	Hallway outside Classrooms 29 - 33	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A	Radiator	Metal	Grey	Flaking	42	5.6	Positive	None	N/A	No	No	no	
1	3	Hallway outside Classrooms 29 - 33	yes	W3	Plaster	Tan	Chipping	5	12.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	3	Hallway outside Classrooms 29 - 33	yes	W4	Plaster	Tan	Chipping	20	13.3	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	3	Hallway outside Classrooms 29 - 33	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	3	Hallway outside Classrooms 29 - 33	yes	Floor	Wood	Brown	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	3	Classroom 23	yes	W1	Plaster	Tan	Cracking	19	34	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	3	Classroom 23	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Wood	Tan	Cracking	17	0.3	Negative	None	N/A	No	No	no	
1	3	Classroom 23	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	Chalkboard frame	Wood	Tan	Cracking	13	0.4	Negative	None	N/A	No	No	no	
1	3	Classroom 23	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	Baseboard	Wood	Tan	Chipping	15	0.3	Negative	None	N/A	No	No	no	
1	3	Classroom 23	yes	W2	Plaster	Tan	Flaking	148	8.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	3	Classroom 23	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A	Radiator	Metal	Grey	Flaking	44	1.1	Positive	None	N/A	No	No	no	
1	3	Classroom 23	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A	Window sill	Wood	Tan	Cracking	9	0.4	Negative	None	N/A	No	No	no	
1	3	Classroom 23	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A	Window trim	Wood	Tan	Cracking	29	0.5	Negative	None	N/A	No	No	no	
1	3	Classroom 23	yes	W3	Plaster	Tan	Flaking	108	26.3	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	3	Classroom 23	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A	Radiator	Metal	Grey	Flaking	30	2.2	Positive	None	N/A	No	No	no	
1	3	Classroom 23	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A	Window sill	Wood	Tan	Cracking	8	0.5	Negative	None	N/A	No	No	no	
1	3	Classroom 23	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A	Window trim	Wood	Tan	Cracking	28	0.4	Negative	None	N/A	No	No	no	
1	3	Classroom 23	yes	W4	Plaster	Tan	Chipping	83	28.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	3	Classroom 23	yes	W4	Plaster	Pink	Cracking	21	19.3	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	3	Classroom 23	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A	Chalkboard frame	Wood	Tan	Cracking	20	0.7	Negative	None	N/A	No	No	no	
1	3	Classroom 23	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	3	Classroom 23	yes	Floor	Wood	Brown	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	3	Classroom 23 Storage Closet	yes	W1	Brick	Black	Flaking	108	29.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	3	Classroom 23 Storage Closet	yes	W2	Wood	Tan	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	3	Classroom 23 Storage Closet	yes	W3	Brick	Tan	Flaking	240	35	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	3	Classroom 23 Storage Closet	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A	Chair rail	Wood	Tan	Chipping	45	0.7	Positive	None	N/A	No	No	no	
1	3	Classroom 23 Storage Closet	yes	W4	Brick	Tan	Flaking	90	2.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	3	Classroom 23 Storage Closet	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A	Window trim	Wood	Tan	Chipping	12	0.4	Negative	None	N/A	No	No	no	
1	3	Classroom 23 Storage Closet	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A	Window sill	Wood	Tan	Flaking	3	0.8	Positive	None	N/A	No	No	no	

School District of Philadelphia
Lead Safe Certification Inspection Report
Francis Scott Key School

Name of Inspector: Charles Rhodes
 Inspection Company: Batta Environmental

Inspection Dates: 7/1-7/9/2019
 ULCS# 2540

Element	Room	On-Site Room Name	Student Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/negative)	Additional Component	Substrate Material	Color	Description of Paint and Plaster Damage	Additional Component Quantity (sf)	XRF Reading (mg/cm2)	Additional Component XRF (positive/negative)	Debris Present (describe location)	Quantity (sf)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Comments/ Description/ Notes
1	3	Classroom 23 Storage Closet	yes	Floor	Wood	Brown	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	No	No	no
1	3	Classroom 24	yes	W1	Flaster	Blue	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	no
1	3	Classroom 24	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	Chalkboard frame	Wood	Tan	Chipping	13	1.6	Positive	None	N/A	No	No	no	
1	3	Classroom 24	yes	W2	Wood	Purple	Flaking	33	0.2	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	3	Classroom 24	yes	W3	Plaster	Blue	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	3	Classroom 24	yes	W3	Brick	Tan	Flaking	54	23.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	3	Classroom 24	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A	Window trim	Wood	Tan	Flaking	10	0.3	Negative	None	N/A	No	No	no	
1	3	Classroom 24	yes	W4	Plaster	Blue	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	3	Classroom 24	yes	W4	Brick	Tan	Flaking	60	24.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	3	Classroom 24	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A	Window sill	Wood	Tan	Cracking	8	0.7	Positive	None	N/A	No	No	no	
1	3	Classroom 24	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A	Window trim	Wood	Tan	Cracking	30	0.4	Negative	None	N/A	No	No	no	
1	3	Classroom 24	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A	Radiator	Metal	Grey	Cracking	56	0.7	Positive	None	N/A	No	No	no	
1	3	Classroom 24	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	3	Classroom 24	yes	Floor	Wood	Brown	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	3	Classroom 24 Storage Closet	yes	W1	Brick	Green	Cracking	53	25.3	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	3	Classroom 24 Storage Closet	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Wood	Green	Cracking	45	0.2	Negative	None	N/A	No	No	no	
1	3	Classroom 24 Storage Closet	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door	Wood	Green	Cracking	25	0.1	Negative	None	N/A	No	No	no	
1	3	Classroom 24 Storage Closet	yes	W2	Brick	Green	Cracking	72	21.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	3	Classroom 24 Storage Closet	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A	Window trim	Wood	Green	Cracking	24	0.3	Negative	None	N/A	No	No	no	
1	3	Classroom 24 Storage Closet	yes	W3	Brick	Green	Cracking	240	28.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	3	Classroom 24 Storage Closet	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A	Chair rail	Wood	Green	Cracking	42	1.1	Negative	None	N/A	No	No	no	
1	3	Classroom 24 Storage Closet	yes	W4	Brick	Green	Flaking	18	29.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	3	Classroom 24 Storage Closet	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Wood	White	Cracking	30	0.3	Negative	None	N/A	No	No	no	
1	3	Classroom 24 Storage Closet	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	3	Classroom 24 Storage Closet	yes	Floor	Wood	Brown	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	3	Classroom 25	yes	W1	Plaster	White	Cracking	10	36	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	3	Classroom 25	yes	W1	Brick	White	Flaking	5	20.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	3	Classroom 25	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	Chalkboard frame	Wood	Tan	Chipping	20	0.8	Negative	None	N/A	No	No	no	
1	3	Classroom 25	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	3	Classroom 25	yes	W2	Wood	White	Chipping	44	0.2	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	3	Classroom 25	yes	W3	Plaster	White	Flaking	75	35	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	3	Classroom 25	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A	Window sill	Wood	Tan	Cracking	18	0.6	Negative	None	N/A	No	No	no	
1	3	Classroom 25	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A	Window frame	Wood	Tan	Cracking	15	0.2	Negative	None	N/A	No	No	no	
1	3	Classroom 25	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A	Radiator	Metal	Grey	Flaking	39	0.5	Negative	None	N/A	No	No	no	
1	3	Classroom 25	yes	W3	Brick	White	Flaking	47	25.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	3	Classroom 25	yes	W4	Wood	White	Cracking	92	0.2	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	3	Classroom 25	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	3	Classroom 25	yes	Floor	Wood	Brown	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	3	Classroom 25 Storage Closet	yes	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access
1	3	Classroom 25 Storage Closet	yes	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access
1	3	Classroom 25 Storage Closet	yes	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access
1	3	Classroom 25 Storage Closet	yes	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access
1	3	Classroom 25 Storage Closet	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access
1	3	Classroom 25 Storage Closet	yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access
1	3	Classroom 26	yes	W1	Plaster	N/A	Chipping	5	34	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	3	Classroom 26	yes	W2	Wood	Tan	Chipping	69	0.2	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	3	Classroom 26	yes	W3	Plaster	Tan	Flaking	50	39	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	3	Classroom 26	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A	Window sill	Wood	Tan	Cracking	15	0.2	Negative	None	N/A	No	No	no	
1	3	Classroom 26	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A	Window trim	Wood	Tan	Cracking	9	0.4	Negative	None	N/A	No	No	no	
1	3	Classroom 26	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A	Radiator	Metal	Grey	Flaking	12	0.2	Negative	None	N/A	No	No	no	
1	3	Classroom 26	yes	W3	Brick	Tan	Flaking	14	22.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	3	Classroom 26	yes	W4	Wood	Brown	Chipping	54	1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	3	Classroom 26	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	3	Classroom 26	yes	Floor	Wood	Brown	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	3	Classroom 26 Storage Closet	yes	W1	Brick	Tan	Flaking	22	27.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	3	Classroom 26 Storage Closet	yes	W2	Wood	Tan	Cracking	43	0.2	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	3	Classroom 26 Storage Closet	yes	W3	Brick	Tan	Flaking	96	32	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	3	Classroom 26 Storage Closet	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A	Chair rail	Wood	Tan	Chipping	26	0.9	Positive	None	N/A	No	No	no	
1	3	Classroom 26 Storage Closet	yes	W4	Brick	Tan	Cracking	5	24.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	3	Classroom 26 Storage Closet	yes	Ceiling	Plaster	Tan	Flaking	14	11.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	3	Classroom 26 Storage Closet	yes	Floor	Wood	Brown	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	3	Classroom 27	yes	W1	Plaster	Tan	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	3	Classroom 27	yes	W2	Wood	Tan	Cracking	46	0.2	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	3	Classroom 27	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A	Chair rail	Wood	Tan	Chipping	1	0.4	Negative	None	N/A	No	No	no	
1	3	Classroom 27	yes	W3	Plaster	Tan	Cracking	38	30	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	3	Classroom 27	yes	W3	Brick	Tan	Flaking	78	22.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	3	Classroom 27	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A	Radiator	Metal	Grey	Flaking	40	1.8	Positive	None	N/A	No	No	no	
1	3	Classroom 27	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A	Window sill	Wood	Tan	Cracking	5	0.5	Negative	None	N/A	No	No	no	
1	3	Classroom 27	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A	Window trim	Wood	Tan	Cracking	27	1	Positive	None	N/A	No	No	no	
1	3	Classroom 27	yes	W4	Wood	Tan	Chipping	59	1.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	3	Classroom 27	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	3	Classroom 27	yes	Floor	Wood	Brown	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	3	Classroom 27 Storage Closet	yes	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access
1	3	Classroom 27 Storage Closet	yes	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access
1	3	Classroom 27 Storage Closet	yes	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access
1	3	Classroom 27 Storage Closet	yes	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access

School District of Philadelphia
Lead Safe Certification Inspection Report
Francis Scott Key School

Name of Inspector: Charles Rhodes
 Inspection Company: Batta Environmental

Inspection Dates: 7/1-7/9/2019
 ULCS# 2540

Element	Room	On-Site Room Name	Student Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/negative)	Additional Component	Substrate Material	Color	Description of Paint and Plaster Damage	Additional Component Quantity (sf)	XRF Reading (mg/cm2)	Additional Component XRF (positive/negative)	Debris Present (describe location)	Quantity (sf)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Comments/Description/ Notes
1	3	Classroom 27 Storage Closet	yes	Ceiling	No Access	No Access	No Access	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	3	Classroom 27 Storage Closet	yes	Floor	Wood	Brown	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	3	Classroom 28	yes	W1	Plaster	Tan	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	3	Classroom 28	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Wood	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	3	Classroom 28	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door	Wood	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	3	Classroom 28	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	Chalkboard frame	Wood	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	3	Classroom 28	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	Baseboard	Wood	Brown	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	3	Classroom 28	yes	W1	Brick	Grey	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	3	Classroom 28	yes	W2	Plaster	Tan	Flaking	14	33	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	3	Classroom 28	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A	Window sill	Wood	Tan	Cracking	3	0.3	Negative	None	N/A	No	No	no	
1	3	Classroom 28	yes	W2	Brick	Grey	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	3	Classroom 28	yes	W3	Plaster	Tan	Cracking	38	35	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	3	Classroom 28	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A	Radiator	Metal	Grey	Flaking	50	1.4	Positive	None	N/A	No	No	no	
1	3	Classroom 28	yes	W3	Brick	Grey	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	3	Classroom 28	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A	Chair rail	Wood	Tan	Chipping	2	1.2	Positive	None	N/A	No	No	no	
1	3	Classroom 28	yes	W4	Wood	White	Cracking	52	0.2	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	3	Classroom 28	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	3	Classroom 28	yes	Floor	Wood	Brown	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	3	Classroom 28 Storage Closet	yes	W1	Brick	Tan	Cracking	110	31	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	3	Classroom 28 Storage Closet	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door	Wood	Grey	Chipping	18	0.1	Negative	None	N/A	No	No	no	
1	3	Classroom 28 Storage Closet	yes	W2	Brick	Tan	Cracking	72	23.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	3	Classroom 28 Storage Closet	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Wood	Grey	Chipping	6	0	Negative	None	N/A	No	No	no	
1	3	Classroom 28 Storage Closet	yes	W3	Brick	Tan	Cracking	170	32	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	3	Classroom 28 Storage Closet	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A	Chair rail	Wood	Tan	Chipping	31	1	Positive	None	N/A	No	No	no	
1	3	Classroom 28 Storage Closet	yes	W4	Brick	Tan	Cracking	68	20	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	3	Classroom 28 Storage Closet	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A	Window trim	Wood	Tan	Chipping	10	0.3	Negative	None	N/A	No	No	no	
1	3	Classroom 28 Storage Closet	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	3	Classroom 28 Storage Closet	yes	Floor	Wood	Brown	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	3	Faculty Lounge next to Classroom 23	yes	W1	Plaster	White	Partially Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	3	Faculty Lounge next to Classroom 23	yes	W2	Plaster	White	Cracking	10	37	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	3	Faculty Lounge next to Classroom 23	yes	W3	Plaster	Pink	Flaking	16	13.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	3	Faculty Lounge next to Classroom 23	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A	Window sill	Wood	White	Cracking	13	0.3	Negative	None	N/A	No	No	no	
1	3	Faculty Lounge next to Classroom 23	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A	Radiator	Metal	Grey	Flaking	10	9.5	Positive	None	N/A	No	No	no	
1	3	Faculty Lounge next to Classroom 23	yes	W4	Brick	Tan	Cracking	14	2.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	3	Faculty Lounge next to Classroom 23	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	3	Faculty Lounge next to Classroom 23	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	3	Custodial Closet next to Faculty Lounge	no	W1	Brick	White	Cracking	1	0.1	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	3	Custodial Closet next to Faculty Lounge	no	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door	Wood	Blue	Chipping	3	0.1	Negative	None	N/A	No	No	no	
1	3	Custodial Closet next to Faculty Lounge	no	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Wood	White	Chipping	3	0.2	Negative	None	N/A	No	No	no	
1	3	Custodial Closet next to Faculty Lounge	no	W2	Brick	White	Cracking	14	0.1	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	3	Custodial Closet next to Faculty Lounge	no	W3	Brick	White	Cracking	15	0.1	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	3	Custodial Closet next to Faculty Lounge	no	W3	N/A	N/A	N/A	N/A	N/A	N/A	Built-in cabinet	Wood	Green	Cracking	72	36	Positive	None	N/A	No	No	no	
1	3	Custodial Closet next to Faculty Lounge	no	W4	Brick	White	Efflorescence	23	0.1	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	3	Custodial Closet next to Faculty Lounge	no	Ceiling	Plaster	White	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	3	Custodial Closet next to Faculty Lounge	no	Floor	Wood	Brown	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	3	Book Closet next to Staff Restroom across from Classroom 27	yes	W1	Brick	White	Spalling	6	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	3	Book Closet next to Staff Restroom across from Classroom 27	yes	W2	Brick	White	Spalling	17	0.1	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	3	Book Closet next to Staff Restroom across from Classroom 27	yes	W3	Brick	White	Flaking	38	0.1	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	3	Book Closet next to Staff Restroom across from Classroom 27	yes	W4	Brick	White	Flaking	14	0.2	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	3	Book Closet next to Staff Restroom across from Classroom 27	yes	Ceiling	Plaster	White	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	3	Book Closet next to Staff Restroom across from Classroom 27	yes	Floor	Wood	Brown	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	3	Staff Restroom across from Classroom 27	yes	W1	Plaster	Tan	Chipping	1	30	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	3	Staff Restroom across from Classroom 27	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door	Wood	Tan	Chipping	1	0.03	Negative	None	N/A	No	No	no	
1	3	Staff Restroom across from Classroom 27	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Wood	Tan	Chipping	1	0.02	Negative	None	N/A	No	No	no	
1	3	Staff Restroom across from Classroom 27	yes	W2	Plaster	Tan	Chipping	1	28.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	3	Staff Restroom across from Classroom 27	yes	W3	Plaster	Tan	Chipping	1	36	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	3	Staff Restroom across from Classroom 27	yes	W4	Plaster	Tan	Chipping	1	0.3	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	3	Staff Restroom across from Classroom 27	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	3	Staff Restroom across from Classroom 27	yes	Floor	Concrete	Tan	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	3	Art Classroom 29	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	Built-in cabinet	Brick	White	Chipping	4	26.9	Positive	None	N/A	No	No	no	
1	3	Art Classroom 29	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Wood	Tan	Chipping	4	0.3	Negative	None	N/A	No	No	no	
1	3	Art Classroom 29	yes	W1	Plaster	Tan	Chipping	6	5.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	3	Art Classroom 29	yes	W2	Plaster	Tan	Cracking	3	3.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	3	Art Classroom 29	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A	Baseboard	Wood	Tan	Chipping	25	0.2	Negative	None	N/A	No	No	no	
1	3	Art Classroom 29	yes	W3	Plaster	Tan	Cracking	3	0.1	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	3	Art Classroom 29	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A	Chalkboard frame	Wood	Tan	Cracking	1	2	Positive	None	N/A	No	No	no	
1	3	Art Classroom 29	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Wood	Tan	Cracking	15	0.2	Negative	None	N/A	No	No	no	
1	3	Art Classroom 29	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A	Door	Wood	Tan	Cracking	5	0	Negative	None	N/A	No	No	no	
1	3	Art Classroom 29	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A	Baseboard	Wood	Tan	Cracking	12	1.4	Positive	None	N/A	No	No	no	
1	3	Art Classroom 29	yes	W4	Plaster	Tan	Cracking	6	35	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	7 sq ft
1	3	Art Classroom 29	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A	Radiator	Metal	Grey	Cracking	26	1	Positive	None	N/A	No	No	no	

School District of Philadelphia
Lead Safe Certification Inspection Report
Francis Scott Key School

Name of Inspector: Charles Rhodes
 Inspection Company: Batta Environmental

Inspection Dates: 7/1-7/9/2019
 ULCS# 2540

Element	FLOOR	On-Site Room Name	Student Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/negative)	Additional Component	Substrate Material	Color	Description of Paint and Damage	Additional Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Additional Component XRF (positive/negative)	Debris Present (describe location)	Quantity (sf)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Comments/Description/Notes	
1	3	Art Classroom 29	yes	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Window trim	Wood	N/A	N/A	Negative	None	N/A	No	No	no	
1	3	Art Classroom 29	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	3	Art Classroom 29	yes	Floor	Concrete	Brown	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no		
1	3	Classroom 30	yes	W1	Plaster	Tan	Cracking	16	27.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no		
1	3	Classroom 30	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	Chalkboard frame	Wood	Tan	Chipping	12	0.2	Negative	None	N/A	No	No	no		
1	3	Classroom 30	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	Window trim	Wood	Tan	Chipping	1	0.2	Negative	None	N/A	No	No	no		
1	3	Classroom 30	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door	Wood	Blue	Chipping	1	0.2	Negative	None	N/A	No	No	no		
1	3	Classroom 30	yes	W2	Plaster	Tan	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no		
1	3	Classroom 30	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Wood	Tan	Flaking	12	0.1	Negative	None	N/A	No	No	no		
1	3	Classroom 30	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A	Door	Wood	Tan	Cracking	5	0	Negative	None	N/A	No	No	no		
1	3	Classroom 30	yes	W3	Plaster	Tan	Efflorescence	12	16.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no		
1	3	Classroom 30	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A	Window frame	Wood	Tan	Cracking	24	0.2	Negative	None	N/A	No	No	no		
1	3	Classroom 30	yes	W4	Plaster	Tan	Cracking	4	29.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no		
1	3	Classroom 30	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no		
1	3	Classroom 30	yes	Floor	Wood	Brown	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no		
1	3	Classroom 30 Storage Closet	yes	W1	Plaster	Tan	Cracking	120	20.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no		
1	3	Classroom 30 Storage Closet	yes	W2	Plaster	Tan	Cracking	18	21.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no		
1	3	Classroom 30 Storage Closet	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A	Door	Wood	Tan	Cracking	4	0.1	Negative	None	N/A	No	No	no		
1	3	Classroom 30 Storage Closet	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Wood	Tan	Cracking	5	0	Negative	None	N/A	No	No	no	broken window pane in door	
1	3	Classroom 30 Storage Closet	yes	W3	Plaster	Tan	Cracking	24	25.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no		
1	3	Classroom 30 Storage Closet	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A	Chair rail	Wood	Tan	Chipping	3	0.3	Negative	None	N/A	No	No	no		
1	3	Classroom 30 Storage Closet	yes	W4	Plaster	Tan	Cracking	12	23.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no		
1	3	Classroom 30 Storage Closet	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no		
1	3	Classroom 30 Storage Closet	yes	Floor	Wood	Brown	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no		
1	3	Classroom 31	yes	W1	Plaster	Tan	Cracking	33	30	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no		
1	3	Classroom 31	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	Chalkboard frame	Wood	White	Cracking	16	1.7	Positive	None	N/A	No	No	no		
1	3	Classroom 31	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	Baseboard	Wood	Tan	Chipping	16	0.5	Negative	None	N/A	No	No	no		
1	3	Classroom 31	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	Chair rail	Wood	Tan	Chipping	7	0.4	Negative	None	N/A	No	No	no		
1	3	Classroom 31	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door	Wood	Tan	Chipping	1	0.1	Negative	None	N/A	No	No	no		
1	3	Classroom 31	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door	Wood	Blue	Chipping	10	0.2	Negative	None	N/A	No	No	no		
1	3	Classroom 31	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Wood	Tan	Chipping	13	0.1	Negative	None	N/A	No	No	no		
1	3	Classroom 31	yes	W2	Plaster	Tan	Cracking	4	28.3	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no		
1	3	Classroom 31	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A	Chalkboard frame	Wood	Tan	Chipping	11	0.4	Negative	None	N/A	No	No	no		
1	3	Classroom 31	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A	Baseboard	Wood	Tan	Chipping	18	0.1	Negative	None	N/A	No	No	no		
1	3	Classroom 31	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A	Chair rail	Wood	Tan	Chipping	3	1.2	Positive	None	N/A	No	No	no		
1	3	Classroom 31	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Wood	Tan	Cracking	12	0.1	Negative	None	N/A	No	No	no		
1	3	Classroom 31	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A	Door	Wood	Tan	Chipping	5	0.1	Negative	None	N/A	No	No	no		
1	3	Classroom 31	yes	W3	Plaster	Tan	Flaking	47	2.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no		
1	3	Classroom 31	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A	Radiator	Metal	Grey	Flaking	37	0.7	Positive	None	N/A	No	No	no		
1	3	Classroom 31	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A	Baseboard	Wood	Tan	Chipping	12	0.2	Negative	None	N/A	No	No	no		
1	3	Classroom 31	yes	W4	Plaster	Tan	Cracking	12	31	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no		
1	3	Classroom 31	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A	Chalkboard frame	Wood	Tan	Chipping	20	0.5	Negative	None	N/A	No	No	no		
1	3	Classroom 31	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A	Baseboard	Wood	Tan	Chipping	9	0.5	Negative	None	N/A	No	No	no		
1	3	Classroom 31	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A	Chair rail	Wood	Tan	Chipping	1	0.6	Negative	None	N/A	No	No	no		
1	3	Classroom 31	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no		
1	3	Classroom 31	yes	Floor	Wood	Brown	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no		
1	3	Classroom 31 Storage Closet	yes	W1	Plaster	Tan	Cracking	24	25	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no		
1	3	Classroom 31 Storage Closet	yes	W2	Plaster	Tan	Cracking	19	25.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no		
1	3	Classroom 31 Storage Closet	yes	W3	Plaster	Tan	Flaking	31	28.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no		
1	3	Classroom 31 Storage Closet	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A	Chair rail	Wood	Tan	Chipping	3	0.2	Negative	None	N/A	No	No	no		
1	3	Classroom 31 Storage Closet	yes	W4	Plaster	Tan	Chipping	15	1.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no		
1	3	Classroom 31 Storage Closet	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A	Window frame	Wood	Tan	Chipping	5	0.1	Negative	None	N/A	No	No	no		
1	3	Classroom 31 Storage Closet	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A	Radiator	Metal	Grey	Chipping	5	0	Negative	None	N/A	No	No	no		
1	3	Classroom 31 Storage Closet	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no		
1	3	Classroom 31 Storage Closet	yes	Floor	Wood	Brown	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no		
1	3	Classroom 32	yes	W1	Plaster	Tan	Chipping	23	26.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no		
1	3	Classroom 32	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	Chalkboard frame	Wood	Tan	Chipping	4	0.3	Negative	None	N/A	No	No	no		
1	3	Classroom 32	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	Baseboard	Wood	Tan	Chipping	11	0.5	Negative	None	N/A	No	No	no		
1	3	Classroom 32	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	Chair rail	Wood	Tan	Chipping	1	0.6	Negative	None	N/A	No	No	no		
1	3	Classroom 32	yes	W2	Plaster	Tan	Chipping	20	26.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no		
1	3	Classroom 32	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door	Wood	Tan	Chipping	1	0.1	Negative	None	N/A	No	No	no		
1	3	Classroom 32	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Wood	Tan	Chipping	1	0.1	Negative	None	N/A	No	No	no		
1	3	Classroom 32	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door	Wood	Blue	Chipping	1	0.2	Negative	None	N/A	No	No	no		
1	3	Classroom 32	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A	Door	Wood	Tan	Chipping	2	0.1	Negative	None	N/A	No	No	no		
1	3	Classroom 32	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Wood	Tan	Chipping	1	0	Negative	None	N/A	No	No	no		
1	3	Classroom 32	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A	Chalkboard frame	Wood	Blue	Chipping	1	0.4	Negative	None	N/A	No	No	no		
1	3	Classroom 32	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A	Baseboard	Wood	Tan	Chipping	4	0.8	Positive	None	N/A	No	No	no		
1	3	Classroom 32	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A	Radiator	Metal	Gray	Flaking	16	8.1	Positive	None	N/A	No	No	no		
1	3	Classroom 32	yes	W3	Plaster	Tan	Cracking	42	1.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no		
1	3	Classroom 32	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A	Baseboard	Wood	Tan	Chipping	5	1.3	Positive	None	N/A	No	No	no		
1	3	Classroom 32	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A	Chair rail	Wood	Tan	Chipping	1	0.7	Negative	None	N/A	No	No	no		
1	3	Classroom 32	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A	Chalkboard frame	Wood	Tan	Chipping	5	0.2	Negative	None	N/A	No	No	no		
1	3	Classroom 32	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A	Window trim	Wood	Tan	Cracking	29	0.2	Negative	None	N/A	No	No	no		
1	3	Classroom 32	yes	W4	Plaster	Tan	Cracking	24	30	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no		
1	3	Classroom 32	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A	Radiator	Metal	Tan	Cracking	25	1.6	Positive	None	N/A	No	No	no		
1	3	Classroom 32	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A	Chair rail	Wood	Tan	Flaking	28									

School District of Philadelphia
Lead Safe Certification Inspection Report
Francis Scott Key School

Name of Inspector: Charles Rhodes
 Inspection Company: Batta Environmental

Inspection Dates: 7/1-7/9/2019
 ULCS# 2540

Element	FLOOR	On-Site Room Name	Student Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/negative)	Additional Component	Substrate Material	Color	Description of Paint and Plaster Damage	Additional Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Additional Component XRF (positive/negative)	Debris Present (describe location)	Quantity (sf)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Comments/ Description/ Notes
1	3	Classroom 32	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A	Baseboard	Wood	Tan	Flaking	N/A	N/A	Positive	None	N/A	No	No	no	
1	3	Classroom 32	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	3	Classroom 32	yes	Floor	Wood	Brown	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	3	Classroom 32 Storage Closet	yes	W1	Plaster	Tan	Chipping	1	20.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	3	Classroom 32 Storage Closet	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door	Wood	Tan	Cracking	5	0.1	Negative	None	N/A	No	No	no	
1	3	Classroom 32 Storage Closet	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Wood	Tan	Cracking	13	0.2	Negative	None	N/A	No	No	no	
1	3	Classroom 32 Storage Closet	yes	W2	Plaster	Tan	Cracking	25	24.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	3	Classroom 32 Storage Closet	yes	W2	Plaster	N/A	N/A	N/A	N/A	N/A	Chair rail	Wood	Tan	Chipping	4	0.4	Negative	None	N/A	No	No	no	
1	3	Classroom 32 Storage Closet	yes	W3	Plaster	Tan	Cracking	27	21.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	3	Classroom 32 Storage Closet	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A	Window trim	Wood	Tan	N/A	16	0.1	Negative	None	N/A	No	No	no	
1	3	Classroom 32 Storage Closet	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A	Radiator	Metal	Gray	Cracking	7	4.9	Positive	None	N/A	No	No	no	
1	3	Classroom 32 Storage Closet	yes	W4	Plaster	Tan	Spalling	4	30	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	3	Classroom 32 Storage Closet	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A	Door	Wood	Tan	Cracking	13	0.1	Negative	None	N/A	No	No	no	
1	3	Classroom 32 Storage Closet	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Wood	Tan	Cracking	13	0.2	Negative	None	N/A	No	No	no	
1	3	Classroom 32 Storage Closet	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	3	Classroom 32 Storage Closet	yes	Floor	Wood	Brown	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	3	Classroom 33	yes	W1	Plaster	Tan	Chipping	1	29.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	3	Classroom 33	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	Chalkboard frame	Wood	Blue	Chipping	1	0.2	Negative	None	N/A	No	No	no	
1	3	Classroom 33	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	Baseboard	Wood	Tan	Chipping	7	0.8	Positive	None	N/A	No	No	no	
1	3	Classroom 33	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	Chair rail	Wood	Tan	Chipping	1	0.01	Negative	None	N/A	No	No	no	
1	3	Classroom 33	yes	W2	Plaster	Tan	Chipping	1	29.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	3	Classroom 33	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A	Door	Wood	Blue	Chipping	1	0.2	Negative	None	N/A	No	No	no	
1	3	Classroom 33	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A	Door	Wood	Tan	Chipping	1	0.1	Negative	None	N/A	No	No	no	
1	3	Classroom 33	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Wood	Tan	Chipping	1	0.1	Negative	None	N/A	No	No	no	
1	3	Classroom 33	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A	Chalkboard frame	Wood	Blue	Chipping	1	0.3	Negative	None	N/A	No	No	no	
1	3	Classroom 33	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A	Baseboards	Wood	Tan	Chipping	5	1.2	Positive	None	N/A	No	No	no	
1	3	Classroom 33	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A	Radiator	Metal	Gray	Flaking	10	0.5	Negative	None	N/A	No	No	no	
1	3	Classroom 33	yes	W3	Plaster	Tan	Flaking	11	14.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	3	Classroom 33	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A	Baseboard	Wood	Tan	Chipping	8	0.4	Negative	None	N/A	No	No	no	
1	3	Classroom 33	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A	Chair rail	Wood	Tan	Chipping	4	0.6	Negative	None	N/A	No	No	no	
1	3	Classroom 33	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A	Window trim	Wood	Tan	Flaking	18	0.3	Negative	None	N/A	No	No	no	
1	3	Classroom 33	yes	W4	Plaster	Tan	Flaking	12	29.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	3	Classroom 33	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A	Chalkboard frame	Wood	Tan	Flaking	6	0.4	Negative	None	N/A	No	No	no	
1	3	Classroom 33	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A	Chair rail	Wood	Tan	Flaking	3	0.7	Positive	None	N/A	No	No	no	
1	3	Classroom 33	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A	Baseboard	Wood	Tan	Flaking	13	1.6	Positive	None	N/A	No	No	no	
1	3	Classroom 33	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	3	Classroom 33	yes	Floor	Wood	Brown	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	3	Classroom 33	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Wood	Tan	Chipping	1	0.1	Negative	None	N/A	No	No	no	
1	3	Classroom 33	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door	Wood	Tan	Chipping	1	0.1	Negative	None	N/A	No	No	no	
1	3	Classroom 33	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A	Radiator	Metal	Gray	Flaking	10	0.5	Negative	None	N/A	No	No	no	
1	3	Classroom 33	yes	W3	Plaster	Tan	Flaking	11	14.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	3	Classroom 33	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A	Baseboard	Wood	Tan	Chipping	8	0.4	Negative	None	N/A	No	No	no	
1	3	Classroom 33	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A	Chair rail	Wood	Tan	Chipping	4	0.6	Negative	None	N/A	No	No	no	
1	3	Classroom 33	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A	Window trim	Wood	Tan	Flaking	18	0.3	Negative	None	N/A	No	No	no	
1	3	Classroom 33	yes	W4	Plaster	Tan	Flaking	12	29.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	3	Classroom 33	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A	Chalkboard frame	Wood	Tan	Flaking	6	0.4	Negative	None	N/A	No	No	no	
1	3	Classroom 33	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A	Chair rail	Wood	Tan	Flaking	3	0.7	Positive	None	N/A	No	No	no	
1	3	Classroom 33	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A	Baseboard	Wood	Tan	Flaking	13	1.6	Positive	None	N/A	No	No	no	
1	3	Classroom 33	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	3	Classroom 33	yes	Floor	Wood	Brown	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	N/A	No	No	no	
1	3	Classroom 33	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Wood	Tan	Chipping	1	0.1	Negative	None	N/A	No	No	no	
1	3	Classroom 33	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door	Wood	Tan	Chipping	1	0.1	Negative	None	N/A	No	No	no	
1	3	Classroom 33 Storage Closet	yes	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access
1	3	Classroom 33 Storage Closet	yes	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access
1	3	Classroom 33 Storage Closet	yes	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access
1	3	Classroom 33 Storage Closet	yes	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access
1	3	Classroom 33 Storage Closet	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access
1	3	Classroom 33 Storage Closet	yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access