

Olney Annex (Tabor Road) Lead Safe Certification Assessment Report

**School District of Philadelphia
Lead Safe Certification Inspection Report
Olney Annex School (Tabor Road)**

		Name of Inspector: Bart McMahon Inspection Company: Synertech, Inc.															Inspection Dates: 07/11-12/2019 ULCS# 7403						
Element	Floor	On-Site Room Name	Student Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/negative)	Additional Component	Substrate Material	Color	Description of Paint and Plaster Damage	Additional Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Additional Component XRF (positive/negative)	Debris Present (describe location)	Quantity (sf)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Comments/ Description/ Notes
1	1	Front Entrance Lobby	yes	W1	Sheetrock	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	*Entire building under renovation
1	1	Front Entrance Lobby	yes	W2	Sheetrock	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Front Entrance Lobby	yes	W3	Sheetrock	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Front Entrance Lobby	yes	W4	Sheetrock	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Front Entrance Lobby	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Front Entrance Lobby	yes	Floor	N/A	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	Suspended Ceiling No Paint
1	1	Female Restroom inside the Front Entrance Lobby	yes	W1	Concrete	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Female Restroom inside the Front Entrance Lobby	yes	W2	Concrete	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Female Restroom inside the Front Entrance Lobby	yes	W3	Concrete	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Female Restroom inside the Front Entrance Lobby	yes	W4	Concrete	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Female Restroom inside the Front Entrance Lobby	yes	Ceiling	N/A	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	Suspended Ceiling Tiles
1	1	Female Restroom inside the Front Entrance Lobby	yes	Floor	N/A	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	Floor Tiles
1	1	Male Restroom inside the Front Entrance Lobby	yes	W1	Concrete	Blue	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Male Restroom inside the Front Entrance Lobby	yes	W2	Sheetrock	Blue	Efflorescence	4	0.02	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Male Restroom inside the Front Entrance Lobby	yes	W3	Concrete	Blue	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Male Restroom inside the Front Entrance Lobby	yes	W4	Sheetrock	Blue	Efflorescence	3	0.02	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Male Restroom inside the Front Entrance Lobby	yes	Ceiling	N/A	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	Suspended Ceiling Tiles
1	1	Male Restroom inside the Front Entrance Lobby	yes	Floor	N/A	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	Floor Tiles
1	1	Front Stairwell beside Front Entrance Lobby	yes	W1	Concrete	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Front Stairwell beside Front Entrance Lobby	yes	W2	Concrete	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Front Stairwell beside Front Entrance Lobby	yes	W3	Concrete	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Front Stairwell beside Front Entrance Lobby	yes	W4	Concrete	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Front Stairwell beside Front Entrance Lobby	yes	Ceiling	N/A	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	Suspended Ceiling Tiles
1	1	Front Stairwell beside Front Entrance Lobby	yes	Floor	N/A	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	Floor Tiles
1	1	Storage Cubby below Front Stairwell beside Front Entrance Lobby	yes	W1	Sheetrock	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Storage Cubby below Front Stairwell beside Front Entrance Lobby	yes	W2	Concrete	Green	Chipping	1	0.02	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Storage Cubby below Front Stairwell beside Front Entrance Lobby	yes	W3	Concrete	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Storage Cubby below Front Stairwell beside Front Entrance Lobby	yes	W4	Concrete	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Storage Cubby below Front Stairwell beside Front Entrance Lobby	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Storage Cubby below Front Stairwell beside Front Entrance Lobby	yes	Floor	N/A	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	Floor Tiles
1	1	Classroom 1	yes	W1	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Classroom 1	yes	W2	Sheetrock	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Classroom 1	yes	W3	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Classroom 1	yes	W4	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Classroom 1	yes	Ceiling	N/A	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	Suspended Ceiling Tiles
1	1	Classroom 1	yes	Floor	Concrete	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	No Paint
1	1	Classroom 2	yes	W1	Sheetrock	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Classroom 2	yes	W2	Sheetrock	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Classroom 2	yes	W3	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Classroom 2	yes	W4	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Classroom 2	yes	Ceiling	N/A	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	Suspended Ceiling Tiles
1	1	Classroom 2	yes	Floor	Concrete	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	No Paint
1	1	Classroom 3	yes	W1	Sheetrock	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Classroom 3	yes	W2	Sheetrock	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Classroom 3	yes	W3	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Classroom 3	yes	W4	Sheetrock	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Classroom 3	yes	Ceiling	N/A	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	Suspended Ceiling Tiles

Olney Annex (Tabor Road) Lead Safe Certification Assessment Report

School District of Philadelphia
Lead Safe Certification Inspection Report
Olney Annex School (Tabor Road)

Name of Inspector: Bart McMahon
Inspection Company: Synertech, Inc.

Inspection Dates: 07/11-12/2019
ULCS# 7403

Element	Floor	On-Site Room Name	Student Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/negative)	Additional Component	Substrate Material	Color	Description of Paint and Plaster Damage	Additional Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Additional Component XRF (positive/negative)	Debris Present (describe location)	Quantity (sf)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Comments/ Description/ Notes
1	2	Main Hallway	yes	W4	Concrete	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Main Hallway	yes	Ceiling	N/A	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	Suspended Ceiling Tiles
1	2	Main Hallway	yes	Floor	N/A	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	Floor Tiles
1	2	Men's Locker Room	yes	W1	Sheetrock	White	Chipping	1	0.02	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Men's Locker Room	yes	W1	N/A	N/A	None	0	N/A	N/A	Bench	Wood	Grey	Chipping	2	0.02	Negative	None	0	No	No	no	
1	2	Men's Locker Room	yes	W2	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Men's Locker Room	yes	W3	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Men's Locker Room	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A	Bench	Wood	Grey	Chipping	2	0.02	Negative	None	0	No	No	no	
1	2	Men's Locker Room	yes	W4	Sheetrock	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Men's Locker Room	yes	Ceiling	Wood	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Men's Locker Room	yes	Floor	Concrete	Grey	Cracking	2	0.02	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Men's Toilet inside Men's Locker Room	yes	W1	Sheetrock	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Men's Toilet inside Men's Locker Room	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Men's Toilet inside Men's Locker Room	yes	W3	Sheetrock	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Men's Toilet inside Men's Locker Room	yes	W4	Sheetrock	White	Cracking	1	0.02	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Men's Toilet inside Men's Locker Room	yes	Ceiling	Wood	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Men's Toilet inside Men's Locker Room	yes	Floor	N/A	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	Floor Tiles
1	2	Men's Shower Room inside Men's Locker Room	yes	W1	Concrete	Blue	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Men's Shower Room inside Men's Locker Room	yes	W2	Concrete	Blue	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Men's Shower Room inside Men's Locker Room	yes	W3	Concrete	Blue	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Men's Shower Room inside Men's Locker Room	yes	W4	Concrete	Blue	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Men's Shower Room inside Men's Locker Room	yes	Ceiling	Metal	Blue	Chipping	1	0.02	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Men's Shower Room inside Men's Locker Room	yes	Floor	N/A	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	Floor Tiles
1	2	Women's Locker Room	yes	W1	Sheetrock	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Women's Locker Room	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	Bench	Wood	Brown	Chipping	2	0.02	Negative	None	0	No	No	no	
1	2	Women's Locker Room	yes	W2	Sheetrock	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Women's Locker Room	yes	W3	Sheetrock	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Women's Locker Room	yes	W4	Sheetrock	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Women's Locker Room	yes	Ceiling	N/A	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	Suspended Ceiling Tiles
1	2	Women's Locker Room	yes	Floor	N/A	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	Floor Tiles
1	2	Women's Toilet inside Women's Locker Room	yes	W1	Sheetrock	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Women's Toilet inside Women's Locker Room	yes	W2	Sheetrock	Tan	Efflorescence	4	0.02	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Women's Toilet inside Women's Locker Room	yes	W3	Sheetrock	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Women's Toilet inside Women's Locker Room	yes	W4	Sheetrock	Tan	Cracking	2	0.02	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Women's Toilet inside Women's Locker Room	yes	Ceiling	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	Suspended Ceiling Tiles
1	2	Women's Toilet inside Women's Locker Room	yes	Floor	N/A	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	Floor Tiles
1	2	Women's Changing Room beside Women's Shower Room	yes	W1	Sheetrock	White	Chipping	2	0.02	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Women's Changing Room beside Women's Shower Room	yes	W2	Sheetrock	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Women's Changing Room beside Women's Shower Room	yes	W3	Concrete	White	Cracking	1	0.02	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Women's Changing Room beside Women's Shower Room	yes	W4	Sheetrock	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Women's Changing Room beside Women's Shower Room	yes	Ceiling	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	Suspended Ceiling Tiles
1	2	Women's Changing Room beside Women's Shower Room	yes	Floor	N/A	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	Floor Tiles
1	2	Women's Shower Room	yes	W1	Concrete	Blue	Cracking	1	0.02	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Women's Shower Room	yes	W2	Concrete	Blue	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Women's Shower Room	yes	W3	Concrete	Blue	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Women's Shower Room	yes	W4	Concrete	Blue	Cracking	2	0.02	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Women's Shower Room	yes	Ceiling	N/A	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	Suspended Ceiling Tiles
1	2	Women's Shower Room	yes	Floor	N/A	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	Floor Tiles
1	2	Gymnasium	yes	W1	Wood	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Partially Inaccessible	No	no	No Paint
1	2	Gymnasium	yes	W2	Wood	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Partially Inaccessible	No	no	No Paint

Olney Annex (Tabor Road) Lead Safe Certification Assessment Report

School District of Philadelphia
Lead Safe Certification Inspection Report
Olney Annex School (Tabor Road)

		Name of Inspector: Bart McMahon Inspection Company: Synertech, Inc.															Inspection Dates: 07/11-12/2019 ULCS# 7403						
E l e m e n t	F l o o r	On-Site Room Name	Student Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/negative)	Additional Component	Substrate Material	Color	Description of Paint and Plaster Damage	Additional Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Additional Component XRF (positive/negative)	Debris Present (describe location)	Quantity (sf)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Comments/ Description/ Notes
1	2	Gymnasium	yes	W3	Wood	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Partially Inaccessible	No	no	No Paint
1	2	Gymnasium	yes	W4	Wood	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Partially Inaccessible	No	no	No Paint
1	2	Gymnasium	yes	Ceiling	Wood	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Partially Inaccessible	No	no	No Paint
1	2	Gymnasium	yes	Floor	Wood	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Partially Inaccessible	No	no	No Paint
1	2	IT Closet beside Classroom 10	yes	W1	Sheetrock	Blue	Chipping	1	0.02	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	IT Closet beside Classroom 10	yes	W2	Concrete	Blue	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	IT Closet beside Classroom 10	yes	W3	Concrete	Blue	Efflorescence	1	0.02	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	IT Closet beside Classroom 10	yes	W4	Concrete	Blue	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	IT Closet beside Classroom 10	yes	Ceiling	N/A	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	Suspended Ceiling Tiles
1	2	IT Closet beside Classroom 10	yes	Floor	N/A	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	Floor Tiles
1	2	Rear Stairwell behind Kitchen	yes	W1	Sheetrock	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Rear Stairwell behind Kitchen	yes	W2	Concrete	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Rear Stairwell behind Kitchen	yes	W3	Concrete	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Rear Stairwell behind Kitchen	yes	W4	Concrete	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Rear Stairwell behind Kitchen	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	Blue	Chipping	2	0.51	Negative	None	0	No	No	no	
1	2	Rear Stairwell behind Kitchen	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A	Door	Metal	Blue	Chipping	2	0.04	Negative	None	0	No	No	no	
1	2	Rear Stairwell behind Kitchen	yes	Ceiling	N/A	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	Suspended Ceiling Tiles
1	2	Rear Stairwell behind Kitchen	yes	Floor	N/A	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	Floor Tiles