

**School District of Philadelphia
Lead Safe Certification Assessment Report
Trinidad Head Start School**

		Name of Inspector: Melissa Billingsley Inspection Company: Criterion Labs., Inc																Inspection Dates: 07/09-7/11/2019 ULCS# 7514					
Element	Fl oor	On-Site Room Name	Student/Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/negative)	Additional Component	Substrate Material	Color	Description of Paint and Plaster Damage	Additional Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Additional Component XRF (positive/negative)	Debris Present (describe location)	Quantity (sf)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Comments/ Description/ Notes
1	1	Classroom 1	yes	W1	Sheetrock	Blue	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Partially Inaccessible	No	no	
1	1	Classroom 1	yes	W2	Sheetrock	Blue	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Partially Inaccessible	No	no	
1	1	Classroom 1	yes	W3	Sheetrock	Blue	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Partially Inaccessible	No	no	
1	1	Classroom 1	yes	W4	Sheetrock	Blue	Chipping	2	0.02	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Partially Inaccessible	No	no	
1	1	Classroom 1	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Partially Inaccessible	No	no	Lay-in tiles
1	1	Classroom 1	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Partially Inaccessible	No	no	12x12 tiles
1	1	Hallway Closet next to Classroom 1	yes	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Door is locked and Admin does not have key
1	1	Hallway Closet next to Classroom 1	yes	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Door is locked and Admin does not have key
1	1	Hallway Closet next to Classroom 1	yes	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Door is locked and Admin does not have key
1	1	Hallway Closet next to Classroom 1	yes	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Door is locked and Admin does not have key
1	1	Hallway Closet next to Classroom 1	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Door is locked and Admin does not have key
1	1	Hallway Closet next to Classroom 1	yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Door is locked and Admin does not have key
1	1	Classroom 2	yes	W1	Sheetrock	Blue	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Classroom 2	yes	W2	Sheetrock	Blue	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Classroom 2	yes	W2	Sheetrock	Tan	Chipping	2	0.02	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Classroom 2	yes	W3	Sheetrock	Blue	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Classroom 2	yes	W3	Sheetrock	Tan	Chipping	1	0.03	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Classroom 2	yes	W4	Sheetrock	Blue	Chipping	2	0.03	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Classroom 2	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	Lay-in Tile
1	1	Classroom 2	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	12x12 tile
1	1	Classroom 3	yes	W1	Sheetrock	Pink	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Partially Inaccessible	No	no	
1	1	Classroom 3	yes	W2	Sheetrock	Blue	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Partially Inaccessible	No	no	
1	1	Classroom 3	yes	W3	Sheetrock	Pink	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Partially Inaccessible	No	no	
1	1	Classroom 3	yes	W3	Sheetrock	Blue	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Partially Inaccessible	No	no	
1	1	Classroom 3	yes	W4	Sheetrock	Blue	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Partially Inaccessible	No	no	
1	1	Classroom 3	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Partially Inaccessible	No	no	Lay-in Tile
1	1	Classroom 3	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Partially Inaccessible	No	no	12x12 tile
1	1	Classroom 4	yes	W1	Sheetrock	Purple	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Partially Inaccessible	No	no	
1	1	Classroom 4	yes	W2	Sheetrock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Partially Inaccessible	No	no	
1	1	Classroom 4	yes	W3	Sheetrock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Partially Inaccessible	No	no	
1	1	Classroom 4	yes	W3	Sheetrock	Purple	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Partially Inaccessible	No	no	
1	1	Classroom 4	yes	W4	Sheetrock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Partially Inaccessible	No	no	
1	1	Classroom 4	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Partially Inaccessible	No	no	Lay-in Tile
1	1	Classroom 4	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Partially Inaccessible	No	no	12x12 tile
1	1	Classroom 5	yes	W1	Sheetrock	Blue	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Partially Inaccessible	No	no	
1	1	Classroom 5	yes	W2	Sheetrock	Yellow	Chipping	2	0.01	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Partially Inaccessible	No	no	
1	1	Classroom 5	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A	Columns	Sheetrock	Blue	Chipping	2	0.03	Negative	None	0	Partially Inaccessible	No	no	
1	1	Classroom 5	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A	Columns	Sheetrock	Brown	Chipping	1	0.01	Negative	None	0	Partially Inaccessible	No	no	
1	1	Classroom 5	yes	W3	Sheetrock	Blue	Chipping	5	0.01	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Partially Inaccessible	No	no	
1	1	Classroom 5	yes	W4	Sheetrock	Yellow	Chipping	3	0.03	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Partially Inaccessible	No	no	
1	1	Classroom 5	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Partially Inaccessible	No	no	Lay-in Tile
1	1	Classroom 5	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Partially Inaccessible	No	no	12x12 tile
1	1	Staff Restroom across from Classroom 5	yes	W1	Sheetrock	Pink	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Staff Restroom across from Classroom 5	yes	W2	Sheetrock	Pink	Chipping	2	0.02	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	

School District of Philadelphia
Lead Safe Certification Assessment Report
Trinidad Head Start School

Name of Inspector: **Melissa Billingsley**
 Inspection Company: **Criterion Labs., Inc**

Inspection Dates: **07/09-7/11/2019**
 ULCS# **7514**

Element	Floor	On-Site Room Name	Student/Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/negative)	Additional Component	Substrate Material	Color	Description of Paint and Plaster Damage	Additional Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Additional Component XRF (positive/negative)	Debris Present (describe location)	Quantity (sf)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Comments/ Description/ Notes
1	1	Staff Restroom across from Classroom 5	yes	W3	Sheetrock	Pink	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Staff Restroom across from Classroom 5	yes	W4	Sheetrock	Pink	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Staff Restroom across from Classroom 5	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	Lay-in Tile
1	1	Staff Restroom across from Classroom 5	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	Ceramic
1	1	Kitchen	yes	W1	Sheetrock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Kitchen	yes	W2	Sheetrock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Kitchen	yes	W3	Sheetrock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Kitchen	yes	W4	Sheetrock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Kitchen	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	Lay-in Tile
1	1	Kitchen	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	12x12 tile
1	1	Director's Office	yes	W1	Sheetrock	Purple	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Director's Office	yes	W2	Sheetrock	Purple	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Director's Office	yes	W3	Sheetrock	Purple	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Director's Office	yes	W3	Sheetrock	Gray	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Director's Office	yes	W4	Sheetrock	Purple	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Director's Office	yes	W4	Sheetrock	Gray	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Director's Office	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Director's Office	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Director's Office Closet	yes	W1	Sheetrock	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Director's Office Closet	yes	W2	Sheetrock	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Director's Office Closet	yes	W3	Sheetrock	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Director's Office Closet	yes	W4	Sheetrock	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Director's Office Closet	yes	Ceiling	Sheetrock	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Director's Office Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	12x12 Tile
1	1	Teacher's Lounge	yes	W1	Sheetrock	Blue	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Partially Inaccessible	No	no	
1	1	Teacher's Lounge	yes	W2	Sheetrock	Blue	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Partially Inaccessible	No	no	
1	1	Teacher's Lounge	yes	W3	Sheetrock	Blue	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Partially Inaccessible	No	no	
1	1	Teacher's Lounge	yes	W4	Sheetrock	Gray	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Partially Inaccessible	No	no	
1	1	Teacher's Lounge	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Partially Inaccessible	No	no	Lay-in Tile
1	1	Teacher's Lounge	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Partially Inaccessible	No	no	12x12 tile
1	1	Teacher's Lounge - Closet	yes	W1	Sheetrock	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Teacher's Lounge - Closet	yes	W2	Sheetrock	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Teacher's Lounge - Closet	yes	W3	Sheetrock	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Teacher's Lounge - Closet	yes	W4	Sheetrock	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Teacher's Lounge - Closet	yes	Ceiling	Sheetrock	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Teacher's Lounge - Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	12x12 tile
1	1	Hallway to Parking Lot Exit	yes	W1	Sheetrock	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Hallway to Parking Lot Exit	yes	W2	Sheetrock	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Hallway to Parking Lot Exit	yes	W3	Sheetrock	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Hallway to Parking Lot Exit	yes	W4	Sheetrock	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Hallway to Parking Lot Exit	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	Lay-in Tile
1	1	Hallway to Parking Lot Exit	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	12x12 tile
1	1	Center Stairwell	yes	W1	Sheetrock	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Center Stairwell	yes	W1	Sheetrock	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Center Stairwell	yes	W2	Sheetrock	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Center Stairwell	yes	W2	Sheetrock	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Center Stairwell	yes	W3	Sheetrock	White	Moisture Damage	5	0.01	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Center Stairwell	yes	W3	Sheetrock	Tan	Moisture Damage	5	0.03	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Center Stairwell	yes	W4	Sheetrock	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Center Stairwell	yes	W4	Sheetrock	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Center Stairwell	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	Lay-in Tile
1	1	Center Stairwell	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	12x12 Tile
1	1	Receptionist Office	yes	W1	Sheetrock	Purple	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Receptionist Office	yes	W2	Sheetrock	Purple	Chipping	2	0.03	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Receptionist Office	yes	W3	Sheetrock	Purple	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Receptionist Office	yes	W4	Sheetrock	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Receptionist Office	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	Lay-in Tile
1	1	Receptionist Office	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	Carpet
1	1	Receptionist's Office - Closet	yes	W1	Sheetrock	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Receptionist's Office - Closet	yes	W2	Sheetrock	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Receptionist's Office - Closet	yes	W3	Sheetrock	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Receptionist's Office - Closet	yes	W4	Sheetrock	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Receptionist's Office - Closet	yes	Ceiling	Sheetrock	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Receptionist's Office - Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	Carpet
1	1	Building Engineer's Office	no	W1	Sheetrock	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Building Engineer's Office	no	W2	Sheetrock	White	Chipping	2	0.01	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Building Engineer's Office	no	W3	Sheetrock	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	

School District of Philadelphia
Lead Safe Certification Assessment Report
Trinidad Head Start School

		Name of Inspector: Melissa Billingsley Inspection Company: Criterion Labs., Inc															Inspection Dates: 07/09-7/11/2019 ULCS# 7514						
Element	Fl	On-Site Room Name	Student/Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/negative)	Additional Component	Substrate Material	Color	Description of Paint and Plaster Damage	Additional Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Additional Component XRF (positive/negative)	Debris Present (describe location)	Quantity (sf)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Comments/ Description/ Notes
1	1	Building Engineer's Office	no	W4	Sheetrock	White	Chipping	2	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Building Engineer's Office	no	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	Lay-in Tile
1	1	Building Engineer's Office	no	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	Carpet
1	1	Building Engineer's Office - Closet	no	W1	Sheetrock	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Building Engineer's Office - Closet	no	W2	Sheetrock	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Building Engineer's Office - Closet	no	W3	Sheetrock	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Building Engineer's Office - Closet	no	W4	Sheetrock	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Building Engineer's Office - Closet	no	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	Lay-in Tile
1	1	Building Engineer's Office - Closet	no	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	Carpet
1	1	Building Engineer's Office Storage Room	no	W1	Sheetrock	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Partially Inaccessible	No	no	
1	1	Building Engineer's Office Storage Room	no	W2	Sheetrock	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Partially Inaccessible	No	no	
1	1	Building Engineer's Office Storage Room	no	W3	Sheetrock	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Partially Inaccessible	No	no	
1	1	Building Engineer's Office Storage Room	no	W4	Sheetrock	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Partially Inaccessible	No	no	
1	1	Building Engineer's Office Storage Room	no	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Partially Inaccessible	No	no	Lay-in Tile
1	1	Building Engineer's Office Storage Room	no	Floor	Concrete	Gray	Friction	5	0.02	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Partially Inaccessible	No	no	
1	1	Building Engineer's Office Storage Room - Closet	no	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Items in storage room are blocking doorwa and it can not be accessed
1	1	Building Engineer's Office Storage Room - Closet	no	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Items in storage room are blocking doorwa and it can not be accessed
1	1	Building Engineer's Office Storage Room - Closet	no	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Items in storage room are blocking doorwa and it can not be accessed
1	1	Building Engineer's Office Storage Room - Closet	no	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Items in storage room are blocking doorwa and it can not be accessed
1	1	Building Engineer's Office Storage Room - Closet	no	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Items in storage room are blocking doorwa and it can not be accessed
1	1	Building Engineer's Office Storage Room - Closet	no	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Items in storage room are blocking doorwa and it can not be accessed
1	1	Girl's Restroom	yes	W1	Sheetrock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Girl's Restroom	yes	W1	Sheetrock	Green	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Girl's Restroom	yes	W2	Sheetrock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Girl's Restroom	yes	W2	Sheetrock	Green	Friction	10	0.02	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Girl's Restroom	yes	W3	Sheetrock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Girl's Restroom	yes	W3	Sheetrock	Green	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Girl's Restroom	yes	W4	Sheetrock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Girl's Restroom	yes	W4	Sheetrock	Green	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Girl's Restroom	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Girl's Restroom	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Boy's Restroom	yes	W1	Sheetrock	Gray	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Boy's Restroom	yes	W1	Sheetrock	Blue	Friction	10	0.03	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Boy's Restroom	yes	W2	Sheetrock	Gray	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Boy's Restroom	yes	W2	Sheetrock	Blue	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Boy's Restroom	yes	W3	Sheetrock	Gray	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Boy's Restroom	yes	W3	Sheetrock	Blue	Chipping	3	0.01	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Boy's Restroom	yes	W4	Sheetrock	Gray	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Boy's Restroom	yes	W4	Sheetrock	Blue	Chipping	2	0.01	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Boy's Restroom	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	Lay-in Tiles
1	1	Boy's Restroom	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	Ceramic
1	1	Custodial Closet adjacent to Boy's Restroom	no	W1	Sheetrock	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Custodial Closet adjacent to Boy's Restroom	no	W2	Sheetrock	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Custodial Closet adjacent to Boy's Restroom	no	W3	Sheetrock	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Custodial Closet adjacent to Boy's Restroom	no	W4	Sheetrock	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Custodial Closet adjacent to Boy's Restroom	no	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	Lay-in Tiles
1	1	Custodial Closet adjacent to Boy's Restroom	no	Floor	Concrete	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	Unpainted
1	1	Hallway Closet next to Girl's Restroom	no	W1	Sheetrock	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Hallway Closet next to Girl's Restroom	no	W2	Sheetrock	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Hallway Closet next to Girl's Restroom	no	W3	Sheetrock	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Hallway Closet next to Girl's Restroom	no	W4	Sheetrock	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Hallway Closet next to Girl's Restroom	no	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	Lay-in Tile
1	1	Hallway Closet next to Girl's Restroom	no	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	12x12 Tile
1	1	Main Hallway	yes	W1	Sheetrock	White	Chipping	10	0.01	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Main Hallway	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	Brown	Friction	3	0.02	Negative	None	0	No	No	no	
1	1	Main Hallway	yes	W2	Sheetrock	White	Chipping	10	0.02	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Main Hallway	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	Brown	Friction	3	0.01	Negative	None	0	No	No	no	
1	1	Main Hallway	yes	W3	Sheetrock	White	Chipping	10	0.01	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Main Hallway	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	Brown	Friction	3	0	Negative	None	0	No	No	no	
1	1	Main Hallway	yes	W4	Sheetrock	White	Chipping	10	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Main Hallway	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	Brown	Friction	3	0.01	Negative	None	0	No	No	no	
1	1	Main Hallway	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	Lay-in Tile

School District of Philadelphia
Lead Safe Certification Assessment Report
Trinidad Head Start School

Inspection Dates: 07/09-7/11/2019
ULCS# 7514

Name of Inspector: Melissa Billingsley
Inspection Company: Criterion Labs., Inc

Element	Floor	On-Site Room Name	Student/Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/negative)	Additional Component	Substrate Material	Color	Description of Paint and Plaster Damage	Additional Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Additional Component XRF (positive/negative)	Debris Present (describe location)	Quantity (sf)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Comments/ Description/ Notes	
1	1	Main Hallway	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	12x12 tile
1	1	End Stairwell	yes	W1	Sheetrock	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	End Stairwell	yes	W1	Sheetrock	Blue	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	End Stairwell	yes	W2	Sheetrock	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	End Stairwell	yes	W2	Sheetrock	Blue	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	End Stairwell	yes	W3	Sheetrock	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	End Stairwell	yes	W3	Sheetrock	Blue	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	End Stairwell	yes	W4	Sheetrock	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	End Stairwell	yes	W4	Sheetrock	Blue	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	End Stairwell	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	Lay-in Tile
1	1	End Stairwell	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	12x12 tile
1	1	End Stairwell Closet	no	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Door is locked and Admin does not have key
1	1	End Stairwell Closet	no	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Door is locked and Admin does not have key
1	1	End Stairwell Closet	no	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Door is locked and Admin does not have key
1	1	End Stairwell Closet	no	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Door is locked and Admin does not have key
1	1	End Stairwell Closet	no	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Door is locked and Admin does not have key
1	1	End Stairwell Closet	no	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Door is locked and Admin does not have key
1	2	Storage Room 10	no	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Door is locked and Admin does not have key
1	2	Storage Room 10	no	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Door is locked and Admin does not have key
1	2	Storage Room 10	no	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Door is locked and Admin does not have key
1	2	Storage Room 10	no	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Door is locked and Admin does not have key
1	2	Storage Room 10	no	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Door is locked and Admin does not have key
1	2	Storage Room 10	no	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Door is locked and Admin does not have key
1	2	Storage Room 9	no	W1	Sheetrock	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	Roof leak	no	Part of room is unpainted walls. Appears to have a roof leak in room
1	2	Storage Room 9	no	W2	Sheetrock	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	Roof leak	no	Part of room is unpainted walls. Appears to have a roof leak in room
1	2	Storage Room 9	no	W3	Sheetrock	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	Roof leak	no	Part of room is unpainted walls. Appears to have a roof leak in room
1	2	Storage Room 9	no	W4	Sheetrock	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	Roof leak	no	Part of room is unpainted walls. Appears to have a roof leak in room
1	2	Storage Room 9	no	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	Roof leak	no	Lay-in tiles
1	2	Storage Room 9	no	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	Roof leak	no	Carpet
1	2	Storage Room 8	no	W1	Sheetrock	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Storage Room 8	no	W2	Sheetrock	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Storage Room 8	no	W3	Sheetrock	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Storage Room 8	no	W4	Sheetrock	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Storage Room 8	no	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	Lay-in tiles
1	2	Storage Room 8	no	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	carpet
1	2	Storage Room 7	no	W1	Sheetrock	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Storage Room 7	no	W2	Sheetrock	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Storage Room 7	no	W3	Sheetrock	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Storage Room 7	no	W4	Sheetrock	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Storage Room 7	no	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	Lay-in Tiles
1	2	Storage Room 7	no	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	Carpet
1	2	Hot Water Heater Closet opposite Storage Room	no	W1	Sheetrock	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	Walls are not painted
1	2	Hot Water Heater Closet opposite Storage Room	no	W2	Sheetrock	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	Walls are not painted
1	2	Hot Water Heater Closet opposite Storage Room	no	W3	Sheetrock	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	Walls are not painted
1	2	Hot Water Heater Closet opposite Storage Room	no	W4	Sheetrock	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	Walls are not painted
1	2	Hot Water Heater Closet opposite Storage Room	no	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	No ceiling, open to decking
1	2	Hot Water Heater Closet opposite Storage Room	no	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	unpainted concrete floor
1	2	Storage Room 6	no	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Door is locked and Admin does not have key
1	2	Storage Room 6	no	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Door is locked and Admin does not have key
1	2	Storage Room 6	no	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Door is locked and Admin does not have key
1	2	Storage Room 6	no	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Door is locked and Admin does not have key
1	2	Storage Room 6	no	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Door is locked and Admin does not have key
1	2	Storage Room 6	no	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Door is locked and Admin does not have key

School District of Philadelphia
Lead Safe Certification Assessment Report
Trinidad Head Start School

Name of Inspector: Melissa Billingsley
 Inspection Company: Criterion Labs., Inc

Inspection Dates: 07/09-7/11/2019
 ULCS# 7514

Element	Fl oor	On-Site Room Name	Student/Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/negative)	Additional Component	Substrate Material	Color	Description of Paint and Plaster Damage	Additional Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Additional Component XRF (positive/negative)	Debris Present (describe location)	Quantity (sf)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Comments/ Description/ Notes
1	2	Storage Room 5	no	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Door is locked and Admin does not have key
1	2	Storage Room 5	no	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Door is locked and Admin does not have key
1	2	Storage Room 5	no	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Door is locked and Admin does not have key
1	2	Storage Room 5	no	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Door is locked and Admin does not have key
1	2	Storage Room 5	no	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Door is locked and Admin does not have key
1	2	Storage Room 5	no	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Door is locked and Admin does not have key
1	2	Telecommunication Equipment Room 4	no	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Door is locked and Admin does not have key
1	2	Telecommunication Equipment Room 4	no	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Door is locked and Admin does not have key
1	2	Telecommunication Equipment Room 4	no	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Door is locked and Admin does not have key
1	2	Telecommunication Equipment Room 4	no	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Door is locked and Admin does not have key
1	2	Telecommunication Equipment Room 4	no	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Door is locked and Admin does not have key
1	2	Telecommunication Equipment Room 4	no	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Door is locked and Admin does not have key
1	2	Storage Room 3	no	W1	Sheetrock	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Storage Room 3	no	W2	Sheetrock	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Storage Room 3	no	W3	Sheetrock	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Storage Room 3	no	W4	Sheetrock	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Storage Room 3	no	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	Lay-in tiles
1	2	Storage Room 3	no	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	Carpet
1	2	Storage Room 2	no	W1	Sheetrock	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Storage Room 2	no	W2	Sheetrock	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Storage Room 2	no	W3	Sheetrock	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Storage Room 2	no	W4	Sheetrock	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Storage Room 2	no	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	Lay-in Tiles
1	2	Storage Room 2	no	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	Carpet
1	2	Storage Room 1	no	W1	Sheetrock	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Storage Room 1	no	W2	Sheetrock	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Storage Room 1	no	W3	Sheetrock	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Storage Room 1	no	W4	Sheetrock	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Storage Room 1	no	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Storage Room 1	no	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	Lay-in Tiles
1	2	Hallway outside Storage Rooms 1-10	no	W1	Sheetrock	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	Carpet
1	2	Hallway outside Storage Rooms 1-10	no	W2	Sheetrock	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Hallway outside Storage Rooms 1-10	no	W3	Sheetrock	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Hallway outside Storage Rooms 1-10	no	W4	Sheetrock	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Hallway outside Storage Rooms 1-10	no	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	Lay-in Tile
1	2	Hallway outside Storage Rooms 1-10	no	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	12x12 Tile
1	2	Hallway outside Boy's and Girl's Restrooms	yes	W1	Sheetrock	Green	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Hallway outside Boy's and Girl's Restrooms	yes	W1	Sheetrock	Blue	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Hallway outside Boy's and Girl's Restrooms	yes	W2	Sheetrock	Green	Friction	10	0.03	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Hallway outside Boy's and Girl's Restrooms	yes	W2	Sheetrock	Blue	Friction	10	0.02	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Hallway outside Boy's and Girl's Restrooms	yes	W3	Sheetrock	Green	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Hallway outside Boy's and Girl's Restrooms	yes	W3	Sheetrock	Blue	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Hallway outside Boy's and Girl's Restrooms	yes	W4	Sheetrock	Green	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Hallway outside Boy's and Girl's Restrooms	yes	W4	Sheetrock	Blue	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Hallway outside Boy's and Girl's Restrooms	yes	W4	Sheetrock	Green	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Hallway outside Boy's and Girl's Restrooms	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	Lay-in Tile
1	2	Hallway outside Boy's and Girl's Restrooms	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	12x12 tile
1	2	Boy's Restroom	yes	W1	Sheetrock	Blue	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Boy's Restroom	yes	W1	Sheetrock	Green	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Boy's Restroom	yes	W2	Sheetrock	Blue	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Boy's Restroom	yes	W2	Sheetrock	Green	Chipping	2	0.02	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Boy's Restroom	yes	W3	Sheetrock	Blue	Chipping	2	0.01	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Boy's Restroom	yes	W3	Sheetrock	Green	Chipping	2	0.01	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Boy's Restroom	yes	W4	Sheetrock	Blue	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Boy's Restroom	yes	W4	Sheetrock	Green	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Boy's Restroom	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	Lay-in Tile
1	2	Boy's Restroom	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	12x12 tile
1	2	Girl's Restroom	yes	W1	Sheetrock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Girl's Restroom	yes	W1	Sheetrock	Purple	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Girl's Restroom	yes	W2	Sheetrock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Girl's Restroom	yes	W2	Sheetrock	Purple	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Girl's Restroom	yes	W3	Sheetrock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Girl's Restroom	yes	W3	Sheetrock	Purple	Chipping	2	0.03	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	

School District of Philadelphia
Lead Safe Certification Assessment Report
Trinidad Head Start School

		Name of Inspector: Melissa Billingsley Inspection Company: Criterion Labs., Inc															Inspection Dates: 07/09-7/11/2019 ULCS# 7514						
Element	Fl oor	On-Site Room Name	Student/Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/negative)	Additional Component	Substrate Material	Color	Description of Paint and Plaster Damage	Additional Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Additional Component XRF (positive/negative)	Debris Present (describe location)	Quantity (sf)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Comments/ Description/ Notes
1	2	Girls Restroom	yes	W4	Sheetrock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Girls Restroom	yes	W4	Sheetrock	Purple	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Girls Restroom	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	Lay-in Tiles
1	2	Girls Restroom	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	12x12 tile
1	2	Vestibule between End Stairwell and Hallway outside Boy's and Girl's Restrooms	yes	W1	Sheetrock	Green	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Vestibule between End Stairwell and Hallway outside Boy's and Girl's Restrooms	yes	W1	Sheetrock	Blue	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Vestibule between End Stairwell and Hallway outside Boy's and Girl's Restrooms	yes	W2	Sheetrock	Green	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Vestibule between End Stairwell and Hallway outside Boy's and Girl's Restrooms	yes	W2	Sheetrock	Blue	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Vestibule between End Stairwell and Hallway outside Boy's and Girl's Restrooms	yes	W3	Sheetrock	Green	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Vestibule between End Stairwell and Hallway outside Boy's and Girl's Restrooms	yes	W3	Sheetrock	Blue	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Vestibule between End Stairwell and Hallway outside Boy's and Girl's Restrooms	yes	W4	Sheetrock	Green	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Vestibule between End Stairwell and Hallway outside Boy's and Girl's Restrooms	yes	W4	Sheetrock	Blue	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Vestibule between End Stairwell and Hallway outside Boy's and Girl's Restrooms	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	Lay-in Tile
1	2	Vestibule between End Stairwell and Hallway outside Boy's and Girl's Restrooms	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	12x12 tile
1	2	End Stairwell	yes	W1	Sheetrock	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	End Stairwell	yes	W1	Sheetrock	Blue	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	End Stairwell	yes	W2	Sheetrock	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	End Stairwell	yes	W2	Sheetrock	Blue	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	End Stairwell	yes	W3	Sheetrock	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	End Stairwell	yes	W3	Sheetrock	Blue	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	End Stairwell	yes	W4	Sheetrock	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	End Stairwell	yes	W4	Sheetrock	Blue	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	End Stairwell	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	Lay-in Tile
1	2	End Stairwell	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	12x12 tile
1	2	Gym	yes	W1	Sheetrock	Blue	Friction	5	0.01	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Gym	yes	W2	Sheetrock	Blue	Friction	5	0.02	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Gym	yes	W3	Sheetrock	Blue	Friction	5	0.01	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Gym	yes	W4	Sheetrock	Blue	Friction	5	0.01	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Gym	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	Lay-in tiles
1	2	Gym	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	9x9 and 12x12 tiles
1	2	Gym Storage Room	yes	W1	Sheetrock	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	Unpainted walls
1	2	Gym Storage Room	yes	W2	Sheetrock	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	Unpainted walls
1	2	Gym Storage Room	yes	W3	Sheetrock	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	Unpainted walls
1	2	Gym Storage Room	yes	W4	Sheetrock	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	Unpainted walls
1	2	Gym Storage Room	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	Lay-in tiles
1	2	Gym Storage Room	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	9x9 tiles
1	2	Classroom 6	yes	W1	Sheetrock	Green	Chipping	3	0.03	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Classroom 6	yes	W2	Sheetrock	Blue	Chipping	3	0.01	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Classroom 6	yes	W3	Sheetrock	Green	Chipping	3	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Classroom 6	yes	W4	Sheetrock	Blue	Chipping	3	0.01	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Classroom 6	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	Lay-in Tile
1	2	Classroom 6	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	9x9 tiles
1	2	Library	yes	W1	Sheetrock	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	Walls also have a mural on them. Multiple colors
1	2	Library	yes	W2	Sheetrock	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	Walls also have a mural on them. Multiple colors
1	2	Library	yes	W3	Sheetrock	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	Walls also have a mural on them. Multiple colors
1	2	Library	yes	W4	Sheetrock	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	Walls also have a mural on them. Multiple colors
1	2	Library	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	Lay-in Tiles
1	2	Library	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	Carpet
1	2	Center Stairwell	yes	W1	Sheetrock	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Center Stairwell	yes	W1	Sheetrock	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Center Stairwell	yes	W2	Sheetrock	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Center Stairwell	yes	W2	Sheetrock	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Center Stairwell	yes	W3	Sheetrock	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Center Stairwell	yes	W3	Sheetrock	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Center Stairwell	yes	W4	Sheetrock	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Center Stairwell	yes	W4	Sheetrock	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Center Stairwell	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	Lay-in Tile
1	2	Center Stairwell	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	Carpet and 12x12 tile
1	2	Hallway from Storage Rooms Hall to Center Sta	no	W1	Sheetrock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Hallway from Storage Rooms Hall to Center Sta	no	W2	Sheetrock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	

**School District of Philadelphia
Lead Safe Certification Assessment Report
Trinidad Head Start School**

		Name of Inspector: Melissa Billingsley Inspection Company: Criterion Labs., Inc												Inspection Dates: 07/09-7/11/2019 ULCS# 7514									
Element	Floor	On-Site Room Name	Student/Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/negative)	Additional Component	Substrate Material	Color	Description of Paint and Plaster Damage	Additional Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Additional Component XRF (positive/negative)	Debris Present (describe location)	Quantity (sf)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Comments/ Description/ Notes
1	2	Hallway from Storage Rooms Hall to Center Sta	no	W3	Sheetrock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Hallway from Storage Rooms Hall to Center Sta	no	W4	Sheetrock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Hallway from Storage Rooms Hall to Center Sta	no	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	Lay-in Tile
1	2	Hallway from Storage Rooms Hall to Center Sta	no	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	Carpet