

		School District of Philadelphia Rhawnhurst Elementary School 7809 Castor Avenue, Philadelphia, PA 19152 ULCS# 8360 Year Built: 1949		AHERA Three-Year Reinspection 2018-2019 Room by Room Location Log Report Red= Confirmed (Contact OEMS prior to the disturbance of any of the following materials and report damage) Yellow= Assumed (Contact OEMS for assessment and sampling prior to the disturbance of these materials and report damage) Green= Non Asbestos Containing/Non Suspect Material (These materials have been sampled and Laboratory Analysis has indicated NO Asbestos present or NO ASBESTOS DETECTED or these materials are not typically known to contain Asbestos)																				
<i>E</i>	<i>l</i>	<i>e</i>	<i>m</i>	<i>e</i>	<i>n</i>	<i>t</i>	<i>F</i>	<i>l</i>	<i>o</i>	<i>r</i>	<i>S</i>	<i>pace</i>	<i>#</i>	<i>On Site Room Name</i>	<i>Material Description</i>	<i>Confirmed/Assumed/NAD/Non Suspect ACM</i>	<i>Amount of Material</i>	<i>SF</i>	<i>LF</i>	<i>EA</i>	<i>Amount of Damage</i>	<i>SF</i>	<i>LF</i>	<i>EA</i>
1	1	103CCL	Principal's Conference Room - Closet	Spline Ceiling Glue Dots	Confirmed	2	SF	0	SF															
1	1	103CCL	Principal's Conference Room - Closet	Pipe Insulation 2-6 inch	Confirmed	16	LF	0	LF															
1	1	103CCL	Principal's Conference Room - Closet	Plaster Walls	NAD	80	SF	0	SF															
1	1	103CCL	Principal's Conference Room - Closet	Floor Tile VAT 9" x 9"	Confirmed	12	SF	0	SF															
1	1	103PH	Hallway between Main Office and Principal's Office	Fiberglass Ceiling Tile 1' x 1'	Non Suspect ACM	35	SF	0	SF															
1	1	103PH	Hallway between Main Office and Principal's Office	Spline Ceiling Glue Dots	Confirmed	8	SF	0	SF															
1	1	103PH	Hallway between Main Office and Principal's Office	Plaster Walls	NAD	125	SF	0	SF															
1	1	103PH	Hallway between Main Office and Principal's Office	Floor Tile VAT 12" x 12"	Assumed	35	SF	0	SF															
1	1	103SR	Main Office Storage Room (between Main Office and Principal's Office)	Concrete Ceiling	Non Suspect ACM	48	SF	0	SF															
1	1	103SR	Main Office Storage Room (between Main Office and Principal's Office)	CMU	Non Suspect ACM	330	SF	0	SF															
1	1	103SR	Main Office Storage Room (between Main Office and Principal's Office)	Cement Floor	Non Suspect ACM	48	SF	0	SF															
1	1	103RR	Principal's Restroom	Plaster Ceiling	NAD	25	SF	0	SF															
1	1	103RR	Principal's Restroom	Plaster Walls	NAD	90	SF	0	SF															
1	1	103RR	Principal's Restroom	Ceramic Tile Walls	Non Suspect ACM	90	SF	0	SF															
1	1	103RR	Principal's Restroom	Ceramic Tile Floors	Non Suspect ACM	25	SF	0	SF															
1	1	103B	Main Office	Fiberglass Ceiling Tile 1' x 1'	Non Suspect ACM	100	SF	0	SF															
1	1	103B	Main Office	Spline Ceiling Glue Dots	Confirmed	10	SF	0	SF															
1	1	103B	Main Office	Floor Tile VAT 12" x 12"	Assumed	100	SF	0	SF															
1	1	103B	Main Office	Plaster Walls	NAD	350	SF	0	SF															
1	1	103BB	Custodial Closet next to Girl's Restroom	Floor Tile VAT 9" x 9"	Confirmed	36	SF	0	SF															
1	1	103BB	Custodial Closet next to Girl's Restroom	Concrete Ceiling	Non Suspect ACM	36	SF	0	SF															
1	1	103BB	Custodial Closet next to Girl's Restroom	CMU	Non Suspect ACM	240	SF	0	SF															
1	1	103SO	Secretary's Office in Main Office	Concrete Ceiling	Non Suspect ACM	36	SF	0	SF															
1	1	103SO	Secretary's Office in Main Office	CMU	Non Suspect ACM	240	SF	0	SF															
1	1	103SO	Secretary's Office in Main Office	Floor Tile VAT 12" x 12"	Assumed	36	SF	0	SF															
1	1	103RH	Rear Hallway to Principal's Conference Room (copier location)	Ceiling Tile 2' x 4'	Non Suspect ACM	48	SF	0	SF															
1	1	103RH	Rear Hallway to Principal's Conference Room (copier location)	CMU	Non Suspect ACM	250	SF	0	SF															
1	1	103RH	Rear Hallway to Principal's Conference Room (copier location)	Floor Tile VAT 12" x 12"	Assumed	48	SF	0	SF															
1	1	103CLL	Closet on Left in Rear Hallway to Principal's Conference Room (copier location)	Ceiling Tile 1' x 1'	Non Suspect ACM	10	SF	0	SF															
1	1	103CLL	Closet on Left in Rear Hallway to Principal's Conference Room (copier location)	Spline Ceiling Glue Dots	Confirmed	2	SF	0	SF															
1	1	103CLL	Closet on Left in Rear Hallway to Principal's Conference Room (copier location)	Concrete Block Wall	Non Suspect ACM	70	SF	0	SF															
1	1	103CLL	Closet on Left in Rear Hallway to Principal's Conference Room (copier location)	Floor Tile VAT 9" x 9"	Confirmed	10	SF	0	SF															
1	1	103CLR	Closet on Left in Rear Hallway to Principal's Conference Room (copier location)	Ceiling Tile 1' x 1'	Non Suspect ACM	10	SF	0	SF															
1	1	103CLR	Closet on Left in Rear Hallway to Principal's Conference Room (copier location)	Spline Ceiling Glue Dots	Confirmed	2	SF	0	SF															
1	1	103CLR	Closet on Left in Rear Hallway to Principal's Conference Room (copier location)	Concrete Block Wall	Non Suspect ACM	70	SF	0	SF															
1	1	103CLR	Closet on Left in Rear Hallway to Principal's Conference Room (copier location)	Floor Tile VAT 9" x 9"	Confirmed	10	SF	0	SF															
1	1	103A	Girl's Restroom next to Classroom 103	Pipe Fitting Insulation	Confirmed	1	EA	0	EA															
1	1	103A	Girl's Restroom next to Classroom 103	Pipe Insulation 2-6 inch	Confirmed	5	LF	0	LF															
1	1	103A	Girl's Restroom next to Classroom 103	Fiberglass Pipe Insulation	Non Suspect ACM	20	LF	0	LF															
1	1	103A	Girl's Restroom next to Classroom 103	Concrete Ceiling	Non Suspect ACM	207	SF	0	SF															
1	1	103A	Girl's Restroom next to Classroom 103	Cement Floor	Non Suspect ACM	207	SF	0	SF															
1	1	103A	Girl's Restroom next to Classroom 103	CMU	Non Suspect ACM	768	SF	0	SF															
1	1	S15	Stairwell adjacent to Classroom 108	Pipe Insulation 2-6 inch	Confirmed	4	LF	0	LF															
1	1	S15	Stairwell adjacent to Classroom 108	Concrete Ceiling	Non Suspect ACM	250	SF	0	SF															
1	1	S15	Stairwell adjacent to Classroom 108	Concrete Wall	Non Suspect ACM	700	SF	0	SF															
1	1	S15	Stairwell adjacent to Classroom 108	Radiator Insulation	Assumed	24	SF	0	SF															
1	1	S15	Stairwell adjacent to Classroom 108	Cement Floor	Non Suspect ACM	250	SF	0	SF															
1	1	108	Classroom 108	Pipe Fitting Insulation	Confirmed	16	EA	0	EA															
1	1	108	Classroom 108	Pipe Insulation 2-6 inch	Confirmed	60	LF	0	LF															
1	1	108	Classroom 108	Fiberglass Ceiling Tile 1' x 1'	Non Suspect ACM	40	SF	0	SF															
1	1	108	Classroom 108	Spline Ceiling Glue Dots	Confirmed	4	SF	0	SF															
1	1	108	Classroom 108	Floor Tile VAT 9" x 9"	Confirmed	1144	SF	0	SF															
1	1	108	Classroom 108	Concrete Ceiling	Non Suspect ACM	1144	SF	0	SF															
1	1	108	Classroom 108	CMU	Non Suspect ACM	1680	SF	0	SF															
1	1	108RC	Classroom 108 Front Right Closet	Ceiling Tile 1' x 1'	Non Suspect ACM	8	SF	0	SF															
1	1	108RC	Classroom 108 Front Right Closet	Spline Ceiling Glue Dots	Confirmed	2	SF	0	SF															
1	1	108RC	Classroom 108 Front Right Closet	CMU	Non Suspect ACM	60	SF	0	SF															
1	1	108RC	Classroom 108 Front Right Closet	Floor Tile VAT 9" x 9"	Confirmed	8	SF	0	SF															
1	1	108LC	Classroom 108 Front Left Closet	Ceiling Tile 1' x 1'	Non Suspect ACM	8	SF	0	SF															
1	1	108LC	Classroom 108 Front Left Closet	Spline Ceiling Glue Dots	Confirmed	2	SF	0	SF															
1	1	108LC	Classroom 108 Front Left Closet	CMU	Non Suspect ACM	60	SF	0	SF															
1	1	108LC	Classroom 108 Front Left Closet	Floor Tile VAT 9" x 9"	Confirmed	8	SF	0	SF															
1	1	103	Classroom 103	Pipe Fitting Insulation	Confirmed	8	EA	0	EA															
1	1	103	Classroom 103	Pipe Insulation 2-6 inch	Confirmed	52	LF	0	LF															
1	1	103	Classroom 103	Fiberglass Ceiling Tile 1' x 1'	Non Suspect ACM	48	SF	0	SF															
1	1	103	Classroom 103	Spline Ceiling Glue Dots	Confirmed	5	SF	0	SF															
1	1	103	Classroom 103	Floor Tile VAT 9" x 9"	Confirmed	1130	SF	0	SF															
1	1	103	Classroom 103	Floor Tile VAT 12" x 12"	Assumed	14	SF	0	SF															

		School District of Philadelphia Rhawnhurst Elementary School 7809 Castor Avenue, Philadelphia, PA 19152 ULCS# 8360 Year Built: 1949		AHERA Three-Year Reinspection 2018-2019 Room by Room Location Log Report Red= Confirmed (Contact OEMS prior to the disturbance of any of the following materials and report damage) Yellow= Assumed (Contact OEMS for assessment and sampling prior to the disturbance of these materials and report damage) Green= Non Asbestos Containing/Non Suspect Material (These materials have been sampled and Laboratory Analysis has indicated NO Asbestos present or NO ASBESTOS DETECTED or these materials are not typically known to contain Asbestos)									
<i>E</i>	<i>l</i>	<i>F</i>	<i>l</i>	<i>o</i>	<i>o</i>	<i>R</i>	<i>o</i>	<i>o</i>	<i>R</i>	<i>o</i>	<i>R</i>	<i>o</i>	<i>R</i>
<i>m</i>	<i>e</i>	<i>l</i>	<i>o</i>	<i>o</i>	<i>o</i>	<i>o</i>	<i>o</i>	<i>o</i>	<i>o</i>	<i>o</i>	<i>o</i>	<i>o</i>	<i>o</i>
<i>n</i>	<i>n</i>	<i>o</i>	<i>o</i>	<i>o</i>	<i>o</i>	<i>o</i>	<i>o</i>	<i>o</i>	<i>o</i>	<i>o</i>	<i>o</i>	<i>o</i>	<i>o</i>
<i>t</i>	<i>n</i>	<i>o</i>	<i>o</i>	<i>o</i>	<i>o</i>	<i>o</i>	<i>o</i>	<i>o</i>	<i>o</i>	<i>o</i>	<i>o</i>	<i>o</i>	<i>o</i>
			Space #	On Site Room Name	Material Description	Confirmed/Assumed/NAD/ Non Suspect ACM	Amount of Material	SF LF EA	Amount of Damage	SF LF EA			
1	1		103	Classroom 103	Concrete Ceiling	Non Suspect ACM	1144	SF	0	SF			
1	1		103	Classroom 103	CMU	Non Suspect ACM	1680	SF	0	SF			
1	1		103RC	Classroom 103 Front Right Closet	Ceiling Tile 1' x 1'	Non Suspect ACM	8	SF	0	SF			
1	1		103RC	Classroom 103 Front Right Closet	Spline Ceiling Glue Dots	Confirmed	2	SF	0	SF			
1	1		103RC	Classroom 103 Front Right Closet	CMU	Non Suspect ACM	60	SF	0	SF			
1	1		103RC	Classroom 103 Front Right Closet	Floor Tile VAT 9" x 9"	Confirmed	8	SF	0	SF			
1	1		103LC	Classroom 103 Front Left Closet	Pipe Insulation 2-6 inch	Confirmed	7	LF	0	LF			
1	1		103LC	Classroom 103 Front Left Closet	Ceiling Tile 1' x 1'	Non Suspect ACM	8	SF	0	SF			
1	1		103LC	Classroom 103 Front Left Closet	Spline Ceiling Glue Dots	Confirmed	2	SF	0	SF			
1	1		103LC	Classroom 103 Front Left Closet	CMU	Non Suspect ACM	60	SF	0	SF			
1	1		103LC	Classroom 103 Front Left Closet	Floor Tile VAT 9" x 9"	Confirmed	8	SF	0	SF			
1	1		107	Classroom 107	Fiberglass Ceiling Tile 1' x 1'	Non Suspect ACM	48	SF	0	SF			
1	1		107	Classroom 107	Spline Ceiling Glue Dots	Confirmed	5	SF	0	SF			
1	1		107	Classroom 107	Floor Tile VAT 9" x 9"	Confirmed	1132	SF	0	SF			
1	1		107	Classroom 107	Floor Tile VAT 12" x 12"	Assumed	12	SF	0	SF			
1	1		107	Classroom 107	Concrete Ceiling	Non Suspect ACM	1144	SF	0	SF			
1	1		107	Classroom 107	CMU	Non Suspect ACM	1680	SF	0	SF			
1	1		107RC	Classroom 107 Front Right Closet	Ceiling Tile 1' x 1'	Non Suspect ACM	8	SF	0	SF			
1	1		107RC	Classroom 107 Front Right Closet	Spline Ceiling Glue Dots	Confirmed	2	SF	0	SF			
1	1		107RC	Classroom 107 Front Right Closet	CMU	Non Suspect ACM	60	SF	0	SF			
1	1		107RC	Classroom 107 Front Right Closet	Floor Tile VAT 9" x 9"	Confirmed	8	SF	0	SF			
1	1		107LC	Classroom 107 Front Left Closet	Ceiling Tile 1' x 1'	Non Suspect ACM	8	SF	0	SF			
1	1		107LC	Classroom 107 Front Left Closet	Spline Ceiling Glue Dots	Confirmed	2	SF	0	SF			
1	1		107LC	Classroom 107 Front Left Closet	CMU	Non Suspect ACM	60	SF	0	SF			
1	1		107LC	Classroom 107 Front Left Closet	Floor Tile VAT 9" x 9"	Confirmed	8	SF	0	SF			
1	1		104	Classroom 104	Fiberglass Ceiling Tile 1' x 1'	Non Suspect ACM	40	SF	0	SF			
1	1		104	Classroom 104	Spline Ceiling Glue Dots	Confirmed	4	SF	0	SF			
1	1		104	Classroom 104	Floor Tile VAT 9" x 9"	Confirmed	1126	SF	0	SF			
1	1		104	Classroom 104	Floor Tile VAT 12" x 12"	Assumed	18	SF	0	SF			
1	1		104	Classroom 104	Concrete Ceiling	Non Suspect ACM	1144	SF	0	SF			
1	1		104	Classroom 104	CMU	Non Suspect ACM	1680	SF	0	SF			
1	1		104RC	Classroom 104 Front Right Closet	Ceiling Tile 1' x 1'	Non Suspect ACM	8	SF	0	SF			
1	1		104RC	Classroom 104 Front Right Closet	Spline Ceiling Glue Dots	Confirmed	2	SF	0	SF			
1	1		104RC	Classroom 104 Front Right Closet	CMU	Non Suspect ACM	60	SF	0	SF			
1	1		104RC	Classroom 104 Front Right Closet	Floor Tile VAT 9" x 9"	Confirmed	8	SF	0	SF			
1	1		104LC	Classroom 104 Front Left Closet	Ceiling Tile 1' x 1'	Non Suspect ACM	8	SF	0	SF			
1	1		104LC	Classroom 104 Front Left Closet	Spline Ceiling Glue Dots	Confirmed	2	SF	0	SF			
1	1		104LC	Classroom 104 Front Left Closet	CMU	Non Suspect ACM	60	SF	0	SF			
1	1		104LC	Classroom 104 Front Left Closet	Floor Tile VAT 9" x 9"	Confirmed	8	SF	0	SF			
1	1		105A	Boy's Restroom next to Classroom 105	Concrete Ceiling	Non Suspect ACM	170	SF	0	SF			
1	1		105A	Boy's Restroom next to Classroom 105	Cement Floor	Non Suspect ACM	170	SF	0	SF			
1	1		105A	Boy's Restroom next to Classroom 105	CMU	Non Suspect ACM	648	SF	0	SF			
1	1		105B	Closet next to Classroom 105	Concrete Ceiling	Non Suspect ACM	54	SF	0	SF			
1	1		105B	Closet next to Classroom 105	CMU	Non Suspect ACM	300	SF	0	SF			
1	1		105B	Closet next to Classroom 105	Floor Tile VAT 9" x 9"	Confirmed	54	SF	0	SF			
1	1		106	Classroom 106	Fiberglass Ceiling Tile 1' x 1'	Non Suspect ACM	872	SF	0	SF			
1	1		106	Classroom 106	Ceiling Tile 1' x 1'	NAD	35	SF	0	SF			
1	1		106	Classroom 106	Ceiling Tile 1' x 1'	NAD	46	SF	0	SF			
1	1		106	Classroom 106	Ceiling Tile 1' x 1'	NAD	29	SF	0	SF			
1	1		106	Classroom 106	Spline Ceiling Glue Dots	Confirmed	100	SF	0	SF			
1	1		106	Classroom 106	Floor Tile VAT 9" x 9"	Confirmed	1014	SF	0	SF			
1	1		106	Classroom 106	CMU	Non Suspect ACM	1560	SF	0	SF			
1	1		106RC	Classroom 106 Front Right Closet	Ceiling Tile 1' x 1'	Non Suspect ACM	8	SF	0	SF			
1	1		106RC	Classroom 106 Front Right Closet	Spline Ceiling Glue Dots	Confirmed	2	SF	0	SF			
1	1		106RC	Classroom 106 Front Right Closet	CMU	Non Suspect ACM	60	SF	0	SF			
1	1		106RC	Classroom 106 Front Right Closet	Floor Tile VAT 9" x 9"	Confirmed	8	SF	0	SF			
1	1		106LC	Classroom 106 Front Left Closet	Ceiling Tile 1' x 1'	Non Suspect ACM	8	SF	0	SF			
1	1		106LC	Classroom 106 Front Left Closet	Spline Ceiling Glue Dots	Confirmed	2	SF	0	SF			
1	1		106LC	Classroom 106 Front Left Closet	CMU	Non Suspect ACM	60	SF	0	SF			
1	1		106LC	Classroom 106 Front Left Closet	Floor Tile VAT 9" x 9"	Confirmed	8	SF	0	SF			
1	1		105	Classroom 105	Fiberglass Ceiling Tile 1' x 1'	Non Suspect ACM	48	SF	0	SF			
1	1		105	Classroom 105	Spline Ceiling Glue Dots	Confirmed	5	SF	0	SF			
1	1		105	Classroom 105	Floor Tile VAT 9" x 9"	Confirmed	1144	SF	0	SF			
1	1		105	Classroom 105	Concrete Ceiling	Non Suspect ACM	1144	SF	0	SF			
1	1		105	Classroom 105	CMU	Non Suspect ACM	1680	SF	0	SF			
1	1		105CL	Classroom 105 - Closet by Door	Fiberglass Ceiling Tile 1' x 1'	Non Suspect ACM	15	SF	0	SF			
1	1		105CL	Classroom 105 - Closet by Door	Spline Ceiling Glue Dots	Confirmed	3	SF	0	SF			
1	1		105CL	Classroom 105 - Closet by Door	Floor Tile VAT 9" x 9"	Confirmed	15	SF	0	SF			
1	1		105CL	Classroom 105 - Closet by Door	CMU	Non Suspect ACM	100	SF	0	SF			
1	1		S13	Exit Foyer near Classrooms 105 and 106	Ceiling Tile 2' x 4'	Non Suspect ACM	68	SF	0	SF			
1	1		S13	Exit Foyer near Classrooms 105 and 106	Cement Floor	Non Suspect ACM	68	SF	0	SF			
1	1		S13	Exit Foyer near Classrooms 105 and 106	Radiator Insulation	Assumed	24	SF	0	SF			
1	1		S13	Exit Foyer near Classrooms 105 and 106	CMU	Non Suspect ACM	264	SF	0	SF			
1	1		H13	Hallway from Lobby by Main Office to Classroom 105	Fiberglass Ceiling Tile 1' x 1'	Non Suspect ACM	1323	SF	10	SF			
1	1		H13	Hallway from Lobby by Main Office to Classroom 105	Spline Ceiling Glue Dots	Confirmed	132	SF	0	SF			
1	1		H13	Hallway from Lobby by Main Office to Classroom 105	Floor Tile VAT 9" x 9"	Confirmed	1323	SF	0	SF			
1	1		H13	Hallway from Lobby by Main Office to Classroom 105	Radiator Insulation	Assumed	72	SF	0	SF			
1	1		H13	Hallway from Lobby by Main Office to Classroom 105	CMU	Non Suspect ACM	3120	SF	0	SF			
1	1		H12	Hallway between Main Entrance and Auditorium	Fiberglass Ceiling Tile 1' x 1'	Non Suspect ACM	1230	SF	0	SF			
1	1		H12	Hallway between Main Entrance and Auditorium	Spline Ceiling Glue Dots	Confirmed	123	SF	0	SF			
1	1		H12	Hallway between Main Entrance and Auditorium	Floor Tile VAT 9" x 9"	Confirmed	1230	SF	0	SF			

		School District of Philadelphia Rhawnhurst Elementary School 7809 Castor Avenue, Philadelphia, PA 19152 ULCS# 8360 Year Built: 1949		AHERA Three-Year Reinspection 2018-2019 Room by Room Location Log Report Red= Confirmed (Contact OEMS prior to the disturbance of any of the following materials and report damage) Yellow= Assumed (Contact OEMS for assessment and sampling prior to the disturbance of these materials and report damage) Green= Non Asbestos Containing/Non Suspect Material (These materials have been sampled and Laboratory Analysis has indicated NO Asbestos present or NO ASBESTOS DETECTED or these materials are not typically known to contain Asbestos)												
<i>E</i>	<i>l</i>	<i>F</i>	<i>l</i>	<i>o</i>	<i>r</i>	<i>S</i>	<i>o</i>	<i>C</i>	<i>o</i>	<i>A</i>	<i>M</i>	<i>S</i>	<i>F</i>	<i>L</i>	<i>F</i>	<i>A</i>
		<i>Space #</i>	<i>On Site Room Name</i>	<i>Material Description</i>	<i>Confirmed/Assumed/NAD/Non Suspect ACM</i>	<i>Amount of Material</i>	<i>SF</i>	<i>LF</i>	<i>EA</i>	<i>Amount of Damage</i>	<i>SF</i>	<i>LF</i>	<i>EA</i>			
1	1	H12	Hallway between Main Entrance and Auditorium	Concrete Wall	Non Suspect ACM	852	SF		0		SF					
1	1	H12	Hallway between Main Entrance and Auditorium	Wood Wall	Non Suspect ACM	568	SF		0		SF					
1	1	H11	Hallway from Nurse's Office to Classroom 110	Fiberglass Ceiling Tile 1' x 1'	Non Suspect ACM	1116	SF		0		SF					
1	1	H11	Hallway from Nurse's Office to Classroom 110	Spline Ceiling Glue Dots	Confirmed	112	SF		0		SF					
1	1	H11	Hallway from Nurse's Office to Classroom 110	Floor Tile VAT 9" x 9"	Confirmed	1116	SF		0		SF					
1	1	H11	Hallway from Nurse's Office to Classroom 110	Radiator Insulation	Assumed	30	SF		0		SF					
1	1	H11	Hallway from Nurse's Office to Classroom 110	CMU	Non Suspect ACM	2660	SF		0		SF					
1	1	H15	Hallway adjacent to the Left side of the Auditorium	Ceiling Tile 2' x 4'	Non Suspect ACM	576	SF		0		SF					
1	1	H15	Hallway adjacent to the Left side of the Auditorium	Floor Tile VAT 9" x 9"	Confirmed	576	SF		0		SF					
1	1	H15	Hallway adjacent to the Left side of the Auditorium	Radiator Insulation	Assumed	45	SF		0		SF					
1	1	H15	Hallway adjacent to the Left side of the Auditorium	CMU	Non Suspect ACM	640	SF		0		SF					
1	1	H16	Hallway between the Gym, Cafeteria, and Women's Restroom	Ceiling Tile 2' x 4'	Non Suspect ACM	468	SF		1		SF					
1	1	H16	Hallway between the Gym, Cafeteria, and Women's Restroom	Floor Tile VAT 9" x 9"	Confirmed	468	SF		0		SF					
1	1	H16	Hallway between the Gym, Cafeteria, and Women's Restroom	CMU	Non Suspect ACM	700	SF		0		SF					
1	1	114	Men's Restroom near Cafeteria	Concrete Ceiling	Non Suspect ACM	77	SF		0		SF					
1	1	114	Men's Restroom near Cafeteria	Cement Floor	Non Suspect ACM	77	SF		0		SF					
1	1	114	Men's Restroom near Cafeteria	CMU	Non Suspect ACM	360	SF		0		SF					
1	1	PC114	Pipe Chase in Men's Restroom near Cafeteria	X	X	X	X		X		X					
1	1	113	Women's Restroom near Cafeteria	Concrete Ceiling	Non Suspect ACM	110	SF		0		SF					
1	1	113	Women's Restroom near Cafeteria	Cement Floor	Non Suspect ACM	110	SF		0		SF					
1	1	113	Women's Restroom near Cafeteria	CMU	Non Suspect ACM	420	SF		0		SF					
1	1	PC113	Pipe Chase in Women's Restroom near Cafeteria	X	X	X	X		X		X					
1	1	112A	Storage in Kitchen Area	Concrete Ceiling	Non Suspect ACM	216	SF		0		SF					
1	1	112A	Storage in Kitchen Area	Cement Floor	Non Suspect ACM	216	SF		0		SF					
1	1	112A	Storage in Kitchen Area	CMU	Non Suspect ACM	924	SF		0		SF					
1	1	112H	Small Hallway between Kitchen and Storage Areas	Concrete Ceiling	Non Suspect ACM	36	SF		0		SF					
1	1	112H	Small Hallway between Kitchen and Storage Areas	CMU	Non Suspect ACM	200	SF		0		SF					
1	1	112H	Small Hallway between Kitchen and Storage Areas	Cement Floor	Non Suspect ACM	36	SF		0		SF					
1	1	112CL	Closets in Small Hallway between Kitchen and Storage Area	X	X	X	X		X		X					
1	1	112HH	Exit Foyer next to Hallway near Kitchen	Ceiling Tile 2' x 4'	Non Suspect ACM	72	SF		0		SF					
1	1	112HH	Exit Foyer next to Hallway near Kitchen	CMU	Non Suspect ACM	270	SF		0		SF					
1	1	112HH	Exit Foyer next to Hallway near Kitchen	Cement Floor	Non Suspect ACM	72	SF		0		SF					
1	1	112B	Kitchen	Concrete Ceiling	Non Suspect ACM	644	SF		0		SF					
1	1	112B	Kitchen	Cement Floor	Non Suspect ACM	644	SF		0		SF					
1	1	112B	Kitchen	CMU	Non Suspect ACM	1428	SF		0		SF					
1	1	112C	Storage adjacent to Kitchen Office	Concrete Ceiling	Non Suspect ACM	110	SF		0		SF					
1	1	112C	Storage adjacent to Kitchen Office	Cement Floor	Non Suspect ACM	110	SF		0		SF					
1	1	112C	Storage adjacent to Kitchen Office	CMU	Non Suspect ACM	588	SF		0		SF					
1	1	112D	Kitchen Office	Concrete Ceiling	Non Suspect ACM	165	SF		0		SF					
1	1	112D	Kitchen Office	Floor Tile VAT 9" x 9"	Confirmed	165	SF		0		SF					
1	1	112D	Kitchen Office	CMU	Non Suspect ACM	728	SF		0		SF					
1	1	112E	Cafeteria Serving Area	Ceiling Tile 2' x 4'	Non Suspect ACM	162	SF		0		SF					
1	1	112E	Cafeteria Serving Area	Cement Floor	Non Suspect ACM	162	SF		0		SF					
1	1	112E	Cafeteria Serving Area	CMU	Non Suspect ACM	432	SF		0		SF					
1	1	112	Cafeteria	Ceiling Tile 2' x 4'	Non Suspect ACM	2560	SF		0		SF					
1	1	112	Cafeteria	Floor Tile VAT 12" x 12"	Assumed	2560	SF		0		SF					
1	1	111	Gymnasium	CMU	Non Suspect ACM	3930	SF		0		SF					
1	1	111	Gymnasium	Pipe Fitting Insulation	Confirmed	2	EA		0		EA					
1	1	111	Gymnasium	Pipe Insulation 2-6 inch	Confirmed	4	LF		0		LF					
1	1	111	Gymnasium	Concrete Ceiling	Non Suspect ACM	4000	SF		0		SF					
1	1	111	Gymnasium	Wood Floor	Non Suspect ACM	4000	SF		0		SF					
1	1	111	Gymnasium	Radiator Insulation	Assumed	100	SF		0		SF					
1	1	111	Gymnasium	CMU	Non Suspect ACM	4420	SF		0		SF					
1	1	111D	Custodial Closet between Gym and Boy's Restroom	Steel Ceiling (Hatch)	Non Suspect ACM	9	SF		0		SF					
1	1	111D	Custodial Closet between Gym and Boy's Restroom	CMU	Non Suspect ACM	120	SF		0		SF					
1	1	111D	Custodial Closet between Gym and Boy's Restroom	Floor Tile VAT 9" x 9"	Confirmed	9	SF		0		SF					
1	1	111B	Boy's Restroom in Gym	Concrete Ceiling	Non Suspect ACM	405	SF		0		SF					
1	1	111B	Boy's Restroom in Gym	Cement Floor	Non Suspect ACM	405	SF		0		SF					
1	1	111B	Boy's Restroom in Gym	CMU	Non Suspect ACM	840	SF		0		SF					
1	1	PC111B	Pipe Chase in Boy's Restroom in Gym	X	X	X	X		X		X					
1	1	111C	Shower Area in Boy's Restroom in Gym	Concrete Ceiling	Non Suspect ACM	56	SF		0		SF					
1	1	111C	Shower Area in Boy's Restroom in Gym	Cement Floor	Non Suspect ACM	56	SF		0		SF					
1	1	111C	Shower Area in Boy's Restroom in Gym	CMU	Non Suspect ACM	300	SF		0		SF					
1	1	111A	Girl's Restroom in Gym	Concrete Ceiling	Non Suspect ACM	345	SF		0		SF					
1	1	111A	Girl's Restroom in Gym	Cement Floor	Non Suspect ACM	345	SF		0		SF					
1	1	111A	Girl's Restroom in Gym	CMU	Non Suspect ACM	760	SF		0		SF					
1	1	111E	Shower Area in Girl's Restroom in Gym	Concrete Ceiling	Non Suspect ACM	56	SF		0		SF					
1	1	111E	Shower Area in Girl's Restroom in Gym	Cement Floor	Non Suspect ACM	56	SF		0		SF					
1	1	111E	Shower Area in Girl's Restroom in Gym	CMU	Non Suspect ACM	300	SF		0		SF					
1	1	S16	Gym Office	Pipe Fitting Insulation	Confirmed	1	EA		0		EA					
1	1	S16	Gym Office	Pipe Insulation 2-6 inch	Confirmed	11	LF		0		LF					
1	1	S16	Gym Office	Concrete Ceiling	Non Suspect ACM	91	SF		0		SF					
1	1	S16	Gym Office	Cement Floor	Non Suspect ACM	91	SF		0		SF					
1	1	S16	Gym Office	CMU	Non Suspect ACM	400	SF		0		SF					
1	1	109B	Stage	Pipe Fitting Insulation	Confirmed	2	EA		0		EA					
1	1	109B	Stage	Pipe Insulation 2-6 inch	Confirmed	26	LF		0		LF					

		School District of Philadelphia Rhawhurst Elementary School 7809 Castor Avenue, Philadelphia, PA 19152 ULCS# 8360 Year Built: 1949		AHERA Three-Year Reinspection 2018-2019 Room by Room Location Log Report Red= Confirmed (Contact OEMS prior to the disturbance of any of the following materials and report damage) Yellow= Assumed (Contact OEMS for assessment and sampling prior to the disturbance of these materials and report damage) Green= Non Asbestos Containing/Non Suspect Material (These materials have been sampled and Laboratory Analysis has indicated NO Asbestos present or NO ASBESTOS DETECTED or these materials are not typically known to contain Asbestos)					
E l e m e n t	F l o o r	Space #	On Site Room Name	Material Description	Confirmed/Assumed/NAD/ Non Suspect ACM	Amount of Material	SF LF EA	Amount of Damage	SF LF EA
1	1	109B	Stage	Concrete Ceiling	Non Suspect ACM	740	SF	0	SF
1	1	109B	Stage	Wood Floor	Non Suspect ACM	740	SF	0	SF
1	1	109B	Stage	CMU	Non Suspect ACM	1771	SF	0	SF
1	1	109A	Auditorium	Fiberglass Pipe Fitting Insulation	Non Suspect ACM	6	EA	0	EA
1	1	109A	Auditorium	Fiberglass Pipe Insulation	Non Suspect ACM	88	LF	0	LF
1	1	109A	Auditorium	Ceiling Tile 6' x 8'	Non Suspect ACM	756	SF	0	SF
1	1	109A	Auditorium	Concrete Ceiling	Non Suspect ACM	4140	SF	0	SF
1	1	109A	Auditorium	Floor Tile VAT 12" x 12"	Assumed	1644	SF	0	SF
1	1	109A	Auditorium	Cement Floor	Non Suspect ACM	2496	SF	0	SF
1	1	109A	Auditorium	Auditorium Plaster Walls	NAD	3390	SF	0	SF
1	1	109A	Auditorium	Radiator Insulation	Assumed	120	SF	0	SF
1	1	109A	Auditorium	Wood Wall	Non Suspect ACM	1130	SF	0	SF
2	1	S19	Stairwell from Gym to Element 2 (A1-A6)	Fiberglass Pipe Insulation	Non Suspect ACM	18	LF	0	LF
2	1	S19	Stairwell from Gym to Element 2 (A1-A6)	Metal Panels (Ceiling)	Non Suspect ACM	95	SF	0	SF
2	1	S19	Stairwell from Gym to Element 2 (A1-A6)	Sheetrock Wall	Non Suspect ACM	63	SF	0	SF
2	1	S19	Stairwell from Gym to Element 2 (A1-A6)	Brick Wall	Non Suspect ACM	54	SF	0	SF
2	1	S19	Stairwell from Gym to Element 2 (A1-A6)	Floor Tile VAT 12" x 12"	Assumed	24	SF	0	SF
2	1	S19	Stairwell from Gym to Element 2 (A1-A6)	Cement Floor	Non Suspect ACM	48	SF	0	SF
2	1	H17	Hallway between Gym and Element 2 (A1-A6)	Pipe Fitting Insulation	Confirmed	6	EA	0	EA
2	1	H17	Hallway between Gym and Element 2 (A1-A6)	Fiberglass Pipe Insulation	Non Suspect ACM	49	LF	2	LF
2	1	H17	Hallway between Gym and Element 2 (A1-A6)	Metal Panels (Ceiling)	Non Suspect ACM	210	SF	0	SF
2	1	H17	Hallway between Gym and Element 2 (A1-A6)	Floor Tile VAT 12" x 12"	Assumed	210	SF	0	SF
2	1	H17	Hallway between Gym and Element 2 (A1-A6)	Sheetrock Wall	Non Suspect ACM	416	SF	0	SF
1	2	202	Classroom 202	Fiberglass Ceiling Tile 1' x 1'	Non Suspect ACM	52	SF	0	SF
1	2	202	Classroom 202	Spline Ceiling Glue Dots	Assumed	5	SF	0	SF
1	2	202	Classroom 202	Concrete Ceiling	Non Suspect ACM	1144	SF	0	SF
1	2	202	Classroom 202	CMU	Non Suspect ACM	1680	SF	0	SF
1	2	202	Classroom 202	Floor Tile VAT 9" x 9"	Confirmed	1080	SF	0	SF
1	2	202	Classroom 202	Floor Tile VAT 12" x 12"	Assumed	64	SF	0	SF
1	2	202RC	Classroom 202 Front Right Closet	Ceiling Tile 1' x 1'	Non Suspect ACM	10	SF	0	SF
1	2	202RC	Classroom 202 Front Right Closet	Spline Ceiling Glue Dots	Assumed	3	SF	0	SF
1	2	202RC	Classroom 202 Front Right Closet	CMU	Non Suspect ACM	72	SF	0	SF
1	2	202RC	Classroom 202 Front Right Closet	Floor Tile VAT 9" x 9"	Confirmed	10	SF	0	SF
1	2	202LC	Classroom 202 Front Left Closet	Ceiling Tile 1' x 1'	Non Suspect ACM	10	SF	0	SF
1	2	202LC	Classroom 202 Front Left Closet	Spline Ceiling Glue Dots	Assumed	3	SF	0	SF
1	2	202LC	Classroom 202 Front Left Closet	CMU	Non Suspect ACM	72	SF	0	SF
1	2	202LC	Classroom 202 Front Left Closet	Floor Tile VAT 9" x 9"	Confirmed	10	SF	0	SF
1	2	202A	Boy's Restroom	Concrete Ceiling	Non Suspect ACM	126	SF	0	SF
1	2	202A	Boy's Restroom	CMU	Non Suspect ACM	552	SF	0	SF
1	2	202A	Boy's Restroom	Cement Floor	Non Suspect ACM	126	SF	0	SF
1	2	203	Classroom 203	Fiberglass Ceiling Tile 1' x 1'	Non Suspect ACM	40	SF	0	SF
1	2	203	Classroom 203	Spline Ceiling Glue Dots	Assumed	4	SF	0	SF
1	2	203	Classroom 203	Concrete Ceiling	Non Suspect ACM	1144	SF	0	SF
1	2	203	Classroom 203	CMU	Non Suspect ACM	1680	SF	0	SF
1	2	203	Classroom 203	Floor Tile VAT 9" x 9"	Confirmed	1144	SF	0	SF
1	2	203RC	Classroom 203 Front Right Closet	Ceiling Tile 1' x 1'	Non Suspect ACM	10	SF	0	SF
1	2	203RC	Classroom 203 Front Right Closet	Spline Ceiling Glue Dots	Assumed	3	SF	0	SF
1	2	203RC	Classroom 203 Front Right Closet	CMU	Non Suspect ACM	72	SF	0	SF
1	2	203RC	Classroom 203 Front Right Closet	Floor Tile VAT 9" x 9"	Confirmed	10	SF	0	SF
1	2	203LC	Classroom 203 Front Left Closet	Ceiling Tile 1' x 1'	Non Suspect ACM	10	SF	0	SF
1	2	203LC	Classroom 203 Front Left Closet	Spline Ceiling Glue Dots	Assumed	3	SF	0	SF
1	2	203LC	Classroom 203 Front Left Closet	CMU	Non Suspect ACM	72	SF	0	SF
1	2	203LC	Classroom 203 Front Left Closet	Floor Tile VAT 9" x 9"	Confirmed	10	SF	0	SF
1	2	S25	Stairwell No. 1 adjacent to Classroom 203	Concrete Ceiling	Non Suspect ACM	250	SF	0	SF
1	2	S25	Stairwell No. 1 adjacent to Classroom 203	Concrete Wall	Non Suspect ACM	700	SF	0	SF
1	2	S25	Stairwell No. 1 adjacent to Classroom 203	Radiator Insulation	Assumed	12	SF	0	SF
1	2	S25	Stairwell No. 1 adjacent to Classroom 203	Cement Floor	Non Suspect ACM	250	SF	0	SF
1	2	203A	Reading Room	Concrete Ceiling	Non Suspect ACM	216	SF	0	SF
1	2	203A	Reading Room	CMU	Non Suspect ACM	792	SF	0	SF
1	2	203A	Reading Room	Carpet	Non Suspect ACM	216	SF	0	SF
1	2	202B	Custodial Closet next to Boy's Restroom	Concrete Ceiling	Non Suspect ACM	48	SF	0	SF
1	2	202B	Custodial Closet next to Boy's Restroom	CMU	Non Suspect ACM	336	SF	0	SF
1	2	202B	Custodial Closet next to Boy's Restroom	Floor Tile VAT 9" x 9"	Confirmed	48	SF	0	SF
1	2	PC202B	Pipe Chase in Custodial Closet next to Boy's Restroom	X	X	X	X	X	X
1	2	201B	ESOL	Fiberglass Ceiling Tile 1' x 1'	Non Suspect ACM	144	SF	0	SF
1	2	201B	ESOL	Spline Ceiling Glue Dots	Assumed	14	SF	0	SF
1	2	201B	ESOL	CMU	Non Suspect ACM	500	SF	0	SF
1	2	201B	ESOL	Floor Tile VAT 9" x 9"	Confirmed	144	SF	0	SF
1	2	201D	ESOL Closet	Fiberglass Ceiling Tile 1' x 1'	Non Suspect ACM	10	SF	0	SF
1	2	201D	ESOL Closet	Spline Ceiling Glue Dots	Assumed	1	SF	0	SF
1	2	201D	ESOL Closet	CMU	Non Suspect ACM	72	SF	0	SF
1	2	201D	ESOL Closet	Floor Tile VAT 9" x 9"	Confirmed	10	SF	0	SF
1	2	201C	Staff Restroom by ESOL Room	Concrete Ceiling	Non Suspect ACM	30	SF	0	SF
1	2	201C	Staff Restroom by ESOL Room	Concrete Wall	Non Suspect ACM	90	SF	0	SF
1	2	201C	Staff Restroom by ESOL Room	Ceramic Tile Walls	Non Suspect ACM	90	SF	0	SF
1	2	201C	Staff Restroom by ESOL Room	Ceramic Tile Floors	Non Suspect ACM	30	SF	0	SF
1	2	H27A	Hallway to ESOL Room from Main Hallway	Fiberglass Ceiling Tile 1' x 1'	Non Suspect ACM	45	SF	0	SF
1	2	H27A	Hallway to ESOL Room from Main Hallway	Spline Ceiling Glue Dots	Assumed	5	SF	0	SF
1	2	H27A	Hallway to ESOL Room from Main Hallway	CMU	Non Suspect ACM	295	SF	0	SF
1	2	H27A	Hallway to ESOL Room from Main Hallway	Floor Tile VAT 9" x 9"	Confirmed	45	SF	0	SF
1	2	205	Fan Room across from Library	Fiberglass Pipe Insulation	Non Suspect ACM	100	LF	0	LF
1	2	205	Fan Room across from Library	Fiberglass Pipe Fitting Insulation	Non Suspect ACM	25	EA	0	EA
1	2	205	Fan Room across from Library	Concrete Ceiling	Non Suspect ACM	300	SF	0	SF
1	2	205	Fan Room across from Library	CMU	Non Suspect ACM	1344	SF	0	SF

		School District of Philadelphia Rhawnhurst Elementary School 7809 Castor Avenue, Philadelphia, PA 19152 ULCS# 8360 Year Built: 1949		AHERA Three-Year Reinspection 2018-2019 Room by Room Location Log Report Red= Confirmed (Contact OEMS prior to the disturbance of any of the following materials and report damage) Yellow= Assumed (Contact OEMS for assessment and sampling prior to the disturbance of these materials and report damage) Green= Non Asbestos Containing/Non Suspect Material (These materials have been sampled and Laboratory Analysis has indicated NO Asbestos present or NO ASBESTOS DETECTED or these materials are not typically known to contain Asbestos)													
<i>E</i>	<i>l</i>	<i>F</i>	<i>l</i>	<i>o</i>	<i>r</i>	<i>C</i>	<i>A</i>	<i>M</i>	<i>S</i>	<i>F</i>	<i>L</i>	<i>A</i>	<i>M</i>	<i>S</i>	<i>F</i>	<i>L</i>	<i>A</i>
		Space #	On Site Room Name	Material Description		Confirmed/Assumed/NAD/ Non Suspect ACM	Amount of Material	SF	LF	EA	Amount of Damage	SF	LF	EA			
1	2	205	Fan Room across from Library	Cement Floor		Non Suspect ACM	300	SF	0	SF							
1	2	201	IMC/Library	Fiberglass Ceiling Tile 1' x 1'		Non Suspect ACM	1260	SF	0	SF							
1	2	201	IMC/Library	Spline Ceiling Glue Dots		Assumed	126	SF	0	SF							
1	2	201	IMC/Library	Concrete Wall		Non Suspect ACM	1728	SF	0	SF							
1	2	201	IMC/Library	Floor Tile VAT 12" x 12"		Assumed	1260	SF	0	SF							
1	2	201A	Teacher Lounge/Dining	Concrete Ceiling		Non Suspect ACM	198	SF	0	SF							
1	2	201A	Teacher Lounge/Dining	CMU		Non Suspect ACM	744	SF	0	SF							
1	2	201A	Teacher Lounge/Dining	Floor Tile VAT 12" x 12"		Assumed	198	SF	0	SF							
1	2	201AB	Computer Server Room in 201A	Concrete Ceiling		Non Suspect ACM	54	SF	0	SF							
1	2	201AB	Computer Server Room in 201A	CMU		Non Suspect ACM	360	SF	0	SF							
1	2	201AB	Computer Server Room in 201A	Floor Tile VAT 9" x 9"		Confirmed	54	SF	0	SF							
1	2	203B	Reading Room	Concrete Ceiling		Non Suspect ACM	234	SF	0	SF							
1	2	203B	Reading Room	CMU		Non Suspect ACM	840	SF	0	SF							
1	2	203B	Reading Room	Floor Tile VAT 9" x 9"		Confirmed	234	SF	0	SF							
1	2	S213	Stairwell No. 2 adjacent to Classroom 204	Concrete Ceiling		Non Suspect ACM	171	SF	0	SF							
1	2	S213	Stairwell No. 2 adjacent to Classroom 204	Cement Floor		Non Suspect ACM	171	SF	0	SF							
1	2	S213	Stairwell No. 2 adjacent to Classroom 204	Radiator Insulation		Assumed	12	SF	0	SF							
1	2	S213	Stairwell No. 2 adjacent to Classroom 204	CMU		Non Suspect ACM	800	SF	0	SF							
1	2	200A	Girl's Restroom	Concrete Ceiling		Non Suspect ACM	135	SF	0	SF							
1	2	200A	Girl's Restroom	CMU		Non Suspect ACM	576	SF	0	SF							
1	2	200A	Girl's Restroom	Cement Floor		Non Suspect ACM	135	SF	0	SF							
1	2	201AC	Book Closet next to Girl's Restroom	Concrete Ceiling		Non Suspect ACM	100	SF	0	SF							
1	2	201AC	Book Closet next to Girl's Restroom	CMU		Non Suspect ACM	500	SF	0	SF							
1	2	201AC	Book Closet next to Girl's Restroom	Cement Floor		Non Suspect ACM	100	SF	0	SF							
1	2	200	Classroom 200	Fiberglass Ceiling Tile 1' x 1'		Non Suspect ACM	50	SF	0	SF							
1	2	200	Classroom 200	Spline Ceiling Glue Dots		Assumed	5	SF	0	SF							
1	2	200	Classroom 200	Concrete Ceiling		Non Suspect ACM	1144	SF	0	SF							
1	2	200	Classroom 200	CMU		Non Suspect ACM	1680	SF	0	SF							
1	2	200	Classroom 200	Floor Tile VAT 9" x 9"		Confirmed	1114	SF	0	SF							
1	2	200	Classroom 200	Floor Tile VAT 12" x 12"		Assumed	30	SF	0	SF							
1	2	200RC	Classroom 200 Front Right Closet	Ceiling Tile 1' x 1'		Non Suspect ACM	10	SF	0	SF							
1	2	200RC	Classroom 200 Front Right Closet	Spline Ceiling Glue Dots		Assumed	3	SF	0	SF							
1	2	200RC	Classroom 200 Front Right Closet	CMU		Non Suspect ACM	72	SF	0	SF							
1	2	200RC	Classroom 200 Front Right Closet	Floor Tile VAT 9" x 9"		Confirmed	10	SF	0	SF							
1	2	200LC	Classroom 200 Front Left Closet	Ceiling Tile 1' x 1'		Non Suspect ACM	10	SF	0	SF							
1	2	200LC	Classroom 200 Front Left Closet	Spline Ceiling Glue Dots		Assumed	3	SF	0	SF							
1	2	200LC	Classroom 200 Front Left Closet	CMU		Non Suspect ACM	72	SF	0	SF							
1	2	200LC	Classroom 200 Front Left Closet	Floor Tile VAT 9" x 9"		Confirmed	10	SF	0	SF							
1	2	204	Classroom 204	Fiberglass Ceiling Tile 1' x 1'		Non Suspect ACM	40	SF	0	SF							
1	2	204	Classroom 204	Spline Ceiling Glue Dots		Assumed	4	SF	0	SF							
1	2	204	Classroom 204	Concrete Ceiling		Non Suspect ACM	1144	SF	0	SF							
1	2	204	Classroom 204	CMU		Non Suspect ACM	1680	SF	0	SF							
1	2	204	Classroom 204	Floor Tile VAT 9" x 9"		Confirmed	1144	SF	0	SF							
1	2	204RC	Classroom 204 Front Right Closet	Ceiling Tile 1' x 1'		Non Suspect ACM	10	SF	0	SF							
1	2	204RC	Classroom 204 Front Right Closet	Spline Ceiling Glue Dots		Assumed	3	SF	0	SF							
1	2	204RC	Classroom 204 Front Right Closet	CMU		Non Suspect ACM	72	SF	0	SF							
1	2	204RC	Classroom 204 Front Right Closet	Floor Tile VAT 9" x 9"		Confirmed	10	SF	0	SF							
1	2	204LC	Classroom 204 Front Left Closet	Ceiling Tile 1' x 1'		Non Suspect ACM	10	SF	0	SF							
1	2	204LC	Classroom 204 Front Left Closet	Spline Ceiling Glue Dots		Assumed	3	SF	0	SF							
1	2	204LC	Classroom 204 Front Left Closet	CMU		Non Suspect ACM	72	SF	0	SF							
1	2	204LC	Classroom 204 Front Left Closet	Floor Tile VAT 9" x 9"		Confirmed	10	SF	0	SF							
1	2	H27	Hallway from Classrooms 200 to 204	Fiberglass Ceiling Tile 1' x 1'		Non Suspect ACM	1575	SF	6	SF							
1	2	H27	Hallway from Classrooms 200 to 204	CMU		Non Suspect ACM	3312	SF	0	SF							
1	2	H27	Hallway from Classrooms 200 to 204	Floor Tile VAT 9" x 9"		Confirmed	1521	SF	0	SF							
1	2	H27	Hallway from Classrooms 200 to 204	Floor Tile VAT 12" x 12"		Assumed	54	SF	0	SF							
1	2	H27	Hallway from Classrooms 200 to 204	Spline Ceiling Glue Dots		Assumed	158	SF	0	SF							
2	1	A6	Classroom A6 (306) and Rear Closet Area	Pipe Fitting Insulation		Confirmed	10	EA	0	EA							
2	1	A6	Classroom A6 (306) and Rear Closet Area	Fiberglass Pipe Insulation		Non Suspect ACM	85	LF	0	LF							
2	1	A6	Classroom A6 (306) and Rear Closet Area	Metal Panels (Ceiling)		Non Suspect ACM	874	SF	0	SF							
2	1	A6	Classroom A6 (306) and Rear Closet Area	Sheetrock Wall		Non Suspect ACM	1220	SF	0	SF							
2	1	A6	Classroom A6 (306) and Rear Closet Area	Floor Tile VAT 9" x 9"		Confirmed	804	SF	0	SF							
2	1	A6	Classroom A6 (306) and Rear Closet Area	Floor Tile VAT 9" x 9"		Confirmed	55	SF	0	SF							
2	1	A6	Classroom A6 (306) and Rear Closet Area	Floor Tile VAT 12" x 12"		Assumed	15	SF	0	SF							
2	1	A1	Classroom A1 (301) and Rear Closet Area	Pipe Fitting Insulation		Confirmed	15	EA	0	EA							
2	1	A1	Classroom A1 (301) and Rear Closet Area	Fiberglass Pipe Insulation		Non Suspect ACM	90	LF	0	LF							
2	1	A1	Classroom A1 (301) and Rear Closet Area	Metal Panels (Ceiling)		Non Suspect ACM	874	SF	0	SF							
2	1	A1	Classroom A1 (301) and Rear Closet Area	Sheetrock Wall		Non Suspect ACM	1220	SF	0	SF							
2	1	A1	Classroom A1 (301) and Rear Closet Area	Floor Tile VAT 12" x 12"		Assumed	874	SF	0	SF							
2	1	A5	Classroom A5 (305) and Rear Closet Area	Pipe Fitting Insulation		Confirmed	7	EA	0	EA							
2	1	A5	Classroom A5 (305) and Rear Closet Area	Fiberglass Pipe Insulation		Non Suspect ACM	48	LF	0	LF							
2	1	A5	Classroom A5 (305) and Rear Closet Area	Metal Panels (Ceiling)		Non Suspect ACM	874	SF	0	SF							
2	1	A5	Classroom A5 (305) and Rear Closet Area	Sheetrock Wall		Non Suspect ACM	1220	SF	0	SF							
2	1	A5	Classroom A5 (305) and Rear Closet Area	Floor Tile VAT 9" x 9"		Confirmed	874	SF	0	SF							
2	1	A2	Classroom A2 (302) and Rear Closet Area	Pipe Fitting Insulation		Confirmed	7	EA	0	EA							
2	1	A2	Classroom A2 (302) and Rear Closet Area	Fiberglass Pipe Insulation		Non Suspect ACM	48	LF	0	LF							
2	1	A2	Classroom A2 (302) and Rear Closet Area	Metal Panels (Ceiling)		Non Suspect ACM	874	SF	0	SF							
2	1	A2	Classroom A2 (302) and Rear Closet Area	Sheetrock Wall		Non Suspect ACM	1220	SF	0	SF							
2	1	A2	Classroom A2 (302) and Rear Closet Area	Floor Tile VAT 9" x 9"		Confirmed	814	SF	0	SF							
2	1	A2	Classroom A2 (302) and Rear Closet Area	Floor Tile VAT 12" x 12"		Assumed	60	SF	0	SF							
2	1	A4	Classroom A4 (304) and Rear Closet Area	Pipe Fitting Insulation		Confirmed	7	EA	0	EA							
2	1	A4	Classroom A4 (304) and Rear Closet Area	Fiberglass Pipe Insulation		Non Suspect ACM	48	LF	0	LF							
2	1	A4	Classroom A4 (304) and Rear Closet Area	Metal Panels (Ceiling)		Non Suspect ACM	874	SF	0	SF							
2	1	A4	Classroom A4 (304) and Rear Closet Area	Sheetrock Wall		Non Suspect ACM	1220	SF	0	SF							
2	1	A4	Classroom A4 (304) and Rear Closet Area	Floor Tile VAT 12" x 12"		Assumed	874	SF	0	SF							
2	1	A3	Classroom A3 (303) and Rear Closet Area	Pipe Fitting Insulation		Confirmed	10	EA	0	EA							
2	1	A3	Classroom A3 (303) and Rear Closet Area	Fiberglass Pipe Insulation		Non Suspect ACM	70	LF	0	LF							

		School District of Philadelphia Rhawnhurst Elementary School 7809 Castor Avenue, Philadelphia, PA 19152 ULCS# 8360 Year Built: 1949		AHERA Three-Year Reinspection 2018-2019 Room by Room Location Log Report					
				Red= Confirmed (Contact OEMS prior to the disturbance of any of the following materials and report damage)					
				Yellow= Assumed (Contact OEMS for assessment and sampling prior to the disturbance of these materials and report damage)					
				Green= Non Asbestos Containing/Non Suspect Material (These materials have been sampled and Laboratory Analysis has indicated NO Asbestos present or NO ASBESTOS DETECTED or these materials are not typically known to contain Asbestos)					
<i>E l e m e n t</i>	<i>F l o o r</i>	<i>Space #</i>	<i>On Site Room Name</i>	<i>Material Description</i>	<i>Confirmed/Assumed/NAD/ Non Suspect ACM</i>	<i>Amount of Material</i>	<i>SF LF EA</i>	<i>Amount of Damage</i>	<i>SF LF EA</i>
2	1	A3	Classroom A3 (303) and Rear Closet Area	Metal Panels (Ceiling)	Non Suspect ACM	874	SF	0	SF
2	1	A3	Classroom A3 (303) and Rear Closet Area	Sheetrock Wall	Non Suspect ACM	1220	SF	0	SF
2	1	A3	Classroom A3 (303) and Rear Closet Area	Floor Tile VAT 9" x 9"	Confirmed	874	SF	0	SF
2	1	H14	Hallway from Classrooms A1 to A4	Pipe Fitting Insulation	Confirmed	8	EA	0	EA
2	1	H14	Hallway from Classrooms A1 to A4	Fiberglass Pipe Insulation	Non Suspect ACM	43	LF	0	LF
2	1	H14	Hallway from Classrooms A1 to A4	Metal Panels (Ceiling)	Non Suspect ACM	1035	SF	0	SF
2	1	H14	Hallway from Classrooms A1 to A4	Metal Panels (Walls)	Non Suspect ACM	1984	SF	0	SF
2	1	H14	Hallway from Classrooms A1 to A4	Floor Tile VAT 9" x 9"	Confirmed	1035	SF	0	SF
3	1	TRAILER	Trailer Classroom	Composite Panels (Ceiling)	Non Suspect ACM	605	SF	0	SF
3	1	TRAILER	Trailer Classroom	Composite Panels (Walls)	Non Suspect ACM	1056	SF	0	SF
3	1	TRAILER	Trailer Classroom	Floor Tile VAT 12" x 12"	Assumed	40	SF	1	SF
3	1	TRAILER	Trailer Classroom	Carpet	Non Suspect ACM	565	SF	0	SF
1	AT	A	Attic-Fan Room Second Floor		x	x	x	x	x
1	CS	C	Crawlspace-Boiler Room		x	x	x	x	x