

School District of Philadelphia
Lead Safe Certification Assessment Report
Feltonville Head Start

Name of Inspector: Ananth K. Vinjamuri
 Inspection Company: Criterion Labs, Inc.

Inspection Dates: 07/17-07/20/2019
 UCLS# 7310

Element	Room	On-Site Room Name	Student Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/negative)	Additional Component	Substrate Material	Color	Description of Paint and Plaster Damage	Additional Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Additional Component XRF (positive/negative)	Debris Present (describe location)	Quantity (sf)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Comments/ Description/ Notes
1	B	Air Intake Room	no	W1	Brick	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	No Paint
1	B	Air Intake Room	no	W2	Brick	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	No Paint
1	B	Air Intake Room	no	W3	Brick	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	No Paint
1	B	Air Intake Room	no	W4	Brick	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	No Paint
1	B	Air Intake Room	no	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	No Paint
1	B	Air Intake Room	no	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	No Paint
1	B	Fan Room	no	W1	Wood	White	Alligatoring	50	7.3	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	B	Fan Room	no	W2	Wood	White	Alligatoring	10	5.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	B	Fan Room	no	W3	Concrete	White	Flaking	60	0.06	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	B	Fan Room	no	W3	Concrete	Grey	Flaking	50	1.3	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	B	Fan Room	no	W4	Concrete	White	Flaking	65	0.04	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	B	Fan Room	no	W4	Concrete	Grey	Flaking	50	1.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	B	Fan Room	no	W4	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	B	Fan Room	no	W4	N/A	N/A	N/A	N/A	N/A	N/A	Drain Pipe	Metal	White	Flaking	8	0.09	Negative	White	0	No	No	no	
1	B	Fan Room	no	W4	N/A	N/A	N/A	N/A	N/A	N/A	Drain Pipe	Metal	Grey	Flaking	4	0.6	Negative	White	0	No	No	no	
1	B	Fan Room	no	Ceiling	Plaster	White	Flaking	200	0.05	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	B	Fan Room	no	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	No paint
1	B	Fan Room	no	Floor	N/A	N/A	N/A	N/A	N/A	N/A	Ductwork	Metal	Grey	Flaking	100	10.1	Positive	None	0	No	No	no	
1	B	Boiler Tank and Fan Room	no	W1	Concrete	White	Flaking	120	0.05	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	B	Boiler Tank and Fan Room	no	W1	Concrete	Grey	Flaking	75	14.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	B	Boiler Tank and Fan Room	no	W2	Concrete	White	Flaking	65	0.04	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	B	Boiler Tank and Fan Room	no	W2	Concrete	Grey	Flaking	45	11.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	B	Boiler Tank and Fan Room	no	W3	Wood	White	Alligatoring	50	4.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	B	Boiler Tank and Fan Room	no	W3	Concrete	Grey	Flaking	10	4.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	B	Boiler Tank and Fan Room	no	W3	Concrete	Grey	Flaking	60	0.07	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	B	Boiler Tank and Fan Room	no	W3	N/A	N/A	N/A	N/A	N/A	N/A	Ductwork	Metal	Grey	Flaking	120	10.1	Positive	None	0	No	No	no	
1	B	Boiler Tank and Fan Room	no	W3	N/A	N/A	N/A	N/A	N/A	N/A	Column	Metal	White	Flaking	10	0.5	Negative	None	0	No	No	no	No paint
1	B	Boiler Tank and Fan Room	no	W3	N/A	N/A	N/A	N/A	N/A	N/A	Column	Metal	Grey	Flaking	2	0.3	Negative	None	0	No	No	no	
1	B	Boiler Tank and Fan Room	no	W3	N/A	N/A	N/A	N/A	N/A	N/A	Hand rails	Metal	Grey	Chipping	30	6.6	Positive	None	0	No	No	no	
1	B	Boiler Tank and Fan Room	no	W4	Plaster	Grey	Flaking	10	0.5	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	B	Boiler Tank and Fan Room	no	Ceiling	Concrete	White	Flaking	20	0.04	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	B	Boiler Tank and Fan Room	no	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	No paint
1	B	Old Boiler Room	no	W1	Concrete	White	Flaking	80	6.3	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	B	Old Boiler Room	no	W1	Concrete	Grey	Flaking	35	6.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	B	Old Boiler Room	no	W1	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	B	Old Boiler Room	no	W2	Concrete	White	Flaking	50	8.3	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	B	Old Boiler Room	no	W2	Concrete	Grey	Flaking	25	5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	B	Old Boiler Room	no	W3	Concrete	Grey	Flaking	20	0.05	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	B	Old Boiler Room	no	W4	Concrete	White	Flaking	100	0.06	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	B	Old Boiler Room	no	W4	Concrete	Grey	Flaking	60	1.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	B	Old Boiler Room	no	Ceiling	Plaster	White	Flaking	80	0.04	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	B	Old Boiler Room	no	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	No paint
1	B	Storage Room in between the Old/New Boiler Rooms	no	W1	Brick	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	B	Storage Room in between the Old/New Boiler Rooms	no	W2	Brick	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	B	Storage Room in between the Old/New Boiler Rooms	no	W3	Brick	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	B	Storage Room in between the Old/New Boiler Rooms	no	W4	Brick	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	B	Storage Room in between the Old/New Boiler Rooms	no	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	B	Storage Room in between the Old/New Boiler Rooms	no	Ceiling	Brick	White	Flaking	4	1.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	Door Archway
1	B	Storage Room in between the Old/New Boiler Rooms	no	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	B	Hallway from Old Boiler Room to New Boiler Room	no	W1	Brick	White	Flaking	10	0.05	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	B	Hallway from Old Boiler Room to New Boiler Room	no	W2	Brick	White	Flaking	8	0.06	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	B	Hallway from Old Boiler Room to New Boiler Room	no	W3	Brick	White	Flaking	5	0.03	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	B	Hallway from Old Boiler Room to New Boiler Room	no	W4	Brick	White	Flaking	7	0.02	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	B	Hallway from Old Boiler Room to New Boiler Room	no	Ceiling	Concrete	White	Flaking	10	0.02	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	B	Hallway from Old Boiler Room to New Boiler Room	no	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	No Paint
1	B	New Boiler Room	no	W1	Brick	White	Flaking	20	0.03	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	B	New Boiler Room	no	W2	Brick	Tan	Flaking	10	0.02	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	B	New Boiler Room	no	W3	Brick	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	B	New Boiler Room	no	W4	Brick	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	B	New Boiler Room	no	Ceiling	Concrete	White	Flaking	30	0.05	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	B	New Boiler Room	no	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	No paint
1	B	Storage Room opposite Building Engineer's Office	no	W1	Brick	Green	Cracking	30	9.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	B	Storage Room opposite Building Engineer's Office	no	W2	Brick	Green	Cracking	20	8.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	

**School District of Philadelphia
Lead Safe Certification Assessment Report
Feltonville Head Start**

Name of Inspector: Ananth K. Vinjamuri
Inspection Company: Criterion Labs, Inc.

Inspection Dates: 07/17-07/20/2019
UCLS# 7310

Element	Room	On-Site Room Name	Student Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/negative)	Additional Component	Substrate Material	Color	Description of Paint and Plaster Damage	Additional Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Additional Component XRF (positive/negative)	Debris Present (describe location)	Quantity (sf)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Comments/ Description/ Notes
1	B	Storage Room opposite Building Engineer's Office	no	W3	Brick	Green	Cracking	50	7.3	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	B	Storage Room opposite Building Engineer's Office	no	W4	Brick	Green	Cracking	20	7.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	B	Storage Room opposite Building Engineer's Office	no	Ceiling	Concrete	White	Flaking	45	8.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	B	Storage Room opposite Building Engineer's Office	no	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	No paint
1	B	Building Engineer's Office	no	W1	Brick	Green	Flaking	10	17.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	B	Building Engineer's Office	no	W2	Brick	Green	Flaking	10	12.3	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	B	Building Engineer's Office	no	W3	Brick	Green	Flaking	6	1.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	B	Building Engineer's Office	no	W4	Brick	Green	Flaking	3	2.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	B	Building Engineer's Office	no	Ceiling	Brick	Green	Flaking	8	16.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	Only at the Archway. Rest of the ceiling has tile
1	B	Building Engineer's Office	no	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	Carpet
1	B	Building Engineer's Office Restroom	no	W1	Ceramic	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	B	Building Engineer's Office Restroom	no	W2	Ceramic	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	B	Building Engineer's Office Restroom	no	W3	Ceramic	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	B	Building Engineer's Office Restroom	no	W4	Ceramic	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	B	Building Engineer's Office Restroom	no	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	B	Building Engineer's Office Restroom	no	Floor	Ceramic	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	Ceiling Tile
1	B	Boy's Restroom	yes	W1	Ceramic	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	B	Boy's Restroom	yes	W2	Ceramic	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	B	Boy's Restroom	yes	W3	Ceramic	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	B	Boy's Restroom	yes	W4	Ceramic	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	B	Boy's Restroom	yes	Ceiling	Plaster	White	Flaking	4	7.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	B	Boy's Restroom	yes	Floor	Ceramic	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	B	Girl's Restroom	yes	W1	Ceramic	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	B	Girl's Restroom	yes	W2	Ceramic	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	B	Girl's Restroom	yes	W3	Ceramic	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	B	Girl's Restroom	yes	W4	Ceramic	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	B	Girl's Restroom	yes	Ceiling	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	B	Girl's Restroom	yes	Floor	Ceramic	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	B	Girl's Restroom Custodial Closet	no	W1	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	B	Girl's Restroom Custodial Closet	no	W2	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	B	Girl's Restroom Custodial Closet	no	W3	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	B	Girl's Restroom Custodial Closet	no	W4	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	B	Girl's Restroom Custodial Closet	no	Ceiling	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	B	Girl's Restroom Custodial Closet	no	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	No paint
1	B	Kitchen	yes	W1	Brick	White	Cracking, Flaking	10	2.3	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	B	Kitchen	yes	W2	Brick	White	Cracking, Flaking	35	6.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	B	Kitchen	yes	W3	Brick	White	Cracking, Flaking	15	18	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	B	Kitchen	yes	W4	Brick	White	Cracking, Flaking	25	15.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	B	Kitchen	yes	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	B	Kitchen	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	No paint
1	B	Kitchen Storage Closet	no	W1	Brick	White	Cracking	12	2.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	B	Kitchen Storage Closet	no	W2	Brick	White	Cracking	6	3	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	B	Kitchen Storage Closet	no	W3	Brick	White	Cracking	15	1.3	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	B	Kitchen Storage Closet	no	W4	Brick	White	Cracking	10	1.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	B	Kitchen Storage Closet	no	Ceiling	Concrete	White	Flaking	10	2.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Floor, shelves, mechanical equipment	12	No	No	no	No paint
1	B	Kitchen Storage Closet	no	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	B	Kitchen Storage (Pipe Chase)	no	W1	Brick	White	Flaking	15	11.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	No paint
1	B	Kitchen Storage (Pipe Chase)	no	W2	Cinderblock	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	B	Kitchen Storage (Pipe Chase)	no	W3	Brick	White	Flaking	15	9.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	B	Kitchen Storage (Pipe Chase)	no	W4	Brick	White	Flaking	50	9.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	B	Kitchen Storage (Pipe Chase)	no	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	B	Kitchen Storage (Pipe Chase)	no	Floor	Concrete	Black	Friction	10	0.03	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	B	Electrical Room	no	W1	Brick	White	Flaking, Cracking	6	6.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	B	Electrical Room	no	W2	Brick	White	Flaking, Cracking	5	6.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	B	Electrical Room	no	W3	Brick	White	Cracking	5	2.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	B	Electrical Room	no	W4	Brick	White	Cracking	4	8.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	B	Electrical Room	no	Ceiling	Concrete	White	Flaking	15	3.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Floor	12	No	No	no	
1	B	Electrical Room	no	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	B	Storage (under stairwell) next to Electrical room	no	W1	Sheetrock	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	B	Storage (under stairwell) next to Electrical room	no	W2	Cinderblock	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	B	Storage (under stairwell) next to Electrical room	no	W3	Concrete	Grey	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	B	Storage (under stairwell) next to Electrical room	no	W4	Brick	White	Cracking	3	10	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	B	Storage (under stairwell) next to Electrical room	no	Ceiling	Metal	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	Stairs

School District of Philadelphia
Lead Safe Certification Assessment Report
Feltonville Head Start

		Name of Inspector: Ananth K. Vinjamuri Inspection Company: Criterion Labs, Inc.															Inspection Dates: 07/17-07/20/2019 UCLS# 7310							
Element	Floor	On-Site Room Name	Student Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/negative)	Additional Component	Substrate Material	Color	Description of Paint and Plaster Damage	Additional Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Additional Component XRF (positive/negative)	Debris Present (describe location)	Quantity (sf)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Comments/ Description/ Notes	
1	B	Storage (under stairwell) next to Electrical room	no	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	B	Small Storage Closet adjacent to Electrical Room	no	W1	Brick	White	Flaking	12	9.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	B	Small Storage Closet adjacent to Electrical Room	no	W2	Brick	White	Flaking	10	10.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	B	Small Storage Closet adjacent to Electrical Room	no	W3	Brick	White	Flaking	7	10.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	B	Small Storage Closet adjacent to Electrical Room	no	W4	Brick	White	Flaking	8	11.3	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	B	Small Storage Closet adjacent to Electrical Room	no	Ceiling	Concrete	White	Flaking	12	13.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	B	Small Storage Closet adjacent to Electrical Room	no	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	No paint
1	B	Large Storage Room adjacent to Electrical Room	no	W1	Brick	Green	Cracking	25	11.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	B	Large Storage Room adjacent to Electrical Room	no	W2	Brick	Green	Cracking, Efflorescence	40	13.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	Unknown	yes	
1	B	Large Storage Room adjacent to Electrical Room	no	W3	Brick	Green	Cracking, Efflorescence	50	18.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Floor	7	No	Unknown	yes	
1	B	Large Storage Room adjacent to Electrical Room	no	W4	Brick	Green	Cracking, Efflorescence	30	16.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Floor	3	No	Unknown	yes	
1	B	Large Storage Room adjacent to Electrical Room	no	Ceiling	Concrete	White	Flaking, Cracking	12	13.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	B	Large Storage Room adjacent to Electrical Room	no	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	No paint
1	B	Main Hallway	yes	W1	Brick	White	Flaking	20	11	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	B	Main Hallway	yes	W2	Cinderblock/Brick	White/Grey	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	B	Main Hallway	yes	W3	Brick	White	Flaking, Cracking	25	9.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	B	Main Hallway	yes	W4	Cinderblock/Brick	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	B	Main Hallway	yes	Ceiling	Concrete	White	Flaking	10	13.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	B	Main Hallway	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	B	Rising Sun Avenue Basement Stairwell	yes	W1	Cinderblock	White/Beige	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	B	Rising Sun Avenue Basement Stairwell	yes	W2	Cinderblock	White/Grey	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	B	Rising Sun Avenue Basement Stairwell	yes	W3	Plaster	White/Beige	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	B	Rising Sun Avenue Basement Stairwell	yes	W4	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	B	Rising Sun Avenue Basement Stairwell	yes	Ceiling	Plaster/Metal	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	Stairs
1	B	Rising Sun Avenue Basement Stairwell	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	Stairs
1	B	Opposite Rising Sun Avenue Basement Stairwell	yes	W1	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	B	Opposite Rising Sun Avenue Basement Stairwell	yes	W2	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	B	Opposite Rising Sun Avenue Basement Stairwell	yes	W3	Plaster	White	Cracking	6	34.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	B	Opposite Rising Sun Avenue Basement Stairwell	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A	Baseboard	Concrete	Grey	Chipping	4	12.3	Positive	None	0	No	No	no		
1	B	Opposite Rising Sun Avenue Basement Stairwell	yes	W4	Cinderblock	White/Grey	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	B	Opposite Rising Sun Avenue Basement Stairwell	yes	Ceiling	Plaster/Metal	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	Stairs
1	B	Opposite Rising Sun Avenue Basement Stairwell	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Classroom 102	yes	W1	Plaster	Green	Flaking, Cracking	25	30.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Classroom 102	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door	Wood	Green	Flaking	2	0.15	Negative	None	0	No	No	no		
1	1	Classroom 102	yes	W2	Plaster	Green	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Classroom 102	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A	Baseboard	Concrete	Grey	Chipping	4	11.9	Positive	None	0	No	No	no		
1	1	Classroom 102	yes	W3	Plaster	Green	Cracking, Spalling	10	0.02	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	Unknown	yes	
1	1	Classroom 102	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A	Baseboard	Concrete	Grey	Chipping	6	10.8	Positive	None	0	No	No	no		
1	1	Classroom 102	yes	W4	Plaster	Green	Cracking	40	44.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Classroom 102	yes	Ceiling	Plaster	White	Cracking, Crack in plaster	15	39	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Classroom 102	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Classroom 102 Restroom	yes	W1	Ceramic	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Classroom 102 Restroom	yes	W2	Ceramic	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Classroom 102 Restroom	yes	W3	Ceramic	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Classroom 102 Restroom	yes	W4	Ceramic	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Classroom 102 Restroom	yes	Ceiling	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Classroom 102 Restroom	yes	Floor	Ceramic	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Classroom 102 Closet	yes	W1	Plaster	Green	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Classroom 102 Closet	yes	W2	Plaster	Green	Friction	8	27.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Classroom 102 Closet	yes	W3	Sheetrock	Green	Flaking	4	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Classroom 102 Closet	yes	W4	Plaster	Green	Cracking	4	23.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Classroom 102 Closet	yes	Ceiling	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Classroom 102 Closet	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Classroom 101	yes	W1	Plaster	Green	Chipping	15	30.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Classroom 101	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	Blackboard	Wood	Green	Chipping	15	0.25	Negative	None	0	No	No	no		
1	1	Classroom 101	yes	W2	Plaster	Green	Flaking	10	0.02	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	

School District of Philadelphia
Lead Safe Certification Assessment Report
Feltonville Head Start

		Name of Inspector: Ananth K. Vinjamuri Inspection Company: Criterion Labs, Inc.																Inspection Dates: 07/17-07/20/2019 UCLS# 7310					
Element	Room	On-Site Room Name	Student Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/negative)	Additional Component	Substrate Material	Color	Description of Paint and Plaster Damage	Additional Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Additional Component XRF (positive/negative)	Debris Present (describe location)		Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Comments/ Description/ Notes
																		Quantity (sf)	None				
1	1	Classroom 101	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A	Baseboard	Concrete	Grey	Chipping	15	11.2	Positive	None	0	No	No	no	
1	1	Classroom 101	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A	Door	Wood	Grey	Chipping	3	0.05	Negative	None	0	No	No	no	
1	1	Classroom 101	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Wood	Grey	Chipping	8	0.07	Negative	None	0	No	No	no	
1	1	Classroom 101	yes	W3	Plaster	Green	Chipping, Flaking	4	0.03	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Classroom 101	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A	Baseboard	Concrete	Grey	Chipping	6	11.3	Positive	None	0	No	No	no	
1	1	Classroom 101	yes	W4	Plaster	Green	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Classroom 101	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A	Blackboard	Wood	Green	Chipping	10	0.13	Negative	None	0	No	No	no	
1	1	Classroom 101	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A	Cabinet	Wood	Green	Chipping	3	0.07	Negative	None	0	No	No	no	
1	1	Classroom 101	yes	Ceiling	Plaster	White	Cracking	3	39.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	Spread out
1	1	Classroom 101	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Classroom 101 Restroom	yes	W1	Ceramic	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Classroom 101 Restroom	yes	W2	Ceramic	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Classroom 101 Restroom	yes	W3	Ceramic	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Classroom 101 Restroom	yes	W4	Ceramic	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Classroom 101 Restroom	yes	Ceiling	Plaster	White	Flaking	2	34.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Classroom 101 Restroom	yes	Floor	Ceramic	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Classroom 101 Closet	yes	W1	Plaster	Green	Partially Inaccessible	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Classroom 101 Closet	yes	W2	Plaster	Green	Partially Inaccessible	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Classroom 101 Closet	yes	W3	Plaster	Green	Partially Inaccessible	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Classroom 101 Closet	yes	W4	Plaster	Green	Partially Inaccessible	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Classroom 101 Closet	yes	Ceiling	Plaster	White	Flaking	5	30.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Classroom 101 Closet	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Exit adjacent to the Faculty Restroom	yes	W1	Plaster	Beige	Efflorescence, Damaged Plaster	3	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	Unknown	yes	
1	1	Exit adjacent to the Faculty Restroom	yes	W2	Plaster	Beige	Partially Inaccessible, Spalling	10	0.01	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	Unknown	yes	
1	1	Exit adjacent to the Faculty Restroom	yes	W3	Plaster	Beige	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Exit adjacent to the Faculty Restroom	yes	W4	Plaster	Beige	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Exit adjacent to the Faculty Restroom	yes	Ceiling	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Exit adjacent to the Faculty Restroom	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Faculty Room adjacent Classroom 101	yes	W1	Ceramic	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Faculty Room adjacent Classroom 101	yes	W2	Ceramic	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Faculty Room adjacent Classroom 101	yes	W3	Ceramic	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Faculty Room adjacent Classroom 101	yes	W4	Ceramic	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Faculty Room adjacent Classroom 101	yes	Ceiling	Plaster	White	Spalling	3	31.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	Unknown	yes	
1	1	Faculty Room adjacent Classroom 101	yes	Floor	Ceramic	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Faculty Room Vestibule	yes	W1	Ceramic	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Faculty Room Vestibule	yes	W2	Ceramic	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Faculty Room Vestibule	yes	W3	Ceramic	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Faculty Room Vestibule	yes	W4	Ceramic	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Faculty Room Vestibule	yes	Ceiling	Plaster	White	Cracking	18	30.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Faculty Room Vestibule	yes	Floor	Ceramic	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Faculty Room Restroom	yes	W1	Ceramic	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Faculty Room Restroom	yes	W2	Ceramic	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Faculty Room Restroom	yes	W3	Ceramic	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Faculty Room Restroom	yes	W4	Ceramic	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Faculty Room Restroom	yes	Ceiling	Plaster	White	Efflorescence, Flaking	6	22.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	Unknown	yes	
1	1	Faculty Room Restroom	yes	Floor	Ceramic	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Classroom 103	yes	W1	Plaster	Beige	Cracking, Flaking	4	20.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	By Telephone and under blackboard
1	1	Classroom 103	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	Baseboard	Concrete	Brown	Chipping	3	10.6	Positive	None	0	No	No	no	
1	1	Classroom 103	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	Blackboard Frame	Wood	Purple	Chipping	8	0.3	Negative	None	0	No	No	no	
1	1	Classroom 103	yes	W2	Plaster	Beige	Flaking	12	0.26	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Classroom 103	yes	W3	Plaster	Beige	Cracking	4	0.14	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Classroom 103	yes	W4	Plaster	Beige	Flaking	6	0.13	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Classroom 103	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A	Baseboard	Concrete	Brown	Chipping	5	10.4	Positive	None	0	No	No	no	
1	1	Classroom 103	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A	Blackboard Frame	Wood	Purple	Chipping	2	0	Negative	None	0	No	No	no	Spread out
1	1	Classroom 103	yes	Ceiling	Plaster	White	Cracking	8	35.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Classroom 103	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Classroom 103 Closet	yes	W1	Plaster	Beige	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Classroom 103 Closet	yes	W2	Plaster	Beige	Flaking, Friction	3	28.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Classroom 103 Closet	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A	Baseboard	Wood	Brown	Chipping	6	12.4	Positive	None	0	No	No	no	
1	1	Classroom 103 Closet	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Wood	Purple	Flaking, Chipping	10	0.98	Negative	None	0	No	No	no	
1	1	Classroom 103 Closet	yes	W3	Plaster	Beige	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Classroom 103 Closet	yes	W4	Plaster	Beige	Cracking	5	0.12	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Classroom 103 Closet	yes	Ceiling	Plaster	White	Flaking, Cracking	16	26.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Classroom 103 Closet	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Classroom 103 Teacher's Closet by entrance	yes	W1	Plaster	Beige	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Classroom 103 Teacher's Closet by entrance	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door	Metal	Black	Chipping	5	0.02	Negative	None	0	No	No	no	
1	1	Classroom 103 Teacher's Closet by entrance	yes	W2	Plaster	Beige	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	

School District of Philadelphia
Lead Safe Certification Assessment Report
Feltonville Head Start

Name of Inspector: Ananth K. Vinjamuri
 Inspection Company: Criterion Labs, Inc.

Inspection Dates: 07/17-07/20/2019
 UCLS# 7310

Element	Room	On-Site Room Name	Student Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/negative)	Additional Component	Substrate Material	Color	Description of Paint and Plaster Damage	Additional Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Additional Component XRF (positive/negative)	Debris Present (describe location)	Quantity (sf)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Comments/ Description/ Notes	
1	1	Classroom 103 Teacher's Closet by entrance	yes	W3	Plaster	Beige	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no		
1	1	Classroom 103 Teacher's Closet by entrance	yes	W4	Plaster	Beige	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no		
1	1	Classroom 103 Teacher's Closet by entrance	yes	Ceiling	Plaster	Beige	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no		
1	1	Classroom 103 Teacher's Closet by entrance	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no		
1	1	Custodial Closet	no	W1	Sheetrock	Beige	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no		
1	1	Custodial Closet	no	W2	Sheetrock	Beige	none	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no		
1	1	Custodial Closet	no	W3	Plaster	Beige	Flaking	1	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no		
1	1	Custodial Closet	no	W4	Sheetrock	Beige	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no		
1	1	Custodial Closet	no	Ceiling	Plaster	White	Cracking, Damaged Plaster	6	30.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	yes		
1	1	Custodial Closet	no	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	Drain Pipe	Metal	Beige	Cracking	2	38.7	Positive	None	0	No	No	no		
1	1	Custodial Closet	no	Floor	Ceramic	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no		
1	1	Storage Closet adjacent to the Custodial Closet	no	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	
1	1	Storage Closet adjacent to the Custodial Closet	no	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	0	No Access	No Access	No Access	No Access	
1	1	Storage Closet adjacent to the Custodial Closet	no	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	0	No Access	No Access	No Access	No Access	
1	1	Storage Closet adjacent to the Custodial Closet	no	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	0	No Access	No Access	No Access	No Access	
1	1	Storage Closet adjacent to the Custodial Closet	no	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	0	No Access	No Access	No Access	No Access	
1	1	Storage Closet adjacent to the Custodial Closet	no	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	0	No Access	No Access	No Access	No Access	
1	1	Storage Closet adjacent to the Storage Closet with Circuit Breaker	no	W1	Plaster	Beige	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no		
1	1	Storage Closet adjacent to the Storage Closet with Circuit Breaker	no	W2	Plaster	Beige	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no		
1	1	Storage Closet adjacent to the Storage Closet with Circuit Breaker	no	W3	Plaster	Beige	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no		
1	1	Storage Closet adjacent to the Storage Closet with Circuit Breaker	no	W4	Plaster	Beige	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no		
1	1	Storage Closet adjacent to the Storage Closet with Circuit Breaker	no	Ceiling	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no		
1	1	Storage Closet adjacent to the Storage Closet with Circuit Breaker	no	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no		
1	1	Storage Closet with Circuit Breaker	no	W1	Plaster	Beige	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no		
1	1	Storage Closet with Circuit Breaker	no	W2	Plaster	Beige	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no		
1	1	Storage Closet with Circuit Breaker	no	W3	Plaster	Beige	Friction	4	0.02	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no		
1	1	Storage Closet with Circuit Breaker	no	W4	Plaster	Beige	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no		
1	1	Storage Closet with Circuit Breaker	no	Ceiling	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no		
1	1	Storage Closet with Circuit Breaker	no	Floor	Concrete	Grey	Friction	6	0.02	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no		
1	1	Classroom 104 Screening Room	yes	W1	Plaster	Beige	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no		
1	1	Classroom 104 Screening Room	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A	Baseboard	Concrete	Brown	Chipping	1	12.1	Positive	None	0	No	No	no		
1	1	Classroom 104 Screening Room	yes	W3	Plaster	Beige	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no		
1	1	Classroom 104 Screening Room	yes	W4	Plaster	Beige	Damaged Plaster	1	0.12	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	yes		
1	1	Classroom 104 Screening Room	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A	Baseboard	Concrete	Brown	Chipping	6	9.2	Positive	None	0	No	No	no		
1	1	Classroom 104 Screening Room	yes	W4	Wood	Beige	Flaking	5	0.15	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no		
1	1	Classroom 104 Screening Room	yes	Ceiling	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no		
1	1	Classroom 104 Screening Room	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no		
1	1	Classroom 104 Closet	yes	W1	Plaster	Beige	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no		
1	1	Classroom 104 Closet	yes	W2	Plaster	Beige	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no		
1	1	Classroom 104 Closet	yes	W3	Plaster	Beige	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no		
1	1	Classroom 104 Closet	yes	W4	Plaster	Beige	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no		
1	1	Classroom 104 Closet	yes	Ceiling	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no		
1	1	Classroom 104 Closet	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no		
1	1	Classroom 104 Teacher's Closet by entrance	yes	W1	Plaster	Beige	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no		
1	1	Classroom 104 Teacher's Closet by entrance	yes	W2	Plaster	Beige	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no		
1	1	Classroom 104 Teacher's Closet by entrance	yes	W3	Plaster	Beige	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no		
1	1	Classroom 104 Teacher's Closet by entrance	yes	W4	Plaster	Beige	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no		
1	1	Classroom 104 Teacher's Closet by entrance	yes	Ceiling	Plaster	Beige	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no		
1	1	Classroom 104 Teacher's Closet by entrance	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no		
1	1	Exit adjacent to the Main Office	yes	W1	Plaster	Beige	Efflorescence	5	0.12	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	Unknown	yes		
1	1	Exit adjacent to the Main Office	yes	W2	Plaster	Beige	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no		
1	1	Exit adjacent to the Main Office	yes	W3	Plaster	Beige	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no		
1	1	Exit adjacent to the Main Office	yes	W4	Plaster	Beige	Efflorescence	5	0.07	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	Unknown	yes		
1	1	Exit adjacent to the Main Office	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A	Baseboard	Concrete	Grey	Chipping	4	15.6	Positive	None	0	No	No	no		
1	1	Exit adjacent to the Main Office	yes	Ceiling	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no		
1	1	Exit adjacent to the Main Office	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no		
1	1	Classroom 105	yes	W1	Plaster	Green	Cracking	3	0.02	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no		
1	1	Classroom 105	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	Baseboard	Concrete	Grey	Chipping	6	14.2	Positive	None	0	No	No	no		
1	1	Classroom 105	yes	W2	Plaster	Beige	Chipping	1	31.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	At the Archway by the door	
1	1	Classroom 105	yes	W2	Plaster	Beige	Flaking	5	1.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	Lower wall	
1	1	Classroom 105	yes	W2	Plaster	Wall	Spalling	12	2.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	Unknown	yes	Upper wall	
1	1	Classroom 105	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A	Baseboard	Concrete	Grey	Chipping	4	11.3	Positive	None	0	No	No	no		
1	1	Classroom 105	yes	W3	Plaster	Beige	Flaking	2	0.06	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no		

School District of Philadelphia
Lead Safe Certification Assessment Report
Feltonville Head Start

Name of Inspector: Ananth K. Vinjamuri
 Inspection Company: Criterion Labs, Inc.

Inspection Dates: 07/17-07/20/2019
 UCLS# 7310

Element	Floor	On-Site Room Name	Student Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/negative)	Additional Component	Substrate Material	Color	Description of Paint and Plaster Damage	Additional Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Additional Component XRF (positive/negative)	Debris Present (describe location)	Quantity (sf)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Comments/ Description/ Notes
1	1	Classroom 105	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A	Baseboard	Concrete	Grey	Chipping	5	14.1	Positive	None	0	No	No	no	
1	1	Classroom 105	yes	W4	Plaster	White/Beige	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Classroom 105	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A	Baseboard	Concrete	Grey	Chipping	5	15.2	Positive	None	0	No	No	no	
1	1	Classroom 105	yes	Ceiling	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Classroom 105	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Classroom 105 Restroom	yes	W1	Ceramic	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Classroom 105 Restroom	yes	W2	Ceramic	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Classroom 105 Restroom	yes	W3	Ceramic	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Classroom 105 Restroom	yes	W4	Ceramic	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Classroom 105 Restroom	yes	Ceiling	Plaster	White	Cracking	4	33.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Classroom 105 Restroom	yes	Floor	Ceramic	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Classroom 105 Closet	yes	W1	Plaster	Beige	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Classroom 105 Closet	yes	W2	Plaster	Beige	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Classroom 105 Closet	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A	Baseboard	Concrete	Blue	Chipping, Flaking	5	17.3	Positive	None	0	No	No	no	
1	1	Classroom 105 Closet	yes	W3	Plaster	Beige	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Classroom 105 Closet	yes	W4	Plaster	Beige	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Classroom 105 Closet	yes	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Baseboard	Concrete	Blue	Chipping, Flaking	5	12.2	Positive	None	0	No	No	no	
1	1	Classroom 105 Closet	yes	Ceiling	Plaster	Beige	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Classroom 105 Closet	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Classroom 106	yes	W1	Plaster	White	Flaking	1	34.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Classroom 106	yes	W2	Plaster	White	Flaking	1	30.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	At the Arch way by the door
1	1	Classroom 106	yes	W2	Plaster	Blue	Flaking	5	34	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Classroom 106	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A	Baseboard	Concrete	Grey	Chipping, Flaking	2	10.6	Positive	None	0	No	No	no	
1	1	Classroom 106	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A	Cork Board	Wood	Blue	Cracking	2	4.7	Positive	None	0	No	No	no	
1	1	Classroom 106	yes	W3	Plaster	White	Flaking	10	0.12	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Classroom 106	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A	Baseboard	Concrete	Grey	Chipping, Flaking	12	6.3	Positive	None	0	No	No	no	
1	1	Classroom 106	yes	W4	Plaster	White	Flaking	3	0.3	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Classroom 106	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A	Baseboard	Concrete	Grey	Chipping, Flaking	10	14	Positive	None	0	No	No	no	
1	1	Classroom 106	yes	Ceiling	Plaster	White	Flaking	10	24.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	Spread out
1	1	Classroom 106	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Classroom 106 Restroom	yes	W1	Ceramic	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Classroom 106 Restroom	yes	W2	Ceramic	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Classroom 106 Restroom	yes	W3	Ceramic	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Classroom 106 Restroom	yes	W4	Ceramic	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Classroom 106 Restroom	yes	Ceiling	Plaster	White	Cracking	4	29.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Classroom 106 Restroom	yes	Floor	Ceramic	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Classroom 106 Closet	yes	W1	Plaster	Beige	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	Partially Inaccessible
1	1	Classroom 106 Closet	yes	W2	Plaster	Beige	Cracking, Flaking	8	25.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	Partially Inaccessible
1	1	Classroom 106 Closet	yes	W3	Sheetrock	Beige	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	Partially Inaccessible
1	1	Classroom 106 Closet	yes	W4	Plaster	Beige	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	Partially Inaccessible
1	1	Classroom 106 Closet	yes	Ceiling	Plaster	White	Cracking	2	25.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	Partially Inaccessible
1	1	Classroom 106 Closet	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	Partially Inaccessible
1	1	Director's Office 107	yes	W1	Plaster	White/Beige	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Director's Office 107	yes	W2	Plaster	Beige	Efflorescence	1	0.02	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	Unknown	yes	
1	1	Director's Office 107	yes	W3	Plaster	White	Flaking	8	33.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Director's Office 107	yes	W4	Plaster	White	Cracking	6	36.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Director's Office 107	yes	Ceiling	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Director's Office 107	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	Carpet
1	1	Director's Office Restroom	yes	W1	Ceramic	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Director's Office Restroom	yes	W2	Ceramic	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Director's Office Restroom	yes	W3	Ceramic	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Director's Office Restroom	yes	W4	Ceramic	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Director's Office Restroom	yes	Ceiling	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Director's Office Restroom	yes	Floor	Ceramic	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Main Office	yes	W1	Plaster	White/Beige	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Main Office	yes	W2	Plaster	White/Beige	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Main Office	yes	W3	Plaster	White/Beige	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Main Office	yes	W4	Plaster	White/Beige	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Main Office	yes	Ceiling	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Main Office	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	Carpet
1	1	Main Hallway	yes	W1	Plaster	White	Spalling	6	0.05	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	Unknown	yes	
1	1	Main Hallway	yes	W1	Plaster	Beige	Spalling	8	0.02	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	Unknown	yes	
1	1	Main Hallway	yes	W2	Cinderblock	White/Beige	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Main Hallway	yes	W3	Plaster	White	Cracking, Damaged Plaster	6	38	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	yes	Above Circuit breaker room, room 102
1	1	Main Hallway	yes	W3	Plaster	Beige	Cracking	3	37.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Main Hallway	yes	W4	Plaster	White/Beige	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Main Hallway	yes	Ceiling	Plaster	White	Flaking	10	42.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Main Hallway	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Rising Sun Avenue First Floor Stairwell	yes	W1	Plaster	White	Flaking	5	26.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Rising Sun Avenue First Floor Stairwell	yes	W2	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Rising Sun Avenue First Floor Stairwell	yes	W3	Plaster	White	Flaking	8	30.3	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Rising Sun Avenue First Floor Stairwell	yes	W4	Plaster	White/Beige	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Rising Sun Avenue First Floor Stairwell	yes	Ceiling	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Rising Sun Avenue First Floor Stairwell	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	

School District of Philadelphia
Lead Safe Certification Assessment Report
Feltonville Head Start

		Name of Inspector: Ananth K. Vinjamuri Inspection Company: Criterion Labs, Inc.															Inspection Dates: 07/17-07/20/2019 UCLS# 7310						
Element	Floor	On-Site Room Name	Student Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/negative)	Additional Component	Substrate Material	Color	Description of Paint and Plaster Damage	Additional Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Additional Component XRF (positive/negative)	Debris Present (describe location)	Quantity (sf)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Comments/ Description/ Notes
1	1	Rising Sun Avenue First Floor Stairwell	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	Newel posts	Metal	Grey	Friction	4	12.9	Positive	None	0	No	No	no	
1	1	Opposite Rising Sun Avenue First Floor Stairwell	yes	W1	Plaster	White/Beige	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Opposite Rising Sun Avenue First Floor Stairwell	yes	W2	Plaster	White/Beige	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Opposite Rising Sun Avenue First Floor Stairwell	yes	W3	Plaster	White	Flaking	1	36.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Opposite Rising Sun Avenue First Floor Stairwell	yes	W4	Plaster	White/Beige	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Opposite Rising Sun Avenue First Floor Stairwell	yes	Ceiling	Plaster	White	Cracking	6	41.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	1	Opposite Rising Sun Avenue First Floor Stairwell	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Classroom 212 - Used as Storage	yes	W1	Plaster	White	Cracking	4	1.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Classroom 212 - Used as Storage	yes	W1	Plaster	Beige	Cracking	8	22.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Classroom 212 - Used as Storage	yes	W2	Plaster	White/Beige	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Classroom 212 - Used as Storage	yes	W3	Plaster	White	Spalling	10	2.3	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Classroom 212 - Used as Storage	yes	W3	Plaster	Beige	Cracking	4	22.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Classroom 212 - Used as Storage	yes	W4	Plaster	White	Efflorescence, Cracking	8	1.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	Unknown	yes	
1	2	Classroom 212 - Used as Storage	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A	Blackboard Frame	Wood	Purple	Chipping	4	0.21	Negative	None	0	No	No	no	
1	2	Classroom 212 - Used as Storage	yes	Ceiling	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Classroom 212 - Used as Storage	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Classroom 212 Closet	yes	W1	Plaster	White/Beige	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Classroom 212 Closet	yes	W2	Plaster	White/Beige	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Classroom 212 Closet	yes	W3	Plaster	White	Spalling/Efflorescence	10	1.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Window sill, floor	5	No	Unknown	yes	
1	2	Classroom 212 Closet	yes	W4	Plaster	Beige	Cracking	6	18.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Classroom 212 Closet	yes	Ceiling	Plaster	White	Cracking	3	23.3	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	Spread out
1	2	Classroom 212 Closet	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Classroom 211	yes	W1	Plaster	Yellow	Chipping	2	26.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Classroom 211	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	Blackboard Frame	Wood	Orange	Chipping	2	0.28	Negative	None	0	No	No	no	
1	2	Classroom 211	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	Baseboard	Concrete	Brown	Chipping	5	9.5	Positive	None	0	No	No	no	
1	2	Classroom 211	yes	W2	Plaster	Yellow	Cracking	30	12.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Floor	3	No	No	no	
1	2	Classroom 211	yes	W2	Plaster	White	Cracking, Efflorescence	4	1.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Floor	3	No	Unknown	yes	
1	2	Classroom 211	yes	W3	Plaster	Yellow	Cracking	2	0.13	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Classroom 211	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A	Baseboard	Concrete	Brown	Chipping	12	9.9	Positive	None	0	No	No	no	
1	2	Classroom 211	yes	W4	Plaster	Yellow	Cracking	4	25.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Classroom 211	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A	Baseboard	Concrete	Brown	Chipping	15	10	Positive	None	0	No	No	no	
1	2	Classroom 211	yes	Ceiling	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Classroom 211	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Classroom 211 Closet	yes	W1	Plaster	White/Beige	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Classroom 211 Closet	yes	W2	Plaster	White/Beige	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Classroom 211 Closet	yes	W3	Plaster	White	Efflorescence	12	17.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	Unknown	yes	
1	2	Classroom 211 Closet	yes	W3	Plaster	Beige	Efflorescence	4	1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Window sill	2	No	Unknown	Yes	
1	2	Classroom 211 Closet	yes	W4	Plaster	White/Beige	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Classroom 211 Closet	yes	Ceiling	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Classroom 211 Closet	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Office 212C adjacent to Classroom 212	yes	W1	Plaster	White/Beige	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Office 212C adjacent to Classroom 212	yes	W2	Plaster	Yellow	Spalling	3	1.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Office 212C adjacent to Classroom 212	yes	W2	Plaster	White	Crack in Plaster	12	7.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	Radiator is dislodged from the wall and is supported on wood blocks on the left end
1	2	Office 212C adjacent to Classroom 212	yes	W3	Plaster	White/Beige	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Office 212C adjacent to Classroom 212	yes	W4	Plaster	White/Beige	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Office 212C adjacent to Classroom 212	yes	Ceiling	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Office 212C adjacent to Classroom 212	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	Floor Tile
1	2	Office 212C Restroom	yes	W1	Ceramic	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Office 212C Restroom	yes	W2	Ceramic	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Office 212C Restroom	yes	W3	Ceramic	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Office 212C Restroom	yes	W4	Ceramic	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Office 212C Restroom	yes	Ceiling	Plaster	White	Cracking	3	26.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	Spread out
1	2	Office 212C Restroom	yes	Floor	Ceramic	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Classroom 210 Parent Room	yes	W1	Plaster	White/Beige	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Classroom 210 Parent Room	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	Baseboard	Concrete	Brown	Chipping	2	10.2	Positive	None	0	No	No	no	
1	2	Classroom 210 Parent Room	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door	Wood	Purple	Flaking	5	0.13	Negative	None	0	No	No	no	
1	2	Classroom 210 Parent Room	yes	W2	Plaster	White/Beige	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Classroom 210 Parent Room	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A	Baseboard	Concrete	Brown	Chipping	2	9.8	Positive	None	0	No	No	no	
1	2	Classroom 210 Parent Room	yes	W3	Plaster	White/Beige	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Classroom 210 Parent Room	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A	Baseboard	Concrete	Brown	Chipping	3	10.6	Positive	None	0	No	No	no	
1	2	Classroom 210 Parent Room	yes	W4	Wood	White/Beige	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Classroom 210 Parent Room	yes	Ceiling	Plaster	White	Spalling	3	23.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	At the Arch by the entrance
1	2	Classroom 210 Parent Room	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Classroom 210 Closet	yes	W1	Plaster	White	Efflorescence	5	26.6														

School District of Philadelphia
Lead Safe Certification Assessment Report
Feltonville Head Start

Name of Inspector: Ananth K. Vinjamuri
 Inspection Company: Criterion Labs, Inc.

Inspection Dates: 07/17-07/20/2019
 UCLS# 7310

Element	Room	On-Site Room Name	Student Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/negative)	Additional Component	Substrate Material	Color	Description of Paint and Plaster Damage	Additional Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Additional Component XRF (positive/negative)	Debris Present (describe location)	Quantity (sf)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Comments/ Description/ Notes
1	2	Classroom 210 Closet	yes	W1	Plaster	Beige	Cracking	2	1.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Classroom 210 Closet	yes	W2	Plaster	White/Beige	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Classroom 210 Closet	yes	W3	Plaster	White/Beige	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Classroom 210 Closet	yes	W4	Plaster	White/Beige	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Classroom 210 Closet	yes	Ceiling	Plaster	White	Efflorescence, Flaking	5	21.3	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	Unknown	yes	
1	2	Classroom 210 Closet	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Storage Closet with Circuit Breaker	no	W1	Plaster	Beige	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Storage Closet with Circuit Breaker	no	W2	Plaster	Beige	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Storage Closet with Circuit Breaker	no	W3	Plaster	Beige	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Storage Closet with Circuit Breaker	no	W4	Plaster	Beige	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Storage Closet with Circuit Breaker	no	Ceiling	Plaster	Beige	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Storage Closet with Circuit Breaker	no	Floor	Concrete	Grey	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Storage Closet adjacent to the Storage Closet with Circuit Breaker	No	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	0	No Access	No Access	No Access	
1	2	Storage Closet adjacent to the Storage Closet with Circuit Breaker	No	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	0	No Access	No Access	No Access	
1	2	Storage Closet adjacent to the Storage Closet with Circuit Breaker	No	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	0	No Access	No Access	No Access	
1	2	Storage Closet adjacent to the Storage Closet with Circuit Breaker	No	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	0	No Access	No Access	No Access	
1	2	Storage Closet adjacent to the Storage Closet with Circuit Breaker	No	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	0	No Access	No Access	No Access	
1	2	Storage Closet adjacent to the Storage Closet with Circuit Breaker	No	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	0	No Access	No Access	No Access	
1	2	Storage Closet adjacent to the Custodial Closet	No	W1	Plaster	Beige	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Storage Closet adjacent to the Custodial Closet	No	W2	Plaster	Beige	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Storage Closet adjacent to the Custodial Closet	No	W3	Plaster	Beige	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Storage Closet adjacent to the Custodial Closet	No	W4	Plaster	Beige	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Storage Closet adjacent to the Custodial Closet	No	Ceiling	Plaster	Beige	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Storage Closet adjacent to the Custodial Closet	No	Floor	Concrete	Grey	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Custodial Closet	No	W1	Sheetrock	Beige	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Custodial Closet	No	W2	Sheetrock	Beige	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Custodial Closet	No	W3	Plaster	Beige	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Custodial Closet	No	W4	Sheetrock	Beige	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Custodial Closet	No	Ceiling	Plaster	Beige	Cracking	3	24.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Custodial Closet	No	Floor	Ceramic	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Classroom 209 Multipurpose Room	yes	W1	Plaster	Beige	Cracking, Damaged plaster	2	1.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	yes	by the phone
1	2	Classroom 209 Multipurpose Room	yes	W2	Wood	Beige	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Classroom 209 Multipurpose Room	yes	W3	Plaster	Beige	Cracking	3	1.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	Spread out
1	2	Classroom 209 Multipurpose Room	yes	W3	Plaster	White	Flaking	4	0.03	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	by windows
1	2	Classroom 209 Multipurpose Room	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A	Baseboard	Concrete	Brown	Chipping	7	9.9	Positive	None	0	No	No	no	
1	2	Classroom 209 Multipurpose Room	yes	W4	Plaster	Beige	Cracking, Damaged plaster	2	1.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	yes	near entrance
1	2	Classroom 209 Multipurpose Room	yes	Ceiling	Plaster	White	Cracking	4	30.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Classroom 209 Multipurpose Room	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Classroom 209 Closet	yes	W1	Plaster	White/Beige	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Classroom 209 Closet	yes	W2	Plaster	Beige	Flaking	1	1.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Classroom 209 Closet	yes	W3	Plaster	White/Beige	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Classroom 209 Closet	yes	W4	Plaster	Beige	Flaking, Chipping	10	20.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Classroom 209 Closet	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A	Vent Cover	Metal	Beige	Cracking	10	7.7	Positive	None	0	No	No	no	
1	2	Classroom 209 Closet	yes	Ceiling	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Classroom 209 Closet	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Classroom 209 Closet Foyer	yes	W1	Plaster	White/Beige	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Classroom 209 Closet Foyer	yes	W2	Plaster	White/Beige	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Classroom 209 Closet Foyer	yes	W3	Plaster	White/Beige	Cracking	8	23.3	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Classroom 209 Closet Foyer	yes	W4	Plaster	White/Beige	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Classroom 209 Closet Foyer	yes	Ceiling	Plaster	White	Flaking	2	29.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Classroom 209 Closet Foyer	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Classroom 209 Teacher's Closet by entrance	yes	W1	Plaster	Beige	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Classroom 209 Teacher's Closet by entrance	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door	Metal	Black	Friction	5	0.19	Negative	None	0	No	No	no	
1	2	Classroom 209 Teacher's Closet by entrance	yes	W2	Plaster	Beige	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Classroom 209 Teacher's Closet by entrance	yes	W3	Plaster	Beige	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Classroom 209 Teacher's Closet by entrance	yes	W4	Plaster	Beige	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Classroom 209 Teacher's Closet by entrance	yes	Ceiling	Plaster	Beige	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Classroom 209 Teacher's Closet by entrance	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Classroom 208	yes	W1	Plaster	Beige	Cracking	3	21.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Classroom 208	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	Baseboard	Concrete	Brown	Chipping	5	10.1	Positive	None	0	No	No	no	
1	2	Classroom 208	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	Blackboard Frame	Wood	Purple	Chipping	4	0.18	Negative	None	0	No	No	no	
1	2	Classroom 208	yes	W2	Plaster	Beige	Cracking, Flaking	3	21.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	

School District of Philadelphia
Lead Safe Certification Assessment Report
Feltonville Head Start

Name of Inspector: Ananth K. Vinjamuri
 Inspection Company: Criterion Labs, Inc.

Inspection Dates: 07/17-07/20/2019
 UCLS# 7310

Element	Room	On-Site Room Name	Student Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/negative)	Additional Component	Substrate Material	Color	Description of Paint and Plaster Damage	Additional Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Additional Component XRF (positive/negative)	Debris Present (describe location)	Quantity (sf)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Comments/ Description/ Notes
1	2	Classroom 208	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A	Baseboard	Concrete	Brown	Chipping	6	7	Positive	None	0	No	No	no	
1	2	Classroom 208	yes	W3	Plaster	Beige	Cracking	2	0.04	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Classroom 208	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A	Baseboard	Concrete	Brown	Chipping	4	9.3	Positive	None	0	No	No	no	
1	2	Classroom 208	yes	W4	Plaster	Beige	Cracking	2	0.07	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Classroom 208	yes	W4	Plaster	White	Cracking	10	1.3	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Classroom 208	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A	Baseboard	Concrete	Brown	Chipping	5	7.3	Positive	None	0	No	No	no	
1	2	Classroom 208	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A	Blackboard Frame	Wood	Purple	Chipping	7	0.23	Negative	None	0	No	No	no	
1	2	Classroom 208	yes	Ceiling	Plaster	White	Cracking, Crack in plaster	6	31.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	yes	
1	2	Classroom 208	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Classroom 208 Closet	yes	W1	Plaster	White	Cracking	2	13.3	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Classroom 208 Closet	yes	W2	Plaster	White	Cracking	7	21.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Classroom 208 Closet	yes	W3	Plaster	White	Flaking	3	23.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	Above window
1	2	Classroom 208 Closet	yes	W4	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Classroom 208 Closet	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A	Vent Cover	Metal	White	Cracking, Chipping	2	8.6	Positive	None	0	No	No	no	Student items to be moved
1	2	Classroom 208 Closet	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A	Coat Hanger	Wood	White	Chipping	3	0.26	Negative	None	0	No	No	no	
1	2	Classroom 208 Closet	yes	Ceiling	Plaster	White	Flaking	5	21.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Classroom 208 Closet	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Classroom 207 Staff Room	yes	W1	Plaster	White/Beige	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Classroom 207 Staff Room	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door	Wood	Purple	Flaking	8	0.3	Negative	None	0	No	No	no	
1	2	Classroom 207 Staff Room	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	Blackboard Frame	Wood	Purple	Chipping	10	0.05	Negative	None	0	No	No	no	
1	2	Classroom 207 Staff Room	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	Baseboard	Concrete	Brown	Chipping	2	14.1	Positive	None	0	No	No	no	
1	2	Classroom 207 Staff Room	yes	W2	Plaster	White	Cracking, Flaking	22	1.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Classroom 207 Staff Room	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A	Baseboard	Concrete	Brown	Chipping	20	11.1	Positive	None	0	No	No	no	
1	2	Classroom 207 Staff Room	yes	W3	Plaster	Beige	Cracking	4	2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	At single window
1	2	Classroom 207 Staff Room	yes	W3	Plaster	Beige	Spalling	4	1.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	Unknown	yes	At right window
1	2	Classroom 207 Staff Room	yes	W3	Plaster	White	Cracking	6	0.02	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Classroom 207 Staff Room	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A	Baseboard	Concrete	Brown	Chipping	5	11.6	Positive	None	0	No	No	no	
1	2	Classroom 207 Staff Room	yes	W4	Plaster	White/Beige	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Classroom 207 Staff Room	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A	Baseboard	Concrete	Brown	Chipping	7	14.8	Positive	None	0	No	No	no	
1	2	Classroom 207 Staff Room	yes	Ceiling	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Classroom 207 Staff Room	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Classroom 207 Closet	yes	W1	Plaster	White/Beige	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Classroom 207 Closet	yes	W2	Plaster	White	Cracking	20	18.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Classroom 207 Closet	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A	Vent Cover	Metal	White	Chipping	2	11	Positive	None	0	No	No	no	Children's game boxes on shelves
1	2	Classroom 207 Closet	yes	W3	Plaster	White	Efflorescence	4	0.04	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	Unknown	Yes	
1	2	Classroom 207 Closet	yes	W4	Plaster	White	Cracking	10	16.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Classroom 207 Closet	yes	Ceiling	Plaster	White	Efflorescence, Flaking	10	28.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	Unknown	Yes	
1	2	Classroom 207 Closet	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Faculty Restroom adjacent to Classroom 207	yes	W1	Ceramic	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Faculty Restroom adjacent to Classroom 207	yes	W2	Ceramic	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Faculty Restroom adjacent to Classroom 207	yes	W3	Ceramic	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Faculty Restroom adjacent to Classroom 207	yes	W4	Ceramic	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Faculty Restroom adjacent to Classroom 207	yes	Ceiling	Plaster	White	Cracking	3	24.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Faculty Restroom adjacent to Classroom 207	yes	Floor	Ceramic	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Hallway from Faculty Restroom to Second Floor Main Hallway	yes	W1	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Hallway from Faculty Restroom to Second Floor Main Hallway	yes	W2	Plaster	White	Cracking	4	30.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Hallway from Faculty Restroom to Second Floor Main Hallway	yes	W3	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Hallway from Faculty Restroom to Second Floor Main Hallway	yes	W4	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Hallway from Faculty Restroom to Second Floor Main Hallway	yes	Ceiling	Plaster	White	Flaking, Cracking	3	32.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Hallway from Faculty Restroom to Second Floor Main Hallway	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Storage Room adjacent to the Faculty Restroom	yes	W1	Plaster	White/Blue	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Storage Room adjacent to the Faculty Restroom	yes	W2	Plaster	White/Blue	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Storage Room adjacent to the Faculty Restroom	yes	W3	Plaster	White/Blue	Spalling, Efflorescence	10	4.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Window sill	1	No	Unknown	yes	
1	2	Storage Room adjacent to the Faculty Restroom	yes	W4	Plaster	White/Blue	Spalling, Efflorescence	7	1.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Window sill radiator	3	No	Unknown	yes	
1	2	Storage Room adjacent to the Faculty Restroom	yes	Ceiling	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Storage Room adjacent to the Faculty Restroom	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	Floor Tile
1	2	Storage Closet across from the Faculty Restroom	no	W1	Plaster	Beige	Flaking	14	9.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Storage Closet across from the Faculty Restroom	no	W2	Plaster	Beige	Flaking, Efflorescence	14	16.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Floor	5	No	Unknown	yes	

School District of Philadelphia
Lead Safe Certification Assessment Report
Feltonville Head Start

Name of Inspector: Ananth K. Vinjamuri
 Inspection Company: Criterion Labs, Inc.

Inspection Dates: 07/17-07/20/2019
 UCL# 7310

Element	Floor	On-Site Room Name	Student Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/negative)	Additional Component	Substrate Material	Color	Description of Paint and Plaster Damage	Additional Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Additional Component XRF (positive/negative)	Debris Present (describe location)	Quantity (sf)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Comments/ Description/ Notes
1	2	Storage Closet across from the Faculty Restroom	no	W3	Plaster	Beige	Cracking, Efflorescence	35	15.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Floor	5	No	Unknown	yes	
1	2	Storage Closet across from the Faculty Restroom	no	W4	Plaster	Beige	Cracking	14	15.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Storage Closet across from the Faculty Restroom	no	Ceiling	Plaster	Beige	Cracking	10	10.3	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Storage Closet across from the Faculty Restroom	no	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	Floor Tile
1	2	Second Floor Main Hallway	yes	W1	Plaster	White	Cracking, Efflorescence	40	1.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Second Floor Main Hallway	yes	W1	Plaster	Beige	Spalling	6	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	Unknown	yes	
1	2	Second Floor Main Hallway	yes	W2	Cinderblock	White/Beige	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Second Floor Main Hallway	yes	W3	Plaster	White	Cracking	3	25.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Second Floor Main Hallway	yes	W3	Plaster	Beige	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Second Floor Main Hallway	yes	W4	Cinderblock	White/Beige	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Second Floor Main Hallway	yes	Ceiling	Plaster	White	Cracking	22	34	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Second Floor Main Hallway	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Rising Sun Avenue Second Floor Stairwell	yes	W1	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Rising Sun Avenue Second Floor Stairwell	yes	W2	Cinderblock	White/Beige	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Rising Sun Avenue Second Floor Stairwell	yes	W2	Plaster	White	Cracking	10	20.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Rising Sun Avenue Second Floor Stairwell	yes	W3	Plaster	White	Cracking	15	26.3	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Rising Sun Avenue Second Floor Stairwell	yes	W4	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Rising Sun Avenue Second Floor Stairwell	yes	Ceiling	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Rising Sun Avenue Second Floor Stairwell	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Rising Sun Avenue Second Floor Stairwell	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	Stair risers	Concrete	Grey	Cracking	66	20.6	Positive	None	0	No	No	no	11 steps
1	2	Opposite Rising Sun Avenue Second Floor Stairwell	yes	W1	Plaster	White	Cracking	1	25.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Opposite Rising Sun Avenue Second Floor Stairwell	yes	W2	Plaster	White	Cracking	14	31.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Opposite Rising Sun Avenue Second Floor Stairwell	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A	Baseboard	Concrete	Grey	Chipping	3	18.7	Positive	None	0	No	No	no	
1	2	Opposite Rising Sun Avenue Second Floor Stairwell	yes	W3	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Opposite Rising Sun Avenue Second Floor Stairwell	yes	W4	Plaster	White	Cracking	2	34	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Opposite Rising Sun Avenue Second Floor Stairwell	yes	Ceiling	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Opposite Rising Sun Avenue Second Floor Stairwell	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	2	Opposite Rising Sun Avenue Second Floor Stairwell	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	Newel posts	Concrete	Grey	Friction	6	13.7	Positive	None	0	No	No	no	
1	2	Opposite Rising Sun Avenue Second Floor Stairwell	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	Ballustrades	Concrete	Grey	Friction	20	6	Positive	None	0	No	No	no	