



THE SCHOOL DISTRICT OF  
PHILADELPHIA

BOARD OF EDUCATION  
Office of Capital Programs  
440 North Broad Street, 3<sup>rd</sup> Floor – Suite 371  
Philadelphia, PA 19130

TELEPHONE: (215) 400-4730

**Addendum No. 8**

**Subject: SDP Contracts No. B-11 C, B-112 C, B-113 C and B-114 C of 2017/18  
Major Renovation and Addition**

**Location: Richmond Elementary School**

---

**This Addendum, dated December 31, 2019, shall modify and become part of the Contract Documents. Any items not mentioned herein, or affected by, shall remain strictly in accordance with the original document.**

---

**1. THE ATTACHED BID PROPOSAL FORM (REBID) CORRECTED MUST BE USED TO SUBMIT YOUR BID.**

**(Discrepancies in Quantities for Unit Prices No 1 and No 2 have been corrected.)**

**2. THE ATTACHED LEAD SAFE CERTIFICATION ASSESSMENT-SCOPE OF WORK IS INCLUDED IN THE PROJECT SCOPE OF WORK FOR PAINT AND PLASTER REPAIRS**

**3. RESPONSES TO BIDDER QUESTIONS:**

**A. Unit Prices No 1 and No 2 apply to removal and replacement of unsuitable soil beyond the design limits.**

**B. Unit Price No 3 applies to Paint and Plaster Repairs in the designated Basement Spaces**

**C. Unit Prices No. 4 and No. 5 apply to plaster repairs in rooms or spaces not included in the Lead Safe Certification Assessment-Scope of Work, or not accessible at the time of inspection.**

**D. Bidders must furnish a New Bid Bond for the Rebid, but do not need to submit a New Bid Processing Fee, if they submitted one for the prior bid.**

**Addendum No. 8 (cont'd)**

**End of Addendum No. 8**

**ATTACHMENTS:**

- 1. (GC-BID PROPOSAL FORM-REBID) CORRECTED.**
- 2. LEAD SAFE CERTIFICATION ASSESSMENT-SCOPE OF WORK**

**BID PROPOSAL FORM (REBID) CORRECTED  
MAJOR RENOVATION AND ADDITION  
RICHMOND ELEMENTARY SCHOOL**

**Contract No. B-111C (R) of 2017/18 General Construction**

**TO:** The School District of Philadelphia  
Board of Education

**OWNER**

Office of Capital Programs  
The School District of Philadelphia  
440 North Broad Street  
Third Floor - Suite 371  
Philadelphia, PA 19130-4015

**ADDRESS**

**FROM:** \_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

**CONTRACTOR  
ADDRESS**

**CITY/STATE  
CONTACT NAME  
PHONE NO.**

**BASE CONTRACT PROPOSAL:**

1. Having become completely familiar with the local conditions affecting the cost of Work at the place where Work is to be executed, and having carefully examined the site conditions as they currently exist, and having carefully examined the Bidding and Contract Documents prepared for this project, together with any Addenda to such Bidding and Contract Documents as listed hereinafter, the Undersigned hereby proposes and agrees to provide all labor, materials, plant, equipment, transportation and other facilities as necessary and/or required to execute all of the Work described by the Contract Documents for: **Contract No. B-111C (R) of 2017/18-General Construction**

for the lump sum consideration of: \_\_\_\_\_ Dollars (\$\_\_\_\_\_), said amount being hereinafter referred to as the Base Proposal Amount. Base proposal Amount includes Unit Price Items listed below, if applicable.

**BID ALTERNATES (Not applicable to this Contract – No Alternates)**

**UNIT PRICES: (Included Base Bid Amount)**

**UNIT PRICE NO. 1: EXCAVATION AND DISPOSAL OF UNSUITABLE SOILS ONLY.**

1. Excavation and Disposal of **unsuitable** material beyond the design lines, grades and elevations or other limits indicated in the Contract Documents, as directed by the Owner's designated representative in accordance with Section 31 000-EARTHWORK , as applicable. (This unit price does not apply to excavation and offsite disposal of **suitable** material rendered **excess** by the construction of the New Addition))

2. Unit of Measurement: Cubic yard (CY) of excavated material as measured by the volume of the excavated area.

3. Payment: Payment to be made for the actual quantities in accordance with Section 01 1600-UNIT PRICES.

4. Base Bid Quantity: 1,200 CY

5. Unit Price Calculation (to be included in Base Bid Amount):

1,200 CY @ \$ \_\_\_\_\_ per CY=  
\$ \_\_\_\_\_ Total\*

**\*This amount included in Base Bid Amount**

**UNIT PRICE NO. 2: IMPORTED STRUCTURAL FILL MATERIAL**

1. Import, Place and Compact Fill Material, determined by testing as suitable for structural fill to Replace Unsuitable Soils excavated under Unit Price No.1 with the requirements of Section 31 0000-EARTHWORK.

2. Unit of Measurement: Cubic Yard (CY) of material in place, as measured by the volume of the excavated area to be filled.

3. Payment: Payment to be made for the actual quantities in accordance with Section 01 1600-UNIT PRICES.

4. Base Bid Quantity: 1,200 CY

5. Unit Price Calculation (Total to be included in Base Bid Amount):

1,200 CY @ \$ \_\_\_\_\_ per CY =

\$ \_\_\_\_\_ Total\*

**\*This amount included in Base Bid Amount**

**UNIT PRICE No. 3: PAINT AND PLASTER REPAIRS IN BASEMENT ROOMS 003, 004, 005 AND 006** and required documentation in accordance with the requirements of Section 09 0290 PLASTER PATCHING AND REPAIR **AND** Section 09 9123 PAINTING, as directed by the owner's representative.

1. Unit of Measurement: Per Square Foot (SF)

2. Payment: Payment will be made for the actual quantities furnished in accordance with Section 01 16 00 - UNIT PRICES.

3. Base Bid Quantity: 15,000 SF

4. Unit Price Calculation: 15,000 SF @ \$ \_\_\_\_\_ per SF =

\$ \_\_\_\_\_ **TOTAL\***

**\*This amount included in Lump Sum Price above**

**UNIT PRICE No. 4: PATCHING WALLS (Spackling)** in areas **not included** in the base scope of work and required documentation in accordance with the requirements of Section 09 0290 PLASTER PATCHING AND REPAIR as directed by the owner's representative as directed by the owner's representative.

1. Unit of Measurement: Per Square Foot (SF)
2. Payment: Payment will be made for the actual quantities furnished in accordance with Section 01 16 00 - UNIT PRICES.
3. Base Bid Quantity: 5,000 SF
4. Unit Price Calculation: 5,000 SF @ \$\_\_\_\_\_ per SF =  
\$\_\_\_\_\_ **TOTAL\***

**\*This amount included in Lump Sum Price above**

**UNIT PRICE No. 5: PATCHING WALLS (Plaster Work)** in areas **not included** in the base scope of work and required documentation in accordance with the requirements of Section 09 0290 PLASTER PATCHING AND REPAIR as directed by the owner's representative as directed by the owner's representative.

1. Unit of Measurement: Per Square Foot (SF)
2. Payment: Payment will be made for the actual quantities furnished in accordance with Section 01 16 00 - UNIT PRICES.
3. Base Bid Quantity: 5,000 SF
4. Unit Price Calculation: 5,000 SF @ \$\_\_\_\_\_ per SF =  
\$\_\_\_\_\_ **TOTAL\***

**\*This amount included in Lump Sum Price above**

**ACKNOWLEDGEMENT OF RECEIPT OF ADDENDA:**

---

---

2. The Undersigned acknowledges receipt of the following Addenda (list by number and date appearing on Addenda):

| <u>Addendum No.</u> | <u>Date</u> | <u>Addendum No.</u> | <u>Date</u> |
|---------------------|-------------|---------------------|-------------|
| _____               | _____       | _____               | _____       |
| _____               | _____       | _____               | _____       |
| _____               | _____       | _____               | _____       |
| _____               | _____       | _____               | _____       |

**TIME OF COMPLETION:**

3. The Undersigned agrees to Substantially Complete all Work under this Contract within the time periods specified in Division 1, General Requirements, Section 00 1300 entitled "Time of Completion, Milestones and Phasing or Sequencing Requirements".

**INSURANCE:**

4. All Bidders are instructed to refer to Article GC-11 of the General Conditions. All Contractors or Subcontractors bidding Work on the Project shall include in their bids the costs of Workers Compensation and Employer's Liability Insurance, Commercial General Liability Insurance, Automobile Liability Insurance, Excess Umbrella Liability Insurance (Commercial Umbrella Liability Insurance) and any other types of insurance identified in Division 1- General Requirements, Section 01200 (or 01 1200) entitled "Special Insurance Requirements".

**LIQUIDATED DAMAGES:**

5. Upon failure by the Contractor to achieve Substantial Completion within the

time specified in Article GC-8 of the General Conditions from the Date of Commencement as set forth in the Notice to Proceed, the Contractor shall pay to the School District, as liquidated damages and not as a penalty, the sum of One Thousand Dollars (\$1,000.00) per day for each consecutive calendar day of delay until such time as Substantial Completion of the Work is achieved.

6. In addition, the Contractor shall be responsible for and pay for the cost of completion of construction of the Work, as well as for any and all additional charges of the School District, Architect/Engineer, other Project Contractors, and any other Consultants to the School District relating to the Contractor's failure to achieve Substantial Completion on a timely basis, including, but not limited to, delay damages, disruption damages, acceleration costs or expenses, investigative expenses, consulting fees, experts' fees, and attorneys' fees.

7. The Contractor and the School District agree that the amounts so fixed herein as liquidated damages are reasonable forecasts of just compensation for the harm that will be caused to the School District by the Contractor's breach.

**GENERAL STATEMENT:**

8. The Undersigned declares that the person or persons signing this Proposal is/are fully authorized to sign on behalf of the firm listed and to fully bind the firm listed to all the Proposal's conditions and provisions thereof.

9. It is agreed that the Undersigned has complied or will comply with all requirements of local, state, and federal laws, and that no legal requirement has been or will be violated in making or accepting this Proposal, in awarding the Contract to it and/or in prosecution of the Work.

10. Bid Security in the amount of ten percent (10%) of the Base Bid, plus all additive Alternates Proposal amounts, is attached hereto and made a part hereof, without endorsement, in the sum of \_\_\_\_\_ Dollars (\$\_\_\_\_\_), which shall become the property of the School District in the event the Contract and Performance Bond and Labor and Materialmen's Bond are not executed within the time set forth, as liquidated damages.

11. The Undersigned further agrees within five (5) calendar days from date of Notice of Acceptance of this Proposal or Contract award, to sign and deliver to the School District, all required copies of the School District/Contractor Agreement, the Performance Bond, the Labor and Materialmen's Bond, and the Maintenance Bond, in the forms included in the Bidding Documents, and the policies of insurance or insurance certificates as required by the General Conditions. In case the undersigned fails or neglects to deliver within the specified time the School District/Contractor Agreement, the Performance Bond, the Labor and Materialmen's Bond, and the Maintenance Bond, and the insurance policies or certificates, all as aforesaid, the undersigned shall be considered as having



abandoned the Contract, and the Bid Bond accompanying this Proposal shall be forfeited to the School District by reason of such failure on the part of the undersigned, as liquidated damages and not as a penalty.

12. The Undersigned further agrees that the Bid Security may be retained by the School District and shall remain with the School District until the School District/Contractor Agreement has been signed and delivered to the School District and the Performance Bond, the Labor and Materialmen's Bond, and the Maintenance Bond, and insurance policies or certificates have been made and delivered to the School District.

Respectfully submitted this \_\_\_\_\_ day of \_\_\_\_\_, 201\_.

***Individual Proprietorship or Partnership***

If Contractor is an individual proprietorship or is a partnership, sign here:

\_\_\_\_\_  
(Trade Name of Firm)

By: \_\_\_\_\_ By: \_\_\_\_\_ (SEAL)  
(Witness) (Owner or Partner)

***Corporation***

If Contractor is a corporation, sign here:

\_\_\_\_\_  
(Name of Corporation)

ATTEST:

By: \_\_\_\_\_ By: \_\_\_\_\_ (SEAL)  
(Secretary or Treasurer) (President or Vice President)

(CORPORATE SEAL)

Signature by anyone other than the President or Vice President and the Secretary or Treasurer of the Corporation must be accompanied by a power of attorney, executed by the proper corporate officers under the corporate seal indicating authority to execute this Bi

| ULCS# | Element | Floor | Space # | On-Site Room Name                 | Student/Teacher Occupied (yes/no) | Component          | Description of Damage     | XRF (positive/negative) | Debris Present (describe location) | Quantity (sf) | Contents Need to be Moved | Plastering Needed (yes or no) | Comments/ Description/ Notes |
|-------|---------|-------|---------|-----------------------------------|-----------------------------------|--------------------|---------------------------|-------------------------|------------------------------------|---------------|---------------------------|-------------------------------|------------------------------|
| 5400  | 1       | 1     | 101     | Classroom 101                     | yes                               | W1                 | Chipping                  | Positive                | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | 101     | Classroom 101                     | yes                               | W2                 | None                      | N/A                     | None                               | 0             | No                        | no                            | Partition Wall               |
| 5400  | 1       | 1     | 101     | Classroom 101                     | yes                               | W3                 | None                      | N/A                     | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | 101     | Classroom 101                     | yes                               | W4                 | Staple Holes              | Positive                | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | 101     | Classroom 101                     | yes                               | Ceiling            | Flaking                   | Positive                | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | 101     | Classroom 101                     | yes                               | Floor              | None                      | N/A                     | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | 101A    | Classroom 101 Closet              | yes                               | W1                 | Flaking                   | Positive                | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | 101A    | Classroom 101 Closet              | yes                               | W2                 | Flaking                   | Positive                | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | 101A    | Classroom 101 Closet              | yes                               | W3                 | None                      | N/A                     | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | 101A    | Classroom 101 Closet              | yes                               | Pipe               | Chipping                  | Positive                | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | 101A    | Classroom 101 Closet              | yes                               | W4                 | None                      | N/A                     | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | 101A    | Classroom 101 Closet              | yes                               | Ceiling            | Flaking                   | Positive                | on ceiling tiles                   | 10            | No                        | no                            |                              |
| 5400  | 1       | 1     | 101A    | Classroom 101 Closet              | yes                               | Floor              | None                      | N/A                     | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | 102     | Classroom 102                     | yes                               | W1                 | Chipping                  | Positive                | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | 102     | Classroom 102                     | yes                               | W2                 | None                      | N/A                     | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | 102     | Classroom 102                     | yes                               | W3                 | Alligating                | Positive                | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | 102     | Classroom 102                     | yes                               | W4                 | None                      | N/A                     | None                               | 0             | No                        | no                            | Partition Wall               |
| 5400  | 1       | 1     | 102     | Classroom 102                     | yes                               | Ceiling            | Flaking                   | Positive                | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | 102     | Classroom 102                     | yes                               | Floor              | None                      | N/A                     | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | 102B    | Classroom 102 Closet              | yes                               | W1                 | Efflorescence/fFlaking    | Positive                | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | 102B    | Classroom 102 Closet              | yes                               | W2                 | None                      | N/A                     | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | 102B    | Classroom 102 Closet              | yes                               | W3                 | None                      | N/A                     | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | 102B    | Classroom 102 Closet              | yes                               | W4                 | Alligating                | Positive                | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | 102B    | Classroom 102 Closet              | yes                               | Ceiling            | Flaking                   | Positive                | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | 102B    | Classroom 102 Closet              | yes                               | Floor              | None                      | N/A                     | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | H11     | Hallway from Classroom 101 to 102 | yes                               | W1                 | None                      | N/A                     | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | H11     | Hallway from Classroom 101 to 102 | yes                               | W2                 | None                      | N/A                     | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | H11     | Hallway from Classroom 101 to 102 | yes                               | Electrical Panel   | Chipping                  | Positive                | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | H11     | Hallway from Classroom 101 to 102 | yes                               | W3                 | Flaking                   | Positive                | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | H11     | Hallway from Classroom 101 to 102 | yes                               | W4                 | Cracking                  | Positive                | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | H11     | Hallway from Classroom 101 to 102 | yes                               | pipe               | Flaking                   | Positive                | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | H11     | Hallway from Classroom 101 to 102 | yes                               | Ceiling            | Moisture Damage/Flaking   | Positive                | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | H11     | Hallway from Classroom 101 to 102 | yes                               | Floor              | None                      | N/A                     | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | 102A    | Nurse's Office                    | yes                               | W1                 | None                      | N/A                     | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | 102A    | Nurse's Office                    | yes                               | Baseboard          | Friction                  | Positive                | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | 102A    | Nurse's Office                    | yes                               | Chair Rail         | Friction                  | Positive                | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | 102A    | Nurse's Office                    | yes                               | Door               | Friction, Flaking         | Positive                | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | 102A    | Nurse's Office                    | yes                               | Door frame         | Friction                  | Positive                | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | 102A    | Nurse's Office                    | yes                               | W2                 | None                      | N/A                     | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | 102A    | Nurse's Office                    | yes                               | Baseboard          | Friction                  | Positive                | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | 102A    | Nurse's Office                    | yes                               | Chair Rail         | Friction                  | Positive                | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | 102A    | Nurse's Office                    | yes                               | Pipe               | Chipping                  | Positive                | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | 102A    | Nurse's Office                    | yes                               | Poster Board Frame | Pin Holes                 | Positive                | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | 102A    | Nurse's Office                    | yes                               | W3                 | Flaking, Chipping         | Positive                | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | 102A    | Nurse's Office                    | yes                               | Baseboard          | Friction                  | Positive                | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | 102A    | Nurse's Office                    | yes                               | Chair Rail         | Friction                  | Positive                | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | 102A    | Nurse's Office                    | yes                               | W4                 | Moisture Damage, Cracking | Positive                | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | 102A    | Nurse's Office                    | yes                               | Baseboard          | Friction                  | Positive                | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | 102A    | Nurse's Office                    | yes                               | Chair Rail         | Friction                  | Positive                | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | 102A    | Nurse's Office                    | yes                               | Hutch              | Flaking                   | Positive                | None                               | 0             | Prior to Repair           | no                            | Attached to the wall.        |

| ULCS# | Element | Floor | Space # | On-Site Room Name       | Student/Teacher Occupied (yes/no) | Component                | Description of Damage       | XRF (positive/negative) | Debris Present (describe location) | Quantity (sf) | Contents Need to be Moved | Plastering Needed (yes or no) | Comments/ Description/ Notes |
|-------|---------|-------|---------|-------------------------|-----------------------------------|--------------------------|-----------------------------|-------------------------|------------------------------------|---------------|---------------------------|-------------------------------|------------------------------|
| 5400  | 1       | 1     | 102A    | Nurse's Office          | yes                               | Door                     | Friction, Flaking           | Positive                | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | 102A    | Nurse's Office          | yes                               | Door frame               | Friction                    | Positive                | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | 102A    | Nurse's Office          | yes                               | Mirror Frame             | Flaking                     | Positive                | None                               | 0             | No                        | no                            | Attached to the wall.        |
| 5400  | 1       | 1     | 102A    | Nurse's Office          | yes                               | Ceiling                  | N/A                         | N/A                     | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | 102A    | Nurse's Office          | yes                               | Floor                    | N/A                         | N/A                     | None                               | 0             | No                        | no                            | Floor tile.                  |
| 5400  | 1       | 1     | 102C    | Nurse's Office Restroom | yes                               | W1                       | None                        | N/A                     | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | 102C    | Nurse's Office Restroom | yes                               | Door                     | Friction, Flaking           | Positive                | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | 102C    | Nurse's Office Restroom | yes                               | Door Frame               | Friction, Flaking           | Positive                | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | 102C    | Nurse's Office Restroom | yes                               | W2                       | Moisture Damage             | Positive                | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | 102C    | Nurse's Office Restroom | yes                               | Window Frame             | Flaking                     | Positive                | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | 102C    | Nurse's Office Restroom | yes                               | W3                       | None                        | N/A                     | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | 102C    | Nurse's Office Restroom | yes                               | Pipe                     | Chipping                    | Positive                | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | 102C    | Nurse's Office Restroom | yes                               | W4                       | None                        | N/A                     | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | 102C    | Nurse's Office Restroom | yes                               | Window Frame             | Flaking                     | Positive                | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | 102C    | Nurse's Office Restroom | yes                               | Ceiling                  | N/A                         | N/A                     | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | 102C    | Nurse's Office Restroom | yes                               | Floor                    | None                        | N/A                     | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | 103     | Classroom 103           | yes                               | W1                       | Chipping, Cracking, Flaking | Positive                | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | 103     | Classroom 103           | yes                               | W2                       | None                        | N/A                     | None                               | 0             | No                        | no                            | Partition Wall               |
| 5400  | 1       | 1     | 103     | Classroom 103           | yes                               | W3                       | Chipping, Cracking          | Positive                | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | 103     | Classroom 103           | yes                               | W4                       | None                        | N/A                     | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | 103     | Classroom 103           | yes                               | Ceiling                  | Moisture Damage/Flaking     | Positive                | on ceiling tiles                   | 300           | Prior to Repair           | yes                           |                              |
| 5400  | 1       | 1     | 103     | Classroom 103           | yes                               | Floor                    | None                        | N/A                     | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | 103A    | Classroom 103 Closet    | yes                               | W1                       | Chipping, cracking          | Positive                | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | 103A    | Classroom 103 Closet    | yes                               | W2                       | Flaking                     | Positive                | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | 103A    | Classroom 103 Closet    | yes                               | Radiator                 | Alligatoring                | Positive                | Floor                              | 5             | No                        | no                            |                              |
| 5400  | 1       | 1     | 103A    | Classroom 103 Closet    | yes                               | W3                       | Flaking                     | Positive                | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | 103A    | Classroom 103 Closet    | yes                               | W4                       | None                        | N/A                     | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | 103A    | Classroom 103 Closet    | yes                               | Ceiling                  | Flaking                     | Positive                | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | 103A    | Classroom 103 Closet    | yes                               | Floor                    | None                        | N/A                     | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | 104     | Classroom 104           | yes                               | W1                       | Chipping                    | Positive                | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | 104     | Classroom 104           | yes                               | W2                       | None                        | N/A                     | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | 104     | Classroom 104           | yes                               | W3                       | None                        | N/A                     | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | 104     | Classroom 104           | yes                               | W4                       | None                        | N/A                     | None                               | 0             | No                        | no                            | Partition Wall               |
| 5400  | 1       | 1     | 104     | Classroom 104           | yes                               | Ceiling                  | None                        | N/A                     | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | 104     | Classroom 104           | yes                               | Floor                    | None                        | N/A                     | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | 104A    | Classroom 104 Closet    | yes                               | W1                       | Holes                       | Positive                | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | 104A    | Classroom 104 Closet    | yes                               | W2                       | None                        | N/A                     | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | 104A    | Classroom 104 Closet    | yes                               | W3                       | Flaking                     | Positive                | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | 104A    | Classroom 104 Closet    | yes                               | W4                       | None                        | N/A                     | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | 104A    | Classroom 104 Closet    | yes                               | Ceiling                  | None                        | N/A                     | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | 104A    | Classroom 104 Closet    | yes                               | Floor                    | None                        | N/A                     | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | LOBBY   | Main Entrance Lobby     | yes                               | W1                       | None                        | N/A                     | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | LOBBY   | Main Entrance Lobby     | yes                               | Door                     | Friction                    | Negative                | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | LOBBY   | Main Entrance Lobby     | yes                               | Door Frame               | Friction                    | Negative                | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | LOBBY   | Main Entrance Lobby     | yes                               | W2                       | None                        | N/A                     | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | LOBBY   | Main Entrance Lobby     | yes                               | Decorative Crown Molding | Chipping, Flaking           | Positive                | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | LOBBY   | Main Entrance Lobby     | yes                               | W3                       | None                        | N/A                     | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | LOBBY   | Main Entrance Lobby     | yes                               | W4                       | None                        | N/A                     | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | LOBBY   | Main Entrance Lobby     | yes                               | Decorative Crown Molding | Chipping, Flaking           | Positive                | None                               | 0             | No                        | no                            |                              |

| ULCS# | Element | Floor | Space # | On-Site Room Name           | Student/Teacher Occupied (yes/no) | Component                | Description of Damage                 | XRF (positive/negative) | Debris Present (describe location) | Quantity (sf) | Contents Need to be Moved | Plastering Needed (yes or no) | Comments/ Description/ Notes |
|-------|---------|-------|---------|-----------------------------|-----------------------------------|--------------------------|---------------------------------------|-------------------------|------------------------------------|---------------|---------------------------|-------------------------------|------------------------------|
| 5400  | 1       | 1     | LOBBY   | Main Entrance Lobby         | yes                               | Ceiling                  | Cracking, Flaking                     | Positive                | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | LOBBY   | Main Entrance Lobby         | yes                               | Decorative Crown Molding | Cracking, Chipping                    | Positive                | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | LOBBY   | Main Entrance Lobby         | yes                               | Floor                    | None                                  | N/A                     | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | 105     | Main Office                 | yes                               | W1                       | Chipping                              | Positive                | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | 105     | Main Office                 | yes                               | Baseboard                | Friction                              | Positive                | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | 105     | Main Office                 | yes                               | W2                       | Cracking                              | Positive                | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | 105     | Main Office                 | yes                               | Baseboard                | Friction                              | Positive                | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | 105     | Main Office                 | yes                               | W3                       | None                                  | N/A                     | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | 105     | Main Office                 | yes                               | Baseboard                | Friction                              | Positive                | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | 105     | Main Office                 | yes                               | W4                       | Cracking                              | Positive                | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | 105     | Main Office                 | yes                               | Baseboard                | Friction                              | Positive                | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | 105     | Main Office                 | yes                               | Ceiling                  | Flaking                               | Positive                | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | 105     | Main Office                 | yes                               | Floor                    | None                                  | N/A                     | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | 1051    | Main Office Server Closet   | yes                               | W1                       | Cracking                              | Positive                | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | 1051    | Main Office Server Closet   | yes                               | W2                       | Hole                                  | Positive                | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | 1051    | Main Office Server Closet   | yes                               | W3                       | Cracking, Holes                       | Positive                | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | 1051    | Main Office Server Closet   | yes                               | W4                       | Cracking                              | Positive                | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | 1051    | Main Office Server Closet   | yes                               | Ceiling                  | None                                  | N/A                     | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | 1051    | Main Office Server Closet   | yes                               | Floor                    | N/A                                   | N/A                     | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | 1052    | Main Office Coat Closet     | yes                               | W1                       | Cracking                              | Positive                | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | 1052    | Main Office Coat Closet     | yes                               | W2                       | Cracking                              | Positive                | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | 1052    | Main Office Coat Closet     | yes                               | W3                       | Cracking                              | Positive                | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | 1052    | Main Office Coat Closet     | yes                               | W4                       | Cracking                              | Positive                | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | 1052    | Main Office Coat Closet     | yes                               | Ceiling                  | Cracking                              | Positive                | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | 1052    | Main Office Coat Closet     | yes                               | Floor                    | N/A                                   | N/A                     | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | 105A    | Principal's Office          | yes                               | W1                       | Chipping                              | Positive                | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | 105A    | Principal's Office          | yes                               | W2                       | Chipping                              | Positive                | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | 105A    | Principal's Office          | yes                               | W3                       | None                                  | N/A                     | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | 105A    | Principal's Office          | yes                               | W4                       | None                                  | N/A                     | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | 105A    | Principal's Office          | yes                               | Ceiling                  | Flaking                               | Positive                | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | 105A    | Principal's Office          | yes                               | Floor                    | N/A                                   | N/A                     | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | 105B    | Principal's Office Restroom | yes                               | W1                       | None                                  | N/A                     | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | 105B    | Principal's Office Restroom | yes                               | W2                       | None                                  | N/A                     | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | 105B    | Principal's Office Restroom | yes                               | W3                       | None                                  | N/A                     | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | 105B    | Principal's Office Restroom | yes                               | W4                       | None                                  | N/A                     | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | 105B    | Principal's Office Restroom | yes                               | Ceiling                  | None                                  | N/A                     | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | 105B    | Principal's Office Restroom | yes                               | Floor                    | None                                  | N/A                     | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | 106     | Classroom 106               | yes                               | W1                       | Chipping, Holes                       | Positive                | None                               | 0             | No                        | yes                           |                              |
| 5400  | 1       | 1     | 106     | Classroom 106               | yes                               | W2                       | Efflorescence, Flaking                | Positive                | None                               | 0             | No                        | yes                           |                              |
| 5400  | 1       | 1     | 106     | Classroom 106               | yes                               | W3                       | Staple Holes, Efflorescence, Cracking | Positive                | None                               | 0             | Partially Inaccessible    | no                            |                              |
| 5400  | 1       | 1     | 106     | Classroom 106               | yes                               | Pipe                     | Flaking                               | Negative                | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | 106     | Classroom 106               | yes                               | W4                       | Staple Holes, Cracking                | Positive                | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | 106     | Classroom 106               | yes                               | Ceiling                  | Flaking/Efflorescence                 | Positive                | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | 106     | Classroom 106               | yes                               | Floor                    | None                                  | N/A                     | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | 106B    | Classroom 106 Restroom      | yes                               | W1                       | Cracking, Chipping                    | Positive                | None                               | 0             | No                        | yes                           |                              |
| 5400  | 1       | 1     | 106B    | Classroom 106 Restroom      | yes                               | W2                       | Moisture Damage                       | Negative                | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | 106B    | Classroom 106 Restroom      | yes                               | W3                       | Moisture Damage, Holes                | Positive                | None                               | 0             | No                        | yes                           |                              |
| 5400  | 1       | 1     | 106B    | Classroom 106 Restroom      | yes                               | W4                       | None                                  | N/A                     | None                               | 0             | No                        | no                            |                              |

| ULCS# | Element | Floor | Space # | On-Site Room Name                              | Student/Teacher Occupied (yes/no) | Component | Description of Damage              | XRF (positive/negative) | Debris Present (describe location) | Quantity (sf) | Contents Need to be Moved | Plastering Needed (yes or no) | Comments/ Description/ Notes |
|-------|---------|-------|---------|--|-----------------------------------|-----------|------------------------------------|-------------------------|------------------------------------|---------------|---------------------------|-------------------------------|------------------------------|
| 5400  | 1       | 1     | 106B    | Classroom 106 Restroom                         | yes                               | Ceiling   | Flaking                            | Positive                | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | 106B    | Classroom 106 Restroom                         | yes                               | Floor     | N/A                                | N/A                     | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | 106C    | Classroom 106 Closet                           | yes                               | W1        | None                               | N/A                     | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | 106C    | Classroom 106 Closet                           | yes                               | W2        | None                               | N/A                     | None                               | 0             | Prior to Repair           | no                            |                              |
| 5400  | 1       | 1     | 106C    | Classroom 106 Closet                           | yes                               | W3        | Flaking                            | Positive                | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | 106C    | Classroom 106 Closet                           | yes                               | W4        | None                               | N/A                     | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | 106C    | Classroom 106 Closet                           | yes                               | Ceiling   | N/A                                | N/A                     | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | 106C    | Classroom 106 Closet                           | yes                               | Floor     | None                               | N/A                     | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | 106D    | Hallway Closet adjacent to Girl's Restroom     | no                                | W1        | No Access                          | No Access               | No Access                          | No Access     | No Access                 | No Access                     |                              |
| 5400  | 1       | 1     | 106D    | Hallway Closet adjacent to Girl's Restroom     | no                                | W2        | No Access                          | No Access               | No Access                          | No Access     | No Access                 | No Access                     |                              |
| 5400  | 1       | 1     | 106D    | Hallway Closet adjacent to Girl's Restroom     | no                                | W3        | No Access                          | No Access               | No Access                          | No Access     | No Access                 | No Access                     |                              |
| 5400  | 1       | 1     | 106D    | Hallway Closet adjacent to Girl's Restroom     | no                                | W4        | No Access                          | No Access               | No Access                          | No Access     | No Access                 | No Access                     | No access to keys            |
| 5400  | 1       | 1     | 106D    | Hallway Closet adjacent to Girl's Restroom     | no                                | Ceiling   | No Access                          | No Access               | No Access                          | No Access     | No Access                 | No Access                     |                              |
| 5400  | 1       | 1     | 106D    | Hallway Closet adjacent to Girl's Restroom     | no                                | Floor     | No Access                          | No Access               | No Access                          | No Access     | No Access                 | No Access                     |                              |
| 5400  | 1       | 1     | 106A    | Girl's Restroom next to Classroom 106          | yes                               | W1        | None                               | N/A                     | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | 106A    | Girl's Restroom next to Classroom 106          | yes                               | W2        | None                               | N/A                     | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | 106A    | Girl's Restroom next to Classroom 106          | yes                               | W3        | None                               | N/A                     | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | 106A    | Girl's Restroom next to Classroom 106          | yes                               | Radiator  | Alligating                         | Negative                | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | 106A    | Girl's Restroom next to Classroom 106          | yes                               | W4        | None                               | N/A                     | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | 106A    | Girl's Restroom next to Classroom 106          | yes                               | Ceiling   | None                               | N/A                     | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | 106A    | Girl's Restroom next to Classroom 106          | yes                               | Floor     | None                               | N/A                     | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | H13     | Hallway from Nurse's Office to Girl's Restroom | yes                               | W1        | None                               | N/A                     | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | H13     | Hallway from Nurse's Office to Girl's Restroom | yes                               | W2        | None                               | N/A                     | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | H13     | Hallway from Nurse's Office to Girl's Restroom | yes                               | W3        | None                               | N/A                     | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | H13     | Hallway from Nurse's Office to Girl's Restroom | yes                               | W4        | None                               | N/A                     | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | H13     | Hallway from Nurse's Office to Girl's Restroom | yes                               | Ceiling   | Flaking                            | Positive                | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | H13     | Hallway from Nurse's Office to Girl's Restroom | yes                               | Floor     | None                               | N/A                     | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | 107A    | Custodial Closet adjacent Classroom 107        | no                                | W1        | Flaking, moisture                  | Positive                | None                               | 0             | No                        | yes                           |                              |
| 5400  | 1       | 1     | 107A    | Custodial Closet adjacent Classroom 107        | no                                | W2        | Flaking, moisture                  | Positive                | None                               | 0             | No                        | yes                           |                              |
| 5400  | 1       | 1     | 107A    | Custodial Closet adjacent Classroom 107        | no                                | W3        | Flaking, holes                     | Positive                | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | 107A    | Custodial Closet adjacent Classroom 107        | no                                | pipe      | Flaking                            | Positive                | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | 107A    | Custodial Closet adjacent Classroom 107        | no                                | W4        | Moisture Damage                    | Positive                | None                               | 0             | No                        | yes                           |                              |
| 5400  | 1       | 1     | 107A    | Custodial Closet adjacent Classroom 107        | no                                | Ceiling   | Flaking, moisture                  | Positive                | None                               | 0             | No                        | yes                           |                              |
| 5400  | 1       | 1     | 107A    | Custodial Closet adjacent Classroom 107        | no                                | Floor     | N/A                                | N/A                     | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | 107     | Classroom 107                                  | yes                               | W1        | Flaking, Chipping, Cracking        | Positive                | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | 107     | Classroom 107                                  | yes                               | W2        | Peeling, Staple Holes              | Negative                | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | 107     | Classroom 107                                  | yes                               | W3        | Flaking, Chipping                  | Positive                | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | 107     | Classroom 107                                  | yes                               | W4        | Cracking, Chipping, Flaking        | Positive                | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | 107     | Classroom 107                                  | yes                               | Ceiling   | None                               | N/A                     | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | 107     | Classroom 107                                  | yes                               | Floor     | N/A                                | N/A                     | None                               | 0             | No                        | no                            | Floor Tile                   |
| 5400  | 1       | 1     | 107B    | Classroom 107 Restroom                         | yes                               | W1        | Flaking                            | Positive                | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | 107B    | Classroom 107 Restroom                         | yes                               | W2        | Flaking                            | Positive                | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | 107B    | Classroom 107 Restroom                         | yes                               | W3        | None                               | N/A                     | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | 107B    | Classroom 107 Restroom                         | yes                               | W4        | Moisture Damage, Cracking, Flaking | Positive                | None                               | 0             | No                        | yes                           |                              |
| 5400  | 1       | 1     | 107B    | Classroom 107 Restroom                         | yes                               | Ceiling   | N/A                                | N/A                     | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | 107B    | Classroom 107 Restroom                         | yes                               | Floor     | N/A                                | N/A                     | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | 107C    | Classroom 107 Closet                           | yes                               | W1        | None                               | N/A                     | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | 107C    | Classroom 107 Closet                           | yes                               | W2        | Flaking, cracking                  | Positive                | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | 107C    | Classroom 107 Closet                           | yes                               | W3        | Cracking                           | Positive                | None                               | 0             | No                        | no                            |                              |

| ULCS# | Element | Floor | Space # | On-Site Room Name                            | Student/Teacher Occupied (yes/no) | Component        | Description of Damage     | XRF (positive/negative) | Debris Present (describe location) | Quantity (sf) | Contents Need to be Moved | Plastering Needed (yes or no) | Comments/ Description/ Notes |
|-------|---------|-------|---------|--|-----------------------------------|------------------|---------------------------|-------------------------|------------------------------------|---------------|---------------------------|-------------------------------|------------------------------|
| 5400  | 1       | 1     | 107C    | Classroom 107 Closet                         | yes                               | W4               | Flaking                   | Positive                | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | 107C    | Classroom 107 Closet                         | yes                               | Ceiling          | Flaking, Chipping         | Positive                | None                               | 0             | No                        | yes                           |                              |
| 5400  | 1       | 1     | 107C    | Classroom 107 Closet                         | yes                               | Floor            | None                      | N/A                     | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | 108B    | Counselor's Office/Faculty Lounge Vestibule  | yes                               | W1               | Flaking, Chipping         | Positive                | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | 108B    | Counselor's Office/Faculty Lounge Vestibule  | yes                               | W2               | None                      | N/A                     | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | 108B    | Counselor's Office/Faculty Lounge Vestibule  | yes                               | W3               | None                      | N/A                     | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | 108B    | Counselor's Office/Faculty Lounge Vestibule  | yes                               | W4               | Flaking                   | Positive                | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | 108B    | Counselor's Office/Faculty Lounge Vestibule  | yes                               | Ceiling          | Flaking                   | Positive                | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | 108B    | Counselor's Office/Faculty Lounge Vestibule  | yes                               | Floor            | None                      | N/A                     | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | 108     | Faculty Lounge                               | yes                               | W1               | Chipping                  | Negative                | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | 108     | Faculty Lounge                               | yes                               | W2               | Cracking                  | Positive                | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | 108     | Faculty Lounge                               | yes                               | W3               | Cracking                  | Positive                | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | 108     | Faculty Lounge                               | yes                               | W4               | Flaking, Cracking         | Positive                | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | 108     | Faculty Lounge                               | yes                               | Ceiling          | Flaking                   | Positive                | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | 108     | Faculty Lounge                               | yes                               | Floor            | None                      | N/A                     | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | 108C    | Faculty Lounge Closet                        | yes                               | W1               | No Access                 | No Access               | No Access                          | No Access     | No Access                 | No Access                     |                              |
| 5400  | 1       | 1     | 108C    | Faculty Lounge Closet                        | yes                               | W2               | No Access                 | No Access               | No Access                          | No Access     | No Access                 | No Access                     |                              |
| 5400  | 1       | 1     | 108C    | Faculty Lounge Closet                        | yes                               | W3               | No Access                 | No Access               | No Access                          | No Access     | No Access                 | No Access                     |                              |
| 5400  | 1       | 1     | 108C    | Faculty Lounge Closet                        | yes                               | W4               | No Access                 | No Access               | No Access                          | No Access     | No Access                 | No Access                     | No access to keys            |
| 5400  | 1       | 1     | 108C    | Faculty Lounge Closet                        | yes                               | Ceiling          | No Access                 | No Access               | No Access                          | No Access     | No Access                 | No Access                     |                              |
| 5400  | 1       | 1     | 108C    | Faculty Lounge Closet                        | yes                               | Floor            | No Access                 | No Access               | No Access                          | No Access     | No Access                 | No Access                     |                              |
| 5400  | 1       | 1     | 108A    | Counselor's Office 108A                      | yes                               | W1               | No Access                 | No Access               | No Access                          | No Access     | No Access                 | No Access                     |                              |
| 5400  | 1       | 1     | 108A    | Counselor's Office 108A                      | yes                               | W2               | No Access                 | No Access               | No Access                          | No Access     | No Access                 | No Access                     |                              |
| 5400  | 1       | 1     | 108A    | Counselor's Office 108A                      | yes                               | W3               | No Access                 | No Access               | No Access                          | No Access     | No Access                 | No Access                     |                              |
| 5400  | 1       | 1     | 108A    | Counselor's Office 108A                      | yes                               | W4               | No Access                 | No Access               | No Access                          | No Access     | No Access                 | No Access                     | No access to keys            |
| 5400  | 1       | 1     | 108A    | Counselor's Office 108A                      | yes                               | Ceiling          | No Access                 | No Access               | No Access                          | No Access     | No Access                 | No Access                     |                              |
| 5400  | 1       | 1     | 108A    | Counselor's Office 108A                      | yes                               | Floor            | No Access                 | No Access               | No Access                          | No Access     | No Access                 | No Access                     |                              |
| 5400  | 1       | 1     | H12     | Hallway from Classroom 107 to Faculty Lounge | yes                               | W1               | None                      | N/A                     | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | H12     | Hallway from Classroom 107 to Faculty Lounge | yes                               | W2               | None                      | N/A                     | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | H12     | Hallway from Classroom 107 to Faculty Lounge | yes                               | Pipe             | Chipping, Flaking         | Positive                | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | H12     | Hallway from Classroom 107 to Faculty Lounge | yes                               | W3               | None                      | N/A                     | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | H12     | Hallway from Classroom 107 to Faculty Lounge | yes                               | W4               | None                      | N/A                     | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | H12     | Hallway from Classroom 107 to Faculty Lounge | yes                               | Electrical Panel | Chipping                  | Positive                | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | H12     | Hallway from Classroom 107 to Faculty Lounge | yes                               | Ceiling          | Flaking                   | Positive                | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | H12     | Hallway from Classroom 107 to Faculty Lounge | yes                               | Floor            | None                      | N/A                     | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | S11     | Stairwell across from Main Office            | yes                               | W1               | None                      | N/A                     | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | S11     | Stairwell across from Main Office            | yes                               | Door             | Friction                  | Negative                | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | S11     | Stairwell across from Main Office            | yes                               | Door Frame       | Friction                  | Negative                | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | S11     | Stairwell across from Main Office            | yes                               | W2               | None                      | N/A                     | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | S11     | Stairwell across from Main Office            | yes                               | W3               | Moisture Damage, CRACKING | Positive                | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | S11     | Stairwell across from Main Office            | yes                               | Door             | Friction                  | Negative                | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | S11     | Stairwell across from Main Office            | yes                               | Door Frame       | Friction                  | Negative                | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | S11     | Stairwell across from Main Office            | yes                               | W4               | None                      | N/A                     | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | S11     | Stairwell across from Main Office            | yes                               | Ceiling          | None                      | N/A                     | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | S11     | Stairwell across from Main Office            | yes                               | Floor            | N/A                       | N/A                     | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | S11     | Stairwell across from Main Office            | yes                               | Tread            | Friction                  | Negative                | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | S11     | Stairwell across from Main Office            | yes                               | Riser            | Friction                  | Negative                | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | S11     | Stairwell across from Main Office            | yes                               | Ballest          | Friction                  | Positive                | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | S11     | Stairwell across from Main Office            | yes                               | Newel Posts      | Friction                  | Positive                | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | S11     | Stairwell across from Main Office            | yes                               | stringer         | Friction                  | Positive                | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | 109     | Classroom 109 - Kindergarten                 | yes                               | W1               | Chipping, Flaking         | Positive                | None                               | 0             | No                        | no                            |                              |

| ULCS# | Element | Floor | Space # | On-Site Room Name                          | Student/Teacher Occupied (yes/no) | Component   | Description of Damage          | XRF (positive/negative) | Debris Present (describe location) | Quantity (sf) | Contents Need to be Moved | Plastering Needed (yes or no) | Comments/ Description/ Notes |
|-------|---------|-------|---------|--|-----------------------------------|-------------|--------------------------------|-------------------------|------------------------------------|---------------|---------------------------|-------------------------------|------------------------------|
| 5400  | 1       | 1     | 109     | Classroom 109 - Kindergarten               | yes                               | W2          | Flaking                        | Positive                | None                               | 0             | No                        | no                            | Behind Radiator              |
| 5400  | 1       | 1     | 109     | Classroom 109 - Kindergarten               | yes                               | W3          | Moisture Damage, Efflorescence | Positive                | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | 109     | Classroom 109 - Kindergarten               | yes                               | Door        | Friction/Moisture Damage       | Negative                | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | 109     | Classroom 109 - Kindergarten               | yes                               | Door frame  | Friction/Moisture Damage       | Negative                | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | 109     | Classroom 109 - Kindergarten               | yes                               | W4          | None                           | N/A                     | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | 109     | Classroom 109 - Kindergarten               | yes                               | Ceiling     | None                           | N/A                     | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | 109     | Classroom 109 - Kindergarten               | yes                               | Floor       | None                           | N/A                     | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | 109A    | Classroom 109 - Kindergarten Restroom      | yes                               | W1          | Chipping/Cracking              | Positive                | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | 109A    | Classroom 109 - Kindergarten Restroom      | yes                               | W2          | Moisture Damage                | Positive                | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | 109A    | Classroom 109 - Kindergarten Restroom      | yes                               | W3          | None                           | N/A                     | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | 109A    | Classroom 109 - Kindergarten Restroom      | yes                               | W4          | None                           | N/A                     | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | 109A    | Classroom 109 - Kindergarten Restroom      | yes                               | Ceiling     | None                           | N/A                     | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | 109A    | Classroom 109 - Kindergarten Restroom      | yes                               | Floor       | None                           | N/A                     | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | 109B    | Classroom 109 Closet adjacent to Restroom  | yes                               | W1          | None                           | N/A                     | None                               | 0             | Partially Inaccessible    | no                            |                              |
| 5400  | 1       | 1     | 109B    | Classroom 109 Closet adjacent to Restroom  | yes                               | W2          | Cracking                       | Positive                | None                               | 0             | Partially Inaccessible    | no                            |                              |
| 5400  | 1       | 1     | 109B    | Classroom 109 Closet adjacent to Restroom  | yes                               | W3          | Hole                           | Positive                | None                               | 0             | Partially Inaccessible    | no                            |                              |
| 5400  | 1       | 1     | 109B    | Classroom 109 Closet adjacent to Restroom  | yes                               | W4          | None                           | N/A                     | None                               | 0             | Partially Inaccessible    | no                            |                              |
| 5400  | 1       | 1     | 109B    | Classroom 109 Closet adjacent to Restroom  | yes                               | Ceiling     | Flaking                        | Positive                | None                               | 0             | Partially Inaccessible    | no                            |                              |
| 5400  | 1       | 1     | 109B    | Classroom 109 Closet adjacent to Restroom  | yes                               | Floor       | None                           | N/A                     | None                               | 0             | Partially Inaccessible    | no                            |                              |
| 5400  | 1       | 1     | 109C    | Classroom 109 Closet on Classroom 104 side | yes                               | W1          | None                           | N/A                     | None                               | 0             | Partially Inaccessible    | no                            |                              |
| 5400  | 1       | 1     | 109C    | Classroom 109 Closet on Classroom 104 side | yes                               | W2          | Flaking                        | Positive                | None                               | 0             | Partially Inaccessible    | no                            |                              |
| 5400  | 1       | 1     | 109C    | Classroom 109 Closet on Classroom 104 side | yes                               | W3          | None                           | N/A                     | None                               | 0             | Partially Inaccessible    | no                            |                              |
| 5400  | 1       | 1     | 109C    | Classroom 109 Closet on Classroom 104 side | yes                               | W4          | None                           | N/A                     | None                               | 0             | Partially Inaccessible    | no                            |                              |
| 5400  | 1       | 1     | 109C    | Classroom 109 Closet on Classroom 104 side | yes                               | Ceiling     | None                           | N/A                     | None                               | 0             | Partially Inaccessible    | no                            |                              |
| 5400  | 1       | 1     | 109C    | Classroom 109 Closet on Classroom 104 side | yes                               | Floor       | None                           | N/A                     | None                               | 0             | Partially Inaccessible    | no                            |                              |
| 5400  | 1       | 1     | S12     | Stairwell across from Classroom 104        | yes                               | W1          | None                           | N/A                     | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | S12     | Stairwell across from Classroom 104        | yes                               | Door        | Friction                       | Negative                | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | S12     | Stairwell across from Classroom 104        | yes                               | Door Frame  | Friction                       | Negative                | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | S12     | Stairwell across from Classroom 104        | yes                               | W2          | None                           | N/A                     | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | S12     | Stairwell across from Classroom 104        | yes                               | W3          | Flaking                        | Positive                | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | S12     | Stairwell across from Classroom 104        | yes                               | Door        | Friction                       | Negative                | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | S12     | Stairwell across from Classroom 104        | yes                               | Door Frame  | Friction                       | Negative                | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | S12     | Stairwell across from Classroom 104        | yes                               | W4          | None                           | N/A                     | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | S12     | Stairwell across from Classroom 104        | yes                               | Ceiling     | None                           | N/A                     | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | S12     | Stairwell across from Classroom 104        | yes                               | Floor       | N/A                            | N/A                     | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | S12     | Stairwell across from Classroom 104        | yes                               | Tread       | Friction                       | Negative                | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | S12     | Stairwell across from Classroom 104        | yes                               | Riser       | Friction                       | Negative                | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | S12     | Stairwell across from Classroom 104        | yes                               | Ballest     | Friction                       | Positive                | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | S12     | Stairwell across from Classroom 104        | yes                               | Newel Posts | Friction                       | Positive                | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | S12     | Stairwell across from Classroom 104        | yes                               | stringer    | Friction                       | Positive                | None                               | 0             | No                        | no                            |                              |

| ULCS# | Element | Floor | Space # | On-Site Room Name                   | Student/Teacher Occupied (yes/no) | Component   | Description of Damage       | XRF (positive/negative) | Debris Present (describe location) | Quantity (sf) | Contents Need to be Moved | Plastering Needed (yes or no) | Comments/ Description/ Notes                        |
|-------|---------|-------|---------|-------------------------------------|-----------------------------------|-------------|-----------------------------|-------------------------|------------------------------------|---------------|---------------------------|-------------------------------|---|
| 5400  | 1       | 2     | 201     | Classroom 201                       | yes                               | W1          | Chipping/Cracking           | Positive                | N/A                                | N/A           | N/A                       | N/A                           |   |
| 5400  | 1       | 2     | 201     | Classroom 201                       | yes                               | W2          | N/A                         | N/A                     | N/A                                | N/A           | N/A                       | N/A                           | Partition Wall                                      |
| 5400  | 1       | 2     | 201     | Classroom 201                       | yes                               | W3          | Flaking                     | Positive                | N/A                                | N/A           | N/A                       | N/A                           |   |
| 5400  | 1       | 2     | 201     | Classroom 201                       | yes                               | Radiator    | Alligating                  | Negative                | N/A                                | N/A           | N/A                       | N/A                           |   |
| 5400  | 1       | 2     | 201     | Classroom 201                       | yes                               | W4          | Cracking                    | Positive                | N/A                                | N/A           | N/A                       | N/A                           |   |
| 5400  | 1       | 2     | 201     | Classroom 201                       | yes                               | Ceiling     | Moisture Damage/Flaking     | Positive                | None                               | 0             | No                        | no                            |   |
| 5400  | 1       | 2     | 201     | Classroom 201                       | yes                               | Floor       | None                        | N/A                     | N/A                                | N/A           | N/A                       | N/A                           |   |
| 5400  | 1       | 2     | 201A    | Classroom 201 Closet                | yes                               | W1          | Flaking/Cracking            | Positive                | N/A                                | N/A           | N/A                       | N/A                           | Radiator is on, too hot to test.                    |
| 5400  | 1       | 2     | 201A    | Classroom 201 Closet                | yes                               | W2          | Efflorescence               | Positive                | N/A                                | N/A           | N/A                       | N/A                           |   |
| 5400  | 1       | 2     | 201A    | Classroom 201 Closet                | yes                               | Radiator    | Flaking/Cracking            | Positive                | N/A                                | N/A           | N/A                       | N/A                           |   |
| 5400  | 1       | 2     | 201A    | Classroom 201 Closet                | yes                               | W3          | Flaking/Cracking            | Positive                | N/A                                | N/A           | N/A                       | N/A                           |   |
| 5400  | 1       | 2     | 201A    | Classroom 201 Closet                | yes                               | Pipe        | Chipping                    | Positive                | N/A                                | N/A           | N/A                       | N/A                           |   |
| 5400  | 1       | 2     | 201A    | Classroom 201 Closet                | yes                               | W4          | None                        | N/A                     | N/A                                | N/A           | N/A                       | N/A                           |   |
| 5400  | 1       | 2     | 201A    | Classroom 201 Closet                | yes                               | Ceiling     | Moisture Damage             | Positive                | None                               | 0             | No                        | no                            |   |
| 5400  | 1       | 2     | 201A    | Classroom 201 Closet                | yes                               | Floor       | None                        | N/A                     | N/A                                | N/A           | N/A                       | N/A                           |   |
| 5400  | 1       | 2     | 202     | Classroom 202                       | yes                               | W1          | Chipping, Cracking          | Positive                | N/A                                | N/A           | N/A                       | N/A                           |   |
| 5400  | 1       | 2     | 202     | Classroom 202                       | yes                               | W2          | Holes, Chipping             | Positive                | N/A                                | N/A           | N/A                       | N/A                           |   |
| 5400  | 1       | 2     | 202     | Classroom 202                       | yes                               | W3          | Moisture, Chipping, Flaking | Positive                | N/A                                | N/A           | N/A                       | N/A                           |   |
| 5400  | 1       | 2     | 202     | Classroom 202                       | yes                               | Radiator    | Chipping                    |                         | N/A                                | N/A           | N/A                       | N/A                           | unable to test. radiator is on and too hot to test. |
| 5400  | 1       | 2     | 202     | Classroom 202                       | yes                               | Pipe        | Flaking                     | Positive                | N/A                                | N/A           | N/A                       | N/A                           |   |
| 5400  | 1       | 2     | 202     | Classroom 202                       | yes                               | W4          | None                        | N/A                     | N/A                                | N/A           | N/A                       | N/A                           |   |
| 5400  | 1       | 2     | 202     | Classroom 202                       | yes                               | Ceiling     | Flaking                     | Positive                | None                               | 0             | No                        | no                            |   |
| 5400  | 1       | 2     | 202     | Classroom 202                       | yes                               | Floor       | None                        | N/A                     | N/A                                | N/A           | N/A                       | N/A                           |   |
| 5400  | 1       | 2     | 202B    | Classroom 202 Closet                | yes                               | W1          | Flaking                     | Positive                | N/A                                | N/A           | N/A                       | N/A                           |   |
| 5400  | 1       | 2     | 202B    | Classroom 202 Closet                | yes                               | W2          | None                        | N/A                     | N/A                                | N/A           | Partially Inaccessible    | N/A                           | Storage   |
| 5400  | 1       | 2     | 202B    | Classroom 202 Closet                | yes                               | W3          | None                        | N/A                     | None                               | 0             | No                        | no                            |   |
| 5400  | 1       | 2     | 202B    | Classroom 202 Closet                | yes                               | W4          | None                        | N/A                     | N/A                                | N/A           | Partially Inaccessible    | N/A                           | Storage   |
| 5400  | 1       | 2     | 202B    | Classroom 202 Closet                | yes                               | Ceiling     | Flaking                     | Positive                | None                               | 0             | No                        | no                            |   |
| 5400  | 1       | 2     | 202B    | Classroom 202 Closet                | yes                               | Floor       | None                        | N/A                     | N/A                                | N/A           | N/A                       | N/A                           |   |
| 5400  | 1       | 2     | H23     | Hallway from Classroom 201 to 202   | yes                               | W1          | None                        | N/A                     | N/A                                | N/A           | N/A                       | N/A                           |   |
| 5400  | 1       | 2     | H23     | Hallway from Classroom 201 to 202   | yes                               | W2          | None                        | N/A                     | N/A                                | N/A           | N/A                       | N/A                           |   |
| 5400  | 1       | 2     | H23     | Hallway from Classroom 201 to 202   | yes                               | W3          | Flaking                     | Positive                | N/A                                | N/A           | N/A                       | N/A                           |   |
| 5400  | 1       | 2     | H23     | Hallway from Classroom 201 to 202   | yes                               | W4          | Flaking                     | Positive                | N/A                                | N/A           | N/A                       | N/A                           |   |
| 5400  | 1       | 2     | H23     | Hallway from Classroom 201 to 202   | yes                               | Pipe Casing | Chipping                    | Positive                | N/A                                | N/A           | N/A                       | N/A                           |   |
| 5400  | 1       | 2     | H23     | Hallway from Classroom 201 to 202   | yes                               | Ceiling     | Moisture Damage             | Positive                | None                               | 0             | No                        | no                            |   |
| 5400  | 1       | 2     | H23     | Hallway from Classroom 201 to 202   | yes                               | Floor       | None                        | N/A                     | N/A                                | N/A           | N/A                       | N/A                           |   |
| 5400  | 1       | 2     | H23A    | Hall Closet adjacent Boy's Restroom | no                                | W1          | No Access                   | No Access               | No Access                          | No Access     | No Access                 | No Access                     | Custodial has no key.                               |
| 5400  | 1       | 2     | H23A    | Hall Closet adjacent Boy's Restroom | no                                | W2          | No Access                   | No Access               | No Access                          | No Access     | No Access                 | No Access                     |   |
| 5400  | 1       | 2     | H23A    | Hall Closet adjacent Boy's Restroom | no                                | W3          | No Access                   | No Access               | No Access                          | No Access     | No Access                 | No Access                     |   |
| 5400  | 1       | 2     | H23A    | Hall Closet adjacent Boy's Restroom | no                                | W4          | No Access                   | No Access               | No Access                          | No Access     | No Access                 | No Access                     |   |
| 5400  | 1       | 2     | H23A    | Hall Closet adjacent Boy's Restroom | no                                | Ceiling     | No Access                   | No Access               | No Access                          | No Access     | No Access                 | No Access                     |   |
| 5400  | 1       | 2     | H23A    | Hall Closet adjacent Boy's Restroom | no                                | Floor       | No Access                   | No Access               | No Access                          | No Access     | No Access                 | No Access                     |   |
| 5400  | 1       | 2     | 202A    | Boy's Restroom                      | yes                               | W1          | None                        | N/A                     | N/A                                | N/A           | N/A                       | N/A                           |   |
| 5400  | 1       | 2     | 202A    | Boy's Restroom                      | yes                               | W2          | Alligating                  | Positive                | N/A                                | N/A           | N/A                       | N/A                           | Behind pipe, adj. to W1.                            |
| 5400  | 1       | 2     | 202A    | Boy's Restroom                      | yes                               | pipe        | Chipping                    | Negative                | N/A                                | N/A           | N/A                       | N/A                           |   |
| 5400  | 1       | 2     | 202A    | Boy's Restroom                      | yes                               | radiator    | Alligating                  | Negative                | N/A                                | N/A           | N/A                       | N/A                           |   |
| 5400  | 1       | 2     | 202A    | Boy's Restroom                      | yes                               | W3          | Chipping                    | Positive                | N/A                                | N/A           | N/A                       | N/A                           |   |
| 5400  | 1       | 2     | 202A    | Boy's Restroom                      | yes                               | pipe        | Chipping                    | Negative                | N/A                                | N/A           | N/A                       | N/A                           |   |



| ULCS# | Element | Floor | Space # | On-Site Room Name                   | Student/Teacher Occupied (yes/no) | Component   | Description of Damage       | XRF (positive/negative) | Debris Present (describe location) | Quantity (sf) | Contents Need to be Moved | Plastering Needed (yes or no) | Comments/ Description/ Notes          |
|-------|---------|-------|---------|-------------------------------------|-----------------------------------|-------------|-----------------------------|-------------------------|------------------------------------|---------------|---------------------------|-------------------------------|---------------------------------------|
| 5400  | 1       | 2     | 202A    | Boy's Restroom                      | yes                               | W3          | Chipping                    | Negative                | N/A                                | N/A           | N/A                       | N/A                           |                                       |
| 5400  | 1       | 2     | 202A    | Boy's Restroom                      | yes                               | W4          | None                        | N/A                     | N/A                                | N/A           | N/A                       | N/A                           |                                       |
| 5400  | 1       | 2     | 202A    | Boy's Restroom                      | yes                               | Ceiling     | N/A                         | N/A                     | None                               | 0             | No                        | no                            |                                       |
| 5400  | 1       | 2     | 202A    | Boy's Restroom                      | yes                               | Floor       | Chipping                    | Negative                | N/A                                | N/A           | N/A                       | N/A                           |                                       |
| 5400  | 1       | 2     | 203     | Classroom 203                       | yes                               | W1          | Flaking/Cracking            | Positive                | N/A                                | N/A           | N/A                       | N/A                           |                                       |
| 5400  | 1       | 2     | 203     | Classroom 203                       | yes                               | W2          | Holes/Chipping              | Positive                | N/A                                | N/A           | N/A                       | N/A                           |                                       |
| 5400  | 1       | 2     | 203     | Classroom 203                       | yes                               | W3          | Cracking, Chipping, Flaking | Positive                | N/A                                | N/A           | N/A                       | yes                           | Plastering Required behind radiators. |
| 5400  | 1       | 2     | 203     | Classroom 203                       | yes                               | radiator    | Alligatoring                | Negative                | N/A                                | N/A           | N/A                       | N/A                           |                                       |
| 5400  | 1       | 2     | 203     | Classroom 203                       | yes                               | W4          | Efflorescence, Flaking      | Positive                | N/A                                | N/A           | N/A                       | N/A                           |                                       |
| 5400  | 1       | 2     | 203     | Classroom 203                       | yes                               | Ceiling     | Moisture Damage/Flaking     | Positive                | None                               | 0             | No                        | no                            |                                       |
| 5400  | 1       | 2     | 203     | Classroom 203                       | yes                               | Floor       | None                        | N/A                     | N/A                                | N/A           | N/A                       | N/A                           |                                       |
| 5400  | 1       | 2     | 203C    | Classroom 203 Coat Closet           | yes                               | W1          | Chipping                    | Positive                | N/A                                | N/A           | N/A                       | N/A                           |                                       |
| 5400  | 1       | 2     | 203C    | Classroom 203 Coat Closet           | yes                               | W2          | None                        | N/A                     | N/A                                | N/A           | N/A                       | N/A                           |                                       |
| 5400  | 1       | 2     | 203C    | Classroom 203 Coat Closet           | yes                               | Pipe Casing | Chipping                    | Positive                | N/A                                | N/A           | N/A                       | N/A                           |                                       |
| 5400  | 1       | 2     | 203C    | Classroom 203 Coat Closet           | yes                               | W3          | Chipping, Cracking          | Positive                | N/A                                | N/A           | N/A                       | yes                           | Plastering Required behind radiator   |
| 5400  | 1       | 2     | 203C    | Classroom 203 Coat Closet           | yes                               | W4          | Cracking                    | Positive                | N/A                                | N/A           | N/A                       | N/A                           |                                       |
| 5400  | 1       | 2     | 203C    | Classroom 203 Coat Closet           | yes                               | Ceiling     | Moisture Damage/Flaking     | Positive                | None                               | 0             | No                        | no                            |                                       |
| 5400  | 1       | 2     | 203C    | Classroom 203 Coat Closet           | yes                               | Floor       | None                        | N/A                     | N/A                                | N/A           | N/A                       | N/A                           |                                       |
| 5400  | 1       | 2     | 203D    | Classroom 203 Storage Closet        | yes                               | W1          | Cracking                    | Positive                | N/A                                | N/A           | N/A                       | N/A                           |                                       |
| 5400  | 1       | 2     | 203D    | Classroom 203 Storage Closet        | yes                               | W2          | Cracking                    | Positive                | N/A                                | N/A           | N/A                       | N/A                           |                                       |
| 5400  | 1       | 2     | 203D    | Classroom 203 Storage Closet        | yes                               | W3          | Cracking                    | Positive                | N/A                                | N/A           | N/A                       | N/A                           |                                       |
| 5400  | 1       | 2     | 203D    | Classroom 203 Storage Closet        | yes                               | W4          | Cracking                    | Positive                | N/A                                | N/A           | N/A                       | N/A                           |                                       |
| 5400  | 1       | 2     | 203D    | Classroom 203 Storage Closet        | yes                               | Ceiling     | Cracking                    | Positive                | N/A                                | N/A           | N/A                       | N/A                           |                                       |
| 5400  | 1       | 2     | 203D    | Classroom 203 Storage Closet        | yes                               | Floor       | None                        | N/A                     | N/A                                | N/A           | N/A                       | N/A                           |                                       |
| 5400  | 1       | 2     | 203A    | Counselor's Office                  | yes                               | W1          | Chipping                    | Positive                | N/A                                | N/A           | N/A                       | N/A                           |                                       |
| 5400  | 1       | 2     | 203A    | Counselor's Office                  | yes                               | W2          | Nail Holes                  | Positive                | N/A                                | N/A           | N/A                       | N/A                           |                                       |
| 5400  | 1       | 2     | 203A    | Counselor's Office                  | yes                               | W3          | Moisture Damage             | Positive                | N/A                                | N/A           | N/A                       | N/A                           | Behind Radiator                       |
| 5400  | 1       | 1     | S12     | Stairwell across from Classroom 104 | yes                               | radiator    | flaking                     | Positive                | N/A                                | N/A           | N/A                       | N/A                           | Radiator is too hot, cannot test.     |
| 5400  | 1       | 2     | 203A    | Counselor's Office                  | yes                               | W4          | Nail Holes/Cracking         | Positive                | N/A                                | N/A           | N/A                       | N/A                           |                                       |
| 5400  | 1       | 2     | 203A    | Counselor's Office                  | yes                               | Ceiling     | N/A                         | N/A                     | None                               | 0             | No                        | no                            |                                       |
| 5400  | 1       | 2     | 203A    | Counselor's Office                  | yes                               | Floor       | None                        | N/A                     | N/A                                | N/A           | N/A                       | N/A                           | Floor tile                            |
| 5400  | 1       | 2     | 203B    | Counselor's Office Restroom         | yes                               | W1          | Holes                       | Positive                | N/A                                | N/A           | N/A                       | N/A                           |                                       |
| 5400  | 1       | 2     | 203B    | Counselor's Office Restroom         | yes                               | W2          | Flaking                     | Positive                | N/A                                | N/A           | N/A                       | N/A                           |                                       |
| 5400  | 1       | 2     | 203B    | Counselor's Office Restroom         | yes                               | W3          | Moisture Damage/Flaking     | Positive                | N/A                                | N/A           | N/A                       | N/A                           |                                       |
| 5400  | 1       | 2     | 203B    | Counselor's Office Restroom         | yes                               | W4          | Flaking                     | Positive                | N/A                                | N/A           | N/A                       | N/A                           |                                       |
| 5400  | 1       | 2     | 203B    | Counselor's Office Restroom         | yes                               | Ceiling     | Moisture Damage             | Positive                | N/A                                | N/A           | N/A                       | N/A                           |                                       |
| 5400  | 1       | 2     | 203B    | Counselor's Office Restroom         | yes                               | Floor       | Friction                    | Negative                | N/A                                | N/A           | N/A                       | N/A                           |                                       |
| 5400  | 1       | 2     | 204     | Classroom 204                       | yes                               | W1          | Chipping, Cracking          | Positive                | N/A                                | N/A           | N/A                       | N/A                           |                                       |
| 5400  | 1       | 2     | 204     | Classroom 204                       | yes                               | W2          | None                        | N/A                     | N/A                                | N/A           | N/A                       | N/A                           | Partition Wall                        |
| 5400  | 1       | 2     | 204     | Classroom 204                       | yes                               | W3          | Flaking                     | Positive                | N/A                                | N/A           | N/A                       | N/A                           |                                       |
| 5400  | 1       | 2     | 204     | Classroom 204                       | yes                               | W4          | Chipping, Cracking, Holes   | Positive                | N/A                                | N/A           | N/A                       | N/A                           |                                       |
| 5400  | 1       | 2     | 204     | Classroom 204                       | yes                               | Ceiling     | Flaking, Holes              | Positive                | Floor                              | 8             | N/A                       | yes                           | Paint chips                           |
| 5400  | 1       | 2     | 204     | Classroom 204                       | yes                               | Floor       | None                        | N/A                     | N/A                                | N/A           | N/A                       | N/A                           |                                       |
| 5400  | 1       | 2     | 204A    | Classroom 204 Closet                | yes                               | W1          | None                        | N/A                     | N/A                                | N/A           | N/A                       | N/A                           |                                       |
| 5400  | 1       | 2     | 204A    | Classroom 204 Closet                | yes                               | W2          | None                        | N/A                     | N/A                                | N/A           | N/A                       | N/A                           |                                       |
| 5400  | 1       | 2     | 204A    | Classroom 204 Closet                | yes                               | W3          | None                        | N/A                     | N/A                                | N/A           | N/A                       | N/A                           |                                       |
| 5400  | 1       | 2     | 204A    | Classroom 204 Closet                | yes                               | W4          | hOLE                        | Positive                | N/A                                | N/A           | N/A                       | yes                           |                                       |
| 5400  | 1       | 2     | 204A    | Classroom 204 Closet                | yes                               | Ceiling     | N/A                         | N/A                     | None                               | 0             | No                        | no                            |                                       |

| ULCS# | Element | Floor | Space # | On-Site Room Name                              | Student/Teacher Occupied (yes/no) | Component  | Description of Damage            | XRF (positive/negative) | Debris Present (describe location) | Quantity (sf) | Contents Need to be Moved | Plastering Needed (yes or no) | Comments/ Description/ Notes |
|-------|---------|-------|---------|--|-----------------------------------|------------|----------------------------------|-------------------------|------------------------------------|---------------|---------------------------|-------------------------------|------------------------------|
| 5400  | 1       | 2     | 204A    | Classroom 204 Closet                           | yes                               | Floor      | None                             | N/A                     | N/A                                | N/A           | N/A                       | N/A                           |                              |
| 5400  | 1       | 2     | 205     | Classroom 205                                  | yes                               | W1         | Chipping                         | Positive                | N/A                                | N/A           | N/A                       | N/A                           |                              |
| 5400  | 1       | 2     | 205     | Classroom 205                                  | yes                               | W2         | Chipping                         | Positive                | N/A                                | N/A           | N/A                       | N/A                           | Damage in Vestibule Area     |
| 5400  | 1       | 2     | 205     | Classroom 205                                  | yes                               | W3         | Flaking, Chipping                | Positive                | N/A                                | N/A           | N/A                       | N/A                           |                              |
| 5400  | 1       | 2     | 205     | Classroom 205                                  | yes                               | W4         | Chipping, Cracking               | Positive                | N/A                                | N/A           | N/A                       | N/A                           | Damage in Vestibule Area     |
| 5400  | 1       | 2     | 205     | Classroom 205                                  | yes                               | Ceiling    | Moisture Damage/Flaking          | Positive                | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 2     | 205     | Classroom 205                                  | yes                               | Floor      | None                             | N/A                     | N/A                                | N/A           | N/A                       | N/A                           |                              |
| 5400  | 1       | 2     | 205A    | Classroom 205 Closet                           | yes                               | W1         | Cracking                         | Positive                | N/A                                | N/A           | N/A                       | N/A                           |                              |
| 5400  | 1       | 2     | 205A    | Classroom 205 Closet                           | yes                               | W2         | Cracking                         | Positive                | N/A                                | N/A           | N/A                       | N/A                           |                              |
| 5400  | 1       | 2     | 205A    | Classroom 205 Closet                           | yes                               | W3         | Cracking                         | Positive                | N/A                                | N/A           | N/A                       | N/A                           |                              |
| 5400  | 1       | 2     | 205A    | Classroom 205 Closet                           | yes                               | W4         | Cracking                         | Positive                | N/A                                | N/A           | N/A                       | N/A                           |                              |
| 5400  | 1       | 2     | 205A    | Classroom 205 Closet                           | yes                               | Ceiling    | Cracking                         | Positive                | N/A                                | N/A           | N/A                       | N/A                           |                              |
| 5400  | 1       | 2     | 205A    | Classroom 205 Closet                           | yes                               | Floor      | N/A                              | N/A                     | None                               | N/A           | N/A                       | N/A                           |                              |
| 5400  | 1       | 2     | 206     | Classroom 206                                  | yes                               | W1         | Cracking, Chipping, Pin Holes    | Positive                | N/A                                | N/A           | N/A                       | N/A                           |                              |
| 5400  | 1       | 2     | 206     | Classroom 206                                  | yes                               | W2         | Efflorescence, Cracking          | Positive                | None                               | 0             | Prior to Repair           | yes                           | Corner of W2 & w3            |
| 5400  | 1       | 2     | 206     | Classroom 206                                  | yes                               | W3         | Efflorescence, Flaking, Cracking | Positive                | N/A                                | N/A           | N/A                       | N/A                           |                              |
| 5400  | 1       | 2     | 206     | Classroom 206                                  | yes                               | Radiator   | Flaking                          | Positive                | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 2     | 206     | Classroom 206                                  | yes                               | W4         | None                             | N/A                     | N/A                                | N/A           | N/A                       | N/A                           | Partition Wall               |
| 5400  | 1       | 2     | 206     | Classroom 206                                  | yes                               | Ceiling    | Moisture Damage/Flaking          | Positive                | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 2     | 206     | Classroom 206                                  | yes                               | Floor      | None                             | N/A                     | N/A                                | N/A           | N/A                       | N/A                           |                              |
| 5400  | 1       | 2     | 206C    | Classroom 206 Closet                           | yes                               | W1         | Efflorescence                    | Positive                | N/A                                | N/A           | N/A                       | N/A                           |                              |
| 5400  | 1       | 2     | 206C    | Classroom 206 Closet                           | yes                               | W2         | None                             | N/A                     | N/A                                | N/A           | N/A                       | N/A                           |                              |
| 5400  | 1       | 2     | 206C    | Classroom 206 Closet                           | yes                               | W3         | None                             | N/A                     | N/A                                | N/A           | N/A                       | N/A                           |                              |
| 5400  | 1       | 2     | 206C    | Classroom 206 Closet                           | yes                               | W4         | Efflorescence, Flaking           | Positive                | N/A                                | N/A           | N/A                       | N/A                           |                              |
| 5400  | 1       | 2     | 206C    | Classroom 206 Closet                           | yes                               | Ceiling    | N/A                              | N/A                     | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 2     | 206C    | Classroom 206 Closet                           | yes                               | Floor      | None                             | N/A                     | N/A                                | N/A           | N/A                       | N/A                           |                              |
| 5400  | 1       | 2     | 206B    | Hallway Closet adjacent to Girl's Restroom     | no                                | W1         | No Access                        | No Access               | No Access                          | No Access     | No Access                 | No Access                     | Custodial has no key.        |
| 5400  | 1       | 2     | 206B    | Hallway Closet adjacent to Girl's Restroom     | no                                | W2         | No Access                        | No Access               | No Access                          | No Access     | No Access                 | No Access                     |                              |
| 5400  | 1       | 2     | 206B    | Hallway Closet adjacent to Girl's Restroom     | no                                | W3         | No Access                        | No Access               | No Access                          | No Access     | No Access                 | No Access                     |                              |
| 5400  | 1       | 2     | 206B    | Hallway Closet adjacent to Girl's Restroom     | no                                | W4         | No Access                        | No Access               | No Access                          | No Access     | No Access                 | No Access                     |                              |
| 5400  | 1       | 2     | 206B    | Hallway Closet adjacent to Girl's Restroom     | no                                | Ceiling    | No Access                        | No Access               | No Access                          | No Access     | No Access                 | No Access                     |                              |
| 5400  | 1       | 2     | 206B    | Hallway Closet adjacent to Girl's Restroom     | no                                | Floor      | No Access                        | No Access               | No Access                          | No Access     | No Access                 | No Access                     |                              |
| 5400  | 1       | 2     | 206A    | Girl's Restroom next to Classroom 206          | yes                               | W1         | None                             | N/A                     | N/A                                | N/A           | N/A                       | N/A                           |                              |
| 5400  | 1       | 2     | 206A    | Girl's Restroom next to Classroom 206          | yes                               | W2         | None                             | N/A                     | N/A                                | N/A           | N/A                       | N/A                           |                              |
| 5400  | 1       | 2     | 206A    | Girl's Restroom next to Classroom 206          | yes                               | W3         | None                             | N/A                     | N/A                                | N/A           | N/A                       | N/A                           |                              |
| 5400  | 1       | 2     | 206A    | Girl's Restroom next to Classroom 206          | yes                               | Pipe       | Chipping                         | Positive                | N/A                                | N/A           | N/A                       | N/A                           |                              |
| 5400  | 1       | 2     | 206A    | Girl's Restroom next to Classroom 206          | yes                               | W4         | None                             | N/A                     | N/A                                | N/A           | N/A                       | N/A                           |                              |
| 5400  | 1       | 2     | 206A    | Girl's Restroom next to Classroom 206          | yes                               | Radiator   | Alligating                       | Negative                | N/A                                | N/A           | N/A                       | N/A                           |                              |
| 5400  | 1       | 2     | 206A    | Girl's Restroom next to Classroom 206          | yes                               | Ceiling    | N/A                              | N/A                     | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 2     | 206A    | Girl's Restroom next to Classroom 206          | yes                               | Floor      | None                             | N/A                     | N/A                                | N/A           | N/A                       | N/A                           |                              |
| 5400  | 1       | 2     | H22     | Hallway from Boy's Restroom to Girl's Restroom | yes                               | W1         | None                             | N/A                     | N/A                                | N/A           | N/A                       | N/A                           |                              |
| 5400  | 1       | 2     | H22     | Hallway from Boy's Restroom to Girl's Restroom | yes                               | W2         | None                             | N/A                     | N/A                                | N/A           | N/A                       | N/A                           |                              |
| 5400  | 1       | 2     | H22     | Hallway from Boy's Restroom to Girl's Restroom | yes                               | W3         | None                             | N/A                     | N/A                                | N/A           | N/A                       | N/A                           |                              |
| 5400  | 1       | 2     | H22     | Hallway from Boy's Restroom to Girl's Restroom | yes                               | door       | Friction                         | Negative                | N/A                                | N/A           | N/A                       | N/A                           |                              |
| 5400  | 1       | 2     | H22     | Hallway from Boy's Restroom to Girl's Restroom | yes                               | door frame | Friction                         | Negative                | N/A                                | N/A           | N/A                       | N/A                           |                              |
| 5400  | 1       | 2     | H22     | Hallway from Boy's Restroom to Girl's Restroom | yes                               | W4         | None                             | N/A                     | N/A                                | N/A           | N/A                       | N/A                           |                              |
| 5400  | 1       | 2     | H22     | Hallway from Boy's Restroom to Girl's Restroom | yes                               | Ceiling    | Flaking                          | Positive                | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 2     | H22     | Hallway from Boy's Restroom to Girl's Restroom | yes                               | Floor      | N/A                              | N/A                     | n/a                                | n/a           | n/a                       | n/a                           |                              |

| ULCS# | Element | Floor | Space # | On-Site Room Name                       | Student/Teacher Occupied (yes/no) | Component | Description of Damage                       | XRF (positive/negative) | Debris Present (describe location) | Quantity (sf) | Contents Need to be Moved | Plastering Needed (yes or no) | Comments/ Description/ Notes |
|-------|---------|-------|---------|---|-----------------------------------|-----------|---|-------------------------|------------------------------------|---------------|---------------------------|-------------------------------|------------------------------|
| 5400  | 1       | 2     | 207A    | Custodial Closet adjacent Classroom 207 | no                                | W1        | Moisture Damage/Flaking                     | Positive                | N/A                                | N/A           | N/A                       | N/A                           |                              |
| 5400  | 1       | 2     | 207A    | Custodial Closet adjacent Classroom 207 | no                                | W2        | Flaking                                     | Positive                | N/A                                | N/A           | N/A                       | N/A                           |                              |
| 5400  | 1       | 2     | 207A    | Custodial Closet adjacent Classroom 207 | no                                | W3        | Flaking                                     | Positive                | N/A                                | N/A           | N/A                       | N/A                           |                              |
| 5400  | 1       | 1     | S12     | Stairwell across from Classroom 104     | yes                               | Pipe      | Flaking                                     | Positive                | N/A                                | N/A           | N/A                       | N/A                           |                              |
| 5400  | 1       | 2     | 207A    | Custodial Closet adjacent Classroom 207 | no                                | W4        | Flaking                                     | Positive                | N/A                                | N/A           | N/A                       | N/A                           |                              |
| 5400  | 1       | 2     | 207A    | Custodial Closet adjacent Classroom 207 | no                                | Ceiling   | Efflorescence, Flaking                      | Positive                | N/A                                | N/A           | N/A                       | N/A                           |                              |
| 5400  | 1       | 2     | 207A    | Custodial Closet adjacent Classroom 207 | no                                | Floor     | Chipping                                    | Negative                | n/a                                | n/a           | n/a                       | n/a                           |                              |
| 5400  | 1       | 2     | 207     | Classroom 207                           | yes                               | W1        | Chipping, holes                             | Positive                | N/A                                | N/A           | N/A                       | N/A                           |                              |
| 5400  | 1       | 2     | 207     | Classroom 207                           | yes                               | W2        | Peeling, staple holes                       | Negative                | N/A                                | N/A           | N/A                       | N/A                           |                              |
| 5400  | 1       | 2     | 207     | Classroom 207                           | yes                               | W3        | Holes, chipping, cracking                   | Positive                | N/A                                | N/A           | N/A                       | N/A                           |                              |
| 5400  | 1       | 2     | 207     | Classroom 207                           | yes                               | W4        | Holes, cracking                             | Positive                | N/A                                | N/A           | N/A                       | N/A                           |                              |
| 5400  | 1       | 2     | 207     | Classroom 207                           | yes                               | Ceiling   | Mositure Damage/Efflorescence               | Positive                | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 2     | 207     | Classroom 207                           | yes                               | Floor     | None  | N/A                     | N/A                                | N/A           | N/A                       | N/A                           | floor tile                   |
| 5400  | 1       | 2     | 207B    | Classroom 207 Restroom                  | yes                               | W1        | Flaking, Moisture Damage                    | Positive                | N/A                                | N/A           | N/A                       | N/A                           |                              |
| 5400  | 1       | 2     | 207B    | Classroom 207 Restroom                  | yes                               | W2        | Moisture Damage                             | Negative                | N/A                                | N/A           | N/A                       | N/A                           |                              |
| 5400  | 1       | 2     | 207B    | Classroom 207 Restroom                  | yes                               | W3        | Chipping, Holes                             | Positive                | N/A                                | N/A           | N/A                       | N/A                           |                              |
| 5400  | 1       | 2     | 207B    | Classroom 207 Restroom                  | yes                               | W4        | Efflorescence, Flaking                      | Positive                | N/A                                | N/A           | N/A                       | N/A                           |                              |
| 5400  | 1       | 2     | 207B    | Classroom 207 Restroom                  | yes                               | Ceiling   | N/A   | N/A                     | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 2     | 207B    | Classroom 207 Restroom                  | yes                               | Floor     | None  | N/A                     | N/A                                | N/A           | N/A                       | N/A                           | floor tile                   |
| 5400  | 1       | 2     | 207C    | Classroom 207 Closet                    | yes                               | W1        | Chipping, Cracking                          | Positive                | N/A                                | N/A           | N/A                       | N/A                           |                              |
| 5400  | 1       | 2     | 207C    | Classroom 207 Closet                    | yes                               | W2        | Holes, Cracking                             | Positive                | N/A                                | N/A           | N/A                       | N/A                           |                              |
| 5400  | 1       | 2     | 207C    | Classroom 207 Closet                    | yes                               | W3        | Chipping, Cracking                          | Positive                | N/A                                | N/A           | N/A                       | N/A                           |                              |
| 5400  | 1       | 2     | 207C    | Classroom 207 Closet                    | yes                               | W4        | Holes, Cracking                             | Positive                | N/A                                | N/A           | Partially Inaccessible    | N/A                           |                              |
| 5400  | 1       | 2     | 207C    | Classroom 207 Closet                    | yes                               | Ceiling   | N/A   | N/A                     | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 2     | 207C    | Classroom 207 Closet                    | yes                               | Floor     | None  | N/A                     | N/A                                | N/A           | N/A                       | N/A                           |                              |
| 5400  | 1       | 2     | 208     | Classroom 208                           | yes                               | W1        | Chipping                                    | Positive                | N/A                                | N/A           | N/A                       | N/A                           |                              |
| 5400  | 1       | 2     | 208     | Classroom 208                           | yes                               | W2        | None  | N/A                     | N/A                                | N/A           | N/A                       | N/A                           |                              |
| 5400  | 1       | 2     | 208     | Classroom 208                           | yes                               | W3        | Chipping, Cracking, Efflorescence and Holes | Positive                | N/A                                | N/A           | N/A                       | N/A                           |                              |
| 5400  | 1       | 2     | 208     | Classroom 208                           | yes                               | radiator  | Alligatoring                                | Negative                | N/A                                | N/A           | N/A                       | N/A                           |                              |
| 5400  | 1       | 2     | 208     | Classroom 208                           | yes                               | W4        | None  | N/A                     | N/A                                | N/A           | N/A                       | N/A                           |                              |
| 5400  | 1       | 2     | 208     | Classroom 208                           | yes                               | Ceiling   | Mositure Damage/Efflorescence               | Positive                | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 2     | 208     | Classroom 208                           | yes                               | Floor     | None  | N/A                     | N/A                                | N/A           | N/A                       | N/A                           |                              |
| 5400  | 1       | 2     | 208A    | Classroom 208 Closet                    | yes                               | W1        | Flaking                                     | Positive                | N/A                                | N/A           | N/A                       | N/A                           |                              |
| 5400  | 1       | 2     | 208A    | Classroom 208 Closet                    | yes                               | W2        | None  | N/A                     | N/A                                | N/A           | N/A                       | N/A                           |                              |
| 5400  | 1       | 2     | 208A    | Classroom 208 Closet                    | yes                               | W3        | Flaking                                     | Positive                | N/A                                | N/A           | N/A                       | N/A                           |                              |
| 5400  | 1       | 2     | 208A    | Classroom 208 Closet                    | yes                               | W4        | Partially Inaccessible                      | N/A                     | N/A                                | N/A           | N/A                       | N/A                           |                              |
| 5400  | 1       | 2     | 208A    | Classroom 208 Closet                    | yes                               | Ceiling   | N/A   | N/A                     | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 2     | 208A    | Classroom 208 Closet                    | yes                               | Floor     | None  | N/A                     | N/A                                | N/A           | N/A                       | N/A                           |                              |
| 5400  | 1       | 2     | H21     | Hallway from Classroom 207 to 208       | yes                               | W1        | None  | N/A                     | N/A                                | N/A           | N/A                       | N/A                           |                              |
| 5400  | 1       | 2     | H21     | Hallway from Classroom 207 to 208       | yes                               | W2        | None  | N/A                     | N/A                                | N/A           | N/A                       | N/A                           |                              |
| 5400  | 1       | 2     | H21     | Hallway from Classroom 207 to 208       | yes                               | pipe      | Chipping                                    | Positive                | N/A                                | N/A           | N/A                       | N/A                           |                              |
| 5400  | 1       | 2     | H21     | Hallway from Classroom 207 to 208       | yes                               | W3        | None  | N/A                     | N/A                                | N/A           | N/A                       | N/A                           |                              |
| 5400  | 1       | 2     | H21     | Hallway from Classroom 207 to 208       | yes                               | W4        | None  | N/A                     | N/A                                | N/A           | N/A                       | N/A                           |                              |
| 5400  | 1       | 2     | H21     | Hallway from Classroom 207 to 208       | yes                               | Ceiling   | Mositure Damage/Efflorescence               | Positive                | None                               | 0             | No                        | no                            |                              |

| ULCS# | Element | Floor | Space # | On-Site Room Name                   | Student/Teacher Occupied (yes/no) | Component  | Description of Damage         | XRF (positive/negative) | Debris Present (describe location) | Quantity (sf) | Contents Need to be Moved | Plastering Needed (yes or no) | Comments/ Description/ Notes                        |
|-------|---------|-------|---------|-------------------------------------|-----------------------------------|------------|-------------------------------|-------------------------|------------------------------------|---------------|---------------------------|-------------------------------|---|
| 5400  | 1       | 2     | H21     | Hallway from Classroom 207 to 208   | yes                               | Floor      | N/A                           | N/A                     | n/a                                | n/a           | n/a                       | n/a                           |   |
| 5400  | 1       | 2     | S21     | Stairwell across from Classroom 205 | yes                               | W1         | None                          | N/A                     | N/A                                | N/A           | N/A                       | N/A                           |   |
| 5400  | 1       | 2     | S21     | Stairwell across from Classroom 205 | yes                               | Door       | Friction                      | Negative                | N/A                                | N/A           | N/A                       | N/A                           |   |
| 5400  | 1       | 2     | S21     | Stairwell across from Classroom 205 | yes                               | Door Frame | Friction                      | Negative                | N/A                                | N/A           | N/A                       | N/A                           |   |
| 5400  | 1       | 2     | S21     | Stairwell across from Classroom 205 | yes                               | W2         | None                          | N/A                     | N/A                                | N/A           | N/A                       | N/A                           |   |
| 5400  | 1       | 2     | S21     | Stairwell across from Classroom 205 | yes                               | W3         | Flaking                       | Positive                | N/A                                | N/A           | N/A                       | N/A                           |   |
| 5400  | 1       | 2     | S21     | Stairwell across from Classroom 205 | yes                               | Pipe       | Chipping                      | Positive                | N/A                                | N/A           | N/A                       | N/A                           |   |
| 5400  | 1       | 2     | S21     | Stairwell across from Classroom 205 | yes                               | W4         | Flaking                       | Positive                | N/A                                | N/A           | N/A                       | N/A                           |   |
| 5400  | 1       | 2     | S21     | Stairwell across from Classroom 205 | yes                               | Ceiling    | Chipping                      | Positive                | N/A                                | N/A           | N/A                       | yes                           | Stair Undercarrage                                  |
| 5400  | 1       | 2     | S21     | Stairwell across from Classroom 205 | yes                               | Floor      | N/A                           | N/A                     | N/A                                | N/A           | N/A                       | N/A                           |   |
| 5400  | 1       | 2     | S21     | Stairwell across from Classroom 205 | yes                               | Tread      | Friction                      | Negative                | N/A                                | N/A           | N/A                       | N/A                           |   |
| 5400  | 1       | 2     | S21     | Stairwell across from Classroom 205 | yes                               | Stringer   | Friction                      | Negative                | N/A                                | N/A           | N/A                       | N/A                           |   |
| 5400  | 1       | 2     | S21     | Stairwell across from Classroom 205 | yes                               | Riser      | Friction                      | Negative                | N/A                                | N/A           | N/A                       | N/A                           |   |
| 5400  | 1       | 2     | S21     | Stairwell across from Classroom 205 | yes                               | Newel Post | Friction                      | Positive                | N/A                                | N/A           | N/A                       | N/A                           |   |
| 5400  | 1       | 2     | S21     | Stairwell across from Classroom 205 | yes                               | Ballest    | Friction                      | Positive                | N/A                                | N/A           | N/A                       | N/A                           |   |
| 5400  | 1       | 2     | 210     | ESOL Office 210                     | yes                               | W1         | None                          | N/A                     | N/A                                | N/A           | N/A                       | N/A                           |   |
| 5400  | 1       | 2     | 210     | ESOL Office 210                     | yes                               | W2         | Alligatoring, Holes           | Positive                | N/A                                | N/A           | N/A                       | N/A                           |   |
| 5400  | 1       | 2     | 210     | ESOL Office 210                     | yes                               | W3         | Flaking                       | Positive                | N/A                                | N/A           | N/A                       | N/A                           |   |
| 5400  | 1       | 2     | 210     | ESOL Office 210                     | yes                               | Radiator   | Alligatoring                  |                         | N/A                                | N/A           | N/A                       | N/A                           | unable to test. radiator is on and too hot to test. |
| 5400  | 1       | 2     | 210     | ESOL Office 210                     | yes                               | W4         | None                          | N/A                     | N/A                                | N/A           | N/A                       | N/A                           |   |
| 5400  | 1       | 2     | 210     | ESOL Office 210                     | yes                               | Ceiling    | N/A                           | N/A                     | None                               | 0             | No                        | no                            |   |
| 5400  | 1       | 2     | 210     | ESOL Office 210                     | yes                               | Floor      | None                          | N/A                     | N/A                                | N/A           | N/A                       | N/A                           |   |
| 5400  | 1       | 2     | 210R    | ESOL Office 210 Restroom            | yes                               | W1         | None                          | N/A                     | N/A                                | N/A           | N/A                       | N/A                           |   |
| 5400  | 1       | 2     | 210R    | ESOL Office 210 Restroom            | yes                               | Pipe       | Chipping                      | Negative                | N/A                                | N/A           | N/A                       | N/A                           |   |
| 5400  | 1       | 2     | 210R    | ESOL Office 210 Restroom            | yes                               | W2         | None                          | N/A                     | N/A                                | N/A           | N/A                       | N/A                           |   |
| 5400  | 1       | 2     | 210R    | ESOL Office 210 Restroom            | yes                               | W3         | None                          | N/A                     | N/A                                | N/A           | N/A                       | N/A                           |   |
| 5400  | 1       | 2     | 210R    | ESOL Office 210 Restroom            | yes                               | W4         | None                          | N/A                     | N/A                                | N/A           | N/A                       | N/A                           |   |
| 5400  | 1       | 2     | 210R    | ESOL Office 210 Restroom            | yes                               | Ceiling    | None                          | N/A                     | N/A                                | N/A           | N/A                       | N/A                           |   |
| 5400  | 1       | 2     | 210R    | ESOL Office 210 Restroom            | yes                               | Floor      | Cracking, Chipping            | Negative                | N/A                                | N/A           | N/A                       | N/A                           |   |
| 5400  | 1       | 2     | 209     | Classroom 209                       | yes                               | W1         | Chipping                      | Positive                | N/A                                | N/A           | N/A                       | yes                           |   |
| 5400  | 1       | 2     | 209     | Classroom 209                       | yes                               | W2         | None                          | N/A                     | N/A                                | N/A           | N/A                       | N/A                           |   |
| 5400  | 1       | 2     | 209     | Classroom 209                       | yes                               | W3         | Flaking, Chipping             | Positive                | N/A                                | N/A           | N/A                       | N/A                           |   |
| 5400  | 1       | 2     | 209     | Classroom 209                       | yes                               | Pipe       | Flaking                       | Positive                | N/A                                | N/A           | N/A                       | N/A                           |   |
| 5400  | 1       | 2     | 209     | Classroom 209                       | yes                               | W4         | Flaking, Chipping             | Positive                | N/A                                | N/A           | N/A                       | N/A                           |   |
| 5400  | 1       | 2     | 209     | Classroom 209                       | yes                               | Ceiling    | Mositure Damage/Efflorescence | Positive                | None                               | 0             | No                        | no                            |   |
| 5400  | 1       | 2     | 209     | Classroom 209                       | yes                               | Floor      | None                          | N/A                     | N/A                                | N/A           | N/A                       | N/A                           |   |
| 5400  | 1       | 2     | 209A    | Classroom 209 Closet                | yes                               | W1         | None                          | N/A                     | N/A                                | N/A           | N/A                       | N/A                           |   |
| 5400  | 1       | 2     | 209A    | Classroom 209 Closet                | yes                               | W2         | None                          | N/A                     | N/A                                | N/A           | N/A                       | N/A                           |   |
| 5400  | 1       | 2     | 209A    | Classroom 209 Closet                | yes                               | W3         | None                          | N/A                     | N/A                                | N/A           | N/A                       | N/A                           |   |
| 5400  | 1       | 2     | 209A    | Classroom 209 Closet                | yes                               | W4         | None                          | N/A                     | N/A                                | N/A           | N/A                       | N/A                           |   |
| 5400  | 1       | 2     | 209A    | Classroom 209 Closet                | yes                               | Ceiling    | None                          | N/A                     | N/A                                | N/A           | N/A                       | N/A                           |   |
| 5400  | 1       | 2     | 209A    | Classroom 209 Closet                | yes                               | Floor      | None                          | N/A                     | N/A                                | N/A           | N/A                       | N/A                           |   |
| 5400  | 1       | 2     | S22     | Stairwell across from Classroom 204 | yes                               | W1         | None                          | N/A                     | N/A                                | N/A           | N/A                       | N/A                           |   |
| 5400  | 1       | 2     | S22     | Stairwell across from Classroom 204 | yes                               | Door       | Friction                      | Negative                | N/A                                | N/A           | N/A                       | N/A                           |   |
| 5400  | 1       | 2     | S22     | Stairwell across from Classroom 204 | yes                               | Door Frame | Friction                      | Negative                | N/A                                | N/A           | N/A                       | N/A                           |   |
| 5400  | 1       | 2     | S22     | Stairwell across from Classroom 204 | yes                               | W2         | None                          | N/A                     | N/A                                | N/A           | N/A                       | N/A                           |   |
| 5400  | 1       | 2     | S22     | Stairwell across from Classroom 204 | yes                               | W3         | None                          | N/A                     | N/A                                | N/A           | N/A                       | N/A                           |   |
| 5400  | 1       | 2     | S22     | Stairwell across from Classroom 204 | yes                               | Pipe       | Chipping                      | Positive                | N/A                                | N/A           | N/A                       | N/A                           |   |
| 5400  | 1       | 2     | S22     | Stairwell across from Classroom 204 | yes                               | W4         | None                          | N/A                     | N/A                                | N/A           | N/A                       | N/A                           |   |
| 5400  | 1       | 2     | S22     | Stairwell across from Classroom 204 | yes                               | Ceiling    | None                          | N/A                     | N/A                                | N/A           | N/A                       | N/A                           |   |

| ULCS# | Element | Floor | Space # | On-Site Room Name                   | Student/Teacher Occupied (yes/no) | Component   | Description of Damage    | XRF (positive/negative) | Debris Present (describe location) | Quantity (sf) | Contents Need to be Moved | Plastering Needed (yes or no) | Comments/ Description/ Notes                    |
|-------|---------|-------|---------|-------------------------------------|-----------------------------------|-------------|--------------------------|-------------------------|------------------------------------|---------------|---------------------------|-------------------------------|---|
| 5400  | 1       | 2     | S22     | Stairwell across from Classroom 204 | yes                               | Floor       | None                     | N/A                     | N/A                                | N/A           | N/A                       | N/A                           |   |
| 5400  | 1       | 2     | S22     | Stairwell across from Classroom 204 | yes                               | Tread       | Friction                 | Negative                | N/A                                | N/A           | N/A                       | N/A                           |   |
| 5400  | 1       | 2     | S22     | Stairwell across from Classroom 204 | yes                               | Stringer    | Friction                 | Negative                | N/A                                | N/A           | N/A                       | N/A                           |   |
| 5400  | 1       | 2     | S22     | Stairwell across from Classroom 204 | yes                               | Riser       | Friction                 | Negative                | N/A                                | N/A           | N/A                       | N/A                           |   |
| 5400  | 1       | 2     | S22     | Stairwell across from Classroom 204 | yes                               | Newel Post  | Friction                 | Positive                | N/A                                | N/A           | N/A                       | N/A                           |   |
| 5400  | 1       | 2     | S22     | Stairwell across from Classroom 204 | yes                               | Ballest     | Friction                 | Positive                | N/A                                | N/A           | N/A                       | N/A                           |   |
| 5400  | 1       | 3     | 301     | Classroom 301                       | yes                               | W1          | Chipping/Cracking        | Positive                | None                               | 0             | No                        | yes                           |   |
| 5400  | 1       | 3     | 301     | Classroom 301                       | yes                               | W2          | N/A                      | N/A                     | None                               | 0             | No                        | no                            | partation wall                                  |
| 5400  | 1       | 3     | 301     | Classroom 301                       | yes                               | W3          | Chipping/Cracking        | Positive                | None                               | 0             | No                        | yes                           |   |
| 5400  | 1       | 3     | 301     | Classroom 301                       | yes                               | W4          | Cracking                 | Positive                | None                               | 0             | No                        | yes                           |   |
| 5400  | 1       | 3     | 301     | Classroom 301                       | yes                               | Ceiling     | Moisture Damage/Flakin   | Positive                | None                               | 0             | No                        | no                            |   |
| 5400  | 1       | 3     | 301     | Classroom 301                       | yes                               | Floor       | N/A                      | N/A                     | None                               | 0             | No                        | no                            |   |
| 5400  | 1       | 3     | 301A    | Classroom 301 Closet                | yes                               | W1          | Chipping                 | Positive                | None                               | 0             | No                        | no                            |   |
| 5400  | 1       | 3     | 301A    | Classroom 301 Closet                | yes                               | W2          | Partially Inaccessible   | N/A                     | None                               | 0             | Partially Inaccessible    | no                            |   |
| 5400  | 1       | 3     | 301A    | Classroom 301 Closet                | yes                               | W3          | Cracking/Moisture Damage | Positive                | None                               | 0             | No                        | yes                           |   |
| 5400  | 1       | 3     | 301A    | Classroom 301 Closet                | yes                               | W4          | Chipping                 | Positive                | None                               | 0             | No                        | no                            |   |
| 5400  | 1       | 3     | 301A    | Classroom 301 Closet                | yes                               | Ceiling     | Moisture Damage/Flakin   | Positive                | None                               | 0             | No                        | no                            |   |
| 5400  | 1       | 3     | 301A    | Classroom 301 Closet                | yes                               | Floor       | N/A                      | N/A                     | None                               | 0             | No                        | no                            |   |
| 5400  | 1       | 3     | 302     | Classroom 302                       | yes                               | W1          | Chipping/Cracking        | Positive                | None                               | 0             | No                        | yes                           |   |
| 5400  | 1       | 3     | 302     | Classroom 302                       | yes                               | W2          | Chipping/Cracking        | Positive                | None                               | 0             | No                        | yes                           |   |
| 5400  | 1       | 3     | 302     | Classroom 302                       | yes                               | W3          | Chipping/Cracking        | Positive                | None                               | 0             | No                        | yes                           |   |
| 5400  | 1       | 3     | 302     | Classroom 302                       | yes                               | W4          | N/A                      | N/A                     | None                               | 0             | No                        | no                            |   |
| 5400  | 1       | 3     | 302     | Classroom 302                       | yes                               | Ceiling     | Moisture Damage/Flakin   | Positive                | None                               | 0             | No                        | no                            |   |
| 5400  | 1       | 3     | 302     | Classroom 302                       | yes                               | Floor       | N/A                      | N/A                     | None                               | 0             | No                        | no                            |   |
| 5400  | 1       | 3     | 302A    | Classroom 302 Closet                | yes                               | W1          | Cracking                 | Positive                | None                               | 0             | No                        | yes                           |   |
| 5400  | 1       | 3     | 302A    | Classroom 302 Closet                | yes                               | W2          | Flaking                  | Positive                | None                               | 0             | No                        | no                            |   |
| 5400  | 1       | 3     | 302A    | Classroom 302 Closet                | yes                               | W3          | Cracking                 | Positive                | None                               | 0             | No                        | yes                           |   |
| 5400  | 1       | 3     | 302A    | Classroom 302 Closet                | yes                               | W4          | Cracking                 | Positive                | None                               | 0             | No                        | yes                           |   |
| 5400  | 1       | 3     | 302A    | Classroom 302 Closet                | yes                               | Ceiling     | N/A                      | N/A                     | None                               | 0             | No                        | no                            |   |
| 5400  | 1       | 3     | 302A    | Classroom 302 Closet                | yes                               | Floor       | N/A                      | N/A                     | None                               | 0             | No                        | no                            |   |
| 5400  | 1       | 3     | H32     | Hallway from Classroom 301 to 302   | yes                               | W1          | None                     | N/A                     | None                               | 0             | No                        | no                            |   |
| 5400  | 1       | 3     | H32     | Hallway from Classroom 301 to 302   | yes                               | W2          | None                     | N/A                     | None                               | 0             | No                        | no                            |   |
| 5400  | 1       | 3     | H32     | Hallway from Classroom 301 to 302   | yes                               | W3          | None                     | N/A                     | None                               | 0             | No                        | no                            |   |
| 5400  | 1       | 3     | H32     | Hallway from Classroom 301 to 302   | yes                               | W4          | Chipping/Flaking         | Positive                | None                               | 0             | No                        | no                            |   |
| 5400  | 1       | 3     | H32     | Hallway from Classroom 301 to 302   | yes                               | Pipe Casing | Flaking                  | Positive                | None                               | 0             | No                        | no                            |   |
| 5400  | 1       | 3     | H32     | Hallway from Classroom 301 to 302   | yes                               | Ceiling     | Moisture Damage/Flakin   | Positive                | None                               | 0             | No                        | no                            |   |
| 5400  | 1       | 3     | H32     | Hallway from Classroom 301 to 302   | yes                               | Floor       | N/A                      | N/A                     | None                               | 0             | No                        | no                            |   |
| 5400  | 1       | 3     | 302B    | Boy's Restroom                      | yes                               | W1          | Cracking                 | Positive                | None                               | 0             | No                        | yes                           |   |
| 5400  | 1       | 3     | 302B    | Boy's Restroom                      | yes                               | Door Frame  | Friction                 | Negative                | None                               | 0             | No                        | no                            |   |
| 5400  | 1       | 3     | 302B    | Boy's Restroom                      | yes                               | W2          | Chipping                 | Positive                | None                               | 0             | No                        | no                            |   |
| 5400  | 1       | 3     | 302B    | Boy's Restroom                      | yes                               | Radiator    | Chipping/Flaking         |                         | None                               | 0             | No                        | no                            | unable to test, radiator on and too hot to test |
| 5400  | 1       | 3     | 302B    | Boy's Restroom                      | yes                               | W3          | Chipping                 | Positive                | None                               | 0             | No                        | no                            |   |
| 5400  | 1       | 3     | 302B    | Boy's Restroom                      | yes                               | W4          | Chipping                 | Positive                | None                               | 0             | No                        | no                            |   |
| 5400  | 1       | 3     | 302B    | Boy's Restroom                      | yes                               | W3          | Chipping                 | Negative                | None                               | 0             | No                        | no                            |   |
| 5400  | 1       | 3     | 302B    | Boy's Restroom                      | yes                               | Pipe        | Flaking                  | Negative                | None                               | 0             | No                        | no                            |   |
| 5400  | 1       | 3     | 302B    | Boy's Restroom                      | yes                               | Ceiling     | None                     | N/A                     | None                               | 0             | No                        | no                            |   |
| 5400  | 1       | 3     | 302B    | Boy's Restroom                      | yes                               | Floor       | Friction                 | Negative                | None                               | 0             | No                        | no                            |   |

| ULCS# | Element | Floor | Space # | On-Site Room Name                                  | Student/Teacher Occupied (yes/no) | Component | Description of Damage     | XRF (positive/negative) | Debris Present (describe location) | Quantity (sf) | Contents Need to be Moved | Plastering Needed (yes or no) | Comments/ Description/ Notes  |
|-------|---------|-------|---------|--|-----------------------------------|-----------|---------------------------|-------------------------|------------------------------------|---------------|---------------------------|-------------------------------|---|
| 5400  | 1       | 3     | H33A    | Hall Closet adjacent to Boy's Restroom             | no                                | W1        | No Access                 | No Access               | No Access                          | No Access     | No Access                 | No Access                     | custodial does not have keys  |
| 5400  | 1       | 3     | H33A    | Hall Closet adjacent to Boy's Restroom             | no                                | W2        | No Access                 | No Access               | No Access                          | No Access     | No Access                 | No Access                     |   |
| 5400  | 1       | 3     | H33A    | Hall Closet adjacent to Boy's Restroom             | no                                | W3        | No Access                 | No Access               | No Access                          | No Access     | No Access                 | No Access                     |   |
| 5400  | 1       | 3     | H33A    | Hall Closet adjacent to Boy's Restroom             | no                                | W4        | No Access                 | No Access               | No Access                          | No Access     | No Access                 | No Access                     |   |
| 5400  | 1       | 3     | H33A    | Hall Closet adjacent to Boy's Restroom             | no                                | Ceiling   | No Access                 | No Access               | No Access                          | No Access     | No Access                 | No Access                     |   |
| 5400  | 1       | 3     | H33A    | Hall Closet adjacent to Boy's Restroom             | no                                | Floor     | No Access                 | No Access               | No Access                          | No Access     | No Access                 | No Access                     |   |
| 5400  | 1       | 3     | 303     | Classroom 303                                      | yes                               | W1        | Chipping/Flaking          | Positive                | None                               | 0             | No                        | no                            |   |
| 5400  | 1       | 3     | 303     | Classroom 303                                      | yes                               | W2        | Cracking                  | Positive                | None                               | 0             | No                        | yes                           |   |
| 5400  | 1       | 3     | 303     | Classroom 303                                      | yes                               | W3        | Flaking                   | Positive                | None                               | 0             | No                        | no                            |   |
| 5400  | 1       | 3     | 303     | Classroom 303                                      | yes                               | Radiator  | Chipping                  |                         | None                               | 0             | No                        | no                            | unable to test, radiator is on and too hot to test                              |
| 5400  | 1       | 3     | 303     | Classroom 303                                      | yes                               | W4        | Cracking/Flaking          | Positive                | None                               | 0             | No                        | yes                           |   |
| 5400  | 1       | 3     | 303     | Classroom 303                                      | yes                               | Ceiling   | Moisture Damage/Flakin    | Positive                | None                               | 0             | No                        | no                            |   |
| 5400  | 1       | 3     | 303     | Classroom 303                                      | yes                               | Floor     | N/A                       | N/A                     | None                               | 0             | No                        | no                            |   |
| 5400  | 1       | 3     | 303     | Classroom 303 Closet                               | yes                               | W1        | No Access                 | No Access               | No Access                          | No Access     | No Access                 | No Access                     | too much stuff. unable to enter closet  |
| 5400  | 1       | 3     | 303B    | Classroom 303 Closet                               | yes                               | W2        | No Access                 | No Access               | No Access                          | No Access     | No Access                 | No Access                     |   |
| 5400  | 1       | 3     | 303B    | Classroom 303 Closet                               | yes                               | W3        | No Access                 | No Access               | No Access                          | No Access     | No Access                 | No Access                     |   |
| 5400  | 1       | 3     | 303B    | Classroom 303 Closet                               | yes                               | W4        | No Access                 | No Access               | No Access                          | No Access     | No Access                 | No Access                     |   |
| 5400  | 1       | 3     | 303B    | Classroom 303 Closet                               | yes                               | Ceiling   | No Access                 | No Access               | No Access                          | No Access     | No Access                 | No Access                     |   |
| 5400  | 1       | 3     | 303B    | Classroom 303 Closet                               | yes                               | Floor     | No Access                 | No Access               | No Access                          | No Access     | No Access                 | No Access                     |   |
| 5400  | 1       | 3     | 303A    | Counselor's Office 303A                            | yes                               | W1        | None                      | N/A                     | None                               | 0             | No                        | no                            |   |
| 5400  | 1       | 3     | 303A    | Counselor's Office 303A                            | yes                               | Baseboard | Cracking                  | Positive                | None                               | 0             | No                        | yes                           |   |
| 5400  | 1       | 3     | 303A    | Counselor's Office 303A                            | yes                               | W2        | Staple Holes              | Positive                | None                               | 0             | No                        | yes                           |   |
| 5400  | 1       | 3     | 303A    | Counselor's Office 303A                            | yes                               | Baseboard | Cracking                  | Positive                | None                               | 0             | No                        | yes                           |   |
| 5400  | 1       | 3     | 303A    | Counselor's Office 303A                            | yes                               | W3        | None                      | N/A                     | None                               | 0             | No                        | no                            |   |
| 5400  | 1       | 3     | 303A    | Counselor's Office 303A                            | yes                               | Baseboard | Cracking                  | Positive                | None                               | 0             | No                        | yes                           |   |
| 5400  | 1       | 3     | 303A    | Counselor's Office 303A                            | yes                               | W4        | None                      | N/A                     | None                               | 0             | No                        | no                            |   |
| 5400  | 1       | 3     | 303A    | Counselor's Office 303A                            | yes                               | Baseboard | Cracking                  | Positive                | None                               | 0             | No                        | yes                           |   |
| 5400  | 1       | 3     | 303A    | Counselor's Office 303A                            | yes                               | Ceiling   | N/A                       | N/A                     | None                               | 0             | No                        | no                            |   |
| 5400  | 1       | 3     | 303A    | Counselor's Office 303A                            | yes                               | Floor     | N/A                       | N/A                     | None                               | 0             | No                        | no                            |   |
| 5400  | 1       | 3     | 303A1   | Counselor's Office 303A Vestibule                  | yes                               | W1        | None                      | N/A                     | None                               | 0             | No                        | no                            |   |
| 5400  | 1       | 3     | 303A2   | Counselor's Office 303A Vestibule                  | yes                               | Baseboard | Cracking                  | Positive                | None                               | 0             | No                        | yes                           |   |
| 5400  | 1       | 3     | 303A3   | Counselor's Office 303A Vestibule                  | yes                               | W2        | None                      | N/A                     | None                               | 0             | No                        | no                            |   |
| 5400  | 1       | 3     | 303A4   | Counselor's Office 303A Vestibule                  | yes                               | Baseboard | Cracking                  | Positive                | None                               | 0             | No                        | yes                           |   |
| 5400  | 1       | 3     | 303A5   | Counselor's Office 303A Vestibule                  | yes                               | W3        | None                      | N/A                     | None                               | 0             | No                        | no                            |   |
| 5400  | 1       | 3     | 303A6   | Counselor's Office 303A Vestibule                  | yes                               | Baseboard | Cracking                  | Positive                | None                               | 0             | No                        | yes                           |   |
| 5400  | 1       | 3     | 303A7   | Counselor's Office 303A Vestibule                  | yes                               | W4        | None                      | N/A                     | None                               | 0             | No                        | no                            |   |
| 5400  | 1       | 3     | 303A8   | Counselor's Office 303A Vestibule                  | yes                               | Baseboard | Cracking                  | Positive                | None                               | 0             | No                        | yes                           |   |
| 5400  | 1       | 3     | 303A9   | Counselor's Office 303A Vestibule                  | yes                               | Ceiling   | N/A                       | N/A                     | None                               | 0             | No                        | no                            |   |
| 5400  | 1       | 3     | 303A10  | Counselor's Office 303A Vestibule                  | yes                               | Floor     | N/A                       | N/A                     | None                               | 0             | No                        | no                            |   |
| 5400  | 1       | 3     | 303C    | Storage Closet adjacent to Counselor's Office 303A | yes                               | W1        | None                      | N/A                     | None                               | 0             | No                        | no                            | Bookcase covers majority of wall. no damage observed on exposed portion of wall |
| 5400  | 1       | 3     | 303C    | Storage Closet adjacent to Counselor's Office 303A | yes                               | W2        | None                      | N/A                     | None                               | 0             | No                        | no                            |   |
| 5400  | 1       | 3     | 303C    | Storage Closet adjacent to Counselor's Office 303A | yes                               | W3        | Cracking                  | Positive                | None                               | 0             | No                        | yes                           |   |
| 5400  | 1       | 3     | 303C    | Storage Closet adjacent to Counselor's Office 303A | yes                               | W4        | Flaking                   | Positive                | None                               | 0             | No                        | no                            |   |
| 5400  | 1       | 3     | 303C    | Storage Closet adjacent to Counselor's Office 303A | yes                               | Ceiling   | Efflorescence             | Positive                | None                               | 0             | No                        | yes                           |   |
| 5400  | 1       | 3     | 303C    | Storage Closet adjacent to Counselor's Office 303A | yes                               | Floor     | N/A                       | N/A                     | None                               | 0             | No                        | no                            |   |
| 5400  | 1       | 3     | 304     | Classroom 304                                      | yes                               | W1        | Chipping/Cracking/Flaking | Positive                | None                               | 0             | No                        | yes                           |   |
| 5400  | 1       | 3     | 304     | Classroom 304                                      | yes                               | W2        | N/A                       | N/A                     | None                               | 0             | No                        | no                            |   |
| 5400  | 1       | 3     | 304     | Classroom 304                                      | yes                               | W3        | Cracking/Flaking          | Positive                | None                               | 0             | No                        | yes                           |   |

| ULCS# | Element | Floor | Space # | On-Site Room Name                          | Student/Teacher Occupied (yes/no) | Component | Description of Damage                 | XRF (positive/negative) | Debris Present (describe location) | Quantity (sf) | Contents Need to be Moved | Plastering Needed (yes or no) | Comments/ Description/ Notes                       |
|-------|---------|-------|---------|--|-----------------------------------|-----------|---------------------------------------|-------------------------|------------------------------------|---------------|---------------------------|-------------------------------|--|
| 5400  | 1       | 3     | 304     | Classroom 305                              | yes                               | Radiator  | Chipping                              |                         | None                               | 0             | No                        | no                            | unable to test, radiator is on and too hot to test |
| 5400  | 1       | 3     | 304     | Classroom 304                              | yes                               | W4        | Cracking/Flaking                      | Positive                | None                               | 0             | No                        | yes                           |  |
| 5400  | 1       | 3     | 304     | Classroom 304                              | yes                               | Ceiling   | Moisture Damage/Flaking               | Positive                | None                               | 0             | No                        | no                            |  |
| 5400  | 1       | 3     | 304     | Classroom 304                              | yes                               | Floor     | N/A                                   | N/A                     | None                               | 0             | No                        | no                            |  |
| 5400  | 1       | 3     | 304A    | Classroom 304 Closet                       | yes                               | W1        | Staple Holes                          | Positive                | None                               | 0             | No                        | yes                           |  |
| 5400  | 1       | 3     | 304A    | Classroom 304 Closet                       | yes                               | W2        | Cracking                              | Positive                | None                               | 0             | No                        | yes                           |  |
| 5400  | 1       | 3     | 304A    | Classroom 304 Closet                       | yes                               | W3        | Cracking                              | Positive                | None                               | 0             | No                        | yes                           |  |
| 5400  | 1       | 3     | 304A    | Classroom 304 Closet                       | yes                               | W4        | None                                  | N/A                     | None                               | 0             | No                        | no                            |  |
| 5400  | 1       | 3     | 304A    | Classroom 304 Closet                       | yes                               | Ceiling   | N/A                                   | N/A                     | None                               | 0             | No                        | no                            |  |
| 5400  | 1       | 3     | 304A    | Classroom 304 Closet                       | yes                               | Floor     | N/A                                   | N/A                     | None                               | 0             | No                        | no                            |  |
| 5400  | 1       | 3     | 305     | Classroom 305                              | yes                               | W1        | Staple Holes/Chipping/Claking         | Positive                | None                               | 0             | Prior to Repair           | yes                           |  |
| 5400  | 1       | 3     | 305     | Classroom 305                              | yes                               | W2        | N/A                                   | N/A                     | None                               | 0             | No                        | no                            |  |
| 5400  | 1       | 3     | 305     | Classroom 305                              | yes                               | W3        | Chipping/Cracking                     | Positive                | None                               | 0             | No                        | yes                           |  |
| 5400  | 1       | 3     | 305     | Classroom 306                              | yes                               | Radiator  | Chipping                              |                         | None                               | 0             | No                        | no                            | unable to test, radiator is on and too hot to test |
| 5400  | 1       | 3     | 305     | Classroom 305                              | yes                               | W4        | N/A                                   | N/A                     | None                               | 0             | No                        | no                            |  |
| 5400  | 1       | 3     | 305     | Classroom 305                              | yes                               | Ceiling   | Moisture Damage/Flaking               | Positive                | None                               | 0             | No                        | no                            |  |
| 5400  | 1       | 3     | 305     | Classroom 305                              | yes                               | Floor     | N/A                                   | N/A                     | None                               | 0             | No                        | no                            |  |
| 5400  | 1       | 3     | 305A    | Classroom 305 Closet                       | yes                               | W1        | Cracking                              | Positive                | None                               | 0             | Prior to Repair           | yes                           |  |
| 5400  | 1       | 3     | 305A    | Classroom 305 Closet                       | yes                               | W2        | None                                  | N/A                     | None                               | 0             | No                        | no                            |  |
| 5400  | 1       | 3     | 305A    | Classroom 305 Closet                       | yes                               | W3        | Flaking/Chipping                      | Positive                | None                               | 0             | No                        | no                            |  |
| 5400  | 1       | 3     | 305A    | Classroom 305 Closet                       | yes                               | W4        | Cracking                              | Positive                | None                               | 0             | No                        | yes                           |  |
| 5400  | 1       | 3     | 305A    | Classroom 305 Closet                       | yes                               | Ceiling   | Moisture Damage                       | Positive                | None                               | 0             | No                        | no                            |  |
| 5400  | 1       | 3     | 305A    | Classroom 305 Closet                       | yes                               | Floor     | N/A                                   | N/A                     | None                               | 0             | No                        | no                            |  |
| 5400  | 1       | 3     | 306     | Classroom 306                              | yes                               | W1        | Chipping/Cracking                     | Positive                | None                               | 0             | No                        | yes                           |  |
| 5400  | 1       | 3     | 306     | Classroom 306                              | yes                               | W2        | Moisture Damage/Flaking               | Positive                | None                               | 0             | Prior to Repair           | yes                           |  |
| 5400  | 1       | 3     | 306     | Classroom 306                              | yes                               | W3        | Cracking/Chipping                     | Positive                | None                               | 0             | No                        | yes                           |  |
| 5400  | 1       | 3     | 306     | Classroom 307                              | yes                               | Radiator  | Chipping                              |                         | None                               | 0             | No                        | no                            | unable to test, radiator is on and too hot to test |
| 5400  | 1       | 3     | 306     | Classroom 306                              | yes                               | W4        | Cracking/Chipping                     | Positive                | None                               | 0             | No                        | yes                           |  |
| 5400  | 1       | 3     | 306     | Classroom 306                              | yes                               | Ceiling   | Moisture Damage/Efflorescence/Flaking | Positive                | None                               | 0             | No                        | no                            |  |
| 5400  | 1       | 3     | 306     | Classroom 306                              | yes                               | Floor     | N/A                                   | N/A                     | None                               | 0             | No                        | no                            |  |
| 5400  | 1       | 3     | 306A    | Classroom 306 Closet                       | yes                               | W1        | Cracking                              | Positive                | None                               | 0             | No                        | yes                           |  |
| 5400  | 1       | 3     | 306A    | Classroom 306 Closet                       | yes                               | W2        | None                                  | N/A                     | None                               | 0             | No                        | no                            |  |
| 5400  | 1       | 3     | 306A    | Classroom 306 Closet                       | yes                               | W3        | Cracking/Chipping                     | Positive                | None                               | 0             | No                        | yes                           |  |
| 5400  | 1       | 3     | 306A    | Classroom 306 Closet                       | yes                               | W4        | Cracking                              | Positive                | None                               | 0             | No                        | yes                           |  |
| 5400  | 1       | 3     | 306A    | Classroom 306 Closet                       | yes                               | Ceiling   | Moisture Damage/Flakin                | Positive                | None                               | 0             | No                        | no                            |  |
| 5400  | 1       | 3     | 306A    | Classroom 306 Closet                       | yes                               | Floor     | N/A                                   | N/A                     | None                               | 0             | No                        | no                            |  |
| 5400  | 1       | 3     | 306C    | Hallway Closet adjacent to Girl's Restroom | no                                | W1        | None                                  | N/A                     | None                               | 0             | No                        | no                            |  |
| 5400  | 1       | 3     | 306C    | Hallway Closet adjacent to Girl's Restroom | no                                | W2        | None                                  | N/A                     | None                               | 0             | No                        | no                            |  |
| 5400  | 1       | 3     | 306C    | Hallway Closet adjacent to Girl's Restroom | no                                | W3        | None                                  | N/A                     | None                               | 0             | No                        | no                            |  |
| 5400  | 1       | 3     | 306C    | Hallway Closet adjacent to Girl's Restroom | no                                | W4        | None                                  | N/A                     | None                               | 0             | No                        | no                            |  |
| 5400  | 1       | 3     | 306C    | Hallway Closet adjacent to Girl's Restroom | no                                | Ceiling   | None                                  | N/A                     | None                               | 0             | No                        | no                            |  |
| 5400  | 1       | 3     | 306C    | Hallway Closet adjacent to Girl's Restroom | no                                | Floor     | N/A                                   | N/A                     | None                               | 0             | No                        | no                            |  |
| 5400  | 1       | 3     | 306B    | Girl's Restroom                            | yes                               | W1        | None                                  | N/A                     | None                               | 0             | No                        | no                            |  |
| 5400  | 1       | 3     | 306B    | Girl's Restroom                            | yes                               | W2        | Cracking                              | Positive                | None                               | 0             | No                        | yes                           |  |

| ULCS# | Element | Floor | Space # | On-Site Room Name                              | Student/Teacher Occupied (yes/no) | Component | Description of Damage            | XRF (positive/negative) | Debris Present (describe location) | Quantity (sf) | Contents Need to be Moved | Plastering Needed (yes or no) | Comments/ Description/ Notes                        |
|-------|---------|-------|---------|--|-----------------------------------|-----------|----------------------------------|-------------------------|------------------------------------|---------------|---------------------------|-------------------------------|---|
| 5400  | 1       | 3     | 306B    | Girl's Restroom                                | yes                               | Pipe      | Chipping                         | Positive                | None                               | 0             | No                        | no                            |   |
| 5400  | 1       | 3     | 306B    | Girl's Restroom                                | yes                               | W3        | None                             | N/A                     | None                               | 0             | No                        | no                            |   |
| 5400  | 1       | 3     | 306B    | Girl's Restroom                                | yes                               | Radiator  | Alligating                       |                         | None                               | 0             | No                        | no                            | unable to test. radiator is on and too hot to test. |
| 5400  | 1       | 3     | 306B    | Girl's Restroom                                | yes                               | W4        | Cracking/Chipping                | Positive                | None                               | 0             | No                        | yes                           |   |
| 5400  | 1       | 3     | 306B    | Girl's Restroom                                | yes                               | Ceiling   | Moisture Damage                  | Positive                | None                               | 0             | No                        | no                            |   |
| 5400  | 1       | 3     | 306B    | Girl's Restroom                                | yes                               | Floor     | None                             | N/A                     | None                               | 0             | No                        | no                            |   |
| 5400  | 1       | 3     | H33     | Hallway from Boy's Restroom to Girl's Restroom | yes                               | W1        | Chipping/Cracking                | Positive                | None                               | 0             | No                        | yes                           |   |
| 5400  | 1       | 3     | H33     | Hallway from Boy's Restroom to Girl's Restroom | yes                               | W2        | Chipping                         | Positive                | None                               | 0             | No                        | no                            |   |
| 5400  | 1       | 3     | H33     | Hallway from Boy's Restroom to Girl's Restroom | yes                               | W3        | None                             | N/A                     | None                               | 0             | No                        | no                            |   |
| 5400  | 1       | 3     | H34     | Hallway from Boy's Restroom to Girl's Restroom | yes                               | Door      | Friction                         | Friction                | None                               | 0             | No                        | no                            |   |
| 5400  | 1       | 3     | H35     | Hallway from Boy's Restroom to Girl's Restroom | yes                               | Dor Frame | Friction                         | Friction                | None                               | 0             | No                        | no                            |   |
| 5400  | 1       | 3     | H33     | Hallway from Boy's Restroom to Girl's Restroom | yes                               | W4        | None                             | N/A                     | None                               | 0             | No                        | no                            |   |
| 5400  | 1       | 3     | H33     | Hallway from Boy's Restroom to Girl's Restroom | yes                               | Ceiling   | Moisture Damage/Flakin           | Positive                | None                               | 0             | No                        | no                            |   |
| 5400  | 1       | 3     | H33     | Hallway from Boy's Restroom to Girl's Restroom | yes                               | Floor     | N/A                              | N/A                     | None                               | 0             | No                        | no                            |   |
| 5400  | 1       | 3     | 307A    | Custodial Closet adjacent to Classroom 307     | no                                | W1        | None                             | N/A                     | None                               | 0             | No                        | no                            |   |
| 5400  | 1       | 3     | 307A    | Custodial Closet adjacent to Classroom 307     | no                                | W2        | None                             | N/A                     | None                               | 0             | No                        | no                            |   |
| 5400  | 1       | 3     | 307A    | Custodial Closet adjacent to Classroom 307     | no                                | W3        | None                             | N/A                     | None                               | 0             | No                        | no                            |   |
| 5400  | 1       | 3     | 307A    | Custodial Closet adjacent to Classroom 307     | no                                | W4        | None                             | N/A                     | None                               | 0             | No                        | no                            |   |
| 5400  | 1       | 3     | 307A    | Custodial Closet adjacent to Classroom 307     | no                                | Ceiling   | None                             | N/A                     | None                               | 0             | No                        | no                            |   |
| 5400  | 1       | 3     | 307A    | Custodial Closet adjacent to Classroom 307     | no                                | Floor     | N/A                              | N/A                     | None                               | 0             | No                        | no                            |   |
| 5400  | 1       | 3     | 307     | Classroom 307                                  | yes                               | W1        | Chipping/Crackin                 | Positive                | None                               | 0             | No                        | yes                           |   |
| 5400  | 1       | 3     | 307     | Classroom 307                                  | yes                               | W2        | N/A                              | N/A                     | None                               | 0             | No                        | no                            |   |
| 5400  | 1       | 3     | 307     | Classroom 307                                  | yes                               | W3        | Cracking/Flaking                 | Positive                | None                               | 0             | No                        | yes                           |   |
| 5400  | 1       | 3     | 307     | Classroom 307                                  | yes                               | W4        | Cracking                         | Positive                | None                               | 0             | No                        | yes                           |   |
| 5400  | 1       | 3     | 307     | Classroom 307                                  | yes                               | Ceiling   | Moisture Damage/Flakin           | Positive                | None                               | 0             | No                        | no                            |   |
| 5400  | 1       | 3     | 307     | Classroom 307                                  | yes                               | Floor     | N/A                              | N/A                     | None                               | 0             | No                        | no                            |   |
| 5400  | 1       | 3     | 307B    | Classroom 307 Closet                           | yes                               | W1        | No Access                        | No Access               | No Access                          | No Access     | No Access                 | No Access                     | teacher has key                                     |
| 5400  | 1       | 3     | 307B    | Classroom 307 Closet                           | yes                               | W2        | No Access                        | No Access               | No Access                          | No Access     | No Access                 | No Access                     |   |
| 5400  | 1       | 3     | 307B    | Classroom 307 Closet                           | yes                               | W3        | No Access                        | No Access               | No Access                          | No Access     | No Access                 | No Access                     |   |
| 5400  | 1       | 3     | 307B    | Classroom 307 Closet                           | yes                               | W4        | No Access                        | No Access               | No Access                          | No Access     | No Access                 | No Access                     |   |
| 5400  | 1       | 3     | 307B    | Classroom 307 Closet                           | yes                               | Ceiling   | No Access                        | No Access               | No Access                          | No Access     | No Access                 | No Access                     |   |
| 5400  | 1       | 3     | 307B    | Classroom 307 Closet                           | yes                               | Floor     | No Access                        | No Access               | No Access                          | No Access     | No Access                 | No Access                     |   |
| 5400  | 1       | 3     | 308     | Classroom 308                                  | yes                               | W1        | Chipping/Cracking                | Positive                | None                               | 0             | No                        | yes                           |   |
| 5400  | 1       | 3     | 308     | Classroom 308                                  | yes                               | W2        | Holes                            | Positive                | None                               | 0             | No                        | yes                           |   |
| 5400  | 1       | 3     | 308     | Classroom 308                                  | yes                               | W3        | Efflorescence/Cracking /Chipping | Positive                | None                               | 0             | No                        | yes                           |   |
| 5400  | 1       | 3     | 308     | Classroom 308                                  | yes                               | W4        | Cracking                         | Positive                | None                               | 0             | No                        | yes                           |   |
| 5400  | 1       | 3     | 308     | Classroom 308                                  | yes                               | Ceiling   | Moisture Damage/Flakin           | Positive                | None                               | 0             | No                        | no                            |   |
| 5400  | 1       | 3     | 308     | Classroom 308                                  | yes                               | Floor     | N/A                              | N/A                     | None                               | 0             | No                        | no                            |   |
| 5400  | 1       | 3     | 308A    | Classroom 308 Closet                           | yes                               | W1        | Chipping                         | Positive                | None                               | 0             | No                        | no                            |   |
| 5400  | 1       | 3     | 308A    | Classroom 308 Closet                           | yes                               | W2        | None                             | N/A                     | None                               | 0             | No                        | no                            |   |
| 5400  | 1       | 3     | 308A    | Classroom 308 Closet                           | yes                               | W3        | None                             | N/A                     | None                               | 0             | No                        | no                            |   |
| 5400  | 1       | 3     | 308A    | Classroom 308 Closet                           | yes                               | W4        | Efflorescence/Moisture Damage    | Positive                | None                               | 0             | No                        | yes                           |   |
| 5400  | 1       | 3     | 308A    | Classroom 308 Closet                           | yes                               | Ceiling   | N/A                              | N/A                     | None                               | 0             | No                        | no                            |   |
| 5400  | 1       | 3     | 308A    | Classroom 308 Closet                           | yes                               | Floor     | N/A                              | N/A                     | None                               | 0             | No                        | no                            |   |
| 5400  | 1       | 3     | H31     | Hallway from Classroom 307 to 308              | yes                               | W1        | None                             | N/A                     | None                               | 0             | No                        | no                            |   |
| 5400  | 1       | 3     | H31     | Hallway from Classroom 307 to 308              | yes                               | W2        | Chipping/Cracking                | Positive                | None                               | 0             | No                        | yes                           |   |
| 5400  | 1       | 3     | H31     | Hallway from Classroom 307 to 309              | yes                               | Pipe      | Chipping                         | Positive                | None                               | 0             | No                        | no                            |   |



| ULCS# | Element | Floor | Space # | On-Site Room Name                   | Student/Teacher Occupied (yes/no) | Component      | Description of Damage   | XRF (positive/negative) | Debris Present (describe location) | Quantity (sf) | Contents Need to be Moved | Plastering Needed (yes or no) | Comments/ Description/ Notes                        |
|-------|---------|-------|---------|-------------------------------------|-----------------------------------|----------------|-------------------------|-------------------------|------------------------------------|---------------|---------------------------|-------------------------------|---|
| 5400  | 1       | 3     | H31     | Hallway from Classroom 307 to 308   | yes                               | W3             | None                    | N/A                     | None                               | 0             | No                        | no                            |   |
| 5400  | 1       | 3     | H31     | Hallway from Classroom 307 to 308   | yes                               | W4             | Chipping                | Positive                | None                               | 0             | No                        | no                            |   |
| 5400  | 1       | 3     | H31     | Hallway from Classroom 307 to 308   | yes                               | Ceiling        | Moisture Damage/Flakin  | Positive                | None                               | 0             | No                        | no                            |   |
| 5400  | 1       | 3     | H31     | Hallway from Classroom 307 to 308   | yes                               | Floor          | N/A                     | N/A                     | None                               | 0             | No                        | no                            |   |
| 5400  | 1       | 3     | S31     | Stairwell across from Classroom 305 | yes                               | W1             | None                    | N/A                     | None                               | 0             | No                        | no                            |   |
| 5400  | 1       | 3     | S32     | Stairwell across from Classroom 306 | yes                               | Door           | Friction                | Negative                | None                               | 0             | No                        | no                            |   |
| 5400  | 1       | 3     | S33     | Stairwell across from Classroom 307 | yes                               | Door Frame     | Friction                | Negative                | None                               | 0             | No                        | no                            |   |
| 5400  | 1       | 3     | S34     | Stairwell across from Classroom 308 | yes                               | W2             | None                    | N/A                     | None                               | 0             | No                        | no                            |   |
| 5400  | 1       | 3     | S35     | Stairwell across from Classroom 309 | yes                               | W3             | None                    | N/A                     | None                               | 0             | No                        | no                            |   |
| 5400  | 1       | 3     | S36     | Stairwell across from Classroom 310 | yes                               | Pipe           | Chipping                | Positive                | None                               | 0             | No                        | no                            |   |
| 5400  | 1       | 3     | S37     | Stairwell across from Classroom 311 | yes                               | Radiator Cover | Friction                | Negative                | None                               | 0             | No                        | no                            |   |
| 5400  | 1       | 3     | S38     | Stairwell across from Classroom 312 | yes                               | W4             | None                    | N/A                     | None                               | 0             | No                        | no                            |   |
| 5400  | 1       | 3     | S39     | Stairwell across from Classroom 313 | yes                               | Ceiling        | None                    | N/A                     | None                               | 0             | No                        | no                            |   |
| 5400  | 1       | 3     | S40     | Stairwell across from Classroom 314 | yes                               | Floor          | N/A                     | N/A                     | None                               | 0             | No                        | no                            |   |
| 5400  | 1       | 3     | S41     | Stairwell across from Classroom 315 | yes                               | Stair Riser    | Friction                | Negative                | None                               | 0             | No                        | no                            |   |
| 5400  | 1       | 3     | S42     | Stairwell across from Classroom 316 | yes                               | Stair Stringer | Friction                | Negative                | None                               | 0             | No                        | no                            |   |
| 5400  | 1       | 3     | S43     | Stairwell across from Classroom 317 | yes                               | Stair Tred     | Friction                | Negative                | None                               | 0             | No                        | no                            |   |
| 5400  | 1       | 3     | S44     | Stairwell across from Classroom 318 | yes                               | Newel Post     | Friction                | Positive                | None                               | 0             | No                        | no                            |   |
| 5400  | 1       | 3     | S45     | Stairwell across from Classroom 319 | yes                               | Ballast        | Friction                | Positive                | None                               | 0             | No                        | no                            |   |
| 5400  | 1       | 3     | 310     | Office 310                          | yes                               | W1             | Cracking                | Positive                | None                               | 0             | No                        | no                            |   |
| 5400  | 1       | 3     | 310     | Office 310                          | yes                               | W2             | Cracking/Chipping       | Positive                | None                               | 0             | No                        | no                            |   |
| 5400  | 1       | 3     | 310     | Office 310                          | yes                               | W3             | Flaking/Chipping        | Positive                | None                               | 0             | No                        | no                            |   |
| 5400  | 1       | 3     | 310     | Office 310                          | yes                               | Radiator       | Chipping                |                         | None                               | 0             | No                        | no                            | unable to test. radiator is on and too hot to test. |
| 5400  | 1       | 3     | 310     | Office 310                          | yes                               | W4             | Cracking                | Positive                | None                               | 0             | No                        | no                            |   |
| 5400  | 1       | 3     | 310     | Office 310                          | yes                               | Ceiling        | N/A                     | N/A                     | None                               | 0             | No                        | no                            |   |
| 5400  | 1       | 3     | 310     | Office 310                          | yes                               | Floor          | N/A                     | N/A                     | None                               | 0             | No                        | no                            |   |
| 5400  | 1       | 3     | 310A1   | Office 310 Vestibule                | yes                               | W1             | None                    | N/A                     | None                               | 0             | No                        | no                            |   |
| 5400  | 1       | 3     | 310A1   | Office 310 Vestibule                | yes                               | W2             | None                    | N/A                     | None                               | 0             | No                        | no                            |   |
| 5400  | 1       | 3     | 310A1   | Office 310 Vestibule                | yes                               | W3             | None                    | N/A                     | None                               | 0             | No                        | no                            |   |
| 5400  | 1       | 3     | 310A1   | Office 310 Vestibule                | yes                               | W4             | None                    | N/A                     | None                               | 0             | No                        | no                            |   |
| 5400  | 1       | 3     | 310A1   | Office 310 Vestibule                | yes                               | Ceiling        | N/A                     | N/A                     | None                               | 0             | No                        | no                            |   |
| 5400  | 1       | 3     | 310A1   | Office 310 Vestibule                | yes                               | Floor          | N/A                     | N/A                     | None                               | 0             | No                        | no                            |   |
| 5400  | 1       | 3     | 310A    | Office 310 Restroom                 | yes                               | W1             | None                    | N/A                     | None                               | 0             | No                        | no                            |   |
| 5400  | 1       | 3     | 310A    | Office 310 Restroom                 | yes                               | W2             | None                    | N/A                     | None                               | 0             | No                        | no                            |   |
| 5400  | 1       | 3     | 310A    | Office 310 Restroom                 | yes                               | W3             | None                    | N/A                     | None                               | 0             | No                        | no                            |   |
| 5400  | 1       | 3     | 310A    | Office 310 Restroom                 | yes                               | W4             | None                    | N/A                     | None                               | 0             | No                        | no                            |   |
| 5400  | 1       | 3     | 310A    | Office 310 Restroom                 | yes                               | Ceiling        | N/A                     | N/A                     | None                               | 0             | No                        | no                            |   |
| 5400  | 1       | 3     | 310A    | Office 310 Restroom                 | yes                               | Floor          | N/A                     | N/A                     | None                               | 0             | No                        | no                            |   |
| 5400  | 1       | 3     | 309     | Classroom 309                       | yes                               | W1             | Cracking/Holes/Chipping | Positive                | None                               | 0             | Prior to Repair           | no                            |   |
| 5400  | 1       | 3     | 309     | Classroom 309                       | yes                               | W2             | Chipping/Cracking       | Positive                | None                               | 0             | Prior to Repair           | no                            |   |
| 5400  | 1       | 3     | 309     | Classroom 309                       | yes                               | W3             | Flaking/Chipping        | Positive                | None                               | 0             | Prior to Repair           | no                            |   |
| 5400  | 1       | 3     | 309     | Classroom 309                       | yes                               | W4             | Chipping/Cracking/Holes | Positive                | None                               | 0             | Prior to Repair           | no                            |   |
| 5400  | 1       | 3     | 309     | Classroom 309                       | yes                               | Ceiling        | Moisture Damage/Flakin  | Positive                | None                               | 0             | No                        | no                            |   |
| 5400  | 1       | 3     | 309     | Classroom 309                       | yes                               | Floor          | N/A                     | N/A                     | None                               | 0             | No                        | no                            |   |
| 5400  | 1       | 3     | 309A    | Classroom 309 Closet                | yes                               | W1             | No Access               | No Access               | No Access                          | No Access     | No Access                 | No Access                     |   |
| 5400  | 1       | 3     | 309A    | Classroom 309 Closet                | yes                               | W2             | No Access               | No Access               | No Access                          | No Access     | No Access                 | No Access                     |   |
| 5400  | 1       | 3     | 309A    | Classroom 309 Closet                | yes                               | W3             | No Access               | No Access               | No Access                          | No Access     | No Access                 | No Access                     |   |

| ULCS# | Element | Floor | Space # | On-Site Room Name  | Student/Teacher Occupied (yes/no) | Component        | Description of Damage   | XRF (positive/negative) | Debris Present (describe location) | Quantity (sf) | Contents Need to be Moved | Plastering Needed (yes or no) | Comments/ Description/ Notes |
|-------|---------|-------|---------|--|-----------------------------------|------------------|-------------------------|-------------------------|------------------------------------|---------------|---------------------------|-------------------------------|------------------------------|
| 5400  | 1       | 3     | 309A    | Classroom 309 Closet                                       | yes                               | W4               | No Access               | No Access               | No Access                          | No Access     | No Access                 | No Access                     |                              |
| 5400  | 1       | 3     | 309A    | Classroom 309 Closet                                       | yes                               | Ceiling          | No Access               | No Access               | No Access                          | 0             | No                        | no                            |                              |
| 5400  | 1       | 3     | 309A    | Classroom 309 Closet                                       | yes                               | Floor            | No Access               | No Access               | No Access                          | 0             | No                        | no                            |                              |
| 5400  | 1       | 3     | S32     | Stairwell across from Classroom 304                        | yes                               | W1               | None                    | N/A                     | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 3     | S32     | Stairwell across from Classroom 304                        | yes                               | Door             | Friction                | Negative                | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 3     | S32     | Stairwell across from Classroom 304                        | yes                               | Door Frame       | Friction                | Negative                | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 3     | S32     | Stairwell across from Classroom 304                        | yes                               | W2               | None                    | N/A                     | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 3     | S32     | Stairwell across from Classroom 304                        | yes                               | W3               | Moisture Damage         | Positive                | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 3     | S32     | Stairwell across from Classroom 304                        | yes                               | Radiator Cover   | Friction                | Negative                | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 3     | S32     | Stairwell across from Classroom 304                        | yes                               | W4               | Moisture Damage/Flaking | Positive                | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 3     | S32     | Stairwell across from Classroom 304                        | yes                               | Ceiling          | None                    | N/A                     | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 3     | S32     | Stairwell across from Classroom 304                        | yes                               | Floor            | N/A                     | N/A                     | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 3     | S32     | Stairwell across from Classroom 304                        | yes                               | Stair Riser      | Friction                | Negative                | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 3     | S32     | Stairwell across from Classroom 304                        | yes                               | Stair Stringer   | Friction                | Negative                | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 3     | S32     | Stairwell across from Classroom 304                        | yes                               | Stair Tred       | Friction                | Negative                | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 3     | S32     | Stairwell across from Classroom 304                        | yes                               | Newel Post       | Friction                | Positive                | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 3     | S32     | Stairwell across from Classroom 304                        | yes                               | Ballast          | Friction                | Positive                | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | B     | S04     | Girl's Side Yard Exit Vestibule                            | yes                               | W1               | None                    | N/A                     | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | B     | S04     | Girl's Side Yard Exit Vestibule                            | yes                               | Door             | Friction                | Negative                | None                               | 0             | Prior to Repair           | no                            |                              |
| 5400  | 1       | B     | S04     | Girl's Side Yard Exit Vestibule                            | yes                               | Door Frame       | Friction                | Negative                | None                               | 0             | Prior to Repair           | no                            |                              |
| 5400  | 1       | B     | S04     | Girl's Side Yard Exit Vestibule                            | yes                               | W2               | None                    | N/A                     | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | B     | S04     | Girl's Side Yard Exit Vestibule                            | yes                               | W3               | None                    | N/A                     | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | B     | S04     | Girl's Side Yard Exit Vestibule                            | yes                               | Door             | Friction                | Negative                | None                               | 0             | Prior to Repair           | no                            |                              |
| 5400  | 1       | B     | S04     | Girl's Side Yard Exit Vestibule                            | yes                               | Door Frame       | Friction                | Negative                | None                               | 0             | Prior to Repair           | no                            |                              |
| 5400  | 1       | B     | S04     | Girl's Side Yard Exit Vestibule                            | yes                               | W4               | None                    | N/A                     | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | B     | S04     | Girl's Side Yard Exit Vestibule                            | yes                               | Ceiling          | None                    | N/A                     | None                               | 0             | Prior to Repair           | no                            |                              |
| 5400  | 1       | B     | S04     | Girl's Side Yard Exit Vestibule                            | yes                               | Floor            | Chipping                | Negative                | None                               | 0             | Prior to Repair           | no                            |                              |
| 5400  | 1       | B     | H01     | Girl's Side Hallway  | yes                               | W1               | Alligatoring, chipping  | Positive                | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | B     | H01     | Girl's Side Hallway  | yes                               | W2               | Chipping                | Positive                | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | B     | H01     | Girl's Side Hallway  | yes                               | W3               | None                    | N/A                     | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | B     | H01     | Girl's Side Hallway  | yes                               | Door             | Friction                | Negative                | None                               | 0             | Prior to Repair           | no                            |                              |
| 5400  | 1       | B     | H01     | Girl's Side Hallway  | yes                               | Door Frame       | Friction                | Negative                | None                               | 0             | Prior to Repair           | no                            |                              |
| 5400  | 1       | B     | H01     | Girl's Side Hallway  | yes                               | W4               | Flaking                 | Positive                | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | B     | H01     | Girl's Side Hallway  | yes                               | Door             | Friction, Flaking       | Positive                | None                               | 0             | Prior to Repair           | no                            |                              |
| 5400  | 1       | B     | H01     | Girl's Side Hallway  | yes                               | Door Frame       | Friction, Flaking       | Negative                | None                               | 0             | Prior to Repair           | no                            |                              |
| 5400  | 1       | B     | H01     | Girl's Side Hallway  | yes                               | pipe             | Chipping                | Positive                | None                               | 0             | Prior to Repair           | no                            |                              |
| 5400  | 1       | B     | H01     | Girl's Side Hallway  | yes                               | electrical panel | Chipping                | Negative                | None                               | 0             | Prior to Repair           | no                            |                              |
| 5400  | 1       | B     | H01     | Girl's Side Hallway  | yes                               | Duct             | Chipping                | Positive                | None                               | 0             | Prior to Repair           | no                            |                              |
| 5400  | 1       | B     | H01     | Girl's Side Hallway  | yes                               | Ceiling          | Efflorescence, Flaking  | Positive                | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | B     | H01     | Girl's Side Hallway  | yes                               | Floor            | Chipping                | Negative                | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | B     | H01     | Girl's Side Hallway  | yes                               | Tread            | Friction                | Positive                | None                               | 0             | Prior to Repair           | no                            |                              |
| 5400  | 1       | B     | H01     | Girl's Side Hallway  | yes                               | Riser            | Friction                | Positive                | None                               | 0             | Prior to Repair           | no                            |                              |
| 5400  | 1       | B     | H01     | Girl's Side Hallway  | yes                               | Handrail         | Friction                | Negative                | None                               | 0             | Prior to Repair           | no                            |                              |
| 5400  | 1       | B     | 1       | Hallway Closet adjacent to Girl's Side Yard Exit Vestibule | no                                | W1               | No Access               | No Access               | No Access                          | No Access     | No Access                 | No Access                     |                              |
| 5400  | 1       | B     | 1       | Hallway Closet adjacent to Girl's Side Yard Exit Vestibule | no                                | W2               | No Access               | No Access               | No Access                          | No Access     | No Access                 | No Access                     |                              |
| 5400  | 1       | B     | 1       | Hallway Closet adjacent to Girl's Side Yard Exit Vestibule | no                                | W3               | No Access               | No Access               | No Access                          | No Access     | No Access                 | No Access                     |                              |
| 5400  | 1       | B     | 1       | Hallway Closet adjacent to Girl's Side Yard Exit Vestibule | no                                | W4               | No Access               | No Access               | No Access                          | No Access     | No Access                 | No Access                     |                              |

| ULCS# | Element | Floor | Space # | On-Site Room Name   | Student/Teacher Occupied (yes/no) | Component | Description of Damage  | XRF (positive/negative) | Debris Present (describe location) | Quantity (sf) | Contents Need to be Moved | Plastering Needed (yes or no) | Comments/ Description/ Notes |
|-------|---------|-------|---------|---|-----------------------------------|-----------|------------------------|-------------------------|------------------------------------|---------------|---------------------------|-------------------------------|------------------------------|
| 5400  | 1       | B     | 1       | Hallway Closet adjacent to Girl's Side Yard Exit Vestibule      | no                                | Ceiling   | No Access              | No Access               | No Access                          | No Access     | No Access                 | No Access                     |                              |
| 5400  | 1       | B     | 1       | Hallway Closet adjacent to Girl's Side Yard Exit Vestibule      | no                                | Floor     | No Access              | No Access               | No Access                          | No Access     | No Access                 | No Access                     |                              |
| 5400  | 1       | B     | 2A      | Hallway Closet next to Girl's Restroom                          | no                                | W1        | No Access              | No Access               | No Access                          | No Access     | No Access                 | No Access                     |                              |
| 5400  | 1       | B     | 2A      | Hallway Closet next to Girl's Restroom                          | no                                | W2        | No Access              | No Access               | No Access                          | No Access     | No Access                 | No Access                     |                              |
| 5400  | 1       | B     | 2A      | Hallway Closet next to Girl's Restroom                          | no                                | W3        | No Access              | No Access               | No Access                          | No Access     | No Access                 | No Access                     |                              |
| 5400  | 1       | B     | 2A      | Hallway Closet next to Girl's Restroom                          | no                                | W4        | No Access              | No Access               | No Access                          | No Access     | No Access                 | No Access                     |                              |
| 5400  | 1       | B     | 2A      | Hallway Closet next to Girl's Restroom                          | no                                | Ceiling   | No Access              | No Access               | No Access                          | No Access     | No Access                 | No Access                     |                              |
| 5400  | 1       | B     | 2A      | Hallway Closet next to Girl's Restroom                          | no                                | Floor     | No Access              | No Access               | No Access                          | No Access     | No Access                 | No Access                     |                              |
| 5400  | 1       | B     | 2       | Girl's Restroom   | yes                               | W1        | None                   | N/A                     | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | B     | 2       | Girl's Restroom   | yes                               | W2        | None                   | N/A                     | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | B     | 2       | Girl's Restroom   | yes                               | W3        | None                   | N/A                     | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | B     | 2       | Girl's Restroom   | yes                               | W4        | None                   | N/A                     | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | B     | 2       | Girl's Restroom   | yes                               | Ceiling   | None                   | N/A                     | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | B     | 2       | Girl's Restroom   | yes                               | Radiator  | Flaking                | Positive                | None                               | 0             | Prior to Repair           | no                            |                              |
| 5400  | 1       | B     | 2       | Girl's Restroom   | yes                               | Floor     | None                   | N/A                     | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | B     | 3       | Classroom A1  | yes                               | W1        | Chipping               | Positive                | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | B     | 3       | Classroom A1  | yes                               | Baseboard | Friction               | Positive                | None                               | 0             | Prior to Repair           | no                            |                              |
| 5400  | 1       | B     | 3       | Classroom A1  | yes                               | W2        | Chipping               | Positive                | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | B     | 3       | Classroom A1  | yes                               | Baseboard | Friction               | Positive                | None                               | 0             | Prior to Repair           | no                            |                              |
| 5400  | 1       | B     | 3       | Classroom A1  | yes                               | W3        | None                   | N/A                     | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | B     | 3       | Classroom A1  | yes                               | Baseboard | Friction               | Positive                | None                               | 0             | Prior to Repair           | no                            |                              |
| 5400  | 1       | B     | 3       | Classroom A1  | yes                               | Pipe      | Chipping               | Positive                | None                               | 0             | Prior to Repair           | no                            |                              |
| 5400  | 1       | B     | 3       | Classroom A1  | yes                               | W4        | None                   | N/A                     | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | B     | 3       | Classroom A1  | yes                               | Baseboard | Friction               | Negative                | None                               | 0             | Prior to Repair           | no                            |                              |
| 5400  | 1       | B     | 3       | Classroom A1  | yes                               | Ceiling   | Alligatoring, chipping | Positive                | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | B     | 3       | Classroom A1  | yes                               | Floor     | N/A                    | N/A                     | None                               | 0             | No                        | no                            | Floor tile                   |
| 5400  | 1       | B     | 003A    | Classroom A1 Closet   | yes                               | W1        | No Access              | No Access               | No Access                          | No Access     | No Access                 | No Access                     |                              |
| 5400  | 1       | B     | 003A    | Classroom A1 Closet   | yes                               | W2        | No Access              | No Access               | No Access                          | No Access     | No Access                 | No Access                     | Padlock, no teacher          |
| 5400  | 1       | B     | 003A    | Classroom A1 Closet   | yes                               | W3        | No Access              | No Access               | No Access                          | No Access     | No Access                 | No Access                     |                              |
| 5400  | 1       | B     | 003A    | Classroom A1 Closet   | yes                               | W4        | No Access              | No Access               | No Access                          | No Access     | No Access                 | No Access                     |                              |
| 5400  | 1       | B     | 003A    | Classroom A1 Closet   | yes                               | Ceiling   | No Access              | No Access               | No Access                          | No Access     | No Access                 | No Access                     |                              |
| 5400  | 1       | B     | 003A    | Classroom A1 Closet   | yes                               | Floor     | No Access              | No Access               | No Access                          | No Access     | No Access                 | No Access                     |                              |
| 5400  | 1       | B     | 4       | Fan Room  | no                                | W1        | No Access              | No Access               | No Access                          | No Access     | No Access                 | No Access                     |                              |
| 5400  | 1       | B     | 4       | Fan Room  | no                                | W2        | No Access              | No Access               | No Access                          | No Access     | No Access                 | No Access                     |                              |
| 5400  | 1       | B     | 4       | Fan Room  | no                                | W3        | No Access              | No Access               | No Access                          | No Access     | No Access                 | No Access                     |                              |
| 5400  | 1       | B     | 4       | Fan Room  | no                                | W4        | No Access              | No Access               | No Access                          | No Access     | No Access                 | No Access                     |                              |
| 5400  | 1       | B     | 4       | Fan Room  | no                                | Ceiling   | No Access              | No Access               | No Access                          | No Access     | No Access                 | No Access                     |                              |
| 5400  | 1       | B     | 4       | Fan Room  | no                                | Floor     | No Access              | No Access               | No Access                          | No Access     | No Access                 | No Access                     |                              |
| 5400  | 1       | B     | H03A    | Hallway Closet off Hallway from Boiler Room to Girl's Side Hall | no                                | W1        | No Access              | No Access               | No Access                          | No Access     | No Access                 | No Access                     |                              |
| 5400  | 1       | B     | H03A    | Hallway Closet off Hallway from Boiler Room to Girl's Side Hall | no                                | W2        | No Access              | No Access               | No Access                          | No Access     | No Access                 | No Access                     |                              |
| 5400  | 1       | B     | H03A    | Hallway Closet off Hallway from Boiler Room to Girl's Side Hall | no                                | W3        | No Access              | No Access               | No Access                          | No Access     | No Access                 | No Access                     |                              |
| 5400  | 1       | B     | H03A    | Hallway Closet off Hallway from Boiler Room to Girl's Side Hall | no                                | W4        | No Access              | No Access               | No Access                          | No Access     | No Access                 | No Access                     |                              |
| 5400  | 1       | B     | H03A    | Hallway Closet off Hallway from Boiler Room to Girl's Side Hall | no                                | Ceiling   | No Access              | No Access               | No Access                          | No Access     | No Access                 | No Access                     |                              |
| 5400  | 1       | B     | H03A    | Hallway Closet off Hallway from Boiler Room to Girl's Side Hall | no                                | Floor     | No Access              | No Access               | No Access                          | No Access     | No Access                 | No Access                     |                              |
| 5400  | 1       | B     | H03     | Hallway from Boiler Room to Girl's Side Hall                    | yes                               | W1        | Flaking                | Positive                | None                               | 0             | Prior to Repair           | no                            |                              |

| ULCS# | Element | Floor | Space # | On-Site Room Name                                   | Student/Teacher Occupied (yes/no) | Component  | Description of Damage | XRF (positive/negative) | Debris Present (describe location) | Quantity (sf) | Contents Need to be Moved | Plastering Needed (yes or no) | Comments/ Description/ Notes |
|-------|---------|-------|---------|---|-----------------------------------|------------|-----------------------|-------------------------|------------------------------------|---------------|---------------------------|-------------------------------|------------------------------|
| 5400  | 1       | B     | H03     | Hallway from Boiler Room to Girl's Side Hall        | yes                               | W2         | Flaking               | Positive                | None                               | 0             | Prior to Repair           | no                            |                              |
| 5400  | 1       | B     | H03     | Hallway from Boiler Room to Girl's Side Hall        | yes                               | W3         | Flaking               | Positive                | None                               | 0             | Prior to Repair           | no                            |                              |
| 5400  | 1       | B     | H03     | Hallway from Boiler Room to Girl's Side Hall        | yes                               | W4         | Flaking               | Positive                | None                               | 0             | Prior to Repair           | no                            |                              |
| 5400  | 1       | B     | H03     | Hallway from Boiler Room to Girl's Side Hall        | yes                               | pipe       | Flaking               | Positive                | None                               | 0             | Prior to Repair           | no                            |                              |
| 5400  | 1       | B     | H03     | Hallway from Boiler Room to Girl's Side Hall        | yes                               | Ceiling    | Flaking               | Positive                | None                               | 0             | Prior to Repair           | no                            |                              |
| 5400  | 1       | B     | H03     | Hallway from Boiler Room to Girl's Side Hall        | yes                               | Floor      | Chipping              | Positive                | Floor                              | 40            | Prior to Repair           | no                            |                              |
| 5400  | 1       | B     | H03     | Hallway from Boiler Room to Girl's Side Hall        | yes                               | tread      | Friction              | Positive                | None                               | 0             | Prior to Repair           | no                            |                              |
| 5400  | 1       | B     | H03     | Hallway from Boiler Room to Girl's Side Hall        | yes                               | riser      | Friction              | Positive                | None                               | 0             | Prior to Repair           | no                            |                              |
| 5400  | 1       | B     | H03     | Hallway from Boiler Room to Girl's Side Hall        | yes                               | handrail   | Friction              | Positive                | None                               | 0             | Prior to Repair           | no                            |                              |
| 5400  | 1       | B     | 6       | Boiler Room   | no                                | W1         | Flaking               | Positive                | None                               | 0             | Prior to Repair           | no                            |                              |
| 5400  | 1       | B     | 6       | Boiler Room   | no                                | W2         | Flaking               | Positive                | None                               | 0             | Prior to Repair           | no                            |                              |
| 5400  | 1       | B     | 6       | Boiler Room   | no                                | W3         | Flaking               | Positive                | None                               | 0             | Prior to Repair           | no                            |                              |
| 5400  | 1       | B     | 6       | Boiler Room   | no                                | W4         | Flaking               | Positive                | None                               | 0             | Prior to Repair           | no                            |                              |
| 5400  | 1       | B     | 6       | Boiler Room   | no                                | Ceiling    | Flaking               | Positive                | None                               | 0             | Prior to Repair           | no                            |                              |
| 5400  | 1       | B     | 6       | Boiler Room   | no                                | Floor      | N/A                   | N/A                     | N/A                                | N/A           | N/A                       | N/A                           | Unpainted                    |
| 5400  | 1       | B     | 5       | Tank Room/Building Engineer's Office Area           | no                                | W1         | Flaking               | Positive                | None                               | 0             | Prior to Repair           | no                            |                              |
| 5400  | 1       | B     | 5       | Tank Room/Building Engineer's Office Area           | no                                | W2         | Flaking/Moisure       | Positive                | None                               | 0             | Prior to Repair           | no                            |                              |
| 5400  | 1       | B     | 5       | Tank Room/Building Engineer's Office Area           | no                                | W3         | None                  | N/A                     | None                               | 0             | Prior to Repair           | no                            |                              |
| 5400  | 1       | B     | 5       | Tank Room/Building Engineer's Office Area           | no                                | W4         | Flaking               | Positive                | None                               | 0             | Prior to Repair           | no                            |                              |
| 5400  | 1       | B     | 5       | Tank Room/Building Engineer's Office Area           | no                                | Ceiling    | Flaking               | Positive                | None                               | 0             | Prior to Repair           | no                            |                              |
| 5400  | 1       | B     | 5       | Tank Room/Building Engineer's Office Area           | no                                | Floor      | Friction              | Negative                | None                               | 0             | Prior to Repair           | no                            |                              |
| 5400  | 1       | B     | 7       | Emergency Generator Room                            | no                                | W1         | Flaking               | Negative                | None                               | 0             | Prior to Repair           | no                            |                              |
| 5400  | 1       | B     | 7       | Emergency Generator Room                            | no                                | W2         | Flaking               | Negative                | None                               | 0             | Prior to Repair           | no                            |                              |
| 5400  | 1       | B     | 7       | Emergency Generator Room                            | no                                | W3         | Flaking               | Negative                | None                               | 0             | Prior to Repair           | no                            |                              |
| 5400  | 1       | B     | 7       | Emergency Generator Room                            | no                                | W4         | Flaking               | Negative                | None                               | 0             | Prior to Repair           | no                            |                              |
| 5400  | 1       | B     | 7       | Emergency Generator Room                            | no                                | Ceiling    | N/A                   | N/A                     | N/A                                | N/A           | N/A                       | N/A                           | Unpainted                    |
| 5400  | 1       | B     | 7       | Emergency Generator Room                            | no                                | Floor      | N/A                   | N/A                     | N/A                                | N/A           | N/A                       | N/A                           | Unpainted                    |
| 5400  | 1       | B     | 06A     | Hallway from Boiler Room to Gym/Cafe                | yes                               | W1         | None                  | N/A                     | None                               | 0             | Prior to Repair           | no                            |                              |
| 5400  | 1       | B     | 06A     | Hallway from Boiler Room to Gym/Cafe                | yes                               | W2         | None                  | N/A                     | None                               | 0             | Prior to Repair           | no                            |                              |
| 5400  | 1       | B     | 06A     | Hallway from Boiler Room to Gym/Cafe                | yes                               | W3         | None                  | N/A                     | None                               | 0             | Prior to Repair           | no                            |                              |
| 5400  | 1       | B     | 06A     | Hallway from Boiler Room to Gym/Cafe                | yes                               | door       | Friction              | Positive                | None                               | 0             | Prior to Repair           | no                            |                              |
| 5400  | 1       | B     | 06A     | Hallway from Boiler Room to Gym/Cafe                | yes                               | door frame | Friction              | Negative                | None                               | 0             | Prior to Repair           | no                            |                              |
| 5400  | 1       | B     | 06A     | Hallway from Boiler Room to Gym/Cafe                | yes                               | W4         | None                  | N/A                     | None                               | 0             | Prior to Repair           | no                            |                              |
| 5400  | 1       | B     | 06A     | Hallway from Boiler Room to Gym/Cafe                | yes                               | Ceiling    | N/A                   | N/A                     | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | B     | 06A     | Hallway from Boiler Room to Gym/Cafe                | yes                               | Floor      | N/A                   | N/A                     | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | B     | 06A     | Hallway from Boiler Room to Gym/Cafe                | yes                               | Tread      | Friction              | Negative                | None                               | 0             | Prior to Repair           | no                            |                              |
| 5400  | 1       | B     | 06A     | Hallway from Boiler Room to Gym/Cafe                | yes                               | Riser      | Friction              | Negative                | None                               | 0             | Prior to Repair           | no                            |                              |
| 5400  | 1       | B     | 06A     | Hallway from Boiler Room to Gym/Cafe                | yes                               | Newel Post | Friction              | Positive                | None                               | 0             | Prior to Repair           | no                            |                              |
| 5400  | 1       | B     | 06A     | Hallway from Boiler Room to Gym/Cafe                | yes                               | Ballest    | Friction              | Positive                | None                               | 0             | Prior to Repair           | no                            |                              |
| 5400  | 1       | B     | 06A     | Hallway from Boiler Room to Gym/Cafe                | yes                               | Handrail   | Friction              | Negative                | None                               | 0             | Prior to Repair           | no                            |                              |
| 5400  | 1       | B     | 06A     | Hallway from Boiler Room to Gym/Cafe                | yes                               | Stringer   | Friction              | Negative                | None                               | 0             | Prior to Repair           | no                            |                              |
| 5400  | 1       | B     | 008B    | Hallway Closet between Gym Stairwell & Classroom A2 | no                                | W1         | No Access             | No Access               | No Access                          | No Access     | No Access                 | No Access                     |                              |
| 5400  | 1       | B     | 008B    | Hallway Closet between Gym Stairwell & Classroom A2 | no                                | W2         | No Access             | No Access               | No Access                          | No Access     | No Access                 | No Access                     |                              |
| 5400  | 1       | B     | 008B    | Hallway Closet between Gym Stairwell & Classroom A2 | no                                | W3         | No Access             | No Access               | No Access                          | No Access     | No Access                 | No Access                     |                              |
| 5400  | 1       | B     | 008B    | Hallway Closet between Gym Stairwell & Classroom A2 | no                                | W4         | No Access             | No Access               | No Access                          | No Access     | No Access                 | No Access                     |                              |
| 5400  | 1       | B     | 008B    | Hallway Closet between Gym Stairwell & Classroom A2 | no                                | Ceiling    | No Access             | No Access               | No Access                          | No Access     | No Access                 | No Access                     |                              |
| 5400  | 1       | B     | 008B    | Hallway Closet between Gym Stairwell & Classroom A2 | no                                | Floor      | No Access             | No Access               | No Access                          | No Access     | No Access                 | No Access                     |                              |

| ULCS# | Element | Floor | Space # | On-Site Room Name                             | Student/Teacher Occupied (yes/no) | Component   | Description of Damage    | XRF (positive/negative) | Debris Present (describe location) | Quantity (sf) | Contents Need to be Moved | Plastering Needed (yes or no) | Comments/ Description/ Notes |
|-------|---------|-------|---------|---|-----------------------------------|-------------|--------------------------|-------------------------|------------------------------------|---------------|---------------------------|-------------------------------|------------------------------|
| 5400  | 1       | B     | 8       | Classroom A2                                  | yes                               | W1          | Flaking                  | Positive                | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | B     | 8       | Classroom A2                                  | yes                               | W2          | None                     | N/A                     | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | B     | 8       | Classroom A2                                  | yes                               | Pipe Casing | Flaking                  | Positive                | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | B     | 8       | Classroom A2                                  | yes                               | W3          | Efflorescence, Flaking   | Positive                | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | B     | 8       | Classroom A2                                  | yes                               | Pipe Casing | Flaking                  | Positive                | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | B     | 8       | Classroom A2                                  | yes                               | W4          | None                     | N/A                     | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | B     | 8       | Classroom A2                                  | yes                               | Ceiling     | Moisture Damage, flaking | Positive                | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | B     | 8       | Classroom A2                                  | yes                               | Floor       | none                     | N/A                     | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | B     | 008A    | Classroom A2 Restroom                         | yes                               | W1          | Efflorescence, Flaking   | Positive                | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | B     | 008A    | Classroom A2 Restroom                         | yes                               | W2          | None                     | N/A                     | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | 008A    | Classroom A2 Restroom                         | yes                               | Pipe casing | Flaking                  | Positive                | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | B     | 008A    | Classroom A2 Restroom                         | yes                               | W3          | None                     | N/A                     | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | B     | 008A    | Classroom A2 Restroom                         | yes                               | W4          | None                     | N/A                     | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | B     | 008A    | Classroom A2 Restroom                         | yes                               | Ceiling     | Moisture Damage, flaking | Positive                | None                               | 0             | Prior to Repair           | yes                           |                              |
| 5400  | 1       | B     | 008A    | Classroom A2 Restroom                         | yes                               | Floor       | none                     | N/A                     | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | B     | 008C    | Classroom A2 Office                           | yes                               | W1          | None                     | N/A                     | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | B     | 008C    | Classroom A2 Office                           | yes                               | W2          | None                     | No Access               | No Access                          | No Access     | No Access                 | No Access                     |                              |
| 5400  | 1       | B     | 008C    | Classroom A2 Office                           | yes                               | W3          | None                     | No Access               | No Access                          | No Access     | No Access                 | No Access                     |                              |
| 5400  | 1       | B     | 008C    | Classroom A2 Office                           | yes                               | W4          | None                     | N/A                     | None                               | 0             | Partially Inaccessible    | no                            |                              |
| 5400  | 1       | B     | 008C    | Classroom A2 Office                           | yes                               | Ceiling     | Flaking                  | Positive                | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | B     | 008C    | Classroom A2 Office                           | yes                               | Floor       | none                     | N/A                     | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | B     | 16      | Classroom A2 Closet                           | yes                               | W1          | Flaking                  | Positive                | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | B     | 16      | Classroom A2 Closet                           | yes                               | W2          | Flaking                  | Positive                | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | B     | 16      | Classroom A2 Closet                           | yes                               | W3          | Flaking                  | Positive                | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | B     | 16      | Classroom A2 Closet                           | yes                               | W4          | Flaking                  | Positive                | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | B     | 16      | Classroom A2 Closet                           | yes                               | Ceiling     | Flaking                  | Positive                | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | B     | 16      | Classroom A2 Closet                           | yes                               | Floor       | None                     | N/A                     | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | B     | 9       | Boy's Restroom                                | yes                               | W1          | None                     | N/A                     | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | B     | 9       | Boy's Restroom                                | yes                               | W2          | None                     | N/A                     | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | B     | 9       | Boy's Restroom                                | yes                               | W3          | None                     | N/A                     | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | B     | 9       | Boy's Restroom                                | yes                               | W4          | None                     | N/A                     | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | B     | 9       | Boy's Restroom                                | yes                               | Ceiling     | None                     | N/A                     | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | B     | 9       | Boy's Restroom                                | yes                               | Floor       | Chipping                 | Negative                | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | B     | 009A    | Custodial Storage next to Boy's Restroom      | no                                | W1          | No Access                | No Access               | No Access                          | No Access     | No Access                 | No Access                     |                              |
| 5400  | 1       | B     | 009A    | Custodial Storage next to Boy's Restroom      | no                                | W2          | No Access                | No Access               | No Access                          | No Access     | No Access                 | No Access                     |                              |
| 5400  | 1       | B     | 009A    | Custodial Storage next to Boy's Restroom      | no                                | W3          | No Access                | No Access               | No Access                          | No Access     | No Access                 | No Access                     |                              |
| 5400  | 1       | B     | 009A    | Custodial Storage next to Boy's Restroom      | no                                | W4          | No Access                | No Access               | No Access                          | No Access     | No Access                 | No Access                     |                              |
| 5400  | 1       | B     | 009A    | Custodial Storage next to Boy's Restroom      | no                                | Ceiling     | No Access                | No Access               | No Access                          | No Access     | No Access                 | No Access                     |                              |
| 5400  | 1       | B     | 009A    | Custodial Storage next to Boy's Restroom      | no                                | Floor       | No Access                | No Access               | No Access                          | No Access     | No Access                 | No Access                     |                              |
| 5400  | 1       | B     | 10      | Custodial Restroom adjacent Custodial Storage | no                                | W1          | Flaking                  | Positive                | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | 10      | Custodial Restroom adjacent Custodial Storage | no                                | pipe        | Flaking                  | Positive                | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | B     | 10      | Custodial Restroom adjacent Custodial Storage | no                                | W2          | Flaking                  | Positive                | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | B     | 10      | Custodial Restroom adjacent Custodial Storage | no                                | W3          | Flaking                  | Positive                | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | B     | 10      | Custodial Restroom adjacent Custodial Storage | no                                | W4          | Flaking                  | Positive                | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | B     | 10      | Custodial Restroom adjacent Custodial Storage | no                                | Ceiling     | Flaking                  | Positive                | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | 10      | Custodial Restroom adjacent Custodial Storage | no                                | radiator    | Flaking                  | Positive                | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | B     | 10      | Custodial Restroom adjacent Custodial Storage | no                                | Floor       | None                     | N/A                     | Floor                              | 40            | Prior to Repair           | no                            |                              |
| 5400  | 1       | B     | S03     | Boy's Side Yard Exit Vestibule                | yes                               | W1          | None                     | N/A                     | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | S03     | Boy's Side Yard Exit Vestibule                | yes                               | Door        | Friction                 | Negative                | None                               | 0             | No                        | no                            |                              |

| ULCS# | Element | Floor | Space # | On-Site Room Name                   | Student/Teacher Occupied (yes/no) | Component  | Description of Damage | XRF (positive/negative) | Debris Present (describe location) | Quantity (sf) | Contents Need to be Moved | Plastering Needed (yes or no) | Comments/ Description/ Notes |
|-------|---------|-------|---------|-------------------------------------|-----------------------------------|------------|-----------------------|-------------------------|------------------------------------|---------------|---------------------------|-------------------------------|------------------------------|
| 5400  | 1       | 1     | S03     | Boy's Side Yard Exit Vestibule      | yes                               | Door Frame | Friction              | Negative                | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | B     | S03     | Boy's Side Yard Exit Vestibule      | yes                               | W2         | None                  | N/A                     | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | B     | S03     | Boy's Side Yard Exit Vestibule      | yes                               | W3         | None                  | N/A                     | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | S03     | Boy's Side Yard Exit Vestibule      | yes                               | Door       | Friction              | Negative                | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | S03     | Boy's Side Yard Exit Vestibule      | yes                               | Door Frame | Friction              | Negative                | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | B     | S03     | Boy's Side Yard Exit Vestibule      | yes                               | W4         | None                  | N/A                     | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | B     | S03     | Boy's Side Yard Exit Vestibule      | yes                               | Ceiling    | None                  | N/A                     | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | B     | S03     | Boy's Side Yard Exit Vestibule      | yes                               | Floor      | Chipping              | Negative                | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | B     | H02     | Boy's Side Hallway                  | yes                               | W1         | None                  | N/A                     | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | B     | H02     | Boy's Side Hallway                  | yes                               | W2         | None                  | N/A                     | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | B     | H02     | Boy's Side Hallway                  | yes                               | W3         | None                  | N/A                     | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | H02     | Boy's Side Hallway                  | yes                               | Door       | Friction              | Negative                | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | H02     | Boy's Side Hallway                  | yes                               | Door Frame | Friction              | Negative                | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | B     | H02     | Boy's Side Hallway                  | yes                               | W4         | None                  | n/a                     | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | B     | H02     | Boy's Side Hallway                  | yes                               | Ceiling    | Chipping/Flaking      | Positive                | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | H02     | Boy's Side Hallway                  | yes                               | Duct       | Flaking               | Positive                | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | B     | H02     | Boy's Side Hallway                  | yes                               | Floor      | None                  | N/A                     | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | B     | H02     | Boy's Side Hallway                  | yes                               | tread      | Friction              | Positive                | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | B     | H02     | Boy's Side Hallway                  | yes                               | riser      | Friction              | Positive                | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | B     | H02     | Boy's Side Hallway                  | yes                               | handrail   | Friction              | Positive                | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | B     | S01     | Boy's Side Gym Stairwell            | yes                               | W1         | None                  | N/A                     | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | B     | S01     | Boy's Side Gym Stairwell            | yes                               | W2         | None                  | N/A                     | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | B     | S01     | Boy's Side Gym Stairwell            | yes                               | W3         | None                  | N/A                     | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | B     | S01     | Boy's Side Gym Stairwell            | yes                               | door       | Friction              | Positive                | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | B     | S01     | Boy's Side Gym Stairwell            | yes                               | door frame | Friction              | Negative                | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | B     | S01     | Boy's Side Gym Stairwell            | yes                               | W4         | None                  | N/A                     | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | B     | S01     | Boy's Side Gym Stairwell            | yes                               | Ceiling    | None                  | N/A                     | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | B     | S01     | Boy's Side Gym Stairwell            | yes                               | Floor      | N/A                   | N/A                     | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | B     | S01     | Boy's Side Gym Stairwell            | yes                               | Tread      | Friction              | Negative                | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | B     | S01     | Boy's Side Gym Stairwell            | yes                               | Riser      | Friction              | Negative                | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | B     | S01     | Boy's Side Gym Stairwell            | yes                               | Newel Post | Friction              | Positive                | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | B     | S01     | Boy's Side Gym Stairwell            | yes                               | Ballest    | Friction              | Positive                | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | B     | S01     | Boy's Side Gym Stairwell            | yes                               | Handrail   | Friction              | Negative                | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | B     | S01     | Boy's Side Gym Stairwell            | yes                               | Stringer   | Friction              | Negative                | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | B     | S01A    | Closet off Boy's Side Gym Stairwell | no                                | W1         | No Access             | No Access               | No Access                          | No Access     | No Access                 | No Access                     |                              |
| 5400  | 1       | B     | S01A    | Closet off Boy's Side Gym Stairwell | no                                | W2         | No Access             | No Access               | No Access                          | No Access     | No Access                 | No Access                     |                              |
| 5400  | 1       | B     | S01A    | Closet off Boy's Side Gym Stairwell | no                                | W3         | No Access             | No Access               | No Access                          | No Access     | No Access                 | No Access                     |                              |
| 5400  | 1       | B     | S01A    | Closet off Boy's Side Gym Stairwell | no                                | W4         | No Access             | No Access               | No Access                          | No Access     | No Access                 | No Access                     |                              |
| 5400  | 1       | B     | S01A    | Closet off Boy's Side Gym Stairwell | no                                | Ceiling    | No Access             | No Access               | No Access                          | No Access     | No Access                 | No Access                     |                              |
| 5400  | 1       | B     | S01A    | Closet off Boy's Side Gym Stairwell | no                                | Floor      | No Access             | No Access               | No Access                          | No Access     | No Access                 | No Access                     |                              |
| 5400  | 1       | B     | 11      | Gymnasium/Cafeteria                 | yes                               | W1         | None                  | N/A                     | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | B     | 11      | Gymnasium/Cafeteria                 | yes                               | Door       | Friction              | Negative                | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | B     | 11      | Gymnasium/Cafeteria                 | yes                               | Door frame | Friction              | Negative                | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | B     | 11      | Gymnasium/Cafeteria                 | yes                               | W2         | Flaking               | Positive                | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | B     | 11      | Gymnasium/Cafeteria                 | yes                               | W3         | Flaking               | Positive                | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | B     | 11      | Gymnasium/Cafeteria                 | yes                               | Door       | Friction              | Negative                | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | B     | 11      | Gymnasium/Cafeteria                 | yes                               | Door frame | Friction              | Negative                | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | B     | 11      | Gymnasium/Cafeteria                 | yes                               | W4         | Flaking               | Positive                | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | B     | 11      | Gymnasium/Cafeteria                 | yes                               | Door       | Friction              | Negative                | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | B     | 11      | Gymnasium/Cafeteria                 | yes                               | Door frame | Friction              | Negative                | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | B     | 11      | Gymnasium/Cafeteria                 | yes                               | Ceiling    | None                  | N/A                     | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | B     | 11      | Gymnasium/Cafeteria                 | yes                               | Floor      | N/A                   | n/a                     | n/a                                | 0             | No                        | no                            | Floor tile                   |

| ULCS# | Element | Floor | Space # | On-Site Room Name                           | Student/Teacher Occupied (yes/no) | Component    | Description of Damage     | XRF (positive/negative) | Debris Present (describe location) | Quantity (sf) | Contents Need to be Moved | Plastering Needed (yes or no) | Comments/ Description/ Notes |
|-------|---------|-------|---------|---|-----------------------------------|--------------|---------------------------|-------------------------|------------------------------------|---------------|---------------------------|-------------------------------|------------------------------|
| 5400  | 1       | B     | 13      | Cafeteria Storage Room on Boy's Side        | yes                               | W1           | Chipping                  | Negative                | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | B     | 13      | Cafeteria Storage Room on Boy's Side        | yes                               | W2           | Friction, Moisture Damage | Negative                | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | 13      | Cafeteria Storage Room on Boy's Side        | yes                               | Door         | Friction                  | Negative                | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | 1     | 13      | Cafeteria Storage Room on Boy's Side        | yes                               | Door frame   | Friction                  | Negative                | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | B     | 13      | Cafeteria Storage Room on Boy's Side        | yes                               | W3           | None                      | N/A                     | None                               | 0             | No                        | no                            | Unpainted                    |
| 5400  | 1       | B     | 13      | Cafeteria Storage Room on Boy's Side        | yes                               | W4           | Friction, Moisture Damage | Negative                | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | B     | 13      | Cafeteria Storage Room on Boy's Side        | yes                               | Ceiling      | N/A                       | n/a                     | n/a                                | 0             | No                        | no                            | Unpainted                    |
| 5400  | 1       | B     | 13      | Cafeteria Storage Room on Boy's Side        | yes                               | Floor        | N/A                       | n/a                     | n/a                                | 0             | No                        | no                            | Unpainted                    |
| 5400  | 1       | B     | 14      | Gym Equipment Storage                       | yes                               | W1           | No Access                 | No Access               | No Access                          | No Access     | No Access                 | No Access                     |                              |
| 5400  | 1       | B     | 14      | Gym Equipment Storage                       | yes                               | W2           | No Access                 | No Access               | No Access                          | No Access     | No Access                 | No Access                     |                              |
| 5400  | 1       | B     | 14      | Gym Equipment Storage                       | yes                               | W3           | No Access                 | No Access               | No Access                          | No Access     | No Access                 | No Access                     |                              |
| 5400  | 1       | B     | 14      | Gym Equipment Storage                       | yes                               | W4           | No Access                 | No Access               | No Access                          | No Access     | No Access                 | No Access                     |                              |
| 5400  | 1       | B     | 14      | Gym Equipment Storage                       | yes                               | Ceiling      | No Access                 | No Access               | No Access                          | No Access     | No Access                 | No Access                     |                              |
| 5400  | 1       | B     | 14      | Gym Equipment Storage                       | yes                               | Floor        | No Access                 | No Access               | No Access                          | No Access     | No Access                 | No Access                     |                              |
| 5400  | 1       | B     | 15      | Kitchen Office                              | no                                | W1           | No Access                 | No Access               | No Access                          | No Access     | No Access                 | No Access                     |                              |
| 5400  | 1       | B     | 15      | Kitchen Office                              | no                                | W2           | No Access                 | No Access               | No Access                          | No Access     | No Access                 | No Access                     |                              |
| 5400  | 1       | B     | 15      | Kitchen Office                              | no                                | W3           | No Access                 | No Access               | No Access                          | No Access     | No Access                 | No Access                     |                              |
| 5400  | 1       | B     | 15      | Kitchen Office                              | no                                | W4           | No Access                 | No Access               | No Access                          | No Access     | No Access                 | No Access                     |                              |
| 5400  | 1       | B     | 15      | Kitchen Office                              | no                                | Ceiling      | No Access                 | No Access               | No Access                          | No Access     | No Access                 | No Access                     |                              |
| 5400  | 1       | B     | 15      | Kitchen Office                              | no                                | Floor        | No Access                 | No Access               | No Access                          | No Access     | No Access                 | No Access                     |                              |
| 5400  | 1       | B     | 12      | Cafeteria Table Storage Room on Girl's Side | yes                               | W1           | Flaking                   | Positive                | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | B     | 12      | Cafeteria Table Storage Room on Girl's Side | yes                               | W2           | Friction, Moisture Damage | Negative                | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | B     | 12      | Cafeteria Table Storage Room on Girl's Side | yes                               | W3           | None                      | N/A                     | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | B     | 12      | Cafeteria Table Storage Room on Girl's Side | yes                               | W4           | Friction, Moisture Damage | Negative                | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | B     | 12      | Cafeteria Table Storage Room on Girl's Side | yes                               | Ceiling      | N/A                       | n/a                     | n/a                                | 0             | No                        | no                            | Unpainted                    |
| 5400  | 1       | B     | 12      | Cafeteria Table Storage Room on Girl's Side | yes                               | Floor        | N/A                       | n/a                     | n/a                                | 0             | No                        | no                            | Unpainted                    |
| 5400  | 1       | B     | S02     | Girl's side Gym Stairwell                   | yes                               | W1           | None                      | N/A                     | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | B     | S02     | Girl's side Gym Stairwell                   | yes                               | Baseboard    | Chipping                  | Negative                | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | B     | S02     | Girl's side Gym Stairwell                   | yes                               | W2           | None                      | N/A                     | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | B     | S02     | Girl's side Gym Stairwell                   | yes                               | Door         | Friction, Flaking         | Positive                | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | B     | S02     | Girl's side Gym Stairwell                   | yes                               | Door Frame   | Friction, Flaking         | Negative                | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | B     | S02     | Girl's side Gym Stairwell                   | yes                               | Baseboard    | Chipping                  | Negative                | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | B     | S02     | Girl's side Gym Stairwell                   | yes                               | W3           | Chipping, flaking         | Positive                | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | B     | S02     | Girl's side Gym Stairwell                   | yes                               | Baseboard    | Chipping                  | Negative                | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | B     | S02     | Girl's side Gym Stairwell                   | yes                               | Door         | Friction                  | Negative                | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | B     | S02     | Girl's side Gym Stairwell                   | yes                               | Door frame   | Friction                  | Negative                | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | B     | S02     | Girl's side Gym Stairwell                   | yes                               | Window Frame | Friction                  | Negative                | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | B     | S02     | Girl's side Gym Stairwell                   | yes                               | W4           | None                      | N/A                     | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | B     | S02     | Girl's side Gym Stairwell                   | yes                               | Baseboard    | Chipping                  | Negative                | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | B     | S02     | Girl's side Gym Stairwell                   | yes                               | Ceiling      | Flaking                   | Positive                | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | B     | S02     | Girl's side Gym Stairwell                   | yes                               | Floor        | N/A                       | N/A                     | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | B     | S02     | Girl's side Gym Stairwell                   | yes                               | Tread        | Friction                  | Negative                | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | B     | S02     | Girl's side Gym Stairwell                   | yes                               | Riser        | Friction                  | Positive                | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | B     | S02     | Girl's side Gym Stairwell                   | yes                               | Newel Post   | Friction                  | Positive                | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | B     | S02     | Girl's side Gym Stairwell                   | yes                               | Ballest      | Friction                  | Positive                | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | B     | S02     | Girl's side Gym Stairwell                   | yes                               | Handrail     | Friction                  | Positive                | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | B     | S02     | Girl's side Gym Stairwell                   | yes                               | Stringer     | Friction                  | Negative                | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | B     | 014A    | Office off Girl's side Gym Stairwell        | yes                               | W1           | None                      | N/A                     | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | B     | 014A    | Office off Girl's side Gym Stairwell        | yes                               | W2           | None                      | N/A                     | None                               | 0             | No                        | no                            |                              |

| ULCS# | Element | Floor | Space # | On-Site Room Name                    | Student/Teacher Occupied (yes/no) | Component | Description of Damage | XRF (positive/negative) | Debris Present (describe location) | Quantity (sf) | Contents Need to be Moved | Plastering Needed (yes or no) | Comments/ Description/ Notes |
|-------|---------|-------|---------|--------------------------------------|-----------------------------------|-----------|-----------------------|-------------------------|------------------------------------|---------------|---------------------------|-------------------------------|------------------------------|
| 5400  | 1       | B     | 014A    | Office off Girl's side Gym Stairwell | yes                               | W3        | None                  | N/A                     | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | B     | 014A    | Office off Girl's side Gym Stairwell | yes                               | W4        | None                  | N/A                     | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | B     | 014A    | Office off Girl's side Gym Stairwell | yes                               | Ceiling   | None                  | N/A                     | None                               | 0             | No                        | no                            |                              |
| 5400  | 1       | B     | 014A    | Office off Girl's side Gym Stairwell | yes                               | Floor     | Friction              | Negative                | None                               | 0             | No                        | no                            |                              |
| 5400  | 2       | 1     | 1       | Portable Classroom                   | no                                | W1        | None                  | N/A                     | None                               | 0             | No                        | no                            |                              |
| 5400  | 2       | 1     | 1       | Portable Classroom                   | no                                | W2        | Cracking              | Negative                | None                               | 0             | No                        | no                            |                              |
| 5400  | 2       | 1     | 1       | Portable Classroom                   | no                                | W3        | None                  | N/A                     | None                               | 0             | No                        | no                            |                              |
| 5400  | 2       | 1     | 1       | Portable Classroom                   | no                                | W4        | None                  | N/A                     | None                               | 0             | No                        | no                            |                              |
| 5400  | 2       | 1     | 1       | Portable Classroom                   | no                                | Ceiling   | None                  | N/A                     | None                               | 0             | No                        | no                            | drop ceiling                 |
| 5400  | 2       | 1     | 1       | Portable Classroom                   | no                                | Floor     | None                  | N/A                     | None                               | 0             | No                        | no                            | floor tile                   |
| 5400  | 2       | 1     | 1A      | Portable Classroom Restroom          | no                                | W1        | Cracking              | Negative                | None                               | 0             | No                        | no                            |                              |
| 5400  | 2       | 1     | 1A      | Portable Classroom Restroom          | no                                | W2        | None                  | N/A                     | None                               | 0             | No                        | no                            |                              |
| 5400  | 2       | 1     | 1A      | Portable Classroom Restroom          | no                                | W3        | None                  | N/A                     | None                               | 0             | No                        | no                            |                              |
| 5400  | 2       | 1     | 1A      | Portable Classroom Restroom          | no                                | W4        | Cracking              | Negative                | None                               | 0             | No                        | no                            |                              |
| 5400  | 2       | 1     | 1A      | Portable Classroom Restroom          | no                                | Ceiling   | None                  | N/A                     | None                               | 0             | No                        | no                            |                              |
| 5400  | 2       | 1     | 1A      | Portable Classroom Restroom          | no                                | Floor     | None                  | N/A                     | None                               | 0             | No                        | no                            | floor tile                   |
| 5400  | 2       | 1     | 1B      | Portable Classroom Closet            | no                                | W1        | None                  | N/A                     | None                               | 0             | No                        | no                            |                              |
| 5400  | 2       | 1     | 1B      | Portable Classroom Closet            | no                                | W2        | None                  | N/A                     | None                               | 0             | No                        | no                            |                              |
| 5400  | 2       | 1     | 1B      | Portable Classroom Closet            | no                                | W3        | None                  | N/A                     | None                               | 0             | No                        | no                            |                              |
| 5400  | 2       | 1     | 1B      | Portable Classroom Closet            | no                                | W4        | None                  | N/A                     | None                               | 0             | No                        | no                            |                              |
| 5400  | 2       | 1     | 1B      | Portable Classroom Closet            | no                                | Ceiling   | Moisture Damage       | Negative                | None                               | 0             | No                        | no                            |                              |
| 5400  | 2       | 1     | 1B      | Portable Classroom Closet            | no                                | Floor     | None                  | N/A                     | None                               | 0             | No                        | no                            | floor tile                   |