

					School District of Philadelphia																
			Name of Inspector: Ryan Hutsell		Lead Safe Certification Assessment Report									Inspection Dates: 05/03-28/21							
			Inspection Company: Synertech, Inc.		Cramp School									ULCS# 5470							
E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	Lead Concentrati on (% wt)	Lead in Paint Chips by Flame AAS Analysis Results (positive / negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes		
1	1	100	Main Office	yes	W1	Wood	White	Chipping	4	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no			
1	1	100	Main Office	yes	W2	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no			
1	1	100	Main Office	yes	W3	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no			
1	1	100	Main Office	yes	Cabinets	Wood	Yellow	Chipping	12	2.5	Positive	None	0	N/A	Prior to Repair	No	no	no			
1	1	100	Main Office	yes	Shelves	Wood	Yellow	Friction	12	2.1	Positive	None	0	N/A	Prior to Repair	No	no	no			
1	1	100	Main Office	yes	W4	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no			
1	1	100	Main Office	yes	Ceiling	Concrete	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no			
1	1	100	Main Office	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no			
1	1	100B	Former Conference Room Back of Main Office	yes	W1	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no			
1	1	100B	Former Conference Room Back of Main Office	yes	W2	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no			
1	1	100B	Former Conference Room Back of Main Office	yes	W3	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no			
1	1	100B	Former Conference Room Back of Main Office	yes	W4	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no			
1	1	100B	Former Conference Room Back of Main Office	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no			
1	1	100B	Former Conference Room Back of Main Office	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no			
1	1	100C	Main Office Conference Room	yes	W1	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no			
1	1	100C	Main Office Conference Room	yes	Door Frame	Metal	White	Chipping	2	0.1	Negative	None	0	N/A	Prior to Repair	No	no	no			
1	1	100C	Main Office Conference Room	yes	Door	Metal	Blue	Chipping	2	0	Negative	None	0	N/A	Prior to Repair	No	no	no			
1	1	100C	Main Office Conference Room	yes	W2	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no			
1	1	100C	Main Office Conference Room	yes	Door	Metal	Green	Chipping	1	0.16	Negative	None	0	N/A	Prior to Repair	No	no	no			
1	1	100C	Main Office Conference Room	yes	Shelves	Wood	Blue	Friction	4	1.5	Positive	None	0	N/A	Prior to Repair	No	no	no			
1	1	100C	Main Office Conference Room	yes	Closet Shelves	Wood	Green	Friction	4	2.1	Positive	None	0	N/A	Prior to Repair	No	no	no			
1	1	100C	Main Office Conference Room	yes	W3	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no			
1	1	100C	Main Office Conference Room	yes	W4	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no			
1	1	100C	Main Office Conference Room	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no			
1	1	100C	Main Office Conference Room	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no			
1	1	104	Principal's Office	yes	W1	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no			
1	1	104	Principal's Office	yes	Door Frame	Metal	Green	Chipping	1	0.12	Negative	None	0	N/A	Prior to Repair	No	no	no			
1	1	104	Principal's Office	yes	Door	Wood	Green	Chipping	2	2	Positive	None	0	N/A	Prior to Repair	No	no	no			
1	1	104	Principal's Office	yes	W2	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no			
1	1	104	Principal's Office	yes	Cabinets/Shelve s	Wood	Green	Friction	5	2.2	Positive	None	0	N/A	Prior to Repair	No	no	no			
1	1	104	Principal's Office	yes	Door	Wood	Yellow	Chipping	2	1.8	Positive	None	0	N/A	Prior to Repair	No	no	no			
1	1	104	Principal's Office	yes	Closet Shelves	Wood	Green	Friction	4	2.4	Positive	None	0	N/A	Prior to Repair	No	no	no			
1	1	104	Principal's Office	yes	W3	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no			
1	1	104	Principal's Office	yes	Door Frame	Metal	Green	Chipping	1	0.2	Negative	None	0	N/A	Prior to Repair	No	no	no			
1	1	104	Principal's Office	yes	Door	Metal	Green	Chipping	1	1.5	Positive	None	0	N/A	Prior to Repair	No	no	no			
1	1	104	Principal's Office	yes	W4	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no			
1	1	104	Principal's Office	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no			
1	1	104	Principal's Office	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no			
1	1	104B	Principal's Office Restroom	yes	W1	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no			
1	1	104B	Principal's Office Restroom	yes	W2	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no			
1	1	104B	Principal's Office Restroom	yes	W3	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no			
1	1	104B	Principal's Office Restroom	yes	W4	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no			
1	1	104B	Principal's Office Restroom	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no			
1	1	104B	Principal's Office Restroom	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no			
1	1	100A	Counselor's Office 107	yes	W1	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no			
1	1	100A	Counselor's Office 107	yes	Door Frame	Metal	White	Chipping	1	0.1	Negative	None	0	N/A	Prior to Repair	No	no	no			
1	1	100A	Counselor's Office 107	yes	Door	Metal	Brown	Chipping	1	1.2	Positive	None	0	N/A	Prior to Repair	No	no	no			
1	1	100A	Counselor's Office 107	yes	W2	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no			

					School District of Philadelphia																	
			Name of Inspector: Ryan Hutsell		Lead Safe Certification Assessment Report									Inspection Dates: 05/03-28/21								
			Inspection Company: Synertech, Inc.		Cramp School									ULCS# 5470								
E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	Lead Concentrati on (% wt)	Lead in Paint Chips by Flame AAS Analysis Results (positive / negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes			
1	1	100A	Counselor's Office 107	yes	W3	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no				
1	1	100A	Counselor's Office 107	yes	Door Frame	Metal	Yellow	Chipping	1	0	Negative	None	0	N/A	Prior to Repair	No	no	no				
1	1	100A	Counselor's Office 107	yes	Door	Metal	Yellow	Chipping	2	1.8	Positive	None	0	N/A	Prior to Repair	No	no	no				
1	1	100A	Counselor's Office 107	yes	W4	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no				
1	1	100A	Counselor's Office 107	yes	Door	Metal	Blue	Chipping	1	0	Negative	None	0	N/A	Prior to Repair	No	no	no				
1	1	100A	Counselor's Office 107	yes	Closet Shelves	Wood	Blue	Friction	2	0.5	Negative	None	0	N/A	Prior to Repair	No	no	no				
1	1	100A	Counselor's Office 107	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no				
1	1	100A	Counselor's Office 107	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no				
1	1	100D	Counselor's Office Closet	yes	W1	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no				
1	1	100D	Counselor's Office Closet	yes	W2	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no				
1	1	100D	Counselor's Office Closet	yes	W3	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no				
1	1	100D	Counselor's Office Closet	yes	Shelves	Wood	Green	Friction	4	N/A	Positive	None	0	N/A	Prior to Repair	No	no	no				
1	1	100D	Counselor's Office Closet	yes	W4	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no				
1	1	100D	Counselor's Office Closet	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no				
1	1	100D	Counselor's Office Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no				
1	1	101	Nurse's Office	yes	W1	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no				
1	1	101	Nurse's Office	yes	Door Frame	Metal	Blue	Chipping	2	0.16	Negative	None	0	N/A	Prior to Repair	No	no	no				
1	1	101	Nurse's Office	yes	Door	Metal	Blue	Chipping	2	1.2	Positive	None	0	N/A	Prior to Repair	No	no	no				
1	1	101	Nurse's Office	yes	W2	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no				
1	1	101	Nurse's Office	yes	Door Frame	Metal	Orange	Chipping	2	0.2	Negative	None	0	N/A	Prior to Repair	No	no	no				
1	1	101	Nurse's Office	yes	Door	Metal	Orange	Chipping	2	2.6	Positive	None	0	N/A	Prior to Repair	No	no	no				
1	1	101	Nurse's Office	yes	Shelves	Wood	Green	Friction	2	1.9	Positive	None	0	N/A	Prior to Repair	No	no	no				
1	1	101	Nurse's Office	yes	W3	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no				
1	1	101	Nurse's Office	yes	Door Frame	Metal	Orange	Chipping	2	0.19	Negative	None	0	N/A	Prior to Repair	No	no	no				
1	1	101	Nurse's Office	yes	Door	Metal	Orange	Chipping	2	2.1	Positive	None	0	N/A	Prior to Repair	No	no	no				
1	1	101	Nurse's Office	yes	W4	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no				
1	1	101	Nurse's Office	yes	Door Frame	Metal	Orange	Chipping	2	0.15	Negative	None	0	N/A	Prior to Repair	No	no	no				
1	1	101	Nurse's Office	yes	Door	Metal	Orange	Chipping	2	2.3	Positive	None	0	N/A	Prior to Repair	No	no	no				
1	1	101	Nurse's Office	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no				
1	1	101	Nurse's Office	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no				
1	1	101A	Nurse's Office Exam Room	yes	W1	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no				
1	1	101A	Nurse's Office Exam Room	yes	W2	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no				
1	1	101A	Nurse's Office Exam Room	yes	Door	Metal	Brown	Chipping	1	1.4	Positive	None	0	N/A	Prior to Repair	No	no	no				
1	1	101A	Nurse's Office Exam Room	yes	W3	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no				
1	1	101A	Nurse's Office Exam Room	yes	W4	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no				
1	1	101A	Nurse's Office Exam Room	yes	Door	Metal	Blue	Chipping	1	1.2	Positive	None	0	N/A	Prior to Repair	No	no	no				
1	1	101A	Nurse's Office Exam Room	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no				
1	1	101A	Nurse's Office Exam Room	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no				
1	1	101B	Nurse's Office Restroom	yes	W1	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no				
1	1	101B	Nurse's Office Restroom	yes	Door Frame	Metal	Orange	Chipping	1	0.15	Negative	None	0	N/A	Prior to Repair	No	no	no				
1	1	101B	Nurse's Office Restroom	yes	Door	Metal	Red	Chipping	1	0.23	Negative	None	0	N/A	Prior to Repair	No	no	no				
1	1	101B	Nurse's Office Restroom	yes	W2	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no				
1	1	101B	Nurse's Office Restroom	yes	W3	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no				
1	1	101B	Nurse's Office Restroom	yes	W4	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no				
1	1	101B	Nurse's Office Restroom	yes	Bench	Wood	Yellow	Friction	4	0.12	Negative	None	0	N/A	Prior to Repair	No	no	no				
1	1	101B	Nurse's Office Restroom	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no				
1	1	101B	Nurse's Office Restroom	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no				
1	1	102C	Copy Room adjacent to Main Office	yes	W1	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no				
1	1	102C	Copy Room adjacent to Main Office	yes	W2	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no				
1	1	102C	Copy Room adjacent to Main Office	yes	W3	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no				
1	1	102C	Copy Room adjacent to Main Office	yes	W4	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no				
1	1	102C	Copy Room adjacent to Main Office	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no				
1	1	102C	Copy Room adjacent to Main Office	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no				

					School District of Philadelphia																	
			Name of Inspector: Ryan Hutsell		Lead Safe Certification Assessment Report									Inspection Dates: 05/03-28/21								
			Inspection Company: Synertech, Inc.		Cramp School									ULCS# 5470								
E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	Lead Concentrati on (% wt)	Lead in Paint Chips by Flame AAS Analysis Results (positive / negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes			
1	1	102A	Assistant Principal's Office	yes	W1	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no				
1	1	102A	Assistant Principal's Office	yes	W2	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no				
1	1	102A	Assistant Principal's Office	yes	W3	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no				
1	1	102A	Assistant Principal's Office	yes	W4	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no				
1	1	102A	Assistant Principal's Office	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no				
1	1	102A	Assistant Principal's Office	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no				
1	1	102B	Office 102	yes	W1	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no				
1	1	102B	Office 102	yes	W2	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no				
1	1	102B	Office 102	yes	W3	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no				
1	1	102B	Office 102	yes	W4	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no				
1	1	102B	Office 102	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no				
1	1	102B	Office 102	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no				
1	1	104A	Faculty Storage behind Elevator	yes	W1	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no				
1	1	104A	Faculty Storage behind Elevator	yes	W2	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no				
1	1	104A	Faculty Storage behind Elevator	yes	W3	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no				
1	1	104A	Faculty Storage behind Elevator	yes	W4	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no				
1	1	104A	Faculty Storage behind Elevator	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no				
1	1	104A	Faculty Storage behind Elevator	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no				
1	1	105	Classroom 13A	yes	W1	CMU	White	None	0	0	Negative	None	0	Positive	Partially Inaccessible	No	no	no	According to the 11/30/2020 classroom modernization specification 13a is part of the project. -JD			
1	1	105	Classroom 13A	yes	Door Frame	Metal	White	Chipping	1	0.16	Negative	None	0	N/A	Prior to Repair	No	no	no	According to the 11/30/2020 classroom modernization specification 13a is part of the project. -JD			
1	1	105	Classroom 13A	yes	Door	Metal	Yellow	Chipping	1	0.09	Negative	None	0	N/A	Prior to Repair	No	no	no	According to the 11/30/2020 classroom modernization specification 13a is part of the project. -JD			
1	1	105	Classroom 13A	yes	Sink Cabinet	Wood	Blue	Chipping	12	0.1	Negative	None	0	N/A	Prior to Repair	No	no	no	According to the 11/30/2020 classroom modernization specification 13a is part of the project. -JD			
1	1	105	Classroom 13A	yes	Shelves	Wood	White	Friction	12	0	Negative	None	0	N/A	Prior to Repair	No	no	no	According to the 11/30/2020 classroom modernization specification 13a is part of the project. -JD			
1	1	105	Classroom 13A	yes	W2	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no	According to the 11/30/2020 classroom modernization specification 13a is part of the project. -JD			
1	1	105	Classroom 13A	yes	Door Frame	Metal	White	Chipping	1	0.15	Negative	None	0	N/A	Prior to Repair	No	no	no	According to the 11/30/2020 classroom modernization specification 13a is part of the project. -JD			
1	1	105	Classroom 13A	yes	Door	Metal	Red	Chipping	1	1.2	Positive	None	0	N/A	Prior to Repair	No	no	no	According to the 11/30/2020 classroom modernization specification 13a is part of the project. -JD			
1	1	105	Classroom 13A	yes	Door	Metal	Yellow	Chipping	2	1.9	Positive	None	0	N/A	Prior to Repair	No	no	no	According to the 11/30/2020 classroom modernization specification 13a is part of the project. -JD			
1	1	105	Classroom 13A	yes	W3	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no	According to the 11/30/2020 classroom modernization specification 13a is part of the project. -JD			
1	1	105	Classroom 13A	yes	Door Frame	Metal	Blue	Chipping	1	0.12	Negative	None	0	N/A	Prior to Repair	No	no	no	According to the 11/30/2020 classroom modernization specification 13a is part of the project. -JD			
1	1	105	Classroom 13A	yes	Door	Metal	Blue	Chipping	1	0.08	Negative	None	0	N/A	Prior to Repair	No	no	no	According to the 11/30/2020 classroom modernization specification 13a is part of the project. -JD			
1	1	105	Classroom 13A	yes	W4	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no	According to the 11/30/2020 classroom modernization specification 13a is part of the project. -JD			
1	1	105	Classroom 13A	yes	Ceiling	Concrete	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	According to the 11/30/2020 classroom modernization specification 13a is part of the project. -JD			
1	1	105	Classroom 13A	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	According to the 11/30/2020 classroom modernization specification 13a is part of the project. -JD			

			School District of Philadelphia																
			Name of Inspector: Ryan Hutsell					Lead Safe Certification Assessment Report					Inspection Dates: 05/03-28/21						
			Inspection Company: Synertech, Inc.					Cramp School					ULCS# 5470						
E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	Lead Concentrati on (% wt)	Lead in Paint Chips by Flame AAS Analysis Results (positive / negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes
1	1	105C	Classroom 13A Closet	yes	W1	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no	According to the 11/30/2020 classroom modernization specification 13a is part of the project. -JD
1	1	105C	Classroom 13A Closet	yes	W2	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no	According to the 11/30/2020 classroom modernization specification 13a is part of the project. -JD
1	1	105C	Classroom 13A Closet	yes	W3	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no	According to the 11/30/2020 classroom modernization specification 13a is part of the project. -JD
1	1	105C	Classroom 13A Closet	yes	Shelves	Wood	White	Friction	4	1.8	Positive	None	0	N/A	Prior to Repair	No	no	no	According to the 11/30/2020 classroom modernization specification 13a is part of the project. -JD
1	1	105C	Classroom 13A Closet	yes	W4	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no	According to the 11/30/2020 classroom modernization specification 13a is part of the project. -JD
1	1	105C	Classroom 13A Closet	yes	Ceiling	Concrete	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	According to the 11/30/2020 classroom modernization specification 13a is part of the project. -JD
1	1	105C	Classroom 13A Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	According to the 11/30/2020 classroom modernization specification 13a is part of the project. -JD
1	1	NP1	Classroom 13A Laminating Room	yes	W1	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no	According to the 11/30/2020 classroom modernization specification 13a is part of the project. -JD
1	1	NP1	Classroom 13A Laminating Room	yes	Door Frame	Metal	Green	Chipping	2	1.9	Positive	None	0	N/A	Prior to Repair	No	no	no	According to the 11/30/2020 classroom modernization specification 13a is part of the project. -JD
1	1	NP1	Classroom 13A Laminating Room	yes	Door	Metal	Green	Chipping	2	1.5	Positive	None	0	N/A	Prior to Repair	No	no	no	According to the 11/30/2020 classroom modernization specification 13a is part of the project. -JD
1	1	NP1	Classroom 13A Laminating Room	yes	W2	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no	According to the 11/30/2020 classroom modernization specification 13a is part of the project. -JD
1	1	NP1	Classroom 13A Laminating Room	yes	W3	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no	According to the 11/30/2020 classroom modernization specification 13a is part of the project. -JD
1	1	NP1	Classroom 13A Laminating Room	yes	Doors	Wood	Blue	Chipping	2	0	Negative	None	0	N/A	Prior to Repair	No	no	no	According to the 11/30/2020 classroom modernization specification 13a is part of the project. -JD
1	1	NP1	Classroom 13A Laminating Room	yes	Shelves	Wood	Green	Friction	10	2.3	Positive	None	0	N/A	Prior to Repair	No	no	no	According to the 11/30/2020 classroom modernization specification 13a is part of the project. -JD
1	1	NP1	Classroom 13A Laminating Room	yes	Shelves	Wood	White	Friction	4	1.5	Positive	None	0	N/A	Prior to Repair	No	no	no	According to the 11/30/2020 classroom modernization specification 13a is part of the project. -JD
1	1	NP1	Classroom 13A Laminating Room	yes	W4	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no	According to the 11/30/2020 classroom modernization specification 13a is part of the project. -JD
1	1	NP1	Classroom 13A Laminating Room	yes	Door Frame	Metal	Green	Chipping	2	0	Negative	None	0	N/A	Prior to Repair	No	no	no	According to the 11/30/2020 classroom modernization specification 13a is part of the project. -JD
1	1	NP1	Classroom 13A Laminating Room	yes	Door	Metal	Green	Chipping	2	1.6	Positive	None	0	N/A	Prior to Repair	No	no	no	According to the 11/30/2020 classroom modernization specification 13a is part of the project. -JD
1	1	NP1	Classroom 13A Laminating Room	yes	Ceiling	Concrete	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	According to the 11/30/2020 classroom modernization specification 13a is part of the project. -JD
1	1	NP1	Classroom 13A Laminating Room	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	According to the 11/30/2020 classroom modernization specification 13a is part of the project. -JD
1	1	107	Classroom 13B	yes	W1	CMU	White	Chipping	12	0	Negative	None	0	Negative	Partially Inaccessible	No	no	no	According to the 11/30/2020 classroom modernization specification 13b is part of the project. -JD
1	1	107	Classroom 13B	yes	W1	Concrete	White	Chipping	4	0.1	Negative	None	0	N/A	Partially Inaccessible	No	no	no	According to the 11/30/2020 classroom modernization specification 13b is part of the project. -JD
1	1	107	Classroom 13B	yes	Cubbies	Wood	Red	Friction	20	1.5	Positive	None	0	N/A	Prior to Repair	No	no	no	According to the 11/30/2020 classroom modernization specification 13b is part of the project. -JD
1	1	107	Classroom 13B	yes	Door Frame	Metal	White	Chipping	2	0.08	Negative	None	0	N/A	Prior to Repair	No	no	no	According to the 11/30/2020 classroom modernization specification 13b is part of the project. -JD
1	1	107	Classroom 13B	yes	Door	Metal	Red	Chipping	2	0.4	Negative	None	0	N/A	Prior to Repair	No	no	no	According to the 11/30/2020 classroom modernization specification 13b is part of the project. -JD

			School District of Philadelphia																
			Name of Inspector: Ryan Hutsell					Lead Safe Certification Assessment Report					Inspection Dates: 05/03-28/21						
			Inspection Company: Synertech, Inc.					Cramp School					ULCS# 5470						
E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	Lead Concentrati on (% wt)	Lead in Paint Chips by Flame AAS Analysis Results (positive / negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes
1	1	107	Classroom 13B	yes	Transom Panel	Wood	White	Chipping	3	0.5	Negative	None	0	N/A	Prior to Repair	No	no	no	According to the 11/30/2020 classroom modernization specification 13b is part of the project. -JD
1	1	107	Classroom 13B	yes	Window Frame	Metal	White	Chipping	4	0.1	Negative	None	0	N/A	Prior to Repair	No	no	no	According to the 11/30/2020 classroom modernization specification 13b is part of the project. -JD
1	1	107	Classroom 13B	yes	Sink Cabinet	Wood	Red	Chipping	4	0	Negative	None	0	N/A	Prior to Repair	No	no	no	According to the 11/30/2020 classroom modernization specification 13b is part of the project. -JD
1	1	107	Classroom 13B	yes	W2	CMU	White	Chipping	10	0	Negative	None	0	Negative	Partially Inaccessible	No	no	no	According to the 11/30/2020 classroom modernization specification 13b is part of the project. -JD
1	1	107	Classroom 13B	yes	W2	Concrete	White	Chipping	2	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no	According to the 11/30/2020 classroom modernization specification 13b is part of the project. -JD
1	1	107	Classroom 13B	yes	Door	Metal	Blue	Chipping	1	0.1	Negative	None	0	N/A	Prior to Repair	No	no	no	According to the 11/30/2020 classroom modernization specification 13b is part of the project. -JD
1	1	107	Classroom 13B	yes	Door	Metal	Yellow	Chipping	1	1.7	Positive	None	0	N/A	Prior to Repair	No	no	no	According to the 11/30/2020 classroom modernization specification 13b is part of the project. -JD
1	1	107	Classroom 13B	yes	Door	Metal	Red	Chipping	1	1.5	Positive	None	0	N/A	Prior to Repair	No	no	no	According to the 11/30/2020 classroom modernization specification 13b is part of the project. -JD
1	1	107	Classroom 13B	yes	W3	CMU	White	Chipping	12	0.06	Negative	None	0	Negative	Partially Inaccessible	No	no	no	According to the 11/30/2020 classroom modernization specification 13b is part of the project. -JD
1	1	107	Classroom 13B	yes	W3	Concrete	White	Chipping	4	0.04	Negative	None	0	N/A	Partially Inaccessible	No	no	no	According to the 11/30/2020 classroom modernization specification 13b is part of the project. -JD
1	1	107	Classroom 13B	yes	Shelves	Wood	Orange	Friction	10	1.8	Positive	None	0	N/A	Prior to Repair	No	no	no	According to the 11/30/2020 classroom modernization specification 13b is part of the project. -JD
1	1	107	Classroom 13B	yes	W4	CMU	White	Chipping	10	0	Negative	None	0	Negative	Partially Inaccessible	No	no	no	According to the 11/30/2020 classroom modernization specification 13b is part of the project. -JD
1	1	107	Classroom 13B	yes	W4	Concrete	White	Chipping	4	0.08	Negative	None	0	N/A	Partially Inaccessible	No	no	no	According to the 11/30/2020 classroom modernization specification 13b is part of the project. -JD
1	1	107	Classroom 13B	yes	Shelves	Wood	Orange	Friction	10	1.6	Positive	None	0	N/A	Prior to Repair	No	no	no	According to the 11/30/2020 classroom modernization specification 13b is part of the project. -JD
1	1	107	Classroom 13B	yes	Ceiling	Concrete	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	According to the 11/30/2020 classroom modernization specification 13b is part of the project. -JD
1	1	107	Classroom 13B	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	According to the 11/30/2020 classroom modernization specification 13b is part of the project. -JD
1	1	107A	Classroom 13B Girl's Restroom	yes	W1	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	According to the 11/30/2020 classroom modernization specification 13b is part of the project. -JD
1	1	107A	Classroom 13B Girl's Restroom	yes	W2	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	According to the 11/30/2020 classroom modernization specification 13b is part of the project. -JD
1	1	107A	Classroom 13B Girl's Restroom	yes	W3	CMU	White	None	0	N/A	N/A	None	0	Negative	No	No	no	no	According to the 11/30/2020 classroom modernization specification 13b is part of the project. -JD
1	1	107A	Classroom 13B Girl's Restroom	yes	W4	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	According to the 11/30/2020 classroom modernization specification 13b is part of the project. -JD
1	1	107A	Classroom 13B Girl's Restroom	yes	Ceiling	Plaster	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	According to the 11/30/2020 classroom modernization specification 13b is part of the project. -JD
1	1	107A	Classroom 13B Girl's Restroom	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	According to the 11/30/2020 classroom modernization specification 13b is part of the project. -JD
1	1	107B	Classroom 13B Boy's Restroom	yes	W1	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	According to the 11/30/2020 classroom modernization specification 13b is part of the project. -JD
1	1	107B	Classroom 13B Boy's Restroom	yes	W2	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	According to the 11/30/2020 classroom modernization specification 13b is part of the project. -JD
1	1	107B	Classroom 13B Boy's Restroom	yes	W3	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	According to the 11/30/2020 classroom modernization specification 13b is part of the project. -JD

			School District of Philadelphia																
			Lead Safe Certification Assessment Report																
			Cramp School																
			Inspection Dates: 05/03-28/21																
			ULCS# 5470																
E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	Lead Concentrati on (% wt)	Lead in Paint Chips by Flame AAS Analysis Results (positive / negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes
1	1	107B	Classroom 13B Boy's Restroom	yes	W4	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	According to the 11/30/2020 classroom modernization specification 13b is part of the project. -JD
1	1	107B	Classroom 13B Boy's Restroom	yes	Ceiling	Plaster	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	According to the 11/30/2020 classroom modernization specification 13b is part of the project. -JD
1	1	107B	Classroom 13B Boy's Restroom	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	According to the 11/30/2020 classroom modernization specification 13b is part of the project. -JD
1	1	107C	Classroom 13B Closet	yes	W1	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no	According to the 11/30/2020 classroom modernization specification 13b is part of the project. -JD
1	1	107C	Classroom 13B Closet	yes	W2	CMU	White	None	0	0	Negative	None	0	Negative	Partially Inaccessible	No	no	no	According to the 11/30/2020 classroom modernization specification 13b is part of the project. -JD
1	1	107C	Classroom 13B Closet	yes	W3	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no	According to the 11/30/2020 classroom modernization specification 13b is part of the project. -JD
1	1	107C	Classroom 13B Closet	yes	Shelves	Wood	Green	Friction	4	1.2	Positive	None	0	N/A	Prior to Repair	No	no	no	According to the 11/30/2020 classroom modernization specification 13b is part of the project. -JD
1	1	107C	Classroom 13B Closet	yes	W4	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no	According to the 11/30/2020 classroom modernization specification 13b is part of the project. -JD
1	1	107C	Classroom 13B Closet	yes	Ceiling	Concrete	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	According to the 11/30/2020 classroom modernization specification 13b is part of the project. -JD
1	1	107C	Classroom 13B Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	According to the 11/30/2020 classroom modernization specification 13b is part of the project. -JD
1	1	105B	Teacher Lounge across from Elevator	yes	W1	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no	
1	1	105B	Teacher Lounge across from Elevator	yes	W2	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no	
1	1	105B	Teacher Lounge across from Elevator	yes	W3	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no	
1	1	105B	Teacher Lounge across from Elevator	yes	W4	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no	
1	1	105B	Teacher Lounge across from Elevator	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	Drop ceiling
1	1	105B	Teacher Lounge across from Elevator	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	
1	1	105D	Teacher Lounge Restroom	yes	W1	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no	
1	1	105D	Teacher Lounge Restroom	yes	W2	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no	
1	1	105D	Teacher Lounge Restroom	yes	W3	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no	
1	1	105D	Teacher Lounge Restroom	yes	W4	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no	
1	1	105D	Teacher Lounge Restroom	yes	Ceiling	Plaster	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	
1	1	105D	Teacher Lounge Restroom	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	Ceramic Tiles
1	1	106C	Custodial Closet by Classroom 106	no	W1	CMU	White	Chipping	4	0	Negative	None	0	N/A	Prior to Repair	No	no	no	
1	1	106C	Custodial Closet by Classroom 106	no	W2	CMU	White	Chipping	2	0	Negative	None	0	N/A	Prior to Repair	No	no	no	
1	1	106C	Custodial Closet by Classroom 106	no	W3	CMU	White	Chipping	2	0	Negative	None	0	N/A	Prior to Repair	No	no	no	
1	1	106C	Custodial Closet by Classroom 106	no	W4	CMU	White	Chipping	1	0	Negative	None	0	N/A	Prior to Repair	No	no	no	
1	1	106C	Custodial Closet by Classroom 106	no	Ceiling	Plaster	White	Chipping	1	0.11	Negative	None	0	N/A	Prior to Repair	No	no	no	
1	1	106C	Custodial Closet by Classroom 106	no	Floor	Concrete	Grey	Chipping	1	0	Negative	None	0	N/A	Prior to Repair	No	no	no	
1	1	106	Classroom 106	yes	W1	CMU	White	Chipping	20	0	Negative	None	0	Negative	Prior to Repair	No	no	no	According to the 11/30/2020 classroom modernization specification 106 is part of the project. -JD
1	1	106	Classroom 106	yes	Door Frame	Metal	Green	Chipping	1	0.17	Negative	None	0	N/A	Prior to Repair	No	no	no	According to the 11/30/2020 classroom modernization specification 106 is part of the project. -JD
1	1	106	Classroom 106	yes	Door	Metal	Green	Chipping	2	1.3	Positive	None	0	N/A	Prior to Repair	No	no	no	According to the 11/30/2020 classroom modernization specification 106 is part of the project. -JD
1	1	106	Classroom 106	yes	Sink Cabinet	Wood	Green	Chipping	4	1.5	Positive	None	0	N/A	Prior to Repair	No	no	no	According to the 11/30/2020 classroom modernization specification 106 is part of the project. -JD
1	1	106	Classroom 106	yes	W2	CMU	White	Chipping	6	0	Negative	None	0	Negative	Prior to Repair	No	no	no	According to the 11/30/2020 classroom modernization specification 106 is part of the project. -JD
1	1	106	Classroom 106	yes	W2	Concrete	White	Chipping	2	0	Negative	None	0	N/A	Prior to Repair	No	no	no	According to the 11/30/2020 classroom modernization specification 106 is part of the project. -JD

			School District of Philadelphia																
			Lead Safe Certification Assessment Report																
			Cramp School																
Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	Lead Concentration (% wt)	Lead in Paint Chips by Flame AAS Analysis Results (positive / negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes
1	1	106	Classroom 106	yes	Doors	Metal	Green	Chipping	2	1.6	Positive	None	0	N/A	Prior to Repair	No	no	no	According to the 11/30/2020 classroom modernization specification 106 is part of the project. -JD
1	1	106	Classroom 106	yes	Doors	Metal	Blue	Chipping	2	1.2	Positive	None	0	N/A	Prior to Repair	No	no	no	According to the 11/30/2020 classroom modernization specification 106 is part of the project. -JD
1	1	106	Classroom 106	yes	W3	CMU	White	Chipping	6	0	Negative	None	0	Negative	Prior to Repair	No	no	no	According to the 11/30/2020 classroom modernization specification 106 is part of the project. -JD
1	1	106	Classroom 106	yes	W3	Concrete	White	Chipping	2	0	Negative	None	0	N/A	Prior to Repair	No	no	no	According to the 11/30/2020 classroom modernization specification 106 is part of the project. -JD
1	1	106	Classroom 106	yes	W4	CMU	White	Chipping	6	0	Negative	None	0	Negative	Prior to Repair	No	no	no	According to the 11/30/2020 classroom modernization specification 106 is part of the project. -JD
1	1	106	Classroom 106	yes	W4	Concrete	White	Chipping	2	0	Negative	None	0	N/A	Prior to Repair	No	no	no	According to the 11/30/2020 classroom modernization specification 106 is part of the project. -JD
1	1	106	Classroom 106	yes	Shelves/Coat Rack	Wood	Green	Friction	10	1.1	Positive	None	0	N/A	Prior to Repair	No	no	no	According to the 11/30/2020 classroom modernization specification 106 is part of the project. -JD
1	1	106	Classroom 106	yes	Ceiling	Concrete	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	According to the 11/30/2020 classroom modernization specification 106 is part of the project. -JD
1	1	106	Classroom 106	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	According to the 11/30/2020 classroom modernization specification 106 is part of the project. -JD
1	1	106	Classroom 106	yes	Baseboard	Concrete	Black	Chipping	2	0.1	Negative	None	0	N/A	Prior to Repair	No	no	no	According to the 11/30/2020 classroom modernization specification 106 is part of the project. -JD
1	1	106A	Classroom 106 Restroom	yes	W1	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	According to the 11/30/2020 classroom modernization specification 106 is part of the project. -JD
1	1	106A	Classroom 106 Restroom	yes	W2	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	According to the 11/30/2020 classroom modernization specification 106 is part of the project. -JD
1	1	106A	Classroom 106 Restroom	yes	W3	CMU	White	None	0	N/A	N/A	None	0	Negative	No	No	no	no	According to the 11/30/2020 classroom modernization specification 106 is part of the project. -JD
1	1	106A	Classroom 106 Restroom	yes	W4	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	According to the 11/30/2020 classroom modernization specification 106 is part of the project. -JD
1	1	106A	Classroom 106 Restroom	yes	Ceiling	Plaster	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	According to the 11/30/2020 classroom modernization specification 106 is part of the project. -JD
1	1	106A	Classroom 106 Restroom	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	According to the 11/30/2020 classroom modernization specification 106 is part of the project. -JD
1	1	106B	Classroom 106 Large Closet	yes	W1	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no	According to the 11/30/2020 classroom modernization specification 106 is part of the project. -JD
1	1	106B	Classroom 106 Large Closet	yes	W2	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no	According to the 11/30/2020 classroom modernization specification 106 is part of the project. -JD
1	1	106B	Classroom 106 Large Closet	yes	Shelves	Wood	Green	Friction	4	1.2	Positive	None	0	N/A	Prior to Repair	No	no	no	According to the 11/30/2020 classroom modernization specification 106 is part of the project. -JD
1	1	106B	Classroom 106 Large Closet	yes	W3	CMU	White	None	0	0	Negative	None	0	Negative	Partially Inaccessible	No	no	no	According to the 11/30/2020 classroom modernization specification 106 is part of the project. -JD
1	1	106B	Classroom 106 Large Closet	yes	Shelves	Wood	Green	Friction	4	1.2	Positive	None	0	N/A	Prior to Repair	No	no	no	According to the 11/30/2020 classroom modernization specification 106 is part of the project. -JD
1	1	106B	Classroom 106 Large Closet	yes	W4	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no	According to the 11/30/2020 classroom modernization specification 106 is part of the project. -JD
1	1	106B	Classroom 106 Large Closet	yes	Ceiling	Concrete	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	According to the 11/30/2020 classroom modernization specification 106 is part of the project. -JD
1	1	106B	Classroom 106 Large Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	According to the 11/30/2020 classroom modernization specification 106 is part of the project. -JD
1	1	106D	Classroom 106 Closet to Right of Entrance	yes	W1	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no	According to the 11/30/2020 classroom modernization specification 106 is part of the project. -JD

					School District of Philadelphia														
			Name of Inspector: Ryan Hutsell		Lead Safe Certification Assessment Report							Inspection Dates: 05/03-28/21							
			Inspection Company: Synertech, Inc.		Cramp School							ULCS# 5470							
E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	Lead Concentrati on (% wt)	Lead in Paint Chips by Flame AAS Analysis Results (positive / negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes
1	1	106D	Classroom 106 Closet to Right of Entrance	yes	W2	CMU	White	None	0	0	Negative	None	0	Negative	Partially Inaccessible	No	no	no	According to the 11/30/2020 classroom modernization specification 106 is part of the project. -JD
1	1	106D	Classroom 106 Closet to Right of Entrance	yes	W3	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no	According to the 11/30/2020 classroom modernization specification 106 is part of the project. -JD
1	1	106D	Classroom 106 Closet to Right of Entrance	yes	Shelves	Wood	Green	Friction	2	N/A	Positive	None	0	N/A	Partially Inaccessible	No	no	no	According to the 11/30/2020 classroom modernization specification 106 is part of the project. -JD
1	1	106D	Classroom 106 Closet to Right of Entrance	yes	W4	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no	According to the 11/30/2020 classroom modernization specification 106 is part of the project. -JD
1	1	106D	Classroom 106 Closet to Right of Entrance	yes	Ceiling	Concrete	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	According to the 11/30/2020 classroom modernization specification 106 is part of the project. -JD
1	1	106D	Classroom 106 Closet to Right of Entrance	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	According to the 11/30/2020 classroom modernization specification 106 is part of the project. -JD
1	1	106E	Classroom 106 Closet to Left of Entrance	yes	W1	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no	According to the 11/30/2020 classroom modernization specification 106 is part of the project. -JD
1	1	106E	Classroom 106 Closet to Left of Entrance	yes	W2	CMU	White	None	0	0	Negative	None	0	Negative	Partially Inaccessible	No	no	no	According to the 11/30/2020 classroom modernization specification 106 is part of the project. -JD
1	1	106E	Classroom 106 Closet to Left of Entrance	yes	W3	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no	According to the 11/30/2020 classroom modernization specification 106 is part of the project. -JD
1	1	106E	Classroom 106 Closet to Left of Entrance	yes	Shelves	Wood	Green	Friction	2	N/A	Positive	None	0	N/A	Partially Inaccessible	No	no	no	According to the 11/30/2020 classroom modernization specification 106 is part of the project. -JD
1	1	106E	Classroom 106 Closet to Left of Entrance	yes	W4	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no	According to the 11/30/2020 classroom modernization specification 106 is part of the project. -JD
1	1	106E	Classroom 106 Closet to Left of Entrance	yes	Ceiling	Concrete	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	According to the 11/30/2020 classroom modernization specification 106 is part of the project. -JD
1	1	106E	Classroom 106 Closet to Left of Entrance	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	According to the 11/30/2020 classroom modernization specification 106 is part of the project. -JD
1	1	108	Classroom 108	yes	W1	CMU	White	None	0	0	Negative	None	0	Negative	Partially Inaccessible	No	no	no	According to the 11/30/2020 classroom modernization specification 108 is part of the project. -JD
1	1	108	Classroom 108	yes	Shelves/Coat Rack	Wood	Yellow	Friction	12	2.1	Positive	None	0	N/A	Prior to Repair	No	no	no	According to the 11/30/2020 classroom modernization specification 108 is part of the project. -JD
1	1	108	Classroom 108	yes	Doors	Metal	Yellow	Chipping	2	1.2	Positive	None	0	N/A	Prior to Repair	No	no	no	According to the 11/30/2020 classroom modernization specification 108 is part of the project. -JD
1	1	108	Classroom 108	yes	Doors	Metal	Brown	Chipping	2	1.4	Positive	None	0	N/A	Prior to Repair	No	no	no	According to the 11/30/2020 classroom modernization specification 108 is part of the project. -JD
1	1	108	Classroom 108	yes	W2	CMU	White	None	0	0	Negative	None	0	Negative	Partially Inaccessible	No	no	no	According to the 11/30/2020 classroom modernization specification 108 is part of the project. -JD
1	1	108	Classroom 108	yes	Pipe	Metal	White	Chipping	4	0.13	Negative	None	0	N/A	Prior to Repair	No	no	no	According to the 11/30/2020 classroom modernization specification 108 is part of the project. -JD
1	1	108	Classroom 108	yes	W3	CMU	White	None	0	0	Negative	None	0	Negative	Partially Inaccessible	No	no	no	According to the 11/30/2020 classroom modernization specification 108 is part of the project. -JD
1	1	108	Classroom 108	yes	Door Frame	Metal	White	Chipping	2	0.15	Negative	None	0	N/A	Prior to Repair	No	no	no	According to the 11/30/2020 classroom modernization specification 108 is part of the project. -JD
1	1	108	Classroom 108	yes	Door	Metal	White	Chipping	2	0	Negative	None	0	N/A	Prior to Repair	No	no	no	According to the 11/30/2020 classroom modernization specification 108 is part of the project. -JD
1	1	108	Classroom 108	yes	W4	CMU	White	None	0	0	Negative	None	0	Negative	Partially Inaccessible	No	no	no	According to the 11/30/2020 classroom modernization specification 108 is part of the project. -JD
1	1	108	Classroom 108	yes	Shelves	Wood	Yellow	Friction	10	2	Positive	None	0	N/A	Prior to Repair	No	no	no	According to the 11/30/2020 classroom modernization specification 108 is part of the project. -JD
1	1	108	Classroom 108	yes	Sink Cabinet	Wood	Yellow	Chipping	12	1.8	Positive	None	0	N/A	Prior to Repair	No	no	no	According to the 11/30/2020 classroom modernization specification 108 is part of the project. -JD

			School District of Philadelphia																
			Lead Safe Certification Assessment Report																
			Cramp School																
Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	Lead Concentration (% wt)	Lead in Paint Chips by Flame AAS Analysis Results (positive / negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes
1	1	108	Classroom 108	yes	Door Frame	Metal	Yellow	Chipping	2	0.1	Negative	None	0	N/A	Prior to Repair	No	no	no	According to the 11/30/2020 classroom modernization specification 108 is part of the project. -JD
1	1	108	Classroom 108	yes	Door	Metal	Yellow	Chipping	2	1.6	Positive	None	0	N/A	Prior to Repair	No	no	no	According to the 11/30/2020 classroom modernization specification 108 is part of the project. -JD
1	1	108	Classroom 108	yes	Ceiling	Concrete	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	According to the 11/30/2020 classroom modernization specification 108 is part of the project. -JD
1	1	108	Classroom 108	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	According to the 11/30/2020 classroom modernization specification 108 is part of the project. -JD
1	1	108A	Classroom 108 Closet adjacent to Restroom	yes	W1	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	According to the 11/30/2020 classroom modernization specification 108 is part of the project. -JD
1	1	108A	Classroom 108 Closet adjacent to Restroom	yes	W2	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	According to the 11/30/2020 classroom modernization specification 108 is part of the project. -JD
1	1	108A	Classroom 108 Closet adjacent to Restroom	yes	W3	CMU	White	None	0	N/A	N/A	None	0	Positive	No	No	no	no	According to the 11/30/2020 classroom modernization specification 108 is part of the project. -JD
1	1	108A	Classroom 108 Closet adjacent to Restroom	yes	Shelves	Wood	Green	Friction	4	1.5	Positive	None	0	N/A	Prior to Repair	No	no	no	According to the 11/30/2020 classroom modernization specification 108 is part of the project. -JD
1	1	108A	Classroom 108 Closet adjacent to Restroom	yes	W4	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	According to the 11/30/2020 classroom modernization specification 108 is part of the project. -JD
1	1	108A	Classroom 108 Closet adjacent to Restroom	yes	Ceiling	Concrete	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	According to the 11/30/2020 classroom modernization specification 108 is part of the project. -JD
1	1	108A	Classroom 108 Closet adjacent to Restroom	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	According to the 11/30/2020 classroom modernization specification 108 is part of the project. -JD
1	1	108B	Classroom 108 Restroom	yes	W1	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	According to the 11/30/2020 classroom modernization specification 108 is part of the project. -JD
1	1	108B	Classroom 108 Restroom	yes	W2	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	According to the 11/30/2020 classroom modernization specification 108 is part of the project. -JD
1	1	108B	Classroom 108 Restroom	yes	W3	CMU	White	None	0	N/A	N/A	None	0	Negative	No	No	no	no	According to the 11/30/2020 classroom modernization specification 108 is part of the project. -JD
1	1	108B	Classroom 108 Restroom	yes	W4	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	According to the 11/30/2020 classroom modernization specification 108 is part of the project. -JD
1	1	108B	Classroom 108 Restroom	yes	Ceiling	Plaster	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	According to the 11/30/2020 classroom modernization specification 108 is part of the project. -JD
1	1	108B	Classroom 108 Restroom	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	According to the 11/30/2020 classroom modernization specification 108 is part of the project. -JD
1	1	108C	Classroom 108 Closet adjacent to Exterior Wall	yes	W1	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no	According to the 11/30/2020 classroom modernization specification 108 is part of the project. -JD
1	1	108C	Classroom 108 Closet adjacent to Exterior Wall	yes	W2	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no	According to the 11/30/2020 classroom modernization specification 108 is part of the project. -JD
1	1	108C	Classroom 108 Closet adjacent to Exterior Wall	yes	W3	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no	According to the 11/30/2020 classroom modernization specification 108 is part of the project. -JD
1	1	108C	Classroom 108 Closet adjacent to Exterior Wall	yes	W4	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no	According to the 11/30/2020 classroom modernization specification 108 is part of the project. -JD
1	1	108C	Classroom 108 Closet adjacent to Exterior Wall	yes	Ceiling	Concrete	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	According to the 11/30/2020 classroom modernization specification 108 is part of the project. -JD
1	1	108C	Classroom 108 Closet adjacent to Exterior Wall	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	According to the 11/30/2020 classroom modernization specification 108 is part of the project. -JD
1	1	108D	Classroom 108 Closet adjacent to Entrance	yes	W1	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no	According to the 11/30/2020 classroom modernization specification 108 is part of the project. -JD
1	1	108D	Classroom 108 Closet adjacent to Entrance	yes	W2	CMU	White	None	0	0	Negative	None	0	Negative	Partially Inaccessible	No	no	no	According to the 11/30/2020 classroom modernization specification 108 is part of the project. -JD

					School District of Philadelphia																
			Name of Inspector: Ryan Hutsell		Lead Safe Certification Assessment Report								Inspection Dates: 05/03-28/21								
			Inspection Company: Synertech, Inc.		Cramp School								ULCS# 5470								
E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	Lead Concentrati on (% wt)	Lead in Paint Chips by Flame AAS Analysis Results (positive / negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes		
1	1	108D	Classroom 108 Closet adjacent to Entrance	yes	W3	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no	According to the 11/30/2020 classroom modernization specification 108 is part of the project. -JD		
1	1	108D	Classroom 108 Closet adjacent to Entrance	yes	Shelves	Wood	Green	Friction	4	N/A	Positive	None	0	N/A	Partially Inaccessible	No	no	no	According to the 11/30/2020 classroom modernization specification 108 is part of the project. -JD		
1	1	108D	Classroom 108 Closet adjacent to Entrance	yes	W4	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no	According to the 11/30/2020 classroom modernization specification 108 is part of the project. -JD		
1	1	108D	Classroom 108 Closet adjacent to Entrance	yes	Ceiling	Concrete	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	According to the 11/30/2020 classroom modernization specification 108 is part of the project. -JD		
1	1	108D	Classroom 108 Closet adjacent to Entrance	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	According to the 11/30/2020 classroom modernization specification 108 is part of the project. -JD		
1	1	110	Classroom 110	yes	W1	CMU	White	None	0	0	Negative	None	0	Negative	Partially Inaccessible	No	no	no	According to the 11/30/2020 Classroom modernization specification 110 is part of the project. -JD		
1	1	110	Classroom 110	yes	W2	CMU	White	None	0	0	Negative	None	0	Negative	Partially Inaccessible	No	no	no	According to the 11/30/2020 Classroom modernization specification 110 is part of the project. -JD		
1	1	110	Classroom 110	yes	Door Frame	Metal	Orange	Chipping	2	0.22	Negative	None	0	N/A	Prior to Repair	No	no	no	According to the 11/30/2020 Classroom modernization specification 110 is part of the project. -JD		
1	1	110	Classroom 110	yes	Door	Metal	Orange	Chipping	2	1.1	Positive	None	0	N/A	Prior to Repair	No	no	no	According to the 11/30/2020 Classroom modernization specification 110 is part of the project. -JD		
1	1	110	Classroom 110	yes	Sink Cabinet	Wood	Red	Chipping	10	1.3	Positive	None	0	N/A	Prior to Repair	No	no	no	According to the 11/30/2020 Classroom modernization specification 110 is part of the project. -JD		
1	1	110	Classroom 110	yes	W3	CMU	White	None	0	0	Negative	None	0	Negative	Partially Inaccessible	No	no	no	According to the 11/30/2020 Classroom modernization specification 110 is part of the project. -JD		
1	1	110	Classroom 110	yes	W4	CMU	White	None	0	0	Negative	None	0	Negative	Partially Inaccessible	No	no	no	According to the 11/30/2020 Classroom modernization specification 110 is part of the project. -JD		
1	1	110	Classroom 110	yes	Shelves/Coat Rack	Wood	Red	Friction	12	1.2	Positive	None	0	N/A	Partially Inaccessible	No	no	no	According to the 11/30/2020 Classroom modernization specification 110 is part of the project. -JD		
1	1	110	Classroom 110	yes	Ceiling	Concrete	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	According to the 11/30/2020 Classroom modernization specification 110 is part of the project. -JD		
1	1	110	Classroom 110	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	According to the 11/30/2020 Classroom modernization specification 110 is part of the project. -JD		
1	1	110A	Classroom 110 Closet adjacent to Restroom	yes	W1	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no	According to the 11/30/2020 Classroom modernization specification 110 is part of the project. -JD		
1	1	110A	Classroom 110 Closet adjacent to Restroom	yes	W2	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no	According to the 11/30/2020 Classroom modernization specification 110 is part of the project. -JD		
1	1	110A	Classroom 110 Closet adjacent to Restroom	yes	W3	CMU	White	None	0	0	Negative	None	0	Negative	Partially Inaccessible	No	no	no	According to the 11/30/2020 Classroom modernization specification 110 is part of the project. -JD		
1	1	110A	Classroom 110 Closet adjacent to Restroom	yes	Shelves	Wood	Green	Friction	4	N/A	Positive	None	0	N/A	Partially Inaccessible	No	no	no	According to the 11/30/2020 Classroom modernization specification 110 is part of the project. -JD		
1	1	110A	Classroom 110 Closet adjacent to Restroom	yes	W4	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no	According to the 11/30/2020 Classroom modernization specification 110 is part of the project. -JD		
1	1	110A	Classroom 110 Closet adjacent to Restroom	yes	Ceiling	Concrete	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	According to the 11/30/2020 Classroom modernization specification 110 is part of the project. -JD		
1	1	110A	Classroom 110 Closet adjacent to Restroom	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	According to the 11/30/2020 Classroom modernization specification 110 is part of the project. -JD		
1	1	110B	Classroom 110 Restroom	yes	W1	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	According to the 11/30/2020 Classroom modernization specification 110 is part of the project. -JD		
1	1	110B	Classroom 110 Restroom	yes	Door Frame	Metal	Green	Chipping	1	0.1	Negative	None	0	N/A	Prior to Repair	No	no	no	According to the 11/30/2020 Classroom modernization specification 110 is part of the project. -JD		
1	1	110B	Classroom 110 Restroom	yes	Door	Metal	Green	Chipping	1	1.2	Positive	None	0	N/A	Prior to Repair	No	no	no	According to the 11/30/2020 Classroom modernization specification 110 is part of the project. -JD		

																																																																																																																																																																																																																																																																																																																																																																																																																							</
--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	----

					School District of Philadelphia															
			Name of Inspector: Ryan Hutsell		Lead Safe Certification Assessment Report								Inspection Dates: 05/03-28/21							
			Inspection Company: Synertech, Inc.		Cramp School								ULCS# 5470							
E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	Lead Concentrati on (% wt)	Lead in Paint Chips by Flame AAS Analysis Results (positive / negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes	
1	1	114D	Classroom 114 Closet by Entrance	no	Shelves	Wood	Green	Friction	4	N/A	Positive	None	0	N/A	Partially Inaccessible	No	no	no		
1	1	114D	Classroom 114 Closet by Entrance	no	W4	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no		
1	1	114D	Classroom 114 Closet by Entrance	no	Ceiling	Concrete	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no		
1	1	114D	Classroom 114 Closet by Entrance	no	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no		
1	1	114B	Women's Restroom adjacent to Cafetorium	yes	W1	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no		
1	1	114B	Women's Restroom adjacent to Cafetorium	yes	W2	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no		
1	1	114B	Women's Restroom adjacent to Cafetorium	yes	W3	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no		
1	1	114B	Women's Restroom adjacent to Cafetorium	yes	Stall Divider	Metal	Blue	Friction	1	0.14	Negative	None	0	N/A	Prior to Repair	No	no	no		
1	1	114B	Women's Restroom adjacent to Cafetorium	yes	W4	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no		
1	1	114B	Women's Restroom adjacent to Cafetorium	yes	Ceiling	Plaster	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no		
1	1	114B	Women's Restroom adjacent to Cafetorium	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	Ceramic Tiles	
1	1	114C	Men's Restroom adjacent to Cafetorium	yes	W1	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no		
1	1	114C	Men's Restroom adjacent to Cafetorium	yes	W2	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no		
1	1	114C	Men's Restroom adjacent to Cafetorium	yes	W3	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no		
1	1	114C	Men's Restroom adjacent to Cafetorium	yes	Stall Divider	Metal	Blue	Friction	1	0.25	Negative	None	0	N/A	Prior to Repair	No	no	no		
1	1	114C	Men's Restroom adjacent to Cafetorium	yes	W4	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no		
1	1	114C	Men's Restroom adjacent to Cafetorium	yes	Ceiling	Plaster	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no		
1	1	114C	Men's Restroom adjacent to Cafetorium	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	Ceramic Tiles	
1	1	114E	Men's Restroom adjacent to Cafetorium Custodial Closet	yes	W1	CMU	White	Chipping	2	0	Negative	None	0	N/A	Prior to Repair	No	no	no		
1	1	114E	Men's Restroom adjacent to Cafetorium Custodial Closet	yes	W2	CMU	White	Chipping	2	0	Negative	None	0	N/A	Prior to Repair	No	no	no		
1	1	114E	Men's Restroom adjacent to Cafetorium Custodial Closet	yes	W3	CMU	White	Chipping	2	0	Negative	None	0	N/A	Prior to Repair	No	no	no		
1	1	114E	Men's Restroom adjacent to Cafetorium Custodial Closet	yes	W4	CMU	White	Chipping	2	0	Negative	None	0	N/A	Prior to Repair	No	no	no		
1	1	114E	Men's Restroom adjacent to Cafetorium Custodial Closet	yes	Ceiling	Concrete	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no		
1	1	114E	Men's Restroom adjacent to Cafetorium Custodial Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no		
1	1	103	Classroom 103 ESOL	yes	W1	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no		
1	1	103	Classroom 103 ESOL	yes	W2	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no		
1	1	103	Classroom 103 ESOL	yes	W3	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no		
1	1	103	Classroom 103 ESOL	yes	W4	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no		
1	1	103	Classroom 103 ESOL	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no		
1	1	103	Classroom 103 ESOL	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no		
1	1	103A	Classroom 103 Closet	yes	W1	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no		
1	1	103A	Classroom 103 Closet	yes	W2	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no		
1	1	103A	Classroom 103 Closet	yes	W3	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no		
1	1	103A	Classroom 103 Closet	yes	Shelves	Wood	Green	Friction	2	N/A	Positive	None	0	N/A	Prior to Repair	No	no	no		
1	1	103A	Classroom 103 Closet	yes	W4	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no		
1	1	103A	Classroom 103 Closet	yes	Ceiling	Concrete	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no		
1	1	103A	Classroom 103 Closet	yes	Floor	Concrete	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no		
1	1	105A	Head Start Office	yes	W1	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no		
1	1	105A	Head Start Office	yes	W2	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no		
1	1	105A	Head Start Office	yes	W3	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no		
1	1	105A	Head Start Office	yes	W4	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no		

|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|

			School District of Philadelphia																					
			Name of Inspector: Ryan Hutsell		Lead Safe Certification Assessment Report																			
			Inspection Company: Synertech, Inc.		Cramp School																			
E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	Lead Concentrati on (% wt)	Lead in Paint Chips by Flame AAS Analysis Results (positive / negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes					
1	1	109D	Classroom 109 Small Closet adjacent to Entrance	yes	W3	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no						
1	1	109D	Classroom 109 Small Closet adjacent to Entrance	yes	Shelves	Wood	Green	Friction	4	N/A	Positive	None	0	N/A	Partially Inaccessible	No	no	no						
1	1	109D	Classroom 109 Small Closet adjacent to Entrance	yes	W4	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no						
1	1	109D	Classroom 109 Small Closet adjacent to Entrance	yes	Ceiling	Concrete	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no						
1	1	109D	Classroom 109 Small Closet adjacent to Entrance	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no						
1	1	111	Classroom 111	yes	W1	CMU	White	None	0	0	Negative	None	0	Negative	Partially Inaccessible	No	no	no	According to the 11/30/2020 classroom modernization specification 111 is part of the project. -JD					
1	1	111	Classroom 111	yes	Door Frame	Metal	Blue	Chipping	2	0.12	Negative	None	0	N/A	Prior to Repair	No	no	no	According to the 11/30/2020 classroom modernization specification 111 is part of the project. -JD					
1	1	111	Classroom 111	yes	Door	Metal	Blue	Chipping	2	0.4	Negative	None	0	N/A	Prior to Repair	No	no	no	According to the 11/30/2020 classroom modernization specification 111 is part of the project. -JD					
1	1	111	Classroom 111	yes	Sink Cabinet	Wood	Black	Chipping	4	0.1	Negative	None	0	N/A	Prior to Repair	No	no	no	According to the 11/30/2020 classroom modernization specification 111 is part of the project. -JD					
1	1	111	Classroom 111	yes	Sink Cabinet	Wood	Blue	Chipping	8	0.34	Negative	None	0	N/A	Prior to Repair	No	no	no	According to the 11/30/2020 classroom modernization specification 111 is part of the project. -JD					
1	1	111	Classroom 111	yes	W2	CMU	White	None	0	0	Negative	None	0	Negative	Partially Inaccessible	No	no	no	According to the 11/30/2020 classroom modernization specification 111 is part of the project. -JD					
1	1	111	Classroom 111	yes	Door Frame	Metal	White	Chipping	2	0.12	Negative	None	0	N/A	Prior to Repair	No	no	no	According to the 11/30/2020 classroom modernization specification 111 is part of the project. -JD					
1	1	111	Classroom 111	yes	Door	Metal	Green	Chipping	2	1.3	Positive	None	0	N/A	Prior to Repair	No	no	no	According to the 11/30/2020 classroom modernization specification 111 is part of the project. -JD					
1	1	111	Classroom 111	yes	Door Frame	Metal	Blue	Chipping	2	0.1	Negative	None	0	N/A	Prior to Repair	No	no	no	According to the 11/30/2020 classroom modernization specification 111 is part of the project. -JD					
1	1	111	Classroom 111	yes	Door	Metal	Blue	Chipping	2	0.2	Negative	None	0	N/A	Prior to Repair	No	no	no	According to the 11/30/2020 classroom modernization specification 111 is part of the project. -JD					
1	1	111	Classroom 111	yes	W3	CMU	White	None	0	0	Negative	None	0	Negative	Partially Inaccessible	No	no	no	According to the 11/30/2020 classroom modernization specification 111 is part of the project. -JD					
1	1	111	Classroom 111	yes	Door	Metal	Green	Chipping	2	1.5	Positive	None	0	N/A	Prior to Repair	No	no	no	According to the 11/30/2020 classroom modernization specification 111 is part of the project. -JD					
1	1	111	Classroom 111	yes	Door	Metal	Brown	Chipping	2	0.21	Negative	None	0	N/A	Prior to Repair	No	no	no	According to the 11/30/2020 classroom modernization specification 111 is part of the project. -JD					
1	1	111	Classroom 111	yes	Pipe	Metal	White	Chipping	4	0.15	Negative	None	0	N/A	Prior to Repair	No	no	no	According to the 11/30/2020 classroom modernization specification 111 is part of the project. -JD					
1	1	111	Classroom 111	yes	W4	CMU	White	None	0	0	Negative	None	0	Negative	Partially Inaccessible	No	no	no	According to the 11/30/2020 classroom modernization specification 111 is part of the project. -JD					
1	1	111	Classroom 111	yes	Shelves	Wood	Blue	Friction	12	0.32	Negative	None	0	N/A	Prior to Repair	No	no	no	According to the 11/30/2020 classroom modernization specification 111 is part of the project. -JD					
1	1	111	Classroom 111	yes	Ceiling	Plaster	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	According to the 11/30/2020 classroom modernization specification 111 is part of the project. -JD					
1	1	111	Classroom 111	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	According to the 11/30/2020 classroom modernization specification 111 is part of the project. -JD					
1	1	111A	Classroom 111 Closet adjacent to Restroom	yes	W1	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no	According to the 11/30/2020 classroom modernization specification 111 is part of the project. -JD					
1	1	111A	Classroom 111 Closet adjacent to Restroom	yes	W2	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no	According to the 11/30/2020 classroom modernization specification 111 is part of the project. -JD					
1	1	111A	Classroom 111 Closet adjacent to Restroom	yes	W3	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no	According to the 11/30/2020 classroom modernization specification 111 is part of the project. -JD					
1	1	111A	Classroom 111 Closet adjacent to Restroom	yes	Shelves	Wood	Green	Friction	4	1.4	Positive	None	0	N/A	Prior to Repair	No	no	no	According to the 11/30/2020 classroom modernization specification 111 is part of the project. -JD					

					School District of Philadelphia															
			Name of Inspector: Ryan Hutsell		Lead Safe Certification Assessment Report							Inspection Dates: 05/03-28/21								
			Inspection Company: Synertech, Inc.		Cramp School							ULCS# 5470								
E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	Lead Concentrati on (% wt)	Lead in Paint Chips by Flame AAS Analysis Results (positive / negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes	
1	1	111A	Classroom 111 Closet adjacent to Restroom	yes	W4	CMU	White	None	0	0	Negative	None	0	Negative	Partially Inaccessible	No	no	no	According to the 11/30/2020 classroom modernization specification 111 is part of the project. -JD	
1	1	111A	Classroom 111 Closet adjacent to Restroom	yes	Ceiling	Concrete	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	According to the 11/30/2020 classroom modernization specification 111 is part of the project. -JD	
1	1	111A	Classroom 111 Closet adjacent to Restroom	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	According to the 11/30/2020 classroom modernization specification 111 is part of the project. -JD	
1	1	111B	Classrooms 111 and 113 Restroom	yes	W1	CMU	White	None	0	N/A	N/A	None	0	Negative	No	No	no	no	According to the 11/30/2020 classroom modernization specification 111 is part of the project. -JD	
1	1	111B	Classrooms 111 and 113 Restroom	yes	Door Frame	Metal	Green	Chipping	2	0.2	Negative	None	0	N/A	Prior to Repair	No	no	no	According to the 11/30/2020 classroom modernization specification 111 is part of the project. -JD	
1	1	111B	Classrooms 111 and 113 Restroom	yes	Door	Metal	Green	Chipping	2	1.3	Positive	None	0	N/A	Prior to Repair	No	no	no	According to the 11/30/2020 classroom modernization specification 111 is part of the project. -JD	
1	1	111B	Classrooms 111 and 113 Restroom	yes	W2	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	According to the 11/30/2020 classroom modernization specification 111 is part of the project. -JD	
1	1	111B	Classrooms 111 and 113 Restroom	yes	W3	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	According to the 11/30/2020 classroom modernization specification 111 is part of the project. -JD	
1	1	111B	Classrooms 111 and 113 Restroom	yes	Door Frame	Metal	Green	Chipping	2	0.12	Negative	None	0	N/A	Prior to Repair	No	no	no	According to the 11/30/2020 classroom modernization specification 111 is part of the project. -JD	
1	1	111B	Classrooms 111 and 113 Restroom	yes	Door	Metal	Green	Chipping	2	1.1	Positive	None	0	N/A	Prior to Repair	No	no	no	According to the 11/30/2020 classroom modernization specification 111 is part of the project. -JD	
1	1	111B	Classrooms 111 and 113 Restroom	yes	W4	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	According to the 11/30/2020 classroom modernization specification 111 is part of the project. -JD	
1	1	111B	Classrooms 111 and 113 Restroom	yes	Ceiling	Plaster	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	According to the 11/30/2020 classroom modernization specification 111 is part of the project. -JD	
1	1	111B	Classrooms 111 and 113 Restroom	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	According to the 11/30/2020 classroom modernization specification 111 is part of the project. -JD	
1	1	NP3	Classroom 111 Closet adjacent to Exterior Entrance	yes	W1	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no	According to the 11/30/2020 classroom modernization specification 111 is part of the project. -JD	
1	1	NP3	Classroom 111 Closet adjacent to Exterior Entrance	yes	W2	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no	According to the 11/30/2020 classroom modernization specification 111 is part of the project. -JD	
1	1	NP3	Classroom 111 Closet adjacent to Exterior Entrance	yes	W3	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no	According to the 11/30/2020 classroom modernization specification 111 is part of the project. -JD	
1	1	NP3	Classroom 111 Closet adjacent to Exterior Entrance	yes	Shelves	Wood	Green	Friction	4	1.2	Positive	None	0	N/A	Prior to Repair	No	no	no	According to the 11/30/2020 classroom modernization specification 111 is part of the project. -JD	
1	1	NP3	Classroom 111 Closet adjacent to Exterior Entrance	yes	W4	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no	According to the 11/30/2020 classroom modernization specification 111 is part of the project. -JD	
1	1	NP3	Classroom 111 Closet adjacent to Exterior Entrance	yes	Ceiling	Concrete	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	According to the 11/30/2020 classroom modernization specification 111 is part of the project. -JD	
1	1	NP3	Classroom 111 Closet adjacent to Exterior Entrance	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	According to the 11/30/2020 classroom modernization specification 111 is part of the project. -JD	
1	1	111C	Classroom 111 Closet adjacent to Hallway Entrance	yes	W1	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no	According to the 11/30/2020 classroom modernization specification 111 is part of the project. -JD	
1	1	111C	Classroom 111 Closet adjacent to Hallway Entrance	yes	W2	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no	According to the 11/30/2020 classroom modernization specification 111 is part of the project. -JD	
1	1	111C	Classroom 111 Closet adjacent to Hallway Entrance	yes	W3	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no	According to the 11/30/2020 classroom modernization specification 111 is part of the project. -JD	
1	1	111C	Classroom 111 Closet adjacent to Hallway Entrance	yes	Shelves	Wood	Green	Friction	4	1.5	Positive	None	0	N/A	Prior to Repair	No	no	no	According to the 11/30/2020 classroom modernization specification 111 is part of the project. -JD	
1	1	111C	Classroom 111 Closet adjacent to Hallway Entrance	yes	W4	CMU	White	None	0	0	Negative	None	0	Negative	Partially Inaccessible	No	no	no	According to the 11/30/2020 classroom modernization specification 111 is part of the project. -JD	

			School District of Philadelphia																
			Lead Safe Certification Assessment Report																
			Cramp School																
Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	Lead Concentration (% wt)	Lead in Paint Chips by Flame AAS Analysis Results (positive / negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes
1	1	111C	Classroom 111 Closet adjacent to Hallway Entrance	yes	Ceiling	Concrete	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	According to the 11/30/2020 classroom modernization specification 111 is part of the project. -JD
1	1	111C	Classroom 111 Closet adjacent to Hallway Entrance	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	According to the 11/30/2020 classroom modernization specification 111 is part of the project. -JD
1	1	113	Classroom 113	yes	W1	CMU	White	None	0	N/A	N/A	None	0	Negative	No	No	no	no	According to the 11/30/2020 classroom modernization specification 113 is part of the project. -JD
1	1	113	Classroom 113	yes	Door Frame	Metal	Blue	Chipping	2	0.2	Negative	None	0	N/A	Prior to Repair	No	no	no	According to the 11/30/2020 classroom modernization specification 113 is part of the project. -JD
1	1	113	Classroom 113	yes	Door	Metal	Blue	Chipping	2	0.3	Negative	None	0	N/A	Prior to Repair	No	no	no	According to the 11/30/2020 classroom modernization specification 113 is part of the project. -JD
1	1	113	Classroom 113	yes	Sink Cabinet	Wood	N/A	Chipping	4	N/A	Positive	None	0	N/A	Prior to Repair	No	no	no	According to the 11/30/2020 classroom modernization specification 113 is part of the project. -JD
1	1	113	Classroom 113	yes	W2	CMU	White	None	0	N/A	N/A	None	0	Negative	No	No	no	no	According to the 11/30/2020 classroom modernization specification 113 is part of the project. -JD
1	1	113	Classroom 113	yes	Shelves	Wood	Red	Friction	10	1.7	Positive	None	0	N/A	Prior to Repair	No	no	no	According to the 11/30/2020 classroom modernization specification 113 is part of the project. -JD
1	1	113	Classroom 113	yes	W3	CMU	White	None	0	N/A	N/A	None	0	Negative	No	No	no	no	According to the 11/30/2020 classroom modernization specification 113 is part of the project. -JD
1	1	113	Classroom 113	yes	Door Frame	Metal	Brown	Chipping	1	0.16	Negative	None	0	N/A	Prior to Repair	No	no	no	According to the 11/30/2020 classroom modernization specification 113 is part of the project. -JD
1	1	113	Classroom 113	yes	Door	Metal	Brown	Chipping	1	0.11	Negative	None	0	N/A	Prior to Repair	No	no	no	According to the 11/30/2020 classroom modernization specification 113 is part of the project. -JD
1	1	113	Classroom 113	yes	W4	CMU	White	None	0	N/A	N/A	None	0	Positive	No	No	no	no	According to the 11/30/2020 classroom modernization specification 113 is part of the project. -JD
1	1	113	Classroom 113	yes	Panel Door	Metal	Grey	Chipping	2	0.1	Negative	None	0	N/A	Prior to Repair	No	no	no	According to the 11/30/2020 classroom modernization specification 113 is part of the project. -JD
1	1	113	Classroom 113	yes	Door Frame	Metal	White	Chipping	1	0.15	Negative	None	0	N/A	Prior to Repair	No	no	no	According to the 11/30/2020 classroom modernization specification 113 is part of the project. -JD
1	1	113	Classroom 113	yes	Door	Metal	Blue	Chipping	1	0	Negative	None	0	N/A	Prior to Repair	No	no	no	According to the 11/30/2020 classroom modernization specification 113 is part of the project. -JD
1	1	113	Classroom 113	yes	Ceiling	Concrete	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	According to the 11/30/2020 classroom modernization specification 113 is part of the project. -JD
1	1	113	Classroom 113	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	According to the 11/30/2020 classroom modernization specification 113 is part of the project. -JD
1	1	113A	Classroom 113 Closet adjacent to Restroom	yes	W1	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no	According to the 11/30/2020 classroom modernization specification 113 is part of the project. -JD
1	1	113A	Classroom 113 Closet adjacent to Restroom	yes	W2	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no	According to the 11/30/2020 classroom modernization specification 113 is part of the project. -JD
1	1	113A	Classroom 113 Closet adjacent to Restroom	yes	W3	CMU	White	None	0	0	Negative	None	0	Positive	Partially Inaccessible	No	no	no	According to the 11/30/2020 classroom modernization specification 113 is part of the project. -JD
1	1	113A	Classroom 113 Closet adjacent to Restroom	yes	Shelves	Wood	Green	Friction	4	1.2	Positive	None	0	N/A	Prior to Repair	No	no	no	According to the 11/30/2020 classroom modernization specification 113 is part of the project. -JD
1	1	113A	Classroom 113 Closet adjacent to Restroom	yes	W4	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no	According to the 11/30/2020 classroom modernization specification 113 is part of the project. -JD
1	1	113A	Classroom 113 Closet adjacent to Restroom	yes	Ceiling	Concrete	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	According to the 11/30/2020 classroom modernization specification 113 is part of the project. -JD
1	1	113A	Classroom 113 Closet adjacent to Restroom	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	According to the 11/30/2020 classroom modernization specification 113 is part of the project. -JD
1	1	113C	Classroom 113 Closet adjacent to Entrance	yes	W1	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no	According to the 11/30/2020 classroom modernization specification 113 is part of the project. -JD

					School District of Philadelphia																
			Name of Inspector: Ryan Hutsell		Lead Safe Certification Assessment Report								Inspection Dates: 05/03-28/21								
			Inspection Company: Synertech, Inc.		Cramp School								ULCS# 5470								
E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	Lead Concentrati on (% wt)	Lead in Paint Chips by Flame AAS Analysis Results (positive / negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes		
1	1	113C	Classroom 113 Closet adjacent to Entrance	yes	W2	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no	According to the 11/30/2020 classroom modernization specification 113 is part of the project. -JD		
1	1	113C	Classroom 113 Closet adjacent to Entrance	yes	W3	CMU	White	None	0	0	Negative	None	0	Positive	Partially Inaccessible	No	no	no	According to the 11/30/2020 classroom modernization specification 113 is part of the project. -JD		
1	1	113C	Classroom 113 Closet adjacent to Entrance	yes	Shelves	Wood	Green	Friction	4	1.2	Positive	None	0	N/A	Prior to Repair	No	no	no	According to the 11/30/2020 classroom modernization specification 113 is part of the project. -JD		
1	1	113C	Classroom 113 Closet adjacent to Entrance	yes	W4	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no	According to the 11/30/2020 classroom modernization specification 113 is part of the project. -JD		
1	1	113C	Classroom 113 Closet adjacent to Entrance	yes	Ceiling	Concrete	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	According to the 11/30/2020 classroom modernization specification 113 is part of the project. -JD		
1	1	113C	Classroom 113 Closet adjacent to Entrance	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	According to the 11/30/2020 classroom modernization specification 113 is part of the project. -JD		
1	1	H17B	Custodial Closet across from Classroom 103	no	W1	CMU	White	Chipping	4	0	Negative	None	0	N/A	Prior to Repair	No	no	no			
1	1	H17B	Custodial Closet across from Classroom 103	no	Door Frame	Metal	Blue	Chipping	1	0.13	Negative	None	0	N/A	Prior to Repair	No	no	no			
1	1	H17B	Custodial Closet across from Classroom 103	no	Door	Metal	Blue	Chipping	1	0.09	Negative	None	0	N/A	Prior to Repair	No	no	no			
1	1	H17B	Custodial Closet across from Classroom 103	no	W2	CMU	White	Chipping	4	0	Negative	None	0	N/A	Prior to Repair	No	no	no			
1	1	H17B	Custodial Closet across from Classroom 103	no	W3	CMU	White	Chipping	4	0	Negative	None	0	N/A	Prior to Repair	No	no	no			
1	1	H17B	Custodial Closet across from Classroom 103	no	Pipes	Metal	White	Flaking	4	0	Negative	None	0	N/A	Prior to Repair	No	no	no			
1	1	H17B	Custodial Closet across from Classroom 103	no	W4	CMU	White	Chipping	4	0	Negative	None	0	N/A	Prior to Repair	No	no	no			
1	1	H17B	Custodial Closet across from Classroom 103	no	Sink	Porcelain	Grey	Flaking	4	0	Negative	None	0	N/A	Prior to Repair	No	no	no			
1	1	H17B	Custodial Closet across from Classroom 103	no	Ceiling	Concrete	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no			
1	1	H17B	Custodial Closet across from Classroom 103	no	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no			
1	1	115	Gym	yes	W1	CMU	Purple	Chipping	20	0	Negative	None	0	N/A	Prior to Repair	No	no	no			
1	1	115	Gym	yes	W1	CMU	White	Chipping	10	0	Negative	None	0	N/A	Prior to Repair	No	no	no			
1	1	115	Gym	yes	W1	CMU	Red	Chipping	10	0	Negative	None	0	N/A	Prior to Repair	No	no	no			
1	1	115	Gym	yes	Door Frame	Metal	Green	Chipping	4	0.2	Negative	None	0	N/A	Prior to Repair	No	no	no			
1	1	115	Gym	yes	Door	Metal	Green	Chipping	4	0.31	Negative	None	0	N/A	Prior to Repair	No	no	no			
1	1	115	Gym	yes	Backboard	Wood	White	Chipping	4	0.15	Negative	None	0	N/A	Prior to Repair	No	no	no			
1	1	115	Gym	yes	W2	CMU	Yellow	Chipping	10	0	Negative	None	0	N/A	Prior to Repair	No	no	no			
1	1	115	Gym	yes	W2	CMU	White	Chipping	10	0	Negative	None	0	N/A	Prior to Repair	No	no	no			
1	1	115	Gym	yes	Conduit	Metal	White	Chipping	5	0.2	Negative	None	0	N/A	Prior to Repair	No	no	no			
1	1	115	Gym	yes	Door Frame	Metal	White	Chipping	2	0.16	Negative	None	0	N/A	Prior to Repair	No	no	no			
1	1	115	Gym	yes	Door	Metal	White	Chipping	2	0.1	Negative	None	0	N/A	Prior to Repair	No	no	no			
1	1	115	Gym	yes	Backboard	Wood	White	Chipping	4	0	Negative	None	0	N/A	Prior to Repair	No	no	no			
1	1	115	Gym	yes	W3	CMU	Purple	Chipping	30	0	Negative	None	0	N/A	Prior to Repair	No	no	no			
1	1	115	Gym	yes	W3	CMU	White	Chipping	5	0	Negative	None	0	N/A	Prior to Repair	No	no	no			
1	1	115	Gym	yes	W3	CMU	Red	Chipping	5	0	Negative	None	0	N/A	Prior to Repair	No	no	no			
1	1	115	Gym	yes	Conduit	Metal	White	Flaking	12	0.14	Negative	None	0	N/A	Prior to Repair	No	no	no			
1	1	115	Gym	yes	W4	CMU	Yellow	Chipping	20	0	Negative	None	0	N/A	Prior to Repair	No	no	no			
1	1	115	Gym	yes	W4	CMU	White	Cracking	20	0	Negative	None	0	N/A	Prior to Repair	No	no	no			
1	1	115	Gym	yes	Backboard	Wood	White	Chipping	4	0	Negative	None	0	N/A	Prior to Repair	No	no	no			
1	1	115	Gym	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	Drop ceiling - missing ceiling tiles		
1	1	115	Gym	yes	Truss	Metal	Yellow	Flaking	8	N/A	Positive	None	0	N/A	Prior to Repair	No	no	no	Same as truss above stage (+); too high to reach - assumed positive. Missing ceiling tiles to be replaced.		
1	1	115	Gym	yes	Duct	Metal	White	Flaking	30	No Access	No Access	None	0	N/A	Prior to Repair	No	no	no	Too high to reach		
1	1	115	Gym	yes	Air Handling Unit	Metal	Green	Flaking	30	No Access	No Access	None	0	N/A	Prior to Repair	No	no	no	Too high to reach		
1	1	115	Gym	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	Wood		
1	1	115B	Gym Storage Room adjacent Entrance	yes	W1	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no			
1	1	115B	Gym Storage Room adjacent Entrance	yes	Door Frame	Metal	White	Chipping	1	0.12	Negative	None	0	N/A	Prior to Repair	No	no	no			
1	1	115B	Gym Storage Room adjacent Entrance	yes	Door	Metal	Green	Chipping	1	0.17	Negative	None	0	N/A	Prior to Repair	No	no	no			
1	1	115B	Gym Storage Room adjacent Entrance	yes	W2	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no			

					School District of Philadelphia																	
			Name of Inspector: Ryan Hutsell		Lead Safe Certification Assessment Report									Inspection Dates: 05/03-28/21								
			Inspection Company: Synertech, Inc.		Cramp School									ULCS# 5470								
E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	Lead Concentrati on (% wt)	Lead in Paint Chips by Flame AAS Analysis Results (positive / negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes			
1	1	115B	Gym Storage Room adjacent Entrance	yes	W3	Sheetrock	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no				
1	1	115B	Gym Storage Room adjacent Entrance	yes	W4	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no				
1	1	115B	Gym Storage Room adjacent Entrance	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	Negative	None	0	N/A	No	No	no	no	Drop ceiling			
1	1	115B	Gym Storage Room adjacent Entrance	yes	Floor	N/A	N/A	N/A	N/A	N/A	Negative	None	0	N/A	No	No	no	no	9"x9" floor tiles			
1	1	115A	Gym Office	yes	W1	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no				
1	1	115A	Gym Office	yes	Window Frame	Metal	White	Chipping	2	0.15	Negative	None	0	N/A	Prior to Repair	No	no	no				
1	1	115A	Gym Office	yes	Door Frame	Metal	White	Chipping	2	0.1	Negative	None	0	N/A	Prior to Repair	No	no	no				
1	1	115A	Gym Office	yes	Door	Metal	Green	Chipping	2	0.12	Negative	None	0	N/A	Prior to Repair	No	no	no				
1	1	115A	Gym Office	yes	W2	CMU	White	None	0	0	Negative	None	0	N/A	No	No	no	no				
1	1	115A	Gym Office	yes	Door	Wood	Green	Chipping	1	0.4	Negative	None	0	N/A	Prior to Repair	No	no	no				
1	1	115A	Gym Office	yes	W3	CMU	White	None	0	0	Negative	None	0	N/A	No	No	no	no				
1	1	115A	Gym Office	yes	Conduit	Metal	White	Flaking	2	0.12	Negative	None	0	N/A	Prior to Repair	No	no	no				
1	1	115A	Gym Office	yes	Door	Wood	Red	Chipping	1	0.32	Negative	None	0	N/A	Prior to Repair	No	no	no				
1	1	115A	Gym Office	yes	Closet Shelves	Wood	Green	Chipping	1	0.17	Negative	None	0	N/A	Prior to Repair	No	no	no				
1	1	115A	Gym Office	yes	W4	CMU	White	None	0	0	Negative	None	0	N/A	No	No	no	no				
1	1	115A	Gym Office	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	Drop ceiling			
1	1	115A	Gym Office	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	9"x9" floor tiles			
1	1	115G	Gym Office Restroom	yes	W1	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no				
1	1	115G	Gym Office Restroom	yes	W2	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no				
1	1	115G	Gym Office Restroom	yes	W3	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no				
1	1	115G	Gym Office Restroom	yes	W4	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no				
1	1	115G	Gym Office Restroom	yes	Ceiling	Plaster	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no				
1	1	115G	Gym Office Restroom	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	Ceramic Tiles			
1	1	115H	Vestibule outside Gym Boy's Restroom	yes	W1	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no				
1	1	115H	Vestibule outside Gym Boy's Restroom	yes	W2	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no				
1	1	115H	Vestibule outside Gym Boy's Restroom	yes	W3	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no				
1	1	115H	Vestibule outside Gym Boy's Restroom	yes	W4	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no				
1	1	115H	Vestibule outside Gym Boy's Restroom	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	Drop ceiling			
1	1	115H	Vestibule outside Gym Boy's Restroom	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	9"x9" floor tiles			
1	1	115E	Gym Boy's Restroom	yes	W1	CMU	White	Chipping	5	0	Negative	None	0	N/A	Prior to Repair	No	no	no				
1	1	115E	Gym Boy's Restroom	yes	Door Frame	Metal	White	Chipping	2	0.1	Negative	None	0	N/A	Prior to Repair	No	no	no				
1	1	115E	Gym Boy's Restroom	yes	Door	Metal	Green	Chipping	2	0.1	Negative	None	0	N/A	Prior to Repair	No	no	no				
1	1	115E	Gym Boy's Restroom	yes	W2	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no				
1	1	115E	Gym Boy's Restroom	yes	W3	Sheetrock	White	Chipping	5	0	Negative	None	0	N/A	Prior to Repair	No	no	no				
1	1	115E	Gym Boy's Restroom	yes	W4	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no				
1	1	115E	Gym Boy's Restroom	yes	Ceiling	Plaster	White	Efflorescence	8	0	Negative	None	0	N/A	Prior to Repair	No	no	no				
1	1	115E	Gym Boy's Restroom	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	Ceramic Tiles			
1	1	115E	Gym Boy's Restroom	yes	Baseboard	Concrete	Black	Chipping	2	0	Negative	None	0	N/A	Prior to Repair	No	no	no				
1	1	115I	Vestibule outside Gym Girl's Restroom	yes	W1	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no				
1	1	115I	Vestibule outside Gym Girl's Restroom	yes	W2	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no				
1	1	115I	Vestibule outside Gym Girl's Restroom	yes	W3	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no				
1	1	115I	Vestibule outside Gym Girl's Restroom	yes	W4	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no				
1	1	115I	Vestibule outside Gym Girl's Restroom	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	Drop ceiling			
1	1	115I	Vestibule outside Gym Girl's Restroom	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	9"x9" floor tiles			
1	1	115F	Gym Girl's Restroom	yes	W1	CMU	White	Chipping	5	0	Negative	None	0	N/A	Prior to Repair	No	no	no				
1	1	115F	Gym Girl's Restroom	yes	Door Frame	Metal	White	Chipping	2	0.1	Negative	None	0	N/A	Prior to Repair	No	no	no				
1	1	115F	Gym Girl's Restroom	yes	Door	Metal	Green	Chipping	2	0.1	Negative	None	0	N/A	Prior to Repair	No	no	no				
1	1	115F	Gym Girl's Restroom	yes	W2	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no				
1	1	115F	Gym Girl's Restroom	yes	W3	Sheetrock	White	Chipping	5	0	Negative	None	0	N/A	Prior to Repair	No	no	no				
1	1	115F	Gym Girl's Restroom	yes	W4	CMU	White	None	0	0	Negative	None	0	N/A	No	No	no	no				
1	1	115F	Gym Girl's Restroom	yes	Ceiling	Plaster	White	Efflorescence	8	0	Negative	None	0	N/A	Prior to Repair	No	no	no				
1	1	115F	Gym Girl's Restroom	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no				
1	1	115F	Gym Girl's Restroom	yes	Baseboard	Concrete	Black	Chipping	2	0	Negative	None	0	N/A	Prior to Repair	No	no	no				

					School District of Philadelphia																
			Name of Inspector: Ryan Hutsell		Lead Safe Certification Assessment Report							Inspection Dates: 05/03-28/21									
														Inspection Company: Synertech, Inc.		Cramp School					
Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	Lead Concentration (% wt)	Lead in Paint Chips by Flame AAS Analysis Results (positive / negative)	Debris Present (describe location)	Quantity (sf)								Asbestos Paint sampled (positive/negative)
1	1	115D	Gym Custodial Closet near Restrooms	yes	W1	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no			
1	1	115D	Gym Custodial Closet near Restrooms	yes	Door Frame	Metal	Green	Chipping	2	0.14	Negative	None	0	N/A	Prior to Repair	No	no	no			
1	1	115D	Gym Custodial Closet near Restrooms	yes	Door	Metal	Green	Chipping	2	0.25	Negative	None	0	N/A	Prior to Repair	No	no	no			
1	1	115D	Gym Custodial Closet near Restrooms	yes	Conduit	Metal	White	Flaking	2	0.2	Negative	None	0	N/A	Prior to Repair	No	no	no			
1	1	115D	Gym Custodial Closet near Restrooms	yes	W2	CMU	White	Chipping	3	0	Negative	None	0	N/A	Prior to Repair	No	no	no			
1	1	115D	Gym Custodial Closet near Restrooms	yes	W3	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no			
1	1	115D	Gym Custodial Closet near Restrooms	yes	Sink	Ceramic	Grey	Flaking	4	0	Negative	None	0	N/A	Prior to Repair	No	no	no			
1	1	115D	Gym Custodial Closet near Restrooms	yes	Pipe	Metal	White	Chipping	2	0.2	Negative	None	0	N/A	Prior to Repair	No	no	no			
1	1	115D	Gym Custodial Closet near Restrooms	yes	W4	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no			
1	1	115D	Gym Custodial Closet near Restrooms	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	Drop ceiling		
1	1	115D	Gym Custodial Closet near Restrooms	yes	Floor	Concrete	Grey	None	0	N/A	N/A	None	0	N/A	No	No	no	no			
1	1	116	Auditorium/Cafeteria	yes	W1	CMU	White	Chipping	2	0	Negative	None	0	N/A	Prior to Repair	No	no	no			
1	1	116	Auditorium/Cafeteria	yes	W1	CMU	Blue	Chipping	5	0	Negative	None	0	N/A	Prior to Repair	No	no	no			
1	1	116	Auditorium/Cafeteria	yes	Chair Rail	Wood	White	Chipping	2	0	Negative	None	0	N/A	Prior to Repair	No	no	no			
1	1	116	Auditorium/Cafeteria	yes	W2	CMU	White	Chipping	2	0	Negative	None	0	N/A	Prior to Repair	No	no	no			
1	1	116	Auditorium/Cafeteria	yes	W2	CMU	Blue	Chipping	5	0	Negative	None	0	N/A	Prior to Repair	No	no	no			
1	1	116	Auditorium/Cafeteria	yes	Door Frame	Metal	White	Chipping	2	0.15	Negative	None	0	N/A	Prior to Repair	No	no	no			
1	1	116	Auditorium/Cafeteria	yes	Door	Wood	Blue	Chipping	2	0.8	Positive	None	0	N/A	Prior to Repair	No	no	no			
1	1	116	Auditorium/Cafeteria	yes	Door	Wood	Green	Chipping	2	1.1	Positive	None	0	N/A	Prior to Repair	No	no	no			
1	1	116	Auditorium/Cafeteria	yes	Door	Wood	Red	Chipping	2	1.2	Positive	None	0	N/A	Prior to Repair	No	no	no			
1	1	116	Auditorium/Cafeteria	yes	W3	CMU	White	Chipping	2	0	Negative	None	0	N/A	Prior to Repair	No	no	no			
1	1	116	Auditorium/Cafeteria	yes	W3	CMU	Blue	Chipping	5	0	Negative	None	0	N/A	Prior to Repair	No	no	no			
1	1	116	Auditorium/Cafeteria	yes	Radiator	Metal	Brown	Chipping	100	0	Negative	None	0	N/A	Prior to Repair	No	no	no			
1	1	116	Auditorium/Cafeteria	yes	Door Frame	Metal	Brown	Chipping	2	0	Negative	None	0	N/A	Prior to Repair	No	no	no			
1	1	116	Auditorium/Cafeteria	yes	Door	Metal	Brown	Chipping	2	0	Negative	None	0	N/A	Prior to Repair	No	no	no			
1	1	116	Auditorium/Cafeteria	yes	W4	CMU	White	Chipping	2	0	Negative	None	0	N/A	Prior to Repair	No	no	no			
1	1	116	Auditorium/Cafeteria	yes	W4	CMU	Blue	Chipping	5	0	Negative	None	0	N/A	Prior to Repair	No	no	no			
1	1	116	Auditorium/Cafeteria	yes	Radiator	Metal	Brown	Chipping	30	0	Negative	None	0	N/A	Prior to Repair	No	no	no			
1	1	116	Auditorium/Cafeteria	yes	Door Frame	Metal	Brown	Chipping	2	0	Negative	None	0	N/A	Prior to Repair	No	no	no			
1	1	116	Auditorium/Cafeteria	yes	Door	Metal	Brown	Chipping	2	0	Negative	None	0	N/A	Prior to Repair	No	no	no			
1	1	116	Auditorium/Cafeteria	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	Drop ceiling		
1	1	116	Auditorium/Cafeteria	yes	Deck	Concrete	Yellow	Flaking	20	N/A	Positive	None	0	N/A	Prior to Repair	No	no	no	Ceiling too high to reach, assumed LBP. Replace missing/damaged ceiling tiles to conceal LBP associated with ceiling.		
1	1	116	Auditorium/Cafeteria	yes	Truss	Metal	Yellow	Flaking	20	2.9	Positive	None	0	N/A	Prior to Repair	No	no	no	Replace missing/damaged ceiling tiles to conceal LBP associated with ceiling.		
1	1	116	Auditorium/Cafeteria	yes	Pendant Light Fixtures	Metal	Yellow	Chipping	32	0.2	Negative	None	0	N/A	Prior to Repair	No	no	no			
1	1	116	Auditorium/Cafeteria	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	9"x9" floor tiles		
1	1	116	Auditorium/Cafeteria	yes	Baseboard	Terracotta	Black	Chipping	10	0	Negative	None	0	N/A	Prior to Repair	No	no	no	Terracotta glaze >0.7 ug/cm^2; paint not LBP		
1	1	116A	Stage	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	No wall		
1	1	116A	Stage	yes	W2	CMU	White	Chipping	20	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no			
1	1	116A	Stage	yes	Door Frame	Metal	White	Chipping	2	0.16	Negative	None	0	N/A	Prior to Repair	No	no	no			
1	1	116A	Stage	yes	Door	Wood	Yellow	Chipping	2	1.9	Positive	None	0	N/A	Prior to Repair	No	no	no			
1	1	116A	Stage	yes	W3	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no			
1	1	116A	Stage	yes	W4	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no			
1	1	116A	Stage	yes	Door Frame	Metal	White	Chipping	2	0.12	Negative	None	0	N/A	Prior to Repair	No	no	no			
1	1	116A	Stage	yes	Door	Wood	Yellow	Chipping	2	1.6	Positive	None	0	N/A	Prior to Repair	No	no	no			
1	1	116A	Stage	yes	Ceiling	Concrete	Yellow	Flaking	20	1.5	Positive	None	0	N/A	Prior to Repair	No	no	no			
1	1	116A	Stage	yes	Truss	Metal	Yellow	Flaking	12	2	Positive	None	0	N/A	Prior to Repair	No	no	no			
1	1	116A	Stage	yes	Duct	Metal	Yellow	Flaking	20	1.4	Positive	None	0	N/A	Prior to Repair	No	no	no			
1	1	116A	Stage	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	Floor tiles		
1	1	116B	Auditorium/Cafeteria Storage Room	yes	W1	No Access	No Access	No Access	No Access	N/A	N/A	None	0	N/A	No Access	No	no	no			
1	1	116B	Auditorium/Cafeteria Storage Room	yes	W2	No Access	No Access	No Access	No Access	N/A	N/A	None	0	N/A	No Access	No	no	no			
1	1	116B	Auditorium/Cafeteria Storage Room	yes	W3	No Access	No Access	No Access	No Access	N/A	N/A	None	0	N/A	No Access	No	no	no			
1	1	116B	Auditorium/Cafeteria Storage Room	yes	W4	No Access	No Access	No Access	No Access	N/A	N/A	None	0	N/A	No Access	No	no	no			
1	1	116B	Auditorium/Cafeteria Storage Room	yes	Ceiling	No Access	No Access	No Access	No Access	N/A	N/A	None	0	N/A	No Access	No	no	no			
1	1	116B	Auditorium/Cafeteria Storage Room	yes	Floor	No Access	No Access	No Access	No Access	N/A	N/A	None	0	N/A	No Access	No	no	no			
1	1	112	Kitchen	yes	W1	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no			
1	1	112	Kitchen	yes	Door Frame	Metal	White	Chipping	2	0.1	Negative	None	0	N/A	Prior to Repair	No	no	no			
1	1	112	Kitchen	yes	Door	Wood	Red	Chipping	2	1.1	Positive	None	0	N/A	Prior to Repair	No	no	no			
1	1	112	Kitchen	yes	Door	Wood	Green	Chipping	2	1.2	Positive	None	0	N/A	Prior to Repair	No	no	no			
1	1	112	Kitchen	yes	W2	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no			
1	1	112	Kitchen	yes	Conduit	Metal	White	Chipping	2	0.21	Negative	None	0	N/A	Prior to Repair	No	no	no			
1	1	112	Kitchen	yes	W3	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no			
1	1	112	Kitchen	yes	Door Frame	Metal	White	Chipping	2	0.13	Negative	None	0	N/A	Prior to Repair	No	no	no			

			School District of Philadelphia																		
			Lead Safe Certification Assessment Report																		
			Cramp School																		
			Name of Inspector: Ryan Hutsell		Inspection Dates: 05/03-28/21																
			Inspection Company: Synertech, Inc.		ULCS# 5470																
E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	Lead Concentrati on (% wt)	Lead in Paint Chips by Flame AAS Analysis Results (positive / negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes		
1	1	112	Kitchen	yes	Door	Metal	Grey	Chipping	12	0.08	Negative	None	0	N/A	Prior to Repair	No	no	no			
1	1	112	Kitchen	yes	W4	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no			
1	1	112	Kitchen	yes	Door Frame	Metal	White	Chipping	2	0.1	Negative	None	0	N/A	Prior to Repair	No	no	no			
1	1	112	Kitchen	yes	Door	Metal	Grey	Chipping	2	0.14	Negative	None	0	N/A	Prior to Repair	No	no	no			
1	1	112	Kitchen	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	Drop ceiling		
1	1	112	Kitchen	yes	Floor	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no			
1	1	112A	Kitchen Office	yes	W1	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no			
1	1	112A	Kitchen Office	yes	W2	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no			
1	1	112A	Kitchen Office	yes	W3	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no			
1	1	112A	Kitchen Office	yes	W4	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no			
1	1	112A	Kitchen Office	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	Drop ceiling		
1	1	112A	Kitchen Office	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	Floor tiles		
1	1	112B	Kitchen Storage Room	yes	W1	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no			
1	1	112B	Kitchen Storage Room	yes	Cabinets/Shelves	Wood	Green	Friction	20	2.2	Positive	None	0	N/A	Prior to Repair	No	no	no			
1	1	112B	Kitchen Storage Room	yes	W2	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no			
1	1	112B	Kitchen Storage Room	yes	Cabinets/Shelves	Wood	Green	Friction	10	2.3	Positive	None	0	N/A	Prior to Repair	No	no	no			
1	1	112B	Kitchen Storage Room	yes	W3	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no			
1	1	112B	Kitchen Storage Room	yes	Cabinets/Shelves	Wood	Green	Friction	50	1.9	Positive	None	0	N/A	Prior to Repair	No	no	no			
1	1	112B	Kitchen Storage Room	yes	W4	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no			
1	1	112B	Kitchen Storage Room	yes	Cabinets/Shelves	Wood	Green	Friction	20	2.4	Positive	None	0	N/A	Prior to Repair	No	no	no			
1	1	112B	Kitchen Storage Room	yes	Ceiling	Concrete	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no			
1	1	112B	Kitchen Storage Room	yes	Duct	Metal	White	Flaking	5	0.15	Negative	None	0	N/A	Prior to Repair	No	no	no			
1	1	112B	Kitchen Storage Room	yes	Air Handling Unit	Metal	Green	Flaking	15	0.3	Negative	None	0	N/A	Prior to Repair	No	no	no			
1	1	112B	Kitchen Storage Room	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no			
1	1	112C	Kitchen Receiving Area	yes	W1	Concrete	White	Alligating	15	0	Negative	None	0	N/A	Prior to Repair	No	no	no			
1	1	112C	Kitchen Receiving Area	yes	Door Frame	Metal	White	Chipping	2	0.1	Negative	None	0	N/A	Prior to Repair	No	no	no			
1	1	112C	Kitchen Receiving Area	yes	Door	Wood	Green	Chipping	2	0.2	Negative	None	0	N/A	Prior to Repair	No	no	no			
1	1	112C	Kitchen Receiving Area	yes	W2	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no			
1	1	112C	Kitchen Receiving Area	yes	Door Frame	Metal	White	Chipping	2	0.12	Negative	None	0	N/A	Prior to Repair	No	no	no			
1	1	112C	Kitchen Receiving Area	yes	Door	Wood	Grey	Chipping	2	1.5	Positive	None	0	N/A	Prior to Repair	No	no	no			
1	1	112C	Kitchen Receiving Area	yes	Door Frame	Metal	Brown	Chipping	2	0.1	Negative	None	0	N/A	Prior to Repair	No	no	no			
1	1	112C	Kitchen Receiving Area	yes	Door	Metal	Brown	Chipping	2	0.12	Negative	None	0	N/A	Prior to Repair	No	no	no			
1	1	112C	Kitchen Receiving Area	yes	W3	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no			
1	1	112C	Kitchen Receiving Area	yes	Door Frame	Metal	Brown	Chipping	2	0.08	Negative	None	0	N/A	Prior to Repair	No	no	no			
1	1	112C	Kitchen Receiving Area	yes	Door	Metal	Brown	Chipping	2	0.14	Negative	None	0	N/A	Prior to Repair	No	no	no			
1	1	112C	Kitchen Receiving Area	yes	W4	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no			
1	1	112C	Kitchen Receiving Area	yes	Door Frame	Metal	Brown	Chipping	2	0	Negative	None	0	N/A	Prior to Repair	No	no	no			
1	1	112C	Kitchen Receiving Area	yes	Door	Metal	Brown	Chipping	2	0.15	Negative	None	0	N/A	Prior to Repair	No	no	no			
1	1	112C	Kitchen Receiving Area	yes	Ceiling	Concrete	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no			
1	1	112C	Kitchen Receiving Area	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no			
1	1	112D	Kitchen Restroom	yes	W1	CMU	Blue	None	0	N/A	N/A	None	0	N/A	No	No	no	no			
1	1	112D	Kitchen Restroom	yes	W2	CMU	Blue	None	0	N/A	N/A	None	0	N/A	No	No	no	no			
1	1	112D	Kitchen Restroom	yes	W3	Concrete	Blue	None	0	N/A	N/A	None	0	N/A	No	No	no	no			
1	1	112D	Kitchen Restroom	yes	W4	CMU	Blue	None	0	N/A	N/A	None	0	N/A	No	No	no	no			
1	1	112D	Kitchen Restroom	yes	Ceiling	Plaster	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no			
1	1	112D	Kitchen Restroom	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	Ceramic Tiles		
1	1	112E	Kitchen Storage/Change Out Room	yes	W1	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no			
1	1	112E	Kitchen Storage/Change Out Room	yes	Door Frame	Metal	White	Chipping	2	0.2	Negative	None	0	N/A	Prior to Repair	No	no	no			
1	1	112E	Kitchen Storage/Change Out Room	yes	Door	Wood	Yellow	Chipping	2	1.8	Positive	None	0	N/A	Prior to Repair	No	no	no			
1	1	112E	Kitchen Storage/Change Out Room	yes	W2	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no			
1	1	112E	Kitchen Storage/Change Out Room	yes	Door Frame	Metal	White	Chipping	2	0.15	Negative	None	0	N/A	Prior to Repair	No	no	no			
1	1	112E	Kitchen Storage/Change Out Room	yes	Door	Wood	Green	Chipping	2	1.4	Positive	None	0	N/A	Prior to Repair	No	no	no			
1	1	112E	Kitchen Storage/Change Out Room	yes	W3	Concrete	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no			
1	1	112E	Kitchen Storage/Change Out Room	yes	W4	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no			
1	1	112E	Kitchen Storage/Change Out Room	yes	Door Frame	Metal	Brown	Chipping	2	0.08	Negative	None	0	N/A	Prior to Repair	No	no	no			
1	1	112E	Kitchen Storage/Change Out Room	yes	Door	Metal	Brown	Chipping	2	0.12	Negative	None	0	N/A	Prior to Repair	No	no	no			
1	1	112E	Kitchen Storage/Change Out Room	yes	Ceiling	Concrete	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no			
1	1	112E	Kitchen Storage/Change Out Room	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	9"x9" Floor Tiles		

			School District of Philadelphia																		
			Name of Inspector: Ryan Hutsell		Lead Safe Certification Assessment Report						Inspection Dates: 05/03-28/21										
			Inspection Company: Synertech, Inc.		Cramp School						ULCS# 5470										
E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	Lead Concentrati on (% wt)	Lead in Paint Chips by Flame AAS Analysis Results (positive / negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes		
1	1	112F	Maintenance Storage Room adjacent to Kitchen	no	W1	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no			
1	1	112F	Maintenance Storage Room adjacent to Kitchen	no	W2	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no			
1	1	112F	Maintenance Storage Room adjacent to Kitchen	no	W3	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no			
1	1	112F	Maintenance Storage Room adjacent to Kitchen	no	W4	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no			
1	1	112F	Maintenance Storage Room adjacent to Kitchen	no	Ceiling	Concrete	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no			
1	1	112F	Maintenance Storage Room adjacent to Kitchen	no	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	9"x9" Floor Tiles		
1	1	H110	Hallway Between Classroom 110 and Kitchen Receiving Area	yes	W1	CMU	White	Chipping	2	0	Negative	None	0	N/A	Prior to Repair	No	no	no			
1	1	H110	Hallway Between Classroom 110 and Kitchen Receiving Area	yes	W1	Concrete	White	Chipping	2	0	Negative	None	0	N/A	Prior to Repair	No	no	no			
1	1	H110	Hallway Between Classroom 110 and Kitchen Receiving Area	yes	Elevator Door Frame	Metal	Blue	Chipping	2	1.2	Positive	None	0	N/A	Prior to Repair	No	no	no			
1	1	H110	Hallway Between Classroom 110 and Kitchen Receiving Area	yes	Elevator Door	Metal	Blue	Chipping	2	1.2	Positive	None	0	N/A	Prior to Repair	No	no	no			
1	1	H110	Hallway Between Classroom 110 and Kitchen Receiving Area	yes	W2	CMU	White	Chipping	1	0	Negative	None	0	N/A	Prior to Repair	No	no	no			
1	1	H110	Hallway Between Classroom 110 and Kitchen Receiving Area	yes	W2	Concrete	White	Chipping	1	0	Negative	None	0	N/A	Prior to Repair	No	no	no			
1	1	H110	Hallway Between Classroom 110 and Kitchen Receiving Area	yes	Door Frame	Metal	Blue	Chipping	2	0	Negative	None	0	N/A	Prior to Repair	No	no	no			
1	1	H110	Hallway Between Classroom 110 and Kitchen Receiving Area	yes	Door	Metal	Blue	Chipping	2	0	Negative	None	0	N/A	Prior to Repair	No	no	no			
1	1	H110	Hallway Between Classroom 110 and Kitchen Receiving Area	yes	W3	CMU	White	Chipping	2	0	Negative	None	0	N/A	Prior to Repair	No	no	no			
1	1	H110	Hallway Between Classroom 110 and Kitchen Receiving Area	yes	W3	Concrete	White	Chipping	2	0	Negative	None	0	N/A	Prior to Repair	No	no	no			
1	1	H110	Hallway Between Classroom 110 and Kitchen Receiving Area	yes	Door Frame	Metal	Brown	Chipping	2	0.1	Negative	None	0	N/A	Prior to Repair	No	no	no			
1	1	H110	Hallway Between Classroom 110 and Kitchen Receiving Area	yes	Doors	Metal	Brown	Chipping	2	1.8	Positive	None	0	N/A	Prior to Repair	No	no	no			
1	1	H110	Hallway Between Classroom 110 and Kitchen Receiving Area	yes	Doors	Metal	Green	Chipping	2	1.5	Positive	None	0	N/A	Prior to Repair	No	no	no			
1	1	H110	Hallway Between Classroom 110 and Kitchen Receiving Area	yes	Doors	Metal	Blue	Chipping	2	0.2	Negative	None	0	N/A	Prior to Repair	No	no	no			
1	1	H110	Hallway Between Classroom 110 and Kitchen Receiving Area	yes	Doors	Metal	Orange	Chipping	2	2.1	Positive	None	0	N/A	Prior to Repair	No	no	no			
1	1	H110	Hallway Between Classroom 110 and Kitchen Receiving Area	yes	W4	CMU	White	Chipping	1	0	Negative	None	0	N/A	Prior to Repair	No	no	no			
1	1	H110	Hallway Between Classroom 110 and Kitchen Receiving Area	yes	W4	Concrete	White	Chipping	1	0	Negative	None	0	N/A	Prior to Repair	No	no	no			
1	1	H110	Hallway Between Classroom 110 and Kitchen Receiving Area	yes	Ceiling	Concrete	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no			
1	1	H110	Hallway Between Classroom 110 and Kitchen Receiving Area	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	Floor tiles		
1	2	216	Art Room 115	yes	W1	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no			
1	2	216	Art Room 115	yes	Door	Wood	Blue	Chipping	2	1.2	Positive	None	0	N/A	Prior to Repair	No	no	no			
1	2	216	Art Room 115	yes	W2	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no			
1	2	216	Art Room 115	yes	Door	Wood	Red	Chipping	2	0.5	Negative	None	0	N/A	Prior to Repair	No	no	no			
1	2	216	Art Room 115	yes	Door	Wood	Blue	Chipping	2	0.5	Negative	None	0	N/A	Prior to Repair	No	no	no			
1	2	216	Art Room 115	yes	W3	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no			
1	2	216	Art Room 115	yes	W4	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no			
1	2	216	Art Room 115	yes	Ceiling	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no			
1	2	216	Art Room 115	yes	Truss	Metal	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no			
1	2	216	Art Room 115	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	See Stairs to Art Room for condition of components		
1	2	216B	Art Room 115 Closet	yes	W1	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no			
1	2	216B	Art Room 115 Closet	yes	W2	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no			
1	2	216B	Art Room 115 Closet	yes	W3	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no			
1	2	216B	Art Room 115 Closet	yes	Shelves	Wood	Green	Friction	2	N/A	Positive	None	0	N/A	Prior to Repair	No	no	no			
1	2	216B	Art Room 115 Closet	yes	W4	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no			

					School District of Philadelphia																	
			Name of Inspector: Ryan Hutsell		Lead Safe Certification Assessment Report									Inspection Dates: 05/03-28/21								
			Inspection Company: Synertech, Inc.		Cramp School									ULCS# 5470								
E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	Lead Concentrati on (% wt)	Lead in Paint Chips by Flame AAS Analysis Results (positive / negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes			
1	2	216B	Art Room 115 Closet	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	Drop Ceiling			
1	2	216B	Art Room 115 Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	Floor Tiles			
1	2	216C	Art Room 115 Closet Mechanical Room	yes	W1	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no				
1	2	216C	Art Room 115 Closet Mechanical Room	yes	W2	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no				
1	2	216C	Art Room 115 Closet Mechanical Room	yes	W3	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no				
1	2	216C	Art Room 115 Closet Mechanical Room	yes	W4	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no				
1	2	216C	Art Room 115 Closet Mechanical Room	yes	Ceiling	Concrete	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no				
1	2	216C	Art Room 115 Closet Mechanical Room	yes	Floor	Concrete	N/A	None	0	N/A	N/A	None	0	N/A	No	No	no	no				
1	2	S24	Stairwell to Art Room	yes	W1	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no				
1	2	S24	Stairwell to Art Room	yes	W2	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no				
1	2	S24	Stairwell to Art Room	yes	W3	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no				
1	2	S24	Stairwell to Art Room	yes	W4	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no				
1	2	S24	Stairwell to Art Room	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no				
1	2	S24	Stairwell to Art Room	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no				
1	1	117	Former Boy's Locker Room	no	W1	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no				
1	1	117	Former Boy's Locker Room	no	W2	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no				
1	1	117	Former Boy's Locker Room	no	W3	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no				
1	1	117	Former Boy's Locker Room	no	W4	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no				
1	1	117	Former Boy's Locker Room	no	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	Drop ceiling			
1	1	117	Former Boy's Locker Room	no	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	Ceramic Tiles			
1	1	119	Security Camera Office	no	W1	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no				
1	1	119	Security Camera Office	no	W2	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no				
1	1	119	Security Camera Office	no	W3	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no				
1	1	119	Security Camera Office	no	W4	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no				
1	1	119	Security Camera Office	no	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no				
1	1	119	Security Camera Office	no	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no				
1	1	120	Girl's Restroom near Security Camera Office	yes	W1	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no				
1	1	120	Girl's Restroom near Security Camera Office	yes	W2	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no				
1	1	120	Girl's Restroom near Security Camera Office	yes	W3	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no				
1	1	120	Girl's Restroom near Security Camera Office	yes	W4	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no				
1	1	120	Girl's Restroom near Security Camera Office	yes	Ceiling	Plaster	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no				
1	1	120	Girl's Restroom near Security Camera Office	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	Ceramic Tiles			
1	1	121	Boy's Restroom near Security Camera Office	yes	W1	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no				
1	1	121	Boy's Restroom near Security Camera Office	yes	W2	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no				
1	1	121	Boy's Restroom near Security Camera Office	yes	W3	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no				
1	1	121	Boy's Restroom near Security Camera Office	yes	W4	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no				
1	1	121	Boy's Restroom near Security Camera Office	yes	Ceiling	Plaster	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no				
1	1	121	Boy's Restroom near Security Camera Office	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	Ceramic Tiles			
1	2	S24	Stairwell to Art Room	yes	Stair Soffit	Metal	Yellow	Chipping	6	1.5	Positive	None	0	N/A	Prior to Repair	No	no	no				
1	2	S24	Stairwell to Art Room	yes	Stair Stringer	Metal	Yellow	Chipping	4	2.1	Positive	None	0	N/A	Prior to Repair	No	no	no				
1	2	S24	Stairwell to Art Room	yes	Stair Treads	Metal	Yellow	Chipping	2	1.6	Positive	None	0	N/A	Prior to Repair	No	no	no				
1	1	S15	Stairwell to Former Music Room 112	yes	W1	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no				
1	1	S15	Stairwell to Former Music Room 112	yes	W2	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no				
1	1	S15	Stairwell to Former Music Room 112	yes	W3	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no				
1	1	S15	Stairwell to Former Music Room 112	yes	W4	CMU	White	Chipping	12	0	Negative	None	0	N/A	Prior to Repair	No	no	no				
1	1	S15	Stairwell to Former Music Room 112	yes	Ceiling	Concrete	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no				
1	1	S15	Stairwell to Former Music Room 112	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no				

					School District of Philadelphia															
			Name of Inspector: Ryan Hutsell		Lead Safe Certification Assessment Report								Inspection Dates: 05/03-28/21							
			Inspection Company: Synertech, Inc.		Cramp School								ULCS# 5470							
E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	Lead Concentrati on (% wt)	Lead in Paint Chips by Flame AAS Analysis Results (positive / negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes	
1	1	118	Former Music Room 112	yes	W1	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no		
1	1	118	Former Music Room 112	yes	W2	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no		
1	1	118	Former Music Room 112	yes	Door Frame	Metal	Green	Chipping	2	0.21	Negative	None	0	N/A	Prior to Repair	No	no	no		
1	1	118	Former Music Room 112	yes	Door	Metal	Green	Chipping	2	0.16	Negative	None	0	N/A	Prior to Repair	No	no	no		
1	1	118	Former Music Room 112	yes	W3	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no		
1	1	118	Former Music Room 112	yes	Door Frame	Metal	Green	Chipping	2	0.14	Negative	None	0	N/A	Prior to Repair	No	no	no		
1	1	118	Former Music Room 112	yes	Door	Metal	Green	Chipping	2	0.17	Negative	None	0	N/A	Prior to Repair	No	no	no		
1	1	118	Former Music Room 112	yes	Window Frame	Metal	Green	Chipping	2	0.15	Negative	None	0	N/A	Prior to Repair	No	no	no		
1	1	118	Former Music Room 112	yes	W4	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no		
1	1	118	Former Music Room 112	yes	Door Frame	Metal	White	Chipping	2	0.12	Negative	None	0	N/A	Prior to Repair	No	no	no		
1	1	118	Former Music Room 112	yes	Door	Metal	Blue	Chipping	2	0.23	Negative	None	0	N/A	Prior to Repair	No	no	no		
1	1	118	Former Music Room 112	yes	Ceiling	Concrete	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no		
1	1	118	Former Music Room 112	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no		
1	1	118A	Former Music Room 112 Office	yes	W1	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no		
1	1	118A	Former Music Room 112 Office	yes	Door Frame	Metal	Green	Chipping	2	0	Negative	None	0	N/A	Prior to Repair	No	no	no		
1	1	118A	Former Music Room 112 Office	yes	W2	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no		
1	1	118A	Former Music Room 112 Office	yes	W3	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no		
1	1	118A	Former Music Room 112 Office	yes	W4	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no		
1	1	118A	Former Music Room 112 Office	yes	Ceiling	Concrete	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no		
1	1	118A	Former Music Room 112 Office	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no		
1	1	118C	Former Music Room 112 Office Closet	yes	W1	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no		
1	1	118C	Former Music Room 112 Office Closet	yes	Door Frame	Metal	Green	Chipping	2	0	Negative	None	0	N/A	Prior to Repair	No	no	no		
1	1	118C	Former Music Room 112 Office Closet	yes	Window Frame	Metal	Green	Chipping	2	0	Negative	None	0	N/A	Prior to Repair	No	no	no		
1	1	118C	Former Music Room 112 Office Closet	yes	W2	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no		
1	1	118C	Former Music Room 112 Office Closet	yes	W3	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no		
1	1	118C	Former Music Room 112 Office Closet	yes	Shelves	Wood	Green	Friction	4	2.1	Positive	None	0	N/A	Prior to Repair	No	no	no		
1	1	118C	Former Music Room 112 Office Closet	yes	W4	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no		
1	1	118C	Former Music Room 112 Office Closet	yes	Ceiling	Concrete	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no		
1	1	118C	Former Music Room 112 Office Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no		
1	1	118B	Former Music Room 112 Storage Room	yes	W1	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no		
1	1	118B	Former Music Room 112 Storage Room	yes	W2	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no		
1	1	118B	Former Music Room 112 Storage Room	yes	W3	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no		
1	1	118B	Former Music Room 112 Storage Room	yes	W4	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no		
1	1	118B	Former Music Room 112 Storage Room	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	Drop ceiling	
1	1	118B	Former Music Room 112 Storage Room	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	9"x9" Floor tiles	
1	1	S13A	Main Entrance Vestibule	yes	W1	Brick	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	Unpainted	
1	1	S13A	Main Entrance Vestibule	yes	Door Frame	Metal	Red	Chipping	2	0.13	Negative	None	0	N/A	Prior to Repair	No	no	no		
1	1	S13A	Main Entrance Vestibule	yes	Door	Metal	Red	Chipping	16	0.06	Negative	None	0	N/A	Prior to Repair	No	no	no		
1	1	S13A	Main Entrance Vestibule	yes	W2	Brick	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	Unpainted	
1	1	S13A	Main Entrance Vestibule	yes	Radiator	Metal	Red	Chipping	2	0.15	Negative	None	0	N/A	Prior to Repair	No	no	no		
1	1	S13A	Main Entrance Vestibule	yes	W3	Brick	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	Unpainted	
1	1	S13A	Main Entrance Vestibule	yes	Door Frame	Metal	Red	Chipping	2	0	Negative	None	0	N/A	Prior to Repair	No	no	no		
1	1	S13A	Main Entrance Vestibule	yes	Door	Metal	Red	Chipping	16	0	Negative	None	0	N/A	Prior to Repair	No	no	no		
1	1	S13A	Main Entrance Vestibule	yes	W4	Brick	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	Unpainted	
1	1	S13A	Main Entrance Vestibule	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	Ceramic Tiles	
1	1	S13	Main Entrance Hallway with Stairs	yes	W1	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no		
1	1	S13	Main Entrance Hallway with Stairs	yes	W1	CMU	Blue	None	0	N/A	N/A	None	0	N/A	No	No	no	no		
1	1	S13	Main Entrance Hallway with Stairs	yes	Door Frame	Metal	Red	Friction	4	0.18	Negative	None	0	N/A	Prior to Repair	No	no	no		
1	1	S13	Main Entrance Hallway with Stairs	yes	Door	Metal	Red	Friction	12	0.21	Negative	None	0	N/A	Prior to Repair	No	no	no	Underside of handrail	
1	1	S13	Main Entrance Hallway with Stairs	yes	W2	CMU	White	Chipping	4	0	Negative	None	0	N/A	Prior to Repair	No	no	no		
1	1	S13	Main Entrance Hallway with Stairs	yes	W2	CMU	Blue	Chipping	12	0	Negative	None	0	N/A	Prior to Repair	No	no	no		
1	1	S13	Main Entrance Hallway with Stairs	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	No wall	
1	1	S13	Main Entrance Hallway with Stairs	yes	W4	CMU	White	Chipping	1	0	Negative	None	0	N/A	Prior to Repair	No	no	no		
1	1	S13	Main Entrance Hallway with Stairs	yes	W4	CMU	Blue	Chipping	8	0	Negative	None	0	N/A	Prior to Repair	No	no	no		
1	1	S13	Main Entrance Hallway with Stairs	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	Drop ceiling	
1	1	S13	Main Entrance Hallway with Stairs	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	9"x9" Floor tiles	
1	1	S13	Main Entrance Hallway with Stairs	yes	Handrail	Metal	Red	Friction	1	0.16	Negative	None	0	N/A	Prior to Repair	No	no	no		
1	1	S13	Main Entrance Hallway with Stairs	yes	Handrail	Metal	Yellow	Friction	1	0.26	Negative	None	0	N/A	Prior to Repair	No	no	no	Underside of handrail	
1	1	H15	Hallway from Auditorium/Cafeteria to Gym	yes	W1	CMU	White	Chipping	2	0	Negative	None	0	N/A	Prior to Repair	No	no	no		
1	1	H15	Hallway from Auditorium/Cafeteria to Gym	yes	W1	CMU	Blue	Chipping	1	0	Negative	None	0	N/A	Prior to Repair	No	no	no		
1	1	H15	Hallway from Auditorium/Cafeteria to Gym	yes	Door Frame	Metal	Red	Chipping	2	0.19	Negative	None	0	N/A	Prior to Repair	No	no	no		

					School District of Philadelphia															
			Name of Inspector: Ryan Hutsell		Lead Safe Certification Assessment Report								Inspection Dates: 05/03-28/21							
			Inspection Company: Synertech, Inc.		Cramp School								ULCS# 5470							
E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	Lead Concentrati on (% wt)	Lead in Paint Chips by Flame AAS Analysis Results (positive / negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes	
1	1	H15	Hallway from Auditorium/Cafeteria to Gym	yes	Door	Metal	Red	Chipping	2	0.14	Negative	None	0	N/A	Prior to Repair	No	no	no		
1	1	H15	Hallway from Auditorium/Cafeteria to Gym	yes	W2	CMU	White	Chipping	4	0	Negative	None	0	N/A	Prior to Repair	No	no	no		
1	1	H15	Hallway from Auditorium/Cafeteria to Gym	yes	W2	CMU	Blue	Chipping	2	0	Negative	None	0	N/A	Prior to Repair	No	no	no		
1	1	H15	Hallway from Auditorium/Cafeteria to Gym	yes	Door Frame	Metal	White	Chipping	2	0.12	Negative	None	0	N/A	Prior to Repair	No	no	no		
1	1	H15	Hallway from Auditorium/Cafeteria to Gym	yes	Door	Metal	White	Chipping	2	0.14	Negative	None	0	N/A	Prior to Repair	No	no	no		
1	1	H15	Hallway from Auditorium/Cafeteria to Gym	yes	W3	CMU	White	Chipping	2	0	Negative	None	0	N/A	Prior to Repair	No	no	no		
1	1	H15	Hallway from Auditorium/Cafeteria to Gym	yes	W3	CMU	Blue	Chipping	4	0	Negative	None	0	N/A	Prior to Repair	No	no	no		
1	1	H15	Hallway from Auditorium/Cafeteria to Gym	yes	Door Frame	Metal	Brown	Chipping	2	0.1	Negative	None	0	N/A	Prior to Repair	No	no	no		
1	1	H15	Hallway from Auditorium/Cafeteria to Gym	yes	Door	Metal	Brown	Chipping	2	0	Negative	None	0	N/A	Prior to Repair	No	no	no		
1	1	H15	Hallway from Auditorium/Cafeteria to Gym	yes	W4	CMU	White	Chipping	2	0	Negative	None	0	N/A	Prior to Repair	No	no	no		
1	1	H15	Hallway from Auditorium/Cafeteria to Gym	yes	W4	CMU	Blue	Chipping	2	0	Negative	None	0	N/A	Prior to Repair	No	no	no		
1	1	H15	Hallway from Auditorium/Cafeteria to Gym	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no		
1	1	H15	Hallway from Auditorium/Cafeteria to Gym	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no		
1	1	S15	Stairwell to Former Music Room 112	yes	Stair Stringer	Metal	Yellow	Chipping	6	2.1	Positive	None	0	N/A	Prior to Repair	No	no	no		
1	1	S15	Stairwell to Former Music Room 112	yes	Riser	Metal	Yellow	Chipping	10	2	Positive	None	0	N/A	Prior to Repair	No	no	no		
1	1	S14	Stairs to Gym	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no		
1	1	S14	Stairs to Gym	yes	W2	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no		
1	1	S14	Stairs to Gym	yes	Handrail	Metal	Silver	Friction	2	0.12	Negative	None	0	N/A	Prior to Repair	No	no	no		
1	1	S14	Stairs to Gym	yes	W3	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no		
1	1	S14	Stairs to Gym	yes	Door Frame	Metal	Green	Chipping	2	0.18	Negative	None	0	N/A	Prior to Repair	No	no	no		
1	1	S14	Stairs to Gym	yes	Door	Metal	Green	Chipping	2	0.14	Negative	None	0	N/A	Prior to Repair	No	no	no		
1	1	S14	Stairs to Gym	yes	W4	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no		
1	1	S14	Stairs to Gym	yes	Handrail	Metal	Red	Friction	2	0.2	Negative	None	0	N/A	Prior to Repair	No	no	no		
1	1	S14	Stairs to Gym	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	Drop ceiling	
1	1	S14	Stairs to Gym	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no		
1	1	H16	Hallway outside Counselor's Office and Nurse's Office	yes	W1	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no		
1	1	H16	Hallway outside Counselor's Office and Nurse's Office	yes	W2	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no		
1	1	H16	Hallway outside Counselor's Office and Nurse's Office	yes	W3	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no		
1	1	H16	Hallway outside Counselor's Office and Nurse's Office	yes	Electrical Panel	Metal	Orange	Chipping	1	1.5	Positive	None	0	N/A	Prior to Repair	No	no	no		
1	1	H16	Hallway outside Counselor's Office and Nurse's Office	yes	W4	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no		
1	1	H16	Hallway outside Counselor's Office and Nurse's Office	yes	Ceiling	Concrete	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no		
1	1	H16	Hallway outside Counselor's Office and Nurse's Office	yes	Duct	Metal	White	Flaking	4	0.2	Negative	None	0	N/A	Prior to Repair	No	no	no		
1	1	H16	Hallway outside Counselor's Office and Nurse's Office	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no		
1	1	H17	Hallway outside Classrooms 103 and 13A	yes	W1	CMU	White	Chipping	2	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no		
1	1	H17	Hallway outside Classrooms 103 and 13A	yes	W2	CMU	White	Chipping	4	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no		
1	1	H17	Hallway outside Classrooms 103 and 13A	yes	W3	CMU	White	Chipping	1	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no		
1	1	H17	Hallway outside Classrooms 103 and 13A	yes	W4	CMU	White	Chipping	2	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no		
1	1	H17	Hallway outside Classrooms 103 and 13A	yes	Ceiling	Concrete	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no		
1	1	H17	Hallway outside Classrooms 103 and 13A	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no		
1	1	H17	Hallway outside Classrooms 103 and 13A	yes	Door Frame	Metal	Brown	Chipping	2	0.32	Negative	None	0	N/A	Prior to Repair	No	no	no		
1	1	H17	Hallway outside Classrooms 103 and 13A	yes	Doors	Metal	Brown	Chipping	2	1.4	Positive	None	0	N/A	Prior to Repair	No	no	no		
1	1	H17	Hallway outside Classrooms 103 and 13A	yes	Doors	Metal	Green	Chipping	2	1.5	Positive	None	0	N/A	Prior to Repair	No	no	no		
1	1	H17	Hallway outside Classrooms 103 and 13A	yes	Doors	Metal	Blue	Chipping	2	1.1	Positive	None	0	N/A	Prior to Repair	No	no	no		

					School District of Philadelphia																
			Name of Inspector: Ryan Hutsell		Lead Safe Certification Assessment Report									Inspection Dates: 05/03-28/21							
			Inspection Company: Synertech, Inc.		Cramp School									ULCS# 5470							
E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	Lead Concentrati on (% wt)	Lead in Paint Chips by Flame AAS Analysis Results (positive / negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes		
1	1	S11	Stairwell across from Classroom 13A	yes	W1	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no			
1	1	S11	Stairwell across from Classroom 13A	yes	W2	Concrete	White	Flaking	15	0	Negative	None	0	N/A	Prior to Repair	No	no	no			
1	1	S11	Stairwell across from Classroom 13A	yes	Door Frame	Metal	Brown	Chipping	2	0	Negative	None	0	N/A	Prior to Repair	No	no	no			
1	1	S11	Stairwell across from Classroom 13A	yes	Door	Metal	Brown	Chipping	2	0.1	Negative	None	0	N/A	Prior to Repair	No	no	no			
1	1	S11	Stairwell across from Classroom 13A	yes	W3	CMU	Orange	Flaking	5	0	Negative	None	0	N/A	Prior to Repair	No	no	no			
1	1	S11	Stairwell across from Classroom 13A	yes	Radiator	Metal	Orange	Chipping	5	0.2	Negative	None	0	N/A	Prior to Repair	No	no	no			
1	1	S11	Stairwell across from Classroom 13A	yes	W4	Concrete	White	Cracking	10	0	Negative	None	0	N/A	Prior to Repair	No	no	no			
1	1	S11	Stairwell across from Classroom 13A	yes	Door Frame	Metal	Brown	Chipping	2	0.15	Negative	None	0	N/A	Prior to Repair	No	no	no			
1	1	S11	Stairwell across from Classroom 13A	yes	Door	Metal	Brown	Chipping	2	0.1	Negative	None	0	N/A	Prior to Repair	No	no	no			
1	1	S11	Stairwell across from Classroom 13A	yes	Ceiling	Concrete	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no			
1	1	S11	Stairwell across from Classroom 13A	yes	Stair Soffit	Metal	Orange	Chipping	4	4.2	Positive	None	0	N/A	Prior to Repair	No	no	no			
1	1	S11	Stairwell across from Classroom 13A	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no			
1	1	H17	Hallway outside Classrooms 103 and 13A	yes	Doors	Metal	Yellow	Chipping	2	1.8	Positive	None	0	N/A	Prior to Repair	No	no	no			
1	1	H18	Hallway From Classroom 13A to Classroom 113	yes	W1	CMU	White	Chipping	1	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no			
1	1	H18	Hallway From Classroom 13A to Classroom 113	yes	W2	CMU	White	Chipping	4	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no			
1	1	H18	Hallway From Classroom 13A to Classroom 113	yes	W3	CMU	White	Chipping	4	0	Negative	None	0	Negative	Partially Inaccessible	No	no	no			
1	1	H18	Hallway From Classroom 13A to Classroom 113	yes	W4	CMU	White	Chipping	2	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no			
1	1	H18	Hallway From Classroom 13A to Classroom 113	yes	Ceiling	Concrete	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no			
1	1	H18	Hallway From Classroom 13A to Classroom 113	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no			
1	1	H18	Hallway From Classroom 13A to Classroom 113	yes	Door Frame	Metal	Brown	Chipping	2	0.16	Negative	None	0	N/A	Prior to Repair	No	no	no			
1	1	H18	Hallway From Classroom 13A to Classroom 113	yes	Doors	Metal	Brown	Chipping	2	1.1	Positive	None	0	N/A	Prior to Repair	No	no	no			
1	1	H18	Hallway From Classroom 13A to Classroom 113	yes	Doors	Metal	Green	Chipping	2	1.2	Positive	None	0	N/A	Prior to Repair	No	no	no			
1	1	H18	Hallway From Classroom 13A to Classroom 113	yes	Doors	Metal	Blue	Chipping	2	1.7	Positive	None	0	N/A	Prior to Repair	No	no	no			
1	1	H18	Hallway From Classroom 13A to Classroom 113	yes	Doors	Metal	Yellow	Chipping	2	1.5	Positive	None	0	N/A	Prior to Repair	No	no	no			
1	1	H14	Hallway from Auditorium/Cafeteria to Classroom 114	yes	W1	CMU	White	Chipping	4	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no			
1	1	H14	Hallway from Auditorium/Cafeteria to Classroom 114	yes	W2	CMU	White	Chipping	4	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no			
1	1	H14	Hallway from Auditorium/Cafeteria to Classroom 114	yes	W3	CMU	White	Chipping	5	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no			
1	1	H14	Hallway from Auditorium/Cafeteria to Classroom 114	yes	W4	CMU	White	Chipping	2	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no			
1	1	H14	Hallway from Auditorium/Cafeteria to Classroom 114	yes	Ceiling	Concrete	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no			
1	1	H14	Hallway from Auditorium/Cafeteria to Classroom 114	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no			
1	1	H14	Hallway from Auditorium/Cafeteria to Classroom 114	yes	Door Frame	Metal	Brown	Chipping	2	0.12	Negative	None	0	N/A	Prior to Repair	No	no	no			
1	1	H14	Hallway from Auditorium/Cafeteria to Classroom 114	yes	Doors	Metal	Brown	Chipping	2	1.1	Positive	None	0	N/A	Prior to Repair	No	no	no			
1	1	H14	Hallway from Auditorium/Cafeteria to Classroom 114	yes	Doors	Metal	Green	Chipping	2	1.6	Positive	None	0	N/A	Prior to Repair	No	no	no			
1	1	H14	Hallway from Auditorium/Cafeteria to Classroom 114	yes	Doors	Metal	Blue	Chipping	2	1.2	Positive	None	0	N/A	Prior to Repair	No	no	no			
1	1	H14	Hallway from Auditorium/Cafeteria to Classroom 114	yes	Doors	Metal	Yellow	Chipping	2	1.1	Positive	None	0	N/A	Prior to Repair	No	no	no			
1	1	H13	Hallway from the Elevator to Classroom 114	yes	W1	CMU	White	Chipping	4	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no			
1	1	H13	Hallway from the Elevator to Classroom 114	yes	W2	CMU	White	Chipping	2	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no			
1	1	H13	Hallway from the Elevator to Classroom 114	yes	W3	CMU	White	Chipping	4	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no			
1	1	H13	Hallway from the Elevator to Classroom 114	yes	W4	CMU	White	Chipping	2	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no			
1	1	H13	Hallway from the Elevator to Classroom 114	yes	Ceiling	Concrete	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no			
1	1	H13	Hallway from the Elevator to Classroom 114	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no			
1	1	S11	Stairwell across from Classroom 13A	yes	Stair Stringer	Metal	Orange	Chipping	12	2.1	Positive	None	0	N/A	Prior to Repair	No	no	no			
1	1	S11	Stairwell across from Classroom 13A	yes	Stair Risers	Metal	Orange	Chipping	25	3.1	Positive	None	0	N/A	Prior to Repair	No	no	no			
1	1	S11	Stairwell across from Classroom 13A	yes	Baseboard	Metal	Orange	Chipping	30	4.2	Positive	None	0	N/A	Prior to Repair	No	no	no			

					School District of Philadelphia															
			Name of Inspector: Ryan Hutsell		Lead Safe Certification Assessment Report						Inspection Dates: 05/03-28/21									
			Inspection Company: Synertech, Inc.		Cramp School						ULCS# 5470									
E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	Lead Concentrati on (% wt)	Lead in Paint Chips by Flame AAS Analysis Results (positive / negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes	
1	1	S11	Stairwell across from Classroom 13A	yes	Baluster	Metal	Orange	Chipping	6	3.9	Positive	None	0	N/A	Prior to Repair	No	no	no		
1	1	S12	Stairwell outside Classroom 110	yes	W1	CMU	White	Cracking	12	0	Negative	None	0	N/A	Prior to Repair	No	no	no		
1	1	S12	Stairwell outside Classroom 110	yes	W2	CMU	White	Cracking	12	0	Negative	None	0	N/A	Prior to Repair	No	no	no		
1	1	S12	Stairwell outside Classroom 110	yes	Door Frame	Metal	Brown	Chipping	2	0.08	Negative	None	0	N/A	Prior to Repair	No	no	no		
1	1	S12	Stairwell outside Classroom 110	yes	Door	Metal	Brown	Chipping	2	0.06	Negative	None	0	N/A	Prior to Repair	No	no	no		
1	1	S12	Stairwell outside Classroom 110	yes	W3	CMU	White	Cracking	12	0	Negative	None	0	N/A	Prior to Repair	No	no	no		
1	1	S12	Stairwell outside Classroom 110	yes	Radiator	Metal	Orange	Chipping	5	0.23	Negative	None	0	N/A	Prior to Repair	No	no	no		
1	1	S12	Stairwell outside Classroom 110	yes	W4	CMU	White	Cracking	12	0	Negative	None	0	N/A	Prior to Repair	No	no	no		
1	1	S12	Stairwell outside Classroom 110	yes	Door Frame	Metal	Brown	Chipping	2	0.14	Negative	None	0	N/A	Prior to Repair	No	no	no		
1	1	S12	Stairwell outside Classroom 110	yes	Door	Metal	Brown	Chipping	2	0.12	Negative	None	0	N/A	Prior to Repair	No	no	no		
1	1	S12	Stairwell outside Classroom 110	yes	Ceiling	Concrete	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no		
1	1	S12	Stairwell outside Classroom 110	yes	Stair Soffit	Metal	Orange	Chipping	4	4.2	Positive	None	0	N/A	Prior to Repair	No	no	no		
1	1	S12	Stairwell outside Classroom 110	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no		
1	1	H12	Hallway from Elevator to Classroom 110	yes	W1	CMU	White	Chipping	4	0	Negative	None	0	Negative	Prior to Repair	No	no	no		
1	1	H12	Hallway from Elevator to Classroom 110	yes	W1	Concrete	White	Chipping	2	0	Negative	None	0	N/A	Prior to Repair	No	no	no		
1	1	H12	Hallway from Elevator to Classroom 110	yes	Door Frame	Metal	Brown	Chipping	2	0.1	Negative	None	0	N/A	Prior to Repair	No	no	no		
1	1	H12	Hallway from Elevator to Classroom 110	yes	Doors	Metal	Orange	Chipping	2	1.8	Positive	None	0	N/A	Prior to Repair	No	no	no		
1	1	H12	Hallway from Elevator to Classroom 110	yes	Doors	Metal	Blue	Chipping	6	1.1	Positive	None	0	N/A	Prior to Repair	No	no	no		
1	1	H12	Hallway from Elevator to Classroom 110	yes	W2	CMU	White	Chipping	4	0	Negative	None	0	N/A	Prior to Repair	No	no	no		
1	1	H12	Hallway from Elevator to Classroom 110	yes	W2	Concrete	White	Chipping	2	0	Negative	None	0	N/A	Prior to Repair	No	no	no		
1	1	H12	Hallway from Elevator to Classroom 110	yes	Door Frame	Metal	Brown	Chipping	2	0.1	Negative	None	0	N/A	Prior to Repair	No	no	no		
1	1	H12	Hallway from Elevator to Classroom 110	yes	Doors	Metal	Blue	Chipping	4	1.2	Positive	None	0	N/A	Prior to Repair	No	no	no		
1	1	H12	Hallway from Elevator to Classroom 110	yes	Doors	Metal	Green	Chipping	4	1.6	Positive	None	0	N/A	Prior to Repair	No	no	no		
1	1	H12	Hallway from Elevator to Classroom 110	yes	W3	CMU	White	Chipping	6	0	Negative	None	0	N/A	Prior to Repair	No	no	no		
1	1	H12	Hallway from Elevator to Classroom 110	yes	Door Frame	Metal	Brown	Chipping	2	0	Negative	None	0	N/A	Prior to Repair	No	no	no		
1	1	H12	Hallway from Elevator to Classroom 110	yes	W3	Concrete	White	Chipping	4	0	Negative	None	0	N/A	Prior to Repair	No	no	no		
1	1	H12	Hallway from Elevator to Classroom 110	yes	Doors	Metal	Orange	Chipping	2	1.9	Positive	None	0	N/A	Prior to Repair	No	no	no		
1	1	H12	Hallway from Elevator to Classroom 110	yes	Doors	Metal	Green	Chipping	2	1.2	Positive	None	0	N/A	Prior to Repair	No	no	no		
1	1	H12	Hallway from Elevator to Classroom 110	yes	Doors	Metal	Brown	Chipping	2	1.4	Positive	None	0	N/A	Prior to Repair	No	no	no		
1	1	H12	Hallway from Elevator to Classroom 110	yes	W4	CMU	White	Chipping	4	0	Negative	None	0	N/A	Prior to Repair	No	no	no		
1	1	H12	Hallway from Elevator to Classroom 110	yes	W4	Concrete	White	Chipping	2	0	Negative	None	0	N/A	Prior to Repair	No	no	no		
1	1	H12	Hallway from Elevator to Classroom 110	yes	Ceiling	Concrete	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no		
1	1	H12	Hallway from Elevator to Classroom 110	yes	Floor	N/A	N/A	Chipping	N/A	N/A	N/A	None	0	N/A	No	No	no	no		
1	1	F1	Throughout First Floor	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no		
1	1	F1	Throughout First Floor	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no		
1	1	F1	Throughout First Floor	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no		
1	1	F1	Throughout First Floor	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no		
1	1	F1	Throughout First Floor	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no		
1	1	F1	Throughout First Floor	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no		
1	2	203	Classroom 200	yes	W1	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	According to the 11/30/2020 classroom modernization specification 200 is part of the project. -JD	
1	2	203	Classroom 200	yes	Door Frame	Metal	Orange	Chipping	2	0.2	Negative	None	0	N/A	Prior to Repair	No	no	no	According to the 11/30/2020 classroom modernization specification 200 is part of the project. -JD	
1	2	203	Classroom 200	yes	Door	Metal	Orange	Chipping	2	1.8	Positive	None	0	N/A	Prior to Repair	No	no	no	According to the 11/30/2020 classroom modernization specification 200 is part of the project. -JD	
1	2	203	Classroom 200	yes	W2	Vinyl	White	Chipping	20	0	Negative	None	0	N/A	Prior to Repair	No	no	no	According to the 11/30/2020 classroom modernization specification 200 is part of the project. -JD	

			School District of Philadelphia																
			Lead Safe Certification Assessment Report																
			Cramp School																
E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	Lead Concentrati on (% wt)	Lead in Paint Chips by Flame AAS Analysis Results (positive / negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes
1	2	203	Classroom 200	yes	W3	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	According to the 11/30/2020 classroom modernization specification 200 is part of the project. -JD
1	2	203	Classroom 200	yes	Sink Cabinet	Wood	White	Chipping	4	0	Negative	None	0	N/A	Prior to Repair	No	no	no	According to the 11/30/2020 classroom modernization specification 200 is part of the project. -JD
1	2	203	Classroom 200	yes	Sink Cabinet	Wood	Yellow	Chipping	4	2.5	Positive	None	0	N/A	Prior to Repair	No	no	no	According to the 11/30/2020 classroom modernization specification 200 is part of the project. -JD
1	2	203	Classroom 200	yes	W4	CMU	White	Chipping	4	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no	According to the 11/30/2020 classroom modernization specification 200 is part of the project. -JD
1	2	203	Classroom 200	yes	Door Frame	Metal	Blue	Chipping	2	0.13	Negative	None	0	N/A	Prior to Repair	No	no	no	According to the 11/30/2020 classroom modernization specification 200 is part of the project. -JD
1	2	203	Classroom 200	yes	Door	Metal	Blue	Chipping	2	0.1	Negative	None	0	N/A	Prior to Repair	No	no	no	According to the 11/30/2020 classroom modernization specification 200 is part of the project. -JD
1	2	203	Classroom 200	yes	Ceiling	Concrete	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	According to the 11/30/2020 classroom modernization specification 200 is part of the project. -JD
1	2	203	Classroom 200	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	According to the 11/30/2020 classroom modernization specification 200 is part of the project. -JD
1	2	203B	Classroom 200 Restroom	yes	W1	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	According to the 11/30/2020 classroom modernization specification 200 is part of the project. -JD
1	2	203B	Classroom 200 Restroom	yes	W2	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	According to the 11/30/2020 classroom modernization specification 200 is part of the project. -JD
1	2	203B	Classroom 200 Restroom	yes	W3	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	According to the 11/30/2020 classroom modernization specification 200 is part of the project. -JD
1	2	203B	Classroom 200 Restroom	yes	W4	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	According to the 11/30/2020 classroom modernization specification 200 is part of the project. -JD
1	2	203B	Classroom 200 Restroom	yes	Ceiling	Plaster	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	According to the 11/30/2020 classroom modernization specification 200 is part of the project. -JD
1	2	203B	Classroom 200 Restroom	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	9"x9" Floor tiles - RH. According to the 11/30/2020 classroom modernization specification 200 is part of the project. -JD
1	2	201	Classroom 201	yes	W1	Concrete	White	Chipping	20	0	N/A	None	0	N/A	Prior to Repair	No	no	no	According to the 11/30/2020 classroom modernization specification 201 is part of the project. -JD
1	2	201	Classroom 201	yes	Door Frame	Metal	Orange	Chipping	2	0	Negative	None	0	N/A	Prior to Repair	No	no	no	According to the 11/30/2020 classroom modernization specification 201 is part of the project. -JD
1	2	201	Classroom 201	yes	Door	Wood	Orange	Chipping	2	0.8	Positive	None	0	N/A	Prior to Repair	No	no	no	According to the 11/30/2020 classroom modernization specification 201 is part of the project. -JD
1	2	201	Classroom 201	yes	Sink Cabinet	Wood	Red	Chipping	4	1.1	Positive	None	0	N/A	Prior to Repair	No	no	no	According to the 11/30/2020 classroom modernization specification 201 is part of the project. -JD
1	2	201	Classroom 201	yes	W2	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	According to the 11/30/2020 classroom modernization specification 201 is part of the project. -JD
1	2	201	Classroom 201	yes	Door Frame	Metal	White	Chipping	2	0	Negative	None	0	N/A	Prior to Repair	No	no	no	According to the 11/30/2020 classroom modernization specification 201 is part of the project. -JD
1	2	201	Classroom 201	yes	Door	Metal	Green	Chipping	2	1.1	Positive	None	0	N/A	Prior to Repair	No	no	no	According to the 11/30/2020 classroom modernization specification 201 is part of the project. -JD
1	2	201	Classroom 201	yes	W3	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	According to the 11/30/2020 classroom modernization specification 201 is part of the project. -JD
1	2	201	Classroom 201	yes	W4	Vinyl	White	Chipping	5	0	Negative	None	0	N/A	Prior to Repair	No	no	no	According to the 11/30/2020 classroom modernization specification 201 is part of the project. -JD
1	2	201	Classroom 201	yes	Door Frame	Metal	White	Chipping	2	0.19	Negative	None	0	N/A	Prior to Repair	No	no	no	According to the 11/30/2020 classroom modernization specification 201 is part of the project. -JD
1	2	201	Classroom 201	yes	Door	Metal	Green	Chipping	2	1.2	Positive	None	0	N/A	Prior to Repair	No	no	no	According to the 11/30/2020 classroom modernization specification 201 is part of the project. -JD

			School District of Philadelphia																
			Lead Safe Certification Assessment Report																
			Cramp School																
E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	Lead Concentrati on (% wt)	Lead in Paint Chips by Flame AAS Analysis Results (positive / negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes
1	2	201	Classroom 201	yes	Ceiling	Concrete	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	According to the 11/30/2020 classroom modernization specification 201 is part of the project. -JD
1	2	201	Classroom 201	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	According to the 11/30/2020 classroom modernization specification 201 is part of the project. -JD
1	2	201A	Classroom 201 Restroom	yes	W1	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	According to the 11/30/2020 classroom modernization specification 201 is part of the project. -JD
1	2	201A	Classroom 201 Restroom	yes	Door	Metal	Green	Chipping	2	0.9	Positive	None	0	N/A	Prior to Repair	No	no	no	According to the 11/30/2020 classroom modernization specification 201 is part of the project. -JD
1	2	201A	Classroom 201 Restroom	yes	W2	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	According to the 11/30/2020 classroom modernization specification 201 is part of the project. -JD
1	2	201A	Classroom 201 Restroom	yes	W3	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	According to the 11/30/2020 classroom modernization specification 201 is part of the project. -JD
1	2	201A	Classroom 201 Restroom	yes	W4	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	According to the 11/30/2020 classroom modernization specification 201 is part of the project. -JD
1	2	201A	Classroom 201 Restroom	yes	Ceiling	Plaster	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	According to the 11/30/2020 classroom modernization specification 201 is part of the project. -JD
1	2	201A	Classroom 201 Restroom	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	According to the 11/30/2020 classroom modernization specification 201 is part of the project. -JD
1	2	204A	Storage between Classrooms 200 and 201	yes	W1	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	According to the 11/30/2020 classroom modernization specification 200 is part of the project. -JD
1	2	204A	Storage between Classrooms 200 and 201	yes	Door	Metal	Green	Chipping	1	1.1	Positive	None	0	N/A	Prior to Repair	No	no	no	According to the 11/30/2020 classroom modernization specification 200 is part of the project. -JD
1	2	204A	Storage between Classrooms 200 and 201	yes	W2	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	According to the 11/30/2020 classroom modernization specification 200 is part of the project. -JD
1	2	204A	Storage between Classrooms 200 and 201	yes	W3	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	According to the 11/30/2020 classroom modernization specification 200 is part of the project. -JD
1	2	204A	Storage between Classrooms 200 and 201	yes	Door	Metal	Yellow	Chipping	1	1.8	Positive	None	0	N/A	Prior to Repair	No	no	no	According to the 11/30/2020 classroom modernization specification 200 is part of the project. -JD
1	2	204A	Storage between Classrooms 200 and 201	yes	W4	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	According to the 11/30/2020 classroom modernization specification 200 is part of the project. -JD
1	2	204A	Storage between Classrooms 200 and 201	yes	Ceiling	Concrete	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	According to the 11/30/2020 classroom modernization specification 200 is part of the project. -JD
1	2	204A	Storage between Classrooms 200 and 201	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	According to the 11/30/2020 classroom modernization specification 200 is part of the project. -JD
1	2	202	Classroom 202	yes	W1	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	
1	2	202	Classroom 202	yes	Door	Metal	Orange	Chipping	1	1	Positive	None	0	N/A	Prior to Repair	No	no	no	
1	2	202	Classroom 202	yes	Sink Cabinet	Wood	N/A	Chipping	4	N/A	Positive	None	0	N/A	Prior to Repair	No	no	no	
1	2	202	Classroom 202	yes	W2	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	
1	2	202	Classroom 202	yes	W3	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	
1	2	202	Classroom 202	yes	Shelves	Wood	Red	Friction	5	1.2	Positive	None	0	N/A	Prior to Repair	No	no	no	
1	2	202	Classroom 202	yes	W4	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	
1	2	202	Classroom 202	yes	Door Frame	Metal	White	Chipping	2	0	Negative	None	0	N/A	Prior to Repair	No	no	no	
1	2	202	Classroom 202	yes	Door	Metal	Blue	Chipping	2	0.1	Negative	None	0	N/A	Prior to Repair	No	no	no	
1	2	202	Classroom 202	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	
1	2	202	Classroom 202	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	
1	2	202A	Classroom 202 Closet	yes	W1	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no	
1	2	202A	Classroom 202 Closet	yes	W2	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no	
1	2	202A	Classroom 202 Closet	yes	W3	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no	
1	2	202A	Classroom 202 Closet	yes	Shelves	Wood	Green	Friction	4	1.2	Positive	None	0	N/A	Prior to Repair	No	no	no	
1	2	202A	Classroom 202 Closet	yes	W4	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no	
1	2	202A	Classroom 202 Closet	yes	Ceiling	Concrete	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	
1	2	202A	Classroom 202 Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	

			School District of Philadelphia																
			Name of Inspector: Ryan Hutsell					Lead Safe Certification Assessment Report					Inspection Dates: 05/03-28/21						
			Inspection Company: Synertech, Inc.					Cramp School					ULCS# 5470						
E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	Lead Concentrati on (% wt)	Lead in Paint Chips by Flame AAS Analysis Results (positive / negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes
1	2	204	Classroom 204	yes	W1	CMU	White	None	0	N/A	N/A	None	0	Positive	No	No	no	no	According to the 11/30/2020 classroom modernization specification 204 is part of the project. - JD
1	2	204	Classroom 204	yes	Door Frame	Metal	Blue	Chipping	2	0	Negative	None	0	N/A	Prior to Repair	No	no	no	According to the 11/30/2020 classroom modernization specification 204 is part of the project. - JD
1	2	204	Classroom 204	yes	Door	Metal	Blue	Chipping	2	0	Negative	None	0	N/A	Prior to Repair	No	no	no	According to the 11/30/2020 classroom modernization specification 204 is part of the project. - JD
1	2	204	Classroom 204	yes	W2	CMU	White	None	Cracking	0	Negative	None	0	Negative	No	No	no	no	According to the 11/30/2020 classroom modernization specification 204 is part of the project. - JD
1	2	204	Classroom 204	yes	W2	Vinyl	White	Chipping	20	0	Negative	None	0	N/A	Prior to Repair	No	no	no	According to the 11/30/2020 classroom modernization specification 204 is part of the project. - JD
1	2	204	Classroom 204	yes	Door Frame	Metal	White	Chipping	2	0	Negative	None	0	N/A	Prior to Repair	No	no	no	According to the 11/30/2020 classroom modernization specification 204 is part of the project. - JD
1	2	204	Classroom 204	yes	Door	Wood	Red	Chipping	2	0.9	Positive	None	0	N/A	Prior to Repair	No	no	no	According to the 11/30/2020 classroom modernization specification 204 is part of the project. - JD
1	2	204	Classroom 204	yes	Sink Cabinet	Wood	Blue	Chipping	12	0.34	Negative	None	0	N/A	Prior to Repair	No	no	no	According to the 11/30/2020 classroom modernization specification 204 is part of the project. - JD
1	2	204	Classroom 204	yes	Pipe Chase Access Panel	Metal	White	Chipping	2	0.2	Negative	None	0	N/A	Prior to Repair	No	no	no	According to the 11/30/2020 classroom modernization specification 204 is part of the project. - JD
1	2	204	Classroom 204	yes	W3	Concrete	White	Chipping	10	0	Negative	None	0	N/A	Prior to Repair	No	no	no	According to the 11/30/2020 classroom modernization specification 204 is part of the project. - JD
1	2	204	Classroom 204	yes	W3	CMU	White	None	0	0	Negative	None	0	Positive	Prior to Repair	No	no	no	According to the 11/30/2020 classroom modernization specification 204 is part of the project. - JD
1	2	204	Classroom 204	yes	Pipe	Metal	White	Chipping	4	0.17	Negative	None	0	N/A	Prior to Repair	No	no	no	According to the 11/30/2020 classroom modernization specification 204 is part of the project. - JD
1	2	204	Classroom 204	yes	W4	CMU	White	None	0	N/A	N/A	None	0	Negative	No	No	no	no	According to the 11/30/2020 classroom modernization specification 204 is part of the project. - JD
1	2	204	Classroom 204	yes	Shelves/Coat Rack	Wood	Blue	Friction	5	0.2	Negative	None	0	N/A	Prior to Repair	No	no	no	According to the 11/30/2020 classroom modernization specification 204 is part of the project. - JD
1	2	204	Classroom 204	yes	Ceiling	Concrete	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	According to the 11/30/2020 classroom modernization specification 204 is part of the project. - JD
1	2	204	Classroom 204	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	According to the 11/30/2020 classroom modernization specification 204 is part of the project. - JD
1	2	204B	Classroom 204 Closet	yes	W1	CMU	White	None	0	0	Negative	None	0	Positive	Partially Inaccessible	No	no	no	According to the 11/30/2020 classroom modernization specification 204 is part of the project. - JD
1	2	204B	Classroom 204 Closet	yes	W2	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no	According to the 11/30/2020 classroom modernization specification 204 is part of the project. - JD
1	2	204B	Classroom 204 Closet	yes	W3	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no	According to the 11/30/2020 classroom modernization specification 204 is part of the project. - JD
1	2	204B	Classroom 204 Closet	yes	Shelves	Wood	Green	Friction	4	1.4	Positive	None	0	N/A	Prior to Repair	No	no	no	According to the 11/30/2020 classroom modernization specification 204 is part of the project. - JD
1	2	204B	Classroom 204 Closet	yes	W4	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no	According to the 11/30/2020 classroom modernization specification 204 is part of the project. - JD
1	2	204B	Classroom 204 Closet	yes	Ceiling	Concrete	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	According to the 11/30/2020 classroom modernization specification 204 is part of the project. - JD
1	2	204B	Classroom 204 Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	According to the 11/30/2020 classroom modernization specification 204 is part of the project. - JD
1	2	206	Classroom 206	yes	W1	CMU	White	None	0	N/A	N/A	None	0	Negative	No	No	no	no	According to the 11/30/2020 classroom modernization specification 206 is part of the project. - JD
1	2	206	Classroom 206	yes	Door Frame	Metal	Green	Chipping	2	0.17	Negative	None	0	N/A	Prior to Repair	No	no	no	According to the 11/30/2020 classroom modernization specification 206 is part of the project. - JD

			School District of Philadelphia																
			Name of Inspector: Ryan Hutsell					Lead Safe Certification Assessment Report					Inspection Dates: 05/03-28/21						
			Inspection Company: Synertech, Inc.					Cramp School					ULCS# 5470						
E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	Lead Concentrati on (% wt)	Lead in Paint Chips by Flame AAS Analysis Results (positive / negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes
1	2	206	Classroom 206	yes	Door	Wood	Green	Chipping	2	1.5	Positive	None	0	N/A	Prior to Repair	No	no	no	According to the 11/30/2020 classroom modernization specification 206 is part of the project. - JD
1	2	206	Classroom 206	yes	W2	CMU	White	None	0	N/A	N/A	None	0	Negative	No	No	no	no	According to the 11/30/2020 classroom modernization specification 206 is part of the project. - JD
1	2	206	Classroom 206	yes	Shelves/Coat Rack	Wood	Green	Friction	12	1.8	Positive	None	0	N/A	Prior to Repair	No	no	no	According to the 11/30/2020 classroom modernization specification 206 is part of the project. - JD
1	2	206	Classroom 206	yes	W3	CMU	White	Cracking	5	0	Negative	None	0	Negative	Prior to Repair	No	no	no	According to the 11/30/2020 classroom modernization specification 206 is part of the project. - JD
1	2	206	Classroom 206	yes	Pipe	Metal	White	Chipping	2	0.2	Negative	None	0	N/A	Prior to Repair	No	no	no	According to the 11/30/2020 classroom modernization specification 206 is part of the project. - JD
1	2	206	Classroom 206	yes	W4	CMU	White	None	0	N/A	N/A	None	0	Negative	No	No	no	no	According to the 11/30/2020 classroom modernization specification 206 is part of the project. - JD
1	2	206	Classroom 206	yes	Sink Cabinet	Wood	Green	Chipping	12	1.6	Positive	None	0	N/A	Prior to Repair	No	no	no	According to the 11/30/2020 classroom modernization specification 206 is part of the project. - JD
1	2	206	Classroom 206	yes	Door	Wood	Green	Chipping	2	1.5	Positive	None	0	N/A	Prior to Repair	No	no	no	According to the 11/30/2020 classroom modernization specification 206 is part of the project. - JD
1	2	206	Classroom 206	yes	Ceiling	Concrete	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	According to the 11/30/2020 classroom modernization specification 206 is part of the project. - JD
1	2	206	Classroom 206	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	According to the 11/30/2020 classroom modernization specification 206 is part of the project. - JD
1	2	206	Classroom 206	yes	Baseboard	Concrete	Black	Chipping	2	0	Negative	None	0	N/A	Prior to Repair	No	no	no	According to the 11/30/2020 classroom modernization specification 206 is part of the project. - JD
1	2	206A	Classroom 206 Closet	yes	W1	CMU	White	None	0	0	Negative	None	0	Negative	Partially Inaccessible	No	no	no	According to the 11/30/2020 classroom modernization specification 206 is part of the project. - JD
1	2	206A	Classroom 206 Closet	yes	W2	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no	According to the 11/30/2020 classroom modernization specification 206 is part of the project. - JD
1	2	206A	Classroom 206 Closet	yes	W3	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no	According to the 11/30/2020 classroom modernization specification 206 is part of the project. - JD
1	2	206A	Classroom 206 Closet	yes	Shelves	Wood	Green	Friction	4	1.2	Positive	None	0	N/A	Prior to Repair	No	no	no	According to the 11/30/2020 classroom modernization specification 206 is part of the project. - JD
1	2	206A	Classroom 206 Closet	yes	W4	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no	According to the 11/30/2020 classroom modernization specification 206 is part of the project. - JD
1	2	206A	Classroom 206 Closet	yes	Ceiling	Concrete	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	According to the 11/30/2020 classroom modernization specification 206 is part of the project. - JD
1	2	206A	Classroom 206 Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	According to the 11/30/2020 classroom modernization specification 206 is part of the project. - JD
1	2	208	Classroom 208	yes	W1	CMU	White	None	0	N/A	N/A	None	0	Negative	No	No	no	no	According to the 11/30/2020 classroom modernization specification 208 is part of the project.
1	2	208	Classroom 208	yes	Door Frame	Metal	Orange	Chipping	2	0.15	Negative	None	0	N/A	Prior to Repair	No	no	no	According to the 11/30/2020 classroom modernization specification 208 is part of the project.
1	2	208	Classroom 208	yes	Door	Metal	Orange	Chipping	2	0.9	Positive	None	0	N/A	Prior to Repair	No	no	no	According to the 11/30/2020 classroom modernization specification 208 is part of the project.
1	2	208	Classroom 208	yes	W2	CMU	White	Chipping	30	0	N/A	None	0	Negative	Prior to Repair	No	no	no	According to the 11/30/2020 classroom modernization specification 208 is part of the project.
1	2	208	Classroom 208	yes	Door Frame	Metal	Blue	Chipping	2	0.1	Negative	None	0	N/A	Prior to Repair	No	no	no	According to the 11/30/2020 classroom modernization specification 208 is part of the project.
1	2	208	Classroom 208	yes	Door	Metal	Blue	Chipping	2	0	Negative	None	0	N/A	Prior to Repair	No	no	no	According to the 11/30/2020 classroom modernization specification 208 is part of the project.
1	2	208	Classroom 208	yes	Sink Cabinet	Wood	Red	Chipping	10	2.1	Positive	None	0	N/A	Prior to Repair	No	no	no	According to the 11/30/2020 classroom modernization specification 208 is part of the project.

			School District of Philadelphia																
			Name of Inspector: Ryan Hutsell					Lead Safe Certification Assessment Report					Inspection Dates: 05/03-28/21						
			Inspection Company: Synertech, Inc.					Cramp School					ULCS# 5470						
E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	Lead Concentrati on (% wt)	Lead in Paint Chips by Flame AAS Analysis Results (positive / negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes
1	2	208	Classroom 208	yes	W3	CMU	White	Chipping	36	0	Negative	None	0	Negative	Prior to Repair	No	no	no	According to the 11/30/2020 classroom modernization specification 208 is part of the project.
1	2	208	Classroom 208	yes	Door Frame	Metal	Brown	Chipping	2	0	Negative	None	0	N/A	Prior to Repair	No	no	no	According to the 11/30/2020 classroom modernization specification 208 is part of the project.
1	2	208	Classroom 208	yes	Door	Metal	Brown	Chipping	2	0.12	Negative	None	0	N/A	Prior to Repair	No	no	no	According to the 11/30/2020 classroom modernization specification 208 is part of the project.
1	2	208	Classroom 208	yes	Pipe	Metal	White	Chipping	6	0.18	Negative	None	0	N/A	Prior to Repair	No	no	no	According to the 11/30/2020 classroom modernization specification 208 is part of the project.
1	2	208	Classroom 208	yes	W4	CMU	White	None	0	N/A	N/A	None	0	Negative	No	No	no	no	According to the 11/30/2020 classroom modernization specification 208 is part of the project.
1	2	208	Classroom 208	yes	Ceiling	Concrete	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	According to the 11/30/2020 classroom modernization specification 208 is part of the project.
1	2	208	Classroom 208	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	According to the 11/30/2020 classroom modernization specification 208 is part of the project.
1	2	208A	Classroom 208 Closet without Door	yes	W1	CMU	White	None	0	0	Negative	None	0	Negative	Partially Inaccessible	No	no	no	According to the 11/30/2020 classroom modernization specification 208 is part of the project.
1	2	208A	Classroom 208 Closet without Door	yes	W2	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no	According to the 11/30/2020 classroom modernization specification 208 is part of the project.
1	2	208A	Classroom 208 Closet without Door	yes	W3	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no	According to the 11/30/2020 classroom modernization specification 208 is part of the project.
1	2	208A	Classroom 208 Closet without Door	yes	W4	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no	According to the 11/30/2020 classroom modernization specification 208 is part of the project.
1	2	208A	Classroom 208 Closet without Door	yes	Ceiling	Concrete	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	According to the 11/30/2020 classroom modernization specification 208 is part of the project.
1	2	208A	Classroom 208 Closet without Door	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	According to the 11/30/2020 classroom modernization specification 208 is part of the project.
1	2	208B	Classroom 208 Closet with Door	yes	W1	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no	According to the 11/30/2020 classroom modernization specification 208 is part of the project.
1	2	208B	Classroom 208 Closet with Door	yes	W2	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no	According to the 11/30/2020 classroom modernization specification 208 is part of the project.
1	2	208B	Classroom 208 Closet with Door	yes	W3	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no	According to the 11/30/2020 classroom modernization specification 208 is part of the project.
1	2	208B	Classroom 208 Closet with Door	yes	Shelves	Wood	Green	Friction	2	1.5	Positive	None	0	N/A	Prior to Repair	No	no	no	According to the 11/30/2020 classroom modernization specification 208 is part of the project.
1	2	208B	Classroom 208 Closet with Door	yes	W4	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no	According to the 11/30/2020 classroom modernization specification 208 is part of the project.
1	2	208B	Classroom 208 Closet with Door	yes	Panel Door	Metal	White	Chipping	1	0.15	Negative	None	0	N/A	Prior to Repair	No	no	no	According to the 11/30/2020 classroom modernization specification 208 is part of the project.
1	2	208B	Classroom 208 Closet with Door	yes	Ceiling	Concrete	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	According to the 11/30/2020 classroom modernization specification 208 is part of the project.
1	2	208B	Classroom 208 Closet with Door	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	According to the 11/30/2020 classroom modernization specification 208 is part of the project.
1	2	210	Classroom 210	yes	W1	CMU	White	None	0	N/A	N/A	None	0	Negative	No	No	no	no	According to the 11/30/2020 classroom modernization specification 210 is part of the project. -JD
1	2	210	Classroom 210	yes	Door Frame	Metal	Green	Chipping	2	0.2	Negative	None	0	N/A	Prior to Repair	No	no	no	According to the 11/30/2020 classroom modernization specification 210 is part of the project. -JD
1	2	210	Classroom 210	yes	Door	Wood	Green	Chipping	2	1.9	Positive	None	0	N/A	Prior to Repair	No	no	no	According to the 11/30/2020 classroom modernization specification 210 is part of the project. -JD
1	2	210	Classroom 210	yes	W2	CMU	White	Chipping	10	0	Negative	None	0	Negative	Prior to Repair	No	no	no	According to the 11/30/2020 classroom modernization specification 210 is part of the project. -JD

			School District of Philadelphia																
			Lead Safe Certification Assessment Report																
			Cramp School																
Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	Lead Concentration (% wt)	Lead in Paint Chips by Flame AAS Analysis Results (positive / negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes
1	2	210	Classroom 210	yes	W2	Concrete	White	Chipping	10	0.06	Negative	None	0	N/A	Prior to Repair	No	no	no	According to the 11/30/2020 classroom modernization specification 210 is part of the project. -JD
1	2	210	Classroom 210	yes	Door Frame	Metal	Green	Chipping	2	0.12	Negative	None	0	N/A	Prior to Repair	No	no	no	According to the 11/30/2020 classroom modernization specification 210 is part of the project. -JD
1	2	210	Classroom 210	yes	Door	Wood	Green	Chipping	2	1.5	Positive	None	0	N/A	Prior to Repair	No	no	no	According to the 11/30/2020 classroom modernization specification 210 is part of the project. -JD
1	2	210	Classroom 210	yes	Sink Cabinet	Wood	Yellow	Chipping	12	2.8	Positive	None	0	N/A	Prior to Repair	No	no	no	According to the 11/30/2020 classroom modernization specification 210 is part of the project. -JD
1	2	210	Classroom 210	yes	W3	CMU	White	Cracking	6	0	Negative	None	0	Negative	Prior to Repair	No	no	no	According to the 11/30/2020 classroom modernization specification 210 is part of the project. -JD
1	2	210	Classroom 210	yes	Pipe	Metal	White	Chipping	12	0.12	Negative	None	0	N/A	Prior to Repair	No	no	no	According to the 11/30/2020 classroom modernization specification 210 is part of the project. -JD
1	2	210	Classroom 210	yes	W4	CMU	White	Chipping	60	0	Negative	None	0	Negative	Prior to Repair	No	no	no	According to the 11/30/2020 classroom modernization specification 210 is part of the project. -JD
1	2	210	Classroom 210	yes	Shelves/Coat Rack	Wood	Yellow	Friction	4	2.5	Positive	None	0	N/A	Prior to Repair	No	no	no	According to the 11/30/2020 classroom modernization specification 210 is part of the project. -JD
1	2	210	Classroom 210	yes	Ceiling	Concrete	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	According to the 11/30/2020 classroom modernization specification 210 is part of the project. -JD
1	2	210	Classroom 210	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	According to the 11/30/2020 classroom modernization specification 210 is part of the project. -JD
1	2	210A	Classroom 210 Closet	yes	W1	CMU	White	None	0	N/A	N/A	None	0	Negative	No	No	no	no	According to the 11/30/2020 classroom modernization specification 210 is part of the project. -JD
1	2	210A	Classroom 210 Closet	yes	W2	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	According to the 11/30/2020 classroom modernization specification 210 is part of the project. -JD
1	2	210A	Classroom 210 Closet	yes	W3	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	According to the 11/30/2020 classroom modernization specification 210 is part of the project. -JD
1	2	210A	Classroom 210 Closet	yes	Shelves	Wood	Green	Friction	2	2.1	Positive	None	0	N/A	Prior to Repair	No	no	no	According to the 11/30/2020 classroom modernization specification 210 is part of the project. -JD
1	2	210A	Classroom 210 Closet	yes	W4	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	According to the 11/30/2020 classroom modernization specification 210 is part of the project. -JD
1	2	210A	Classroom 210 Closet	yes	Ceiling	Concrete	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	According to the 11/30/2020 classroom modernization specification 210 is part of the project. -JD
1	2	210A	Classroom 210 Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	According to the 11/30/2020 classroom modernization specification 210 is part of the project. -JD
1	2	203A	Office 212	yes	W1	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	
1	2	203A	Office 212	yes	Door Frame	Metal	Orange	Chipping	1	0.23	Negative	None	0	N/A	Prior to Repair	No	no	no	
1	2	203A	Office 212	yes	Door	Metal	Orange	Chipping	1	2.7	Positive	None	0	N/A	Prior to Repair	No	no	no	
1	2	203A	Office 212	yes	W2	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	
1	2	203A	Office 212	yes	Door Frame	Metal	White	Chipping	2	0.15	Negative	None	0	N/A	Prior to Repair	No	no	no	
1	2	203A	Office 212	yes	Door	Metal	Blue	Chipping	2	0.12	Negative	None	0	N/A	Prior to Repair	No	no	no	
1	2	203A	Office 212	yes	W3	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	
1	2	203A	Office 212	yes	Shelves	Wood	Yellow	Friction	5	2.5	Positive	None	0	N/A	Prior to Repair	No	no	no	
1	2	203A	Office 212	yes	W4	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	
1	2	203A	Office 212	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	
1	2	203A	Office 212	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	
1	2	203A	Office 212	yes	Baseboard	Concrete	Black	Chipping	4	0	Negative	None	0	N/A	Prior to Repair	No	no	no	
1	2	203C	Office 212 Closet	yes	W1	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	
1	2	203C	Office 212 Closet	yes	W2	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	
1	2	203C	Office 212 Closet	yes	W3	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	
1	2	203C	Office 212 Closet	yes	Shelves	Wood	Green	Friction	2	1.5	Positive	None	0	N/A	Prior to Repair	No	no	no	
1	2	203C	Office 212 Closet	yes	W4	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	
1	2	203C	Office 212 Closet	yes	Ceiling	Concrete	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	
1	2	203C	Office 212 Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	
1	2	205	Classroom 205	yes	W1	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	According to the 11/30/2020 classroom modernization specification 205 is part of the project. -JD

			School District of Philadelphia																
			Lead Safe Certification Assessment Report																
			Cramp School																
E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	Lead Concentrati on (% wt)	Lead in Paint Chips by Flame AAS Analysis Results (positive / negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes
1	2	205	Classroom 205	yes	Door Frame	Metal	Green	Chipping	2	0.21	Negative	None	0	N/A	Prior to Repair	No	no	no	According to the 11/30/2020 classroom modernization specification 205 is part of the project. -JD
1	2	205	Classroom 205	yes	Door	Metal	Green	Chipping	2	1.9	Positive	None	0	N/A	Prior to Repair	No	no	no	According to the 11/30/2020 classroom modernization specification 205 is part of the project. -JD
1	2	205	Classroom 205	yes	Sink Cabinet	Wood	Green	Chipping	4	N/A	N/A	None	0	N/A	Prior to Repair	No	no	no	According to the 11/30/2020 classroom modernization specification 205 is part of the project. -JD
1	2	205	Classroom 205	yes	W2	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	According to the 11/30/2020 classroom modernization specification 205 is part of the project. -JD
1	2	205	Classroom 205	yes	Shelves/Coat Rack	Wood	Green	Friction	2	2	Positive	None	0	N/A	Prior to Repair	No	no	no	According to the 11/30/2020 classroom modernization specification 205 is part of the project. -JD
1	2	205	Classroom 205	yes	W3	Concrete	White	Chipping	2	0	Negative	None	0	N/A	Prior to Repair	No	no	no	According to the 11/30/2020 classroom modernization specification 205 is part of the project. -JD
1	2	205	Classroom 205	yes	Pipe	Metal	White	Chipping	2	0.17	Negative	None	0	N/A	Prior to Repair	No	no	no	According to the 11/30/2020 classroom modernization specification 205 is part of the project. -JD
1	2	205	Classroom 205	yes	W4	Sheetrock	White	Chipping	10	0	Negative	None	0	N/A	Prior to Repair	No	no	no	According to the 11/30/2020 classroom modernization specification 205 is part of the project. -JD
1	2	205	Classroom 205	yes	W4	Concrete	White	Chipping	10	0	Negative	None	0	N/A	Prior to Repair	No	no	no	According to the 11/30/2020 classroom modernization specification 205 is part of the project. -JD
1	2	205	Classroom 205	yes	Pipe Chase Door	Metal	White	Chipping	2	0.19	Negative	None	0	N/A	Prior to Repair	No	no	no	According to the 11/30/2020 classroom modernization specification 205 is part of the project. -JD
1	2	205	Classroom 205	yes	Ceiling	Concrete	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	According to the 11/30/2020 classroom modernization specification 205 is part of the project. -JD
1	2	205	Classroom 205	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	According to the 11/30/2020 classroom modernization specification 205 is part of the project. -JD
1	2	205A	Classroom 205 Closet	yes	W1	CMU	White	None	0	0	Negative	None	0	N/A	No	No	no	no	According to the 11/30/2020 classroom modernization specification 205 is part of the project. -JD
1	2	205A	Classroom 205 Closet	yes	W2	CMU	White	None	0	0	Negative	None	0	N/A	No	No	no	no	According to the 11/30/2020 classroom modernization specification 205 is part of the project. -JD
1	2	205A	Classroom 205 Closet	yes	W3	CMU	White	None	0	0	Negative	None	0	N/A	No	No	no	no	According to the 11/30/2020 classroom modernization specification 205 is part of the project. -JD
1	2	205A	Classroom 205 Closet	yes	Shelves	Wood	Green	Friction	2	1.5	Positive	None	0	N/A	Prior to Repair	No	no	no	According to the 11/30/2020 classroom modernization specification 205 is part of the project. -JD
1	2	205A	Classroom 205 Closet	yes	W4	CMU	White	None	0	0	Negative	None	0	N/A	No	No	no	no	According to the 11/30/2020 classroom modernization specification 205 is part of the project. -JD
1	2	205A	Classroom 205 Closet	yes	Ceiling	Concrete	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	According to the 11/30/2020 classroom modernization specification 205 is part of the project. -JD
1	2	205A	Classroom 205 Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	According to the 11/30/2020 classroom modernization specification 205 is part of the project. -JD
1	2	207	Classroom 207	yes	W1	CMU	White	None	0	0	Negative	None	0	Positive	No	No	no	no	According to the 11/30/2020 classroom modernization specification 207 is part of the project. -JD
1	2	207	Classroom 207	yes	Door Frame	Metal	Orange	Chipping	4	0.2	Negative	None	0	N/A	Prior to Repair	No	no	no	According to the 11/30/2020 classroom modernization specification 207 is part of the project. -JD
1	2	207	Classroom 207	yes	Door	Wood	Orange	Chipping	4	2.1	Positive	None	0	N/A	Prior to Repair	No	no	no	According to the 11/30/2020 classroom modernization specification 207 is part of the project. -JD
1	2	207	Classroom 207	yes	Sink Cabinet	Wood	Red	Chipping	4	3.2	Positive	None	0	N/A	Prior to Repair	No	no	no	According to the 11/30/2020 classroom modernization specification 207 is part of the project. -JD
1	2	207	Classroom 207	yes	W2	CMU	White	Chipping	40	0	Negative	None	0	Negative	Prior to Repair	No	no	no	According to the 11/30/2020 classroom modernization specification 207 is part of the project. -JD
1	2	207	Classroom 207	yes	W2	Concrete	White	Chipping	40	0	Negative	None	0	N/A	Prior to Repair	No	no	no	According to the 11/30/2020 classroom modernization specification 207 is part of the project. -JD

			School District of Philadelphia																
			Name of Inspector: Ryan Hutsell					Lead Safe Certification Assessment Report					Inspection Dates: 05/03-28/21						
			Inspection Company: Synertech, Inc.					Cramp School					ULCS# 5470						
E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	Lead Concentrati on (% wt)	Lead in Paint Chips by Flame AAS Analysis Results (positive / negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes
1	2	207	Classroom 207	yes	Door Frame	Metal	Green	Chipping	2	0	Negative	None	0	N/A	Prior to Repair	No	no	no	According to the 11/30/2020 classroom modernization specification 207 is part of the project. -JD
1	2	207	Classroom 207	yes	Door	Wood	Green	Chipping	2	0.3	Negative	None	0	N/A	Prior to Repair	No	no	no	According to the 11/30/2020 classroom modernization specification 207 is part of the project. -JD
1	2	207	Classroom 207	yes	W3	CMU	White	None	0	0	Negative	None	0	Negative	No	No	no	no	According to the 11/30/2020 classroom modernization specification 207 is part of the project. -JD
1	2	207	Classroom 207	yes	Pipe	Metal	White	Chipping	1	0.27	Negative	None	0	N/A	Prior to Repair	No	no	no	According to the 11/30/2020 classroom modernization specification 207 is part of the project. -JD
1	2	207	Classroom 207	yes	Door Frame	Metal	Brown	Chipping	2	0.08	Negative	None	0	N/A	Prior to Repair	No	no	no	According to the 11/30/2020 classroom modernization specification 207 is part of the project. -JD
1	2	207	Classroom 207	yes	Door	Wood	Brown	Chipping	2	0.16	Negative	None	0	N/A	Prior to Repair	No	no	no	According to the 11/30/2020 classroom modernization specification 207 is part of the project. -JD
1	2	207	Classroom 207	yes	W4	CMU	White	Chipping	50	0	Negative	None	0	Negative	Prior to Repair	No	no	no	According to the 11/30/2020 classroom modernization specification 207 is part of the project. -JD
1	2	207	Classroom 207	yes	Shelving/Coat Rack	Wood	Red	Friction	10	2.5	Positive	None	0	N/A	Prior to Repair	No	no	no	According to the 11/30/2020 classroom modernization specification 207 is part of the project. -JD
1	2	207	Classroom 207	yes	Ceiling	Concrete	White	None	0	0	Negative	None	0	N/A	No	No	no	no	According to the 11/30/2020 classroom modernization specification 207 is part of the project. -JD
1	2	207	Classroom 207	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	According to the 11/30/2020 classroom modernization specification 207 is part of the project. -JD
1	2	207	Classroom 207	yes	Baseboard	Terracotta	Black	Chipping	6	0.15	Negative	None	0	N/A	Prior to Repair	No	no	no	According to the 11/30/2020 classroom modernization specification 207 is part of the project. -JD
1	2	207	Classroom 207	yes	Baseboard	Concrete	Black	Chipping	2	0	Negative	None	0	N/A	Prior to Repair	No	no	no	According to the 11/30/2020 classroom modernization specification 207 is part of the project. -JD
1	2	207A	Classroom 207 Closet	yes	W1	CMU	White	None	0	0	Negative	None	0	Negative	Partially Inaccessible	No	no	no	According to the 11/30/2020 classroom modernization specification 207 is part of the project. -JD
1	2	207A	Classroom 207 Closet	yes	W2	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no	According to the 11/30/2020 classroom modernization specification 207 is part of the project. -JD
1	2	207A	Classroom 207 Closet	yes	W3	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no	According to the 11/30/2020 classroom modernization specification 207 is part of the project. -JD
1	2	207A	Classroom 207 Closet	yes	Shelves	Wood	Green	Friction	2	1	Positive	None	0	N/A	Prior to Repair	No	no	no	According to the 11/30/2020 classroom modernization specification 207 is part of the project. -JD
1	2	207A	Classroom 207 Closet	yes	W4	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no	According to the 11/30/2020 classroom modernization specification 207 is part of the project. -JD
1	2	207A	Classroom 207 Closet	yes	Ceiling	Concrete	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	According to the 11/30/2020 classroom modernization specification 207 is part of the project. -JD
1	2	207A	Classroom 207 Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	According to the 11/30/2020 classroom modernization specification 207 is part of the project. -JD
1	2	209	Classroom 209	yes	W1	CMU	White	None	0	0	Negative	None	0	Negative	Partially Inaccessible	No	no	no	According to the 11/30/2020 classroom modernization specification 209 is part of the project. -JD
1	2	209	Classroom 209	yes	Door Frame	Metal	Green	Chipping	2	0.1	Negative	None	0	N/A	Prior to Repair	No	no	no	According to the 11/30/2020 classroom modernization specification 209 is part of the project. -JD
1	2	209	Classroom 209	yes	Door	Metal	Green	Chipping	2	1.5	Positive	None	0	N/A	Prior to Repair	No	no	no	According to the 11/30/2020 classroom modernization specification 209 is part of the project. -JD
1	2	209	Classroom 209	yes	Sink Cabinet	Wood	Yellow	Chipping	4	3.9	Positive	None	0	N/A	Prior to Repair	No	no	no	According to the 11/30/2020 classroom modernization specification 209 is part of the project. -JD
1	2	209	Classroom 209	yes	W2	Concrete	White	Chipping	60	0	Negative	None	0	Negative	Prior to Repair	No	no	no	According to the 11/30/2020 classroom modernization specification 209 is part of the project. -JD
1	2	209	Classroom 209	yes	Shelves/Coat Rack	Wood	Yellow	Friction	5	3.4	Positive	None	0	N/A	Prior to Repair	No	no	no	According to the 11/30/2020 classroom modernization specification 209 is part of the project. -JD

			School District of Philadelphia																
			Name of Inspector: Ryan Hutsell			Lead Safe Certification Assessment Report									Inspection Dates: 05/03-28/21				
			Inspection Company: Synertech, Inc.			Cramp School									ULCS# 5470				
E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	Lead Concentrati on (% wt)	Lead in Paint Chips by Flame AAS Analysis Results (positive / negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes
1	2	209	Classroom 209	yes	W3	CMU	White	None	0	0	Negative	None	0	Negative	No	No	no	no	According to the 11/30/2020 classroom modernization specification 209 is part of the project. -JD
1	2	209	Classroom 209	yes	Door Frame	Metal	Brown	Chipping	6	0.14	Negative	None	0	N/A	Prior to Repair	No	no	no	According to the 11/30/2020 classroom modernization specification 209 is part of the project. -JD
1	2	209	Classroom 209	yes	Door	Metal	Brown	Chipping	6	0.1	Negative	None	0	N/A	Prior to Repair	No	no	no	According to the 11/30/2020 classroom modernization specification 209 is part of the project. -JD
1	2	209	Classroom 209	yes	Pipe	Metal	White	Chipping	2	0.08	Negative	None	0	N/A	Prior to Repair	No	no	no	According to the 11/30/2020 classroom modernization specification 209 is part of the project. -JD
1	2	209	Classroom 209	yes	W4	Concrete	White	Chipping	20	0	Negative	None	0	Negative	Prior to Repair	No	no	no	According to the 11/30/2020 classroom modernization specification 209 is part of the project. -JD
1	2	209	Classroom 209	yes	Door Frame	Metal	White	Chipping	2	0.12	Negative	None	0	N/A	Prior to Repair	No	no	no	According to the 11/30/2020 classroom modernization specification 209 is part of the project. -JD
1	2	209	Classroom 209	yes	Door	Metal	Blue	Chipping	4	0.08	Negative	None	0	N/A	Prior to Repair	No	no	no	According to the 11/30/2020 classroom modernization specification 209 is part of the project. -JD
1	2	209	Classroom 209	yes	Door	Metal	Green	Chipping	4	0.25	Negative	None	0	N/A	Prior to Repair	No	no	no	According to the 11/30/2020 classroom modernization specification 209 is part of the project. -JD
1	2	209	Classroom 209	yes	Ceiling	Concrete	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	According to the 11/30/2020 classroom modernization specification 209 is part of the project. -JD
1	2	209	Classroom 209	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	According to the 11/30/2020 classroom modernization specification 209 is part of the project. -JD
1	2	209A	Classroom 209 Closet without Door	yes	W1	CMU	White	None	0	N/A	N/A	None	0	Negative	No	No	no	no	According to the 11/30/2020 classroom modernization specification 209 is part of the project. -JD
1	2	209A	Classroom 209 Closet without Door	yes	W2	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	According to the 11/30/2020 classroom modernization specification 209 is part of the project. -JD
1	2	209A	Classroom 209 Closet without Door	yes	W3	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	According to the 11/30/2020 classroom modernization specification 209 is part of the project. -JD
1	2	209A	Classroom 209 Closet without Door	yes	W4	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	According to the 11/30/2020 classroom modernization specification 209 is part of the project. -JD
1	2	209A	Classroom 209 Closet without Door	yes	Ceiling	Concrete	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	According to the 11/30/2020 classroom modernization specification 209 is part of the project. -JD
1	2	209A	Classroom 209 Closet without Door	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	According to the 11/30/2020 classroom modernization specification 209 is part of the project. -JD
1	2	209B	Classroom 209 Closet with Door	yes	W1	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no	According to the 11/30/2020 classroom modernization specification 209 is part of the project. -JD
1	2	209B	Classroom 209 Closet with Door	yes	W2	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no	According to the 11/30/2020 classroom modernization specification 209 is part of the project. -JD
1	2	209B	Classroom 209 Closet with Door	yes	W3	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no	According to the 11/30/2020 classroom modernization specification 209 is part of the project. -JD
1	2	209B	Classroom 209 Closet with Door	yes	W4	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no	According to the 11/30/2020 classroom modernization specification 209 is part of the project. -JD
1	2	209B	Classroom 209 Closet with Door	yes	Ceiling	Concrete	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	According to the 11/30/2020 classroom modernization specification 209 is part of the project. -JD
1	2	209B	Classroom 209 Closet with Door	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	According to the 11/30/2020 classroom modernization specification 209 is part of the project. -JD
1	2	211	Classroom 211	yes	W1	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no	
1	2	211	Classroom 211	yes	Door Frame	Metal	Blue	Chipping	2	0.16	Negative	None	0	N/A	Prior to Repair	No	no	no	
1	2	211	Classroom 211	yes	Door	Wood	Blue	Chipping	2	0.25	Negative	None	0	N/A	Prior to Repair	No	no	no	
1	2	211	Classroom 211	yes	Sink Cabinet	Wood	Blue	Chipping	4	0.2	Negative	None	0	N/A	Prior to Repair	No	no	no	
1	2	211	Classroom 211	yes	W2	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no	
1	2	211	Classroom 211	yes	Shelves/Coat Rack	Wood	Blue	Friction	5	1.1	Positive	None	0	N/A	Prior to Repair	No	no	no	

			School District of Philadelphia																
			Lead Safe Certification Assessment Report																
			Cramp School																
			Inspection Dates: 05/03-28/21																
			ULCS# 5470																
E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	Lead Concentrati on (% wt)	Lead in Paint Chips by Flame AAS Analysis Results (positive / negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes
1	2	211	Classroom 211	yes	W3	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no	
1	2	211	Classroom 211	yes	Pipe	Metal	White	Chipping	2	0.15	Negative	None	0	N/A	Prior to Repair	No	no	no	
1	2	211	Classroom 211	yes	W4	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no	
1	2	211	Classroom 211	yes	Door Frame	Metal	Green	Chipping	1	0.12	Negative	None	0	N/A	Prior to Repair	No	no	no	
1	2	211	Classroom 211	yes	Door	Metal	Green	Chipping	2	0.1	Negative	None	0	N/A	Prior to Repair	No	no	no	
1	2	211	Classroom 211	yes	Ceiling	Concrete	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	
1	2	211	Classroom 211	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	
1	2	211	Classroom 211	yes	Baseboard	Concrete	Black	Chipping	40	0	Negative	None	0	N/A	Prior to Repair	No	no	no	
1	2	211A	Classroom 211 Closet	yes	W1	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no	
1	2	211A	Classroom 211 Closet	yes	W2	CMU	White	None	0	0	Negative	None	0	N/A	No	No	no	no	
1	2	211A	Classroom 211 Closet	yes	W3	CMU	White	None	0	0	Negative	None	0	N/A	No	No	no	no	
1	2	211A	Classroom 211 Closet	yes	Shelves	Wood	Green	Friction	4	1.4	Positive	None	0	N/A	Prior to Repair	No	no	no	
1	2	211A	Classroom 211 Closet	yes	W4	CMU	White	None	0	0	Negative	None	0	N/A	No	No	no	no	
1	2	211A	Classroom 211 Closet	yes	Ceiling	Concrete	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	
1	2	211A	Classroom 211 Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	
1	2	212A	Men's Restroom across from Boy's Restroom	yes	W1	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	
1	2	212A	Men's Restroom across from Boy's Restroom	yes	Door Frame	Metal	Blue	Chipping	2	0.14	Negative	None	0	N/A	Prior to Repair	No	no	no	
1	2	212A	Men's Restroom across from Boy's Restroom	yes	Door	Metal	Blue	Chipping	2	0.1	Negative	None	0	N/A	Prior to Repair	No	no	no	
1	2	212A	Men's Restroom across from Boy's Restroom	yes	W2	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	
1	2	212A	Men's Restroom across from Boy's Restroom	yes	W3	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	
1	2	212A	Men's Restroom across from Boy's Restroom	yes	W4	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	
1	2	212A	Men's Restroom across from Boy's Restroom	yes	Ceiling	Plaster	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	
1	2	212A	Men's Restroom across from Boy's Restroom	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	
1	2	212	Boy's Restroom	yes	W1	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	
1	2	212	Boy's Restroom	yes	Door	Metal	Orange	Chipping	2	0.4	Negative	None	0	N/A	Prior to Repair	No	no	no	
1	2	212	Boy's Restroom	yes	W2	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	
1	2	212	Boy's Restroom	yes	W3	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	
1	2	212	Boy's Restroom	yes	W4	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	
1	2	212	Boy's Restroom	yes	Ceiling	Concrete	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	
1	2	212	Boy's Restroom	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	
1	2	212D	Custodial Closet next to Boy's Restroom	no	W1	CMU	White	Chipping	2	0	Negative	None	0	N/A	Prior to Repair	No	no	no	
1	2	212D	Custodial Closet next to Boy's Restroom	no	Door Frame	Metal	White	Chipping	2	0	Negative	None	0	N/A	Prior to Repair	No	no	no	
1	2	212D	Custodial Closet next to Boy's Restroom	no	Door	Wood	Green	Chipping	2	0.15	Negative	None	0	N/A	Prior to Repair	No	no	no	
1	2	212D	Custodial Closet next to Boy's Restroom	no	W2	CMU	White	Chipping	2	0	Negative	None	0	N/A	Prior to Repair	No	no	no	
1	2	212D	Custodial Closet next to Boy's Restroom	no	Sink	Metal	White	Flaking	4	0	Negative	None	0	N/A	Prior to Repair	No	no	no	
1	2	212D	Custodial Closet next to Boy's Restroom	no	W3	CMU	White	None	N/A	N/A	N/A	None	0	N/A	No	No	no	no	
1	2	212D	Custodial Closet next to Boy's Restroom	no	W4	CMU	White	None	N/A	N/A	N/A	None	0	N/A	No	No	no	no	
1	2	212D	Custodial Closet next to Boy's Restroom	no	Ceiling	Concrete	White	None	N/A	N/A	N/A	None	0	N/A	No	No	no	no	
1	2	212D	Custodial Closet next to Boy's Restroom	no	Floor	Concrete	Grey	Chipping	6	0	Negative	None	0	N/A	Prior to Repair	No	no	no	
1	2	213	Classroom 213	yes	W1	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	
1	2	213	Classroom 213	yes	Door Frame	Metal	Blue	Chipping	2	0	Negative	None	0	N/A	Prior to Repair	No	no	no	
1	2	213	Classroom 213	yes	Door	Metal	Blue	Chipping	2	0	Negative	None	0	N/A	Prior to Repair	No	no	no	
1	2	213	Classroom 213	yes	Shelves	Wood	N/A	Chipping	4	N/A	Positive	None	0	N/A	Prior to Repair	No	no	no	
1	2	213	Classroom 213	yes	W2	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	
1	2	213	Classroom 213	yes	W3	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	
1	2	213	Classroom 213	yes	Pipe Chase	Metal	White	Chipping	1	0.1	Negative	None	0	N/A	Prior to Repair	No	no	no	
1	2	213	Classroom 213	yes	W4	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	
1	2	213	Classroom 213	yes	Ceiling	Concrete	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	
1	2	213	Classroom 213	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	
1	2	213A	Storage Room adjacent to Elevator	yes	W1	CMU	N/A	None	0	N/A	N/A	None	0	N/A	No	No	no	no	
1	2	213A	Storage Room adjacent to Elevator	yes	W2	CMU	N/A	None	0	N/A	N/A	None	0	N/A	No	No	no	no	

			School District of Philadelphia																
			Lead Safe Certification Assessment Report																
			Cramp School																
			Inspection Dates: 05/03-28/21																
			ULCS# 5470																
E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	Lead Concentrati on (% wt)	Lead in Paint Chips by Flame AAS Analysis Results (positive / negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes
1	2	213A	Storage Room adjacent to Elevator	yes	Electrical Panel Door	Metal	White	Chipping	1	0.19	Negative	None	0	N/A	Prior to Repair	No	no	no	
1	2	213A	Storage Room adjacent to Elevator	yes	W3	CMU	N/A	None	0	N/A	N/A	None	0	N/A	No	No	no	no	
1	2	213A	Storage Room adjacent to Elevator	yes	W4	CMU	N/A	None	0	N/A	N/A	None	0	N/A	No	No	no	no	
1	2	213A	Storage Room adjacent to Elevator	yes	Ceiling	Concrete	N/A	None	0	N/A	N/A	None	0	N/A	No	No	no	no	
1	2	213A	Storage Room adjacent to Elevator	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	
1	2	213B	Girl's Restroom	yes	W1	CMU	N/A	None	0	N/A	N/A	None	0	N/A	No	No	no	no	
1	2	213B	Girl's Restroom	yes	Door Frame	Metal	Yellow	Chipping	2	0.1	Negative	None	0	N/A	Prior to Repair	No	no	no	
1	2	213B	Girl's Restroom	yes	Door	Metal	Yellow	Chipping	2	1.8	Positive	None	0	N/A	Prior to Repair	No	no	no	
1	2	213B	Girl's Restroom	yes	W2	CMU	N/A	None	0	N/A	N/A	None	0	N/A	No	No	no	no	
1	2	213B	Girl's Restroom	yes	W3	CMU	N/A	None	0	N/A	N/A	None	0	N/A	No	No	no	no	
1	2	213B	Girl's Restroom	yes	W4	CMU	N/A	None	0	N/A	N/A	None	0	N/A	No	No	no	no	
1	2	213B	Girl's Restroom	yes	Ceiling	Plaster	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	
1	2	213B	Girl's Restroom	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	Ceramic Tiles
1	2	213C	Women's Restroom	yes	W1	CMU	N/A	None	0	N/A	N/A	None	0	N/A	No	No	no	no	
1	2	213C	Women's Restroom	yes	Door Frame	Metal	Yellow	Chipping	2	0.1	Negative	None	0	N/A	Prior to Repair	No	no	no	
1	2	213C	Women's Restroom	yes	Door	Metal	Yellow	Chipping	2	1.5	Positive	None	0	N/A	Prior to Repair	No	no	no	
1	2	213C	Women's Restroom	yes	W2	CMU	N/A	None	0	N/A	N/A	None	0	N/A	No	No	no	no	
1	2	213C	Women's Restroom	yes	W3	CMU	N/A	None	0	N/A	N/A	None	0	N/A	No	No	no	no	
1	2	213C	Women's Restroom	yes	W4	CMU	N/A	None	0	N/A	N/A	None	0	N/A	No	No	no	no	
1	2	213C	Women's Restroom	yes	Ceiling	Plaster	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	
1	2	213C	Women's Restroom	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	9"x9" Floor tiles
1	2	213D	Custodial Closet Near Elevator	no	W1	CMU	White	Chipping	2	0	Negative	None	0	N/A	Prior to Repair	No	no	no	
1	2	213D	Custodial Closet Near Elevator	no	Door Frame	Metal	White	Chipping	2	0	Negative	None	0	N/A	Prior to Repair	No	no	no	
1	2	213D	Custodial Closet Near Elevator	no	Door	Wood	Green	Chipping	2	0.1	Negative	None	0	N/A	Prior to Repair	No	no	no	
1	2	213D	Custodial Closet Near Elevator	no	W2	CMU	White	Chipping	2	0	Negative	None	0	N/A	Prior to Repair	No	no	no	
1	2	213D	Custodial Closet Near Elevator	no	Sink	Metal	White	Flaking	4	0	Negative	None	0	N/A	Prior to Repair	No	no	no	
1	2	213D	Custodial Closet Near Elevator	no	W3	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	
1	2	213D	Custodial Closet Near Elevator	no	W4	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	
1	2	213D	Custodial Closet Near Elevator	no	Ceiling	Concrete	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	
1	2	213D	Custodial Closet Near Elevator	no	Floor	Concrete	Grey	Chipping	6	0	Negative	None	0	N/A	Prior to Repair	No	no	no	
1	2	214	Computer Lab 214	yes	W1	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no	
1	2	214	Computer Lab 214	yes	Door	Metal	Green	Chipping	1	0.18	Negative	None	0	N/A	Prior to Repair	No	no	no	
1	2	214	Computer Lab 214	yes	W2	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no	
1	2	214	Computer Lab 214	yes	Door	Metal	Red	Chipping	1	1.2	Positive	None	0	N/A	Prior to Repair	No	no	no	
1	2	214	Computer Lab 214	yes	W3	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no	
1	2	214	Computer Lab 214	yes	W4	Sheetrock	White	Chipping	40	0	Negative	None	0	N/A	Prior to Repair	No	no	no	
1	2	214	Computer Lab 214	yes	Ceiling	Concrete	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	
1	2	214	Computer Lab 214	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	9"x9" Floor tiles
1	2	214A	Computer Lab 214 Storage Room	yes	W1	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no	
1	2	214A	Computer Lab 214 Storage Room	yes	W2	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no	
1	2	214A	Computer Lab 214 Storage Room	yes	W3	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no	
1	2	214A	Computer Lab 214 Storage Room	yes	W4	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no	
1	2	214A	Computer Lab 214 Storage Room	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	Drop ceiling
1	2	214A	Computer Lab 214 Storage Room	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	9"x9" Floor tiles
1	2	214C	Hallway From Computer Lab 214 to Elevator	yes	W1	Concrete	Orange	Chipping	4	0	Negative	None	0	N/A	Prior to Repair	No	no	no	
1	2	214C	Hallway From Computer Lab 214 to Elevator	yes	W1	Concrete	Blue	Chipping	6	0.06	Negative	None	0	N/A	Prior to Repair	No	no	no	
1	2	214C	Hallway From Computer Lab 214 to Elevator	yes	Door	Wood	Green	Chipping	2	0.25	Negative	None	0	N/A	Prior to Repair	No	no	no	
1	2	214C	Hallway From Computer Lab 214 to Elevator	yes	W2	Concrete	Orange	Chipping	4	0	Negative	None	0	N/A	Prior to Repair	No	no	no	
1	2	214C	Hallway From Computer Lab 214 to Elevator	yes	W2	Concrete	Blue	Chipping	5	0	Negative	None	0	N/A	Prior to Repair	No	no	no	
1	2	214C	Hallway From Computer Lab 214 to Elevator	yes	W3	Concrete	Orange	Chipping	12	0	Negative	None	0	N/A	Prior to Repair	No	no	no	
1	2	214C	Hallway From Computer Lab 214 to Elevator	yes	W3	Concrete	Blue	Chipping	10	0	Negative	None	0	N/A	Prior to Repair	No	no	no	
1	2	214C	Hallway From Computer Lab 214 to Elevator	yes	W4	Concrete	Orange	Chipping	8	0.08	Negative	None	0	N/A	Prior to Repair	No	no	no	
1	2	214C	Hallway From Computer Lab 214 to Elevator	yes	W4	Concrete	Blue	Chipping	6	0	Negative	None	0	N/A	Prior to Repair	No	no	no	

					School District of Philadelphia																	
			Name of Inspector: Ryan Hutsell		Lead Safe Certification Assessment Report									Inspection Dates: 05/03-28/21								
			Inspection Company: Synertech, Inc.		Cramp School									ULCS# 5470								
E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	Lead Concentrati on (% wt)	Lead in Paint Chips by Flame AAS Analysis Results (positive / negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes			
1	2	214C	Hallway From Computer Lab 214 to Elevator	yes	Ceiling	Concrete	White	Chipping	2	0.1	Negative	None	0	N/A	Prior to Repair	No	no	no				
1	2	214C	Hallway From Computer Lab 214 to Elevator	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no				
1	2	215	Classroom 215	yes	W1	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no				
1	2	215	Classroom 215	yes	Sink Cabinet Shelves/Coat Rack	Wood	N/A	Chipping	12	N/A	Positive	None	0	N/A	Prior to Repair	No	no	no				
1	2	215	Classroom 215	yes	W2	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no				
1	2	215	Classroom 215	yes	W3	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no				
1	2	215	Classroom 215	yes	W4	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no				
1	2	215	Classroom 215	yes	Ceiling	Concrete	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no				
1	2	215	Classroom 215	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	9"x9" Floor tiles			
1	2	215A	Classroom 215 Girl's Restroom	yes	W1	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no				
1	2	215A	Classroom 215 Girl's Restroom	yes	W2	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no				
1	2	215A	Classroom 215 Girl's Restroom	yes	W3	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no				
1	2	215A	Classroom 215 Girl's Restroom	yes	W4	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no				
1	2	215A	Classroom 215 Girl's Restroom	yes	Ceiling	Plaster	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no				
1	2	215A	Classroom 215 Girl's Restroom	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no				
1	2	215B	Classroom 215 Boy's Restroom	yes	W1	CMU	White	None	0	0	Negative	None	0	N/A	No	No	no	no				
1	2	215B	Classroom 215 Boy's Restroom	yes	W2	CMU	White	None	0	0	Negative	None	0	N/A	No	No	no	no				
1	2	215B	Classroom 215 Boy's Restroom	yes	W3	CMU	White	None	0	0	Negative	None	0	N/A	No	No	no	no				
1	2	215B	Classroom 215 Boy's Restroom	yes	W4	CMU	White	None	0	0	Negative	None	0	N/A	No	No	no	no				
1	2	215B	Classroom 215 Boy's Restroom	yes	Ceiling	Plaster	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no				
1	2	215B	Classroom 215 Boy's Restroom	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no				
1	2	215C	Classroom 215 Custodial Closet	yes	W1	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no				
1	2	215C	Classroom 215 Custodial Closet	yes	W2	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no				
1	2	215C	Classroom 215 Custodial Closet	yes	W3	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no				
1	2	215C	Classroom 215 Custodial Closet	yes	W4	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no				
1	2	215C	Classroom 215 Custodial Closet	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no				
1	2	215C	Classroom 215 Custodial Closet	yes	Floor	Concrete	Grey	None	0	N/A	N/A	None	0	N/A	No	No	no	no				
1	1	S12	Stairwell outside Classroom 110	yes	Stair Stringer	Metal	Orange	Chipping	12	1.7	Positive	None	0	N/A	Prior to Repair	No	no	no				
1	1	S12	Stairwell outside Classroom 110	yes	Stair Risers	Metal	Orange	Chipping	25	2.1	Positive	None	0	N/A	Prior to Repair	No	no	no				
1	1	S12	Stairwell outside Classroom 110	yes	Baseboard	Metal	Orange	Chipping	30	3.2	Positive	None	0	N/A	Prior to Repair	No	no	no				
1	1	S12	Stairwell outside Classroom 110	yes	Baluster	Metal	Orange	Chipping	6	2.2	Positive	None	0	N/A	Prior to Repair	No	no	no				
1	2	S27	Stairwell to Library	yes	W1	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no				
1	2	S27	Stairwell to Library	yes	W2	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no				
1	2	S27	Stairwell to Library	yes	W3	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no				
1	2	S27	Stairwell to Library	yes	W4	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no				
1	2	S27	Stairwell to Library	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no				
1	2	S27	Stairwell to Library	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no				
1	2	S27	Stairwell to Library	yes	Stair Soffit	Metal	Yellow	Chipping	6	1.5	Positive	None	0	N/A	Prior to Repair	No	no	no				
1	2	S27	Stairwell to Library	yes	Stair Stringer	Metal	Yellow	Chipping	4	2.1	Positive	None	0	N/A	Prior to Repair	No	no	no				
1	2	S27	Stairwell to Library	yes	Stair Treads	Metal	Yellow	Chipping	2	1.6	Positive	None	0	N/A	Prior to Repair	No	no	no				
1	2	214C	Hallway From Computer Lab 214 to Elevator	yes	Doors	Metal	Green	Chipping	2	1.4	Positive	None	0	N/A	Prior to Repair	No	no	no				
1	2	214C	Hallway From Computer Lab 214 to Elevator	yes	Doors	Metal	Orange	Chipping	2	1.8	Positive	None	0	N/A	Prior to Repair	No	no	no				
1	2	214C	Hallway From Computer Lab 214 to Elevator	yes	Doors	Metal	Blue	Chipping	2	0.32	Negative	None	0	N/A	Prior to Repair	No	no	no				
1	2	214C	Hallway From Computer Lab 214 to Elevator	yes	Doors	Metal	Brown	Chipping	2	1.5	Positive	None	0	N/A	Prior to Repair	No	no	no				
1	2	H215	Hallway at Classroom 208 to 231A	yes	W1	Concrete	Orange	Chipping	4	0.06	Negative	None	0	N/A	Prior to Repair	No	no	no				
1	2	H215	Hallway at Classroom 208 to 231A	yes	W1	Concrete	Blue	Chipping	4	0	Negative	None	0	N/A	Prior to Repair	No	no	no				
1	2	H215	Hallway at Classroom 208 to 231A	yes	W2	Concrete	Orange	Chipping	5	0	Negative	None	0	N/A	Prior to Repair	No	no	no				
1	2	H215	Hallway at Classroom 208 to 231A	yes	W2	Concrete	Blue	Chipping	10	0	Negative	None	0	Negative	Prior to Repair	No	no	no				
1	2	H215	Hallway at Classroom 208 to 231A	yes	W3	Concrete	Orange	Chipping	4	0.06	Negative	None	0	N/A	Prior to Repair	No	no	no				
1	2	H215	Hallway at Classroom 208 to 231A	yes	W3	Concrete	Blue	Chipping	4	0	Negative	None	0	N/A	Prior to Repair	No	no	no				
1	2	H215	Hallway at Classroom 208 to 231A	yes	W4	Concrete	Orange	Chipping	4	0.08	Negative	None	0	N/A	Prior to Repair	No	no	no				
1	2	H215	Hallway at Classroom 208 to 231A	yes	W4	Concrete	Blue	Chipping	6	0	Negative	None	0	N/A	Prior to Repair	No	no	no				
1	2	H215	Hallway at Classroom 208 to 231A	yes	Ceiling	Concrete	White	None	0	0	Negative	None	0	N/A	No	No	no	no				
1	2	H215	Hallway at Classroom 208 to 231A	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no				
1	2	H215	Hallway at Classroom 208 to 231A	yes	Door Frame	Metal	Brown	Chipping	2	0.1	Negative	None	0	N/A	Prior to Repair	No	no	no				
1	2	H215	Hallway at Classroom 208 to 231A	yes	Doors	Metal	Green	Chipping	2	1.2	Positive	None	0	N/A	Prior to Repair	No	no	no				
1	2	H215	Hallway at Classroom 208 to 231A	yes	Doors	Metal	Orange	Chipping	2	1.3	Positive	None	0	N/A	Prior to Repair	No	no	no				
1	2	H215	Hallway at Classroom 208 to 231A	yes	Doors	Metal	Blue	Chipping	2	0.15	Negative	None	0	N/A	Prior to Repair	No	no	no				

					School District of Philadelphia																	
			Name of Inspector: Ryan Hutsell		Lead Safe Certification Assessment Report									Inspection Dates: 05/03-28/21								
			Inspection Company: Synertech, Inc.		Cramp School									ULCS# 5470								
E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	Lead Concentrati on (% wt)	Lead in Paint Chips by Flame AAS Analysis Results (positive / negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes			
1	2	H215	Hallway at Classroom 208 to 231A	yes	Doors	Metal	Brown	Chipping	2	1.1	Positive	None	0	N/A	Prior to Repair	No	no	no				
1	2	H215B	Hallway at 213A to Classroom 209	yes	W1	CMU	Tan	Chipping	5	0	Negative	None	0	N/A	Prior to Repair	No	no	no				
1	2	H215B	Hallway at 213A to Classroom 209	yes	W2	CMU	Tan	None	0	N/A	N/A	None	0	Negative	No	No	no	no				
1	2	H215B	Hallway at 213A to Classroom 209	yes	W3	CMU	Tan	Chipping	4	0	Negative	None	0	N/A	Prior to Repair	No	no	no				
1	2	H215B	Hallway at 213A to Classroom 209	yes	W4	CMU	Tan	None	0	N/A	N/A	None	0	N/A	No	No	no	no				
1	2	H215B	Hallway at 213A to Classroom 209	yes	Ceiling	Concrete	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no				
1	2	H215B	Hallway at 213A to Classroom 209	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no				
1	2	S21	Stairwell near Classroom 211	yes	W1	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no				
1	2	S21	Stairwell near Classroom 211	yes	Doors	Metal	Orange	Chipping	4	0	Negative	None	0	N/A	Prior to Repair	No	no	no				
1	2	S21	Stairwell near Classroom 211	yes	W2	Concrete	White	Flaking	4	0	Negative	None	0	N/A	Prior to Repair	No	no	no				
1	2	S21	Stairwell near Classroom 211	yes	Handrail	Metal	Black	Friction	12	0.15	Negative	None	0	N/A	Prior to Repair	No	no	no				
1	2	S21	Stairwell near Classroom 211	yes	W3	CMU	White	Cracking	12	0	Negative	None	0	N/A	Prior to Repair	No	no	no				
1	2	S21	Stairwell near Classroom 211	yes	Radiator	Metal	Orange	Chipping	2	0.12	Negative	None	0	N/A	Prior to Repair	No	no	no				
1	2	S21	Stairwell near Classroom 211	yes	W4	Concrete	White	Flaking	15	0	Negative	None	0	N/A	Prior to Repair	No	no	no				
1	2	S21	Stairwell near Classroom 211	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no				
1	2	S21	Stairwell near Classroom 211	yes	Floor	Concrete	N/A	None	0	N/A	N/A	None	0	N/A	No	No	no	no				
1	2	S21	Stairwell near Classroom 211	yes	Stair Stringer	Metal	Orange	Chipping	12	1.2	Positive	None	0	N/A	Prior to Repair	No	no	no				
1	2	S21	Stairwell near Classroom 211	yes	Stair Risers	Metal	Orange	Chipping	25	2	Positive	None	0	N/A	Prior to Repair	No	no	no				
1	2	S21	Stairwell near Classroom 211	yes	Baseboard	Metal	Orange	Chipping	30	1.9	Positive	None	0	N/A	Prior to Repair	No	no	no				
1	2	S21	Stairwell near Classroom 211	yes	Baluster	Metal	Orange	Chipping	6	2.4	Positive	None	0	N/A	Prior to Repair	No	no	no				
1	2	H219	Hallway from Stairwell near Cassroom 211 to Classroom 215	yes	W1	Concrete	Orange	Chipping	4	0	Negative	None	0	N/A	Prior to Repair	No	no	no				
1	2	H219	Hallway from Stairwell near Cassroom 211 to Classroom 215	yes	W1	Concrete	Blue	Chipping	4	0	Negative	None	0	N/A	Prior to Repair	No	no	no				
1	2	H219	Hallway from Stairwell near Cassroom 211 to Classroom 215	yes	W2	Concrete	Orange	Chipping	2	0	Negative	None	0	N/A	Prior to Repair	No	no	no				
1	2	H219	Hallway from Stairwell near Cassroom 211 to Classroom 215	yes	W2	Concrete	Blue	Chipping	4	0	Negative	None	0	N/A	Prior to Repair	No	no	no				
1	2	H219	Hallway from Stairwell near Cassroom 211 to Classroom 215	yes	W3	Concrete	Orange	Chipping	12	0	Negative	None	0	N/A	Prior to Repair	No	no	no				
1	2	H219	Hallway from Stairwell near Cassroom 211 to Classroom 215	yes	W3	Concrete	Blue	Chipping	2	0.06	Negative	None	0	N/A	Prior to Repair	No	no	no				
1	2	H219	Hallway from Stairwell near Cassroom 211 to Classroom 215	yes	W4	Concrete	Orange	Chipping	1	0.1	Negative	None	0	N/A	Prior to Repair	No	no	no				
1	2	H219	Hallway from Stairwell near Cassroom 211 to Classroom 215	yes	W4	Concrete	Blue	Chipping	4	0	Negative	None	0	N/A	Prior to Repair	No	no	no				
1	2	H219	Hallway from Stairwell near Cassroom 211 to Classroom 215	yes	Ceiling	Concrete	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no				
1	2	H219	Hallway from Stairwell near Cassroom 211 to Classroom 215	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no				
1	2	S22	Stairwell near Classroom 210	yes	W1	CMU	White	Cracking	10	0	Negative	None	0	N/A	Prior to Repair	No	no	no				
1	2	S22	Stairwell near Classroom 210	yes	Door Frame	Metal	Orange	Chipping	2	0.18	Negative	None	0	N/A	Prior to Repair	No	no	no				
1	2	S22	Stairwell near Classroom 210	yes	Door	Metal	Orange	Chipping	2	0.25	Negative	None	0	N/A	Prior to Repair	No	no	no				
1	2	S22	Stairwell near Classroom 210	yes	W2	CMU	White	Cracking	10	0	Negative	None	0	N/A	Prior to Repair	No	no	no				
1	2	S22	Stairwell near Classroom 210	yes	W3	CMU	White	Cracking	12	0	Negative	None	0	N/A	Prior to Repair	No	no	no				
1	2	S22	Stairwell near Classroom 210	yes	Handrail	Metal	Orange	Friction	2	1.5	Positive	None	0	N/A	Prior to Repair	No	no	no				
1	2	S22	Stairwell near Classroom 210	yes	W4	CMU	White	Cracking	12	0	Negative	None	0	N/A	Prior to Repair	No	no	no				
1	2	S22	Stairwell near Classroom 210	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no				
1	2	S22	Stairwell near Classroom 210	yes	Floor	Concrete	N/A	None	0	N/A	N/A	None	0	N/A	No	No	no	no				
1	2	S22	Stairwell near Classroom 210	yes	Stair Stringer	Metal	Orange	Chipping	12	2	Positive	None	0	N/A	Prior to Repair	No	no	no				
1	2	S22	Stairwell near Classroom 210	yes	Stair Risers	Metal	Orange	Chipping	25	2.6	Positive	None	0	N/A	Prior to Repair	No	no	no				
1	2	S22	Stairwell near Classroom 210	yes	Baseboard	Metal	Orange	Chipping	30	2.4	Positive	None	0	N/A	Prior to Repair	No	no	no				
1	2	S22	Stairwell near Classroom 210	yes	Baluster	Metal	Orange	Chipping	6	2.1	Positive	None	0	N/A	Prior to Repair	No	no	no				
1	2	H219	Hallway from Stairwell near Cassroom 211 to Classroom 215	yes	Door Frame	Metal	Brown	Chipping	2	0.1	Negative	None	0	N/A	Prior to Repair	No	no	no				
1	2	H219	Hallway from Stairwell near Cassroom 211 to Classroom 215	yes	Doors	Metal	Green	Chipping	2	1.2	Positive	None	0	N/A	Prior to Repair	No	no	no				
1	2	H219	Hallway from Stairwell near Cassroom 211 to Classroom 215	yes	Doors	Metal	Orange	Chipping	2	1.2	Positive	None	0	N/A	Prior to Repair	No	no	no				
1	2	H219	Hallway from Stairwell near Cassroom 211 to Classroom 215	yes	Doors	Metal	Blue	Chipping	2	0.1	Negative	None	0	N/A	Prior to Repair	No	no	no				
1	2	H219	Hallway from Stairwell near Cassroom 211 to Classroom 215	yes	Doors	Metal	Brown	Chipping	2	1.3	Positive	None	0	N/A	Prior to Repair	No	no	no				
1	2	H217	Hallway from Stairwell near Classroom 210 to Classroom 214	yes	W1	Concrete	Orange	Chipping	4	0.1	Negative	None	0	N/A	Prior to Repair	No	no	no				
1	2	H217	Hallway from Stairwell near Classroom 210 to Classroom 214	yes	W1	Concrete	Blue	Chipping	4	0	Negative	None	0	N/A	Prior to Repair	No	no	no				
1	2	H217	Hallway from Stairwell near Classroom 210 to Classroom 214	yes	W2	Concrete	Orange	Chipping	4	0	Negative	None	0	N/A	Prior to Repair	No	no	no				
1	2	H217	Hallway from Stairwell near Classroom 210 to Classroom 214	yes	W2	Concrete	Blue	Chipping	6	0.08	Negative	None	0	N/A	Prior to Repair	No	no	no				

					School District of Philadelphia																	
					Lead Safe Certification Assessment Report																	
					Cramp School																	
			Name of Inspector: Ryan Hutsell									Inspection Dates: 05/03-28/21										
			Inspection Company: Synertech, Inc.									ULCS# 5470										
E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	Lead Concentrati on (% wt)	Lead in Paint Chips by Flame AAS Analysis Results (positive / negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes			
1	2	H217	Hallway from Stairwell near Classroom 210 to Classroom 214	yes	W3	Concrete	Orange	Chipping	2	0.04	Negative	None	0	N/A	Prior to Repair	No	no	no				
1	2	H217	Hallway from Stairwell near Classroom 210 to Classroom 214	yes	W3	Concrete	Blue	Chipping	4	0	Negative	None	0	N/A	Prior to Repair	No	no	no				
1	2	H217	Hallway from Stairwell near Classroom 210 to Classroom 214	yes	W4	Concrete	Orange	Chipping	2	0.1	Negative	None	0	N/A	Prior to Repair	No	no	no				
1	2	H217	Hallway from Stairwell near Classroom 210 to Classroom 214	yes	W4	Concrete	Blue	Chipping	6	0	Negative	None	0	N/A	Prior to Repair	No	no	no				
1	2	H217	Hallway from Stairwell near Classroom 210 to Classroom 214	yes	Ceiling	Concrete	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no				
1	2	H217	Hallway from Stairwell near Classroom 210 to Classroom 214	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no				
1	2	F2	Throughout Second Floor	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no				
1	2	F2	Throughout Second Floor	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no				
1	2	F2	Throughout Second Floor	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no				
1	2	F2	Throughout Second Floor	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no				
1	2	F2	Throughout Second Floor	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no				
1	2	F2	Throughout Second Floor	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no				
1	3	300	Classroom 300	yes	W1	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no				
1	3	300	Classroom 300	yes	Sink Cabinet	Wood	Green	Chipping	15	1.2	Positive	None	0	N/A	Prior to Repair	No	no	no				
1	3	300	Classroom 300	yes	W2	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no				
1	3	300	Classroom 300	yes	W3	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no				
1	3	300	Classroom 300	yes	W4	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no				
1	3	300	Classroom 300	yes	Ceiling	Concrete	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no				
1	3	300	Classroom 300	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no				
1	3	301	Classroom 301	yes	W1	CMU	White	Chipping	4	0	Negative	None	0	N/A	Prior to Repair	No	no	no				
1	3	301	Classroom 301	yes	Door Frame	Metal	Yellow	Chipping	2	0	Negative	None	0	N/A	Prior to Repair	No	no	no				
1	3	301	Classroom 301	yes	Door	Wood	Brown	Chipping	4	2.6	Positive	None	0	N/A	Prior to Repair	No	no	no				
1	3	301	Classroom 301	yes	Sink Cabinet	Wood	Yellow	Chipping	15	1.5	Positive	None	0	N/A	Prior to Repair	No	no	no				
1	3	301	Classroom 301	yes	W2	CMU	White	Chipping	6	0	Negative	None	0	N/A	Prior to Repair	No	no	no				
1	3	301	Classroom 301	yes	W3	CMU	White	Chipping	5	0	Negative	None	0	N/A	Prior to Repair	No	no	no				
1	3	301	Classroom 301	yes	Partition Room Divider	Vinyl	White	Chipping	4	0	Negative	None	0	N/A	Prior to Repair	No	no	no				
1	3	301	Classroom 301	yes	W4	CMU	White	Chipping	8	0	Negative	None	0	N/A	Prior to Repair	No	no	no				
1	3	301	Classroom 301	yes	Door Frame	Wood	White	Chipping	1	0	Negative	None	0	N/A	Prior to Repair	No	no	no				
1	3	301	Classroom 301	yes	Door	Vinyl	White	Chipping	20	0	Negative	None	0	N/A	Prior to Repair	No	no	no				
1	3	301	Classroom 301	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	Drop ceiling			
1	3	301	Classroom 301	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	12"x12" Floor Tiles			
1	3	302	Storage Room between Classrooms 300 and 301	yes	W1	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no				
1	3	302	Storage Room between Classrooms 300 and 301	yes	Door	Wood	Black	Chipping	2	1.1	Positive	None	0	N/A	Prior to Repair	No	no	no				
1	3	302	Storage Room between Classrooms 300 and 301	yes	W2	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no				
1	3	302	Storage Room between Classrooms 300 and 301	yes	W3	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no				
1	3	302	Storage Room between Classrooms 300 and 301	yes	Shelves	Wood	Yellow	Friction	5	1.2	Positive	None	0	N/A	Prior to Repair	No	no	no				
1	3	302	Storage Room between Classrooms 300 and 301	yes	W4	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no				
1	3	302	Storage Room between Classrooms 300 and 301	yes	Door	Metal	Yellow	Chipping	1	0.3	Negative	None	0	N/A	Prior to Repair	No	no	no				
1	3	302	Storage Room between Classrooms 300 and 301	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	Drop ceiling			
1	3	302	Storage Room between Classrooms 300 and 301	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	12"x12" Floor Tiles			
1	3	305A	Storage Room 312	yes	W1	CMU	White	None	0	0	Negative	None	0	N/A	No	No	no	no				
1	3	305A	Storage Room 312	yes	W2	CMU	White	None	0	0	Negative	None	0	N/A	No	No	no	no				
1	3	305A	Storage Room 312	yes	Door Frame	Metal	Grey	Chipping	4	0	Negative	None	0	N/A	Prior to Repair	No	no	no				
1	3	305A	Storage Room 312	yes	W3	CMU	White	None	0	0	Negative	None	0	N/A	No	No	no	no				
1	3	305A	Storage Room 312	yes	Shelves	Wood	Green	Chipping	4	1.4	Positive	None	0	N/A	Prior to Repair	No	no	no				
1	3	305A	Storage Room 312	yes	Sink Cabinet	Wood	Green	Chipping	12	1.4	Positive	None	0	N/A	Prior to Repair	No	no	no				
1	3	305A	Storage Room 312	yes	W4	CMU	White	None	0	0	Negative	None	0	N/A	No	No	no	no				
1	3	305A	Storage Room 312	yes	Ceiling	Concrete	White	None	0	0.08	Negative	None	0	N/A	No	No	no	no				
1	3	305A	Storage Room 312	yes	Column	Concrete	Black	Chipping	4	0	Negative	None	0	N/A	Prior to Repair	No	no	no				
1	3	305A	Storage Room 312	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no				
1	3	305B	Storage Room 312 Closet	yes	W1	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no				

					School District of Philadelphia															
			Name of Inspector: Ryan Hutsell		Lead Safe Certification Assessment Report								Inspection Dates: 05/03-28/21							
			Inspection Company: Synertech, Inc.		Cramp School								ULCS# 5470							
E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	Lead Concentrati on (% wt)	Lead in Paint Chips by Flame AAS Analysis Results (positive / negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes	
1	3	305B	Storage Room 312 Closet	yes	W2	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no		
1	3	305B	Storage Room 312 Closet	yes	W3	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no		
1	3	305B	Storage Room 312 Closet	yes	Shelves	Wood	Green	Friction	4	1.6	Positive	None	0	N/A	Prior to Repair	No	no	no		
1	3	305B	Storage Room 312 Closet	yes	W4	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no		
1	3	305B	Storage Room 312 Closet	yes	Ceiling	Concrete	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no		
1	3	305B	Storage Room 312 Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no		
1	3	303	Classroom 305	yes	W1	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no		
1	3	303	Classroom 305	yes	Door Frame	Metal	Blue	Friction	2	0.1	Negative	None	0	N/A	Prior to Repair	No	no	no		
1	3	303	Classroom 305	yes	Door	Metal	Blue	Chipping	2	0.12	Negative	None	0	N/A	Prior to Repair	No	no	no		
1	3	303	Classroom 305	yes	W2	CMU	White	Cracking	10	0	Negative	None	0	N/A	Prior to Repair	No	no	no		
1	3	303	Classroom 305	yes	W3	Sheetrock	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no		
1	3	303	Classroom 305	yes	W4	Vinyl	White	Cracking	6	0.1	Negative	None	0	N/A	Prior to Repair	No	no	no		
1	3	303	Classroom 305	yes	Sink Cabinet	Wood	Blue	Chipping	12	0.3	Negative	None	0	N/A	Prior to Repair	No	no	no		
1	3	303	Classroom 305	yes	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no		
1	3	303	Classroom 305	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no		
1	3	303	Classroom 305	yes	Baseboard	Wood	Brown	Chipping	8	0	Negative	None	0	N/A	Prior to Repair	No	no	no		
1	3	303A	Classroom 305 Closet	yes	W1	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no		
1	3	303A	Classroom 305 Closet	yes	W2	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no		
1	3	303A	Classroom 305 Closet	yes	W3	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no		
1	3	303A	Classroom 305 Closet	yes	Shelves	Wood	Green	Friction	4	1.3	Positive	None	0	N/A	Prior to Repair	No	no	no		
1	3	303A	Classroom 305 Closet	yes	W4	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no		
1	3	303A	Classroom 305 Closet	yes	Ceiling	Concrete	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no		
1	3	303A	Classroom 305 Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no		
1	3	307	Classroom 307	yes	W1	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no		
1	3	307	Classroom 307	yes	Door Frame	Metal	Yellow	Chipping	2	0.12	Negative	None	0	N/A	Prior to Repair	No	no	no		
1	3	307	Classroom 307	yes	Door	Wood	Yellow	Chipping	4	1.8	Positive	None	0	N/A	Prior to Repair	No	no	no		
1	3	307	Classroom 307	yes	Sink Cabinet	Wood	Red	Chipping	4	2.5	Positive	None	0	N/A	Prior to Repair	No	no	no		
1	3	307	Classroom 307	yes	Door	Wood	Red	Chipping	12	1.3	Positive	None	0	N/A	Prior to Repair	No	no	no		
1	3	307	Classroom 307	yes	W2	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no		
1	3	307	Classroom 307	yes	Door Frame	Metal	Yellow	Chipping	2	0.14	Negative	None	0	N/A	Prior to Repair	No	no	no		
1	3	307	Classroom 307	yes	Door	Wood	Yellow	Chipping	2	1.8	Positive	None	0	N/A	Prior to Repair	No	no	no		
1	3	307	Classroom 307	yes	W3	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no		
1	3	307	Classroom 307	yes	W4	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no		
1	3	307	Classroom 307	yes	Shelves/Coat Rack	Wood	Red	Chipping	10	1.3	Positive	None	0	N/A	Prior to Repair	No	no	no		
1	3	307	Classroom 307	yes	Ceiling	Concrete	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no		
1	3	307	Classroom 307	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no		
1	3	307A	Classroom 307 Closet	yes	W1	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no		
1	3	307A	Classroom 307 Closet	yes	W2	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no		
1	3	307A	Classroom 307 Closet	yes	W3	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no		
1	3	307A	Classroom 307 Closet	yes	Shelves	Wood	Green	Friction	4	1.3	Positive	None	0	N/A	Prior to Repair	No	no	no		
1	3	307A	Classroom 307 Closet	yes	W4	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no		
1	3	307A	Classroom 307 Closet	yes	Ceiling	Concrete	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no		
1	3	307A	Classroom 307 Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no		
1	3	309	Classroom 309	yes	W1	CMU	White	Chipping	4	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no		
1	3	309	Classroom 309	yes	Sink Cabinet	Wood	Green	Chipping	4	1.4	Positive	None	0	N/A	Prior to Repair	No	no	no		
1	3	309	Classroom 309	yes	W2	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no		
1	3	309	Classroom 309	yes	W3	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no		
1	3	309	Classroom 309	yes	W4	Concrete	White	Cracking	10	0.1	Negative	None	0	N/A	Partially Inaccessible	No	no	no		
1	3	309	Classroom 309	yes	Shelves	Wood	Green	Friction	16	1.2	Positive	None	0	N/A	Partially Inaccessible	No	no	no		
1	3	309	Classroom 309	yes	Ceiling	Concrete	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no		
1	3	309	Classroom 309	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no		

					School District of Philadelphia																	
			Name of Inspector: Ryan Hutsell		Lead Safe Certification Assessment Report									Inspection Dates: 05/03-28/21								
			Inspection Company: Synertech, Inc.		Cramp School									ULCS# 5470								
E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	Lead Concentrati on (% wt)	Lead in Paint Chips by Flame AAS Analysis Results (positive / negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes			
1	3	309A	Classroom 309 Closet without Door	yes	W1	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no				
1	3	309A	Classroom 309 Closet without Door	yes	W2	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no				
1	3	309A	Classroom 309 Closet without Door	yes	W3	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no				
1	3	309A	Classroom 309 Closet without Door	yes	W4	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no				
1	3	309A	Classroom 309 Closet without Door	yes	Ceiling	Concrete	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no				
1	3	309A	Classroom 309 Closet without Door	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no				
1	3	309B	Classroom 309 Closet with Door	yes	W1	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no				
1	3	309B	Classroom 309 Closet with Door	yes	Door	Wood	Blue	Friction	2	1.2	Positive	None	0	N/A	Prior to Repair	No	no	no				
1	3	309B	Classroom 309 Closet with Door	yes	W2	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no				
1	3	309B	Classroom 309 Closet with Door	yes	W3	CMU	White	None	0	0.04	Negative	None	0	N/A	Partially Inaccessible	No	no	no				
1	3	309B	Classroom 309 Closet with Door	yes	Shelves	Wood	Green	Friction	10	1.4	Positive	None	0	N/A	Prior to Repair	No	no	no				
1	3	309B	Classroom 309 Closet with Door	yes	W4	CMU	White	None	0	0.02	Negative	None	0	N/A	Partially Inaccessible	No	no	no				
1	3	309B	Classroom 309 Closet with Door	yes	Ceiling	Concrete	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no				
1	3	309B	Classroom 309 Closet with Door	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no				
1	3	311	Classroom 311	yes	W1	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no				
1	3	311	Classroom 311	yes	Door Frame	Metal	Yellow	Friction	4	0.25	Negative	None	0	N/A	Prior to Repair	No	no	no				
1	3	311	Classroom 311	yes	Door	Metal	Brown	Chipping	2	1.9	Positive	None	0	N/A	Prior to Repair	No	no	no				
1	3	311	Classroom 311	yes	Sink Cabinet	Wood	Yellow	Chipping	4	1.6	Positive	None	0	N/A	Prior to Repair	No	no	no				
1	3	311	Classroom 311	yes	W2	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no				
1	3	311	Classroom 311	yes	Shelves	Wood	Yellow	Friction	2	2.1	Positive	None	0	N/A	Prior to Repair	No	no	no				
1	3	311	Classroom 311	yes	Shelves/Coat Rack	Wood	Yellow	Chipping	4	1.9	Positive	None	0	N/A	Prior to Repair	No	no	no				
1	3	311	Classroom 311	yes	W3	CMU	White	Cracking	10	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no				
1	3	311	Classroom 311	yes	W4	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no				
1	3	311	Classroom 311	yes	Partition Room Divider	Wood	White	Cracking	10	0	Negative	None	0	N/A	Prior to Repair	No	no	no				
1	3	311	Classroom 311	yes	Sink Cabinet	Wood	Yellow	Chipping	12	1.5	Positive	None	0	N/A	Prior to Repair	No	no	no				
1	3	311	Classroom 311	yes	Door Frame	Metal	Yellow	Chipping	2	0.2	Negative	None	0	N/A	Prior to Repair	No	no	no				
1	3	311	Classroom 311	yes	Door	Wood	Red	Chipping	1	2.1	Positive	None	0	N/A	Prior to Repair	No	no	no				
1	3	311	Classroom 311	yes	Ceiling	Concrete	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no				
1	3	311	Classroom 311	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no				
1	3	311A	Classroom 311 Closet	yes	W1	CMU	White	None	0	0	N/A	None	0	N/A	No	No	no	no				
1	3	311A	Classroom 311 Closet	yes	W2	CMU	White	None	0	0	N/A	None	0	N/A	No	No	no	no				
1	3	311A	Classroom 311 Closet	yes	W3	CMU	White	None	0	0	N/A	None	0	N/A	No	No	no	no				
1	3	311A	Classroom 311 Closet	yes	Shelves	Wood	Green	Friction	2	1.2	Positive	None	0	N/A	Prior to Repair	No	no	no				
1	3	311A	Classroom 311 Closet	yes	W4	CMU	White	None	0	0	N/A	None	0	N/A	No	No	no	no				
1	3	311A	Classroom 311 Closet	yes	Ceiling	Concrete	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no				
1	3	311A	Classroom 311 Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no				
1	3	300A	Office across from Classroom 308	yes	W1	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no				
1	3	300A	Office across from Classroom 308	yes	W2	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no				
1	3	300A	Office across from Classroom 308	yes	W3	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no				
1	3	300A	Office across from Classroom 308	yes	Shelves	Wood	Yellow	Friction	6	1.8	Positive	None	0	N/A	Prior to Repair	No	no	no				
1	3	300A	Office across from Classroom 308	yes	W4	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no				
1	3	300A	Office across from Classroom 308	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	Drop ceiling			
1	3	300A	Office across from Classroom 308	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	12"x12" Floor tiles			
1	3	300B	Office across from Classroom 308 Closet	yes	W1	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no				
1	3	300B	Office across from Classroom 308 Closet	yes	W2	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no				
1	3	300B	Office across from Classroom 308 Closet	yes	W3	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no				
1	3	300B	Office across from Classroom 308 Closet	yes	Shelves	Wood	Green	Friction	4	1.3	Positive	None	0	N/A	Prior to Repair	No	no	no				
1	3	300B	Office across from Classroom 308 Closet	yes	W4	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no				

					School District of Philadelphia																	
			Name of Inspector: Ryan Hutsell		Lead Safe Certification Assessment Report									Inspection Dates: 05/03-28/21								
			Inspection Company: Synertech, Inc.		Cramp School									ULCS# 5470								
E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	Lead Concentrati on (% wt)	Lead in Paint Chips by Flame AAS Analysis Results (positive / negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes			
1	3	300B	Office across from Classroom 308 Closet	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no				
1	3	300B	Office across from Classroom 308 Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no				
1	3	304	Classroom 304	yes	W1	CMU	White	Chipping	4	0.04	Negative	None	0	N/A	Prior to Repair	No	no	no				
1	3	304	Classroom 304	yes	Sink Cabinet	Wood	Green	Chipping	15	2.8	Positive	None	0	N/A	Prior to Repair	No	no	no				
1	3	304	Classroom 304	yes	W2	Sheetrock	White	Chipping	40	0	Negative	None	0	N/A	Prior to Repair	No	no	no				
1	3	304	Classroom 304	yes	Partition Room Divider	Vinyl	White	Chipping	30	0	Negative	None	0	N/A	Prior to Repair	No	no	no				
1	3	304	Classroom 304	yes	Door	Wood	Black	Chipping	4	2	Positive	None	0	N/A	Prior to Repair	No	no	no				
1	3	304	Classroom 304	yes	W3	Concrete	White	Cracking	60	0.1	Negative	None	0	N/A	Prior to Repair	No	no	no				
1	3	304	Classroom 304	yes	W4	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no				
1	3	304	Classroom 304	yes	Shelves	Wood	Green	Friction	9	2.1	Positive	None	0	N/A	Prior to Repair	No	no	no				
1	3	304	Classroom 304	yes	Shelves/Coat Rack	Wood	Green	Friction	9	2.3	Positive	None	0	N/A	Prior to Repair	No	no	no				
1	3	304	Classroom 304	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no				
1	3	304	Classroom 304	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no				
1	3	304A	Classroom 304 Closet	yes	W1	CMU	White	None	0	0	Negative	None	0	N/A	No	No	no	no				
1	3	304A	Classroom 304 Closet	yes	W2	CMU	White	None	0	0	Negative	None	0	N/A	No	No	no	no				
1	3	304A	Classroom 304 Closet	yes	W3	CMU	White	None	0	0	Negative	None	0	N/A	No	No	no	no				
1	3	304A	Classroom 304 Closet	yes	Shelves	Wood	Green	Friction	4	1.9	Positive	None	0	N/A	Prior to Repair	No	no	no				
1	3	304A	Classroom 304 Closet	yes	W4	CMU	White	None	0	0	Negative	None	0	N/A	No	No	no	no				
1	3	304A	Classroom 304 Closet	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no				
1	3	304A	Classroom 304 Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no				
1	3	306	Classroom 306	yes	W1	CMU	White	Chipping	2	0	Negative	None	0	N/A	Prior to Repair	No	no	no				
1	3	306	Classroom 306	yes	Shelves	Wood	Red	Friction	10	0.9	Positive	None	0	N/A	Prior to Repair	No	no	no				
1	3	306	Classroom 306	yes	Shelves/Coat Rack	Wood	Red	Friction	10	1.2	Positive	None	0	N/A	Prior to Repair	No	no	no				
1	3	306	Classroom 306	yes	Door Frame	Metal	Blue	Chipping	6	0.1	Negative	None	0	N/A	Prior to Repair	No	no	no				
1	3	306	Classroom 306	yes	Door	Wood	Black	Chipping	8	1	Positive	None	0	N/A	Prior to Repair	No	no	no				
1	3	306	Classroom 306	yes	Sink Cabinet	Wood	Red	Chipping	15	1.5	Positive	None	0	N/A	Prior to Repair	No	no	no				
1	3	306	Classroom 306	yes	W2	CMU	White	Chipping	8	0	Negative	None	0	N/A	Prior to Repair	No	no	no				
1	3	306	Classroom 306	yes	W3	CMU	White	Chipping	10	0	Negative	None	0	N/A	Prior to Repair	No	no	no				
1	3	306	Classroom 306	yes	W4	CMU	White	Chipping	10	0	Negative	None	0	N/A	Prior to Repair	No	no	no				
1	3	306	Classroom 306	yes	Door	Metal	Green	Chipping	2	0.9	Positive	None	0	N/A	Prior to Repair	No	no	no				
1	3	306	Classroom 306	yes	Partition Room Divider	Vinyl	White	Chipping	10	0	Negative	None	0	N/A	Prior to Repair	No	no	no				
1	3	306	Classroom 306	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no				
1	3	306	Classroom 306	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no				
1	3	306A	Classroom 306 Closet	yes	W1	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no				
1	3	306A	Classroom 306 Closet	yes	Door	Wood	Green	Holes	2	1.2	Positive	None	0	N/A	Prior to Repair	No	no	no				
1	3	306A	Classroom 306 Closet	yes	W2	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no				
1	3	306A	Classroom 306 Closet	yes	W3	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no				
1	3	306A	Classroom 306 Closet	yes	Shelves	Wood	Green	Friction	2	1	Positive	None	0	N/A	Prior to Repair	No	no	no				
1	3	306A	Classroom 306 Closet	yes	W4	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no				
1	3	306A	Classroom 306 Closet	yes	Ceiling	Concrete	White	Cracking	2	0	Negative	None	0	N/A	Prior to Repair	No	no	no				
1	3	306A	Classroom 306 Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no				
1	3	308	Classroom 308	yes	W1	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no				
1	3	308	Classroom 308	yes	Door Frame	Metal	Blue	Chipping	2	0.1	Negative	None	0	N/A	Prior to Repair	No	no	no				
1	3	308	Classroom 308	yes	Door	Metal	Blue	Chipping	2	0.17	Negative	None	0	N/A	Prior to Repair	No	no	no				
1	3	308	Classroom 308	yes	Sink Cabinet	Wood	N/A	Chipping	15	0.12	Negative	None	0	N/A	Prior to Repair	No	no	no				
1	3	308	Classroom 308	yes	W2	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no				
1	3	308	Classroom 308	yes	W3	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no				
1	3	308	Classroom 308	yes	W4	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no				
1	3	308	Classroom 308	yes	Shelves	Wood	Blue	Friction	8	0.08	Negative	None	0	N/A	Prior to Repair	No	no	no				
1	3	308	Classroom 308	yes	Shelves/Coat Rack	Wood	Blue	Friction	8	0.02	Negative	None	0	N/A	Prior to Repair	No	no	no				
1	3	308	Classroom 308	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	Drop ceiling			
1	3	308	Classroom 308	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	12"x12" Floor Tiles			
1	3	308A	Classroom 308 Closet without Door	yes	W1	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no				
1	3	308A	Classroom 308 Closet without Door	yes	W2	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no				
1	3	308A	Classroom 308 Closet without Door	yes	W3	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no				
1	3	308A	Classroom 308 Closet without Door	yes	Shelves	Wood	Green	Friction	4	2	Positive	None	0	N/A	Partially Inaccessible	No	no	no				

			School District of Philadelphia																		
			Name of Inspector: Ryan Hutsell		Lead Safe Certification Assessment Report							Inspection Dates: 05/03-28/21									
			Inspection Company: Synertech, Inc.		Cramp School							ULCS# 5470									
E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	Lead Concentrati on (% wt)	Lead in Paint Chips by Flame AAS Analysis Results (positive / negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes		
1	3	308A	Classroom 308 Closet without Door	yes	W4	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no			
1	3	308A	Classroom 308 Closet without Door	yes	Ceiling	Concrete	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no			
1	3	308A	Classroom 308 Closet without Door	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no			
1	3	308B	Classroom 308 Closet with Door	yes	W1	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no			
1	3	308B	Classroom 308 Closet with Door	yes	W2	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no			
1	3	308B	Classroom 308 Closet with Door	yes	W3	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no			
1	3	308B	Classroom 308 Closet with Door	yes	Shelves	Wood	Green	Friction	4	1.9	Positive	None	0	N/A	Partially Inaccessible	No	no	no			
1	3	308B	Classroom 308 Closet with Door	yes	W4	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no			
1	3	308B	Classroom 308 Closet with Door	yes	Ceiling	Concrete	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no			
1	3	308B	Classroom 308 Closet with Door	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no			
1	3	310	Classroom 310	yes	W1	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no			
1	3	310	Classroom 310	yes	Door	Wood	Green	Chipping	4	1.5	Positive	None	0	N/A	Prior to Repair	No	no	no			
1	3	310	Classroom 310	yes	Sink Cabinet	Wood	Green	Chipping	4	1.9	Positive	None	0	N/A	Prior to Repair	No	no	no			
1	3	310	Classroom 310	yes	W2	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no			
1	3	310	Classroom 310	yes	Door	Wood	Green	Chipping	12	1.6	Positive	None	0	N/A	Prior to Repair	No	no	no			
1	3	310	Classroom 310	yes	W3	Concrete	White	Cracking	12	0.06	Negative	None	0	N/A	Prior to Repair	No	no	no			
1	3	310	Classroom 310	yes	W4	Concrete	White	Chipping	36		Negative	None	0	N/A	Prior to Repair	No	no	no			
1	3	310	Classroom 310	yes	Shelves/Coat Rack	Wood	Green	Friction	12	1.8	Positive	None	0	N/A	Prior to Repair	No	no	no			
1	3	310	Classroom 310	yes	Ceiling	Concrete	White	Chipping	2	0	Negative	None	0	N/A	Prior to Repair	No	no	no			
1	3	310	Classroom 310	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no			
1	3	310B	Classroom 310 Closet	yes	W1	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no			
1	3	310B	Classroom 310 Closet	yes	W2	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no			
1	3	310B	Classroom 310 Closet	yes	W3	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no			
1	3	310B	Classroom 310 Closet	yes	Shelves	Wood	Green	Friction	2	2.1	Positive	None	0	N/A	Prior to Repair	No	no	no			
1	3	310B	Classroom 310 Closet	yes	W4	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no			
1	3	310B	Classroom 310 Closet	yes	Ceiling	Concrete	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no			
1	3	310B	Classroom 310 Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no			
1	3	311C	Custodial Closet adjacent to Boy's Restroom	no	W1	CMU	White	Chipping	2	0	Negative	None	0	N/A	Prior to Repair	No	no	no			
1	3	311C	Custodial Closet adjacent to Boy's Restroom	no	Door Frame	Metal	White	Chipping	2	0	Negative	None	0	N/A	Prior to Repair	No	no	no			
1	3	311C	Custodial Closet adjacent to Boy's Restroom	no	Door	Wood	Green	Chipping	2	0.15	Negative	None	0	N/A	Prior to Repair	No	no	no			
1	3	311C	Custodial Closet adjacent to Boy's Restroom	no	W2	CMU	White	Chipping	2	0	Negative	None	0	N/A	Prior to Repair	No	no	no			
1	3	311C	Custodial Closet adjacent to Boy's Restroom	no	Sink	Metal	White	Flaking	4	0	Negative	None	0	N/A	Prior to Repair	No	no	no			
1	3	311C	Custodial Closet adjacent to Boy's Restroom	no	W3	CMU	White	None	N/A	N/A	N/A	None	0	N/A	No	No	no	no			
1	3	311C	Custodial Closet adjacent to Boy's Restroom	no	W4	CMU	White	None	N/A	N/A	N/A	None	0	N/A	No	No	no	no			
1	3	311C	Custodial Closet adjacent to Boy's Restroom	no	Ceiling	Concrete	White	None	N/A	N/A	N/A	None	0	N/A	No	No	no	no			
1	3	311C	Custodial Closet adjacent to Boy's Restroom	no	Floor	Concrete	Grey	Chipping	6	0	Negative	None	0	N/A	Prior to Repair	No	no	no			
1	3	311D	3rd Floor Men's Restroom	yes	W1	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no			
1	3	311D	3rd Floor Men's Restroom	yes	W2	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no			
1	3	311D	3rd Floor Men's Restroom	yes	W3	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no			
1	3	311D	3rd Floor Men's Restroom	yes	W4	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no			
1	3	311D	3rd Floor Men's Restroom	yes	Ceiling	Plaster	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no			
1	3	311D	3rd Floor Men's Restroom	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	Ceramic Tiles		
1	3	313	Classroom 313	yes	W1	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no			
1	3	313	Classroom 313	yes	Sink Cabinet	Wood	N/A	Chipping	4	N/A	Positive	None	0	N/A	Prior to Repair	No	no	no			
1	3	313	Classroom 313	yes	W2	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no			
1	3	313	Classroom 313	yes	W3	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no			
1	3	313	Classroom 313	yes	W4	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no			
1	3	313	Classroom 313	yes	Ceiling	Concrete	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no			

					School District of Philadelphia																	
			Name of Inspector: Ryan Hutsell		Lead Safe Certification Assessment Report									Inspection Dates: 05/03-28/21								
			Inspection Company: Synertech, Inc.		Cramp School									ULCS# 5470								
E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	Lead Concentrati on (% wt)	Lead in Paint Chips by Flame AAS Analysis Results (positive / negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes			
1	3	313	Classroom 313	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no				
1	3	313A	Storage Room behind Elevator	yes	W1	CMU	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	Unpainted			
1	3	313A	Storage Room behind Elevator	yes	W2	CMU	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no				
1	3	313A	Storage Room behind Elevator	yes	W3	CMU	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no				
1	3	313A	Storage Room behind Elevator	yes	Shelves	Wood	Green	Friction	10	2	Positive	None	0	N/A	Prior to Repair	No	no	no				
1	3	313A	Storage Room behind Elevator	yes	W4	CMU	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no				
1	3	313A	Storage Room behind Elevator	yes	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no				
1	3	313A	Storage Room behind Elevator	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	9"x9" Floor tiles			
1	3	312B	3rd Floor Women's Restroom	yes	W1	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no				
1	3	312B	3rd Floor Women's Restroom	yes	Switch Plate	Metal	Blue	Chipping	1	0	Negative	None	0	N/A	Prior to Repair	No	no	no				
1	3	312B	3rd Floor Women's Restroom	yes	Door Frame	Metal	White	Chipping	2	0	Negative	None	0	N/A	Prior to Repair	No	no	no				
1	3	312B	3rd Floor Women's Restroom	yes	Door	Wood	Yellow	Chipping	4	1.8	Positive	None	0	N/A	Prior to Repair	No	no	no				
1	3	312B	3rd Floor Women's Restroom	yes	W2	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no				
1	3	312B	3rd Floor Women's Restroom	yes	W3	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no				
1	3	312B	3rd Floor Women's Restroom	yes	W4	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no				
1	3	312B	3rd Floor Women's Restroom	yes	Ceiling	Concrete	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no				
1	3	312B	3rd Floor Women's Restroom	yes	Floor	Concrete	Grey	None	0	N/A	N/A	None	0	N/A	No	No	no	no				
1	3	312B	3rd Floor Women's Restroom	yes	Stall Divider	Metal	Blue	Chipping	10	0.1	Negative	None	0	N/A	Prior to Repair	No	no	no				
1	3	310A	Custodial Closet and Roof Access adjacent to Women's Restroom	yes	W1	CMU	White	Chipping	2	0	Negative	None	0	N/A	Prior to Repair	No	no	no				
1	3	310A	Custodial Closet and Roof Access adjacent to Women's Restroom	yes	Door Frame	Metal	White	Chipping	2	0.11	Negative	None	0	N/A	Prior to Repair	No	no	no				
1	3	310A	Custodial Closet and Roof Access adjacent to Women's Restroom	yes	Door	Metal	Blue	Chipping	2	0.06	Negative	None	0	N/A	Prior to Repair	No	no	no				
1	3	310A	Custodial Closet and Roof Access adjacent to Women's Restroom	yes	W2	CMU	White	Chipping	2	0	Negative	None	0	N/A	Prior to Repair	No	no	no				
1	3	310A	Custodial Closet and Roof Access adjacent to Women's Restroom	yes	Shelves	Wood	Green	Friction	4	1.6	Positive	None	0	N/A	Prior to Repair	No	no	no				
1	3	310A	Custodial Closet and Roof Access adjacent to Women's Restroom	yes	W3	CMU	White	Chipping	2	0	Negative	None	0	N/A	Prior to Repair	No	no	no				
1	3	310A	Custodial Closet and Roof Access adjacent to Women's Restroom	yes	W4	CMU	White	Chipping	2	0	Negative	None	0	N/A	Prior to Repair	No	no	no				
1	3	310A	Custodial Closet and Roof Access adjacent to Women's Restroom	yes	Ceiling	Concrete	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no				
1	3	310A	Custodial Closet and Roof Access adjacent to Women's Restroom	yes	Floor	Concrete	Grey	Chipping	1	0	Negative	None	0	N/A	Prior to Repair	No	no	no				
1	3	310B	Custodial Closet and Roof Access adjacent to Women's Restroom Pipe Chase	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	Unpainted			
1	3	310B	Custodial Closet and Roof Access adjacent to Women's Restroom Pipe Chase	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	Unpainted			
1	3	310B	Custodial Closet and Roof Access adjacent to Women's Restroom Pipe Chase	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	Unpainted			
1	3	310B	Custodial Closet and Roof Access adjacent to Women's Restroom Pipe Chase	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	Unpainted			
1	3	310B	Custodial Closet and Roof Access adjacent to Women's Restroom Pipe Chase	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	Unpainted			
1	3	310B	Custodial Closet and Roof Access adjacent to Women's Restroom Pipe Chase	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	Unpainted			
1	3	314	Library	yes	W1	CMU	Yellow	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no				
1	3	314	Library	yes	W1	CMU	Blue	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no				
1	3	314	Library	yes	W1	Concrete	Blue	Chipping	2	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no				
1	3	314	Library	yes	Door Frame	Metal	Orange	Chipping	2	0.17	Negative	None	0	N/A	Prior to Repair	No	no	no				
1	3	314	Library	yes	Door	Metal	Orange	Chipping	2	2.1	Positive	None	0	N/A	Prior to Repair	No	no	no				
1	3	314	Library	yes	W2	CMU	Yellow	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no				
1	3	314	Library	yes	W2	CMU	Blue	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no				
1	3	314	Library	yes	W2	Concrete	Blue	Chipping	1	0.1	Negative	None	0	N/A	Partially Inaccessible	No	no	no				
1	3	314	Library	yes	Door	Metal	Yellow	Chipping	2	2.6	Positive	None	0	N/A	Prior to Repair	No	no	no				
1	3	314	Library	yes	W3	CMU	Yellow	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no				
1	3	314	Library	yes	W3	CMU	Blue	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no				

					School District of Philadelphia																	
			Name of Inspector: Ryan Hutsell		Lead Safe Certification Assessment Report									Inspection Dates: 05/03-28/21								
			Inspection Company: Synertech, Inc.		Cramp School									ULCS# 5470								
E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	Lead Concentrati on (% wt)	Lead in Paint Chips by Flame AAS Analysis Results (positive / negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes			
1	3	314	Library	yes	W3	Concrete	Blue	Chipping	2	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no				
1	3	314	Library	yes	Door Frame	Metal	Red	Chipping	2	0.5	Negative	None	0	N/A	Prior to Repair	No	no	no				
1	3	314	Library	yes	Door	Metal	Red	Chipping	2	1.3	Positive	None	0	N/A	Prior to Repair	No	no	no				
1	3	314	Library	yes	W4	CMU	Yellow	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no				
1	3	314	Library	yes	W4	CMU	Blue	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no				
1	3	314	Library	yes	Door	Metal	Green	Chipping	1	0.15	Negative	None	0	N/A	Prior to Repair	No	no	no				
1	3	314	Library	yes	Door Frame	Metal	White	Chipping	4	0.1	Negative	None	0	N/A	Prior to Repair	No	no	no				
1	3	314	Library	yes	Window Frame	Metal	White	Chipping	4	0.11	Negative	None	0	N/A	Prior to Repair	No	no	no				
1	3	314	Library	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no				
1	3	314	Library	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no				
1	3	314	Library	yes	Stair Soffit	Metal	Yellow	Chipping	6	1.5	Positive	None	0	N/A	Prior to Repair	No	no	no				
1	3	314	Library	yes	Stair Stringer	Metal	Yellow	Chipping	4	2.1	Positive	None	0	N/A	Prior to Repair	No	no	no				
1	3	314	Library	yes	Stair Treads	Metal	Yellow	Chipping	2	1.6	Positive	None	0	N/A	Prior to Repair	No	no	no				
1	3	314A	Library Office adjacent to Computer Lab	yes	W1	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no				
1	3	314A	Library Office adjacent to Computer Lab	yes	Door	Metal	Yellow	Chipping	1	1.9	Positive	None	0	N/A	Prior to Repair	No	no	no				
1	3	314A	Library Office adjacent to Computer Lab	yes	W2	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no				
1	3	314A	Library Office adjacent to Computer Lab	yes	Door	Metal	Blue	Chipping	1	0.14	Positive	None	0	N/A	Prior to Repair	No	no	no				
1	3	314A	Library Office adjacent to Computer Lab	yes	W3	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no				
1	3	314A	Library Office adjacent to Computer Lab	yes	Door	Metal	Green	Chipping	1	2.1	Positive	None	0	N/A	Prior to Repair	No	no	no				
1	3	314A	Library Office adjacent to Computer Lab	yes	W4	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no				
1	3	314A	Library Office adjacent to Computer Lab	yes	Door	Metal	Green	Chipping	1	1.8	Positive	None	0	N/A	Prior to Repair	No	no	no				
1	3	314A	Library Office adjacent to Computer Lab	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no				
1	3	314A	Library Office adjacent to Computer Lab	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no				
1	3	314F	Library Office adjacent to Computer Lab Closet	yes	W1	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no				
1	3	314F	Library Office adjacent to Computer Lab Closet	yes	W2	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no				
1	3	314F	Library Office adjacent to Computer Lab Closet	yes	W3	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no				
1	3	314F	Library Office adjacent to Computer Lab Closet	yes	W4	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no				
1	3	314F	Library Office adjacent to Computer Lab Closet	yes	Ceiling	Concrete	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no				
1	3	314F	Library Office adjacent to Computer Lab Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no				
1	3	314B	Audio Visual Storage Room	yes	W1	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no				
1	3	314B	Audio Visual Storage Room	yes	Door	Metal	Green	Chipping	2	1.4	Positive	None	0	N/A	Prior to Repair	No	no	no				
1	3	314B	Audio Visual Storage Room	yes	W2	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no				
1	3	314B	Audio Visual Storage Room	yes	Door Frame	Metal	Blue	Chipping	1	1.5	Positive	None	0	N/A	Prior to Repair	No	no	no				
1	3	314B	Audio Visual Storage Room	yes	Door	Metal	Blue	Chipping	1	1.1	Positive	None	0	N/A	Prior to Repair	No	no	no				
1	3	314B	Audio Visual Storage Room	yes	W3	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no				
1	3	314B	Audio Visual Storage Room	yes	Sink Cabinet	Wood	Green	Chipping	6	1.5	Positive	None	0	N/A	Prior to Repair	No	no	no				
1	3	314B	Audio Visual Storage Room	yes	W4	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no				
1	3	314B	Audio Visual Storage Room	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no				
1	3	314B	Audio Visual Storage Room	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no				
1	3	314C	Computer Lockdown Storage	yes	W1	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no				
1	3	314C	Computer Lockdown Storage	yes	W2	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no				
1	3	314C	Computer Lockdown Storage	yes	W3	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no				
1	3	314C	Computer Lockdown Storage	yes	W4	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no				
1	3	314C	Computer Lockdown Storage	yes	Ceiling	Concrete	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no				
1	3	314C	Computer Lockdown Storage	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no				
1	2	H217	Hallway from Stairwell near Classroom 210 to Classroom 214	yes	Door Frame	Metal	Brown	Chipping	2	0.1	Negative	None	0	N/A	Prior to Repair	No	no	no				
1	2	H217	Hallway from Stairwell near Classroom 210 to Classroom 214	yes	Doors	Metal	Green	Chipping	2	1.6	Positive	None	0	N/A	Prior to Repair	No	no	no				
1	2	H217	Hallway from Stairwell near Classroom 210 to Classroom 214	yes	Doors	Metal	Orange	Chipping	2	2	Positive	None	0	N/A	Prior to Repair	No	no	no				
1	2	H217	Hallway from Stairwell near Classroom 210 to Classroom 214	yes	Doors	Metal	Blue	Chipping	2	1.4	Negative	None	0	N/A	Prior to Repair	No	no	no				

					School District of Philadelphia																						
					Name of Inspector: Ryan Hutsell		Lead Safe Certification Assessment Report																			Inspection Dates: 05/03-28/21	
					Inspection Company: Synertech, Inc.		Cramp School																			ULCS# 5470	
E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	Lead Concentrati on (% wt)	Lead in Paint Chips by Flame AAS Analysis Results (positive / negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes								
1	2	H217	Hallway from Stairwell near Classroom 210 to Classroom 214	yes	Doors	Metal	Brown	Chipping	2	1.5	Positive	None	0	N/A	Prior to Repair	No	no	no									
1	3	H314	Hallway from Audio Visual Storage Room to Elevator	yes	W1	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no									
1	3	H314	Hallway from Audio Visual Storage Room to Elevator	yes	Door	Wood	Yellow	Chipping	2	1.6	Positive	None	0	N/A	Prior to Repair	No	no	no									
1	3	H314	Hallway from Audio Visual Storage Room to Elevator	yes	W2	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no									
1	3	H314	Hallway from Audio Visual Storage Room to Elevator	yes	W3	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no									
1	3	H314	Hallway from Audio Visual Storage Room to Elevator	yes	Elevator Door Frame	Metal	Blue	Chipping	1	1.5	Positive	None	0	N/A	Prior to Repair	No	no	no									
1	3	H314	Hallway from Audio Visual Storage Room to Elevator	yes	Elevator Door	Metal	Blue	Chipping	1	1.9	Positive	None	0	N/A	Prior to Repair	No	no	no									
1	3	H314	Hallway from Audio Visual Storage Room to Elevator	yes	W4	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no									
1	3	H314	Hallway from Audio Visual Storage Room to Elevator	yes	Ceiling	Concrete	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no									
1	3	H314	Hallway from Audio Visual Storage Room to Elevator	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no									
1	3	314D	Office at Northwest side of Library	yes	W1	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no									
1	3	314D	Office at Northwest side of Library	yes	W2	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no									
1	3	314D	Office at Northwest side of Library	yes	W3	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no									
1	3	314D	Office at Northwest side of Library	yes	W4	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no									
1	3	314D	Office at Northwest side of Library	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no									
1	3	314D	Office at Northwest side of Library	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no									
1	3	H324	Hallway from Library to Stairwell adjacent to Classroom 311	yes	W1	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no									
1	3	H324	Hallway from Library to Stairwell adjacent to Classroom 311	yes	W2	CMU	White	Chipping	12	0	Negative	None	0	N/A	Prior to Repair	No	no	no									
1	3	H324	Hallway from Library to Stairwell adjacent to Classroom 311	yes	W2	Concrete	White	Chipping	12	0.1	Negative	None	0	N/A	Prior to Repair	No	no	no									
1	3	H324	Hallway from Library to Stairwell adjacent to Classroom 311	yes	Door	Metal	Orange	Chipping	6	0.9	Positive	None	0	N/A	Prior to Repair	No	no	no									
1	3	H324	Hallway from Library to Stairwell adjacent to Classroom 311	yes	Door	Metal	Yellow	Chipping	4	1.8	Positive	None	0	N/A	Prior to Repair	No	no	no									
1	3	H324	Hallway from Library to Stairwell adjacent to Classroom 311	yes	Elevator Door Frame	Metal	Blue	Chipping	1	1.8	Positive	None	0	N/A	Prior to Repair	No	no	no									
1	3	H324	Hallway from Library to Stairwell adjacent to Classroom 311	yes	Elevator Door	Metal	Green	Chipping	1	2	Positive	None	0	N/A	Prior to Repair	No	no	no									
1	3	H324	Hallway from Library to Stairwell adjacent to Classroom 311	yes	W3	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no									
1	3	H324	Hallway from Library to Stairwell adjacent to Classroom 311	yes	W4	CMU	White	Chipping	15	0	Negative	None	0	N/A	Prior to Repair	No	no	no									
1	3	H324	Hallway from Library to Stairwell adjacent to Classroom 311	yes	W4	Concrete	White	Chipping	15	0.06	Negative	None	0	N/A	Prior to Repair	No	no	no									
1	3	H324	Hallway from Library to Stairwell adjacent to Classroom 311	yes	Door Frame	Metal	Green	Chipping	4	0	Negative	None	0	N/A	Prior to Repair	No	no	no									
1	3	H324	Hallway from Library to Stairwell adjacent to Classroom 311	yes	Door	Metal	Green	Chipping	4	0	Negative	None	0	N/A	Prior to Repair	No	no	no									
1	3	H324	Hallway from Library to Stairwell adjacent to Classroom 311	yes	Radiator	Metal	Green	Chipping	5	0	Negative	None	0	N/A	Prior to Repair	No	no	no									
1	3	H324	Hallway from Library to Stairwell adjacent to Classroom 311	yes	Ceiling	Concrete	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no									
1	3	H324	Hallway from Library to Stairwell adjacent to Classroom 311	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no									
1	3	314E	Computer Lab 318 adjacent to Library	yes	W1	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no									
1	3	314E	Computer Lab 318 adjacent to Library	yes	Door	Metal	Green	Chipping	1	1.5	Positive	None	0	N/A	Prior to Repair	No	no	no									
1	3	314E	Computer Lab 318 adjacent to Library	yes	W2	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no									
1	3	314E	Computer Lab 318 adjacent to Library	yes	Door	Metal	Red	Chipping	1	2	Positive	None	0	N/A	Prior to Repair	No	no	no									
1	3	314E	Computer Lab 318 adjacent to Library	yes	W3	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no									
1	3	314E	Computer Lab 318 adjacent to Library	yes	W4	Sheetrock	White	Chipping	40	0	Negative	None	0	N/A	Prior to Repair	No	no	no									
1	3	314E	Computer Lab 318 adjacent to Library	yes	Ceiling	Concrete	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no									
1	3	314E	Computer Lab 318 adjacent to Library	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no									
1	3	H323	Hallway from Computer Lab to Stairwell near Classroom 310	yes	W1	Concrete	White	Chipping	2	0	Negative	None	0	N/A	Prior to Repair	No	no	no									
1	3	H323	Hallway from Computer Lab to Stairwell near Classroom 310	yes	W1	Concrete	Green	Chipping	2	0	Negative	None	0	N/A	Prior to Repair	No	no	no									
1	3	H323	Hallway from Computer Lab to Stairwell near Classroom 310	yes	Door Frame	Metal	Green	Chipping	4	0.12	Negative	None	0	N/A	Prior to Repair	No	no	no									
1	3	H323	Hallway from Computer Lab to Stairwell near Classroom 310	yes	Door	Metal	Green	Chipping	4	1.5	Positive	None	0	N/A	Prior to Repair	No	no	no									
1	3	H323	Hallway from Computer Lab to Stairwell near Classroom 310	yes	W2	Concrete	White	Chipping	2	0	Negative	None	0	N/A	Prior to Repair	No	no	no									

					School District of Philadelphia															
			Name of Inspector: Ryan Hutsell		Lead Safe Certification Assessment Report								Inspection Dates: 05/03-28/21							
			Inspection Company: Synertech, Inc.		Cramp School								ULCS# 5470							
E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	Lead Concentrati on (% wt)	Lead in Paint Chips by Flame AAS Analysis Results (positive / negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes	
1	3	H323	Hallway from Computer Lab to Stairwell near Classroom 310	yes	W2	Concrete	Green	Chipping	2	0	Negative	None	0	N/A	Prior to Repair	No	no	no		
1	3	H323	Hallway from Computer Lab to Stairwell near Classroom 310	yes	Door Frame	Metal	Green	Chipping	4	0.08	Negative	None	0	N/A	Prior to Repair	No	no	no		
1	3	H323	Hallway from Computer Lab to Stairwell near Classroom 310	yes	Door	Metal	Green	Chipping	4	1.9	Positive	None	0	N/A	Prior to Repair	No	no	no		
1	3	H323	Hallway from Computer Lab to Stairwell near Classroom 310	yes	W3	Concrete	White	Chipping	2	0	Negative	None	0	N/A	Prior to Repair	No	no	no		
1	3	H323	Hallway from Computer Lab to Stairwell near Classroom 310	yes	W3	Concrete	Green	Chipping	2	0	Negative	None	0	N/A	Prior to Repair	No	no	no		
1	3	H323	Hallway from Computer Lab to Stairwell near Classroom 310	yes	Door Frame	Metal	Green	Chipping	4	0	Negative	None	0	N/A	Prior to Repair	No	no	no		
1	3	H323	Hallway from Computer Lab to Stairwell near Classroom 310	yes	Door	Metal	Green	Chipping	4	1.2	Positive	None	0	N/A	Prior to Repair	No	no	no		
1	3	H323	Hallway from Computer Lab to Stairwell near Classroom 310	yes	W4	Concrete	White	Chipping	2	0	Negative	None	0	N/A	Prior to Repair	No	no	no		
1	3	H323	Hallway from Computer Lab to Stairwell near Classroom 310	yes	W4	Concrete	Green	Chipping	2	0	Negative	None	0	N/A	Prior to Repair	No	no	no		
1	3	H323	Hallway from Computer Lab to Stairwell near Classroom 310	yes	Ceiling	Concrete	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no		
1	3	H323	Hallway from Computer Lab to Stairwell near Classroom 310	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no		
1	3	H320	Hallway at Classroom 308 to 313A	yes	W1	CMU	White	None	0	0	Negative	None	0	N/A	No	No	no	no		
1	3	H320	Hallway at Classroom 308 to 313A	yes	W1	Concrete	Green	None	5	0.08	Negative	None	0	N/A	Prior to Repair	No	no	no		
1	3	H320	Hallway at Classroom 308 to 313A	yes	W2	CMU	White	None	0	0	Negative	None	0	N/A	No	No	no	no		
1	3	H320	Hallway at Classroom 308 to 313A	yes	W2	Concrete	Green	Chipping	2	0.12	Negative	None	0	N/A	Prior to Repair	No	no	no		
1	3	H320	Hallway at Classroom 308 to 313A	yes	Door Frame	Metal	Brown	Chipping	2	0.17	Negative	None	0	N/A	Prior to Repair	No	no	no		
1	3	H320	Hallway at Classroom 308 to 313A	yes	Door	Metal	Brown	Chipping	2	1.2	Positive	None	0	N/A	Prior to Repair	No	no	no		
1	3	H320	Hallway at Classroom 308 to 313A	yes	W3	CMU	White	None	0	0	Negative	None	0	N/A	No	No	no	no		
1	3	H320	Hallway at Classroom 308 to 313A	yes	W3	Concrete	Green	Chipping	4	0.1	Negative	None	0	N/A	Prior to Repair	No	no	no		
1	3	H320	Hallway at Classroom 308 to 313A	yes	Door Frame	Metal	Brown	Chipping	2	0.12	Negative	None	0	N/A	Prior to Repair	No	no	no		
1	3	H320	Hallway at Classroom 308 to 313A	yes	Doors	Metal	Green	Chipping	4	1.5	Positive	None	0	N/A	Prior to Repair	No	no	no		
1	3	H320	Hallway at Classroom 308 to 313A	yes	Doors	Metal	Brown	Chipping	4	1.6	Positive	None	0	N/A	Prior to Repair	No	no	no		
1	3	H320	Hallway at Classroom 308 to 313A	yes	W4	CMU	White	None	0	0	Negative	None	0	N/A	No	No	no	no		
1	3	H320	Hallway at Classroom 308 to 313A	yes	W4	Concrete	Green	Chipping	2	0	Negative	None	0	N/A	Prior to Repair	No	no	no		
1	3	H320	Hallway at Classroom 308 to 313A	yes	Door Frame	Metal	Brown	Chipping	2	0.16	Negative	None	0	N/A	Prior to Repair	No	no	no		
1	3	H320	Hallway at Classroom 308 to 313A	yes	Doors	Metal	Blue	Chipping	4	1.1	Positive	None	0	N/A	Prior to Repair	No	no	no		
1	3	H320	Hallway at Classroom 308 to 313A	yes	Doors	Metal	Green	Chipping	4	1.4	Positive	None	0	N/A	Prior to Repair	No	no	no		
1	3	H320	Hallway at Classroom 308 to 313A	yes	Ceiling	Concrete	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no		
1	3	H320	Hallway at Classroom 308 to 313A	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no		
1	3	H320B	Hallway at S37 to Classroom 309	yes	W1	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no		
1	3	H320B	Hallway at S37 to Classroom 309	yes	W1	Concrete	Green	Chipping	6	0	Negative	None	0	N/A	Prior to Repair	No	no	no		
1	3	H320B	Hallway at S37 to Classroom 309	yes	Door Frame	Metal	Green	Chipping	2	0.11	Negative	None	0	N/A	Prior to Repair	No	no	no		
1	3	H320B	Hallway at S37 to Classroom 309	yes	Door	Wood	Green	Chipping	2	1.4	Positive	None	0	N/A	Prior to Repair	No	no	no		
1	3	H320B	Hallway at S37 to Classroom 309	yes	W2	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no		
1	3	H320B	Hallway at S37 to Classroom 309	yes	W2	Concrete	Green	Chipping	5	0.1	Negative	None	0	N/A	Prior to Repair	No	no	no		
1	3	H320B	Hallway at S37 to Classroom 309	yes	Door Frame	Metal	Green	Chipping	2	0.18	Negative	None	0	N/A	Prior to Repair	No	no	no		
1	3	H320B	Hallway at S37 to Classroom 309	yes	Door	Wood	Green	Chipping	2	1.2	Positive	None	0	N/A	Prior to Repair	No	no	no		
1	3	H320B	Hallway at S37 to Classroom 309	yes	W3	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no		
1	3	H320B	Hallway at S37 to Classroom 309	yes	W3	Concrete	Green	Chipping	5	0.08	Negative	None	0	N/A	Prior to Repair	No	no	no		
1	3	H320B	Hallway at S37 to Classroom 309	yes	Door Frame	Metal	Green	Chipping	2	0.17	Negative	None	0	N/A	Prior to Repair	No	no	no		
1	3	H320B	Hallway at S37 to Classroom 309	yes	Door	Wood	Green	Chipping	2	1.6	Positive	None	0	N/A	Prior to Repair	No	no	no		
1	3	H320B	Hallway at S37 to Classroom 309	yes	W4	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no		
1	3	H320B	Hallway at S37 to Classroom 309	yes	W4	Concrete	Green	Chipping	6	0	Negative	None	0	N/A	Prior to Repair	No	no	no		
1	3	H320B	Hallway at S37 to Classroom 309	yes	Ceiling	Concrete	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no		
1	3	H320B	Hallway at S37 to Classroom 309	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no		
1	3	S32	Stairwell near Classroom 310	yes	W1	CMU	White	Cracking	10	0	Negative	None	0	N/A	Prior to Repair	No	no	no		
1	3	S32	Stairwell near Classroom 310	yes	Door Frame	Metal	Orange	Chipping	2	0.16	Negative	None	0	N/A	Prior to Repair	No	no	no		
1	3	S32	Stairwell near Classroom 310	yes	Door	Metal	Orange	Chipping	2	0.3	Negative	None	0	N/A	Prior to Repair	No	no	no		
1	3	S32	Stairwell near Classroom 310	yes	W2	CMU	White	Cracking	10	0	Negative	None	0	N/A	Prior to Repair	No	no	no		
1	3	S32	Stairwell near Classroom 310	yes	W3	CMU	White	Cracking	12	0	Negative	None	0	N/A	Prior to Repair	No	no	no		
1	3	S32	Stairwell near Classroom 310	yes	Handrail	Metal	Orange	Friction	2	1.1	Positive	None	0	N/A	Prior to Repair	No	no	no		
1	3	S32	Stairwell near Classroom 310	yes	W4	CMU	White	Cracking	12	0	Negative	None	0	N/A	Prior to Repair	No	no	no		
1	3	S32	Stairwell near Classroom 310	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no		
1	3	S32	Stairwell near Classroom 310	yes	Floor	Concrete	N/A	None	0	N/A	N/A	None	0	N/A	No	No	no	no		
1	3	S32	Stairwell near Classroom 310	yes	Stair Stringer	Metal	Orange	Chipping	12	2.4	Positive	None	0	N/A	Prior to Repair	No	no	no		
1	3	S32	Stairwell near Classroom 310	yes	Stair Risers	Metal	Orange	Chipping	25	2	Positive	None	0	N/A	Prior to Repair	No	no	no		
1	3	S32	Stairwell near Classroom 310	yes	Baseboard	Metal	Orange	Chipping	30	2.5	Positive	None	0	N/A	Prior to Repair	No	no	no		
1	3	S32	Stairwell near Classroom 310	yes	Baluster	Metal	Orange	Chipping	6	1.8	Positive	None	0	N/A	Prior to Repair	No	no	no		
1	3	S31	Stairwell near Classroom 311	yes	W1	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no		

					School District of Philadelphia															
			Name of Inspector: Ryan Hutsell		Lead Safe Certification Assessment Report								Inspection Dates: 05/03-28/21							
			Inspection Company: Synertech, Inc.		Cramp School								ULCS# 5470							
E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	Lead Concentrati on (% wt)	Lead in Paint Chips by Flame AAS Analysis Results (positive / negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes	
1	3	S31	Stairwell near Classroom 311	yes	Doors	Metal	Orange	Chipping	4	0	Negative	None	0	N/A	Prior to Repair	No	no	no		
1	3	S31	Stairwell near Classroom 311	yes	W2	Concrete	White	Flaking	4	0	Negative	None	0	N/A	Prior to Repair	No	no	no		
1	3	S31	Stairwell near Classroom 311	yes	Handrail	Metal	Black	Friction	12	0.2	Negative	None	0	N/A	Prior to Repair	No	no	no		
1	3	S31	Stairwell near Classroom 311	yes	W3	CMU	White	Cracking	12	0	Negative	None	0	N/A	Prior to Repair	No	no	no		
1	3	S31	Stairwell near Classroom 311	yes	Radiator	Metal	Orange	Chipping	2	0.16	Negative	None	0	N/A	Prior to Repair	No	no	no		
1	3	S31	Stairwell near Classroom 311	yes	W4	Concrete	White	Flaking	15	0	Negative	None	0	N/A	Prior to Repair	No	no	no		
1	3	S31	Stairwell near Classroom 311	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	Drop Ceiling	
1	3	S31	Stairwell near Classroom 311	yes	Floor	Concrete	N/A	None	0	N/A	N/A	None	0	N/A	No	No	no	no		
1	3	S31	Stairwell near Classroom 311	yes	Stair Stringer	Metal	Orange	Chipping	12	1.5	Positive	None	0	N/A	Prior to Repair	No	no	no		
1	3	S31	Stairwell near Classroom 311	yes	Stair Risers	Metal	Orange	Chipping	25	2.8	Positive	None	0	N/A	Prior to Repair	No	no	no		
1	3	S31	Stairwell near Classroom 311	yes	Baseboard	Metal	Orange	Chipping	30	2.3	Positive	None	0	N/A	Prior to Repair	No	no	no		
1	3	S31	Stairwell near Classroom 311	yes	Baluster	Metal	Orange	Chipping	6	2.1	Positive	None	0	N/A	Prior to Repair	No	no	no		
1	3	F3	Throughout Third Floor	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no		
1	3	F3	Throughout Third Floor	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no		
1	3	F3	Throughout Third Floor	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no		
1	3	F3	Throughout Third Floor	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no		
1	3	F3	Throughout Third Floor	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no		
1	3	F3	Throughout Third Floor	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no		
1	B	001B	Main Mechanical Room	no	W1	Concrete	White	Flaking	30	0	Negative	Floor	100	N/A	Prior to Repair	No	no	no		
1	B	001B	Main Mechanical Room	no	Door Frame	Metal	Brown	Chipping	2	0	Negative	None	0	N/A	Prior to Repair	No	no	no		
1	B	001B	Main Mechanical Room	no	Door	Metal	Brown	Chipping	2	0	Negative	None	0	N/A	Prior to Repair	No	no	no		
1	B	001B	Main Mechanical Room	no	W2	Concrete	White	Flaking	36	0.12	Negative	Floor	100	N/A	Prior to Repair	No	no	no		
1	B	001B	Main Mechanical Room	no	W3	CMU	White	Chipping	20	0	Negative	Floor	100	N/A	Prior to Repair	No	no	no		
1	B	001B	Main Mechanical Room	no	W4	CMU	White	Chipping	20	0.08	Negative	Floor	100	N/A	Prior to Repair	No	no	no		
1	B	001B	Main Mechanical Room	no	Ceiling	Concrete	White	Chipping	20	0	Negative	Floor	100	N/A	Prior to Repair	No	no	no		
1	B	001B	Main Mechanical Room	no	Duct	Metal	White	Flaking	40	0.15	Negative	None	0	N/A	Prior to Repair	No	no	no		
1	B	001B	Main Mechanical Room	no	Pipes	Metal	White	Chipping	15	0.2	Negative	None	0	N/A	Prior to Repair	No	no	no		
1	B	001B	Main Mechanical Room	no	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	Floor	100	N/A	Prior to Repair	No	no	no		
1	B	001C	Electrical Room	no	W1	CMU	N/A	N/A	N/A	N/A	N/A	None	0	N/A	Prior to Repair	No	no	no	Unpainted	
1	B	001C	Electrical Room	no	Door Frame	Metal	White	Chipping	2	0	Negative	None	0	N/A	Prior to Repair	No	no	no		
1	B	001C	Electrical Room	no	Door	Metal	Blue	Chipping	2	0.2	Negative	None	0	N/A	Prior to Repair	No	no	no		
1	B	001C	Electrical Room	no	W2	CMU	N/A	N/A	N/A	N/A	N/A	None	0	N/A	Prior to Repair	No	no	no	Unpainted	
1	B	001C	Electrical Room	no	W3	CMU	N/A	N/A	N/A	N/A	N/A	None	0	N/A	Prior to Repair	No	no	no	Unpainted	
1	B	001C	Electrical Room	no	Door Frame	Metal	Red	Chipping	2	0.35	Negative	None	0	N/A	Prior to Repair	No	no	no		
1	B	001C	Electrical Room	no	Door	Metal	Red	Chipping	2	0.5	Negative	None	0	N/A	Prior to Repair	No	no	no		
1	B	001C	Electrical Room	no	W4	Concrete	N/A	N/A	N/A	N/A	N/A	None	0	N/A	Prior to Repair	No	no	no		
1	B	001C	Electrical Room	no	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	None	0	N/A	Prior to Repair	No	no	no	Unpainted	
1	B	001C	Electrical Room	no	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	Prior to Repair	No	no	no	Unpainted	
1	B	002B	Storage/Engineer Work Shop	no	W1	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no		
1	B	002B	Storage/Engineer Work Shop	no	W2	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no		
1	B	002B	Storage/Engineer Work Shop	no	W3	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no		
1	B	002B	Storage/Engineer Work Shop	no	W4	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no		
1	B	002B	Storage/Engineer Work Shop	no	Ceiling	Concrete	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no		
1	B	002B	Storage/Engineer Work Shop	no	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	Prior to Repair	No	no	no		
1	B	003B	Building Engineer's Office	no	W1	CMU	White	Chipping	2	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no		
1	B	003B	Building Engineer's Office	no	W2	CMU	White	None	2	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no		
1	B	003B	Building Engineer's Office	no	W3	CMU	White	None	2	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no		
1	B	003B	Building Engineer's Office	no	W4	CMU	White	None	2	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no		
1	B	003B	Building Engineer's Office	no	Ceiling	Concrete	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no		
1	B	003B	Building Engineer's Office	no	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	Prior to Repair	No	no	no		
1	B	004B	Custodial Breakroom	no	W1	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no		
1	B	004B	Custodial Breakroom	no	Door Frame	Metal	White	Chipping	2	0.1	Negative	None	0	N/A	Prior to Repair	No	no	no		
1	B	004B	Custodial Breakroom	no	Door	Metal	Green	Chipping	2	1.5	Positive	None	0	N/A	Prior to Repair	No	no	no		
1	B	004B	Custodial Breakroom	no	W2	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no		
1	B	004B	Custodial Breakroom	no	Door Frame	Metal	White	Chipping	2	0.1	Negative	None	0	N/A	Prior to Repair	No	no	no		
1	B	004B	Custodial Breakroom	no	Door	Metal	Green	Chipping	2	1.4	Positive	None	0	N/A	Prior to Repair	No	no	no		
1	B	004B	Custodial Breakroom	no	W3	Concrete	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no		
1	B	004B	Custodial Breakroom	no	W4	CMU	White	None	0	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no		

			School District of Philadelphia																		
			Lead Safe Certification Assessment Report																		
			Cramp School																		
			Inspection Dates: 05/03-28/21																		
			ULCS# 5470																		
E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	Lead Concentrati on (% wt)	Lead in Paint Chips by Flame AAS Analysis Results (positive / negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes		
1	B	004B	Custodial Breakroom	no	Ceiling	Concrete	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no			
1	B	004B	Custodial Breakroom	no	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	Prior to Repair	No	no	no			
1	B	004D	Custodial Breakroom Closet	no	W1	CMU	White	No Access	N/A	N/A	N/A	None	0	N/A	Prior to Repair	No	no	no			
1	B	004D	Custodial Breakroom Closet	no	W2	CMU	White	No Access	N/A	N/A	N/A	None	0	N/A	Prior to Repair	No	no	no			
1	B	004D	Custodial Breakroom Closet	no	W3	CMU	White	No Access	N/A	N/A	N/A	None	0	N/A	Prior to Repair	No	no	no			
1	B	004D	Custodial Breakroom Closet	no	W4	CMU	White	No Access	N/A	N/A	N/A	None	0	N/A	Prior to Repair	No	no	no			
1	B	004D	Custodial Breakroom Closet	no	Ceiling	Concrete	White	No Access	N/A	N/A	N/A	None	0	N/A	Prior to Repair	No	no	no			
1	B	004D	Custodial Breakroom Closet	no	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	Prior to Repair	No	no	no			
1	B	004C	Custodial Restroom	no	W1	CMU	White	Flaking	4	0	Negative	None	0	N/A	Prior to Repair	No	no	no			
1	B	004C	Custodial Restroom	no	Door Frame	Metal	White	Flaking	2	0.18	Negative	None	0	N/A	Prior to Repair	No	no	no			
1	B	004C	Custodial Restroom	no	W2	CMU	White	Flaking	4	0.14	Negative	None	0	N/A	Prior to Repair	No	no	no			
1	B	004C	Custodial Restroom	no	W3	CMU	White	None	0	0	Negative	None	0	N/A	No	No	no	no			
1	B	004C	Custodial Restroom	no	W4	CMU	White	None	0	0	Negative	None	0	N/A	No	No	no	no			
1	B	004C	Custodial Restroom	no	Ceiling	Plaster	White	Flaking	4	0	Negative	None	0	N/A	Prior to Repair	No	no	no			
1	B	004C	Custodial Restroom	no	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	Prior to Repair	No	no	no			
1	B	005B	Elevator Mechanical Room	no	W1	CMU	White	Chipping	2	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no			
1	B	005B	Elevator Mechanical Room	no	W2	CMU	White	Chipping	2	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no			
1	B	005B	Elevator Mechanical Room	no	W3	CMU	White	Chipping	2	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no			
1	B	005B	Elevator Mechanical Room	no	W4	CMU	White	Chipping	2	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no			
1	B	005B	Elevator Mechanical Room	no	Ceiling	Plaster	White	Chipping	2	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no			
1	B	005B	Elevator Mechanical Room	no	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	None	0	N/A	Prior to Repair	No	no	no			
1	B	NP-1	Incinerator Room	no	W1	CMU	White	Chipping	5	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no			
1	B	NP-1	Incinerator Room	no	Door Frame	Metal	White	Chipping	2	0	Negative	None	0	N/A	Prior to Repair	No	no	no			
1	B	NP-1	Incinerator Room	no	Door	Metal	Blue	Chipping	2	0	Negative	None	0	N/A	Prior to Repair	No	no	no			
1	B	NP-1	Incinerator Room	no	W2	CMU	White	Chipping	5	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no			
1	B	NP-1	Incinerator Room	no	W3	CMU	White	Chipping	5	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no			
1	B	NP-1	Incinerator Room	no	W4	CMU	White	Chipping	5	0	Negative	None	0	N/A	Partially Inaccessible	No	no	no			
1	B	NP-1	Incinerator Room	no	Ceiling	Concrete	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no			
1	B	NP-1	Incinerator Room	no	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	Prior to Repair	No	no	no	Unpainted		
1	B	NP-1	Incinerator Room	no	Incinerator	Metal	Grey	Chipping	10	0	Negative	None	0	N/A	Prior to Repair	No	no	no			
1	B	H01	Hallway from Incinerator Room to Main Mechanical Room	no	W1	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	Prior to Repair	No	no	no	No wall		
1	B	H01	Hallway from Incinerator Room to Main Mechanical Room	no	W2	CMU	White	Chipping	20	0	Negative	None	0	N/A	Prior to Repair	No	no	no			
1	B	H01	Hallway from Incinerator Room to Main Mechanical Room	no	Door Frame	Metal	White	Chipping	2	0.2	Negative	None	0	N/A	Prior to Repair	No	no	no			
1	B	H01	Hallway from Incinerator Room to Main Mechanical Room	no	Doors	Metal	Blue	Chipping	8	1.2	Positive	None	0	N/A	Prior to Repair	No	no	no			
1	B	H01	Hallway from Incinerator Room to Main Mechanical Room	no	Doors	Metal	Green	Chipping	8	1.7	Positive	None	0	N/A	Prior to Repair	No	no	no			
1	B	H01	Hallway from Incinerator Room to Main Mechanical Room	no	W3	CMU	N/A	N/A	0	N/A	N/A	None	0	N/A	No	No	no	no	No wall		
1	B	H01	Hallway from Incinerator Room to Main Mechanical Room	no	W4	CMU	White	Chipping	20	0.04	Negative	None	0	N/A	Prior to Repair	No	no	no			
1	B	H01	Hallway from Incinerator Room to Main Mechanical Room	no	Door Frame	Metal	White	Chipping	2	0.16	Negative	None	0	N/A	Prior to Repair	No	no	no			
1	B	H01	Hallway from Incinerator Room to Main Mechanical Room	no	Doors	Metal	Blue	Chipping	8	1.3	Positive	None	0	N/A	Prior to Repair	No	no	no			
1	B	H01	Hallway from Incinerator Room to Main Mechanical Room	no	Doors	Metal	Green	Chipping	8	1.9	Positive	None	0	N/A	Prior to Repair	No	no	no			
1	B	H01	Hallway from Incinerator Room to Main Mechanical Room	no	Ceiling	Concrete	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no			
1	B	H01	Hallway from Incinerator Room to Main Mechanical Room	no	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	None	0	N/A	Prior to Repair	No	no	no	Unpainted		
1	B	S01	Stairwell adjacent to Main Mechanical Room	no	W1	CMU	White	Chipping	2	0	Negative	None	0	N/A	Prior to Repair	No	no	no			
1	B	S01	Stairwell adjacent to Main Mechanical Room	no	W2	CMU	White	Chipping	4	0	Negative	None	0	N/A	Prior to Repair	No	no	no			
1	B	S01	Stairwell adjacent to Main Mechanical Room	no	W3	Concrete	White	Flaking	4	0	Negative	None	0	N/A	Prior to Repair	No	no	no			
1	B	S01	Stairwell adjacent to Main Mechanical Room	no	W4	CMU	White	Cracking	20	0	Negative	None	0	N/A	Prior to Repair	No	no	no			
1	B	S01	Stairwell adjacent to Main Mechanical Room	no	Ceiling	Concrete	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no			

					School District of Philadelphia															
			Name of Inspector: Ryan Hutsell		Lead Safe Certification Assessment Report							Inspection Dates: 05/03-28/21								
			Inspection Company: Synertech, Inc.		Cramp School							ULCS# 5470								
Element	Floor	Space #																		
			On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	Lead Concentration (% wt)	Lead in Paint Chips by Flame AAS Analysis Results (positive / negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes	
1	B	S01	Stairwell adjacent to Main Mechanical Room	no	Stair Soffit	Metal	Yellow	Flaking	10	3.9	Positive	None	0	N/A	Prior to Repair	No	no	no		
1	B	S01	Stairwell adjacent to Main Mechanical Room	no	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	None	0	N/A	Prior to Repair	No	no	no		
1	B	S02	Stairwell adjacent to Incinerator Room	no	W1	CMU	White	Chipping	4	0	Negative	None	0	N/A	Prior to Repair	No	no	no		
1	B	S02	Stairwell adjacent to Incinerator Room	no	W2	CMU	White	Chipping	4	0	Negative	None	0	N/A	Prior to Repair	No	no	no		
1	B	S02	Stairwell adjacent to Incinerator Room	no	W3	Concrete	White	Flaking	4	0	Negative	None	0	N/A	Prior to Repair	No	no	no		
1	B	S02	Stairwell adjacent to Incinerator Room	no	W4	CMU	White	Cracking	20	0	Negative	None	0	N/A	Prior to Repair	No	no	no		
1	B	S02	Stairwell adjacent to Incinerator Room	no	Ceiling	Concrete	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no		
1	B	S02	Stairwell adjacent to Incinerator Room	no	Stair Soffit	Metal	Yellow	Flaking	10	4.2	Positive	None	0	N/A	Prior to Repair	No	no	no		
1	B	S02	Stairwell adjacent to Incinerator Room	no	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	None	0	N/A	Prior to Repair	No	no	no		
1	B	FB	Throughout Basement Level	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	Prior to Repair	No	no	no		
1	B	FB	Throughout Basement Level	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	Prior to Repair	No	no	no		
1	B	FB	Throughout Basement Level	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	Prior to Repair	No	no	no		
1	B	FB	Throughout Basement Level	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	Prior to Repair	No	no	no		
1	B	FB	Throughout Basement Level	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	Prior to Repair	No	no	no		
1	B	FB	Throughout Basement Level	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	Prior to Repair	No	no	no		
1	B	EL1	Elevator	no	W1	Metal	N/A	N/A	N/A	N/A	N/A	None	0	N/A	Prior to Repair	No	no	no		
1	B	EL1	Elevator	no	W2	Metal	N/A	N/A	N/A	N/A	N/A	None	0	N/A	Prior to Repair	No	no	no		
1	B	EL1	Elevator	no	W3	Metal	N/A	N/A	N/A	N/A	N/A	None	0	N/A	Prior to Repair	No	no	no		
1	B	EL1	Elevator	no	W4	Metal	N/A	N/A	N/A	N/A	N/A	None	0	N/A	Prior to Repair	No	no	no		
1	B	EL1	Elevator	no	Ceiling	Metal	N/A	N/A	N/A	N/A	N/A	None	0	N/A	Prior to Repair	No	no	no		
1	B	EL1	Elevator	no	Floor	Metal	N/A	N/A	N/A	N/A	N/A	None	0	N/A	Prior to Repair	No	no	no		