

					School District of Philadelphia															
			Name of Inspector: Alexis Johnson/ Justine James		Lead Safe Certification Assessment Report							Date: 5/3/21-5/10/21								
			Inspection Company: BATT A		Ethel Allen							ULCS# 4440								
E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes	
1	1	100	Main Office	Yes	W1	Block	Pink/Purple	None	0	N/A	N/A	None	N/A	N/A	N/A	No	N/A	N/A		
1	1	100	Main Office	Yes	W1	Metal	Black	Cracking	1	0.5	Negative	None	N/A	Negative	Yes	No	No	No	Door Frame	
1	1	100	Main Office	Yes	W1	Metal	Black	Cracking	5	0.8	Positive	None	N/A	Negative	Yes	No	No	No	Door	
1	1	100	Main Office	Yes	W2	Block	Pink/Purple	None	0	N/A	N/A	None	N/A	N/A	N/A	No	N/A	N/A		
1	1	100	Main Office	Yes	W3	Block	Pink/Purple	None	0	N/A	N/A	None	N/A	N/A	N/A	No	N/A	N/A		
1	1	100	Main Office	Yes	W4	Block	Pink/Purple	None	0	N/A	N/A	None	N/A	N/A	N/A	No	N/A	N/A		
1	1	100	Main Office	Yes	Ceiling	Drop Ceiling	White	None	0	N/A	N/A	None	N/A	N/A	N/A	No	N/A	N/A		
1	1	100	Main Office	Yes	Floor	12 x 12 Tile	Brown	N/A	0	N/A	N/A	None	N/A	N/A	N/A	No	N/A	N/A		
1	1		School Community Coordinator	Yes	W1	Block	Tan	None	0	N/A	N/A	None	N/A	N/A	N/A	No	N/A	N/A		
1	1		School Community Coordinator	Yes	W1	Metal	Black	Chipping	1	0.3	Negative	None	N/A	Negative	Yes	No	No	No	Door Frame	
1	1		School Community Coordinator	Yes	W2	Block	Tan	None	0	N/A	N/A	None	N/A	N/A	N/A	No	N/A	N/A		
1	1		School Community Coordinator	Yes	W3	Block	Tan	None	0	N/A	N/A	None	N/A	N/A	N/A	No	N/A	N/A		
1	1		School Community Coordinator	Yes	W4	Block	Tan	None	0	N/A	N/A	None	N/A	N/A	N/A	No	N/A	N/A		
1	1		School Community Coordinator	Yes	Ceiling	Drop Ceiling	White	None	0	N/A	N/A	None	N/A	N/A	N/A	No	N/A	N/A		
1	1		School Community Coordinator	Yes	Floor	12 x 12 Tile	Brown	N/A	0	N/A	N/A	None	N/A	N/A	N/A	No	N/A	N/A		
1	1	100IT	Intermediate Distribution Frame-1 Room	Yes	W1	Block	White	None	0	N/A	N/A	None	N/A	N/A	N/A	No	N/A	N/A		
1	1	100IT	Intermediate Distribution Frame-1 Room	yes	W1	Metal	Black	None	0	N/A	N/A	None	N/A	Negative	N/A	No	N/A	N/A	Door Frame	
1	1	100IT	Intermediate Distribution Frame-1 Room	Yes	W2	Block	White	None	0	N/A	N/A	None	N/A	N/A	N/A	No	N/A	N/A		
1	1	100IT	Intermediate Distribution Frame-1 Room	Yes	W3	Block	White	None	0	N/A	N/A	None	N/A	N/A	N/A	No	N/A	N/A		
1	1	100IT	Intermediate Distribution Frame-1 Room	Yes	W4	Block	White	None	0	N/A	N/A	None	N/A	N/A	N/A	No	N/A	N/A		
1	1	100IT	Intermediate Distribution Frame-1 Room	Yes	Ceiling	Concrete	N/A	None	0	N/A	N/A	None	N/A	N/A	N/A	No	N/A	N/A		
1	1	100IT	Intermediate Distribution Frame-1 Room	Yes	Floor	12 x 12 Tile	Brown	N/A	0	N/A	N/A	None	N/A	N/A	N/A	No	N/A	N/A		
1	1	100A	Principal's Office	Yes	W1	Block	Tan	None	0	N/A	N/A	None	N/A	N/A	N/A	No	N/A	N/A		
1	1	100A	Principal's Office	Yes	W1	Metal	Black	Chipping	4	0.5	Negative	None	N/A	Negative	Yes	No	No	No	Door Frame	
1	1	100A	Principal's Office	Yes	W2	Block	Tan	None	0	N/A	N/A	None	N/A	N/A	N/A	No	N/A	N/A		
1	1	100A	Principal's Office	Yes	W3	Block	Tan	None	0	N/A	N/A	None	N/A	N/A	N/A	No	N/A	N/A		
1	1	100A	Principal's Office	Yes	W4	Block	Gray	None	0	N/A	N/A	None	N/A	N/A	N/A	No	N/A	N/A		
1	1	100A	Principal's Office	Yes	W4	Metal	Black	Cracking	3	0.8	Positive	None	N/A	Negative	Yes	No	No	No	Door Frame	
1	1	100A	Principal's Office	Yes	Ceiling	Drop Ceiling	White	None	0	N/A	N/A	None	N/A	N/A	N/A	No	N/A	N/A		
1	1	100A	Principal's Office	Yes	Floor	12 x 12 Tile	Tan	N/A	0	N/A	N/A	None	N/A	N/A	N/A	No	N/A	N/A		
1	1		Principal's Office Bathroom	Yes	W1	Block	Tan	None	0	N/A	N/A	None	N/A	N/A	N/A	No	N/A	N/A		
1	1		Principal's Office Bathroom	Yes	W1	Metal	Black	Cracking	1	0.8	Positive	None	N/A	Negative	Yes	No	No	No	Door Frame	
1	1		Principal's Office Bathroom	Yes	W2	Block	Tan	None	0	N/A	N/A	None	N/A	N/A	N/A	No	N/A	N/A		
1	1		Principal's Office Bathroom	Yes	W3	Block	Tan	None	0	N/A	N/A	None	N/A	N/A	N/A	No	N/A	N/A		
1	1		Principal's Office Bathroom	Yes	W4	Block	Tan	None	0	N/A	N/A	None	N/A	N/A	N/A	No	N/A	N/A		
1	1		Principal's Office Bathroom	Yes	W4	Metal	Black	None	0	N/A	N/A	None	N/A	Negative	N/A	No	N/A	N/A	Door Frame	
1	1		Principal's Office Bathroom	Yes	Ceiling	Concrete	White	None	0	N/A	N/A	None	N/A	N/A	N/A	No	N/A	N/A		
1	1		Principal's Office Bathroom	Yes	Floor	12 x 12 Tile	Tan	N/A	0	N/A	N/A	None	N/A	N/A	N/A	No	N/A	N/A		
1	1	100B	Main Office Conference Room	Yes	W1	Block	Multi	None	0	N/A	N/A	None	N/A	N/A	N/A	No	N/A	N/A		
1	1	100B	Main Office Conference Room	yes	W1	Metal	Black	Cracking	3	0.8	Positive	None	N/A	Negative	Yes	No	No	No	Door Frame	
1	1	100B	Main Office Conference Room	Yes	W2	Block	Multi	None	0	N/A	N/A	None	N/A	N/A	N/A	No	N/A	N/A		
1	1	100B	Main Office Conference Room	Yes	W3	Block	Multi	None	0	N/A	N/A	None	N/A	N/A	N/A	No	N/A	N/A		
1	1	100B	Main Office Conference Room	yes	W1	Metal	Black	None	0	N/A	N/A	None	N/A	Negative	N/A	No	N/A	N/A	Door	
1	1	100B	Main Office Conference Room	yes	W3	Metal	Black	Cracking	3	0.8	Positive	None	N/A	Negative	Yes	No	No	No	Door Frame	
1	1	100B	Main Office Conference Room	Yes	W4	Block	Multi	None	0	N/A	N/A	None	N/A	N/A	N/A	No	N/A	N/A		
1	1	100B	Main Office Conference Room	Yes	Ceiling	Drop Ceiling	White	None	0	N/A	N/A	None	N/A	N/A	N/A	No	N/A	N/A		
1	1	100B	Main Office Conference Room	Yes	Floor	12 x 12 Tile	Brown	N/A	0	N/A	N/A	None	N/A	N/A	N/A	No	N/A	N/A		
1	1		Vice Principal's Office	Yes	W1	Block	Tan	None	0	N/A	N/A	None	N/A	N/A	N/A	No	N/A	N/A		
1	1		Vice Principal's Office	Yes	W1	Metal	Black	Cracking	2	0.4	Negative	None	N/A	Negative	Yes	No	No	No	Door Frame	
1	1		Vice Principal's Office	Yes	W2	Block	Tan	None	0	N/A	N/A	None	N/A	N/A	N/A	No	N/A	N/A		
1	1		Vice Principal's Office	Yes	W3	Block	Tan	None	0	N/A	N/A	None	N/A	N/A	N/A	No	N/A	N/A		
1	1		Vice Principal's Office	Yes	W4	Block	Tan	None	0	N/A	N/A	None	N/A	N/A	N/A	No	N/A	N/A		
1	1		Vice Principal's Office	Yes	Ceiling	Drop Ceiling	White	None	0	N/A	N/A	None	N/A	N/A	N/A	No	N/A	N/A		
1	1		Vice Principal's Office	Yes	Floor	12 x 12 Tile	Brown	N/A	0	N/A	N/A	None	N/A	N/A	N/A	No	N/A	N/A		
1	1	100C	Main Nurse Office - Adjacent to 116C	Yes	W1	Block	Tan	None	0	N/A	N/A	None	N/A	N/A	N/A	No	N/A	N/A		
1	1	100C	Main Nurse Office - Adjacent to 116C	Yes	W1	Metal	Black	Cracking	3	0.1	Negative	None	N/A	Negative	Yes	No	No	No	Door Frame	
1	1	100C	Main Nurse Office - Adjacent to 116C	Yes	W2	Block	Tan	None	0	N/A	N/A	None	N/A	N/A	N/A	No	N/A	N/A		
1	1	100C	Main Nurse Office - Adjacent to 116C	Yes	W3	Block	Tan	None	0	N/A	N/A	None	N/A	N/A	N/A	No	N/A	N/A		
1	1	100C	Main Nurse Office - Adjacent to 116C	Yes	W4	Block	Tan	None	0	N/A	N/A	None	N/A	N/A	N/A	No	N/A	N/A		
1	1	100C	Main Nurse Office - Adjacent to 116C	Yes	Ceiling	Drop Ceiling	White	None	0	N/A	N/A	None	N/A	N/A	N/A	No	N/A	N/A		
1	1	100C	Main Nurse Office - Adjacent to 116C	Yes	Floor	12 x 12 Tile	Tan	N/A	0	N/A	N/A	None	N/A	N/A	N/A	No	N/A	N/A		
1	1	100A	Main Health Suite	Yes	W1	Block	Tan	None	0	N/A	N/A	None	N/A	N/A	N/A	No	N/A	N/A		
1	1	100A	Main Health Suite	Yes	W1	Metal	Black	Cracking	3	0.7	Negative	None	N/A	Negative	Yes	No	No	No	Door Frame	
1	1	100A	Main Health Suite	Yes	W2	Block	Tan	None	0	N/A	N/A	None	N/A	N/A	N/A	No	N/A	N/A		
1	1	100A	Main Health Suite	Yes	W3	Block	Tan	None	0	N/A	N/A	None	N/A	N/A	N/A	No	N/A	N/A		
1	1	100A	Main Health Suite	Yes	W4	Block	Tan	None	0	N/A	N/A	None	N/A	N/A	N/A	No	N/A	N/A		
1	1	100A	Main Health Suite	Yes	W4	Metal	Black	Cracking	1	0.4	Negative	None	N/A	Negative	Yes	No	No	No	Door Frame	
1	1	100A	Main Health Suite	Yes	Ceiling	Concrete	White	None	0	N/A	N/A	None	N/A	N/A	N/A	No	N/A	N/A		
1	1	100A	Main Health Suite	Yes	Floor	12 x 12 Tile	Brown	N/A	0	N/A	N/A	None	N/A	N/A	N/A	No	N/A	N/A		
1	1	100F	Restroom in Main Office Area	Yes	W1	Block	Multi	None	0	N/A	N/A	None	N/A	N/A	N/A	No	N/A	N/A		
1	1	100F	Restroom in Main Office Area	yes	W1	Metal	Black	Cracking	2	0.3	Negative	None	N/A	Negative	Yes	No	No	No	Door Frame	
1	1	100F	Restroom in Main Office Area	Yes	W2	Block	Multi	None	0	N/A	N/A	None	N/A	N/A	N/A	No	N/A	N/A		
1	1	100F	Restroom in Main Office Area	Yes	W3	Block	Multi	None	0	N/A	N/A	None	N/A	N/A	N/A	No	N/A			

			School District of Philadelphia																
			Name of Inspector: Alexis Johnson/ Justine James										Date: 5/3/21-5/10/21						
			Inspection Company: BATTA										Ethel Allen						
													ULCS# 4440						
E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes
1	1	100F	Restroom in Main Office Area	Yes	Ceiling	Concrete	White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1	100F	Restroom in Main Office Area	Yes	Floor	Ceramic Tile	Multi	N/A	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1	100H	Nurse Storage Room - Conference	Yes	W1	Block	Tan	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1	100H	Nurse Storage Room - Conference	Yes	W1	Metal	Black	Cracking	3	0.6	Negative	None	N/A	Negative	Yes	No	No	No	Door Frame
1	1	100H	Nurse Storage Room - Conference	Yes	W2	Block	Tan	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1	100H	Nurse Storage Room - Conference	Yes	W3	Block	Tan	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1	100H	Nurse Storage Room - Conference	Yes	W4	Block	Tan	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1	100H	Nurse Storage Room - Conference	Yes	W4	Metal	Black	Cracking	1	0.4	Negative	None	N/A	Negative	Yes	No	No	No	Door Frame
1	1	100H	Nurse Storage Room - Conference	Yes	Ceiling	Drop Ceiling	White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1	100H	Nurse Storage Room - Conference	Yes	Floor	12 x 12 Tile	Brown	N/A	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1	100I	Women's Restroom in Nurse Suite	Yes	W1	Block	Tan	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1	100I	Women's Restroom in Nurse Suite	Yes	W1	Metal	Black	Cracking	3	0.2	Negative	None	N/A	Negative	Yes	No	No	No	Door Frame
1	1	100I	Women's Restroom in Nurse Suite	Yes	W2	Block	Tan	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1	100I	Women's Restroom in Nurse Suite	Yes	W3	Block	Tan	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1	100I	Women's Restroom in Nurse Suite	Yes	W4	Block	Tan	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1	100I	Women's Restroom in Nurse Suite	Yes	Ceiling	Concrete	White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1	100I	Women's Restroom in Nurse Suite	Yes	Floor	Ceramic Tile	Multi	N/A	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1	101A	Classroom 101	Yes	W1	Block	Tan/White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1	101A	Classroom 101	Yes	W1	Metal	Black	None	0	N/A	N/A	None	N/A	Negative	N/A	No	N/A	N/A	Door Frame
1	1	101A	Classroom 101	Yes	W2	Block	Gray	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1	101A	Classroom 101	Yes	W3	Block	Tan/White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1	101A	Classroom 101	Yes	W3	Metal	Tan	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	Univent
1	1	101A	Classroom 101	Yes	W4	Block	Tan/White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1	101A	Classroom 101	Yes	Ceiling	Concrete	White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1	101A	Classroom 101	Yes	Floor	12 x 12 Tile	Multi	N/A	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1	101B	Classroom 102	Yes	W1	Block	Gray	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1	101B	Classroom 102	Yes	W1	Metal	Gray	None	0	N/A	N/A	None	N/A	Negative	N/A	No	N/A	N/A	Door Frame
1	1	101B	Classroom 102	Yes	W2	Block	Gray	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1	101B	Classroom 102	Yes	W3	Block	Gray	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1	101B	Classroom 102	Yes	W3	Metal	Tan	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	Univent
1	1	101B	Classroom 102	Yes	W4	Block	Orange	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1	101B	Classroom 102	Yes	Ceiling	Concrete	White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1	101B	Classroom 102	Yes	Floor	12 x 12 Tile	Multi	N/A	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1	101C	Classroom 102 and 103 Closet	Yes	W1	Block	White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1	101C	Classroom 102 and 103 Closet	Yes	W1	Metal	Gray	None	0	N/A	N/A	None	N/A	Negative	N/A	No	N/A	N/A	Door Frame
1	1	101C	Classroom 102 and 103 Closet	Yes	W2	Block	White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1	101C	Classroom 102 and 103 Closet	Yes	W3	Block	White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1	101C	Classroom 102 and 103 Closet	yes	W3	Metal	Gray	None	0	N/A	N/A	None	N/A	Negative	N/A	No	N/A	N/A	Door Frame
1	1	101C	Classroom 102 and 103 Closet	Yes	W4	Block	White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1	101C	Classroom 102 and 103 Closet	Yes	Ceiling	Drop Ceiling	White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1	101C	Classroom 102 and 103 Closet	Yes	Floor	12 x 12 Tile	Gray	N/A	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1	101D	Men's Restroom next to Classroom 101	Yes	W1	Block	White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1	101D	Men's Restroom next to Classroom 101	Yes	W1	Metal	Black	Chipping	3	0.9	Positive	None	N/A	Negative	Yes	No	No	No	Door Frame
1	1	101D	Men's Restroom next to Classroom 101	Yes	W2	Block	White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1	101D	Men's Restroom next to Classroom 101	Yes	W3	Block	White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1	101D	Men's Restroom next to Classroom 101	Yes	W4	Block	White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1	101D	Men's Restroom next to Classroom 101	Yes	Ceiling	Plaster	White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1	101D	Men's Restroom next to Classroom 101	Yes	Floor	Ceramic Tile	Multi	N/A	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1	101E	Women's Restroom next to Classroom 101	Yes	W1	Block	White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1	101E	Women's Restroom next to Classroom 101	Yes	W1	Metal	Black	Chipping	3	0.8	Positive	None	N/A	Negative	Yes	No	No	No	Door Frame
1	1	101E	Women's Restroom next to Classroom 101	Yes	W2	Block	White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1	101E	Women's Restroom next to Classroom 101	Yes	W3	Block	White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1	101E	Women's Restroom next to Classroom 101	Yes	W4	Block	White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1	101E	Women's Restroom next to Classroom 101	Yes	Ceiling	Plaster	White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1	101E	Women's Restroom next to Classroom 101	Yes	Floor	Ceramic Tile	Multi	N/A	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1	102A	Classroom 103	Yes	W1	Block	Gray	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1	102A	Classroom 103	Yes	W1	Metal	Gray	None	0	N/A	N/A	None	N/A	Negative	N/A	No	N/A	N/A	Door Frame
1	1	102A	Classroom 103	Yes	W2	Block	Gray	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1	102A	Classroom 103	Yes	W3	Block	Orange	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1	102A	Classroom 103	Yes	W3	Metal	Tan	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	Univent
1	1	102A	Classroom 103	Yes	W4	Block	Gray	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1	102A	Classroom 103	Yes	Ceiling	Concrete	White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1	102A	Classroom 103	Yes	Floor	12 x 12 Tile	Multi	N/A	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1	102B	Classroom 104	Yes	W1	Block	Gray	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1	102B	Classroom 104	Yes	W1	Metal	Gray	None	0	N/A	N/A	None	N/A	Negative	N/A	No	N/A	N/A	Door Frame
1	1	102B	Classroom 104	Yes	W2	Block	Gray	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1	102B	Classroom 104	Yes	W3	Block	Gray	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1	102B	Classroom 104	Yes	W3	Metal	Tan	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	Univent
1	1	102B	Classroom 104	Yes	W4	Block	Orange	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1	102B	Classroom 104	Yes	Ceiling	Concrete	White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1	102B	Classroom 104	Yes	Floor	12 x 12 Tile	Multi	N/A	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1	102C	Classroom 105	Yes	W1	Block	Gray	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1	102C	Classroom 105	Yes	W1	Metal	Gray	Cracking	2	0.6	Negative	None	N/A	Negative	Yes	No	No	No	Door Frame
1	1	102C	Classroom 105	Yes	W2	Block	Orange	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	

					School District of Philadelphia															
			Name of Inspector: Alexis Johnson/ Justine James		Lead Safe Certification Assessment Report							Date: 5/3/21-5/10/21								
			Inspection Company: BATT A		Ethel Allen							ULCS# 4440								
E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes	
1	1	102C	Classroom 105	Yes	W3	Block	Gray	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A		
1	1	102C	Classroom 105	Yes	W3	Metal	Gray	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	Univent	
1	1	102C	Classroom 105	Yes	W4	Block	Gray	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A		
1	1	102C	Classroom 105	Yes	Ceiling	Concrete	White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A		
1	1	102C	Classroom 105	Yes	Floor	12 x 12 Tile	Multi	N/A	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A		
1	1	102D	Classroom 106	Yes	W1	Block	Gray	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A		
1	1	102D	Classroom 106	Yes	W1	Metal	Gray	None	0	N/A	N/A	None	N/A	Negative	N/A	No	N/A	N/A	Door Frame	
1	1	102D	Classroom 106	Yes	W2	Block	Gray	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A		
1	1	102D	Classroom 106	Yes	W3	Block	Gray	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A		
1	1	102D	Classroom 106	Yes	W3	Metal	Gray	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	Univent	
1	1	102D	Classroom 106	Yes	W4	Block	Orange	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A		
1	1	102D	Classroom 106	Yes	Ceiling	Concrete	White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A		
1	1	102D	Classroom 106	Yes	Floor	12 x 12 Tile	Multi	N/A	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A		
1	1	102E	Boy's Restroom	Yes	W1	Block	Tan	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A		
1	1	102E	Boy's Restroom	Yes	W1	Metal	Black	Cracking	1	0.4	Negative	None	N/A	Negative	Yes	No	No	No	Door Frame	
1	1	102E	Boy's Restroom	Yes	W2	Block	Tan	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A		
1	1	102E	Boy's Restroom	Yes	W3	Block	Tan	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A		
1	1	102E	Boy's Restroom	Yes	W4	Block	Tan	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A		
1	1	102E	Boy's Restroom	Yes	Ceiling	Concrete	White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A		
1	1	102E	Boy's Restroom	Yes	Floor	Ceramic Tile	Multi	N/A	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A		
1	1	102F	Girl's Restroom	Yes	W1	Block	Tan	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A		
1	1	102F	Girl's Restroom	Yes	W1	Metal	Black	Cracking	5	0.8	Positive	None	N/A	Negative	Yes	No	No	No	Door Frame	
1	1	102F	Girl's Restroom	Yes	W2	Block	Tan	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A		
1	1	102F	Girl's Restroom	Yes	W3	Block	Tan	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A		
1	1	102F	Girl's Restroom	Yes	W4	Block	Tan	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A		
1	1	102F	Girl's Restroom	Yes	Ceiling	Concrete	White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A		
1	1	102F	Girl's Restroom	Yes	Floor	Ceramic Tile	Multi	N/A	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A		
1	1	103	IMC	Yes	W1	Block	White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A		
1	1	103	IMC	Yes	W1	Metal	Black	None	0	N/A	N/A	None	N/A	Negative	N/A	No	N/A	N/A	(2) Door Frame	
1	1	103	IMC	Yes	W2	Block	White	Flaking	5	-0.1	Negative	None	N/A	Negative	Yes	No	No	No		
1	1	103	IMC	Yes	W3	Block	White	Flaking	10	0.1	Negative	None	N/A	Negative	Yes	No	No	No		
1	1	103	IMC	Yes	W3	Metal	Black	None	0	N/A	N/A	None	N/A	Negative	N/A	No	N/A	N/A	Door Frame	
1	1	103	IMC	Yes	W3	Metal	Tan	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	Univent	
1	1	103	IMC	Yes	W4	Block	White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A		
1	1	103	IMC	Yes	Ceiling	Concrete	White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A		
1	1	103	IMC	Yes	Floor	12 x 12 Tile	Brown	N/A	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A		
1	1	103C	School Safety	Yes	W1	Block	White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A		
1	1	103C	School Safety	Yes	W1	Metal	Brown	None	0	N/A	N/A	None	N/A	Negative	N/A	No	N/A	N/A	Door Frame	
1	1	103C	School Safety	Yes	W2	Block	White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A		
1	1	103C	School Safety	Yes	W3	Block	White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A		
1	1	103C	School Safety	Yes	W4	Block	White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A		
1	1	103C	School Safety	Yes	Ceiling	Concrete	N/A	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A		
1	1	103C	School Safety	Yes	Floor	12 x 12 Tile	Brown	N/A	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A		
1	1	103D	Libarian Storage	Yes	W1	Block	White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A		
1	1	103D	Libarian Storage	Yes	W1	Metal	Brown	None	0	N/A	N/A	None	N/A	Negative	N/A	No	N/A	N/A	Door Frame	
1	1	103D	Libarian Storage	Yes	W2	Block	White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A		
1	1	103D	Libarian Storage	Yes	W3	Block	White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A		
1	1	103D	Libarian Storage	Yes	W4	Block	White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A		
1	1	103D	Libarian Storage	Yes	W4	Metal	Brown	None	0	N/A	N/A	None	N/A	Negative	N/A	No	N/A	N/A	Door Frame	
1	1	103D	Libarian Storage	Yes	Ceiling	Concrete	N/A	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A		
1	1	103D	Libarian Storage	Yes	Floor	12 x 12 Tile	Brown	N/A	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A		
1	1	103F	Office accross from Librarian Storage - Teacher's Lounge	Yes	W1	Block	White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A		
1	1	103F	Office accross from Librarian Storage - Teacher's Lounge	Yes	W2	Block	White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A		
1	1	103F	Office accross from Librarian Storage - Teacher's Lounge	Yes	W3	Block	White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A		
1	1	103F	Office accross from Librarian Storage - Teacher's Lounge	Yes	W4	Block	White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A		
1	1	103F	Office accross from Librarian Storage - Teacher's Lounge	Yes	Ceiling	Concrete	White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A		
1	1	103F	Office accross from Librarian Storage - Teacher's Lounge	Yes	Floor	12 x 12 Tile	Brown	N/A	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A		
1	1	103G	Book Study Area to Right of IMC	Yes	W1	Block	White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A		
1	1	103G	Book Study Area to Right of IMC	Yes	W2	Block	White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A		
1	1	103G	Book Study Area to Right of IMC	Yes	W3	Block	White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A		
1	1	103G	Book Study Area to Right of IMC	Yes	W3	Block	White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	Univent	
1	1	103G	Book Study Area to Right of IMC	Yes	W4	Block	White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A		
1	1	103G	Book Study Area to Right of IMC	Yes	Ceiling	Concrete	White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A		
1	1	103G	Book Study Area to Right of IMC	Yes	Floor	12 x 12 Tile	Brown	N/A	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A		
1	1	104	Classroom 107	Yes	W1	Block	Blue	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A		
1	1	104	Classroom 107	Yes	W1	Metal	Black	Chipping	3	0.2	Negative	None	N/A	Negative	Yes	No	No	No	Door Frame	
1	1	104	Classroom 107	Yes	W2	Block	Gray	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A		
1	1	104	Classroom 107	Yes	W3	Block	Gray	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A		
1	1	104	Classroom 107	Yes	W4	Block	Gray	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A		

Element Floor Space #			School District of Philadelphia																
			Name of Inspector: Alexis Johnson/ Justine James										Lead Safe Certification Assessment Report						
			Inspection Company: BATT										Date: 5/3/21-5/10/21						
			Ethel Allen										ULCS# 4440						
			On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes
1	1	104	Classroom 107	Yes	Ceiling	Concrete	Gray	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1	104	Classroom 107	Yes	Floor	12 x 12 Tile	Multi	N/A	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1	104A	Classroom 107 Restroom	Yes	W1	Block	Gray	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1	104A	Classroom 107 Restroom	Yes	W1	Metal	Gray	None	0	N/A	N/A	None	N/A	Negative	N/A	No	N/A	N/A	Door Frame
1	1	104A	Classroom 107 Restroom	Yes	W2	Block	Gray	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1	104A	Classroom 107 Restroom	Yes	W3	Block	Gray	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1	104A	Classroom 107 Restroom	Yes	W4	Block	Gray	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1	104A	Classroom 107 Restroom	Yes	Ceiling	Plaster	Gray	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1	104A	Classroom 107 Restroom	Yes	Floor	Ceramic Tile	Multi	N/A	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1	104B	Classroom 107 Storage Closet	Yes	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	N/A	N/A	Inaccessible [BATTAAJ 5.07.21]
1	1	104B	Classroom 107 Storage Closet	Yes	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	N/A	N/A	Inaccessible [BATTAAJ 5.07.21]
1	1	104B	Classroom 107 Storage Closet	Yes	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	N/A	N/A	Inaccessible [BATTAAJ 5.07.21]
1	1	104B	Classroom 107 Storage Closet	Yes	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	N/A	N/A	Inaccessible [BATTAAJ 5.07.21]
1	1	104B	Classroom 107 Storage Closet	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	N/A	N/A	Inaccessible [BATTAAJ 5.07.21]
1	1	104B	Classroom 107 Storage Closet	Yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	N/A	N/A	Inaccessible [BATTAAJ 5.07.21]
1	1	105	Classroom 108	Yes	W1	Block	Gray	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	Inaccessible [BATTAAJ 5.07.21]
1	1	105	Classroom 108	Yes	W2	Block	Gray	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1	105	Classroom 108	Yes	W3	Block	Gray	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1	105	Classroom 108	Yes	W4	Block	Blue	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1	105	Classroom 108	Yes	Ceiling	Concrete	White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1	105	Classroom 108	Yes	Floor	12 x 12 Tile	Multi	N/A	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1	105A	Classroom 108 Restroom	Yes	W1	Block	Gray	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1	105A	Classroom 108 Restroom	Yes	W1	Metal	Gray	None	0	N/A	N/A	None	N/A	Negative	N/A	No	N/A	N/A	Door Frame
1	1	105A	Classroom 108 Restroom	Yes	W2	Block	Gray	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1	105A	Classroom 108 Restroom	Yes	W3	Block	Gray	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1	105A	Classroom 108 Restroom	Yes	W4	Block	Gray	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1	105A	Classroom 108 Restroom	Yes	Ceiling	Plaster	Gray	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1	105A	Classroom 108 Restroom	Yes	Floor	Ceramic Tile	Multi	N/A	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1	105B	Classroom 108 Storage Closet	Yes	W1	Block	White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1	105B	Classroom 108 Storage Closet	yes	W1	Metal	Grey	None	0	N/A	N/A	None	N/A	Negative	N/A	No	N/A	N/A	Door Frame
1	1	105B	Classroom 108 Storage Closet	Yes	W2	Block	White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1	105B	Classroom 108 Storage Closet	Yes	W3	Block	White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1	105B	Classroom 108 Storage Closet	Yes	W4	Block	White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1	105B	Classroom 108 Storage Closet	Yes	Ceiling	Concrete	White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1	105B	Classroom 108 Storage Closet	Yes	Floor	12 x 12 Tile	Gray	N/A	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1		Classroom 108 Storage Closet in Rear	Yes	W1	Block	White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1		Classroom 108 Storage Closet in Rear	Yes	W1	Metal	Grey	None	0	N/A	N/A	None	N/A	Negative	N/A	No	N/A	N/A	Door Frame
1	1		Classroom 108 Storage Closet in Rear	Yes	W2	Block	White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1		Classroom 108 Storage Closet in Rear	Yes	W3	Block	White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1		Classroom 108 Storage Closet in Rear	Yes	W4	Block	White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1		Classroom 108 Storage Closet in Rear	Yes	Ceiling	Concrete	White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1		Classroom 108 Storage Closet in Rear	Yes	Floor	12 x 12 Tile	Gray	N/A	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1	106	Classroom 109	Yes	W1	Block	Gray	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1	106	Classroom 109	Yes	W1	Metal	Gray	None	0	N/A	N/A	None	N/A	Negative	N/A	No	N/A	N/A	Door Frame
1	1	106	Classroom 109	Yes	W2	Block	Blue	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1	106	Classroom 109	Yes	W3	Block	Gray	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1	106	Classroom 109	Yes	W3	Metal	Gray	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	Univent
1	1	106	Classroom 109	Yes	W3	Metal	Gray	None	0	N/A	N/A	None	N/A	Negative	N/A	No	N/A	N/A	Door Frame
1	1	106	Classroom 109	Yes	W3	Metal	Gray	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	Univent
1	1	106	Classroom 109	Yes	W4	Block	Grey	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1	106	Classroom 109	Yes	Ceiling	Concrete	White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1	106	Classroom 109	Yes	Floor	12 x 12 Tile	Multi	N/A	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1	106A	Classroom 109 Restroom	Yes	W1	Block	Grey	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1	106A	Classroom 109 Restroom	Yes	W1	Metal	Grey	None	0	N/A	N/A	None	N/A	Negative	N/A	No	N/A	N/A	Door Frame
1	1	106A	Classroom 109 Restroom	Yes	W2	Block	Grey	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1	106A	Classroom 109 Restroom	Yes	W3	Block	Grey	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1	106A	Classroom 109 Restroom	Yes	W4	Block	Grey	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1	106A	Classroom 109 Restroom	Yes	Ceiling	Concrete	Grey	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1	106A	Classroom 109 Restroom	Yes	Floor	Ceramic Tile	Grey	N/A	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1	106B	Classroom 109 Storage Closet	Yes	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	N/A	N/A	Inaccessible [BATTAAJ 5.07.21]
1	1	106B	Classroom 109 Storage Closet	Yes	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	N/A	N/A	Inaccessible [BATTAAJ 5.07.21]
1	1	106B	Classroom 109 Storage Closet	Yes	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	N/A	N/A	Inaccessible [BATTAAJ 5.07.21]
1	1	106B	Classroom 109 Storage Closet	Yes	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	N/A	N/A	Inaccessible [BATTAAJ 5.07.21]
1	1	106B	Classroom 109 Storage Closet	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	N/A	N/A	Inaccessible [BATTAAJ 5.07.21]
1	1	106B	Classroom 109 Storage Closet	Yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	N/A	N/A	Inaccessible [BATTAAJ 5.07.21]
1	1		Classroom 109 Storage Closet in Rear	Yes	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		N/A	No	N/A	N/A	Inaccessible [BATTAAJ 5.07.21]
1	1		Classroom 109 Storage Closet in Rear	Yes	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		N/A	No	N/A	N/A	Inaccessible [BATTAAJ 5.07.21]
1	1		Classroom 109 Storage Closet in Rear	Yes	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		N/A	No	N/A	N/A	Inaccessible [BATTAAJ 5.07.21]
1	1		Classroom 109 Storage Closet in Rear	Yes	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		N/A	No	N/A	N/A	Inaccessible [BATTAAJ 5.07.21]
1	1		Classroom 109 Storage Closet in Rear	Yes	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		N/A	No	N/A	N/A	Inaccessible [BATTAAJ 5.07.21]
1	1		Classroom 109 Storage Closet in Rear	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		N/A	No	N/A	N/A	Inaccessible [BATTAAJ 5.07.21]
1	1		Classroom 109 Storage Closet in Rear	Yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		N/A	No	N/A	N/A	Inaccessible [BATTAAJ 5.07.21]
1	1	107	Classroom 110	Yes	W1	Block	No Access	No Access	No Access	No Access	No Access	No Access	No Access		N/A	No	N/A	N/A	Inaccessible [BATTAAJ 5.07.21]
1	1	107	Classroom 110	Yes	W1	Metal	Gray	Cracking	1	0.4	Negative	None	N/A	Negative	Yes	No	No	No	Door Frame

Element Floor Space #			School District of Philadelphia																
			Name of Inspector: Alexis Johnson/ Justine James										Lead Safe Certification Assessment Report						Date: 5/3/21-5/10/21
			Inspection Company: BATTA										Ethel Allen						ULCS# 4440
			On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes
1	1	107	Classroom 110	Yes	W2	Block	Gray	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1	107	Classroom 110	Yes	W3	Block	Gray	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1	107	Classroom 110	Yes	W3	Metal	Gray	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	Univent
1	1	107	Classroom 110	Yes	W3	Metal	Gray	None	0	N/A	N/A	None	N/A	Negative	N/A	No	N/A	N/A	Door Frame
1	1	107	Classroom 110	Yes	W3	Metal	Gray	None	0	N/A	N/A	None	N/A	Negative	N/A	No	N/A	N/A	Door
1	1	107	Classroom 110	Yes	W4	Block	Blue	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1	107	Classroom 110	Yes	Ceiling	Concrete	White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1	107	Classroom 110	Yes	Floor	12 x 12 Tile	Multi	N/A	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1	107A	Classroom 110 Restroom	Yes	W1	Block	Grey	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1	107A	Classroom 110 Restroom	Yes	W1	Metal	Grey	None	0	N/A	N/A	None	N/A	Negative	N/A	No	N/A	N/A	Door Frame
1	1	107A	Classroom 110 Restroom	Yes	W2	Block	Grey	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1	107A	Classroom 110 Restroom	Yes	W3	Block	Grey	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1	107A	Classroom 110 Restroom	Yes	W4	Block	Grey	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1	107A	Classroom 110 Restroom	Yes	Ceiling	Concrete	Grey	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1	107A	Classroom 110 Restroom	Yes	Floor	Ceramic Tile	Grey	N/A	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	Inaccessible [BATTA AJ 5.07.21]
1	1	107B	Classroom 110 Storage Closet	Yes	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	N/A	N/A	Inaccessible [BATTA AJ 5.07.21]
1	1	107B	Classroom 110 Storage Closet	Yes	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	N/A	N/A	Inaccessible [BATTA AJ 5.07.21]
1	1	107B	Classroom 110 Storage Closet	Yes	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	N/A	N/A	Inaccessible [BATTA AJ 5.07.21]
1	1	107B	Classroom 110 Storage Closet	Yes	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	N/A	N/A	Inaccessible [BATTA AJ 5.07.21]
1	1	107B	Classroom 110 Storage Closet	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	N/A	N/A	Inaccessible [BATTA AJ 5.07.21]
1	1	107B	Classroom 110 Storage Closet	Yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	N/A	N/A	Inaccessible [BATTA AJ 5.07.21]
1	1		Classroom 110 Storage Closet in Rear	Yes	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		N/A	No	N/A	N/A	Inaccessible [BATTA AJ 5.07.21]
1	1		Classroom 110 Storage Closet in Rear	Yes	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		N/A	No	N/A	N/A	Inaccessible [BATTA AJ 5.07.21]
1	1		Classroom 110 Storage Closet in Rear	Yes	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		N/A	No	N/A	N/A	Inaccessible [BATTA AJ 5.07.21]
1	1		Classroom 110 Storage Closet in Rear	Yes	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		N/A	No	N/A	N/A	Inaccessible [BATTA AJ 5.07.21]
1	1		Classroom 110 Storage Closet in Rear	Yes	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		N/A	No	N/A	N/A	Inaccessible [BATTA AJ 5.07.21]
1	1		Classroom 110 Storage Closet in Rear	Yes	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		N/A	No	N/A	N/A	Inaccessible [BATTA AJ 5.07.21]
1	1		Classroom 110 Storage Closet in Rear	Yes	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		N/A	No	N/A	N/A	Inaccessible [BATTA AJ 5.07.21]
1	1	108	Main Distribution Frame Room and Storage (across from Classroom 109)	Yes	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	N/A	N/A	Inaccessible [BATTA AJ 5.07.21]
1	1	108	Main Distribution Frame Room and Storage (across from Classroom 109)	Yes	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	N/A	N/A	Inaccessible [BATTA AJ 5.07.21]
1	1	108	Main Distribution Frame Room and Storage (across from Classroom 109)	Yes	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	N/A	N/A	Inaccessible [BATTA AJ 5.07.21]
1	1	108	Main Distribution Frame Room and Storage (across from Classroom 109)	Yes	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	N/A	N/A	Inaccessible [BATTA AJ 5.07.21]
1	1	108	Main Distribution Frame Room and Storage (across from Classroom 109)	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	N/A	N/A	Inaccessible [BATTA AJ 5.07.21]
1	1	108	Main Distribution Frame Room and Storage (across from Classroom 109)	Yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		N/A	No	N/A	N/A	Inaccessible [BATTA AJ 5.07.21]
1	1	109	Classroom 111	Yes	W1	Block	Gray	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1	109	Classroom 111	Yes	W1	Metal	Gray	Chipping	1	0.2	Negative	None	N/A	Negative	Yes	No	No	No	Door Frame
1	1	109	Classroom 111	Yes	W2	Block	Blue	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1	109	Classroom 111	Yes	W3	Block	Gray	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1	109	Classroom 111	Yes	W3	Metal	Gray	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	Univent
1	1	109	Classroom 111	Yes	W4	Block	Gray	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1	109	Classroom 111	Yes	Ceiling	Concrete	White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1	109	Classroom 111	Yes	Floor	12 x 12 Tile	Multi	N/A	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1	109A	Classroom 111 Restroom	Yes	W1	Block	White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1	109A	Classroom 111 Restroom	Yes	W1	Metal	Grey	None	0	N/A	N/A	None	N/A	Negative	N/A	No	N/A	N/A	Door Frame
1	1	109A	Classroom 111 Restroom	Yes	W2	Block	White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1	109A	Classroom 111 Restroom	Yes	W3	Block	White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1	109A	Classroom 111 Restroom	Yes	W4	Block	White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1	109A	Classroom 111 Restroom	Yes	Ceiling	Plaster	White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1	109A	Classroom 111 Restroom	Yes	Floor	Ceramic Tile	Multi	N/A	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1	109B	Classroom 111 Storage Closet	Yes	W1	Block	White	No Access	No Access	No Access	No Access	No Access	No Access		N/A	No	N/A	N/A	Inaccessible [BATTA AJ 5.07.21]
1	1	109B	Classroom 111 Storage Closet	Yes	W1	Metal	Gray	No Access	No Access	No Access	No Access	No Access	No Access		N/A	No	N/A	N/A	Inaccessible [BATTA AJ 5.07.21]
1	1	109B	Classroom 111 Storage Closet	Yes	W2	Block	White	No Access	No Access	No Access	No Access	No Access	No Access		N/A	No	N/A	N/A	Inaccessible [BATTA AJ 5.07.21]
1	1	109B	Classroom 111 Storage Closet	Yes	W3	Block	White	No Access	No Access	No Access	No Access	No Access	No Access		N/A	No	N/A	N/A	Inaccessible [BATTA AJ 5.07.21]
1	1	109B	Classroom 111 Storage Closet	Yes	W4	Block	White	No Access	No Access	No Access	No Access	No Access	No Access		N/A	No	N/A	N/A	Inaccessible [BATTA AJ 5.07.21]
1	1	109B	Classroom 111 Storage Closet	Yes	Ceiling	Drop Ceiling	White	No Access	No Access	No Access	No Access	No Access	No Access		N/A	No	N/A	N/A	Inaccessible [BATTA AJ 5.07.21]
1	1	109B	Classroom 111 Storage Closet	Yes	Floor	12 x 12 Tile	Gray	No Access	No Access	No Access	No Access	No Access	No Access		N/A	No	N/A	N/A	Inaccessible [BATTA AJ 5.07.21]
1	1	110	Computer Power Room	No	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	N/A	N/A	Inaccessible [BATTA AJ 5.07.21]
1	1	110	Computer Power Room	No	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	N/A	N/A	Inaccessible [BATTA AJ 5.07.21]
1	1	110	Computer Power Room	No	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	N/A	N/A	Inaccessible [BATTA AJ 5.07.21]
1	1	110	Computer Power Room	No	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	N/A	N/A	Inaccessible [BATTA AJ 5.07.21]
1	1	110	Computer Power Room	No	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	N/A	N/A	Inaccessible [BATTA AJ 5.07.21]
1	1	110	Computer Power Room	No	Floor	N/A	N/A	N/A	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1	111	Storage Room to Left of Classroom 111	Yes	W1	Block	N/A	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1	111	Storage Room to Left of Classroom 111	Yes	W1	Metal	Black	None	0	N/A	N/A	None	N/A	Negative	N/A	No	N/A	N/A	Door Frame
1	1	111	Storage Room to Left of Classroom 112	Yes	W2	Block	N/A	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1	111	Storage Room to Left of Classroom 113	Yes	W3	Block	N/A	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1	111	Storage Room to Left of Classroom 114	Yes	W4	Block	N/A	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1	111	Storage Room to Left of Classroom 115	Yes	Ceiling	Concrete	N/A	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1	111	Storage Room to Left of Classroom 116	Yes	Floor	Concrete	N/A	N/A	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	

Element Floor Space #			School District of Philadelphia																
			Name of Inspector: Alexis Johnson/ Justine James										Lead Safe Certification Assessment Report						
			Inspection Company: BATT A										Date: 5/3/21-5/10/21						
			Ethel Allen										ULCS# 4440						
			On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes
1	1	111A	Gym Teacher's Office	Yes	W1	Block	Tan	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1	111A	Gym Teacher's Office	Yes	W1	Metal	Brown	Cracking	4	0.8	Positive	None	N/A	Negative	Yes	No	No	No	Door Frame
1	1	111A	Gym Teacher's Office	Yes	W2	Block	Tan	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1	111A	Gym Teacher's Office	Yes	W3	Block	Tan	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1	111A	Gym Teacher's Office	Yes	W4	Block	Tan	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1	111A	Gym Teacher's Office	Yes	W4	Metal	Brown	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	Univent
1	1	111A	Gym Teacher's Office	Yes	Ceiling	Concrete	White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1	111A	Gym Teacher's Office	Yes	Floor	12 x 12 Tile	Brown	N/A	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1	111B	Coat Room adjacent to Gym Office	Yes	W1	Block	Tan	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1	111B	Coat Room adjacent to Gym Office	Yes	W1	Metal	Brown	Cracking	4	0.8	Positive	None	N/A	Negative	Yes	No	No	No	Door Frame
1	1	111B	Coat Room adjacent to Gym Office	Yes	W2	Block	Tan	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1	111B	Coat Room adjacent to Gym Office	Yes	W3	Block	Tan	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1	111B	Coat Room adjacent to Gym Office	Yes	W4	Block	Tan	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1	111B	Coat Room adjacent to Gym Office	Yes	Ceiling	Concrete	N/A	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1	111B	Coat Room adjacent to Gym Office	Yes	Floor	12 x 12 Tile	Tan	No Access	No Access	No Access	No Access	No Access	No Access		N/A	No	N/A	N/A	Inaccessible [BATT A J 5.07.21]
1	1	111C	Storage Next to Gym Teacher's Office	Yes	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	N/A	N/A	Inaccessible [BATT A J 5.07.21]
1	1	111C	Storage Next to Gym Teacher's Office	Yes	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	N/A	N/A	Inaccessible [BATT A J 5.07.21]
1	1	111C	Storage Next to Gym Teacher's Office	Yes	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	N/A	N/A	Inaccessible [BATT A J 5.07.21]
1	1	111C	Storage Next to Gym Teacher's Office	Yes	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	N/A	N/A	Inaccessible [BATT A J 5.07.21]
1	1	111C	Storage Next to Gym Teacher's Office	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	N/A	N/A	Inaccessible [BATT A J 5.07.21]
1	1	111C	Storage Next to Gym Teacher's Office	Yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	N/A	N/A	Not Accessible [BATT A 05.10.21]
1	1	111D	Storage Room E and D to left of Girl's Room	Yes	W1	Block	Tan	No Access	No Access	No Access	No Access	No Access	No Access		N/A	No	N/A	N/A	Not Accessible [BATT A 05.10.21]
1	1	111D	Storage Room E and D to left of Girl's Room	Yes	W1	Metal	Brown	No Access	No Access	No Access	No Access	No Access	No Access		N/A	No	N/A	N/A	Not Accessible [BATT A 05.10.21]
1	1	111D	Storage Room E and D to left of Girl's Room	Yes	W2	Block	Tan	No Access	No Access	No Access	No Access	No Access	No Access		N/A	No	N/A	N/A	Not Accessible [BATT A 05.10.21]
1	1	111D	Storage Room E and D to left of Girl's Room	Yes	W3	Block	Tan	No Access	No Access	No Access	No Access	No Access	No Access		N/A	No	N/A	N/A	Not Accessible [BATT A 05.10.21]
1	1	111D	Storage Room E and D to left of Girl's Room	Yes	W4	Block	Tan	No Access	No Access	No Access	No Access	No Access	No Access		N/A	No	N/A	N/A	Not Accessible [BATT A 05.10.21]
1	1	111D	Storage Room E and D to left of Girl's Room	Yes	Ceiling	Plaster	White	No Access	No Access	No Access	No Access	No Access	No Access		N/A	No	N/A	N/A	Not Accessible [BATT A 05.10.21]
1	1	111D	Storage Room E and D to left of Girl's Room	Yes	Floor	Concrete	N/A	No Access	No Access	No Access	No Access	No Access	No Access		N/A	No	N/A	N/A	Not Accessible [BATT A 05.10.21]
1	1	111E	Girl's Restroom	Yes	W1	Block	No Access	No Access	No Access	No Access	No Access	No Access	No Access		N/A	No	N/A	N/A	Not Accessible [BATT A 05.10.21]
1	1	111E	Girl's Restroom	Yes	W1	Metal	No Access	No Access	No Access	No Access	No Access	No Access	No Access		N/A	No	N/A	N/A	Not Accessible [BATT A 05.10.21]
1	1	111E	Girl's Restroom	Yes	W2	Block	No Access	No Access	No Access	No Access	No Access	No Access	No Access		N/A	No	N/A	N/A	Not Accessible [BATT A 05.10.21]
1	1	111E	Girl's Restroom	Yes	W3	Block	No Access	No Access	No Access	No Access	No Access	No Access	No Access		N/A	No	N/A	N/A	Not Accessible [BATT A 05.10.21]
1	1	111E	Girl's Restroom	Yes	W4	Block	No Access	No Access	No Access	No Access	No Access	No Access	No Access		N/A	No	N/A	N/A	Not Accessible [BATT A 05.10.21]
1	1	111E	Girl's Restroom	Yes	Ceiling	Plaster	No Access	No Access	No Access	No Access	No Access	No Access	No Access		N/A	No	N/A	N/A	Not Accessible [BATT A 05.10.21]
1	1	111E	Girl's Restroom	Yes	Floor	Concrete	No Access	No Access	No Access	No Access	No Access	No Access	No Access		N/A	No	N/A	N/A	Not Accessible [BATT A 05.10.21]
1	1	111F	Boy's Restroom in Rear of Gym	Yes	W1	Block	Tan	No Access	No Access	No Access	No Access	No Access	No Access		N/A	No	N/A	N/A	Not Accessible [BATT A 05.10.21]
1	1	111F	Boy's Restroom in Rear of Gym	Yes	W1	Metal	Brown	No Access	No Access	No Access	No Access	No Access	No Access		N/A	No	N/A	N/A	Not Accessible [BATT A 05.10.21]
1	1	111F	Boy's Restroom in Rear of Gym	Yes	W2	Block	Tan	No Access	No Access	No Access	No Access	No Access	No Access		N/A	No	N/A	N/A	Not Accessible [BATT A 05.10.21]
1	1	111F	Boy's Restroom in Rear of Gym	Yes	W3	Block	Tan	No Access	No Access	No Access	No Access	No Access	No Access		N/A	No	N/A	N/A	Not Accessible [BATT A 05.10.21]
1	1	111F	Boy's Restroom in Rear of Gym	Yes	W4	Block	Tan	No Access	No Access	No Access	No Access	No Access	No Access		N/A	No	N/A	N/A	Not Accessible [BATT A 05.10.21]
1	1	111F	Boy's Restroom in Rear of Gym	Yes	Ceiling	Plaster	White	No Access	No Access	No Access	No Access	No Access	No Access		N/A	No	N/A	N/A	Not Accessible [BATT A 05.10.21]
1	1	111F	Boy's Restroom in Rear of Gym	Yes	Floor	Concrete	N/A	No Access	No Access	No Access	No Access	No Access	No Access		N/A	No	N/A	N/A	Not Accessible [BATT A 05.10.21]
1	1		Storage Rooms to the left of Boy's Room	Yes	W1	Block	Tan	No Access	No Access	No Access	No Access	No Access	No Access		N/A	No	N/A	N/A	Not Accessible [BATT A 05.10.21]
1	1		Storage Rooms to the left of Boy's Room	Yes	W1	Metal	Brown	No Access	No Access	No Access	No Access	No Access	No Access		N/A	No	N/A	N/A	Not Accessible [BATT A 05.10.21]
1	1		Storage Rooms to the left of Boy's Room	Yes	W2	Block	Tan	No Access	No Access	No Access	No Access	No Access	No Access		N/A	No	N/A	N/A	Not Accessible [BATT A 05.10.21]
1	1		Storage Rooms to the left of Boy's Room	Yes	W3	Block	Tan	No Access	No Access	No Access	No Access	No Access	No Access		N/A	No	N/A	N/A	Not Accessible [BATT A 05.10.21]
1	1		Storage Rooms to the left of Boy's Room	Yes	W4	Block	Tan	No Access	No Access	No Access	No Access	No Access	No Access		N/A	No	N/A	N/A	Not Accessible [BATT A 05.10.21]
1	1		Storage Rooms to the left of Boy's Room	Yes	Ceiling	Plaster	White	No Access	No Access	No Access	No Access	No Access	No Access		N/A	No	N/A	N/A	Not Accessible [BATT A 05.10.21]
1	1		Storage Rooms to the left of Boy's Room	Yes	Floor	Concrete	N/A	No Access	No Access	No Access	No Access	No Access	No Access		N/A	No	N/A	N/A	Not Accessible [BATT A 05.10.21]
1	1	111G	Gym	Yes	W1	Block	Blue/White	Cracking	6	0.1	Negative	None	N/A	Negative	Yes	No	No	No	
1	1	111G	Gym	Yes	W1	Metal	Brown	None	0	N/A	N/A	None	N/A	Negative	N/A	No	N/A	N/A	Door Frame
1	1	111G	Gym	Yes	W2	Block	Blue/White	Cracking	2	0.1	Negative	None	N/A	Negative	Yes	No	No	No	
1	1	111G	Gym	Yes	W3	Block	Blue/White	Cracking	1	0	Negative	None	N/A	Negative	Yes	No	No	No	
1	1	111G	Gym	Yes	W4	Block	Blue/White	Cracking	3	-0.2	Negative	None	N/A	Negative	Yes	No	No	No	
1	1	111G	Gym	Yes	W4	Metal	Brown	None	0	N/A	N/A	None	N/A	Negative	N/A	No	N/A	N/A	Door Frame
1	1	111G	Gym	Yes	Ceiling	Concrete	N/A	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1	111G	Gym	Yes	Floor	12 x 12 Tile	Blue	N/A	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1	111H	Gym Staff Restroom	Yes	W1	Block	Tan	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1	111H	Gym Staff Restroom	Yes	W1	Metal	Brown	None	0	N/A	N/A	None	N/A	Negative	N/A	No	N/A	N/A	Door Frame
1	1	111H	Gym Staff Restroom	Yes	W2	Block	Tan	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1	111H	Gym Staff Restroom	Yes	W3	Block	Tan	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1	111H	Gym Staff Restroom	Yes	W4	Block	Tan	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1	111H	Gym Staff Restroom	Yes	Ceiling	Concrete	White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1	111H	Gym Staff Restroom	Yes	Floor	Ceramic Tile	White	N/A	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1	112A	Classroom 112	Yes	W1	Block	Tan/White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1	112A	Classroom 112	Yes	W1	Metal	Black	Chipping	9	0.8	Positive	None	N/A	Negative	Yes	No	No	No	Door Frame
1	1	112A	Classroom 112	Yes	W2	Block	Tan/White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1	112A	Classroom 112	Yes	W3	Block	Tan/White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1	112A	Classroom 112	Yes	W3	Metal	Tan	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	Univent
1	1	112A	Classroom 112	Yes	W4	Block	Tan/White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1	112A	Classroom 112	Yes	Ceiling	Concrete	Tan/White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1	112A	Classroom 112	Yes	Floor	12 x 12 Tile	Brown	N/A	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1	112	Classroom 113	Yes	W1	Block	Gray	Cracking	2	-0.1	Negative	None	N/A	Negative	Yes	No	No	No	
1	1	112	Classroom 113	Yes	W1	Metal	Gray	Cracking	2	0.7	Negative	None	N/A	Negative	Yes	No	No	No	Door Frame

					School District of Philadelphia														
			Name of Inspector: Alexis Johnson/ Justine James		Lead Safe Certification Assessment Report							Date: 5/3/21-5/10/21							
			Inspection Company: BATT A		Ethel Allen							ULCS# 4440							
E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes
1	1	112	Classroom 113	Yes	W2	Block	Gray	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1	112	Classroom 113	Yes	W3	Block	Gray	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1	112	Classroom 113	Yes	W3	Metal	Tan	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	Univent
1	1	112	Classroom 113	Yes	W4	Block	Yellow	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1	112	Classroom 113	Yes	Ceiling	Concrete	White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1	112	Classroom 113	Yes	Floor	12 x 12 Tile	Multi	N/A	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1	113	Classroom 114	Yes	W1	Block	Gray	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1	113	Classroom 114	Yes	W1	Metal	Gray	None	0	N/A	N/A	None	N/A	Negative	N/A	No	N/A	N/A	Door Frame
1	1	113	Classroom 114	Yes	W2	Block	Grey	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1	113	Classroom 114	Yes	W3	Block	Gray	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1	113	Classroom 114	Yes	W3	Metal	Gray	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	Univent
1	1	113	Classroom 114	Yes	W4	Block	Orange	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1	113	Classroom 114	Yes	Ceiling	Concrete	White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1	113	Classroom 114	Yes	Floor	12 x 12 Tile	Multi	N/A	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1	114	Classroom115	Yes	W1	Block	Tan/White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1	114	Classroom115	Yes	W1	Metal	Black	Cracking	6	0.6	Negative	None	N/A	Negative	Yes	No	No	No	Door Frame
1	1	114	Classroom115	Yes	W2	Block	Tan/White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1	114	Classroom115	Yes	W3	Block	Tan/White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1	114	Classroom115	Yes	W3	Metal	Gray	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	Univent
1	1	114	Classroom115	Yes	W4	Block	Tan/White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1	114	Classroom115	Yes	Ceiling	Concrete	White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1	114	Classroom115	Yes	Floor	12 x 12 Tile	Tan	N/A	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1	114A	Copy Room next to Classroom 115	Yes	W1	Block	Purple	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1	114A	Copy Room next to Classroom 115	Yes	W2	Block	Purple	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1	114A	Copy Room next to Classroom 115	Yes	W3	Block	Purple	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1	114A	Copy Room next to Classroom 115	Yes	W4	Block	Purple	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1	114A	Copy Room next to Classroom 115	Yes	Ceiling	Drop Ceiling	White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1	114A	Copy Room next to Classroom 115	Yes	Floor	12 x 12 Tile	Brown	N/A	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1	114B	NRRCF Coordinator	Yes	W1	Block	White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1	114B	NRRCF Coordinator	Yes	W1	Metal	Black	Cracking	2	0.9	Positive	None	N/A	Negative	Yes	No	No	No	Door Frame
1	1	114B	NRRCF Coordinator	Yes	W2	Block	White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1	114B	NRRCF Coordinator	Yes	W3	Block	White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1	114B	NRRCF Coordinator	Yes	W4	Block	White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1	114B	NRRCF Coordinator	Yes	Ceiling	Drop Ceiling	White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1	114B	NRRCF Coordinator	Yes	Floor	12 x 12 Tile	Brown	N/A	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1		Office to the Left of Copy Room	Yes	W1	Block	White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1		Office to the Left of Copy Room	Yes	W1	Metal	Black	Cracking	2	0.6	Negative	None	N/A	Negative	Yes	No	No	No	Door Frame
1	1		Office to the Left of Copy Room	Yes	W2	Block	White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1		Office to the Left of Copy Room	Yes	W3	Block	White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1		Office to the Left of Copy Room	Yes	W4	Block	White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1		Office to the Left of Copy Room	Yes	Ceiling	Drop Ceiling	White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1		Office to the Left of Copy Room	Yes	Floor	12 x 12 Tile	Brown	N/A	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1	115	Classroom 116	Yes	W1	Block	Tan	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1	115	Classroom 116	yes	W1	Metal	Black	None	0	N/A	N/A	None	N/A	Negative	N/A	No	N/A	N/A	Door Frame
1	1	115	Classroom 116	Yes	W2	Block	Tan	Chipping	3	-0.2	Negative	None	N/A	Negative	Yes	No	No	No	
1	1	115	Classroom 116	Yes	W2	Metal	Tan	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	Univent
1	1	115	Classroom 116	Yes	W3	Block	Tan	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1	115	Classroom 116	Yes	W4	Block	Tan	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1	115	Classroom 116	Yes	Ceiling	Concrete	Tan	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1	115	Classroom 116	Yes	Floor	12 x 12 Tile	Brown	N/A	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1	115B	Storage next to Classroom 116	Yes	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		N/A	No	N/A	N/A	Not Accessible [BATTA 05.10.21]
1	1	115B	Storage next to Classroom 116	Yes	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		N/A	No	N/A	N/A	Not Accessible [BATTA 05.10.21]
1	1	115B	Storage next to Classroom 116	Yes	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		N/A	No	N/A	N/A	Not Accessible [BATTA 05.10.21]
1	1	115B	Storage next to Classroom 116	Yes	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		N/A	No	N/A	N/A	Not Accessible [BATTA 05.10.21]
1	1	115B	Storage next to Classroom 116	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		N/A	No	N/A	N/A	Not Accessible [BATTA 05.10.21]
1	1	115B	Storage next to Classroom 116	Yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		N/A	No	N/A	N/A	Not Accessible [BATTA 05.10.21]
1	1	115E	Men's Restroom next to Classroom 116	Yes	W1	Block	Tan	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1	115E	Men's Restroom next to Classroom 116	Yes	W1	Metal	Black	None	0	N/A	N/A	None	N/A	Negative	N/A	No	N/A	N/A	Door Frame
1	1	115E	Men's Restroom next to Classroom 116	Yes	W2	Block	Tan	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1	115E	Men's Restroom next to Classroom 116	Yes	W3	Block	Tan	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1	115E	Men's Restroom next to Classroom 116	Yes	W3	Metal	Tan	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	Univent
1	1	115E	Men's Restroom next to Classroom 116	Yes	W4	Block	Tan	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1	115E	Men's Restroom next to Classroom 116	Yes	Ceiling	Plaster	Tan	Flaking	2	-0.1	Negative	None	N/A	Negative	Yes	No	No	No	NAD previously
1	1	115E	Men's Restroom next to Classroom 116	Yes	Floor	Ceramic Tile	Multi	N/A	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1	115F	Women's Restroom next to Classroom 116	Yes	W1	Block	Tan	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1	115F	Women's Restroom next to Classroom 116	Yes	W1	Metal	Black	None	0	N/A	N/A	None	N/A	Negative	N/A	No	N/A	N/A	Door Frame
1	1	115F	Women's Restroom next to Classroom 116	Yes	W2	Block	Tan	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1	115F	Women's Restroom next to Classroom 116	Yes	W3	Block	Tan	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1	115F	Women's Restroom next to Classroom 116	Yes	W4	Block	Tan	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1	115F	Women's Restroom next to Classroom 116	Yes	Ceiling	Concrete	White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1	115F	Women's Restroom next to Classroom 116	Yes	Floor	Ceramic Tile	Multi	N/A	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1	115H	Kitchen Storage Area next to Cafeteria	No	W1	Block	Tan	None											

			School District of Philadelphia																			
			Lead Safe Certification Assessment Report												Date: 5/3/21-5/10/21							
			Ethel Allen												ULCS# 4440							
Name of Inspector: Alexis Johnson/ Justine James																						
Inspection Company: BATTA																						
Element	Floor	Space #			Component	Substrate	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)				
			On-Site Room Name	Student/ Teacher Occupied (yes/no)																		
1	1	115H	Kitchen Storage Area next to Cafeteria	No	W3	Block	Tan	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A				
1	1	115H	Kitchen Storage Area next to Cafeteria	No	W4	Block	Tan	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A				
1	1	115H	Kitchen Storage Area next to Cafeteria	No	Ceiling	Concrete	Tan	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A				
1	1	115H	Kitchen Storage Area next to Cafeteria	No	Floor	12 x 12 Tile	Tan	N/A	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A				
1	1		Kitchen	No	W1	Block	Tan/Brown	Flaking	2	0.1	Negative	None	N/A	Negative	Yes	No	No	No				
1	1		Kitchen	No	W1	Metal	Brown	Chipping	7	0.6	Negative	None	N/A	Negative	Yes	No	No	No	Door Frame			
1	1		Kitchen	No	W2	Block	Tan/Brown	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A				
1	1		Kitchen	No	W3	Block	Tan/Brown	Chipping	6	0	Negative	None	N/A	Negative	Yes	No	No	No				
1	1		Kitchen	No	W4	Block	Tan/Brown	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A				
1	1		Kitchen	No	Ceiling	Concrete	White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A				
1	1		Kitchen	No	Floor	Concrete	Brown	N/A	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A				
1	1		Kitchen Serving Area	No	W1	Block	Tan/Brown	Cracking	5	-0.1	Negative	None	N/A	Negative	Yes	No	No	No				
1	1		Kitchen Serving Area	no	W1	Metal	Brown	Chipping	2	0.7	Negative	None	N/A	Negative	Yes	No	No	No	Door Frame			
1	1		Kitchen Serving Area	No	W2	Block	Tan/Brown	Cracking	3	0.2	Negative	None	N/A	Negative	Yes	No	No	No				
1	1		Kitchen Serving Area	No	W2	Metal	Brown	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	Univent			
1	1		Kitchen Serving Area	No	W3	Block	Tan/Brown	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A				
1	1		Kitchen Serving Area	No	W4	Block	Tan/Brown	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A				
1	1		Kitchen Serving Area	No	Ceiling	Concrete	White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A				
1	1		Kitchen Serving Area	No	Floor	Ceramic Tile	Tan	N/A	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A				
1	1		Kitchen Loading Dock	No	W1	Block	Blue/White	Chipping	16	0.3	Negative	None	N/A	Negative	Yes	No	No	No				
1	1		Kitchen Loading Dock	No	W1	Metal	Brown	Chipping	8	0.1	Negative	None	N/A	Negative	Yes	No	No	No	Door			
1	1		Kitchen Loading Dock	No	W1	Metal	Brown	Chipping	5	0.8	Positive	None	N/A	Negative	Yes	No	No	No	Door Frame			
1	1		Kitchen Loading Dock	No	W2	Block	Blue/White	Chipping	50	0.1	Negative	None	N/A	Negative	Yes	No	No	No				
1	1		Kitchen Loading Dock	No	W3	Block	Blue/White	Chipping	10	-0.1	Negative	None	N/A	Negative	Yes	No	No	No				
1	1		Kitchen Loading Dock	No	W4	Block	Blue/White	Chipping	20	0.3	Negative	None	N/A	Negative	Yes	No	No	No				
1	1		Kitchen Loading Dock	No	W4	Metal	Blue	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	Univent			
1	1		Kitchen Loading Dock	No	Ceiling	Concrete	Tan	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A				
1	1		Kitchen Loading Dock	No	Floor	Concrete	Tan	N/A	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A				
1	1		Kitchen Locker Room/Restroom	No	W1	Block	Tan	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A				
1	1		Kitchen Locker Room/Restroom	No	W1	Metal	Brown	Cracking	2	0.5	Negative	None	N/A	Negative	Yes	No	No	No	Door Frame			
1	1		Kitchen Locker Room/Restroom	No	W2	Block	Brown	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A				
1	1		Kitchen Locker Room/Restroom	No	W3	Block	Brown	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A				
1	1		Kitchen Locker Room/Restroom	No	W4	Block	Brown	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A				
1	1		Kitchen Locker Room/Restroom	No	Ceiling	Concrete	Tan	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A				
1	1		Kitchen Locker Room/Restroom	No	Floor	Concrete	Red	N/A	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A				
1	1	116C	Counselor's Office Room 116C	Yes	W1	Block	Tan	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A				
1	1	116C	Counselor's Office Room 116C	Yes	W1	Metal	Black	Cracking	5	0.8	Positive	None	N/A	Negative	Yes	No	No	No	(2) Door Frames			
1	1	116C	Counselor's Office Room 116C	Yes	W2	Block	Tan	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A				
1	1	116C	Counselor's Office Room 116C	Yes	W3	Block	Tan	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A				
1	1	116C	Counselor's Office Room 116C	Yes	W4	Block	Tan	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A				
1	1	116C	Counselor's Office Room 116C	Yes	Ceiling	Drop Ceiling	White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A				
1	1	116C	Counselor's Office Room 116C	Yes	Floor	12 x 12 Tile	Brown	N/A	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A				
1	1	117	Cafeteria	Yes	W1	Block	Tan/White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A				
1	1	117	Cafeteria	Yes	W1	Metal	Brown	Cracking	1	0.7	Negative	None	N/A	Negative	Yes	No	No	No	Door Frame			
1	1	117	Cafeteria	Yes	W1	Metal	Brown	Cracking	2	0.7	Negative	None	N/A	Negative	Yes	No	No	No	Door Frame			
1	1	117	Cafeteria	Yes	W2	Block	Tan/White	Cracking	2	0	Negative	None	N/A	Negative	Yes	No	No	No				
1	1	117	Cafeteria	Yes	W2	Metal	Black	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	Univent			
1	1	117	Cafeteria	Yes	W3	Block	Tan/White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A				
1	1	117	Cafeteria	Yes	W3	Metal	Brown	Chipping	5	-0.1	Negative	None	N/A	Negative	Yes	No	No	No	Door Frame			
1	1	117	Cafeteria	Yes	W3	Metal	Brown	Chipping	3	0.1	Negative	None	N/A	Negative	Yes	No	No	No	Door Frame			
1	1	117	Cafeteria	Yes	W4	Block	Tan/White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A				
1	1	117	Cafeteria	Yes	W4	Metal	Black	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	Univent			
1	1	117	Cafeteria	yes	Ceiling	Concrete	White	N/A	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A				
1	1	117	Cafeteria	Yes	Ceiling	Drop Ceiling	White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A				
1	1	117	Cafeteria	Yes	Floor	12 x 12 Tile	Tan	N/A	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A				
1	1	117A	Hallway to Cafeteria	Yes	W1	Block	Multi	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A				
1	1	117A	Hallway to Cafeteria	Yes	W2	Block	Multi	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A				
1	1	117A	Hallway to Cafeteria	Yes	W3	Block	Multi	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A				
1	1	117A	Hallway to Cafeteria	Yes	W4	Block	Multi	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A				
1	1	117A	Hallway to Cafeteria	Yes	Ceiling	Drop Ceiling	White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A				
1	1	117A	Hallway to Cafeteria	Yes	Floor	12 x 12 Tile	Tan	N/A	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A				
1	1	117B	Boy's Restroom	Yes	W1	Block	White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A				
1	1	117B	Boy's Restroom	Yes	W1	Metal	Black	Chipping	6	0.6	Negative	None	N/A	Negative	Yes	No	No	No	Door Frame			
1	1	117B	Boy's Restroom	Yes	W2	Block	White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A				
1	1	117B	Boy's Restroom	Yes	W3	Block	White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A				
1	1	117B	Boy's Restroom	Yes	W4	Block	White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A				
1	1	117B	Boy's Restroom	Yes	Ceiling	Plaster	White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A				
1	1	117B	Boy's Restroom	Yes	Floor	Ceramic Tile	Multi	N/A	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A				
1	1	117C	Girl's Restroom	Yes	W1	Block	White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A				
1	1	117C	Girl's Restroom	Yes	W1	Metal	Black	Chipping	10	0.5	Negative	None	N/A	Negative	Yes	No	No	No	Door Frame			
1	1	117C	Girl's Restroom	Yes	W2	Block	White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A				
1	1	117C	Girl's Restroom	Yes	W3	Block	White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A				
1	1	117C	Girl's Restroom	Yes	W4	Block	White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A				
1	1	117C	Girl's Restroom	Yes	Ceiling	Plaster	White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A				

					School District of Philadelphia														
			Name of Inspector: Alexis Johnson/ Justine James		Lead Safe Certification Assessment Report							Date: 5/3/21-5/10/21							
			Inspection Company: BATTA		Ethel Allen							ULCS# 4440							
E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes
1	1	117C	Girl's Restroom	Yes	Floor	12 x 12 Tile	Tan	N/A	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1	120	Boy's Restroom in Hallway next to Gym	Yes	W1	Block	White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1	120	Boy's Restroom in Hallway next to Gym	Yes	W1	Metal	Brown	Chipping	6	0.9	Positive	None	N/A	Negative	Yes	No	No	No	Door Frame
1	1	120	Boy's Restroom in Hallway next to Gym	Yes	W2	Block	White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1	120	Boy's Restroom in Hallway next to Gym	Yes	W3	Block	White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1	120	Boy's Restroom in Hallway next to Gym	Yes	W4	Block	White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1	120	Boy's Restroom in Hallway next to Gym	Yes	Ceiling	Plaster	White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1	120	Boy's Restroom in Hallway next to Gym	Yes	Floor	Ceramic Tile	Multi	N/A	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1	H1	First Floor Main Hallway	Yes	W1	Block	Multi	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1	H1	First Floor Main Hallway	Yes	W2	Block	Multi	Cracking	10	-0.1	Negative	None	N/A	Negative	Yes	No	No	No	
1	1	H1	First Floor Main Hallway	Yes	W2	Metal	Tan	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	(5) Univents
1	1	H1	First Floor Main Hallway	Yes	W3	Block	Multi	Cracking	15	0	Negative	None	N/A	Negative	Yes	No	No	No	
1	1	H1	First Floor Main Hallway	Yes	W4	Block	Multi	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1	H1	First Floor Main Hallway	Yes	Ceiling	Drop Ceiling	White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1	H1	First Floor Main Hallway	Yes	Floor	12 x 12 Tile	Brown	N/A	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1	H3	Gym Hallway	Yes	W1	Block	Multi	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1	H3	Gym Hallway	Yes	W2	Block	Multi	Cracking	3	0	Negative	None	N/A	Negative	Yes	No	No	No	
1	1	H3	Gym Hallway	Yes	W4	Block	Multi	Cracking	3	-0.1	Negative	None	N/A	Negative	Yes	No	No	No	
1	1	H3	Gym Hallway	Yes	Ceiling	Drop Ceiling	White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1	H3	Gym Hallway	Yes	Floor	12 x 12 Tile	N/A	N/A	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1	S1	Stairs Leading to Auditorium	Yes	W1	Block	White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	Poor Lighting [BATTA AJ 05.07.21]
1	1	S1	Stairs Leading to Auditorium	Yes	W2	Block	White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	Poor Lighting [BATTA AJ 05.07.21]
1	1	S1	Stairs Leading to Auditorium	Yes	W3	Block	White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	Poor Lighting [BATTA AJ 05.07.21]
1	1	S1	Stairs Leading to Auditorium	Yes	W4	Block	White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	Poor Lighting [BATTA AJ 05.07.21]
1	1	S1	Stairs Leading to Auditorium	Yes	Ceiling	Concrete	N/A	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	Poor Lighting [BATTA AJ 05.07.21]
1	1	S1	Stairs Leading to Auditorium	Yes	Floor	Concrete	N/A	N/A	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	Poor Lighting [BATTA AJ 05.07.21]
1	1	SA	Stair A next to Classroom 101	Yes	W1	Block	Multi	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1	SA	Stair A next to Classroom 101	Yes	W1	Metal	Black	Cracking	3	-0.1	Negative	None	N/A	Negative	Yes	No	No	No	Door Frame
1	1	SA	Stair A next to Classroom 101	Yes	W1	Metal	Black	Cracking	2	-0.1	Negative	None	N/A	Negative	Yes	No	No	No	(2) Doors
1	1	SA	Stair A next to Classroom 101	Yes	W2	Block	Multi	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1	SA	Stair A next to Classroom 101	Yes	W2	Metal	Tan	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	Univent
1	1	SA	Stair A next to Classroom 101	Yes	W3	Block	Multi	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1	SA	Stair A next to Classroom 101	Yes	W3	Metal	Black	Cracking	1	0	Negative	None	N/A	Negative	Yes	No	No	No	(2) Doors
1	1	SA	Stair A next to Classroom 101	Yes	W4	Block	Multi	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1	SA	Stair A next to Classroom 101	Yes	Ceiling	Concrete	N/A	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1	SA	Stair A next to Classroom 101	Yes	Floor	Concrete	Gray	N/A	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1	SB	Stair B next to Classroom 116	Yes	W1	Metal	Black	Cracking	3	0.3	Negative	None	N/A	Negative	Yes	No	No	No	Door Frame
1	1	SB	Stair B next to Classroom 116	Yes	W1	Metal	Black	Cracking	2	0.3	Negative	None	N/A	Negative	Yes	No	No	No	(2) Doors
1	1	SB	Stair B next to Classroom 116	Yes	W2	Block	Multi	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1	SB	Stair B next to Classroom 116	Yes	W2	Metal	Tan	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	Univent
1	1	SB	Stair B next to Classroom 116	Yes	W3	Block	Multi	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1	SB	Stair B next to Classroom 116	Yes	W3	Metal	Black	None	0	N/A	N/A	None	N/A	Negative	N/A	No	N/A	N/A	(2) Doors
1	1	SB	Stair B next to Classroom 116	Yes	W4	Block	Multi	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1	SB	Stair B next to Classroom 116	Yes	Ceiling	Concrete	N/A	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1	SB	Stair B next to Classroom 116	Yes	Floor	Concrete	Gray	N/A	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1	SC	Stair C next to Gym	Yes	W1	Block	Multi	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1	SC	Stair C next to Gym	Yes	W1	Metal	Black	None	0	N/A	N/A	None	N/A	Negative	N/A	No	N/A	N/A	Door Frame
1	1	SC	Stair C next to Gym	Yes	W2	Block	Multi	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1	SC	Stair C next to Gym	Yes	W2	Metal	Purple	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	Univent
1	1	SC	Stair C next to Gym	Yes	W3	Block	Multi	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1	SC	Stair C next to Gym	Yes	W3	Metal	Black	None	0	N/A	N/A	None	N/A	Negative	N/A	No	N/A	N/A	Door Frame
1	1	SC	Stair C next to Gym	Yes	W3	Metal	Black	None	0	N/A	N/A	None	N/A	Negative	N/A	No	N/A	N/A	Door
1	1	SC	Stair C next to Gym	Yes	W4	Block	Multi	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1	SC	Stair C next to Gym	Yes	Ceiling	Concrete	White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1	SC	Stair C next to Gym	Yes	Floor	12 x 12 Tile	Tan	N/A	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1	SD	Stair D next to Classroom 106	Yes	W1	Block	Multi	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1	SD	Stair D next to Classroom 106	Yes	W1	Metal	Black	Cracking	2	0.6	Negative	None	N/A	Negative	Yes	No	No	No	(2) Door Frame
1	1	SD	Stair D next to Classroom 106	Yes	W1	Metal	Black	Cracking	5	0.4	Negative	None	N/A	Negative	Yes	No	No	No	(4) Door
1	1	SD	Stair D next to Classroom 106	Yes	W2	Block	Multi	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1	SD	Stair D next to Classroom 106	Yes	W3	Block	Multi	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1	SD	Stair D next to Classroom 106	Yes	W3	Metal	Black	None	0	N/A	N/A	None	N/A	Negative	N/A	No	N/A	N/A	Door Frame
1	1	SD	Stair D next to Classroom 106	Yes	W4	Block	Multi	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1	SD	Stair D next to Classroom 106	Yes	W4	Metal	Purple	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	Univent
1	1	SD	Stair D next to Classroom 106	Yes	Ceiling	Concrete	White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	1	SD	Stair D next to Classroom 106	Yes	Floor	12 x 12 Tile	Brown	N/A	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	2	10	Book Room to left of Classroom 207	Yes	W1	Block	N/A	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	2	10	Book Room to left of Classroom 207	yes	W1	Metal	Black	None	0	N/A	N/A	None	N/A	Negative	N/A	No	N/A	N/A	Door Frame
1	2	10	Book Room to left of Classroom 207	Yes	W2	Block	N/A	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	2	10	Book Room to left of Classroom 207	Yes	W3	Block	N/A	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	2	10																	

					School District of Philadelphia														
			Name of Inspector: Alexis Johnson/ Justine James		Lead Safe Certification Assessment Report							Date: 5/3/21-5/10/21							
			Inspection Company: BATTA		Ethel Allen							ULCS# 4440							
E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes
1	2	200	Classroom 200	Yes	W2	Block	Tan/White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	2	200	Classroom 200	Yes	W3	Block	Tan/White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	2	200	Classroom 200	Yes	W3	Metal	Tan	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	(2) Univent
1	2	200	Classroom 200	Yes	W4	Block	Tan/White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	2	200	Classroom 200	Yes	Ceiling	Concrete	White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	2	200	Classroom 200	Yes	Floor	12 x 12 Tile	Multi	N/A	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	2	200	Classroom 200 Storage A	Yes	W1	Block	Tan	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	2	200	Classroom 200 Storage A	Yes	W1	Metal	Black	None	0	N/A	N/A	None	N/A	Negative	N/A	No	N/A	N/A	(2) Door Frame
1	2	200	Classroom 200 Storage A	Yes	W2	Block	Tan	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	2	200	Classroom 200 Storage A	Yes	W3	Block	Tan	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	2	200	Classroom 200 Storage A	Yes	W4	Block	Tan	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	2	200	Classroom 200 Storage A	Yes	Ceiling	Concrete	N/A	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	2	200	Classroom 200 Storage A	Yes	Ceiling	Metal	White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	Duct Work
1	2	200	Classroom 200 Storage A	Yes	Floor	12 x 12 Tile	Multi	N/A	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	2	200	Classroom 200 Storage B	Yes	W1	Block	Tan	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	2	200	Classroom 200 Storage B	Yes	W1	Metal	Black	None	0	N/A	N/A	None	N/A	Negative	N/A	No	N/A	N/A	Door Frame
1	2	200	Classroom 200 Storage B	Yes	W2	Block	Tan	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	2	200	Classroom 200 Storage B	Yes	W3	Block	Tan	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	2	200	Classroom 200 Storage B	Yes	W4	Block	Tan	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	2	200	Classroom 200 Storage B	Yes	Ceiling	Concrete	N/A	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	2	200	Classroom 200 Storage B	Yes	Ceiling	Metal	White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	Duct Work
1	2	200	Classroom 200 Storage B	Yes	Floor	12 x 12 Tile	Multi	N/A	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	2	200A	Classroom 200C	Yes	W1	Block	Tan/White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	2	200A	Classroom 200C	Yes	W1	Metal	Door Frame	None	0	N/A	N/A	None	N/A	Negative	N/A	No	N/A	N/A	Door Frame
1	2	200A	Classroom 200C	Yes	W1	Metal	Door Frame	None	0	N/A	N/A	None	N/A	Negative	N/A	No	N/A	N/A	Door Frame
1	2	200A	Classroom 200C	Yes	W2	Block	Tan/White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	2	200A	Classroom 200C	Yes	W3	Block	Tan/White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	2	200A	Classroom 200C	Yes	W4	Block	Tan/White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	2	200A	Classroom 200C	Yes	Ceiling	Drop Ceiling	White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	2	200A	Classroom 200C	Yes	Floor	12 x 12 Tile	Brown	N/A	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	2	200C	Classroom 200A	Yes	W1	Block	Tan/White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	2	200C	Classroom 200A	Yes	W1	Metal	Black	Cracking	2	0.3	Negative	None	N/A	Negative	Yes	No	No	No	Door Frame
1	2	200C	Classroom 200A	Yes	W2	Block	Tan/White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	2	200C	Classroom 200A	Yes	W3	Block	Tan/White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	2	200C	Classroom 200A	Yes	W3	Metal	Tan	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	Univent
1	2	200C	Classroom 200A	Yes	W4	Block	Tan/White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	2	200C	Classroom 200A	Yes	Ceiling	Concrete	White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	2	200C	Classroom 200A	Yes	Floor	12 x 12 Tile	Green	N/A	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	2	SB	Stair B Next to Classroom 200A	Yes	W1	Block	Multi	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	2	SB	Stair B Next to Classroom 200A	Yes	W1	Metal	Black	None	0	N/A	N/A	None	N/A	Negative	N/A	No	N/A	N/A	Door Frame
1	2	SB	Stair B Next to Classroom 200A	Yes	W2	Block	Multi	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	Univent
1	2	SB	Stair B Next to Classroom 200A	Yes	W3	Block	Multi	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	2	SB	Stair B Next to Classroom 200A	Yes	W4	Block	Multi	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	Univent
1	2	SB	Stair B Next to Classroom 200A	Yes	Ceiling	Concrete	N/A	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	2	SB	Stair B Next to Classroom 200A	Yes	Floor	Concrete	Gray	N/A	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	2	200B	Music Classroom 200B	Yes	W1	Block	Tan	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	2	200B	Music Classroom 200B	Yes	W1	Metal	Black	None	0	N/A	N/A	None	N/A	Negative	N/A	No	N/A	N/A	Door Frame
1	2	200B	Music Classroom 200B	Yes	W2	Block	Tan	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	2	200B	Music Classroom 200B	Yes	W2	Metal	Black	None	0	N/A	N/A	None	N/A	Negative	N/A	No	N/A	N/A	(3) Door Frame
1	2	200B	Music Classroom 200B	Yes	W3	Block	Tan	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	2	200B	Music Classroom 200B	Yes	W3	Plaster	Tan	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	2	200B	Music Classroom 200B	Yes	W4	Block	Tan	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	2	200B	Music Classroom 200B	Yes	Ceiling	Drop Ceiling	White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	2	200B	Music Classroom 200B	Yes	Floor	12 x 12 Tile	Multi	N/A	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	2	200E	HVAC Room	No	W1	Concrete	N/A	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	2	200E	HVAC Room	no	W1	Metal	Black	None	0	N/A	N/A	None	N/A	Negative	N/A	No	N/A	N/A	Door Frame
1	2	200E	HVAC Room	No	W2	Concrete	N/A	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	2	200E	HVAC Room	No	W3	Concrete	N/A	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	2	200E	HVAC Room	No	W4	Concrete	N/A	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	2	200E	HVAC Room	No	Ceiling	Concrete	N/A	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	2	200E	HVAC Room	No	Floor	Concrete	N/A	N/A	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	2	2011A	Book Closet to Left of Classroom 200C	Yes	W1	Block	N/A	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	2	2011A	Book Closet to Left of Classroom 200C	yes	W1	Metal	Black	None	0	N/A	N/A	None	N/A	Negative	N/A	No	N/A	N/A	Door Frame
1	2	2011A	Book Closet to Left of Classroom 200C	Yes	W2	Block	N/A	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	2	2011A	Book Closet to Left of Classroom 200C	Yes	W3	Block	N/A	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	2	2011A	Book Closet to Left of Classroom 200C	Yes	W4	Block	N/A	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	2	2011A	Book Closet to Left of Classroom 200C	Yes	Ceiling	Concrete	White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	2	2011A	Book Closet to Left of Classroom 200C	Yes	Floor	Concrete	N/A	N/A	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	2	201A	Classroom 201	Yes	W1	Block	Tan/White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	2	201A	Classroom 201	Yes	W1	Metal	Black	Flaking	3	0.8	Positive								

			School District of Philadelphia																	
			Name of Inspector: Alexis Johnson/ Justine James		Lead Safe Certification Assessment Report								Date: 5/3/21-5/10/21							
			Inspection Company: BATT		Ethel Allen								ULCS# 4440							
E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes	
1	2	201A	Classroom 201	Yes	Floor	12 x 12 Tile	Tan	N/A	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A		
1	2	2011B	Book Closet to Right of Classroom 201	Yes	W1	Block	N/A	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A		
1	2	2011B	Book Closet to Right of Classroom 201	yes	W1	Metal	Black	None	0	N/A	N/A	None	N/A	Negative	N/A	No	N/A	N/A	Door Frame	
1	2	2011B	Book Closet to Right of Classroom 201	Yes	W2	Block	N/A	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A		
1	2	2011B	Book Closet to Right of Classroom 201	Yes	W3	Block	N/A	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A		
1	2	2011B	Book Closet to Right of Classroom 201	Yes	W4	Block	N/A	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A		
1	2	2011B	Book Closet to Right of Classroom 201	Yes	Ceiling	Drop Ceiling	White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A		
1	2	2011B	Book Closet to Right of Classroom 201	Yes	Floor	Concrete	N/A	N/A	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A		
1	2	201B	Classroom 202	Yes	W1	Block	Tan/White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A		
1	2	201B	Classroom 202	Yes	W1	Metal	Black	Cracking	3	0.8	Positive	None	N/A	Negative	Yes	No	No	No	Door Frame	
1	2	201B	Classroom 202	Yes	W2	Block	Tan/White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A		
1	2	201B	Classroom 202	Yes	W2	Metal	Black	None	0	N/A	N/A	None	N/A	Negative	N/A	No	N/A	N/A	Door Frame	
1	2	201B	Classroom 202	Yes	W3	Block	Tan/White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A		
1	2	201B	Classroom 202	Yes	W4	Partition	Tan	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A		
1	2	201B	Classroom 202	Yes	Ceiling	Concrete	White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A		
1	2	201B	Classroom 202	Yes	Floor	12 x 12 Tile	Tan	N/A	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A		
1	2	201C	Classroom 202 and 204 Closet	Yes	W1	Block	White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A		
1	2	201C	Classroom 202 and 204 Closet	Yes	W2	Block	White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A		
1	2	201C	Classroom 202 and 204 Closet	Yes	W3	Block	White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A		
1	2	201C	Classroom 202 and 204 Closet	Yes	W4	Block	White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A		
1	2	201C	Classroom 202 and 204 Closet	Yes	Ceiling	Drop Ceiling	White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A		
1	2	201C	Classroom 202 and 204 Closet	Yes	Floor	12 x 12 Tile	Brown	N/A	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A		
1	2	201D	Book Room to the Left of Stair A	No	W1	Block	N/A	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A		
1	2	201D	Book Room to the Left of Stair A	No	W1	Metal	Black	None	0	N/A	N/A	None	N/A	Negative	N/A	No	N/A	N/A	Door Frame	
1	2	201D	Book Room to the Left of Stair A	No	W2	Block	N/A	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A		
1	2	201D	Book Room to the Left of Stair A	No	W3	Block	N/A	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A		
1	2	201D	Book Room to the Left of Stair A	No	W4	Block	N/A	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A		
1	2	201D	Book Room to the Left of Stair A	No	Ceiling	Concrete	White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A		
1	2	201D	Book Room to the Left of Stair A	No	Floor	Concrete	N/A	N/A	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A		
1	2	202	Classroom 203	Yes	W1	Block	Tan/White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A		
1	2	202	Classroom 203	Yes	W1	Metal	Black	Chipping	5	0.6	Negative	None	N/A	Negative	Yes	No	No	No	Door Frame	
1	2	202	Classroom 203	Yes	W2	Block	Tan/White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A		
1	2	202	Classroom 203	Yes	W3	Block	Tan/White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A		
1	2	202	Classroom 203	Yes	W3	Metal	Tan	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	Univent	
1	2	202	Classroom 203	Yes	W4	Block	Tan/White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A		
1	2	202	Classroom 203	Yes	Ceiling	Concrete	Tan/White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A		
1	2	202	Classroom 203	Yes	Floor	12 x 12 Tile	Brown	N/A	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A		
1	2	SA	Stair A next to Classroom 203	Yes	W1	Block	Multi	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A		
1	2	SA	Stair A next to Classroom 203	yes	W1	Metal	Red	None	0	N/A	N/A	None	N/A	Negative	N/A	No	N/A	N/A	Door Frame	
1	2	SA	Stair A next to Classroom 203	Yes	W2	Block	Multi	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A		
1	2	SA	Stair A next to Classroom 203	yes	W2	Metal	Tan	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	Univent	
1	2	SA	Stair A next to Classroom 203	Yes	W3	Block	Multi	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A		
1	2	SA	Stair A next to Classroom 203	Yes	W4	Block	Multi	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A		
1	2	SA	Stair A next to Classroom 203	yes	W4	Metal	Tan	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	Univent	
1	2	SA	Stair A next to Classroom 203	Yes	W4	Metal	Black	Chipping	3	0.2	Negative	None	N/A	Negative	Yes	No	No	No	Door Frame	
1	2	SA	Stair A next to Classroom 203	Yes	Ceiling	Concrete	N/A	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A		
1	2	SA	Stair A next to Classroom 203	Yes	Floor	Concrete	Gray	N/A	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A		
1	2	203A	Classroom 204	Yes	W1	Block	Tan/White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A		
1	2	203A	Classroom 204	Yes	W1	Metal	Black	Flaking	4	0.4	Negative	None	N/A	Negative	Yes	No	No	No	Door Frame	
1	2	203A	Classroom 204	Yes	W2	Block	Tan/White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A		
1	2	203A	Classroom 204	Yes	W3	Block	Tan/White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A		
1	2	203A	Classroom 204	Yes	W4	Block	Tan/White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A		
1	2	203A	Classroom 204	Yes	Ceiling	Block	White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A		
1	2	203A	Classroom 204	Yes	Floor	12 x 12 Tile	Multi	N/A	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A		
1	2	203B	Classroom 205	Yes	W1	Block	Tan/White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A		
1	2	203B	Classroom 205	Yes	W1	Metal	Black	Cracking	4	0.8	Positive	None	N/A	Negative	Yes	No	No	No	Door Frame	
1	2	203B	Classroom 205	Yes	W2	Block	Tan/White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A		
1	2	203B	Classroom 205	Yes	W2	Partition	Tan	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A		
1	2	203B	Classroom 205	Yes	W3	Block	Tan	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A		
1	2	203B	Classroom 205	Yes	W4	Block	Tan/White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A		
1	2	203B	Classroom 205	Yes	Ceiling	Concrete	White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A		
1	2	203B	Classroom 205	Yes	Floor	12 x 12 Tile	Tan	N/A	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A		
1	2	203C	Classroom 206	Yes	W1	Block	Tan/White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A		
1	2	203C	Classroom 206	Yes	W1	Metal	Black	Cracking	5	0.8	Positive	None	N/A	Negative	Yes	No	No	No	Door Frame	
1	2	203C	Classroom 206	Yes	W2	Block	Tan/White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A		
1	2	203C	Classroom 206	Yes	W3	Block	Tan/White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A		
1	2	203C	Classroom 206	Yes	W4	Block	Tan/White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A		
1	2	203C	Classroom 206	Yes	Ceiling	Concrete	White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A		
1	2	203C	Classroom 206	Yes	Floor	12 x 12 Tile	Tan	N/A	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A		
1	2	203D	Classroom 207	Yes	W1	Block	Tan/White	None	0	N/A	N/A	None	N/A		N/A	No	N/A			

			School District of Philadelphia																	
			Lead Safe Certification Assessment Report																	
			Ethel Allen																	
			Name of Inspector: Alexis Johnson/ Justine James												Date: 5/3/21-5/10/21					
			Inspection Company: BATT												ULCS# 4440					
E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes	
1	2	203D	Classroom 207	Yes	Ceiling	Concrete	White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A		
1	2	203D	Classroom 207	Yes	Floor	12 x 12 Tile	Tan	N/A	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A		
1	2		Book Room to the Left of Stair D	Yes	W1	Block	N/A	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A		
1	2		Book Room to the Left of Stair D	Yes	W1	Metal	Black	None	0	N/A	N/A	None	N/A	Negative	N/A	No	N/A	N/A	Door Frame	
1	2		Book Room to the Left of Stair D	Yes	W2	Block	N/A	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A		
1	2		Book Room to the Left of Stair D	Yes	W3	Block	N/A	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A		
1	2		Book Room to the Left of Stair D	Yes	W4	Block	N/A	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A		
1	2		Book Room to the Left of Stair D	Yes	Ceiling	Concrete	N/A	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A		
1	2		Book Room to the Left of Stair D	Yes	Floor	Concrete	N/A	N/A	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A		
1	2		Book Room to the Right of Stair D	Yes	W1	Block	N/A	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A		
1	2		Book Room to the Right of Stair D	Yes	W1	Metal	Black	None	0	N/A	N/A	None	N/A	Negative	N/A	No	N/A	N/A	Door Frame	
1	2		Book Room to the Right of Stair D	Yes	W2	Block	N/A	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A		
1	2		Book Room to the Right of Stair D	Yes	W3	Block	N/A	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A		
1	2		Book Room to the Right of Stair D	Yes	W4	Block	N/A	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A		
1	2		Book Room to the Right of Stair D	Yes	Ceiling	Concrete	N/A	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A		
1	2		Book Room to the Right of Stair D	Yes	Floor	Concrete	N/A	N/A	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A		
1	2	203E	Custodial Closet to Right of Stair D	Yes	W1	N/A	N/A	N/A	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A		
1	2	203E	Custodial Closet to Right of Stair D	Yes	W2	N/A	N/A	N/A	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A		
1	2	203E	Custodial Closet to Right of Stair D	Yes	W3	N/A	N/A	N/A	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A		
1	2	203E	Custodial Closet to Right of Stair D	Yes	W4	N/A	N/A	N/A	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A		
1	2	203E	Custodial Closet to Right of Stair D	Yes	Ceiling	N/A	N/A	N/A	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A		
1	2	203E	Custodial Closet to Right of Stair D	Yes	Floor	N/A	N/A	N/A	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A		
1	2	203F	Girl's Restroom	Yes	W1	Block	Tan	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A		
1	2	203F	Girl's Restroom	Yes	W1	Metal	Black	Cracking	7	0.7	Negative	None	N/A	Negative	Yes	No	No	No	Door Frame	
1	2	203F	Girl's Restroom	Yes	W2	Block	Tan	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A		
1	2	203F	Girl's Restroom	Yes	W3	Block	Tan	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A		
1	2	203F	Girl's Restroom	Yes	W4	Block	Tan	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A		
1	2	203F	Girl's Restroom	Yes	Ceiling	Concrete	White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A		
1	2	203F	Girl's Restroom	Yes	Floor	Ceramic Tile	Multi	N/A	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A		
1	2	204	Classroom 208 (Computer Lab)	Yes	W1	Block	Tan/White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A		
1	2	204	Classroom 208 (Computer Lab)	yes	W1	Metal	Black	None	0	N/A	N/A	None	N/A	Negative	N/A	No	N/A	N/A	Door Frame	
1	2	204	Classroom 208 (Computer Lab)	Yes	W2	Block	Tan/White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A		
1	2	204	Classroom 208 (Computer Lab)	Yes	W3	Block	Tan/White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A		
1	2	204	Classroom 208 (Computer Lab)	yes	W3	Metal	Tan	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	Univent	
1	2	204	Classroom 208 (Computer Lab)	Yes	W4	Block	Tan/White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A		
1	2	204	Classroom 208 (Computer Lab)	Yes	Ceiling	Concrete	White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A		
1	2	204	Classroom 208 (Computer Lab)	Yes	Floor	12 x 12 Tile	Brown	N/A	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A		
1	2	206	Classroom 209	Yes	W1	Block	Tan	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A		
1	2	206	Classroom 209	Yes	W1	Metal	Black	None	0	N/A	N/A	None	N/A	Negative	N/A	No	N/A	N/A	(2) Door Frame	
1	2	206	Classroom 209	Yes	W2	Block	Tan	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A		
1	2	206	Classroom 209	Yes	W3	Block	Tan	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A		
1	2	206	Classroom 209	Yes	W3	Metal	Tan	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	(2) Univent	
1	2	206	Classroom 209	Yes	W4	Block	Tan	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A		
1	2	206	Classroom 209	Yes	Ceiling	Concrete	White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A		
1	2	206	Classroom 209	Yes	Floor	12 x 12 Tile	Brown	N/A	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A		
1	2	206B	Classroom 209 Storage Closet (IDF-2)	Yes	W1	Block	Tan	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A		
1	2	206B	Classroom 209 Storage Closet (IDF-2)	Yes	W1	Metal	Brown	None	0	N/A	N/A	None	N/A	Negative	N/A	No	N/A	N/A	Door Frame	
1	2	206B	Classroom 209 Storage Closet (IDF-2)	Yes	W2	Block	Tan	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A		
1	2	206B	Classroom 209 Storage Closet (IDF-2)	Yes	W2	Plaster	White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A		
1	2	206B	Classroom 209 Storage Closet (IDF-2)	Yes	W3	Block	Tan	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A		
1	2	206B	Classroom 209 Storage Closet (IDF-2)	Yes	W4	Block	Tan	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A		
1	2	206B	Classroom 209 Storage Closet (IDF-2)	Yes	Ceiling	Concrete	N/A	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A		
1	2	206B	Classroom 209 Storage Closet (IDF-2)	Yes	Floor	12 x 12 Tile	Brown	N/A	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A		
1	2	207A	Classroom 210	Yes	W1	Block	Tan/White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A		
1	2	207A	Classroom 210	Yes	W1	Metal	Black	Chipping	8	0.7	Negative	None	N/A	Negative	Yes	No	No	No	Door Frame	
1	2	207A	Classroom 210	Yes	W2	Partition	Tan/White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A		
1	2	207A	Classroom 210	Yes	W3	Block	Tan/White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A		
1	2	207A	Classroom 210	Yes	W4	Block	Tan/White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A		
1	2	207A	Classroom 210	Yes	Ceiling	Concrete	White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A		
1	2	207A	Classroom 210	Yes	Floor	12 x 12 Tile	Tan	N/A	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A		
1	2	207C	Men's Restroom next to Classroom 210	Yes	W1	Block	Tan	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A		
1	2	207C	Men's Restroom next to Classroom 210	Yes	W1	Metal	Black	None	0	N/A	N/A	None	N/A	Negative	N/A	No	N/A	N/A	Door Frame	
1	2	207C	Men's Restroom next to Classroom 210	Yes	W2	Block	Tan	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A		
1	2	207C	Men's Restroom next to Classroom 210	Yes	W3	Block	Tan	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A		
1	2	207C	Men's Restroom next to Classroom 210	Yes	W4	Block	Tan	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A		
1	2	207C	Men's Restroom next to Classroom 210	Yes	Ceiling	Plaster	White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A		
1	2	207C	Men's Restroom next to Classroom 210	Yes	Floor	12 x 12 Tile	Multi	N/A	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A		
1	2	207D	Women's Restroom next to Classroom 210	Yes	W1	Block	Tan	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A		
1	2	207D	Women's Restroom next to Classroom 210	Yes	W1	Metal	Black	None	0	N/A	N/A	None	N/A	Negative	N/A	No	N/A	N/A	Door Frame	
1	2	207D	Women's Restroom next to Classroom 210	Yes	W2	Block	Tan	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A		
1	2	207D	Women's Restroom next to Classroom 210	Yes	W3	Block</														

			School District of Philadelphia																
			Name of Inspector: Alexis Johnson/ Justine James		Lead Safe Certification Assessment Report							Date: 5/3/21-5/10/21							
			Inspection Company: BATTA		Ethel Allen							ULCS# 4440							
E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes
1	2	SD	Stair D Next to Classroom 210	Yes	W1	Block	Multi	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	2	SD	Stair D Next to Classroom 210	Yes	W1	Metal	Brown	Cracking	2	0.6	Negative	None	N/A	Negative	Yes	No	No	No	(2) Door Frame
1	2	SD	Stair D Next to Classroom 210	Yes	W2	Block	Multi	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	2	SD	Stair D Next to Classroom 210	Yes	W2	Metal	Tan	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	Univent
1	2	SD	Stair D Next to Classroom 210	Yes	W3	Block	Multi	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	2	SD	Stair D Next to Classroom 210	Yes	W4	Block	Multi	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	2	SD	Stair D Next to Classroom 210	Yes	W4	Metal	Tan	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	Univent
1	2	SD	Stair D Next to Classroom 210	Yes	Ceiling	Concrete	N/A	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	2	SD	Stair D Next to Classroom 210	Yes	Floor	Concrete	Gray	N/A	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	2	207B	Classroom 211	Yes	W1	Block	Tan/White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	2	207B	Classroom 211	yes	W1	Metal	Black	Cracking	6	0.8	Positive	None	N/A	Negative	Yes	No	No	No	Door Frame
1	2	207B	Classroom 211	Yes	W2	Block	Tan/White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	2	207B	Classroom 211	Yes	W3	Block	Tan/White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	2	207B	Classroom 211	Yes	W3	Metal	Black	Cracking	4	0.8	Positive	None	N/A	Negative	Yes	No	No	No	Door Frame
1	2	207B	Classroom 211	Yes	W4	Partition	Tan/White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	2	207B	Classroom 211	Yes	Ceiling	Concrete	White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	2	207B	Classroom 211	Yes	Floor	12 x 12 Tile	Tan	N/A	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	2	208A	Classroom 212	Yes	W1	Block	Tan/White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	2	208A	Classroom 212	Yes	W1	Metal	Black	Cracking	8	0.8	Positive	None	N/A	Negative	Yes	No	No	No	Door Frame
1	2	208A	Classroom 212	Yes	W2	Block	Tan/White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	2	208A	Classroom 212	Yes	W3	Block	Tan/White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	2	208A	Classroom 212	Yes	W4	Block	Tan/White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	2	208A	Classroom 212	Yes	Ceiling	Concrete	White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	2	208A	Classroom 212	Yes	Floor	12 x 12 Tile	Multi	N/A	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	2	208D	Classroom 211 and 212 Closet	Yes	W1	Block	White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	2	208D	Classroom 211 and 212 Closet	Yes	W1	Metal	Black	Cracking	4	0.8	Positive	None	N/A	Negative	Yes	No	No	No	Door Frame
1	2	208D	Classroom 211 and 212 Closet	Yes	W2	Block	White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	2	208D	Classroom 211 and 212 Closet	Yes	W3	Block	White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	2	208D	Classroom 211 and 212 Closet	Yes	W4	Block	White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	2	208D	Classroom 211 and 212 Closet	Yes	Ceiling	Drop Ceiling	White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	2	208D	Classroom 211 and 212 Closet	Yes	Floor	12 x 12 Tile	Brown	N/A	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	2	208B	Classroom 213	Yes	W1	Block	Tan	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	2	208B	Classroom 213	Yes	W1	Metal	Black	Cracking	4	0.4	Negative	None	N/A	Negative	Yes	No	No	No	Door Frame
1	2	208B	Classroom 213	Yes	W2	Plaster	Tan	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	2	208B	Classroom 213	Yes	W3	Block	Tan	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	2	208B	Classroom 213	Yes	W4	Plaster	Tan	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	2	208B	Classroom 213	Yes	Ceiling	Concrete	White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	2	208B	Classroom 213	Yes	Floor	12 x 12 Tile	Tan	N/A	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	2	208B	Classroom 213	Yes	Floor	9 x 9 Tile	Tan	N/A	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	2	208C	Classroom 214	Yes	W1	Block	Tan/White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	2	208C	Classroom 214	Yes	W1	Metal	Black	Chipping	3	0.7	Negative	None	N/A	Negative	Yes	No	No	No	Door Frame
1	2	208C	Classroom 214	Yes	W2	Block	Tan/White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	2	208C	Classroom 214	Yes	W3	Block	Tan/White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	2	208C	Classroom 214	Yes	W4	Metal	Tan	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	Univent
1	2	208C	Classroom 214	Yes	W4	Block	Tan/White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	2	208C	Classroom 214	Yes	W4	Plaster	Tan/White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	2	208C	Classroom 214	Yes	Ceiling	Concrete	White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	2	208C	Classroom 214	Yes	Floor	12 x 12 Tile	Multi	N/A	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	2	209	Staff Room next to Classroom 214	Yes	W1	Block	Tan/White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	2	209	Staff Room next to Classroom 214	Yes	W1	Metal	Black	None	0	N/A	N/A	None	N/A	Negative	N/A	No	N/A	N/A	Door Frame
1	2	209	Staff Room next to Classroom 214	Yes	W2	Block	Tan/White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	2	209	Staff Room next to Classroom 214	Yes	W2	Metal	Black	Cracking	4	0.8	Positive	None	N/A	Negative	Yes	No	No	No	Door Frame
1	2	209	Staff Room next to Classroom 214	Yes	W3	Block	Tan/White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	2	209	Staff Room next to Classroom 214	Yes	W4	Block	Tan/White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	2	209	Staff Room next to Classroom 214	Yes	Ceiling	Concrete	White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	2	209	Staff Room next to Classroom 214	Yes	Floor	12 x 12 Tile	Brown	N/A	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	2	211	Storage Closet next to Classroom 215	Yes	W1	Block	N/A	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	2	211	Storage Closet next to Classroom 215	Yes	W1	Metal	Black	Flaking	3	0.7	Negative	None	N/A	Negative	Yes	No	No	No	Door Frame
1	2	211	Storage Closet next to Classroom 215	Yes	W2	Block	N/A	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	2	211	Storage Closet next to Classroom 215	Yes	W3	Block	N/A	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	2	211	Storage Closet next to Classroom 215	Yes	W3	Metal	Tan	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	Univent
1	2	211	Storage Closet next to Classroom 215	Yes	W4	Block	N/A	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	2	211	Storage Closet next to Classroom 215	Yes	Ceiling	Concrete	N/A	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	2	211	Storage Closet next to Classroom 215	Yes	Floor	Concrete	N/A	N/A	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	2		Boy's Restroom next to Classroom 215	Yes	W1	Block	Tan	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	2		Boy's Restroom next to Classroom 216	Yes	W1	Metal	Black	Cracking	3	0.8	Positive	None	N/A	Negative	Yes	No	No	No	Door Frame
1	2		Boy's Restroom next to Classroom 217	Yes	W2	Block	Tan	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	2		Boy's Restroom next to Classroom 218	Yes	W3	Block	Tan	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	2		Boy's Restroom next to Classroom 219	Yes	W4	Block	Tan	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	
1	2		Boy's Restroom next to Classroom 220	Yes	Ceiling	Concrete	White	None	0										

			School District of Philadelphia																			
			Name of Inspector: Alexis Johnson/ Justine James		Lead Safe Certification Assessment Report								Date: 5/3/21-5/10/21									
			Inspection Company: BATT A		Ethel Allen								ULCS# 4440									
E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes			
1	2	212	Office Room 216	Yes	W3	Block	Tan/White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A				
1	2	212	Office Room 216	Yes	W4	Block	Tan/White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A				
1	2	212	Office Room 216	Yes	Ceiling	Concrete	White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A				
1	2	212	Office Room 216	Yes	Floor	12 x 12 Tile	Brown	N/A	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A				
1	2	SC	Stair C Next to Classroom 216	Yes	W1	Block	Multi	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A				
1	2	SC	Stair C Next to Classroom 216	Yes	W1	Metal	Black	None	0	N/A	N/A	None	N/A	Negative	N/A	No	N/A	N/A	Door Frame			
1	2	SC	Stair C Next to Classroom 216	Yes	W2	Block	Multi	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A				
1	2	SC	Stair C Next to Classroom 216	Yes	W2	Metal	Tan	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	Univent			
1	2	SC	Stair C Next to Classroom 216	Yes	W3	Block	Multi	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A				
1	2	SC	Stair C Next to Classroom 216	Yes	W4	Block	Multi	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A				
1	2	SC	Stair C Next to Classroom 216	Yes	W4	Metal	Tan	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	Univent			
1	2	SC	Stair C Next to Classroom 216	Yes	W4	Metal	Gray	None	0	N/A	N/A	None	N/A	Negative	N/A	No	N/A	N/A	Door Frame			
1	2	SC	Stair C Next to Classroom 216	Yes	Ceiling	Concrete	N/A	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A				
1	2	SC	Stair C Next to Classroom 216	Yes	Floor	Concrete	Gray	N/A	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A				
1	2	H2	Second Floor Main Hallway	Yes	W1	Block	Multi	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A				
1	2	H2	Second Floor Main Hallway	Yes	W2	Block	Multi	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A				
1	2	H2	Second Floor Main Hallway	Yes	W3	Block	Multi	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A				
1	2	H2	Second Floor Main Hallway	Yes	W3	Metal	Tan	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	(4) Univent			
1	2	H2	Second Floor Main Hallway	Yes	W4	Metal	Purple	Cracking	3	0	Negative	None	N/A	Negative	Yes	No	No	No	Pole			
1	2	H2	Second Floor Main Hallway	Yes	W4	Block	Multi	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A				
1	2	H2	Second Floor Main Hallway	Yes	W4	Metal	Tan	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	Univent			
1	2	H2	Second Floor Main Hallway	Yes	Ceiling	Drop Ceiling	White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A				
1	2	H2	Second Floor Main Hallway	Yes	Floor	12 x 12 Tile	Brown	N/A	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A				
1	B	ELV	Elevator	Yes	W1	Metal	Gray	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	Elevator			
1	B	ELV	Elevator	Yes	W2	Metal	Gray	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	Elevator			
1	B	ELV	Elevator	Yes	W3	Metal	Gray	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	Elevator			
1	B	ELV	Elevator	Yes	W4	Metal	Gray	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	Elevator			
1	B	ELV	Elevator	Yes	Ceiling	Metal	Gray	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	Elevator			
1	B	ELV	Elevator	Yes	Floor	12 x 12 Tile	Multi	N/A	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A				
1	B	1	Boiler Room	No	W1	Block	N/A	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A				
1	B	1	Boiler Room	No	W2	Block	N/A	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A				
1	B	1	Boiler Room	No	W3	Block	N/A	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A				
1	B	1	Boiler Room	No	W4	Block	N/A	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A				
1	B	1	Boiler Room	No	W4	Metal	Brown	Cracking	5	-0.1	Negative	None	N/A	Negative	Yes	No	No	No	(2) Door Frame			
1	B	1	Boiler Room	No	W4	Metal	Brown	Cracking	10	-0.2	Negative	None	N/A	Negative	Yes	No	No	No	(4) Doors			
1	B	1	Boiler Room	No	Ceiling	Concrete	N/A	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A				
1	B	1	Boiler Room	No	Floor	Concrete	N/A	N/A	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A				
1	B	001A	Building Engineer's Office	Yes	W1	Block	Multi	N/A	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A				
1	B	001A	Building Engineer's Office	Yes	W1	Metal	Brown	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	Door Frame			
1	B	001A	Building Engineer's Office	Yes	W2	Block	Multi	Cracking	3	0.1	Negative	None	N/A	Negative	Yes	No	No	No				
1	B	001A	Building Engineer's Office	Yes	W3	Block	Multi	Chipping	2	0.3	Negative	None	N/A	Negative	Yes	No	No	No				
1	B	001A	Building Engineer's Office	Yes	W4	Block	Multi	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A				
1	B	001A	Building Engineer's Office	Yes	Ceiling	Concrete	N/A	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A				
1	B	001A	Building Engineer's Office	Yes	Floor	12 x 12 Tile	Brown	N/A	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A				
1	B	001B	Pump Room next to Boiler Room	No	W1	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A		N/A	No	N/A	N/A				
1	B	001B	Pump Room next to Boiler Room	No	W2	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A		N/A	No	N/A	N/A				
1	B	001B	Pump Room next to Boiler Room	No	W3	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A		N/A	No	N/A	N/A				
1	B	001B	Pump Room next to Boiler Room	No	W4	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A		N/A	No	N/A	N/A				
1	B	001B	Pump Room next to Boiler Room	No	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A		N/A	No	N/A	N/A				
1	B	001B	Pump Room next to Boiler Room	No	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A		N/A	No	N/A	N/A				
1	B	001C	Men's Restroom in Building Engineer's Office	Yes	W1	Block	White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A				
1	B	001C	Men's Restroom in Building Engineer's Office	Yes	W1	Metal	Brown	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	Door Frame			
1	B	001C	Men's Restroom in Building Engineer's Office	Yes	W2	Block	White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A				
1	B	001C	Men's Restroom in Building Engineer's Office	Yes	W3	Block	White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A				
1	B	001C	Men's Restroom in Building Engineer's Office	Yes	W4	Block	White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A				
1	B	001C	Men's Restroom in Building Engineer's Office	Yes	Ceiling	Plaster	White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A				
1	B	001C	Men's Restroom in Building Engineer's Office	Yes	Floor	Ceramic Tile	Multi	N/A	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A				
1	B	2	Room 2	Yes	W1	Block	Multi	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A				
1	B	2	Room 2	Yes	W1	Metal	Brown	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	Door Frame			
1	B	2	Room 2	Yes	W2	Block	Multi	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A				
1	B	2	Room 2	Yes	W3	Block	Multi	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A				
1	B	2	Room 2	Yes	W4	Block	Multi	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A				
1	B	2	Room 2	Yes	Ceiling	Concrete	N/A	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A				
1	B	2	Room 2	Yes	Floor	Concrete	N/A	N/A	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A				
1	B		Community Room - Building Engineer Storage	No	W1	Block	White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A				
1	B		Community Room - Building Engineer Storage	No	W1	Metal	Brown	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	Door Frame			
1	B		Community Room - Building Engineer Storage	No	W2	Block	White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A				
1	B		Community Room - Building Engineer Storage	No	W3	Block	White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A				
1	B		Community Room - Building Engineer Storage	No	W4	Block	White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A				
1	B		Community Room - Building Engineer Storage	No	Ceiling	Concrete	N/A	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A				
1	B		Community Room - Building Engineer Storage	No	Floor	12 x 12 Tile	Brown	N/A	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A				
1	B	3	Auditorium	Yes	W1	Block	Multi	Partially Inaccessible	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A				
1	B	3	Auditorium	yes	W1	Metal	Black	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	Door Frame			
1	B	3	Auditorium	Yes	W2	Block	Multi	Partially Inaccessible	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	Poor Lighting [BATT A AJ 05.07.2021]			

			School District of Philadelphia																	
			Name of Inspector: Alexis Johnson/ Justine James		Lead Safe Certification Assessment Report							Date: 5/3/21-5/10/21								
			Inspection Company: BATTA		Ethel Allen							ULCS# 4440								
E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes	
1	B	3	Auditorium	yes	W2	Concrete	Black	Partially Inaccessible	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	Poor Lighting [BATTAAJ 05.07.2021]	
1	B	3	Auditorium	Yes	W3	Block	Multi	Partially Inaccessible	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	Poor Lighting [BATTAAJ 05.07.2021]	
1	B	3	Auditorium	Yes	W4	Block	Multi	Partially Inaccessible	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	Poor Lighting [BATTAAJ 05.07.2021]	
1	B	3	Auditorium	Yes	Ceiling	Concrete	Multi	Partially Inaccessible	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	Poor Lighting [BATTAAJ 05.07.2021]	
1	B	3	Auditorium	Yes	Floor	12 x 12 Tile	Multi	N/A	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	Poor Lighting [BATTAAJ 05.07.2021]	
1	B	3A	Auditorium Stage	Yes	W1	Block	Tan	Partially Inaccessible	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	Poor Lighting [BATTAAJ 05.07.2021]	
1	B	3A	Auditorium Stage	Yes	W2	Block	Multi	Partially Inaccessible	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	Poor Lighting [BATTAAJ 05.07.2021]	
1	B	3A	Auditorium Stage	Yes	W3	Block	Multi	Flaking	25	0.1	Negative	None	N/A	Negative	Yes	No	No	No	Poor Lighting [BATTAAJ 05.07.2021]	
1	B	3A	Auditorium Stage	Yes	W4	Block	Multi	Partially Inaccessible	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	Poor Lighting [BATTAAJ 05.07.2021]	
1	B	3A	Auditorium Stage	Yes	Ceiling	Concrete	Multi	Partially Inaccessible	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	Poor Lighting [BATTAAJ 05.07.2021]	
1	B	3A	Auditorium Stage	Yes	Floor	12 x 12 Tile	Tan	N/A	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	Poor Lighting [BATTAAJ 05.07.2021]	
1	B	002A	Storage across from Auditorium	Yes	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		N/A	No	N/A	N/A	Inaccessible [BATTAAJ 05.07.21]	
1	B	002A	Storage across from Auditorium	Yes	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		N/A	No	N/A	N/A	Inaccessible [BATTAAJ 05.07.21]	
1	B	002A	Storage across from Auditorium	Yes	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		N/A	No	N/A	N/A	Inaccessible [BATTAAJ 05.07.21]	
1	B	002A	Storage across from Auditorium	Yes	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		N/A	No	N/A	N/A	Inaccessible [BATTAAJ 05.07.21]	
1	B	002A	Storage across from Auditorium	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		N/A	No	N/A	N/A	Inaccessible [BATTAAJ 05.07.21]	
1	B	002A	Storage across from Auditorium	Yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		N/A	No	N/A	N/A	Inaccessible [BATTAAJ 05.07.21]	
1	B	003A	Storage to left of Auditorium	Yes	W1	Block	Tan	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A		
1	B	003A	Storage to left of Auditorium	Yes	W1	Metal	Brown	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	Door Frame	
1	B	003A	Storage to left of Auditorium	Yes	W2	Block	Tan	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A		
1	B	003A	Storage to left of Auditorium	Yes	W3	Block	Tan	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A		
1	B	003A	Storage to left of Auditorium	Yes	W4	Block	Tan	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A		
1	B	003A	Storage to left of Auditorium	Yes	Ceiling	Plaster	White	Moisture Damage	75	-0.2	Negative	None	N/A	Negative	Yes	Yes	Yes	No	NAD previously	
1	B	003A	Storage to left of Auditorium	Yes	Floor	12 x 12 Tile	Tan	N/A	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A		
1	B	003B	Storage to right of stage	Yes	W1	Block	Tan	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A		
1	B	003B	Storage to right of stage	Yes	W1	Metal	Brown	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	Univent	
1	B	003B	Storage to right of stage	Yes	W1	Metal	Brown	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	Door Frame	
1	B	003B	Storage to right of stage	Yes	W2	Block	Tan	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A		
1	B	003B	Storage to right of stage	Yes	W3	Block	Tan	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A		
1	B	003B	Storage to right of stage	Yes	W4	Block	Tan	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A		
1	B	003B	Storage to right of stage	Yes	Ceiling	Concrete	White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A		
1	B	003B	Storage to right of stage	Yes	Floor	12 x 12 Tile	Tan	N/A	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A		
1	B		Electrical Room in Storage Room	no	W1	Block	N/A	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A		
1	B		Electrical Room in Storage Room	no	W2	Block	N/A	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A		
1	B		Electrical Room in Storage Room	no	W3	Block	N/A	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A		
1	B		Electrical Room in Storage Room	no	W4	Block	N/A	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A		
1	B		Electrical Room in Storage Room	no	Ceiling	Concrete	N/A	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A		
1	B		Electrical Room in Storage Room	no	Floor	Concrete	N/A	N/A	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A		
1	B	5	Elevator Machine Room	No	W1	Block	N/A	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A		
1	B	5	Elevator Machine Room	No	W1	Metal	Brown	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	Door Frame	
1	B	5	Elevator Machine Room	No	W2	Block	N/A	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A		
1	B	5	Elevator Machine Room	No	W3	Block	N/A	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A		
1	B	5	Elevator Machine Room	No	W4	Block	N/A	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A		
1	B	5	Elevator Machine Room	No	Ceiling	Concrete	N/A	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A		
1	B	5	Elevator Machine Room	No	Floor	Concrete	N/A	N/A	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A		
1	B	6	Staff Locker Room	Yes	W1	Block	White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A		
1	B	6	Staff Locker Room	Yes	W1	Metal	Brown	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	Door Frame	
1	B	6	Staff Locker Room	Yes	W2	Block	White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A		
1	B	6	Staff Locker Room	Yes	W3	Block	White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A		
1	B	6	Staff Locker Room	Yes	W4	Block	White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A		
1	B	6	Staff Locker Room	Yes	Ceiling	Concrete	N/A	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A		
1	B	6	Staff Locker Room	Yes	Floor	Concrete	N/A	N/A	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A		
1	B		Staff Locker Room - Bathroom	Yes	W1	Block	White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A		
1	B		Staff Locker Room - Bathroom	Yes	W1	Metal	Brown	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A	Door Frame	
1	B		Staff Locker Room - Bathroom	Yes	W2	Block	White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A		
1	B		Staff Locker Room - Bathroom	Yes	W3	Block	White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A		
1	B		Staff Locker Room - Bathroom	Yes	W4	Block	White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A		
1	B		Staff Locker Room - Bathroom	Yes	Ceiling	Concrete	White	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A		
1	B		Staff Locker Room - Bathroom	Yes	Floor	Ceramic Tile	Multi	N/A	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A		
1	B	HB1	Main Basement Hallway	Yes	W1	Block	Yellow	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A		
1	B	HB1	Main Basement Hallway	Yes	W2	Block	Yellow	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A		
1	B	HB1	Main Basement Hallway	Yes	W3	Block	Yellow	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A		
1	B	HB1	Main Basement Hallway	Yes	W4	Block	Yellow	Flaking	16	-0.1	Negative	None	N/A	Negative	Yes	No	No	No		
1	B	HB1	Main Basement Hallway	Yes	Ceiling	Concrete	N/A	None	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A		
1	B	HB1	Main Basement Hallway	Yes	Floor	Concrete	N/A	N/A	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A		
1	A	AT	Attic	No	W1	N/A	N/A	N/A	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A		
1	A	AT	Attic	No	W2	N/A	N/A	N/A	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A		
1	A	AT	Attic	No	W3	N/A	N/A	N/A	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A		
1	A	AT	Attic	No	W4	N/A	N/A	N/A	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A		
1	A	AT	Attic	No	Ceiling	N/A	N/A	N/A	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A		
1	A	AT	Attic	No	Floor	N/A	N/A	N/A	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A		
1	C	CS	Crawlspace in Basement	No	W1	N/A	N/A	N/A	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A		
1	C	CS	Crawlspace in Basement	No	W2	N/A	N/A	N/A	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A		
1	C	CS	Crawlspace in Basement	No	W3	N/A	N/A	N/A</												

					School District of Philadelphia															
			Name of Inspector: Alexis Johnson/ Justine James		Lead Safe Certification Assessment Report							Date: 5/3/21-5/10/21								
			Inspection Company: BATTA		Ethel Allen							ULCS# 4440								
E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes	
1	C	CS	Crawlspace in Basement	No	W4	N/A	N/A	N/A	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A		
1	C	CS	Crawlspace in Basement	No	Ceiling	N/A	N/A	N/A	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A		
1	C	CS	Crawlspace in Basement	No	Floor	N/A	N/A	N/A	0	N/A	N/A	None	N/A		N/A	No	N/A	N/A		