



			School District of Philadelphia																				
			Name of Inspector: Jen Drialo		Lead Safe Certification Assessment Report							Inspection Dates: 9/20/21-10/7/21											
			Inspection Company: Synertech, Inc.		Gideon ES School							ULCS# 4530											
E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate	Color	Damage	Damage amount (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes				
1	3	309A	Classroom 309 Closet	yes	Vent	Metal	White	Flaking	2	0	Negative	None	0	Negative	No	No	no	no					
1	3	309A	Classroom 309 Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Negative	No	No	no	no					
1	3	S33	Stairwell adjacent to Classroom 311	yes	W1	CMU	Tan	Chipping	2	0.07	Negative	None	0	Negative	No	No	no	no					
1	3	S33	Stairwell adjacent to Classroom 311	yes	W1	Concrete	Tan	Chipping	1	0.04	Negative	None	0	Negative	No	No	no	no					
1	3	S33	Stairwell adjacent to Classroom 311	yes	Door	Metal	Tan	Chipping	3	0	Negative	None	0	Negative	No	No	no	no					
1	3	S33	Stairwell adjacent to Classroom 311	yes	Door Frame	Metal	Tan	Chipping	1	0.12	Negative	None	0	Negative	No	No	no	no					
1	3	S33	Stairwell adjacent to Classroom 311	yes	W2	CMU	Tan	Chipping	1	0.15	Negative	None	0	Negative	No	No	no	no					
1	3	S33	Stairwell adjacent to Classroom 311	yes	Column	Concrete	Tan	Flaking	1	0.06	Negative	None	0	Negative	No	No	no	no					
1	3	S33	Stairwell adjacent to Classroom 311	yes	Radiator	Metal	Grey	Chipping	1	0.06	Negative	None	0	Negative	No	No	no	no					
1	3	S33	Stairwell adjacent to Classroom 311	yes	W3	CMU	Tan	Chipping	1	0.11	Negative	None	0	Negative	No	No	no	no					
1	3	S33	Stairwell adjacent to Classroom 311	yes	Baluster	Metal	Orange	Chipping	5	2.9	Positive	None	0	Negative	No	No	no	no					
1	3	S33	Stairwell adjacent to Classroom 311	yes	Column	Concrete	Tan	Flaking	2	0.04	Negative	None	0	Negative	No	No	no	no					
1	3	S33	Stairwell adjacent to Classroom 311	yes	W4	CMU	Tan	Chipping	1	0.04	Negative	None	0	Negative	No	No	no	no					
1	3	S33	Stairwell adjacent to Classroom 311	yes	Column	Concrete	Tan	Flaking	5	0.11	Negative	None	0	Negative	No	No	no	no					
1	3	S33	Stairwell adjacent to Classroom 311	yes	Radiator	Metal	Grey	Chipping	1	0.04	Negative	None	0	Negative	No	No	no	no					
1	3	S33	Stairwell adjacent to Classroom 311	yes	Ceiling	Concrete	Tan	Flaking	3	0.06	Negative	None	0	Negative	No	No	no	no					
1	3	S33	Stairwell adjacent to Classroom 311	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Negative	No	No	no	no					
1	3	S33	Stairwell adjacent to Classroom 311	yes	Open Stringer	Metal	Orange	Chipping	2	6	Positive	None	0	Negative	No	No	no	no					
1	3	S33	Stairwell adjacent to Classroom 311	yes	Wall Stringer	Metal	Grey	Chipping	1	6.8	Positive	None	0	Negative	No	No	no	no					
1	3	S33	Stairwell adjacent to Classroom 311	yes	Baluster	Metal	Orange	Chipping	6	4	Positive	None	0	Negative	No	No	no	no					
1	3	S33	Stairwell adjacent to Classroom 311	yes	Newel Post	Metal	Orange	Friction	5	5.7	Positive	None	0	Negative	No	No	no	no					
1	3	S33	Stairwell adjacent to Classroom 311	yes	Riser	Metal	Grey	Chipping	5	2.7	Positive	None	0	Negative	No	No	no	no					
1	3	S33	Stairwell adjacent to Classroom 311	yes	Handrail	Metal	Orange	Friction	10	3.7	Positive	None	0	Negative	No	No	no	no					
1	3	H38A	Storage 6	yes	W1	CMU	Tan	None	0	N/A	N/A	None	0	Negative	No	No	no	no					
1	3	H38A	Storage 6	yes	Door Frame	Metal	Tan	Chipping	3	0.26	Negative	None	0	Negative	No	No	no	no					
1	3	H38A	Storage 6	yes	W2	CMU	Tan	None	0	N/A	N/A	None	0	Negative	No	No	no	no					
1	3	H38A	Storage 6	yes	W3	CMU	Tan	Chipping	2	0	Negative	None	0	Negative	No	No	no	no					
1	3	H38A	Storage 6	yes	W4	CMU	Tan	None	0	N/A	Negative	None	0	Negative	No	No	no	no					
1	3	H38A	Storage 6	yes	Ceiling	Concrete	White	None	0	N/A	N/A	None	0	Negative	No	No	no	no					
1	3	H38A	Storage 6	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Negative	No	No	no	no					
1	3	312	Tech Room 312	yes	W1	CMU	Grey	Flaking	2	0	Negative	None	0	Negative	No	No	no	no					
1	3	312	Tech Room 312	yes	Door Frame	Metal	Tan	Chipping	1	0.2	Negative	None	0	Negative	No	No	no	no					
1	3	312	Tech Room 312	yes	W2	CMU	Grey	Chipping	1	0	Negative	None	0	Negative	Partially Inaccessible	No	no	no					
1	3	312	Tech Room 312	yes	W3	CMU	Grey	Chipping	4	0	Negative	None	0	Negative	No	No	no	no					
1	3	312	Tech Room 312	yes	Univent Cabinet Top	Wood	Brown	Chipping	5	0.24	Negative	None	0	Negative	No	No	no	no					
1	3	312	Tech Room 312	yes	Univent	Metal	Brown	Chipping	10	0.21	Negative	None	0	Negative	No	No	no	no					
1	3	312	Tech Room 312	yes	Shelves	Wood	Brown	Friction	6	0.16	Negative	None	0	Negative	No	No	no	no					
1	3	312	Tech Room 312	yes	W4	CMU	Grey	Chipping	1	0	Negative	None	0	Negative	No	No	no	no					
1	3	312	Tech Room 312	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Negative	No	No	no	no					
1	3	312	Tech Room 312	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Negative	No	No	no	no					
1	3	312B	312 Closet by entrance	yes	Door Frame	Metal	Green	Chipping	1	0.14	Negative	None	0	Negative	No	No	no	no					
1	3	312B	312 Closet by entrance	yes	Shelves	Wood	Green	None	0	N/A	N/A	None	0	Negative	No	No	no	no					
1	3	312B	312 Closet by entrance	yes	Cabinet Wall	Wood	Green	None	0	N/A	N/A	None	0	Negative	No	No	no	no					
1	3	312B	312 Closet by entrance	yes	W2	CMU	Green	None	0	N/A	N/A	None	0	Negative	No	No	no	no					
1	3	312B	312 Closet by entrance	yes	W3	CMU	Green	None	0	N/A	N/A	None	0	Negative	No	No	no	no					
1	3	312B	312 Closet by entrance	yes	W4	CMU	Green	None	0	N/A	N/A	None	0	Negative	No	No	no	no					
1	3	312B	312 Closet by entrance	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Negative	No	No	no	no					
1	3	312A	312 Large Closet	yes	W1	CMU	Tan	Chipping	1	0	Negative	None	0	Negative	Partially Inaccessible	No	no	no					
1	3	312A	312 Large Closet	yes	Door Frame	Metal	Tan	Chipping	6	0.23	Negative	None	0	Negative	No	No	no	no					

			School District of Philadelphia																	
			Name of Inspector: Jen Drialo		Lead Safe Certification Assessment Report							Inspection Dates: 9/20/21-10/7/21								
			Inspection Company: Synertech, Inc.		Gideon ES School							ULCS# 4530								
E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate	Color	Damage	Damage amount (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes	
1	3	312A	312 Large Closet	yes	W2	CMU	Green	Flaking	20	0	Negative	None	0	Negative	No	No	no	no		
1	3	312A	312 Large Closet	yes	W3	CMU	Tan	Flaking	3	0	Negative	None	0	Negative	No	No	no	no		
1	3	312A	312 Large Closet	yes	W4	CMU	Tan	Flaking	3	0	Negative	None	0	Negative	No	No	no	no		
1	3	312A	312 Large Closet	yes	Ceiling	Concrete	Tan	Flaking	100	0.06	Negative	None	0	Negative	No	No	no	no		
1	3	312A	312 Large Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Negative	No	No	no	no		
1	3	308	Classroom 308	yes	W1	CMU	White	Chipping	1	0	Negative	None	0	Negative	No	No	no	no		
1	3	308	Classroom 308	yes	Door Frame	Metal	Tan	Chipping	4	0.2	Negative	None	0	Negative	No	No	no	no		
1	3	308	Classroom 308	yes	W2	CMU	White	Chipping	2	0	Negative	None	0	Negative	No	No	no	no		
1	3	308	Classroom 308	yes	W3	CMU	White	Chipping	4	0	Negative	None	0	Negative	No	No	no	no		
1	3	308	Classroom 308	yes	Univent Cabinet Top	Wood	Gray	Chipping	5	0.24	Negative	None	0	Negative	No	No	no	no		
1	3	308	Classroom 308	yes	Univent	Metal	Grey	Chipping	5	0.21	Negative	None	0	Negative	No	No	no	no		
1	3	308	Classroom 308	yes	Shelves	Wood	Grey	Chipping	6	0.16	Negative	None	0	Negative	No	No	no	no		
1	3	308	Classroom 308	yes	W4	CMU	White	Chipping	1	0	Negative	None	0	Negative	No	No	no	no		
1	3	308	Classroom 308	yes	Ceiling	Concrete	White	None	0	N/A	N/A	None	0	Negative	No	No	no	no		
1	3	308	Classroom 308	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Negative	No	No	no	no		
1	3	308A	Classroom 308 Closet	yes	Door Frame	Metal	Tan	Chipping	2	0	Negative	None	0	Negative	No	No	no	no		
1	3	308A	Classroom 308 Closet	yes	Shelves	Wood	Brown	Friction	2	0.7	Positive	None	0	Negative	Partially Inaccessible	No	no	no	Several shelf paint chip samples were taken and the results were positive. Shelves in the classroom closets should be treated as homogenous.	
1	3	308A	Classroom 308 Closet	yes	Cabinet Wall	Wood	Brown	Chipping	2	1	Positive	None	0	Negative	No	No	no	no		
1	3	308A	Classroom 308 Closet	yes	W2	CMU	Brown	Chipping	2	0	Negative	None	0	Negative	No	No	no	no		
1	3	308A	Classroom 308 Closet	yes	W3	CMU	Brown	Chipping	1	0	Negative	None	0	Negative	No	No	no	no		
1	3	308A	Classroom 308 Closet	yes	W4	CMU	Brown	Chipping	1	0	Negative	None	0	Negative	No	No	no	no		
1	3	308A	Classroom 308 Closet	yes	Vent	Metal	Brown	Flaking	2	0	Negative	None	0	Negative	No	No	no	no		
1	3	308A	Classroom 308 Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Negative	No	No	no	no		
1	3	313	Storage 5	yes	W1	CMU	Tan	None	0	N/A	N/A	None	0	Negative	No	No	no	no		
1	3	313	Storage 5	yes	Door Frame	Metal	Tan	Chipping	3	0.26	Negative	None	0	Negative	No	No	no	no		
1	3	313	Storage 5	yes	W2	CMU	Tan	None	0	N/A	N/A	None	0	Negative	No	No	no	no		
1	3	313	Storage 5	yes	W3	CMU	Tan	Chipping	2	0	Negative	None	0	Negative	No	No	no	no		
1	3	313	Storage 5	yes	W4	CMU	Tan	None	0	N/A	Negative	None	0	Negative	No	No	no	no		
1	3	313	Storage 5	yes	Ceiling	Concrete	White	Chipping	2	0.03	Negative	None	0	Negative	No	No	no	no		
1	3	313	Storage 5	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Negative	No	No	no	no		
1	3	314	Girl's Restroom	yes	W1	CMU	Tan	Chipping	1	0	Negative	None	0	Negative	No	No	no	no		
1	3	314	Girl's Restroom	yes	Door Frame	Metal	Tan	Chipping	2	0.3	Negative	None	0	Negative	No	No	no	no		
1	3	314	Girl's Restroom	yes	W2	CMU	Tan	Chipping	2	0	Negative	None	0	Negative	No	No	no	no		
1	3	314	Girl's Restroom	yes	Transite Stall	Transite	Grey	None	N/A	0	Negative	None	0	Negative	No	No	no	no		
1	3	314	Girl's Restroom	yes	W3	CMU	Tan	Chipping	1	0	Negative	None	0	Negative	No	No	no	no		
1	3	314	Girl's Restroom	yes	Column	Concrete	White	Efflorescence	2	1.4	Positive	None	0	Negative	No	Unknown	no	no		
1	3	314	Girl's Restroom	yes	Univent	Metal	Grey	Chipping	3	0.16	Negative	None	0	Negative	No	No	no	no		
1	3	314	Girl's Restroom	yes	W4	CMU	Tan	Chipping	5	0	Negative	None	0	Negative	No	No	no	no		
1	3	314	Girl's Restroom	yes	Ceiling	Concrete	White	Flaking	100	0.02	Negative	None	0	Negative	No	No	no	no		
1	3	314	Girl's Restroom	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Negative	No	No	no	no		
1	3	314A	Custodial Closet next to Girl's Restroom	no	W1	CMU	Blue	Flaking	1	0	Negative	None	0	Negative	No	No	no	no		
1	3	314A	Custodial Closet next to Girl's Restroom	no	Door Frame	Metal	Blue	Chipping	3	0.12	Negative	None	0	Negative	No	No	no	no		
1	3	314A	Custodial Closet next to Girl's Restroom	no	W2	CMU	Blue	None	0	N/A	N/A	None	0	Negative	No	No	no	no		
1	3	314A	Custodial Closet next to Girl's Restroom	no	W3	CMU	Blue	Chipping	4	0	Negative	None	0	Negative	No	No	no	no		
1	3	314A	Custodial Closet next to Girl's Restroom	no	W4	CMU	Blue	None	0	0	Negative	None	0	Negative	No	No	no	no		
1	3	314A	Custodial Closet next to Girl's Restroom	no	Ceiling	Concrete	White	Flaking	2	0.03	Negative	None	0	Negative	No	No	no	no		
1	3	314A	Custodial Closet next to Girl's Restroom	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Negative	No	No	no	no		
1	3	314B	Server Closet next to Boy's Restroom	yes	W1	CMU	Tan	Chipping	1	0	Negative	None	0	Negative	No	No	no	no		
1	3	314B	Server Closet next to Boy's Restroom	yes	Door Frame	Metal	Tan	Chipping	6	0.19	Negative	None	0	Negative	No	No	no	no		
1	3	314B	Server Closet next to Boy's Restroom	yes	Column	Concrete	Tan	Chipping	2	0.05	Negative	None	0	Negative	No	No	no	no		
1	3	314B	Server Closet next to Boy's Restroom	yes	W2	CMU	Tan	None	0	N/A	N/A	None	0	Negative	Partially Inaccessible	No	no	no		
1	3	314B	Server Closet next to Boy's Restroom	yes	W3	CMU	Tan	Flaking	5	0	Negative	None	0	Negative	No	No	no	no		
1	3	314B	Server Closet next to Boy's Restroom	yes	W4	CMU	Tan	Flaking	1	0	Negative	None	0	Negative	No	No	no	no		
1	3	314B	Server Closet next to Boy's Restroom	yes	Ceiling	Concrete	Tan	Flaking	10	0.03	Negative	None	0	Negative	No	No	no	no		

			School District of Philadelphia																								
			Name of Inspector: Jen Drialo		Lead Safe Certification Assessment Report																						
			Inspection Company: Synertech, Inc.		Gideon ES School																						
E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate	Color	Damage	Damage amount (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes								
1	3	314B	Server Closet next to Boy's Restroom	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Negative	No	No	no	no									
1	3	315	Boy's Restroom	yes	W1	CMU	Tan	Chipping	1	0	Negative	None	0	Negative	No	No	no	no									
1	3	315	Boy's Restroom	yes	Door Frame	Metal	Tan	Chipping	2	0.26	Negative	None	0	Negative	No	No	no	no									
1	3	315	Boy's Restroom	yes	Push Bar	Metal	Grey	Chipping	1	0	Negative	None	0	Negative	No	No	no	no									
1	3	315	Boy's Restroom	yes	W2	CMU	Tan	Chipping	2	0	Negative	None	0	Negative	No	No	no	no									
1	3	315	Boy's Restroom	yes	Transite Stall	Transite	Grey	None	N/A	0	Negative	None	0	Negative	No	No	no	no									
1	3	315	Boy's Restroom	yes	W3	CMU	Tan	Chipping	1	0	Negative	None	0	Negative	No	No	no	no									
1	3	315	Boy's Restroom	yes	Column	Concrete	Grey	Flaking	2	0.08	inconclusive	None	0	Negative	No	No	no	no	Paint Chip Sampled; 1.2% Pb/Weight								
1	3	315	Boy's Restroom	yes	Column	Concrete	Tan	Flaking	4	0.7	inconclusive	None	0	Negative	No	No	no	no									
1	3	315	Boy's Restroom	yes	Column	Concrete	White	Flaking	2	0.03	inconclusive	None	0	Negative	No	No	no	no	Paint Chip Sampled; 0.44% Pb/Weight								
1	3	315	Boy's Restroom	yes	Univent	Metal	Grey	Chipping	1	0.1	Negative	None	0	Negative	No	No	no	no									
1	3	315	Boy's Restroom	yes	W4	CMU	Tan	Chipping	5	0	Negative	None	0	Negative	No	No	no	no									
1	3	315	Boy's Restroom	yes	Ceiling	Concrete	White	Flaking	100	0.02	Negative	None	0	Negative	No	No	no	no									
1	3	315	Boy's Restroom	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Negative	No	No	no	no									
1	3	307	Classroom 307 Computer Lab	yes	W1	CMU	Tan	Chipping	2	0	Negative	None	0	Negative	No	No	no	no									
1	3	307	Classroom 307 Computer Lab	yes	Door Frame	Metal	Tan	Chipping	2	0.3	Negative	None	0	Negative	No	No	no	no									
1	3	307	Classroom 307 Computer Lab	yes	W2	CMU	Tan	Chipping	8	0	Negative	None	0	Negative	No	No	no	no									
1	3	307	Classroom 307 Computer Lab	yes	W3	CMU	Tan	Chipping	3	0	Negative	None	0	Negative	No	No	no	no									
1	3	307	Classroom 307 Computer Lab	yes	Univent	Metal	Tan	Chipping	5	0.24	Negative	None	0	Negative	No	No	no	no									
1	3	307	Classroom 307 Computer Lab	yes	Cabinet Top	Wood	Tan	Chipping	10	0.25	Negative	None	0	Negative	No	No	no	no									
1	3	307	Classroom 307 Computer Lab	yes	Shelves	Metal	Tan	Chipping	2	0.09	Negative	None	0	Negative	No	No	no	no									
1	3	307	Classroom 307 Computer Lab	yes	Column	Concrete	Tan	Flaking	15	0.02	Negative	None	0	Negative	No	No	no	no									
1	3	307	Classroom 307 Computer Lab	yes	W4	CMU	Tan	Flaking	2	0	Negative	None	0	Negative	No	No	no	no									
1	3	307	Classroom 307 Computer Lab	yes	Ceiling	Concrete	White	Flaking	10	0.05	Negative	None	0	Negative	No	No	no	no									
1	3	307	Classroom 307 Computer Lab	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Negative	No	No	no	no									
1	3	307A	Classroom 307 Closet	yes	Door Frame	Metal	Tan	Chipping	2	0.27	Negative	None	0	Negative	No	No	no	no									
1	3	307A	Classroom 307 Closet	yes	W2	CMU	Tan	Chipping	1	0	Negative	None	0	Negative	Partially Inaccessible	No	no	no									
1	3	307A	Classroom 307 Closet	yes	Partition	Wood	Tan	Chipping	1	1	Positive	None	0	Negative	No	No	no	no									
1	3	307A	Classroom 307 Closet	yes	Shelves	Wood	Tan	Friction	2	0.7	Positive	None	0	Negative	No	No	no	no	Several shelf paint chip samples were taken and the results were positive. Shelves in the classroom closets should be treated as homogenous.								
1	3	307A	Classroom 307 Closet	yes	W2	CMU	White	Chipping	2	0	Negative	None	0	Negative	No	No	no	no									
1	3	307A	Classroom 307 Closet	yes	W3	CMU	Tan	Chipping	2	0	Negative	None	0	Negative	Partially Inaccessible	No	no	no									
1	3	307A	Classroom 307 Closet	yes	W3	CMU	White	Chipping	1	0	Negative	None	0	Negative	No	No	no	no									
1	3	307A	Classroom 307 Closet	yes	W4	CMU	Tan	Chipping	1	0	Negative	None	0	Negative	Partially Inaccessible	No	no	no									
1	3	307A	Classroom 307 Closet	yes	W4	CMU	White	Chipping	1	0	Negative	None	0	Negative	No	No	no	no									
1	3	307A	Classroom 307 Closet	yes	Ceiling	Wood	Tan	None	0	N/A	N/A	None	0	Negative	No	No	no	no									
1	3	307A	Classroom 307 Closet	yes	Vent	Metal	White	Chipping	2	0.4	Negative	None	0	Negative	No	No	no	no									
1	3	307A	Classroom 307 Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Negative	No	No	no	no									
1	3	S35	Stairwell across from Classroom 307	yes	W1	CMU	Tan	Chipping	1	0	Negative	None	0	Negative	No	No	no	no									
1	3	S35	Stairwell across from Classroom 307	yes	Door	Metal	Tan	Chipping	4	0	Negative	None	0	Negative	No	No	no	no									
1	3	S35	Stairwell across from Classroom 307	yes	Door Frame	Metal	Tan	Chipping	1	0.14	Negative	None	0	Negative	No	No	no	no									
1	3	S35	Stairwell across from Classroom 307	yes	W2	CMU	Tan	Flaking	4	0	Negative	None	0	Negative	No	No	no	no									
1	3	S35	Stairwell across from Classroom 307	yes	Column	Concrete	Tan	Flaking	2	0.03	Negative	None	0	Negative	No	No	no	no									
1	3	S35	Stairwell across from Classroom 307	yes	W3	CMU	Tan	None	0	N/A	N/A	None	0	Negative	No	No	no	no									
1	3	S35	Stairwell across from Classroom 307	yes	Door	Metal	Tan	Chipping	1	0	Negative	None	0	Negative	No	No	no	no									
1	3	S35	Stairwell across from Classroom 307	yes	Door Frame	Metal	Tan	Chipping	2	0.22	Negative	None	0	Negative	No	No	no	no									
1	3	S35	Stairwell across from Classroom 307	yes	W4	CMU	Tan	Chipping	3	0	Negative	None	0	Negative	No	No	no	no									
1	3	S35	Stairwell across from Classroom 307	yes	Column	Concrete	Tan	Flaking	4	0.05	Negative	None	0	Negative	No	No	no	no									
1	3	S35	Stairwell across from Classroom 307	yes	Radiator	Metal	Grey	Chipping	2	0.06	Negative	None	0	Negative	No	No	no	no									
1	3	S35	Stairwell across from Classroom 307	yes	Ceiling	Metal	White	Flaking	6	2.7	Positive	None	0	Negative	No	Unknown	no	no									
1	3	S35	Stairwell across from Classroom 307	yes	Ceiling	Concrete	White	Efflorescence	5	0.02	Negative	None	0	Negative	No	No	no	no									

			School District of Philadelphia																								
			Name of Inspector: Jen Drialo		Lead Safe Certification Assessment Report																						
			Inspection Company: Synertech, Inc.		Gideon ES School																						
E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate	Color	Damage	Damage amount (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes								
1	3	S35	Stairwell across from Classroom 307	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Negative	No	No	no	no									
1	3	S35	Stairwell across from Classroom 307	yes	Baluster	Metal	Orange	Chipping	8	4	Positive	None	0	Negative	No	No	no	no	At Window								
1	3	S35	Stairwell across from Classroom 307	yes	Riser	Concrete	Grey	Chipping	1	3.1	Positive	None	0	Negative	No	No	no	no									
1	3	S35	Stairwell across from Classroom 307	yes	Handrail	Metal	Orange	Chipping	10	3.4	Positive	None	0	Negative	No	No	no	no									
1	3	306	Classroom 306	yes	W1	CMU	Tan	Chipping	2	0	Negative	None	0	Negative	No	No	no	no									
1	3	306	Classroom 306	yes	Door Frame	Metal	Tan	Chipping	2	0.16	Negative	None	0	Negative	No	No	no	no									
1	3	306	Classroom 306	yes	W2	CMU	Tan	None	0	0	Negative	None	0	Negative	No	No	no	no									
1	3	306	Classroom 306	yes	W3	CMU	Tan	Chipping	3	0	Negative	None	0	Negative	No	No	no	no									
1	3	306	Classroom 306	yes	Univent	Metal	Tan	Chipping	4	0.15	Negative	None	0	Negative	No	No	no	no									
1	3	306	Classroom 306	yes	Cabinet Top	Wood	Tan	Chipping	3	0.25	Negative	None	0	Negative	No	No	no	no									
1	3	306	Classroom 306	yes	Shelves	Metal	Tan	Chipping	2	0.12	Negative	None	0	Negative	No	No	no	no									
1	3	306	Classroom 306	yes	Column	Concrete	Tan	Flaking	1	0	Negative	None	0	Negative	No	No	no	no									
1	3	306	Classroom 306	yes	W4	CMU	Tan	Chipping	1	0	Negative	None	0	Negative	No	No	no	no									
1	3	306	Classroom 306	yes	Ceiling	Concrete	White	Flaking	5	0	Negative	None	0	Negative	No	No	no	no									
1	3	306	Classroom 306	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Negative	No	No	no	no									
1	3	306A	Classroom 306 Closet	yes	W2	CMU	Green	Chipping	1	0	Negative	None	0	Negative	Partially Inaccessible	No	no	no									
1	3	306A	Classroom 306 Closet	yes	Partition	Wood	Green	Chipping	1	1.5	Positive	None	0	Negative	No	No	no	no									
1	3	306A	Classroom 306 Closet	yes	Shelves	Wood	Green	Friction	2	0.6	Positive	None	0	Negative	No	No	no	no	Paint Chip Sampled; 0.90 Pb/weight								
1	3	306A	Classroom 306 Closet	yes	W2	CMU	White	Chipping	2	0	Negative	None	0	Negative	No	No	no	no									
1	3	306A	Classroom 306 Closet	yes	W3	CMU	Green	Chipping	2	0	Negative	None	0	Negative	Partially Inaccessible	No	no	no									
1	3	306A	Classroom 306 Closet	yes	W3	CMU	White	Chipping	1	0	Negative	None	0	Negative	No	No	no	no									
1	3	306A	Classroom 306 Closet	yes	W4	CMU	Green	Chipping	1	0	Negative	None	0	Negative	Partially Inaccessible	No	no	no									
1	3	306A	Classroom 306 Closet	yes	W4	CMU	White	Chipping	1	0	Negative	None	0	Negative	No	No	no	no									
1	3	306A	Classroom 306 Closet	yes	Pipe	Metal	Tan	Chipping	2	0.3	Negative	None	0	Negative	No	No	no	no									
1	3	306A	Classroom 306 Closet	yes	Ceiling	Wood	Green	None	0	N/A	N/A	None	0	Negative	No	No	no	no									
1	3	306A	Classroom 306 Closet	yes	Vent	Metal	White	Chipping	2	0.4	Negative	None	0	Negative	No	No	no	no									
1	3	306A	Classroom 306 Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Negative	No	No	no	no									
1	3	316	Cafeteria / Gym	yes	W1	CMU	Tan	Chipping	1	0	Negative	None	0	Negative	No	No	no	no									
1	3	316	Cafeteria / Gym	yes	Door	Metal	Tan	Chipping	1	0	Negative	None	0	Negative	No	No	no	no									
1	3	316	Cafeteria / Gym	yes	Door Frame	Metal	Tan	Chipping	1	0.15	Negative	None	0	Negative	No	No	no	no									
1	3	316	Cafeteria / Gym	yes	Push Bar	Metal	Grey	Chipping	4	0	Negative	None	0	Negative	No	No	no	no									
1	3	316	Cafeteria / Gym	yes	Radiator	Metal	Blue	Chipping	1	0.1	Negative	None	0	Negative	No	No	no	no									
1	3	316	Cafeteria / Gym	yes	W2	CMU	Tan	Chipping	2	0	Negative	None	0	Negative	No	No	no	no									
1	3	316	Cafeteria / Gym	yes	Door	Metal	Tan	Chipping	1	0	Negative	None	0	Negative	No	No	no	no									
1	3	316	Cafeteria / Gym	yes	Door Frame	Metal	Tan	Chipping	1	0.15	Negative	None	0	Negative	No	No	no	no									
1	3	316	Cafeteria / Gym	yes	Push Bar	Metal	Grey	Chipping	1	0	Negative	None	0	Negative	No	No	no	no									
1	3	316	Cafeteria / Gym	yes	W3	CMU	Tan	None	0	0	Negative	None	0	Negative	No	No	no	no									
1	3	316	Cafeteria / Gym	yes	Door	Metal	Tan	Chipping	1	0	Negative	None	0	Negative	No	No	no	no									
1	3	316	Cafeteria / Gym	yes	Door Frame	Metal	Tan	Chipping	1	0.13	Negative	None	0	Negative	No	No	no	no									
1	3	316	Cafeteria / Gym	yes	Column	Concrete	Blue	Chipping	2	0.12	Negative	None	0	Negative	No	No	no	no									
1	3	316	Cafeteria / Gym	yes	W4	CMU	Tan	Chipping	2	0	Negative	None	0	Negative	No	No	no	no									
1	3	316	Cafeteria / Gym	yes	W4	CMU	White	None	N/A	0	Negative	None	0	Negative	No	No	no	no									
1	3	316	Cafeteria / Gym	yes	Cafe Serving Window Frame	Metal	Grey	Chipping	4	0.22	Negative	None	0	Negative	No	No	no	no									
1	3	316	Cafeteria / Gym	yes	Wall Board	Wood	Black	Chipping	1	0	Negative	None	0	Negative	No	No	no	no									
1	3	316	Cafeteria / Gym	yes	Wall Board	Wood	Blue	Chipping	2	0	Negative	None	0	Negative	No	No	no	no									
1	3	316	Cafeteria / Gym	yes	Wall Board	Wood	Yellow	Chipping	1	0	Negative	None	0	Negative	No	No	no	no									
1	3	316	Cafeteria / Gym	yes	Basketball Backboard	Wood	Orange	Chipping	3	0.1	Negative	None	0	Negative	No	No	no	no									
1	3	316	Cafeteria / Gym	yes	Basketball Backboard	Wood	Light Blue	Chipping	2	0.11	Negative	None	0	Negative	No	No	no	no									
1	3	316	Cafeteria / Gym	yes	Basketball Backboard	Wood	Dark Blue	Chipping	1	0.1	Negative	None	0	Negative	No	No	no	no									
1	3	316	Cafeteria / Gym	yes	Basketball Backboard	Wood	Yellow	Chipping	1	0.1	Negative	None	0	Negative	No	No	no	no									
1	3	316	Cafeteria / Gym	yes	Radiator	Metal	Tan	Flaking	4	0.12	Negative	None	0	Negative	No	No	no	no									
1	3	316	Cafeteria / Gym	yes	Recessed Radiator Back Panel	Metal	Tan	Chipping	12	0.4	Negative	None	0	Negative	No	No	no	no									
1	3	316	Cafeteria / Gym	yes	Column	Concrete	White	Flaking	1	0.01	Negative	None	0	Negative	No	No	no	no									
1	3	316	Cafeteria / Gym	yes	Column	Concrete	Tan	Flaking	1	0.01	Negative	None	0	Negative	No	No	no	no									
1	3	316	Cafeteria / Gym	yes	Ceiling	Concrete	White	Efflorescence	6	0	Negative	None	0	Negative	No	No	no	no									
1	3	316	Cafeteria / Gym	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Negative	No	No	no	no									
1	3	316	Cafeteria / Gym	yes	Radiator Covers	Metal	White	Chipping	14	0.4	Negative	None	0	Negative	No	No	no	no	7 Total								
1	3	316	Cafeteria / Gym	yes	Radiator Covers	Metal	Blue	Chipping	12	0.4	Negative	None	0	Negative	No	No	no	no	6 Total								
1	3	316B	Gym Office	yes	W1	CMU	Tan	Chipping	1	0	Negative	None	0	Negative	No	No	no	no									

			School District of Philadelphia																				
			Name of Inspector: Jen Drialo		Lead Safe Certification Assessment Report											Inspection Dates: 9/20/21-10/7/21							
			Inspection Company: Synertech, Inc.		Gideon ES School											ULCS# 4530							
E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate	Color	Damage	Damage amount (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes				
1	3	316B	Gym Office	yes	W2	CMU	Tan	Efflorescence	4	0	Negative	None	0	Negative	Partially Inaccessible	Unknown	no	no					
1	3	316B	Gym Office	yes	Pipe	Metal	White	Flaking	1	0.24	Negative	None	0	Negative	No	No	no	no					
1	3	316B	Gym Office	yes	W3	CMU	Tan	None	0	0	Negative	None	0	Negative	No	No	no	no					
1	3	316B	Gym Office	yes	W4	CMU	Tan	Chipping	2	0	Negative	None	0	Negative	No	No	no	no					
1	3	316B	Gym Office	yes	W4	CMU	White	None	N/A	0	Negative	None	0	Negative	No	No	no	no					
1	3	316B	Gym Office	yes	Radiator	Metal	Tan	Flaking	5	0.25	Negative	None	0	Negative	No	No	no	no					
1	3	316B	Gym Office	yes	Column	Concrete	White	Flaking	1	0.01	Negative	None	0	Negative	No	No	no	no					
1	3	316B	Gym Office	yes	Column	Concrete	Tan	Flaking	1	0.01	Negative	None	0	Negative	No	No	no	no					
1	3	316B	Gym Office	yes	Ceiling	Concrete	White	Efflorescence	6	0	Negative	None	0	Negative	No	No	no	no					
1	3	316B	Gym Office	yes	Floor	Gym	N/A	N/A	N/A	N/A	N/A	None	0	Negative	No	No	no	no					
1	3	316K	Kitchen	yes	W1	CMU	White	Flaking	1	0	Negative	None	0	Negative	No	No	no	no					
1	3	316K	Kitchen	yes	Glazed Terracotta Block	Concrete	Green	None	N/A	N/A	N/A	None	0	Negative	No	No	no	no					
1	3	316K	Kitchen	yes	Door	Metal	Tan	Chipping	1	0	Negative	None	0	Negative	No	No	no	no					
1	3	316K	Kitchen	yes	Door Frame	Metal	Tan	Friction	10	0.25	Negative	None	0	Negative	No	No	no	no					
1	3	316K	Kitchen	yes	W2	CMU	White	None	1	0	Negative	None	0	Negative	No	No	no	no					
1	3	316K	Kitchen	yes	Door	Metal	Tan	Chipping	1	0	Negative	None	0	Negative	No	No	no	no					
1	3	316K	Kitchen	yes	Door Frame	Metal	Tan	Chipping	6	0.25	Negative	None	0	Negative	No	No	no	no					
1	3	316K	Kitchen	yes	Glazed Terracotta Block	Concrete	Green	None	N/A	N/A	N/A	None	0	Negative	No	No	no	no					
1	3	316K	Kitchen	yes	W3	CMU	White	Chipping	1	0	Negative	None	0	Negative	Partially Inaccessible	No	no	no					
1	3	316K	Kitchen	yes	Glazed Terracotta Block	Concrete	Green	None	N/A	N/A	N/A	None	0	Negative	No	No	no	no					
1	3	316K	Kitchen	yes	Electrical Panel	Metal	Grey	Chipping	1	0.18	Negative	None	0	Negative	No	No	no	no					
1	3	316K	Kitchen	yes	Column	Concrete	White	Flaking	1	0.09	Negative	None	0	Negative	No	No	no	no					
1	3	316K	Kitchen	yes	W4	CMU	White	Chipping	1	0	Negative	None	0	Negative	Partially Inaccessible	No	no	no					
1	3	316K	Kitchen	yes	Glazed Terracotta Block	Concrete	Green	None	N/A	N/A	N/A	None	0	Negative	No	No	no	no					
1	3	316K	Kitchen	yes	Roll Up Door Panel	Metal	Grey	Chipping	1	0.4	Negative	None	0	Negative	No	No	no	no					
1	3	316K	Kitchen	yes	Roll Up Door	Metal	Grey	Chipping	40	0.17	Negative	None	0	Negative	No	No	no	no					
1	3	316K	Kitchen	yes	Ceiling	Concrete	White	None	0	N/A	N/A	None	0	Negative	No	No	no	no					
1	3	316K	Kitchen	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Negative	No	No	no	no					
1	3	316A	Kitchen Closet	yes	W1	CMU	Tan	Chipping	1	0	Negative	None	0	Negative	No	No	no	no					
1	3	316A	Kitchen Closet	yes	Door	Metal	Tan	Chipping	1	0.12	Negative	None	0	Negative	No	No	no	no					
1	3	316A	Kitchen Closet	yes	Door Frame	Metal	Tan	Chipping	6	0.4	Negative	None	0	Negative	No	No	no	no					
1	3	316A	Kitchen Closet	yes	W2	CMU	Tan	Chipping	1	0	Negative	None	0	Negative	Partially Inaccessible	No	no	no					
1	3	316A	Kitchen Closet	yes	W3	CMU	Tan	Chipping	1	0	Negative	None	0	Negative	Partially Inaccessible	No	no	no					
1	3	316A	Kitchen Closet	yes	W4	CMU	Tan	Chipping	1	0	Negative	None	0	Negative	Partially Inaccessible	No	no	no					
1	3	316A	Kitchen Closet	yes	Ceiling	Concrete	White	Chipping	2	0.02	Negative	None	0	Negative	No	No	no	no					
1	3	316A	Kitchen Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Negative	No	No	no	no					
1	3	316C	Cafeteria Table Closet	yes	W1	CMU	White	Chipping	2	0	Negative	None	0	Negative	No	No	no	no					
1	3	316C	Cafeteria Table Closet	yes	HVAC	Metal	Grey	Flaking	20	0.25	Negative	None	0	Negative	No	No	no	no					
1	3	316C	Cafeteria Table Closet	yes	Door	Metal	Tan	Chipping	1	0	Negative	None	0	Negative	No	No	no	no					
1	3	316C	Cafeteria Table Closet	yes	Door Frame	Metal	Tan	Chipping	2	0.12	Negative	None	0	Negative	No	No	no	no					
1	3	316C	Cafeteria Table Closet	yes	W2	CMU	White	Chipping	2	0	Negative	None	0	Negative	No	No	no	no					
1	3	316C	Cafeteria Table Closet	yes	W3	CMU	White	Chipping	4	0	Negative	None	0	Negative	No	No	no	no					
1	3	316C	Cafeteria Table Closet	yes	W4	CMU	White	Chipping	3	0	Negative	None	0	Negative	No	Roof leak	no	no					
1	3	316C	Cafeteria Table Closet	yes	Ceiling	Concrete	White	Efflorescence	5	0	Negative	None	0	Negative	No	No	no	no					
1	3	316C	Cafeteria Table Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Negative	No	No	no	no					
1	3	316D	Fan Room	no	W1	CMU	Tan	Chipping	1	0	Negative	None	0	Negative	Partially Inaccessible	No	no	no					
1	3	316D	Fan Room	no	Door Frame	Metal	Tan	Chipping	20	0.14	Negative	None	0	Negative	No	No	no	no					
1	3	316D	Fan Room	no	W2	CMU	Tan	Flaking	4	0	Negative	None	0	Negative	Partially Inaccessible	No	no	no					
1	3	316D	Fan Room	no	W3	CMU	Tan	Flaking	10	0	Negative	None	0	Negative	Partially Inaccessible	No	no	no					
1	3	316D	Fan Room	no	W4	CMU	Tan	Flaking	3	0	Negative	None	0	Negative	Partially Inaccessible	No	no	no					
1	3	316D	Fan Room	no	Ceiling	Concrete	White	Flaking	200	0.04	Negative	None	0	Negative	No	Unknown	no	no					
1	3	316D	Fan Room	no	Floor	Concrete	Grey	Friction	200	0	Negative	None	0	Negative	No	No	no	no					
1	3	316D	Fan Room	no	Fan Unit	Metal	Tan	Flaking	100	0.11	Negative	None	0	Negative	Partially Inaccessible	No	no	no					
1	3	H37	Hallway from Classroom 301 to Custodial Break Room	yes	W2	CMU	Yellow	Chipping	1	0	Negative	None	0	Negative	No	No	no	no					
1	3	H37	Hallway from Classroom 301 to Custodial Break Room	yes	W2	CMU	White	None	1	0	Negative	None	0	Negative	No	No	no	no					

			School District of Philadelphia																				
			Name of Inspector: Jen Drialo		Lead Safe Certification Assessment Report							Inspection Dates: 9/20/21-10/7/21											
			Inspection Company: Synertech, Inc.		Gideon ES School							ULCS# 4530											
E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate	Color	Damage	Damage amount (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes				
1	3	H37	Hallway from Classroom 301 to Custodial Break Room	yes	W3	CMU	Yellow	Chipping	2	0	Negative	None	0	Negative	No	No	no	no					
1	3	H37	Hallway from Classroom 301 to Custodial Break Room	yes	W3	CMU	White	Chipping	1	0	Negative	None	0	Negative	No	No	no	no					
1	3	H37	Hallway from Classroom 301 to Custodial Break Room	yes	Radiator	CMU	Tan	Chipping	2	0.17	Negative	None	0	Negative	No	No	no	no					
1	3	H37	Hallway from Classroom 301 to Custodial Break Room	yes	W4	CMU	Yellow	None	1	0	Negative	None	0	Negative	No	No	no	no					
1	3	H37	Hallway from Classroom 301 to Custodial Break Room	yes	W4	CMU	White	Chipping	1	0	Negative	None	0	Negative	No	No	no	no					
1	3	H37	Hallway from Classroom 301 to Custodial Break Room	yes	Ceiling	Concrete	White	Flaking	10	0.04	Negative	None	0	Negative	No	No	no	no					
1	3	H37	Hallway from Classroom 301 to Custodial Break Room	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Negative	No	No	no	no					
1	3	S34	Stairwell adjacent to Classroom 301	yes	W1	CMU	White	None	0	N/A	N/A	None	0	Negative	No	No	no	no					
1	3	S34	Stairwell adjacent to Classroom 301	yes	W1	CMU	Tan	None	0	N/A	N/A	None	0	Negative	No	No	no	no					
1	3	S34	Stairwell adjacent to Classroom 301	yes	Door	Metal	Tan	Chipping	3	0	Negative	None	0	Negative	No	No	no	no					
1	3	S34	Stairwell adjacent to Classroom 301	yes	Door Frame	Metal	Tan	Chipping	1	0.02	Negative	None	0	Negative	No	No	no	no					
1	3	S34	Stairwell adjacent to Classroom 301	yes	W2	CMU	Tan	None	0	N/A	N/A	None	0	Negative	No	No	no	no					
1	3	S34	Stairwell adjacent to Classroom 301	yes	W2	Concrete	Tan	None	0	N/A	N/A	None	0	Negative	No	No	no	no					
1	3	S34	Stairwell adjacent to Classroom 301	yes	W3	CMU	Tan	None	0	N/A	N/A	None	0	Negative	No	No	no	no					
1	3	S34	Stairwell adjacent to Classroom 301	yes	Baluster	Metal	Orange	Chipping	2	4	Positive	None	0	Negative	No	No	no	no					
1	3	S34	Stairwell adjacent to Classroom 301	yes	Column	Concrete	Tan	Chipping	3	0.07	Negative	None	0	Negative	No	No	no	no					
1	3	S34	Stairwell adjacent to Classroom 301	yes	W4	CMU	Tan	Chipping	1	0.04	Negative	None	0	Negative	No	No	no	no					
1	3	S34	Stairwell adjacent to Classroom 301	yes	W4	CMU	White	None	0	N/A	N/A	None	0	Negative	No	No	no	no					
1	3	S34	Stairwell adjacent to Classroom 301	yes	Radiator	Metal	Grey	Chipping	1	0.1	Negative	None	0	Negative	No	No	no	no					
1	3	S34	Stairwell adjacent to Classroom 301	yes	Ceiling	Metal	White	Chipping	5	2.5	Positive	None	0	Negative	No	Unknown	no	no					
1	3	S34	Stairwell adjacent to Classroom 301	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Negative	No	No	no	no					
1	3	S34	Stairwell adjacent to Classroom 301	yes	Open Stringer	Metal	Orange	None	0	N/A	N/A	None	0	Negative	No	No	no	no					
1	3	S34	Stairwell adjacent to Classroom 301	yes	Wall Stringer	Metal	Grey	None	0	N/A	N/A	None	0	Negative	No	No	no	no					
1	3	S34	Stairwell adjacent to Classroom 301	yes	Baluster	Metal	Orange	Chipping	10	4	Positive	None	0	Negative	No	No	no	no					
1	3	S34	Stairwell adjacent to Classroom 301	yes	Newel Post	Metal	Orange	Friction	3	7	Positive	None	0	Negative	No	No	no	no					
1	3	S34	Stairwell adjacent to Classroom 301	yes	Riser	Metal	Grey	Chipping	1	3.5	Positive	None	0	Negative	No	No	no	no					
1	3	S34	Stairwell adjacent to Classroom 301	yes	Handrail	Metal	Orange	Friction	14	3.7	Positive	None	0	Negative	No	No	no	no					
1	3	301	Classroom 301	yes	W1	CMU	Tan	Flaking	10	0	Negative	None	0	Negative	No	No	no	no					
1	3	301	Classroom 301	yes	Door Frame	Metal	Tan	Chipping	6	0.22	Negative	None	0	Negative	No	No	no	no					
1	3	301	Classroom 301	yes	W2	CMU	Tan	None	0	0	Negative	None	0	Negative	No	No	no	no					
1	3	301	Classroom 301	yes	W3	CMU	Tan	Flaking	10	0	Negative	None	0	Negative	No	No	no	no					
1	3	301	Classroom 301	yes	Univent	Metal	Tan	Chipping	2	0.29	Negative	None	0	Negative	No	No	no	no					
1	3	301	Classroom 301	yes	Cabinet Top	Wood	Tan	Chipping	15	0.22	Negative	None	0	Negative	No	No	no	no					
1	3	301	Classroom 301	yes	Shelves	Metal	Tan	Chipping	8	0.22	Negative	None	0	Negative	No	No	no	no					
1	3	301	Classroom 301	yes	Column	Concrete	Tan	Chipping	2	0.03	Negative	None	0	Negative	No	No	no	no					
1	3	301	Classroom 301	yes	W4	CMU	Blue	Flaking	2	0	Negative	None	0	Negative	No	No	no	no					
1	3	301	Classroom 301	yes	Ceiling	Concrete	White	Chipping	2	0	Negative	None	0	Negative	No	No	no	no					
1	3	301	Classroom 301	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Negative	No	No	no	no					
1	3	301A	Classroom 301 Closet	yes	Door Frame	Metal	Tan	Chipping	10	0.16	Negative	None	0	Negative	No	No	no	no					
1	3	301A	Classroom 301 Closet	yes	W2	CMU	Tan	Chipping	8	0	Negative	None	0	Negative	Partially Inaccessible	No	no	no					
1	3	301A	Classroom 301 Closet	yes	Partition	Wood	Tan	Chipping	1	1	Positive	None	0	Negative	No	No	no	no					
1	3	301A	Classroom 301 Closet	yes	Shelves	Wood	Tan	Friction	1	0.8	Positive	None	0	Negative	No	No	no	no	Several shelf paint chip samples were taken and the results were positive. Shelves in the classroom closets should be treated as homogenous.				
1	3	301A	Classroom 301 Closet	yes	W2	CMU	White	None	N/A	N/A	Negative	None	0	Negative	No	No	no	no					

			School District of Philadelphia																								
			Name of Inspector: Jen Drialo		Lead Safe Certification Assessment Report																						
			Inspection Company: Synertech, Inc.		Gideon ES School																						
E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate	Color	Damage	Damage amount (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes								
1	3	301A	Classroom 301 Closet	yes	W3	CMU	Tan	Chipping	2	0	Negative	None	0	Negative	Partially Inaccessible	No	no	no									
1	3	301A	Classroom 301 Closet	yes	W3	CMU	White	Flaking	10	0	Negative	None	0	Negative	No	No	no	no									
1	3	301A	Classroom 301 Closet	yes	W4	CMU	Tan	None	N/A	0	Negative	None	0	Negative	Partially Inaccessible	No	no	no									
1	3	301A	Classroom 301 Closet	yes	W4	CMU	White	Chipping	1	0	Negative	None	0	Negative	No	No	no	no									
1	3	301A	Classroom 301 Closet	yes	Ceiling	Wood	Tan	None	0	N/A	N/A	None	0	Negative	No	No	no	no									
1	3	301A	Classroom 301 Closet	yes	Vent	Metal	White	Chipping	2	0.4	Negative	None	0	Negative	No	No	no	no									
1	3	301A	Classroom 301 Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Negative	No	No	no	no									
1	3	302	Classroom 302	yes	W1	CMU	Blue	Chipping	2	0	Negative	None	0	Negative	No	No	no	no									
1	3	302	Classroom 302	yes	Door Frame	Metal	Tan	Chipping	1	0.16	Negative	None	0	Negative	No	No	no	no									
1	3	302	Classroom 302	yes	W2	CMU	Blue	None	0	0	Negative	None	0	Negative	No	No	no	no									
1	3	302	Classroom 302	yes	W3	CMU	Blue	Chipping	3	0	Negative	None	0	Negative	No	No	no	no									
1	3	302	Classroom 302	yes	Univent	Metal	Blue	Chipping	2	0.13	Negative	None	0	Negative	No	No	no	no									
1	3	302	Classroom 302	yes	Cabinet Top	Wood	Blue	Chipping	20	0.28	Negative	None	0	Negative	No	No	no	no									
1	3	302	Classroom 302	yes	Shelves	Metal	Blue	Chipping	12	0.13	Negative	None	0	Negative	No	No	no	no									
1	3	302	Classroom 302	yes	Column	Concrete	Blue	Flaking	8	0.03	Negative	None	0	Negative	No	No	no	no									
1	3	302	Classroom 302	yes	W4	CMU	Blue	Chipping	90	0	Negative	None	0	Negative	No	No	no	no									
1	3	302	Classroom 302	yes	Ceiling	Concrete	White	Chipping	2	0	Negative	None	0	Negative	No	No	no	no									
1	3	302	Classroom 302	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Negative	No	No	no	no									
1	3	302A	Classroom 302 Closet	yes	Door Frame	Metal	Tan	Chipping	10	0.26	Negative	None	0	Negative	No	No	no	no									
1	3	302A	Classroom 302 Closet	yes	W2	CMU	Blue	Chipping	8	0	Negative	None	0	Negative	Partially Inaccessible	No	no	no									
1	3	302A	Classroom 302 Closet	yes	Partition	Wood	Blue	Flaking	1	1.3	Positive	None	0	Negative	No	No	no	no									
1	3	302A	Classroom 302 Closet	yes	Shelves	Wood	Blue	Friction	2	0.7	Positive	None	0	Negative	No	No	no	no	Several shelf paint chip samples were taken and the results were positive. Shelves in the classroom closets should be treated as homogenous.								
1	3	302A	Classroom 302 Closet	yes	W2	CMU	White	Chipping	1	0	Negative	None	0	Negative	No	No	no	no									
1	3	302A	Classroom 302 Closet	yes	W3	CMU	Blue	Chipping	2	0	Negative	None	0	Negative	Partially Inaccessible	No	no	no									
1	3	302A	Classroom 302 Closet	yes	W3	CMU	White	Chipping	1	0	Negative	None	0	Negative	No	No	no	no									
1	3	302A	Classroom 302 Closet	yes	W4	CMU	Blue	None	N/A	0	Negative	None	0	Negative	Partially Inaccessible	No	no	no									
1	3	302A	Classroom 302 Closet	yes	W4	CMU	White	Chipping	1	0	Negative	None	0	Negative	No	No	no	no									
1	3	302A	Classroom 302 Closet	yes	Ceiling	Wood	Blue	None	0	N/A	N/A	None	0	Negative	No	No	no	no									
1	3	302A	Classroom 302 Closet	yes	Vent	Metal	White	Chipping	2	0.4	Negative	None	0	Negative	No	No	no	no									
1	3	302A	Classroom 302 Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Negative	No	No	no	no									
1	3	302C	Women's Teachers Lounge	yes	W1	CMU	Tan	Flaking	10	0	Negative	None	0	Negative	No	No	no	no									
1	3	302C	Women's Teachers Lounge	yes	Door Frame	Metal	Tan	Chipping	8	0.17	Negative	None	0	Negative	No	No	no	no									
1	3	302C	Women's Teachers Lounge	yes	W2	CMU	Tan	Flaking	50	0	Negative	None	0	Negative	No	No	no	no									
1	3	302C	Women's Teachers Lounge	yes	W3	CMU	Tan	Flaking	5	0	Negative	None	0	Negative	No	No	no	no									
1	3	302C	Women's Teachers Lounge	yes	Univent	Metal	Tan	Chipping	2	0.12	Negative	None	0	Negative	No	No	no	no									
1	3	302C	Women's Teachers Lounge	yes	Column	Concrete	Tan	Flaking	2	0.04	Negative	None	0	Negative	No	No	no	no									
1	3	302C	Women's Teachers Lounge	yes	W4	CMU	Tan	Flaking	15	0	Negative	None	0	Negative	No	No	no	no									
1	3	302C	Women's Teachers Lounge	yes	Ceiling	Concrete	White	Flaking	10	0.03	Negative	None	0	Negative	No	No	no	no									
1	3	302C	Women's Teachers Lounge	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Negative	No	No	no	no									
1	3	302F	Custodial Locker/Break Room Restroom	yes	W1	CMU	Tan	Chipping	4	0	Negative	None	0	Negative	No	No	no	no									
1	3	302F	Custodial Locker/Break Room Restroom	yes	Door Frame	Metal	Tan	Chipping	6	0.25	Negative	None	0	Negative	No	No	no	no									
1	3	302F	Custodial Locker/Break Room Restroom	yes	W2	CMU	Tan	Efflorescence	6	0.06	Negative	None	0	Negative	No	Unknown	no	no									
1	3	302F	Custodial Locker/Break Room Restroom	yes	W3	CMU	Tan	Chipping	6	0	Negative	None	0	Negative	No	No	no	no									
1	3	302F	Custodial Locker/Break Room Restroom	yes	W4	CMU	Tan	Flaking	4	0	Negative	None	0	Negative	No	No	no	no									
1	3	302F	Custodial Locker/Break Room Restroom	yes	Ceiling	Concrete	White	Flaking	2	0.02	Negative	None	0	Negative	No	No	no	no									
1	3	302F	Custodial Locker/Break Room Restroom	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Negative	No	No	no	no									
1	3	302S	Custodial Storage Room Closet	no	W1	CMU	Tan	Chipping	1	0	Negative	None	0	Negative	No	No	no	no									
1	3	302S	Custodial Storage Room Closet	no	Door Frame	Metal	Tan	Chipping	8	0.16	Negative	None	0	Negative	No	No	no	no									
1	3	302S	Custodial Storage Room Closet	no	Pipe	Metal	White	Flaking	6	1.3	Positive	None	0	Negative	No	No	no	no									
1	3	302S	Custodial Storage Room Closet	no	W2	CMU	Tan	Chipping	2	0.06	Negative	None	0	Negative	No	No	no	no									
1	3	302S	Custodial Storage Room Closet	no	W3	CMU	Tan	Chipping	1	0	Negative	None	0	Negative	No	No	no	no									
1	3	302S	Custodial Storage Room Closet	no	Sink	Porcelain	Grey	Chipping	2	1.3	Positive	None	0	Negative	No	No	no	no									
1	3	302S	Custodial Storage Room Closet	no	W4	CMU	Tan	Flaking	4	0.03	Negative	None	0	Negative	No	No	no	no									
1	3	302S	Custodial Storage Room Closet	no	Ceiling	Concrete	White	Flaking	60	0.04	Negative	None	0	Negative	No	No	no	no									
1	3	302S	Custodial Storage Room Closet	no	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Negative	No	No	no	no									
1	3	302B	Break Room	yes	W1	CMU	Tan	Chipping	1	0	Negative	None	0	Negative	No	No	no	no									
1	3	302B	Break Room	yes	Door Frame	Metal	Tan	Chipping	6	0.13	Negative	None	0	Negative	No	No	no	no									

			School District of Philadelphia																				
			Name of Inspector: Jen Drialo		Lead Safe Certification Assessment Report							Inspection Dates: 9/20/21-10/7/21											
			Inspection Company: Synertech, Inc.		Gideon ES School							ULCS# 4530											
E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate	Color	Damage	Damage amount (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes				
1	3	302B	Break Room	yes	W2	CMU	Tan	Flaking	2	0.06	Negative	None	0	Negative	No	No	no	no					
1	3	302B	Break Room	yes	W3	CMU	Tan	Chipping	1	0	Negative	None	0	Negative	No	No	no	no					
1	3	302B	Break Room	yes	Radiator	Metal	Tan	Chipping	1	0.04	Negative	None	0	Negative	No	No	no	no					
1	3	302B	Break Room	yes	Column	Concrete	White	Flaking	1	0.01	Negative	None	0	Negative	No	No	no	no					
1	3	302B	Break Room	yes	W4	CMU	Tan	Flaking	4	0	Negative	None	0	Negative	No	No	no	no					
1	3	302B	Break Room	yes	Ceiling	Concrete	White	Flaking	15	0.02	Negative	None	0	Negative	No	No	no	no					
1	3	302B	Break Room	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Negative	No	No	no	no					
1	3	302E	Custodial Closet next to Locker/Break Room	no	W1	CMU	Tan	None	0	N/A	N/A	None	0	Negative	No	No	no	no					
1	3	302E	Custodial Closet next to Locker/Break Room	no	Door Frame	Metal	Tan	Chipping	6	0.26	Negative	None	0	Negative	No	No	no	no					
1	3	302E	Custodial Closet next to Locker/Break Room	no	W2	CMU	Tan	Chipping	2	0	Negative	None	0	Negative	Partially Inaccessible	No	no	no					
1	3	302E	Custodial Closet next to Locker/Break Room	no	W3	CMU	Tan	None	0	N/A	N/A	None	0	Negative	Partially Inaccessible	No	no	no					
1	3	302E	Custodial Closet next to Locker/Break Room	no	W4	CMU	Tan	None	0	N/A	N/A	None	0	Negative	No	No	no	no					
1	3	302E	Custodial Closet next to Locker/Break Room	no	Ceiling	Concrete	White	Chipping	2	0	Negative	None	0	Negative	No	No	no	no					
1	3	302E	Custodial Closet next to Locker/Break Room	no	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Negative	No	No	no	no					
1	3	S38	Stairwell next to Custodial Locker/Break Room	yes	W1	CMU	Tan	None	0	N/A	N/A	None	0	Negative	No	No	no	no					
1	3	S38	Stairwell next to Custodial Locker/Break Room	yes	W1	Concrete	Tan	None	0	N/A	N/A	None	0	Negative	No	No	no	no					
1	3	S38	Stairwell next to Custodial Locker/Break Room	yes	Door	Metal	Tan	Chipping	2	0	Negative	None	0	Negative	No	No	no	no					
1	3	S38	Stairwell next to Custodial Locker/Break Room	yes	Door Frame	Metal	Tan	Chipping	4	0.02	Negative	None	0	Negative	No	No	no	no					
1	3	S38	Stairwell next to Custodial Locker/Break Room	yes	W2	CMU	Tan	None	0	N/A	N/A	None	0	Negative	No	No	no	no					
1	3	S38	Stairwell next to Custodial Locker/Break Room	yes	W2	Concrete	Tan	Chipping	1	0.05	Negative	None	0	Negative	No	No	no	no					
1	3	S38	Stairwell next to Custodial Locker/Break Room	yes	Baluster	Metal	Orange	Chipping	1	3.8	Positive	None	0	Negative	No	No	no	no					
1	3	S38	Stairwell next to Custodial Locker/Break Room	yes	W3	CMU	Tan	Flaking	4	0	Negative	None	0	Negative	No	No	no	no					
1	3	S38	Stairwell next to Custodial Locker/Break Room	yes	W3	Concrete	Tan	None	0	N/A	N/A	None	0	Negative	No	No	no	no					
1	3	S38	Stairwell next to Custodial Locker/Break Room	yes	Radiator	Metal	Grey	Chipping	1	0.1	Negative	None	0	Negative	No	No	no	no					
1	3	S38	Stairwell next to Custodial Locker/Break Room	yes	Baluster	Metal	Orange	Chipping	8	4	Positive	None	0	Negative	No	No	no	no					
1	3	S38	Stairwell next to Custodial Locker/Break Room	yes	W4	CMU	Tan	None	0	N/A	N/A	None	0	Negative	No	No	no	no					
1	3	S38	Stairwell next to Custodial Locker/Break Room	yes	Door	Metal	Tan	Chipping	6	0	Negative	None	0	Negative	No	No	no	no					
1	3	S38	Stairwell next to Custodial Locker/Break Room	yes	Door Frame	Metal	Tan	Chipping	3	0.12	Negative	None	0	Negative	No	No	no	no					
1	3	S38	Stairwell next to Custodial Locker/Break Room	yes	Radiator	Metal	Grey	Chipping	2	0.06	Negative	None	0	Negative	No	No	no	no					
1	3	S38	Stairwell next to Custodial Locker/Break Room	yes	Ceiling	Concrete	White	None	0	N/A	N/A	None	0	Negative	No	No	no	no					
1	3	S38	Stairwell next to Custodial Locker/Break Room	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Negative	No	No	no	no					
1	3	S38	Stairwell next to Custodial Locker/Break Room	yes	Open Stringer	Metal	Orange	Chipping	2	6	Positive	None	0	Negative	No	No	no	no					
1	3	S38	Stairwell next to Custodial Locker/Break Room	yes	Wall Stringer	Metal	Grey	Chipping	1	6.1	Positive	None	0	Negative	No	No	no	no					
1	3	S38	Stairwell next to Custodial Locker/Break Room	yes	Baluster	Metal	Orange	Chipping	6	4	Positive	None	0	Negative	No	No	no	no					
1	3	S38	Stairwell next to Custodial Locker/Break Room	yes	Newel Post	Metal	Grey	Friction	2	5.7	Positive	None	0	Negative	No	No	no	no					
1	3	S38	Stairwell next to Custodial Locker/Break Room	yes	Riser	Metal	Grey	Chipping	5	2.7	Positive	None	0	Negative	No	No	no	no					
1	3	S38	Stairwell next to Custodial Locker/Break Room	yes	Handrail	Metal	Orange	Friction	5	3.7	Positive	None	0	Negative	No	No	no	no					
1	3	305	Classroom 305	yes	W1	CMU	Grey	Chipping	2	0	Negative	None	0	Negative	No	No	no	no					
1	3	305	Classroom 305	yes	Door Frame	Metal	Grey	Chipping	1	0.1	Negative	None	0	Negative	No	No	no	no					
1	3	305	Classroom 305	yes	W2	CMU	Grey	None	0	0	Negative	None	0	Negative	No	No	no	no					
1	3	305	Classroom 305	yes	W3	CMU	Grey	Chipping	3	0	Negative	None	0	Negative	No	No	no	no					
1	3	305	Classroom 305	yes	Univent	Metal	Grey	Chipping	4	0.17	Negative	None	0	Negative	No	No	no	no					
1	3	305	Classroom 305	yes	Cabinet Top	Wood	Grey	Chipping	15	0.22	Negative	None	0	Negative	No	No	no	no					
1	3	305	Classroom 305	yes	Shelves	Metal	Grey	Chipping	2	0.12	Negative	None	0	Negative	No	No	no	no					
1	3	305	Classroom 305	yes	Panel	Metal	Grey	Chipping	1	0.06	inconclusive	None	0	Negative	No	No	no	no	Paint Chip Sampled; 0.87% Pb/weight				



			School District of Philadelphia																	
			Name of Inspector: Jen Drialo		Lead Safe Certification Assessment Report							Inspection Dates: 9/20/21-10/7/21								
			Inspection Company: Synertech, Inc.		Gideon ES School							ULCS# 4530								
E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate	Color	Damage	Damage amount (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes	
1	3	303A	Classroom 303 Closet	yes	W4	CMU	White	Chipping	1	0	Negative	None	0	Negative	No	No	no	no		
1	3	303A	Classroom 303 Closet	yes	Ceiling	Wood	White	None	0	N/A	N/A	None	0	Negative	No	No	no	no		
1	3	303A	Classroom 303 Closet	yes	Vent	Metal	White	Chipping	1	0.4	Negative	None	0	Negative	No	No	no	no		
1	3	303A	Classroom 303 Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Negative	No	No	no	no		
1	3	H38	Hallway from Classrooms 311 to 303	yes	W1	CMU	Yellow	Chipping	2	0	Negative	None	0	Negative	No	No	no	no		
1	3	H38	Hallway from Classrooms 311 to 303	yes	W1	CMU	White	None	0	N/A	N/A	None	0	Negative	No	No	no	no		
1	3	H38	Hallway from Classrooms 311 to 303	yes	W2	CMU	Yellow	Chipping	1	0	Negative	None	0	Negative	No	No	no	no		
1	3	H38	Hallway from Classrooms 311 to 303	yes	W2	CMU	White	None	0	N/A	N/A	None	0	Negative	No	No	no	no		
1	3	H38	Hallway from Classrooms 311 to 303	yes	W3	CMU	Yellow	Chipping	1	0	Negative	None	0	Negative	No	No	no	no		
1	3	H38	Hallway from Classrooms 311 to 303	yes	W3	CMU	White	Chipping	1	0	Negative	None	0	Negative	No	No	no	no		
1	3	H38	Hallway from Classrooms 311 to 303	yes	Radiator	CMU	Tan	Chipping	2	0.17	Negative	None	0	Negative	No	No	no	no		
1	3	H38	Hallway from Classrooms 311 to 303	yes	W4	CMU	Yellow	None	0	N/A	N/A	None	0	Negative	No	No	no	no		
1	3	H38	Hallway from Classrooms 311 to 303	yes	W4	CMU	White	Chipping	1	0	Negative	None	0	Negative	No	No	no	no		
1	3	H38	Hallway from Classrooms 311 to 303	yes	Ceiling	Concrete	White	Flaking	5	0.04	Negative	None	0	Negative	No	No	no	no		
1	3	H38	Hallway from Classrooms 311 to 303	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Negative	No	No	no	no		
1	2	211	Classroom 211	yes	W1	CMU	Grey	Chipping	1	0	Negative	None	0	Negative	No	No	no	no		
1	2	211	Classroom 211	yes	Door Frame	Metal	Grey	Friction	3	0.11	Negative	None	0	Negative	No	No	no	no		
1	2	211	Classroom 211	yes	W2	CMU	Grey	Chipping	1	0	Negative	None	0	Negative	No	No	no	no		
1	2	211	Classroom 211	yes	W3	CMU	Grey	Chipping	3	0	Negative	None	0	Negative	No	No	no	no		
1	2	211	Classroom 211	yes	Column	Concrete	Grey	Chipping	1	0.03	Negative	None	0	Negative	No	No	no	no		
1	2	211	Classroom 211	yes	Cabinet Top	Wood	Grey	Flaking	6	0.23	Negative	None	0	Negative	No	No	no	no		
1	2	211	Classroom 211	yes	Shelves	Metal	Grey	Friction	2	0.08	Negative	None	0	Negative	No	No	no	no		
1	2	211	Classroom 211	yes	Univent	Metal	Grey	Chipping	4	0.13	Negative	None	0	Negative	No	No	no	no		
1	2	211	Classroom 211	yes	Pipe Riser	Metal	Yellow	Chipping	3	0.5	Negative	None	0	Negative	No	No	no	no		
1	2	211	Classroom 211	yes	W4	CMU	Yellow	Chipping	1	0	Negative	None	0	Negative	No	No	no	no		
1	2	211	Classroom 211	yes	Ceiling	Concrete	White	Flaking	6	0	Negative	None	0	Negative	No	No	no	no		
1	2	211	Classroom 211	yes	Pipe	Metal	White	Flaking	1	0.26	Negative	None	0	Negative	No	No	no	no		
1	2	211	Classroom 211	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Negative	No	No	no	no		
1	2	211A	Classroom 211 Closet	yes	W2	CMU	Grey	None	0	0	Negative	None	0	Negative	Partially Inaccessible	No	no	no		
1	2	211A	Classroom 211 Closet	yes	Partition	Wood	Grey	Chipping	1	1.5	Positive	None	0	Negative	No	No	no	no		
1	2	211A	Classroom 211 Closet	yes	Shelves	Wood	Green	Friction	2	0.7	Positive	None	0	Negative	No	No	no	no	Several shelf paint chip samples were taken and the results were positive. Shelves in the classroom closets should be treated as homogenous.	
1	2	211A	Classroom 211 Closet	yes	W2	CMU	Grey	Chipping	1	0	Negative	None	0	Negative	No	No	no	no		
1	2	211A	Classroom 211 Closet	yes	W3	CMU	Grey	Chipping	2	0	Negative	None	0	Negative	Partially Inaccessible	No	no	no		
1	2	211A	Classroom 211 Closet	yes	W3	CMU	Grey	Chipping	1	0	Negative	None	0	Negative	No	No	no	no		
1	2	211A	Classroom 211 Closet	yes	W4	CMU	Grey	Chipping	1	0	Negative	None	0	Negative	Partially Inaccessible	No	no	no		
1	2	211A	Classroom 211 Closet	yes	W4	CMU	Grey	Chipping	1	0	Negative	None	0	Negative	No	No	no	no		
1	2	211A	Classroom 211 Closet	yes	Ceiling	Wood	Grey	None	0	N/A	N/A	None	0	Negative	No	No	no	no		
1	2	211A	Classroom 211 Closet	yes	Vent	Metal	Grey	Chipping	1	0.4	Negative	None	0	Negative	No	No	no	no		
1	2	211A	Classroom 211 Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Negative	No	No	no	no		
1	2	210	Classroom 210	yes	W1	CMU	Grey	Chipping	1	0	Negative	None	0	Negative	No	No	no	no		
1	2	210	Classroom 210	yes	Door Frame	Metal	Grey	Friction	2	0.15	Negative	None	0	Negative	No	No	no	no		
1	2	210	Classroom 210	yes	W2	CMU	Grey	Chipping	1	0	Negative	None	0	Negative	No	No	no	no		
1	2	210	Classroom 210	yes	W3	CMU	Grey	Chipping	3	0	Negative	None	0	Negative	No	No	no	no		
1	2	210	Classroom 210	yes	Column	Concrete	Grey	Chipping	1	0.03	Negative	None	0	Negative	No	No	no	no		
1	2	210	Classroom 210	yes	Cabinet Top	Wood	Grey	Flaking	15	0.23	Negative	None	0	Negative	No	No	no	no		
1	2	210	Classroom 210	yes	Shelves	Metal	Grey	Friction	4	0.08	Negative	None	0	Negative	No	No	no	no		
1	2	210	Classroom 210	yes	Univent	Metal	Grey	Chipping	6	0.13	Negative	None	0	Negative	No	No	no	no		
1	2	210	Classroom 210	yes	Pipe Riser	Metal	Yellow	Chipping	3	0.5	Negative	None	0	Negative	No	No	no	no		
1	2	210	Classroom 210	yes	W4	CMU	Yellow	Chipping	1	0	Negative	None	0	Negative	No	No	no	no		
1	2	210	Classroom 210	yes	Ceiling	Concrete	White	Flaking	6	0	Negative	None	0	Negative	No	No	no	no		
1	2	210	Classroom 210	yes	Pipe	Metal	White	Flaking	1	0.26	Negative	None	0	Negative	No	No	no	no		
1	2	210	Classroom 210	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Negative	No	No	no	no		
1	2	210A	Classroom 210 Closet	yes	W2	CMU	Grey	None	0	0	Negative	None	0	Negative	Partially Inaccessible	No	no	no		
1	2	210A	Classroom 210 Closet	yes	Partition	Wood	Grey	Chipping	1	1.5	Positive	None	0	Negative	No	No	no	no		

			School District of Philadelphia																								
			Name of Inspector: Jen Drialo		Lead Safe Certification Assessment Report																						
			Inspection Company: Synertech, Inc.		Gideon ES School																						
E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate	Color	Damage	Damage amount (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes								
1	2	210A	Classroom 210 Closet	yes	Shelves	Wood	Green	Friction	5	0.7	Positive	None	0	Negative	No	No	no	no	Several shelf paint chip samples were taken and the results were positive. Shelves in the classroom closets should be treated as homogenous.								
1	2	210A	Classroom 210 Closet	yes	W2	CMU	Grey	Chipping	1	0	Negative	None	0	Negative	No	No	no	no									
1	2	210A	Classroom 210 Closet	yes	W3	CMU	Grey	Chipping	2	0	Negative	None	0	Negative	Partially Inaccessible	No	no	no									
1	2	210A	Classroom 210 Closet	yes	W3	CMU	Grey	Chipping	1	0	Negative	None	0	Negative	No	No	no	no									
1	2	210A	Classroom 210 Closet	yes	W4	CMU	Grey	Chipping	1	0	Negative	None	0	Negative	Partially Inaccessible	No	no	no									
1	2	210A	Classroom 210 Closet	yes	W4	CMU	Grey	Chipping	1	0	Negative	None	0	Negative	No	No	no	no									
1	2	210A	Classroom 210 Closet	yes	Ceiling	Wood	Grey	None	0	N/A	N/A	None	0	Negative	No	No	no	no									
1	2	210A	Classroom 210 Closet	yes	Vent	Metal	Grey	Chipping	1	0.4	Negative	None	0	Negative	No	No	no	no									
1	2	210A	Classroom 210 Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Negative	No	No	no	no									
1	2	S23	Stairwell next to Classroom 211	yes	W1	CMU	Tan	Chipping	2	0.07	Negative	None	0	Negative	No	No	no	no									
1	2	S23	Stairwell next to Classroom 211	yes	W1	Concrete	Tan	Chipping	1	0.04	Negative	None	0	Negative	No	No	no	no									
1	2	S23	Stairwell next to Classroom 211	yes	Door	Metal	Tan	Chipping	1	0	Negative	None	0	Negative	No	No	no	no									
1	2	S23	Stairwell next to Classroom 211	yes	Door Frame	Metal	Tan	Chipping	1	0.12	Negative	None	0	Negative	No	No	no	no									
1	2	S23	Stairwell next to Classroom 211	yes	W2	CMU	Tan	Chipping	1	0.15	Negative	None	0	Negative	No	No	no	no									
1	2	S23	Stairwell next to Classroom 211	yes	Column	Concrete	Tan	Flaking	1	0.06	Negative	None	0	Negative	No	No	no	no									
1	2	S23	Stairwell next to Classroom 211	yes	Radiator	Metal	Grey	Chipping	1	0.06	Negative	None	0	Negative	No	No	no	no									
1	2	S23	Stairwell next to Classroom 211	yes	W3	CMU	Tan	Chipping	1	0.11	Negative	None	0	Negative	No	No	no	no									
1	2	S23	Stairwell next to Classroom 211	yes	Baluster	Metal	Orange	Chipping	5	2.9	Positive	None	0	Negative	No	No	no	no	At Window								
1	2	S23	Stairwell next to Classroom 211	yes	Column	Concrete	Tan	Flaking	2	0.04	Negative	None	0	Negative	No	No	no	no									
1	2	S23	Stairwell next to Classroom 211	yes	W4	CMU	Tan	Chipping	1	0.04	Negative	None	0	Negative	No	No	no	no									
1	2	S23	Stairwell next to Classroom 211	yes	Column	Concrete	Tan	Flaking	5	0.11	Negative	None	0	Negative	No	No	no	no									
1	2	S23	Stairwell next to Classroom 211	yes	Radiator	Metal	Grey	Chipping	1	0.04	Negative	None	0	Negative	No	No	no	no									
1	2	S23	Stairwell next to Classroom 211	yes	Ceiling	Metal	White	Chipping	10	2.5	Positive	None	0	Negative	No	Unknown	no	no									
1	2	S23	Stairwell next to Classroom 211	yes	Ceiling	Concrete	Tan	Chipping	1	0.06	Negative	None	0	Negative	No	No	no	no									
1	2	S23	Stairwell next to Classroom 211	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Negative	No	No	no	no									
1	2	S23	Stairwell next to Classroom 211	yes	Open Stringer	Metal	Orange	Chipping	2	6	Positive	None	0	Negative	No	No	no	no									
1	2	S23	Stairwell next to Classroom 211	yes	Wall Stringer	Metal	Grey	Chipping	1	6.8	Positive	None	0	Negative	No	No	no	no									
1	2	S23	Stairwell next to Classroom 211	yes	Baluster	Metal	Orange	Chipping	6	4	Positive	None	0	Negative	No	No	no	no									
1	2	S23	Stairwell next to Classroom 211	yes	Newel Post	Metal	Orange	Friction	5	5.7	Positive	None	0	Negative	No	No	no	no									
1	2	S23	Stairwell next to Classroom 211	yes	Riser	Metal	Grey	Chipping	5	2.7	Positive	None	0	Negative	No	No	no	no									
1	2	S23	Stairwell next to Classroom 211	yes	Handrail	Metal	Orange	Friction	10	3.7	Positive	None	0	Negative	No	No	no	no									
1	2	H26B	Storage 4	yes	W1	CMU	Tan	None	0	N/A	N/A	None	0	Negative	Partially Inaccessible	No	no	no									
1	2	H26B	Storage 4	yes	Door Frame	Metal	Tan	Chipping	6	0.26	Negative	None	0	Negative	Partially Inaccessible	No	no	no									
1	2	H26B	Storage 4	yes	Pipe	Metal	Tan	Chipping	1	0.3	Negative	None	0	Negative	No	No	no	no									
1	2	H26B	Storage 4	yes	W2	CMU	Tan	None	0	N/A	N/A	None	0	Negative	Partially Inaccessible	No	no	no									
1	2	H26B	Storage 4	yes	W3	CMU	Tan	None	0	N/A	N/A	None	0	Negative	Partially Inaccessible	No	no	no									
1	2	H26B	Storage 4	yes	W4	CMU	Tan	None	0	N/A	N/A	None	0	Negative	Partially Inaccessible	No	no	no									
1	2	H26B	Storage 4	yes	Ceiling	Concrete	White	None	0	N/A	N/A	None	0	Negative	No	No	no	no									
1	2	H26B	Storage 4	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Negative	No	No	no	no									
1	2	212	Classroom 212	yes	W1	CMU	Grey	Chipping	2	0	Negative	None	0	Negative	No	No	no	no									
1	2	212	Classroom 212	yes	Door Frame	Metal	Grey	Friction	6	0.15	Negative	None	0	Negative	No	No	no	no									
1	2	212	Classroom 212	yes	W2	CMU	Grey	Chipping	1	0	Negative	None	0	Negative	No	No	no	no									
1	2	212	Classroom 212	yes	Pipe	Metal	Green	Chipping	4	0.16	Negative	None	0	Negative	No	No	no	no									
1	2	212	Classroom 212	yes	W3	CMU	Grey	Chipping	3	0	Negative	None	0	Negative	No	No	no	no									
1	2	212	Classroom 212	yes	Column	Concrete	Grey	Chipping	1	0.03	Negative	None	0	Negative	No	No	no	no									
1	2	212	Classroom 212	yes	Cabinet Top	Wood	Grey	Flaking	12	0.23	Negative	None	0	Negative	No	No	no	no									
1	2	212	Classroom 212	yes	Shelves	Metal	Grey	Friction	4	0.08	Negative	None	0	Negative	No	No	no	no									
1	2	212	Classroom 212	yes	Univent	Metal	Grey	Chipping	6	0.16	Negative	None	0	Negative	No	No	no	no									
1	2	212	Classroom 212	yes	Pipe Riser	Metal	Yellow	Chipping	3	0.4	Negative	None	0	Negative	No	No	no	no									
1	2	212	Classroom 212	yes	W4	CMU	Yellow	Chipping	1	0	Negative	None	0	Negative	No	No	no	no									
1	2	212	Classroom 212	yes	Ceiling	Concrete	White	Flaking	6	0.03	Negative	None	0	Negative	No	No	no	no									
1	2	212	Classroom 212	yes	Pipe	Metal	White	Flaking	1	0.26	Negative	None	0	Negative	No	No	no	no									
1	2	212	Classroom 212	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Negative	No	No	no	no									
1	2	212A	Classroom 212 Closet	yes	W2	CMU	Grey	None	0	0	Negative	None	0	Negative	Partially Inaccessible	No	no	no									
1	2	212A	Classroom 212 Closet	yes	Partition	Wood	Grey	Chipping	1	1	Positive	None	0	Negative	No	No	no	no									
1	2	212A	Classroom 212 Closet	yes	Shelves	Wood	Green	Friction	5	0.8	Positive	None	0	Negative	No	No	no	no	Several shelf paint chip samples were taken and the results were positive. Shelves in the classroom closets should be treated as homogenous.								
1	2	212A	Classroom 212 Closet	yes	W2	CMU	Grey	Chipping	1	0	Negative	None	0	Negative	No	No	no	no									

			School District of Philadelphia																
			Name of Inspector: Jen Drialo		Lead Safe Certification Assessment Report							Inspection Dates: 9/20/21-10/7/21							
			Inspection Company: Synertech, Inc.		Gideon ES School							ULCS# 4530							
E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate	Color	Damage	Damage amount (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes
1	2	212A	Classroom 212 Closet	yes	W3	CMU	Grey	Chipping	2	0	Negative	None	0	Negative	Partially Inaccessible	No	no	no	
1	2	212A	Classroom 212 Closet	yes	W3	CMU	Grey	Chipping	1	0	Negative	None	0	Negative	No	No	no	no	
1	2	212A	Classroom 212 Closet	yes	W4	CMU	Grey	Chipping	1	0	Negative	None	0	Negative	Partially Inaccessible	No	no	no	
1	2	212A	Classroom 212 Closet	yes	W4	CMU	Grey	Chipping	1	0	Negative	None	0	Negative	No	No	no	no	
1	2	212A	Classroom 212 Closet	yes	Ceiling	Wood	Grey	None	0	N/A	N/A	None	0	Negative	No	No	no	no	
1	2	212A	Classroom 212 Closet	yes	Vent	Metal	Grey	Chipping	1	0.4	Negative	None	0	Negative	No	No	no	no	
1	2	212A	Classroom 212 Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Negative	No	No	no	no	
1	2	209	Classroom 209	yes	W1	CMU	Grey	Chipping	2	0	Negative	None	0	Negative	No	No	no	no	
1	2	209	Classroom 209	yes	Coat Rack	Wood	Grey	Friction	1	0	Negative	None	0	Negative	No	No	no	no	
1	2	209	Classroom 209	yes	Door Frame	Metal	Grey	Friction	6	0.15	Negative	None	0	Negative	No	No	no	no	
1	2	209	Classroom 209	yes	W2	CMU	Grey	Chipping	1	0	Negative	None	0	Negative	No	No	no	no	
1	2	209	Classroom 209	yes	Pipe	Metal	Green	Chipping	4	0.16	Negative	None	0	Negative	No	No	no	no	
1	2	209	Classroom 209	yes	W3	CMU	Grey	Chipping	3	0	Negative	None	0	Negative	No	No	no	no	
1	2	209	Classroom 209	yes	Column	Concrete	Grey	Chipping	1	0.03	Negative	None	0	Negative	No	No	no	no	
1	2	209	Classroom 209	yes	Cabinet Top	Wood	Grey	Flaking	12	0.23	Negative	None	0	Negative	No	No	no	no	
1	2	209	Classroom 209	yes	Shelves	Metal	Grey	Friction	4	0.08	Negative	None	0	Negative	No	No	no	no	
1	2	209	Classroom 209	yes	Univent	Metal	Grey	Chipping	6	0.16	Negative	None	0	Negative	No	No	no	no	
1	2	209	Classroom 209	yes	W4	CMU	Blue	Chipping	1	0	Negative	None	0	Negative	No	No	no	no	
1	2	209	Classroom 209	yes	Ceiling	Concrete	White	Flaking	6	0.03	Negative	None	0	Negative	No	No	no	no	
1	2	209	Classroom 209	yes	Pipe	Metal	White	Flaking	1	0.26	Negative	None	0	Negative	No	No	no	no	
1	2	209	Classroom 209	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Negative	No	No	no	no	
1	2	209A	Classroom 209 Closet	yes	W2	CMU	Grey	None	0	0	Negative	None	0	Negative	Partially Inaccessible	No	no	no	
1	2	209A	Classroom 209 Closet	yes	Partition	Wood	Grey	Chipping	1	1	Positive	None	0	Negative	No	No	no	no	
1	2	209A	Classroom 209 Closet	yes	Shelves	Wood	Grey	Friction	5	0.8	Positive	None	0	Negative	No	No	no	no	Several shelf paint chip samples were taken and the results were positive. Shelves in the classroom closets should be treated as homogenous.
1	2	209A	Classroom 209 Closet	yes	W2	CMU	Grey	Chipping	1	0	Negative	None	0	Negative	No	No	no	no	
1	2	209A	Classroom 209 Closet	yes	W3	CMU	Grey	Chipping	2	0	Negative	None	0	Negative	Partially Inaccessible	No	no	no	
1	2	209A	Classroom 209 Closet	yes	W3	CMU	Grey	Chipping	1	0	Negative	None	0	Negative	No	No	no	no	
1	2	209A	Classroom 209 Closet	yes	W4	CMU	Grey	Chipping	1	0	Negative	None	0	Negative	Partially Inaccessible	No	no	no	
1	2	209A	Classroom 209 Closet	yes	W4	CMU	Grey	Chipping	1	0	Negative	None	0	Negative	No	No	no	no	
1	2	209A	Classroom 209 Closet	yes	Ceiling	Wood	Grey	None	0	N/A	N/A	None	0	Negative	No	No	no	no	
1	2	209A	Classroom 209 Closet	yes	Vent	Metal	Grey	Chipping	1	0.4	Negative	None	0	Negative	No	No	no	no	
1	2	209A	Classroom 209 Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Negative	No	No	no	no	
1	2	213	Climate Control Manager Office Room 213	yes	W1	CMU	Tan	Chipping	1	0	Negative	None	0	Negative	No	No	no	no	
1	2	213	Climate Control Manager Office Room 213	yes	W1	CMU	White	None	N/A	N/A	N/A	None	0	Negative	No	No	no	no	
1	2	213	Climate Control Manager Office Room 213	yes	Door Frame	Metal	Tan	Chipping	6	0.13	Negative	None	0	Negative	No	No	no	no	
1	2	213	Climate Control Manager Office Room 213	yes	W2	CMU	Tan	Flaking	2	0	Negative	None	0	Negative	No	No	no	no	
1	2	213	Climate Control Manager Office Room 213	yes	W2	CMU	White	Chipping	1	0	Negative	None	0	Negative	No	No	no	no	
1	2	213	Climate Control Manager Office Room 213	yes	W3	CMU	Tan	Chipping	1	0	Negative	None	0	Negative	No	No	no	no	
1	2	213	Climate Control Manager Office Room 213	yes	W3	CMU	White	None	N/A	N/A	N/A	None	0	Negative	No	No	no	no	
1	2	213	Climate Control Manager Office Room 213	yes	Column	Concrete	Tan	Chipping	3	0.03	Negative	None	0	Negative	No	No	no	no	
1	2	213	Climate Control Manager Office Room 213	yes	Univent	Metal	Tan	Chipping	1	0.4	Negative	None	0	Negative	No	No	no	no	
1	2	213	Climate Control Manager Office Room 213	yes	Cabinet Top	Wood	Tan	Chipping	2	0.23	Negative	None	0	Negative	No	No	no	no	
1	2	213	Climate Control Manager Office Room 213	yes	Shelves	Metal	Tan	Friction	4	0.1	Negative	None	0	Negative	No	No	no	no	
1	2	213	Climate Control Manager Office Room 213	yes	W4	CMU	Tan	Chipping	1	0	Negative	None	0	Negative	No	No	no	no	
1	2	213	Climate Control Manager Office Room 213	yes	W4	CMU	White	Chipping	1	0	Negative	None	0	Negative	No	No	no	no	
1	2	213	Climate Control Manager Office Room 213	yes	Ceiling	Concrete	White	Chipping	1	0.04	Negative	None	0	Negative	No	No	no	no	
1	2	213	Climate Control Manager Office Room 213	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Negative	No	No	no	no	
1	2	213A	Climate Control Manager Office Room 213 Closet	yes	W1	CMU	Green	None	0	N/A	N/A	None	0	Negative	No	No	no	no	
1	2	213A	Climate Control Manager Office Room 213 Closet	yes	Door Frame	Metal	Tan	Chipping	4	0.21	Negative	None	0	Negative	No	No	no	no	

			School District of Philadelphia																				
			Name of Inspector: Jen Drialo		Lead Safe Certification Assessment Report							Inspection Dates: 9/20/21-10/7/21											
			Inspection Company: Synertech, Inc.		Gideon ES School							ULCS# 4530											
E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate	Color	Damage	Damage amount (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes				
1	2	213A	Climate Control Manager Office Room 213 Closet	yes	W2	CMU	Green	None	0	N/A	N/A	None	0	Negative	No	No	no	no					
1	2	213A	Climate Control Manager Office Room 213 Closet	yes	W3	CMU	Green	None	0	N/A	N/A	None	0	Negative	No	No	no	no					
1	2	213A	Climate Control Manager Office Room 213 Closet	yes	Shelves	Wood	Green	Chipping	1	0.15	Negative	None	0	Negative	No	No	no	no					
1	2	213A	Climate Control Manager Office Room 213 Closet	yes	W4	CMU	Green	None	0	N/A	N/A	None	0	Negative	No	No	no	no					
1	2	213A	Climate Control Manager Office Room 213 Closet	yes	Ceiling	Concrete	Green	None	0	N/A	N/A	None	0	Negative	No	No	no	no					
1	2	213A	Climate Control Manager Office Room 213 Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Negative	No	No	no	no					
1	2	208	Classroom 208	yes	W1	CMU	Grey	Chipping	2	0	Negative	None	0	Negative	No	No	no	no					
1	2	208	Classroom 208	yes	Door Frame	Metal	Grey	Friction	4	0.22	Negative	None	0	Negative	No	No	no	no					
1	2	208	Classroom 208	yes	W2	CMU	Grey	Chipping	1	0	Negative	None	0	Negative	No	No	no	no					
1	2	208	Classroom 208	yes	W3	CMU	Grey	Chipping	3	0	Negative	None	0	Negative	No	No	no	no					
1	2	208	Classroom 208	yes	Column	Concrete	Grey	Chipping	1	0.03	Negative	None	0	Negative	No	No	no	no					
1	2	208	Classroom 208	yes	Cabinet Top	Wood	Grey	Flaking	12	0.3	Negative	None	0	Negative	No	No	no	no					
1	2	208	Classroom 208	yes	Shelves	Metal	Grey	Friction	4	0.26	Negative	None	0	Negative	No	No	no	no					
1	2	208	Classroom 208	yes	Univent	Metal	Grey	Chipping	6	0.11	Negative	None	0	Negative	No	No	no	no					
1	2	208	Classroom 208	yes	W4	CMU	Blue	Chipping	1	0	Negative	None	0	Negative	No	No	no	no					
1	2	208	Classroom 208	yes	Ceiling	Concrete	White	Flaking	6	0.03	Negative	None	0	Negative	No	No	no	no					
1	2	208	Classroom 208	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Negative	No	No	no	no					
1	2	208A	Classroom 208 Closet	yes	W2	CMU	Grey	None	0	0	Negative	None	0	Negative	Partially Inaccessible	No	no	no					
1	2	208A	Classroom 208 Closet	yes	Partition	Wood	Grey	Chipping	1	1	Positive	None	0	Negative	No	No	no	no					
1	2	208A	Classroom 208 Closet	yes	Shelves	Wood	Grey	Friction	5	0.8	Positive	None	0	Negative	No	No	no	no	Several shelf paint chip samples were taken and the results were positive. Shelves in the classroom closets should be treated as homogenous.				
1	2	208A	Classroom 208 Closet	yes	W2	CMU	Grey	Chipping	1	0	Negative	None	0	Negative	No	No	no	no					
1	2	208A	Classroom 208 Closet	yes	W3	CMU	Grey	Chipping	2	0	Negative	None	0	Negative	Partially Inaccessible	No	no	no					
1	2	208A	Classroom 208 Closet	yes	W3	CMU	Grey	Chipping	1	0	Negative	None	0	Negative	No	No	no	no					
1	2	208A	Classroom 208 Closet	yes	W4	CMU	Grey	Chipping	1	0	Negative	None	0	Negative	Partially Inaccessible	No	no	no					
1	2	208A	Classroom 208 Closet	yes	W4	CMU	Grey	Chipping	1	0	Negative	None	0	Negative	No	No	no	no					
1	2	208A	Classroom 208 Closet	yes	Ceiling	Wood	Grey	None	0	N/A	N/A	None	0	Negative	No	No	no	no					
1	2	208A	Classroom 208 Closet	yes	Vent	Metal	Grey	Chipping	2	0.4	Negative	None	0	Negative	No	No	no	no					
1	2	208A	Classroom 208 Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Negative	No	No	no	no					
1	2	214A	Women's Restroom	yes	W1	CMU	Purple	Chipping	1	0.06	Negative	None	0	Negative	No	No	no	no					
1	2	214A	Women's Restroom	yes	Door Frame	Metal	Tan	Chipping	4	0	Negative	None	0	Negative	No	No	no	no					
1	2	214A	Women's Restroom	yes	W2	CMU	Purple	Flaking	1	0.08	Negative	None	0	Negative	No	No	no	no					
1	2	214A	Women's Restroom	yes	W3	CMU	Purple	Flaking	1	0.12	Negative	None	0	Negative	No	No	no	no					
1	2	214A	Women's Restroom	yes	W4	CMU	Purple	Chipping	1	0.06	Negative	None	0	Negative	No	No	no	no					
1	2	214A	Women's Restroom	yes	Ceiling	Concrete	White	Flaking	20	0.03	Negative	None	0	Negative	No	No	no	no					
1	2	214A	Women's Restroom	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Negative	No	No	no	no					
1	2	214	Girl's Restroom	yes	W1	CMU	Tan	Chipping	1	0	Negative	None	0	Negative	No	No	no	no					
1	2	214	Girl's Restroom	yes	Door Frame	Metal	Tan	Chipping	2	0.3	Negative	None	0	Negative	No	No	no	no					
1	2	214	Girl's Restroom	yes	W2	CMU	Tan	Chipping	2	0	Negative	None	0	Negative	No	No	no	no					
1	2	214	Girl's Restroom	yes	Transite Stall	Metal	Grey	None	N/A	0	Negative	None	0	Negative	No	No	no	no					
1	2	214	Girl's Restroom	yes	W3	CMU	Tan	Chipping	1	0	Negative	None	0	Negative	No	No	no	no					
1	2	214	Girl's Restroom	yes	Column	Concrete	Tan	None	0	N/A	N/A	None	0	Negative	No	No	no	no					
1	2	214	Girl's Restroom	yes	Univent	Metal	Grey	Chipping	3	0.16	Negative	None	0	Negative	No	No	no	no					
1	2	214	Girl's Restroom	yes	W4	CMU	Tan	Chipping	5	0	Negative	None	0	Negative	No	No	no	no					
1	2	214	Girl's Restroom	yes	Ceiling	Concrete	White	Flaking	100	0.02	Negative	None	0	Negative	No	No	no	no					
1	2	214	Girl's Restroom	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Negative	No	No	no	no					
1	2	215	Boy's Restroom	yes	W1	CMU	Tan	Chipping	1	0	Negative	None	0	Negative	No	No	no	no					
1	2	215	Boy's Restroom	yes	Door Frame	Metal	Tan	Chipping	2	0.3	Negative	None	0	Negative	No	No	no	no					
1	2	215	Boy's Restroom	yes	W2	CMU	Tan	Chipping	2	0	Negative	None	0	Negative	No	No	no	no					
1	2	215	Boy's Restroom	yes	Transite Stall	Metal	Grey	None	N/A	0	Negative	None	0	Negative	No	No	no	no					
1	2	215	Boy's Restroom	yes	W3	CMU	Tan	Chipping	1	0	Negative	None	0	Negative	No	No	no	no					
1	2	215	Boy's Restroom	yes	Column	Concrete	Tan	Chipping	1	0.5	inconclusive	None	0	Negative	No	No	no	no	Paint Chip Sampled, .46% Pb/Weight				
1	2	215	Boy's Restroom	yes	Univent	Metal	Grey	Chipping	3	0.16	Negative	None	0	Negative	No	No	no	no					
1	2	215	Boy's Restroom	yes	W4	CMU	Tan	Chipping	5	0	Negative	None	0	Negative	No	No	no	no					
1	2	215	Boy's Restroom	yes	Ceiling	Concrete	White	Flaking	100	0.02	Negative	None	0	Negative	No	No	no	no					
1	2	215	Boy's Restroom	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Negative	No	No	no	no					
1	2	H26A	Custodial Closet adjacent to Boy's Restroom	no	W1	CMU	Blue	Flaking	1	0	Negative	None	0	Negative	Partially Inaccessible	No	no	no					
1	2	H26A	Custodial Closet adjacent to Boy's Restroom	yes	Door Frame	Metal	Blue	Chipping	4	0.17	Negative	None	0	Negative	No	No	no	no					

			School District of Philadelphia																								
			Name of Inspector: Jen Drialo		Lead Safe Certification Assessment Report																						
			Inspection Company: Synertech, Inc.		Gideon ES School																						
E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate	Color	Damage	Damage amount (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes								
1	2	H26A	Custodial Closet adjacent to Boy's Restroom	no	W2	CMU	Blue	Chipping	2	0	Negative	None	0	Negative	Partially Inaccessible	No	no	no									
1	2	H26A	Custodial Closet adjacent to Boy's Restroom	no	W3	CMU	Blue	Chipping	4	0	Negative	None	0	Negative	Partially Inaccessible	No	no	no									
1	2	H26A	Custodial Closet adjacent to Boy's Restroom	no	W4	CMU	Blue	None	0	0	Negative	None	0	Negative	Partially Inaccessible	No	no	no									
1	2	H26A	Custodial Closet adjacent to Boy's Restroom	no	Ceiling	Concrete	White	Flaking	2	0.03	Negative	None	0	Negative	No	No	no	no									
1	2	H26A	Custodial Closet adjacent to Boy's Restroom	no	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Negative	No	No	no	no									
1	2	207	Classroom 207	yes	W1	CMU	Tan	Chipping	2	0.06	Negative	None	0	Negative	No	No	no	no									
1	2	207	Classroom 207	yes	W1	CMU	White	None	0	N/A	N/A	None	0	Negative	No	No	no	no									
1	2	207	Classroom 207	yes	Door Frame	Metal	Tan	Friction	4	0.22	Negative	None	0	Negative	No	No	no	no									
1	2	207	Classroom 207	yes	W2	CMU	Tan	Chipping	1	0	Negative	None	0	Negative	No	No	no	no									
1	2	207	Classroom 207	yes	W2	CMU	White	Chipping	2	0	Negative	None	0	Negative	No	No	no	no									
1	2	207	Classroom 207	yes	W3	CMU	Tan	Chipping	3	0	Negative	None	0	Negative	No	No	no	no									
1	2	207	Classroom 207	yes	W3	CMU	White	Chipping	1	0	Negative	None	0	Negative	No	No	no	no									
1	2	207	Classroom 207	yes	Column	Concrete	Tan	Chipping	1	0.03	Negative	None	0	Negative	No	No	no	no									
1	2	207	Classroom 207	yes	Cabinet Top	Wood	Tan	Flaking	12	0.3	Negative	None	0	Negative	No	No	no	no									
1	2	207	Classroom 207	yes	Shelves	Metal	Tan	Friction	4	0.26	Negative	None	0	Negative	No	No	no	no									
1	2	207	Classroom 207	yes	Univent	Metal	Tan	Chipping	6	0.11	Negative	None	0	Negative	No	No	no	no									
1	2	207	Classroom 207	yes	W4	CMU	Tan	Chipping	1	0	Negative	None	0	Negative	No	No	no	no									
1	2	207	Classroom 207	yes	W4	CMU	White	None	0	N/A	N/A	None	0	Negative	No	No	no	no									
1	2	207	Classroom 207	yes	Ceiling	Concrete	White	Flaking	6	0.03	Negative	None	0	Negative	No	No	no	no									
1	2	207	Classroom 207	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Negative	No	No	no	no									
1	2	207A	Classroom 207 Closet	yes	W2	CMU	Grey	None	0	0	Negative	None	0	Negative	Partially Inaccessible	No	no	no									
1	2	207A	Classroom 207 Closet	yes	Partition	Wood	Grey	Chipping	1	1	Positive	None	0	Negative	No	No	no	no									
1	2	207A	Classroom 207 Closet	yes	Shelves	Wood	Grey	Friction	5	0.4	Negative	None	0	Negative	No	No	no	no									
1	2	207A	Classroom 207 Closet	yes	W2	CMU	Grey	Chipping	1	0	Negative	None	0	Negative	No	No	no	no									
1	2	207A	Classroom 207 Closet	yes	W3	CMU	Grey	Chipping	2	0	Negative	None	0	Negative	Partially Inaccessible	No	no	no									
1	2	207A	Classroom 207 Closet	yes	W3	CMU	Grey	Chipping	1	0	Negative	None	0	Negative	No	No	no	no									
1	2	207A	Classroom 207 Closet	yes	W4	CMU	Grey	Chipping	1	0	Negative	None	0	Negative	Partially Inaccessible	No	no	no									
1	2	207A	Classroom 207 Closet	yes	W4	CMU	Grey	Chipping	1	0	Negative	None	0	Negative	No	No	no	no									
1	2	207A	Classroom 207 Closet	yes	Ceiling	Wood	Grey	None	0	N/A	N/A	None	0	Negative	No	No	no	no									
1	2	207A	Classroom 207 Closet	yes	Vent	Metal	Grey	Chipping	2	0.4	Negative	None	0	Negative	No	No	no	no									
1	2	207A	Classroom 207 Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Negative	No	No	no	no									
1	2	S25	Stairwell across from Classroom 207	yes	W1	CMU	Tan	Chipping	1	0.06	Negative	None	0	Negative	No	Unknown	no	no									
1	2	S25	Stairwell across from Classroom 207	yes	Door	Metal	Tan	Chipping	3	0	Negative	None	0	Negative	No	No	no	no									
1	2	S25	Stairwell across from Classroom 207	yes	Door Frame	Metal	Tan	Chipping	5	0.02	Negative	None	0	Negative	No	No	no	no									
1	2	S25	Stairwell across from Classroom 207	yes	W2	CMU	Tan	None	0	N/A	N/A	None	0	Negative	No	No	no	no									
1	2	S25	Stairwell across from Classroom 207	yes	Radiator	Metal	Grey	Chipping	1	0.04	Negative	None	0	Negative	No	No	no	no									
1	2	S25	Stairwell across from Classroom 207	yes	W3	CMU	Tan	Chipping	1	0.11	Negative	None	0	Negative	No	No	no	no									
1	2	S25	Stairwell across from Classroom 207	yes	Baluster	Metal	Orange	Chipping	3	4	Positive	None	0	Negative	No	No	no	no	At Window								
1	2	S25	Stairwell across from Classroom 207	yes	Column	Concrete	Tan	Chipping	3	0.07	Negative	None	0	Negative	No	No	no	no									
1	2	S25	Stairwell across from Classroom 207	yes	W4	CMU	Tan	Chipping	1	0.04	Negative	None	0	Negative	No	No	no	no									
1	2	S25	Stairwell across from Classroom 207	yes	Column	Concrete	Tan	Flaking	5	0.07	Negative	None	0	Negative	No	No	no	no									
1	2	S25	Stairwell across from Classroom 207	yes	Radiator	Metal	Grey	Chipping	1	0.1	Negative	None	0	Negative	No	No	no	no									
1	2	S25	Stairwell across from Classroom 207	yes	Ceiling	Metal	White	Chipping	5	2.5	Positive	None	0	Negative	No	Unknown	no	no									
1	2	S25	Stairwell across from Classroom 207	yes	Ceiling	Concrete	Tan	Flaking	3	0.06	Negative	None	0	Negative	No	Unknown	no	no									
1	2	S25	Stairwell across from Classroom 207	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Negative	No	No	no	no									
1	2	S25	Stairwell across from Classroom 207	yes	Open Stringer	Metal	Orange	Chipping	1	6	Positive	None	0	Negative	No	No	no	no									
1	2	S25	Stairwell across from Classroom 207	yes	Wall Stringer	Metal	Grey	Chipping	2	6.8	Positive	None	0	Negative	No	No	no	no									
1	2	S25	Stairwell across from Classroom 207	yes	Baluster	Metal	Orange	Chipping	10	4	Positive	None	0	Negative	No	No	no	no									

			School District of Philadelphia																								
			Name of Inspector: Jen Drialo		Lead Safe Certification Assessment Report																						
			Inspection Company: Synertech, Inc.		Gideon ES School																						
E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate	Color	Damage	Damage amount (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes								
1	2	S25	Stairwell across from Classroom 207	yes	Newel Post	Metal	Grey	Friction	4	7	Positive	None	0	Negative	No	No	no	no									
1	2	S25	Stairwell across from Classroom 207	yes	Riser	Metal	Grey	Chipping	3	3.5	Positive	None	0	Negative	No	No	no	no									
1	2	S25	Stairwell across from Classroom 207	yes	Handrail	Metal	Orange	Friction	4	3.7	Positive	None	0	Negative	No	No	no	no									
1	2	206	Classroom 206	yes	W1	CMU	Tan	Chipping	2	0.06	Negative	None	0	Negative	No	No	no	no									
1	2	206	Classroom 206	yes	W1	CMU	White	None	0	N/A	N/A	None	0	Negative	No	No	no	no									
1	2	206	Classroom 206	yes	Door Frame	Metal	Tan	Friction	2	0.13	Negative	None	0	Negative	No	No	no	no									
1	2	206	Classroom 206	yes	W2	CMU	Tan	Chipping	1	0	Negative	None	0	Negative	No	No	no	no									
1	2	206	Classroom 206	yes	W2	CMU	White	Chipping	2	0	Negative	None	0	Negative	No	No	no	no									
1	2	206	Classroom 206	yes	W3	CMU	Tan	Chipping	3	0	Negative	None	0	Negative	No	No	no	no									
1	2	206	Classroom 206	yes	W3	CMU	White	Chipping	1	0	Negative	None	0	Negative	No	No	no	no									
1	2	206	Classroom 206	yes	Column	Concrete	Tan	Chipping	1	0.03	Negative	None	0	Negative	No	No	no	no									
1	2	206	Classroom 206	yes	Cabinet Top	Wood	Tan	Flaking	12	0.3	Negative	None	0	Negative	No	No	no	no									
1	2	206	Classroom 206	yes	Shelves	Metal	Tan	Friction	4	0.26	Negative	None	0	Negative	No	No	no	no									
1	2	206	Classroom 206	yes	Univent	Metal	Tan	Chipping	6	0.11	Negative	None	0	Negative	No	No	no	no									
1	2	206	Classroom 206	yes	W4	CMU	Tan	Chipping	1	0	Negative	None	0	Negative	No	No	no	no									
1	2	206	Classroom 206	yes	W4	CMU	White	None	0	N/A	N/A	None	0	Negative	No	No	no	no									
1	2	206	Classroom 206	yes	Ceiling	Concrete	White	Flaking	6	0.03	Negative	None	0	Negative	No	No	no	no									
1	2	206	Classroom 206	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Negative	No	No	no	no									
1	2	206A	Classroom 206 Closet	yes	W2	CMU	Green	None	0	0	Negative	None	0	Negative	Partially Inaccessible	No	no	no									
1	2	206A	Classroom 206 Closet	yes	Partition	Wood	Green	Chipping	1	1	Positive	None	0	Negative	No	No	no	no									
1	2	206A	Classroom 206 Closet	yes	Shelves	Wood	Green	Friction	5	0.7	Positive	None	0	Negative	No	No	no	no	Several shelf paint chip samples were taken and the results were positive. Shelves in the classroom closets should be treated as homogenous.								
1	2	206A	Classroom 206 Closet	yes	W2	CMU	Tan	Chipping	1	0	Negative	None	0	Negative	No	No	no	no									
1	2	206A	Classroom 206 Closet	yes	W3	Wood	Green	Chipping	2	0	Negative	None	0	Negative	Partially Inaccessible	No	no	no									
1	2	206A	Classroom 206 Closet	yes	W3	CMU	Tan	Chipping	1	0	Negative	None	0	Negative	No	No	no	no									
1	2	206A	Classroom 206 Closet	yes	W4	Wood	Green	Chipping	1	0	Negative	None	0	Negative	Partially Inaccessible	No	no	no									
1	2	206A	Classroom 206 Closet	yes	W4	CMU	Tan	Chipping	1	0	Negative	None	0	Negative	No	No	no	no									
1	2	206A	Classroom 206 Closet	yes	Ceiling	Wood	Green	None	0	N/A	N/A	None	0	Negative	No	No	no	no									
1	2	206A	Classroom 206 Closet	yes	Vent	Metal	Tan	Chipping	2	0.4	Negative	None	0	Negative	No	No	no	no									
1	2	206A	Classroom 206 Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Negative	No	No	no	no									
1	2	215M	Fan Room next to Elevator	no	W1	CMU	Tan	Chipping	1	0	Negative	None	0	Negative	Partially Inaccessible	No	no	no									
1	2	215M	Fan Room next to Elevator	no	Column	Concrete	Tan	Chipping	2	0.04	Negative	None	0	Negative	Partially Inaccessible	No	no	no									
1	2	215M	Fan Room next to Elevator	no	W2	CMU	Tan	Flaking	1	0	Negative	None	0	Negative	Partially Inaccessible	No	no	no									
1	2	215M	Fan Room next to Elevator	no	W3	CMU	Tan	Chipping	2	0	Negative	None	0	Negative	Partially Inaccessible	No	no	no									
1	2	215M	Fan Room next to Elevator	no	W4	CMU	Tan	Chipping	1	0	Negative	None	0	Negative	Partially Inaccessible	No	no	no									
1	2	215M	Fan Room next to Elevator	no	Ceiling	Concrete	White	Flaking	2	0.03	Negative	None	0	Negative	No	No	no	no									
1	2	215M	Fan Room next to Elevator	no	Duct Work	Metal	Tan	Flaking	200	0.3	Negative	None	0	Negative	No	No	no	no									
1	2	215M	Fan Room next to Elevator	no	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Negative	No	No	no	no									
1	2	215E	Fan Room off Fan Room next to Elevator	no	W1	CMU	Tan	Chipping	1	0	Negative	None	0	Negative	Partially Inaccessible	No	no	no									
1	2	215E	Fan Room off Fan Room next to Elevator	no	W2	CMU	Tan	None	0	N/A	N/A	None	0	Negative	Partially Inaccessible	No	no	no									
1	2	215E	Fan Room off Fan Room next to Elevator	no	W3	CMU	Tan	Chipping	1	0	Negative	None	0	Negative	Partially Inaccessible	No	no	no									
1	2	215E	Fan Room off Fan Room next to Elevator	no	W4	CMU	Tan	Chipping	1	0	Negative	None	0	Negative	Partially Inaccessible	No	no	no									
1	2	215E	Fan Room off Fan Room next to Elevator	no	Ceiling	Concrete	White	Flaking	4	0.03	Negative	None	0	Negative	No	No	no	no									
1	2	215E	Fan Room next to Elevator	no	Fan Unit	Metal	Tan	Flaking	2	0.3	Negative	None	0	Negative	No	No	no	no									
1	2	205	Classroom 205	yes	W1	CMU	Tan	Chipping	2	0.06	Negative	None	0	Negative	No	No	no	no									
1	2	205	Classroom 205	yes	W1	CMU	White	None	0	N/A	N/A	None	0	Negative	No	No	no	no									
1	2	205	Classroom 205	yes	Door Frame	Metal	Tan	Friction	2	0.13	Negative	None	0	Negative	No	No	no	no									
1	2	205	Classroom 205	yes	W2	CMU	Tan	Chipping	1	0	Negative	None	0	Negative	No	No	no	no									
1	2	205	Classroom 205	yes	W2	CMU	White	Chipping	2	0	Negative	None	0	Negative	No	No	no	no									
1	2	205	Classroom 205	yes	W3	CMU	Tan	Chipping	3	0	Negative	None	0	Negative	No	No	no	no									
1	2	205	Classroom 205	yes	W3	CMU	White	Chipping	1	0	Negative	None	0	Negative	No	No	no	no									
1	2	205	Classroom 205	yes	Column	Concrete	Tan	Chipping	1	0.03	Negative	None	0	Negative	No	No	no	no									
1	2	205	Classroom 205	yes	Cabinet Top	Wood	Tan	Flaking	12	0.3	Negative	None	0	Negative	No	No	no	no									
1	2	205	Classroom 205	yes	Shelves	Metal	Tan	Friction	4	0.26	Negative	None	0	Negative	No	No	no	no									



			School District of Philadelphia																								
			Name of Inspector: Jen Drialo		Lead Safe Certification Assessment Report																						
			Inspection Company: Synertech, Inc.		Gideon ES School																						
E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate	Color	Damage	Damage amount (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes								
																				ULCS# 4530							
1	2	203A	Classroom 203 Closet	yes	W3	Wood	Green	Chipping	2	0	Negative	None	0	Negative	Partially Inaccessible	No	no	no									
1	2	203A	Classroom 203 Closet	yes	W3	CMU	Green	Chipping	1	0	Negative	None	0	Negative	No	No	no	no									
1	2	203A	Classroom 203 Closet	yes	W4	Wood	Green	Chipping	1	0	Negative	None	0	Negative	Partially Inaccessible	No	no	no									
1	2	203A	Classroom 203 Closet	yes	W4	CMU	Green	Chipping	1	0	Negative	None	0	Negative	No	No	no	no									
1	2	203A	Classroom 203 Closet	yes	Ceiling	Wood	Green	None	0	N/A	N/A	None	0	Negative	No	No	no	no									
1	2	203A	Classroom 203 Closet	yes	Vent	Metal	Green	Chipping	2	0.4	Negative	None	0	Negative	No	No	no	no									
1	2	203A	Classroom 203 Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Negative	No	No	no	no									
1	2	H25	Hallway from Classrooms 201 to 202	yes	W2	CMU	Yellow	Chipping	1	0.06	Negative	None	0	Negative	No	No	no	no									
1	2	H25	Hallway from Classrooms 201 to 202	yes	W2	CMU	White	None	0	N/A	N/A	None	0	Negative	No	No	no	no									
1	2	H25	Hallway from Classrooms 201 to 202	yes	Door	Metal	Blue	None	0	N/A	N/A	None	0	Negative	No	No	no	no									
1	2	H25	Hallway from Classrooms 201 to 202	yes	Door Frame	Metal	Blue	Chipping	3	0.4	Negative	None	0	Negative	No	No	no	no									
1	2	H25	Hallway from Classrooms 201 to 202	yes	Push Bar	Metal	Grey	Friction	1	0	Negative	None	0	Negative	No	No	no	no									
1	2	H25	Hallway from Classrooms 201 to 202	yes	W3	CMU	Yellow	Chipping	1	0	Negative	None	0	Negative	No	No	no	no									
1	2	H25	Hallway from Classrooms 201 to 202	yes	W3	CMU	White	Chipping	1	0	Negative	None	0	Negative	No	No	no	no									
1	2	H25	Hallway from Classrooms 201 to 202	yes	Door	Metal	Tan	None	0	N/A	N/A	None	0	Negative	No	No	no	no									
1	2	H25	Hallway from Classrooms 201 to 202	yes	Door Frame	Metal	Tan	Chipping	2	0.4	Negative	None	0	Negative	No	No	no	no									
1	2	H25	Hallway from Classrooms 201 to 202	yes	Radiator	CMU	Tan	Chipping	2	0.17	Negative	None	0	Negative	No	No	no	no									
1	2	H25	Hallway from Classrooms 201 to 202	yes	W4	CMU	Yellow	None	0	N/A	N/A	None	0	Negative	No	No	no	no									
1	2	H25	Hallway from Classrooms 201 to 202	yes	W4	CMU	White	Chipping	1	0	Negative	None	0	Negative	No	No	no	no									
1	2	H25	Hallway from Classrooms 201 to 202	yes	Ceiling	Concrete	White	Flaking	4	0.04	Negative	None	0	Negative	No	No	no	no									
1	2	H25	Hallway from Classrooms 201 to 202	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Negative	No	No	no	no									
1	2	S28	Stairwell adjacent to Classroom 202	yes	W1	CMU	Tan	None	0	N/A	N/A	None	0	Negative	No	No	no	no									
1	2	S28	Stairwell adjacent to Classroom 202	yes	Column	Concrete	White	Chipping	1	0.05	Negative	None	0	Negative	No	No	no	no									
1	2	S28	Stairwell adjacent to Classroom 202	yes	Door	Metal	Tan	Chipping	3	0	Negative	None	0	Negative	No	No	no	no									
1	2	S28	Stairwell adjacent to Classroom 202	yes	Door Frame	Metal	Tan	Chipping	1	0.14	Negative	None	0	Negative	No	No	no	no									
1	2	S28	Stairwell adjacent to Classroom 202	yes	Column	Concrete	Tan	Chipping	1	0.12	Negative	None	0	Negative	No	No	no	no									
1	2	S28	Stairwell adjacent to Classroom 202	yes	W2	CMU	Tan	Chipping	1	0.07	Negative	None	0	Negative	No	No	no	no									
1	2	S28	Stairwell adjacent to Classroom 202	yes	W2	Concrete	Tan	None	0	N/A	N/A	None	0	Negative	No	No	no	no									
1	2	S28	Stairwell adjacent to Classroom 202	yes	Baluster	Metal	Orange	Chipping	1	3.5	Positive	None	0	Negative	No	No	no	no									
1	2	S28	Stairwell adjacent to Classroom 202	yes	W3	CMU	Tan	None	0	N/A	N/A	None	0	Negative	No	No	no	no									
1	2	S28	Stairwell adjacent to Classroom 202	yes	W3	Concrete	Tan	Chipping	2	0.07	Negative	None	0	Negative	No	No	no	no									
1	2	S28	Stairwell adjacent to Classroom 202	yes	W4	CMU	Tan	Chipping	15	0.04	Negative	None	0	Negative	No	No	no	no									
1	2	S28	Stairwell adjacent to Classroom 202	yes	Door	Metal	Brown	Chipping	2	0	Negative	None	0	Negative	No	No	no	no									
1	2	S28	Stairwell adjacent to Classroom 202	yes	Door Frame	Metal	Brown	Friction	1	0.02	Negative	None	0	Negative	No	No	no	no									
1	2	S28	Stairwell adjacent to Classroom 202	yes	Radiator	Metal	Grey	Chipping	3	0.12	Negative	None	0	Negative	No	No	no	no									
1	2	S28	Stairwell adjacent to Classroom 202	yes	Ceiling	Metal	White	Flaking	4	2.5	Positive	None	0	Negative	No	No	no	no									
1	2	S28	Stairwell adjacent to Classroom 202	yes	Ceiling	Concrete	Tan	Flaking	1	0.12	Negative	None	0	Negative	No	No	no	no									
1	2	S28	Stairwell adjacent to Classroom 202	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Negative	No	No	no	no									
1	2	S28	Stairwell adjacent to Classroom 202	yes	Open Stringer	Metal	Orange	Chipping	1	6	Positive	None	0	Negative	No	No	no	no									
1	2	S28	Stairwell adjacent to Classroom 202	yes	Wall Stringer	Metal	Grey	Chipping	1	5.5	Positive	None	0	Negative	No	No	no	no									

			School District of Philadelphia																								
			Name of Inspector: Jen Drialo		Lead Safe Certification Assessment Report																						
			Inspection Company: Synertech, Inc.		Gideon ES School																						
E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate	Color	Damage	Damage amount (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes								
1	2	S28	Stairwell adjacent to Classroom 202	yes	Baluster	Metal	Orange	Chipping	2	3.5	Positive	None	0	Negative	No	No	no	no									
1	2	S28	Stairwell adjacent to Classroom 202	yes	Newel Post	Metal	Grey	Friction	4	6.8	Positive	None	0	Negative	No	No	no	no									
1	2	S28	Stairwell adjacent to Classroom 202	yes	Riser	Metal	Grey	Chipping	3	3.5	Positive	None	0	Negative	No	No	no	no									
1	2	S28	Stairwell adjacent to Classroom 202	yes	Handrail	Metal	Orange	Friction	6	3.7	Positive	None	0	Negative	No	No	no	no									
1	2	202	Classroom 202	yes	W1	CMU	Tan	Chipping	2	0	Negative	None	0	Negative	No	No	no	no									
1	2	202	Classroom 202	yes	W1	CMU	White	None	0	N/A	N/A	None	0	Negative	No	No	no	no									
1	2	202	Classroom 202	yes	Door Frame	Metal	Tan	Friction	6	0.15	Negative	None	0	Negative	No	No	no	no									
1	2	202	Classroom 202	yes	Corkboard	Wood	Brown	Chipping	5	1.4	Positive	None	0	Negative	No	No	no	no									
1	2	202	Classroom 202	yes	W2	CMU	Tan	Chipping	1	0	Negative	None	0	Negative	No	No	no	no									
1	2	202	Classroom 202	yes	W2	CMU	White	Chipping	1	0	Negative	None	0	Negative	No	No	no	no									
1	2	202	Classroom 202	yes	W3	CMU	Tan	Chipping	3	0	Negative	None	0	Negative	No	No	no	no									
1	2	202	Classroom 202	yes	W3	CMU	White	Chipping	2	0	Negative	None	0	Negative	No	No	no	no									
1	2	202	Classroom 202	yes	Pipe Riser	Metal	White	Chipping	2	2.1	Positive	None	0	Negative	No	No	no	no									
1	2	202	Classroom 202	yes	Pipe Riser	Metal	Tan	Chipping	1	2.1	Positive	None	0	Negative	No	No	no	no									
1	2	202	Classroom 202	yes	Column	Concrete	Tan	Chipping	1	0.03	Negative	None	0	Negative	No	No	no	no									
1	2	202	Classroom 202	yes	Cabinet Top	Wood	Tan	Flaking	12	0.23	Negative	None	0	Negative	No	No	no	no									
1	2	202	Classroom 202	yes	Shelves	Metal	Tan	Friction	4	0.08	Negative	None	0	Negative	No	No	no	no									
1	2	202	Classroom 202	yes	Univent	Metal	Tan	Chipping	6	0.16	Negative	None	0	Negative	No	No	no	no									
1	2	202	Classroom 202	yes	W4	CMU	Tan	Chipping	4	0	Negative	None	0	Negative	No	No	no	no									
1	2	202	Classroom 202	yes	W4	CMU	White	Chipping	2	0	Negative	None	0	Negative	No	No	no	no									
1	2	202	Classroom 202	yes	Ceiling	Concrete	White	Flaking	40	0.03	Negative	None	0	Negative	No	No	no	no									
1	2	202	Classroom 202	yes	Pipe	Metal	White	Flaking	1	0.26	Negative	None	0	Negative	No	No	no	no									
1	2	202	Classroom 202	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Negative	No	No	no	no									
1	2	202A	Classroom 202 Closet	yes	W2	CMU	Green	None	0	0	Negative	None	0	Negative	Partially Inaccessible	No	no	no									
1	2	202A	Classroom 202 Closet	yes	Partition	Wood	Green	Chipping	1	1	Positive	None	0	Negative	No	No	no	no									
1	2	202A	Classroom 202 Closet	yes	Shelves	Wood	Green	Friction	3	0.7	Positive	None	0	Negative	No	No	no	no	Several shelf paint chip samples were taken and the results were positive. Shelves in the classroom closets should be treated as homogenous.								
1	2	202A	Classroom 202 Closet	yes	W2	CMU	Tan	Chipping	1	0	Negative	None	0	Negative	No	No	no	no									
1	2	202A	Classroom 202 Closet	yes	W3	Wood	Green	Chipping	2	0	Negative	None	0	Negative	Partially Inaccessible	No	no	no									
1	2	202A	Classroom 202 Closet	yes	W3	CMU	Tan	Chipping	1	0	Negative	None	0	Negative	No	No	no	no									
1	2	202A	Classroom 202 Closet	yes	W4	Wood	Green	Chipping	1	0	Negative	None	0	Negative	Partially Inaccessible	No	no	no									
1	2	202A	Classroom 202 Closet	yes	W4	CMU	Tan	Chipping	1	0	Negative	None	0	Negative	No	No	no	no									
1	2	202A	Classroom 202 Closet	yes	Ceiling	Wood	Green	None	0	N/A	N/A	None	0	Negative	No	No	no	no									
1	2	202A	Classroom 202 Closet	yes	Vent	Metal	Tan	Chipping	2	0.4	Negative	None	0	Negative	No	No	no	no									
1	2	202A	Classroom 202 Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Negative	No	No	no	no									
1	2	201A	Storage 3	yes	W1	CMU	Tan	None	0	N/A	N/A	None	0	Negative	Partially Inaccessible	No	no	no	No Visible Damage								
1	2	201A	Storage 3	yes	Door Frame	Metal	Tan	Chipping	3	0.26	Negative	None	0	Negative	No	No	no	no									
1	2	201A	Storage 3	yes	W2	CMU	Tan	None	0	N/A	N/A	None	0	Negative	Partially Inaccessible	No	no	no	No Visible Damage								
1	2	201A	Storage 3	yes	W3	CMU	Tan	None	0	N/A	N/A	None	0	Negative	Partially Inaccessible	No	no	no	No Visible Damage/ Too cluttered to get a close look								
1	2	201A	Storage 3	yes	W4	CMU	Tan	None	0	N/A	N/A	None	0	Negative	Partially Inaccessible	No	no	no	No Visible Damage								
1	2	201A	Storage 3	yes	Ceiling	Concrete	White	None	0	N/A	N/A	None	0	Negative	No	No	no	no									
1	2	201A	Storage 3	yes	Floor	Concrete	Grey	Friction	120	0.22	Negative	None	0	Negative	No	No	no	no									
1	2	201	Classroom 201	yes	W1	CMU	Grey	Chipping	2	0.06	Negative	None	0	Negative	No	No	no	no									
1	2	201	Classroom 201	yes	Door Frame	Metal	Tan	Friction	2	0.13	Negative	None	0	Negative	No	No	no	no									
1	2	201	Classroom 201	yes	W2	CMU	Blue	Chipping	1	0	Negative	None	0	Negative	No	No	no	no									
1	2	201	Classroom 201	yes	W3	CMU	Grey	Chipping	1	0	Negative	None	0	Negative	No	No	no	no									
1	2	201	Classroom 201	yes	Column	Concrete	Grey	Chipping	1	0.03	Negative	None	0	Negative	No	No	no	no									
1	2	201	Classroom 201	yes	Cabinet Top	Wood	Grey	Flaking	12	0.3	Negative	None	0	Negative	No	No	no	no									
1	2	201	Classroom 201	yes	Shelves	Metal	Grey	Friction	4	0.26	Negative	None	0	Negative	No	No	no	no									
1	2	201	Classroom 201	yes	Univent	Metal	Grey	Chipping	6	0.11	Negative	None	0	Negative	No	No	no	no									
1	2	201	Classroom 201	yes	W4	CMU	Grey	Chipping	1	0	Negative	None	0	Negative	No	No	no	no									
1	2	201	Classroom 201	yes	Ceiling	Concrete	White	Flaking	10	0.03	Negative	None	0	Negative	No	No	no	no									
1	2	201	Classroom 201	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Negative	No	No	no	no									
1	2	201B	Classroom 201 Closet with double doors	yes	Door Frame	Metal	Grey	Chipping	2	0.12	Negative	None	0	Negative	No	No	no	no									
1	2	201B	Classroom 201 Closet with double doors	yes	W2	CMU	Grey	None	0	N/A	N/A	None	0	Negative	No	No	no	no									
1	2	201B	Classroom 201 Closet with double doors	yes	W3	CMU	Grey	None	0	N/A	N/A	None	0	Negative	No	No	no	no									

				School District of Philadelphia																	
			Name of Inspector: Jen Drialo		Lead Safe Certification Assessment Report								Inspection Dates: 9/20/21-10/7/21								
			Inspection Company: Synertech, Inc.		Gideon ES School								ULCS# 4530								
E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate	Color	Damage	Damage amount (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes		
1	2	201B	Classroom 201 Closet with double doors	yes	W4	CMU	Grey	None	0	N/A	N/A	None	0	Negative	No	No	no	no			
1	2	201B	Classroom 201 Closet with double doors	yes	Ceiling	Wood	Grey	None	0	N/A	N/A	None	0	Negative	No	No	no	no			
1	2	201B	Classroom 201 Closet with double doors	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Negative	No	No	no	no			
1	2	201C	Classroom 201 Closet by entrance	yes	W2	CMU	White	None	0	0	Negative	None	0	Negative	Partially Inaccessible	No	no	no			
1	2	201C	Classroom 201 Closet by entrance	yes	Partition	Wood	Grey	Chipping	1	1	Positive	None	0	Negative	No	No	no	no			
1	2	201C	Classroom 201 Closet by entrance	yes	Shelves	Wood	Grey	Friction	3	0.7	Positive	None	0	Negative	No	No	no	no	Several shelf paint chip samples were taken and the results were positive. Shelves in the classroom closets should be treated as homogenous.		
1	2	201C	Classroom 201 Closet by entrance	yes	W2	CMU	White	Chipping	1	0	Negative	None	0	Negative	No	No	no	no			
1	2	201C	Classroom 201 Closet by entrance	yes	W3	CMU	White	Chipping	1	0	Negative	None	0	Negative	No	No	no	no			
1	2	201C	Classroom 201 Closet by entrance	yes	W4	CMU	White	Chipping	1	0	Negative	None	0	Negative	No	No	no	no			
1	2	201C	Classroom 201 Closet by entrance	yes	Ceiling	Wood	White	None	0	N/A	N/A	None	0	Negative	No	No	no	no			
1	2	201C	Classroom 201 Closet by entrance	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Negative	No	No	no	no			
1	2	H26	Hallway from Classrooms 204 to 210	yes	W1	CMU	Yellow	Chipping	2	0	Negative	None	0	Negative	No	No	no	no			
1	2	H26	Hallway from Classrooms 204 to 210	yes	W1	CMU	White	None	0	N/A	N/A	None	0	Negative	No	No	no	no			
1	2	H26	Hallway from Classrooms 204 to 210	yes	W2	CMU	Yellow	Chipping	1	0	Negative	None	0	Negative	No	No	no	no			
1	2	H26	Hallway from Classrooms 204 to 210	yes	W2	CMU	White	None	0	N/A	N/A	None	0	Negative	No	No	no	no			
1	2	H26	Hallway from Classrooms 204 to 210	yes	W3	CMU	Yellow	Chipping	1	0	Negative	None	0	Negative	No	No	no	no			
1	2	H26	Hallway from Classrooms 204 to 210	yes	W3	CMU	White	Chipping	1	0	Negative	None	0	Negative	No	No	no	no			
1	2	H26	Hallway from Classrooms 204 to 210	yes	Radiator	CMU	Tan	Chipping	2	0.07	Negative	None	0	Negative	No	No	no	no			
1	2	H26	Hallway from Classrooms 204 to 210	yes	Pipe	Metal	Tan	Chipping	1	0.25	Negative	None	0	Negative	No	No	no	no			
1	2	H26	Hallway from Classrooms 204 to 210	yes	W4	CMU	Yellow	None	0	N/A	N/A	None	0	Negative	No	No	no	no			
1	2	H26	Hallway from Classrooms 204 to 210	yes	W4	CMU	White	Chipping	1	0	Negative	None	0	Negative	No	No	no	no			
1	2	H26	Hallway from Classrooms 204 to 210	yes	Ceiling	Concrete	White	Flaking	4	0.06	Negative	None	0	Negative	No	No	no	no			
1	2	H26	Hallway from Classrooms 204 to 210	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Negative	No	No	no	no			
1	2	S26	Stairwell adjacent to Classroom 201	yes	W1	CMU	Tan	Chipping	2	0.07	Negative	None	0	Negative	No	No	no	no			
1	2	S26	Stairwell adjacent to Classroom 201	yes	Door	Metal	Tan	N/A	N/A	N/A	N/A	None	0	Negative	No	No	no	no			
1	2	S26	Stairwell adjacent to Classroom 201	yes	Door Frame	Metal	Tan	Chipping	2	0.02	Negative	None	0	Negative	No	No	no	no			
1	2	S26	Stairwell adjacent to Classroom 201	yes	W2	CMU	Tan	None	0	N/A	N/A	None	0	Negative	No	No	no	no			
1	2	S26	Stairwell adjacent to Classroom 201	yes	W3	CMU	Tan	Chipping	1	0.11	Negative	None	0	Negative	No	No	no	no			
1	2	S26	Stairwell adjacent to Classroom 201	yes	Baluster	Metal	Orange	Chipping	2	4	Positive	None	0	Negative	No	No	no	no			
1	2	S26	Stairwell adjacent to Classroom 201	yes	Column	Concrete	Tan	Chipping	3	0.07	Negative	None	0	Negative	No	No	no	no			
1	2	S26	Stairwell adjacent to Classroom 201	yes	W4	CMU	Tan	Chipping	1	0.04	Negative	None	0	Negative	No	No	no	no			
1	2	S26	Stairwell adjacent to Classroom 201	yes	Radiator	Metal	Grey	Chipping	1	0.1	Negative	None	0	Negative	No	No	no	no			
1	2	S26	Stairwell adjacent to Classroom 201	yes	Ceiling	Metal	White	None	0	N/A	N/A	None	0	Negative	No	No	no	no			
1	2	S26	Stairwell adjacent to Classroom 201	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Negative	No	No	no	no			
1	2	S26	Stairwell adjacent to Classroom 201	yes	Open Stringer	Metal	Orange	Chipping	2	6	Positive	None	0	Negative	No	No	no	no			
1	2	S26	Stairwell adjacent to Classroom 201	yes	Wall Stringer	Metal	Grey	Chipping	4	6.8	Positive	None	0	Negative	No	No	no	no			
1	2	S26	Stairwell adjacent to Classroom 201	yes	Baluster	Metal	Orange	Chipping	10	4	Positive	None	0	Negative	No	No	no	no			

			School District of Philadelphia																					
			Name of Inspector: Jen Drialo		Lead Safe Certification Assessment Report																Inspection Dates: 9/20/21-10/7/21			
			Inspection Company: Synertech, Inc.		Gideon ES School																ULCS# 4530			
E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate	Color	Damage	Damage amount (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes					
1	2	S26	Stairwell adjacent to Classroom 201	yes	Newel Post	Metal	Grey	Friction	4	7	Positive	None	0	Negative	No	No	no	no						
1	2	S26	Stairwell adjacent to Classroom 201	yes	Riser	Metal	Grey	Chipping	3	3.5	Positive	None	0	Negative	No	No	no	no						
1	2	S26	Stairwell adjacent to Classroom 201	yes	Handrail	Metal	Orange	Friction	4	3.7	Positive	None	0	Negative	No	No	no	no						
1	2	217	Custodial Storage off Stairwell adjacent to Classroom 201	no	W1	CMU	Tan	Chipping	1	0	Negative	None	0	Negative	No	No	no	no						
1	2	217	Custodial Storage off Stairwell adjacent to Classroom 201	no	Door Frame	Metal	Tan	Chipping	10	0.16	Negative	None	0	Negative	No	No	no	no						
1	2	217	Custodial Storage off Stairwell adjacent to Classroom 201	no	W2	CMU	Tan	Chipping	2	0.06	Negative	None	0	Negative	No	No	no	no						
1	2	217	Custodial Storage off Stairwell adjacent to Classroom 201	no	W3	CMU	Tan	Chipping	1	0	Negative	None	0	Negative	No	No	no	no						
1	2	217	Custodial Storage off Stairwell adjacent to Classroom 201	no	W4	CMU	Tan	None	0	N/A	N/A	None	0	Negative	No	No	no	no						
1	2	217	Custodial Storage off Stairwell adjacent to Classroom 201	no	Ceiling	Concrete	White	Chipping	5	0.03	Negative	None	0	Negative	No	No	no	no						
1	2	217	Custodial Storage off Stairwell adjacent to Classroom 201	no	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Negative	No	No	no	no						
1	1	S16	Stairwell adjacent to Classroom 101	yes	W1	CMU	Tan	Flaking	2	0.07	Negative	None	0	Negative	No	No	no	no						
1	1	S16	Stairwell adjacent to Classroom 101	yes	Column	Concrete	White	Chipping	3	0.05	Negative	None	0	Negative	No	No	no	no						
1	1	S16	Stairwell adjacent to Classroom 101	yes	Door	Metal	Blue	None	N/A	N/A	N/A	None	0	Negative	No	No	no	no						
1	1	S16	Stairwell adjacent to Classroom 101	yes	Door Frame	Metal	Blue	Chipping	1	0.14	Negative	None	0	Negative	No	No	no	no						
1	1	S16	Stairwell adjacent to Classroom 101	yes	Column	Concrete	Tan	Chipping	1	0.12	Negative	None	0	Negative	No	No	no	no						
1	1	S16	Stairwell adjacent to Classroom 101	yes	W2	CMU	Tan	Chipping	10	0.07	Negative	None	0	Negative	No	No	no	no						
1	1	S16	Stairwell adjacent to Classroom 101	yes	Radiator	Metal	Grey	Chipping	3	0.12	Negative	None	0	Negative	No	No	no	no						
1	1	S16	Stairwell adjacent to Classroom 101	yes	W3	CMU	Tan	Chipping	1	0.06	Negative	None	0	Negative	No	No	no	no						
1	1	S16	Stairwell adjacent to Classroom 101	yes	Door	Metal	Brown	Chipping	6	0	Negative	None	0	Negative	No	No	no	no						
1	1	S16	Stairwell adjacent to Classroom 101	yes	Door Frame	Metal	Brown	Friction	10	0.02	Negative	None	0	Negative	No	No	no	no						
1	1	S16	Stairwell adjacent to Classroom 101	yes	Column	Concrete	Tan	Chipping	1	0.07	Negative	None	0	Negative	No	No	no	no						
1	1	S16	Stairwell adjacent to Classroom 101	yes	W4	CMU	Tan	Chipping	15	0.04	Negative	None	0	Negative	No	No	no	no						
1	1	S16	Stairwell adjacent to Classroom 101	yes	Radiator	Metal	Grey	Chipping	3	0.12	Negative	None	0	Negative	No	No	no	no						
1	1	S16	Stairwell adjacent to Classroom 101	yes	Ceiling	Metal	White	Efflorescence	1	2.5	Positive	None	0	Negative	No	Unknown	no	no						
1	1	S16	Stairwell adjacent to Classroom 101	yes	Ceiling	Concrete	Tan	None	0	N/A	N/A	None	0	Negative	No	No	no	no						
1	1	S16	Stairwell adjacent to Classroom 101	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Negative	No	No	no	no						
1	1	S16	Stairwell adjacent to Classroom 101	yes	Open Stringer	Metal	Orange	Chipping	1	6	Positive	None	0	Negative	No	No	no	no						
1	1	S16	Stairwell adjacent to Classroom 101	yes	Wall Stringer	Metal	Grey	Chipping	1	5.5	Positive	None	0	Negative	No	No	no	no						
1	1	S16	Stairwell adjacent to Classroom 101	yes	Baluster	Metal	Orange	Chipping	2	3.5	Positive	None	0	Negative	No	No	no	no						
1	1	S16	Stairwell adjacent to Classroom 101	yes	Newel Post	Metal	Grey	Friction	4	6.8	Positive	None	0	Negative	No	No	no	no						
1	1	S16	Stairwell adjacent to Classroom 101	yes	Riser	Metal	Grey	Chipping	3	3.5	Positive	None	0	Negative	No	No	no	no						
1	1	S16	Stairwell adjacent to Classroom 101	yes	Handrail	Metal	Orange	Friction	4	3.7	Positive	None	0	Negative	No	No	no	no						
1	1	S17	Auditorium Entrance across from Classroom 101	yes	W1	CMU	Green	None	0	N/A	N/A	None	0	Negative	No	No	no	no						
1	1	S17	Auditorium Entrance across from Classroom 101	yes	Door	Metal	Tan	None	0	N/A	N/A	None	0	Negative	No	No	no	no						
1	1	S17	Auditorium Entrance across from Classroom 101	yes	Door Frame	Metal	Tan	Chipping	3	0.23	Negative	None	0	Negative	No	No	no	no						
1	1	S17	Auditorium Entrance across from Classroom 101	yes	W2	CMU	Green	Chipping	1	0	Negative	None	0	Negative	No	No	no	no						
1	1	S17	Auditorium Entrance across from Classroom 101	yes	Door	Metal	Tan	None	0	N/A	N/A	None	0	Negative	No	No	no	no						
1	1	S17	Auditorium Entrance across from Classroom 101	yes	Door Frame	Metal	Tan	Chipping	1	0.18	Negative	None	0	Negative	No	No	no	no						

			School District of Philadelphia																				
			Name of Inspector: Jen Drialo		Lead Safe Certification Assessment Report							Inspection Dates: 9/20/21-10/7/21											
			Inspection Company: Synertech, Inc.		Gideon ES School							ULCS# 4530											
E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate	Color	Damage	Damage amount (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes				
1	1	S17	Auditorium Entrance across from Classroom 101	yes	W3	CMU	Green	None	0	N/A	N/A	None	0	Negative	No	No	no	no					
1	1	S17	Auditorium Entrance across from Classroom 101	yes	Door	Metal	Tan	None	0	N/A	N/A	None	0	Negative	No	No	no	no					
1	1	S17	Auditorium Entrance across from Classroom 101	yes	Door Frame	Metal	Tan	Chipping	1	0.21	Negative	None	0	Negative	No	No	no	no					
1	1	S17	Auditorium Entrance across from Classroom 101	yes	W4	CMU	Green	None	0	N/A	N/A	None	0	Negative	No	No	no	no					
1	1	S17	Auditorium Entrance across from Classroom 101	yes	Ceiling	Metal	White	Flaking	2	0.02	Negative	None	0	Negative	No	No	no	no					
1	1	S17	Auditorium Entrance across from Classroom 101	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Negative	No	No	no	no					
1	1	S17	Auditorium Entrance across from Classroom 101	yes	Stair tread	Concrete	Red	Friction	50	0.1	Negative	None	0	Negative	No	No	no	no					
1	1	116	Auditorium	yes	W1	CMU	Yellow	None	0	N/A	N/A	None	0	Negative	No	No	no	no					
1	1	116	Auditorium	yes	W1	CMU	White	None	1	0	Negative	None	0	Negative	No	No	no	no					
1	1	116	Auditorium	yes	Door	Metal	Blue	None	0	N/A	N/A	None	0	Negative	No	No	no	no					
1	1	116	Auditorium	yes	Door Frame	Metal	Blue	Chipping	1	0.1	Negative	None	0	Negative	No	No	no	no					
1	1	116	Auditorium	yes	W2	CMU	Yellow	Chipping	1	0	Negative	None	0	Negative	No	No	no	no					
1	1	116	Auditorium	yes	W2	CMU	White	None	0	N/A	N/A	None	0	Negative	No	No	no	no					
1	1	116	Auditorium	yes	Mural	CMU	Blue	Chipping	2	0.04	Negative	None	0	Negative	No	No	no	no					
1	1	116	Auditorium	yes	Chairs	Metal	Blue	None	0	0.25	Negative	None	0	Negative	No	No	no	no					
1	1	116	Auditorium	yes	Chairs	Metal	Green	None	0	0.25	Negative	None	0	Negative	No	No	no	no					
1	1	116	Auditorium	yes	W3	CMU	Yellow	None	0	N/A	N/A	None	0	Negative	No	No	no	no					
1	1	116	Auditorium	yes	W3	CMU	White	None	0	N/A	N/A	None	0	Negative	No	No	no	no					
1	1	116	Auditorium	yes	Door	Metal	Blue	Chipping	1	0.23	Negative	None	0	Negative	No	No	no	no					
1	1	116	Auditorium	yes	Door Frame	Metal	Blue	Friction	1	0.24	Negative	None	0	Negative	No	No	no	no					
1	1	116	Auditorium	yes	Push Bar	Metal	Grey	Chipping	1	0	Negative	None	0	Negative	No	No	no	no					
1	1	116	Auditorium	yes	Stage Vent	Metal	Brown	Chipping	2	0.27	Negative	None	0	Negative	No	No	no	no					
1	1	116	Auditorium	yes	Stage Cove Base	Vinyl	Black	Chipping	2	0.14	Negative	None	0	Negative	No	No	no	no					
1	1	116	Auditorium	yes	W4	CMU	Yellow	None	0	0.09	Negative	None	0	Negative	No	No	no	no					
1	1	116	Auditorium	yes	W4	CMU	White	None	0	0.09	Negative	None	0	Negative	No	No	no	no					
1	1	116	Auditorium	yes	Radiator	Metal	Yellow	Chipping	1	0.07	Negative	None	0	Negative	No	No	no	no					
1	1	116	Auditorium	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Negative	No	No	no	no	1x1 Ceiling Tile				
1	1	116	Auditorium	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Negative	No	No	no	no	12 x 12 Floor Tile				
1	1	116S	Stage	yes	W1	CMU	White	None	0	N/A	N/A	None	0	Negative	No	No	no	no					
1	1	116S	Stage	yes	Door Frame	Metal	Tan	Chipping	2	0.4	Negative	None	0	Negative	No	No	no	no					
1	1	116S	Stage	yes	W2	CMU	White	None	0	N/A	N/A	None	0	Negative	Partially Inaccessible	No	no	no					
1	1	116S	Stage	yes	W3	CMU	White	None	0	N/A	N/A	None	0	Negative	Partially Inaccessible	No	no	no					
1	1	116S	Stage	yes	W4	CMU	White	None	0	N/A	N/A	None	0	Negative	Partially Inaccessible	No	no	no					
1	1	116S	Stage	yes	Door	Metal	Brown	None	0	N/A	N/A	None	0	Negative	No	No	no	no					
1	1	116S	Stage	yes	Door Frame	Metal	Brown	Chipping	3	0.25	Negative	None	0	Negative	No	No	no	no					
1	1	116S	Stage	yes	Ceiling	Concrete	White	None	0	N/A	N/A	None	0	Negative	No	No	no	no					
1	1	116S	Stage	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Negative	No	No	no	no					
1	1	116A	Stage Closet	yes	W1	CMU	Tan	Chipping	1	0	Negative	None	0	Negative	Partially Inaccessible	No	no	no					
1	1	116A	Stage Closet	yes	Door Frame	Metal	Tan	Chipping	4	0.23	Negative	None	0	Negative	No	No	no	no					
1	1	116A	Stage Closet	yes	W2	CMU	Tan	Chipping	2	0	Negative	None	0	Negative	Partially Inaccessible	No	no	no					
1	1	116A	Stage Closet	yes	W3	CMU	Tan	None	0	N/A	N/A	None	0	Negative	Partially Inaccessible	No	no	no					
1	1	116A	Stage Closet	yes	W4	CMU	Tan	Chipping	2	0	Negative	None	0	Negative	Partially Inaccessible	No	no	no					
1	1	116A	Stage Closet	yes	Ceiling	Concrete	White	Flaking	15	0.02	Negative	None	0	Negative	No	No	no	no					
1	1	116A	Stage Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Negative	No	No	no	no					
1	1	S14	Auditorium Exit to Exterior	yes	W1	CMU	Green	None	0	N/A	N/A	None	0	Negative	No	No	no	no					
1	1	S14	Auditorium Exit to Exterior	yes	Door	Metal	Tan	None	0	N/A	N/A	None	0	Negative	No	No	no	no					
1	1	S14	Auditorium Exit to Exterior	yes	Door Frame	Metal	Tan	Chipping	6	0.23	Negative	None	0	Negative	No	No	no	no					
1	1	S14	Auditorium Exit to Exterior	yes	W2	CMU	Green	Flaking	25	0	Negative	None	0	Negative	No	No	no	no					
1	1	S14	Auditorium Exit to Exterior	yes	Door	Metal	Tan	None	0	N/A	N/A	None	0	Negative	No	No	no	no					
1	1	S14	Auditorium Exit to Exterior	yes	Door Frame	Metal	Tan	Chipping	1	0.18	Negative	None	0	Negative	No	No	no	no					
1	1	S14	Auditorium Exit to Exterior	yes	W3	CMU	Green	None	0	N/A	N/A	None	0	Negative	No	No	no	no					
1	1	S14	Auditorium Exit to Exterior	yes	Door	Metal	Tan	None	0	N/A	N/A	None	0	Negative	No	No	no	no					
1	1	S14	Auditorium Exit to Exterior	yes	Door Frame	Metal	Tan	Chipping	1	0.21	Negative	None	0	Negative	No	No	no	no					
1	1	S14	Auditorium Exit to Exterior	yes	W4	CMU	Green	None	0	N/A	N/A	None	0	Negative	No	No	no	no					
1	1	S14	Auditorium Exit to Exterior	yes	Ceiling	Metal	White	Flaking	30	0.02	Negative	None	0	Negative	No	No	no	no					

			School District of Philadelphia																				
			Name of Inspector: Jen Drialo		Lead Safe Certification Assessment Report							Inspection Dates: 9/20/21-10/7/21											
			Inspection Company: Synertech, Inc.		Gideon ES School							ULCS# 4530											
E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate	Color	Damage	Damage amount (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes				
1	1	S14	Auditorium Exit to Exterior	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Negative	No	No	no	no					
1	1	S14	Auditorium Exit to Exterior	yes	Stair tread	Concrete	Red	Friction	100	0.1	Negative	None	0	Negative	No	No	no	no					
1	1	H11	Hallway from Classroom 101 to Girl's Restroom	yes	W1	CMU	Yellow	Chipping	4	0	Negative	None	0	Negative	No	No	no	no					
1	1	H11	Hallway from Classroom 101 to Girl's Restroom	yes	W1	CMU	White	None	2	0.05	Negative	None	0	Negative	No	No	no	no					
1	1	H11	Hallway from Classroom 101 to Girl's Restroom	yes	Conduit	Metal	Yellow	Chipping	2	0.03	Negative	None	0	Negative	No	No	no	no					
1	1	H11	Hallway from Classroom 101 to Girl's Restroom	yes	W2	CMU	Yellow	Chipping	1	0	Negative	None	0	Negative	No	No	no	no					
1	1	H11	Hallway from Classroom 101 to Girl's Restroom	yes	W2	CMU	White	None	0	N/A	N/A	None	0	Negative	No	No	no	no					
1	1	H11	Hallway from Classroom 101 to Girl's Restroom	yes	W3	CMU	Yellow	None	0	N/A	N/A	None	0	Negative	No	No	no	no					
1	1	H11	Hallway from Classroom 101 to Girl's Restroom	yes	W3	CMU	White	None	0	N/A	N/A	None	0	Negative	No	No	no	no					
1	1	H11	Hallway from Classroom 101 to Girl's Restroom	yes	Door	Metal	Blue	None	0	N/A	N/A	None	0	Negative	No	No	no	no					
1	1	H11	Hallway from Classroom 101 to Girl's Restroom	yes	Door Frame	Metal	Blue	Chipping	1	0.17	Negative	None	0	Negative	No	No	no	no					
1	1	H11	Hallway from Classroom 101 to Girl's Restroom	yes	Push Bar	Metal	Grey	Friction	1	0	Negative	None	0	Negative	No	No	no	no					
1	1	H11	Hallway from Classroom 101 to Girl's Restroom	yes	Pipe Riser	Metal	Yellow	Chipping	2	0.25	Negative	None	0	Negative	No	No	no	no					
1	1	H11	Hallway from Classroom 101 to Girl's Restroom	yes	W4	CMU	Yellow	None	0	N/A	N/A	None	0	Negative	No	No	no	no					
1	1	H11	Hallway from Classroom 101 to Girl's Restroom	yes	W4	CMU	White	Chipping	1	0	Negative	None	0	Negative	No	No	no	no					
1	1	H11	Hallway from Classroom 101 to Girl's Restroom	yes	Door	Metal	Blue	None	0	N/A	N/A	None	0	Negative	No	No	no	no					
1	1	H11	Hallway from Classroom 101 to Girl's Restroom	yes	Door Frame	Metal	Blue	Chipping	1	0.27	Negative	None	0	Negative	No	No	no	no					
1	1	H11	Hallway from Classroom 101 to Girl's Restroom	yes	Radiator	CMU	Blue	Chipping	4	0.17	Negative	None	0	Negative	No	No	no	no					
1	1	H11	Hallway from Classroom 101 to Girl's Restroom	yes	Electrical Panel	Metal	Yellow	Chipping	1	0.3	Negative	None	0	Negative	No	No	no	no					
1	1	H11	Hallway from Classroom 101 to Girl's Restroom	yes	Ceiling	Concrete	White	Flaking	4	0.04	Negative	None	0	Negative	No	No	no	no					
1	1	H11	Hallway from Classroom 101 to Girl's Restroom	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Negative	No	No	no	no					
1	1	101	Education Works Room 101	yes	W1	CMU	Blue	Flaking	2	0	Negative	None	0	Negative	No	No	no	no					
1	1	101	Education Works Room 101	yes	Door Frame	Metal	Blue	Chipping	10	0	Negative	None	0	Negative	No	No	no	no					
1	1	101	Education Works Room 101	yes	W2	CMU	Blue	Chipping	2	0	Negative	None	0	Negative	No	No	no	no					
1	1	101	Education Works Room 101	yes	W3	CMU	Blue	Chipping	1	0	Negative	None	0	Negative	Partially Inaccessible	No	no	no					
1	1	101	Education Works Room 101	yes	Pipe	Metal	Tan	Chipping	2	0.5	Negative	None	0	Negative	No	No	no	no					
1	1	101	Education Works Room 101	yes	Column	Concrete	Blue	Flaking	1	0.1	Negative	None	0	Negative	No	No	no	no					
1	1	101	Education Works Room 101	yes	Cabinet Top	Wood	Blue	Flaking	20	0.25	Negative	None	0	Negative	No	No	no	no					
1	1	101	Education Works Room 101	yes	Shelves	Metal	Blue	Friction	10	0.15	Negative	None	0	Negative	No	No	no	no					
1	1	101	Education Works Room 101	yes	Univent	Metal	Blue	Chipping	1	0	Negative	None	0	Negative	No	No	no	no					
1	1	101	Education Works Room 101	yes	W4	CMU	Blue	Chipping	1	0	Negative	None	0	Negative	No	No	no	no					
1	1	101	Education Works Room 101	yes	Teacher's Desk	Wood	Blue	Chipping	20	0.06	Negative	None	0	Negative	No	No	no	no					
1	1	101	Education Works Room 101	yes	Ceiling	Concrete	White	Flaking	60	0.03	Negative	None	0	Negative	No	No	no	no					
1	1	101	Education Works Room 101	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Negative	No	No	no	no					
1	1	101A	Education Works Room 101 Closet	yes	Door Frame	Metal	Tan	Chipping	2	0.17	Negative	None	0	Negative	No	No	no	no					
1	1	101A	Education Works Room 101 Closet	yes	W2	CMU	Tan	None	0	N/A	N/A	None	0	Negative	Partially Inaccessible	No	no	no					
1	1	101A	Education Works Room 101 Closet	yes	W3	CMU	Tan	Flaking	1	0	Negative	None	0	Negative	Partially Inaccessible	No	no	no					
1	1	101A	Education Works Room 101 Closet	yes	W4	CMU	Tan	None	0	N/A	N/A	None	0	Negative	No	No	no	no					
1	1	101A	Education Works Room 101 Closet	yes	Ceiling	Concrete	White	None	0	N/A	N/A	None	0	Negative	No	No	no	no					
1	1	101A	Education Works Room 101 Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Negative	No	No	no	no					
1	1	117A	Closet next to Auditorium Entrance	yes	W1	CMU	White	None	0	N/A	N/A	None	0	Negative	No	No	no	no					
1	1	117A	Closet next to Auditorium Entrance	yes	Door Frame	Metal	Tan	Chipping	1	0.25	Negative	None	0	Negative	No	No	no	no					
1	1	117A	Closet next to Auditorium Entrance	yes	W2	CMU	White	Chipping	1	0	Negative	None	0	Negative	No	No	no	no					
1	1	117A	Closet next to Auditorium Entrance	yes	Shelves	Wood	White	Friction	2	0.4	Negative	None	0	Negative	No	No	no	no					

			School District of Philadelphia																								
			Name of Inspector: Jen Drialo		Lead Safe Certification Assessment Report																						
			Inspection Company: Synertech, Inc.		Gideon ES School																						
E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate	Color	Damage	Damage amount (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes								
1	1	117A	Closet next to Auditorium Entrance	yes	W3	CMU	White	None	0	N/A	N/A	None	0	Negative	No	No	no	no									
1	1	117A	Closet next to Auditorium Entrance	yes	W4	CMU	White	None	0	N/A	N/A	None	0	Negative	No	No	no	no									
1	1	117A	Closet next to Auditorium Entrance	yes	Ceiling	Concrete	White	None	0	N/A	N/A	None	0	Negative	No	No	no	no									
1	1	117A	Closet next to Auditorium Entrance	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Negative	No	No	no	no									
1	1	117B	Closet across from Classroom 101	yes	W1	CMU	Tan	None	0	N/A	N/A	None	0	Negative	No	No	no	no									
1	1	117B	Closet across from Classroom 101	yes	Door Frame	Metal	Tan	Chipping	1	0.25	Negative	None	0	Negative	No	No	no	no									
1	1	117B	Closet across from Classroom 101	yes	W2	CMU	Tan	Chipping	1	0	Negative	None	0	Negative	No	No	no	no									
1	1	117B	Closet across from Classroom 101	yes	Shelves	Wood	Tan	Friction	1	0.4	Negative	None	0	Negative	No	No	no	no									
1	1	117B	Closet across from Classroom 101	yes	Pipe	Metal	Tan	Chipping	4	0.3	Negative	None	0	Negative	No	No	no	no									
1	1	117B	Closet across from Classroom 101	yes	W3	CMU	Tan	None	0	N/A	N/A	None	0	Negative	No	No	no	no									
1	1	117B	Closet across from Classroom 101	yes	W4	CMU	Tan	None	0	N/A	N/A	None	0	Negative	No	No	no	no									
1	1	117B	Closet across from Classroom 101	yes	Ceiling	Concrete	White	None	0	N/A	N/A	None	0	Negative	No	No	no	no									
1	1	117B	Closet across from Classroom 101	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Negative	No	No	no	no									
1	1	102	Classroom 102	yes	W1	CMU	Blue	Flaking	2	0	Negative	None	0	Negative	No	No	no	no									
1	1	102	Classroom 102	yes	Door Frame	Metal	White	Chipping	12	0	Negative	None	0	Negative	No	No	no	no									
1	1	102	Classroom 102	yes	W2	CMU	Blue	Chipping	1	0	Negative	None	0	Negative	No	No	no	no									
1	1	102	Classroom 102	yes	W3	CMU	Blue	None	0	N/A	N/A	None	0	Negative	No	No	no	no									
1	1	102	Classroom 102	yes	Pipe	Metal	Tan	Chipping	2	0.5	Negative	None	0	Negative	No	No	no	no									
1	1	102	Classroom 102	yes	Column	Concrete	Blue	Flaking	1	0.1	Negative	None	0	Negative	No	No	no	no									
1	1	102	Classroom 102	yes	Cabinet Top	Wood	Blue	Flaking	4	0.28	Negative	None	0	Negative	No	No	no	no									
1	1	102	Classroom 102	yes	Shelves	Metal	Blue	Friction	6	0.12	Negative	None	0	Negative	No	No	no	no									
1	1	102	Classroom 102	yes	Univent	Metal	Blue	Chipping	1	0	Negative	None	0	Negative	No	No	no	no									
1	1	102	Classroom 102	yes	Pipe	Metal	White	Chipping	1	0.15	Negative	None	0	Negative	No	No	no	no									
1	1	102	Classroom 102	yes	W4	CMU	Blue	Chipping	4	0	Negative	None	0	Negative	No	No	no	no									
1	1	102	Classroom 102	yes	Ceiling	Concrete	White	Flaking	40	0.03	Negative	None	0	Negative	No	No	no	no									
1	1	102	Classroom 102	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Negative	No	No	no	no									
1	1	102D	Classroom 102 Closet	yes	W2	CMU	Green	None	0	0	Negative	None	0	Negative	Partially Inaccessible	No	no	no									
1	1	102D	Classroom 102 Closet	yes	Parltion	Wood	Green	Chipping	1	2.1	Positive	None	0	Negative	No	No	no	no									
1	1	102D	Classroom 102 Closet	yes	Shelves	Wood	Green	Friction	5	0.22	Negative	None	0	Negative	No	No	no	no									
1	1	102D	Classroom 102 Closet	yes	W2	CMU	Green	Chipping	1	0	Negative	None	0	Negative	No	No	no	no									
1	1	102D	Classroom 102 Closet	yes	W3	Wood	Green	Chipping	2	0	Negative	None	0	Negative	Partially Inaccessible	No	no	no									
1	1	102D	Classroom 102 Closet	yes	W3	CMU	Green	Chipping	1	0	Negative	None	0	Negative	No	No	no	no									
1	1	102D	Classroom 102 Closet	yes	W4	Wood	Green	Chipping	1	0	Negative	None	0	Negative	Partially Inaccessible	No	no	no									
1	1	102D	Classroom 102 Closet	yes	W4	CMU	Green	Chipping	1	0	Negative	None	0	Negative	No	No	no	no									
1	1	102D	Classroom 102 Closet	yes	Ceiling	Wood	Green	None	0	N/A	N/A	None	0	Negative	No	No	no	no									
1	1	102D	Classroom 102 Closet	yes	Vent	Metal	Green	Chipping	2	0.4	Negative	None	0	Negative	No	No	no	no									
1	1	102D	Classroom 102 Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Negative	No	No	no	no									
1	1	102A	Boy's Restroom next to Breakfast Room 102	yes	W1	CMU	White	None	0	N/A	N/A	None	0	Negative	No	No	no	no									
1	1	102A	Boy's Restroom next to Breakfast Room 102	yes	Door Frame	Metal	Tan	Chipping	4	0.25	Negative	None	0	Negative	No	No	no	no									
1	1	102A	Boy's Restroom next to Breakfast Room 102	yes	W1	Glazed Terracotta	Green	None	0	N/A	N/A	None	0	Negative	No	No	no	no									
1	1	102A	Boy's Restroom next to Breakfast Room 102	yes	W2	CMU	White	None	0	N/A	N/A	None	0	Negative	No	No	no	no									
1	1	102A	Boy's Restroom next to Breakfast Room 102	yes	W2	Glazed Terracotta	Green	None	0	N/A	N/A	None	0	Negative	No	No	no	no									
1	1	102A	Boy's Restroom next to Breakfast Room 102	yes	W3	CMU	White	None	0	N/A	N/A	None	0	Negative	No	No	no	no									
1	1	102A	Boy's Restroom next to Breakfast Room 102	yes	W3	Glazed Terracotta	Green	None	0	N/A	N/A	None	0	Negative	No	No	no	no									
1	1	102A	Boy's Restroom next to Breakfast Room 102	yes	Pipe	Metal	Grey	Chipping	3	0.27	Negative	None	0	Negative	No	No	no	no									
1	1	102A	Boy's Restroom next to Breakfast Room 102	yes	Door	Metal	Brown	Friction	1	0	Negative	None	0	Negative	No	No	no	no									
1	1	102A	Boy's Restroom next to Breakfast Room 102	yes	Door Frame	Metal	Brown	Chipping	2	0.15	Negative	None	0	Negative	No	No	no	no									

			School District of Philadelphia																					
			Name of Inspector: Jen Drialo		Lead Safe Certification Assessment Report																Inspection Dates: 9/20/21-10/7/21			
			Inspection Company: Synertech, Inc.		Gideon ES School																ULCS# 4530			
E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate	Color	Damage	Damage amount (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes					
1	1	102A	Boy's Restroom next to Breakfast Room 102	yes	W4	CMU	White	Flaking	1	0	Negative	None	0	Negative	No	No	no	no						
1	1	102A	Boy's Restroom next to Breakfast Room 102	yes	W4	Glazed Terracotta	Green	None	0	N/A	N/A	None	0	Negative	No	No	no	no						
1	1	102A	Boy's Restroom next to Breakfast Room 102	yes	Univent	Metal	Grey	Chipping	2	0.08	Negative	None	0	Negative	No	No	no	no						
1	1	102A	Boy's Restroom next to Breakfast Room 102	yes	Ceiling	Concrete	White	Flaking	100	0.04	Negative	None	0	Negative	No	No	no	no						
1	1	102A	Boy's Restroom next to Breakfast Room 102	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Negative	No	No	no	no						
1	1	102B	Girl's Restroom by Breakfast Room 102	yes	W1	CMU	White	None	0	N/A	N/A	None	0	Negative	No	No	no	no						
1	1	102B	Girl's Restroom by Breakfast Room 102	yes	Door Frame	Metal	Tan	Chipping	4	0.25	Negative	None	0	Negative	No	No	no	no						
1	1	102B	Girl's Restroom by Breakfast Room 102	yes	W1	Glazed Terracotta	Green	None	0	N/A	N/A	None	0	Negative	No	No	no	no						
1	1	102B	Girl's Restroom by Breakfast Room 102	yes	W2	CMU	White	None	0	N/A	N/A	None	0	Negative	No	No	no	no						
1	1	102B	Girl's Restroom by Breakfast Room 102	yes	W2	Glazed Terracotta	Green	None	0	N/A	N/A	None	0	Negative	No	No	no	no						
1	1	102B	Girl's Restroom by Breakfast Room 102	yes	W3	CMU	White	None	0	N/A	N/A	None	0	Negative	No	No	no	no						
1	1	102B	Girl's Restroom by Breakfast Room 102	yes	W3	Glazed Terracotta	Green	None	0	N/A	N/A	None	0	Negative	No	No	no	no						
1	1	102B	Girl's Restroom by Breakfast Room 102	yes	Pipe	Metal	Grey	Chipping	3	0.27	Negative	None	0	Negative	No	No	no	no						
1	1	102B	Girl's Restroom by Breakfast Room 102	yes	Door	Metal	Brown	Friction	1	0	Negative	None	0	Negative	No	No	no	no						
1	1	102B	Girl's Restroom by Breakfast Room 102	yes	Door Frame	Metal	Brown	Chipping	2	0.15	Negative	None	0	Negative	No	No	no	no						
1	1	102B	Girl's Restroom by Breakfast Room 102	yes	W4	CMU	White	Flaking	1	0	Negative	None	0	Negative	No	No	no	no						
1	1	102B	Girl's Restroom by Breakfast Room 102	yes	W4	Glazed Terracotta	Green	None	0	N/A	N/A	None	0	Negative	No	No	no	no						
1	1	102B	Girl's Restroom by Breakfast Room 102	yes	Univent	Metal	Grey	Chipping	2	0.08	Negative	None	0	Negative	No	No	no	no						
1	1	102B	Girl's Restroom by Breakfast Room 102	yes	Ceiling	Concrete	White	Flaking	100	0.04	Negative	None	0	Negative	No	No	no	no						
1	1	102B	Girl's Restroom by Breakfast Room 102	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Negative	No	No	no	no						
1	1	102C	Custodial Closet by Breakfast Room 102	no	W1	CMU	Tan	None	0	N/A	N/A	None	0	Negative	No	No	no	no						
1	1	102C	Custodial Closet by Breakfast Room 102	no	Door	Metal	Tan	Chipping	1	0	Negative	None	0	Negative	No	No	no	no						
1	1	102C	Custodial Closet by Breakfast Room 102	no	Door Frame	Metal	White	Chipping	8	0.11	Negative	None	0	Negative	No	No	no	no						
1	1	102C	Custodial Closet by Breakfast Room 102	no	W2	CMU	Tan	Chipping	1	0	Negative	None	0	Negative	No	No	no	no						
1	1	102C	Custodial Closet by Breakfast Room 102	no	W2	CMU	Grey	Flaking	3	0.05	Negative	None	0	Negative	No	No	no	no						
1	1	102C	Custodial Closet by Breakfast Room 102	no	Shelves	Wood	Tan	Friction	2	0.11	Negative	None	0	Negative	No	No	no	no						
1	1	102C	Custodial Closet by Breakfast Room 102	no	W3	CMU	Tan	Chipping	1	0	Negative	None	0	Negative	No	No	no	no						
1	1	102C	Custodial Closet by Breakfast Room 102	no	W3	CMU	Grey	Flaking	2	0.05	Negative	None	0	Negative	No	No	no	no						
1	1	102C	Custodial Closet by Breakfast Room 102	no	Duct	Metal	Grey	Chipping	4	0.05	Negative	None	0	Negative	No	No	no	no						
1	1	102C	Custodial Closet by Breakfast Room 102	no	Pipe	Metal	Grey	Chipping	6	0.24	Negative	None	0	Negative	No	No	no	no						
1	1	102C	Custodial Closet by Breakfast Room 102	no	Pipe	Metal	Tan	Chipping	6	0.22	Negative	None	0	Negative	No	No	no	no						
1	1	102C	Custodial Closet by Breakfast Room 102	no	Column	Concrete	Grey	Chipping	8	0.05	Negative	None	0	Negative	No	No	no	no						
1	1	102C	Custodial Closet by Breakfast Room 102	no	W4	CMU	Tan	Chipping	4	0	Negative	None	0	Negative	No	No	no	no						
1	1	102C	Custodial Closet by Breakfast Room 102	no	W4	CMU	Grey	Chipping	8	0.05	Negative	None	0	Negative	No	No	no	no						
1	1	102C	Custodial Closet by Breakfast Room 102	no	Shelves	Wood	Tan	Friction	2	0.14	Negative	None	0	Negative	No	No	no	no						
1	1	102C	Custodial Closet by Breakfast Room 102	no	Sink	Porcelain	Grey	Chipping	2	0.29	Negative	None	0	Negative	No	No	no	no						
1	1	102C	Custodial Closet by Breakfast Room 102	no	Ceiling	Concrete	White	None	0	N/A	Negative	None	0	Negative	No	No	no	no						
1	1	102C	Custodial Closet by Breakfast Room 102	no	Floor	Concrete	Grey	Friction	10	0	Negative	None	0	Negative	No	No	no	no						

			School District of Philadelphia																								
			Name of Inspector: Jen Drialo		Lead Safe Certification Assessment Report																						
			Inspection Company: Synertech, Inc.		Gideon ES School																						
				ULCS# 4530																							
E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate	Color	Damage	Damage amount (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes								
1	1	116C	Storage 1	yes	W1	CMU	Tan	Chipping	2	0	Negative	None	0	Negative	Partially Inaccessible	No	no	no									
1	1	116C	Storage 1	yes	Door Frame	Metal	Tan	Chipping	8	0.18	Negative	None	0	Negative	No	No	no	no									
1	1	116C	Storage 1	yes	Pipe	Metal	White	Chipping	12	0.19	Negative	None	0	Negative	No	No	no	no									
1	1	116C	Storage 1	yes	W2	CMU	Tan	None	0	N/A	N/A	None	0	Negative	Partially Inaccessible	No	no	no									
1	1	116C	Storage 1	yes	W3	CMU	Tan	None	0	N/A	N/A	None	0	Negative	No	No	no	no									
1	1	116C	Storage 1	yes	W4	CMU	Tan	None	0	N/A	N/A	None	0	Negative	Partially Inaccessible	No	no	no									
1	1	116C	Storage 1	yes	HVAC	Metal	White	Flaking	2	0.15	Negative	None	0	Negative	No	No	no	no									
1	1	116C	Storage 1	yes	Ceiling	Concrete	White	None	0	N/A	N/A	None	0	Negative	No	No	no	no									
1	1	116C	Storage 1	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Negative	No	No	no	no									
1	1	S18	Stairwell next to Classrooms 103/104 Entrance	yes	W1	CMU	Tan	None	0	N/A	N/A	None	0	Negative	No	No	no	no									
1	1	S18	Stairwell next to Classrooms 103/104 Entrance	yes	Column	Concrete	Tan	None	0	N/A	N/A	None	0	Negative	No	No	no	no									
1	1	S18	Stairwell next to Classrooms 103/104 Entrance	yes	Column	Concrete	Tan	Chipping	1	0.12	Negative	None	0	Negative	No	No	no	no									
1	1	S18	Stairwell next to Classrooms 103/104 Entrance	yes	W2	CMU	Tan	Chipping	1	0.07	Negative	None	0	Negative	No	No	no	no									
1	1	S18	Stairwell next to Classrooms 103/104 Entrance	yes	Door	Metal	Brown	Friction	4	0.03	Negative	None	0	Negative	No	No	no	no									
1	1	S18	Stairwell next to Classrooms 103/104 Entrance	yes	Door Frame	Metal	Brown	Chipping	5	0.12	Negative	None	0	Negative	No	No	no	no									
1	1	S18	Stairwell next to Classrooms 103/104 Entrance	yes	Radiator	Metal	Grey	Chipping	3	0.12	Negative	None	0	Negative	No	No	no	no									
1	1	S18	Stairwell next to Classrooms 103/104 Entrance	yes	W3	CMU	Tan	Flaking	2	0.06	Negative	None	0	Negative	No	No	no	no									
1	1	S18	Stairwell next to Classrooms 103/104 Entrance	yes	Radiator	Metal	Grey	Chipping	3	0.12	Negative	None	0	Negative	No	No	no	no									
1	1	S18	Stairwell next to Classrooms 103/104 Entrance	yes	W4	CMU	Tan	None	0	N/A	N/A	None	0	Negative	No	No	no	no									
1	1	S18	Stairwell next to Classrooms 103/104 Entrance	yes	Door	Metal	Tan	Friction	8	0.03	Negative	None	0	Negative	No	No	no	no									
1	1	S18	Stairwell next to Classrooms 103/104 Entrance	yes	Door Frame	Metal	Tan	Chipping	1	0.12	Negative	None	0	Negative	No	No	no	no									
1	1	S18	Stairwell next to Classrooms 103/104 Entrance	yes	Ceiling	Metal	White	Efflorescence	1	2.5	Positive	None	0	Negative	No	Unknown	no	no									
1	1	S18	Stairwell next to Classrooms 103/104 Entrance	yes	Ceiling	Concrete	Tan	Flaking	1	0.12	Negative	None	0	Negative	No	Unknown	no	no									
1	1	S18	Stairwell next to Classrooms 103/104 Entrance	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Negative	No	No	no	no									
1	1	S18	Stairwell next to Classrooms 103/104 Entrance	yes	Open Stringer	Metal	Grey	Chipping	1	6	Positive	None	0	Negative	No	No	no	no									
1	1	S18	Stairwell next to Classrooms 103/104 Entrance	yes	Wall Stringer	Metal	Grey	Chipping	1	5.5	Positive	None	0	Negative	No	No	no	no									
1	1	S18	Stairwell next to Classrooms 103/104 Entrance	yes	Baluster	Metal	Orange	Chipping	2	3.5	Positive	None	0	Negative	No	No	no	no									
1	1	S18	Stairwell next to Classrooms 103/104 Entrance	yes	Newel Post	Metal	Grey	Chipping	1	6.8	Positive	None	0	Negative	No	No	no	no									
1	1	S18	Stairwell next to Classrooms 103/104 Entrance	yes	Riser	Metal	Grey	Chipping	3	3.5	Positive	None	0	Negative	No	No	no	no									
1	1	S18	Stairwell next to Classrooms 103/104 Entrance	yes	Handrail	Metal	Orange	Friction	20	3.7	Positive	None	0	Negative	No	No	no	no									
1	1	H14	Entrance to Storage Rooms 103/104	yes	W1	CMU	Tan	Chipping	2	0	Negative	None	0	Negative	No	No	no	no									
1	1	H14	Entrance to Storage Rooms 103/104	yes	W1	CMU	White	None	0	N/A	N/A	None	0	Negative	No	No	no	no									
1	1	H14	Entrance to Storage Rooms 103/104	yes	Door Frame	Metal	Brown	Chipping	2	0.16	Negative	None	0	Negative	No	No	no	no									
1	1	H14	Entrance to Storage Rooms 103/104	yes	W2	CMU	Tan	Flaking	1	0	Negative	None	0	Negative	No	No	no	no									
1	1	H14	Entrance to Storage Rooms 103/104	yes	W2	CMU	White	Chipping	1	0	Negative	None	0	Negative	No	No	no	no									
1	1	H14	Entrance to Storage Rooms 103/104	yes	W3	CMU	Tan	None	0	N/A	N/A	None	0	Negative	No	No	no	no									
1	1	H14	Entrance to Storage Rooms 103/104	yes	W3	CMU	White	None	0	N/A	N/A	None	0	Negative	No	No	no	no									
1	1	H14	Entrance to Storage Rooms 103/104	yes	Door	Metal	Brown	None	0	N/A	N/A	None	0	Negative	No	No	no	no									
1	1	H14	Entrance to Storage Rooms 103/104	yes	Door Frame	Metal	Brown	Chipping	6	0.22	Negative	None	0	Negative	No	No	no	no									
1	1	H14	Entrance to Storage Rooms 103/104	yes	Univent	Metal	Tan	Chipping	1	0.02	Negative	None	0	Negative	No	No	no	no									

			School District of Philadelphia																	
			Name of Inspector: Jen Drialo		Lead Safe Certification Assessment Report							Inspection Dates: 9/20/21-10/7/21								
			Inspection Company: Synertech, Inc.		Gideon ES School							ULCS# 4530								
E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate	Color	Damage	Damage amount (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes	
1	1	H14	Entrance to Storage Rooms 103/104	yes	Pipe	Metal	Tan	Chipping	1	0.3	Negative	None	0	Negative	No	No	no	no		
1	1	H14	Entrance to Storage Rooms 103/104	yes	W4	CMU	Tan	None	0	N/A	N/A	None	0	Negative	No	No	no	no		
1	1	H14	Entrance to Storage Rooms 103/104	yes	W4	CMU	White	None	0	N/A	N/A	None	0	Negative	No	No	no	no		
1	1	H14	Entrance to Storage Rooms 103/104	yes	Ceiling	Concrete	White	None	0	N/A	N/A	None	0	Negative	No	No	no	no		
1	1	H14	Entrance to Storage Rooms 103/104	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Negative	No	No	no	no		
1	1	H14A	Coat Room next to Storage Room 103	yes	W1	CMU	Tan	Partially Inaccessible	0	N/A	N/A	None	0	Negative	Partially Inaccessible	No	no	no		
1	1	H14A	Coat Room next to Storage Room 103	yes	Door Frame	Metal	Brown	Chipping	2	0.24	Negative	None	0	Negative	No	No	no	no		
1	1	H14A	Coat Room next to Storage Room 103	yes	W2	CMU	Tan	Partially Inaccessible	0	N/A	N/A	None	0	Negative	Partially Inaccessible	No	no	no		
1	1	H14A	Coat Room next to Storage Room 103	yes	W3	CMU	Tan	Flaking	1	0	Negative	None	0	Negative	Partially Inaccessible	No	no	no		
1	1	H14A	Coat Room next to Storage Room 103	yes	W4	CMU	Tan	Partially Inaccessible	0	N/A	N/A	None	0	Negative	Partially Inaccessible	No	no	no		
1	1	H14A	Coat Room next to Storage Room 103	yes	Ceiling	Concrete	White	None	0	N/A	N/A	None	0	Negative	No	No	no	no		
1	1	H14A	Coat Room next to Storage Room 103	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Negative	No	No	no	no		
1	1	103	Nurse's Office CommonArea	yes	W1	CMU	Tan	None	0	N/A	N/A	None	0	Negative	No	No	no	no		
1	1	103	Nurse's Office CommonArea	yes	W2	Sheetrock	Tan	None	0	N/A	N/A	None	0	Negative	No	No	no	no		
1	1	103	Nurse's Office CommonArea	yes	W3	Concrete	Tan	None	0	N/A	N/A	None	0	Negative	No	No	no	no		
1	1	103	Nurse's Office CommonArea	yes	Cabinet Top	Wood	Brown	None	0	N/A	N/A	None	0	Negative	No	No	no	no		
1	1	103	Nurse's Office CommonArea	yes	Univent	Metal	Brown	Chipping	2	0.06	Negative	None	0	Negative	No	No	no	no		
1	1	103	Nurse's Office CommonArea	yes	Shelves	Metal	Brown	Chipping	3	0.16	Negative	None	0	Negative	No	No	no	no		
1	1	103	Nurse's Office CommonArea	yes	Pipe	Metal	Tan	Flaking	1	0.03	Negative	None	0	Negative	No	No	no	no		
1	1	103	Nurse's Office CommonArea	yes	W4	CMU	Blue	None	0	N/A	N/A	None	0	Negative	No	No	no	no		
1	1	103	Nurse's Office CommonArea	yes	Ceiling	Concrete	White	None	0	N/A	N/A	None	0	Negative	No	No	no	no		
1	1	103	Nurse's Office CommonArea	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Negative	No	No	no	no		
1	1	103A	Nurse's Office Closet	yes	W1	CMU	Tan	None	0	N/A	N/A	None	0	Negative	No	No	no	no		
1	1	103A	Nurse's Office Closet	yes	Door Frame	Metal	Tan	Chipping	1	0.21	Negative	None	0	Negative	No	No	no	no		
1	1	103A	Nurse's Office Closet	yes	W2	CMU	Tan	None	0	N/A	N/A	None	0	Negative	No	No	no	no		
1	1	103A	Nurse's Office Closet	yes	W3	CMU	Tan	None	0	N/A	N/A	None	0	Negative	No	No	no	no		
1	1	103A	Nurse's Office Closet	yes	W4	CMU	Tan	None	0	N/A	N/A	None	0	Negative	No	No	no	no		
1	1	103A	Nurse's Office Closet	yes	Ceiling	Concrete	White	None	0	N/A	N/A	None	0	Negative	No	No	no	no		
1	1	103A	Nurse's Office Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Negative	No	No	no	no		
1	1	103B	Nurse's Office Coat Closet	yes	W1	CMU	Tan	None	0	N/A	N/A	None	0	Negative	No	No	no	no		
1	1	103B	Nurse's Office Coat Closet	yes	Door Frame	Metal	Tan	Chipping	1	0.21	Negative	None	0	Negative	No	No	no	no		
1	1	103B	Nurse's Office Coat Closet	yes	W2	CMU	Tan	None	0	N/A	N/A	None	0	Negative	No	No	no	no		
1	1	103B	Nurse's Office Coat Closet	yes	W3	CMU	Tan	None	0	N/A	N/A	None	0	Negative	No	No	no	no		
1	1	103B	Nurse's Office Coat Closet	yes	Shelves	Wood	Tan	None	0	N/A	N/A	None	0	Negative	No	No	no	no		
1	1	103B	Nurse's Office Coat Closet	yes	W4	CMU	Tan	None	0	N/A	N/A	None	0	Negative	No	No	no	no		
1	1	103B	Nurse's Office Coat Closet	yes	Ceiling	Concrete	White	None	0	N/A	N/A	None	0	Negative	No	No	no	no		
1	1	103B	Nurse's Office Coat Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Negative	No	No	no	no		
1	1	103C	Nurse's Office Restroom	yes	W1	CMU	Tan	None	0	N/A	N/A	None	0	Negative	No	No	no	no		
1	1	103C	Nurse's Office Restroom	yes	W2	CMU	Tan	None	0	N/A	N/A	None	0	Negative	No	No	no	no		
1	1	103C	Nurse's Office Restroom	yes	W3	CMU	Tan	None	0	N/A	N/A	None	0	Negative	No	No	no	no		
1	1	103C	Nurse's Office Restroom	yes	W4	CMU	Tan	None	0	N/A	N/A	None	0	Negative	No	No	no	no		
1	1	103C	Nurse's Office Restroom	yes	Ceiling	Concrete	White	None	0	N/A	N/A	None	0	Negative	No	No	no	no		
1	1	103C	Nurse's Office Restroom	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Negative	No	No	no	no		
1	1	103D	Nurse's Office	yes	W1	Sheetrock	Tan	None	0	N/A	N/A	None	0	Negative	No	No	no	no		
1	1	103D	Nurse's Office	yes	W2	Sheetrock	Tan	None	0	N/A	N/A	None	0	Negative	No	No	no	no		
1	1	103D	Nurse's Office	yes	W3	Sheetrock	Tan	None	0	N/A	N/A	None	0	Negative	No	No	no	no		
1	1	103D	Nurse's Office	yes	Window Sill	Wood	Brown	None	0	N/A	N/A	None	0	Negative	No	No	no	no		
1	1	103D	Nurse's Office	yes	Univent	Metal	Brown	Chipping	2	0.06	Negative	None	0	Negative	No	No	no	no		
1	1	103D	Nurse's Office	yes	W4	Sheetrock	Green	None	0	N/A	N/A	None	0	Negative	No	No	no	no		
1	1	103D	Nurse's Office	yes	Ceiling	Concrete	White	None	0	N/A	N/A	None	0	Negative	No	No	no	no		
1	1	103D	Nurse's Office	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Negative	No	No	no	no		
1	1	103E	Nurse Practioner Office	yes	W1	Sheetrock	Tan	None	0	N/A	N/A	None	0	Negative	No	No	no	no		
1	1	103E	Nurse Practioner Office	yes	W2	Sheetrock	Orange	None	0	N/A	N/A	None	0	Negative	No	No	no	no		
1	1	103E	Nurse Practioner Office	yes	W3	CMU	Tan	None	0	N/A	N/A	None	0	Negative	No	No	no	no		
1	1	103E	Nurse Practioner Office	yes	W4	Concrete	Tan	None	0	N/A	N/A	None	0	Negative	No	No	no	no		
1	1	103E	Nurse Practioner Office	yes	Cabinet Top	Wood	Brown	None	0	N/A	N/A	None	0	Negative	No	No	no	no		
1	1	103E	Nurse Practioner Office	yes	Univent	Metal	Brown	Chipping	2	0.19	Negative	None	0	Negative	No	No	no	no		
1	1	103E	Nurse Practioner Office	yes	Shelves	Metal	Brown	Chipping	1	0.07	Negative	None	0	Negative	No	No	no	no		
1	1	103E	Nurse Practioner Office	yes	Ceiling	Concrete	White	None	0	N/A	N/A	None	0	Negative	No	No	no	no		

			School District of Philadelphia																	
			Name of Inspector: Jen Drialo		Lead Safe Certification Assessment Report												Inspection Dates: 9/20/21-10/7/21			
			Inspection Company: Synertech, Inc.		Gideon ES School												ULCS# 4530			
E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate	Color	Damage	Damage amount (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes	
1	1	103E	Nurse Practioner Office	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Negative	No	No	no	no		
1	1	104	Classroom 104	yes	W1	CMU	Tan	Chipping	2	0	Negative	None	0	Negative	No	No	no	no		
1	1	104	Classroom 104	yes	Door Frame	Metal	Brown	Chipping	3	0.28	Negative	None	0	Negative	No	No	no	no		
1	1	104	Classroom 104	yes	W2	CMU	Tan	Chipping	1	0	Negative	None	0	Negative	No	No	no	no		
1	1	104	Classroom 104	yes	W3	Sheetrock	Orange	None	0	N/A	N/A	None	0	Negative	No	No	no	no		
1	1	104	Classroom 104	yes	W4	CMU	Tan	None	0	N/A	N/A	None	0	Negative	No	No	no	no		
1	1	104	Classroom 104	yes	Ceiling	Concrete	White	None	0	N/A	N/A	None	0	Negative	No	No	no	no		
1	1	104	Classroom 104	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Negative	No	No	no	no		
1	1	104F	North room inside Classroom 104	yes	W1	Sheetrock	Tan	Chipping	1	0	Negative	None	0	Negative	No	No	no	no		
1	1	104F	North room inside Classroom 104	yes	Door Frame	Metal	Brown	None	0	N/A	N/A	None	0	Negative	No	No	no	no		
1	1	104F	North room inside Classroom 104	yes	W2	CMU	Blue	None	0	N/A	N/A	None	0	Negative	No	No	no	no		
1	1	104F	North room inside Classroom 104	yes	W3	Concrete	Blue	None	0	N/A	N/A	None	0	Negative	No	No	no	no		
1	1	104F	North room inside Classroom 104	yes	Cabinet Top	Wood	Brown	Chipping	4	0.17	Negative	None	0	Negative	No	No	no	no		
1	1	104F	North room inside Classroom 104	yes	Univent	Metal	Brown	Chipping	2	0.09	Negative	None	0	Negative	No	No	no	no		
1	1	104F	North room inside Classroom 104	yes	Shelves	Metal	Brown	Chipping	2	0.11	Negative	None	0	Negative	No	No	no	no		
1	1	104F	North room inside Classroom 104	yes	W4	Sheetrock	Tan	None	0	N/A	N/A	None	0	Negative	No	No	no	no		
1	1	104F	North room inside Classroom 104	yes	Ceiling	Concrete	White	None	0	N/A	N/A	None	0	Negative	No	No	no	no		
1	1	104F	North room inside Classroom 104	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Negative	No	No	no	no		
1	1	104G	Middle room inside Classroom 104	yes	W1	Sheetrock	Tan	Chipping	1	0	Negative	None	0	Negative	No	No	no	no		
1	1	104G	Middle room inside Classroom 104	yes	Door Frame	Metal	Brown	Chipping	1	0.21	Negative	None	0	Negative	No	No	no	no		
1	1	104G	Middle room inside Classroom 104	yes	W2	Sheetrock	Green	None	0	N/A	N/A	None	0	Negative	No	No	no	no		
1	1	104G	Middle room inside Classroom 104	yes	W3	Concrete	Tan	None	0	N/A	N/A	None	0	Negative	No	No	no	no		
1	1	104G	Middle room inside Classroom 104	yes	Cabinet Top	Wood	Brown	Chipping	4	0.12	Negative	None	0	Negative	No	No	no	no		
1	1	104G	Middle room inside Classroom 104	yes	Univent	Metal	Brown	Chipping	2	0.07	Negative	None	0	Negative	No	No	no	no		
1	1	104G	Middle room inside Classroom 104	yes	Shelves	Metal	Brown	Chipping	2	0.12	Negative	None	0	Negative	No	No	no	no		
1	1	104G	Middle room inside Classroom 104	yes	Pipe	Metal	Tan	Chipping	1	0.03	Negative	None	0	Negative	No	No	no	no		
1	1	104G	Middle room inside Classroom 104	yes	W4	Sheetrock	Tan	None	0	N/A	N/A	None	0	Negative	No	No	no	no		
1	1	104G	Middle room inside Classroom 104	yes	Ceiling	Concrete	White	None	0	N/A	N/A	None	0	Negative	No	No	no	no		
1	1	104G	Middle room inside Classroom 104	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Negative	No	No	no	no		
1	1	104H	South room inside Classroom 104	yes	W1	Sheetrock	Tan	Chipping	1	0	Negative	None	0	Negative	No	No	no	no		
1	1	104H	South room inside Classroom 104	yes	W2	Sheetrock	Orange	Chipping	1	0	Negative	None	0	Negative	No	No	no	no		
1	1	104H	South room inside Classroom 104	yes	W3	Concrete	Tan	None	0	N/A	N/A	None	0	Negative	No	No	no	no		
1	1	104H	South room inside Classroom 104	yes	Cabinet Top	Wood	Brown	Flaking	10	0.16	Negative	None	0	Negative	No	No	no	no		
1	1	104H	South room inside Classroom 104	yes	Univent	Metal	Brown	Chipping	2	0.05	Negative	None	0	Negative	No	No	no	no		
1	1	104H	South room inside Classroom 104	yes	Shelves	Metal	Brown	Chipping	2	0.12	Negative	None	0	Negative	No	No	no	no		
1	1	104H	South room inside Classroom 104	yes	Pipe	Metal	Tan	Flaking	2	0.4	Negative	None	0	Negative	No	No	no	no		
1	1	104H	South room inside Classroom 104	yes	W4	Sheetrock	Tan	None	0	N/A	N/A	None	0	Negative	No	No	no	no		
1	1	104H	South room inside Classroom 104	yes	Ceiling	Concrete	White	None	0	N/A	N/A	None	0	Negative	No	No	no	no		
1	1	104H	South room inside Classroom 104	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Negative	No	No	no	no		
1	1	104E	Classroom 104 Closet next to Classroom 105	yes	Door Frame	Metal	Tan	Chipping	1	0.18	Negative	None	0	Negative	No	No	no	no		
1	1	104E	Classroom 104 Closet next to Classroom 105	yes	W2	CMU	Tan	Partially Inaccessible	0	N/A	N/A	None	0	Negative	Partially Inaccessible	No	no	no		

			School District of Philadelphia																				
			Name of Inspector: Jen Drialo		Lead Safe Certification Assessment Report							Inspection Dates: 9/20/21-10/7/21											
			Inspection Company: Synertech, Inc.		Gideon ES School							ULCS# 4530											
E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate	Color	Damage	Damage amount (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes				
1	1	104E	Classroom 104 Closet next to Classroom 105	yes	W3	CMU	Tan	Partially Inaccessible	0	N/A	N/A	None	0	Negative	Partially Inaccessible	No	no	no					
1	1	104E	Classroom 104 Closet next to Classroom 105	yes	W4	CMU	Tan	None	0	N/A	N/A	None	0	Negative	No	No	no	no					
1	1	104E	Classroom 104 Closet next to Classroom 105	yes	Ceiling	Concrete	White	None	0	N/A	N/A	None	0	Negative	No	No	no	no					
1	1	104E	Classroom 104 Closet next to Classroom 105	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Negative	No	No	no	no					
1	1	104A	Classroom 104 Restroom	yes	W1	CMU	White	None	0	N/A	N/A	None	0	Negative	No	No	no	no					
1	1	104A	Classroom 104 Restroom	yes	W1	Brick	Green	None	0	N/A	N/A	None	0	Negative	No	No	no	no					
1	1	104A	Classroom 104 Restroom	yes	Door Frame	Metal	Tan	Chipping	1	0.12	Negative	None	0	Negative	No	No	no	no					
1	1	104A	Classroom 104 Restroom	yes	W2	Brick	Green	None	0	N/A	N/A	None	0	Negative	No	No	no	no					
1	1	104A	Classroom 104 Restroom	yes	W3	Wood	Black	None	0	N/A	N/A	None	0	Negative	No	No	no	no					
1	1	104A	Classroom 104 Restroom	yes	W4	CMU	White	None	0	N/A	N/A	None	0	Negative	No	No	no	no					
1	1	104A	Classroom 104 Restroom	yes	W4	Brick	Green	None	0	N/A	N/A	None	0	Negative	No	No	no	no					
1	1	104A	Classroom 104 Restroom	yes	Ceiling	Concrete	White	Flaking	3	0	Negative	None	0	Negative	No	No	no	no					
1	1	104A	Classroom 104 Restroom	yes	Floor	Concrete	Grey	Chipping	10	0.03	Negative	None	0	Negative	No	No	no	no					
1	1	104B	Storage Room 104 Coat Room	yes	Door Frame	Metal	Tan	Chipping	1	0.18	Negative	None	0	Negative	No	No	no	no					
1	1	104B	Storage Room 104 Coat Room	yes	W2	CMU	Tan	Partially Inaccessible	0	N/A	N/A	None	0	Negative	Partially Inaccessible	No	no	no					
1	1	104B	Storage Room 104 Coat Room	yes	W3	CMU	Tan	Partially Inaccessible	0	N/A	N/A	None	0	Negative	Partially Inaccessible	No	no	no					
1	1	104B	Storage Room 104 Coat Room	yes	W4	CMU	Tan	None	0	N/A	N/A	None	0	Negative	No	No	no	no					
1	1	104B	Storage Room 104 Coat Room	yes	Ceiling	Concrete	White	None	0	N/A	N/A	None	0	Negative	No	No	no	no					
1	1	104B	Storage Room 104 Coat Room	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Negative	No	No	no	no					
1	1	104C	Storage Room 104 Closet next to Restroom	yes	Door Frame	Metal	Tan	None	0	N/A	N/A	None	0	Negative	No	No	no	no					
1	1	104C	Storage Room 104 Closet next to Restroom	yes	W2	CMU	Tan	None	0	N/A	N/A	None	0	Negative	No	No	no	no					
1	1	104C	Storage Room 104 Closet next to Restroom	yes	Shelves	Wood	Tan	Chipping	1	0.12	Negative	None	0	Negative	No	No	no	no					
1	1	104C	Storage Room 104 Closet next to Restroom	yes	W3	CMU	Tan	None	0	N/A	N/A	None	0	Negative	No	No	no	no					
1	1	104C	Storage Room 104 Closet next to Restroom	yes	W4	CMU	Tan	None	0	N/A	N/A	None	0	Negative	No	No	no	no					
1	1	104C	Storage Room 104 Closet next to Restroom	yes	Ceiling	Concrete	White	None	0	N/A	N/A	None	0	Negative	No	No	no	no					
1	1	104C	Storage Room 104 Closet next to Restroom	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Negative	No	No	no	no					
1	1	104D	Classroom 104 Small Closet	yes	Door Frame	Metal	Tan	Chipping	1	0.18	Negative	None	0	Negative	No	No	no	no					
1	1	104D	Classroom 104 Small Closet	yes	W2	CMU	Tan	None	0	N/A	N/A	None	0	Negative	No	No	no	no					
1	1	104D	Classroom 104 Small Closet	yes	W3	CMU	Tan	None	0	N/A	N/A	None	0	Negative	No	No	no	no					
1	1	104D	Classroom 104 Small Closet	yes	W4	CMU	Tan	None	0	N/A	N/A	None	0	Negative	No	No	no	no					
1	1	104D	Classroom 104 Small Closet	yes	Ceiling	Concrete	White	None	0	N/A	N/A	None	0	Negative	No	No	no	no					
1	1	105	Multi-Purpose Parent Room 105	yes	W1	CMU	Tan	Flaking	2	0	Negative	None	0	Negative	No	No	no	no					
1	1	105	Multi-Purpose Parent Room 105	yes	Door Frame	Metal	White	Chipping	4	0.06	Negative	None	0	Negative	No	No	no	no					
1	1	105	Multi-Purpose Parent Room 105	yes	W2	CMU	Tan	Flaking	2	0	Negative	None	0	Negative	No	No	no	no					
1	1	105	Multi-Purpose Parent Room 105	yes	W3	CMU	Tan	Chipping	6	0	Negative	None	0	Negative	No	No	no	no					
1	1	105	Multi-Purpose Parent Room 105	yes	Pipe	Metal	Tan	Chipping	1	0.4	Negative	None	0	Negative	No	No	no	no	Paint Chip Sampled 0.10% Pb/weight				
1	1	105	Multi-Purpose Parent Room 105	yes	Column	Concrete	Tan	Flaking	3	0.04	Negative	None	0	Negative	No	No	no	no					
1	1	105	Multi-Purpose Parent Room 105	yes	Cabinet Top	Wood	Green	Flaking	30	0.25	Negative	None	0	Negative	No	No	no	no					
1	1	105	Multi-Purpose Parent Room 105	yes	Shelves	Metal	Tan	Friction	4	0.26	Negative	None	0	Negative	No	No	no	no					
1	1	105	Multi-Purpose Parent Room 105	yes	Univent	Metal	Tan	Chipping	1	0.03	Negative	None	0	Negative	No	No	no	no					
1	1	105	Multi-Purpose Parent Room 105	yes	W4	CMU	Tan	Chipping	4	0	Negative	None	0	Negative	No	No	no	no					
1	1	105	Multi-Purpose Parent Room 105	yes	Ceiling	Concrete	White	Flaking	50	0.03	Negative	None	0	Negative	No	No	no	no					
1	1	105	Multi-Purpose Parent Room 105	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Negative	No	No	no	no					
1	1	105A	Classroom 105 Closet	yes	W2	CMU	Green	None	0	0	Negative	None	0	Negative	No	No	no	no					
1	1	105A	Classroom 105 Closet	yes	Partition	Wood	Green	Chipping	1	2.1	Positive	None	0	Negative	No	No	no	no					
1	1	105A	Classroom 105 Closet	yes	Shelves	Wood	Green	Friction	4	0.8	Positive	None	0	Negative	No	No	no	no	Paint Chip Sampled 0.37% Pb/weight				
1	1	105A	Classroom 105 Closet	yes	W2	CMU	Green	Chipping	1	0	Negative	None	0	Negative	No	No	no	no					
1	1	105A	Classroom 105 Closet	yes	W3	Wood	Green	Chipping	2	0	Negative	None	0	Negative	No	No	no	no					
1	1	105A	Classroom 105 Closet	yes	W3	CMU	Green	Chipping	1	0	Negative	None	0	Negative	No	No	no	no					





			School District of Philadelphia																										
			Name of Inspector: Jen Drialo		Lead Safe Certification Assessment Report																								
			Inspection Company: Synertech, Inc.		Gideon ES School																								
E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate	Color	Damage	Damage amount (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes										
																				ULCS# 4530									
1	1	108A	Teacher's Lounge 108 Closet	yes	Ceiling	Concrete	White	Chipping	1	0	Negative	None	0	Negative	No	No	no	no											
1	1	108A	Teacher's Lounge 108 Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Negative	No	No	no	no											
1	1	S15	Stairwell across from Main Office	yes	W1	CMU	Tan	Flaking	2	0.07	Negative	None	0	Negative	No	No	no	no											
1	1	S15	Stairwell across from Main Office	yes	Door	Metal	Tan	N/A	N/A	N/A	N/A	None	0	Negative	No	No	no	no											
1	1	S15	Stairwell across from Main Office	yes	Door Frame	Metal	Tan	Chipping	2	0.02	Negative	None	0	Negative	No	No	no	no											
1	1	S15	Stairwell across from Main Office	yes	Column	Concrete	Tan	Chipping	1	0.12	Negative	None	0	Negative	No	No	no	no											
1	1	S15	Stairwell across from Main Office	yes	W2	CMU	Tan	Chipping	14	0.07	Negative	None	0	Negative	No	No	no	no											
1	1	S15	Stairwell across from Main Office	yes	W3	CMU	Tan	Chipping	1	0.06	Negative	None	0	Negative	No	No	no	no											
1	1	S15	Stairwell across from Main Office	yes	Door	Metal	Brown	Friction	10	0	Negative	None	0	Negative	No	No	no	no											
1	1	S15	Stairwell across from Main Office	yes	Door Frame	Metal	Brown	Friction	15	0.02	Negative	None	0	Negative	No	No	no	no											
1	1	S15	Stairwell across from Main Office	yes	Column	Concrete	Tan	Chipping	3	0.07	Negative	None	0	Negative	No	No	no	no											
1	1	S15	Stairwell across from Main Office	yes	W4	CMU	Tan	Chipping	4	0.04	Negative	None	0	Negative	No	No	no	no											
1	1	S15	Stairwell across from Main Office	yes	Radiator	Metal	Grey	Chipping	5	0.12	Negative	None	0	Negative	No	No	no	no											
1	1	S15	Stairwell across from Main Office	yes	Ceiling	Metal	White	Chipping	5	2.5	Positive	None	0	Negative	No	Unknown	no	no											
1	1	S15	Stairwell across from Main Office	yes	Ceiling	Concrete	Tan	Flaking	4	0.12	Negative	None	0	Negative	No	Unknown	no	no											
1	1	S15	Stairwell across from Main Office	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Negative	No	No	no	no											
1	1	S15	Stairwell across from Main Office	yes	Open Stringer	Metal	Orange	Chipping	1	6	Positive	None	0	Negative	No	No	no	no											
1	1	S15	Stairwell across from Main Office	yes	Wall Stringer	Metal	Grey	Chipping	1	6.8	Positive	None	0	Negative	No	No	no	no											
1	1	S15	Stairwell across from Main Office	yes	Baluster	Metal	Orange	Chipping	2	4	Positive	None	0	Negative	No	No	no	no											
1	1	S15	Stairwell across from Main Office	yes	Newel Post	Metal	Grey	Friction	5	7	Positive	None	0	Negative	No	No	no	no											
1	1	S15	Stairwell across from Main Office	yes	Riser	Metal	Grey	Chipping	3	3.5	Positive	None	0	Negative	No	No	no	no											
1	1	S15	Stairwell across from Main Office	yes	Handrail	Metal	Orange	Friction	20	3.7	Positive	None	0	Negative	No	No	no	no											
1	1	115A	Boy's Restroom across from Main Office	yes	W1	CMU	White	None	0	N/A	N/A	None	0	Negative	No	No	no	no											
1	1	115A	Boy's Restroom across from Main Office	yes	Door Frame	Metal	Tan	Chipping	4	0.25	Negative	None	0	Negative	No	No	no	no											
1	1	115A	Boy's Restroom across from Main Office	yes	W1	Glazed Terracotta	Green	None	0	N/A	N/A	None	0	Negative	No	No	no	no											
1	1	115A	Boy's Restroom across from Main Office	yes	W2	CMU	White	None	0	N/A	N/A	None	0	Negative	No	No	no	no											
1	1	115A	Boy's Restroom across from Main Office	yes	W2	Glazed Terracotta	Green	None	0	N/A	N/A	None	0	Negative	No	No	no	no											
1	1	115A	Boy's Restroom across from Main Office	yes	W3	CMU	White	Flaking	2	0	Negative	None	0	Negative	No	No	no	no											
1	1	115A	Boy's Restroom across from Main Office	yes	W3	Glazed Terracotta	Green	None	0	N/A	N/A	None	0	Negative	No	No	no	no											
1	1	115A	Boy's Restroom across from Main Office	yes	Radiator	Metal	Grey	Chipping	1	0.05	Negative	None	0	Negative	No	No	no	no											
1	1	115A	Boy's Restroom across from Main Office	yes	Pipe	Metal	Grey	Chipping	3	0.27	Negative	None	0	Negative	No	No	no	no											
1	1	115A	Boy's Restroom across from Main Office	yes	Door	Metal	Brown	Friction	1	0	Negative	None	0	Negative	No	No	no	no											
1	1	115A	Boy's Restroom across from Main Office	yes	Door Frame	Metal	Brown	Chipping	2	0.17	Negative	None	0	Negative	No	No	no	no											
1	1	115A	Boy's Restroom across from Main Office	yes	W4	CMU	White	None	0	N/A	N/A	None	0	Negative	No	No	no	no											
1	1	115A	Boy's Restroom across from Main Office	yes	W4	Glazed Terracotta	Green	None	0	N/A	N/A	None	0	Negative	No	No	no	no											
1	1	115A	Boy's Restroom across from Main Office	yes	Radiator	Metal	Grey	Chipping	2	0.08	Negative	None	0	Negative	No	No	no	no											
1	1	115A	Boy's Restroom across from Main Office	yes	Ceiling	Concrete	White	None	0	N/A	N/A	None	0	Negative	No	No	no	no											
1	1	115A	Boy's Restroom across from Main Office	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Negative	No	No	no	no											
1	1	115B	Closet adjacent to Main Office Boy's Restroom	yes	W1	CMU	Tan	None	0	N/A	N/A	None	0	Negative	No	No	no	no											

			School District of Philadelphia																										
			Name of Inspector: Jen Drialo		Lead Safe Certification Assessment Report																								
			Inspection Company: Synertech, Inc.		Gideon ES School																								
E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate	Color	Damage	Damage amount (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes										
1	1	115B	Closet adjacent to Main Office Boy's Restroom	yes	Door Frame	Metal	Tan	Chipping	2	0.11	Negative	None	0	Negative	No	No	no	no											
1	1	115B	Closet adjacent to Main Office Boy's Restroom	yes	W2	CMU	Tan	None	0	N/A	N/A	None	0	Negative	No	No	no	no											
1	1	115B	Closet adjacent to Main Office Boy's Restroom	yes	W3	CMU	Tan	None	0	N/A	N/A	None	0	Negative	No	No	no	no											
1	1	115B	Closet adjacent to Main Office Boy's Restroom	yes	W4	CMU	Tan	None	0	N/A	N/A	None	0	Negative	No	No	no	no											
1	1	115B	Closet adjacent to Main Office Boy's Restroom	yes	Conduit	Metal	Grey	None	0	N/A	N/A	None	0	Negative	No	No	no	no											
1	1	115B	Closet adjacent to Main Office Boy's Restroom	yes	Ceiling	Concrete	White	Flaking	1	0	Negative	None	0	Negative	No	No	no	no											
1	1	115B	Closet adjacent to Main Office Boy's Restroom	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Negative	No	No	no	no											
1	1	115C	Custodial Closet across from Main Office	no	W1	CMU	Blue	None	0	N/A	N/A	None	0	Negative	Partially Inaccessible	No	no	no											
1	1	115C	Custodial Closet across from Main Office	no	Door Frame	Metal	Tan	Chipping	4	0.12	Negative	None	0	Negative	No	No	no	no											
1	1	115C	Custodial Closet across from Main Office	no	W2	CMU	Blue	Chipping	2	0	Negative	None	0	Negative	Partially Inaccessible	No	no	no											
1	1	115C	Custodial Closet across from Main Office	no	W3	CMU	Blue	Chipping	4	0	Negative	None	0	Negative	Partially Inaccessible	No	no	no											
1	1	115C	Custodial Closet across from Main Office	no	W4	CMU	Blue	None	0	N/A	N/A	None	0	Negative	Partially Inaccessible	No	no	no											
1	1	115C	Custodial Closet across from Main Office	no	Ceiling	Concrete	White	Flaking	4	0.05	Negative	None	0	Negative	No	No	no	no											
1	1	115C	Custodial Closet across from Main Office	no	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Negative	No	No	no	no											
1	1	115	Girl's Restroom across from Main Office	yes	W1	CMU	White	None	0	N/A	N/A	None	0	Negative	No	No	no	no											
1	1	115	Girl's Restroom across from Main Office	yes	Door Frame	Metal	Tan	Chipping	4	0.25	Negative	None	0	Negative	No	No	no	no											
1	1	115	Girl's Restroom across from Main Office	yes	W1	Glazed Terracotta	Green	None	0	N/A	N/A	None	0	Negative	No	No	no	no											
1	1	115	Girl's Restroom across from Main Office	yes	W2	CMU	White	None	0	N/A	N/A	None	0	Negative	No	No	no	no											
1	1	115	Girl's Restroom across from Main Office	yes	W2	Glazed Terracotta	Green	None	0	N/A	N/A	None	0	Negative	No	No	no	no											
1	1	115	Girl's Restroom across from Main Office	yes	W3	CMU	White	Flaking	2	0	Negative	None	0	Negative	No	No	no	no											
1	1	115	Girl's Restroom across from Main Office	yes	W3	Glazed Terracotta	Green	None	0	N/A	N/A	None	0	Negative	No	No	no	no											
1	1	115	Girl's Restroom across from Main Office	yes	Access Panel	Metal	Grey	Chipping	4	0	Negative	None	0	Negative	No	No	no	no											
1	1	115	Girl's Restroom across from Main Office	yes	Pipe	Metal	Grey	Chipping	3	0.27	Negative	None	0	Negative	No	No	no	no											
1	1	115	Girl's Restroom across from Main Office	yes	Door	Metal	Brown	Friction	1	0	Negative	None	0	Negative	No	No	no	no											
1	1	115	Girl's Restroom across from Main Office	yes	Door Frame	Metal	Brown	Chipping	2	0.17	Negative	None	0	Negative	No	No	no	no											
1	1	115	Girl's Restroom across from Main Office	yes	W4	CMU	White	None	0	N/A	N/A	None	0	Negative	No	No	no	no											
1	1	115	Girl's Restroom across from Main Office	yes	W4	Glazed Terracotta	Green	None	0	N/A	N/A	None	0	Negative	No	No	no	no											
1	1	115	Girl's Restroom across from Main Office	yes	Radiator	Metal	Grey	Chipping	2	0.08	Negative	None	0	Negative	No	No	no	no											
1	1	115	Girl's Restroom across from Main Office	yes	Ceiling	Concrete	White	None	0	N/A	N/A	None	0	Negative	No	No	no	no											
1	1	115	Girl's Restroom across from Main Office	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Negative	No	No	no	no											
1	1	114	Vice Principal's Office	yes	W1	CMU	Green	None	0	N/A	N/A	None	0	Negative	No	No	no	no											
1	1	114	Vice Principal's Office	yes	W1	CMU	White	None	0	N/A	N/A	None	0	Negative	No	No	no	no											
1	1	114	Vice Principal's Office	yes	Door Frame	Metal	Blue	Chipping	10	0.3	Negative	None	0	Negative	No	No	no	no											
1	1	114	Vice Principal's Office	yes	W2	CMU	Green	None	0	N/A	N/A	None	0	Negative	No	No	no	no											
1	1	114	Vice Principal's Office	yes	W2	CMU	White	None	0	N/A	N/A	None	0	Negative	No	No	no	no											
1	1	114	Vice Principal's Office	yes	W3	CMU	Green	None	0	N/A	N/A	None	0	Negative	No	No	no	no											
1	1	114	Vice Principal's Office	yes	W3	CMU	White	None	0	N/A	N/A	None	0	Negative	No	No	no	no											
1	1	114	Vice Principal's Office	yes	W4	CMU	Green	Chipping	3	0	Negative	None	0	Negative	No	No	no	no											
1	1	114	Vice Principal's Office	yes	W4	CMU	White	None	0	N/A	N/A	None	0	Negative	No	No	no	no											
1	1	114	Vice Principal's Office	yes	Radiator	Metal	Green	None	0	N/A	N/A	None	0	Negative	No	No	no	no											
1	1	114	Vice Principal's Office	yes	Pipe	Metal	Green	None	0	0.29	Negative	None	0	Negative	No	No	no	no											
1	1	114	Vice Principal's Office	yes	Ceiling	Concrete	White	Flaking	4	0.03	Negative	None	0	Negative	No	No	no	no											
1	1	114	Vice Principal's Office	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Negative	No	No	no	no											
1	1	113A	Counselor's Office adjacent to Vice Principa's Office	yes	W1	CMU	Green	None	0	N/A	N/A	None	0	Negative	No	No	no	no											

			School District of Philadelphia																						
			Name of Inspector: Jen Drialo		Lead Safe Certification Assessment Report																	Inspection Dates: 9/20/21-10/7/21			
			Inspection Company: Synertech, Inc.		Gideon ES School																	ULCS# 4530			
E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate	Color	Damage	Damage amount (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes						
1	1	113A	Counselor's Office adjacent to Vice Principa's Office	yes	W1	CMU	White	None	0	N/A	N/A	None	0	Negative	No	No	no	no							
1	1	113A	Counselor's Office adjacent to Vice Principa's Office	yes	Door Frame	Metal	Blue	Chipping	3	0.4	Negative	None	0	Negative	No	No	no	no							
1	1	113A	Counselor's Office adjacent to Vice Principa's Office	yes	W2	CMU	Green	None	0	N/A	N/A	None	0	Negative	Partially Inaccessible	No	no	no							
1	1	113A	Counselor's Office adjacent to Vice Principa's Office	yes	W2	CMU	White	None	0	N/A	N/A	None	0	Negative	No	No	no	no							
1	1	113A	Counselor's Office adjacent to Vice Principa's Office	yes	W3	CMU	Green	None	0	N/A	N/A	None	0	Negative	Partially Inaccessible	No	no	no							
1	1	113A	Counselor's Office adjacent to Vice Principa's Office	yes	W3	CMU	White	None	0	N/A	N/A	None	0	Negative	No	No	no	no							
1	1	113A	Counselor's Office adjacent to Vice Principa's Office	yes	W4	CMU	Green	None	0	N/A	N/A	None	0	Negative	No	No	no	no							
1	1	113A	Counselor's Office adjacent to Vice Principa's Office	yes	W4	CMU	White	None	0	N/A	N/A	None	0	Negative	No	No	no	no							
1	1	113A	Counselor's Office adjacent to Vice Principa's Office	yes	Ceiling	Concrete	White	Chipping	1	0.05	Negative	None	0	Negative	No	No	no	no							
1	1	113A	Counselor's Office adjacent to Vice Principa's Office	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Negative	No	No	no	no							
1	1	113A1	Counselor's Office Closet	yes	W1	CMU	Brown	None	0	N/A	N/A	None	0	Negative	No	No	no	no							
1	1	113A1	Counselor's Office Closet	yes	Door Frame	Metal	Blue	Chipping	4	0.4	Negative	None	0	Negative	No	No	no	no							
1	1	113A1	Counselor's Office Closet	yes	W2	CMU	Brown	None	0	N/A	N/A	None	0	Negative	No	No	no	no							
1	1	113A1	Counselor's Office Closet	yes	Partition	Wood	White	Chipping	1	1.1	Positive	None	0	Negative	No	No	no	no	Bottom of wall						
1	1	113A1	Counselor's Office Closet	yes	W3	CMU	Brown	None	0	N/A	N/A	None	0	Negative	No	No	no	no							
1	1	113A1	Counselor's Office Closet	yes	W4	CMU	Brown	None	0	N/A	N/A	None	0	Negative	No	No	no	no							
1	1	113A1	Counselor's Office Closet	yes	Ceiling	Concrete	White	None	0	N/A	N/A	None	0	Negative	No	No	no	no							
1	1	113A1	Counselor's Office Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Negative	No	No	no	no							
1	1	H15	Entrance to Nurse / Counselor Suite	yes	W1	CMU	Yellow	Chipping	1	0	Negative	None	0	Negative	No	No	no	no							
1	1	H15	Entrance to Nurse / Counselor Suite	yes	Door Frame	Metal	Blue	Chipping	2	0.06	Negative	None	0	Negative	No	No	no	no							
1	1	H15	Entrance to Nurse / Counselor Suite	yes	W2	CMU	Yellow	None	0	0	Negative	None	0	Negative	No	No	no	no							
1	1	H15	Entrance to Nurse / Counselor Suite	yes	Door Frame	Metal	Blue	Chipping	4	0.12	Negative	None	0	Negative	No	No	no	no							
1	1	H15	Entrance to Nurse / Counselor Suite	yes	W3	CMU	Yellow	None	0	0	Negative	None	0	Negative	No	No	no	no							
1	1	H15	Entrance to Nurse / Counselor Suite	yes	Door Frame	Metal	Blue	Chipping	5	0.1	Negative	None	0	Negative	No	No	no	no							
1	1	H15	Entrance to Nurse / Counselor Suite	yes	W4	CMU	Yellow	None	0	0	Negative	None	0	Negative	No	No	no	no							
1	1	H15	Entrance to Nurse / Counselor Suite	yes	Door Frame	Metal	Blue	Chipping	1	0.16	Negative	None	0	Negative	No	No	no	no							
1	1	H15	Entrance to Nurse / Counselor Suite	yes	Ceiling	Concrete	White	Flaking	2	0.04	Negative	None	0	Negative	No	No	no	no							
1	1	H15	Entrance to Nurse / Counselor Suite	yes	Vent	Metal	White	None	0	N/A	N/A	None	0	Negative	No	No	no	no							
1	1	H15	Entrance to Nurse / Counselor Suite	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Negative	No	No	no	no							
1	1	113	Counselor's Office adjacent to Restroom	yes	W1	CMU	Tan	None	0	N/A	N/A	None	0	Negative	No	No	no	no							
1	1	113	Counselor's Office adjacent to Restroom	yes	W1	CMU	White	None	0	N/A	N/A	None	0	Negative	No	No	no	no							
1	1	113	Counselor's Office adjacent to Restroom	yes	Door Frame	Metal	Tan	Chipping	4	0.4	Negative	None	0	Negative	No	No	no	no							
1	1	113	Counselor's Office adjacent to Restroom	yes	W2	CMU	Tan	None	0	N/A	N/A	None	0	Negative	No	No	no	no							
1	1	113	Counselor's Office adjacent to Restroom	yes	W2	CMU	White	None	0	N/A	N/A	None	0	Negative	No	No	no	no							
1	1	113	Counselor's Office adjacent to Restroom	yes	W3	CMU	Tan	None	0	N/A	N/A	None	0	Negative	No	No	no	no							
1	1	113	Counselor's Office adjacent to Restroom	yes	W3	CMU	White	None	0	N/A	N/A	None	0	Negative	No	No	no	no							
1	1	113	Counselor's Office adjacent to Restroom	yes	Radiator	Metal	Tan	Chipping	2	0.18	Negative	None	0	Negative	No	No	no	no							
1	1	113	Counselor's Office adjacent to Restroom	yes	W4	CMU	Tan	Chipping	1	0	Negative	None	0	Negative	No	No	no	no							
1	1	113	Counselor's Office adjacent to Restroom	yes	W4	CMU	White	None	0	N/A	N/A	None	0	Negative	No	No	no	no							
1	1	113	Counselor's Office adjacent to Restroom	yes	Ceiling	Concrete	White	Flaking	2	0.05	Negative	None	0	Negative	No	No	no	no							
1	1	113	Counselor's Office adjacent to Restroom	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Negative	No	No	no	no							
1	1	113C	Counselor Suite Restroom	yes	W1	CMU	Tan	None	0	N/A	N/A	None	0	Negative	No	No	no	no							

			School District of Philadelphia																				
			Name of Inspector: Jen Drialo		Lead Safe Certification Assessment Report							Inspection Dates: 9/20/21-10/7/21											
			Inspection Company: Synertech, Inc.		Gideon ES School							ULCS# 4530											
E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate	Color	Damage	Damage amount (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes				
1	1	113C	Counselor Suite Restroom	yes	W1	CMU	White	None	0	N/A	N/A	None	0	Negative	No	No	no	no					
1	1	113C	Counselor Suite Restroom	yes	Door Frame	Metal	Tan	Chipping	2	0.4	Negative	None	0	Negative	No	No	no	no					
1	1	113C	Counselor Suite Restroom	yes	W2	CMU	Tan	None	0	N/A	N/A	None	0	Negative	No	No	no	no					
1	1	113C	Counselor Suite Restroom	yes	W2	CMU	White	None	0	N/A	N/A	None	0	Negative	No	No	no	no					
1	1	113C	Counselor Suite Restroom	yes	W3	CMU	Tan	Chipping	1	0	Negative	None	0	Negative	No	No	no	no					
1	1	113C	Counselor Suite Restroom	yes	W3	CMU	White	None	0	N/A	N/A	None	0	Negative	No	No	no	no					
1	1	113C	Counselor Suite Restroom	yes	W4	CMU	Tan	None	0	N/A	N/A	None	0	Negative	No	No	no	no					
1	1	113C	Counselor Suite Restroom	yes	W4	CMU	White	None	0	N/A	N/A	None	0	Negative	No	No	no	no					
1	1	113C	Counselor Suite Restroom	yes	Ceiling	Concrete	White	None	0	N/A	N/A	None	0	Negative	No	No	no	no					
1	1	113C	Counselor Suite Restroom	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Negative	No	No	no	no					
1	1	112A	Security Camera Room	yes	W1	CMU	Blue	Flaking	8	0	Negative	None	0	Negative	No	No	no	no					
1	1	112A	Security Camera Room	yes	W1	Sheetrock	Tan	None	0	N/A	N/A	None	0	Negative	No	No	no	no					
1	1	112A	Security Camera Room	yes	Door Frame	Metal	Tan	Chipping	5	0.23	Negative	None	0	Negative	No	No	no	no					
1	1	112A	Security Camera Room	yes	W2	CMU	Green	Flaking	20	0	Negative	None	0	Negative	No	No	no	no					
1	1	112A	Security Camera Room	yes	W3	CMU	Tan	Chipping	2	0	Negative	None	0	Negative	No	No	no	no					
1	1	112A	Security Camera Room	yes	Pipe	Metal	Green	Chipping	3	0.4	Negative	None	0	Negative	No	No	no	no					
1	1	112A	Security Camera Room	yes	W4	CMU	Tan	Flaking	25	0	Negative	None	0	Negative	No	No	no	no					
1	1	112A	Security Camera Room	yes	Ceiling	Concrete	Brown	Flaking	50	0.03	Negative	None	0	Negative	No	No	no	no					
1	1	112A	Security Camera Room	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Negative	No	No	no	no					
1	1	112E	Hallway to Women's Restroom and Camera Room	yes	W1	CMU	Tan	Flaking	1	0	Negative	None	0	Negative	No	No	no	no					
1	1	112E	Hallway to Women's Restroom and Camera Room	yes	Door Frame	Metal	Blue	Chipping	2	0.4	Negative	None	0	Negative	No	No	no	no					
1	1	112E	Hallway to Women's Restroom and Camera Room	yes	W2	CMU	Tan	Flaking	10	0	Negative	None	0	Negative	No	No	no	no					
1	1	112E	Hallway to Women's Restroom and Camera Room	yes	W3	Sheetrock	Tan	None	0	N/A	N/A	None	0	Negative	No	No	no	no					
1	1	112E	Hallway to Women's Restroom and Camera Room	yes	W4	CMU	Tan	None	5	0	Negative	None	0	Negative	No	No	no	no					
1	1	112E	Hallway to Women's Restroom and Camera Room	yes	Access Panel	Metal	Tan	Chipping	1	2.5	Positive	None	0	Negative	No	No	no	no					
1	1	112E	Hallway to Women's Restroom and Camera Room	yes	Ceiling	Concrete	Tan	Flaking	15	0.03	Negative	None	0	Negative	No	No	no	no					
1	1	112E	Hallway to Women's Restroom and Camera Room	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Negative	No	No	no	no					
1	1	112C	Women's Restroom adjacent to Camera Room	yes	W1	CMU	White	Chipping	1	0	Negative	None	0	Negative	No	No	no	no					
1	1	112C	Women's Restroom adjacent to Camera Room	yes	Door Frame	Metal	White	Chipping	1	0.5	Negative	None	0	Negative	No	No	no	no					
1	1	112C	Women's Restroom adjacent to Camera Room	yes	W2	CMU	White	Chipping	2	0	Negative	None	0	Negative	No	No	no	no					
1	1	112C	Women's Restroom adjacent to Camera Room	yes	W3	CMU	White	None	0	0	Negative	None	0	Negative	No	No	no	no					
1	1	112C	Women's Restroom adjacent to Camera Room	yes	W4	CMU	White	None	0	0	Negative	None	0	Negative	No	No	no	no					
1	1	112C	Women's Restroom adjacent to Camera Room	yes	Ceiling	Concrete	White	None	0	N/A	N/A	None	0	Negative	No	No	no	no					
1	1	112C	Women's Restroom adjacent to Camera Room	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Negative	No	No	no	no					
1	1	111B	Men's Restroom next to Building Engineer's Office	yes	W1	CMU	White	Chipping	1	0	Negative	None	0	Negative	No	No	no	no					
1	1	111B	Men's Restroom next to Building Engineer's Office	yes	Door Frame	Metal	White	Chipping	2	0.4	Negative	None	0	Negative	No	No	no	no					
1	1	111B	Men's Restroom next to Building Engineer's Office	yes	W2	CMU	White	None	0	0	Negative	None	0	Negative	No	No	no	no					
1	1	111B	Men's Restroom next to Building Engineer's Office	yes	W3	CMU	White	None	0	0	Negative	None	0	Negative	No	No	no	no					
1	1	111B	Men's Restroom next to Building Engineer's Office	yes	W4	CMU	White	None	0	0	Negative	None	0	Negative	No	No	no	no					
1	1	111B	Men's Restroom next to Building Engineer's Office	yes	Ceiling	Concrete	White	Flaking	4	0.03	Negative	None	0	Negative	No	No	no	no					
1	1	111B	Men's Restroom next to Building Engineer's Office	yes	Vent	Metal	White	Chipping	1	0.07	Negative	None	0	Negative	No	No	no	no					
1	1	111B	Men's Restroom next to Building Engineer's Office	yes	Floor	Concrete	Grey	Friction	2	0	Negative	None	0	Negative	No	No	no	no					
1	1	109	Conference Room 109	yes	W1	CMU	Tan	Flaking	2	0	Negative	None	0	Negative	No	No	no	no					
1	1	109	Conference Room 109	yes	Door Frame	Metal	Tan	Chipping	10	0.5	Negative	None	0	Negative	No	No	no	no					
1	1	109	Conference Room 109	yes	W2	CMU	Tan	Flaking	2	0	Negative	None	0	Negative	No	No	no	no					
1	1	109	Conference Room 109	yes	W3	CMU	Tan	Chipping	6	0	Negative	None	0	Negative	No	No	no	no					
1	1	109	Conference Room 109	yes	Pipe	Metal	Tan	Flaking	1	0.4	Negative	None	0	Negative	No	No	no	no					
1	1	109	Conference Room 109	yes	Column	Concrete	Tan	Flaking	3	0.04	Negative	None	0	Negative	No	No	no	no					
1	1	109	Conference Room 109	yes	Cabinet Top	Wood	Green	Flaking	20	0.25	Negative	None	0	Negative	No	No	no	no					
1	1	109	Conference Room 109	yes	Shelves	Metal	Tan	Friction	2	0.12	Negative	None	0	Negative	No	No	no	no					



			School District of Philadelphia																				
			Name of Inspector: Jen Drialo		Lead Safe Certification Assessment Report							Inspection Dates: 9/20/21-10/7/21											
			Inspection Company: Synertech, Inc.		Gideon ES School							ULCS# 4530											
E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate	Color	Damage	Damage amount (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes				
1	1	S13	Stairwell adjacent to Classroom 111	yes	Open Stringer	Metal	Orange	Chipping	4	6	Positive	None	0	Negative	No	No	no	no					
1	1	S13	Stairwell adjacent to Classroom 111	yes	Wall Stringer	Metal	Grey	Chipping	1	6.8	Positive	None	0	Negative	No	No	no	no					
1	1	S13	Stairwell adjacent to Classroom 111	yes	Baluster	Metal	Orange	Chipping	15	4	Positive	None	0	Negative	No	No	no	no					
1	1	S13	Stairwell adjacent to Classroom 111	yes	Newel Post	Metal	Grey	Friction	5	7	Positive	None	0	Negative	No	No	no	no					
1	1	S13	Stairwell adjacent to Classroom 111	yes	Riser	Metal	Grey	Chipping	3	3.5	Positive	None	0	Negative	No	No	no	no					
1	1	S13	Stairwell adjacent to Classroom 111	yes	Handrail	Metal	Orange	Friction	30	3.7	Positive	None	0	Negative	No	No	no	no					
1	1	110	Classroom 110	yes	W1	CMU	Grey	Chipping	4	0	Negative	None	0	Negative	No	No	no	no					
1	1	110	Classroom 110	yes	Door Frame	Metal	Grey	Chipping	6	0.07	Negative	None	0	Negative	No	No	no	no					
1	1	110	Classroom 110	yes	W2	CMU	Grey	Chipping	6	0	Negative	None	0	Negative	No	No	no	no					
1	1	110	Classroom 110	yes	W3	CMU	Grey	None	0	N/A	N/A	None	0	Negative	No	No	no	no					
1	1	110	Classroom 110	yes	Pipe	Metal	White	Flaking	3	0.5	Negative	None	0	Negative	No	No	no	no					
1	1	110	Classroom 110	yes	Column	Concrete	Grey	Flaking	1	0.1	Negative	None	0	Negative	No	No	no	no					
1	1	110	Classroom 110	yes	Cabinet Top	Wood	Grey	Flaking	2	0.21	Negative	None	0	Negative	No	No	no	no					
1	1	110	Classroom 110	yes	Shelves	Metal	Grey	Friction	2	0.1	Negative	None	0	Negative	No	No	no	no					
1	1	110	Classroom 110	yes	Univent	Metal	Grey	Chipping	1	0	Negative	None	0	Negative	No	No	no	no					
1	1	110	Classroom 110	yes	Pipe	Metal	White	Flaking	3	0.5	Negative	None	0	Negative	No	No	no	no					
1	1	110	Classroom 110	yes	W4	CMU	Orange	None	0	N/A	N/A	None	0	Negative	No	No	no	no					
1	1	110	Classroom 110	yes	Ceiling	Concrete	White	None	0	N/A	N/A	None	0	Negative	No	No	no	no					
1	1	110	Classroom 110	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Negative	No	No	no	no					
1	1	110A	Classroom 110 Closet	yes	Door Frame	Metal	Grey	Chipping	2	0.18	Negative	None	0	Negative	No	No	no	no					
1	1	110A	Classroom 110 Closet	yes	W2	CMU	Grey	None	0	0	Negative	None	0	Negative	No	No	no	no					
1	1	110A	Classroom 110 Closet	yes	Partition	Wood	Grey	Chipping	1	2.1	Positive	None	0	Negative	No	No	no	no					
1	1	110A	Classroom 110 Closet	yes	Shelves	Wood	Grey	Friction	2	0.8	Positive	None	0	Negative	No	No	no	no	Several shelf paint chip samples were taken and the results were positive. Shelves in the classroom closets should be treated as homogenous.				
1	1	110A	Classroom 110 Closet	yes	W2	CMU	Grey	None	0	N/A	N/A	None	0	Negative	No	No	no	no					
1	1	110A	Classroom 110 Closet	yes	W3	Wood	Grey	Chipping	2	0	Negative	None	0	Negative	No	No	no	no					
1	1	110A	Classroom 110 Closet	yes	W3	CMU	Grey	Chipping	1	0	Negative	None	0	Negative	No	No	no	no					
1	1	110A	Classroom 110 Closet	yes	W4	Wood	Grey	None	0	N/A	N/A	None	0	Negative	No	No	no	no					
1	1	110A	Classroom 110 Closet	yes	W4	CMU	Grey	Chipping	1	0	Negative	None	0	Negative	No	No	no	no					
1	1	110A	Classroom 110 Closet	yes	Vent	Metal	Grey	Chipping	2	0.4	Negative	None	0	Negative	No	No	no	no					
1	1	110A	Classroom 110 Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Negative	No	No	no	no					
1	1	111	Classroom 111	yes	W1	CMU	Tan	Chipping	5	0	Negative	None	0	Negative	No	No	no	no					
1	1	111	Classroom 111	yes	Pipe	Metal	Green	Chipping	2	0.22	Negative	None	0	Negative	No	No	no	no					
1	1	111	Classroom 111	yes	Door Frame	Metal	Tan	Chipping	4	0.07	Negative	None	0	Negative	No	No	no	no					
1	1	111	Classroom 111	yes	W2	CMU	Tan	Chipping	1	0	Negative	None	0	Negative	Partially Inaccessible	No	no	no					
1	1	111	Classroom 111	yes	W3	CMU	Tan	None	0	N/A	N/A	None	0	Negative	No	No	no	no					
1	1	111	Classroom 111	yes	Pipe	Metal	Tan	Chipping	2	0.5	Negative	None	0	Negative	No	No	no	no	Paint Chip Sample Collected; 0.16% Pb/Weight				
1	1	111	Classroom 111	yes	Column	Concrete	Tan	Flaking	1	0.1	Negative	None	0	Negative	No	No	no	no					
1	1	111	Classroom 111	yes	Cabinet Top	Wood	Tan	Flaking	4	0.23	Negative	None	0	Negative	No	No	no	no					
1	1	111	Classroom 111	yes	Shelves	Metal	Tan	Friction	6	0.12	Negative	None	0	Negative	No	No	no	no					
1	1	111	Classroom 111	yes	Univent	Metal	Tan	Chipping	1	0	Negative	None	0	Negative	No	No	no	no					
1	1	111	Classroom 111	yes	Pipe	Metal	White	Flaking	3	0.5	Negative	None	0	Negative	No	No	no	no					
1	1	111	Classroom 111	yes	W4	CMU	Tan	Chipping	2	0	Negative	None	0	Negative	No	No	no	no					
1	1	111	Classroom 111	yes	Ceiling	Concrete	White	Flaking	10	0.03	Negative	None	0	Negative	No	No	no	no					
1	1	111	Classroom 111	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Negative	No	No	no	no					
1	1	111A	Classroom 111 Closet	yes	W2	CMU	Brown	None	0	0	Negative	None	0	Negative	No	No	no	no					
1	1	111A	Classroom 111 Closet	yes	Partition	Wood	Brown	Chipping	1	2.1	Positive	None	0	Negative	No	No	no	no					
1	1	111A	Classroom 111 Closet	yes	Shelves	Wood	Brown	Friction	2	0.8	Positive	None	0	Negative	No	No	no	no	Several shelf paint chip samples were taken and the results were positive. Shelves in the classroom closets should be treated as homogenous.				
1	1	111A	Classroom 111 Closet	yes	W2	CMU	Brown	None	0	N/A	N/A	None	0	Negative	No	No	no	no					
1	1	111A	Classroom 111 Closet	yes	W3	Wood	Brown	Chipping	2	0	Negative	None	0	Negative	No	No	no	no					
1	1	111A	Classroom 111 Closet	yes	W3	CMU	Brown	Chipping	1	0	Negative	None	0	Negative	No	No	no	no					
1	1	111A	Classroom 111 Closet	yes	W4	Wood	Brown	None	0	N/A	N/A	None	0	Negative	No	No	no	no					
1	1	111A	Classroom 111 Closet	yes	W4	CMU	Brown	Chipping	1	0	Negative	None	0	Negative	No	No	no	no					
1	1	111A	Classroom 111 Closet	yes	Ceiling	Wood	Brown	None	0	N/A	N/A	None	0	Negative	No	No	no	no					
1	1	111A	Classroom 111 Closet	yes	Vent	Metal	Brown	Chipping	2	0.4	Negative	None	0	Negative	No	No	no	no					
1	1	111A	Classroom 111 Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Negative	No	No	no	no					
1	1	111C	Community/School Coordinator Office Room 111	yes	W1	CMU	Tan	Chipping	8	0	Negative	None	0	Negative	No	No	no	no					

			School District of Philadelphia																								
			Name of Inspector: Jen Drialo		Lead Safe Certification Assessment Report																						
			Inspection Company: Synertech, Inc.		Gideon ES School																						
E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate	Color	Damage	Damage amount (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes								
1	1	111C	Community/School Coordinator Office Room 111	yes	Door Frame	Metal	Tan	Chipping	10	0.16	Negative	None	0	Negative	No	No	no	no									
1	1	111C	Community/School Coordinator Office Room 111	yes	W2	CMU	Tan	Chipping	1	0	Negative	None	0	Negative	Partially Inaccessible	No	no	no									
1	1	111C	Community/School Coordinator Office Room 111	yes	W3	CMU	Tan	None	0	0	Negative	None	0	Negative	No	No	no	no									
1	1	111C	Community/School Coordinator Office Room 111	yes	Cabinet Top	Wood	Tan	Chipping	2	0.1	Negative	None	0	Negative	Partially Inaccessible	No	no	no									
1	1	111C	Community/School Coordinator Office Room 111	yes	Shelves	Metal	Tan	Friction	4	0.16	Negative	None	0	Negative	No	No	no	no									
1	1	111C	Community/School Coordinator Office Room 111	yes	Univent	Metal	Tan	Chipping	2	0.06	Negative	None	0	Negative	No	No	no	no									
1	1	111C	Community/School Coordinator Office Room 111	yes	Pipe	Metal	Tan	Flaking	3	0.24	Negative	None	0	Negative	No	No	no	no									
1	1	111C	Community/School Coordinator Office Room 111	yes	Column	Concrete	Tan	Flaking	5	0.08	Negative	None	0	Negative	No	No	no	no									
1	1	111C	Community/School Coordinator Office Room 111	yes	W4	CMU	Tan	Flaking	2	0	Negative	None	0	Negative	Partially Inaccessible	No	no	no									
1	1	111C	Community/School Coordinator Office Room 111	yes	Ceiling	Concrete	White	Flaking	30	0.04	Negative	None	0	Negative	No	No	no	no									
1	1	111C	Community/School Coordinator Office Room 111	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Negative	No	No	no	no									
1	1	H13	Hallway from Classrooms 111 to 103	yes	W1	CMU	Yellow	Chipping	1	0	Negative	None	0	Negative	No	No	no	no									
1	1	H13	Hallway from Classrooms 111 to 103	yes	Door Frame	Metal	Blue	Chipping	2	0.23	Negative	None	0	Negative	No	No	no	no									
1	1	H13	Hallway from Classrooms 111 to 103	yes	W2	CMU	Yellow	None	0	N/A	N/A	None	0	Negative	No	No	no	no									
1	1	H13	Hallway from Classrooms 111 to 103	yes	Door	Metal	Blue	None	0	N/A	N/A	None	0	Negative	No	No	no	no									
1	1	H13	Hallway from Classrooms 111 to 103	yes	Door Frame	Metal	Blue	Chipping	1	0.2	Negative	None	0	Negative	No	No	no	no									
1	1	H13	Hallway from Classrooms 111 to 103	yes	W3	CMU	Yellow	None	0	N/A	N/A	None	0	Negative	No	No	no	no									
1	1	H13	Hallway from Classrooms 111 to 103	yes	Radiator	Metal	Blue	Chipping	10	0.05	Negative	None	0	Negative	No	No	no	no									
1	1	H13	Hallway from Classrooms 111 to 103	yes	W4	CMU	Yellow	None	0	N/A	N/A	None	0	Negative	No	No	no	no									
1	1	H13	Hallway from Classrooms 111 to 103	yes	Ceiling	Concrete	White	None	0	N/A	N/A	None	0	Negative	No	No	no	no									
1	1	H13	Hallway from Classrooms 111 to 103	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Negative	No	No	no	no									
1	1	H13PC	Pipe chase in hallway next to teacher's lounge	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Negative	No	No	no	no									
1	1	H13PC	Pipe chase in hallway next to teacher's lounge	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Negative	No	No	no	no									
1	1	H13PC	Pipe chase in hallway next to teacher's lounge	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Negative	No	No	no	no									
1	1	H13PC	Pipe chase in hallway next to teacher's lounge	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Negative	No	No	no	no									
1	1	H13PC	Pipe chase in hallway next to teacher's lounge	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Negative	No	No	no	no									
1	1	H13PC	Pipe chase in hallway next to teacher's lounge	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Negative	No	No	no	no									
1	BS	004B	Boiler Room Mezzanine	no	W1	CMU	Tan	Flaking	450	0.17	Negative	None	0	Negative	No	No	no	no									
1	BS	004B	Boiler Room Mezzanine	no	W1	Concrete	White	Flaking	200	0.4	Negative	None	0	Negative	No	No	no	no									
1	BS	004B	Boiler Room Mezzanine	no	W2	CMU	Tan	Flaking	600	0.19	Negative	None	0	Negative	No	No	no	no									
1	BS	004B	Boiler Room Mezzanine	no	W2	Concrete	White	Flaking	400	0.5	Negative	None	0	Negative	No	No	no	no									
1	BS	004B	Boiler Room Mezzanine	no	W3	CMU	Tan	Flaking	800	0.15	Negative	None	0	Negative	No	No	no	no									
1	BS	004B	Boiler Room Mezzanine	no	W3	Concrete	White	Flaking	350	0.4	Negative	None	0	Negative	No	No	no	no									
1	BS	004B	Boiler Room Mezzanine	no	W4	CMU	Tan	Flaking	400	0.17	Negative	None	0	Negative	No	No	no	no									
1	BS	004B	Boiler Room Mezzanine	no	W4	Concrete	White	Flaking	900	0.3	Negative	None	0	Negative	No	No	no	no									
1	BS	004B	Boiler Room Mezzanine	no	Ceiling	Concrete	White	Flaking	1100	0.06	Negative	None	0	Negative	No	No	no	no									
1	BS	004B	Boiler Room Mezzanine	no	Floor	Concrete	Grey	Flaking	650	0	Negative	None	0	Negative	No	No	no	no									
1	BS	007B	Office	yes	W1	CMU	White	Flaking	20	0.16	Negative	None	0	Negative	No	No	no	no									
1	BS	007B	Office	yes	Door Frame	Metal	Tan	Chipping	2	0.4	Negative	None	0	Negative	No	No	no	no									
1	BS	007B	Office	yes	Door	Metal	Tan	Chipping	4	0	Negative	None	0	Negative	No	No	no	no									
1	BS	007B	Office	yes	W2	CMU	White	Flaking	24	0.14	Negative	None	0	Negative	No	No	no	no									
1	BS	007B	Office	yes	W2	CMU	Tan	None	N/A	N/A	N/A	None	0	Negative	No	No	no	no									
1	BS	007B	Office	yes	W3	CMU	White	Flaking	4	0.05	Negative	None	0	Negative	No	No	no	no									
1	BS	007B	Office	yes	W3	CMU	Tan	Flaking	2	0.13	Negative	None	0	Negative	No	No	no	no									
1	BS	007B	Office	yes	W4	Brick	White	Flaking	1	0	Negative	None	0	Negative	No	No	no	no									
1	BS	007B	Office	yes	W4	Brick	Tan	Flaking	4	0.09	Negative	None	0	Negative	No	No	no	no									
1	BS	007B	Office	yes	Pipe	Metal	Tan	Flaking	20	0.28	Negative	None	0	Negative	No	No	no	no									

			School District of Philadelphia																
			Name of Inspector: Jen Drialo		Lead Safe Certification Assessment Report							Inspection Dates: 9/20/21-10/7/21							
			Inspection Company: Synertech, Inc.		Gideon ES School							ULCS# 4530							
E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate	Color	Damage	Damage amount (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes
1	BS	007B	Office	yes	Pipe	Metal	White	Flaking	10	0.23	Negative	None	0	Negative	No	No	no	no	
1	BS	007B	Office	yes	Ceiling	Concrete	White	Flaking	60	0	Negative	None	0	Negative	No	No	no	no	
1	BS	007B	Office	yes	Floor	Concrete	Grey	Flaking	650	0	Negative	None	0	Negative	No	No	no	no	
1	BS	007B1	Restroom	yes	W1	CMU	White	Flaking	2	0.01	Negative	None	0	Negative	No	No	no	no	
1	BS	007B1	Restroom	yes	W1	CMU	Tan	Flaking	4	0.05	Negative	None	0	Negative	No	No	no	no	
1	BS	007B1	Restroom	yes	W2	CMU	White	Flaking	16	0.01	Negative	None	0	Negative	No	No	no	no	
1	BS	007B1	Restroom	yes	W2	CMU	Tan	Flaking	8	0.05	Negative	None	0	Negative	No	No	no	no	
1	BS	007B1	Restroom	yes	W3	CMU	White	Flaking	24	0.01	Negative	None	0	Negative	No	No	no	no	
1	BS	007B1	Restroom	yes	W3	CMU	Tan	Flaking	1	0.05	Negative	None	0	Negative	No	No	no	no	
1	BS	007B1	Restroom	yes	W4	CMU	White	Flaking	26	0.01	Negative	None	0	Negative	No	No	no	no	
1	BS	007B1	Restroom	yes	W4	CMU	Tan	Flaking	6	0.05	Negative	None	0	Negative	No	No	no	no	
1	BS	007B1	Restroom	yes	Ceiling	Concrete	White	Flaking	1000	0	Negative	None	0	Negative	No	No	no	no	
1	BS	007B1	Restroom	yes	Floor	Concrete	Grey	Flaking	600	0	Negative	None	0	Negative	No	No	no	no	
1	BS	006B	Former Custodial Staff Lounge	yes	W1	Concrete	White	Flaking	6	0	Negative	None	0	Negative	No	No	no	no	
1	BS	006B	Former Custodial Staff Lounge	yes	W1	Concrete	Tan	Flaking	10	0.08	Negative	None	0	Negative	No	No	no	no	
1	BS	006B	Former Custodial Staff Lounge	yes	Door Frame	Metal	Tan	Chipping	12	0.4	Negative	None	0	Negative	No	No	no	no	
1	BS	006B	Former Custodial Staff Lounge	yes	W2	Concrete	White	Flaking	8	0	Negative	None	0	Negative	No	No	no	no	
1	BS	006B	Former Custodial Staff Lounge	yes	W2	Concrete	Tan	Flaking	25	0.08	Negative	None	0	Negative	No	No	no	no	
1	BS	006B	Former Custodial Staff Lounge	yes	W3	Concrete	White	Flaking	10	0	Negative	None	0	Negative	No	No	no	no	
1	BS	006B	Former Custodial Staff Lounge	yes	W3	Concrete	Tan	Flaking	6	0.08	Negative	None	0	Negative	No	No	no	no	
1	BS	006B	Former Custodial Staff Lounge	yes	Door Frame	Metal	Tan	Chipping	2	0.4	Negative	None	0	Negative	No	No	no	no	
1	BS	006B	Former Custodial Staff Lounge	yes	W4	Concrete	White	Flaking	15	0	Negative	None	0	Negative	No	No	no	no	
1	BS	006B	Former Custodial Staff Lounge	yes	W4	Concrete	Tan	Flaking	20	0.08	Negative	None	0	Negative	No	No	no	no	
1	BS	006B	Former Custodial Staff Lounge	yes	Ceiling	Concrete	White	None	0	N/A	N/A	None	0	Negative	No	No	no	no	
1	BS	006B	Former Custodial Staff Lounge	yes	Floor	Concrete	N/A	None	0	N/A	N/A	None	0	Negative	No	No	no	no	
1	BS	003B	Boiler Room	no	W1	Concrete	White	Flaking	1500	0.2	Negative	None	0	Negative	No	No	no	no	
1	BS	003B	Boiler Room	no	Handrail	Metal	Black	Chipping	15	0.5	Negative	None	0	Negative	No	No	no	no	
1	BS	003B	Boiler Room	no	Stringer	Metal	Black	Chipping	12	1.9	Negative	None	0	Negative	No	No	no	no	
1	BS	003B	Boiler Room	no	Stair tread	Metal	Black	Chipping	36	0.17	Negative	None	0	Negative	No	No	no	no	
1	BS	003B	Boiler Room	no	Pipe	Metal	White	Flaking	100	1.5	Positive	None	0	Negative	No	No	no	no	
1	BS	003B	Boiler Room	no	W2	Concrete	White	Flaking	1000	0	Negative	None	0	Negative	No	No	no	no	
1	BS	003B	Boiler Room	no	W2	Concrete	Tan	Flaking	650	0.24	Negative	None	0	Negative	No	No	no	no	
1	BS	003B	Boiler Room	no	Conduit	Metal	White	Chipping	20	0.1	Negative	None	0	Negative	No	No	no	no	
1	BS	003B	Boiler Room	no	W3	Concrete	White	Flaking	950	0	Negative	None	0	Negative	No	No	no	no	
1	BS	003B	Boiler Room	no	W3	Concrete	Tan	Flaking	400	0.21	Negative	None	0	Negative	No	No	no	no	
1	BS	003B	Boiler Room	no	W4	Concrete	White	Flaking	275	0	Negative	None	0	Negative	No	No	no	no	
1	BS	003B	Boiler Room	no	W4	Concrete	Tan	Flaking	895	0.19	Negative	None	0	Negative	No	No	no	no	
1	BS	003B	Boiler Room	no	Conduit	Metal	White	Chipping	28	0.1	Negative	None	0	Negative	No	No	no	no	
1	BS	003B	Boiler Room	no	Electrical Panel	Metal	Grey	Chipping	2	0.01	Negative	None	0	Negative	No	No	no	no	
1	BS	003B	Boiler Room	no	Ceiling	Concrete	White	Flaking	1000	0	Negative	None	0	Negative	No	No	no	no	
1	BS	003B	Boiler Room	no	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	Negative	No	No	no	no	
1	BS	003B	Boiler Room	no	Boilers	Metal	Blue	Flaking	120	0.02	Negative	None	0	Negative	No	No	no	no	
1	BS	003B	Boiler Room	no	Front of Boilers	Metal	Gray	Flaking	20	0.03	Negative	None	0	Negative	No	No	no	no	
1	BS	003B	Boiler Room	no	Flame Burner	Metal	Blue	Flaking	2	0	Negative	None	0	Negative	No	No	no	no	
1	BS	002B	Boiler Room Storage Room on exterior wall	no	W1	Concrete	White	Flaking	20	0	Negative	None	0	Negative	No	No	no	no	
1	BS	002B	Boiler Room Storage Room on exterior wall	no	W1	Concrete	Tan	Flaking	15	0.08	Negative	None	0	Negative	No	No	no	no	
1	BS	002B	Boiler Room Storage Room on exterior wall	no	W2	Concrete	White	Flaking	12	0	Negative	None	0	Negative	No	No	no	no	
1	BS	002B	Boiler Room Storage Room on exterior wall	no	W2	Concrete	Tan	Flaking	25	0.08	Negative	None	0	Negative	No	No	no	no	
1	BS	002B	Boiler Room Storage Room on exterior wall	no	W3	Concrete	White	Flaking	10	0	Negative	None	0	Negative	No	No	no	no	
1	BS	002B	Boiler Room Storage Room on exterior wall	no	W3	Concrete	Tan	Flaking	6	0.08	Negative	None	0	Negative	No	No	no	no	
1	BS	002B	Boiler Room Storage Room on exterior wall	no	W4	Concrete	White	Flaking	15	0	Negative	None	0	Negative	No	No	no	no	
1	BS	002B	Boiler Room Storage Room on exterior wall	no	W4	Concrete	Tan	Flaking	20	0.08	Negative	None	0	Negative	No	No	no	no	
1	BS	002B	Boiler Room Storage Room on exterior wall	no	Ceiling	Concrete	White	None	0	N/A	N/A	None	0	Negative	No	No	no	no	
1	BS	002B	Boiler Room Storage Room on exterior wall	no	Floor	Concrete	N/A	None	0	N/A	N/A	None	0	Negative	No	No	no	no	
1	BS	001B	Boiler Room Storage Room next to Mezzanine	no	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	
1	BS	001B	Boiler Room Storage Room next to Mezzanine	no	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	
1	BS	001B	Boiler Room Storage Room next to Mezzanine	no	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	
1	BS	001B	Boiler Room Storage Room next to Mezzanine	no	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	

				School District of Philadelphia																	
			Name of Inspector: Jen Drialo		Lead Safe Certification Assessment Report								Inspection Dates: 9/20/21-10/7/21								
			Inspection Company: Synertech, Inc.		Gideon ES School								ULCS# 4530								
E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate	Color	Damage	Damage amount (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes		
1	BS	001B	Boiler Room Storage Room next to Mezzanine	no	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access			
1	BS	001B	Boiler Room Storage Room next to Mezzanine	no	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access			
1	C	CS1	Crawlspace in Basement next to Former Building Engineer's Office/Near Stairwell C	no	W1	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	no			
1	C	CS1	Crawlspace in Basement next to Former Building Engineer's Office/Near Stairwell C	no	W2	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	no			
1	C	CS1	Crawlspace in Basement next to Former Building Engineer's Office/Near Stairwell C	no	W3	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	no			
1	C	CS1	Crawlspace in Basement next to Former Building Engineer's Office/Near Stairwell C	no	W4	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	no			
1	C	CS1	Crawlspace in Basement next to Former Building Engineer's Office/Near Stairwell C	no	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	no			
1	C	CS1	Crawlspace in Basement next to Former Building Engineer's Office/Near Stairwell C	no	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	no			
1	C	CS2	Additional Crawlspace near Stairwell C	no	W1	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	no			
1	C	CS2	Additional Crawlspace near Stairwell C	no	W2	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	no			
1	C	CS2	Additional Crawlspace near Stairwell C	no	W3	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	no			
1	C	CS2	Additional Crawlspace near Stairwell C	no	W4	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	no			
1	C	CS2	Additional Crawlspace near Stairwell C	no	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	no			
1	C	CS2	Additional Crawlspace near Stairwell C	no	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	no			
1	A	AT	Attic	no	W1	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	no			
1	A	AT	Attic	no	W2	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	no			
1	A	AT	Attic	no	W3	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	no			
1	A	AT	Attic	no	W4	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	no			
1	A	AT	Attic	no	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	no			
1	A	AT	Attic	no	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	no			
1	1	104D	Classroom 104 Small Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	no			