

					School District of Philadelphia																		
					Name of Inspectors: Shalaunda Gourdine, Suzanne Shourds, James Arbuckle, Ted Mosher										Inspection Dates: 4/5/2021-4/28/2021								
					Lead Safe Certification Assessment Report										Inspection Company: REPSG, Inc				James Blaine Elementary School				
															ULCS# 4220								
E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	Lead Concentration (% wt)	Lead in Paint Chips by Flame AAS Analysis Results (positive / negative)	XRF Reading (mg/cm2)	XRF (positive/ negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes		
1	3	S32	Stairwell #3	Yes	W1	Concrete	Tan	None	0	N/A	N/A	N/A	N/A	None									
1	3	S32	Stairwell #3	Yes	W2	Concrete	Tan	None	0	N/A	N/A	N/A	N/A	None									
1	3	S32	Stairwell #3	Yes	W3	Concrete	Tan	None	0	N/A	N/A	N/A	N/A	None									
1	3	S32	Stairwell #3	Yes	W4	Concrete	Tan	None	0	N/A	N/A	N/A	N/A	None									
1	3	S32	Stairwell #3	Yes	Ceiling	Concrete	Tan	None	0	N/A	N/A	N/A	N/A	None									
1	3	S32	Stairwell #3	Yes	Floor	N/A	N/A	None	0	N/A	N/A	N/A	N/A	None									
1	3	301	Classroom 301	Yes	W1	Concrete	Beige	Chipping	6	See Note	Negative	N/A	N/A								Same Wall System as Testedd Wall (Negative)		
1	3	301	Classroom 301	Yes	W2	Concrete	Beige	Chipping	6	0.008	Negative	N/A	N/A								Same Wall System as Testedd Wall (Negative)		
1	3	301	Classroom 301	Yes	W3	Concrete	Beige	Chipping	6	See Note	Negative	N/A	N/A								Same Wall System as Testedd Wall (Negative)		
1	3	301	Classroom 301	Yes	W4	Concrete	Beige	Chipping	6	See Note	Negative	N/A	N/A								Same Wall System as Testedd Wall (Negative)		
1	3	301	Classroom 301	Yes	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A										
1	3	301	Classroom 301	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A										
1	3	301A	Classroom 301 Closet A	Yes	W1	Concrete	Tan	Chipping	2	See Note	Negative	N/A	N/A								Same Wall System as Testedd Wall (Negative)		
1	3	301A	Classroom 301 Closet A	Yes	W2	Concrete	Tan	Chipping	2	See Note	Negative	N/A	N/A								Same Wall System as Testedd Wall (Negative)		
1	3	301A	Classroom 301 Closet A	Yes	W3	Concrete	Tan	Chipping	2	0.008	Negative	N/A	N/A								Same Wall System as Testedd Wall (Negative)		
1	3	301A	Classroom 301 Closet A	Yes	W4	Concrete	Tan	Chipping	2	See Note	Negative	N/A	N/A								Same Wall System as Testedd Wall (Negative)		
1	3	301A	Classroom 301 Closet A	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access			
1	3	301A	Classroom 301 Closet A	Yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access			
1	3	303	Classroom 303	Yes	W1	Concrete	Beige	Chipping	2	0.011	Negative	N/A	N/A										
1	3	303	Classroom 303	Yes	W2	Concrete	Beige	None	0	N/A	Negative	N/A	N/A								Same Wall System as Testedd Wall (Negative)		
1	3	303	Classroom 303	Yes	W3	Concrete	Beige	Chipping	4	See Note	Negative	N/A	N/A								Same Wall System as Testedd Wall (Negative)		
1	3	303	Classroom 303	Yes	W4	Concrete	Beige	None	0	N/A	Negative	N/A	N/A								Same Wall System as Testedd Wall (Negative)		
1	3	303	Classroom 303	Yes	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A										
1	3	303	Classroom 303	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A										
1	3	303A	Classroom 303 Closet A (front)	Yes	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access			
1	3	303A	Classroom 303 Closet A (front)	Yes	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access			
1	3	303A	Classroom 303 Closet A (front)	Yes	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access			
1	3	303A	Classroom 303 Closet A (front)	Yes	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access			
1	3	303A	Classroom 303 Closet A (front)	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access			
1	3	303A	Classroom 303 Closet A (front)	Yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access			
1	3	303A	Classroom 303 Closet B (rear)	Yes	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access			
1	3	303A	Classroom 303 Closet B (rear)	Yes	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access			
1	3	303A	Classroom 303 Closet B (rear)	Yes	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access			
1	3	303A	Classroom 303 Closet B (rear)	Yes	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access			
1	3	303A	Classroom 303 Closet B (rear)	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access			
1	3	303A	Classroom 303 Closet B (rear)	Yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access			
1	3	306	Classroom 306	Yes	W1	Concrete	Green	Chipping	6	0.011	Negative	N/A	N/A										
1	3	306	Classroom 306	Yes	W2	Concrete	Green	Chipping	6	See Note	Negative	N/A	N/A								Same Wall System as Testedd Wall (Negative)		
1	3	306	Classroom 306	Yes	W3	Concrete	Green	Chipping	6	See Note	Negative	N/A	N/A								Same Wall System as Testedd Wall (Negative)		
1	3	306	Classroom 306	Yes	W4	Wood	Green	Chipping	6	See Note	Negative	N/A	N/A								Same Wall System as Testedd Wall (Negative)		
1	3	306	Classroom 306	Yes	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A										
1	3	306	Classroom 306	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A										
1	3	306A	Classroom 306 Closet A	Yes	W1	Concrete	Green	Chipping	2	See Note	Negative	N/A	N/A								Same Wall System as Testedd Wall (Negative)		
1	3	306A	Classroom 306 Closet A	Yes	W2	Concrete	Green	Chipping	2	See Note	Negative	N/A	N/A								Same Wall System as Testedd Wall (Negative)		
1	3	306A	Classroom 306 Closet A	Yes	W3	Concrete	Green	Chipping	2	0.014	Negative	N/A	N/A								Same Wall System as Testedd Wall (Negative)		
1	3	306A	Classroom 306 Closet A	Yes	W4	Concrete	Green	Chipping	2	See Note	Negative	N/A	N/A								Same Wall System as Testedd Wall (Negative)		
1	3	306A	Classroom 306 Closet A	Yes	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A										
1	3	306A	Classroom 306 Closet A	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A										
1	3	306B	Classroom 306 Closet B	Yes	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access			
1	3	306B	Classroom 306 Closet B	Yes	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access			
1	3	306B	Classroom 306 Closet B	Yes	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access			
1	3	306B	Classroom 306 Closet B	Yes	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access			
1	3	306B	Classroom 306 Closet B	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access			
1	3	306B	Classroom 306 Closet B	Yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access			
1	3	307	Classroom 307	Yes	W1	Concrete	Beige	None	0	N/A	N/A	N/A	N/A								Same Wall Systems as Tested Walls		
1	3	307	Classroom 307	Yes	W2	Concrete	Beige	None	0	N/A	N/A	N/A	N/A								Same Wall Systems as Tested Walls		
1	3	307	Classroom 307	Yes	W3	Base Brick	Dark Gray	None	0	0.008	Negative	N/A	N/A								Same Wall System as Testedd Wall (Negative)		
1	3	307	Classroom 307	Yes	W4	Concrete	White	None	0	0.008	Negative	N/A	N/A								Same Wall System as Testedd Wall (Negative)		
1	3	307	Classroom 307	Yes	W4	Concrete	Light Green	None	0	0.008	Negative	N/A	N/A								Same Wall System as Testedd Wall (Negative)		
1	3	307	Classroom 307	Yes	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A										
1	3	307	Classroom 307	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A										
1	3	307A	Classroom 307 Closet A (front)	Yes	W1	No Access	No Access	No Access															

			Name of Inspectors: Shalaunda Gourdine, Suzanne Shourds, James Arbuckle, Ted Mosher		Lead Safe Certification Assessment Report										Inspection Dates: 4/5/2021-4/28/2021								
			Inspection Company: REPSG, Inc		James Blaine Elementary School										ULCS# 4220								
E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	Lead Concentration (% wt)	Lead in Paint Chips by Flame AAS Analysis Results (positive / negative)	XRF Reading (mg/cm2)	XRF (positive/ negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes		
1	3	307B	Classroom 307 Closet B (rear)	Yes	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access			
1	3	307B	Classroom 307 Closet B (rear)	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access			
1	3	307B	Classroom 307 Closet B (rear)	Yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access			
1	3	S33	Stairwell #2	Yes	W1	Concrete	Tan	None	0	N/A	N/A	N/A	N/A										
1	3	S33	Stairwell #2	Yes	W2	Concrete	Tan	None	0	N/A	N/A	N/A	N/A										
1	3	S33	Stairwell #2	Yes	W3	Concrete	Tan	None	0	N/A	N/A	N/A	N/A										
1	3	S33	Stairwell #2	Yes	W4	Concrete	Tan	None	0	N/A	N/A	N/A	N/A										
1	3	S33	Stairwell #2	Yes	Ceiling	Concrete	Tan	None	0	N/A	N/A	N/A	N/A										
1	3	S33	Stairwell #2	Yes	Floor																		
1	3	307B	Boy's Restroom	Yes	W1	Concrete	Beige	Chipping	6	See Note	Negative	N/A	N/A								Same Wall System as Tested Wall (Negative)		
1	3	307B	Boy's Restroom	Yes	W2	Concrete	Beige	Chipping	6	0.008	Negative	N/A	N/A										
1	3	307B	Boy's Restroom	Yes	W3	Base Brick	Dark Gray	Chipping	6	0.008	Negative	N/A	N/A										
1	3	307B	Boy's Restroom	Yes	W4	Concrete	Green	Chipping	6	0.008	Negative	N/A	N/A			Negative							
1	3	307B	Boy's Restroom	Yes	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A										
1	3	307B	Boy's Restroom	Yes	Floor																		
1	3	308B	Girl's Restroom	Yes	W1	Concrete		None	0	N/A	N/A	N/A	N/A										
1	3	308B	Girl's Restroom	Yes	W2	Concrete		None	0	N/A	N/A	N/A	N/A										
1	3	308B	Girl's Restroom	Yes	W3	Concrete		None	0	N/A	N/A	N/A	N/A										
1	3	308B	Girl's Restroom	Yes	W4	Concrete		None	0	N/A	N/A	N/A	N/A										
1	3	308B	Girl's Restroom	Yes	Ceiling	Concrete		None	0	N/A	N/A	N/A	N/A										
1	3	308B	Girl's Restroom	Yes	Floor																		
1	3	S31	Stairwell #1	Yes	W1	Concrete	Tan	None	0	N/A	N/A	N/A	N/A										
1	3	S31	Stairwell #1	Yes	W2	Concrete	Tan	None	0	N/A	N/A	N/A	N/A										
1	3	S31	Stairwell #1	Yes	W3	Concrete	Tan	None	0	N/A	N/A	N/A	N/A										
1	3	S31	Stairwell #1	Yes	W4	Concrete	Tan	None	0	N/A	N/A	N/A	N/A										
1	3	S31	Stairwell #1	Yes	Ceiling	Concrete	Tan	None	0	N/A	N/A	N/A	N/A										
1	3	S31	Stairwell #1	Yes	Floor																		
1	3	315	Classroom 315	Yes	W1	Concrete	Beige	None	0	See Note	Negative	N/A	N/A								Same Wall System as Tested Wall (Negative)		
1	3	315	Classroom 315	Yes	W2	Concrete	Beige	None	0	See Note	Negative	N/A	N/A								Same Wall System as Tested Wall (Negative)		
1	3	315	Classroom 315	Yes	W3	Concrete	Beige	None	0	See Note	Negative	N/A	N/A								Same Wall System as Tested Wall (Negative)		
1	3	315	Classroom 315	Yes	W4	Concrete	Beige	None	0	0.008	Negative	N/A	N/A										
1	3	315	Classroom 315	Yes	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A										
1	3	315	Classroom 315	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A										
1	3	315A	Classroom 315 Closet A	Yes	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access			
1	3	315A	Classroom 315 Closet A	Yes	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access			
1	3	315A	Classroom 315 Closet A	Yes	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access			
1	3	315A	Classroom 315 Closet A	Yes	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access			
1	3	315A	Classroom 315 Closet A	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access			
1	3	315A	Classroom 315 Closet A	Yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access			
1	3	315B	Classroom 315 Closet B	Yes	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access			
1	3	315B	Classroom 315 Closet B	Yes	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access			
1	3	315B	Classroom 315 Closet B	Yes	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access			
1	3	315B	Classroom 315 Closet B	Yes	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access			
1	3	315B	Classroom 315 Closet B	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access			
1	3	315B	Classroom 315 Closet B	Yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access			
1	3	H38	Hallway from Classrooms 310 to 316	Yes	W1	Concrete	Beige	None	0	0.011	Negative	N/A	N/A				No Access	No Access	No Access	No Access			
1	3	H38	Hallway from Classrooms 310 to 316	Yes	W2	Concrete	Beige	None	0	See Note	Negative	N/A	N/A								Same Wall System as Tested Wall (Negative)		
1	3	H38	Hallway from Classrooms 310 to 316	Yes	W3	Concrete	Beige	None	0	See Note	Negative	N/A	N/A								Same Wall System as Tested Wall (Negative)		
1	3	H38	Hallway from Classrooms 310 to 316	Yes	W4	Concrete	Beige	None	0	See Note	Negative	N/A	N/A								Same Wall System as Tested Wall (Negative)		
1	3	H38	Hallway from Classrooms 310 to 316	Yes	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A										
1	3	H38	Hallway from Classrooms 310 to 316	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A										
1	3	H38	Hallway from Classrooms 310 to 316	Yes	Pilar	Concrete	Red	None	0	0.008	Negative	N/A	N/A										
1	3	H39	Hallway from Classrooms 300 to 309	Yes	W1	Concrete	Beige	None	0	See Note	Negative	N/A	N/A								Same Wall System as Tested Wall (Negative)		
1	3	H39	Hallway from Classrooms 300 to 309	Yes	W2	Concrete	Beige	None	0	See Note	Negative	N/A	N/A								Same Wall System as Tested Wall (Negative)		
1	3	H39	Hallway from Classrooms 300 to 309	Yes	W3	Concrete	Beige	None	0	See Note	Negative	N/A	N/A								Same Wall System as Tested Wall (Negative)		
1	3	H39	Hallway from Classrooms 300 to 309	Yes	W4	Concrete	Beige	None	0	0.008	Negative	N/A	N/A										
1	3	H39	Hallway from Classrooms 300 to 309	Yes	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A										
1	3	H39	Hallway from Classrooms 300 to 309	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A										
1	3	H39	Hallway from Classrooms 300 to 309	Yes	Pilar	Concrete	Red	None	0	0.008	Negative	N/A	N/A										
1	3	302	Classroom 302	Yes	W1	Concrete	Beige	Chipping	4	See Note	Negative	N/A	N/A								Same Wall System as Tested Wall (Negative)		
1	3	302	Classroom 302	Yes	W2	Concrete	Beige	Chipping	4	See Note	Negative	N/A	N/A								Same Wall System as Tested Wall (Negative)		
1	3	302	Classroom 302	Yes	W3	Concrete	Beige	Chipping	4	See Note	Negative	N/A	N/A								Same Wall System as Tested Wall (Negative)		
1	3	302	Classroom 302	Yes	W4	Concrete	Beige	Chipping	4	0.014	Negative	N/A	N/A										
1	3	302	Classroom 302	Yes	Ceiling	Concrete	White	Chipping	4														
1	3	302	Classroom 302	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A										
1	3	302A	Classroom 302 Closet A (front)	Yes	W1	Concrete	Yellow	Chipping	2														
1	3	302A	Classroom 302 Closet A (front)	Yes	W2	Concrete	Yellow	Chipping	2														
1	3	302A	Classroom 302 Closet A (front)	Yes	W3	Concrete	Yellow	Chipping	2														
1	3	302A	Classroom 302 Closet A (front)	Yes	W4	Concrete	Yellow	Chipping	2														

					School District of Philadelphia																	
					Name of Inspectors: Shalaunda Gourdine, Suzanne Shourds, James Arbuckle, Ted Mosher										Inspection Dates: 4/5/2021-4/28/2021							
					Lead Safe Certification Assessment Report																	
					James Blaine Elementary School										ULCS# 4220							
E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	Lead Concentration (% wt)	Lead in Paint Chips by Flame AAS Analysis Results (positive / negative)	XRF Reading (mg/cm2)	XRF (positive/ negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes	
1	3	304A	Classroom 304 Closet A	Yes	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access		
1	3	304A	Classroom 304 Closet A	Yes	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access		
1	3	304A	Classroom 304 Closet A	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access		
1	3	304A	Classroom 304 Closet A	Yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access		
1	3	304B	Classroom 304 Closet B	Yes	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access		
1	3	304B	Classroom 304 Closet B	Yes	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access		
1	3	304B	Classroom 304 Closet B	Yes	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access		
1	3	304B	Classroom 304 Closet B	Yes	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access		
1	3	304B	Classroom 304 Closet B	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access		
1	3	304B	Classroom 304 Closet B	Yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access		
1	3	300	Classroom 300	Yes	W1	Concrete	Beige	Chipping	4	See Note	Negative	N/A	N/A								Same Wall System as Testedd Wall (Negative)	
1	3	300	Classroom 300	Yes	W2	Concrete	Beige	Chipping	4	See Note	Negative	N/A	N/A								Same Wall System as Testedd Wall (Negative)	
1	3	300	Classroom 300	Yes	W3	Concrete	Beige	Chipping	4	0.016	Negative	N/A	N/A									
1	3	300	Classroom 300	Yes	W4	Concrete	Beige	Chipping	4	See Note	Negative	N/A	N/A								Same Wall System as Testedd Wall (Negative)	
1	3	300	Classroom 300	Yes	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A									
1	3	300	Classroom 300	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A									
1	3	300C	Classroom 300 Pipe Chase	Yes	W1	Concrete	Beige		4	See Note	Negative	N/A	N/A								Same Wall System as Testedd Wall (Negative)	
1	3	300	Classroom 300 Pipe Chase	Yes	W2	Concrete	Beige	Chipping	4	See Note	Negative	N/A	N/A								Same Wall System as Testedd Wall (Negative)	
1	3	300	Classroom 300 Pipe Chase	Yes	W3	Concrete	Beige	Chipping	4	See Note	Negative	N/A	N/A								Same Wall System as Testedd Wall (Negative)	
1	3	300	Classroom 300 Pipe Chase	Yes	W4	Concrete	Beige	Chipping	4	0.0093	Negative	N/A	N/A									
1	3	300	Classroom 300 Pipe Chase	Yes	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A									
1	3	300	Classroom 300 Pipe Chase	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A									
1	3	300A	Classroom 300 Closet A (front)	Yes	W1	Concrete	Beige	Chipping	2													
1	3	300A	Classroom 300 Closet A (front)	Yes	W2	Concrete	Beige	Chipping	2													
1	3	300A	Classroom 300 Closet A (front)	Yes	W3	Concrete	Beige	Chipping	2													
1	3	300A	Classroom 300 Closet A (front)	Yes	W4	Concrete	Beige	Chipping	2													
1	3	300A	Classroom 300 Closet A (front)	Yes	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A									
1	3	300A	Classroom 300 Closet A (front)	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A									
1	3	300A	Classroom 300 Closet A	Yes	W1	Concrete	Beige	Chipping	2													
1	3	300A	Classroom 300 Closet A	Yes	W2	Concrete	Beige	Chipping	2													
1	3	300A	Classroom 300 Closet A	Yes	W3	Concrete	Beige	Chipping	2													
1	3	300A	Classroom 300 Closet A	Yes	W4	Concrete	Beige	Chipping	2													
1	3	300A	Classroom 300 Closet A	Yes	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A									
1	3	300A	Classroom 300 Closet A	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A									
1	3	300B	Classroom 300 Closet B (rear)	Yes	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access									
1	3	300B	Classroom 300 Closet B (rear)	Yes	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access									
1	3	300B	Classroom 300 Closet B (rear)	Yes	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access									
1	3	300B	Classroom 300 Closet B (rear)	Yes	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access									
1	3	300B	Classroom 300 Closet B (rear)	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access									
1	3	300B	Classroom 300 Closet B (rear)	Yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access									
1	3	307A	Men's Restroom	Yes	W1	Concrete		None	0	See Note	Negative	N/A	N/A								Same Wall System as Testedd Wall (Negative)	
1	3	307A	Men's Restroom	Yes	W2	Concrete		None	0	See Note	Negative	N/A	N/A								Same Wall System as Testedd Wall (Negative)	
1	3	307A	Men's Restroom	Yes	W3	Concrete	Beige	None	0	0.0082	Negative	N/A	N/A									
1	3	307A	Men's Restroom	Yes	W4	Concrete		None	0	See Note	Negative	N/A	N/A								Same Wall System as Testedd Wall (Negative)	
1	3	307A	Men's Restroom	Yes	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A									
1	3	307A	Men's Restroom	Yes	Floor	Concrete	Gray	Friction	6	See Note	Negative	N/A	N/A								Same Floor Type/Paint as Other Restrooms that tested negative via XRF	
1	3	308A	Women's Restroom	Yes	W1	Concrete	Beige	None	0	See Note	Negative	N/A	N/A								Same Wall System as Testedd Wall	
1	3	308A	Women's Restroom	Yes	W2	Concrete	Beige	None	0	See Note	Negative	N/A	N/A								Same Wall System as Testedd Wall	
1	3	308A	Women's Restroom	Yes	W3	Concrete	Beige	None	0	0.0089	Negative	N/A	N/A									
1	3	308A	Women's Restroom	Yes	W4	Concrete	Beige	None	0	See Note	Negative	N/A	N/A								Same Wall System as Testedd Wall	
1	3	308A	Women's Restroom	Yes	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A									
1	3	308A	Women's Restroom	Yes	Floor	Concrete	Gray	Friction	6	See Note	Negative	N/A	N/A								Same Floor Type/Paint as Other Restrooms that tested negative via XRF	
1	3	310	Classroom 310	Yes	W1	Concrete	Beige	Chipping	4	See Note	Negative	N/A	N/A								Same Wall System as Testedd Wall (Negative)	
1	3	310	Classroom 310	Yes	W2	Concrete	Beige	Chipping	4	See Note	Negative	N/A	N/A								Same Wall System as Testedd Wall (Negative)	
1	3	310	Classroom 310	Yes	W3	Concrete	Beige	Chipping	4	0.026	Negative	N/A	N/A									
1	3	310	Classroom 310	Yes	W4	Concrete	Beige	Chipping	4	See Note	Negative	N/A	N/A								Same Wall System as Testedd Wall (Negative)	
1	3	310	Classroom 310	Yes	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A									
1	3	310	Classroom 310	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A									
1	3	310A	Classroom 310 Closet A	Yes	W1	Concrete	Beige	Chipping	2													
1	3	310A	Classroom 310 Closet A	Yes	W2	Concrete	Beige	Chipping	2													
1	3	310A	Classroom 310 Closet A	Yes	W3	Concrete	Beige	Chipping	2													
1	3	310A	Classroom 310 Closet A	Yes	W4	Concrete	Beige	Chipping	2													
1	3	310A	Classroom 310 Closet A	Yes	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A									
1	3	310A	Classroom 310 Closet A	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A									
1	3	310B	Classroom 310 Closet B	Yes	W1	Concrete	Tan	Chipping	2	See Note	Negative	N/A	N/A								Same Wall System as Testedd Wall (Negative)	
1	3	310B	Classroom 310 Closet B	Yes	W2	Concrete	Tan	Chipping	2	0.024	Negative	N/A	N/A									
1	3	310B	Classroom 310 Closet B	Yes	W3	Concrete	Tan	Chipping	2	See Note	Negative	N/A	N/A								Same Wall System as Testedd Wall (Negative)	
1	3	310B	Classroom 310 Closet B	Yes	W4	Concrete	Tan	Chipping	2	See Note	Negative	N/A	N/A								Same Wall System as Testedd Wall (Negative)	
1	3	310B	Classroom 310 Closet B	Yes	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A					</				

			Name of Inspectors: Shalaunda Gourdine, Suzanne Shourds, James Arbuckle, Ted Mosher		Lead Safe Certification Assessment Report										Inspection Dates: 4/5/2021-4/28/2021						
			Inspection Company: REPSG, Inc		James Blaine Elementary School										ULCS# 4220						
E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	Lead Concentration (% wt)	Lead in Paint Chips by Flame AAS Analysis Results (positive / negative)	XRF Reading (mg/cm2)	XRF (positive/ negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes
1	3	316	Classroom 316	Yes	W1	Concrete	Beige	None	0	See Note	Negative	N/A	N/A								Same Wall System as Tested Wall (Negative)
1	3	316	Classroom 316	Yes	W2	Concrete	Beige	None	0	0.008	Negative	N/A	N/A								
1	3	316	Classroom 316	Yes	W3	Concrete	Beige	None	0	See Note	Negative	N/A	N/A								Same Wall System as Tested Wall (Negative)
1	3	316	Classroom 316	Yes	W4	Concrete	Beige	None	0	See Note	Negative	N/A	N/A								Same Wall System as Tested Wall (Negative)
1	3	316	Classroom 316	Yes	Ceiling	Concrete	White	Chipping	6	0.008	Negative	N/A	N/A								
1	3	316	Classroom 316	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A								
1	3	316A	Classroom 316 Closet A	Yes	W1	Concrete	Tan	Chipping	2	See Note	Negative	N/A	N/A								Same Wall System as Tested Wall (Negative)
1	3	316A	Classroom 316 Closet A	Yes	W2	Concrete	Tan	Chipping	2	0.015	Negative	N/A	N/A								
1	3	316A	Classroom 316 Closet A	Yes	W3	Concrete	Tan	Chipping	2	See Note	Negative	N/A	N/A								Same Wall System as Tested Wall (Negative)
1	3	316A	Classroom 316 Closet A	Yes	W4	Concrete	Tan	Chipping	2	See Note	Negative	N/A	N/A								Same Wall System as Tested Wall (Negative)
1	3	316A	Classroom 316 Closet A	Yes	Ceiling	Concrete	Beige	Chipping	2												
1	3	316A	Classroom 316 Closet A	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A								
1	3	316B	Classroom 316 Closet B	Yes	W1	Concrete	Beige	Chipping	2												
1	3	316B	Classroom 316 Closet B	Yes	W2	Concrete	Beige	Chipping	2												
1	3	316B	Classroom 316 Closet B	Yes	W3	Concrete	Beige	Chipping	2												
1	3	316B	Classroom 316 Closet B	Yes	W4	Concrete	Beige	Chipping	2												
1	3	316B	Classroom 316 Closet B	Yes	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A								
1	3	316B	Classroom 316 Closet B	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A								
1	3	313	Classroom 313	Yes	W1	Concrete	Beige	None	0	See Note	Negative	N/A	N/A								Same Wall System as Tested Wall (Negative)
1	3	313	Classroom 313	Yes	W2	Concrete	Beige	None	0	See Note	Negative	N/A	N/A								Same Wall System as Tested Wall (Negative)
1	3	313	Classroom 313	Yes	W3	Concrete	Beige	None	0	0.014	Negative	N/A	N/A								
1	3	313	Classroom 313	Yes	W4	Concrete	Beige	None	0	See Note	Negative	N/A	N/A								Same Wall System as Tested Wall (Negative)
1	3	313	Classroom 313	Yes	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A								
1	3	313	Classroom 313	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A								
1	3	313A	Classroom 313 Closet A	Yes	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access								
1	3	313A	Classroom 313 Closet A	Yes	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access								
1	3	313A	Classroom 313 Closet A	Yes	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access								
1	3	313A	Classroom 313 Closet A	Yes	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access								
1	3	313A	Classroom 313 Closet A	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access								
1	3	313A	Classroom 313 Closet A	Yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access								
1	3	313B	Classroom 313 Closet B	Yes	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access								
1	3	313B	Classroom 313 Closet B	Yes	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access								
1	3	313B	Classroom 313 Closet B	Yes	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access								
1	3	313B	Classroom 313 Closet B	Yes	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access								
1	3	313B	Classroom 313 Closet B	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access								
1	3	313B	Classroom 313 Closet B	Yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access								
1	3	311	Classroom 311	Yes	W1	Concrete	Beige	Chipping	4	See Note	Negative	N/A	N/A								Same Wall System as Tested Wall (Negative)
1	3	311	Classroom 311	Yes	W2	Concrete	Beige	Chipping	4	See Note	Negative	N/A	N/A								Same Wall System as Tested Wall (Negative)
1	3	311	Classroom 311	Yes	W3	Concrete	Beige	Chipping	4	See Note	Negative	N/A	N/A								Same Wall System as Tested Wall (Negative)
1	3	311	Classroom 311	Yes	W4	Concrete	Beige	Chipping	4	0.008	Negative	N/A	N/A								
1	3	311	Classroom 311	Yes	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A								
1	3	311	Classroom 311	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A								
1	3	311C	Classroom 311 Pipe Closet	Yes	W1	Concrete	Tan	Chipping	2	See Note	Negative	N/A	N/A								Same Wall System as Tested Wall (Negative)
1	3	311C	Classroom 311 Pipe Closet	Yes	W2	Concrete	Tan	Chipping	2	0.015	Negative	N/A	N/A								
1	3	311C	Classroom 311 Pipe Closet	Yes	W3	Concrete	Tan	Chipping	2	See Note	Negative	N/A	N/A								Same Wall System as Tested Wall (Negative)
1	3	311C	Classroom 311 Pipe Closet	Yes	W4	Concrete	Tan	Chipping	2	See Note	Negative	N/A	N/A								Same Wall System as Tested Wall (Negative)
1	3	311C	Classroom 311 Pipe Closet	Yes	Ceiling	Concrete	Yellow	Chipping	2												
1	3	311C	Classroom 311 Pipe Closet	Yes	Floor	N/A	No Access	No Access	N/A	N/A	N/A	N/A	N/A								
1	3	311A	Classroom 311 Closet A	Yes	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access								
1	3	311A	Classroom 311 Closet A	Yes	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access								
1	3	311A	Classroom 311 Closet A	Yes	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access								
1	3	311A	Classroom 311 Closet A	Yes	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access								
1	3	311A	Classroom 311 Closet A	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access								
1	3	311A	Classroom 311 Closet A	Yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access								
1	3	311B	Classroom 311 Closet B	Yes	W1	Concrete	Beige	Chipping	2												
1	3	311B	Classroom 311 Closet B	Yes	W2	Concrete	Beige	Chipping	2												
1	3	311B	Classroom 311 Closet B	Yes	W3	Concrete	Beige	Chipping	2												
1	3	311B	Classroom 311 Closet B	Yes	W4	Concrete	Beige	Chipping	2												
1	3	311B	Classroom 311 Closet B	Yes	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A								
1	3	311B	Classroom 311 Closet B	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A								
1	3	317	Classroom 317	Yes	W1	Concrete	Beige	None	0	N/A	N/A	N/A	N/A								
1	3	317	Classroom 317	Yes	W2	Concrete	Beige	None	0	N/A	N/A	N/A	N/A								
1	3	317	Classroom 317	Yes	W3	Concrete	Beige	None	0	N/A	N/A	N/A	N/A								
1	3	317	Classroom 317	Yes	W4	Concrete	Beige	None	0	N/A	N/A	N/A	N/A								
1	3	317	Classroom 317	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A								Drop Ceiling Tiles
1	3	317	Classroom 317	Yes	Floor																
1	3	317A	Classroom 317 Closet A	Yes	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access								

						School District of Philadelphia															
			Name of Inspectors: Shalaunda Gourdine, Suzanne Shourds, James Arbuckle, Ted Mosher			Lead Safe Certification Assessment Report								Inspection Dates: 4/5/2021-4/28/2021							
			Inspection Company: REPSG, Inc			James Blaine Elementary School								ULCS# 4220							
E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	Lead Concentration (% wt)	Lead in Paint Chips by Flame AAS Analysis Results (positive / negative)	XRF Reading (mg/cm2)	XRF (positive/ negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes
1	3	317B	Classroom 317 Closet B	Yes	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access								
1	3	317B	Classroom 317 Closet B	Yes	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access								
1	3	317B	Classroom 317 Closet B	Yes	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access								
1	3	317B	Classroom 317 Closet B	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access								
1	3	317B	Classroom 317 Closet B	Yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access								
1	3	314	Classroom 314	Yes	W1	Concrete	Beige	None	0	See Note	Negative	N/A	N/A								Same Wall System as Testedd Wall (Negative)
1	3	314	Classroom 314	Yes	W2	Concrete	Beige	None	0	0.008	Negative	N/A	N/A								
1	3	314	Classroom 314	Yes	W3	Concrete	Beige	None	0	See Note	Negative	N/A	N/A								Same Wall System as Testedd Wall (Negative)
1	3	314	Classroom 314	Yes	W4	Concrete	Beige	None	0	See Note	Negative	N/A	N/A								Same Wall System as Testedd Wall (Negative)
1	3	314	Classroom 314	Yes	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A								
1	3	314	Classroom 314	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A								
1	3	314A	Classroom 314 Closet A	Yes	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access								
1	3	314A	Classroom 314 Closet A	Yes	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access								
1	3	314A	Classroom 314 Closet A	Yes	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access								
1	3	314A	Classroom 314 Closet A	Yes	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access								
1	3	314A	Classroom 314 Closet A	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access								
1	3	314A	Classroom 314 Closet A	Yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access								
1	3	314B	Classroom 314 Closet B	Yes	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access								
1	3	314B	Classroom 314 Closet B	Yes	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access								
1	3	314B	Classroom 314 Closet B	Yes	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access								
1	3	314B	Classroom 314 Closet B	Yes	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access								
1	3	314B	Classroom 314 Closet B	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access								
1	3	314B	Classroom 314 Closet B	Yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access								
1	3	312	Classroom 312	Yes	W1	Concrete	Beige	None	0	0.011	Negative	N/A	N/A								
1	3	312	Classroom 312	Yes	W2	Concrete	Beige	None	0	See Note	Negative	N/A	N/A								Same Wall System as Testedd Wall (Negative)
1	3	312	Classroom 312	Yes	W3	Concrete	Beige	None	0	See Note	Negative	N/A	N/A								Same Wall System as Testedd Wall (Negative)
1	3	312	Classroom 312	Yes	W4	Concrete	Beige	None	0	See Note	Negative	N/A	N/A								Same Wall System as Testedd Wall (Negative)
1	3	312	Classroom 312	Yes	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A								
1	3	312	Classroom 312	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A								
1	3	312A	Classroom 312 Closet A (front)	Yes	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access								
1	3	312A	Classroom 312 Closet A (front)	Yes	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access								
1	3	312A	Classroom 312 Closet A (front)	Yes	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access								
1	3	312A	Classroom 312 Closet A (front)	Yes	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access								
1	3	312A	Classroom 312 Closet A (front)	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access								
1	3	312A	Classroom 312 Closet A (front)	Yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access								
1	3	312B	Classroom 312 Closet B (rear)	Yes	W1	Concrete	Beige	Chipping	2												
1	3	312B	Classroom 312 Closet B (rear)	Yes	W2	Concrete	Beige	Chipping	2												
1	3	312B	Classroom 312 Closet B (rear)	Yes	W3	Concrete	Beige	Chipping	2												
1	3	312B	Classroom 312 Closet B (rear)	Yes	W4	Concrete	Beige	Chipping	2												
1	3	312B	Classroom 312 Closet B (rear)	Yes	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A								
1	3	312B	Classroom 312 Closet B (rear)	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A								
1	3	312B	Classroom 312 Closet B	Yes	W1	Concrete	Tan	Chipping	2	See Note	Negative	N/A	N/A								Same Wall System as Testedd Wall (Negative)
1	3	312B	Classroom 312 Closet B	Yes	W2	Concrete	Tan	Chipping	2	See Note	Negative	N/A	N/A								Same Wall System as Testedd Wall (Negative)
1	3	312B	Classroom 312 Closet B	Yes	W3	Concrete	Tan	Chipping	2	0.013	Negative	N/A	N/A								Same Wall System as Testedd Wall (Negative)
1	3	312B	Classroom 312 Closet B	Yes	W4	Concrete	Tan	Chipping	2	See Note	Negative	N/A	N/A								
1	3	312B	Classroom 312 Closet B	Yes	Ceiling	Concrete	Beige	Chipping	2												
1	3	312B	Classroom 312 Closet B	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A								
1	3	311A	Storage Room 311A	Yes	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access								
1	3	311A	Storage Room 311A	Yes	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access								
1	3	311A	Storage Room 311A	Yes	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access								
1	3	311A	Storage Room 311A	Yes	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access								
1	3	311A	Storage Room 311A	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access								
1	3	311A	Storage Room 311A	Yes	Floor																
1	3	309A	Book Storage Room 309A	Yes	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access								
1	3	309A	Book Storage Room 309A	Yes	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access								
1	3	309A	Book Storage Room 309A	Yes	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access								
1	3	309A	Book Storage Room 309A	Yes	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access								
1	3	309A	Book Storage Room 309A	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access								
1	3	309A	Book Storage Room 309A	Yes	Floor																
1	3	311B	Slop Closet 311B	No	W1	Concrete	Tan	Chipping	2												
1	3	311B	Slop Closet 311B	No	W2	Concrete	Tan	Chipping	2												
1	3	311B	Slop Closet 311B	No	W3	Concrete	Tan	Chipping	2												
1	3	311B	Slop Closet 311B	No	W4	Concrete	Tan	Chipping	2												
1	3	311B	Slop Closet 311B	No	Ceiling	Concrete	Beige	Chipping	2												
1	3	311B	Slop Closet 311B	No	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A								
1	2	213	Classroom 213	Yes	W1	Concrete	Beige	Flaking	3	N/A	N/A	See Note	Negative								Same Wall System as Testedd Wall (Negative)
1	2	213	Classroom 213	Yes	W2	Concrete	Beige	Flaking	30	N/A	N/A		0	Negative							
1	2	213	Classroom 213	Yes	W3	Concrete	Beige	Flaking	15	N/A	N/A	See Note	Negative								Same Wall System as Testedd Wall (Negative)
1	2	213	Classroom 213	Yes	W4	Concrete	Beige	Flaking	15	N/A	N/A	See Note	Negative								Same Wall System as Testedd Wall (Negative)
1	2	213	Classroom 213	Yes	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A								
1	2	213	Classroom 213	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A								
1	2	213	Classroom 213	Yes	Ventilation System	Metal	Tan	None	0	N/A	N/A		0.01	Negative							
1	2	213	Classroom 213	Yes	Door Frame	Metal	Tan	None	0	N/A	N/A		0	Negative							
1	2	213	Classroom 213	Yes	Door	Metal	Tan	None	0	N/A	N/A		0	Negative							

			Name of Inspectors: Shalaunda Gourdine, Suzanne Shourds, James Arbuckle, Ted Mosher		Lead Safe Certification Assessment Report										Inspection Dates: 4/5/2021-4/28/2021							
			Inspection Company: REPSG, Inc		James Blaine Elementary School										ULCS# 4220							
E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	Lead Concentration (% wt)	Lead in Paint Chips by Flame AAS Analysis Results (positive / negative)	XRF Reading (mg/cm2)	XRF (positive/ negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes	
1	2	213A	Classroom 213 Closet A	Yes	W1	Concrete	Yellow	Flaking	1	N/A	N/A	See Note	Negative								Same Wall System as Tested Wall (Negative)	
1	2	213A	Classroom 213 Closet A	Yes	W2	Concrete	Yellow	None	0	N/A	N/A		Negative									
1	2	213A	Classroom 213 Closet A	Yes	W3	Concrete	Yellow	None	0	N/A	N/A	N/A	Negative								Same Wall System as Tested Wall	
1	2	213A	Classroom 213 Closet A	Yes	W4	Concrete	Yellow	Flaking	1	N/A	N/A	See Note	Negative								Same Wall System as Tested Wall (Negative)	
1	2	213A	Classroom 213 Closet A	Yes	Ceiling	Concrete	Yellow	None	0	N/A	N/A	N/A	N/A									
1	2	213A	Classroom 213 Closet A	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A									
1	2	213A	Classroom 213 Closet A	Yes	Door Frame	Metal	Tan	Friction	0	N/A	N/A		0 Negative									
1	2	213B	Classroom 213 Closet B	Yes	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access									
1	2	213B	Classroom 213 Closet B	Yes	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access									
1	2	213B	Classroom 213 Closet B	Yes	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access									
1	2	213B	Classroom 213 Closet B	Yes	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access									
1	2	213B	Classroom 213 Closet B	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access									
1	2	213B	Classroom 213 Closet B	Yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access									
1	2	215	Classroom 215	Yes	W1	Concrete	Beige	Flaking	40	N/A	N/A		0 Negative									
1	2	215	Classroom 215	Yes	W2	Concrete	Beige	None	0	N/A	N/A	N/A	Negative								Same Wall System as Tested Wall	
1	2	215	Classroom 215	Yes	W3	Concrete	Beige	Cracking	2	N/A	N/A		0 Negative									
1	2	215	Classroom 215	Yes	W4	Concrete	Beige	Flaking	0	N/A	N/A	N/A	Negative								Same Wall System as Tested Wall	
1	2	215	Classroom 215	Yes	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A									
1	2	215	Classroom 215	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A									
1	2	215	Classroom 215	Yes	Ventilation System	N/A	Tan	Friction	0	N/A	N/A		0 Negative									
1	2	215	Classroom 215	Yes	Door Frame	N/A	Tan	Friction	1	N/A	N/A		0 Negative									
1	2	215	Classroom 215	Yes	Door Jam	N/A	Tan	Friction	1	N/A	N/A		0 Negative									
1	2	215A	Classroom 215 Closet A	Yes	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access									
1	2	215A	Classroom 215 Closet A	Yes	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access									
1	2	215A	Classroom 215 Closet A	Yes	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access									
1	2	215A	Classroom 215 Closet A	Yes	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access									
1	2	215A	Classroom 215 Closet A	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access									
1	2	215A	Classroom 215 Closet A	Yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access									
1	2	215A	Classroom 215 Closet A	Yes	Door Frame	Metal	Tan	Friction	1	N/A	N/A		0 Negative									
1	2	215B	Classroom 215 Closet B	Yes	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access									
1	2	215B	Classroom 215 Closet B	Yes	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access									
1	2	215B	Classroom 215 Closet B	Yes	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access									
1	2	215B	Classroom 215 Closet B	Yes	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access									
1	2	215B	Classroom 215 Closet B	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access									
1	2	215B	Classroom 215 Closet B	Yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access									
1	2	215B	Classroom 215 Closet B	Yes	Door Frame	Metal	Tan	Friction	1	N/A	N/A		0 Negative									
1	2	217	Classroom 217	Yes	W1	Concrete	Beige	Flaking	1	N/A	N/A		0 Negative									
1	2	217	Classroom 217	Yes	W2	Concrete	Beige	Flaking	4	N/A	N/A	See Note	Negative								Same Wall System as Tested Wall (Negative)	
1	2	217	Classroom 217	Yes	W3	Concrete	Beige	Flaking	2	N/A	N/A	See Note	Negative								Same Wall System as Tested Wall (Negative)	
1	2	217	Classroom 217	Yes	W4	Concrete	Beige	Flaking	1	N/A	N/A	See Note	Negative								Same Wall System as Tested Wall (Negative)	
1	2	217	Classroom 217	Yes	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A									
1	2	217	Classroom 217	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A									
1	2	217	Classroom 217	Yes	Ventilation System	N/A	Tan	None	0	N/A	N/A		0 Negative									
1	2	217	Classroom 217	Yes	Door Frame	N/A	Tan	None	0	N/A	N/A		0 Negative									
1	2	217A	Classroom 217 Closet A	Yes	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access									
1	2	217A	Classroom 217 Closet A	Yes	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access									
1	2	217A	Classroom 217 Closet A	Yes	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access									
1	2	217A	Classroom 217 Closet A	Yes	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access									
1	2	217A	Classroom 217 Closet A	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access									
1	2	217A	Classroom 217 Closet A	Yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access									
1	2	217B	Classroom 217 Closet B	Yes	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access									
1	2	217B	Classroom 217 Closet B	Yes	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access									
1	2	217B	Classroom 217 Closet B	Yes	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access									
1	2	217B	Classroom 217 Closet B	Yes	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access									
1	2	217B	Classroom 217 Closet B	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access									
1	2	216	Classroom 216	Yes	W1	Concrete	Beige	Flaking	10	N/A	N/A	See Note	Negative								Same Wall System as Tested Wall (Negative)	
1	2	216	Classroom 216	Yes	W2	Concrete	Beige	Flaking	2	N/A	N/A	See Note	Negative								Same Wall System as Tested Wall (Negative)	
1	2	216	Classroom 216	Yes	W3	Concrete	Beige	Flaking	3	N/A	N/A		0 Negative									
1	2	216	Classroom 216	Yes	W4	Concrete	Beige	None	0	N/A	N/A	N/A	Negative								Same Wall System as Tested Wall	
1	2	216	Classroom 216	Yes	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A									
1	2	216	Classroom 216	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A									
1	2	216	Classroom 216	Yes	Ventilation System	Metal	Tan	Friction	0	N/A	N/A		0.18 Negative									
1	2	216	Classroom 216	Yes	Door Frame	Metal	Tan	None	0	N/A	N/A		0 Negative									
1	2	216A	Classroom 216 Closet A	Yes	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access									
1	2	216A	Classroom 216 Closet A	Yes	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access									
1	2	216A	Classroom 216 Closet A	Yes																		

			Name of Inspectors: Shalaunda Gourdine, Suzanne Shourds, James Arbuckle, Ted Mosher		Lead Safe Certification Assessment Report										Inspection Dates: 4/5/2021-4/28/2021							
			Inspection Company: REPSG, Inc		James Blaine Elementary School										ULCS# 4220							
E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	Lead Concentration (% wt)	Lead in Paint Chips by Flame AAS Analysis Results (positive / negative)	XRF Reading (mg/cm2)	XRF (positive/ negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes	
1	2	216B	Classroom 216 Closet B	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A									
1	2	216B	Classroom 216 Closet B	Yes	Door Frame	Metal	Tan	Friction	1	N/A	N/A	N/A	0 Negative									
1	2	211	Classroom 211	Yes	W1	Concrete	Beige	Flaking	1			See Note	Negative								Same Wall System as Tested Wall (Negative)	
1	2	211	Classroom 211	Yes	W2	Concrete	Beige	None	0	N/A	N/A	N/A	N/A								Same Wall System as Testedd Wall	
1	2	211	Classroom 211	Yes	W3	Concrete	Beige	None	0	N/A	N/A		0 Negative									
1	2	211	Classroom 211	Yes	W4	Concrete	Beige	None	0	N/A	N/A	N/A	N/A								Same Wall System as Testedd Wall	
1	2	211	Classroom 211	Yes	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A									
1	2	211	Classroom 211	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A									
1	2	211	Classroom 211	Yes	Ventilation System	Metal	Tan	None	0	N/A	N/A		0 Negative									
1	2	211	Classroom 211	Yes	Door Frame	Metal	Tan	Friction	1	N/A	N/A		0 Negative									
1	2	211	Classroom 211	Yes	Door	Metal	Tan	Friction	0	N/A	N/A		0.01 Negative									
1	2	211A	Classroom 211 Closet A	Yes	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access									
1	2	211A	Classroom 211 Closet A	Yes	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access									
1	2	211A	Classroom 211 Closet A	Yes	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access									
1	2	211A	Classroom 211 Closet A	Yes	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access									
1	2	211A	Classroom 211 Closet A	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access									
1	2	211A	Classroom 211 Closet A	Yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access									
1	2	214	Classroom 214	Yes	W1	Concrete	Beige	Flaking	10	N/A	N/A	See Note	Negative								Same Wall System as Tested Wall (Negative)	
1	2	214	Classroom 214	Yes	W2	Concrete	Beige	Flaking	5	N/A	N/A	See Note	Negative								Same Wall System as Tested Wall (Negative)	
1	2	214	Classroom 214	Yes	W3	Concrete	Beige	Flaking	10	N/A	N/A	See Note	Negative								Same Wall System as Tested Wall (Negative)	
1	2	214	Classroom 214	Yes	W4	Concrete	Beige	Flaking	8	N/A	N/A		0 Negative									
1	2	214	Classroom 214	Yes	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A									
1	2	214	Classroom 214	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A									
1	2	214	Classroom 214	Yes	Ventilation System	Metal	Tan	None	0	N/A	N/A		0 Negative									
1	2	214A	Classroom 214 Closet A	Yes	W1	Concrete	Yellow	Flaking	10	N/A	N/A		0 Negative									
1	2	214A	Classroom 214 Closet A	Yes	W2	Concrete	Yellow	Flaking	5	N/A	N/A	See Note	Negative								Same Wall System as Tested Wall (Negative)	
1	2	214A	Classroom 214 Closet A	Yes	W3	Concrete	Yellow	Flaking	3	N/A	N/A	See Note	Negative								Same Wall System as Tested Wall (Negative)	
1	2	214A	Classroom 214 Closet A	Yes	W4	Concrete	Yellow	Flaking	6	N/A	N/A	See Note	Negative								Same Wall System as Tested Wall (Negative)	
1	2	214A	Classroom 214 Closet A	Yes	Ceiling	Concrete	Yellow	None	0	N/A	N/A	N/A	N/A									
1	2	214A	Classroom 214 Closet A	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A									
1	2	214A	Classroom 214 Closet A	Yes	Door Frame	Metal	Tan	Chipping	1	N/A	N/A		0 Negative									
1	2	214B	Classroom 214 Closet B	Yes	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access									
1	2	214B	Classroom 214 Closet B	Yes	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access									
1	2	214B	Classroom 214 Closet B	Yes	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access									
1	2	214B	Classroom 214 Closet B	Yes	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access									
1	2	214B	Classroom 214 Closet B	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access									
1	2	214B	Classroom 214 Closet B	Yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access									
1	2	212	Classroom 212	Yes	W1	Concrete	Beige	Flaking	15	N/A	N/A		0.02 Negative									
1	2	212	Classroom 212	Yes	W2	Concrete	Beige	Flaking	2	N/A	N/A	See Note	Negative								Same Wall System as Tested Wall (Negative)	
1	2	212	Classroom 212	Yes	W3	Concrete	Beige	Flaking	4	N/A	N/A	See Note	Negative								Same Wall System as Tested Wall (Negative)	
1	2	212	Classroom 212	Yes	W4	Concrete	Beige	Flaking	1	N/A	N/A	See Note	Negative								Same Wall System as Tested Wall (Negative)	
1	2	212	Classroom 212	Yes	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A									
1	2	212	Classroom 212	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A									
1	2	212	Classroom 212	Yes	Ventilation System	N/A	Tan	Friction	0	N/A	N/A		0.06 Negative									
1	2	212A	Classroom 212 Closet A	Yes	W1																	
1	2	212A	Classroom 212 Closet A	Yes	W2																	
1	2	212A	Classroom 212 Closet A	Yes	W3																	
1	2	212A	Classroom 212 Closet A	Yes	W4																	
1	2	212A	Classroom 212 Closet A	Yes	Ceiling																	
1	2	212A	Classroom 212 Closet A	Yes	Floor																	
1	2	212B	Classroom 212 Closet B	Yes	W1	Concrete	Yellow	Flanking	1	N/A	N/A	See Note	Negative								Same Wall System as Tested Wall (Negative)	
1	2	212B	Classroom 212 Closet B	Yes	W2	Concrete	Yellow	None	0	N/A	N/A	N/A	Negative								Same Wall System as Testedd Wall	
1	2	212B	Classroom 212 Closet B	Yes	W3	Concrete	Yellow	None	0	N/A	N/A	N/A	Negative								Same Wall System as Testedd Wall	
1	2	212B	Classroom 212 Closet B	Yes	W4	Concrete	Yellow	Flanking	1	N/A	N/A		0 Negative									
1	2	212B	Classroom 212 Closet B	Yes	Ceiling	Concrete	Yellow	None	0	N/A	N/A	N/A	N/A									
1	2	212B	Classroom 212 Closet B	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A									
1	2	212B	Classroom 212 Closet B	Yes	Door Frame	Metal	Tan	Friction	1	N/A	N/A		0 Negative									
1	2	209	Classroom 209	Yes	W1	Concrete	Beige	None	0	N/A	N/A		0 Negative									
1	2	209	Classroom 209	Yes	W2	Concrete	Beige	Flaking	1	N/A	N/A	See Note	Negative								Same Wall System as Tested Wall (Negative)	
1	2	209	Classroom 209	Yes	W3	Concrete	Beige	Chipping	1	N/A	N/A	See Note	Negative								Same Wall System as Tested Wall (Negative)	
1	2	209	Classroom 209	Yes	W4	Concrete	Beige	None	0	N/A	N/A	N/A	Negative								Same Wall System as Testedd Wall	
1	2	209	Classroom 209	Yes	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A									
1	2	209	Classroom 209	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A									
1	2	209	Classroom 209	Yes	Venntilation System	Metal	Tan	None	0	N/A	N/A		0.27 Negative									
1	2	209	Classroom 209	Yes	Door	Metal	Tan	None	0	N/A	N/A		0 Negative									
1	2	209A	Classroom 209 Closet A	Yes	W1	Concrete	Tan	None	0	N/A	N/A		0 Negative									
1	2	209A	Classroom 209 Closet A	Yes	W2	Sheetrock	Tan	None	0	N/A	N/A	N/A	N/A								Same Wall System as Testedd Wall	
1	2	209A	Classroom 209 Closet A	Yes	W3	Sheetrock	Tan	None	0	N/A	N/A		0 Negative									
1	2	209A	Classroom 209 Closet A	Yes	W4	Concrete	Tan	None	0	N/A	N/A	N/A	N/A								Same Wall System as Testedd Wall	
1	2	209A	Classroom 209 Closet A</																			

					School District of Philadelphia																	
			Name of Inspectors: Shalaunda Gourdine, Suzanne Shourds, James Arbuckle, Ted Mosher		Lead Safe Certification Assessment Report										Inspection Dates: 4/5/2021-4/28/2021							
			Inspection Company: REPSG, Inc		James Blaine Elementary School										ULCS# 4220							
E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	Lead Concentration (% wt)	Lead in Paint Chips by Flame AAS Analysis Results (positive / negative)	XRF Reading (mg/cm2)	XRF (positive/ negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes	
1	2	209B	Classroom 209 Closet B	Yes	W1	Sheetrock	White	None	0	N/A	N/A		0 Negative									
1	2	209B	Classroom 209 Closet B	Yes	W2	Concrete	Beige	None	0	N/A	N/A	N/A	N/A								Same Wall System as Testedd Wall	
1	2	209B	Classroom 209 Closet B	Yes	W3	Concrete	Beige	None	0	N/A	N/A		0 Negative									
1	2	209B	Classroom 209 Closet B	Yes	W4	Concrete	Beige	None	0	N/A	N/A	N/A	N/A								Same Wall System as Testedd Wall	
1	2	209B	Classroom 209 Closet B	Yes	Ceiling	Concrete	White	None	0	N/A	N/A		0 Negative									
1	2	209B	Classroom 209 Closet B	Yes	Floor	N/A	N/A	None	0	N/A	N/A	N/A	N/A									
1	2	209B	Classroom 209 Closet B	Yes	Door Frame	Metal	Black	None	0	N/A	N/A		0 Negative									
1	2	208	Classroom 208	Yes	W1	Concrete	Beige	Flaking	15	N/A	N/A	See Note	Negative								Same Wall System as Testedd Wall (Negative)	
1	2	208	Classroom 208	Yes	W2	Concrete	Beige	Flaking	3	N/A	N/A	See Note	Negative								Same Wall System as Testedd Wall (Negative)	
1	2	208	Classroom 208	Yes	W3	Concrete	Beige	Flaking	4	N/A	N/A		0 Negative									
1	2	208	Classroom 208	Yes	W4	Concrete	Beige	Flaking	15	N/A	N/A	See Note	Negative								Same Wall System as Testedd Wall (Negative)	
1	2	208	Classroom 208	Yes	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A									
1	2	208	Classroom 208	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A									
1	2	208	Classroom 208	Yes	Ventilation System	Metal	Tan	None	0	N/A	N/A		0.13 Negative									
1	2	208	Classroom 208	Yes	Door Frame	Metal	Tan	Friction	1	N/A	N/A		0 Negative									
1	2	208A	Classroom 208 Closet A	Yes	W1	Concrete	Yellow	Flaking	1	N/A	N/A	See Note	Negative								Same Wall System as Testedd Wall (Negative)	
1	2	208A	Classroom 208 Closet A	Yes	W2	Concrete	Yellow	Flaking	1	N/A	N/A	See Note	Negative								Same Wall System as Testedd Wall (Negative)	
1	2	208A	Classroom 208 Closet A	Yes	W3	Concrete	Yellow	None	0	N/A	N/A		0 Negative									
1	2	208A	Classroom 208 Closet A	Yes	W4	Concrete	Yellow	Flaking	1	N/A	N/A	See Note	Negative								Same Wall System as Testedd Wall (Negative)	
1	2	208A	Classroom 208 Closet A	Yes	Ceiling	Concrete	Yellow	None	0	N/A	N/A	N/A	N/A									
1	2	208A	Classroom 208 Closet A	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A									
1	2	208A	Classroom 208 Closet A	Yes	Door Frame	Metal	Tan	Friction	1	N/A	N/A		0 Negative									
1	2	208B	Classroom 208 Closet B	Yes	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access									
1	2	208B	Classroom 208 Closet B	Yes	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access									
1	2	208B	Classroom 208 Closet B	Yes	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access									
1	2	208B	Classroom 208 Closet B	Yes	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access									
1	2	208B	Classroom 208 Closet B	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access									
1	2	208B	Classroom 208 Closet B	Yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access									
1	2	208C	Girls Restroom	Yes	W1	Concrete	Green & white	None	0	N/A	N/A		0 Negative									
1	2	208C	Girls Restroom	Yes	W2	Concrete	Green & white	None	0	N/A	N/A		Negative								Same Wall System as Testedd Wall	
1	2	208C	Girls Restroom	Yes	W3	Concrete	Green & white	None	0	N/A	N/A		Negative								Same Wall System as Testedd Wall	
1	2	208C	Girls Restroom	Yes	W4	Concrete	Green & white	None	0	N/A	N/A		Negative								Same Wall System as Testedd Wall	
1	2	208C	Girls Restroom	Yes	Ceiling	Concrete	White	None	0	N/A	N/A	N/A										
1	2	208C	Girls Restroom	Yes	Floor	Concrete	Gray	Chipping	10	N/A	N/A		0 Negative									
1	2	208C	Girls Restroom	Yes	Ductwork	Metal	White	None	0	N/A	N/A		0.03 Negative									
1	2	208C	Girls Restroom	Yes	Door Frame	Metal	White	None	0	N/A	N/A		0 Negative									
1	2	208C	Girls Restroom	Yes	Door Frame	Metal	White	None	0	N/A	N/A		0 Negative									
1	2	208C	Girls Restroom	Yes	Kick Plate	Metal	White	None	0	N/A	N/A		1 Positive						no			
1	2	208D	Womens Restroom	Yes	W1	Concrete	Beige	None	0	N/A	N/A		0 Negative									
1	2	208D	Womens Restroom	Yes	W2	Concrete	Beige	None	0	N/A	N/A		Negative								Same Wall System as Testedd Wall	
1	2	208D	Womens Restroom	Yes	W3	Concrete	Beige	None	0	N/A	N/A		Negative								Same Wall System as Testedd Wall	
1	2	208D	Womens Restroom	Yes	W4	Concrete	Beige	None	0	N/A	N/A		Negative								Same Wall System as Testedd Wall	
1	2	208D	Womens Restroom	Yes	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A									
1	2	208D	Womens Restroom	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A									
1	2	208D	Womens Restroom	Yes	Door Frame	Metal	Tan	Friction	0	N/A	N/A		0.01 Negative									
1	2	204	Classroom 204	Yes	W1	Concrete	Beige	Flaking	3	N/A	N/A		0 Negative									
1	2	204	Classroom 204	Yes	W2	Concrete	Beige	None	0	N/A	N/A	N/A	Negative								Same Wall System as Testedd Wall	
1	2	204	Classroom 204	Yes	W3	Concrete	Beige	Flaking	3	N/A	N/A	See Note	Negative								Same Wall System as Testedd Wall (Negative)	
1	2	204	Classroom 204	Yes	W4	Concrete	Beige	Flaking	10	N/A	N/A	See Note	Negative								Same Wall System as Testedd Wall (Negative)	
1	2	204	Classroom 204	Yes	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A									
1	2	204	Classroom 204	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A									
1	2	204	Classroom 204	Yes	Ventilation System	N/A	Tan	None	0	N/A	N/A		0 Negative									
1	2	204	Classroom 204 Closet A	Yes	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access									
1	2	204	Classroom 204 Closet A	Yes	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access									
1	2	204	Classroom 204 Closet A	Yes	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access									
1	2	204	Classroom 204 Closet A	Yes	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access									
1	2	204	Classroom 204 Closet A	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access									
1	2	204	Classroom 204 Closet A	Yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access									
1	2	204B	Classroom 204 Closet B	Yes	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access									
1	2	204B	Classroom 204 Closet B	Yes	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access									
1	2	204B	Classroom 204 Closet B	Yes	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access									
1	2	204B	Classroom 204 Closet B	Yes	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access									
1	2	204B	Classroom 204 Closet B	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access									
1	2	204B	Classroom 204 Closet B	Yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access									
1	2	204B	Classroom 204 Closet B	Yes	Door Frame	Metal	Tan	Friction	1	N/A	N/A		0 Negative									
1	2	206	Classroom 206	Yes	W1	Concrete	Beige	Flaking	6	N/A	N/A		0 Negative							</		

					School District of Philadelphia																	
					Name of Inspectors: Shalaunda Gourdine, Suzanne Shourds, James Arbuckle, Ted Mosher										Inspection Dates: 4/5/2021-4/28/2021							
					Lead Safe Certification Assessment Report																	
					James Blaine Elementary School										ULCS# 4220							
E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	Lead Concentration (% wt)	Lead in Paint Chips by Flame AAS Analysis Results (positive / negative)	XRF Reading (mg/cm2)	XRF (positive/ negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes	
1	2	206A	Classroom 206 Closet A	Yes	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access									
1	2	206A	Classroom 206 Closet A	Yes	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access									
1	2	206A	Classroom 206 Closet A	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access									
1	2	206A	Classroom 206 Closet A	Yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access									
1	2	206B	Classroom 206 Closet B	Yes	W1	Concrete	Yellow	Flaking	50	N/A	N/A	See Note	Negative								Same Wall System as Tested Wall (Negative)	
1	2	206B	Classroom 206 Closet B	Yes	W2	Concrete	Yellow	Flaking	10	N/A	N/A	See Note	Negative								Same Wall System as Tested Wall (Negative)	
1	2	206B	Classroom 206 Closet B	Yes	W3	Concrete	Yellow	Flaking	5	N/A	N/A		0 Negative									
1	2	206B	Classroom 206 Closet B	Yes	W4	Concrete	Yellow	Flaking	10	N/A	N/A	See Note	Negative								Same Wall System as Tested Wall (Negative)	
1	2	206B	Classroom 206 Closet B	Yes	Ceiling	Concrete	Yellow	None	0	N/A	N/A	N/A	N/A									
1	2	206B	Classroom 206 Closet B	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A									
1	2	206B	Classroom 206 Closet B	Yes	Door Frame	Metal	Tan	Friction	1	N/A	N/A		0 Negative									
1	2	206B	Classroom 206 Closet B	Yes	Door	Metal	Tan	Friction	0	N/A	N/A		0 Negative									
1	2	203	Classroom 203	Yes	W1	Concrete	Beige	Flaking	10	N/A	N/A		0 Negative									
1	2	203	Classroom 203	Yes	W2	Concrete	Beige	Flaking	2	N/A	N/A	See Note	Negative								Same Wall System as Tested Wall (Negative)	
1	2	203	Classroom 203	Yes	W3	Concrete	Beige	Flaking	3	N/A	N/A	See Note	Negative								Same Wall System as Tested Wall (Negative)	
1	2	203	Classroom 203	Yes	W4	Concrete	Beige	Flaking	2	N/A	N/A	See Note	Negative								Same Wall System as Tested Wall (Negative)	
1	2	203	Classroom 203	Yes	Ceiling	Concrete	White	None	N/A	N/A	N/A	N/A	N/A									
1	2	203	Classroom 203	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A									
1	2	203	Classroom 203	Yes	Ventilation System	N/A	Tan	None	1	N/A	N/A		0.1 Negative									
1	2	203	Classroom 203	Yes	Door Frame	N/A	Tan	Deterioration	1	N/A	N/A		0 Negative									
1	2	203A	Classroom 203 Closet A	Yes	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access									
1	2	203A	Classroom 203 Closet A	Yes	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access									
1	2	203A	Classroom 203 Closet A	Yes	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access									
1	2	203A	Classroom 203 Closet A	Yes	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access									
1	2	203A	Classroom 203 Closet A	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access									
1	2	203A	Classroom 203 Closet A	Yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access									
1	2	203A	Classroom 203 Closet A	Yes	Door Frame	Metal	Tan	Friction	1	N/A	N/A		0 Negative									
1	2	203B	Classroom 203 Closet B	Yes	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access									
1	2	203B	Classroom 203 Closet B	Yes	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access									
1	2	203B	Classroom 203 Closet B	Yes	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access									
1	2	203B	Classroom 203 Closet B	Yes	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access									
1	2	203B	Classroom 203 Closet B	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access									
1	2	203B	Classroom 203 Closet B	Yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access									
1	2	H26	Hallway from Classrooms 200 to 209	Yes	W1	Concrete	Beige	Flaking	1	N/A	N/A		1 Positive				No		yes		Near Classroom 202	
1	2	H26	Hallway from Classrooms 200 to 209	Yes	W1	Concrete	Red	Flaking	0	N/A	N/A		0 Negative									
1	2	H26	Hallway from Classrooms 200 to 209	Yes	W2	Concrete	Beige	Flaking	0	N/A	N/A	See Note	Positive						no		Same Wall System as Tested Wall (Positive)	
1	2	H26	Hallway from Classrooms 200 to 209	Yes	W3	Concrete	Beige	Flaking	1	N/A	N/A		1 Positive				No		yes		Same Wall System as Tested Wall (Negative)	
1	2	H26	Hallway from Classrooms 200 to 209	Yes	W3	Concrete	Red	Flaking	0	N/A	N/A	See Note	Negative								Near Classrooms 200 and 204	
1	2	H26	Hallway from Classrooms 200 to 209	Yes	W4	Concrete	Beige	Flaking	1	N/A	N/A		1 Positive				No		yes		Near Classroom 200	
1	2	H26	Hallway from Classrooms 200 to 209	Yes	Ceiling	Concrete	Beige	None	0	N/A	N/A		0 Negative									
1	2	H26	Hallway from Classrooms 200 to 209	Yes	Floor	N/A	N/A		N/A	N/A	N/A	N/A	N/A									
1	2	H26	Hallway from Classrooms 200 to 209	Yes	Ventilation System	Metal	Brown	Friction	0	N/A	N/A		0 Negative									
1	2	H26	Hallway from Classrooms 200 to 209	Yes	Door Frame	Metal	Brown	Friction	0	N/A	N/A		0.05 Negative									
1	2	205	Classroom 205	Yes	W1	Concrete	Beige	Flaking	2	N/A	N/A		0 Negative									
1	2	205	Classroom 205	Yes	W2	Concrete	Beige	Flaking	6	N/A	N/A	See Note	Negative								Same Wall System as Tested Wall (Negative)	
1	2	205	Classroom 205	Yes	W3	Concrete	Beige	Flaking	10	N/A	N/A	See Note	Negative								Same Wall System as Tested Wall (Negative)	
1	2	205	Classroom 205	Yes	W4	Concrete	Beige	Flaking	4	N/A	N/A	See Note	Negative								Same Wall System as Tested Wall (Negative)	
1	2	205	Classroom 205	Yes	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A									
1	2	205	Classroom 205	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A									
1	2	205	Classroom 205	Yes	Door Frame	Metal	Tan	Friction	1	N/A	N/A		0 Negative									
1	2	205A	Classroom 205 Closet A	Yes	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access									
1	2	205A	Classroom 205 Closet A	Yes	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access									
1	2	205A	Classroom 205 Closet A	Yes	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access									
1	2	205A	Classroom 205 Closet A	Yes	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access									
1	2	205A	Classroom 205 Closet A	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access									
1	2	205A	Classroom 205 Closet A	Yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access									
1	2	205B	Classroom 205 Closet B	Yes	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access									
1	2	205B	Classroom 205 Closet B	Yes	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access									
1	2	205B	Classroom 205 Closet B	Yes	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access									
1	2	205B	Classroom 205 Closet B	Yes	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access									
1	2	205B	Classroom 205 Closet B	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access									
1	2	205B	Classroom 205 Closet B	Yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access									
1	2	205B	Classroom 205 Closet B	Yes	Ventilation System	Metal	Tan	Friction	0	N/A	N/A		0.1 Negative									
1	2	205B	Classroom 205 Closet B	Yes	Door Frame	Metal	Tan	Friction	0	N/A	N/A		0 Negative									
1	2	207	Classroom 207	Yes	W1	Concrete	Beige	Flaking	10	N/A	N/A		0.02 Negative									
1	2	207	Classroom 207	Yes	W2	Concrete	Beige	Flaking	3	N/A	N/A	See Note	Negative								Same Wall System as Tested Wall (Negative)	
1	2	207	Classroom 207	Yes	W3	Concrete	Beige	Flaking	10	N/A	N/A	See Note	Negative								Same Wall System as Tested Wall (Negative)	
1	2	207	Classroom 207	Yes	W4	Concrete	Beige	Flaking	3	N/A	N/A	See Note	Negative								Same Wall System as Tested Wall (Negative)	
1	2	207	Classroom 207	Yes	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A									
1	2	207																				

			Name of Inspectors: Shalaunda Gourdine, Suzanne Shourds, James Arbuckle, Ted Mosher		Lead Safe Certification Assessment Report										Inspection Dates: 4/5/2021-4/28/2021						
			Inspection Company: REPSG, Inc		James Blaine Elementary School										ULCS# 4220						
E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	Lead Concentration (% wt)	Lead in Paint Chips by Flame AAS Analysis Results (positive / negative)	XRF Reading (mg/cm2)	XRF (positive/ negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes
1	2	207	Classroom 207	Yes	Ventilation System	Metal	Tan	None	0	N/A	N/A	0.07	Negative								
1	2	207	Classroom 207	Yes	Door Frame	Metal	Tan	Friction	0	N/A	N/A	0	Negative								
1	2	207A	Classroom 207 Closet	Yes	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access								
1	2	207A	Classroom 207 Closet	Yes	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access								
1	2	207A	Classroom 207 Closet	Yes	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access								
1	2	207A	Classroom 207 Closet	Yes	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access								
1	2	207A	Classroom 207 Closet	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access								
1	2	207A	Classroom 207 Closet	Yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access								
1	2	207A	Classroom 207 Closet	Yes	Door Frame	Metal	Tan	Friction	0	N/A	N/A	0	Negative								
1	2	207B	Classroom 207 Restroom	Yes	W1	Concrete	Light Green & White	None	0	N/A	N/A	0	Negative								
1	2	207B	Classroom 207 Restroom	Yes	W2	Concrete	Light Green & White	None	0	N/A	N/A	N/A	Negative								Same Wall System as Testedd Wall
1	2	207B	Classroom 207 Restroom	Yes	W3	Concrete	Light Green & White	None	0	N/A	N/A	N/A	Negative								Same Wall System as Testedd Wall
1	2	207B	Classroom 207 Restroom	Yes	W4	Concrete	Light Green & White	Flaking	3	N/A	N/A	See Note	Negative								Same Wall System as Testedd Wall (Negative)
1	2	207B	Classroom 207 Restroom	Yes	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A								
1	2	207B	Classroom 207 Restroom	Yes	Floor	Concrete	Gray	Chipping	40	N/A	N/A	0	Negative								
1	2	207B	Classroom 207 Restroom	Yes	Kick Plate	Ceramic	Gray	Chipping	1	N/A	N/A	1.57	Positive				No	no			Substrate is Ceramic, Similar paint tested negative elsewhere, Assume Positive result due to content in Ceramic tile
1	2	207B	Classroom 207 Restroom	Yes	Duct Work	Metal	White	Flaking	1	N/A	N/A	0.11	Negative				Negative				
1	2	207B	Classroom 207 Restroom	Yes	Door Frame	Metal	Gray	Friction	1	N/A	N/A	0	Negative								
1	2	207B	Classroom 207 Restroom	Yes	Door Frame	Metal	Tan	Friction	1	N/A	N/A	0	Negative								
1	2	207C	Mens Restroom	Yes	W1	Concrete	Beige	None	0	N/A	N/A	N/A	Negative								Same Wall System as Testedd Wall
1	2	207C	Mens Restroom	Yes	W2	Concrete	Beige	None	0	N/A	N/A	N/A	Negative								Same Wall System as Testedd Wall
1	2	207C	Mens Restroom	Yes	W3	Concrete	Beige	None	0	N/A	N/A	0	Negative								
1	2	207C	Mens Restroom	Yes	W4	Concrete	Beige	Flaking	3	N/A	N/A	See Note	Negative								Same Wall System as Testedd Wall (Negative)
1	2	207C	Mens Restroom	Yes	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A								
1	2	207C	Mens Restroom	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A								
1	2	207C	Mens Restroom	Yes	Door Frame	Metal	Tan	None	0	N/A	N/A	0.01	Negative								
1	2	H27	Hallway from Classrooms 210 to 216	Yes	W1	Concrete	Beige	Flaking	0	N/A	N/A	0	Negative								
1	2	H27	Hallway from Classrooms 210 to 216	Yes	W1	Concrete	Red	None	0	N/A	N/A	0	Negative								
1	2	H27	Hallway from Classrooms 210 to 216	Yes	W2	Concrete	Beige	None	0	N/A	N/A	0	Negative								
1	2	H27	Hallway from Classrooms 210 to 216	Yes	W3	Concrete	Beige	Cracking	0	N/A	N/A	0	Negative								
1	2	H27	Hallway from Classrooms 210 to 216	Yes	W3	Concrete	Red	None	0	N/A	N/A	0	Negative								
1	2	H27	Hallway from Classrooms 210 to 216	Yes	W4																
1	2	H27	Hallway from Classrooms 210 to 216	Yes	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A								
1	2	H27	Hallway from Classrooms 210 to 216	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A								
1	2	H27	Hallway from Classrooms 210 to 216	Yes	Elevator Door Frame	Metal	Beige	Friction	0	N/A	N/A	0.03	Negative								
1	2	210	Classroom 210	Yes	W1	Concrete	Beige	Flaking	7	N/A	N/A	0.04	Negative								
1	2	210	Classroom 210	Yes	W2	Concrete	Beige	Flaking	5	N/A	N/A	See Note	Negative								Same Wall System as Testedd Wall (Negative)
1	2	210	Classroom 210	Yes	W3	Concrete	Beige	Flaking	8	N/A	N/A	0	Negative								
1	2	210	Classroom 210	Yes	W4	Concrete	Beige	Flaking	5	N/A	N/A	See Note	Negative								Same Wall System as Testedd Wall (Negative)
1	2	210	Classroom 210	Yes	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A								
1	2	210	Classroom 210	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A								
1	2	210	Classroom 210	Yes	Ventilation System	Metal	Tan	None	0	N/A	N/A	0.36	Negative								
1	2	210	Classroom 210	Yes	Door Frame	Metal	Tan	None	0	N/A	N/A	0	Negative								
1	2	210	Classroom 210 Closet A	Yes	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access								
1	2	210	Classroom 210 Closet A	Yes	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access								
1	2	210	Classroom 210 Closet A	Yes	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access								
1	2	210	Classroom 210 Closet A	Yes	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access								
1	2	210	Classroom 210 Closet A	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access								
1	2	210	Classroom 210 Closet A	Yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access								
1	2	210	Classroom 210 Closet A	Yes	Door Frame	Metal	Tan	None	0	N/A	N/A	0	Negative								
1	2	210	Classroom 210 Closet B	Yes	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access								
1	2	210	Classroom 210 Closet B	Yes	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access								
1	2	210	Classroom 210 Closet B	Yes	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access								
1	2	210	Classroom 210 Closet B	Yes	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access								
1	2	210	Classroom 210 Closet B	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access								
1	2	210	Classroom 210 Closet B	Yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access								
1	2	210A	Storage Room 210	Yes	W1																
1	2	210A	Storage Room 210	Yes	W2																
1	2	210A	Storage Room 210	Yes	W3																
1	2	210A	Storage Room 210	Yes	W4																
1	2	210A	Storage Room 210	Yes	Ceiling																
1	2	210A	Storage Room 210	Yes	Floor																
1	2	202	Classroom 202	Yes	W1	Concrete	Beige	Flaking	10	N/A	N/A	See Note	Negative								Same Wall System as Testedd Wall (Negative)
1	2	202	Classroom 202	Yes	W2	Concrete	Beige	Flaking	1	N/A	N/A	See Note	Negative								Same Wall System as Testedd Wall (Negative)
1	2	202	Classroom 202	Yes	W3	Concrete	Beige	Flaking	3	N/A	N/A	0	Negative								
1	2	202	Classroom 202	Yes	W4	Concrete	Beige	Flaking	3	N/A	N/A	See Note	Negative								Same Wall System as Testedd Wall (Negative)
1	2	202	Classroom 202	Yes	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A								
1	2	202	Classroom 202	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A								
1	2	202	Classroom 202	Yes	Ventilation System	Metal	Tan	Deterioration	1	N/A	N/A	0.08	Negative								
1	2	202	Classroom 202	Yes	Door Frame	Metal	Tan	Deterioration	1	N/A	N/A	0	Negative								
1	2																				

					School District of Philadelphia																	
					Name of Inspectors: Shalaunda Gourdine, Suzanne Shourds, James Arbuckle, Ted Mosher										Inspection Dates: 4/5/2021-4/28/2021							
					Inspection Company: REPSG, Inc										James Blaine Elementary School				ULCS# 4220			
E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	Lead Concentration (% wt)	Lead in Paint Chips by Flame AAS Analysis Results (positive / negative)	XRF Reading (mg/cm2)	XRF (positive/ negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes	
1	2	202	Classroom 202 Closet A	Yes	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access									
1	2	202	Classroom 202 Closet A	Yes	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access									
1	2	202	Classroom 202 Closet A	Yes	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access									
1	2	202	Classroom 202 Closet A	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access									
1	2	202	Classroom 202 Closet A	Yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access									
1	2	202	Classroom 202 Closet B	Yes	W1	Concrete	Beige	Flaking	2	N/A	N/A	See Note	Negative								Same Wall System as Tested Wall (Negative)	
1	2	202	Classroom 202 Closet B	Yes	W2	Concrete	Beige	Flaking	3	N/A	N/A		0 Negative									
1	2	202	Classroom 202 Closet B	Yes	W3	Concrete	Beige	Flaking	2	N/A	N/A	See Note	Negative								Same Wall System as Tested Wall (Negative)	
1	2	202	Classroom 202 Closet B	Yes	W4	Concrete	Beige	Flaking	3	N/A	N/A	See Note	Negative								Same Wall System as Tested Wall (Negative)	
1	2	202	Classroom 202 Closet B	Yes	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A									
1	2	202	Classroom 202 Closet B	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A									
1	2	202	Classroom 202 Closet B	Yes	Door	Metal	Tan	Friction	1	N/A	N/A		0 Negative									
1	2	201	Classroom 201	Yes	W1	Concrete	Beige	Flaking	15	N/A	N/A	See Note	Negative								Same Wall System as Tested Wall (Negative)	
1	2	201	Classroom 201	Yes	W2	Concrete	Beige	Flaking	10	N/A	N/A	See Note	Negative								Same Wall System as Tested Wall (Negative)	
1	2	201	Classroom 201	Yes	W3	Concrete	Beige	Flaking	15	N/A	N/A		0 Negative									
1	2	201	Classroom 201	Yes	W4	Concrete	Beige	None	0	N/A	N/A	N/A	Negative								Same Wall System as Tested Wall	
1	2	201	Classroom 201	Yes	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A									
1	2	201	Classroom 201	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A									
1	2	201	Classroom 201	Yes	Ventilation System	Concrete	Tan	Flaking	1	N/A	N/A		0 Negative									
1	2	201	Classroom 201	Yes	Door Frame	Concrete	Tan	None	0	N/A	N/A		0 Negative									
1	2	201	Classroom 201	Yes	Door Jam	Concrete	Tan	Deterioration	1	N/A	N/A		0 Negative									
1	2	201	Classroom 201 Closet A	Yes	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access									
1	2	201	Classroom 201 Closet A	Yes	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access									
1	2	201	Classroom 201 Closet A	Yes	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access									
1	2	201	Classroom 201 Closet A	Yes	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access									
1	2	201	Classroom 201 Closet A	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access									
1	2	201	Classroom 201 Closet A	Yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access									
1	2	201	Classroom 201 Closet A	Yes	Door Frame	Metal	Tan	None	0	N/A	N/A		0 Negative									
1	2	200	Classroom 200	Yes	W1	Concrete	Tan	Flaking	8	N/A	N/A		0 Negative									
1	2	200	Classroom 200	Yes	W2	Concrete	Tan	Flaking	3	N/A	N/A	See Note	Negative								Same Wall System as Tested Wall (Negative)	
1	2	200	Classroom 200	Yes	W3	Concrete	Tan	Flaking	4	N/A	N/A	See Note	Negative								Same Wall System as Tested Wall (Negative)	
1	2	200	Classroom 200	Yes	W4	Concrete	Tan	Flaking	8	N/A	N/A	See Note	Negative								Same Wall System as Tested Wall (Negative)	
1	2	200	Classroom 200	Yes	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A									
1	2	200	Classroom 200	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A									
1	2	200	Classroom 200	Yes	Ventilation System	Metal	Tan	None	1	N/A	N/A		0.28 Negative									
1	2	200	Classroom 200	Yes	Door Frame	Metal	Tan	None	0	N/A	N/A		0 Negative									
1	2	200	Classroom 200 Closet B	Yes	W1	Concrete	Yellow	Flaking	3	N/A	N/A	See Note	Negative								Same Wall System as Tested Wall (Negative)	
1	2	200	Classroom 200 Closet B	Yes	W2	Concrete	Yellow	Flaking	4	N/A	N/A	See Note	Negative								Same Wall System as Tested Wall (Negative)	
1	2	200	Classroom 200 Closet B	Yes	W3	Concrete	Yellow	Flaking	1	N/A	N/A		0 Negative									
1	2	200	Classroom 200 Closet B	Yes	W4	Concrete	Yellow	Flaking	4	N/A	N/A	See Note	Negative								Same Wall System as Tested Wall (Negative)	
1	2	200	Classroom 200 Closet B	Yes	Ceiling	Concrete	Yellow	None	0	N/A	N/A	N/A	N/A									
1	2	200	Classroom 200 Closet B	Yes	Floor	N/A	N/A	N/A	N/A			N/A	N/A									
1	2	200	Classroom 200 Closet B	Yes	Door Frame	Metal	Tan	Deterioration	1				0									
1	2	200	Classroom 200 Closet B	Yes	Door Jam	Metal	Pink	Deterioration	1				0									
1	2	209A	Storage Room 209A (server room/book closet)	Yes	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access									
1	2	209A	Storage Room 209A (server room/book closet)	Yes	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access									
1	2	209A	Storage Room 209A (server room/book closet)	Yes	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access									
1	2	209A	Storage Room 209A (server room/book closet)	Yes	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access									
1	2	209A	Storage Room 209A (server room/book closet)	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access									
1	2	209A	Storage Room 209A (server room/book closet)	Yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access									
1	2	209A	Storage Room 209A	Yes	W1																	
1	2	209A	Storage Room 209A	Yes	W2																	
1	2	209A	Storage Room 209A	Yes	W3																	
1	2	209A	Storage Room 209A	Yes	W4																	
1	2	209A	Storage Room 209A	Yes	Ceiling																	
1	2	209A	Storage Room 209A	Yes	Floor																	
1	1	H17	Hallway between Auditorium and Cafeteria	Yes	W1																	
1	1	H17	Hallway between Auditorium and Cafeteria	Yes	W2																	
1	1	H17	Hallway between Auditorium and Cafeteria	Yes	W3																	
1	1	H17	Hallway between Auditorium and Cafeteria	Yes	W4																	
1	1	H17	Hallway between Auditorium and Cafeteria	Yes	Ceiling																	
1	1	H17	Hallway between Auditorium and Cafeteria	Yes	Floor																	
1	1	113	Main Office	Yes	W1	Concrete	Beige	Flaking	2	N/A	N/A	See Note	Negative								Same Wall System as Tested Wall (Negative)	
1	1	113	Main Office	Yes	W2	Concrete	Beige	None	0	N/A	N/A	N/A	Negative								Same Wall System as Tested Wall	
1	1	113	Main Office	Yes	W3	Concrete	Beige	Flaking	2	N/A	N/A		0 Negative									
1	1	113	Main Office	Yes	W4	Concrete	Beige	None	0	N/A	N/A	N/A	Negative								Same Wall System as Tested Wall	
1	1	113	Main Office	Yes	Ceiling	Drop Ceiling Tile System	White	N/A	N/A	N/A	N/A	N/A	N/A									
1	1	113	Main Office	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A									
1	1	113	Main Office	Yes	Door Frame	Metal	Tan	Friction	0	N/A	N/A		0.01 Negative									
1	1	113	Main Office	Yes	Ventilation	Metal	Beige	Friction	0	N/A	N/A		0 Negative									
1	1	114	Principal's Office	Yes	W1	Concrete	Beige	None	0	N/A	N/A	N/A	Negative								Same Wall System as Tested Wall	
1	1	114	Principal's Office	Yes	W2	Concrete	Beige	None	0	N/A	N/A		0 Negative									

				Name of Inspectors: Shalaunda Gourdine, Suzanne Shourds, James Arbuckle, Ted Mosher		School District of Philadelphia										Inspection Dates: 4/5/2021-4/28/2021							
				Inspection Company: REPSG, Inc		James Blaine Elementary School										ULCS# 4220							
E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	Lead Concentration (% wt)	Lead in Paint Chips by Flame AAS Analysis Results (positive / negative)	XRF Reading (mg/cm2)	XRF (positive/ negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes		
1	1	114	Principal's Office	Yes	W4	Concrete	Beige	None	0	N/A	N/A	N/A	Negative								Same Wall System as Testedd Wall		
1	1	114	Principal's Office	Yes	Ceiling	Drop Ceiling Tile System	White	N/A	N/A	N/A	N/A	N/A	N/A										
1	1	114	Principal's Office	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A										
1	1	114	Principal's Office	Yes	Ventilation System	Metal	Tan	None	0	N/A	N/A		0 Negative										
1	1	114	Principal's Office	Yes	Door Frame	Metal	Tan	Friction	0	N/A	N/A		0 Negative										
1	1	114A	Principal's Office Restroom	Yes	W1	Concrete	Beige	Flaking	3	N/A	N/A		0.05 Negative										
1	1	114A	Principal's Office Restroom	Yes	W2	Concrete	Beige	Flaking	4	N/A	N/A	See Note	Negative								Same Wall System as Testedd Wall (Negative)		
1	1	114A	Principal's Office Restroom	Yes	W3	Concrete	Beige	None	0	N/A	N/A	N/A	Negative								Same Wall System as Testedd Wall (Negative)		
1	1	114A	Principal's Office Restroom	Yes	W4	Concrete	Beige	Flaking	6	N/A	N/A	See Note	Negative								Same Wall System as Testedd Wall (Negative)		
1	1	114A	Principal's Office Restroom	Yes	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A										
1	1	114A	Principal's Office Restroom	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A										
1	1	114A	Principal's Office Restroom	Yes	Door Frame	Metal	Tan	Friction	0	N/A	N/A		0 Negative										
1	1	114B	Principal's Office Closet	Yes	W1	Concrete	Beige	Flaking	5	N/A	N/A	See Note	Negative								Same Wall System as Testedd Wall (Negative)		
1	1	114B	Principal's Office Closet	Yes	W2	Concrete	Beige	Flaking	10	N/A	N/A		0.01 Negative										
1	1	114B	Principal's Office Closet	Yes	W3	Concrete	Beige	Flaking	3	N/A	N/A	See Note	Negative								Same Wall System as Testedd Wall (Negative)		
1	1	114B	Principal's Office Closet	Yes	W4	Concrete	Beige	Flaking	3	N/A	N/A	See Note	Negative								Same Wall System as Testedd Wall (Negative)		
1	1	114B	Principal's Office Closet	Yes	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A										
1	1	114B	Principal's Office Closet	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A										
1	1	114B	Principal's Office Closet	Yes	Door Frame	Metal	Tan	Friction	0	N/A	N/A		0.01 Negative										
1	1	105	Classroom 105	Yes	W1	Concrete	Beige	Flaking	3	N/A	N/A		1 Positive			Negative	Prior to Repair		yes	no			
1	1	105	Classroom 105	Yes	W2	Concrete	Beige	Flaking	2	N/A	N/A		0.09 Negative										
1	1	105	Classroom 105	Yes	W3	Concrete	Beige	Flaking	3	N/A	N/A	See Note	Positive			Negative	Prior to Repair		yes	no	Same Wall System as Tested Wall (Positive)		
1	1	105	Classroom 105	Yes	W4	Concrete	Beige	None	0	N/A	N/A	N/A	N/A										
1	1	105	Classroom 105	Yes	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A										
1	1	105	Classroom 105	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A										
1	1	105	Classroom 105	Yes	Ventilation System	Metal	Tan	Friction	0	N/A	N/A		0.12 Negative										
1	1	105	Classroom 105	Yes	Door Frame	Metal	Tan	Friction	0	N/A	N/A		0 Negative										
1	1	105A	Classroom 105 Closet A	Yes	W1	Concrete	Beige	Partially Inaccessible	0	N/A	N/A	N/A	N/A										
1	1	105A	Classroom 105 Closet A	Yes	W2	Concrete	Beige	Partially Inaccessible	0	N/A	N/A	N/A	N/A										
1	1	105A	Classroom 105 Closet A	Yes	W3	Concrete	Beige	Partially Inaccessible	0	N/A	N/A	N/A	N/A										
1	1	105A	Classroom 105 Closet A	Yes	W4	Concrete	Beige	Partially Inaccessible	0	N/A	N/A	N/A	N/A										
1	1	105A	Classroom 105 Closet A	Yes	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A										
1	1	105A	Classroom 105 Closet A	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A										
1	1	105A	Classroom 105 Closet A	Yes	Door Frame	Metal	Tan	Friction	0	N/A	N/A	N/A	0 Negative										
1	1	105B	Classroom 105 Closet B	Yes	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access										
1	1	105B	Classroom 105 Closet B	Yes	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access										
1	1	105B	Classroom 105 Closet B	Yes	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access										
1	1	105B	Classroom 105 Closet B	Yes	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access										
1	1	105B	Classroom 105 Closet B	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access										
1	1	105B	Classroom 105 Closet B	Yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access										
1	1	108	Teacher's Lounge	Yes	W1	Concrete	Beige	Flaking	1	N/A	N/A		0 Negative										
1	1	108	Teacher's Lounge	Yes	W2	Concrete	Beige	Flaking	1	N/A	N/A	See Note	Negative								Same Wall System as Testedd Wall (Negative)		
1	1	108	Teacher's Lounge	Yes	W3	Concrete	Beige	Flaking	3	N/A	N/A	See Note	Negative								Same Wall System as Testedd Wall (Negative)		
1	1	108	Teacher's Lounge	Yes	W4	Concrete	Beige	Flaking	3	N/A	N/A		0 Negative										
1	1	108	Teacher's Lounge	Yes	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A										
1	1	108	Teacher's Lounge	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A										
1	1	108	Teacher's Lounge	Yes	Ventilation System	Metal	Tan	Friction	0	N/A	N/A		0 Negative										
1	1	108	Teacher's Lounge	Yes	Door Frame	Metal	Tan	Friction	0	N/A	N/A		0 Negative										
1	1	108A	Teacher's Lounge Restroom	Yes	W1	Sheetrock	White	Flacking	1	N/A	N/A		0 Negative										
1	1	108A	Teacher's Lounge Restroom	Yes	W2	Concrete	Beige	None	0	N/A	N/A		0 Negative										
1	1	108A	Teacher's Lounge Restroom	Yes	W3	Concrete	Beige	None	0	N/A	N/A	N/A	Negative								Same Wall System as Testedd Wall (Negative)		
1	1	108A	Teacher's Lounge Restroom	Yes	W4	Sheetrock	White	Flacking	1	N/A	N/A	See Note	Negative								Same Wall System as Testedd Wall (Negative)		
1	1	108A	Teacher's Lounge Restroom	Yes	Ceiling	Concrete	Beige	None	1	N/A	N/A	N/A	N/A										
1	1	108A	Teacher's Lounge Restroom	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A										
1	1	108A	Teacher's Lounge Restroom	Yes	Door Frame	Metal	Tan	Friction	0	N/A	N/A		0.01 Negative										
1	1	108B	Teacher's Lounge Closet	Yes	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access										
1	1	108B	Teacher's Lounge Closet	Yes	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access										
1	1	108B	Teacher's Lounge Closet	Yes	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access										
1	1	108B	Teacher's Lounge Closet	Yes	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access										
1	1	108B	Teacher's Lounge Closet	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access										
1	1	108B	Teacher's Lounge Closet	Yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access										
1	1	108B	Teacher's Lounge Closet	Yes	Door Frame	Metal	Tan	Friction	0	N/A	N/A	N/A	0										
1	1	S17	Exit Foyer adjacent Teacher's Lounge	Yes	W1	Ceramic	Tan	None	0	N/A	N/A	N/A	N/A										
1	1	S17	Exit Foyer adjacent Teacher's Lounge	Yes	W2	Ceramic	Tan	None	0	N/A	N/A	N/A	N/A										
1	1	S17	Exit Foyer adjacent Teacher's Lounge	Yes	W3	Ceramic	Tan	None	0	N/A	N/A	N/A	N/A										
1	1	S17	Exit Foyer adjacent Teacher's Lounge	Yes	W4	Ceramic	Tan	None	0	N/A	N/A	N/A	N/A										
1	1	S17	Exit Foyer adjacent Teacher's Lounge	Yes	Ceiling	Concrete	White	Efflorescence	1														
1	1	S17	Exit Foyer adjacent Teacher's Lounge	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A										
1	1	S17	Exit Foyer adjacent Teacher's Lounge	Yes	Door	Metal	Brown	Friction	0	N/A	N/A		0.01 Negative										
1	1	106	Library Class 104/106	Yes																			

			Name of Inspectors: Shalaunda Gourdine, Suzanne Shourds, James Arbuckle, Ted Mosher		Lead Safe Certification Assessment Report											Inspection Dates: 4/5/2021-4/28/2021					
			Inspection Company: REPSG, Inc		James Blaine Elementary School											ULCS# 4220					
E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	Lead Concentration (% wt)	Lead in Paint Chips by Flame AAS Analysis Results (positive / negative)	XRF Reading (mg/cm2)	XRF (positive/ negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes
1	1	106	Library Class 104/106	Yes	Ceiling	Drop Ceiling Tile System	White	N/A													
1	1	106	Library Class 104/106	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A								
1	1	106	Library Class 104/106	Yes	Ventilation System	Metal	Tan	Friction	0	N/A	N/A	0	Negative								
1	1	106	Library Class 104/106	Yes	Door Frame	Metal	Tan	Friction		N/A	N/A	0	Negative								
1	1	106	Library Class 104/107	Yes	W1	Concrete	Beige	None	0	N/A	N/A	1	Positive						no		
1	1	106	Library Class 104/107	Yes	W2	Concrete	Beige	None	0	N/A	N/A	See Note	Positive						no		Same Wall System as Tested Wall (Positive)
1	1	106	Library Class 104/107	Yes	W3	Concrete	Beige	None	0	N/A	N/A	See Note	Positive						no		Same Wall System as Tested Wall (Positive)
1	1	106	Library Class 104/107	Yes	W4	Concrete	Beige	None	0	N/A	N/A	See Note	Positive						no		Same Wall System as Tested Wall (Positive)
1	1	106	Library Class 104/107	Yes	Ceiling	Drop Ceiling Tile System	White	N/A	N/A	N/A	N/A	N/A	N/A								
1	1	106	Library Class 104/107	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A								
1	1	106	Library Class 104/107	Yes	Ventilation System	Metal	Tan	Friction	0	N/A	N/A	0	Negative								
1	1	106	Library Class 104/107	Yes	Door Frame	Metal	Tan	Friction		N/A	N/A	0	Negative								
1	1	106	Library Class 104/108	Yes	W1	Concrete	Beige	Intact													
1	1	106	Library Class 104/108	Yes	W2	Wood	Beige	None	0	N/A	N/A	N/A	N/A								
1	1	106	Library Class 104/108	Yes	W3	Concrete	Beige	Flaking													
1	1	106	Library Class 104/108	Yes	W4	Concrete	Beige	None	0	N/A	N/A	N/A	N/A								
1	1	106	Library Class 104/108	Yes	Ceiling	Drop Ceiling Tile System	White	N/A													
1	1	106	Library Class 104/108	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A								
1	1	106A	Library Classroom 106A	Yes	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access								
1	1	106A	Library Classroom 106A	Yes	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access								
1	1	106A	Library Classroom 106A	Yes	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access								
1	1	106A	Library Classroom 106A	Yes	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access								
1	1	106A	Library Classroom 106A	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access								
1	1	106A	Library Classroom 106A	Yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access								
1	1	106A	Library Classroom 106A	Yes	Door Frame	Metal	Tan	Friction	0	N/A	N/A	0	Negative								
1	1	106B	Library Classroom 106B	Yes	W1																
1	1	106B	Library Classroom 106B	Yes	W2																
1	1	106B	Library Classroom 106B	Yes	W3																
1	1	106B	Library Classroom 106B	Yes	W4																
1	1	106B	Library Classroom 106B	Yes	Ceiling																
1	1	106B	Library Classroom 106B	Yes	Floor																
1	1	104	Boys Restroom	Yes	W1	Concrete	Green & White	Moisture Damage	1												
1	1	104	Boys Restroom	Yes	W2	Concrete	Green & White	None	0	N/A	N/A	N/A	N/A								
1	1	104	Boys Restroom	Yes	W3	Concrete	Green & White	Cracking	1												
1	1	104	Boys Restroom	Yes	W4	Concrete	Green & White	Moisture Damage	3												
1	1	104	Boys Restroom	Yes	Ceiling	Concrete	White	Moisture Damage	4												
1	1	104	Boys Restroom	Yes	Floor	Concrete	Gray	None	0	N/A	N/A	N/A	N/A								
1	1	104	Boys Restroom	Yes	Ductwork	Metal	White	Moisture Damage	1												
1	1	104	Boys Restroom	Yes	Door Frame	Metal	Tan	None	0	N/A	N/A	N/A	N/A								
1	1	104A	Girls Restroom	Yes	W1	Concrete	Green & White	None	0	N/A	N/A	N/A	N/A								
1	1	104A	Girls Restroom	Yes	W2	Concrete	Green & White	None	0	N/A	N/A	N/A	N/A								
1	1	104A	Girls Restroom	Yes	W3	Concrete	Green & White	None	0	N/A	N/A	N/A	N/A								
1	1	104A	Girls Restroom	Yes	W4	Concrete	Green & White	None	0	N/A	N/A	N/A	N/A								
1	1	104A	Girls Restroom	Yes	Ceiling	Concrete	White	Moisture Damage	1												
1	1	104A	Girls Restroom	Yes	Floor	Concrete	Gray	Chipping	0	N/A	N/A	N/A	N/A								
1	1	104A	Girls Restroom	Yes	Ductwork	Metal	White	None	0	N/A	N/A	N/A	N/A								
1	1	104A	Girls Restroom	Yes	Door Frame	Metal	Tan	None	0	N/A	N/A	0	Negative								
1	1	104B	Library Classroom 104B	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A								See Library Classroom 106 For Notes Regarding This Area
1	1	104B	Library Classroom 104B	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A								See Library Classroom 106 For Notes Regarding This Area
1	1	104B	Library Classroom 104B	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A								See Library Classroom 106 For Notes Regarding This Area
1	1	104B	Library Classroom 104B	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A								See Library Classroom 106 For Notes Regarding This Area
1	1	104B	Library Classroom 104B	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A								See Library Classroom 106 For Notes Regarding This Area
1	1	104B	Library Classroom 104B	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A								See Library Classroom 106 For Notes Regarding This Area
1	1	105B	Storage adjacent Elevator	no	W1																
1	1	105B	Storage adjacent Elevator	no	W2																
1	1	105B	Storage adjacent Elevator	no	W3																
1	1	105B	Storage adjacent Elevator	no	W4																
1	1	105B	Storage adjacent Elevator	no	Ceiling																
1	1	105B	Storage adjacent Elevator	no	Floor																
1	1	103	Classroom 103	Yes	W1	Concrete	Beige	Flaking	20	N/A	N/A	1	Positive			Negative	Prior to Repair	yes	no		
1	1	103	Classroom 103	Yes	W2	Concrete	Beige	Flaking	12	N/A	N/A	0	Negative								
1	1	103	Classroom 103	Yes	W3	Concrete	Beige	Flaking	34	N/A	N/A	0	Negative								
1	1	103	Classroom 103	Yes	W4	Concrete	Beige	Flaking	12	N/A	N/A	0	Negative								
1	1	103	Classroom 103	Yes	Ceiling	Drop Ceiling Tile System	N/A	N/A	N/A	N/A	N/A	N/A	N/A								
1	1	103	Classroom 103	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A								
1	1	103	Classroom 103	Yes	Ventilation System	Metal	Tan	Friction	0	N/A	N/A	0	Negative								
1	1	103	Classroom 103	Yes	Door Frame	Metal	Tan	Friction	0	N/A	N/A	0	Negative								
1	1	103A	Classroom 103 Coat Room	Yes	W1	Concrete	Beige	Flaking	2	N/A	N/A		Negative								
1	1	103A	Classroom 103 Coat Room	Yes	W2	Concrete	Beige	None	0	N/A	N/A	N/A	Negative								
1	1	103A	Classroom 103 Coat Room	Yes	W3	Concrete	Beige	Flaking	1	N/A	N/A	0	Negative								
1	1	103A	Classroom 103 Coat Room	Yes	W4	Concrete	Beige	Flaking	2	N/A	N/A		Negative								
1	1	103A	Classroom 103 Coat Room	Yes	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A								

					School District of Philadelphia																	
			Name of Inspectors: Shalaunda Gourdine, Suzanne Shourds, James Arbuckle, Ted Mosher		Lead Safe Certification Assessment Report										Inspection Dates: 4/5/2021-4/28/2021							
			Inspection Company: REPSG, Inc		James Blaine Elementary School										ULCS# 4220							
E l e m e n t	F l o o r		Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	Lead Concentration (% wt)	Lead in Paint Chips by Flame AAS Analysis Results (positive / negative)	XRF Reading (mg/cm2)	XRF (positive/ negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes
1	1		103A	Classroom 103 Coat Room	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A								
1	1		103B	Classroom 103 Restroom	Yes	W1	Concrete	Beige	None	0	N/A	N/A	N/A	N/A								Same Wall System as Testedd Wall
1	1		103B	Classroom 103 Restroom	Yes	W2	Concrete	Beige	Efflorescence	1	N/A	N/A	See Note	Negative								Same Wall System as Testedd Wall (Negative)
1	1		103B	Classroom 103 Restroom	Yes	W3	Concrete	Beige	Efflorescence	1	N/A	N/A	0	Negative								
1	1		103B	Classroom 103 Restroom	Yes	W4	Concrete	Beige	None	0	N/A	N/A	N/A	N/A								Same Wall System as Testedd Wall
1	1		103B	Classroom 103 Restroom	Yes	Ceiling	Concrete	Beige	None	0	N/A	N/A	N/A	N/A								
1	1		103B	Classroom 103 Restroom	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A								
1	1		103B	Classroom 103 Restroom	Yes	Door	Metal	Tan	None	0	N/A	N/A	0	Negative								
1	1		103C	Classroom 103 Closet	Yes	W1	Concrete	Beige	Flaking	2												
1	1		103C	Classroom 103 Closet	Yes	W2	Concrete	Beige	None	0	N/A	N/A	N/A	N/A								
1	1		103C	Classroom 103 Closet	Yes	W3	Concrete	Beige	Flaking	1												
1	1		103C	Classroom 103 Closet	Yes	W4	Concrete	Beige	Flaking	1												
1	1		103C	Classroom 103 Closet	Yes	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A								
1	1		103C	Classroom 103 Closet	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A								
1	1		103C	Classroom 103 Closet	Yes	Door Frame	Metal	Tan	None	0	N/A	N/A	0	Negative								
1	1		S18	Classroom 101/103 Exit Foyer	Yes	W1																
1	1		S18	Classroom 101/103 Exit Foyer	Yes	W2																
1	1		S18	Classroom 101/103 Exit Foyer	Yes	W3																
1	1		S18	Classroom 101/103 Exit Foyer	Yes	W4																
1	1		S18	Classroom 101/103 Exit Foyer	Yes	Ceiling																
1	1		S18	Classroom 101/103 Exit Foyer	Yes	Floor																
1	1		102	Classroom 102	Yes	W1	Concrete	Beige	Flaking	15	N/A	N/A	See Note	Negative								Same Wall System as Testedd Wall (Negative)
1	1		102	Classroom 102	Yes	W2	Concrete	Beige	Flaking	3	N/A	N/A	See Note	Negative								Same Wall System as Testedd Wall (Negative)
1	1		102	Classroom 102	Yes	W3	Concrete	Beige	Flaking	15	N/A	N/A	See Note	Negative								Same Wall System as Testedd Wall (Negative)
1	1		102	Classroom 102	Yes	W4	Concrete	Beige	Flaking	12	N/A	N/A	0	Negative								
1	1		102	Classroom 102	Yes	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A								
1	1		102	Classroom 102	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A								
1	1		102	Classroom 102	Yes	Ventilation System	Metal	Beige	Friction	0	N/A	N/A	0	Negative								
1	1		102	Classroom 102	Yes	Door Frame	Metal	Tan	Friction	0	N/A	N/A	0	Negative								
1	1		102A	Classroom 102 Restroom	Yes	W1	Concrete	Beige	Flaking	20	N/A	N/A	See Note	Negative								Same Wall System as Testedd Wall (Negative)
1	1		102A	Classroom 102 Restroom	Yes	W2	Concrete	Beige	Flaking	2	N/A	N/A	0	Negative								
1	1		102A	Classroom 102 Restroom	Yes	W3	Concrete	Beige	Flaking	25	N/A	N/A	See Note	Negative								Same Wall System as Testedd Wall (Negative)
1	1		102A	Classroom 102 Restroom	Yes	W4	Concrete	Beige	Flaking	15	N/A	N/A	See Note	Negative								Same Wall System as Testedd Wall (Negative)
1	1		102A	Classroom 102 Restroom	Yes	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A								
1	1		102A	Classroom 102 Restroom	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A								
1	1		102A	Classroom 102 Restroom	Yes	Radiator	Metal	Tan	Friction	0	N/A	N/A	0	Negative								
1	1		102A	Classroom 102 Restroom	Yes	Door Frame	Metal	Tan	Friction	0	N/A	N/A	0.01	Negative								
1	1		102B	Classroom 102 Coat Room	Yes	W1	Concrete	Beige	None	0	N/A	N/A	N/A	Negative								Same Wall System as Testedd Wall
1	1		102B	Classroom 102 Coat Room	Yes	W2	Concrete	Beige	Flaking	1	N/A	N/A	See Note	Negative								Same Wall System as Testedd Wall (Negative)
1	1		102B	Classroom 102 Coat Room	Yes	W3	Concrete	Beige	Flaking	5	N/A	N/A	0	Negative								
1	1		102B	Classroom 102 Coat Room	Yes	W4	Concrete	Beige	Flaking	1	N/A	N/A	See Note	Negative								Same Wall System as Testedd Wall (Negative)
1	1		102B	Classroom 102 Coat Room	Yes	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A								
1	1		102B	Classroom 102 Coat Room	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A								
1	1		102C	Classroom 102 Closet	Yes	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access								
1	1		102C	Classroom 102 Closet	Yes	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access								
1	1		102C	Classroom 102 Closet	Yes	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access								
1	1		102C	Classroom 102 Closet	Yes	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access								
1	1		102C	Classroom 102 Closet	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access								
1	1		102C	Classroom 102 Closet	Yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access								
1	1		102C	Classroom 102 Closet	Yes	Door Frame	Metal	Tan	Flaking	1	0	Negative	N/A	N/A								
1	1		100	Classroom 100	Yes	W1	Concrete	Beige	Flaking	2	N/A	N/A	See Note	Negative								Same Wall System as Testedd Wall (Negative)
1	1		100	Classroom 100	Yes	W2	Concrete	Beige	Flaking	2	N/A	N/A	See Note	Negative								Same Wall System as Testedd Wall (Negative)
1	1		100	Classroom 100	Yes	W3	Concrete	Beige	Flaking	5	N/A	N/A	0	Negative								
1	1		100	Classroom 100	Yes	W4	Concrete	Beige	Flaking	2	N/A	N/A	See Note	Negative								Same Wall System as Testedd Wall (Negative)
1	1		100	Classroom 100	Yes	Ceiling	Drop Ceilings Tile System	N/A	None	0	N/A	N/A	N/A	N/A								
1	1		100	Classroom 100	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A								
1	1		100	Classroom 100	Yes	Ventilation System	Metal	Tan	None	0	N/A	N/A	0	Negative								
1	1		100	Classroom 100	Yes	Door Frame	Metal	Tan	Friction	0	N/A	N/A	0	Negative								
1	1		100C	Classroom 100 Closet A	Yes	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access								
1	1		100C	Classroom 100 Closet A	Yes	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access								
1	1		100C	Classroom 100 Closet A	Yes	W3	No Access	No Access	No Access	No Access	No Access	No Access	0	Negative								
1	1		100C	Classroom 100 Closet A	Yes	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access								
1	1		100C	Classroom 100 Closet A	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access								
1	1		100C	Classroom 100 Closet A	Yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access								
1	1		100C	Classroom 100 Closet A	Yes	Door Frame	Metal	Tan	Friction	0	N/A	N/A	0	Negative								
1	1		100A	Classroom 100 Coat Room	Yes	W1	Concrete	Beige	Flaking	2	N/A	N/A	See Note	Negative								Same Wall System as Testedd Wall (Negative)
1	1		100A	Classroom 100 Coat Room	Yes	W2	Concrete	Beige	Flaking	1	N/A	N/A	See Note	Negative								Same Wall System as Testedd Wall (Negative)
1	1		100A	Classroom 100 Coat Room	Yes	W3	Concrete	Beige	Flaking	10	N/A	N/A	0.01	Negative								

					School District of Philadelphia																	
			Name of Inspectors: Shalaunda Gourdine, Suzanne Shourds, James Arbuckle, Ted Mosher		Lead Safe Certification Assessment Report										Inspection Dates: 4/5/2021-4/28/2021							
			Inspection Company: REPSG, Inc		James Blaine Elementary School										ULCS# 4220							
E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	Lead Concentration (% wt)	Lead in Paint Chips by Flame AAS Analysis Results (positive / negative)	XRF Reading (mg/cm2)	XRF (positive/ negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes	
1	1	100A	Classroom 100 Coat Room	Yes	W4	Concrete	Beige	Flaking	2	N/A	N/A	See Note	Negative								Same Wall System as Tested Wall (Negative)	
1	1	100A	Classroom 100 Coat Room	Yes	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A									
1	1	100A	Classroom 100 Coat Room	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A									
1	1	100B	Classroom 100 Restroom	Yes	W1	Concrete	Beige	Flaking	3	N/A	N/A	See Note	Negative								Same Wall System as Tested Wall (Negative)	
1	1	100B	Classroom 100 Restroom	Yes	W2	Concrete	Beige	Flaking	3	N/A	N/A	See Note	Negative								Same Wall System as Tested Wall (Negative)	
1	1	100B	Classroom 100 Restroom	Yes	W3	Concrete	Beige	Flaking	6	N/A	N/A		0 Negative									
1	1	100B	Classroom 100 Restroom	Yes	W4	Concrete	Beige	Flaking	9	N/A	N/A	See Note	Negative								Same Wall System as Tested Wall (Negative)	
1	1	100B	Classroom 100 Restroom	Yes	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A									
1	1	100B	Classroom 100 Restroom	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A									
1	1	100B	Classroom 100 Restroom	Yes	Radiator	Metal	Gray	Deteriorated	1	N/A	N/A		0 Negative									
1	1	100B	Classroom 100 Restroom	Yes	Door Frame	Metal	Tan	Friction	0	N/A	N/A		0 Negative									
1	1	099	Technology Office 099	Yes	W1	Concrete	Beige	Flaking	10	N/A	N/A		0 Negative									
1	1	099	Technology Office 099	Yes	W2	Concrete	Beige	Flaking	8	N/A	N/A		0 Negative									
1	1	099	Technology Office 099	Yes	W3	Concrete	Beige	Flaking	1	N/A	N/A	See Note	Negative								Same Wall System as Tested Wall (Negative)	
1	1	099	Technology Office 099	Yes	W4	Concrete	Beige	Flaking	1	N/A	N/A	See Note	Negative								Same Wall System as Tested Wall (Negative)	
1	1	099	Technology Office 099	Yes	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A									
1	1	099	Technology Office 099	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A									
1	1	099	Technology Office 099	Yes	Ventilation System	Metal	Tan	Friction	0	N/A	N/A		0 Negative									
1	1	099	Technology Office 099	Yes	Door Frame	Metal	Tan	Friction	1	N/A	N/A		0 Negative									
1	1	099A	Technology Office 099 Closet A	Yes	W1	No Access	No Access	No Access	No Access	No Access	No Access		0 Negative									
1	1	099A	Technology Office 099 Closet A	Yes	W2	No Access	No Access	No Access	No Access	No Access	No Access		0 Negative									
1	1	099A	Technology Office 099 Closet A	Yes	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access									
1	1	099A	Technology Office 099 Closet A	Yes	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access									
1	1	099A	Technology Office 099 Closet A	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access									
1	1	099A	Technology Office 099 Closet A	Yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access									
1	1	099A	Technology Office 099 Closet A	Yes	Door Frame	Metal	Tan	Friction	0	N/A	N/A		0 Negative									
1	1	101	Classroom 101	Yes	W1	Concrete	Beige	Flaking	7	N/A	N/A		0 Negative									
1	1	101	Classroom 101	Yes	W2	Concrete	Beige	Flaking	5	N/A	N/A	See Note	Negative								Same Wall System as Tested Wall (Negative)	
1	1	101	Classroom 101	Yes	W3	Concrete	Beige	Flaking	7	N/A	N/A	See Note	Negative								Same Wall System as Tested Wall (Negative)	
1	1	101	Classroom 101	Yes	W4	Concrete	Beige	Flaking	2	N/A	N/A	See Note	Negative								Same Wall System as Tested Wall (Negative)	
1	1	101	Classroom 101	Yes	Ceiling	Drop Ceiling Tile System	N/A	N/A	N/A	N/A	N/A	N/A	N/A									
1	1	101	Classroom 101	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A									
1	1	101	Classroom 101	Yes	Ventilation System	Metal	Tan	Friction	0	N/A	N/A		0 Negative									
1	1	101	Classroom 101	Yes	Door Frame	Metal	Tan	Friction	0	N/A	N/A		0 Negative									
1	1	101	Classroom 101	Yes	Door Frame	Metal	Green	Friction	0	N/A	N/A		0 Negative									
1	1	101C	Classroom 101 Closet B	Yes	W1	No Access	No Access	No Access	No Access	No Access	No Access		0 Negative									
1	1	101C	Classroom 101 Closet B	Yes	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Negative								Same Wall System as Tested Wall	
1	1	101C	Classroom 101 Closet B	Yes	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Negative								Same Wall System as Tested Wall	
1	1	101C	Classroom 101 Closet B	Yes	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Negative								Same Wall System as Tested Wall	
1	1	101C	Classroom 101 Closet B	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access									
1	1	101C	Classroom 101 Closet B	Yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access									
1	1	101C	Classroom 101 Closet B	Yes	Door Frame	Metal	Tan	Friction	0	N/A	N/A		0.01 Negative									
1	1	101D	Classroom 101 Closet A	Yes	W1	No Access	No Access	No Access	No Access	No Access	No Access		0 Negative									
1	1	101D	Classroom 101 Closet A	Yes	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Negative								Same Wall System as Tested Wall	
1	1	101D	Classroom 101 Closet A	Yes	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Negative								Same Wall System as Tested Wall	
1	1	101D	Classroom 101 Closet A	Yes	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Negative								Same Wall System as Tested Wall	
1	1	101D	Classroom 101 Closet A	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access									
1	1	101D	Classroom 101 Closet A	Yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access									
1	1	101D	Classroom 101 Closet A	Yes	Door Frame	No Access	No Access	No Access	No Access	No Access	No Access		0.01 Negative									
1	1	101A	Classroom 101 Coat Room	Yes	W1	Concrete	Beige	Flaking	1	N/A	N/A	See Note	Negative								Same Wall System as Tested Wall (Negative)	
1	1	101A	Classroom 101 Coat Room	Yes	W2	Concrete	Beige	Flaking	3	N/A	N/A		0.01 Negative									
1	1	101A	Classroom 101 Coat Room	Yes	W3	Concrete	Beige	Flaking	1	N/A	N/A	See Note	Negative								Same Wall System as Tested Wall (Negative)	
1	1	101A	Classroom 101 Coat Room	Yes	W4	Concrete	Beige	Flaking	1	N/A	N/A	See Note	Negative								Same Wall System as Tested Wall (Negative)	
1	1	101A	Classroom 101 Coat Room	Yes	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A									
1	1	101A	Classroom 101 Coat Room	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A									
1	1	101B	Classroom 101 Restroom	Yes	W1	Concrete	Beige	Flaking	1	N/A	N/A	See Note	Negative								Same Wall System as Tested Wall (Negative)	
1	1	101B	Classroom 101 Restroom	Yes	W2	Concrete	Beige	Flaking	1	N/A	N/A	See Note	Negative								Same Wall System as Tested Wall (Negative)	
1	1	101B	Classroom 101 Restroom	Yes	W3	Concrete	Beige	None	0	N/A	N/A	N/A	Negative								Same Wall System as Tested Wall	
1	1	101B	Classroom 101 Restroom	Yes	W4	Concrete	Beige	Flaking	1	N/A	N/A		0 Negative									
1	1	101B	Classroom 101 Restroom	Yes	Ceiling	Concrete	White	Flaking	1													
1	1	101B	Classroom 101 Restroom	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A									
1	1	101B	Classroom 101 Restroom	Yes	Door Frame	Metal	Tan	Friction	0	N/A	N/A		0 Negative									
1	1	H15	Hallway from Classrooms 100 to 106	Yes	W1	Concrete	Beige	Flaking	10	N/A	N/A		1 Positive				No		yes		Near Classroom 106	
1	1	H15	Hallway from Classrooms 100 to 106	Yes	W1	Concrete	Red	None	0	N/A	N/A		0 Negative									
1	1	H15	Hallway from Classrooms 100 to 106	Yes	W2	Concrete	Beige	Flaking	0	N/A	N/A	See Note	Positive						no		Same Wall System as Tested Wall (Positive)	
1	1	H15	Hallway from Classrooms 100 to 106	Yes	W3	Concrete	Beige	Flaking	18	N/A	N/A		1 Positive				No		yes		Near Classroom 106	
1	1	H15	Hallway from Classrooms 100 to 106	Yes	W3	Concrete	Red	None	0	N/A	N/A		0 Negative									
1	1	H15	Hallway from Classrooms 100 to 106	Yes	W4	Concrete	Beige	Flaking	1	N/A	N/A		1 Positive				No		yes		Near Classroom 9	

			School District of Philadelphia																						
			Name of Inspectors: Shalaunda Gourdine, Suzanne Shourds, James Arbuckle, Ted Mosher			Lead Safe Certification Assessment Report												Inspection Dates: 4/5/2021-4/28/2021							
			Inspection Company: REPSG, Inc			James Blaine Elementary School												ULCS# 4220							
E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	Lead Concentration (% wt)	Lead in Paint Chips by Flame AAS Analysis Results (positive / negative)	XRF Reading (mg/cm2)	XRF (positive/ negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes				
1	1	H15	Hallway from Classrooms 100 to 106	Yes	Ventilation System	Metal	Tan	Friction	0	N/A	N/A	0	Negative												
1	1	H13	Hallway from Classrooms 107 to 108	Yes	W1																				
1	1	H13	Hallway from Classrooms 107 to 108	Yes	W2																				
1	1	H13	Hallway from Classrooms 107 to 108	Yes	W3																				
1	1	H13	Hallway from Classrooms 107 to 108	Yes	W4																				
1	1	H13	Hallway from Classrooms 107 to 108	Yes	Ceiling																				
1	1	H13	Hallway from Classrooms 107 to 108	Yes	Floor																				
1	1	H10	Hallway at Auditorium	Yes	W1																				
1	1	H10	Hallway at Auditorium	Yes	W2																				
1	1	H10	Hallway at Auditorium	Yes	W3																				
1	1	H10	Hallway at Auditorium	Yes	W4																				
1	1	H10	Hallway at Auditorium	Yes	Ceiling																				
1	1	H10	Hallway at Auditorium	Yes	Floor																				
1	1	S14	Main Entrance Stairs	Yes	W1																				
1	1	S14	Main Entrance Stairs	Yes	W2																				
1	1	S14	Main Entrance Stairs	Yes	W3																				
1	1	S14	Main Entrance Stairs	Yes	W4																				
1	1	S14	Main Entrance Stairs	Yes	Ceiling																				
1	1	S14	Main Entrance Stairs	Yes	Floor																				
1	1	116	Auditorium	Yes	W1																				
1	1	116	Auditorium	Yes	W2																				
1	1	116	Auditorium	Yes	W3																				
1	1	116	Auditorium	Yes	W4																				
1	1	116	Auditorium	Yes	Ceiling																				
1	1	116	Auditorium	Yes	Floor																				
1	1	116A	Stage	Yes	W1		Black			<0.0080	Negative	N/A	N/A												
1	1	116A	Stage	Yes	W2		Beige			<0.0080	Negative	N/A	N/A												
1	1	116A	Stage	Yes	W3																				
1	1	116A	Stage	Yes	W4																				
1	1	116A	Stage	Yes	Ceiling																				
1	1	116A	Stage	Yes	Floor																				
1	1	117	Cafetorium	Yes	W1	Concrete	Blue	Flaking	8	N/A	N/A	0	Negative												
1	1	117	Cafetorium	Yes	W2	Concrete	Blue	Flaking	2	N/A	N/A	See Note	Negative								Same Wall System as Tested Wall (Negative)				
1	1	117	Cafetorium	Yes	W3	Concrete	Blue	Flaking	2	N/A	N/A	See Note	Negative								Same Wall System as Tested Wall (Negative)				
1	1	117	Cafetorium	Yes	W4	Concrete	Blue	Flaking	6	N/A	N/A	See Note	Negative								Same Wall System as Tested Wall (Negative)				
1	1	117	Cafetorium	Yes	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A												
1	1	117	Cafetorium	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A												
1	1	117	Cafetorium	Yes	Door Frame	Metal	Brown	Friction	0	N/A	N/A	N/A	0	Negative											
1	1	117	Cafetorium Exit Doors	Yes	Door Frame	Metal	Brown	Friction	0	N/A	N/A	N/A	0	Negative											
1	1	117	Cafetorium	Yes	Wall Pilar	Concrete	Light Green	Friction	0	N/A	N/A	N/A	0	Negative											
1	1	117A	Cafetorium Closet near Entrance	Yes	W1	Concrete	Blue	Flaking	4	N/A	N/A	0.25	Negative												
1	1	117A	Cafetorium Closet near Entrance	Yes	W2	Concrete	Blue	Flaking	2	N/A	N/A	See Note	Negative								Same Wall System as Tested Wall (Negative)				
1	1	117A	Cafetorium Closet near Entrance	Yes	W3	Concrete	Blue	Flaking	3	N/A	N/A	See Note	Negative								Same Wall System as Tested Wall (Negative)				
1	1	117A	Cafetorium Closet near Entrance	Yes	W4	Concrete	Blue	Partially Inaccessible	0	N/A	N/A	N/A	Negative								Same Wall System as Tested Wall				
1	1	117A	Cafetorium Closet near Entrance	Yes	Ceiling	Drop Ceiling Tile Syste,	White	N/A	None	N/A	N/A		0	Negative											
1	1	117A	Cafetorium Closet near Entrance	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A												
1	1	117A	Cafetorium Closet near Entrance	Yes	Door Frame	Metal	Green	Friction	0	N/A	N/A		0.01	Negative											
1	1	117A	Cafetorium Closet near Entrance	Yes	Door	Metal	Green	Friction	0	N/A	N/A		0	Negative											
1	1	123	Kitchen	Yes	W1	Ceramic	Light Green	None	0	N/A	N/A	N/A	N/A												
1	1	123	Kitchen	Yes	W2	Ceramic	Light Green	None	0	N/A	N/A	N/A	N/A												
1	1	123	Kitchen	Yes	W3	Ceramic	Light Green	None	0	N/A	N/A	N/A	N/A												
1	1	123	Kitchen	Yes	W4	Ceramic	Light Green	None	0	N/A	N/A	N/A	N/A												
1	1	123	Kitchen	Yes	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	0	Negative											
1	1	123	Kitchen	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A												
1	1	123	Kitchen	Yes	Ventilation System	Metal	Beige	None	0	N/A	N/A		0	Negative											
1	1	123	Kitchen	Yes	Door	Metal	Gray	Friction	0	N/A	N/A		0	Negative											
1	1	123	Kitchen	Yes	Door Frame	Metal	Green	Friction	1	N/A	N/A		0.01	Negative											
1	1	123A	Kitchen Closet	Yes	W1	Concrete	Beige	None	0	N/A	N/A	N/A	Negative								Same Wall System as Tested Wall				
1	1	123A	Kitchen Closet	Yes	W2	Concrete	Beige	None	0	N/A	N/A	N/A	Negative								Same Wall System as Tested Wall				
1	1	123A	Kitchen Closet	Yes	W3	Concrete	Beige	None	0	N/A	N/A	N/A	0	Negative											
1	1	123A	Kitchen Closet	Yes	W4	Concrete	Beige	Partially Inaccessible	0	N/A	N/A	N/A	Negative								Same Wall System as Tested Wall				
1	1	123A	Kitchen Closet	Yes	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	0	Negative											
1	1	123A	Kitchen Closet	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A												
1	1	123A	Kitchen Closet	Yes	Door Frame	Metal	Green	Friction	0	N/A	N/A	N/A	0	Negative											
1	1	122	Cafeteria Boy's Restroom	Yes	W1	Concrete	Light Green	None	0	N/A	N/A	N/A	Negative								Same Wall System as Tested Wall				
1	1	122	Cafeteria Boy's Restroom	Yes	W2	Concrete	Light Green	Moisture Damage	4	N/A	N/A	See Note	Negative								Same Wall System as Tested Wall (Negative)				
1	1	122	Cafeteria Boy's Restroom	Yes	W3	Concrete	Light Green	None	0	N/A	N/A	N/A	Negative								Same Wall System as Tested Wall				
1	1	122	Cafeteria Boy's Restroom	Yes	W4	Concrete	Light Green	None	0	N/A	N/A		0	Negative											
1	1	122	Cafeteria Boy's Restroom	Yes	Ceiling	Concrete	White	Flaking	2	N/A	N/A		0	Negative											
1	1	122	Cafeteria Boy's Restroom	Yes	Floor	Concrete	Gray	Cracking	2	N/A	N/A		0	Negative											
1	1	122	Cafeteria Boy's Restroom	Yes	Kickplate	Ceramic	Gray	Flacking	1	N/A	N/A	1.83	Positive				No		no		Substrate is Ceramic, Similar paint tested negative elsewhere, Assume Positive result due to content in Ceramic tile				
1	1	122	Cafeteria Boy's Restroom	Yes	Door	Metal	Gray	Friction	0	N/A	N/A		0	Negative											
1	1	122	Cafeteria Boy's Restroom	Yes	Door Frame	Metal	Gray	Friction	0	N/A	N/A		0	Negative											
1	1	121	Cafeteria Girl's Restroom	Yes	W1	Concrete	Light Green	None	0	N/A	N/A		0	Negative											
1	1	121	Cafeteria Girl's Restroom	Yes	W2	Concrete	Light Green	None	0	N/A	N/A	N/A	Negative								Same Wall System as Tested Wall				

			School District of Philadelphia																		
			Name of Inspectors: Shalaunda Gourdine, Suzanne Shourds, James Arbuckle, Ted Mosher		Lead Safe Certification Assessment Report								Inspection Dates: 4/5/2021-4/28/2021								
			Inspection Company: REPSG, Inc		James Blaine Elementary School								ULCS# 4220								
E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	Lead Concentration (% wt)	Lead in Paint Chips by Flame AAS Analysis Results (positive / negative)	XRF Reading (mg/cm2)	XRF (positive/ negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes
1	1	121	Cafeteria Girl's Restroom	Yes	W3	Concrete	Light Green	None	0	N/A	N/A	N/A	Negative								Same Wall System as Tested Wall
				Yes	W4	Concrete	Light Green	Moisture Damage	5	N/A	N/A	See Note	Negative								Same Wall System as Tested Wall (Negative)
1	1	121	Cafeteria Girl's Restroom	Yes	Ceiling	Concrete	White	Cracking	5	N/A	N/A	See Note	0 Negative								
1	1	121	Cafeteria Girl's Restroom	Yes	Floor	Concrete	Gray	Flaking	4	N/A	N/A		0 Negative								
1	1	121	Cafeteria Girl's Restroom	Yes	Kickplate	Ceramic	Gray	None	0	N/A	N/A	2.77	Positive					no			
1	1	121	Cafeteria Girl's Restroom	Yes	Door	Metal	Gray	Friction	0	N/A	N/A		0 Negative								
1	1	121	Cafeteria Girl's Restroom	Yes	Door Frame	Metal	Gray	Friction	0	N/A	N/A		0 Negative								
1	1	120	Kitchen Storage	Yes	W1	Concrete	Beige	Flaking	1	N/A	N/A	See Note	Negative								Same Wall System as Tested Wall (Negative)
1	1	120	Kitchen Storage	Yes	W2	Concrete	Beige	Flaking	1	N/A	N/A	See Note	Negative								Same Wall System as Tested Wall (Negative)
1	1	120	Kitchen Storage	Yes	W3	Concrete	Beige	Cracking	1	N/A	N/A	See Note	Negative								Same Wall System as Tested Wall (Negative)
1	1	120	Kitchen Storage	Yes	W4	Concrete	Beige	Cracking	1	N/A	N/A		0.15 Negative								
1	1	120	Kitchen Storage	Yes	Ceiling	Concrete	White	None	0	N/A	N/A		0 Negative								
1	1	120	Kitchen Storage	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A								
1	1	120	Kitchen Storage	Yes	Ventilation System	Metal	Beige	None	0	N/A	N/A		0.44 Negative								
1	1	120	Kitchen Storage	Yes	Door Frame	Metal	Green	Friction	0	N/A	N/A		0 Negative								
1	1	120	Kitchen Storage	Yes	Door Frame	Metal	Gray	Friction	0	N/A	N/A		0 Negative								
1	1	107A	Receiving/Trash Room	no	W1																
1	1	107A	Receiving/Trash Room	no	W2																
1	1	107A	Receiving/Trash Room	no	W3																
1	1	107A	Receiving/Trash Room	no	W4																
1	1	107A	Receiving/Trash Room	no	Ceiling																
1	1	107A	Receiving/Trash Room	no	Floor																
1	1	S16	Hallway Stairs adjacent Auditorium	Yes	W1																
1	1	S16	Hallway Stairs adjacent Auditorium	Yes	W2																
1	1	S16	Hallway Stairs adjacent Auditorium	Yes	W3																
1	1	S16	Hallway Stairs adjacent Auditorium	Yes	W4																
1	1	S16	Hallway Stairs adjacent Auditorium	Yes	Ceiling																
1	1	S16	Hallway Stairs adjacent Auditorium	Yes	Floor																
1	1	109	Office 109	Yes	W1	Concrete	Beige	Flaking	30	N/A	N/A	See Note	Negative								Same Wall System as Tested Wall (Negative)
1	1	109	Office 109	Yes	W2	Concrete	Beige	Flaking	6	N/A	N/A		0 Negative								
1	1	109	Office 109	Yes	W3	Concrete	Beige	Flaking	14	N/A	N/A	See Note	Negative								Same Wall System as Tested Wall (Negative)
1	1	109	Office 109	Yes	W4	Concrete	Beige	Flaking	8	N/A	N/A	See Note	Negative								Same Wall System as Tested Wall (Negative)
1	1	109	Office 109	Yes	Ceiling	Drop Ceiling Tile System	N/A	N/A	N/A	N/A	N/A	N/A	N/A								
1	1	109	Office 109	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A								
1	1	109	Office 109	Yes	Ventilation System	Metal	Tan	Friction	0	N/A	N/A		0 Negative								
1	1	109	Office 109	Yes	Door Frame	Metal	Tan	Flaking	1	N/A	N/A		0 Negative								
1	1	110	Nurse's Office	Yes	W1	Concrete	Beige	Flaking	4	N/A	N/A		1 Positive			Negative	Prior to Repair		yes	no	
1	1	110	Nurse's Office	Yes	W2	Concrete	Beige	Flaking	7	N/A	N/A		1 Positive			Negative	Prior to Repair		yes	no	
1	1	110	Nurse's Office	Yes	W3	Sheetrock	Beige	Flaking	9	N/A	N/A		0 Negative								
1	1	110	Nurse's Office	Yes	W4	Sheetrock	Beige	Flaking	6	N/A	N/A		0 Negative								
1	1	110	Nurse's Office	Yes	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A								
1	1	110	Nurse's Office	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A								
1	1	110	Nurse's Office	Yes	Door Frame	Metal	Tan	Friction	1	N/A	N/A		0 Negative								
1	1	110	Nurse's Office	Yes	Ventilation System	Metal	Tan	Friction	0	N/A	N/A		0 Negative								
1	1	110A	Nurse's Office Restroom	Yes	W1	Concrete	Beige	Flaking	2	N/A	N/A	See Note	Negative								Same Wall System as Tested Wall (Negative)
1	1	110A	Nurse's Office Restroom	Yes	W2	Concrete	Beige	Flaking	3	N/A	N/A	See Note	Negative								Same Wall System as Tested Wall (Negative)
1	1	110A	Nurse's Office Restroom	Yes	W3	Concrete	Beige	Flaking	4	N/A	N/A	See Note	Negative								Same Wall System as Tested Wall (Negative)
1	1	110A	Nurse's Office Restroom	Yes	W4	Sheetrock	Beige	Flaking	4	N/A	N/A		0.01 Negative								
1	1	110A	Nurse's Office Restroom	Yes	Ceiling	Concrete	Beige	None	0	N/A	N/A	N/A	N/A								
1	1	110A	Nurse's Office Restroom	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A								
1	1	110A	Nurse's Office Restroom	Yes	Door Frame	Metal	Tan	Friction	0	N/A	N/A		0 Negative								
1	1	110B	Nurse's Office Closet	Yes	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access								
1	1	110B	Nurse's Office Closet	Yes	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access								
1	1	110B	Nurse's Office Closet	Yes	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access								
1	1	110B	Nurse's Office Closet	Yes	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access								
1	1	110B	Nurse's Office Closet	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access								
1	1	110B	Nurse's Office Closet	Yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access								
1	1	110B	Nurse's Office Closet	Yes	Door Frame	Metal	Tan	Friction	0	N/A	N/A		0 Negative								
1	1	112	Office 112	Yes	W1	Concrete	Beige	Flaking	2	N/A	N/A	See Note	Negative								Same Wall System as Tested Wall (Negative)
1	1	112	Office 112	Yes	W2	Concrete	Beige	Flaking	1	N/A	N/A		0 Negative								
1	1	112	Office 112	Yes	W3	Concrete	Beige	Flaking	3	N/A	N/A	See Note	Negative								Same Wall System as Tested Wall (Negative)
1	1	112	Office 112	Yes	W4	Concrete	Beige	Flaking	3	N/A	N/A		Negative								
1	1	112	Office 112	Yes	Ceiling	Drop Ceiling Tile System	White	None	0	N/A	N/A	N/A	N/A								
1	1	112	Office 112	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A								
1	1	112	Office 112	Yes	Window Frame	Metal	Tan	Friction	0	N/A	N/A		0 Negative								
1	1	112	Office 112	Yes	Ventilation System	Metal	Beige	Friction	0	N/A	N/A		0 Negative								
1	1	112	Office 112	Yes	Door Frame	Metal	Tan	Friction	0	N/A	N/A		0.03 Negative								
1	1	111	Office 111	Yes	W1	Concrete	Beige	Flaking	4	N/A	N/A	See Note	Negative								Same Wall System as Tested Wall (Negative)
1	1	111	Office 111	Yes	W2	Concrete	Beige	Flaking	6	N/A	N/A		0 Negative								

					School District of Philadelphia																	
			Name of Inspectors: Shalaunda Gourdine, Suzanne Shourds, James Arbuckle, Ted Mosher		Lead Safe Certification Assessment Report										Inspection Dates: 4/5/2021-4/28/2021							
			Inspection Company: REPSG, Inc		James Blaine Elementary School										ULCS# 4220							
E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	Lead Concentration (% wt)	Lead in Paint Chips by Flame AAS Analysis Results (positive / negative)	XRF Reading (mg/cm2)	XRF (positive/ negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes	
1	1	111	Office 111	Yes	W3	Concrete	Beige	Flaking	3	N/A	N/A	See Note	Negative								Same Wall System as Tested Wall (Negative)	
1	1	111	Office 111	Yes	W4	Concrete	Beige	Flaking	3	N/A	N/A	See Note	Negative								Same Wall System as Tested Wall (Negative)	
1	1	111	Office 111	Yes	Ceiling	Drop Ceiling Tile System	White	N/A	N/A	N/A	N/A	N/A	N/A									
1	1	111	Office 111	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A									
1	1	111	Office 111	Yes	Window Frame	Metal	Tan	Friction	0	N/A	N/A		0 Negative									
1	1	111	Office 111	Yes	Ventilation System	Metal	Tan	Friction	0	N/A	N/A		0 Negative									
1	1	111	Office 111	Yes	Door Frame	Metal	Beige	Friction	0	N/A	N/A		0.01 Negative									
1	1	113A	Main Office Closet	Yes	W1	Concrete	Beige	None	0	N/A	N/A	N/A	Negative								Same Wall System as Tested Wall	
1	1	113A	Main Office Closet	Yes	W2	Concrete	Beige	Flaking	2	N/A	N/A		0 Negative									
1	1	113A	Main Office Closet	Yes	W3	Concrete	Beige	Flaking	1	N/A	N/A	See Note	Negative								Same Wall System as Tested Wall (Negative)	
1	1	113A	Main Office Closet	Yes	W4	Concrete	Beige	None	0	N/A	N/A	N/A	Negative								Same Wall System as Tested Wall	
1	1	113A	Main Office Closet	Yes	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A									
1	1	113A	Main Office Closet	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A									
1	1	113A	Main Office Closet	Yes	Door Frame	Metal	Tan	Friction	0	N/A	N/A		0.01 Negative									
1	1	113B	Main Office Closet B	Yes	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Negative								Same Wall System as Tested Wall	
1	1	113B	Main Office Closet B	Yes	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access									
1	1	113B	Main Office Closet B	Yes	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Negative								Same Wall System as Tested Wall	
1	1	113B	Main Office Closet B	Yes	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Negative								Same Wall System as Tested Wall	
1	1	113B	Main Office Closet B	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access									
1	1	113B	Main Office Closet B	Yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access									
1	1	113B	Main Office Closet B	Yes	Door Frame	Metal	Tan	Friction	0	N/A	N/A		0 Negative									
1	1	113C	Main Office Closet C	Yes	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Negative								Same Wall System as Tested Wall	
1	1	113C	Main Office Closet C	Yes	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access									
1	1	113C	Main Office Closet C	Yes	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Negative								Same Wall System as Tested Wall	
1	1	113C	Main Office Closet C	Yes	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Negative								Same Wall System as Tested Wall	
1	1	113C	Main Office Closet C	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access									
1	1	113C	Main Office Closet C	Yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access									
1	1	113C	Main Office Closet C	Yes	Door Frame	Metal	Tan	Friction	0	N/A	N/A		0 Negative									
1	1	105A	Book Storage Room 105A	Yes	W1	Sheetrock	Beige	None	0	N/A	N/A		0 Negative									
1	1	105A	Book Storage Room 105A	Yes	W2	Sheetrock	Beige	None	0	N/A	N/A	N/A	N/A								Same Wall System as Testedd Wall	
1	1	105A	Book Storage Room 105A	Yes	W3	Sheetrock	Beige	None	0	N/A	N/A	N/A	N/A								Same Wall System as Testedd Wall	
1	1	105A	Book Storage Room 105A	Yes	W4	Sheetrock	Beige	None	0	N/A	N/A	N/A	N/A								Same Wall System as Testedd Wall	
1	1	105A	Book Storage Room 105A	Yes	Ceiling	Concrete	White	None	0	N/A	N/A		0 Negative									
1	1	105A	Book Storage Room 105A	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A									
1	1	105A	Book Storage Room 105A	Yes	Door Frame	Metal	Light Green	Friction	0	N/A	N/A		0.02 Negative									
1	1	105A	Book Storage Room 105A	Yes	Door Frame	Metal	Beige	Friction	0	N/A	N/A		0 Negative									
1	1	107	Classroom 107	Yes	W1	Concrete	Beige	Flaking	1	N/A	N/A		0 Negative									
1	1	107	Classroom 107	Yes	W2	Concrete	Beige	None	0	N/A	N/A	N/A	Negative								Same Wall System as Testedd Wall	
1	1	107	Classroom 107	Yes	W3	Concrete	Beige	Flaking	12	N/A	N/A	See Note	Negative								Same Wall System as Testedd Wall (Negative)	
1	1	107	Classroom 107	Yes	W4	Sheetrock	Beige	None	0	N/A	N/A		0 Negative									
1	1	107	Classroom 107	Yes	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A									
1	1	107	Classroom 107	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A									
1	1	107	Classroom 107	Yes	Ventilation System	Metal	Tan	Friction	0	N/A	N/A		0 Negative									
1	1	107	Classroom 107	Yes	Door Frame	Metal	Tan	Friction	1	N/A	N/A		0.01 Negative									
1	1	107A	Classroom 107A Closet	Yes	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access									
1	1	107A	Classroom 107A Closet	Yes	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access									
1	1	107A	Classroom 107A Closet	Yes	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access									
1	1	107A	Classroom 107A Closet	Yes	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access									
1	1	107A	Classroom 107A Closet	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access									
1	1	107A	Classroom 107A Closet	Yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access									
1	1	107A	Classroom 107A Closet	Yes	Door Frame	Metal	Tan	Friction	0	N/A	N/A		0 Negative									
1	1	107B	Classroom 107B Closet	Yes	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access									
1	1	107B	Classroom 107B Closet	Yes	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access									
1	1	107B	Classroom 107B Closet	Yes	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access									
1	1	107B	Classroom 107B Closet	Yes	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access									
1	1	107B	Classroom 107B Closet	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access									
1	1	107B	Classroom 107B Closet	Yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access									
1	1	107C	Staff Restroom Womens	Yes	W1	Concrete	Beige	Craking	2	N/A	N/A	See Note	Negative								Same Wall System as Tested Wall (Negative)	
1	1	107C	Staff Restroom Womens	Yes	W2	Concrete	Beige	Cracking	2	N/A	N/A	See Note	Negative								Same Wall System as Tested Wall (Negative)	
1	1	107C	Staff Restroom Womens	Yes	W3	Concrete	Beige	Cracking	2	N/A	N/A		0 Negative									
1	1	107C	Staff Restroom Womens	Yes	W4	Concrete	Beige	None	0	N/A	N/A	N/A	N/A								Same Wall System as Testedd Wall	
1	1	107C	Staff Restroom Womens	Yes	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A									
1	1	107C	Staff Restroom Womens	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A									
1	1	107C	Staff Restroom Womens	Yes	Radiator	Metal	Tan	Friction	0	N/A	N/A	N/A	N/A									
1	1	107C	Staff Restroom Womens	Yes	Door Frame	Metal	Tan	Friction	0	N/A	N/A		0.05 Negative									
1	1	106C	Book Storage	Yes	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access									
1	1	106C	Book Storage	Yes	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No									

					School District of Philadelphia																	
			Name of Inspectors: Shalaunda Gourdine, Suzanne Shourds, James Arbuckle, Ted Mosher		Lead Safe Certification Assessment Report										Inspection Dates: 4/5/2021-4/28/2021							
			Inspection Company: REPSG, Inc		James Blaine Elementary School										ULCS# 4220							
E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	Lead Concentration (% wt)	Lead in Paint Chips by Flame AAS Analysis Results (positive / negative)	XRF Reading (mg/cm2)	XRF (positive/ negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes	
1	1	118	Physical Education Office	Yes	Floor																	
1	1	119	Cafeteria Storage	Yes	W1	Concrete	Beige	Partially Inaccessible	0	N/A	N/A	N/A	Negative								Same Wall System as Tested Wall	
1	1	119	Cafeteria Storage	Yes	W2	Concrete	Beige	Partially Inaccessible	0	N/A	N/A		0	Negative								
1	1	119	Cafeteria Storage	Yes	W3	Concrete	Beige	Partially Inaccessible	0	N/A	N/A	N/A	Negative								Same Wall System as Tested Wall	
1	1	119	Cafeteria Storage	Yes	W4	Concrete	Beige	None	0	N/A	N/A	N/A	Negative								Same Wall System as Tested Wall	
1	1	119	Cafeteria Storage	Yes	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A									
1	1	119	Cafeteria Storage	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A									
1	1	119	Cafeteria Storage	Yes	Door Frame	Metal	Green	None	0	N/A	N/A		0	Negative								
1	B	S11	Stairs to Basement		W1																	
1	B	S11	Stairs to Basement	Yes	W2																	
1	B	S11	Stairs to Basement	Yes	W3																	
1	B	S11	Stairs to Basement	Yes	W4																	
1	B	S11	Stairs to Basement	Yes	Ceiling	Tan				0.15	Negative	N/A	N/A									
1	B	S11	Stairs to Basement	Yes	Floor	N/A			N/A	N/A	N/A	N/A	N/A									
1	1	S22	Hallway Stairs adjacent to Classroom 200	Yes	W1																	
1	1	S22	Hallway Stairs adjacent to Classroom 200	Yes	W2																	
1	1	S22	Hallway Stairs adjacent to Classroom 200	Yes	W3																	
1	1	S22	Hallway Stairs adjacent to Classroom 200	Yes	W4																	
1	1	S22	Hallway Stairs adjacent to Classroom 200	Yes	Ceiling	Tan				<0.016	Negative	N/A	N/A									
1	1	S22	Hallway Stairs adjacent to Classroom 200	Yes	Floor	N/A			N/A	N/A	N/A	N/A	N/A									
1	1	S21	Hallway Stairs adjacent to Classroom 214	Yes	W1	Concrete	Beige	None	0	N/A	N/A	N/A	N/A									
1	1	S21	Hallway Stairs adjacent to Classroom 214	Yes	W2	Concrete	Beige	None	0	N/A	N/A	N/A	N/A									
1	1	S21	Hallway Stairs adjacent to Classroom 214	Yes	W3	Concrete	Beige	None	0	N/A	N/A	N/A	N/A									
1	1	S21	Hallway Stairs adjacent to Classroom 214	Yes	W4	Concrete	Beige	None	0	N/A	N/A	N/A	N/A									
1	1	S21	Hallway Stairs adjacent to Classroom 214	Yes	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A									
1	1	S21	Hallway Stairs adjacent to Classroom 214	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A									
1	1	S21	Hallway Stairs adjacent to Classroom 214	Yes	Door Frame	Metal	Brown	Friction	0	N/A	N/A		0.03	Negative								
1	1	S02	Hallway Stairs adjacent to Classroom 99	Yes	W1	Concrete	Beige	None	0	N/A	N/A	N/A	N/A									
1	1	S02	Hallway Stairs adjacent to Classroom 99	Yes	W2	Concrete	Beige	None	0	N/A	N/A	N/A	N/A									
1	1	S02	Hallway Stairs adjacent to Classroom 99	Yes	W3	Concrete	Beige	None	0	N/A	N/A	N/A	N/A									
1	1	S02	Hallway Stairs adjacent to Classroom 99	Yes	W4	Concrete	Beige	None	0	N/A	N/A	N/A	N/A									
1	1	S02	Hallway Stairs adjacent to Classroom 99	Yes	Ceiling	Tan	White	None	0	0.051	Negative	N/A	N/A									
1	1	S02	Hallway Stairs adjacent to Classroom 99	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A									
1	1	S02	Hallway Stairs adjacent to Classroom 99	Yes	Door Frame	Metal	Brown	Friction	1	N/A	N/A		0.05	Negative								
				Yes	Ventilation System	Metal	Tan	Friction	0	N/A	N/A		0	Negative								
1	1	S02	Hallway Stairs adjacent to Classroom 99	Yes	Exit Door Frame	Metal	Brown	Friction	1	N/A	N/A		0.1	Negative								
1	1	S02	Hallway Stairs adjacent to Classroom 99	Yes	Exit Door	Metal	Brown	Friction	1	N/A	N/A		0	Negative								
1	1	S02	Hallway Stairs adjacent to Classroom 99	Yes	Stairs	Metal	Brown	Friction	1	N/A	N/A		0.02	Negative								
1	1	S13	Hallway Stairs adjacent to Classroom 106	Yes	W1	Concrete	Beige	None	0	N/A	N/A	N/A	N/A									
1	1	S13	Hallway Stairs adjacent to Classroom 106	Yes	W2	Concrete	Beige	None	0	N/A	N/A	N/A	N/A									
1	1	S13	Hallway Stairs adjacent to Classroom 106	Yes	W3	Concrete	Beige	Flaking														
1	1	S13	Hallway Stairs adjacent to Classroom 106	Yes	W4	Concrete	Beige	None	0	N/A	N/A	N/A	N/A									
1	1	S13	Hallway Stairs adjacent to Classroom 106	Yes	Ceiling	Concrete	White	None	0	0.078	Negative	N/A	N/A									
1	1	S13	Hallway Stairs adjacent to Classroom 106	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A									
				Yes	Ventilation System	Metal	Brown	Friction	0	N/A	N/A		0	Negative								
1	1	S13	Hallway Stairs adjacent to Classroom 106	Yes	Exit Door Frame	Metal	Brown	Friction	1	N/A	N/A		0.05	Negative								
1	1	S13	Hallway Stairs adjacent to Classroom 106	Yes	Door Frame	Metal	Brown	Friction	1	N/A	N/A		0.11	Negative								
1	1	S23	Hallway Stairs adjacent to Classroom 208	Yes	W1	Concrete	Beige	None	0	N/A	N/A		0.06	Negative							Same Wall System as Tested Wall	
1	1	S23	Hallway Stairs adjacent to Classroom 208	Yes	W2	Concrete	Beige	None	0	N/A	N/A	N/A	Negative								Same Wall System as Tested Wall	
1	1	S23	Hallway Stairs adjacent to Classroom 208	Yes	W3	Concrete	Beige	None	0	N/A	N/A	N/A	Negative								Same Wall System as Tested Wall	
1	1	S23	Hallway Stairs adjacent to Classroom 208	Yes	W4	Concrete	Beige	None	0	N/A	N/A	N/A	Negative								Same Wall System as Tested Wall	
1	1	S23	Hallway Stairs adjacent to Classroom 208	Yes	Ceiling	Concrete	White	None	0	0.085	Negative	N/A	N/A									
1	1	S23	Hallway Stairs adjacent to Classroom 208	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A									
1	1	S23	Hallway Stairs adjacent to Classroom 208	Yes	Door Frame	Metal	Brown	Friction	0	N/A	N/A		0	Negative								
1	1	S31	Hallway Stairs adjacent to Classroom 314	Yes	W1																	
1	1	S31	Hallway Stairs adjacent to Classroom 314	Yes	W2																	
1	1	S31	Hallway Stairs adjacent to Classroom 314	Yes	W3																	
1	1	S31	Hallway Stairs adjacent to Classroom 314	Yes	W4																	
1	1	S31	Hallway Stairs adjacent to Classroom 314	Yes	Ceiling	Tan				0.022	Negative	N/A	N/A									
1	1	S31	Hallway Stairs adjacent to Classroom 314	Yes	Floor	N/A			N/A	N/A	N/A	N/A	N/A									
1	B	H01	Basement Hallway	No	W1																	
1	B	H01	Basement Hallway	No	W2																	
1	B	H01	Basement Hallway	No	W3																	
1	B	H01	Basement Hallway	No	W4																	
1	B	H01	Basement Hallway	No	Ceiling																	
1	B	H01	Basement Hallway	No	Floor					</												

			School District of Philadelphia																				
			Name of Inspectors: Shalaunda Gourdine, Suzanne Shourds, James Arbuckle, Ted Mosher			Lead Safe Certification Assessment Report										Inspection Dates: 4/5/2021-4/28/2021							
			Inspection Company: REPSG, Inc			James Blaine Elementary School										ULCS# 4220							
E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	Lead Concentration (% wt)	Lead in Paint Chips by Flame AAS Analysis Results (positive / negative)	XRF Reading (mg/cm2)	XRF (positive/ negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes		
1	B	003	Storage Room B-3	No	W1																		
1	B	003	Storage Room B-3	No	W2																		
1	B	003	Storage Room B-3	No	W3																		
1	B	003	Storage Room B-3	No	W4																		
1	B	003	Storage Room B-3	No	Ceiling																		
1	B	003	Storage Room B-3	No	Floor																		
1	B	005	Staff Restroom	No	W1																		
1	B	005	Staff Restroom	No	W2																		
1	B	005	Staff Restroom	No	W3																		
1	B	005	Staff Restroom	No	W4																		
1	B	005	Staff Restroom	No	Ceiling																		
1	B	005	Staff Restroom	No	Floor																		
1	B	004	Building Engineer's Office	No	W1																		
1	B	004	Building Engineer's Office	No	W2																		
1	B	004	Building Engineer's Office	No	W3																		
1	B	004	Building Engineer's Office	No	W4																		
1	B	004	Building Engineer's Office	No	Ceiling																		
1	B	004	Building Engineer's Office	No	Floor																		
1	B	004A	Building Engineer's Office Restroom	No	W1																		
1	B	004A	Building Engineer's Office Restroom	No	W2																		
1	B	004A	Building Engineer's Office Restroom	No	W3																		
1	B	004A	Building Engineer's Office Restroom	No	W4																		
1	B	004A	Building Engineer's Office Restroom	No	Ceiling																		
1	B	004A	Building Engineer's Office Restroom	No	Floor																		
1	B	001	Boiler Room	No	W1																		
1	B	001	Boiler Room	No	W2																		
1	B	001	Boiler Room	No	W3																		
1	B	001	Boiler Room	No	W4																		
1	B	001	Boiler Room	No	Ceiling																		
1	B	001	Boiler Room	No	Floor																		
1	2	217B	Classroom 217 Closet B	Yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access										
1	2	217B	Classroom 217 Closet B	Yes	Door Frame	Metal	Tan	Friction	0	N/A			0 Negative										