

					School District of Philadelphia														
			Name of Inspector: Suzanne Shourds and Shalaunda Gourdine		Lead Safe Certification Assessment Report							Inspection Dates: 9/20-29/2021							
			Inspection Company: React		Farrell School							ULCS# 8380							
E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes
1	BS	002	Building Engineer's Office	yes	W1	Concrete	Green	Chipping	1	0.04	Negative	None	None						
1	BS	002	Building Engineer's Office	yes	W2	Concrete	White	None	0	N/A	N/A	None	None						
1	BS	002	Building Engineer's Office	yes	W3	Concrete	White	None	0	N/A	N/A	None	None						
1	BS	002	Building Engineer's Office	yes	W4	Concrete	Green	None	0	0.036	Negative	None	None						
1	BS	002	Building Engineer's Office	yes	Ceiling	Concrete	White	None	0	0.056	Negative	None	None						
1	BS	002	Building Engineer's Office	yes	Floor	Concrete	Grey	None	0		Negative	None	None						
1	BS	003	Storage Room adjacent to Building Engineer's Office	yes	W1	Concrete	Yellow/Green	Partially Inaccessible	0	N/A	N/A	None	None						
1	BS	003	Storage Room adjacent to Building Engineer's Office	yes	W2	Concrete	Yellow/Green	Partially Inaccessible	0	0.06	Negative	None	None						
1	BS	003	Storage Room adjacent to Building Engineer's Office	yes	W3	Concrete	Yellow/Green	Partially Inaccessible	0	0.088	Negative	None	None						
1	BS	003	Storage Room adjacent to Building Engineer's Office	yes	W4	Concrete	Yellow	Partially Inaccessible	0	N/A	N/A	None	None						
1	BS	003	Storage Room adjacent to Building Engineer's Office	yes	Ceiling	Concrete	White	Partially Inaccessible	0	N/A	N/A	None	None						
1	BS	003	Storage Room adjacent to Building Engineer's Office	yes	Floor	Concrete	Red	Friction	4	0	Negative	None	None						
1	BS	Elevator	Elevator	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	None	None						Plastic and unpainted metal
1	BS	Elevator	Elevator	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A	None	None						Plastic and unpainted metal
1	BS	Elevator	Elevator	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A	None	None						Plastic and unpainted metal
1	BS	Elevator	Elevator	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A	None	None						Plastic and unpainted metal
1	BS	Elevator	Elevator	yes	Ceiling	Metal	Cream	None	0	N/A	N/A	None	None						
1	BS	Elevator	Elevator	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	None						12x12 Floor tile
1	BS	002A	Elevator Mechanical Room adjacent to Building Engineer's Office	yes	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	BS	002A	Elevator Mechanical Room adjacent to Building Engineer's Office	yes	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	BS	002A	Elevator Mechanical Room adjacent to Building Engineer's Office	yes	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	BS	002A	Elevator Mechanical Room adjacent to Building Engineer's Office	yes	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	BS	002A	Elevator Mechanical Room adjacent to Building Engineer's Office	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	BS	002A	Elevator Mechanical Room adjacent to Building Engineer's Office	yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	BS	004	Storage Area adjacent to Boiler Room	yes	W1	Concrete	White	Partially Inaccessible	0	0.043	Negative	None	None						
1	BS	004	Storage Area adjacent to Boiler Room	yes	W2	Concrete	White	Partially Inaccessible	0	N/A	N/A	None	None						
1	BS	004	Storage Area adjacent to Boiler Room	yes	W3	Concrete	White	Partially Inaccessible	0	0.049	Negative	None	None						
1	BS	004	Storage Area adjacent to Boiler Room	yes	W4	Concrete	White	Partially Inaccessible	0	N/A	N/A	None	None						
1	BS	004	Storage Area adjacent to Boiler Room	yes	Ceiling	Concrete	Yellow	None	0	N/A	N/A	None	None						
1	BS	004	Storage Area adjacent to Boiler Room	yes	Floor	Concrete	Grey	Friction	5	0	Negative	None	None						
1	BS	S001	Stairwell to Boiler Room	yes	W1	Concrete / Ceramic	Cream	None	0	N/A	N/A	None	None						
1	BS	S001	Stairwell to Boiler Room	yes	W2	Concrete	Cream/Green	Chipping	2	0.091	Negative	None	None						
1	BS	S001	Stairwell to Boiler Room	yes	W3	Concrete	Cream	Flaking	4	0.062	Negative	None	None						
1	BS	S001	Stairwell to Boiler Room	yes	W4	Concrete	Cream	None	0	0.072	Negative	None	None						
1	BS	S001	Stairwell to Boiler Room	yes	Ceiling	Concrete	White	None	0	N/A	N/A	None	None						
1	BS	S001	Stairwell to Boiler Room	yes	Floor	Concrete	Red	Friction	5	0	Negative	None	None						
1	BS	S001	Stairwell to Boiler Room	yes	Stair Railing	Metal	Tan	None	0	0.114	Negative	None	None						
1	BS	S001	Stairwell to Boiler Room	yes	Stair Riser	Metal	Tan	Chipping	1	0.066	Negative	None	None						
1	BS	S001	Stairwell to Boiler Room	yes	Stair Riser	Metal	Green	None	0	0.059	Negative	None	None						
1	BS	001	Boiler Room	no	W1	Concrete	White/Pink	Chipping	2	0.096	Negative	None	None						No longer a separate room. Combined with Transformer Room 005
1	BS	001	Boiler Room	no	W2	Concrete	White/Pink	Chipping	8	0.087	Negative	None	None						No longer a separate room. Combined with Transformer Room 005
1	BS	001	Boiler Room	no	W3	Concrete	White/Pink	Chipping	4	0.083	Negative	None	None						No longer a separate room. Combined with Transformer Room 005
1	BS	001	Boiler Room	no	W4	Concrete	White/Pink	Chipping	4	0.113	Negative	None	None						No longer a separate room. Combined with Transformer Room 005
1	BS	001	Boiler Room	no	Piping	Concrete	White	Cracking	2	0.037	Negative	None	None						No longer a separate room. Combined with Transformer Room 005
1	BS	001	Boiler Room	no	Ceiling	Metal	White	Cracking	2	0.021	Negative	None	None						No longer a separate room. Combined with Transformer Room 005
1	BS	001	Boiler Room	no	Floor	Concrete	Red	Friction	10	0	Negative	None	None						No longer a separate room. Combined with Transformer Room 005
1	BS	005	Transformer Room	no	W1	Concrete	White/Pink	Chipping	2	0.096	Negative	None	None						No longer a separate room. Combined with Boiler Room 001
1	BS	005	Transformer Room	no	W2	Concrete	White/Pink	Chipping	8	0.087	Negative	None	None						No longer a separate room. Combined with Boiler Room 001
1	BS	005	Transformer Room	no	W3	Concrete	White/Pink	Chipping	4	0.083	Negative	None	None						No longer a separate room. Combined with Boiler Room 001
1	BS	005	Transformer Room	no	W4	Concrete	White/Pink	Chipping	4	0.113	Negative	None	None						No longer a separate room. Combined with Boiler Room 001
1	BS	005	Transformer Room	no	Ceiling	Concrete	White	Cracking	2	0.021	Negative	None	None						No longer a separate room. Combined with Boiler Room 001
1	BS	005	Transformer Room	no	Floor	Concrete	Red	Friction	10	0	Negative	None	None						No longer a separate room. Combined with Boiler Room 001
1	1	S3N	Stairwell near Rooms 112 and 113	yes	W1	Concrete / Ceramic	Beige	None	0	N/A	N/A	None	None						
1	1	S3N	Stairwell near Rooms 112 and 113	yes	W2	Concrete / Ceramic	Beige	None	0	N/A	N/A	None	None						
1	1	S3N	Stairwell near Rooms 112 and 113	yes	W3	Concrete / Ceramic	Beige	Chipping	6	0.06	Negative	None	None						
1	1	S3N	Stairwell near Rooms 112 and 113	yes	W4	Concrete / Ceramic	Beige	Friction	14	0.06	Negative	None	None						
1	1	S3N	Stairwell near Rooms 112 and 113	yes	Ceiling	Concrete	White	Chipping	12	0.04	Negative	None	None						
1	1	S3N	Stairwell near Rooms 112 and 113	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	None						Terracotta Tile

			Name of Inspector: Suzanne Shourds and Shalaunda Gourdine		Lead Safe Certification Assessment Report							Inspection Dates: 9/20-29/2021							
			Inspection Company: React		Farrell School							ULCS# 8380							
E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes
1	1	S3N	Stairwell near Rooms 112 and 113	yes	Stair Railing	Metal	Tan	None	0	N/A	N/A	None	None						
1	1	S3N	Stairwell near Rooms 112 and 113	yes	Stair Riser	Metal	Gray	Chipping	6	0.04	Negative	None	None						
1	1	S3N	Stairwell near Rooms 112 and 113	yes	Stair Riser	Metal	Tan	Moisture Damage	6	0.11	Negative	None	None						
1	1	112	Classroom 112	yes	W1	Concrete/ Sheetrock	Yellow	Friction	1	0	Negative	None	None						
1	1	112	Classroom 112	yes	W2	Concrete	Yellow	None	0	0	Negative	None	None						
1	1	112	Classroom 112	yes	W3	Concrete	Yellow	Chipping	2	0	Negative	None	None						
1	1	112	Classroom 112	yes	W4	Concrete/ Sheetrock	Yellow	Chipping	1	0	Negative	None	None						
1	1	112	Classroom 112	yes	Radiator	Metal	Tan	None	0	N/A	N/A	None	None						12x12 Tiles
1	1	112	Classroom 112	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	None						12x12 Tiles
1	1	112	Classroom 112	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	None						
1	1	112B	Classroom 112 - Closet	yes	W1	Concrete	Yellow	None	0	N/A	N/A	None	None						
1	1	112B	Classroom 112 - Closet	yes	W2	Concrete	Yellow	None	0	N/A	N/A	None	None						
1	1	112B	Classroom 112 - Closet	yes	W3	Concrete	Yellow	None	0	N/A	N/A	None	None						
1	1	112B	Classroom 112 - Closet	yes	W4	Concrete	Yellow	None	0	N/A	N/A	None	None						
1	1	112B	Classroom 112 - Closet	yes	Ceiling	Sheetrock	Yellow	None	0	N/A	N/A	None	None						
1	1	112B	Classroom 112 - Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	None						
1	1	112A	Classroom 112 Restroom	yes	W1	Sheetrock	Yellow	None	0	N/A	N/A	None	None						
1	1	112A	Classroom 112 Restroom	yes	W2	Sheetrock	Yellow	Chipping	1	0	Negative	None	None						
1	1	112A	Classroom 112 Restroom	yes	W3	Concrete	Yellow	None	0	N/A	N/A	None	None						
1	1	112A	Classroom 112 Restroom	yes	W4	Concrete	Yellow	Chipping	1	0	Negative	None	None						
1	1	112A	Classroom 112 Restroom	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	None						
1	1	112A	Classroom 112 Restroom	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	None						
1	1	113	Classroom 113	yes	W1	Concrete	Blue	Chipping	1	0.05	Negative	None	None						Cracks in CMU Blocks
1	1	113	Classroom 113	yes	W2	Concrete	Blue	None	0	N/A	N/A	None	None						
1	1	113	Classroom 113	yes	W3	Concrete	Blue	None	0	N/A	N/A	None	None						
1	1	113	Classroom 113	yes	W4	Concrete	Blue	None	0	N/A	N/A	None	None						
1	1	113	Classroom 113	yes	Radiator	Metal	Tan	Friction	2	0.03	Negative	None	None						
1	1	113	Classroom 113	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	None						12x12 Ceiling Tile
1	1	113	Classroom 113	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	None						9x9 FT
1	1	113B	Classroom 113 - Closet	yes	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	1	113B	Classroom 113 - Closet	yes	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	1	113B	Classroom 113 - Closet	yes	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	1	113B	Classroom 113 - Closet	yes	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	1	113B	Classroom 113 - Closet	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	1	113B	Classroom 113 - Closet	yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	1	113A	Classroom 113 Restroom	yes	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	1	113A	Classroom 113 Restroom	yes	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	1	113A	Classroom 113 Restroom	yes	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	1	113A	Classroom 113 Restroom	yes	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	1	113A	Classroom 113 Restroom	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	1	113A	Classroom 113 Restroom	yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	1	115	Teacher's Lounge 110	yes	W1	Concrete	Yellow	None	0	N/A	N/A	None	None						
1	1	115	Teacher's Lounge 110	yes	W2	Concrete	Yellow	None	0	N/A	N/A	None	None						
1	1	115	Teacher's Lounge 110	yes	W3	Concrete/ Sheetrock	Yellow	Cracking	2	0.07	Negative	None	None						
1	1	115	Teacher's Lounge 110	yes	W4	Concrete	Yellow	None	0	N/A	N/A	None	None						
1	1	115	Teacher's Lounge 110	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	None						12x12 Ceiling Tile
1	1	115	Teacher's Lounge 110	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	None						
1	1	115A	Room 115 Storage	yes	W1	Concrete/ Sheetrock	Yellow	None	0	N/A	N/A	None	None						
1	1	115A	Room 115 Storage	yes	W2	Concrete	Yellow	None	0	N/A	N/A	None	None						
1	1	115A	Room 115 Storage	yes	W3	Concrete	Yellow	None	0	N/A	N/A	None	None						
1	1	115A	Room 115 Storage	yes	W4	Concrete	Yellow	None	0	N/A	N/A	None	None						
1	1	115A	Room 115 Storage	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	None						12x12 Ceiling Tile
1	1	115A	Room 115 Storage	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	None						
1	1	111	Classroom 111	yes	W1	Concrete	Yellow	Chipping	2	0.09	Negative	None	None						
1	1	111	Classroom 111	yes	W2	Concrete	Yellow	None	0	N/A	N/A	None	None						
1	1	111	Classroom 111	yes	W3	Concrete	Yellow	Moisture Damage	2	0.13	Negative	None	None						
1	1	111	Classroom 111	yes	W4	Concrete	Yellow	None	0	N/A	N/A	None	None						Cracks in CMU Blocks
1	1	111	Classroom 111	yes	Radiator	Metal	Tan	Friction	2	0.02	Negative	None	None						
1	1	111	Classroom 111	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	None						12x12 Ceiling Tile
1	1	111	Classroom 111	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	None						9x9 FT
1	1	111A	Classroom 111 - Closet	yes	W1	Concrete	Yellow	Partially Inaccessible	0	N/A	N/A	None	None						
1	1	111A	Classroom 111 - Closet	yes	W2	Concrete	Yellow	Partially Inaccessible	0	N/A	N/A	None	None						
1	1	111A	Classroom 111 - Closet	yes	W3	Concrete	Yellow	Partially Inaccessible	0	0.08	Negative	None	None						
1	1	111A	Classroom 111 - Closet	yes	W4	Concrete	Yellow	Partially Inaccessible	0	N/A	N/A	None	None						
1	1	111A	Classroom 111 - Closet	yes	Ceiling	Sheetrock	Yellow	None	0	N/A	N/A	None	None						
1	1	111A	Classroom 111 - Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	None						9x9 FT
1	1	S3S	Stairwell by Classrooms 100 and 101	yes	W1	Concrete / Ceramic	Beige	None	0	N/A	N/A	None	None						
1	1	S3S	Stairwell by Classrooms 100 and 101	yes	W2	Concrete / Ceramic	Beige	Cracking	8	0.05	Negative	None	None						
1	1	S3S	Stairwell by Classrooms 100 and 101	yes	W3	Concrete / Ceramic	Beige	None	0	N/A	N/A	None	None						
1	1	S3S	Stairwell by Classrooms 100 and 101	yes	W4	Concrete / Ceramic	Beige	Cracking	6	0.02	Negative	None	None						
1	1	S3S	Stairwell by Classrooms 100 and 101	yes	Ceiling	Concrete	White	Chipping	4	0.02	Negative	None	None						
1	1	S3S	Stairwell by Classrooms 100 and 101	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	None						Terracotta Tile
1	1	S3S	Stairwell by Classrooms 100 and 101	yes	Stair Railing	Metal	Tan	Friction	3	0.19	Negative	None	None						

					School District of Philadelphia														
			Name of Inspector: Suzanne Shourds and Shalaunda Gourdine		Lead Safe Certification Assessment Report							Inspection Dates: 9/20-29/2021							
			Inspection Company: React		Farrell School							ULCS# 8380							
E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes
1	1	S3S	Stairwell by Classrooms 100 and 101	yes	Stair Riser	Metal	Gray	Chipping	1	0.08	Negative	None	None						
1	1	S3S	Stairwell by Classrooms 100 and 101	yes	Stair Riser	Metal	Tan	N/A	N/A	N/A	N/A	None	None						
1	1	101	Classroom 101	yes	W1	Concrete	Orange / Gray	None	0	N/A	N/A	None	None						
1	1	101	Classroom 101	yes	W2	Concrete	Gray	None	0	N/A	N/A	None	None						
1	1	101	Classroom 101	yes	W3	Concrete	Gray	None	0	N/A	N/A	None	None						
1	1	101	Classroom 101	yes	W4	Concrete	Gray	None	0	N/A	N/A	None	None						
1	1	101	Classroom 101	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	None						2x4 Ceiling Tile
1	1	101	Classroom 101	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	None						12x12 FT
1	1	101CL	Classroom 101 - Center Closet	yes	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	1	101CL	Classroom 101 - Center Closet	yes	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	1	101CL	Classroom 101 - Center Closet	yes	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	1	101CL	Classroom 101 - Center Closet	yes	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	1	101CL	Classroom 101 - Center Closet	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	1	101CL	Classroom 101 - Center Closet	yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	1	101B	Classroom 101 Restroom	yes	W1	Concrete / Ceramic	White	None	0	N/A	N/A	None	None						
1	1	101B	Classroom 101 Restroom	yes	W2	Concrete / Ceramic	White	None	0	N/A	N/A	None	None						
1	1	101B	Classroom 101 Restroom	yes	W3	Concrete / Ceramic	White	None	0	N/A	N/A	None	None						
1	1	101B	Classroom 101 Restroom	yes	W4	Concrete / Ceramic	White	None	0	N/A	N/A	None	None						
1	1	101B	Classroom 101 Restroom	yes	Ceiling	Sheetrock	White	None	0	N/A	N/A	None	None						
1	1	101B	Classroom 101 Restroom	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	None						Ceramic Tile
1	1	101A	Classroom 101 Coat Room	yes	W1	Concrete	Gray	None	0	N/A	N/A	None	None						
1	1	101A	Classroom 101 Coat Room	yes	W2	Concrete	Gray	None	0	N/A	N/A	None	None						
1	1	101A	Classroom 101 Coat Room	yes	W3	Concrete	Gray	None	0	N/A	N/A	None	None						
1	1	101A	Classroom 101 Coat Room	yes	W4	Concrete	Gray	None	0	N/A	N/A	None	None						
1	1	101A	Classroom 101 Coat Room	yes	Ceiling	Sheetrock	Gray	None	0	N/A	N/A	None	None						
1	1	101A	Classroom 101 Coat Room	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	None						12x12 FT
1	1	100C	Classroom 101 Storage	yes	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	1	100C	Classroom 101 Storage	yes	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	1	100C	Classroom 101 Storage	yes	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	1	100C	Classroom 101 Storage	yes	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	1	100C	Classroom 101 Storage	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	1	100C	Classroom 101 Storage	yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	1	100	Classroom 100	yes	W1	Concrete	Orange / Gray	None	0	N/A	N/A	None	None						
1	1	100	Classroom 100	yes	W2	Concrete	Gray	None	0	N/A	N/A	None	None						
1	1	100	Classroom 100	yes	W3	Concrete	Gray	None	0	N/A	N/A	None	None						
1	1	100	Classroom 100	yes	W4	Concrete	Gray	None	0	N/A	N/A	None	None						
1	1	100	Classroom 100	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	None						2x4 Ceiling Tile
1	1	100	Classroom 100	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	None						12x12 FT
1	1	100CL	Classroom 100 - Center Closet	yes	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	1	100CL	Classroom 100 - Center Closet	yes	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	1	100CL	Classroom 100 - Center Closet	yes	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	1	100CL	Classroom 100 - Center Closet	yes	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	1	100CL	Classroom 100 - Center Closet	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	1	100CL	Classroom 100 - Center Closet	yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	1	100B	Classroom 100 Restroom	yes	W1	Concrete / Ceramic	White	None	0	N/A	N/A	None	None						
1	1	100B	Classroom 100 Restroom	yes	W2	Concrete / Ceramic	White	None	0	N/A	N/A	None	None						
1	1	100B	Classroom 100 Restroom	yes	W3	Concrete / Ceramic	White	None	0	N/A	N/A	None	None						
1	1	100B	Classroom 100 Restroom	yes	W4	Concrete / Ceramic	White	None	0	N/A	N/A	None	None						
1	1	100B	Classroom 100 Restroom	yes	Ceiling	Sheetrock	White	None	0	N/A	N/A	None	None						
1	1	100B	Classroom 100 Restroom	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	None						Ceramic Tile
1	1	100A	Classroom 100 Coat Room	yes	W1	Concrete	Gray	None	0	N/A	N/A	None	None						
1	1	100A	Classroom 100 Coat Room	yes	W2	Concrete	Gray	None	0	N/A	N/A	None	None						
1	1	100A	Classroom 100 Coat Room	yes	W3	Concrete	Gray	None	0	N/A	N/A	None	None						
1	1	100A	Classroom 100 Coat Room	yes	W4	Concrete	Gray	None	0	N/A	N/A	None	None						
1	1	100A	Classroom 100 Coat Room	yes	Ceiling	Sheetrock	Gray	None	0	N/A	N/A	None	None						
1	1	100A	Classroom 100 Coat Room	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	None						12x12 FT
1	1	102A	Classroom 100 Storage	yes	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	1	102A	Classroom 100 Storage	yes	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	1	102A	Classroom 100 Storage	yes	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	1	102A	Classroom 100 Storage	yes	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	1	102A	Classroom 100 Storage	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	1	102A	Classroom 100 Storage	yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	1	103	Classroom 103	yes	W1	Concrete	Gray	None	0	N/A	N/A	None	None						
1	1	103	Classroom 103	yes	W2	Concrete	Gray	None	0	N/A	N/A	None	None						
1	1	103	Classroom 103	yes	W3	Concrete	Gray	None	0	N/A	N/A	None	None						
1	1	103	Classroom 103	yes	W4	Concrete	Orange	None	0	N/A	N/A	None	None						
1	1	103	Classroom 103	yes	Radiator	Metal	Gray	Chipping	1	0	Negative	None	None						
1	1	103	Classroom 103	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	None						
1	1	103	Classroom 103	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	None						2x4 Ceiling Tile
1	1	103A	Classroom 103 - Closet	yes	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	12x12 FT
1	1	103A	Classroom 103 - Closet	yes	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	1	103A	Classroom 103 - Closet	yes	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	1	103A	Classroom 103 - Closet	yes	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	

					School District of Philadelphia															
			Name of Inspector: Suzanne Shourds and Shalaunda Gourdine		Lead Safe Certification Assessment Report							Inspection Dates: 9/20-29/2021								
			Inspection Company: React		Farrell School							ULCS# 8380								
E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes	
1	1	103A	Classroom 103 - Closet	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access		
1	1	103A	Classroom 103 - Closet	yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access		
1	1	102	Counselor's Office C-1	yes	W1	Concrete	Light blue	None	0	N/A	N/A	None	None							
1	1	102	Counselor's Office C-1	yes	W2	Concrete	Light blue	None	0	N/A	N/A	None	None							
1	1	102	Counselor's Office C-1	yes	W3	Concrete	Light blue	None	0	N/A	N/A	None	None							
1	1	102	Counselor's Office C-1	yes	W4	Concrete	Light blue	None	0	N/A	N/A	None	None							
1	1	102	Counselor's Office C-1	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	None						12"x12" ceiling tile	
1	1	102	Counselor's Office C-1	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	None							
1	1	PC102	Pipe Chase in Counselor's Office C-1	no	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access		
1	1	PC102	Pipe Chase in Counselor's Office C-1	no	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access		
1	1	PC102	Pipe Chase in Counselor's Office C-1	no	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access		
1	1	PC102	Pipe Chase in Counselor's Office C-1	no	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access		
1	1	PC102	Pipe Chase in Counselor's Office C-1	no	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access		
1	1	PC102	Pipe Chase in Counselor's Office C-1	no	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access		
1	1	102C	Women's Restroom across from Classroom 103	yes	W1	Concrete / Ceramic	Pink	None	0	N/A	N/A	None	None							
1	1	102C	Women's Restroom across from Classroom 103	yes	W2	Concrete / Ceramic	Pink	None	0	N/A	N/A	None	None							
1	1	102C	Women's Restroom across from Classroom 103	yes	W3	Concrete / Ceramic	Pink	None	0	N/A	N/A	None	None							
1	1	102C	Women's Restroom across from Classroom 103	yes	W4	Concrete / Ceramic	Pink	Cracking	3	0.09	Negative	None	None							
1	1	102C	Women's Restroom across from Classroom 103	yes	Ceiling	Sheetrock	Beige	Moisture Damage	4	0.03	Negative	None	None							
1	1	102C	Women's Restroom across from Classroom 103	yes	Floor	Ceramic	N/A	N/A	N/A	N/A	N/A	None	None							
1	1	102B	Boy's Restroom near Classroom 103	yes	W1	Concrete / Ceramic	Beige	Cracking	2	0.03	Negative	None	None							
1	1	102B	Boy's Restroom near Classroom 103	yes	W2	Concrete / Ceramic	Beige	Cracking	5	0.03	Negative	None	None							
1	1	102B	Boy's Restroom near Classroom 103	yes	W3	Concrete / Ceramic	Beige	Cracking	4	0.04	Negative	None	None							
1	1	102B	Boy's Restroom near Classroom 103	yes	W4	Concrete / Ceramic	Beige	Cracking	5	0.04	Negative	None	None							
1	1	102B	Boy's Restroom near Classroom 103	yes	Ceiling	Sheetrock	Beige	Cracking	40	0.07	Negative	None	None							
1	1	102B	Boy's Restroom near Classroom 103	yes	Floor	Ceramic	N/A	N/A	N/A	N/A	N/A	None	None							
1	1	S3W	Stairwell across from Classroom 105	yes	W1	Concrete / Ceramic	Beige	None	0	N/A	N/A	None	None							
1	1	S3W	Stairwell across from Classroom 105	yes	W2	Concrete / Ceramic	Beige	Friction	2	0.08	Negative	None	None							
1	1	S3W	Stairwell across from Classroom 105	yes	W3	Concrete / Ceramic	Beige	Chipping	4	0.03	Negative	None	None							
1	1	S3W	Stairwell across from Classroom 105	yes	W4	Concrete / Ceramic	Beige	Friction	4	0.08	Negative	None	None							
1	1	S3W	Stairwell across from Classroom 105	yes	Ceiling	Concrete	White	Chipping	6	0.01	Negative	None	None							
1	1	S3W	Stairwell across from Classroom 105	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	None						Terracotta Tile	
1	1	S3W	Stairwell across from Classroom 105	yes	Stair Railing	Metal	Tan	None	0	N/A	N/A	None	None							
1	1	S3W	Stairwell across from Classroom 105	yes	Stair Riser	Metal	Green	Chipping	2	0.05	Negative	None	None							
1	1	S3W	Stairwell across from Classroom 105	yes	Stair Riser	Metal	Tan	Chipping	32	0.07	Negative	None	None							
1	1	105	Classroom 105	yes	W1	Concrete	Green	Friction	2	0.04	Negative	None	None							
1	1	105	Classroom 105	yes	W2	Concrete	Green	Flaking	10	0	Negative	None	None							
1	1	105	Classroom 105	yes	W3	Concrete	Green	None	0	N/A	N/A	None	None							
1	1	105	Classroom 105	yes	W4	Concrete	Green	None	0	N/A	N/A	None	None							
1	1	105	Classroom 105	yes	Radiator	Metal	Tan	None	0	N/A	N/A	None	None							
1	1	105	Classroom 105	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	None						12x12 Ceiling Tile	
1	1	105	Classroom 105	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	None						9x9 FT	
1	1	105A	Classroom 105 Storage Closet	yes	W1	Concrete	Beige	None	0	N/A	N/A	None	None							
1	1	105A	Classroom 105 Storage Closet	yes	W2	Concrete	Beige	None	0	N/A	N/A	None	None							
1	1	105A	Classroom 105 Storage Closet	yes	W3	Concrete	Beige	None	0	N/A	N/A	None	None							
1	1	105A	Classroom 105 Storage Closet	yes	W4	Concrete	Beige	None	0	N/A	N/A	None	None							
1	1	105A	Classroom 105 Storage Closet	yes	Ceiling	Sheetrock	Beige	None	0	N/A	N/A	None	None							
1	1	105A	Classroom 105 Storage Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	None						9x9 FT	
1	1	104	Girl's Restroom across from Classroom 105	yes	W1	Concrete / Ceramic	Beige	None	0	N/A	N/A	None	None							
1	1	104	Girl's Restroom across from Classroom 105	yes	W2	Concrete / Ceramic	Beige	None	0	N/A	N/A	None	None							
1	1	104	Girl's Restroom across from Classroom 105	yes	W3	Concrete / Ceramic	Beige	None	0	N/A	N/A	None	None							
1	1	104	Girl's Restroom across from Classroom 105	yes	W4	Concrete / Ceramic	Beige	None	0	N/A	N/A	None	None							
1	1	104	Girl's Restroom across from Classroom 105	yes	Ceiling	Sheetrock	Beige	Cracking	20	0.05	Negative	None	None							
1	1	104	Girl's Restroom across from Classroom 105	yes	Floor	Ceramic	N/A	N/A	N/A	N/A	N/A	None	None							
1	1	104A	Women's Restroom across from Classroom 105	yes	W1	Concrete / Ceramic	Pink	None	0	N/A	N/A	None	None							
1	1	104A	Women's Restroom across from Classroom 105	yes	W2	Concrete / Ceramic	Pink	None	0	N/A	N/A	None	None							
1	1	104A	Women's Restroom across from Classroom 105	yes	W3	Concrete / Ceramic	Pink	None	0	N/A	N/A	None	None							
1	1	104A	Women's Restroom across from Classroom 105	yes	W4	Concrete / Ceramic	Pink	None	0	N/A	N/A	None	None							
1	1	104A	Women's Restroom across from Classroom 105	yes	Ceiling	Sheetrock	Beige	Moisture Damage	1	0.06	Negative	None	None							
1	1	104A	Women's Restroom across from Classroom 105	yes	Floor	Ceramic	N/A	N/A	N/A	N/A	N/A	None	None							
1	1	Vest-1	Main Entrance Vestibule	yes	W1	Concrete / Ceramic	White	Chipping	2	0.06	Negative	None	None							
1	1	Vest-1	Main Entrance Vestibule	yes	W2	Concrete / Ceramic	White	None	0	N/A	N/A	None	None							
1	1	Vest-1	Main Entrance Vestibule	yes	W3	Concrete / Ceramic	White	None	0	N/A	N/A	None	None							
1	1	Vest-1	Main Entrance Vestibule	yes	W4	Concrete / Ceramic	White	None	0	N/A	N/A	None	None							
1	1	Vest-1	Main Entrance Vestibule	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	None						12x12 Ceiling Tiles	
1	1	Vest-1	Main Entrance Vestibule	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	None							
1	1	H01	Hallway from Main Entrance to Auditorium	yes	W1	Concrete/ Ceramic	White	None	0	N/A	N/A	None	None							
1	1	H01	Hallway from Main Entrance to Auditorium	yes	W2	Concrete/ Ceramic	White	None	0	N/A	N/A	None	None							
1	1	H01	Hallway from Main Entrance to Auditorium	yes	W3	Concrete/ Ceramic	White	None	0	N/A	N/A	None	None							
1	1	H01	Hallway from Main Entrance to Auditorium	yes	W4	Concrete/ Ceramic	White	None	0	N/A	N/A	None	None							
1	1	H01	Hallway from Main Entrance to Auditorium	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	None						12x12 and 2x4 Ceiling Tiles	
1	1	H01	Hallway from Main Entrance to Auditorium	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	None							
1	1	104B	Custodial Closet by Auditorium Entrance	yes	W1	Concrete	Royal Blue	Friction	1	0.13	Negative	None	None							

					School District of Philadelphia														
			Name of Inspector: Suzanne Shourds and Shalaunda Gourdine		Lead Safe Certification Assessment Report							Inspection Dates: 9/20-29/2021							
			Inspection Company: React		Farrell School							ULCS# 8380							
E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes
1	1	104B	Custodial Closet by Auditorium Entrance	yes	W2	Concrete	Concrete	None	0	N/A	N/A	None	None						
1	1	104B	Custodial Closet by Auditorium Entrance	yes	W3	Concrete	Concrete	None	0	N/A	N/A	None	None						
1	1	104B	Custodial Closet by Auditorium Entrance	yes	W4	Concrete	Concrete	None	0	N/A	N/A	None	None						
1	1	104B	Custodial Closet by Auditorium Entrance	yes	Ceiling	Sheetrock	White	None	0	N/A	N/A	None	None						
1	1	104B	Custodial Closet by Auditorium Entrance	yes	Floor	Concrete	Gray	Friction	1	0	Negative	None	None						
1	1	PC104B	Pipe Chase in Custodial Closet by Auditorium Entrance	no	W1	Concrete	N/A	N/A	N/A	N/A	N/A	None	None						
	1	PC104B	Pipe Chase in Custodial Closet by Auditorium Entrance	no	W2	Concrete	N/A	N/A	N/A	N/A	N/A	None	None						
1	1	PC104B	Pipe Chase in Custodial Closet by Auditorium Entrance	no	W3	Concrete	N/A	N/A	N/A	N/A	N/A	None	None						
1	1	PC104B	Pipe Chase in Custodial Closet by Auditorium Entrance	no	W4	Concrete	N/A	N/A	N/A	N/A	N/A	None	None						
1	1	PC104B	Pipe Chase in Custodial Closet by Auditorium Entrance	no	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	None	None						
1	1	PC104B	Pipe Chase in Custodial Closet by Auditorium Entrance	no	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	None	None						
1	1	114	Auditorium	yes	W1	Concrete	Multi	None	0	N/A	N/A	None	None						
1	1	114	Auditorium	yes	W2	Concrete	Sky Blue/White	None	0	N/A	N/A	None	None						
1	1	114	Auditorium	yes	W3	Plaster	Sky Blue/White	None	0	N/A	N/A	None	None						
1	1	114	Auditorium	yes	W4	Concrete	Multi	Chipping	10	0.01	Negative	None	None						
1	1	114	Auditorium	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	None						12x12 Ceiling Tiles
1	1	114	Auditorium	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	None						
1	1	114 STAGE	Auditorium Stage	yes	W1	Concrete/ Plaster	Sky Blue/White	None	0	N/A	N/A	None	None						
1	1	114 STAGE	Auditorium Stage	yes	W2	Concrete	Sky Blue/White	None	0	N/A	N/A	None	None						
1	1	114 STAGE	Auditorium Stage	yes	W3	Concrete	Sky Blue/White	None	0	N/A	N/A	None	None						
1	1	114 STAGE	Auditorium Stage	yes	W4	Concrete	Sky Blue/White	None	0	N/A	N/A	None	None						
1	1	114 STAGE	Auditorium Stage	yes	Ceiling	Fiberglass	White	Moisture Damage	1	No Access	No Access	None	None						2x4 Fiberglass/ Acoustic Ceiling Tiles
1	1	114 STAGE	Auditorium Stage	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	None						
1	1	106A	Men's Restroom across from Nurse's Office	yes	W1	Concrete / Ceramic	Baby Blue	None	0	N/A	N/A	None	None						
1	1	106A	Men's Restroom across from Nurse's Office	yes	W2	Concrete / Ceramic	Baby Blue	None	0	N/A	N/A	None	None						
1	1	106A	Men's Restroom across from Nurse's Office	yes	W3	Concrete / Ceramic	Baby Blue	Friction	1	0.06	Negative	None	None						
1	1	106A	Men's Restroom across from Nurse's Office	yes	W4	Concrete / Ceramic	Baby Blue	None	0	N/A	N/A	None	None						
1	1	106A	Men's Restroom across from Nurse's Office	yes	Ceiling	Sheetrock	White	None	0	N/A	N/A	None	None						
1	1	106A	Men's Restroom across from Nurse's Office	yes	Floor	Ceramic	N/A	N/A	N/A	N/A	N/A	None	None						
1	1	106	Nurse's Office	yes	W1	Concrete / Metal	Green	None	0	N/A	N/A	None	None						
1	1	106	Nurse's Office	yes	W2	Concrete	Green	None	0	N/A	N/A	None	None						
1	1	106	Nurse's Office	yes	W3	Concrete	Green	None	0	N/A	N/A	None	None						
1	1	106	Nurse's Office	yes	W4	Concrete	Green	None	0	N/A	N/A	None	None						
1	1	106	Nurse's Office	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	None						12x12 Ceiling Tile
1	1	106	Nurse's Office	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	None						12x12 FT
1	1	106D	Nurse's Office Restroom	yes	W1	Concrete / Ceramic	Green	None	0	N/A	N/A	None	None						
1	1	106D	Nurse's Office Restroom	yes	W2	Concrete / Ceramic	Green	None	0	N/A	N/A	None	None						
1	1	106D	Nurse's Office Restroom	yes	W3	Concrete / Ceramic	Green	None	0	N/A	N/A	None	None						
1	1	106D	Nurse's Office Restroom	yes	W4	Concrete / Ceramic	Green	None	0	N/A	N/A	None	None						
1	1	106D	Nurse's Office Restroom	yes	Ceiling	Sheetrock	White	None	0	N/A	N/A	None	None						
1	1	106D	Nurse's Office Restroom	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	None						12x12 FT
1	1	106C	Nurse's Office Closet	yes	W1	Concrete	Yellow	None	0	N/A	N/A	None	None						
1	1	106C	Nurse's Office Closet	yes	W2	Concrete	Yellow	None	0	N/A	N/A	None	None						
1	1	106C	Nurse's Office Closet	yes	W3	Concrete	Yellow	None	0	N/A	N/A	None	None						
1	1	106C	Nurse's Office Closet	yes	W4	Concrete	Yellow	None	0	N/A	N/A	None	None						
1	1	106C	Nurse's Office Closet	yes	Ceiling	Sheetrock	Yellow	None	0	N/A	N/A	None	None						
1	1	106C	Nurse's Office Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	None						
1	1	106B	Main Office Storage Room	yes	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	1	106B	Main Office Storage Room	yes	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	1	106B	Main Office Storage Room	yes	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	1	106B	Main Office Storage Room	yes	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	1	106B	Main Office Storage Room	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	1	106B	Main Office Storage Room	yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	1	107A	Counselor's Office in Main Office	yes	W1	Concrete / Metal	Brown	None	0	N/A	N/A	None	None						
1	1	107A	Counselor's Office in Main Office	yes	W2	Concrete	Yellow	None	0	N/A	N/A	None	None						
1	1	107A	Counselor's Office in Main Office	yes	W3	Concrete / Metal	Brown	None	0	N/A	N/A	None	None						
1	1	107A	Counselor's Office in Main Office	yes	W4	Concrete / Metal	Brown	Friction	1	0.07	Negative	None	None						
1	1	107A	Counselor's Office in Main Office	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	None						12x12 Ceiling Tile
1	1	107A	Counselor's Office in Main Office	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	None						9x9 FT
1	1	109	Main Office	yes	W1	Concrete	Beige	None	0	N/A	N/A	None	None						
1	1	109	Main Office	yes	W2	Concrete / Metal	Beige	None	0	N/A	N/A	None	None						
1	1	109	Main Office	yes	W3	Concrete	Beige	None	0	N/A	N/A	None	None						
1	1	109	Main Office	yes	W4	Concrete / Metal	Beige	None	0	N/A	N/A	None	None						
1	1	109	Main Office	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	None						12x12 Ceiling Tile
1	1	109	Main Office	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	None						12x12 FT
1	1	109A	Principal's Office	yes	W1	Metal	Blue	None	0	N/A	N/A	None	None						
1	1	109A	Principal's Office	yes	W2	Concrete	Blue	None	0	N/A	N/A	None	None						
1	1	109A	Principal's Office	yes	W3	Concrete	Blue	None	0	N/A	N/A	None	None						
1	1	109A	Principal's Office	yes	W4	Concrete	Blue	None	0	N/A	N/A	None	None						

						School District of Philadelphia														
				Name of Inspector: Suzanne Shourds and Shalaunda Gourdine		Lead Safe Certification Assessment Report										Inspection Dates: 9/20-29/2021				
				Inspection Company: React		Farrell School										ULCS# 8380				
E l e m e n t	F l o o r		Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes
1	1		109A	Principal's Office	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	None						12x12 Ceiling Tile
1	1		109A	Principal's Office	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	None						12x12 FT
1	1		109B	Principal's Office Restroom	yes	W1	Concrete / Ceramic	Beige	None	0	N/A	N/A	None	None						
1	1		109B	Principal's Office Restroom	yes	W2	Concrete / Ceramic	Beige	None	0	N/A	N/A	None	None						
1	1		109B	Principal's Office Restroom	yes	W3	Concrete / Ceramic	Beige	None	0	N/A	N/A	None	None						
1	1		109B	Principal's Office Restroom	yes	W4	Concrete / Ceramic	Beige	None	0	N/A	N/A	None	None						
1	1		109B	Principal's Office Restroom	yes	Ceiling	Sheetrock	White	None	0	N/A	N/A	None	None						
1	1		109B	Principal's Office Restroom	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	None						Ceramic tile
1	1		109C	Principal's Office Closet	yes	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	1		109C	Principal's Office Closet	yes	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	1		109C	Principal's Office Closet	yes	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	1		109C	Principal's Office Closet	yes	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	1		109C	Principal's Office Closet	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	1		109C	Principal's Office Closet	yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	1		107	Storage Room across from Main Office	yes	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	1		107	Storage Room across from Main Office	yes	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	1		107	Storage Room across from Main Office	yes	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	1		107	Storage Room across from Main Office	yes	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	1		107	Storage Room across from Main Office	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	1		107	Storage Room across from Main Office	yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	1		108	Dean of Students	yes	W1	Concrete	Baby Blue	None	0	N/A	N/A	None	None						
1	1		108	Dean of Students	yes	W2	Concrete	Baby Blue	None	0	N/A	N/A	None	None						
1	1		108	Dean of Students	yes	W3	Concrete	Baby Blue	None	0	N/A	N/A	None	None						
1	1		108	Dean of Students	yes	W4	Sheetrock	Baby Blue	Chipping	1	0	Negative	None	None						
1	1		108	Dean of Students	yes	Ceiling	Sheetrock	Baby Blue	None	0	N/A	N/A	None	None						
1	1		108	Dean of Students	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	None						
1	1		108A	Dean of Students Storage	yes	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	1		108A	Dean of Students Storage	yes	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	1		108A	Dean of Students Storage	yes	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	1		108A	Dean of Students Storage	yes	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	1		108A	Dean of Students Storage	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	1		108A	Dean of Students Storage	yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	1		108B	Special Education Liasion Office	yes	W1	Concrete	Baby Blue	None	0	N/A	N/A	None	None						
1	1		108B	Special Education Liasion Office	yes	W2	Concrete	Multi	None	0	N/A	N/A	None	None						
1	1		108B	Special Education Liasion Office	yes	W3	Concrete	Baby Blue	None	0	0	Negative	None	None						
1	1		108B	Special Education Liasion Office	yes	W4	Concrete	Baby Blue	None	0	N/A	N/A	None	None						
1	1		108B	Special Education Liasion Office	yes	Ceiling	Sheetrock	White	None	0	N/A	N/A	None	None						
1	1		108B	Special Education Liasion Office	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	None						
				Hallway from across Classroom 111 to Gym and Cafeteria	yes	W1	Concrete/ Ceramic	White	None	0	N/A	N/A	None	None						
1	1		H02	Hallway from across Classroom 111 to Gym and Cafeteria	yes	W2	Concrete/ Ceramic	White	Friction	2	0.05	Negative	None	None						
				Hallway from across Classroom 111 to Gym and Cafeteria	yes	W3	Concrete / Ceramic	White	None	0	N/A	N/A	None	None						
1	1		H02	Hallway from across Classroom 111 to Gym and Cafeteria	yes	W4	Concrete/ Ceramic	White	None	0	N/A	N/A	None	None						
				Hallway from across Classroom 111 to Gym and Cafeteria	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	None						12"x12" ceiling tile
				Hallway from across Classroom 111 to Gym and Cafeteria	yes	Floor	Ceramic	N/A	N/A	N/A	N/A	N/A	None	None						
1	1		110	Gymnasium	yes	W1	Concrete	White	None	0	N/A	N/A	None	None						
1	1		110	Gymnasium	yes	W2	Concrete	White	None	0	N/A	N/A	None	None						
1	1		110	Gymnasium	yes	W3	Concrete	White	Chipping	6	0.03	Negative	None	None						
1	1		110	Gymnasium	yes	W4	Concrete	White	Chipping	4	0.07	Negative	None	None						
1	1		110	Gymnasium	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	None						Insulated Ceiling Panels
1	1		110	Gymnasium	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	None						
1	1		110B	Girl's Restroom in Gym	yes	W1	Concrete / Ceramic	Beige	None	0	N/A	N/A	None	None						
1	1		110B	Girl's Restroom in Gym	yes	W2	Concrete / Ceramic	Beige	None	0	N/A	N/A	None	None						
1	1		110B	Girl's Restroom in Gym	yes	W3	Concrete / Ceramic	Beige	None	0	N/A	N/A	None	None						
1	1		110B	Girl's Restroom in Gym	yes	W4	Concrete / Ceramic	Beige	Flaking	6	0.08	Negative	None	None						
1	1		110B	Girl's Restroom in Gym	yes	Ceiling	Sheetrock	Beige	Flaking	3	0.7	Positive	None	None						
1	1		110B	Girl's Restroom in Gym	yes	Floor	Ceramic	N/A	N/A	N/A	N/A	N/A	None	None						
1	1		PC110B	Pipe Chase in Girl's Restroom in Gym	no	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	1		PC110B	Pipe Chase in Girl's Restroom in Gym	no	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	1		PC110B	Pipe Chase in Girl's Restroom in Gym	no	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	1		PC110B	Pipe Chase in Girl's Restroom in Gym	no	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	1		PC110B	Pipe Chase in Girl's Restroom in Gym	no	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	1		PC110B	Pipe Chase in Girl's Restroom in Gym	no	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	1		110E	Boy's Restroom in Gym	yes	W1	Concrete / Ceramic	Beige	None	0	N/A	N/A	None	None						
1	1		110E	Boy's Restroom in Gym	yes	W1	Concrete / Ceramic	Beige	Cracking	2	0.06	Negative	None	None						
1	1		110E	Boy's Restroom in Gym	yes	W2	Concrete / Ceramic	Beige	Cracking	2	0.04	Negative	None	None						
1	1		110E	Boy's Restroom in Gym	yes	W3	Concrete / Ceramic	Beige	None	0	N/A	N/A	None	None						
1	1		110E	Boy's Restroom in Gym	yes	W4	Concrete / Ceramic	Beige	None	0	N/A	N/A	None	None						
1	1		110E	Boy's Restroom in Gym	yes	Ceiling	Sheetrock	Beige	None	0	N/A	N/A	None	None						
1	1		110E	Boy's Restroom in Gym	yes	Floor	Ceramic	N/A	N/A	N/A	N/A	N/A	None	None						

					School District of Philadelphia														
			Name of Inspector: Suzanne Shourds and Shalaunda Gourdine		Lead Safe Certification Assessment Report							Inspection Dates: 9/20-29/2021							
			Inspection Company: React		Farrell School							ULCS# 8380							
E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes
1	1	110E	Boy's Restroom in Gym	yes	Floor	Ceramic	N/A	N/A	N/A	N/A	N/A	None	None						
1	1	110F	Gym Storage Room (Front Area)	yes	W1	Concrete	Beige	None	0	N/A	N/A	None	None						
1	1	110F	Gym Storage Room (Front Area)	yes	W2	Concrete	Beige	None	0	N/A	N/A	None	None						
1	1	110F	Gym Storage Room (Front Area)	yes	W3	Concrete	Beige	None	0	N/A	N/A	None	None						
1	1	110F	Gym Storage Room (Front Area)	yes	W4	Concrete	Beige	None	0	N/A	N/A	None	None						
1	1	110F	Gym Storage Room (Front Area)	yes	Ceiling	Sheetrock	Beige	None	0	N/A	N/A	None	None						
1	1	110F	Gym Storage Room (Front Area)	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	None						
1	1	110G	Gym Storage Room (Rear Area)	yes	Duct Work	Metal	Beige	Flaking	40	No Access	No Access	None	None						
1	1	110G	Gym Storage Room (Rear Area)	yes	W1	Concrete	Beige	None	0	N/A	N/A	None	None						
1	1	110G	Gym Storage Room (Rear Area)	yes	W2	Concrete	Beige	None	0	N/A	N/A	None	None						
1	1	110G	Gym Storage Room (Rear Area)	yes	W3	Concrete	Beige	None	0	N/A	N/A	None	None						
1	1	110G	Gym Storage Room (Rear Area)	yes	W4	Concrete	Beige	None	0	N/A	N/A	None	None						
1	1	110G	Gym Storage Room (Rear Area)	yes	Ceiling	Sheetrock	Beige	None	0	N/A	N/A	None	None						
1	1	110G	Gym Storage Room (Rear Area)	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	None						
1	1	110C	Gym Office	yes	W1	Concrete	Beige	None	0	N/A	N/A	None	None						
1	1	110C	Gym Office	yes	W2	Concrete	Beige	None	0	N/A	N/A	None	None						
1	1	110C	Gym Office	yes	W3	Concrete	Beige	None	0	N/A	N/A	None	None						
1	1	110C	Gym Office	yes	W4	Concrete	Beige	Chipping	1	0	Negative	None	None						
1	1	110C	Gym Office	yes	Ceiling	Sheetrock	Beige	None	0	N/A	N/A	None	None						
1	1	110C	Gym Office	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	None						
1	1	110D	Gym Office Closet	yes	W1	Concrete	Beige	None	0	N/A	N/A	None	None						
1	1	110D	Gym Office Closet	yes	W2	Concrete	Beige	None	0	N/A	N/A	None	None						
1	1	110D	Gym Office Closet	yes	W3	Concrete	Beige	None	0	N/A	N/A	None	None						
1	1	110D	Gym Office Closet	yes	W4	Concrete	Beige	None	0	N/A	N/A	None	None						
1	1	110D	Gym Office Closet	yes	Ceiling	Sheetrock	Beige	Moisture Damage	3	No Access	No Access	None	None						
1	1	110D	Gym Office Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	None						
1	1	H02A	Custodial Closet in Hallway next to Cafeteria	yes	W1	Concrete	Baby Blue/ Sky Blue	None	0	N/A	N/A	None	None						
1	1	H02A	Custodial Closet in Hallway next to Cafeteria	yes	W2	Concrete	Baby Blue/ Sky Blue	None	0	N/A	N/A	None	None						
1	1	H02A	Custodial Closet in Hallway next to Cafeteria	yes	W3	Concrete	Baby Blue/ Sky Blue	Chipping	5	0.2	Negative	None	None						
1	1	H02A	Custodial Closet in Hallway next to Cafeteria	yes	W4	Metal	Baby Blue/ Sky Blue	Chipping	8	0.04	Negative	None	None						
1	1	H02A	Custodial Closet in Hallway next to Cafeteria	yes	Ceiling	Sheetrock	White	Cracking	4	No Access	No Access	None	None						
1	1	H02A	Custodial Closet in Hallway next to Cafeteria	yes	Floor	Concrete	Red/ Gray	Friction	10	0	Negative	None	None						
1	1	116	Cafeteria	yes	W1	Concrete	Multi	Chipping	2	0.07	Negative	None	None						
1	1	116	Cafeteria	yes	W2	Concrete	Beige	None	0	N/A	N/A	None	None						
1	1	116	Cafeteria	yes	W3	Concrete	Beige	Chipping	2	0.03	Negative	None	None						
1	1	116	Cafeteria	yes	W4	Concrete	Multi	Friction	12	0.09	Negative	None	None						
1	1	116	Cafeteria	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	None						12x12 Celimg tiles
1	1	116	Cafeteria	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	None						
1	1	116A	Kitchen	yes	W1	Concrete/ Ceramic	Beige	None	0	N/A	N/A	None	None						
1	1	116A	Kitchen	yes	W2	Concrete/ Ceramic	Beige	None	0	N/A	N/A	None	None						
1	1	116A	Kitchen	yes	W3	Concrete / Ceramic	Beige	Moisture Damage	3	0.01	Negative	None	None						
1	1	116A	Kitchen	yes	W4	Concrete / Ceramic	Beige	None	0	N/A	N/A	None	None						
1	1	116A	Kitchen	yes	Ceiling	Sheetrock	White	Moisture Damage	1	No Access	No Access	None	None						
1	1	116A	Kitchen	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	None						
1	1	116D	Kitchen Office	yes	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	1	116D	Kitchen Office	yes	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	1	116D	Kitchen Office	yes	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	1	116D	Kitchen Office	yes	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	1	116D	Kitchen Office	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	1	116D	Kitchen Office	yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	1	116E	Staff Restroom next to Kitchen Office	yes	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	1	116E	Staff Restroom next to Kitchen Office	yes	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	1	116E	Staff Restroom next to Kitchen Office	yes	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	1	116E	Staff Restroom next to Kitchen Office	yes	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	1	116E	Staff Restroom next to Kitchen Office	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	1	116E	Staff Restroom next to Kitchen Office	yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	1	116B	Kitchen Dry Storage	yes	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	1	116B	Kitchen Dry Storage	yes	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	1	116B	Kitchen Dry Storage	yes	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	1	116B	Kitchen Dry Storage	yes	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	1	116B	Kitchen Dry Storage	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	1	116B	Kitchen Dry Storage	yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	1	S04	Hallway from Cafeteria to Kitchen	yes	W1	Concrete	Beige	Chipping	1	0.07	Negative	None	None						
1	1	S04	Hallway from Cafeteria to Kitchen	yes	W2	Concrete	Multi	None	0	N/A	N/A	None	None						
1	1	S04	Hallway from Cafeteria to Kitchen	yes	W3	Concrete	Beige	None	0	N/A	N/A	None	None						
1	1	S04	Hallway from Cafeteria to Kitchen	yes	W4	Concrete	Multi	None	0	N/A	N/A	None	None						
1	1	S04	Hallway from Cafeteria to Kitchen	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	None						12x12 Celimg tiles
1	1	S04	Hallway from Cafeteria to Kitchen	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	None						
1	1	H05	Hallway from Classrooms 100 to 113	yes	W1	Concrete / Ceramic	White	Chipping	2	0.12	Negative	None	None						
1	1	H05	Hallway from Classrooms 100 to 113	yes	W2	Concrete / Ceramic	White	None	0	N/A	N/A	None	None						

Element Floor Space #					School District of Philadelphia														
			Name of Inspector: Suzanne Shourds and Shalaunda Gourdine		Lead Safe Certification Assessment Report							Inspection Dates: 9/20-29/2021							
			Inspection Company: React		Farrell School							ULCS# 8380							
			On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes
1	1	H05	Hallway from Classrooms 100 to 113	yes	W3	Concrete / Ceramic	White	None	0	N/A	N/A	None	None						
1	1	H05	Hallway from Classrooms 100 to 113	yes	W4	Concrete / Ceramic	White	None	0	N/A	N/A	None	None						
1	1	H05	Hallway from Classrooms 100 to 113	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	None						
1	1	H05	Hallway from Classrooms 100 to 113	yes	Floor	Ceramic	N/A	N/A	N/A	N/A	N/A	None	None						12x12 Ceiling Tiles
5	1	TRAILER 4	Trailer 4 - Classroom	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	None	None						Trailers no longer at school
5	1	TRAILER 4	Trailer 4 - Classroom	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A	None	None						Trailers no longer at school
5	1	TRAILER 4	Trailer 4 - Classroom	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A	None	None						Trailers no longer at school
5	1	TRAILER 4	Trailer 4 - Classroom	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A	None	None						Trailers no longer at school
5	1	TRAILER 4	Trailer 4 - Classroom	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	None						Trailers no longer at school
5	1	TRAILER 4	Trailer 4 - Classroom	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	None						Trailers no longer at school
7	1	TRAILER 1	Trailer 1 - Classroom	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	None	None						Trailers no longer at school
7	1	TRAILER 1	Trailer 1 - Classroom	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A	None	None						Trailers no longer at school
7	1	TRAILER 1	Trailer 1 - Classroom	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A	None	None						Trailers no longer at school
7	1	TRAILER 1	Trailer 1 - Classroom	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A	None	None						Trailers no longer at school
7	1	TRAILER 1	Trailer 1 - Classroom	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	None						Trailers no longer at school
7	1	TRAILER 1	Trailer 1 - Classroom	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	None						Trailers no longer at school
6	1	TRAILER 2	Trailer 2 - Classroom	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	None	None						Trailers no longer at school
6	1	TRAILER 2	Trailer 2 - Classroom	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A	None	None						Trailers no longer at school
6	1	TRAILER 2	Trailer 2 - Classroom	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A	None	None						Trailers no longer at school
6	1	TRAILER 2	Trailer 2 - Classroom	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A	None	None						Trailers no longer at school
6	1	TRAILER 2	Trailer 2 - Classroom	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	None						Trailers no longer at school
6	1	TRAILER 2	Trailer 2 - Classroom	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	None						Trailers no longer at school
4	1	TRAILER 3	Trailer 3 - Classroom	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	None	None						Trailers no longer at school
4	1	TRAILER 3	Trailer 3 - Classroom	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A	None	None						Trailers no longer at school
4	1	TRAILER 3	Trailer 3 - Classroom	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A	None	None						Trailers no longer at school
4	1	TRAILER 3	Trailer 3 - Classroom	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A	None	None						Trailers no longer at school
4	1	TRAILER 3	Trailer 3 - Classroom	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	None						Trailers no longer at school
4	1	TRAILER 3	Trailer 3 - Classroom	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	None						Trailers no longer at school
2	1	A3	Classroom A3 and Closet Areas	yes	W1	Concrete	Tan	None	0	N/A	N/A	None	None						
2	1	A3	Classroom A3 and Closet Areas	yes	W2	Concrete / Sheetrock	Tan	None	0	N/A	N/A	None	None						
2	1	A3	Classroom A3 and Closet Areas	yes	W3	Concrete	Tan	Chipping	3	0	Negative	None	None						
2	1	A3	Classroom A3 and Closet Areas	yes	W4	Concrete	Tan	Chipping	1	0.0022	Negative	None	None						
2	1	A3	Classroom A3 and Closet Areas	yes	Radiator	Metal	Tan	Rust	4	0	Negative	None	None						
2	1	A3	Classroom A3 and Closet Areas	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	None						12x12 Ceiling Tile
2	1	A3	Classroom A3 and Closet Areas	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	None						12x12 Floor Tile
2	1	A6	Classroom A6 and Closet Areas	yes	W1	Concrete	Orange	None	0	0	Negative	None	None						
2	1	A6	Classroom A6 and Closet Areas	yes	W2	Concrete / Sheetrock	Tan	None	0	N/A	N/A	None	None						
2	1	A6	Classroom A6 and Closet Areas	yes	W3	Concrete	Tan	None	0	0	Negative	None	None						
2	1	A6	Classroom A6 and Closet Areas	yes	W4	Sheetrock	Tan	None	0	N/A	N/A	None	None						
2	1	A6	Classroom A6 and Closet Areas	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	None						2x4 Ceiling Tile
2	1	A6	Classroom A6 and Closet Areas	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	None						12x12 Floor Tile
2	1	A4	Special Education Office and Closet Areas	yes	W1	Concrete	Light Green	None	0	N/A	N/A	None	None						
2	1	A4	Special Education Office and Closet Areas	yes	W2	Sheetrock	Light Green	None	0	N/A	N/A	None	None						
2	1	A4	Special Education Office and Closet Areas	yes	W3	Concrete	Light Green	None	0	N/A	N/A	None	None						
2	1	A4	Special Education Office and Closet Areas	yes	W4	Sheetrock	Light Green	Chipping	1	0.005	Negative	None	None						
2	1	A4	Special Education Office and Closet Areas	yes	Radiator	Metal	Tan	Flaking	1	0	Negative	None	None						
2	1	A4	Special Education Office and Closet Areas	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	None						12x12 Ceiling Tile
2	1	A4	Special Education Office and Closet Areas	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	None						12x12 Floor Tile
2	1	A4A	Girl's Restroom next to Special Education Office	yes	W1	Concrete / Sheetrock	Purple	None	0	N/A	N/A	None	None						
2	1	A4A	Girl's Restroom next to Special Education Office	yes	W2	Sheetrock	Purple	None	0	0.012	Negative	None	None						
2	1	A4A	Girl's Restroom next to Special Education Office	yes	W3	Concrete	Purple	None	0	0.0014	Negative	None	None						
2	1	A4A	Girl's Restroom next to Special Education Office	yes	W4	Sheetrock	Purple	None	0	N/A	N/A	None	None						
2	1	A4A	Girl's Restroom next to Special Education Office	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	None						2x4 Ceiling Tile
2	1	A4A	Girl's Restroom next to Special Education Office	yes	Floor	Concrete	Grey	None	0	N/A	N/A	None	None						
2	1	A2A	Boy's Restroom near IMC	yes	W1	Concrete	Blue	None	0	0.001	Negative	None	None						
2	1	A2A	Boy's Restroom near IMC	yes	W2	Sheetrock	Blue	None	0	N/A	N/A	None	None						
2	1	A2A	Boy's Restroom near IMC	yes	W3	Sheetrock	Blue	None	0	N/A	N/A	None	None						
2	1	A2A	Boy's Restroom near IMC	yes	W4	Sheetrock	Blue	None	0	0.0019	Negative	None	None						
2	1	A2A	Boy's Restroom near IMC	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	None						2x4 Ceiling Tile
2	1	A2A	Boy's Restroom near IMC	yes	Floor	Concrete	Grey	None	0	0	Negative	None	None						
2	1	A1	Library	yes	W1	Concrete	Light Blue	None	0	0.024	Negative	None	None						
2	1	A1	Library	yes	W2	Concrete	Blue	None	0	0	Negative	None	None						
2	1	A1	Library	yes	W3	Concrete	Light Blue	None	0	N/A	N/A	None	None						
2	1	A1	Library	yes	W4	Sheetrock	Light Blue	None	0	N/A	N/A	None	None						
2	1	A1	Library	yes	Radiator	Metal	Blue	None	0	N/A	N/A	None	None						
2	1	A1	Library	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	None						2x4 Ceiling Tile
2	1	A1	Library	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	None						Carpet and 12x12 FT
2	1	A1A	Office in Library	yes	W1	Sheetrock	Light Blue	None	0	N/A	N/A	None	None						
2	1	A1A	Office in Library	yes	W2	Sheetrock	Light Blue	None	0	N/A	N/A	None	None						
2	1	A1A	Office in Library	yes	W3	Concrete	Light Blue	None	0	N/A	N/A	None	None						
2	1	A1A	Office in Library	yes	W4	Sheetrock	Light Blue	None	0	0	Negative	None	None						
2	1	A1A	Office in Library	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	None						2x4 Ceiling Tile
2	1	A1A	Office in Library	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	None						12x12 Floor Tile



					School District of Philadelphia															
			Name of Inspector: Suzanne Shourds and Shalaunda Gourdine		Lead Safe Certification Assessment Report							Inspection Dates: 9/20-29/2021								
			Inspection Company: React		Farrell School							ULCS# 8380								
E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes	
2	1	A2	Classroom A2 and Closet Areas	yes	W1	Concrete	Orange	None	0	N/A	N/A	None	None							
2	1	A2	Classroom A2 and Closet Areas	yes	W2	Concrete / Sheetrock	Light Brown	None	0	0.012	Negative	None	None							
2	1	A2	Classroom A2 and Closet Areas	yes	W3	Concrete	Light Brown	None	0	N/A	N/A	None	None							
2	1	A2	Classroom A2 and Closet Areas	yes	W4	Concrete	Light Brown	None	0	N/A	N/A	None	None							
2	1	A2	Classroom A2 and Closet Areas	yes	Radiator	Metal	Grey	Peeling	3	0	Negative	None	None							
2	1	A2	Classroom A2 and Closet Areas	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	None						2x4 Ceiling Tile	
2	1	A2	Classroom A2 and Closet Areas	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	None						12x12 Floor Tile	
2	1	A5	Utility Room/Custodial Room	no	W1	Concrete	Yellow-Cream	Friction	3	0	Negative	None	None							
2	1	A5	Utility Room/Custodial Room	no	W2	Concrete	Yellow-Cream	Friction	8	0.0007	Negative	None	None							
2	1	A5	Utility Room/Custodial Room	no	W3	Concrete	Yellow-Cream	Friction	8	0	Negative	None	None							
2	1	A5	Utility Room/Custodial Room	no	W4	Concrete	Yellow-Cream	Friction	1	0.003	Negative	None	None							
2	1	A5	Utility Room/Custodial Room	no	Vertical Pipe Run	Metal	Yellow-Cream	Peeling	3	0.109	Negative	None	None							
2	1	A5	Utility Room/Custodial Room	no	Ceiling	Concrete	White	None	0	N/A	N/A	None	None							
2	1	A5	Utility Room/Custodial Room	no	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	None						9x9 Floor Tile and 12x12 Floor Tile	
2	1	H001	Hallway from Classrooms A2 to A6	yes	W1	Concrete	Cream	None	0	N/A	N/A	None	None							
2	1	H001	Hallway from Classrooms A2 to A6	yes	W2	Concrete/Stone	Cream	None	0	0.005	Negative	None	None							
2	1	H001	Hallway from Classrooms A2 to A6	yes	W3	Concrete	Cream	None	0	0	Negative	None	None							
2	1	H001	Hallway from Classrooms A2 to A6	yes	W4	Concrete/Stone	Cream	None	0	N/A	N/A	None	None							
2	1	H001	Hallway from Classrooms A2 to A6	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	None						2x4 Ceiling Tile	
2	1	H001	Hallway from Classrooms A2 to A6	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	None						12x12 Floor Tile	
2	1	H002	Connecting Hallway between Annex and Main Building	yes	W1	Brick	Cream	None	0	N/A	N/A	None	None							
2	1	H002	Connecting Hallway between Annex and Main Building	yes	W2	Concrete	Cream	Friction	2	0.015	Negative	None	None							
2	1	H002	Connecting Hallway between Annex and Main Building	yes	W3	Metal	Tan	None	0	N/A	N/A	None	None							
2	1	H002	Connecting Hallway between Annex and Main Building	yes	W4	Concrete	Cream	None	0	N/A	N/A	None	None							
2	1	H002	Connecting Hallway between Annex and Main Building	yes	Ceiling	Concrete	Cream	Chipping	1	0.049	Negative	None	None							
2	1	H002	Connecting Hallway between Annex and Main Building	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	None							
1	2	S2N	Stairwell near Classrooms 212 and 213	yes	W1	Concrete / Ceramic	Beige	None	0	N/A	N/A	None	None							
1	2	S2N	Stairwell near Classrooms 212 and 213	yes	W2	Concrete / Ceramic	Beige	Friction	3	0.06	Negative	None	None							
1	2	S2N	Stairwell near Classrooms 212 and 213	yes	W3	Concrete / Ceramic	Beige	None	0	N/A	N/A	None	None							
1	2	S2N	Stairwell near Classrooms 212 and 213	yes	W4	Concrete / Ceramic	Beige	None	0	N/A	N/A	None	None							
1	2	S2N	Stairwell near Classrooms 212 and 213	yes	Ceiling	Concrete	White	None	0	N/A	N/A	None	None							
1	2	S2N	Stairwell near Classrooms 212 and 213	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	None						Terracotta Tile	
1	2	212	Classroom 212	yes	W1	Concrete	Electric Blue	None	0	0.03	Negative	None	None							
1	2	212	Classroom 212	yes	W2	Concrete	Light Blue	None	0	N/A	N/A	None	None							
1	2	212	Classroom 212	yes	W3	Concrete	Electric Blue	None	0	N/A	N/A	None	None							
1	2	212	Classroom 212	yes	W4	Concrete	Light Blue	None	0	N/A	N/A	None	None							
1	2	212	Classroom 212	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	None						12x12 Ceiling Tile	
1	2	212	Classroom 212	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	None							
1	2	212A	Classroom 212 - Closet	yes	W1	Concrete	Yellow	None	0	N/A	N/A	None	None							
1	2	212A	Classroom 212 - Closet	yes	W2	Concrete	Yellow	None	0	N/A	N/A	None	None							
1	2	212A	Classroom 212 - Closet	yes	W3	Concrete	Yellow	None	0	N/A	N/A	None	None							
1	2	212A	Classroom 212 - Closet	yes	W4	Concrete	Yellow	None	0	N/A	N/A	None	None							
1	2	212A	Classroom 212 - Closet	yes	Ceiling	Sheetrock	Yellow	None	0	N/A	N/A	None	None							
1	2	212A	Classroom 212 - Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	None							
1	2	213	Classroom 213	yes	W1	Concrete	Green	None	0	N/A	N/A	None	None							
1	2	213	Classroom 213	yes	W2	Concrete	Green	Chipping	4	0.05	Negative	None	None						Cracks in CMU Blocks	
1	2	213	Classroom 213	yes	W3	Concrete	Green/Blue	Flaking	15	0.07	Negative	None	None						Cracks in CMU Blocks	
1	2	213	Classroom 213	yes	W4	Concrete	Green	None	0	N/A	N/A	None	None							
1	2	213	Classroom 213	yes	Radiator	Metal	Tan	Friction	1	0.03	Negative	None	None							
1	2	213	Classroom 213	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	None						12x12 Ceiling Tile	
1	2	213	Classroom 213	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	None						9x9 FT	
1	2	213A	Classroom 213 - Closet	yes	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access		
1	2	213A	Classroom 213 - Closet	yes	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access		
1	2	213A	Classroom 213 - Closet	yes	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access		
1	2	213A	Classroom 213 - Closet	yes	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access		
1	2	213A	Classroom 213 - Closet	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access		
1	2	213A	Classroom 213 - Closet	yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access		
1	2	210	Classroom 210	yes	W1	Concrete	Blue	Friction	1	0.01	Negative	None	None							
1	2	210	Classroom 210	yes	W2	Concrete	Blue / Light Blue	Chipping	1	0.03	Negative	None	None							
1	2	210	Classroom 210	yes	W3	Concrete	Dark Green	None	0	N/A	N/A	None	None							
1	2	210	Classroom 210	yes	W4	Concrete	Beige	None	0	N/A	N/A	None	None							
1	2	210	Classroom 210	yes	Radiator	Metal	Tan	None	0	N/A	N/A	None	None							
1	2	210	Classroom 210	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	None						12x12 Ceiling Tile	
1	2	210	Classroom 210	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	None						9x9 FT	
1	2	210A	Classroom 210 - Closet	yes	W1	Concrete	Yellow	None	0	N/A	N/A	None	None							
1	2	210A	Classroom 210 - Closet	yes	W2	Concrete	Yellow	None	0	N/A	N/A	None	None							
1	2	210A	Classroom 210 - Closet	yes	W3	Concrete	Yellow	None	0	N/A	N/A	None	None							
1	2	210A	Classroom 210 - Closet	yes	W4	Concrete	Yellow	None	0	N/A	N/A	None	None							
1	2	210A	Classroom 210 - Closet	yes	Ceiling	Sheetrock	Yellow	None	0	N/A	N/A	None	None							
1	2	210A	Classroom 210 - Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	None						9x9 FT	
1	2	211	Classroom 211	yes	W1	Concrete	Yellow	Moisture Damage	2	0	Negative	None	None						Cracks in CMU Blocks	
1	2	211	Classroom 211	yes	W2	Concrete	Yellow	Friction	2	0	Negative	None	None							

					School District of Philadelphia														
			Name of Inspector: Suzanne Shourds and Shalaunda Gourdine		Lead Safe Certification Assessment Report							Inspection Dates: 9/20-29/2021							
			Inspection Company: React		Farrell School							ULCS# 8380							
E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes
1	2	211	Classroom 211	yes	W3	Concrete	Yellow	Chipping	2	0	Negative	None	None						
1	2	211	Classroom 211	yes	W4	Concrete	Yellow	None	0	N/A	N/A	None	None						Cracks in CMU Blocks
1	2	211	Classroom 211	yes	Radiator	Metal	Tan	Friction	1	0.04	Negative	None	None						
1	2	211	Classroom 211	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	None						12x12 Ceiling Tile
1	2	211	Classroom 211	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	None						12x12 FT
1	2	211A	Classroom 211 - Closet	yes	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	2	211A	Classroom 211 - Closet	yes	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	2	211A	Classroom 211 - Closet	yes	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	2	211A	Classroom 211 - Closet	yes	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	2	211A	Classroom 211 - Closet	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	2	211A	Classroom 211 - Closet	yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	2	208	Classroom 208	yes	W1	Concrete	Yellow	None	0	N/A	N/A	None	None						
1	2	208	Classroom 208	yes	W2	Concrete	Yellow/ Blue	None	0	N/A	N/A	None	None						
1	2	208	Classroom 208	yes	W3	Concrete	Yellow	Flaking	8	0.7	Positive	None	None						
1	2	208	Classroom 208	yes	W4	Concrete	Yellow	None	0	N/A	N/A	None	None						
1	2	208	Classroom 208	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	None						12x12 Ceiling Tile
1	2	208	Classroom 208	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	None						9x9 FT
1	2	208	Classroom 208	yes	Radiator	Metal	Tan	Friction	2	0.03	Negative	None	None						
1	2	208A	Classroom 208 - Closet	yes	W1	Concrete	Yellow	None	0	N/A	N/A	None	None						
1	2	208A	Classroom 208 - Closet	yes	W2	Concrete	Yellow	None	0	N/A	N/A	None	None						
1	2	208A	Classroom 208 - Closet	yes	W3	Concrete	Yellow	None	0	N/A	N/A	None	None						
1	2	208A	Classroom 208 - Closet	yes	W4	Concrete	Yellow	None	0	N/A	N/A	None	None						
1	2	208A	Classroom 208 - Closet	yes	Ceiling	Sheetrock	Yellow	None	0	N/A	N/A	None	None						
1	2	208A	Classroom 208 - Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	None						9x9 FT
1	2	209A	Art Office	yes	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	2	209A	Art Office	yes	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	2	209A	Art Office	yes	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	2	209A	Art Office	yes	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	2	209A	Art Office	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	2	209A	Art Office	yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	2	209	Classroom 209	yes	W1	Concrete	Yellow / Teal	None	0	N/A	N/A	None	None						
1	2	209	Classroom 209	yes	W2	Concrete	Yellow / Teal	None	0	N/A	N/A	None	None						
1	2	209	Classroom 209	yes	W3	Concrete	Yellow	Cracking	2	0.05	Negative	None	None						
1	2	209	Classroom 209	yes	W4	Concrete	Yellow	None	0	N/A	N/A	None	None						
1	2	209	Classroom 209	yes	Radiator	Metal	Tan	Friction	1	0.01	Negative	None	None						
1	2	209	Classroom 209	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	None						2x4 Ceiling Tile
1	2	209	Classroom 209	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	None						9x9 FT
1	2	209B	Classroom 209 - Closet	yes	W1	Concrete	Yellow	None	0	N/A	N/A	None	None						
1	2	209B	Classroom 209 - Closet	yes	W2	Concrete	Yellow	None	0	N/A	N/A	None	None						
1	2	209B	Classroom 209 - Closet	yes	W3	Concrete	Yellow	None	0	N/A	N/A	None	None						
1	2	209B	Classroom 209 - Closet	yes	W4	Concrete	Yellow	None	0	N/A	N/A	None	None						
1	2	209B	Classroom 209 - Closet	yes	Ceiling	Sheetrock	Yellow	None	0	N/A	N/A	None	None						
1	2	209B	Classroom 209 - Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	None						9x9 FT
1	2	206	Classroom 206	yes	W1	Concrete	Baby Blue	Chipping	1	0	Negative	None	None						
1	2	206	Classroom 206	yes	W2	Concrete	Baby Blue	None	0	N/A	N/A	None	None						
1	2	206	Classroom 206	yes	W3	Concrete	Baby Blue	None	0	N/A	N/A	None	None						
1	2	206	Classroom 206	yes	W4	Concrete	Baby Blue	None	0	N/A	N/A	None	None						
1	2	206	Classroom 206	yes	Radiator	Metal	Tan	None	0	N/A	N/A	None	None						
1	2	206	Classroom 206	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	None						12x12 Ceiling Tile
1	2	206	Classroom 206	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	None						9x9 FT
1	2	206A	Classroom 206 - Closet	yes	W1	Concrete	Light Green	None	0	N/A	N/A	None	None						
1	2	206A	Classroom 206 - Closet	yes	W2	Concrete	Light Green	None	0	N/A	N/A	None	None						
1	2	206A	Classroom 206 - Closet	yes	W3	Concrete	Light Green	None	0	N/A	N/A	None	None						
1	2	206A	Classroom 206 - Closet	yes	W4	Concrete	Light Green	None	0	N/A	N/A	None	None						
1	2	206A	Classroom 206 - Closet	yes	Ceiling	Sheetrock	Light Green	None	0	N/A	N/A	None	None						
1	2	206A	Classroom 206 - Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	None						9x9 FT
1	2	207	Classroom 207	yes	W1	Concrete	Green	Friction	5	0.01	Negative	None	None						Cracks in CMU Blocks
1	2	207	Classroom 207	yes	W2	Concrete	Green	None	0	N/A	N/A	None	None						
1	2	207	Classroom 207	yes	W3	Concrete	Green	Chipping	2	0	Negative	None	None						
1	2	207	Classroom 207	yes	W4	Concrete	Green	None	0	N/A	N/A	None	None						
1	2	207	Classroom 207	yes	Radiator	Metal	Tan	None	0	N/A	N/A	None	None						
1	2	207	Classroom 207	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	None						12x12 Ceiling Tile
1	2	207	Classroom 207	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	None						9x9 FT
1	2	207A	Classroom 207 - Closet	yes	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	2	207A	Classroom 207 - Closet	yes	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	2	207A	Classroom 207 - Closet	yes	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	2	207A	Classroom 207 - Closet	yes	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	2	207A	Classroom 207 - Closet	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	2	207A	Classroom 207 - Closet	yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	2	204A	Girl's Restroom across from Classroom 207	yes	W1	Concrete / Ceramic	Beige	None	0	N/A	N/A	None	None						
1	2	204A	Girl's Restroom across from Classroom 207	yes	W2	Concrete / Ceramic	Beige	None	0	N/A	N/A	None	None						
1	2	204A	Girl's Restroom across from Classroom 207	yes	W3	Concrete / Ceramic	Beige	None	0	N/A	N/A	None	None						
1	2	204A	Girl's Restroom across from Classroom 207	yes	W4	Concrete / Ceramic	Beige	None	0	N/A	N/A	None	None						

					School District of Philadelphia															
			Name of Inspector: Suzanne Shourds and Shalaunda Gourdine		Lead Safe Certification Assessment Report							Inspection Dates: 9/20-29/2021								
			Inspection Company: React		Farrell School							ULCS# 8380								
E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes	
1	2	204A	Girl's Restroom across from Classroom 207	yes	Ceiling	Sheetrock	Beige	Chipping	20	0.04	Negative	None	None							
1	2	204A	Girl's Restroom across from Classroom 207	yes	Floor	Ceramic	N/A	N/A	N/A	N/A	N/A	None	None							
1	2	204B	Custodial Closet across from Classroom 207	yes	W1	Concrete	Beige	None	0	N/A	N/A	None	None							
1	2	204B	Custodial Closet across from Classroom 207	yes	W2	Concrete	Beige	Chipping	1	0.04	Negative	None	None						Damaged elbow less than 1 LF	
1	2	204B	Custodial Closet across from Classroom 207	yes	W3	Concrete	Beige	None	0	N/A	N/A	None	None							
1	2	204B	Custodial Closet across from Classroom 207	yes	W4	Concrete	Beige	Flaking	1	0.1	Negative	None	None							
1	2	204B	Custodial Closet across from Classroom 207	yes	Ceiling	Sheetrock	Beige	Chipping	4	0.05	Negative	None	None							
1	2	204B	Custodial Closet across from Classroom 207	yes	Floor	Concrete	Red	Chipping	10	0	Negative	None	None							
1	2	204B	Custodial Closet across from Classroom 207	yes	Duct work	Metal	Beige	Friction	4	0.03	Negative	None	None							
1	2	PC204B	Pipe Chase in Custodial Closet across from Classroom 207	yes	W1	Concrete	N/A	N/A	N/A	N/A	N/A	None	None							
1	2	PC204B	Pipe Chase in Custodial Closet across from Classroom 207	yes	W2	Concrete	N/A	N/A	N/A	N/A	N/A	None	None							
1	2	PC204B	Pipe Chase in Custodial Closet across from Classroom 207	yes	W3	Concrete	N/A	N/A	N/A	N/A	N/A	None	None							
1	2	PC204B	Pipe Chase in Custodial Closet across from Classroom 207	yes	W4	Concrete	N/A	N/A	N/A	N/A	N/A	None	None							
1	2	PC204B	Pipe Chase in Custodial Closet across from Classroom 207	yes	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	None	None							
1	2	PC204B	Pipe Chase in Custodial Closet across from Classroom 207	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	None	None							
1	2	204	Boy's Restroom near Classroom 207	yes	W1	Concrete / Ceramic	Blue	None	0	N/A	N/A	None	None							
1	2	204	Boy's Restroom near Classroom 207	yes	W2	Concrete / Ceramic	Blue	None	0	N/A	N/A	None	None							
1	2	204	Boy's Restroom near Classroom 207	yes	W3	Concrete / Ceramic	Blue	None	0	N/A	N/A	None	None							
1	2	204	Boy's Restroom near Classroom 207	yes	W4	Concrete / Ceramic	Blue	None	0	N/A	N/A	None	None							
1	2	204	Boy's Restroom near Classroom 207	yes	Ceiling	Sheetrock	White	Chipping	20	0.1	Negative	None	None							
1	2	204	Boy's Restroom near Classroom 207	yes	Floor	Ceramic	N/A	N/A	N/A	N/A	N/A	None	None							
1	2	205	Classroom 205	yes	W1	Concrete	Eggshell Blue	None	0	N/A	N/A	None	None							
1	2	205	Classroom 205	yes	W2	Concrete	Yellow	None	0	N/A	N/A	None	None							
1	2	205	Classroom 205	yes	W3	Concrete	Yellow	Cracking	1	0	Negative	None	None							
1	2	205	Classroom 205	yes	W4	Concrete	Yellow	None	0	N/A	N/A	None	None							
1	2	205	Classroom 205	yes	Radiator	Metal	Silver	Friction	1	0.03	Negative	None	None							
1	2	205	Classroom 205	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	None							
1	2	205	Classroom 205	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	None						12x12 Ceiling Tile 9x9 FT	
1	2	205A	Classroom 205 - Closet	yes	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access		
1	2	205A	Classroom 205 - Closet	yes	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access		
1	2	205A	Classroom 205 - Closet	yes	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access		
1	2	205A	Classroom 205 - Closet	yes	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access		
1	2	205A	Classroom 205 - Closet	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access		
1	2	205A	Classroom 205 - Closet	yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access		
1	2	S2N	Stairwell near Classrooms 212 and 213	yes	Stair Railing	Metal	Tan	None	0	N/A	N/A	None	None							
1	2	S2N	Stairwell near Classrooms 212 and 213	yes	Stair Riser	Metal	Gray	None	0	N/A	N/A	None	None							
1	2	S2N	Stairwell near Classrooms 212 and 213	yes	Stair Riser	Metal	Tan	None	0	N/A	N/A	None	None							
1	2	S2W	Stairwell near Classroom 205	yes	W1	Concrete / Ceramic	Beige	None	0	N/A	N/A	None	None							
1	2	S2W	Stairwell near Classroom 205	yes	W2	Concrete / Ceramic	Beige	None	0	0.06	Negative	None	None						Cracks in CMU Blocks	
1	2	S2W	Stairwell near Classroom 205	yes	W3	Concrete / Ceramic	Beige	None	0	N/A	N/A	None	None							
1	2	S2W	Stairwell near Classroom 205	yes	W4	Concrete / Ceramic	Beige	None	0	0.07	Negative	None	None						Cracks in CMU Blocks	
1	2	S2W	Stairwell near Classroom 205	yes	Stair Railing	Metal	Tan	Friction	2	0.12	Negative	None	None							
1	2	S2W	Stairwell near Classroom 205	yes	Stair Riser	Metal	Green	Flaking	1	0.08	Negative	None	None							
1	2	S2W	Stairwell near Classroom 205	yes	Stair Riser	Metal	Beige	Chipping	1	0.06	Negative	None	None							
1	2	S2W	Stairwell near Classroom 205	yes	Ceiling	Concrete	White	None	0	N/A	N/A	None	None							
1	2	S2W	Stairwell near Classroom 205	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	None						Terracotta Tile	
1	2	202B	Women's Restroom across from Classroom 205	yes	W1	Concrete / Ceramic	Pink	Chipping	1	0.05	Negative	None	None							
1	2	202B	Women's Restroom across from Classroom 205	yes	W2	Concrete / Ceramic	Pink	Chipping	1	0.05	Negative	None	None							
1	2	202B	Women's Restroom across from Classroom 205	yes	W3	Concrete / Ceramic	Pink	None	0	N/A	N/A	None	None							
1	2	202B	Women's Restroom across from Classroom 205	yes	W4	Concrete / Ceramic	Pink	None	0	N/A	N/A	None	None							
1	2	202B	Women's Restroom across from Classroom 205	yes	Ceiling	Sheetrock	White	Cracking	5	0.08	Negative	None	None							
1	2	202B	Women's Restroom across from Classroom 205	yes	Floor	Ceramic	N/A	N/A	N/A	N/A	N/A	None	None							
1	2	202A	Speech Therapist Room 204	yes	W1	Concrete	Beige	None	0	N/A	N/A	None	None							
1	2	202A	Speech Therapist Room 204	yes	W2	Concrete	Beige	None	0	N/A	N/A	None	None							
1	2	202A	Speech Therapist Room 204	yes	W3	Concrete	Beige	None	0	N/A	N/A	None	None							
1	2	202A	Speech Therapist Room 204	yes	W4	Concrete	Beige	None	0	N/A	N/A	None	None							
1	2	202A	Speech Therapist Room 204	yes	Ceiling	Sheetrock	Beige	Moisture Damage	2	0.02	Negative	None	None							
1	2	202A	Speech Therapist Room 204	yes	Floor	Concrete	Red	Friction	1	0	Negative	None	None							
1	2	202	Classroom 202	yes	W1	Concrete	Baby Blue	None	0	N/A	N/A	None	None							
1	2	202	Classroom 202	yes	W2	Concrete	Baby Blue	None	0	N/A	N/A	None	None							
1	2	202	Classroom 202	yes	W3	Concrete	Baby Blue	Chipping	1	0.06	Negative	None	None							
1	2	202	Classroom 202	yes	W4	Concrete	Baby Blue	None	0	N/A	N/A	None	None							
1	2	202	Classroom 202	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	None						12x12 Ceiling Tile 9x9 FT	
1	2	202	Classroom 202	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	None							
1	2	202	Classroom 202	yes	Radiator	Metal	Tan	Friction	5	0.01	Negative	None	None							
1	2	202C	Classroom 202 - Closet	yes	W1	Concrete	Light Green	None	0	N/A	N/A	None	None							
1	2	202C	Classroom 202 - Closet	yes	W2	Concrete	Light Green	None	0	N/A	N/A	None	None							
1	2	202C	Classroom 202 - Closet	yes	W3	Concrete	Light Green	None	0	N/A	N/A	None	None							
1	2	202C	Classroom 202 - Closet	yes	W4	Concrete	Light Green	None	0	N/A	N/A	None	None							

					School District of Philadelphia															
			Name of Inspector: Suzanne Shourds and Shalaunda Gourdine		Lead Safe Certification Assessment Report							Inspection Dates: 9/20-29/2021								
			Inspection Company: React		Farrell School							ULCS# 8380								
E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved					
1	2	202C	Classroom 202 - Closet	yes	Ceiling	Sheetrock	Light Green	None	0	N/A	N/A	None	None							
1	2	202C	Classroom 202 - Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	None							
1	2	203	Classroom 203	yes	W1	Concrete	White	None	0	N/A	N/A	None	None							
1	2	203	Classroom 203	yes	W2	Concrete	Lime Green / Baby Blue	None	0	N/A	N/A	None	None							
1	2	203	Classroom 203	yes	W3	Concrete	Lime Green	None	0	N/A	N/A	None	None							
1	2	203	Classroom 203	yes	W4	Concrete	Lime Green	None	0	N/A	N/A	None	None							
1	2	203	Classroom 203	yes	Radiator	Metal	White	Chipping	1	0.01	Negative	None	None							
1	2	203	Classroom 203	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	None							
1	2	203	Classroom 203	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	None							
1	2	203A	Classroom 203 - Closet	yes	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access		
1	2	203A	Classroom 203 - Closet	yes	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access		
1	2	203A	Classroom 203 - Closet	yes	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access		
1	2	203A	Classroom 203 - Closet	yes	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access		
1	2	203A	Classroom 203 - Closet	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access		
1	2	203A	Classroom 203 - Closet	yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access		
1	2	200	Classroom 200	yes	W1	Concrete	Beige	None	0	N/A	N/A	None	None							
1	2	200	Classroom 200	yes	W2	Concrete	Beige	None	0	N/A	N/A	None	None							
1	2	200	Classroom 200	yes	W3	Concrete	Beige	Chipping	1	0	Negative	None	None							
1	2	200	Classroom 200	yes	W4	Concrete	Beige	None	0	N/A	N/A	None	None							
1	2	200	Classroom 200	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	None						12x12 tiles	
1	2	200	Classroom 200	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	None							
1	2	200	Classroom 200	yes	Radiator	Metal	Tan	Friction	5	0.01	Negative	None	None							
1	2	200A	Classroom 200 - Closet	yes	W1	Concrete	Light Green	None	0	N/A	N/A	None	None							
1	2	200A	Classroom 200 - Closet	yes	W2	Concrete	Light Green	None	0	N/A	N/A	None	None							
1	2	200A	Classroom 200 - Closet	yes	W3	Concrete	Light Green	None	0	N/A	N/A	None	None							
1	2	200A	Classroom 200 - Closet	yes	W4	Concrete	Light Green	None	0	N/A	N/A	None	None							
1	2	200A	Classroom 200 - Closet	yes	Ceiling	Sheetrock	Light Green	None	0	N/A	N/A	None	None							
1	2	200A	Classroom 200 - Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	None							
1	2	201	Classroom 201	yes	W1	Concrete	Green	Moisture Damage	10	0.03	Negative	None	None						Cracks in CMU Blocks	
1	2	201	Classroom 201	yes	W2	Concrete	Green	Cracking	2	0	Negative	None	None							
1	2	201	Classroom 201	yes	W3	Concrete	Green	None	0	N/A	N/A	None	None						Cracks in CMU Blocks	
1	2	201	Classroom 201	yes	W4	Concrete	Green	Cracking	4	0	Negative	None	None							
1	2	201	Classroom 201	yes	Radiator	Metal	Tan	Friction	1	0.01	Negative	None	None							
1	2	201	Classroom 201	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	None						12x12 Ceiling Tile	
1	2	201	Classroom 201	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	None						9x9 FT	
1	2	201A	Classroom 201 - Closet	yes	W1	Concrete	Beige	None	0	N/A	N/A	None	None							
1	2	201A	Classroom 201 - Closet	yes	W2	Concrete	Beige	None	0	N/A	N/A	None	None							
1	2	201A	Classroom 201 - Closet	yes	W3	Concrete	Beige	Cracking	4	0.11	Negative	None	None						Cracks in CMU Blocks	
1	2	201A	Classroom 201 - Closet	yes	W4	Concrete	Beige	None	0	N/A	N/A	None	None							
1	2	201A	Classroom 201 - Closet	yes	Ceiling	Sheetrock	White	None	0	N/A	N/A	None	None							
1	2	201A	Classroom 201 - Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	None							
1	2	S2S	Stairwell by Classrooms 200 and 201	yes	W1	Concrete / Ceramic	Beige	None	0	N/A	N/A	None	None							
1	2	S2S	Stairwell by Classrooms 200 and 201	yes	W2	Concrete / Ceramic	Beige	None	0	N/A	N/A	None	None							
1	2	S2S	Stairwell by Classrooms 200 and 201	yes	W3	Concrete / Ceramic	Beige	None	0	N/A	N/A	None	None							
1	2	S2S	Stairwell by Classrooms 200 and 201	yes	W4	Concrete / Ceramic	Beige	None	0	N/A	N/A	None	None							
1	2	S2S	Stairwell by Classrooms 200 and 201	yes	Ceiling	Concrete	White	None	0	N/A	N/A	None	None							
1	2	S2S	Stairwell by Classrooms 200 and 201	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	None						Terracotta Tile	
1	2	S2S	Stairwell by Classrooms 200 and 201	yes	Stair Railing	Metal	Tan	Chipping	1	0.08	Negative	None	None							
1	2	S2S	Stairwell by Classrooms 200 and 201	yes	Stair Riser	Metal	Gray	None	0	N/A	N/A	None	None							
1	2	S2S	Stairwell by Classrooms 200 and 201	yes	Stair Riser	Metal	Tan	Rust	3	0.06	Negative	None	None							
1	2	H24	Hallway from Classrooms 200 to 213	yes	W1	Concrete / Ceramic	White	None	0	N/A	N/A	None	None							
1	2	H24	Hallway from Classrooms 200 to 213	yes	W2	Concrete / Ceramic	White	None	0	0.12	Negative	None	None							
1	2	H24	Hallway from Classrooms 200 to 213	yes	W3	Concrete / Ceramic	White	None	0	N/A	N/A	None	None							
1	2	H24	Hallway from Classrooms 200 to 213	yes	W4	Concrete / Ceramic	White	None	0	N/A	N/A	None	None							
1	2	H24	Hallway from Classrooms 200 to 213	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	None						12x12 Ceiling Tile	
1	2	H24	Hallway from Classrooms 200 to 213	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	None						Terracotta Tile	
1	3	313	Classroom 313	yes	W1	Concrete	Beige	None	0	N/A	N/A	None	None							
1	3	313	Classroom 313	yes	W2	Concrete	Beige	None	0	N/A	N/A	None	None							
1	3	313	Classroom 313	yes	W3	Concrete	Blue	Chipping	1	0	Negative	None	None							
1	3	313	Classroom 313	yes	W4	Concrete	Beige	None	0	N/A	N/A	None	None							
1	3	313	Classroom 313	yes	Radiator	Metal	Blue	Rust	1	0	Negative	None	None							
1	3	313	Classroom 313	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	None						2x4 Ceiling Tile	
1	3	313	Classroom 313	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	None						12x12 FT	
1	3	313A	Classroom 313 - Closet	yes	W1	Concrete	Beige	None	0	N/A	N/A	None	None							
1	3	313A	Classroom 313 - Closet	yes	W2	Concrete	Beige	None	0	N/A	N/A	None	None							
1	3	313A	Classroom 313 - Closet	yes	W3	Concrete	Beige	None	0	N/A	N/A	None	None							
1	3	313A	Classroom 313 - Closet	yes	W4	Concrete	Beige	None	0	N/A	N/A	None	None							
1	3	313A	Classroom 313 - Closet	yes	Ceiling	Sheetrock	Beige	None	0	N/A	N/A	None	None							
1	3	313A	Classroom 313 - Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	None						12x12 FT	
1	3	S1N	Stairwell near Classrooms 312 and 313	yes	W1	Concrete / Ceramic	Beige	Cracking	1	0.09	Negative	None	None							
1	3	S1N	Stairwell near Classrooms 312 and 313	yes	W2	Concrete / Ceramic	Beige	Moisture Damage	10	0.09	Negative	None	None						Cracks in CMU Blocks	
1	3	S1N	Stairwell near Classrooms 312 and 313	yes	W3	Concrete / Ceramic	Beige	Moisture Damage	4	0.04	Negative	None	None						Cracks in CMU Blocks	
1	3	S1N	Stairwell near Classrooms 312 and 313	yes	W4	Concrete / Ceramic	Beige	None	0	N/A	N/A	None	None						Cracks in CMU Blocks	

					School District of Philadelphia														
			Name of Inspector: Suzanne Shourds and Shalaunda Gourdine		Lead Safe Certification Assessment Report							Inspection Dates: 9/20-29/2021							
			Inspection Company: React		Farrell School							ULCS# 8380							
E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes
1	3	S1N	Stairwell near Classrooms 312 and 313	yes	Radiator	Metal	Tan	None	0	N/A	N/A	None	None						12x12 Ceiling Tile
1	3	S1N	Stairwell near Classrooms 312 and 313	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	None						Terracotta Tile
1	3	S1N	Stairwell near Classrooms 312 and 313	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	None						Terracotta Tile
1	3	S1N	Stairwell near Classrooms 312 and 313	yes	Stair Railing	Metal	Tan	None	0	N/A	N/A	None	None						
1	3	S1N	Stairwell near Classrooms 312 and 313	yes	Stair Riser	Metal	Gray	None	0	N/A	N/A	None	None						
1	3	312	Classroom 312	yes	W1	Concrete	Yellow	Flaking	4	0.02	Negative	None	None						
1	3	312	Classroom 312	yes	W2	Concrete	Yellow	None	0	N/A	N/A	None	None						
1	3	312	Classroom 312	yes	W3	Concrete	Yellow	None	0	N/A	N/A	None	None						
1	3	312	Classroom 312	yes	W4	Concrete	Yellow	Chipping	1	0	Negative	None	None						
1	3	312	Classroom 312	yes	Radiator	Metal	Tan	Friction	1	0.02	Negative	None	None						12x12 Ceiling Tile
1	3	312	Classroom 312	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	None						12x12 Ceiling Tile
1	3	312	Classroom 312	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	None						9x9 FT
1	3	312A	Classroom 312 - Closet	yes	W1	Concrete	Beige	None	0	N/A	N/A	None	None						
1	3	312A	Classroom 312 - Closet	yes	W2	Concrete	Beige	None	0	N/A	N/A	None	None						
1	3	312A	Classroom 312 - Closet	yes	W3	Concrete	Beige	None	0	N/A	N/A	None	None						
1	3	312A	Classroom 312 - Closet	yes	W4	Concrete	Beige	None	0	N/A	N/A	None	None						
1	3	312A	Classroom 312 - Closet	yes	Ceiling	Sheetrock	Beige	None	0	N/A	N/A	None	None						
1	3	312A	Classroom 312 - Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	None						9x9 FT
1	3	312A	Classroom 312 - Closet	yes	Duct Work	Metal	Beige	Chipping	1	0.04	Negative	None	None						
1	3	311	Classroom 311	yes	W1	Concrete	Beige	Friction	1	0	Negative	None	None						
1	3	311	Classroom 311	yes	W2	Concrete	Beige	None	0	N/A	N/A	None	None						
1	3	311	Classroom 311	yes	W3	Concrete	Beige	None	0	N/A	N/A	None	None						
1	3	311	Classroom 311	yes	W4	Concrete	Blue	Chipping	1	0	Negative	None	None						
1	3	311	Classroom 311	yes	Radiator	Metal	Blue	Friction	1	0.04	Negative	None	None						
1	3	311	Classroom 311	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	None						2x4 Ceiling Tile
1	3	311	Classroom 311	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	None						12x12 FT
1	3	311A	Classroom 311 - Closet	yes	W1	Concrete	Beige	None	0	N/A	N/A	None	None						
1	3	311A	Classroom 311 - Closet	yes	W2	Concrete	Beige	None	0	N/A	N/A	None	None						
1	3	311A	Classroom 311 - Closet	yes	W3	Concrete	Beige	None	0	N/A	N/A	None	None						
1	3	311A	Classroom 311 - Closet	yes	W4	Concrete	Beige	None	0	N/A	N/A	None	None						
1	3	311A	Classroom 311 - Closet	yes	Ceiling	Sheetrock	Beige	None	0	N/A	N/A	None	None						
1	3	311A	Classroom 311 - Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	None						12x12 FT
1	3	310	Classroom 310	yes	W1	Concrete	Light Blue	None	0	N/A	N/A	None	None						
1	3	310	Classroom 310	yes	W2	Concrete	Light Blue	None	0	N/A	N/A	None	None						
1	3	310	Classroom 310	yes	W3	Concrete	Light Blue	Cracking	2	0	Negative	None	None						
1	3	310	Classroom 310	yes	W4	Concrete	Light Blue	None	0	N/A	N/A	None	None						
1	3	310	Classroom 310	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	None						12x12 Ceiling Tile
1	3	310	Classroom 310	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	None						9x9 FT
1	3	310	Classroom 310	yes	Radiator	Metal	Tan	None	0	N/A	N/A	None	None						
1	3	310A	Classroom 310 - Closet	yes	W1	Concrete	Yellow	None	0	N/A	N/A	None	None						
1	3	310A	Classroom 310 - Closet	yes	W2	Concrete	Yellow	None	0	N/A	N/A	None	None						
1	3	310A	Classroom 310 - Closet	yes	W3	Concrete	Yellow	None	0	N/A	N/A	None	None						
1	3	310A	Classroom 310 - Closet	yes	W4	Concrete	Yellow	None	0	N/A	N/A	None	None						
1	3	310A	Classroom 310 - Closet	yes	Ceiling	Sheetrock	N/A	N/A	N/A	N/A	N/A	None	None						
1	3	310A	Classroom 310 - Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	None						9x9 FT
1	3	308	Classroom 308	yes	W1	Concrete	Yellow	None	0	N/A	N/A	None	None						
1	3	308	Classroom 308	yes	W2	Concrete	Yellow	None	0	N/A	N/A	None	None						
1	3	308	Classroom 308	yes	W3	Concrete	Yellow	Cracking	3	0.7	Positive	None	None						
1	3	308	Classroom 308	yes	W4	Concrete	Yellow	None	0	N/A	N/A	None	None						
1	3	308	Classroom 308	yes	Radiator	Metal	Tan	None	0	N/A	N/A	None	None						12x12 Ceiling Tile
1	3	308	Classroom 308	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	None						12x12 Ceiling Tile
1	3	308	Classroom 308	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	None						9x9 FT
1	3	308A	Classroom 308 - Closet	yes	W1	Concrete	Yellow	None	0	N/A	N/A	None	None						
1	3	308A	Classroom 308 - Closet	yes	W2	Concrete	Yellow	None	0	N/A	N/A	None	None						
1	3	308A	Classroom 308 - Closet	yes	W3	Concrete	Yellow	None	0	N/A	N/A	None	None						
1	3	308A	Classroom 308 - Closet	yes	W4	Concrete	Yellow	None	0	N/A	N/A	None	None						
1	3	308A	Classroom 308 - Closet	yes	Ceiling	Sheetrock	N/A	N/A	N/A	N/A	N/A	None	None						12x12 Ceiling Tile
1	3	308A	Classroom 308 - Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	None						
1	3	309	Classroom 309	yes	W1	Concrete	Beige	None	0	N/A	N/A	None	None						
1	3	309	Classroom 309	yes	W2	Concrete	Beige	None	0	N/A	N/A	None	None						
1	3	309	Classroom 309	yes	W3	Concrete	Beige	Chipping	3	0.12	Negative	None	None						
1	3	309	Classroom 309	yes	W4	Concrete	Orange	None	0	N/A	N/A	None	None						
1	3	309	Classroom 309	yes	Radiator	Metal	Orange	Rust	1	0.01	Negative	None	None						
1	3	309	Classroom 309	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	None						2x4 Ceiling Tile
1	3	309	Classroom 309	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	None						12x12 FT
1	3	306	Classroom 306	yes	W1	Concrete	Beige	None	0	N/A	N/A	None	None						
1	3	306	Classroom 306	yes	W2	Concrete	Beige	Chipping	1	0.1	Negative	None	None						
1	3	306	Classroom 306	yes	W3	Concrete	Beige	Chipping	1	0	Negative	None	None						
1	3	306	Classroom 306	yes	W4	Concrete	Blue	Chipping	1	0	Negative	None	None						
1	3	306	Classroom 306	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	None						2x4 Ceiling Tile
1	3	306	Classroom 306	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	None						
1	3	306	Classroom 306	yes	Radiator	Metal	Tan	Flaking	1	0	Negative	None	None						
1	3	306A	Classroom 306 - Closet	yes	W1	Concrete	Beige	None	0	N/A	N/A	None	None						

					School District of Philadelphia														
			Name of Inspector: Suzanne Shourds and Shalaunda Gourdine		Lead Safe Certification Assessment Report							Inspection Dates: 9/20-29/2021							
			Inspection Company: React		Farrell School							ULCS# 8380							
E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes
1	3	306A	Classroom 306 - Closet	yes	W2	Concrete	Beige	None	0	N/A	N/A	None	None						
1	3	306A	Classroom 306 - Closet	yes	W3	Concrete	Beige	None	0	N/A	N/A	None	None						
1	3	306A	Classroom 306 - Closet	yes	W4	Concrete	Beige	None	0	N/A	N/A	None	None						
1	3	306A	Classroom 306 - Closet	yes	Ceiling	Sheetrock	Beige	N/A	N/A	N/A	N/A	None	None						
1	3	306A	Classroom 306 - Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	None						
1	3	307	Classroom 307	yes	W1	Concrete	Green	None	0	N/A	N/A	None	None						
1	3	307	Classroom 307	yes	W2	Concrete	Green	Chipping	2	0	Negative	None	None						
1	3	307	Classroom 307	yes	W3	Concrete	Green	Cracking	3	0	Negative	None	None						
1	3	307	Classroom 307	yes	W4	Concrete	Green	None	0	N/A	N/A	None	None						
1	3	307	Classroom 307	yes	Radiator	Metal	Tan	None	0	N/A	N/A	None	None						
1	3	307	Classroom 307	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	None						12x12 Ceiling Tile
1	3	307	Classroom 307	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	None						9x9 FT
1	3	307A	Classroom 307 - Closet	yes	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	3	307A	Classroom 307 - Closet	yes	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	3	307A	Classroom 307 - Closet	yes	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	3	307A	Classroom 307 - Closet	yes	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	3	307A	Classroom 307 - Closet	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	3	307A	Classroom 307 - Closet	yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	3	304A	Girl's Restroom near Classroom 307	yes	W1	Concrete / Ceramic	Beige	None	0	N/A	N/A	None	None						
1	3	304A	Girl's Restroom near Classroom 307	yes	W2	Concrete / Ceramic	Beige	None	0	N/A	N/A	None	None						
1	3	304A	Girl's Restroom near Classroom 307	yes	W3	Concrete / Ceramic	Beige	None	0	N/A	N/A	None	None						
1	3	304A	Girl's Restroom near Classroom 307	yes	W4	Concrete / Ceramic	Beige	None	0	N/A	N/A	None	None						
1	3	304A	Girl's Restroom near Classroom 307	yes	Ceiling	Sheetrock	White	Flaking	5	0.05	Negative	None	None						
1	3	304A	Girl's Restroom near Classroom 307	yes	Floor	Ceramic	N/A	N/A	N/A	N/A	N/A	None	None						
1	3	304A	Girl's Restroom near Classroom 307	yes	Radiator	Metal	Tan	Flaking	1	0.02	Negative	None	None						
1	3	304	Boy's Restroom near Classroom 305	yes	W1	Concrete / Ceramic	Beige	None	0	N/A	N/A	None	None						
1	3	304	Boy's Restroom near Classroom 305	yes	W2	Concrete / Ceramic	Beige	None	0	N/A	N/A	None	None						
1	3	304	Boy's Restroom near Classroom 305	yes	W3	Concrete / Ceramic	Beige	None	0	N/A	N/A	None	None						
1	3	304	Boy's Restroom near Classroom 305	yes	W4	Concrete / Ceramic	Beige	None	0	N/A	N/A	None	None						
1	3	304	Boy's Restroom near Classroom 305	yes	Ceiling	Sheetrock	Beige	None	0	N/A	N/A	None	None						
1	3	304	Boy's Restroom near Classroom 305	yes	Floor	Ceramic	N/A	N/A	N/A	N/A	N/A	None	None						
1	3	S1W	Stairwell across from Classroom 305	yes	W1	Concrete / Ceramic	Beige	None	0	N/A	N/A	None	None						
1	3	S1W	Stairwell across from Classroom 305	yes	W2	Concrete / Ceramic	Beige	None	0	N/A	N/A	None	None						Cracks in CMU Blocks
1	3	S1W	Stairwell across from Classroom 305	yes	W3	Concrete / Ceramic	Beige	None	0	0.08	Negative	None	None						Cracks in CMU Blocks
1	3	S1W	Stairwell across from Classroom 305	yes	W4	Concrete / Ceramic	Beige	None	0	0.1	Negative	None	None						Cracks in CMU Blocks
1	3	S1W	Stairwell across from Classroom 305	yes	Radiator	Metal	Tan	None	0	N/A	N/A	None	None						
1	3	S1W	Stairwell across from Classroom 305	yes	Ceiling	N/A	N/A	Moisture Damage	10	N/A	N/A	None	None						12x12 Ceiling Tile
1	3	S1W	Stairwell across from Classroom 305	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	None						Terracotta Tile
1	3	S1W	Stairwell across from Classroom 305	yes	Stair Railing	Metal	Tan	None	0	N/A	N/A	None	None						
1	3	S1W	Stairwell across from Classroom 305	yes	Stair Riser	Metal	Green	None	0	N/A	N/A	None	None						
1	3	302A	Women's Restroom across from Classroom 305	yes	W1	Concrete / Ceramic	Pink	None	0	N/A	N/A	None	None						
1	3	302A	Women's Restroom across from Classroom 305	yes	W2	Concrete / Ceramic	Pink	None	0	N/A	N/A	None	None						
1	3	302A	Women's Restroom across from Classroom 305	yes	W3	Concrete / Ceramic	Pink	None	0	N/A	N/A	None	None						
1	3	302A	Women's Restroom across from Classroom 305	yes	W4	Concrete / Ceramic	Pink	None	0	N/A	N/A	None	None						
1	3	302A	Women's Restroom across from Classroom 305	yes	Ceiling	Sheetrock	White	Moisture Damage	3	0.7	Positive	None	None						
1	3	302A	Women's Restroom across from Classroom 305	yes	Floor	Ceramic	N/A	N/A	N/A	N/A	N/A	None	None						
1	3	302B	Men's Restroom across from Classroom 305	yes	W1	Concrete / Ceramic	Light Blue	None	0	N/A	N/A	None	None						
1	3	302B	Men's Restroom across from Classroom 305	yes	W2	Concrete / Ceramic	Light Blue	None	0	N/A	N/A	None	None						
1	3	302B	Men's Restroom across from Classroom 305	yes	W3	Concrete / Ceramic	Light Blue	None	0	N/A	N/A	None	None						
1	3	302B	Men's Restroom across from Classroom 305	yes	W4	Concrete / Ceramic	Light Blue	None	0	N/A	N/A	None	None						
1	3	302B	Men's Restroom across from Classroom 305	yes	Ceiling	Sheetrock	White	Moisture Damage	2	0.7	Positive	None	None						
1	3	302B	Men's Restroom across from Classroom 305	yes	Floor	Ceramic	N/A	N/A	N/A	N/A	N/A	None	None						
1	3	304B	Custodial Closet across from Classroom 307	yes	W1	Concrete	Yellow	Moisture Damage	2	0.02	Negative	None	None						
1	3	304B	Custodial Closet across from Classroom 307	yes	W2	Concrete	Yellow	None	0	N/A	N/A	None	None						
1	3	304B	Custodial Closet across from Classroom 307	yes	W3	Concrete	Yellow	None	0	N/A	N/A	None	None						
1	3	304B	Custodial Closet across from Classroom 307	yes	W4	Concrete	Yellow	None	0	N/A	N/A	None	None						
1	3	304B	Custodial Closet across from Classroom 307	yes	Ceiling	Sheetrock	White	Moisture Damage	2	0.7	Positive	None	None						
1	3	304B	Custodial Closet across from Classroom 307	yes	Floor	Concrete	Black	None	0	N/A	N/A	None	None						
1	3	PC304B	Pipe Chase in Custodial Closet across from Classroom 307	yes	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	3	PC304B	Pipe Chase in Custodial Closet across from Classroom 307	yes	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	3	PC304B	Pipe Chase in Custodial Closet across from Classroom 307	yes	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	3	PC304B	Pipe Chase in Custodial Closet across from Classroom 307	yes	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	3	PC304B	Pipe Chase in Custodial Closet across from Classroom 307	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	3	PC304B	Pipe Chase in Custodial Closet across from Classroom 307	yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	3	305	Classroom 305	yes	W1	Concrete	Beige	None	0	0	Negative	None	None						Cracks in CMU Blocks
1	3	305	Classroom 305	yes	W2	Concrete	Beige	None	0	N/A	N/A	None	None						
1	3	305	Classroom 305	yes	W3	Concrete	Beige	Chipping	5	0.09	Negative	None	None						
1	3	305	Classroom 305	yes	W4	Concrete	Beige	Chipping	2	0	Negative	None	None						
1	3	305	Classroom 305	yes	Radiator	Metal	Tan	None	0	N/A	N/A	None	None						

					School District of Philadelphia															
			Name of Inspector: Suzanne Shourds and Shalaunda Gourdine		Lead Safe Certification Assessment Report							Inspection Dates: 9/20-29/2021								
			Inspection Company: React		Farrell School							ULCS# 8380								
E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes	
1	3	305	Classroom 305	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	None						12x12 Ceiling Tile	
1	3	305	Classroom 305	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	None						9x9 FT	
1	3	305A	Classroom 305 - Closet	yes	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access		
1	3	305A	Classroom 305 - Closet	yes	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access		
1	3	305A	Classroom 305 - Closet	yes	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access		
1	3	305A	Classroom 305 - Closet	yes	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access		
1	3	305A	Classroom 305 - Closet	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access		
1	3	305A	Classroom 305 - Closet	yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access		
1	3	302C	Academic Enrichment Office	yes	W1	Concrete	Beige	Friction	1	0.04	Negative	None	None							
1	3	302C	Academic Enrichment Office	yes	W2	Concrete	Beige	None	0	N/A	N/A	None	None							
1	3	302C	Academic Enrichment Office	yes	W3	Concrete	Beige	None	0	N/A	N/A	None	None							
1	3	302C	Academic Enrichment Office	yes	W4	Sheetrock	Beige	Flaking	2	0	Negative	None	None							
1	3	302C	Academic Enrichment Office	yes	Ceiling	Sheetrock	Beige	None	0	N/A	N/A	None	None							
1	3	302C	Academic Enrichment Office	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	None							
1	3	302	Classroom 302	yes	W1	Concrete	Yellow	Flaking	1	0	Negative	None	None							
1	3	302	Classroom 302	yes	W2	Concrete	Yellow/ Light Blue	None	0	N/A	N/A	None	None							
1	3	302	Classroom 302	yes	W3	Concrete	Yellow	Chipping	1	0	Negative	None	None							
1	3	302	Classroom 302	yes	W4	Concrete	Yellow	None	0	N/A	N/A	None	None							
1	3	302	Classroom 302	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	None						12x12 Ceiling Tile	
1	3	302	Classroom 302	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	None						12x12 FT	
1	3	302	Classroom 302	yes	Radiator	Metal	Tan	Friction	10	0.03	Negative	None	None							
1	3	302CL	Classroom 302 - Closet	yes	W1	Concrete	Light Blue	None	0	N/A	N/A	None	None							
1	3	302CL	Classroom 302 - Closet	yes	W2	Concrete	Light Blue	None	0	N/A	N/A	None	None							
1	3	302CL	Classroom 302 - Closet	yes	W3	Concrete	Light Blue	None	0	N/A	N/A	None	None							
1	3	302CL	Classroom 302 - Closet	yes	W4	Concrete	Light Blue	None	0	N/A	N/A	None	None							
1	3	302CL	Classroom 302 - Closet	yes	Ceiling	Sheetrock	Light Blue	None	0	N/A	N/A	None	None							
1	3	302CL	Classroom 302 - Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	None						12x12 FT	
1	3	303	Classroom 303	yes	W1	Concrete	Yellow	None	0	N/A	N/A	None	None							
1	3	303	Classroom 303	yes	W2	Concrete	Yellow	None	0	N/A	N/A	None	None							
1	3	303	Classroom 303	yes	W3	Concrete	Yellow	Chipping	2	0	Negative	None	None						Cracks in CMU Blocks	
1	3	303	Classroom 303	yes	W4	Concrete	Yellow	None	0	N/A	N/A	None	None							
1	3	303	Classroom 303	yes	Radiator	Metal	Tan	None	0	N/A	N/A	None	None							
1	3	303	Classroom 303	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	None						12x12 Ceiling Tile	
1	3	303	Classroom 303	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	None						9x9 FT	
1	3	303A	Classroom 303 - Closet	yes	W1	Concrete	Yellow	None	0	N/A	N/A	None	None							
1	3	303A	Classroom 303 - Closet	yes	W2	Concrete	Yellow	None	0	N/A	N/A	None	None							
1	3	303A	Classroom 303 - Closet	yes	W3	Concrete	Yellow	None	0	N/A	N/A	None	None							
1	3	303A	Classroom 303 - Closet	yes	W4	Concrete	Yellow	None	0	N/A	N/A	None	None							
1	3	303A	Classroom 303 - Closet	yes	Ceiling	Sheetrock	Yellow	None	0	N/A	N/A	None	None							
1	3	303A	Classroom 303 - Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	None						12x12 FT	
1	3	300	Classroom 300	yes	W1	Concrete	Light Blue / Green	None	5	0	Negative	None	None							
1	3	300	Classroom 300	yes	W2	Concrete	Light Blue / Green	Flaking	5	0.06	Negative	None	None							
1	3	300	Classroom 300	yes	W3	Concrete	Light Blue / Green	None	0	N/A	N/A	None	None							
1	3	300	Classroom 300	yes	W4	Concrete	Light Blue / Green	Flaking	5	0	Negative	None	None							
1	3	300	Classroom 300	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	None						12x12 Ceiling Tile	
1	3	300	Classroom 300	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	None						9x9 FT	
1	3	300	Classroom 300	yes	Radiator	Metal	Tan	Friction	2	0.02	Negative	None	None							
1	3	300A	Classroom 300 - Closet	yes	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access		
1	3	300A	Classroom 300 - Closet	yes	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access		
1	3	300A	Classroom 300 - Closet	yes	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access		
1	3	300A	Classroom 300 - Closet	yes	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access		
1	3	300A	Classroom 300 - Closet	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access		
1	3	300A	Classroom 300 - Closet	yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access		
1	3	301	Classroom 301 (Computer Lab)	yes	W1	Concrete	Beige	Chipping	3	0.02	Negative	None	None						Cracks in CMU Blocks	
1	3	301	Classroom 301 (Computer Lab)	yes	W2	Concrete	Beige	Partially Inaccessible	1	0.06	Negative	None	None							
1	3	301	Classroom 301 (Computer Lab)	yes	W3	Concrete	Beige	Flaking	3	0	Negative	None	None						Cracks in CMU Blocks	
1	3	301	Classroom 301 (Computer Lab)	yes	W4	Concrete	Beige	Flaking	1	0.05	Negative	None	None						Cracks in CMU Blocks	
1	3	301	Classroom 301 (Computer Lab)	yes	Radiator	Metal	Tan	Friction	1	0.01	Negative	None	None							
1	3	301	Classroom 301 (Computer Lab)	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	None						12x12 Ceiling Tile	
1	3	301	Classroom 301 (Computer Lab)	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	None						9x9 FT	
1	3	301A	Classroom 301 - Closet	yes	W1	Concrete	Beige	None	0	N/A	N/A	None	None							
1	3	301A	Classroom 301 - Closet	yes	W2	Concrete	Beige	None	0	N/A	N/A	None	None							
1	3	301A	Classroom 301 - Closet	yes	W3	Concrete	Beige	None	0	0.03	Negative	None	None						Cracks in CMU Blocks	
1	3	301A	Classroom 301 - Closet	yes	W4	Concrete	Beige	None	0	N/A	N/A	None	None							
1	3	301A	Classroom 301 - Closet	yes	Ceiling	Sheetrock	Beige	None	0	N/A	N/A	None	None							
1	3	301A	Classroom 301 - Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	None						9x9 FT	
1	3	S1S	Stairwell near Classrooms 300 and 301	yes	W1	Concrete / Ceramic	Beige	Cracking	3	0.04	Negative	None	None							
1	3	S1S	Stairwell near Classrooms 300 and 301	yes	W2	Concrete / Ceramic	Beige	Moisture Damage	8	0.06	Negative	None	None							
1	3	S1S	Stairwell near Classrooms 300 and 301	yes	W3	Concrete / Ceramic	Beige	Moisture Damage	4	0.06	Negative	None	None							

			School District of Philadelphia																										
			Name of Inspector: Suzanne Shourds and Shalaunda Gourdine																Inspection Dates: 9/20-29/2021										
			Lead Safe Certification Assessment Report																										
			Inspection Company: React										Farrell School										ULCS# 8380						
E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes										
1	3	S1S	Stairwell near Classrooms 300 and 301	yes	W4	Concrete / Ceramic	Beige	None	0	N/A	N/A	None	None						Cracks in CMU Blocks										
1	3	S1S	Stairwell near Classrooms 300 and 301	yes	Radiator	Metal	Tan	None	0	N/A	N/A	None	None						12x12 Ceiling Tile										
1	3	S1S	Stairwell near Classrooms 300 and 301	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	None						12x12 Ceiling Tile										
1	3	S1S	Stairwell near Classrooms 300 and 301	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	None						Terracotta Tile										
1	3	S1S	Stairwell near Classrooms 300 and 301	yes	Stair Railing	Metal	Tan	None	0	N/A	N/A	None	None																
1	3	S1S	Stairwell near Classrooms 300 and 301	yes	Stair Riser	Metal	Gray	None	0	N/A	N/A	None	None																
1	3	H3	Hallway from Classrooms 300 to 313	yes	W1	Concrete / Ceramic	White	None	0	N/A	N/A	None	None																
1	3	H3	Hallway from Classrooms 300 to 313	yes	W2	Concrete / Ceramic	White	None	0	N/A	N/A	None	None																
1	3	H3	Hallway from Classrooms 300 to 313	yes	W3	Concrete / Ceramic	White	None	0	N/A	N/A	None	None																
1	3	H3	Hallway from Classrooms 300 to 313	yes	W4	Concrete / Ceramic	White	None	0	0.08	Negative	None	None																
1	3	H3	Hallway from Classrooms 300 to 313	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	None						12x12 Ceiling Tile										
1	3	H3	Hallway from Classrooms 300 to 313	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	None						Terracotta Tile										
1	AT	AT	Attic	no	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access											
1	AT	AT	Attic	no	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access											
1	AT	AT	Attic	no	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access											
1	AT	AT	Attic	no	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access											
1	AT	AT	Attic	no	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access											
1	AT	AT	Attic	no	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access											
1	CS	CS1	Crawl Space - Boy's Rest Room	no	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access											
1	CS	CS1	Crawl Space - Boy's Rest Room	no	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access											
1	CS	CS1	Crawl Space - Boy's Rest Room	no	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access											
1	CS	CS1	Crawl Space - Boy's Rest Room	no	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access											
1	CS	CS1	Crawl Space - Boy's Rest Room	no	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access											
1	CS	CS1	Crawl Space - Boy's Rest Room	no	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access											
2	CS	CS2	Crawl Space - Northeast Mechanical/HVAC Room	no	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access											
2	CS	CS2	Crawl Space - Northeast Mechanical/HVAC Room	no	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access											
2	CS	CS2	Crawl Space - Northeast Mechanical/HVAC Room	no	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access											
2	CS	CS2	Crawl Space - Northeast Mechanical/HVAC Room	no	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access											
2	CS	CS2	Crawl Space - Northeast Mechanical/HVAC Room	no	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access											
2	CS	CS2	Crawl Space - Northeast Mechanical/HVAC Room	no	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access											
8	1	S11	Stairwell next to Classrooms A15 and A16	yes	W1	Concrete	Orange	None	0	N/A	N/A	None	None						New Building built post 2015										
8	1	S11	Stairwell next to Classrooms A15 and A16	yes	W2	Concrete	Orange	None	0	N/A	N/A	None	None						New Building built post 2015										
8	1	S11	Stairwell next to Classrooms A15 and A16	yes	W3	Concrete	Orange	None	0	N/A	N/A	None	None						New Building built post 2015										
8	1	S11	Stairwell next to Classrooms A15 and A16	yes	W4	Concrete	Orange	None	0	N/A	N/A	None	None						New Building built post 2015										
8	1	S11	Stairwell next to Classrooms A15 and A16	yes	Ceiling	Metal	Gray	None	0	N/A	N/A	None	None						New Building built post 2015										
8	1	S11	Stairwell next to Classrooms A15 and A16	yes	Floor	Concrete	N/A	None	0	N/A	N/A	None	None						New Building built post 2015										
8	1	A15	Classroom A15	yes	W1	Concrete	Blue	None	0	N/A	N/A	None	None						New Building built post 2015										
8	1	A15	Classroom A15	yes	W2	Sheetrock	Light Blue	None	0	N/A	N/A	None	None						New Building built post 2015										
8	1	A15	Classroom A15	yes	W3	Sheetrock	White	None	0	N/A	N/A	None	None						New Building built post 2015										
8	1	A15	Classroom A15	yes	W4	Sheetrock	White	None	0	N/A	N/A	None	None						New Building built post 2015										
8	1	A15	Classroom A15	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	None						New Building built post 2015										
8	1	A15	Classroom A15	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	None						New Building built post 2015										
8	1	A16	Classroom A16	yes	W1	Concrete	Blue	None	0	N/A	N/A	None	None						New Building built post 2015										
8	1	A16	Classroom A16	yes	W2	Sheetrock	White	None	0	N/A	N/A	None	None						New Building built post 2015										
8	1	A16	Classroom A16	yes	W3	Sheetrock	White	None	0	N/A	N/A	None	None						New Building built post 2015										
8	1	A16	Classroom A16	yes	W4	Sheetrock	Light Blue	None	0	N/A	N/A	None	None						New Building built post 2015										
8	1	A16	Classroom A16	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	None						New Building built post 2015										
8	1	A16	Classroom A16	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	None						New Building built post 2015										
8	1	A13	Classroom A13	yes	W1	Concrete	Blue	None	0	N/A	N/A	None	None						New Building built post 2015										
8	1	A13	Classroom A13	yes	W2	Sheetrock	White	None	0	N/A	N/A	None	None						New Building built post 2015										
8	1	A13	Classroom A13	yes	W3	Sheetrock	White	None	0	N/A	N/A	None	None						New Building built post 2015										
8	1	A13	Classroom A13	yes	W4	Sheetrock	Light Blue	None	0	N/A	N/A	None	None						New Building built post 2015										
8	1	A13	Classroom A13	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	None						New Building built post 2015										
8	1	A13	Classroom A13	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	None						New Building built post 2015										
8	1	A14	Classroom A14	yes	W1	Concrete	Blue	None	0	N/A	N/A	None	None						New Building built post 2015										
8	1	A14	Classroom A14	yes	W2	Sheetrock	Light Blue	None	0	N/A	N/A	None	None						New Building built post 2015										
8	1	A14	Classroom A14	yes	W3	Sheetrock	White	None	0	N/A	N/A	None	None						New Building built post 2015										
8	1	A14	Classroom A14	yes	W4	Sheetrock	White	None	0	N/A	N/A	None	None						New Building built post 2015										
8	1	A14	Classroom A14	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	None						New Building built post 2015										
8	1	A14	Classroom A14	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	None						New Building built post 2015										
8	1	A11	Classroom A11	yes	W1	Concrete	Green	None	0	N/A	N/A	None	None						New Building built post 2015										
8	1	A11	Classroom A11	yes	W2	Concrete	White	None	0	N/A	N/A	None	None						New Building built post 2015										
8	1	A11	Classroom A11	yes	W3	Sheetrock	White	None	0	N/A	N/A	None	None						New Building built post 2015										
8	1	A11	Classroom A11	yes	W4	Sheetrock	Light Green	None	0	N/A	N/A	None	None						New Building built post 2015										
8	1	A11	Classroom A11	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	None						New Building built post 2015										
8	1	A11	Classroom A11	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	None						New Building built post 2015										
8	1	A12	Classroom A12	yes	W1	Concrete	Green	None	0	N/A	N/A	None	None						New Building built post 2015										
8	1	A12	Classroom A12	yes	W2	Sheetrock	Light Green	None	0	N/A	N/A	None	None						New Building built post 2015										
8	1	A12	Classroom A12	yes	W3	Sheetrock	White	None	0	N/A	N/A	None	None						New Building built post 2015										
8	1	A12	Classroom A12	yes	W4	Sheetrock/Concrete	Green/White	None	0	N/A	N/A	None	None						New Building built post 2015										
8	1	A12	Classroom A12	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	None						New Building built post 2015										
8	1	A12	Classroom A12	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	None						New Building built post 2015										
8	1	H11	Hallway along Classrooms A11 to A16	yes	W1	Concrete	Cream	None	0	N/A	N/A	None	None						New Building built post 2015										



						School District of Philadelphia														
				Name of Inspector: Suzanne Shourds and Shalaunda Gourdine		Lead Safe Certification Assessment Report							Inspection Dates: 9/20-29/2021							
				Inspection Company: React		Farrell School							ULCS# 8380							
E l e m e n t	F l o o r		Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes
8	1		H11	Hallway along Classrooms A11 to A16	yes	W2	Concrete	Cream/Blue	None	0	N/A	N/A	None	None						New Building built post 2015
8	1		H11	Hallway along Classrooms A11 to A16	yes	W3	Concrete	Cream/Blue	None	0	N/A	N/A	None	None						New Building built post 2015
8	1		H11	Hallway along Classrooms A11 to A16	yes	W4	Concrete	Cream	None	0	N/A	N/A	None	None						New Building built post 2015
8	1		H11	Hallway along Classrooms A11 to A16	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	None						New Building built post 2015
8	1		H11	Hallway along Classrooms A11 to A16	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	None						New Building built post 2015
8	1		A10	Classroom A10	yes	W1	Concrete	Green	None	0	N/A	N/A	None	None						New Building built post 2015
8	1		A10	Classroom A10	yes	W2	Concrete	White	None	0	N/A	N/A	None	None						New Building built post 2015
8	1		A10	Classroom A10	yes	W3	Sheetrock	White	None	0	N/A	N/A	None	None						New Building built post 2015
8	1		A10	Classroom A10	yes	W4	Sheetrock	White	None	0	N/A	N/A	None	None						New Building built post 2015
8	1		A10	Classroom A10	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	None						New Building built post 2015
8	1		A10	Classroom A10	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	None						New Building built post 2015
8	1		A10A	Classroom A10 - Restroom	yes	W1	Concrete / Ceramic	Grey	None	0	N/A	N/A	None	None						New Building built post 2015
8	1		A10A	Classroom A10 - Restroom	yes	W2	Concrete / Ceramic	Grey	None	0	N/A	N/A	None	None						New Building built post 2015
8	1		A10A	Classroom A10 - Restroom	yes	W3	Concrete / Ceramic	Grey	None	0	N/A	N/A	None	None						New Building built post 2015
8	1		A10A	Classroom A10 - Restroom	yes	W4	Concrete / Ceramic	Blue	None	0	N/A	N/A	None	None						New Building built post 2015
8	1		A10A	Classroom A10 - Restroom	yes	Ceiling	Sheetrock	Grey	None	0	N/A	N/A	None	None						New Building built post 2015
8	1		A10A	Classroom A10 - Restroom	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	None						New Building built post 2015
8	1		1GRR	Girl's Restroom across from Classroom A10	yes	W1	Concrete / Ceramic	Grey	None	0	N/A	N/A	None	None						New Building built post 2015
8	1		1GRR	Girl's Restroom across from Classroom A10	yes	W2	Concrete / Ceramic	Grey	None	0	N/A	N/A	None	None						New Building built post 2015
8	1		1GRR	Girl's Restroom across from Classroom A10	yes	W3	Concrete / Ceramic	Grey	None	0	N/A	N/A	None	None						New Building built post 2015
8	1		1GRR	Girl's Restroom across from Classroom A10	yes	W4	Concrete / Ceramic	Orange	None	0	N/A	N/A	None	None						New Building built post 2015
8	1		1GRR	Girl's Restroom across from Classroom A10	yes	Ceiling	Sheetrock	Grey	None	0	N/A	N/A	None	None						New Building built post 2015
8	1		1GRR	Girl's Restroom across from Classroom A10	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	None						New Building built post 2015
8	1		1BRR	Boy's Restroom across from Classroom A10	yes	W1	Concrete / Ceramic	Grey/Blue	None	0	N/A	N/A	None	None						New Building built post 2015
8	1		1BRR	Boy's Restroom across from Classroom A10	yes	W2	Concrete / Ceramic	Grey/Blue	None	0	N/A	N/A	None	None						New Building built post 2015
8	1		1BRR	Boy's Restroom across from Classroom A10	yes	W3	Concrete / Ceramic	Grey	None	0	N/A	N/A	None	None						New Building built post 2015
8	1		1BRR	Boy's Restroom across from Classroom A10	yes	W4	Concrete / Ceramic	Grey	None	0	N/A	N/A	None	None						New Building built post 2015
8	1		1BRR	Boy's Restroom across from Classroom A10	yes	Ceiling	Sheetrock	Grey	None	0	N/A	N/A	None	None						New Building built post 2015
8	1		1BRR	Boy's Restroom across from Classroom A10	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	None						New Building built post 2015
8	1		PC1BRR	Pipe Chase in Boy's Restroom across from Classroom A10	no	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	New Building built post 2015
8	1		PC1BRR	Pipe Chase in Boy's Restroom across from Classroom A10	no	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	New Building built post 2015
8	1		PC1BRR	Pipe Chase in Boy's Restroom across from Classroom A10	no	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	New Building built post 2015
8	1		PC1BRR	Pipe Chase in Boy's Restroom across from Classroom A10	no	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	New Building built post 2015
8	1		PC1BRR	Pipe Chase in Boy's Restroom across from Classroom A10	no	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	New Building built post 2015
8	1		PC1BRR	Pipe Chase in Boy's Restroom across from Classroom A10	no	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	New Building built post 2015
8	1		1SRR	Staff Restroom across from Classroom A10	yes	W1	Concrete / Ceramic	Grey	None	0	N/A	N/A	None	None						New Building built post 2015
8	1		1SRR	Staff Restroom across from Classroom A10	yes	W2	Concrete / Ceramic	Grey	None	0	N/A	N/A	None	None						New Building built post 2015
8	1		1SRR	Staff Restroom across from Classroom A10	yes	W3	Concrete / Ceramic	Orange	None	0	N/A	N/A	None	None						New Building built post 2015
8	1		1SRR	Staff Restroom across from Classroom A10	yes	W4	Concrete / Ceramic	Grey	None	0	N/A	N/A	None	None						New Building built post 2015
8	1		1SRR	Staff Restroom across from Classroom A10	yes	Ceiling	Sheetrock	Grey	None	0	N/A	N/A	None	None						New Building built post 2015
8	1		1SRR	Staff Restroom across from Classroom A10	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	None						New Building built post 2015
8	1		1CC	Custodial Closet next to Boy's Restroom	yes	W1	Concrete	Cream	None	0	N/A	N/A	None	None						New Building built post 2015
8	1		1CC	Custodial Closet next to Boy's Restroom	yes	W2	Concrete	Cream	None	0	N/A	N/A	None	None						New Building built post 2015
8	1		1CC	Custodial Closet next to Boy's Restroom	yes	W3	Concrete	Cream	None	0	N/A	N/A	None	None						New Building built post 2015
8	1		1CC	Custodial Closet next to Boy's Restroom	yes	W4	Concrete	Cream	None	0	N/A	N/A	None	None						New Building built post 2015
8	1		1CC	Custodial Closet next to Boy's Restroom	yes	Ceiling	Sheetrock	Cream	None	0	N/A	N/A	None	None						New Building built post 2015
8	1		1CC	Custodial Closet next to Boy's Restroom	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	None						New Building built post 2015
8	1		ER1	Electrical Room near Boy's Restroom	yes	W1	Concrete	Cream	None	0	N/A	N/A	None	None						New Building built post 2015
8	1		ER1	Electrical Room near Boy's Restroom	yes	W2	Concrete	Cream	None	0	N/A	N/A	None	None						New Building built post 2015
8	1		ER1	Electrical Room near Boy's Restroom	yes	W3	Concrete	Cream	None	0	N/A	N/A	None	None						New Building built post 2015
8	1		ER1	Electrical Room near Boy's Restroom	yes	W4	Concrete	Cream	None	0	N/A	N/A	None	None						New Building built post 2015
8	1		ER1	Electrical Room near Boy's Restroom	yes	Ceiling	Metal	N/A	N/A	N/A	N/A	N/A	None	None						New Building built post 2015
8	1		ER1	Electrical Room near Boy's Restroom	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	None	None						New Building built post 2015
8	1		MR1	Mechanical Room between Electrical Room and Elevator Electrical Room	no	W1	Concrete	Cream	None	0	N/A	N/A	None	None						New Building built post 2015
8	1		MR1	Mechanical Room between Electrical Room and Elevator Electrical Room	no	W2	Concrete	Cream	None	0	N/A	N/A	None	None						New Building built post 2015
8	1		MR1	Mechanical Room between Electrical Room and Elevator Electrical Room	no	W3	Concrete	Cream	None	0	N/A	N/A	None	None						New Building built post 2015
8	1		MR1	Mechanical Room between Electrical Room and Elevator Electrical Room	no	W4	Concrete	Cream	None	0	N/A	N/A	None	None						New Building built post 2015
8	1		MR1	Mechanical Room between Electrical Room and Elevator Electrical Room	no	Ceiling	Metal	N/A	N/A	N/A	N/A	N/A	None	None						New Building built post 2015
8	1		MR1	Mechanical Room between Electrical Room and Elevator Electrical Room	no	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	None	None						New Building built post 2015
8	1		EER1	Elevator Electrical Room	no	W1	Concrete	Cream	None	0	N/A	N/A	None	None						New Building built post 2015
8	1		EER1	Elevator Electrical Room	no	W2	Concrete	Cream	None	0	N/A	N/A	None	None						New Building built post 2015
8	1		EER1	Elevator Electrical Room	no	W3	Concrete	Cream	None	0	N/A	N/A	None	None						New Building built post 2015
8	1		EER1	Elevator Electrical Room	no	W4	Concrete	Cream	None	0	N/A	N/A	None	None						New Building built post 2015
8	1		EER1	Elevator Electrical Room	no	Ceiling	Metal	N/A	N/A	N/A	N/A	N/A	None	None						New Building built post 2015

					School District of Philadelphia														
			Name of Inspector: Suzanne Shourds and Shalaunda Gourdine		Lead Safe Certification Assessment Report							Inspection Dates: 9/20-29/2021							
			Inspection Company: React		Farrell School							ULCS# 8380							
E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes
8	1	EER1	Elevator Electrical Room	no	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	None	None						New Building built post 2015
8	1	H12	Hallway between Boy's Restroom and Classroom A10	yes	W1	Concrete	Blue/Cream	None	0	N/A	N/A	None	None						New Building built post 2015
8	1	H12	Hallway between Boy's Restroom and Classroom A10	yes	W2	Concrete	Blue-Grey	None	0	N/A	N/A	None	None						New Building built post 2015
8	1	H12	Hallway between Boy's Restroom and Classroom A10	yes	W3	Concrete	Blue-Grey	None	0	N/A	N/A	None	None						New Building built post 2015
8	1	H12	Hallway between Boy's Restroom and Classroom A10	yes	W4	Concrete	Blue/Cream	None	0	N/A	N/A	None	None						New Building built post 2015
8	1	H12	Hallway between Boy's Restroom and Classroom A10	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	None						New Building built post 2015
8	1	H12	Hallway between Boy's Restroom and Classroom A10	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	None						New Building built post 2015
8	1	H13	Hallway ramp between Element 2 and Element 8 Lobby	yes	W1	Concrete	Cream	None	0	N/A	N/A	None	None						New Building built post 2015
8	1	H13	Hallway ramp between Element 2 and Element 8 Lobby	yes	W2	Concrete	Cream	None	0	N/A	N/A	None	None						New Building built post 2015
8	1	H13	Hallway ramp between Element 2 and Element 8 Lobby	yes	W3	Concrete	Cream	None	0	N/A	N/A	None	None						New Building built post 2015
8	1	H13	Hallway ramp between Element 2 and Element 8 Lobby	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A	None	None						New Building built post 2015
8	1	H13	Hallway ramp between Element 2 and Element 8 Lobby	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	None						New Building built post 2015
8	1	H13	Hallway ramp between Element 2 and Element 8 Lobby	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	None						New Building built post 2015
8	1	Lobby	Element 8 Lobby Area	yes	W1	Concrete	Blue/Cream	None	0	N/A	N/A	None	None						New Building built post 2015
8	1	Lobby	Element 8 Lobby Area	yes	W2	Concrete	Blue-Grey	None	0	N/A	N/A	None	None						New Building built post 2015
8	1	Lobby	Element 8 Lobby Area	yes	W3	Concrete	Blue-Grey	None	0	N/A	N/A	None	None						New Building built post 2015
8	1	Lobby	Element 8 Lobby Area	yes	W4	Concrete	Blue/Cream	None	0	N/A	N/A	None	None						New Building built post 2015
8	1	Lobby	Element 8 Lobby Area	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	None						New Building built post 2015
8	1	Lobby	Element 8 Lobby Area	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	None						New Building built post 2015
8	2	S21	Stairwell next to Classrooms A25 and A26	yes	W1	Concrete	Orange	None	0	N/A	N/A	None	None						New Building built post 2015
8	2	S21	Stairwell next to Classrooms A25 and A26	yes	W2	Concrete	Orange	None	0	N/A	N/A	None	None						New Building built post 2015
8	2	S21	Stairwell next to Classrooms A25 and A26	yes	W3	Concrete	Orange	None	0	N/A	N/A	None	None						New Building built post 2015
8	2	S21	Stairwell next to Classrooms A25 and A26	yes	W4	Concrete	Orange	None	0	N/A	N/A	None	None						New Building built post 2015
8	2	S21	Stairwell next to Classrooms A25 and A26	yes	Ceiling	Metal	Orange	None	0	N/A	N/A	None	None						New Building built post 2015
8	2	S21	Stairwell next to Classrooms A25 and A26	yes	Floor	Concrete	N/A	None	0	N/A	N/A	None	None						New Building built post 2015
8	2	A25	Classroom A25	yes	W1	Concrete	Green	None	0	N/A	N/A	None	None						New Building built post 2015
8	2	A25	Classroom A25	yes	W2	Sheetrock	Light Green	None	0	N/A	N/A	None	None						New Building built post 2015
8	2	A25	Classroom A25	yes	W3	Sheetrock	White	None	0	N/A	N/A	None	None						New Building built post 2015
8	2	A25	Classroom A25	yes	W4	Sheetrock	White	None	0	N/A	N/A	None	None						New Building built post 2015
8	2	A25	Classroom A25	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	None						New Building built post 2015
8	2	A25	Classroom A25	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	None						New Building built post 2015
8	2	A26	Classroom A26	yes	W1	Concrete	Green	None	0	N/A	N/A	None	None						New Building built post 2015
8	2	A26	Classroom A26	yes	W2	Sheetrock	White	None	0	N/A	N/A	None	None						New Building built post 2015
8	2	A26	Classroom A26	yes	W3	Sheetrock	White	None	0	N/A	N/A	None	None						New Building built post 2015
8	2	A26	Classroom A26	yes	W4	Sheetrock	Light Green	None	0	N/A	N/A	None	None						New Building built post 2015
8	2	A26	Classroom A26	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	None						New Building built post 2015
8	2	A26	Classroom A26	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	None						New Building built post 2015
8	2	A23	Classroom A23	yes	W1	Concrete	Green	None	0	N/A	N/A	None	None						New Building built post 2015
8	2	A23	Classroom A23	yes	W2	Sheetrock	White	None	0	N/A	N/A	None	None						New Building built post 2015
8	2	A23	Classroom A23	yes	W3	Sheetrock	White	None	0	N/A	N/A	None	None						New Building built post 2015
8	2	A23	Classroom A23	yes	W4	Sheetrock	Light Green	None	0	N/A	N/A	None	None						New Building built post 2015
8	2	A23	Classroom A23	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	None						New Building built post 2015
8	2	A23	Classroom A23	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	None						New Building built post 2015
8	2	A24	Classroom A24	yes	W1	Concrete	Green	None	0	N/A	N/A	None	None						New Building built post 2015
8	2	A24	Classroom A24	yes	W2	Sheetrock	Light Green	None	0	N/A	N/A	None	None						New Building built post 2015
8	2	A24	Classroom A24	yes	W3	Sheetrock	White	None	0	N/A	N/A	None	None						New Building built post 2015
8	2	A24	Classroom A24	yes	W4	Sheetrock	White	None	0	N/A	N/A	None	None						New Building built post 2015
8	2	A24	Classroom A24	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	None						New Building built post 2015
8	2	A24	Classroom A24	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	None						New Building built post 2015
8	2	A21	Classroom A21	yes	W1	Concrete	Green	None	0	N/A	N/A	None	None						New Building built post 2015
8	2	A21	Classroom A21	yes	W2	Concrete	White	None	0	N/A	N/A	None	None						New Building built post 2015
8	2	A21	Classroom A21	yes	W3	Sheetrock	White	None	0	N/A	N/A	None	None						New Building built post 2015
8	2	A21	Classroom A21	yes	W4	Sheetrock	Light Green	None	0	N/A	N/A	None	None						New Building built post 2015
8	2	A21	Classroom A21	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	None						New Building built post 2015
8	2	A21	Classroom A21	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	None						New Building built post 2015
8	2	A22	Classroom A22	yes	W1	Concrete	Green	None	0	N/A	N/A	None	None						New Building built post 2015
8	2	A22	Classroom A22	yes	W2	Sheetrock	Light Green	None	0	N/A	N/A	None	None						New Building built post 2015
8	2	A22	Classroom A22	yes	W3	Sheetrock	White	None	0	N/A	N/A	None	None						New Building built post 2015
8	2	A22	Classroom A22	yes	W4	Sheetrock	White	None	0	N/A	N/A	None	None						New Building built post 2015
8	2	A22	Classroom A22	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	None						New Building built post 2015
8	2	A22	Classroom A22	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	None						New Building built post 2015
8	2	H21	Hallway along Classrooms A21 to A26	yes	W1	Concrete	Cream	None	0	N/A	N/A	None	None						New Building built post 2015
8	2	H21	Hallway along Classrooms A21 to A26	yes	W2	Concrete	Blue/Cream	None	0	N/A	N/A	None	None						New Building built post 2015
8	2	H21	Hallway along Classrooms A21 to A26	yes	W3	Concrete	Blue/Cream	None	0	N/A	N/A	None	None						New Building built post 2015
8	2	H21	Hallway along Classrooms A21 to A26	yes	W4	Concrete	Cream	None	0	N/A	N/A	None	None						New Building built post 2015
8	2	H21	Hallway along Classrooms A21 to A26	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	None						New Building built post 2015
8	2	H21	Hallway along Classrooms A21 to A26	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	None						New Building built post 2015
8	2	2GRR	Second Floor Girl's Restroom	yes	W1	Concrete / Ceramic	Grey	None	0	N/A	N/A	None	None						New Building built post 2015
8	2	2GRR	Second Floor Girl's Restroom	yes	W2	Concrete / Ceramic	Grey	None	0	N/A	N/A	None	None						New Building built post 2015

				School District of Philadelphia																
			Name of Inspector: Suzanne Shourds and Shalaunda Gourdine		Lead Safe Certification Assessment Report										Inspection Dates: 9/20-29/2021					
			Inspection Company: React		Farrell School										ULCS# 8380					
E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes	
8	2	2GRR	Second Floor Girl's Restroom	yes	W3	Concrete / Ceramic	Grey	None	0	N/A	N/A	None	None						New Building built post 2015	
8	2	2GRR	Second Floor Girl's Restroom	yes	W4	Concrete / Ceramic	Orange	None	0	N/A	N/A	None	None						New Building built post 2015	
8	2	2GRR	Second Floor Girl's Restroom	yes	Ceiling	Sheetrock	Grey	None	0	N/A	N/A	None	None						New Building built post 2015	
8	2	2GRR	Second Floor Girl's Restroom	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	None						New Building built post 2015	
8	2	2BRR	Second Floor Boy's Restroom	yes	W1	Concrete / Ceramic	Grey/Blue	None	0	N/A	N/A	None	None						New Building built post 2015	
8	2	2BRR	Second Floor Boy's Restroom	yes	W2	Concrete / Ceramic	Grey/Blue	None	0	N/A	N/A	None	None						New Building built post 2015	
8	2	2BRR	Second Floor Boy's Restroom	yes	W3	Concrete / Ceramic	Grey	None	0	N/A	N/A	None	None						New Building built post 2015	
8	2	2BRR	Second Floor Boy's Restroom	yes	W4	Concrete / Ceramic	Grey	None	0	N/A	N/A	None	None						New Building built post 2015	
8	2	2BRR	Second Floor Boy's Restroom	yes	Ceiling	Sheetrock	Grey	None	0	N/A	N/A	None	None						New Building built post 2015	
8	2	2BRR	Second Floor Boy's Restroom	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	None						New Building built post 2015	
8	2	PC2BRR	Pipe Chase in Second Floor Boy's Restroom	yes	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	New Building built post 2015	
8	2	PC2BRR	Pipe Chase in Second Floor Boy's Restroom	yes	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	New Building built post 2015	
8	2	PC2BRR	Pipe Chase in Second Floor Boy's Restroom	yes	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	New Building built post 2015	
8	2	PC2BRR	Pipe Chase in Second Floor Boy's Restroom	yes	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	New Building built post 2015	
8	2	PC2BRR	Pipe Chase in Second Floor Boy's Restroom	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	New Building built post 2015	
8	2	PC2BRR	Pipe Chase in Second Floor Boy's Restroom	yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	New Building built post 2015	
8	2	2SRR	Second Floor Staff Restroom	no	W1	Concrete / Ceramic	Grey	None	0	N/A	N/A	None	None						New Building built post 2015	
8	2	2SRR	Second Floor Staff Restroom	no	W2	Concrete / Ceramic	Grey	None	0	N/A	N/A	None	None						New Building built post 2015	
8	2	2SRR	Second Floor Staff Restroom	no	W3	Concrete / Ceramic	Blue	None	0	N/A	N/A	None	None						New Building built post 2015	
8	2	2SRR	Second Floor Staff Restroom	no	W4	Concrete / Ceramic	Grey	None	0	N/A	N/A	None	None						New Building built post 2015	
8	2	2SRR	Second Floor Staff Restroom	no	Ceiling	Sheetrock	Grey	None	0	N/A	N/A	None	None						New Building built post 2015	
8	2	2SRR	Second Floor Staff Restroom	no	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	None						New Building built post 2015	
8	2	2CC	Second Floor Custodial Closet next to Boy's Restroom	yes	W1	Concrete	Cream	None	0	N/A	N/A	None	None						New Building built post 2015	
8	2	2CC	Second Floor Custodial Closet next to Boy's Restroom	yes	W2	Concrete	Cream	None	0	N/A	N/A	None	None						New Building built post 2015	
8	2	2CC	Second Floor Custodial Closet next to Boy's Restroom	yes	W3	Concrete	Cream	None	0	N/A	N/A	None	None						New Building built post 2015	
8	2	2CC	Second Floor Custodial Closet next to Boy's Restroom	yes	W4	Concrete	Cream	None	0	N/A	N/A	None	None						New Building built post 2015	
8	2	2CC	Second Floor Custodial Closet next to Boy's Restroom	yes	Ceiling	Sheetrock	Cream	None	0	N/A	N/A	None	None						New Building built post 2015	
8	2	2CC	Second Floor Custodial Closet next to Boy's Restroom	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	None						New Building built post 2015	
8	2	A22A	Storage Room across from Second Floor Girl's Restroom	yes	W1	Concrete	Cream	None	0	N/A	N/A	None	None						New Building built post 2015	
8	2	A22A	Storage Room across from Second Floor Girl's Restroom	yes	W2	Concrete	Cream	None	0	N/A	N/A	None	None						New Building built post 2015	
8	2	A22A	Storage Room across from Second Floor Girl's Restroom	yes	W3	Concrete	Cream	None	0	N/A	N/A	None	None						New Building built post 2015	
8	2	A22A	Storage Room across from Second Floor Girl's Restroom	yes	W4	Concrete	Cream	None	0	N/A	N/A	None	None						New Building built post 2015	
8	2	A22A	Storage Room across from Second Floor Girl's Restroom	yes	Ceiling	Sheetrock	Cream	None	0	N/A	N/A	None	None						New Building built post 2015	
8	2	A22A	Storage Room across from Second Floor Girl's Restroom	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	None						New Building built post 2015	
8	2	A22B	Area of Refuge (Storage)	no	W1	Concrete	Cream	None	0	N/A	N/A	None	None						New Building built post 2015	
8	2	A22B	Area of Refuge (Storage)	no	W2	Concrete	Cream	None	0	N/A	N/A	None	None						New Building built post 2015	
8	2	A22B	Area of Refuge (Storage)	no	W3	Concrete	Cream	None	0	N/A	N/A	None	None						New Building built post 2015	
8	2	A22B	Area of Refuge (Storage)	no	W4	Concrete	Cream	None	0	N/A	N/A	None	None						New Building built post 2015	
8	2	A22B	Area of Refuge (Storage)	no	Ceiling	Sheetrock	Cream	None	0	N/A	N/A	None	None						New Building built post 2015	
8	2	A22B	Area of Refuge (Storage)	no	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	None						New Building built post 2015	