

			School District of Philadelphia																
			Name of Inspector: Paul M. Davis		Lead Safe Certification Assessment Report							Inspection Dates: June 2021							
																			Inspection Company: VERTEX
E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes
1	1	100	Community Room 100	Yes	W1	CMU	Yellow	None	0	N/A	N/A	None	0	Negative	No	No	no	no	
1	1	100	Community Room 100	Yes	W2	CMU	Blue	Chipping	5	0	Negative	None	0	N/A	No	No	no	no	
1	1	100	Community Room 100	Yes	W3	CMU	Blue	Chipping	6	0	Negative	None	0	N/A	No	No	no	no	
1	1	100	Community Room 100	Yes	W3	Plaster	Blue	Chipping	4	0	Negative	None	0	N/A	No	No	no	no	In Corner of Room.
1	1	100	Community Room 100	Yes	W4	CMU	Yellow	None	0	N/A	N/A	None	0	N/A	No	No	no	no	
1	1	100	Community Room 100	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	Drop Ceiling
1	1	100	Community Room 100	Yes	Ceiling	Plaster	White	Flaking	4	0	Negative	None	0	N/A	No	No	no	no	Plaster Ceiling in Corner of room.
1	1	100	Community Room 100	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	12 x 12 Floor Tiles
1	1	101	Teacher's Lounge 101	Yes	W1	CMU	Yellow	None	0	0.07	Negative	None	0	N/A	No	No	no	no	
1	1	101	Teacher's Lounge 101	Yes	Door Frame	Metal	Blue	Chipping	1	0.5	Negative	None	0	N/A	No	No	no	no	
1	1	101	Teacher's Lounge 101	Yes	W2	CMU	Yellow	None	0	0	Negative	None	0	N/A	No	No	no	no	
1	1	101	Teacher's Lounge 101	Yes	W3	CMU	Yellow	None	0	N/A	N/A	None	0	N/A	No	No	no	no	
1	1	101	Teacher's Lounge 101	Yes	Pipe	Metal	Blue	Chipping	1	0	Negative	None	0	N/A	No	No	no	no	
1	1	101	Teacher's Lounge 101	Yes	W4	CMU	Yellow	None	0	N/A	N/A	None	0	N/A	No	No	no	no	
1	1	101	Teacher's Lounge 101	Yes	Ceiling	Plaster	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	
1	1	101	Teacher's Lounge 101	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	12 x 12 Floor Tiles
1	1	101A	Special Needs Room	Yes	W1	CMU	White	None	0	N/A	N/A	None	0	Negative	No	No	no	no	
1	1	101A	Special Needs Room	Yes	Door Frame	Metal	Blue	Chipping	1	0.07	Negative	None	0	N/A	No	No	no	no	
1	1	101A	Special Needs Room	Yes	W2	CMU	White	Chipping	5	0	Negative	None	0	N/A	No	No	no	no	
1	1	101A	Special Needs Room	Yes	W3	CMU	White	Cracking	10	0	Negative	None	0	N/A	No	No	no	no	
1	1	101A	Special Needs Room	Yes	W4	CMU	White	Cracking/Chipping	8	0	Negative	None	0	N/A	No	No	no	no	
1	1	101A	Special Needs Room	Yes	Ceiling	Concrete	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	
1	1	101A	Special Needs Room	Yes	Ceiling	Plaster	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	In Corner
1	1	101A	Special Needs Room	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	12 x 12 Floor Tiles
1	1	106B	Girl's Restroom across from Classroom 101	Yes	W1	CMU	White	Chipping	2	0	Negative	None	0	Negative	No	No	no	no	
1	1	106B	Girl's Restroom across from Classroom 101	Yes	Door Frame	Metal	Blue	Chipping	10	0.1	Negative	None	0	N/A	No	No	no	no	
1	1	106B	Girl's Restroom across from Classroom 101	Yes	W2	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	
1	1	106B	Girl's Restroom across from Classroom 101	Yes	W3	CMU	White	Chipping	2	0	Negative	None	0	N/A	No	No	no	no	
1	1	106B	Girl's Restroom across from Classroom 101	Yes	W4	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	
1	1	106B	Girl's Restroom across from Classroom 101	Yes	Ceiling	Plaster	White	Efflorescence	30	0	Negative	None	0	N/A	No	No	no	no	
1	1	106B	Girl's Restroom across from Classroom 101	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	Ceramic Tiles
1	1	119B	Storage Room behind Building Enginner's Office	No	W1	CMU	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	Wall 1 is from Hallway. Wall is Unpainted
1	1	119B	Storage Room behind Building Enginner's Office	No	Door Frame	Metal	Pink	Chipping	2	0.13	Negative	None	0	N/A	No	No	no	no	
1	1	119B	Storage Room behind Building Enginner's Office	No	W2	CMU	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	Wall is Unpainted
1	1	119B	Storage Room behind Building Enginner's Office	No	W3	CMU	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	Wall is Unpainted
1	1	119B	Storage Room behind Building Enginner's Office	No	Door Frame	Metal	Pink	Chipping	4	0.07	Negative	None	0	N/A	No	No	no	no	
1	1	119B	Storage Room behind Building Enginner's Office	No	W4	CMU	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	Wall is Unpainted
1	1	119B	Storage Room behind Building Enginner's Office	No	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	Ceiling is Unpainted
1	1	119B	Storage Room behind Building Enginner's Office	No	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	Floor is Unpainted
1	1	119C	Building Enginner's Office	No	W1	CMU	White	Cracking	4	0	Negative	None	0	N/A	No	No	no	no	
1	1	119C	Building Enginner's Office	No	Door Frame	Metal	White	Chipping	4	0.08	Negative	None	0	N/A	No	No	no	no	
1	1	119C	Building Enginner's Office	No	W2	CMU	White	Cracking	4	0	Negative	None	0	N/A	No	No	no	no	
1	1	119C	Building Enginner's Office	No	W3	CMU	White	Cracking	12	0	Negative	None	0	N/A	No	No	no	no	
1	1	119C	Building Enginner's Office	No	Pipe Cover	Metal	White	Chipping	1	0.03	Negative	None	0	N/A	No	No	no	no	
1	1	119C	Building Enginner's Office	No	W4	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	
1	1	119C	Building Enginner's Office	No	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	2 x 4 Drop Ceiling
1	1	119C	Building Enginner's Office	No	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	12 x 12 Floor Tiles
1	1	H16	Hallway Room 101A to Classroom 101	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	Wall 1 is open to adjacent Hallway
1	1	H16	Hallway Room 101A to Classroom 101	Yes	W2	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	
1	1	H16	Hallway Room 101A to Classroom 101	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	Wall 3 is open to adjacent Hallways
1	1	H16	Hallway Room 101A to Classroom 101	Yes	W4	CMU	White	Chipping	6	0.01	Negative	None	0	N/A	No	No	no	no	On Clifford
1	1	H16	Hallway Room 101A to Classroom 101	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	2 x 4 Drop Ceiling
1	1	H16	Hallway Room 101A to Classroom 101	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	12 x 12 Floor Tiles
1	1	102	Classroom 102	Yes	W1	CMU	White	Chipping/Cracking	12	0.03	Negative	None	0	N/A	No	No	no	no	
1	1	102	Classroom 102	Yes	Door Frame	Metal	Blue	Friction	1	0.17	Negative	None	0	N/A	No	No	no	no	
1	1	102	Classroom 102	Yes	W2	CMU	White	Chipping/Cracking	6	0.05	Negative	None	0	N/A	No	No	no	no	
1	1	102	Classroom 102	Yes	W3	CMU	White	Chipping/Flaking/Cracking	10	0.1	Negative	None	0	N/A	No	No	no	no	
1	1	102	Classroom 102	Yes	W4	CMU	White	Flaking	3	0	Negative	None	0	Negative	No	No	no	no	
1	1	102	Classroom 102	Yes	Ceiling	Plaster	White	Cracking	2	0	Negative	None	0	N/A	No	No	no	no	
1	1	102	Classroom 102	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	12 x 12 Floor Tiles
1	1	104	Classroom 104	Yes	W1	CMU	White	Chipping/Cracking	10	0.02	Negative	None	0	N/A	No	No	no	no	
1	1	104	Classroom 104	Yes	W2	CMU	White	Flaking/Chipping/Cracking	6	0.03	Negative	None	0	N/A	No	No	no	no	
1	1	104	Classroom 104	Yes	W3	CMU	White	Efflorescence/Chipping/Cracking	25	0.02	Negative	None	0	N/A	No	Unknown	no	no	Near Window
1	1	104	Classroom 104	Yes	W4	CMU	White	Partially Inaccessible	0	0	Negative	None	0	N/A	No	No	no	no	
1	1	104	Classroom 104	Yes	Ceiling	Plaster	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	
1	1	104	Classroom 104	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	12 x 12 Floor Tiles
1	1	103	Classroom 103	Yes	W1	CMU	White	Chipping/Flaking	4	0.01	Negative	None	0	N/A	No	No	no	no	

			School District of Philadelphia																	
			Name of Inspector: Paul M. Davis			Lead Safe Certification Assessment Report								Inspection Dates: June 2021						
			Inspection Company: VERTEX			Bethune ES School								ULCS# 7510						
E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes	
1	1	103	Classroom 103	Yes	Door Frame	Metal	Blue	Chipping	1	0.08	Negative	None	0	N/A	No	No	no	no		
1	1	103	Classroom 103	Yes	W2	CMU	White	Chipping	2	0	Negative	None	0	N/A	No	No	no	no		
1	1	103	Classroom 103	Yes	W3	CMU	White	Chipping/Flaking	8	0	Negative	None	0	N/A	No	No	no	no		
1	1	103	Classroom 103	Yes	W4	CMU	White	Efflorescence/Chipping /Flaking	10	0.02	Negative	None	0	N/A	No	No	no	no		
1	1	103	Classroom 103	Yes	W4	Concrete	White	Flaking	2	0.01	Negative	None	0	N/A	No	No	no	no	On Beam	
1	1	103	Classroom 103	Yes	Ceiling	Plaster	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no		
1	1	103	Classroom 103	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	12 x 12 Floor Tiles	
1	1	H17	Hallway adjacent to Classrooms 102, 103, & 104	Yes	W1	CMU	White	Chipping	2	0.16	Negative	None	0	N/A	No	No	no	no		
1	1	H17	Hallway adjacent to Classrooms 102, 103, & 104	Yes	W2	CMU	White	Chipping	2	0.01	Negative	None	0	N/A	No	No	no	no		
1	1	H17	Hallway adjacent to Classrooms 102, 103, & 104	Yes	W3	CMU	White	Chipping	2	0.09	Negative	None	0	N/A	No	No	no	no		
1	1	H17	Hallway adjacent to Classrooms 102, 103, & 104	Yes	W4	CMU	White	Chipping	2	0.03	Negative	None	0	N/A	No	No	no	no		
1	1	H17	Hallway adjacent to Classrooms 102, 103, & 104	Yes	Ceiling	Plaster	White	Chipping	2	0	Negative	None	0	N/A	No	No	no	no		
1	1	H17	Hallway adjacent to Classrooms 102, 103, & 104	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	12 x 12 Floor Tiles	
1	1	105	Classroom 105	Yes	W1	CMU	White	Chipping/Flaking	4	0.04	Negative	None	0	N/A	No	No	no	no		
1	1	105	Classroom 105	Yes	W2	CMU	White	Partially Inaccessible	0	0	Negative	None	0	N/A	No	No	no	no		
1	1	105	Classroom 105	Yes	W3	CMU	White	Chipping/Flaking	12	0.01	Negative	None	0	N/A	No	No	no	no		
1	1	105	Classroom 105	Yes	W4	CMU	White	Chipping	10	0.02	Negative	None	0	N/A	No	No	no	no		
1	1	105	Classroom 105	Yes	Ceiling	Plaster	White	Flaking	1	0	Negative	None	0	N/A	No	No	no	no		
1	1	105	Classroom 105	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	12 x 12 Floor Tiles	
1	1	105B	Boy's Restroom across from Classroom 105	Yes	W1	CMU	White	Chipping	1	0.07	Negative	None	0	N/A	No	No	no	no		
1	1	105B	Boy's Restroom across from Classroom 105	Yes	Door Frame	Metal	Blue	Chipping	10	0.19	Negative	None	0	N/A	No	No	no	no		
1	1	105B	Boy's Restroom across from Classroom 105	Yes	W2	CMU	White	Chipping	3	0.03	Negative	None	0	N/A	No	No	no	no		
1	1	105B	Boy's Restroom across from Classroom 105	Yes	W3	CMU	White	Chipping	1	0.05	Negative	None	0	N/A	No	No	no	no		
1	1	105B	Boy's Restroom across from Classroom 105	Yes	Door Frame	Metal	Blue	Chipping	10	0.06	Negative	None	0	N/A	No	No	no	no		
1	1	105B	Boy's Restroom across from Classroom 105	Yes	W4	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no		
1	1	105B	Boy's Restroom across from Classroom 105	Yes	Ceiling	Plaster	White	Efflorescence	12	0	Negative	None	0	N/A	No	Unknown	yes	no		
1	1	105B	Boy's Restroom across from Classroom 105	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	Ceramic Tiles	
1	1	105C	Closet in Boy's Restroom across from Classroom 105	No	W1	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no		
1	1	105C	Closet in Boy's Restroom across from Classroom 105	No	W2	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no		
1	1	105C	Closet in Boy's Restroom across from Classroom 105	No	W3	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no		
1	1	105C	Closet in Boy's Restroom across from Classroom 105	No	Shelving	Wood	Yellow	Partially Inaccessible	N/A	0.02	Negative	None	0	N/A	No	No	no	no		
1	1	105C	Closet in Boy's Restroom across from Classroom 105	No	W4	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no		
1	1	105C	Closet in Boy's Restroom across from Classroom 105	No	Ceiling	Sheetrock	White	Scuffs	1	0	Negative	None	0	N/A	No	No	no	no		
1	1	105C	Closet in Boy's Restroom across from Classroom 105	No	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	Ceramic Tiles	
1	1	S14	Stairwell A next to Classroom 105	Yes	W1	CMU	White	Chipping	3	0.01	Negative	None	0	N/A	No	No	no	no	Wall 1 is along Room 106A side.	
1	1	S14	Stairwell A next to Classroom 105	Yes	W2	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	Wall 2 is along Hallway side.	
1	1	S14	Stairwell A next to Classroom 105	Yes	W3	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no		
1	1	S14	Stairwell A next to Classroom 105	Yes	W4	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no		
1	1	S14	Stairwell A next to Classroom 105	Yes	Ceiling	Concrete	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no		
1	1	S14	Stairwell A next to Classroom 105	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	12 x 12 Floor Tiles	
1	1	106	Classroom 106	Yes	W1	CMU	White	Chipping/Flaking	5	0.05	Negative	None	0	Negative	No	No	no	no		
1	1	106	Classroom 106	Yes	W2	CMU	White	Chipping/Cracking	8	0.03	Negative	None	0	N/A	No	No	no	no		
1	1	106	Classroom 106	Yes	W3	CMU	White	Chipping/Flaking	25	0	Negative	None	0	N/A	No	No	no	no		
1	1	106	Classroom 106	Yes	Pipe Sleeve	Metal	White	Flaking	1	0.09	Negative	None	0	N/A	No	No	no	no		
1	1	106	Classroom 106	Yes	W4	CMU	White	Chipping	4	0.01	Negative	None	0	N/A	No	No	no	no		
1	1	106	Classroom 106	Yes	Ceiling	Plaster	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no		
1	1	106	Classroom 106	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	12 x 12 Floor Tiles	
1	1	H14	Hallway from Classroom 105 to Classroom 107	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	Wall 1 is open to adjacent Hallway by Classroom 108	
1	1	H14	Hallway from Classroom 105 to Classroom 107	Yes	W2	CMU	White	Chipping	6	0.05	Negative	None	0	N/A	No	No	no	no		
1	1	H14	Hallway from Classroom 105 to Classroom 107	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	Wall 3 is open to adjacent Hallway by Classroom 104	
1	1	H14	Hallway from Classroom 105 to Classroom 107	Yes	W4	CMU	White	Chipping	6	0.01	Negative	None	0	N/A	No	No	no	no		
1	1	H14	Hallway from Classroom 105 to Classroom 107	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	2 x 4 Ceiling Tiles	
1	1	H14	Hallway from Classroom 105 to Classroom 107	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	12 x 12 Floor Tiles	
1	1	106A	Storage Room adjacent to Classroom 106	yes	W1	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no		
1	1	106A	Storage Room adjacent to Classroom 106	yes	Door Frame	Metal	Blue	Chipping	1	0.1	Negative	None	0	N/A	No	No	no	no		
1	1	106A	Storage Room adjacent to Classroom 106	yes	W2	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no		
1	1	106A	Storage Room adjacent to Classroom 106	yes	IT Holder	Wood	White	Cracking	4	0	Negative	None	0	N/A	No	No	no	no		
1	1	106A	Storage Room adjacent to Classroom 106	yes	IT Holder	Wood	Tan	Cracking	2	0	Negative	None	0	N/A	No	No	no	no		
1	1	106A	Storage Room adjacent to Classroom 106	yes	W3	CMU	White	Chipping	3	0	Negative	None	0	N/A	No	No	no	no		
1	1	106A	Storage Room adjacent to Classroom 106	yes	W4	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no		
1	1	106A	Storage Room adjacent to Classroom 106	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	2 x 4 Drop Ceiling	
1	1	106A	Storage Room adjacent to Classroom 106	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	12 x 12 Floor Tiles	
1	1	119A	Office across from Classroom 106 (Room 119C)	Yes	W1	CMU	Yellow	Cracking	4	0.04	Negative	None	0	Negative	No	No	no	no		
1	1	119A	Office across from Classroom 106 (Room 119C)	Yes	Door Frame	Metal	Yellow	Chipping	6	0.08	Negative	None	0	N/A	No	No	no	no		
1	1	119A	Office across from Classroom 106 (Room 119C)	Yes	W2	CMU	Yellow	Cracking	10	0.05	Negative	None	0	N/A	No	No	no	no		
1	1	119A	Office across from Classroom 106 (Room 119C)	Yes	W3	CMU	Yellow	Cracking	15	0.08	Negative	None	0	N/A	No	No	no	no		
1	1	119A	Office across from Classroom 106 (Room 119C)	Yes	W4	CMU	Yellow	Cracking	2	0.03	Negative	None	0	N/A	No	No	no	no		

			School District of Philadelphia																						
			Name of Inspector: Paul M. Davis			Lead Safe Certification Assessment Report									Inspection Dates: June 2021										
			Inspection Company: VERTEX			Bethune ES School									ULCS# 7510										
Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes						
1	1	119A	Office across from Classroom 106 (Room 119C)	Yes	Conduit	Metal	Yellow	Flaking	4	0.17	Negative	Cabinet	1	N/A	No	No	no	no							
1	1	119A	Office across from Classroom 106 (Room 119C)	Yes	Ceiling	Plaster	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no							
1	1	119A	Office across from Classroom 106 (Room 119C)	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	9 x 9 Floor Tiles						
1	1	107	Classroom 107	Yes	W1	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no							
1	1	107	Classroom 107	Yes	W2	CMU	White	Chipping	6	0	Negative	None	0	N/A	No	No	no	no							
1	1	107	Classroom 107	Yes	W3	CMU	White	Cracking	10	0.02	Negative	None	0	N/A	No	No	no	no							
1	1	107	Classroom 107	Yes	W4	CMU	White	Chipping	4	0	Negative	None	0	N/A	No	No	no	no							
1	1	107	Classroom 107	Yes	Ceiling	Plaster	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no							
1	1	107	Classroom 107	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	12 x 12 Floor Tiles						
1	1	120	IMC Library	Yes	W1	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	Wall 1 is same side as IMC 120A Office and across from Classrooms 106 & 109						
1	1	120	IMC Library	Yes	Door Frame	Metal	Blue	Chipping	12	0.25	Negative	None	0	N/A	No	No	no	no	Across from Classroom 109						
1	1	120	IMC Library	Yes	Door Frame	Metal	Blue	Chipping	10	0.06	Negative	None	0	N/A	No	No	no	no	Across from Classroom 106						
1	1	120	IMC Library	Yes	W2	CMU	White	Chipping	1	0.03	Negative	None	0	N/A	No	No	no	no							
1	1	120	IMC Library	Yes	Window Frame	Metal	Blue	Chipping	4	0.05	Negative	None	0	N/A	No	No	no	no	Windows to IMC Office						
1	1	120	IMC Library	Yes	Door Frame	Metal	Blue	Chipping	10	0.04	Negative	None	0	N/A	No	No	no	no	Includes two doors						
1	1	120	IMC Library	Yes	W3	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no							
1	1	120	IMC Library	Yes	Door	Metal	Blue	Scrapes	3	0.9	Positive	None	0	N/A	No	No	no	no	Includes two doors						
1	1	120	IMC Library	Yes	Door Frame	Metal	Blue	Flaking/Cracking	3	0.7	Positive	None	0	N/A	No	No	no	no	Includes two doors						
1	1	120	IMC Library	Yes	W4	Sheetrock	Blue	None	0	N/A	N/A	None	0	N/A	No	No	no	no							
1	1	120	IMC Library	Yes	Columns	Concrete	Blue	None	0	N/A	N/A	None	0	Negative	No	No	no	no							
1	1	120	IMC Library	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	2 x 4 Drop Ceiling						
1	1	120	IMC Library	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	12 x 12 Floor Tiles						
1	1	120A	Office within the IMC Library	Yes	W1	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	Wall 1 is from the IMC/Library side.						
1	1	120A	Office within the IMC Library	Yes	W2	CMU	White	Chipping	1	0	Negative	None	0	N/A	No	No	no	no							
1	1	120A	Office within the IMC Library	Yes	W3	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no							
1	1	120A	Office within the IMC Library	Yes	W4	CMU	White	Partially Inaccessible	0	0	Negative	None	0	N/A	No	No	no	no							
1	1	120A	Office within the IMC Library	Yes	Window Frame	Metal	Blue	Chipping	6	0.09	Negative	None	0	N/A	No	No	no	no							
1	1	120A	Office within the IMC Library	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	2 x4 Drop Ceiling; Concrete Ceiling above is Unpainted.						
1	1	120A	Office within the IMC Library	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	12 x 12 Floor Tiles						
1	1	120C	Library Storage Room	yes	W1	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	Wall 1 is from IMC/Library side.						
1	1	120C	Library Storage Room	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	Wall 2 is an unpainted metal fence.						
1	1	120C	Library Storage Room	yes	W3	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	Wall 3 is the Hallway side.						
1	1	120C	Library Storage Room	yes	Door Frame	Metal	Blue	Chipping	4	0.19	Negative	None	0	N/A	No	No	no	no							
1	1	120C	Library Storage Room	yes	W4	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no							
1	1	120C	Library Storage Room	yes	Ceiling	Plaster	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no							
1	1	120C	Library Storage Room	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	12 x 12 Floor Tiles						
1	1	108	Classroom 108	Yes	W1	CMU	White	Chipping	4	0.03	Negative	None	0	N/A	No	No	no	no							
1	1	108	Classroom 108	Yes	W2	CMU	White	Chipping/Cracking	10	0	Negative	None	0	N/A	No	No	no	no							
1	1	108	Classroom 108	Yes	W3	CMU	White	Chipping/Cracking	6	0.01	Negative	None	0	N/A	No	No	no	no							
1	1	108	Classroom 108	Yes	W4	CMU	White	Chipping	20	0	Negative	None	0	N/A	No	No	no	no							
1	1	108	Classroom 108	Yes	Ceiling	Plaster	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no							
1	1	108	Classroom 108	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	12 x 12 Floor Tiles						
1	1	109	Classroom 109	Yes	W1	CMU	White	Chipping	3	0.04	Negative	None	0	N/A	No	No	no	no							
1	1	109	Classroom 109	Yes	W2	CMU	White	Chipping	4	0	Negative	None	0	N/A	No	No	no	no							
1	1	109	Classroom 109	Yes	W3	CMU	White	Chipping/Cracking	10	0.05	Negative	None	0	N/A	No	No	no	no							
1	1	109	Classroom 109	Yes	W4	CMU	White	Chipping	5	0.04	Negative	None	0	N/A	No	No	no	no							
1	1	109	Classroom 109	Yes	Ceiling	Plaster	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no							
1	1	109	Classroom 109	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	12 x 12 Floor Tiles						
1	1	109A	Storage Next to Elevator	yes	W1	CMU	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	Wall is Unpainted						
1	1	109A	Storage Next to Elevator	yes	W2	CMU	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	Wall is Unpainted						
1	1	109A	Storage Next to Elevator	yes	W3	CMU	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	Wall is Unpainted						
1	1	109A	Storage Next to Elevator	yes	W4	CMU	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	Wall is Unpainted						
1	1	109A	Storage Next to Elevator	yes	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	Ceiling is Unpainted						
1	1	109A	Storage Next to Elevator	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	Floor is Unpainted						
1	1	H13	Hallway from Classroom 108 to Classroom 110	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	Wall 1 is open to adjacent Hallway by Classroom 111						
1	1	H13	Hallway from Classroom 108 to Classroom 110	Yes	W2	Concrete	White	Chipping	12	0	Negative	None	0	Negative	No	No	no	no							
1	1	H13	Hallway from Classroom 108 to Classroom 110	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	Wall 3 is open to adjacent Hallway by Classroom 107						
1	1	H13	Hallway from Classroom 108 to Classroom 110	Yes	W4	CMU	White	Chipping	4	0.01	Negative	None	0	N/A	No	No	no	no							
1	1	H13	Hallway from Classroom 108 to Classroom 110	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	2 x 4 Drop Ceiling						
1	1	H13	Hallway from Classroom 108 to Classroom 110	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	12 x 12 Floor Tiles						
1	1	S13	Stairwell B next to Classroom 110	Yes	W1	CMU	White	Chipping	2	0	Negative	None	0	N/A	No	No	no	no	Wall 1 is along Classroom 110 side.						
1	1	S13	Stairwell B next to Classroom 110	Yes	W2	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no							
1	1	S13	Stairwell B next to Classroom 110	Yes	W3	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no							
1	1	S13	Stairwell B next to Classroom 110	Yes	W4	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no							
1	1	S13	Stairwell B next to Classroom 110	Yes	Ceiling	Concrete	White	None	0	N/A	N/A	None	0	Negative	No	No	no	no							
1	1	S13	Stairwell B next to Classroom 110	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	12 x 12 Floor Tiles						

			School District of Philadelphia																
			Name of Inspector: Paul M. Davis			Lead Safe Certification Assessment Report													
			Inspection Company: VERTEX			Bethune ES School										ULCS# 7510			
E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes
1	1	S13	Stairwell B next to Classroom 110	Yes	Stringer	Metal	Blue	Chipping	1	0.1	Negative	None	0	N/A	No	No	no	no	
1	1	110	Classroom 110	Yes	W1	CMU	White	Chipping/Cracking	3	0.12	Negative	None	0	N/A	No	No	no	no	
1	1	110	Classroom 110	Yes	Door Frame	Metal	Blue	Chipping	5	0.13	Negative	None	0	N/A	No	No	no	no	
1	1	110	Classroom 110	Yes	W2	CMU	White	Cracking	20	0.06	Negative	None	0	N/A	No	No	no	no	
1	1	110	Classroom 110	Yes	W3	CMU	White	Chipping/Cracking	10	0.02	Negative	None	0	N/A	No	No	no	no	
1	1	110	Classroom 110	Yes	W4	CMU	White	Chipping/Flaking/Cracking	12	0	Negative	None	0	N/A	No	No	no	no	
1	1	110	Classroom 110	Yes	Ceiling	Plaster	White	None	0	0	Negative	None	0	N/A	No	No	no	no	
1	1	110	Classroom 110	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	12 x 12 Floor Tiles
1	1	110B	Boy's Restroom across from Classroom 110	Yes	W1	CMU	White	Chipping/Flaking	6	0.08	Negative	None	0	N/A	No	No	no	no	
1	1	110B	Boy's Restroom across from Classroom 110	Yes	Door	Metal	Blue	Chipping	2	0	Negative	None	0	N/A	No	No	no	no	
1	1	110B	Boy's Restroom across from Classroom 110	Yes	Door Frame	Metal	Blue	Chipping	8	0.13	Negative	None	0	N/A	No	No	no	no	
1	1	110B	Boy's Restroom across from Classroom 110	Yes	W2	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	
1	1	110B	Boy's Restroom across from Classroom 110	Yes	W3	CMU	White	Efflorescence	2	0.02	Negative	None	0	N/A	No	Unknown	no	no	
1	1	110B	Boy's Restroom across from Classroom 110	Yes	W4	CMU	White	Chipping	3	0.08	Negative	None	0	N/A	No	No	no	no	
1	1	110B	Boy's Restroom across from Classroom 110	Yes	Ceiling	Plaster	White	Efflorescence/Flaking	50	0	Negative	None	0	N/A	No	Unknown	yes	no	
1	1	110B	Boy's Restroom across from Classroom 110	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	Ceramic Tiles
1	1	110C	Closet in Boy's Restroom across from Classroom 110	No	W1	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	
1	1	110C	Closet in Boy's Restroom across from Classroom 110	No	Door Frame	Metal	White	Chipping	4	0.05	Negative	None	0	N/A	No	No	no	no	
1	1	110C	Closet in Boy's Restroom across from Classroom 110	No	W2	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	
1	1	110C	Closet in Boy's Restroom across from Classroom 110	No	W3	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	
1	1	110C	Closet in Boy's Restroom across from Classroom 110	No	W4	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	
1	1	110C	Closet in Boy's Restroom across from Classroom 110	No	Ceiling	Sheetrock	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	
1	1	110C	Closet in Boy's Restroom across from Classroom 110	No	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	Ceramic Tiles
1	1	120B	Storage Room adjacent to Boy's Restroom across from Classroom 110	yes	W1	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	Wall 1 is from Hallway
1	1	120B	Storage Room adjacent to Boy's Restroom across from Classroom 110	yes	Door Frame	Metal	Blue	Chipping	2	0.11	Negative	None	0	N/A	No	No	no	no	Wall 1 is from Hallway
1	1	120B	Storage Room adjacent to Boy's Restroom across from Classroom 110	yes	W2	CMU	White	Cracking	10	0.05	Negative	None	0	N/A	No	No	no	no	
1	1	120B	Storage Room adjacent to Boy's Restroom across from Classroom 110	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	Wall 3 is an unpainted metal fence.
1	1	120B	Storage Room adjacent to Boy's Restroom across from Classroom 110	yes	W4	CMU	White	Cracking	6	0.07	Negative	None	0	Negative	No	No	no	no	
1	1	120B	Storage Room adjacent to Boy's Restroom across from Classroom 110	yes	Door Frame	Metal	Blue	Chipping	8	0.09	Negative	None	0	N/A	No	No	no	no	Includes two doors.
1	1	120B	Storage Room adjacent to Boy's Restroom across from Classroom 110	yes	Ceiling	Plaster	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	
1	1	120B	Storage Room adjacent to Boy's Restroom across from Classroom 110	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	12 x 12 Floor Tiles
1	1	111	Classroom 111	Yes	W1	CMU	White	Chipping/Flaking	6	0	Negative	None	0	N/A	No	No	no	no	
1	1	111	Classroom 111	Yes	W2	CMU	White	Chipping/Flaking	6	0.04	Negative	None	0	N/A	No	No	no	no	
1	1	111	Classroom 111	Yes	W3	CMU	White	Chipping/Flaking	4	0.01	Negative	None	0	N/A	No	No	no	no	
1	1	111	Classroom 111	Yes	W4	CMU	White	Chipping/Flaking	2	0.03	Negative	None	0	N/A	No	No	no	no	
1	1	111	Classroom 111	Yes	Ceiling	Plaster	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	
1	1	111	Classroom 111	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	12 x 12 Floor Tiles
1	1	112	Classroom 112	Yes	W1	CMU	White	Chipping	3	0.03	Negative	None	0	N/A	No	No	no	no	
1	1	112	Classroom 112	Yes	W2	CMU	White	Chipping/Flaking	1	0.03	Negative	None	0	N/A	No	No	no	no	
1	1	112	Classroom 112	Yes	W3	CMU	White	Chipping	1	0.05	Negative	None	0	N/A	No	No	no	no	
1	1	112	Classroom 112	Yes	W4	CMU	White	Partially Inaccessible	0	0	Negative	None	0	N/A	No	No	no	no	
1	1	112	Classroom 112	Yes	Ceiling	Plaster	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	
1	1	112	Classroom 112	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	12 x 12 Floor Tiles
1	1	H19	Hallway between Classrooms 111 to 113	Yes	W1	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	Wall 1 is along Classroom 113 side.
1	1	H19	Hallway between Classrooms 111 to 113	Yes	W2	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	
1	1	H19	Hallway between Classrooms 111 to 113	Yes	W3	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	
1	1	H19	Hallway between Classrooms 111 to 113	Yes	W4	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	
1	1	H19	Hallway between Classrooms 111 to 113	Yes	Ceiling	Plaster	White	Efflorescence	5	0	Negative	None	0	N/A	No	Unknown	yes	no	
1	1	H19	Hallway between Classrooms 111 to 113	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	12 x 12 Floor Tiles
1	1	113	Classroom 113	Yes	W1	CMU	White	Chipping	2	0	Negative	None	0	N/A	No	No	no	no	
1	1	113	Classroom 113	Yes	Door Frame	Metal	Blue	Chipping	15	0.04	Negative	None	0	N/A	No	No	no	no	
1	1	113	Classroom 113	Yes	W2	CMU	White	Chipping	2	0.01	Negative	None	0	N/A	No	No	no	no	
1	1	113	Classroom 113	Yes	W3	CMU	White	Chipping	8	0.02	Negative	None	0	N/A	No	No	no	no	
1	1	113	Classroom 113	Yes	W4	CMU	White	Chipping/Holes	8	0.03	Negative	None	0	N/A	No	No	no	no	
1	1	113	Classroom 113	Yes	Ceiling	Plaster	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	
1	1	113	Classroom 113	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	12 x 12 Floor Tiles
1	1	114	Classroom 114	Yes	W1	CMU	White	Chipping	2	0.03	Negative	None	0	N/A	No	No	no	no	
1	1	114	Classroom 114	Yes	W2	CMU	White	Chipping	4	0.04	Negative	None	0	N/A	No	No	no	no	
1	1	114	Classroom 114	Yes	W3	CMU	White	Chipping	3	0.03	Negative	None	0	N/A	No	No	no	no	
1	1	114	Classroom 114	Yes	W4	CMU	White	Chipping/Cracking	12	0.05	Negative	None	0	N/A	No	No	no	no	
1	1	114	Classroom 114	Yes	Ceiling	Plaster	White	Chipping	1	0	Negative	None	0	N/A	No	No	no	no	
1	1	114	Classroom 114	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	12 x 12 Floor Tiles

Element Floor Space #			School District of Philadelphia										Inspection Dates: June 2021															
			Name of Inspector: Paul M. Davis		Lead Safe Certification Assessment Report																							
			Inspection Company: VERTEX		Bethune ES School								ULCS# 7510															
			On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes									
1	1	114A	SBTL Office 114A	Yes	W1	CMU	White	Chipping	2	0.04	Negative	None	0	N/A	No	No	no	no										
1	1	114A	SBTL Office 114A	Yes	W2	CMU	White	Chipping	4	0.02	Negative	None	0	N/A	No	No	no	no										
1	1	114A	SBTL Office 114A	Yes	Light Fixture	Metal	White	Flaking	1	0	Negative	None	0	N/A	No	No	no	no										
1	1	114A	SBTL Office 114A	Yes	W3	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no										
1	1	114A	SBTL Office 114A	Yes	W4	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no										
1	1	114A	SBTL Office 114A	Yes	Columns	Concrete	Brown	Flaking	2	0.01	Negative	None	0	N/A	No	No	no	no	On Bottom									
1	1	114A	SBTL Office 114A	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	2 x 4 Drop Ceiling									
1	1	114A	SBTL Office 114A	Yes	Ceiling	Plaster	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	In Corner									
1	1	114A	SBTL Office 114A	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	12 x 12 Floor Tiles									
1	1	110A	Girl's Restroom across from Classroom 114	Yes	W1	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no										
1	1	110A	Girl's Restroom across from Classroom 114	Yes	Door Frame	Metal	Blue	Chipping	8	0.18	Negative	None	0	N/A	No	No	no	no										
1	1	110A	Girl's Restroom across from Classroom 114	Yes	W2	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no										
1	1	110A	Girl's Restroom across from Classroom 114	Yes	W3	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no										
1	1	110A	Girl's Restroom across from Classroom 114	Yes	W4	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no										
1	1	110A	Girl's Restroom across from Classroom 114	Yes	Ceiling	Plaster	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no										
1	1	110A	Girl's Restroom across from Classroom 114	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	Ceramic Tiles									
1	1	H15	Hallway from Classroom 114 to Classroom 115	Yes	W1	CMU	White	Chipping	4	0.01	Negative	None	0	N/A	No	No	no	no	Wall 1 is along 114/114A side									
1	1	H15	Hallway from Classroom 114 to Classroom 115	Yes	W2	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no										
1	1	H15	Hallway from Classroom 114 to Classroom 115	Yes	W3	CMU	White	Chipping	4	0.01	Negative	None	0	N/A	No	No	no	no										
1	1	H15	Hallway from Classroom 114 to Classroom 115	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	Wall 4 is open to adjacent Hallway by 113									
1	1	H15	Hallway from Classroom 114 to Classroom 115	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	2 x 4 Drop Ceiling									
1	1	H15	Hallway from Classroom 114 to Classroom 115	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	12 x 12 Floor Tiles									
1	1	115	115 School Therapeutic Service (STS) Office	Yes	W1	CMU	Blue	None	0	N/A	N/A	None	0	N/A	No	No	no	no										
1	1	115	115 School Therapeutic Service (STS) Office	Yes	W2	CMU	Blue	None	0	N/A	N/A	None	0	N/A	No	No	no	no										
1	1	115	115 School Therapeutic Service (STS) Office	Yes	W3	CMU	Blue	None	0	N/A	N/A	None	0	N/A	No	No	no	no										
1	1	115	115 School Therapeutic Service (STS) Office	Yes	W4	CMU	Blue	None	0	N/A	N/A	None	0	N/A	No	No	no	no										
1	1	115	115 School Therapeutic Service (STS) Office	Yes	Ceiling	Plaster	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no										
1	1	115	115 School Therapeutic Service (STS) Office	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	12 x 12 Floor Tiles									
1	1	H111	Hallway adjacent to STS Office	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	Wall 1 is open to adjacent Hallway by Gym									
1	1	H111	Hallway adjacent to STS Office	Yes	W2	CMU	White	Chipping	20	0.05	Negative	None	0	N/A	No	No	no	no										
1	1	H111	Hallway adjacent to STS Office	Yes	W3	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no										
1	1	H111	Hallway adjacent to STS Office	Yes	W4	CMU	White	Chipping	12	0	Negative	None	0	N/A	No	No	no	no										
1	1	H111	Hallway adjacent to STS Office	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	2 x 4 Drop Ceiling									
1	1	H111	Hallway adjacent to STS Office	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	12 x 12 Floor Tiles									
1	1	S15	Stairwell C by Gym	Yes	W1	CMU	White	Chipping	10	0	Negative	None	0	N/A	No	No	no	no	Wall 1 is along Gym side									
1	1	S15	Stairwell C by Gym	Yes	W2	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no										
1	1	S15	Stairwell C by Gym	Yes	W3	CMU	White	Chipping	10	0	Negative	None	0	N/A	No	No	no	no										
1	1	S15	Stairwell C by Gym	Yes	Radiator Cover	Metal	White	Chipping	2	0	Negative	None	0	N/A	No	No	no	no										
1	1	S15	Stairwell C by Gym	Yes	W4	CMU	White	Chipping	1	0	Negative	None	0	N/A	No	No	no	no										
1	1	S15	Stairwell C by Gym	Yes	Door	Metal	Blue	Chipping	2	0	Negative	None	0	N/A	No	No	no	no										
1	1	S15	Stairwell C by Gym	Yes	Door Frame	Metal	Blue	Chipping	2	0	Negative	None	0	N/A	No	No	no	no										
1	1	S15	Stairwell C by Gym	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	2 x 4 Drop Ceiling									
1	1	S15	Stairwell C by Gym	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	12 x 12 Floor Tiles									
1	1	121	Nurse's Office	Yes	W1	CMU	White	Chipping	2	0	Negative	None	0	N/A	No	No	no	no	Wall 1 is from Hallway side									
1	1	121	Nurse's Office	Yes	Door Frame	Metal	Blue	Chipping	8	0.05	Negative	None	0	N/A	No	No	no	no	Includes two doors.									
1	1	121	Nurse's Office	Yes	W2	CMU	White	Chipping	6	0.02	Negative	None	0	N/A	No	No	no	no										
1	1	121	Nurse's Office	Yes	Door Frame	Metal	Blue	Chipping	12	0.06	Negative	None	0	N/A	No	No	no	no	Includes two doors.									
1	1	121	Nurse's Office	Yes	W3	CMU	White	Chipping	6	0	Negative	None	0	N/A	No	No	no	no										
1	1	121	Nurse's Office	Yes	W4	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no										
1	1	121	Nurse's Office	Yes	Window Frame	Metal	Blue	Chipping	4	0.04	Negative	None	0	N/A	No	No	no	no										
1	1	121	Nurse's Office	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	2 x 4 Drop Ceiling									
1	1	121	Nurse's Office	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	12 x 12 Floor Tiles									
1	1	121A	Paper Storage Room near Nurse's Office	yes	W1	CMU	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	Wall is Unpainted									
1	1	121A	Paper Storage Room near Nurse's Office	yes	W2	CMU	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	Wall is Unpainted									
1	1	121A	Paper Storage Room near Nurse's Office	yes	W3	CMU	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	Wall is Unpainted									
1	1	121A	Paper Storage Room near Nurse's Office	yes	W4	CMU	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	Wall is Unpainted									
1	1	121A	Paper Storage Room near Nurse's Office	yes	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	Ceiling is Unpainted									
1	1	121A	Paper Storage Room near Nurse's Office	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	Floor is Unpainted									
1	1	121B	Nurse's Patient Room	Yes	W1	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no										
1	1	121B	Nurse's Patient Room	Yes	Door Frame	Metal	Blue	Chipping	4	0.26	Negative	None	0	N/A	No	No	no	no										
1	1	121B	Nurse's Patient Room	Yes	W2	CMU	White	Chipping	1	0.02	Negative	None	0	N/A	No	No	no	no										
1	1	121B	Nurse's Patient Room	Yes	W3	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no										
1	1	121B	Nurse's Patient Room	Yes	W4	CMU	White	Chipping	1	0.01	Negative	None	0	N/A	No	No	no	no										
1	1	121B	Nurse's Patient Room	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	2 x 4 Drop Ceiling									
1	1	121B	Nurse's Patient Room	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	12 x 12 Floor Tiles									
1	1	121E	Nurse's Storage Room	yes	W1	CMU	White	Partially Inaccessible	N/A	0.01	Negative	None	0	N/A	No	No	no	no										
1	1	121E	Nurse's Storage Room	yes	W2	CMU	White	Partially Inaccessible	N/A	0.01	Negative	None	0	N/A	No	No	no	no										
1	1	121E	Nurse's Storage Room	yes	W3	CMU	White	Partially Inaccessible	N/A	0.06	Negative	None	0	N/A	No	No	no	no										
1	1	121E	Nurse's Storage Room	yes	W4	CMU	White	Partially Inaccessible	N/A	0.02	Negative	None	0	N/A	No	No	no	no										

			School District of Philadelphia																					
			Name of Inspector: Paul M. Davis		Lead Safe Certification Assessment Report																Inspection Dates: June 2021			
Inspection Company: VERTEX		Bethune ES School									ULCS# 7510													
		Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes			
1	1	121E	Nurse's Storage Room	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	2 x 4 Drop Ceiling				
1	1	121E	Nurse's Storage Room	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	12 x 12 Floor Tiles				
1	1	121F	Nurse's Storage Room Closet	yes	W1	CMU	White	None	0	N/A	N/A	N/A	None	0	N/A	No	No	no	no					
1	1	121F	Nurse's Storage Room Closet	yes	W2	CMU	White	None	0	N/A	N/A	N/A	None	0	N/A	No	No	no	no					
1	1	121F	Nurse's Storage Room Closet	yes	W3	CMU	White	None	0	N/A	N/A	N/A	None	0	N/A	No	No	no	no					
1	1	121F	Nurse's Storage Room Closet	yes	W4	CMU	White	None	0	N/A	N/A	N/A	None	0	N/A	No	No	no	no					
1	1	121F	Nurse's Storage Room Closet	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	2 x 4 Drop Ceiling				
1	1	121F	Nurse's Storage Room Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	12 x 12 Floor Tiles				
1	1	121G	Nurse's Office Restroom	Yes	W1	CMU	White	None	0	N/A	N/A	N/A	None	0	N/A	No	No	no	no					
1	1	121G	Nurse's Office Restroom	Yes	W2	CMU	White	Chipping/Flaking	2	0.04	Negative	N/A	None	0	N/A	No	No	no	no					
1	1	121G	Nurse's Office Restroom	Yes	W3	CMU	White	Chipping	1	0.05	Negative	N/A	None	0	N/A	No	No	no	no					
1	1	121G	Nurse's Office Restroom	Yes	W4	CMU	White	None	0	N/A	N/A	N/A	None	0	N/A	No	No	no	no					
1	1	121G	Nurse's Office Restroom	Yes	Ceiling	Plaster	White	None	0	N/A	N/A	N/A	None	0	N/A	No	No	no	no					
1	1	121G	Nurse's Office Restroom	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	Ceramic Tiles				
1	1	H111A	Hallway to Gym from Hall by STS Office (Entrance area to Gym)	Yes	W1	CMU	White	None	0	N/A	N/A	N/A	None	0	N/A	No	No	no	no	Wall 1 ia along Gym side				
1	1	H111A	Hallway to Gym from Hall by STS Office (Entrance area to Gym)	Yes	W2	CMU	White	None	0	N/A	N/A	N/A	None	0	N/A	No	No	no	no					
1	1	H111A	Hallway to Gym from Hall by STS Office (Entrance area to Gym)	Yes	W3	CMU	White	None	0	N/A	N/A	N/A	None	0	N/A	No	No	no	no					
1	1	H111A	Hallway to Gym from Hall by STS Office (Entrance area to Gym)	Yes	W4	CMU	White	None	0	N/A	N/A	N/A	None	0	N/A	No	No	no	no					
1	1	H111A	Hallway to Gym from Hall by STS Office (Entrance area to Gym)	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	2 x 4 Drop Ceiling				
1	1	H111A	Hallway to Gym from Hall by STS Office (Entrance area to Gym)	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	12 x 12 Floor Tiles				
1	1	116	Gym	Yes	W1	CMU	Multi	Chipping	25	0.05	Negative	N/A	None	0	Negative	No	No	no	no					
1	1	116	Gym	Yes	Door Frame	Metal	Blue	Chipping	2	0.11	Negative	N/A	None	0	N/A	No	No	no	no	Includes four doors				
1	1	116	Gym	Yes	W2	CMU	Blue	Chipping	25	0.04	Negative	N/A	None	0	N/A	No	No	no	no					
1	1	116	Gym	Yes	W2	Plaster	White	None	0	N/A	N/A	N/A	None	0	N/A	No	No	no	no					
1	1	116	Gym	Yes	Window Frame	Metal	White	Chipping	5	0.01	Negative	N/A	None	0	N/A	No	No	no	no	To gym office				
1	1	116	Gym	Yes	Door	Metal	Blue	Chipping	1	0	Negative	N/A	None	0	N/A	No	No	no	no					
1	1	116	Gym	Yes	W3	CMU	Blue	Chipping	25	0.12	Negative	N/A	None	0	N/A	No	No	no	no					
1	1	116	Gym	Yes	W3	Plaster	White	None	0	N/A	N/A	N/A	None	0	N/A	No	No	no	no					
1	1	116	Gym	Yes	W4	CMU	Blue	Chipping	25	0.02	Negative	N/A	None	0	N/A	No	No	no	no					
1	1	116	Gym	Yes	W4	Plaster	White	None	0	N/A	N/A	N/A	None	0	N/A	No	No	no	no					
1	1	116	Gym	Yes	Basketball Backboards	Composite	White	Chipping	4	0.04	Negative	N/A	None	0	N/A	No	No	no	no					
1	1	116	Gym	Yes	Basketball Backboard Frames	Metal	Black	Chipping	4	0.02	Negative	N/A	None	0	N/A	No	No	no	no					
1	1	116	Gym	Yes	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	None	0	N/A	No	No	no	no					
1	1	116	Gym	Yes	Ceiling	Plaster	White	None	0	N/A	N/A	N/A	None	0	N/A	No	No	no	no					
1	1	116	Gym	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	12 x 12 Floor Tiles				
1	1	116A	Gym Office	Yes	W1	CMU	White	None	0	N/A	N/A	N/A	None	0	N/A	No	No	no	no					
1	1	116A	Gym Office	Yes	Door Frame	Metal	White	Chipping	6	0.04	Negative	N/A	None	0	N/A	No	No	no	no					
1	1	116A	Gym Office	Yes	W2	CMU	White	Chipping	1	0.04	Negative	N/A	None	0	N/A	No	No	no	no					
1	1	116A	Gym Office	Yes	W3	CMU	White	None	0	N/A	N/A	N/A	None	0	N/A	No	No	no	no					
1	1	116A	Gym Office	Yes	Door Frame	Metal	White	Chipping	5	0.01	Negative	N/A	None	0	N/A	No	No	no	no					
1	1	116A	Gym Office	Yes	W4	CMU	White	Chipping/Cracking	5	0.07	Negative	N/A	None	0	N/A	No	No	no	no					
1	1	116A	Gym Office	Yes	Ceiling	Plaster	White	None	0	N/A	N/A	N/A	None	0	N/A	No	No	no	no					
1	1	116A	Gym Office	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	12 x 12 Floor Tiles				
1	1	116B	Gym Office Restroom	Yes	W1	CMU	White	None	0	N/A	N/A	N/A	None	0	N/A	No	No	no	no					
1	1	116B	Gym Office Restroom	Yes	W2	CMU	White	None	0	N/A	N/A	N/A	None	0	N/A	No	No	no	no					
1	1	116B	Gym Office Restroom	Yes	W3	CMU	White	None	0	N/A	N/A	N/A	None	0	N/A	No	No	no	no					
1	1	116B	Gym Office Restroom	Yes	W4	CMU	White	None	0	N/A	N/A	N/A	None	0	N/A	No	No	no	no					
1	1	116B	Gym Office Restroom	Yes	Ceiling	Plaster	White	None	0	N/A	N/A	N/A	None	0	N/A	No	No	no	no					
1	1	116B	Gym Office Restroom	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	Ceramic Tiles				
1	1	116C	Girl's Locker Room	Yes	W1	CMU	White	None	0	N/A	N/A	N/A	None	0	N/A	No	No	no	no					
1	1	116C	Girl's Locker Room	Yes	Door Frame	Metal	Brown	Chipping	3	0.03	Negative	N/A	None	0	N/A	No	No	no	no					
1	1	116C	Girl's Locker Room	Yes	W2	CMU	White	None	0	N/A	N/A	N/A	None	0	N/A	No	No	no	no					
1	1	116C	Girl's Locker Room	Yes	W3	CMU	White	None	0	N/A	N/A	N/A	None	0	N/A	No	No	no	no					
1	1	116C	Girl's Locker Room	Yes	W4	CMU	White	Chipping	4	0	Negative	N/A	None	0	N/A	No	No	no	no					
1	1	116C	Girl's Locker Room	Yes	Ceiling	Plaster	White	Efflorescence	50	0	Negative	N/A	None	0	N/A	No	Unknown	yes	no					
1	1	116C	Girl's Locker Room	Yes	Bench Supports	Metal	Pink	Chipping	4	0.12	Negative	N/A	None	0	N/A	No	No	no	no					
1	1	116C	Girl's Locker Room	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	Ceramic Tiles				
1	1	116D	Boy's Locker Room	Yes	W1	CMU	White	None	0	N/A	N/A	N/A	None	0	N/A	No	No	no	no					
1	1	116D	Boy's Locker Room	Yes	Door Frame	Metal	Brown	Chipping	2	0.07	Negative	N/A	None	0	N/A	No	No	no	no					
1	1	116D	Boy's Locker Room	Yes	W2	CMU	White	None	0	N/A	N/A	N/A	None	0	N/A	No	No	no	no					
1	1	116D	Boy's Locker Room	Yes	W3	CMU	White	Cracking	10	0	Negative	N/A	None	0	N/A	No	No	no	no					
1	1	116D	Boy's Locker Room	Yes	W4	CMU	White	Cracking	6	0.03	Negative	N/A	None	0	N/A	No	No	no	no					

			School District of Philadelphia																
			Name of Inspector: Paul M. Davis		Lead Safe Certification Assessment Report						Inspection Dates: June 2021								
Inspection Company: VERTEX			Bethune ES School										ULCS# 7510						
E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes
1	1	116D	Boy's Locker Room	Yes	Ceiling	Plaster	White	Efflorescence	6	0	Negative	None	0	N/A	No	Unknown	yes	no	
1	1	116D	Boy's Locker Room	Yes	Bench Supports	Metal	Pink	Chipping	6	0.15	Negative	None	0	N/A	No	No	no	no	
1	1	116D	Boy's Locker Room	Yes	Floor	N/A	N/A		N/A	N/A	N/A	None	0	N/A	No	No	no	no	Ceramic Tiles
1	1	116E	Gym Storage	yes	W1	CMU	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	Wall is Unpainted
1	1	116E	Gym Storage	yes	Door Frame	Metal	Pink	Chipping	10	0.15	Negative	None	0	N/A	No	No	no	no	
1	1	116E	Gym Storage	yes	W2	CMU	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	Wall is Unpainted
1	1	116E	Gym Storage	yes	W3	CMU	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	Wall is Unpainted
1	1	116E	Gym Storage	yes	W4	CMU	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	Wall is Unpainted
1	1	116E	Gym Storage	yes	Supports	Metal	Red	Chipping	4	0.08	Negative	None	0	N/A	No	No	no	no	
1	1	116E	Gym Storage	yes	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	Ceiling is Unpainted
1	1	116E	Gym Storage	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	Floor is Unpainted
1	1	H111B	Hallway to Gym adjacent to Main Entrance	Yes	W1	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	Wall 1 is the exterior wall
1	1	H111B	Hallway to Gym adjacent to Main Entrance	Yes	W2	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	
1	1	H111B	Hallway to Gym adjacent to Main Entrance	Yes	Entrance Frame	Metal	White	Chipping	3	0.24	Negative	None	0	N/A	No	No	no	no	
1	1	H111B	Hallway to Gym adjacent to Main Entrance	Yes	W3	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	
1	1	H111B	Hallway to Gym adjacent to Main Entrance	Yes	W4	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	
1	1	H111B	Hallway to Gym adjacent to Main Entrance	Yes	Doors	Metal	Blue	Chipping	2	0	Negative	None	0	N/A	No	No	no	no	
1	1	H111B	Hallway to Gym adjacent to Main Entrance	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	2 x 4 Drop Ceiling
1	1	H111B	Hallway to Gym adjacent to Main Entrance	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	12 x 12 Floor Tiles
1	1	H114	Main Entrance Hallway	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	Wall 1 is Entrance Doors; No Walls
1	1	H114	Main Entrance Hallway	Yes	Doors	Metal	Blue	Chipping	4	0	Negative	None	0	N/A	No	No	no	no	
1	1	H114	Main Entrance Hallway	Yes	W2	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	
1	1	H114	Main Entrance Hallway	Yes	Radiator Cover	Metal	White	Chipping	1	0	Negative	None	0	N/A	No	No	no	no	
1	1	H114	Main Entrance Hallway	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	Wall 3 is Glass Windows and Doors to Hall outside Main Office
1	1	H114	Main Entrance Hallway	Yes	W4	CMU	White	Chipping	2	0	Negative	None	0	N/A	No	No	no	no	
1	1	H114	Main Entrance Hallway	Yes	Radiator Cover	Metal	White	Chipping	1	0	Negative	None	0	N/A	No	No	no	no	
1	1	H114	Main Entrance Hallway	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	2 x 4 Drop Ceiling
1	1	H114	Main Entrance Hallway	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	12 x 12 Floor Tiles
1	1	H110	Hallway adjacent to Main Office	Yes	W1	CMU	White	Chipping	12	0	Negative	None	0	N/A	No	No	no	no	Wall 1 is along Main Entrance Lobby side
1	1	H110	Hallway adjacent to Main Office	Yes	W2	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	
1	1	H110	Hallway adjacent to Main Office	Yes	W3	CMU	White	Chipping	6	0.01	Negative	None	0	N/A	No	No	no	no	
1	1	H110	Hallway adjacent to Main Office	Yes	Door Frame	Metal	White	Chipping	4	0.04	Negative	None	0	N/A	No	No	no	no	
1	1	H110	Hallway adjacent to Main Office	Yes	W4	CMU	White	Chipping	2	0.01	Negative	None	0	N/A	No	No	no	no	
1	1	H110	Hallway adjacent to Main Office	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	2 x 4 Drop Ceiling
1	1	H110	Hallway adjacent to Main Office	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	12 x 12 Floor Tiles
1	1	122F	Storage Room adjacent to Main Office	yes	W1	CMU	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	Wall is Unpainted
1	1	122F	Storage Room adjacent to Main Office	yes	Door Frame	Metal	Pink	Chipping	6	0.07	Negative	None	0	N/A	No	No	no	no	Wall is Unpainted
1	1	122F	Storage Room adjacent to Main Office	yes	W2	CMU	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	Wall is Unpainted
1	1	122F	Storage Room adjacent to Main Office	yes	W3	CMU	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	Wall is Unpainted
1	1	122F	Storage Room adjacent to Main Office	yes	W4	CMU	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	Wall is Unpainted
1	1	122F	Storage Room adjacent to Main Office	yes	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	Ceiling is Unpainted
1	1	122F	Storage Room adjacent to Main Office	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	Floor is Unpainted
1	1	122	Main Office	Yes	W1	CMU	Yellow	None	0	N/A	N/A	None	0	N/A	No	No	no	no	
1	1	122	Main Office	Yes	W2	CMU	Yellow	Cracking	2	0.02	Negative	None	0	N/A	No	No	no	no	
1	1	122	Main Office	Yes	Door Frame	Metal	Blue	Cracking	1	0.07	Negative	None	0	N/A	No	No	no	no	Includes two doors
1	1	122	Main Office	Yes	W3	CMU	Yellow	Chipping	1	0.02	Negative	None	0	N/A	No	No	no	no	
1	1	122	Main Office	Yes	W4	CMU	Yellow	Cracking	3	0.02	Negative	None	0	Negative	No	No	no	no	
1	1	122	Main Office	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	2 x 4 Drop Ceiling
1	1	122	Main Office	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	12 x 12 Floor Tiles
1	1	122	Main Office	Yes	Cabinets	Metal	Blue	Scrapes	4	0.03	Negative	None	0	N/A	No	No	no	no	
1	1	121C	Main Office Storage Room (Administrative Assistant)	yes	W1	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	
1	1	121C	Main Office Storage Room (Administrative Assistant)	yes	W2	CMU	White	Cracking	5	0.01	Negative	None	0	N/A	No	No	no	no	
1	1	121C	Main Office Storage Room (Administrative Assistant)	yes	W3	CMU	White	Cracking	10	0.01	Negative	None	0	N/A	No	No	no	no	
1	1	121C	Main Office Storage Room (Administrative Assistant)	yes	W4	CMU	White	Cracking	2	0.04	Negative	None	0	N/A	No	No	no	no	
1	1	121C	Main Office Storage Room (Administrative Assistant)	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	2 x 4 Drop Ceiling
1	1	121C	Main Office Storage Room (Administrative Assistant)	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	12 x 12 Floor Tiles
1	1	121D	Main Office Storage Room Closet	yes	W1	CMU	White	Cracking	1	0.05	Negative	None	0	N/A	No	No	no	no	
1	1	121D	Main Office Storage Room Closet	yes	W2	CMU	White	Cracking	6	0.01	Negative	None	0	N/A	No	No	no	no	
1	1	121D	Main Office Storage Room Closet	yes	Shelving	Wood	White	Friction	4	0.02	Negative	None	0	N/A	No	No	no	no	
1	1	121D	Main Office Storage Room Closet	yes	W3	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	
1	1	121D	Main Office Storage Room Closet	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	No Wall 4
1	1	121D	Main Office Storage Room Closet	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	2 x 4 Drop Ceiling
1	1	121D	Main Office Storage Room Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	9 x 9 Floor Tiles
1	1	122D	Principal's Office	Yes	W1	CMU	White	Partially Inaccessible	N/A	0	Negative	None	0	N/A	No	No	no	no	
1	1	122D	Principal's Office	Yes	W2	CMU	White	Partially Inaccessible/Flaking	2	0	Negative	None	0	N/A	No	No	no	no	
1	1	122D	Principal's Office	Yes	W3	CMU	White	Partially Inaccessible	N/A	0	Negative	None	0	N/A	No	No	no	no	
1	1	122D	Principal's Office	Yes	W4	CMU	White	Partially Inaccessible	N/A	0.01	Negative	None	0	N/A	No	No	no	no	
1	1	122D	Principal's Office	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	2 x 4 Drop Ceiling

Element Floor Space #			School District of Philadelphia										Inspection Dates: June 2021						
			Name of Inspector: Paul M. Davis		Lead Safe Certification Assessment Report														
			Inspection Company: VERTEX		Bethune ES School							ULCS# 7510							
			On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes
1	1	122D	Principal's Office	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	12 x 12 Floor Tiles
1	1	122H	Principal's Office Closet	yes	W1	CMU	Pink	None	0	N/A	N/A	None	0	N/A	No	No	no	no	
1	1	122H	Principal's Office Closet	yes	W2	CMU	Pink	Partially Inaccessible	N/A	0	Negative	None	0	N/A	No	No	no	no	
1	1	122H	Principal's Office Closet	yes	W3	CMU	Pink	Partially Inaccessible	N/A	0	Negative	None	0	N/A	No	No	no	no	
1	1	122H	Principal's Office Closet	yes	Shelving	Wood	Tan	Partially Inaccessible	N/A	0	Negative	None	0	N/A	No	No	no	no	
1	1	122H	Principal's Office Closet	yes	W4	CMU	Pink	Partially Inaccessible	N/A	0	Negative	None	0	N/A	No	No	no	no	
1	1	122H	Principal's Office Closet	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	2 x 4 Drop Ceiling
1	1	122H	Principal's Office Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	9 x 9 Floor Tiles
1	1	122J	Principal's Office Restroom	Yes	W1	CMU	White	Cracking	2	0.08	Negative	None	0	N/A	No	No	no	no	
1	1	122J	Principal's Office Restroom	Yes	W2	CMU	White	Chipping	1	0.02	Negative	None	0	N/A	No	No	no	no	
1	1	122J	Principal's Office Restroom	Yes	W3	CMU	White	Craking/Chipping	8	0.04	Negative	None	0	N/A	No	No	no	no	
1	1	122J	Principal's Office Restroom	Yes	W4	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	
1	1	122J	Principal's Office Restroom	Yes	Ceiling	Plaster	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	
1	1	122J	Principal's Office Restroom	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	Ceramic Tiles
1	1	122G	Conference Room A adjacent to Principal's Office	Yes	W1	CMU	Yellow	None	0	N/A	N/A	None	0	N/A	No	No	no	no	Wall 1 is from Main Office side
1	1	122G	Conference Room A adjacent to Principal's Office	Yes	W2	CMU	Yellow	None	0	N/A	N/A	None	0	N/A	No	No	no	no	
1	1	122G	Conference Room A adjacent to Principal's Office	Yes	W3	CMU	Yellow	None	0	N/A	N/A	None	0	N/A	No	No	no	no	
1	1	122G	Conference Room A adjacent to Principal's Office	Yes	W4	CMU	Yellow	None	0	N/A	N/A	None	0	N/A	No	No	no	no	
1	1	122G	Conference Room A adjacent to Principal's Office	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	2 x 4 Drop Ceiling
1	1	122G	Conference Room A adjacent to Principal's Office	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	12 x 12 Floor Tiles
1	1	122A	Server Room 122A	No	W1	CMU	White	Partially Inaccessible	N/A	0.02	Negative	None	0	N/A	No	No	no	no	
1	1	122A	Server Room 122A	No	Door Frame	Metal	Blue	Friction	4	0.09	Negative	None	0	N/A	No	No	no	no	
1	1	122A	Server Room 122A	No	Shelving	Wood	White	Partially Inaccessible	N/A	0.01	Negative	None	0	N/A	No	No	no	no	
1	1	122A	Server Room 122A	No	W2	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	
1	1	122A	Server Room 122A	No	W3	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	
1	1	122A	Server Room 122A	No	W4	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	
1	1	122A	Server Room 122A	No	Shelving	Wood	White	Friction	2	0.02	Negative	None	0	N/A	No	No	no	no	
1	1	122A	Server Room 122A	No	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	2 x 4 Drop Ceiling
1	1	122A	Server Room 122A	No	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	12 x 12 Floor Tiles
1	1	122B	Main Office Copy Room	No	W1	CMU	White	Cracking	5	0	Negative	None	0	N/A	No	No	no	no	
1	1	122B	Main Office Copy Room	No	W2	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	
1	1	122B	Main Office Copy Room	No	W3	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	
1	1	122B	Main Office Copy Room	No	W4	CMU	White	Cracking	5	0	Negative	None	0	N/A	No	No	no	no	
1	1	122B	Main Office Copy Room	No	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	2 x 4 Drop Ceiling
1	1	122B	Main Office Copy Room	No	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	12 x 12 Floor Tiles
1	1	H112B	Hallway from Server Room to Hallway by Room 100	Yes	W1	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	Wall 1 is along 122A (Server Room) side
1	1	H112B	Hallway from Server Room to Hallway by Room 100	Yes	W2	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	
1	1	H112B	Hallway from Server Room to Hallway by Room 100	Yes	W3	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	
1	1	H112B	Hallway from Server Room to Hallway by Room 100	Yes	W4	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	
1	1	H112B	Hallway from Server Room to Hallway by Room 100	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	2 x 4 Drop Ceiling
1	1	H112B	Hallway from Server Room to Hallway by Room 100	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	12 x 12 Floor Tiles
1	1	118A	Psychologist's Office 118A	Yes	W1	CMU	White	Cracking	4	0	Negative	None	0	N/A	No	No	no	no	
1	1	118A	Psychologist's Office 118A	Yes	Door Frame	Metal	Blue	Friction	1	0.08	Negative	None	0	N/A	No	No	no	no	
1	1	118A	Psychologist's Office 118A	Yes	W2	CMU	White	Chipping	2	0.04	Negative	None	0	N/A	No	No	no	no	
1	1	118A	Psychologist's Office 118A	Yes	W3	CMU	White	Chipping	2	0	Negative	None	0	N/A	No	No	no	no	
1	1	118A	Psychologist's Office 118A	Yes	W4	CMU	White	Chipping	2	0	Negative	None	0	N/A	No	No	no	no	
1	1	118A	Psychologist's Office 118A	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	2 x 4 Drop Ceiling
1	1	118A	Psychologist's Office 118A	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	12 x 12 Floor Tiles
1	1	118B	Counselor's Office 118B	Yes	W1	CMU	White	Chipping	25	0	Negative	None	0	N/A	No	No	no	no	
1	1	118B	Counselor's Office 118B	Yes	W2	CMU	White	Cracking/Chipping	12	0	Negative	None	0	N/A	No	No	no	no	
1	1	118B	Counselor's Office 118B	Yes	W3	CMU	White	Chipping	12	0	Negative	None	0	N/A	No	No	no	no	
1	1	118B	Counselor's Office 118B	Yes	W4	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	
1	1	118B	Counselor's Office 118B	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	2 x 4 Drop Ceiling
1	1	118B	Counselor's Office 118B	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	12 x 12 Floor Tiles
1	1	118C	Room 118C Conference Room B	Yes	W1	CMU	White	Partially Inaccessible	N/A	0	Negative	None	0	N/A	No	No	no	no	
1	1	118C	Room 118C Conference Room B	Yes	W2	CMU	White	Partially Inaccessible	N/A	0	Negative	None	0	N/A	No	No	no	no	
1	1	118C	Room 118C Conference Room B	Yes	W3	CMU	White	Partially Inaccessible	N/A	0.01	Negative	None	0	N/A	No	No	no	no	
1	1	118C	Room 118C Conference Room B	Yes	W4	CMU	White	Partially Inaccessible	N/A	0	Negative	None	0	N/A	No	No	no	no	
1	1	118C	Room 118C Conference Room B	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	2 x 4 Drop Ceiling
1	1	118C	Room 118C Conference Room B	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	12 x 12 Floor Tiles
1	1	H112A	Hallway adjacent to Conference Room B	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	Wall 1 is open to adjacent Hallway by Room 118A
1	1	H112A	Hallway adjacent to Conference Room B	Yes	W2	CMU	White	Chipping/Flaking	1	0	Negative	None	0	N/A	No	No	no	no	
1	1	H112A	Hallway adjacent to Conference Room B	Yes	W3	CMU	White	Cracking/Chipping	2	0	Negative	None	0	N/A	No	No	no	no	
1	1	H112A	Hallway adjacent to Conference Room B	Yes	W4	CMU	White	Cracking	10	0	Negative	None	0	N/A	No	No	no	no	
1	1	H112A	Hallway adjacent to Conference Room B	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	2 x 4 Drop Ceiling
1	1	H112A	Hallway adjacent to Conference Room B	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	12 x 12 Floor Tiles
1	1	118D	Office adjacent to Conference Room B	Yes	W1	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	
1	1	118D	Office adjacent to Conference Room B	Yes	Door Frame	Metal	Blue	Chipping	3	0.22	Negative	None	0	N/A	No	No	no	no	
1	1	118D	Office adjacent to Conference Room B	Yes	W2	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	

Element Floor Space #			School District of Philadelphia										Inspection Dates: June 2021																
			Name of Inspector: Paul M. Davis		Lead Safe Certification Assessment Report																								
			Inspection Company: VERTEX		Bethune ES School										ULCS# 7510														
			On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes										
1	1	118D	Office adjacent to Conference Room B	Yes	W3	CMU	White	Chipping	1	0.03	Negative	None	0	N/A	No	No	no	no											
1	1	118D	Office adjacent to Conference Room B	Yes	W4	CMU	White	Cracking	10	0.01	Negative	None	0	N/A	No	No	no	no											
1	1	118D	Office adjacent to Conference Room B	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	2 x 4 Drop Ceiling										
1	1	118D	Office adjacent to Conference Room B	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	12 x 12 Floor Tiles										
1	1	S16	Stairwell D by Cafeteria	Yes	W1	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	Wall 1 is Cafeteria/Auditorium side										
1	1	S16	Stairwell D by Cafeteria	Yes	W2	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no											
1	1	S16	Stairwell D by Cafeteria	Yes	W3	CMU	White	Chipping/Cracking	3	0.03	Negative	None	0	N/A	No	No	no	no											
1	1	S16	Stairwell D by Cafeteria	Yes	Door	Metal	Blue	Chipping	2	0	Negative	None	0	N/A	No	No	no	no											
1	1	S16	Stairwell D by Cafeteria	Yes	W4	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no											
1	1	S16	Stairwell D by Cafeteria	Yes	Ceiling	Concrete	White	Cracking	8	0.01	Negative	None	0	Negative	No	No	no	no											
1	1	S16	Stairwell D by Cafeteria	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	12 x 12 Floor Tiles										
1	1	H110B	Hallway to Cafeteria	Yes	W1	CMU	White	Chipping	4	0.04	Negative	None	0	N/A	No	No	no	no	Wall 1 is Cafeteria side										
1	1	H110B	Hallway to Cafeteria	Yes	W2	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no											
1	1	H110B	Hallway to Cafeteria	Yes	W3	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no											
1	1	H110B	Hallway to Cafeteria	Yes	Door	Metal	Blue	Chipping	1	0	Negative	None	0	N/A	No	No	no	no											
1	1	H110B	Hallway to Cafeteria	Yes	W4	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no											
1	1	H110B	Hallway to Cafeteria	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	2 x 4 Drop Ceiling										
1	1	H110B	Hallway to Cafeteria	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	12 x 12 Floor Tiles										
1	1	117D	Cafeteria	Yes	W1	Ceramic Tile	N/A	None	0	1.5	Positive	None	0	N/A	No	No	no	no	Wall 1 is from Main Lobby. Lead glazing on ceramic tiles (unpainted).										
1	1	117D	Cafeteria	Yes	W1	Sheetrock	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no											
1	1	117D	Cafeteria	Yes	Door	Metal	Blue	Chipping	2	0	Negative	None	0	N/A	No	No	no	no											
1	1	117D	Cafeteria	Yes	Door Frame	Metal	Blue	Chipping	1	0.15	Negative	None	0	N/A	No	No	no	no											
1	1	117D	Cafeteria	Yes	Door Frame	Metal	Tan	Flaking	15	0.03	Negative	None	0	N/A	No	No	no	no	Door to 117H Storage										
1	1	117D	Cafeteria	Yes	W2	CMU	Multi	None	0	N/A	N/A	None	0	Positive	No	No	no	no	Point Count Trace - Chrysotile										
1	1	117D	Cafeteria	Yes	W2	Sheetrock	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no											
1	1	117D	Cafeteria	Yes	Columns	Concrete	Multi	Chipping	6	0	Negative	None	0	Negative	No	No	no	no											
1	1	117D	Cafeteria	Yes	W3	CMU	Yellow	Chipping	2	0	Negative	None	0	N/A	No	No	no	no											
1	1	117D	Cafeteria	Yes	W4	CMU	Multi	Chipping	8	0	Negative	None	0	N/A	No	No	no	no											
1	1	117D	Cafeteria	Yes	W4	Sheetrock	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no											
1	1	117D	Cafeteria	Yes	Columns	Concrete	Tan	Chipping	4	0	Negative	None	0	N/A	No	No	no	no											
1	1	117D	Cafeteria	Yes	Door Frame	Metal	Yellow	Chipping	5	0.17	Negative	None	0	N/A	No	No	no	no											
1	1	117D	Cafeteria	Yes	Ceiling	Concrete	White	None	0	N/A	N/A	None	0	Negative	No	No	no	no											
1	1	117D	Cafeteria	Yes	Ceiling	Plaster	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no											
1	1	117D	Cafeteria	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	12 x 12 Floor Tiles										
1	1	117C	Kitchen	No	W1	CMU	Blue/White	None	0	N/A	N/A	None	0	N/A	No	No	no	no											
1	1	117C	Kitchen	No	W2	CMU	Blue/White	None	0	N/A	N/A	None	0	N/A	No	No	no	no											
1	1	117C	Kitchen	No	W3	CMU	Blue/White	None	0	N/A	N/A	None	0	N/A	No	No	no	no											
1	1	117C	Kitchen	No	Door Frame	Metal	White	Chipping	5	0.18	Negative	None	0	N/A	No	No	no	no											
1	1	117C	Kitchen	No	W4	CMU	Blue/White	None	0	N/A	N/A	None	0	N/A	No	No	no	no											
1	1	117C	Kitchen	No	Radiator	Metal	Red	Chipping	2	0.04	Negative	None	0	N/A	No	No	no	no											
1	1	117C	Kitchen	No	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	2 x 4 Drop Ceiling										
1	1	117C	Kitchen	No	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	12 x 12 Floor Tiles										
1	1	117B	Dishwashing Room	No	W1	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	Wall 1 is from Kitchen side										
1	1	117B	Dishwashing Room	No	W2	CMU	White	Chipping	4	0.02	Negative	None	0	N/A	No	No	no	no											
1	1	117B	Dishwashing Room	No	W3	CMU	White	Partially Inaccessible	0	0.01	Negative	None	0	N/A	No	No	no	no											
1	1	117B	Dishwashing Room	No	W4	CMU	White	Partially Inaccessible	0	0.04	Negative	None	0	N/A	No	No	no	no											
1	1	117B	Dishwashing Room	No	Radiator Cover	Metal	White	Chipping	1	0.02	Negative	None	0	N/A	No	No	no	no											
1	1	117B	Dishwashing Room	No	Ceiling	Concrete	White	Flaking	8	0.01	Negative	None	0	N/A	No	No	no	no											
1	1	117B	Dishwashing Room	No	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	12 x 12 Floor Tiles										
1	1	H113A	Hallway from Kitchen to Stage	Yes	W1	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	Wall 1 is Stage side										
1	1	H113A	Hallway from Kitchen to Stage	Yes	W2	CMU	White	Cracking	4	0	Negative	None	0	N/A	No	No	no	no											
1	1	H113A	Hallway from Kitchen to Stage	Yes	Door	Metal	Blue	Chipping	2	0	Negative	None	0	N/A	No	No	no	no	Door to Outside										
1	1	H113A	Hallway from Kitchen to Stage	Yes	Door Frame	Metal	Blue	Chipping	2	0	Negative	None	0	N/A	No	No	no	no	Door to Outside										
1	1	H113A	Hallway from Kitchen to Stage	Yes	W3	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no											
1	1	H113A	Hallway from Kitchen to Stage	Yes	W4	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no											
1	1	H113A	Hallway from Kitchen to Stage	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	2 x 4 Drop Ceiling										
1	1	H113A	Hallway from Kitchen to Stage	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	12 x 12 Floor Tiles										
1	1	117E	Lost and Found	yes	W1	No Access	No Access	No Access	No Access	No Access	No Access	None	0	N/A	No	No	no	no											
1	1	117E	Lost and Found	yes	W2	No Access	No Access	No Access	No Access	No Access	No Access	None	0	N/A	No	No	no	no											
1	1	117E	Lost and Found	yes	W3	No Access	No Access	No Access	No Access	No Access	No Access	None	0	N/A	No	No	no	no											
1	1	117E	Lost and Found	yes	W4	No Access	No Access	No Access	No Access	No Access	No Access	None	0	N/A	No	No	no	no											
1	1	117E	Lost and Found	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	None	0	N/A	No	No	no	no											
1	1	117E	Lost and Found	yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access	None	0	N/A	No	No	no	no											
1	1	117F	Women's Restroom Entrance Lobby	Yes	W1	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no											
1	1	117F	Women's Restroom Entrance Lobby	Yes	W2	CMU	White	Cracking	3	0	Negative	None	0	N/A	No	No	no	no											
1	1	117F	Women's Restroom Entrance Lobby	Yes	W3	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no											
1	1	117F	Women's Restroom Entrance Lobby	Yes	W4	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no											
1	1	117F	Women's Restroom Entrance Lobby	Yes	Ceiling	Plaster	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no											
1	1	117F	Women's Restroom Entrance Lobby	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	Ceramic Tiles										

			School District of Philadelphia																
			Name of Inspector: Paul M. Davis		Lead Safe Certification Assessment Report								Inspection Dates: June 2021						
			Inspection Company: VERTEX		Bethune ES School								ULCS# 7510						
E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes
1	1	117G	Men's Restroom in Entrance Lobby	Yes	W1	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	
1	1	117G	Men's Restroom in Entrance Lobby	Yes	W2	CMU	White	Chipping/Flaking	3	0.05	Negative	None	0	N/A	No	No	no	no	
1	1	117G	Men's Restroom in Entrance Lobby	Yes	W3	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	
1	1	117G	Men's Restroom in Entrance Lobby	Yes	W4	CMU	White	Chipping	3	0.02	Negative	None	0	N/A	No	No	no	no	
1	1	117G	Men's Restroom in Entrance Lobby	Yes	Ceiling	Plaster	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	
1	1	117G	Men's Restroom in Entrance Lobby	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	Ceramic Tiles
1	1	117H	Cafeteria Storage Closet 117H	No	W1	CMU	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	Wall is Unpainted
1	1	117H	Cafeteria Storage Closet 117H	No	W2	CMU	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	Wall is Unpainted
1	1	117H	Cafeteria Storage Closet 117H	No	W3	CMU	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	Wall is Unpainted
1	1	117H	Cafeteria Storage Closet 117H	No	W4	Concrete	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	Wall is Unpainted
1	1	117H	Cafeteria Storage Closet 117H	No	Ceiling	Plaster	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	
1	1	117H	Cafeteria Storage Closet 117H	No	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	12 x 12 Floor Tiles
1	1	117K	Cafeteria Storage Room	No	W1	CMU	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	Wall is Unpainted
1	1	117K	Cafeteria Storage Room	No	W2	CMU	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	Wall is Unpainted
1	1	117K	Cafeteria Storage Room	No	W3	CMU	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	Wall is Unpainted
1	1	117K	Cafeteria Storage Room	No	W4	CMU	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	Wall is Unpainted
1	1	117K	Cafeteria Storage Room	No	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	Ceiling is Unpainted
1	1	117K	Cafeteria Storage Room	No	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	Floor is Unpainted
1	1	117A	Auditorium	Yes	W1	CMU	Yellow	None	0	N/A	N/A	None	0	N/A	No	No	no	no	Wall 1 is Cafeteria side.
1	1	117A	Auditorium	Yes	Columns	Concrete	Yellow	Flaking	10	0	Negative	None	0	N/A	No	No	no	no	Wall 1 is Cafeteria side.
1	1	117A	Auditorium	Yes	W2	CMU	Yellow	Chipping	10	0.02	Negative	None	0	N/A	No	No	no	no	
1	1	117A	Auditorium	Yes	W2	Sheetrock	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	
1	1	117A	Auditorium	Yes	Columns	Concrete	Brown	Flaking	3	0	Negative	None	0	N/A	No	No	no	no	
1	1	117A	Auditorium	Yes	W3	Sheetrock	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	Wall 3 is Stage side
1	1	117A	Auditorium	Yes	W3	Concrete	Yellow	Chipping	6	0	Negative	None	0	N/A	No	No	no	no	Wall 3 is Stage side
1	1	117A	Auditorium	Yes	W4	CMU	Yellow	None	0	N/A	N/A	None	0	Negative	No	No	no	no	
1	1	117A	Auditorium	Yes	W4	Sheetrock	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	
1	1	117A	Auditorium	Yes	Ceiling	Concrete	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	
1	1	117A	Auditorium	Yes	Ceiling	Plaster	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	
1	1	117A	Auditorium	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	12 x 12 Floor Tiles
1	1		Stage	Yes	W1	Sheetrock	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	Wall 1 is Auditorium side.
1	1		Stage	Yes	W2	CMU	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	Wall is Unpainted
1	1		Stage	Yes	W2	Sheetrock	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	
1	1		Stage	Yes	W3	CMU	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	Wall is Unpainted
1	1		Stage	Yes	W3	Sheetrock	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	
1	1		Stage	Yes	W4	CMU	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	Wall is Unpainted
1	1		Stage	Yes	W4	Sheetrock	White	None	0	N/A	N/A	None	0	Negative	No	No	no	no	
1	1		Stage	Yes	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	Ceiling is Unpainted
1	1		Stage	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	12 x 12 Floor Tiles
1	1	117I	Auditorium Dressing Room B	Yes	W1	CMU	Green	None	0	N/A	N/A	None	0	N/A	No	No	no	no	
1	1	117I	Auditorium Dressing Room B	Yes	W2	CMU	Green	None	0	N/A	N/A	None	0	N/A	No	No	no	no	
1	1	117I	Auditorium Dressing Room B	Yes	W3	CMU	Green/White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	
1	1	117I	Auditorium Dressing Room B	Yes	W4	CMU	Green	None	0	N/A	N/A	None	0	N/A	No	No	no	no	
1	1	117I	Auditorium Dressing Room B	Yes	Ceiling	Plaster	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	
1	1	117I	Auditorium Dressing Room B	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	9 x 9 Floor Tiles Removed; Black Mastic Remains
1	1	117J	Auditorium Dressing Room A	Yes	W1	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	
1	1	117J	Auditorium Dressing Room A	Yes	W2	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	
1	1	117J	Auditorium Dressing Room A	Yes	W3	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	
1	1	117J	Auditorium Dressing Room A	Yes	W4	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	
1	1	117J	Auditorium Dressing Room A	Yes	Ceiling	Plaster	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	
1	1	117J	Auditorium Dressing Room A	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	9 x 9 Floor Tiles Removed; Black Mastic Remains
1	1	H113	Hallway outside Kitchen and Teacher's Lounge	Yes	W1	CMU	White	Chipping	12	0	Negative	None	0	N/A	No	No	no	no	Wall 1 is along Auditorium side
1	1	H113	Hallway outside Kitchen and Teacher's Lounge	Yes	W2	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	
1	1	H113	Hallway outside Kitchen and Teacher's Lounge	Yes	W3	CMU	White	Chipping	10	0	Negative	None	0	N/A	No	No	no	no	
1	1	H113	Hallway outside Kitchen and Teacher's Lounge	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	Wall 4 is open to adjacent Hallway
1	1	H113	Hallway outside Kitchen and Teacher's Lounge	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	2 x 4 Drop Ceiling
1	1	H113	Hallway outside Kitchen and Teacher's Lounge	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	12 x 12 Floor Tiles
1	1	H110A	Hallway to Stairwell D	Yes	W1	CMU	White	Chipping	2	0	Negative	None	0	N/A	No	No	no	no	Wall 1 is Cafeteria/Auditorium side
1	1	H110A	Hallway to Stairwell D	Yes	W2	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	
1	1	H110A	Hallway to Stairwell D	Yes	W3	CMU	White	Chipping	10	0	Negative	None	0	N/A	No	No	no	no	
1	1	H110A	Hallway to Stairwell D	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	Wall 4 is open to adjacent Hallway
1	1	H110A	Hallway to Stairwell D	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	2 x 4 Drop Ceiling
1	1	H110A	Hallway to Stairwell D	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	12 x 12 Floor Tiles
1	1	H112	Hallway from Teacher's Lounge 100 to Building Engineer's Office	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	Wall 1 is open to adjacent Hallway by Cafeteria
1	1	H112	Hallway from Teacher's Lounge 100 to Building Engineer's Office	Yes	W2	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	Wall 2 is along Room 100 side.

			School District of Philadelphia																			
			Name of Inspector: Paul M. Davis		Lead Safe Certification Assessment Report									Inspection Dates: June 2021								
			Inspection Company: VERTEX		Bethune ES School									ULCS# 7510								
E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes			
1	1	H112	Hallway from Teacher's Lounge 100 to Building Engineer's Office	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	Wall 3 is open to adjacent Hallway by BE Office.			
1	1	H112	Hallway from Teacher's Lounge 100 to Building Engineer's Office	Yes	W4	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no				
1	1	H112	Hallway from Teacher's Lounge 100 to Building Engineer's Office	Yes	Door	Metal	Blue	Chipping	1	0	Negative	None	0	N/A	No	No	no	no	To Courtyard			
1	1	H112	Hallway from Teacher's Lounge 100 to Building Engineer's Office	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	2 x 4 Drop Ceiling			
1	1	H112	Hallway from Teacher's Lounge 100 to Building Engineer's Office	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	12 x 12 Floor Tiles			
1	1	123	Teacher's Lounge 123 (Kitchen)	Yes	W1	CMU	White	Partially Inaccessible	0	0	Negative	None	0	N/A	No	No	no	no				
1	1	123	Teacher's Lounge 123 (Kitchen)	Yes	Door Frame	Metal	Blue	Chipping	2	0.09	Negative	None	0	N/A	No	No	no	no				
1	1	123	Teacher's Lounge 123 (Kitchen)	Yes	W2	CMU	White	Partially Inaccessible	0	0	Negative	None	0	N/A	No	No	no	no				
1	1	123	Teacher's Lounge 123 (Kitchen)	Yes	W3	CMU	White	Efflorescence	10	0	Negative	None	0	N/A	No	Unknown	no	no				
1	1	123	Teacher's Lounge 123 (Kitchen)	Yes	W4	CMU	White	Partially Inaccessible	0	0	Negative	None	0	N/A	No	No	no	no				
1	1	123	Teacher's Lounge 123 (Kitchen)	Yes	Door Frame	Metal	Blue	Chipping	2	0.03	Negative	None	0	N/A	No	No	no	no				
1	1	123	Teacher's Lounge 123 (Kitchen)	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	2 x 4 Drop Ceiling			
1	1	123	Teacher's Lounge 123 (Kitchen)	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	12 x 12 Floor Tiles			
1	1	123A	TOCFWH Office	Yes	W1	CMU	Orange	Chipping/Flaking	12	0.02	Negative	None	0	Negative	No	No	no	no				
1	1	123A	TOCFWH Office	Yes	W2	CMU	Orange	Chipping	4	0.02	Negative	None	0	N/A	No	No	no	no				
1	1	123A	TOCFWH Office	Yes	Door Frame	Metal	Blue	Chipping	2	0.05	Negative	None	0	N/A	No	No	no	no				
1	1	123A	TOCFWH Office	Yes	W3	CMU	Orange	Chipping/Efflorescence	12	0.02	Negative	None	0	N/A	No	Unknown	no	no				
1	1	123A	TOCFWH Office	Yes	W4	CMU	Orange/White	Chipping	2	0.02	Negative	None	0	N/A	No	No	no	no				
1	1	123A	TOCFWH Office	Yes	Shelves	Wood	White	Chipping/Cracking	6	0	Negative	None	0	N/A	No	No	no	no				
1	1	123A	TOCFWH Office	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	2 x 4 Drop Ceiling			
1	1	123A	TOCFWH Office	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	12 x 12 Floor Tiles			
1	2	200	Classroom 200 Technology	Yes	W1	CMU	White	None	0	N/A	N/A	None	0	Negative	No	No	no	no				
1	2	200	Classroom 200 Technology	Yes	Door Frame	Metal	Blue	Friction	2	0.08	Negative	None	0	N/A	No	No	no	no				
1	2	200	Classroom 200 Technology	Yes	W2	CMU	White	Cracking	6	0.06	Negative	None	0	N/A	No	No	no	no				
1	2	200	Classroom 200 Technology	Yes	Door Frame	Metal	Blue/White	Chipping	8	0.18	Negative	None	0	N/A	No	No	no	no				
1	2	200	Classroom 200 Technology	Yes	W3	CMU	White	Cracking	6	0.02	Negative	None	0	N/A	No	No	no	no				
1	2	200	Classroom 200 Technology	Yes	W4	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no				
1	2	200	Classroom 200 Technology	Yes	Ceiling	Plaster	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no				
1	2	200	Classroom 200 Technology	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	12 x 12 Floor Tiles			
1	2	200A	Classroom 200 Technology Closet	yes	W1	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no				
1	2	200A	Classroom 200 Technology Closet	yes	W2	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no				
1	2	200A	Classroom 200 Technology Closet	yes	W3	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no				
1	2	200A	Classroom 200 Technology Closet	yes	Door Frame	Metal	Pink	Chipping	6	0.07	Negative	None	0	N/A	No	No	no	no				
1	2	200A	Classroom 200 Technology Closet	yes	W4	CMU	White	Partially Inaccessible	N/A	0.03	Negative	None	0	N/A	No	No	no	no				
1	2	200A	Classroom 200 Technology Closet	yes	Shelving	Wood	White	Partially Inaccessible	N/A	0.03	Negative	None	0	N/A	No	No	no	no				
1	2	200A	Classroom 200 Technology Closet	yes	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	Ceiling is Unpainted			
1	2	200A	Classroom 200 Technology Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	9 x 9 Floor Tiles			
1	2	S26	Stairwell D next to Classroom 200	Yes	W1	CMU	White	Chipping	6	0.01	Negative	None	0	N/A	No	No	no	no	Wall 1 is along Fan Room side			
1	2	S26	Stairwell D next to Classroom 200	Yes	W2	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no				
1	2	S26	Stairwell D next to Classroom 200	Yes	W3	CMU	White	Chipping	4	0	Negative	None	0	N/A	No	No	no	no				
1	2	S26	Stairwell D next to Classroom 200	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	Wall 4 is open to adjacent hallway			
1	2	S26	Stairwell D next to Classroom 200	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	2 x 4 Drop Ceiling			
1	2	S26	Stairwell D next to Classroom 200	Yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	Steps are Unpainted			
1	2	200B	Fan Room adjacent to Classroom 200	No	W1	CMU	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	Wall 1 is from Hallway. Wall is Unpainted			
1	2	200B	Fan Room adjacent to Classroom 200	No	Door Frame	Metal	Olive	Chipping	4	0.05	Negative	None	0	N/A	No	No	no	no				
1	2	200B	Fan Room adjacent to Classroom 200	No	W2	CMU	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	Wall is Unpainted			
1	2	200B	Fan Room adjacent to Classroom 200	No	W3	CMU	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	Wall is Unpainted			
1	2	200B	Fan Room adjacent to Classroom 200	No	W4	CMU	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	Wall is Unpainted			
1	2	200B	Fan Room adjacent to Classroom 200	No	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	Ceiling is Unpainted			
1	2	200B	Fan Room adjacent to Classroom 200	No	Fan Units	Metal	Olive	Scrapes	25	0.01	Negative	None	0	N/A	No	No	no	no				
1	2	200B	Fan Room adjacent to Classroom 200	No	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	Floor is Unpainted			
1	2	H220	Hallway adjacent to Classroom 200	Yes	W1	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	Wall 1 is Fan Room side			
1	2	H220	Hallway adjacent to Classroom 200	Yes	W2	CMU	White	Chipping	2	0.01	Negative	None	0	N/A	No	No	no	no	Wall 2 is along Classroom 200 side			
1	2	H220	Hallway adjacent to Classroom 200	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	Wall 3 is open to adjacent Hallway			
1	2	H220	Hallway adjacent to Classroom 200	Yes	W4	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no				
1	2	H220	Hallway adjacent to Classroom 200	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	2 x 4 Drop Ceiling			
1	2	H220	Hallway adjacent to Classroom 200	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	12 x 12 Floor Tiles			
1	2	201	Classroom 201	Yes	W1	CMU	White	Chipping	8	0	Negative	None	0	Negative	No	No	no	no	Wall 1 is along both hallway sides			
1	2	201	Classroom 201	Yes	W2	CMU	White	Chipping	4	0	Negative	None	0	N/A	No	No	no	no				
1	2	201	Classroom 201	Yes	W3	CMU	White	Efflorescence	2	0	Negative	None	0	N/A	No	Unknown	no	no				
1	2	201	Classroom 201	Yes	W4	CMU	White	Chipping	4	0	Negative	None	0	N/A	No	No	no	no				
1	2	201	Classroom 201	Yes	Ceiling	Plaster	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no				
1	2	201	Classroom 201	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	12 x 12 Floor Tiles			
1	2	201A	Storage adjacent to Classroom 201	Yes	W1	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no				
1	2	201A	Storage adjacent to Classroom 201	Yes	Door Frame	Metal	White	Chipping	5	0.1	Negative	None	0	N/A	No	No	no	no				

Element Floor			School District of Philadelphia		Lead Safe Certification Assessment Report							Inspection Dates: June 2021								
			Name of Inspector: Paul M. Davis																	
			Inspection Company: VERTEX		Bethune ES School							ULCS# 7510								
		Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes	
1	2	201A	Storage adjacent to Classroom 201	Yes	W2	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no		
1	2	201A	Storage adjacent to Classroom 201	Yes	W3	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no		
1	2	201A	Storage adjacent to Classroom 201	Yes	W4	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no		
1	2	201A	Storage adjacent to Classroom 201	Yes	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	Ceiling is Unpainted	
1	2	201A	Storage adjacent to Classroom 201	Yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	Floor is Unpainted	
1	2	201C	Girl's Restroom across from Classroom 201	Yes	W1	CMU	White	Chipping	2	0	Negative	None	0	N/A	No	No	no	no		
1	2	201C	Girl's Restroom across from Classroom 201	Yes	Door Frame	Metal	Blue	Chipping	3	0.14	Negative	None	0	N/A	No	No	no	no		
1	2	201C	Girl's Restroom across from Classroom 201	Yes	W2	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no		
1	2	201C	Girl's Restroom across from Classroom 201	Yes	W3	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no		
1	2	201C	Girl's Restroom across from Classroom 201	Yes	W4	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no		
1	2	201C	Girl's Restroom across from Classroom 201	Yes	Ceiling	Plaster	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no		
1	2	201C	Girl's Restroom across from Classroom 201	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	Ceramic Tiles	
1	2	H215	Hallway adjacent to Classroom 201	Yes	W1	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	Wall 1 is along Classroom 201 side	
1	2	H215	Hallway adjacent to Classroom 201	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	Wall 2 is open to adjacent Hallway	
1	2	H215	Hallway adjacent to Classroom 201	Yes	W3	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	Wall 3 is along Girl's Restroom side	
1	2	H215	Hallway adjacent to Classroom 201	Yes	Electrical Panels	Metal	White	Chipping	2	0	Negative	None	0	N/A	No	No	no	no		
1	2	H215	Hallway adjacent to Classroom 201	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	Wall 4 is open to adjacent Hallway	
1	2	H215	Hallway adjacent to Classroom 201	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	2 x 4 Drop Ceiling	
1	2	H215	Hallway adjacent to Classroom 201	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	12 x 12 Floor Tiles	
1	2	202	Classroom 202	Yes	W1	CMU	White	Chipping	2	0.02	Negative	None	0	Negative	No	No	no	no		
1	2	202	Classroom 202	Yes	W2	CMU	White	Chipping/Flaking	2	0.04	Negative	None	0	N/A	No	No	no	no		
1	2	202	Classroom 202	Yes	W3	CMU	White	Chipping	1	0.02	Negative	None	0	N/A	No	No	no	no		
1	2	202	Classroom 202	Yes	W4	CMU	White	Chipping	15	0	Negative	None	0	N/A	No	No	no	no		
1	2	202	Classroom 202	Yes	Ceiling	Plaster	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no		
1	2	202	Classroom 202	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	12 x 12 Floor Tiles	
1	2	203	Classroom 203	Yes	W1	CMU	White	Chipping	12	0	Negative	None	0	N/A	No	No	no	no		
1	2	203	Classroom 203	Yes	W2	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no		
1	2	203	Classroom 203	Yes	W3	CMU	White	Chipping/Flaking	1	0	Negative	None	0	N/A	No	No	no	no		
1	2	203	Classroom 203	Yes	W4	CMU	White	Partially Inaccessible	N/A	0.11	Negative	None	0	N/A	No	No	no	no		
1	2	203	Classroom 203	Yes	Door Frame	Metal	Blue	Chipping	2	0.22	Negative	None	0	N/A	No	No	no	no		
1	2	203	Classroom 203	Yes	Ceiling	Plaster	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no		
1	2	203	Classroom 203	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	12 x 12 Floor Tiles	
1	2	H216	Hallway between Classrooms 201 to 205	Yes	W1	CMU	White	None	0	N/A	N/A	None	0	Negative	No	No	no	no	Wall 1 is along Classroom 201 side	
1	2	H216	Hallway between Classrooms 201 to 205	Yes	W2	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no		
1	2	H216	Hallway between Classrooms 201 to 205	Yes	W3	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no		
1	2	H216	Hallway between Classrooms 201 to 205	Yes	W4	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no		
1	2	H216	Hallway between Classrooms 201 to 205	Yes	Ceiling	Plaster	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no		
1	2	H216	Hallway between Classrooms 201 to 205	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	12 x 12 Floor Tiles	
1	2	204	Classroom 204	Yes	W1	CMU	White	Partially Inaccessible	N/A	0	Negative	None	0	N/A	No	No	no	no		
1	2	204	Classroom 204	Yes	W2	CMU	White	Chipping/Flaking	8	0	Negative	None	0	N/A	No	No	no	no		
1	2	204	Classroom 204	Yes	W3	CMU	White	Chipping/Flaking	12	0	Negative	None	0	N/A	No	No	no	no		
1	2	204	Classroom 204	Yes	W4	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no		
1	2	204	Classroom 204	Yes	Ceiling	Plaster	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no		
1	2	204	Classroom 204	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	12 x 12 Floor Tiles	
1	2	205	Classroom 205	Yes	W1	CMU	White	Chipping	4	0.07	Negative	None	0	N/A	No	No	no	no	Wall 1: comprising both walls with entrance doors from hallways	
1	2	205	Classroom 205	Yes	W2	CMU	White	Chipping	2	0	Negative	None	0	Negative	No	No	no	no		
1	2	205	Classroom 205	Yes	W3	CMU	White	Chipping/Flaking/Efflor escence	15	0.02	Negative	None	0	Negative	No	Unknown	no	no		
1	2	205	Classroom 205	Yes	W4	CMU	White	Chipping/Flaking	8	0.01	Negative	None	0	N/A	No	No	no	no		
1	2	205	Classroom 205	Yes	Ceiling	Plaster	White	None	0	N/A	N/A	None	0	Negative	No	No	no	no		
1	2	205	Classroom 205	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	12 x 12 Floor Tiles	
1	2	205B	Boy's Restroom across from Classroom 205	Yes	W1	CMU	White	Chipping	2	0.09	Negative	None	0	Negative	No	No	no	no		
1	2	205B	Boy's Restroom across from Classroom 205	Yes	Door Frame	Metal	Blue	Chipping	4	0	Negative	None	0	N/A	No	No	no	no		
1	2	205B	Boy's Restroom across from Classroom 205	Yes	W2	CMU	White	Chipping/Flaking	1	0.06	Negative	None	0	N/A	No	No	no	no		
1	2	205B	Boy's Restroom across from Classroom 205	Yes	Radiator Cover	Metal	White	Chipping/Flaking	1	0.02	Negative	None	0	N/A	No	No	no	no		
1	2	205B	Boy's Restroom across from Classroom 205	Yes	W3	CMU	White	Chipping	1	0.08	Negative	None	0	N/A	No	No	no	no		
1	2	205B	Boy's Restroom across from Classroom 205	Yes	W4	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no		
1	2	205B	Boy's Restroom across from Classroom 205	Yes	Ceiling	Plaster	White	Flaking	6	0	Negative	None	0	N/A	No	No	no	no	About 10 SF of Plaster Damage (missing skim coat)	
1	2	205B	Boy's Restroom across from Classroom 205	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	Ceramic Tiles	
1	2	S24	Stairwell A next to Classroom 205	Yes	W1	CMU	White	None	0	N/A	N/A	None	0	Negative	No	No	no	no	Wall 1 is on the Hallway side	
1	2	S24	Stairwell A next to Classroom 205	Yes	W2	CMU	White	Chipping	2	0.02	Negative	None	0	N/A	No	No	no	no		
1	2	S24	Stairwell A next to Classroom 205	Yes	W3	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no		
1	2	S24	Stairwell A next to Classroom 205	Yes	W4	CMU	White	Chipping	4	0.03	Negative	None	0	N/A	No	No	no	no		
1	2	S24	Stairwell A next to Classroom 205	Yes	Ceiling	Concrete	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no		
1	2	S24	Stairwell A next to Classroom 205	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	12 x 12 Floor Tiles or Unpainted Concrete	
1	2		Staff Restroom between Stairwell A and Classroom 205	yes	W1	CMU	Pink	None	0	N/A	N/A	None	0	N/A	No	No	no	no		

			School District of Philadelphia																
			Name of Inspector: Paul M. Davis		Lead Safe Certification Assessment Report									Inspection Dates: June 2021					
			Inspection Company: VERTEX		Bethune ES School									ULCS# 7510					
E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes
1	2		Staff Restroom between Stairwell A and Classroom 205	yes	W2	CMU	Pink	None	0	N/A	N/A	None	0	N/A	No	No	no	no	
1	2		Staff Restroom between Stairwell A and Classroom 205	yes	W3	CMU	Pink	None	0	N/A	N/A	None	0	N/A	No	No	no	no	
1	2		Staff Restroom between Stairwell A and Classroom 205	yes	W4	CMU	Pink	None	0	N/A	N/A	None	0	N/A	No	No	no	no	
1	2		Staff Restroom between Stairwell A and Classroom 205	yes	Ceiling	Plaster	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	
1	2		Staff Restroom between Stairwell A and Classroom 205	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	Ceramic Tiles
1	2	219	Room 219 City Year Office	Yes	W1	CMU	Blue	Cracking	4	0.09	Negative	None	0	N/A	No	No	no	no	
1	2	219	Room 219 City Year Office	Yes	W2	Concrete	Blue	Chipping/Flaking	15	0.01	Negative	None	0	Negative	No	No	no	no	
1	2	219	Room 219 City Year Office	Yes	W3	CMU	Blue	None	0	N/A	N/A	None	0	Negative	No	No	no	no	
1	2	219	Room 219 City Year Office	Yes	W4	CMU	Blue	None	0	N/A	N/A	None	0	N/A	No	No	no	no	
1	2	219	Room 219 City Year Office	Yes	Ceiling	Plaster	White	Efflorescence	20	0	Negative	None	0	N/A	No	Unknown	yes	no	
1	2	219	Room 219 City Year Office	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	12 x 12 & 9 x 9 Floor Tiles
1	2	219A	City Year Office 219 Storage Room	yes	W1	CMU	Yellow	None	0	N/A	N/A	None	0	N/A	No	No	no	no	
1	2	219A	City Year Office 219 Storage Room	yes	Door Frame	Metal	Yellow	Chipping	2	0.26	Negative	None	0	N/A	No	No	no	no	
1	2	219A	City Year Office 219 Storage Room	yes	W2	CMU	Yellow	Cracking	6	0	Negative	None	0	N/A	No	No	no	no	
1	2	219A	City Year Office 219 Storage Room	yes	W3	Concrete	Yellow	Cracking	8	0	Negative	None	0	N/A	No	No	no	no	
1	2	219A	City Year Office 219 Storage Room	yes	W4	CMU	Yellow	Partially Inaccessible	N/A	0.01	Negative	None	0	N/A	No	No	no	no	
1	2	219A	City Year Office 219 Storage Room	yes	Ceiling	Plaster	White	Water Damage	4	0	Negative	None	0	N/A	No	No	no	no	
1	2	219A	City Year Office 219 Storage Room	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	9 x 9 Floor Tiles
1	2	206A	Team Planning next to Classroom 206	Yes	W1	No Access	No Access	No Access	No Access	No Access	No Access	None	0	N/A	No	No	no	no	
1	2	206A	Team Planning next to Classroom 206	Yes	W2	No Access	No Access	No Access	No Access	No Access	No Access	None	0	N/A	No	No	no	no	
1	2	206A	Team Planning next to Classroom 206	Yes	W3	No Access	No Access	No Access	No Access	No Access	No Access	None	0	N/A	No	No	no	no	
1	2	206A	Team Planning next to Classroom 206	Yes	W4	No Access	No Access	No Access	No Access	No Access	No Access	None	0	N/A	No	No	no	no	
1	2	206A	Team Planning next to Classroom 206	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	None	0	N/A	No	No	no	no	
1	2	206A	Team Planning next to Classroom 206	Yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access	None	0	N/A	No	No	no	no	
1	2	206	Classroom 206	Yes	W1	CMU	Blue	None	0	N/A	N/A	None	0	N/A	No	No	no	no	
1	2	206	Classroom 206	Yes	W2	CMU	Blue	None	0	N/A	N/A	None	0	N/A	No	No	no	no	
1	2	206	Classroom 206	Yes	W3	CMU	Blue	None	0	N/A	N/A	None	0	N/A	No	No	no	no	
1	2	206	Classroom 206	Yes	W4	CMU	Blue	None	0	N/A	N/A	None	0	N/A	No	No	no	no	
1	2	206	Classroom 206	Yes	Ceiling	Plaster	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	
1	2	206	Classroom 206	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	12 x 12 Floor Tiles
1	2	207	Classroom 207	Yes	W1	CMU	White	Chipping	1	0.03	Negative	None	0	N/A	No	No	no	no	
1	2	207	Classroom 207	Yes	Door Frame	Metal	Blue	Chipping	8	0.22	Negative	None	0	N/A	No	No	no	no	
1	2	207	Classroom 207	Yes	W2	CMU	White	Chipping	2	0	Negative	None	0	N/A	No	No	no	no	
1	2	207	Classroom 207	Yes	W3	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	
1	2	207	Classroom 207	Yes	Column	Concrete	White	Chipping	8	0	Negative	None	0	N/A	No	No	no	no	
1	2	207	Classroom 207	Yes	W4	CMU	White	Cracking/Chipping	6	0	Negative	None	0	N/A	No	No	no	no	
1	2	207	Classroom 207	Yes	Ceiling	Plaster	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	
1	2	207	Classroom 207	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	12 x 12 Floor Tiles
1	2	207A	Storage Room across from Classrooms 206 and 207	yes	W1	CMU	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	Wall is Unpainted
1	2	207A	Storage Room across from Classrooms 206 and 207	yes	W1	Plaster	White	Efflorescence	25	0	Negative	None	0	N/A	No	Unknown	yes	no	
1	2	207A	Storage Room across from Classrooms 206 and 207	yes	Door Frame	Metal	Pink	Chipping	2	0.04	Negative	None	0	N/A	No	No	no	no	
1	2	207A	Storage Room across from Classrooms 206 and 207	yes	W2	CMU	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	Wall is Unpainted
1	2	207A	Storage Room across from Classrooms 206 and 207	yes	W3	CMU	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	Wall is Unpainted
1	2	207A	Storage Room across from Classrooms 206 and 207	yes	W4	CMU	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	Wall is Unpainted
1	2	207A	Storage Room across from Classrooms 206 and 207	yes	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	Ceiling is Unpainted
1	2	207A	Storage Room across from Classrooms 206 and 207	yes	Ceiling	Plaster	White	Efflorescence	4	0	Negative	None	0	N/A	No	No	no	no	
1	2	207A	Storage Room across from Classrooms 206 and 207	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	Floor is Unpainted
1	2	H217	Hallway from Classrooms 205 to 207	Yes	W1	CMU	White	Chipping	8	0.02	Negative	None	0	N/A	No	No	no	no	Wall 1 is along Classroom 219 side
1	2	H217	Hallway from Classrooms 205 to 207	Yes	Radiator Cover	Metal	White	Scuffs	3	0.5	Negative	None	0	N/A	No	No	no	no	
1	2	H217	Hallway from Classrooms 205 to 207	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	Wall 2 is open to adjacent Hallway
1	2	H217	Hallway from Classrooms 205 to 207	Yes	W3	CMU	White	Chipping	8	0.01	Negative	None	0	N/A	No	No	no	no	
1	2	H217	Hallway from Classrooms 205 to 207	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	Wall 4 is open to adjacent Hallway by Classroom 208
1	2	H217	Hallway from Classrooms 205 to 207	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	2 x 4 Drop Ceiling
1	2	H217	Hallway from Classrooms 205 to 207	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	12 x 12 Floor Tiles
1	2	208	Classroom 208	Yes	W1	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	
1	2	208	Classroom 208	Yes	Door Frame	Metal	Blue	Chipping	12	0.02	Negative	None	0	N/A	No	No	no	no	
1	2	208	Classroom 208	Yes	W2	CMU	White	Cracking/Chipping	10	0	Negative	None	0	N/A	No	No	no	no	
1	2	208	Classroom 208	Yes	W3	CMU	White	Cracking/Chipping	8	0	Negative	None	0	N/A	No	No	no	no	
1	2	208	Classroom 208	Yes	W4	CMU	White	Chipping	1	0	Negative	None	0	N/A	No	No	no	no	
1	2	208	Classroom 208	Yes	Ceiling	Plaster	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	
1	2	208	Classroom 208	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	12 x 12 Floor Tiles
1	2	208	Classroom 209	Yes	W1	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	
1	2	208	Classroom 209	Yes	Door Frame	Metal	Blue	Chipping	8	0.13	Negative	None	0	N/A	No	No	no	no	
1	2	208	Classroom 209	Yes	W2	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	

			School District of Philadelphia																					
			Name of Inspector: Paul M. Davis		Lead Safe Certification Assessment Report										Inspection Dates: June 2021									
			Inspection Company: VERTEX		Bethune ES School										ULCS# 7510									
E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes					
1	2	208	Classroom 209	Yes	W3	CMU	White	Chipping	6	0	Negative	None	0	N/A	No	No	no	no						
1	2	208	Classroom 209	Yes	W4	CMU	White	Chipping	6	0	Negative	None	0	N/A	No	No	no	no						
1	2	208	Classroom 209	Yes	Ceiling	Plaster	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no						
1	2	208	Classroom 209	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	12 x 12 Floor Tiles					
1	2	209A	Storage Room Adjacent to Elevator	yes	W1	CMU	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	Wall is Unpainted					
1	2	209A	Storage Room Adjacent to Elevator	yes	Door Frame	Metal	Pink	Chipping	6	0.09	Negative	None	0	N/A	No	No	no	no						
1	2	209A	Storage Room Adjacent to Elevator	yes	W2	CMU	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	Wall is Unpainted					
1	2	209A	Storage Room Adjacent to Elevator	yes	W3	CMU	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	Wall is Unpainted					
1	2	209A	Storage Room Adjacent to Elevator	yes	Radiator Cover	Metal	Green	Pitting	2	0	Negative	None	0	N/A	No	No	no	no						
1	2	209A	Storage Room Adjacent to Elevator	yes	W4	CMU	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	Wall is Unpainted					
1	2	209A	Storage Room Adjacent to Elevator	yes	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	Ceiling is Unpainted					
1	2	209A	Storage Room Adjacent to Elevator	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	Floor is Unpainted					
1	2	209A	Classroom 220	yes	W1	CMU	White	Chipping	1	0	Negative	None	0	N/A	No	No	no	no	Wall 1 is along Hallway by Elevator side					
1	2	209A	Classroom 220	yes	Pipes	Metal	White	Chipping/Flaking	8	0.22	Negative	None	0	N/A	No	No	no	no						
1	2	209A	Classroom 220	yes	Door Frame	Metal	Blue	Chipping	8	0.13	Negative	None	0	N/A	No	No	no	no						
1	2	209A	Classroom 220	yes	W2	Sheetrock	White	Chipping	12	0	Negative	None	0	N/A	No	No	no	no						
1	2	209A	Classroom 220	yes	W3	CMU	White	Chipping	6	0	Negative	None	0	N/A	No	No	no	no						
1	2	209A	Classroom 220	yes	W4	CMU	White	Chipping/Flaking	2	0	Negative	None	0	N/A	No	No	no	no						
1	2	209A	Classroom 220	yes	Ceiling	Plaster	White	Efflorescence	8	0	Negative	None	0	N/A	No	Unknown	yes	no						
1	2	209A	Classroom 220	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	18 x 18 Floor Tiles					
1	2	220A	Classroom 220 Storage Room	yes	W1	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no						
1	2	220A	Classroom 220 Storage Room	yes	Door Frame	Metal	Blue	Chipping	2	0.07	Negative	None	0	N/A	No	No	no	no						
1	2	220A	Classroom 220 Storage Room	yes	W2	Concrete	White	Partially Inaccessible	N/A	0	Negative	None	0	N/A	No	No	no	no						
1	2	220A	Classroom 220 Storage Room	yes	W3	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no						
1	2	220A	Classroom 220 Storage Room	yes	Radiator Cover	Metal	Blue	Pitting	2	0	Negative	None	0	N/A	No	No	no	no						
1	2	220A	Classroom 220 Storage Room	yes	W4	CMU	White	Partially Inaccessible	N/A	0	Negative	None	0	N/A	No	No	no	no						
1	2	220A	Classroom 220 Storage Room	yes	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	Ceiling is Unpainted					
1	2	220A	Classroom 220 Storage Room	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	18 x 18 Floor Tiles					
1	2	220B	Classroom 220 Storage Closet at Entrance	yes	W1	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no						
1	2	220B	Classroom 220 Storage Closet at Entrance	yes	W2	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no						
1	2	220B	Classroom 220 Storage Closet at Entrance	yes	Duct Work	Metal	White	Flaking	5	0.05	Negative	None	0	N/A	No	No	no	no						
1	2	220B	Classroom 220 Storage Closet at Entrance	yes	W3	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no						
1	2	220B	Classroom 220 Storage Closet at Entrance	yes	W4	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no						
1	2	220B	Classroom 220 Storage Closet at Entrance	yes	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	Ceiling is Unpainted					
1	2	220B	Classroom 220 Storage Closet at Entrance	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	18 x 18 Floor Tiles					
1	2	220C	Classroom 220 Storage Closet in Corner	yes	W1	No Access	No Access	No Access	No Access	No Access	No Access	None	0	N/A	No	No	no	no						
1	2	220C	Classroom 220 Storage Closet in Corner	yes	W2	No Access	No Access	No Access	No Access	No Access	No Access	None	0	N/A	No	No	no	no						
1	2	220C	Classroom 220 Storage Closet in Corner	yes	W3	No Access	No Access	No Access	No Access	No Access	No Access	None	0	N/A	No	No	no	no						
1	2	220C	Classroom 220 Storage Closet in Corner	yes	W4	No Access	No Access	No Access	No Access	No Access	No Access	None	0	N/A	No	No	no	no						
1	2	220C	Classroom 220 Storage Closet in Corner	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	None	0	N/A	No	No	no	no						
1	2	220C	Classroom 220 Storage Closet in Corner	yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access	None	0	N/A	No	No	no	no						
1	2	S23	Stairwell B next to Classroom 210	Yes	W1	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	Wall 1 is Hallway side					
1	2	S23	Stairwell B next to Classroom 210	Yes	W2	CMU	White	Chipping	2	0.03	Negative	None	0	N/A	No	No	no	no						
1	2	S23	Stairwell B next to Classroom 210	Yes	W3	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no						
1	2	S23	Stairwell B next to Classroom 210	Yes	W4	CMU	White	Chipping	2	0.01	Negative	None	0	N/A	No	No	no	no						
1	2	S23	Stairwell B next to Classroom 210	Yes	Ceiling	Concrete	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no						
1	2	S23	Stairwell B next to Classroom 210	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	12 x 12 Floor Tiles or Unpainted Concrete					
1	2		Staff Restroom between Stairwell B and Classroom 210	yes	W1	CMU	Blue	None	0	N/A	N/A	None	0	N/A	No	No	no	no						
1	2		Staff Restroom between Stairwell B and Classroom 210	yes	W2	CMU	Blue	None	0	N/A	N/A	None	0	N/A	No	No	no	no						
1	2		Staff Restroom between Stairwell B and Classroom 210	yes	W3	CMU	Blue	None	0	N/A	N/A	None	0	N/A	No	No	no	no						
1	2		Staff Restroom between Stairwell B and Classroom 210	yes	W4	CMU	Blue	Chipping/Flaking	2	0.01	Negative	None	0	N/A	No	No	no	no						
1	2		Staff Restroom between Stairwell B and Classroom 210	yes	Ceiling	Plaster	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no						
1	2		Staff Restroom between Stairwell B and Classroom 210	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	Ceramic Tiles					
1	2	210B	Boy's Restroom across from Classroom 210	Yes	W1	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no						
1	2	210B	Boy's Restroom across from Classroom 210	Yes	Door Frame	Metal	Blue	Chipping	4	0.16	Negative	None	0	N/A	No	No	no	no						
1	2	210B	Boy's Restroom across from Classroom 210	Yes	W2	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no						
1	2	210B	Boy's Restroom across from Classroom 210	Yes	W3	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no						
1	2	210B	Boy's Restroom across from Classroom 210	Yes	W4	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no						
1	2	210B	Boy's Restroom across from Classroom 210	Yes	Ceiling	Plaster	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no						
1	2	210B	Boy's Restroom across from Classroom 210	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	Ceramic Tiles					
1	2	H218	Hallway from Classrooms 208 to 210	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	Wall 1 is open to adjacent Hallway past Boy's Restroom					
1	2	H218	Hallway from Classrooms 208 to 210	Yes	W2	CMU	White	Chipping	4	0.02	Negative	None	0	N/A	No	No	no	no	Wall 2 is along Classroom 220 side					
1	2	H218	Hallway from Classrooms 208 to 210	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	Wall 3 is open to adjacent Hallway by Classroom 207					

Element Floor Space #			School District of Philadelphia		Lead Safe Certification Assessment Report							Inspection Dates: June 2021								
			Name of Inspector: Paul M. Davis																	
			Inspection Company: VERTEX		Bethune ES School							ULCS# 7510								
			On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes	
1	2	H218	Hallway from Classrooms 208 to 210	Yes	W4	CMU	White	Chipping	4	0.01	Negative	None	0	N/A	No	No	no	no		
1	2	H218	Hallway from Classrooms 208 to 210	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	2 x 4 Drop Ceiling	
1	2	H218	Hallway from Classrooms 208 to 210	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	N/A	No	No	no	12 x 12 Floor Tiles	
1	2	210	Classroom 210	Yes	W1	CMU	White	Chipping	3	0.09	Negative	None	0	N/A	No	No	no	no	Wall 1 is walls with both doors	
1	2	210	Classroom 210	Yes	Door Frame	Metal	Blue	Chipping	8	0.12	Negative	None	0	N/A	No	No	no	no	Includes two doors	
1	2	210	Classroom 210	Yes	W2	CMU	White	Chipping	3	0	Negative	None	0	N/A	No	No	no	no		
1	2	210	Classroom 210	Yes	W3	CMU	White	Chipping	4	0.04	Negative	None	0	N/A	No	No	no	no		
1	2	210	Classroom 210	Yes	W4	CMU	White	Partially Inaccessible	N/A	0	Negative	None	0	N/A	No	No	no	no		
1	2	210	Classroom 210	Yes	Ceiling	Plaster	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no		
1	2	210	Classroom 210	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	12 x 12 Floor Tiles	
1	2	211	Classroom 211	Yes	W1	CMU	White	Chipping	4	0.13	Negative	None	0	N/A	No	No	no	no		
1	2	211	Classroom 211	Yes	W2	CMU	White	Cracking/Chipping	20	0.02	Negative	None	0	N/A	No	No	no	no		
1	2	211	Classroom 211	Yes	W3	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no		
1	2	211	Classroom 211	Yes	W4	CMU	White	Chipping	3	0.04	Negative	None	0	N/A	No	No	no	no		
1	2	211	Classroom 211	Yes	Ceiling	Plaster	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no		
1	2	211	Classroom 211	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	N/A	No	No	no	12 x 12 Floor Tiles	
1	2	212	Classroom 212	Yes	W1	CMU	Blue	None	0	N/A	N/A	None	0	N/A	No	No	no	no		
1	2	212	Classroom 212	Yes	W2	CMU	Blue	None	0	N/A	N/A	None	0	N/A	No	No	no	no		
1	2	212	Classroom 212	Yes	W3	CMU	Blue	None	0	N/A	N/A	None	0	N/A	No	No	no	no		
1	2	212	Classroom 212	Yes	W4	CMU	Blue	None	0	N/A	N/A	None	0	N/A	No	No	no	no		
1	2	212	Classroom 212	Yes	Ceiling	Plaster	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no		
1	2	212	Classroom 212	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	N/A	No	No	no	12 x 12 Floor Tiles	
1	2	H220	Hallway between Classrooms 210 to 214	Yes	W1	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	Wall 1 is along Classrooms 213 & 214 side	
1	2	H220	Hallway between Classrooms 210 to 214	Yes	W2	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no		
1	2	H220	Hallway between Classrooms 210 to 214	Yes	W3	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no		
1	2	H220	Hallway between Classrooms 210 to 214	Yes	W4	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no		
1	2	H220	Hallway between Classrooms 210 to 214	Yes	Ceiling	Plaster	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no		
1	2	H220	Hallway between Classrooms 210 to 214	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	12 x 12 Floor Tiles	
1	2	213	Classroom 213	Yes	W1	CMU	White	Chipping	4	0	Negative	None	0	N/A	No	No	no	no		
1	2	213	Classroom 213	Yes	Door Frame	Metal	Blue	Chipping	3	0.09	Negative	None	0	N/A	No	No	no	no		
1	2	213	Classroom 213	Yes	W2	CMU	White	Chipping	20	0	Negative	None	0	N/A	No	No	no	no		
1	2	213	Classroom 213	Yes	W3	CMU	White	Chipping	4	0	Negative	None	0	N/A	No	No	no	no		
1	2	213	Classroom 213	Yes	W4	CMU	White	Chipping	1	0	Negative	None	0	N/A	No	No	no	no		
1	2	213	Classroom 213	Yes	Ceiling	Plaster	White	Chipping	1	0	Negative	None	0	N/A	No	No	no	no		
1	2	213	Classroom 213	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	12 x 12 Floor Tiles	
1	2	214	Classroom 214	Yes	W1	CMU	White	Chipping	8	0	Negative	None	0	N/A	No	No	no	no		
1	2	214	Classroom 214	Yes	W2	CMU	White	Chipping	10	0	Negative	None	0	N/A	No	No	no	no		
1	2	214	Classroom 214	Yes	W3	CMU	White	Chipping	4	0	Negative	None	0	N/A	No	No	no	no		
1	2	214	Classroom 214	Yes	W4	CMU	White	Chipping	4	0	Negative	None	0	N/A	No	No	no	no		
1	2	214	Classroom 214	Yes	Ceiling	Plaster	White	Chipping	1	0	Negative	None	0	N/A	No	No	no	no		
1	2	214	Classroom 214	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	N/A	No	No	no	12 x 12 Floor Tiles	
1	2	H219	Hallway adjacent to Classroom 214	Yes	W1	CMU	White	Chipping	10	0	Negative	None	0	N/A	No	No	no	no	Wall 1 is along Classroom 214 side	
1	2	H219	Hallway adjacent to Classroom 214	Yes	W2	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no		
1	2	H219	Hallway adjacent to Classroom 214	Yes	W3	CMU	White	Chipping	6	0.01	Negative	None	0	N/A	No	No	no	no		
1	2	H219	Hallway adjacent to Classroom 214	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	Wall 4 is open to adjacent Hallway	
1	2	H219	Hallway adjacent to Classroom 214	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	2 x 4 Drop Ceiling	
1	2	H219	Hallway adjacent to Classroom 214	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	12 x 12 Floor Tiles	
1	2	214A	Office adjacent to Classroom 214	Yes	W1	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no		
1	2	214A	Office adjacent to Classroom 214	Yes	Door Frame	Metal	White	Chipping	6	0.13	Negative	None	0	N/A	No	No	no	no		
1	2	214A	Office adjacent to Classroom 214	Yes	W2	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no		
1	2	214A	Office adjacent to Classroom 214	Yes	W3	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no		
1	2	214A	Office adjacent to Classroom 214	Yes	W4	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no		
1	2	214A	Office adjacent to Classroom 214	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	2 x 4 Drop Ceiling	
1	2	214A	Office adjacent to Classroom 214	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	9 x 9 Floor Tiles	
1	2	214B	Girl's Restroom across from Classroom 214	Yes	W1	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no		
1	2	214B	Girl's Restroom across from Classroom 214	Yes	Door Frame	Metal	Blue	Chipping/Scratches	8	0.14	Negative	None	0	N/A	No	No	no	no		
1	2	214B	Girl's Restroom across from Classroom 214	Yes	W2	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no		
1	2	214B	Girl's Restroom across from Classroom 214	Yes	W3	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no		
1	2	214B	Girl's Restroom across from Classroom 214	Yes	W4	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no		
1	2	214B	Girl's Restroom across from Classroom 214	Yes	Ceiling	Plaster	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no		
1	2	214B	Girl's Restroom across from Classroom 214	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	Ceramic Tiles	
1	2	215	Classroom 215	Yes	W1	CMU	Purple	None	0	N/A	N/A	None	0	N/A	No	No	no	no		
1	2	215	Classroom 215	Yes	W2	CMU	Purple	None	0	N/A	N/A	None	0	N/A	No	No	no	no		
1	2	215	Classroom 215	Yes	W3	CMU	Purple	None	0	N/A	N/A	None	0	N/A	No	No	no	no		
1	2	215	Classroom 215	Yes	W4	CMU	Purple	Chipping/Flaking	1	0.03	Negative	None	0	N/A	No	No	no	no		
1	2	215	Classroom 215	Yes	Door	Wood	Blue	Chipping	1	0.07	Negative	None	0	N/A	No	No	no	no		
1	2	215	Classroom 215	Yes	Ceiling	Plaster	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no		
1	2	215	Classroom 215	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	12 x 12 Floor Tiles	
1	2	215B	Classroom 215 Closet	yes	W1	No Access	No Access	No Access	No Access	No Access	No Access	None	0	N/A	No	No	no	no		

Element Floor Space #			School District of Philadelphia									Inspection Dates: June 2021															
			Name of Inspector: Paul M. Davis		Lead Safe Certification Assessment Report																						
			Inspection Company: VERTEX		Bethune ES School															ULCS# 7510							
On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component			Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes									
1	2	215B	Classroom 215 Closet	yes	W2	No Access	No Access	No Access	No Access	No Access	No Access	None	0	N/A	No	No	no										
1	2	215B	Classroom 215 Closet	yes	W3	No Access	No Access	No Access	No Access	No Access	No Access	None	0	N/A	No	No	no										
1	2	215B	Classroom 215 Closet	yes	W4	No Access	No Access	No Access	No Access	No Access	No Access	None	0	N/A	No	No	no										
1	2	215B	Classroom 215 Closet	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	None	0	N/A	No	No	no										
1	2	215B	Classroom 215 Closet	yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access	None	0	N/A	No	No	no										
1	2	221	Room 221 Diagnostic Center	Yes	W1	CMU	White	Chipping	4	0.01	Negative	None	0	N/A	No	No	no										
1	2	221	Room 221 Diagnostic Center	Yes	W2	CMU	White	Chipping	2	0.03	Negative	None	0	N/A	No	No	no										
1	2	221	Room 221 Diagnostic Center	Yes	W3	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no										
1	2	221	Room 221 Diagnostic Center	Yes	W4	CMU	White	Cracking/Chipping	8	0.03	Negative	None	0	N/A	No	No	no										
1	2	221	Room 221 Diagnostic Center	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	2 x 4 Drop Ceiling									
1	2	221	Room 221 Diagnostic Center	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	12 x 12 Floor Tiles									
1	2	S25	Stairwell C next to Classroom 215	Yes	W1	CMU	Yellow	Chipping	4	0	Negative	None	0	N/A	No	No	no	Wall 1 is the Fan Room side									
1	2	S25	Stairwell C next to Classroom 215	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	Wall 2 is open to Hallway									
1	2	S25	Stairwell C next to Classroom 215	Yes	W3	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no										
1	2	S25	Stairwell C next to Classroom 215	Yes	W4	CMU	White	Chipping	2	0	Negative	None	0	N/A	No	No	no										
1	2	S25	Stairwell C next to Classroom 215	Yes	W4	Sheetrock	White	Chipping	1	0	Negative	None	0	N/A	No	No	no										
1	2	S25	Stairwell C next to Classroom 215	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	2 x 4 Drop Ceiling									
1	2	S25	Stairwell C next to Classroom 215	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	12 x 12 Floor Tiles or Unpainted Concrete Steps									
1	2	215A	Fan Room adjacent to Classroom 215	No	W1	CMU	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	Wall is Unpainted									
1	2	215A	Fan Room adjacent to Classroom 215	No	W2	CMU	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	Wall is Unpainted									
1	2	215A	Fan Room adjacent to Classroom 215	No	Ladder	Metal	Gold	Chipping	10	0.04	Negative	None	0	N/A	No	No	no										
1	2	215A	Fan Room adjacent to Classroom 215	No	W3	CMU	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	Wall is Unpainted									
1	2	215A	Fan Room adjacent to Classroom 215	No	W4	CMU	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	Wall is Unpainted									
1	2	215A	Fan Room adjacent to Classroom 215	No	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	Ceiling is Unpainted									
1	2	215A	Fan Room adjacent to Classroom 215	No	Fan Units	Metal	Olive	Scratches	10	0	Negative	None	0	N/A	No	No	no										
1	2	215A	Fan Room adjacent to Classroom 215	No	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	Floor is Unpainted									
1	2	H221	Hallway adjacent to Classroom 215	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	Wall 1 is open to adjacent Hallway									
1	2	H221	Hallway adjacent to Classroom 215	Yes	W2	CMU	White	Chipping	8	0.01	Negative	None	0	N/A	No	No	no										
1	2	H221	Hallway adjacent to Classroom 215	Yes	W3	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no										
1	2	H221	Hallway adjacent to Classroom 215	Yes	W4	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no										
1	2	H221	Hallway adjacent to Classroom 215	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	2 x 4 Drop Ceiling									
1	2	H221	Hallway adjacent to Classroom 215	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	12 x 12 Floor Tiles									
1	2	221A	Team Planning Room Adjacent to Classroom 218	Yes	W1	No Access	No Access	No Access	No Access	No Access	No Access	None	0	N/A	No	No	no										
1	2	221A	Team Planning Room Adjacent to Classroom 218	Yes	W2	No Access	No Access	No Access	No Access	No Access	No Access	None	0	N/A	No	No	no										
1	2	221A	Team Planning Room Adjacent to Classroom 218	Yes	W3	No Access	No Access	No Access	No Access	No Access	No Access	None	0	N/A	No	No	no										
1	2	221A	Team Planning Room Adjacent to Classroom 218	Yes	W4	No Access	No Access	No Access	No Access	No Access	No Access	None	0	N/A	No	No	no										
1	2	221A	Team Planning Room Adjacent to Classroom 218	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	None	0	N/A	No	No	no										
1	2	221A	Team Planning Room Adjacent to Classroom 218	Yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access	None	0	N/A	No	No	no										
1	2	216	Room 216 Music	Yes	W1	CMU	Blue	None	0	N/A	N/A	None	0	N/A	No	No	no										
1	2	216	Room 216 Music	Yes	Door Frame	Metal	Blue	Chipping	1	0.08	Negative	None	0	N/A	No	No	no										
1	2	216	Room 216 Music	Yes	W2	CMU	Blue	None	0	N/A	N/A	None	0	N/A	No	No	no										
1	2	216	Room 216 Music	Yes	W2	Concrete	Blue	None	0	N/A	N/A	None	0	N/A	No	No	no										
1	2	216	Room 216 Music	Yes	Door Frame	Metal	Blue	Chipping	4	0.02	Negative	None	0	N/A	No	No	no										
1	2	216	Room 216 Music	Yes	W3	Concrete	Blue	None	0	N/A	N/A	None	0	N/A	No	No	no										
1	2	216	Room 216 Music	Yes	W4	CMU	Blue	None	0	N/A	N/A	None	0	N/A	No	No	no										
1	2	216	Room 216 Music	Yes	Ceiling	Plaster	White	None	0	N/A	N/A	None	0	N/A	No	No	no										
1	2	216	Room 216 Music	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	12 x 12 Floor Tiles									
1	2	216A	Room 216 Music Closet	yes	W1	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no										
1	2	216A	Room 216 Music Closet	yes	W2	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no										
1	2	216A	Room 216 Music Closet	yes	W3	Concrete	White	None	0	N/A	N/A	None	0	N/A	No	No	no										
1	2	216A	Room 216 Music Closet	yes	Shelves	Wood	Tan	Friction	4	0	Negative	None	0	N/A	No	No	no										
1	2	216A	Room 216 Music Closet	yes	W4	Concrete	White	None	0	N/A	N/A	None	0	N/A	No	No	no										
1	2	216A	Room 216 Music Closet	yes	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	Ceiling is Unpainted									
1	2	216A	Room 216 Music Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	9 x 9 Floor Tiles									
1	2	217	Room 217 Technology	Yes	W1	No Access	No Access	No Access	No Access	No Access	No Access	None	0	Negative	No	No	no										
1	2	217	Room 217 Technology	Yes	Column	No Access	No Access	No Access	No Access	No Access	No Access	None	0	Negative	No	No	no										
1	2	217	Room 217 Technology	Yes	W2	No Access	No Access	No Access	No Access	No Access	No Access	None	0	N/A	No	No	no										
1	2	217	Room 217 Technology	Yes	W3	Concrete						None	0	Negative	No	No	no										
1	2	217	Room 217 Technology	Yes	W4	Concrete						None	0	Negative	No	No	no										
1	2	217	Room 217 Technology	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	None	0	N/A	No	No	no										
1	2	217	Room 217 Technology	Yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access	None	0	N/A	No	No	no										
1	2	217A	Room 217 Technology Closet	yes	W1	No Access	No Access	No Access	No Access	No Access	No Access	None	0	N/A	No	No	no										
1	2	217A	Room 217 Technology Closet	yes	W2	No Access	No Access	No Access	No Access	No Access	No Access	None	0	N/A	No	No	no										
1	2	217A	Room 217 Technology Closet	yes	W3	No Access	No Access	No Access	No Access	No Access	No Access	None	0	N/A	No	No	no										
1	2	217A	Room 217 Technology Closet	yes	W4	No Access	No Access	No Access	No Access	No Access	No Access	None	0	N/A	No	No	no										
1	2	217A	Room 217 Technology Closet	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	None	0	N/A	No	No	no										
1	2	217A	Room 217 Technology Closet	yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access	None	0	N/A	No	No	no	Wall 1 is along Fan Room near Classroom 215 side									
1	2	H222	Hallway adjacent to Classrooms 216 and 217	Yes	W1	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	Wall 1 is along Fan Room near Classroom 215 side									

			School District of Philadelphia																
			Name of Inspector: Paul M. Davis		Lead Safe Certification Assessment Report							Inspection Dates: June 2021							
			Inspection Company: VERTEX		Bethune ES School							ULCS# 7510							
E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes
1	2	H222	Hallway adjacent to Classrooms 216 and 217	Yes	W2	CMU	White	Chipping	10	0.01	Negative	None	0	Negative	No	No	no	no	
1	2	H222	Hallway adjacent to Classrooms 216 and 217	Yes	W3	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	
1	2	H222	Hallway adjacent to Classrooms 216 and 217	Yes	W4	CMU	White	Chipping	10	0.01	Negative	None	0	N/A	No	No	no	no	
1	2	H222	Hallway adjacent to Classrooms 216 and 217	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	2 x 4 Drop Ceiling
1	2	H222	Hallway adjacent to Classrooms 216 and 217	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	12 x 12 Floor Tiles
1	2	218	Art Room 218	Yes	W1	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	
1	2	218	Art Room 218	Yes	W2	CMU	White	Chipping	6	0	Negative	None	0	N/A	No	No	no	no	
1	2	218	Art Room 218	Yes	Window Frames	Metal	Blue	Chipping	6	0.17	Negative	None	0	N/A	No	No	no	no	
1	2	218	Art Room 218	Yes	W3	CMU	White	Chipping	2	0	Negative	None	0	N/A	No	No	no	no	
1	2	218	Art Room 218	Yes	W4	CMU	White	Chipping	2	0	Negative	None	0	N/A	No	No	no	no	
1	2	218	Art Room 218	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	2 x 4 Drop Ceiling
1	2	218	Art Room 218	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	12 x 12 Floor Tiles
1	2	218A	Storage Closet Room 218A	No	W1	No Access	No Access	No Access	No Access	No Access	No Access	None	0	N/A	No	No	no	no	
1	2	218A	Storage Closet Room 218A	No	W2	No Access	No Access	No Access	No Access	No Access	No Access	None	0	N/A	No	No	no	no	
1	2	218A	Storage Closet Room 218A	No	W3	No Access	No Access	No Access	No Access	No Access	No Access	None	0	N/A	No	No	no	no	
1	2	218A	Storage Closet Room 218A	No	W4	No Access	No Access	No Access	No Access	No Access	No Access	None	0	N/A	No	No	no	no	
1	2	218A	Storage Closet Room 218A	No	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	None	0	N/A	No	No	no	no	
1	2	218A	Storage Closet Room 218A	No	Floor	No Access	No Access	No Access	No Access	No Access	No Access	None	0	N/A	No	No	no	no	
1	2	218B	Copy Room 218B	No	W1	CMU	White	Chipping	4	0.03	Negative	None	0	N/A	No	No	no	no	
1	2	218B	Copy Room 218B	No	Door Frame	Metal	Blue	Chipping	2	0.16	Negative	None	0	N/A	No	No	no	no	
1	2	218B	Copy Room 218B	No	Window Frame	Metal	Blue	Chipping	1	0.04	Negative	None	0	N/A	No	No	no	no	
1	2	218B	Copy Room 218B	No	W2	CMU	White	Chipping	2	0.03	Negative	None	0	N/A	No	No	no	no	
1	2	218B	Copy Room 218B	No	W3	CMU	White	Chipping	4	0.07	Negative	None	0	N/A	No	No	no	no	
1	2	218B	Copy Room 218B	No	W4	CMU	White	Chipping	2	0.04	Negative	None	0	N/A	No	No	no	no	
1	2	218B	Copy Room 218B	No	Window Frame	Metal	Blue	Chipping	2	0.06	Negative	None	0	N/A	No	No	no	no	
1	2	218B	Copy Room 218B	No	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	2 x 4 Drop Ceiling
1	2	218B	Copy Room 218B	No	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	9 x 9 Floor Tiles
1	2	H223	Hallway adjacent to Copy Room	Yes	W1	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	Wall 1 is along Room 218D side.
1	2	H223	Hallway adjacent to Copy Room	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	Wall 2 is open to adjacent Hallway
1	2	H223	Hallway adjacent to Copy Room	Yes	W3	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	
1	2	H223	Hallway adjacent to Copy Room	Yes	W4	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	
1	2	H223	Hallway adjacent to Copy Room	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	2 x 4 Drop Ceiling
1	2	H223	Hallway adjacent to Copy Room	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	12 x 12 Floor Tiles
1	2	218C	Classroom 218C	Yes	W1	CMU	White	Chipping	3	0.02	Negative	None	0	N/A	No	No	no	no	
1	2	218C	Classroom 218C	Yes	Door Frame	Metal	Blue	Chipping	2	0.13	Negative	None	0	N/A	No	No	no	no	
1	2	218C	Classroom 218C	Yes	W2	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	
1	2	218C	Classroom 218C	Yes	W3	CMU	White	Chipping	4	0.02	Negative	None	0	N/A	No	No	no	no	
1	2	218C	Classroom 218C	Yes	W4	CMU	White	Cracking	2	0.04	Negative	None	0	N/A	No	No	no	no	
1	2	218C	Classroom 218C	Yes	Window Frame	Metal	Blue	Chipping	2	0.03	Negative	None	0	N/A	No	No	no	no	
1	2	218C	Classroom 218C	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	2 x 4 Drop Ceiling
1	2	218C	Classroom 218C	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	9 x 9 Floor Tiles
1	2	218D	Office across from Copy Room	Yes	W1	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	
1	2	218D	Office across from Copy Room	Yes	Window Frame	Metal	Blue	Chipping	2	0.02	Negative	None	0	N/A	No	No	no	no	
1	2	218D	Office across from Copy Room	Yes	W2	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	
1	2	218D	Office across from Copy Room	Yes	Window Frame	Metal	Blue	Chipping	2	0.02	Negative	None	0	N/A	No	No	no	no	
1	2	218D	Office across from Copy Room	Yes	W3	CMU	White	Cracking	4	0.02	Negative	None	0	N/A	No	No	no	no	
1	2	218D	Office across from Copy Room	Yes	W4	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	
1	2	218D	Office across from Copy Room	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	2 x 4 Drop Ceiling
1	2	218D	Office across from Copy Room	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	9 x 9 Floor Tiles
1	2		Closet in Office across from Copy Room	Yes	W1	CMU	Green	None	0	N/A	N/A	None	0	N/A	No	No	no	no	
1	2		Closet in Office across from Copy Room	Yes	W2	CMU	Green	None	0	N/A	N/A	None	0	N/A	No	No	no	no	
1	2		Closet in Office across from Copy Room	Yes	W3	CMU	Green	None	0	N/A	N/A	None	0	N/A	No	No	no	no	
1	2		Closet in Office across from Copy Room	Yes	Shelves	Wood	Green	Friction	6	0	Negative	None	0	N/A	No	No	no	no	
1	2		Closet in Office across from Copy Room	Yes	W4	CMU	Green	None	0	N/A	N/A	None	0	N/A	No	No	no	no	
1	2		Closet in Office across from Copy Room	Yes	Ceiling	Concrete	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	
1	2		Closet in Office across from Copy Room	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	9 x 9 Floor Tiles
1	B	1	Classroom 1	Yes	W1	CMU	White	Chipping	1	0.06	Negative	None	0	N/A	No	No	no	no	
1	B	1	Classroom 1	Yes	Door Frame	Metal	Brown	Chipping	6	0.12	Negative	None	0	N/A	No	No	no	no	
1	B	1	Classroom 1	Yes	W2	CMU	White	None	0	0.05	Negative	None	0	Negative	No	No	no	no	
1	B	1	Classroom 1	Yes	W3	Concrete	White	Chipping	8	0.01	Negative	None	0	Negative	No	No	no	no	
1	B	1	Classroom 1	Yes	W4	Concrete	White	Chipping	2	0.03	Negative	None	0	Negative	No	No	no	no	
1	B	1	Classroom 1	Yes	Ceiling	Plaster	White	Efflorescence	3	0	Negative	None	0	N/A	No	Unknown	yes	no	
1	B	1	Classroom 1	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	12 x 12 Floor Tiles
1	B	001B	Classroom 1 Restroom	Yes	W1	CMU	White	Chipping	2	0.02	Negative	None	0	N/A	No	No	no	no	
1	B	001B	Classroom 1 Restroom	Yes	Door Frame	Metal	Blue	Chipping	2	0.21	Negative	None	0	N/A	No	No	no	no	
1	B	001B	Classroom 1 Restroom	Yes	W2	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	
1	B	001B	Classroom 1 Restroom	Yes	W3	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	
1	B	001B	Classroom 1 Restroom	Yes	W4	CMU	White	Chipping	1	0.02	Negative	None	0	N/A	No	No	no	no	
1	B	001B	Classroom 1 Restroom	Yes	Ceiling	Plaster	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	

18

			School District of Philadelphia																
			Name of Inspector: Paul M. Davis		Lead Safe Certification Assessment Report							Inspection Dates: June 2021							
			Inspection Company: VERTEX		Bethune ES School							ULCS# 7510							
E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes
1	B	003A	Classroom 3 Restroom	Yes	Radiator Cover	Metal	White	Chipping/Pitting/Rustin g	4	0.4	Negative	None	0	N/A	No	No	no	no	
1	B	003A	Classroom 3 Restroom	Yes	W4	CMU	White	None	0	0.03	Negative	None	0	N/A	No	No	no	no	
1	B	003A	Classroom 3 Restroom	Yes	Ceiling	Plaster	White	None	0	0	Negative	None	0	N/A	No	No	no	no	
1	B	003A	Classroom 3 Restroom	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	Ceramic Tiles
1	B	003B	Classroom 3 Rear Left Closet	yes	W1	CMU	Green	Partially Inaccessible	N/A	0.04	Negative	None	0	N/A	No	No	no	no	
1	B	003B	Classroom 3 Rear Left Closet	yes	W2	CMU	Green	Partially Inaccessible	N/A	0.03	Negative	None	0	N/A	No	No	no	no	
1	B	003B	Classroom 3 Rear Left Closet	yes	W3	CMU	Green	Partially Inaccessible	N/A	0.01	Negative	None	0	N/A	No	No	no	no	
1	B	003B	Classroom 3 Rear Left Closet	yes	Shelving	Wood	Green	Partially Inaccessible	N/A	0	Negative	None	0	N/A	No	No	no	no	
1	B	003B	Classroom 3 Rear Left Closet	yes	W4	CMU	Green	Partially Inaccessible	N/A	0.01	Negative	None	0	N/A	No	No	no	no	
1	B	003B	Classroom 3 Rear Left Closet	yes	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	Ceiling is Unpainted
1	B	003B	Classroom 3 Rear Left Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	9 x 9 Floor Tiles
1	B		Classroom 3 Rear Right Closet	yes	W1	No Access	No Access	No Access	No Access	No Access	No Access	None	0	N/A	No	No	no	no	
1	B		Classroom 3 Rear Right Closet	yes	W2	No Access	No Access	No Access	No Access	No Access	No Access	None	0	N/A	No	No	no	no	
1	B		Classroom 3 Rear Right Closet	yes	W3	No Access	No Access	No Access	No Access	No Access	No Access	None	0	N/A	No	No	no	no	
1	B		Classroom 3 Rear Right Closet	yes	W4	No Access	No Access	No Access	No Access	No Access	No Access	None	0	N/A	No	No	no	no	
1	B		Classroom 3 Rear Right Closet	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	None	0	N/A	No	No	no	no	
1	B		Classroom 3 Rear Right Closet	yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access	None	0	N/A	No	No	no	no	
1	B	H01	Hallway outside Classroom 3	Yes	W1	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	Wall 1 is Window side
1	B	H01	Hallway outside Classroom 3	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	Wall 2 is open to adjacent Hallway
1	B	H01	Hallway outside Classroom 3	Yes	W3	CMU	White	Chipping	3	0.02	Negative	None	0	N/A	No	No	no	no	
1	B	H01	Hallway outside Classroom 3	Yes	W4	CMU	White	Chipping	1	0.02	Negative	None	0	N/A	No	No	no	no	
1	B	H01	Hallway outside Classroom 3	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	2 x 4 Drop Ceiling
1	B	H01	Hallway outside Classroom 3	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	12 x 12 Floor Tiles
1	B	4	Classroom 4	Yes	W1	CMU	White	Chipping	1	0.01	Negative	None	0	N/A	No	No	no	no	
1	B	4	Classroom 4	Yes	Door Frame	Metal	Brown	Chipping	2	0.11	Negative	None	0	N/A	No	No	no	no	
1	B	4	Classroom 4	Yes	W2	CMU	White	Chipping	1	0	Negative	None	0	Negative	No	No	no	no	
1	B	4	Classroom 4	Yes	Door Frame	Metal	Blue	Chipping	4	0.07	Negative	None	0	N/A	No	No	no	no	
1	B	4	Classroom 4	Yes	W3	CMU	White	Chipping	2	0	Negative	None	0	N/A	No	No	no	no	
1	B	4	Classroom 4	Yes	Shelving	Wood	Blue	Partially Inaccessible	N/A	0.07	Negative	None	0	N/A	No	No	no	no	
1	B	4	Classroom 4	Yes	W4	CMU	White	Chipping	2	0	Negative	None	0	N/A	No	No	no	no	
1	B	4	Classroom 4	Yes	Ceiling	Plaster	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	
1	B	4	Classroom 4	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	9 x 9 and 12 x 12 Floor Tiles
1	B	004A	Classroom 4 Front Closet	yes	W1	No Access	No Access	No Access	No Access	No Access	No Access	None	0	N/A	No	No	no	no	
1	B	004A	Classroom 4 Front Closet	yes	W2	No Access	No Access	No Access	No Access	No Access	No Access	None	0	N/A	No	No	no	no	
1	B	004A	Classroom 4 Front Closet	yes	W3	No Access	No Access	No Access	No Access	No Access	No Access	None	0	N/A	No	No	no	no	
1	B	004A	Classroom 4 Front Closet	yes	W4	No Access	No Access	No Access	No Access	No Access	No Access	None	0	N/A	No	No	no	no	
1	B	004A	Classroom 4 Front Closet	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	None	0	N/A	No	No	no	no	
1	B	004A	Classroom 4 Front Closet	yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access	None	0	N/A	No	No	no	no	
1	B	004B	Classroom 4 Restroom	Yes	W1	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	
1	B	004B	Classroom 4 Restroom	Yes	Door Frame	Metal	Blue	Chipping	4	0.04	Negative	None	0	N/A	No	No	no	no	
1	B	004B	Classroom 4 Restroom	Yes	W2	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	
1	B	004B	Classroom 4 Restroom	Yes	Radiator Cover	Metal	White	None	0	0.5	Negative	None	0	N/A	No	No	no	no	
1	B	004B	Classroom 4 Restroom	Yes	W3	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	
1	B	004B	Classroom 4 Restroom	Yes	W4	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	
1	B	004B	Classroom 4 Restroom	Yes	Ceiling	Plaster	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	
1	B	004B	Classroom 4 Restroom	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	Ceramic Tiles
1	B		Classroom 4 Rear Closet	yes	W1							None	0	N/A	No	No	no	no	
1	B		Classroom 4 Rear Closet	yes	W2	No Access	No Access	No Access	No Access	No Access	No Access	None	0	N/A	No	No	no	no	
1	B		Classroom 4 Rear Closet	yes	W3	No Access	No Access	No Access	No Access	No Access	No Access	None	0	N/A	No	No	no	no	
1	B		Classroom 4 Rear Closet	yes	W4	No Access	No Access	No Access	No Access	No Access	No Access	None	0	N/A	No	No	no	no	
1	B		Classroom 4 Rear Closet	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	None	0	N/A	No	No	no	no	
1	B		Classroom 4 Rear Closet	yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access	None	0	N/A	No	No	no	no	
1	B	S02	Stairwell A next to Classroom 1	Yes	W1	CMU	White	Chipping	2	0.03	Negative	None	0	Negative	No	No	no	no	Wall 1 is Boiler Room Area side
1	B	S02	Stairwell A next to Classroom 1	Yes	W2	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	
1	B	S02	Stairwell A next to Classroom 1	Yes	W3	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	
1	B	S02	Stairwell A next to Classroom 1	Yes	W4	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no	
1	B	S02	Stairwell A next to Classroom 1	Yes	Ceiling	Concrete	White	None	0	N/A	N/A	None	0	Negative	No	No	no	no	There is also 2 x 4 Drop Ceiling
1	B	S02	Stairwell A next to Classroom 1	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	Unpainted
1	B	S02	Stairwell A next to Classroom 1	Yes	Stairs Underside	Metal	Blue	Chipping	3	3.1	Positive	None	0	N/A	No	No	no	no	Main Beam
1	B	005A	Storage Room Adjacent to Classroom 5	No	W1	CMU	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	Wall is Unpainted
1	B	005A	Storage Room Adjacent to Classroom 5	No	Doors	Metal	Brown	Scrapes	2	0	Negative	None	0	N/A	No	No	no	no	
1	B	005A	Storage Room Adjacent to Classroom 5	No	W2	CMU	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	Wall is Unpainted
1	B	005A	Storage Room Adjacent to Classroom 5	No	W3	CMU	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	Wall is Unpainted
1	B	005A	Storage Room Adjacent to Classroom 5	No	W4	CMU	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	Wall is Unpainted
1	B	005A	Storage Room Adjacent to Classroom 5	No	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	Ceiling is Unpainted
1	B	005A	Storage Room Adjacent to Classroom 5	No	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	Floor is Unpainted
1	B	6	Classroom 5	Yes	W1	CMU	White	None	0	0	Negative	None	0	Negative	No	No	no	no	
1	B	6	Classroom 5	Yes	W2	CMU	White	Flaking	2	0	Negative	None	0	N/A	No	No	no	no	

			School District of Philadelphia																							
			Name of Inspector: Paul M. Davis		Lead Safe Certification Assessment Report										Inspection Dates: June 2021											
			Inspection Company: VERTEX		Bethune ES School										ULCS# 7510											
E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes							
1	B	6	Classroom 5	Yes	W3	CMU	White	None	0	0	Negative	None	0	N/A	No	No	no	no								
1	B	6	Classroom 5	Yes	W4	CMU	White	Cracking	6	0	Negative	None	0	N/A	No	No	no	no								
1	B	6	Classroom 5	Yes	Ceiling	Plaster	White	None	0	N/A	N/A	None	0	Negative	No	No	no	no								
1	B	6	Classroom 5	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	12 x 12 Floor Tiles							
1	B	006A	Classroom 5 Restroom	Yes	W1	CMU	White	Chipping	1	0.01	Negative	None	0	N/A	No	No	no	no								
1	B	006A	Classroom 5 Restroom	Yes	W2	CMU	White	None	0	0.02	Negative	None	0	N/A	No	No	no	no								
1	B	006A	Classroom 5 Restroom	Yes	W3	CMU	White	None	0	0.03	Negative	None	0	N/A	No	No	no	no								
1	B	006A	Classroom 5 Restroom	Yes	W4	CMU	White	Chipping	1	0.02	Negative	None	0	N/A	No	No	no	no								
1	B	006A	Classroom 5 Restroom	Yes	Ceiling	Plaster	White	None	0	0	Negative	None	0	N/A	No	No	no	no								
1	B	006A	Classroom 5 Restroom	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	Ceramic Tile							
1	B	006B	Classroom 5 Closet	yes	W1	No Access	No Access	No Access	No Access	No Access	No Access	None	0	N/A	No	No	no	no								
1	B	006B	Classroom 5 Closet	yes	W2	No Access	No Access	No Access	No Access	No Access	No Access	None	0	N/A	No	No	no	no								
1	B	006B	Classroom 5 Closet	yes	W3	No Access	No Access	No Access	No Access	No Access	No Access	None	0	N/A	No	No	no	no								
1	B	006B	Classroom 5 Closet	yes	W4	No Access	No Access	No Access	No Access	No Access	No Access	None	0	N/A	No	No	no	no								
1	B	006B	Classroom 5 Closet	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	None	0	N/A	No	No	no	no								
1	B	006B	Classroom 5 Closet	yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access	None	0	N/A	No	No	no	no								
1	B	H02	Hallway from Classrooms 1 to 5	Yes	W1	CMU	White	Chipping	6	0.04	Negative	None	0	N/A	No	No	no	no	Wall 1 along Classroom 1 and Stairwell side							
1	B	H02	Hallway from Classrooms 1 to 5	Yes	W2	CMU	White	Chipping	4	0.04	Negative	None	0	N/A	No	No	no	no								
1	B	H02	Hallway from Classrooms 1 to 5	Yes	Doors	Metal	Blue	Chipping	2	0	Negative	None	0	N/A	No	No	no	no	Exterior Doors to Parking Lot							
1	B	H02	Hallway from Classrooms 1 to 5	Yes	W3	CMU	White	None	0	0.04	Negative	None	0	N/A	No	No	no	no								
1	B	H02	Hallway from Classrooms 1 to 5	Yes	Doors	Metal	Blue	Chipping	2	0	Negative	None	0	N/A	No	No	no	no	Exterior Doors to Play Area							
1	B	H02	Hallway from Classrooms 1 to 5	Yes	W4	CMU	White	Chipping	4	0.03	Negative	None	0	N/A	No	No	no	no								
1	B	H02	Hallway from Classrooms 1 to 5	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	2 x 4 Drop Ceiling							
1	B	H02	Hallway from Classrooms 1 to 5	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	12 x 12 Floor Tiles							
1	B	5	Boiler Room	No	W1	CMU	White	Chipping	4	0	Negative	None	0	N/A	No	No	no	no								
1	B	5	Boiler Room	No	Window Frame	Metal	Olive	Chipping	6	0.02	Negative	None	0	N/A	No	No	no	no								
1	B	5	Boiler Room	No	W1	Concrete	White	Chipping	4	0	Negative	None	0	N/A	No	No	no	no	In Lower Part of Boiler Room							
1	B	5	Boiler Room	No	W2	CMU	White	Chipping	4	0	Negative	None	0	Negative	No	No	no	no								
1	B	5	Boiler Room	No	Column	Concrete	White	Chipping	4	0	Negative	None	0	Negative	No	No	no	no								
1	B	5	Boiler Room	No	W3	CMU	White	Chipping	4	0	Negative	None	0	N/A	No	No	no	no								
1	B	5	Boiler Room	No	Doors	Metal	Olive	Chipping	2	0	Negative	None	0	N/A	No	No	no	no								
1	B	5	Boiler Room	No	W4	CMU	White	Chipping	4	0	Negative	None	0	Negative	No	No	no	no								
1	B	5	Boiler Room	No	Duct Work	Metal	White	Chipping	4	0	Negative	None	0	Negative	No	No	no	no								
1	B	5	Boiler Room	No	Ceiling	Concrete	White	Chipping	4	0	Negative	None	0	N/A	No	No	no	no								
1	B	5	Boiler Room	No	Railings	Metal	Yellow	Chipping	2	0.05	Negative	None	0	N/A	No	No	no	no								
1	B	5	Boiler Room	No	Steps	Metal	Grey	Chipping	2	0.07	Negative	None	0	N/A	No	No	no	no	Steps to Lower Area							
1	B	5	Boiler Room	No	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	Floor is Unpainted							
1	B		Main Electrical Room	No	W1	CMU	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	Wall is Unpainted							
1	B		Main Electrical Room	No	W2	CMU	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	Wall is Unpainted							
1	B		Main Electrical Room	No	W3	CMU	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	Wall is Unpainted							
1	B		Main Electrical Room	No	W4	CMU	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	Wall is Unpainted							
1	B		Main Electrical Room	No	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	Ceiling is Unpainted							
1	B		Main Electrical Room	No	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	Floor is Unpainted							
1	B	10	Building Engineer's Office adjacent to Boiler Room	No	W1	CMU	Tan	None	0	N/A	N/A	None	0	N/A	No	No	no	no								
1	B	10	Building Engineer's Office adjacent to Boiler Room	No	Door Frame	Metal	Green	Chipping	4	0.02	Negative	None	0	N/A	No	No	no	no								
1	B	10	Building Engineer's Office adjacent to Boiler Room	No	W2	CMU	Tan	Partially Inaccessible	N/A	0	Negative	None	0	N/A	No	No	no	no								
1	B	10	Building Engineer's Office adjacent to Boiler Room	No	Door Frame	Metal	Green	Chipping	2	0.09	Negative	None	0	N/A	No	No	no	no								
1	B	10	Building Engineer's Office adjacent to Boiler Room	No	W3	CMU	Tan	Partially Inaccessible	N/A	0	Negative	None	0	N/A	No	No	no	no								
1	B	10	Building Engineer's Office adjacent to Boiler Room	No	W4	CMU	Tan	Partially Inaccessible	N/A	0	Negative	None	0	N/A	No	No	no	no								
1	B	10	Building Engineer's Office adjacent to Boiler Room	No	Ceiling	Plaster	White	Partially Inaccessible	N/A	0	Negative	None	0	N/A	No	No	no	no								
1	B	10	Building Engineer's Office adjacent to Boiler Room	No	Duct Work	Metal	White	Flaking	2	0	Negative	None	0	N/A	No	No	no	no								
1	B	10	Building Engineer's Office adjacent to Boiler Room	No	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	12 x 12 Floor Tiles							
1	B	10A	Building Engineer's Office Restroom	No	W1	CMU	Yellow	None	0	N/A	N/A	None	0	N/A	No	No	no	no								
1	B	10A	Building Engineer's Office Restroom	No	W2	CMU	Yellow	None	0	N/A	N/A	None	0	N/A	No	No	no	no								
1	B	10A	Building Engineer's Office Restroom	No	W3	CMU	Yellow	None	0	N/A	N/A	None	0	N/A	No	No	no	no								
1	B	10A	Building Engineer's Office Restroom	No	W4	CMU	Yellow	None	0	N/A	N/A	None	0	N/A	No	No	no	no								
1	B	10A	Building Engineer's Office Restroom	No	Ceiling	Plaster	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no								
1	B	10A	Building Engineer's Office Restroom	No	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	Ceramic Tile							
1	B	005B	Storage Room Adjacent to Boiler Room	No	W1	CMU	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	Wall is Unpainted							
1	B	005B	Storage Room Adjacent to Boiler Room	No	Doors	Metal	Olive	Chipping	6	0	Negative	None	0	N/A	No	No	no	no								
1	B	005B	Storage Room Adjacent to Boiler Room	No	W2	CMU	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	Wall is Unpainted							
1	B	005B	Storage Room Adjacent to Boiler Room	No	W3	CMU	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	Wall is Unpainted							
1	B	005B	Storage Room Adjacent to Boiler Room	No	W4	CMU	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	Wall is Unpainted							
1	B	005B	Storage Room Adjacent to Boiler Room	No	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	Ceiling is Unpainted							
1	B	005B	Storage Room Adjacent to Boiler Room	No	Pipes	Metal	Grey	Chipping	10	0.29	Negative	None	0	N/A	No	No	no	no								
1	B	005B	Storage Room Adjacent to Boiler Room	No	Hand Rail	Metal	Pink	Chipping	8	0.04	Negative	None	0	N/A	No	No	no	no								
1	B	005B	Storage Room Adjacent to Boiler Room	No	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	Floor is Unpainted							
1	B	005C	School Supply Storage Room	yes	W1	CMU	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	Wall is Unpainted							
1	B	005C	School Supply Storage Room	yes	Pipes	Metal	Grey	Chipping	1	0.14	Negative	None	0	N/A	No	No	no	no	Wall is Unpainted							

			School District of Philadelphia		Lead Safe Certification Assessment Report								Inspection Dates: June 2021								
			Name of Inspector: Paul M. Davis																		
			Inspection Company: VERTEX		Bethune ES School								ULCS# 7510								
E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes		
1	B	005C	School Supply Storage Room	yes	W2	Concrete	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	Wall is Unpainted		
1	B	005C	School Supply Storage Room	yes	W3	Concrete	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	Wall is Unpainted		
1	B	005C	School Supply Storage Room	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	No Wall; Cage Fencing		
1	B	005C	School Supply Storage Room	yes	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	Ceiling is Unpainted		
1	B	005C	School Supply Storage Room	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	Floor is Unpainted		
1	B	7	Custodial Break Room	No	W1	CMU	White	None	0	N/A	N/A	None	0	Negative	No	No	no	no			
1	B	7	Custodial Break Room	No	W2	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no			
1	B	7	Custodial Break Room	No	W3	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no			
1	B	7	Custodial Break Room	No	W4	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no			
1	B	7	Custodial Break Room	No	Ceiling	Plaster	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no			
1	B	7	Custodial Break Room	No	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	12 x 12 Floor Tiles		
1	B	007B	Custodian's Restroom	No	W1	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no			
1	B	007B	Custodian's Restroom	No	W2	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no			
1	B	007B	Custodian's Restroom	No	W3	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no			
1	B	007B	Custodian's Restroom	No	W4	CMU	White	None	0	N/A	N/A	None	0	Negative	No	No	no	no			
1	B	007B	Custodian's Restroom	No	Ceiling	Plaster	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no			
1	B	007B	Custodian's Restroom	No	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	Ceramic Tiles		
1	B	007A	Elevator Mechanical Room	No	W1	CMU	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	Wall is Unpainted		
1	B	007A	Elevator Mechanical Room	No	W2	CMU	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	Wall is Unpainted		
1	B	007A	Elevator Mechanical Room	No	W3	CMU	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	Wall is Unpainted		
1	B	007A	Elevator Mechanical Room	No	W4	CMU	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	Wall is Unpainted		
1	B	007A	Elevator Mechanical Room	No	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	Ceiling is Unpainted		
1	B	007A	Elevator Mechanical Room	No	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	Floor is Unpainted		
1	B	H03	Hallway adjacent to Elevator	Yes	W1	CMU	White	None	0	N/A	N/A	None	0	Negative	No	No	no	no	Wall 1 is along School Supply Storage Room side		
1	B	H03	Hallway adjacent to Elevator	Yes	W2	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no			
1	B	H03	Hallway adjacent to Elevator	Yes	W3	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no			
1	B	H03	Hallway adjacent to Elevator	Yes	W4	CMU	White	None	0	N/A	N/A	None	0	Negative	No	No	no	no			
1	B	H03	Hallway adjacent to Elevator	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	2 x 4 Drop Ceiling		
1	B	H03	Hallway adjacent to Elevator	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	12 x 12 Floor Tiles		
1	B	ELEV	Elevator	Yes	W1	Metal	White	Chipping	2	0.01	Negative	None	0	N/A	No	No	no	no			
1	B	ELEV	Elevator	Yes	W2	Metal	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no			
1	B	ELEV	Elevator	Yes	W3	Metal	White	Chipping	4	0	Negative	None	0	N/A	No	No	no	no			
1	B	ELEV	Elevator	Yes	W4	Metal	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no			
1	B	ELEV	Elevator	Yes	Ceiling	Metal	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no			
1	B	ELEV	Elevator	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	12 x 12 Floor Tiles		
1	B	S01	Stairwell B by Elevator	Yes	W1	Concrete	White	None	0	N/A	N/A	None	0	Negative	No	No	no	no	Wall 1 is along School Supply Storage Room side		
1	B	S01	Stairwell B by Elevator	Yes	W2	CMU	White	None	0	N/A	N/A	None	0	Negative	No	No	no	no			
1	B	S01	Stairwell B by Elevator	Yes	W3	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no			
1	B	S01	Stairwell B by Elevator	Yes	W4	CMU	White	None	0	N/A	N/A	None	0	N/A	No	No	no	no			
1	B	S01	Stairwell B by Elevator	Yes	Ceiling	Concrete	White	None	0	N/A	N/A	None	0	Negative	No	No	no	no			
1	B	S01	Stairwell B by Elevator	Yes	Stair Riser	Metal	Blue	Chipping	4	0.04	Negative	None	0	N/A	No	No	no	no			
1	B	S01	Stairwell B by Elevator	Yes	Stair Stringer	Metal	Blue	Chipping	2	0.06	Negative	None	0	N/A	No	No	no	no			
1	B	S01	Stairwell B by Elevator	Yes	Stairs Underside	Metal	Blue	Chipping	1	2.1	Positive	None	0	N/A	No	No	no	no	Main Beam		
1	B	S01	Stairwell B by Elevator	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A	No	No	no	no	12 x 12 Floor Tiles or Unpainted		