

Element Floor Space #			School District of Philadelphia																
			Name of Inspector: Lionel Ray Wilson		Lead Safe Certification Assessment Report							Inspection Dates: 09/30/21-10/01/21							
			Inspection Company: Viva EHS		Overbrook Elementary School							ULCS# 4370							
On Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes			
1	1	9A	Main Office	Yes	W1	Sheetrock	Tan	Chipping	5	0	Negative						Changed reading from (22.4) to (0) - Viva EHS - 10/1/21 - EJS		
1	1	9A	Main Office	Yes	W2	Plaster	Tan	Chipping	50	0.9	Positive	N/A	N/A	N/A	N/A	N/A	Changed from sheetrock to plaster - Viva EHS - 10/1/21 - EJS		
1	1	9A	Main Office	Yes	W3	Plaster	Tan	Chipping	50	19.8	Positive	N/A	N/A	N/A	N/A	N/A	Changed from sheetrock to plaster - Viva EHS - 10/1/21 - EJS		
1	1	9A	Main Office	Yes	W4	Sheetrock	Tan	Chipping	10	0	Negative						Changed reading from (18.8) to (0) - Viva EHS - 10/1/21 - EJS		
1	1	9A	Main Office	Yes	Ceiling	Plaster	Tan	Chipping	10	8.8	Positive	N/A	N/A	N/A	N/A	N/A	Changed from sheetrock to plaster - Viva EHS - 10/1/21 - EJS		
1	1	9A	Main Office	yes	Radiator	Metal	Grey	Chipping	5	0.7	Positive		This material has not been sampled based on AHERA log-Viva EHS-RW						
1	1	9A	Main Office	Yes	Conduit	Metal	White	Chipping	5	10.1	Positive		This material has not been sampled based on AHERA log-Viva EHS-RW						
1	1	9A	Main Office	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A								
1	1	9C	Principal's Office	Yes	W1	Plaster	Tan	Chipping	5	22	Positive	N/A	N/A	N/A	N/A	N/A	Changed from sheetrock to plaster - Viva EHS - 10/1/21 - EJS		
1	1	9C	Principal's Office	Yes	W2	Sheetrock	Tan	Chipping	10	0	Negative						Changed reading from (23.4) to (0) - Viva EHS - 10/1/21 - EJS		
1	1	9C	Principal's Office	Yes	W3	Sheetrock	Tan	Chipping	5	0	Negative						Changed reading from (20.1) to (0) - Viva EHS - 10/1/21 - EJS		
1	1	9C	Principal's Office	Yes	W4	Sheetrock	Tan	Chipping	5	0	Negative						Changed reading from (21.8) to (0) - Viva EHS - 10/1/21 - EJS		
1	1	9C	Principal's Office	Yes	Ceiling	Plaster	Tan	Flaking	5	19.3	Positive	N/A	N/A	N/A	N/A	N/A			
1	1	9C	Principal's Office	Yes	Radiator	Metal	Grey	Chipping	4	13.1	Positive		This material has not been sampled based on AHERA log-Viva EHS-RW						
1	1	9C	Principal's Office	Yes	Baseboard	Wood	Brown	Chipping	3 LF	0.17	Negative						Added - Viva EHS - 10/1/21 - EJS		
1	1	9C	Principal's Office	Yes	Window Sill	Wood	Brown	Chipping	3	0.28	Negative						Added - Viva EHS - 10/1/21 - EJS		
1	1	9	Classroom 9	Yes	W1	Plaster	Tan	None	0	24.5	Positive	N/A	N/A	N/A	N/A	N/A	Changed from sheetrock to plaster - Viva EHS - 9/30/21 - EJS		
1	1	9	Classroom 9	Yes	W2	Wood	Brown	None	0	N/A	N/A								
1	1	9	Classroom 9	Yes	W3	Plaster	Tan	Chipping	10	26.6	Positive	N/A	N/A	N/A	N/A	N/A	Changed from sheetrock to plaster - Viva EHS - 9/30/21 - EJS		
1	1	9	Classroom 9	Yes	W4	Plaster	Tan	Chipping	15	23.5	Positive	N/A	N/A	N/A	N/A	N/A	Changed from sheetrock to plaster - Viva EHS - 9/30/21 - EJS		
1	1	9	Classroom 9	Yes	Ceiling	Concrete	Tan	Chipping	5	10.4	Positive	N/A	N/A	N/A	N/A	N/A			
1	1	9	Classroom 9	Yes	Window Sill	Wood	Tan	Chipping	5	6.7	Positive		This material has not been sampled based on AHERA log-Viva EHS-RW						
1	1	9D	Classroom 9 Restrooms	Yes	W1	Plaster	Tan	Chipping	10	13.6	Positive	N/A	N/A	N/A	N/A	N/A	Changed from sheetrock to plaster - Viva EHS - 9/30/21 - EJS		
1	1	9D	Classroom 9 Restrooms	Yes	W2	Plaster	Tan	Chipping	8	10.8	Positive	N/A	N/A	N/A	N/A	N/A	Changed from sheetrock to plaster - Viva EHS - 9/30/21 - EJS		
1	1	9D	Classroom 9 Restrooms	Yes	W3	Plaster	Tan	Chipping	10	15.2	Positive	N/A	N/A	N/A	N/A	N/A	Changed from sheetrock to plaster - Viva EHS - 9/30/21 - EJS		
1	1	9D	Classroom 9 Restrooms	Yes	W4	Sheetrock	Tan	Chipping	15	14.6	Positive	N/A	N/A	N/A	N/A	N/A			
1	1	9D	Classroom 9 Restrooms	Yes	Window Sill	Wood	Tan	Chipping	2	0.3	Negative						Changed from sheetrock to wood and reading (1.1) to (0.3) - Viva EHS - 9/30/21 - EJS		
1	1	9D	Classroom 9 Restrooms	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Added- Viva EHS - 9/30/21 - EJS		
1	1	9D	Classroom 9 Restrooms	Yes	Floor	Concrete	Grey	Flaking	15	0.17	Negative						Changed from tan to grey, no damage to flaking 15SF, and reading (N/A) to (.17) - Viva EHS - 9/30/21 - EJS		
1	1	9D	Classroom 9 Restrooms	Yes	Pipe	Metal	White	Chipping	3	7.6	Positive		This material has not been sampled based on AHERA log-Viva EHS-RW				Added - Viva EHS - 9/30/21 - EJS		
1	1	9E	Coat Closet next to Classroom 9	Yes	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Items blocking path-Viva EHS-RW		
1	1	9E	Coat Closet next to Classroom 9	Yes	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Items blocking path-Viva EHS-RW		
1	1	9E	Coat Closet next to Classroom 9	Yes	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Items blocking path-Viva EHS-RW		
1	1	9E	Coat Closet next to Classroom 9	Yes	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Items blocking way-Viva EHS-RW		
1	1	9E	Coat Closet next to Classroom 9	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Items blocking path to sample-Viva EHS-RW		
1	1	9E	Coat Closet next to Classroom 9	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A								
1	1	8	Classroom 8	Yes	W1	Plaster	Tan	None	0	23	Positive	N/A	N/A	N/A	N/A	N/A	Changed from sheetrock to plaster - Viva EHS - 10/1/21 - EJS		
1	1	8	Classroom 8	Yes	W2	Plaster	Tan	Chipping	5	24.2	Positive	N/A	N/A	N/A	N/A	N/A	Changed from sheetrock to plaster - Viva EHS - 10/1/21 - EJS		
1	1	8	Classroom 8	Yes	W3	Plaster	Tan	Chipping	15	27.4	Positive	N/A	N/A	N/A	N/A	N/A	Changed from sheetrock to plaster - Viva EHS - 10/1/21 - EJS		
1	1	8	Classroom 8	Yes	W4	Plaster	Tan	Cracking	5	25.2	Positive	N/A	N/A	N/A	N/A	N/A	Changed from sheetrock to plaster - Viva EHS - 10/1/21 - EJS		
1	1	8	Classroom 8	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A						Ceiling tile in space-Viva EHS-RW		
1	1	8	Classroom 8	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A								

1	1	8A	Classroom 8 Closet	Yes	W1	Plaster	Tan	Chipping	15	18.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	1	8A	Classroom 8 Closet	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A								
1	1	8A	Classroom 8 Closet	Yes	W3	Plaster	Tan	Chipping	10	17.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Changed from sheetrock to plaster - Viva EHS - 10/1/21 - EJS
1	1	8A	Classroom 8 Closet	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A								
1	1	8A	Classroom 8 Closet	Yes	Ceiling	Plaster	Tan	None	0	10.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Changed from sheetrock to plaster - Viva EHS - 10/1/21 - EJS
1	1	8A	Classroom 8 Closet	Yes	Floor	Wood	Brown	None	0	N/A	N/A								
1	1	7	Classroom 7	Yes	W1	Plaster	Tan	Chipping	5	35	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	1	7	Classroom 7	Yes	W2	Sheetrock	Tan	Chipping	5	0.1	Negative								
1	1	7	Classroom 7	Yes	W3	Plaster	Tan	Flaking	5	22.3	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Changed from sheetrock to plaster - Viva EHS - 10/1/21 - EJS
1	1	7	Classroom 7	Yes	W4	Wood	Tan	None	0	0.1	Negative								
1	1	7	Classroom 7	Yes	Ceiling	Plaster	Tan	Flaking	5	10	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	1	7	Classroom 7	Yes	Floor	Wood	Brown	None	0	N/A	N/A								
1	1	7A	Classroom 7 Closet	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A								
1	1	7A	Classroom 7 Closet	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A								
1	1	7A	Classroom 7 Closet	Yes	W3	Plaster	Tan	Friction	1	0.1	Negative								
1	1	7A	Classroom 7 Closet	Yes	W4	Sheetrock	Tan	Friction	1	0.2	Negative								
1	1	7A	Classroom 7 Closet	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Items blocking path to sample-Viva EHS-RW
1	1	7A	Classroom 7 Closet	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A								
1	1	S10	Stairwell next to Main Office	Yes	W1	Sheetrock	Tan	Chipping	5	0.1	Negative	None							Changed from plaster to sheetrock - Viva EHS - 9/30/21 - EJS
1	1	S10	Stairwell next to Main Office	Yes	W2	Sheetrock	Tan	Chipping	6	0.2	Negative	None							
1	1	S10	Stairwell next to Main Office	Yes	W3	Wood	Tan	None	0	0	Negative	None							
1	1	S10	Stairwell next to Main Office	Yes	W4	Sheetrock	Tan	Flaking	8	0.2	Negative	None							Changed from plaster to sheetrock - Viva EHS - 9/30/21 - EJS
1	1	S10	Stairwell next to Main Office	Yes	W4 door	Wood	Tan	None	0	0.2	Negative	None							
1	1	S10	Stairwell next to Main Office	Yes	W4 chair rail	Wood	Tan	Chipping	15	0.2	Negative	None							
1	1	S10	Stairwell next to Main Office	Yes	Ceiling	Metal	White	Flaking	12	4.7	Positive	None		This material has not been sampled based on AHERA log-Viva EHS-RW					Viva EHS - Viva EHS - 9/30/21 - EJS
1	1	S10	Stairwell next to Main Office	Yes	Floor	Wood	Brown	None	0	N/A	N/A								Changed from concrete to wood - Viva EHS - 9/30/21 - EJS
2	1	SC	Service Closet across from Classroom 4	no	W1	Sheetrock	White	Flaking	1	0	Negative								Added - Viva EHS - 9/30/21 - EJS
2	1	SC	Service Closet across from Classroom 4	no	W2	Plaster	Blue	Flaking	10	20.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Added - Viva EHS - 9/30/21 - EJS
2	1	SC	Service Closet across from Classroom 4	no	W3	Plaster	Blue	Flaking	15	38.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Added - Viva EHS - 9/30/21 - EJS
2	1	SC	Service Closet across from Classroom 4	no	W4	Plaster	Blue	Flaking	25	25	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Added - Viva EHS - 9/30/21 - EJS
2	1	SC	Service Closet across from Classroom 4	no	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	Added - Viva EHS - 9/30/21 - EJS
2	1	SC	Service Closet across from Classroom 4	no	Floor	N/A	N/A	N/A	N/A	N/A	N/A								Added - Viva EHS - 9/30/21 - EJS
1	1	H10	Hallway near Main Office and Classroom 7	Yes	W1	Sheetrock	Tan	None	0	0.1	Negative								Changed everything - Viva EHS - 9/30/21 - EJS
1	1	H10	Hallway near Main Office and Classroom 7	Yes	W2	Plaster	Tan	Chipping	3	24.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Changed brick to plaster - Viva EHS - 9/30/21 - EJS
1	1	H10	Hallway near Main Office and Classroom 7	Yes	W3	Plaster	Tan	Chipping	5	20.3	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Changed brick to plaster - Viva EHS - 9/30/21 - EJS
1	1	H10	Hallway near Main Office and Classroom 7	Yes	W4	Plaster	Tan	Chipping	5	1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Changed brick to plaster - Viva EHS - 9/30/21 - EJS
1	1	H10	Hallway near Main Office and Classroom 7	Yes	Ceiling	Concrete	Tan	Flaking	5	5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	1	H10	Hallway near Main Office and Classroom 7	Yes	Window Sill	Wood	Brown	Chipping	0.5	0.2	Negative								
2	1	7C	Women's Staff Restroom next to Classroom 7	Yes	W1	Plaster	Tan	Chipping	0.5	18.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Changed from sheetrock to plaster - Viva EHS - 9/30/21 - EJS
2	1	7C	Women's Staff Restroom next to Classroom 7	Yes	W2	Plaster	Tan	Chipping	1	21.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Changed from sheetrock to plaster - Viva EHS - 9/30/21 - EJS
2	1	7C	Women's Staff Restroom next to Classroom 7	Yes	W3	Plaster	Tan	Cracking	15	22.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Changed from sheetrock to plaster - Viva EHS - 9/30/21 - EJS
2	1	7C	Women's Staff Restroom next to Classroom 7	Yes	W4	Plaster	Tan	Chipping	10	20.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Changed from sheetrock to plaster - Viva EHS - 9/30/21 - EJS
2	1	7C	Women's Staff Restroom next to Classroom 7	Yes	Ceiling	Plaster	Tan	Flaking	2	15.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Changed from sheetrock to plaster - Viva EHS - 9/30/21 - EJS
2	1	7C	Women's Staff Restroom next to Classroom 7	Yes	Baseboard	Concrete	Brown	None	0	0.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2	1	7A	Storeroom/Entrance to Staff Restroom off Stairwell	Yes	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	B.E. did not have keys to open-Viva EHS-RW
2	1	7A	Storeroom/Entrance to Staff Restroom off Stairwell	Yes	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	B.E. did not have keys to open-Viva EHS-RW
2	1	7A	Storeroom/Entrance to Staff Restroom off Stairwell	Yes	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	B.E. did not have keys to open-Viva EHS-RW
2	1	7A	Storeroom/Entrance to Staff Restroom off Stairwell	Yes	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	B.E. did not have keys to open-Viva EHS-RW
2	1	7A	Storeroom/Entrance to Staff Restroom off Stairwell	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	B.E. was not able to open this space-Viva EHS-RW
2	1	7A	Storeroom/Entrance to Staff Restroom off Stairwell	Yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	B.E. was not able to open this space-Viva EHS-RW
2	1	7B	Staff Restroom off Stairwell	Yes	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	B.E. did not have keys to open-Viva EHS-RW
2	1	7B	Staff Restroom off Stairwell	Yes	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	B.E. did not have keys to open-Viva EHS-RW
2	1	7B	Staff Restroom off Stairwell	Yes	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	B.E. did not have keys to open-Viva EHS-RW
2	1	7B	Staff Restroom off Stairwell	Yes	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	B.E. did not have keys to open-Viva EHS-RW
2	1	7B	Staff Restroom off Stairwell	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	B.E. was not able to open this space-Viva EHS-RW
2	1	7B	Staff Restroom off Stairwell	Yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	B.E. was not able to open this space-Viva EHS-RW
1	1	S11	Stairwell next to Classroom 7	Yes	W1	Sheetrock	Tan	None	0	0.1	Negative	None							
1	1	S11	Stairwell next to Classroom 7	Yes	W1 door	Wood	Tan	None	0	0	Negative	None							
1	1	S11	Stairwell next to Classroom 7	Yes	W2	Plaster	Tan	Flaking	29	23.3	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	1	S11	Stairwell next to Classroom 7	Yes	W3	Wood	Brown	None	0	0	Negative	None							
1	1	S11	Stairwell next to Classroom 7	Yes	W4	Plaster	Tan	None	0	32	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	

1	1	S11	Stairwell next to Classroom 7	Yes	W4 baluster	Metal	Grey	None	0	6.2	Positive	None		This material has not been sampled based on AHERA log-Viva EHS-RW					
1	1	S11	Stairwell next to Classroom 7	Yes	Newel Post	Metal	Grey	Friction	2	5	Positive	None		This material has not been sampled based on AHERA log-Viva EHS-RW					
1	1	S11	Stairwell next to Classroom 7	Yes	W4 Baseboard	Concrete	Grey	None	0	6.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	1	S11	Stairwell next to Classroom 7	Yes	W4 riser	Metal	Grey	Chipping	4	3	Positive	None		This material has not been sampled based on AHERA log-Viva EHS-RW					
2	1	S11	Stairwell next to Classroom 7	Yes	Ceiling	Plaster	Tan	None	0	32	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2	1	S11	Stairwell next to Classroom 7	Yes	Floor	Concrete	Brown	None	0	N/A	N/A			N/A					
2	1	6	Classroom 6	Yes	W1	Plaster	Tan	Chipping	10	26.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Changed from sheetrock to plaster - Viva EHS - 9/30/21 - EJS
2	1	6	Classroom 6	Yes	W2	Plaster	Tan	Chipping	5	11.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Changed from sheetrock to plaster - Viva EHS - 9/30/21 - EJS
2	1	6	Classroom 6	Yes	W3	Plaster	Tan	Efflorescence	20	28.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Changed from sheetrock to plaster and flaking to efflorescence - Viva EHS - 9/30/21 - EJS
2	1	6	Classroom 6	Yes	W4	Plaster	Tan	Flaking	5	24.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Changed from sheetrock to plaster and 45SF to 5SF - Viva EHS - 9/30/21 - EJS
2	1	6	Classroom 6	Yes	Ceiling	Plaster	Tan	Chipping	20	33	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Changed from sheetrock to plaster - Viva EHS - 9/30/21 - EJS
2	1	6	Classroom 6	yes	Radiator	Metal	Grey	Flaking	3	1.8	Positive			This material has not been sampled based on AHERA log-Viva EHS-RW					
2	1	6	Classroom 6	yes	Pipe	Metal	Tan	Chipping	5	21.1	Positive			This material has not been sampled based on AHERA log-Viva EHS-RW					
2	1	6	Classroom 6	Yes	Floor	Wood	Tan	Friction	5	0	Negative								
2	1	5	Classroom 5	Yes	W1	Plaster	Tan	Chipping	15	21.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Changed from sheetrock to plaster - Viva EHS - 9/30/21 - EJS
2	1	5	Classroom 5	Yes	W2	Plaster	Tan	Flaking	5	13.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Changed from sheetrock to plaster - Viva EHS - 9/30/21 - EJS
2	1	5	Classroom 5	Yes	W3	Plaster	Tan	Flaking	25	19.3	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Changed from sheetrock to plaster - Viva EHS - 9/30/21 - EJS
2	1	5	Classroom 5	Yes	W4	Plaster	Tan	Flaking	10	19.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Changed from sheetrock to plaster - Viva EHS - 9/30/21 - EJS
2	1	5	Classroom 5	Yes	Ceiling	Plaster	Tan	Chipping	5	0.4	Negative								Changed from sheetrock to plaster - Viva EHS - 9/30/21 - EJS
2	1	5	Classroom 5	Yes	Floor	Wood	Brown	Friction	5	0.1	Negative								
2	1	4	Classroom 4	Yes	W1	Plaster	Tan	Cracking	10	12.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Changed from sheetrock to plaster - Viva EHS - 9/30/21 - EJS
2	1	4	Classroom 4	Yes	W2	Sheetrock	Tan	Chipping	5	0.1	Negative								
2	1	4	Classroom 4	Yes	W3	Plaster	Tan	Chipping	10	28.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Changed from sheetrock to plaster - Viva EHS - 9/30/21 - EJS
2	1	4	Classroom 4	Yes	W4	Plaster	Tan	Chipping	5	26.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Changed from sheetrock to plaster - Viva EHS - 9/30/21 - EJS
2	1	4	Classroom 4	Yes	Ceiling	Plaster	White	Flaking	20	25.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Changed from sheetrock to plaster - Viva EHS - 9/30/21 - EJS
2	1	4	Classroom 4	Yes	Floor	Wood	Tan	Friction	5	0.1	Negative								
2	1	4A	Classroom 4 Girl's Restroom	Yes	W1	Sheetrock	White	Friction	2	0.1	Negative								
2	1	4A	Classroom 4 Girl's Restroom	Yes	W2	Plaster	White	Friction	10	14	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Changed from sheetrock to plaster and reading (0) to (14) - Viva EHS - 9/30/21 - EJS
2	1	4A	Classroom 4 Girl's Restroom	Yes	W3	Sheetrock	White	None	0	0	Negative								Changed from sheetrock to plaster - Viva EHS - 9/30/21 - EJS
2	1	4A	Classroom 4 Girl's Restroom	Yes	W4	Sheetrock	White	Friction	5	0	Negative								
2	1	4A	Classroom 4 Girl's Restroom	Yes	Ceiling	Sheetrock	White	None	0	0	Negative								
2	1	4A	Classroom 4 Girl's Restroom	Yes	Floor	Wood	Tan	None	0	0.1	Negative								
2	1	4B	Classroom 4 Storage Closet	Yes	W1	Sheetrock	White	None	0	0	Negative								Added - Viva EHS - 9/30/21 - EJS
2	1	4B	Classroom 4 Storage Closet	Yes	W2	Sheetrock	White	None	0	0	Negative								Added - Viva EHS - 9/30/21 - EJS
2	1	4B	Classroom 4 Storage Closet	Yes	W3	Sheetrock	White	Cracking	2	0	Negative								Added - Viva EHS - 9/30/21 - EJS
2	1	4B	Classroom 4 Storage Closet	Yes	W4	Plaster	White	Efflorescence	5	27.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Added - Viva EHS - 9/30/21 - EJS
2	1	4B	Classroom 4 Storage Closet	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	Added - Viva EHS - 9/30/21 - EJS
2	1	4B	Classroom 4 Storage Closet	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A								Added - Viva EHS - 9/30/21 - EJS
2	1	3	Classroom 3	Yes	W1	Plaster	White	Chipping	25	21.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Changed from sheetrock to plaster - Viva EHS - 9/30/21 - EJS
2	1	3	Classroom 3	Yes	W2	Plaster	Tan	Chipping	10	28.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Changed from sheetrock to plaster - Viva EHS - 9/30/21 - EJS
2	1	3	Classroom 3	Yes	W2	Wood	Brown	N/A	N/A	N/A	N/A								Added - Viva EHS - 9/30/21 - EJS
2	1	3	Classroom 3	Yes	W3	Plaster	Tan	Chipping	5	28.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Changed from sheetrock to plaster and reading from (0.2) to (28.8) - Viva EHS - 9/30/21 - EJS
2	1	3	Classroom 3	Yes	W4	Plaster	Tan	Chipping	10	29.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Changed from sheetrock to plaster and reading from (-0.2) to (29.9) - Viva EHS - 9/30/21 - EJS
2	1	3	Classroom 3	Yes	W4	Wood	Brown	None	0	N/A	N/A								Added - Viva EHS - 9/30/21 - EJS
2	1	3	Classroom 3	Yes	Radiator	Metal	Grey	Chipping	5	28.5	Positive			This material has not been sampled based on AHERA log-Viva EHS-RW					Added - Viva EHS - 9/30/21 - EJS
2	1	3	Classroom 3	Yes	Ceiling	Plaster	White	Chipping	25	19.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Changed from sheetrock to plaster - Viva EHS - 9/30/21 - EJS
2	1	3	Classroom 3	Yes	Floor	Wood	Brown	Friction	10	0.1	Negative								
2	1	2	Classroom 2	Yes	W1	Plaster	Tan	Flaking	5	24.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Changed from sheetrock to plaster - Viva EHS - 9/30/21 - EJS
2	1	2	Classroom 2	Yes	W2	Plaster	Tan	Flaking	5	13.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Changed from sheetrock to plaster and reading from (0) to (13.7) - Viva EHS - 9/30/21 - EJS
2	1	2	Classroom 2	Yes	W3	Plaster	Tan	Flaking	10	10.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Changed from sheetrock to plaster - Viva EHS - 9/30/21 - EJS

2	1	2	Classroom 2	Yes	W4	Plaster	Tan	Flaking	5	17.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Changed from sheetrock to plaster and reading (0) to (17.9) - Viva EHS - 9/30/21 - EJS
2	1	2	Classroom 2	Yes	Ceiling	Plaster	Tan	Chipping	15	27.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Changed from sheetrock to plaster - Viva EHS - 9/30/21 - EJS
2	1	2	Classroom 2	Yes	Floor	Wood	Tan	Friction	5	0.1	Negative								
				Yes	Radiator	Metal	Silver	Chipping	10	33.7	Positive			This material has not been sampled based on AHERA log-Viva EHS-RW					Added - Viva EHS - 9/30/21 - EJS
2	1	2	Classroom 2																
2	1	2A	Classroom 4 Boy's Restroom	Yes	W1	Sheetrock	White	Friction	3	0.1	Negative								
2	1	2A	Classroom 4 Boy's Restroom	Yes	W2	Sheetrock	White	None	0	0.1	Negative								
2	1	2A	Classroom 4 Boy's Restroom	Yes	W3	Sheetrock	White	None	0	0	Negative								
2	1	2A	Classroom 4 Boy's Restroom	Yes	W4	Sheetrock	White	None	0	0.1	Negative								
2	1	2A	Classroom 4 Boy's Restroom	Yes	Ceiling	Sheetrock	White	None	0	0	Negative								
2	1	2A	Classroom 4 Boy's Restroom	Yes	Floor	Wood	Tan	None	0	N/A	N/A								
2	1	1	Classroom 1	Yes	W1	Plaster	Tan	None	0	25.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Changed from sheetrock to plaster and flaking to none - Viva EHS - 9/30/21 - EJS
2	1	1	Classroom 1	Yes	W2	Plaster	Tan	None	0	26.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Changed from sheetrock to plaster and flaking to none - Viva EHS - 9/30/21 - EJS
2	1	1	Classroom 1	Yes	W3	Plaster	Tan	None	0	24.3	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Changed from sheetrock to plaster and flaking to none - Viva EHS - 9/30/21 - EJS
2	1	1	Classroom 1	Yes	W4	Plaster	Tan	None	0	22.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Changed from sheetrock to plaster and flaking to none - Viva EHS - 9/30/21 - EJS
2	1	1	Classroom 1	Yes	Ceiling	Plaster	White	Efflorescence	15	20.3	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Changed from sheetrock to plaster and chipping to efflorescence - Viva EHS - 9/30/21 - EJS
2	1	1	Classroom 1	Yes	Floor	Wood	Brown	Friction	5	0.1	Negative								
1	1	H11	Hallway from Classrooms 2 to 6	Yes	W1	Sheetrock	Tan	Friction	5	0.2	Negative	None							
1	1	H11	Hallway from Classrooms 2 to 6	Yes	W2	Plaster	Tan	Friction	5	21.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	1	H11	Hallway from Classrooms 2 to 6	Yes	W3	Plaster	Tan	Chipping	4	24.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	1	H11	Hallway from Classrooms 2 to 6	Yes	W4	Plaster	Tan	Friction	12	26	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2	1	H11	Hallway from Classrooms 2 to 6	Yes	Ceiling	Plaster	White	Flaking	10	36	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2	1	H11	Hallway from Classrooms 2 to 6	Yes	Floor	Concrete	Brown	Friction	12	0.2	Negative								
1	1	S12	Stair near Classroom 2	Yes	W1	Sheetrock	Tan	None	0	0.1	Negative	None							
1	1	S12	Stair near Classroom 2	Yes	W2	Plaster	Tan	None	0	23.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	1	S12	Stair near Classroom 2	Yes	W2 post	Metal	Brown	Chipping	18	22.2	Positive	None		This material has not been sampled based on AHERA log-Viva EHS-RW					
1	1	S12	Stair near Classroom 2	Yes	W2 riser	Metal	Grey	Chipping	1	10.8	Positive	None		This material has not been sampled based on AHERA log-Viva EHS-RW					
1	1	S12	Stair near Classroom 2	Yes	W2 stringer	Metal	Grey	Chipping	1	1.1	Positive	None		This material has not been sampled based on AHERA log-Viva EHS-RW					w/ concrete baseboard
1	1	S12	Stair near Classroom 2	Yes	W3	Plaster	Tan	None	0	4.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	1	S12	Stair near Classroom 2	Yes	W3 radiator	Metal	Grey	Cracking	1	5.8	Positive	None		This material has not been sampled based on AHERA log-Viva EHS-RW					
1	1	S12	Stair near Classroom 2	Yes	W4	Plaster	Tan	Chipping	6	12.3	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2	1	S12	Stair near Classroom 2	Yes	Ceiling	Plaster	White	None	0	24.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2	1	S12	Stair near Classroom 2	Yes	Floor	Concrete	Unpainted												
1	2	20	Classroom 20	Yes	W1	Plaster	Tan	Flaking	29	34	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	2	20	Classroom 20	Yes	W1 chalk board	Wood	Brown	Chipping	37	0.1	Negative	None	0						Frame and tray
1	2	20	Classroom 20	Yes	W1 baseboard	Wood	Brown	Chipping	6 LF	0.2	Negative	None							foling wall
1	2	20	Classroom 20	Yes	W2	Wood	Brown	Varnish	None	N/A	N/A								
1	2	20	Classroom 20	Yes	W3	Plaster	Tan	Flaking	48	12.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	2	20	Classroom 20	Yes	W2	Wood	Brown	None	0	N/A	N/A								
1	2	20	Classroom 20	Yes	W3 chalk board	Wood	Brown	Chipping	14	0.9	Positive	None	0	This material has not been sampled based on AHERA log-Viva EHS-RW					Frame and tray W3 and W4
1	2	20	Classroom 20	Yes	W3 sill w chair rail	Wood	Brown	Chipping	15	5.2	Positive			This material has not been sampled based on AHERA log-Viva EHS-RW					
1	2	20	Classroom 20	Yes	W3 radiator pipe	Metal	Silver	Chipping	70	1.6	Positive			This material has not been sampled based on AHERA log-Viva EHS-RW					
1	2	20	Classroom 20	Yes	W3 radiator cover	Metal	Silver	Chipping	60	0.1	Negative								
1	2	20	Classroom 20	Yes	W3 baseboard	Wood	Brown	Chipping	8 LF	0.1	Negative	None							foling wall
1	2	20	Classroom 20	Yes	W4	Plaster	Tan	Flaking	52	39	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	2	20	Classroom 20	Yes	W4 radiator pipe	Metal	Silver	Chipping	55	16.6	Positive			This material has not been sampled based on AHERA log-Viva EHS-RW					
1	2	20	Classroom 20	Yes	W4 radiator cover	Metal	Silver	Chipping	45	0.2	Negative								
1	2	20	Classroom 20	Yes	W4 baseboard	Wood	Brown	Chipping	6 LF	0.1	Negative	None							foling wall
1	2	20	Classroom 20	Yes	W4 sill w chair rail	Wood	Brown	Chipping	20	7.4	Positive			This material has not been sampled based on AHERA log-Viva EHS-RW					
1	2	20	Classroom 20	Yes	Ceiling	N/A	White	N/A	N/A	N/A	N/A								drop panels
1	2	20	Classroom 20	Yes	Floor	Wood	Brown	None	0	N/A	N/A								
1	2	20D	Classroom 20 Closet	Yes	W1	Plaster	Tan	Flaking	1	31	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	

1	2	20D	Classroom 20 Closet	Yes	W2	Plaster	Tan	Flaking	1	34	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	2	20D	Classroom 20 Closet	Yes	W3	Plaster	Tan	Flaking	2	23	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	2	20D	Classroom 20 Closet	Yes	W4	Plaster	Tan	Flaking	1	33	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	2	20D	Classroom 20 Closet	Yes	Ceiling	Plaster	White	Cracking	6	2.3	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	drop panels
1	2	20D	Classroom 20 Closet	Yes	Floor	Wood	Brown	None	0	N/A	N/A								
1	2	19	Library	Yes	W1	Plaster	Blue	Flaking	0	35	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	2	19	Library	Yes	W1 chalk board	Wood	Brown	Chipping	3	0	Negative								
1	2	19	Library	Yes	W2	Plaster	Blue	Flaking	0	23	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	2	19	Library	Yes	W2	Wood	Brown	None	0	N/A	N/A								Added - Viva EHS - 10/1/21 - EJS
1	2	19	Library	Yes	W3	Plaster	Blue	Flaking	0	23.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	2	19	Library	Yes	W3 radiator	Metal	Silver	Chipping	4	12.2	Positive			This material has not been sampled based on AHERA log-Viva EHS-RW					
1	2	19	Library	Yes	W3 sill w chair rail	Wood	Brown	Chipping	3	7.2	Positive			This material has not been sampled based on AHERA log-Viva EHS-RW					
1	2	19	Library	Yes	W4	Plaster	Blue	Flaking	0	25	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	2	19	Library	yes	W4 baseboard	Wood	Brown	Chipping	2 LF	0.2	Negative								baseboard W1-W3 no Damage
1	2	19	Library	Yes	Ceiling	N/A	White	N/A	N/A	N/A	N/A								drop panels
1	2	19	Library	Yes	Floor	Wood	Brown	None	0	N/A	N/A								
1	2	19	Library	yes	W4 wanscoat	Wood	White	None	0	24.4	Positive			This material has not been sampled based on AHERA log-Viva EHS-RW					
1	2	19	Library	Yes	Ceiling	N/A	White	N/A	N/A	N/A	N/A								drop panels
1	2	19	Library	Yes	Floor	Wood	Brown	None	0	N/A	N/A								
1	2	19A	Library Closet	Yes	W1	Plaster	White	Flaking	8	28	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	fresh Paint
1	2	19A	Library Closet	Yes	W1 baseboard	Wood	Brown	Chipping	1 LF	12.2	Positive			This material has not been sampled based on AHERA log-Viva EHS-RW					fresh Paint
1	2	19A	Library Closet	Yes	W2	Plaster	Tan	Chipping	2	32	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	fresh Paint
1	2	19A	Library Closet	Yes	W3	Plaster	Tan	Chipping	1	31	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	fresh Paint
1	2	19A	Library Closet	Yes	W4	Wood	Brown	None	0	N/A	N/A								varnish
1	2	19A	Library Closet	Yes	Ceiling	Plaster	White	Flaking	2	2.3	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	fresh Paint
1	2	19A	Library Closet	Yes	Floor	Wood	Brown	None	0	N/A	N/A								
1	2	20C	Counselor's Office across from Library	Yes	W1	Plaster	Tan	Flaking	5	24.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	2	20C	Counselor's Office across from Library	Yes	W1 baseboard	Wood	Brown	Chipping	1 LF	0.1	Negative								fresh Paint
1	2	20C	Counselor's Office across from Library	Yes	W2	Plaster	Tan	Chipping	2	23.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	2	20C	Counselor's Office across from Library	Yes	W2 shelf	Wood	Brown	Chipping	1	0.1	Negative								bookcase
1	2	20C	Counselor's Office across from Library	Yes	W3	Plaster	Tan	Chipping	2	22.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	2	20C	Counselor's Office across from Library	Yes	W3 sill w chair rail	Wood	Brown	Chipping	1	0.1	Negative								
1	2	20C	Counselor's Office across from Library	Yes	W4	Plaster	Tan	Chipping	2	27.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	2	20C	Counselor's Office across from Library	Yes	W4 baseboard	Wood	Brown	Chipping	2 LF	0.2	Negative								
1	2	20C	Counselor's Office across from Library	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A								panel
1	2	20C	Counselor's Office across from Library	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A								
1	2	18	Storeroom next to Library	Yes	W1	Plaster	Tan	Chipping	2	32	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	2	18	Storeroom next to Library	Yes	W2	Plaster	Tan	Flaking	12	31	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	2	18	Storeroom next to Library	Yes	W2 sill	Wood	Brown	Chipping	8	11.7	Positive			This material has not been sampled based on AHERA log-Viva EHS-RW					W2 and W3
1	2	18	Storeroom next to Library	Yes	W2 radiator	Metal	Gray	Flaking	20	21.2	Positive			This material has not been sampled based on AHERA log-Viva EHS-RW					W2 and W3
1	2	18	Storeroom next to Library	Yes	W2 cover	Metal	Gray	Chipping	20	0.1	Negative								W2 and W3
1	2	18	Storeroom next to Library	Yes	W3	Plaster	Tan	Chipping	11	25.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	2	18	Storeroom next to Library	Yes	W4	Wood	Brown	Chipping	11	0.23	Negative								foding Wall
1	2	18	Storeroom next to Library	Yes	Ceiling	N/A	White	None	0	N/A	Negative								ceiling panels
1	2	18	Storeroom next to Library	Yes	Floor	Wood	Brown	None	0	N/A	N/A								
1	2	18A	Server Closet next to Storeroom	Yes	W1	Plaster	Tan	Chipping	5	32	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	2	18A	Server Closet next to Storeroom	Yes	W2	Plaster	Tan	Chipping	4	32.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	2	18A	Server Closet next to Storeroom	Yes	W3	Plaster	Tan	Chipping	2	19.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	2	18A	Server Closet next to Storeroom	Yes	W4	Plaster	Tan	Chipping	1	20.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	2	18A	Server Closet next to Storeroom	Yes	Ceiling	Plaster	Tan	Efflorescence	11	28.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	2	18A	Server Closet next to Storeroom	Yes	Floor	Wood	Brown	None	0	N/A	N/A								
1	2	20A	Teacher's Lounge	Yes	W1	Sheetrock	Tan	Chipping	2	0.1	Negative								
1	2	20A	Teacher's Lounge	Yes	W2	Plaster	Tan	Efflorescence	11	28.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	2	20A	Teacher's Lounge	Yes	W3	Plaster	Tan	Efflorescence	31	25.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	2	20A	Teacher's Lounge	Yes	W4	Plaster	Tan	Chipping	1	23.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	2	20A	Teacher's Lounge	Yes	Ceiling	Plaster	White	Efflorescence	14	37	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	2	20A	Teacher's Lounge	Yes	Floor	Wood	Brown	None	0	N/A	N/A								
1	2	20B	Teacher's Lounge Server Room	No	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	No access. B.E. did not have keys to open-Viva EHS-RW
1	2	20B	Teacher's Lounge Server Room	No	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	No access. B.E. did not have keys to open-Viva EHS-RW
1	2	20B	Teacher's Lounge Server Room	No	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	No access. B.E. did not have keys to open-Viva EHS-RW
1	2	20B	Teacher's Lounge Server Room	No	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	No access. B.E. did not have keys to open-Viva EHS-RW
1	2	20B	Teacher's Lounge Server Room	No	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	No access. B.E. did not have keys to open-Viva EHS-RW
1	2	20B	Teacher's Lounge Server Room	No	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	No access. B.E. did not have keys to open-Viva EHS-RW

1	2	S20	Stairwell next to Classroom 20	Yes	W1	Sheetrock	White	None	0	0.1	Negative								
1	2	S20	Stairwell next to Classroom 20	Yes	W2	Sheetrock	Tan	None	0	0.2	Negative								
1	2	S20	Stairwell next to Classroom 20	Yes	W2	Wood	Brown	None	0	0.2	Negative								
1	2	S20	Stairwell next to Classroom 20	Yes	W3	Sheetrock	Tan	None	0	0.3	Negative								
1	2	S20	Stairwell next to Classroom 20	Yes	W4	Sheetrock	Tan	None	0	0.2	Negative								
1	2	S20	Stairwell next to Classroom 20	Yes	W4	Metal	Grey	None	0	0.1	Negative								
1	2	S20	Stairwell next to Classroom 20	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A								Ceiling tile present.-Viva EHS-RW
1	2	S20	Stairwell next to Classroom 20	Yes	Floor	Wood	Brown	None	0	N/A	N/A								
1	2	H20	Hallway from Classrooms 20 to 18	Yes	W1	Wood	Tan	None	0	0.1	Negative								
1	2	H20	Hallway from Classrooms 20 to 18	Yes	W2	Plaster	Tan	Chipping	2	34	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	2	H20	Hallway from Classrooms 20 to 18	Yes	W2	Wood	Tan	Chipping	2	1	Positive			This material has not been sampled based on AHERA log-Viva EHS-RW					Bulletin Board Frame
1	2	H20	Hallway from Classrooms 20 to 18	Yes	W2 radiator	Metal	Grey	Chipping	2	9.9	Positive			This material has not been sampled based on AHERA log-Viva EHS-RW					Bulletin Board Frame
1	2	H20	Hallway from Classrooms 20 to 18	Yes	W3	Wood	Tan	None	0	0.1	Negative								
1	2	H20	Hallway from Classrooms 20 to 18	Yes	W4	Plaster	Tan	Chipping	11	25.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	2	H20	Hallway from Classrooms 20 to 18	Yes	W4	Wood	Brown	Chipping	12	0.3	Negative								Chair Rail/ Sill
1	2	H20	Hallway from Classrooms 20 to 18	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A								ceiling panels
1	2	H20	Hallway from Classrooms 20 to 18	Yes	Floor	Wood	Brown	None	0	N/A	N/A								Changed from concrete to wood and reading from (28.8) to (N/A) - Viva EHS - 10/1/21 - EJS
1	2	17C	Book Closet near Classroom 18	Yes	W1	Plaster	Tan	Chipping	3	17.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Changed from 11SF efflorescence to 3SF chipping and reading (28.8) to (17.9) - Viva EHS - 10/1/21 - EJS
1	2	17C	Book Closet near Classroom 18	Yes	W2	Plaster	Tan	No Access	No Access	No Access	No Access								Unaccessable due to crowding - Viva EHS - 10/1/21 - EJS
1	2	17C	Book Closet near Classroom 18	Yes	W3	Plaster	Tan	Chipping	3	15.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Changed from 11SF efflorescence to 3SF chipping and reading (28.8) to (15.4) - Viva EHS - 10/1/21 - EJS
1	2	17C	Book Closet near Classroom 18	Yes	W4	Plaster	Tan	Cracking	3	22.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Changed from 11SF efflorescence to 3SF cracking and reading (28.8) to (22.6) - Viva EHS - 10/1/21 - EJS
1	2	17C	Book Closet near Classroom 18	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A								ceiling panels
2	2	17C	Book Closet near Classroom 18	Yes	Floor	Wood	Brown	None	0	N/A	N/A								
1	2	17B	Women's Staff Restroom in Stairwell near Classroom 18	Yes	W1	Plaster	Tan	None	0	N/A	N/A								
1	2	17B	Women's Staff Restroom in Stairwell near Classroom 18	Yes	W2	Plaster	Tan	None	0	N/A	N/A								
1	2	17B	Women's Staff Restroom in Stairwell near Classroom 18	Yes	W3	Plaster	Tan	Chipping	3	6.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	2	17B	Women's Staff Restroom in Stairwell near Classroom 18	Yes	W4	Plaster	Tan	Cracking	15	33.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	2	17B	Women's Staff Restroom in Stairwell near Classroom 18	Yes	Ceiling	Plaster	Tan	None	0	N/A	N/A								
2	2	17B	Women's Staff Restroom in Stairwell near Classroom 18	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A								
2	2	17B	Women's Staff Restroom in Stairwell near Classroom 19	Yes	W1	Plaster	Tan	Cracking	5	28.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2	2	17B	Women's Staff Restroom in Stairwell near Classroom 19	Yes	W2	Plaster	Tan	Cracking	5	44.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2	2	17B	Women's Staff Restroom in Stairwell near Classroom 19	Yes	W3	Plaster	Tan	Cracking	10	37.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2	2	17B	Women's Staff Restroom in Stairwell near Classroom 19	Yes	W4	Plaster	Tan	Chipping	5	38.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2	2	17B	Women's Staff Restroom in Stairwell near Classroom 19	Yes	Baseboard	Concrete	Grey	Chipping	15 LF	1.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2	2	17B	Women's Staff Restroom in Stairwell near Classroom 19	Yes	Radiator	Metal	Grey	Chipping	5	5.6	Positive			This material has not been sampled based on AHERA log-Viva EHS-RW					
2	2	17B	Women's Staff Restroom in Stairwell near Classroom 19	Yes	Ceiling	Plaster	Tan	None	0	N/A	N/A								
2	2	17B	Women's Staff Restroom in Stairwell near Classroom 19	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A								
1	2	17A	Nurse's Office	Yes	W1	Plaster	Tan	Chipping	10	34	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	2	17A	Nurse's Office	Yes	W2	Plaster	Tan	Chipping	10	25.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	2	17A	Nurse's Office	Yes	W3	Plaster	Tan	Chipping	20	26.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	2	17A	Nurse's Office	Yes	W4	Plaster	Tan	Flaking	25	13.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	2	17A	Nurse's Office	Yes	Ceiling	Plaster	Tan	Chipping	2	19.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	2	17A	Nurse's Office	Yes	Floor	Wood	Brown	None	0	N/A	N/A								
1	2	17B	Nurse's Office Restroom	Yes	W1	Plaster	Tan	None	0	16.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	2	17B	Nurse's Office Restroom	Yes	W2	Plaster	Tan	Flaking	5	18.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	2	17B	Nurse's Office Restroom	Yes	W3	Plaster	Tan	None	0	19.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	2	17B	Nurse's Office Restroom	Yes	W4	Plaster	Tan	Efflorescence	8	13.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	2	17B	Nurse's Office Restroom	Yes	Ceiling	Concrete	Tan	Cracking	15	12.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	2	17B	Nurse's Office Restroom	Yes	Floor	Concrete	Grey	Chipping	10	0.4	Negative								
1	2	S21	Stairwell next to Classroom 17	Yes	W1	Wood	White	None	0	0	Negative								
1	2	S21	Stairwell next to Classroom 17	Yes	W2	Plaster	Tan	None	0	23	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	2	S21	Stairwell next to Classroom 17	Yes	W2	Plaster	White	None	0	23	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	2	S21	Stairwell next to Classroom 17	Yes	W2 riser	Metal	Grey	None	0	5	Positive			This material has not been sampled based on AHERA log-Viva EHS-RW					
1	2	S21	Stairwell next to Classroom 17	Yes	W3	Plaster	Tan	None	0	36	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	2	S21	Stairwell next to Classroom 17	Yes	W4	Plaster	Tan	Flaking	20	23.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	2	S21	Stairwell next to Classroom 17	Yes	Ceiling	Plaster	White	None	0	26	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	2	S21	Stairwell next to Classroom 17	Yes	Floor	Concrete	Grey	None	0	N/A	N/A								

														This material has not been sampled based on AHERA log-Viva EHS-RW					
1	2	S21	Stairwell next to Classroom 17	Yes	Newel Post	Metal	Grey	Chipping	2	2.5	Positive								
1	2	17	Classroom 17	Yes	W1	Plaster	Tan	Chipping	6	22.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	2	17	Classroom 17	Yes	W2	Plaster	Tan	Chipping	10	12.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	2	17	Classroom 17	Yes	W3	Plaster	Tan	Efflorescence	25	27.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	2	17	Classroom 17	Yes	W4	Plaster	Tan	Chipping	2	26.3	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	2	17	Classroom 17	Yes	Ceiling	Plaster	White	Flaking	8	31	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2	2	17	Classroom 17	Yes	Floor	Wood	Brown	None	0	N/A	N/A								
				Yes	Radiator	Metal	Silver	Chipping	5	1.2	Positive			This material has not been sampled based on AHERA log-Viva EHS-RW					
2	2	17	Classroom 17																
1	2	16	Classroom 16	Yes	W1	Plaster	Tan	Chipping	10	23.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	2	16	Classroom 16	Yes	W2	Plaster	Tan	Chipping	14	13.3	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	2	16	Classroom 16	Yes	W3	Plaster	Tan	Efflorescence	20	26.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	2	16	Classroom 16	Yes	W4	Wood Partition	Brown	None	0	N/A	N/A								
1	2	16	Classroom 16	Yes	Ceiling	Plaster	White	Cracking	8	21.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2	2	16	Classroom 16	Yes	Floor	Wood	Brown	None	0	N/A	N/A								
				Yes	Radiator	Metal	Silver	Chipping	5	38.6	Positive			This material has not been sampled based on AHERA log-Viva EHS-RW					
2	2	16	Classroom 16																
1	2	16A	Custodial Closet next to Classroom 16	Yes	W1	Sheetrock	White	Chipping	3	0	Negative								
1	2	16A	Custodial Closet next to Classroom 16	Yes	W2	Plaster	White	Cracking	10	24.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	2	16A	Custodial Closet next to Classroom 16	Yes	W3	Plaster	White	Cracking	10	30.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	2	16A	Custodial Closet next to Classroom 16	Yes	W4	Plaster	White	Cracking	10	29.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	2	16A	Custodial Closet next to Classroom 16	Yes	Ceiling	Plaster	White	None	0	N/A	N/A								
2	2	16A	Custodial Closet next to Classroom 16	No	Floor	Concrete	Red	Chipping	10	0.02	Negative								
2	2	16C	Hall Closet across from Classroom 17	Yes	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	No access. B.E. did not have keys to open-Viva EHS-RW
2	2	16C	Hall Closet across from Classroom 17	Yes	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	No access. B.E. did not have keys to open-Viva EHS-RW
2	2	16C	Hall Closet across from Classroom 17	Yes	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	No access. B.E. did not have keys to open-Viva EHS-RW
2	2	16C	Hall Closet across from Classroom 17	Yes	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	No access. B.E. did not have keys to open-Viva EHS-RW
2	2	16C	Hall Closet across from Classroom 17	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	No access. B.E. did not have keys to open-Viva EHS-RW
2	2	16C	Hall Closet across from Classroom 17	No	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	No access. B.E. did not have keys to open-Viva EHS-RW
1	2	15	Classroom 15	Yes	W1	Plaster	Tan	Chipping	13	26.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	2	15	Classroom 15	Yes	W2	Plaster	Tan	Chipping	7	16.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	2	15	Classroom 15	Yes	W3	Plaster	Tan	Efflorescence	15	25.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	2	15	Classroom 15	Yes	W4	Plaster	Tan	Flaking	13	31	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	2	15	Classroom 15	Yes	Ceiling	Plaster	White	Chipping	10	17.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2	2	15	Classroom 15	Yes	Floor	Wood	Brown	None	0	N/A	N/A								
1	2	14	Classroom 14	Yes	W1	Plaster	Tan	Chipping	20	20.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	2	14	Classroom 14	Yes	W2	Wood Partition	Brown	None	0	N/A	N/A								
1	2	14	Classroom 14	Yes	W3	Plaster	Tan	Efflorescence	16	21	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	2	14	Classroom 14	Yes	W4	Plaster	Tan	Flaking	12	21.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	2	14	Classroom 14	Yes	W4	Wood	Brown	None	0	N/A	N/A								Partition. Added - Viva EHS - 10/1/21 - EJS
1	2	14	Classroom 14	Yes	Ceiling	Plaster	White	Chipping	24	22.3	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2	2	14	Classroom 14	Yes	Floor	Wood	Brown	None	0	N/A	N/A								
				Yes	Radiator	Metal	Silver	Chipping	8	25.8	Positive			This material has not been sampled based on AHERA log-Viva EHS-RW					
2	2	14	Classroom 14																
1	2	13	Classroom 13	Yes	W1	Plaster	Tan	Chipping	6	16.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	2	13	Classroom 13	Yes	W2	Plaster	Tan	Chipping	2	10.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	2	13	Classroom 13	Yes	W3	Plaster	Tan	Flaking	12	19.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	2	13	Classroom 13	Yes	W4	Plaster	Tan	Chipping	2	24.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	2	13	Classroom 13	Yes	Ceiling	Plaster	White	Moisture Damage	3	17.3	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2	2	13	Classroom 13	Yes	Floor	Wood	Brown	None	0	N/A	N/A								
2	2	13	Classroom 13	Yes	Radiator	Metal	Silver	Chipping	4	1.3	Positive			This material has					
1	2	12	Classroom 12	Yes	W1	Plaster	Tan	Chipping	20	15.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	2	12	Classroom 12	Yes	W2	Plaster	Tan	Chipping	6	21	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	2	12	Classroom 12	Yes	W2	Wood	Brown	None	0	N/A	N/A								Partition. Added - Viva EHS - 10/1/21 - EJS
1	2	12	Classroom 12	Yes	W3	Plaster	Tan	Chipping	16	23.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	2	12	Classroom 12	Yes	W4	Plaster	Tan	Chipping	12	22.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	2	12	Classroom 12	Yes	Ceiling	Plaster	White	Flaking	4	33	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2	2	12	Classroom 12	Yes	Floor	Wood	Brown	None	0	N/A	N/A								
1	2	12B	Classroom 12 closet	Yes	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Unaccessable due to crowding - Viva EHS - 10/1/21 - EJS
1	2	12B	Classroom 12 closet	Yes	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Unaccessable due to crowding - Viva EHS - 10/1/21 - EJS
1	2	12B	Classroom 12 closet	Yes	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Unaccessable due to crowding - Viva EHS - 10/1/21 - EJS
1	2	12B	Classroom 12 closet	Yes	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Unaccessable due to crowding - Viva EHS - 10/1/21 - EJS
1	2	12B	Classroom 12 closet	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Unaccessable due to crowding - Viva EHS - 10/1/21 - EJS
2	2	12B	Classroom 12 closet	Yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Unaccessable due to crowding - Viva EHS - 10/1/21 - EJS
1	2	S22	Stairwell next to Classroom 12	Yes	W1	Plaster	Tan	None	0	26.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	2	S22	Stairwell next to Classroom 12	Yes	W2	Plaster	Tan	Cracking	2	24.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	

1	2	S22	Stairwell next to Classroom 12	Yes	W2 riser	Metal	Grey	Chipping	3	5.8	Positive			This material has not been sampled based on AHERA log-Viva EHS-RW					
1	2	S22	Stairwell next to Classroom 12	Yes	W2 Stringer	Metal	Grey	Chipping	4	2.1	Positive			This material has not been sampled based on AHERA log-Viva EHS-RW					
1	2	S22	Stairwell next to Classroom 12	Yes	W3	Plaster	Tan	Cracking	4	22.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	2	S22	Stairwell next to Classroom 12	Yes	W4	Plaster	Tan	None	0	24.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	2	S22	Stairwell next to Classroom 12	Yes	Ceiling	Plaster	White	Flaking	10	29.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2	2	S22	Stairwell next to Classroom 12	Yes	Floor	Concrete	Grey	None	0	N/A	N/A								
1	2	12A	Speech Office in Stairwell Landing near Classroom 12	Yes	W1	Plaster	Tan	Cracking	2	20.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	storage used for speech office
1	2	12A	Speech Office in Stairwell Landing near Classroom 12	Yes	W1	Concrete	Blue	Chipping	24	1.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Baseboards W1-W4
1	2	12A	Speech Office in Stairwell Landing near Classroom 12	Yes	W2	Plaster	Tan	Chipping	10	25.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	2	12A	Speech Office in Stairwell Landing near Classroom 12	Yes	W3	Plaster	Tan	Flaking	6	14.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	2	12A	Speech Office in Stairwell Landing near Classroom 12	Yes	W3 radiator	Metal	Gray	Flaking	16	4.8	Positive			This material has not been sampled based on AHERA log-Viva EHS-RW					
1	2	12A	Speech Office in Stairwell Landing near Classroom 12	Yes	W4	Plaster	Tan	Cracking	8	21.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	2	12A	Speech Office in Stairwell Landing near Classroom 12	Yes	Ceiling	Plaster	Tan	Flaking	3	33	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2	2	12A	Speech Office in Stairwell Landing near Classroom 12	Yes	Floor	Concrete	Grey	None	0	N/A	N/A								
1	2	H21	Hallway from Classrooms 13 to 17	Yes	W1	Wood	White	None	0	0	Negative								
1	2	H21	Hallway from Classrooms 13 to 17	Yes	W2	Plaster	Tan	Chipping	10	28.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	2	H21	Hallway from Classrooms 13 to 17	Yes	W3	Plaster	Tan	Chipping	4	23.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	2	H21	Hallway from Classrooms 13 to 17	Yes	W4	Plaster	Tan	Chipping	5	36	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	2	H21	Hallway from Classrooms 13 to 17	Yes	Ceiling	Plaster	White	Chipping	20	30	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2	2	H21	Hallway from Classrooms 13 to 17	Yes	Floor	Concrete	Grey	None	0	N/A	N/A								
2	2	H21	Hallway from Classrooms 13 to 17	Yes	Baseboard	Concrete	Grey	Chipping	6 LF	1.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	B	H01	Hallway next to Kitchen	Yes	W1	Concrete	Tan	Flaking	25	0.02	Negative								Changed tan brick to tan concrete and reading from (10.8) to (.02) - Viva EHS - 9/30/21 - EJS
1	B	H01	Hallway next to Kitchen	Yes	W1	Concrete	White	Flaking	25	0	Negative								Added - Viva EHS - 9/30/21 - EJS
1	B	H01	Hallway next to Kitchen	Yes	W2	Concrete	White	Flaking	20	1.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Changed tan brick to tan concrete and reading from (14.4) to (1.1) - Viva EHS - 9/30/21 - EJS
1	B	H01	Hallway next to Kitchen	Yes	W3	Concrete	Tan	Chipping	40	17.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Changed tan brick to tan concrete and reading from (17.1) to (30.5) - Viva EHS - 9/30/21 - EJS
1	B	H01	Hallway next to Kitchen	Yes	W3	Brick	White	Chipping	5	7.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Added - Viva EHS - 9/30/21 - EJS
1	B	H01	Hallway next to Kitchen	Yes	W4	Brick	Tan	Chipping	100	16.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	B	H01	Hallway next to Kitchen	Yes	Ceiling	Plaster	White	Chipping	250	20.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Changed tan concrete to white wood - Viva EHS - 9/30/21 - EJS
1	B	H01	Hallway next to Kitchen	yes	Door W2	Wood	Tan	Flaking	3	10.4	Positive			This material has not been sampled based on AHERA log-Viva EHS-RW					
1	B	H01	Hallway next to Kitchen	yes	Duct Work	Metal	Tan	Flaking	20	3.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	B	H01	Hallway next to Kitchen	yes	Window Sill	Concrete	Brown	Flaking	2	14.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	B	H01	Hallway next to Kitchen	Yes	Door casing	Concrete	Brown	Cracking	2	9.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	B	S01	Stairwell next to Kitchen	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A								Changed from plaster to N/A - Viva EHS - 9/30/21 - EJS
1	B	S01	Stairwell next to Kitchen	Yes	W2	Sheetrock	White	Chipping	20	0.2	Negative								Changed from plaster to wood - Viva EHS - 9/30/21 - EJS
1	B	S01	Stairwell next to Kitchen	Yes	W3	Wood	Tan	Chipping	20	0	Negative								
1	B	S01	Stairwell next to Kitchen	Yes	W3 door Frame	Wood	Brown	None	N/A	N/A	N/A								
1	B	S01	Stairwell next to Kitchen	Yes	W4	Sheetrock	Tan	Chipping	2	0	Negative								Changed from wood to sheetrock - Viva EHS - 9/30/21 - EJS
1	B	S01	Stairwell next to Kitchen	Yes	W4	Sheetrock	White	None	N/A	N/A	N/A								Added - Viva EHS - 9/30/21 - EJS
1	B	S01	Stairwell next to Kitchen	Yes	W4 chair Rail	Wood	Tan	Chipping	15	0.2	Negative								
1	B	S01	Stairwell next to Kitchen	Yes	Ceiling	Metal	White	Flaking	15	4.7	Positive			This material has not been sampled based on AHERA log-Viva EHS-RW					
1	B	S01	Stairwell next to Kitchen	Yes	Floor	Concrete	Unpainted												
1	B	10B	Kitchen	No	W1	Plaster	Purple	None	0	21.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Changed from brick to concrete - Viva EHS - 9/30/21 - EJS
1	B	10B	Kitchen	No	W1	Wood	Purple	None	0	3.4	Positive			This material has not been sampled based on AHERA log-Viva EHS-RW					Added - Viva EHS - 9/30/21 - EJS
1	B	10B	Kitchen	No	W2	Sheetrock	Purple	None	0	0.4	Negative								Changed from brick to sheetrock - Viva EHS - 9/30/21 - EJS
1	B	10B	Kitchen	No	W3	Concrete	Purple	None	0	3.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Changed from brick to concrete - Viva EHS - 9/30/21 - EJS
1	B	10B	Kitchen	No	W4	Concrete	Purple	None	0	17.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Changed from brick to concrete - Viva EHS - 9/30/21 - EJS
1	B	10B	Kitchen	No	Ceiling	Plaster	White	None	0	5.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Above ceiling tile - Viva EHS - 9/30/21 - EJS
1	B	10B	Kitchen	No	Door - W1	Wood	Brown	Friction	0.5	5	Positive			This material has not been sampled based on AHERA log-Viva EHS-RW					
1	B	9B	Cafeteria	Yes	W1	Plaster	Tan	Chipping	200	9.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Changed from brick to plaster - Viva EHS - 9/30/21 - EJS
1	B	9B	Cafeteria	Yes	W2	Plaster	Tan	Chipping	50	1.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Changed from brick to plaster - Viva EHS - 9/30/21 - EJS



1	B	9B	Cafeteria	Yes	W3	Plaster	Tan	Chipping	5	0.1	Negative								Changed from brick to plaster - Viva EHS - 9/30/21 - EJS
1	B	9B	Cafeteria	Yes	W4	Sheetrock	Tan	Chipping	5	0	Negative								Changed from brick to sheetrock - Viva EHS - 9/30/21 - EJS
1	B	9B	Cafeteria	Yes	Ceiling	Concrete	Tan	Flaking	10	5.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Above ceiling tile - Viva EHS - 9/30/21 - EJS
1	B	9B	Cafeteria	yes	Stair stinger - W2	Concrete	Tan	Flaking	5	10.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	B	9B	Cafeteria	yes	Stair Rail - W2	Metal	Tan	Friction	2	0.5	Negative								
1	B	9B	Cafeteria	Yes	Window Sill	Concrete	Brown	Flaking	5	1.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	B	9BB	Cafeteria Closet	No	W1	Wood	Brown	None	0	N/A	N/A								Added - Viva EHS - 9/30/21 - EJS
1	B	9BB	Cafeteria Closet	No	W2	Concrete	White	Chipping	15	0	Negative								Added - Viva EHS - 9/30/21 - EJS
1	B	9BB	Cafeteria Closet	No	W3	Concrete	White	Chipping	20	0	Negative								Added - Viva EHS - 9/30/21 - EJS
1	B	9BB	Cafeteria Closet	No	W4	Wood	Brown	None	0	N/A	N/A								Added - Viva EHS - 9/30/21 - EJS
1	B	9AB	Cafeteria Closet	No	Ceiling	Plaster	White	None	0	N/A	N/A								Added - Viva EHS - 9/30/21 - EJS
1	B	9BB	Cafeteria Closet	No	Floor	N/A	N/A	N/A	N/A	N/A	N/A								Added - Viva EHS - 9/30/21 - EJS
1	B	9BB	Cafeteria Closet	No	Pipe	Metal	White	Chipping	5	0.21	Negative								Added - Viva EHS - 9/30/21 - EJS
1	B	11B	Girl's Restroom Across from Cafeteria	Yes	W1	Brick	White	Chipping	5	4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Changed from tan to white - Viva EHS - 9/30/21 - EJS
1	B	11B	Girl's Restroom Across from Cafeteria	Yes	W2	Brick	White	Chipping	10	2.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Changed from tan to white - Viva EHS - 9/30/21 - EJS
1	B	11B	Girl's Restroom Across from Cafeteria	Yes	W3	Brick	White	Chipping	10	3.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Changed from tan to white - Viva EHS - 9/30/21 - EJS
1	B	11B	Girl's Restroom Across from Cafeteria	Yes	W4	Brick	White	Chipping	4	4.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Changed from tan to white - Viva EHS - 9/30/21 - EJS
1	B	11B	Girl's Restroom Across from Cafeteria	Yes	Ceiling	Plaster	White	Flaking	25	8.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	B	11B	Girl's Restroom Across from Cafeteria	yes	Baseboard	Concrete	Brown	Friction	0.3 LF	1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	B	11B	Girl's Restroom Across from Cafeteria	yes	Floor	Concrete	Tan	Friction	5	0.2	Negative								
1	B	11B	Girl's Restroom Across from Cafeteria	Yes	Door - W2	Metal	Green	Chipping	1	6.2	Positive			This material has not been sampled based on AHERA log-Viva EHS-RW					
1	B	8B	Food Storage cage in Hallway near Cafeteria	Yes	W1	N/A	N/A	None	0	N/A	N/A								No access. Gate is padlocked-Viva EHS-RW
1	B	8B	Food Storage cage in Hallway near Cafeteria	Yes	W2	Brick	Tan	None	0	2.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	B	8B	Food Storage cage in Hallway near Cafeteria	Yes	W3	Brick	Tan	None	0	4.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	B	8B	Food Storage cage in Hallway near Cafeteria	Yes	W4	Brick	Tan	None	0	2.3	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	B	8B	Food Storage cage in Hallway near Cafeteria	Yes	Ceiling	Plaster	White	None	0	14.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	B	8B	Food Storage cage in Hallway near Cafeteria	Yes	Floor	Concrete	Tan	None	0	N/A	N/A								
1	B	7B	Hallway next to Cafeteria	Yes	W1	Brick	Red	N/A	N/A	N/A	N/A								Changed to Ceramic Brick N/A due to being unpainted - Viva EHS - 9/30/21 - EJS
1	B	7B	Hallway next to Cafeteria	Yes	W2	Brick	Tan	Chipping	2	8.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Changed reading from (2.8) to (8.8) - Viva EHS - 9/30/21 - EJS
1	B	7B	Hallway next to Cafeteria	Yes	W2	Brick	White	Chipping	2	1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Added - Viva EHS - 9/30/21 - EJS
1	B	7B	Hallway next to Cafeteria	Yes	W3	Brick	Tan	Flaking	15	5.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	B	7B	Hallway next to Cafeteria	Yes	W3	Brick	White	None	0	0	Negative								Added - Viva EHS - 9/30/21 - EJS
1	B	7B	Hallway next to Cafeteria	Yes	W4	Brick	White	Chipping	10	1.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Changed tan brick to white brick and reading from (1.6) to (2.3) - Viva EHS - 9/30/21 - EJS
1	B	7B	Hallway next to Cafeteria	Yes	W4	Concrete	Tan	Chipping	10	9.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Added - Viva EHS - 9/30/21 - EJS
1	B	7B	Hallway next to Cafeteria	Yes	Ceiling	Plaster	White	Flaking	25	14.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Changed tan brick to white ceiling - Viva EHS - 9/30/21 - EJS
1	B	7B	Hallway next to Cafeteria	Yes	Pipe	Metal	Tan	Flaking	10	9.3	Positive			This material has not been sampled based on AHERA log-Viva EHS-RW					
2	B	6B	Custodial Office next to Cafeteria	No	W1	Plaster	Tan	Flaking	250	21.3	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Changed brick to plaster - Viva EHS - 9/30/21 - EJS
2	B	6B	Custodial Office next to Cafeteria	No	W2	Plaster	Tan	Flaking	100	26.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Changed brick to plaster - Viva EHS - 9/30/21 - EJS
2	B	6B	Custodial Office next to Cafeteria	No	W3	Plaster	Tan	Flaking	250	23.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Changed brick to plaster - Viva EHS - 9/30/21 - EJS
2	B	6B	Custodial Office next to Cafeteria	No	W4	Plaster	Tan	Flaking	100	24.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Changed brick to plaster - Viva EHS - 9/30/21 - EJS
2	B	6B	Custodial Office next to Cafeteria	no	Pipe - W3	Metal	Tan	Chipping	15	18	Positive			This material has not been sampled based on AHERA log-Viva EHS-RW					Damage changed from (4) to (15) and tan to white - Viva EHS - 9/30/21 - EJS
2	B	6B	Custodial Office next to Cafeteria	no	Radiator	Metal	Tan	Chipping	6	23.4	Positive			This material has not been sampled based on AHERA log-Viva EHS-RW					Added - Viva EHS - 9/30/21 - EJS
2	B	6B	Custodial Office next to Cafeteria	no	Baseboard - W1	Concrete	Brown	Flaking	5 LF	7.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2	B	6B	Custodial Office next to Cafeteria	no	Door	Wood	Brown	Chipping	2	7.8	Positive			This material has not been sampled based on AHERA log-Viva EHS-RW					
2	B	6B	Custodial Office next to Cafeteria	no	Window Sill - W3	Concrete	Brown	Chipping	10	6.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2	B	6B	Custodial Office next to Cafeteria	No	Ceiling	Plaster	Tan	Flaking	100	24.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Changed concrete to plaster - Viva EHS - 9/30/21 - EJS
2	B	6B	Custodial Office next to Cafeteria	No	Floor	Concrete	Tan	Friction	20	0.4	Negative								
2	B	6A	Custodial Staff Office Restroom	No	W1	Plaster	Tan	Chipping	20	31	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Changed brick to plaster, 100SF chipping to 20SF, reading from (24.3) to (31) - Viva EHS - 9/30/21 - EJS
2	B	6A	Custodial Staff Office Restroom	No	W2	Plaster	Tan	Chipping	20	21.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Changed brick to plaster, 100SF chipping to 20SF, reading from (29.1) to (21.8) - Viva EHS - 9/30/21 - EJS

2	B	6A	Custodial Staff Office Restroom	No	W1	Plaster	White	Chipping	20	23.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Changed brick to plaster, 100SF chipping to 20SF, reading from (24.3) to (23.1) - Viva EHS - 9/30/21 - EJS
2	B	6A	Custodial Staff Office Restroom	No	W2	Plaster	White	Chipping	20	27.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Changed brick to plaster, 100SF chipping to 20SF, reading from (29.1) to (27.2) - Viva EHS - 9/30/21 - EJS
2	B	6A	Custodial Staff Office Restroom	No	W3	Plaster	Tan	Chipping	40	21.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Changed brick to plaster, 100SF chipping to 20SF - Viva EHS - 9/30/21 - EJS
2	B	6A	Custodial Staff Office Restroom	No	W4	Plaster	Tan	Chipping	40	22.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Changed brick to plaster, 100SF chipping to 20SF - Viva EHS - 9/30/21 - EJS
2	B	6A	Custodial Staff Office Restroom	No	Ceiling	Plaster	Tan	Flaking	50	26.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Changed from sheetrock to plaster - Viva EHS - 9/30/21 - EJS
2	B	6A	Custodial Staff Office Restroom	no	Pipe	Metal	Tan	Chipping	15	31	Positive			This material has not been sampled based on AHERA log-Viva EHS-RW					Damage changed from (5) to (15) and reading changed from (18) to (31) - Viva EHS - 9/30/21 - EJS
2	B	6A	Custodial Staff Office Restroom	no	Radiator	Metal	White	Chipping	5	32.7	Positive			This material has not been sampled based on AHERA log-Viva EHS-RW					
2	B	6A	Custodial Staff Office Restroom	No	Baseboard - W3	Concrete	Brown	Chipping	3 LF	8.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2	B	S02	Stairwell near Cafeteria	Yes	W1	Plaster	White	Chipping	2	25.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Changed from tan wood wall to white plaster and reading (.1) to (25.4) - Viva EHS - 9/30/21 - EJS
2	B	S02	Stairwell near Cafeteria	Yes	W1	Plaster	White	Chipping	2	27	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Changed from tan wood wall to tan plaster and reading (.1) to (27) - Viva EHS - 9/30/21 - EJS
2	B	S02	Stairwell near Cafeteria	Yes	W1 door	Wood	Tan	None	N/A	N/A	N/A								
2	B	S02	Stairwell near Cafeteria	Yes	W2	Plaster	Tan	Cracking	5	31	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Changed reading from (23.3) to (31) - Viva EHS - 9/30/21 - EJS
2	B	S02	Stairwell near Cafeteria	Yes	W2	Plaster	White	Cracking	5	30	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Added - Viva EHS - 9/30/21 - EJS
2	B	S02	Stairwell near Cafeteria	Yes	W2 radiator	Metal	Gray	Flaking	2	19.4	Positive			This material has not been sampled based on AHERA log-Viva EHS-RW					W2 and W4 Damage added - Viva EHS - 9/30/21 - EJS
2	B	S02	Stairwell near Cafeteria	Yes	W3	Plaster	White	Flaking	5	30	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Added - Viva EHS - 9/30/21 - EJS
2	B	S02	Stairwell near Cafeteria	Yes	W3	Plaster	Tan	Flaking	5	31.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Changed from tan wood wall to tan plaster and reading (N/A) to (31.7) - Viva EHS - 9/30/21 - EJS
2	B	S02	Stairwell near Cafeteria	Yes	W4	Plaster	White	Flaking	5	28.3	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Added - Viva EHS - 9/30/21 - EJS
2	B	S02	Stairwell near Cafeteria	Yes	W4	Plaster	Tan	Flaking	5	32	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Damage added - Viva EHS - 9/30/21 - EJS
2	B	S02	Stairwell near Cafeteria	Yes	W4 Baseboard	Concrete	Grey	Chipping	10 LF	3.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Changed from riser to tan baseboard and reading (3.6) to (3.7) - Viva EHS - 9/30/21 - EJS
2	B	S02	Stairwell near Cafeteria	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A								
2	B	S02	Stairwell near Cafeteria	Yes	Pipe	Metal	White	Chipping	5	0	Negative								
2	B	5B	Building Engineer's Office (Former Ash Room)	No	W1	Brick	White	Flaking	300	0.5	Negative								W / Hall
2	B	5B	Building Engineer's Office (Former Ash Room)	No	W2	Concrete	Grey	None	0	N/A	N/A								Unpainted - Viva EHS - 9/30/21 - EJS
2	B	5B	Building Engineer's Office (Former Ash Room)	No	W3	Brick	White	Flaking	250	0.1	Negative								W/ Hall
2	B	5B	Building Engineer's Office (Former Ash Room)	No	W4	Brick	White	Flaking	50	0	Negative								
2	B	5B	Building Engineer's Office (Former Ash Room)	No	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A								Unpainted - Viva EHS - 9/30/21 - EJS
2	B	5B	Building Engineer's Office (Former Ash Room)	No	Floor	Concrete	Grey	None	0	N/A	N/A								bare concrete
2	B	4B	Coal Room	No	W1	Brick	Grey	None	N/A	N/A	N/A								Unpainted - Viva EHS - 9/30/21 - EJS
2	B	4B	Coal Room	No	W1	Brick	White	None	N/A	N/A	N/A								Unpainted - Viva EHS - 9/30/21 - EJS
2	B	4B	Coal Room	No	W1	Brick	White	None	N/A	N/A	N/A								native brick/ stone w/ parge
2	B	4B	Coal Room	No	W2	Brick	Grey	Flaking	50	0.1	Negative								Unpainted - Viva EHS - 9/30/21 - EJS
2	B	4B	Coal Room	No	W3	Brick	Grey	None	0	N/A	N/A								Unpainted - Viva EHS - 9/30/21 - EJS
2	B	4B	Coal Room	No	W1	Brick	White	Flaking	20	0.12	Negative								doorway
2	B	4B	Coal Room	No	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A								Changed reading from (4) to (.12) - Viva EHS - 9/30/21 - EJS
2	B	4B	Coal Room	No	W4	Brick	Grey	None	0	N/A	N/A								Unpainted - Viva EHS - 9/30/21 - EJS
2	B	4B	Coal Room	No	W4	Concrete	White	None	0	N/A	N/A								Unpainted - Viva EHS - 9/30/21 - EJS
2	B	4B	Coal Room	No	Floor	Concrete	Unpainted												Unpainted - Viva EHS - 9/30/21 - EJS
2	B	3B	Fan Room	No	W1	Brick	White	Flaking	45	0.3	Negative								
2	B	3B	Fan Room	No	W1	Brick	Grey	Flaking	6	16.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2	B	3B	Fan Room	No	W2	Brick	White	Flaking	100	0.08	Negative								
2	B	3B	Fan Room	No	W2	Concrete	Grey	Flaking	100	0.05	Negative								Added - Viva EHS - 9/30/21 - EJS
2	B	3B	Fan Room	No	W2	Concrete	White	Flaking	100	0	Negative								Added - Viva EHS - 9/30/21 - EJS
2	B	3B	Fan Room	No	DoorWay	Brick	Gray	Flaking	10	11.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Added - Viva EHS - 9/30/21 - EJS
2	B	3B	Fan Room	No	W3	Brick	White	Flaking	250	2.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2	B	3B	Fan Room	No	Ceiling	Concrete	White	Flaking	350	0.3	Negative								
2	B	3B	Fan Room	No	Floor	Concrete	Unpainted												
2	B	3B	Fan Room	No	Pipe	Metal	White	Chipping	5	0.18	Negative								
2	B	3B	Fan Room	No	Pipe	Metal	Grey	Chipping	5	0.16	Negative								
2	B	3B	Fan Room	No	W4 (Fan Unit)	Metal	Gray	Flaking	325	2.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Fan
2	B	3B	Fan Room	No	W2 (Fan Unit)	Metal	Grey	Flaking	250	1.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Fan
2	B	3B	Fan Room	No	W3 (Fan Unit)	Metal	Grey	Flaking	375	5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Fan
2	B	2B	Boiler Room	No	W1	Brick	Tan	Flaking	600	9.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2	B	2B	Boiler Room	No	W2	Concrete	Tan	Flaking	400	2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2	B	2B	Boiler Room	No	W3	Concrete	Tan	Flaking	450	1.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	patches
2	B	2B	Boiler Room	No	W4	Brick	Tan	Flaking	350	3	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2	B	2B	Boiler Room	No	W4	Concrete	Tan	Flaking	70	0	Negative								
2	B	2C	Boiler Room	No	Ceiling	Concrete	White	Flaking	750	0.2	Negative								
2	B	2B	Boiler Room	No	Floor	Concrete	Unpainted												Unpainted - Viva EHS - 9/30/21 - EJS

				No	Rail	Metal	Red	Flaking	15	1.6	Positive			This material has not been sampled based on AHERA log-Viva EHS-RW						
2	B	2B	Boiler Room																	
2	B	2B	Boiler Room	No	Tread	Metal	Brown	Chipping	35	0.1	Negative									
				No	Riser	Metal	Grey	Chipping	15	1	Positive			This material has not been sampled based on AHERA log-Viva EHS-RW						
2	B	2B	Boiler Room																	
2	B	2B	Boiler Room	No	Door	Wood	Red	None	0	0.5	Negative									
				No	Door Frame	Metal	Red	None	0	1.8	Positive			This material has not been sampled based on AHERA log-Viva EHS-RW						
2	B	2B	Boiler Room																	
2	B	1B	Boy's Restroom near Boiler Room	Yes	W1	Brick	Tan	Flaking	10	8.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2	B	1B	Boy's Restroom near Boiler Room	Yes	W2	Brick	Tan	Chipping	5	6.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2	B	1B	Boy's Restroom near Boiler Room	Yes	W3	Brick	Tan	Flaking	8	7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2	B	1B	Boy's Restroom near Boiler Room	Yes	W4	Brick	Tan	Flaking	5	4.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2	B	1B	Boy's Restroom near Boiler Room	yes	Duct - W3	Metal	Tan	Chipping	10	2.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2	B	1B	Boy's Restroom near Boiler Room	yes	Pipe	Metal	White	Chipping	1	0	Negative									
2	B	1B	Boy's Restroom near Boiler Room	Yes	Ceiling	Concrete	Tan	Chipping	10	15.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2	B	1B	Boy's Restroom near Boiler Room	Yes	Floor	Concrete	Unpainted													
2	B	1B	Boy's Restroom near Boiler Room	Yes	Door - W4	Wood	Brown	Chipping	0.5	0.05	Negative									Changed reading from (3.1) to (.05) - Viva EHS - 9/30/21 - EJS
2	B	1C	Storage under Steps near Boiler Room	No	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	No Access	Padlocked-Viva EHS-RW
2	B	1C	Storage under Steps near Boiler Room	No	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	No Access	Padlocked-Viva EHS-RW
2	B	1C	Storage under Steps near Boiler Room	No	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	No Access	Padlocked-Viva EHS-RW
2	B	1C	Storage under Steps near Boiler Room	No	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	No Access	Padlocked-Viva EHS-RW
2	B	1C	Storage under Steps near Boiler Room	No	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	No Access	Padlocked-Viva EHS-RW
2	B	1C	Storage under Steps near Boiler Room	No	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	No Access	Padlocked-Viva EHS-RW
2	B	H02	Hallway by Boiler Room	Yes	W1	Brick	Tan	Flaking	5	7.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2	B	H02	Hallway by Boiler Room	Yes	W2	Brick	Tan	Flaking	7	3.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2	B	H02	Hallway by Boiler Room	Yes	W3	Brick	Tan	Flaking	10	10.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2	B	H02	Hallway by Boiler Room	Yes	W4	Brick	Tan	Flaking	5	9.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2	B	H02	Hallway by Boiler Room	Yes	Ceiling	Concrete	Tan	Chipping	100	19.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
				yes	Pipe	Metal	Tan	Chipping	50	13.7	Positive			This material has not been sampled based on AHERA log-Viva EHS-RW						
2	B	H02	Hallway by Boiler Room																	
2	B	H02	Hallway by Boiler Room	yes	Duct Work	Metal	White	Chipping	15	4.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2	B	H02	Hallway by Boiler Room	Yes	Stringer	Concrete	Brown	Friction	1	0.6	Negative									
2	B	S03	Stairwell near Boiler Room	Yes	W1	Plaster	Tan	Cracking	10	23.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Changed from wood to plaster and reading from (.1) to (23.9) - Viva EHS - 9/30/21 - EJS
2	B	S03	Stairwell near Boiler Room	Yes	W1	Plaster	White	Cracking	10	18.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Added - Viva EHS - 9/30/21 - EJS
2	B	S03	Stairwell near Boiler Room	Yes	W2	Plaster	Tan	Cracking	8	26.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Changed from wood to plaster and reading from (.05) to (26.1) - Viva EHS - 9/30/21 - EJS
2	B	S03	Stairwell near Boiler Room	Yes	W2	Plaster	White	Cracking	8	22	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Added - Viva EHS - 9/30/21 - EJS
2	B	S03	Stairwell near Boiler Room	Yes	W3	Plaster	Tan	Cracking	15	3.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Changed from wood to plaster - Viva EHS - 9/30/21 - EJS
2	B	S03	Stairwell near Boiler Room	Yes	W3	Plaster	White	Cracking	15	26.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Added - Viva EHS - 9/30/21 - EJS
				Yes	W3 post	Metal	Brown	Chipping	6	18.6	Positive			This material has not been sampled based on AHERA log-Viva EHS-RW						
2	B	S03	Stairwell near Boiler Room																	
2	B	S03	Stairwell near Boiler Room	Yes	W4	Plaster	Tan	Flaking	10	24.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2	B	S03	Stairwell near Boiler Room	Yes	W4	Plaster	White	Flaking	10	21.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Added - Viva EHS - 9/30/21 - EJS
				Yes	W4 tread	Metal	Tan	Flaking	10	19.8	Positive			This material has not been sampled based on AHERA log-Viva EHS-RW						
2	B	S03	Stairwell near Boiler Room																	
2	B	S03	Stairwell near Boiler Room	Yes	Ceiling	Plaster	White	None	0	26	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2	B	S03	Stairwell near Boiler Room	Yes	Floor	Concrete	Tan	None	0	N/A	N/A									sealed
3	1	21	Classroom T1		W1	Vinyl Sheetrock Material	Purple	None	0	N/A	N/A									New Trailers/ Classrooms ~5 yr old - Viva EHS - 10/1/21 - EJS
3	1	21	Classroom T1		W2	Vinyl Sheetrock Material	Purple	None	0	N/A	N/A									New Trailers/ Classrooms ~5 yr old - Viva EHS - 10/1/21 - EJS
3	1	21	Classroom T1		W3	Vinyl Sheetrock Material	Purple	None	0	N/A	N/A									New Trailers/ Classrooms ~5 yr old - Viva EHS - 10/1/21 - EJS
3	1	21	Classroom T1		W4	Vinyl Sheetrock Material	Purple	None	0	N/A	N/A									New Trailers/ Classrooms ~5 yr old - Viva EHS - 10/1/21 - EJS
3	1	21	Classroom T1		Ceiling	N/A	N/A	N/A	N/A	N/A	N/A									Ceiling tile in space - Viva EHS - 10/1/21 - EJS
3	1	21	Classroom T1		Floor	N/A	N/A	N/A	N/A	N/A	N/A									12x12 VAT- Viva EHS - 10/1/21 - EJS
3	1	22	Classroom T2		W1	Vinyl Sheetrock Material	Purple	None	0	N/A	N/A									New Trailers/ Classrooms ~5 yr old - Viva EHS - 10/1/21 - EJS
3	1	22	Classroom T2		W2	Vinyl Sheetrock Material	Purple	None	0	N/A	N/A									New Trailers/ Classrooms ~5 yr old - Viva EHS - 10/1/21 - EJS
3	1	22	Classroom T2		W3	Vinyl Sheetrock Material	Purple	None	0	N/A	N/A									New Trailers/ Classrooms ~5 yr old - Viva EHS - 10/1/21 - EJS
3	1	22	Classroom T2		W4	Vinyl Sheetrock Material	Purple	None	0	N/A	N/A									New Trailers/ Classrooms ~5 yr old - Viva EHS - 10/1/21 - EJS
3	1	22	Classroom T2		Ceiling	N/A	N/A	N/A	N/A	N/A	N/A									Ceiling tile in space - Viva EHS - 10/1/21 - EJS
3	1	22	Classroom T2		Floor	N/A	N/A	N/A	N/A	N/A	N/A									12x12 VAT- Viva EHS - 10/1/21 - EJS
3	1	23	Classroom T3		W1	Vinyl Sheetrock Material	Purple	None	0	N/A	N/A									New Trailers/ Classrooms ~5 yr old - Viva EHS - 10/1/21 - EJS
3	1	23	Classroom T3		W2	Vinyl Sheetrock Material	Purple	None	0	N/A	N/A									New Trailers/ Classrooms ~5 yr old - Viva EHS - 10/1/21 - EJS
3	1	23	Classroom T3		W3	Vinyl Sheetrock Material	Purple	None	0	N/A	N/A									New Trailers/ Classrooms ~5 yr old - Viva EHS - 10/1/21 - EJS
3	1	23	Classroom T3		W4	Vinyl Sheetrock Material	Purple	None	0	N/A	N/A									New Trailers/ Classrooms ~5 yr old - Viva EHS - 10/1/21 - EJS

3	1	23	Classroom T3		Ceiling	N/A	N/A	N/A	N/A	N/A	N/A								Ceiling tile in space - Viva EHS - 10/1/21 - EJS
3	1	23	Classroom T3		Floor	N/A	N/A	N/A	N/A	N/A	N/A								12x12 VAT- Viva EHS - 10/1/21 - EJS
3	1	23	Men Restroom		W1	Vinyl Sheetrock Material	Purple	None	0	N/A	N/A								
3	1	23	Men Restroom		W2	Vinyl Sheetrock Material	Purple	None	0	N/A	N/A								
3	1	23	Men Restroom		W3	Vinyl Sheetrock Material	Purple	None	0	N/A	N/A								
3	1	23	Men Restroom		W4	Vinyl Sheetrock Material	Purple	None	0	N/A	N/A								
3	1	23	Men Restroom		Ceiling	N/A	N/A	N/A	N/A	N/A	N/A								
3	1	23	Men Restroom		Floor	N/A	N/A	N/A	N/A	N/A	N/A								
3	1	23	Women Restroom		W1	Vinyl Sheetrock Material	Purple	None	0	N/A	N/A								
3	1	23	Women Restroom		W2	Vinyl Sheetrock Material	Purple	None	0	N/A	N/A								
3	1	23	Women Restroom		W3	Vinyl Sheetrock Material	Purple	None	0	N/A	N/A								
3	1	23	Women Restroom		W4	Vinyl Sheetrock Material	Purple	None	0	N/A	N/A								
3	1	23	Women Restroom		Ceiling	N/A	N/A	N/A	N/A	N/A	N/A								
3	1	23	Women Restroom		Floor	N/A	N/A	N/A	N/A	N/A	N/A								
1	A	AT	Main Attic	No	W1	Concrete	Unpainted												
1	A	AT	Main Attic	No	W2	Concrete	Unpainted												
1	A	AT	Main Attic	No	W3	Concrete	Unpainted												
1	A	AT	Main Attic	No	W4	Concrete	Unpainted												
1	A	AT	Main Attic	No	Ceiling	Wood	Unpainted												
1	A	AT	Main Attic	No	Floor	Wood	Unpainted												
1	C	CS	Crawlspc	No	W1	X	X	X	X	X	X								No CS per BE - Viva EHS - 10/1/21 - EJS
1	C	CS	Crawlspc	No	W2	X	X	X	X	X	X								No CS per BE - Viva EHS - 10/1/21 - EJS
1	C	CS	Crawlspc	No	W3	X	X	X	X	X	X								No CS per BE - Viva EHS - 10/1/21 - EJS
1	C	CS	Crawlspc	No	W4	X	X	X	X	X	X								No CS per BE - Viva EHS - 10/1/21 - EJS
1	C	CS	Crawlspc	No	Ceiling	X	X	X	X	X	X								No CS per BE - Viva EHS - 10/1/21 - EJS
1	C	CS	Crawlspc	No	Floor	X	X	X	X	X	X								No CS per BE - Viva EHS - 10/1/21 - EJS