

			Inspection Dates: 09/21/20-09/29/20				Lead Safe Certification Assessment Report						
			Name of Inspector: Michael Barth				Fell Elementary School						
			Inspection Company: Criterion Labs										
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm <sup>2</sup> )	XRF (positive/ negative)	
2190	1	B	24	Girl's Restroom	Yes	W1	Brick	White	None	0	17.8	Positive	
2190	1	B	24	Girl's Restroom	Yes	W2	Brick	White	None	0	19.2	Positive	
2190	1	1	112	Auditorium	Yes	W1	Wood	Tan	Cracking	2	3.1	Positive	
2190	1	B	24	Girl's Restroom	Yes	W4	Brick	White	None	0	22.3	Positive	
2190	1	1	112	Auditorium	Yes	W2	Wood	Tan	Cracking	3	3.5	Positive	
2190	1	B	24	Girl's Restroom	Yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
2190	1	B	23	Storage Closet beside Southeast Stairwell	Yes	W1	Brick	White	None	0	18.9	Positive	
2190	1	B	23	Storage Closet beside Southeast Stairwell	Yes	W2	Brick	White	None	0	19.8	Positive	
2190	1	B	23	Storage Closet beside Southeast Stairwell	Yes	W3	Brick	White	None	0	17.8	Positive	
2190	1	B	23	Storage Closet beside Southeast Stairwell	Yes	W4	Brick	White	None	0	19.2	Positive	
2190	1	1	112	Auditorium	Yes	W3	Wood	Tan	Cracking	3	3.4	Positive	
2190	1	1	103B	Girl's Restroom	Yes	W2	Metal	Black	None	0	0.1	Negative	
2190	1	B	23	Storage Closet beside Southeast Stairwell	Yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
2190	1	B	H03A	East Hallway; South End	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	
2190	1	1	112	Auditorium	Yes	W3	Wood	Tan	Chipping	10	1.9	Positive	
2190	1	1	112	Auditorium	Yes	W4	Wood	Tan	Cracking	6	3.2	Positive	
2190	1	1	103B	Girl's Restroom	Yes	W3	Metal	Black	Chipping	3	0.02	Negative	
2190	1	1	112	Auditorium	Yes	W2	Metal	Tan	Chipping	5	3.1	Positive	
2190	1	B	H03A	East Hallway; South End	Yes	Ceiling	Plaster	White	None	0	22.4	Positive	
2190	1	B	H03A	East Hallway; South End	Yes	Floor	Concrete	Blue	Friction	1	0.21	Negative	
2190	1	1	S18	Auditorium Entrance Stairwell across from Classroom 104	Yes	W1	Wood	White	Cracking	5	3.2	Positive	
2190	1	1	S19	Auditorium Entrance Stairwell across from Classroom 105	Yes	W1	Plaster	Tan	Cracking	2	21.4	Positive	
2190	1	1	S19	Auditorium Entrance Stairwell across from Classroom 105	Yes	W1	Wood	White	Cracking	5	3.4	Positive	
2190	1	1	112B	Auditorium Stage	Yes	W2	Plaster	Tan	Cracking	2	14.1	Positive	
2190	1	1	112B	Auditorium Stage	Yes	W3	Plaster	Tan	Cracking	2	21.3	Positive	
2190	1	1	112B	Auditorium Stage	Yes	W4	Plaster	Tan	Cracking	2	22.1	Positive	
2190	1	B	S06	Stairwell and Entrance Vestibule beside Girl's Restroom	Yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	

				Inspection Dates: 09/21/20-09/29/20								
				Name of Inspector: Michael Barth		Lead Safe Certification Assessment Report						
				Inspection Company: Criterion Labs		Fell Elementary School						
ULCS#	Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm <sup>2</sup> )	XRF (positive/negative)
2190	1	1	112D	Auditorium Stage Dressing Room - Classroom 100 Side	Yes	Floor	Wood	Tan	Friction	5	5.4	Positive
2190	1	B	PTA3	PTA Lunchroom Storage Closet 3	Yes	W2	Plaster	Green	None	0	22.5	Positive
2190	1	1	112D	Auditorium Stage Dressing Room - Classroom 100 Side	Yes	W1	Wood	Tan	Friction	1	7.8	Positive
2190	1	1	112D	Auditorium Stage Dressing Room - Classroom 100 Side	Yes	W4	Wood	Tan	Friction	1	6.5	Positive
2190	1	1	112D	Auditorium Stage Dressing Room - Classroom 100 Side	Yes	W1	Plaster	Tan	Cracking	1	21.3	Positive
2190	1	B	PTA3	PTA Lunchroom Storage Closet 3	Yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
2190	1	1	112D	Auditorium Stage Dressing Room - Classroom 100 Side	Yes	W2	Plaster	Tan	Cracking	1	21.4	Positive
2190	1	1	112D	Auditorium Stage Dressing Room - Classroom 100 Side	Yes	W3	Plaster	Tan	Cracking	2	22.6	Positive
2190	1	1	112D	Auditorium Stage Dressing Room - Classroom 100 Side	Yes	W4	Plaster	Tan	Cracking	2	23.1	Positive
2190	1	1	106B	Boy's Restroom	Yes	W3	Metal	Black	Chipping	1	0.21	Negative
2190	1	B	PTA4	PTA Lunchroom Storage Closet 4	Yes	W4	Plaster	Green	None	0	N/A	N/A
2190	1	1	110A	Principal's Office Restroom	yes	W1	Wood	Black	Chipping	1	0.1	Negative
2190	1	1	112D	Auditorium Stage Dressing Room - Classroom 100 Side	Yes	Ceiling	Plaster	Tan	Cracking	1	18.9	Positive
2190	1	B	PTA4	PTA Lunchroom Storage Closet 4	Yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
2190	1	1	112C	Auditorium Stage Dressing Room - Classroom 109 Side	Yes	Floor	Wood	Tan	Friction	5	6.7	Positive
2190	1	1	112C	Auditorium Stage Dressing Room - Classroom 109 Side	Yes	W3	Metal	Gray	Chipping	3	1.7	Positive

				Inspection Dates: 09/21/20-09/29/20								
				Name of Inspector: Michael Barth		Lead Safe Certification Assessment Report						
				Inspection Company: Criterion Labs		Fell Elementary School						
ULCS#	Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm <sup>2</sup> )	XRF (positive/negative)
2190	1	1	110A	Principal's Office Restroom	yes	W2	Wood	Black	Chipping	1	0.03	Negative
2190	1	1	112C	Auditorium Stage Dressing Room - Classroom 109 Side	Yes	W1	Wood	Tan	Friction	2	14.1	Positive
2190	1	1	112C	Auditorium Stage Dressing Room - Classroom 109 Side	Yes	W2	Wood	Tan	Friction	2	7.8	Positive
2190	1	1	110A	Principal's Office Restroom	yes	W3	Wood	Black	Chipping	1	0.1	Negative
2190	1	1	112C	Auditorium Stage Dressing Room - Classroom 109 Side	Yes	Ceiling	Wood	Tan	Cracking	3	7.4	Positive
2190	1	1	112C	Auditorium Stage Dressing Room - Classroom 109 Side	Yes	W1	Plaster	Tan	Cracking	1	23.1	Positive
2190	1	1	110A	Principal's Office Restroom	yes	W4	Wood	Black	Chipping	1	0.02	Negative
2190	1	1	112C	Auditorium Stage Dressing Room - Classroom 109 Side	Yes	W2	Plaster	Tan	Cracking	3	21.2	Positive
2190	1	1	112C	Auditorium Stage Dressing Room - Classroom 109 Side	Yes	W3	Plaster	Tan	Cracking	1	17.9	Positive
2190	1	B	PTA	Lunch Room	Yes	W4	Plaster	Mural	None	0	0.3	Negative
2190	1	1	110	Principal's Office	Yes	W1	Wood	Black	None	0	N/A	N/A
2190	1	B	PTA	Lunch Room	Yes	Ceiling	Plaster	White	None	0	N/A	N/A
2190	1	1	110	Principal's Office	Yes	W2	Wood	Black	None	0	N/A	N/A
2190	1	B	PTA	Lunch Room	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2190	1	B	PTA1	PTA Lunchroom Storage Closet 1	Yes	W1	Plaster	Tan	None	0	N/A	N/A
2190	1	1	112C	Auditorium Stage Dressing Room - Classroom 109 Side	Yes	W4	Plaster	Tan	Cracking	6	18.9	Positive
2190	1	1	112C	Auditorium Stage Dressing Room - Classroom 109 Side	Yes	Ceiling	Plaster	Tan	Flaking	6	19.2	Positive
2190	1	1	110	Principal's Office	Yes	W3	Wood	Black	None	0	N/A	N/A
2190	1	1	106B	Boy's Restroom	Yes	W4	Metal	Grey	Chipping	3	4.5	Positive
2190	1	B	PTA1	PTA Lunchroom Storage Closet 1	Yes	Ceiling	Plaster	Tan	Partially Inaccessible	N/A	N/A	N/A
2190	1	1	110	Principal's Office	Yes	W4	Wood	Black	None	0	N/A	N/A

				Inspection Dates: 09/21/20-09/29/20								
				Name of Inspector: Michael Barth			Lead Safe Certification Assessment Report					
				Inspection Company: Criterion Labs			Fell Elementary School					
ULCS#	Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm <sup>2</sup> )	XRF (positive/negative)
2190	1	B	PTA1	PTA Lunchroom Storage Closet 1	Yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
2190	1	1	106B	Boy's Restroom	Yes	W1	Plaster	White	Cracking	3	21.3	Positive
2190	1	1	106B	Boy's Restroom	Yes	W2	Plaster	White	Cracking	5	22.4	Positive
2190	1	1	106B	Boy's Restroom	Yes	W3	Plaster	White	Moisture Damage	5	25.1	Positive
2190	1	1	106B	Boy's Restroom	Yes	W4	Plaster	White	Cracking	5	22.1	Positive
2190	1	1	106B	Boy's Restroom	Yes	Ceiling	Plaster	White	Moisture Damage/Flaking	15	21.4	Positive
2190	1	B	PTA2	PTA Lunchroom Storage Closet 2	Yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
2190	1	B	40	Boy's Restroom beside Speech Classroom	Yes	Ceiling	Plaster	White	Moisture Damage	3	19.2	Positive
2190	1	B	40	Boy's Restroom beside Speech Classroom	Yes	W1	Brick	White	Cracking	1	24.5	Positive
2190	1	B	40	Boy's Restroom beside Speech Classroom	Yes	W2	Brick	White	Cracking	1	21.2	Positive
2190	1	B	40	Boy's Restroom beside Speech Classroom	Yes	W3	Brick	White	Moisture Damage	3	22.4	Positive
2190	1	B	39	Building Engineer's Restroom beside Boy's Restroom	Yes	W2	Plaster	White	Moisture Damage/Chipping	3	21.3	Positive
2190	1	1	111	Main Office	Yes	W1	Wood	Black	Chipping	1	0.1	Negative
2190	1	B	H03	Hallway outside of PTA Cafeteria and Girls Restroom	Yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
2190	1	1	111	Main Office	Yes	W2	Wood	Black	Chipping	1	0.03	Negative
2190	1	B	39	Building Engineer's Restroom beside Boy's Restroom	Yes	Ceiling	Plaster	White	Flaking	3	21.3	Positive
2190	1	B	39	Building Engineer's Restroom beside Boy's Restroom	Yes	W1	Brick	White	Cracking	1	24.4	Positive
2190	1	B	39	Building Engineer's Restroom beside Boy's Restroom	Yes	W3	Brick	White	Cracking	3	22.1	Positive
2190	1	B	S05	Stairwell beside Cafeteria B	Yes	Ceiling	Plaster	White	None	0	N/A	N/A
2190	1	B	S05	Stairwell beside Cafeteria B	Yes	Floor	Concrete	N/A	N/A	0	N/A	N/A

			Inspection Dates: 09/21/20-09/29/20				Lead Safe Certification Assessment Report						
			Name of Inspector: Michael Barth				Fell Elementary School						
			Inspection Company: Criterion Labs										
ULCS#	Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm <sup>2</sup> )	XRF (positive/negative)	
2190	1	B	S05	Stairwell beside Cafeteria B	Yes	Floor	Concrete	Grey	None	0	N/A	N/A	
2190	1	B	39	Building Engineer's Restroom beside Boy's Restroom	Yes	W4	Brick	White	Cracking	1	23.5	Positive	
2190	1	B	36	Building Engineers Office (accessed from Gymnasium)	Yes	Ceiling	Metal	Tan	Chipping	2	12.3	Positive	
2190	1	1	111	Main Office	Yes	W3	Wood	Black	Chipping	1	0.01	Negative	
	1	2	H28	Center Hallway	Yes	Floor	Concrete	Grey	Friction	10	4	Positive	
2190	1	1	111	Main Office	Yes	W4	Wood	Black	Chipping	1	0.04	Negative	
2190	1	2	H28	Center Hallway	Yes	W1	Plaster	Red/Yellow	Cracking	5	21.3	Positive	
2190	1	1	S15	Stairwell beside Classroom 102	Yes	W1	Metal	Blue	Friction	1	0.21	Negative	
2190	1	2	H28	Center Hallway	Yes	W3	Plaster	Red/Yellow	Chipping	5	23.1	Positive	
2190	1	B	S05A	Visitors Entrance Foyer to Northeast Stairwell beside Cafeteria B	Yes	Ceiling	Plaster	Blue	None	0	N/A	N/A	
2190	1	B	S05A	Visitors Entrance Foyer to Northeast Stairwell beside Cafeteria B	Yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
2190	1	B	30	Boiler Room	No	W1	Brick	Blue	Cracking	25	21.2	Positive	
2190	1	B	30	Boiler Room	No	W2	Brick	Blue	Cracking	20	23.2	Positive	
2190	1	B	30	Boiler Room	No	W3	Brick	Blue	Cracking	30	26.1	Positive	
2190	1	B	30	Boiler Room	No	W4	Brick	Blue	Cracking	30	22.1	Positive	
2190	1	B	30	Boiler Room	No	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	
2190	1	B	30	Boiler Room	No	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
2190	1	1	H15	Center Hallway between Classrooms 103 - 106	Yes	Floor	Concrete	Grey	Friction	10	3.4	Positive	
2190	1	B	H02	Hallway outside of Cafeteria B	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A	
2190	1	1	H15	Center Hallway between Classrooms 103 - 106	Yes	W3	Metal	Gray	Chipping	1	1.8	Positive	
2190	1	1	H15	Center Hallway between Classrooms 103 - 106	Yes	Ceiling	Metal	Tan	Chipping	1	5.4	Positive	
2190	1	1	H15	Center Hallway between Classrooms 103 - 106	Yes	W1	Plaster	Red	Cracking	2	21.4	Positive	
2190	1	1	S11	Stairwell beside Classroom 107	Yes	W3	Metal	Blue	Friction	1	0.21	Negative	

				Inspection Dates: 09/21/20-09/29/20									
				Name of Inspector: Michael Barth			Lead Safe Certification Assessment Report						
				Inspection Company: Criterion Labs			Fell Elementary School						
ULCS#	Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm <sup>2</sup> )	XRF (positive/negative)	
2190	1	B	H02	Hallway outside of Cafeteria B	Yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
2190	1	B	B1	Kitchen Storage Room 1	No	W1	Plaster	Tan	None	0	25.3	Positive	
2190	1	B	B1	Kitchen Storage Room 1	No	W2	Plaster	Tan	Cracking	2	21.5	Positive	
2190	1	B	B1	Kitchen Storage Room 1	No	W3	Plaster	Tan	Cracking	1	24.3	Positive	
2190	1	B	B1	Kitchen Storage Room 1	No	W4	Plaster	Tan	Cracking	2	22.7	Positive	
2190	1	B	B1	Kitchen Storage Room 1	No	Ceiling	Plaster	Tan	None	0	N/A	N/A	
2190	1	1	S12	Stairwell across from 109	Yes	W1	Metal	Blue	Friction	1	0.2	Negative	
2190	1	B	B1	Kitchen Storage Room 1	No	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
2190	1	B	B2	Kitchen Storage Room 2	No	W1	No Access	No Access	No Access	No Access	No Access	No Access	
2190	1	B	B2	Kitchen Storage Room 2	No	W2	No Access	No Access	No Access	No Access	No Access	No Access	
2190	1	B	B2	Kitchen Storage Room 2	No	W3	No Access	No Access	No Access	No Access	No Access	No Access	
2190	1	B	B2	Kitchen Storage Room 2	No	W4	No Access	No Access	No Access	No Access	No Access	No Access	
2190	1	B	B2	Kitchen Storage Room 2	No	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	
2190	1	B	B2	Kitchen Storage Room 2	No	Floor	No Access	No Access	No Access	No Access	No Access	No Access	
2190	1	B	B3	Kitchen Storage Room 3	Yes	W1	Plaster	Tan	None	0	21.2	Positive	
2190	1	B	B3	Kitchen Storage Room 3	Yes	W2	Plaster	Tan	None	0	22.4	Positive	
2190	1	B	B3	Kitchen Storage Room 3	Yes	W3	Plaster	Tan	None	0	24.1	Positive	
2190	1	1	107A	Women's Restroom	Yes	W2	Metal	Blue	None	0	0.3	Negative	
2190	1	B	B3	Kitchen Storage Room 3	Yes	W4	Plaster	Tan	None	0	23.2	Positive	
2190	1	1	S10	Stairwell outside of Main Office	Yes	W3	Metal	Brown	Friction	1	0.1	Negative	
2190	1	B	B3	Kitchen Storage Room 3	Yes	Ceiling	Plaster	Tan	None	0	N/A	N/A	
2190	1	B	B3	Kitchen Storage Room 3	Yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
2190	1	1	H15	Center Hallway between Classrooms 103 - 106	Yes	W1	Plaster	Yellow	Flaking	5	22.7	Positive	
2190	1	B	B4	Kitchen Serving Line	No	W2	N/A	N/A	N/A	N/A	N/A	N/A	
2190	1	1	H15	Center Hallway between Classrooms 103 - 106	Yes	W3	Plaster	Red	Cracking	3	21.4	Positive	
2190	1	1	100	Classroom 100	Yes	W3	Plaster	Tan	Chipping	3	21.2	Positive	
2190	1	B	B4	Kitchen Serving Line	No	Ceiling	Concrete	Tan	None	0	N/A	N/A	
2190	1	B	B4	Kitchen Serving Line	No	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
2190	1	1	101	Classroom 101	Yes	W3	Metal	Grey	Chipping	5	1.5	Positive	
2190	1	1	102	Classroom 102	Yes	W2	Plaster	Tan	Cracking	1	22.3	Positive	

				Inspection Dates: 09/21/20-09/29/20									
				Name of Inspector: Michael Barth			Lead Safe Certification Assessment Report						
				Inspection Company: Criterion Labs			Fell Elementary School						
ULCS#	Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)	
2190	1	1	102	Classroom 102	Yes	W3	Plaster	Tan	Chipping	2	24.1	Positive	
2190	1	1	102	Classroom 102	Yes	W4	Plaster	Tan	Cracking	5	19.8	Positive	
2190	1	1	103	Classroom 103	Yes	W3	Metal	Grey	Chipping	3	1.6	Positive	
2190	1	1	112	Auditorium	Yes	W2	Metal	Brown	Friction	2	0.2	Negative	
2190	1	B	34	Gymnasium	Yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
2190	1	B	31	Gas Main/Storage	No	W1	Brick	Blue	Cracking	20	21.3	Positive	
2190	1	B	31	Gas Main/Storage	No	W2	Brick	Blue	Cracking	15	29.6	Positive	
2190	1	B	31	Gas Main/Storage	No	W3	Brick	Blue	Cracking	10	32.1	Positive	
2190	1	B	31	Gas Main/Storage	No	W4	Brick	Blue	Cracking	20	15.6	Positive	
2190	1	B	31	Gas Main/Storage	No	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	
2190	1	B	31	Gas Main/Storage	No	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
2190	1	B	32	Emergency Generator/Storage	No	W1	Brick	Blue	Cracking	15	19.6	Positive	
2190	1	B	32	Emergency Generator/Storage	No	W2	Brick	Blue	Cracking	15	21.3	Positive	
2190	1	B	32	Emergency Generator/Storage	No	W3	Brick	Blue	Cracking	20	25.4	Positive	
2190	1	B	32	Emergency Generator/Storage	No	W4	Brick	Blue	Cracking	10	21.2	Positive	
2190	1	B	32	Emergency Generator/Storage	No	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	
2190	1	B	32	Emergency Generator/Storage	No	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
2190	1	B	33	Fan Room	No	W1	Brick	Blue	Cracking	12	26.5	Positive	
2190	1	B	33	Fan Room	No	W2	Brick	Blue	Cracking	15	24.3	Positive	
2190	1	B	33	Fan Room	No	W3	Brick	Blue	Cracking	10	26.1	Positive	
2190	1	B	33	Fan Room	No	W4	Brick	Blue	Cracking	10	21.2	Positive	
2190	1	B	33	Fan Room	No	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	
2190	1	B	33	Fan Room	No	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
2190	1	B	38	Gymnasium Storage	Yes	W1	Brick	White	Partially Inaccessible	0	21.3	Positive	
2190	1	B	38	Gymnasium Storage	Yes	W2	Brick	White	Partially Inaccessible	0	N/A	N/A	
2190	1	B	38	Gymnasium Storage	Yes	W3	Brick	White	Partially Inaccessible	0	18.9	Positive	
2190	1	B	38	Gymnasium Storage	Yes	W4	Brick	White	Partially Inaccessible	0	21.7	Positive	
2190	1	B	38	Gymnasium Storage	Yes	Ceiling	Plaster	White	Partially Inaccessible	0	22.8	Positive	
2190	1	1	112	Auditorium	Yes	W3	Metal	Brown	Friction	2	0.2	Negative	

				Inspection Dates: 09/21/20-09/29/20								
				Name of Inspector: Michael Barth			Lead Safe Certification Assessment Report					
				Inspection Company: Criterion Labs			Fell Elementary School					
ULCS#	Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm <sup>2</sup> )	XRF (positive/negative)
2190	1	B	38	Gymnasium Storage	Yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
2190	1	B	S04	Fire Stair Tower	Yes	W1	Brick	White	None	0	24.7	Positive
2190	1	1	103A	Classroom 103 Coat Closet	Yes	W2	Plaster	Tan	Cracking	2	22.1	Positive
2190	1	B	S04	Fire Stair Tower	Yes	W3	Brick	White	None	0	23.2	Positive
2190	1	B	S04	Fire Stair Tower	Yes	W4	Brick	White	None	0	20.2	Positive
2190	1	1	103A	Classroom 103 Coat Closet	Yes	W4	Plaster	Tan	Chipping	2	21.2	Positive
2190	1	B	S04	Fire Stair Tower	Yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
2190	1	1	104	Classroom 104	Yes	W3	Metal	Grey	Chipping	5	1.8	Positive
2190	1	1	104	Classroom 104	Yes	W3	Plaster	Tan	Cracking	2	21.3	Positive
2190	1	1	104A	Classroom 104 Coat Closet	Yes	W3	Metal	Tan	Chipping	1	4.5	Positive
2190	1	1	104A	Classroom 104 Coat Closet	Yes	W2	Plaster	Tan	Cracking	2	23.2	Positive
2190	1	1	104A	Classroom 104 Coat Closet	Yes	W4	Plaster	Tan	Alligatoring/Cracking	8	27.4	Positive
2190	1	1	101B	Counselor	yes	W1	Wood	Brown	Chipping	2	0.06	Negative
2190	1	B	37	Gymnasium Office	Yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
2190	1	B	36	Building Engineers Office (accessed from Gymnasium)	Yes	W1	Brick	White	None	0	N/A	N/A
2190	1	B	36	Building Engineers Office (accessed from Gymnasium)	Yes	W2	Brick	White	None	0	N/A	N/A
2190	1	B	36	Building Engineers Office (accessed from Gymnasium)	Yes	W3	Brick	White	None	0	N/A	N/A
2190	1	B	36	Building Engineers Office (accessed from Gymnasium)	Yes	W4	Brick	White	None	0	N/A	N/A
2190	1	B	36	Building Engineers Office (accessed from Gymnasium)	Yes	Ceiling	Plaster	White	None	0	N/A	N/A
2190	1	1	101B	Counselor	yes	W2	Wood	Brown	Chipping	1	0	Negative
2190	1	B	36	Building Engineers Office (accessed from Gymnasium)	Yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
2190	1	B	S02	Stairwell and Foyer beside Boy's Restroom	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
2190	1	1	105	Classroom 105	Yes	W3	Metal	Grey	Chipping	3	1.8	Positive



				Inspection Dates: 09/21/20-09/29/20									
				Name of Inspector: Michael Barth			Lead Safe Certification Assessment Report						
				Inspection Company: Criterion Labs			Fell Elementary School						
ULCS#	Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm <sup>2</sup> )	XRF (positive/negative)	
2190	1	1	105	Classroom 105	Yes	W1	Plaster	Tan	Cracking	1	23.7	Positive	
2190	1	1	101B	Counselor	yes	W3	Wood	Brown	Chipping	1	0.03	Negative	
2190	1	1	105	Classroom 105	Yes	W3	Plaster	Tan	Chipping	5	22.4	Positive	
2190	1	B	S02	Stairwell and Foyer beside Boy's Restroom	Yes	Ceiling	Plaster	White	None	0	N/A	N/A	
2190	1	B	S02	Stairwell and Foyer beside Boy's Restroom	Yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
2190	1	B	S02	Stairwell and Foyer beside Boy's Restroom	Yes	Floor	Concrete	Grey	None	0	3.9	Positive	
2190	1	B	S02	Stairwell and Foyer beside Boy's Restroom	Yes	Floor	Concrete	Grey	Friction	2	0.2	Negative	
2190	1	1	106	Classroom 106	Yes	W3	Metal	Grey	Chipping	5	1.4	Positive	
2190	1	1	106	Classroom 106	Yes	W1	Plaster	Tan	Chipping	1	23.1	Positive	
2190	1	1	106	Classroom 106	Yes	W2	Plaster	Tan	Cracking	3	22.7	Positive	
2190	1	B	40	Boy's Restroom beside Speech Classroom	Yes	W4	Brick	White	None	0	23.5	Positive	
2190	1	1	106	Classroom 106	Yes	W3	Plaster	Tan	Cracking	6	21.3	Positive	
2190	1	B	40	Boy's Restroom beside Speech Classroom	Yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
2190	1	1	106A	Classroom 106 Coat Closet	Yes	W1	Plaster	Tan	Cracking	5	21.5	Positive	
2190	1	1	106A	Classroom 106 Coat Closet	Yes	W2	Plaster	Tan	Cracking	10	21.2	Positive	
2190	1	1	106A	Classroom 106 Coat Closet	Yes	W4	Plaster	Tan	Cracking	10	23.4	Positive	
2190	1	1	107	Classroom 107	Yes	W1	Plaster	Tan	Cracking	1	21.4	Positive	
2190	1	1	107	Classroom 107	Yes	W3	Plaster	Tan	Flaking	15	21.7	Positive	
2190	1	B	39	Building Engineer's Restroom beside Boy's Restroom	Yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
2190	1	1	107	Classroom 107	Yes	W4	Plaster	Tan	Chipping	1	24.5	Positive	
2190	1	1	107A	Classroom 107 Coat Closet	Yes	W4	Plaster	Green	Cracking	10	21.4	Positive	
2190	1	1	107A	Classroom 107 Coat Closet	Yes	W4	Plaster	Blue	Chipping	1	23.4	Positive	
2190	1	1	107B	Classroom 107 Restroom	Yes	W1	Plaster	Tan	Cracking	1	19.1	Positive	
2190	1	1	107B	Classroom 107 Restroom	Yes	W2	Plaster	Tan	Cracking	2	23.1	Positive	
2190	1	1	101B	Counselor	yes	W4	Wood	Brown	Chipping	1	0.01	Negative	
2190	1	B	H01	Hallway outside Rooms 1-3	Yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
2190	1	1	107B	Classroom 107 Restroom	Yes	W4	Plaster	Tan	Chipping	1	21.2	Positive	

				Inspection Dates: 09/21/20-09/29/20									
				Name of Inspector: Michael Barth			Lead Safe Certification Assessment Report						
				Inspection Company: Criterion Labs			Fell Elementary School						
ULCS#	Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm <sup>2</sup> )	XRF (positive/negative)	
2190	1	1	108	Classroom 108	Yes	W3	Plaster	Tan	Moisture Damage	3	23.6	Positive	
2190	1	1	108A	Classroom 108 Coat Closet	Yes	W2	Plaster	Tan	Cracking	6	22.1	Positive	
2190	1	1	108A	Classroom 108 Coat Closet	Yes	W4	Plaster	Tan	Cracking	10	29.1	Positive	
2190	1	1	109	Classroom 109	Yes	W1	Plaster	Tan	Chipping	3	17.8	Positive	
2190	1	B	RM1	Speech	Yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
2190	1	1	109	Classroom 109	Yes	W2	Plaster	Tan	Partially Inaccessible/Cracking	5	22.1	Positive	
2190	1	1	109	Classroom 109	Yes	W3	Plaster	Tan	Cracking	3	24.5	Positive	
2190	1	1	109	Classroom 109	Yes	W4	Plaster	Tan	Chipping	2	21.1	Positive	
2190	1	1	109A	Classroom 109 Coat Closet	Yes	W2	Metal	Tan	Flaking	3	5.4	Positive	
2190	1	B	1A	RM1 Storage Closet	Yes	Ceiling	Plaster	Tan	None	0	N/A	N/A	
2190	1	1	109A	Classroom 109 Coat Closet	Yes	W1	Plaster	Tan	Cracking	2	21.3	Positive	
2190	1	B	1A	RM1 Storage Closet	Yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
2190	1	1	109A	Classroom 109 Coat Closet	Yes	W3	Plaster	Tan	Cracking/Flaking	10	23.5	Positive	
2190	1	1	109A	Classroom 109 Coat Closet	Yes	W4	Plaster	Tan	Cracking	8	24.7	Positive	
2190	1	B	RM2	Music Room	Yes	W2	Brick	Tan	None	0	18.7	Positive	
2190	1	2	200	Classroom 200	Yes	W1	Plaster	Tan	Cracking/Flaking	15	21.4	Positive	
2190	1	2	200	Classroom 200	Yes	W2	Plaster	Tan	Cracking/Flaking	20	22.5	Positive	
2190	1	2	200	Classroom 200	Yes	W3	Plaster	Tan	Cracking	10	26.7	Positive	
2190	1	2	200	Classroom 200	Yes	W3	Plaster	White	Flaking	15	23.2	Positive	
2190	1	B	RM2	Music Room	Yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
2190	1	B	2A	RM2 Storage Closet A	Yes	W1	Plaster	Tan	None	0	18.9	Positive	
2190	1	B	2A	RM2 Storage Closet A	Yes	W2	Plaster	Tan	None	0	24.6	Positive	
2190	1	B	2A	RM2 Storage Closet A	Yes	W3	Plaster	Tan	None	0	23.2	Positive	
2190	1	B	2A	RM2 Storage Closet A	Yes	W4	Plaster	Tan	None	0	22.7	Positive	
2190	1	B	2A	RM2 Storage Closet A	Yes	Ceiling	Plaster	Tan	None	0	21.2	Positive	
2190	1	2	200	Classroom 200	Yes	W4	Plaster	Tan	Cracking/flaking	20	24.1	Positive	
2190	1	1	H15	Center Hallway between Classrooms 103 - 106	Yes	W1	Metal	Gray	Chipping	1	0.1	Negative	
2190	1	2	200	Classroom 200	Yes	W4	Plaster	White	Chipping	3	26.3	Positive	
2190	1	2	200	Classroom 200	Yes	W4	Wood	Tan	Chipping	1	12.2	Positive	

				Inspection Dates: 09/21/20-09/29/20								
				Name of Inspector: Michael Barth		Lead Safe Certification Assessment Report						
				Inspection Company: Criterion Labs		Fell Elementary School						
ULCS#	Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm <sup>2</sup> )	XRF (positive/negative)
2190	1	2	200A	Classroom 200 Coat Closet	Yes	W3	Metal	Grey	Chipping	2	1.7	Positive
2190	1	2	200A	Classroom 200 Coat Closet	Yes	W1	Plaster	Tan	Cracking	3	24.6	Positive
2190	1	2	200A	Classroom 200 Coat Closet	Yes	W2	Plaster	Tan	Cracking/Partially Inaccessible	5	21.3	Positive
2190	1	1	H15	Center Hallway between Classrooms 103 - 106	Yes	W3	Metal	Gray	Chipping	1	0.21	Negative
2190	1	2	200A	Classroom 200 Coat Closet	Yes	W3	Plaster	Tan	Flaking	8	23.1	Positive
2190	1	2	200A	Classroom 200 Coat Closet	Yes	W4	Plaster	Tan	Cracking/Partially Inaccessible	5	19.2	Positive
2190	1	2	201	Classroom 201	Yes	W3	Metal	Grey	Chipping	6	1.7	Positive
2190	1	2	201	Classroom 201	Yes	W1	Plaster	Tan	Chipping	1	24.1	Positive
2190	1	2	201	Classroom 201	Yes	W3	Plaster	Tan	Cracking	8	23.6	Positive
2190	1	B	RM3	Facilities Storage (former classroom)	Yes	Floor	Concrete	Blue	Friction	15	0.2	Negative
2190	1	2	201	Classroom 201	Yes	W4	Plaster	Tan	Flaking	2	26.1	Positive
2190	1	2	201A	Classroom 201 Coat Closet	Yes	W1	Plaster	Tan	Cracking/Alligatoring	5	24.1	Positive
2190	1	2	201A	Classroom 201 Coat Closet	Yes	W2	Plaster	Tan	Flaking	10	23.3	Positive
2190	1	2	201A	Classroom 201 Coat Closet	Yes	W4	Plaster	Tan	Cracking/Alligatoring	12	21.3	Positive
2190	1	2	202	Classroom 202	Yes	W1	Plaster	Tan	Cracking	3	24.2	Positive
2190	1	B	3A	RM3 Storage Closet A	Yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
2190	1	2	202	Classroom 202	Yes	W2	Plaster	Tan	Cracking	1	23.4	Positive
2190	1	2	202	Classroom 202	Yes	W3	Plaster	Tan	Chipping	10	22.3	Positive
2190	1	2	202	Classroom 202	Yes	W2	Wood	Tan	Cracking	1	12.4	Positive
2190	1	2	202	Classroom 202	Yes	W3	Wood	Tan	Cracking	1	11.5	Positive
2190	1	B	S01	Stairwell beside Basement Facilities Storage Room	Yes	Ceiling	Plaster	White	None	0	N/A	N/A
2190	1	B	S01	Stairwell beside Basement Facilities Storage Room	Yes	Floor	Concrete	N/A	N/A	0	N/A	N/A
2190	1	B	S01	Stairwell beside Basement Facilities Storage Room	Yes	Floor	Concrete	Grey	None	0	N/A	N/A
2190	1	2	203	Classroom 203	Yes	W3	Metal	Grey	Chipping	1	1.8	Positive
2190	1	2	203	Classroom 203	Yes	W1	Plaster	Tan	Cracking	15	22.3	Positive

				Inspection Dates: 09/21/20-09/29/20									
				Name of Inspector: Michael Barth			Lead Safe Certification Assessment Report						
				Inspection Company: Criterion Labs			Fell Elementary School						
ULCS#	Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)	
2190	1	1	107A	Classroom 107 Coat Closet	Yes	W3	Metal	Green	None	0	0.22	Negative	
2190	1	2	203	Classroom 203	Yes	W3	Plaster	Tan	Cracking	15	21.4	Positive	
2190	1	1	100	Classroom 100	Yes	W3	Metal	Grey	Chipping	1	0.21	Negative	
2190	1	B	S01A	Northwest Stairwell Entrance Vestibule beside Room 3	Yes	W3	Plaster	Blue	None	0	N/A	N/A	
2190	1	2	203	Classroom 203	Yes	W3	Plaster	White	Chipping	1	22.5	Positive	
2190	1	B	S01A	Northwest Stairwell Entrance Vestibule beside Room 3	Yes	W4	Plaster	Blue	None	0	N/A	N/A	
2190	1	B	S01A	Northwest Stairwell Entrance Vestibule beside Room 3	Yes	Ceiling	Plaster	Blue	Partially Inaccessible	0	N/A	N/A	
2190	1	B	S01A	Northwest Stairwell Entrance Vestibule beside Room 3	Yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
2190	1	1	100	Classroom 100	Yes	W1	Plaster	Tan	None	0	23.1	Positive	
2190	1	1	100	Classroom 100	Yes	W2	Plaster	Tan	None	0	24.1	Positive	
2190	1	2	203	Classroom 203	Yes	W4	Plaster	Tan	Cracking	15	24.5	Positive	
2190	1	2	203	Classroom 203	Yes	W4	Plaster	White	Cracking	1	22.6	Positive	
2190	1	1	100	Classroom 100	Yes	W4	Plaster	Tan	None	0	24.1	Positive	
2190	1	1	100	Classroom 100	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	
2190	1	1	102	Classroom 102	Yes	W3	Metal	Grey	Chipping	3	0.3	Negative	
2190	1	1	100A	Classroom 100 Coat Closet	Yes	W1	No Access	No Access	No Access	No Access	No Access	No Access	
2190	1	1	100A	Classroom 100 Coat Closet	Yes	W2	No Access	No Access	No Access	No Access	No Access	No Access	
2190	1	1	100A	Classroom 100 Coat Closet	Yes	W3	No Access	No Access	No Access	No Access	No Access	No Access	
2190	1	1	100A	Classroom 100 Coat Closet	Yes	W4	No Access	No Access	No Access	No Access	No Access	No Access	
2190	1	1	100A	Classroom 100 Coat Closet	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	
2190	1	1	100A	Classroom 100 Coat Closet	Yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access	
2190	1	1	100B	Classroom 100 Restroom	Yes	W1	No Access	No Access	No Access	No Access	No Access	No Access	
2190	1	1	100B	Classroom 100 Restroom	Yes	W2	No Access	No Access	No Access	No Access	No Access	No Access	

				Inspection Dates: 09/21/20-09/29/20								
				Name of Inspector: Michael Barth		Lead Safe Certification Assessment Report						
				Inspection Company: Criterion Labs		Fell Elementary School						
ULCS#	Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm <sup>2</sup> )	XRF (positive/negative)
2190	1	1	100B	Classroom 100 Restroom	Yes	W3	No Access	No Access	No Access	No Access	No Access	No Access
2190	1	1	100B	Classroom 100 Restroom	Yes	W4	No Access	No Access	No Access	No Access	No Access	No Access
2190	1	1	100B	Classroom 100 Restroom	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
2190	1	1	100B	Classroom 100 Restroom	Yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access
2190	1	2	204	Classroom 204	Yes	W3	Metal	Gray	Chipping	8	1.8	Positive
2190	1	1	100C	Women's Restroom	Yes	W2	Plaster	Tan	None	0	24.1	Positive
2190	1	2	204	Classroom 204	Yes	W3	Plaster	Tan	Chipping	1	23.4	Positive
2190	1	2	206B	Classroom 206 Closet B	Yes	W4	Plaster	White	Cracking	1	23.2	Positive
2190	1	1	100C	Women's Restroom	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2190	1	1	100C	Women's Restroom	Yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
2190	1	1	S10	Stairwell outside of Main Office	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
2190	1	2	207	Classroom 207	Yes	W1	Plaster	Tan	Flaking	10	22.1	Positive
2190	1	2	207	Classroom 207	Yes	W2	Plaster	Tan	Cracking	5	23.2	Positive
2190	1	2	207	Classroom 207	Yes	W3	Plaster	Tan	Cracking	3	24.6	Positive
2190	1	1	S10	Stairwell outside of Main Office	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2190	1	1	S10	Stairwell outside of Main Office	Yes	Floor	Concrete	N/A	N/A	0	N/A	N/A
2190	1	1	S10	Stairwell outside of Main Office	Yes	Floor	Concrete	Grey	None	0	0.11	Negative
2190	1	2	207	Classroom 207	Yes	W3	Wood	Tan	Chipping	1	12.4	Positive
2190	1	2	207	Classroom 207	Yes	W3	Wood	Tan	Chipping	1	9.6	Positive
2190	1	2	207A	Classroom 207 Coat Closet	Yes	W1	Plaster	White	Cracking	5	22.3	Positive
2190	1	1	H16	East Hallway	Yes	W2	Plaster	Yellow	None	0	23.4	Negative
2190	1	1	H16	East Hallway	Yes	W3	Plaster	Red	None	0	25.7	Positive
2190	1	1	H16	East Hallway	Yes	W3	Plaster	Yellow	None	0	22.3	Positive
2190	1	2	207A	Classroom 207 Coat Closet	Yes	W2	Plaster	White	Cracking	15	21.7	Positive
2190	1	1	H16	East Hallway	Yes	W4	Plaster	Yellow	None	0	24.1	Positive
2190	1	1	H16	East Hallway	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2190	1	1	H16	East Hallway	Yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
2190	1	2	207A	Classroom 207 Coat Closet	Yes	W3	Plaster	White	Partially Inaccessible/Cracking	3	21.2	Positive
2190	1	1	101	Classroom 101	Yes	W1	Plaster	Tan	None	0	21.2	Positive

			Inspection Dates: 09/21/20-09/29/20										
			Name of Inspector: Michael Barth		Lead Safe Certification Assessment Report								
			Inspection Company: Criterion Labs		Fell Elementary School								
ULCS#	Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm <sup>2</sup> )	XRF (positive/negative)	
2190	1	1	101	Classroom 101	Yes	W2	Plaster	Tan	None	0	22.3	Positive	
2190	1	1	101	Classroom 101	Yes	W3	Plaster	Tan	None	0	24.1	Positive	
2190	1	2	207A	Classroom 207 Coat Closet	Yes	W4	Plaster	White	Cracking/Chipping	10	22.3	Positive	
2190	1	1	101	Classroom 101	Yes	W4	Plaster	Tan	None	0	23.4	Positive	
2190	1	1	101	Classroom 101	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	
2190	1	2	208	Classroom 208	Yes	W3	Metal	Grey	Chipping	5	2.4	Positive	
2190	1	1	101A	Classroom 101 Coat Closet	Yes	W1	No Access	No Access	No Access	No Access	No Access	No Access	
2190	1	1	101A	Classroom 101 Coat Closet	Yes	W2	No Access	No Access	No Access	No Access	No Access	No Access	
2190	1	1	101A	Classroom 101 Coat Closet	Yes	W3	No Access	No Access	No Access	No Access	No Access	No Access	
2190	1	1	101A	Classroom 101 Coat Closet	Yes	W4	No Access	No Access	No Access	No Access	No Access	No Access	
2190	1	1	101A	Classroom 101 Coat Closet	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	
2190	1	1	101A	Classroom 101 Coat Closet	Yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access	
2190	1	1	101B	Counselor	Yes	W1	Plaster	Tan	None	0	26.5	Positive	
2190	1	2	208	Classroom 208	Yes	W2	Plaster	Tan	Chipping	2	22.1	Positive	
2190	1	2	208	Classroom 208	Yes	W3	Plaster	Tan	Chipping	2	24.7	Positive	
2190	1	2	208	Classroom 208	Yes	W4	Plaster	Tan	Chipping	3	18.9	Positive	
2190	1	2	208A	Classroom 208 Coat Closet	Yes	W1	Plaster	Tan	Flaking	1	24.1	Positive	
2190	1	1	108	Classroom 108	Yes	W3	Metal	Grey	None	0	N/A	N/A	
2190	1	1	109	Classroom 109	Yes	W2	Metal	Grey	Partially Inaccessible	N/A	N/A	N/A	
2190	1	1	101B	Counselor	yes	W4	Plaster	Tan	None	0	23.2	Positive	
2190	1	1	109	Classroom 109	Yes	W3	Metal	Grey	Partially Inaccessible	N/A	N/A	N/A	
2190	1	1	101B	Counselor	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	
2190	1	2	208A	Classroom 208 Coat Closet	Yes	W2	Plaster	Tan	Flaking	5	22	Positive	
2190	1	1	102	Classroom 102	Yes	W1	Plaster	Tan	None	0	21.2	Positive	
2190	1	2	208A	Classroom 208 Coat Closet	Yes	W3	Plaster	Tan	Chipping	1	21.5	Positive	
2190	1	2	208A	Classroom 208 Coat Closet	Yes	W4	Plaster	Tan	Flaking	6	23.2	Positive	
2190	1	2	209	Classroom 209	Yes	W1	Plaster	Tan	Cracking	3	22.7	Positive	
2190	1	2	209	Classroom 209	Yes	W2	Plaster	Tan	Chipping	5	21.4	Positive	

				Inspection Dates: 09/21/20-09/29/20									
				Name of Inspector: Michael Barth			Lead Safe Certification Assessment Report						
				Inspection Company: Criterion Labs			Fell Elementary School						
ULCS#	Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm <sup>2</sup> )	XRF (positive/negative)	
2190	1	1	102	Classroom 102	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	
2190	1	1	112D	Auditorium Stage Dressing Room - Classroom 100 Side	Yes	W3	Metal	Grey	None	0	1.6	Positive	
2190	1	1	102	Classroom 102 closet	Yes	W1	No Access	No Access	No Access	No Access	No Access	No Access	
2190	1	1	102	Classroom 102 closet	Yes	W2	No Access	No Access	No Access	No Access	No Access	No Access	
2190	1	1	102	Classroom 102 closet	Yes	W3	No Access	No Access	No Access	No Access	No Access	No Access	
2190	1	1	102	Classroom 102 closet	Yes	W4	No Access	No Access	No Access	No Access	No Access	No Access	
2190	1	1	102	Classroom 102 closet	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	
2190	1	1	102	Classroom 102 closet	Yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access	
2190	1	1	102A	Classroom 102 Coat Closet	Yes	W1	No Access	No Access	No Access	No Access	No Access	No Access	
2190	1	1	102A	Classroom 102 Coat Closet	Yes	W2	No Access	No Access	No Access	No Access	No Access	No Access	
2190	1	1	102A	Classroom 102 Coat Closet	Yes	W3	No Access	No Access	No Access	No Access	No Access	No Access	
2190	1	1	102A	Classroom 102 Coat Closet	Yes	W4	No Access	No Access	No Access	No Access	No Access	No Access	
2190	1	1	102A	Classroom 102 Coat Closet	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	
2190	1	1	102A	Classroom 102 Coat Closet	Yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access	
2190	1	1	PC102A	Classroom 102 Coat Closet Pipe Chase	Yes	W1	No Access	No Access	No Access	No Access	No Access	No Access	
2190	1	1	PC102A	Classroom 102 Coat Closet Pipe Chase	Yes	W2	No Access	No Access	No Access	No Access	No Access	No Access	
2190	1	1	PC102A	Classroom 102 Coat Closet Pipe Chase	Yes	W3	No Access	No Access	No Access	No Access	No Access	No Access	
2190	1	1	PC102A	Classroom 102 Coat Closet Pipe Chase	Yes	W4	No Access	No Access	No Access	No Access	No Access	No Access	
2190	1	1	PC102A	Classroom 102 Coat Closet Pipe Chase	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	
2190	1	1	PC102A	Classroom 102 Coat Closet Pipe Chase	Yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access	
2190	1	1	102B	Classroom 102 Restroom	Yes	W1	Plaster	Tan	None	0	21.4	Positive	
2190	1	1	102B	Classroom 102 Restroom	Yes	W2	Plaster	Tan	None	0	23.2	Positive	

				Inspection Dates: 09/21/20-09/29/20								
				Name of Inspector: Michael Barth			Lead Safe Certification Assessment Report					
				Inspection Company: Criterion Labs			Fell Elementary School					
ULCS#	Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm <sup>2</sup> )	XRF (positive/negative)
2190	1	1	102B	Classroom 102 Restroom	Yes	W3	Plaster	Tan	None	0	24.2	Positive
2190	1	1	102B	Classroom 102 Restroom	Yes	W4	Plaster	Tan	None	0	22.4	Positive
2190	1	1	102B	Classroom 102 Restroom	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2190	1	1	109	Classroom 109	Yes	W4	Wood	Grey	None	0	0.03	Negative
2190	1	2	209	Classroom 209	Yes	W3	Plaster	Tan	Cracking/Chipping	5	23.4	Positive
2190	1	2	209	Classroom 209	Yes	W4	Plaster	Tan	Cracking	3	22.9	Positive
2190	1	2	209	Classroom 209	Yes	W2	Wood	Tan	Chipping	1	12.2	Positive
2190	1	2	209	Classroom 209	Yes	W3	Wood	Tan	Chipping	1	16.7	Positive
2190	1	1	S15	Stairwell beside Classroom 102	Yes	Ceiling	Plaster	White	None	0	N/A	N/A
2190	1	1	S15	Stairwell beside Classroom 102	Yes	Floor	Concrete	N/A	N/A	0	N/A	N/A
2190	1	1	S15	Stairwell beside Classroom 102	Yes	Floor	Concrete	Grey	None	0	0.11	Negative
2190	1	2	209A	Classroom 209 Coat Closet	Yes	W3	Plaster	White	Flaking	10	24.1	Positive
2190	1	1	S18	Auditorium Entrance Stairwell across from Classroom 104	Yes	W1	Plaster	Tan	None	0	24.2	Positive
2190	1	1	109A	Classroom 109 Coat Closet	Yes	W3	Metal	Grey	No Access	N/A	N/A	N/A
2190	1	1	S18	Auditorium Entrance Stairwell across from Classroom 104	Yes	W2	Plaster	Tan	None	0	21.3	Positive
2190	1	1	100	Classroom 100	Yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
2190	1	1	S18	Auditorium Entrance Stairwell across from Classroom 104	Yes	W3	Plaster	Tan	None	0	26.1	Positive
2190	1	1	101	Classroom 101	Yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
2190	1	1	S18	Auditorium Entrance Stairwell across from Classroom 104	Yes	W4	Plaster	Tan	None	0	21.4	Positive
2190	1	1	101B	Counselor	Yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
2190	1	1	S18	Auditorium Entrance Stairwell across from Classroom 104	Yes	Ceiling	Plaster	White	Partially Inaccessible	N/A	N/A	N/A
2190	1	1	S18	Auditorium Entrance Stairwell across from Classroom 104	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A



				Inspection Dates: 09/21/20-09/29/20									
				Name of Inspector: Michael Barth			Lead Safe Certification Assessment Report						
				Inspection Company: Criterion Labs			Fell Elementary School						
ULCS#	Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm <sup>2</sup> )	XRF (positive/negative)	
2190	1	2	209A	Classroom 209 Coat Closet	Yes	W4	Plaster	White	Chipping	2	22.1	Positive	
2190	1	1	102	Classroom 102	Yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A	
2190	1	1	S19	Auditorium Entrance Stairwell across from Classroom 105	Yes	W2	Plaster	Tan	None	0	22.1	Positive	
2190	1	1	102B	Classroom 102 Restroom	Yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A	
2190	1	1	S19	Auditorium Entrance Stairwell across from Classroom 105	Yes	W3	Plaster	Tan	None	0	23.1	Positive	
2190	1	1	103	Classroom 103	Yes	W2	Wood	N/A	N/A	N/A	N/A	N/A	
2190	1	1	S19	Auditorium Entrance Stairwell across from Classroom 105	Yes	W4	Plaster	Tan	None	0	24.5	Positive	
2190	1	1	103	Classroom 103	Yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A	
2190	1	1	S19	Auditorium Entrance Stairwell across from Classroom 105	Yes	Ceiling	Plaster	White	Partially Inaccessible	N/A	N/A	N/A	
2190	1	1	S19	Auditorium Entrance Stairwell across from Classroom 105	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
2190	1	3	300	Classroom 300	Yes	W3	Wood	White	Chipping	2	1.6	Positive	
2190	1	3	300	Classroom 300	Yes	W1	Plaster	White	Cracking	3	22.1	Positive	
2190	1	1	104	Classroom 104	Yes	W2	Wood	N/A	N/A	N/A	N/A	N/A	
2190	1	1	104	Classroom 104	Yes	W4	Wood	N/A	N/A	N/A	N/A	N/A	
2190	1	1	104	Classroom 104	Yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A	
2190	1	1	105	Classroom 105	Yes	W2	Wood	N/A	N/A	N/A	N/A	N/A	
2190	1	3	300	Classroom 300	Yes	W4	Wood	White	Chipping	1	1.9	Positive	
2190	1	1	105	Classroom 105	Yes	W4	Wood	N/A	N/A	N/A	N/A	N/A	
2190	1	3	300	Classroom 300	Yes	W2	Plaster	White	Chipping	8	23.6	Positive	
2190	1	3	300	Classroom 300	Yes	W3	Plaster	White	Moisture Damage/Chipping	18	24.1	Positive	
2190	1	1	103B	Girl's Restroom	Yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
2190	1	1	103	Classroom 103	Yes	W1	Plaster	Tan	None	0	24.1	Positive	
2190	1	1	105	Classroom 105	Yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A	
2190	1	1	103	Classroom 103	Yes	W3	Plaster	Tan	None	0	21.4	Positive	
2190	1	1	106	Classroom 106	Yes	W4	Wood	N/A	N/A	N/A	N/A	N/A	
2190	1	1	106	Classroom 106	Yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A	
2190	1	1	103	Classroom 103	Yes	W4	Plaster	Tan	None	0	22.7	Positive	

				Inspection Dates: 09/21/20-09/29/20								
				Name of Inspector: Michael Barth			Lead Safe Certification Assessment Report					
				Inspection Company: Criterion Labs			Fell Elementary School					
ULCS#	Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
2190	1	1	103	Classroom 103	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2190	1	1	108	Classroom 108	Yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
2190	1	1	104	Classroom 104	Yes	W1	Plaster	Tan	None	0	24.1	Positive
2190	1	1	109	Classroom 109	Yes	Ceiling	Wood	N/A	N/A	N/A	N/A	N/A
2190	1	3	300	Classroom 300	Yes	W4	Plaster	White	Chipping	2	21.2	Positive
2190	1	1	110	Principal's Office	Yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
2190	1	1	H16B	Principal's Office Hallway/Storage	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
2190	1	1	104	Classroom 104	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2190	1	1	110B	Principals Office Closet	Yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
2190	1	3	301	Classroom 301	Yes	W1	Plaster	White	Cracking	10	24	Positive
2190	1	1	112	Auditorium	Yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
2190	1	3	301	Classroom 301	Yes	W2	Plaster	White	Chipping	1	27.8	Positive
2190	1	1	112B	Auditorium Stage	Yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
2190	1	1	112C	Auditorium Stage Dressing Room - Classroom 109 Side	Yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
2190	1	1	105	Classroom 105	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2190	1	1	112D	Auditorium Stage Dressing Room - Classroom 100 Side	Yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
2190	1	3	301	Classroom 301	Yes	W3	Plaster	White	Flaking	30	32.1	Positive
2190	1	3	302	Classroom 302	Yes	W2	Wood	White	Chipping	1	1.8	Positive
2190	1	3	302	Classroom 302	Yes	W3	Wood	White	Chipping	1	2.1	Positive
2190	1	1	103A	Classroom 103 Coat Closet	Yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
2190	1	1	107A	Classroom 107 Coat Closet	Yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
2190	1	1	106	Classroom 106	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2190	1	1	108A	Classroom 108 Coat Closet	Yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
2190	1	3	302	Classroom 302	Yes	W1	Plaster	Tan	Cracking	3	27.1	Positive
2190	1	3	302	Classroom 302	Yes	W2	Plaster	Tan	Cracking	5	22.5	Positive
2190	1	1	109A	Classroom 109 Coat Closet	Yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
2190	1	3	302	Classroom 302	Yes	W3	Plaster	Tan	Chipping	8	31.2	Positive
2190	1	1	S11	Stairwell beside Classroom 107	Yes	Ceiling	Plaster	White	None	0	N/A	N/A
2190	1	1	S11	Stairwell beside Classroom 107	Yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A

				Inspection Dates: 09/21/20-09/29/20									
				Name of Inspector: Michael Barth			Lead Safe Certification Assessment Report						
				Inspection Company: Criterion Labs			Fell Elementary School						
ULCS#	Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)	
2190	1	1	S11	Stairwell beside Classroom 107	Yes	Floor	Concrete	Grey	None	0	0.2	Negative	
2190	1	3	302	Classroom 302	Yes	W4	Plaster	Tan	Chipping	5	24.1	Positive	
2190	1	1	S18	Auditorium Entrance Stairwell across from Classroom 104	Yes	W3	Wood	Purple	Friction	3	0.2	Negative	
2190	1	3	303	Classroom 303	Yes	W1	Plaster	Tan	Cracking	2	22.1	Positive	
2190	1	3	303	Classroom 303	Yes	W3	Plaster	Tan	Cracking	5	23.4	Positive	
2190	1	3	303	Classroom 303	Yes	W4	Plaster	Tan	Cracking	2	22.7	Positive	
2190	1	1	S12	Stairwell across from 109	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	
2190	1	1	S12	Stairwell across from 109	Yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
2190	1	1	S12	Stairwell across from 109	Yes	Floor	Concrete	Grey	None	0	0.1	N/A	
2190	1	3	304	Classroom 304	Yes	W3	Metal	Grey	Chipping	5	1.5	Positive	
2190	1	3	304	Classroom 304	Yes	W1	Plaster	Tan	Cracking	3	22.9	Positive	
2190	1	3	304	Classroom 304	Yes	W3	Plaster	Tan	Moisture Damage/Cracking	8	21.8	Positive	
2190	1	3	304A	Classroom 304 Coat Closet	Yes	W1	Plaster	Tan	Cracking	2	22.4	Positive	
2190	1	1	S19	Auditorium Entrance Stairwell across from Classroom 105	Yes	W3	Wood	Purple	Friction	2	0.3	Negative	
2190	1	1	106B	Boy's Restroom	Yes	W3	Plastic	Grey	Flaking	5	0.1	Negative	
2190	1	3	304A	Classroom 304 Coat Closet	Yes	W2	Plaster	Tan	Cracking	3	21.3	Positive	
2190	1	1	H16	East Hallway	Yes	W1	Metal	Red	Friction	1	0.2	Negative	
2190	1	1	H14	West Hallway	Yes	W1	Metal	Red	Friction	2	0.2	Negative	
2190	1	1	106B	Boy's Restroom	Yes	W4	Concrete	Black	None	0	0.2	Negative	
2190	1	3	304A	Classroom 304 Coat Closet	Yes	W3	Plaster	Tan	Partially Inaccessible/Cracking	2	22.5	Positive	
2190	1	1	106B	Boy's Restroom	Yes	Floor	Concrete	Blue	None	0	0.1	Negative	
2190	1	3	304A	Classroom 304 Coat Closet	Yes	W4	Plaster	Tan	Cracking/Chipping	15	24.7	Positive	
2190	1	1	107	Classroom 107	Yes	W2	Plaster	Tan	None	0	22.3	Positive	
2190	1	3	305	Classroom 305	Yes	W1	Plaster	Tan	Chipping	5	25.1	Positive	
2190	1	3	305	Classroom 305	Yes	W3	Plaster	Tan	Moisture Damage/Chipping	25	24.2	Positive	
2190	1	1	107	Classroom 107	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	
2190	1	1	107	Classroom 107	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	

				Inspection Dates: 09/21/20-09/29/20								
				Name of Inspector: Michael Barth		Lead Safe Certification Assessment Report						
				Inspection Company: Criterion Labs		Fell Elementary School						
ULCS#	Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm <sup>2</sup> )	XRF (positive/negative)
2190	1	3	306	Classroom 306	Yes	W1	Plaster	Tan	Cracking/Chipping	5	21.2	Positive
2190	1	3	306	Classroom 306	Yes	W2	Plaster	Tan	Cracking/Chipping	5	25.3	Positive
2190	1	1	107B	Classroom 107 Restroom	Yes	W3	Plaster	Tan	None	0	N/A	N/A
2190	1	3	306	Classroom 306	Yes	W3	Plaster	Tan	Cracking/Chipping/Moisture Damage	10	29.1	Positive
2190	1	1	107B	Classroom 107 Restroom	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2190	1	1	107B	Classroom 107 Restroom	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2190	1	1	108	Classroom 108	Yes	W1	Plaster	Tan	None	0	21.4	Positive
2190	1	1	108	Classroom 108	Yes	W2	Plaster	Tan	None	0	22.5	Positive
2190	1	3	307	Classroom 307	Yes	W1	Plaster	Tan	Cracking	5	22.1	Positive
2190	1	3	307	Classroom 307	Yes	W2	Plaster	Tan	Chipping	10	24.3	Positive
2190	1	1	108	Classroom 108	Yes	W4	Plaster	Tan	None	0	27.6	Positive
2190	1	1	108	Classroom 108	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2190	1	3	307	Classroom 307	Yes	W3	Plaster	Tan	Chipping/Cracking	10	31.2	Positive
2190	1	3	307	Classroom 307	Yes	W4	Plaster	Tan	Cracking	10	21.3	Positive
2190	1	3	307	Classroom 307	Yes	W4	Plaster	White	Cracking	5	26.2	Positive
2190	1	3	308	Classroom 308	Yes	W3	Metal	Grey	Flaking	10	3.1	Positive
2190	1	3	308	Classroom 308	Yes	W2	Plaster	Tan	Chipping/Cracking	2	22.3	Positive
2190	1	3	308	Classroom 308	Yes	W3	Plaster	Tan	Chipping/Cracking	5	24.3	Positive
2190	1	3	309	Classroom 309	Yes	W2	Wood	Tan	Chipping	1	24.7	Positive
2190	1	3	309	Classroom 309	Yes	W3	Wood	Tan	Chipping	1	26.3	Positive
2190	1	1	112A	Handicap Access to Auditorium/Auditorium Storage Closet	Yes	W3	Wood	Tan	Cracking	1	0.21	Negative
2190	1	1	109	Classroom 109	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2190	1	1	109B	Men's Restroom beside Classroom 109	Yes	W1	Plaster	Blue	None	0	21.3	Positive
2190	1	3	309	Classroom 309	Yes	W1	Plaster	Tan	Cracking	5	25.8	Positive
2190	1	1	109B	Men's Restroom beside Classroom 109	Yes	W1	Concrete	Grey	None	0	1.4	Positive
2190	1	1	109B	Men's Restroom beside Classroom 109	Yes	W2	Plaster	Blue	None	0	N/A	N/A
2190	1	3	309	Classroom 309	Yes	W2	Plaster	Tan	Cracking	3	23.5	Positive
2190	1	1	109B	Men's Restroom beside Classroom 109	Yes	W2	Concrete	Grey	None	0	1.6	Positive

				Inspection Dates: 09/21/20-09/29/20								
				Name of Inspector: Michael Barth			Lead Safe Certification Assessment Report					
				Inspection Company: Criterion Labs			Fell Elementary School					
ULCS#	Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm <sup>2</sup> )	XRF (positive/negative)
2190	1	1	109B	Men's Restroom beside Classroom 109	Yes	W3	Plaster	Blue	None	0	N/A	N/A
2190	1	3	309	Classroom 309	Yes	W3	Plaster	Tan	Chipping	5	22.3	Positive
2190	1	1	109B	Men's Restroom beside Classroom 109	Yes	W3	Concrete	Grey	None	0	1.9	Positive
2190	1	3	309	Classroom 309	Yes	W4	Plaster	Tan	Moisture Damage	5	31.2	Positive
2190	1	1	109B	Men's Restroom beside Classroom 109	Yes	W4	Plaster	Blue	None	0	N/A	N/A
2190	1	3	310	Classroom 310	Yes	W3	Plaster	White	Cracking	2	21.4	Positive
2190	1	1	109B	Men's Restroom beside Classroom 109	Yes	W4	Concrete	Grey	None	0	1.6	Positive
2190	1	1	109B	Men's Restroom beside Classroom 109	Yes	Ceiling	Plaster	Tan	None	0	22.3	Positive
2190	1	1	109B	Men's Restroom beside Classroom 109	Yes	Floor	Concrete	Grey	None	0	0.1	Negative
2190	1	3	310	Classroom 310	Yes	W4	Plaster	White	Cracking	3	18.9	Positive
2190	1	1	H15A	Closet across from Classroom 104	Yes	W1	Plaster	White	Moisture Damage	5	21.3	Positive
2190	1	1	H15A	Closet across from Classroom 104	Yes	W2	Plaster	White	Chipping	3	24.7	Positive
2190	1	1	112C	Auditorium Stage Dressing Room - Classroom 109 Side	Yes	W3	Wood	Tan	None	0	12.4	Positive
2190	1	1	H15A	Closet across from Classroom 104	Yes	W3	Plaster	White	Chipping	3	24.5	Positive
2190	1	1	110A	Principal's Office Restroom	Yes	W3	Plaster	Tan	None	0	N/A	N/A
2190	1	1	112D	Auditorium Stage Dressing Room - Classroom 100 Side	Yes	W3	Wood	Tan	None	0	6.4	Positive
2190	1	1	H15A	Closet across from Classroom 104	Yes	W4	Plaster	White	Moisture Damage	8	23.1	Positive
2190	1	1	H15A	Closet across from Classroom 104	Yes	Ceiling	Plaster	White	Moisture Damage	8	22.7	Positive
2190	1	1	103	Classroom 103	Yes	W3	Metal	Tan	Flaking	1	0.2	Negative
2190	1	1	101B	Counselor	Yes	W3	Metal	Grey	Chipping	3	1.5	Positive
2190	1	1	110A	Principal's Office Restroom	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2190	1	1	101B	Counselor	Yes	W2	Plaster	Tan	Chipping	1	16.8	Positive
2190	1	1	101B	Counselor	Yes	W3	Plaster	Tan	Cracking	1	24.1	Positive
2190	1	3	316	Dean	Yes	Floor	Concrete	Grey	Friction	5	4.1	Positive

				Inspection Dates: 09/21/20-09/29/20								
				Name of Inspector: Michael Barth			Lead Safe Certification Assessment Report					
				Inspection Company: Criterion Labs			Fell Elementary School					
ULCS#	Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm <sup>2</sup> )	XRF (positive/negative)
2190	1	1	112	Auditorium	Yes	W3	Metal	Tan	None	0	3.7	Positive
2190	1	1	110	Principal's Office	Yes	W3	Plaster	Tan	None	0	N/A	N/A
2190	1	1	112	Auditorium	Yes	W4	Metal	Tan	Chipping	6	2.4	Negative
2190	1	1	110	Principal's Office	Yes	W4	Plaster	Tan	None	0	N/A	N/A
2190	1	1	112	Auditorium	Yes	W4	Metal	Tan	Friction	5	0.3	Negative
2190	1	1	103A	Classroom 103 Coat Closet	Yes	W3	Metal	Tan	None	0	0.2	Negative
2190	1	1	110	Principal's Office	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2190	1	3	316	Dean	Yes	W3	Metal	Grey	Chipping	2	2.1	Positive
2190	1	1	H16B	Principal's Office Hallway/Storage	yes	W1	Plaster	Tan	None	0	22.4	Positive
2190	1	3	316	Dean	Yes	W1	Plaster	Tan	Cracking	3	23.1	Positive
2190	1	1	H16B	Principal's Office Hallway/Storage	yes	W3	Plaster	Tan	None	0	18.9	Positive
2190	1	1	H16B	Principal's Office Hallway/Storage	yes	W4	Plaster	Tan	Partially Inaccessible	0	23.6	Positive
2190	1	1	H16B	Principal's Office Hallway/Storage	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2190	1	3	316	Dean	Yes	W2	Plaster	Tan	Cracking	2	22.5	Positive
2190	1	3	316	Dean	Yes	W3	Plaster	Tan	Chipping	5	27.6	Positive
2190	1	3	316	Dean	Yes	W4	Plaster	Tan	Cracking	10	21.2	Positive
2190	1	1	S18	Auditorium Entrance Stairwell across from Classroom 104	Yes	W2	Wood	White	None	0	0.2	Negative
2190	1	3	316	Dean	Yes	Ceiling	Plaster	Tan	Cracking	3	21.9	Positive
2190	1	1	S18	Auditorium Entrance Stairwell across from Classroom 104	Yes	W4	Wood	White	None	0	0.21	Negative
2190	1	1	H16	East Hallway	Yes	Floor	Concrete	Grey	Friction	10	3.4	Positive
2190	1	1	H16	East Hallway	Yes	W2	Plaster	Red	Cracking	3	22.1	Positive
2190	1	1	H16	East Hallway	Yes	W4	Plaster	Red	Chipping/Moisture Damage	5	21.3	Positive
2190	1	1	111	Main Office	Yes	W1	Plaster	Tan	None	0	24.1	Positive
2190	1	1	S19	Auditorium Entrance Stairwell across from Classroom 105	Yes	W2	Wood	White	None	0	0.21	Negative
2190	1	B	H03A	East Hallway; South End	Yes	Floor	Concrete	Blue	Friction	1	4.5	Positive
2190	1	1	S19	Auditorium Entrance Stairwell across from Classroom 105	Yes	W4	Wood	White	None	0	0.1	Negative
2190	1	B	H03A	East Hallway; South End	Yes	W2	Brick	White	Alligating	5	21.4	Positive

				Inspection Dates: 09/21/20-09/29/20								
				Name of Inspector: Michael Barth		Lead Safe Certification Assessment Report						
				Inspection Company: Criterion Labs		Fell Elementary School						
ULCS#	Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm <sup>2</sup> )	XRF (positive/negative)
2190	1	1	103B	Girl's Restroom	Yes	W2	Wood	White	None	0	21.3	Positive
2190	1	B	H03A	East Hallway; South End	Yes	W3	Brick	White	Cracking	2	23.5	Positive
2190	1	1	112	Auditorium	Yes	W1	Wood	White	None	0	0.2	Negative
2190	1	1	111	Main Office	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2190	1	1	111	Main Office	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2190	1	1	111B	Main Office Storage Closet	Yes	W1	Plaster	Tan	Partially Inaccessible	0	22.1	Positive
2190	1	B	H03A	East Hallway; South End	Yes	W4	Brick	White	Cracking	5	25.1	Positive
2190	1	1	112	Auditorium	Yes	W2	Wood	White	Cracking	2	0.1	Negative
2190	1	B	RM3	Facilities Storage (former classroom)	Yes	W1	Plaster	White	Cracking	15	18.6	Positive
2190	1	B	RM3	Facilities Storage (former classroom)	Yes	W2	Plaster	Tan	Moisture Damage	51	21.3	Positive
2190	1	B	RM3	Facilities Storage (former classroom)	Yes	W3	Plaster	Tan	Chipping	2	22.9	Positive
2190	1	1	111B	Main Office Storage Closet	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2190	1	1	PC111B	Main Office Storage Closet Pipe Chase	Yes	W1	Terracotta	N/A	N/A	N/A	N/A	N/A
2190	1	1	PC111B	Main Office Storage Closet Pipe Chase	Yes	W2	Terracotta	N/A	N/A	N/A	N/A	N/A
2190	1	1	PC111B	Main Office Storage Closet Pipe Chase	Yes	W3	Terracotta	N/A	N/A	N/A	N/A	N/A
2190	1	1	PC111B	Main Office Storage Closet Pipe Chase	Yes	W4	Terracotta	N/A	N/A	N/A	N/A	N/A
2190	1	1	PC111B	Main Office Storage Closet Pipe Chase	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2190	1	1	PC111B	Main Office Storage Closet Pipe Chase	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2190	1	1	112	Auditorium	Yes	W1	Plaster	Tan	Chipping	10	0.21	Negative
2190	1	1	112	Auditorium	Yes	W3	Wood	White	Chipping	5	0.1	Negative
2190	1	B	RM3	Facilities Storage (former classroom)	Yes	W4	Plaster	Tan	Chipping	1	21.4	Positive
2190	1	1	112	Auditorium	Yes	W2	Plaster	Tan	Chipping	10	0.21	Negative
2190	1	1	112D	Auditorium Stage Dressing Room - Classroom 100 Side	Yes	Ceiling	Wood	White	None	0	9.8	Positive
2190	1	B	RM3	Facilities Storage (former classroom)	Yes	Ceiling	Plaster	Tan	Moisture Damage	25	24.5	Positive
2190	1	1	106B	Boy's Restroom	Yes	W4	Metal	White	Chipping	1	0.3	Negative

				Inspection Dates: 09/21/20-09/29/20								
				Name of Inspector: Michael Barth			Lead Safe Certification Assessment Report					
				Inspection Company: Criterion Labs			Fell Elementary School					
ULCS#	Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm <sup>2</sup> )	XRF (positive/negative)
2190	1	1	110A	Principal's Office Restroom	yes	W2	Metal	White	None	0	0.3	Negative
2190	1	1	112	Auditorium	Yes	W3	Plaster	Tan	Chipping	3	0.2	Negative
2190	1	1	110A	Principal's Office Restroom	yes	W3	Metal	White	Chipping	6	0.4	Negative
2190	1	B	S04	Fire Stair Tower	Yes	Ceiling	Plaster	White	Moisture Damage	1	22.3	Positive
2190	1	B	S04	Fire Stair Tower	Yes	W2	Brick	White	Moisture Damage	1	21.2	Positive
2190	1	1	111B	Main Office Storage Closet	yes	W2	Metal	White	Chipping	1	0.3	Negative
2190	1	1	H15A	Closet across from Classroom 104	Yes	W3	Metal	White	Chipping	1	0.2	Negative
2190	1	1	112	Auditorium	Yes	W4	Plaster	Tan	Cracking	5	0.1	Negative
2190	1	2	S24	Fire Tower Stairwell	Yes	Ceiling	Plaster	White	Moisture Damage	5	23.3	Positive
2190	1	1	103B	Girl's Restroom	yes	W2	Metal	Grey	Cracking	3	3.1	Positive
2190	1	1	103B	Girl's Restroom	Yes	W1	Plaster	Tan	Cracking	2	22.1	Positive
2190	1	1	112	Auditorium	Yes	Ceiling	Plaster	White	No Access	N/A	N/A	N/A
2190	1	2	216	Teacher's Lounge 216	Yes	W3	Wood	Blue	None	0	12.3	Positive
2190	1	1	112B	Auditorium Stage	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
2190	1	1	103B	Girl's Restroom	Yes	W2	Plaster	Tan	Cracking/Moisture Damage	15	24.3	Positive
2190	1	1	103B	Girl's Restroom	Yes	W3	Plaster	Tan	Cracking	1	32.1	Positive
2190	1	1	103B	Girl's Restroom	Yes	W4	Plaster	Tan	Cracking	1	31.3	Positive
2190	1	1	112B	Auditorium Stage	Yes	Ceiling	Plaster	Tan	None	0	N/A	N/A
2190	1	2	207	Classroom 207	Yes	Floor	Wood	Brown	Friction	5	0.22	Negative
2190	1	1	103B	Girl's Restroom	Yes	Ceiling	Plaster	Tan	Moisture Damage	10	25.9	Positive
2190	1	1	103B	Girl's Restroom	yes	W2	Metal	White	Cracking	3	5.4	Positive
2190	1	B	24	Girl's Restroom	Yes	Ceiling	Plaster	White	Moisture Damage	2	21.4	Positive
2190	1	2	208	Classroom 208	Yes	Floor	Wood	Brown	Friction	5	0.11	Negative
2190	1	B	24	Girl's Restroom	Yes	W3	Brick	White	Moisture Damage	2	21.3	Positive
2190	1	B	34	Gymnasium	Yes	Ceiling	Plaster	White	Moisture Damage	10	18.9	Positive
2190	1	1	112A	Handicap Access to Auditorium/Auditorium Storage Closet	Yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
2190	1	B	34	Gymnasium	Yes	W1	Brick	White	Cracking	10	21.3	Positive



				Inspection Dates: 09/21/20-09/29/20									
				Name of Inspector: Michael Barth			Lead Safe Certification Assessment Report						
				Inspection Company: Criterion Labs			Fell Elementary School						
ULCS#	Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm <sup>2</sup> )	XRF (positive/negative)	
2190	1	2	209	Classroom 209	Yes	Floor	Wood	Brown	Friction	5	0.11	Negative	
2190	1	B	34	Gymnasium	Yes	W2	Brick	White	Cracking	5	22.4	Positive	
2190	1	B	34	Gymnasium	Yes	W3	Brick	White	Cracking	5	26.7	Positive	
2190	1	B	34	Gymnasium	Yes	W4	Brick	White	Cracking	10	21.2	Positive	
2190	1	2	207A	Classroom 207 Coat Closet	Yes	Floor	Wood	Brown	Friction	4	0.21	Negative	
2190	1	2	208A	Classroom 208 Coat Closet	Yes	Floor	Wood	Brown	Friction	3	0.2	Negative	
2190	1	B	34	Gymnasium	Yes	Ceiling	Metal	Tan	Chipping	12	17.2	Positive	
2190	1	B	37	Gymnasium Office	Yes	Ceiling	Plaster	White	Moisture Damage	3	21.3	Positive	
2190	1	B	37	Gymnasium Office	Yes	W1	Brick	White	Cracking	2	21.4	Positive	
2190	1	2	216A	Teacher's Lounge 216 Staff Restroom	Yes	W2	Metal	Green	None	0	0.2	Negative	
2190	1	2	216A	Teacher's Lounge 216 Staff Restroom	Yes	W3	Metal	Green	None	0	0.3	Negative	
2190	1	B	37	Gymnasium Office	Yes	W2	Brick	White	Cracking	3	22.7	Positive	
2190	1	2	200	Classroom 200	Yes	W3	Metal	Grey	Chipping	1	0.24	Negative	
2190	1	B	37	Gymnasium Office	Yes	W3	Brick	White	Cracking	3	29.8	Positive	
2190	1	B	37	Gymnasium Office	Yes	W4	Brick	White	Chipping	5	23.4	Positive	
2190	1	2	200	Classroom 200	Yes	W4	Metal	Grey	None	1	0.3	Negative	
2190	1	B	37	Gymnasium Office	Yes	Ceiling	Metal	Tan	Chipping	2	17.9	Positive	
2190	1	B	38	Gymnasium Storage	Yes	Ceiling	Metal	Tan	Chipping	1	12.2	Positive	
2190	1	3	H312	Hallway outside Classrooms 300 - 302	Yes	Floor	Concrete	Grey	Friction	5	4.2	Positive	
2190	1	3	H312	Hallway outside Classrooms 300 - 302	Yes	W2	Plaster	Yellow/Black	Chipping	5	24.1	Positive	
2190	1	2	206	IMC (Library)	Yes	W3	Metal	Grey	None	0	0.3	Negative	
2190	1	3	H312	Hallway outside Classrooms 300 - 302	Yes	W3	Plaster	Yellow/Green	Chipping	2	21.2	Positive	
2190	1	3	H312	Hallway outside Classrooms 300 - 302	Yes	W4	Plaster	Yellow/Black	Chipping	4	22.3	Positive	
2190	1	3	H310	Hallway outside Classrooms 307 - 309	Yes	Floor	Concrete	Grey	Friction	5	3.4	Positive	
2190	1	3	H310	Hallway outside Classrooms 307 - 309	Yes	W2	Metal	Grey	Chipping	2	1.6	Positive	
2190	1	3	H310	Hallway outside Classrooms 307 - 309	Yes	W2	Plaster	Yellow/Green	Cracking	10	22.3	Positive	
2190	1	3	H310	Hallway outside Classrooms 307 - 309	Yes	W4	Plaster	Yellow/Green	Chipping	4	22.7	Positive	

				Inspection Dates: 09/21/20-09/29/20								
				Name of Inspector: Michael Barth			Lead Safe Certification Assessment Report					
				Inspection Company: Criterion Labs			Fell Elementary School					
ULCS#	Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm <sup>2</sup> )	XRF (positive/negative)
2190	1	B	H02	Hallway outside of Cafeteria B	Yes	Ceiling	Plaster	White	Flaking	10	23.5	Positive
2190	1	1	H14	West Hallway	Yes	W3	Plaster	Yellow	None	0	21.7	Positive
2190	1	B	H02	Hallway outside of Cafeteria B	Yes	W1	Brick	White	Cracking	5	21.4	Positive
2190	1	B	H02	Hallway outside of Cafeteria B	Yes	W3	Brick	White	Cracking	2	24.5	Positive
2190	1	1	H14	West Hallway	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2190	1	1	H14	West Hallway	Yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
2190	1	B	H02	Hallway outside of Cafeteria B	Yes	W4	Brick	White	Cracking	5	22.1	Positive
2190	1	B	H02	Hallway outside of Cafeteria B	Yes	Ceiling	Metal	White	Chipping	5	21.2	Positive
	1	2	H29	Hallway outside of Classrooms 200 - 202	Yes	Floor	Concrete	Grey	Friction	5	3.6	Positive
2190	1	2	H29	Hallway outside of Classrooms 200 - 202	Yes	W2	Plaster	Red/Yellow	Cracking	8	19.5	Positive
2190	1	1	H15	Center Hallway between Classrooms 103 - 106	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
2190	1	2	H29	Hallway outside of Classrooms 200 - 202	Yes	W3	Plaster	Red/Yellow	Chipping	6	21.6	Positive
2190	1	1	H15	Center Hallway between Classrooms 103 - 106	Yes	W3	Plaster	Yellow	None	0	22.7	Positive
2190	1	2	H29	Hallway outside of Classrooms 200 - 202	Yes	W4	Plaster	Red/Yellow	Chipping	6	21.6	Positive
2190	1	2	H27	Hallway outside of Classrooms 207-209	yes	Floor	Concrete	Grey	Friction	5	3.4	Positive
2190	1	1	H15	Center Hallway between Classrooms 103 - 106	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
2190	1	1	H15	Center Hallway between Classrooms 103 - 106	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2190	1	2	H27	Hallway outside of Classrooms 207-209	yes	W2	Metal	Grey	Chipping	1	22.1	Positive
2190	1	1	H15	Center Hallway between Classrooms 103 - 106	Yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
2190	1	2	H27	Hallway outside of Classrooms 207-209	yes	W1	Metal	Red	Friction	1	0.1	Positive
2190	1	2	H27	Hallway outside of Classrooms 207-209	yes	W2	Plaster	Red/Yellow	Cracking	5	23.2	Positive
2190	1	2	H27	Hallway outside of Classrooms 207-209	yes	W3	Plaster	Red/Yellow	Cracking	1	21.9	Positive

				Inspection Dates: 09/21/20-09/29/20		Lead Safe Certification Assessment Report						
				Name of Inspector: Michael Barth		Fell Elementary School						
				Inspection Company: Criterion Labs								
ULCS#	Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm <sup>2</sup> )	XRF (positive/negative)
2190	1	2	209A	Classroom 209 Coat Closet	Yes	W3	Metal	Grey	Chipping	1	0.4	Negative
2190	1	2	H27	Hallway outside of Classrooms 207-209	yes	W4	Plaster	Red/Yellow	Cracking	5	24.1	Positive
2190	1	B	H03	Hallway outside of PTA Cafeteria and Girls Restroom	Yes	Ceiling	Plaster	White	Chipping	5	18.9	Positive
2190	1	B	H03	Hallway outside of PTA Cafeteria and Girls Restroom	Yes	W1	Brick	White	Cracking	2	27.8	Positive
2190	1	1	H15A	Closet across from Classroom 104	Yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
2190	1	1	103A	Classroom 103 Coat Closet	Yes	W1	Plaster	Tan	None	0	21.3	Positive
2190	1	B	H03	Hallway outside of PTA Cafeteria and Girls Restroom	Yes	W2	Brick	White	Cracking	5	23.4	Positive
2190	1	1	103A	Classroom 103 Coat Closet	Yes	W3	Plaster	Tan	Partially Inaccessible	0	24.3	Positive
2190	1	2	202	Classroom 202	Yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
2190	1	B	H03	Hallway outside of PTA Cafeteria and Girls Restroom	Yes	W3	Brick	White	Cracking	2	22.5	Positive
2190	1	1	103A	Classroom 103 Coat Closet	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2190	1	2	200	Classroom 200	Yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
2190	1	1	104A	Classroom 104 Coat Closet	Yes	W1	Plaster	Tan	None	0	21.3	Positive
2190	1	B	H03	Hallway outside of PTA Cafeteria and Girls Restroom	Yes	W4	Brick	White	Cracking	5	21.2	Positive
2190	1	1	104A	Classroom 104 Coat Closet	Yes	W3	Plaster	Tan	Partially Inaccessible	0	21.4	Positive
2190	1	2	201	Classroom 201	Yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
2190	1	B	H03	Hallway outside of PTA Cafeteria and Girls Restroom	Yes	Ceiling	Metal	White	Chipping	10	17.8	Positive
2190	1	1	104A	Classroom 104 Coat Closet	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2190	1	1	104A	Classroom 104 Coat Closet	Yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A

				Inspection Dates: 09/21/20-09/29/20								
				Name of Inspector: Michael Barth			Lead Safe Certification Assessment Report					
				Inspection Company: Criterion Labs			Fell Elementary School					
ULCS#	Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm <sup>2</sup> )	XRF (positive/negative)
2190	1	1	PC104A	Classroom 104 Coat Closet Pipe Chase	Yes	W1	Brick	N/A	N/A	N/A	N/A	N/A
2190	1	1	PC104A	Classroom 104 Coat Closet Pipe Chase	Yes	W2	Brick	N/A	N/A	N/A	N/A	N/A
2190	1	1	PC104A	Classroom 104 Coat Closet Pipe Chase	Yes	W3	Brick	N/A	N/A	N/A	N/A	N/A
2190	1	1	PC104A	Classroom 104 Coat Closet Pipe Chase	Yes	W4	Brick	N/A	N/A	N/A	N/A	N/A
2190	1	1	PC104A	Classroom 104 Coat Closet Pipe Chase	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2190	1	1	PC104A	Classroom 104 Coat Closet Pipe Chase	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2190	1	1	105A	Classroom 105 Coat Closet	Yes	W1	No Access	No Access	No Access	No Access	No Access	No Access
2190	1	1	105A	Classroom 105 Coat Closet	Yes	W2	No Access	No Access	No Access	No Access	No Access	No Access
2190	1	1	105A	Classroom 105 Coat Closet	Yes	W3	No Access	No Access	No Access	No Access	No Access	No Access
2190	1	1	105A	Classroom 105 Coat Closet	Yes	W4	No Access	No Access	No Access	No Access	No Access	No Access
2190	1	1	105A	Classroom 105 Coat Closet	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
2190	1	1	105A	Classroom 105 Coat Closet	Yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access
2190	1	B	H01	Hallway outside Rooms 1-3	Yes	Ceiling	Plaster	White	Flaking	10	18.2	Positive
2190	1	B	H01	Hallway outside Rooms 1-3	Yes	W1	Brick	White	Cracking	3	23.4	Positive
2190	1	1	106A	Classroom 106 Coat Closet	Yes	W3	Plaster	Tan	Partially Inaccessible	1	N/A	No Access
2190	1	B	H01	Hallway outside Rooms 1-3	Yes	W2	Brick	White	Cracking	5	24.1	Positive
2190	1	1	106A	Classroom 106 Coat Closet	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2190	1	1	106A	Classroom 106 Coat Closet	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2190	1	1	107A	Classroom 107 Coat Closet	Yes	W1	Plaster	Green	None	0	21.3	Positive
2190	1	1	107A	Classroom 107 Coat Closet	Yes	W1	Plaster	Blue	None	0	22.7	Positive
2190	1	1	107A	Classroom 107 Coat Closet	Yes	W2	Plaster	Green	None	0	23.1	Positive

				Inspection Dates: 09/21/20-09/29/20									
				Name of Inspector: Michael Barth			Lead Safe Certification Assessment Report						
				Inspection Company: Criterion Labs			Fell Elementary School						
ULCS#	Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm <sup>2</sup> )	XRF (positive/negative)	
2190	1	1	107A	Classroom 107 Coat Closet	Yes	W2	Plaster	Blue	None	0	22.6	Positive	
2190	1	2	203	Classroom 203	Yes	W2	Wood	N/A	N/A	0	N/A	N/A	
2190	1	1	107A	Classroom 107 Coat Closet	Yes	W3	Plaster	Green	None	0	21.4	Positive	
2190	1	1	107A	Classroom 107 Coat Closet	Yes	W3	Plaster	Blue	None	0	22.3	Positive	
2190	1	2	203	Classroom 203	Yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A	
2190	1	B	H01	Hallway outside Rooms 1-3	Yes	W3	Brick	White	Cracking	3	22.3	Positive	
2190	1	B	H01	Hallway outside Rooms 1-3	Yes	W4	Brick	White	Cracking	5	24.5	Positive	
2190	1	1	107A	Classroom 107 Coat Closet	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	
2190	1	2	204	Classroom 204	Yes	W2	Wood	N/A	N/A	N/A	N/A	N/A	
2190	1	1	PC107A	Classroom 107 Coat Closet Pipe Chase	Yes	W1	Brick	N/A	N/A	N/A	N/A	N/A	
2190	1	1	PC107A	Classroom 107 Coat Closet Pipe Chase	Yes	W2	Brick	N/A	N/A	N/A	N/A	N/A	
2190	1	1	PC107A	Classroom 107 Coat Closet Pipe Chase	Yes	W3	Brick	N/A	N/A	N/A	N/A	N/A	
2190	1	1	PC107A	Classroom 107 Coat Closet Pipe Chase	Yes	W4	Brick	N/A	N/A	N/A	N/A	N/A	
2190	1	1	PC107A	Classroom 107 Coat Closet Pipe Chase	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	
2190	1	1	PC107A	Classroom 107 Coat Closet Pipe Chase	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
2190	1	1	108A	Classroom 108 Coat Closet	Yes	W1	Plaster	Tan	None	0	24.6	Positive	
2190	1	B	H01	Hallway outside Rooms 1-3	Yes	Ceiling	Metal	Tan	Flaking	25	19.1	Positive	
2190	1	1	108A	Classroom 108 Coat Closet	Yes	W3	Plaster	Tan	Partially Inaccessible	0	23.4	Positive	
2190	1	2	H29A	Hallway/Vestibule to Teacher's Lounge	Yes	W2	Plaster	Tan	Flaking	3	21.4	Positive	
2190	1	1	108A	Classroom 108 Coat Closet	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	
2190	1	2	204	Classroom 204	Yes	W4	Wood	N/A	N/A	N/A	N/A	N/A	
2190	1	2	H29A	Hallway/Vestibule to Teacher's Lounge	Yes	W4	Wood	Tan	Friction	3	8.8	Positive	
2190	1	1	109A	Classroom 109 Coat Closet	Yes	W2	Plaster	Tan	Partially Inaccessible	0	24.5	Positive	

				Inspection Dates: 09/21/20-09/29/20									
				Name of Inspector: Michael Barth			Lead Safe Certification Assessment Report						
				Inspection Company: Criterion Labs			Fell Elementary School						
ULCS#	Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm <sup>2</sup> )	XRF (positive/negative)	
2190	1	2	204	Classroom 204	Yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A	
2190	1	1	112A	Handicap Access to Auditorium/Auditorium Storage Closet	Yes	W1	Plaster	Tan	Cracking	3	21.5	Positive	
2190	1	2	206	IMC (Library)	Yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A	
2190	1	1	112A	Handicap Access to Auditorium/Auditorium Storage Closet	Yes	W2	Plaster	Tan	Chipping	5	22.3	Positive	
2190	1	1	109A	Classroom 109 Coat Closet	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	
2190	1	2	207	Classroom 207	Yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A	
2190	1	1	PC109A	Classroom 109 Coat Closet Pipe Chase	Yes	W1	Terracotta	N/A	N/A	N/A	N/A	N/A	
2190	1	1	PC109A	Classroom 109 Coat Closet Pipe Chase	Yes	W2	Terracotta	N/A	N/A	N/A	N/A	N/A	
2190	1	1	PC109A	Classroom 109 Coat Closet Pipe Chase	Yes	W3	Terracotta	N/A	N/A	N/A	N/A	N/A	
2190	1	1	PC109A	Classroom 109 Coat Closet Pipe Chase	Yes	W4	Terracotta	N/A	N/A	N/A	N/A	N/A	
2190	1	1	PC109A	Classroom 109 Coat Closet Pipe Chase	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	
2190	1	1	PC109A	Classroom 109 Coat Closet Pipe Chase	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
2190	1	1	112A	Handicap Access to Auditorium/Auditorium Storage Closet	Yes	W3	Plaster	Tan	Cracking	5	24.1	Positive	
2190	1	1	112A	Handicap Access to Auditorium/Auditorium Storage Closet	Yes	W4	Plaster	Tan	Chipping	3	21.2	Positive	
2190	1	2	208	Classroom 208	Yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A	
2190	1	2	209	Classroom 209	Yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A	
2190	1	1	112A	Handicap Access to Auditorium/Auditorium Storage Closet	Yes	Ceiling	Plaster	Tan	Cracking	5	23.1	Positive	
2190	1	2	210A	Nurse's Restroom	Yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A	
2190	1	2	210	Nurse	Yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A	
2190	1	2	202	Classroom 202	Yes	W4	Plaster	Tan	None	0	21.4	Positive	
2190	1	2	202	Classroom 202	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	
2190	1	2	215A	Teacher's Lounge 215 Storage Closet	Yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A	
2190	1	2	206	IMC (Library)	Yes	W1	Plaster	White	Chipping	3	23.4	Positive	

				Inspection Dates: 09/21/20-09/29/20								
				Name of Inspector: Michael Barth			Lead Safe Certification Assessment Report					
				Inspection Company: Criterion Labs			Fell Elementary School					
ULCS#	Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm <sup>2</sup> )	XRF (positive/negative)
2190	1	2	206	IMC (Library)	Yes	W3	Plaster	White	Flaking/Moisture Damage/Cracking	3	22.1	Positive
2190	1	B	B4	Kitchen Serving Line	yes	W1	Brick	White	Cracking	5	22.3	Positive
2190	1	B	B4	Kitchen Serving Line	yes	W3	Brick	White	Cracking	2	21.4	Positive
2190	1	2	216	Teacher's Lounge 216	Yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
2190	1	2	216A	Teacher's Lounge 216 Staff Restroom	Yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
2190	1	B	B4	Kitchen Serving Line	yes	W4	Brick	White	Cracking	2	25.4	Positive
2190	1	3	313	Large Storage Closet outside of Classroom 309	Yes	W3	Metal	Grey	Chipping	5	7.8	Positive
2190	1	2	200A	Classroom 200 Coat Closet	Yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
2190	1	2	201A	Classroom 201 Coat Closet	Yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
2190	1	2	200	Classroom 200	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2190	1	2	207A	Classroom 207 Coat Closet	Yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
2190	1	3	313	Large Storage Closet outside of Classroom 309	Yes	W1	Plaster	Tan	Chipping	1	22.1	Positive
2190	1	2	201	Classroom 201	Yes	W2	Plaster	Tan	Partially Inaccessible	0	22.7	Positive
2190	1	3	313	Large Storage Closet outside of Classroom 309	Yes	W2	Plaster	Tan	Flaking	10	23.4	Positive
2190	1	2	209A	Classroom 209 Coat Closet	Yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
2190	1	3	313	Large Storage Closet outside of Classroom 309	Yes	W3	Plaster	Tan	Flaking	1	27.8	Positive
2190	1	2	201	Classroom 201	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2190	1	2	H29	Hallway outside of Classrooms 200 - 202	Yes	W1	Metal	Red	Friction	1	0.11	Negative
2190	1	3	313	Large Storage Closet outside of Classroom 309	Yes	W4	Plaster	Tan	Flaking	5	26.4	Positive
2190	1	3	313	Large Storage Closet outside of Classroom 309	Yes	Ceiling	Plaster	Tan	Flaking	2	23.2	Positive
2190	1	B	PTA	Lunch Room	Yes	W1	Plaster	White	Cracking	5	22.3	Positive
2190	1	B	PTA	Lunch Room	Yes	W1	Plaster	Green	Chipping	3	21.4	Positive
2190	1	B	PTA	Lunch Room	Yes	W2	Plaster	White	Cracking	3	18.7	Positive
2190	1	B	PTA	Lunch Room	Yes	W2	Plaster	Green	Cracking	3	19.2	Positive
2190	1	2	202	Classroom 202	Yes	W2	Metal	Tan	Chipping	1	0.03	Negative

				Inspection Dates: 09/21/20-09/29/20								
				Name of Inspector: Michael Barth			Lead Safe Certification Assessment Report					
				Inspection Company: Criterion Labs			Fell Elementary School					
ULCS#	Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm <sup>2</sup> )	XRF (positive/negative)
2190	1	B	PTA	Lunch Room	Yes	W3	Plaster	White	Chipping	3	21.9	Positive
2190	1	B	PTA	Lunch Room	Yes	W3	Plaster	Green	Chipping	4	22.3	Positive
2190	1	2	203	Classroom 203	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2190	1	2	202	Classroom 202	Yes	W3	Metal	Tan	Chipping	1	0.01	Negative
2190	1	2	204	Classroom 204	Yes	W1	Plaster	Tan	None	0	21.2	Positive
2190	1	2	203	Classroom 203	Yes	W1	Metal	Tan	None	0	0.2	Negative
2190	1	B	PTA	Lunch Room	Yes	W4	Plaster	White	Cracking	2	24.5	Positive
2190	1	2	200A	Classroom 200 Coat Closet	Yes	W2	Metal	Tan	None	0	22.5	Positive
2190	1	2	200A	Classroom 200 Coat Closet	Yes	W3	Metal	Tan	Flaking	5	0.21	Negative
2190	1	2	204	Classroom 204	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2190	1	2	206B	Classroom 206 Closet B	Yes	Ceiling	Metal	Tan	Chipping	1	0	Negative
2190	1	B	PTA	Lunch Room	Yes	W4	Plaster	Green	Chipping	1	22.9	Positive
2190	1	2	206	IMC (Library)	Yes	W2	Plaster	White	None	0	25.3	Positive
2190	1	B	PTA	Lunch Room	Yes	Ceiling	Metal	White	Cracking	5	15.4	Positive
2190	1	1	111	Main Office	Yes	W2	Plaster	Tan	Cracking	1	28.9	Positive
2190	1	2	206	IMC (Library)	Yes	W4	Plaster	White	Partially Inaccessible	0	21.2	Positive
2190	1	2	206	IMC (Library)	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2190	1	1	111	Main Office	Yes	W3	Plaster	Tan	Chipping/Moisture Damage	6	32.1	Positive
2190	1	2	H29A	Hallway/Vestibule to Teacher's Lounge	Yes	W1	Plaster	Tan	None	0	22.2	Positive
2190	1	1	111	Main Office	Yes	W4	Plaster	Tan	Cracking	1	21.7	Positive
2190	1	2	H29A	Hallway/Vestibule to Teacher's Lounge	Yes	W3	Plaster	Tan	None	0	23.4	Positive
2190	1	2	H29A	Hallway/Vestibule to Teacher's Lounge	Yes	W4	Plaster	Tan	None	0	25.3	Positive
2190	1	1	111B	Main Office Storage Closet	Yes	W2	Plaster	Tan	Chipping	2	16.7	Positive
2190	1	2	H29A	Hallway/Vestibule to Teacher's Lounge	Yes	Ceiling	Plaster	Tan	None	0	N/A	N/A
2190	1	2	H29A	Hallway/Vestibule to Teacher's Lounge	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2190	1	1	111B	Main Office Storage Closet	Yes	W3	Plaster	Tan	Flaking	10	12.1	Positive
2190	1	1	111B	Main Office Storage Closet	Yes	W4	Plaster	Tan	Cracking	10	24.1	Positive
2190	1	1	111B	Main Office Storage Closet	Yes	Ceiling	Plaster	Tan	Flaking	12	23.2	Positive



				Inspection Dates: 09/21/20-09/29/20								
				Name of Inspector: Michael Barth			Lead Safe Certification Assessment Report					
				Inspection Company: Criterion Labs			Fell Elementary School					
ULCS#	Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm <sup>2</sup> )	XRF (positive/negative)
2190	1	1	109B	Men's Restroom beside Classroom 109	Yes	W3	Metal	Grey	Chipping	1	5.4	Positive
2190	1	2	215A	Teacher's Lounge 215 Storage Closet	Yes	W1	Wood	Tan	None	0	5.6	Positive
2190	1	2	207	Classroom 207	Yes	W4	Plaster	Tan	None	0	21.4	Positive
2190	1	1	109B	Men's Restroom beside Classroom 109	Yes	W1	Plaster	Tan	Chipping	1	31.2	Positive
2190	1	2	215A	Teacher's Lounge 215 Storage Closet	Yes	W2	Wood	Tan	None	0	6.4	Positive
2190	1	2	207	Classroom 207	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2190	1	1	109B	Men's Restroom beside Classroom 109	Yes	W2	Plaster	Tan	Cracking	10	32.2	Positive
2190	1	1	109B	Men's Restroom beside Classroom 109	Yes	W3	Plaster	Tan	Chipping	1	24.5	Positive
2190	1	2	208	Classroom 208	Yes	W1	Plaster	Tan	None	0	21.7	Positive
2190	1	1	109B	Men's Restroom beside Classroom 109	Yes	W4	Plaster	Tan	Chipping	2	26.7	Positive
2190	1	B	RM2	Music Room	Yes	W1	Plaster	Tan	Flaking	10	21.3	Positive
2190	1	B	RM2	Music Room	Yes	W2	Plaster	Tan	Cracking	15	22.7	Positive
2190	1	B	RM2	Music Room	Yes	W3	Plaster	Tan	Cracking	5	24.1	Positive
2190	1	2	208	Classroom 208	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2190	1	B	RM2	Music Room	Yes	W4	Plaster	Tan	Cracking	5	26.7	Positive
2190	1	B	RM2	Music Room	Yes	Ceiling	Plaster	Tan	Moisture Damage	15	28.9	Positive
2190	1	B	S01A	Northwest Stairwell Entrance Vestibule beside Room 3	Yes	W1	Plaster	Blue	Cracking	3	21.3	Positive
2190	1	B	S01A	Northwest Stairwell Entrance Vestibule beside Room 3	Yes	W2	Plaster	Blue	Chipping	2	23.2	Positive
2190	1	B	S01A	Northwest Stairwell Entrance Vestibule beside Room 3	Yes	W2	Metal	Grey	Chipping	1	1.5	Positive
2190	1	2	210	Nurse	Yes	W2	Metal	Grey	Chipping	1	2.1	Positive
2190	1	2	210	Nurse	Yes	W2	Wood	Tan	Cracking	8	5.7	Positive
2190	1	2	210	Nurse	Yes	Floor	Wood	Tan	Friction	5	4.1	Positive
2190	1	2	200	Classroom 200	Yes	W3	Wood	White	None	0	14.1	Positive
2190	1	2	210	Nurse	Yes	W1	Wood	Tan	Friction/Cracking	5	5.4	Positive
2190	1	2	209	Classroom 209	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2190	1	2	210	Nurse	Yes	W1	Wood	Tan	Chipping	2	4.8	Positive

				Inspection Dates: 09/21/20-09/29/20								
				Name of Inspector: Michael Barth			Lead Safe Certification Assessment Report					
				Inspection Company: Criterion Labs			Fell Elementary School					
ULCS#	Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm <sup>2</sup> )	XRF (positive/negative)
2190	1	2	210	Nurse	Yes	W2	Plaster	Blue	Cracking	8	22.1	Positive
2190	1	2	210A	Nurse's Restroom	Yes	W1	Plaster	Blue	None	0	22.1	Positive
2190	1	2	210	Nurse	Yes	W3	Wood	Tan	Friction/Alligatoring	5	6.5	Positive
2190	1	2	210A	Nurse's Restroom	Yes	W3	Metal	Grey	Chipping	1	1.7	Positive
2190	1	2	210A	Nurse's Restroom	Yes	W3	Wood	Tan	Alligatoring	10	12.1	Positive
2190	1	2	210A	Nurse's Restroom	Yes	Floor	Wood	Tan	Friction	2	4.7	Positive
2190	1	2	210A	Nurse's Restroom	Yes	W2	Plaster	Blue	Cracking	2	23.5	Positive
2190	1	2	210A	Nurse's Restroom	Yes	W3	Plaster	Blue	Cracking	3	23.7	Positive
2190	1	2	210A	Nurse's Restroom	Yes	W4	Plaster	Blue	Chipping	1	23.9	Positive
2190	1	2	210A	Nurse's Restroom	Yes	Ceiling	Plaster	Tan	Chipping	1	12.4	Positive
2190	1	2	210A	Nurse's Restroom	Yes	W1	Wood	Tan	Cracking	5	4.5	Positive
2190	1	2	210A	Nurse's Restroom	Yes	W4	Wood	Tan	Alligatoring	2	14.1	Positive
2190	1	2	210	Nurse	Yes	W1	Plaster	Blue	Partially Inaccessible	0	21.3	Positive
2190	1	1	110	Principal's Office	Yes	W4	Metal	Grey	Chipping	1	1.5	Positive
2190	1	1	110	Principal's Office	Yes	W1	Plaster	Tan	Cracking	2	32.1	Positive
2190	1	1	110	Principal's Office	Yes	W2	Plaster	Tan	Cracking	1	23.5	Positive
2190	1	2	210	Nurse	Yes	W2	Plaster	Orange	None	0	23.1	Positive
2190	1	1	H16B	Principal's Office Hallway/Storage	yes	W2	Plaster	Tan	Cracking	3	26.1	Positive
2190	1	1	110A	Principal's Office Restroom	Yes	W1	Plaster	Tan	Cracking/Chipping	8	26.1	Positive
2190	1	2	210	Nurse	Yes	W3	Plaster	Mural	None	0	24.5	Positive
2190	1	1	110A	Principal's Office Restroom	Yes	W2	Plaster	Tan	Cracking	10	23.2	Positive
2190	1	2	210	Nurse	Yes	W4	Plaster	Blue	None	0	21.4	Positive
2190	1	2	210	Nurse	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2190	1	1	110A	Principal's Office Restroom	Yes	W4	Plaster	Tan	Cracking/Chipping	5	22.7	Positive
2190	1	1	110A	Principal's Office Restroom	Yes	Ceiling	Plaster	Tan	Moisture Damage/Cracking	8	21.5	Positive
2190	1	1	110B	Principals Office Closet	Yes	W1	Plaster	Tan	Cracking	1	22.1	Positive
2190	1	1	110B	Principals Office Closet	Yes	W2	Plaster	Tan	Cracking	2	23.2	Positive
2190	1	1	110B	Principals Office Closet	Yes	W3	Plaster	Tan	Cracking	2	24.5	Positive
2190	1	1	110B	Principals Office Closet	Yes	W4	Plaster	Tan	Cracking	3	27.1	Positive
2190	1	1	110B	Principals Office Closet	Yes	Ceiling	Plaster	Tan	Cracking	3	16.1	Positive
2190	1	2	210A	Storage Room beside Classroom 200	Yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A

				Inspection Dates: 09/21/20-09/29/20								
				Name of Inspector: Michael Barth			Lead Safe Certification Assessment Report					
				Inspection Company: Criterion Labs			Fell Elementary School					
ULCS#	Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm <sup>2</sup> )	XRF (positive/negative)
2190	1	2	213	Janitor's Closet beside Classroom 203	No	W1	Plaster	Tan	Cracking	5	22.5	Positive
2190	1	2	213	Janitor's Closet beside Classroom 203	No	W2	Plaster	Tan	Chipping	2	26.4	Positive
2190	1	2	213	Janitor's Closet beside Classroom 203	No	W3	Plaster	Tan	Chipping	3	24.5	Positive
2190	1	2	213	Janitor's Closet beside Classroom 203	No	W4	Plaster	Tan	Cracking	1	26.4	Positive
2190	1	2	213	Janitor's Closet beside Classroom 203	No	Ceiling	Plaster	Tan	Moisture Damage	5	21.2	Positive
2190	1	2	213	Janitor's Closet beside Classroom 203	No	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
2190	1	1	110B	Principals Office Closet	yes	W2	Metal	Tan	Cracking	2	6.2	Positive
2190	1	1	110B	Principals Office Closet	yes	W3	Metal	Tan	Cracking	2	5.4	Positive
2190	1	2	215	Teacher's Lounge 215	Yes	W2	Wood	White	None	0	7.2	Positive
2190	1	B	PTA1	PTA Lunchroom Storage Closet 1	Yes	W2	Plaster	Tan	Cracking	4	24.7	Positive
2190	1	2	215	Teacher's Lounge 215	Yes	W2	Plaster	Blue	None	0	24.7	Positive
2190	1	B	PTA1	PTA Lunchroom Storage Closet 1	Yes	W3	Plaster	Tan	Cracking	2	21.2	Positive
2190	1	B	PTA1	PTA Lunchroom Storage Closet 1	Yes	W4	Plaster	Tan	Cracking	4	23.4	Positive
2190	1	B	PTA1	PTA Lunchroom Storage Closet 1	Yes	W3	Metal	Tan	Chipping	1	2.8	Positive
2190	1	2	215	Teacher's Lounge 215	Yes	W3	Plaster	Blue	None	0	N/A	N/A
2190	1	B	PTA1	PTA Lunchroom Storage Closet 1	Yes	Ceiling	Metal	Tan	Chipping	1	20.9	Positive
2190	1	B	PTA2	PTA Lunchroom Storage Closet 2	Yes	W1	Plaster	Tan	Chipping	2	23.2	Positive
2190	1	B	PTA2	PTA Lunchroom Storage Closet 2	Yes	W2	Plaster	Tan	Cracking	2	22.7	Positive
2190	1	2	215	Teacher's Lounge 215	Yes	W4	Plaster	Blue	None	0	21.4	Positive
2190	1	2	215A	Teacher's Lounge 215 Storage Closet	Yes	W2	Wood	White	None	0	5.9	Positive
2190	1	2	203	Classroom 203	Yes	W3	Metal	White	Chipping	1	0.2	Negative
2190	1	2	207	Classroom 207	Yes	W3	Metal	White	Chipping	1	0.11	Negative
2190	1	2	207	Classroom 207	Yes	W3	Metal	White	Chipping	1	0.2	Negative
2190	1	2	215	Teacher's Lounge 215	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2190	1	2	215	Teacher's Lounge 215	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2190	1	B	PTA2	PTA Lunchroom Storage Closet 2	Yes	W3	Plaster	Tan	Cracking	1	21.8	Positive

				Inspection Dates: 09/21/20-09/29/20								
				Name of Inspector: Michael Barth			Lead Safe Certification Assessment Report					
				Inspection Company: Criterion Labs			Fell Elementary School					
ULCS#	Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm <sup>2</sup> )	XRF (positive/negative)
2190	1	2	209	Classroom 209	Yes	W2	Metal	White	Chipping	1	0.21	Negative
2190	1	2	209	Classroom 209	Yes	W3	Metal	White	Chipping	1	0.1	Negative
2190	1	2	215A	Teacher's Lounge 215 Storage Closet	Yes	W3	Metal	White	None	0	0.21	Negative
2190	1	2	216A	Teacher's Lounge 216 Staff Restroom	Yes	W2	Metal	White	None	0	0.21	Negative
2190	1	2	215A	Teacher's Lounge 215 Storage Closet	Yes	W2	Plaster	White	None	0	20.4	Positive
2190	1	2	216A	Teacher's Lounge 216 Staff Restroom	Yes	W3	Metal	White	Chipping	1	0.22	Negative
2190	1	2	211	Janitor's Closet beside IMC (206)	No	W3	Metal	White	Chipping	8	0.2	Negative
2190	1	B	PTA2	PTA Lunchroom Storage Closet 2	Yes	W4	Plaster	Tan	Cracking	1	26.3	Positive
2190	1	2	207A	Classroom 207 Coat Closet	Yes	W2	Metal	White	None	0	0.21	Negative
2190	1	2	215A	Teacher's Lounge 215 Storage Closet	Yes	W4	Plaster	White	None	0	24.5	Positive
2190	1	2	207A	Classroom 207 Coat Closet	Yes	W2	Metal	White	Chipping	1	0.3	Negative
2190	1	B	PTA2	PTA Lunchroom Storage Closet 2	Yes	Ceiling	Plaster	Tan	Moisture Damage	1	18.9	Positive
2190	1	3	300	Classroom 300	Yes	W1	Wood	Brown	Chipping	1	0.01	Negative
2190	1	B	PTA3	PTA Lunchroom Storage Closet 3	Yes	W1	Plaster	Green	Cracking	1	21.4	Positive
2190	1	3	300	Classroom 300	Yes	W2	Wood	Brown	Chipping	1	0.03	Negative
2190	1	3	300	Classroom 300	Yes	W3	Wood	Brown	Chipping	1	0.01	Negative
2190	1	3	300	Classroom 300	Yes	W4	Wood	Brown	Chipping	1	0.1	Negative
2190	1	3	310	Classroom 310	Yes	Floor	Wood	Brown	Friction	3	0.21	Negative
2190	1	B	PTA3	PTA Lunchroom Storage Closet 3	Yes	W3	Plaster	Green	Cracking	2	23.7	Positive
2190	1	3	304	Classroom 304	Yes	Floor	Wood	Brown	Friction	5	0.11	Negative
2190	1	3	303	Classroom 303	Yes	Floor	Wood	Brown	Friction	5	0.21	Negative
2190	1	3	H310	Hallway outside Classrooms 307 - 309	Yes	W1	Metal	Green	Friction	2	0.2	Negative
2190	1	B	PTA3	PTA Lunchroom Storage Closet 3	Yes	W4	Plaster	Green	Cracking	2	21.8	Positive
2190	1	3	H312	Hallway outside Classrooms 300 - 302	Yes	W1	Metal	Green	Friction	2	0.1	Negative
2190	1	B	PTA3	PTA Lunchroom Storage Closet 3	Yes	Ceiling	Plaster	Tan	Moisture Damage	1	14.9	Positive

				Inspection Dates: 09/21/20-09/29/20								
				Name of Inspector: Michael Barth			Lead Safe Certification Assessment Report					
				Inspection Company: Criterion Labs			Fell Elementary School					
ULCS#	Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
2190	1	B	PTA4	PTA Lunchroom Storage Closet 4	Yes	W1	Plaster	Green	Cracking	1	17.4	Positive
2190	1	2	216	Teacher's Lounge 216	Yes	W4	Plaster	Blue	None	0	24.6	Positive
2190	1	2	216	Teacher's Lounge 216	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2190	1	B	PTA4	PTA Lunchroom Storage Closet 4	Yes	W2	Plaster	Green	Cracking	1	21.9	Positive
2190	1	2	216A	Teacher's Lounge 216 Staff Restroom	Yes	W1	Plaster	Green	None	0	19.8	Positive
2190	1	2	216A	Teacher's Lounge 216 Staff Restroom	Yes	W1	Plaster	White	None	0	21.2	Positive
2190	1	2	216A	Teacher's Lounge 216 Staff Restroom	Yes	W2	Plaster	Green	None	0	22.5	Positive
2190	1	2	216A	Teacher's Lounge 216 Staff Restroom	Yes	W2	Plaster	White	None	0	24.3	Positive
2190	1	3	301	Classroom 301	Yes	W3	Metal	Grey	Chipping	2	0.2	Negative
2190	1	B	PTA4	PTA Lunchroom Storage Closet 4	Yes	W3	Plaster	Green	Cracking	1	22.1	Positive
2190	1	2	216A	Teacher's Lounge 216 Staff Restroom	Yes	W2	Plastic	Green	None	0	0.01	Negative
2190	1	2	216A	Teacher's Lounge 216 Staff Restroom	Yes	W2	Plastic	White	None	0	0.01	Negative
2190	1	B	PTA4	PTA Lunchroom Storage Closet 4	Yes	Ceiling	Plaster	Green	Moisture Damage	1	23.2	Positive
2190	1	2	216A	Teacher's Lounge 216 Staff Restroom	Yes	W3	Plaster	Green	None	0	24.2	Positive
2190	1	B	1A	RM1 Storage Closet	Yes	W1	Plaster	Tan	Cracking	2	22.1	Positive
2190	1	B	1A	RM1 Storage Closet	Yes	W2	Plaster	Tan	Cracking	3	21.7	Positive
2190	1	3	315	Storage Closet across from 302	No	W4	Metal	Grey	Chipping	1	1.7	Positive
2190	1	2	216A	Teacher's Lounge 216 Staff Restroom	Yes	W4	Plaster	Green	None	0	17.9	Positive
2190	1	2	216A	Teacher's Lounge 216 Staff Restroom	Yes	W4	Plaster	White	None	0	22.4	Positive
2190	1	B	1A	RM1 Storage Closet	Yes	W3	Plaster	Tan	Cracking	1	23.4	Positive
2190	1	B	1A	RM1 Storage Closet	Yes	W4	Plaster	Tan	Cracking	1	20.9	Positive
2190	1	2	211	Janitor's Closet beside IMC (206)	No	W1	Plaster	Tan	Cracking	2	24.7	Positive
2190	1	2	211	Janitor's Closet beside IMC (206)	No	W2	Plaster	Tan	Chipping	2	21.1	Positive
2190	1	2	211	Janitor's Closet beside IMC (206)	No	W3	Plaster	Tan	Cracking	10	22.3	Positive

				Inspection Dates: 09/21/20-09/29/20									
				Name of Inspector: Michael Barth			Lead Safe Certification Assessment Report						
				Inspection Company: Criterion Labs			Fell Elementary School						
ULCS#	Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm <sup>2</sup> )	XRF (positive/negative)	
2190	1	3	310	Classroom 310	Yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A	
2190	1	2	211	Janitor's Closet beside IMC (206)	No	W4	Plaster	Tan	Chipping	15	21.4	Positive	
2190	1	2	211	Janitor's Closet beside IMC (206)	No	Ceiling	Plaster	Tan	Moisture Damage	8	22.7	Positive	
2190	1	2	211	Janitor's Closet beside IMC (206)	No	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
2190	1	B	1A	RM1 Storage Closet	Yes	Ceiling	Metal	Tan	Chipping	10	12.7	Positive	
2190	1	2	H28	Center Hallway	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A	
2190	1	B	2B	RM2 Storage Closet B	Yes	W1	Plaster	Tan	Cracking	2	18.7	Positive	
2190	1	2	H28	Center Hallway	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A	
2190	1	2	H28	Center Hallway	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	
2190	1	2	H28	Center Hallway	Yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
2190	1	B	2B	RM2 Storage Closet B	Yes	W2	Plaster	Tan	Cracking	2	22.3	Positive	
2190	1	3	304	Classroom 304	Yes	W2	Wood	N/A	N/A	N/A	N/A	N/A	
2190	1	B	2B	RM2 Storage Closet B	Yes	W3	Plaster	Tan	Cracking	2	21.7	Positive	
2190	1	B	2B	RM2 Storage Closet B	Yes	W4	Plaster	Tan	Cracking	2	26.5	Positive	
2190	1	B	2B	RM2 Storage Closet B	Yes	Ceiling	Plaster	Tan	Moisture Damage/Flaking	10	22.7	Positive	
2190	1	2	H29	Hallway outside of Classrooms 200 - 202	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	
2190	1	2	H29	Hallway outside of Classrooms 200 - 202	Yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
2190	1	B	3A	RM3 Storage Closet A	Yes	W1	Plaster	Tan	Cracking	1	21	Positive	
2190	1	3	304	Classroom 304	Yes	W4	Wood	N/A	N/A	N/A	N/A	N/A	
2190	1	B	3A	RM3 Storage Closet A	Yes	W2	Plaster	Tan	Cracking	3	22.7	Positive	
2190	1	3	304	Classroom 304	Yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A	
2190	1	B	3A	RM3 Storage Closet A	Yes	W3	Plaster	Tan	Cracking	3	29.1	Positive	
2190	1	B	3A	RM3 Storage Closet A	Yes	W4	Plaster	Tan	Cracking	1	23.1	Positive	
2190	1	2	H27	Hallway outside of Classrooms 207-209	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	
2190	1	2	H27	Hallway outside of Classrooms 207-209	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
2190	1	B	3A	RM3 Storage Closet A	Yes	Ceiling	Plaster	Tan	Chipping	2	17.2	Positive	
2190	1	2	S24	Fire Tower Stairwell	Yes	W1	Brick	White	None	0	21.2	Positive	
2190	1	2	S24	Fire Tower Stairwell	Yes	W2	Brick	White	None	0	22.3	Positive	
2190	1	2	S24	Fire Tower Stairwell	Yes	W3	Brick	White	None	0	24.5	Positive	
2190	1	2	S24	Fire Tower Stairwell	Yes	W4	Brick	White	None	0	21	Positive	
2190	1	B	RM1	Speech	Yes	W1	Plaster	Tan	Chipping	3	21.3	Positive	

			Inspection Dates: 09/21/20-09/29/20				Lead Safe Certification Assessment Report						
			Name of Inspector: Michael Barth		Fell Elementary School								
			Inspection Company: Criterion Labs										
ULCS#	Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm <sup>2</sup> )	XRF (positive/negative)	
2190	1	2	S24	Fire Tower Stairwell	Yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
2190	1	B	RM1	Speech	Yes	W2	Plaster	Tan	Cracking	4	22.7	Positive	
2190	1	B	RM1	Speech	Yes	W3	Plaster	Tan	Moisture Damage	10	24.1	Positive	
2190	1	3	305	Classroom 305	Yes	W2	Wood	N/A	N/A	N/A	N/A	N/A	
2190	1	B	RM1	Speech	Yes	W4	Plaster	Tan	Cracking	5	22.9	Positive	
2190	1	3	305	Classroom 305	Yes	W4	Wood	N/A	N/A	N/A	N/A	N/A	
2190	1	3	305	Classroom 305	Yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A	
2190	1	B	RM1	Speech	Yes	Ceiling	Plaster	Tan	Moisture Damage	10	28.2	Positive	
2190	1	2	200A	Classroom 200 Coat Closet	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	
2190	1	3	306	Classroom 306	Yes	W4	Wood	N/A	N/A	N/A	N/A	N/A	
2190	1	2	PC200A	Classroom 200 Coat Closet Pipe Chase	Yes	W1	Brick	N/A	N/A	N/A	N/A	N/A	
2190	1	2	PC200A	Classroom 200 Coat Closet Pipe Chase	Yes	W2	Brick	N/A	N/A	N/A	N/A	N/A	
2190	1	2	PC200A	Classroom 200 Coat Closet Pipe Chase	Yes	W3	Brick	N/A	N/A	N/A	N/A	N/A	
2190	1	2	PC200A	Classroom 200 Coat Closet Pipe Chase	Yes	W4	Brick	N/A	N/A	N/A	N/A	N/A	
2190	1	2	PC200A	Classroom 200 Coat Closet Pipe Chase	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	
2190	1	2	PC200A	Classroom 200 Coat Closet Pipe Chase	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
2190	1	1	S12	Stairwell across from 109	Yes	Floor	Concrete	Grey	Friction	4	2.3	Positive	
2190	1	1	S12	Stairwell across from 109	Yes	W2	Plaster	White/Mural	Cracking	4	23.5	Positive	
2190	1	2	201A	Classroom 201 Coat Closet	Yes	W3	Plaster	Tan	Partially Inaccessible	0	22.4	Positive	
2190	1	1	S12	Stairwell across from 109	Yes	W3	Plaster	White/Mural	Chipping	1	24.3	Positive	
2190	1	2	201A	Classroom 201 Coat Closet	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	
2190	1	3	306	Classroom 306	Yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A	
2190	1	2	202A	Classroom 202 Coat Closet	Yes	W1	No Access	No Access	No Access	No Access	No Access	No Access	
2190	1	2	202A	Classroom 202 Coat Closet	Yes	W2	No Access	No Access	No Access	No Access	No Access	No Access	
2190	1	2	202A	Classroom 202 Coat Closet	Yes	W3	No Access	No Access	No Access	No Access	No Access	No Access	

				Inspection Dates: 09/21/20-09/29/20								
				Name of Inspector: Michael Barth			Lead Safe Certification Assessment Report					
				Inspection Company: Criterion Labs			Fell Elementary School					
ULCS#	Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
2190	1	2	202A	Classroom 202 Coat Closet	Yes	W4	No Access	No Access	No Access	No Access	No Access	No Access
2190	1	2	202A	Classroom 202 Coat Closet	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
2190	1	2	202A	Classroom 202 Coat Closet	Yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access
2190	1	2	203A	Classroom 203 Coat Closet	Yes	W1	No Access	No Access	No Access	No Access	No Access	No Access
2190	1	2	203A	Classroom 203 Coat Closet	Yes	W2	No Access	No Access	No Access	No Access	No Access	No Access
2190	1	2	203A	Classroom 203 Coat Closet	Yes	W3	No Access	No Access	No Access	No Access	No Access	No Access
2190	1	2	203A	Classroom 203 Coat Closet	Yes	W4	No Access	No Access	No Access	No Access	No Access	No Access
2190	1	2	203A	Classroom 203 Coat Closet	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
2190	1	2	203A	Classroom 203 Coat Closet	Yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access
2190	1	2	PC203A	Classroom 203 Coat Closet Pipe Chase	Yes	W1	No Access	No Access	No Access	No Access	No Access	No Access
2190	1	2	PC203A	Classroom 203 Coat Closet Pipe Chase	Yes	W2	No Access	No Access	No Access	No Access	No Access	No Access
2190	1	2	PC203A	Classroom 203 Coat Closet Pipe Chase	Yes	W3	No Access	No Access	No Access	No Access	No Access	No Access
2190	1	2	PC203A	Classroom 203 Coat Closet Pipe Chase	Yes	W4	No Access	No Access	No Access	No Access	No Access	No Access
2190	1	2	PC203A	Classroom 203 Coat Closet Pipe Chase	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
2190	1	2	PC203A	Classroom 203 Coat Closet Pipe Chase	Yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access
2190	1	2	204A	Classroom 204 Coat Closet	Yes	W1	No Access	No Access	No Access	No Access	No Access	No Access
2190	1	2	204A	Classroom 204 Coat Closet	Yes	W2	No Access	No Access	No Access	No Access	No Access	No Access
2190	1	2	204A	Classroom 204 Coat Closet	Yes	W3	No Access	No Access	No Access	No Access	No Access	No Access
2190	1	2	204A	Classroom 204 Coat Closet	Yes	W4	No Access	No Access	No Access	No Access	No Access	No Access
2190	1	2	204A	Classroom 204 Coat Closet	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
2190	1	2	204A	Classroom 204 Coat Closet	Yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access



			Inspection Dates: 09/21/20-09/29/20			Lead Safe Certification Assessment Report						
			Name of Inspector: Michael Barth			Fell Elementary School						
			Inspection Company: Criterion Labs									
ULCS#	Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm <sup>2</sup> )	XRF (positive/negative)
2190	1	2	206A	Classroom 206 Closet A	Yes	W1	Plaster	White	None	0	17.9	Positive
2190	1	2	206A	Classroom 206 Closet A	Yes	W2	Plaster	White	None	0	22.1	Positive
2190	1	2	206A	Classroom 206 Closet A	Yes	W3	Plaster	White	None	0	22.3	Positive
2190	1	2	206A	Classroom 206 Closet A	Yes	W4	Plaster	White	None	0	24.1	Positive
2190	1	2	206A	Classroom 206 Closet A	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2190	1	2	206A	Classroom 206 Closet A	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2190	1	2	206B	Classroom 206 Closet B	Yes	W1	Plaster	White	None	0	25.3	Positive
2190	1	2	206B	Classroom 206 Closet B	Yes	W2	Plaster	White	None	0	22.5	Positive
2190	1	2	206B	Classroom 206 Closet B	Yes	W3	Plaster	White	None	0	24.1	Positive
2190	1	1	S12	Stairwell across from 109	Yes	W4	Plaster	White/Mural	Chipping	4	21.2	Positive
2190	1	2	206B	Classroom 206 Closet B	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2190	1	3	307	Classroom 307	Yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
2190	1	2	206B	Classroom 206 Closet B	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2190	1	B	S06	Stairwell and Entrance Vestibule beside Girl's Restroom	Yes	Ceiling	Plaster	White	Moisture Damage	3	22.5	Positive
2190	1	B	S06	Stairwell and Entrance Vestibule beside Girl's Restroom	Yes	W1	Brick	White	Cracking	1	22.3	Positive
2190	1	3	308	Classroom 308	Yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
2190	1	3	309	Classroom 309	Yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
2190	1	B	S06	Stairwell and Entrance Vestibule beside Girl's Restroom	Yes	W2	Brick	White	Cracking	1	25.6	Positive
2190	1	B	S06	Stairwell and Entrance Vestibule beside Girl's Restroom	Yes	W3	Brick	White	Cracking	1	28.9	Positive
2190	1	2	207A	Classroom 207 Coat Closet	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2190	1	3	303	Classroom 303	Yes	W2	Wood	N/A	N/A	N/A	N/A	N/A
2190	1	3	303	Classroom 303	Yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
2190	1	B	S06	Stairwell and Entrance Vestibule beside Girl's Restroom	Yes	W4	Brick	White	Cracking	1	23.4	Positive
2190	1	B	S02	Stairwell and Foyer beside Boy's Restroom	Yes	W2	Brick	White	Cracking	3	21.2	Positive
2190	1	B	S02	Stairwell and Foyer beside Boy's Restroom	Yes	W3	Brick	White	Cracking	1	25.4	Positive
2190	1	B	S02	Stairwell and Foyer beside Boy's Restroom	Yes	W4	Brick	White	Cracking	3	22	Positive

				Inspection Dates: 09/21/20-09/29/20								
				Name of Inspector: Michael Barth		Lead Safe Certification Assessment Report						
				Inspection Company: Criterion Labs		Fell Elementary School						
ULCS#	Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm <sup>2</sup> )	XRF (positive/negative)
2190	1	2	208A	Classroom 208 Coat Closet	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2190	1	3	304A	Classroom 304 Coat Closet	Yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
2190	1	2	209A	Classroom 209 Coat Closet	Yes	W1	Plaster	White	None	0	24.6	Positive
2190	1	2	209A	Classroom 209 Coat Closet	Yes	W2	Plaster	White	Partially Inaccessible	0	22.1	Positive
2190	1	B	S01	Stairwell beside Basement Facilities Storage Room	Yes	Floor	Concrete	Grey	Friction	1	2.4	Positive
2190	1	3	307	Classroom 307	Yes	W3	Metal	White	Chipping	5	0.2	Negative
2190	1	B	S01	Stairwell beside Basement Facilities Storage Room	Yes	W2	Plaster	White/Blue	Cracking	2	21.2	Positive
2190	1	2	209A	Classroom 209 Coat Closet	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2190	1	3	307	Classroom 307	Yes	W3	Wood	White	None	0	1.6	Positive
2190	1	2	PC209A	Classroom 209 Coat Closet Pipe Chase	Yes	W1	Brick	N/A	N/A	N/A	N/A	N/A
2190	1	2	PC209A	Classroom 209 Coat Closet Pipe Chase	Yes	W2	Brick	N/A	N/A	N/A	N/A	N/A
2190	1	2	PC209A	Classroom 209 Coat Closet Pipe Chase	Yes	W3	Brick	N/A	N/A	N/A	N/A	N/A
2190	1	2	PC209A	Classroom 209 Coat Closet Pipe Chase	Yes	W4	Brick	N/A	N/A	N/A	N/A	N/A
2190	1	2	PC209A	Classroom 209 Coat Closet Pipe Chase	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2190	1	2	PC209A	Classroom 209 Coat Closet Pipe Chase	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2190	1	B	S01	Stairwell beside Basement Facilities Storage Room	Yes	W3	Plaster	White/Blue	Chipping	3	23.4	Positive
2190	1	B	S01	Stairwell beside Basement Facilities Storage Room	Yes	W4	Plaster	White/Blue	Chipping	2	22.1	Positive
2190	1	B	S05	Stairwell beside Cafeteria B	Yes	Floor	Concrete	Grey	Friction	3	4.5	Positive
2190	1	B	S05	Stairwell beside Cafeteria B	Yes	W2	Plaster	Blue/White	Cracking	2	22.1	Positive
2190	1	B	S05	Stairwell beside Cafeteria B	Yes	W3	Plaster	Blue/White	Cracking	1	19.5	Positive

				Inspection Dates: 09/21/20-09/29/20								
				Name of Inspector: Michael Barth		Lead Safe Certification Assessment Report						
				Inspection Company: Criterion Labs		Fell Elementary School						
ULCS#	Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm <sup>2</sup> )	XRF (positive/negative)
2190	1	B	S05	Stairwell beside Cafeteria B	Yes	W4	Plaster	Blue/White	Cracking	1	21.3	Positive
2190	1	3	316	Dean	Yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
2190	1	1	S15	Stairwell beside Classroom 102	Yes	Floor	Concrete	Grey	Friction	2	2.6	Positive
2190	1	1	S15	Stairwell beside Classroom 102	Yes	W2	Plaster	White/Blue	Cracking	3	22.3	Positive
2190	1	1	S15	Stairwell beside Classroom 102	Yes	W3	Plaster	White/Blue	Cracking	3	23.4	Positive
2190	1	1	S15	Stairwell beside Classroom 102	Yes	W4	Plaster	White/Mural	Cracking	5	21.2	Positive
2190	1	1	S11	Stairwell beside Classroom 107	Yes	Floor	Concrete	Grey	Friction	2	2.1	Positive
2190	1	1	S11	Stairwell beside Classroom 107	Yes	W1	Plaster	Yellow/White	Cracking	2	22.3	Positive
2190	1	1	S11	Stairwell beside Classroom 107	Yes	W2	Plaster	Yellow/White	Cracking	1	23.4	Positive
2190	1	1	S11	Stairwell beside Classroom 107	Yes	W4	Plaster	Yellow/White	Chipping	5	19.8	Positive
2190	1	3	S35	Stairwell beside Classroom 302	Yes	Floor	Concrete	Grey	Friction	3	1.5	Positive
2190	1	3	S35	Stairwell beside Classroom 302	Yes	W3	Metal	Green	Friction	1	2.4	Positive
2190	1	3	300	Classroom 300	Yes	W3	Metal	White	Chipping	3	0.3	Negative
2190	1	3	300	Classroom 300	Yes	W4	Metal	White	Chipping	1	0.1	Negative
2190	1	3	302	Classroom 302	Yes	W2	Metal	White	None	0	0.2	Negative
2190	1	3	300	Classroom 300	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2190	1	3	300	Classroom 300	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2190	1	3	S35	Stairwell beside Classroom 302	Yes	W1	Plaster	White	Cracking	3	21.2	Positive
2190	1	3	S35	Stairwell beside Classroom 302	Yes	W4	Plaster	White	Cracking	2	22.1	Positive
2190	1	3	S35	Stairwell beside Classroom 302	Yes	Ceiling	Plaster	White	Cracking	2	23.4	Positive
2190	1	3	302	Classroom 302	Yes	W3	Metal	White	Chipping	2	0.3	Negative
2190	1	3	301	Classroom 301	Yes	W4	Plaster	White	None	0	25.1	Positive
2190	1	3	301	Classroom 301	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2190	1	3	301	Classroom 301	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2190	1	3	S31	Stairwell beside Classroom 307	Yes	Floor	Concrete	Grey	Friction	2	2.1	Positive

				Inspection Dates: 09/21/20-09/29/20								
				Name of Inspector: Michael Barth			Lead Safe Certification Assessment Report					
				Inspection Company: Criterion Labs			Fell Elementary School					
ULCS#	Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm <sup>2</sup> )	XRF (positive/negative)
2190	1	3	S31	Stairwell beside Classroom 307	Yes	W3	Metal	Green	Friction	1	24.1	Positive
2190	1	3	309	Classroom 309	Yes	W2	Metal	White	None	0	0.1	Negative
2190	1	3	309	Classroom 309	Yes	W3	Metal	White	None	0	0.2	Negative
2190	1	3	S31	Stairwell beside Classroom 307	Yes	W1	Plaster	White	Cracking	2	21.2	Positive
2190	1	3	315	Storage Closet across from 302	No	W3	Metal	White	Chipping	3	0.21	Negative
2190	1	B	S05A	Visitors Entrance Foyer to Northeast Stairwell beside Cafeteria B	Yes	W3	Metal	Blue	Friction	2	0.1	Negative
2190	1	3	S31	Stairwell beside Classroom 307	Yes	W2	Plaster	White	Chipping	2	23.1	Positive
2190	1	3	302	Classroom 302	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2190	1	3	302	Classroom 302	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2190	1	3	PC302	Classroom 302 Pipe Chase	Yes	W1	No Access	No Access	No Access	No Access	No Access	No Access
2190	1	3	PC302	Classroom 302 Pipe Chase	Yes	W2	No Access	No Access	No Access	No Access	No Access	No Access
2190	1	3	PC302	Classroom 302 Pipe Chase	Yes	W3	No Access	No Access	No Access	No Access	No Access	No Access
2190	1	3	PC302	Classroom 302 Pipe Chase	Yes	W4	No Access	No Access	No Access	No Access	No Access	No Access
2190	1	3	PC302	Classroom 302 Pipe Chase	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
2190	1	3	PC302	Classroom 302 Pipe Chase	Yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access
2190	1	3	310	Classroom 310	Yes	W1	Plaster	White	None	0	21.2	Positive
2190	1	3	310	Classroom 310	Yes	W2	Plaster	White	None	0	22.3	Positive
2190	1	3	S31	Stairwell beside Classroom 307	Yes	W4	Plaster	White	Cracking	3	25.2	Positive
2190	1	1	S10	Stairwell outside of Main Office	Yes	Floor	Concrete	Grey	Friction	2	2.7	Positive
2190	1	3	310	Classroom 310	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2190	1	B	S01A	Northwest Stairwell Entrance Vestibule beside Room 3	Yes	W3	Metal	Blue	Friction	1	0.21	Negative
2190	1	B	H03A	East Hallway; South End	Yes	W3	Metal	Brown	Friction	1	0.01	Negative
2190	1	1	S10	Stairwell outside of Main Office	Yes	W2	Brick	White	Cracking	2	21.2	Positive
2190	1	B	S05	Stairwell beside Cafeteria B	Yes	W1	Metal	Brown	Friction	1	0.21	Negative

				Inspection Dates: 09/21/20-09/29/20									
				Name of Inspector: Michael Barth			Lead Safe Certification Assessment Report						
				Inspection Company: Criterion Labs			Fell Elementary School						
ULCS#	Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm <sup>2</sup> )	XRF (positive/negative)	
2190	1	1	S10	Stairwell outside of Main Office	Yes	W4	Brick	White	Cracking	2	22.7	Positive	
2190	1	B	S05A	Visitors Entrance Foyer to Northeast Stairwell beside Cafeteria B	Yes	W1	Metal	Brown	Friction	2	0.21	Negative	
2190	1	B	S02	Stairwell and Foyer beside Boy's Restroom	Yes	W3	Metal	Brown	Friction	1	0.21	Negative	
2190	1	3	304	Classroom 304	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	
2190	1	B	S01	Stairwell beside Basement Facilities Storage Room	Yes	W1	Metal	Brown	Friction	1	0.11	Negative	
2190	1	B	S01A	Northwest Stairwell Entrance Vestibule beside Room 3	Yes	W1	Metal	Brown	Friction	1	0.11	Negative	
2190	1	3	PC304	Classroom 304 Pipe Chase	Yes	W1	Brick	N/A	N/A	N/A	N/A	N/A	
2190	1	3	PC304	Classroom 304 Pipe Chase	Yes	W2	Brick	N/A	N/A	N/A	N/A	N/A	
2190	1	3	PC304	Classroom 304 Pipe Chase	Yes	W3	Brick	N/A	N/A	N/A	N/A	N/A	
2190	1	3	PC304	Classroom 304 Pipe Chase	Yes	W4	Brick	N/A	N/A	N/A	N/A	N/A	
2190	1	3	PC304	Classroom 304 Pipe Chase	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	
2190	1	3	PC304	Classroom 304 Pipe Chase	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
2190	1	B	23	Storage Closet beside Southeast Stairwell	Yes	Ceiling	Plaster	White	Moisture Damage	5	22.3	Positive	
2190	1	B	PTA4	PTA Lunchroom Storage Closet 4	Yes	W3	Wood	Green	None	0	N/A	N/A	
2190	1	B	23	Storage Closet beside Southeast Stairwell	Yes	Ceiling	Metal	Tan	Chipping	2	17.9	Positive	
2190	1	B	PTA4	PTA Lunchroom Storage Closet 4	Yes	W4	Wood	Green	None	0	N/A	N/A	
2190	1	3	305	Classroom 305	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	
2190	1	B	PTA	Lunch Room	Yes	W1	Wood	Green	None	0	0.1	Negative	
2190	1	3	PC305	Classroom 305 Pipe Chase	Yes	W1	No Access	No Access	No Access	No Access	No Access	No Access	
2190	1	3	PC305	Classroom 305 Pipe Chase	Yes	W2	No Access	No Access	No Access	No Access	No Access	No Access	
2190	1	3	PC305	Classroom 305 Pipe Chase	Yes	W3	No Access	No Access	No Access	No Access	No Access	No Access	

				Inspection Dates: 09/21/20-09/29/20								
				Name of Inspector: Michael Barth			Lead Safe Certification Assessment Report					
				Inspection Company: Criterion Labs			Fell Elementary School					
ULCS#	Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
2190	1	3	PC305	Classroom 305 Pipe Chase	Yes	W4	No Access	No Access	No Access	No Access	No Access	No Access
2190	1	3	PC305	Classroom 305 Pipe Chase	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
2190	1	3	PC305	Classroom 305 Pipe Chase	Yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access
2190	1	3	311	Storage Room across from Classroom 307	Yes	W1	Plaster	Tan	Cracking	2	23.6	Positive
2190	1	3	311	Storage Room across from Classroom 307	Yes	W2	Plaster	Tan	Moisture Damage	10	25.8	Positive
2190	1	3	311	Storage Room across from Classroom 307	Yes	Ceiling	Plaster	Tan	Chipping	2	29.1	Positive
2190	1	B	PTA	Lunch Room	Yes	W2	Wood	Green	None	0	0.3	Negative
2190	1	3	306	Classroom 306	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2190	1	B	PTA	Lunch Room	Yes	W3	Wood	Green	None	0	0.2	Negative
2190	1	3	PC306	Classroom 306 Pipe Chase	Yes	W1	Terracotta	N/A	N/A	N/A	N/A	N/A
2190	1	3	PC306	Classroom 306 Pipe Chase	Yes	W2	Terracotta	N/A	N/A	N/A	N/A	N/A
2190	1	3	PC306	Classroom 306 Pipe Chase	Yes	W3	Terracotta	N/A	N/A	N/A	N/A	N/A
2190	1	3	PC306	Classroom 306 Pipe Chase	Yes	W4	Terracotta	N/A	N/A	N/A	N/A	N/A
2190	1	3	PC306	Classroom 306 Pipe Chase	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2190	1	3	PC306	Classroom 306 Pipe Chase	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2190	1	2	210A	Storage Room beside Classroom 200	Yes	W1	Plaster	Tan	Cracking	2	21	Positive
2190	1	2	210A	Storage Room beside Classroom 200	Yes	W2	Plaster	Tan	Chipping	1	22.4	Positive
2190	1	2	210A	Storage Room beside Classroom 200	Yes	W3	Plaster	Tan	Chipping	3	23.4	Positive
2190	1	B	PTA	Lunch Room	Yes	W4	Wood	Green	None	0	0.21	Negative
2190	1	2	210A	Storage Room beside Classroom 200	Yes	W4	Plaster	Tan	Cracking	1	21.5	Positive
2190	1	2	210A	Storage Room beside Classroom 200	Yes	Ceiling	Plaster	Tan	Moisture Damage	2	26.7	Positive
2190	1	2	215	Teacher's Lounge 215	Yes	W3	Metal	Grey	Chipping	1	1.5	Positive

				Inspection Dates: 09/21/20-09/29/20								
				Name of Inspector: Michael Barth		Lead Safe Certification Assessment Report						
				Inspection Company: Criterion Labs		Fell Elementary School						
ULCS#	Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm <sup>2</sup> )	XRF (positive/negative)
2190	1	3	307	Classroom 307	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2190	1	2	215	Teacher's Lounge 215	Yes	W1	Wood	White	Friction	2	8.9	Positive
2190	1	3	308	Classroom 308	Yes	W1	Plaster	Tan	None	0	26.1	Positive
2190	1	2	215	Teacher's Lounge 215	Yes	W1	Wood	White	Chipping	1	10.1	Positive
2190	1	2	215	Teacher's Lounge 215	Yes	W2	Wood	White	Friction	1	7.2	Positive
2190	1	B	2A	RM2 Storage Closet A	Yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
2190	1	3	308	Classroom 308	Yes	W4	Plaster	Tan	None	0	19.1	Positive
2190	1	3	308	Classroom 308	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2190	1	B	2B	RM2 Storage Closet B	Yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
2190	1	2	215	Teacher's Lounge 215	Yes	W2	Wood	White	Friction	1	6.4	Positive
2190	1	2	215	Teacher's Lounge 215	Yes	W1	Plaster	Blue	Chipping	1	22.4	Positive
2190	1	B	B3	Kitchen Storage Room 3	Yes	W3	Wood	Tan	Chipping	1	0.2	Negative
2190	1	B	B3	Kitchen Storage Room 3	Yes	W4	Wood	Tan	Chipping	1	0.21	Negative
2190	1	2	215	Teacher's Lounge 215	Yes	W1	Plaster	Tan	Chipping	1	21.7	Positive
2190	1	B	RM2	Music Room	Yes	W2	Wood	Tan	None	0	0.1	Negative
2190	1	B	B1	Kitchen Storage Room 1	No	Ceiling	Metal	Tan	Flaking	5	12.2	Positive
2190	1	2	215	Teacher's Lounge 215	Yes	W3	Wood	White	Cracking	3	4.5	Positive
2190	1	3	309	Classroom 309	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2190	1	2	215	Teacher's Lounge 215	Yes	W3	Wood	White	Cracking	3	5.2	Positive
2190	1	3	PC309	Classroom 309 Pipe Chase	Yes	W1	No Access	No Access	No Access	No Access	No Access	No Access
2190	1	3	PC309	Classroom 309 Pipe Chase	Yes	W2	No Access	No Access	No Access	No Access	No Access	No Access
2190	1	3	PC309	Classroom 309 Pipe Chase	Yes	W3	No Access	No Access	No Access	No Access	No Access	No Access
2190	1	3	PC309	Classroom 309 Pipe Chase	Yes	W4	No Access	No Access	No Access	No Access	No Access	No Access
2190	1	3	PC309	Classroom 309 Pipe Chase	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
2190	1	3	PC309	Classroom 309 Pipe Chase	Yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access
2190	1	2	215	Teacher's Lounge 215	Yes	W4	Wood	White	Chipping	1	6.8	Positive
2190	1	2	215	Teacher's Lounge 215	Yes	W4	Wood	White	Friction	3	8.6	Positive
2190	1	2	215	Teacher's Lounge 215	Yes	W4	Wood	White	Friction	1	7.3	Positive
2190	1	2	215	Teacher's Lounge 215	Yes	W4	Wood	White	Flaking	1	6.4	Positive
2190	1	3	303	Classroom 303	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2190	1	2	215A	Teacher's Lounge 215 Storage Closet	Yes	W1	Wood	Tan	Chipping	1	5.8	Positive
2190	1	2	215A	Teacher's Lounge 215 Storage Closet	Yes	W1	Wood	Tan	Chipping	1	20.6	Positive

				Inspection Dates: 09/21/20-09/29/20									
				Name of Inspector: Michael Barth			Lead Safe Certification Assessment Report						
				Inspection Company: Criterion Labs			Fell Elementary School						
ULCS#	Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm <sup>2</sup> )	XRF (positive/negative)	
2190	1	2	215A	Teacher's Lounge 215 Storage Closet	Yes	W4	Wood	Tan	Cracking	8	4.8	Positive	
2190	1	3	311	Storage Room across from Classroom 307	Yes	W1	Concrete	Grey	None	0	4.3	Positive	
2190	1	2	215A	Teacher's Lounge 215 Storage Closet	Yes	W1	Wood	Tan	Chipping	1	21.4	Positive	
2190	1	3	311	Storage Room across from Classroom 307	Yes	W2	Concrete	Grey	None	0	2.5	Positive	
2190	1	3	311	Storage Room across from Classroom 307	Yes	W3	Plaster	Tan	Partially Inaccessible	0	21.2	Positive	
2190	1	3	311	Storage Room across from Classroom 307	Yes	W3	Concrete	Grey	None	0	4.6	Positive	
2190	1	3	311	Storage Room across from Classroom 307	Yes	W4	Plaster	Tan	Partially Inaccessible	0	23.4	Positive	
2190	1	3	311	Storage Room across from Classroom 307	Yes	W4	Concrete	Grey	None	0	3.7	Positive	
2190	1	2	215A	Teacher's Lounge 215 Storage Closet	Yes	W1	Plaster	White	Chipping	8	27.1	Positive	
2190	1	3	311	Storage Room across from Classroom 307	Yes	Floor	Concrete	N/A	None	0	N/A	N/A	
2190	1	3	312	Janitors Closet beside Classroom 306	No	W1	Plaster	Tan	Cracking	2	21.2	Positive	
2190	1	3	312	Janitors Closet beside Classroom 306	No	W2	Plaster	Tan	Cracking	1	22.3	Positive	
2190	1	3	312	Janitors Closet beside Classroom 306	No	W3	Plaster	Tan	Cracking	1	18.9	Positive	
2190	1	3	312	Janitors Closet beside Classroom 306	No	W4	Plaster	Tan	Chipping	1	17.4	Positive	
2190	1	3	312	Janitors Closet beside Classroom 306	No	Ceiling	Plaster	Tan	Moisture Damage	4	21.4	Positive	
2190	1	3	312	Janitors Closet beside Classroom 306	No	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
2190	1	2	215A	Teacher's Lounge 215 Storage Closet	Yes	W3	Plaster	White	Alligatoring	5	25.7	Positive	
2190	1	3	313	Large Storage Closet outside of Classroom 309	Yes	W1	Concrete	Grey	None	0	1.5	Positive	
2190	1	2	215A	Teacher's Lounge 215 Storage Closet	Yes	Ceiling	Plaster	White	Cracking	1	18.9	Positive	
2190	1	3	313	Large Storage Closet outside of Classroom 309	Yes	W2	Concrete	Grey	None	0	3.2	Positive	
2190	1	2	216	Teacher's Lounge 216	Yes	W2	Wood	Tan	Chipping	1	6.7	Positive	



				Inspection Dates: 09/21/20-09/29/20								
				Name of Inspector: Michael Barth		Lead Safe Certification Assessment Report						
				Inspection Company: Criterion Labs		Fell Elementary School						
ULCS#	Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm <sup>2</sup> )	XRF (positive/negative)
2190	1	3	313	Large Storage Closet outside of Classroom 309	Yes	W3	Concrete	Grey	None	0	2.2	Positive
2190	1	2	216	Teacher's Lounge 216	Yes	W3	Metal	Grey	Chipping	1	1.6	Positive
2190	1	2	216	Teacher's Lounge 216	Yes	W1	Wood	Tan	Chipping	1	8.8	Positive
2190	1	3	313	Large Storage Closet outside of Classroom 309	Yes	W4	Concrete	Grey	None	0	1.4	Positive
2190	1	2	216	Teacher's Lounge 216	Yes	W1	Wood	Tan	Friction	2	9.6	Positive
2190	1	3	313	Large Storage Closet outside of Classroom 309	Yes	Floor	Concrete	Brown	None	0	1.5	Positive
2190	1	3	314	Janitors Closet beside Classroom 303	No	W1	Plaster	Tan	Cracking	2	21.2	Positive
2190	1	3	314	Janitors Closet beside Classroom 303	No	W2	Plaster	Tan	Chipping	3	23.2	Positive
2190	1	3	314	Janitors Closet beside Classroom 303	No	W3	Plaster	Tan	Chipping	3	22.7	Positive
2190	1	3	314	Janitors Closet beside Classroom 303	No	W4	Plaster	Tan	Cracking	5	24.1	Positive
2190	1	3	314	Janitors Closet beside Classroom 303	No	Ceiling	Plaster	Tan	Moisture Damage	3	19.2	Positive
2190	1	3	314	Janitors Closet beside Classroom 303	No	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
2190	1	3	315	Storage Closet across from 302	No	W1	Plaster	Tan	Cracking/Partially Inaccessible	2	22.3	Positive
2190	1	3	315	Storage Closet across from 302	No	W2	Plaster	Tan	Cracking	1	22.1	Positive
2190	1	3	315	Storage Closet across from 302	No	W3	Plaster	Tan	Cracking/Partially Inaccessible	2	24.1	Positive
2190	1	2	216	Teacher's Lounge 216	Yes	W1	Wood	Tan	Friction	1	7.4	Positive
2190	1	3	315	Storage Closet across from 302	No	W4	Plaster	Tan	Cracking/Moisture Damage	8	23.4	Positive
2190	1	2	216	Teacher's Lounge 216	Yes	W1	Wood	Tan	Cracking	1	6.7	Positive
2190	1	3	315	Storage Closet across from 302	No	Ceiling	Plaster	Tan	Moisture Damage	6	21.2	Positive
2190	1	3	315	Storage Closet across from 302	No	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
2190	1	2	216	Teacher's Lounge 216	Yes	W2	Wood	Tan	Cracking	2	5.4	Positive
2190	1	2	216	Teacher's Lounge 216	Yes	W2	Wood	Tan	Flaking	5	11.6	Positive
2190	1	2	216	Teacher's Lounge 216	Yes	W3	Wood	Tan	Cracking	5	14.6	Positive
2190	1	3	H310	Hallway outside Classrooms 307 - 309	Yes	W3	Plaster	Yellow/Green	None	0	21.4	Positive
2190	1	2	216	Teacher's Lounge 216	Yes	W1	Plaster	Blue	Cracking	5	21.4	Positive

				Inspection Dates: 09/21/20-09/29/20									
				Name of Inspector: Michael Barth			Lead Safe Certification Assessment Report						
				Inspection Company: Criterion Labs			Fell Elementary School						
ULCS#	Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm <sup>2</sup> )	XRF (positive/negative)	
2190	1	3	H310	Hallway outside Classrooms 307 - 309	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	
2190	1	3	H310	Hallway outside Classrooms 307 - 309	Yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
2190	1	2	216	Teacher's Lounge 216	Yes	W2	Plaster	Blue	Chipping	10	25.6	Positive	
2190	1	2	216	Teacher's Lounge 216	Yes	W3	Plaster	Tan	Chipping	10	24.9	Positive	
2190	1	2	216A	Teacher's Lounge 216 Staff Restroom	Yes	W3	Metal	Grey	Chipping	2	1.7	Positive	
2190	1	2	216A	Teacher's Lounge 216 Staff Restroom	Yes	W3	Plaster	White	Cracking	2	21.3	Positive	
2190	1	2	216A	Teacher's Lounge 216 Staff Restroom	Yes	Ceiling	Plaster	White	Cracking	1	25.1	Positive	
2190	1	3	H312	Hallway outside Classrooms 300 - 302	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	
2190	1	3	H312	Hallway outside Classrooms 300 - 302	Yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
2190	1	B	S05A	Visitors Entrance Foyer to Northeast Stairwell beside Cafeteria B	Yes	W1	Plaster	Blue	Cracking	5	15.7	Positive	
2190	1	B	S05A	Visitors Entrance Foyer to Northeast Stairwell beside Cafeteria B	Yes	W2	Plaster	Blue	Chipping	10	18.9	Positive	
2190	1	B	S05A	Visitors Entrance Foyer to Northeast Stairwell beside Cafeteria B	Yes	W3	Plaster	Blue	Cracking	3	21.3	Positive	
2190	1	B	S05A	Visitors Entrance Foyer to Northeast Stairwell beside Cafeteria B	Yes	W4	Plaster	Blue	Moisture Damage	1	18.9	Positive	
2190	1	B	S05A	Visitors Entrance Foyer to Northeast Stairwell beside Cafeteria B	Yes	W2	Metal	Grey	Chipping	1	1.8	Positive	
2190	1	3	S31	Stairwell beside Classroom 307	Yes	Ceiling	Plaster	White	None	0	N/A	N/A	
2190	1	3	S31	Stairwell beside Classroom 307	Yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
2190	1	3	S31	Stairwell beside Classroom 307	Yes	Floor	Concrete	Grey	None	0	0.2	Negative	
2190	1	1	H14	West Hallway	Yes	Floor	Concrete	Grey	Friction	5	4.3	Positive	
2190	1	3	S34	Fire Tower Stairwell	Yes	W1	Brick	White	None	0	18.6	Positive	
2190	1	3	S34	Fire Tower Stairwell	Yes	W2	Brick	White	None	0	16.7	Positive	
2190	1	3	S34	Fire Tower Stairwell	Yes	W3	Brick	White	None	0	20.1	Positive	
2190	1	3	S34	Fire Tower Stairwell	Yes	W4	Brick	White	None	0	19.3	Positive	

				Inspection Dates: 09/21/20-09/29/20								
				Name of Inspector: Michael Barth			Lead Safe Certification Assessment Report					
				Inspection Company: Criterion Labs			Fell Elementary School					
ULCS#	Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm <sup>2</sup> )	XRF (positive/negative)
2190	1	3	S34	Fire Tower Stairwell	Yes	Ceiling	Plaster	White	None	0	21.2	Positive
2190	1	3	S34	Fire Tower Stairwell	Yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
2190	1	1	H14	West Hallway	Yes	W2	Metal	Grey	Chipping	2	1.5	Positive
2190	1	3	S35	Stairwell beside Classroom 302	Yes	W2	Plaster	White	None	0	N/A	N/A
2190	1	1	H14	West Hallway	Yes	W2	Plaster	Red	Chipping	5	21.3	Positive
2190	1	1	H14	West Hallway	Yes	W2	Plaster	Yellow	Chipping	15	22.7	Positive
2190	1	1	H14	West Hallway	Yes	W3	Plaster	Red	Cracking	1	23.4	Positive
2190	1	3	S35	Stairwell beside Classroom 302	Yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
2190	1	3	S35	Stairwell beside Classroom 302	Yes	Floor	Concrete	Grey	None	0	0.2	Negative
2190	1	1	H14	West Hallway	Yes	W4	Plaster	Red	Chipping/Cracking	3	18.9	Positive
2190	1	3	300A	Classroom 300 Coat Closet	Yes	W1	No Access	No Access	No Access	No Access	No Access	No Access
2190	1	3	300A	Classroom 300 Coat Closet	Yes	W2	No Access	No Access	No Access	No Access	No Access	No Access
2190	1	3	300A	Classroom 300 Coat Closet	Yes	W3	No Access	No Access	No Access	No Access	No Access	No Access
2190	1	3	300A	Classroom 300 Coat Closet	Yes	W4	No Access	No Access	No Access	No Access	No Access	No Access
2190	1	3	300A	Classroom 300 Coat Closet	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
2190	1	3	300A	Classroom 300 Coat Closet	Yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access
2190	1	3	301A	Classroom 301 Coat Closet	Yes	W1	No Access	No Access	No Access	No Access	No Access	No Access
2190	1	3	301A	Classroom 301 Coat Closet	Yes	W2	No Access	No Access	No Access	No Access	No Access	No Access
2190	1	3	301A	Classroom 301 Coat Closet	Yes	W3	No Access	No Access	No Access	No Access	No Access	No Access
2190	1	3	301A	Classroom 301 Coat Closet	Yes	W4	No Access	No Access	No Access	No Access	No Access	No Access
2190	1	3	301A	Classroom 301 Coat Closet	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
2190	1	3	301A	Classroom 301 Coat Closet	Yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access
2190	1	3	302A	Classroom 302 Coat Closet	Yes	W1	No Access	No Access	No Access	No Access	No Access	No Access
2190	1	3	302A	Classroom 302 Coat Closet	Yes	W2	No Access	No Access	No Access	No Access	No Access	No Access

				Inspection Dates: 09/21/20-09/29/20								
				Name of Inspector: Michael Barth		Lead Safe Certification Assessment Report						
				Inspection Company: Criterion Labs		Fell Elementary School						
ULCS#	Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
2190	1	3	302A	Classroom 302 Coat Closet	Yes	W3	No Access	No Access	No Access	No Access	No Access	No Access
2190	1	3	302A	Classroom 302 Coat Closet	Yes	W4	No Access	No Access	No Access	No Access	No Access	No Access
2190	1	3	302A	Classroom 302 Coat Closet	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
2190	1	3	302A	Classroom 302 Coat Closet	Yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access
2190	1	3	303A	Classroom 303 Coat Closet	Yes	W1	No Access	No Access	No Access	No Access	No Access	No Access
2190	1	3	303A	Classroom 303 Coat Closet	Yes	W2	No Access	No Access	No Access	No Access	No Access	No Access
2190	1	3	303A	Classroom 303 Coat Closet	Yes	W3	No Access	No Access	No Access	No Access	No Access	No Access
2190	1	3	303A	Classroom 303 Coat Closet	Yes	W4	No Access	No Access	No Access	No Access	No Access	No Access
2190	1	3	303A	Classroom 303 Coat Closet	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
2190	1	3	303A	Classroom 303 Coat Closet	Yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access
2190	1	1	H14	West Hallway	Yes	W4	Plaster	Yellow	Chipping/Cracking	5	21.4	Positive
2190	1	1	100C	Women's Restroom	Yes	W1	Plaster	Tan	Cracking	2	21.2	Positive
2190	1	1	100C	Women's Restroom	Yes	W3	Plaster	Tan	Cracking	1	23.1	Positive
2190	1	1	100C	Women's Restroom	Yes	W4	Plaster	Tan	Cracking	1	22.3	Positive
2190	1	3	304A	Classroom 304 Coat Closet	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2190	1	B	2A	RM2 Storage Closet A	Yes	Ceiling	Metal	White	None	0	12.2	Positive
2190	1	3	305A	Classroom 305 Coat Closet	Yes	W1	No Access	No Access	No Access	No Access	No Access	No Access
2190	1	3	305A	Classroom 305 Coat Closet	Yes	W2	No Access	No Access	No Access	No Access	No Access	No Access
2190	1	3	305A	Classroom 305 Coat Closet	Yes	W3	No Access	No Access	No Access	No Access	No Access	No Access
2190	1	3	305A	Classroom 305 Coat Closet	Yes	W4	No Access	No Access	No Access	No Access	No Access	No Access
2190	1	3	305A	Classroom 305 Coat Closet	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
2190	1	3	305A	Classroom 305 Coat Closet	Yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access
2190	1	3	305B	Classroom 305 Rear Storage Closet	Yes	W1	No Access	No Access	No Access	No Access	No Access	No Access

				Inspection Dates: 09/21/20-09/29/20								
				Name of Inspector: Michael Barth		Lead Safe Certification Assessment Report						
				Inspection Company: Criterion Labs		Fell Elementary School						
ULCS#	Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm <sup>2</sup> )	XRF (positive/negative)
2190	1	3	305B	Classroom 305 Rear Storage Closet	Yes	W2	No Access	No Access	No Access	No Access	No Access	No Access
2190	1	3	305B	Classroom 305 Rear Storage Closet	Yes	W3	No Access	No Access	No Access	No Access	No Access	No Access
2190	1	3	305B	Classroom 305 Rear Storage Closet	Yes	W4	No Access	No Access	No Access	No Access	No Access	No Access
2190	1	3	305B	Classroom 305 Rear Storage Closet	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
2190	1	3	305B	Classroom 305 Rear Storage Closet	Yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access
2190	1	3	306A	Classroom 306 Coat Closet	Yes	W1	No Access	No Access	No Access	No Access	No Access	No Access
2190	1	3	306A	Classroom 306 Coat Closet	Yes	W2	No Access	No Access	No Access	No Access	No Access	No Access
2190	1	3	306A	Classroom 306 Coat Closet	Yes	W3	No Access	No Access	No Access	No Access	No Access	No Access
2190	1	3	306A	Classroom 306 Coat Closet	Yes	W4	No Access	No Access	No Access	No Access	No Access	No Access
2190	1	3	306A	Classroom 306 Coat Closet	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
2190	1	3	306A	Classroom 306 Coat Closet	Yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access
2190	1	3	307A	Classroom 307 Coat Closet	Yes	W1	No Access	No Access	No Access	No Access	No Access	No Access
2190	1	3	307A	Classroom 307 Coat Closet	Yes	W2	No Access	No Access	No Access	No Access	No Access	No Access
2190	1	3	307A	Classroom 307 Coat Closet	Yes	W3	No Access	No Access	No Access	No Access	No Access	No Access
2190	1	3	307A	Classroom 307 Coat Closet	Yes	W4	No Access	No Access	No Access	No Access	No Access	No Access
2190	1	3	307A	Classroom 307 Coat Closet	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
2190	1	3	307A	Classroom 307 Coat Closet	Yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access
2190	1	3	308A	Classroom 308 Coat Closet	Yes	W1	No Access	No Access	No Access	No Access	No Access	No Access
2190	1	3	308A	Classroom 308 Coat Closet	Yes	W2	No Access	No Access	No Access	No Access	No Access	No Access
2190	1	3	308A	Classroom 308 Coat Closet	Yes	W3	No Access	No Access	No Access	No Access	No Access	No Access
2190	1	3	308A	Classroom 308 Coat Closet	Yes	W4	No Access	No Access	No Access	No Access	No Access	No Access

				Inspection Dates: 09/21/20-09/29/20								
				Name of Inspector: Michael Barth		Lead Safe Certification Assessment Report						
				Inspection Company: Criterion Labs		Fell Elementary School						
ULCS#	Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm <sup>2</sup> )	XRF (positive/negative)
2190	1	3	308A	Classroom 308 Coat Closet	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
2190	1	3	308A	Classroom 308 Coat Closet	Yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access
2190	1	3	309A	Classroom 309 Coat Closet	Yes	W1	No Access	No Access	No Access	No Access	No Access	No Access
2190	1	3	309A	Classroom 309 Coat Closet	Yes	W2	No Access	No Access	No Access	No Access	No Access	No Access
2190	1	3	309A	Classroom 309 Coat Closet	Yes	W3	No Access	No Access	No Access	No Access	No Access	No Access
2190	1	3	309A	Classroom 309 Coat Closet	Yes	W4	No Access	No Access	No Access	No Access	No Access	No Access
2190	1	3	309A	Classroom 309 Coat Closet	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
2190	1	3	309A	Classroom 309 Coat Closet	Yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access
2190	1	3	310A	Classroom 310 Coat Closet	Yes	W1	No Access	No Access	No Access	No Access	No Access	No Access
2190	1	3	310A	Classroom 310 Coat Closet	Yes	W2	No Access	No Access	No Access	No Access	No Access	No Access
2190	1	3	310A	Classroom 310 Coat Closet	Yes	W3	No Access	No Access	No Access	No Access	No Access	No Access
2190	1	3	310A	Classroom 310 Coat Closet	Yes	W4	No Access	No Access	No Access	No Access	No Access	No Access
2190	1	3	310A	Classroom 310 Coat Closet	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
2190	1	3	310A	Classroom 310 Coat Closet	Yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access
2190	1	3	PC310A	Classroom 310 Coat Closet Pipe Chase	Yes	W1	No Access	No Access	No Access	No Access	No Access	No Access
2190	1	3	PC310A	Classroom 310 Coat Closet Pipe Chase	Yes	W2	No Access	No Access	No Access	No Access	No Access	No Access
2190	1	3	PC310A	Classroom 310 Coat Closet Pipe Chase	Yes	W3	No Access	No Access	No Access	No Access	No Access	No Access
2190	1	3	PC310A	Classroom 310 Coat Closet Pipe Chase	Yes	W4	No Access	No Access	No Access	No Access	No Access	No Access
2190	1	3	PC310A	Classroom 310 Coat Closet Pipe Chase	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
2190	1	3	PC310A	Classroom 310 Coat Closet Pipe Chase	Yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access

				Inspection Dates: 09/21/20-09/29/20								
				Name of Inspector: Michael Barth		Lead Safe Certification Assessment Report						
				Inspection Company: Criterion Labs		Fell Elementary School						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm <sup>2</sup> )	XRF (positive/ negative)
2190	1	A	R8	Tank Room - Accessed from Janitors Closet beside Northeast Stairwell (314)	No	W1	Brick	N/A	None	0	N/A	N/A
2190	1	A	R8	Tank Room - Accessed from Janitors Closet beside Northeast Stairwell (314)	No	W2	Brick	N/A	None	0	N/A	N/A
2190	1	A	R8	Tank Room - Accessed from Janitors Closet beside Northeast Stairwell (314)	No	W3	Brick	N/A	None	0	N/A	N/A
2190	1	A	R8	Tank Room - Accessed from Janitors Closet beside Northeast Stairwell (314)	No	W4	Brick	N/A	None	0	N/A	N/A
2190	1	A	R8	Tank Room - Accessed from Janitors Closet beside Northeast Stairwell (314)	No	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2190	1	A	R8	Tank Room - Accessed from Janitors Closet beside Northeast Stairwell (314)	No	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2190	1	A	AT	Attic accessible from 3rd Floor Janitor's Closet beside Northeast Stairwell	No	W1	Brick	N/A	None	0	N/A	N/A
2190	1	A	AT	Attic accessible from 3rd Floor Janitor's Closet beside Northeast Stairwell	No	W2	Brick	N/A	None	0	N/A	N/A
2190	1	A	AT	Attic accessible from 3rd Floor Janitor's Closet beside Northeast Stairwell	No	W3	Brick	N/A	None	0	N/A	N/A
2190	1	A	AT	Attic accessible from 3rd Floor Janitor's Closet beside Northeast Stairwell	No	W4	Brick	N/A	None	0	N/A	N/A

				Inspection Dates: 09/21/20-09/29/20		Lead Safe Certification Assessment Report						
				Name of Inspector: Michael Barth		Fell Elementary School						
				Inspection Company: Criterion Labs								
ULCS#	Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm <sup>2</sup> )	XRF (positive/negative)
2190	1	A	AT	Attic accessible from 3rd Floor Janitor's Closet beside Northeast Stairwell	No	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2190	1	A	AT	Attic accessible from 3rd Floor Janitor's Closet beside Northeast Stairwell	No	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2190	1	A	AT	Attic above 3rd Floor - accessible by Tank Room	No	W1	Brick	N/A	None	0	N/A	N/A
2190	1	A	AT	Attic above 3rd Floor - accessible by Tank Room	No	W2	Brick	N/A	None	0	N/A	N/A
2190	1	A	AT	Attic above 3rd Floor - accessible by Tank Room	No	W3	Brick	N/A	None	0	N/A	N/A
2190	1	A	AT	Attic above 3rd Floor - accessible by Tank Room	No	W4	Brick	N/A	None	0	N/A	N/A
2190	1	A	AT	Attic above 3rd Floor - accessible by Tank Room	No	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2190	1	A	AT	Attic above 3rd Floor - accessible by Tank Room	No	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2190	1	A	AT	Attic above Auditorium - accessible by Room next to Stage	No	W1	Brick	N/A	None	0	N/A	N/A
2190	1	A	AT	Attic above Auditorium - accessible by Room next to Stage	No	W2	Brick	N/A	None	0	N/A	N/A
2190	1	A	AT	Attic above Auditorium - accessible by Room next to Stage	No	W3	Brick	N/A	None	0	N/A	N/A
2190	1	A	AT	Attic above Auditorium - accessible by Room next to Stage	No	W4	Brick	N/A	None	0	N/A	N/A
2190	1	A	AT	Attic above Auditorium - accessible by Room next to Stage	No	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2190	1	A	AT	Attic above Auditorium - accessible by Room next to Stage	No	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2190	1	C	CS	Crawlspace accessible by back of Stage in Auditorium	No	W1	Brick	N/A	None	0	N/A	N/A



				Inspection Dates: 09/21/20-09/29/20								
				Name of Inspector: Michael Barth		Lead Safe Certification Assessment Report						
				Inspection Company: Criterion Labs		Fell Elementary School						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
2190	1	C	CS	Crawlspace accessible by back of Stage in Auditorium	No	W2	Brick	N/A	None	0	N/A	N/A
2190	1	C	CS	Crawlspace accessible by back of Stage in Auditorium	No	W3	Brick	N/A	None	0	N/A	N/A
2190	1	C	CS	Crawlspace accessible by back of Stage in Auditorium	No	W4	Brick	N/A	None	0	N/A	N/A
2190	1	C	CS	Crawlspace accessible by back of Stage in Auditorium	No	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2190	1	C	CS	Crawlspace accessible by back of Stage in Auditorium	No	Floor	N/A	N/A	N/A	N/A	N/A	N/A