

				Inspection Dates: May 2020		School District of Philadelphia						
				James Mongan		Lead Safe Certification Assessment Report						
				Vertex		Cayuga Elementary School						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
5490	1	B	CAFE	Cafeteria	yes	W1	Sheetrock	Tan	chipping/cracking	15	0	Negative
5490	1	B	CAFE	Cafeteria	yes	W1	Sheetrock	Blue	Chipping	1	0	Negative
5490	1	B	CAFE	Cafeteria	yes	W1	Sheetrock	Green	Chipping	1	0	Negative
5490	1	B	CAFE	Cafeteria	yes	W2	Plaster	Tan	Cracking	15	0.01	Negative
5490	1	B	CAFE	Cafeteria	yes	W3	Plaster	Yellow	Cracking	4	0.06	Negative
5490	1	B	CAFE	Cafeteria	yes	W4	Plaster	Tan	Cracking/chipping	13	0.01	Negative
5490	1	B	CAFE	Cafeteria	yes	W4	Sheetrock	Tan	Chipping	3	0	Negative
5490	1	B	CAFE	Cafeteria	yes	Floor	Concrete	N/A	None	0	N/A	N/A
5490	1	B	CAFE	Cafeteria	yes	Ceiling	Plaster	N/A	None	0	N/A	N/A
5490	1	B	14	Generator Room next to Cafeteria	no	W1	N/A	N/A	N/A	N/A	N/A	N/A
5490	1	B	14	Generator Room next to Cafeteria	no	W2	N/A	N/A	N/A	N/A	N/A	N/A
5490	1	B	14	Generator Room next to Cafeteria	no	W3	N/A	N/A	N/A	N/A	N/A	N/A
5490	1	B	14	Generator Room next to Cafeteria	no	W4	N/A	N/A	N/A	N/A	N/A	N/A
5490	1	B	14	Generator Room next to Cafeteria	no	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5490	1	B	14	Generator Room next to Cafeteria	no	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5490	1	B	G01	Girl's Restroom next to Cafeteria	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
5490	1	B	G01	Girl's Restroom next to Cafeteria	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
5490	1	B	G01	Girl's Restroom next to Cafeteria	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
5490	1	B	G01	Girl's Restroom next to Cafeteria	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
5490	1	B	G01	Girl's Restroom next to Cafeteria	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5490	1	B	G01	Girl's Restroom next to Cafeteria	yes	Ceiling	Plaster	White	None	0	N/A	N/A
5490	1	B	B01	Boy's Restroom next to Cafeteria	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
5490	1	B	B01	Boy's Restroom next to Cafeteria	yes	Door frame	Metal	Blue	Chipping	3	0	Negative
5490	1	B	B01	Boy's Restroom next to Cafeteria	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
5490	1	B	B01	Boy's Restroom next to Cafeteria	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
5490	1	B	B01	Boy's Restroom next to Cafeteria	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
5490	1	B	B01	Boy's Restroom next to Cafeteria	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5490	1	B	B01	Boy's Restroom next to Cafeteria	yes	Ceiling	Plaster	White	None	0	N/A	N/A
5490	1	B	11	Custodial Closet next to Cafeteria	no	W1	Sheetrock	Tan	None	0	N/A	N/A
5490	1	B	11	Custodial Closet next to Cafeteria	no	Door Frame	Metal	Tan	Chipping	8	0	
5490	1	B	11	Custodial Closet next to Cafeteria	no	W2	Sheetrock	Tan	None	0	N/A	N/A
5490	1	B	11	Custodial Closet next to Cafeteria	no	W3	Sheetrock	Tan	Efflorescence	4	0	Negative
5490	1	B	11	Custodial Closet next to Cafeteria	no	W4	Sheetrock	Tan	Chipping	4	0	Negative
5490	1	B	11	Custodial Closet next to Cafeteria	no	Floor	Concrete	N/A	N/A	0	N/A	N/A

				Inspection Dates: May 2020		School District of Philadelphia						
				James Mongan		Lead Safe Certification Assessment Report						
				Vertex		Cayuga Elementary School						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
5490	1	B	11	Custodial Closet next to Cafeteria	no	Ceiling	Sheetrock	Tan	None	0	N/A	N/A
5490	1	B	V01	Vestibule between Cafeteria and Stairwell 3	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
5490	1	B	V01	Vestibule between Cafeteria and Stairwell 3	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
5490	1	B	V01	Vestibule between Cafeteria and Stairwell 3	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
5490	1	B	V01	Vestibule between Cafeteria and Stairwell 3	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
5490	1	B	V01	Vestibule between Cafeteria and Stairwell 3	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
5490	1	B	V01	Vestibule between Cafeteria and Stairwell 3	yes	Ceiling	Plaster	White	holes	3		
5490	1	B	V02	Vestibule outside of Elevator Machine Room 009A	no	W1	Plaster	White	holes	1	0.05	Negative
5490	1	B	V02	Vestibule outside of Elevator Machine Room 009A	no	Door	Metal	Blue	Chipping	2	0	Negative
5490	1	B	V02	Vestibule outside of Elevator Machine Room 009A	no	W2	Plaster	White	None	0	N/A	N/A
5490	1	B	V02	Vestibule outside of Elevator Machine Room 009A	no	W3	concrete block	Tan	None	0	N/A	N/A
5490	1	B	V02	Vestibule outside of Elevator Machine Room 009A	no	W4	Plaster	Tan	holes	1	0.05	Negative
5490	1	B	V02	Vestibule outside of Elevator Machine Room 009A	no	Floor	Concrete	N/A	N/A	0	N/A	N/A
5490	1	B	V02	Vestibule outside of Elevator Machine Room 009A	no	Ceiling	Plaster	White	Partially Inaccessible	0	N/A	N/A
5490	1	B	EMR	Elevator Machine Room 009A	no	W1	Concrete	White	None	0	N/A	N/A
5490	1	B	EMR	Elevator Machine Room 009A	no	W2	N/A	N/A	N/A	N/A	N/A	N/A
5490	1	B	EMR	Elevator Machine Room 009A	no	W3	N/A	N/A	N/A	N/A	N/A	N/A
5490	1	B	EMR	Elevator Machine Room 009A	no	W4	N/A	N/A	N/A	N/A	N/A	N/A
5490	1	B	EMR	Elevator Machine Room 009A	no	Floor	Concrete	N/A	N/A	0	N/A	N/A
5490	1	B	EMR	Elevator Machine Room 009A	no	Ceiling	Sheetrock	N/A	N/A	0	N/A	N/A
5490	1	B	S03	Stairwell 3 next to Boy's Restroom	yes	W1	Concrete	N/A	N/A	0	N/A	N/A
5490	1	B	S03	Stairwell 3 next to Boy's Restroom	yes	Door Frame	Metal	Blue	Chipping	5	0	Negative
5490	1	B	S03	Stairwell 3 next to Boy's Restroom	yes	W2	Concrete	N/A	N/A	0	N/A	N/A
5490	1	B	S03	Stairwell 3 next to Boy's Restroom	yes	W3	Concrete	N/A	N/A	0	N/A	N/A
5490	1	B	S03	Stairwell 3 next to Boy's Restroom	yes	W4	Concrete	N/A	N/A	0	N/A	N/A

				Inspection Dates: May 2020		School District of Philadelphia						
				James Mongan		Lead Safe Certification Assessment Report						
				Vertex		Cayuga Elementary School						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
5490	1	B	S03	Stairwell 3 next to Boy's Restroom	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5490	1	B	S03	Stairwell 3 next to Boy's Restroom	yes	Ceiling	Metal	Blue	None	0	N/A	N/A
5490	1	B	S04	Stairwell 4 next to Kitchen	yes	W1	concrete/plaster	White	None	0	N/A	N/A
5490	1	B	S04	Stairwell 4 next to Kitchen	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
5490	1	B	S04	Stairwell 4 next to Kitchen	yes	W3	Plaster	White	None	0	N/A	N/A
5490	1	B	S04	Stairwell 4 next to Kitchen	yes	Door frame	Metal	Tan	Chipping	4	0	Negative
5490	1	B	S04	Stairwell 4 next to Kitchen	yes	W4	Plaster	White	None	0	N/A	N/A
5490	1	B	S04	Stairwell 4 next to Kitchen	yes	Floor	Concrete	N/A	N/A	0	N/A	N/A
5490	1	B	S04	Stairwell 4 next to Kitchen	yes	Ceiling	Plaster	White	Chipping	1		
5490	1	B	KIT	Kitchen	yes	W1	Sheetrock	Tan	Friction	6	0	Negative
5490	1	B	KIT	Kitchen	yes	Door	Metal	White	Chipping	3	0	Negative
5490	1	B	KIT	Kitchen	yes	Door Frame	Metal	White	Chipping	1	0	Negative
5490	1	B	KIT	Kitchen	yes	W2	Sheetrock	Tan	Chipping	1	0	Negative
5490	1	B	KIT	Kitchen	yes	W3	Sheetrock	Tan	Cracking	3	0	Negative
5490	1	B	KIT	Kitchen	yes	W4	Sheetrock	Tan	None	0	N/A	N/A
5490	1	B	KIT	Kitchen	yes	Floor	Concrete	N/A	N/A	0	N/A	N/A
5490	1	B	KIT	Kitchen	yes	Ceiling	Plaster	White	None	0	N/A	N/A
5490	1	B	K01	Kitchen Office	yes	W1	Sheetrock	Tan	None	0	N/A	N/A
5490	1	B	K01	Kitchen Office	yes	W2	Sheetrock	Tan	None	0	N/A	N/A
5490	1	B	K01	Kitchen Office	yes	W3	Sheetrock	Tan	Chipping	2	0	Negative
5490	1	B	K01	Kitchen Office	yes	W4	Sheetrock	Tan	None	0	N/A	N/A
5490	1	B	K01	Kitchen Office	yes	Floor	Concrete	N/A	None	0	N/A	N/A
5490	1	B	K01	Kitchen Office	yes	Ceiling	Plaster	White	None	0	N/A	N/A
5490	1	B	V03	Vestibule outside of Electrical Room 018	no	W1	Plaster	Tan	None	0	N/A	N/A
5490	1	B	V03	Vestibule outside of Electrical Room 018	no	door	Metal	White	Chipping	5	0	Negative
5490	1	B	V03	Vestibule outside of Electrical Room 018	no	door frame	Metal	White	Chipping	6	0	Negative
5490	1	B	V03	Vestibule outside of Electrical Room 018	no	W2	Concrete	Tan	None	0	N/A	N/A
5490	1	B	V03	Vestibule outside of Electrical Room 018	no	W3	Plaster	Tan	Flaking	2	0	Negative
5490	1	B	V03	Vestibule outside of Electrical Room 018	no	W4	Plaster	Tan	cracking/chipping/spalling	10	0	Negative

				Inspection Dates: May 2020		School District of Philadelphia						
				James Mongan		Lead Safe Certification Assessment Report						
				Vertex		Cayuga Elementary School						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
5490	1	B	V03	Vestibule outside of Electrical Room 018	no	Floor	Concrete	N/A	N/A	0	N/A	N/A
5490	1	B	V03	Vestibule outside of Electrical Room 018	no	Ceiling	Sheetrock	Tan	None	0	N/A	N/A
5490	1	B	18	Electrical Room 018	no	W1	Plaster	Tan	cracking/flaking	14	1.6	Positive
5490	1	B	18	Electrical Room 018	no	Column	Concrete	White	Flaking	20	1.2	Positive
5490	1	B	18	Electrical Room 018	no	Column	Concrete	Brown	Flaking	10	88	Positive
5490	1	B	18	Electrical Room 018	no	door	Metal	White	Chipping	5		
5490	1	B	18	Electrical Room 018	no	door frame	Metal	White	Chipping	5		
5490	1	B	18	Electrical Room 018	no	W2	Concrete	N/A	N/A	0	N/A	N/A
5490	1	B	18	Electrical Room 018	no	W3	Concrete	N/A	N/A	0	N/A	N/A
5490	1	B	18	Electrical Room 018	no	Column	Concrete	White	Flaking	18	0.02	Negative
5490	1	B	18	Electrical Room 018	no	W4	Concrete	N/A	N/A	0	N/A	N/A
5490	1	B	18	Electrical Room 018	no	Floor	Concrete	N/A	N/A	0	N/A	N/A
5490	1	B	18	Electrical Room 018	no	Ceiling	Plaster	Tan	Chipping	30		
5490	1	1	H11	Main Hallway	yes	W1	Sheetrock	White	Chipping	1	0	Negative
5490	1	1	H11	Main Hallway	yes	W2	Sheetrock	Green	Chipping	7	0	Negative
5490	1	1	H11	Main Hallway	yes	W3	Sheetrock	Green	None	0	N/A	N/A
5490	1	1	H11	Main Hallway	yes	W4	Sheetrock	Green	Chipping	3	0	Negative
5490	1	1	H11	Main Hallway	yes	W4	Sheetrock	White	Peeling	2	0	Negative
5490	1	1	H11	Main Hallway	yes	Floor	Concrete		None	0	N/A	N/A
5490	1	1	H11	Main Hallway	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5490	1	1	S13	Stairwell 3 across from Teacher's Lounge 116	yes	W1	Plaster	White	None	0	N/A	N/A
5490	1	1	S13	Stairwell 3 across from Teacher's Lounge 116	yes	W2	Plaster	White	None	0	N/A	N/A
5490	1	1	S13	Stairwell 3 across from Teacher's Lounge 116	yes	W3	Plaster	White	None	0	N/A	N/A
5490	1	1	S13	Stairwell 3 across from Teacher's Lounge 116	yes	W4	Plaster	White	None	0	N/A	N/A
5490	1	1	S13	Stairwell 3 across from Teacher's Lounge 116	yes	Floor	Concrete	N/A	None	0	N/A	N/A
5490	1	1	S13	Stairwell 3 across from Teacher's Lounge 116	yes	Ceiling	Plaster	White	None	0	N/A	N/A
5490	1	1	S14	Stairwell 4 across from Office 121	yes	W1	Plaster	White	None	0	N/A	N/A
5490	1	1	S14	Stairwell 4 across from Office 121	yes	W2	Plaster	White	None	0	N/A	N/A
5490	1	1	S14	Stairwell 4 across from Office 121	yes	W3	Plaster	White	None	0	N/A	N/A

				Inspection Dates: May 2020		School District of Philadelphia						
				James Mongan		Lead Safe Certification Assessment Report						
				Vertex		Cayuga Elementary School						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
5490	1	1	S14	Stairwell 4 across from Office 121	yes	door frame	Metal	Red	Chipping	3	0	Negative
5490	1	1	S14	Stairwell 4 across from Office 121	yes	W4	Plaster	White	Chipping	1	0.11	Negative
5490	1	1	S14	Stairwell 4 across from Office 121	yes	Floor	Concrete	N/A	None	0	N/A	N/A
5490	1	1	S14	Stairwell 4 across from Office 121	yes	Ceiling	Plaster	White	hole	1		
5490	1	1	V11	Vestibule between Stairwell 3 and Teacher's Lounge 116	yes	W1	Sheetrock	White	Chipping	5	0	Negative
5490	1	1	V11	Vestibule between Stairwell 3 and Teacher's Lounge 116	yes	W2	ceramic	Tan	None	0	N/A	N/A
5490	1	1	V11	Vestibule between Stairwell 3 and Teacher's Lounge 116	yes	W3	ceramic	Tan	None	0	N/A	N/A
5490	1	1	V11	Vestibule between Stairwell 3 and Teacher's Lounge 116	yes	window sill	Concrete	Grey	Chipping	10	1.3	Positive
5490	1	1	V11	Vestibule between Stairwell 3 and Teacher's Lounge 116	yes	W4	ceramic	Tan	None	0	N/A	N/A
5490	1	1	V11	Vestibule between Stairwell 3 and Teacher's Lounge 116	yes	Floor	Concrete	Grey	Cracking	10	0	Negative
5490	1	1	V11	Vestibule between Stairwell 3 and Teacher's Lounge 116	yes	Ceiling	Plaster	White	None	0	N/A	N/A
5490	1	1	TL11	Teacher Lounge 116 across from Stairwell 3	yes	W1	Sheetrock	White	Chipping	1	0	Negative
5490	1	1	TL11	Teacher Lounge 116 across from Stairwell 3	yes	door frame	Metal	Blue	Chipping	2	0	Negative
5490	1	1	TL11	Teacher Lounge 116 across from Stairwell 3	yes	W2	Sheetrock	White	None	0	N/A	N/A
5490	1	1	TL11	Teacher Lounge 116 across from Stairwell 3	yes	W3	Sheetrock	Green	None	0	N/A	N/A
5490	1	1	TL11	Teacher Lounge 116 across from Stairwell 3	yes	W4	Sheetrock	White	None	0	N/A	N/A
5490	1	1	TL11	Teacher Lounge 116 across from Stairwell 3	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5490	1	1	TL11	Teacher Lounge 116 across from Stairwell 3	yes	Ceiling	Plaster	White	None	0	N/A	N/A
5490	1	1	W11	Women's Restroom inside Teacher Lounge 116	yes	W1	ceramic	Tan	None	0	N/A	N/A
5490	1	1	W11	Women's Restroom inside Teacher Lounge 116	yes	W2	ceramic	Tan	None	0	N/A	N/A
5490	1	1	W11	Women's Restroom inside Teacher Lounge 116	yes	W3	ceramic	Tan	None	0	N/A	N/A

				Inspection Dates: May 2020		School District of Philadelphia						
				James Mongan		Lead Safe Certification Assessment Report						
				Vertex		Cayuga Elementary School						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
5490	1	1	W11	Women's Restroom inside Teacher Lounge 116	yes	W4	ceramic	Tan	None	0	N/A	N/A
5490	1	1	W11	Women's Restroom inside Teacher Lounge 116	yes	Floor	ceramic	White	None	0	N/A	N/A
5490	1	1	W11	Women's Restroom inside Teacher Lounge 116	yes	Ceiling	Sheetrock	White	None	0	N/A	N/A
5490	1	1	M11	Men's Restroom inside Teacher Lounge 116	yes	W1	ceramic	Tan	None	0	N/A	N/A
5490	1	1	M11	Men's Restroom inside Teacher Lounge 116	yes	W2	ceramic	Tan	None	0	N/A	N/A
5490	1	1	M11	Men's Restroom inside Teacher Lounge 116	yes	W3	ceramic	Tan	None	0	N/A	N/A
5490	1	1	M11	Men's Restroom inside Teacher Lounge 116	yes	W4	ceramic	Tan	None	0	N/A	N/A
5490	1	1	M11	Men's Restroom inside Teacher Lounge 116	yes	Floor	ceramic	White	None	0	N/A	N/A
5490	1	1	M11	Men's Restroom inside Teacher Lounge 116	yes	Ceiling	N/A	White	N/A	N/A	N/A	N/A
5490	1	1	117	Classroom 117	yes	W1	Sheetrock	White	Chipping	1	0	Negative
5490	1	1	117	Classroom 117	yes	door frame	Metal	Tan	Chipping	3	0	Negative
5490	1	1	117	Classroom 117	yes	door frame	Metal	Red	Chipping	3	0	Negative
5490	1	1	117	Classroom 117	yes	W2	Sheetrock	Blue	Chipping	1	0	Negative
5490	1	1	117	Classroom 117	yes	W3	Plaster	White	Cracking	1	26.7	Positive
5490	1	1	117	Classroom 117	yes	W4	Sheetrock	White	Chipping	1	0	Negative
5490	1	1	117	Classroom 117	yes	Floor	Concrete	N/A	None	0	N/A	N/A
5490	1	1	117	Classroom 117	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
5490	1	1	117A	Classroom 117 Closet	yes	W1	Sheetrock	White	None	0	N/A	N/A
5490	1	1	117A	Classroom 117 Closet	yes	W2	Sheetrock	White	None	0	N/A	N/A
5490	1	1	117A	Classroom 117 Closet	yes	W3	Sheetrock	White	None	0	N/A	N/A
5490	1	1	117A	Classroom 117 Closet	yes	W4	Sheetrock	White	None	0	N/A	N/A
5490	1	1	117A	Classroom 117 Closet	yes	Floor	Concrete	N/A	None	0	N/A	N/A
5490	1	1	117A	Classroom 117 Closet	yes	Ceiling	Sheetrock	White	None	0	N/A	N/A
5490	1	1	125	Classroom 117 Restroom	yes	W1	Sheetrock	Tan	None	0	N/A	N/A
5490	1	1	125	Classroom 117 Restroom	yes	W2	Sheetrock	Tan	None	0	N/A	N/A
5490	1	1	125	Classroom 117 Restroom	yes	W3	Sheetrock	Tan	None	0	N/A	N/A
5490	1	1	125	Classroom 117 Restroom	yes	W4	Sheetrock	Tan	None	0	N/A	N/A
5490	1	1	125	Classroom 117 Restroom	yes	Floor	Concrete	N/A	None	0	N/A	N/A

				Inspection Dates: May 2020		School District of Philadelphia						
				James Mongan		Lead Safe Certification Assessment Report						
				Vertex		Cayuga Elementary School						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
5490	1	1	125	Classroom 117 Restroom	yes	Ceiling	Sheetrock	White	None	0	N/A	N/A
5490	1	1	118	Classroom 118	yes	W1	Sheetrock	White	None	0	N/A	N/A
5490	1	1	118	Classroom 118	yes	door frame	Metal	Tan	Chipping	1	0	Negative
5490	1	1	118	Classroom 118	yes	door frame	Metal	Red	Chipping	2	0	Negative
5490	1	1	118	Classroom 118	yes	W2	Sheetrock	White	None	0	N/A	N/A
5490	1	1	118	Classroom 118	yes	W3	Plaster	White	None	0	N/A	N/A
5490	1	1	118	Classroom 118	yes	W4	Sheetrock	White	None	0	N/A	N/A
5490	1	1	118	Classroom 118	yes	Floor	Concrete	N/A	None	0	N/A	N/A
5490	1	1	118	Classroom 118	yes	Ceiling	Sheetrock	White	None	0	N/A	N/A
5490	1	1	122	Classroom 118 Restroom	yes	W1	Sheetrock	Tan	None	0	N/A	N/A
5490	1	1	122	Classroom 118 Restroom	yes	W2	Sheetrock	Tan	None	0	N/A	N/A
5490	1	1	122	Classroom 118 Restroom	yes	W3	Sheetrock	Tan	None	0	N/A	N/A
5490	1	1	122	Classroom 118 Restroom	yes	W4	Sheetrock	Tan	None	0	N/A	N/A
5490	1	1	122	Classroom 118 Restroom	yes	Floor	Concrete	White	None	0	N/A	N/A
5490	1	1	122	Classroom 118 Restroom	yes	Ceiling	Sheetrock	White	None	0	N/A	N/A
5490	1	1	119	Classroom 119	yes	W1	Sheetrock	White	Chipping	4	0	Negative
5490	1	1	119	Classroom 119	yes	column	Concrete	White	Chipping	5	15.1	Positive
5490	1	1	119	Classroom 119	yes	door frame	Metal	Tan	Chipping	5	0	Negative
5490	1	1	119	Classroom 119	yes	W2	Sheetrock	White	None	0	N/A	N/A
5490	1	1	119	Classroom 119	yes	W3	Plaster	White	None	0	N/A	N/A
5490	1	1	119	Classroom 119	yes	W4	Sheetrock	White	Chipping	4	0	Negative
5490	1	1	119	Classroom 119	yes	Floor	Concrete	N/A	None	0	N/A	N/A
5490	1	1	119	Classroom 119	yes	Ceiling	Sheetrock	White	None	0	N/A	N/A
5490	1	1	126	Classroom 119 Restroom	yes	W1	Sheetrock	Tan	None	0	N/A	N/A
5490	1	1	126	Classroom 119 Restroom	yes	doorframe	Metal	Red	Chipping	1	0	Negative
5490	1	1	126	Classroom 119 Restroom	yes	W2	Sheetrock	Tan	None	0	N/A	N/A
5490	1	1	126	Classroom 119 Restroom	yes	W3	Sheetrock	Tan	None	0	N/A	N/A
5490	1	1	126	Classroom 119 Restroom	yes	W4	Sheetrock	Tan	None	0	N/A	N/A
5490	1	1	126	Classroom 119 Restroom	yes	Floor	Concrete	N/A	None	0	N/A	N/A
5490	1	1	126	Classroom 119 Restroom	yes	Ceiling	Sheetrock	White	None	0	N/A	N/A
5490	1	1	120	Classroom 120	yes	W1	Sheetrock	White	None	0	N/A	N/A
5490	1	1	120	Classroom 120	yes	door frame	Metal	Tan	Chipping	5	0	Negative
5490	1	1	120	Classroom 120	yes	door frame	Metal	Red	Chipping	7	0	Negative
5490	1	1	120	Classroom 120	yes	W2	Sheetrock	Blue	None	0	N/A	N/A
5490	1	1	120	Classroom 120	yes	W3	Plaster	Blue	Chipping	1	5.9	Positive
5490	1	1	120	Classroom 120	yes	W4	Sheetrock	White	None	0	N/A	N/A

				Inspection Dates: May 2020		School District of Philadelphia						
				James Mongan		Lead Safe Certification Assessment Report						
				Vertex		Cayuga Elementary School						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
5490	1	1	120	Classroom 120	yes	Floor	Concrete	N/A	None	0	N/A	N/A
5490	1	1	120	Classroom 120	yes	Ceiling	Sheetrock	White	None	0	N/A	N/A
5490	1	1	120A	Classroom 120 Restroom	yes	W1	Sheetrock	Tan	None	0	N/A	N/A
5490	1	1	120A	Classroom 120 Restroom	yes	door frame	Metal	Red	Chipping	2	0	Negative
5490	1	1	120A	Classroom 120 Restroom	yes	W2	Sheetrock	Tan	None	0	N/A	N/A
5490	1	1	120A	Classroom 120 Restroom	yes	W3	Sheetrock	Tan	None	0	N/A	N/A
5490	1	1	120A	Classroom 120 Restroom	yes	W4	Sheetrock	Tan	None	0	N/A	N/A
5490	1	1	120A	Classroom 120 Restroom	yes	Floor	Concrete	White	None	0	N/A	N/A
5490	1	1	120A	Classroom 120 Restroom	yes	Ceiling	Sheetrock	White	None	0	N/A	N/A
5490	1	1	121	Office 121	yes	W1	Plaster	Blue	Chipping	5	0.03	Negative
5490	1	1	121	Office 121	yes	W2	Plaster	Blue	None	0	N/A	N/A
5490	1	1	121	Office 121	yes	W3	Plaster	Blue	None	0	N/A	N/A
5490	1	1	121	Office 121	yes	W4	Plaster	White	None	0	N/A	N/A
5490	1	1	121	Office 121	yes	Floor	Concrete	N/A	None	0	N/A	N/A
5490	1	1	121	Office 121	yes	Ceiling	Plaster	White	None	0	N/A	N/A
5490	1	2	H12	Main Hallway	yes	W1	Sheetrock	White	None	0	N/A	N/A
5490	1	2	H12	Main Hallway	yes	W2	Sheetrock	White	holes	4	0	Negative
5490	1	2	H12	Main Hallway	yes	W2	Sheetrock	Blue	Cracking/peeling	9	0	Negative
5490	1	2	H12	Main Hallway	yes	W3	Sheetrock	White	Cracking	20	0	Negative
5490	1	2	H12	Main Hallway	yes	W4	Sheetrock	Blue	Chipping	1	0	Negative
5490	1	2	H12	Main Hallway	yes	Floor	Concrete	N/A	None	0	N/A	N/A
5490	1	2	H12	Main Hallway	yes	Ceiling	Sheetrock	White	None	0	N/A	N/A
5490	1	2	S23	Stairwell 3 across from Boy's Restroom	yes	W1	Sheetrock		None	0	N/A	N/A
5490	1	2	S23	Stairwell 3 across from Boy's Restroom	yes	W2			None	0	N/A	N/A
5490	1	2	S23	Stairwell 3 across from Boy's Restroom	yes	W3			None	0	N/A	N/A
5490	1	2	S23	Stairwell 3 across from Boy's Restroom	yes	W4			None	0	N/A	N/A
5490	1	2	S23	Stairwell 3 across from Boy's Restroom	yes	Floor			None	0	N/A	N/A
5490	1	2	S23	Stairwell 3 across from Boy's Restroom	yes	Ceiling			None	0	N/A	N/A
5490	1	2	V21	Vestibule between Stairwell 3 and Boy's Restroom	yes	W1	Sheetrock	White	Chipping	3	0	Negative

				Inspection Dates: May 2020		School District of Philadelphia						
				James Mongan		Lead Safe Certification Assessment Report						
				Vertex		Cayuga Elementary School						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
5490	1	2	V21	Vestibule between Stairwell 3 and Boy's Restroom	yes	W2			None	0	N/A	N/A
5490	1	2	V21	Vestibule between Stairwell 3 and Boy's Restroom	yes	W3			None	0	N/A	N/A
5490	1	2	V21	Vestibule between Stairwell 3 and Boy's Restroom	yes	Window Sill	Cement	Grey	Chipping	8	1.5	Positive
5490	1	2	V21	Vestibule between Stairwell 3 and Boy's Restroom	yes	W4			None	0	N/A	N/A
5490	1	2	V21	Vestibule between Stairwell 3 and Boy's Restroom	yes	Floor			None	0	N/A	N/A
5490	1	2	V21	Vestibule between Stairwell 3 and Boy's Restroom	yes	Ceiling	Concrete	Grey	Cracking	7	0	Negative
5490	1	2	S24	Stairwell 4 across from Office 220	yes	W1	Plaster	White	None	0	N/A	N/A
5490	1	2	S24	Stairwell 4 across from Office 220	yes	W2	Plaster	White	None	0	N/A	N/A
5490	1	2	S24	Stairwell 4 across from Office 220	yes	W3	Plaster	White	Cracking	2	0.03	Negative
5490	1	2	S24	Stairwell 4 across from Office 220	yes	Door Frame	Metal	Beige	Peeling	3	0	Negative
5490	1	2	S24	Stairwell 4 across from Office 220	yes	W4	Plaster	White	None	0	N/A	N/A
5490	1	2	S24	Stairwell 4 across from Office 220	yes	Floor	Concrete	N/A	None	0	N/A	N/A
5490	1	2	S24	Stairwell 4 across from Office 220	yes	Ceiling	Plaster	White	Chipping	2		
5490	1	2	S25	Stairwell between Element 1 and Element 2	yes	W1	Concrete	Blue	None	0	N/A	N/A
5490	1	2	S25	Stairwell between Element 1 and Element 2	yes	W2	Concrete	Blue	None	0	N/A	N/A
5490	1	2	S25	Stairwell between Element 1 and Element 2	yes	W3	Concrete	Blue	None	0	N/A	N/A
5490	1	2	S25	Stairwell between Element 1 and Element 2	yes	W4	Concrete	Blue	None	0	N/A	N/A
5490	1	2	S25	Stairwell between Element 1 and Element 2	yes	Door Frame	Metal	Beige	Chipping	3	0	Negative
5490	1	2	S25	Stairwell between Element 1 and Element 2	yes	Door Frame	Metal	Green	Chipping	3	0	Negative
5490	1	2	S25	Stairwell between Element 1 and Element 2	yes	Floor	Concrete	N/A	None	0	N/A	N/A
5490	1	2	S25	Stairwell between Element 1 and Element 2	yes	Ceiling	Sheetrock	White	Chipping	1	0	Negative
5490	1	2	EL1	Elevator between Element 1 and Element 2	yes	W1	Sheetrock	Blue	None	0	N/A	N/A

				Inspection Dates: May 2020		School District of Philadelphia						
				James Mongan		Lead Safe Certification Assessment Report						
				Vertex		Cayuga Elementary School						
ULCS#	Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
5490	1	2	EL1	Elevator between Element 1 and Element 2	yes	Door frame	Wood	Beige	Chipping	2	0	Negative
5490	1	2	EL1	Elevator between Element 1 and Element 2	yes	W2	Sheetrock	Blue	None	0	N/A	N/A
5490	1	2	EL1	Elevator between Element 1 and Element 2	yes	W3	Sheetrock	Blue	None	0	N/A	N/A
5490	1	2	EL1	Elevator between Element 1 and Element 2	yes	W4	Sheetrock	Blue	None	0	N/A	N/A
5490	1	2	EL1	Elevator between Element 1 and Element 2	yes	Floor	Concrete	N/A	None	0	N/A	N/A
5490	1	2	EL1	Elevator between Element 1 and Element 2	yes	Ceiling	Sheetrock	White	None	0	N/A	N/A
5490	1	2	B12	Boy's Restroom next to Elevator	yes	W1	Sheetrock	Tan	None	0	N/A	N/A
5490	1	2	B12	Boy's Restroom next to Elevator	yes	Door Frame	Metal	Beige	Chipping	3	0	Negative
5490	1	2	B12	Boy's Restroom next to Elevator	yes	W2	Sheetrock	Tan	None	0	N/A	N/A
5490	1	2	B12	Boy's Restroom next to Elevator	yes	Radiator cover	Metal	Light grey	Rusting	5	0.01	Negative
5490	1	2	B12	Boy's Restroom next to Elevator	yes	W3	Sheetrock	Tan	None	0	N/A	N/A
5490	1	2	B12	Boy's Restroom next to Elevator	yes	W4	Sheetrock	Tan	None	0	N/A	N/A
5490	1	2	B12	Boy's Restroom next to Elevator	yes	Floor	Concrete	White	None	0	N/A	N/A
5490	1	2	B12	Boy's Restroom next to Elevator	yes	Ceiling	Sheetrock	White	None	0	N/A	N/A
5490	1	2	213	Storage Room 213	no	W1	Sheetrock	White	None	0	N/A	N/A
5490	1	2	213	Storage Room 213	no	Door Frame	Metal	Beige	Chipping	4	0	Negative
5490	1	2	213	Storage Room 213	no	W2	Sheetrock	White	Chipping	1	0	Negative
5490	1	2	213	Storage Room 213	no	W3	Sheetrock	White	None	0	N/A	N/A
5490	1	2	213	Storage Room 213	no	W4	Sheetrock	White	None	0	N/A	N/A
5490	1	2	213	Storage Room 213	no	Floor	Concrete	N/A	None	0	N/A	N/A
5490	1	2	213	Storage Room 213	no	Ceiling	Sheetrock	White	None	0	N/A	N/A
5490	1	2	214	Classroom 214	yes	W1	Sheetrock	Tan	Chipping	4	0	Negative
5490	1	2	214	Classroom 214	yes	Column	Wood	Green	Chipping	4	24.7	Positive
5490	1	2	214	Classroom 214	yes	Door Frame	Metal	Beige	Chipping	6	0	Negative
5490	1	2	214	Classroom 214	yes	W2	Sheetrock	Blue	Chipping	1	0	Negative
5490	1	2	214	Classroom 214	yes	W3	Plaster	Beige	Efflorescence/Chipping	1	0	Negative
5490	1	2	214	Classroom 214	yes	Window Sill	Wood	White	Chipping	1	0	Negative
5490	1	2	214	Classroom 214	yes	W4	Sheetrock	Blue	Chipping	1	0	Negative
5490	1	2	214	Classroom 214	yes	Floor	Concrete	N/A	None	0	N/A	N/A
5490	1	2	214	Classroom 214	yes	Ceiling	Sheetrock	White	None	0	N/A	N/A

				Inspection Dates: May 2020		School District of Philadelphia						
				James Mongan		Lead Safe Certification Assessment Report						
				Vertex		Cayuga Elementary School						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
5490	1	2	216	Classroom 216	yes	W1	Sheetrock	White	Chipping/Cracking	6	0	Negative
5490	1	2	216	Classroom 216	yes	Door Frame	Metal	Beige	Chipping	10	0	Negative
5490	1	2	216	Classroom 216	yes	W2	Plaster	White	None	0	N/A	N/A
5490	1	2	216	Classroom 216	yes	W3	Plaster	White	Chipping	1	14.3	Positive
5490	1	2	216	Classroom 216	yes	W4	Sheetrock	Blue	Peeling	1	0	Negative
5490	1	2	216	Classroom 216	yes	Floor	Concrete	N/A	None	0	N/A	N/A
5490	1	2	216	Classroom 216	yes	Ceiling	Sheetrock	White	None	0	N/A	N/A
5490	1	2	215	IMC/Library 215	yes	W1	Sheetrock	White	Cracking, Holes	11	0	Negative
5490	1	2	215	IMC/Library 215	yes	Door Frame	Metal	Beige	Peeling	8	0	Negative
5490	1	2	215	IMC/Library 215	yes	Column	Wood	Green	Chipping	6	24.5	Positive
5490	1	2	215	IMC/Library 215	yes	Window Sill	Wood	Tan	Peeling	8	0.01	Negative
5490	1	2	215	IMC/Library 215	yes	W2	Sheetrock	White	Cracking	6	0	Negative
5490	1	2	215	IMC/Library 215	yes	W3	Plaster	White	Hole	1	11	Positive
5490	1	2	215	IMC/Library 215	yes	WindowSill	Wood	White	Chipping	1	0	Negative
5490	1	2	215	IMC/Library 215	yes	W4	Sheetrock	White	Chipping	3	0	Negative
5490	1	2	215	IMC/Library 215	yes	Floor	Concrete	N/A	None	0	N/A	N/A
5490	1	2	215	IMC/Library 215	yes	Ceiling	Sheetrock	White	None	0	N/A	N/A
5490	1	2	215A	IMC/Library Office	yes	W1	Sheetrock	White	None	0	N/A	N/A
5490	1	2	215A	IMC/Library Office	yes	W2	Sheetrock	White	Chipping	2	0	Negative
5490	1	2	215A	IMC/Library Office	yes	W3	Sheetrock	White	Chipping	2	0	Negative
5490	1	2	215A	IMC/Library Office	yes	W4	Sheetrock	White	Chipping	2	0	Negative
5490	1	2	215A	IMC/Library Office	yes	Floor	Concrete	N/A	None	0	N/A	N/A
5490	1	2	215A	IMC/Library Office	yes	Ceiling	Sheetrock	White	None	0	N/A	N/A
5490	1	2	218	Library IT MDF Room	yes	W1	Sheetrock	White	holes	2		
5490	1	2	218	Library IT MDF Room	yes	W2	Sheetrock	White	hole	1		
5490	1	2	218	Library IT MDF Room	yes	W3	Sheetrock	White	None	0	N/A	N/A
5490	1	2	218	Library IT MDF Room	yes	W4	Sheetrock	White	holes	3		
5490	1	2	218	Library IT MDF Room	yes	Floor	Concrete	N/A	None	0	N/A	N/A
5490	1	2	218	Library IT MDF Room	yes	Ceiling	Sheetrock	White	None	0	N/A	N/A
5490	1	2	217	Computer Lab 217	yes	W1	Sheetrock	Blue	Chipping	4	0	Negative
5490	1	2	217	Computer Lab 217	yes	Door Frame	Metal	Tan	Chipping	8	0	Negative
5490	1	2	217	Computer Lab 217	yes	Column	Wood	Blue	Chipping	4	26.9	Positive
5490	1	2	217	Computer Lab 217	yes	W2	Sheetrock	Blue	Chipping/Holes	4	0	Negative
5490	1	2	217	Computer Lab 217	yes	W3	Plaster	Blue	Cracking	1	2.7	Positive
5490	1	2	217	Computer Lab 217	yes	W4	Sheetrock	Blue	None	0	N/A	N/A

				Inspection Dates: May 2020		School District of Philadelphia						
				James Mongan		Lead Safe Certification Assessment Report						
				Vertex		Cayuga Elementary School						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
5490	1	2	217	Computer Lab 217	yes	Floor	Concrete	N/A	None	0	N/A	N/A
5490	1	2	217	Computer Lab 217	yes	Ceiling	Sheetrock	White	None	0	N/A	N/A
5490	1	2	219	Office 219 inside Computer Lab 217	yes	W1	Sheetrock	Tan	Peeling	2	0	Negative
5490	1	2	219	Office 219 inside Computer Lab 217	yes	Door Frame	Metal	Tan	Peeling	2	0	Negative
5490	1	2	219	Office 219 inside Computer Lab 217	yes	W2	Sheetrock	Tan	None	0	N/A	N/A
5490	1	2	219	Office 219 inside Computer Lab 217	yes	W3	Sheetrock	Tan	None	0	N/A	N/A
5490	1	2	219	Office 219 inside Computer Lab 217	yes	W4	Plaster	Tan	None	0	N/A	N/A
5490	1	2	219	Office 219 inside Computer Lab 217	yes	Floor	Concrete	N/A	None	0	N/A	N/A
5490	1	2	219	Office 219 inside Computer Lab 217	yes	Ceiling	Sheetrock	White	None	0	N/A	N/A
5490	1	2	221	Storage Room 221 inside Computer Lab 217	yes	W1	No Access	No Access	No Access	No Access	No Access	No Access
5490	1	2	221	Storage Room 221 inside Computer Lab 217	yes	W2	No Access	No Access	No Access	No Access	No Access	No Access
5490	1	2	221	Storage Room 221 inside Computer Lab 217	yes	W3	No Access	No Access	No Access	No Access	No Access	No Access
5490	1	2	221	Storage Room 221 inside Computer Lab 217	yes	W4	No Access	No Access	No Access	No Access	No Access	No Access
5490	1	2	221	Storage Room 221 inside Computer Lab 217	yes	Floor	No Access	No Access	None	No Access	No Access	No Access
5490	1	2	221	Storage Room 221 inside Computer Lab 217	yes	Ceiling	No Access	No Access	None	No Access	No Access	No Access
5490	1	2	220	Office 220	yes	W1	Plaster	White	None	0	N/A	N/A
5490	1	2	220	Office 220	yes	W2	Plaster	White	Chipping	3	0.02	Negative
5490	1	2	220	Office 220	yes	Baseboard	Wood	White	Chipping	10	6.8	Positive
5490	1	2	220	Office 220	yes	W3	Plaster	White	None	0	N/A	N/A
5490	1	2	220	Office 220	yes	W4	Plaster	Blue	None	0	N/A	N/A
5490	1	2	220	Office 220	yes	Baseboard	Wood	Blue	Chipping	4	6.9	Positive
5490	1	2	220	Office 220	yes	Floor	Concrete	N/A	None	0	N/A	N/A
5490	1	2	220	Office 220	yes	Ceiling	Sheetrock	White	None	0	N/A	N/A
5490	2	B	BR1	Boiler Room 005	no	W1	Concrete	Blue	None	0	N/A	N/A
5490	2	B	BR1	Boiler Room 005	no	W2	Concrete	Blue	None	0	N/A	N/A

				Inspection Dates: May 2020		School District of Philadelphia						
				James Mongan		Lead Safe Certification Assessment Report						
				Vertex		Cayuga Elementary School						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
5490	2	B	BR1	Boiler Room 005	no	W3	Concrete	Blue	None	0	N/A	N/A
5490	2	B	BR1	Boiler Room 005	no	W4	Concrete	Blue	Cracking	4	0	Negative
5490	2	B	BR1	Boiler Room 005	no	Floor	Concrete	N/A	None	0	N/A	N/A
5490	2	B	BR1	Boiler Room 005	no	Ceiling	Metal	N/A	None	0	N/A	N/A
5490	2	B	H02	Hallway from Stairwell 2 to Gymnasium	yes	W1	Concrete	White	None	0	N/A	N/A
5490	2	B	H02	Hallway from Stairwell 2 to Gymnasium	yes	W2	Concrete	White	None	0	N/A	N/A
5490	2	B	H02	Hallway from Stairwell 2 to Gymnasium	yes	W3	Concrete	White	None	0	N/A	N/A
5490	2	B	H02	Hallway from Stairwell 2 to Gymnasium	yes	W4	Concrete	White	None	0	N/A	N/A
5490	2	B	H02	Hallway from Stairwell 2 to Gymnasium	yes	Floor	Concrete	N/A	None	0	N/A	N/A
5490	2	B	H02	Hallway from Stairwell 2 to Gymnasium	yes	Ceiling	Concrete	White	None	0	N/A	N/A
5490	2	B	S02	Stairwell 2	yes	W1	Concrete	Green	None	0	N/A	N/A
5490	2	B	S02	Stairwell 2	yes	W2	Concrete	Green	None	0	N/A	N/A
5490	2	B	S02	Stairwell 2	yes	W3	Concrete	Green	None	0	N/A	N/A
5490	2	B	S02	Stairwell 2	yes	W4	Concrete	Green	None	0	N/A	N/A
5490	2	B	S02	Stairwell 2	yes	Floor	Concrete	N/A	None	0	N/A	N/A
5490	2	B	S02	Stairwell 2	yes	Ceiling	Concrete	White	None	0	N/A	N/A
5490	2	B	6	Gym Office 006	yes	W1	Concrete	Tan	None	0	N/A	N/A
5490	2	B	6	Gym Office 006	yes	door frame	metal	blue	chipping	3	0.22	Negative
5490	2	B	6	Gym Office 006	yes	W2	Concrete	Tan	None	0	N/A	N/A
5490	2	B	6	Gym Office 006	yes	W3	Concrete	Tan	None	0	N/A	N/A
5490	2	B	6	Gym Office 006	yes	W4	Concrete	Tan	None	0	N/A	N/A
5490	2	B	6	Gym Office 006	yes	Floor	Concrete	N/A	None	0	N/A	N/A
5490	2	B	6	Gym Office 006	yes	Ceiling	Plaster	White	None	0	N/A	N/A
5490	2	B	7	Storage Room 007 next to Gym Office 006	yes	W1	Brick	Tan	None	0	N/A	N/A
5490	2	B	7	Storage Room 007 next to Gym Office 006	yes	W2	Concrete	Tan	None	0	N/A	N/A
5490	2	B	7	Storage Room 007 next to Gym Office 006	yes	W3	Concrete	Tan	None	0	N/A	N/A
5490	2	B	7	Storage Room 007 next to Gym Office 006	yes	W4	Brick	Tan	None	0	N/A	N/A

				Inspection Dates: May 2020		School District of Philadelphia						
				James Mongan		Lead Safe Certification Assessment Report						
				Vertex		Cayuga Elementary School						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
5490	2	B	7	Storage Room 007 next to Gym Office 006	yes	Floor	Concrete	N/A	None	0	N/A	N/A
5490	2	B	7	Storage Room 007 next to Gym Office 006	yes	Ceiling	Plaster	White	hole	1	0	Negative
5490	2	B	GYM	Gymnasium	yes	W1	Concrete	White	None	0	N/A	N/A
5490	2	B	GYM	Gymnasium	yes	W2	Concrete	White	None	0	N/A	N/A
5490	2	B	GYM	Gymnasium	yes	W3	Sheetrock	White	None	0	N/A	N/A
5490	2	B	GYM	Gymnasium	yes	W4	Concrete	White	None	0	N/A	N/A
5490	2	B	GYM	Gymnasium	yes	Floor	Concrete	N/A	None	0	N/A	N/A
5490	2	B	GYM	Gymnasium	yes	Ceiling	Concrete	White	None	0	N/A	N/A
5490	2	B	AUD	Auditorium	yes	W1	Sheetrock	Blue	None	0	N/A	N/A
5490	2	B	AUD	Auditorium	yes	W2	Concrete	White	None	0	N/A	N/A
5490	2	B	AUD	Auditorium	yes	W3	Concrete	White	None	0	N/A	N/A
5490	2	B	AUD	Auditorium	yes	W4	Concrete	White	None	0	N/A	N/A
5490	2	B	AUD	Auditorium	yes	Floor	Concrete	N/A	None	0	N/A	N/A
5490	2	B	AUD	Auditorium	yes	Ceiling	Concrete	White	None	0	N/A	N/A
5490	2	B	ST1	Auditorium Stage	yes	W1	Concrete	White	None	0	N/A	N/A
5490	2	B	ST1	Auditorium Stage	yes	W2	Concrete	White	None	0	N/A	N/A
5490	2	B	ST1	Auditorium Stage	yes	W3	Concrete	White	None	0	N/A	N/A
5490	2	B	ST1	Auditorium Stage	yes	W4	Concrete	White	None	0	N/A	N/A
5490	2	B	ST1	Auditorium Stage	yes	Floor	Concrete	N/A	None	0	N/A	N/A
5490	2	B	ST1	Auditorium Stage	yes	Ceiling	Concrete	White	None	0	N/A	N/A
5490	2	B	004A	Storage Room 004A inside Auditorium	yes	W1	Concrete	White	None	0	N/A	N/A
5490	2	B	004A	Storage Room 004A inside Auditorium	yes	W2	Concrete	White	None	0	N/A	N/A
5490	2	B	004A	Storage Room 004A inside Auditorium	yes	W3	Concrete	White	None	0	N/A	N/A
5490	2	B	004A	Storage Room 004A inside Auditorium	yes	W4	Concrete	White	None	0	N/A	N/A
5490	2	B	004A	Storage Room 004A inside Auditorium	yes	Floor	Concrete	N/A	None	0	N/A	N/A
5490	2	B	004A	Storage Room 004A inside Auditorium	yes	Ceiling	N/A	N/A	None	0	N/A	N/A
5490	2	B	004B	Storage Room 004B inside Auditorium	yes	W1	Concrete	White	None	0	N/A	N/A

				Inspection Dates: May 2020		School District of Philadelphia						
				James Mongan		Lead Safe Certification Assessment Report						
				Vertex		Cayuga Elementary School						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
5490	2	B	004B	Storage Room 004B inside Auditorium	yes	W2	Concrete	White	None	0	N/A	N/A
5490	2	B	004B	Storage Room 004B inside Auditorium	yes	W3	Concrete	White	None	0	N/A	N/A
5490	2	B	004B	Storage Room 004B inside Auditorium	yes	W4	Concrete	White	None	0	N/A	N/A
5490	2	B	004B	Storage Room 004B inside Auditorium	yes	Floor	Concrete	N/A	None	0	N/A	N/A
5490	2	B	004B	Storage Room 004B inside Auditorium	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5490	2	B	004C	Storage Room 004C inside Auditorium	yes	W1	Concrete	White	None	0	N/A	N/A
5490	2	B	004C	Storage Room 004C inside Auditorium	yes	W2	Concrete	White	None	0	N/A	N/A
5490	2	B	004C	Storage Room 004C inside Auditorium	yes	W3	Concrete	White	None	0	N/A	N/A
5490	2	B	004C	Storage Room 004C inside Auditorium	yes	W4	Concrete	White	None	0	N/A	N/A
5490	2	B	004C	Storage Room 004C inside Auditorium	yes	Floor	Concrete	N/A	None	0	N/A	N/A
5490	2	B	004C	Storage Room 004C inside Auditorium	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5490	2	B	004D	Storage Room 004D behind the Auditorium Stage	yes	W1	Concrete	White	None	0	N/A	N/A
5490	2	B	004D	Storage Room 004D behind the Auditorium Stage	yes	W2	Concrete	White	None	0	N/A	N/A
5490	2	B	004D	Storage Room 004D behind the Auditorium Stage	yes	W3	Concrete	White	None	0	N/A	N/A
5490	2	B	004D	Storage Room 004D behind the Auditorium Stage	yes	W4	Concrete	White	None	0	N/A	N/A
5490	2	B	004D	Storage Room 004D behind the Auditorium Stage	yes	Floor	Concrete	N/A	None	0	N/A	N/A
5490	2	B	004D	Storage Room 004D behind the Auditorium Stage	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5490	2	M	HM2	Mezzanine Level Hallway	yes	W1	Concrete	White	None	0	N/A	N/A
5490	2	M	HM2	Mezzanine Level Hallway	yes	W2	Concrete	White	None	0	N/A	N/A
5490	2	M	HM2	Mezzanine Level Hallway	yes	W3	Concrete	White	holes	2	0	Negative
5490	2	M	HM2	Mezzanine Level Hallway	yes	W4	Concrete	White	None	0	N/A	N/A
5490	2	M	HM2	Mezzanine Level Hallway	yes	Floor	Concrete	N/A	None	0	N/A	N/A

				Inspection Dates: May 2020		School District of Philadelphia						
				James Mongan		Lead Safe Certification Assessment Report						
				Vertex		Cayuga Elementary School						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
5490	2	M	HM2	Mezzanine Level Hallway	yes	Ceiling	Concrete	White	None	0	N/A	N/A
5490	2	M	VM2	Front Entrance/Visitor's Entrance Vestibule	yes	W1	Concrete	White	None	0	N/A	N/A
5490	2	M	VM2	Front Entrance/Visitor's Entrance Vestibule	yes	W2	Concrete	White	None	0	N/A	N/A
5490	2	M	VM2	Front Entrance/Visitor's Entrance Vestibule	yes	W3	Concrete	White	None	0	N/A	N/A
5490	2	M	VM2	Front Entrance/Visitor's Entrance Vestibule	yes	W4	Concrete	White	None	0	N/A	N/A
5490	2	M	VM2	Front Entrance/Visitor's Entrance Vestibule	yes	Floor	Concrete	White	None	0	N/A	N/A
5490	2	M	VM2	Front Entrance/Visitor's Entrance Vestibule	yes	Ceiling	Sheetrock	White	None	0	N/A	N/A
5490	2	B	SM2	Stairwell 2	yes	W1	Concrete	Green	None	0	N/A	N/A
5490	2	B	SM2	Stairwell 2	yes	W2	Concrete	Green	None	0	N/A	N/A
5490	2	B	SM2	Stairwell 2	yes	W3	Concrete	Green	None	0	N/A	N/A
5490	2	B	SM2	Stairwell 2	yes	W4	Concrete	Green	None	0	N/A	N/A
5490	2	B	SM2	Stairwell 2	yes	Floor	Concrete	N/A	None	0	N/A	N/A
5490	2	B	SM2	Stairwell 2	yes	Ceiling	Concrete	White	None	0	N/A	N/A
5490	2	B	M02	Building Engineer's Office	no	W1	Concrete	White	None	0	N/A	N/A
5490	2	B	M02	Building Engineer's Office	no	W2	Concrete	White	None	0	N/A	N/A
5490	2	B	M02	Building Engineer's Office	no	W3	Concrete	White	Chipping	2	0	Negative
5490	2	B	M02	Building Engineer's Office	no	W4	Concrete	White	None	0	N/A	N/A
5490	2	B	M02	Building Engineer's Office	no	Floor	Concrete	N/A	None	0	N/A	N/A
5490	2	B	M02	Building Engineer's Office	no	Ceiling	Concrete	White	None	0	N/A	N/A
5490	2	1	S11	Stairwell 1	yes	W1	Concrete	Blue	None	0	N/A	N/A
5490	2	1	S11	Stairwell 1	yes	W2	Concrete	Blue	Flaking	1	0	Negative
5490	2	1	S11	Stairwell 1	yes	W3	Concrete	White	None	0	N/A	N/A
5490	2	1	S11	Stairwell 1	yes	W4	Concrete	Blue	None	0	N/A	N/A
5490	2	1	S11	Stairwell 1	yes	Floor	Concrete	N/A	None	0	N/A	N/A
5490	2	1	S11	Stairwell 1	yes	Ceiling	Concrete	White	None	0	N/A	N/A
5490	2	1	S12	Stairwell 2	yes	W1	Concrete	Green	None	0	N/A	N/A
5490	2	1	S12	Stairwell 2	yes	W2	Concrete	Green	None	0	N/A	N/A
5490	2	1	S12	Stairwell 2	yes	W3	Concrete	Green	None	0	N/A	N/A
5490	2	1	S12	Stairwell 2	yes	W4	Concrete	Green	None	0	N/A	N/A
5490	2	1	S12	Stairwell 2	yes	Floor	Concrete	N/A	None	0	N/A	N/A
5490	2	1	S12	Stairwell 2	yes	Ceiling	Sheetrock	White	None	0	N/A	N/A

				Inspection Dates: May 2020		School District of Philadelphia						
				James Mongan		Lead Safe Certification Assessment Report						
				Vertex		Cayuga Elementary School						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
5490	2	1	H12	Hallway from Stairwell 1 to Stairwell 2	yes	W1	Concrete	White	None	0	N/A	N/A
5490	2	1	H12	Hallway from Stairwell 1 to Stairwell 2	yes	W2	Concrete	White	None	0	N/A	N/A
5490	2	1	H12	Hallway from Stairwell 1 to Stairwell 2	yes	W3	Concrete	White	Chipping	1	0.05	Negative
5490	2	1	H12	Hallway from Stairwell 1 to Stairwell 2	yes	W4	Concrete	White	None	0	N/A	N/A
5490	2	1	H12	Hallway from Stairwell 1 to Stairwell 2	yes	Floor	Concrete	N/A	None	0	N/A	N/A
5490	2	1	H12	Hallway from Stairwell 1 to Stairwell 2	yes	Ceiling	Concrete	White	None	0	N/A	N/A
5490	2	1	B12	Boy's Restroom next to Classroom 102	yes	W1	Concrete	Tan	None	0	N/A	N/A
5490	2	1	B12	Boy's Restroom next to Classroom 102	yes	W2	Concrete	Tan	None	0	N/A	N/A
5490	2	1	B12	Boy's Restroom next to Classroom 102	yes	W3	Concrete	Tan	None	0	N/A	N/A
5490	2	1	B12	Boy's Restroom next to Classroom 102	yes	W4	Concrete	Tan	None	0	N/A	N/A
5490	2	1	B12	Boy's Restroom next to Classroom 102	yes	Floor	Concrete	White	None	0	N/A	N/A
5490	2	1	B12	Boy's Restroom next to Classroom 102	yes	Ceiling	Sheetrock	White	None	0	N/A	N/A
5490	2	1	101	Classroom 101	yes	W1	Concrete	Tan	None	0	N/A	N/A
5490	2	1	101	Classroom 101	yes	door frame	Metal	Blue	Chipping	0	0	Negative
5490	2	1	101	Classroom 101	yes	W2	Concrete	Tan	None	0	N/A	N/A
5490	2	1	101	Classroom 101	yes	W3	Concrete	Tan	None	0	N/A	N/A
5490	2	1	101	Classroom 101	yes	W4	Concrete	Blue	None	0	N/A	N/A
5490	2	1	101	Classroom 101	yes	Floor	Concrete	N/A	None	0	N/A	N/A
5490	2	1	101	Classroom 101	yes	Ceiling	Concrete	White	None	0	N/A	N/A
5490	2	1	102	Classroom 102	yes	W1	Concrete	Tan	Chipping	7	0	Negative
5490	2	1	102	Classroom 102	yes	door frame	Metal	Blue	Chipping	4	0	Negative
5490	2	1	102	Classroom 102	yes	W2	Concrete	Tan	Chipping	3	0	Negative
5490	2	1	102	Classroom 102	yes	W3	Concrete	Tan	None	0	N/A	N/A
5490	2	1	102	Classroom 102	yes	W4	Concrete	Blue	None	0	N/A	N/A
5490	2	1	102	Classroom 102	yes	Floor	Concrete	N/A	None	0	N/A	N/A
5490	2	1	102	Classroom 102	yes	Ceiling	Concrete	White	None	0	N/A	N/A

				Inspection Dates: May 2020		School District of Philadelphia						
				James Mongan		Lead Safe Certification Assessment Report						
				Vertex		Cayuga Elementary School						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
5490	2	1	103	Classroom 103	yes	W1	Concrete	Tan	None	0	N/A	N/A
5490	2	1	103	Classroom 103	yes	door frame	Metal	Blue	Chipping	4	0	Negative
5490	2	1	103	Classroom 103	yes	W2	Concrete	Tan	None	0	N/A	N/A
5490	2	1	103	Classroom 103	yes	W3	Concrete	Tan	None	0	N/A	N/A
5490	2	1	103	Classroom 103	yes	W4	Concrete	Blue	None	0	N/A	N/A
5490	2	1	103	Classroom 103	yes	Floor	Concrete	N/A	None	0	N/A	N/A
5490	2	1	103	Classroom 103	yes	Ceiling	Concrete	White	None	0	N/A	N/A
5490	2	1	104	Classroom 104	yes	W1	Concrete	Tan	Chipping	4	0	Negative
5490	2	1	104	Classroom 104	yes	door frame	Metal	Blue	Chipping	5	0	Negative
5490	2	1	104	Classroom 104	yes	W2	Concrete	Tan	None	0	N/A	N/A
5490	2	1	104	Classroom 104	yes	W3	Concrete	Tan	None	0	N/A	N/A
5490	2	1	104	Classroom 104	yes	W4	Concrete	Blue	None	0	N/A	N/A
5490	2	1	104	Classroom 104	yes	Floor	Concrete	N/A	None	0	N/A	N/A
5490	2	1	104	Classroom 104	yes	Ceiling	Concrete	White	None	0	N/A	N/A
5490	2	1	105	Classroom 105	yes	W1	Concrete	Tan	Chipping	2	0	Negative
5490	2	1	105	Classroom 105	yes	door frame	Metal	Blue	Chipping	4	0.01	Negative
5490	2	1	105	Classroom 105	yes	W2	Concrete	Tan	None	0	N/A	N/A
5490	2	1	105	Classroom 105	yes	W3	Concrete	Tan	None	0	N/A	N/A
5490	2	1	105	Classroom 105	yes	W4	Concrete	Tan	None	0	N/A	N/A
5490	2	1	105	Classroom 105	yes	Floor	Concrete	N/A	None	0	N/A	N/A
5490	2	1	105	Classroom 105	yes	Ceiling	Concrete	White	None	0	N/A	N/A
5490	2	1	106	Main Office 106	yes	W1	Sheetrock	White	Chipping	1	0	Negative
5490	2	1	106	Main Office 106	yes	door frame	Metal	Blue	Chipping	5	0	Negative
5490	2	1	106	Main Office 106	yes	W2	Concrete	White	None	0	N/A	N/A
5490	2	1	106	Main Office 106	yes	W3	Concrete	White	None	0	N/A	N/A
5490	2	1	106	Main Office 106	yes	W4	Sheetrock	Green	None	0	N/A	N/A
5490	2	1	106	Main Office 106	yes	Floor	Concrete	N/A	None	0	N/A	N/A
5490	2	1	106	Main Office 106	yes	Ceiling	Concrete	White	None	0	N/A	N/A
5490	2	1	106A	Office 106A inside Main Office 106	yes	W1	Sheetrock	White	None	0	N/A	N/A
5490	2	1	106A	Office 106A inside Main Office 106	yes	W2	Sheetrock	White	None	0	N/A	N/A
5490	2	1	106A	Office 106A inside Main Office 106	yes	W3	Sheetrock	White	None	0	N/A	N/A
5490	2	1	106A	Office 106A inside Main Office 106	yes	W4	Sheetrock	White	None	0	N/A	N/A

				Inspection Dates: May 2020		School District of Philadelphia						
				James Mongan		Lead Safe Certification Assessment Report						
				Vertex		Cayuga Elementary School						
ULCS#	Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
5490	2	1	106A	Office 106A inside Main Office 106	yes	Floor	Concrete	N/A	None	0	N/A	N/A
5490	2	1	106A	Office 106A inside Main Office 106	yes	Ceiling	Concrete	White	None	0	N/A	N/A
5490	2	1	107	Principal's Office 107	yes	W1	Sheetrock	White	None	0	N/A	N/A
5490	2	1	107	Principal's Office 107	yes	door frame	Metal	Blue	Chipping	5	0	Negative
5490	2	1	107	Principal's Office 107	yes	W2	Sheetrock	White	None	0	N/A	N/A
5490	2	1	107	Principal's Office 107	yes	W3	Sheetrock	White	None	0	N/A	N/A
5490	2	1	107	Principal's Office 107	yes	W4	Sheetrock	White	None	0	N/A	N/A
5490	2	1	107	Principal's Office 107	yes	Floor	Concrete	N/A	None	0	N/A	N/A
5490	2	1	107	Principal's Office 107	yes	Ceiling	Concrete	White	None	0	N/A	N/A
5490	2	1	107A	Restroom inside Principal's Office 107	yes	W1	Concrete	White	None	0	N/A	N/A
5490	2	1	107A	Restroom inside Principal's Office 107	yes	W2	Concrete	White	None	0	N/A	N/A
5490	2	1	107A	Restroom inside Principal's Office 107	yes	W3	Concrete	White	None	0	N/A	N/A
5490	2	1	107A	Restroom inside Principal's Office 107	yes	W4	Concrete	White	None	0	N/A	N/A
5490	2	1	107A	Restroom inside Principal's Office 107	yes	Floor	Concrete	N/A	None	0	N/A	N/A
5490	2	1	107A	Restroom inside Principal's Office 107	yes	Ceiling	Concrete	White	None	0	N/A	N/A
5490	2	1	110	Counselor's Office 110	yes	W1	Concrete	Tan	None	0	N/A	N/A
5490	2	1	110	Counselor's Office 110	yes	door frame	Metal	Blue	Chipping	5	0	Negative
5490	2	1	110	Counselor's Office 110	yes	W2	Concrete	Tan	Cracking	8	0	Negative
5490	2	1	110	Counselor's Office 110	yes	W3	Concrete	Tan	None	0	N/A	N/A
5490	2	1	110	Counselor's Office 110	yes	W4	Concrete	Tan	Cracking	8	0	Negative
5490	2	1	110	Counselor's Office 110	yes	Floor	Concrete	N/A	None	0	N/A	N/A
5490	2	1	110	Counselor's Office 110	yes	Ceiling	Concrete	White	None	0	N/A	N/A
5490	2	1	109	Electrical Room 109 inside Counselor's Office 110	no	W1	Concrete	N/A	None	0	N/A	N/A
5490	2	1	109	Electrical Room 109 inside Counselor's Office 110	no	W2	Concrete	Tan	None	0	N/A	N/A
5490	2	1	109	Electrical Room 109 inside Counselor's Office 110	no	W3	Concrete	N/A	None	0	N/A	N/A
5490	2	1	109	Electrical Room 109 inside Counselor's Office 110	no	W4	Concrete	N/A	None	0	N/A	N/A

				Inspection Dates: May 2020		School District of Philadelphia						
				James Mongan		Lead Safe Certification Assessment Report						
				Vertex		Cayuga Elementary School						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
5490	2	1	109	Electrical Room 109 inside Counselor's Office 110	no	Floor	Concrete	N/A	None	0	N/A	N/A
5490	2	1	109	Electrical Room 109 inside Counselor's Office 110	no	Ceiling	Concrete	White	None	0	N/A	N/A
5490	2	1	111	Custodial Closet 111 outside Counselor's Office 110	no	W1	Concrete	White	None	0	N/A	N/A
5490	2	1	111	Custodial Closet 111 outside Counselor's Office 110	no	W2	Concrete	White	None	0	N/A	N/A
5490	2	1	111	Custodial Closet 111 outside Counselor's Office 110	no	W3	Concrete	White	None	0	N/A	N/A
5490	2	1	111	Custodial Closet 111 outside Counselor's Office 110	no	W4	Concrete	White	None	0	N/A	N/A
5490	2	1	111	Custodial Closet 111 outside Counselor's Office 110	no	Floor	Concrete	N/A	None	0	N/A	N/A
5490	2	1	111	Custodial Closet 111 outside Counselor's Office 110	no	Ceiling	Concrete	White	None	0	N/A	N/A
5490	2	1	111A	Pipe Chase in Custodial Closet 111 outside Counselor's Office 110	no	W1	No Access	No Access	No Access	No Access	No Access	No Access
5490	2	1	111A	Pipe Chase in Custodial Closet 111 outside Counselor's Office 110	no	W2	No Access	No Access	No Access	No Access	No Access	No Access
5490	2	1	111A	Pipe Chase in Custodial Closet 111 outside Counselor's Office 110	no	W3	No Access	No Access	No Access	No Access	No Access	No Access
5490	2	1	111A	Pipe Chase in Custodial Closet 111 outside Counselor's Office 110	no	W4	No Access	No Access	No Access	No Access	No Access	No Access
5490	2	1	111A	Pipe Chase in Custodial Closet 111 outside Counselor's Office 110	no	Floor	No Access	No Access	No Access	No Access	No Access	No Access
5490	2	1	111A	Pipe Chase in Custodial Closet 111 outside Counselor's Office 110	no	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
5490	2	1	G12	Girl's Restroom next to Classroom 102	yes	W1	Concrete	Tan	None	0	N/A	N/A
5490	2	1	G12	Girl's Restroom next to Classroom 102	yes	W2	Concrete	Tan	None	0	N/A	N/A

				Inspection Dates: May 2020		School District of Philadelphia						
				James Mongan		Lead Safe Certification Assessment Report						
				Vertex		Cayuga Elementary School						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
5490	2	1	G12	Girl's Restroom next to Classroom 102	yes	W3	Concrete	Tan	None	0	N/A	N/A
5490	2	1	G12	Girl's Restroom next to Classroom 102	yes	W4	Concrete	Tan	None	0	N/A	N/A
5490	2	1	G12	Girl's Restroom next to Classroom 102	yes	Floor	Concrete	White	None	0	N/A	N/A
5490	2	1	G12	Girl's Restroom next to Classroom 102	yes	Ceiling	Sheetrock	White	None	0	N/A	N/A
5490	2	2	S21	Stairwell 1	yes	W1	Concrete	blue/white	None	0	N/A	N/A
5490	2	2	S21	Stairwell 1	yes	W2	Concrete	blue/white	None	0	N/A	N/A
5490	2	2	S21	Stairwell 1	yes	W3	Concrete	blue/white	Cracking	6	0	Negative
5490	2	2	S21	Stairwell 1	yes	W4	Concrete	blue/white	None	0	N/A	N/A
5490	2	2	S21	Stairwell 1	yes	Floor	Concrete	N/A	None	0	N/A	N/A
5490	2	2	S21	Stairwell 1	yes	Ceiling	Concrete	White	None	0	N/A	N/A
5490	2	2	S22	Stairwell 2	yes	W1	Concrete	green/white	None	0	N/A	N/A
5490	2	2	S22	Stairwell 2	yes	W2	Concrete	green/white	None	0	N/A	N/A
5490	2	2	S22	Stairwell 2	yes	W3	Concrete	green/white	None	0	N/A	N/A
5490	2	2	S22	Stairwell 2	yes	W4	Concrete	green/white	None	0	N/A	N/A
5490	2	2	S22	Stairwell 2	yes	Floor	Concrete	N/A	None	0	N/A	N/A
5490	2	2	S22	Stairwell 2	yes	Ceiling	Concrete	White	None	0	N/A	N/A
5490	2	2	H22	Hallway from Stairwell 1 to Stairwell 2	yes	W1	Concrete	Yellow	Cracking	3	0	Negative
5490	2	2	H22	Hallway from Stairwell 1 to Stairwell 2	yes	W2	Concrete	multiple	None	0	N/A	N/A
5490	2	2	H22	Hallway from Stairwell 1 to Stairwell 2	yes	W3	Concrete	multiple	None	0	N/A	N/A
5490	2	2	H22	Hallway from Stairwell 1 to Stairwell 2	yes	W4	Concrete	multiple	None	0	N/A	N/A
5490	2	2	H22	Hallway from Stairwell 1 to Stairwell 2	yes	Floor	Concrete	N/A	None	0	N/A	N/A
5490	2	2	H22	Hallway from Stairwell 1 to Stairwell 2	yes	Ceiling	Concrete	White	None	0	N/A	N/A
5490	2	2	200	Meeting Room 200	yes	W1	Sheetrock	Blue	Flaking	5	0	Negative
5490	2	2	200	Meeting Room 200	yes	door frame	Metal	Blue	Chipping	5	0	Negative

				Inspection Dates: May 2020		School District of Philadelphia						
				James Mongan		Lead Safe Certification Assessment Report						
				Vertex		Cayuga Elementary School						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
5490	2	2	200	Meeting Room 200	yes	W2	Sheetrock	Blue	Chipping	2	0	Negative
5490	2	2	200	Meeting Room 200	yes	W3	Sheetrock	Blue	None	0	N/A	N/A
5490	2	2	200	Meeting Room 200	yes	W4	Sheetrock	White	holes	4	0	Negative
5490	2	2	200	Meeting Room 200	yes	Floor	Concrete	N/A	None	0	N/A	N/A
5490	2	2	200	Meeting Room 200	yes	Ceiling	Concrete	White	None	0	N/A	N/A
5490	2	2	201	Classroom 201	yes	W1	Concrete	Tan	None	0	N/A	N/A
5490	2	2	201	Classroom 201	yes	door frame	Metal	Blue	Chipping	4	0.02	Negative
5490	2	2	201	Classroom 201	yes	W2	Concrete	Tan	None	0	N/A	N/A
5490	2	2	201	Classroom 201	yes	W3	Concrete	Tan	None	0	N/A	N/A
5490	2	2	201	Classroom 201	yes	W4	Concrete	Green	None	0	N/A	N/A
5490	2	2	201	Classroom 201	yes	Floor	Concrete	N/A	None	0	N/A	N/A
5490	2	2	201	Classroom 201	yes	Ceiling	Concrete	White	None	0	N/A	N/A
5490	2	2	202	Classroom 202	yes	W1	Concrete	Tan	Chipping	6	0	Negative
5490	2	2	202	Classroom 202	yes	door frame	Metal	Blue	Chipping	10	0.01	Negative
5490	2	2	202	Classroom 202	yes	W2	Concrete	Tan	Chipping	1	0	Negative
5490	2	2	202	Classroom 202	yes	W3	Concrete	Tan	None	0	N/A	N/A
5490	2	2	202	Classroom 202	yes	W4	Concrete	Green	None	0	N/A	N/A
5490	2	2	202	Classroom 202	yes	Floor	Concrete	N/A	None	0	N/A	N/A
5490	2	2	202	Classroom 202	yes	Ceiling	Concrete	White	None	0	N/A	N/A
5490	2	2	203	Classroom 203	yes	W1	Concrete	Tan	Cracking	8	0	Negative
5490	2	2	203	Classroom 203	yes	door frame	Metal	Blue	Chipping	8	0	Negative
5490	2	2	203	Classroom 203	yes	W2	Concrete	Tan	None	0	N/A	N/A
5490	2	2	203	Classroom 203	yes	W3	Concrete	Tan	None	0	N/A	N/A
5490	2	2	203	Classroom 203	yes	W4	Concrete	Green	None	0	N/A	N/A
5490	2	2	203	Classroom 203	yes	Floor	Concrete	N/A	None	0	N/A	N/A
5490	2	2	203	Classroom 203	yes	Ceiling	Concrete	White	None	0	N/A	N/A
5490	2	2	204	Classroom 204	yes	W1	Concrete	Yellow	None	0	N/A	N/A
5490	2	2	204	Classroom 204	yes	door frame	Metal	Blue	Chipping	8	0	Negative
5490	2	2	204	Classroom 204	yes	W2	Concrete	Yellow	None	0	N/A	N/A
5490	2	2	204	Classroom 204	yes	W3	Concrete	Green	None	0	N/A	N/A
5490	2	2	204	Classroom 204	yes	W4	Concrete	Green	None	0	N/A	N/A
5490	2	2	204	Classroom 204	yes	Floor	Concrete	N/A	None	0	N/A	N/A
5490	2	2	204	Classroom 204	yes	Ceiling	Concrete	White	None	0	N/A	N/A
5490	2	2	205	Classroom 205	yes	W1	Concrete	Tan	None	0	N/A	N/A
5490	2	2	205	Classroom 205	yes	door frame	Metal	Blue	Chipping	10	0.01	Negative

				Inspection Dates: May 2020		School District of Philadelphia						
				James Mongan		Lead Safe Certification Assessment Report						
				Vertex		Cayuga Elementary School						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
5490	2	2	205	Classroom 205	yes	W2	Concrete	Tan	None	0	N/A	N/A
5490	2	2	205	Classroom 205	yes	W3	Concrete	Tan	None	0	N/A	N/A
5490	2	2	205	Classroom 205	yes	W4	Concrete	Green	Cracking	8	0	Negative
5490	2	2	205	Classroom 205	yes	Floor	Concrete	N/A	None	0	N/A	N/A
5490	2	2	205	Classroom 205	yes	Ceiling	Concrete	White	None	0	N/A	N/A
5490	2	2	206	Classroom 206	yes	W1	Concrete	Tan	None	0	N/A	N/A
5490	2	2	206	Classroom 206	yes	door frame	Metal	Blue	Chipping	10	0.02	Negative
5490	2	2	206	Classroom 206	yes	W2	Concrete	Tan	None	0	N/A	N/A
5490	2	2	206	Classroom 206	yes	W3	Concrete	Tan	None	0	N/A	N/A
5490	2	2	206	Classroom 206	yes	W4	Concrete	Green	None	0	N/A	N/A
5490	2	2	206	Classroom 206	yes	Floor	Concrete	N/A	None	0	N/A	N/A
5490	2	2	206	Classroom 206	yes	Ceiling	Concrete	White	None	0	N/A	N/A
5490	2	2	207	Nurse's Office 207	yes	W1	Concrete	blue/white	None	0	N/A	N/A
5490	2	2	207	Nurse's Office 207	yes	door frame	Metal	Blue	Chipping	10	0	Negative
5490	2	2	207	Nurse's Office 207	yes	W2	Concrete	blue/white	None	0	N/A	N/A
5490	2	2	207	Nurse's Office 207	yes	W3	Concrete	White	None	0	N/A	N/A
5490	2	2	207	Nurse's Office 207	yes	W4	Concrete	blue/white	None	0	N/A	N/A
5490	2	2	207	Nurse's Office 207	yes	Floor	Concrete	N/A	None	0	N/A	N/A
5490	2	2	207	Nurse's Office 207	yes	Ceiling	Concrete	White	None	0	N/A	N/A
5490	2	2	207A	Nurse's Office Restroom	yes	W1	Concrete	White	None	0	N/A	N/A
5490	2	2	207A	Nurse's Office Restroom	yes	door frame	Metal	Blue	Chipping	8	0	Negative
5490	2	2	207A	Nurse's Office Restroom	yes	W2	Concrete	White	None	0	N/A	N/A
5490	2	2	207A	Nurse's Office Restroom	yes	W3	Concrete	White	None	0	N/A	N/A
5490	2	2	207A	Nurse's Office Restroom	yes	W4	Concrete	White	None	0	N/A	N/A
5490	2	2	207A	Nurse's Office Restroom	yes	Floor	Concrete	N/A	None	0	N/A	N/A
5490	2	2	207A	Nurse's Office Restroom	yes	Ceiling	Concrete	White	None	0	N/A	N/A
5490	2	2	ST2	Speech Therapy Room across from Nurse's Office 207	yes	W1	Concrete	Tan	None	0	N/A	N/A
5490	2	2	ST2	Speech Therapy Room across from Nurse's Office 207	yes	door frame	Metal	Blue	Chipping	8	0	Negative
5490	2	2	ST2	Speech Therapy Room across from Nurse's Office 207	yes	W2	Concrete	Tan	None	0	N/A	N/A
5490	2	2	ST2	Speech Therapy Room across from Nurse's Office 207	yes	W3	Concrete	Tan	None	0	N/A	N/A
5490	2	2	ST2	Speech Therapy Room across from Nurse's Office 207	yes	W4	Concrete	Tan	Cracking	8	0	Negative

				Inspection Dates: May 2020		School District of Philadelphia						
				James Mongan		Lead Safe Certification Assessment Report						
				Vertex		Cayuga Elementary School						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
5490	2	2	ST2	Speech Therapy Room across from Nurse's Office 207	yes	Floor	Concrete	N/A	None	0	N/A	N/A
5490	2	2	ST2	Speech Therapy Room across from Nurse's Office 207	yes	Ceiling	Concrete	White	None	0	N/A	N/A
5490	2	2	209	Electrical Room 209 inside Speech Therapy Room	no	W1	Concrete	N/A	None	0	N/A	N/A
5490	2	2	209	Electrical Room 209 inside Speech Therapy Room	no	W2	Concrete	Tan	None	0	N/A	N/A
5490	2	2	209	Electrical Room 209 inside Speech Therapy Room	no	W3	Concrete	Tan	None	0	N/A	N/A
5490	2	2	209	Electrical Room 209 inside Speech Therapy Room	no	W4	Concrete	Tan	None	0	N/A	N/A
5490	2	2	209	Electrical Room 209 inside Speech Therapy Room	no	Floor	Concrete	N/A	None	0	N/A	N/A
5490	2	2	209	Electrical Room 209 inside Speech Therapy Room	no	Ceiling	Concrete	White	None	0	N/A	N/A
5490	2	2	210	Custodial Closet 210 outside Speech Therapy Room	no	W1	Concrete	Tan	None	0	N/A	N/A
5490	2	2	210	Custodial Closet 210 outside Speech Therapy Room	no	W2	Concrete	Tan	None	0	N/A	N/A
5490	2	2	210	Custodial Closet 210 outside Speech Therapy Room	no	W3	Concrete	Tan	None	0	N/A	N/A
5490	2	2	210	Custodial Closet 210 outside Speech Therapy Room	no	W4	Concrete	Tan	None	0	N/A	N/A
5490	2	2	210	Custodial Closet 210 outside Speech Therapy Room	no	Floor	Concrete	N/A	None	0	N/A	N/A
5490	2	2	210	Custodial Closet 210 outside Speech Therapy Room	no	Ceiling	Concrete	White	None	0	N/A	N/A
5490	2	2	210A	Pipe Chase in Custodial Closet 210 outside Speech Therapy Room	no	W1	No Access	No Access	No Access	No Access	No Access	No Access
5490	2	2	210A	Pipe Chase in Custodial Closet 210 outside Speech Therapy Room	no	W2	No Access	No Access	No Access	No Access	No Access	No Access
5490	2	2	210A	Pipe Chase in Custodial Closet 210 outside Speech Therapy Room	no	W3	No Access	No Access	No Access	No Access	No Access	No Access

				Inspection Dates: May 2020		School District of Philadelphia						
				James Mongan		Lead Safe Certification Assessment Report						
				Vertex		Cayuga Elementary School						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
5490	2	2	210A	Pipe Chase in Custodial Closet 210 outside Speech Therapy Room	no	W4	No Access	No Access	No Access	No Access	No Access	No Access
5490	2	2	210A	Pipe Chase in Custodial Closet 210 outside Speech Therapy Room	no	Floor	No Access	No Access	No Access	No Access	No Access	No Access
5490	2	2	210A	Pipe Chase in Custodial Closet 210 outside Speech Therapy Room	no	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
5490	2	2	G22	Girl's Restroom across from Stairwell 2	yes	W1	Concrete	Tan	None	0	N/A	N/A
5490	2	2	G22	Girl's Restroom across from Stairwell 2	yes	W2	Concrete	Tan	None	0	N/A	N/A
5490	2	2	G22	Girl's Restroom across from Stairwell 2	yes	W3	Concrete	Tan	None	0	N/A	N/A
5490	2	2	G22	Girl's Restroom across from Stairwell 2	yes	W4	Concrete	Tan	None	0	N/A	N/A
5490	2	2	G22	Girl's Restroom across from Stairwell 2	yes	Floor	Concrete	White	None	0	N/A	N/A
5490	2	2	G22	Girl's Restroom across from Stairwell 2	yes	Ceiling	Concrete	White	None	0	N/A	N/A
5490	2	3	S31	Stairwell 1	yes	W1	Concrete	Orange	Chipping	2	0.11	Negative
5490	2	3	S31	Stairwell 1	yes	W2	Concrete	Orange	Cracking	10	0.1	Negative
5490	2	3	S31	Stairwell 1	yes	W3	Concrete	White	None	0	N/A	N/A
5490	2	3	S31	Stairwell 1	yes	W4	Concrete	White	Cracking	10	0.04	Negative
5490	2	3	S31	Stairwell 1	yes	Floor	Concrete	N/A	None	0	N/A	N/A
5490	2	3	S31	Stairwell 1	yes	Ceiling	Concrete	White	None	0	N/A	N/A
5490	2	3	S32	Stairwell 2	yes	W1	Concrete	Green	Efflorescence	2	0	Negative
5490	2	3	S32	Stairwell 2	yes	W2	Concrete	green/white	None	0	N/A	N/A
5490	2	3	S32	Stairwell 2	yes	W3	Concrete	green/white	None	0	N/A	N/A
5490	2	3	S32	Stairwell 2	yes	W4	Concrete	green/white	None	0	N/A	N/A
5490	2	3	S32	Stairwell 2	yes	Floor	Concrete	N/A	None	0	N/A	N/A
5490	2	3	S32	Stairwell 2	yes	Ceiling	Concrete	White	None	0	N/A	N/A
5490	2	3	H32	Hallway from Stairwell 1 to Stairwell 2	yes	W1	Concrete	White	None	0	N/A	N/A

				Inspection Dates: May 2020		School District of Philadelphia						
				James Mongan		Lead Safe Certification Assessment Report						
				Vertex		Cayuga Elementary School						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
5490	2	3	H32	Hallway from Stairwell 1 to Stairwell 2	yes	W2	Concrete	White	None	0	N/A	N/A
5490	2	3	H32	Hallway from Stairwell 1 to Stairwell 2	yes	W3	Concrete	White	Chipping	1	0	Negative
5490	2	3	H32	Hallway from Stairwell 1 to Stairwell 2	yes	W4	Concrete	White	None	0	N/A	N/A
5490	2	3	H32	Hallway from Stairwell 1 to Stairwell 2	yes	Floor	Concrete	N/A	None	0	N/A	N/A
5490	2	3	H32	Hallway from Stairwell 1 to Stairwell 2	yes	Ceiling	Concrete	White	None	0	N/A	N/A
5490	2	3	B32	Boy's Restroom across from Stairwell 1	yes	W1	Concrete	Tan	None	0	N/A	N/A
5490	2	3	B32	Boy's Restroom across from Stairwell 1	yes	W2	Concrete	Tan	None	0	N/A	N/A
5490	2	3	B32	Boy's Restroom across from Stairwell 1	yes	W3	Concrete	Tan	None	0	N/A	N/A
5490	2	3	B32	Boy's Restroom across from Stairwell 1	yes	W4	Concrete	Tan	None	0	N/A	N/A
5490	2	3	B32	Boy's Restroom across from Stairwell 1	yes	Floor	Concrete	White	None	0	N/A	N/A
5490	2	3	B32	Boy's Restroom across from Stairwell 1	yes	Ceiling	Concrete	White	None	0	N/A	N/A
5490	2	3	G32	Girl's Restroom across from Stairwell 2	yes	W1	Concrete	Tan	None	0	N/A	N/A
5490	2	3	G32	Girl's Restroom across from Stairwell 2	yes	door frame	Metal	Pink	Chipping	9	0	Negative
5490	2	3	G32	Girl's Restroom across from Stairwell 2	yes	W2	Concrete	Tan	None	0	N/A	N/A
5490	2	3	G32	Girl's Restroom across from Stairwell 2	yes	W3	Concrete	Tan	None	0	N/A	N/A
5490	2	3	G32	Girl's Restroom across from Stairwell 2	yes	W4	Concrete	Tan	None	0	N/A	N/A
5490	2	3	G32	Girl's Restroom across from Stairwell 2	yes	Floor	Concrete	White	None	0	N/A	N/A
5490	2	3	G32	Girl's Restroom across from Stairwell 2	yes	Ceiling	Concrete	White	Cracking	4	0	Negative
5490	2	3	301	Classroom 301	yes	W1	Concrete	White	None	0	N/A	N/A
5490	2	3	301	Classroom 301	yes	door frame	Metal	Blue	Chipping	8	0.12	Negative
5490	2	3	301	Classroom 301	yes	W2	Concrete	White	None	0	N/A	N/A

				Inspection Dates: May 2020		School District of Philadelphia						
				James Mongan		Lead Safe Certification Assessment Report						
				Vertex		Cayuga Elementary School						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
5490	2	3	301	Classroom 301	yes	W3	Concrete	White	None	0	N/A	N/A
5490	2	3	301	Classroom 301	yes	W4	Concrete	Green	None	0	N/A	N/A
5490	2	3	301	Classroom 301	yes	Floor	Concrete	N/A	None	0	N/A	N/A
5490	2	3	301	Classroom 301	yes	Ceiling	Concrete	White	None	0	N/A	N/A
5490	2	3	302	Classroom 302	yes	W1	Concrete	White	None	0	N/A	N/A
5490	2	3	302	Classroom 302	yes	door frame	Metal	Blue	Chipping	8	0.04	Negative
5490	2	3	302	Classroom 302	yes	W2	Concrete	White	None	0	N/A	N/A
5490	2	3	302	Classroom 302	yes	W3	Concrete	White	None	0	N/A	N/A
5490	2	3	302	Classroom 302	yes	W4	Concrete	Green	None	0	N/A	N/A
5490	2	3	302	Classroom 302	yes	Floor	Concrete	N/A	None	0	N/A	N/A
5490	2	3	302	Classroom 302	yes	Ceiling	Concrete	White	None	0	N/A	N/A
5490	2	3	303	Classroom 303	yes	W1	Concrete	White	None	0	N/A	N/A
5490	2	3	303	Classroom 303	yes	door frame	Metal	Blue	Chipping	8	0.02	Negative
5490	2	3	303	Classroom 303	yes	W2	Concrete	White	None	0	N/A	N/A
5490	2	3	303	Classroom 303	yes	W3	Concrete	White	None	0	N/A	N/A
5490	2	3	303	Classroom 303	yes	W4	Concrete	Green	Chipping	1	0.04	Negative
5490	2	3	303	Classroom 303	yes	Floor	Concrete	N/A	None	0	N/A	N/A
5490	2	3	303	Classroom 303	yes	Ceiling	Concrete	White	None	0	N/A	N/A
5490	2	3	304	Classroom 304	yes	W1	Concrete	White	None	0	N/A	N/A
5490	2	3	304	Classroom 304	yes	door frame	Metal	Blue	Chipping	10	0.11	Negative
5490	2	3	304	Classroom 304	yes	W2	Concrete	White	None	0	N/A	N/A
5490	2	3	304	Classroom 304	yes	W3	Concrete	White	None	0	N/A	N/A
5490	2	3	304	Classroom 304	yes	W4	Concrete	Green	None	0	N/A	N/A
5490	2	3	304	Classroom 304	yes	Floor	Concrete	N/A	None	0	N/A	N/A
5490	2	3	304	Classroom 304	yes	Ceiling	Concrete	White	None	0	N/A	N/A
5490	2	3	305	Classroom 305	yes	W1	Concrete	White	None	0	N/A	N/A
5490	2	3	305	Classroom 305	yes	door frame	Metal	Blue	Chipping	8	0.06	Negative
5490	2	3	305	Classroom 305	yes	W2	Concrete	White	None	0	N/A	N/A
5490	2	3	305	Classroom 305	yes	W3	Concrete	White	None	0	N/A	N/A
5490	2	3	305	Classroom 305	yes	W4	Concrete	Green	None	0	N/A	N/A
5490	2	3	305	Classroom 305	yes	Floor	Concrete	N/A	None	0	N/A	N/A
5490	2	3	305	Classroom 305	yes	Ceiling	Concrete	White	None	0	N/A	N/A
5490	2	3	306	Classroom 306	yes	W1	Concrete	White	None	0	N/A	N/A
5490	2	3	306	Classroom 306	yes	door frame	Metal	Blue	Chipping	8	0.02	Negative
5490	2	3	306	Classroom 306	yes	W2	Concrete	White	None	0	N/A	N/A
5490	2	3	306	Classroom 306	yes	W3	Concrete	White	None	0	N/A	N/A

				Inspection Dates: May 2020		School District of Philadelphia						
				James Mongan		Lead Safe Certification Assessment Report						
				Vertex		Cayuga Elementary School						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
5490	2	3	306	Classroom 306	yes	W4	Concrete	Green	None	0	N/A	N/A
5490	2	3	306	Classroom 306	yes	Floor	Concrete	N/A	None	0	N/A	N/A
5490	2	3	306	Classroom 306	yes	Ceiling	Concrete	White	None	0	N/A	N/A
5490	2	3	TL32	Teacher's Lounge next to Classroom 305	yes	W1	Concrete	Tan	None	0	N/A	N/A
5490	2	3	TL32	Teacher's Lounge next to Classroom 305	yes	door frame	Metal	Pink	Chipping	8	0.04	Negative
5490	2	3	TL32	Teacher's Lounge next to Classroom 305	yes	W2	Concrete	Tan	Chipping	1	0	Negative
5490	2	3	TL32	Teacher's Lounge next to Classroom 305	yes	W3	Concrete	Green	None	0	N/A	N/A
5490	2	3	TL32	Teacher's Lounge next to Classroom 305	yes	W4	Concrete	Tan	None	0	N/A	N/A
5490	2	3	TL32	Teacher's Lounge next to Classroom 305	yes	Floor	Concrete	N/A	None	0	N/A	N/A
5490	2	3	TL32	Teacher's Lounge next to Classroom 305	yes	Ceiling	Concrete	White	None	0	N/A	N/A
5490	2	3	ST32	Storage Room next to Classroom 306	yes	W1	Concrete	Tan	None	0	N/A	N/A
5490	2	3	ST32	Storage Room next to Classroom 306	yes	door frame	Metal	Pink	Chipping	10	0.04	Negative
5490	2	3	ST32	Storage Room next to Classroom 306	yes	W2	Concrete	Tan	None	0	N/A	N/A
5490	2	3	ST32	Storage Room next to Classroom 306	yes	W3	Concrete	Tan	None	0	N/A	N/A
5490	2	3	ST32	Storage Room next to Classroom 306	yes	W4	Concrete	Tan	Chipping	2	0	Negative
5490	2	3	ST32	Storage Room next to Classroom 306	yes	Floor	Concrete	N/A	None	0	N/A	N/A
5490	2	3	ST32	Storage Room next to Classroom 306	yes	Ceiling	Concrete	White	None	0	N/A	N/A
5490	2	3	310	Custodial Closet 310 next to Girl's Restroom	no	W1	Concrete	green/white	None	0	N/A	N/A
5490	2	3	310	Custodial Closet 310 next to Girl's Restroom	no	W2	Concrete	green/white	None	0	N/A	N/A
5490	2	3	310	Custodial Closet 310 next to Girl's Restroom	no	W3	Concrete	green/white	None	0	N/A	N/A
5490	2	3	310	Custodial Closet 310 next to Girl's Restroom	no	W4	Concrete	green/white	None	0	N/A	N/A

				Inspection Dates: May 2020		School District of Philadelphia						
				James Mongan		Lead Safe Certification Assessment Report						
				Vertex		Cayuga Elementary School						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
5490	2	3	310	Custodial Closet 310 next to Girl's Restroom	no	Floor	Concrete	White	None	0	N/A	N/A
5490	2	3	310	Custodial Closet 310 next to Girl's Restroom	no	Ceiling	N/A	N/A	None	0	N/A	N/A
5490	2	3	310A	Pipe Chase in Custodial Closet 310 next to Girl's Restroom	no	W1	No Access	No Access	No Access	No Access	No Access	No Access
5490	2	3	310A	Pipe Chase in Custodial Closet 310 next to Girl's Restroom	no	W2	No Access	No Access	No Access	No Access	No Access	No Access
5490	2	3	310A	Pipe Chase in Custodial Closet 310 next to Girl's Restroom	no	W3	No Access	No Access	No Access	No Access	No Access	No Access
5490	2	3	310A	Pipe Chase in Custodial Closet 310 next to Girl's Restroom	no	W4	No Access	No Access	No Access	No Access	No Access	No Access
5490	2	3	310A	Pipe Chase in Custodial Closet 310 next to Girl's Restroom	no	Floor	No Access	No Access	No Access	No Access	No Access	No Access
5490	2	3	310A	Pipe Chase in Custodial Closet 310 next to Girl's Restroom	no	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
5490	1	A	AT	Attic - None	N/A	W1	N/A	N/A	N/A	N/A	N/A	N/A
5490	1	A	AT	Attic - None	N/A	W2	N/A	N/A	N/A	N/A	N/A	N/A
5490	1	A	AT	Attic - None	N/A	W3	N/A	N/A	N/A	N/A	N/A	N/A
5490	1	A	AT	Attic - None	N/A	W4	N/A	N/A	N/A	N/A	N/A	N/A
5490	1	A	AT	Attic - None	N/A	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5490	1	A	AT	Attic - None	N/A	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5490	1	C	CS	Crawl Space - None	N/A	W1	N/A	N/A	N/A	N/A	N/A	N/A
5490	1	C	CS	Crawl Space - None	N/A	W2	N/A	N/A	N/A	N/A	N/A	N/A
5490	1	C	CS	Crawl Space - None	N/A	W3	N/A	N/A	N/A	N/A	N/A	N/A
5490	1	C	CS	Crawl Space - None	N/A	W4	N/A	N/A	N/A	N/A	N/A	N/A
5490	1	C	CS	Crawl Space - None	N/A	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5490	1	C	CS	Crawl Space - None	N/A	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A