

				Inspection Dates: 09/08/2021-09/10/2021			School District of Philadelphia					
				Name of Inspector: Lionel Ray Wilson			Lead Safe Certification Assessment Report					
				Inspection Company: Viva EHS			Dunbar School					
ULCS#	Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
5250	1	B	1A	Storage Room 1A	No	W1	Unpainted	N/A	N/A	N/A	N/A	N/A
5250	1	B	1A	Storage Room 1A	No	W2	Unpainted	N/A	N/A	N/A	N/A	N/A
5250	1	B	1A	Storage Room 1A	No	W3	Unpainted	N/A	N/A	N/A	N/A	N/A
5250	1	B	1A	Storage Room 1A	No	W4	Unpainted	N/A	N/A	N/A	N/A	N/A
5250	1	B	1A	Storage Room 1A	No	Ceiling	Unpainted	N/A	N/A	N/A	N/A	N/A
5250	1	B	1A	Storage Room 1A	No	Floor	Unpainted	N/A	N/A	N/A	N/A	N/A
5250	1	B	001A	Storage below Stairwell 001A	No	W1	Brick	Yellow	None	0	N/A	N/A
5250	1	B	001A	Storage below Stairwell 001A	No	W2	Brick	Yellow	Chipping	1	0.3	Negative
5250	1	B	001A	Storage below Stairwell 001A	No	W3	Brick	Yellow	No Access to inspect			
5250	1	B	001A	Storage below Stairwell 001A	No	W4	Brick	Yellow	None	0	N/A	N/A
5250	1	B	001A	Storage below Stairwell 001A	No	Ceiling	Concrete	Yellow	None	0	N/A	N/A
5250	1	B	001A	Storage below Stairwell 001A	No	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
5250	1	B	1B	Auditorium Supply Plenum (Crawl Space below Auditorium)	No	W1	Unpainted	N/A	N/A	N/A	N/A	N/A
5250	1	B	1B	Auditorium Supply Plenum (Crawl Space below Auditorium)	No	W2	Unpainted	N/A	N/A	N/A	N/A	N/A
5250	1	B	1B	Auditorium Supply Plenum (Crawl Space below Auditorium)	No	W3	Unpainted	N/A	N/A	N/A	N/A	N/A
5250	1	B	1B	Auditorium Supply Plenum (Crawl Space below Auditorium)	No	W4	Unpainted	N/A	N/A	N/A	N/A	N/A
5250	1	B	1B	Auditorium Supply Plenum (Crawl Space below Auditorium)	No	Ceiling	Unpainted	N/A	N/A	N/A	N/A	N/A
5250	1	B	1B	Auditorium Supply Plenum (Crawl Space below Auditorium)	No	Floor	Unpainted	N/A	N/A	N/A	N/A	N/A
5250	1	B	1C	Crawl Space below Lunch Rooms 104 and 106	No	W1	Unpainted	N/A	N/A	N/A	N/A	N/A
5250	1	B	1C	Crawl Space below Lunch Rooms 104 and 106	No	W2	Unpainted	N/A	N/A	N/A	N/A	N/A
5250	1	B	1C	Crawl Space below Lunch Rooms 104 and 106	No	W3	Unpainted	N/A	N/A	N/A	N/A	N/A
5250	1	B	1C	Crawl Space below Lunch Rooms 104 and 106	No	W4	Unpainted	N/A	N/A	N/A	N/A	N/A
5250	1	B	1C	Crawl Space below Lunch Rooms 104 and 106	No	Ceiling	Unpainted	N/A	N/A	N/A	N/A	N/A
5250	1	B	1C	Crawl Space below Lunch Rooms 104 and 106	No	Floor	Unpainted	N/A	N/A	N/A	N/A	N/A
5250	1	B	3	Hallway outside of Girl's Restroom	Yes	W1	Brick	Unpainted	None	0	N/A	N/A
5250	1	B	3	Hallway outside of Girl's Restroom	Yes	W2	Brick	Unpainted	None	0	N/A	N/A
5250	1	B	3	Hallway outside of Girl's Restroom	Yes	W3	Brick	Unpainted	None	0	N/A	N/A
5250	1	B	3	Hallway outside of Girl's Restroom	Yes	W4	Brick	Unpainted	None	0	N/A	N/A
5250	1	B	3	Hallway outside of Girl's Restroom	Yes	Ceiling	Concrete	White	None	0	N/A	N/A
5250	1	B	3	Hallway outside of Girl's Restroom	Yes	Floor	Concrete	Unpainted	None	0	N/A	N/A
5250	1	B	1	Gym Teachers Office	Yes	W1	Brick	White	None	0	N/A	N/A
5250	1	B	1	Gym Teachers Office	Yes	W2	Brick	White	None	0	N/A	N/A
5250	1	B	1	Gym Teachers Office	Yes	W3	Brick	White	None	0	N/A	N/A
5250	1	B	1	Gym Teachers Office	Yes	W4	Brick	White	None	0	N/A	N/A
5250	1	B	1	Gym Teachers Office	Yes	Ceiling	Concrete	White	None	0	N/A	N/A
5250	1	B	1	Gym Teachers Office	Yes	Floor	Concrete	Unpainted	None	0	N/A	N/A
5250	1	B	2	Girl's Restroom	Yes	W1	Brick	White	None	0	N/A	N/A
5250	1	B	2	Girl's Restroom	Yes	W1	CMU Block Wall	White	None	0	0	Negative
5250	1	B	2	Girl's Restroom	Yes	W2	Brick	White	None	0	N/A	N/A
5250	1	B	2	Girl's Restroom	Yes	W3	Brick	White	None	0	N/A	N/A
5250	1	B	2	Girl's Restroom	Yes	W4	Brick	White	None	0	N/A	N/A

				Inspection Dates: 09/08/2021-09/10/2021		School District of Philadelphia						
				Name of Inspector: Lionel Ray Wilson		Lead Safe Certification Assessment Report						
				Inspection Company: Viva EHS		Dunbar School						
ULCS#	Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
5250	1	B	2	Girl's Restroom	Yes	Ceiling	Concrete	White	None	0	N/A	N/A
5250	1	B	2	Girl's Restroom	Yes	Floor	Concrete	Grey	None	0	N/A	N/A
5250	1	B	2A	Storage Room inside Girl's Restroom	Yes	W1	Brick	White	None	0	N/A	N/A
5250	1	B	2A	Storage Room inside Girl's Restroom	Yes	W2	Brick	White	Chipping	1	4	Positive
5250	1	B	2A	Storage Room inside Girl's Restroom	Yes	W3	Brick	White	Chipping	3	4	Positive
5250	1	B	2A	Storage Room inside Girl's Restroom	Yes	W4	Brick	White	None	0	N/A	N/A
5250	1	B	2A	Storage Room inside Girl's Restroom	Yes	Ceiling	Concrete	White	Chipping	20	No access to ceiling	N/A
5250	1	B	2A	Storage Room inside Girl's Restroom	Yes	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
5250	1	B	2B	Girl's Restroom Pipechase accessed from the adjacent Hallway	No	W1	Unpainted	N/A	N/A	N/A	N/A	N/A
5250	1	B	2B	Girl's Restroom Pipechase accessed from the adjacent Hallway	No	W2	Unpainted	N/A	N/A	N/A	N/A	N/A
5250	1	B	2B	Girl's Restroom Pipechase accessed from the adjacent Hallway	No	W3	Unpainted	N/A	N/A	N/A	N/A	N/A
5250	1	B	2B	Girl's Restroom Pipechase accessed from the adjacent Hallway	No	W4	Unpainted	N/A	N/A	N/A	N/A	N/A
5250	1	B	2B	Girl's Restroom Pipechase accessed from the adjacent Hallway	No	Ceiling	Unpainted	N/A	N/A	N/A	N/A	N/A
5250	1	B	2B	Girl's Restroom Pipechase accessed from the adjacent Hallway	No	Floor	Unpainted	N/A	N/A	N/A	N/A	N/A
5250	1	B	3A	Electrical Room	No	W1	Brick	White	None	0	N/A	N/A
5250	1	B	3A	Electrical Room	No	W2	Brick	White	None	0	N/A	N/A
5250	1	B	3A	Electrical Room	No	W3	Brick	White	None	0	N/A	N/A
5250	1	B	3A	Electrical Room	No	W4	Brick	White	None	0	N/A	N/A
5250	1	B	3A	Electrical Room	No	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
5250	1	B	3A	Electrical Room	No	Floor	Concrete	Unpainted				
5250	1	B	4	Gymnasium	Yes	W1	Brick	Unpainted	None	0	N/A	N/A
5250	1	B	4	Gymnasium	Yes	W2	Brick	Unpainted	None	0	N/A	N/A
5250	1	B	4	Gymnasium	Yes	W3	Brick	Unpainted	None	0	N/A	N/A
5250	1	B	4	Gymnasium	Yes	W4	Brick	Unpainted	None	0	N/A	N/A
5250	1	B	4	Gymnasium	Yes	Ceiling	Plaster	No Access				
5250	1	B	4	Gymnasium	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5250	1	B	4	Gymnasium	Yes	Door	Metal	Green	Chipping	1	0	Negative
5250	1	B	4	Gymnasium	Yes	Door Casing	Metal	Green	Chipping	1	0	Negative
5250	1	B	5	Hallway outside of Boys Restroom	Yes	W1	Brick	Unpainted	None	0	N/A	N/A
5250	1	B	5	Hallway outside of Boys Restroom	Yes	W2	Brick	Unpainted	None	0	N/A	N/A
5250	1	B	5	Hallway outside of Boys Restroom	Yes	W3	Brick	Unpainted	None	0	N/A	N/A
5250	1	B	5	Hallway outside of Boys Restroom	Yes	W4	Brick	Unpainted	None	0	N/A	N/A
5250	1	B	5	Hallway outside of Boys Restroom	Yes	Ceiling	Concrete	White	None	0	N/A	N/A
5250	1	B	5	Hallway outside of Boys Restroom	Yes	Floor	Concrete	N/A				
5250	1	B	6	Boys Restroom	Yes	W1	Brick	White	None	0	N/A	N/A
5250	1	B	6	Boys Restroom	Yes	W1	CMU Block Wall	White	None	0	0	Negative
5250	1	B	6	Boys Restroom	Yes	W2	Brick	White	None	0	N/A	N/A
5250	1	B	6	Boys Restroom	Yes	W3	Brick	White	None	0	N/A	N/A
5250	1	B	6	Boys Restroom	Yes	W4	Brick	White	None	0	N/A	N/A
5250	1	B	6	Boys Restroom	Yes	Ceiling	Concrete	White	None	0	N/A	N/A
5250	1	B	6	Boys Restroom	Yes	Floor	Concrete	Grey	Chipping	2	0.01	Negative

				Inspection Dates: 09/08/2021-09/10/2021				School District of Philadelphia				
				Name of Inspector: Lionel Ray Wilson				Lead Safe Certification Assessment Report				
				Inspection Company: Viva EHS				Dunbar School				
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
5250	1	B	NP-2	Storage Room inside Boys Restroom	No	W1	Brick	White	None	0	N/A	N/A
5250	1	B	NP-2	Storage Room inside Boys Restroom	No	W2	Brick	White	None	0	N/A	N/A
5250	1	B	NP-2	Storage Room inside Boys Restroom	No	W3	Brick	White	Flaking	5	0.06	Negative
5250	1	B	NP-2	Storage Room inside Boys Restroom	No	W4	Brick	White	None	0	N/A	N/A
5250	1	B	NP-2	Storage Room inside Boys Restroom	No	Ceiling	Concrete	White	None	0	N/A	N/A
5250	1	B	NP-2	Storage Room inside Boys Restroom	No	Floor	Concrete	Unpainted				
5250	1	B	8	Building Engineer's Office	No	W1	Brick	White/Blue	None	0	N/A	N/A
5250	1	B	8	Building Engineer's Office	No	W2	Brick	White/Blue	None	0	N/A	N/A
5250	1	B	8	Building Engineer's Office	No	W3	Plaster	White/Blue	None	0	N/A	N/A
5250	1	B	8	Building Engineer's Office	No	W4	Brick	White/Blue	None	0	N/A	N/A
5250	1	B	8	Building Engineer's Office	No	W4	Plaster	White/Blue	None	0	N/A	N/A
5250	1	B	8	Building Engineer's Office	No	Ceiling	Concrete	White	Chipping	20	0.55	Negative
5250	1	B	8	Building Engineer's Office	No	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5250	1	B	8A	Building Engineer's Office Restroom	No	W1	Plaster	White/Purple	None	0	N/A	N/A
5250	1	B	8A	Building Engineer's Office Restroom	No	W2	Plaster	White/Purple	None	0	N/A	N/A
5250	1	B	8A	Building Engineer's Office Restroom	No	W3	Plaster	White/Purple	None	0	N/A	N/A
5250	1	B	8A	Building Engineer's Office Restroom	No	W4	Plaster	White/Purple	None	0	N/A	N/A
5250	1	B	8A	Building Engineer's Office Restroom	No	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
5250	1	B	8A	Building Engineer's Office Restroom	No	Floor	Concrete	Grey	Chipping	1	1.5	Positive
5250	1	B	9	Building Engineer's Office Closet	No	W1	Plaster	Yellow	Chipping	4	8.9	Positive
5250	1	B	9	Building Engineer's Office Closet	No	W2	Brick	Yellow	None	0	N/A	N/A
5250	1	B	9	Building Engineer's Office Closet	No	W3	Concrete	Yellow	Chipping	10	8.4	Positive
5250	1	B	9	Building Engineer's Office Closet	No	W4	Concrete	Yellow	Chipping	5	0.09	Negative
5250	1	B	9	Building Engineer's Office Closet	No	Ceiling	Concrete	Yellow	Chipping	20	N/A	N/A
5250	1	B	9	Building Engineer's Office Closet	No	Floor	Concrete	Grey	Chipping	4	0.12	Negative
5250	1	B	9	Building Engineer's Office Closet	No	Door Casing	Metal	Yellow	Chipping	8	12.8	Positive
5250	1	B	NP-1	Storage across from the Old Ash Room	No	W1	Unpainted	N/A	N/A	N/A	N/A	N/A
5250	1	B	NP-1	Storage across from the Old Ash Room	No	W2	Unpainted	N/A	N/A	N/A	N/A	N/A
5250	1	B	NP-1	Storage across from the Old Ash Room	No	W3	Unpainted	N/A	N/A	N/A	N/A	N/A
5250	1	B	NP-1	Storage across from the Old Ash Room	No	W4	Unpainted	N/A	N/A	N/A	N/A	N/A
5250	1	B	NP-1	Storage across from the Old Ash Room	No	Ceiling	Concrete	Brown	No Access			
5250	1	B	NP-1	Storage across from the Old Ash Room	No	Floor	Unpainted	N/A	N/A	N/A	N/A	N/A
5250	1	B	006A	Pipe Chase inside Storage across Old Ash Room	No	W1	Unpainted	N/A	N/A	N/A	N/A	N/A
5250	1	B	006A	Pipe Chase inside Storage across Old Ash Room	No	W2	Unpainted	N/A	N/A	N/A	N/A	N/A
5250	1	B	006A	Pipe Chase inside Storage across Old Ash Room	No	W3	Unpainted	N/A	N/A	N/A	N/A	N/A
5250	1	B	006A	Pipe Chase inside Storage across Old Ash Room	No	W4	Unpainted	N/A	N/A	N/A	N/A	N/A
5250	1	B	006A	Pipe Chase inside Storage across Old Ash Room	No	Ceiling	Unpainted	N/A	N/A	N/A	N/A	N/A
5250	1	B	006A	Pipe Chase inside Storage across Old Ash Room	No	Floor	Unpainted	N/A	N/A	N/A	N/A	N/A
5250	1	B	7	Boiler Room	No	W1	Concrete	Tan	Flaking	100	0.01	Negative
5250	1	B	7	Boiler Room	No	W1	Brick	Tan	Flaking	150	0.01	Negative
5250	1	B	7	Boiler Room	No	W2	Brick	Tan	Flaking	100	0.1	Negative
5250	1	B	7	Boiler Room	No	W2	Concrete	Tan	Chipping	50	9	Positive
5250	1	B	7	Boiler Room	No	W3	Concrete	Tan	Chipping	75	0.09	Negative
5250	1	B	7	Boiler Room	No	W4	Concrete	Tan	Chipping	75	0.23	Negative
5250	1	B	7	Boiler Room	No	Concrete Column	Concrete	Tan	Chipping	25	0	Negative

				Inspection Dates: 09/08/2021-09/10/2021	School District of Philadelphia							
				Name of Inspector: Lionel Ray Wilson	Lead Safe Certification Assessment Report							
				Inspection Company: Viva EHS	Dunbar School							
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
5250	1	B	7	Boiler Room	No	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
5250	1	B	7	Boiler Room	No	Floor	Unpainted	N/A	N/A	N/A	N/A	N/A
5250	1	B	7	Sump Pump Room- Boiler Room	No	W1	Concrete	White	Chipping	10	5.5	Positive
5250	1	B	7	Sump Pump Room- Boiler Room	No	W2	Concrete	White	Chipping	15	14.5	Positive
5250	1	B	7	Sump Pump Room- Boiler Room	No	W3	Concrete	White	Chipping	15	1.7	Positive
5250	1	B	7	Sump Pump Room- Boiler Room	No	W4	Concrete	White	Chipping	15	7.9	Positive
5250	1	B	7	Sump Pump Room- Boiler Room	No	Ceiling	Concrete	White	None	N/A	N/A	Positive
5250	1	B	7	Sump Pump Room- Boiler Room	No	Floor	Unpainted	N/A	N/A	N/A	N/A	Positive
5250	1	B	10	Old Ash Storage Room	No	W1	Unpainted	N/A	N/A	N/A	N/A	N/A
5250	1	B	10	Old Ash Storage Room	No	W2	Unpainted	N/A	N/A	N/A	N/A	N/A
5250	1	B	10	Old Ash Storage Room	No	W3	Unpainted	N/A	N/A	N/A	N/A	N/A
5250	1	B	10	Old Ash Storage Room	No	W4	Unpainted	N/A	N/A	N/A	N/A	N/A
5250	1	B	10	Old Ash Storage Room	No	Ceiling	Unpainted	N/A	N/A	N/A	N/A	N/A
5250	1	B	10	Old Ash Storage Room	No	Floor	Unpainted	N/A	N/A	N/A	N/A	N/A
5250	1	B	11	Old Coal Storage Room	No	W1	Unpainted	N/A	N/A	N/A	N/A	N/A
5250	1	B	11	Old Coal Storage Room	No	W2	Unpainted	N/A	N/A	N/A	N/A	N/A
5250	1	B	11	Old Coal Storage Room	No	W3	Unpainted	N/A	N/A	N/A	N/A	N/A
5250	1	B	11	Old Coal Storage Room	No	W4	Unpainted	N/A	N/A	N/A	N/A	N/A
5250	1	B	11	Old Coal Storage Room	No	Ceiling	Unpainted	N/A	N/A	N/A	N/A	N/A
5250	1	B	11	Old Coal Storage Room	No	Floor	Unpainted	N/A	N/A	N/A	N/A	N/A
5250	1	B	PL	Auditorium Plenum	No	W1	No Access	No Access	No Access	No Access	No Access	No Access
5250	1	B	PL	Auditorium Plenum	No	W2	No Access	No Access	No Access	No Access	No Access	No Access
5250	1	B	PL	Auditorium Plenum	No	W3	No Access	No Access	No Access	No Access	No Access	No Access
5250	1	B	PL	Auditorium Plenum	No	W4	No Access	No Access	No Access	No Access	No Access	No Access
5250	1	B	PL	Auditorium Plenum	No	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
5250	1	B	PL	Auditorium Plenum	No	Floor	No Access	No Access	No Access	No Access	No Access	No Access
5250	1	1	H13	Lobby/Hallway outside Auditorium	Yes	W1	Plaster	White	None	0	N/A	N/A
5250	1	1	H13	Lobby/Hallway outside Auditorium		Door Frame	Metal	Brown	Friction	2	0.1	Negative
5250	1	1	H13	Lobby/Hallway outside Auditorium		Door	Metal	Brown	Chipping	2	0	Negative
5250	1	1	H13	Lobby/Hallway outside Auditorium	Yes	W2	Plaster	White	Efflorescence	2	20.4	Positive
5250	1	1	H13	Lobby/Hallway outside Auditorium	Yes	W3	Plaster	White	Efflorescence	5	18	Positive
5250	1	1	H13	Lobby/Hallway outside Auditorium	Yes	W4	Plaster	White	None	0	N/A	N/A
5250	1	1	H13	Lobby/Hallway outside Auditorium		Radiator Grille	Metal	Tan	Flaking	2	0	Negative
5250	1	1	H13	Lobby/Hallway outside Auditorium	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5250	1	1	H13	Lobby/Hallway outside Auditorium	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5250	1	1	S16	Stairwell outside of Auditorium	Yes	W1	Plaster	White	None	0	N/A	N/A
5250	1	1	S16	Stairwell outside of Auditorium		Door Frame	Metal	Red	Friction	1	0	Negative
5250	1	1	S16	Stairwell outside of Auditorium		Pushbar	Metal	Grey	Friction	1	0	Negative
5250	1	1	S16	Stairwell outside of Auditorium	Yes	W2	Plaster	White	Cracking	3	30.4	Positive
5250	1	1	S16	Stairwell outside of Auditorium	Yes	W3	Plaster	White	Cracking	10	3.8	Positive
5250	1	1	S16	Stairwell outside of Auditorium		Door	Metal	Blue	Chipping	4	0	Negative
5250	1	1	S16	Stairwell outside of Auditorium	Yes	W4	Plaster	White	Efflorescence	8	30.4	Positive
5250	1	1	S16	Stairwell outside of Auditorium		Radiator Grille	Metal	Tan	Flaking	2	0	Negative
5250	1	1	S16	Stairwell outside of Auditorium	Yes	Ceiling	Plaster	White	None	0	N/A	N/A
5250	1	1	S16	Stairwell outside of Auditorium	Yes	Ceiling	Concrete	White	None	0	N/A	N/A
5250	1	1	S16	Stairwell outside of Auditorium	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A

				Inspection Dates: 09/08/2021-09/10/2021		School District of Philadelphia						
				Name of Inspector: Lionel Ray Wilson		Lead Safe Certification Assessment Report						
				Inspection Company: Viva EHS		Dunbar School						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
5250	1	1	S16	Stairwell outside of Auditorium	Yes	Newel Post	Metal	Tan	Chipping	1	2.3	Positive
5250	1	1	S16	Stairwell outside of Auditorium	Yes	Baluster	Metal	Tan	Chipping	5	3.8	Positive
5250	1	1	S16	Stairwell outside of Auditorium	Yes	Radiator	Metal	Tan	Chipping	1	0.26	Negative
5250	1	1	S16	Stairwell outside of Auditorium	Yes	Door	Metal	Blue	Chipping	3	0	Negative
5250	1	1	101A	Principal's Office	Yes	W1	Plaster	Blue	None	0	N/A	N/A
5250	1	1	101A	Principal's Office	Yes	W2	Plaster	Blue	None	0	N/A	N/A
5250	1	1	101A	Principal's Office	Yes	W3	Plaster	Blue	None	0	N/A	N/A
5250	1	1	101A	Principal's Office	Yes	W4	Plaster	Blue	None	0	N/A	N/A
5250	1	1	101A	Principal's Office	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5250	1	1	101A	Principal's Office	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5250	1	1	101D	Principal's Office Restroom	Yes	W1	Plaster	Blue	None	0	N/A	N/A
5250	1	1	101D	Principal's Office Restroom	Yes	W2	Plaster	Blue	None	0	N/A	N/A
5250	1	1	101D	Principal's Office Restroom	Yes	W3	Plaster	Blue	None	0	N/A	N/A
5250	1	1	101D	Principal's Office Restroom	Yes	W4	Plaster	Blue	None	0	N/A	N/A
5250	1	1	101D	Principal's Office Restroom	Yes	Ceiling	Plaster	Blue	Chipping	1	5.6	Positive
5250	1	1	101D	Principal's Office Restroom	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5250	1	1	101	Main Office	Yes	W1	Plaster	Blue	None	0	N/A	N/A
5250	1	1	101	Main Office	Yes	W2	Plaster	Blue	None	0	N/A	N/A
5250	1	1	101	Main Office	Yes	W3	Plaster	Blue	None	0	N/A	N/A
5250	1	1	101	Main Office	Yes	W4	Plaster	Blue	None	0	N/A	N/A
5250	1	1	101	Main Office	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5250	1	1	101	Main Office	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5250	1	1	101C	Main Office Closet	Yes	W1	Plaster	White	None	0	N/A	N/A
5250	1	1	101C	Main Office Closet	Yes	W2	Plaster	White	None	0	N/A	N/A
5250	1	1	101C	Main Office Closet	Yes	W3	Plaster	White	None	0	N/A	N/A
5250	1	1	101C	Main Office Closet	Yes	W4	Plaster	White	None	0	N/A	N/A
5250	1	1	101C	Main Office Closet	Yes	Ceiling	Plaster	White	N/A	N/A	N/A	N/A
5250	1	1	101C	Main Office Closet	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5250	1	1	100	Auditorium	Yes	W1	Plaster	White	Cracking	25	4.4	Positive
5250	1	1	100	Auditorium	Yes	W2	Plaster	White	Cracking	10	8.2	Positive
5250	1	1	100	Auditorium	Yes	W3	Plaster	White	Cracking	4	4.2	Positive
5250	1	1	100	Auditorium	Yes	W4	Plaster	White	Cracking	6	5.5	Positive
5250	1	1	100	Auditorium	Yes	Ceiling	Plaster	White	Cracking	3	N/A	N/A
5250	1	1	100	Auditorium	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5250	1	1	100E	Auditorium Stage	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
5250	1	1	100E	Auditorium Stage	Yes	W2	Plaster	White	Cracking	20	3.9	Positive
5250	1	1	100E	Auditorium Stage	Yes	W3	Plaster	White	Cracking	10	2.5	Positive
5250	1	1	100E	Auditorium Stage	Yes	W4	Plaster	White	Cracking	25	6	Positive
5250	1	1	100E	Auditorium Stage	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
5250	1	1	100E	Auditorium Stage	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5250	1	1	100A	Vestibule next to Stage along Exterior Wall	Yes	W1	Plaster	White	Cracking	1	13.4	Positive
5250	1	1	100A	Vestibule next to Stage along Exterior Wall	Yes	W2	Plaster	White	Efflorescence	4	18.1	Positive
5250	1	1	100A	Vestibule next to Stage along Exterior Wall	Yes	W3	Plaster	White	Efflorescence	10	1.8	Positive
5250	1	1	100A	Vestibule next to Stage along Exterior Wall	Yes	W4	Plaster	White	Cracking	2	13.3	Positive
5250	1	1	100A	Vestibule next to Stage along Exterior Wall	Yes	Ceiling	Plaster	White	None	0	N/A	N/A
5250	1	1	100A	Vestibule next to Stage along Exterior Wall	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A

Inspection Dates: 09/08/2021-09/10/2021					School District of Philadelphia							
Name of Inspector: Lionel Ray Wilson					Lead Safe Certification Assessment Report							
Inspection Company: Viva EHS					Dunbar School							
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
5250	1	1	100C	Restroom next to Stage along Exterior Wall	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
5250	1	1	100C	Restroom next to Stage along Exterior Wall	Yes	W2	Plaster	White	Chipping	5	15.2	Positive
5250	1	1	100C	Restroom next to Stage along Exterior Wall	Yes	W3	Plaster	White	Cracking	10	13.2	Positive
5250	1	1	100C	Restroom next to Stage along Exterior Wall	Yes	W4	Plaster	White	Chipping	20	17.9	Positive
5250	1	1	100C	Restroom next to Stage along Exterior Wall	Yes	Ceiling	Concrete	White	Hole	1	5.6	Positive
5250	1	1	100C	Restroom next to Stage along Exterior Wall	Yes	Floor	Concrete	Grey	Cracking	5	0.01	Negative
5250	1	1	100C	Restroom next to Stage along Exterior Wall	Yes	Radiator	Metal	White	Chipping	2	0.8	Positive
5250	1	1	100B	Vestibule next to Stage along Hallway Wall	Yes	W1	Plaster	White	Cracking	1	14.7	Positive
5250	1	1	100B	Vestibule next to Stage along Hallway Wall	Yes	W2	Plaster	White	Cracking	2	17	Positive
5250	1	1	100B	Vestibule next to Stage along Hallway Wall	Yes	W3	Plaster	White	Cracking	1	12.3	Positive
5250	1	1	100B	Vestibule next to Stage along Hallway Wall	Yes	W4	Plaster	White	Cracking	4	18.8	Positive
5250	1	1	100B	Vestibule next to Stage along Hallway Wall	Yes	Ceiling	Plaster	White	None	0	N/A	N/A
5250	1	1	100B	Vestibule next to Stage along Hallway Wall	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5250	1	1	100D	Restroom next to Stage along Hallway Wall	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
5250	1	1	100D	Restroom next to Stage along Hallway Wall	Yes	W2	Plaster	White	Chipping	2	16.7	Positive
5250	1	1	100D	Restroom next to Stage along Hallway Wall	Yes	W3	Plaster	White	None	0	N/A	N/A
5250	1	1	100D	Restroom next to Stage along Hallway Wall	Yes	W4	Plaster	White	Flaking	3	18	Positive
5250	1	1	100D	Restroom next to Stage along Hallway Wall	Yes	Ceiling	Concrete	White	Flaking	2	0.01	Negative
5250	1	1	100D	Restroom next to Stage along Hallway Wall	Yes	Floor	Concrete	Grey	Cracking	2	0.01	Negative
5250	1	1	100D	Restroom next to Stage along Hallway Wall	Yes	Radiator	Metal	Silver	Chipping	2	6.6	Positive
5250	1	1	101F	1st Floor Custodial Closet	No	W1	Plaster	White	Chipping	1	11.3	Positive
5250	1	1	101F	1st Floor Custodial Closet	No	W2	Plaster	White	Flaking	3	13.2	Positive
5250	1	1	101F	1st Floor Custodial Closet	No	W3	Plaster	White	Efflorescence/Chipping	5	9.3	Positive
5250	1	1	101F	1st Floor Custodial Closet	No	W4	Plaster	White	Cracking	10	3.7	Positive
5250	1	1	101F	1st Floor Custodial Closet	No	Ceiling	Plaster	White	None	0	N/A	N/A
5250	1	1	101F	1st Floor Custodial Closet	No	Floor	Concrete	Grey	Chipping	15	0	Negative
5250	1	1	101E	Closet across from Classroom 102	Yes	W1	No Access	No Access	No Access	No Access	No Access	No Access
5250	1	1	101E	Closet across from Classroom 102	Yes	W2	No Access	No Access	No Access	No Access	No Access	No Access
5250	1	1	101E	Closet across from Classroom 102	Yes	W3	No Access	No Access	No Access	No Access	No Access	No Access
5250	1	1	101E	Closet across from Classroom 102	Yes	W4	No Access	No Access	No Access	No Access	No Access	No Access
5250	1	1	101E	Closet across from Classroom 102	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
5250	1	1	101E	Closet across from Classroom 102	Yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access
5250	1	1	102	Classroom 102	Yes	W1	Plaster	Grey	None	0	N/A	N/A
5250	1	1	102	Classroom 102	Yes	W2	Plaster	Grey	None	0	N/A	N/A
5250	1	1	102	Classroom 102	Yes	W3	Plaster	Grey	None	0	N/A	N/A
5250	1	1	102	Classroom 102	Yes	W4	Plaster	Orange	None	0	N/A	N/A
5250	1	1	102	Classroom 102	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5250	1	1	102	Classroom 102	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5250	1	1	102A	Classroom 102 Coat Closet	Yes	W1	Plaster	Grey	None	0	N/A	N/A
5250	1	1	102A	Classroom 102 Coat Closet	Yes	W2	Plaster	Grey	None	0	N/A	N/A
5250	1	1	102A	Classroom 102 Coat Closet	Yes	W3	Plaster	Grey	None	0	N/A	N/A
5250	1	1	102A	Classroom 102 Coat Closet	Yes	W4	Plaster	Grey	None	0	N/A	N/A
5250	1	1	102A	Classroom 102 Coat Closet	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5250	1	1	102A	Classroom 102 Coat Closet	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5250	1	1	H14	Main Hallway	Yes	W1	Plaster	Multi	None	0	N/A	N/A
5250	1	1	H14	Main Hallway	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A

				Inspection Dates: 09/08/2021-09/10/2021		School District of Philadelphia						
				Name of Inspector: Lionel Ray Wilson		Lead Safe Certification Assessment Report						
				Inspection Company: Viva EHS		Dunbar School						
ULCS#	Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
5250	1	1	H14	Main Hallway	Yes	W3	Plaster	White	Chipping	3	15.8	Positive
5250	1	1	H14	Main Hallway	Yes	W4	Plaster	White	None	0	N/A	N/A
5250	1	1	H14	Main Hallway	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5250	1	1	H14	Main Hallway	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5250	1	1	103	Classroom 103	Yes	W1	Plaster	Yellow	Cracking	1	14.6	Positive
5250	1	1	103	Classroom 103	Yes	W2	Plaster	Yellow	Cracking	3	13.4	Positive
5250	1	1	103	Classroom 103	Yes	W3	Plaster	Yellow	Cracking	4	12.2	Positive
5250	1	1	103	Classroom 103	Yes	W4	Plaster	Yellow	Cracking	6	15.8	Positive
5250	1	1	103	Classroom 103	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5250	1	1	103	Classroom 103	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5250	1	1	103	Classroom 103	Yes	Pipe	Metal	Yellow	Cracking	1	3.2	Positive
5250	1	1	103	Classroom 103	Yes	Radiator	Metal	Yellow	Chipping	3	5.2	Positive
5250	1	1	103A	Classroom 103 Closet	Yes	W1	Plaster	White	None	0	N/A	N/A
5250	1	1	103A	Classroom 103 Closet	Yes	W2	Plaster	White	Chipping	7	9.2	Positive
5250	1	1	103A	Classroom 103 Closet	Yes	W3	Plaster	White	None	0	N/A	N/A
5250	1	1	103A	Classroom 103 Closet	Yes	W4	Plaster	White	Chipping	10	13	Positive
5250	1	1	103A	Classroom 103 Closet	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5250	1	1	103A	Classroom 103 Closet	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5250	1	1	103B	Classroom 103 Restroom	Yes	W1	Plaster	White	None	0	N/A	N/A
5250	1	1	103B	Classroom 103 Restroom	Yes	W2	Plaster	White	None	0	N/A	N/A
5250	1	1	103B	Classroom 103 Restroom	Yes	W3	Plaster	White	None	0	N/A	N/A
5250	1	1	103B	Classroom 103 Restroom	Yes	W4	Plaster	White	None	0	N/A	N/A
5250	1	1	103B	Classroom 103 Restroom	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5250	1	1	103B	Classroom 103 Restroom	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5250	1	1	103B	Classroom 103 Restroom	Yes	Baseboard	Wood	White	Cracking	1	0.04	Negative
5250	1	1	104	Lunchroom 104	Yes	W1	Plaster	White	Chipping	5	15	Positive
5250	1	1	104	Lunchroom 104	Yes	W2	Plaster	White	None	0	N/A	N/A
5250	1	1	104	Lunchroom 104	Yes	W3	Plaster	White	Cracking	2	12.3	Positive
5250	1	1	104	Lunchroom 104	Yes	W4	Plaster	White	Cracking	1	11.4	Positive
5250	1	1	104	Lunchroom 104	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5250	1	1	104	Lunchroom 104	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5250	1	1	104A	Dishwashing Room inside of Lunchroom (Former Coat Closet)	Yes	W1	Plaster	White	None	0	N/A	N/A
5250	1	1	104A	Dishwashing Room inside of Lunchroom (Former Coat Closet)	Yes	W2	Plaster	White	Chipping	10	7.4	Positive
5250	1	1	104A	Dishwashing Room inside of Lunchroom (Former Coat Closet)	Yes	W3	Plaster	White	None	0	N/A	N/A
5250	1	1	104A	Dishwashing Room inside of Lunchroom (Former Coat Closet)	Yes	W4	Plaster	White	None	0	N/A	N/A
5250	1	1	104A	Dishwashing Room inside of Lunchroom (Former Coat Closet)	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5250	1	1	104A	Dishwashing Room inside of Lunchroom (Former Coat Closet)	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5250	1	1	106	Lunchroom 106	Yes	W1	Plaster	White	Chipping	5	15	Positive
5250	1	1	106	Lunchroom 106	Yes	W2	Plaster	White	None	0	N/A	N/A
5250	1	1	106	Lunchroom 106	Yes	W3	Plaster	White	Cracking	2	12.3	Positive
5250	1	1	106	Lunchroom 106	Yes	W4	Plaster	White	Cracking	1	11.4	Positive

				Inspection Dates: 09/08/2021-09/10/2021		School District of Philadelphia						
				Name of Inspector: Lionel Ray Wilson		Lead Safe Certification Assessment Report						
				Inspection Company: Viva EHS		Dunbar School						
ULCS#	Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
5250	1	1	106	Lunchroom 106	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5250	1	1	106	Lunchroom 106	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5250	1	1	106	Lunchroom 106	Yes	Radiator	Metal	White	Chipping	5	4.9	Positive
5250	1	1	106A	Dry Food Storage inside of Lunchroom	Yes	W1	Plaster	White	None	0	N/A	N/A
5250	1	1	106A	Dry Food Storage inside of Lunchroom	Yes	W2	Plaster	White	None	0	N/A	N/A
5250	1	1	106A	Dry Food Storage inside of Lunchroom	Yes	W3	Plaster	White	None	0	N/A	N/A
5250	1	1	106A	Dry Food Storage inside of Lunchroom	Yes	W4	Plaster	White	None	0	N/A	N/A
5250	1	1	106A	Dry Food Storage inside of Lunchroom	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5250	1	1	106A	Dry Food Storage inside of Lunchroom	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5250	1	1	105	Classroom 105	Yes	W1	Plaster	Grey	None	0	N/A	N/A
5250	1	1	105	Classroom 105	Yes	W2	Plaster	Grey	None	0	N/A	N/A
5250	1	1	105	Classroom 105	Yes	W3	Plaster	Grey	None	0	N/A	N/A
5250	1	1	105	Classroom 105	Yes	W4	Plaster	Orange	None	0	N/A	N/A
5250	1	1	105	Classroom 105	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5250	1	1	105	Classroom 105	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5250	1	1	105A	Classroom 105 Closet	Yes	W1	Plaster	Grey	None	0	N/A	N/A
5250	1	1	105A	Classroom 105 Closet	Yes	W2	Plaster	Grey	None	0	N/A	N/A
5250	1	1	105A	Classroom 105 Closet	Yes	W3	Plaster	Grey	None	0	N/A	N/A
5250	1	1	105A	Classroom 105 Closet	Yes	W4	Plaster	Grey	None	0	N/A	N/A
5250	1	1	105A	Classroom 105 Closet	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5250	1	1	105A	Classroom 105 Closet	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5250	1	1	105B	Classroom 105 Restroom	Yes	W1	Plaster	Grey	None	0	N/A	N/A
5250	1	1	105B	Classroom 105 Restroom	Yes	W2	Sheetrock	Grey	None	0	N/A	N/A
5250	1	1	105B	Classroom 105 Restroom	Yes	W3	Plaster	Grey	None	0	N/A	N/A
5250	1	1	105B	Classroom 105 Restroom	Yes	W3	Sheetrock	Grey	None	0	N/A	N/A
5250	1	1	105B	Classroom 105 Restroom	Yes	W4	Plaster	Grey	None	0	N/A	N/A
5250	1	1	105B	Classroom 105 Restroom	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5250	1	1	105B	Classroom 105 Restroom	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5250	1	1	105D	Pipe Shaft in Hallway outside of Classroom 105	No	W1	Unpainted	N/A	N/A	N/A	N/A	N/A
5250	1	1	105D	Pipe Shaft in Hallway outside of Classroom 105	No	W2	Unpainted	N/A	N/A	N/A	N/A	N/A
5250	1	1	105D	Pipe Shaft in Hallway outside of Classroom 105	No	W3	Unpainted	N/A	N/A	N/A	N/A	N/A
5250	1	1	105D	Pipe Shaft in Hallway outside of Classroom 105	No	W4	Unpainted	N/A	N/A	N/A	N/A	N/A
5250	1	1	105D	Pipe Shaft in Hallway outside of Classroom 105	No	Ceiling	Unpainted	N/A	N/A	N/A	N/A	N/A
5250	1	1	105D	Pipe Shaft in Hallway outside of Classroom 105	No	Floor	Unpainted	N/A	N/A	N/A	N/A	N/A
5250	1	1	H15	Hallway between Classrooms 105 and 107	Yes	W1	Plaster	White	None	0	N/A	N/A
5250	1	1	H15	Hallway between Classrooms 105 and 107	Yes	W2	N/A	White	N/A	N/A	N/A	N/A
5250	1	1	H15	Hallway between Classrooms 105 and 107	Yes	W3	Plaster	White	None	0	N/A	N/A
5250	1	1	H15	Hallway between Classrooms 105 and 107	Yes	W4	Plaster	White	None	0	N/A	N/A
5250	1	1	H15	Hallway between Classrooms 105 and 107	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5250	1	1	H15	Hallway between Classrooms 105 and 107	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5250	1	1	H15	Hallway between Classrooms 105 and 107	Yes	Pipe	Metal	White	Chipping	2	14.5	Positive
5250	1	1	S12	Stairwell next to Cafeteria	Yes	W1	Plaster	White	None	0	N/A	N/A
5250	1	1	S12	Stairwell next to Cafeteria		Door Frame	Metal	Red	Friction	1	0	Negative
5250	1	1	S12	Stairwell next to Cafeteria		Pushbar	Metal	Grey	Friction	1	0	Negative
5250	1	1	S12	Stairwell next to Cafeteria	Yes	W2	Plaster	White	Cracking	5	23.6	Positive
5250	1	1	S12	Stairwell next to Cafeteria	Yes	W3	Plaster	White	Cracking	3	19.9	Positive

				Inspection Dates: 09/08/2021-09/10/2021		School District of Philadelphia						
				Name of Inspector: Lionel Ray Wilson		Lead Safe Certification Assessment Report						
				Inspection Company: Viva EHS		Dunbar School						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
5250	1	1	S12	Stairwell next to Cafeteria		Door	Metal	Blue	Chipping	2	0	Negative
5250	1	1	S12	Stairwell next to Cafeteria		Pushbar	Metal	Grey	Friction	1	0	Negative
5250	1	1	S12	Stairwell next to Cafeteria		Pipe Jacket	Metal	Tan	Chipping	1	0.1	Negative
5250	1	1	S12	Stairwell next to Cafeteria		Pipe	Metal	White	Chipping	3	0.12	Negative
5250	1	1	S12	Stairwell next to Cafeteria	Yes	W4	Plaster	White	Cracking	6	7.1	Positive
5250	1	1	S12	Stairwell next to Cafeteria		Radiator Grille	Metal	Tan	Flaking	4	0.2	Negative
5250	1	1	S12	Stairwell next to Cafeteria	Yes	Ceiling	Plaster	White	None	0	N/A	N/A
5250	1	1	S12	Stairwell next to Cafeteria	Yes	Ceiling	Concrete	White	None	0	N/A	N/A
5250	1	1	S12	Stairwell next to Cafeteria	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5250	1	1	S12	Stairwell next to Cafeteria	Yes	Newel Post	Metal	Tan	Chipping	2	0.26	Negative
5250	1	1	S12	Stairwell next to Cafeteria	Yes	Baluster	Metal	Tan	Chipping	5	1.9	Positive
5250	1	1	S12	Stairwell next to Cafeteria	Yes	Door	Metal	Blue	Chipping	2	0	Negative
5250	1	1	107	Kindergarten 107	Yes	W1	Plaster	Grey	None	0	N/A	N/A
5250	1	1	107	Kindergarten 107	Yes	W1	Plaster	Orange	None	0	N/A	N/A
5250	1	1	107	Kindergarten 107	Yes	W2	Plaster	Grey	None	0	N/A	N/A
5250	1	1	107	Kindergarten 107	Yes	W3	Plaster	Grey	None	0	N/A	N/A
5250	1	1	107	Kindergarten 107	Yes	W4	Plaster	Grey	None	0	N/A	N/A
5250	1	1	107	Kindergarten 107	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5250	1	1	107	Kindergarten 107	Yes	Ceiling	Plaster	Grey	None	0	N/A	N/A
5250	1	1	107	Kindergarten 107	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5250	1	1	107A	Classroom 107 Coat Closet	Yes	W1	Plaster	Grey	None	0	N/A	N/A
5250	1	1	107A	Classroom 107 Coat Closet	Yes	W2	Plaster	Grey	None	0	N/A	N/A
5250	1	1	107A	Classroom 107 Coat Closet	Yes	W3	Plaster	Grey	None	0	N/A	N/A
5250	1	1	107A	Classroom 107 Coat Closet	Yes	W4	Plaster	Grey	None	0	N/A	N/A
5250	1	1	107A	Classroom 107 Coat Closet	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5250	1	1	107A	Classroom 107 Coat Closet	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5250	1	1	107B-RR	Kindergarten 107 Restroom	Yes	W1	Plaster	Grey	None	0	N/A	N/A
5250	1	1	107B-RR	Kindergarten 107 Restroom	Yes	W2	Plaster	Grey	None	0	N/A	N/A
5250	1	1	107B-RR	Kindergarten 107 Restroom	Yes	W3	Plaster	Grey	None	0	N/A	N/A
5250	1	1	107B-RR	Kindergarten 107 Restroom	Yes	W4	Plaster	Grey	None	0	N/A	N/A
5250	1	1	107B-RR	Kindergarten 107 Restroom	Yes	Ceiling	Plaster	Grey	None	0	N/A	N/A
5250	1	1	107B-RR	Kindergarten 107 Restroom	Yes	Floor	Concrete	Unpainted				
5250	1	1	107C	Kindergarten Classroom 107 Closet	Yes	W1	Plaster	White	Cracking	2	13.2	Positive
5250	1	1	107C	Kindergarten Classroom 107 Closet	Yes	W2	Plaster	White	None	0	N/A	N/A
5250	1	1	107C	Kindergarten Classroom 107 Closet	Yes	W3	Plaster	White	None	0	N/A	N/A
5250	1	1	107C	Kindergarten Classroom 107 Closet	Yes	W4	Plaster	White	None	0	N/A	N/A
5250	1	1	107C	Kindergarten Classroom 107 Closet	Yes	Ceiling	Plaster	Grey	None	0	N/A	N/A
5250	1	1	107C	Kindergarten Classroom 107 Closet	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5250	1	1	108	Classroom 108	Yes	W1	Plaster	Grey	None	0	N/A	N/A
5250	1	1	108	Classroom 108	Yes	W2	Plaster	Grey	None	0	N/A	N/A
5250	1	1	108	Classroom 108	Yes	W3	Plaster	Grey	Chipping	5	14	Positive
5250	1	1	108	Classroom 108	Yes	W4	Plaster	Orange	None	0	N/A	N/A
5250	1	1	108	Classroom 108	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5250	1	1	108	Classroom 108	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5250	1	1	108A	Classroom 108 Restroom	Yes	W1	Plaster	Grey	None	0	N/A	N/A
5250	1	1	108A	Classroom 108 Restroom	Yes	W2	CMU Block Wall	Grey	None	0	N/A	N/A

				Inspection Dates: 09/08/2021-09/10/2021				School District of Philadelphia				
				Name of Inspector: Lionel Ray Wilson				Lead Safe Certification Assessment Report				
				Inspection Company: Viva EHS				Dunbar School				
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
5250	1	1	108A	Classroom 108 Restroom	Yes	W3	Plaster	Grey	None	0	N/A	N/A
5250	1	1	108A	Classroom 108 Restroom	Yes	W4	Plaster	Grey	None	0	N/A	N/A
5250	1	1	108A	Classroom 108 Restroom	Yes	Ceiling	Plaster	White	None	0	N/A	N/A
5250	1	1	108A	Classroom 108 Restroom	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5250	1	1	108B	Classroom 108 Closet	Yes	W1	Plaster	Grey	None	0	N/A	N/A
5250	1	1	108B	Classroom 108 Closet	Yes	W2	Plaster	Grey	None	0	N/A	N/A
5250	1	1	108B	Classroom 108 Closet	Yes	W3	CMU Block Wall	Grey	None	0	N/A	N/A
5250	1	1	108B	Classroom 108 Closet	Yes	W4	Plaster	N/A	N/A	N/A	N/A	N/A
5250	1	1	108B	Classroom 108 Closet	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
5250	1	1	108B	Classroom 108 Closet	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5250	1	1	107B-ST	Speech Therapist	Yes	W1	Plaster	White	None	0	N/A	N/A
5250	1	1	107B-ST	Speech Therapist	Yes	W2	Plaster	White	Hole	2	16.3	Positive
5250	1	1	107B-ST	Speech Therapist	Yes	W3	Plaster	White	None	0	N/A	N/A
5250	1	1	107B-ST	Speech Therapist	Yes	W4	Plaster	White	None	0	N/A	N/A
5250	1	1	107B-ST	Speech Therapist	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5250	1	1	107B-ST	Speech Therapist	Yes	Floor	Concrete	Grey	Cracking	5	0.5	Negative
5250	1	1	110	Special Education	Yes	W1	Plaster	Tan	None	0	N/A	N/A
5250	1	1	110	Special Education	Yes	W2	Plaster	Tan	Chipping	1	34.7	Positive
5250	1	1	110	Special Education	Yes	W3	Plaster	Tan	None	0	N/A	N/A
5250	1	1	110	Special Education	Yes	W4	Plaster	Tan	None	0	N/A	N/A
5250	1	1	110	Special Education	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5250	1	1	110	Special Education	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5250	1	1	110	Special Education	Yes	Radiator	Metal	Tan	Chipping	8	7.8	Positive
5250	1	1	110B	Special Education Classroom Restroom	Yes	W1	Plaster	White	Efflorescence	15	12.7	Positive
5250	1	1	110B	Special Education Classroom Restroom	Yes	W2	Plaster	White	Efflorescence	10	15.8	Positive
5250	1	1	110B	Special Education Classroom Restroom	Yes	W3	Plaster	White	Cracking	10	14.5	Positive
5250	1	1	110B	Special Education Classroom Restroom	Yes	W4	Plaster	White	Cracking	10	12	Positive
5250	1	1	110B	Special Education Classroom Restroom	Yes	Ceiling	Plaster	White	Cracking	15	14	Positive
0.6	1	1	110B	Special Education Classroom Restroom	Yes	Floor	Concrete	Grey	None	0	N/A	N/A
5250	1	2	200A	Large Book Closet next to Girl's Restroom	Yes	W1	Plaster	Blue	Cracking	5	5.7	Positive
5250	1	2	200A	Large Book Closet next to Girl's Restroom	Yes	W2	Plaster	Blue	Cracking	1	7.1	Positive
5250	1	2	200A	Large Book Closet next to Girl's Restroom	Yes	W3	Plaster	Blue	Cracking	3	7.1	Positive
5250	1	2	200A	Large Book Closet next to Girl's Restroom	Yes	W4	Plaster	Blue	Cracking	3	5.7	Positive
5250	1	2	200A	Large Book Closet next to Girl's Restroom	Yes	Ceiling	Plaster	White	None	0	N/A	N/A
5250	1	2	200A	Large Book Closet next to Girl's Restroom	Yes	Floor	Concrete	Unpainted				
5250	1	2	200B	2nd Floor Custodial Closet	No	W1	Plaster	Off-White	Cracking	1	3.1	Positive
5250	1	2	200B	2nd Floor Custodial Closet	No	W2	Plaster	Off-White	Chipping	6	2.6	Positive
5250	1	2	200B	2nd Floor Custodial Closet	No	W3	Plaster	Off-White	Chipping	10	9.6	Positive
5250	1	2	200B	2nd Floor Custodial Closet	No	W4	Plaster	Off-White	Chipping	5	7.1	Positive
5250	1	2	200B	2nd Floor Custodial Closet	No	Ceiling	Plaster	Off-White	Chipping	5	6.1	Positive
5250	1	2	200B	2nd Floor Custodial Closet	No	Floor	Concrete	Unpainted				
5250	1	2	200C	Small Closet next to Large Book Closet next to Girl's Restroom	Yes	W1	Plaster	Off-White	Efflorescence	1	13	Positive
5250	1	2	200C	Small Closet next to Large Book Closet next to Girl's Restroom	Yes	W2	Plaster	Off-White	None	0	N/A	N/A
5250	1	2	200C	Small Closet next to Large Book Closet next to Girl's Restroom	Yes	W3	Plaster	Off-White	Flaking	30	12.1	Positive

				Inspection Dates: 09/08/2021-09/10/2021			School District of Philadelphia					
				Name of Inspector: Lionel Ray Wilson			Lead Safe Certification Assessment Report					
				Inspection Company: Viva EHS			Dunbar School					
ULCS#	Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
5250	1	2	200C	Small Closet next to Large Book Closet next to Girl's Restroom	Yes	W4	Plaster	Off-White	Efflorescence	10	15.1	Positive
5250	1	2	200C	Small Closet next to Large Book Closet next to Girl's Restroom	Yes	Ceiling	Plaster	Off-White	Flaking	3	11.5	Positive
5250	1	2	200C	Small Closet next to Large Book Closet next to Girl's Restroom	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5250	1	2	200D	Small Closet next to Stairwell next to Classroom 202	Yes	W1	Plaster	Off-White	Cracking	3	11.5	Positive
5250	1	2	200D	Small Closet next to Stairwell next to Classroom 202	Yes	W2	Plaster	Off-White	Flaking	5	11.6	Positive
5250	1	2	200D	Small Closet next to Stairwell next to Classroom 202	Yes	W3	Plaster	Off-White	Chipping	30	10.6	Positive
5250	1	2	200D	Small Closet next to Stairwell next to Classroom 202	Yes	W4	Plaster	Off-White	Cracking	2	10.8	Positive
5250	1	2	200D	Small Closet next to Stairwell next to Classroom 202	Yes	Ceiling	Plaster	Off-White	Hole	3	11.3	Positive
5250	1	2	200D	Small Closet next to Stairwell next to Classroom 202	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5250	1	2	200-PC	2nd Floor Pipe Chase in Girls Restroom	No	W1	Unpainted	N/A	N/A	N/A	N/A	N/A
5250	1	2	200-PC	2nd Floor Pipe Chase in Girls Restroom	No	W2	Unpainted	N/A	N/A	N/A	N/A	N/A
5250	1	2	200-PC	2nd Floor Pipe Chase in Girls Restroom	No	W3	Unpainted	N/A	N/A	N/A	N/A	N/A
5250	1	2	200-PC	2nd Floor Pipe Chase in Girls Restroom	No	W4	Unpainted	N/A	N/A	N/A	N/A	N/A
5250	1	2	200-PC	2nd Floor Pipe Chase in Girls Restroom	No	Ceiling	Unpainted	N/A	N/A	N/A	N/A	N/A
5250	1	2	200-PC	2nd Floor Pipe Chase in Girls Restroom	No	Floor	Unpainted	N/A	N/A	N/A	N/A	N/A
5250	1	2	200	2nd Floor Girl's Restroom	Yes	W1	Plaster	White	None	0	N/A	N/A
5250	1	2	200	2nd Floor Girl's Restroom	Yes	W2	Plaster	White	Cracking	1	9.5	Positive
5250	1	2	200	2nd Floor Girl's Restroom	Yes	W3	Plaster	White	None	0	N/A	N/A
5250	1	2	200	2nd Floor Girl's Restroom	Yes	W4	Plaster	White	None	0	N/A	N/A
5250	1	2	200	2nd Floor Girl's Restroom	Yes	W4	CMU Block Wall	White	Chipping	1	12.4	Positive
5250	1	2	200	2nd Floor Girl's Restroom	Yes	Ceiling	Plaster	White	None	0	N/A	N/A
5250	1	2	200	2nd Floor Girl's Restroom	Yes	Floor	Concrete	Grey	Cracking	35	13.7	Positive
5250	1	2	200	2nd Floor Girl's Restroom	Yes	Radiator	Metal	Off-White	Chipping	7	7.6	Positive
5250	1	2	201	Classroom 201	Yes	W1	Plaster	Grey	None	0	N/A	N/A
5250	1	2	201	Classroom 201	Yes	W2	Plaster	Grey	None	0	N/A	N/A
5250	1	2	201	Classroom 201	Yes	W3	Plaster	Grey	None	0	N/A	N/A
5250	1	2	201	Classroom 201	Yes	W4	Plaster	Grey	None	0	N/A	N/A
5250	1	2	201	Classroom 201	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5250	1	2	201	Classroom 201	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5250	1	2	201A	Classroom 201 Coat Closet	Yes	W1	Plaster	Grey	None	0	N/A	N/A
5250	1	2	201A	Classroom 201 Coat Closet	Yes	W2	Plaster	Grey	Cracking	4	8.2	Positive
5250	1	2	201A	Classroom 201 Coat Closet	Yes	W3	Plaster	Grey	None	0	N/A	N/A
5250	1	2	201A	Classroom 201 Coat Closet	Yes	W4	Plaster	Grey	None	0	N/A	N/A
5250	1	2	201A	Classroom 201 Coat Closet	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5250	1	2	201A	Classroom 201 Coat Closet	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5250	1	2	S26	Stairwell next to Classroom 202	Yes	W1	Sheetrock	White	None	0	N/A	N/A
5250	1	2	S26	Stairwell next to Classroom 202	Yes	W2	Plaster	White	Cracking	1	9	Positive
5250	1	2	S26	Stairwell next to Classroom 202	Yes	W3	Plaster	White	Cracking	3	8.1	Positive
5250	1	2	S26	Stairwell next to Classroom 202		Pipe	Metal	Tan	Chipping	1	0.1	Negative
5250	1	2	S26	Stairwell next to Classroom 202	Yes	W4	Plaster	White	Cracking	1	8.1	Positive
5250	1	2	S26	Stairwell next to Classroom 202	Yes	Ceiling	Plaster	White	Chipping	5	10	Positive
5250	1	2	S26	Stairwell next to Classroom 202	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5250	1	2	S26	Stairwell next to Classroom 202	Yes	Baluster	Metal	Tan	Chipping	2	3.3	Positive
5250	1	2	S26	Stairwell next to Classroom 202	Yes	Newel Post	Metal	Tan	Chipping	5	8	Positive

				Inspection Dates: 09/08/2021-09/10/2021		School District of Philadelphia						
				Name of Inspector: Lionel Ray Wilson		Lead Safe Certification Assessment Report						
				Inspection Company: Viva EHS		Dunbar School						
ULCS#	Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
5250	1	2	S26	Stairwell next to Classroom 202	Yes	Radiator	Metal	White	None	0	N/A	N/A
5250	1	2	H27	2nd Floor Hallway	Yes	W1	Plaster	White	Cracking	2	9.7	Positive
5250	1	2	H27	2nd Floor Hallway		Pipe	Metal	Tan	Chipping	1	0.4	Negative
5250	1	2	H27	2nd Floor Hallway	Yes	W2	Plaster	White	Chipping	2	12	Positive
5250	1	2	H27	2nd Floor Hallway	Yes	W3	Plaster	White	Cracking	2	7.4	Positive
5250	1	2	H27	2nd Floor Hallway	Yes	W4	Plaster	White	Cracking	1	7	Positive
5250	1	2	H27	2nd Floor Hallway	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5250	1	2	H27	2nd Floor Hallway	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5250	1	2	H27	2nd Floor Hallway	Yes	Pipe	Metal	Tan	Chipping	5	9.3	Positive
5250	1	2	H27	2nd Floor Hallway	Yes	Pipe	Metal	White	Chipping	5	10	Positive
5250	1	2	202	Classroom 202	Yes	W1	Plaster	Grey	Cracking	1	10.1	Positive
5250	1	2	202	Classroom 202	Yes	W2	Plaster	Grey	None	0	N/A	N/A
5250	1	2	202	Classroom 202	Yes	W3	Plaster	Grey	None	0	N/A	N/A
5250	1	2	202	Classroom 202	Yes	W4	Sheetrock	Grey	Flaking	1	14.2	Positive
5250	1	2	202	Classroom 202	Yes	W4	Plaster	Grey	None	0	N/A	N/A
5250	1	2	202	Classroom 202	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5250	1	2	202	Classroom 202	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5250	1	2	202	Classroom 202	Yes	Radiator	Metal	Grey	Chipping	3	8.8	Positive
5250	1	2	202A	Classroom 202 Coat Closet	Yes	W1	Plaster	Grey	None	0	N/A	N/A
5250	1	2	202A	Classroom 202 Coat Closet	Yes	W2	Plaster	Grey	None	0	N/A	N/A
5250	1	2	202A	Classroom 202 Coat Closet	Yes	W3	Plaster	Grey	None	0	N/A	N/A
5250	1	2	202A	Classroom 202 Coat Closet	Yes	W4	Plaster	Grey	Efflorescence	12	8.5	Positive
5250	1	2	202A	Classroom 202 Coat Closet	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5250	1	2	202A	Classroom 202 Coat Closet	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5250	1	2	203	Classroom 203	Yes	W1	Plaster	Grey	None	0	N/A	N/A
5250	1	2	203	Classroom 203	Yes	W2	Plaster	Grey	None	0	N/A	N/A
5250	1	2	203	Classroom 203	Yes	W3	Plaster	Grey	None	0	N/A	N/A
5250	1	2	203	Classroom 203	Yes	W4	Plaster	Grey	None	0	N/A	N/A
5250	1	2	203	Classroom 203	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5250	1	2	203	Classroom 203	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5250	1	2	203	Classroom 203	Yes	Radiator	Metal	Grey	None	0	N/A	N/A
5250	1	2	203A	Classroom 203 Coat Closet	Yes	W1	Plaster	Grey	None	0	N/A	N/A
5250	1	2	203A	Classroom 203 Coat Closet	Yes	W2	Plaster	Grey	None	0	N/A	N/A
5250	1	2	203A	Classroom 203 Coat Closet	Yes	W3	Plaster	Grey	None	0	N/A	N/A
5250	1	2	203A	Classroom 203 Coat Closet	Yes	W4	Plaster	Grey	None	0	N/A	N/A
5250	1	2	203A	Classroom 203 Coat Closet	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5250	1	2	203A	Classroom 203 Coat Closet	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5250	1	2	204	Classroom 204	Yes	W1	Plaster	Grey	Chipping	1	8.6	Positive
5250	1	2	204	Classroom 204	Yes	W2	Sheetrock	Grey	Flaking	3	12.9	Positive
5250	1	2	204	Classroom 204	Yes	W3	Plaster	Grey	None	0	N/A	N/A
5250	1	2	204	Classroom 204	Yes	W4	Sheetrock	Grey	Flaking	1	12.4	Positive
5250	1	2	204	Classroom 204	Yes	W4	Plaster	Grey	None	0	N/A	N/A
5250	1	2	204	Classroom 204	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5250	1	2	204	Classroom 204	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5250	1	2	204A	Classroom 204 Coat Closet	Yes	W1	Plaster	Grey	None	0	N/A	N/A
5250	1	2	204A	Classroom 204 Coat Closet	Yes	W2	Plaster	Grey	None	0	N/A	N/A

				Inspection Dates: 09/08/2021-09/10/2021		School District of Philadelphia						
				Name of Inspector: Lionel Ray Wilson		Lead Safe Certification Assessment Report						
				Inspection Company: Viva EHS		Dunbar School						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
5250	1	2	204A	Classroom 204 Coat Closet	Yes	W3	Plaster	Grey	None	0	N/A	N/A
5250	1	2	204A	Classroom 204 Coat Closet	Yes	W4	Plaster	Grey	Chipping	2	9	Positive
5250	1	2	204A	Classroom 204 Coat Closet	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5250	1	2	204A	Classroom 204 Coat Closet	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5250	1	2	205	Classroom 205	Yes	W1	Plaster	Grey	None	0	N/A	N/A
5250	1	2	205	Classroom 205	Yes	W2	Plaster	Grey	None	0	N/A	N/A
5250	1	2	205	Classroom 205	Yes	W3	Plaster	Grey	Cracking	2	14.4	Positive
5250	1	2	205	Classroom 205	Yes	W4	Plaster	Grey	None	0	N/A	N/A
5250	1	2	205	Classroom 205	Yes	W4	Sheetrock	Grey	None	0	N/A	N/A
5250	1	2	205	Classroom 205	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5250	1	2	205	Classroom 205	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5250	1	2	205A	Classroom 205 Coat Closet	Yes	W1	Plaster	Grey	None	0	N/A	N/A
5250	1	2	205A	Classroom 205 Coat Closet	Yes	W2	Plaster	Grey	Chipping	1	8.4	Positive
5250	1	2	205A	Classroom 205 Coat Closet	Yes	W3	Plaster	Grey	None	0	N/A	N/A
5250	1	2	205A	Classroom 205 Coat Closet	Yes	W4	Plaster	Grey	Cracking	1	6.7	Positive
5250	1	2	205A	Classroom 205 Coat Closet	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5250	1	2	205A	Classroom 205 Coat Closet	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5250	1	2	205D	Pipe Shaft in Hallway outside of Classroom 205	No	W1	Unpainted	N/A	N/A	N/A	N/A	N/A
5250	1	2	205D	Pipe Shaft in Hallway outside of Classroom 205	No	W2	Unpainted	N/A	N/A	N/A	N/A	N/A
5250	1	2	205D	Pipe Shaft in Hallway outside of Classroom 205	No	W3	Unpainted	N/A	N/A	N/A	N/A	N/A
5250	1	2	205D	Pipe Shaft in Hallway outside of Classroom 205	No	W4	Unpainted	N/A	N/A	N/A	N/A	N/A
5250	1	2	205D	Pipe Shaft in Hallway outside of Classroom 205	No	Ceiling	Unpainted	N/A	N/A	N/A	N/A	N/A
5250	1	2	205D	Pipe Shaft in Hallway outside of Classroom 205	No	Floor	Unpainted	N/A	N/A	N/A	N/A	N/A
5250	1	2	206	Classroom 206	Yes	W1	Plaster	Grey	Chipping	1	8	Positive
5250	1	2	206	Classroom 206	Yes	W2	Sheetrock	Grey	None	0	N/A	N/A
5250	1	2	206	Classroom 206	Yes	W3	Plaster	Grey	None	0	N/A	N/A
5250	1	2	206	Classroom 206	Yes	W4	Plaster	Grey	None	0	N/A	N/A
5250	1	2	206	Classroom 206	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5250	1	2	206	Classroom 206	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5250	1	2	206	Classroom 206	Yes	Radiator	Metal	Grey	Chipping	3	3.4	Positive
5250	1	2	206A	Classroom 206 Coat Closet	Yes	W1	Plaster	Grey	None	0	N/A	N/A
5250	1	2	206A	Classroom 206 Coat Closet	Yes	W2	Plaster	Grey	None	0	N/A	N/A
5250	1	2	206A	Classroom 206 Coat Closet	Yes	W3	Plaster	Grey	None	0	N/A	N/A
5250	1	2	206A	Classroom 206 Coat Closet	Yes	W4	Plaster	Grey	None	0	N/A	N/A
5250	1	2	206A	Classroom 206 Coat Closet	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5250	1	2	206A	Classroom 206 Coat Closet	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5250	1	2	205B-PC	2nd Floor Pipe Chase in Boys Restroom	No	W1	Unpainted	N/A	N/A	N/A	N/A	N/A
5250	1	2	205B-PC	2nd Floor Pipe Chase in Boys Restroom	No	W2	Unpainted	N/A	N/A	N/A	N/A	N/A
5250	1	2	205B-PC	2nd Floor Pipe Chase in Boys Restroom	No	W3	Unpainted	N/A	N/A	N/A	N/A	N/A
5250	1	2	205B-PC	2nd Floor Pipe Chase in Boys Restroom	No	W4	Unpainted	N/A	N/A	N/A	N/A	N/A
5250	1	2	205B-PC	2nd Floor Pipe Chase in Boys Restroom	No	Ceiling	Unpainted	N/A	N/A	N/A	N/A	N/A
5250	1	2	205B-PC	2nd Floor Pipe Chase in Boys Restroom	No	Floor	Unpainted	N/A	N/A	N/A	N/A	N/A
5250	1	2	205B	2nd Floor Boys Restroom	Yes	W1	Plaster	White	Cracking	8	8.1	Positive
5250	1	2	205B	2nd Floor Boys Restroom	Yes	W2	Plaster	White	Cracking	25	13.7	Positive
5250	1	2	205B	2nd Floor Boys Restroom	Yes	W3	Plaster	White	Cracking	2	9.3	Positive
5250	1	2	205B	2nd Floor Boys Restroom	Yes	W4	Plaster	White	Cracking	2	8.2	Positive

				Inspection Dates: 09/08/2021-09/10/2021		School District of Philadelphia						
				Name of Inspector: Lionel Ray Wilson		Lead Safe Certification Assessment Report						
				Inspection Company: Viva EHS		Dunbar School						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
					Yes	W4	CMU Block Wall	White	Chipping	3	11.3	Positive
5250	1	2	205B	2nd Floor Boys Restroom								
5250	1	2	205B	2nd Floor Boys Restroom	Yes	Ceiling	Plaster	White	Flaking	40	7.9	Positive
5250	1	2	205B	2nd Floor Boys Restroom	Yes	Door	Metal	Pink	Rust	3	5.8	Positive
5250	1	2	205B	2nd Floor Boys Restroom	Yes	Floor	Concrete	Grey	Cracking	1	15.3	Positive
5250	1	2	205C	Health Room	Yes	W1	Plaster	White	Cracking	1	8.5	Positive
5250	1	2	205C	Health Room	Yes	W2	Plaster	White	None	0	N/A	N/A
5250	1	2	205C	Health Room	Yes	W3	Plaster	White	Cracking	3	8	Positive
5250	1	2	205C	Health Room	Yes	W4	Plaster	White	None	0	N/A	N/A
5250	1	2	205C	Health Room	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5250	1	2	205C	Health Room	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5250	1	2	205C	Health Room	Yes	Window Sill	Wood	White	Cracking	1	9.7	Positive
5250	1	2	205C	Health Room	Yes	Radiator	Metal	White	Chipping	1	7.9	Positive
5250	1	2	205C	Health Room	Yes	Shelf	Wood	Pink	Chipping	2	7.7	Positive
5250	1	2	205C	Health Room	Yes	Baseboard	Wood	Pink	Chipping	5	22.6	Positive
5250	1	2	S22	Stairwell next to Classroom 206	Yes	W1	Sheetrock	White	Cracking	1	12.9	Positive
5250	1	2	S22	Stairwell next to Classroom 206	Yes	W2	Plaster	White	Cracking	30	7.9	Positive
5250	1	2	S22	Stairwell next to Classroom 206	Yes	W3	Plaster	White	Cracking	10	8.8	Positive
5250	1	2	S22	Stairwell next to Classroom 206		Radiator	Metal	Tan	Chipping	4	2.1	Positive
5250	1	2	S22	Stairwell next to Classroom 206		Pipe	Metal	Tan	Chipping	1	0.25	Negative
5250	1	2	S22	Stairwell next to Classroom 206	Yes	W4	Plaster	White	Chipping	5	8	Positive
5250	1	2	S22	Stairwell next to Classroom 206	Yes	Ceiling	Plaster	White	None	0	N/A	N/A
5250	1	2	S22	Stairwell next to Classroom 206	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5250	1	2	S22	Stairwell next to Classroom 206	Yes	Radiator	Metal	Tan	Chipping	2	7.4	Positive
5250	1	2	S22	Stairwell next to Classroom 206	Yes	Newel Post	Metal	Tan	Chipping	5	9.5	Positive
5250	1	2	S22	Stairwell next to Classroom 206	Yes	Baluster	Metal	Tan	Chipping	3	3.1	Positive
5250	1	2	207	Art Classroom 207	Yes	W1	Plaster	White	None	0	N/A	N/A
5250	1	2	207	Art Classroom 207	Yes	W2	Plaster	White	Chipping	2	14.4	Positive
5250	1	2	207	Art Classroom 207	Yes	W3	Plaster	White	Efflorescence	3	9.2	Positive
5250	1	2	207	Art Classroom 207	Yes	W4	Plaster	White	Cracking	1	8	Positive
5250	1	2	207	Art Classroom 207	Yes	Radiator	Metal	White	Chipping	5	7.7	Positive
5250	1	2	207	Art Classroom 207	Yes	Sink	Ceramic	White	Chipping	2	6.6	Positive
5250	1	2	207	Art Classroom 207	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5250	1	2	207	Art Classroom 207	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5250	1	2	207A	Art Classroom 207 Coat Closet	Yes	W1	No Access	No Access	No Access	No Access	No Access	No Access
5250	1	2	207A	Art Classroom 207 Coat Closet	Yes	W2	No Access	No Access	No Access	No Access	No Access	No Access
5250	1	2	207A	Art Classroom 207 Coat Closet	Yes	W3	No Access	No Access	No Access	No Access	No Access	No Access
5250	1	2	207A	Art Classroom 207 Coat Closet	Yes	W4	No Access	No Access	No Access	No Access	No Access	No Access
5250	1	2	207A	Art Classroom 207 Coat Closet	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
5250	1	2	207A	Art Classroom 207 Coat Closet	Yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access
5250	1	2	207B	Classroom 207 Restroom	Yes	W1	Plaster	White	Cracking	5	12.7	Positive
5250	1	2	207B	Classroom 207 Restroom	Yes	W2	Plaster	White	Chipping	1	13.4	Positive

				Inspection Dates: 09/08/2021-09/10/2021				School District of Philadelphia				
				Name of Inspector: Lionel Ray Wilson				Lead Safe Certification Assessment Report				
				Inspection Company: Viva EHS				Dunbar School				
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
5250	1	2	207B	Classroom 207 Restroom	Yes	W3	Plaster	White	Efflorescence	40	15.1	Positive
5250	1	2	207B	Classroom 207 Restroom	Yes	W4	Plaster	White	Efflorescence	25	8	Positive
5250	1	2	207B	Classroom 207 Restroom	Yes	Ceiling	Plaster	White	Flaking	10	13.8	Positive
5250	1	2	207B	Classroom 207 Restroom	Yes	Floor	Concrete	Grey	Cracking	10	14.6	Positive
5250	1	2	207B	Classroom 207 Restroom	Yes	Pipe	Metal	White	Cracking	10	5.5	Positive
5250	1	2	207C	Classroom 207 Closet	Yes	W1	Plaster	White	Chipping	5	4.1	Positive
5250	1	2	207C	Classroom 207 Closet	Yes	W2	Plaster	White	Efflorescence	30	8	Positive
5250	1	2	207C	Classroom 207 Closet	Yes	W3	Plaster	White	Efflorescence	70	8.4	Positive
5250	1	2	207C	Classroom 207 Closet	Yes	W4	Plaster	White	Flaking	3	8.2	Positive
5250	1	2	207C	Classroom 207 Closet	Yes	Ceiling	Plaster	White	Flaking	40	5.6	Positive
5250	1	2	207C	Classroom 207 Closet	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5250	1	2	208	Classroom 208	Yes	W1	Plaster	Grey	None	0	N/A	N/A
5250	1	2	208	Classroom 208	Yes	W2	Plaster	Grey	Chipping	2	13.7	Positive
5250	1	2	208	Classroom 208	Yes	W3	Plaster	Grey	Chipping	1	9.7	Positive
5250	1	2	208	Classroom 208	Yes	W4	Plaster	Grey	Chipping	1	9.3	Positive
5250	1	2	208	Classroom 208	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5250	1	2	208	Classroom 208	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5250	1	2	208	Classroom 208	Yes	Radiator	Metal	Silver	Chipping	1	1.6	Positive
5250	1	2	208A	Classroom 208 Coat Closet	Yes	W1	Plaster	Grey	None	0	N/A	N/A
5250	1	2	208A	Classroom 208 Coat Closet	Yes	W2	Plaster	Grey	None	0	N/A	N/A
5250	1	2	208A	Classroom 208 Coat Closet	Yes	W3	Plaster	Grey	None	0	N/A	N/A
5250	1	2	208A	Classroom 208 Coat Closet	Yes	W4	Plaster	Grey	Cracking	1	7.5	Positive
5250	1	2	208A	Classroom 208 Coat Closet	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5250	1	2	208A	Classroom 208 Coat Closet	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5250	1	2	210	Counselor's Office	Yes	W1	Plaster	White	Chipping	2	7.5	Positive
5250	1	2	210	Counselor's Office	Yes	W2	Plaster	White	Cracking	1	7.1	Positive
5250	1	2	210	Counselor's Office	Yes	W3	Plaster	White	Chipping	1	8.7	Positive
5250	1	2	210	Counselor's Office	Yes	W4	Plaster	White	Flaking	12	7.9	Positive
5250	1	2	210	Counselor's Office	Yes	Partition Wall	Wood	Tan	Chipping	3	27	Positive
5250	1	2	210	Counselor's Office	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5250	1	2	210	Counselor's Office	Yes	Radiator	Metal	White	Chipping	8	8.3	Positive
5250	1	2	210	Counselor's Office	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5250	1	2	210A	Counselor's Office Restroom	Yes	W1	Plaster	White	Cracking	10	1.4	Positive
5250	1	2	210A	Counselor's Office Restroom	Yes	W2	Plaster	White	Cracking	7	12.8	Positive
5250	1	2	210A	Counselor's Office Restroom	Yes	W3	Plaster	White	Efflorescence	40	8.3	Positive
5250	1	2	210A	Counselor's Office Restroom	Yes	W4	Plaster	White	Cracking	8	8.4	Positive
5250	1	2	210A	Counselor's Office Restroom	Yes	Ceiling	Plaster	White	Efflorescence	80	14	Positive
5250	1	2	210A	Counselor's Office Restroom	Yes	Floor	Concrete	Grey	Chipping	1	14.9	Positive
5250	1	2	210A	Counselor's Office Restroom	Yes	Radiator	Metal	White	Chipping	6	6.7	Positive
5250	1	2	208B	IT MDF Room outside Counselor's Office	No	W1	Plaster	Tan	Cracking	2	10.1	Positive
5250	1	2	208B	IT MDF Room outside Counselor's Office	No	W2	Plaster	Tan	Flaking	10	7.6	Positive
5250	1	2	208B	IT MDF Room outside Counselor's Office	No	W3	Plaster	Tan	Flaking	40	7.8	Positive
5250	1	2	208B	IT MDF Room outside Counselor's Office	No	W4	Plaster	Tan	Flaking	10	9.2	Positive
5250	1	2	208B	IT MDF Room outside Counselor's Office	No	Ceiling	Plaster	Tan	Chipping	20	7.5	Positive
5250	1	2	208B	IT MDF Room outside Counselor's Office	No	Floor	Concrete	Unpainted				
5250	1	3	300B	Teacher's Lounge	Yes	W1	Plaster	Blue	None	0	N/A	N/A

				Inspection Dates: 09/08/2021-09/10/2021		School District of Philadelphia						
				Name of Inspector: Lionel Ray Wilson		Lead Safe Certification Assessment Report						
				Inspection Company: Viva EHS		Dunbar School						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
5250	1	3	300B	Teacher's Lounge	Yes	W2	Plaster	Blue	None	0	N/A	N/A
5250	1	3	300B	Teacher's Lounge	Yes	W3	Plaster	Blue	Efflorescence	2	17.5	Positive
5250	1	3	300B	Teacher's Lounge	Yes	W4	Plaster	Blue	Chipping	1	34.4	Positive
5250	1	3	300B	Teacher's Lounge	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5250	1	3	300B	Teacher's Lounge	Yes	Radiator	Metal	Blue	Chipping	1	12	Positive
5250	1	3	300B	Teacher's Lounge	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5250	1	3	300C	Teacher's Lounge Kitchen	Yes	W1	Plaster	White	None	0	N/A	N/A
5250	1	3	300C	Teacher's Lounge Kitchen	Yes	W2	Plaster	White	Chipping	2	14.2	Positive
5250	1	3	300C	Teacher's Lounge Kitchen	Yes	W3	Plaster	White	Chipping	5	14	Positive
5250	1	3	300C	Teacher's Lounge Kitchen	Yes	W4	Plaster	White	Chipping	3	17.5	Positive
5250	1	3	300C	Teacher's Lounge Kitchen	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5250	1	3	300C	Teacher's Lounge Kitchen	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5250	1	3	300D	Teacher's Lounge Kitchen Closet	Yes	W1	No Access	No Access	No Access	No Access	No Access	No Access
5250	1	3	300D	Teacher's Lounge Kitchen Closet	Yes	W2	No Access	No Access	No Access	No Access	No Access	No Access
5250	1	3	300D	Teacher's Lounge Kitchen Closet	Yes	W3	No Access	No Access	No Access	No Access	No Access	No Access
5250	1	3	300D	Teacher's Lounge Kitchen Closet	Yes	W4	No Access	No Access	No Access	No Access	No Access	No Access
5250	1	3	300D	Teacher's Lounge Kitchen Closet	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
5250	1	3	300D	Teacher's Lounge Kitchen Closet	Yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access
5250	1	3	309	Classroom 309	Yes	W1	Plaster	Multi	Cracking	1	6.8	Positive
5250	1	3	309	Classroom 309	Yes	W2	Plaster	White	Cracking	3	7.4	Positive
5250	1	3	309	Classroom 309	Yes	W3	Plaster	White	None	0	N/A	N/A
5250	1	3	309	Classroom 309	Yes	W4	Plaster	Multi	None	0	N/A	N/A
5250	1	3	309	Classroom 309	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5250	1	3	309	Classroom 309	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5250	1	3	309	Classroom 309	Yes	Radiator	Metal	White	Chipping	3	1.4	Positive
5250	1	3	309A	Classroom 309 Large Closet	Yes	W1	Wood Partition	N/A	N/A	N/A	N/A	N/A
5250	1	3	309A	Classroom 309 Large Closet	Yes	W2	Plaster	White	Cracking	12	14.4	Positive
5250	1	3	309A	Classroom 309 Large Closet	Yes	W3	Plaster	White	Chipping	70	20.7	Positive
5250	1	3	309A	Classroom 309 Large Closet	Yes	W4	Plaster	White	Cracking	6	17.6	Positive
5250	1	3	309A	Classroom 309 Large Closet	Yes	Ceiling	Plaster	White	Efflorescence	15	14.1	Positive
5250	1	3	309A	Classroom 309 Large Closet	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5250	1	3	309B	Classroom 309 Small Closet	Yes	W1	Plaster	White	Cracking	5	15	Positive
5250	1	3	309B	Classroom 309 Small Closet	Yes	W2	Plaster	White	Cracking	10	11	Positive
5250	1	3	309B	Classroom 309 Small Closet	Yes	W3	Plaster	White	Cracking	15	9.1	Positive
5250	1	3	309B	Classroom 309 Small Closet	Yes	W4	Plaster	White	Cracking	20	0.21	Negative
5250	1	3	309B	Classroom 309 Small Closet	Yes	Ceiling	Plaster	White	Efflorescence	10	14	Positive
5250	1	3	309B	Classroom 309 Small Closet	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5250	1	3	300	Computer Lab	Yes	W1	Plaster	White	Chipping	5	14.4	Positive
5250	1	3	300	Computer Lab	Yes	W2	Plaster	White	Cracking	2	22.8	Positive
5250	1	3	300	Computer Lab	Yes	W3	Plaster	White	Chipping	5	8.4	Positive
5250	1	3	300	Computer Lab	Yes	W4	Plaster	White	Cracking	2	22.6	Positive
5250	1	3	300	Computer Lab	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5250	1	3	300	Computer Lab	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5250	1	3	300	Computer Lab	Yes	Radiator	Metal	White	Cracking	2	0.23	Negative
5250	1	3	300A	Computer Lab 300 Coat Closet	Yes	W1	Plaster	White	None	0	N/A	N/A
5250	1	3	300A	Computer Lab 300 Coat Closet	Yes	W2	Plaster	White	Cracking	25	17.8	Positive

				Inspection Dates: 09/08/2021-09/10/2021		School District of Philadelphia						
				Name of Inspector: Lionel Ray Wilson		Lead Safe Certification Assessment Report						
				Inspection Company: Viva EHS		Dunbar School						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
5250	1	3	300A	Computer Lab 300 Coat Closet	Yes	W3	Plaster	White	Cracking	5	18.6	Positive
5250	1	3	300A	Computer Lab 300 Coat Closet	Yes	W4	Plaster	White	Flaking	7	8.8	Positive
5250	1	3	300A	Computer Lab 300 Coat Closet	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5250	1	3	300A	Computer Lab 300 Coat Closet	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5250	1	3	301C	Closet next to Girl's Restroom	No	W1	Plaster	Off-White	Cracking	2	6.5	Positive
5250	1	3	301C	Closet next to Girl's Restroom	No	W2	Plaster	Off-White	Cracking	3	8.2	Positive
5250	1	3	301C	Closet next to Girl's Restroom	No	W3	Plaster	Off-White	Cracking	2	10.5	Positive
5250	1	3	301C	Closet next to Girl's Restroom	No	W4	Plaster	Off-White	Cracking	5	8.8	Positive
5250	1	3	301C	Closet next to Girl's Restroom	No	Ceiling	Plaster	Off-White	None	N/A	N/A	N/A
5250	1	3	301C	Closet next to Girl's Restroom	No	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5250	1	3		3rd Floor Girl's Restroom	Yes	W1	Plaster	White	None	0	N/A	N/A
5250	1	3		3rd Floor Girl's Restroom	Yes	W2	Plaster	White	Cracking	30	13.6	Positive
5250	1	3		3rd Floor Girl's Restroom	Yes	W3	Plaster	White	None	0	N/A	N/A
5250	1	3		3rd Floor Girl's Restroom	Yes	W4	Plaster	White	None	0	N/A	N/A
5250	1	3		3rd Floor Girl's Restroom	Yes	Ceiling	Plaster	White	Cracking	5	11	Positive
5250	1	3		3rd Floor Girl's Restroom	Yes	Floor	Concrete	Grey	Cracking	10	0	Negative
5250	1	3		3rd Floor Girl's Restroom	Yes	Radiator	Metal	Pink	Chipping	1	0.1	Negative
5250	1	3	301C	3rd Floor Hallways	Yes	W1	Plaster	White	Chipping	15	13.6	Positive
5250	1	3	301C	3rd Floor Hallways	Yes	W2	Plaster	White	Cracking	1	13.9	Positive
5250	1	3	301C	3rd Floor Hallways	Yes	W3	Plaster	White	Cracking	4	14.2	Positive
5250	1	3	301C	3rd Floor Hallways	Yes	W4	Plaster	White	Cracking	1	20.8	Positive
5250	1	3	301C	3rd Floor Hallways	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5250	1	3	301C	3rd Floor Hallways	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5250	1	3	301C	3rd Floor Hallways	Yes	Radiator	Metal	White	Chipping	3	0.02	Negative
5250	1	3	301C	3rd Floor Hallways	Yes	Pipe	Metal	White	Chipping	2	1.3	Positive
5250	1	3	301D	3rd Floor Custodial Closet	No	W1	Plaster	Green	Cracking	2	20.5	Positive
5250	1	3	301D	3rd Floor Custodial Closet	No	W2	Plaster	Green	Cracking	4	18.7	Positive
5250	1	3	301D	3rd Floor Custodial Closet	No	W3	Plaster	Green	Cracking	10	11.8	Positive
5250	1	3	301D	3rd Floor Custodial Closet	No	W4	Plaster	Green	Cracking	2	7.7	Positive
5250	1	3	301D	3rd Floor Custodial Closet	No	Ceiling	Plaster	White	Cracking	1	12.1	Positive
5250	1	3	301D	3rd Floor Custodial Closet	No	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5250	1	3	301B-PC	3rd Floor Girls Restroom Pipe Chase	No	W1	Unpainted	N/A	N/A	N/A	N/A	N/A
5250	1	3	301B-PC	3rd Floor Girls Restroom Pipe Chase	No	W2	Unpainted	N/A	N/A	N/A	N/A	N/A
5250	1	3	301B-PC	3rd Floor Girls Restroom Pipe Chase	No	W3	Unpainted	N/A	N/A	N/A	N/A	N/A
5250	1	3	301B-PC	3rd Floor Girls Restroom Pipe Chase	No	W4	Unpainted	N/A	N/A	N/A	N/A	N/A
5250	1	3	301B-PC	3rd Floor Girls Restroom Pipe Chase	No	Ceiling	Unpainted	N/A	N/A	N/A	N/A	N/A
5250	1	3	301B-PC	3rd Floor Girls Restroom Pipe Chase	No	Floor	Unpainted	N/A	N/A	N/A	N/A	N/A
5250	1	3	301	Classroom 301	Yes	W1	Plaster	White	Cracking	2	20.9	Positive
5250	1	3	301	Classroom 301	Yes	W2	Plaster	White	Cracking	4	5.1	Positive
5250	1	3	301	Classroom 301	Yes	W3	Plaster	White	Cracking	3	5.8	Positive
5250	1	3	301	Classroom 301	Yes	W4	Plaster	White	Cracking	1	19.1	Positive
5250	1	3	301	Classroom 301	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5250	1	3	301	Classroom 301	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5250	1	3	301	Classroom 301	Yes	Radiator	Metal	White	Chipping	10	0	Negative
5250	1	3	301	Classroom 301	Yes	Pipe	Metal	White	Cracking	1	15.7	Positive
5250	1	3	301A	Classroom 301 Coat Closet	Yes	W1	Plaster	White	Cracking	1	14.6	Positive

				Inspection Dates: 09/08/2021-09/10/2021		School District of Philadelphia						
				Name of Inspector: Lionel Ray Wilson		Lead Safe Certification Assessment Report						
				Inspection Company: Viva EHS		Dunbar School						
ULCS#	Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
5250	1	3	301A	Classroom 301 Coat Closet	Yes	W2	Plaster	White	Cracking	2	12.8	Positive
5250	1	3	301A	Classroom 301 Coat Closet	Yes	W3	Plaster	White	Cracking	5	8.2	Positive
5250	1	3	301A	Classroom 301 Coat Closet	Yes	W4	Plaster	White	Cracking	5	14.4	Positive
5250	1	3	301A	Classroom 301 Coat Closet	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5250	1	3	301A	Classroom 301 Coat Closet	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5250	1	3	302	Classroom 302	Yes	W1	Plaster	White	None	0	N/A	N/A
5250	1	3	302	Classroom 302	Yes	W2	Plaster	White	None	0	N/A	N/A
5250	1	3	302	Classroom 302	Yes	W3	Plaster	White	None	0	N/A	N/A
5250	1	3	302	Classroom 302	Yes	W4	Plaster	White	None	0	N/A	N/A
5250	1	3	302	Classroom 302	Yes	Ceiling	N/A	White	None	0	N/A	N/A
5250	1	3	302	Classroom 302	Yes	Floor	N/A	White	None	0	N/A	N/A
5250	1	3	302A	Classroom 302 Coat Closet	Yes	W1	Plaster	White	None	0	N/A	N/A
5250	1	3	302A	Classroom 302 Coat Closet	Yes	W2	Plaster	White	None	0	N/A	N/A
5250	1	3	302A	Classroom 302 Coat Closet	Yes	W3	Plaster	White	None	0	N/A	N/A
5250	1	3	302A	Classroom 302 Coat Closet	Yes	W4	Plaster	White	None	0	N/A	N/A
5250	1	3	302A	Classroom 302 Coat Closet	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5250	1	3	302A	Classroom 302 Coat Closet	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5250	1	3	S36	Stairwell next to Classroom 309	Yes	W1	Plaster	White	Cracking	1	22	Positive
5250	1	3	S36	Stairwell next to Classroom 309	Yes	W2	Plaster	White	Cracking	10	23.1	Positive
5250	1	3	S36	Stairwell next to Classroom 309	Yes	W3	Plaster	White	Cracking	10	20	Positive
5250	1	3	S36	Stairwell next to Classroom 309		Pipe	Metal	Tan	Chipping	1	0.2	Negative
5250	1	3	S36	Stairwell next to Classroom 309		Radiator	Metal	Tan	Chipping	4	1.6	Positive
5250	1	3	S36	Stairwell next to Classroom 309	Yes	W4	Plaster	White	Cracking	5	26.6	Positive
5250	1	3	S36	Stairwell next to Classroom 309	Yes	Ceiling	Plaster	White	None	0	N/A	N/A
5250	1	3	S36	Stairwell next to Classroom 309	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5250	1	3	S36	Stairwell next to Classroom 309	Yes	Newel Post	Metal	Tan	Chipping	12	2	Positive
5250	1	3	S36	Stairwell next to Classroom 309	Yes	Baluster	Metal	Tan	Chipping	3	3.9	Positive
5250	1	3	303	Classroom 303	Yes	W1	Plaster	White	None	0	N/A	N/A
5250	1	3	303	Classroom 303	Yes	W2	Plaster	White	None	0	N/A	N/A
5250	1	3	303	Classroom 303	Yes	W3	Plaster	White	Chipping	3	14.6	Positive
5250	1	3	303	Classroom 303	Yes	W4	Plaster	White	Chipping	1	6.1	Positive
5250	1	3	303	Classroom 303	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5250	1	3	303	Classroom 303	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5250	1	3	303	Classroom 303	Yes	Radiator	Metal	White	Chipping	2	0.04	Negative
5250	1	3	303A	Classroom 303 Coat Closet	Yes	W1	Plaster	Pink	None	0	N/A	N/A
5250	1	3	303A	Classroom 303 Coat Closet	Yes	W2	Plaster	Pink	None	0	N/A	N/A
5250	1	3	303A	Classroom 303 Coat Closet	Yes	W3	Plaster	Pink	None	0	N/A	N/A
5250	1	3	303A	Classroom 303 Coat Closet	Yes	W4	Plaster	Pink	Chipping	1	7.6	Positive
5250	1	3	303A	Classroom 303 Coat Closet	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5250	1	3	303A	Classroom 303 Coat Closet	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5250	1	3	305	Classroom 305	Yes	W1	Plaster	White	Cracking	3	14.2	Positive
5250	1	3	305	Classroom 305	Yes	W2	Plaster	White	Cracking	2	0	Negative
5250	1	3	305	Classroom 305	Yes	W3	Plaster	White	Flaking	10	17.4	Positive
5250	1	3	305	Classroom 305	Yes	W4	Plaster	White	Cracking	1	14.9	Positive
5250	1	3	305	Classroom 305	Yes	W4	Sheetrock	White	Flaking	3	0	Negative
5250	1	3	305	Classroom 305	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A

				Inspection Dates: 09/08/2021-09/10/2021		School District of Philadelphia						
				Name of Inspector: Lionel Ray Wilson		Lead Safe Certification Assessment Report						
				Inspection Company: Viva EHS		Dunbar School						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
5250	1	3	305	Classroom 305	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5250	1	3	305	Classroom 305	Yes	Radiator	Metal	White	Chipping	4	0.3	Negative
5250	1	3	305A	Classroom 305 Coat Closet	Yes	W1	No Access	No Access	No Access	No Access	No Access	No Access
5250	1	3	305A	Classroom 305 Coat Closet	Yes	W2	No Access	No Access	No Access	No Access	No Access	No Access
5250	1	3	305A	Classroom 305 Coat Closet	Yes	W3	No Access	No Access	No Access	No Access	No Access	No Access
5250	1	3	305A	Classroom 305 Coat Closet	Yes	W4	No Access	No Access	No Access	No Access	No Access	No Access
5250	1	3	305A	Classroom 305 Coat Closet	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
5250	1	3	305A	Classroom 305 Coat Closet	Yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access
5250	1	3	304	Classroom 304	Yes	W1	Plaster	White	Chipping	1	21.7	Positive
5250	1	3	304	Classroom 304	Yes	W2	Plaster	White	Chipping	1	0	Negative
5250	1	3	304	Classroom 304	Yes	W3	Plaster	White	Chipping	5	14	Positive
5250	1	3	304	Classroom 304	Yes	W4	Plaster	White	Chipping	2	16.8	Positive
5250	1	3	304	Classroom 304	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5250	1	3	304	Classroom 304	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5250	1	3	304	Classroom 304	Yes	Radiator	Metal	White	Flaking	5	0.1	Negative
5250	1	3	304A	Classroom 304 Coat Closet	Yes	W1	Plaster	White	Cracking	2	6.7	Positive
5250	1	3	304A	Classroom 304 Coat Closet	Yes	W2	Plaster	White	Cracking	3	7.8	Positive
5250	1	3	304A	Classroom 304 Coat Closet	Yes	W3	Plaster	White	Efflorescence	24	13.5	Positive
5250	1	3	304A	Classroom 304 Coat Closet	Yes	W4	Plaster	White	Cracking	5	8	Positive
5250	1	3	304A	Classroom 304 Coat Closet	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5250	1	3	304A	Classroom 304 Coat Closet	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5250	1	3	306	Classroom 306	Yes	W1	Plaster	White	Chipping	6	19.9	Positive
5250	1	3	306	Classroom 306	Yes	W2	Plaster	White	None	0	N/A	N/A
5250	1	3	306	Classroom 306	Yes	W3	Plaster	White	Cracking	10	18.8	Positive
5250	1	3	306	Classroom 306	Yes	W4	Plaster	White	Cracking	5	10.6	Positive
5250	1	3	306	Classroom 306	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5250	1	3	306	Classroom 306	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5250	1	3	306	Classroom 306	Yes	Radiator	Metal	White	Chipping	5	0.06	Negative
5250	1	3	306A	Classroom 306 Coat Closet	Yes	W1	Plaster	White	None	0	N/A	N/A
5250	1	3	306A	Classroom 306 Coat Closet	Yes	W2	Plaster	White	Flaking	20	5.8	Positive
5250	1	3	306A	Classroom 306 Coat Closet	Yes	W3	Plaster	White	Cracking	2	16.2	Positive
5250	1	3	306A	Classroom 306 Coat Closet	Yes	W4	Plaster	White	Cracking	10	16.4	Positive
5250	1	3	306A	Classroom 306 Coat Closet	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5250	1	3	306A	Classroom 306 Coat Closet	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5250	1	3	305D	Pipe Shaft in Hallway outside of Classroom 305	No	W1	Unpainted	N/A	N/A	N/A	N/A	N/A
5250	1	3	305D	Pipe Shaft in Hallway outside of Classroom 305	No	W2	Unpainted	N/A	N/A	N/A	N/A	N/A
5250	1	3	305D	Pipe Shaft in Hallway outside of Classroom 305	No	W3	Unpainted	N/A	N/A	N/A	N/A	N/A
5250	1	3	305D	Pipe Shaft in Hallway outside of Classroom 305	No	W4	Unpainted	N/A	N/A	N/A	N/A	N/A
5250	1	3	305D	Pipe Shaft in Hallway outside of Classroom 305	No	Ceiling	Unpainted	N/A	N/A	N/A	N/A	N/A
5250	1	3	305D	Pipe Shaft in Hallway outside of Classroom 305	No	Floor	Unpainted	N/A	N/A	N/A	N/A	N/A
5250	1	3	305B	Closet next to Boys Restroom	Yes	W1	Plaster	Blue	Cracking	2	13.6	Positive
5250	1	3	305B	Closet next to Boys Restroom	Yes	W2	Plaster	Blue	Cracking	20	7.5	Positive
5250	1	3	305B	Closet next to Boys Restroom	Yes	W3	Plaster	Blue	Efflorescence	40	20.5	Positive
5250	1	3	305B	Closet next to Boys Restroom	Yes	W4	Plaster	Blue	Cracking	3	17.8	Positive
5250	1	3	305B	Closet next to Boys Restroom	Yes	Ceiling	Plaster	White	Flaking	30	15	Positive
5250	1	3	305B	Closet next to Boys Restroom	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A

				Inspection Dates: 09/08/2021-09/10/2021		School District of Philadelphia						
				Name of Inspector: Lionel Ray Wilson		Lead Safe Certification Assessment Report						
				Inspection Company: Viva EHS		Dunbar School						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
5250	1	3	305C-PC	3rd Floor Boys Restroom Pipe Chase	No	W1	Unpainted	N/A	N/A	N/A	N/A	N/A
5250	1	3	305C-PC	3rd Floor Boys Restroom Pipe Chase	No	W2	Unpainted	N/A	N/A	N/A	N/A	N/A
5250	1	3	305C-PC	3rd Floor Boys Restroom Pipe Chase	No	W3	Unpainted	N/A	N/A	N/A	N/A	N/A
5250	1	3	305C-PC	3rd Floor Boys Restroom Pipe Chase	No	W4	Unpainted	N/A	N/A	N/A	N/A	N/A
5250	1	3	305C-PC	3rd Floor Boys Restroom Pipe Chase	No	Ceiling	Unpainted	N/A	N/A	N/A	N/A	N/A
5250	1	3	305C-PC	3rd Floor Boys Restroom Pipe Chase	No	Floor	Unpainted	N/A	N/A	N/A	N/A	N/A
5250	1	3	305C	3rd Floor Boy's Restroom	Yes	W1	Plaster	Multi	Cracking	3	14.4	Positive
5250	1	3	305C	3rd Floor Boy's Restroom	Yes	W2	Plaster	Multi	Cracking	12	20.2	Positive
5250	1	3	305	3rd Floor Boy's Restroom	Yes	W2	CMU Block Wall	Tan	Cracking	1	0	Negative
5250	1	3	305C	3rd Floor Boy's Restroom	Yes	W3	Plaster	Multi	Efflorescence	20	25.4	Positive
5250	1	3	305C	3rd Floor Boy's Restroom	Yes	W4	Plaster	Multi	Chipping	20	24.6	Positive
5250	1	3	305	3rd Floor Boy's Restroom	Yes	W4	CMU Block Wall	Multi	Flaking	5	0	Negative
5250	1	3	305C	3rd Floor Boy's Restroom	Yes	Ceiling	Plaster	White	Efflorescence	45	25	Positive
5250	1	3	305	3rd Floor Boy's Restroom	Yes	Floor	Concrete	Grey	Chipping	30	0	Negative
5250	1	3	S32	Stairwell next to Classroom 308	Yes	W1	Plaster	White	Chipping	1	23.3	Positive
5250	1	3	S32	Stairwell next to Classroom 308	Yes	W2	Plaster	White	Efflorescence	25	22.5	Positive
5250	1	3	S32	Stairwell next to Classroom 308	Yes	W3	Plaster	White	Chipping	4	20.9	Positive
5250	1	3	S32	Stairwell next to Classroom 308		Pipe	Metal	Tan	Chipping	1	0.1	Negative
5250	1	3	S32	Stairwell next to Classroom 308		Radiator	Metal	Tan	Chipping	4	1.4	Positive
5250	1	3	S32	Stairwell next to Classroom 308	Yes	W4	Plaster	White	Chipping	2	5.2	Positive
5250	1	3	S32	Stairwell next to Classroom 308	Yes	Ceiling	Plaster	White	Chipping	40	15.8	Positive
5250	1	3	S32	Stairwell next to Classroom 308	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5250	1	3	S32	Stairwell next to Classroom 308	Yes	Newel Post	Metal	Tan	Chipping	10	3.1	Positive
5250	1	3	S32	Stairwell next to Classroom 308	Yes	Baluster	Metal	Tan	Chipping	5	2.9	Positive
5250	1	3	307	Classroom 307	Yes	W1	Plaster	White	Cracking	1	17.5	Positive
5250	1	3	307	Classroom 307	Yes	W2	Plaster	White	None	0	N/A	N/A
5250	1	3	307	Classroom 307	Yes	W3	Plaster	White	Cracking	15	9.1	Positive
5250	1	3	307	Classroom 307	Yes	W4	Plaster	White	Cracking	1	15.6	Positive
5250	1	3	307	Classroom 307	Yes	Pipe	Metal	White	Cracking	1	17.1	Positive
5250	1	3	307	Classroom 307	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5250	1	3	307	Classroom 307	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5250	1	3	307A	Classroom 307 Coat Closet	Yes	W1	Plaster	White	None	0	N/A	N/A
5250	1	3	307A	Classroom 307 Coat Closet	Yes	W2	Plaster	White	Chipping	2	4.2	Positive
5250	1	3	307A	Classroom 307 Coat Closet	Yes	W3	Plaster	White	Efflorescence	5	10.1	Positive
5250	1	3	307A	Classroom 307 Coat Closet	Yes	W4	Plaster	White	None	0	N/A	N/A
5250	1	3	307A	Classroom 307 Coat Closet	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5250	1	3	307A	Classroom 307 Coat Closet	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5250	1	3	307B	Classroom 307 Rear Closet	Yes	W1	Plaster	White	Flaking	20	13.9	Positive
5250	1	3	307B	Classroom 307 Rear Closet	Yes	W2	Plaster	White	None	0	N/A	N/A
5250	1	3	307B	Classroom 307 Rear Closet	Yes	W3	Plaster	Multi	Flaking	50	4.2	Positive
5250	1	3	307B	Classroom 307 Rear Closet	Yes	W4	Plaster	White	Efflorescence	2	18.3	Positive
5250	1	3	307B	Classroom 307 Rear Closet	Yes	Ceiling	Plaster	White	None	0	N/A	N/A
5250	1	3	307B	Classroom 307 Rear Closet	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5250	1	3	308	Classroom 308	Yes	W1	Plaster	Off-White	Cracking	5	23	Positive
5250	1	3	308	Classroom 308	Yes	W2	Plaster	Off-White	Cracking	1	15.7	Positive
5250	1	3	308	Classroom 308	Yes	W3	Plaster	Off-White	None	0	N/A	N/A

				Inspection Dates: 09/08/2021-09/10/2021		School District of Philadelphia						
				Name of Inspector: Lionel Ray Wilson		Lead Safe Certification Assessment Report						
				Inspection Company: Viva EHS		Dunbar School						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
5250	1	3	308	Classroom 308	Yes	W4	Plaster	Off-White	Cracking	1	19.2	Positive
5250	1	3	308	Classroom 308	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5250	1	3	308	Classroom 308	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5250	1	3	308	Classroom 308	Yes	Radiator	Metal	White	Chipping	5	0.9	Positive
5250	1	3	308A	Classroom 308 Coat Closet	Yes	W1	Plaster	White	None	0	N/A	N/A
5250	1	3	308A	Classroom 308 Coat Closet	Yes	W2	Plaster	White	Cracking	2	14.4	Positive
5250	1	3	308A	Classroom 308 Coat Closet	Yes	W3	Plaster	White	Efflorescence	30	10	Positive
5250	1	3	308A	Classroom 308 Coat Closet	Yes	W4	Plaster	White	Efflorescence	45	11.7	Positive
5250	1	3	308A	Classroom 308 Coat Closet	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5250	1	3	308A	Classroom 308 Coat Closet	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5250	1	3	310	Classroom 310	Yes	W1	Plaster	Green	Chipping	1	42.1	Positive
5250	1	3	310	Classroom 310	Yes	W2	Plaster	Green	Chipping	1	50.2	Positive
5250	1	3	310	Classroom 310	Yes	W3	Plaster	Green	Cracking	1	42.5	Positive
5250	1	3	310	Classroom 310	Yes	W4	Plaster	Green	Efflorescence	25	41.7	Positive
5250	1	3	310	Classroom 310	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5250	1	3	310	Classroom 310	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5250	1	3	310	Classroom 310	Yes	Radiator	Metal	White	Chipping	15	0.4	Negative
5250	1	3	310C	Classroom 310 Restroom	Yes	W1	Plaster	White	Cracking	1	0.06	Negative
5250	1	3	310C	Classroom 310 Restroom	Yes	W2	Plaster	White	None	0	N/A	N/A
5250	1	3	310C	Classroom 310 Restroom	Yes	W3	Plaster	White	Cracking	2	12.6	Positive
5250	1	3	310C	Classroom 310 Restroom	Yes	W4	Plaster	White	None	0	N/A	N/A
5250	1	3	310C	Classroom 310 Restroom	Yes	Ceiling	Plaster	White	None	0	N/A	N/A
5250	1	3	310C	Classroom 310 Restroom	Yes	Floor	Concrete	Grey	None	0	N/A	N/A
5250	1	3	310C	Classroom 310 Restroom	Yes	Radiator	Metal	Tan	Cracking	1	0.4	Negative
5250	1	4	400	Outdoor Classroom 400	Yes	W1	Brick	Unpainted	None	0	N/A	N/A
5250	1	4	400	Outdoor Classroom 400		Door Frame	Metal	Brown	Chipping	2	0	Negative
5250	1	4	400	Outdoor Classroom 400		Door	Metal	Brown	Chipping	2	0	Negative
5250	1	4	400	Outdoor Classroom 400	Yes	W2	Brick	Unpainted	None	0	N/A	N/A
5250	1	4	400	Outdoor Classroom 400	Yes	W3	Brick	Unpainted	None	0	N/A	N/A
5250	1	4	400	Outdoor Classroom 400	Yes	W4	Brick	Unpainted	None	0	N/A	N/A
5250	1	4	400	Outdoor Classroom 400	Yes	Ceiling	Concrete	White	Chipping	2	2.5	Positive
5250	1	4	400	Outdoor Classroom 400	Yes	Floor	Concrete	Unpainted	None	0	N/A	N/A
5250	1	4	401	Vestibule between South Stairwell and Outdoor Classroom 400	Yes	W1	Brick	Unpainted	None	0	N/A	N/A
5250	1	4	401	Vestibule between South Stairwell and Outdoor Classroom 400		Drain Pipe	Metal	Brown	Flaking	2	0.1	Negative
5250	1	4	401	Vestibule between South Stairwell and Outdoor Classroom 400		Handrail	Metal	Tan	Chipping	8	1.5	Positive
5250	1	4	401	Vestibule between South Stairwell and Outdoor Classroom 400		Door Frame	Metal	Brown	Chipping	2	0.1	Negative
5250	1	4	401	Vestibule between South Stairwell and Outdoor Classroom 400		Door	Metal	Brown	Chipping	2	0	Negative
5250	1	4	401	Vestibule between South Stairwell and Outdoor Classroom 400	Yes	W2	Brick	Unpainted	None	0	N/A	N/A
5250	1	4	401	Vestibule between South Stairwell and Outdoor Classroom 400	Yes	W3	Brick	Unpainted	None	0	N/A	N/A
5250	1	4	401	Vestibule between South Stairwell and Outdoor Classroom 400	Yes	W4	Brick	Unpainted	None	0	N/A	N/A

				Inspection Dates: 09/08/2021-09/10/2021	School District of Philadelphia							
				Name of Inspector: Lionel Ray Wilson	Lead Safe Certification Assessment Report							
				Inspection Company: Viva EHS	Dunbar School							
ULCS#	Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
5250	1	4	401	Vestibule between South Stairwell and Outdoor Classroom 400		Radiator	Metal	Tan	Chipping	2	2.3	Positive
5250	1	4	401	Vestibule between South Stairwell and Outdoor Classroom 400	Yes	Ceiling	Concrete	White	None	0	N/A	N/A
5250	1	4	401	Vestibule between South Stairwell and Outdoor Classroom 400	Yes	Floor	Concrete	Unpainted	None	0	N/A	N/A
5250	1	4	403	4th Floor Girl's Restroom	Yes	W1	Brick	Unpainted	None	0	N/A	N/A
5250	1	4	403	4th Floor Girl's Restroom	Yes	W2	Brick	Unpainted	None	0	N/A	N/A
5250	1	4	403	4th Floor Girl's Restroom		Radiator	Metal	Tan	Chipping	2	1.2	Positive
5250	1	4	403	4th Floor Girl's Restroom	Yes	W3	Brick	Unpainted	None	0	N/A	N/A
5250	1	4	403	4th Floor Girl's Restroom	Yes	W4	Brick	Unpainted	None	0	N/A	N/A
5250	1	4	403	4th Floor Girl's Restroom	Yes	Ceiling	Concrete	White	None	0	N/A	N/A
5250	1	4	403	4th Floor Girl's Restroom	Yes	Floor	Concrete	Grey	None	0	N/A	N/A
5250	1	4	403	4th Floor Girl's Restroom	Yes	Radiator	Metal	Pink	Chipping	2	1.3	Positive
5250	1	4	403-PC	4th Floor Pipe Chase in Girl's Restroom	No	W1	Unpainted	N/A	N/A	N/A	N/A	N/A
5250	1	4	403-PC	4th Floor Pipe Chase in Girl's Restroom	No	W2	Unpainted	N/A	N/A	N/A	N/A	N/A
5250	1	4	403-PC	4th Floor Pipe Chase in Girl's Restroom	No	W3	Unpainted	N/A	N/A	N/A	N/A	N/A
5250	1	4	403-PC	4th Floor Pipe Chase in Girl's Restroom	No	W4	Unpainted	N/A	N/A	N/A	N/A	N/A
5250	1	4	403-PC	4th Floor Pipe Chase in Girl's Restroom	No	Ceiling	Unpainted	N/A	N/A	N/A	N/A	N/A
5250	1	4	403-PC	4th Floor Pipe Chase in Girl's Restroom	No	Floor	Unpainted	N/A	N/A	N/A	N/A	N/A
5250	1	4	S46	Stairwell next to Girl's Restroom	Yes	W1	Plaster	Pink	Efflorescence	7	20.5	Positive
5250	1	4	S46	Stairwell next to Girl's Restroom	Yes	W2	Plaster	White	Efflorescence	5	20.5	Positive
5250	1	4	S46	Stairwell next to Girl's Restroom	Yes	W3	Plaster	White	Efflorescence	5	2.4	Positive
5250	1	4	S46	Stairwell next to Girl's Restroom	Yes	W4	Plaster	White	Chipping	5	2.9	Positive
5250	1	4	S46	Stairwell next to Girl's Restroom	Yes	Ceiling	Plaster	White	Chipping	5	7.8	Positive
5250	1	4	S46	Stairwell next to Girl's Restroom	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5250	1	4	S46	Stairwell next to Girl's Restroom		Handrail	Metal	Tan	Chipping	1	1.8	Positive
5250	1	4	S46	Stairwell next to Girl's Restroom		Baluster	Metal	Tan	Chipping	10	2.1	Positive
5250	1	4	S46	Stairwell next to Girl's Restroom		Newel Post	Metal	Tan	Chipping	2	1.5	Positive
5250	1	4	404	Exterior Rooftop Gym	Yes	W1	Brick	Unpainted	None	0	N/A	N/A
5250	1	4	404	Exterior Rooftop Gym	Yes	W2	Brick	Unpainted	None	0	N/A	N/A
5250	1	4	404	Exterior Rooftop Gym	Yes	W3	Brick	Unpainted	None	0	N/A	N/A
5250	1	4	404	Exterior Rooftop Gym	Yes	W4	Brick	Unpainted	None	0	N/A	N/A
5250	1	4	404	Exterior Rooftop Gym	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5250	1	4	404	Exterior Rooftop Gym	Yes	Floor	Concrete	Unpainted				
5250	1	4	S42	Stairwell next to Boys Restroom	Yes	W1	Plaster	Tan	Chipping	2	24.7	Positive
5250	1	4	S42	Stairwell next to Boys Restroom	Yes	W2	Plaster	Tan	None	0	N/A	N/A
5250	1	4	S42	Stairwell next to Boys Restroom	Yes	W3	Plaster	Tan	Chipping	5	11.6	Positive
5250	1	4	S42	Stairwell next to Boys Restroom	Yes	W4	Plaster	Tan	None	0	N/A	N/A
5250	1	4	S42	Stairwell next to Boys Restroom	Yes	Ceiling	Plaster	White	Efflorescence	3	9	Positive
5250	1	4	S42	Stairwell next to Boys Restroom	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5250	1	4	408	4th floor Boys Restroom	Yes	W1	Brick	Unpainted	None	0	N/A	N/A
5250	1	4	408	4th floor Boys Restroom	Yes	W2	Brick	Unpainted	None	0	N/A	N/A
5250	1	4	408	4th floor Boys Restroom		Radiator	Metal	Tan	Chipping	2	1.8	Positive
5250	1	4	408	4th floor Boys Restroom	Yes	W3	Brick	Unpainted	None	0	N/A	N/A
5250	1	4	408	4th floor Boys Restroom	Yes	W4	Brick	Unpainted	None	0	N/A	N/A
5250	1	4	408	4th floor Boys Restroom	Yes	Ceiling	Concrete	White	None	0	N/A	N/A

				Inspection Dates: 09/08/2021-09/10/2021		School District of Philadelphia						
				Name of Inspector: Lionel Ray Wilson		Lead Safe Certification Assessment Report						
				Inspection Company: Viva EHS		Dunbar School						
ULCS#	Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
5250	1	4	408	4th floor Boys Restroom	Yes	Floor	Concrete	Grey	None	0	N/A	N/A
5250	1	4	406	Vestibule between North Stairwell and Outdoor Classroom 407	Yes	W1	Brick	Unpainted	None	0	N/A	N/A
5250	1	4	406	Vestibule between North Stairwell and Outdoor Classroom 407		Door Frame	Metal	Brown	Chipping	2	0	Negative
5250	1	4	406	Vestibule between North Stairwell and Outdoor Classroom 407		Door	Metal	Brown	Chipping	2	0	Negative
5250	1	4	406	Vestibule between North Stairwell and Outdoor Classroom 407	Yes	W2	Brick	Unpainted	None	0	N/A	N/A
5250	1	4	406	Vestibule between North Stairwell and Outdoor Classroom 407	Yes	W3	Brick	Unpainted	None	0	N/A	N/A
5250	1	4	406	Vestibule between North Stairwell and Outdoor Classroom 407	Yes	W4	Brick	Unpainted	None	0	N/A	N/A
5250	1	4	406	Vestibule between North Stairwell and Outdoor Classroom 407		Radiator	Metal	Tan	Chipping	3	1.6	Positive
5250	1	4	406	Vestibule between North Stairwell and Outdoor Classroom 407	Yes	Ceiling	Concrete	White	None	0	N/A	N/A
5250	1	4	406	Vestibule between North Stairwell and Outdoor Classroom 407	Yes	Floor	Concrete	Unpainted	None	0	N/A	N/A
5250	1	4	407	Outdoor Classroom 407	Yes	W1	Brick	Unpainted	None	0	N/A	N/A
5250	1	4	407	Outdoor Classroom 407	Yes	W2	Brick	Unpainted	None	0	N/A	N/A
5250	1	4	407	Outdoor Classroom 407	Yes	W3	Brick	Unpainted	None	0	N/A	N/A
5250	1	4	407	Outdoor Classroom 407	Yes	W4	Brick	Unpainted	None	0	N/A	N/A
5250	1	4	407	Outdoor Classroom 407	Yes	Ceiling	Concrete	White	Chipping	3	15.8	Positive
5250	1	4	407	Outdoor Classroom 407	Yes	Floor	Concrete	Unpainted	None	0	N/A	N/A
5250	1	4	408A	4th Floor Boys Restroom Pipe Chase	No	W1	Unpainted	N/A	N/A	N/A	N/A	N/A
5250	1	4	408A	4th Floor Boys Restroom Pipe Chase	No	W2	Unpainted	N/A	N/A	N/A	N/A	N/A
5250	1	4	408A	4th Floor Boys Restroom Pipe Chase	No	W3	Unpainted	N/A	N/A	N/A	N/A	N/A
5250	1	4	408A	4th Floor Boys Restroom Pipe Chase	No	W4	Unpainted	N/A	N/A	N/A	N/A	N/A
5250	1	4	408A	4th Floor Boys Restroom Pipe Chase	No	Ceiling	Unpainted	N/A	N/A	N/A	N/A	N/A
5250	1	4	408A	4th Floor Boys Restroom Pipe Chase	No	Floor	Unpainted	N/A	N/A	N/A	N/A	N/A
5250	1	5	500D	Fresh Air Intake/Recirculation	No	W1	Concrete	White	None	0	N/A	N/A
5250	1	5	500D	Fresh Air Intake/Recirculation	No	W2	Concrete	White	Cracking	5	0	Negative
5250	1	5	500D	Fresh Air Intake/Recirculation	No	W2	Brick	White	Chipping	5	0.45	Negative
5250	1	5	500D	Fresh Air Intake/Recirculation	No	W3	Brick	White	None	0	N/A	N/A
5250	1	5	500D	Fresh Air Intake/Recirculation	No	W4	Concrete	White	Cracking	5	0	Negative
5250	1	5	500D	Fresh Air Intake/Recirculation	No	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
5250	1	5	500D	Fresh Air Intake/Recirculation	No	Floor	Unpainted	N/A	N/A	N/A	N/A	N/A
5250	1	4	500C	Fan Room	No	W1	Concrete	White	Cracking	15	0.4	Negative
5250	1	4	500C	Fan Room	No	W2	N/A	N/A	N/A	N/A	N/A	N/A
5250	1	4	500C	Fan Room	No	W3	N/A	N/A	N/A	N/A	N/A	N/A
5250	1	4	500C	Fan Room	No	W4	N/A	N/A	N/A	N/A	N/A	N/A
5250	1	4	500C	Fan Room	No	Ceiling	No Access	White	Chipping	5	N/A	N/A
5250	1	4	500C	Fan Room	No	Floor	Unpainted	N/A	N/A	N/A	N/A	N/A
5250	1	4	500G	Exhaust Fan Room	No	W1	No Access	No Access	No Access	No Access	No Access	No Access
5250	1	4	500G	Exhaust Fan Room	No	W2	No Access	No Access	No Access	No Access	No Access	No Access
5250	1	4	500G	Exhaust Fan Room	No	W3	No Access	No Access	No Access	No Access	No Access	No Access
5250	1	4	500G	Exhaust Fan Room	No	W4	No Access	No Access	No Access	No Access	No Access	No Access

				Inspection Dates: 09/08/2021-09/10/2021		School District of Philadelphia						
				Name of Inspector: Lionel Ray Wilson		Lead Safe Certification Assessment Report						
				Inspection Company: Viva EHS		Dunbar School						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
5250	1	4	500G	Exhaust Fan Room	No	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
5250	1	4	500G	Exhaust Fan Room	No	Floor	No Access	No Access	No Access	No Access	No Access	No Access
5250	1	5	500E	North End Penthouse - Water Holding Tank Room	No	W1	Brick	White	Efflorescence	350	0	Negative
5250	1	5	500E	North End Penthouse - Water Holding Tank Room	No	W2	Brick	White	Efflorescence	80	0	Negative
5250	1	5	500E	North End Penthouse - Water Holding Tank Room	No	W3	Brick	White	Efflorescence	300	0	Negative
5250	1	5	500E	North End Penthouse - Water Holding Tank Room	No	W4	Brick	White	Efflorescence	120	0	Negative
5250	1	5	500E	North End Penthouse - Water Holding Tank Room	No	Ceiling	Concrete	White	Chipping	60	0	Negative
5250	1	5	500E	North End Penthouse - Water Holding Tank Room	No	Floor	Unpainted	N/A	N/A	N/A	N/A	N/A
5250	1	5	500E	North End Penthouse - Water Holding Tank Room	No	Water Tank	Metal	Silver	Cracking	100	0.04	Negative
5250	1	5	500E	North End Penthouse - Water Holding Tank Room	No	Radiator	Metal	White	Flaking	20	0	Negative
5250	1	5	500G	South End Penthouse (Empty Room)	No	W1	N/A	N/A	N/A	N/A	N/A	N/A
5250	1	5	500G	South End Penthouse (Empty Room)	No	W2	Brick	White	Chipping	5	0.4	Negative
5250	1	5	500G	South End Penthouse (Empty Room)	No	W3	Concrete	White	Cracking	4	0.35	Negative
5250	1	5	500G	South End Penthouse (Empty Room)	No	W4	N/A	N/A	N/A	N/A	N/A	N/A
5250	1	5	500G	South End Penthouse (Empty Room)	No	Pipe	Metal	White	Chipping	3	0.15	Negative
5250	1	5	500G	South End Penthouse (Empty Room)	No	Ceiling	No Access	White	Chipping	2	N/A	N/A
5250	1	5	500G	South End Penthouse (Empty Room)	No	Floor	Unpainted	N/A	N/A	N/A	N/A	N/A
5250	1	A	AT-M	Main Attic below 4th Floor Play Deck	No	W1	Unpainted	N/A	None	0	N/A	N/A
5250	1	A	AT-M	Main Attic below 4th Floor Play Deck	No	W2	Unpainted	N/A	None	0	N/A	N/A
5250	1	A	AT-M	Main Attic below 4th Floor Play Deck	No	W3	Unpainted	N/A	None	0	N/A	N/A
5250	1	A	AT-M	Main Attic below 4th Floor Play Deck	No	W4	Unpainted	N/A	None	0	N/A	N/A
5250	1	A	AT-M	Main Attic below 4th Floor Play Deck	No	Ceiling	Unpainted	N/A	None	0	N/A	N/A
5250	1	A	AT-M	Main Attic below 4th Floor Play Deck	No	Floor	Unpainted	N/A	None	0	N/A	N/A
5250	1	A	AT-A	Auditorium Attic	No	W1	Unpainted	N/A	None	0	N/A	N/A
5250	1	A	AT-A	Auditorium Attic	No	W2	Unpainted	N/A	None	0	N/A	N/A
5250	1	A	AT-A	Auditorium Attic	No	W3	Unpainted	N/A	None	0	N/A	N/A
5250	1	A	AT-A	Auditorium Attic	No	W4	Unpainted	N/A	None	0	N/A	N/A
5250	1	A	AT-A	Auditorium Attic	No	Ceiling	Unpainted	N/A	None	0	N/A	N/A
5250	1	A	AT-A	Auditorium Attic	No	Floor	Unpainted	N/A	None	0	N/A	N/A