

				Inspection Dates: May 2020			School District of Philadelphia					
				Name of Inspector: Paul Davis			Lead Safe Certification Assessment Report					
				Inspection Company: VERTEX			1300 A.D. Harrington ES/1301 Harrington Annex School					
ULCS#	Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1300	1	1	100A	Women's Lounge	yes	W1	Plaster	Blue	None	0	N/A	N/A
1300	1	1	100A	Women's Lounge	yes	W2	Plaster	Blue	Flaking	2	24.1	Positive
1300	1	1	100A	Women's Lounge	yes	W3	Plaster	Blue	None	0	N/A	N/A
1300	1	1	100A	Women's Lounge	yes	W4	Plaster	Blue	Partially Inaccessible/flaking	2	25.6	Positive
1300	1	1	100A	Women's Lounge	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1300	1	1	100A	Women's Lounge	yes	Floor	Wood	Varnish	None	0	N/A	N/A
1300	1	1	102A	Restroom in Women's Lounge	yes	W1	Plaster	White	Flaking	6	19.8	Positive
1300	1	1	102A	Restroom in Women's Lounge	yes	W2	Plaster	White	None	0	N/A	N/A
1300	1	1	102A	Restroom in Women's Lounge	yes	W3	Plaster	White	Flaking	6	21.6	Positive
1300	1	1	102A	Restroom in Women's Lounge	yes	Pipe	Metal	Blue & White	Flaking	6	0.3	Negative
1300	1	1	102A	Restroom in Women's Lounge	yes	W4	Plaster	White	efflorescence/flaking	10	23.9	Positive
1300	1	1	102A	Restroom in Women's Lounge	yes	Ceiling	Concrete	White	None	0	N/A	N/A
1300	1	1	102A	Restroom in Women's Lounge	yes	Floor	Concrete	Brown	Chipping	2	0.03	Negative
1300	1	1	101	Classroom 101	yes	W1	Plaster	White	cracking/flaking	200	30.2	Positive
1300	1	1	101	Classroom 101	yes	Chalkboard Frame	Wood	Varnish	Chipping	10	0.25	Negative
1300	1	1	101	Classroom 101	yes	W2	Plaster	White & Pink	Cracking	3	28.8	Positive
1300	1	1	101	Classroom 101	yes	Door/Door Frame	Wood	Varnish	Chipping	4	0.04	Negative
1300	1	1	101	Classroom 101	yes	W3	Plaster	White	Flaking	25	14	Positive
1300	1	1	101	Classroom 101	yes	Radiator	Metal	Grey	chipping/flaking	24	4.8	Positive
1300	1	1	101	Classroom 101	yes	Window Sill/Frame	Wood	Varnish	Chipping	20	0.14	Negative
1300	1	1	101	Classroom 101	yes	W4	Plaster	White	Flaking	3	25	Positive
1300	1	1	101	Classroom 101	yes	Ceiling	Plaster	White	Flaking	5	34	Positive
1300	1	1	101	Classroom 101	yes	Floor	Wood	Varnish	Chipping	40	0.01	Negative
1300	1	1	101	Classroom 101	yes	Baseboard	Wood	Varnish	Chipping	20	0.05	Negative
1300	1	1	101A	Classroom 101 Restroom	yes	W1	Plaster	White	Flaking	25	14.7	Positive
1300	1	1	101A	Classroom 101 Restroom	yes	W2	Plaster	White	Efflorescence/flaking	5	15.6	Positive
1300	1	1	101A	Classroom 101 Restroom	yes	Radiator	Metal	Grey	Flaking	8	1.3	Positive
1300	1	1	101A	Classroom 101 Restroom	yes	W3	Plaster	White	None	0	N/A	N/A
1300	1	1	101A	Classroom 101 Restroom	yes	Pipe	Metal	White	Flaking	12	22.3	Positive
1300	1	1	101A	Classroom 101 Restroom	yes	W4	Plaster	White	None	0	N/A	N/A
1300	1	1	101A	Classroom 101 Restroom	yes	Ceiling	Concrete	White	Flaking	2	20.4	Positive
1300	1	1	101A	Classroom 101 Restroom	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1300	1	1	101B	Room 101B Principal's Storage across from Classroom 101	yes	W1	Brick	White	Partially Inaccessible	0	0.05	Negative
1300	1	1	101B	Room 101B Principal's Storage across from Classroom 101	yes	W2	CMU	White	Partially Inaccessible	0	0.05	Negative
1300	1	1	101B	Room 101B Principal's Storage across from Classroom 101	yes	W3	Brick	White	Partially Inaccessible	0	0.04	Negative
1300	1	1	101B	Room 101B Principal's Storage across from Classroom 101	yes	Pipe	Metal	White	Flaking	20	0.24	Negative
1300	1	1	101B	Room 101B Principal's Storage across from Classroom 101	yes	W4	Brick	White	Partially Inaccessible	0	0.04	Negative

				Inspection Dates: May 2020		School District of Philadelphia						
				Name of Inspector: Paul Davis		Lead Safe Certification Assessment Report						
				Inspection Company: VERTEX		1300 A.D. Harrington ES/1301 Harrington Annex School						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1300	1	1	101B	Room 101B Principal's Storage across from Classroom 101	yes	Ceiling	Concrete	White	None	0	N/A	N/A
1300	1	1	101B	Room 101B Principal's Storage across from Classroom 101	yes	Ductwork	Metal	White	Flaking	25	0.04	Negative
1300	1	1	101B	Room 101B Principal's Storage across from Classroom 101	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1300	1	1	101C	Classroom 101 Large Storage	yes	W1	Plaster	White	Flaking	2	21.3	Positive
1300	1	1	101C	Classroom 101 Large Storage	yes	W2	Plaster	White	None	0	N/A	N/A
1300	1	1	101C	Classroom 101 Large Storage	yes	W3	Plaster	White	Flaking	2	21.9	Positive
1300	1	1	101C	Classroom 101 Large Storage	yes	W4	Plaster	White	None	0	N/A	N/A
1300	1	1	101C	Classroom 101 Large Storage	yes	Pipe Outer Cover	Metal	White	Flaking	3	10.1	Positive
1300	1	1	101C	Classroom 101 Large Storage	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1300	1	1	101C	Classroom 101 Large Storage	yes	Floor	Wood	Varnish	None	0	N/A	N/A
1300	1	1		Classroom 101 Storage near Restroom	yes	W1	No Access	No Access	No Access	No Access	No Access	No Access
1300	1	1		Classroom 101 Storage near Restroom	yes	W2	No Access	No Access	No Access	No Access	No Access	No Access
1300	1	1		Classroom 101 Storage near Restroom	yes	W3	No Access	No Access	No Access	No Access	No Access	No Access
1300	1	1		Classroom 101 Storage near Restroom	yes	W4	No Access	No Access	No Access	No Access	No Access	No Access
1300	1	1		Classroom 101 Storage near Restroom	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1300	1	1		Classroom 101 Storage near Restroom	yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1300	1	1	102	Nurse's Office	yes	W1	Plaster	Green & Tan	None	0	N/A	N/A
1300	1	1	102	Nurse's Office	yes	Door	Wood	Tan	chipping/flaking	9	1.7	Positive
1300	1	1	102	Nurse's Office	yes	Door Frame	Wood	Tan	chipping/flaking	10	5.7	Positive
1300	1	1	102	Nurse's Office	yes	W2	Plaster	Green & Tan	Partially Inaccessible/flaking	40	30	Positive
1300	1	1	102	Nurse's Office	yes	W3	Plaster	Green & Tan	Partially Inaccessible/flaking	10	31.3	Positive
1300	1	1	102	Nurse's Office	yes	Window Sill	Wood	Tan	chipping/flaking	4	2.8	Positive
1300	1	1	102	Nurse's Office	yes	Window Frame	Wood	Tan	Flaking	1	3.7	Positive
1300	1	1	102	Nurse's Office	yes	Radiator	Metal	Grey	Flaking	12	5.8	Positive
1300	1	1	102	Nurse's Office	yes	W4	Plaster	Green & Tan	Efflorescence/flaking	6	34	Positive
1300	1	1	102	Nurse's Office	yes	Cabinet	Wood	Tan	Flaking	5	1.7	Positive
1300	1	1	102	Nurse's Office	yes	Ceiling	Plaster	Tan	Efflorescence/flaking	35	37.1	Positive
1300	1	1	102	Nurse's Office	yes	Pipe	Metal	White	Chipping	4	0.12	Negative
1300	1	1	102	Nurse's Office	yes	Floor	Wood	Varnish	None	0	N/A	N/A
1300	1	1	102	Nurse's Office	yes	Baseboard	Wood	Tan & Green	Chipping	10	2.4	Positive
1300	1	1	102	Nurse's Office	yes	Chair Rail	Wood	Tan	Chipping	12	3.1	Positive
1300	1	1	102B	Room SC-5 Book Closet	yes	W1	No Access	No Access	No Access	No Access	No Access	No Access
1300	1	1	102B	Room SC-5 Book Closet	yes	W2	No Access	No Access	No Access	No Access	No Access	No Access
1300	1	1	102B	Room SC-5 Book Closet	yes	W3	No Access	No Access	No Access	No Access	No Access	No Access
1300	1	1	102B	Room SC-5 Book Closet	yes	W4	No Access	No Access	No Access	No Access	No Access	No Access
1300	1	1	102B	Room SC-5 Book Closet	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1300	1	1	102B	Room SC-5 Book Closet	yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1300	1	1		Nurse's Office Closet	yes	W1	No Access	No Access	No Access	No Access	No Access	No Access
1300	1	1		Nurse's Office Closet	yes	W2	No Access	No Access	No Access	No Access	No Access	No Access
1300	1	1		Nurse's Office Closet	yes	W3	No Access	No Access	No Access	No Access	No Access	No Access

				Inspection Dates: May 2020			School District of Philadelphia					
				Name of Inspector: Paul Davis			Lead Safe Certification Assessment Report					
				Inspection Company: VERTEX			1300 A.D. Harrington ES/1301 Harrington Annex School					
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1300	1	1		Nurse's Office Closet	yes	W4	No Access	No Access	No Access	No Access	No Access	No Access
1300	1	1		Nurse's Office Closet	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1300	1	1		Nurse's Office Closet	yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1300	1	1	102C	Nurse's Office Restroom	yes	W1	Plaster	White	None	0	N/A	N/A
1300	1	1	102C	Nurse's Office Restroom	yes	Door	Wood	Tan	chipping/flaking	4	1.8	Positive
1300	1	1	102C	Nurse's Office Restroom	yes	Door Frame	Wood	Tan	Chipping	1	5.6	Positive
1300	1	1	102C	Nurse's Office Restroom	yes	W2	Plaster	White	flaking/cracking	5	28.6	Positive
1300	1	1	102C	Nurse's Office Restroom	yes	W3	Plaster	White	None	0	N/A	N/A
1300	1	1	102C	Nurse's Office Restroom	yes	W4	Plaster	White	Cracking	5	33.2	Positive
1300	1	1	102C	Nurse's Office Restroom	yes	Ceiling	Plaster	White	Flaking	1	25.5	Positive
1300	1	1	102C	Nurse's Office Restroom	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1300	1	1	103	Classroom 103	yes	W1	Plaster	White	Partially Inaccessible/cracking	15	31.7	Positive
1300	1	1	103	Classroom 103	yes	W2	Wood	Varnish	None	0	N/A	N/A
1300	1	1	103	Classroom 103	yes	W3	Plaster	White	Flaking	10	20	Positive
1300	1	1	103	Classroom 103	yes	Radiator	Metal	Grey	Flaking	12	4.9	Positive
1300	1	1	103	Classroom 103	yes	W4	Plaster	White	Partially Inaccessible/cracking/ bulging	3	28.5	Positive
1300	1	1	103	Classroom 103	yes	Ceiling	Plaster	White	Flaking	30	33.5	Positive
1300	1	1	103	Classroom 103	yes	Floor	Wood	Varnish	N/A	N/A	N/A	N/A
1300	1	1	103A	Classroom 103 Storage	yes	W1	Plaster	White	None	0	N/A	N/A
1300	1	1	103A	Classroom 103 Storage	yes	W2	Plaster	White	None	0	N/A	N/A
1300	1	1	103A	Classroom 103 Storage	yes	Pipe Outer Cover	Metal	White	Flaking	2	10.1	Positive
1300	1	1	103A	Classroom 103 Storage	yes	Radiator	Metal	Grey	Flaking	6	5.8	Positive
1300	1	1	103A	Classroom 103 Storage	yes	W3	Plaster	White	Partially Inaccessible	0	16.9	Positive
1300	1	1	103A	Classroom 103 Storage	yes	W4	Plaster	White	Partially Inaccessible	0	23.4	Positive
1300	1	1	103A	Classroom 103 Storage	yes	Ceiling	Plaster	White	Flaking	2	27.7	Positive
1300	1	1	103A	Classroom 103 Storage	yes	Floor	Wood	Varnish	None	0	N/A	N/A
1300	1	1	104	Classroom 104 Office	yes	W1	Plaster	White	Flaking	6	29.7	Positive
1300	1	1	104	Classroom 104 Office	yes	W2	Plaster	White	Partially Inaccessible/Flaking	5	25.5	Positive
1300	1	1	104	Classroom 104 Office	yes	W3	Plaster	White	Partially Inaccessible/flaking	2	22.5	Positive
1300	1	1	104	Classroom 104 Office	yes	Radiator	Metal	Grey	Flaking	12	1.8	Positive
1300	1	1	104	Classroom 104 Office	yes	W4	Plaster	White	Flaking	1	23.7	Positive
1300	1	1	104	Classroom 104 Office	yes	Ceiling	Plaster	White	Efflorescence/flaking	75	37.3	Positive
1300	1	1	104	Classroom 104 Office	yes	Floor	Wood	Varnish	None	0	N/A	N/A
1300	1	1	104	Classroom 104 Office	yes	Partition Wall	Metal	Tan	Chipping	4	0	Negative
1300	1	1	104A	Classroom 104 Storage	yes	W1	Plaster	White	None	0	N/A	N/A
1300	1	1	104A	Classroom 104 Storage	yes	W2	Plaster	White	Flaking	2	9.5	Positive
1300	1	1	104A	Classroom 104 Storage	yes	W3	Plaster	White	Flaking	2	15.1	Positive
1300	1	1	104A	Classroom 104 Storage	yes	W4	Plaster	White	Flaking	1	19	Positive
1300	1	1	104A	Classroom 104 Storage	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1300	1	1	104A	Classroom 104 Storage	yes	Floor	Wood	Varnish	None	0	N/A	N/A

				Inspection Dates: May 2020			School District of Philadelphia					
				Name of Inspector: Paul Davis			Lead Safe Certification Assessment Report					
				Inspection Company: VERTEX			1300 A.D. Harrington ES/1301 Harrington Annex School					
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1300	1	1	105	Principal's Office	yes	W1	Plaster	White/Blue	Partially Inaccessible	0	43.5	Positive
1300	1	1	105	Principal's Office	yes	W2	Plaster	White/Blue	Partially Inaccessible	0	37.5	Positive
1300	1	1	105	Principal's Office	yes	W3	Plaster	White/Blue	Partially Inaccessible	0	29.3	Positive
1300	1	1	105	Principal's Office	yes	W4	Plaster	White	None	0	N/A	N/A
1300	1	1	105	Principal's Office	yes	Ceiling	Plaster	White	Efflorescence/flaking	20	23.7	Positive
1300	1	1	105	Principal's Office	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1300	1	1	105B	Principal's Office Restroom	yes	W1	Plaster	Yellow	None	0	N/A	N/A
1300	1	1	105B	Principal's Office Restroom	yes	W2	Plaster	Yellow	None	0	N/A	N/A
1300	1	1	105B	Principal's Office Restroom	yes	W3	Plaster	Yellow	None	0	N/A	N/A
1300	1	1	105B	Principal's Office Restroom	yes	W4	Plaster	Yellow	None	0	N/A	N/A
1300	1	1	105B	Principal's Office Restroom	yes	Ceiling	Plaster	Yellow	None	0	N/A	N/A
1300	1	1	105B	Principal's Office Restroom	yes	Floor	Wood	Varnish	N/A	N/A	N/A	N/A
1300	1	1	105A	Main Office	yes	W1	Plaster	White/Blue	None	0	N/A	N/A
1300	1	1	105A	Main Office	yes	W2	Plaster	White/Blue	Partially Inaccessible	0	39.7	Positive
1300	1	1	105A	Main Office	yes	W3	Plaster	White/Blue	None	0	N/A	N/A
1300	1	1	105A	Main Office	yes	Radiator	Metal	Grey	Flaking	6	6.6	Positive
1300	1	1	105A	Main Office	yes	W4	Plaster	White/Blue	Partially Inaccessible/Flaking	2	42	Positive
1300	1	1	105A	Main Office	yes	Ceiling	Plaster	White	Flaking	20	33.5	Positive
1300	1	1	105A	Main Office	yes	Floor	Wood	Varnish	N/A	N/A	N/A	N/A
1300	1	1	105C	Main Office Storage	yes	W1	Plaster	Pink	Partially Inaccessible	0	7.4	Positive
1300	1	1	105C	Main Office Storage	yes	W2	Plaster	Pink	Partially Inaccessible	0	13.1	Positive
1300	1	1	105C	Main Office Storage	yes	W3	Plaster	Pink	Partially Inaccessible	0	14	Positive
1300	1	1	105C	Main Office Storage	yes	W4	Plaster	Pink	Partially Inaccessible	0	15.1	Positive
1300	1	1	105C	Main Office Storage	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1300	1	1	105C	Main Office Storage	yes	Floor	Wood	Varnish	N/A	N/A	N/A	N/A
1300	1	1	105C	Main Office Storage	yes	Shelving	Wood	Varnish	Chipping	10	0.01	Negative
1300	1	1	105C	Main Office Closet	yes	W1	Plaster	Tan/White	None	0	N/A	N/A
1300	1	1	105C	Main Office Closet	yes	W2	Plaster	Tan/White	Cracking	8	18	Positive
1300	1	1	105C	Main Office Closet	yes	W3	Plaster	Tan/White	Partially Inaccessible/Flaking	1	21.1	Positive
1300	1	1	105C	Main Office Closet	yes	W4	Plaster	Tan/White	Partially Inaccessible	0	19.7	Positive
1300	1	1	105C	Main Office Closet	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1300	1	1	105C	Main Office Closet	yes	Floor	Wood	Varnish	N/A	N/A	N/A	N/A
1300	1	1	105C	Main Office Closet	yes	Shelving	Wood	Varnish	Chipping	2	0.02	Negative
1300	1	1	106	Classroom 106	yes	W1	Plaster	Yellow	Flaking	10	32.4	Positive
1300	1	1	106	Classroom 106	yes	W2	Plaster	White	Efflorescence/Flaking	4	26.9	Positive
1300	1	1	106	Classroom 106	yes	W3	Plaster	Yellow	Efflorescence/Flaking	6	22.2	Positive
1300	1	1	106	Classroom 106	yes	Radiator	Metal	Grey	flaking	24	6.5	Positive
1300	1	1	106	Classroom 106	yes	W4	Plaster	Yellow	Partially Inaccessible	0	28.3	Positive
1300	1	1	106	Classroom 106	yes	Ceiling	Plaster	Tan	Flaking	30	27	Positive
1300	1	1	106	Classroom 106	yes	Floor	Wood	Varnish	Chipping	100	0.02	Negative
1300	1	1	106A	Classroom 106 Restroom	yes	W1	Plaster	White	None	0	N/A	N/A
1300	1	1	106A	Classroom 106 Restroom	yes	W2	Plaster	White	None	0	N/A	N/A

				Inspection Dates: May 2020			School District of Philadelphia					
				Name of Inspector: Paul Davis			Lead Safe Certification Assessment Report					
				Inspection Company: VERTEX			1300 A.D. Harrington ES/1301 Harrington Annex School					
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1300	1	1	106A	Classroom 106 Restroom	yes	W3	Plaster	White	Efflorescence/Flaking/ Cracking	12	22.4	Positive
1300	1	1	106A	Classroom 106 Restroom	yes	W4	Plaster	White	Efflorescence/Flaking	12	30.1	Positive
1300	1	1	106A	Classroom 106 Restroom	yes	Pipe Outer Cover	Metal	White	Flaking	6	18.9	Positive
1300	1	1	106A	Classroom 106 Restroom	yes	Ceiling	Plaster	White	Efflorescence/Flaking	20	33	Positive
1300	1	1	106A	Classroom 106 Restroom	yes	Floor	Concrete	Grey	Chipping	10	0.09	Negative
1300	1	1		Storage outside Classroom 106	yes	W1	Plaster	Yellow	Flaking	1	10.1	Positive
1300	1	1		Storage outside Classroom 106	yes	W2	Plaster	Yellow	Cracking	4	21.2	Positive
1300	1	1		Storage outside Classroom 106	yes	W3	Plaster	Yellow	Partially Inaccessible	0	17	Positive
1300	1	1		Storage outside Classroom 106	yes	W4	Plaster	Yellow	flaking/cracking	30	19.7	Positive
1300	1	1		Storage outside Classroom 106	yes	Ceiling	Plaster	White	Flaking	2	18.9	Positive
1300	1	1		Storage outside Classroom 106	yes	Floor	Wood	Varnish	N/A	N/A	N/A	N/A
1300	1	1	107	Classroom 107	yes	W1	Plaster	Blue	Chipping	10	24.3	Positive
1300	1	1	107	Classroom 107	yes	Door	Wood	Varnish	Chipping	2	0.06	Negative
1300	1	1	107	Classroom 107	yes	Door Frame	Wood	Varnish	Chipping	6	0.08	Negative
1300	1	1	107	Classroom 107	yes	W2	Wood	Varnish	Chipping	8	0.02	Negative
1300	1	1	107	Classroom 107	yes	W3	Plaster	Blue	Partially Inaccessible	0	24.5	Positive
1300	1	1	107	Classroom 107	yes	Window Sill	Wood	Varnish	Chipping	12	0.12	Negative
1300	1	1	107	Classroom 107	yes	Window Frame	Wood	Varnish	Chipping	6	0.18	Negative
1300	1	1	107	Classroom 107	yes	W4	Plaster	Blue	Partially Inaccessible	0	17.6	Positive
1300	1	1	107	Classroom 107	yes	Chalkboard Frame	Wood	Varnish	Chipping	8	0.05	Negative
1300	1	1	107	Classroom 107	yes	Ceiling	Plaster	White	Flaking	2	34.1	Positive
1300	1	1	107	Classroom 107	yes	Floor	Wood	Varnish	Chipping	40	0	Negative
1300	1	1	107	Classroom 107	yes	Baseboard	Wood	Varnish	Chipping	20	0.08	Negative
1300	1	1	107A	Classroom 107 Storage	yes	W1	Plaster	Blue	Chipping	12	20	Positive
1300	1	1	107A	Classroom 107 Storage	yes	W2	Plaster	Blue	Partially Inaccessible	0	17.8	Positive
1300	1	1	107A	Classroom 107 Storage	yes	W3	Plaster	Blue	Chipping	20	21.3	Positive
1300	1	1	107A	Classroom 107 Storage	yes	W4	Plaster	Blue	Partially Inaccessible	0	18.1	Positive
1300	1	1	107A	Classroom 107 Storage	yes	Ceiling	Plaster	Blue	None	0	N/A	N/A
1300	1	1	107A	Classroom 107 Storage	yes	Floor	Wood	Varnish	N/A	N/A	N/A	N/A
1300	1	1	107B	Room SC-2 Custodial Storage outside Classroom 107	no	W1	Plaster	Tan	Flaking	3	8.9	Positive
1300	1	1	107B	Room SC-2 Custodial Storage outside Classroom 107	no	W2	Plaster	Tan/Blue	Flaking	2	15.1	Positive
1300	1	1	107B	Room SC-2 Custodial Storage outside Classroom 107	no	W3	Plaster	Tan/Blue	Flaking	20	10.1	Positive
1300	1	1	107B	Room SC-2 Custodial Storage outside Classroom 107	no	W4	Plaster	Tan/Blue	Flaking	5	8.2	Positive
1300	1	1	107B	Room SC-2 Custodial Storage outside Classroom 107	no	Pipe	Metal	Grey/Tan	Flaking	12	8.1	Positive
1300	1	1	107B	Room SC-2 Custodial Storage outside Classroom 107	no	Ceiling	Plaster	Tan	Flaking	20	10.1	Positive
1300	1	1	107B	Room SC-2 Custodial Storage outside Classroom 107	no	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1300	1	1	108	Classroom 108	yes	W1	Plaster	Blue	Partially Inaccessible	0	23.4	Positive
1300	1	1	108	Classroom 108	yes	W2	Plaster	Blue	Partially Inaccessible/chipping	20	27	Positive
1300	1	1	108	Classroom 108	yes	W3	Plaster	Blue	Partially Inaccessible/flaking	10	28.8	Positive
1300	1	1	108	Classroom 108	yes	W4	Wood	Varnish	Partially Inaccessible	0	0.02	Negative
1300	1	1	108	Classroom 108	yes	Ceiling	Plaster	Tan	Efflorescence/flaking	40	26.9	Positive

				Inspection Dates: May 2020			School District of Philadelphia					
				Name of Inspector: Paul Davis			Lead Safe Certification Assessment Report					
				Inspection Company: VERTEX			1300 A.D. Harrington ES/1301 Harrington Annex School					
ULCS#	Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1300	1	1	108	Classroom 108	yes	Floor	Wood	Varnish	N/A	N/A	N/A	N/A
1300	1	1	108B	Classroom 108 Storage	yes	W1	Plaster	Blue	Efflorescence/flaking	25	19.2	Positive
1300	1	1	108B	Classroom 108 Storage	yes	W2	Plaster	Blue	None	0	N/A	N/A
1300	1	1	108B	Classroom 108 Storage	yes	W3	Plaster	Blue	Flaking	75	21.4	Positive
1300	1	1	108B	Classroom 108 Storage	yes	W4	Plaster	Blue	flaking/broken plaster/efflorescence	8	23.9	Positive
1300	1	1	108B	Classroom 108 Storage	yes	Ceiling	Concrete	Blue	None	0	N/A	N/A
1300	1	1	108B	Classroom 108 Storage	yes	Floor	Wood	Varnish	N/A	N/A	N/A	N/A
1300	1	1	108A	Storage across from Classroom 108	yes	W1	Brick	White	Partially Inaccessible	0	0.01	Negative
1300	1	1	108A	Storage across from Classroom 108	yes	W2	Brick	White	Partially Inaccessible	0	0.02	Negative
1300	1	1	108A	Storage across from Classroom 108	yes	W3	Brick	White	Partially Inaccessible	0	0.03	Negative
1300	1	1	108A	Storage across from Classroom 108	yes	Pipe	Metal	White	Flaking	12	0.19	Negative
1300	1	1	108A	Storage across from Classroom 108	yes	W4	CMU	White	Partially Inaccessible	0	0.02	Negative
1300	1	1	108A	Storage across from Classroom 108	yes	Ceiling	Concrete	White	None	0	N/A	N/A
1300	1	1	108A	Storage across from Classroom 108	yes	Duct Work	Metal	White	Flaking	20	0.02	Negative
1300	1	1	108A	Storage across from Classroom 108	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1300	1	1	109	Classroom 109	yes	W1	CMU	Beige	Flaking	1	0	Negative
1300	1	1	109	Classroom 109	yes	Door Frame	Metal	Grey	Chipping	8	0.06	Negative
1300	1	1	109	Classroom 109	yes	W2	CMU	Beige	Partially Inaccessible	0	0.13	Negative
1300	1	1	109	Classroom 109	yes	W3	CMU	Beige	Partially Inaccessible	0	0	Negative
1300	1	1	109	Classroom 109	yes	Univent	Metal	Beige	chipping/rusting	7	1.4	Positive
1300	1	1	109	Classroom 109	yes	W4	CMU	Beige	Partially Inaccessible	0	0	Negative
1300	1	1	109	Classroom 109	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1300	1	1	109	Classroom 109	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1300	1	1	109A	Classroom 109 Storage	yes	W1	CMU	Beige	Partially Inaccessible	0	0	Negative
1300	1	1	109A	Classroom 109 Storage	yes	W2	CMU	Beige	Partially Inaccessible	0	0	Negative
1300	1	1	109A	Classroom 109 Storage	yes	W3	CMU	Beige	Partially Inaccessible	0	0	Negative
1300	1	1	109A	Classroom 109 Storage	yes	W4	CMU	Beige	Partially Inaccessible	0	0	Negative
1300	1	1	109A	Classroom 109 Storage	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1300	1	1	109A	Classroom 109 Storage	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1300	1	1		Classroom 109 Small Closet	yes	W1	CMU	White	None	0	N/A	N/A
1300	1	1		Classroom 109 Small Closet	yes	W2	CMU	White	None	0	N/A	N/A
1300	1	1		Classroom 109 Small Closet	yes	W3	CMU	White	None	0	N/A	N/A
1300	1	1		Classroom 109 Small Closet	yes	W4	CMU	White	None	0	N/A	N/A
1300	1	1		Classroom 109 Small Closet	yes	Pipe	Metal	White	Chipping	1	0.26	Negative
1300	1	1		Classroom 109 Small Closet	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1300	1	1		Classroom 109 Small Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1300	1	1	109B	Room 109B Book Closet	yes	W1	CMU	White	None	0	N/A	N/A
1300	1	1	109B	Room 109B Book Closet	yes	W2	CMU	Orange	None	0	N/A	N/A
1300	1	1	109B	Room 109B Book Closet	yes	W3	CMU	Yellow	None	0	N/A	N/A
1300	1	1	109B	Room 109B Book Closet	yes	W4	CMU	Purple	None	0	N/A	N/A
1300	1	1	109B	Room 109B Book Closet	yes	Ceiling	Concrete	White	None	0	N/A	N/A
1300	1	1	109B	Room 109B Book Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1300	1	1	110	Room 110 IMC Library	yes	W1	CMU	Beige	Partially Inaccessible	0	0	Negative
1300	1	1	110	Room 110 IMC Library	yes	W1	metal	Brown	Partially Inaccessible	0	0.1	Negative

				Inspection Dates: May 2020			School District of Philadelphia					
				Name of Inspector: Paul Davis			Lead Safe Certification Assessment Report					
				Inspection Company: VERTEX			1300 A.D. Harrington ES/1301 Harrington Annex School					
ULCS#	Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1300	1	1	110	Room 110 IMC Library	yes	W2	CMU	Brown	Partially Inaccessible	0	0.02	Negative
1300	1	1	110	Room 110 IMC Library	yes	W3	CMU	Beige	Partially Inaccessible	0	0.01	Negative
1300	1	1	110	Room 110 IMC Library	yes	Column	Concrete	Blue	Chipping	4	0	Negative
1300	1	1	110	Room 110 IMC Library	yes	Univent	Metal	Beige	Chipping	5	0.01	Negative
1300	1	1	110	Room 110 IMC Library	yes	W4	CMU	Tan	None	0	N/A	N/A
1300	1	1	110	Room 110 IMC Library	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1300	1	1	110	Room 110 IMC Library	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1300	1	1	110A	Library Office	yes	W1	Metal	Brown	Partially Inaccessible	0	0.06	Negative
1300	1	1	110A	Library Office	yes	W2	Metal	Brown	Partially Inaccessible	0	0.07	Negative
1300	1	1	110A	Library Office	yes	W3	CMU	Beige	None	0	N/A	N/A
1300	1	1	110A	Library Office	yes	W4	CMU	Beige	None	0	N/A	N/A
1300	1	1	110A	Library Office	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1300	1	1	110A	Library Office	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1300	1	1	110B	Climate Manager Office	yes	W1	CMU	Beige	None	0	N/A	N/A
1300	1	1	110B	Climate Manager Office	yes	W2	CMU	Beige	Partially Inaccessible	0	0	Negative
1300	1	1	110B	Climate Manager Office	yes	W3	CMU	Beige	Partially Inaccessible	0	0	Negative
1300	1	1	110B	Climate Manager Office	yes	W4	CMU	Beige	None	0	N/A	N/A
1300	1	1	110B	Climate Manager Office	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1300	1	1	110B	Climate Manager Office	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1300	1	1	110C	Climate Manager Office	yes	W1	CMU	Beige	None	0	N/A	N/A
1300	1	1	110C	Climate Manager Office	yes	W2	CMU	Beige	None	0	N/A	N/A
1300	1	1	110C	Climate Manager Office	yes	W3	CMU	Beige	Partially Inaccessible	0	0	Negative
1300	1	1	110C	Climate Manager Office	yes	W4	CMU	Beige	None	0	N/A	N/A
1300	1	1	110C	Climate Manager Office	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1300	1	1	110C	Climate Manager Office	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1300	1	1	110D	Boy's Restroom	yes	W1	CMU	Blue/White	None	0	N/A	N/A
1300	1	1	110D	Boy's Restroom	yes	W2	CMU	Blue/White	Flaking	6	0	Negative
1300	1	1	110D	Boy's Restroom	yes	W3	CMU	Blue/White	None	0	N/A	N/A
1300	1	1	110D	Boy's Restroom	yes	W4	CMU	Blue/White	None	0	N/A	N/A
1300	1	1	110D	Boy's Restroom	yes	Ceiling	Sheetrock	White	None	0	N/A	N/A
1300	1	1	110D	Boy's Restroom	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1300	1	1	110E	Custodial Closet across from Library	no	W1	CMU	White	None	0	N/A	N/A
1300	1	1	110E	Custodial Closet across from Library	no	W2	CMU	White	Partially Inaccessible	0	0	Negative
1300	1	1	110E	Custodial Closet across from Library	no	W3	CMU	White	None	0	N/A	N/A
1300	1	1	110E	Custodial Closet across from Library	no	Ductwork	Metal	White	Flaking	2	0.02	Negative
1300	1	1	110E	Custodial Closet across from Library	no	W4	CMU	White	None	0	N/A	N/A
1300	1	1	110E	Custodial Closet across from Library	no	Ceiling	Concrete	White	None	0	N/A	N/A
1300	1	1	110E	Custodial Closet across from Library	no	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1300	1	1	111	Girl's Restroom	yes	W1	CMU	Blue	None	0	N/A	N/A
1300	1	1	111	Girl's Restroom	yes	W2	CMU	Blue	None	0	N/A	N/A
1300	1	1	111	Girl's Restroom	yes	W3	CMU	Beige	Holes	2	0	Negative
1300	1	1	111	Girl's Restroom	yes	W4	CMU	Beige	None	0	N/A	N/A
1300	1	1	111	Girl's Restroom	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1300	1	1	111	Girl's Restroom	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1300	1	1	111E	Men's Restroom next to Room 107	yes	W1	CMU	Blue/White	None	0	N/A	N/A

				Inspection Dates: May 2020				School District of Philadelphia				
				Name of Inspector: Paul Davis				Lead Safe Certification Assessment Report				
				Inspection Company: VERTEX				1300 A.D. Harrington ES/1301 Harrington Annex School				
ULCS#	Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1300	1	1	111E	Men's Restroom next to Room 107	yes	W2	CMU	Blue/White	None	0	N/A	N/A
1300	1	1	111E	Men's Restroom next to Room 107	yes	W3	CMU	Blue/White	None	0	N/A	N/A
1300	1	1	111E	Men's Restroom next to Room 107	yes	Radiator	metal	Grey	Flaking	2	0.02	Negative
1300	1	1	111E	Men's Restroom next to Room 107	yes	W4	CMU	Blue/White	None	0	N/A	N/A
1300	1	1	111E	Men's Restroom next to Room 107	yes	Ceiling	Plaster	Blue/White	None	0	N/A	N/A
1300	1	1	111E	Men's Restroom next to Room 107	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1300	1	1	106E	Auditorium	yes	W1	Wood	Varnish	Chipping	1	0	Negative
1300	1	1	106E	Auditorium	yes	W2	CMU	White	None	0	N/A	N/A
1300	1	1	106E	Auditorium	yes	W2	Wood	Varnish	Scrapes	30	0	Negative
1300	1	1	106E	Auditorium	yes	W3	Wood	Varnish	Scrapes	10	0	Negative
1300	1	1	106E	Auditorium	yes	W4	Wood	Varnish	Chipping	10	0.01	Negative
1300	1	1	106E	Auditorium	yes	W4	CMU	White	None	0	N/A	N/A
1300	1	1	106E	Auditorium	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1300	1	1	106E	Auditorium	yes	Ceiling	Wood	Varnish	None	0	N/A	N/A
1300	1	1	106E	Auditorium	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1300	1	1	106F	Stage	yes	W1	CMU	White	Partially Inaccessible/efflorescence	1	0	Negative
1300	1	1	106F	Stage	yes	W2	CMU	White	Holes	2	0.06	Negative
1300	1	1	106F	Stage	yes	W3	CMU	White	Partially Inaccessible	0	0.01	Negative
1300	1	1	106F	Stage	yes	W4	CMU	White	Partially Inaccessible	0	0.03	Negative
1300	1	1	106F	Stage	yes	Ceiling	Concrete	Tan	None	0	N/A	N/A
1300	1	1	106F	Stage	yes	Floor	Wood	Varnish	Chipping	10	0	Negative
1300	1	1	105E	Foyer Left of Auditorium	yes	W1	Brick	White	Partially Inaccessible	0	0.08	Negative
1300	1	1	105E	Foyer Left of Auditorium	yes	W2	CMU	White	Partially Inaccessible	0	0.04	Negative
1300	1	1	105E	Foyer Left of Auditorium	yes	W3	Brick	White	None	0	N/A	N/A
1300	1	1	105E	Foyer Left of Auditorium	yes	W4	CMU	White	None	0	N/A	N/A
1300	1	1	105E	Foyer Left of Auditorium	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1300	1	1	105E	Foyer Left of Auditorium	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1300	1	1	105F	Control Room Left of Stage	yes	W1	CMU	White	Partially Inaccessible	0	0	Negative
1300	1	1	105F	Control Room Left of Stage	yes	W2	Brick	White	Partially Inaccessible	0	0.01	Negative
1300	1	1	105F	Control Room Left of Stage	yes	W3	CMU	White	Partially Inaccessible	0	0	Negative
1300	1	1	105F	Control Room Left of Stage	yes	W4	Brick	White	None	0	N/A	N/A
1300	1	1	105F	Control Room Left of Stage	yes	Ceiling	Concrete	White	None	0	N/A	N/A
1300	1	1	105F	Control Room Left of Stage	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1300	1	1	H115	Foyer Right of Auditorium	yes	W1	Brick	White	Partially Inaccessible	0	0.05	Negative
1300	1	1	H115	Foyer Right of Auditorium	yes	W2	CMU	White	None	0	N/A	N/A
1300	1	1	H115	Foyer Right of Auditorium	yes	W3	Brick	White	Partially Inaccessible	0	0.05	Negative
1300	1	1	H115	Foyer Right of Auditorium	yes	W4	CMU	White	None	0	N/A	N/A
1300	1	1	H115	Foyer Right of Auditorium	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1300	1	1	H115	Foyer Right of Auditorium	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1300	1	1	107E	Fan Room Right of Stage	no	W1	CMU	White	Partially Inaccessible	0	0.05	Negative
1300	1	1	107E	Fan Room Right of Stage	no	W2	CMU	White	None	0	N/A	N/A
1300	1	1	107E	Fan Room Right of Stage	no	W3	CMU	White	Partially Inaccessible	0	0	Negative
1300	1	1	107E	Fan Room Right of Stage	no	W4	CMU	White	Partially Inaccessible	0	0	Negative

				Inspection Dates: May 2020			School District of Philadelphia					
				Name of Inspector: Paul Davis			Lead Safe Certification Assessment Report					
				Inspection Company: VERTEX			1300 A.D. Harrington ES/1301 Harrington Annex School					
ULCS#	Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1300	1	1	107E	Fan Room Right of Stage	no	Ceiling	Concrete	White	None	0	N/A	N/A
1300	1	1	107E	Fan Room Right of Stage	no	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1300	1	1	107E	Fan Room Right of Stage	no	Fan Unit/Ductwork	Metal	White	Flaking	4	0.01	Negative
1300	1	1	H19	Hallway at Classroom 101	yes	W1	Plaster	White	Flaking	2	22.5	Positive
1300	1	1	H19	Hallway at Classroom 101	yes	W2	Plaster	White	Chipping/Holes	3	18.1	Positive
1300	1	1	H19	Hallway at Classroom 101	yes	Small Electrical Access Doors	Metal	Brown	Chipping/Flaking	2	7.3	Positive
1300	1	1	H19	Hallway at Classroom 101	yes	W3	Plaster	White	None	0	N/A	N/A
1300	1	1	H19	Hallway at Classroom 101	yes	Door Frame	Metal	Blue	Chipping	10	0.18	Negative
1300	1	1	H19	Hallway at Classroom 101	yes	W4	Plaster	White	Flaking	4	15.5	Positive
1300	1	1	H19	Hallway at Classroom 101	yes	Door Frame	Metal	Blue	Chipping	5	0.03	Negative
1300	1	1	H19	Hallway at Classroom 101	yes	Radiator Cover	Metal	White	Chipping	2	0	Negative
1300	1	1	H19	Hallway at Classroom 101	yes	Pipe Outer Cover	Metal	Brown/White	Flaking	8	5.3	Positive
1300	1	1	H19	Hallway at Classroom 101	yes	Ceiling	Plaster	White	Efflorescence/flaking	15	18.3	Positive
1300	1	1	H19	Hallway at Classroom 101	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1300	1	1	H19	Hallway at Classroom 101	yes	Covebase	Concrete	Brown	Chipping	10	0.28	Negative
1300	1	1	H110	Hallway by Main Office	yes	W1	Plaster	Blue	Holes	3	14.7	Positive
1300	1	1	H110	Hallway by Main Office	yes	Bench	Wood	Varnish	Chipping	12	0.01	Negative
1300	1	1	H110	Hallway by Main Office	yes	W2	Plaster	Blue	Flaking	1	0.08	Negative
1300	1	1	H110	Hallway by Main Office	yes	W3	Plaster	Blue	Partially Inaccessible/flaking	2	15.6	Positive
1300	1	1	H110	Hallway by Main Office	yes	Radiator Cover	Metal	Tan	Chipping	1	0	Negative
1300	1	1	H110	Hallway by Main Office	yes	Pipe Outer Cover	Metal	Blue/Brown	Flaking	7	2.2	Positive
1300	1	1	H110	Hallway by Main Office	yes	W4	Plaster	Blue	Chipping	1	0.05	Negative
1300	1	1	H110	Hallway by Main Office	yes	Ceiling	Plaster	White	Flaking	10	31.6	Positive
1300	1	1	H110	Hallway by Main Office	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1300	1	1	H110	Hallway by Main Office	yes	Covebase	Concrete	Grey	Chipping	20	0.02	Negative
1300	1	1	H111	Hallway at Classrooms 107 and 108	yes	W1	Plaster	White	None	0	N/A	N/A
1300	1	1	H111	Hallway at Classrooms 107 and 108	yes	W2	Plaster	White	Flaking	2	22	Positive
1300	1	1	H111	Hallway at Classrooms 107 and 108	yes	Radiator Cover	Metal	White	Chipping	2	0	Negative
1300	1	1	H111	Hallway at Classrooms 107 and 108	yes	Door	Metal	Blue	Chipping	5	0	Negative
1300	1	1	H111	Hallway at Classrooms 107 and 108	yes	Door Frame	Metal	Blue	Chipping	5	0.01	Negative
1300	1	1	H111	Hallway at Classrooms 107 and 108	yes	Pipe Outer Cover	Metal	Brown/White	Chipping/Flaking	6	12.2	Positive
1300	1	1	H111	Hallway at Classrooms 107 and 108	yes	W3	Plaster	White	None	0	N/A	N/A
1300	1	1	H111	Hallway at Classrooms 107 and 108	yes	W4	Plaster	White	Flaking	2	25.2	Positive
1300	1	1	H111	Hallway at Classrooms 107 and 108	yes	Small Electrical Access Doors	Metal	Brown	Scrapes	1	2.5	Positive
1300	1	1	H111	Hallway at Classrooms 107 and 108	yes	Ceiling	Plaster	White	Flaking	5	24.7	Positive
1300	1	1	H111	Hallway at Classrooms 107 and 108	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1300	1	1	H112	Hallway at Library	yes	W1	CMU	White	None	0	N/A	N/A

				Inspection Dates: May 2020		School District of Philadelphia						
				Name of Inspector: Paul Davis		Lead Safe Certification Assessment Report						
				Inspection Company: VERTEX		1300 A.D. Harrington ES/1301 Harrington Annex School						
ULCS#	Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1300	1	1	H112	Hallway at Library	yes	Elevator Door Frame	Metal	Blue	Chipping	6	0.04	Negative
1300	1	1	H112	Hallway at Library	yes	W2	CMU	White	None	0	N/A	N/A
1300	1	1	H112	Hallway at Library	yes	W3	CMU	White	None	0	N/A	N/A
1300	1	1	H112	Hallway at Library	yes	Door Frame	Metal	Blue	Chipping	4	0.07	Negative
1300	1	1	H112	Hallway at Library	yes	Univent	Metal	Blue	Chipping	2	0.07	Negative
1300	1	1	H112	Hallway at Library	yes	W4	CMU	White	None	0	N/A	N/A
1300	1	1	H112	Hallway at Library	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1300	1	1	H112	Hallway at Library	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1300	1	1		Small Hallway at Stairwell #1	yes	W1	CMU	White	None	0	N/A	N/A
1300	1	1		Small Hallway at Stairwell #1	yes	W2	CMU	White	None	0	N/A	N/A
1300	1	1		Small Hallway at Stairwell #1	yes	Door	Metal	Blue	Chipping	1	0	Negative
1300	1	1		Small Hallway at Stairwell #1	yes	Door Frame	Metal	Blue	Chipping	4	0.01	Negative
1300	1	1		Small Hallway at Stairwell #1	yes	W3	CMU	White	None	0	N/A	N/A
1300	1	1		Small Hallway at Stairwell #1	yes	W4	CMU	White	None	0	N/A	N/A
1300	1	1		Small Hallway at Stairwell #1	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1300	1	1		Small Hallway at Stairwell #1	yes	Floor	Concrete	Black	Cracking	2	0.06	Negative
1300	1	1		Small Hallway at Stairwell #4	yes	Door Frame	Metal	Blue	Chipping	10	0.07	Negative
1300	1	1		Small Hallway at Stairwell #4	yes	W1	CMU	White	Chipping	1	0.01	Negative
1300	1	1		Small Hallway at Stairwell #4	yes	W2	CMU	White	None	0	N/A	N/A
1300	1	1		Small Hallway at Stairwell #4	yes	Pipe	Metal	Brown/White	Chipping	1	3	Positive
1300	1	1		Small Hallway at Stairwell #4	yes	W3	CMU	White	None	0	N/A	N/A
1300	1	1		Small Hallway at Stairwell #4	yes	W4	CMU	White	Chipping	1	0.02	Negative
1300	1	1		Small Hallway at Stairwell #4	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1300	1	1		Small Hallway at Stairwell #4	yes	Floor	Concrete	Black	Cracking	2	0.08	Negative
1300	1	1	S12	Stairwell #1	yes	W1	Brick	Beige	None	0	N/A	N/A
1300	1	1	S12	Stairwell #1	yes	W2	Brick	Beige	None	0	N/A	N/A
1300	1	1	S12	Stairwell #1	yes	W3	Brick	Beige	None	0	N/A	N/A
1300	1	1	S12	Stairwell #1	yes	W4	Brick	Beige	None	0	N/A	N/A
1300	1	1	S12	Stairwell #1	yes	Ceiling	Concrete	Beige	None	0	N/A	N/A
1300	1	1	S12	Stairwell #1	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1300	1	1	S14	Stairwell #2	yes	W1	Plaster	White	Faking/Hole	1	0.1	Negative
1300	1	1	S14	Stairwell #2	yes	W2	Plaster	White	None	0	N/A	N/A
1300	1	1	S14	Stairwell #2	yes	Pipe	Metal	Brown	Chipping/Flaking	3	0.26	Negative
1300	1	1	S14	Stairwell #2	yes	W3	Plaster	White	Flaking	1	0.05	Negative
1300	1	1	S14	Stairwell #2	yes	W4	Plaster	White	None	0	N/A	N/A
1300	1	1	S14	Stairwell #2	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1300	1	1	S14	Stairwell #2	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1300	1	1	S14	Stairwell #2	yes	Tread	Concrete	Grey	Chipping	20	3.8	Positive
1300	1	1	S14	Stairwell #2	yes	Riser	Concrete	Grey	Chipping	6	2.5	Positive
1300	1	1	S14	Stairwell #2	yes	Stringer	Concrete	Grey	Chipping/Flaking	12	3.8	Positive
1300	1	1	S14	Stairwell #2	yes	Spindels	Metal	Brown	Chipping	30	3.9	Positive
1300	1	1	S14	Stairwell #2	yes	Newell Post	Metal	Brown	Chipping	8	3.9	Positive
1300	1	1	S14	Stairwell #2	yes	Covebase	Concrete	Grey	Chipping	12	0.5	Negative
1300	1	1	S13	Stairwell #3	yes	W1	Plaster	White	None	0	N/A	N/A

				Inspection Dates: May 2020			School District of Philadelphia					
				Name of Inspector: Paul Davis			Lead Safe Certification Assessment Report					
				Inspection Company: VERTEX			1300 A.D. Harrington ES/1301 Harrington Annex School					
ULCS#	Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1300	1	1	S13	Stairwell #3	yes	Door	Metal	Blue	Chipping	6	0	Negative
1300	1	1	S13	Stairwell #3	yes	W2	Plaster	White	None	0	N/A	N/A
1300	1	1	S13	Stairwell #3	yes	W3	Plaster	White	None	0	N/A	N/A
1300	1	1	S13	Stairwell #3	yes	W4	Plaster	White	Spalling	1	25.7	Positive
1300	1	1	S13	Stairwell #3	yes	Pipe	Metal	Brown	Chipping/Flaking	3	0.1	Negative
1300	1	1	S13	Stairwell #3	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1300	1	1	S13	Stairwell #3	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1300	1	1	S13	Stairwell #3	yes	Tread	Concrete	Grey	Chipping	20	1.1	Positive
1300	1	1	S13	Stairwell #3	yes	Riser	Concrete	Grey	Chipping	8	4.8	Positive
1300	1	1	S13	Stairwell #3	yes	Stringer	Concrete	Grey	Chipping	12	1.4	Positive
1300	1	1	S13	Stairwell #3	yes	Spindels	Metal	Brown	Chipping	8	4.1	Positive
1300	1	1	S13	Stairwell #3	yes	Newell Post	Metal	Brown	Chipping	8	6.9	Positive
1300	1	1	S13	Stairwell #3	yes	Covebase	Concrete	Grey	Chipping	12	1.2	Positive
1300	1	1	S11	Stairwell #4	yes	W1	Brick	Beige	None	0	N/A	N/A
1300	1	1	S11	Stairwell #4	yes	W2	Brick	Beige	None	0	N/A	N/A
1300	1	1	S11	Stairwell #4	yes	Door Frame	Metal	Blue	Chipping	3	0.03	Negative
1300	1	1	S11	Stairwell #4	yes	W3	Brick	Beige	None	0	N/A	N/A
1300	1	1	S11	Stairwell #4	yes	W4	Brick	Beige	None	0	N/A	N/A
1300	1	1	S11	Stairwell #4	yes	Ceiling	Concrete	Beige	None	0	N/A	N/A
1300	1	1	S11	Stairwell #4	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1300	1	1	S18	Main Entrance	yes	W1	Plaster	Blue	Flaking	8	32	Positive
1300	1	1	S18	Main Entrance	yes	Door	Metal	Blue	Chipping	5	0	Negative
1300	1	1	S18	Main Entrance	yes	Door	Metal	Blue	Chipping	12	0.19	Negative
1300	1	1	S18	Main Entrance	yes	W2	Plaster	Blue	Partially Inaccessible/flaking	2	31.8	Positive
1300	1	1	S18	Main Entrance	yes	W3	Plaster	Blue	Flaking	1	18.3	Positive
1300	1	1	S18	Main Entrance	yes	W4	Plaster	Blue	Partially Inaccessible	0	29.9	Positive
1300	1	1	S18	Main Entrance	yes	Ceiling	Plaster	White	Flaking	5	32.4	Positive
1300	1	1	S18	Main Entrance	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1300	1	2	201	Classroom 201	yes	W1	Plaster	Blue	Partially Inaccessible/chipping	1	27.8	Positive
1300	1	2	201	Classroom 201	yes	W2	Wood	Varnish	Scrapes	4	0.04	Negative
1300	1	2	201	Classroom 201	yes	W3	Plaster	Blue	Flaking/Holes	12	31.4	Positive
1300	1	2	201	Classroom 201	yes	Radiator	Metal	Grey	Flaking	12	2.7	Positive
1300	1	2	201	Classroom 201	yes	W4	Plaster	Blue	Partially Inaccessible/chipping/flaking	2	25.4	Positive
1300	1	2	201	Classroom 201	yes	Ceiling	Plaster	White	Efflorescence/Flaking/Spalling	4	27.9	Positive
1300	1	2	201	Classroom 201	yes	Floor	Wood	Varnish	N/A	N/A	N/A	N/A
1300	1	2	201A	Classroom 201 Storage	yes	W1	Plaster	Blue	Chipping/Flaking/Hole	4	33.4	Positive
1300	1	2	201A	Classroom 201 Storage	yes	W2	Plaster	Blue	Flaking/Chipping	3	21.8	Positive
1300	1	2	201A	Classroom 201 Storage	yes	Radiator	Metal	Grey	Flaking	6	5.8	Positive
1300	1	2	201A	Classroom 201 Storage	yes	W3	Plaster	Blue	Cracking	1	19.6	Positive
1300	1	2	201A	Classroom 201 Storage	yes	Pipe	Metal	Blue	Flaking	10	21.1	Positive
1300	1	2	201A	Classroom 201 Storage	yes	W4	Plaster	Blue	None	0	N/A	N/A

				Inspection Dates: May 2020			School District of Philadelphia					
				Name of Inspector: Paul Davis			Lead Safe Certification Assessment Report					
				Inspection Company: VERTEX			1300 A.D. Harrington ES/1301 Harrington Annex School					
ULCS#	Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1300	1	2	201A	Classroom 201 Storage	yes	Ceiling	Concrete	Blue	None	0	N/A	N/A
1300	1	2	201A	Classroom 201 Storage	yes	Floor	Wood	Varnish	N/A	N/A	N/A	N/A
1300	1	2	202	Classroom 202	yes	W1	Plaster	Blue	Chipping/Flaking/Holes /Partially Inaccessible	10	29.8	Positive
1300	1	2	202	Classroom 202	yes	Door	Wood	Varnish	Chipping	2	0.02	Negative
1300	1	2	202	Classroom 202	yes	Door Frame	Wood	Varnish	Chipping	4	0.04	Negative
1300	1	2	202	Classroom 202	yes	W2	Plaster	Blue/White	Chipping/Flaking/Hole	10	26.8	Positive
1300	1	2	202	Classroom 202	yes	Chalkboard Frame	Wood	Varnish	Chipping	10	0.18	Negative
1300	1	2	202	Classroom 202	yes	W3	Plaster	Blue	Flaking	12	29.4	Positive
1300	1	2	202	Classroom 202	yes	Window Sill	Wood	Varnish	Chipping	8	0.2	Negative
1300	1	2	202	Classroom 202	yes	Window Frame	Wood	Varnish	Scrapes	2	0.21	Negative
1300	1	2	202	Classroom 202	yes	Radiator	Metal	Grey	Flaking	6	5.3	Positive
1300	1	2	202	Classroom 202	yes	W4	Wood	Varnish	Partially Inaccessible	0	0.03	Negative
1300	1	2	202	Classroom 202	yes	Ceiling	Plaster	White	Flaking	50	24.8	Positive
1300	1	2	202	Classroom 202	yes	Floor	Wood	Varnish	Chipping	20	0.01	Negative
1300	1	2	202	Classroom 202	yes	Baseboard	Wood	Varnish	Chipping	20	0.07	Negative
1300	1	2	202B	Classroom 202 Storage	yes	W1	Plaster	Blue	Flaking	1	25.6	Positive
1300	1	2	202B	Classroom 202 Storage	yes	W2	Plaster	Blue	None	0	N/A	N/A
1300	1	2	202B	Classroom 202 Storage	yes	W3	Plaster	Blue	Flaking	10	26.8	Positive
1300	1	2	202B	Classroom 202 Storage	yes	W4	Plaster	Blue	Flaking/Holes	2	33.2	Positive
1300	1	2	202B	Classroom 202 Storage	yes	Radiator	Metal	Grey	Flaking	4	17.6	Positive
1300	1	2	202B	Classroom 202 Storage	yes	Pipe Outer Cover	Metal	Blue	Flaking	2	23.3	Positive
1300	1	2	202B	Classroom 202 Storage	yes	Ceiling	Concrete	Blue	None	0	N/A	N/A
1300	1	2	202B	Classroom 202 Storage	yes	Floor	Wood	Varnish	N/A	N/A	N/A	N/A
1300	1	2	202A	Boy's Restroom	yes	W1	CMU	Blue/White	None	0	N/A	N/A
1300	1	2	202A	Boy's Restroom	yes	W2	CMU	Blue/White	None	0	N/A	N/A
1300	1	2	202A	Boy's Restroom	yes	W3	CMU	Blue/White	None	0	N/A	N/A
1300	1	2	202A	Boy's Restroom	yes	W4	CMU	Blue/White	Flaking	1	0.06	Negative
1300	1	2	202A	Boy's Restroom	yes	Ceiling	Plaster	White	Flaking	1	20.4	Positive
1300	1	2	202A	Boy's Restroom	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1300	1	2	203	Classroom 203	yes	W1	Plaster	Blue	Flaking	20	36.9	Positive
1300	1	2	203	Classroom 203	yes	Chalkboard Tray	Wood	Tan	Chipping	8	0.18	Negative
1300	1	2	203	Classroom 203	yes	W2	Plaster	Blue	Flaking	2	44.1	Positive
1300	1	2	203	Classroom 203	yes	Chalkboard Tray	Wood	Tan	Chipping	10	0.28	Negative
1300	1	2	203	Classroom 203	yes	W3	Plaster	Blue	Flaking	30	28.8	Positive
1300	1	2	203	Classroom 203	yes	Window Sill	Wood	Tan	Chipping	12	0.1	Negative
1300	1	2	203	Classroom 203	yes	Radiator	Metal	Grey	Flaking	6	8.8	Positive
1300	1	2	203	Classroom 203	yes	W4	Plaster	Blue	Flaking	15	24.2	Positive
1300	1	2	203	Classroom 203	yes	Chalkboard Tray	Wood	Tan	Chipping	10	0.2	Negative
1300	1	2	203	Classroom 203	yes	Ceiling	Plaster	White	Flaking	200	32.8	Positive
1300	1	2	203	Classroom 203	yes	Floor	Wood	Varnish	None	0	N/A	N/A

				Inspection Dates: May 2020		School District of Philadelphia						
				Name of Inspector: Paul Davis		Lead Safe Certification Assessment Report						
				Inspection Company: VERTEX		1300 A.D. Harrington ES/1301 Harrington Annex School						
ULCS#	Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1300	1	2	203A	Classroom 203 Large Storage	yes	W1	Plaster	Blue	Flaking	3	33.4	Positive
1300	1	2	203A	Classroom 203 Large Storage	yes	W2	Plaster	Blue	Flaking	1	28.3	Positive
1300	1	2	203A	Classroom 203 Large Storage	yes	Pipe Outer Cover	Metal	Blue	Flaking	3	18.7	Positive
1300	1	2	203A	Classroom 203 Large Storage	yes	Radiator	Metal	Grey	Flaking	2	6.1	Positive
1300	1	2	203A	Classroom 203 Large Storage	yes	W3	Plaster	Blue	Flaking	10	33.2	Positive
1300	1	2	203A	Classroom 203 Large Storage	yes	W4	Plaster	Blue	Flaking	1	31.1	Positive
1300	1	2	203A	Classroom 203 Large Storage	yes	Ceiling	Plaster	Blue	Flaking	12	30.4	Positive
1300	1	2	203A	Classroom 203 Large Storage	yes	Floor	Wood	Varnish	None	0	N/A	N/A
1300	1	2		Classroom 203 Small Storage	yes	W1	Plaster	Yellow	Flaking	40	18.5	Positive
1300	1	2		Classroom 203 Small Storage	yes	W2	Plaster	Yellow	Flaking	1	10.1	Positive
1300	1	2		Classroom 203 Small Storage	yes	W3	Plaster	Yellow	Partially Inaccessible/Flaking	25	14.4	Positive
1300	1	2		Classroom 203 Small Storage	yes	Shelving	Wood	Varnish	Chipping	10	0.06	Negative
1300	1	2		Classroom 203 Small Storage	yes	W4	Plaster	Yellow	Flaking	6	16	Positive
1300	1	2		Classroom 203 Small Storage	yes	Ceiling	Plaster	White	Flaking	60	29.6	Positive
1300	1	2		Classroom 203 Small Storage	yes	Floor	Wood	Varnish	None	0	N/A	N/A
1300	1	2	203B	Vice Principals Office	yes	W1	Plaster	Beige	None	0	N/A	N/A
1300	1	2	203B	Vice Principals Office	yes	W2	Plaster	Beige	None	0	N/A	N/A
1300	1	2	203B	Vice Principals Office	yes	W2	Sheetrock	Beige	Chipping	5	0	Negative
1300	1	2	203B	Vice Principals Office	yes	W3	Plaster	Beige	Flaking	1	3	Positive
1300	1	2	203B	Vice Principals Office	yes	W3	Sheetrock	Beige	Partially Inaccessible	0	0	Negative
1300	1	2	203B	Vice Principals Office	yes	W4	Plaster	Beige	Partially Inaccessible/chipping	8	32.1	Positive
1300	1	2	203B	Vice Principals Office	yes	Ceiling	Plaster	Beige	Flaking	10	26.7	Positive
1300	1	2	203B	Vice Principals Office	yes	Floor	Wood	Varnish	None	0	N/A	N/A
1300	1	2		Vice Principals Office Restroom	yes	W1	Plaster	Beige	Chipping	1	26.4	Positive
1300	1	2		Vice Principals Office Restroom	yes	W2	Plaster	Beige	None	0	N/A	N/A
1300	1	2		Vice Principals Office Restroom	yes	W3	Plaster	Beige	Cracking/Flaking	5	28.9	Positive
1300	1	2		Vice Principals Office Restroom	yes	W4	Plaster	Beige	Flaking	1	28.9	Positive
1300	1	2		Vice Principals Office Restroom	yes	Ceiling	Plaster	Beige	None	0	N/A	N/A
1300	1	2		Vice Principals Office Restroom	yes	Floor	Concrete	N/A	N/A	0	N/A	N/A
1300	1	2		Vice Principals Office Restroom	yes	Covebase	Concrete	Gray	Chipping/Flaking	3	1.8	Positive
1300	1	2		IT Room in Vice Principals Office	no	W1	Sheetrock	Beige	None	0	N/A	N/A
1300	1	2		IT Room in Vice Principals Office	no	W2	Sheetrock	Beige	None	0	N/A	N/A
1300	1	2		IT Room in Vice Principals Office	no	W3	Plaster	Beige	Flaking	3	28.3	Positive
1300	1	2		IT Room in Vice Principals Office	no	Radiator	Metal	Gray	Flaking	6	15.6	Positive
1300	1	2		IT Room in Vice Principals Office	no	W4	Plaster	Beige	Flaking/Crackin	5	4.2	Positive
1300	1	2		IT Room in Vice Principals Office	no	Ceiling	Plaster	Beige	Flaking	6	25.8	Positive
1300	1	2		IT Room in Vice Principals Office	no	Floor	Wood	Varnish	Chipping	20	0.03	Negative
1300	1	2	204	Classroom 204	yes	W1	Plaster	Blue	Cracking/Flaking	10	40.2	Positive
1300	1	2	204	Classroom 204	yes	W2	Wood	Varnish	Partially Inaccessible	0	0.07	Negative
1300	1	2	204	Classroom 204	yes	W3	Plaster	Blue	Flaking	15	28.4	Positive
1300	1	2	204	Classroom 204	yes	Raduator	Metal	Gray	Flaking	10	6.6	Positive

				Inspection Dates: May 2020			School District of Philadelphia						
				Name of Inspector: Paul Davis			Lead Safe Certification Assessment Report						
				Inspection Company: VERTEX			1300 A.D. Harrington ES/1301 Harrington Annex School						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	
1300	1	2	204	Classroom 204	yes	W4	Plaster	Blue	Partially Inaccessible/Flaking/Holes	15	33.4	Positive	
1300	1	2	204	Classroom 204	yes	Ceiling	Plaster	White	Alligating/Flaking	50	34.7	Positive	
1300	1	2	204	Classroom 204	yes	Floor	Wood	Varnish	None	0	N/A	N/A	
1300	1	2	204A	Classroom 204 Storage	yes	W1	Plaster	Blue	None	0	N/A	N/A	
1300	1	2	204A	Classroom 204 Storage	yes	W2	Plaster	Blue	Flaking	6	27.7	Positive	
1300	1	2	204A	Classroom 204 Storage	yes	W3	Plaster	Blue	Gouges	2	28.2	Positive	
1300	1	2	204A	Classroom 204 Storage	yes	W4	Plaster	Blue	Chipping	25	20.7	Positive	
1300	1	2	204A	Classroom 204 Storage	yes	Ceiling	Plaster	Blue	None	0	N/A	N/A	
1300	1	2	204A	Classroom 204 Storage	yes	Floor	Wood	Varnish	None	0	N/A	N/A	
1300	1	2	205	Classroom 205	yes	W1	Plaster	Blue	Cracking/Flaking	3	26.1	Positive	
1300	1	2	205	Classroom 205	yes	Door	Wood	Varnish	Chipping	6	0.03	Negative	
1300	1	2	205	Classroom 205	yes	Door frame	Wood	Varnish	Chipping	6	0.09	Negative	
1300	1	2	205	Classroom 205	yes	Chalkboard frame and tray	Wood	Blue	Chipping	8	0.19	Negative	
1300	1	2	205	Classroom 205	yes	W2	Wood	Varnish	Partially Inaccessible	0	0.02	Negative	
1300	1	2	205	Classroom 205	yes	W2	Plaster	Blue/White	Flaking	6	20.1	Positive	
1300	1	2	205	Classroom 205	yes	W3	Plaster	Blue	Flaking	25	8.1	Positive	
1300	1	2	205	Classroom 205	yes	Window Frames	Wood	Varnish	Cracking	8	0.19	Negative	
1300	1	2	205	Classroom 205	yes	Window Sills	Wood	Varnish	Chipping	12	0.3	Negative	
1300	1	2	205	Classroom 205	yes	Radiator	Metal	Gray	Flaking	6	6.2	Positive	
1300	1	2	205	Classroom 205	yes	W4	Wood	Varnish	Partially Inaccessible	0	0.05	Negative	
1300	1	2	205	Classroom 205	yes	W4	Plaster	Blue/White	Flaking	8	26.9	Positive	
1300	1	2	205	Classroom 205	yes	Ceiling	Plaster	White	Flaking	20	30.5	Positive	
1300	1	2	205	Classroom 205	yes	Floor	Wood	Varnish	Chipping	20	0.06	Negative	
1300	1	2	205	Classroom 205	yes	Baseboard	Wood	Varnish	Chipping	10	0.09	Negative	
1300	1	2	205A	Classroom 205 Storage	yes	W1	Plaster	Blue	None	0	N/A	N/A	
1300	1	2	205A	Classroom 205 Storage	yes	W2	Plaster	Blue	Flaking	50	23.3	Positive	
1300	1	2	205A	Classroom 205 Storage	yes	W3	Plaster	Blue	None	0	N/A	N/A	
1300	1	2	205A	Classroom 205 Storage	yes	W4	Plaster	Blue	None	0	N/A	N/A	
1300	1	2	205A	Classroom 205 Storage	yes	Ceiling	Plaster	Blue	Flaking	1	35.2	Positive	
1300	1	2	205A	Classroom 205 Storage	yes	Floor	Wood	Varnish	None	0	N/A	N/A	
1300	1	2	206	Classroom 206	yes	W1	Plaster	Blue	Flaking	6	28.2	Positive	
1300	1	2	206	Classroom 206	yes	W2	Plaster	Blue	Partially Inaccessible/Flaking	20	22.6	Positive	
1300	1	2	206	Classroom 206	yes	W3	Plaster	Blue	Flaking	8	26.9	Positive	
1300	1	2	206	Classroom 206	yes	Radiator	Metal	Gray	Flaking	4	5.1	Positive	
1300	1	2	206	Classroom 206	yes	W4	Plaster	Blue	Flaking	35	21.1	Positive	
1300	1	2	206	Classroom 206	yes	Ceiling	Plaster	White	Flaking	225	29.2	Positive	
1300	1	2	206	Classroom 206	yes	Floor	Wood	Varnish	None	0	N/A	N/A	
1300	1	2	206B	Classroom 206 Storage	yes	W1	Plaster	Blue	None	0	N/A	N/A	
1300	1	2	206B	Classroom 206 Storage	yes	W2	Plaster	Blue	Flaking	2	28.1	Positive	
1300	1	2	206B	Classroom 206 Storage	yes	W3	Plaster	Blue	Efflorescence/Flaking	12	30.7	Positive	
1300	1	2	206B	Classroom 206 Storage	yes	Radiator	Metal	Gray	Flaking	3	16.6	Positive	

				Inspection Dates: May 2020		School District of Philadelphia						
				Name of Inspector: Paul Davis		Lead Safe Certification Assessment Report						
				Inspection Company: VERTEX		1300 A.D. Harrington ES/1301 Harrington Annex School						
ULCS#	Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1300	1	2	206B	Classroom 206 Storage	yes	Pipe Outer Cover	Metal	Blue	Flaking	4	0.18	Negative
1300	1	2	206B	Classroom 206 Storage	yes	W4	Plaster	Blue	Flaking	6	28.8	Positive
1300	1	2	206B	Classroom 206 Storage	yes	Ceiling	Plaster	Blue	Flaking	40	22.9	Positive
1300	1	2	206B	Classroom 206 Storage	yes	Floor	Wood	Varnish	None	0	N/A	N/A
1300	1	2	206A	Girl's Restroom next to Classroom 206	yes	W1	CMU	Blue/White	None	0	N/A	N/A
1300	1	2	206A	Girl's Restroom next to Classroom 206	yes	W2	CMU	Blue/White	None	0	N/A	N/A
1300	1	2	206A	Girl's Restroom next to Classroom 206	yes	W3	CMU	Blue/White	None	0	N/A	N/A
1300	1	2	206A	Girl's Restroom next to Classroom 206	yes	Radiator	Metal	Grey	Flaking	8	0.05	Negative
1300	1	2	206A	Girl's Restroom next to Classroom 206	yes	W4	CMU	Blue/White	None	0	N/A	N/A
1300	1	2	206A	Girl's Restroom next to Classroom 206	yes	Ceiling	Plaster	White	Flaking	50	30.6	Positive
1300	1	2	206A	Girl's Restroom next to Classroom 206	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1300	1	2	207	Classroom 207	yes	W1	Plaster	Blue	Partially Inaccessible	0	28.9	Positive
1300	1	2	207	Classroom 207	yes	W2	Wood	Varnish	Partially Inaccessible	0	0.05	Negative
1300	1	2	207	Classroom 207	yes	W3	Plaster	Blue	Efflorescence/Flaking	20	30	Positive
1300	1	2	207	Classroom 207	yes	Radiator	Metal	Grey	Flaking	10	10.1	Positive
1300	1	2	207	Classroom 207	yes	W4	Plaster	Blue	Partially Inaccessible	0	28.1	Positive
1300	1	2	207	Classroom 207	yes	Ceiling	Plaster	White	Flaking	12	31.5	Positive
1300	1	2	207	Classroom 207	yes	Floor	Wood	Varnish	None	0	N/A	N/A
1300	1	2	207B	Classroom 207 Storage	yes	W1	Plaster	Blue	Holes	2	26.6	Positive
1300	1	2	207B	Classroom 207 Storage	yes	W2	Plaster	Blue	Flaking	2	25.2	Positive
1300	1	2	207B	Classroom 207 Storage	yes	W3	Plaster	Blue	Flaking	6	23.6	Positive
1300	1	2	207B	Classroom 207 Storage	yes	W4	Plaster	Blue	None	0	N/A	N/A
1300	1	2	207B	Classroom 207 Storage	yes	Ceiling	Plaster	Blue	Efflorescence/Flaking	4	29.5	Positive
1300	1	2	207B	Classroom 207 Storage	yes	Floor	Wood	Varnish	None	0	N/A	N/A
1300	1	2	207A	Room SC-6 Custodial Closet outside Room 207	no	W1	Plaster	Beige	Flaking	20	10.5	Positive
1300	1	2	207A	Room SC-6 Custodial Closet outside Room 207	no	W2	Plaster	Beige	Flaking	40	11	Positive
1300	1	2	207A	Room SC-6 Custodial Closet outside Room 207	no	W3	Plaster	Beige	Flaking	50	3	Positive
1300	1	2	207A	Room SC-6 Custodial Closet outside Room 207	no	Pipes	Metal	Beige	Flaking	20	20.4	Positive
1300	1	2	207A	Room SC-6 Custodial Closet outside Room 207	no	W4	Plaster	Beige	Flaking	40	8.3	Positive
1300	1	2	207A	Room SC-6 Custodial Closet outside Room 207	no	Ceiling	Plaster	Beige	Flaking	15	29.4	Positive
1300	1	2	207A	Room SC-6 Custodial Closet outside Room 207	no	Floor	Concrete	Gray	Chipping	10	0.06	Negative
1300	1	2	208	Classroom 208	yes	W1	Plaster	Blue	Partially Inaccessible/Flaking	2	30.5	Positive
1300	1	2	208	Classroom 208	yes	Door Frames	Wood	Varnish	Chipping	6	0.05	Negative
1300	1	2	208	Classroom 208	yes	Doors	Wood	Varnish	Chipping	2	0.04	Negative
1300	1	2	208	Classroom 208	yes	Chalkboard Frame/Tray	Wood	Varnish	Chipping	12	0.06	Negative
1300	1	2	208	Classroom 208	yes	W2	Plaster	Blue	None	0	N/A	N/A
1300	1	2	208	Classroom 208	yes	Book Case	Wood	Varnish	Chipping	10	0	Negative
1300	1	2	208	Classroom 208	yes	W3	Plaster	Blue	Efflorescence/Flaking	12	24.6	Positive
1300	1	2	208	Classroom 208	yes	Radiator	Metal	Gray	Flaking	3	3.9	Positive
1300	1	2	208	Classroom 208	yes	Window Frame	Wood	Varnish	Scrapes	10	0.18	Negative
1300	1	2	208	Classroom 208	yes	Window Sill	Wood	Varnish	Chipping	10	0.15	Negative
1300	1	2	208	Classroom 208	yes	W4	Wood	Varnish	Scrapes	5	0.04	Negative

				Inspection Dates: May 2020			School District of Philadelphia					
				Name of Inspector: Paul Davis			Lead Safe Certification Assessment Report					
				Inspection Company: VERTEX			1300 A.D. Harrington ES/1301 Harrington Annex School					
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1300	1	2	208	Classroom 208	yes	Ceiling	Plaster	White	Flaking	5	31.9	Positive
1300	1	2	208	Classroom 208	yes	Floor	Wood	Varnish	Chipping	10	0.01	Negative
1300	1	2	208	Classroom 208	yes	Baseboard	Wood	Varnish	Chipping	10	0.04	Negative
1300	1	2	208A	Classroom 208 Storage	yes	W1	Plaster	Blue	None	0	N/A	N/A
1300	1	2	208A	Classroom 208 Storage	yes	W2	Plaster	Blue	None	0	N/A	N/A
1300	1	2	208A	Classroom 208 Storage	yes	W3	Plaster	Blue	Partially Inaccessible	0	31	Positive
1300	1	2	208A	Classroom 208 Storage	yes	W4	Plaster	Blue	Efflorescence/Flaking	6	21.7	Positive
1300	1	2	208A	Classroom 208 Storage	yes	Pipe Outer Cover	Metal	Blue	Flaking	2	24.7	Positive
1300	1	2	208A	Classroom 208 Storage	yes	Radiator	Metal	Gray	Flaking	4	1.8	Positive
1300	1	2	208A	Classroom 208 Storage	yes	Ceiling	Concrete	Blue	None	0	N/A	N/A
1300	1	2	208A	Classroom 208 Storage	yes	Floor	Wood	Varnish	None	0	N/A	N/A
1300	1	2	H219	Hallway at Classrooms 201 and 202	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
1300	1	2	H219	Hallway at Classrooms 201 and 202	yes	W2	Plaster	White	None	0	N/A	N/A
1300	1	2	H219	Hallway at Classrooms 201 and 202	yes	W3	Plaster	White	None	0	N/A	N/A
1300	1	2	H219	Hallway at Classrooms 201 and 202	yes	Door Frame	Metal	Blue	Chipping	10	0.13	Negative
1300	1	2	H219	Hallway at Classrooms 201 and 202	yes	W4	Plaster	White	Flaking/Cracking	20	17.8	Positive
1300	1	2	H219	Hallway at Classrooms 201 and 202	yes	Access Panel	Metal	Brown	Scrapes	2	0.01	Negative
1300	1	2	H219	Hallway at Classrooms 201 and 202	yes	Pipe Outer Covers	Metal	Brown/White	Flaking	5	8.1	Positive
1300	1	2	H219	Hallway at Classrooms 201 and 202	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1300	1	2	H219	Hallway at Classrooms 201 and 202	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1300	1	2	H219	Hallway at Classrooms 201 and 202	yes	Covebase	Concrete	Brown	Chipping	15	0.1	Negative
1300	1	2	H218	Hallway at Classrooms 204 and 206	yes	W1	Plaster	White	Partially Inaccessible/Flaking/Chipping	5	21.4	Positive
1300	1	2	H218	Hallway at Classrooms 204 and 206	yes	W2	Plaster	White	Gouges	2	23.4	Positive
1300	1	2	H218	Hallway at Classrooms 204 and 206	yes	W3	Plaster	White	Flaking/Cracking	2	17.4	Positive
1300	1	2	H218	Hallway at Classrooms 204 and 206	yes	Pipe Outer Covers	Metal	Brown/White	Chipping	8	11.7	Positive
1300	1	2	H218	Hallway at Classrooms 204 and 206	yes	Door	Metal	Blue	Chipping	6	0	Negative
1300	1	2	H218	Hallway at Classrooms 204 and 206	yes	Door Frame	Metal	Blue	Chipping	8	0.02	Negative
1300	1	2	H218	Hallway at Classrooms 204 and 206	yes	W4	Plaster	White	None	0	N/A	N/A
1300	1	2	H218	Hallway at Classrooms 204 and 206	yes	Ceiling	Plaster	White	Flaking	35	29.6	Positive
1300	1	2	H218	Hallway at Classrooms 204 and 206	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1300	1	2	H218	Hallway at Classrooms 204 and 206	yes	Covebase	Concrete	Brown	Chipping	25	0.24	Negative
1300	1	2	H220	Hallway at Classrooms 207 and 208	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
1300	1	2	H220	Hallway at Classrooms 207 and 208	yes	Door/Door Frame	Metal	Brown	Chipping/Flaking	4	0.14	Negative
1300	1	2	H220	Hallway at Classrooms 207 and 208	yes	W2	Plaster	White	None	0	N/A	N/A
1300	1	2	H220	Hallway at Classrooms 207 and 208	yes	Radiator Cover	Metal	White	Chipping	4	0	Negative
1300	1	2	H220	Hallway at Classrooms 207 and 208	yes	Access Panel	Metal	Brown	Scrapes	2	0.02	Negative
1300	1	2	H220	Hallway at Classrooms 207 and 208	yes	Pipe Outer Cover	Metal	Brown/White	Flaking	4	2.3	Positive
1300	1	2	H220	Hallway at Classrooms 207 and 208	yes	W3	Plaster	White	None	0	N/A	N/A
1300	1	2	H220	Hallway at Classrooms 207 and 208	yes	Door Frame	Metal	Blue	Chipping	12	0.3	Negative

				Inspection Dates: May 2020			School District of Philadelphia					
				Name of Inspector: Paul Davis			Lead Safe Certification Assessment Report					
				Inspection Company: VERTEX			1300 A.D. Harrington ES/1301 Harrington Annex School					
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1300	1	2	H220	Hallway at Classrooms 207 and 208	yes	W4	Plaster	White	None	0	N/A	N/A
1300	1	2	H220	Hallway at Classrooms 207 and 208	yes	Ceiling	Plaster	White	Flaking	10	1.3	Positive
1300	1	2	H220	Hallway at Classrooms 207 and 208	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1300	1	2	H220	Hallway at Classrooms 207 and 208	yes	Covebase	Concrete	Brown	Chipping	12	0.09	Negative
1300	1	2		Elevator Lobby	yes	W1	CMU	White	Partially Inaccessible	0	0.08	Negative
1300	1	2		Elevator Lobby	yes	W2	CMU	White	None	0	N/A	N/A
1300	1	2		Elevator Lobby	yes	W3	CMU	White	None	0	N/A	N/A
1300	1	2		Elevator Lobby	yes	Elevator Door Frame	Metal	Blue	Chipping	8	0.3	Negative
1300	1	2		Elevator Lobby	yes	W4	CMU	White	None	0	N/A	N/A
1300	1	2		Elevator Lobby	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1300	1	2		Elevator Lobby	yes	Floor	Concrete	Brown	Chipping	100	0.02	Negative
1300	1	2	S22	Stairwell #1	yes	W1	Brick	Beige	None	0	N/A	N/A
1300	1	2	S22	Stairwell #1	yes	W2	Brick	Beige	None	0	N/A	N/A
1300	1	2	S22	Stairwell #1	yes	W3	Brick	Beige	None	0	N/A	N/A
1300	1	2	S22	Stairwell #1	yes	W4	Brick	Beige	None	0	N/A	N/A
1300	1	2	S22	Stairwell #1	yes	Window Frame	Metal	Gray	Flaking	3	3.6	Positive
1300	1	2	S22	Stairwell #1	yes	Ceiling	Concrete	Beige	Spalling/Cracking	6	17.1	Positive
1300	1	2	S22	Stairwell #1	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1300	1	2	S24	Stairwell #2	yes	W1	Plaster	White	None	0	N/A	N/A
1300	1	2	S24	Stairwell #2	yes	W2	Plaster	White	None	0	N/A	N/A
1300	1	2	S24	Stairwell #2	yes	Pipe	Metal	Brown/White	Chipping	3	7.4	Positive
1300	1	2	S24	Stairwell #2	yes	W3	Plaster	White	None	0	N/A	N/A
1300	1	2	S24	Stairwell #2	yes	W4	Plaster	White	None	0	N/A	N/A
1300	1	2	S24	Stairwell #2	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1300	1	2	S24	Stairwell #2	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1300	1	2	S24	Stairwell #2	yes	Tread	Concrete	Grey	Friction	30	3.7	Positive
1300	1	2	S24	Stairwell #2	yes	Riser	Concrete	Grey	Chipping	6	3	Positive
1300	1	2	S24	Stairwell #2	yes	Stringer	Concrete	Grey	Chipping	12	1.4	Positive
1300	1	2	S24	Stairwell #2	yes	Spindels	Metal	Brown	Chipping	30	3.5	Positive
1300	1	2	S24	Stairwell #2	yes	Newell Post	Metal	Brown	Chipping	8	3.3	Positive
1300	1	2	S24	Stairwell #2	yes	Covebase	Concrete	Grey	Chipping	12	0.8	Positive
1300	1	2	S23	Stairwell #3	yes	W1	Plaster	White	None	0	N/A	N/A
1300	1	2	S23	Stairwell #3	yes	W2	Plaster	White	None	0	N/A	N/A
1300	1	2	S23	Stairwell #3	yes	W3	Plaster	White	Flaking	1	29.6	Positive
1300	1	2	S23	Stairwell #3	yes	W4	Plaster	White	Spalling/Flaking	2	22.6	Positive
1300	1	2	S23	Stairwell #3	yes	Pipe	Metal	Brown/White	Chipping	2	0.2	Negative
1300	1	2	S23	Stairwell #3	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1300	1	2	S23	Stairwell #3	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1300	1	2	S23	Stairwell #3	yes	Tread	Concrete	Grey	Friction	30	3.3	Positive
1300	1	2	S23	Stairwell #3	yes	Riser	Concrete	Grey	Chipping	6	3.6	Positive
1300	1	2	S23	Stairwell #3	yes	Stringer	Concrete	Grey	Chipping	20	3.8	Positive
1300	1	2	S23	Stairwell #3	yes	Spindels	Metal	Brown	Chipping	12	2.8	Positive
1300	1	2	S23	Stairwell #3	yes	Newell Post	Metal	Brown	Chipping	8	5.1	Positive
1300	1	2	S23	Stairwell #3	yes	Covebase	Concrete	Grey	Chipping	12	0.8	Positive

				Inspection Dates: May 2020			School District of Philadelphia					
				Name of Inspector: Paul Davis			Lead Safe Certification Assessment Report					
				Inspection Company: VERTEX			1300 A.D. Harrington ES/1301 Harrington Annex School					
ULCS#	Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1300	1	2	S21	Stairwell #4	yes	W1	Brick	Beige	None	0	N/A	N/A
1300	1	2	S21	Stairwell #4	yes	W2	Brick	Beige	None	0	N/A	N/A
1300	1	2	S21	Stairwell #4	yes	W3	Brick	Beige	None	0	N/A	N/A
1300	1	2	S21	Stairwell #4	yes	W4	Brick	Beige	None	0	N/A	N/A
1300	1	2	S21	Stairwell #4	yes	Ceiling	Concrete	Beige	None	0	N/A	N/A
1300	1	2	S21	Stairwell #4	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1300	1	3	301	Classroom 301	yes	W1	Plaster	Blue	Cracking/Chipping	25	32.9	Positive
1300	1	3	301	Classroom 301	yes	W2	Wood	Varnish	Partially Inaccessible	0	0.06	Negative
1300	1	3	301	Classroom 301	yes	W3	Plaster	Blue	Flaking	10	25.8	Positive
1300	1	3	301	Classroom 301	yes	Radiator	Metal	Gray	Flaking	6	2.5	Positive
1300	1	3	301	Classroom 301	yes	W4	Plaster	Blue	Chipping/Flaking	10	33.3	Positive
1300	1	3	301	Classroom 301	yes	Ceiling	Plaster	White	Flaking	6	39.7	Positive
1300	1	3	301	Classroom 301	yes	Floor	Wood	Varnish	None	0	N/A	N/A
1300	1	3	301A	Classroom 301 Storage	yes	W1	Plaster	Blue	Chipping	6	21.1	Positive
1300	1	3	301A	Classroom 301 Storage	yes	W2	Plaster	Blue	Flaking	2	17.8	Positive
1300	1	3	301A	Classroom 301 Storage	yes	Radiator	Metal	Gray	Flaking	3	7.6	Positive
1300	1	3	301A	Classroom 301 Storage	yes	Pipe Outer Cover	Metal	Blue	Flaking	1	16.7	Positive
1300	1	3	301A	Classroom 301 Storage	yes	W3	Plaster	Blue	Chipping/Flaking	6	21.6	Positive
1300	1	3	301A	Classroom 301 Storage	yes	Pipe	Metal	Blue	Flaking	5	22.7	Positive
1300	1	3	301A	Classroom 301 Storage	yes	W4	Plaster	Blue	Chipping/Cracking	6	21.3	Positive
1300	1	3	301A	Classroom 301 Storage	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1300	1	3	301A	Classroom 301 Storage	yes	Floor	Wood	Varnish	None	0	N/A	N/A
1300	1	3	302	Classroom 302	yes	W1	Plaster	Blue	Alligating	100	33.1	Positive
1300	1	3	302	Classroom 302	yes	Door Frame	Wood	Varnish	Chipping	6	0.04	Negative
1300	1	3	302	Classroom 302	yes	Chalkboard Frame/Tray	Wood	Varnish	Chipping	12	0.13	Negative
1300	1	3	302	Classroom 302	yes	W2	Plaster	Blue	Alligating	100	33.9	Positive
1300	1	3	302	Classroom 302	yes	W3	Plaster	Blue	Alligating/Flaking	25	24.7	Positive
1300	1	3	302	Classroom 302	yes	Window Frame	Wood	Varnish	Scrapes	4	0.29	Negative
1300	1	3	302	Classroom 302	yes	Window Sill	Wood	Varnish	Chipping	10	0.6	Negative
1300	1	3	302	Classroom 302	yes	Radiator	Metal	Gray	Flaking	4	7.5	Positive
1300	1	3	302	Classroom 302	yes	W4	Wood	Varnish	Partially Inaccessible	0	0.04	Negative
1300	1	3	302	Classroom 302	yes	Ceiling	Plaster	White	Efflorescence/Flaking	3	35	Positive
1300	1	3	302	Classroom 302	yes	Floor	Wood	Varnish	Friction	20	0.01	Negative
1300	1	3	302	Classroom 302	yes	Baseboard	Wood	Varnish	Chipping	15	0.05	Negative
1300	1	3	302B	Classroom 302 Storage	yes	W1	Plaster	Blue	Chipping	3	24.5	Positive
1300	1	3	302B	Classroom 302 Storage	yes	W2	Plaster	Blue	Cracking	3	29	Positive
1300	1	3	302B	Classroom 302 Storage	yes	W3	Plaster	Blue	Flaking	1	26.8	Positive
1300	1	3	302B	Classroom 302 Storage	yes	W4	Plaster	Blue	Flaking	1	26.2	Positive
1300	1	3	302B	Classroom 302 Storage	yes	Radiator	Metal	Gray	Flaking	4	5.5	Positive
1300	1	3	302B	Classroom 302 Storage	yes	Pipe Outer Cover	Metal	Blue	Flaking	3	15.1	Positive
1300	1	3	302B	Classroom 302 Storage	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1300	1	3	302B	Classroom 302 Storage	yes	Floor	Wood	Varnish	None	0	N/A	N/A

				Inspection Dates: May 2020			School District of Philadelphia					
				Name of Inspector: Paul Davis			Lead Safe Certification Assessment Report					
				Inspection Company: VERTEX			1300 A.D. Harrington ES/1301 Harrington Annex School					
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1300	1	3	302A	Boy's Restroom	yes	W1	CMU	Blue/White	None	0	N/A	N/A
1300	1	3	302A	Boy's Restroom	yes	W2	CMU	Blue/White	None	0	N/A	N/A
1300	1	3	302A	Boy's Restroom	yes	W3	CMU	Blue/White	None	0	N/A	N/A
1300	1	3	302A	Boy's Restroom	yes	W4	CMU	Blue/White	Efflorescence/Spalling/ Flaking	12	0.05	Negative
1300	1	3	302A	Boy's Restroom	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1300	1	3	302A	Boy's Restroom	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1300	1	3	303	Classroom 303	yes	W1	Plaster	Blue	Alligating	125	31.7	Positive
1300	1	3	303	Classroom 303	yes	W2	Plaster	Blue	Partially Inaccessible/Chipping	4	26.5	Positive
1300	1	3	303	Classroom 303	yes	W3	Plaster	Blue	Efflorescence/Flaking	30	2.5	Positive
1300	1	3	303	Classroom 303	yes	Radiator	Metal	Gray	Flaking	10	5.2	Positive
1300	1	3	303	Classroom 303	yes	W4	Plaster	Blue	Alligating	100	17.8	Positive
1300	1	3	303	Classroom 303	yes	Ceiling	Plaster	White	Efflorescence/Flaking	6	43.2	Positive
1300	1	3	303	Classroom 303	yes	Floor	Wood	Varnish	None	0	N/A	N/A
1300	1	3	303B	Classroom 303 Storage	yes	W1	Plaster	Yellow	Alligating	150	37.7	Positive
1300	1	3	303B	Classroom 303 Storage	yes	W2	Plaster	Yellow	Alligating/Flaking	40	28.3	Positive
1300	1	3	303B	Classroom 303 Storage	yes	Pipe Outer Cover	Metal	Yellow	Flaking	2	21.8	Positive
1300	1	3	303B	Classroom 303 Storage	yes	W3	Plaster	Yellow	Alligating	225	31.5	Positive
1300	1	3	303B	Classroom 303 Storage	yes	W4	Plaster	Yellow	None	0	N/A	N/A
1300	1	3	303B	Classroom 303 Storage	yes	Ceiling	Plaster	White	Alligating	100	32.6	Positive
1300	1	3	303B	Classroom 303 Storage	yes	Floor	Wood	Varnish	None	0	N/A	N/A
1300	1	3	303A	Teacher's Lounge	yes	W1	Plaster	Yellow/White	Cracking	2	27.4	Positive
1300	1	3	303A	Teacher's Lounge	yes	W2	Plaster	Yellow/White	Flaking	2	27.2	Positive
1300	1	3	303A	Teacher's Lounge	yes	W3	Plaster	Yellow/White	Efflorescence/Flaking/ Broken	10	28.4	Positive
1300	1	3	303A	Teacher's Lounge	yes	Radiator	Metal	Gray	Flaking	12	5	Positive
1300	1	3	303A	Teacher's Lounge	yes	W4	Plaster	Yellow/White	Chipping/Cracking	8	31.5	Positive
1300	1	3	303A	Teacher's Lounge	yes	Ceiling	Plaster	White	Efflorescence/Flaking	4	35.8	Positive
1300	1	3	303A	Teacher's Lounge	yes	Floor	Wood	Varnish	None	0	N/A	N/A
1300	1	3	304	Classroom 304	yes	W1	Plaster	Blue	Partially Inaccessible/Flaking/C racking/Staple Holes	100	29.3	Positive
1300	1	3	304	Classroom 304	yes	W2	Wood	Varnish	Scrapes	4	0.03	Negative
1300	1	3	304	Classroom 304	yes	Door	Wood	Varnish	Chipping	4	0.04	Negative
1300	1	3	304	Classroom 304	yes	Door Frame	Wood	Varnish	Chipping	4	0.06	Negative
1300	1	3	304	Classroom 304	yes	Chalkboard Frame/Tray	Wood	Varnish	Chipping	12	0.15	Negative
1300	1	3	304	Classroom 304	yes	W2	Plaster	Blue/White	Cracking/Chipping/Fla king	5	27.7	Positive
1300	1	3	304	Classroom 304	yes	W3	Plaster	Blue	Efflorescence/Flaking/ Broken/Staple Holes	40	18.8	Positive
1300	1	3	304	Classroom 304	yes	Window Frame	Wood	Varnish	Scrapes	4	0.14	Negative
1300	1	3	304	Classroom 304	yes	Window Sill	Wood	Varnish	Chipping	8	0.15	Negative
1300	1	3	304	Classroom 304	yes	Radiator	Metal	Gray	Flaking	10	5.7	Positive

				Inspection Dates: May 2020				School District of Philadelphia				
				Name of Inspector: Paul Davis				Lead Safe Certification Assessment Report				
				Inspection Company: VERTEX				1300 A.D. Harrington ES/1301 Harrington Annex School				
ULCS#	Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1300	1	3	304	Classroom 304	yes	W4	Plaster	Blue	Flaking/Staple Holes	20	26.5	Positive
1300	1	3	304	Classroom 304	yes	Ceiling	Plaster	White	Efflorescence/flaking	8	35.5	Positive
1300	1	3	304	Classroom 304	yes	Floor	Wood	Varnish	Friction	20	0.04	Negative
1300	1	3	304	Classroom 304	yes	Baseboard	Wood	Varnish	Chipping	15	0.03	Negative
1300	1	3	304A	Classroom 304 Storage	yes	W1	No Access	No Access	No Access	No Access	No Access	No Access
1300	1	3	304A	Classroom 304 Storage	yes	W2	No Access	No Access	No Access	No Access	No Access	No Access
1300	1	3	304A	Classroom 304 Storage	yes	W3	No Access	No Access	No Access	No Access	No Access	No Access
1300	1	3	304A	Classroom 304 Storage	yes	W4	No Access	No Access	No Access	No Access	No Access	No Access
1300	1	3	304A	Classroom 304 Storage	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1300	1	3	304A	Classroom 304 Storage	yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1300	1	3	305	Classroom 305	yes	W1	Plaster	Blue/White	Chipping/Flaking/Cracking/Alligatoring	125	26.5	Positive
1300	1	3	305	Classroom 305	yes	W2	Wood	Varnish	Scrapes	15	0.13	Negative
1300	1	3	305	Classroom 305	yes	W2	Plaster	White/Blue	Alligatoring	30	22	Positive
1300	1	3	305	Classroom 305	yes	W3	Plaster	Blue	Efflorescence/Flaking	40	27.8	Positive
1300	1	3	305	Classroom 305	yes	Radiator	Metal	Gray	Flaking	15	4.5	Positive
1300	1	3	305	Classroom 305	yes	W4	Wood	Varnish	Scrapes	12	0.03	Negative
1300	1	3	305	Classroom 305	yes	Ceiling	Plaster	White	Flaking	2	37.5	Positive
1300	1	3	305	Classroom 305	yes	Floor	Wood	Varnish	None	0	N/A	N/A
1300	1	3	305A	Classroom 305 Storage	yes	W1	Plaster	Blue	None	0	N/A	N/A
1300	1	3	305A	Classroom 305 Storage	yes	W2	Plaster	Blue	Alligatoring	120	25.3	Positive
1300	1	3	305A	Classroom 305 Storage	yes	W3	Plaster	Blue	Alligatoring	50	29.1	Positive
1300	1	3	305A	Classroom 305 Storage	yes	W4	Plaster	Blue	Alligatoring/Flaking	150	23.4	Positive
1300	1	3	305A	Classroom 305 Storage	yes	Ceiling	Plaster	White	Alligatoring	100	36.2	Positive
1300	1	3	305A	Classroom 305 Storage	yes	Floor	Wood	Varnish	None	0	N/A	N/A
1300	1	3	306	Classroom 306	yes	W1	Plaster	Beige	None	0	N/A	N/A
1300	1	3	306	Classroom 306	yes	W2	Plaster	Beige	None	0	N/A	N/A
1300	1	3	306	Classroom 306	yes	W3	Plaster	Beige	None	0	N/A	N/A
1300	1	3	306	Classroom 306	yes	Radiator	Metal	Gray	Flaking	8	5.9	Positive
1300	1	3	306	Classroom 306	yes	W4	Wood	Varnish	None	N/A	N/A	N/A
1300	1	3	306	Classroom 306	yes	W4	Plaster	Beige	None	0	N/A	N/A
1300	1	3	306	Classroom 306	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1300	1	3	306	Classroom 306	yes	Floor	Wood	Varnish	None	0	N/A	N/A
1300	1	3	306B	Classroom 306 Storage	yes	W1	Plaster	Beige	None	0	N/A	N/A
1300	1	3	306B	Classroom 306 Storage	yes	W2	Plaster	Beige	None	0	N/A	N/A
1300	1	3	306B	Classroom 306 Storage	yes	W3	Plaster	Beige	None	0	N/A	N/A
1300	1	3	306B	Classroom 306 Storage	yes	Radiator	Metal	Gray	Flaking	2	9.1	Positive
1300	1	3	306B	Classroom 306 Storage	yes	W4	Plaster	Beige	None	0	N/A	N/A
1300	1	3	306B	Classroom 306 Storage	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1300	1	3	306B	Classroom 306 Storage	yes	Floor	Wood	Varnish	None	0	N/A	N/A
1300	1	3	306A	Girl's Restroom next to Classroom 306	yes	W1	CMU	Blue/White	None	0	N/A	N/A
1300	1	3	306A	Girl's Restroom next to Classroom 306	yes	W2	CMU	Blue/White	None	0	N/A	N/A
1300	1	3	306A	Girl's Restroom next to Classroom 306	yes	W3	CMU	Blue/White	None	0	N/A	N/A
1300	1	3	306A	Girl's Restroom next to Classroom 306	yes	Radiator	Metal	Gray	Flaking	9	3.9	Positive
1300	1	3	306A	Girl's Restroom next to Classroom 306	yes	W4	CMU	Blue/White	Flaking	2	0.02	Negative

				Inspection Dates: May 2020			School District of Philadelphia						
				Name of Inspector: Paul Davis			Lead Safe Certification Assessment Report						
				Inspection Company: VERTEX			1300 A.D. Harrington ES/1301 Harrington Annex School						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	
1300	1	3	306A	Girl's Restroom next to Classroom 306	yes	Ceiling	Plaster	White	Flaking	2	25.1	Positive	
1300	1	3	306A	Girl's Restroom next to Classroom 306	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
1300	1	3	306B	Room SC-8 Custodial Closet outside Classroom 306	no	W1	Plaster	Beige	Flaking	7	19.6	Positive	
1300	1	3	306B	Room SC-8 Custodial Closet outside Classroom 306	no	W2	Plaster	Beige	Flaking	30	15.3	Positive	
1300	1	3	306B	Room SC-8 Custodial Closet outside Classroom 306	no	W3	Plaster	Beige	Flaking	20	14	Positive	
1300	1	3	306B	Room SC-8 Custodial Closet outside Classroom 306	no	Pipes	Metal	Beige	Flaking	10	18.7	Positive	
1300	1	3	306B	Room SC-8 Custodial Closet outside Classroom 306	no	W4	Plaster	Beige	Flaking/Cracking	10	19.9	Positive	
1300	1	3	306B	Room SC-8 Custodial Closet outside Classroom 306	no	Ceiling	Plaster	Beige	Flaking	10	21.3	Positive	
1300	1	3	306B	Room SC-8 Custodial Closet outside Classroom 306	no	Floor	Concrete	Gray	Chipping	10	0.3	Negative	
1300	1	3	307	Classroom 307	yes	W1	Plaster	Blue	Chipping	20	27	Positive	
1300	1	3	307	Classroom 307	yes	W2	Wood	Varnish	None	0	N/A	N/A	
1300	1	3	307	Classroom 307	yes	W3	Plaster	Blue	Efflorescence/Flaking	20	29.5	Positive	
1300	1	3	307	Classroom 307	yes	Radiator	Metal	Gray	Flaking	15	6.4	Positive	
1300	1	3	307	Classroom 307	yes	W4	Plaster	Blue	Chipping/cracking	40	31.6	Positive	
1300	1	3	307	Classroom 307	yes	Ceiling	Plaster	White	Efflorescence/Flaking	5	38.3	Positive	
1300	1	3	307	Classroom 307	yes	Floor	Wood	Varnish	None	0	N/A	N/A	
1300	1	3	307A	Classroom 307 Storage	yes	W1	Plaster	Blue	Flaking	10	25.7	Positive	
1300	1	3	307A	Classroom 307 Storage	yes	W2	Plaster	Blue	Efflorescence/Cracking /Flaking	30	23.2	Positive	
1300	1	3	307A	Classroom 307 Storage	yes	Pipe Outer Cover	Metal	Blue	Chipping	2	10	Positive	
1300	1	3	307A	Classroom 307 Storage	yes	W3	Plaster	Blue	Flaking/Cracking	15	24.5	Positive	
1300	1	3	307A	Classroom 307 Storage	yes	W4	Plaster	Blue	Flaking/Cracking	30	25.8	Positive	
1300	1	3	307A	Classroom 307 Storage	yes	Ceiling	Plaster	Blue	Flaking	35	28.3	Positive	
1300	1	3	307A	Classroom 307 Storage	yes	Floor	Wood	Varnish	None	0	N/A	N/A	
1300	1	3	308	Classroom 308	yes	W1	Plaster	Beige	Partially Inaccessible/Alligatorin g/Flaking	100	33.6	Positive	
1300	1	3	308	Classroom 308	yes	Door	Wood	Varnish	Chipping	4	0.06	Negative	
1300	1	3	308	Classroom 308	yes	Door Frame	Wood	Varnish	Chipping	4	0.07	Negative	
1300	1	3	308	Classroom 308	yes	Chalk Board Frame/Tray	Wood	Varnish	Chipping	12	0.12	Negative	
1300	1	3	308	Classroom 308	yes	W2	Plaster	Beige	Alligatoring/Cracking	150	35	Positive	
1300	1	3	308	Classroom 308	yes	W3	Plaster	Beige	Efflorescence/Cracking /Flaking	35	26.9	Positive	
1300	1	3	308	Classroom 308	yes	Radiator	Metal	Gray	Flaking	10	4.9	Positive	
1300	1	3	308	Classroom 308	yes	Window Sill	Wood	Varnish	Chipping	20	0.27	Negative	
1300	1	3	308	Classroom 308	yes	Window Frame	Wood	Varnish	Scrapes	4	0.13	Negative	
1300	1	3	308	Classroom 308	yes	W4	Wood	Varnish	Scrapes	5	0.04	Negative	
1300	1	3	308	Classroom 308	yes	W4	Plaster	Beige	Efflorescence/Flaking	3	30	Positive	
1300	1	3	308	Classroom 308	yes	Ceiling	Plaster	White	Efflorescence/Flaking	10	38.2	Positive	
1300	1	3	308	Classroom 308	yes	Floor	Wood	Varnish	Friction	20	0	Negative	
1300	1	3	308	Classroom 308	yes	Baseboard	Wood	Varnish	Chipping	15	0.05	Negative	
1300	1	3	308A	Classroom 308 Storage	yes	W1	Plaster	Beige	Flaking	10	23.1	Positive	
1300	1	3	308A	Classroom 308 Storage	yes	W2	Plaster	Beige	Cracking	2	26.9	Positive	
1300	1	3	308A	Classroom 308 Storage	yes	W3	Plaster	Beige	Flaking	100	29.8	Positive	

				Inspection Dates: May 2020			School District of Philadelphia					
				Name of Inspector: Paul Davis			Lead Safe Certification Assessment Report					
				Inspection Company: VERTEX			1300 A.D. Harrington ES/1301 Harrington Annex School					
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1300	1	3	308A	Classroom 308 Storage	yes	W4	Plaster	Beige	Flaking	20	25.9	Positive
1300	1	3	308A	Classroom 308 Storage	yes	Radiator	Metal	Gray	Flaking	3	2.9	Positive
1300	1	3	308A	Classroom 308 Storage	yes	Pipe Outer Cover	Metal	White/Brown	Flaking	4	7.9	Positive
1300	1	3	308A	Classroom 308 Storage	yes	Ceiling	Plaster	White	Cracking/Flaking	2	37.5	Positive
1300	1	3	308A	Classroom 308 Storage	yes	Floor	Wood	Varnish	None	0	N/A	N/A
1300	1	3	308B	Elevator Foyer	yes	W1	CMU	Beige	Partially Inaccessible	0	0.02	Negative
1300	1	3	308B	Elevator Foyer	yes	W2	CMU	Beige	Partially Inaccessible	0	0.03	Negative
1300	1	3	308B	Elevator Foyer	yes	W3	CMU	Beige	Partially Inaccessible	0	0.03	Negative
1300	1	3	308B	Elevator Foyer	yes	Elevator Door Frame	Metal	Blue	Scrapes	5	0.04	Negative
1300	1	3	308B	Elevator Foyer	yes	W4	CMU	Beige	None	0	N/A	N/A
1300	1	3	308B	Elevator Foyer	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1300	1	3	308B	Elevator Foyer	yes	Floor	Concrete	Brown	Scrapes	50	0.09	Negative
1300	1	3	H323	Hallway at Classrooms 301 and 302	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
1300	1	3	H323	Hallway at Classrooms 301 and 302	yes	W2	Plaster	White	Efflorescence/Cracking/Flaking	8	27.2	Positive
1300	1	3	H323	Hallway at Classrooms 301 and 302	yes	W3	Plaster	White	None	0	N/A	N/A
1300	1	3	H323	Hallway at Classrooms 301 and 302	yes	Door	Metal	Blue	Chipping	4	0	Negative
1300	1	3	H323	Hallway at Classrooms 301 and 302	yes	Door Frame	Metal	Blue	Chipping	8	0.1	Negative
1300	1	3	H323	Hallway at Classrooms 301 and 302	yes	W4	Plaster	White	None	0	N/A	N/A
1300	1	3	H323	Hallway at Classrooms 301 and 302	yes	Radiator	Metal	Grey	Chipping/Flaking	6	6.8	Positive
1300	1	3	H323	Hallway at Classrooms 301 and 302	yes	Pipe Outer Covers	Metal	Brown	Chipping/Flaking	6	17.6	Positive
1300	1	3	H323	Hallway at Classrooms 301 and 302	yes	Ceiling	Plaster	White	Efflorescence	1	35.8	Positive
1300	1	3	H323	Hallway at Classrooms 301 and 302	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1300	1	3	H323	Hallway at Classrooms 301 and 302	yes	Covebase	Concrete	Brown	Chipping	15	1.2	Positive
1300	1	3	H324	Hallway at Classrooms 304 and 306	yes	W1	Plaster	White	Flaking	1	21.4	Positive
1300	1	3	H324	Hallway at Classrooms 304 and 306	yes	Door/Door Frame	Metal	Brown	Chipping	12	0.16	Negative
1300	1	3	H324	Hallway at Classrooms 304 and 306	yes	W2	Plaster	White	None	0	N/A	N/A
1300	1	3	H324	Hallway at Classrooms 304 and 306	yes	W3	Plaster	White	Spalling/Flaking	3	18.3	Positive
1300	1	3	H324	Hallway at Classrooms 304 and 306	yes	Radiator	Metal	Gray	Flaking	15	0.01	Negative
1300	1	3	H324	Hallway at Classrooms 304 and 306	yes	Door	Metal	Blue	Chipping	6	0	Negative
1300	1	3	H324	Hallway at Classrooms 304 and 306	yes	Pipe Outer Cover	Metal	Brown	Flaking/Chipping	5	1.5	Positive
1300	1	3	H324	Hallway at Classrooms 304 and 306	yes	W4	Plaster	White	Cracking	4	18.7	Positive
1300	1	3	H324	Hallway at Classrooms 304 and 306	yes	Ceiling	Plaster	White	Efflorescence/Flaking	10	29.8	Positive
1300	1	3	H324	Hallway at Classrooms 304 and 306	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1300	1	3	H324	Hallway at Classrooms 304 and 306	yes	Covebase	Concrete	Brown	Chipping	12	1	Positive
1300	1	3	H325	Hallway at Classrooms 307 and 308	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
1300	1	3	H325	Hallway at Classrooms 307 and 308	yes	W2	Plaster	Beige	Chipping	5	21.1	Positive
1300	1	3	H325	Hallway at Classrooms 307 and 308	yes	Access Panel	Metal	Brown	Scrapes	2	0.01	Negative
1300	1	3	H325	Hallway at Classrooms 307 and 308	yes	Pipe Outer Cover	Metal	White/Brown	Flaking	6	10.1	Positive
1300	1	3	H325	Hallway at Classrooms 307 and 308	yes	W3	Plaster	White	None	0	N/A	N/A

				Inspection Dates: May 2020			School District of Philadelphia					
				Name of Inspector: Paul Davis			Lead Safe Certification Assessment Report					
				Inspection Company: VERTEX			1300 A.D. Harrington ES/1301 Harrington Annex School					
ULCS#	Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1300	1	3	H325	Hallway at Classrooms 307 and 308	yes	Door Frame	Metal	Blue	Chipping/Flaking	10	0.26	Negative
1300	1	3	H325	Hallway at Classrooms 307 and 308	yes	W4	Plaster	White	Efflorescence/Cracking	5	18.9	Positive
1300	1	3	H325	Hallway at Classrooms 307 and 308	yes	Ceiling	Plaster	White	Efflorescence/Flaking	3	30.3	Positive
1300	1	3	H325	Hallway at Classrooms 307 and 308	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1300	1	3	H325	Hallway at Classrooms 307 and 308	yes	Covebase	Concrete	Brown	Chipping	12	1.3	Positive
1300	1	3	S32	Stairwell #1	yes	W1	Brick	Beige	None	0	N/A	N/A
1300	1	3	S32	Stairwell #1	yes	W2	Brick	Beige	None	0	N/A	N/A
1300	1	3	S32	Stairwell #1	yes	W3	Brick	Beige	None	0	N/A	N/A
1300	1	3	S32	Stairwell #1	yes	Pipe	Metal	Gray	Flaking	20	0.6	Negative
1300	1	3	S32	Stairwell #1	yes	W4	Brick	Beige	Flaking	1	14.2	Positive
1300	1	3	S32	Stairwell #1	yes	Window Frame	Metal	Gray	Flaking	6	5.1	Positive
1300	1	3	S32	Stairwell #1	yes	Door Frame	Metal	Blue	Chipping	4	0.16	Negative
1300	1	3	S32	Stairwell #1	yes	Ceiling	Concrete	Beige	None	0	N/A	N/A
1300	1	3	S32	Stairwell #1	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1300	1	3	S34	Stairwell #2	yes	W1	Plaster	White	Flaking	1	0.06	Negative
1300	1	3	S34	Stairwell #2	yes	W2	Plaster	White	Flaking	10	23.6	Positive
1300	1	3	S34	Stairwell #2	yes	Pipe	Metal	Brown/White	Chipping	2	0.9	Positive
1300	1	3	S34	Stairwell #2	yes	W3	Plaster	White	None	0	N/A	N/A
1300	1	3	S34	Stairwell #2	yes	W4	Plaster	White	Flaking	1	22.2	Positive
1300	1	3	S34	Stairwell #2	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1300	1	3	S34	Stairwell #2	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1300	1	3	S34	Stairwell #2	yes	Tread	Concrete	Grey	Friction	15	2.4	Positive
1300	1	3	S34	Stairwell #2	yes	Riser	Concrete	Grey	Chipping	6	2	Positive
1300	1	3	S34	Stairwell #2	yes	Stringer	Concrete	Grey	Chipping	6	1.9	Positive
1300	1	3	S34	Stairwell #2	yes	Spindels	Metal	Brown	Chipping	12	3.4	Positive
1300	1	3	S34	Stairwell #2	yes	Newell Post	Metal	Brown	Chipping	4	4.8	Positive
1300	1	3	S34	Stairwell #2	yes	Covebase	Concrete	Grey	Chipping	6	1.5	Positive
1300	1	3	S33	Stairwell #3	yes	W1	Plaster	White	None	0	N/A	N/A
1300	1	3	S33	Stairwell #3	yes	W2	Plaster	White	None	0	N/A	N/A
1300	1	3	S33	Stairwell #3	yes	W3	Plaster	White	Flaking/cracking	1	15.4	Positive
1300	1	3	S33	Stairwell #3	yes	W4	Plaster	White	Chipping	5	21.7	Positive
1300	1	3	S33	Stairwell #3	yes	Pipe	Metal	Gray/White	Chipping	3	0.17	Negative
1300	1	3	S33	Stairwell #3	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1300	1	3	S33	Stairwell #3	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1300	1	3	S33	Stairwell #3	yes	Tread	Concrete	Grey	Friction	12	4.4	Positive
1300	1	3	S33	Stairwell #3	yes	Riser	Concrete	Grey	Chipping	6	2.2	Positive
1300	1	3	S33	Stairwell #3	yes	Stringer	Concrete	Grey	Chipping	6	1.1	Positive
1300	1	3	S33	Stairwell #3	yes	Spindels	Metal	Brown	Chipping	12	3.7	Positive
1300	1	3	S33	Stairwell #3	yes	Newell Post	Metal	Brown	Chipping	4	3.8	Positive
1300	1	3	S33	Stairwell #3	yes	Covebase	Concrete	Grey	Chipping	12	0.8	Positive
1300	1	3	S31	Stairwell #4	yes	W1	Brick	Beige	None	0	N/A	N/A
1300	1	3	S31	Stairwell #4	yes	W2	Brick	Beige	None	0	N/A	N/A
1300	1	3	S31	Stairwell #4	yes	W3	Brick	Beige	None	0	N/A	N/A
1300	1	3	S31	Stairwell #4	yes	W4	Brick	Beige	None	0	N/A	N/A
1300	1	3	S31	Stairwell #4	yes	Window Frame	Metal	Gray	Flaking	4	9.3	Positive

				Inspection Dates: May 2020			School District of Philadelphia					
				Name of Inspector: Paul Davis			Lead Safe Certification Assessment Report					
				Inspection Company: VERTEX			1300 A.D. Harrington ES/1301 Harrington Annex School					
ULCS#	Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1300	1	3	S31	Stairwell #4	yes	Ceiling	Concrete	Beige	Flaking/Cracking	10	15.6	Positive
1300	1	3	S31	Stairwell #4	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1300	1	B	001B	Classroom B1	yes	W1	Plaster	Beige	Flaking	20	29.3	Positive
1300	1	B	001B	Classroom B1	yes	Pipes	Metal	Beige/Brown	Chipping	1	2.8	Positive
1300	1	B	001B	Classroom B1	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
1300	1	B	001B	Classroom B1	yes	W3	Plaster	Beige	Efflorescence/Flaking	8	32.7	Positive
1300	1	B	001B	Classroom B1	yes	Radiator Cover	Metal	Brown	Scrapes	6	0.06	Negative
1300	1	B	001B	Classroom B1	yes	W4	Plaster	Beige	Efflorescence/Flaking	6	27	Positive
1300	1	B	001B	Classroom B1	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1300	1	B	001B	Classroom B1	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1300	1	B	00B1A	Classroom B1 Storage	yes	W1	Brick	Beige	Partially Inaccessible	0	0.14	Negative
1300	1	B	00B1A	Classroom B1 Storage	yes	W2	Brick	Beige	Partially Inaccessible	0	0.11	Negative
1300	1	B	00B1A	Classroom B1 Storage	yes	W3	Brick	Beige	Partially Inaccessible	0	0.21	Negative
1300	1	B	00B1A	Classroom B1 Storage	yes	Column	Plaster	Beige	Cracking/Broken	10	3.5	Positive
1300	1	B	00B1A	Classroom B1 Storage	yes	W4	Brick	Beige	Partially Inaccessible	0	0.14	Negative
1300	1	B	00B1A	Classroom B1 Storage	yes	Ceiling	Plaster	Beige	Flaking	12	7.9	Positive
1300	1	B	00B1A	Classroom B1 Storage	yes	Duct Work	Metal	Beige	Flaking	6	3.6	Positive
1300	1	B	00B1A	Classroom B1 Storage	yes	Floor	Wood	Varnish	None	0	N/A	N/A
1300	1	B	00B1A	Classroom B1 Storage	yes	Shelving	Wood	Beige	Partially Inaccessible	0	0.09	Negative
1300	1	B	00B1B	Classroom B1 Restroom	yes	W1	Plaster	Beige	Cracking	10	15.5	Positive
1300	1	B	00B1B	Classroom B1 Restroom	yes	W2	Sheetrock	Beige	Gouges	1	0	Negative
1300	1	B	00B1B	Classroom B1 Restroom	yes	W3	Concrete	Beige	None	0	N/A	N/A
1300	1	B	00B1B	Classroom B1 Restroom	yes	W4	Plaster	Beige	Flaking/cracking	3	12.7	Positive
1300	1	B	00B1B	Classroom B1 Restroom	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1300	1	B	00B1B	Classroom B1 Restroom	yes	Floor	Concrete	Brown	Chipping	20	0.07	Negative
1300	1	B	00B1B	Classroom B1 Restroom	yes	Covebase	Concrete	Brown	Chipping	3	0.12	Negative
1300	1	B	00B1B	Classroom B1 Restroom	yes	Bathroom stalls	Wood	Brown	Chipping	4	0.01	Negative
1300	1	B	00B1C	Classroom B1 Coat Closet	yes	W1	Plaster	Beige	Cracking	2	18	Positive
1300	1	B	00B1C	Classroom B1 Coat Closet	yes	W2	Plaster	Beige	Broken/Flaking	6	26.5	Positive
1300	1	B	00B1C	Classroom B1 Coat Closet	yes	W3	Plaster	Beige	Cracking	2	11.7	Positive
1300	1	B	00B1C	Classroom B1 Coat Closet	yes	W4	Plaster	Beige	Cracking	20	27.5	Positive
1300	1	B	00B1C	Classroom B1 Coat Closet	yes	Ceiling	Plaster	Beige	None	0	N/A	N/A
1300	1	B	00B1C	Classroom B1 Coat Closet	yes	Radiator	Metal	Gray	Flaking	4	8.5	Positive
1300	1	B	00B1C	Classroom B1 Coat Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1300	1	B	00B1D	Classroom B1 Storage next to Restroom	no	W1	Sheetrock	N/A	N/A	N/A	N/A	N/A
1300	1	B	00B1D	Classroom B1 Storage next to Restroom	no	W2	Plaster	Beige	Flaking/Cracking	60	10.6	Positive
1300	1	B	00B1D	Classroom B1 Storage next to Restroom	no	W3	Plaster	Beige	Flaking/Broken	75	11.6	Positive
1300	1	B	00B1D	Classroom B1 Storage next to Restroom	no	W4	Plaster	Beige	Flaking/Broken	50	6.5	Positive
1300	1	B	00B1D	Classroom B1 Storage next to Restroom	no	Pipe	Metal	Beige	Flaking	20	7.4	Positive
1300	1	B	00B1D	Classroom B1 Storage next to Restroom	no	Ceiling	Plaster	Beige	Flaking/Broken	70	7.2	Positive
1300	1	B	00B1D	Classroom B1 Storage next to Restroom	no	Duct Work	Metal	Gray	Flaking	10	4	Positive
1300	1	B	00B1D	Classroom B1 Storage next to Restroom	no	Radiator	Metal	Gray	Flaking	12	4.9	Positive
1300	1	B	00B1D	Classroom B1 Storage next to Restroom	no	Floor	Concrete	Gray	Chipping	10	0.07	Negative
1300	1	B	002B	Classroom B2	yes	W1	CMU	Blue/Beige	Partially Inaccessible	0	0.01	Negative
1300	1	B	002B	Classroom B2	yes	Door Frame	Metal	Brown	Chipping	2	0.02	Negative

				Inspection Dates: May 2020			School District of Philadelphia					
				Name of Inspector: Paul Davis			Lead Safe Certification Assessment Report					
				Inspection Company: VERTEX			1300 A.D. Harrington ES/1301 Harrington Annex School					
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1300	1	B	002B	Classroom B2	yes	W2	CMU	Blue/Beige	Partially Inaccessible	0	0.05	Negative
1300	1	B	002B	Classroom B2	yes	Duct work	Metal	Beige	Flaking	2	0.08	Negative
1300	1	B	002B	Classroom B2	yes	W3	CMU	Blue/Beige	Partially Inaccessible	0	0	Negative
1300	1	B	002B	Classroom B2	yes	Radiator Cover	Metal	Blue	Partially Inaccessible	0	0.01	Negative
1300	1	B	002B	Classroom B2	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
1300	1	B	002B	Classroom B2	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1300	1	B	002B	Classroom B2	yes	Ceiling	Concrete	Beige	Flaking	15	0.04	Negative
1300	1	B	002B	Classroom B2	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1300	1	B	023B	Classroom B2 Restroom	yes	W1	CMU	Beige	Holes	1	0	Negative
1300	1	B	023B	Classroom B2 Restroom	yes	W2	CMU	Beige	None	0	N/A	N/A
1300	1	B	023B	Classroom B2 Restroom	yes	W3	CMU	Beige	None	0	N/A	N/A
1300	1	B	023B	Classroom B2 Restroom	yes	Access Door	Metal	Beige	Flaking	1	0	Negative
1300	1	B	023B	Classroom B2 Restroom	yes	W4	CMU	Beige	None	0	N/A	N/A
1300	1	B	023B	Classroom B2 Restroom	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1300	1	B	023B	Classroom B2 Restroom	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1300	1	B	024B	Classroom B2 Storage	yes	W1	CMU	Beige	Partially Inaccessible	0	0	Negative
1300	1	B	024B	Classroom B2 Storage	yes	W2	CMU	Beige	Partially Inaccessible	0	0	Negative
1300	1	B	024B	Classroom B2 Storage	yes	W3	CMU	Beige	Partially Inaccessible	0	0	Negative
1300	1	B	024B	Classroom B2 Storage	yes	W4	CMU	Beige	Partially Inaccessible	0	0	Negative
1300	1	B	024B	Classroom B2 Storage	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1300	1	B	024B	Classroom B2 Storage	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1300	1	B	00B3	Classroom B3	yes	W1	CMU	White/Brown	Partially Inaccessible	0	0	Negative
1300	1	B	00B3	Classroom B3	yes	Door Frame	Metal	Blue/Brown	Chipping	6	0.01	Negative
1300	1	B	00B3	Classroom B3	yes	W2	CMU	White	Partially Inaccessible	0	0.01	Negative
1300	1	B	00B3	Classroom B3	yes	W3	CMU	White	Partially Inaccessible	0	0	Negative
1300	1	B	00B3	Classroom B3	yes	Univent	Metal	Beige	Chipping	10	0	Negative
1300	1	B	00B3	Classroom B3	yes	Radiator Cover	Metal	Beige	Partially Inaccessible	0	0	Negative
1300	1	B	00B3	Classroom B3	yes	W4	CMU	White	Partially Inaccessible	0	0	Negative
1300	1	B	00B3	Classroom B3	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1300	1	B	00B3	Classroom B3	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1300	1	B		Classroom B3 Coat Cubby	yes	W1	CMU	Brown	Chipping	1	0	Negative
1300	1	B		Classroom B3 Coat Cubby	yes	W2	CMU	Brown	None	0	N/A	N/A
1300	1	B		Classroom B3 Coat Cubby	yes	W3	CMU	Brown	None	0	N/A	N/A
1300	1	B		Classroom B3 Coat Cubby	yes	W4	CMU	Brown	None	0	N/A	N/A
1300	1	B		Classroom B3 Coat Cubby	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1300	1	B		Classroom B3 Coat Cubby	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1300	1	B		Classroom B3 Closet	yes	W1	No Access	No Access	No Access	No Access	No Access	No Access
1300	1	B		Classroom B3 Closet	yes	W2	No Access	No Access	No Access	No Access	No Access	No Access
1300	1	B		Classroom B3 Closet	yes	W3	No Access	No Access	No Access	No Access	No Access	No Access
1300	1	B		Classroom B3 Closet	yes	W4	No Access	No Access	No Access	No Access	No Access	No Access
1300	1	B		Classroom B3 Closet	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1300	1	B		Classroom B3 Closet	yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1300	1	B	00B4	Classroom B4	yes	W1	CMU	Beige	Partially Inaccessible	0	0	Negative
1300	1	B	00B4	Classroom B4	yes	W1	Sheetrock	White	Chipping	2	0.01	Negative
1300	1	B	00B4	Classroom B4	yes	Door Frame	Metal	Blue	Chipping	15	0.06	Negative

				Inspection Dates: May 2020			School District of Philadelphia					
				Name of Inspector: Paul Davis			Lead Safe Certification Assessment Report					
				Inspection Company: VERTEX			1300 A.D. Harrington ES/1301 Harrington Annex School					
ULCS#	Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1300	1	B	00B4	Classroom B4	yes	W2	CMU	Beige	Partially Inaccessible	0	0.05	Negative
1300	1	B	00B4	Classroom B4	yes	Shelving	Metal	Beige	Partially Inaccessible/Chipping	5	0	Negative
1300	1	B	00B4	Classroom B4	yes	W3	CMU	Beige	Partially Inaccessible	0	0	Negative
1300	1	B	00B4	Classroom B4	yes	Radiator Cover	Metal	Blue	Chipping	4	0.01	Negative
1300	1	B	00B4	Classroom B4	yes	Univent	Metal	Blue	Chipping	10	0	Negative
1300	1	B	00B4	Classroom B4	yes	W4	CMU	Beige	Partially Inaccessible	0	0.03	Negative
1300	1	B	00B4	Classroom B4	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1300	1	B	00B4	Classroom B4	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1300	1	B	00B4A	Classroom B4 Storage	yes	W1	No Access	No Access	No Access	No Access	No Access	No Access
1300	1	B	00B4A	Classroom B4 Storage	yes	W2	No Access	No Access	No Access	No Access	No Access	No Access
1300	1	B	00B4A	Classroom B4 Storage	yes	W3	No Access	No Access	No Access	No Access	No Access	No Access
1300	1	B	00B4A	Classroom B4 Storage	yes	W4	No Access	No Access	No Access	No Access	No Access	No Access
1300	1	B	00B4A	Classroom B4 Storage	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1300	1	B	00B4A	Classroom B4 Storage	yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1300	1	B		Classroom B4 Closet	yes	W1	No Access	No Access	No Access	No Access	No Access	No Access
1300	1	B		Classroom B4 Closet	yes	W2	No Access	No Access	No Access	No Access	No Access	No Access
1300	1	B		Classroom B4 Closet	yes	W3	No Access	No Access	No Access	No Access	No Access	No Access
1300	1	B		Classroom B4 Closet	yes	W4	No Access	No Access	No Access	No Access	No Access	No Access
1300	1	B		Classroom B4 Closet	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1300	1	B		Classroom B4 Closet	yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1300	1	B		Book Closet next to Classroom B5	yes	W1	CMU	White	Partially Inaccessible	0	0	Negative
1300	1	B		Book Closet next to Classroom B5	yes	W2	CMU	White	Partially Inaccessible	0	0	Negative
1300	1	B		Book Closet next to Classroom B5	yes	W3	CMU	White	Partially Inaccessible	0	0	Negative
1300	1	B		Book Closet next to Classroom B5	yes	W4	CMU	White	Partially Inaccessible	0	0	Negative
1300	1	B		Book Closet next to Classroom B5	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1300	1	B		Book Closet next to Classroom B5	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1300	1	B	00B5	Classroom B5	yes	W1	CMU	White	Partially Inaccessible	0	0.01	Negative
1300	1	B	00B5	Classroom B5	yes	W1	Sheetrock	White	Chipping	5	0.01	Negative
1300	1	B	00B5	Classroom B5	yes	W2	CMU	White	Partially Inaccessible	0	0	Negative
1300	1	B	00B5	Classroom B5	yes	W3	CMU	White	Partially Inaccessible	0	0	Negative
1300	1	B	00B5	Classroom B5	yes	Univent	Metal	Brown	Chipping	6	0.02	Negative
1300	1	B	00B5	Classroom B5	yes	Radiator Cover	Metal	Brown	Chipping	4	0.01	Negative
1300	1	B	00B5	Classroom B5	yes	W4	CMU	White	Partially Inaccessible	0	0	Negative
1300	1	B	00B5	Classroom B5	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1300	1	B	00B5	Classroom B5	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1300	1	B		Classroom B5 Coat Cubby	yes	W1	CMU	White	Cracking	1	0	Negative
1300	1	B		Classroom B5 Coat Cubby	yes	W2	CMU	White	Partially Inaccessible	0	0	Negative
1300	1	B		Classroom B5 Coat Cubby	yes	W3	CMU	White	None	0	N/A	N/A
1300	1	B		Classroom B5 Coat Cubby	yes	W4	CMU	White	None	0	N/A	N/A
1300	1	B		Classroom B5 Coat Cubby	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1300	1	B		Classroom B5 Coat Cubby	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1300	1	B		Classroom B5 Closet	yes	W1	No Access	No Access	No Access	No Access	No Access	No Access
1300	1	B		Classroom B5 Closet	yes	W2	No Access	No Access	No Access	No Access	No Access	No Access
1300	1	B		Classroom B5 Closet	yes	W3	No Access	No Access	No Access	No Access	No Access	No Access

				Inspection Dates: May 2020		School District of Philadelphia						
				Name of Inspector: Paul Davis		Lead Safe Certification Assessment Report						
				Inspection Company: VERTEX		1300 A.D. Harrington ES/1301 Harrington Annex School						
ULCS#	Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1300	1	B		Classroom B5 Closet	yes	W4	No Access	No Access	No Access	No Access	No Access	No Access
1300	1	B		Classroom B5 Closet	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1300	1	B		Classroom B5 Closet	yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1300	1	B	00B6	Classroom B6	yes	W1	CMU	Peach/Purple	Partially Inaccessible	0	0	Negative
1300	1	B	00B6	Classroom B6	yes	Window Frame	Metal	Blue	Chipping	2	0.01	Negative
1300	1	B	00B6	Classroom B6	yes	W1	Sheetrock	Blue	Chipping/Flaking	3	0.01	Negative
1300	1	B	00B6	Classroom B6	yes	W2	CMU	White	None	0	N/A	N/A
1300	1	B	00B6	Classroom B6	yes	W3	CMU	Multicolored	Partially Inaccessible	0	0	Negative
1300	1	B	00B6	Classroom B6	yes	Univent	Metal	Blue	Scrapes	2	0.01	Negative
1300	1	B	00B6	Classroom B6	yes	Radiator Cover	Metal	Blue	Scrapes	4	0	Negative
1300	1	B	00B6	Classroom B6	yes	W4	CMU	White	Partially Inaccessible	0	0	Negative
1300	1	B	00B6	Classroom B6	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1300	1	B	00B6	Classroom B6	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1300	1	B	007C	Classroom B6 Counseling Office (near hallway)	yes	W1	CMU	White	Partially Inaccessible	0	0	Negative
1300	1	B	007C	Classroom B6 Counseling Office (near hallway)	yes	Door Frame	Metal	Beige/Brown	Chipping	3	0.08	Negative
1300	1	B	007C	Classroom B6 Counseling Office (near hallway)	yes	W2	CMU	White	Partially Inaccessible	0	0	Negative
1300	1	B	007C	Classroom B6 Counseling Office (near hallway)	yes	W3	CMU	White	Partially Inaccessible	0	0	Negative
1300	1	B	007C	Classroom B6 Counseling Office (near hallway)	yes	W4	CMU	White	Partially Inaccessible	0	0	Negative
1300	1	B	007C	Classroom B6 Counseling Office (near hallway)	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1300	1	B	007C	Classroom B6 Counseling Office (near hallway)	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1300	1	B	008C	Classroom B6 Office	yes	W1	CMU	Beige/Blue	None	0	N/A	N/A
1300	1	B	008C	Classroom B6 Office	yes	Door Frame	Metal	Brown/Blue	Chipping	6	0.01	Negative
1300	1	B	008C	Classroom B6 Office	yes	W2	CMU	Beige/Blue	None	0	N/A	N/A
1300	1	B	008C	Classroom B6 Office	yes	Window Frame	Metal	Blue	Chipping	2	0.07	Negative
1300	1	B	008C	Classroom B6 Office	yes	W3	CMU	Beige/Blue	Partially Inaccessible	0	0	Negative
1300	1	B	008C	Classroom B6 Office	yes	W4	CMU	Beige/Blue	Partially Inaccessible	0	0	Negative
1300	1	B	008C	Classroom B6 Office	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1300	1	B	008C	Classroom B6 Office	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1300	1	B	009C	Classroom B6 Office (near hallway)	yes	W1	CMU	White	Partially Inaccessible/Chipping	1	0	Negative
1300	1	B	009C	Classroom B6 Office (near hallway)	yes	W2	CMU	White	Partially Inaccessible	0	0	Negative
1300	1	B	009C	Classroom B6 Office (near hallway)	yes	W3	CMU	White	Partially Inaccessible	0	0	Negative
1300	1	B	009C	Classroom B6 Office (near hallway)	yes	Radiator Cover	Metal	Brown	Partially Inaccessible/Scrapes	2	0.02	Negative
1300	1	B	009C	Classroom B6 Office (near hallway)	yes	W4	CMU	White	Cracking	4	0	Negative
1300	1	B	009C	Classroom B6 Office (near hallway)	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1300	1	B	009C	Classroom B6 Office (near hallway)	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1300	1	B	008B	Classroom B8	yes	W1	No Access	No Access	No Access	No Access	No Access	No Access
1300	1	B	008B	Classroom B8	yes	W2	No Access	No Access	No Access	No Access	No Access	No Access
1300	1	B	008B	Classroom B8	yes	W3	No Access	No Access	No Access	No Access	No Access	No Access
1300	1	B	008B	Classroom B8	yes	W4	No Access	No Access	No Access	No Access	No Access	No Access
1300	1	B	008B	Classroom B8	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1300	1	B	008B	Classroom B8	yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1300	1	B	002C	Teacher's Lounge	yes	W1	Brick	Blue	None	0	N/A	N/A
1300	1	B	002C	Teacher's Lounge	yes	Door Frame	Metal	Blue/Beige	Chipping	5	0.05	Negative

				Inspection Dates: May 2020			School District of Philadelphia					
				Name of Inspector: Paul Davis			Lead Safe Certification Assessment Report					
				Inspection Company: VERTEX			1300 A.D. Harrington ES/1301 Harrington Annex School					
ULCS#	Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1300	1	B	002C	Teacher's Lounge	yes	W2	Brick	Blue	None	0	N/A	N/A
1300	1	B	002C	Teacher's Lounge	yes	W3	Brick	Blue	None	0	N/A	N/A
1300	1	B	002C	Teacher's Lounge	yes	Radiator Cover	Metal	Beige	Chipping	6	0	Negative
1300	1	B	002C	Teacher's Lounge	yes	W4	CMU	Blue	None	0	N/A	N/A
1300	1	B	002C	Teacher's Lounge	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1300	1	B	002C	Teacher's Lounge	yes	Ceiling	Concrete	White	Flaking	15	7.3	Positive
1300	1	B	002C	Teacher's Lounge	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1300	1	B	017C	Women's Restroom outside Teacher's Lounge	yes	W1	CMU	Blue	None	0	N/A	N/A
1300	1	B	017C	Women's Restroom outside Teacher's Lounge	yes	W2	CMU	Blue	None	0	N/A	N/A
1300	1	B	017C	Women's Restroom outside Teacher's Lounge	yes	W3	CMU	Blue	None	0	N/A	N/A
1300	1	B	017C	Women's Restroom outside Teacher's Lounge	yes	W4	CMU	Blue	None	0	N/A	N/A
1300	1	B	017C	Women's Restroom outside Teacher's Lounge	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1300	1	B	017C	Women's Restroom outside Teacher's Lounge	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1300	1	B	002E	Men's Restroom next to Boy's Restroom	yes	W1	CMU	Blue	None	0	N/A	N/A
1300	1	B	002E	Men's Restroom next to Boy's Restroom	yes	Door Frame	Metal	Blue	Chipping	4	0.07	Negative
1300	1	B	002E	Men's Restroom next to Boy's Restroom	yes	W2	CMU	Blue	None	0	N/A	N/A
1300	1	B	002E	Men's Restroom next to Boy's Restroom	yes	W3	CMU	Blue	None	0	N/A	N/A
1300	1	B	002E	Men's Restroom next to Boy's Restroom	yes	W4	CMU	Blue	None	0	N/A	N/A
1300	1	B	002E	Men's Restroom next to Boy's Restroom	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1300	1	B	002E	Men's Restroom next to Boy's Restroom	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1300	1	B	002D	Boy's Restroom	yes	W1	CMU	Blue	Chipping	4	0	Negative
1300	1	B	002D	Boy's Restroom	yes	Door Frame	Metal	Blue/Brown	Chipping	4	0.03	Negative
1300	1	B	002D	Boy's Restroom	yes	W2	CMU	Blue	None	0	N/A	N/A
1300	1	B	002D	Boy's Restroom	yes	W3	CMU	Blue	None	0	N/A	N/A
1300	1	B	002D	Boy's Restroom	yes	Pipe Outer Cover	Metal	Brown	Chipping	4	0	Negative
1300	1	B	002D	Boy's Restroom	yes	W4	CMU	Blue	None	0	N/A	N/A
1300	1	B	002D	Boy's Restroom	yes	Ceiling	Concrete	White	None	0	N/A	N/A
1300	1	B	002D	Boy's Restroom	yes	Duct Work	Metal	White	Flaking	2	0.01	Negative
1300	1	B	002D	Boy's Restroom	yes	Pipe	Metal	White	Flaking	1	0.04	Negative
1300	1	B	002D	Boy's Restroom	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1300	1	B	014B	Girl's Restroom	yes	W1	CMU	Blue	None	0	N/A	N/A
1300	1	B	014B	Girl's Restroom	yes	Door Frame	Metal	Blue	Chipping	8	0.02	Negative
1300	1	B	014B	Girl's Restroom	yes	W2	CMU	Blue	None	0	N/A	N/A
1300	1	B	014B	Girl's Restroom	yes	W3	CMU	Blue	None	0	N/A	N/A
1300	1	B	014B	Girl's Restroom	yes	W4	CMU	Blue	None	0	N/A	N/A
1300	1	B	014B	Girl's Restroom	yes	Univent	Metal	Blue	Scrapes	4	0.04	Negative
1300	1	B	014B	Girl's Restroom	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1300	1	B	014B	Girl's Restroom	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1300	1	B	017B	Fan Room	no	W1	Brick	White	None	0	N/A	N/A
1300	1	B	017B	Fan Room	no	W2	Concrete	White	Partially Inaccessible/Flaking	10	0.03	Negative
1300	1	B	017B	Fan Room	no	Pipes	Metal	White	Flaking	20	0.18	Negative
1300	1	B	017B	Fan Room	no	W3	Brick	White	Partially Inaccessible/Flaking	250	5.1	Positive

				Inspection Dates: May 2020			School District of Philadelphia					
				Name of Inspector: Paul Davis			Lead Safe Certification Assessment Report					
				Inspection Company: VERTEX			1300 A.D. Harrington ES/1301 Harrington Annex School					
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1300	1	B	017B	Fan Room	no	W4	Brick	White	Partially Inaccessible/Flaking	300	0.02	Negative
1300	1	B	017B	Fan Room	no	Ceiling	Concrete	White	Flaking	200	0.04	Negative
1300	1	B	017B	Fan Room	no	Duct Work	Metal	White	Flaking	20	9	Positive
1300	1	B	017B	Fan Room	no	Floor	Concrete	Gray	Chipping	100	8.8	Positive
1300	1	B	017B	Fan Room	no	Tread	Concrete	Gray	Chipping	10	20.5	Positive
1300	1	B	017B	Fan Room	no	Riser	Concrete	Gray	Chipping	10	18.9	Positive
1300	1	B	017B	Fan Room	no	Hand Rail	Metal	Gray	Chipping/Flaking	10	22.5	Positive
1300	1	B	017B	Fan Room	no	Fan Housing	Metal	Olive Green	Flaking	150	22.4	Positive
1300	1	B	018B	Storage Room in Boiler Room	no	W1	Concrete	Gray	Partially Inaccessible/Flaking	10	0.03	Negative
1300	1	B	018B	Storage Room in Boiler Room	no	W1	Concrete	White	Flaking	25	0.01	Negative
1300	1	B	018B	Storage Room in Boiler Room	no	W2	Concrete	Gray	Partially Inaccessible	0	0.02	Negative
1300	1	B	018B	Storage Room in Boiler Room	no	W2	Concrete	White	Flaking	500	0.01	Negative
1300	1	B	018B	Storage Room in Boiler Room	no	W3	Concrete	Gray	Partially Inaccessible	0	0.04	Negative
1300	1	B	018B	Storage Room in Boiler Room	no	W3	Concrete	White	Partially Inaccessible	0	0.01	Negative
1300	1	B	018B	Storage Room in Boiler Room	no	W4	Concrete	Gray	Partially Inaccessible	0	0.03	Negative
1300	1	B	018B	Storage Room in Boiler Room	no	W4	Concrete	White	Partially Inaccessible	0	0	Negative
1300	1	B	018B	Storage Room in Boiler Room	no	Ceiling	Concrete	White	Flaking	600	0.03	Negative
1300	1	B	018B	Storage Room in Boiler Room	no	Duct Work	Metal	White	Flaking	6	3.4	Positive
1300	1	B	018B	Storage Room in Boiler Room	no	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1300	1	B	018B	Storage Room in Boiler Room	no	Column	Concrete	Gray	Flaking	50	8.6	Positive
1300	1	B	018B	Storage Room in Boiler Room	no	Column	Concrete	White	Flaking	100	4.2	Positive
1300	1	B	018B	Storage Room in Boiler Room	no	Pipe	Metal	Gray/White	Flaking	5	8.7	Positive
1300	1	B	019B	Boiler Room	no	W1	Brick	Gray	Flaking	100	17.7	Positive
1300	1	B	019B	Boiler Room	no	W1	Brick	White	Chipping	25	0.02	Negative
1300	1	B	019B	Boiler Room	no	Door	Metal	Blue	Chipping	6	0	Negative
1300	1	B	019B	Boiler Room	no	Door Frame	Metal	Blue	Chipping	6	0.29	Negative
1300	1	B	019B	Boiler Room	no	Pipe	Metal	Gray/White	Flaking	20	0.09	Negative
1300	1	B	019B	Boiler Room	no	W2	Concrete	Gray	Flaking	125	20.1	Positive
1300	1	B	019B	Boiler Room	no	W2	Concrete	White	Flaking	30	0.01	Negative
1300	1	B	019B	Boiler Room	no	W3	Concrete	Gray	Flaking	20	20.3	Positive
1300	1	B	019B	Boiler Room	no	W3	Concrete	White	Flaking	150	0.01	Negative
1300	1	B	019B	Boiler Room	no	W3	Brick	White	Flaking	100	0.01	Negative
1300	1	B	019B	Boiler Room	no	W4	Concrete	Gray	Partially Inaccessible/Flaking	20	9.8	Positive
1300	1	B	019B	Boiler Room	no	W4	Concrete	White	Flaking	125	0.03	Negative
1300	1	B	019B	Boiler Room	no	Ceiling	Concrete	White	Flaking	200	0.01	Negative
1300	1	B	019B	Boiler Room	no	Pipe	Metal	White	Flaking	30	0.06	Negative
1300	1	B	019B	Boiler Room	no	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1300	1	B	019B	Boiler Room	no	Column	Concrete	White	Flaking	100	0.03	Negative
1300	1	B	019B	Boiler Room	no	Column	Concrete	Gray	Flaking	40	0.12	Negative
1300	1	B	020B	Coal Storage in Boiler Room	no	W1	Concrete	Gray	Partially Inaccessible	0	8.2	Positive
1300	1	B	020B	Coal Storage in Boiler Room	no	W1	Concrete	White	Flaking	25	0.01	Negative
1300	1	B	020B	Coal Storage in Boiler Room	no	W2	Concrete	Gray	Partially Inaccessible	0	0.06	Negative

				Inspection Dates: May 2020			School District of Philadelphia					
				Name of Inspector: Paul Davis			Lead Safe Certification Assessment Report					
				Inspection Company: VERTEX			1300 A.D. Harrington ES/1301 Harrington Annex School					
ULCS#	Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1300	1	B	020B	Coal Storage in Boiler Room	no	W2	Concrete	White	Flaking	2	0.01	Negative
1300	1	B	020B	Coal Storage in Boiler Room	no	W3	Brick	Gray	Flaking	100	0.14	Negative
1300	1	B	020B	Coal Storage in Boiler Room	no	W3	Brick	White	Flaking	20	0.02	Negative
1300	1	B	020B	Coal Storage in Boiler Room	no	W4	Concrete	White	Chipping/flaking	20	0.03	Negative
1300	1	B	020B	Coal Storage in Boiler Room	no	W4	Metal	White	Flaking	20	0.04	Negative
1300	1	B	020B	Coal Storage in Boiler Room	no	Ceiling	Concrete	White	Flaking	125	0.03	Negative
1300	1	B	020B	Coal Storage in Boiler Room	no	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1300	1	B	021B	Building Engineer's Office	no	W1	Brick	Blue	Partially Inaccessible	0	0.13	Negative
1300	1	B	021B	Building Engineer's Office	no	W2	Brick	Blue	Partially Inaccessible/Chipping	10	0.22	Negative
1300	1	B	021B	Building Engineer's Office	no	W3	Brick	Blue	Partially Inaccessible	0	0.23	Negative
1300	1	B	021B	Building Engineer's Office	no	W4	Brick	Blue	Partially Inaccessible	0	0.23	Negative
1300	1	B	021B	Building Engineer's Office	no	Columns	Concrete	Blue	Chipping/Flaking	6	4.9	Positive
1300	1	B	021B	Building Engineer's Office	no	Coat Rack	Wood	Blue	Chipping	2	0.02	Negative
1300	1	B	021B	Building Engineer's Office	no	Ceiling	Plaster	White	Flaking	6	4.7	Positive
1300	1	B	021B	Building Engineer's Office	no	Floor	Concrete	Gray	Chipping	50	0.8	Positive
1300	1	B	024A	Cafetorium	yes	W1	Brick	White	Partially Inaccessible	0	0.19	Negative
1300	1	B	024A	Cafetorium	yes	Door	Metal	Blue	Chipping	12	0.02	Negative
1300	1	B	024A	Cafetorium	yes	Door Frame	Metal	Blue	Chipping	10	0.15	Negative
1300	1	B	024A	Cafetorium	yes	W2	Brick	White	Partially Inaccessible/Flaking	2	0.19	Negative
1300	1	B	024A	Cafetorium	yes	Door	Metal	Blue	Chipping	6	0	Negative
1300	1	B	024A	Cafetorium	yes	Door Frame	Metal	Blue	Chipping	8	0.08	Negative
1300	1	B	024A	Cafetorium	yes	W3	Brick	White	Partially Inaccessible/Flaking	1	0.9	Positive
1300	1	B	024A	Cafetorium	yes	Door	Metal	Blue	Chipping	4	0	Negative
1300	1	B	024A	Cafetorium	yes	Door Frame	Metal	Blue	Chipping	5	0.03	Negative
1300	1	B	024A	Cafetorium	yes	W4	Brick	White	Partially Inaccessible	0	1.9	Positive
1300	1	B	024A	Cafetorium	yes	Door	Metal	Blue	Chipping	2	0	Negative
1300	1	B	024A	Cafetorium	yes	Door Frame	Metal	Blue	Chipping	2	0.06	Negative
1300	1	B	024A	Cafetorium	yes	Ceiling	Concrete	White	Flaking	500	0.04	Negative
1300	1	B	024A	Cafetorium	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1300	1	B	024B	Storage Room in Stairwell #2	no	W1	Brick	White	Partially Inaccessible	0	0.05	Negative
1300	1	B	024B	Storage Room in Stairwell #2	no	W2	Brick	White	Partially Inaccessible	0	0.04	Negative
1300	1	B	024B	Storage Room in Stairwell #2	no	W3	Brick	White	Partially Inaccessible	0	0.19	Negative
1300	1	B	024B	Storage Room in Stairwell #2	no	W4	Brick	White	Partially Inaccessible	0	0.08	Negative
1300	1	B	024B	Storage Room in Stairwell #2	no	Ceiling	Concrete	White	Alligating	2	6.2	Positive
1300	1	B	024B	Storage Room in Stairwell #2	no	Floor	Concrete	Green	Partially Inaccessible	0	0.03	Negative
1300	1	B	024B	Storage Room in Stairwell #2	no	Columns	Concrete	White	Flaking	10	3.9	Positive
1300	1	B	024D	Storage Room in Boiler Room Hallway	no	W1	Plaster	Yellow	Partially Inaccessible	0	0	Negative
1300	1	B	024D	Storage Room in Boiler Room Hallway	no	W2	Plaster	Yellow	Partially Inaccessible	0	0	Negative
1300	1	B	024D	Storage Room in Boiler Room Hallway	no	W3	Plaster	Yellow	Partially Inaccessible	0	0	Negative
1300	1	B	024D	Storage Room in Boiler Room Hallway	no	W4	Plaster	Yellow	Partially Inaccessible	0	0	Negative
1300	1	B	024D	Storage Room in Boiler Room Hallway	no	Ceiling	Plaster	Yellow	None	0	N/A	N/A
1300	1	B	024D	Storage Room in Boiler Room Hallway	no	Floor	Concrete	N/A	N/A	N/A	N/A	N/A

				Inspection Dates: May 2020		School District of Philadelphia						
				Name of Inspector: Paul Davis		Lead Safe Certification Assessment Report						
				Inspection Company: VERTEX		1300 A.D. Harrington ES/1301 Harrington Annex School						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1300	1	B	024C	Cafetorium Office by Stairwell #2	yes	W1	Brick	White	Partially Inaccessible/Chipping	4	0.02	Negative
1300	1	B	024C	Cafetorium Office by Stairwell #2	yes	W2	Brick	White	Partially Inaccessible/Flaking	20	0.18	Negative
1300	1	B	024C	Cafetorium Office by Stairwell #2	yes	W3	Brick	White	Partially Inaccessible	0	0.12	Negative
1300	1	B	024C	Cafetorium Office by Stairwell #2	yes	Column	Concrete	White	Flaking	2	0.07	Negative
1300	1	B	024C	Cafetorium Office by Stairwell #2	yes	W4	Brick	White	Partially Inaccessible	0	0.19	Negative
1300	1	B	024C	Cafetorium Office by Stairwell #2	yes	Ceiling	Plaster	White	Flaking	25	4.2	Positive
1300	1	B	024C	Cafetorium Office by Stairwell #2	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1300	1	B	024E	Gym Office	yes	W1	Brick	Beige	Partially Inaccessible	0	0.11	Negative
1300	1	B	024E	Gym Office	yes	W2	Brick	Beige	Partially Inaccessible	0	0.1	Negative
1300	1	B	024E	Gym Office	yes	W3	Brick	Beige	Partially Inaccessible	0	0.03	Negative
1300	1	B	024E	Gym Office	yes	Column	Concrete	Beige	Partially Inaccessible	0	0.07	Negative
1300	1	B	024E	Gym Office	yes	W4	Brick	Beige	Partially Inaccessible	0	0.06	Negative
1300	1	B	024E	Gym Office	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1300	1	B	024E	Gym Office	yes	Floor	Wood	Brown	Partially Inaccessible	0	0.01	Negative
1300	1	B	024F	Cafeteria Freezer Room	no	W1	Brick	White	Partially Inaccessible/Flaking	50	0.06	Negative
1300	1	B	024F	Cafeteria Freezer Room	no	Pipe	Metal	White	Flaking	50	0.08	Negative
1300	1	B	024F	Cafeteria Freezer Room	no	W2	Brick	White	Flaking	30	0.03	Negative
1300	1	B	024F	Cafeteria Freezer Room	no	W3	Brick	White	Partially Inaccessible/Flaking	50	0.03	Negative
1300	1	B	024F	Cafeteria Freezer Room	no	Ladder	Metal	White	Flaking	6	5	Positive
1300	1	B	024F	Cafeteria Freezer Room	no	Pipe	Metal	White	Flaking	4	0.08	Negative
1300	1	B	024F	Cafeteria Freezer Room	no	Window Sill	Wood	White	Flaking	10	8.7	Positive
1300	1	B	024F	Cafeteria Freezer Room	no	W4	CMU	White	Partially Inaccessible/Flaking	10	0.03	Negative
1300	1	B	024F	Cafeteria Freezer Room	no	Ceiling	Concrete	White	None	0	N/A	N/A
1300	1	B	024F	Cafeteria Freezer Room	no	Beams	Concrete	White	Flaking	100	0.02	Negative
1300	1	B	024F	Cafeteria Freezer Room	no	Duct Work	Metal	White	Flaking	20	0	Negative
1300	1	B	024F	Cafeteria Freezer Room	no	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1300	1	B	024G	Cafeteria Storage	no	W1	Brick	White	Partially Inaccessible/Flaking	150	0.03	Negative
1300	1	B	024G	Cafeteria Storage	no	W2	CMU	White	None	0	N/A	N/A
1300	1	B	024G	Cafeteria Storage	no	W3	Brick	White	Partially Inaccessible/Flaking	100	0.02	Negative
1300	1	B	024G	Cafeteria Storage	no	Ladder	Metal	White	Chipping	6	1.8	Positive
1300	1	B	024G	Cafeteria Storage	no	Pipe	Metal	White	Flaking	4	0.1	Negative
1300	1	B	024G	Cafeteria Storage	no	Window Frame	Wood	Brown	Flaking	6	10.5	Positive
1300	1	B	024G	Cafeteria Storage	no	W4	Brick	White	Partially Inaccessible	0	0.04	Negative
1300	1	B	024G	Cafeteria Storage	no	Ceiling	Concrete	White	None	0	N/A	N/A
1300	1	B	024G	Cafeteria Storage	no	Pipe	Metal	White	Flaking	20	0.11	Negative
1300	1	B	024G	Cafeteria Storage	no	Beams	Concrete	White	Flaking	250	0.04	Negative
1300	1	B	024G	Cafeteria Storage	no	Duct Work	Metal	White	Flaking	200	0.08	Negative
1300	1	B	024G	Cafeteria Storage	no	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1300	1	B	024H	Custodial Closet in Hallway across from Room 00B3	no	W1	CMU	Yellow/Beige	Partially Inaccessible	0	0	Negative

				Inspection Dates: May 2020		School District of Philadelphia						
				Name of Inspector: Paul Davis		Lead Safe Certification Assessment Report						
				Inspection Company: VERTEX		1300 A.D. Harrington ES/1301 Harrington Annex School						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1300	1	B	024H	Custodial Closet in Hallway across from Room 00B3	no	Door Frame	Metal	Blue	Chipping	10	0.14	Negative
1300	1	B	024H	Custodial Closet in Hallway across from Room 00B3	no	W2	CMU	Yellow/Beige	Partially Inaccessible	0	0	Negative
1300	1	B	024H	Custodial Closet in Hallway across from Room 00B3	no	W3	CMU	Yellow/Beige	Partially Inaccessible	0	0	Negative
1300	1	B	024H	Custodial Closet in Hallway across from Room 00B3	no	W4	CMU	Yellow/Beige	None	0	N/A	N/A
1300	1	B	024H	Custodial Closet in Hallway across from Room 00B3	no	Ceiling	Concrete	White	Flaking	2	0.04	Negative
1300	1	B	024H	Custodial Closet in Hallway across from Room 00B3	no	Duct Work	Metal	Beige	Flaking	1	0.04	Negative
1300	1	B	024H	Custodial Closet in Hallway across from Room 00B3	no	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1300	1	B	H01	Hallway at Nurse's Suite	yes	W1	Brick	White	None	0	N/A	N/A
1300	1	B	H01	Hallway at Nurse's Suite	yes	W2	Brick	White	Chipping/Flaking	8	0.17	Negative
1300	1	B	H01	Hallway at Nurse's Suite	yes	W2	CMU	White/Beige	Chipping	12	0.03	Negative
1300	1	B	H01	Hallway at Nurse's Suite	yes	Electrical Panel	Metal	Blue	Chipping	3	0.01	Negative
1300	1	B	H01	Hallway at Nurse's Suite	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
1300	1	B	H01	Hallway at Nurse's Suite	yes	W4	Brick	White	None	0	N/A	N/A
1300	1	B	H01	Hallway at Nurse's Suite	yes	W4	CMU	White/Beige	Chipping	8	0.02	Negative
1300	1	B	H01	Hallway at Nurse's Suite	yes	Ceiling	Plaster	White	Flaking	100	20.6	Positive
1300	1	B	H01	Hallway at Nurse's Suite	yes	Duct Work	Metal	White	Flaking	6	5.4	Positive
1300	1	B	H01	Hallway at Nurse's Suite	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1300	1	B	H01	Hallway at Nurse's Suite	yes	Covebase	Concrete	Brown	Chipping	20	0.5	Negative
1300	1	B	H02	Hallway at Teacher's Lounge	yes	W1	Brick	White	Flaking	2	1.5	Positive
1300	1	B	H02	Hallway at Teacher's Lounge	yes	W2	Brick	White	Flaking	6	0.21	Negative
1300	1	B	H02	Hallway at Teacher's Lounge	yes	W2	CMU	White/Beige	None	0	N/A	N/A
1300	1	B	H02	Hallway at Teacher's Lounge	yes	W3	CMU	White	None	0	N/A	N/A
1300	1	B	H02	Hallway at Teacher's Lounge	yes	W4	CMU	White/Beige	None	0	N/A	N/A
1300	1	B	H02	Hallway at Teacher's Lounge	yes	W4	Brick	White	None	0	N/A	N/A
1300	1	B	H02	Hallway at Teacher's Lounge	yes	Ceiling	Plaster	White	Flaking	100	8.4	Positive
1300	1	B	H02	Hallway at Teacher's Lounge	yes	Duct Work	Metal	White	Chipping	6	2	Positive
1300	1	B	H02	Hallway at Teacher's Lounge	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1300	1	B	H02	Hallway at Teacher's Lounge	yes	Covebase	Concrete	Brown	Chipping	25	0.27	Negative
1300	1	B	H03	Boiler Room Walkway	no	W1	Concrete	White	Scrapes	5	0.01	Negative
1300	1	B	H03	Boiler Room Walkway	no	W1	Concrete	Grey	Flaking	30	0.18	Negative
1300	1	B	H03	Boiler Room Walkway	no	W2	Brick	Gray	Chipping	6	0.07	Negative
1300	1	B	H03	Boiler Room Walkway	no	Door	Wood	Gray	Chipping/Cracking	8	5.1	Positive
1300	1	B	H03	Boiler Room Walkway	no	Door Frame	Wood	Gray	Chipping	8	3.2	Positive
1300	1	B	H03	Boiler Room Walkway	no	W3	Brick	White	Chipping	10	0.01	Negative
1300	1	B	H03	Boiler Room Walkway	no	W3	Brick	Grey	Partially Inaccessible/Flaking	20	19.7	Positive
1300	1	B	H03	Boiler Room Walkway	no	Ladder	Metal	Gray	Chipping	5	9.9	Positive
1300	1	B	H03	Boiler Room Walkway	no	W4	N/A	N/A	N/A	N/A	N/A	N/A
1300	1	B	H03	Boiler Room Walkway	no	Ceiling	Concrete	White	None	0	N/A	N/A
1300	1	B	H03	Boiler Room Walkway	no	Floor	Concrete	Gray	Chipping	20	0.05	Negative
1300	1	B	H03	Boiler Room Walkway	no	Tread	Concrete	Gray	Chipping	4	15.4	Positive
1300	1	B	H03	Boiler Room Walkway	no	Riser	Concrete	Gray	Chipping	4	13.1	Positive
1300	1	B	H03	Boiler Room Walkway	no	Hand Rail	Metal	Gray	Chipping	10	27.9	Positive
1300	1	B	H04	Hallway at Rooms 00B3 to 00B6	yes	W1	Sheetrock	Beige	chipping/Flaking	3	0	Negative
1300	1	B	H04	Hallway at Rooms 00B3 to 00B6	yes	W1	CMU	Multicolored	Chipping	4	0	Negative

				Inspection Dates: May 2020			School District of Philadelphia					
				Name of Inspector: Paul Davis			Lead Safe Certification Assessment Report					
				Inspection Company: VERTEX			1300 A.D. Harrington ES/1301 Harrington Annex School					
ULCS#	Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1300	1	B	H04	Hallway at Rooms 00B3 to 00B6	yes	Elevator Door Frame	Metal	Blue	Chipping	10	0.13	Negative
1300	1	B	H04	Hallway at Rooms 00B3 to 00B6	yes	W2	CMU	White	None	0	N/A	N/A
1300	1	B	H04	Hallway at Rooms 00B3 to 00B6	yes	Door	Metal	Blue	Chipping	10	0	Negative
1300	1	B	H04	Hallway at Rooms 00B3 to 00B6	yes	Door Frame	Metal	Blue	Chipping	10	0.28	Negative
1300	1	B	H04	Hallway at Rooms 00B3 to 00B6	yes	W3	CMU	White	None	0	N/A	N/A
1300	1	B	H04	Hallway at Rooms 00B3 to 00B6	yes	Univent	Metal	Blue	Chipping	6	0.04	Negative
1300	1	B	H04	Hallway at Rooms 00B3 to 00B6	yes	W4	CMU	White	None	0	N/A	N/A
1300	1	B	H04	Hallway at Rooms 00B3 to 00B6	yes	Door	Metal	Blue	Chipping	8	0	Negative
1300	1	B	H04	Hallway at Rooms 00B3 to 00B6	yes	Door Frame	Metal	Blue	Chipping	6	0.04	Negative
1300	1	B	H04	Hallway at Rooms 00B3 to 00B6	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1300	1	B	H04	Hallway at Rooms 00B3 to 00B6	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1300	1	B	S05	Stairs between Hallway at Rooms 00B3 to 00B6 and Cafeteria	yes	W1	CMU	Beige	Partially Inaccessible	0	0	Negative
1300	1	B	S05	Stairs between Hallway at Rooms 00B3 to 00B6 and Cafeteria	yes	W2	CMU	Beige	Partially Inaccessible	0	0	Negative
1300	1	B	S05	Stairs between Hallway at Rooms 00B3 to 00B6 and Cafeteria	yes	W3	CMU	Beige	Partially Inaccessible	0	0	Negative
1300	1	B	S05	Stairs between Hallway at Rooms 00B3 to 00B6 and Cafeteria	yes	W4	CMU	Beige	None	0	N/A	N/A
1300	1	B	S05	Stairs between Hallway at Rooms 00B3 to 00B6 and Cafeteria	yes	Ceiling	Concrete	White	None	0	N/A	N/A
1300	1	B	S05	Stairs between Hallway at Rooms 00B3 to 00B6 and Cafeteria	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1300	1	B	S04	Stairwell #2	yes	W1	Plaster	White	Chipping	1	17.1	Positive
1300	1	B	S04	Stairwell #2	yes	W2	Plaster	White	Flaking	5	15.6	Positive
1300	1	B	S04	Stairwell #2	yes	Hand Rail	Metal	Brown	Chipping	3	0.7	Positive
1300	1	B	S04	Stairwell #2	yes	W3	Plaster	White	Efflorescence/Flaking	10	17.6	Positive
1300	1	B	S04	Stairwell #2	yes	W4	Plaster	White	Efflorescence/Flaking	6	0.06	Negative
1300	1	B	S04	Stairwell #2	yes	Ceiling	Concrete	White	Efflorescence/Flaking	4	23	Positive
1300	1	B	S04	Stairwell #2	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1300	1	B	S04	Stairwell #2	yes	Tread	Concrete	Grey	Friction	30	4.9	Positive
1300	1	B	S04	Stairwell #2	yes	Riser	Concrete	Grey	Chipping	12	5.4	Positive
1300	1	B	S04	Stairwell #2	yes	Stringer	Concrete	Grey	Chipping	12	3.8	Positive
1300	1	B	S04	Stairwell #2	yes	Spindels	Metal	Brown	Chipping	20	5	Positive
1300	1	B	S04	Stairwell #2	yes	Newell Post	Metal	Brown	Chipping	10	5.3	Positive
1300	1	B	S04	Stairwell #2	yes	Covebase	Concrete	Grey	Chipping	12	1.2	Positive
1300	1	B	S03	Stairwell #3	yes	W1	Plaster	White	None	0	N/A	N/A
1300	1	B	S03	Stairwell #3	yes	W2	Plaster	White	Flaking/Cracking	4	0.11	Negative
1300	1	B	S03	Stairwell #3	yes	W3	Plaster	White	Chipping/Cracking	4	0.11	Negative
1300	1	B	S03	Stairwell #3	yes	W4	Plaster	White	None	0	N/A	N/A
1300	1	B	S03	Stairwell #3	yes	Hand Rail	Metal	Brown	Chipping	4	0.27	Negative
1300	1	B	S03	Stairwell #3	yes	Ceiling	Concrete	White	Flaking	1	17.6	Positive
1300	1	B	S03	Stairwell #3	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1300	1	B	S03	Stairwell #3	yes	Tread	Concrete	Grey	Friction	20	9.7	Positive
1300	1	B	S03	Stairwell #3	yes	Riser	Concrete	Grey	Chipping	12	3	Positive

				Inspection Dates: May 2020			School District of Philadelphia					
				Name of Inspector: Paul Davis			Lead Safe Certification Assessment Report					
				Inspection Company: VERTEX			1300 A.D. Harrington ES/1301 Harrington Annex School					
ULCS#	Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1300	1	B	S03	Stairwell #3	yes	Stringer	Concrete	Grey	Chipping	12	1.5	Positive
1300	1	B	S03	Stairwell #3	yes	Spindels	Metal	Brown	Chipping	20	3.2	Positive
1300	1	B	S03	Stairwell #3	yes	Newell Post	Metal	Brown	Chipping	10	10.1	Positive
1300	1	B	S03	Stairwell #3	yes	Covebase	Concrete	Grey	Chipping	12	1.1	Positive
1300	1	B	S02	Stairwell #1	yes	W1	CMU	Beige	None	0	N/A	N/A
1300	1	B	S02	Stairwell #1	yes	W1	Brick	White	None	0	N/A	N/A
1300	1	B	S02	Stairwell #1	yes	W2	CMU	White/Beige	None	0	N/A	N/A
1300	1	B	S02	Stairwell #1	yes	W3	CMU	White/Beige	None	0	N/A	N/A
1300	1	B	S02	Stairwell #1	yes	Pipe	Metal	Beige	Flaking	2	0.01	Negative
1300	1	B	S02	Stairwell #1	yes	W4	CMU	White	None	0	N/A	N/A
1300	1	B	S02	Stairwell #1	yes	Ceiling	Concrete	White	None	0	N/A	N/A
1300	1	B	S02	Stairwell #1	yes	Floor	Concrete	N/A	None	0	N/A	N/A
1300	1	B	S01	Stairwell #4	yes	W1	CMU	Beige	None	0	N/A	N/A
1300	1	B	S01	Stairwell #4	yes	W1	Brick	White	None	0	N/A	N/A
1300	1	B	S01	Stairwell #4	yes	W2	CMU	White	None	0	N/A	N/A
1300	1	B	S01	Stairwell #4	yes	W3	CMU	White/Beige	None	0	N/A	N/A
1300	1	B	S01	Stairwell #4	yes	Pipe	Metal	Beige	Chipping	2	0.01	Negative
1300	1	B	S01	Stairwell #4	yes	W4	CMU	White/Beige	None	0	N/A	N/A
1300	1	B	S01	Stairwell #4	yes	Ceiling	Concrete	White	None	0	N/A	N/A
1300	1	B	S01	Stairwell #4	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1301	Annex	1	00A1	Classroom A1	yes	W1	CMU	White	Partially Inaccessible	0	0.05	Negative
1301	Annex	1	00A1	Classroom A1	yes	Door Frame	Metal	Blue	Chipping	5	0.02	Negative
1301	Annex	1	00A1	Classroom A1	yes	W2	Plaster	White	Partially Inaccessible	0	4.5	Positive
1301	Annex	1	00A1	Classroom A1	yes	Widow Sill	Wood	Blue	Chipping	2	0.4	Negative
1301	Annex	1	00A1	Classroom A1	yes	Widow Frame	Wood	Blue	Chipping	2	0.4	Negative
1301	Annex	1	00A1	Classroom A1	yes	Univent	Wood	Blue	Chipping	3	0.16	Negative
1301	Annex	1	00A1	Classroom A1	yes	Univent	Metal	Blue	Chipping	3	0	Negative
1301	Annex	1	00A1	Classroom A1	yes	W3	Plaster	White	Flaking	4	13.9	Positive
1301	Annex	1	00A1	Classroom A1	yes	Widow Sill	Wood	Blue	Chipping/Flaking	3	0.3	Negative
1301	Annex	1	00A1	Classroom A1	yes	Widow Frame	Wood	Blue	Chipping	2	0.5	Negative
1301	Annex	1	00A1	Classroom A1	yes	W4	CMU	White	Partially Inaccessible	0	0.01	Negative
1301	Annex	1	00A1	Classroom A1	yes	Door Frame	Metal	Blue	Chipping	4	0.01	Negative
1301	Annex	1	00A1	Classroom A1	yes	Column	Plaster	White	Chipping/Flaking	5	8	Positive
1301	Annex	1	00A1	Classroom A1	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1301	Annex	1	00A1	Classroom A1	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1301	Annex	1	00A17	Classroom A1 Restroom	yes	W1	CMU	White	None	0	N/A	N/A
1301	Annex	1	00A17	Classroom A1 Restroom	yes	W2	Plaster	White	Efflorescence/flaking	6	0	Negative
1301	Annex	1	00A17	Classroom A1 Restroom	yes	Widow Sill	Wood	Blue	Chipping	2	0.28	Negative
1301	Annex	1	00A17	Classroom A1 Restroom	yes	Widow Frame	Wood	Blue	Cracking	2	0.4	Negative
1301	Annex	1	00A17	Classroom A1 Restroom	yes	Radiator Cover	Metal	Blue	Chipping	3	0	Negative
1301	Annex	1	00A17	Classroom A1 Restroom	yes	W3	CMU	White	Flaking	1	0	Negative
1301	Annex	1	00A17	Classroom A1 Restroom	yes	W4	CMU	White	Partially Inaccessible	0	0	Negative
1301	Annex	1	00A17	Classroom A1 Restroom	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1301	Annex	1	00A17	Classroom A1 Restroom	yes	Floor	Concrete	Brown	Flaking	1	0.01	Negative
1301	Annex	1	00A2	Classroom A2	yes	W1	CMU	White	None	0	N/A	N/A

				Inspection Dates: May 2020				School District of Philadelphia				
				Name of Inspector: Paul Davis				Lead Safe Certification Assessment Report				
				Inspection Company: VERTEX				1300 A.D. Harrington ES/1301 Harrington Annex School				
ULCS#	Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1301	Annex	1	00A2	Classroom A2	yes	Door Frame	Metal	Blue	Chipping	7	0.06	Negative
1301	Annex	1	00A2	Classroom A2	yes	W2	CMU	White	None	0	N/A	N/A
1301	Annex	1	00A2	Classroom A2	yes	Column	Plaster	White	chipping/flaking	5	0	Negative
1301	Annex	1	00A2	Classroom A2	yes	W3	CMU	White	None	0	N/A	N/A
1301	Annex	1	00A2	Classroom A2	yes	Door frame	Metal	Blue	Chipping	4	0.05	Negative
1301	Annex	1	00A2	Classroom A2	yes	W4	Plaster	White	Partially Inaccessible	0	11.1	Positive
1301	Annex	1	00A2	Classroom A2	yes	Widow Sill	Wood	Blue	Chipping	8	0.18	Negative
1301	Annex	1	00A2	Classroom A2	yes	Widow Frame	Wood	Blue	Chipping/flaking	15	0.3	Negative
1301	Annex	1	00A2	Classroom A2	yes	Univent	Metal	Blue	Chipping	3	0.17	Negative
1301	Annex	1	00A2	Classroom A2	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1301	Annex	1	00A2	Classroom A2	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1301	Annex	1	00A16	Classroom A2 Restroom	yes	W1	CMU	White	None	0	N/A	N/A
1301	Annex	1	00A16	Classroom A2 Restroom	yes	bathroom stall	Metal	Green	Rusting/Flaking	12	0.1	Negative
1301	Annex	1	00A16	Classroom A2 Restroom	yes	W2	CMU	White	Holes/Flaking	2	0	Negative
1301	Annex	1	00A16	Classroom A2 Restroom	yes	W3	Plaster	White	Efflorescence	2	0	Negative
1301	Annex	1	00A16	Classroom A2 Restroom	yes	Widow Sill	Wood	Blue	Chipping	1	0.4	Negative
1301	Annex	1	00A16	Classroom A2 Restroom	yes	Widow Frame	Wood	Blue	Cracking	2	0.4	Negative
1301	Annex	1	00A16	Classroom A2 Restroom	yes	radiator cover	Metal	Blue	Chipping	1	0.01	Negative
1301	Annex	1	00A16	Classroom A2 Restroom	yes	W4	Plaster	White	Efflorescence/Cracking	4	1.3	Positive
1301	Annex	1	00A16	Classroom A2 Restroom	yes	Widow Sill	Wood	Blue	Chipping/flaking	2	0.17	Negative
1301	Annex	1	00A16	Classroom A2 Restroom	yes	Widow Frame	Wood	Blue	Alligating	5	0.3	Negative
1301	Annex	1	00A16	Classroom A2 Restroom	yes	radiator cover	Metal	Blue	Chipping/flaking	2	0.03	Negative
1301	Annex	1	00A16	Classroom A2 Restroom	yes	pipe	Metal	Blue/white	Flaking	2	0.13	Negative
1301	Annex	1	00A16	Classroom A2 Restroom	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1301	Annex	1	00A16	Classroom A2 Restroom	yes	Floor	Concrete	Grey	Chipping	30	0	Negative
1301	Annex	1	00A3	Classroom A3	yes	W1	CMU	White	None	0	N/A	N/A
1301	Annex	1	00A3	Classroom A3	yes	door frame	Metal	Blue	Chipping/Flaking	4	0.05	Negative
1301	Annex	1	00A3	Classroom A3	yes	W2	Plaster	White	Cracking/Flaking	20	9.6	Positive
1301	Annex	1	00A3	Classroom A3	yes	Widow Sill	Wood	Blue	Chipping/Flaking	6	0.1	Negative
1301	Annex	1	00A3	Classroom A3	yes	Widow Frame	Wood	Blue	Cracking	4	0.23	Negative
1301	Annex	1	00A3	Classroom A3	yes	Univent	Metal	Blue	Chipping	6	0.3	Negative
1301	Annex	1	00A3	Classroom A3	yes	pipe outer cover	Metal	Blue/white	Flaking	2	0.02	Negative
1301	Annex	1	00A3	Classroom A3	yes	W3	Plaster	White	Cracking/Flaking	12	15.4	Positive
1301	Annex	1	00A3	Classroom A3	yes	Widow Sill	Wood	Blue	Chipping	3	0.3	Negative
1301	Annex	1	00A3	Classroom A3	yes	Widow Frame	Wood	Blue	Cracking	4	0.4	Negative
1301	Annex	1	00A3	Classroom A3	yes	W4	CMU	White	None	0	N/A	N/A
1301	Annex	1	00A3	Classroom A3	yes	Column	Plaster	White	Chipping/Flaking	6	0.07	Negative
1301	Annex	1	00A3	Classroom A3	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1301	Annex	1	00A3	Classroom A3	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1301	Annex	1	A3A	Classroom A3 Coat Closet	yes	W1	CMU	White	None	0	N/A	N/A
1301	Annex	1	A3A	Classroom A3 Coat Closet	yes	W2	CMU	White	None	0	N/A	N/A
1301	Annex	1	A3A	Classroom A3 Coat Closet	yes	W3	CMU	White	None	0	N/A	N/A
1301	Annex	1	A3A	Classroom A3 Coat Closet	yes	coat hanger	Wood	Blue	Chipping	2	0.01	Negative
1301	Annex	1	A3A	Classroom A3 Coat Closet	yes	shelf	Metal	Blue	Chipping	1	0.02	Negative
1301	Annex	1	A3A	Classroom A3 Coat Closet	yes	W4	CMU	White	None	0	N/A	N/A

				Inspection Dates: May 2020			School District of Philadelphia					
				Name of Inspector: Paul Davis			Lead Safe Certification Assessment Report					
				Inspection Company: VERTEX			1300 A.D. Harrington ES/1301 Harrington Annex School					
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1301	Annex	1	A3A	Classroom A3 Coat Closet	yes	Ceiling	Concrete	White	Flaking	1	0.04	Negative
1301	Annex	1	A3A	Classroom A3 Coat Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1301	Annex	1	A3B	Classroom A3 Closet	yes	W1	CMU	White	Partially Inaccessible	0	0.02	Negative
1301	Annex	1	A3B	Classroom A3 Closet	yes	W2	CMU	White	Partially Inaccessible	0	0.04	Negative
1301	Annex	1	A3B	Classroom A3 Closet	yes	W3	CMU	White	Partially Inaccessible	0	0.02	Negative
1301	Annex	1	A3B	Classroom A3 Closet	yes	W4	Plaster	White	Flaking	6	11.9	Positive
1301	Annex	1	A3B	Classroom A3 Closet	yes	Widow Sill	Wood	White	Cracking/Flaking	4	0.22	Negative
1301	Annex	1	A3B	Classroom A3 Closet	yes	Widow Frame	Wood	White	Cracking/Flaking	4	0.3	Negative
1301	Annex	1	A3B	Classroom A3 Closet	yes	Ceiling	Concrete	White	None	0	N/A	N/A
1301	Annex	1	A3B	Classroom A3 Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1301	Annex	1	00A4	Classroom A4	yes	W1	CMU	Tan	Chipping	2	0.01	Negative
1301	Annex	1	00A4	Classroom A4	yes	door frame	Metal	Blue	Chipping	10	0.02	Negative
1301	Annex	1	00A4	Classroom A4	yes	W2	CMU	Tan	Partially Inaccessible	0	0	Negative
1301	Annex	1	00A4	Classroom A4	yes	Column	Plaster	Tan	Chipping/Flaking	10	7.8	Positive
1301	Annex	1	00A4	Classroom A4	yes	W3	Plaster	Tan	Partially Inaccessible	10	14.4	Positive
1301	Annex	1	00A4	Classroom A4	yes	Widow Sill	Wood	Blue	Chipping/Flaking	5	0.15	Negative
1301	Annex	1	00A4	Classroom A4	yes	Widow Frame	Wood	Blue	Chipping/Flaking	4	0.5	Negative
1301	Annex	1	00A4	Classroom A4	yes	W4	Plaster	White	Partially Inaccessible	4	13.4	Positive
1301	Annex	1	00A4	Classroom A4	yes	Widow Sill	Wood	Blue	Chipping/Flaking	8	0.2	Negative
1301	Annex	1	00A4	Classroom A4	yes	Widow Frame	Wood	Blue	Cracking	16	1.3	Positive
1301	Annex	1	00A4	Classroom A4	yes	Univent	Metal	Blue	Partially Inaccessible	0	0	Negative
1301	Annex	1	00A4	Classroom A4	yes	pipe outer cover	Metal	White	Flaking	3	0.01	Negative
1301	Annex	1	00A4	Classroom A4	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1301	Annex	1	00A4	Classroom A4	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1301	Annex	1	A4A	Classroom A4 Coat Closet	yes	W1	CMU	White	None	0	N/A	N/A
1301	Annex	1	A4A	Classroom A4 Coat Closet	yes	W1	Transite	White	Flaking	4	0.02	Negative
1301	Annex	1	A4A	Classroom A4 Coat Closet	yes	W2	CMU	White	None	0	N/A	N/A
1301	Annex	1	A4A	Classroom A4 Coat Closet	yes	W3	CMU	White	None	0	N/A	N/A
1301	Annex	1	A4A	Classroom A4 Coat Closet	yes	coat hanger	Wood	Blue	Chipping	2	0.02	Negative
1301	Annex	1	A4A	Classroom A4 Coat Closet	yes	shelf	Metal	Blue	Chipping	1	0.02	Negative
1301	Annex	1	A4A	Classroom A4 Coat Closet	yes	W4	CMU	White	None	0	N/A	N/A
1301	Annex	1	A4A	Classroom A4 Coat Closet	yes	Ceiling	Concrete	White	Flaking	2	0.03	Negative
1301	Annex	1	A4A	Classroom A4 Coat Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1301	Annex	1	A4B	Classroom A4 Closet	yes	W1	No Access	No Access	No Access	No Access	No Access	No Access
1301	Annex	1	A4B	Classroom A4 Closet	yes	W2	No Access	No Access	No Access	No Access	No Access	No Access
1301	Annex	1	A4B	Classroom A4 Closet	yes	W3	No Access	No Access	No Access	No Access	No Access	No Access
1301	Annex	1	A4B	Classroom A4 Closet	yes	W4	No Access	No Access	No Access	No Access	No Access	No Access
1301	Annex	1	A4B	Classroom A4 Closet	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1301	Annex	1	A4B	Classroom A4 Closet	yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1301	Annex	1	0A12	Boy's Restroom	yes	W1	CMU	White	None	0	N/A	N/A
1301	Annex	1	0A12	Boy's Restroom	yes	W2	CMU	White	None	0	N/A	N/A
1301	Annex	1	0A12	Boy's Restroom	yes	radiator cover	Metal	White	Chipping	1	0	Negative
1301	Annex	1	0A12	Boy's Restroom	yes	W3	Plaster	White	Hole	1	19.6	Positive
1301	Annex	1	0A12	Boy's Restroom	yes	Widow Sill	Wood	Blue	Chipping	2	0.5	Negative
1301	Annex	1	0A12	Boy's Restroom	yes	Window Frame	Wood	Blue	Chipping	2	0.5	Negative

				Inspection Dates: May 2020		School District of Philadelphia						
				Name of Inspector: Paul Davis		Lead Safe Certification Assessment Report						
				Inspection Company: VERTEX		1300 A.D. Harrington ES/1301 Harrington Annex School						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1301	Annex	1	0A12	Boy's Restroom	yes	W4	CMU	White	None	0	N/A	N/A
1301	Annex	1	0A12	Boy's Restroom	yes	Bathroom stalls	Metal	Blue	Flaking/Rust	14	0.07	Negative
1301	Annex	1	0A12	Boy's Restroom	yes	Pipe Outer Cover	Metal	White	Flaking	2	0.03	Negative
1301	Annex	1	0A12	Boy's Restroom	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1301	Annex	1	0A12	Boy's Restroom	yes	Floor	Concrete	Brown	Chipping/Flaking	10	0	Negative
1301	Annex	1	0A13	Girl's Restroom	yes	W1	CMU	White	None	0	N/A	N/A
1301	Annex	1	0A13	Girl's Restroom	yes	W2	CMU	White	None	0	N/A	N/A
1301	Annex	1	0A13	Girl's Restroom	yes	W3	Plaster	White	Efflorescence	2	10.8	Positive
1301	Annex	1	0A13	Girl's Restroom	yes	Widow Sill	Wood	Blue	Chipping/Flaking	2	0.3	Negative
1301	Annex	1	0A13	Girl's Restroom	yes	Window Frame	Wood	Blue	Cracking	1	0.3	Negative
1301	Annex	1	0A13	Girl's Restroom	yes	W4	CMU	White	None	0	N/A	N/A
1301	Annex	1	0A13	Girl's Restroom	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1301	Annex	1	0A13	Girl's Restroom	yes	Floor	Concrete	Brown	Friction	5	0	Negative
1301	Annex	1	0A13	Girl's Restroom	yes	Bathroom stalls	Metal	Blue	Chipping/Flaking	20	0.17	Negative
1301	Annex	1	0A14	Women's Restroom	yes	W1	CMU	White	None	0	N/A	N/A
1301	Annex	1	0A14	Women's Restroom	yes	W2	CMU	White	None	0	N/A	N/A
1301	Annex	1	0A14	Women's Restroom	yes	W3	CMU	White	Chipping	1	0	Negative
1301	Annex	1	0A14	Women's Restroom	yes	W4	CMU	White	None	0	N/A	N/A
1301	Annex	1	0A14	Women's Restroom	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1301	Annex	1	0A14	Women's Restroom	yes	Floor	Concrete	Brown	Friction	2	0.01	Negative
1301	Annex	1	0A15	Main Office	yes	W1	CMU	White	None	0	N/A	N/A
1301	Annex	1	0A15	Main Office	yes	W2	CMU	White	Partially Inaccessible	0	0.02	Negative
1301	Annex	1	0A15	Main Office	yes	W3	Plaster	White	Flaking	5	14.1	Positive
1301	Annex	1	0A15	Main Office	yes	Window Sill	Wood	Blue	Chipping/Flaking	2	0.4	Negative
1301	Annex	1	0A15	Main Office	yes	Widow Frame	Wood	Blue	Alligatoring	8	0.27	Negative
1301	Annex	1	0A15	Main Office	yes	Radiator over	No Access	Blue	Chipping	4	0.01	Negative
1301	Annex	1	0A15	Main Office	yes	W4	CMU	White	None	0	N/A	N/A
1301	Annex	1	0A15	Main Office	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1301	Annex	1	0A15	Main Office	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1301	Annex	1	A15A	Main Office Coat Closet	yes	W1	No Access	No Access	No Access	No Access	No Access	No Access
1301	Annex	1	A15A	Main Office Coat Closet	yes	W2	No Access	No Access	No Access	No Access	No Access	No Access
1301	Annex	1	A15A	Main Office Coat Closet	yes	W3	No Access	No Access	No Access	No Access	No Access	No Access
1301	Annex	1	A15A	Main Office Coat Closet	yes	W4	No Access	No Access	No Access	No Access	No Access	No Access
1301	Annex	1	A15A	Main Office Coat Closet	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1301	Annex	1	A15A	Main Office Coat Closet	yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1301	Annex	1	A15B	Main Office Closet	yes	W1	No Access	No Access	No Access	No Access	No Access	No Access
1301	Annex	1	A15B	Main Office Closet	yes	W2	No Access	No Access	No Access	No Access	No Access	No Access
1301	Annex	1	A15B	Main Office Closet	yes	W3	No Access	No Access	No Access	No Access	No Access	No Access
1301	Annex	1	A15B	Main Office Closet	yes	W4	No Access	No Access	No Access	No Access	No Access	No Access
1301	Annex	1	A15B	Main Office Closet	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1301	Annex	1	A15B	Main Office Closet	yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1301	Annex	1	JC1	Custodial Closet outside Boy's Restroom	no	W1	CMU	White	None	0	N/A	N/A
1301	Annex	1	JC1	Custodial Closet outside Boy's Restroom	no	W2	CMU	White	None	0	N/A	N/A
1301	Annex	1	JC1	Custodial Closet outside Boy's Restroom	no	W3	CMU	White	None	0	N/A	N/A

				Inspection Dates: May 2020			School District of Philadelphia					
				Name of Inspector: Paul Davis			Lead Safe Certification Assessment Report					
				Inspection Company: VERTEX			1300 A.D. Harrington ES/1301 Harrington Annex School					
ULCS#	Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1301	Annex	1	JC1	Custodial Closet outside Boy's Restroom	no	W4	CMU	White	None	0	N/A	N/A
1301	Annex	1	JC1	Custodial Closet outside Boy's Restroom	no	Ceiling	Concrete	White	None	0	N/A	N/A
1301	Annex	1	JC1	Custodial Closet outside Boy's Restroom	no	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1301	Annex	1	Hall	Hallway	yes	W1	CMU	Tan/White	None	0	N/A	N/A
1301	Annex	1	Hall	Hallway	yes	Door	Metal	Blue	Chipping	5	0	Negative
1301	Annex	1	Hall	Hallway	yes	Door Frame	Metal	Blue	Chipping	20	0.06	Negative
1301	Annex	1	Hall	Hallway	yes	Column	Plaster	Tan/White	Flaking	3	0	Negative
1301	Annex	1	Hall	Hallway	yes	W2	CMU	Tan/White	None	0	N/A	N/A
1301	Annex	1	Hall	Hallway	yes	W3	CMU	Tan/White	None	0	N/A	N/A
1301	Annex	1	Hall	Hallway	yes	Door	Metal	Blue	Chipping	5	0	Negative
1301	Annex	1	Hall	Hallway	yes	Door Frame	Metal	Blue	Chipping	6	0.08	Negative
1301	Annex	1	Hall	Hallway	yes	W4	CMU	Tan/White	None	0	N/A	N/A
1301	Annex	1	Hall	Hallway	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1301	Annex	1	Hall	Hallway	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1301	Annex	1	Stairs	Stairwell by Classroom A2	yes	W1	Plaster	Tan	None	0	N/A	N/A
1301	Annex	1	Stairs	Stairwell by Classroom A2	yes	W2	CMU	Tan	Cracking	4	0.03	Negative
1301	Annex	1	Stairs	Stairwell by Classroom A2	yes	W3	CMU	Tan	None	0	N/A	N/A
1301	Annex	1	Stairs	Stairwell by Classroom A2	yes	W4	CMU	Tan	None	0	N/A	N/A
1301	Annex	1	Stairs	Stairwell by Classroom A2	yes	Ceiling	Metal	Tan	Flaking/Rusting	12	0.06	Negative
1301	Annex	1	Stairs	Stairwell by Classroom A2	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1301	Annex	1	Stairs	Stairwell by Classroom A2	yes	Riser	Metal	Green/Grey	Chipping	5	0.18	Negative
1301	Annex	1	Stairs	Stairwell by Classroom A2	yes	Spindels	Metal	Tan	Chipping	12	1.1	Positive
1301	Annex	1	Stairs	Stairwell by Classroom A2	yes	Newell Post	Metal	Tan	Chipping	4	1.1	Positive
1301	Annex	1	Stairs	Stairwell by Classroom A2	yes	Stringer	Metal	Green/Grey	Chipping	5	1	Positive
1301	Annex	1	Stairs	Main Entrance	yes	W1	Plaster	White	Efflorescence/spalling/cracking	10	17.9	Positive
1301	Annex	1	Stairs	Main Entrance	yes	W2	CMU	White	None	0	N/A	N/A
1301	Annex	1	Stairs	Main Entrance	yes	W2	Plaster	White	Cracking	12	17.7	Positive
1301	Annex	1	Stairs	Main Entrance	yes	W3	CMU	White	None	0	N/A	N/A
1301	Annex	1	Stairs	Main Entrance	yes	W4	CMU	White	Cracking	4	0.03	Negative
1301	Annex	1	Stairs	Main Entrance	yes	W4	Plaster	White	Cracking	12	20.2	Positive
1301	Annex	1	Stairs	Main Entrance	yes	Ceiling	Plaster	White	Broken	2	0.02	Negative
1301	Annex	1	Stairs	Main Entrance	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1301	Annex	1	Stairs	Main Entrance	yes	Tread	Metal	Brown	Friction	40	0.05	Negative
1301	Annex	1	Stairs	Main Entrance	yes	Riser	Metal	Brown	Chipping/Flaking	25	0.05	Negative
1301	Annex	1	Stairs	Main Entrance	yes	Spindels	Metal	Green	Chipping	12	0.3	Negative
1301	Annex	1	Stairs	Main Entrance	yes	Newell Post	Metal	Green	Chipping	4	0.3	Negative
1301	Annex	1	Stairs	Main Entrance	yes	Stringer	Metal	Brown	Chipping/Flaking	2	0.3	Negative
1301	Annex	1	Stairs	Main Entrance	yes	Handrail	Wood	Green	Friction	20	0.01	Negative
1301	Annex	1		Storage Closet under Main Stairwell	no	W1	Plaster	Tan	None	0	N/A	N/A
1301	Annex	1		Storage Closet under Main Stairwell	no	W2	Plaster	Tan	Flaking	4	10.1	Positive
1301	Annex	1		Storage Closet under Main Stairwell	no	W3	Plaster	Tan	Flaking	5	5.5	Positive
1301	Annex	1		Storage Closet under Main Stairwell	no	W4	Plaster	Tan	Partially Inaccessible	0	5.2	Positive
1301	Annex	1		Storage Closet under Main Stairwell	no	Ceiling	Metal	Tan	Flaking	12	10.1	Positive
1301	Annex	1		Storage Closet under Main Stairwell	no	Floor	N/A	N/A	N/A	N/A	N/A	N/A

				Inspection Dates: May 2020		School District of Philadelphia						
				Name of Inspector: Paul Davis		Lead Safe Certification Assessment Report						
				Inspection Company: VERTEX		1300 A.D. Harrington ES/1301 Harrington Annex School						
ULCS#	Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1301	Annex	2	00A5	Classroom A5	yes	W1	CMU	Tan/White	None	0	N/A	N/A
1301	Annex	2	00A5	Classroom A5	yes	Door Frame	Metal	Blue	Chipping	4	0.01	Negative
1301	Annex	2	00A5	Classroom A5	yes	W2	Plaster	Tan	Efflorescence/spalling	50	1.5	Positive
1301	Annex	2	00A5	Classroom A5	yes	Window Sill	Wood	Blue	Chipping/flaking	6	0.02	Negative
1301	Annex	2	00A5	Classroom A5	yes	Widow Frame	Wood	Blue	cracking/flaking	3	0.7	Positive
1301	Annex	2	00A5	Classroom A5	yes	Univent	Metal	Blue	Chipping	3	0.09	Negative
1301	Annex	2	00A5	Classroom A5	yes	W3	Plaster	Tan	Efflorescence/spalling	20	0.23	Negative
1301	Annex	2	00A5	Classroom A5	yes	Window Sill	Wood	Blue	Chipping/flaking	3	0.3	Negative
1301	Annex	2	00A5	Classroom A5	yes	Widow Frame	Wood	Blue	Cracking	1	1.1	Positive
1301	Annex	2	00A5	Classroom A5	yes	W4	CMU	Tan	None	0	N/A	N/A
1301	Annex	2	00A5	Classroom A5	yes	Column	Plaster	Tan	Chipping/Flaking	4	0	Negative
1301	Annex	2	00A5	Classroom A5	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1301	Annex	2	00A5	Classroom A5	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1301	Annex	2	A5A	Classroom A5 Coat Closet	yes	W1	CMU	White	None	0	N/A	N/A
1301	Annex	2	A5A	Classroom A5 Coat Closet	yes	W2	CMU	White	None	0	N/A	N/A
1301	Annex	2	A5A	Classroom A5 Coat Closet	yes	W3	CMU	White	None	0	N/A	N/A
1301	Annex	2	A5A	Classroom A5 Coat Closet	yes	Coat Rack	Wood	Blue	Chipping	5	0.03	Negative
1301	Annex	2	A5A	Classroom A5 Coat Closet	yes	W4	CMU	White	None	0	N/A	N/A
1301	Annex	2	A5A	Classroom A5 Coat Closet	yes	Ceiling	Concrete	Grey	Flaking	30	11.6	Positive
1301	Annex	2	A5A	Classroom A5 Coat Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1301	Annex	2	A5B	Classroom A5 Closet	yes	W1	CMU	White	Partially Inaccessible	0	0.01	Negative
1301	Annex	2	A5B	Classroom A5 Closet	yes	W2	CMU	White	Partially Inaccessible	0	0.02	Negative
1301	Annex	2	A5B	Classroom A5 Closet	yes	W3	CMU	White	Partially Inaccessible	0	0.03	Negative
1301	Annex	2	A5B	Classroom A5 Closet	yes	W4	Plaster	White	Efflorescence/partially inaccessible	12	1.7	Positive
1301	Annex	2	A5B	Classroom A5 Closet	yes	Ceiling	Concrete	White	Efflorescence/flaking	9	10.1	Positive
1301	Annex	2	A5B	Classroom A5 Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1301	Annex	2	00A6	Classroom A6	yes	W1	CMU	White	Chipping	2	0.02	Negative
1301	Annex	2	00A6	Classroom A6	yes	Door Frame	Metal	Blue	Chipping	4	0.04	Negative
1301	Annex	2	00A6	Classroom A6	yes	W2	CMU	White	Chipping	3	0.05	Negative
1301	Annex	2	00A6	Classroom A6	yes	Column	Plaster	White	Flaking	15	0.02	Negative
1301	Annex	2	00A6	Classroom A6	yes	W3	Plaster	White	Partially Inaccessible	0	0	Negative
1301	Annex	2	00A6	Classroom A6	yes	Window Sill	Wood	Blue	Chipping/flaking	2	0.17	Negative
1301	Annex	2	00A6	Classroom A6	yes	Widow Frame	Wood	Blue	cracking/flaking	1	1.4	Positive
1301	Annex	2	00A6	Classroom A6	yes	Pipe	Metal	White	Flaking	2	0.2	Negative
1301	Annex	2	00A6	Classroom A6	yes	W4	Plaster	White	cracking/flaking/chipping	25	0.12	Negative
1301	Annex	2	00A6	Classroom A6	yes	Window Sill	Wood	Blue	Chipping/flaking	5	0.01	Negative
1301	Annex	2	00A6	Classroom A6	yes	Widow Frame	Wood	Blue	Partially Inaccessible	0	0.3	Negative
1301	Annex	2	00A6	Classroom A6	yes	Pipe	Metal	White	Chipping	1	0.23	Negative
1301	Annex	2	00A6	Classroom A6	yes	Univent	Metal	Blue	Partially Inaccessible	0	0.3	Negative
1301	Annex	2	00A6	Classroom A6	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1301	Annex	2	00A6	Classroom A6	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1301	Annex	2	A6A	Classroom A6 Coat Closet	yes	W1	CMU	White	None	0	N/A	N/A
1301	Annex	2	A6A	Classroom A6 Coat Closet	yes	W2	CMU	White	None	0	N/A	N/A

				Inspection Dates: May 2020		School District of Philadelphia						
				Name of Inspector: Paul Davis		Lead Safe Certification Assessment Report						
				Inspection Company: VERTEX		1300 A.D. Harrington ES/1301 Harrington Annex School						
ULCS#	Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1301	Annex	2	A6A	Classroom A6 Coat Closet	yes	W3	CMU	White	None	0	N/A	N/A
1301	Annex	2	A6A	Classroom A6 Coat Closet	yes	Coat Rack	Wood	Blue	Chipping	5	0.02	Negative
1301	Annex	2	A6A	Classroom A6 Coat Closet	yes	W4	CMU	White	None	0	N/A	N/A
1301	Annex	2	A6A	Classroom A6 Coat Closet	yes	Ceiling	Concrete	Tan	Flaking	15	7.9	Positive
1301	Annex	2	A6A	Classroom A6 Coat Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1301	Annex	2	A6B	Classroom A6 Closet	yes	W1	CMU	White	None	0	N/A	N/A
1301	Annex	2	A6B	Classroom A6 Closet	yes	W2	Plaster	White	Partially Inaccessible	0	1.9	Positive
1301	Annex	2	A6B	Classroom A6 Closet	yes	Window Sill	Wood	White	Partially Inaccessible	0	0.3	Negative
1301	Annex	2	A6B	Classroom A6 Closet	yes	Widow Frame	Wood	White	Partially Inaccessible	0	0.3	Negative
1301	Annex	2	A6B	Classroom A6 Closet	yes	W3	CMU	White	Partially Inaccessible	0	0.04	Negative
1301	Annex	2	A6B	Classroom A6 Closet	yes	W4	CMU	White	Partially Inaccessible	0	0.03	Negative
1301	Annex	2	A6B	Classroom A6 Closet	yes	Ceiling	Sheetrock	White	Partially Inaccessible	0	0.01	Negative
1301	Annex	2	A6B	Classroom A6 Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1301	Annex	2	00A7	Classroom A7	yes	W1	CMU	White	Chipping	2	0.02	Negative
1301	Annex	2	00A7	Classroom A7	yes	Door Frame	Metal	Blue	Chipping	7	0.06	Negative
1301	Annex	2	00A7	Classroom A7	yes	W2	CMU	White	Partially Inaccessible	0	0.05	Negative
1301	Annex	2	00A7	Classroom A7	yes	W3	Plaster	White	Partially Inaccessible/flaking	12	0.02	Negative
1301	Annex	2	00A7	Classroom A7	yes	Window Sill	Wood	Blue	Chipping/flaking	6	0.5	Negative
1301	Annex	2	00A7	Classroom A7	yes	Widow Frame	Wood	Blue	Flaking	15	0.5	Negative
1301	Annex	2	00A7	Classroom A7	yes	Univent	Metal	Blue	Chipping	10	0.3	Negative
1301	Annex	2	00A7	Classroom A7	yes	W4	CMU	White	None	0	N/A	N/A
1301	Annex	2	00A7	Classroom A7	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1301	Annex	2	00A7	Classroom A7	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1301	Annex	2	A7A	Classroom A7 Coat Closet	yes	W1	CMU	White	None	0	N/A	N/A
1301	Annex	2	A7A	Classroom A7 Coat Closet	yes	W2	CMU	White	None	0	N/A	N/A
1301	Annex	2	A7A	Classroom A7 Coat Closet	yes	W3	CMU	White	None	0	N/A	N/A
1301	Annex	2	A7A	Classroom A7 Coat Closet	yes	W4	CMU	White	None	0	N/A	N/A
1301	Annex	2	A7A	Classroom A7 Coat Closet	yes	Ceiling	Concrete	Tan	Flaking	25	6	Positive
1301	Annex	2	A7A	Classroom A7 Coat Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1301	Annex	2	A7B	Classroom A7 Closet	yes	W1	CMU	White	None	0	N/A	N/A
1301	Annex	2	A7B	Classroom A7 Closet	yes	W2	Plaster	Tan	Flaking	8	6.8	Positive
1301	Annex	2	A7B	Classroom A7 Closet	yes	W3	CMU	White	None	0	N/A	N/A
1301	Annex	2	A7B	Classroom A7 Closet	yes	W4	CMU	White	None	0	N/A	N/A
1301	Annex	2	A7B	Classroom A7 Closet	yes	Ceiling	Concrete	Tan	None	0	N/A	N/A
1301	Annex	2	A7B	Classroom A7 Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1301	Annex	2	00A8	Classroom A8	yes	W1	CMU	White	Chipping	2	0	Negative
1301	Annex	2	00A8	Classroom A8	yes	Door Frame	Metal	Blue	Chipping	3	0	Negative
1301	Annex	2	00A8	Classroom A8	yes	W2	Plaster	White	Chipping/flaking/cracking/efflorescence	20	12.1	Positive
1301	Annex	2	00A8	Classroom A8	yes	Window Sill	Wood	Blue	Chipping/Flaking	4	0.07	Negative
1301	Annex	2	00A8	Classroom A8	yes	Widow Frame	Metal	Blue	Flaking	8	0.5	Negative
1301	Annex	2	00A8	Classroom A8	yes	Univent	Metal	Blue	Chipping	4	0.14	Negative
1301	Annex	2	00A8	Classroom A8	yes	W3	Plaster	White	Chipping/Flaking	20	0.02	Negative
1301	Annex	2	00A8	Classroom A8	yes	Window Sill	Wood	Blue	Chipping/Flaking	5	0.4	Negative

				Inspection Dates: May 2020				School District of Philadelphia				
				Name of Inspector: Paul Davis				Lead Safe Certification Assessment Report				
				Inspection Company: VERTEX				1300 A.D. Harrington ES/1301 Harrington Annex School				
ULCS#	Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1301	Annex	2	00A8	Classroom A8	yes	Widow Frame	Wood	Blue	Flaking	5	1.5	Positive
1301	Annex	2	00A8	Classroom A8	yes	W4	CMU	White	Flaking	2	0	Negative
1301	Annex	2	00A8	Classroom A8	yes	Column	Plaster	White	Flaking	4	0.02	Negative
1301	Annex	2	00A8	Classroom A8	yes	Ceiling	Plaster	Tan	Flaking	25	5	Positive
1301	Annex	2	00A8	Classroom A8	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1301	Annex	2	A8A	Classroom A8 Student Assistance Area	yes	W1	CMU	White	None	0	N/A	N/A
1301	Annex	2	A8A	Classroom A8 Student Assistance Area	yes	Door Frame	Metal	Blue	Chipping	4	0.01	Negative
1301	Annex	2	A8A	Classroom A8 Student Assistance Area	yes	W2	CMU	White	None	0	N/A	N/A
1301	Annex	2	A8A	Classroom A8 Student Assistance Area	yes	W3	Plaster	White	Flaking/Cracking	6	9.1	Positive
1301	Annex	2	A8A	Classroom A8 Student Assistance Area	yes	Window Sill	Wood	Blue	Chipping/Flaking	3	0.2	Negative
1301	Annex	2	A8A	Classroom A8 Student Assistance Area	yes	Widow Frame	Metal	Blue	Flaking	5	0.27	Negative
1301	Annex	2	A8A	Classroom A8 Student Assistance Area	yes	Radiator Cover	Metal	Blue	Chipping	2	0.03	Negative
1301	Annex	2	A8A	Classroom A8 Student Assistance Area	yes	W4	CMU	White	None	0	N/A	N/A
1301	Annex	2	A8A	Classroom A8 Student Assistance Area	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1301	Annex	2	A8A	Classroom A8 Student Assistance Area	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1301	Annex	2	A8B	Classroom A8 Coat Closet	yes	W1	CMU	White	None	0	N/A	N/A
1301	Annex	2	A8B	Classroom A8 Coat Closet	yes	W2	CMU	White	Partially Inaccessible	0	0.02	Negative
1301	Annex	2	A8B	Classroom A8 Coat Closet	yes	W3	CMU	White	Partially Inaccessible	0	0.04	Negative
1301	Annex	2	A8B	Classroom A8 Coat Closet	yes	W4	CMU	White	Partially Inaccessible	0	0.02	Negative
1301	Annex	2	A8B	Classroom A8 Coat Closet	yes	Ceiling	Plaster	Tan	Flaking	2	5.8	Positive
1301	Annex	2	A8B	Classroom A8 Coat Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1301	Annex	2	A8C	Classroom A8 Closet	yes	W1	CMU	White	None	0	N/A	N/A
1301	Annex	2	A8C	Classroom A8 Closet	yes	W2	CMU	White	None	0	N/A	N/A
1301	Annex	2	A8C	Classroom A8 Closet	yes	W3	CMU	White	None	0	N/A	N/A
1301	Annex	2	A8C	Classroom A8 Closet	yes	W4	Plaster	White	Flaking	1	7.5	Positive
1301	Annex	2	A8C	Classroom A8 Closet	yes	Window Sill	Wood	White	Chipping	2	0.14	Negative
1301	Annex	2	A8C	Classroom A8 Closet	yes	Widow Frame	Metal	White	Flaking	6	0.5	Negative
1301	Annex	2	A8C	Classroom A8 Closet	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1301	Annex	2	A8C	Classroom A8 Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1301	Annex	2		Small Hallway to Classroom A8	yes	W1	CMU	White	None	0	N/A	N/A
1301	Annex	2		Small Hallway to Classroom A8	yes	W2	CMU	White	None	0	N/A	N/A
1301	Annex	2		Small Hallway to Classroom A8	yes	W3	CMU	White	None	0	N/A	N/A
1301	Annex	2		Small Hallway to Classroom A8	yes	W4	CMU	White	None	0	N/A	N/A
1301	Annex	2		Small Hallway to Classroom A8	yes	Column	Plaster	White	Flaking	2	0.01	Negative
1301	Annex	2		Small Hallway to Classroom A8	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1301	Annex	2		Small Hallway to Classroom A8	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1301	Annex	2	00A9	Classroom A9	yes	W1	CMU	White	Chipping	1	0	Negative
1301	Annex	2	00A9	Classroom A9	yes	Door Frame	Metal	Blue	Chipping	5	0	Negative
1301	Annex	2	00A9	Classroom A9	yes	W2	CMU	White	Chipping	2	0	Negative
1301	Annex	2	00A9	Classroom A9	yes	Column	Plaster	White	Flaking	2	0.03	Negative
1301	Annex	2	00A9	Classroom A9	yes	W3	Plaster	White	cracking/chipping/flaking	20	19	Positive
1301	Annex	2	00A9	Classroom A9	yes	Window Sill	Wood	Blue	cracking/chipping	3	0.2	Negative
1301	Annex	2	00A9	Classroom A9	yes	Widow Frame	Wood	Blue	Flaking	5	1.3	Positive

				Inspection Dates: May 2020		School District of Philadelphia						
				Name of Inspector: Paul Davis		Lead Safe Certification Assessment Report						
				Inspection Company: VERTEX		1300 A.D. Harrington ES/1301 Harrington Annex School						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1301	Annex	2	00A9	Classroom A9	yes	W4	Plaster	White	Efflorescence/flaking/cracking	6	19.5	Positive
1301	Annex	2	00A9	Classroom A9	yes	Window Sill	Wood	Blue	flaking/chipping	5	0.14	Negative
1301	Annex	2	00A9	Classroom A9	yes	Widow Frame	Wood	Blue	Flaking	10	0.4	Negative
1301	Annex	2	00A9	Classroom A9	yes	Univent	Metal	Blue	Chipping	4	0.21	Negative
1301	Annex	2	00A9	Classroom A9	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1301	Annex	2	00A9	Classroom A9	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1301	Annex	2	A9A	Classroom A9 Student Assistance Area	yes	W1	CMU	White	Partially Inaccessible	0	0	Negative
1301	Annex	2	A9A	Classroom A9 Student Assistance Area	yes	W2	CMU	White	Partially Inaccessible	0	0	Negative
1301	Annex	2	A9A	Classroom A9 Student Assistance Area	yes	W3	Plaster	White	Flaking	6	1.4	Positive
1301	Annex	2	A9A	Classroom A9 Student Assistance Area	yes	Window Sill	Wood	Brown	Chipping	1	0.3	Negative
1301	Annex	2	A9A	Classroom A9 Student Assistance Area	yes	Widow Frame	Wood	White	Flaking	4	1.4	Positive
1301	Annex	2	A9A	Classroom A9 Student Assistance Area	yes	Radiator Cover	Metal	Brown	Chipping	1	0.01	Negative
1301	Annex	2	A9A	Classroom A9 Student Assistance Area	yes	W4	CMU	White	None	0	N/A	N/A
1301	Annex	2	A9A	Classroom A9 Student Assistance Area	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1301	Annex	2	A9A	Classroom A9 Student Assistance Area	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1301	Annex	2	A9B	Classroom A9 Coat Closet	yes	W1	N/A	White	Partially Inaccessible	0	0.01	Negative
1301	Annex	2	A9B	Classroom A9 Coat Closet	yes	W2	CMU	White	Partially Inaccessible	0	0.41	Negative
1301	Annex	2	A9B	Classroom A9 Coat Closet	yes	W3	CMU	White	Partially Inaccessible	0	0.03	Negative
1301	Annex	2	A9B	Classroom A9 Coat Closet	yes	W4	CMU	White	Partially Inaccessible	0	0.01	Negative
1301	Annex	2	A9B	Classroom A9 Coat Closet	yes	Ceiling	Plaster	White	Flaking	30	6.1	Positive
1301	Annex	2	A9B	Classroom A9 Coat Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1301	Annex	2	A9C	Classroom A9 Closet	yes	W1	CMU	White	None	0	N/A	N/A
1301	Annex	2	A9C	Classroom A9 Closet	yes	W2	Plaster	White	Efflorescence	1	0.01	Negative
1301	Annex	2	A9C	Classroom A9 Closet	yes	Window Sill	Wood	White	Cracking	4	0.4	Negative
1301	Annex	2	A9C	Classroom A9 Closet	yes	Widow Frame	Wood	White	flaking/cracking	4	0.9	Positive
1301	Annex	2	A9C	Classroom A9 Closet	yes	W3	CMU	White	None	0	N/A	N/A
1301	Annex	2	A9C	Classroom A9 Closet	yes	W4	CMU	White	None	0	N/A	N/A
1301	Annex	2	A9C	Classroom A9 Closet	yes	Ceiling	Plaster	White	Flaking	12	5.6	Positive
1301	Annex	2	A9C	Classroom A9 Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1301	Annex	2		Small Hallway to Classroom A9	yes	W1	CMU	White	None	0	N/A	N/A
1301	Annex	2		Small Hallway to Classroom A9	yes	W2	CMU	White	Flaking	1	0	Negative
1301	Annex	2		Small Hallway to Classroom A9	yes	W3	CMU	White	None	0	N/A	N/A
1301	Annex	2		Small Hallway to Classroom A9	yes	W4	CMU	White	None	0	N/A	N/A
1301	Annex	2		Small Hallway to Classroom A9	yes	Column	Plaster	White	Flaking	8	16.8	Positive
1301	Annex	2		Small Hallway to Classroom A9	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1301	Annex	2		Small Hallway to Classroom A9	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1301	Annex	2	0A18	Men's Restroom	yes	W1	CMU	White	Flaking	1	0	Negative
1301	Annex	2	0A18	Men's Restroom	yes	W2	CMU	White	Flaking	3	0	Negative
1301	Annex	2	0A18	Men's Restroom	yes	W3	CMU	White	Flaking	4	0	Negative
1301	Annex	2	0A18	Men's Restroom	yes	W4	CMU	White	None	0	N/A	N/A
1301	Annex	2	0A18	Men's Restroom	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1301	Annex	2	0A18	Men's Restroom	yes	Floor	Concrete	Brown	Flaking	1	0	Negative
1301	Annex	2		Girl's Restroom	yes	W1	CMU	White	None	0	N/A	N/A
1301	Annex	2		Girl's Restroom	yes	W2	CMU	White	None	0	N/A	N/A

				Inspection Dates: May 2020		School District of Philadelphia						
				Name of Inspector: Paul Davis		Lead Safe Certification Assessment Report						
				Inspection Company: VERTEX		1300 A.D. Harrington ES/1301 Harrington Annex School						
ULCS#	Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1301	Annex	2		Girl's Restroom	yes	W3	Plaster	White	Efflorescence	4	1.6	Positive
1301	Annex	2		Girl's Restroom	yes	Widow Sill	Wood	Blue	Chipping	2	0.3	Negative
1301	Annex	2		Girl's Restroom	yes	Window Frame	Wood	Blue	Flaking	2	0.28	Negative
1301	Annex	2		Girl's Restroom	yes	W4	CMU	White	None	0	N/A	N/A
1301	Annex	2		Girl's Restroom	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1301	Annex	2		Girl's Restroom	yes	Floor	Concrete	Brown	Chipping	2	0	Negative
1301	Annex	2		Girl's Restroom	yes	Bathroom stalls	Metal	Blue	Chipping	6	0.14	Negative
1301	Annex	2	0A12	Boy's Restroom	yes	W1	CMU	White	None	0	N/A	N/A
1301	Annex	2	0A12	Boy's Restroom	yes	W2	CMU	White	None	0	N/A	N/A
1301	Annex	2	0A12	Boy's Restroom	yes	Radiator Cover	Metal	White	Chipping	1	0	Negative
1301	Annex	2	0A12	Boy's Restroom	yes	W3	Plaster	White	spalling/efflorescence/flaking	20	4.3	Positive
1301	Annex	2	0A12	Boy's Restroom	yes	Widow Sill	Wood	Blue	Chipping	2	0.5	Negative
1301	Annex	2	0A12	Boy's Restroom	yes	Window Frame	Wood	Blue	chipping/cracking	1	0.5	Negative
1301	Annex	2	0A12	Boy's Restroom	yes	W4	CMU	White	None	0	N/A	N/A
1301	Annex	2	0A12	Boy's Restroom	yes	Bathroom stalls	Metal	Blue	Flaking	4	0	Negative
1301	Annex	2	0A12	Boy's Restroom	yes	Pipe Outer Cover	Metal	White	Partially Inaccessible	0	0.11	Negative
1301	Annex	2	0A12	Boy's Restroom	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1301	Annex	2	0A12	Boy's Restroom	yes	Floor	Concrete	Brown	Chipping	20	0	Negative
1301	Annex	2		Custodial Closet outside Boy's Restroom	no	W1	CMU	White	None	0	N/A	N/A
1301	Annex	2		Custodial Closet outside Boy's Restroom	no	W2	CMU	White	None	0	N/A	N/A
1301	Annex	2		Custodial Closet outside Boy's Restroom	no	W3	CMU	White	None	0	N/A	N/A
1301	Annex	2		Custodial Closet outside Boy's Restroom	no	W4	CMU	White	None	0	N/A	N/A
1301	Annex	2		Custodial Closet outside Boy's Restroom	no	Ceiling	Plaster	White	flaking/holes	9	9.7	Positive
1301	Annex	2		Custodial Closet outside Boy's Restroom	no	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1301	Annex	2	Hall	Hallway	yes	W1	CMU	White	Chipping	1	0.04	Negative
1301	Annex	2	Hall	Hallway	yes	Door	Metal	Blue	chipping/flaking	4	0.02	Negative
1301	Annex	2	Hall	Hallway	yes	Door Frame	Metal	Blue	Chipping	20	0.01	Negative
1301	Annex	2	Hall	Hallway	yes	W2	CMU	White	None	0	N/A	N/A
1301	Annex	2	Hall	Hallway	yes	W3	CMU	White	Cracking	2	0.12	Negative
1301	Annex	2	Hall	Hallway	yes	Door	Metal	Blue	Chipping	1	0.01	Negative
1301	Annex	2	Hall	Hallway	yes	Column	Plaster	White	Flaking	5	21.6	Positive
1301	Annex	2	Hall	Hallway	yes	Door Frame	Metal	Blue	Chipping	2	0.02	Negative
1301	Annex	2	Hall	Hallway	yes	W4	CMU	White	None	0	N/A	N/A
1301	Annex	2	Hall	Hallway	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1301	Annex	2	Hall	Hallway	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1301	Annex	2	Stairs	Stairwell by Classroom A6	yes	W1	Plaster	White	Cracking	4	0.02	Negative
1301	Annex	2	Stairs	Stairwell by Classroom A6	yes	W2	CMU	White/Tan	none	0	N/A	N/A
1301	Annex	2	Stairs	Stairwell by Classroom A6	yes	W3	CMU	White/Tan	Cracking	12	0.02	Negative
1301	Annex	2	Stairs	Stairwell by Classroom A6	yes	W4	CMU	White/Tan	None	0	N/A	N/A
1301	Annex	2	Stairs	Stairwell by Classroom A6	yes	Ceiling	Concrete	White	None	0	N/A	N/A
1301	Annex	2	Stairs	Stairwell by Classroom A6	yes	Pipe	Metal	White	Flaking	2	0.09	Negative
1301	Annex	2	Stairs	Stairwell by Classroom A6	yes	Floor	Concrete	N/A	None	0	N/A	N/A
1301	Annex	2	Stairs	Stairwell by Classroom A6	yes	Riser	Metal	Green/Grey	Chipping	5	0.18	Negative

				Inspection Dates: May 2020		School District of Philadelphia						
				Name of Inspector: Paul Davis		Lead Safe Certification Assessment Report						
				Inspection Company: VERTEX		1300 A.D. Harrington ES/1301 Harrington Annex School						
ULCS#	Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1301	Annex	2	Stairs	Stairwell by Classroom A6	yes	Spindels	Metal	Tan	Chipping	10	1	Positive
1301	Annex	2	Stairs	Stairwell by Classroom A6	yes	Newell Post	Metal	Tan	Chipping	3	0.8	Positive
1301	Annex	2	Stairs	Stairwell by Classroom A6	yes	Stringer	Metal	Tan	Chipping	5	1.6	Positive
1301	Annex	2	Stairs	Front Stairwell	yes	W1	Plaster	Blue	Efflorescence/spalling/flaking	150	3.3	Positive
1301	Annex	2	Stairs	Front Stairwell	yes	Window Sill	Wood	White	chipping/flaking	3	0.4	Negative
1301	Annex	2	Stairs	Front Stairwell	yes	Window Frame	Wood	White	Flaking	4	2	Positive
1301	Annex	2	Stairs	Front Stairwell	yes	W2	CMU	White	Flaking	1	0.03	Negative
1301	Annex	2	Stairs	Front Stairwell	yes	W3	CMU	White	None	0	N/A	N/A
1301	Annex	2	Stairs	Front Stairwell	yes	W4	CMU	White	Flaking	1	0.02	Negative
1301	Annex	2	Stairs	Front Stairwell	yes	Ceiling	Plaster	Tan	Efflorescence/flaking	100	4.9	Positive
1301	Annex	2	Stairs	Front Stairwell	yes	Floor	Concrete	Brown	chipping/flaking	2	0.06	Negative
1301	Annex	2	Stairs	Front Stairwell	yes	Riser	Metal	Brown	Chipping	2	0.16	Negative
1301	Annex	2	Stairs	Front Stairwell	yes	Spindels	Metal	Blue	Chipping	10	0.2	Negative
1301	Annex	2	Stairs	Front Stairwell	yes	Newell Post	Metal	Blue	Chipping	4	0.17	Negative
1301	Annex	2	Stairs	Front Stairwell	yes	Handrail	Wood	Blue	Friction	20	0.04	Negative
1301	Annex	2	Stairs	Front Stairwell	yes	Tread	Metal	Brown	chipping/flaking	15	0.07	Negative
1301	Annex	B	00B1	Cafeteria	yes	W1	CMU	White	None	0	N/A	N/A
1301	Annex	B	00B1	Cafeteria	yes	W1	Plaster	White	Efflorescence/flaking	20	0.09	Negative
1301	Annex	B	00B1	Cafeteria	yes	Door Frame	Metal	Blue	Chipping	4	0.02	Negative
1301	Annex	B	00B1	Cafeteria	yes	Coat Rack	Wood	Blue	Chipping	8	0.05	Negative
1301	Annex	B	00B1	Cafeteria	yes	W2	Plaster	White	Flaking	25	0.01	Negative
1301	Annex	B	00B1	Cafeteria	yes	Window Sill	Wood	Brown	chipping/flaking	3	0.7	Positive
1301	Annex	B	00B1	Cafeteria	yes	W3	Plaster	White	flaking/efflorescence	10	0.04	Negative
1301	Annex	B	00B1	Cafeteria	yes	Window Sill	Wood	Brown	chipping/flaking	6	0.9	Positive
1301	Annex	B	00B1	Cafeteria	yes	W4	Plaster	White	Efflorescence/spalling/flaking	150	0.01	Negative
1301	Annex	B	00B1	Cafeteria	yes	Window Sill	Wood	Brown	chipping/flaking	3	0.7	Positive
1301	Annex	B	00B1	Cafeteria	yes	Ceiling	Plaster	White	Efflorescence/flaking	10	12.3	Positive
1301	Annex	B	00B1	Cafeteria	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1301	Annex	B	00B1	Cafeteria	yes	Baseboard	Concrete	Brown/White	chipping/flaking	20	0.3	Negative
1301	Annex	B	00B1	Cafeteria	yes	Column	Plaster	White	Flaking	3	0	Negative
1301	Annex	B	002B	Storage Room Adjacent to Rear Stairs	yes	W1	CMU	White	None	0	N/A	N/A
1301	Annex	B	002B	Storage Room Adjacent to Rear Stairs	yes	W2	Plaster	Tan	Flaking	30	0.02	Negative
1301	Annex	B	002B	Storage Room Adjacent to Rear Stairs	yes	Window Sill	Wood	Brown	chipping/flaking	1	0.2	Negative
1301	Annex	B	002B	Storage Room Adjacent to Rear Stairs	yes	W3	CMU	Tan	Partially Inaccessible	0	0	Negative
1301	Annex	B	002B	Storage Room Adjacent to Rear Stairs	yes	W4	CMU	Tan	Partially Inaccessible	0	0.01	Negative
1301	Annex	B	002B	Storage Room Adjacent to Rear Stairs	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1301	Annex	B	002B	Storage Room Adjacent to Rear Stairs	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1301	Annex	B	003B	Building Engineer's Office	no	W1	CMU	White	None	0	N/A	N/A
1301	Annex	B	003B	Building Engineer's Office	no	W2	CMU	White	Partially Inaccessible	0	0.03	Negative
1301	Annex	B	003B	Building Engineer's Office	no	W3	CMU	White	Partially Inaccessible	0	0.04	Negative
1301	Annex	B	003B	Building Engineer's Office	no	W4	CMU	White	Partially Inaccessible	0	0.02	Negative
1301	Annex	B	003B	Building Engineer's Office	no	Ceiling	Concrete	Brown	Flaking	50	4.4	Positive
1301	Annex	B	003B	Building Engineer's Office	no	Floor	N/A	N/A	N/A	N/A	N/A	N/A

				Inspection Dates: May 2020		School District of Philadelphia						
				Name of Inspector: Paul Davis		Lead Safe Certification Assessment Report						
				Inspection Company: VERTEX		1300 A.D. Harrington ES/1301 Harrington Annex School						
ULCS#	Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1301	Annex	B	0010B	Storage to the left of Building Engineer's Office	no	W1	CMU	Brown	Partially Inaccessible	0	0.06	Negative
1301	Annex	B	0010B	Storage to the left of Building Engineer's Office	no	W2	CMU	Brown	Partially Inaccessible	0	0	Negative
1301	Annex	B	0010B	Storage to the left of Building Engineer's Office	no	W3	Plaster	White	Flaking	40	9.9	Positive
1301	Annex	B	0010B	Storage to the left of Building Engineer's Office	no	W4	CMU	Brown	None	0	N/A	N/A
1301	Annex	B	0010B	Storage to the left of Building Engineer's Office	no	Ceiling	Concrete	Brown	Flaking	2	0.03	Negative
1301	Annex	B	0010B	Storage to the left of Building Engineer's Office	no	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1301	Annex	B	005B	Boiler Room	no	W1	CMU	White/Grey	Partially Inaccessible	0	0.04	Negative
1301	Annex	B	005B	Boiler Room	no	Door	Metal	Tan	Chipping	20	0.01	Negative
1301	Annex	B	005B	Boiler Room	no	Door Frame	Metal	Tan	Chipping	10	0.02	Negative
1301	Annex	B	005B	Boiler Room	no	W2	Brick	White/Grey	Partially Inaccessible/flaking	50	16.5	Positive
1301	Annex	B	005B	Boiler Room	no	W3	Brick	White/Grey	Flaking	350	4.7	Positive
1301	Annex	B	005B	Boiler Room	no	W4	Plaster	Grey	Flaking	150	18.5	Positive
1301	Annex	B	005B	Boiler Room	no	Window Sill	Wood	Grey	Flaking	10	0.5	Negative
1301	Annex	B	005B	Boiler Room	no	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1301	Annex	B	005B	Boiler Room	no	Ceiling	Concrete	Grey	Flaking	600	4.4	Positive
1301	Annex	B	005B	Boiler Room	no	Pipe	Metal	White	Chipping	50	0.03	Negative
1301	Annex	B	006B	Teacher Lounge/Dining	yes	W1	CMU	White	Partially Inaccessible	0	0.02	Negative
1301	Annex	B	006B	Teacher Lounge/Dining	yes	W2	CMU	White	Partially Inaccessible	0	0.04	Negative
1301	Annex	B	006B	Teacher Lounge/Dining	yes	W3	Plaster	White	Efflorescence/spalling	50	0.05	Negative
1301	Annex	B	006B	Teacher Lounge/Dining	yes	W4	CMU	White	None	0	N/A	N/A
1301	Annex	B	006B	Teacher Lounge/Dining	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1301	Annex	B	006B	Teacher Lounge/Dining	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1301	Annex	B	008BA	Restroom Foyer	yes	W1	CMU	White	Partially Inaccessible	0	0.03	Negative
1301	Annex	B	008BA	Restroom Foyer	yes	W2	CMU	White	None	0	N/A	N/A
1301	Annex	B	008BA	Restroom Foyer	yes	W3	CMU	White	None	0	N/A	N/A
1301	Annex	B	008BA	Restroom Foyer	yes	W4	Plaster	White	Efflorescence/spalling	5	19.7	Positive
1301	Annex	B	008BA	Restroom Foyer	yes	Ceiling	Concrete	Brown	Flaking	80	11	Positive
1301	Annex	B	008BA	Restroom Foyer	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1301	Annex	B		Women's Restroom	yes	W1	CMU	White	None	0	N/A	N/A
1301	Annex	B		Women's Restroom	yes	W2	CMU	White	None	3	0	Negative
1301	Annex	B		Women's Restroom	yes	W3	Plaster	White	Efflorescence	20	8.3	Positive
1301	Annex	B		Women's Restroom	yes	W4	Plaster	White	Efflorescence	25	18.4	Positive
1301	Annex	B		Women's Restroom	yes	Ceiling	Concrete	Brown	Flaking	75	10.8	Positive
1301	Annex	B		Women's Restroom	yes	Floor	Concrete	Brown	Chipping	10	0.01	Negative
1301	Annex	B		Women's Restroom	yes	Bathroom Stall	Metal	Green	rusting/flaking	2	0.13	Negative
1301	Annex	B		Men's Restroom	yes	W1	CMU	White	None	0	N/A	N/A
1301	Annex	B		Men's Restroom	yes	W2	CMU	White	None	0	N/A	N/A
1301	Annex	B		Men's Restroom	yes	W3	Plaster	White	Efflorescence/spalling	20	22.1	Positive
1301	Annex	B		Men's Restroom	yes	W4	CMU	White	None	0	N/A	N/A
1301	Annex	B		Men's Restroom	yes	Bathroom Stall	Metal	Green	rusting/flaking	2	0.07	Negative
1301	Annex	B		Men's Restroom	yes	Ceiling	Plaster	White	Flaking	5	10.5	Positive
1301	Annex	B		Men's Restroom	yes	Floor	Concrete	Brown	Chipping	20	0.01	Negative
1301	Annex	B	0B9	Storage outside Cafeteria	no	W1	CMU	Green/White	None	0	N/A	N/A
1301	Annex	B	0B9	Storage outside Cafeteria	no	Column	Plaster	White	Efflorescence/flaking	4	0.16	Negative

				Inspection Dates: May 2020			School District of Philadelphia					
				Name of Inspector: Paul Davis			Lead Safe Certification Assessment Report					
				Inspection Company: VERTEX			1300 A.D. Harrington ES/1301 Harrington Annex School					
ULCS#	Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1301	Annex	B	0B9	Storage outside Cafeteria	no	W2	CMU	Green	Partially Inaccessible	0	0.03	Negative
1301	Annex	B	0B9	Storage outside Cafeteria	no	W3	Plaster	Tan/Green	Efflorescence/flaking/s palling	100	0.03	Negative
1301	Annex	B	0B9	Storage outside Cafeteria	no	Window Sill	Wood	Green	chipping/flaking	3	0.07	Negative
1301	Annex	B	0B9	Storage outside Cafeteria	no	W4	CMU	Green	Partially Inaccessible	0	0.01	Negative
1301	Annex	B	0B9	Storage outside Cafeteria	no	Ceiling	Plaster	Tan	chipping/flaking	5	0.01	Negative
1301	Annex	B	0B9	Storage outside Cafeteria	no	Ceiling	Metal	Tan	flaking/rusting	15	0.03	Negative
1301	Annex	B	0B9	Storage outside Cafeteria	no	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1301	Annex	B	004B	Storage outside Boiler Room	no	W1	CMU	White	Partially Inaccessible	0	0.02	Negative
1301	Annex	B	004B	Storage outside Boiler Room	no	W2	Brick	White	Flaking	75	0.03	Negative
1301	Annex	B	004B	Storage outside Boiler Room	no	Window Sill	Concrete	Grey	Chipping/Flaking	3	0.21	Negative
1301	Annex	B	004B	Storage outside Boiler Room	no	Pipe Outer Cover	Metal	Tan	Flaking	2	0.1	Negative
1301	Annex	B	004B	Storage outside Boiler Room	no	W3	CMU	White	Partially Inaccessible	0	0.04	Negative
1301	Annex	B	004B	Storage outside Boiler Room	no	W4	CMU	White	Partially Inaccessible	0	0.02	Negative
1301	Annex	B	004B	Storage outside Boiler Room	no	Ceiling	Concrete	White	Flaking	4	4.4	Positive
1301	Annex	B	004B	Storage outside Boiler Room	no	Floor	Concrete	Grey	Chipping/Flaking	25	0.15	Negative
1301	Annex	B	SB	Stairs	yes	W1	Plaster	White	Flaking	1	20.1	Positive
1301	Annex	B	SB	Stairs	yes	Door	Wood	Brown	Chipping/Flaking	5	0	Negative
1301	Annex	B	SB	Stairs	yes	Door Frame	Wood	Brown	Chipping/Flaking	6	0.09	Negative
1301	Annex	B	SB	Stairs	yes	W2	Plaster	White	Flaking	3	24.7	Positive
1301	Annex	B	SB	Stairs	yes	W2	CMU	White	None	0	N/A	N/A
1301	Annex	B	SB	Stairs	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
1301	Annex	B	SB	Stairs	yes	W4	Plaster	White	Efflorescence/flaking	10	23.3	Positive
1301	Annex	B	SB	Stairs	yes	Handrail	Wood	Brown	Friction	12	0.12	Negative
1301	Annex	B	SB	Stairs	yes	Ceiling	Plaster	White	Flaking	1	7.2	Positive
1301	Annex	B	SB	Stairs	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1301	Annex	B	SB	Stairs	yes	Riser	Metal	Brown	chipping/flaking	2	0.05	Negative
1301	Annex	B	SB	Stairs	yes	Tread	Metal	Brown	Chipping	10	0.04	Negative
1301	Annex	B	SB	Stairs	yes	Stringer	Metal	Brown	Flaking	2	2.3	Positive
1301	Annex	B	SB	Rear Stairs	yes	W1	Plaster	White	None	0	N/A	N/A
1301	Annex	B	SB	Rear Stairs	yes	W2	CMU	White	Efflorescence	12	0.07	Negative
1301	Annex	B	SB	Rear Stairs	yes	W3	CMU	White	None	0	N/A	N/A
1301	Annex	B	SB	Rear Stairs	yes	W4	CMU	White	None	0	N/A	N/A
1301	Annex	B	SB	Rear Stairs	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1301	Annex	B	SB	Rear Stairs	yes	Stair Underside	Metal	Tan	chipping/rusting	20	0.08	Negative
1301	Annex	B	SB	Rear Stairs	yes	Floor	Concrete	N/A	None	0	N/A	N/A
1301	Annex	B	SB	Rear Stairs	yes	Riser	Metal	Green/Grey	Chipping	5	0.07	Negative
1301	Annex	B	SB	Rear Stairs	yes	Spindels	Metal	Tan	Chipping	10	2.2	Positive
1301	Annex	B	SB	Rear Stairs	yes	Newell Post	Metal	Tan	Chipping	2	1.6	Positive
1301	Annex	B	SB	Rear Stairs	yes	Stringer	Metal	Tan	Chipping	2	2.5	Positive
1301	Annex	B	Hall	Hallway	yes	W1	CMU	White	None	0	N/A	N/A
1301	Annex	B	Hall	Hallway	yes	Door Frame	Metal	Brown	Chipping	8	0.04	Negative
1301	Annex	B	Hall	Hallway	yes	Column	Plaster	White	flaking/efflorescence	6	2.3	Positive
1301	Annex	B	Hall	Hallway	yes	W2	CMU	White	None	0	N/A	N/A

				Inspection Dates: May 2020		School District of Philadelphia						
				Name of Inspector: Paul Davis		Lead Safe Certification Assessment Report						
				Inspection Company: VERTEX		1300 A.D. Harrington ES/1301 Harrington Annex School						
ULCS#	Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1301	Annex	B	Hall	Hallway	yes	W3	CMU	White	None	0	N/A	N/A
1301	Annex	B	Hall	Hallway	yes	Door Frame	Metal	White	Chipping	8	0.04	Negative
1301	Annex	B	Hall	Hallway	yes	W4	CMU	White	None	0	N/A	N/A
1301	Annex	B	Hall	Hallway	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1301	Annex	B	Hall	Hallway	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A