

					Inspection Dates: May 2020		School District of Philadelphia							
					Name of Inspector: Paul Davis		Lead Safe Certification Assessment Report							
					Inspection Company: VERTEX		Lea Elementary School							
ULCS#	E l e m e n t	BldgElmt ID	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1340	1	B134001-1	1	103	Conference Room	Conference Room 103	yes	W1	Plaster	White	Partially Inaccessible	0	33.3	Positive
1340	1	B134001-1	1	103	Conference Room	Conference Room 103	yes	Shelving	Wood	White	Partially Inaccessible	0	0	Negative
1340	1	B134001-1	1	103	Conference Room	Conference Room 103	yes	Pipe	Metal	White	Flaking	1	0.04	Negative
1340	1	B134001-1	1	103	Conference Room	Conference Room 103	yes	Door Frame	Wood	White	Partially Inaccessible	0	0.17	Negative
1340	1	B134001-1	1	103	Conference Room	Conference Room 103	yes	Door	Wood	White	Partially Inaccessible	0	0	Negative
1340	1	B134001-1	1	103	Conference Room	Conference Room 103	yes	W2	Plaster	White	Partially Inaccessible	0	0	Negative
1340	1	B134001-1	1	103	Conference Room	Conference Room 103	yes	Radiator	Metal	Gray	Flaking	6	1.3	Positive
1340	1	B134001-1	1	103	Conference Room	Conference Room 103	yes	W3	Plaster	White	Partially Inaccessible	0	36.6	Positive
1340	1	B134001-1	1	103	Conference Room	Conference Room 103	yes	Window Frame	Wood	White	Chipping	5	0.27	Negative
1340	1	B134001-1	1	103	Conference Room	Conference Room 103	yes	Radiator	Metal	Gray	Flaking	6	1.3	Positive
1340	1	B134001-1	1	103	Conference Room	Conference Room 103	yes	W4	Plaster	White	Partially Inaccessible	0	0	Negative
1340	1	B134001-1	1	103	Conference Room	Conference Room 103	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1340	1	B134001-1	1	103	Conference Room	Conference Room 103	yes	Floor	Wood	Varnish	N/A	N/A	N/A	N/A
1340	1	B134001-1	1	103	Conference Room	Conference Room 103	yes	Baseboard	Wood	Tan	Partially Inaccessible	0	0.07	Negative
1340	1	B134001-1	1	104	General Administrative Space	Main Office	yes	W1	Plaster	White	Flaking	1	0.07	Negative
1340	1	B134001-1	1	104	General Administrative Space	Main Office	yes	Door Frame	Wood	White	Chipping	2	0.23	Negative
1340	1	B134001-1	1	104	General Administrative Space	Main Office	yes	Vent Grate	Metal	White	Chipping	1	0.08	Negative
1340	1	B134001-1	1	104	General Administrative Space	Main Office	yes	W2	Sheetrock	White	Partially Inaccessible	0	0.09	Negative
1340	1	B134001-1	1	104	General Administrative Space	Main Office	yes	W2	Metal	White	Partially Inaccessible/Flaking	1	0.11	Negative
1340	1	B134001-1	1	104	General Administrative Space	Main Office	yes	W3	Plaster	White	Partially Inaccessible	0	19.6	Positive
1340	1	B134001-1	1	104	General Administrative Space	Main Office	yes	Window Frame	Wood	White	Chipping	5	0.19	Negative
1340	1	B134001-1	1	104	General Administrative Space	Main Office	yes	W4	Plaster	White	Chipping/Flaking	6	37.6	Positive
1340	1	B134001-1	1	104	General Administrative Space	Main Office	yes	Bulletin Board Frame	Wood	White	Chipping	2	0	Negative
1340	1	B134001-1	1	104	General Administrative Space	Main Office	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1340	1	B134001-1	1	104	General Administrative Space	Main Office	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1340	1	B134001-1	1	104	General Administrative Space	Main Office	yes	File Cabinet/Counter	Metal	Gray	Chipping	20	0	Negative
1340	1	B134001-1	1	104	General Administrative Space	Main Office	yes	Baseboard	Wood	Brown	Chipping	6	0.13	Negative
1340	1	B134001-1	1	104B	Administrative Office	Office in Main Office	yes	W1	Plaster	White	Flaking	4	23.9	Positive
1340	1	B134001-1	1	104B	Administrative Office	Office in Main Office	yes	W2	Plaster	White	None	0	34.6	Positive
1340	1	B134001-1	1	104B	Administrative Office	Office in Main Office	yes	Radiator	Metal	Gray	Flaking	4	2.4	Positive
1340	1	B134001-1	1	104B	Administrative Office	Office in Main Office	yes	W3	Plaster	White	Partially Inaccessible/Flaking	1	26.8	Positive
1340	1	B134001-1	1	104B	Administrative Office	Office in Main Office	yes	W4	Plaster	White	Partially Inaccessible	0	0.05	Negative
1340	1	B134001-1	1	104B	Administrative Office	Office in Main Office	yes	Ceiling	Concrete	White	None	0	N/A	N/A
1340	1	B134001-1	1	104B	Administrative Office	Office in Main Office	yes	Floor	Concrete	Gray	Partially Inaccessible/Chipping	2	0	Negative
1340	1	B134001-1	1	104B	Administrative Office	Office in Main Office	yes	Baseboard	Concrete	Gray	Partially Inaccessible	0	0.02	Negative
1340	1	B134001-1	1	104D	Administrative Storage	Main Office File Room	yes	W1	Plaster	Green	Partially Inaccessible/Chipping/Hole	6	0	Negative
1340	1	B134001-1	1	104D	Administrative Storage	Main Office File Room	yes	Door	Wood	White	Chipping	4	0.16	Negative
1340	1	B134001-1	1	104D	Administrative Storage	Main Office File Room	yes	Door Frame	Wood	Green	Chipping/Cracking	15	0.23	Negative
1340	1	B134001-1	1	104D	Administrative Storage	Main Office File Room	yes	W2	Plaster	Green	Partially Inaccessible	0	0	Negative

1340	1	B134001-1	1	104D	Administrative Storage	Main Office File Room	yes	W3	Plaster	Green	Partially Inaccessible/Chipping	12	0.03	Negative
1340	1	B134001-1	1	104D	Administrative Storage	Main Office File Room	yes	W4	Plaster	Green	Partially Inaccessible	0	4.9	Positive
1340	1	B134001-1	1	104D	Administrative Storage	Main Office File Room	yes	Ceiling	Plaster	White	Chipping/Flaking	30	5.58	Positive
1340	1	B134001-1	1	104D	Administrative Storage	Main Office File Room	yes	Pipe	Metal	Green	Chipping	1	0.22	Negative
1340	1	B134001-1	1	104D	Administrative Storage	Main Office File Room	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1340	1	B134001-1	1	104D	Administrative Storage	Main Office File Room	yes	Baseboard	Wood	Gray	Partially Inaccessible	0	0.05	Negative
1340	1	B134001-1	1	104A	Principal/Directors Office	Principal's Office	yes	W1	Sheetrock	White	Chipping	1	0.01	Negative
1340	1	B134001-1	1	104A	Principal/Directors Office	Principal's Office	yes	W1	Metal	White	Partially Inaccessible	0	0.04	Negative
1340	1	B134001-1	1	104A	Principal/Directors Office	Principal's Office	yes	Door	Metal	Black	Chipping	4	0.14	Negative
1340	1	B134001-1	1	104A	Principal/Directors Office	Principal's Office	yes	W2	Metal	White	Partially Inaccessible	0	0.14	Negative
1340	1	B134001-1	1	104A	Principal/Directors Office	Principal's Office	yes	W3	Plaster	White	Partially Inaccessible	0	0.04	Negative
1340	1	B134001-1	1	104A	Principal/Directors Office	Principal's Office	yes	W4	Plaster	White	Partially Inaccessible	0	38.3	Positive
1340	1	B134001-1	1	104A	Principal/Directors Office	Principal's Office	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1340	1	B134001-1	1	104A	Principal/Directors Office	Principal's Office	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1340	1	B134001-1	1	104A	Principal/Directors Office	Principal's Office	yes	Baseboard	Wood	Brown	Partially Inaccessible	0	0.19	Negative
1340	1	B134001-1	1	104E	Storage	Principal's Office Closet	yes	W1	Sheetrock	White	None	0	0	Negative
1340	1	B134001-1	1	104E	Storage	Principal's Office Closet	yes	W2	Metal	White	Flaking/Chipping	1	0.11	Negative
1340	1	B134001-1	1	104E	Storage	Principal's Office Closet	yes	W3	Metal	White	Partially Inaccessible	0	0.17	Negative
1340	1	B134001-1	1	104E	Storage	Principal's Office Closet	yes	W3	Sheetrock	White	Hole	1	0.13	Negative
1340	1	B134001-1	1	104E	Storage	Principal's Office Closet	yes	W4	Metal	White	Partially Inaccessible	0	0.19	Negative
1340	1	B134001-1	1	104E	Storage	Principal's Office Closet	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1340	1	B134001-1	1	104E	Storage	Principal's Office Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1340	1	B134001-1	1	104F	Restrooms, Staff - Male/Female	Principal's Office Restroom	yes	W1	Plaster	White	None	0	0.15	Negative
1340	1	B134001-1	1	104F	Restrooms, Staff - Male/Female	Principal's Office Restroom	yes	W2	Metal	White	Flaking	2	0.23	Negative
1340	1	B134001-1	1	104F	Restrooms, Staff - Male/Female	Principal's Office Restroom	yes	W3	Sheetrock	White	Flaking	1	0.09	Negative
1340	1	B134001-1	1	104F	Restrooms, Staff - Male/Female	Principal's Office Restroom	yes	W4	Plaster	White	Cracking	3	32.1	Positive
1340	1	B134001-1	1	104F	Restrooms, Staff - Male/Female	Principal's Office Restroom	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1340	1	B134001-1	1	104F	Restrooms, Staff - Male/Female	Principal's Office Restroom	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1340	1	B134001-1	1	104G	Circulation (Hallway)	Principal's Office Walkway	yes	W1	Plaster	White	None	0	0.01	Negative
1340	1	B134001-1	1	104G	Circulation (Hallway)	Principal's Office Walkway	yes	W2	Plaster	White	None	0	0.02	Negative
1340	1	B134001-1	1	104G	Circulation (Hallway)	Principal's Office Walkway	yes	W3	Sheetrock	White	None	0	0	Negative
1340	1	B134001-1	1	104G	Circulation (Hallway)	Principal's Office Walkway	yes	W4	Sheetrock	White	Chipping	1	0.05	Negative
1340	1	B134001-1	1	104G	Circulation (Hallway)	Principal's Office Walkway	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1340	1	B134001-1	1	104G	Circulation (Hallway)	Principal's Office Walkway	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1340	1	B134001-1	1	104G	Circulation (Hallway)	Principal's Office Walkway	yes	Baseboard	Wood	Brown	Chipping	2	0.21	Negative
1340	1	B134001-1	1	104C	Restrooms, Staff - Male/Female	Staff Restroom in Hallway outside Main Office	yes	W1	Plaster	White	None	0	19.5	Positive
1340	1	B134001-1	1	104C	Restrooms, Staff - Male/Female	Staff Restroom in Hallway outside Main Office	yes	W2	Plaster	White	Chipping	3	17.9	Positive
1340	1	B134001-1	1	104C	Restrooms, Staff - Male/Female	Staff Restroom in Hallway outside Main Office	yes	W3	Plaster	White	Chipping/Flaking	15	23	Positive
1340	1	B134001-1	1	104C	Restrooms, Staff - Male/Female	Staff Restroom in Hallway outside Main Office	yes	W4	Plaster	White	None	0	27.6	Positive
1340	1	B134001-1	1	104C	Restrooms, Staff - Male/Female	Staff Restroom in Hallway outside Main Office	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1340	1	B134001-1	1	104C	Restrooms, Staff - Male/Female	Staff Restroom in Hallway outside Main Office	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1340	1	B134001-1	1	104C	Restrooms, Staff - Male/Female	Staff Restroom in Hallway outside Main Office	yes	Baseboard	Concrete	Gray	Chipping	4	0.23	Negative
1340	1	B134001-1	1	112	Health Service Room	Nurse's Office across from Main Office	yes	W1	Plaster	White	Flaking	6	32.9	Positive
1340	1	B134001-1	1	112	Health Service Room	Nurse's Office across from Main Office	yes	Door Frame	Wood	White	Chipping/Cracking	2	0.05	Negative
1340	1	B134001-1	1	112	Health Service Room	Nurse's Office across from Main Office	yes	W2	Plaster	White	Holes/Flaking	12	28.5	Positive
1340	1	B134001-1	1	112	Health Service Room	Nurse's Office across from Main Office	yes	Door Frame	Wood	White	Chipping	8	0.12	Negative

1340	1	B134001-1	1	112	Health Service Room	Nurse's Office across from Main Office	yes	W3	Plaster	White	Flaking	2	32	Positive
1340	1	B134001-1	1	112	Health Service Room	Nurse's Office across from Main Office	yes	Window Frame	Wood	White	Chipping	3	0.01	Negative
1340	1	B134001-1	1	112	Health Service Room	Nurse's Office across from Main Office	yes	W4	Plaster	White	Flaking	10	34	Positive
1340	1	B134001-1	1	112	Health Service Room	Nurse's Office across from Main Office	yes	Radiator	Metal	Gray	Flaking	4	2.3	Positive
1340	1	B134001-1	1	112	Health Service Room	Nurse's Office across from Main Office	yes	Window Frame	Wood	White	Flaking	3	0.25	Negative
1340	1	B134001-1	1	112	Health Service Room	Nurse's Office across from Main Office	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1340	1	B134001-1	1	112	Health Service Room	Nurse's Office across from Main Office	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1340	1	B134001-1	1	112	Health Service Room	Nurse's Office across from Main Office	yes	Baseboard	Wood	Brown	Chipping	12	0.03	Negative
1340	1	B134001-1	1	113	Health Service Room	Patient Area in Nurse's Suite	yes	W1	Plaster	White	Partially Inaccessible	0	16	Positive
1340	1	B134001-1	1	113	Health Service Room	Patient Area in Nurse's Suite	yes	Door	Wood	White	Chipping	4	0.25	Negative
1340	1	B134001-1	1	113	Health Service Room	Patient Area in Nurse's Suite	yes	W2	Plaster	White	Efflorescence/Flaking	2	21.3	Positive
1340	1	B134001-1	1	113	Health Service Room	Patient Area in Nurse's Suite	yes	W3	Metal	White	None	0	0.11	Negative
1340	1	B134001-1	1	113	Health Service Room	Patient Area in Nurse's Suite	yes	W4	Plaster	White	Partially Inaccessible	0	1.3	Positive
1340	1	B134001-1	1	113	Health Service Room	Patient Area in Nurse's Suite	yes	Window Sill	Brick	White	Chipping/Flaking	2	0.3	Negative
1340	1	B134001-1	1	113	Health Service Room	Patient Area in Nurse's Suite	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1340	1	B134001-1	1	113	Health Service Room	Patient Area in Nurse's Suite	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1340	1	B134001-1	1	113A	Student Restrooms - Male/Female	Nurse's Suite Restroom	yes	W1	Sheetrock	White	Efflorescence/Flaking	3	0.05	Negative
1340	1	B134001-1	1	113A	Student Restrooms - Male/Female	Nurse's Suite Restroom	yes	W2	Plaster	White	Flaking	2	0.03	Negative
1340	1	B134001-1	1	113A	Student Restrooms - Male/Female	Nurse's Suite Restroom	yes	W3	Plaster	White	Flaking	4	21.9	Positive
1340	1	B134001-1	1	113A	Student Restrooms - Male/Female	Nurse's Suite Restroom	yes	W4	Metal	White	None	0	0.1	Negative
1340	1	B134001-1	1	113A	Student Restrooms - Male/Female	Nurse's Suite Restroom	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1340	1	B134001-1	1	113A	Student Restrooms - Male/Female	Nurse's Suite Restroom	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1340	1	B134001-1	1	H14	Circulation (Hallway)	Hallway at the Main Office	yes	W1	Metal	White	Hole	1	0.5	Negative
1340	1	B134001-1	1	H14	Circulation (Hallway)	Hallway at the Main Office	yes	Door	Metal	Blue	Chipping	5	0	Negative
1340	1	B134001-1	1	H14	Circulation (Hallway)	Hallway at the Main Office	yes	Door Frame	Metal	Blue	Chipping	4	0.08	Negative
1340	1	B134001-1	1	H14	Circulation (Hallway)	Hallway at the Main Office	yes	W2	Plaster	White	Chipping/Flaking	6	21.6	Positive
1340	1	B134001-1	1	H14	Circulation (Hallway)	Hallway at the Main Office	yes	Radiator Cover	Metal	Green	Chipping/Flaking	2	0	Negative
1340	1	B134001-1	1	H14	Circulation (Hallway)	Hallway at the Main Office	yes	W3	Plaster	White	None	0	0.07	Negative
1340	1	B134001-1	1	H14	Circulation (Hallway)	Hallway at the Main Office	yes	Door	Metal	Blue	Chipping	5	0	Negative
1340	1	B134001-1	1	H14	Circulation (Hallway)	Hallway at the Main Office	yes	Door Frame	Metal	Blue	Chipping	6	0.03	Negative
1340	1	B134001-1	1	H14	Circulation (Hallway)	Hallway at the Main Office	yes	W4	Plaster	White	None	0	19.6	Positive
1340	1	B134001-1	1	H14	Circulation (Hallway)	Hallway at the Main Office	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1340	1	B134001-1	1	H14	Circulation (Hallway)	Hallway at the Main Office	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1340	1	B134001-1	1	H14	Circulation (Hallway)	Hallway at the Main Office	yes	Baseboard	Concrete	Brown	Chipping	12	3.7	Positive
1340	1	B134001-1	1	S11	Stairs	Stairwell by Classroom 105	yes	W1	Plaster	White	Chipping/Flaking	10	22.7	Positive
1340	1	B134001-1	1	S11	Stairs	Stairwell by Classroom 105	yes	W2	Metal	White	Chipping	4	0.5	Negative
1340	1	B134001-1	1	S11	Stairs	Stairwell by Classroom 105	yes	W2	Plaster	White	None	0	24.2	Positive
1340	1	B134001-1	1	S11	Stairs	Stairwell by Classroom 105	yes	W3	Metal	White	Hole	1	0.4	Negative
1340	1	B134001-1	1	S11	Stairs	Stairwell by Classroom 105	yes	W3	Plaster	White	Chipping	4	15.8	Positive
1340	1	B134001-1	1	S11	Stairs	Stairwell by Classroom 105	yes	W4	Plaster	White	Flaking	20	23.2	Positive
1340	1	B134001-1	1	S11	Stairs	Stairwell by Classroom 105	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1340	1	B134001-1	1	S11	Stairs	Stairwell by Classroom 105	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1340	1	B134001-1	1	S11	Stairs	Stairwell by Classroom 105	yes	Baseboard	Concrete	Gray	Chipping	20	4.1	Positive
1340	1	B134001-1	1	S11	Stairs	Stairwell by Classroom 105	yes	Riser	Metal	Gray	Chipping	6	2.6	Positive
1340	1	B134001-1	1	S11	Stairs	Stairwell by Classroom 105	yes	Stringer	Metal	Gray	Chipping	6	6.1	Positive
1340	1	B134001-1	1	S11	Stairs	Stairwell by Classroom 105	yes	Hand Rail	Wood	Gray	Friction	20	0.14	Negative
1340	1	B134001-1	1	S11	Stairs	Stairwell by Classroom 105	yes	Newel Post	Metal	Gray	Chipping	4	2.3	Positive
1340	1	B134001-1	1	S11	Stairs	Stairwell by Classroom 105	yes	Spindles	Metal	Gray	Chipping	20	2.9	Positive
1340	1	B134001-1	1	S11	Stairs	Stairwell by Classroom 105	yes	Stair Undercarriage	Concrete	White	Flaking	10	8.3	Positive
1340	1	B134001-1	1		Exit Vestibule for Stairwell by Classroom 105	Exit Vestibule for Stairwell by Classroom 105	yes	W1	Plaster	White	Flaking	20	3.73	Positive
1340	1	B134001-1	1		Exit Vestibule for Stairwell by Classroom 105	Exit Vestibule for Stairwell by Classroom 105	yes	W2	Metal	Blue	Chipping	2	0.01	Negative
1340	1	B134001-1	1		Exit Vestibule for Stairwell by Classroom 105	Exit Vestibule for Stairwell by Classroom 105	yes	W3	Plaster	White	Flaking/Cracking	15	2.67	Positive
1340	1	B134001-1	1		Exit Vestibule for Stairwell by Classroom 105	Exit Vestibule for Stairwell by Classroom 105	yes	W4	Plaster	White	Flaking/Cracking	25	0.11	Negative
1340	1	B134001-1	1		Exit Vestibule for Stairwell by Classroom 105	Exit Vestibule for Stairwell by Classroom 105	yes	Door	Metal	Blue	Chipping	2	0.01	Negative
1340	1	B134001-1	1		Exit Vestibule for Stairwell by Classroom 105	Exit Vestibule for Stairwell by Classroom 105	yes	Door Frame	Metal	Blue	Chipping	2	0.1	Negative
1340	1	B134001-1	1		Exit Vestibule for Stairwell by Classroom 105	Exit Vestibule for Stairwell by Classroom 105	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1340	1	B134001-1	1		Exit Vestibule for Stairwell by Classroom 105	Exit Vestibule for Stairwell by Classroom 105	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1340	1	B134001-1	1		Exit Vestibule for Stairwell by Classroom 105	Exit Vestibule for Stairwell by Classroom 105	yes	Covebase	Concrete	Grey	Chipping	8	2.41	Positive
1340	1	B134001-1	1	105	Primary	Classroom 105	yes	W1	Plaster	White	Partially Inaccessible	0	28.3	Positive

1340	1	B134001-1	1	105	Primary	Classroom 105	yes	Pipe	Metal	Brown	Chipping	12	1.8	Positive
1340	1	B134001-1	1	105	Primary	Classroom 105	yes	Door Frame	Wood	White	Chipping	2	0.14	Negative
1340	1	B134001-1	1	105	Primary	Classroom 105	yes	Coat Rack	Wood	White	Chipping	8	0.08	Negative
1340	1	B134001-1	1	105	Primary	Classroom 105	yes	Door Frame on Floor	Metal	Brown	Chipping	6	1.2	Positive
1340	1	B134001-1	1	105	Primary	Classroom 105	yes	W2	Plaster	White	Partially Inaccessible/Flaking	8	0	Negative
1340	1	B134001-1	1	105	Primary	Classroom 105	yes	W3	Plaster	White	Chipping	4	38.7	Positive
1340	1	B134001-1	1	105	Primary	Classroom 105	yes	Window Frames	Wood	White	Chipping	8	0.08	Negative
1340	1	B134001-1	1	105	Primary	Classroom 105	yes	W4	Plaster	White	Chipping	8	37.7	Positive
1340	1	B134001-1	1	105	Primary	Classroom 105	yes	W4	Wood	White	Chipping/Cracking	25	0.12	Negative
1340	1	B134001-1	1	105	Primary	Classroom 105	yes	Wall Frame	Wood	White	Chipping	6	0.06	Negative
1340	1	B134001-1	1	105	Primary	Classroom 105	yes	Ceiling	Plaster	Beige	Flaking	20	6.44	Positive
1340	1	B134001-1	1	105	Primary	Classroom 105	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1340	1	B134001-1	1	105	Primary	Classroom 105	yes	Floor	Wood	Varnish	Partially Inaccessible	0	0.01	Negative
1340	1	B134001-1	1	105	Primary	Classroom 105	yes	Baseboard	Wood	Brown	Partially Inaccessible	0	0.07	Negative
1340	1	B134001-1	1	106	Primary	Classroom 106	yes	W1	Plaster	White	Partially Inaccessible	0	22.3	Positive
1340	1	B134001-1	1	106	Primary	Classroom 106	yes	Pipe	Metal	Brown	Chipping	2	1.3	Positive
1340	1	B134001-1	1	106	Primary	Classroom 106	yes	Door Frame	Wood	Blue	Chipping	6	0.09	Negative
1340	1	B134001-1	1	106	Primary	Classroom 106	yes	Door Frame	Wood	White	Chipping	5	0.1	Negative
1340	1	B134001-1	1	106	Primary	Classroom 106	yes	W2	Sheetrock	White	Partially Inaccessible	0	0	Negative
1340	1	B134001-1	1	106	Primary	Classroom 106	yes	W3	Plaster	White	None	0	36.7	Positive
1340	1	B134001-1	1	106	Primary	Classroom 106	yes	W4	Plaster	Green	Flaking	1	0	Negative
1340	1	B134001-1	1	106	Primary	Classroom 106	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1340	1	B134001-1	1	106	Primary	Classroom 106	yes	Floor	Wood	Varnish	None	0	N/A	N/A
1340	1	B134001-1	1	114	Administrative Office	Counselor's Office across from Classroom 106	yes	W1	Plaster	White	Partially Inaccessible	0	28.5	Positive
1340	1	B134001-1	1	114	Administrative Office	Counselor's Office across from Classroom 106	yes	Door Frame	Wood	Gray	Chipping	8	0.27	Negative
1340	1	B134001-1	1	114	Administrative Office	Counselor's Office across from Classroom 106	yes	W2	Plaster	White	None	0	31.2	Positive
1340	1	B134001-1	1	114	Administrative Office	Counselor's Office across from Classroom 106	yes	Radiator	Metal	Gray	Chipping/Flaking	4	6.2	Positive
1340	1	B134001-1	1	114	Administrative Office	Counselor's Office across from Classroom 106	yes	W3	Metal	White	None	0	0.18	Negative
1340	1	B134001-1	1	114	Administrative Office	Counselor's Office across from Classroom 106	yes	W4	Plaster	White	Partially Inaccessible	0	0.24	Negative
1340	1	B134001-1	1	114	Administrative Office	Counselor's Office across from Classroom 106	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1340	1	B134001-1	1	114	Administrative Office	Counselor's Office across from Classroom 106	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1340	1	B134001-1	1	114	Administrative Office	Counselor's Office across from Classroom 106	yes	Baseboard	Wood	Brown	Chipping	6	0.3	Negative
1340	1	B134001-1	1	106A	Administrative Office	Office 124 next to Classroom 106	yes	W1	Plaster	Blue	Flaking	2	16	Positive
1340	1	B134001-1	1	106A	Administrative Office	Office 124 next to Classroom 106	yes	Door Frame	Wood	Gray	Chipping	6	0.14	Negative
1340	1	B134001-1	1	106A	Administrative Office	Office 124 next to Classroom 106	yes	Door	Wood	Gray	Chipping	4	0.19	Negative
1340	1	B134001-1	1	106A	Administrative Office	Office 124 next to Classroom 106	yes	W2	Plaster	Blue	Partially Inaccessible	0	21.6	Positive
1340	1	B134001-1	1	106A	Administrative Office	Office 124 next to Classroom 106	yes	W3	Plaster	Blue	None	0	26.1	Positive
1340	1	B134001-1	1	106A	Administrative Office	Office 124 next to Classroom 106	yes	Radiator	Metal	Gray	Chipping/Flaking	2	14.9	Positive
1340	1	B134001-1	1	106A	Administrative Office	Office 124 next to Classroom 106	yes	W4	Plaster	Blue	Partially Inaccessible	0	20.3	Positive
1340	1	B134001-1	1	106A	Administrative Office	Office 124 next to Classroom 106	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1340	1	B134001-1	1	106A	Administrative Office	Office 124 next to Classroom 106	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1340	1	B134001-1	1	S16	Circulation (Hallway)	Original Main Entrance Foyer between Offices 124 and 125	yes	W1	Plaster	White	None	0	37.9	Positive
1340	1	B134001-1	1	S16	Circulation (Hallway)	Original Main Entrance Foyer between Offices 124 and 125	yes	W2	Plaster	White	None	0	38.6	Positive
1340	1	B134001-1	1	S16	Circulation (Hallway)	Original Main Entrance Foyer between Offices 124 and 125	yes	W3	Metal	Blue	None	0	0	Negative
1340	1	B134001-1	1	S16	Circulation (Hallway)	Original Main Entrance Foyer between Offices 124 and 125	yes	W4	Plaster	White	None	0	38.3	Positive
1340	1	B134001-1	1	S16	Circulation (Hallway)	Original Main Entrance Foyer between Offices 124 and 125	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1340	1	B134001-1	1	S16	Circulation (Hallway)	Original Main Entrance Foyer between Offices 124 and 125	yes	Floor	Marble	N/A	N/A	N/A	N/A	N/A
1340	1	B134001-1	1	106B	Administrative Office	Office 125 next to Classroom 108	yes	W1	Plaster	Blue	None	0	21.9	Positive
1340	1	B134001-1	1	106B	Administrative Office	Office 125 next to Classroom 108	yes	Door Frame	Wood	Gray	Chipping	4	0.07	Negative
1340	1	B134001-1	1	106B	Administrative Office	Office 125 next to Classroom 108	yes	Door	Wood	Gray	Chipping	4	0.17	Negative
1340	1	B134001-1	1	106B	Administrative Office	Office 125 next to Classroom 108	yes	W2	Plaster	Blue	Chipping	3	18.4	Positive
1340	1	B134001-1	1	106B	Administrative Office	Office 125 next to Classroom 108	yes	W3	Plaster	Blue	None	0	26.9	Positive
1340	1	B134001-1	1	106B	Administrative Office	Office 125 next to Classroom 108	yes	Radiator	Metal	Gray	Chipping	4	15.8	Positive
1340	1	B134001-1	1	106B	Administrative Office	Office 125 next to Classroom 108	yes	W4	Plaster	Blue	Chipping	6	23.8	Positive
1340	1	B134001-1	1	106B	Administrative Office	Office 125 next to Classroom 108	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1340	1	B134001-1	1	106B	Administrative Office	Office 125 next to Classroom 108	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1340	1	B134001-1	1	106B	Administrative Office	Office 125 next to Classroom 108	yes	Baseboard	Concrete	Brown	Chipping	8	0.16	Negative
1340	1	B134001-1	1	107	Primary	Classroom 107	yes	W1	Plaster	White	Partially Inaccessible	0	25.4	Positive

1340	1	B134001-1	1	107	Primary	Classroom 107	yes	Pipe	Metal	Brown	Chipping	3	1.3	Positive
1340	1	B134001-1	1	107	Primary	Classroom 107	yes	Door Frame	Wood	Gray	Chipping	3	0.07	Negative
1340	1	B134001-1	1	107	Primary	Classroom 107	yes	Door	Wood	White	Flaking	1	0.13	Negative
1340	1	B134001-1	1	107	Primary	Classroom 107	yes	W2	Plaster	White	None	0	0	Negative
1340	1	B134001-1	1	107	Primary	Classroom 107	yes	W3	Plaster	White	None	0	32.1	Positive
1340	1	B134001-1	1	107	Primary	Classroom 107	yes	W4	Plaster	Blue	Chipping/Flaking	3	0	Negative
1340	1	B134001-1	1	107	Primary	Classroom 107	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1340	1	B134001-1	1	107	Primary	Classroom 107	yes	Floor	Wood	Varnish	None	N/A	N/A	N/A
1340	1	B134001-1	1	107	Primary	Classroom 107	yes	Baseboard	Wood	Brown	Chipping	12	0.17	Negative
1340	1	B134001-1	1	108	Primary	Classroom 108	yes	W1	Plaster	White	Partially Inaccessible/Chipping	3	23.8	Positive
1340	1	B134001-1	1	108	Primary	Classroom 108	yes	Pipe	Metal	Brown	Chipping	1	1.2	Positive
1340	1	B134001-1	1	108	Primary	Classroom 108	yes	Door Frame	Wood	Blue	Chipping	8	0.25	Negative
1340	1	B134001-1	1	108	Primary	Classroom 108	yes	Door Frame	Wood	White	Chipping/Flaking	10	0.18	Negative
1340	1	B134001-1	1	108	Primary	Classroom 108	yes	W2	Plaster	White	None	0	26.5	Positive
1340	1	B134001-1	1	108	Primary	Classroom 108	yes	W3	Plaster	White	None	0	33.5	Positive
1340	1	B134001-1	1	108	Primary	Classroom 108	yes	W4	Sheetrock	Yellow	Partially Inaccessible	0	0	Negative
1340	1	B134001-1	1	108	Primary	Classroom 108	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1340	1	B134001-1	1	108	Primary	Classroom 108	yes	Floor	Wood	Varnish	None	0	N/A	N/A
1340	1	B134001-1	1	108	Primary	Classroom 108	yes	Baseboard	Wood	Brown	Chipping	12	0.05	Negative
1340	1	B134001-1	1	109	Primary	Classroom 109	yes	W1	Plaster	White	Partially Inaccessible/Staple Holes	20	20.7	Positive
1340	1	B134001-1	1	109	Primary	Classroom 109	yes	Door Frame	Metal	Gray	Chipping	4	0.01	Negative
1340	1	B134001-1	1	109	Primary	Classroom 109	yes	Door	Metal	Gray	Chipping	4	0	Negative
1340	1	B134001-1	1	109	Primary	Classroom 109	yes	W2	Sheetrock	Green	None	0	0	Negative
1340	1	B134001-1	1	109	Primary	Classroom 109	yes	W3	Plaster	White	Cracking	3	34.1	Positive
1340	1	B134001-1	1	109	Primary	Classroom 109	yes	W4	Plaster	White	Flaking	15	0	Negative
1340	1	B134001-1	1	109	Primary	Classroom 109	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1340	1	B134001-1	1	109	Primary	Classroom 109	yes	Ceiling	Plaster	White	Flaking	20	11.44	Positive
1340	1	B134001-1	1	109	Primary	Classroom 109	yes	Floor	Wood	Varnish	None	0	N/A	N/A
1340	1	B134001-1	1	109	Primary	Classroom 109	yes	Baseboard	Wood	Brown	Chipping	6	0.12	Negative
1340	1	B134001-1	1	S13	Stairs	Stairwell by Classroom 109	yes	W1	Plaster	White	Chipping/Flaking	12	17.3	Positive
1340	1	B134001-1	1	S13	Stairs	Stairwell by Classroom 109	yes	W2	Plaster	White	None	0	16.4	Positive
1340	1	B134001-1	1	S13	Stairs	Stairwell by Classroom 109	yes	W3	Plaster	White	Flaking	12	0.8	Positive
1340	1	B134001-1	1	S13	Stairs	Stairwell by Classroom 109	yes	W4	Plaster	White	None	0	23.2	Positive
1340	1	B134001-1	1	S13	Stairs	Stairwell by Classroom 109	yes	W4	Metal	White	Scrapes	3	0.4	Negative
1340	1	B134001-1	1	S13	Stairs	Stairwell by Classroom 109	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1340	1	B134001-1	1	S13	Stairs	Stairwell by Classroom 109	yes	Ceiling	Plaster	White	None	0	3.57	Positive
1340	1	B134001-1	1	S13	Stairs	Stairwell by Classroom 109	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1340	1	B134001-1	1	S13	Stairs	Stairwell by Classroom 109	yes	Baseboard	Concrete	Gray	Chipping	12	2.7	Positive
1340	1	B134001-1	1	S13	Stairs	Stairwell by Classroom 109	yes	Riser	Metal	Gray	Chipping	6	2.7	Positive
1340	1	B134001-1	1	S13	Stairs	Stairwell by Classroom 109	yes	Stringer	Metal	Gray	Chipping	8	3.3	Positive
1340	1	B134001-1	1	S13	Stairs	Stairwell by Classroom 109	yes	Newel Post	Metal	Gray	Chipping	4	3	Positive
1340	1	B134001-1	1	S13	Stairs	Stairwell by Classroom 109	yes	Spindle	Metal	Gray	Chipping	20	2.4	Positive
1340	1	B134001-1	1	S13	Stairs	Stairwell by Classroom 109	yes	Hand Rail	Wood	Gray	Friction	15	0.06	Negative
1340	1	B134001-1	1	S13	Stairs	Stairwell by Classroom 109	yes	Stairs Undercarriage	Concrete	White	Flaking	6	9.1	Positive
1340	1	B134001-1	1	H15	Circulation (Hallway)	Hallway from Classrooms 105 to 109	yes	W1	Plaster	White	Chipping	6	27.4	Positive
1340	1	B134001-1	1	H15	Circulation (Hallway)	Hallway from Classrooms 105 to 109	yes	W2	Metal	White	None	0	0.4	Negative
1340	1	B134001-1	1	H15	Circulation (Hallway)	Hallway from Classrooms 105 to 109	yes	W3	Plaster	White	Chipping	4	24.9	Positive
1340	1	B134001-1	1	H15	Circulation (Hallway)	Hallway from Classrooms 105 to 109	yes	Paneling	Wood	White	Flaking	50	9.1	Positive
1340	1	B134001-1	1	H15	Circulation (Hallway)	Hallway from Classrooms 105 to 109	yes	Radiator Cover	Metal	Blue/Red	Chipping	2	0	Negative
1340	1	B134001-1	1	H15	Circulation (Hallway)	Hallway from Classrooms 105 to 109	yes	Window Sill	Brick	Brown	Chipping/Flaking	8	0.14	Negative
1340	1	B134001-1	1	H15	Circulation (Hallway)	Hallway from Classrooms 105 to 109	yes	W4	Metal	White	None	0	0.5	Negative
1340	1	B134001-1	1	H15	Circulation (Hallway)	Hallway from Classrooms 105 to 109	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1340	1	B134001-1	1	H15	Circulation (Hallway)	Hallway from Classrooms 105 to 109	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1340	1	B134001-1	1	H15	Circulation (Hallway)	Hallway from Classrooms 105 to 109	yes	Baseboard	Concrete	Brown	Chipping	10	3.7	Positive
1340	1	B134001-1	1	110A	Restrooms, Staff - Female	Women's Restroom next to Classroom 110	yes	W1	Plaster	White	None	0	28.1	Positive
1340	1	B134001-1	1	110A	Restrooms, Staff - Female	Women's Restroom next to Classroom 110	yes	Door	Wood	Blue	Chipping	8	0.14	Negative
1340	1	B134001-1	1	110A	Restrooms, Staff - Female	Women's Restroom next to Classroom 110	yes	Door Frame	Wood	Gray	Chipping	6	0.06	Negative
1340	1	B134001-1	1	110A	Restrooms, Staff - Female	Women's Restroom next to Classroom 110	yes	W2	Plaster	White	Chipping/Flaking/Spalling	15	24.6	Positive

1340	1	B134001-1	1	110A	Restrooms, Staff - Female	Women's Restroom next to Classroom 110	yes	W3	Plaster	White	None	0	2.4	Positive
1340	1	B134001-1	1	110A	Restrooms, Staff - Female	Women's Restroom next to Classroom 110	yes	Door Frame	Wood	Tan/Gray	Chipping	2	0.09	Negative
1340	1	B134001-1	1	110A	Restrooms, Staff - Female	Women's Restroom next to Classroom 110	yes	W4	Plaster	White	Flaking	1	30.8	Positive
1340	1	B134001-1	1	110A	Restrooms, Staff - Female	Women's Restroom next to Classroom 110	yes	Ceiling	Plaster	White	Efflorescence/Spalling/Flaking	40	3.28	Positive
1340	1	B134001-1	1	110A	Restrooms, Staff - Female	Women's Restroom next to Classroom 110	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1340	1	B134001-1	1	110A	Restrooms, Staff - Female	Women's Restroom next to Classroom 110	yes	Baseboard	Concrete	Gray	Chipping	10	2.3	Positive
1340	1	B134001-1	1	110A	Restrooms, Staff - Female	Women's Restroom next to Classroom 110	yes	Baseboard	Concrete	Brown	Chipping	8	3.9	Positive
1340	1	B134001-1	1	110	Primary	Classroom 110	yes	W1	Plaster	White	Partially Inaccessible	0	22.3	Positive
1340	1	B134001-1	1	110	Primary	Classroom 110	yes	W2	Plaster	White	Flaking	6	0	Negative
1340	1	B134001-1	1	110	Primary	Classroom 110	yes	W3	Plaster	White	Flaking	3	1.8	Positive
1340	1	B134001-1	1	110	Primary	Classroom 110	yes	W4	Plaster	Blue	Chipping	4	0	Negative
1340	1	B134001-1	1	110	Primary	Classroom 110	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1340	1	B134001-1	1	110	Primary	Classroom 110	yes	Floor	Wood	Varnish	None	0	N/A	N/A
1340	1	B134001-1	1	111	Primary	Classroom 111	yes	W1	Plaster	White	None	0	25	Positive
1340	1	B134001-1	1	111	Primary	Classroom 111	yes	Door Frame	Wood	Blue/White	Chipping	4	0.08	Negative
1340	1	B134001-1	1	111	Primary	Classroom 111	yes	W2	Plaster	Blue	Chipping	10	32.2	Positive
1340	1	B134001-1	1	111	Primary	Classroom 111	yes	W3	Plaster	White	None	0	35.4	Positive
1340	1	B134001-1	1	111	Primary	Classroom 111	yes	Window Frame	Wood	White	Chipping/Flaking	6	0.08	Negative
1340	1	B134001-1	1	111	Primary	Classroom 111	yes	W4	Plaster	White	None	0	0	Negative
1340	1	B134001-1	1	111	Primary	Classroom 111	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1340	1	B134001-1	1	111	Primary	Classroom 111	yes	Ceiling	Plaster	White	Flaking	10	4.59	Positive
1340	1	B134001-1	1	111	Primary	Classroom 111	yes	Floor	Wood	Varnish	None	0	N/A	N/A
1340	1	B134001-1	1	111	Primary	Classroom 111	yes	Baseboard	Wood	Brown	Chipping	20	0.21	Negative
1340	1	B134001-1	1	H16	Circulation (Hallway)	Hallway from Classrooms 110 to 111	yes	W1	Metal	White	Hole	1	0.5	Negative
1340	1	B134001-1	1	H16	Circulation (Hallway)	Hallway from Classrooms 110 to 111	yes	W2	Plaster	White	Chipping/Flaking	2	27.6	Positive
1340	1	B134001-1	1	H16	Circulation (Hallway)	Hallway from Classrooms 110 to 111	yes	W3	Plaster	Red/Yellow	None	0	22.8	Positive
1340	1	B134001-1	1	H16	Circulation (Hallway)	Hallway from Classrooms 110 to 111	yes	Door	Metal	Blue	Scrapes	4	0	Negative
1340	1	B134001-1	1	H16	Circulation (Hallway)	Hallway from Classrooms 110 to 111	yes	Door Frame	Metal	White	Chipping	4	0.23	Negative
1340	1	B134001-1	1	H16	Circulation (Hallway)	Hallway from Classrooms 110 to 111	yes	W4	Plaster	White	None	0	26.5	Positive
1340	1	B134001-1	1	H16	Circulation (Hallway)	Hallway from Classrooms 110 to 111	yes	Window Frame	Wood	White	Chipping/Flaking	1	0.29	Negative
1340	1	B134001-1	1	H16	Circulation (Hallway)	Hallway from Classrooms 110 to 111	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1340	1	B134001-1	1	H16	Circulation (Hallway)	Hallway from Classrooms 110 to 111	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1340	1	B134001-1	1	H16	Circulation (Hallway)	Hallway from Classrooms 110 to 111	yes	Baseboard	Concrete	Brown	Chipping/Flaking	5	5.3	Positive
1340	1	B134001-1	1	S14	Stairs	Stairwell by Classroom 111	yes	W1	Plaster	White	None	0	30.1	Positive
1340	1	B134001-1	1	S14	Stairs	Stairwell by Classroom 111	yes	W2	Plaster	White	None	0	31.4	Positive
1340	1	B134001-1	1	S14	Stairs	Stairwell by Classroom 111	yes	Radiator	Metal	Gray	Chipping	8	0.21	Negative
1340	1	B134001-1	1	S14	Stairs	Stairwell by Classroom 111	yes	W3	Plaster	White	Flaking	6	28.9	Positive
1340	1	B134001-1	1	S14	Stairs	Stairwell by Classroom 111	yes	Door Frame	Metal	Brown	Chipping	4	0	Negative
1340	1	B134001-1	1	S14	Stairs	Stairwell by Classroom 111	yes	Door	Metal	Brown	Chipping	8	0.08	Negative
1340	1	B134001-1	1	S14	Stairs	Stairwell by Classroom 111	yes	W4	Plaster	White	Chipping	6	30.7	Positive
1340	1	B134001-1	1	S14	Stairs	Stairwell by Classroom 111	yes	Ceiling	Plaster	White	Flaking	4	3.31	Positive
1340	1	B134001-1	1	S14	Stairs	Stairwell by Classroom 111	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1340	1	B134001-1	1	S14	Stairs	Stairwell by Classroom 111	yes	Riser	Metal	Brown	Chipping	8	2.2	Positive
1340	1	B134001-1	1	S14	Stairs	Stairwell by Classroom 111	yes	Stringer	Metal	Brown	Chipping	10	4	Positive
1340	1	B134001-1	1	S14	Stairs	Stairwell by Classroom 111	yes	Newel Post	Metal	Brown	Chipping	2	5.3	Positive
1340	1	B134001-1	1	S14	Stairs	Stairwell by Classroom 111	yes	Spindles	Metal	Brown	Chipping	15	6.7	Positive
1340	1	B134001-1	1	S14	Stairs	Stairwell by Classroom 111	yes	Hand Rail	Wood	Brown	Friction	20	0.06	Negative
1340	1	B134001-1	1	S14	Stairs	Stairwell by Classroom 111	yes	Baseboard	Concrete	Brown	Chipping	8	1.9	Positive
1340	1	B134001-1	1			Exit Vestibule for Stairwell by Classroom 105	yes	W1	Plaster	White	Cracking/Flaking	15	2.93	Positive
1340	1	B134001-1	1			Exit Vestibule for Stairwell by Classroom 105	yes	W2	Plaster	White	Cracking	5	0.12	Negative
1340	1	B134001-1	1			Exit Vestibule for Stairwell by Classroom 105	yes	W3	Plaster	White	Cracking/Flaking	15	4.7	Positive
1340	1	B134001-1	1			Exit Vestibule for Stairwell by Classroom 105	yes	W4	Plaster	White	Cracking	5	3.3	Positive
1340	1	B134001-1	1			Exit Vestibule for Stairwell by Classroom 105	yes	Ceiling	Concrete	White	None	0	N/A	N/A
1340	1	B134001-1	1			Exit Vestibule for Stairwell by Classroom 105	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1340	1	B134001-1	1			Exit Vestibule for Stairwell by Classroom 105	yes	Covebase	Concrete	Brown	Chipping	8	2.49	Positive
1340	1	B134001-1	1	PS	Pipe Shaft	First Floor Restroom Pipeshaft	no	W1	Brick	N/A	N/A	N/A	N/A	N/A
1340	1	B134001-1	1	PS	Pipe Shaft	First Floor Restroom Pipeshaft	no	W2	Brick	N/A	N/A	N/A	N/A	N/A
1340	1	B134001-1	1	PS	Pipe Shaft	First Floor Restroom Pipeshaft	no	W3	Brick	N/A	N/A	N/A	N/A	N/A
1340	1	B134001-1	1	PS	Pipe Shaft	First Floor Restroom Pipeshaft	no	W4	Brick	N/A	N/A	N/A	N/A	N/A

1340	1	B134001-1	1	PS	Pipe Shaft	First Floor Restroom Pipeshaft	no	Ceiling	Brick	N/A	N/A	N/A	N/A	N/A
1340	1	B134001-1	1	PS	Pipe Shaft	First Floor Restroom Pipeshaft	no	Floor	Brick	N/A	N/A	N/A	N/A	N/A
1340	1	B134001-1	1	S18	Stairs	Fire Tower Stairwell beside Classroom 107	yes	W1	Ceramic Brick	N/A	N/A	N/A	N/A	N/A
1340	1	B134001-1	1	S18	Stairs	Fire Tower Stairwell beside Classroom 107	yes	W2	Ceramic Brick	N/A	N/A	N/A	N/A	N/A
1340	1	B134001-1	1	S18	Stairs	Fire Tower Stairwell beside Classroom 107	yes	W3	Ceramic Brick	N/A	N/A	N/A	N/A	N/A
1340	1	B134001-1	1	S18	Stairs	Fire Tower Stairwell beside Classroom 107	yes	W4	Ceramic Brick	N/A	N/A	N/A	N/A	N/A
1340	1	B134001-1	1	S18	Stairs	Fire Tower Stairwell beside Classroom 107	yes	Ceiling	Concrete	White	None	0	3.07	Positive
1340	1	B134001-1	1	S18	Stairs	Fire Tower Stairwell beside Classroom 107	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1340	1	B134001-1	1	S19	Stairs	Fire Tower Stairwell across from Office 124	yes	W1	Ceramic Brick	N/A	N/A	N/A	N/A	N/A
1340	1	B134001-1	1	S19	Stairs	Fire Tower Stairwell across from Office 124	yes	W2	Ceramic Brick	N/A	N/A	N/A	N/A	N/A
1340	1	B134001-1	1	S19	Stairs	Fire Tower Stairwell across from Office 124	yes	W3	Ceramic Brick	N/A	N/A	N/A	N/A	N/A
1340	1	B134001-1	1	S19	Stairs	Fire Tower Stairwell across from Office 124	yes	W4	Ceramic Brick	N/A	N/A	N/A	N/A	N/A
1340	1	B134001-1	1	S19	Stairs	Fire Tower Stairwell across from Office 124	yes	Ceiling	Concrete	White	None	0	3.1	Positive
1340	1	B134001-1	1	S19	Stairs	Fire Tower Stairwell across from Office 124	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1340	1	B134001-1	2	203	Primary	Classroom 203	yes	W1	Plaster	White	Flaking/Cracking/Staple Holes	20	36.7	Positive
1340	1	B134001-1	2	203	Primary	Classroom 203	yes	Shelving	Wood	White	Chipping	6	0.03	Negative
1340	1	B134001-1	2	203	Primary	Classroom 203	yes	Door Frame	Wood	White	Chipping/Staple Holes	20	0.19	Negative
1340	1	B134001-1	2	203	Primary	Classroom 203	yes	W2	Plaster	White	Flaking/Staple Holes	35	31.3	Positive
1340	1	B134001-1	2	203	Primary	Classroom 203	yes	Chalk Board Frame/Tray	Wood	White	Chipping/Staple Holes	10	0.09	Negative
1340	1	B134001-1	2	203	Primary	Classroom 203	yes	W3	Plaster	White	Flaking/Staple Holes	40	33	Positive
1340	1	B134001-1	2	203	Primary	Classroom 203	yes	Window Frames	Wood	White	Chipping/Staple Holes	12	0.14	Negative
1340	1	B134001-1	2	203	Primary	Classroom 203	yes	Radiator Pipes	Metal	Gray	Chipping/Flaking	50	2.4	Positive
1340	1	B134001-1	2	203	Primary	Classroom 203	yes	W4	Plaster	White	Flaking/Staple Holes	25	38.1	Positive
1340	1	B134001-1	2	203	Primary	Classroom 203	yes	Chalk Board Frame/Tray	Wood	White	Chipping/Staple Holes	15	0.09	Negative
1340	1	B134001-1	2	203	Primary	Classroom 203	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1340	1	B134001-1	2	203	Primary	Classroom 203	yes	Floor	Wood	Varnish	Scrapes	12	0.01	Negative
1340	1	B134001-1	2	203	Primary	Classroom 203	yes	Baseboard	Wood	Brown	Partially Inaccessible	0	0.27	Negative
1340	1	B134001-1	2	204	Primary	Classroom 204	yes	W1	Plaster	White	Partially Inaccessible/Cracking/Flaking	6	24.1	Positive
1340	1	B134001-1	2	204	Primary	Classroom 204	yes	Pipe	Metal	Brown	Partially Inaccessible	0	0.2	Negative
1340	1	B134001-1	2	204	Primary	Classroom 204	yes	Shelves	Wood	White	Chipping	4	0.04	Negative
1340	1	B134001-1	2	204	Primary	Classroom 204	yes	Door	Wood	Gray	Chipping	8	0.19	Negative
1340	1	B134001-1	2	204	Primary	Classroom 204	yes	Door Frame	Wood	Gray	Chipping	6	0.3	Negative
1340	1	B134001-1	2	204	Primary	Classroom 204	yes	W2	Plaster	White	Flaking	6	31.8	Positive
1340	1	B134001-1	2	204	Primary	Classroom 204	yes	Chalk Board Frame/Tray	Wood	White	Chipping	10'	0.2	Negative
1340	1	B134001-1	2	204	Primary	Classroom 204	yes	W3	Plaster	White	Flaking	10	24.6	Positive
1340	1	B134001-1	2	204	Primary	Classroom 204	yes	Radiator Pipes	Metal	Gray	Flaking/Chipping	50	3	Positive
1340	1	B134001-1	2	204	Primary	Classroom 204	yes	W4	Plaster	White	Partially Inaccessible/Flaking	4	32.9	Positive
1340	1	B134001-1	2	204	Primary	Classroom 204	yes	Chalk Board Frame/Tray	Wood	White	Chipping	15	0.27	Negative
1340	1	B134001-1	2	204	Primary	Classroom 204	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1340	1	B134001-1	2	204	Primary	Classroom 204	yes	Ceiling	Plaster	White	Flaking	5	42.2	Positive
1340	1	B134001-1	2	204	Primary	Classroom 204	yes	Floor	Wood	Varnish	None	0	N/A	N/A
1340	1	B134001-1	2	204	Primary	Classroom 204	yes	Baseboard	Wood	Brown	Partially Inaccessible	0	0.21	Negative
1340	1	B134001-1	2	204A	Student Restrooms - Male (4-12)	Boy's Restroom next to Classroom 204	yes	W1	Plaster	White	Hole	1	25.4	Positive
1340	1	B134001-1	2	204A	Student Restrooms - Male (4-12)	Boy's Restroom next to Classroom 204	yes	Door Frame	Wood	White	Flaking/Chipping	6	0.16	Negative
1340	1	B134001-1	2	204A	Student Restrooms - Male (4-12)	Boy's Restroom next to Classroom 204	yes	W2	Plaster	White	Flaking	1	25.7	Positive
1340	1	B134001-1	2	204A	Student Restrooms - Male (4-12)	Boy's Restroom next to Classroom 204	yes	W3	Plaster	White	Flaking	8	38.3	Positive
1340	1	B134001-1	2	204A	Student Restrooms - Male (4-12)	Boy's Restroom next to Classroom 204	yes	Pipe	Metal	Gray/White	Cracking	4	44.7	Positive
1340	1	B134001-1	2	204A	Student Restrooms - Male (4-12)	Boy's Restroom next to Classroom 204	yes	W4	Plaster	White	Flaking	10	21.7	Positive
1340	1	B134001-1	2	204A	Student Restrooms - Male (4-12)	Boy's Restroom next to Classroom 204	yes	Ceiling	Concrete	White	Flaking	10	27.9	Positive
1340	1	B134001-1	2	204A	Student Restrooms - Male (4-12)	Boy's Restroom next to Classroom 204	yes	Floor	Concrete	Gray	Chipping	50	0.02	Negative
1340	1	B134001-1	2	204A	Student Restrooms - Male (4-12)	Boy's Restroom next to Classroom 204	yes	Covebase	Concrete	Gray	Chipping	20	4.1	Positive

1340	1	B134001-1	2	213	Teacher Lounge/Dining	Teacher's Lounge across from Classroom 204	yes	W1	Plaster	White	Partially Inaccessible	0	45.6	Positive
1340	1	B134001-1	2	213	Teacher Lounge/Dining	Teacher's Lounge across from Classroom 204	yes	Pipe	Metal	White	Chipping	1	0.07	Negative
1340	1	B134001-1	2	213	Teacher Lounge/Dining	Teacher's Lounge across from Classroom 204	yes	Door	Wood	Gray	Chipping	5	0.15	Negative
1340	1	B134001-1	2	213	Teacher Lounge/Dining	Teacher's Lounge across from Classroom 204	yes	Door Frame	Wood	Gray	Chipping	4	0.14	Negative
1340	1	B134001-1	2	213	Teacher Lounge/Dining	Teacher's Lounge across from Classroom 204	yes	W2	Sheetrock	White	Partially Inaccessible	0	0	Negative
1340	1	B134001-1	2	213	Teacher Lounge/Dining	Teacher's Lounge across from Classroom 204	yes	W3	Plaster	White	Partially Inaccessible	0	47.5	Positive
1340	1	B134001-1	2	213	Teacher Lounge/Dining	Teacher's Lounge across from Classroom 204	yes	Radiator	Metal	Gray	Chipping/Flaking	2	5.9	Positive
1340	1	B134001-1	2	213	Teacher Lounge/Dining	Teacher's Lounge across from Classroom 204	yes	W4	Plaster	White	Partially Inaccessible	0	41.9	Positive
1340	1	B134001-1	2	213	Teacher Lounge/Dining	Teacher's Lounge across from Classroom 204	yes	Radiator	Metal	Gray	Chipping/Flaking	2	5.5	Positive
1340	1	B134001-1	2	213	Teacher Lounge/Dining	Teacher's Lounge across from Classroom 204	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1340	1	B134001-1	2	213	Teacher Lounge/Dining	Teacher's Lounge across from Classroom 204	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1340	1	B134001-1	2	213A	Restrooms, Staff - Male/Female	Staff Restroom next to Teacher's Lounge	yes	W1	Sheetrock	White	None	0	0	Negative
1340	1	B134001-1	2	213A	Restrooms, Staff - Male/Female	Staff Restroom next to Teacher's Lounge	yes	W2	Sheetrock	White	Flaking	1	0	Negative
1340	1	B134001-1	2	213A	Restrooms, Staff - Male/Female	Staff Restroom next to Teacher's Lounge	yes	W3	Plaster	White	None	0	36.2	Positive
1340	1	B134001-1	2	213A	Restrooms, Staff - Male/Female	Staff Restroom next to Teacher's Lounge	yes	W4	Sheetrock	White	None	0	0	Negative
1340	1	B134001-1	2	213A	Restrooms, Staff - Male/Female	Staff Restroom next to Teacher's Lounge	yes	Ceiling	Plaster	White	None	0	22.2	Positive
1340	1	B134001-1	2	213A	Restrooms, Staff - Male/Female	Staff Restroom next to Teacher's Lounge	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1340	1	B134001-1	2	213B	Administrative Office	Office/Copy Room across from Boy's Restroom	yes	W1	Plaster	White	None	0	38.7	Positive
1340	1	B134001-1	2	213B	Administrative Office	Office/Copy Room across from Boy's Restroom	yes	Door Frame	Wood	Gray/Tan	Chipping	2	0.12	Negative
1340	1	B134001-1	2	213B	Administrative Office	Office/Copy Room across from Boy's Restroom	yes	W2	Sheetrock	White	None	0	0	Negative
1340	1	B134001-1	2	213B	Administrative Office	Office/Copy Room across from Boy's Restroom	yes	W3	Sheetrock	White	None	0	0	Negative
1340	1	B134001-1	2	213B	Administrative Office	Office/Copy Room across from Boy's Restroom	yes	W4	Sheetrock	White	None	0	0	Negative
1340	1	B134001-1	2	213B	Administrative Office	Office/Copy Room across from Boy's Restroom	yes	Ceiling	Plaster	White	Flaking	2	19.5	Positive
1340	1	B134001-1	2	213B	Administrative Office	Office/Copy Room across from Boy's Restroom	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1340	1	B134001-1	2	H27	Circulation (Hallway)	Hallway at Classrooms 203 and 204	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
1340	1	B134001-1	2	H27	Circulation (Hallway)	Hallway at Classrooms 203 and 204	yes	W2	Plaster	White	Flaking	2	16	Positive
1340	1	B134001-1	2	H27	Circulation (Hallway)	Hallway at Classrooms 203 and 204	yes	Window Frames	Wood	Gray	Chipping	2	0.27	Negative
1340	1	B134001-1	2	H27	Circulation (Hallway)	Hallway at Classrooms 203 and 204	yes	Radiators	Metal	Gray	Chipping/Flaking	6	0.03	Negative
1340	1	B134001-1	2	H27	Circulation (Hallway)	Hallway at Classrooms 203 and 204	yes	W3	Plaster	White	None	0	0.17	Negative
1340	1	B134001-1	2	H27	Circulation (Hallway)	Hallway at Classrooms 203 and 204	yes	Door	Metal	Blue	Chipping	6	0.08	Negative
1340	1	B134001-1	2	H27	Circulation (Hallway)	Hallway at Classrooms 203 and 204	yes	Door Frame	Metal	Blue	Chipping	8	0.08	Negative
1340	1	B134001-1	2	H27	Circulation (Hallway)	Hallway at Classrooms 203 and 204	yes	W4	Plaster	White	Flaking	2	31.2	Positive
1340	1	B134001-1	2	H27	Circulation (Hallway)	Hallway at Classrooms 203 and 204	yes	Vent Covers	Metal	White	Chipping	2	10.3	Positive
1340	1	B134001-1	2	H27	Circulation (Hallway)	Hallway at Classrooms 203 and 204	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1340	1	B134001-1	2	H27	Circulation (Hallway)	Hallway at Classrooms 203 and 204	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1340	1	B134001-1	2	H27	Circulation (Hallway)	Hallway at Classrooms 203 and 204	yes	Covebase	Concrete	Brown	Chipping	20	4.9	Positive
1340	1	B134001-1	2	S21	Stairs	Stairwell by Classroom 205	yes	W1	Plaster	White	None	0	25.3	Positive
1340	1	B134001-1	2	S21	Stairs	Stairwell by Classroom 205	yes	W2	Metal	White	Scrapes	5	0.4	Negative
1340	1	B134001-1	2	S21	Stairs	Stairwell by Classroom 205	yes	W3	Plaster	White	None	0	23	Positive
1340	1	B134001-1	2	S21	Stairs	Stairwell by Classroom 205	yes	W4	Plaster	White	Flaking	2	26.8	Positive
1340	1	B134001-1	2	S21	Stairs	Stairwell by Classroom 205	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1340	1	B134001-1	2	S21	Stairs	Stairwell by Classroom 205	yes	Ceiling	Plaster	White	Chipping/Flaking	20	24.8	Positive
1340	1	B134001-1	2	S21	Stairs	Stairwell by Classroom 205	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1340	1	B134001-1	2	S21	Stairs	Stairwell by Classroom 205	yes	Riser	Metal	Gray	Chipping	10	5.4	Positive
1340	1	B134001-1	2	S21	Stairs	Stairwell by Classroom 205	yes	Stringer	Metal	Gray	Chipping	12	5.7	Positive
1340	1	B134001-1	2	S21	Stairs	Stairwell by Classroom 205	yes	Newel Post	Metal	Gray	Chipping	4	3.3	Positive
1340	1	B134001-1	2	S21	Stairs	Stairwell by Classroom 205	yes	Spindles	Metal	Gray	Chipping	20	1.8	Positive
1340	1	B134001-1	2	S21	Stairs	Stairwell by Classroom 205	yes	Handrail	Wood	Gray	Chipping	15	0.03	Negative
1340	1	B134001-1	2	S21	Stairs	Stairwell by Classroom 205	yes	Covebase	Concrete	Gray	Chipping	10	3.6	Positive
1340	1	B134001-1	2	S21	Stairs	Stairwell by Classroom 205	yes	Stair Undercarriage	Concrete	White	Flaking	2	9.9	Positive

1340	1	B134001-1	2		Storage	Book Closet in Stairwell by Classroom 205	yes	W1	Plaster	Green	Partially Inaccessible/Chipping	4	18.1	Positive
1340	1	B134001-1	2		Storage	Book Closet in Stairwell by Classroom 205	yes	W2	Plaster	Green	Partially Inaccessible	0	16.5	Positive
1340	1	B134001-1	2		Storage	Book Closet in Stairwell by Classroom 205	yes	W3	Plaster	Green	Partially Inaccessible	0	18.7	Positive
1340	1	B134001-1	2		Storage	Book Closet in Stairwell by Classroom 205	yes	W4	Plaster	Green	Partially Inaccessible/Hole	1	18	Positive
1340	1	B134001-1	2		Storage	Book Closet in Stairwell by Classroom 205	yes	Ceiling	Plaster	Green	None	0	19.3	Positive
1340	1	B134001-1	2		Storage	Book Closet in Stairwell by Classroom 205	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1340	1	B134001-1	2		Storage	Book Closet in Stairwell by Classroom 205	yes	Shelving	Wood	Varnish	Chipping	10	0.05	Negative
1340	1	B134001-1	2	205	Primary	Classroom 205	yes	W1	Plaster	White	Partially Inaccessible/Cracking	4	31.9	Positive
1340	1	B134001-1	2	205	Primary	Classroom 205	yes	Door	Wood	Gray	Chipping	10	0.13	Negative
1340	1	B134001-1	2	205	Primary	Classroom 205	yes	Door Frame	Wood	Gray	Chipping	6	0.18	Negative
1340	1	B134001-1	2	205	Primary	Classroom 205	yes	Coat Cubby Frame	Wood	White	Chipping	12	0.11	Negative
1340	1	B134001-1	2	205	Primary	Classroom 205	yes	Pipe	Metal	Brown	Partially Inaccessible	0	0.4	Negative
1340	1	B134001-1	2	205	Primary	Classroom 205	yes	W2	Plaster	Purple	Partially Inaccessible	0	0	Negative
1340	1	B134001-1	2	205	Primary	Classroom 205	yes	W3	Plaster	White	Partially Inaccessible	0	37.5	Positive
1340	1	B134001-1	2	205	Primary	Classroom 205	yes	W3	Sheetrock	White	Flaking	2	0	Negative
1340	1	B134001-1	2	205	Primary	Classroom 205	yes	Window Frames	Wood	White	Chipping	4	0.23	Negative
1340	1	B134001-1	2	205	Primary	Classroom 205	yes	W4	Plaster	White	Flaking	3	43.6	Positive
1340	1	B134001-1	2	205	Primary	Classroom 205	yes	W4	Wood	White	Partially Inaccessible	0	0.1	Negative
1340	1	B134001-1	2	205	Primary	Classroom 205	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1340	1	B134001-1	2	205	Primary	Classroom 205	yes	Floor	Wood	Varnish	Scrapes	20	0.02	Negative
1340	1	B134001-1	2	205	Primary	Classroom 205	yes	Door Frame on Floor	Metal	Brown	Chipping	3	1.2	Positive
1340	1	B134001-1	2	205	Primary	Classroom 205	yes	Baseboard	Wood	Brown	Partially Inaccessible	0	0.3	Negative
1340	1	B134001-1	2	206	Primary	Classroom 206	yes	W1	Plaster	White	Partially Inaccessible/Cracking	6	33.8	Positive
1340	1	B134001-1	2	206	Primary	Classroom 206	yes	Door	Wood	Gray	Chipping	10	0.07	Negative
1340	1	B134001-1	2	206	Primary	Classroom 206	yes	Door Frame	Wood	Gray	Chipping	8	0.11	Negative
1340	1	B134001-1	2	206	Primary	Classroom 206	yes	Coat Cubby Frame	Wood	White	Chipping	10	0.12	Negative
1340	1	B134001-1	2	206	Primary	Classroom 206	yes	Pipe	Metal	Brown	Partially Inaccessible/Chipping	5	0.2	Negative
1340	1	B134001-1	2	206	Primary	Classroom 206	yes	Shelving	Wood	White	Chipping	6	0.04	Negative
1340	1	B134001-1	2	206	Primary	Classroom 206	yes	Coat Rack	Wood	White	Chipping	4	0.14	Negative
1340	1	B134001-1	2	206	Primary	Classroom 206	yes	W2	Sheetrock	White	Partially Inaccessible	0	0	Negative
1340	1	B134001-1	2	206	Primary	Classroom 206	yes	W2	Plaster	White	Chipping	6	43.8	Positive
1340	1	B134001-1	2	206	Primary	Classroom 206	yes	Wall Frame	Wood	White	Chipping	2	0.1	Negative
1340	1	B134001-1	2	206	Primary	Classroom 206	yes	W3	Plaster	White	Partially Inaccessible	0	37.4	Positive
1340	1	B134001-1	2	206	Primary	Classroom 206	yes	Window Frames	Wood	White	Chipping	8	0.21	Negative
1340	1	B134001-1	2	206	Primary	Classroom 206	yes	Radiator Pipes	Metal	Gray	Partially Inaccessible	0	2	Positive
1340	1	B134001-1	2	206	Primary	Classroom 206	yes	W4	Plaster	White	Chipping	15	33.9	Positive
1340	1	B134001-1	2	206	Primary	Classroom 206	yes	W4	Wood	White	Partially Inaccessible	0	0.26	Negative
1340	1	B134001-1	2	206	Primary	Classroom 206	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1340	1	B134001-1	2	206	Primary	Classroom 206	yes	Ceiling	Plaster	White	Cracking	6	42.5	Positive
1340	1	B134001-1	2	206	Primary	Classroom 206	yes	Floor	Wood	Varnish	None	0	N/A	N/A
1340	1	B134001-1	2	206	Primary	Classroom 206	yes	Baseboard	Wood	Brown	Partially Inaccessible	0	0.17	Negative
1340	1	B134001-1	2	206	Primary	Classroom 206	yes	Door Frame on Floor	Metal	Brown	Chipping	1	0.22	Negative
1340	1	B134001-1	2	213C	Service Closets	Custodial Closet in the Hallway across from Classroom 206	no	W1	Plaster	White	Flaking	2	0.35	Negative
1340	1	B134001-1	2	213C	Service Closets	Custodial Closet in the Hallway across from Classroom 206	no	W2	Sheetrock	White	Chipping	2	0.01	Negative
1340	1	B134001-1	2	213C	Service Closets	Custodial Closet in the Hallway across from Classroom 206	no	W3	Sheetrock	White	Chipping	2	0.01	Negative
1340	1	B134001-1	2	213C	Service Closets	Custodial Closet in the Hallway across from Classroom 206	no	W4	Sheetrock	White	None	0	0.01	Negative
1340	1	B134001-1	2	213C	Service Closets	Custodial Closet in the Hallway across from Classroom 206	no	Ceiling	Plaster	White	Flaking/Hole	2	2.53	Positive
1340	1	B134001-1	2	213C	Service Closets	Custodial Closet in the Hallway across from Classroom 206	no	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1340	1	B134001-1	2	207	Primary	Classroom 207	yes	W1	Plaster	White	Partially Inaccessible/Cracking	4	26.5	Positive
1340	1	B134001-1	2	207	Primary	Classroom 207	yes	Door	Wood	Gray	Chipping	5	0.04	Negative
1340	1	B134001-1	2	207	Primary	Classroom 207	yes	Door Frame	Wood	Gray	Chipping	5	0.11	Negative

1340	1	B134001-1	2	207	Primary	Classroom 207	yes	Coat Cubby Frame	Wood	White	Chipping	8	0.08	Negative
1340	1	B134001-1	2	207	Primary	Classroom 207	yes	Pipe	Metal	Brown	Chipping	3	0.5	Negative
1340	1	B134001-1	2	207	Primary	Classroom 207	yes	Shelving	Wood	White	Chipping	6	0.02	Negative
1340	1	B134001-1	2	207	Primary	Classroom 207	yes	Coat Rack	Wood	White	Chipping	4	0.21	Negative
1340	1	B134001-1	2	207	Primary	Classroom 207	yes	W2	Sheetrock	White	Partially Inaccessible	0	0	Negative
1340	1	B134001-1	2	207	Primary	Classroom 207	yes	W2	Plaster	White	Chipping	2	40.3	Positive
1340	1	B134001-1	2	207	Primary	Classroom 207	yes	W3	Plaster	White	Chipping/Flaking	20	33.3	Positive
1340	1	B134001-1	2	207	Primary	Classroom 207	yes	Radiator	Metal	Gray	Chipping	4	10	Positive
1340	1	B134001-1	2	207	Primary	Classroom 207	yes	Window Frame	Wood	White	Chipping	12	0.23	Negative
1340	1	B134001-1	2	207	Primary	Classroom 207	yes	W4	Wood	White	Partially Inaccessible/Chipping	12	0.24	Negative
1340	1	B134001-1	2	207	Primary	Classroom 207	yes	W4	Plaster	White	Chipping/Flaking	4	38.4	Positive
1340	1	B134001-1	2	207	Primary	Classroom 207	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1340	1	B134001-1	2	207	Primary	Classroom 207	yes	Ceiling	Plaster	White	Flaking	10	35	Positive
1340	1	B134001-1	2	207	Primary	Classroom 207	yes	Floor	Wood	Varnish	Scrapes	25	0.05	Negative
1340	1	B134001-1	2	207	Primary	Classroom 207	yes	Baseboard	Wood	Brown	Partially Inaccessible	0	0.23	Negative
1340	1	B134001-1	2	208	Primary	Classroom 209	yes	W1	Plaster	White	Chipping/Flaking	10	29	Positive
1340	1	B134001-1	2	208	Primary	Classroom 209	yes	Door	Wood	Gray	Chipping	5	0.14	Negative
1340	1	B134001-1	2	208	Primary	Classroom 209	yes	Door Frame	Wood	Gray	Chipping	6	0.18	Negative
1340	1	B134001-1	2	208	Primary	Classroom 209	yes	Coat Cubby Frame	Wood	White	Chipping	8	0.19	Negative
1340	1	B134001-1	2	208	Primary	Classroom 209	yes	Pipe	Metal	Brown	Chipping	10	0.3	Negative
1340	1	B134001-1	2	208	Primary	Classroom 209	yes	Shelving	Wood	White/Green	Chipping	8	0.07	Negative
1340	1	B134001-1	2	208	Primary	Classroom 209	yes	Coat Rack	Wood	White	Chipping	3	0.21	Negative
1340	1	B134001-1	2	208	Primary	Classroom 209	yes	W2	Plaster	White	Chipping/Flaking	2	31.6	Positive
1340	1	B134001-1	2	208	Primary	Classroom 209	yes	Chalk Board Frame/Tray	Wood	White	Chipping	12	0.18	Negative
1340	1	B134001-1	2	208	Primary	Classroom 209	yes	W3	Plaster	White	Partially Inaccessible/Flaking/C racking	12	36.3	Positive
1340	1	B134001-1	2	208	Primary	Classroom 209	yes	Window Frames	Wood	White	Chipping	4	0.11	Negative
1340	1	B134001-1	2	208	Primary	Classroom 209	yes	Radiator Pipes	Metal	Gray	Chipping/Flaking	50	0.7	Positive
1340	1	B134001-1	2	208	Primary	Classroom 209	yes	W4	Plaster	White	Chipping/Flaking	6	29.4	Positive
1340	1	B134001-1	2	208	Primary	Classroom 209	yes	Chalk Board Frame/Tray	Wood	White	Chipping	12	0.12	Negative
1340	1	B134001-1	2	208	Primary	Classroom 209	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1340	1	B134001-1	2	208	Primary	Classroom 209	yes	Ceiling	Plaster	White	Flaking	10	36.8	Positive
1340	1	B134001-1	2	208	Primary	Classroom 209	yes	Floor	Wood	Varnish	Scrapes	25	0.01	Negative
1340	1	B134001-1	2	208	Primary	Classroom 209	yes	Baseboard	Wood	Brown	Partially Inaccessible	0	0.22	Negative
1340	1	B134001-1	2	209	Primary	Classroom 208	yes	W1	Plaster	White	Partially Inaccessible/Cracking/ Flaking/Staples	30	22.6	Positive
1340	1	B134001-1	2	209	Primary	Classroom 208	yes	Coat Cubby Frame	Wood	White	Chipping	10	0.28	Negative
1340	1	B134001-1	2	209	Primary	Classroom 208	yes	Pipe	Metal	Brown	Partially Inaccessible	0	0.6	Negative
1340	1	B134001-1	2	209	Primary	Classroom 208	yes	Coat Rack	Wood	White	Chipping	10	0.09	Negative
1340	1	B134001-1	2	209	Primary	Classroom 208	yes	Shelves	Wood	White	Chipping	4	0.07	Negative
1340	1	B134001-1	2	209	Primary	Classroom 208	yes	W2	Sheetrock	White	Partially Inaccessible/Flaking	5	0	Negative
1340	1	B134001-1	2	209	Primary	Classroom 208	yes	W2	Plaster	White	Flaking	2	36.6	Positive
1340	1	B134001-1	2	209	Primary	Classroom 208	yes	W3	Plaster	White	Partially Inaccessible/Flaking	6	40.3	Positive
1340	1	B134001-1	2	209	Primary	Classroom 208	yes	Window Frames	Wood	White	Chipping	2	0.24	Negative
1340	1	B134001-1	2	209	Primary	Classroom 208	yes	Radiator Pipes	Metal	Gray	Flaking/Chipping	40	6.4	Positive
1340	1	B134001-1	2	209	Primary	Classroom 208	yes	W4	Sheetrock	White	Chipping	8	0	Negative
1340	1	B134001-1	2	209	Primary	Classroom 208	yes	W4	Plaster	White	Flaking	3	38.3	Positive
1340	1	B134001-1	2	209	Primary	Classroom 208	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1340	1	B134001-1	2	209	Primary	Classroom 208	yes	Ceiling	Plaster	White	Flaking	2	37.3	Positive
1340	1	B134001-1	2	209	Primary	Classroom 208	yes	Floor	Wood	Varnish	None	0	N/A	N/A
1340	1	B134001-1	2	209	Primary	Classroom 208	yes	Baseboard	Wood	Brown	Partially Inaccessible	0	0.14	Negative
1340	1	B134001-1	2	210	Primary	Classroom 210	yes	W1	Plaster	White	Partially Inaccessible/Flaking	10	20.8	Positive
1340	1	B134001-1	2	210	Primary	Classroom 210	yes	Coat Cubby Frame	Wood	White	Chipping	10	0.06	Negative
1340	1	B134001-1	2	210	Primary	Classroom 210	yes	Coat Rack	Wood	White	Chipping	8	0.07	Negative
1340	1	B134001-1	2	210	Primary	Classroom 210	yes	Pipe	Metal	Brown	Chipping	6	0.11	Negative

1340	1	B134001-1	2	210	Primary	Classroom 210	yes	W2	Plaster	White	Flaking/Chipping	10	43.1	Positive
1340	1	B134001-1	2	210	Primary	Classroom 210	yes	W2	Wood	White	Partially Inaccessible	0	0.24	Negative
1340	1	B134001-1	2	210	Primary	Classroom 210	yes	W3	Plaster	White	Flaking	8	30.3	Positive
1340	1	B134001-1	2	210	Primary	Classroom 210	yes	Window Frames	Wood	White	Chipping	12	0.22	Negative
1340	1	B134001-1	2	210	Primary	Classroom 210	yes	Radiator Pipes	Metal	Gray	Partially Inaccessible	0	1.8	Positive
1340	1	B134001-1	2	210	Primary	Classroom 210	yes	W4	Plaster	White	Partially Inaccessible/Cracking	10	32.2	Positive
1340	1	B134001-1	2	210	Primary	Classroom 210	yes	Chalk Board Frame/Tray	Wood	White	Partially Inaccessible	0	0.17	Negative
1340	1	B134001-1	2	210	Primary	Classroom 210	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1340	1	B134001-1	2	210	Primary	Classroom 210	yes	Floor	Wood	Varnish	None	0	N/A	N/A
1340	1	B134001-1	2	210	Primary	Classroom 210	yes	Baseboard	Wood	Brown	Partially Inaccessible	0	0.3	Negative
1340	1	B134001-1	2	S213	Stairs	Stairwell by Classroom 210	yes	W1	Plaster	White	Scrapes	8	23.1	Positive
1340	1	B134001-1	2	S213	Stairs	Stairwell by Classroom 210	yes	W2	Plaster	White	Flaking	4	25.4	Positive
1340	1	B134001-1	2	S213	Stairs	Stairwell by Classroom 210	yes	W3	Plaster	White	Flaking	5	27	Positive
1340	1	B134001-1	2	S213	Stairs	Stairwell by Classroom 210	yes	W4	Metal	White	Scrapes	2	0.5	Negative
1340	1	B134001-1	2	S213	Stairs	Stairwell by Classroom 210	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1340	1	B134001-1	2	S213	Stairs	Stairwell by Classroom 210	yes	Ceiling	Plaster	White	None	0	35.6	Positive
1340	1	B134001-1	2	S213	Stairs	Stairwell by Classroom 210	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1340	1	B134001-1	2	S213	Stairs	Stairwell by Classroom 210	yes	Covebase	Concrete	Gray	Chipping	5	5.6	Positive
1340	1	B134001-1	2	S213	Stairs	Stairwell by Classroom 210	yes	Riser	Metal	Gray	Chipping	6	6.3	Positive
1340	1	B134001-1	2	S213	Stairs	Stairwell by Classroom 210	yes	Stringer	Metal	Gray	Chipping	10	0.7	Positive
1340	1	B134001-1	2	S213	Stairs	Stairwell by Classroom 210	yes	Newel Post	Metal	Gray	Chipping	4	2.2	Positive
1340	1	B134001-1	2	S213	Stairs	Stairwell by Classroom 210	yes	Spindle	Metal	Gray	Chipping	20	2.9	Positive
1340	1	B134001-1	2	S213	Stairs	Stairwell by Classroom 210	yes	Hand Rail	Wood	Gray	Chipping	20	0.01	Negative
1340	1	B134001-1	2	S213	Stairs	Stairwell by Classroom 210	yes	Stair Undercarriage	Concrete	White	Flaking	4	11.2	Positive
1340	1	B134001-1	2	H28	Circulation (Hallway)	Hallway from Classrooms 205 to 210	yes	W1	Plaster	White	Chipping/Cracking	10	27	Positive
1340	1	B134001-1	2	H28	Circulation (Hallway)	Hallway from Classrooms 205 to 210	yes	Pipe	Metal	White	Chipping	2	12.3	Positive
1340	1	B134001-1	2	H28	Circulation (Hallway)	Hallway from Classrooms 205 to 210	yes	W2	Metal	White	None	0	0.5	Negative
1340	1	B134001-1	2	H28	Circulation (Hallway)	Hallway from Classrooms 205 to 210	yes	Door	Metal	Blue	Chipping	2	0	Negative
1340	1	B134001-1	2	H28	Circulation (Hallway)	Hallway from Classrooms 205 to 210	yes	Door Frame	Metal	Blue	Chipping	4	0.06	Negative
1340	1	B134001-1	2	H28	Circulation (Hallway)	Hallway from Classrooms 205 to 210	yes	W3	Plaster	White	Chipping/Flaking	8	25.1	Positive
1340	1	B134001-1	2	H28	Circulation (Hallway)	Hallway from Classrooms 205 to 210	yes	Radiators	Metal	Gray	Chipping/Flaking	4	0.4	Negative
1340	1	B134001-1	2	H28	Circulation (Hallway)	Hallway from Classrooms 205 to 210	yes	W4	Metal	White	Chipping	2	0.5	Negative
1340	1	B134001-1	2	H28	Circulation (Hallway)	Hallway from Classrooms 205 to 210	yes	Door	Metal	Blue	Chipping	2	0	Negative
1340	1	B134001-1	2	H28	Circulation (Hallway)	Hallway from Classrooms 205 to 210	yes	Door Frame	Metal	Blue	Chipping	4	0.28	Negative
1340	1	B134001-1	2	H28	Circulation (Hallway)	Hallway from Classrooms 205 to 210	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1340	1	B134001-1	2	H28	Circulation (Hallway)	Hallway from Classrooms 205 to 210	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1340	1	B134001-1	2	H28	Circulation (Hallway)	Hallway from Classrooms 205 to 210	yes	Covebase	Concrete	Brown	Chipping	10	2.7	Positive
1340	1	B134001-1	2	H28PS	Circulation (Hallway)	Pipe Shaft in Hallway from Classrooms 205 to 210	no	W1	Brick	N/A	N/A	N/A	N/A	N/A
1340	1	B134001-1	2	H28PS	Circulation (Hallway)	Pipe Shaft in Hallway from Classrooms 205 to 210	no	W2	Brick	N/A	N/A	N/A	N/A	N/A
1340	1	B134001-1	2	H28PS	Circulation (Hallway)	Pipe Shaft in Hallway from Classrooms 205 to 210	no	W3	Brick	N/A	N/A	N/A	N/A	N/A
1340	1	B134001-1	2	H28PS	Circulation (Hallway)	Pipe Shaft in Hallway from Classrooms 205 to 210	no	W4	Brick	N/A	N/A	N/A	N/A	N/A
1340	1	B134001-1	2	H28PS	Circulation (Hallway)	Pipe Shaft in Hallway from Classrooms 205 to 210	no	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1340	1	B134001-1	2	H28PS	Circulation (Hallway)	Pipe Shaft in Hallway from Classrooms 205 to 210	no	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1340	1	B134001-1	2	211A	Student Restrooms - Female (4-12)	Girl's Restroom next to Classroom 211	yes	W1	Plaster	White	None	0	29.3	Positive
1340	1	B134001-1	2	211A	Student Restrooms - Female (4-12)	Girl's Restroom next to Classroom 211	yes	Door Frame	Wood	Peach	Chipping	3	0	Negative
1340	1	B134001-1	2	211A	Student Restrooms - Female (4-12)	Girl's Restroom next to Classroom 211	yes	W2	CMU	White	None	0	0	Negative
1340	1	B134001-1	2	211A	Student Restrooms - Female (4-12)	Girl's Restroom next to Classroom 211	yes	W2	Plaster	White	Flaking	1	1.3	Positive
1340	1	B134001-1	2	211A	Student Restrooms - Female (4-12)	Girl's Restroom next to Classroom 211	yes	W3	Plaster	White	None	0	24.1	Positive
1340	1	B134001-1	2	211A	Student Restrooms - Female (4-12)	Girl's Restroom next to Classroom 211	yes	W4	Plaster	White	Flaking	1	24.6	Positive
1340	1	B134001-1	2	211A	Student Restrooms - Female (4-12)	Girl's Restroom next to Classroom 211	yes	Ceiling	Plaster	White	Flaking	8	38.3	Positive
1340	1	B134001-1	2	211A	Student Restrooms - Female (4-12)	Girl's Restroom next to Classroom 211	yes	Floor	Concrete	Brown	Chipping	50	0.01	Negative
1340	1	B134001-1	2	211A	Student Restrooms - Female (4-12)	Girl's Restroom next to Classroom 211	yes	Covebase	Concrete	Brown	Chipping	10	2.5	Positive
1340	1	B134001-1	2	211	Primary	Classroom 211	yes	W1	Plaster	White	Partially Inaccessible/Chipping/Cracking	10	26.1	Positive

1340	1	B134001-1	2	211	Primary	Classroom 211	yes	Door	Wood	Gray	Chipping	10	0.08	Negative
1340	1	B134001-1	2	211	Primary	Classroom 211	yes	Door Frame	Wood	Gray	Chipping	8	0.15	Negative
1340	1	B134001-1	2	211	Primary	Classroom 211	yes	Coat Cubby Frame	Wood	White	Chipping	12	0.13	Negative
1340	1	B134001-1	2	211	Primary	Classroom 211	yes	Coat Rack	Wood	White	Chipping	5	0.06	Negative
1340	1	B134001-1	2	211	Primary	Classroom 211	yes	Pipe	Metal	Brown	Chipping	3	0.6	Negative
1340	1	B134001-1	2	211	Primary	Classroom 211	yes	Shelving	Wood	White/Green	Chipping	4	0.03	Negative
1340	1	B134001-1	2	211	Primary	Classroom 211	yes	W2	Plaster	White	Partially Inaccessible/Chipping	4	27.9	Positive
1340	1	B134001-1	2	211	Primary	Classroom 211	yes	Chalk Board Frame/Tray	Wood	White	Chipping	10	0.22	Negative
1340	1	B134001-1	2	211	Primary	Classroom 211	yes	W3	Plaster	White	Partially Inaccessible/Chipping	1	37.1	Positive
1340	1	B134001-1	2	211	Primary	Classroom 211	yes	Window Frames	Wood	White	Chipping	4	0.19	Negative
1340	1	B134001-1	2	211	Primary	Classroom 211	yes	Radiator Pipes	Metal	Gray	Partially Inaccessible	0	3.6	Positive
1340	1	B134001-1	2	211	Primary	Classroom 211	yes	W4	Plaster	White	Partially Inaccessible/Chipping	4	35.8	Positive
1340	1	B134001-1	2	211	Primary	Classroom 211	yes	Chalk Board Frame/Tray	Wood	White	Partially Inaccessible	0	0.04	Negative
1340	1	B134001-1	2	211	Primary	Classroom 211	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1340	1	B134001-1	2	211	Primary	Classroom 211	yes	Ceiling	Plaster	White	Flaking	10	43.6	Positive
1340	1	B134001-1	2	211	Primary	Classroom 211	yes	Floor	Wood	Varnish	Scrapes	25	0.05	Negative
1340	1	B134001-1	2	211	Primary	Classroom 211	yes	Baseboard	Wood	Brown	Partially Inaccessible	0	0.12	Negative
1340	1	B134001-1	2	212	Primary	Classroom 212	yes	W1	Plaster	White	Partially Inaccessible/Flaking	2	23.2	Positive
1340	1	B134001-1	2	212	Primary	Classroom 212	yes	Door	Wood	Gray	Chipping	5	0.27	Negative
1340	1	B134001-1	2	212	Primary	Classroom 212	yes	Door Frame	Wood	Gray	Chipping	6	0.24	Negative
1340	1	B134001-1	2	212	Primary	Classroom 212	yes	Coat Cubby Frame	Wood	White	Chipping	4	0.18	Negative
1340	1	B134001-1	2	212	Primary	Classroom 212	yes	Coat Rack	Wood	White	Chipping	4	0.06	Negative
1340	1	B134001-1	2	212	Primary	Classroom 212	yes	Shelving	Wood	White/Green	Chipping	4	0.13	Negative
1340	1	B134001-1	2	212	Primary	Classroom 212	yes	W2	Plaster	White	Partially Inaccessible/Flaking	1	33.6	Positive
1340	1	B134001-1	2	212	Primary	Classroom 212	yes	Chalk Board Frame/Tray	Wood	White	Chipping	10	0.11	Negative
1340	1	B134001-1	2	212	Primary	Classroom 212	yes	W3	Plaster	White	Partially Inaccessible/Cracking/Flaking	8	35.9	Positive
1340	1	B134001-1	2	212	Primary	Classroom 212	yes	Window Frames	Wood	White	Chipping	4	0.09	Negative
1340	1	B134001-1	2	212	Primary	Classroom 212	yes	Radiator Pipes	Metal	Gray	Partially Inaccessible	0	1.3	Positive
1340	1	B134001-1	2	212	Primary	Classroom 212	yes	W4	Plaster	White	Partially Inaccessible	0	28.7	Positive
1340	1	B134001-1	2	212	Primary	Classroom 212	yes	Chalk Board Frame/Tray	Wood	White	Chipping	10	0.12	Negative
1340	1	B134001-1	2	212	Primary	Classroom 212	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1340	1	B134001-1	2	212	Primary	Classroom 212	yes	Floor	Wood	Varnish	Scrapes	25	0.05	Negative
1340	1	B134001-1	2	212	Primary	Classroom 212	yes	Covebase	Wood	Brown	Partially Inaccessible	0	0.03	Negative
1340	1	B134001-1	2	212A	Storage	Storage 212A at the end of the Hallway at Classroom 212	yes	W1	Plaster	Tan	Flaking	12	21.4	Positive
1340	1	B134001-1	2	212A	Storage	Storage 212A at the end of the Hallway at Classroom 212	yes	Door	Wood	Tan	Chipping	2	0.17	Negative
1340	1	B134001-1	2	212A	Storage	Storage 212A at the end of the Hallway at Classroom 212	yes	Door Frame	Wood	Tan	Chipping	6	0.18	Negative
1340	1	B134001-1	2	212A	Storage	Storage 212A at the end of the Hallway at Classroom 212	yes	W2	Plaster	Tan	Partially Inaccessible/Flaking	40	21.8	Positive
1340	1	B134001-1	2	212A	Storage	Storage 212A at the end of the Hallway at Classroom 212	yes	W3	Plaster	Tan	Partially Inaccessible	0	23.3	Positive
1340	1	B134001-1	2	212A	Storage	Storage 212A at the end of the Hallway at Classroom 212	yes	W4	Plaster	Tan	Partially Inaccessible/Flaking	10	18.1	Positive
1340	1	B134001-1	2	212A	Storage	Storage 212A at the end of the Hallway at Classroom 212	yes	Window Frame	Wood	White	Chipping	6	0.16	Negative
1340	1	B134001-1	2	212A	Storage	Storage 212A at the end of the Hallway at Classroom 212	yes	Radiator	Metal	Gray	Chipping/Flaking	8	0.22	Negative
1340	1	B134001-1	2	212A	Storage	Storage 212A at the end of the Hallway at Classroom 212	yes	Ceiling	Plaster	Tan	Flaking	25	15.4	Positive
1340	1	B134001-1	2	212A	Storage	Storage 212A at the end of the Hallway at Classroom 212	yes	Floor	Concrete	Gray	Partially Inaccessible/Chipping	10	0.8	Positive
1340	1	B134001-1	2	212A	Storage	Storage 212A at the end of the Hallway at Classroom 212	yes	Shelving	Wood	Tan	Partially Inaccessible	0	0.04	Negative

1340	1	B134001-1	2	212A	Storage	Storage 212A at the end of the Hallway at Classroom 212	yes	Covebase	Concrete	Gray	Partially Inaccessible	0	0.5	Negative
1340	1	B134001-1	2	H29	Circulation (Hallway)	Hallway at Classrooms 211 and 212	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
1340	1	B134001-1	2	H29	Circulation (Hallway)	Hallway at Classrooms 211 and 212	yes	W2	Plaster	White	Flaking/Chipping	15	32.1	Positive
1340	1	B134001-1	2	H29	Circulation (Hallway)	Hallway at Classrooms 211 and 212	yes	Pipe	Metal	White	Chipping	1	11.5	Positive
1340	1	B134001-1	2	H29	Circulation (Hallway)	Hallway at Classrooms 211 and 212	yes	Vent Covers	Metal	White	Chipping	2	17.7	Positive
1340	1	B134001-1	2	H29	Circulation (Hallway)	Hallway at Classrooms 211 and 212	yes	W3	Plaster	White	None	0	1.8	Positive
1340	1	B134001-1	2	H29	Circulation (Hallway)	Hallway at Classrooms 211 and 212	yes	W4	Plaster	White	Flaking/Chipping	10	27.4	Positive
1340	1	B134001-1	2	H29	Circulation (Hallway)	Hallway at Classrooms 211 and 212	yes	Radiator	Metal	Gray	Chipping/Flaking	4	4	Positive
1340	1	B134001-1	2	H29	Circulation (Hallway)	Hallway at Classrooms 211 and 212	yes	Window Frame	Wood	Tan	Chipping	5	0.27	Negative
1340	1	B134001-1	2	H29	Circulation (Hallway)	Hallway at Classrooms 211 and 212	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1340	1	B134001-1	2	H29	Circulation (Hallway)	Hallway at Classrooms 211 and 212	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1340	1	B134001-1	2	H29	Circulation (Hallway)	Hallway at Classrooms 211 and 212	yes	Covebase	Concrete	Brown	Chipping	6	1.8	Positive
1340	1	B134001-1	2	PS	Pipe Shaft	Second Floor Restroom Pipeshaft	no	W1	Brick	N/A	N/A	N/A	N/A	N/A
1340	1	B134001-1	2	PS	Pipe Shaft	Second Floor Restroom Pipeshaft	no	W2	Brick	N/A	N/A	N/A	N/A	N/A
1340	1	B134001-1	2	PS	Pipe Shaft	Second Floor Restroom Pipeshaft	no	W3	Brick	N/A	N/A	N/A	N/A	N/A
1340	1	B134001-1	2	PS	Pipe Shaft	Second Floor Restroom Pipeshaft	no	W4	Brick	N/A	N/A	N/A	N/A	N/A
1340	1	B134001-1	2	PS	Pipe Shaft	Second Floor Restroom Pipeshaft	no	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1340	1	B134001-1	2	PS	Pipe Shaft	Second Floor Restroom Pipeshaft	no	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1340	1	B134001-1	2		Stairs	Fire Tower Stairwell beside Classroom 209	yes	W1	Ceramic Brick	N/A	N/A	N/A	N/A	N/A
1340	1	B134001-1	2		Stairs	Fire Tower Stairwell beside Classroom 209	yes	W2	Ceramic Brick	N/A	N/A	N/A	N/A	N/A
1340	1	B134001-1	2		Stairs	Fire Tower Stairwell beside Classroom 209	yes	W3	Ceramic Brick	N/A	N/A	N/A	N/A	N/A
1340	1	B134001-1	2		Stairs	Fire Tower Stairwell beside Classroom 209	yes	W4	Ceramic Brick	N/A	N/A	N/A	N/A	N/A
1340	1	B134001-1	2		Stairs	Fire Tower Stairwell beside Classroom 209	yes	Ceiling	Concrete	White	None	0	23	Positive
1340	1	B134001-1	2		Stairs	Fire Tower Stairwell beside Classroom 209	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1340	1	B134001-1	2		Stairs	Fire Tower Stairwell across from Office 206	yes	W1	Ceramic Brick	N/A	N/A	N/A	N/A	N/A
1340	1	B134001-1	2		Stairs	Fire Tower Stairwell across from Office 206	yes	W2	Ceramic Brick	N/A	N/A	N/A	N/A	N/A
1340	1	B134001-1	2		Stairs	Fire Tower Stairwell across from Office 206	yes	W3	Ceramic Brick	N/A	N/A	N/A	N/A	N/A
1340	1	B134001-1	2		Stairs	Fire Tower Stairwell across from Office 206	yes	Window Grate	Metal	Brown	Flaking	25	28	Positive
1340	1	B134001-1	2		Stairs	Fire Tower Stairwell across from Office 206	yes	W4	Ceramic Brick	N/A	N/A	N/A	N/A	N/A
1340	1	B134001-1	2		Stairs	Fire Tower Stairwell across from Office 206	yes	Window Grate	Metal	Brown	Flaking	50	28	Positive
1340	1	B134001-1	2		Stairs	Fire Tower Stairwell across from Office 206	yes	Ceiling	Concrete	White	None	0	22.6	Positive
1340	1	B134001-1	2		Stairs	Fire Tower Stairwell across from Office 206	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1340	1	B134001-2	3	300B	Storage	Storage Room at the end of the Hallway by Classroom 303	yes	W1	Plaster	Green	Partially Inaccessible	0	35.2	Positive
1340	1	B134001-2	3	300B	Storage	Storage Room at the end of the Hallway by Classroom 303	yes	W2	Plaster	White	Efflorescence/Flaking	100	38	Positive
1340	1	B134001-2	3	300B	Storage	Storage Room at the end of the Hallway by Classroom 303	yes	Radiator	Metal	Gray	Chipping	4	4.6	Positive
1340	1	B134001-2	3	300B	Storage	Storage Room at the end of the Hallway by Classroom 303	yes	W3	Plaster	Green	Flaking/Cracking	15	0.15	Negative
1340	1	B134001-2	3	300B	Storage	Storage Room at the end of the Hallway by Classroom 303	yes	W4	Plaster	Green	Partially Inaccessible/Cracking	20	33.9	Positive
1340	1	B134001-2	3	300B	Storage	Storage Room at the end of the Hallway by Classroom 303	yes	Ceiling	Plaster	White	Flaking	150	44.1	Positive
1340	1	B134001-2	3	300B	Storage	Storage Room at the end of the Hallway by Classroom 303	yes	Floor	Concrete	Gray	Partially Inaccessible	0	0.07	Negative
1340	1	B134001-2	3	300B	Storage	Storage Room at the end of the Hallway by Classroom 303	yes	Covebase	Concrete	Gray	Partially Inaccessible	0	0.5	Negative
1340	1	B134001-2	3	300B	Storage	Storage Room at the end of the Hallway by Classroom 303	yes	Shelving	Wood	Gray	Chipping	12	0.21	Negative
1340	1	B134001-1	3	303	Primary	Classroom 303	yes	W1	Plaster	White	Partially Inaccessible/Cracking	10	26.3	Positive
1340	1	B134001-1	3	303	Primary	Classroom 303	yes	Pipe	Metal	White	Chipping	2	0.06	Negative
1340	1	B134001-1	3	303	Primary	Classroom 303	yes	Door	Wood	White	Chipping	4	0.06	Negative
1340	1	B134001-1	3	303	Primary	Classroom 303	yes	Door Frame	Wood	White	Chipping	4	0.08	Negative
1340	1	B134001-1	3	303	Primary	Classroom 303	yes	Coat Cubby Frame	Wood	White	Chipping	4	0.09	Negative
1340	1	B134001-1	3	303	Primary	Classroom 303	yes	W2	Plaster	White	Chipping/Flaking	15	0	Negative
1340	1	B134001-1	3	303	Primary	Classroom 303	yes	W3	Plaster	White	Chipping/Flaking	15	22.7	Positive
1340	1	B134001-1	3	303	Primary	Classroom 303	yes	Window Frames	Wood	White	Chipping	3	0.07	Negative
1340	1	B134001-1	3	303	Primary	Classroom 303	yes	W4	Sheetrock	White	Chipping	12	0	Negative
1340	1	B134001-1	3	303	Primary	Classroom 303	yes	W4	Plaster	White	Chipping/Flaking	4	33.7	Positive
1340	1	B134001-1	3	303	Primary	Classroom 303	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1340	1	B134001-1	3	303	Primary	Classroom 303	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1340	1	B134001-1	3	304	Primary	Classroom 304	yes	W1	Plaster	White	None	0	22.1	Positive
1340	1	B134001-1	3	304	Primary	Classroom 304	yes	W2	Plaster	White	None	0	21.5	Positive

1340	1	B134001-1	3	304	Primary	Classroom 304	yes	W2	Sheetrock	White	Chipping	4	0	Negative
1340	1	B134001-1	3	304	Primary	Classroom 304	yes	W3	Plaster	White	Cracking	4	38.9	Positive
1340	1	B134001-1	3	304	Primary	Classroom 304	yes	W4	Plaster	Blue/White	None	0	36.2	Positive
1340	1	B134001-1	3	304	Primary	Classroom 304	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1340	1	B134001-1	3	304	Primary	Classroom 304	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1340	1	B134001-1	3	304A	Student Restrooms - Male (4-12)	Boy's Restroom next to Classroom 304	yes	W1	Plaster	White	None	0	28.9	Positive
1340	1	B134001-1	3	304A	Student Restrooms - Male (4-12)	Boy's Restroom next to Classroom 304	yes	W2	Plaster	White	Flaking	4	22.8	Positive
1340	1	B134001-1	3	304A	Student Restrooms - Male (4-12)	Boy's Restroom next to Classroom 304	yes	W2	CMU	White	None	0	0.01	Negative
1340	1	B134001-1	3	304A	Student Restrooms - Male (4-12)	Boy's Restroom next to Classroom 304	yes	W3	Plaster	White	Flaking	2	36.3	Positive
1340	1	B134001-1	3	304A	Student Restrooms - Male (4-12)	Boy's Restroom next to Classroom 304	yes	Pipe	Metal	White	Flaking	10	48	Positive
1340	1	B134001-1	3	304A	Student Restrooms - Male (4-12)	Boy's Restroom next to Classroom 304	yes	W4	Plaster	White	Flaking	3	27.6	Positive
1340	1	B134001-1	3	304A	Student Restrooms - Male (4-12)	Boy's Restroom next to Classroom 304	yes	Ceiling	Plaster	White	Flaking	10	32.3	Positive
1340	1	B134001-1	3	304A	Student Restrooms - Male (4-12)	Boy's Restroom next to Classroom 304	yes	Floor	Concrete	Brown	Chipping	50	0.22	Negative
1340	1	B134001-1	3	304A	Student Restrooms - Male (4-12)	Boy's Restroom next to Classroom 304	yes	Covebase	Concrete	Brown	Chipping	2	3.3	Positive
1340	1	B134001-1	3	H310	Circulation (Hallway)	Hallway at Classrooms 303 and 304	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
1340	1	B134001-1	3	H310	Circulation (Hallway)	Hallway at Classrooms 303 and 304	yes	W2	Plaster	White	Flaking/Staple Holes	6	30.9	Positive
1340	1	B134001-1	3	H310	Circulation (Hallway)	Hallway at Classrooms 303 and 304	yes	W3	Plaster	White	Partially Inaccessible	0	27.4	Positive
1340	1	B134001-1	3	H310	Circulation (Hallway)	Hallway at Classrooms 303 and 304	yes	W4	Plaster	White	Chipping/Flaking	6	26.7	Positive
1340	1	B134001-1	3	H310	Circulation (Hallway)	Hallway at Classrooms 303 and 304	yes	Vent Covers	Metal	Blue	Chipping	1	8.7	Positive
1340	1	B134001-1	3	H310	Circulation (Hallway)	Hallway at Classrooms 303 and 304	yes	Door	Wood	Blue	Chipping	4	0.15	Negative
1340	1	B134001-1	3	H310	Circulation (Hallway)	Hallway at Classrooms 303 and 304	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1340	1	B134001-1	3	H310	Circulation (Hallway)	Hallway at Classrooms 303 and 304	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1340	1	B134001-1	3	H310	Circulation (Hallway)	Hallway at Classrooms 303 and 304	yes	Covebase	Concrete	Brown	Chipping	40	2.6	Positive
1340	1	B134001-1	3	305	Teacher Lounge/Dining	Staff Lounge 305	yes	W1	Plaster	White	Staple Holes/Chipping/Flaking	30	35.2	Positive
1340	1	B134001-1	3	305	Teacher Lounge/Dining	Staff Lounge 305	yes	Chalk Board Frame/Tray	Wood	White	Chipping	8	0.04	Negative
1340	1	B134001-1	3	305	Teacher Lounge/Dining	Staff Lounge 305	yes	Pipe	Metal	White	Chipping	1	0.09	Negative
1340	1	B134001-1	3	305	Teacher Lounge/Dining	Staff Lounge 305	yes	W2	Sheetrock	White	Chipping	10	0	Negative
1340	1	B134001-1	3	305	Teacher Lounge/Dining	Staff Lounge 305	yes	W3	Plaster	White	Flaking/Staple Holes	50	26.4	Positive
1340	1	B134001-1	3	305	Teacher Lounge/Dining	Staff Lounge 305	yes	Radiator	Metal	Gray	Chipping/Flaking	10	3.8	Positive
1340	1	B134001-1	3	305	Teacher Lounge/Dining	Staff Lounge 305	yes	W4	Plaster	White	Flaking	30	37.9	Positive
1340	1	B134001-1	3	305	Teacher Lounge/Dining	Staff Lounge 305	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1340	1	B134001-1	3	305	Teacher Lounge/Dining	Staff Lounge 305	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1340	1	B134001-1	3	305	Teacher Lounge/Dining	Staff Lounge 305	yes	Baseboard	Wood	Brown	Partially Inaccessible	0	0.26	Negative
1340	1	B134001-1	3	305A	Restrooms, Staff - Male/Female	Restroom inside Copy Room	yes	W1	Sheetrock	White	None	0	0	Negative
1340	1	B134001-1	3	305A	Restrooms, Staff - Male/Female	Restroom inside Copy Room	yes	W2	Sheetrock	White	None	0	0	Negative
1340	1	B134001-1	3	305A	Restrooms, Staff - Male/Female	Restroom inside Copy Room	yes	W3	Plaster	White	None	0	39.7	Positive
1340	1	B134001-1	3	305A	Restrooms, Staff - Male/Female	Restroom inside Copy Room	yes	W4	Sheetrock	White	None	0	0	Negative
1340	1	B134001-1	3	305A	Restrooms, Staff - Male/Female	Restroom inside Copy Room	yes	Ceiling	Plaster	White	Flaking	6	42.9	Positive
1340	1	B134001-1	3	305A	Restrooms, Staff - Male/Female	Restroom inside Copy Room	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1340	1	B134001-1	3	305B	Copying Room	Copy Room across from Classroom 304	yes	W1	Plaster	White	None	0	31.3	Positive
1340	1	B134001-1	3	305B	Copying Room	Copy Room across from Classroom 304	yes	Door	Wood	Tan	Chipping	4	0.2	Negative
1340	1	B134001-1	3	305B	Copying Room	Copy Room across from Classroom 304	yes	Door Frame	Wood	Blue/Tan	Chipping	2	0.15	Negative
1340	1	B134001-1	3	305B	Copying Room	Copy Room across from Classroom 304	yes	W2	Sheetrock	White	Hole	1	0	Negative
1340	1	B134001-1	3	305B	Copying Room	Copy Room across from Classroom 304	yes	W3	Sheetrock	White	None	0	0	Negative

1340	1	B134001-1	3	305B	Copying Room	Copy Room across from Classroom 304	yes	W4	Sheetrock	White	Chipping	2	0	Negative
1340	1	B134001-1	3	305B	Copying Room	Copy Room across from Classroom 304	yes	Ceiling	Plaster	White	Flaking	2	41.4	Positive
1340	1	B134001-1	3	305B	Copying Room	Copy Room across from Classroom 304	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1340	1	B134001-1	3	S31	Stairs	Stairwell by Classroom 306	yes	W1	Plaster	White	None	0	26	Positive
1340	1	B134001-1	3	S31	Stairs	Stairwell by Classroom 306	yes	W2	Metal	White	None	0	0.4	Negative
1340	1	B134001-1	3	S31	Stairs	Stairwell by Classroom 306	yes	W3	Plaster	White	None	0	5.9	Positive
1340	1	B134001-1	3	S31	Stairs	Stairwell by Classroom 306	yes	W4	Plaster	White	Chipping	6	21.8	Positive
1340	1	B134001-1	3	S31	Stairs	Stairwell by Classroom 306	yes	Ceiling	Plaster	White	None	0	24.4	Positive
1340	1	B134001-1	3	S31	Stairs	Stairwell by Classroom 306	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1340	1	B134001-1	3	S31	Stairs	Stairwell by Classroom 306	yes	Covebase	Concrete	Gray	Chipping	6	2.9	Positive
1340	1	B134001-1	3	S31	Stairs	Stairwell by Classroom 306	yes	Riser	Metal	Gray	Chipping	6	3.6	Positive
1340	1	B134001-1	3	S31	Stairs	Stairwell by Classroom 306	yes	Stringer	Metal	Gray	Chipping	6	3.2	Positive
1340	1	B134001-1	3	S31	Stairs	Stairwell by Classroom 306	yes	Newel Post	Metal	Gray	Chipping	2	1.3	Positive
1340	1	B134001-1	3	S31	Stairs	Stairwell by Classroom 306	yes	Spindle	Metal	Gray	Chipping	10	2.4	Positive
1340	1	B134001-1	3	S31	Stairs	Stairwell by Classroom 306	yes	Hand Rail	Wood	Gray	Chipping	15	0	Negative
1340	1	B134001-1	3		Stairs	Stairs to Mezzanine Level Office	yes	W1	Metal	White	None	0	0	Negative
1340	1	B134001-1	3		Stairs	Stairs to Mezzanine Level Office	yes	W2	Plaster	White	None	0	19.7	Positive
1340	1	B134001-1	3		Stairs	Stairs to Mezzanine Level Office	yes	W3	Plaster	White	Chipping	2	34	Positive
1340	1	B134001-1	3		Stairs	Stairs to Mezzanine Level Office	yes	W4	Plaster	White	Chipping/Flaking	2	25.8	Positive
1340	1	B134001-1	3		Stairs	Stairs to Mezzanine Level Office	yes	Door	Wood	White	Chipping	2	0.09	Negative
1340	1	B134001-1	3		Stairs	Stairs to Mezzanine Level Office	yes	Ceiling	Plaster	White	None	0	25.9	Positive
1340	1	B134001-1	3		Stairs	Stairs to Mezzanine Level Office	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1340	1	B134001-1	3		Stairs	Stairs to Mezzanine Level Office	yes	Riser	Metal	Brown	Chipping	6	3.8	Positive
1340	1	B134001-1	3		Stairs	Stairs to Mezzanine Level Office	yes	Stringer	Metal	Brown	Chipping	6	5.1	Positive
1340	1	B134001-1	3		Stairs	Stairs to Mezzanine Level Office	yes	Newel Post	Metal	Brown	Chipping	2	4.8	Positive
1340	1	B134001-1	3		Stairs	Stairs to Mezzanine Level Office	yes	Spindle	Metal	Brown	Chipping	15	5.4	Positive
1340	1	B134001-1	3		Stairs	Stairs to Mezzanine Level Office	yes	Hand Rail	Wood	Brown	Chipping	10	0.05	Negative
1340	1	B134001-1	3	305.5	Administrative Office	Office on the Mezzanine Level above the Stairwell at Classroom 306	yes	W1	Plaster	White	Flaking	6	4.12	Positive
1340	1	B134001-1	3	305.5	Administrative Office	Office on the Mezzanine Level above the Stairwell at Classroom 306	yes	W2	Plaster	White	None	0	8.59	Positive
1340	1	B134001-1	3	305.5	Administrative Office	Office on the Mezzanine Level above the Stairwell at Classroom 306	yes	W3	Plaster	White	None	0	8.02	Positive
1340	1	B134001-1	3	305.5	Administrative Office	Office on the Mezzanine Level above the Stairwell at Classroom 306	yes	Radiator	Metal	Gray	Flaking	4	3.13	Positive
1340	1	B134001-1	3	305.5	Administrative Office	Office on the Mezzanine Level above the Stairwell at Classroom 306	yes	W4	Plaster	White	Cracking/Hole	20	4.13	Positive
1340	1	B134001-1	3	305.5	Administrative Office	Office on the Mezzanine Level above the Stairwell at Classroom 306	yes	Ceiling	Plaster	White	Efflorescence/Flaking	30	3.19	Positive
1340	1	B134001-1	3	305.5	Administrative Office	Office on the Mezzanine Level above the Stairwell at Classroom 306	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1340	1	B134001-1	3	305.5R	Restrooms, Staff - Male/Female	Restroom in Office on the Mezzanine Level above the Stairwell at Classroom 306	yes	W1	Sheetrock	White	None	0	0.07	Negative
1340	1	B134001-1	3	305.5R	Restrooms, Staff - Male/Female	Restroom in Office on the Mezzanine Level above the Stairwell at Classroom 306	yes	W2	Sheetrock	White	None	0	0.06	Negative
1340	1	B134001-1	3	305.5R	Restrooms, Staff - Male/Female	Restroom in Office on the Mezzanine Level above the Stairwell at Classroom 306	yes	W3	Plaster	White	Cracking/Flaking	10	3.69	Positive
1340	1	B134001-1	3	305.5R	Restrooms, Staff - Male/Female	Restroom in Office on the Mezzanine Level above the Stairwell at Classroom 306	yes	W4	Plaster	White	None	0	3.33	Positive
1340	1	B134001-1	3	305.5R	Restrooms, Staff - Male/Female	Restroom in Office on the Mezzanine Level above the Stairwell at Classroom 306	yes	Ceiling	Plaster	White	Efflorescence/Flaking	3	3.06	Positive
1340	1	B134001-1	3	305.5R	Restrooms, Staff - Male/Female	Restroom in Office on the Mezzanine Level above the Stairwell at Classroom 306	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1340	1	B134001-1	3	306	Primary	Classroom 306	yes	W1	Plaster	White	Flaking/Cracking	6	35.8	Positive
1340	1	B134001-1	3	306	Primary	Classroom 306	yes	Door	Wood	Tan	Chipping	12	0.06	Negative
1340	1	B134001-1	3	306	Primary	Classroom 306	yes	Coat Cubby Frame	Wood	White	Chipping	6	0.3	Negative
1340	1	B134001-1	3	306	Primary	Classroom 306	yes	Pipe	Metal	Brown	Partially Inaccessible	0	0.6	Negative
1340	1	B134001-1	3	306	Primary	Classroom 306	yes	W2	Plaster	White	Flaking	6	22.8	Positive
1340	1	B134001-1	3	306	Primary	Classroom 306	yes	W2	Sheetrock	White	Chipping	4	0	Negative
1340	1	B134001-1	3	306	Primary	Classroom 306	yes	W3	Plaster	White	Alligating	8	31.5	Positive
1340	1	B134001-1	3	306	Primary	Classroom 306	yes	W3	Sheetrock	White	Chipping	3	0	Negative
1340	1	B134001-1	3	306	Primary	Classroom 306	yes	Window Frames	Wood	White	Chipping	10	0.06	Negative
1340	1	B134001-1	3	306	Primary	Classroom 306	yes	W4	Wood	White	Chipping	10	0.18	Negative
1340	1	B134001-1	3	306	Primary	Classroom 306	yes	W4	Plaster	White	Flaking	75	19.5	Positive
1340	1	B134001-1	3	306	Primary	Classroom 306	yes	Wall Frame	Wood	White	Chipping	5	0.1	Negative
1340	1	B134001-1	3	306	Primary	Classroom 306	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A

1340	1	B134001-1	3	306	Primary	Classroom 306	yes	Ceiling	Plaster	Green	Flaking	25	50.3	Positive
1340	1	B134001-1	3	306	Primary	Classroom 306	yes	Floor	Wood	Varnish	Scrapes	25	0	Negative
1340	1	B134001-1	3	306	Primary	Classroom 306	yes	Baseboard	Wood	Brown	Chipping	20	0.21	Negative
1340	1	B134001-1	3	307	Primary	Classroom 307	yes	W1	Plaster	White	None	0	26.5	Positive
1340	1	B134001-1	3	307	Primary	Classroom 307	yes	Door	Wood	Blue	Chipping	8	0.05	Negative
1340	1	B134001-1	3	307	Primary	Classroom 307	yes	Door Frame	Wood	Blue	Chipping	6	0.1	Negative
1340	1	B134001-1	3	307	Primary	Classroom 307	yes	Coat Cubby Frame	Wood	White	Chipping	10	0.06	Negative
1340	1	B134001-1	3	307	Primary	Classroom 307	yes	Pipe	Metal	Brown	Chipping	3	0.09	Negative
1340	1	B134001-1	3	307	Primary	Classroom 307	yes	W2	Plaster	White	Flaking	20	0.7	Positive
1340	1	B134001-1	3	307	Primary	Classroom 307	yes	W2	Sheetrock	White	None	0	0	Negative
1340	1	B134001-1	3	307	Primary	Classroom 307	yes	W3	Plaster	White	Flaking	20	26.3	Positive
1340	1	B134001-1	3	307	Primary	Classroom 307	yes	Radiator Pipe	Metal	Gray	Chipping/Flaking	40	8.8	Positive
1340	1	B134001-1	3	307	Primary	Classroom 307	yes	W4	Wood	White	Chipping	8	0.21	Negative
1340	1	B134001-1	3	307	Primary	Classroom 307	yes	W4	Plaster	White	Flaking	20	36.8	Positive
1340	1	B134001-1	3	307	Primary	Classroom 307	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1340	1	B134001-1	3	307	Primary	Classroom 307	yes	Ceiling	Plaster	Green	Flaking	25	47.3	Positive
1340	1	B134001-1	3	307	Primary	Classroom 307	yes	Floor	Wood	Varnish	None	0	N/A	N/A
1340	1	B134001-1	3	307A	Service Closets	Custodial Storage in the Hallway across from Classroom 307	no	W1	Plaster	White	None	0	19.41	Positive
1340	1	B134001-1	3	307A	Service Closets	Custodial Storage in the Hallway across from Classroom 307	no	W2	Sheetrock	White	Chipping/Flaking	3	0.07	Negative
1340	1	B134001-1	3	307A	Service Closets	Custodial Storage in the Hallway across from Classroom 307	no	W3	Sheetrock	White	Chipping	4	0.22	Negative
1340	1	B134001-1	3	307A	Service Closets	Custodial Storage in the Hallway across from Classroom 307	no	W4	Plaster	White	None	0	4.51	Positive
1340	1	B134001-1	3	307A	Service Closets	Custodial Storage in the Hallway across from Classroom 307	no	Ceiling	Plaster	White	Holes	2	4.1	Positive
1340	1	B134001-1	3	307A	Service Closets	Custodial Storage in the Hallway across from Classroom 307	no	Floor	Wood	Varnish	None	0	N/A	N/A
1340	1	B134001-1	3	308	Primary	Classroom 308	yes	W1	Plaster	White	None	0	26.9	Positive
1340	1	B134001-1	3	308	Primary	Classroom 308	yes	Door Frame	Wood	White	Chipping	10	0.05	Negative
1340	1	B134001-1	3	308	Primary	Classroom 308	yes	Coat Cubby Frame	Wood	White	Chipping	12	0.18	Negative
1340	1	B134001-1	3	308	Primary	Classroom 308	yes	Pipe	Metal	Brown	Partially Inaccessible	0	0.18	Negative
1340	1	B134001-1	3	308	Primary	Classroom 308	yes	W2	Plaster	White	Chipping/Flaking	25	37.9	Positive
1340	1	B134001-1	3	308	Primary	Classroom 308	yes	W2	Sheetrock	White	None	0	0	Negative
1340	1	B134001-1	3	308	Primary	Classroom 308	yes	W3	Plaster	White	Flaking	20	30.7	Positive
1340	1	B134001-1	3	308	Primary	Classroom 308	yes	Window Frames	Wood	White	Chipping	10	0.05	Negative
1340	1	B134001-1	3	308	Primary	Classroom 308	yes	Radiator	Metal	Gray	Chipping/Flaking	6	5.6	Positive
1340	1	B134001-1	3	308	Primary	Classroom 308	yes	W4	Plaster	White	Chipping/Flaking	20	34.9	Positive
1340	1	B134001-1	3	308	Primary	Classroom 308	yes	W4	Wood	Blue	None	0	0.25	Negative
1340	1	B134001-1	3	308	Primary	Classroom 308	yes	Wall Frame	Wood	White	Chipping	8	0.15	Negative
1340	1	B134001-1	3	308	Primary	Classroom 308	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1340	1	B134001-1	3	308	Primary	Classroom 308	yes	Ceiling	Plaster	White	Flaking	25	42.8	Positive
1340	1	B134001-1	3	308	Primary	Classroom 308	yes	Floor	Wood	Varnish	Scraping	25	0.02	Negative
1340	1	B134001-1	3	308	Primary	Classroom 308	yes	Baseboard	Wood	Brown	Chipping	20	0.23	Negative
1340	1	B134001-1	3	309	Primary	Classroom 309	yes	W1	Plaster	White	Partially Inaccessible/Flaking	6	28.3	Positive
1340	1	B134001-1	3	309	Primary	Classroom 309	yes	Closet Door/Frame	Wood	White	Chipping	6	0.13	Negative
1340	1	B134001-1	3	309	Primary	Classroom 309	yes	Pipe	Metal	Brown	Partially Inaccessible	0	2.2	Positive
1340	1	B134001-1	3	309	Primary	Classroom 309	yes	W2	Plaster	Green	Partially Inaccessible	0	0.01	Negative
1340	1	B134001-1	3	309	Primary	Classroom 309	yes	W3	Plaster	White	Partially Inaccessible/Flaking	1	30.8	Positive
1340	1	B134001-1	3	309	Primary	Classroom 309	yes	W4	Plaster	White	Partially Inaccessible/Flaking/C racking	15	34.6	Positive
1340	1	B134001-1	3	309	Primary	Classroom 309	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1340	1	B134001-1	3	309	Primary	Classroom 309	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1340	1	B134001-1	3	310	Primary	Classroom 310	yes	W1	Plaster	Green	Partially Inaccessible/Flaking/C hipping	4	36.1	Positive
1340	1	B134001-1	3	310	Primary	Classroom 310	yes	Door Frame	Wood	White	Chipping	5	0	Negative
1340	1	B134001-1	3	310	Primary	Classroom 310	yes	Coat Cubby Frame	Wood	White	Chipping	15	0.18	Negative
1340	1	B134001-1	3	310	Primary	Classroom 310	yes	Pipe	Metal	Gray	Partially Inaccessible	0	0.27	Negative
1340	1	B134001-1	3	310	Primary	Classroom 310	yes	W2	Sheetrock	White	Chipping	15	0	Negative

1340	1	B134001-1	3	310	Primary	Classroom 310	yes	W2	Plaster	Green	Flaking	6	36.3	Positive
1340	1	B134001-1	3	310	Primary	Classroom 310	yes	W3	Plaster	Green	Flaking	2	29.8	Positive
1340	1	B134001-1	3	310	Primary	Classroom 310	yes	Window Frames	Wood	White	Chipping	8	0.11	Negative
1340	1	B134001-1	3	310	Primary	Classroom 310	yes	Radiator Pipes	Metal	Gray	Chipping/Flaking	40	12.5	Positive
1340	1	B134001-1	3	310	Primary	Classroom 310	yes	W4	Wood	White	Chipping	25	0.16	Negative
1340	1	B134001-1	3	310	Primary	Classroom 310	yes	W4	Plaster	Green	Flaking	8	31.7	Positive
1340	1	B134001-1	3	310	Primary	Classroom 310	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1340	1	B134001-1	3	310	Primary	Classroom 310	yes	Ceiling	Plaster	Tan	Flaking	20	47.8	Positive
1340	1	B134001-1	3	310	Primary	Classroom 310	yes	Floor	Wood	Varnish	None	0	N/A	N/A
1340	1	B134001-1	3	310	Primary	Classroom 310	yes	Baseboard	Wood	Brown/White	Chipping	20	0.06	Negative
1340	1	B134001-1	3	311	Primary	Classroom 311	yes	W1	Plaster	Green	Flaking	25	29.8	Positive
1340	1	B134001-1	3	311	Primary	Classroom 311	yes	Door	Wood	Tan	Chipping	12	0.09	Negative
1340	1	B134001-1	3	311	Primary	Classroom 311	yes	Door Frame	Wood	White/Tan/Gray	Chipping	6	0	Negative
1340	1	B134001-1	3	311	Primary	Classroom 311	yes	Coat Cubby Frame	Wood	White	Chipping	30	0.24	Negative
1340	1	B134001-1	3	311	Primary	Classroom 311	yes	Pipe	Metal	Gray	Partially Inaccessible	0	0.17	Negative
1340	1	B134001-1	3	311	Primary	Classroom 311	yes	W2	Sheetrock	White	Flaking	1	0	Negative
1340	1	B134001-1	3	311	Primary	Classroom 311	yes	W2	Plaster	Green	Flaking	30	35.4	Positive
1340	1	B134001-1	3	311	Primary	Classroom 311	yes	W3	Plaster	Green	Flaking	3	34.9	Positive
1340	1	B134001-1	3	311	Primary	Classroom 311	yes	Window Frame	Wood	White	Chipping	15	0.23	Negative
1340	1	B134001-1	3	311	Primary	Classroom 311	yes	Radiator Pipes	Metal	Gray	Chipping	50	1.9	Positive
1340	1	B134001-1	3	311	Primary	Classroom 311	yes	W4	Plaster	White	Flaking	75	31	Positive
1340	1	B134001-1	3	311	Primary	Classroom 311	yes	Chalk Board Frame/Tray	Wood	White	Chipping	10	0.29	Negative
1340	1	B134001-1	3	311	Primary	Classroom 311	yes	Closet Door	Wood	White	Chipping	12	0.13	Negative
1340	1	B134001-1	3	311	Primary	Classroom 311	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1340	1	B134001-1	3	311	Primary	Classroom 311	yes	Ceiling	Plaster	Tan	Flaking	25	54.2	Positive
1340	1	B134001-1	3	311	Primary	Classroom 311	yes	Floor	Wood	Varnish	Scraping	25	0.03	Negative
1340	1	B134001-1	3	311	Primary	Classroom 311	yes	Baseboard	Wood	Brown	Chipping	15	0.07	Negative
1340	1	B134001-1	3	H311	Circulation (Hallway)	Hallway from Classrooms 306 to 311	yes	W1	Plaster	White	Chipping/Flaking	4	32.8	Positive
1340	1	B134001-1	3	H311	Circulation (Hallway)	Hallway from Classrooms 306 to 311	yes	Door	Wood	Gray	Chipping	12	0.13	Negative
1340	1	B134001-1	3	H311	Circulation (Hallway)	Hallway from Classrooms 306 to 311	yes	Door Frame	Wood	Gray	Chipping	12	0.09	Negative
1340	1	B134001-1	3	H311	Circulation (Hallway)	Hallway from Classrooms 306 to 311	yes	W2	Metal	White	Chipping	6	0.5	Negative
1340	1	B134001-1	3	H311	Circulation (Hallway)	Hallway from Classrooms 306 to 311	yes	Door	Metal	Blue	Chipping	2	0	Negative
1340	1	B134001-1	3	H311	Circulation (Hallway)	Hallway from Classrooms 306 to 311	yes	Door Frame	Metal	Blue	Chipping	4	0.07	Negative
1340	1	B134001-1	3	H311	Circulation (Hallway)	Hallway from Classrooms 306 to 311	yes	W3	Plaster	White	Chipping/Flaking	2	29.7	Positive
1340	1	B134001-1	3	H311	Circulation (Hallway)	Hallway from Classrooms 306 to 311	yes	Radiator	Metal	Gray	Chipping/Flaking	8	0.23	Negative
1340	1	B134001-1	3	H311	Circulation (Hallway)	Hallway from Classrooms 306 to 311	yes	W4	Metal	White	None	0	0.4	Negative
1340	1	B134001-1	3	H311	Circulation (Hallway)	Hallway from Classrooms 306 to 311	yes	Door	Metal	Blue	Chipping	2	0	Negative
1340	1	B134001-1	3	H311	Circulation (Hallway)	Hallway from Classrooms 306 to 311	yes	Door Frame	Metal	Blue	Chipping	4	0.2	Negative
1340	1	B134001-1	3	H311	Circulation (Hallway)	Hallway from Classrooms 306 to 311	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1340	1	B134001-1	3	H311	Circulation (Hallway)	Hallway from Classrooms 306 to 311	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1340	1	B134001-1	3	H311	Circulation (Hallway)	Hallway from Classrooms 306 to 311	yes	Covebase	Concrete	Brown	Chipping	50	2.9	Positive
1340	1	B134001-1	3	S33	Stairs	Stairwell by Classroom 311	yes	W1	Plaster	White	None	0	30.6	Positive
1340	1	B134001-1	3	S33	Stairs	Stairwell by Classroom 311	yes	W2	Plaster	White	Efflorescence	4	20.9	Positive
1340	1	B134001-1	3	S33	Stairs	Stairwell by Classroom 311	yes	W3	Plaster	White	Flaking	2	27.9	Positive
1340	1	B134001-1	3	S33	Stairs	Stairwell by Classroom 311	yes	W4	Metal	White	None	0	0.4	Negative
1340	1	B134001-1	3	S33	Stairs	Stairwell by Classroom 311	yes	W4	Plaster	White	Chipping	2	22.9	Positive
1340	1	B134001-1	3	S33	Stairs	Stairwell by Classroom 311	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1340	1	B134001-1	3	S33	Stairs	Stairwell by Classroom 311	yes	Ceiling	Plaster	White	None	0	12.2	Positive
1340	1	B134001-1	3	S33	Stairs	Stairwell by Classroom 311	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1340	1	B134001-1	3	S33	Stairs	Stairwell by Classroom 311	yes	Riser	Metal	Gray	Chipping	6	2.4	Positive
1340	1	B134001-1	3	S33	Stairs	Stairwell by Classroom 311	yes	Stringer	Metal	Gray	Chipping	6	3.1	Positive
1340	1	B134001-1	3	S33	Stairs	Stairwell by Classroom 311	yes	Newel Post	Metal	Gray	Chipping	2	4.9	Positive
1340	1	B134001-1	3	S33	Stairs	Stairwell by Classroom 311	yes	Spindle	Metal	Blue	Chipping	6	2.3	Positive
1340	1	B134001-1	3	S33	Stairs	Stairwell by Classroom 311	yes	Hand Rail	Wood	Gray	Chipping	20	0.05	Negative
1340	1	B134001-1	3	S33	Stairs	Stairwell by Classroom 311	yes	Baseboard	Concrete	Gray	Chipping	10	2.4	Positive
1340	1	B134001-1	3	312A	Student Restrooms - Female (4-12)	Girl's Restroom next to Classroom 312	yes	W1	Plaster	White	Flaking	4	23.8	Positive
1340	1	B134001-1	3	312A	Student Restrooms - Female (4-12)	Girl's Restroom next to Classroom 312	yes	Door Frame	Wood	Blue/Tan/White	Chipping	4	0.16	Negative
1340	1	B134001-1	3	312A	Student Restrooms - Female (4-12)	Girl's Restroom next to Classroom 312	yes	W2	CMU	White	None	0	0	Negative
1340	1	B134001-1	3	312A	Student Restrooms - Female (4-12)	Girl's Restroom next to Classroom 312	yes	W2	Plaster	White	None	0	20.7	Positive

1340	1	B134001-1	3	312A	Student Restrooms - Female (4-12)	Girl's Restroom next to Classroom 312	yes	W3	Plaster	White	None	0	23.5	Positive
1340	1	B134001-1	3	312A	Student Restrooms - Female (4-12)	Girl's Restroom next to Classroom 312	yes	Pipe	Metal	White	Cracking	6	30.8	Positive
1340	1	B134001-1	3	312A	Student Restrooms - Female (4-12)	Girl's Restroom next to Classroom 312	yes	W4	Plaster	White	Flaking	1	18.3	Positive
1340	1	B134001-1	3	312A	Student Restrooms - Female (4-12)	Girl's Restroom next to Classroom 312	yes	Ceiling	Plaster	White	Flaking	20	22.8	Positive
1340	1	B134001-1	3	312A	Student Restrooms - Female (4-12)	Girl's Restroom next to Classroom 312	yes	Floor	Concrete	Brown	Chipping	50	0.1	Negative
1340	1	B134001-1	3	312A	Student Restrooms - Female (4-12)	Girl's Restroom next to Classroom 312	yes	Covebase	Concrete	Brown	Chipping	6	3.1	Positive
1340	1	B134001-1	3	312	Primary	Classroom 312	yes	W1	Plaster	White	None	0	31.1	Positive
1340	1	B134001-1	3	312	Primary	Classroom 312	yes	Door Frame	Metal	Tan	Chipping	4	0.03	Negative
1340	1	B134001-1	3	312	Primary	Classroom 312	yes	Coat Cubby Frame	Wood	White	Chipping	4	0.28	Negative
1340	1	B134001-1	3	312	Primary	Classroom 312	yes	Pipe	Metal	Brown	Chipping	2	1.4	Positive
1340	1	B134001-1	3	312	Primary	Classroom 312	yes	W2	Plaster	White	Staples/Chipping	100	0	Negative
1340	1	B134001-1	3	312	Primary	Classroom 312	yes	W3	Plaster	White	Flaking	10	39.2	Positive
1340	1	B134001-1	3	312	Primary	Classroom 312	yes	Window Frames	Wood	White	Chipping	6	0.21	Negative
1340	1	B134001-1	3	312	Primary	Classroom 312	yes	W4	Plaster	White	Flaking	20	34.6	Positive
1340	1	B134001-1	3	312	Primary	Classroom 312	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1340	1	B134001-1	3	312	Primary	Classroom 312	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1340	1	B134001-1	3	312	Primary	Classroom 312	yes	Baseboard	Wood	Brown	Chipping	10	0.05	Negative
1340	1	B134001-1	3	313	Primary	Classroom 313	yes	W1	Plaster	White	Flaking	12	30.1	Positive
1340	1	B134001-1	3	313	Primary	Classroom 313	yes	Closet Door	Wood	White	Chipping	1	0.16	Negative
1340	1	B134001-1	3	313	Primary	Classroom 313	yes	Door Frame	Metal	Tan	Chipping	6	0	Negative
1340	1	B134001-1	3	313	Primary	Classroom 313	yes	Coat Cubby Frame	Wood	White	Chipping	4	0.07	Negative
1340	1	B134001-1	3	313	Primary	Classroom 313	yes	W2	Plaster	White	Chipping/Flaking	10	0	Negative
1340	1	B134001-1	3	313	Primary	Classroom 313	yes	W3	Plaster	White	Partially Inaccessible/Flaking	2	35.7	Positive
1340	1	B134001-1	3	313	Primary	Classroom 313	yes	Window Frames	Wood	White	Chipping	10	0.07	Negative
1340	1	B134001-1	3	313	Primary	Classroom 313	yes	W4	Plaster	White	Partially Inaccessible/Flaking	6	0	Negative
1340	1	B134001-1	3	313	Primary	Classroom 313	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1340	1	B134001-1	3	313	Primary	Classroom 313	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1340	1	B134001-1	3	313A	Storage	Storage 313A at the end of the Hallway at Classroom 313	yes	W1	Plaster	Tan	Flaking	30	28.4	Positive
1340	1	B134001-1	3	313A	Storage	Storage 313A at the end of the Hallway at Classroom 313	yes	Door	Wood	Blue	Chipping	6	0.13	Negative
1340	1	B134001-1	3	313A	Storage	Storage 313A at the end of the Hallway at Classroom 313	yes	W2	Plaster	Tan	Flaking	125	23	Positive
1340	1	B134001-1	3	313A	Storage	Storage 313A at the end of the Hallway at Classroom 313	yes	W3	Plaster	Tan	Flaking	100	20.7	Positive
1340	1	B134001-1	3	313A	Storage	Storage 313A at the end of the Hallway at Classroom 313	yes	W4	Plaster	Tan	Flaking	100	26	Positive
1340	1	B134001-1	3	313A	Storage	Storage 313A at the end of the Hallway at Classroom 313	yes	Window Frame	Wood	White	Chipping	4	0.4	Negative
1340	1	B134001-1	3	313A	Storage	Storage 313A at the end of the Hallway at Classroom 313	yes	Ceiling	Plaster	Tan	Flaking	150	26.9	Positive
1340	1	B134001-1	3	313A	Storage	Storage 313A at the end of the Hallway at Classroom 313	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1340	1	B134001-1	3	313A	Storage	Storage 313A at the end of the Hallway at Classroom 313	yes	Covebase	Concrete	Gray	Partially Inaccessible	0	0.7	Positive
1340	1	B134001-1	3	313A	Storage	Storage 313A at the end of the Hallway at Classroom 313	yes	Shelving	Wood	Tan	Chipping	50	0.02	Negative
1340	1	B134001-1	3	H312	Circulation (Hallway)	Hallway at Classrooms 312 and 313	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
1340	1	B134001-1	3	H312	Circulation (Hallway)	Hallway at Classrooms 312 and 313	yes	W2	Plaster	White	None	0	30.1	Positive
1340	1	B134001-1	3	H312	Circulation (Hallway)	Hallway at Classrooms 312 and 313	yes	W3	Plaster	White	None	0	28.3	Positive
1340	1	B134001-1	3	H312	Circulation (Hallway)	Hallway at Classrooms 312 and 313	yes	W4	Plaster	White	None	0	34.5	Positive
1340	1	B134001-1	3	H312	Circulation (Hallway)	Hallway at Classrooms 312 and 313	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1340	1	B134001-1	3	H312	Circulation (Hallway)	Hallway at Classrooms 312 and 313	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1340	1	B134001-1	3	H312	Circulation (Hallway)	Hallway at Classrooms 312 and 313	yes	Covebase	Concrete	Brown	Chipping	50	2.5	Positive
1340	1	B134001-1	3	S38	Stairs, Fire Tower	Fire Tower Stairwell beside Classroom 309	yes	W1	Ceramic Brick	N/A	N/A	N/A	N/A	N/A
1340	1	B134001-1	3	S38	Stairs, Fire Tower	Fire Tower Stairwell beside Classroom 309	yes	W2	Ceramic Brick	N/A	N/A	N/A	N/A	N/A
1340	1	B134001-1	3	S38	Stairs, Fire Tower	Fire Tower Stairwell beside Classroom 309	yes	W3	Ceramic Brick	N/A	N/A	N/A	N/A	N/A
1340	1	B134001-1	3	S38	Stairs, Fire Tower	Fire Tower Stairwell beside Classroom 309	yes	Grate	Metal	Brown	Chipping	30	0.3	Negative
1340	1	B134001-1	3	S38	Stairs, Fire Tower	Fire Tower Stairwell beside Classroom 309	yes	W4	Ceramic Brick	N/A	N/A	N/A	N/A	N/A

1340	1	B134001-1	3	S38	Stairs, Fire Tower	Fire Tower Stairwell beside Classroom 309	yes	Ceiling	Concrete	White	Efflorescence	10	4.9	Positive
1340	1	B134001-1	3	S38	Stairs, Fire Tower	Fire Tower Stairwell beside Classroom 309	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1340	1	B134001-1	3	S39	Stairs, Fire Tower	Fire Tower Stairwell across from Classroom 307	yes	W1	Ceramic Brick	N/A	N/A	N/A	N/A	N/A
1340	1	B134001-1	3	S39	Stairs, Fire Tower	Fire Tower Stairwell across from Classroom 307	yes	W2	Ceramic Brick	N/A	N/A	N/A	N/A	N/A
1340	1	B134001-1	3	S39	Stairs, Fire Tower	Fire Tower Stairwell across from Classroom 307	yes	W3	Ceramic Brick	N/A	N/A	N/A	N/A	N/A
1340	1	B134001-1	3	S39	Stairs, Fire Tower	Fire Tower Stairwell across from Classroom 307	yes	Grate	Metal	Brown	Chipping/Flaking	15	25.4	Positive
1340	1	B134001-1	3	S39	Stairs, Fire Tower	Fire Tower Stairwell across from Classroom 307	yes	W4	Ceramic Brick	N/A	N/A	N/A	N/A	N/A
1340	1	B134001-1	3	S39	Stairs, Fire Tower	Fire Tower Stairwell across from Classroom 307	yes	Grate	Metal	Brown	Chipping/Flaking	30	1.6	Positive
1340	1	B134001-1	3	S39	Stairs, Fire Tower	Fire Tower Stairwell across from Classroom 307	yes	Ceiling	Concrete	White	Efflorescence	25	5.1	Positive
1340	1	B134001-1	3	S39	Stairs, Fire Tower	Fire Tower Stairwell across from Classroom 307	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1340	1	B134001-1	B	S01	Stairs	Stairwell by Boiler Room	yes	W1	Plaster	White	None	0	7.6	Positive
1340	1	B134001-1	B	S01	Stairs	Stairwell by Boiler Room	yes	W2	Sheetrock	White	None	0	0.01	Negative
1340	1	B134001-1	B	S01	Stairs	Stairwell by Boiler Room	yes	W3	Plaster	White	Flaking	2	3	Positive
1340	1	B134001-1	B	S01	Stairs	Stairwell by Boiler Room	yes	W4	Metal	Blue	Chipping	4	0.09	Negative
1340	1	B134001-1	B	S01	Stairs	Stairwell by Boiler Room	yes	Ceiling	Concrete	White	None	0	N/A	N/A
1340	1	B134001-1	B	S01	Stairs	Stairwell by Boiler Room	yes	Stair Undercarriage	Metal	White	Flaking	25	5.07	Positive
1340	1	B134001-1	B	S01	Stairs	Stairwell by Boiler Room	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1340	1	B134001-1	B	S01	Stairs	Stairwell by Boiler Room	yes	Covebase	Concrete	Gray	Chipping	6	0.15	Negative
1340	1	B134001-1	B	S01	Stairs	Stairwell by Boiler Room	yes	Riser	Metal	Gray	Chipping	20	0.41	Negative
1340	1	B134001-1	B	S01	Stairs	Stairwell by Boiler Room	yes	Stringer	Metal	Gray	Chipping	6	3.32	Positive
1340	1	B134001-1	B	S01	Stairs	Stairwell by Boiler Room	yes	Hand rails	Wood	Gray	Chipping	20	0.15	Negative
1340	1	B134001-1	B	002B	Computer - Intermediate Middle	Computer Room B2	yes	W1	Plaster	White	Chipping	10	0.42	Negative
1340	1	B134001-1	B	002B	Computer - Intermediate Middle	Computer Room B2	yes	W1	Brick	White	Chipping	10	0.05	Negative
1340	1	B134001-1	B	002B	Computer - Intermediate Middle	Computer Room B2	yes	Door Frame	Metal	Brown	Chipping	15	0.14	Negative
1340	1	B134001-1	B	002B	Computer - Intermediate Middle	Computer Room B2	yes	W2	Sheetrock	White	Partially Inaccessible	0	0.01	Negative
1340	1	B134001-1	B	002B	Computer - Intermediate Middle	Computer Room B2	yes	W3	Plaster	White	Flaking	25	3.03	Positive
1340	1	B134001-1	B	002B	Computer - Intermediate Middle	Computer Room B2	yes	W3	Brick	White	Chipping	50	0.08	Negative
1340	1	B134001-1	B	002B	Computer - Intermediate Middle	Computer Room B2	yes	W3	Sheetrock	White	Chipping	12	0.01	Negative
1340	1	B134001-1	B	002B	Computer - Intermediate Middle	Computer Room B2	yes	W4	Plaster	White	Flaking	10	9.13	Positive
1340	1	B134001-1	B	002B	Computer - Intermediate Middle	Computer Room B2	yes	W4	Brick	White	Chipping	2	0.09	Negative
1340	1	B134001-1	B	002B	Computer - Intermediate Middle	Computer Room B2	yes	Door Frame	Wood	Brown	Chipping	4	0.03	Negative
1340	1	B134001-1	B	002B	Computer - Intermediate Middle	Computer Room B2	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1340	1	B134001-1	B	002B	Computer - Intermediate Middle	Computer Room B2	yes	Ceiling	Plaster	White	Flaking	12	2.8	Positive
1340	1	B134001-1	B	002B	Computer - Intermediate Middle	Computer Room B2	yes	Duct Work	Metal	White	Flaking	2	6.6	Positive
1340	1	B134001-1	B	002B	Computer - Intermediate Middle	Computer Room B2	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1340	1	B134001-1	B	002B	Computer - Intermediate Middle	Computer Room B2	yes	Covebase	Concrete	Brown	Flaking/Chipping	100	2.54	Positive
1340	1	B134001-1	B	007B-1	Electrical Room	IT MDF Room inside Computer Room Storage on Boiler Room Side	no	W1	No Access	No Access	No Access	No Access	No Access	No Access
1340	1	B134001-1	B	007B-1	Electrical Room	IT MDF Room inside Computer Room Storage on Boiler Room Side	no	W2	No Access	No Access	No Access	No Access	No Access	No Access
1340	1	B134001-1	B	007B-1	Electrical Room	IT MDF Room inside Computer Room Storage on Boiler Room Side	no	W3	No Access	No Access	No Access	No Access	No Access	No Access
1340	1	B134001-1	B	007B-1	Electrical Room	IT MDF Room inside Computer Room Storage on Boiler Room Side	no	W4	No Access	No Access	No Access	No Access	No Access	No Access
1340	1	B134001-1	B	007B-1	Electrical Room	IT MDF Room inside Computer Room Storage on Boiler Room Side	no	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1340	1	B134001-1	B	007B-1	Electrical Room	IT MDF Room inside Computer Room Storage on Boiler Room Side	no	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1340	1	B134001-1	B	007B	Storage	Computer Room Storage on Boiler Room Side	yes	W1	Brick	White	None	0	0.01	Negative
1340	1	B134001-1	B	007B	Storage	Computer Room Storage on Boiler Room Side	yes	Pipe	Metal	White	Flaking	4	0.14	Negative
1340	1	B134001-1	B	007B	Storage	Computer Room Storage on Boiler Room Side	yes	W2	Brick	White	None	0	0.16	Negative
1340	1	B134001-1	B	007B	Storage	Computer Room Storage on Boiler Room Side	yes	W2	Sheetrock	White	None	0	0.05	Negative
1340	1	B134001-1	B	007B	Storage	Computer Room Storage on Boiler Room Side	yes	W3	Brick	White	Flaking	4	0.01	Negative

1340	1	B134001-1	B	007B	Storage	Computer Room Storage on Boiler Room Side	yes	W3	Sheetrock	White	None	0	0.01	Negative
1340	1	B134001-1	B	007B	Storage	Computer Room Storage on Boiler Room Side	yes	W4	Brick	White	None	0	0.08	Negative
1340	1	B134001-1	B	007B	Storage	Computer Room Storage on Boiler Room Side	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1340	1	B134001-1	B	007B	Storage	Computer Room Storage on Boiler Room Side	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1340	1	B134001-1	B	002B-1	Storage	Computer Room Storage by Back of Buidling	yes	W1	Sheetrock	White	Partially Inaccessible/Chipping	15	0.01	Negative
1340	1	B134001-1	B	002B-1	Storage	Computer Room Storage by Back of Buidling	yes	W2	Brick	White	Partially Inaccessible	0	0.06	Negative
1340	1	B134001-1	B	002B-1	Storage	Computer Room Storage by Back of Buidling	yes	W2	Plaster	White	Partially Inaccessible	0	4.21	Positive
1340	1	B134001-1	B	002B-1	Storage	Computer Room Storage by Back of Buidling	yes	W3	Plaster	White	Partially Inaccessible/Flaking	6	2.98	Positive
1340	1	B134001-1	B	002B-1	Storage	Computer Room Storage by Back of Buidling	yes	W3	Brick	White	Partially Inaccessible	0	0.11	Negative
1340	1	B134001-1	B	002B-1	Storage	Computer Room Storage by Back of Buidling	yes	W3	Sheetrock	White	Partially Inaccessible	0	0.01	Negative
1340	1	B134001-1	B	002B-1	Storage	Computer Room Storage by Back of Buidling	yes	W4	Plaster	White	Efflorescence/Spalling/Flaking	25	3.76	Positive
1340	1	B134001-1	B	002B-1	Storage	Computer Room Storage by Back of Buidling	yes	W4	Brick	White	Partially Inaccessible	0	0.12	Negative
1340	1	B134001-1	B	002B-1	Storage	Computer Room Storage by Back of Buidling	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1340	1	B134001-1	B	002B-1	Storage	Computer Room Storage by Back of Buidling	yes	Ceiling	Plaster	White	Flaking	5	2.5	Positive
1340	1	B134001-1	B	002B-1	Storage	Computer Room Storage by Back of Buidling	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1340	1	B134001-1	B	002B-1	Storage	Computer Room Storage by Back of Buidling	yes	Covebase	Concrete	Brown	Partially Inaccessible	0	1.25	Positive
1340	1	B134001-1	B	H01	Circulation (Hallway)	Hallway at Computer Room	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
1340	1	B134001-1	B	H01	Circulation (Hallway)	Hallway at Computer Room	yes	W2	Brick	White	Flaking	100	2.11	Positive
1340	1	B134001-1	B	H01	Circulation (Hallway)	Hallway at Computer Room	yes	W3	Plaster	White	Cracking	4	0.17	Negative
1340	1	B134001-1	B	H01	Circulation (Hallway)	Hallway at Computer Room	yes	W4	Brick	White	Flaking	10	1.77	Positive
1340	1	B134001-1	B	H01	Circulation (Hallway)	Hallway at Computer Room	yes	Pipe	Metal	White	Flaking	1	0.28	Negative
1340	1	B134001-1	B	H01	Circulation (Hallway)	Hallway at Computer Room	yes	Ceiling	Concrete	White	Partially Inaccessible/Flaking	50	0.32	Negative
1340	1	B134001-1	B	H01	Circulation (Hallway)	Hallway at Computer Room	yes	Duct Work	Metal	White	Flaking	25	3.16	Positive
1340	1	B134001-1	B	H01	Circulation (Hallway)	Hallway at Computer Room	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1340	1	B134001-1	B	H01	Circulation (Hallway)	Hallway at Computer Room	yes	Riser	Concrete	Gray	Chipping	20	0.09	Negative
1340	1	B134001-1	B	H01	Circulation (Hallway)	Hallway at Computer Room	yes	Hand Rail	Metal	Brown	Chipping	15	0.18	Negative
1340	1	B134001-1	B	H01	Circulation (Hallway)	Hallway at Computer Room	yes	Covebase	Concrete	Brown	Chipping/Flaking	15	0.1	Negative
1340	1	B134001-1	B	004B	Storage	Storage under Stairwell near Boiler Room	no	W1	Brick	White	None	0	0.07	Negative
1340	1	B134001-1	B	004B	Storage	Storage under Stairwell near Boiler Room	no	W2	Plaster	White	Partially Inaccessible	0	0.06	Negative
1340	1	B134001-1	B	004B	Storage	Storage under Stairwell near Boiler Room	no	W3	Brick	White	Partially Inaccessible	0	0.07	Negative
1340	1	B134001-1	B	004B	Storage	Storage under Stairwell near Boiler Room	no	W4	Brick	White	Partially Inaccessible/Flaking	6	0.09	Negative
1340	1	B134001-1	B	004B	Storage	Storage under Stairwell near Boiler Room	no	Ceiling	Metal	Tan	Rusting	25	2.64	Positive
1340	1	B134001-1	B	004B	Storage	Storage under Stairwell near Boiler Room	no	Floor	Concrete	Gray	Partially Inaccessible	0	0.09	Negative
1340	1	B134001-1	B	003B	Student Restrooms - Female (4-12)	Girl's Restroom across from Boiler Room	yes	W1	Brick	White	Flaking	12	0.18	Negative
1340	1	B134001-1	B	003B	Student Restrooms - Female (4-12)	Girl's Restroom across from Boiler Room	yes	Door Frame	Metal	Brown	Chipping	8	0.07	Negative
1340	1	B134001-1	B	003B	Student Restrooms - Female (4-12)	Girl's Restroom across from Boiler Room	yes	Steel Beam	Metal	White	Flaking	4	2.88	Positive
1340	1	B134001-1	B	003B	Student Restrooms - Female (4-12)	Girl's Restroom across from Boiler Room	yes	W2	Brick	White	None	0	0.25	Negative
1340	1	B134001-1	B	003B	Student Restrooms - Female (4-12)	Girl's Restroom across from Boiler Room	yes	W3	Brick	White	Flaking	20	0.07	Negative
1340	1	B134001-1	B	003B	Student Restrooms - Female (4-12)	Girl's Restroom across from Boiler Room	yes	W4	CMU	White	None	0	0.05	Negative
1340	1	B134001-1	B	003B	Student Restrooms - Female (4-12)	Girl's Restroom across from Boiler Room	yes	Ceiling	Concrete	White	Flaking	200	0.25	Negative
1340	1	B134001-1	B	003B	Student Restrooms - Female (4-12)	Girl's Restroom across from Boiler Room	yes	Duct Work	Metal	White	Flaking	2	0.01	Negative
1340	1	B134001-1	B	003B	Student Restrooms - Female (4-12)	Girl's Restroom across from Boiler Room	yes	Floor	Concrete	Gray	Chipping	25	0.11	Negative
1340	1	B134001-1	B	003B	Student Restrooms - Female (4-12)	Girl's Restroom across from Boiler Room	yes	Columns	Concrete	White	Chipping	4	0.32	Negative
1340	1	B134001-1	B	003B	Student Restrooms - Female (4-12)	Girl's Restroom across from Boiler Room	yes	Covebase	Concrete	Gray	Chipping	12	0.29	Negative
1340	1	B134001-1	B	005B	Boiler Room	Boiler Room	no	W1	Brick	White	Partially Inaccessible/Flaking	100	6.11	Positive
1340	1	B134001-1	B	005B	Boiler Room	Boiler Room	no	W2	Brick	White	Partially Inaccessible	0	0.17	Negative
1340	1	B134001-1	B	005B	Boiler Room	Boiler Room	no	W3	Brick	White	Partially Inaccessible	0	0.18	Negative
1340	1	B134001-1	B	005B	Boiler Room	Boiler Room	no	W4	Brick	White	Partially Inaccessible	0	10.91	Positive
1340	1	B134001-1	B	005B	Boiler Room	Boiler Room	no	Ceiling	Concrete	White	Flaking	500	0.06	Negative
1340	1	B134001-1	B	005B	Boiler Room	Boiler Room	no	Duct Work	Metal	White	Flaking	20	14.56	Positive
1340	1	B134001-1	B	005B	Boiler Room	Boiler Room	no	Floor	Concrete	Gray	Partially Inaccessible	0	0.31	Negative

1340	1	B134001-1	B	005B	Boiler Room	Boiler Room	no	Hand Rail	Metal	Green	Chipping	20	0.81	Positive
1340	1	B134001-1	B	006B	Boiler Room	Pump Room in Boiler Room	no	W1	Brick	Green/White	Flaking	250	3.02	Positive
1340	1	B134001-1	B	006B	Boiler Room	Pump Room in Boiler Room	no	W2	Brick	Green/White	Flaking	75	2.98	Positive
1340	1	B134001-1	B	006B	Boiler Room	Pump Room in Boiler Room	no	W3	Brick	Green/White	Flaking	200	1.78	Positive
1340	1	B134001-1	B	006B	Boiler Room	Pump Room in Boiler Room	no	W4	Brick	Green/White	Flaking	100	1.88	Positive
1340	1	B134001-1	B	006B	Boiler Room	Pump Room in Boiler Room	no	Ceiling	Concrete	White	Flaking	200	3.27	Positive
1340	1	B134001-1	B	006B	Boiler Room	Pump Room in Boiler Room	no	Pipe	Metal	White	Flaking	6	2.36	Positive
1340	1	B134001-1	B	006B	Boiler Room	Pump Room in Boiler Room	no	Floor	Concrete	Gray	Partially Inaccessible	0	0.07	Negative
1340	1	B134001-1	B	009B	General Office	Building Engineer's Office in Boiler Room	no	W1	Brick	White	Flaking	75	0.39	Negative
1340	1	B134001-1	B	009B	General Office	Building Engineer's Office in Boiler Room	no	Window Frame	Wood	Blue	Flaking	2	3.75	Positive
1340	1	B134001-1	B	009B	General Office	Building Engineer's Office in Boiler Room	no	Door Frame	Wood	Tan	Chipping	8	0.21	Negative
1340	1	B134001-1	B	009B	General Office	Building Engineer's Office in Boiler Room	no	W2	Brick	White	Flaking/Spalling	50	0.33	Negative
1340	1	B134001-1	B	009B	General Office	Building Engineer's Office in Boiler Room	no	Pipe	Metal	White	Chipping/Flaking	2	8.69	Positive
1340	1	B134001-1	B	009B	General Office	Building Engineer's Office in Boiler Room	no	W3	Brick	White	Partially Inaccessible/Flaking	40	0.31	Negative
1340	1	B134001-1	B	009B	General Office	Building Engineer's Office in Boiler Room	no	W4	Brick	White	Partially Inaccessible/Flaking	20	0.35	Negative
1340	1	B134001-1	B	009B	General Office	Building Engineer's Office in Boiler Room	no	Panel	Wood	Tan	Chipping	2	0.06	Negative
1340	1	B134001-1	B	009B	General Office	Building Engineer's Office in Boiler Room	no	Panel	Metal	Tan	Chipping	2	0.08	Negative
1340	1	B134001-1	B	009B	General Office	Building Engineer's Office in Boiler Room	no	Ceiling	Concrete	White	Flaking	200	2.74	Positive
1340	1	B134001-1	B	009B	General Office	Building Engineer's Office in Boiler Room	no	Floor	Concrete	Gray	Chipping	125	0.13	Negative
1340	1	B134001-1	B	008B	Storage	Storage Room in the Hallway next to Boiler Room	no	W1	Brick	Gray/White	Partially Inaccessible	0	0.93	Positive
1340	1	B134001-1	B	008B	Storage	Storage Room in the Hallway next to Boiler Room	no	W2	Brick	Gray/White	Partially Inaccessible	0	0.78	Positive
1340	1	B134001-1	B	008B	Storage	Storage Room in the Hallway next to Boiler Room	no	W3	Brick	Gray/White	Partially Inaccessible	0	0.81	Positive
1340	1	B134001-1	B	008B	Storage	Storage Room in the Hallway next to Boiler Room	no	W4	Brick	Gray/White	Partially Inaccessible	0	0.89	Positive
1340	1	B134001-1	B	008B	Storage	Storage Room in the Hallway next to Boiler Room	no	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A
1340	1	B134001-1	B	008B	Storage	Storage Room in the Hallway next to Boiler Room	no	Floor	Concrete	Gray	Partially Inaccessible	0	0.13	Negative
1340	1	B134001-1	B	011B	Storage	Storage at Cafeteria A	no	W1	Sheetrock	N/A	N/A	N/A	N/A	N/A
1340	1	B134001-1	B	011B	Storage	Storage at Cafeteria A	no	W2	Brick	White	Partially Inaccessible	0	0.01	Negative
1340	1	B134001-1	B	011B	Storage	Storage at Cafeteria A	no	W3	Brick	White	Partially Inaccessible	0	0.01	Negative
1340	1	B134001-1	B	011B	Storage	Storage at Cafeteria A	no	W4	Brick	White	Partially Inaccessible	0	0.04	Negative
1340	1	B134001-1	B	011B	Storage	Storage at Cafeteria A	no	Ceiling	Concrete	White	None	0	0.05	Negative
1340	1	B134001-1	B	011B	Storage	Storage at Cafeteria A	no	Floor	Wood	Varnish	Partially Inaccessible	0	0.06	Negative
1340	1	B134001-1	B	001B	Cafeteria (Dining Area)	Cafeteria A	yes	W1	Plaster	Blue	None	0	14.71	Positive
1340	1	B134001-1	B	001B	Cafeteria (Dining Area)	Cafeteria A	yes	W1	Brick	Blue	Chipping	2	0.04	Negative
1340	1	B134001-1	B	001B	Cafeteria (Dining Area)	Cafeteria A	yes	Door	Metal	Brown	Chipping	8	0.01	Negative
1340	1	B134001-1	B	001B	Cafeteria (Dining Area)	Cafeteria A	yes	Door Frame	Metal	Brown	Chipping	6	0.04	Negative
1340	1	B134001-1	B	001B	Cafeteria (Dining Area)	Cafeteria A	yes	W2	Plaster	Yellow	Spalling/Flaking	1	3.95	Positive
1340	1	B134001-1	B	001B	Cafeteria (Dining Area)	Cafeteria A	yes	W2	Brick	Yellow	None	0	0.03	Negative
1340	1	B134001-1	B	001B	Cafeteria (Dining Area)	Cafeteria A	yes	Door Frame	Wood	Brown	Chipping	4	0.31	Negative
1340	1	B134001-1	B	001B	Cafeteria (Dining Area)	Cafeteria A	yes	W3	Plaster	Blue	None	0	13.11	Positive
1340	1	B134001-1	B	001B	Cafeteria (Dining Area)	Cafeteria A	yes	W3	Brick	Blue	Efflorescence/Chipping /Flaking	50	0.04	Negative
1340	1	B134001-1	B	001B	Cafeteria (Dining Area)	Cafeteria A	yes	W4	Plaster	Yellow	None	0	4.82	Positive
1340	1	B134001-1	B	001B	Cafeteria (Dining Area)	Cafeteria A	yes	W4	Brick	Yellow	None	0	0.14	Negative
1340	1	B134001-1	B	001B	Cafeteria (Dining Area)	Cafeteria A	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1340	1	B134001-1	B	001B	Cafeteria (Dining Area)	Cafeteria A	yes	Ceiling	Plaster	White	Flaking	10	4.15	Positive
1340	1	B134001-1	B	001B	Cafeteria (Dining Area)	Cafeteria A	yes	Duct Work	Metal	White	Flaking	6	4.24	Positive
1340	1	B134001-1	B	001B	Cafeteria (Dining Area)	Cafeteria A	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1340	1	B134001-1	B	001B	Cafeteria (Dining Area)	Cafeteria A	yes	Covebase	Concrete	Brown	Chipping/Flaking	50	5.36	Positive
1340	1	B134001-1	B	010B	Storage	Storage at the Left Corner of Cafeteria A	no	W1	Plaster	White	Efflorescence/Cracking	4	4.55	Positive
1340	1	B134001-1	B	010B	Storage	Storage at the Left Corner of Cafeteria A	no	W2	Plaster	White	Partially Inaccessible	0	4.5	Positive
1340	1	B134001-1	B	010B	Storage	Storage at the Left Corner of Cafeteria A	no	W3	Plaster	White	Partially Inaccessible/Flakin	2	0.74	Positive
1340	1	B134001-1	B	010B	Storage	Storage at the Left Corner of Cafeteria A	no	W4	Plaster	White	Efflorescence/Spalling	40	5.45	Positive
1340	1	B134001-1	B	010B	Storage	Storage at the Left Corner of Cafeteria A	no	Ceiling	Plaster	White	Flaking	2	4.3	Positive
1340	1	B134001-1	B	010B	Storage	Storage at the Left Corner of Cafeteria A	no	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1340	1	B134001-1	B	014B	Student Restrooms - Male (4-12)	Boy's Restroom across from Cafeteria A	yes	W1	Brick	White	Flaking	2	0.23	Negative
1340	1	B134001-1	B	014B	Student Restrooms - Male (4-12)	Boy's Restroom across from Cafeteria A	yes	Door Frames	Metal	Brown	Chipping	8	0.04	Negative
1340	1	B134001-1	B	014B	Student Restrooms - Male (4-12)	Boy's Restroom across from Cafeteria A	yes	Duct Work	Metal	White	Flaking	3	0.35	Negative
1340	1	B134001-1	B	014B	Student Restrooms - Male (4-12)	Boy's Restroom across from Cafeteria A	yes	W2	Brick	White	Flaking	4	0.31	Negative
1340	1	B134001-1	B	014B	Student Restrooms - Male (4-12)	Boy's Restroom across from Cafeteria A	yes	W3	Brick	White	Flaking	12	0.4	Negative

1340	1	B134001-1	B	014B	Student Restrooms - Male (4-12)	Boy's Restroom across from Cafeteria A	yes	W4	Brick	White	None	0	0.39	Negative
1340	1	B134001-1	B	014B	Student Restrooms - Male (4-12)	Boy's Restroom across from Cafeteria A	yes	Ceiling	Concrete	White	Flaking	400	0.07	Negative
1340	1	B134001-1	B	014B	Student Restrooms - Male (4-12)	Boy's Restroom across from Cafeteria A	yes	Floor	Concrete	Gray	Chipping	100	0.11	Negative
1340	1	B134001-1	B	S03	Stairs	Stairwell by Cafeteria A	yes	W1	Plaster	White	None	0	5.02	Positive
1340	1	B134001-1	B	S03	Stairs	Stairwell by Cafeteria A	yes	W2	Plaster	White	None	0	4.98	Positive
1340	1	B134001-1	B	S03	Stairs	Stairwell by Cafeteria A	yes	Door	Wood	Blue	Chipping	3	0.18	Negative
1340	1	B134001-1	B	S03	Stairs	Stairwell by Cafeteria A	yes	Door Frame	Wood	Gray	Chipping	2	0.13	Negative
1340	1	B134001-1	B	S03	Stairs	Stairwell by Cafeteria A	yes	Door	Metal	Blue	Chipping	4	0.01	Negative
1340	1	B134001-1	B	S03	Stairs	Stairwell by Cafeteria A	yes	Door Frame	Metal	Blue	Chipping	8	0.13	Negative
1340	1	B134001-1	B	S03	Stairs	Stairwell by Cafeteria A	yes	W3	Plaster	White	Chipping	2	2.72	Positive
1340	1	B134001-1	B	S03	Stairs	Stairwell by Cafeteria A	yes	W4	Metal	White	Chipping	4	0.55	Negative
1340	1	B134001-1	B	S03	Stairs	Stairwell by Cafeteria A	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1340	1	B134001-1	B	S03	Stairs	Stairwell by Cafeteria A	yes	Stair Undercarriage	Metal	White	Flaking	8	7.41	Positive
1340	1	B134001-1	B	S03	Stairs	Stairwell by Cafeteria A	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1340	1	B134001-1	B	S03	Stairs	Stairwell by Cafeteria A	yes	Steel Plate	Metal	Gray	Chipping	10	0.07	Negative
1340	1	B134001-1	B	S03	Stairs	Stairwell by Cafeteria A	yes	Covebase	Concrete	Gray	Chipping	10	0.17	Negative
1340	1	B134001-1	B	S03	Stairs	Stairwell by Cafeteria A	yes	Riser	Metal	Gray	Chipping/Flaking	20	1.5	Positive
1340	1	B134001-1	B	S03	Stairs	Stairwell by Cafeteria A	yes	Stringer	Metal	Gray	Chipping	6	1.78	Positive
1340	1	B134001-1	B	S03	Stairs	Stairwell by Cafeteria A	yes	Hand Rails	Wood	Gray	Chipping	10	0.23	Negative
1340	1	B134001-1	B	S03	Stairs	Stairwell by Cafeteria A	yes	Newel Post	Metal	Gray	Chipping	2	3.09	Positive
1340	1	B134001-1	B	S03	Stairs	Stairwell by Cafeteria A	yes	Spindles	Metal	Blue	Chipping	15	2.75	Positive
1340	1	B134001-1	B	H02	Circulation (Hallway)	Hallway from Boiler Room to Cafeteria A	yes	W1	Brick	White	Flaking	40	1.65	Positive
1340	1	B134001-1	B	H02	Circulation (Hallway)	Hallway from Boiler Room to Cafeteria A	yes	Pipes	Metal	Brown/White	Chipping/Flaking	20	4.21	Positive
1340	1	B134001-1	B	H02	Circulation (Hallway)	Hallway from Boiler Room to Cafeteria A	yes	W2	Metal	Yellow	None	0	0.59	Negative
1340	1	B134001-1	B	H02	Circulation (Hallway)	Hallway from Boiler Room to Cafeteria A	yes	W3	Brick	White	Flaking	25	2.6	Positive
1340	1	B134001-1	B	H02	Circulation (Hallway)	Hallway from Boiler Room to Cafeteria A	yes	W4	Brick	White	Flaking	10	0.2	Negative
1340	1	B134001-1	B	H02	Circulation (Hallway)	Hallway from Boiler Room to Cafeteria A	yes	W4	Sheetrock	White	Chipping	12	0.03	Negative
1340	1	B134001-1	B	H02	Circulation (Hallway)	Hallway from Boiler Room to Cafeteria A	yes	Ceiling	Concrete	White	Partially Inaccessible/Flaking	125	3.26	Positive
1340	1	B134001-1	B	H02	Circulation (Hallway)	Hallway from Boiler Room to Cafeteria A	yes	Duct Work	Metal	White	Flaking	75	9.9	Positive
1340	1	B134001-1	B	H02	Circulation (Hallway)	Hallway from Boiler Room to Cafeteria A	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1340	1	B134001-1	B	H02	Circulation (Hallway)	Hallway from Boiler Room to Cafeteria A	yes	Posts	Metal	Gray	Chipping	15	2.55	Positive
1340	1	B134001-1	B	H02	Circulation (Hallway)	Hallway from Boiler Room to Cafeteria A	yes	Covebase	Concrete	Brown	Chipping/Flaking	15	0.13	Negative
1340	1	B134001-1	B	J1	Service Closets	Janitor's Closet between Boy's and Girl's Restrooms	no	W1	CMU	White	None	0	0.01	Negative
1340	1	B134001-1	B	J1	Service Closets	Janitor's Closet between Boy's and Girl's Restrooms	no	Door Frame	Metal	White	Chipping	4	0.06	Negative
1340	1	B134001-1	B	J1	Service Closets	Janitor's Closet between Boy's and Girl's Restrooms	no	W2	CMU	White	None	0	0.08	Negative
1340	1	B134001-1	B	J1	Service Closets	Janitor's Closet between Boy's and Girl's Restrooms	No	W3	Brick	White	Flaking	6	2.34	Positive
1340	1	B134001-1	B	J1	Service Closets	Janitor's Closet between Boy's and Girl's Restrooms	No	W4	Brick	White	Flaking	4	2.35	Positive
1340	1	B134001-1	B	J1	Service Closets	Janitor's Closet between Boy's and Girl's Restrooms	No	Ceiling	Concrete	White	None	0	3.26	Positive
1340	1	B134001-1	B	J1	Service Closets	Janitor's Closet between Boy's and Girl's Restrooms	No	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1340	1	B134001-1	B	012B	Kitchen	Kitchen	No	W1	Brick	White	Partially Inaccessible/Chipping	12	1.81	Positive
1340	1	B134001-1	B	012B	Kitchen	Kitchen	no	Door	Wood	Brown	Chipping	6	0.18	Negative
1340	1	B134001-1	B	012B	Kitchen	Kitchen	no	Door Frame	Wood	Brown	Chipping	4	0.07	Negative
1340	1	B134001-1	B	012B	Kitchen	Kitchen	No	W2	Brick	White	None	0	5.98	Positive
1340	1	B134001-1	B	012B	Kitchen	Kitchen	no	Door	Wood	Brown	Chipping	8	0.23	Negative
1340	1	B134001-1	B	012B	Kitchen	Kitchen	no	Door Frame	Metal	Brown	Chipping	8	0.06	Negative
1340	1	B134001-1	B	012B	Kitchen	Kitchen	No	W3	Brick	White	Partially Inaccessible	0	3.27	Positive
1340	1	B134001-1	B	012B	Kitchen	Kitchen	No	Pipes	Metal	Brown	Flaking	4	3.01	Positive
1340	1	B134001-1	B	012B	Kitchen	Kitchen	No	W4	Brick	White	No Access	30	N/A	N/A
1340	1	B134001-1	B	012B	Kitchen	Kitchen	No	Ceiling	Concrete	White	Flaking	400	1.57	Positive
1340	1	B134001-1	B	012B	Kitchen	Kitchen	no	Duct Work	Metal	White	Flaking	5	0.23	Negative
1340	1	B134001-1	B	012B	Kitchen	Kitchen	no	Floor	Concrete	Black	Chipping	10	0.08	Negative
1340	1	B134001-1	B	013B	Cafeteria (Dining Area)	Lunch Room B	yes	W1	Plaster	Blue	None	0	3.8	Positive
1340	1	B134001-1	B	013B	Cafeteria (Dining Area)	Lunch Room B	yes	W1	Brick	Blue	None	0	0.01	Negative
1340	1	B134001-1	B	013B	Cafeteria (Dining Area)	Lunch Room B	yes	Door Frame	Wood	Brown	Chipping	8	0.07	Negative
1340	1	B134001-1	B	013B	Cafeteria (Dining Area)	Lunch Room B	yes	W2	Plaster	Yellow	None	0	3.6	Positive
1340	1	B134001-1	B	013B	Cafeteria (Dining Area)	Lunch Room B	yes	W2	Brick	Yellow	None	0	0.07	Negative
1340	1	B134001-1	B	013B	Cafeteria (Dining Area)	Lunch Room B	yes	W3	Plaster	Blue	Partially Inaccessible	0	0.36	Negative
1340	1	B134001-1	B	013B	Cafeteria (Dining Area)	Lunch Room B	yes	W3	Brick	Blue	Partially Inaccessible	0	0.06	Negative
1340	1	B134001-1	B	013B	Cafeteria (Dining Area)	Lunch Room B	yes	W4	Plaster	Yellow	Flaking	2	28.8	Positive

1340	1	B134001-1	B	013B	Cafeteria (Dining Area)	Lunch Room B	yes	W4	Brick	Yellow	Chipping/Flaking	20	0.14	Negative
1340	1	B134001-1	B	013B	Cafeteria (Dining Area)	Lunch Room B	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1340	1	B134001-1	B	013B	Cafeteria (Dining Area)	Lunch Room B	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1340	1	B134001-1	B	013B	Cafeteria (Dining Area)	Lunch Room B	yes	Covebase	Concrete	Brown	Chipping/Flaking	75	2.95	Positive
1340	1	B134001-1	B	H03	Circulation (Hallway)	Hallway at Lunch Room B	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
1340	1	B134001-1	B	H03	Circulation (Hallway)	Hallway at Lunch Room B	yes	W2	Brick	White	None	0	1.58	Positive
1340	1	B134001-1	B	H03	Circulation (Hallway)	Hallway at Lunch Room B	yes	W3	Brick	White	Flaking	6	0.86	Positive
1340	1	B134001-1	B	H03	Circulation (Hallway)	Hallway at Lunch Room B	yes	Door	Metal	Blue/Brown	Chipping	4	0.01	Negative
1340	1	B134001-1	B	H03	Circulation (Hallway)	Hallway at Lunch Room B	yes	Door Frame	Metal	Blue	Chipping	4	0.26	Negative
1340	1	B134001-1	B	H03	Circulation (Hallway)	Hallway at Lunch Room B	yes	W4	Brick	White	Flaking	20	2.42	Positive
1340	1	B134001-1	B	H03	Circulation (Hallway)	Hallway at Lunch Room B	yes	Ceiling	Concrete	White	Partially Inaccessible/Flaking	12	3.26	Positive
1340	1	B134001-1	B	H03	Circulation (Hallway)	Hallway at Lunch Room B	yes	Duct Work	Metal	White	Flaking	25	8.83	Positive
1340	1	B134001-1	B	H03	Circulation (Hallway)	Hallway at Lunch Room B	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1340	1	B134001-1	B	H03	Circulation (Hallway)	Hallway at Lunch Room B	yes	Covebase	Concrete	Brown	Chipping	15	0.27	Negative
1340	1	B134001-1	B	S04	Stairs	Stairwell by Lunch Room B	yes	W1	Plaster	White	Flaking	6	6.3	Positive
1340	1	B134001-1	B	S04	Stairs	Stairwell by Lunch Room B	yes	W2	Plaster	White	None	0	7.98	Positive
1340	1	B134001-1	B	S04	Stairs	Stairwell by Lunch Room B	yes	W3	Plaster	White	Flaking	3	3.04	Positive
1340	1	B134001-1	B	S04	Stairs	Stairwell by Lunch Room B	yes	W4	Plaster	White	Flaking	6	9.73	Positive
1340	1	B134001-1	B	S04	Stairs	Stairwell by Lunch Room B	yes	Ceiling	Metal	White	Flaking	10	10.76	Positive
1340	1	B134001-1	B	S04	Stairs	Stairwell by Lunch Room B	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1340	1	B134001-1	B	S04	Stairs	Stairwell by Lunch Room B	yes	Covebase	Concrete	Brown	Chipping/Flaking	10	0.34	Negative
1340	1	B134001-1	B	S04	Stairs	Stairwell by Lunch Room B	yes	Riser	Metal	Brown	Chipping/Flaking	12	2.58	Positive
1340	1	B134001-1	B	S04	Stairs	Stairwell by Lunch Room B	yes	Stringer	Metal	Brown	Chipping	6	3.43	Positive
1340	1	B134001-1	B	S04	Stairs	Stairwell by Lunch Room B	yes	Hand Rail	Wood	Brown	Chipping	15	0.21	Negative
1340	2	B134001-2	1	100	Auditorium	Auditorium	yes	W1	CMU	White	None	0	0.09	Negative
1340	2	B134001-2	1	100	Auditorium	Auditorium	yes	W2	CMU	White	None	0	0.15	Negative
1340	2	B134001-2	1	100	Auditorium	Auditorium	yes	W3	CMU	White	Chipping	5	0.15	Negative
1340	2	B134001-2	1	100	Auditorium	Auditorium	yes	W4	CMU	White	None	0	0.08	Negative
1340	2	B134001-2	1	100	Auditorium	Auditorium	yes	Radiator Cover	Metal	Blue	Chipping	6	0.26	Negative
1340	2	B134001-2	1	100	Auditorium	Auditorium	yes	Door	Metal	Blue	Chipping	4	0.01	Negative
1340	2	B134001-2	1	100	Auditorium	Auditorium	yes	Door Frame	Metal	Blue	Chipping	2	0.12	Negative
1340	2	B134001-2	1	100	Auditorium	Auditorium	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1340	2	B134001-2	1	100	Auditorium	Auditorium	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1340	2	B134001-2	1	100 STAGE	Stage	Stage	yes	W1	CMU	White	None	0	0.11	Negative
1340	2	B134001-2	1	100 STAGE	Stage	Stage	yes	W2	CMU	White	None	0	0.13	Negative
1340	2	B134001-2	1	100 STAGE	Stage	Stage	yes	Door Frame	Metal	White	Chipping	12	0.15	Negative
1340	2	B134001-2	1	100 STAGE	Stage	Stage	yes	Pipe Outer Cover	Metal	White	Flaking	5	0.21	Negative
1340	2	B134001-2	1	100 STAGE	Stage	Stage	yes	W3	CMU	White	Flaking	100	0.11	Negative
1340	2	B134001-2	1	100 STAGE	Stage	Stage	yes	W4	CMU	White	Partially Inaccessible	0	0.14	Negative
1340	2	B134001-2	1	100 STAGE	Stage	Stage	yes	Ceiling	Concrete	White	None	0	N/A	N/A
1340	2	B134001-2	1	100 STAGE	Stage	Stage	yes	Floor	Wood	Varnish	Scrapes	20	0.11	Negative
1340	2	B134001-2	1	101	Primary	Classroom 101	yes	W1	CMU	White	None	0	0.14	Negative
1340	2	B134001-2	1	101	Primary	Classroom 101	yes	Door Frame	Metal	Black	Chipping	4	0.17	Negative
1340	2	B134001-2	1	101	Primary	Classroom 101	yes	W2	CMU	White	None	0	0.32	Negative
1340	2	B134001-2	1	101	Primary	Classroom 101	yes	W3	CMU	White	Partially Inaccessible	0	0.11	Negative
1340	2	B134001-2	1	101	Primary	Classroom 101	yes	Pipe Outer Covers	Metal	White	Flaking	2	0.19	Negative
1340	2	B134001-2	1	101	Primary	Classroom 101	yes	Shelves	Metal	Gray	Chipping	4	0.24	Negative
1340	2	B134001-2	1	101	Primary	Classroom 101	yes	Univent	Metal	Gray	Chipping	2	0.19	Negative
1340	2	B134001-2	1	101	Primary	Classroom 101	yes	W4	CMU	Yellow/White	None	0	0.06	Negative
1340	2	B134001-2	1	101	Primary	Classroom 101	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1340	2	B134001-2	1	101	Primary	Classroom 101	yes	Ceiling	Concrete	White	Flaking	6	0.12	Negative
1340	2	B134001-2	1	101	Primary	Classroom 101	yes	Beams	Concrete	White	None	0	0.06	Negative
1340	2	B134001-2	1	101	Primary	Classroom 101	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1340	2	B134001-2	1	101	Primary	Classroom 101	yes	Covebase	Concrete	Brown	Partially Inaccessible	0	0.05	Negative
1340	2	B134001-2	1	101	Primary	Classroom 101	yes	Coat Cubbies	Wood	Green	Cracking	10	0.11	Negative
1340	2	B134001-2	1	101	Primary	Classroom 101	yes	Columns	Concrete	White	Chipping	1	0.1	Negative
1340	2	B134001-2	1	101B	Storage	Classroom 101 Storage	yes	W1	CMU	White	None	0	0.19	Negative
1340	2	B134001-2	1	101B	Storage	Classroom 101 Storage	yes	W2	CMU	White	Partially Inaccessible	0	0.17	Negative
1340	2	B134001-2	1	101B	Storage	Classroom 101 Storage	yes	W3	CMU	White	Partially Inaccessible	0	0.12	Negative
1340	2	B134001-2	1	101B	Storage	Classroom 101 Storage	yes	W4	CMU	White	None	0	0.13	Negative
1340	2	B134001-2	1	101B	Storage	Classroom 101 Storage	yes	Ceiling	Concrete	White	Flaking	2	0.14	Negative
1340	2	B134001-2	1	101B	Storage	Classroom 101 Storage	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A

1340	2	B134001-2	1	101A	Student Restrooms - Male/Female (Classroom)	Classroom 101 Restroom	yes	W1	CMU	White	None	0	0.18	Negative
1340	2	B134001-2	1	101A	Student Restrooms - Male/Female (Classroom)	Classroom 101 Restroom	yes	Door Frame	Metal	Brown	Chipping	1	0.09	Negative
1340	2	B134001-2	1	101A	Student Restrooms - Male/Female (Classroom)	Classroom 101 Restroom	yes	W2	CMU	White	None	0	0.17	Negative
1340	2	B134001-2	1	101A	Student Restrooms - Male/Female (Classroom)	Classroom 101 Restroom	yes	W3	CMU	White	None	0	0.15	Negative
1340	2	B134001-2	1	101A	Student Restrooms - Male/Female (Classroom)	Classroom 101 Restroom	yes	W4	CMU	White	None	0	0.13	Negative
1340	2	B134001-2	1	101A	Student Restrooms - Male/Female (Classroom)	Classroom 101 Restroom	yes	Ceiling	Concrete	White	Flaking	2	0.12	Negative
1340	2	B134001-2	1	101A	Student Restrooms - Male/Female (Classroom)	Classroom 101 Restroom	yes	Floor	Terrazzo	N/A	N/A	N/A	N/A	N/A
1340	2	B134001-2	1	102	Primary	Classroom 102	yes	W1	CMU	White	None	0	0.04	Negative
1340	2	B134001-2	1	102	Primary	Classroom 102	yes	Door Frame	Metal	Black	Chipping	2	0.12	Negative
1340	2	B134001-2	1	102	Primary	Classroom 102	yes	W2	CMU	Green/White	Flaking	2	0.01	Negative
1340	2	B134001-2	1	102	Primary	Classroom 102	yes	W3	CMU	White	Partially Inaccessible	0	0.07	Negative
1340	2	B134001-2	1	102	Primary	Classroom 102	yes	Shelves	Metal	Gray	Partially Inaccessible	0	0.01	Negative
1340	2	B134001-2	1	102	Primary	Classroom 102	yes	Univent	Metal	Gray	Chipping	10	0.12	Negative
1340	2	B134001-2	1	102	Primary	Classroom 102	yes	Pipe Outer Covers	Metal	White	Flaking	3	0.18	Negative
1340	2	B134001-2	1	102	Primary	Classroom 102	yes	W4	CMU	White	Partially Inaccessible	0	0.07	Negative
1340	2	B134001-2	1	102	Primary	Classroom 102	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1340	2	B134001-2	1	102	Primary	Classroom 102	yes	Ceiling	Concrete	White	Flaking	2	0.09	Negative
1340	2	B134001-2	1	102	Primary	Classroom 102	yes	Beams	Concrete	White	None	0	0.14	Negative
1340	2	B134001-2	1	102	Primary	Classroom 102	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1340	2	B134001-2	1	102	Primary	Classroom 102	yes	Columns	Concrete	White	None	0	0.1	Negative
1340	2	B134001-2	1	102	Primary	Classroom 102	yes	Coat Cubbies	Wood	Green	Flaking	8	0.08	Negative
1340	2	B134001-2	1	102	Primary	Classroom 102	yes	Covebase	Concrete	Brown	Partially Inaccessible	0	0.14	Negative
1340	2	B134001-2	1	102B	Storage	Classroom 102 Storage	yes	W1	CMU	White	Partially Inaccessible	0	0.12	Negative
1340	2	B134001-2	1	102B	Storage	Classroom 102 Storage	yes	W2	CMU	White	Partially Inaccessible	0	0.16	Negative
1340	2	B134001-2	1	102B	Storage	Classroom 102 Storage	yes	Support Panel	Wood	Gray	Partially Inaccessible	0	0.01	Negative
1340	2	B134001-2	1	102B	Storage	Classroom 102 Storage	yes	W3	CMU	White	Partially Inaccessible	0	0.14	Negative
1340	2	B134001-2	1	102B	Storage	Classroom 102 Storage	yes	W4	CMU	White	Partially Inaccessible	0	0.02	Negative
1340	2	B134001-2	1	102B	Storage	Classroom 102 Storage	yes	Ceiling	Concrete	White	None	0	0.09	Negative
1340	2	B134001-2	1	102B	Storage	Classroom 102 Storage	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1340	2	B134001-2	1	102A	Student Restrooms - Male/Female (Classroom)	Classroom 102 Restroom	yes	W1	CMU	White	None	0	0.15	Negative
1340	2	B134001-2	1	102A	Student Restrooms - Male/Female (Classroom)	Classroom 102 Restroom	yes	W2	CMU	White	None	0	0.08	Negative
1340	2	B134001-2	1	102A	Student Restrooms - Male/Female (Classroom)	Classroom 102 Restroom	yes	W3	CMU	White	None	0	0.27	Negative
1340	2	B134001-2	1	102A	Student Restrooms - Male/Female (Classroom)	Classroom 102 Restroom	yes	W4	CMU	White	None	0	0.21	Negative
1340	2	B134001-2	1	102A	Student Restrooms - Male/Female (Classroom)	Classroom 102 Restroom	yes	Ceiling	Concrete	White	None	0	0.1	Negative
1340	2	B134001-2	1	102A	Student Restrooms - Male/Female (Classroom)	Classroom 102 Restroom	yes	Floor	Terrazzo	N/A	N/A	N/A	N/A	N/A
1340	2	B134001-2	1	H18	Circulation (Hallway)	Hallway outside Auditorium	yes	W1	CMU	White	Flaking	4	0.18	Negative
1340	2	B134001-2	1	H18	Circulation (Hallway)	Hallway outside Auditorium	yes	Univent	Metal	Blue	Chipping	6	0.07	Negative
1340	2	B134001-2	1	H18	Circulation (Hallway)	Hallway outside Auditorium	yes	W2	CMU	White	Chipping/Flaking	15	0.16	Negative
1340	2	B134001-2	1	H18	Circulation (Hallway)	Hallway outside Auditorium	yes	Univent	Metal	Blue	Chipping	4	0.14	Negative
1340	2	B134001-2	1	H18	Circulation (Hallway)	Hallway outside Auditorium	yes	Door	Metal	Blue	Chipping	6	0.11	Negative
1340	2	B134001-2	1	H18	Circulation (Hallway)	Hallway outside Auditorium	yes	Door Frame	Metal	Blue	Chipping	4	0.16	Negative
1340	2	B134001-2	1	H18	Circulation (Hallway)	Hallway outside Auditorium	yes	W3	CMU	White	None	0	0.14	Negative

1340	2	B134001-2	1	H18	Circulation (Hallway)	Hallway outside Auditorium	yes	W3	Concrete	White	Flaking	25	0.23	Negative
1340	2	B134001-2	1	H18	Circulation (Hallway)	Hallway outside Auditorium	yes	Door	Metal	Blue	Chipping	10	0.14	Negative
1340	2	B134001-2	1	H18	Circulation (Hallway)	Hallway outside Auditorium	yes	Door Frame	Metal	Blue	Chipping	6	0.16	Negative
1340	2	B134001-2	1	H18	Circulation (Hallway)	Hallway outside Auditorium	yes	W4	CMU	White	Chipping/Flaking	20	0.1	Negative
1340	2	B134001-2	1	H18	Circulation (Hallway)	Hallway outside Auditorium	yes	Door	Metal	Blue	Chipping	4	0.01	Negative
1340	2	B134001-2	1	H18	Circulation (Hallway)	Hallway outside Auditorium	yes	Door Frame	Metal	Blue	Chipping	2	0.18	Negative
1340	2	B134001-2	1	H18	Circulation (Hallway)	Hallway outside Auditorium	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1340	2	B134001-2	1	H18	Circulation (Hallway)	Hallway outside Auditorium	yes	Ceiling	Concrete	White	None	0	0.1	Negative
1340	2	B134001-2	1	H18	Circulation (Hallway)	Hallway outside Auditorium	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1340	2	B134001-2	1	H18	Circulation (Hallway)	Hallway outside Auditorium	yes	Covebase	Concrete	Brown	Chipping/Flaking	50	0.1	Negative
1340	2	B134001-2	1			Custodial Closet between Classrooms 101 and 102	no	W1	CMU	White	Flaking	2	0.2	Negative
1340	2	B134001-2	1			Custodial Closet between Classrooms 101 and 102	no	Door Frame	Metal	Brown	Chipping	4	0.16	Negative
1340	2	B134001-2	1			Custodial Closet between Classrooms 101 and 102	no	Column	Concrete	White	Flaking	2	0.12	Negative
1340	2	B134001-2	1			Custodial Closet between Classrooms 101 and 102	no	W2	CMU	White	None	0	0.22	Negative
1340	2	B134001-2	1			Custodial Closet between Classrooms 101 and 102	no	W3	CMU	White	None	0	0.19	Negative
1340	2	B134001-2	1			Custodial Closet between Classrooms 101 and 102	no	W4	CMU	White	None	0	0.22	Negative
1340	2	B134001-2	1			Custodial Closet between Classrooms 101 and 102	no	Ceiling	Concrete	White	Flaking	2	0.15	Negative
1340	2	B134001-2	1			Custodial Closet between Classrooms 101 and 102	no	Duct Work	Metal	White	Flaking	4	0.26	Negative
1340	2	B134001-2	1			Custodial Closet between Classrooms 101 and 102	no	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1340	2	B134001-2	1	S25	Stairs	Stairwell connecting Element 1 to Element 2	yes	W1	CMU	White	Flaking	1	0.18	Negative
1340	2	B134001-2	1	S25	Stairs	Stairwell connecting Element 1 to Element 2	yes	Doors	Metal	Blue	Chipping	4	0.16	Negative
1340	2	B134001-2	1	S25	Stairs	Stairwell connecting Element 1 to Element 2	yes	Radiator Cover	Metal	Blue	Chipping	2	0.23	Negative
1340	2	B134001-2	1	S25	Stairs	Stairwell connecting Element 1 to Element 2	yes	W2	CMU	White	Flaking	1	0.16	Negative
1340	2	B134001-2	1	S25	Stairs	Stairwell connecting Element 1 to Element 2	yes	Doors	Metal	Blue	Chipping	20	0.01	Negative
1340	2	B134001-2	1	S25	Stairs	Stairwell connecting Element 1 to Element 2	yes	Door Frame	Metal	Blue	Chipping	12	0.1	Negative
1340	2	B134001-2	1	S25	Stairs	Stairwell connecting Element 1 to Element 2	yes	W3	CMU	White	Flaking	15	0.17	Negative
1340	2	B134001-2	1	S25	Stairs	Stairwell connecting Element 1 to Element 2	yes	Univent	Metal	Blue	Chipping	6	0.18	Negative
1340	2	B134001-2	1	S25	Stairs	Stairwell connecting Element 1 to Element 2	yes	W4	CMU	White	None	0	0.2	Negative
1340	2	B134001-2	1	S25	Stairs	Stairwell connecting Element 1 to Element 2	yes	Ceiling	Concrete	White	Flaking	10	0.1	Negative
1340	2	B134001-2	1	S25	Stairs	Stairwell connecting Element 1 to Element 2	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1340	2	B134001-2	1	S25	Stairs	Stairwell connecting Element 1 to Element 2	yes	Riser	Metal	Brown	Chipping	20	0.35	Negative
1340	2	B134001-2	1	S25	Stairs	Stairwell connecting Element 1 to Element 2	yes	Stringer	Metal	Brown	Chipping	6	0.42	Negative
1340	2	B134001-2	1	S25	Stairs	Stairwell connecting Element 1 to Element 2	yes	Hand Rail	Metal	Brown	Chipping	10	0.26	Negative
1340	2	B134001-2	1	S25	Stairs	Stairwell connecting Element 1 to Element 2	yes	Covebase	Concrete	Brown	Chipping	4	0.01	Negative
1340	2	B134001-2	1			Women's Restroom in Stairwell between Elements 1 and 2	yes	W1	CMU	White	None	0	0.09	Negative
1340	2	B134001-2	1			Women's Restroom in Stairwell between Elements 1 and 2	yes	W2	CMU	White	None	0	0.16	Negative
1340	2	B134001-2	1			Women's Restroom in Stairwell between Elements 1 and 2	yes	W3	CMU	White	None	0	0.14	Negative
1340	2	B134001-2	1			Women's Restroom in Stairwell between Elements 1 and 2	yes	W4	CMU	White	None	0	0.17	Negative
1340	2	B134001-2	1			Women's Restroom in Stairwell between Elements 1 and 2	yes	Ceiling	Concrete	White	Flaking	1	0.15	Negative
1340	2	B134001-2	1			Women's Restroom in Stairwell between Elements 1 and 2	yes	Pipe	Metal	White	Flaking	3	0.16	Negative
1340	2	B134001-2	1			Women's Restroom in Stairwell between Elements 1 and 2	yes	Floor	Terrazzo	N/A	N/A	N/A	N/A	N/A
1340	2	B134001-2	1		Stairs	Stairwell connecting Element 2 to Breezeway to Element 3 (L Wing)	yes	W1	CMU	White	Chipping	5	0.15	Negative
1340	2	B134001-2	1		Stairs	Stairwell connecting Element 2 to Breezeway to Element 3 (L Wing)	yes	W2	CMU	White	Flaking	1	0.14	Negative
1340	2	B134001-2	1		Stairs	Stairwell connecting Element 2 to Breezeway to Element 3 (L Wing)	yes	Pipe Outer Covers	Metal	White	Flaking	1	0.3	Negative
1340	2	B134001-2	1		Stairs	Stairwell connecting Element 2 to Breezeway to Element 3 (L Wing)	yes	W3	CMU	White	Flaking/Chipping	2	0.1	Negative
1340	2	B134001-2	1		Stairs	Stairwell connecting Element 2 to Breezeway to Element 3 (L Wing)	yes	Radiator Cover	Metal	Blue	Chipping	8	0.26	Negative
1340	2	B134001-2	1		Stairs	Stairwell connecting Element 2 to Breezeway to Element 3 (L Wing)	yes	Door	Wood	Blue	Chipping	4	0.17	Negative
1340	2	B134001-2	1		Stairs	Stairwell connecting Element 2 to Breezeway to Element 3 (L Wing)	yes	Door Frame	Wood	Blue	Chipping	4	0.12	Negative
1340	2	B134001-2	1		Stairs	Stairwell connecting Element 2 to Breezeway to Element 3 (L Wing)	yes	Pipe	Metal	White	Flaking	2	0.18	Negative
1340	2	B134001-2	1		Stairs	Stairwell connecting Element 2 to Breezeway to Element 3 (L Wing)	yes	W4	CMU	White	Chipping	2	0.12	Negative
1340	2	B134001-2	1		Stairs	Stairwell connecting Element 2 to Breezeway to Element 3 (L Wing)	yes	Pipe	Metal	White	Flaking	3	0.15	Negative

1340	2	B134001-2	1		Stairs	Stairwell connecting Element 2 to Breezeway to Element 3 (L Wing)	yes	Ceiling	Concrete	White	Flaking	10	0.1	Negative
1340	2	B134001-2	1		Stairs	Stairwell connecting Element 2 to Breezeway to Element 3 (L Wing)	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1340	2	B134001-2	1		Stairs	Stairwell connecting Element 2 to Breezeway to Element 3 (L Wing)	yes	Covebase	Concrete	Brown	Chipping	6	0.13	Negative
1340	2	B134001-2	1		Stairs	Stairwell connecting Element 2 to Breezeway to Element 3 (L Wing)	yes	Riser	Metal	Brown	Chipping	6	0.33	Negative
1340	2	B134001-2	1		Stairs	Stairwell connecting Element 2 to Breezeway to Element 3 (L Wing)	yes	Stringer	Metal	Brown	Chipping	6	0.35	Negative
1340	2	B134001-2	1		Stairs	Stairwell connecting Element 2 to Breezeway to Element 3 (L Wing)	yes	Hand Rail	Metal	Brown	Chipping	10	0.36	Negative
1340	2	B134001-2	1	H18B	Circulation (Hallway)	Breezeway Hallway connecting Element 2 and Element 3 (L Wing)	yes	W1	Brick	N/A	N/A	N/A	N/A	N/A
1340	2	B134001-2	1	H18B	Circulation (Hallway)	Breezeway Hallway connecting Element 2 and Element 3 (L Wing)	yes	W2	Sheetrock	White	Chipping/Flaking	4	0.09	Negative
1340	2	B134001-2	1	H18B	Circulation (Hallway)	Breezeway Hallway connecting Element 2 and Element 3 (L Wing)	yes	W3	Metal	White	None	0	0.18	Negative
1340	2	B134001-2	1	H18B	Circulation (Hallway)	Breezeway Hallway connecting Element 2 and Element 3 (L Wing)	yes	W4	Sheetrock	White	Chipping/Flaking	2	0.13	Negative
1340	2	B134001-2	1	H18B	Circulation (Hallway)	Breezeway Hallway connecting Element 2 and Element 3 (L Wing)	yes	Ceiling	Metal	White	None	0	0.15	Negative
1340	2	B134001-2	1	H18B	Circulation (Hallway)	Breezeway Hallway connecting Element 2 and Element 3 (L Wing)	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1340	2	B134001-2	1	H18B	Circulation (Hallway)	Breezeway Hallway connecting Element 2 and Element 3 (L Wing)	yes	Covebase	Concrete	Brown	Chipping/Flaking	15	0.12	Negative
1340	2	B134001-2	1	H18B	Circulation (Hallway)	Breezeway Hallway connecting Element 2 and Element 3 (L Wing)	yes	Baseboard	Wood	Brown	Chipping	2	0.14	Negative
1340	2	B134001-2	2	201A	Gymnasium - Intermediate Middle	Gym	yes	W1	CMU	White/Blue	None	0	0.02	Negative
1340	2	B134001-2	2	201A	Gymnasium - Intermediate Middle	Gym	yes	Door Frame	Metal	Black	Chipping	6	0.07	Negative
1340	2	B134001-2	2	201A	Gymnasium - Intermediate Middle	Gym	yes	Door	Metal	Black	Chipping	8	0.09	Negative
1340	2	B134001-2	2	201A	Gymnasium - Intermediate Middle	Gym	yes	W2	CMU	White/Blue	Chipping	6	0.03	Negative
1340	2	B134001-2	2	201A	Gymnasium - Intermediate Middle	Gym	yes	Doors	Wood	Black	Chipping	12	0	Negative
1340	2	B134001-2	2	201A	Gymnasium - Intermediate Middle	Gym	yes	W3	CMU	White/Blue	Chipping	2	0.01	Negative
1340	2	B134001-2	2	201A	Gymnasium - Intermediate Middle	Gym	yes	Door	Metal	Black	Chipping	4	0.04	Negative
1340	2	B134001-2	2	201A	Gymnasium - Intermediate Middle	Gym	yes	Door Frame	Metal	Black	Chipping	2	0.06	Negative
1340	2	B134001-2	2	201A	Gymnasium - Intermediate Middle	Gym	yes	W4	CMU	White/Blue	Chipping	2	0.02	Negative
1340	2	B134001-2	2	201A	Gymnasium - Intermediate Middle	Gym	yes	Ceiling	Concrete	White	None	0	N/A	N/A
1340	2	B134001-2	2	201A	Gymnasium - Intermediate Middle	Gym	yes	Duct Work	Metal	White	Flaking	1	0.01	Negative
1340	2	B134001-2	2	201A	Gymnasium - Intermediate Middle	Gym	yes	Floor	Wood	Varnish	None	0	0	Negative
1340	2	B134001-2	2	201A	Gymnasium - Intermediate Middle	Gym	yes	Baseboard	Metal	Black	Chipping	50	0	Negative
1340	2	B134001-2	2	201B	Circulation (Hallway)	Gym Entrance	yes	W1	CMU	White	None	0	0.05	Negative
1340	2	B134001-2	2	201B	Circulation (Hallway)	Gym Entrance	yes	W1	Concrete	White	Flaking	4	0.01	Negative
1340	2	B134001-2	2	201B	Circulation (Hallway)	Gym Entrance	yes	W2	CMU	White	Flaking	3	0.08	Negative
1340	2	B134001-2	2	201B	Circulation (Hallway)	Gym Entrance	yes	W3	CMU	White	None	0	0.05	Negative
1340	2	B134001-2	2	201B	Circulation (Hallway)	Gym Entrance	yes	W4	CMU	White	Flaking	7	0.06	Negative
1340	2	B134001-2	2	201B	Circulation (Hallway)	Gym Entrance	yes	Radiator Cover	Metal	Brown	Chipping	1	0.21	Negative
1340	2	B134001-2	2	201B	Circulation (Hallway)	Gym Entrance	yes	Ceiling	Concrete	White	Flaking	1	0.01	Negative
1340	2	B134001-2	2	201B	Circulation (Hallway)	Gym Entrance	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1340	2	B134001-2	2	201B	Circulation (Hallway)	Gym Entrance	yes	Hand Rail	Metal	Black	Chipping	10	0.09	Negative
1340	2	B134001-2	2	201B	Circulation (Hallway)	Gym Entrance	yes	Stringer	Metal	Brown	Chipping	2	0.01	Negative
1340	2	B134001-2	2	201B	Circulation (Hallway)	Gym Entrance	yes	Riser	Concrete	Brown	Chipping	6	0	Negative
1340	2	B134001-2	2	201B	Circulation (Hallway)	Gym Entrance	yes	Covebase	Metal	Brown	Chipping	10	0.02	Negative
1340	2	B134001-2	2	201	Primary	Classroom 201	yes	W1	CMU	Blue/Yellow	Chipping	2	0.03	Negative
1340	2	B134001-2	2	201	Primary	Classroom 201	yes	Door	Wood	Brown	Chipping	8	0.02	Negative
1340	2	B134001-2	2	201	Primary	Classroom 201	yes	Door Frame	Metal	Brown	Chipping	6	0.03	Negative

1340	2	B134001-2	2	201	Primary	Classroom 201	yes	Coat Cubby Frame	Wood	Brown	Chipping	5	0.07	Negative
1340	2	B134001-2	2	201	Primary	Classroom 201	yes	W2	CMU	Blue	Partially Inaccessible	0	0.03	Negative
1340	2	B134001-2	2	201	Primary	Classroom 201	yes	Chalk Board Frame/Tray	Wood	Brown	Chipping	8	0.11	Negative
1340	2	B134001-2	2	201	Primary	Classroom 201	yes	W3	CMU	White	Flaking	6	0.01	Negative
1340	2	B134001-2	2	201	Primary	Classroom 201	yes	Pipe Outer Covers	Metal	White	Flaking	6	0.05	Negative
1340	2	B134001-2	2	201	Primary	Classroom 201	yes	Shelving	Wood	Brown	Chipping	8	0.25	Negative
1340	2	B134001-2	2	201	Primary	Classroom 201	yes	Univent	Metal	Brown	Chipping	8	0.04	Negative
1340	2	B134001-2	2	201	Primary	Classroom 201	yes	Columns	Concrete	Yellow	None	0	0.02	Negative
1340	2	B134001-2	2	201	Primary	Classroom 201	yes	W4	CMU	Blue	Chipping/Flaking	1	0.07	Negative
1340	2	B134001-2	2	201	Primary	Classroom 201	yes	Chalk Board Frame/Tray	Wood	Brown	Chipping	12	0.01	Negative
1340	2	B134001-2	2	201	Primary	Classroom 201	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1340	2	B134001-2	2	201	Primary	Classroom 201	yes	Ceiling	Concrete	White	Flaking	2	0.03	Negative
1340	2	B134001-2	2	201	Primary	Classroom 201	yes	Beams	Concrete	Yellow	None	0	0.02	Negative
1340	2	B134001-2	2	201	Primary	Classroom 201	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1340	2	B134001-2	2	201	Primary	Classroom 201	yes	Baseboard	Concrete	Blue/Brown	Partially Inaccessible	0	0.02	Negative
1340	2	B134001-2	2	202	Primary	Classroom 202	yes	W1	CMU	White	Partially Inaccessible	0	0.02	Negative
1340	2	B134001-2	2	202	Primary	Classroom 202	yes	Door Frame	Metal	Brown	Chipping	6	0.24	Negative
1340	2	B134001-2	2	202	Primary	Classroom 202	yes	W2	CMU	White	Partially Inaccessible	0	0.01	Negative
1340	2	B134001-2	2	202	Primary	Classroom 202	yes	W3	CMU	White	Partially Inaccessible	0	0.03	Negative
1340	2	B134001-2	2	202	Primary	Classroom 202	yes	Shelving	Metal	Brown	Chipping	8	0.04	Negative
1340	2	B134001-2	2	202	Primary	Classroom 202	yes	Univent	Metal	Brown	Chipping	8	0.03	Negative
1340	2	B134001-2	2	202	Primary	Classroom 202	yes	Pipe Outer Cover	Metal	White	Chipping	2	0.15	Negative
1340	2	B134001-2	2	202	Primary	Classroom 202	yes	Column	Concrete	White	Flaking	2	0.04	Negative
1340	2	B134001-2	2	202	Primary	Classroom 202	yes	W4	CMU	White	Partially Inaccessible	0	0.04	Negative
1340	2	B134001-2	2	202	Primary	Classroom 202	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1340	2	B134001-2	2	202	Primary	Classroom 202	yes	Ceiling	Concrete	White	None	0	0.02	Negative
1340	2	B134001-2	2	202	Primary	Classroom 202	yes	Beams	Concrete	White	Flaking	25	0.05	Negative
1340	2	B134001-2	2	202	Primary	Classroom 202	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1340	2	B134001-2	2	202	Primary	Classroom 202	yes	Covebase	Concrete	Brown	Partially Inaccessible	0	0.02	Negative
1340	2	B134001-2	2	RRM-2	Restrooms, Staff - Male	Men's Restroom in Stairwell next to Classroom 202	yes	W1	CMU	White	Flaking	1	0.18	Negative
1340	2	B134001-2	2	RRM-2	Restrooms, Staff - Male	Men's Restroom in Stairwell next to Classroom 202	yes	Door Frame	Metal	White	Chipping	4	0.11	Negative
1340	2	B134001-2	2	RRM-2	Restrooms, Staff - Male	Men's Restroom in Stairwell next to Classroom 202	yes	W2	CMU	White	None	0	0.17	Negative
1340	2	B134001-2	2	RRM-2	Restrooms, Staff - Male	Men's Restroom in Stairwell next to Classroom 202	yes	Pipe Outer Cover	Metal	White	Flaking	5	0.19	Negative
1340	2	B134001-2	2	RRM-2	Restrooms, Staff - Male	Men's Restroom in Stairwell next to Classroom 202	yes	W3	CMU	White	None	0	0.12	Negative
1340	2	B134001-2	2	RRM-2	Restrooms, Staff - Male	Men's Restroom in Stairwell next to Classroom 202	yes	W4	CMU	White	None	0	0.07	Negative
1340	2	B134001-2	2	RRM-2	Restrooms, Staff - Male	Men's Restroom in Stairwell next to Classroom 202	yes	Ceiling	Concrete	White	Flaking	2	0.01	Negative
1340	2	B134001-2	2	RRM-2	Restrooms, Staff - Male	Men's Restroom in Stairwell next to Classroom 202	yes	Pipe	Metal	White	Flaking	4	0.11	Negative
1340	2	B134001-2	2	RRM-2	Restrooms, Staff - Male	Men's Restroom in Stairwell next to Classroom 202	yes	Floor	Terrazzo	N/A	N/A	N/A	N/A	N/A
1340	2	B134001-2	2	RRW-2	Restrooms, Staff - Female	Women's Restroom in Stairwell next to Classroom 202	yes	W1	CMU	White	None	0	0	Negative
1340	2	B134001-2	2	RRW-2	Restrooms, Staff - Female	Women's Restroom in Stairwell next to Classroom 202	yes	W2	CMU	White	None	0	0.01	Negative
1340	2	B134001-2	2	RRW-2	Restrooms, Staff - Female	Women's Restroom in Stairwell next to Classroom 202	yes	W3	CMU	White	None	0	0.1	Negative
1340	2	B134001-2	2	RRW-2	Restrooms, Staff - Female	Women's Restroom in Stairwell next to Classroom 202	yes	W4	CMU	White	None	0	0	Negative
1340	2	B134001-2	2	RRW-2	Restrooms, Staff - Female	Women's Restroom in Stairwell next to Classroom 202	yes	Ceiling	Concrete	White	Flaking	1	0.12	Negative
1340	2	B134001-2	2	RRW-2	Restrooms, Staff - Female	Women's Restroom in Stairwell next to Classroom 202	yes	Floor	Terrazzo	N/A	N/A	N/A	N/A	N/A
1340	2	B134001-2	2	H30	Circulation (Hallway)	Hallway at Classrooms 201 and 202	yes	W1	CMU	White	Chipping/Flaking	2	0.07	Negative
1340	2	B134001-2	2	H30	Circulation (Hallway)	Hallway at Classrooms 201 and 202	yes	Door Frame	Metal	Brown	Chipping	10	0.03	Negative
1340	2	B134001-2	2	H30	Circulation (Hallway)	Hallway at Classrooms 201 and 202	yes	W2	CMU	White	Chipping/Flaking	25	0.1	Negative
1340	2	B134001-2	2	H30	Circulation (Hallway)	Hallway at Classrooms 201 and 202	yes	Univent	Metal	Brown	Chipping	10	0.03	Negative
1340	2	B134001-2	2	H30	Circulation (Hallway)	Hallway at Classrooms 201 and 202	yes	W3	CMU	White	Chipping/Flaking	2	0.06	Negative

1340	2	B134001-2	2	H30	Circulation (Hallway)	Hallway at Classrooms 201 and 202	yes	Door Frame	Metal	Brown	Chipping	10	0.02	Negative
1340	2	B134001-2	2	H30	Circulation (Hallway)	Hallway at Classrooms 201 and 202	yes	W4	CMU	White	Chipping/Flaking	30	0.01	Negative
1340	2	B134001-2	2	H30	Circulation (Hallway)	Hallway at Classrooms 201 and 202	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1340	2	B134001-2	2	H30	Circulation (Hallway)	Hallway at Classrooms 201 and 202	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1340	2	B134001-2	2	H30	Circulation (Hallway)	Hallway at Classrooms 201 and 202	yes	Covebase	Concrete	Brown	Chipping	25	0.04	Negative
1340	2	B134001-2	2			Custodial Closet near Women's Restroom	no	W1	CMU	White	None	0	0.04	Negative
1340	2	B134001-2	2			Custodial Closet near Women's Restroom	no	Door Frame	Metal	White/Brown	Chipping	8	0.05	Negative
1340	2	B134001-2	2			Custodial Closet near Women's Restroom	no	W2	CMU	White	None	0	0.05	Negative
1340	2	B134001-2	2			Custodial Closet near Women's Restroom	no	W3	CMU	White	None	0	0.02	Negative
1340	2	B134001-2	2			Custodial Closet near Women's Restroom	no	W4	CMU	White	None	0	0.17	Negative
1340	2	B134001-2	2			Custodial Closet near Women's Restroom	no	Duct Work	Metal	White	Flaking	8	0.18	Negative
1340	2	B134001-2	2			Custodial Closet near Women's Restroom	no	Ceiling	Concrete	White	None	0	0.03	Negative
1340	2	B134001-2	2			Custodial Closet near Women's Restroom	no	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1340	2	B134001-2	2	S25	Stairs	Stairwell by Men's and Women's Restrooms	yes	W1	CMU	White	Chipping/Flaking	3	0.14	Negative
1340	2	B134001-2	2	S25	Stairs	Stairwell by Men's and Women's Restrooms	yes	Radiator Cover	Metal	Brown	Chipping	1	0.28	Negative
1340	2	B134001-2	2	S25	Stairs	Stairwell by Men's and Women's Restrooms	yes	W2	CMU	White	Flaking	2	0.07	Negative
1340	2	B134001-2	2	S25	Stairs	Stairwell by Men's and Women's Restrooms	yes	W3	CMU	White	Flaking	6	0.2	Negative
1340	2	B134001-2	2	S25	Stairs	Stairwell by Men's and Women's Restrooms	yes	W4	CMU	White	Flaking	2	0.08	Negative
1340	2	B134001-2	2	S25	Stairs	Stairwell by Men's and Women's Restrooms	yes	Ceiling	Concrete	White	Flaking	125	0.01	Negative
1340	2	B134001-2	2	S25	Stairs	Stairwell by Men's and Women's Restrooms	yes	Stair Undercarriage	Metal	White	Flaking	1	0.18	Negative
1340	2	B134001-2	2	S25	Stairs	Stairwell by Men's and Women's Restrooms	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1340	2	B134001-2	2	S25	Stairs	Stairwell by Men's and Women's Restrooms	yes	Riser	Metal	Brown	Chipping	6	0.17	Negative
1340	2	B134001-2	2	S25	Stairs	Stairwell by Men's and Women's Restrooms	yes	Stringer	Metal	Brown	Chipping	8	0.23	Negative
1340	2	B134001-2	2	S25	Stairs	Stairwell by Men's and Women's Restrooms	yes	Hand Rail	Metal	Brown	Chipping	20	0.31	Negative
1340	2	B134001-2	2	S25	Stairs	Stairwell by Men's and Women's Restrooms	yes	Covebase	Concrete	Brown	Chipping	10	0.06	Negative
1340	2	B134001-2	2		Circulation (Hallway)	Gym Rear Entrance	yes	W1	CMU	White	None	0	0.15	Negative
1340	2	B134001-2	2		Circulation (Hallway)	Gym Rear Entrance	yes	W1	Concrete	White	Chipping	1	0.01	Negative
1340	2	B134001-2	2		Circulation (Hallway)	Gym Rear Entrance	yes	W2	CMU	White	Chipping	2	0.11	Negative
1340	2	B134001-2	2		Circulation (Hallway)	Gym Rear Entrance	yes	Radiator Cover	Metal	Brown	Chipping	4	0.2	Negative
1340	2	B134001-2	2		Circulation (Hallway)	Gym Rear Entrance	yes	W3	CMU	White	Chipping	3	0.21	Negative
1340	2	B134001-2	2		Circulation (Hallway)	Gym Rear Entrance	yes	W4	CMU	White	None	0	0.14	Negative
1340	2	B134001-2	2		Circulation (Hallway)	Gym Rear Entrance	yes	Ceiling	Concrete	White	Flaking	2	0.01	Negative
1340	2	B134001-2	2		Circulation (Hallway)	Gym Rear Entrance	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1340	2	B134001-2	2		Circulation (Hallway)	Gym Rear Entrance	yes	Covebase	Concrete	Brown	Chipping	4	0.13	Negative
1340	2	B134001-2	2		Circulation (Hallway)	Gym Rear Entrance	yes	Riser	Concrete	Brown	Chipping	6	0.05	Negative
1340	2	B134001-2	2		Circulation (Hallway)	Gym Rear Entrance	yes	Stringer	Metal	Brown	Chipping	4	0.12	Negative
1340	2	B134001-2	2		Circulation (Hallway)	Gym Rear Entrance	yes	Hand Rail	Metal	Brown	Chipping	10	0.4	Negative
1340	2	B134001-2	2	S26	Stairs	Stairwell by Classroom 201/Rear Gym	yes	W1	CMU	White	Flaking	3	0.09	Negative
1340	2	B134001-2	2	S26	Stairs	Stairwell by Classroom 201/Rear Gym	yes	W2	CMU	White	None	0	0.11	Negative
1340	2	B134001-2	2	S26	Stairs	Stairwell by Classroom 201/Rear Gym	yes	Radiator Cover	Metal	Brown	Chipping	2	0.18	Negative
1340	2	B134001-2	2	S26	Stairs	Stairwell by Classroom 201/Rear Gym	yes	Pipe Outer Cover	Metal	White/Brown	Chipping	2	0.18	Negative
1340	2	B134001-2	2	S26	Stairs	Stairwell by Classroom 201/Rear Gym	yes	W3	CMU	White	Chipping/Flaking	7	0.24	Negative
1340	2	B134001-2	2	S26	Stairs	Stairwell by Classroom 201/Rear Gym	yes	Radiator Cover	Metal	Brown	Chipping	1	0.25	Negative
1340	2	B134001-2	2	S26	Stairs	Stairwell by Classroom 201/Rear Gym	yes	Pipe Outer Cover	Metal	White	Flaking	3	0.17	Negative
1340	2	B134001-2	2	S26	Stairs	Stairwell by Classroom 201/Rear Gym	yes	W4	CMU	White	None	0	0.16	Negative
1340	2	B134001-2	2	S26	Stairs	Stairwell by Classroom 201/Rear Gym	yes	Ceiling	Concrete	White	None	0	0.09	Negative
1340	2	B134001-2	2	S26	Stairs	Stairwell by Classroom 201/Rear Gym	yes	Stair Undercarriage	Concrete	White	Flaking	1	0.19	Negative
1340	2	B134001-2	2	S26	Stairs	Stairwell by Classroom 201/Rear Gym	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1340	2	B134001-2	2	S26	Stairs	Stairwell by Classroom 201/Rear Gym	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1340	2	B134001-2	2	S26	Stairs	Stairwell by Classroom 201/Rear Gym	yes	Riser	Metal	Brown	Chipping	10	0.33	Negative
1340	2	B134001-2	2	S26	Stairs	Stairwell by Classroom 201/Rear Gym	yes	Stringer	Metal	Brown	Chipping	6	0.35	Negative
1340	2	B134001-2	2	S26	Stairs	Stairwell by Classroom 201/Rear Gym	yes	Hand Rail	Metal	Brown	Chipping	20	0.33	Negative
1340	2	B134001-2	2	S26	Stairs	Stairwell by Classroom 201/Rear Gym	yes	Covebase	Concrete	Brown	Chipping	6	0.2	Negative
1340	2	B134001-2	3	300	Restrooms, Staff - Male	Men's Restroom in the Stairwell	yes	W1	CMU	White	None	0	0.06	Negative
1340	2	B134001-2	3	300	Restrooms, Staff - Male	Men's Restroom in the Stairwell	yes	Door Frame	Metal	White	Chipping	2	0.02	Negative
1340	2	B134001-2	3	300	Restrooms, Staff - Male	Men's Restroom in the Stairwell	yes	W2	CMU	White	None	0	0.07	Negative
1340	2	B134001-2	3	300	Restrooms, Staff - Male	Men's Restroom in the Stairwell	yes	Pipe Outer Cover	Metal	Brown	Flaking	5	0.19	Negative
1340	2	B134001-2	3	300	Restrooms, Staff - Male	Men's Restroom in the Stairwell	yes	W3	CMU	White	None	0	0.06	Negative

1340	2	B134001-2	3	300	Restrooms, Staff - Male	Men's Restroom in the Stairwell	yes	W4	CMU	White	None	0	0.04	Negative
1340	2	B134001-2	3	300	Restrooms, Staff - Male	Men's Restroom in the Stairwell	yes	Access Panel	Metal	White	Flaking	1	0	Negative
1340	2	B134001-2	3	300	Restrooms, Staff - Male	Men's Restroom in the Stairwell	yes	Ceiling	Concrete	White	Flaking	5	0.16	Negative
1340	2	B134001-2	3	300	Restrooms, Staff - Male	Men's Restroom in the Stairwell	yes	Floor	Terrazzo	N/A	N/A	N/A	N/A	N/A
1340	2	B134001-2	3	300A	Administrative Office	Physical Education Teacher's Office at the Stairwell	yes	W1	CMU	White	Partially Inaccessible	0	0.01	Negative
1340	2	B134001-2	3	300A	Administrative Office	Physical Education Teacher's Office at the Stairwell	yes	Door	Metal	Brown	Chipping	2	0.02	Negative
1340	2	B134001-2	3	300A	Administrative Office	Physical Education Teacher's Office at the Stairwell	yes	Door Frame	Metal	Brown	Chipping	2	0.03	Negative
1340	2	B134001-2	3	300A	Administrative Office	Physical Education Teacher's Office at the Stairwell	yes	W2	CMU	White	None	0	0	Negative
1340	2	B134001-2	3	300A	Administrative Office	Physical Education Teacher's Office at the Stairwell	yes	W3	CMU	White	None	0	0	Negative
1340	2	B134001-2	3	300A	Administrative Office	Physical Education Teacher's Office at the Stairwell	yes	W4	CMU	White	None	0	0	Negative
1340	2	B134001-2	3	300A	Administrative Office	Physical Education Teacher's Office at the Stairwell	yes	Radiator Cover	Metal	Brown	Chipping	2	0.11	Negative
1340	2	B134001-2	3	300A	Administrative Office	Physical Education Teacher's Office at the Stairwell	yes	Ceiling	Concrete	White	None	0	0.02	Negative
1340	2	B134001-2	3	300A	Administrative Office	Physical Education Teacher's Office at the Stairwell	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1340	2	B134001-2	3	300A	Administrative Office	Physical Education Teacher's Office at the Stairwell	yes	Covebase	Concrete	Black	Friction	20	0.02	Negative
1340	2	B134001-2	3	300B	Restrooms, Staff - Female	Women's Restroom in the Hallway	yes	W1	CMU	White	None	0	0.03	Negative
1340	2	B134001-2	3	300B	Restrooms, Staff - Female	Women's Restroom in the Hallway	yes	W2	CMU	White	None	0	0.07	Negative
1340	2	B134001-2	3	300B	Restrooms, Staff - Female	Women's Restroom in the Hallway	yes	W3	CMU	White	None	0	0.04	Negative
1340	2	B134001-2	3	300B	Restrooms, Staff - Female	Women's Restroom in the Hallway	yes	W4	CMU	White	Flaking	3	0.04	Negative
1340	2	B134001-2	3	300B	Restrooms, Staff - Female	Women's Restroom in the Hallway	yes	Ceiling	Concrete	White	None	0	0.09	Negative
1340	2	B134001-2	3	300B	Restrooms, Staff - Female	Women's Restroom in the Hallway	yes	Floor	Terrazzo	N/A	N/A	N/A	N/A	N/A
1340	2	B134001-2	3	301/302	IMC (Library)	Library	yes	W1	CMU	White	Partially Inaccessible	0	0.06	Negative
1340	2	B134001-2	3	301/302	IMC (Library)	Library	yes	W2	CMU	White	None	0	0	Negative
1340	2	B134001-2	3	301/302	IMC (Library)	Library	yes	W3	CMU	White	Partially Inaccessible	0	0.04	Negative
1340	2	B134001-2	3	301/302	IMC (Library)	Library	yes	Univent	Metal	Brown	Chipping	3	0.04	Negative
1340	2	B134001-2	3	301/302	IMC (Library)	Library	yes	Column	Concrete	White	None	0	0.04	Negative
1340	2	B134001-2	3	301/302	IMC (Library)	Library	yes	W4	CMU	White	Partially Inaccessible	0	0	Negative
1340	2	B134001-2	3	301/302	IMC (Library)	Library	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1340	2	B134001-2	3	301/302	IMC (Library)	Library	yes	Beams	Concrete	White	None	0	0.01	Negative
1340	2	B134001-2	3	301/302	IMC (Library)	Library	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1340	2	B134001-2	3	M1	Mechanical Room	Air Handler Room in the Hallway across from Library - Room 301	no	W1	CMU	Green	None	0	0	Negative
1340	2	B134001-2	3	M1	Mechanical Room	Air Handler Room in the Hallway across from Library - Room 301	no	Door Frame	Metal	Green	Chipping	4	0.06	Negative
1340	2	B134001-2	3	M1	Mechanical Room	Air Handler Room in the Hallway across from Library - Room 301	no	W2	CMU	Green	Partially Inaccessible	0	0	Negative
1340	2	B134001-2	3	M1	Mechanical Room	Air Handler Room in the Hallway across from Library - Room 301	no	W3	CMU	Green	Partially Inaccessible	0	0	Negative
1340	2	B134001-2	3	M1	Mechanical Room	Air Handler Room in the Hallway across from Library - Room 301	no	W4	CMU	Green	Partially Inaccessible	0	0	Negative
1340	2	B134001-2	3	M1	Mechanical Room	Air Handler Room in the Hallway across from Library - Room 301	no	Ceiling	Concrete	Green	None	0	0.08	Negative
1340	2	B134001-2	3	M1	Mechanical Room	Air Handler Room in the Hallway across from Library - Room 301	no	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1340	2	B134001-2	3	M2	Mechanical Room	Air Handler Room in the Hallway across from Library - Room 302	no	W1	CMU	Green	None	0	0	Negative
1340	2	B134001-2	3	M2	Mechanical Room	Air Handler Room in the Hallway across from Library - Room 302	no	Door Frame	Metal	Green	Chipping	6	0.06	Negative
1340	2	B134001-2	3	M2	Mechanical Room	Air Handler Room in the Hallway across from Library - Room 302	no	W2	CMU	Green	Partially Inaccessible	0	0	Negative
1340	2	B134001-2	3	M2	Mechanical Room	Air Handler Room in the Hallway across from Library - Room 302	no	W3	CMU	Green	Partially Inaccessible	0	0	Negative
1340	2	B134001-2	3	M2	Mechanical Room	Air Handler Room in the Hallway across from Library - Room 302	no	W4	CMU	Green	Partially Inaccessible	0	0	Negative
1340	2	B134001-2	3	M2	Mechanical Room	Air Handler Room in the Hallway across from Library - Room 302	no	Ceiling	Concrete	Green	Flaking	6	0	Negative
1340	2	B134001-2	3	M2	Mechanical Room	Air Handler Room in the Hallway across from Library - Room 302	no	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1340	2	B134001-2	3	SC-1	Storage	Center Book Storage in the Hallway across from Library	yes	W1	CMU	White	None	0	0.03	Negative

1340	2	B134001-2	3	SC-1	Storage	Center Book Storage in the Hallway across from Library	yes	W2	CMU	White	None	0	0	Negative
1340	2	B134001-2	3	SC-1	Storage	Center Book Storage in the Hallway across from Library	yes	W3	CMU	White	None	0	0.03	Negative
1340	2	B134001-2	3	SC-1	Storage	Center Book Storage in the Hallway across from Library	yes	W4	CMU	White	None	0	0.02	Negative
1340	2	B134001-2	3	SC-1	Storage	Center Book Storage in the Hallway across from Library	yes	Ceiling	Concrete	White	Flaking	4	0.07	Negative
1340	2	B134001-2	3	SC-1	Storage	Center Book Storage in the Hallway across from Library	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1340	2	B134001-2	3		Storage	Left Book Storage in the Hallway across from Library	yes	W1	CMU	White	None	0	0	Negative
1340	2	B134001-2	3		Storage	Left Book Storage in the Hallway across from Library	yes	W2	CMU	White	None	0	0.02	Negative
1340	2	B134001-2	3		Storage	Left Book Storage in the Hallway across from Library	yes	W3	CMU	White	None	0	0.03	Negative
1340	2	B134001-2	3		Storage	Left Book Storage in the Hallway across from Library	yes	W4	CMU	White	None	0	0.06	Negative
1340	2	B134001-2	3		Storage	Left Book Storage in the Hallway across from Library	yes	Ceiling	Concrete	White	Flaking	4	0.07	Negative
1340	2	B134001-2	3		Storage	Left Book Storage in the Hallway across from Library	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1340	2	B134001-2	3		Storage	Right Book Storage in the Hallway across from Library	yes	W1	CMU	White	None	0	0	Negative
1340	2	B134001-2	3		Storage	Right Book Storage in the Hallway across from Library	yes	W2	CMU	White	None	0	0.02	Negative
1340	2	B134001-2	3		Storage	Right Book Storage in the Hallway across from Library	yes	W3	CMU	White	None	0	0.01	Negative
1340	2	B134001-2	3		Storage	Right Book Storage in the Hallway across from Library	yes	W4	CMU	White	None	0	0.04	Negative
1340	2	B134001-2	3		Storage	Right Book Storage in the Hallway across from Library	yes	Ceiling	Concrete	White	Flaking	4	0.09	Negative
1340	2	B134001-2	3		Storage	Right Book Storage in the Hallway across from Library	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1340	2	B134001-2	3	H313	Circulation (Hallway)	Hallway at the Library	yes	W1	CMU	White	None	0	0.1	Negative
1340	2	B134001-2	3	H313	Circulation (Hallway)	Hallway at the Library	yes	Door	Metal	Brown	Chipping	1	0	Negative
1340	2	B134001-2	3	H313	Circulation (Hallway)	Hallway at the Library	yes	Door Frame	Metal	Brown	Chipping	5	0.07	Negative
1340	2	B134001-2	3	H313	Circulation (Hallway)	Hallway at the Library	yes	W2	CMU	White	Flaking	15	0.05	Negative
1340	2	B134001-2	3	H313	Circulation (Hallway)	Hallway at the Library	yes	Univent	Metal	Brown	Chipping	2	0.02	Negative
1340	2	B134001-2	3	H313	Circulation (Hallway)	Hallway at the Library	yes	W3	CMU	White	Flaking	1	0.12	Negative
1340	2	B134001-2	3	H313	Circulation (Hallway)	Hallway at the Library	yes	Door	Metal	Brown	Chipping	2	0	Negative
1340	2	B134001-2	3	H313	Circulation (Hallway)	Hallway at the Library	yes	Door Frame	Metal	Brown	Chipping	4	0.02	Negative
1340	2	B134001-2	3	H313	Circulation (Hallway)	Hallway at the Library	yes	W4	CMU	White	Flaking	5	0.06	Negative
1340	2	B134001-2	3	H313	Circulation (Hallway)	Hallway at the Library	yes	Door	Wood	Brown	Chipping	15	0	Negative
1340	2	B134001-2	3	H313	Circulation (Hallway)	Hallway at the Library	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1340	2	B134001-2	3	H313	Circulation (Hallway)	Hallway at the Library	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1340	2	B134001-2	3	H313	Circulation (Hallway)	Hallway at the Library	yes	Covebase	Concrete	Brown	Chipping	40	0.01	Negative
1340	2	B134001-2	3	S36	Stairs	Stairwell at the End of the Library	yes	W1	CMU	White	Flaking	75	0.05	Negative
1340	2	B134001-2	3	S36	Stairs	Stairwell at the End of the Library	yes	W2	CMU	White	Flaking	100	0.03	Negative
1340	2	B134001-2	3	S36	Stairs	Stairwell at the End of the Library	yes	W3	CMU	White	Flaking	150	0.04	Negative
1340	2	B134001-2	3	S36	Stairs	Stairwell at the End of the Library	yes	Radiator Cover	Metal	Brown	Chipping	1	0.15	Negative
1340	2	B134001-2	3	S36	Stairs	Stairwell at the End of the Library	yes	W4	CMU	White	Flaking	50	0.07	Negative
1340	2	B134001-2	3	S36	Stairs	Stairwell at the End of the Library	yes	Ceiling	Concrete	White	None	0	0.08	Negative
1340	2	B134001-2	3	S36	Stairs	Stairwell at the End of the Library	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1340	2	B134001-2	3	S36	Stairs	Stairwell at the End of the Library	yes	Riser	Metal	Brown	Chipping	6	0.17	Negative
1340	2	B134001-2	3	S36	Stairs	Stairwell at the End of the Library	yes	Stringer	Metal	Brown	Chipping	6	0.3	Negative
1340	2	B134001-2	3	S36	Stairs	Stairwell at the End of the Library	yes	Hand Rail	Metal	Brown	Chipping	12	0.24	Negative
1340	2	B134001-2	3	S36	Stairs	Stairwell at the End of the Library	yes	Baseboard	Metal	Brown	Chipping	10	0.17	Negative
1340	2	B134001-2	3			Custodial Closet near Library	no	W1	CMU	White	None	0	0.03	Negative
1340	2	B134001-2	3			Custodial Closet near Library	no	W2	CMU	White	None	0	0.03	Negative
1340	2	B134001-2	3			Custodial Closet near Library	no	W3	CMU	White	Partially Inaccessible	0	0.03	Negative
1340	2	B134001-2	3			Custodial Closet near Library	no	W4	CMU	White	None	0	0.08	Negative
1340	2	B134001-2	3			Custodial Closet near Library	no	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A
1340	2	B134001-2	3			Custodial Closet near Library	no	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1340	2	B134001-2	3	S35	Stairs	Stairwell outside Men's Restroom and Gym Office	yes	W1	CMU	White	Flaking	2	0.05	Negative
1340	2	B134001-2	3	S35	Stairs	Stairwell outside Men's Restroom and Gym Office	yes	W2	CMU	White	Flaking	5	0.12	Negative
1340	2	B134001-2	3	S35	Stairs	Stairwell outside Men's Restroom and Gym Office	yes	W3	CMU	White	Flaking	5	0	Negative
1340	2	B134001-2	3	S35	Stairs	Stairwell outside Men's Restroom and Gym Office	yes	W4	CMU	White	None	0	0.09	Negative
1340	2	B134001-2	3	S35	Stairs	Stairwell outside Men's Restroom and Gym Office	yes	Ceiling	Concrete	White	Flaking	125	0.15	Negative
1340	2	B134001-2	3	S35	Stairs	Stairwell outside Men's Restroom and Gym Office	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1340	2	B134001-2	3	S35	Stairs	Stairwell outside Men's Restroom and Gym Office	yes	Covebase	Concrete	Brown	Chipping	2	0.01	Negative
1340	2	B134001-2	3	S35	Stairs	Stairwell outside Men's Restroom and Gym Office	yes	Riser	Metal	Brown	Chipping	2	0.11	Negative
1340	2	B134001-2	3	S35	Stairs	Stairwell outside Men's Restroom and Gym Office	yes	Stringer	Metal	Brown	Chipping	2	0.24	Negative
1340	2	B134001-2	3	S35	Stairs	Stairwell outside Men's Restroom and Gym Office	yes	Hand Rail	Metal	Brown	Chipping	10	0.27	Negative
1340	3	B134002-1	1	H112	Circulation (Hallway)	Front Hallway/Foyer beside Classroom L2	yes	W1	Sheetrock	White	None	0	0.22	Negative
1340	3	B134002-1	1	H112	Circulation (Hallway)	Front Hallway/Foyer beside Classroom L2	yes	Door	Metal	Blue	Chipping	2	0.03	Negative
1340	3	B134002-1	1	H112	Circulation (Hallway)	Front Hallway/Foyer beside Classroom L2	yes	Door Frame	Metal	Blue	Chipping	8	0.28	Negative
1340	3	B134002-1	1	H112	Circulation (Hallway)	Front Hallway/Foyer beside Classroom L2	yes	W2	Sheetrock	White	None	0	0.04	Negative

1340	3	B134002-1	1	H112	Circulation (Hallway)	Front Hallway/Foyer beside Classroom L2	yes	W2	Metal	White	None	0	0.06	Negative
1340	3	B134002-1	1	H112	Circulation (Hallway)	Front Hallway/Foyer beside Classroom L2	yes	Door	Metal	Blue	Chipping	6	0.01	Negative
1340	3	B134002-1	1	H112	Circulation (Hallway)	Front Hallway/Foyer beside Classroom L2	yes	Door Frame	Metal	Blue	Chipping	6	0.1	Negative
1340	3	B134002-1	1	H112	Circulation (Hallway)	Front Hallway/Foyer beside Classroom L2	yes	W3	Metal	White	Flaking	2	0.17	Negative
1340	3	B134002-1	1	H112	Circulation (Hallway)	Front Hallway/Foyer beside Classroom L2	yes	W3	Sheetrock	White	None	0	0.01	Negative
1340	3	B134002-1	1	H112	Circulation (Hallway)	Front Hallway/Foyer beside Classroom L2	yes	W3	Concrete	Brown	Flaking	4	0.32	Negative
1340	3	B134002-1	1	H112	Circulation (Hallway)	Front Hallway/Foyer beside Classroom L2	yes	Radiator Cover	Metal	Blue	Chipping	2	0.11	Negative
1340	3	B134002-1	1	H112	Circulation (Hallway)	Front Hallway/Foyer beside Classroom L2	yes	W4	Sheetrock	White	Cracking	10	0.07	Negative
1340	3	B134002-1	1	H112	Circulation (Hallway)	Front Hallway/Foyer beside Classroom L2	yes	Ceiling	Metal	White	Flaking	2	0.11	Negative
1340	3	B134002-1	1	H112	Circulation (Hallway)	Front Hallway/Foyer beside Classroom L2	yes	Ceiling	Plaster	White	Efflorescence/Spalling	6	0.04	Negative
1340	3	B134002-1	1	H112	Circulation (Hallway)	Front Hallway/Foyer beside Classroom L2	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1340	3	B134002-1	1	H112	Circulation (Hallway)	Front Hallway/Foyer beside Classroom L2	yes	Baseboard	Wood	Brown	Chipping	2	0.28	Negative
1340	3	B134002-1	1	H112	Circulation (Hallway)	Front Hallway/Foyer beside Classroom L2	yes	Baseboard	Metal	Brown	Chipping	2	0.01	Negative
1340	3	B134002-1	1	H112	Circulation (Hallway)	Front Hallway/Foyer beside Classroom L2	yes	Riser	Concrete	Brown	Chipping	10	0.13	Negative
1340	3	B134002-1	1	H112	Circulation (Hallway)	Front Hallway/Foyer beside Classroom L2	yes	Stringer	Concrete	Brown	Chipping	2	0.22	Negative
1340	3	B134002-1	1	H112	Circulation (Hallway)	Front Hallway/Foyer beside Classroom L2	yes	Hand Rail	Metal	Gray	Chipping	10	0.2	Negative
1340	3	B134002-1	1	H113	Circulation (Hallway)	L Wing Main Hallway	yes	W1	Sheetrock	White	None	0	0.01	Negative
1340	3	B134002-1	1	H113	Circulation (Hallway)	L Wing Main Hallway	yes	Door	Metal	Blue	Chipping	8	0.08	Negative
1340	3	B134002-1	1	H113	Circulation (Hallway)	L Wing Main Hallway	yes	Door Frame	Metal	Blue	Chipping	4	0.01	Negative
1340	3	B134002-1	1	H113	Circulation (Hallway)	L Wing Main Hallway	yes	W2	Metal	White	None	0	0.01	Negative
1340	3	B134002-1	1	H113	Circulation (Hallway)	L Wing Main Hallway	yes	W2	Sheetrock	White	Flaking	2	0.06	Negative
1340	3	B134002-1	1	H113	Circulation (Hallway)	L Wing Main Hallway	yes	Door Frame	Metal	White/Blue	Chipping	3	0.02	Negative
1340	3	B134002-1	1	H113	Circulation (Hallway)	L Wing Main Hallway	yes	W3	Metal	White	None	0	0.11	Negative
1340	3	B134002-1	1	H113	Circulation (Hallway)	L Wing Main Hallway	yes	W4	Metal	White	Chipping	2	0.13	Negative
1340	3	B134002-1	1	H113	Circulation (Hallway)	L Wing Main Hallway	yes	W4	Sheetrock	White	Spalling	1	0.01	Negative
1340	3	B134002-1	1	H113	Circulation (Hallway)	L Wing Main Hallway	yes	Door Frame	Metal	Blue	Chipping	4	0.01	Negative
1340	3	B134002-1	1	H113	Circulation (Hallway)	L Wing Main Hallway	yes	Univent	Metal	Blue	Chipping	4	0.09	Negative
1340	3	B134002-1	1	H113	Circulation (Hallway)	L Wing Main Hallway	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1340	3	B134002-1	1	H113	Circulation (Hallway)	L Wing Main Hallway	yes	Ceiling	Plaster	White	Efflorescence/Spalling	6	0.04	Negative
1340	3	B134002-1	1	H113	Circulation (Hallway)	L Wing Main Hallway	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1340	3	B134002-1	1	H113	Circulation (Hallway)	L Wing Main Hallway	yes	Baseboard	Metal	Brown	Chipping	10	0.01	Negative
1340	3	B134002-1	1	L1	Primary	Classroom L1	yes	W1	Sheetrock	White	Flaking	4	0.11	Negative
1340	3	B134002-1	1	L1	Primary	Classroom L1	yes	W2	Sheetrock	White	None	0	0.01	Negative
1340	3	B134002-1	1	L1	Primary	Classroom L1	yes	W3	Sheetrock	White	Cracking	2	0.13	Negative
1340	3	B134002-1	1	L1	Primary	Classroom L1	yes	Univent	Metal	White	Chipping	2	0.06	Negative
1340	3	B134002-1	1	L1	Primary	Classroom L1	yes	Window Sill	Wood	Brown	Chipping	2	0.17	Negative
1340	3	B134002-1	1	L1	Primary	Classroom L1	yes	Window Frames	Metal	Brown	Chipping	2	0.27	Negative
1340	3	B134002-1	1	L1	Primary	Classroom L1	yes	W4	Sheetrock	Yellow	Chipping	6	0.36	Negative
1340	3	B134002-1	1	L1	Primary	Classroom L1	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1340	3	B134002-1	1	L1	Primary	Classroom L1	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1340	3	B134002-1	1	L1-A	Storage	Classroom L1 Storage	yes	W1	Sheetrock	White	Chipping	10	0.01	Negative
1340	3	B134002-1	1	L1-A	Storage	Classroom L1 Storage	yes	W2	Sheetrock	White	Chipping	2	0.06	Negative
1340	3	B134002-1	1	L1-A	Storage	Classroom L1 Storage	yes	W3	Sheetrock	White	Chipping	8	0.01	Negative
1340	3	B134002-1	1	L1-A	Storage	Classroom L1 Storage	yes	W4	Sheetrock	White	Chipping	1	0.01	Negative
1340	3	B134002-1	1	L1-A	Storage	Classroom L1 Storage	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1340	3	B134002-1	1	L1-A	Storage	Classroom L1 Storage	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1340	3	B134002-1	1	L2	Primary	Classroom L2	yes	W1	Metal	White	None	0	0.12	Negative
1340	3	B134002-1	1	L2	Primary	Classroom L2	yes	W1	Sheetrock	White	Flaking	20	0.01	Negative
1340	3	B134002-1	1	L2	Primary	Classroom L2	yes	Univent	Metal	Brown	Chipping	6	0.07	Negative
1340	3	B134002-1	1	L2	Primary	Classroom L2	yes	W2	Sheetrock	White	Partially Inaccessible	0	0.03	Negative
1340	3	B134002-1	1	L2	Primary	Classroom L2	yes	W3	Sheetrock	White	Partially Inaccessible	0	0.09	Negative
1340	3	B134002-1	1	L2	Primary	Classroom L2	yes	Window Sill	Wood	Brown	Flaking	12	0.22	Negative
1340	3	B134002-1	1	L2	Primary	Classroom L2	yes	Window Frame	Metal	Brown	Flaking	12	0.07	Negative
1340	3	B134002-1	1	L2	Primary	Classroom L2	yes	W4	Metal	White	Partially Inaccessible	0	0.13	Negative
1340	3	B134002-1	1	L2	Primary	Classroom L2	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1340	3	B134002-1	1	L2	Primary	Classroom L2	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1340	3	B134002-1	1	L3	Primary	Classroom L3	yes	W1	Sheetrock	White	Partially Inaccessible	0	0.05	Negative
1340	3	B134002-1	1	L3	Primary	Classroom L3	yes	W2	Metal	White	Partially Inaccessible	0	0.11	Negative
1340	3	B134002-1	1	L3	Primary	Classroom L3	yes	W3	Sheetrock	White	Chipping	4	0.1	Negative
1340	3	B134002-1	1	L3	Primary	Classroom L3	yes	Univent	Metal	Brown	Chipping	4	0.05	Negative
1340	3	B134002-1	1	L3	Primary	Classroom L3	yes	Window Sill	Wood	Brown	Flaking	15	0.15	Negative
1340	3	B134002-1	1	L3	Primary	Classroom L3	yes	Window Frame	Metal	Brown	Flaking	12	0.11	Negative
1340	3	B134002-1	1	L3	Primary	Classroom L3	yes	Pipe Outer Cover	Metal	White	Flaking	3	0.08	Negative
1340	3	B134002-1	1	L3	Primary	Classroom L3	yes	W4	Sheetrock	White	Staple Holes	30	0.07	Negative

1340	3	B134002-1	1	L3	Primary	Classroom L3	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1340	3	B134002-1	1	L3	Primary	Classroom L3	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1340	3	B134002-1	1	L3	Primary	Classroom L3	yes	Baseboard	Wood	Brown	Chipping	10	0.21	Negative
1340	3	B134002-1	1	L4	Primary	Classroom L4	yes	W1	Sheetrock	White	Efflorescence/Spalling	6	0.06	Negative
1340	3	B134002-1	1	L4	Primary	Classroom L4	yes	W2	Sheetrock	Green	Partially Inaccessible	0	0.01	Negative
1340	3	B134002-1	1	L4	Primary	Classroom L4	yes	W3	Sheetrock	White	Partially Inaccessible	0	0.1	Negative
1340	3	B134002-1	1	L4	Primary	Classroom L4	yes	Univent	Metal	White	Chipping	2	0.08	Negative
1340	3	B134002-1	1	L4	Primary	Classroom L4	yes	Window Sill	Wood	Brown	Chipping	2	0.1	Negative
1340	3	B134002-1	1	L4	Primary	Classroom L4	yes	Window Frame	Metal	Brown	Chipping	2	0.1	Negative
1340	3	B134002-1	1	L4	Primary	Classroom L4	yes	Pipe Outer Cover	Metal	White	Flaking	2	0.06	Negative
1340	3	B134002-1	1	L4	Primary	Classroom L4	yes	W4	Sheetrock	White	Partially Inaccessible	0	0.03	Negative
1340	3	B134002-1	1	L4	Primary	Classroom L4	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1340	3	B134002-1	1	L4	Primary	Classroom L4	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1340	3	B134002-1	1	L5	Primary	Classroom L5	yes	W1	Sheetrock	White	Partially Inaccessible	0	0.01	Negative
1340	3	B134002-1	1	L5	Primary	Classroom L5	yes	W2	Sheetrock	White	None	0	0.01	Negative
1340	3	B134002-1	1	L5	Primary	Classroom L5	yes	W3	Sheetrock	White	Partially Inaccessible	0	0.13	Negative
1340	3	B134002-1	1	L5	Primary	Classroom L5	yes	Univent	Metal	White	Chipping	2	0.11	Negative
1340	3	B134002-1	1	L5	Primary	Classroom L5	yes	Window Sill	Wood	Brown	Chipping	2	0.11	Negative
1340	3	B134002-1	1	L5	Primary	Classroom L5	yes	Window Frame	Metal	Brown	Chipping	2	0.14	Negative
1340	3	B134002-1	1	L5	Primary	Classroom L5	yes	W4	Sheetrock	Blue	Partially Inaccessible	0	0.01	Negative
1340	3	B134002-1	1	L5	Primary	Classroom L5	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1340	3	B134002-1	1	L5	Primary	Classroom L5	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1340	3	B134002-1	1	L6	Primary	Classroom L6	yes	W1	Sheetrock	White	Efflorescence/Spalling	2	0.1	Negative
1340	3	B134002-1	1	L6	Primary	Classroom L6	yes	W2	Sheetrock	White	Chipping	5	0.03	Negative
1340	3	B134002-1	1	L6	Primary	Classroom L6	yes	W3	Sheetrock	White	None	0	0.17	Negative
1340	3	B134002-1	1	L6	Primary	Classroom L6	yes	Window Sill	Wood	Brown	Chipping	3	0.18	Negative
1340	3	B134002-1	1	L6	Primary	Classroom L6	yes	Window Frame	Metal	Brown	Chipping	2	0.16	Negative
1340	3	B134002-1	1	L6	Primary	Classroom L6	yes	W4	Sheetrock	White	None	0	0.01	Negative
1340	3	B134002-1	1	L6	Primary	Classroom L6	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1340	3	B134002-1	1	L6	Primary	Classroom L6	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1340	3	B134002-1	1	L7	Primary	Classroom L7	yes	W1	Sheetrock	White	Chipping	20	0.01	Negative
1340	3	B134002-1	1	L7	Primary	Classroom L7	yes	W2	Sheetrock	White	Chipping	12	0.01	Negative
1340	3	B134002-1	1	L7	Primary	Classroom L7	yes	W3	Sheetrock	White	None	0	0.12	Negative
1340	3	B134002-1	1	L7	Primary	Classroom L7	yes	Window Sill	Wood	Brown	Chipping	5	0.29	Negative
1340	3	B134002-1	1	L7	Primary	Classroom L7	yes	Window Frame	Metal	Brown	Flaking	6	0.21	Negative
1340	3	B134002-1	1	L7	Primary	Classroom L7	yes	Univent	Metal	Brown	Chipping	4	0.08	Negative
1340	3	B134002-1	1	L7	Primary	Classroom L7	yes	W4	Sheetrock	White	None	0	0.01	Negative
1340	3	B134002-1	1	L7	Primary	Classroom L7	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1340	3	B134002-1	1	L7	Primary	Classroom L7	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1340	3	B134002-1	1	L8	Administrative Office	Work Room next to Classroom L6	yes	W1	Metal	White	None	0	0.21	Negative
1340	3	B134002-1	1	L8	Administrative Office	Work Room next to Classroom L6	yes	W2	Metal	White	None	0	0.09	Negative
1340	3	B134002-1	1	L8	Administrative Office	Work Room next to Classroom L6	yes	W2	Sheetrock	White	None	0	0.08	Negative
1340	3	B134002-1	1	L8	Administrative Office	Work Room next to Classroom L6	yes	W3	Sheetrock	White	None	0	0.14	Negative
1340	3	B134002-1	1	L8	Administrative Office	Work Room next to Classroom L6	yes	W4	Sheetrock	White	None	0	0.01	Negative
1340	3	B134002-1	1	L8	Administrative Office	Work Room next to Classroom L6	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1340	3	B134002-1	1	L8	Administrative Office	Work Room next to Classroom L6	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1340	3	B134002-1	1	L9	Administrative Office	Office next to Classroom L6	yes	W1	Metal	White	None	0	0.17	Negative
1340	3	B134002-1	1	L9	Administrative Office	Office next to Classroom L6	yes	W2	Sheetrock	White	None	0	0.08	Negative
1340	3	B134002-1	1	L9	Administrative Office	Office next to Classroom L6	yes	W3	Sheetrock	White	Chipping	2	0.14	Negative
1340	3	B134002-1	1	L9	Administrative Office	Office next to Classroom L6	yes	W4	Sheetrock	White	None	0	0.2	Negative
1340	3	B134002-1	1	L9	Administrative Office	Office next to Classroom L6	yes	Window Sill	Wood	Brown	Chipping	2	0.29	Negative
1340	3	B134002-1	1	L9	Administrative Office	Office next to Classroom L6	yes	Window Frame	Metal	Brown	Flaking	8	0.37	Negative
1340	3	B134002-1	1	L9	Administrative Office	Office next to Classroom L6	yes	Univent	Metal	Tan	Chipping	4	0.07	Negative
1340	3	B134002-1	1	L9	Administrative Office	Office next to Classroom L6	yes	Pipe Outer Cover	Metal	White	Chipping	1	0.18	Negative
1340	3	B134002-1	1	L9	Administrative Office	Office next to Classroom L6	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1340	3	B134002-1	1	L9	Administrative Office	Office next to Classroom L6	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1340	3	B134002-1	1	L10	Circulation (Hallway)	Small Hall outside of Work Room and Office	yes	W1	Sheetrock	White	Efflorescence/Flaking	2	0.01	Negative
1340	3	B134002-1	1	L10	Circulation (Hallway)	Small Hall outside of Work Room and Office	yes	W2	Metal	White	None	0	0.14	Negative
1340	3	B134002-1	1	L10	Circulation (Hallway)	Small Hall outside of Work Room and Office	yes	W3	Sheetrock	White	Partially Inaccessible	0	0.01	Negative
1340	3	B134002-1	1	L10	Circulation (Hallway)	Small Hall outside of Work Room and Office	yes	Window Sill	Wood	Brown	Flaking	2	0.26	Negative
1340	3	B134002-1	1	L10	Circulation (Hallway)	Small Hall outside of Work Room and Office	yes	Radiator Cover	Metal	Brown	Partially Inaccessible	0	0.14	Negative
1340	3	B134002-1	1	L10	Circulation (Hallway)	Small Hall outside of Work Room and Office	yes	W4	Sheetrock	White	None	0	0.08	Negative
1340	3	B134002-1	1	L10	Circulation (Hallway)	Small Hall outside of Work Room and Office	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A

1340	3	B134002-1	1	L10	Circulation (Hallway)	Small Hall outside of Work Room and Office	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1340	3	B134002-1	1	131	Student Restrooms - Male (4-12)	Boy's Restroom at Rear Foyer	yes	W1	Metal	White	Flaking	1	0.16	Negative
1340	3	B134002-1	1	131	Student Restrooms - Male (4-12)	Boy's Restroom at Rear Foyer	yes	Door	Wood	Brown	Chipping	2	0.21	Negative
1340	3	B134002-1	1	131	Student Restrooms - Male (4-12)	Boy's Restroom at Rear Foyer	yes	Door Frame	Metal	Brown	Chipping	4	0.26	Negative
1340	3	B134002-1	1	131	Student Restrooms - Male (4-12)	Boy's Restroom at Rear Foyer	yes	W2	Metal	White	None	0	0.01	Negative
1340	3	B134002-1	1	131	Student Restrooms - Male (4-12)	Boy's Restroom at Rear Foyer	yes	W3	Sheetrock	White	None	0	0.05	Negative
1340	3	B134002-1	1	131	Student Restrooms - Male (4-12)	Boy's Restroom at Rear Foyer	yes	Window Sill	Wood	Brown	Flaking	3	0.08	Negative
1340	3	B134002-1	1	131	Student Restrooms - Male (4-12)	Boy's Restroom at Rear Foyer	yes	W4	Sheetrock	White	None	0	0.06	Negative
1340	3	B134002-1	1	131	Student Restrooms - Male (4-12)	Boy's Restroom at Rear Foyer	yes	Radiator Cover	Metal	Brown	Chipping	1	0.01	Negative
1340	3	B134002-1	1	131	Student Restrooms - Male (4-12)	Boy's Restroom at Rear Foyer	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1340	3	B134002-1	1	131	Student Restrooms - Male (4-12)	Boy's Restroom at Rear Foyer	yes	Floor	Concrete	Gray	Chipping	4	0.08	Negative
1340	3	B134002-1	1	120	Student Restrooms - Female (4-12)	Girl's Restroom at Rear Foyer	yes	W1	Metal	White	Chipping	1	0.06	Negative
1340	3	B134002-1	1	120	Student Restrooms - Female (4-12)	Girl's Restroom at Rear Foyer	yes	W1	Sheetrock	White	Flaking	2	0.09	Negative
1340	3	B134002-1	1	120	Student Restrooms - Female (4-12)	Girl's Restroom at Rear Foyer	yes	Door	Wood	Brown	Chipping	2	0.32	Negative
1340	3	B134002-1	1	120	Student Restrooms - Female (4-12)	Girl's Restroom at Rear Foyer	yes	Door Frame	Metal	Brown	Chipping	2	0.11	Negative
1340	3	B134002-1	1	120	Student Restrooms - Female (4-12)	Girl's Restroom at Rear Foyer	yes	W2	Sheetrock	White	None	0	0.1	Negative
1340	3	B134002-1	1	120	Student Restrooms - Female (4-12)	Girl's Restroom at Rear Foyer	yes	Radiator Cover	Metal	White	Chipping	2	0.08	Negative
1340	3	B134002-1	1	120	Student Restrooms - Female (4-12)	Girl's Restroom at Rear Foyer	yes	W3	Sheetrock	White	None	0	0.03	Negative
1340	3	B134002-1	1	120	Student Restrooms - Female (4-12)	Girl's Restroom at Rear Foyer	yes	W4	Metal	White	Chipping	4	0.08	Negative
1340	3	B134002-1	1	120	Student Restrooms - Female (4-12)	Girl's Restroom at Rear Foyer	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1340	3	B134002-1	1	120	Student Restrooms - Female (4-12)	Girl's Restroom at Rear Foyer	yes	Floor	Concrete	Gray	Chipping	4	0.05	Negative
1340	3	B134002-1	1	L15	Restrooms, Staff - Male/Female	Staff Restroom in Rear Foyer	yes	W1	Sheetrock	Blue	None	0	0.12	Negative
1340	3	B134002-1	1	L15	Restrooms, Staff - Male/Female	Staff Restroom in Rear Foyer	yes	Door	Wood	Brown	Chipping	1	0.25	Negative
1340	3	B134002-1	1	L15	Restrooms, Staff - Male/Female	Staff Restroom in Rear Foyer	yes	Door Frame	Metal	White	Chipping	3	0.29	Negative
1340	3	B134002-1	1	L15	Restrooms, Staff - Male/Female	Staff Restroom in Rear Foyer	yes	W2	Sheetrock	Blue	Chipping	1	0.1	Negative
1340	3	B134002-1	1	L15	Restrooms, Staff - Male/Female	Staff Restroom in Rear Foyer	yes	Pipe	Metal	White	Chipping	2	0.19	Negative
1340	3	B134002-1	1	L15	Restrooms, Staff - Male/Female	Staff Restroom in Rear Foyer	yes	Pipe Outer Cover	Metal	White	Chipping	2	0.07	Negative
1340	3	B134002-1	1	L15	Restrooms, Staff - Male/Female	Staff Restroom in Rear Foyer	yes	W3	Sheetrock	Blue	Holes	2	0.16	Negative
1340	3	B134002-1	1	L15	Restrooms, Staff - Male/Female	Staff Restroom in Rear Foyer	yes	W4	Metal	Blue	Chipping	1	0.11	Negative
1340	3	B134002-1	1	L15	Restrooms, Staff - Male/Female	Staff Restroom in Rear Foyer	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1340	3	B134002-1	1	L15	Restrooms, Staff - Male/Female	Staff Restroom in Rear Foyer	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1340	3	B134002-1	1	L13	Service Closets	Custodial Closet outside Boy's Restroom	no	W1	Sheetrock	Green	Flaking	4	0.01	Negative
1340	3	B134002-1	1	L13	Service Closets	Custodial Closet outside Boy's Restroom	no	Door	Wood	Brown	Chipping	2	0.35	Negative
1340	3	B134002-1	1	L13	Service Closets	Custodial Closet outside Boy's Restroom	no	Door Frame	Metal	Green	Chipping	4	0.15	Negative
1340	3	B134002-1	1	L13	Service Closets	Custodial Closet outside Boy's Restroom	no	W2	Sheetrock	N/A	N/A	N/A	N/A	N/A
1340	3	B134002-1	1	L13	Service Closets	Custodial Closet outside Boy's Restroom	no	W3	Sheetrock	Green	Chipping/Flaking	4	0.1	Negative
1340	3	B134002-1	1	L13	Service Closets	Custodial Closet outside Boy's Restroom	no	Pipe	Metal	Green	Chipping	8	0.14	Negative
1340	3	B134002-1	1	L13	Service Closets	Custodial Closet outside Boy's Restroom	no	Box	Metal	Green	Flaking	2	0.06	Negative
1340	3	B134002-1	1	L13	Service Closets	Custodial Closet outside Boy's Restroom	no	W4	Sheetrock	Green	Partially Inaccessible	0	0.09	Negative
1340	3	B134002-1	1	L13	Service Closets	Custodial Closet outside Boy's Restroom	no	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A

1340	3	B134002-1	1	L13	Service Closets	Custodial Closet outside Boy's Restroom	no	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1340	3	B134002-1	1	H24	Circulation (Hallway)	Rear Entrance Foyer	yes	W1	Metal	White	Chipping	1	0.12	Negative
1340	3	B134002-1	1	H24	Circulation (Hallway)	Rear Entrance Foyer	yes	W2	Metal	White	None	0	0.22	Negative
1340	3	B134002-1	1	H24	Circulation (Hallway)	Rear Entrance Foyer	yes	W2	Sheetrock	White	None	0	0.06	Negative
1340	3	B134002-1	1	H24	Circulation (Hallway)	Rear Entrance Foyer	yes	W3	Sheetrock	White	None	0	0.01	Negative
1340	3	B134002-1	1	H24	Circulation (Hallway)	Rear Entrance Foyer	yes	Door	Metal	Brown	Chipping	2	0.01	Negative
1340	3	B134002-1	1	H24	Circulation (Hallway)	Rear Entrance Foyer	yes	Door Frame	Metal	Brown	Chipping	2	0.08	Negative
1340	3	B134002-1	1	H24	Circulation (Hallway)	Rear Entrance Foyer	yes	Column	Metal	Brown	Chipping	2	1.24	Positive
1340	3	B134002-1	1	H24	Circulation (Hallway)	Rear Entrance Foyer	yes	W4	Metal	White	None	0	0.2	Negative
1340	3	B134002-1	1	H24	Circulation (Hallway)	Rear Entrance Foyer	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1340	3	B134002-1	1	H24	Circulation (Hallway)	Rear Entrance Foyer	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1340	1	B134001-1	4	TR	Mechanical Room	Tank Room	no	W1	Plaster	N/A	N/A	N/A	N/A	N/A
1340	1	B134001-1	4	TR	Mechanical Room	Tank Room	no	W2	Plaster	N/A	N/A	N/A	N/A	N/A
1340	1	B134001-1	4	TR	Mechanical Room	Tank Room	no	W3	Plaster	N/A	N/A	N/A	N/A	N/A
1340	1	B134001-1	4	TR	Mechanical Room	Tank Room	no	Door	Metal	Brown	Chipping	4	0.01	Negative
1340	1	B134001-1	4	TR	Mechanical Room	Tank Room	no	Door Frame	Metal	Brown	Chipping	2	0.12	Negative
1340	1	B134001-1	4	TR	Mechanical Room	Tank Room	no	W4	Plaster	N/A	N/A	N/A	N/A	N/A
1340	1	B134001-1	4	TR	Mechanical Room	Tank Room	no	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A
1340	1	B134001-1	4	TR	Mechanical Room	Tank Room	no	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1340	1	B134001-1	4	TR	Mechanical Room	Tank Room	no	Tank	Metal	Black	Chipping	20	0.33	Negative
1340	1	B134001-1	4	TR	Mechanical Room	Tank Room	no	Tank Frame	Metal	Black	Chipping	12	2.58	Positive
1340	1	B134001-1	4	TR	Mechanical Room	Tank Room	no	Platform	Metal	Black	Chipping	4	0.18	Negative
1340	1	B134001-1	4	TR	Mechanical Room	Tank Room	no	Hand Rail	Metal	Black	Chipping	10	0.49	Negative
1340	1	B134001-1	4	TR	Mechanical Room	Tank Room	no	Tread	Metal	Black	Friction	20	0.92	Positive
1340	1	B134001-1	4	TR	Mechanical Room	Tank Room	no	Stringer	Metal	Black	Chipping	20	3.41	Positive
1340	1	B134001-1	AT	MA	Attic	Main Attic- Accessed via Fouth Floor Stairwell A to Tank Room (stairwell along 47th and Locust Streets)	no	W1	Brick	N/A	N/A	N/A	N/A	N/A
1340	1	B134001-1	AT	MA	Attic	Main Attic- Accessed via Fouth Floor Stairwell A to Tank Room (stairwell along 47th and Locust Streets)	no	W2	Brick	N/A	N/A	N/A	N/A	N/A
1340	1	B134001-1	AT	MA	Attic	Main Attic- Accessed via Fouth Floor Stairwell A to Tank Room (stairwell along 47th and Locust Streets)	no	W3	Brick	N/A	N/A	N/A	N/A	N/A
1340	1	B134001-1	AT	MA	Attic	Main Attic- Accessed via Fouth Floor Stairwell A to Tank Room (stairwell along 47th and Locust Streets)	no	W4	Brick	N/A	N/A	N/A	N/A	N/A
1340	1	B134001-1	AT	MA	Attic	Main Attic- Accessed via Fouth Floor Stairwell A to Tank Room (stairwell along 47th and Locust Streets)	no	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A
1340	1	B134001-1	AT	MA	Attic	Main Attic- Accessed via Fouth Floor Stairwell A to Tank Room (stairwell along 47th and Locust Streets)	no	Floor	Plaster	N/A	N/A	N/A	N/A	N/A
1340	2	B134001-1	CS	C	Crawlspace	Crawlspace below the Addition (below Element 2)	no	W1	No Access	No Access	No Access	No Access	No Access	No Access
1340	2	B134001-1	CS	C	Crawlspace	Crawlspace below the Addition (below Element 2)	no	W2	No Access	No Access	No Access	No Access	No Access	No Access
1340	2	B134001-1	CS	C	Crawlspace	Crawlspace below the Addition (below Element 2)	no	W3	No Access	No Access	No Access	No Access	No Access	No Access
1340	2	B134001-1	CS	C	Crawlspace	Crawlspace below the Addition (below Element 2)	no	W4	No Access	No Access	No Access	No Access	No Access	No Access
1340	2	B134001-1	CS	C	Crawlspace	Crawlspace below the Addition (below Element 2)	no	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1340	2	B134001-1	CS	C	Crawlspace	Crawlspace below the Addition (below Element 2)	no	Floor	No Access	No Access	No Access	No Access	No Access	No Access