

		School District of Philadelphia																	
		Lead Safe Certification Assessment Report										Inspection Dates: December 2020 and January 2021							
		Longstreth Elementary School										ULCS# 1350							
Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (y/n)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes
1	1	100	Cafeteria	Yes	W1	CMU	Blue	None	0	0	Negative	None	0		No	No			
1	1	100	Cafeteria	Yes	Table Cubbies	Metal	Blue	Chipping	12	0	Negative	None	0		No	No		Cafeteria table holding cubbies	
1	1	100	Cafeteria	Yes	Door	Metal	Brown	Chipping	4	0	Negative	None	0		No	No		Main Entrance Doors	
1	1	100	Cafeteria	Yes	Door Frame	Metal	Brown	Chipping	8	0	Negative	None	0		No	No		Main Entrance Doors	
1	1	100	Cafeteria	Yes	W2	CMU	Blue	None	0	0	Negative	None	0		No	No			
1	1	100	Cafeteria	Yes	Table Cubbies	Metal	Blue	Chipping	12	0	Negative	None	0		No	No		Cafeteria table holding cubbies	
1	1	100	Cafeteria	Yes	Door Frame	Metal	Brown	Chipping	2	0	Negative	None	0		No	No		100C Storage Door (wood door)	
1	1	100	Cafeteria	Yes	W3	CMU	Blue	None	0	0	Negative	None	0		No	No			
1	1	100	Cafeteria	Yes	Partition Folding Wall	Metal	Blue	Chipping	15	0	Negative	None	0		No	No		To Auditorium	
1	1	100	Cafeteria	Yes	Door Frame	Metal	Brown	Chipping	8	0.27	Negative	None	0		No	No		Left Exit Door (wood door)	
1	1	100	Cafeteria	Yes	Door Frame	Metal	Brown	Chipping	10	0	Negative	None	0		No	No		Right Exit Door (wood door)	
1	1	100	Cafeteria	Yes	W4	CMU	Blue	Chipping	8	0	Negative	None	0		No	No			
1	1	100	Cafeteria	Yes	Door Frame	Metal	Brown	Chipping	12	0.02	Negative	None	0		No	No		(2) Doors	
1	1	100	Cafeteria	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	0		No	No		2' x 4' Drop Ceiling	
1	1	100	Cafeteria	Yes	Columns	Concrete	Blue	Chipping	6	0	Negative	None	0		No	No		(4) Columns	
1	1	100	Cafeteria	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0		No	No		12 x 12 VAT Tan	
1	1	100A	Staff Restroom across from Classroom 105	Yes	W1	CMU	White	None	0	0	Negative	None	0		No	No			
1	1	100A	Staff Restroom across from Classroom 105	Yes	Door Frame	Metal	Brown	Chipping	4	0	Negative	None	0		No	No		Wood Door	
1	1	100A	Staff Restroom across from Classroom 105	Yes	W2	CMU	White	None	0	0	Negative	None	0		No	No			
1	1	100A	Staff Restroom across from Classroom 105	Yes	W3	CMU	White	None	0	0	Negative	None	0		No	No			
1	1	100A	Staff Restroom across from Classroom 105	Yes	W4	CMU	White	None	0	0	Negative	None	0		No	No			
1	1	100A	Staff Restroom across from Classroom 105	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	0		No	No		2' x 4' Drop Ceiling	
1	1	100A	Staff Restroom across from Classroom 105	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0		No	No		Ceramic Tiles	
1	1	100B	Women's Restroom across from Classroom 105	Yes	W1	CMU	White	Cracking	5	0	Negative	None	0		No	No			
1	1	100B	Women's Restroom across from Classroom 105	Yes	Door Frame	Metal	Brown	Chipping	2	0	Negative	None	0		No	No		Wood Door	
1	1	100B	Women's Restroom across from Classroom 105	Yes	W2	CMU	White	Cracking	5	0	Negative	None	0		No	No			
1	1	100B	Women's Restroom across from Classroom 105	Yes	W3	CMU	White	None	0	0	Negative	None	0		No	No			
1	1	100B	Women's Restroom across from Classroom 105	Yes	W4	CMU	White	Cracking	2	0	Negative	None	0		No	No			
1	1	100B	Women's Restroom across from Classroom 105	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	0		No	No		2' x 4' Drop Ceiling	
1	1	100B	Women's Restroom across from Classroom 105	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0		No	No		Ceramic Tiles	
1	1	100C	Supply Room in Cafeteria	no	W1	CMU	White	Partially Inaccessible	N/A	0.14	Negative	None	0		No	No		Same door frame as in cafeteria side	
1	1	100C	Supply Room in Cafeteria	no	W2	CMU	White	Partially Inaccessible	N/A	0.01	Negative	None	0		No	No			
1	1	100C	Supply Room in Cafeteria	no	W3	CMU	White	Partially Inaccessible/Cracking	8	0.01	Negative	None	0		No	No			
1	1	100C	Supply Room in Cafeteria	no	W4	CMU	White	Partially Inaccessible	N/A	0.01	Negative	None	0		No	No			
1	1	100C	Supply Room in Cafeteria	no	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	0		No	No		2' x 4' Drop Ceiling	
1	1	100C	Supply Room in Cafeteria	no	Floor	Concrete	N/A	Partially Inaccessible	N/A	0	Negative	None	0		No	No		Floor appears to be Unpainted	
1	1	100D	Teacher's Dining Room	Yes	W1	CMU	Peach	None	0	0.02	Negative	None	0		No	No		Wall 1 is from Cafeteria side. Same door frame to Cafeteria was tested (see Cafeteria reading).	
1	1	100D	Teacher's Dining Room	Yes	W2	CMU	Peach	Partially Inaccessible/Chipping/Flaking	8	0.01	Negative	None	0		No	No		Damage is by the Sink.	
1	1	100D	Teacher's Dining Room	Yes	Door Frame	Metal	Brown	Chipping	2	0	Negative	None	0		No	No		Door to Kitchen Area (wood door)	
1	1	100D	Teacher's Dining Room	Yes	W3	CMU	Peach	Partially Inaccessible	N/A	0.06	Negative	None	0		No	No			
1	1	100D	Teacher's Dining Room	Yes	W4	CMU	Peach	Cracking	10	0.05	Negative	None	0		No	No			
1	1	100D	Teacher's Dining Room	Yes	Door Frame	Metal	Brown	Chipping	6	0.19	Negative	None	0		No	No		Door to Hallway (wood door)	
1	1	100D	Teacher's Dining Room	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	0		No	No		2' x 4' Drop Ceiling	
1	1	100D	Teacher's Dining Room	Yes	Columns	Concrete	White	Chipping	1	0.02	Negative	None	0		No	No		(1) Column	
1	1	100D	Teacher's Dining Room	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0		No	No		12 x 12 VAT Tan	
1	1	100E	Kitchen and Dry Storage Area	no	W1	CMU	White	Partially Inaccessible	N/A	0	Negative	None	0		No	No		Wall 1 is from Cafeteria side. Door frame to cafeteria was tested on Cafeteria side.	
1	1	100E	Kitchen and Dry Storage Area	no	W2	CMU	White	None	N/A	0	Negative	None	0		No	No			
1	1	100E	Kitchen and Dry Storage Area	no	Door Frame	Metal	Brown	Chipping	10	0.03	Negative	None	0		No	No		Door to Hallway (wood door)	
1	1	100E	Kitchen and Dry Storage Area	no	W3	CMU	White	Partially Inaccessible	N/A	0	Negative	None	0		No	No			
1	1	100E	Kitchen and Dry Storage Area	no	Pipe	Metal	White	Chipping	2	0.11	Negative	None	0		No	No			
1	1	100E	Kitchen and Dry Storage Area	no	W4	CMU	White	Partially Inaccessible	N/A	0	Negative	None	0		No	No		Door frame to Teacher's Dining Room was tested on that side.	
1	1	100E	Kitchen and Dry Storage Area	no	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	0		No	No		2' x 4' Drop Ceiling	
1	1	100E	Kitchen and Dry Storage Area	no	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0		No	No		Ceramic Tiles	
1	1	101-101D	Classroom 103	Yes	W1	CMU	White	Chipping/Cracking	12	0.01	Negative	None	0		No	No			
1	1	101-101D	Classroom 103	Yes	Door Frame	Metal	Brown	Chipping	12	0	Negative	None	0		No	No			
1	1	101-101D	Classroom 103	Yes	W2	CMU	White	Chipping/Flaking	15	0.01	Negative	None	0		No	No			
1	1	101-101D	Classroom 103	Yes	W3	CMU	White	Chipping/Flaking	8	0	Negative	None	0		No	No			
1	1	101-101D	Classroom 103	Yes	Window/Window Frame	Metal	Brown	Chipping	4	0	Negative	None	0		No	No			
1	1	101-101D	Classroom 103	Yes	W4	CMU	White	None	0	0.01	Negative	None	0		No	No			
1	1	101-101D	Classroom 103	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	0		No	No		2' x 4' Drop Ceiling	
1	1	101-101D	Classroom 103	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0		No	No		12 x 12 VAT Tan	
1	1	102	Main Office	Yes	W1	CMU	White	None	0	0.01	Negative	None	0		No	No			
1	1	102	Main Office	Yes	Window and Door Frame	Metal	Brown	Chipping	35	0.08	Negative	None	0		No	No			
1	1	102	Main Office	Yes	W2	CMU	White	None	0	0.01	Negative	None	0		No	No			
1	1	102	Main Office	Yes	Door Frame	Metal	Brown	Chipping	8	0.09	Negative	None	0		No	No		Includes two door frames (doors are wood)	
1	1	102	Main Office	Yes	Wall Plate Cover	Metal	White	Chipping	1	0.01	Negative	None	0		No	No			
1	1	102	Main Office	Yes	W3	CMU	White	Partially Inaccessible	N/A	0.05	Negative	None	0		No	No			
1	1	102	Main Office	Yes	W4	CMU	White	Cracking	12	0.02	Negative	None	0		No	No			

		School District of Philadelphia																	
		Lead Safe Certification Assessment Report										Inspection Dates: December 2020 and January 2021							
		Longstreth Elementary School										ULCS# 1350							
Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes
1	1	102	Main Office	Yes	Door Frame	Metal	Brown	Chipping	20	0.15	Negative	None	0		No	No	no		Includes three door frames (two doors are wood)
1	1	102	Main Office	Yes	Door	Metal	Brown	Chipping	2	0	Negative	None	0		No	No	no		
1	1	102	Main Office	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	0		No	No	no		2' x 4' Drop Ceiling
1	1	102	Main Office	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0		No	No	no		12 x 12 VAT Tan
1	1	102A	File Storage in Main Office	Yes	W1	CMU	Blue	Partially Inaccessible/Flaking	5	0	Negative	None	0		No	No	no		Door frame tested from Main Office side.
1	1	102A	File Storage in Main Office	Yes	W2	CMU	Blue	Partially Inaccessible/Cracking	2	0.01	Negative	None	0		No	No	no		
1	1	102A	File Storage in Main Office	Yes	Cabinet	Metal	Orange & Brown	Chipping	8	0.61	Negative	None	0		No	No	no		
1	1	102A	File Storage in Main Office	Yes	W3	CMU	Blue	Partially Inaccessible	N/A	0.02	Negative	None	0		No	No	no		
1	1	102A	File Storage in Main Office	Yes	W4	CMU	Blue	Partially Inaccessible/Cracking	10	0.06	Negative	None	0		No	No	no		
1	1	102A	File Storage in Main Office	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	0		No	No	no		2' x 4' Drop Ceiling. Unpainted Metal Deck Ceiling above Ceiling Tiles.
1	1	102A	File Storage in Main Office	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0		No	No	no		12 x 12 VAT Tan
1	1	102B	Financial Advisor's Office	Yes	W1	CMU	Blue	Cracking	1	0.02	Negative	None	0		No	No	no		Door frame tested from Main Office side.
1	1	102B	Financial Advisor's Office	Yes	W2	CMU	Blue	Chipping/Flaking/Cracking	4	0	Negative	None	0		No	No	no		
1	1	102B	Financial Advisor's Office	Yes	W3	CMU	Blue	Cracking	3	0.06	Negative	None	0		No	No	no		
1	1	102B	Financial Advisor's Office	Yes	W4	CMU	Blue	Cracking	4	0.09	Negative	None	0		No	No	no		
1	1	102B	Financial Advisor's Office	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	0		No	No	no		2' x 4' Drop Ceiling.
1	1	102B	Financial Advisor's Office	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0		No	No	no		12 x 12 VAT Tan
1	1	102C	Principal's Office	Yes	W1	CMU	White	None	0	0.02	Negative	None	0		No	No	no		
1	1	102C	Principal's Office	Yes	Door Frame	Metal	Brown	Chipping	6	0.15	Negative	None	0		No	No	no		Includes two door frames (doors are wood).
1	1	102C	Principal's Office	Yes	W2	CMU	White	Cracking	12	0.02	Negative	None	0		No	No	no		
1	1	102C	Principal's Office	Yes	W3	CMU	White	None	0	0.01	Negative	None	0		No	No	no		
1	1	102C	Principal's Office	Yes	W4	CMU	White	Cracking	5	0.01	Negative	None	0		No	No	no		Door frame tested from Main Office side.
1	1	102C	Principal's Office	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	0		No	No	no		2' x 4' Drop Ceiling.
1	1	102C	Principal's Office	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0		No	No	no		12 x 12 VAT White
1	1	104E	Principal's Office Restroom	Yes	W1	CMU	White	None	0	0	Negative	None	0		No	No	no		Door frame tested from Principal Office side.
1	1	104E	Principal's Office Restroom	Yes	W2	CMU	White	None	0	0	Negative	None	0		No	No	no		
1	1	104E	Principal's Office Restroom	Yes	W3	CMU	White	None	0	0	Negative	None	0		No	No	no		
1	1	104E	Principal's Office Restroom	Yes	W4	CMU	White	None	0	0	Negative	None	0		No	No	no		
1	1	104E	Principal's Office Restroom	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	0		No	No	no		2' x 4' Drop Ceiling.
1	1	104E	Principal's Office Restroom	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0		No	No	no		Ceramic Tiles
1	1		Principal's Office Closet	Yes	W1	Wood	Varnish	None	0	0	Negative	None	0		No	No	no		Door frame tested from Principal Office side. Wood doors to closet.
1	1		Principal's Office Closet	Yes	W2	CMU	White	None	0	0.01	Negative	None	0		No	No	no		
1	1		Principal's Office Closet	Yes	W3	CMU	White	Partially Inaccessible	N/A	0.01	Negative	None	0		No	No	no		
1	1		Principal's Office Closet	Yes	W4	CMU	White	None	0	0	Negative	None	0		No	No	no		
1	1		Principal's Office Closet	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	0		No	No	no		2' x 4' Drop Ceiling.
1	1		Principal's Office Closet	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0		No	No	no		12 x 12 VAT White
1	1	102D	Conference Room	Yes	W1	CMU	Pink	None	0	0.01	Negative	None	0		No	No	no		Wall 1 is from Hallway
1	1	102D	Conference Room	Yes	Door Frame	Metal	Brown	Chipping	4	0.2	Negative	None	0		No	No	no		Door is wood
1	1	102D	Conference Room	Yes	W2	CMU	Pink	None	0	0.01	Negative	None	0		No	No	no		
1	1	102D	Conference Room	Yes	W3	CMU	Pink	None	0	0.03	Negative	None	0		No	No	no		Door frame tested from Principal Office side
1	1	102D	Conference Room	Yes	W4	CMU	Pink	Cracking	1	0.01	Negative	None	0		No	No	no		Door frame tested from Main Office side
1	1	102D	Conference Room	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	0		No	No	no		2' x 4' Drop Ceiling.
1	1	102D	Conference Room	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0		No	No	no		12 x 12 VAT Tan
1	1		Conference Room Closet	Yes	W1	Wood	Varnish	Scrapes	2	0	Negative	None	0		No	No	no		Wood doors to closet.
1	1		Conference Room Closet	Yes	W2	CMU	White	Partially Inaccessible	N/A	0.01	Negative	None	0		No	No	no		
1	1		Conference Room Closet	Yes	W3	CMU	White	Partially Inaccessible	N/A	0	Negative	None	0		No	No	no		
1	1		Conference Room Closet	Yes	W4	CMU	White	Partially Inaccessible	N/A	0	Negative	None	0		No	No	no		
1	1		Conference Room Closet	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	0		No	No	no		2' x 4' Drop Ceiling.
1	1		Conference Room Closet	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0		No	No	no		12 x 12 VAT Tan
1	1		Custodial Closet next to Conference Room	no	W1	CMU	White	None	0	0.02	Negative	None	0		No	No	no		
1	1		Custodial Closet next to Conference Room	no	Door Frame	Metal	Brown	Chipping	4	0.14	Negative	None	0		No	No	no		Door is Wood.
1	1		Custodial Closet next to Conference Room	no	W2	CMU	White	None	0	0.01	Negative	None	0		No	No	no		
1	1		Custodial Closet next to Conference Room	no	W3	CMU	White	None	0	0.01	Negative	None	0		No	No	no		
1	1		Custodial Closet next to Conference Room	no	W4	CMU	White	Partially Inaccessible	N/A	0.01	Negative	None	0		No	No	no		
1	1		Custodial Closet next to Conference Room	no	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	0		No	No	no		2' x 4' Drop Ceiling. Unpainted metal deck ceiling above drop ceiling.
1	1		Custodial Closet next to Conference Room	no	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	None	0		No	No	no		Unpainted Floor
1	1	104	Diagnostic Center (Front Room)	Yes	W1	CMU	Blue	Cracking/Flaking/Staple Holes	5	0.02	Negative	None	0		No	No	no		Wall 1 is from Hallway
1	1	104	Diagnostic Center (Front Room)	Yes	Door Frame	Metal	Brown	Chipping	4	0.13	Negative	None	0		No	No	no		Door is Wood
1	1	104	Diagnostic Center (Front Room)	Yes	W2	CMU	Blue	Holes	8	0.01	Negative	None	0		No	No	no		
1	1	104	Diagnostic Center (Front Room)	Yes	W3	CMU	Blue	Cracking	2	0.01	Negative	None	0		No	No	no		
1	1	104	Diagnostic Center (Front Room)	Yes	Window and Door Frame	Metal	Brown	Chipping	4	0.24	Negative	None	0		No	No	no		Door is Wood
1	1	104	Diagnostic Center (Front Room)	Yes	W4	CMU	Blue	Cracking	1	0.01	Negative	None	0		No	No	no		
1	1	104	Diagnostic Center (Front Room)	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	0		No	No	no		2' x 4' Drop Ceiling.
1	1	104	Diagnostic Center (Front Room)	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0		No	No	no		12 x 12 VAT Tan
1	1	104A	Diagnostic Center (Rear Room)	Yes	W1	CMU	Blue	Cracking/Flaking	5	0.01	Negative	None	0		No	No	no		Window and door frame tested from front room side.
1	1	104A	Diagnostic Center (Rear Room)	Yes	W2	CMU	Blue	Cracking/Holes	10	0.01	Negative	None	0		No	No	no		
1	1	104A	Diagnostic Center (Rear Room)	Yes	W3	CMU	Blue	Partially Inaccessible/Chipping	6	0.01	Negative	None	0		No	No	no		

		School District of Philadelphia																	
		Lead Safe Certification Assessment Report										Inspection Dates: December 2020 and January 2021							
		Longstreth Elementary School										ULCS# 1350							
Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes
1	1	104A	Diagnostic Center (Rear Room)	Yes	Cabinet	Metal	Orange and Brown	Chipping	4	0.45	Negative	None	0		No	No	no		
1	1	104A	Diagnostic Center (Rear Room)	Yes	W4	CMU	Blue	Partially Inaccessible/Cracking	20	0.02	Negative	None	0		No	No	no		
1	1	104A	Diagnostic Center (Rear Room)	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	0		No	No	no		2' x 4' Drop Ceiling.
1	1	104A	Diagnostic Center (Rear Room)	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0		No	No	no		12 x 12 VAT Tan
1	1	105	Classroom 105	Yes	W1	CMU	White	Chipping/Flaking/Staple Holes	40	0.05	Negative	None	0		No	No	no		
1	1	105	Classroom 105	Yes	Door Frame	Metal	Brown	Chipping	12	0.16	Negative	None	0		No	No	no		Includes two door frames (doors are wood).
1	1	105	Classroom 105	Yes	W2	CMU	White	Chipping/Flaking/Staple Holes	80	0	Negative	None	0		No	No	no		
1	1	105	Classroom 105	Yes	W3	CMU	White	Chipping/Flaking/Staple Holes	60	0.01	Negative	None	0		No	No	no		
1	1	105	Classroom 105	Yes	Window/Window Frame	Metal	Brown	Chipping	2	0	Negative	None	0		No	No	no		
1	1	105	Classroom 105	Yes	W4	CMU	White	Chipping/Flaking/Staple Holes	150	0	Negative	None	0		No	No	no		
1	1	105	Classroom 105	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	0		No	No	no		2' x 4' Drop Ceiling
1	1	105	Classroom 105	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0		No	No	no		12 x 12 VAT Tan
1	1	105A	Classroom 105 Storage	Yes	W1	CMU	White	None	0	0	Negative	None	0		No	No	no		Door Frame was tested on Classroom side
1	1	105A	Classroom 105 Storage	Yes	W2	CMU	White	Chipping	2	0.01	Negative	None	0		No	No	no		
1	1	105A	Classroom 105 Storage	Yes	W3	CMU	White	Partially Inaccessible	N/A	0	Negative	None	0		No	No	no		
1	1	105A	Classroom 105 Storage	Yes	W4	CMU	White	Partially Inaccessible	N/A	0.01	Negative	None	0		No	No	no		
1	1	105A	Classroom 105 Storage	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	0		No	No	no		2' x 4' Drop Ceiling
1	1	105A	Classroom 105 Storage	Yes	Floor	Concrete	N/A	None	0	N/A	N/A	None	0		No	No	no		Unpainted Floor
1	1	106	Art Room 106	Yes	W1	CMU	White	Cracking	15	0.02	Negative	None	0		No	No	no		
1	1	106	Art Room 106	Yes	Door Frame	Metal	Brown	Chipping	4	0.2	Negative	None	0		No	No	no		
1	1	106	Art Room 106	Yes	W2	CMU	White	Chipping/Staples	4	0.01	Negative	None	0		No	No	no		
1	1	106	Art Room 106	Yes	Door Frame	Metal	Brown	Chipping	6	0.21	Negative	None	0		No	No	no		Includes two doors (doors are wood)
1	1	106	Art Room 106	Yes	W3	CMU	White	None	0	0	Negative	None	0		No	No	no		
1	1	106	Art Room 106	Yes	W4	CMU	White	Partially Inaccessible	N/A	0.02	Negative	None	0		No	No	no		
1	1	106	Art Room 106	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	0		No	No	no		2' x 4' Drop Ceiling
1	1	106	Art Room 106	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0		No	No	no		12 x 12 VAT Tan
1	1	106A	Art Room Storage Room	Yes	W1	CMU	White	Partially Inaccessible/Staples	8	0	Negative	None	0		No	No	no		Wall 1 is from Art Room side. Door frames tested from Art Room side.
1	1	106A	Art Room Storage Room	Yes	W2	CMU	White	Cracking/Staples	6	0	Negative	None	0		No	No	no		
1	1	106A	Art Room Storage Room	Yes	W3	CMU	White	Cracking/Staples	12	0.01	Negative	None	0		No	No	no		
1	1	106A	Art Room Storage Room	Yes	W4	CMU	White	Partially Inaccessible	N/A	0.04	Negative	None	0		No	No	no		
1	1	106A	Art Room Storage Room	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	0		No	No	no		2' x 4' Drop Ceiling
1	1	106A	Art Room Storage Room	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0		No	No	no		12 x 12 VAT Tan
1	1	106B	Room 108A Office next to Art Room	Yes	W1	CMU	White	Partially Inaccessible	N/A	0.01	Negative	None	0		No	No	no		
1	1	106B	Room 108A Office next to Art Room	Yes	W1	Wood	White	Partially Inaccessible	N/A	0	Negative	None	0		No	No	no		
1	1	106B	Room 108A Office next to Art Room	Yes	Door Frame	Metal	Brown	Chipping	6	0.24	Negative	None	0		No	No	no		Door is Wood
1	1	106B	Room 108A Office next to Art Room	Yes	W2	CMU	White	Holes	10	0.03	Negative	None	0		No	No	no		
1	1	106B	Room 108A Office next to Art Room	Yes	W3	CMU	White	Holes	6	0.11	Negative	None	0		No	No	no		
1	1	106B	Room 108A Office next to Art Room	Yes	Lintel	Metal	White	Flaking	3	0	Negative	None	0		No	No	no		Over door to art room storage area.
1	1	106B	Room 108A Office next to Art Room	Yes	W4	CMU	White	Holes	1	0.01	Negative	None	0		No	No	no		
1	1	106B	Room 108A Office next to Art Room	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	0		No	No	no		2' x 4' Drop Ceiling
1	1	106B	Room 108A Office next to Art Room	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0		No	No	no		12 x 12 VAT Tan
1	1	107	Classroom 107	Yes	W1	CMU	White	Chipping/Flaking/Staple Holes	75	0.02	Negative	None	0		No	No	no		
1	1	107	Classroom 107	Yes	Door Frame	Metal	Brown	Chipping	12	0.16	Negative	None	0		No	No	no		Includes two doors (doors are wood)
1	1	107	Classroom 107	Yes	Cabinets	Metal	Brown	Chipping	6	0.02	Negative	None	0		No	No	no		On Wall and with Counter Top
1	1	107	Classroom 107	Yes	W2	CMU	Green	Partially Inaccessible	N/A	0.01	Negative	None	0		No	No	no		
1	1	107	Classroom 107	Yes	W3	CMU	White	Partially Inaccessible/Cracking	3	0.03	Negative	None	0		No	No	no		
1	1	107	Classroom 107	Yes	W4	CMU	White	Partially Inaccessible/Cracking/Staple Holes	20	0.01	Negative	None	0		No	No	no		
1	1	107	Classroom 107	Yes	Door	Metal	Brown	Chipping	6	0	Negative	None	0		No	No	no		Exterior Exit Door
1	1	107	Classroom 107	Yes	Door Frame	Metal	Brown	Chipping	2	0	Negative	None	0		No	No	no		Exterior Exit Door
1	1	107	Classroom 107	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	0		No	No	no		2' x 4' Drop Ceiling
1	1	107	Classroom 107	Yes	Column	CMU	White	Chipping/Cracking	4	0	Negative	None	0		No	No	no		Two Columns
1	1	107	Classroom 107	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0		No	No	no		12 x 12 VAT Tan
1	1	107.2	Classroom 107 Restroom	Yes	W1	CMU	White	Cracking/Flaking	1	0	Negative	None	0		No	No	no		Door Frame tested on Classroom side
1	1	107.2	Classroom 107 Restroom	Yes	W2	CMU	White	None	0	0	Negative	None	0		No	No	no		
1	1	107.2	Classroom 107 Restroom	Yes	W3	CMU	White	None	0	0	Negative	None	0		No	No	no		
1	1	107.2	Classroom 107 Restroom	Yes	W4	CMU	White	Chipping/Cracking	6	0	Negative	None	0		No	No	no		
1	1	107.2	Classroom 107 Restroom	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	0		No	No	no		2' x 4' Drop Ceiling
1	1	107.2	Classroom 107 Restroom	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0		No	No	no		Ceramic Tiles
1	1	109	Classroom 109	Yes	W1	CMU	Tan	Partially Inaccessible	N/A	0.01	Negative	None	0		No	No	no		
1	1	109	Classroom 109	Yes	Book Shelves	Metal	Brown	Partially Inaccessible	N/A	0.01	Negative	None	0		No	No	no		
1	1	109	Classroom 109	Yes	Door Frame	Metal	Brown	Chipping	6	0.26	Negative	None	0		No	No	no		
1	1	109	Classroom 109	Yes	W2	CMU	Tan	Chipping/Flaking	75	0.05	Negative	None	0		No	No	no		
1	1	109	Classroom 109	Yes	Door Frame	Metal	Brown	Chipping	4	0.38	Negative	None	0		No	No	no		Restroom Door
1	1	109	Classroom 109	Yes	Cabinets	Metal	Brown	Chipping	6	0	Negative	None	0		No	No	no		On Wall and with Counter Top
1	1	109	Classroom 109	Yes	W3	CMU	Tan	Staple Holes	4	0	Negative	None	0		No	No	no		

		School District of Philadelphia																	
		Lead Safe Certification Assessment Report										Inspection Dates: December 2020 and January 2021							
		Longstreth Elementary School										ULCS# 1350							
		Name of Inspector: Jim Mongan																	
		Inspection Company: VERTEX																	
E	F	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes
1	1	109	Classroom 109	Yes	Windows/Window Frames	Metal	Brown	Chipping	4	0	Negative	None	0		No	No	no		
1	1	109	Classroom 109	Yes	W4	CMU	Tan	Partially Inaccessible/Cracking	4	0	Negative	None	0		No	No	no		
1	1	109	Classroom 109	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	0		No	No	no		2' x 4' Drop Ceiling
1	1	109	Classroom 109	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0		No	No	no		12 x 12 VAT Tan
1	1	107.3	Classroom 107/109 Storage	Yes	W1	CMU	White	Partially Inaccessible	N/A	0.01	Negative	None	0		No	No	no		
1	1	107.3	Classroom 107/109 Storage	Yes	Door Frame	Metal	Brown	Chipping	2	0.2	Negative	None	0		No	No	no		Wood Door
1	1	107.3	Classroom 107/109 Storage	Yes	W2	CMU	White	Partially Inaccessible	N/A	0.01	Negative	None	0		No	No	no		
1	1	107.3	Classroom 107/109 Storage	Yes	W3	CMU	White	Partially Inaccessible	N/A	0.02	Negative	None	0		No	No	no		
1	1	107.3	Classroom 107/109 Storage	Yes	W4	CMU	White	Partially Inaccessible	N/A	0.04	Negative	None	0		No	No	no		
1	1	107.3	Classroom 107/109 Storage	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	0		No	No	no		2' x 4' Drop Ceiling
1	1	107.3	Classroom 107/109 Storage	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0		No	No	no		12 x 12 VAT Brown
1	1	107.1	Classroom 109 Restroom	Yes	W1	CMU	White	None	0	0	Negative	None	0		No	No	no		Door Frame test from classroom side.
1	1	107.1	Classroom 109 Restroom	Yes	W2	CMU	White	None	0	0	Negative	None	0		No	No	no		
1	1	107.1	Classroom 109 Restroom	Yes	W3	CMU	White	None	0	0	Negative	None	0		No	No	no		
1	1	107.1	Classroom 109 Restroom	Yes	W4	CMU	White	Cracking/Chipping	4	0	Negative	None	0		No	No	no		
1	1	107.1	Classroom 109 Restroom	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	0		No	No	no		2' x 4' Drop Ceiling
1	1	107.1	Classroom 109 Restroom	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0		No	No	no		Ceramic Tiles
1	1	111	Classroom 111	Yes	W1	CMU	White	Chipping	2	0	Negative	None	0		No	No	no		
1	1	111	Classroom 111	Yes	Door Frame	Metal	Brown	Chipping	4	0.1	Negative	None	0		No	No	no		
1	1	111	Classroom 111	Yes	W2	CMU	White	Cracking	3	1	Positive	None	0		Prior to Repair	No	no		Confirmed with two Positive readings
1	1	111	Classroom 111	Yes	W3	CMU	White	Cracking	4	1	Positive	None	0		Prior to Repair	No	no		
1	1	111	Classroom 111	Yes	Door	Metal	Brown	Chipping	4	0	Negative	None	0		No	No	no		Exterior Exit
1	1	111	Classroom 111	Yes	Door Frame	Metal	Brown	Chipping	6	0	Negative	None	0		No	No	no		Exterior Exit
1	1	111	Classroom 111	Yes	W4	CMU	White	Partially Inaccessible/Cracking	3	1	Positive	None	0		Prior to Repair	No	no		
1	1	111	Classroom 111	Yes	Door Frame	Metal	Brown	Chipping	2	0.18	Negative	None	0		No	No	no		Restroom Door
1	1	111	Classroom 111	Yes	Cabinets	Metal	Brown	Chipping	6	0	Negative	None	0		No	No	no		On Wall and with Counter Top
1	1	111	Classroom 111	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	0		No	No	no		2' x 4' Drop Ceiling
1	1	111	Classroom 111	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0		No	No	no		12 x 12 VAT Tan
1	1	111A	Classroom 111 Restroom	Yes	W1	CMU	White	Cracking	2	0	Negative	None	0		No	No	no		Door Frame tested from Classroom side
1	1	111A	Classroom 111 Restroom	Yes	W2	CMU	White	None	0	0	Negative	None	0		No	No	no		
1	1	111A	Classroom 111 Restroom	Yes	W3	CMU	White	Cracking	5	0	Negative	None	0		No	No	no		
1	1	111A	Classroom 111 Restroom	Yes	W4	CMU	White	None	0	0	Negative	None	0		No	No	no		
1	1	111A	Classroom 111 Restroom	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	0		No	No	no		2' x 4' Drop Ceiling
1	1	111A	Classroom 111 Restroom	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0		No	No	no		Ceramic Tiles
1	1	111B	Classroom 111/113 Storage	Yes	W1	CMU	White	Partially Inaccessible	N/A	0.01	Negative	None	0		No	No	no		
1	1	111B	Classroom 111/113 Storage	Yes	Door Frame	Metal	Brown	Chipping	2	0	Negative	None	0		No	No	no		
1	1	111B	Classroom 111/113 Storage	Yes	W2	CMU	White	Partially Inaccessible	N/A	0.01	Negative	None	0		No	No	no		
1	1	111B	Classroom 111/113 Storage	Yes	W3	CMU	White	Partially Inaccessible	N/A	0.01	Negative	None	0		No	No	no		
1	1	111B	Classroom 111/113 Storage	Yes	W4	CMU	White	Partially Inaccessible	N/A	0.01	Negative	None	0		No	No	no		
1	1	111B	Classroom 111/113 Storage	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	0		No	No	no		2' x 4' Drop Ceiling
1	1	111B	Classroom 111/113 Storage	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0		No	No	no		12 x 12 VAT Tan
1	1	113	Classroom 113	Yes	W1	CMU	White	Cracking	8	1	Positive	None	0		Prior to Repair	No	no		
1	1	113	Classroom 113	Yes	Door Frame	Metal	Brown	Chipping	2	0.19	Negative	None	0		No	No	no		Includes two door frames (wood doors)
1	1	113	Classroom 113	Yes	Cabinets	Metal	Brown	Chipping	4	0	Negative	None	0		No	No	no		On Wall and with Counter Top
1	1	113	Classroom 113	Yes	W2	CMU	White	Partially Inaccessible/Chipping	1	1	Positive	None	0		Prior to Repair	No	no		
1	1	113	Classroom 113	Yes	Windows/Window Frames	Metal	Brown	Chipping	4	0	Negative	None	0		No	No	no		
1	1	113	Classroom 113	Yes	W3	CMU	White	Partially Inaccessible/Chipping	4	1	Positive	None	0		Prior to Repair	No	no		
1	1	113	Classroom 113	Yes	W4	CMU	White	None	0	0.01	Negative	None	0		No	No	no		
1	1	113	Classroom 113	Yes	Book Shelves	Metal	Brown	Chipping	4	0	Negative	None	0		No	No	no		
1	1	113	Classroom 113	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	0		No	No	no		2' x 4' Drop Ceiling
1	1	113	Classroom 113	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0		No	No	no		12 x 12 VAT Tan
1	1	113A	Classroom 113 Restroom	Yes	W1	CMU	White	Cracking	6	0	Negative	None	0		No	No	no		Door Frame tested from Clsroom side
1	1	113A	Classroom 113 Restroom	Yes	W2	CMU	White	Chipping/Flaking	4	0	Negative	None	0		No	No	no		
1	1	113A	Classroom 113 Restroom	Yes	W3	CMU	White	None	0	0	Negative	None	0		No	No	no		
1	1	113A	Classroom 113 Restroom	Yes	W4	CMU	White	None	0	0	Negative	None	0		No	No	no		
1	1	113A	Classroom 113 Restroom	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	0		No	No	no		2' x 4' Drop Ceiling
1	1	113A	Classroom 113 Restroom	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0		No	No	no		Ceramic Tiles
1	1	110	Nurse Waiting Area	Yes	W1	CMU	White	None	0	0.01	Negative	None	0		No	No	no		Wall 1 is from Hallway
1	1	110	Nurse Waiting Area	Yes	Door Frames	Metal	Brown	Chipping	4	0.17	Negative	None	0		No	No	no		Includes three door frames. Doors are wood.
1	1	110	Nurse Waiting Area	Yes	W2	CMU	White	None	0	0.01	Negative	None	0		No	No	no		
1	1	110	Nurse Waiting Area	Yes	Door Frame	Metal	Brown	Chipping	2	0.21	Negative	None	0		No	No	no		Door is wood.
1	1	110	Nurse Waiting Area	Yes	W3	CMU	White	None	0	0.01	Negative	None	0		No	No	no		
1	1	110	Nurse Waiting Area	Yes	Door Frames	Metal	Brown	Chipping	6	0.28	Negative	None	0		No	No	no		Includes two door frames. Doors are wood.
1	1	110	Nurse Waiting Area	Yes	W4	CMU	White	Cracking	1	0.03	Negative	None	0		No	No	no		
1	1	110	Nurse Waiting Area	Yes	Door Frame	Metal	Brown	Chipping	2	0.17	Negative	None	0		No	No	no		Door is wood.
1	1	110	Nurse Waiting Area	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	0		No	No	no		2' x 4' Drop Ceiling
1	1	110	Nurse Waiting Area	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0		No	No	no		12 x 12 VAT Tan
1	1	110A	Room 110 Storage	Yes	W1	CMU	White	None	0	0.02	Negative	None	0		No	No	no		Wall 1 is from Hallway
1	1	110A	Room 110 Storage	Yes	Door Frame	Metal	Brown	Chipping	2	0.25	Negative	None	0		No	No	no		Door is wood.
1	1	110A	Room 110 Storage	Yes	W2	CMU	White	Partially Inaccessible	N/A	0.01	Negative	None	0		No	No	no		
1	1	110A	Room 110 Storage	Yes	W3	CMU	White	Partially Inaccessible	N/A	0.01	Negative	None	0		No	No	no		Door frame tested from nurse waiting area.

		School District of Philadelphia																	
		Lead Safe Certification Assessment Report										Inspection Dates: December 2020 and January 2021							
		Longstreth Elementary School										ULCS# 1350							
Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes
1	1	110A	Room 110 Storage	Yes	W4	CMU	White	Partially Inaccessible	N/A	0.01	Negative	None	0		No	No	No		
1	1	110A	Room 110 Storage	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	0		No	No	No		2' x 4' Drop Ceiling
1	1	110A	Room 110 Storage	Yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	None	0		No	No	No		Unpainted concrete floor
1	1	110C	Nurse's Office	Yes	W1	CMU	White	None	0	0	Negative	None	0		No	No	No		Wall 1 is from Waiting Area. Door frame tested from Waiting Area side.
1	1	110C	Nurse's Office	Yes	W2	CMU	White	None	0	0.01	Negative	None	0		No	No	No		
1	1	110C	Nurse's Office	Yes	Door Frame	Metal	Brown	Chipping	2	0.27	Negative	None	0		No	No	No		Door is Wood
1	1	110C	Nurse's Office	Yes	W3	CMU	White	Gouges	1	0	Negative	None	0		No	No	No		
1	1	110C	Nurse's Office	Yes	Cabinet	Metal	Orange and Brown	Chipping	2	0.55	Negative	None	0		No	No	No		
1	1	110C	Nurse's Office	Yes	W4	CMU	White	None	0	0.05	Negative	None	0		No	No	No		
1	1	110C	Nurse's Office	Yes	Door Frame	Metal	Brown	Chipping	2	0.21	Negative	None	0		No	No	No		Door is Wood
1	1	110C	Nurse's Office	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	0		No	No	No		2' x 4' Drop Ceiling
1	1	110C	Nurse's Office	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0		No	No	No		12 x 12 VAT Tan
1	1	110D	Nurse Patient Exam Room	Yes	W1	CMU	White	None	0	0	Negative	None	0		No	No	No		Wall 1 is from Waiting Area. Door frame tested from Waiting Area side.
1	1	110D	Nurse Patient Exam Room	Yes	W2	CMU	White	None	0	0	Negative	None	0		No	No	No		Door frame tested from Nurse Office side.
1	1	110D	Nurse Patient Exam Room	Yes	W3	CMU	White	None	0	0	Negative	None	0		No	No	No		
	1	110D	Nurse Patient Exam Room	Yes	Cabinet	Metal	Orange and Brown	Chipping	2	0.48	Negative	None	0		No	No	No		
1	1	110D	Nurse Patient Exam Room	Yes	W4	CMU	White	None	0	0	Negative	None	0		No	No	No		
1	1	110D	Nurse Patient Exam Room	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	0		No	No	No		2' x 4' Drop Ceiling
1	1	110D	Nurse Patient Exam Room	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0		No	No	No		12 x 12 VAT Tan
1	1	110E	Nurse Area Restroom	Yes	W1	CMU	White	None	0	0	Negative	None	0		No	No	No		Door frame tested from nurse waiting area side.
1	1	110E	Nurse Area Restroom	Yes	W2	CMU	White	Holes	1	0	Negative	None	0		No	No	No		
1	1	110E	Nurse Area Restroom	Yes	W3	CMU	White	None	0	0	Negative	None	0		No	No	No		
1	1	110E	Nurse Area Restroom	Yes	W4	CMU	White	None	0	0	Negative	None	0		No	No	No		
1	1	110E	Nurse Area Restroom	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	0		No	No	No		2' x 4' Drop Ceiling
1	1	110E	Nurse Area Restroom	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0		No	No	No		Ceramic Tiles
1	1	110F	Audio Room (next to Nurse's Restroom)	Yes	W1	Fiber board	White	None	0	0.02	Negative	None	0		No	No	No		Peg Board. Door frame tested from nurse waiting area side.
1	1	110F	Audio Room (next to Nurse's Restroom)	Yes	W2	Fiber board	White	None	0	0.01	Negative	None	0		No	No	No		Peg Board
1	1	110F	Audio Room (next to Nurse's Restroom)	Yes	W3	Fiber board	White	None	0	0.02	Negative	None	0		No	No	No		Peg Board
1	1	110F	Audio Room (next to Nurse's Restroom)	Yes	W4	Fiber board	White	Dent	1	0.02	Negative	None	0		No	No	No		Peg Board
1	1	110F	Audio Room (next to Nurse's Restroom)	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	0		No	No	No		2' x 4' Drop Ceiling
1	1	110F	Audio Room (next to Nurse's Restroom)	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0		No	No	No		12 x 12 VAT Tan
1	1	110.1	Staff Restroom outside Room 110	Yes	W1	CMU	Yellow	None	0	0	Negative	None	0		No	No	No		Door frame tested from locker side.
1	1	110.1	Staff Restroom outside Room 110	Yes	W2	CMU	Yellow	None	0	0	Negative	None	0		No	No	No		
1	1	110.1	Staff Restroom outside Room 110	Yes	W3	CMU	Yellow	None	0	0	Negative	None	0		No	No	No		
1	1	110.1	Staff Restroom outside Room 110	Yes	W4	CMU	Yellow	None	0	0	Negative	None	0		No	No	No		
1	1	110.1	Staff Restroom outside Room 110	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	0		No	No	No		2' x 4' Drop Ceiling
1	1	110.1	Staff Restroom outside Room 110	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0		No	No	No		Ceramic Tiles
1	1	110.2	Locker Room for Staff Restroom	Yes	W1	CMU	White	None	0	0.02	Negative	None	0		No	No	No		
1	1	110.2	Locker Room for Staff Restroom	Yes	Door Frame	Metal	Brown	Chipping	6	0.34	Negative	None	0		No	No	No		Includes two door frames. Doors are wood.
1	1	110.2	Locker Room for Staff Restroom	Yes	W2	CMU	White	None	0	0.02	Negative	None	0		No	No	No		
1	1	110.2	Locker Room for Staff Restroom	Yes	W3	CMU	White	Gouges	7	0.05	Negative	None	0		No	No	No		
1	1	110.2	Locker Room for Staff Restroom	Yes	Lockers	Metal	Orange and Tan	Chipping	6	0.35	Negative	None	0		No	No	No		
1	1	110.2	Locker Room for Staff Restroom	Yes	W4	CMU	White	Cracking/Gouges	7	0.05	Negative	None	0		No	No	No		
1	1	110.2	Locker Room for Staff Restroom	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	0		No	No	No		2' x 4' Drop Ceiling
1	1	110.2	Locker Room for Staff Restroom	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0		No	No	No		12 x 12 VAT Tan
1	1	110B	Laundry Room next to Nurse's Office	Yes	W1	CMU	White	None	0	0	Negative	None	0		No	No	No		Wall 1 is from the Hallway
1	1	110B	Laundry Room next to Nurse's Office	Yes	Door Frame	Metal	Brown	Chipping	2	0.32	Negative	None	0		No	No	No		Door is Wood
1	1	110B	Laundry Room next to Nurse's Office	Yes	W2	CMU	White	Cracking	3	0	Negative	None	0		No	No	No		
1	1	110B	Laundry Room next to Nurse's Office	Yes	W3	CMU	White	Cracking/Chipping	3	0	Negative	None	0		No	No	No		
1	1	110B	Laundry Room next to Nurse's Office	Yes	Cabinet	Metal	Orange and Brown	Chipping	2	0.77	Positive	None	0		No	No	No		Chipping on top of drawer edges
1	1	110B	Laundry Room next to Nurse's Office	Yes	W4	CMU	White	None	0	0	Negative	None	0		No	No	No		Door frames tested from nurse area side.
1	1	110B	Laundry Room next to Nurse's Office	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	0		No	No	No		2' x 4' Drop Ceiling
1	1	110B	Laundry Room next to Nurse's Office	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0		No	No	No		12 x 12 VAT Tan
1	1	112	Boiler Room	No	W1	CMU	White	Holes	2	0.01	Negative	None	0		No	No	No		Wall 1 is along Hallway side
	1	112	Boiler Room	no	tread	Metal	Grey	None	0	7.1	Positive	None	0		No	No	No		
	1	112	Boiler Room	no	stringer	Metal	Grey	None	0	15.8	Positive	None	0		No	No	No		
1	1	112	Boiler Room	No	W2	CMU	White	Flaking	4	0	Negative	None	0		No	No	No		
1	1	112	Boiler Room	No	W3	CMU	White	Flaking	8	0.01	Negative	None	0		No	No	No		
	1	112	Boiler Room	no	pipe	Metal	Yellow	None	0	0	Negative	None	0		No	No	No		
	1	112	Boiler Room	no	pipe	Metal	Blue	None	0	0	Negative	None	0		No	No	No		
	1	112	Boiler Room	no	pipe	Metal	Orange	None	0	0	Negative	None	0		No	No	No		
	1	112	Boiler Room	no	motor	Metal	Red	None	0	0	Negative	None	0		No	No	No		
1	1	112	Boiler Room	No	W4	CMU	White	Flaking	6	0	Negative	None	0		No	No	No		
1	1	112	Boiler Room	No	Ceiling	Concrete	White	None	0	0.01	Negative	None	0		No	No	No		
1	1	112	Boiler Room	No	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	None	0		No	No	No		Concrete floor is Unpainted.
1	1	112A	Building Engineer's Office	No	W1	CMU	White	None	0	0.03	Negative	None	0		No	No	No		
	1	112A	Building Engineer's Office	no	door frame	Metal	Black	Friction	8	0.21	Negative	None	0		No	No	No		
1	1	112A	Building Engineer's Office	No	W2	CMU	White	None	0	0.05	Negative	None	0		No	No	No		
	1	112A	Building Engineer's Office	no	window	Metal	Black	Chipping	8	0	Negative	None	0		No	No	No		
1	1	112A	Building Engineer's Office	No	W3	CMU	White	None	0	0	Negative	None	0		No	No	No		

		School District of Philadelphia																	
		Lead Safe Certification Assessment Report										Inspection Dates: December 2020 and January 2021							
		Longstreth Elementary School										ULCS# 1350							
		Name of Inspector: Jim Mongan																	
		Inspection Company: VERTEX																	
E	F	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes
1	1	112A	Building Engineer's Office	No	W4	CMU	White	None	0	0	Negative	None	0		No	No	No	No	
1	1	112A	Building Engineer's Office	No	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	1	112A	Building Engineer's Office	No	Floor	Concrete	Gray	None	0	0	Negative	None	0		No	No	No	No	
1	1	110.3	Building Engineer's Office Restroom	No	W1	CMU	White	Cracking	9	0	Negative	None	0		No	No	No	No	
1	1	110.3	Building Engineer's Office Restroom	no	door frame	Metal	Black	Friction	6	0.13	Negative	None	0		No	No	No	No	
1	1	110.3	Building Engineer's Office Restroom	No	W2	CMU	White	None	0	0	Negative	None	0		No	No	No	No	
1	1	110.3	Building Engineer's Office Restroom	No	W3	CMU	White	None	0	0	Negative	None	0		No	No	No	No	
1	1	110.3	Building Engineer's Office Restroom	No	W4	CMU	White	None	0	0	Negative	None	0		No	No	No	No	
1	1	110.3	Building Engineer's Office Restroom	No	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	1	110.3	Building Engineer's Office Restroom	No	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0		No	No	No	No	
1	1	114	Equipment Storage next to Boiler Room	No	W1	CMU	Green	Chipping	3	0.01	Negative	None	0		No	No	No	No	
1	1	114	Equipment Storage next to Boiler Room	No	W2	CMU	Green	Chipping	12	0.01	Negative	None	0		No	No	No	No	
1	1	114	Equipment Storage next to Boiler Room	No	W3	CMU	Green	Chipping	7	0	Negative	None	0		No	No	No	No	
1	1	114	Equipment Storage next to Boiler Room	No	W4	CMU	Green	Chipping	2	0.02	Negative	None	0		No	No	No	No	
1	1	114	Equipment Storage next to Boiler Room	No	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	1	114	Equipment Storage next to Boiler Room	No	Floor	Concrete	N/A	None	0	N/A	N/A	None	0		No	No	No	No	
1	1	114A	Caged Storage Area	No	W1	CMU	N/A	N/A	N/A	N/A	N/A	None	0		No	No	No	No	
1	1	114A	Caged Storage Area	No	W2	CMU	Tan	None	0	N/A	N/A	None	0		No	No	No	No	
1	1	114A	Caged Storage Area	No	W3	CMU	Tan	None	0	N/A	N/A	None	0		No	No	No	No	
1	1	114A	Caged Storage Area	No	W4	CMU	Tan	None	0	N/A	N/A	None	0		No	No	No	No	
1	1	114A	Caged Storage Area	No	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	1	114A	Caged Storage Area	No	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0		No	No	No	No	
1	1	114B	Storage at the end of the Hallway by Boiler Room	No	W1	CMU	Green	holes	3	0.01	Negative	None	0		No	No	No	No	
1	1	114B	Storage at the end of the Hallway by Boiler Room	No	W2	CMU	Green	Chipping	5	0	Negative	None	0		No	No	No	No	
1	1	114B	Storage at the end of the Hallway by Boiler Room	No	W3	CMU	Green	holes	3	0.01	Negative	None	0		No	No	No	No	
1	1	114B	Storage at the end of the Hallway by Boiler Room	No	W4	N/A	N/A	N/A	N/A	N/A	N/A	None	0		No	No	No	No	
1	1	114B	Storage at the end of the Hallway by Boiler Room	No	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	1	114B	Storage at the end of the Hallway by Boiler Room	No	Floor	Concrete	N/A	N/A	0	N/A	N/A	None	0		No	No	No	No	
1	1	116	Auditorium	Yes	W1	CMU	White	None	0	N/A	N/A	None	0		No	No	No	No	wall 1 on boiler room side
1	1	116	Auditorium	Yes	W2	CMU	Orange	Flaking	14	1.1	Positive	None	0		No	No	No	No	
1	1	116	Auditorium	Yes	W3	CMU	White	None	0	0.01	Negative	None	0		No	No	No	No	
1	1	116	Auditorium	Yes	W4	Wood	Brown	None	0	0	Negative	None	0		No	No	No	No	below stage
1	1	116	Auditorium	Yes	Ceiling	Plaster	White	None	0	N/A	N/A	None	0		No	No	No	No	BE does not have ladder to reach ceiling
1	1	116	Auditorium	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0		No	No	No	No	
1	1	116 STAGE	Stage	Yes	W1	CMU	White	None	0	0.01	Negative	None	0		No	No	No	No	wall 1 is on boiler rm. hall side
1	1	116 STAGE	Stage	Yes	W2	CMU	White	None	0	0.01	Negative	None	0		No	No	No	No	
1	1	116 STAGE	Stage	Yes	W3	CMU	White	None	0	0	Negative	None	0		No	No	No	No	
1	1	116 STAGE	Stage	Yes	W4	CMU	White	None	0	0.01	Negative	None	0		No	No	No	No	
1	1	116 STAGE	Stage	Yes	Ceiling	Plaster	White	None	0	N/A	N/A	None	0		No	No	No	No	need ladder to test
1	1	116 STAGE	Stage	Yes	Floor	Wood	varnish	None	0	0.02	Negative	None	0		No	No	No	No	
1	1	115	Storage across from Room 113	No	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	Principle has key. Not on site
1	1	115	Storage across from Room 113	No	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	Principle has key. Not on site
1	1	115	Storage across from Room 113	No	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	Principle has key. Not on site
1	1	115	Storage across from Room 113	No	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	Principle has key. Not on site
1	1	115	Storage across from Room 113	No	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	Principle has key. Not on site
1	1	115	Storage across from Room 113	No	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	Principle has key. Not on site
1	1	116A	Girl's Restroom by Gym	Yes	W1	CMU	White	None	0	0	Negative	None	0		No	No	No	No	
1	1	116A	Girl's Restroom by Gym	Yes	W2	CMU	White	None	0	0	Negative	None	0		No	No	No	No	
1	1	116A	Girl's Restroom by Gym	yes	baseboard	ceramic	Black	None	0	0.8	Positive	None	0		No	No	No	No	
1	1	116A	Girl's Restroom by Gym	Yes	W3	CMU	White	None	0	0	Negative	None	0		No	No	No	No	
1	1	116A	Girl's Restroom by Gym	Yes	W4	CMU	White	None	0	0	Negative	None	0		No	No	No	No	
1	1	116A	Girl's Restroom by Gym	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	1	116A	Girl's Restroom by Gym	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0		No	No	No	No	
1	1	116B	Boy's Restroom by Gym	Yes	W1	CMU	White	None	0	0	Negative	None	0		No	No	No	No	
1	1	116B	Boy's Restroom by Gym	Yes	W2	CMU	White	None	0	0.01	Negative	None	0		No	No	No	No	
1	1	116B	Boy's Restroom by Gym	yes	baseboard	ceramic	Black	None	0	1.7	Positive	None	0		No	No	No	No	
1	1	116B	Boy's Restroom by Gym	Yes	W3	CMU	White	None	0	0	Negative	None	0		No	No	No	No	
1	1	116B	Boy's Restroom by Gym	Yes	W4	CMU	White	None	0	0	Negative	None	0		No	No	No	No	
1	1	116B	Boy's Restroom by Gym	Yes	Ceiling	Sheetrock	White	None	0	0	Negative	None	0		No	No	No	No	
1	1	116B	Boy's Restroom by Gym	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0		No	No	No	No	
1	1	117	Gym	Yes	W1	CMU	Grey	None	0	0	Negative	None	0		No	No	No	No	wall 1 is near hall restrooms
1	1	117	Gym	Yes	W2	CMU	Grey	None	0	0.02	Negative	None	0		No	No	No	No	
1	1	117	Gym	yes	column	CMU	Purple	None	0	0	Negative	None	0		No	No	No	No	
1	1	117	Gym	Yes	W3	CMU	Grey	None	0	0	Negative	None	0		No	No	No	No	
1	1	117	Gym	Yes	W4	CMU	Grey	None	0	0.01	Negative	None	0		No	No	No	No	
1	1	117	Gym	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	1	117	Gym	Yes	Floor	Wood	N/A	None	0	0	Negative	None	0		No	No	No	No	
1	1	117A	Gym Office	Yes	W1	CMU	Grey	None	0	0	Negative	None	0		No	No	No	No	
1	1	117A	Gym Office	Yes	W2	CMU	Yellow	None	0	0.02	Negative	None	0		No	No	No	No	
1	1	117A	Gym Office	yes	baseboard	ceramic	Black	None	0	0.8	Positive	None	0		No	No	No	No	
1	1	117A	Gym Office	Yes	W3	CMU	Grey	None	0	0	Negative	None	0		No	No	No	No	
1	1	117A	Gym Office	Yes	W4	CMU	Grey	None	0	0.01	Negative	None	0		No	No	No	No	
1	1	117A	Gym Office	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	1	117A	Gym Office	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0		No	No	No	No	
1	1	117A.1	Gym Office Restroom	Yes	W1	CMU	Tan	None	0	0	Negative	None	0						
1	1	117A.1	Gym Office Restroom	Yes	W2	CMU	Tan	Chipping	6	0.01	Negative	None	0						

		School District of Philadelphia																	
		Name of Inspector: Jim Mongan										Lead Safe Certification Assessment Report						Inspection Dates: December 2020 and January 2021	
		Inspection Company: VERTEX										Longstreth Elementary School						ULCS# 1350	
E	F	Space #	On-Site Room Name	Student/Teacher Occupied (y/n)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes
1	1	117A.1	Gym Office Restroom	Yes	W3	CMU	Tan	None	0	0.01	Negative	None	0						
1	1	117A.1	Gym Office Restroom	Yes	W4	CMU	Tan	Cracking	10	0	Negative	None	0						
1	1	117A.1	Gym Office Restroom	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	1	117A.1	Gym Office Restroom	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0						
1	1	117C	Boy's Locker Room Restroom	Yes	W1	CMU	White	None	0	0.01	Negative	None	0		No	No	No		
1	1	117C	Boy's Locker Room Restroom	Yes	W2	CMU	White	None	0	0	Negative	None	0		No	No	No		
1	1	117C	Boy's Locker Room Restroom	Yes	W3	CMU	White	None	0	0	Negative	None	0		No	No	No		
1	1	117C	Boy's Locker Room Restroom	Yes	W4	CMU	White	None	0	0	Negative	None	0		No	No	No		
1	1	117C	Boy's Locker Room Restroom	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	1	117C	Boy's Locker Room Restroom	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0		No	No	No		
1	1	117D	Boy's Locker Room	Yes	W1	CMU	Tan	None	0	0	Negative	None	0		No	No	No		
1	1	117D	Boy's Locker Room	Yes	W2	CMU	Tan	None	0	0.01	Negative	None	0		No	No	No		
1	1	117D	Boy's Locker Room	Yes	W3	CMU	Tan	None	0	0.01	Negative	None	0		No	No	No		
1	1	117D	Boy's Locker Room	Yes	W4	CMU	Tan	None	0	0	Negative	None	0		No	No	No		
1	1	117D	Boy's Locker Room	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	1	117D	Boy's Locker Room	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0		No	No	No		
1	1	117F	Boy's Locker Shower Room	Yes	W1	CMU	Tan	None	0	0.01	Negative	None	0		No	No	No		
1	1	117F	Boy's Locker Shower Room	Yes	W2	CMU	Tan	None	0	0	Negative	None	0		No	No	No		
1	1	117F	Boy's Locker Shower Room	Yes	W3	CMU	Tan	None	0	0	Negative	None	0		No	No	No		
1	1	117F	Boy's Locker Shower Room	Yes	W4	CMU	Tan	None	0	0	Negative	None	0		No	No	No		
1	1	117F	Boy's Locker Shower Room	Yes	Ceiling	Sheetrock	White	None	0	0	Negative	None	0		No	No	No		
1	1	117F	Boy's Locker Shower Room	Yes	Floor	Concrete	N/A	None	0	N/A	N/A	None	0		No	No	No		
1	1	117B	Gym Storage	Yes	W1	CMU	Tan	None	0	0.01	Negative	None	0		No	No	No		
1	1	117B	Gym Storage	Yes	W2	CMU	Tan	None	0	0	Negative	None	0		No	No	No		
1	1	117B	Gym Storage	Yes	W3	CMU	Tan	None	0	0	Negative	None	0		No	No	No		
1	1	117B	Gym Storage	Yes	W4	CMU	Tan	None	0	0	Negative	None	0		No	No	No		
1	1	117B	Gym Storage	Yes	Ceiling	Metal	N/A	None	0	N/A	N/A	None	0		No	No	No		
1	1	117B	Gym Storage	Yes	Floor	Wood	N/A	None	0	N/A	N/A	None	0		No	No	No		
1	1	117E	Girl's Locker Room	Yes	W1	CMU	Tan	None	0	0	Negative	None	0		No	No	No		
1	1	117E	Girl's Locker Room	Yes	W2	CMU	Tan	None	0	0	Negative	None	0		No	No	No		
1	1	117E	Girl's Locker Room	Yes	W3	CMU	Tan	None	0	0.01	Negative	None	0		No	No	No		
1	1	117E	Girl's Locker Room	Yes	W4	CMU	Tan	None	0	0	Negative	None	0		No	No	No		
1	1	117E	Girl's Locker Room	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	1	117E	Girl's Locker Room	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0		No	No	No		
1	1	117H	Girl's Locker Room Restroom	Yes	W1	CMU	Tan	None	0	0	Negative	None	0		No	No	No		
1	1	117H	Girl's Locker Room Restroom	Yes	W2	CMU	Tan	None	0	0.02	Negative	None	0		No	No	No		
1	1	117H	Girl's Locker Room Restroom	Yes	W3	CMU	Tan	None	0	0	Negative	None	0		No	No	No		
1	1	117H	Girl's Locker Room Restroom	Yes	W4	CMU	Tan	None	0	0.01	Negative	None	0		No	No	No		
1	1	117H	Girl's Locker Room Restroom	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	1	117H	Girl's Locker Room Restroom	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0		No	No	No		
1	1	117I	Girl's Locker Shower Room	Yes	W1	CMU	Tan	None	0	0.01	Negative	None	0		No	No	No		
1	1	117I	Girl's Locker Shower Room	Yes	W2	CMU	Tan	None	0	0.01	Negative	None	0		No	No	No		
1	1	117I	Girl's Locker Shower Room	Yes	W3	CMU	Tan	None	0	0	Negative	None	0		No	No	No		
1	1	117I	Girl's Locker Shower Room	Yes	W4	CMU	Tan	None	0	0	Negative	None	0		No	No	No		
1	1	117I	Girl's Locker Shower Room	Yes	Ceiling	Sheetrock	White	None	0	N/A	N/A	None	0		No	No	No		
1	1	117I	Girl's Locker Shower Room	Yes	Floor	Concrete	N/A	None	0	N/A	N/A	None	0		No	No	No		
1	1	117G	Gym Vestibule Parking Lot Side	Yes	W1	Brick	Red	None	0	0	Negative	None	0		No	No	No		
1	1	117G	Gym Vestibule Parking Lot Side	Yes	W2	Brick	Red	None	0	0	Negative	None	0		No	No	No		
1	1	117G	Gym Vestibule Parking Lot Side	Yes	W3	CMU	N/A	None	0	N/A	N/A	None	0		No	No	No		
1	1	117G	Gym Vestibule Parking Lot Side	Yes	W4	Brick	Red	None	0	0	Negative	None	0		No	No	No		
1	1	117G	Gym Vestibule Parking Lot Side	Yes	Ceiling	Concrete	N/A	None	0	N/A	N/A	None	0		No	No	No		
1	1	117G	Gym Vestibule Parking Lot Side	Yes	Floor	Concrete	N/A	None	0	N/A	N/A	None	0		No	No	No		
1	1	117J	Gym Vestibule School Yard Side	Yes	W1	Brick	Red	None	0	0	Negative	None	0		No	No	No		
1	1	117J	Gym Vestibule School Yard Side	Yes	W2	Brick	Red	None	0	0.02	Negative	None	0		No	No	No		
1	1	117J	Gym Vestibule School Yard Side	Yes	W3	CMU	N/A	None	0	N/A	N/A	None	0		No	No	No		
1	1	117J	Gym Vestibule School Yard Side	Yes	W4	Brick	Red	None	0	0	Negative	None	0		No	No	No		
1	1	117J	Gym Vestibule School Yard Side	Yes	Ceiling	Concrete	N/A	None	0	N/A	N/A	None	0		No	No	No		
1	1	117J	Gym Vestibule School Yard Side	Yes	Floor	Concrete	N/A	None	0	N/A	N/A	None	0		No	No	No		
1	1	H10	Hallway from Stage to Custodial Storage	Yes	W1	CMU	Tan	None	0	0	Negative	None	0		No	No	No		
1	1	H10	Hallway from Stage to Custodial Storage	Yes	W2	CMU	Tan	None	0	0	Negative	None	0		No	No	No		
1	1	H10	Hallway from Stage to Custodial Storage	Yes	W3	CMU	Tan	None	0	0.01	Negative	None	0		No	No	No		
1	1	H10	Hallway from Stage to Custodial Storage	Yes	W4	CMU	Tan	None	0	0	Negative	None	0		No	No	No		
1	1	H10	Hallway from Stage to Custodial Storage	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	1	H10	Hallway from Stage to Custodial Storage	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0		No	No	No		
1	1	H15	Hallway at Boiler Room	Yes	W1	CMU	Tan	None	0	0	Negative	None	0		No	No	No		
1	1	H15	Hallway at Boiler Room	Yes	W2	CMU	Tan	None	0	0.01	Negative	None	0		No	No	No		
1	1	H15	Hallway at Boiler Room	Yes	W3	CMU	Tan	None	0	0	Negative	None	0		No	No	No		
1	1	H15	Hallway at Boiler Room	Yes	W4	CMU	Tan	None	0	0	Negative	None	0		No	No	No		
1	1	H15	Hallway at Boiler Room	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	1	H15	Hallway at Boiler Room	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0		No	No	No		
1	1	H16	Hallway at Main Office	Yes	W1	CMU	Tan	None	0	0	Negative	None	0		No	No	No		
1	1	H16	Hallway at Main Office	Yes	W2	CMU	Tan	None	0	0	Negative	None	0		No	No	No		
1	1	H16	Hallway at Main Office	Yes	W3	CMU	Tan	None	0	0	Negative	None	0		No	No	No		
1	1	H16	Hallway at Main Office	Yes	W4	CMU	Tan	None	0	0	Negative	None	0		No	No	No		
1	1	H16	Hallway at Main Office	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	1	H16	Hallway at Main Office	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0		No	No	No		

		School District of Philadelphia																	
		Lead Safe Certification Assessment Report										Inspection Dates: December 2020 and January 2021							
		Longstreth Elementary School										ULCS# 1350							
		Name of Inspector: Jim Mongan																	
		Inspection Company: VERTEX																	
E	F	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes
1	1	H16A	Hallway at Main Entrance	Yes	W1	CMU	Tan	Cracking	7	0	Negative	None	0		No	No	No		
1	1	H16A	Hallway at Main Entrance	Yes	W2	CMU	Tan	None	0	0	Negative	None	0		No	No	No		
1	1	H16A	Hallway at Main Entrance	Yes	W3	CMU	Tan	None	0	0	Negative	None	0		No	No	No		
1	1	H16A	Hallway at Main Entrance	Yes	W4	CMU	Tan	None	0	0	Negative	None	0		No	No	No		
1	1	H16A	Hallway at Main Entrance	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	1	H16A	Hallway at Main Entrance	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0		No	No	No		
1	1	H17	Hallway at Classroom 105	Yes	W1	CMU	Tan	None	0	0	Negative	None	0		No	No	No		
1	1	H17	Hallway at Classroom 105	Yes	W2	CMU	Tan	None	0	0	Negative	None	0		No	No	No		
1	1	H17	Hallway at Classroom 105	Yes	W3	CMU	Tan	None	0	0	Negative	None	0		No	No	No		
1	1	H17	Hallway at Classroom 105	Yes	W4	CMU	Tan	None	0	0	Negative	None	0		No	No	No		
1	1	H17	Hallway at Classroom 105	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	1	H17	Hallway at Classroom 105	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0		No	No	No		
1	1	H18	Hallway at Classrooms 109, 111, 113	Yes	W1	CMU	Blue	None	0	0	Negative	None	0		No	No	No		
1	1	H18	Hallway at Classrooms 109, 111, 113	Yes	W2	CMU	Blue	None	0	0	Negative	None	0		No	No	No		
1	1	H18	Hallway at Classrooms 109, 111, 113	Yes	W3	CMU	Blue	None	0	0.01	Negative	None	0		No	No	No		
1	1	H18	Hallway at Classrooms 109, 111, 113	Yes	W4	CMU	Blue	None	0	0	Negative	None	0		No	No	No		
1	1	H18	Hallway at Classrooms 109, 111, 113	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	1	H18	Hallway at Classrooms 109, 111, 113	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0		No	No	No		
1	1	H19	Hallway at Right Stage Exit	Yes	W1	CMU	Tan	None	0	0	Negative	None	0		No	No	No		
1	1	H19	Hallway at Right Stage Exit	Yes	W2	CMU	Tan	None	0	0	Negative	None	0		No	No	No		
1	1	H19	Hallway at Right Stage Exit	Yes	W3	CMU	Tan	None	0	0	Negative	None	0		No	No	No		
1	1	H19	Hallway at Right Stage Exit	Yes	W4	CMU	Tan	None	0	0	Negative	None	0		No	No	No		
1	1	H19	Hallway at Right Stage Exit	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	1	H19	Hallway at Right Stage Exit	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0		No	No	No		
1	1	S11	Stairwell by Girl's Restroom near Gym	Yes	W1	CMU	Tan	None	0	0	Negative	None	0		No	No	No		
1	1	S11	Stairwell by Girl's Restroom near Gym	Yes	W2	CMU	Tan	None	0	0	Negative	None	0		No	No	No		
1	1	S11	Stairwell by Girl's Restroom near Gym	yes	tread	Concrete	Brown	None	0	0	Negative	None	0		No	No	No		
1	1	S11	Stairwell by Girl's Restroom near Gym	yes	riser	Concrete	Brown	None	0	3.6	Positive	None	0		No	No	No		
1	1	S11	Stairwell by Girl's Restroom near Gym	yes	stringer	Metal	Brown	None	0	12.9	Positive	None	0		No	No	No		
1	1	S11	Stairwell by Girl's Restroom near Gym	Yes	W3	CMU	Tan	None	0	0	Negative	None	0		No	No	No		
1	1	S11	Stairwell by Girl's Restroom near Gym	Yes	W4	CMU	Tan	None	0	0	Negative	None	0		No	No	No		
1	1	S11	Stairwell by Girl's Restroom near Gym	Yes	Ceiling	Sheetrock	White	None	0	0	Negative	None	0		No	No	No		
1	1	S11	Stairwell by Girl's Restroom near Gym	Yes	Floor	Concrete	N/A	None	0	N/A	N/A	None	0		No	No	No		
1	1	S12	Stairwell by Main Office	Yes	W1	CMU	Tan	None	0	0	Negative	None	0		No	No	No		
1	1	S12	Stairwell by Main Office	yes	stringer	Metal	Brown	None	0	9.8	Positive	None	0		No	No	No		
1	1	S12	Stairwell by Main Office	Yes	W2	CMU	Tan	None	0	0	Negative	None	0		No	No	No		
1	1	S12	Stairwell by Main Office	Yes	W3	CMU	Tan	None	0	0	Negative	None	0		No	No	No		
1	1	S12	Stairwell by Main Office	Yes	W4	CMU	Tan	None	0	0	Negative	None	0		No	No	No		
1	1	S12	Stairwell by Main Office	Yes	Ceiling	Sheetrock	White	None	0	0	Negative	None	0		No	No	No		
1	1	S12	Stairwell by Main Office	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0		No	No	No		
1	1	EL	Elevator	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	None	0						
1	1	EL	Elevator	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A	None	0						
1	1	EL	Elevator	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A	None	0						
1	1	EL	Elevator	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A	None	0						
1	1	EL	Elevator	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	0						
1	1	EL	Elevator	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0						
1	2	200	IMC/Library	Yes	W1	CMU	Orange	None	0	0.01	Negative	None	0		No	No	No		wall 1 is elevator doors
1	2	200	IMC/Library	Yes	W2	CMU	Green	None	0	0.01	Negative	None	0		No	No	No		
1	2	200	IMC/Library	yes	riser	Metal	Brown	scratches	2	4.3	Positive	None	0		No	No	No		
1	2	200	IMC/Library	yes	stringer	Metal	Brown	Chipping	10	9.7	Positive	None	0		No	No	No		
1	2	200	IMC/Library	Yes	W3	CMU	Green	None	0	0	Negative	None	0		No	No	No		
1	2	200	IMC/Library	Yes	W4	CMU	Green	None	0	0.01	Negative	None	0		No	No	No		
1	2	200	IMC/Library	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	2	200	IMC/Library	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0		No	No	No		
1	2	200A/200D	Computer Room	Yes	W1	CMU	White	None	0	0.01	Negative	None	0		No	No	No		
1	2	200A/200D	Computer Room	Yes	W2	CMU	White	None	0	0	Negative	None	0		No	No	No		
1	2	200A/200D	Computer Room	Yes	W3	CMU	White	None	0	0	Negative	None	0		No	No	No		
1	2	200A/200D	Computer Room	Yes	W4	CMU	White	None	0	0	Negative	None	0		No	No	No		
1	2	200A/200D	Computer Room	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	2	200A/200D	Computer Room	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0		No	No	No		
1	2	200B	Consortium Room in IMC	Yes	W1	CMU	White	None	0	0.01	Negative	None	0		No	No	No		
1	2	200B	Consortium Room in IMC	Yes	W2	CMU	White	None	0	0.01	Negative	None	0		No	No	No		
1	2	200B	Consortium Room in IMC	Yes	W3	CMU	White	None	0	0	Negative	None	0		No	No	No		
1	2	200B	Consortium Room in IMC	Yes	W4	CMU	White	None	0	0.01	Negative	None	0		No	No	No		
1	2	200B	Consortium Room in IMC	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	2	200B	Consortium Room in IMC	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0		No	No	No		
1	2	201	Classroom 201	Yes	W1	CMU	White	None	0	0.01	Negative	None	0		No	No	No		
1	2	201	Classroom 201	yes	cabinet	Metal	Brown	scratches	3	0.01	Negative	None	0		No	No	No		
1	2	201	Classroom 201	Yes	W2	CMU	White	None	0	0	Negative	None	0		No	No	No		
1	2	201	Classroom 201	Yes	W3	CMU	White	None	0	0.02	Negative	None	0		No	No	No		
1	2	201	Classroom 201	Yes	W4	CMU	White	None	0	0.01	Negative	None	0		No	No	No		
1	2	201	Classroom 201	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	2	201	Classroom 201	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0		No	No	No		
1	2	202	Classroom 202	Yes	W1	Sheetrock	White	Chipping	3	0.01	Negative	None	0		No	No	No		
1	2	202	Classroom 202	Yes	W2	Sheetrock	White	None	0	0	Negative	None	0		No	No	No		
1	2	202	Classroom 202	Yes	W3	Sheetrock	White	Moisture Damage	3	0	Negative	None	0		No	No	No		

		School District of Philadelphia																	
		Name of Inspector: Jim Mongan										Lead Safe Certification Assessment Report				Inspection Dates: December 2020 and January 2021			
		Inspection Company: VERTEX										Longstreth Elementary School				ULCS# 1350			
E	F	Space #	On-Site Room Name	Student/Teacher Occupied (y/n)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes
1	2	202	Classroom 202	Yes	W4	CMU	White	None	0	0.01	Negative	None	0		No	No	No	No	
1	2	202	Classroom 202	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	2	202	Classroom 202	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0		Partially Inaccessible	No	No	No	
1	2	202A	Classroom 202 Storage	Yes	W1	CMU	Blue	Partially Inaccessible	0	N/A	N/A	None	0		Partially Inaccessible	No	No	No	
1	2	202A	Classroom 202 Storage	Yes	W2	CMU	Blue	Partially Inaccessible	0	N/A	N/A	None	0		Partially Inaccessible	No	No	No	
1	2	202A	Classroom 202 Storage	Yes	W3	CMU	Blue	Partially Inaccessible	0	N/A	N/A	None	0		Partially Inaccessible	No	No	No	
1	2	202A	Classroom 202 Storage	Yes	W4	CMU	Blue	Partially Inaccessible	0	N/A	N/A	None	0		Partially Inaccessible	No	No	No	
1	2	202A	Classroom 202 Storage	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	2	202A	Classroom 202 Storage	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0		No	No	No	No	
1	2	203	Classroom 203	Yes	W1	CMU	White	None	0	0	Negative	None	0		No	No	No	No	
1	2	203	Classroom 203	Yes	door frame	Metal	Black	scratches	8	0.23	Negative	None	0		No	No	No	No	
1	2	203	Classroom 203	Yes	W2	CMU	White	None	0	0	Negative	None	0		No	No	No	No	
1	2	203	Classroom 203	Yes	W3	CMU	White	None	0	0	Negative	None	0		No	No	No	No	
1	2	203	Classroom 203	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A	None	0		No	No	No	No	particle board divider, no paint
1	2	203	Classroom 203	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	2	203	Classroom 203	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0		No	No	No	No	
1	2	204	Classroom 204	Yes	W1	Sheetrock	White	Chipping	3	0.02	Negative	None	0		No	No	No	No	
1	2	204	Classroom 204	Yes	W2	Sheetrock	White	Chipping	10	0.01	Negative	None	0		No	No	No	No	
1	2	204	Classroom 204	Yes	W3	No Access	White	None	No Access	0.01	Negative	None	0		No	No	No	No	
1	2	204	Classroom 204	Yes	W4	Sheetrock	White	Chipping	12	0	Negative	None	0		No	No	No	No	
1	2	204	Classroom 204	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	2	204	Classroom 204	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0		No	No	No	No	
1	2	205	Classroom 205	Yes	W1	CMU	White	None	0	0	Negative	None	0		No	No	No	No	
1	2	205	Classroom 205	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A	None	0		No	No	No	No	particle board divider
1	2	205	Classroom 205	Yes	W3	CMU	White	None	0	0	Negative	None	0		No	No	No	No	
1	2	205	Classroom 205	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A	None	0		No	No	No	No	particle board divider
1	2	205	Classroom 205	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	2	205	Classroom 205	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0		No	No	No	No	
1	2	206	Classroom 206	Yes	W1	Sheetrock	Purple	holes	2	0.01	Negative	None	0		No	No	No	No	
1	2	206	Classroom 206	Yes	W2	Sheetrock	Purple	Moisture Damage	3	0	Negative	None	0		No	No	No	No	
1	2	206	Classroom 206	Yes	W3	CMU	White	None	0	0	Negative	None	0		No	No	No	No	
1	2	206	Classroom 206	Yes	W4	Sheetrock	Blue	Chipping	4	0.01	Negative	None	0		No	No	No	No	
1	2	206	Classroom 206	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	2	206	Classroom 206	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0		No	No	No	No	
1	2	207	Classroom 207	Yes	W1	CMU	White	None	0	0.01	Negative	None	0		No	No	No	No	
1	2	207	Classroom 207	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A	None	0		No	No	No	No	particle board divider
1	2	207	Classroom 207	Yes	W3	CMU	White	None	0	0	Negative	None	0		No	No	No	No	
1	2	207	Classroom 207	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A	None	0		No	No	No	No	particle board divider
1	2	207	Classroom 207	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	2	207	Classroom 207	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0		No	No	No	No	
1	2	208	Classroom 208	Yes	W1	Sheetrock	White	Chipping	2	0	Negative	None	0		No	No	No	No	
1	2	208	Classroom 208	Yes	W2	Sheetrock	White	Chipping	4	0	Negative	None	0		No	No	No	No	
1	2	208	Classroom 208	Yes	W3	CMU	White	Chipping	0	0.01	Negative	None	0		No	No	No	No	
1	2	208	Classroom 208	Yes	W4	Sheetrock	White	Chipping	8	0	Negative	None	0		No	No	No	No	
1	2	208	Classroom 208	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	2	208	Classroom 208	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0		No	No	No	No	
1	2	209	Classroom 209	Yes	W1	CMU	White	None	0	0.01	Negative	None	0		No	No	No	No	
1	2	209	Classroom 209	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A	None	0		No	No	No	No	particle board divider
1	2	209	Classroom 209	Yes	W3	CMU	White	None	0	0	Negative	None	0		No	No	No	No	
1	2	209	Classroom 209	Yes	W4	CMU	White	holes	3	0	Negative	None	0		No	No	No	No	
1	2	209	Classroom 209	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	2	209	Classroom 209	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0		No	No	No	No	
1	2	210	Classroom 210	Yes	W1	Sheetrock	Blue	Chipping	2	0	Negative	None	0		No	No	No	No	
1	2	210	Classroom 210	Yes	W2	Sheetrock	Blue	holes	3	0	Negative	None	0		No	No	No	No	
1	2	210	Classroom 210	Yes	W3	CMU	White	None	0	0	Negative	None	0		No	No	No	No	
1	2	210	Classroom 210	Yes	W4	Sheetrock	Blue	Chipping	8	0.01	Negative	None	0		No	No	No	No	
1	2	210	Classroom 210	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	2	210	Classroom 210	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0		No	No	No	No	
1	2	211	Classroom 211	Yes	W1	CMU	White	None	0	0.01	Negative	None	0		No	No	No	No	
1	2	211	Classroom 211	Yes	W2	CMU	White	None	0	0	Negative	None	0		No	No	No	No	
1	2	211	Classroom 211	Yes	W3	CMU	White	None	0	0	Negative	None	0		No	No	No	No	
1	2	211	Classroom 211	Yes	W4	CMU	White	None	0	0	Negative	None	0		No	No	No	No	
1	2	211	Classroom 211	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	2	211	Classroom 211	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0		No	No	No	No	
1	2	211A	Girl's Restroom near Classroom 211	Yes	W1	CMU	White	None	0	0.01	Negative	None	0		No	No	No	No	
1	2	211A	Girl's Restroom near Classroom 211	Yes	W2	CMU	White	None	0	0	Negative	None	0		No	No	No	No	
1	2	211A	Girl's Restroom near Classroom 211	Yes	W3	CMU	White	None	0	0	Negative	None	0		No	No	No	No	
1	2	211A	Girl's Restroom near Classroom 211	Yes	W4	CMU	White	None	0	0.01	Negative	None	0		No	No	No	No	
1	2	211A	Girl's Restroom near Classroom 211	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	2	211A	Girl's Restroom near Classroom 211	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0		No	No	No	No	
1	2	211B	Boy's Restroom near Classroom 211	Yes	W1	CMU	White	None	0	0	Negative	None	0		No	No	No	No	
1	2	211B	Boy's Restroom near Classroom 211	Yes	W2	CMU	White	None	0	0	Negative	None	0		No	No	No	No	

		School District of Philadelphia																	
		Lead Safe Certification Assessment Report										Inspection Dates: December 2020 and January 2021							
		Longstreth Elementary School										ULCS# 1350							
		Inspection Company: VERTEX																	
E	F	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes
1	2	211B	Boy's Restroom near Classroom 211	Yes	W3	CMU	White	None	0	0	Negative	None	0		No	No	No		
1	2	211B	Boy's Restroom near Classroom 211	Yes	W4	CMU	White	None	0	0	Negative	None	0		No	No	No		
1	2	211B	Boy's Restroom near Classroom 211	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	2	211B	Boy's Restroom near Classroom 211	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0		No	No	No		
1	2	211C	Custodial Closet between Restrooms near Classroom 211	No	W1	N/A	N/A	N/A	N/A	N/A	N/A	None	0		No	No	No		
1	2	211C	Custodial Closet between Restrooms near Classroom 211	No	W2	CMU	White	None	0	0	Negative	None	0		No	No	No		
1	2	211C	Custodial Closet between Restrooms near Classroom 211	No	W3	CMU	White	None	0	0	Negative	None	0		No	No	No		
1	2	211C	Custodial Closet between Restrooms near Classroom 211	No	W4	CMU	White	None	0	0	Negative	None	0		No	No	No		
1	2	211C	Custodial Closet between Restrooms near Classroom 211	No	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	2	211C	Custodial Closet between Restrooms near Classroom 211	No	Floor	Concrete	N/A	N/A	0	N/A	N/A	None	0		No				
1	2	212	Classroom 212	Yes	W1	Sheetrock	White	Cracking	2	0	Negative	None	0		No	No	No		
1	2	212	Classroom 212	Yes	W2	CMU	White	None	0	0.03	Negative	None	0		No	No	No		
1	2	212	Classroom 212	Yes	W3	Sheetrock	White	None	0	0	Negative	None	0		No	No	No		
1	2	212	Classroom 212	Yes	W4	Sheetrock	White	None	0	0	Negative	None	0		No	No	No		
1	2	212	Classroom 212	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	2	212	Classroom 212	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0		No	No	No		
1	2	213/213A	Classroom 213	Yes	W1	CMU	White	None	0	0	Negative	None	0		No	No	No		
1	2	213/213A	Classroom 213	Yes	W2	CMU	White	Moisture Damage	3	0	Negative	None	0		No	No	No		
1	2	213/213A	Classroom 213	Yes	W3	CMU	White	None	0	0	Negative	None	0		No	No	No		
1	2	213/213A	Classroom 213	Yes	W4	CMU	White	None	0	0	Negative	None	0		No	No	No		
1	2	213/213A	Classroom 213	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	2	213/213A	Classroom 213	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0		No	No	No		
1	2	214/216	Weight Room	Yes	W1	CMU	White	None	0	0.01	Negative	None	0		No	No	No		
1	2	214/216	Weight Room	Yes	W2	CMU	White	None	0	0	Negative	None	0		No	No	No		
1	2	214/216	Weight Room	Yes	W3	CMU	White	None	0	0.02	Negative	None	0		No	No	No		
1	2	214/216	Weight Room	Yes	W4	CMU	White	Moisture Damage	3	0.03	Negative	None	0		No	No	No		
1	2	214/216	Weight Room	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	2	214/216	Weight Room	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0		No	No	No		
1	2	214A	Girls Restroom near Classroom 214	Yes	W1	CMU	White	None	0	0	Negative	None	0		No	No	No		
1	2	214A	Girls Restroom near Classroom 214	Yes	W2	CMU	White	None	0	0	Negative	None	0		No	No	No		
1	2	214A	Girls Restroom near Classroom 214	Yes	W3	CMU	White	None	0	0	Negative	None	0		No	No	No		
1	2	214A	Girls Restroom near Classroom 214	Yes	W4	CMU	White	None	0	0	Negative	None	0		No	No	No		
1	2	214A	Girls Restroom near Classroom 214	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No	No Access	No Access	No Access	
1	2	214A	Girls Restroom near Classroom 214	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0		No	No	No		
1	2	214B	Boy's Restroom near Classroom 214	Yes	W1	CMU	White	None	0	0	Negative	None	0		No	No	No		
1	2	214B	Boy's Restroom near Classroom 214	Yes	W2	CMU	White	None	0	0	Negative	None	0		No	No	No		
1	2	214B	Boy's Restroom near Classroom 214	Yes	W3	CMU	White	None	0	0	Negative	None	0		No	No	No		
1	2	214B	Boy's Restroom near Classroom 214	Yes	W4	CMU	White	None	0	0	Negative	None	0		No	No	No		
1	2	214B	Boy's Restroom near Classroom 214	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	2	214B	Boy's Restroom near Classroom 214	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	0	0		No	No	No		
1	2	214C	Custodial Closet between Restrooms near Classroom 214	No	W1	N/A	N/A	N/A	N/A	N/A	N/A	None	0		No	No	No		wall 1 is the door
1	2	214C	Custodial Closet between Restrooms near Classroom 214	no	door frame	Metal	Brown	scratches	4	0.23	Negative	None	0		No	No	No		
1	2	214C	Custodial Closet between Restrooms near Classroom 214	No	W2	CMU	White	None	0	0	Negative	None	0		No	No	No		
1	2	214C	Custodial Closet between Restrooms near Classroom 214	No	W3	CMU	White	None	0	0	Negative	None	0		No	No	No		
1	2	214C	Custodial Closet between Restrooms near Classroom 214	No	W4	CMU	White	None	0	0	Negative	None	0		No	No	No		
1	2	214C	Custodial Closet between Restrooms near Classroom 214	No	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	2	214C	Custodial Closet between Restrooms near Classroom 214	No	Floor	Concrete	N/A	None	0	N/A	N/A	None	0		No	No	No		
1	2	215	Office Room 215	Yes	W1	CMU	White	None	0	0	Negative	None	0		No	No	No		
1	2	215	Office Room 215	Yes	W2	CMU	White	None	0	0.02	Negative	None	0		No	No	No		
1	2	215	Office Room 215	Yes	W3	CMU	White	None	0	0.01	Negative	None	0		No	No	No		
1	2	215	Office Room 215	Yes	W4	CMU	White	None	0	0	Negative	None	0		No	No	No		
1	2	215	Office Room 215	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	2	215	Office Room 215	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0		No	No	No		
1	2	215A	Staff Restroom by Office 215	Yes	W1	CMU	White	None	0	0	Negative	None	0		No	No	No		
1	2	215A	Staff Restroom by Office 215	Yes	W2	CMU	White	None	0	0	Negative	None	0		No	No	No		
1	2	215A	Staff Restroom by Office 215	Yes	W3	CMU	White	None	0	0	Negative	None	0		No	No	No		
1	2	215A	Staff Restroom by Office 215	Yes	W4	CMU	White	None	0	0	Negative	None	0		No	No	No		
1	2	215A	Staff Restroom by Office 215	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	2	215A	Staff Restroom by Office 215	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0		No	No	No		
1	2	215B	Staff Restroom by Stair 2	Yes	W1	CMU	White	None	0	0	Negative	None	0		No	No	No		
1	2	215B	Staff Restroom by Stair 2	Yes	W2	CMU	White	None	0	0	Negative	None	0		No	No	No		
1	2	215B	Staff Restroom by Stair 2	yes	pipe chase door	Metal	Brown	scratches	1	5.3	Positive	None	0		No	No	No		
1	2	215B	Staff Restroom by Stair 2	Yes	W3	CMU	White	None	0	0	Negative	None	0		No	No	No		
1	2	215B	Staff Restroom by Stair 2	Yes	W4	CMU	White	None	0	0	Negative	None	0		No	No	No		
1	2	215B	Staff Restroom by Stair 2	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	

		School District of Philadelphia																	
		Name of Inspector: Jim Mongan										Lead Safe Certification Assessment Report						Inspection Dates: December 2020 and January 2021	
		Inspection Company: VERTEX										Longstreth Elementary School						ULCS# 1350	
Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (y/n)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes
1	2	215B	Staff Restroom by Stair 2	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0		No	No	No		
1	2	217	Air Handler Room 217	No	W1	CMU	White	None	0	0	Negative	None	0		No	No	No		
1	2	217	Air Handler Room 217	No	W2	CMU	White	None	0	0	Negative	None	0		No	No	No		
1	2	217	Air Handler Room 217	No	W3	CMU	White	None	0	0	Negative	None	0		No	No	No		
1	2	217	Air Handler Room 217	No	W4	CMU	White	None	0	0	Negative	None	0		No	No	No		
1	2	217	Air Handler Room 217	No	Ceiling	Concrete	White	None	0	0	Negative	None	0		No	No	No		
1	2	217	Air Handler Room 217	No	Floor	Concrete	N/A	None	0	N/A	N/A	None	0		No	No	No		
1	2	218	Air Handler Room 218	No	W1	CMU	White	None	0	0	Negative	None	0		No	No	No		
1	2	218	Air Handler Room 218	No	W2	CMU	White	None	0	0	Negative	None	0		No	No	No		
1	2	218	Air Handler Room 218	No	W3	CMU	White	None	0	0	Negative	None	0		No	No	No		
1	2	218	Air Handler Room 218	No	W4	CMU	White	None	0	0	Negative	None	0		No	No	No		
1	2	218	Air Handler Room 218	No	Ceiling	Concrete	White	None	0	0	Negative	None	0		No	No	No		
1	2	218	Air Handler Room 218	No	Floor	Concrete	N/A	None	0	N/A	N/A	None	0		No	No	No		
1	3	218A	Storage across from Air Handler Room 218	No	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	Principle has key. Not on site
1	3	218A	Storage across from Air Handler Room 218	No	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	Principle has key. Not on site
1	3	218A	Storage across from Air Handler Room 218	No	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	Principle has key. Not on site
1	3	218A	Storage across from Air Handler Room 218	No	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	Principle has key. Not on site
1	3	218A	Storage across from Air Handler Room 218	No	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	Principle has key. Not on site
1	3	218A	Storage across from Air Handler Room 218	No	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	Principle has key. Not on site
1	2	219	Office 219	Yes	W1	CMU	White	None	0	0.01	Negative	None	0		No	No	No		
1	2	219	Office 219	Yes	W2	CMU	White	None	0	0.01	Negative	None	0		No	No	No		
1	2	219	Office 219	Yes	W3	CMU	White	None	0	0	Negative	None	0		No	No	No		
1	2	219	Office 219	Yes	W4	CMU	White	None	0	0	Negative	None	0		No	No	No		
1	2	219	Office 219	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	2	219	Office 219	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0		No	No	No		
1	2	220	Office 220	No	W1	CMU	White	None	0	0.01	Negative	None	0		No	No	No		
1	2	220	Office 220	No	W2	CMU	White	None	0	0	Negative	None	0		No	No	No		
1	2	220	Office 220	No	W3	CMU	White	None	0	0	Negative	None	0		No	No	No		
1	2	220	Office 220	No	W4	CMU	White	None	0	0	Negative	None	0		No	No	No		
1	2	220	Office 220	No	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	2	220	Office 220	No	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0		No	No	No		
1	2	221	Storage Room 221	Yes	W1	CMU	White	None	0	0.01	Negative	None	0		No	No	No		
1	2	221	Storage Room 221	Yes	W2	CMU	White	None	0	0.01	Negative	None	0		No	No	No		
1	2	221	Storage Room 221	Yes	W3	CMU	White	None	0	0	Negative	None	0		No	No	No		
1	2	221	Storage Room 221	Yes	W4	CMU	White	None	0	0	Negative	None	0		No	No	No		
1	2	221	Storage Room 221	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	2	221	Storage Room 221	Yes	Floor	Concrete	N/A	None	0	N/A	N/A	None	0		No	No	No		
1	2	222	Storage Room 222	Yes	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	2	222	Storage Room 222	Yes	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	2	222	Storage Room 222	Yes	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	2	222	Storage Room 222	Yes	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	2	222	Storage Room 222	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	2	222	Storage Room 222	Yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	2	224	Elevator Mechanical Room	Yes	W1	CMU	White	None	0	0.01	Negative	None	0		No	No	No		
1	2	224	Elevator Mechanical Room	Yes	W2	CMU	White	None	0	0.01	Negative	None	0		No	No	No		
1	2	224	Elevator Mechanical Room	Yes	W3	CMU	White	None	0	1	Positive	None	0		No	No	No		
1	2	224	Elevator Mechanical Room	Yes	W4	CMU	White	None	0	0.03	Negative	None	0		No	No	No		
1	2	224	Elevator Mechanical Room	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	2	224	Elevator Mechanical Room	Yes	Floor	Concrete	Tan	hole, flaking	8	0	Negative	None	0		No	No	No		
1	2	H212	Hallway by Classroom 211	Yes	W1	CMU	Green	None	0	0	Negative	None	0		No	No	No		
1	2	H212	Hallway by Classroom 211	Yes	W2	CMU	Green	None	0	0	Negative	None	0		No	No	No		
1	2	H212	Hallway by Classroom 211	Yes	W3	CMU	Green	None	0	0	Negative	None	0		No	No	No		
1	2	H212	Hallway by Classroom 211	Yes	W4	CMU	Green	None	0	0	Negative	None	0		No	No	No		
1	2	H212	Hallway by Classroom 211	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	2	H212	Hallway by Classroom 211	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0		No	No	No		
1	2	H213	Hallway by Classroom 212	Yes	W1	CMU	White	None	0	0	Negative	None	0		No	No	No		
1	2	H213	Hallway by Classroom 212	Yes	W2	CMU	White	None	0	0.01	Negative	None	0		No	No	No		
1	2	H213	Hallway by Classroom 212	Yes	W3	Sheetrock	White	None	0	0	Negative	None	0		No	No	No		
1	2	H213	Hallway by Classroom 212	Yes	W4	Sheetrock	White	None	0	0	Negative	None	0		No	No	No		
1	2	H213	Hallway by Classroom 212	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	2	H213	Hallway by Classroom 212	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0		No	No	No		
1	2	H214	Hallway by Classroom 202	Yes	W1	CMU	White	None	0	0.02	Negative	None	0		No	No	No		
1	2	H214	Hallway by Classroom 202	Yes	W2	CMU	White	None	0	0.01	Negative	None	0		No	No	No		
1	2	H214	Hallway by Classroom 202	Yes	W3	Sheetrock	White	None	0	0	Negative	None	0		No	No	No		
1	2	H214	Hallway by Classroom 202	Yes	W4	Sheetrock	White	None	0	0	Negative	None	0		No	No	No		
1	2	H214	Hallway by Classroom 202	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	2	H214	Hallway by Classroom 202	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0		No	No	No		
1	2	224B	Storeroom next to Stair 3	Yes	W1	CMU	White	None	0	0	Negative	None	0		No	No	No		
1	2	224B	Storeroom next to Stair 3	Yes	W2	CMU	White	None	0	0	Negative	None	0		No	No	No		
1	2	224B	Storeroom next to Stair 3	Yes	W3	CMU	White	None	0	0	Negative	None	0		No	No	No		
1	2	224B	Storeroom next to Stair 3	Yes	W4	CMU	White	None	0	0	Negative	None	0		No	No	No		
1	2	224B	Storeroom next to Stair 3	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	2	224B	Storeroom next to Stair 3	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0		No	No	No		
1	2	H215	Hallway by Classroom 201	Yes	W1	CMU	Green	None	0	0	Negative	None	0		No	No	No		
1	2	H215	Hallway by Classroom 201	Yes	W2	CMU	Green	None	0	0	Negative	None	0		No	No	No		
1	2	H215	Hallway by Classroom 201	Yes	W3	CMU	Green	None	0	0	Negative	None	0		No	No	No		

		School District of Philadelphia																	
		Lead Safe Certification Assessment Report										Inspection Dates: December 2020 and January 2021							
		Longstreth Elementary School										ULCS# 1350							
		Name of Inspector: Jim Mongan																	
		Inspection Company: VERTEX																	
E	F	Space #	On-Site Room Name	Student/Teacher Occupied (y/n)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes
1	2	H215	Hallway by Classroom 201	Yes	W4	CMU	Green	None	0	0	Negative	None	0		No	No	No		
1	2	H215	Hallway by Classroom 201	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	2	H215	Hallway by Classroom 201	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0		No	No	No		
1	2	S21	Stairwell by Classroom 215	Yes	W1	CMU	White	None	0	0	Negative	None	0		No	No	No		
1	2	S21	Stairwell by Classroom 215	Yes	W2	CMU	White	None	0	0	Negative	None	0		No	No	No		
	2	S21	Stairwell by Classroom 215	Yes	tread	Concrete	Brown	None	0	0	Negative	None	0		No	No	No		
	2	S21	Stairwell by Classroom 215	Yes	riser	Metal	Brown	None	0	4.3	Positive	None	0		No	No	No		
	2	S21	Stairwell by Classroom 215	Yes	stringer	Metal	Brown	None	0	8.9	Positive	None	0		No	No	No		
1	2	S21	Stairwell by Classroom 215	Yes	W3	CMU	White	None	0	0	Negative	None	0		No	No	No		
1	2	S21	Stairwell by Classroom 215	Yes	W4	CMU	White	None	0	0	Negative	None	0		No	No	No		
1	2	S21	Stairwell by Classroom 215	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	2	S21	Stairwell by Classroom 215	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0		No	No	No		
1	2	S25	Stairwell by Classroom 214	Yes	W1	CMU	Tan	None	0	0	Negative	None	0		No	No	No		
1	2	S25	Stairwell by Classroom 214	Yes	W2	CMU	Tan	None	0	0	Negative	None	0		No	No	No		
1	2	S25	Stairwell by Classroom 214	Yes	W3	CMU	Tan	None	0	0	Negative	None	0		No	No	No		
1	2	S25	Stairwell by Classroom 214	Yes	W4	CMU	Tan	None	0	0.01	Negative	None	0		No	No	No		
	2	S25	Stairwell by Classroom 214	Yes	tread	Concrete	Brown	None	0	0	Negative	None	0		No	No	No		
	2	S25	Stairwell by Classroom 214	Yes	riser	Metal	Brown	None	0	4.1	Positive	None	0		No	No	No		
	2	S25	Stairwell by Classroom 214	Yes	stringer	Metal	Brown	None	0	9.4	Positive	None	0		No	No	No		
1	2	S25	Stairwell by Classroom 214	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	2	S25	Stairwell by Classroom 214	Yes	Floor	Concrete	Brown	None	0	0	Negative	None	0		No	No	No		
1	2	S22	Stairwell by Classroom 201	Yes	W1	CMU	Tan	None	0	0	Negative	None	0		No	No	No		
	2	S22	Stairwell by Classroom 201	yes	door	Metal	olive	Chipping	10	0	Negative	None	0		No	No	No		
	2	S22	Stairwell by Classroom 201	yes	door frame	Metal	olive	Chipping	8	0	Negative	None	0		No	No	No		
1	2	S22	Stairwell by Classroom 201	Yes	W2	CMU	Tan	None	0	0	Negative	None	0		No	No	No		
	2	S22	Stairwell by Classroom 201	yes	stringer	Metal	Brown	None	0	8.5	Positive	None	0		No	No	No		
1	2	S22	Stairwell by Classroom 201	Yes	W3	CMU	Tan	None	0	0	Negative	None	0		No	No	No		
1	2	S22	Stairwell by Classroom 201	Yes	W4	CMU	Tan	None	0	0	Negative	None	0		No	No	No		
1	2	S22	Stairwell by Classroom 201	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	2	S22	Stairwell by Classroom 201	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0		No	No	No		
1	3	301	Classroom 301	Yes	W1	CMU	Tan	None	0	0.01	Negative	None	0		No	No	No		
1	3	301	Classroom 301	Yes	W2	CMU	Tan	None	0	0.01	Negative	None	0		No	No	No		
1	3	301	Classroom 301	Yes	W3	CMU	Green	None	0	0.01	Negative	None	0		No	No	No		
1	3	301	Classroom 301	Yes	W4	CMU	Blue	None	0	0.01	Negative	None	0		No	No	No		
1	3	301	Classroom 301	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	3	301	Classroom 301	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0		No	No	No		
1	3	302	Classroom 302	Yes	W1	Sheetrock	Tan	peeling	4	0	Negative	None	0		Partially Inaccessible	No	no		
1	3	302	Classroom 302	Yes	W2	Sheetrock	Tan	None	0	0	Negative	None	0		No	No	No		
1	3	302	Classroom 302	Yes	W3	Sheetrock	Tan	None	0	0	Negative	None	0		No	No	No		
1	3	302	Classroom 302	Yes	W4	CMU	Tan	None	0	0	Negative	None	0		No	No	No		
1	3	302	Classroom 302	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	3	302	Classroom 302	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0		No	No	No		
1	3	302A	Classroom 302 Storage	Yes	W1	CMU	Tan	None	0	0.03	Negative	None	0		No	No	No		
1	3	302A	Classroom 302 Storage	Yes	W2	CMU	Tan	None	0	0.01	Negative	None	0		No	No	No		
1	3	302A	Classroom 302 Storage	Yes	W3	CMU	Tan	None	0	0	Negative	None	0		No	No	No		
1	3	302A	Classroom 302 Storage	Yes	W4	CMU	Tan	None	0	0.01	Negative	None	0		No	No	No		
1	3	302A	Classroom 302 Storage	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	3	302A	Classroom 302 Storage	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0		No	No	No		
1	3	303	Classroom 303	Yes	W1	CMU	Tan	None	0	0.02	Negative	None	0		No	No	No		
1	3	303	Classroom 303	Yes	W2	CMU	Tan	None	0	0.05	Negative	None	0		No	No	No		
1	3	303	Classroom 303	Yes	W3	CMU	Tan	None	0	0	Negative	None	0		No	No	No		
1	3	303	Classroom 303	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A	None	0		No	No	No		particle board divider
1	3	303	Classroom 303	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	3	303	Classroom 303	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0		No	No	No		
1	3	304	Classroom 304	Yes	W1	Sheetrock	Green	Chipping	2	0	Negative	None	0		No	No	No		
1	3	304	Classroom 304	Yes	W2	Sheetrock	Green	Chipping	4	0	Negative	None	0		No	No	No		
1	3	304	Classroom 304	Yes	W3	CMU	Tan	None	0	0.02	Negative	None	0		No	No	No		
1	3	304	Classroom 304	Yes	W4	Sheetrock	Green	None	0	0	Negative	None	0		No	No	No		
1	3	304	Classroom 304	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	3	304	Classroom 304	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0		No	No	No		
1	3	305	Classroom 305	Yes	W1	CMU	Tan	None	0	0.02	Negative	None	0		No	No	No		
1	3	305	Classroom 305	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A	None	0		No	No	No		particle board divider
1	3	305	Classroom 305	Yes	W3	CMU	Tan	None	0	0	Negative	None	0		No	No	No		
1	3	305	Classroom 305	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A	None	0		No	No	No		particle board divider
1	3	305	Classroom 305	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	3	305	Classroom 305	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0		No	No	No		
1	3	306	Classroom 306	Yes	W1	Sheetrock	Tan	Chipping	2	0	Negative	None	0		No	No	No		
1	3	306	Classroom 306	Yes	W2	Sheetrock	Tan	Chipping	8	0	Negative	None	0		No	No	No		
1	3	306	Classroom 306	Yes	W3	CMU	Tan	None	0	0	Negative	None	0		No	No	No		
1	3	306	Classroom 306	Yes	W4	Sheetrock	Tan	Chipping	3	0	Negative	None	0		No	No	No		
1	3	306	Classroom 306	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	3	306	Classroom 306	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0		No	No	No		
1	3	307	Classroom 307	Yes	W1	CMU	Tan	None	0	0.01	Negative	None	0		No	No	No		
1	3	307	Classroom 307	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A	None	0		No	No	No		particle board divider
1	3	307	Classroom 307	Yes	W3	CMU	Tan	None	0	0.01	Negative	None	0		No	No	No		

		School District of Philadelphia																	
		Lead Safe Certification Assessment Report										Inspection Dates: December 2020 and January 2021							
		Longstreth Elementary School										ULCS# 1350							
Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes
1	3	307	Classroom 307	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A	None	0		No	No	No		particle board divider
1	3	307	Classroom 307	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	3	307	Classroom 307	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0		No	No	No		
1	3	308	Classroom 308	Yes	W1	Sheetrock	Purple	Chipping	3	0	Negative	None	0		No	No	No		
1	3	308	Classroom 308	Yes	W2	Sheetrock	Green	holes	5	0	Negative	None	0		No	No	No		
1	3	308	Classroom 308	Yes	W3	CMU	Purple	None	0	0.01	Negative	None	0		No	No	No		
1	3	308	Classroom 308	Yes	W4	Sheetrock	Green	peeling	4	0	Negative	None	0		No	No	No		
1	3	308	Classroom 308	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	3	308	Classroom 308	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0		No	No	No		
1	3	309	Classroom 309	Yes	W1	CMU	Tan	None	0	0.03	Negative	None	0		No	No	No		
1	3	309	Classroom 309	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A	None	0		No	No	No		particle board divider
1	3	309	Classroom 309	Yes	W3	CMU	Tan	Flaking	5	0.02	Negative	None	0		No	No	No		
1	3	309	Classroom 309	Yes	W4	CMU	Tan	Chipping	6	0.03	Negative	None	0		No	No	No		
1	3	309	Classroom 309	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	3	309	Classroom 309	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0		No	No	No		
1	3	310	Classroom 310	Yes	W1	Sheetrock	Blue	peeling	6	0	Negative	None	0		No	No	No		
1	3	310	Classroom 310	Yes	W2	Sheetrock	Tan	None	0	0	Negative	None	0		No	No	No		
1	3	310	Classroom 310	Yes	W3	CMU	Tan	None	0	0.29	Negative	None	0		No	No	No		
1	3	310	Classroom 310	Yes	W4	Sheetrock	Blue	peeling	1	0	Negative	None	0		No	No	No		
1	3	310	Classroom 310	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	3	310	Classroom 310	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0		No	No	No		
1	3	311	Classroom 311	Yes	W1	CMU	Tan	None	0	0.01	Negative	None	0		No	No	No		
1	3	311	Classroom 311	Yes	W2	CMU	Tan	None	0	0.01	Negative	None	0		No	No	No		
1	3	311	Classroom 311	Yes	W3	CMU	Tan	None	0	0.01	Negative	None	0		No	No	No		
1	3	311	Classroom 311	Yes	W4	CMU	Tan	None	0	0	Negative	None	0		No	No	No		
1	3	311	Classroom 311	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	3	311	Classroom 311	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0		No	No	No		
1	3	311A	Girl's Restroom near Classroom 311	Yes	W1	CMU	Tan	None	0	0	Negative	None	0		No	No	No		
1	3	311A	Girl's Restroom near Classroom 311	Yes	W2	CMU	Tan	None	0	0	Negative	None	0		No	No	No		
1	3	311A	Girl's Restroom near Classroom 311	Yes	W3	CMU	Tan	None	0	0	Negative	None	0		No	No	No		
1	3	311A	Girl's Restroom near Classroom 311	Yes	W4	CMU	Tan	None	0	0	Negative	None	0		No	No	No		
1	3	311A	Girl's Restroom near Classroom 311	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	3	311A	Girl's Restroom near Classroom 311	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0		No	No	No		
1	3	311B	Boy's Restroom near Classroom 311	Yes	W1	CMU	Tan	None	0	0	Negative	None	0		No	No	No		
1	3	311B	Boy's Restroom near Classroom 311	Yes	W2	CMU	Tan	holes	3	0	Negative	None	0		No	No	No		
1	3	311B	Boy's Restroom near Classroom 311	Yes	W3	CMU	Tan	holes	4	0	Negative	None	0		No	No	No		
1	3	311B	Boy's Restroom near Classroom 311	Yes	W4	CMU	Tan	None	0	0	Negative	None	0		No	No	No		
1	3	311B	Boy's Restroom near Classroom 311	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No	No Access	No Access	No Access	
1	3	311B	Boy's Restroom near Classroom 311	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0		No	No	No		
1	3	311C	Custodial Closet between Restrooms near Classroom 311	No	W1	N/A	N/A	N/A	N/A	N/A	N/A	None	0		No	No	No		wall 1 is door
1	3	311C	Custodial Closet between Restrooms near Classroom 311	No	W2	CMU	Tan	None	0	0.01	Negative	None	0		No	No	No		
1	3	311C	Custodial Closet between Restrooms near Classroom 311	No	W3	CMU	Tan	None	0	0.02	Negative	None	0		No	No	No		
1	3	311C	Custodial Closet between Restrooms near Classroom 311	No	W4	CMU	Tan	None	0	0.02	Negative	None	0		No	No	No		
1	3	311C	Custodial Closet between Restrooms near Classroom 311	No	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	3	311C	Custodial Closet between Restrooms near Classroom 311	No	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0		No	No	No		
1	3	312	Classroom 312	Yes	W1	Sheetrock	Tan	None	0	0	Negative	None	0		No	No	No		
1	3	312	Classroom 312	Yes	W2	CMU	Tan	None	0	0.02	Negative	None	0		No	No	No		
1	3	312	Classroom 312	Yes	W3	Sheetrock	Tan	None	0	0	Negative	None	0		No	No	No		
1	3	312	Classroom 312	Yes	W4	Sheetrock	Tan	None	0	0	Negative	None	0		No	No	No		
1	3	312	Classroom 312	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	3	312	Classroom 312	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0		No	No	No		
1	3	313	Classroom 313	Yes	W1	CMU	Tan	None	0	0.01	Negative	None	0		No	No	No		
1	3	313	Classroom 313	yes	door frame	Metal	Black	scratches	8	0.18	Negative	None	0		No	No	No		
1	3	313	Classroom 313	Yes	W2	CMU	Tan	None	0	0	Negative	None	0		No	No	No		
1	3	313	Classroom 313	Yes	W3	CMU	Tan	None	0	0	Negative	None	0		No	No	No		
1	3	313	Classroom 313	Yes	W4	CMU	Tan	None	0	0.02	Negative	None	0		No	No	No		
1	3	313	Classroom 313	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	3	313	Classroom 313	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0		No	No	No		
1	3	313A	Classroom 313 Restroom	Yes	W1	CMU	Yellow	None	0	0	Negative	None	0		No	No	No		
1	3	313A	Classroom 313 Restroom	Yes	W2	CMU	Yellow	holes	4	0	Negative	None	0		No	No	No		
1	3	313A	Classroom 313 Restroom	Yes	W3	CMU	Yellow	None	0	0	Negative	None	0		No	No	No		
1	3	313A	Classroom 313 Restroom	Yes	W4	CMU	Yellow	None	0	0	Negative	None	0		No	No	No		
1	3	313A	Classroom 313 Restroom	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	3	313A	Classroom 313 Restroom	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0		No	No	No		
1	3	314/316	Dance Room	Yes	W1	CMU	Tan	None	0	0.01	Negative	None	0		No	No	No		
1	3	314/316	Dance Room	Yes	W2	CMU	Tan	None	0	0	Negative	None	0		No	No	No		
1	3	314/316	Dance Room	Yes	W3	CMU	Tan	Cracking	5	0	Negative	None	0		No	No	No		
1	3	314/316	Dance Room	Yes	W4	CMU	Tan	None	0	0.01	Negative	None	0		No	No	No		
1	3	314/316	Dance Room	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	3	314/316	Dance Room	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0		No	No	No		
1	3	314A	Girl's Restroom near Classroom 312	Yes	W1	CMU	Tan	None	0	0	Negative	None	0		No	No	No		

		School District of Philadelphia																	
		Lead Safe Certification Assessment Report										Inspection Dates: December 2020 and January 2021							
		Longstreth Elementary School										ULCS# 1350							
		Name of Inspector: Jim Mongan																	
		Inspection Company: VERTEX																	
Element	Room	Space #	On-Site Room Name	Student/Teacher Occupied (y/n)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes
1	3	314A	Girl's Restroom near Classroom 312	Yes	W2	CMU	Tan	None	0	0	Negative	None	0		No	No	No		
1	3	314A	Girl's Restroom near Classroom 312	Yes	W3	CMU	Tan	None	0	0	Negative	None	0		No	No	No		
1	3	314A	Girl's Restroom near Classroom 312	Yes	W4	CMU	Tan	None	0	0	Negative	None	0		No	No	No		
1	3	314A	Girl's Restroom near Classroom 312	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	3	314A	Girl's Restroom near Classroom 312	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0		No	No	No		
1	3	314B	Boy's Restroom near Classroom 312	Yes	W1	CMU	Tan	None	0	0	Negative	None	0		No	No	No		
1	3	314B	Boy's Restroom near Classroom 312	Yes	W2	CMU	Tan	None	0	0	Negative	None	0		No	No	No		
1	3	314B	Boy's Restroom near Classroom 312	Yes	W3	CMU	Tan	None	0	0	Negative	None	0		No	No	No		
1	3	314B	Boy's Restroom near Classroom 312	Yes	W4	CMU	Tan	None	0	0	Negative	None	0		No	No	No		
1	3	314B	Boy's Restroom near Classroom 312	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	3	314B	Boy's Restroom near Classroom 312	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0		No	No	No		
1	3	314C	Custodial Closet between Restrooms near Classroom 312	No	W1	CMU	Tan	None	0	0	Negative	None	0		No	No	No		
1	3	314C	Custodial Closet between Restrooms near Classroom 312	No	W2	CMU	Tan	None	0	0	Negative	None	0		No	No	No		
1	3	314C	Custodial Closet between Restrooms near Classroom 312	No	W3	CMU	Tan	None	0	0	Negative	None	0		No	No	No		
1	3	314C	Custodial Closet between Restrooms near Classroom 312	No	W4	CMU	Tan	None	0	0	Negative	None	0		No	No	No		
1	3	314C	Custodial Closet between Restrooms near Classroom 312	No	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	3	314C	Custodial Closet between Restrooms near Classroom 312	No	Floor	Concrete	N/A	None	0	N/A	N/A	None	0		No	No	No		
1	3	315	Work Room 315	Yes	W1	CMU	White	None	0	0	Negative	None	0		No	No	No		
1	3	315	Work Room 315	Yes	W2	CMU	White	None	0	0	Negative	None	0		No	No	No		
1	3	315	Work Room 315	Yes	W3	CMU	White	None	0	0	Negative	None	0		No	No	No		
1	3	315	Work Room 315	Yes	W4	CMU	White	None	0	0	Negative	None	0		No	No	No		
1	3	315	Work Room 315	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	3	315	Work Room 315	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0		No	No	No		
1	3	315A	Staff Restroom by Work Room 315	Yes	W1	CMU	White	None	0	0.01	Negative	None	0		No	No	No		
1	3	315A	Staff Restroom by Work Room 315	Yes	W2	CMU	White	None	0	0	Negative	None	0		No	No	No		
1	3	315A	Staff Restroom by Work Room 315	Yes	W3	CMU	White	None	0	0	Negative	None	0		No	No	No		
1	3	315A	Staff Restroom by Work Room 315	Yes	W4	CMU	White	None	0	0	Negative	None	0		No	No	No		
1	3	315A	Staff Restroom by Work Room 315	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	3	315A	Staff Restroom by Work Room 315	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0		No	No	No		
1	3	317	Air Handler Room 317	No	W1	CMU	White	None	0	0	Negative	None	0		No	No	No		
1	3	317	Air Handler Room 317	No	W2	CMU	White	None	0	0	Negative	None	0		No	No	No		
1	3	317	Air Handler Room 317	No	W3	CMU	White	None	0	0	Negative	None	0		No	No	No		
1	3	317	Air Handler Room 317	No	W4	CMU	White	None	0	0.01	Negative	None	0		No	No	No		
1	3	317	Air Handler Room 317	No	Ceiling	Concrete	White	None	0	0.01	Negative	None	0		No	No	No		
1	3	317	Air Handler Room 317	No	Floor	Concrete	N/A	None	0	N/A	N/A	None	0		No	No	No		
1	3	318	Air Handler Room 318	No	W1	CMU	White	None	0	0.01	Negative	None	0		No	No	No		
1	3	318	Air Handler Room 318	No	W2	CMU	White	None	0	0	Negative	None	0		No	No	No		
1	3	318	Air Handler Room 318	No	W3	CMU	White	None	0	0	Negative	None	0		No	No	No		
1	3	318	Air Handler Room 318	No	W4	CMU	White	None	0	0.01	Negative	None	0		No	No	No		
1	3	318	Air Handler Room 318	No	Ceiling	Concrete	White	None	0	0.01	Negative	None	0		No	No	No		
1	3	318	Air Handler Room 318	No	Floor	Concrete	N/A	None	0	0.01	Negative	None	0		No	No	No		
1	3	318A	Storage across from Air Handler Room 318	No	W1	CMU	Tan	None	0	0	Negative	None	0		No	No	No		
1	3	318A	Storage across from Air Handler Room 318	No	W2	CMU	Tan	None	0	0	Negative	None	0		No	No	No		
1	3	318A	Storage across from Air Handler Room 318	No	W3	CMU	Tan	None	0	0.02	Negative	None	0		No	No	No		
1	3	318A	Storage across from Air Handler Room 318	No	W4	CMU	Tan	None	0	0	Negative	None	0		No	No	No		
1	3	318A	Storage across from Air Handler Room 318	No	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	3	318A	Storage across from Air Handler Room 318	No	Floor	Concrete	N/A	None	0	N/A	N/A	None	0		No	No	No		
1	3	319	Office 319	Yes	W1	CMU	White	None	0	0.01	Positive	None	0		No	No	No		
1	3	319	Office 319	Yes	W2	CMU	White	None	0	0	Negative	None	0		No	No	No		
1	3	319	Office 319	Yes	W3	CMU	White	None	0	0	Negative	None	0		No	No	No		
1	3	319	Office 319	Yes	W4	CMU	White	None	0	0	Negative	None	0		No	No	No		
1	3	319	Office 319	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	3	319	Office 319	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0		No	No	No		
1	3	320	Office 320	Yes	W1	CMU	Tan	None	0	0	Negative	None	0		No	No	No		
1	3	320	Office 320	Yes	W2	CMU	Tan	None	0	0	Negative	None	0		No	No	No		
1	3	320	Office 320	Yes	W3	CMU	Tan	None	0	0.01	Negative	None	0		No	No	No		
1	3	320	Office 320	Yes	W4	CMU	Tan	None	0	0	Negative	None	0		No	No	No		
1	3	320	Office 320	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	3	320	Office 320	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0		No	No	No		
1	3	321	Storage Room 321	No	W1	CMU	White	None	0	0.01	Negative	None	0		No	No	No		
1	3	321	Storage Room 321	No	W2	CMU	White	None	0	0.01	Negative	None	0		No	No	No		
1	3	321	Storage Room 321	No	W3	CMU	White	None	0	0.01	Negative	None	0		No	No	No		
1	3	321	Storage Room 321	No	W4	CMU	White	None	0	0	Negative	None	0		No	No	No		
1	3	321	Storage Room 321	No	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	3	321	Storage Room 321	No	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0		No	No	No		
1	3	322	Storage Room 322	No	W1	CMU	Tan	None	0	0.02	Negative	None	0		No	No	No		
1	3	322	Storage Room 322	No	W2	CMU	Tan	None	0	0.01	Negative	None	0		No	No	No		
1	3	322	Storage Room 322	No	W3	CMU	Tan	Cracking	6	0	Negative	None	0		No	No	No		
1	3	322	Storage Room 322	No	W4	CMU	Tan	None	0	0	Negative	None	0		No	No	No		
1	3	322	Storage Room 322	No	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	3	322	Storage Room 322	No	Floor	Concrete	N/A	None	0	N/A	N/A	None	0		No	No	No		

		School District of Philadelphia																	
		Lead Safe Certification Assessment Report										Inspection Dates: December 2020 and January 2021							
		Longstreth Elementary School										ULCS# 1350							
Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes
1	3	324	Storage by Elevator	No	W1	CMU	Tan	None	0	0.044	Negative	None	0		No	No	No		
1	3	324	Storage by Elevator	No	W2	CMU	Tan	None	0	0.03	Negative	None	0		No	No	No		
1	3	324	Storage by Elevator	No	W3	CMU	Tan	None	0	0.02	Negative	None	0		No	No	No		
1	3	324	Storage by Elevator	No	W4	CMU	Tan	None	0	0	Negative	None	0		No	No	No		
1	3	324	Storage by Elevator	No	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	3	324	Storage by Elevator	No	Floor	Concrete	N/A	None	0	N/A	N/A	None	0		No	No	No		
1	3	H319	Hallway by Classroom 311	Yes	W1	CMU	Tan	None	0	0	Negative	None	0		No	No	No		
1	3	H319	Hallway by Classroom 311	Yes	W2	CMU	Tan	None	0	0	Negative	None	0		No	No	No		
1	3	H319	Hallway by Classroom 311	Yes	W3	CMU	Tan	None	0	0	Negative	None	0		No	No	No		
1	3	H319	Hallway by Classroom 311	Yes	W4	CMU	Tan	None	0	0	Negative	None	0		No	No	No		
1	3	H319	Hallway by Classroom 311	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	3	H319	Hallway by Classroom 311	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0		No	No	No		
1	3	H316	Hallway by Classroom 312	Yes	W1	CMU	Tan	None	0	0.01	Negative	None	0		No	No	No		
1	3	H316	Hallway by Classroom 312	Yes	W2	Sheetrock	Tan	None	0	0	Negative	None	0		No	No	No		
1	3	H316	Hallway by Classroom 312	Yes	W3	Sheetrock	Tan	None	0	0	Negative	None	0		No	No	No		
1	3	H316	Hallway by Classroom 312	Yes	W4	CMU	Tan	None	0	0	Negative	None	0		No	No	No		
1	3	H316	Hallway by Classroom 312	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	3	H316	Hallway by Classroom 312	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0		No	No	No		
1	3	H321	Hallway by Classroom 302	Yes	W1	CMU	Tan	None	0	0	Negative	None	0		No	No	No		
1	3	H321	Hallway by Classroom 302	Yes	W2	CMU	Tan	None	0	0	Negative	None	0		No	No	No		
1	3	H321	Hallway by Classroom 302	Yes	W3	Sheetrock	Tan	None	0	0	Negative	None	0		No	No	No		
1	3	H321	Hallway by Classroom 302	Yes	W4	Sheetrock	Tan	None	0	0	Negative	None	0		No	No	No		
1	3	H321	Hallway by Classroom 302	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	3	H321	Hallway by Classroom 302	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0		No	No	No		
1	3	H320	Hallway by Classroom 301	Yes	W1	CMU	Tan	None	0	0	Negative	None	0		No	No	No		
1	3	H320	Hallway by Classroom 301	Yes	W2	CMU	Tan	None	0	0	Negative	None	0		No	No	No		
1	3	H320	Hallway by Classroom 301	Yes	W3	CMU	Tan	None	0	0	Negative	None	0		No	No	No		
1	3	H320	Hallway by Classroom 301	Yes	W4	CMU	Tan	None	0	0	Negative	None	0		No	No	No		
1	3	H320	Hallway by Classroom 301	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	3	H320	Hallway by Classroom 301	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0		No	No	No		
1	3	S31	Stairwell by Work Room 315	Yes	W1	CMU	Tan	None	0	0	Negative	None	0		No	No	No		
1	3	S31	Stairwell by Work Room 315	Yes	W2	CMU	Tan	None	0	0	Negative	None	0		No	No	No		
1	3	S31	Stairwell by Work Room 315	Yes	W3	CMU	Tan	None	0	0	Negative	None	0		No	No	No		
1	3	S31	Stairwell by Work Room 315	Yes	W4	CMU	Tan	None	0	0	Negative	None	0		No	No	No		
3		S31	Stairwell by Work Room 315	yes	tread	Concrete	Brown	None	0	0	Negative	None	0		No	No	No		
3		S31	Stairwell by Work Room 315	yes	riser	Metal	Brown	None	0	3.1	Positive	None	0		No	No	No		
3		S31	Stairwell by Work Room 315	yes	stringer	Metal	Brown	None	0	10.1	Positive	None	0		No	No	No		
1	3	S31	Stairwell by Work Room 315	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	3	S31	Stairwell by Work Room 315	Yes	Floor	Concrete	Brown	None	0	0	Negative	None	0		No	No	No		
1	3	S35	Stairwell by Dance Room 314	Yes	W1	CMU	Tan	None	0	0	Negative	None	0		No	No	No		
1	3	S35	Stairwell by Dance Room 314	Yes	W2	CMU	Tan	None	0	0	Negative	None	0		No	No	No		
1	3	S35	Stairwell by Dance Room 314	Yes	W3	CMU	Tan	None	0	0	Negative	None	0		No	No	No		
3		S35	Stairwell by Dance Room 314	yes	tread	Concrete	Brown	None	0	0.01	Negative	None	0		No	No	No		
3		S35	Stairwell by Dance Room 314	Yes	riser	Metal	Brown	None	0	3.2	Positive	None	0		No	No	No		
3		S35	Stairwell by Dance Room 314	yes	stringer	Metal	Brown	None	0	8.9	Positive	None	0		No	No	No		
1	3	S35	Stairwell by Dance Room 314	Yes	W3	CMU	Tan	None	0	0	Negative	None	0		No	No	No		
1	3	S35	Stairwell by Dance Room 314	Yes	W4	CMU	Tan	None	0	0	Negative	None	0		No	No	No		
1	3	S35	Stairwell by Dance Room 314	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	3	S35	Stairwell by Dance Room 314	Yes	Floor	Concrete	Brown	None	0	0	Negative	None	0		No	No	No		
1	3	S32	Stairwell by Classroom 301	Yes	W1	CMU	Tan	None	0	0	Negative	None	0		No	No	No		
1	3	S32	Stairwell by Classroom 301	Yes	W2	CMU	Tan	None	0	0.01	Negative	None	0		No	No	No		
3		S32	Stairwell by Classroom 301	Yes	tread	Concrete	Brown	None	0	0	Negative	None	0		No	No	No		
3		S32	Stairwell by Classroom 301	Yes	riser	Metal	Brown	None	0	4.1	Positive	None	0		No	No	No		
3		S32	Stairwell by Classroom 301	Yes	stringer	Metal	Brown	None	0	10.1	Positive	None	0		No	No	No		
1	3	S32	Stairwell by Classroom 301	Yes	W3	CMU	Tan	None	0	0	Negative	None	0		No	No	No		
1	3	S32	Stairwell by Classroom 301	Yes	W4	CMU	Tan	None	0	0	Negative	None	0		No	No	No		
3		S32	Stairwell by Classroom 301	yes	stringer	Metal	Brown	None	0	4.9	Positive	None	0		No	No	No		
1	3	S32	Stairwell by Classroom 301	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	3	S32	Stairwell by Classroom 301	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0		No	No	No		
1	3	S37	Stairwell to Roof	No	W1	CMU	Tan	None	0	0	Negative	None	0		No	No	No		
1	3	S37	Stairwell to Roof	No	W2	CMU	Tan	Cracking	5	0	Negative	None	0		No	No	No		
3		S37	Stairwell to Roof	no	riser	Metal	Brown	Chipping	6	1.9	Positive	None	0		No	No	No		
3		S37	Stairwell to Roof	no	stringer	Metal	Brown	Chipping	10	9.5	Positive	None	0		No	No	No		
1	3	S37	Stairwell to Roof	No	W3	CMU	Tan	None	0	0	Negative	None	0		No	No	No		
1	3	S37	Stairwell to Roof	No	W4	CMU	Green	None	0	0	Negative	None	0		No	No	No		
1	3	S37	Stairwell to Roof	No	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	3	S37	Stairwell to Roof	No	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0		No	No	No		