

				Inspection Dates: 8/30/21-9/9/21		School District of Philadelphia						
				Name of Inspector: Justine James/ Alyssa Cartagena		Lead Safe Certification Assessment Report						
				Inspection Company: Batta		Morris School						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
2390	1	1	110	Gym	Yes	W1	CMU	White/Tan	Flaking	40	0	Negative
2390	1	1	110	Gym	Yes	W2	CMU	White/Tan	Cracking	3	0.3	Negative
2390	1	1	110	Gym	Yes	W3	CMU	White/Tan	Cracking	100	0.1	Negative
2390	1	1	110	Gym	Yes	W4	CMU	White/Tan	Flaking	50	0.3	Negative
2390	1	1	110	Gym	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	1	110	Gym	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	1	E1	Elevator	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	1	E1	Elevator	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	1	E1	Elevator	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	1	E1	Elevator	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	1	E1	Elevator	Yes	Ceiling	Metal	White	None	0	N/A	N/A
2390	1	1	E1	Elevator	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	1	111	Fan Room between Stage and Gym	No	W1	No Access	No Access	No Access	No Access	No Access	No Access
2390	1	1	111	Fan Room between Stage and Gym	No	W2	No Access	No Access	No Access	No Access	No Access	No Access
2390	1	1	111	Fan Room between Stage and Gym	No	W3	No Access	No Access	No Access	No Access	No Access	No Access
2390	1	1	111	Fan Room between Stage and Gym	No	W4	No Access	No Access	No Access	No Access	No Access	No Access
2390	1	1	111	Fan Room between Stage and Gym	No	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
2390	1	1	111	Fan Room between Stage and Gym	No	Floor	No Access	No Access	No Access	No Access	No Access	No Access
2390	1	1	S14	Stairwell behind Stage to Fan Room	No	W1	CMU	White/Tan	None	0	N/A	N/A
2390	1	1	S14	Stairwell behind Stage to Fan Room	No	W2	CMU	White/Tan	None	0	N/A	N/A
2390	1	1	S14	Stairwell behind Stage to Fan Room	No	W3	CMU	White/Tan	None	0	N/A	N/A
2390	1	1	S14	Stairwell behind Stage to Fan Room	No	W4	CMU	White/Tan	None	0	N/A	N/A
2390	1	1	S14	Stairwell behind Stage to Fan Room	No	Ceiling	Plaster	White	None	0	N/A	N/A
2390	1	1	S14	Stairwell behind Stage to Fan Room	No	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	1	S14	Stairwell behind Stage to Fan Room	No	Floor	Metal	Gray	Friction	40	0	Negative
2390	1	1	S14	Stairwell behind Stage to Fan Room	No	Floor	Metal	Gray	Friction	5	0.2	Negative
2390	1	1	110D	Storage below Fan Room in Gymnasium	No	W1	CMU	White/Blue	None	0	N/A	N/A
2390	1	1	110D	Storage below Fan Room in Gymnasium	No	W2	CMU	White/Blue	None	0	N/A	N/A
2390	1	1	110D	Storage below Fan Room in Gymnasium	No	W3	CMU	White/Blue	None	0	N/A	N/A
2390	1	1	110D	Storage below Fan Room in Gymnasium	No	W4	CMU	White/Blue	None	0	N/A	N/A
2390	1	1	110D	Storage below Fan Room in Gymnasium	No	Ceiling	Plaster	White	Flaking	30	0.3	Negative
2390	1	1	110D	Storage below Fan Room in Gymnasium	No	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	1	110D	Fan Room (Upper Level) in Gymnasium	No	W1	No Access	No Access	No Access	No Access	No Access	No Access
2390	1	1	110D	Fan Room (Upper Level) in Gymnasium	No	W2	No Access	No Access	No Access	No Access	No Access	No Access
2390	1	1	110D	Fan Room (Upper Level) in Gymnasium	No	W3	No Access	No Access	No Access	No Access	No Access	No Access
2390	1	1	110D	Fan Room (Upper Level) in Gymnasium	No	W4	No Access	No Access	No Access	No Access	No Access	No Access
2390	1	1	110D	Fan Room (Upper Level) in Gymnasium	No	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
2390	1	1	110D	Fan Room (Upper Level) in Gymnasium	No	Floor	No Access	No Access	No Access	No Access	No Access	No Access
2390	1	1	110F	Coats Storage next to Boy's Restroom in Gym	Yes	W1	CMU	White	None	0	N/A	N/A
2390	1	1	110F	Coats Storage next to Boy's Restroom in Gym	Yes	W2	CMU	White	None	0	N/A	N/A
2390	1	1	110F	Coats Storage next to Boy's Restroom in Gym	Yes	W3	CMU	White	None	0	N/A	N/A
2390	1	1	110F	Coats Storage next to Boy's Restroom in Gym	Yes	W4	CMU	White	None	0	N/A	N/A
2390	1	1	110F	Coats Storage next to Boy's Restroom in Gym	Yes	Ceiling	Sheetrock	White	None	0	N/A	N/A
2390	1	1	110F	Coats Storage next to Boy's Restroom in Gym	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	1	110E	Coats Storage next to Storage Room	Yes	W1	CMU	White	None	0	N/A	N/A

				Inspection Dates: 8/30/21-9/9/21		School District of Philadelphia						
				Name of Inspector: Justine James/ Alyssa Cartagena		Lead Safe Certification Assessment Report						
				Inspection Company: Batta		Morris School						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
2390	1	1	110E	Coats Storage next to Storage Room	Yes	W2	CMU	White	None	0	N/A	N/A
2390	1	1	110E	Coats Storage next to Storage Room	Yes	W3	CMU	White	None	0	N/A	N/A
2390	1	1	110E	Coats Storage next to Storage Room	Yes	W4	CMU	White	None	0	N/A	N/A
2390	1	1	110E	Coats Storage next to Storage Room	Yes	Ceiling	Sheetrock	White	None	0	N/A	N/A
2390	1	1	110E	Coats Storage next to Storage Room	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	1	PC110E	Pipe Chase in Coats Storage next to Storage Room	No	W1	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	1	PC110E	Pipe Chase in Coats Storage next to Storage Room	No	W2	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	1	PC110E	Pipe Chase in Coats Storage next to Storage Room	No	W3	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	1	PC110E	Pipe Chase in Coats Storage next to Storage Room	No	W4	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	1	PC110E	Pipe Chase in Coats Storage next to Storage Room	No	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	1	PC110E	Pipe Chase in Coats Storage next to Storage Room	No	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	1	110G	Boy's Restroom in Gym	Yes	W1	CMU	Tan/White	None	0	N/A	N/A
2390	1	1	110G	Boy's Restroom in Gym	Yes	W2	CMU	Tan/White	None	0	N/A	N/A
2390	1	1	110G	Boy's Restroom in Gym	Yes	W3	CMU	Tan/White	None	0	N/A	N/A
2390	1	1	110G	Boy's Restroom in Gym	Yes	W3	Metal	Brown	Flaking	4	0.2	Negative
2390	1	1	110G	Boy's Restroom in Gym	Yes	W4	CMU	Tan/White	None	0	N/A	N/A
2390	1	1	110G	Boy's Restroom in Gym	Yes	Ceiling	Plaster	White	Flaking	8	0.1	Negative
2390	1	1	110G	Boy's Restroom in Gym	Yes	Floor	Concrete	Grey	Flaking	50	0.2	Negative
2390	1	1	110C	Girl's Restroom in Gym	Yes	W1	CMU	White	Flaking	6	0.1	Negative
2390	1	1	110C	Girl's Restroom in Gym	Yes	W2	CMU	White	None	0	N/A	N/A
2390	1	1	110C	Girl's Restroom in Gym	Yes	W3	CMU	White	None	0	N/A	N/A
2390	1	1	110C	Girl's Restroom in Gym	Yes	W4	CMU	White	None	0	N/A	N/A
2390	1	1	110C	Girl's Restroom in Gym	Yes	Ceiling	Plaster	White	None	0	N/A	N/A
2390	1	1	110C	Girl's Restroom in Gym	Yes	Floor	Concrete	Grey	None	0	N/A	N/A
2390	1	1	PC110C	Pipe Chase in Girl's Restroom in Gym	No	W1	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	1	PC110C	Pipe Chase in Girl's Restroom in Gym	No	W2	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	1	PC110C	Pipe Chase in Girl's Restroom in Gym	No	W3	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	1	PC110C	Pipe Chase in Girl's Restroom in Gym	No	W4	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	1	PC110C	Pipe Chase in Girl's Restroom in Gym	No	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	1	PC110C	Pipe Chase in Girl's Restroom in Gym	No	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	1	110A	Gym Storage next to Gym Office (Old Kitchen)	Yes	W1	CMU	White	None	0	N/A	N/A
2390	1	1	110A	Gym Storage next to Gym Office (Old Kitchen)	Yes	W1	Metal	Tan	Flaking	6	0.2	Negative
2390	1	1	110A	Gym Storage next to Gym Office (Old Kitchen)	Yes	W2	CMU	White	None	0	N/A	N/A
2390	1	1	110A	Gym Storage next to Gym Office (Old Kitchen)	Yes	W3	CMU	White	None	0	N/A	N/A
2390	1	1	110A	Gym Storage next to Gym Office (Old Kitchen)	Yes	W4	CMU	White	None	0	N/A	N/A
2390	1	1	110A	Gym Storage next to Gym Office (Old Kitchen)	Yes	Ceiling	Plaster	White	Flaking	50	0	Negative
2390	1	1	110A	Gym Storage next to Gym Office (Old Kitchen)	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	1	110B	Gym Office	Yes	W1	CMU	White	None	0	N/A	N/A
2390	1	1	110B	Gym Office	Yes	W2	CMU	White	None	0	N/A	N/A
2390	1	1	110B	Gym Office	Yes	W3	CMU	White	None	0	N/A	N/A
2390	1	1	110B	Gym Office	Yes	W4	CMU	White	None	0	N/A	N/A
2390	1	1	110B	Gym Office	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	1	110B	Gym Office	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	1	110C	Gym Office Restroom	Yes	W1	CMU	White	None	0	N/A	N/A
2390	1	1	110C	Gym Office Restroom	Yes	W2	CMU	White	None	0	N/A	N/A

				Inspection Dates: 8/30/21-9/9/21		School District of Philadelphia						
				Name of Inspector: Justine James/ Alyssa Cartagena		Lead Safe Certification Assessment Report						
				Inspection Company: Batta		Morris School						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
2390	1	1	110C	Gym Office Restroom	Yes	W3	CMU	White	None	0	N/A	N/A
2390	1	1	110C	Gym Office Restroom	Yes	W4	CMU	White	None	0	N/A	N/A
2390	1	1	110C	Gym Office Restroom	Yes	Ceiling	Plaster	White	None	0	N/A	N/A
2390	1	1	110C	Gym Office Restroom	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	1	H19	Back Hallway from Auditorium to Gym	Yes	W1	CMU	White	None	0	N/A	N/A
2390	1	1	H19	Back Hallway from Auditorium to Gym	Yes	W2	CMU	White/Tan	Flaking	5	0.1	Negative
2390	1	1	H19	Back Hallway from Auditorium to Gym	Yes	W3	CMU	White	None	0	N/A	N/A
2390	1	1	H19	Back Hallway from Auditorium to Gym	Yes	W4	CMU	White/Tan	None	0	N/A	N/A
2390	1	1	H19	Back Hallway from Auditorium to Gym	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	1	H19	Back Hallway from Auditorium to Gym	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	1	H19	Back Hallway from Auditorium to Gym	Yes	Floor	Metal	Grey	Friction	8	0.1	Negative
2390	1	1	Stage	Auditorium Stage	Yes	W1	CMU	Black	None	0	N/A	N/A
2390	1	1	Stage	Auditorium Stage	Yes	W2	CMU	Black	None	0	N/A	N/A
2390	1	1	Stage	Auditorium Stage	Yes	W3	CMU	Black/Tan	None	0	N/A	N/A
2390	1	1	Stage	Auditorium Stage	Yes	W4	CMU	Black	None	0	N/A	N/A
2390	1	1	Stage	Auditorium Stage	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	1	Stage	Auditorium Stage	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	1	109A	Stage Storage Room	Yes	W1	CMU	White	None	0	N/A	N/A
2390	1	1	109A	Stage Storage Room	Yes	W2	CMU	White	None	0	N/A	N/A
2390	1	1	109A	Stage Storage Room	Yes	W3	CMU	White	None	0	N/A	N/A
2390	1	1	109A	Stage Storage Room	Yes	W4	CMU	White	None	0	N/A	N/A
2390	1	1	109A	Stage Storage Room	Yes	Ceiling	Sheetrock	White	None	0	N/A	N/A
2390	1	1	109A	Stage Storage Room	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	1	109	Auditorium	Yes	W1	CMU	White	None	0	N/A	N/A
2390	1	1	109	Auditorium	Yes	W2	CMU	White	Flaking	5	0.1	Negative
2390	1	1	109	Auditorium	Yes	W3	CMU	White	None	0	N/A	N/A
2390	1	1	109	Auditorium	Yes	W4	CMU	White	None	0	N/A	N/A
2390	1	1	109	Auditorium	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	1	109	Auditorium	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	1	109B	Storage Room in Auditorium (near entrance)	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	1	109B	Storage Room in Auditorium (near entrance)	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	1	109B	Storage Room in Auditorium (near entrance)	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	1	109B	Storage Room in Auditorium (near entrance)	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	1	109B	Storage Room in Auditorium (near entrance)	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	1	109B	Storage Room in Auditorium (near entrance)	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	1	108	Men's Restroom next to Principal's Office	Yes	W1	CMU	Tan/White	None	0	N/A	N/A
2390	1	1	108	Men's Restroom next to Principal's Office	Yes	W2	CMU	Tan/White	None	0	N/A	N/A
2390	1	1	108	Men's Restroom next to Principal's Office	Yes	W3	CMU	Tan/White	None	0	N/A	N/A
2390	1	1	108	Men's Restroom next to Principal's Office	Yes	W4	CMU	Tan/White	None	0	N/A	N/A
2390	1	1	108	Men's Restroom next to Principal's Office	Yes	Ceiling	Plaster	White	None	0	N/A	N/A
2390	1	1	108	Men's Restroom next to Principal's Office	Yes	Floor	Concrete	Grey	Flaking	15	0.3	Negative
2390	1	1	PC108	Pipe Chase in Men's Restroom next to Principal's Office	No	W1	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	1	PC108	Pipe Chase in Men's Restroom next to Principal's Office	No	W2	N/A	N/A	N/A	N/A	N/A	N/A

				Inspection Dates: 8/30/21-9/9/21		School District of Philadelphia						
				Name of Inspector: Justine James/ Alyssa Cartagena		Lead Safe Certification Assessment Report						
				Inspection Company: Batta		Morris School						
ULCS#	Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
2390	1	1	PC108	Pipe Chase in Men's Restroom next to Principal's Office	No	W3	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	1	PC108	Pipe Chase in Men's Restroom next to Principal's Office	No	W4	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	1	PC108	Pipe Chase in Men's Restroom next to Principal's Office	No	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	1	PC108	Pipe Chase in Men's Restroom next to Principal's Office	No	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	1	108A	Women's Restroom next to Principal's Office	Yes	W1	CMU	Tan/White	None	0	N/A	N/A
2390	1	1	108A	Women's Restroom next to Principal's Office	Yes	W2	CMU	Tan/White	None	0	N/A	N/A
2390	1	1	108A	Women's Restroom next to Principal's Office	Yes	W3	CMU	Tan/White	None	0	N/A	N/A
2390	1	1	108A	Women's Restroom next to Principal's Office	Yes	W4	CMU	Tan/White	None	0	N/A	N/A
2390	1	1	108A	Women's Restroom next to Principal's Office	Yes	Ceiling	Plaster	White	None	0	N/A	N/A
2390	1	1	108A	Women's Restroom next to Principal's Office	Yes	Floor	Concrete	Grey	Flaking	5	0.2	Negative
2390	1	1	H15	Main Entrance Lobby (Includes Vestibule)	Yes	W1	Brick	N/A	N/A	N/A	N/A	N/A
2390	1	1	H15	Main Entrance Lobby (Includes Vestibule)	Yes	W2	Brick	N/A	N/A	N/A	N/A	N/A
2390	1	1	H15	Main Entrance Lobby (Includes Vestibule)	Yes	W2	Sheetrock	White	None	0	N/A	N/A
2390	1	1	H15	Main Entrance Lobby (Includes Vestibule)	Yes	W3	Brick	N/A	N/A	N/A	N/A	N/A
2390	1	1	H15	Main Entrance Lobby (Includes Vestibule)	Yes	W3	Sheetrock	White	None	0	N/A	N/A
2390	1	1	H15	Main Entrance Lobby (Includes Vestibule)	Yes	W3	Metal	Tan	Flaking	4	0.6	Negative
2390	1	1	H15	Main Entrance Lobby (Includes Vestibule)	Yes	W4	Brick	N/A	N/A	N/A	N/A	N/A
2390	1	1	H15	Main Entrance Lobby (Includes Vestibule)	Yes	Ceiling	Sheetrock	White	None	0	N/A	N/A
2390	1	1	H15	Main Entrance Lobby (Includes Vestibule)	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	1	107A1	Principal's Office Restroom	Yes	W1	CMU	White	None	0	N/A	N/A
2390	1	1	107A1	Principal's Office Restroom	Yes	W2	CMU	White	None	0	N/A	N/A
2390	1	1	107A1	Principal's Office Restroom	Yes	W3	CMU	White	None	0	N/A	N/A
2390	1	1	107A1	Principal's Office Restroom	Yes	W4	CMU	White	None	0	N/A	N/A
2390	1	1	107A1	Principal's Office Restroom	Yes	Ceiling	Plaster	White	None	0	N/A	N/A
2390	1	1	107A1	Principal's Office Restroom	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	1	107A	Principal's Office	Yes	W1	CMU	White	None	0	N/A	N/A
2390	1	1	107A	Principal's Office	Yes	W2	CMU	White	None	0	N/A	N/A
2390	1	1	107A	Principal's Office	Yes	W3	CMU	White	None	0	N/A	N/A
2390	1	1	107A	Principal's Office	Yes	W4	CMU	White	None	0	N/A	N/A
2390	1	1	107A	Principal's Office	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	1	107A	Principal's Office	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	1	107A2	Principal's Office Closet	Yes	W1	CMU	White	None	0	N/A	N/A
2390	1	1	107A2	Principal's Office Closet	Yes	W2	CMU	White	None	0	N/A	N/A
2390	1	1	107A2	Principal's Office Closet	Yes	W3	CMU	White	None	0	N/A	N/A
2390	1	1	107A2	Principal's Office Closet	Yes	W4	CMU	White	None	0	N/A	N/A
2390	1	1	107A2	Principal's Office Closet	Yes	Ceiling	Plaster	White	None	0	N/A	N/A
2390	1	1	107A2	Principal's Office Closet	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	1	107C	School Police next to Main Office	Yes	W1	CMU	Blue	None	0	N/A	N/A
2390	1	1	107C	School Police next to Main Office	Yes	W2	CMU	Blue	None	0	N/A	N/A
2390	1	1	107C	School Police next to Main Office	Yes	W3	CMU	Blue	None	0	N/A	N/A
2390	1	1	107C	School Police next to Main Office	Yes	W4	CMU	Blue	None	0	N/A	N/A
2390	1	1	107C	School Police next to Main Office	Yes	Ceiling	Sheetrock	White	None	0	N/A	N/A

				Inspection Dates: 8/30/21-9/9/21		School District of Philadelphia						
				Name of Inspector: Justine James/ Alyssa Cartagena		Lead Safe Certification Assessment Report						
				Inspection Company: Batta		Morris School						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
2390	1	1	107C	School Police next to Main Office	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	1	107	Main Office	Yes	W1	CMU	Tan/White	Flaking	5	0.1	Negative
2390	1	1	107	Main Office	Yes	W2	CMU	Tan/White	None	0	N/A	N/A
2390	1	1	107	Main Office	Yes	W3	CMU	Tan/White	Flaking	4	0.2	Negative
2390	1	1	107	Main Office	Yes	W4	CMU	Tan/White	None	0	N/A	N/A
2390	1	1	107	Main Office	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	1	107	Main Office	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	1	107B	Main Office Closet	Yes	W1	CMU	Blue	None	0	N/A	N/A
2390	1	1	107B	Main Office Closet	Yes	W2	CMU	Blue	None	0	N/A	N/A
2390	1	1	107B	Main Office Closet	Yes	W3	CMU	Blue	None	0	N/A	N/A
2390	1	1	107B	Main Office Closet	Yes	W4	CMU	Blue	None	0	N/A	N/A
2390	1	1	107B	Main Office Closet	Yes	Ceiling	Sheetrock	White	None	0	N/A	N/A
2390	1	1	107B	Main Office Closet	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	1	106A	Main Office - Room Across from Mail Boxes	Yes	W1	CMU	Blue	None	0	N/A	N/A
2390	1	1	106A	Main Office - Room Across from Mail Boxes	Yes	W2	CMU	Blue	None	0	N/A	N/A
2390	1	1	106A	Main Office - Room Across from Mail Boxes	Yes	W3	CMU	Blue	None	0	N/A	N/A
2390	1	1	106A	Main Office - Room Across from Mail Boxes	Yes	W4	CMU	Blue	None	0	N/A	N/A
2390	1	1	106A	Main Office - Room Across from Mail Boxes	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	1	106A	Main Office - Room Across from Mail Boxes	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	1	106	Office/Copy Room in Main Office	Yes	W1	CMU	Blue	None	0	N/A	N/A
2390	1	1	106	Office/Copy Room in Main Office	Yes	W2	CMU	Blue	None	0	N/A	N/A
2390	1	1	106	Office/Copy Room in Main Office	Yes	W3	CMU	Blue	None	0	N/A	N/A
2390	1	1	106	Office/Copy Room in Main Office	Yes	W4	CMU	Blue	None	0	N/A	N/A
2390	1	1	106	Office/Copy Room in Main Office	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	1	106	Office/Copy Room in Main Office	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	1	106C	Computer Server/Kitchenette in Main Office	Yes	W1	CMU	Blue	None	0	N/A	N/A
2390	1	1	106C	Computer Server/Kitchenette in Main Office	Yes	W2	CMU	Blue	None	0	N/A	N/A
2390	1	1	106C	Computer Server/Kitchenette in Main Office	Yes	W3	CMU	Blue	None	0	N/A	N/A
2390	1	1	106C	Computer Server/Kitchenette in Main Office	Yes	W4	CMU	Blue	None	0	N/A	N/A
2390	1	1	106C	Computer Server/Kitchenette in Main Office	Yes	Ceiling	Sheetrock	White	None	0	N/A	N/A
2390	1	1	106C	Computer Server/Kitchenette in Main Office	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	1	105A	Nurse's Office Restroom	Yes	W1	CMU	Blue	None	0	N/A	N/A
2390	1	1	105A	Nurse's Office Restroom	Yes	W2	CMU	Blue	None	0	N/A	N/A
2390	1	1	105A	Nurse's Office Restroom	Yes	W3	CMU	Blue	None	0	N/A	N/A
2390	1	1	105A	Nurse's Office Restroom	Yes	W4	CMU	Blue	None	0	N/A	N/A
2390	1	1	105A	Nurse's Office Restroom	Yes	Ceiling	Plaster	White	None	0	N/A	N/A
2390	1	1	105A	Nurse's Office Restroom	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	1	105	Nurse's Office	Yes	W1	CMU	Blue/White	None	0	N/A	N/A
2390	1	1	105	Nurse's Office	Yes	W2	CMU	Blue/White	None	0	N/A	N/A
2390	1	1	105	Nurse's Office	Yes	W3	CMU	Blue/White	None	0	N/A	N/A
2390	1	1	105	Nurse's Office	Yes	W4	CMU	Blue/White	None	0	N/A	N/A
2390	1	1	105	Nurse's Office	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	1	105	Nurse's Office	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	1	105B	Nurse's Office Closet	Yes	W1	CMU	Blue	None	0	N/A	N/A
2390	1	1	105B	Nurse's Office Closet	Yes	W2	CMU	Blue	None	0	N/A	N/A

				Inspection Dates: 8/30/21-9/9/21		School District of Philadelphia						
				Name of Inspector: Justine James/ Alyssa Cartagena		Lead Safe Certification Assessment Report						
				Inspection Company: Batta		Morris School						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
2390	1	1	105B	Nurse's Office Closet	Yes	W3	CMU	Blue	None	0	N/A	N/A
2390	1	1	105B	Nurse's Office Closet	Yes	W4	CMU	Blue	None	0	N/A	N/A
2390	1	1	105B	Nurse's Office Closet	Yes	Ceiling	Sheetrock	White	None	0	N/A	N/A
2390	1	1	105B	Nurse's Office Closet	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	1	104	Counselor's Office	Yes	W1	CMU	Tan/White	Flaking	4	0	Negative
2390	1	1	104	Counselor's Office	Yes	W2	CMU	Tan/White	None	0	N/A	N/A
2390	1	1	104	Counselor's Office	Yes	W3	CMU	Tan/White	Flaking	3	0	Negative
2390	1	1	104	Counselor's Office	Yes	W4	CMU	Tan/White	Flaking	12	0.2	Negative
2390	1	1	104	Counselor's Office	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	1	104	Counselor's Office	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	1	104A	Counselor's Office Large Closet	Yes	W1	No Access	No Access	No Access	No Access	No Access	No Access
2390	1	1	104A	Counselor's Office Large Closet	Yes	W2	No Access	No Access	No Access	No Access	No Access	No Access
2390	1	1	104A	Counselor's Office Large Closet	Yes	W3	No Access	No Access	No Access	No Access	No Access	No Access
2390	1	1	104A	Counselor's Office Large Closet	Yes	W4	No Access	No Access	No Access	No Access	No Access	No Access
2390	1	1	104A	Counselor's Office Large Closet	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
2390	1	1	104A	Counselor's Office Large Closet	Yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access
2390	1	1	104B	Counselor's Office Small Closet	Yes	W1	No Access	No Access	No Access	No Access	No Access	No Access
2390	1	1	104B	Counselor's Office Small Closet	Yes	W2	No Access	No Access	No Access	No Access	No Access	No Access
2390	1	1	104B	Counselor's Office Small Closet	Yes	W3	No Access	No Access	No Access	No Access	No Access	No Access
2390	1	1	104B	Counselor's Office Small Closet	Yes	W4	No Access	No Access	No Access	No Access	No Access	No Access
2390	1	1	104B	Counselor's Office Small Closet	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
2390	1	1	104B	Counselor's Office Small Closet	Yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access
2390	1	1	103A	Custodial Closet across from Main Office	No	W1	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	1	103A	Custodial Closet across from Main Office	No	W2	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	1	103A	Custodial Closet across from Main Office	No	W3	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	1	103A	Custodial Closet across from Main Office	No	W4	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	1	103A	Custodial Closet across from Main Office	No	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	1	103A	Custodial Closet across from Main Office	No	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	1	S11	Stairwell across from Main Office	Yes	W1	CMU	White/Tan	None	0	N/A	N/A
2390	1	1	S11	Stairwell across from Main Office	Yes	W2	CMU	White/Tan	None	0	N/A	N/A
2390	1	1	S11	Stairwell across from Main Office	Yes	W3	CMU	White/Tan	None	0	N/A	N/A
2390	1	1	S11	Stairwell across from Main Office	Yes	W4	CMU	White/Tan	None	0	N/A	N/A
2390	1	1	S11	Stairwell across from Main Office	Yes	Ceiling	Plaster	White	None	0	N/A	N/A
2390	1	1	S11	Stairwell across from Main Office	Yes	Floor	Concrete	Black	None	0	N/A	N/A
2390	1	1	H14	Hallway from Main Office to Gym	Yes	W1	CMU	Tan/White	None	0	N/A	N/A
2390	1	1	H14	Hallway from Main Office to Gym	Yes	W2	CMU	Tan/White	None	0	N/A	N/A
2390	1	1	H14	Hallway from Main Office to Gym	Yes	W3	CMU	Tan/White	None	0	N/A	N/A
2390	1	1	H14	Hallway from Main Office to Gym	Yes	W4	CMU	Tan/White	None	0	N/A	N/A
2390	1	1	H14	Hallway from Main Office to Gym	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	1	H14	Hallway from Main Office to Gym	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	1	S14	Stairwell next to Gymnasium	Yes	W1	CMU	White/Tan	None	0	N/A	N/A
2390	1	1	S14	Stairwell next to Gymnasium	Yes	W2	CMU	White/Tan	None	0	N/A	N/A
2390	1	1	S14	Stairwell next to Gymnasium	Yes	W3	CMU	White/Tan	None	0	N/A	N/A
2390	1	1	S14	Stairwell next to Gymnasium	Yes	W4	CMU	White/Tan	None	0	N/A	N/A
2390	1	1	S14	Stairwell next to Gymnasium	Yes	Ceiling	Plaster	White	None	0	N/A	N/A

				Inspection Dates: 8/30/21-9/9/21		School District of Philadelphia						
				Name of Inspector: Justine James/ Alyssa Cartagena		Lead Safe Certification Assessment Report						
				Inspection Company: Batta		Morris School						
ULCS#	Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
2390	1	1	S14	Stairwell next to Gymnasium	Yes	Floor	Metal	Grey	Friction	40	0	Negative
2390	1	1	S14	Stairwell next to Gymnasium	Yes	Floor	Metal	Grey	Friction	5	0.2	Negative
2390	1	1	S14	Stairwell next to Gymnasium	Yes	Floor	Concrete	Black	None	0	N/A	N/A
2390	1	1	103	Storage across from Nurse's Office	Yes	W1	CMU	Blue	None	0	N/A	N/A
2390	1	1	103	Storage across from Nurse's Office	Yes	W2	Brick	Blue	None	0	N/A	N/A
2390	1	1	103	Storage across from Nurse's Office	Yes	W3	CMU	Blue	None	0	N/A	N/A
2390	1	1	103	Storage across from Nurse's Office	Yes	W4	CMU	Blue	None	0	N/A	N/A
2390	1	1	103	Storage across from Nurse's Office	Yes	Ceiling	Plaster	White	Flaking	100	0.2	Negative
2390	1	1	103	Storage across from Nurse's Office	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	1	102	Girl's Restroom across from Nurse's Office	Yes	W1	CMU	Tan/White	None	0	N/A	N/A
2390	1	1	102	Girl's Restroom across from Nurse's Office	Yes	W2	CMU	Tan/White	None	0	N/A	N/A
2390	1	1	102	Girl's Restroom across from Nurse's Office	Yes	W3	CMU	Tan/White	None	0	N/A	N/A
2390	1	1	102	Girl's Restroom across from Nurse's Office	Yes	W4	CMU	Tan/White	None	0	N/A	N/A
2390	1	1	102	Girl's Restroom across from Nurse's Office	Yes	Ceiling	Plaster	White	Cracking	15	0.1	Negative
2390	1	1	102	Girl's Restroom across from Nurse's Office	Yes	Floor	Concrete	Black	Flaking	35	0.1	Negative
2390	1	1	PC102	Pipe Chase in Girl's Restroom across from Nurse's Office	No	W1	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	1	PC102	Pipe Chase in Girl's Restroom across from Nurse's Office	No	W2	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	1	PC102	Pipe Chase in Girl's Restroom across from Nurse's Office	No	W3	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	1	PC102	Pipe Chase in Girl's Restroom across from Nurse's Office	No	W4	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	1	PC102	Pipe Chase in Girl's Restroom across from Nurse's Office	No	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	1	PC102	Pipe Chase in Girl's Restroom across from Nurse's Office	No	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	1	PC102B	Pipe Chase in Hallway Outside Girl's Restroom across from Nurse's Office	No	W1	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	1	PC102B	Pipe Chase in Hallway Outside Girl's Restroom across from Nurse's Office	No	W2	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	1	PC102B	Pipe Chase in Hallway Outside Girl's Restroom across from Nurse's Office	No	W3	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	1	PC102B	Pipe Chase in Hallway Outside Girl's Restroom across from Nurse's Office	No	W4	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	1	PC102B	Pipe Chase in Hallway Outside Girl's Restroom across from Nurse's Office	No	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	1	PC102B	Pipe Chase in Hallway Outside Girl's Restroom across from Nurse's Office	No	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	1	PC105	Pipe Chase in Hallway outside Nurse's Office	No	W1	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	1	PC105	Pipe Chase in Hallway outside Nurse's Office	No	W2	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	1	PC105	Pipe Chase in Hallway outside Nurse's Office	No	W3	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	1	PC105	Pipe Chase in Hallway outside Nurse's Office	No	W4	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	1	PC105	Pipe Chase in Hallway outside Nurse's Office	No	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	1	PC105	Pipe Chase in Hallway outside Nurse's Office	No	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	1	H16	Hallway from Main Lobby to Classroom 100	Yes	W1	CMU	Tan/White	None	0	N/A	N/A
2390	1	1	H16	Hallway from Main Lobby to Classroom 100	Yes	W2	CMU	Tan/White	None	0	N/A	N/A

				Inspection Dates: 8/30/21-9/9/21		School District of Philadelphia						
				Name of Inspector: Justine James/ Alyssa Cartagena		Lead Safe Certification Assessment Report						
				Inspection Company: Batta		Morris School						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
2390	1	1	H16	Hallway from Main Lobby to Classroom 100	Yes	W3	CMU	Tan/White	None	0	N/A	N/A
2390	1	1	H16	Hallway from Main Lobby to Classroom 100	Yes	W4	CMU	Red	None	0	N/A	N/A
2390	1	1	H16	Hallway from Main Lobby to Classroom 100	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	1	H16	Hallway from Main Lobby to Classroom 100	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	1	PCH16	Pipe Chase in Hallway by Classroom 100	No	W1	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	1	PCH16	Pipe Chase in Hallway by Classroom 100	No	W2	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	1	PCH16	Pipe Chase in Hallway by Classroom 100	No	W3	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	1	PCH16	Pipe Chase in Hallway by Classroom 100	No	W4	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	1	PCH16	Pipe Chase in Hallway by Classroom 100	No	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	1	PCH16	Pipe Chase in Hallway by Classroom 100	No	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	1	101A	Classroom 101 Restroom	Yes	W1	CMU	Tan	None	0	N/A	N/A
2390	1	1	101A	Classroom 101 Restroom	Yes	W2	CMU	Tan	None	0	N/A	N/A
2390	1	1	101A	Classroom 101 Restroom	Yes	W3	CMU	Tan	None	0	N/A	N/A
2390	1	1	101A	Classroom 101 Restroom	Yes	W4	CMU	Tan	None	0	N/A	N/A
2390	1	1	101A	Classroom 101 Restroom	Yes	Ceiling	Plaster	White	None	0	N/A	N/A
2390	1	1	101A	Classroom 101 Restroom	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	1	101B	Classroom 101 Coat and Storage Area	Yes	W1	CMU	Tan	None	0	N/A	N/A
2390	1	1	101B	Classroom 101 Coat and Storage Area	Yes	W2	CMU	Tan	None	0	N/A	N/A
2390	1	1	101B	Classroom 101 Coat and Storage Area	Yes	W3	CMU	Tan	None	0	N/A	N/A
2390	1	1	101B	Classroom 101 Coat and Storage Area	Yes	W4	CMU	Tan	None	0	N/A	N/A
2390	1	1	101B	Classroom 101 Coat and Storage Area	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	1	101B	Classroom 101 Coat and Storage Area	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	1	101C	Classroom 101 Storage Closet	Yes	W1	CMU	Tan	None	0	N/A	N/A
2390	1	1	101C	Classroom 101 Storage Closet	Yes	W2	CMU	Tan	None	0	N/A	N/A
2390	1	1	101C	Classroom 101 Storage Closet	Yes	W3	CMU	Tan	None	0	N/A	N/A
2390	1	1	101C	Classroom 101 Storage Closet	Yes	W4	CMU	Tan	None	0	N/A	N/A
2390	1	1	101C	Classroom 101 Storage Closet	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	1	101C	Classroom 101 Storage Closet	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	1	101	Classroom 101	Yes	W1	CMU	Tan	None	0	N/A	N/A
2390	1	1	101	Classroom 101	Yes	W2	CMU	Tan	None	0	N/A	N/A
2390	1	1	101	Classroom 101	Yes	W3	CMU	Tan	None	0	N/A	N/A
2390	1	1	101	Classroom 101	Yes	W4	CMU	Orange	None	0	N/A	N/A
2390	1	1	101	Classroom 101	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	1	101	Classroom 101	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	1	100	Classroom 100	Yes	W1	CMU	Tan	None	0	N/A	N/A
2390	1	1	100	Classroom 100	Yes	W2	CMU	Tan	None	0	N/A	N/A
2390	1	1	100	Classroom 100	Yes	W3	CMU	Tan	None	0	N/A	N/A
2390	1	1	100	Classroom 100	Yes	W4	CMU	Orange	None	0	N/A	N/A
2390	1	1	100	Classroom 100	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	1	100	Classroom 100	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	1	100A	Classroom 100 Restroom	Yes	W1	CMU	Tan	None	0	N/A	N/A
2390	1	1	100A	Classroom 100 Restroom	Yes	W2	CMU	Tan	None	0	N/A	N/A
2390	1	1	100A	Classroom 100 Restroom	Yes	W3	CMU	Tan	None	0	N/A	N/A
2390	1	1	100A	Classroom 100 Restroom	Yes	W4	CMU	Tan	None	0	N/A	N/A
2390	1	1	100A	Classroom 100 Restroom	Yes	Ceiling	Plaster	White	None	0	N/A	N/A

				Inspection Dates: 8/30/21-9/9/21		School District of Philadelphia						
				Name of Inspector: Justine James/ Alyssa Cartagena		Lead Safe Certification Assessment Report						
				Inspection Company: Batta		Morris School						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
2390	1	1	100A	Classroom 100 Restroom	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	1	100B	Classroom 100 Coat and Storage Area	Yes	W1	CMU	Tan	None	0	N/A	N/A
2390	1	1	100B	Classroom 100 Coat and Storage Area	Yes	W2	CMU	Tan	None	0	N/A	N/A
2390	1	1	100B	Classroom 100 Coat and Storage Area	Yes	W3	CMU	Tan	None	0	N/A	N/A
2390	1	1	100B	Classroom 100 Coat and Storage Area	Yes	W4	CMU	Tan	None	0	N/A	N/A
2390	1	1	100B	Classroom 100 Coat and Storage Area	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	1	100B	Classroom 100 Coat and Storage Area	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	1	100C	Classroom 100 Storage Closet	Yes	W1	CMU	Tan	None	0	N/A	N/A
2390	1	1	100C	Classroom 100 Storage Closet	Yes	W2	CMU	Tan	None	0	N/A	N/A
2390	1	1	100C	Classroom 100 Storage Closet	Yes	W3	CMU	Tan	None	0	N/A	N/A
2390	1	1	100C	Classroom 100 Storage Closet	Yes	W4	CMU	Tan	None	0	N/A	N/A
2390	1	1	100C	Classroom 100 Storage Closet	Yes	Ceiling	Plaster	White	None	0	N/A	N/A
2390	1	1	100C	Classroom 100 Storage Closet	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	1	S12	Stairwell across from Classroom 100	Yes	W1	CMU	Tan/White	None	0	N/A	N/A
2390	1	1	S12	Stairwell across from Classroom 100	Yes	W2	CMU	Tan/White	None	0	N/A	N/A
2390	1	1	S12	Stairwell across from Classroom 100	Yes	W3	CMU	Tan/White	None	0	N/A	N/A
2390	1	1	S12	Stairwell across from Classroom 100	Yes	W4	CMU	Tan/White	None	0	N/A	N/A
2390	1	1	S12	Stairwell across from Classroom 100	Yes	Ceiling	Plaster	White	None	0	N/A	N/A
2390	1	1	S12	Stairwell across from Classroom 100	Yes	Floor	Concrete	Black	None	0	N/A	N/A
2390	1	1	S12	Stairwell across from Classroom 100	Yes	Floor	Metal	Black	Friction	20	0	Negative
2390	1	2	S22	Stairwell next to Classroom 201	Yes	W1	CMU	Tan/White	None	0	N/A	N/A
2390	1	2	S22	Stairwell next to Classroom 201	Yes	W2	CMU	Tan/White	None	0	N/A	N/A
2390	1	2	S22	Stairwell next to Classroom 201	Yes	W3	CMU	Tan/White	None	0	N/A	N/A
2390	1	2	S22	Stairwell next to Classroom 201	Yes	W4	CMU	Tan/White	None	0	N/A	N/A
2390	1	2	S22	Stairwell next to Classroom 201	Yes	Ceiling	Plaster	White	None	0	N/A	N/A
2390	1	2	S22	Stairwell next to Classroom 201	Yes	Floor	Concrete	Black	Flaking	15	0.2	Negative
2390	1	2	S22	Stairwell next to Classroom 201	Yes	Floor	Metal	Black	Friction	15	0	Negative
2390	1	2	H210	Hallway from Lunch Room to Classroom 200	Yes	W1	CMU	Tan/White	None	0	N/A	N/A
2390	1	2	H210	Hallway from Lunch Room to Classroom 200	Yes	W2	CMU	Tan/White	None	0	N/A	N/A
2390	1	2	H210	Hallway from Lunch Room to Classroom 200	Yes	W3	CMU	Tan/White	None	0	N/A	N/A
2390	1	2	H210	Hallway from Lunch Room to Classroom 200	Yes	W4	CMU	Tan/White	None	0	N/A	N/A
2390	1	2	H210	Hallway from Lunch Room to Classroom 200	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	2	H210	Hallway from Lunch Room to Classroom 200	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	2	S21	Stairwell across from Classroom 206	Yes	W1	CMU	Tan/White	None	0	N/A	N/A
2390	1	2	S21	Stairwell across from Classroom 206	Yes	W2	CMU	Tan/White	None	0	N/A	N/A
2390	1	2	S21	Stairwell across from Classroom 206	Yes	W3	CMU	Tan/White	None	0	N/A	N/A
2390	1	2	S21	Stairwell across from Classroom 206	Yes	W4	CMU	Tan/White	None	0	N/A	N/A
2390	1	2	S21	Stairwell across from Classroom 206	Yes	Ceiling	Plaster	White	None	0	N/A	N/A
2390	1	2	S21	Stairwell across from Classroom 206	Yes	Floor	Concrete	Black	None	0	N/A	N/A
2390	1	2	S21	Stairwell across from Classroom 206	Yes	Floor	Metal	Black	Friction	40	0	Negative
2390	1	2	S21	Stairwell across from Classroom 206	Yes	Floor	Metal	Black	Friction	6	0.1	Negative
2390	1	2	200	Classroom 200	Yes	W1	CMU	Tan/White	None	0	N/A	N/A
2390	1	2	200	Classroom 200	Yes	W2	CMU	Blue	None	0	N/A	N/A
2390	1	2	200	Classroom 200	Yes	W3	CMU	Tan	None	0	N/A	N/A
2390	1	2	200	Classroom 200	Yes	W4	CMU	Tan	None	0	N/A	N/A

				Inspection Dates: 8/30/21-9/9/21		School District of Philadelphia						
				Name of Inspector: Justine James/ Alyssa Cartagena		Lead Safe Certification Assessment Report						
				Inspection Company: Batta		Morris School						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
2390	1	2	200	Classroom 200	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	2	200	Classroom 200	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	2	201	Classroom 201	Yes	W1	CMU	Blue	None	0	N/A	N/A
2390	1	2	201	Classroom 201	Yes	W2	CMU	Blue	None	0	N/A	N/A
2390	1	2	201	Classroom 201	Yes	W3	CMU	Blue	None	0	N/A	N/A
2390	1	2	201	Classroom 201	Yes	W4	CMU	Blue	None	0	N/A	N/A
2390	1	2	201	Classroom 201	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	2	201	Classroom 201	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	2	202	Classroom 202	Yes	W1	CMU	Blue/Yellow	None	0	N/A	N/A
2390	1	2	202	Classroom 202	Yes	W1	Wood	Green	Flaking	5	1.7	Positive
2390	1	2	202	Classroom 202	Yes	W2	CMU	Blue	None	0	N/A	N/A
2390	1	2	202	Classroom 202	Yes	W3	CMU	Blue	Flaking	15	0.3	Negative
2390	1	2	202	Classroom 202	Yes	W4	CMU	Blue	None	0	N/A	N/A
2390	1	2	202	Classroom 202	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	2	202	Classroom 202	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	2	203	Classroom 203	Yes	W1	CMU	Tan	None	0	N/A	N/A
2390	1	2	203	Classroom 203	Yes	W2	CMU	Tan	None	0	N/A	N/A
2390	1	2	203	Classroom 203	Yes	W3	CMU	Tan	None	0	N/A	N/A
2390	1	2	203	Classroom 203	Yes	W4	CMU	Blue	None	0	N/A	N/A
2390	1	2	203	Classroom 203	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	2	203	Classroom 203	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	2	204	Classroom 204	Yes	W1	CMU	Tan	None	0	N/A	N/A
2390	1	2	204	Classroom 204	Yes	W2	CMU	Blue	None	0	N/A	N/A
2390	1	2	204	Classroom 204	Yes	W3	CMU	Tan	None	0	N/A	N/A
2390	1	2	204	Classroom 204	Yes	W4	CMU	Tan	None	0	N/A	N/A
2390	1	2	204	Classroom 204	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	2	204	Classroom 204	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	2	220	Boy's Restroom next to Classroom 203	Yes	W1	CMU	Tan/White	None	0	N/A	N/A
2390	1	2	220	Boy's Restroom next to Classroom 203	Yes	W2	CMU	Tan/White	None	0	N/A	N/A
2390	1	2	220	Boy's Restroom next to Classroom 203	Yes	W3	CMU	Tan/White	None	0	N/A	N/A
2390	1	2	220	Boy's Restroom next to Classroom 203	Yes	W4	CMU	Tan/White	None	0	N/A	N/A
2390	1	2	220	Boy's Restroom next to Classroom 203	Yes	Ceiling	Plaster	White	None	0	N/A	N/A
2390	1	2	220	Boy's Restroom next to Classroom 203	Yes	Floor	Concrete	Black	None	0	N/A	N/A
2390	1	2	PC220	Pipe Chase in Boy's Restroom next to Classroom 203	No	W1	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	2	PC220	Pipe Chase in Boy's Restroom next to Classroom 203	No	W2	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	2	PC220	Pipe Chase in Boy's Restroom next to Classroom 203	No	W3	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	2	PC220	Pipe Chase in Boy's Restroom next to Classroom 203	No	W4	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	2	PC220	Pipe Chase in Boy's Restroom next to Classroom 203	No	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	2	PC220	Pipe Chase in Boy's Restroom next to Classroom 203	No	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	2	221	Girl's Restroom across from Classroom 204	Yes	W1	CMU	Tan	None	0	N/A	N/A
2390	1	2	221	Girl's Restroom across from Classroom 204	Yes	W2	CMU	Tan	None	0	N/A	N/A
2390	1	2	221	Girl's Restroom across from Classroom 204	Yes	W3	CMU	Tan	None	0	N/A	N/A
2390	1	2	221	Girl's Restroom across from Classroom 204	Yes	W4	CMU	Tan	None	0	N/A	N/A
2390	1	2	221	Girl's Restroom across from Classroom 204	Yes	Ceiling	Plaster	White	None	0	N/A	N/A
2390	1	2	221	Girl's Restroom across from Classroom 204	Yes	Floor	Concrete	Grey	None	0	N/A	N/A

				Inspection Dates: 8/30/21-9/9/21		School District of Philadelphia						
				Name of Inspector: Justine James/ Alyssa Cartagena		Lead Safe Certification Assessment Report						
				Inspection Company: Batta		Morris School						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
2390	1	2	PC221	Pipe Chase in Girl's Restroom across from Classroom 204	No	W1	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	2	PC221	Pipe Chase in Girl's Restroom across from Classroom 204	No	W2	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	2	PC221	Pipe Chase in Girl's Restroom across from Classroom 204	No	W3	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	2	PC221	Pipe Chase in Girl's Restroom across from Classroom 204	No	W4	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	2	PC221	Pipe Chase in Girl's Restroom across from Classroom 204	No	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	2	PC221	Pipe Chase in Girl's Restroom across from Classroom 204	No	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	2	222	Women's Restroom across from Classroom 204	Yes	W1	CMU	Tan/White	None	0	N/A	N/A
2390	1	2	222	Women's Restroom across from Classroom 204	Yes	W2	CMU	Tan/White	None	0	N/A	N/A
2390	1	2	222	Women's Restroom across from Classroom 204	Yes	W3	CMU	Tan/White	None	0	N/A	N/A
2390	1	2	222	Women's Restroom across from Classroom 204	Yes	W4	CMU	Tan/White	None	0	N/A	N/A
2390	1	2	222	Women's Restroom across from Classroom 204	Yes	Ceiling	Plaster	White	None	0	N/A	N/A
2390	1	2	222	Women's Restroom across from Classroom 204	Yes	Floor	Concrete	Grey	None	0	N/A	N/A
2390	1	2	222	Women's Restroom across from Classroom 204	Yes	Floor	Metal	Tan	Flaking	20	0.2	Negative
2390	1	2	206	Classroom 206	Yes	W1	CMU	Blue	None	0	N/A	N/A
2390	1	2	206	Classroom 206	Yes	W2	CMU	Blue	None	0	N/A	N/A
2390	1	2	206	Classroom 206	Yes	W3	CMU	Blue	Flaking	8	0.1	Negative
2390	1	2	206	Classroom 206	Yes	W4	CMU	Blue	None	0	N/A	N/A
2390	1	2	206	Classroom 206	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	2	206	Classroom 206	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	2	224A	Custodial Closet next to Elevator	No	W1	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	2	224A	Custodial Closet next to Elevator	No	W2	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	2	224A	Custodial Closet next to Elevator	No	W3	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	2	224A	Custodial Closet next to Elevator	No	W4	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	2	224A	Custodial Closet next to Elevator	No	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	2	224A	Custodial Closet next to Elevator	No	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	2	208	Classroom 208	Yes	W1	CMU	Green/Tan	None	0	N/A	N/A
2390	1	2	208	Classroom 208	Yes	W2	CMU	Green	None	0	N/A	N/A
2390	1	2	208	Classroom 208	Yes	W3	CMU	Green	None	0	N/A	N/A
2390	1	2	208	Classroom 208	Yes	W4	CMU	Green	None	0	N/A	N/A
2390	1	2	208	Classroom 208	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	2	208	Classroom 208	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	2	224	Men's Restroom across from Lunch Room	Yes	W1	CMU	Tan/White	None	0	N/A	N/A
2390	1	2	224	Men's Restroom across from Lunch Room	Yes	W2	CMU	Tan/White	None	0	N/A	N/A
2390	1	2	224	Men's Restroom across from Lunch Room	Yes	W3	CMU	Tan/White	None	0	N/A	N/A
2390	1	2	224	Men's Restroom across from Lunch Room	Yes	W4	CMU	Tan/White	None	0	N/A	N/A
2390	1	2	224	Men's Restroom across from Lunch Room	Yes	Ceiling	Plaster	White	None	0	N/A	N/A
2390	1	2	224	Men's Restroom across from Lunch Room	Yes	Floor	Concrete	Black	None	0	N/A	N/A
2390	1	2	PC224	Pipe Chase next to Men's Restroom Door	No	W1	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	2	PC224	Pipe Chase next to Men's Restroom Door	No	W2	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	2	PC224	Pipe Chase next to Men's Restroom Door	No	W3	N/A	N/A	N/A	N/A	N/A	N/A

				Inspection Dates: 8/30/21-9/9/21		School District of Philadelphia						
				Name of Inspector: Justine James/ Alyssa Cartagena		Lead Safe Certification Assessment Report						
				Inspection Company: Batta		Morris School						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
2390	1	2	PC224	Pipe Chase next to Men's Restroom Door	No	W4	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	2	PC224	Pipe Chase next to Men's Restroom Door	No	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	2	PC224	Pipe Chase next to Men's Restroom Door	No	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	2	210	Cafeteria (210)	Yes	W1	CMU	Yellow	None	0	N/A	N/A
2390	1	2	210	Cafeteria (210)	Yes	W2	CMU	Yellow	None	0	N/A	N/A
2390	1	2	210	Cafeteria (210)	Yes	W3	CMU	Yellow	None	0	N/A	N/A
2390	1	2	210	Cafeteria (210)	Yes	W4	CMU	Yellow	None	0	N/A	N/A
2390	1	2	210	Cafeteria (210)	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	2	210	Cafeteria (210)	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	2	212	Cafeteria (212)	Yes	W1	See above	See above	See above	See above	See above	See above
2390	1	2	212	Cafeteria (212)	Yes	W2	See above	See above	See above	See above	See above	See above
2390	1	2	212	Cafeteria (212)	Yes	W3	See above	See above	See above	See above	See above	See above
2390	1	2	212	Cafeteria (212)	Yes	W4	See above	See above	See above	See above	See above	See above
2390	1	2	212	Cafeteria (212)	Yes	Ceiling	See above	See above	See above	See above	See above	See above
2390	1	2	212	Cafeteria (212)	Yes	Floor	See above	See above	See above	See above	See above	See above
2390	1	2	223	Storage next to Classroom 213	Yes	W1	CMU	Blue	None	0	N/A	N/A
2390	1	2	223	Storage next to Classroom 213	Yes	W2	CMU	Blue	None	0	N/A	N/A
2390	1	2	223	Storage next to Classroom 213	Yes	W3	CMU	Blue	None	0	N/A	N/A
2390	1	2	223	Storage next to Classroom 213	Yes	W4	CMU	Blue	None	0	N/A	N/A
2390	1	2	223	Storage next to Classroom 213	Yes	Ceiling	Plaster	White	None	0	N/A	N/A
2390	1	2	223	Storage next to Classroom 213	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	2	223A	Computer Server Room in Storage Room	Yes	W1	Sheetrock	White	None	0	N/A	N/A
2390	1	2	223A	Computer Server Room in Storage Room	Yes	W2	Sheetrock	White	None	0	N/A	N/A
2390	1	2	223A	Computer Server Room in Storage Room	Yes	W3	CMU	Blue	None	0	N/A	N/A
2390	1	2	223A	Computer Server Room in Storage Room	Yes	W4	CMU	Blue	None	0	N/A	N/A
2390	1	2	223A	Computer Server Room in Storage Room	Yes	Ceiling	Plaster	White	None	0	N/A	N/A
2390	1	2	223A	Computer Server Room in Storage Room	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	2	213	Classroom 213	Yes	W1	CMU	Tan	None	0	N/A	N/A
2390	1	2	213	Classroom 213	Yes	W2	CMU	Blue	None	0	N/A	N/A
2390	1	2	213	Classroom 213	Yes	W3	CMU	Tan	None	0	N/A	N/A
2390	1	2	213	Classroom 213	Yes	W4	CMU	Tan	None	0	N/A	N/A
2390	1	2	213	Classroom 213	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	2	213	Classroom 213	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	2	214	Classroom 214	Yes	W1	CMU	Blue	None	0	N/A	N/A
2390	1	2	214	Classroom 214	Yes	W2	CMU	Blue	None	0	N/A	N/A
2390	1	2	214	Classroom 214	Yes	W3	CMU	Blue	None	0	N/A	N/A
2390	1	2	214	Classroom 214	Yes	W3	Metal	Blue	Chipping	5	0.2	Negative
2390	1	2	214	Classroom 214	Yes	W4	CMU	Blue	None	0	N/A	N/A
2390	1	2	214	Classroom 214	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	2	214	Classroom 214	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	2	216	Classroom 216	Yes	W1	CMU	Tan	None	0	N/A	N/A
2390	1	2	216	Classroom 216	Yes	W2	CMU	Blue	None	0	N/A	N/A
2390	1	2	216	Classroom 216	Yes	W3	CMU	Tan	None	0	N/A	N/A
2390	1	2	216	Classroom 216	Yes	W4	CMU	Tan	None	0	N/A	N/A
2390	1	2	216	Classroom 216	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A

Inspection Dates: 8/30/21-9/9/21					School District of Philadelphia							
Name of Inspector: Justine James/ Alyssa Cartagena					Lead Safe Certification Assessment Report							
Inspection Company: Batta					Morris School							
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
2390	1	2	216	Classroom 216	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	2	S212	Stairwell next to Classroom 215	Yes	W1	CMU	Tan/White	None	0	N/A	N/A
2390	1	2	S212	Stairwell next to Classroom 215	Yes	W2	CMU	Tan/White	None	0	N/A	N/A
2390	1	2	S212	Stairwell next to Classroom 215	Yes	W3	CMU	Tan/White	None	0	N/A	N/A
2390	1	2	S212	Stairwell next to Classroom 215	Yes	W4	CMU	Tan/White	None	0	N/A	N/A
2390	1	2	S212	Stairwell next to Classroom 215	Yes	Ceiling	Plaster	White	None	0	N/A	N/A
2390	1	2	S212	Stairwell next to Classroom 215	Yes	Floor	Concrete	Black	None	0	N/A	N/A
2390	1	2	S212	Stairwell next to Classroom 215	Yes	Floor	Metal	Grey	Friction	40	0	Negative
2390	1	2	S212	Stairwell next to Classroom 215	Yes	Floor	Metal	Grey	Friction	6	0.1	Negative
2390	1	2	215	Classroom 215	Yes	W1	CMU	Blue	None	0	N/A	N/A
2390	1	2	215	Classroom 215	Yes	W2	CMU	Blue	None	0	N/A	N/A
2390	1	2	215	Classroom 215	Yes	W3	CMU	Blue	Flaking	15	0	Negative
2390	1	2	215	Classroom 215	Yes	W3	Metal	Blue	Flaking	6	0.2	Negative
2390	1	2	215	Classroom 215	Yes	W4	CMU	Blue	None	0	N/A	N/A
2390	1	2	215	Classroom 215	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	2	215	Classroom 215	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	2	218	Classroom 218	Yes	W1	CMU	Grey	None	0	N/A	N/A
2390	1	2	218	Classroom 218	Yes	W2	CMU	Blue	None	0	N/A	N/A
2390	1	2	218	Classroom 218	Yes	W3	CMU	Grey	None	0	N/A	N/A
2390	1	2	218	Classroom 218	Yes	W4	CMU	Grey	None	0	N/A	N/A
2390	1	2	218	Classroom 218	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	2	218	Classroom 218	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	2	217	Office 217 across from Classroom 216	Yes	W1	CMU	Blue	None	0	N/A	N/A
2390	1	2	217	Office 217 across from Classroom 216	Yes	W2	CMU	Blue	Flaking	8	0.2	Negative
2390	1	2	217	Office 217 across from Classroom 216	Yes	W3	CMU	Blue	Flaking	10	0.1	Negative
2390	1	2	217	Office 217 across from Classroom 216	Yes	W4	CMU	Blue	None	0	N/A	N/A
2390	1	2	217	Office 217 across from Classroom 216	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	2	217	Office 217 across from Classroom 216	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	2	219	Room 219 Kitchen	Yes	W1	CMU	White	None	0	N/A	N/A
2390	1	2	219	Room 219 Kitchen	Yes	W2	Sheetrock	Tan	None	0	N/A	N/A
2390	1	2	219	Room 219 Kitchen	Yes	W3	Sheetrock	White/Tan	None	0	N/A	N/A
2390	1	2	219	Room 219 Kitchen	Yes	W3	CMU	White	None	0	N/A	N/A
2390	1	2	219	Room 219 Kitchen	Yes	W4	CMU	White	None	0	N/A	N/A
2390	1	2	219	Room 219 Kitchen	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	2	219	Room 219 Kitchen	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	2	219A	Kitchen Office	Yes	W1	Sheetrock	Grey	Flaking	15	0.2	Negative
2390	1	2	219A	Kitchen Office	Yes	W2	CMU	Grey	None	0	N/A	N/A
2390	1	2	219A	Kitchen Office	Yes	W3	CMU	Grey	None	0	N/A	N/A
2390	1	2	219A	Kitchen Office	Yes	W4	Sheetrock	Grey	Flaking	20	0.2	Negative
2390	1	2	219A	Kitchen Office	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	2	219A	Kitchen Office	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	2	218A	Storage outside Classroom 218 and at end of Hallway	Yes	W1	CMU	White/Tan	None	0	N/A	N/A
2390	1	2	218A	Storage outside Classroom 218 and at end of Hallway	Yes	W2	CMU	White/Tan	None	0	N/A	N/A
2390	1	2	218A	Storage outside Classroom 218 and at end of Hallway	Yes	W3	CMU	White/Tan	None	0	N/A	N/A
2390	1	2	218A	Storage outside Classroom 218 and at end of Hallway	Yes	W4	CMU	White/Tan	None	0	N/A	N/A

				Inspection Dates: 8/30/21-9/9/21		School District of Philadelphia						
				Name of Inspector: Justine James/ Alyssa Cartagena		Lead Safe Certification Assessment Report						
				Inspection Company: Batta		Morris School						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
2390	1	2	218A	Storage outside Classroom 218 and at end of Hallway	Yes	Ceiling	Plaster	White	None	0	N/A	N/A
2390	1	2	218A	Storage outside Classroom 218 and at end of Hallway	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	2	218B	Women's Restroom by Classroom 218	Yes	W1	No Access	No Access	No Access	No Access	No Access	No Access
2390	1	2	218B	Women's Restroom by Classroom 218	Yes	W2	No Access	No Access	No Access	No Access	No Access	No Access
2390	1	2	218B	Women's Restroom by Classroom 218	Yes	W3	No Access	No Access	No Access	No Access	No Access	No Access
2390	1	2	218B	Women's Restroom by Classroom 218	Yes	W4	No Access	No Access	No Access	No Access	No Access	No Access
2390	1	2	218B	Women's Restroom by Classroom 218	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
2390	1	2	218B	Women's Restroom by Classroom 218	Yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access
2390	1	2	H211	Hallway from Classroom 208 to 218	Yes	W1	CMU	Tan/White	None	0	N/A	N/A
2390	1	2	H211	Hallway from Classroom 208 to 218	Yes	W2	CMU	Tan/White	None	0	N/A	N/A
2390	1	2	H211	Hallway from Classroom 208 to 218	Yes	W3	CMU	Tan/White	None	0	N/A	N/A
2390	1	2	H211	Hallway from Classroom 208 to 218	Yes	W4	CMU	Tan/White	None	0	N/A	N/A
2390	1	2	H211	Hallway from Classroom 208 to 218	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	2	H211	Hallway from Classroom 208 to 218	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	3	319	Classroom 319	Yes	W1	CMU	Blue	Flaking	20	0.1	Negative
2390	1	3	319	Classroom 319	Yes	W2	CMU	Blue	None	0	N/A	N/A
2390	1	3	319	Classroom 319	Yes	W3	CMU	Blue	Flaking	2	0.1	Negative
2390	1	3	319	Classroom 319	Yes	W3	Metal	Blue	Chipping	30	0.1	Negative
2390	1	3	319	Classroom 319	Yes	W4	CMU	Blue	None	0	N/A	N/A
2390	1	3	319	Classroom 319	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	3	319	Classroom 319	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	3	319A	Classroom 319 Storage	Yes	W1	No Access	No Access	No Access	No Access	No Access	No Access
2390	1	3	319A	Classroom 319 Storage	Yes	W2	No Access	No Access	No Access	No Access	No Access	No Access
2390	1	3	319A	Classroom 319 Storage	Yes	W3	No Access	No Access	No Access	No Access	No Access	No Access
2390	1	3	319A	Classroom 319 Storage	Yes	W4	No Access	No Access	No Access	No Access	No Access	No Access
2390	1	3	319A	Classroom 319 Storage	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
2390	1	3	319A	Classroom 319 Storage	Yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access
2390	1	3	318B	Storage Room next to Classroom 318	Yes	W1	CMU	Yellow	None	0	N/A	N/A
2390	1	3	318B	Storage Room next to Classroom 318	Yes	W2	CMU	Yellow	None	0	N/A	N/A
2390	1	3	318B	Storage Room next to Classroom 318	Yes	W3	CMU	Yellow	None	0	N/A	N/A
2390	1	3	318B	Storage Room next to Classroom 318	Yes	W4	CMU	Yellow	None	0	N/A	N/A
2390	1	3	318B	Storage Room next to Classroom 318	Yes	Ceiling	Plaster	White	None	0	N/A	N/A
2390	1	3	318B	Storage Room next to Classroom 318	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	3	318	Classroom 318	Yes	W1	CMU	Blue	None	0	N/A	N/A
2390	1	3	318	Classroom 318	Yes	W2	CMU	Blue	None	0	N/A	N/A
2390	1	3	318	Classroom 318	Yes	W3	CMU	Blue	None	0	N/A	N/A
2390	1	3	318	Classroom 318	Yes	W3	Metal	Blue	Chipping	15	0.2	Negative
2390	1	3	318	Classroom 318	Yes	W4	CMU	Blue	None	0	N/A	N/A
2390	1	3	318	Classroom 318	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	3	318	Classroom 318	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	3	318A	Classroom 318 Storage	Yes	W1	No Access	No Access	No Access	No Access	No Access	No Access
2390	1	3	318A	Classroom 318 Storage	Yes	W2	No Access	No Access	No Access	No Access	No Access	No Access
2390	1	3	318A	Classroom 318 Storage	Yes	W3	No Access	No Access	No Access	No Access	No Access	No Access
2390	1	3	318A	Classroom 318 Storage	Yes	W4	No Access	No Access	No Access	No Access	No Access	No Access
2390	1	3	318A	Classroom 318 Storage	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access

				Inspection Dates: 8/30/21-9/9/21		School District of Philadelphia						
				Name of Inspector: Justine James/ Alyssa Cartagena		Lead Safe Certification Assessment Report						
				Inspection Company: Batta		Morris School						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
2390	1	3	318A	Classroom 318 Storage	Yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access
2390	1	3	317	Classroom 317	Yes	W1	CMU	Blue	None	0	N/A	N/A
2390	1	3	317	Classroom 317	Yes	W2	CMU	Blue	None	0	N/A	N/A
2390	1	3	317	Classroom 317	Yes	W3	CMU	Blue	None	0	N/A	N/A
2390	1	3	317	Classroom 317	Yes	W4	CMU	Blue	None	0	N/A	N/A
2390	1	3	317	Classroom 317	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	3	317	Classroom 317	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	3	315	Classroom 315	Yes	W1	CMU	Blue	None	0	N/A	N/A
2390	1	3	315	Classroom 315	Yes	W1	Wood	Blue	Flaking	12	0.2	Negative
2390	1	3	315	Classroom 315	Yes	W1	Metal	Blue	Flaking	5	0.1	Negative
2390	1	3	315	Classroom 315	Yes	W2	CMU	Blue	None	0	N/A	N/A
2390	1	3	315	Classroom 315	Yes	W3	CMU	Blue	None	0	N/A	N/A
2390	1	3	315	Classroom 315	Yes	W3	Metal	Blue	Chipping	40	0.2	Negative
2390	1	3	315	Classroom 315	Yes	W4	CMU	Blue	None	0	N/A	N/A
2390	1	3	315	Classroom 315	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	3	315	Classroom 315	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	3	S33	Stairwell next to Classroom 315	Yes	W1	CMU	Tan/White	None	0	N/A	N/A
2390	1	3	S33	Stairwell next to Classroom 315	Yes	W2	CMU	Tan/White	None	0	N/A	N/A
2390	1	3	S33	Stairwell next to Classroom 315	Yes	W3	CMU	Tan/White	None	0	N/A	N/A
2390	1	3	S33	Stairwell next to Classroom 315	Yes	W4	CMU	Tan/White	None	0	N/A	N/A
2390	1	3	S33	Stairwell next to Classroom 315	Yes	Ceiling	Plaster	White	None	0	N/A	N/A
2390	1	3	S33	Stairwell next to Classroom 315	Yes	Floor	Concrete	Black	None	0	N/A	N/A
2390	1	3	S33	Stairwell next to Classroom 315	Yes	Floor	Metal	Grey	Friction	40	0.2	Negative
2390	1	3	S33	Stairwell next to Classroom 315	Yes	Floor	Metal	Grey	Friction	5	0.3	Negative
2390	1	3	316	Classroom 316	Yes	W1	CMU	White	None	0	N/A	N/A
2390	1	3	316	Classroom 316	Yes	W2	CMU	Blue	None	0	N/A	N/A
2390	1	3	316	Classroom 316	Yes	W3	CMU	White	None	0	N/A	N/A
2390	1	3	316	Classroom 316	Yes	W4	CMU	White	None	0	N/A	N/A
2390	1	3	316	Classroom 316	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	3	316	Classroom 316	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	3	313	Classroom 313	Yes	W1	CMU	Blue	None	0	N/A	N/A
2390	1	3	313	Classroom 313	Yes	W2	CMU	Blue	None	0	N/A	N/A
2390	1	3	313	Classroom 313	Yes	W3	CMU	Blue	None	0	N/A	N/A
2390	1	3	313	Classroom 313	Yes	W4	CMU	Blue	None	0	N/A	N/A
2390	1	3	313	Classroom 313	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	3	313	Classroom 313	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	3	323	Storage next to Classroom 313	Yes	W1	CMU	Blue	None	0	N/A	N/A
2390	1	3	323	Storage next to Classroom 313	Yes	W2	CMU	Blue	None	0	N/A	N/A
2390	1	3	323	Storage next to Classroom 313	Yes	W3	CMU	Blue	None	0	N/A	N/A
2390	1	3	323	Storage next to Classroom 313	Yes	W4	CMU	Blue	None	0	N/A	N/A
2390	1	3	323	Storage next to Classroom 313	Yes	Ceiling	Plaster	White	None	0	N/A	N/A
2390	1	3	323	Storage next to Classroom 313	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	3	324	Men's Restroom across from Library	Yes	W1	CMU	White/Tan	None	0	N/A	N/A
2390	1	3	324	Men's Restroom across from Library	Yes	W2	CMU	White/Tan	None	0	N/A	N/A
2390	1	3	324	Men's Restroom across from Library	Yes	W3	CMU	White/Tan	None	0	N/A	N/A

				Inspection Dates: 8/30/21-9/9/21		School District of Philadelphia						
				Name of Inspector: Justine James/ Alyssa Cartagena		Lead Safe Certification Assessment Report						
				Inspection Company: Batta		Morris School						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
2390	1	3	324	Men's Restroom across from Library	Yes	W4	CMU	White/Tan	None	0	N/A	N/A
2390	1	3	324	Men's Restroom across from Library	Yes	Ceiling	Plaster	White	None	0	N/A	N/A
2390	1	3	324	Men's Restroom across from Library	Yes	Floor	Concrete	Black	None	0	N/A	N/A
2390	1	3	314	Library (310, 312, & 314)	Yes	W1	CMU	Blue	None	0	N/A	N/A
2390	1	3	314	Library (310, 312, & 314)	Yes	W2	CMU	Blue	None	0	N/A	N/A
2390	1	3	314	Library (310, 312, & 314)	Yes	W3	CMU	Blue	None	0	N/A	N/A
2390	1	3	314	Library (310, 312, & 314)	Yes	W4	Sheetrock	Blue	None	0	N/A	N/A
2390	1	3	314	Library (310, 312, & 314)	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	3	314	Library (310, 312, & 314)	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	3	314A	Library Office	Yes	W1	No Access	No Access	No Access	No Access	No Access	No Access
2390	1	3	314A	Library Office	Yes	W2	No Access	No Access	No Access	No Access	No Access	No Access
2390	1	3	314A	Library Office	Yes	W3	No Access	No Access	No Access	No Access	No Access	No Access
2390	1	3	314A	Library Office	Yes	W4	No Access	No Access	No Access	No Access	No Access	No Access
2390	1	3	314A	Library Office	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
2390	1	3	314A	Library Office	Yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access
2390	1	3	314B	Library Storage	Yes	W1	Sheetrock	Blue	None	0	N/A	N/A
2390	1	3	314B	Library Storage	Yes	W2	Sheetrock	Blue	None	0	N/A	N/A
2390	1	3	314B	Library Storage	Yes	W3	CMU	Blue	None	0	N/A	N/A
2390	1	3	314B	Library Storage	Yes	W4	CMU	Blue	None	0	N/A	N/A
2390	1	3	314B	Library Storage	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	3	314B	Library Storage	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	3	308	Classroom 308	Yes	W1	CMU	Yellow	None	0	N/A	N/A
2390	1	3	308	Classroom 308	Yes	W2	CMU	Yellow	None	0	N/A	N/A
2390	1	3	308	Classroom 308	Yes	W3	CMU	Yellow	None	0	N/A	N/A
2390	1	3	308	Classroom 308	Yes	W4	CMU	Yellow	None	0	N/A	N/A
2390	1	3	308	Classroom 308	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	3	308	Classroom 308	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	3	306	Classroom 306	Yes	W1	CMU	Blue/Black	None	0	N/A	N/A
2390	1	3	306	Classroom 306	Yes	W2	CMU	Blue	None	0	N/A	N/A
2390	1	3	306	Classroom 306	Yes	W3	CMU	Blue	None	0	N/A	N/A
2390	1	3	306	Classroom 306	Yes	W4	CMU	Blue	None	0	N/A	N/A
2390	1	3	306	Classroom 306	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	3	306	Classroom 306	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	3	S31	Stairwell next to Elevator	Yes	W1	CMU	Tan/White	None	0	N/A	N/A
2390	1	3	S31	Stairwell next to Elevator	Yes	W2	CMU	Tan/White	None	0	N/A	N/A
2390	1	3	S31	Stairwell next to Elevator	Yes	W3	CMU	Tan/White	None	0	N/A	N/A
2390	1	3	S31	Stairwell next to Elevator	Yes	W4	CMU	Tan/White	None	0	N/A	N/A
2390	1	3	S31	Stairwell next to Elevator	Yes	Ceiling	Plaster	White	None	0	N/A	N/A
2390	1	3	S31	Stairwell next to Elevator	Yes	Floor	Concrete	Black	None	0	N/A	N/A
2390	1	3	S31	Stairwell next to Elevator	Yes	Floor	Metal	Black	Friction	35	0.2	Negative
2390	1	3	S31	Stairwell next to Elevator	Yes	Floor	Metal	Black	Friction	5	0.2	Negative
2390	1	3	322	Women's Restroom across from Classroom 304	Yes	W1	CMU	Green/White	None	0	N/A	N/A
2390	1	3	322	Women's Restroom across from Classroom 304	Yes	W2	CMU	Green/White	None	0	N/A	N/A
2390	1	3	322	Women's Restroom across from Classroom 304	Yes	W3	CMU	Green/White	None	0	N/A	N/A
2390	1	3	322	Women's Restroom across from Classroom 304	Yes	W4	CMU	Green/White	None	0	N/A	N/A

				Inspection Dates: 8/30/21-9/9/21		School District of Philadelphia						
				Name of Inspector: Justine James/ Alyssa Cartagena		Lead Safe Certification Assessment Report						
				Inspection Company: Batta		Morris School						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
2390	1	3	322	Women's Restroom across from Classroom 304	Yes	Ceiling	Plaster	White	None	0	N/A	N/A
2390	1	3	322	Women's Restroom across from Classroom 304	Yes	Floor	Concrete	Grey	None	0	N/A	N/A
2390	1	3	321	Girl's Restroom across from Classroom 304	Yes	W1	CMU	White/Tan	None	0	N/A	N/A
2390	1	3	321	Girl's Restroom across from Classroom 304	Yes	W2	CMU	White/Tan	None	0	N/A	N/A
2390	1	3	321	Girl's Restroom across from Classroom 304	Yes	W3	CMU	White/Tan	None	0	N/A	N/A
2390	1	3	321	Girl's Restroom across from Classroom 304	Yes	W4	CMU	White/Tan	None	0	N/A	N/A
2390	1	3	321	Girl's Restroom across from Classroom 304	Yes	Ceiling	Plaster	White	None	0	N/A	N/A
2390	1	3	321	Girl's Restroom across from Classroom 304	Yes	Floor	Concrete	Black	None	0	N/A	N/A
2390	1	3	PC321	Pipe Chase in Girl's Restroom across from Classroom 304	No	W1	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	3	PC321	Pipe Chase in Girl's Restroom across from Classroom 304	No	W2	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	3	PC321	Pipe Chase in Girl's Restroom across from Classroom 304	No	W3	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	3	PC321	Pipe Chase in Girl's Restroom across from Classroom 304	No	W4	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	3	PC321	Pipe Chase in Girl's Restroom across from Classroom 304	No	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	3	PC321	Pipe Chase in Girl's Restroom across from Classroom 304	No	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	3	320	Boy's Restroom next to Classroom 303	Yes	W1	CMU	White/Tan	None	0	N/A	N/A
2390	1	3	320	Boy's Restroom next to Classroom 303	Yes	W2	CMU	White/Tan	None	0	N/A	N/A
2390	1	3	320	Boy's Restroom next to Classroom 303	Yes	W3	CMU	White/Tan	None	0	N/A	N/A
2390	1	3	320	Boy's Restroom next to Classroom 303	Yes	W4	CMU	White/Tan	None	0	N/A	N/A
2390	1	3	320	Boy's Restroom next to Classroom 303	Yes	Ceiling	Plaster	White	None	0	N/A	N/A
2390	1	3	320	Boy's Restroom next to Classroom 303	Yes	Floor	Concrete	Black	Flaking	12	0.1	Negative
2390	1	3	PC320	Pipe Chase in Boy's Restroom next to Classroom 303	No	W1	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	3	PC320	Pipe Chase in Boy's Restroom next to Classroom 303	No	W2	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	3	PC320	Pipe Chase in Boy's Restroom next to Classroom 303	No	W3	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	3	PC320	Pipe Chase in Boy's Restroom next to Classroom 303	No	W4	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	3	PC320	Pipe Chase in Boy's Restroom next to Classroom 303	No	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	3	PC320	Pipe Chase in Boy's Restroom next to Classroom 303	No	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	3	304	Classroom 304	Yes	W1	CMU	Blue	None	0	N/A	N/A
2390	1	3	304	Classroom 304	Yes	W1	Metal	Green	Flaking	5	0.1	Negative
2390	1	3	304	Classroom 304	Yes	W2	CMU	Blue	None	0	N/A	N/A
2390	1	3	304	Classroom 304	Yes	W3	CMU	Blue	Flaking	10	0	Negative
2390	1	3	304	Classroom 304	Yes	W3	Metal	Blue	Chipping	40	0.1	Negative
2390	1	3	304	Classroom 304	Yes	W4	CMU	Blue	None	0	N/A	N/A
2390	1	3	304	Classroom 304	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	3	304	Classroom 304	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	3	302	Classroom 302	Yes	W1	CMU	Green	None	0	N/A	N/A
2390	1	3	302	Classroom 302	Yes	W2	CMU	Green	None	0	N/A	N/A
2390	1	3	302	Classroom 302	Yes	W3	CMU	Green	None	0	N/A	N/A
2390	1	3	302	Classroom 302	Yes	W4	CMU	Green	None	0	N/A	N/A
2390	1	3	302	Classroom 302	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	3	302	Classroom 302	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A

				Inspection Dates: 8/30/21-9/9/21		School District of Philadelphia						
				Name of Inspector: Justine James/ Alyssa Cartagena		Lead Safe Certification Assessment Report						
				Inspection Company: Batta		Morris School						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
2390	1	3	303	Classroom 303	Yes	W1	CMU	Blue	Flaking	10	0.1	Negative
2390	1	3	303	Classroom 303	Yes	W1	Metal	Blue	Flaking	5	0.1	Negative
2390	1	3	303	Classroom 303	Yes	W1	Wood	Blue	Flaking	25	1.1	Positive
2390	1	3	303	Classroom 303	Yes	W2	CMU	Blue	None	0	N/A	N/A
2390	1	3	303	Classroom 303	Yes	W3	CMU	Blue	Flaking	25	0	Negative
2390	1	3	303	Classroom 303	Yes	W3	Metal	Blue	Chipping	15	0.2	Negative
2390	1	3	303	Classroom 303	Yes	W4	CMU	Blue	None	0	N/A	N/A
2390	1	3	303	Classroom 303	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	3	303	Classroom 303	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	3	301	Classroom 301	Yes	W1	CMU	Blue	None	0	N/A	N/A
2390	1	3	301	Classroom 301	Yes	W2	CMU	Blue	None	0	N/A	N/A
2390	1	3	301	Classroom 301	Yes	W3	CMU	Blue	None	0	N/A	N/A
2390	1	3	301	Classroom 301	Yes	W4	CMU	Blue	None	0	N/A	N/A
2390	1	3	301	Classroom 301	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	3	301	Classroom 301	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	3	300	Classroom 300	Yes	W1	CMU	Blue	None	0	N/A	N/A
2390	1	3	300	Classroom 300	Yes	W1	Metal	Blue	Flaking	5	0	Negative
2390	1	3	300	Classroom 300	Yes	W1	Wood	Blue	Flaking	12	1	Positive
2390	1	3	300	Classroom 300	Yes	W2	CMU	Blue	Flaking	10	0	Negative
2390	1	3	300	Classroom 300	Yes	W3	CMU	Blue	Flaking	12	0	Negative
2390	1	3	300	Classroom 300	Yes	W3	Metal	Blue	Flaking	10	0.1	Negative
2390	1	3	300	Classroom 300	Yes	W4	CMU	Blue	None	0	N/A	N/A
2390	1	3	300	Classroom 300	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	3	300	Classroom 300	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	3	S32	Stairwell next to Classroom 301	Yes	W1	CMU	Tan/White	None	0	N/A	N/A
2390	1	3	S32	Stairwell next to Classroom 301	Yes	W2	CMU	Tan/White	None	0	N/A	N/A
2390	1	3	S32	Stairwell next to Classroom 301	Yes	W3	CMU	Tan/White	None	0	N/A	N/A
2390	1	3	S32	Stairwell next to Classroom 301	Yes	W4	CMU	Tan/White	None	0	N/A	N/A
2390	1	3	S32	Stairwell next to Classroom 301	Yes	Ceiling	Plaster	White	None	0	N/A	N/A
2390	1	3	S32	Stairwell next to Classroom 301	Yes	Floor	Concrete	Black	Flaking	15	0.1	Negative
2390	1	3	S32	Stairwell next to Classroom 301	Yes	Floor	Metal	Black	Friction	15	0.1	Negative
2390	1	3	H315	Hallway from Library to Classroom 300	Yes	W1	CMU	Tan/White	None	0	N/A	N/A
2390	1	3	H315	Hallway from Library to Classroom 300	Yes	W2	CMU	Tan/White	None	0	N/A	N/A
2390	1	3	H315	Hallway from Library to Classroom 300	Yes	W3	CMU	Tan/White	None	0	N/A	N/A
2390	1	3	H315	Hallway from Library to Classroom 300	Yes	W4	CMU	Tan/White	None	0	N/A	N/A
2390	1	3	H315	Hallway from Library to Classroom 300	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	3	H315	Hallway from Library to Classroom 300	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	3	H313	Hallway from Classroom 308 to 318	Yes	W1	CMU	Tan/White	None	0	N/A	N/A
2390	1	3	H313	Hallway from Classroom 308 to 318	Yes	W2	CMU	Tan/White	None	0	N/A	N/A
2390	1	3	H313	Hallway from Classroom 308 to 318	Yes	W3	CMU	Tan/White	None	0	N/A	N/A
2390	1	3	H313	Hallway from Classroom 308 to 318	Yes	W4	CMU	Tan/White	None	0	N/A	N/A
2390	1	3	H313	Hallway from Classroom 308 to 318	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	3	H313	Hallway from Classroom 308 to 318	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	4	400	Classroom 400	Yes	W1	CMU	Blue	None	0	N/A	N/A
2390	1	4	400	Classroom 400	Yes	W2	CMU	Blue	None	0	N/A	N/A

				Inspection Dates: 8/30/21-9/9/21		School District of Philadelphia						
				Name of Inspector: Justine James/ Alyssa Cartagena		Lead Safe Certification Assessment Report						
				Inspection Company: Batta		Morris School						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
2390	1	4	400	Classroom 400	Yes	W3	CMU	Blue	None	0	N/A	N/A
2390	1	4	400	Classroom 400	Yes	W3	Metal	Blue	Flaking	1	0.2	Negative
2390	1	4	400	Classroom 400	Yes	W4	CMU	Blue	None	0	N/A	N/A
2390	1	4	400	Classroom 400	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	4	400	Classroom 400	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	4	S42	Stairwell next to Classroom 401	Yes	W1	CMU	Tan/White	None	0	N/A	N/A
2390	1	4	S42	Stairwell next to Classroom 401	Yes	W2	CMU	Tan/White	None	0	N/A	N/A
2390	1	4	S42	Stairwell next to Classroom 401	Yes	W3	CMU	Tan/White	None	0	N/A	N/A
2390	1	4	S42	Stairwell next to Classroom 401	Yes	W4	CMU	Tan/White	None	0	N/A	N/A
2390	1	4	S42	Stairwell next to Classroom 401	Yes	Ceiling	Plaster	White	None	0	N/A	N/A
2390	1	4	S42	Stairwell next to Classroom 401	Yes	Floor	Concrete	Black	Flaking	1	0.1	Negative
2390	1	4	401	Classroom 401	Yes	W1	CMU	Green	None	0	N/A	N/A
2390	1	4	401	Classroom 401	Yes	W2	CMU	Green	None	0	N/A	N/A
2390	1	4	401	Classroom 401	Yes	W3	CMU	Green	None	0	N/A	N/A
2390	1	4	401	Classroom 401	Yes	W4	CMU	Green	None	0	N/A	N/A
2390	1	4	401	Classroom 401	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	4	401	Classroom 401	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	4	402	Classroom 402	Yes	W1	CMU	Blue/Yellow	None	0	N/A	N/A
2390	1	4	402	Classroom 402	Yes	W1	Wood	Yellow	Flaking	2	1.1	Positive
2390	1	4	402	Classroom 402	Yes	W1	Metal	Blue	Flaking	5	0.1	Negative
2390	1	4	402	Classroom 402	Yes	W2	CMU	Blue	None	0	N/A	N/A
2390	1	4	402	Classroom 402	Yes	W3	CMU	Blue	None	0	N/A	N/A
2390	1	4	402	Classroom 402	Yes	W4	CMU	Blue	None	0	N/A	N/A
2390	1	4	402	Classroom 402	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	4	402	Classroom 402	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	4	403	Classroom 403	Yes	W1	CMU	Blue	None	0	N/A	N/A
2390	1	4	403	Classroom 403	Yes	W1	Wood	Blue	Flaking	8	1	Positive
2390	1	4	403	Classroom 403	Yes	W2	CMU	Blue	None	0	N/A	N/A
2390	1	4	403	Classroom 403	Yes	W3	CMU	Blue	None	0	N/A	N/A
2390	1	4	403	Classroom 403	Yes	W3	Metal	Blue	Flaking	2	0.1	Negative
2390	1	4	403	Classroom 403	Yes	W4	CMU	Blue	None	0	N/A	N/A
2390	1	4	403	Classroom 403	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	4	403	Classroom 403	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	4	404	Classroom 404	Yes	W1	CMU	Blue	None	0	N/A	N/A
2390	1	4	404	Classroom 404	Yes	W1	Wood	Blue	Flaking	10	0.9	Positive
2390	1	4	404	Classroom 404	Yes	W2	CMU	Blue	None	0	N/A	N/A
2390	1	4	404	Classroom 404	Yes	W3	CMU	Blue	Flaking	15	0.1	Negative
2390	1	4	404	Classroom 404	Yes	W3	Metal	Blue	Chipping	20	0.2	Negative
2390	1	4	404	Classroom 404	Yes	W4	CMU	Blue	None	0	N/A	N/A
2390	1	4	404	Classroom 404	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	4	404	Classroom 404	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	4	420	Boy's Restroom next to Classroom 403	Yes	W1	CMU	Blue/ White	None	0	N/A	N/A
2390	1	4	420	Boy's Restroom next to Classroom 403	Yes	W2	CMU	Blue/ White	None	0	N/A	N/A
2390	1	4	420	Boy's Restroom next to Classroom 403	Yes	W3	CMU	Blue/ White	None	0	N/A	N/A
2390	1	4	420	Boy's Restroom next to Classroom 403	Yes	W4	CMU	Blue/ White	None	0	N/A	N/A

				Inspection Dates: 8/30/21-9/9/21		School District of Philadelphia						
				Name of Inspector: Justine James/ Alyssa Cartagena		Lead Safe Certification Assessment Report						
				Inspection Company: Batta		Morris School						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
2390	1	4	420	Boy's Restroom next to Classroom 403	Yes	Ceiling	Plaster	White	None	0	N/A	N/A
2390	1	4	420	Boy's Restroom next to Classroom 403	Yes	Floor	Concrete	Grey	None	0	N/A	N/A
2390	1	4	PC420	Pipe Chase in Boy's Restroom next to Classroom 403	No	W1	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	4	PC420	Pipe Chase in Boy's Restroom next to Classroom 403	No	W2	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	4	PC420	Pipe Chase in Boy's Restroom next to Classroom 403	No	W3	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	4	PC420	Pipe Chase in Boy's Restroom next to Classroom 403	No	W4	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	4	PC420	Pipe Chase in Boy's Restroom next to Classroom 403	No	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	4	PC420	Pipe Chase in Boy's Restroom next to Classroom 403	No	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	4	421	Girl's Restroom across from Classroom 404	Yes	W1	CMU	White/Tan	None	0	N/A	N/A
2390	1	4	421	Girl's Restroom across from Classroom 404	Yes	W2	CMU	White/Tan	None	0	N/A	N/A
2390	1	4	421	Girl's Restroom across from Classroom 404	Yes	W3	CMU	White/Tan	None	0	N/A	N/A
2390	1	4	421	Girl's Restroom across from Classroom 404	Yes	W4	CMU	White/Tan	None	0	N/A	N/A
2390	1	4	421	Girl's Restroom across from Classroom 404	Yes	Ceiling	Plaster	White	None	0	N/A	N/A
2390	1	4	421	Girl's Restroom across from Classroom 404	Yes	Floor	Concrete	Grey	None	0	N/A	N/A
2390	1	4	PC421	Pipe Chase Girl's/Women's Restroom across from Classroom 404	No	W1	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	4	PC421	Pipe Chase Girl's/Women's Restroom across from Classroom 404	No	W2	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	4	PC421	Pipe Chase Girl's/Women's Restroom across from Classroom 404	No	W3	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	4	PC421	Pipe Chase Girl's/Women's Restroom across from Classroom 404	No	W4	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	4	PC421	Pipe Chase Girl's/Women's Restroom across from Classroom 404	No	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	4	PC421	Pipe Chase Girl's/Women's Restroom across from Classroom 404	No	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	4	422	Women's Restroom across from Classroom 404	Yes	W1	CMU	White	None	0	N/A	N/A
2390	1	4	422	Women's Restroom across from Classroom 404	Yes	W2	CMU	White	None	0	N/A	N/A
2390	1	4	422	Women's Restroom across from Classroom 404	Yes	W3	CMU	White	None	0	N/A	N/A
2390	1	4	422	Women's Restroom across from Classroom 404	Yes	W4	CMU	White	None	0	N/A	N/A
2390	1	4	422	Women's Restroom across from Classroom 404	Yes	Ceiling	Plaster	White	None	0	N/A	N/A
2390	1	4	422	Women's Restroom across from Classroom 404	Yes	Floor	Concrete	Grey	None	0	N/A	N/A
2390	1	4	406	Classroom 406	Yes	W1	CMU	Blue	None	0	N/A	N/A
2390	1	4	406	Classroom 406	Yes	W1	Metal	Blue	Flaking	5	0.2	Negative
2390	1	4	406	Classroom 406	Yes	W2	CMU	Blue	None	0	N/A	N/A
2390	1	4	406	Classroom 406	Yes	W3	CMU	Blue	Flaking	1	0.4	Negative
2390	1	4	406	Classroom 406	Yes	W3	Metal	Blue	Flaking	25	0	Negative
2390	1	4	406	Classroom 406	Yes	W4	CMU	Blue	None	0	N/A	N/A
2390	1	4	406	Classroom 406	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	4	406	Classroom 406	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	4	408	Classroom 408	Yes	W1	CMU	Blue	None	0	N/A	N/A
2390	1	4	408	Classroom 408	Yes	W1	Metal	Blue	Flaking	5	0.1	Negative
2390	1	4	408	Classroom 408	Yes	W1	Wood	Blue	Flaking	10	0.8	Positive
2390	1	4	408	Classroom 408	Yes	W1	Wood	Blue	Flaking	15	0.1	Negative
2390	1	4	408	Classroom 408	Yes	W2	CMU	Blue	None	0	N/A	N/A
2390	1	4	408	Classroom 408	Yes	W3	CMU	Blue	Flaking	10	0.1	Negative

Inspection Dates: 8/30/21-9/9/21					School District of Philadelphia							
Name of Inspector: Justine James/ Alyssa Cartagena					Lead Safe Certification Assessment Report							
Inspection Company: Batta					Morris School							
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
2390	1	4	408	Classroom 408	Yes	W3	Metal	Blue	Flaking	20	0.1	Negative
2390	1	4	408	Classroom 408	Yes	W4	CMU	Blue	None	0	N/A	N/A
2390	1	4	408	Classroom 408	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	4	408	Classroom 408	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	4	410	Cafeteria (410)	Yes	W1	CMU	Yellow	None	0	N/A	N/A
2390	1	4	410	Cafeteria (410)	Yes	W2	CMU	Yellow	None	0	N/A	N/A
2390	1	4	410	Cafeteria (410)	Yes	W3	CMU	Yellow	None	0	N/A	N/A
2390	1	4	410	Cafeteria (410)	Yes	W3	Metal	Black	Flaking	5	0.1	Negative
2390	1	4	410	Cafeteria (410)	Yes	W4	CMU	Yellow	None	0	N/A	N/A
2390	1	4	410	Cafeteria (410)	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	4	410	Cafeteria (410)	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	4	412	Cafeteria (412)	Yes	W1	See above	See above	See above	See above	See above	See above
2390	1	4	412	Cafeteria (412)	Yes	W2	See above	See above	See above	See above	See above	See above
2390	1	4	412	Cafeteria (412)	Yes	W3	See above	See above	See above	See above	See above	See above
2390	1	4	412	Cafeteria (412)	Yes	W4	See above	See above	See above	See above	See above	See above
2390	1	4	412	Cafeteria (412)	Yes	Ceiling	See above	See above	See above	See above	See above	See above
2390	1	4	412	Cafeteria (412)	Yes	Floor	See above	See above	See above	See above	See above	See above
2390	1	4	424	Men's Restroom across from Classroom 410	Yes	W1	CMU	White/Tan	None	0	N/A	N/A
2390	1	4	424	Men's Restroom across from Classroom 410	Yes	W2	CMU	White/Tan	None	0	N/A	N/A
2390	1	4	424	Men's Restroom across from Classroom 410	Yes	W3	CMU	White/Tan	None	0	N/A	N/A
2390	1	4	424	Men's Restroom across from Classroom 410	Yes	W4	CMU	White/Tan	None	0	N/A	N/A
2390	1	4	424	Men's Restroom across from Classroom 410	Yes	Ceiling	Plaster	White	None	0	N/A	N/A
2390	1	4	424	Men's Restroom across from Classroom 410	Yes	Floor	Concrete	Grey	Flaking	50	0	Negative
2390	1	4	423	Storage next to Classroom 413	Yes	W1	CMU	Blue	None	0	N/A	N/A
2390	1	4	423	Storage next to Classroom 413	Yes	W2	CMU	Blue	None	0	N/A	N/A
2390	1	4	423	Storage next to Classroom 413	Yes	W3	CMU	Blue	None	0	N/A	N/A
2390	1	4	423	Storage next to Classroom 413	Yes	W4	CMU	Blue	None	0	N/A	N/A
2390	1	4	423	Storage next to Classroom 413	Yes	Ceiling	Plaster	White	Flaking	40	0	Negative
2390	1	4	423	Storage next to Classroom 413	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	4	413	Classroom 413	Yes	W1	CMU	Green	None	0	N/A	N/A
2390	1	4	413	Classroom 413	Yes	W2	CMU	Green	None	0	N/A	N/A
2390	1	4	413	Classroom 413	Yes	W3	CMU	Green	None	0	N/A	N/A
2390	1	4	413	Classroom 413	Yes	W4	CMU	Green	None	0	N/A	N/A
2390	1	4	413	Classroom 413	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	4	413	Classroom 413	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	4	414	Classroom 414	Yes	W1	CMU	Blue	None	0	N/A	N/A
2390	1	4	414	Classroom 414	Yes	W2	CMU	Blue	None	0	N/A	N/A
2390	1	4	414	Classroom 414	Yes	W3	CMU	Blue	None	0	N/A	N/A
2390	1	4	414	Classroom 414	Yes	W4	CMU	Blue	None	0	N/A	N/A
2390	1	4	414	Classroom 414	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	4	414	Classroom 414	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	4	415	Classroom 415	Yes	W1	CMU	Green	Flaking	7	0	Negative
2390	1	4	415	Classroom 415	Yes	W1	Wood	Green	Flaking	6	1.5	Positive
2390	1	4	415	Classroom 415	Yes	W1	Wood	Green	Flaking	8	0.1	Negative
2390	1	4	415	Classroom 415	Yes	W2	CMU	Green	None	0	N/A	N/A

				Inspection Dates: 8/30/21-9/9/21		School District of Philadelphia						
				Name of Inspector: Justine James/ Alyssa Cartagena		Lead Safe Certification Assessment Report						
				Inspection Company: Batta		Morris School						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
2390	1	4	415	Classroom 415	Yes	W3	CMU	Green	None	0	N/A	N/A
2390	1	4	415	Classroom 415	Yes	W3	Metal	Blue	Chipping	4	0.2	Negative
2390	1	4	415	Classroom 415	Yes	W4	CMU	Green	None	0	N/A	N/A
2390	1	4	415	Classroom 415	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	4	415	Classroom 415	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	4	416	Classroom 416	Yes	W1	CMU	White	Flaking	3	0	Negative
2390	1	4	416	Classroom 416	Yes	W2	CMU	Blue	None	0	N/A	N/A
2390	1	4	416	Classroom 416	Yes	W3	CMU	White	None	0	N/A	N/A
2390	1	4	416	Classroom 416	Yes	W4	CMU	White	None	0	N/A	N/A
2390	1	4	416	Classroom 416	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	4	416	Classroom 416	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	4	S43	Stairwell next to Classroom 415	Yes	W1	CMU	Tan/White	None	0	N/A	N/A
2390	1	4	S43	Stairwell next to Classroom 415	Yes	W2	CMU	Tan/White	None	0	N/A	N/A
2390	1	4	S43	Stairwell next to Classroom 415	Yes	W3	CMU	Tan/White	None	0	N/A	N/A
2390	1	4	S43	Stairwell next to Classroom 415	Yes	W4	CMU	Tan/White	None	0	N/A	N/A
2390	1	4	S43	Stairwell next to Classroom 415	Yes	Floor	Metal	Grey	Friction	20	0.1	Negative
2390	1	4	S43	Stairwell next to Classroom 415	Yes	Floor	Metal	Grey	Friction	6	0.2	Negative
2390	1	4	S43	Stairwell next to Classroom 415	Yes	Ceiling	Plaster	White	None	0	N/A	N/A
2390	1	4	S43	Stairwell next to Classroom 415	Yes	Floor	Concrete	Black	Flaking	3	0.1	Negative
2390	1	4	425	Storage next to Classroom 417	Yes	W1	CMU	Yellow	None	0	N/A	N/A
2390	1	4	425	Storage next to Classroom 417	Yes	W2	CMU	Yellow	None	0	N/A	N/A
2390	1	4	425	Storage next to Classroom 417	Yes	W3	CMU	Yellow	None	0	N/A	N/A
2390	1	4	425	Storage next to Classroom 417	Yes	W4	CMU	Yellow	None	0	N/A	N/A
2390	1	4	425	Storage next to Classroom 417	Yes	Ceiling	Plaster	White	None	0	N/A	N/A
2390	1	4	425	Storage next to Classroom 417	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	4	417	Classroom 417	Yes	W1	CMU	Blue	None	0	N/A	N/A
2390	1	4	417	Classroom 417	Yes	W2	CMU	Blue	None	0	N/A	N/A
2390	1	4	417	Classroom 417	Yes	W3	CMU	Blue	None	0	N/A	N/A
2390	1	4	417	Classroom 417	Yes	W4	CMU	Blue	None	0	N/A	N/A
2390	1	4	417	Classroom 417	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	4	417	Classroom 417	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	4	418	Classroom 418	Yes	W1	CMU	White	None	0	N/A	N/A
2390	1	4	418	Classroom 418	Yes	W2	CMU	Blue	None	0	N/A	N/A
2390	1	4	418	Classroom 418	Yes	W3	CMU	White	Flaking	8	0.1	Negative
2390	1	4	418	Classroom 418	Yes	W4	CMU	White	Flaking	3	0.1	Negative
2390	1	4	418	Classroom 418	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	4	418	Classroom 418	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	4	419	Classroom 419	Yes	W1	No Access	No Access	No Access	No Access	No Access	No Access
2390	1	4	419	Classroom 419	Yes	W2	No Access	No Access	No Access	No Access	No Access	No Access
2390	1	4	419	Classroom 419	Yes	W3	No Access	No Access	No Access	No Access	No Access	No Access
2390	1	4	419	Classroom 419	Yes	W4	No Access	No Access	No Access	No Access	No Access	No Access
2390	1	4	419	Classroom 419	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
2390	1	4	419	Classroom 419	Yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access
2390	1	4	419A	Storage next to Classroom 419	Yes	W1	CMU	Blue	None	0	N/A	N/A
2390	1	4	419A	Storage next to Classroom 419	Yes	W2	CMU	Blue	None	0	N/A	N/A

				Inspection Dates: 8/30/21-9/9/21		School District of Philadelphia						
				Name of Inspector: Justine James/ Alyssa Cartagena		Lead Safe Certification Assessment Report						
				Inspection Company: Batta		Morris School						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
2390	1	4	419A	Storage next to Classroom 419	Yes	W3	CMU	Blue	None	0	N/A	N/A
2390	1	4	419A	Storage next to Classroom 419	Yes	W4	CMU	Blue	None	0	N/A	N/A
2390	1	4	419A	Storage next to Classroom 419	Yes	Ceiling	Plaster	White	None	0	N/A	N/A
2390	1	4	419A	Storage next to Classroom 419	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	4	H418	Hallway from Classroom 408 to 419	Yes	W1	CMU	Tan/White	None	0	N/A	N/A
2390	1	4	H418	Hallway from Classroom 408 to 419	Yes	W2	CMU	Tan/White	None	0	N/A	N/A
2390	1	4	H418	Hallway from Classroom 408 to 419	Yes	W3	CMU	Tan/White	None	0	N/A	N/A
2390	1	4	H418	Hallway from Classroom 408 to 419	Yes	W4	CMU	Tan/White	None	0	N/A	N/A
2390	1	4	H418	Hallway from Classroom 408 to 419	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	4	H418	Hallway from Classroom 408 to 419	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	4	H420	Hallway from Custodial Closet to Classroom 400	Yes	W1	CMU	Tan/White	None	0	N/A	N/A
2390	1	4	H420	Hallway from Custodial Closet to Classroom 400	Yes	W2	CMU	Tan/White	None	0	N/A	N/A
2390	1	4	H420	Hallway from Custodial Closet to Classroom 400	Yes	W3	CMU	Tan/White	None	0	N/A	N/A
2390	1	4	H420	Hallway from Custodial Closet to Classroom 400	Yes	W4	CMU	Blue	None	0	N/A	N/A
2390	1	4	H420	Hallway from Custodial Closet to Classroom 400	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	4	H420	Hallway from Custodial Closet to Classroom 400	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	Roof	RF	Elevator Motor Room	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	Roof	RF	Elevator Motor Room	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	Roof	RF	Elevator Motor Room	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	Roof	RF	Elevator Motor Room	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	Roof	RF	Elevator Motor Room	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	Roof	RF	Elevator Motor Room	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	B	S02	Stairwell by Building Engineer's Office	No	W1	CMU	Blue	None	0	N/A	N/A
2390	1	B	S02	Stairwell by Building Engineer's Office	No	W2	CMU	Blue	None	0	N/A	N/A
2390	1	B	S02	Stairwell by Building Engineer's Office	No	W3	CMU	Blue	None	0	N/A	N/A
2390	1	B	S02	Stairwell by Building Engineer's Office	No	W4	CMU	Blue	None	0	N/A	N/A
2390	1	B	S02	Stairwell by Building Engineer's Office	No	Ceiling	Concrete	White	None	0	N/A	N/A
2390	1	B	S02	Stairwell by Building Engineer's Office	No	Floor	Concrete	Black	None	0	N/A	N/A
2390	1	B	S02	Stairwell by Building Engineer's Office	No	Floor	Metal	Black	Friction	20	0	Negative
2390	1	B	4B	Pump Room behind Building Engineer's Office	No	W1	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	B	4B	Pump Room behind Building Engineer's Office	No	W2	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	B	4B	Pump Room behind Building Engineer's Office	No	W3	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	B	4B	Pump Room behind Building Engineer's Office	No	W4	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	B	4B	Pump Room behind Building Engineer's Office	No	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	B	4B	Pump Room behind Building Engineer's Office	No	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	B	5B	Building Engineer's Office	No	W1	CMU	White	None	0	N/A	N/A
2390	1	B	5B	Building Engineer's Office	No	W2	CMU	White	None	0	N/A	N/A
2390	1	B	5B	Building Engineer's Office	No	W3	CMU	White	None	0	N/A	N/A
2390	1	B	5B	Building Engineer's Office	No	W4	CMU	White	None	0	N/A	N/A
2390	1	B	5B	Building Engineer's Office	No	Ceiling	Sheetrock	White	None	0	N/A	N/A
2390	1	B	5B	Building Engineer's Office	No	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	B	PC5B	Pipe Chase in Building Engineer's Office	No	W1	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	B	PC5B	Pipe Chase in Building Engineer's Office	No	W2	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	B	PC5B	Pipe Chase in Building Engineer's Office	No	W3	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	B	PC5B	Pipe Chase in Building Engineer's Office	No	W4	N/A	N/A	N/A	N/A	N/A	N/A

				Inspection Dates: 8/30/21-9/9/21		School District of Philadelphia						
				Name of Inspector: Justine James/ Alyssa Cartagena		Lead Safe Certification Assessment Report						
				Inspection Company: Batta		Morris School						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
2390	1	B	PC5B	Pipe Chase in Building Engineer's Office	No	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	B	PC5B	Pipe Chase in Building Engineer's Office	No	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	B	5BB	Building Engineer's Office - Restroom	No	W1	CMU	White	None	0	N/A	N/A
2390	1	B	5BB	Building Engineer's Office - Restroom	No	W2	CMU	White	Flaking	20	0.1	Negative
2390	1	B	5BB	Building Engineer's Office - Restroom	No	W3	CMU	White	Flaking	5	0	Negative
2390	1	B	5BB	Building Engineer's Office - Restroom	No	W4	CMU	White	None	0	N/A	N/A
2390	1	B	5BB	Building Engineer's Office - Restroom	No	Ceiling	Sheetrock	White	None	0	N/A	N/A
2390	1	B	5BB	Building Engineer's Office - Restroom	No	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	B	6B	Women's Staff Locker Room	No	W1	CMU	Blue	Flaking	20	0.1	Negative
2390	1	B	6B	Women's Staff Locker Room	No	W2	CMU	Blue	Flaking	20	0.1	Negative
2390	1	B	6B	Women's Staff Locker Room	No	W3	CMU	Blue	Flaking	25	0	Negative
2390	1	B	6B	Women's Staff Locker Room	No	W4	CMU	Blue	Flaking	15	0	Negative
2390	1	B	6B	Women's Staff Locker Room	No	Ceiling	Sheetrock	White	None	0	N/A	N/A
2390	1	B	6B	Women's Staff Locker Room	No	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	B	6BB	Maintenance Women's Locker Room - Restroom	No	W1	CMU	White	Flaking	15	0.2	Negative
2390	1	B	6BB	Maintenance Women's Locker Room - Restroom	No	W2	CMU	White	Flaking	40	0.2	Negative
2390	1	B	6BB	Maintenance Women's Locker Room - Restroom	No	W3	CMU	White	Flaking	30	0.1	Negative
2390	1	B	6BB	Maintenance Women's Locker Room - Restroom	No	W4	CMU	White	Flaking	40	0.3	Negative
2390	1	B	6BB	Maintenance Women's Locker Room - Restroom	No	Ceiling	Sheetrock	White	None	0	N/A	N/A
2390	1	B	6BB	Maintenance Women's Locker Room - Restroom	No	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	B	3B	Storage next to Boiler Room	No	W1	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	B	3B	Storage next to Boiler Room	No	W2	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	B	3B	Storage next to Boiler Room	No	W3	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	B	3B	Storage next to Boiler Room	No	W4	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	B	3B	Storage next to Boiler Room	No	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	B	3B	Storage next to Boiler Room	No	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	B	2B	Boiler Room	No	W1	CMU	White/Tan	None	0	N/A	N/A
2390	1	B	2B	Boiler Room	No	W2	CMU	White/Tan	None	0	N/A	N/A
2390	1	B	2B	Boiler Room	No	W3	CMU	White/Tan	Flaking	15	0.2	Negative
2390	1	B	2B	Boiler Room	No	W4	CMU	White/Tan	Flaking	8	0.1	Negative
2390	1	B	2B	Boiler Room	No	Ceiling	Concrete	White	None	0	N/A	N/A
2390	1	B	2B	Boiler Room	No	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	B	2B	Boiler Room	No	Floor	Metal	Blue	Flaking	20	0	Negative
2390	1	B	1B	Electrical Room	No	W1	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	B	1B	Electrical Room	No	W2	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	B	1B	Electrical Room	No	W3	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	B	1B	Electrical Room	No	W4	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	B	1B	Electrical Room	No	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	B	1B	Electrical Room	No	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	B	S01	Stairwell by Electrical Room	No	W1	CMU	White	None	0	N/A	N/A
2390	1	B	S01	Stairwell by Electrical Room	No	W2	CMU	White	None	0	N/A	N/A
2390	1	B	S01	Stairwell by Electrical Room	No	W3	CMU	White	None	0	N/A	N/A
2390	1	B	S01	Stairwell by Electrical Room	No	W4	CMU	White	None	0	N/A	N/A
2390	1	B	S01	Stairwell by Electrical Room	No	Ceiling	Concrete	White	None	0	N/A	N/A
2390	1	B	S01	Stairwell by Electrical Room	No	Floor	Concrete	Black	None	0	N/A	N/A

				Inspection Dates: 8/30/21-9/9/21		School District of Philadelphia						
				Name of Inspector: Justine James/ Alyssa Cartagena		Lead Safe Certification Assessment Report						
				Inspection Company: Batta		Morris School						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
2390	1	B	H02	Basement Hallway	No	W1	Concrete	White/Gray	Flaking	50	0.6	Negative
2390	1	B	H02	Basement Hallway	No	W2	Concrete	White/Gray	None	0	N/A	N/A
2390	1	B	H02	Basement Hallway	No	W3	Concrete	White/Gray	Flaking	10	0.5	Negative
2390	1	B	H02	Basement Hallway	No	W4	Concrete	White/Gray	None	0	N/A	N/A
2390	1	B	H02	Basement Hallway	No	Ceiling	Concrete	White	None	0	N/A	N/A
2390	1	B	H02	Basement Hallway	No	Floor	Concrete	Gray	None	0	N/A	N/A
2390	1	CS	C	Crawl Space Basement Pump Room	No	W1	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	CS	C	Crawl Space Basement Pump Room	No	W2	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	CS	C	Crawl Space Basement Pump Room	No	W3	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	CS	C	Crawl Space Basement Pump Room	No	W4	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	CS	C	Crawl Space Basement Pump Room	No	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	CS	C	Crawl Space Basement Pump Room	No	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	AT	A	Attic	No	W1	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	AT	A	Attic	No	W2	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	AT	A	Attic	No	W3	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	AT	A	Attic	No	W4	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	AT	A	Attic	No	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2390	1	AT	A	Attic	No	Floor	N/A	N/A	N/A	N/A	N/A	N/A